

371 - Work Order In Progress (Fiscal Year)

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
805	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Ruben Solis		Alma Del Valle Daycare
2285	Work In Progress NEED CARPET REPLACED IN MS. COOKS CLASSROOM. CARPET IS VERY DIRTY WITH PEE, VOMIT, ETC. AS PER E-MAIL ON 5/20/05 FROM AIDA TO MIKE MUNOZ.	5/25/2005 Medium	Aida Salcedo Michael Munoz	Classroom	Anthony ES MS. COOK
882	Work In Progress freezer at 20 degrees Rebecca Saenz - SNP Manager (505) 882-3507	4/6/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Anthony ES
766	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Carlos Lujan		Anthony ES
1862	Work In Progress New unit that was installed in Nurces area is not sufficient. Need to provide more cooling. Please see Mike	5/11/2005 Medium	Jaime Gomez		Anthony ES
1880	Work In Progress As per Ms. Marquez. Would like 1 enter and 1 exit gates. cars are bottling up.	5/12/2005 Medium	Ruben Ronquillo	Parking Lot	Anthony ES
2391	Work In Progress please replace the carpets and cove base in portables 219&220. water line broke and flooded roms.	5/31/2005 Medium	Michael Munoz	Classroom	Anthony ES
2390	Work In Progress room 207 door will not lock need to fix a.s. a. p. for today	5/31/2005 Medium	Hector Villalobos Hector Lozoya	Classroom	Anthony ES
489	Work In Progress replace long gate with half swing and half slide. gate 3 and 1. Had a injury with a custodial	3/17/2005 Medium	Hector Villalobos Michael Munoz		Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
205	Work In Progress Annex Bldg Girls rr - Broken window 45 1/2 x 14 3/4.	3/9/2005 Medium	Hector Villalobos Ruben Ronquillo	Restroom (Girls)	Anthony ES Annex Bldg
331	Work In Progress need 8 sheet metal plates 20x20	3/11/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
226	Work In Progress need to fill in sidewalk with crusher fine	3/10/2005 Medium	Hector Villalobos Lorenzo Hernandez	Athletic Field	Anthony ES
227	Work In Progress need tractor to scrape off weeds	3/10/2005 Medium	Hector Villalobos Lorenzo Hernandez	Athletic Field	Anthony ES
228	Work In Progress pt 217 replace heating and cooling	3/10/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
102	Work In Progress need to remove dirt with tractor by dumpster	3/7/2005 Medium	Hector Villalobos Lorenzo Hernandez	Cafeteria	Anthony ES
103	Work In Progress boiler room we have a leak in pipe line	3/7/2005 Medium	Hector Villalobos Jaime Gomez	Mechanical Room	Anthony ES
1038	Work In Progress replace a/c unit in cafeteria 63 a/c unit	4/11/2005 Medium	Hector Villalobos Jaime Gomez	Cafeteria	Anthony ES
1039	Work In Progress primary office to replace 45 sidedraft master cool	4/11/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
820	Work In Progress Pump house tank has a big leak upper primary	4/4/2005 Medium	Hector Villalobos Ricardo Jacquez	Athletic Field	Anthony ES
823	Work In Progress ALL windows in old primary bldg do not open	4/4/2005 Medium	Hector Villalobos Ruben Ronquillo	Classroom	Anthony ES
764	Work In Progress rooms 3 4 5 6 7 8 emergency windows do not open	4/1/2005 Medium	Hector Villalobos Ruben Ronquillo	Classroom	Anthony ES
623	Work In Progress 3/18/05 1. check boilers 1.5 go to shop put gas pick up supplies 5.5 pruning trees by football field	3/24/2005 Medium	Hector Villalobos Hector Villalobos		Anthony ES
1321	Work In Progress hook up electrical power to storage outside	4/21/2005 Medium	Hector Villalobos Enrique Sotelo	Athletic Field	Anthony ES
1558	Work In Progress upper primary daycare center need to be spray all 3 room for pest control Faxed PO on 5/9/05 45012727	5/2/2005 Medium	Hector Villalobos Margret Villalobos	Classroom	Anthony ES
1976	Work In Progress cover walls , where a/c's were removed	5/17/2005 Medium	Jaime Gomez Danny Miranda	Classroom	Anthony ES 214

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1780	Work In Progress As per Mrs. Marquez please set up banquet tables on May 17, 2005 by 3:30 p.m.	5/10/2005 Medium	karla Quesada Jimmy Carbajal		Anthony ES
911	Work In Progress Lucky,Joe WE need to find out which lockers are to be moved and re-locate to GMS. Rudy will assist.	4/6/2005 4/12/2005 Medium	Michael Munoz Hector Villalobos		Anthony ES
1500	Work In Progress Irrigation Wells - Need Grounds to pick up old well column piping and dispose of it properly.	4/28/2005 Medium	Raul Sanchez Lorenzo Hernandez		Anthony ES
720	Work In Progress PLAYGROUND NEEDS TO BE AERATED	3/31/2005 Medium	Ramiro Holguin Lorenzo Hernandez		Berino ES
846	Work In Progress JAIME GOMEZ NEED TO REPLACE FOUR A/C UNITS WESTWING 131,128 ON EASTWING 103,107 ALL 6500	4/5/2005 Medium	Ramiro Holguin Jaime Gomez		Berino ES
203	Work In Progress NEED PLAYGROUND FERTELIZES	3/9/2005 Medium	Ramiro Holguin Lorenzo Hernandez		Berino ES
1977	Work In Progress 5/17/05 GROUNDS NEED TRACTOR TO REMOVE BROKEN CONCRETE AND CONCRETE SLAP TO RELOCATE SEE-SAW	5/17/2005 Medium	Ramiro Holguin Lorenzo Hernandez		Berino ES
2247	Work In Progress MANNY LOZOYA PORTABLE 140 DOOR NEEDS CLOSURE AND PORTABLE 151 CORE IN HANDLE NEEDS TO BE CHECK OUT KEYS DO NOT WORK	5/24/2005 Medium	Ramiro Holguin Hector Lozoya		Berino ES
441	Work In Progress CHARGER NEEDS TO BE FIXED AGAIN	3/16/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES
1615	Work In Progress As per David V. we need to relocate a portion of the chain link fence at Berino Elem. Due to the fact that it is located right on top of the shut off vavle to the fire hydrant. I believe a work order was submitted for this a long time ago. FAXED PURCHASE ORDER ON 5/26/05	5/3/2005 Medium	David Villalobos Michael Munoz		Berino ES
2222	Work In Progress Room 140 - Need to replace door closer.	5/23/2005 Medium	Hector Lozoya Danny Miranda		Berino ES
1075	Work In Progress 04/12/05 enrique sotelo main bldg. need new timer for the outside lites	4/12/2005 Medium	Juan Vargas Enrique Sotelo		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1422	Work In Progress 04/26/05/jaime gomes library need 3 new master cools	4/26/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
1369	Work In Progress Automobile ran thru about 70ft of fence and 1 gate. Fence is located between DT and CHE Northend of Mc Combs. Case # 2005-03486 Deputy Williams	4/22/2005 Medium	Juan Vargas Michael Munoz		Chaparral ES
1767	Work In Progress 05/10/05 lorenzo hernandez nesesito que enparege con el tractor a round the school	5/10/2005 Medium	Juan Vargas Lorenzo Hernandez		Chaparral ES
1871	Work In Progress 05/11/05/ jaime gomes cafeteria need new air conditioning	5/12/2005 Medium	Juan Vargas Jaime Gomez	Cafeteria	Chaparral ES
2121	Work In Progress Air condition on cosesion stand need new motor 2 peed	5/19/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
2076	Work In Progress 05/08/05 the play ground have scorpions emergency please	5/18/2005 Medium	Juan Vargas Margret Villalobos		Chaparral ES
2314	Work In Progress 05/26/05 lorenzo nesesito ayada para ubicar los sprinklers	5/26/2005 Medium	Juan Vargas Lorenzo Hernandez		Chaparral ES
2316	Work In Progress E-WING - FINISH REPAIRING THE PORCH.	5/26/2005 Medium	Michael Munoz Juan Vargas		Chaparral ES
1080	Work In Progress START ON WOOD FLOORS E-WING	4/12/2005 Medium	Danny Miranda Danny Miranda		Chaparral ES
2311	Work In Progress Room 81 need a price quote for new carpet and cove base.	5/26/2005 Medium	Michael Munoz	Classroom	Chaparral ES
2356	Work In Progress P{lease replace cove base thru out site where needed.	5/27/2005 Medium	Juan Vargas		Chaparral ES
1823	Work In Progress jimmy/carbajal/need/repairs/for/vaccum/roller/bearings/broken/	5/11/2005 Medium	Daniel Ramirez Jimmy Carbajal		Chaparral ES
1854	Work In Progress Joe please order paint from Ruben so when portables arrive you can start painting them. Please call Mike	5/11/2005 Medium	Joe Ramirez	Portables	Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1981	Work In Progress 5/17/05. I NEED FOR ENRIQUE TO REPLACE A BATTERY IN ONE OF THE EMERGENCY LIGHT FIXTURES ,ALSO ONE OF THE LIGHTS IN THE GYM KEEPS COMING ON EVEN AFTER THE LIGHT SWITCH HAS BEEN TURNED OFF. THANK YOU.	5/17/2005 Medium	Joe Ramirez Enrique Sotelo		Chaparral MS
2115	Work In Progress As per Mr.Diggs we are requesting the back-hoe to clean up around the pond so that new liner can be put in THANK YOU.	5/19/2005 Medium	Joe Ramirez Lorenzo Hernandez		Chaparral MS
2009	Work In Progress NEED THE KEY TO MY OFFICE TO BE CHANGED. SOMEONE HAS A COPY AND IS GOING INTO MY OFFICE AFTER I LEAVE FOR THE DAY. THANK YOU ROBERT	5/17/2005 Medium	Robert Gonzalez Hector Lozoya		Chaparral MS
1316	Work In Progress ONE OF OUR SHOWER SCRUBBERS HAD A HARD TIME WORKING LAST SUMMER WHEN WE WERE USING A GRIT SCREENS IN THE GYM. MAY BE THE BRUSHES	4/21/2005 Medium	Robert Gonzalez Jimmy Carbajal		Chaparral MS
1708	Work In Progress NEED TO CHANGE STORAGE ROOM LOCK TO OPEN WITH KEY A-82 ONLY. ALSO DOOR MUST REMAIN LOCKED AT ALL TIMES.	5/6/2005 Medium	Vickie Reed Hector Lozoya	Hallway/Corridor	Chaparral MS 100 STORAGE
724	Work In Progress REPAIR BROKEN 3" WATER LINE ON WEST SIDE OF SCHOOL.	3/31/2005 Medium	Vickie Reed Lorenzo Hernandez		Chaparral MS west side of school
1020	Work In Progress WEST DOOR TO FOOTBALL LOCKER ROOM NEED TO BE REPAIRED.	4/11/2005 Medium	Vickie Reed Danny Miranda		Chaparral MS FOOTBALL LOCKER ROOM
1108	Work In Progress need to replace the pump for a toilet (front office)	4/13/2005 Medium	David Acosta David Villalobos	Office	Desert Pride
210	Work In Progress need golfer traps	3/9/2005 Medium	David Acosta Ruben Ronquillo		Desert Pride
1410	Work In Progress need seven locks for doors to front offices. (in counslor, social workers area.)	4/25/2005 Medium	David Acosta Hector Lozoya	Office	Desert Pride
1612	Work In Progress restroom in lounge area- when flushed, water is pushes back up and smell like sewer	5/3/2005 Medium	David Acosta David Villalobos	Office	Desert Pride
1751	Work In Progress need new flapper for toilet	5/9/2005 Medium	David Acosta David Villalobos	Classroom	Desert Pride #8

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1834	Work In Progress need two plastic name plates for front office doors-(ALL VISITORS MUST SIGN IN AT FRONT OFFICE)	5/11/2005 Medium	David Acosta Hector Lozoya	Office	Desert Pride
1380	Work In Progress need to paint new frame @ varnish door to lounge	4/25/2005 Medium	Danny Miranda David Acosta		Desert Pride
2322	Work In Progress PLEASE SEND EXTERMINATOR OR MOUSE TRAPS TO RM.#116(MRS. DOMINGUEZ) MOUSE INSIDE CLASSROOM.	5/26/2005 Medium	Johnny Acuna Johnny Acuna		Desert Trail Intermediate
2402	Work In Progress NEED TO REPAIR SEVERAL FENCE SITUATIONS: *REPLACE BENT POST AND REPAIR FENCE TO CAGE BEHIND PLAYGROUND BACKSTOP, *WEST FENCE IS MISSING A CENTER RE-ENFORCEMENT POLE NEXT TO GATE, *NEED TO REPLACE GUIDING WHEEL TO SOUTH GATE IN BUS TURN AROUND, *SOUTHEAST FENCE NEEDS REPAIR IN TWO PLACES.	6/1/2005 Medium	Johnny Acuna Michael Munoz		Desert Trail Intermediate
2403	Work In Progress NEED A LOCK FOR SOUTHWEST GATE NEXT TO LISA ST.	6/1/2005 Medium	Johnny Acuna Hector Lozoya		Desert Trail Intermediate
2376	Work In Progress NEED TO REPLACE DOOR FRAME TO PORTABLE #411. (MAIN DOOR).	5/31/2005 Medium	Johnny Acuna Danny Miranda		Desert Trail Intermediate
2210	Work In Progress NEED A NEW SINK CABINET FOR PORTABLE #413 GIRL'S RESTROOM. SIZE: 36" WIDE (FRONT) X 23" LONG X 2' 6" TALL	5/23/2005 Medium	Johnny Acuna Danny Miranda		Desert Trail Intermediate
2211	Work In Progress NEED A NEW REPLACEMENT HOLLOW DOOR FOR CLASSROOM # 411 GIRL'S RESTROOM. DOOR SIZE: 32 1/2" WIDE X 80" LONG. ALSO NEED (2) DOOR KNOBS. ONE (ROUND) FOR HALLWAY DOOR, AND ONE (LEVER) FOR BOY'S RESTROOM DOOR. THANK YOU !!!!!	5/23/2005 Medium	Johnny Acuna Danny Miranda		Desert Trail Intermediate
2212	Work In Progress (STUDENT RECORDS) NEED TO REPAIR BROKEN FILE CABINET LOCK, ALSO NEED A KEY TO BE ABLE TO LOCK CABINETS. BOTH STUDENT RECORD CABINETS ARE THE SAME KEY. (LOCATED INSIDE THE VAULT IN THE MAIN OFFICE)	5/23/2005 Medium	Johnny Acuna Hector Lozoya		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2214	Work In Progress NEED (4) STICKERS FOR MAIN ENTRANCE DOORS TO MAIN BUILDING. ACCORDING TO THE LAW: FOR THE SAFETY OF ALL STUDENTS, ALL VISITORS REPORT TO THE OFFICE. LA LEY REQUIERE PARA LA SEGURIDAD DE TODOS LOS ALUMNOS TODOS VISITANTES DEBEN REPORTARSE A LA OFICINA.	5/23/2005 Medium	Johnny Acuna Ruben Ronquillo		Desert Trail Intermediate
2238	Work In Progress PLEASE SEND PEST CONTROL OR MOUSE TRAPS FOR ROOM #119 INSIDE THE MAIN BUILDING. (MOUSE INSIDE CLASSROOM)	5/24/2005 Medium	Johnny Acuna Johnny Acuna		Desert Trail Intermediate
2289	Work In Progress NEED A SCREW EXTRACTOR FOR CLASSROOM #112 SINK HANDLE. (VALVE)	5/25/2005 Medium	Johnny Acuna Fred Appelzoller		Desert Trail Intermediate
2290	Work In Progress NEED NEW LOCKS AND KEYS FOR CABINET/CLOSET AND THE TEACHER'S DESK. MAIN BLDG. RM. #115.	5/25/2005 Medium	Johnny Acuna Hector Lozoya		Desert Trail Intermediate
2298	Work In Progress 5/25/05 .5-CHECK LIFT STATION .5-REPLACE MISSING INTERCOM BUTTONS TO CLASSROOMS. 2.0-FIX LIGHT FIXTURES TO CLASSROOM RESTROOMS. .5-REPLACE PENCIL SHARPENERS TO ROOMS. #102 AND 406. 1.5-TROUBLESHOOT AND FIX A/C TO ROOM #209. 3.0-CUT WEEDS. 5/25 - 8	5/25/2005 Medium	Johnny Acuna Johnny Acuna		Desert Trail Intermediate
1192	Work In Progress RM. #112 GUTIERREZ . NEED TO FIX AND MAKE A KEY FOR FILING CABINET INSIDE CLASSROOM..THANK YOU.....	4/15/2005 Medium	Johnny Acuna Hector Lozoya		Desert Trail Intermediate
1211	Work In Progress need irrigation backflow preventer to be installed for irrigation to front trees. (irrigation line has been installed).	4/18/2005 Medium	Johnny Acuna Lorenzo Hernandez		Desert Trail Intermediate
1041	Work In Progress NEED A HALL AND CLOSET NON-LOCKING DOOR SET FOR PORTABLE #412 INSIDE DOOR.	4/11/2005 Medium	Johnny Acuna Hector Lozoya		Desert Trail Intermediate
360	Work In Progress PLEASE REPAIR PARKING LOT SECURITY LIGHT FIXTURE LOCATED IN THE PARKING LOT ENTRANCE/EXIT GATE.	3/14/2005 Medium	Johnny Acuna Enrique Sotelo		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1556	Work In Progress PORTABLE #411: NEED A NEW DOORKNOB (LEVER TYPE) FOR BOYS RR, AND ALSO NEED TO RE-WELD DOOR HINGE TO MAIN CLASSROOM DOOR. FALLEN DOOR HARD TO CLOSE.	5/2/2005 Medium	Johnny Acuna Hector Lozoya		Desert Trail Intermediate
2117	Work In Progress ICE MACHINE NOT WORKING. NEED TO REPLACE HOT GAS VALVE. ICE MACHINE MAKES ICE, BUT STAYS IN THE HARVEST MODE, THEN TRIPS THE HIGH PRESSURE SWITCH. (ICE-O-MATIC : MODEL #EC200FAPB1) HOT GAS VALVE: M.O.P.D. (300), COIL:(R235), BODY: (B), TYPE: (RS314)	5/19/2005 Medium	Johnny Acuna Danny Orozco		Desert Trail Intermediate
1807	Work In Progress NEED SCRAPER TO CLEAN OUTSIDE AND INSIDE OF FENCE LINES. THANK YOU !!!!	5/10/2005 Medium	Johnny Acuna Lorenzo Hernandez		Desert Trail Intermediate
2061	Work In Progress NEED TO REPLACE CONDENSATION PUMP TO THE REFRIGERATION UNIT LOCATED INSIDE THE SERVER ROOM.	5/18/2005 Medium	Johnny Acuna Jaime Gomez		Desert Trail Intermediate
704	Work In Progress GLASS TO SERVING LINE IS CRACKED. PATRICIA CISNEROS 824-3822	3/30/2005 Medium	Jacqueline Aguilar Danny Orozco		Desert Trail Intermediate
1592	Work In Progress PUMP ROOM - REPAIR LEAKING FILTERS.	5/3/2005 Medium	Ricardo Jacquez Ricardo Jacquez		Desert Trail Intermediate
1968	Work In Progress pat aguilar - asper principal to replace ac in port #2 room 3&4 with refrigrated air conditioning	5/16/2005 Medium	Patricio Aguilar Jose Ambriz		Desert View ES
1969	Work In Progress pat aguilar move sand away from rock wall move sand back up hill	5/16/2005 Medium	Patricio Aguilar Lorenzo Hernandez		Desert View ES
1860	Work In Progress pat aguilar grounds need grass seed & fertilizer need 10 trees	5/11/2005 Medium	Patricio Aguilar Lorenzo Hernandez		Desert View ES
1851	Work In Progress pat aguilar elect lower class rest room need emergency light replaced	5/11/2005 Medium	Patricio Aguilar Carlos Castillo		Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1855	Work In Progress pat aguilar elect kitchen hall need a trasformer for lights	5/11/2005 Medium	Patricio Aguilar Carlos Castillo		Desert View ES
2287	Work In Progress NEED TO HAVE MAINTENANCE DONE ON AN EXTRACTOR PLEASE ITS BEEN OUT OF SERVICE FOR A LONG TIME. THANK YOU.	5/25/2005 Medium	Jimmy Carbajal Jimmy Carbajal	Classroom	Desert View ES
2288	Work In Progress COULD YOU PLEASE REPAIR THE UPPER HANDLE ASSY. ON A VACUUM PLEASE ASAP. THANK YOU.	5/25/2005 Medium	Jimmy Carbajal Jimmy Carbajal	Classroom	Desert View ES
740	Work In Progress MIKE, THE SCHOOL SIGN THAT MRS. YTURREALDE REQUESTED IT'S ALREADY AT THE WAREHOUSE. LARRY TOLD ME TO LET YOU KNOW SO YOU CAN PICK IT UP AND INSTALL IT. THANK YOU VERY MUCH FOR YOUR HELP! THANK YOU, MARGARET :)	3/31/2005 Medium	Margarita Terrazas Michael Munoz		Desert View ES
1746	Work In Progress AS PER CORA, SHE NEEDS A MASTER KEY FOR THE CONTRACTORS TO WORK AT DV. (DV- MASTER KEY)	5/9/2005 Medium	Mary Garcia Hector Lozoya	Office	Desert View ES DV SCHOOL
2359	Work In Progress Need water solution tank for floor machine, Note:request is for machine at Desert View Elementary.	5/27/2005 Medium	Miguel Aguilar Jimmy Carbajal		Desert View ES
1183	Work In Progress NEED TO REPLACE HOSE SPIGOTS IN PATIOS. LOOSING WATER PRESSURE AND HANDLES ARE BROKEN. NO HEAD CUSTODIAN AT SCHOOL SITE. IF YOU NEED ANY INFORMATION, CONTACT JIMMY CARBAJAL @ THE CUSTODIAL WAREHOUSE	4/15/2005 Medium	Aida Salcedo David Villalobos		Desert View ES
2109	Work In Progress drains are clogged up again, (dishwasher area and serving line area) martha flores - snp manager 505-589-2425	5/19/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Desert View ES
1533	Work In Progress Please use auger and assist with installation of marquee.	4/29/2005 Medium	Lorenzo Hernandez		Desert View ES
1276	Work In Progress please install fabricated iron supports for new marquee. Please see mike before installation.	4/20/2005 Medium	Lorenzo Hernandez		Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1858	Work In Progress New Marquee is going to be installed at site. Will need to run power to it. Please Make arrangements to install next week when Marquee is istalled. Thanks	5/11/2005 Medium	Carlos Castillo		Desert View ES
1944	Work In Progress pLEASE SUPPORT WITH THE INSTALLATION OF THE MARQUEE	5/16/2005 Medium	Lorenzo Hernandez	Parking Lot	Desert View ES
2083	Work In Progress C-WING, PLEASE HAVE DIMAR GIVE US A PRICE QUOTE FOR LOWERING OF SPRIKLERS IN DEMO AREA. PLEASE SEE MIKE	5/18/2005 Medium	Danny Orozco		GAC
1674	Work In Progress NEED 2FT.BY2FT. CONCRETE BASE TO INTALL LIGHT FIXTURES ON BOTH SIDES OF ENTRANCE SIGN TO THE GAC.	5/5/2005 Medium	Carlos Castillo Michael Munoz		GAC
850	Work In Progress As per Manny Prospero: Needs weeds to be cut if can have ground come out to help.	4/5/2005 Medium	Mary Garcia Lorenzo Hernandez		GAC
929	Work In Progress As per Rafa-mop holder needs to be replaced with a new mop holder. Old one does not hold items in place.	4/7/2005 Medium	Mary Garcia Jimmy Carbajal	Custodial	GAC
1021	Work In Progress As per Jose Ambriz, needs Cali to come in and check power in the A-Wing Offices and Conference Room #1, across from Computer Lab in order for him to install cooling & heating unit. Please refer back to work order # 1368.	4/11/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC
144	Work In Progress IN A-WING SPECIAL ED, ACROSS COMPUTER LAB; ROOMS HAVE NO COOLING AND HEATING. NEED TO TALK W/SYLVIA MORENO.	3/8/2005 Medium	Mary Garcia Jose Ambriz	Office	GAC
2265	Work In Progress Repair the sprinkler system at the GAC in the front.	5/25/2005 Medium	Michael Munoz Lorenzo Hernandez		GAC
1980	Work In Progress AS PER MANY LOZOYA WE NEED 4 KEY FOR RESETE FIRE ALARM.	5/17/2005 Medium	Manuel Prospero Hector Lozoya		GAC
2163	Work In Progress 5/20/05 WE NEED TO CHANGED LOCKS AT NEW HANDICAP RESTROOMS. TO PRIMUS LOCKS. THIS IN FOR MANNY LOZOYA	5/20/2005 Medium	Manuel Prospero Hector Lozoya		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
898	Work In Progress BUS BLDG 611- REMOVE AND INSTALL COVEBASE. (Please call Mike before you start on this work order) - Thanks mkv	4/6/2005 Medium	Michael Munoz Mario Apodaca	Classroom	Gadsden HS
2385	Work In Progress SWIMMING POOL (PUMP ROOM) - AS PER NM ENVIRONMENT DEPT. POOL REGULATIONS, PUBLIC POOLS AND GENERAL USE POOLS WILL HAVE AN EMERGENCY SHUT OF SWITCH INSTALLED TO TURN OFF RECIRCULATING PUMP IN CASE OF AN EMERGENCY.	5/31/2005 Medium	Raul Sanchez Michael Mc Dermott		Gadsden HS
1499	Work In Progress Irrigation Wells - Need Grounds to pick up old well column piping and dispose of it properly.	4/28/2005 Medium	Raul Sanchez Lorenzo Hernandez		Gadsden HS
332	Work In Progress DOOR AT ACADEMIC BLDG NEED TO BE FIX HINGES ARE LOSS FRAM BY ROOM 344	3/11/2005 Medium	Mario Apodaca Danny Miranda	Office	Gadsden HS
333	Work In Progress NEED NEW DOOR AT MAIN BLDG GOING OUT TO COMPUTER LAB WEST WING	3/11/2005 Medium	Mario Apodaca Danny Miranda	Hallway/Corridor	Gadsden HS
1204	Work In Progress NEED A OIL PRESSUREFOR AIR COMPRESSOR AT AG SHOP	4/15/2005 Medium	Mario Apodaca Jose Ambriz		Gadsden HS
652	Work In Progress NEED TO ORDER THE WET SIED FOR E/COOLER AT ACADEMIC BLDG W/NEW COOLING MEDIA	3/29/2005 Medium	Mario Apodaca Jose Ambriz		Gadsden HS
653	Work In Progress NEED TO REMOVE AND REINSTALL SAFETY SWITCH BOXES FOR E/COOLER AT WEIGHT ROOM AND ACADEMIC BLDG SO WE CAN PUT NEW WET SIDE	3/29/2005 Medium	Mario Apodaca Carlos Castillo		Gadsden HS
654	Work In Progress NEED A NEW SWITCH W/PILOT LIGHT FOR WALK IN COOLER ASAP COMPLETED BY DANNY OROZCO AS PER MARIO.	3/29/2005 5/19/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
2279	Work In Progress NEED SCISSOR LIFT FOR V-GYM BY 5-31-05	5/25/2005 Medium	Mario Apodaca Ruben Ronquillo	Gym	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1393	Work In Progress BASEBALL & SOFTBALL DUGOUT AREA - NEED (3) HOLLOW METAL DOORS WITH HOLLOW METAL FRAMES (3'0" X 6'8") FOR STORAGE ROOMS.	4/25/2005 Medium	Lorenzo Hernandez Danny Miranda	Athletic Field	Gadsden HS
1394	Work In Progress GROUNDS SHOP - NEED TO RESTOCK FIRST AID KIT.	4/25/2005 Medium	Lorenzo Hernandez Ruben Ronquillo		Gadsden HS
1655	Work In Progress NEED TO COVER ALL WALL AT CONCCSSION STAND W/WHITE WALL LINER PANEL AND END CAPS NEED 20 # MORE SHEETS	5/4/2005 Medium	Mario Apodaca Danny Miranda		Gadsden HS
1501	Work In Progress NEED 2 # NEW SINKS AND FAUCETS FOR THE CONCESSION STAND	4/28/2005 Medium	Mario Apodaca David Villalobos		Gadsden HS
2089	Work In Progress NEED NEW BEARINGS FOR E/COOLER AT ACADEMIC BLDG	5/18/2005 Medium	Mario Apodaca Jose Ambriz		Gadsden HS
2068	Work In Progress NEED TO CALL ELECTRIC CO. TO SERVICE OUTSID LAMPS	5/18/2005 Medium	Mario Apodaca Michael Munoz		Gadsden HS
261	Work In Progress NEED NEW WOOD DOOR AT OLD ENG BLDG ROOM #140,141,135,134,132,128,129,153,150,148.	3/10/2005 Medium	Mario Apodaca Danny Miranda	Classroom	Gadsden HS
263	Work In Progress NEED NEW WOOD DOOR AT N-BLDG AT ROOM # 224,230,211,232,233	3/10/2005 Medium	Mario Apodaca Danny Miranda		Gadsden HS
264	Work In Progress NEED A METAL DOOR FOR BOY RESTROOM AT N-BLDG - ONE DOOR	3/10/2005 Medium	Mario Apodaca Danny Miranda	Restroom (Boys)	Gadsden HS
133	Work In Progress NEED NEW STAIR VINYL STRIP FOR MAIN GOING UP TO OLD/ENG	3/7/2005 Medium	Mario Apodaca Michael Munoz	Stairway	Gadsden HS
134	Work In Progress NEED TO REWELD TRAY RAILING AT LINE #2	3/7/2005 Medium	Mario Apodaca Danny Orozco	Cafeteria	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2386	Work In Progress Nss Roto GISD tag 000395 has a short in cord.	5/31/2005 Medium	Jesus Estrada Jimmy Carbajal	Athletic Field	Gadsden HS
1354	Work In Progress need casters on tables fixed. I counted 14 that need replacement.	4/22/2005 Medium	Jesus Estrada Guillermo Hernandez	Cafeteria	Gadsden HS
1552	Work In Progress Emergency Call-no power to treatment plant.Hi voltage circuit breaker is tripping.	5/2/2005 5/3/2005 Medium	Carlos Castillo Carlos Castillo		Gadsden HS
1307	Work In Progress Replace damaged steamer contactor	4/21/2005 Medium	Carlos Castillo Carlos Castillo	Electrical Room	Gadsden HS
1232	Work In Progress PLease demo and cancell all plumbing as per Mr.Foster.	4/19/2005 Medium	David Villalobos		Gadsden HS
182	Work In Progress North Bldg Room 328 Pam Holguin - need to check outlet that comes from west wall where there is no electricity.	3/8/2005 Medium	Carlos Castillo	Classroom	Gadsden HS 328
190	Work In Progress Main Bldg Room 109 - Dead air not working.	3/8/2005 Medium	Jose Ambriz	Classroom	Gadsden HS 109
1581	Work In Progress curtains that where purchased thru the site need to have altering done to them by Rodriquez upholster.	5/2/2005 Medium	Michael Munoz		Gadsden HS
2315	Work In Progress Please paint inside and out of both guard shacks and repair what is damaged before school starts this year.	5/26/2005 Medium	Mario Apodaca		Gadsden HS
107	Work In Progress need to varnish 4 new doors in rooms #109,134,147,1542	3/7/2005 Medium	Danny Miranda Fernando Moncayo		Gadsden HS
1686	Work In Progress Need to replace contactor after the power outage on 4/29/05.	5/5/2005 Medium	Carlos Castillo Carlos Castillo		Gadsden HS
1329	Work In Progress Need assistance with electrical problems;There is no power on a/cs.After ckd them out I think the 3ph conntactor is bad thank you	4/21/2005 Medium	Fernando Moncayo Carlos Castillo	Custodial	Gadsden HS
1850	Work In Progress Attention; MR AMBRIZ, need to order a new mtr starter coil for AG SHOP air compressor.Also need an air gauge and a oil gauge for same machine. Coil is FURNAS brand, air gauge is 1/4npt 0-150psi, oil gauge is 1/8npt 0-15psi thank you!	5/11/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1973	Work In Progress Need to rerun conduit and wires to kitchen exhaust in PANTHER HUT HOMEC ROOM	5/16/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
1856	Work In Progress Attention, MR AMBRIZ;Need a new a/c for the GROUND SHOP	5/11/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
147	Work In Progress Rm 112-varnish new door waiting on materials	3/8/2005 Medium	Fernando Moncayo Fernando Moncayo		Gadsden HS
895	Work In Progress Need to order new fire extinguishers;10;10lb-5;5lb also need fire extinguisher locator stiker to identify extinguisher location asap please 100 stikers	4/6/2005 Medium	Fernando Moncayo Ruben Ronquillo		Gadsden HS
1094	Work In Progress Need an exhaust fan motor, for DAY CARE restroom no info in old motor, will match it with BROAN motor	4/13/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
1097	Work In Progress Need to connect electrical power to new exhaust fan in COUNCELING CTR	4/13/2005 Medium	Fernando Moncayo Carlos Castillo		Gadsden HS
1153	Work In Progress All restrooms and plumbing chases need to be sprayed to control roaches, thankyou! Faxed PO on 5/3/05 45012450	4/14/2005 Medium	Fernando Moncayo Margret Villalobos	Restroom (Boys)	Gadsden HS
2225	Work In Progress Need to order vinyl panels ,adhesive and trim for restrooms As per Mike - Route back to Fernando and have him order material thru Ruben.	5/23/2005 Medium	Fernando Moncayo Fernando Moncayo		Gadsden HS
1019	Work In Progress Requested by Ms. Moreno Rm. 126 Main Building- Put blinds on the windows.	4/11/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
1159	Work In Progress Requested by Ms. M. Garcia Rm 752 Barracks- Blinds needed on one window (45 x 60). Fire hazard, covered with paper. Special Ed. classroom	4/14/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
1179	Work In Progress Requested by Velia Rm 113 & 114 Main Building (Front Office)-We need the windows replaced in the men and women bathrooms, we're unable to open or close windows properly.	4/15/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS PATIO

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
963	Work In Progress Requested by Jesus Estrada Varsity Gym-Girls locker room, sink has been pulled off the wall.	4/8/2005 Medium	Velia Alarcon David Villalobos	Restroom (Girls)	Gadsden HS
893	Work In Progress Requested by Mr. Contaldo Rm 103-Paint outside of observatory using white oil-based paint.	4/6/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS
689	Work In Progress Classrooms above Varsity Gym-Due to the power outage a few weeks ago, several outlet have no electricity.	3/30/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
725	Work In Progress Requested by Mr. S. Alvarado, Rm 141 Old English building-Door is about ready to fall off it's hinges.	3/31/2005 Medium	Velia Alarcon Danny Miranda	Classroom	Gadsden HS
727	Work In Progress Requested by Mr. Haack, Rm 127 Main Building-Window was broken on 3/30/05.	3/31/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
450	Work In Progress Requested by Mr. D. Martinez main hallway in North Building-Move the snack machines from the main hallway to the shaded area outside, once the electrical outlets have been placed.	3/16/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
445	Work In Progress Rm 158 Concession Stand-need to connect power to new exhaust fan.	3/16/2005 Medium	Velia Alarcon Carlos Castillo		Gadsden HS
447	Work In Progress Requested by Mr. D. Martinez Rm 227C North Building-Replace windows in the Assistant Principal's Office. The windows that are there currently are painted shut.	3/16/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
448	Work In Progress Requested by Mr. D. Martinez Outside of North Building-Have electrical outlets placed outside the North Building in the shaded area for the candy/snack machines.	3/16/2005 Medium	Velia Alarcon Carlos Castillo		Gadsden HS
337	Work In Progress Coke machines by Academic Building, Cafeteria, and Auto Shop no power to Coke machines. Mario checked out the problem, they seem to be working correctly now.	3/11/2005 Medium	Velia Alarcon Carlos Castillo		Gadsden HS
345	Work In Progress The gate on the south side of the school was hit over the weekend. We're unable to close gate, we need this repaired as soon as possible.	3/14/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
315	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop- Install exhaust system (hook up pipe, tubes, etc.) for Jointer/Planer	3/11/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
316	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop- 1. Install heavier electric circuit for operation of drum sander. 2. Re-route machine wiring (belt/disc., sander, etc.) through safety kill switch.	3/11/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
317	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop- Install mirror on office wall, next to bathroom door and wash/clean-up station (between 554e and 554d)	3/11/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
321	Work In Progress Requested by Mr. J. Gonzales Rm 300 Academic Building-No power on south wall of classroom.	3/11/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
185	Work In Progress Requested by Mr. Martin, Rm 551 Wood Shop- Broken Window	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
178	Work In Progress Requested by Ms. M. Gonzalez, Rm 140 Old English Building-The window on the far left side will not stay open. We have to hold it up with a book. Mario looked at it and he states that the Window Company needs to come in and fix all windows in building	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
179	Work In Progress Requested by Ms. M. Gonzalez, Rm 140 Old English Building-Third Request-The blinds in my room are broken and do not work properly. This will help keep the sun out in the afternoon when the roon gets "very hot". Mario took a look at them, class will need 4 set of blinds measurements 44 X 90	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
2036	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- The light directly above the shop sink is burned out.	5/17/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
1638	Work In Progress Requested by Ms. Jordan Rm. 320 Academic Building-Lights blown out.	5/4/2005 Medium	Velia Alarcon Fernando Moncayo	Classroom	Gadsden HS
1640	Work In Progress Requested by Mr. Whitener Rm. 563 Ag. Shop- Needed: one 25 foot extension cord made for the arc welding machines. Also, repair the female ends on 3 existing extension cords.	5/4/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1641	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- The oil pressure gauge on the air compressor is broken and drips crankcase oil onto the floor. It also has an air leak on the small copper tubing on the compressor which causes it to turn on frequently.	5/4/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS
1642	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- The door lock on the south shop door (emergency exit) is very difficult to lock and unlock.	5/4/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
1527	Work In Progress Requested by Mr. A. Perez Rm. 550 Wood Shop Building-Paint entry door; in order to avoid tagging. Adjust gap between door.	4/29/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS
1569	Work In Progress Requested by Fernando Moncayo Varsity Gym- Broken glass in basketball locker room.	5/2/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
1489	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace broken ceiling tile and install plank roof over office and storeroom.	4/28/2005 Medium	Velia Alarcon Joe Ontiveros	Classroom	Gadsden HS
1490	Work In Progress Requested by Mr. Villa Rm. 510 Annex Building (Band Room)-Need replacement bulbs in main band room and office.	4/28/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
1680	Work In Progress Requested by Mr. Chambers Rm. 317 Academic Building-Install a combination lock in the mail room in the Academic Building.	5/5/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
1804	Work In Progress Requested by Mr. Wallis Rm. 609 Volleyball Courts-Spread new sand donated by Maintainance, on to the sandy volleyball court next to the Soccer Fields. Attn: Speedy	5/10/2005 Medium	Velia Alarcon Lorenzo Hernandez		Gadsden HS
2360	Work In Progress Requested by Velia Old English Building-Four classroom are getting new doors and need to be re-keyed.	5/27/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
2221	Work In Progress Weeds are growing out on the new tennis courts. Please cut and apply a none coloring chemical to prevent weeds from coming out thru concrete and damaging the courts. Also please cut the weeds around tennis court. THanks	5/23/2005 Medium	Michael Munoz Lorenzo Hernandez	Athletic Field	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1700	Work In Progress NEED OUTLETS INSTALLED FOR WASHER AND DRYER, 120V AND 230V.	5/5/2005 Medium	Danny Orozco Enrique Sotelo		Gadsden MS
1064	Work In Progress Would like to take out an office wall and turn the old tech offices into one classroom. ROUTED BACK TO RUDY AS PER MIKE MUNOZ 5/31/05 - MKV	4/12/2005 Medium	Dana Hamel Rudy Arreola	Office	Gadsden MS
266	Work In Progress washing machine out of order Teresa Portillo - SNP Manager (505) 882-2824	3/10/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Gadsden MS
117	Work In Progress Softball Field Concession Stand need to run power to it.	3/7/2005 Medium	Mario Apodaca Carlos Castillo	Athletic Field	Gadsden MS
354	Work In Progress Need to installing emerg. lights in hallways and restrooms girls and boys as per pm 125602.	3/14/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
269	Work In Progress Broken window need to be replaced this window was replaced about 1 week ago and its broken again. 31 x 76 As per Mike Munoz cove it with a board, this window was replace on 2/28/05.	3/10/2005 Medium	Rudy Arreola Ruben Ronquillo	Hallway/Corridor	Gadsden MS
2341	Work In Progress Light fixture on eastside of cafeteria was damaged and needs to be replaced.	5/27/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
2342	Work In Progress Light fixture on the westside of the A-WING boiler room was broken needs to be replaced.	5/27/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
2401	Work In Progress Door handles on both A/B wing boiler RMs need to be replaced they have tried to get into them one handle is missing.	6/1/2005 Medium	Rudy Arreola Hector Lozoya		Gadsden MS
2253	Work In Progress We need to replace the carpet in main office with tile the carpet is worn out and their are some runs. Also there are some patches were the old furniture used to be.	5/24/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
2259	Work In Progress Light fixture was broken on the southside of boiler room.	5/24/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
2260	Work In Progress Light fixture was broken the west side of the gym.	5/24/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2242	Work In Progress MAIN BANDROOM. We need to remove 2 steps in bandroom to make more room.	5/24/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
2244	Work In Progress Room 140 handle was broken need to have it replaced.	5/24/2005 Medium	Rudy Arreola Hector Lozoya		Gadsden MS
600	Work In Progress need new breakers to be installed on wwp. pulled old breakers and install new breakers	3/24/2005 4/7/2005 Medium	Michael Munoz Ricardo Jacquez		Gadsden MS
2155	Work In Progress We need to have the connections for the internet and phone lines. Electrical poles need to be removed.	5/20/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
2156	Work In Progress We need 3 electrical poles removed from front office. To clear up space for counter.	5/20/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
2145	Work In Progress Broken window in RM#303 in the VOC/BLDG.	5/20/2005 Medium	Rudy Arreola Ruben Ronquillo		Gadsden MS
2194	Work In Progress Need some help for knocking down some walls to make an extra classroom in C-WING old Calixto's office.	5/23/2005 Medium	Rudy Arreola Danny Miranda		Gadsden MS
2031	Work In Progress 2 A/C in main gym need to be replaced.	5/17/2005 Medium	Rudy Arreola Jaime Gomez		Gadsden MS
1465	Work In Progress We need metal frames around windows we several threw out the campus in main bldg. The moulding is missing.	4/27/2005 Medium	Rudy Arreola Ruben Ronquillo		Gadsden MS
851	Work In Progress Fence by the football feild is getting knocked down by students when they are running.	4/5/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
852	Work In Progress We are having problems with mice in the gym area. Boys and girls lockerrooms and coaches offices. Faxed PO on 4/14/05 - mkv	4/5/2005 Medium	Rudy Arreola Margret Villalobos		Gadsden MS
686	Work In Progress Some of the sprinklers in the front of campus are watering on to the street need to them adjusted or replaced.	3/30/2005 Medium	Rudy Arreola Lorenzo Hernandez		Gadsden MS
1105	Work In Progress Sidewalk on eastside of annex bldg is to steep for wheelchair need sidewalk raised.	4/13/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1101	Work In Progress We are going have a new student in a wheelchair the only concern is we need a walkway where the new fence was put up to connect to the side of the bandroom.	4/13/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
1102	Work In Progress Some of the doors to the main entance have a little step the wheelchair may not be able to go up (Concerned the student may flip forward).	4/13/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
326	Work In Progress We are having a problem with students in the cafeteria after hours we need to have dead bolts installed so we can secure cafeteria.	3/11/2005 Medium	Rudy Arreola Hector Lozoya	Cafeteria	Gadsden MS
1453	Work In Progress need to plow playground and seed	4/27/2005 Medium	Frank Lara Lorenzo Hernandez		La Mesa ES
1857	Work In Progress Aztec flooring. Need Price quotes on flooring on portables at La Mesa and portable at Deser-trail. Pleas call Mike before you go.	5/11/2005 Medium	Michael Munoz		La Mesa ES
2084	Work In Progress AZTEC FLOORING PLEASE PROVIDE A PRICE QUOTE FOR THE FOLLOWING ROOMS. VCT&COVEBASE RMS 28&29.	5/18/2005 Medium	Michael Munoz	Portables	La Mesa ES
886	Work In Progress Alvarez farms. washer and drier can be installed after May 17th. When David has completed the install please provide power. Might want to get with David.	4/6/2005 Medium	Carlos Castillo		La Union ES
817	Work In Progress Hookup of washer & dryer at La Union JTP (Alvarez) building.	4/4/2005 Medium	David Villalobos David Villalobos		La Union ES JTP - Alvarez
1748	Work In Progress A contactor is requested for a/c units.NEMA size 4. 8502SFO2S.Ser.460/575V 60hz.100HP. 3 phase	5/9/2005 Medium	Eddie Baeza Carlos Castillo		La Union ES
1613	Work In Progress Transformer for the high temp. alarm in the server rm. does not have 120v circuit only the 24v side was hooked up.	5/3/2005 Medium	Eddie Baeza Carlos Castillo		La Union ES
1932	Work In Progress A bubbler system is requested for the trees at the playground.	5/13/2005 Medium	Eddie Baeza Lorenzo Hernandez		La Union ES
739	Work In Progress Exterior light at the front parking lot near storm drain is out.	3/31/2005 Medium	Eddie Baeza Carlos Castillo		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
166	Work In Progress A motor starter coil is requested for the boiler pump at new addition	3/8/2005 Medium	Eddie Baeza Jose Ambriz		La Union ES
525	Work In Progress 600 Pounds of fertilizer is requested for the playground area.	3/18/2005 Medium	Eddie Baeza Lorenzo Hernandez		La Union ES
2233	Work In Progress A 16' trailer and 2 men are requested to take lockers which were removed from the Main bldg. to the PPD.	5/24/2005 Medium	Eddie Baeza Margret Villalobos		La Union ES
2205	Work In Progress Remodel areas where lockers were removed in four classrooms, with shelving.	5/23/2005 Medium	Eddie Baeza Danny Miranda		La Union ES
1676	Work In Progress NEED ANOTHER ROYAL BAG FOR THE VACUUM CLEANER. TO REPLACE TWO WITH SOME HOLES (DAMAGED). THANK YOU.	5/5/2005 Medium	Luis Solis Jimmy Carbajal		Loma Linda ES
490	Work In Progress need tractor to clean-up walk-in paths by north fence line/also east fence line	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
491	Work In Progress need fill-dirt on baseball diamonds/puddling water	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
492	Work In Progress need to re-do borders around playground equipment/plus remove sand from rockwall	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
493	Work In Progress need tractor to level off dirt in library courtyard	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
494	Work In Progress need tractor to level off rain erosion in bus parking run-off circle/eastside	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
163	Work In Progress side walk by front entrance has buckled and lifted/safety hazard/redo portion of sidewalk. 1395 wo	3/8/2005 Medium	Danny Vega Michael Munoz		Loma Linda ES
164	Work In Progress need tractor&scrapper to clean west pine tree-line/also rock wall sand	3/8/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
699	Work In Progress need window latches for rms 103-106-105-204 asap- need to secure windows at end of day-sent sample to ppd	3/30/2005 Medium	Danny Vega Danny Miranda	Classroom	Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
311	Work In Progress locks in Mr. Ramos window are broken and need to be replaced. also the window on south end of room could use new blinds Blinds are changed every 6 months in this room none in stock order thru PPD. Locks in order thru PPD. - Danny Vega	3/11/2005 Medium	Grace Alvarado Margret Villalobos		Loma Linda ES
452	Work In Progress DISTRICT ART SHOW SETUP AT GADSDEN MIDDLE SCHOOL, PUT UP IS APRIL 14, 2005 AT 8:30 AM TAKE DOWN IS APRIL 18, 2005 AT 10:00 AM	3/16/2005 Medium	Grace Alvarado Danny Vega		Loma Linda ES
352	Work In Progress UNABLE TO LOCK ROOM	3/14/2005 Medium	Grace Alvarado Hector Lozoya	Classroom	Loma Linda ES 114
2150	Work In Progress NEEDING NEW CHAIN WELDED ONTO GATE. CHAIN WAS CUT DURING A EMERGENCY MEDIVAC LANDING. NEEDED AS SOON AS POSSIBLE	5/20/2005 Medium	Grace Alvarado Hector Lozoya	Parking Lot	Loma Linda ES
1761	Work In Progress Needing Speedy to fertilize within next 2 weeks, also needing dirt to build borders for trees	5/9/2005 Medium	Grace Alvarado Lorenzo Hernandez		Loma Linda ES
796	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Ruben Solis		Mesquite ES
993	Work In Progress Need concrete poured around grease trap lids.	4/8/2005 Medium	Ricardo Jacquez Michael Munoz		Mesquite ES
971	Work In Progress NEED FILING CABINETS CYLINDERS REPLACED.THANX.	4/8/2005 Medium	Romauldo Apodaca Hector Lozoya		Mesquite ES
1117	Work In Progress NEED TO MAKE 6 FT. OPENING IN BOOK RM. TO ENTER NEXT RM. PER PHILLIPS.	4/13/2005 Medium	Romauldo Apodaca Michael Munoz		Mesquite ES
237	Work In Progress need 25 bags fertilizer.	3/10/2005 Medium	Romauldo Apodaca Lorenzo Hernandez		Mesquite ES
1619	Work In Progress have leak between wall in rm. 401 rest rm.thanx.	5/3/2005 Medium	Romauldo Apodaca Fred Appelzoller		Mesquite ES
1621	Work In Progress need replacement of a/c side draft in portable 610.	5/3/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1622	Work In Progress need replacement of industrial unit on barracks,per phillips and leyva.	5/3/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES
2152	Work In Progress PORTABLE 612 - DOOR HANDLE BROKEN.	5/20/2005 Medium	Romauldo Apodaca Hector Lozoya	Portables	Mesquite ES
2116	Work In Progress BERNICE SAPIEN - ROOM 304 NEED A NEW LOCK FOR FILING CABINET - KEY BROKE INSIDE LOCK.	5/19/2005 Medium	Luz Griego Hector Lozoya	Classroom	Mesquite ES
1673	Work In Progress Transporation Office - Need to install door w/window.	5/5/2005 Medium	Margret Villalobos Danny Miranda		Physical Plant Complex
2263	Work In Progress Maint. Office - Need to fix door closer to main door.	5/24/2005 Medium	Margret Villalobos Hector Lozoya		Physical Plant Complex
353	Work In Progress Need to installing emerg. lights as per pm 125559.	3/14/2005 Medium	Rudy Arreola Enrique Sotelo		Physical Plant Complex
2235	Work In Progress please order material for fill for disrict portable re-location. please include site and material that will be delivered on w.o . (per site)	5/24/2005 Medium	Lorenzo Hernandez		Physical Plant Complex
1309	Work In Progress Need to make material list and request for general maintenance duties	4/21/2005 Medium	Carlos Castillo Carlos Castillo	Electrical Room	Physical Plant Complex
1866	Work In Progress need to provide flooring to auto shop. aztec	5/11/2005 Medium	Michael Munoz		Physical Plant Complex
2357	Work In Progress Custodial Office - Need to correct cooling in Mary and Aida's Office.	5/27/2005 Medium	Alfredo Holguin Jaime Gomez	Custodial	Physical Plant Complex
1950	Work In Progress DEMO WALLS @ G.A.C C-WING	5/16/2005 Medium	Danny Miranda Danny Miranda		Physical Plant Complex
2070	Work In Progress FREEZER #3 LIGHT SWITCH IS OUT.	5/18/2005 Medium	Jacqueline Aguilar Danny Orozco		Physical Plant Complex
1430	Work In Progress OVEN NOT WORKING AT ALL. NANCY ROLLIN SNP MGR 589-2550	4/26/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Riverside ES
1971	Work In Progress Please remove carpet and install VCT with covebase in the following classrooms. 32,34,35,36,37,39,41.	5/16/2005 Medium	Michael Munoz	Classroom	Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2313	Work In Progress 5/26/05 ANGEL GONZALES NEED NEW BLADES FOR JOHNDEERE MOWER REAL BAD NOT OVER LAPING AND CUTTING THANK YOU SIR	5/26/2005 Medium	Adan Duran Angel Gonzales		Riverside ES
2185	Work In Progress 5/20/05 MR CARLOS CASTILLO WILL NEED LIFT TO CHANGE OUT LIGHTS IN GYN AND CAFETERIA BURN OUT THANK YOU SIR	5/20/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
2049	Work In Progress 5/17/05 MR CARLOS CASTILLO NEED TO CHANGE OUT SWITCH FOR AC IN CAFETERIA WATER PUMP NOT WORKING THANK YOU SIR	5/17/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
1576	Work In Progress 5/2/05 MR ANGEL GONZLES WILL NEED NEW BLADES FOR JOHNDEERE MOWER OLD ONES ARE SHOT THANK YOU SIR	5/2/2005 Medium	Adan Duran Angel Gonzales		Riverside ES
338	Work In Progress MR CARLOS CASTILLO WILL NEED TO REPLACE LIGHT COVERS IN PORTABLE BROKEN AND SOME IN NEW WING NEED TO COME OVER SO THAT YOU WILL KNOW WHAT KIND TO GET THANK YOU SIR	3/11/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
2085	Work In Progress RM 39, PLEASE REMOVE OLD CAULK AND BLOW OUT WITH AIR. INSTALLED NEW SEAL TO PREVENT AIR FROM ENTERING. ROOF TOP	5/18/2005 Medium	Adan Duran	Classroom	Riverside ES
2086	Work In Progress PLEASE INSTALL NEW WEATHER STRIPPING TO ALL DOORS AND WINDOWS TO PREVENT SAND FROM ENTERING ROOM.	5/18/2005 Medium	Adan Duran	Classroom	Riverside ES
2087	Work In Progress PLEASE REMOVE OLD TAR AND APPLY NEW ONE WHERE 90 WEIGHT IS BETWEEN CAFETERIA AND AUDITORIUM. ALSO REMOVE SAND FROM ROOF TOP.	5/18/2005 Medium	Adan Duran	Cafeteria	Riverside ES
2088	Work In Progress PLEASE REMOVE OLD SEAL, INSTALL NEW ONE WITH NEW CAULKING AND 45 CONCRETE AGAINST WALL AND FLOOR. OUTSIDE PATIO WHERE MAIN HALL WAY ENTERS TOWARDS CAFETERIA. THIS WILL PREVENT WATER FROM ENTERING TO BUILDING.	5/18/2005 Medium	Adan Duran	Cafeteria	Riverside ES
2151	Work In Progress KITCHEN HOOD SUPPRESSION SYSTEMS WAS DISCHARGED BY ACCIDENT. NEED TO RE- CHARGE SYSTEM.	5/20/2005 High	Danny Orozco	Cafeteria	Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2388	Work In Progress Need to replace filing cabinet keys for room 13, Mr. Enrique Moreno	5/31/2005 Medium	Olga Arias Hector Lozoya		Riverside ES
2241	Work In Progress Need to repair carpet. (edge) is picking-up within the office area. Doorway to the back copy room. Adan can you glue this down? - As per Mike.	5/24/2005 Medium	Olga Arias Adan Duran		Riverside ES
2110	Work In Progress RM 13 - 3 BROKEN WINDOWS	5/19/2005 Medium	REYES VALTIERRIA Ruben Ronquillo		Riverside ES
2283	Work In Progress Vacuum broken, loud and not working properly, serial#F96A00001406, model#1020P, tag#970166, issued 10-24-96.	5/25/2005 Medium	Miguel Aguilar Jimmy Carbajal		Riverside ES
2074	Work In Progress When fire alarm system replaced, ceiling light in upper grade library storage was removed and not placed back. Refrigeration air escaping and may cause overheating of unit and server located in room.	5/18/2005 Medium	Miguel Aguilar Adan Duran		Riverside ES
123	Work In Progress Mr. Valtierra, Principal RS, is requesting new carpet/flooring in Rm#36.	3/7/2005 3/2/2005 Medium	Miguel Aguilar Michael Munoz	Classroom	Riverside ES
146	Work In Progress "Please sent one of you employees to assist me with fixing 9 broken sprinklers, ASAP need to start watering grass. Please bring the following. Tees 1 1/2 inch to 1inch screw in. niples 1 inch 12 and 8 inch long. easy fix 1 1/2 inch. "	3/8/2005 Medium	Lorenzo Solis Lorenzo Hernandez		San Miguel ES
124	Work In Progress As per School Pricipal, Need a truck load of 3/4 inch rock for spreading in front of portable. Need it ASAP. Thank You!	3/7/2005 3/2/2005 Medium	Lorenzo Solis Lorenzo Hernandez		San Miguel ES
214	Work In Progress Please replace nonlocking door knob with locking one. Mrs. Avalos portable#45.	3/9/2005 Medium	Lorenzo Solis Hector Lozoya		San Miguel ES
216	Work In Progress Replaced falling apart door knob with new one on entrance door in cafeteria.	3/9/2005 Medium	Lorenzo Solis Hector Lozoya		San Miguel ES
2382	Work In Progress Connect utilities to relocated portable.	5/31/2005 Medium	Michael Munoz Fred Appelzoller	Portables	San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2383	Work In Progress Connect utilities to relocated portable.	5/31/2005 Medium	Michael Munoz Enrique Sotelo	Portables	San Miguel ES
717	Work In Progress Boiler Room - relief valve drain is not properly supported. As per Boiler Inspector.	3/30/2005 Medium	Michael Munoz Jaime Gomez		San Miguel ES
2268	Work In Progress CONNECT NEW PORTABLE.	5/25/2005 Medium	Michael Munoz Enrique Sotelo		San Miguel ES
1852	Work In Progress Please order paint so when portables arrive you can go ahead and paint. You site will be receiving one PLease see mike or call him for more info.	5/11/2005 Medium	Danny Vega	Portables	San Miguel ES
1826	Work In Progress NEED 14X30X1 PLEATED FILERS 8EA	5/11/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
1820	Work In Progress need filetrs for units 12ea) 20x20x1 pleated 12ea)12x25x1 pleated 12ea)12x25x1 pleated -asap	5/11/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
1821	Work In Progress ramp not level- door hits bottom platform -need to lift with chains asap	5/11/2005 5/12/2005 Medium	Danny Vega Danny Vega	Classroom	San Miguel ES #37
1766	Work In Progress KEY JAMMED IN CORE/CORE WILL NOT TURN - OVER	5/10/2005 Medium	Danny Vega Hector Lozoya	Classroom	San Miguel ES PORTABLE#37
1749	Work In Progress NEED TO REPLACE GUTTERS IN KITCHEN ROOF/NEED SCAFFOLDS/ D.MIRANDA NEED TO ORDERS GUTTERS.	5/9/2005 5/9/2005 Medium	Danny Vega Danny Miranda	Cafeteria	San Miguel ES
1881	Work In Progress NEED TOP PIVOT LACTH HINGE/RIGHT SIDE FOR METAL DOOR IN LIBRARY ASAP	5/12/2005 Medium	Danny Vega Hector Lozoya	Classroom	San Miguel ES LIBRARY
2103	Work In Progress need number (stick-on)plates for all class rm doors as per MRS DUNCAN (PRINCIPAL) 1 THRU 60	5/19/2005 Medium	Danny Vega Hector Lozoya		San Miguel ES
2118	Work In Progress REFG. AIR UNIT PORTABLE#33/IS NOT WORKING/USED FOR SUMMER SCHOOL /NEED HVAC -TECH	5/19/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
2140	Work In Progress 1-THROW TRASH 1-REPAIR CHAIR RM#19 1-CK A/C UNIT RM#33 5-GRDS WK ON CAMPUS 5/19 - 8	5/19/2005 Medium	Danny Vega Danny Vega		San Miguel ES

6/1/2005 11:15:37 AM

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2195	Work In Progress NEED TO COMPLETE INSPECTION AND EVALUATION ON RALH REYES BY JUNE 1, 2005	5/23/2005 Medium	Aida Salcedo Cervando Padilla		San Miguel ES
2196	Work In Progress NEED TO COMPLETE INSPECTION AND EVALUATION ON RALH REYES BY JULY 6TH, 2005	5/23/2005 Medium	Aida Salcedo Cervando Padilla		San Miguel ES
2198	Work In Progress NEED TO COMPLETE INSPECTION AND EVALUATION ON RALH REYES BY AUG 3, 2005	5/23/2005 Medium	Aida Salcedo Cervando Padilla		San Miguel ES
2199	Work In Progress NEED TO COMPLETE INSPECTION AND EVALUATION ON RALH REYES BY SEPT 7, 2005	5/23/2005 Medium	Aida Salcedo Cervando Padilla		San Miguel ES
2200	Work In Progress NEED TO COMPLETE INSPECTION AND EVALUATION ON RALH REYES BY OCT 5, 2005	5/23/2005 Medium	Aida Salcedo Cervando Padilla		San Miguel ES
2201	Work In Progress NEED TO COMPLETE INSPECTION AND EVALUATION ON RALH REYES BY NOV 2, 2005	5/23/2005 Medium	Aida Salcedo Cervando Padilla		San Miguel ES
1879	Work In Progress FILTER TO ICE MACHINE FELL OFF - WATER ALL OVER THE PLACE (THEY DID TURN OFF THE WATER)	5/12/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	San Miguel ES
1214	Work In Progress WALK IN REFRIGERATOR - VERY WARM, NOT COOLING AT ALL EVA MIRANDA - SNP MANAGER 505-233-2860	4/18/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	San Miguel ES
1777	Work In Progress Need a lock installed in a filing cabinet in the Library.	5/10/2005 Medium	Barbara Cardenas Hector Lozoya		San Miguel ES
2280	Work In Progress need flourescent lamp	5/25/2005 Medium	Danny Vega Enrique Sotelo		San Miguel ES
2347	Work In Progress need to open & install door between rms 37 and 38	5/27/2005 Medium	Danny Vega Danny Miranda	Portables	San Miguel ES rm#37-38
1982	Work In Progress ATTN. ANGEL GONZALEZ ANGEL COULD YOU DELIVER THE BOBCAT AND SWEEPER ATTACHMENT TO ME ON MONDAY ,MAY 23.	5/17/2005 Medium	Gerardo Marquez Angel Gonzales		Santa Teresa ES

THANKS JERRY.

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
453	Work In Progress ATT. ANGEL GONZALEZ. ANGEL I NEED FOR YOU TO SERVICE TRUCK 107.WOULD YOU LET ME KNOW WHEN YOU CAN FIT IT IN TO YOUR SCHEDULE. THANKS.	3/16/2005 Medium	Gerardo Marquez Angel Gonzales		Santa Teresa ES
454	Work In Progress ATT. CALI CASTILLO. CALI, NEED FOR YOU TO FOLLOW UP ON WK. OR. 124323. THANKS. NEED FOR YOU TO COME CHECK A COUPLE OF LIGHT FIXTURES THAT I AM HAVING TROUBLE WITH.	3/16/2005 Medium	Gerardo Marquez Carlos Castillo		Santa Teresa ES
2355	Work In Progress ATTN. JOSE AMBRIZ. JOSE, I NEED FOR YOU TO ORDER ME 3 BOXES OF HVAC FILTERS. 20"X30"X1" THANKS.	5/27/2005 Medium	Gerardo Marquez Jose Ambriz		Santa Teresa ES
2323	Work In Progress 5/26/O5 MIKE; I NEED FOR YOU TO GET ME A COPY OF THE PAINT SCHEDULE. THANKS.	5/26/2005 Medium	Gerardo Marquez Michael Munoz		Santa Teresa ES
2324	Work In Progress jimmy could you please send me a water solution tank, rotary brashes for roto mach. a.s.a.p thanks pablo	5/26/2005 Medium	Pablo Diaz Jimmy Carbajal		Santa Teresa ES
2111	Work In Progress SOUTH GATE WAS KNOCKED OF HINGES, SE CORNER OF FENCE WAS RIPPED AND PAINTED ON. CASE# 0503832	5/2/2005 Medium	Pablo Diaz Michael Munoz		Santa Teresa ES
2245	Work In Progress 3 COMP SINK IS LEAKING FROM THE BOTTOM.	5/24/2005 Medium	Margret Villalobos Danny Orozco	Cafeteria	Santa Teresa HS OLGA BUSTAMANTE
1130	Work In Progress Bus driveway - Need to fill pot holes located where Airport Road meets with the turn	4/14/2005 Medium	Michael Munoz Lorenzo Hernandez		Santa Teresa HS
714	Work In Progress Dress Room - replace electrical covers. As per Boiler Inspector.	3/30/2005 Medium	Michael Munoz Carlos Castillo		Santa Teresa HS
1395	Work In Progress GROUNDS SHOP - NEED TO RESTOCK FIRST AID KIT.	4/25/2005 Medium	Lorenzo Hernandez Ruben Ronquillo		Santa Teresa HS
348	Work In Progress BOTH MIRRORRS FROM BOYS BATH ROOM ARE FADED THEY NEED TO BE REPLACE IN THE ENGLISH WING THANK YOU.	3/14/2005 Medium	Luis Murillo Ruben Ronquillo		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
449	Work In Progress MS. HILL SHE HAS A PROBLEM WITH CUCARACHAS AND GRILLOS ON CLASS ROOM 312 AT ENGLISH WING AREA Faxed PO on 4/11/05 45010704	3/16/2005 Medium	Joel Herrera Margret Villalobos		Santa Teresa HS
341	Work In Progress BROKEN DOOR GLASS AT V.O.C BUILDING SIZE 23 3/4 X 23 1/4 WIRE GLASS	3/14/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
444	Work In Progress RUBEN RONQUILLO I NNED REPLACE WINDOW'S SCREENS ON CLASS ROOM 308 AT ENGLISH WING SIZE 30 3/4 X 36 1/2 INCHES. THANK YOU RUBEN...	3/16/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
923	Work In Progress WE NEED CHECK AND REPAIR DOOR LOCK NO WELDING CLASS ROOM AT V.O.C BUILDING	4/7/2005 Medium	Joel Herrera Hector Lozoya		Santa Teresa HS
1387	Work In Progress need to repair sheetrock in gym locker room	4/25/2005 Medium	Danny Miranda Danny Miranda	Auditorium	Santa Teresa HS
2387	Work In Progress Need 2 sets of the following keys 106e, 115r,039 for mailbox inside gate, as per Mr. Gallegos.	5/31/2005 Medium	Arturo Nunez Hector Lozoya		Santa Teresa HS
406	Work In Progress NEED TO HAVE MOP SINK FAUCETS AT KITCHEN REPLACED, WE HAVE A WATER LEAK.	3/15/2005 Medium	Arturo Nunez David Villalobos		Santa Teresa HS
1011	Work In Progress NEED CYLINDER AT DRESSING ROOM HALLWAY CHECKED SOME ONE STUCK SOMETHING IN IT, CAN" T OPEN IT ,AFRAID SOMEONE WILL BREAK KEY.	4/11/2005 Medium	Arturo Nunez Hector Lozoya		Santa Teresa HS
925	Work In Progress NEED TO HAVE OUTSIDE LIGHTING ON FRONT PARKING LOT CHECKED, MIGHT HAVE TO REPLACE LIGHT FIXTURES, TO DARK BY FENCE AREA,	4/7/2005 Medium	Arturo Nunez Carlos Castillo		Santa Teresa HS
693	Work In Progress NEED SIX (6) 240V OUTLET INSTALLED IN WELDING SHOP FOR WELDERS	3/30/2005 Medium	Arturo Nunez Carlos Castillo		Santa Teresa HS
695	Work In Progress NEED TILE INSTALLED AT TRAINERS WRAPPING AREA, REQUESTED BY MR. MUNOZ,FRANK.	3/30/2005 Medium	Arturo Nunez Michael Munoz		Santa Teresa HS
1967	Work In Progress NEED PICK UP TRUCK SERVICED ON PWR. STEERING PUMP, KEY IGNITION SWT, AND MUFFLER, I WILL BE OUT ON 5/18/05 TO 5/24/05 THANK YOU.....	5/16/2005 Medium	Arturo Nunez Angel Gonzales		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1998	Work In Progress 03/23/05 3/23 8.0 - CONT. PAINTING DRESSING ROOM	5/17/2005 Medium	Arturo Nunez Arturo Nunez		Santa Teresa HS
2317	Work In Progress need to provide new side walks to new portable.	5/26/2005 Medium	Michael Munoz	Portables	Santa Teresa MS
1277	Work In Progress please support with setting in of new portable and install ramps.	4/20/2005 Medium	Lorenzo Hernandez		Santa Teresa MS
1100	Work In Progress Receptacle shocking staff.	4/13/2005 Emergency	Carlos Castillo Carlos Castillo		Santa Teresa MS
1775	Work In Progress SPEEDY NEED TOO BORROW THE WHITE TRAILER ON 5/12/05	5/10/2005 Medium	Ismael Rodriguez Lorenzo Hernandez		Santa Teresa MS
1704	Work In Progress THE TIMER FOR THE OUTSIDE PARKING LIGHTS NEEDS TOO SET TO TURN OFF AT 6.00AM. THERE TURNING OFF AT 8.00AM.THANK YOU.CONTACT MR.RODRIGUEZ.	5/6/2005 Medium	Ismael Rodriguez Carlos Castillo		Santa Teresa MS
1098	Work In Progress Need a electrician to run some electrical wiring through some particians in the new nurses office. as per MS.WILLIAMS. THANK YOU.	4/13/2005 Medium	Ismael Rodriguez Carlos Castillo	Classroom	Santa Teresa MS
1055	Work In Progress SPEEDY HERNANDEZ NEED BACKHOE TO REMOVE SAND FROM NORTH AND SOUTHBUILDING.THANK YOU SIR.	4/12/2005 Medium	Ismael Rodriguez Lorenzo Hernandez		Santa Teresa MS
1103	Work In Progress ATTN;RUBEN RONQILLO. I NEED A TRAILER TOO TRANSPORT ART WORK FOR MR. SANCHEZ TO THE G.M.S 4/14/05. THANK YOU.	4/13/2005 Medium	Ismael Rodriguez Ruben Ronquillo		Santa Teresa MS
1431	Work In Progress NORTH BUILDING NURSES OFFICE ROOM 8 NEED ELECTRICIAN TO SET UP ELECTRICAL ACCESS DUE TO REMODLING	4/26/2005 Medium	Jose Hinojosa Carlos Castillo	Office	Santa Teresa MS
2204	Work In Progress 5 copies of cabinet key for North building kitchen cabinets	5/23/2005 Medium	Jose Hinojosa Hector Lozoya	Restroom (Boys)	Santa Teresa MS
2191	Work In Progress door cabinets off hinges need repair	5/23/2005 Medium	Jose Hinojosa Jaime Mijarez	Office	Santa Teresa MS Round Room Kitchen
2161	Work In Progress duplicate keys for new portables	5/20/2005 Medium	Jose Hinojosa Hector Lozoya	Portables	Santa Teresa MS
2056	Work In Progress NEED OUTLET EXTENSIONS FOR NURSE NEW CUBICLES AND EXTRA PHONE OUTLET	5/18/2005 Medium	Jose Hinojosa Carlos Castillo		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2057	Work In Progress ROOM 3 REFRIDGERATOR AND STOVE NEED TO BE LOOKED AT	5/18/2005 Medium	Jose Hinojosa Danny Orozco	Classroom	Santa Teresa MS
2058	Work In Progress DRYER AND WASHER NEED TO BE SERVICED...HAVE NOT BEEN IN 10 YEARS	5/18/2005 Medium	Jose Hinojosa David Villalobos	Classroom	Santa Teresa MS 3
2059	Work In Progress HINGES NEED TO BE REPLACED...DOOR NOT CLOSING IN UPPER LEVEL GIRLS BATHROOM	5/18/2005 Medium	Jose Hinojosa Danny Miranda	Restroom (Girls)	Santa Teresa MS
2060	Work In Progress WEST SIDE OF ROOM POWER STRIP SHORTED OUT...NEED REPLACING OR REPAIR	5/18/2005 Medium	Jose Hinojosa Carlos Castillo	Classroom	Santa Teresa MS 52
2246	Work In Progress remove carpet from art room, if possible As per Mike - Route back to Jaime. - mkv	5/24/2005 Medium	Jose Hinojosa Jaime Mijarez	Classroom	Santa Teresa MS room 1
1884	Work In Progress S.bldg rm36. Need to have a safety window with safety glass installed. Rm will be used for a special ed student. Requested by Ms Williams.	5/12/2005 Medium	Jaime Mijarez Danny Miranda	Classroom	Santa Teresa MS
298	Work In Progress Gym - Replace westside doors.	3/11/2005 Medium	Jaime Mijarez Danny Miranda		Santa Teresa MS
542	Work In Progress Choir Rm . Outside metal door is damaged and old used to belong to the demolished mechanical rm. Door is to big and heavy for students to be opening every day. Would like to have it replaced to a new and smaller door. Approved by principal.	3/18/2005 Medium	Jaime Mijarez Danny Miranda		Santa Teresa MS
173	Work In Progress Rm 8 N.bldg- Nurses office is going to be remodeled and is going to need new electrical outlets for counter areas and office area.	3/8/2005 Medium	Jaime Mijarez Carlos Castillo		Santa Teresa MS
546	Work In Progress Room 28 - Need to replace door glass on outside door.	3/18/2005 Medium	Sebastian Diaz Ruben Ronquillo	Classroom	Sunland Park ES
1083	Work In Progress 4/12/05 need 4 metal cover for A/C THANK YOU	4/12/2005 Medium	Sebastian Diaz Jose Ambriz		Sunland Park ES
2409	Work In Progress THIS IS A REQUEST FOR SAND TO BE PLACED UNDER SWING AREA AND MONKEY BAR PIT.	6/1/2005 Medium	Irene Trujillo Lorenzo Hernandez		Sunland Park ES
2319	Work In Progress Replace pipe under sink.	5/26/2005 Medium	Irene Trujillo David Villalobos	Classroom	Sunland Park ES room 28

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2320	Work In Progress Replace faucet and pipe under sink.	5/26/2005 Medium	Irene Trujillo David Villalobos	Office	Sunland Park ES teacher's lounge
2321	Work In Progress THE GRASS SHOULD BE REPLACED ON THE CIRCLE ENTERING THE SCHOOL GROUNDS. WE NEED THE AREA SMOOTHED AND SOD PLACED. REQUESTED AS PER MS. LINDA PEREZ, ASST. PRINCIPAL.	5/26/2005 Medium	Irene Trujillo Lorenzo Hernandez		Sunland Park ES GROUNDS
488	Work In Progress NEED TO REPAIR WINDOWS @ OPERATORS	3/17/2005 Medium	Danny Miranda Danny Miranda		Sunland Park ES
992	Work In Progress Need North and South leachfields cleaned out.	4/8/2005 Medium	Ricardo Jacquez Lorenzo Hernandez		Sunrise ES
2158	Work In Progress I NEED MORTAR MIX TO PATCH UP BRICK WALL IN WING A BRICKS COMING APART FROM TOP OF WALL.	5/20/2005 Medium	Paul Quinones Ruben Ronquillo		Sunrise ES
2113	Work In Progress I NEED A COUPLING THAT TURNS THE CIRCULATING PUMP WITH MOTOR SHAFT, TO CIRCULATE WATER TO UNIT IN OUT DOOR MECH. RM.	5/19/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
946	Work In Progress I NEED SAND FOR BOTH PLAY GROUNDS	4/7/2005 Medium	Paul Quinones Lorenzo Hernandez		Sunrise ES
2208	Work In Progress MASTER COOL UNIT WILL NOT TURN ON AND THE EXHAUST FAN AS WELL,	5/23/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
2209	Work In Progress STERLING UNIT WET SECTION MIXED AIR CONTROL NOT WORKING PROPERLY DAMPER STAYS SHUT AT TIMES, AND HAS TO BE MOVED MANUALLY FOR COOLING, AND HEATING AS WELL.	5/23/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
2278	Work In Progress UNIT IN RM.308 NO CIRCULATING WATER. A SLEEVE IS NEEDED TRIPPING ON HIGH HEAD PRESSURE AS WELL	5/25/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2407	Work In Progress 5-27-05 .5,CHECK IN WITH OFFICE 3.0,PICK UP MATERIALS,AND TURN IN TIME SHEET 2.5,REROUT 6 INCH FLEX MORE AIR FLOW NEEDED IN CAFET- ERIA MANAGERS OFFICE. 1.0,PICK UP TRASH,AND SWEEP GRAVEL FROM BASKETBALL COURTS 1.0,ASSIST RICK J. CLEAN LIFT STATION 5/27 - 8	6/1/2005 Medium	Paul Quinones Paul Quinones		Sunrise ES
2318	Work In Progress REQUESTING PEST CONTROL SPRAYING IN CLASS ROOMS TOO MANY SPIDERS,AND SCORPIONS. THANK YOU.	5/26/2005 Medium	Paul Quinones Margret Villalobos		Sunrise ES