

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

24365					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24366					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24684	Drug Free Bldg.	Office			7/11/2007		209		\$0.00
-------	-----------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/11/2007 7:36:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Drug free need to replace door handle on two doors and it a off master

Hector Villalobos

25385	Main Building	Custodial			8/3/2007		186		\$0.00
-------	---------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/3/2007 11:57:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel repair weed eater

David Vega

25565		Cafeteria			8/7/2007		182		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/7/2007 11:21:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Reach-In Refrigerator is still out of order - Refrigerator gets a block of ice inside - she was instructed to disconnect the refrigerator, wait, then plug it back in; when she did this process this morning, the refrigerator kept on flipping on the Breaker.

Becky Saenz - SNP Manager 882-3507

Alma Terrell

25569		Cafeteria			8/7/2007		182		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/7/2007 11:32:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Reach-In Freezer is still out. Needs parts for compressor

Becky Saenz - SNP Manager 882-3507

Alma Terrell

25606	Annex Building	Classroom			8/8/2007		112		\$0.00
-------	----------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/8/2007 10:36:13 AM	11/28/2007			
--------	------------------	--	--	--	----------------------	------------	--	--	--

Moncayo, Fernando Room 203 - A/C unit is not cooling. (Informed Fernando)

David Vega

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

26289	Cafeteria	Cafeteria			8/27/2007		162		\$0.00
-------	-----------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/27/2007 11:19:01 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny AS PER ECOLAB - AE 3-6 CAMPUS: LINE TO THE RINSE IS CLOGGED UP. DOES NOT COME OUT.

CUCA PEREZ 882-5607

Jacqueline Aguilar

26332	Main Building				8/28/2007		161		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/28/2007 7:45:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael Mild blg lounge replace counter top and make door for cabinet

Hector Villalobos

26348	Cafeteria	Cafeteria			8/28/2007		161		\$0.00
-------	-----------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/28/2007 10:07:49 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny REACH - IN REFRIG. TEMP IS GOING UP FAST WAS AT 50 THIS MORNING AND NOW ITS AT 55.

CUCA PEREZ: SNP MGR 882-5607

Jacqueline Aguilar

26750	Cafeteria	Cafeteria			9/6/2007		152		\$0.00
-------	-----------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2007 12:38:20 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny As per Mr. Giovas, he was there at Anthony Elementary, water is leaking from the top and bottom pipes to the dishwashing machine.

Rebecca Saenz - SNP Manager 882-3507

Alma Terrell

27502	Main Building				9/27/2007		131		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/27/2007 10:03:40 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben Borken wire glass 21 1/4x58 room 21

Hector Villalobos

27548		Portables			9/28/2007		130		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/28/2007 8:26:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben PT3 broken window 33 3/4x 22

Hector Villalobos

27846	Office				10/4/2007		124		\$0.00
-------	--------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Pre-K			10/4/2007 7:46:44 AM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Sotelo, Enrique PREK on track office needs more outlets for computer

Hector Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

27868	Main Building	Office			10/4/2007		124		\$0.00
-------	---------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/4/2007 11:04:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
 WE WILL BE NEEDING TO CHANGE THE LOCK FOR THE SUPPLY ROOM IN THE MAIN AND PRIMARY BUILDING. WE WILL BE NEEDING 9 ADDITIONAL KEYS. IF YOU HAVE ANY QUESTIONS PLEASE FREE TO CONTACT ME.

Loraine Gandara

27893					10/5/2007		123		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/5/2007 9:13:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
 check exterior lights, i will show electrician which ones are burned out

David Vega

28350					10/19/2007		109		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress	Anthony On Track			10/19/2007 4:48:27 PM				
--------	------------------	------------------	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben
 Blinds for windows (6) in office portable and in two classrooms.
 4- 47 x 37
 2- 33 x 62

Lucy Meza

28492	Dona Ana	Office			10/24/2007		104		\$0.00
-------	----------	--------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2007 3:14:21 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
 Hector Villalobos
 Need to charge locks for p.e and office

28563		Classroom			10/25/2007		103		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	Pre - K			10/25/2007 3:46:59 PM				
--------	------------------	---------	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben
 Hector Villalobos
 P.R.E.K headstart rooms 306 307 blinds 12 63x54

29108					11/9/2007		88		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/9/2007 11:14:13 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenzø
 Michael Munoz
 Nurse Station - Install a package unit.

29151	Original Main	Classroom			11/13/2007		84		\$0.00
-------	---------------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 9:07:01 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
 Loraine Gandara
 WE NEED AN KEYS FOR ROOM 206 SPEECH ROOM...

29388	Main Building	Hallway/Corridor			11/26/2007		71		\$0.00
-------	---------------	------------------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/26/2007 8:19:29 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben
 Hector Villalobos
 Broken windows exit door mild blg two 8 3/4 x 37 1/2 wire grass

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Anthony ES							
29390	Chapter I	Classroom			11/26/2007		71		\$0.00
Medium	Work In Progress				11/26/2007 8:21:25 AM				
Lozoya, Manny		Chapter blg music room borken lock can not open							
Hector Villalobos									
29811		Portables			12/4/2007		63		\$0.00
Medium	Work In Progress				12/4/2007 3:02:11 PM				
Lozoya, Manny		PT219 need a key made for filing cabinet							
Hector Villalobos									
29812		Portables			12/4/2007		63		\$0.00
Medium	Work In Progress				12/4/2007 3:04:29 PM				
Lozoya, Manny		Headstrat pt 1 need a keymade for filing cabinet							
Hector Villalobos									
29900					11/26/2007		71		\$0.00
Medium	Work In Progress				12/7/2007 9:33:21 AM				
Munoz, Michael		NEW PLAYGROUND SHATE WAS CUT 3 TIMES.							
Hector Villalobos									
29903	Original Main	Office			12/7/2007		60		\$0.00
Medium	Work In Progress				12/7/2007 9:39:26 AM				
Lozoya, Manny		Old main blg new office cabinet and filing cabinet need keys made							
Hector Villalobos									
29930		Portables			12/10/2007		57		\$0.00
Medium	Work In Progress				12/10/2007 10:27:27				
Solis, Lorenzø		pt 221 replace heater.							
Hector Villalobos									
30300					1/6/2008	1/27/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:28:57 AM				
Orozco, Danny		Monthly - Anthony ES Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									
30908					1/24/2008		12		\$0.00
Medium	Work In Progress				1/24/2008 11:02:52 AM				
Lozoya, Manny		Provide me with a list of individuals who have keys to the gates on this campus							
Alfredo Holguin									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

30955		Cafeteria			1/25/2008		11		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/25/2008 12:01:01 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny KITCHEN SINKS ARE BACKING UP.

CUCA PEREZ/ AE MGR 882-5607

Jacqueline Aguilar

31015	Main Building	Custodial			1/29/2008		7		\$0.00
-------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/29/2008 10:14:33 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

need new ez way

David Vega

31029	Main Building	Classroom			1/29/2008		7		\$0.00
-------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/29/2008 2:32:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique Replace brun out lamps and ballast in milg blg

Hector Villalobos

31031	Main Building	Office			1/29/2008		7		\$0.00
-------	---------------	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/29/2008 2:47:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe Remove toilet from Mrs Marqurz office

Hector Villalobos

31116	Main Building	Parking Lot			1/31/2008		5		\$0.00
-------	---------------	-------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/31/2008 7:23:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique Need bucket truck to replace lamps in parking lot mild blg

Hector Villalobos

31117	Main Building				1/31/2008		5		\$0.00
-------	---------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/31/2008 7:25:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique mild blg front side out side lighting need to install photo cell

Hector Villalobos

31191					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:32 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Hector Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

31193					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:32 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Hector Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

31239					2/3/2008	2/9/2008	2		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:52 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Hector Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

31290	AnnexBuilding	Classroom			2/5/2008		0		\$0.00
-------	---------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/5/2008 8:30:33 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ronquillo, Ruben Broken window room 203 two 38 1/8 x15 5/8

Hector Villalobos

31292		Portables			2/5/2008		0		\$0.00
-------	--	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/5/2008 8:35:16 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ronquillo, Ruben pt 221 broken window one 32 3/4 x28 1/8 one 33 3/4 x28

Hector Villalobos

31305	Main Building	Office			2/5/2008		0		\$0.00
-------	---------------	--------	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/5/2008 10:57:29 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Hector Replace floor tile in Mrs Marquz office and hallway

Hector Villalobos

31307	Cafeteria	Cafeteria			2/5/2008		0		\$0.00
-------	-----------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/5/2008 11:03:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Hector Need to get cafeteria ready on 2/27 /08 for banquet . ceiling tile panit walls and doors

Hector Villalobos

Count: 43 Work Orders		Avg. Age of WO's 84				Total for Anthony ES	0		\$0.00
------------------------------	--	----------------------------	--	--	--	-----------------------------	----------	--	---------------

Location: Berino ES

24367					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24368					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24369					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

2/5/2008 6:09:33 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Berino ES
------------------	------------------

24370					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24539					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Holguin, Ramiro		Yearly - Berino ES Emer. Light Test: Annual - Refer to PM schedule details.							
-----------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24624					7/9/2007		211		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				7/9/2007 11:01:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		NEED A KEY MADE FOR PARENT ROOM MRS. DOMINGUEZ NEEDS A KEY							
---------------	--	--	--	--	--	--	--	--	--

Ramiro Holguin									
----------------	--	--	--	--	--	--	--	--	--

26739					9/4/2007		154		\$1,400.00
-------	--	--	--	--	----------	--	-----	--	------------

Medium	Work In Progress				9/6/2007 9:41:23 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Holguin, Ramiro		Some tagging on Rm 135 and top of bldg eastside of cafeteria. Stolen Equipment: gateway, lenuxes printer, cassette player sony SE 100879-FED Case# 2007-08258 Deputy Alvarado 657							
-----------------	--	---	--	--	--	--	--	--	--

Jimmy Cortez									
--------------	--	--	--	--	--	--	--	--	--

26824	Main Building	Gym			9/10/2007		148		\$0.00
-------	---------------	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	5058822242			9/10/2007 6:54:35 AM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Lozoya, Manny		LOCK TO HATCH TO ROOF WAS BROKEN OFF DURING THE BREAK IN NEEDS TO BE REPLACED							
---------------	--	---	--	--	--	--	--	--	--

Jimmy Cortez									
--------------	--	--	--	--	--	--	--	--	--

27278		Cafeteria			9/21/2007		137		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/21/2007 2:02:30 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		KIDS PLAYING WITH A BASKETBALL BROKE SERVING LINE GLASS IN THE KITCHEN.							
---------------	--	---	--	--	--	--	--	--	--

ESLA CHAIREZ 882-2417									
-----------------------	--	--	--	--	--	--	--	--	--

Jacqueline Aguilar									
--------------------	--	--	--	--	--	--	--	--	--

27631					9/30/2007	10/21/2007	128		\$0.00
-------	--	--	--	--	-----------	------------	-----	--	--------

Medium	Work In Progress				9/30/2007 12:17:37 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny		Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

28572		Cafeteria			10/26/2007		102		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/26/2007 8:57:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny

Having problems with Dishwasher - Tom/Ecolab checked the DW-his recommendation: repair or replace the vacuum breaker and repair or replace the solenoid valve for the final rinse.

Aida Salcedo - SNP Coord. 882-6772 and Elsa Chairez - SNP Manager 882-2417

Alma Terrell

28663					10/30/2007		98		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/30/2007 9:16:41 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Holguin, Ramiro

please rake and clean around and beneath all pine trees, make new wells and make sure bubblers are worknig. especially in the west area.

Michael Munoz

28992		Cafeteria			11/6/2007		91		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/6/2007 12:53:59 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny

SLICER KEEPS ON CUTTING OFF/NOT WORKING/IT SEEMS LIKE THE WIRING, HAVE TO JIGGLE IT TO WORK.

AIDA SALCEDO -SNP COMPLIANCE COORD. 882-6771
ELSA CHAIREZ - SNP MANAGER 882-2417

Alma Terrell

29029					11/7/2007		90		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/7/2007 9:26:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny

BROKEN FLOOR TILES THROUGHOUT FACILITY - REPEAT VIOLATION FROM ENVIRONMENT INSPECTION DEPARTMENT.

AIDA SALCEDO - SNP COMPLIANCE COORDINATOR 882-6772
ELSA CHAIREZ - SNP MANAGER - 882-2417

Alma Terrell

29143		Cafeteria			11/13/2007		84		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 8:40:56 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny

WALK-IN REFRIG. TEMP. IS AT 45 TO 55

ELSA CHAIREZ - SNP MGR 882-2417

Jacqueline Aguilar

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

29618					12/2/2007	12/8/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:29:54 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Holguin, Ramiro		Monthly - Berino ES Monthly FE Inpsection - Refer to PMschedule details.							
-----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

29640					12/2/2007	12/10/2007	65		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:03 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Holguin, Ramiro		Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
-----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

29643					12/2/2007	12/10/2007	65		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:04 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Holguin, Ramiro		Monthly - Berino ES Emer. Light Test: Monthly - Refer to PMschedule details.							
-----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

30165					12/18/2007		49		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/18/2007 7:53:56 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenzø		ONE OF THE BOILERS NEEDS TO BE CHECK OUT NOT WORKING							
----------------	--	--	--	--	--	--	--	--	--

Ramiro Holguin

30254					1/6/2008	1/12/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:39 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Holguin, Ramiro		Monthly - Berino ES Monthly FE Inpsection - Refer to PMschedule details.							
-----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

30271					1/6/2008	1/14/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Holguin, Ramiro		Monthly - Berino ES Roof Inspection - Refer to PM schedule details.							
-----------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

30295					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

30301					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - Berino ES Range Hood Cleaning - Refer to PMschedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

30323					1/6/2008	1/14/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:06 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Holguin, Ramiro		Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
-----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

30326					1/6/2008	1/14/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Holguin, Ramiro		Monthly - Berino ES Emer. Light Test: Monthly - Refer to PMschedule details.							
-----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

30670					1/16/2008		20		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/16/2008 7:23:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo		BOILERS NOT WORKING RIGHT TEMPETURE IN WATER TO LOW NEEDS TO BE CHECK OUT. CLASS ROOMS ARE COLD							
----------------	--	---	--	--	--	--	--	--	--

Ramiro Holguin

30776	Main Building	Custodial			1/18/2008		5	1	\$25.00
-------	---------------	-----------	--	--	-----------	--	---	---	---------

Medium	Work In Progress				1/18/2008 9:14:42 AM	1/23/2008			
--------	------------------	--	--	--	----------------------	-----------	--	--	--

Carbajal, Jimmy		ROTO NEEDS TO BE READJUSTED				ADJUSTED LIMIT SWITCH			
-----------------	--	-----------------------------	--	--	--	-----------------------	--	--	--

Jimmy Cortez

30777	Main Building	Hallway/Corridor			1/18/2008		18		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/18/2008 9:17:54 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan		TILES NEED TO BE EXCHANGED CRACKED IN MAIN HALL AND ENTRANCE				AS PER JESUS ESTRADA - ROUTE TO BUILDING MECHANIC			
-------------	--	--	--	--	--	---	--	--	--

Jimmy Cortez

30778		Restroom (Boys)			1/18/2008		18		\$0.00
-------	--	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/18/2008 9:29:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan		BASEBOARDS NEEDS TO BE REPLACED IN ALL 8 SMALL RESTROOMS BOYS AND GIRLS IN CLASSROOMS 100 101 105 104				AS PER JESUS ESTRADA - ROUTE TO BLDG MECH.			
-------------	--	---	--	--	--	--	--	--	--

Jimmy Cortez

30827					1/22/2008		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/22/2008 10:01:06 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Holguin, Ramiro		Portable 157 - Window was left open and they went in and stole the overhead projector. (Case# 2008-00879) est loss 150.00							
-----------------	--	---	--	--	--	--	--	--	--

Maribel Chavez

30906					1/24/2008		12		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/24/2008 10:36:48 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenzo		THE TWO HEATERS ON EASTSIDE OF GYM ARE NOT WORKING NEED TO BE CHECK OUT							
----------------	--	---	--	--	--	--	--	--	--

Ramiro Holguin

2/5/2008 6:09:33 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

31053	Main Building	Library			1/30/2008		6		\$0.00
-------	---------------	---------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 10:40:38 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Adan Duran
Library - Door knob is coming loose.

31054		Portables			1/30/2008		6		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 10:41:13 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Adan Duran
Portable 158- Door knob is coming loose.

31055	Main Building	Restroom (Boys)			1/30/2008		6		\$0.00
-------	---------------	-----------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 10:42:13 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Joe
Adan Duran
Kinder Classroom (Boys RR) - Need a bowl wax.

31056	Main Building	Restroom (Boys)			1/30/2008		6		\$0.00
-------	---------------	-----------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 10:42:55 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Joe
Adan Duran
2nd Grade (Boys RR) - Need to replace all p-traps.

31057	Main Building				1/30/2008		6		\$0.00
-------	---------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 10:43:53 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique
Adan Duran
Teachers Lounge - Breaker keeps tripping when they turn something on.

31058	Main Building				1/30/2008		6		\$0.00
-------	---------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 10:44:49 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique
Adan Duran
Broken outlets in hallway between rooms 110 & 115.

31059		Portables			1/30/2008		6		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 10:45:18 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique
Adan Duran
Pt 136 - broken outlet.

31192					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:32 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan
Margret Villalobos
Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.

31195					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:33 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan
Margret Villalobos
Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Berino ES

31240					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:52 AM				
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									

Count: 41 Work Orders **Avg. Age of WO's 71** **Total for Berino ES 1 \$1,425.00**

Location: Chaparral ES

24377					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:50 AM				
Villalobos, David	Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									

24935		Classroom			7/20/2007		200		\$0.00
Medium	Work In Progress	103			7/20/2007 8:00:42 AM				
Lozoya, Manny	Teacher lost her keys, will pay. needs key to be done. See Jennifer								
Jennifer Corral									

25629					8/8/2007		181		\$0.00
Medium	Work In Progress				8/8/2007 3:37:25 PM				
Sotelo, Enrique	8/8/07. need electrical strip installed in rm.101.								
Joe Ramirez									

25630					8/8/2007		181		\$0.00
Medium	Work In Progress				8/8/2007 3:38:23 PM				
Sotelo, Enrique	8/8/07 breaker for lounge keeps tripping. please check.								
Joe Ramirez									

26178		Library			8/23/2007		166		\$0.00
High	Work In Progress				8/23/2007 8:07:46 AM				
Lozoya, Manny	Push Bar needs to be replaced, Librarian cut her hand.								
Joe Ramirez									

26976					9/13/2007		145		\$0.00
Medium	Work In Progress				9/13/2007 6:57:38 AM				
Lozoya, Manny	9/13/07 fire proof file cabinet in principals' office needs to be re-keyed.								
Joe Ramirez									

28206					10/16/2007		112		\$0.00
Medium	Work In Progress				10/16/2007 3:55:10 PM				
Orozco, Danny	Drain to walk-in freezer inside Ch. Elem. kitchen is clogged up and frozen.								
Johnny Acuna									

2/5/2008 6:09:33 PM

Page 12 of 165

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

24376 7/1/2007 8/1/2007 219 \$0.00

Medium Work In Progress 7/1/2007 12:15:50 AM

Villalobos, David Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24647 Custodial 7/9/2007 211 \$0.00

Medium Work In Progress 7/9/2007 4:00:58 PM

Carbajal, Jimmy The furniture out in the open (Chaparral Elem.) goes to La Mesa Elem. for storage. (Route to Jimmy Carbajal)

Jesus Estrada

24936 Classroom 7/20/2007 200 \$0.00

Medium Work In Progress 510 7/20/2007 8:03:29 AM

Lozoya, Manny Need key for classroom. Music teacher that was there lost key and needs to be replaced.

Jennifer Corral

24938 Classroom 7/20/2007 200 \$0.00

Medium Work In Progress 502 7/20/2007 8:05:12 AM

Lozoya, Manny new counselor in room, has key to open office but needs locks replaced so she can open outside doors, they require master keys and Principal does not want her to have a master key.

Jennifer Corral

24940 Computer Lab 7/20/2007 200 \$0.00

Medium Work In Progress 310 7/20/2007 8:06:56 AM

Lozoya, Manny computer teacher needs key for her desk. Cannot open her desk. Wants to know if it's able to be fixed. See Olivia

Jennifer Corral

25071 Office 7/25/2007 195 \$0.00

Medium Work In Progress OFFICE 7/25/2007 11:28:57 AM

Lozoya, Manny REQUESTING 2 MASTER KEYS FOR THE PORTABLES AND 1 MASTER KEY FOR THE TWO FRONT GATES. WILL BE USED FOR OFF TRACK PRE-KINDER DIRECTOR

Jennifer Corral

25329 8/2/2007 187 \$0.00

Medium Work In Progress 8/2/2007 8:48:56 AM

Lozoya, Manny Need lock replaced in P-1. Teacher has hard time trying to open the key. See Ms. Atkins

Jennifer Corral

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

25709					8/10/2007		179		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/10/2007 10:01:33 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
8/10/07.
keys to a fire proof file cabinet were accidentally locked inside p-3 pre kinder office and they need the important papers inside.

Joe Ramirez

26071		Office			8/21/2007		168		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	OFFICE			8/21/2007 8:14:36 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Lozoya, Manny
CABINET LOCK WAS LOCKED ACCIDENTLY AND WE CANNOT FIND KEYS FOR CABINET, NEED KEYS AS SOON AS POSSIBLE. BIRD DRILLED AND CABINET NEEDS NEW LOCK AND KEYS. IT'S FOR NEW PRINCIPAL. THANKS

Jennifer Corral

26299		Classroom			8/27/2007		162		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	403			8/27/2007 1:28:55 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny
Teacher has a key to door, says it gets stuck constantly and wants it replaced with a new lock. See Ms. Degeeter

Jennifer Corral

26649		Portables			9/4/2007		154		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	p-3			9/4/2007 8:25:13 AM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Lozoya, Manny
need another key to portable 3 for pre kinder classes for new clerk. See Judy Atkins

Jennifer Corral

26931		Classroom			9/12/2007		146		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	512			9/12/2007 10:40:56 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lozoya, Manny
teacher is requesting another key for room. There are now two teachers in that room. See Ms. Adina

Jennifer Corral

27215					9/20/2007		138		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/20/2007 8:32:42 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Briones, Enrique
9/20/07.
we need discarded furn. and equip. to be picked up by the purch. wrhse. turn in sheets are available.

Joe Ramirez

28176					10/16/2007		112		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

High	Work In Progress				10/16/2007 9:36:42 AM				
------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenzo
please do a start-up of all heaters and shut down off a/c. ask site administrator on shut-down. Johnnny and paul will assist

Michael Munoz

2/5/2008 6:09:33 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

28241					10/17/2007		111		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/17/2007 3:45:12 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny (Chaparral Elementary): (Ms. Vasquez, Room #414):
Door to classroom is fallen. Door is hard to close. Need to re-weld top hinge of frame. Also, need to weld door closure to top of metal frame.

Johnny Acuna

28329					10/19/2007		109		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/19/2007 2:10:05 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny Chaparral Elementary: Milk cooler is not cooling and with the Dishwasher the water is not hot enough.

Johnny Acuna

28503					10/24/2007		104		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2007 3:51:34 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Michael Mike Muñoz: Need a double gate installed on the east side of fence area (Where the Trees are). Pre-K portable at Chaparral Elementary.

Johnny Acuna

29299		Cafeteria			11/16/2007		81		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/16/2007 9:53:31 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny THERE IS A MOUSE IN THE KITCHEN

ESTHER CISNEROS SNP MGR 824-0048

Jacqueline Aguilar

29796					12/4/2007		63		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/4/2007 10:54:27 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Joe Chaparral Elementary: Portable 2 / Pre-K. Water faucet to sink is leaking. Need a new gasket in the cold water side of the valve.

Johnny Acuna

29827					12/4/2007		63		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/4/2007 3:57:47 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique Need help in checking hand dryer to boy's restroom in the E-wing.

Johnny Acuna

29828					12/4/2007		63		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/4/2007 4:00:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Need a pad lock for Blue box inside the irrigation system area.
Pad Lock (N-53)

Johnny Acuna

2/5/2008 6:09:34 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

29915 12/7/2007 60 \$0.00

Medium Work In Progress 12/7/2007 2:34:25 PM

Sotelo, Enrique Chaparral Elementary: Need (1) 250w outdoor security light bulb. (Largo y Delgado: Entrada Grande). ** (4) 175w outdoor security light bulbs (Foco y entrada chico).

Johnny Acuna

29916 12/7/2007 60 \$0.00

Medium Work In Progress 12/7/2007 2:39:27 PM

Lozoya, Manny Need to re-weld rebar back on to the Roof top Ladder and re-enforce all other bars. Main building: Metal Ladder on top of Roof: Cafeteria Section.

Johnny Acuna

29917 12/7/2007 60 \$0.00

Medium Work In Progress 12/7/2007 2:42:29 PM

Lozoya, Manny Chaparral Elementary Rooftop: Need to Make and install Metal ladder and frame to main building wall to be able to go up from the kitchen rooftop to cafeteria rooftop.

Johnny Acuna

29932 12/10/2007 57 \$0.00

Medium Work In Progress 12/10/2007 10:36:50

Sotelo, Enrique Chaparral Elementary: Principal Requesting to check and fix Parking Lot Security light fixtures. Lights not working: Too dark at night.

Johnny Acuna

30094 12/14/2007 53 \$0.00

Medium Work In Progress 12/14/2007 10:20:27

Vargas, Juan SUPPORT CHE ON WEDNESDAY DECEMBER 19TH IN THE MORNING IN REMOVING FURNITURE IN OFFICE AREA. REINSTALL FURNITURE ON MONDAY MORNING JAN.7,2008. (JOHNNY, PAUL AND EDDIE WILL ASSIST)

Michael Munoz

30129 12/17/2007 50 \$0.00

Medium Work In Progress 12/17/2007 8:03:41 AM

Carbajal, Jimmy need,to,borrow,dolleys,to,move,furniture,on,the,19, 1/11/08 - REQUESTED STATUS FROM
Daniel Ramirez JIMMY

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
30130					12/17/2007		50		\$0.00
Medium	Work In Progress				12/17/2007 8:06:27 AM				
Sotelo, Enrique		Chaparral Elementary: Rm. #101 - Mrs. Ledesma - Requesting 2 sets of electrical outlets to be installed on the south wall between restroom door and the window. These outlets are for the student's cd players storybook learning center.							
Johnny Acuna									
30154					12/17/2007		50		\$0.00
Medium	Work In Progress				12/17/2007 3:36:14 PM				
Lozoya, Manny		Chaparral Elementary School Principal: Mrs. Ballard is requesting a lock for the Fire Proof Filing Cabinet.							
Johnny Acuna									
30255					1/6/2008	1/12/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:28:39 AM				
Acuna, Johnny		Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
30272					1/6/2008	1/14/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:28:46 AM				
Acuna, Johnny		Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
30302					1/6/2008	1/27/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:28:58 AM				
Orozco, Danny		Monthly - Chapparral ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
30897					1/24/2008		12		\$0.00
Medium	Work In Progress				1/24/2008 8:22:20 AM				
Orozco, Danny		Sink to kitchen area is cracked. (Where pots and pans are washed)							
Johnny Acuna									
31171					2/1/2008		4		\$0.00
Medium	Work In Progress				2/1/2008 2:01:22 PM				
Ontiveros, Joe		sinck On teacher longe esta tapado							
Juan Vargas									
30325					1/6/2008	1/14/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:29:07 AM				
Acuna, Johnny		Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

30365					1/6/2008	1/14/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:24 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acuna, Johnny Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PMSchedule details.

Margret Villalobos

30577		Classroom			1/14/2008		22		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	101			1/14/2008 7:51:37 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny need key for cabinet, teacher misplaced cabinet key and cannot open it. See Ms. Ledesma

Jennifer Corral

30721	2001 Classroom	Classroom			1/17/2008		19		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	220			1/17/2008 9:19:23 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny Chaparral Elementary: (Emergency Health Issue)- Need to replace Restroom Door Knob to Room #220 in the New Wing Area. Students remove loose handle and dump it in the toilet.

Johnny Acuna

30977		Custodial			1/28/2008		8		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	office			1/28/2008 1:48:11 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Lozoya, Manny need extra master keys for head custodian/ please see front office. as soon as possible

Jennifer Corral

31194					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:33 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PMSchedule details.

Margret Villalobos

31234					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:50 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PMSchedule details.

Margret Villalobos

31241					2/3/2008	2/9/2008	2		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:52 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan Monthly - Chaparral ES Monthly FE Inspection - Refer to PMSchedule details.

Margret Villalobos

31258					2/3/2008		2		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Jacquez, Ricardo Monthly - Chaparral ES-Wastewater Weed Control - Refer to PMSchedule details.

Margret Villalobos

2/5/2008 6:09:34 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

Count: 50 Work Orders Avg. Age of WO's 99 Total for Chaparral ES 0 \$0.00

Location: Chaparral HS

26039 8/20/2007 169 \$0.00

Medium Work In Progress 8/20/2007 1:26:06 PM

Boyd, David WARRANTY WO. NEED CRANK FOR ROLL UP CURTAIN AT THE CONCESSION STAND.

Eddie Baeza

26040 8/20/2007 169 \$0.00

Medium Work In Progress 8/20/2007 1:29:14 PM

Boyd, David WARRANTY WO. TRANSITION STRIPS IN KITCHEN FLOORS ARE COMING LOOSE.

Eddie Baeza

26041 8/20/2007 169 \$0.00

Medium Work In Progress 8/20/2007 1:32:07 PM

Boyd, David WARRANTY WO. E-WING COMPUTER LAB HOLE IN WALL UNDER BULLETIN BOARD.

Eddie Baeza

26043 8/20/2007 169 \$0.00

Medium Work In Progress 8/20/2007 1:36:10 PM

Boyd, David WARRANTY WO. VENT UNCOVERED IN CEILING. UNFINISHED HOLE IN WALL COUNCELORS OFFICE. (BARNETT)

Eddie Baeza

26045 8/20/2007 169 \$0.00

Medium Work In Progress 8/20/2007 1:38:33 PM

Boyd, David WARRANTY WO PAPER LEFT IN LIGHT FIXTURE IN COUNCELORS OFFICE.

Eddie Baeza

24434 7/1/2007 8/1/2007 219 \$0.00

Medium Work In Progress 7/1/2007 12:15:59 AM

Villalobos, David Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24435 7/1/2007 8/1/2007 219 \$0.00

Medium Work In Progress 7/1/2007 12:15:59 AM

Villalobos, David Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

24436					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:00 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24884					7/18/2007		202		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/18/2007 3:38:37 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny PLEASE ISSUE A "B" KEY TO SERGIO SANDOVAL.
(HEAD CUSTODIAN)

Jesus Estrada

25084		Cafeteria			7/25/2007		195		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	CHAPARRAL			7/25/2007 3:56:01 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Lozoya, Manny AS PER MR. GIOVAS-NEEDS A TEMP LOCK ON THE CAFETERIA DOOR BEFORE MONDAY JULY 30TH.
(DELIVERY OF FOOD WILL COME IN ON MONDAY & NEEDS TO HAVE A LOCK.)

Mary Garcia

25501					8/6/2007		183		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

High	Work In Progress				8/6/2007 10:51:33 AM				
------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny we need 3 sets of keys for the custodial personnel at Chaparral High.

Jesus Estrada

25662					8/9/2007		180		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress	CHAPARRAL			8/9/2007 11:09:54 AM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Ronquillo, Ruben AS PER MR. DIGGS-FOR BIKE RACKS TO BE INSTALLED AT CHAPARRAL HIGH SCHOOL TO ACCCOMMODATE HIS STUDENTS. (CALL MR. DIGGS FIRST BEFORE ORDERING OR PLACING THEM.) APPROVED AS PER MR. CHAVEZ. MIKE, PLEASE FOLLOW UP ON THIS. THANKS
8/13 - Asp Mike route to Ruben for cost.

Mary Garcia

25873		Lift Station			8/15/2007		174		\$0.00
-------	--	--------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/15/2007 8:08:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Need 3 locks for lift station at chap High school thanks

Ricardo Jacquez

26036					8/20/2007		169		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:18:09 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. D-WING COMPUTOR RM.
CHANGE STORE RM. LOCK TO CLASS RM.LOCK

Eddie Baeza

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

26038					8/20/2007		169		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:24:09 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. (7) MULLENS ON EXTERIOR DOORS MISSING PLATES,ADJUST CYL. SO CORE CAN BE IN LOCKED POSITION.

Eddie Baeza

26046					8/20/2007		169		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:45:56 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. F-WING COMPUTER LAB 2 HOLES IN WALL NEXT TO TV STAND, HOLES NEAR OUTLETS, MISSING PAINT BETWEEN GLASS BLOCKS, CEILING TILES MISSING.

Eddie Baeza

26047					8/20/2007		169		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:49:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. RM. D-1 WALL OUTLET NOT COMPLETED, STAIN ON CEILING TILE, CEILING TILES MISSING.

Eddie Baeza

26048					8/20/2007		169		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:51:57 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. BAND RM. OUTLETS HAVE NOT BEEN COVERED AND WIRES ARE STICKING OUT.

Eddie Baeza

26049					8/20/2007		169		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:54:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. CEILING TILES MISSING THRU OUT CAMPUS.

Eddie Baeza

26050					8/20/2007		169		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:56:27 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRAFNTY WO. RMB-6 CHIPPED PAINT ON A/C VENT.

Eddie Baeza

26051					8/20/2007		169		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:59:36 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. RM. C-3 DOOR ON STORAGE CABINET CANNOT OPEN ALL THE WAY DUE TO T-STAT COVER.

Eddie Baeza

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
26052					8/20/2007		169		\$0.00
Medium	Work In Progress				8/20/2007 2:04:24 PM				
Boyd, David		WARRANTY WO. RM. F-7 WATER STAINS ON CEILING TILES.							
Eddie Baeza									
26053					8/20/2007		169		\$0.00
Medium	Work In Progress				8/20/2007 2:07:05 PM				
Boyd, David		WARRANTY WO. LIBRARY CONFERENCE RM. JHOLE IN NORTH WALL. ELECTRICAL OUTLETS DO NOT WORK.							
Eddie Baeza									
26054					8/20/2007		169		\$0.00
Medium	Work In Progress				8/20/2007 2:11:34 PM				
Boyd, David		WARRANTY WO. B-SPED NEED HOOK UP FOR WASHER, NEED HOOK UP DRIER.NEED HOOKUP FOR STOVE. HOOK UP FOR DISHWASHER.							
Eddie Baeza									
26055					8/20/2007		169		\$0.00
Medium	Work In Progress				8/20/2007 2:13:14 PM				
Boyd, David		WARRANTY WO. WEST SCORE BOARD IN GYM NOT WORKING.							
Eddie Baeza									
26056					8/20/2007		169		\$0.00
Medium	Work In Progress				8/20/2007 2:16:29 PM				
Boyd, David		WARRANTY WO. BLEACHERS IN GYM NEED TO HAVE 120 VOLT, AND PA RECEPTALS AT THE BLEACHERS							
Eddie Baeza									
26057					8/20/2007		169		\$0.00
Medium	Work In Progress				8/20/2007 2:22:33 PM				
Boyd, David		WARRANTY WO FIRE PUMP NEEDS TO BE PROGRAMMED SO THAT IT WILL SHUT OFF AUTOMATICALLY. ALSO EVERY TIME IT STARTS IT CALLS THE FIRE DEPT.							
Eddie Baeza									
26073					8/21/2007		168		\$0.00
Medium	Work In Progress				8/21/2007 9:06:31 AM				
Lozoya, Manny		OUT ATHLETIC COORDINATOR, FERNANDO SANCHEZ, NEEDS A MASTER KEY A.S.A.P.							
Rosa Quezada									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
26275	A-Wing	Office			8/27/2007		162		\$0.00
Medium	Work In Progress	FRONT OFFICE			8/27/2007 9:45:20 AM				
Lozoya, Manny		COMPUTER LAB B-WING - MR. DIGGS NEEDS A KEY CT NEED 9 FIRE ALARMS KEYS 17021 FOR FRONT OFFICE NEED 5 CH-10 KEYS FOR SECURITY OFFICE NEED 5 TRASH COMPACTER KEYS							
Rosa Quezada									
26400					8/29/2007		160		\$0.00
Medium	Work In Progress				8/29/2007 9:46:51 AM				
Carrasco, Danny		Danny need to conduct inventory of all Bldg Mechanic tools and equipment. Ask Ruben for present inventory list to match up.							
Michael Munoz									
26638					9/2/2007	9/3/2007	156		\$0.00
Medium	Work In Progress				9/2/2007 12:16:49 AM				
Quinones, Paul		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
26639					9/2/2007	9/3/2007	156		\$0.00
Medium	Work In Progress				9/2/2007 12:16:50 AM				
Quinones, Paul		Monthly - Chaparral HS Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
26642					9/2/2007	9/10/2007	156		\$0.00
Medium	Work In Progress				9/2/2007 12:16:51 AM				
Quinones, Paul		Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
26822					9/7/2007		151		\$0.00
Medium	Work In Progress	OUTSIDE HOSE			9/7/2007 4:33:14 PM				
Lozoya, Manny		NEED 8 KEYS FOR OUTSIDE HOSE BIBS, AS PER EDDIE BAEZA							
Rosa Quezada									
26823		Cafeteria			9/7/2007		151		\$0.00
Medium	Work In Progress	SNP MANAGER			9/7/2007 4:34:11 PM				
Lara, Ralph		JUANITA MONTELONGO NEEDS A NAME TAG FOR HER OFFICE SNP MANAGER							
Rosa Quezada									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

26640 9/2/2007 9/3/2007 156 \$0.00

Medium Work In Progress 9/2/2007 12:16:50 AM

Quinones, Paul Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

26821 9/7/2007 151 \$0.00

Medium Work In Progress BAND ROOM 9/7/2007 4:31:33 PM

Lozoya, Manny RESTROOMS - LOCKS SHOULD BE CHANGED BECAUSE STUDENTS CAN LOCK THE DOOR FROM THE INSIDE AND IT SHOULDN'T BE THE CASE. GIRLS DOOR WON'T LOCK EITHER. ALSO, THE BATHROOM NEEDS BOYS AND GIRLS SIGNS POSTED ONT THE DOORS

Rosa Quezada

26941 9/12/2007 146 \$0.00

Medium Work In Progress gym 9/12/2007 2:15:46 PM

Lozoya, Manny please rekey the ch1 key to a ch86 to fit the custodial door on the northwest end of the gym.

Rosa Quezada

26943 B-Wing 9/12/2007 146 \$0.00

Medium Work In Progress B-2 9/12/2007 2:26:44 PM

Lozoya, Manny COACH YTURRALDE NEEDS A KEY (CH32) TO ACCESS WASHER AND DRYER FOR FOOTBALL

Rosa Quezada

26964 C-Wing 9/12/2007 146 \$0.00

Medium Work In Progress sped room 9/12/2007 3:55:48 PM

Lozoya, Manny need ch32 to open door - need two keys - one for teacher and one for spare

Rosa Quezada

26965 Gym 9/12/2007 146 \$0.00

Medium Work In Progress gym 9/12/2007 3:57:05 PM

Lozoya, Manny need 4 keys off the GM1 master for coaches, Nougues, Yturralde, and Ulibarri and one for spare

Rosa Quezada

26967 C-Wing Classroom 9/12/2007 146 \$0.00

Medium Work In Progress sped - c wing 9/12/2007 3:59:24 PM

Lozoya, Manny please change order # 26964 previously entered to ch45 (2 keys) instead of ch32 - my mistake

Rosa Quezada

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

27280					9/21/2007		137		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/21/2007 2:11:32 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Baeza, Eddie		9-19-07				9/19 -8			
--------------	--	---------	--	--	--	---------	--	--	--

1.5 HRS CFHECK ALL SYSTEMS
6.5 HRS REMOVE CONSTRUCTION REMNANTS
FROM WEIGHT RM. TO MAINT STORAGE

Eddie Baeza

27283					9/21/2007		137		\$50.00
-------	--	--	--	--	-----------	--	-----	--	---------

Medium	Work In Progress				9/21/2007 2:17:52 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Margret		MOUSE TRAPS ARE REQUESTED FOR ALL COPIER RMS.				FAXED PO 10/9/07			
---------------------	--	--	--	--	--	------------------	--	--	--

Eddie Baeza

27410					9/25/2007		133		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/25/2007 2:10:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		Chaparral High School: Requesting Lobo Lane Fenceline be treated with arsenal and round up. Need motorized sprayer to spray on fenceline. All weeds are cut and raked. Thank You...							
----------------------	--	---	--	--	--	--	--	--	--

Johnny Acuna

28047					10/11/2007		117		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/11/2007 9:53:40 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Margret		AN EXTERMINATOR IS REQUESTED FOR PEST IN ROOM C-6.							
---------------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

28146		Custodial			10/15/2007		113		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/15/2007 3:16:11 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

		Need a set of tools and drill motor for various jobs that pop up				ON HOLD AS PER CHUY			
--	--	---	--	--	--	---------------------	--	--	--

Arthur Contreras

28271					10/18/2007		110		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/18/2007 1:50:07 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Margret		AN EXTERMINATOR IS REQUESTED TO GET RID OF RODENTS.							
---------------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

28641					10/30/2007		98		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/30/2007 7:46:46 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Boyd, David		#1 UNIT IN THE CAFETERIA IS TRIPPING THE CONTROL TRANSFORMER SEEMS LIKE A DIRECT SHORT							
-------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

28837	C-Wing				11/2/2007		95		\$0.00
-------	--------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	c-4			11/2/2007 2:27:46 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny
NEED A SET OF D156AR KEYS (CABINET) FOR HALLEY WOODS AT C-4

Rosa Quezada

29166		Cafeteria			11/13/2007		84		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 1:26:01 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Margret
BAD ANT PROBLEM BY THE TRAY ROOM

JUANA MONTELONGO - SNP MANAGER 824-4461

Alma Terrell

29213					11/14/2007		83		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/14/2007 11:07:12				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny
STORAGE RM IN THE CAREER CENTER NEEDS TO BE REKEYED OFF MASTER, AND 4 KEYS ARE NEEDED

Eddie Baeza

31256					2/3/2008		2		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Baeza, Eddie
Monthly - Chaparral HS Monthly FE Inspection - Refer to PMschedule details.

Margret Villalobos

31257					2/3/2008		2		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Baeza, Eddie
Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PMschedule details.

Margret Villalobos

29691					12/2/2007	12/23/2007	65		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:23 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny
Monthly - Chaparral HS Fire Suppression Insp. - Refer to PMschedule details.

Margret Villalobos

29748					12/3/2007		64		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/3/2007 2:28:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David
POWER NEEDS TO BE SUPPLIED TO BLEACHERS, AND PA SYSTEM

Eddie Baeza

29749					12/3/2007		64		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/3/2007 2:30:00 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
FIRE BLOCK DOORS IN THE MAIN CORRIDOR NEEDS LOCKSETS INSTALLED

Eddie Baeza

2/5/2008 6:09:34 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

29806					12/4/2007		63		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/4/2007 2:47:41 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny (1) CH-7 AND (1) CH-3 KEYS ARE REQUESTED FOR NURSE HIGGS IN THE HEALTH CENTER

Eddie Baeza

29858					12/6/2007		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				12/6/2007 7:52:44 AM	12/6/2007			
--------	------------------	--	--	--	----------------------	-----------	--	--	--

Lozoya, Manny Can we get a key to the gate for the compactor at Chaparral High School. Please let me know when the key is ready and I will go by and pick it up.

Juliet Parra

29952		Library			12/10/2007		57		\$0.00
-------	--	---------	--	--	------------	--	----	--	--------

Medium	Work In Progress	LIBRARY			12/10/2007 3:37:09 PM				
--------	------------------	---------	--	--	-----------------------	--	--	--	--

Baeza, Eddie PUT LETTERS ON WALL FOR "NON FICTION" "SPANISH" AND "CAREERS" - HANG UP SOLAR PICTURES GIVEN TO CHS FROM NASA. (I.GARCIA)

Rosa Quezada

29953		Gym			12/10/2007		57		\$0.00
-------	--	-----	--	--	------------	--	----	--	--------

Medium	Work In Progress	GYM			12/10/2007 3:38:16 PM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lozoya, Manny NEED A KEY TO RETRACT THE SIDE BASKETS IN THE GYM (F.SANCHEZ)

Rosa Quezada

29954		Classroom			12/10/2007		57		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	SECRETARY			12/10/2007 3:39:28 PM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Lozoya, Manny NEED A WA (LIFT STATION GATE KEY)

Rosa Quezada

30137	A-Wing				12/17/2007		50		\$0.00
-------	--------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	RECEPTIONIST			12/17/2007 10:23:58				
--------	------------------	--------------	--	--	---------------------	--	--	--	--

Lozoya, Manny NEED COPIES OF D-264AR FOR CABINETS BEHIND RECEPTIONIST DESK (M.MEZA)

Rosa Quezada

30138		Gym			12/17/2007		50		\$0.00
-------	--	-----	--	--	------------	--	----	--	--------

Medium	Work In Progress	OFFICE			12/17/2007 10:25:42				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Lozoya, Manny NEED A KEY FOR CABINET IN P.E. OFFICE FOR COACH YTURRALDE A.S.A.P.

Rosa Quezada

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

30485 Office 1/10/2008 26 \$0.00
 Medium Work In Progress MAINTENANCE 1/10/2008 2:19:49 PM
 Lozoya, Manny NEED A C-T KEY FOR EDDIE BAEZA (MAINTENANCE) TO ACCESS ROOF HATCH AND A/C UNITS

Rosa Quezada
 30728 E-Wing Classroom 1/17/2008 19 \$0.00
 Medium Work In Progress E-7 1/17/2008 10:48:11 AM
 Lozoya, Manny LOCK ON TALL CABINET IN BACK OF CLASSROOM FELL OUT. NEEDS TO BE REPAIRED (SAVOIE)

Rosa Quezada
 30729 D-Wing Classroom 1/17/2008 19 \$0.00
 Medium Work In Progress D-4 1/17/2008 10:50:47 AM
 Lozoya, Manny CABINET KEYS GET STUCK - UNABLE TO LOCK)
 Rosa Quezada

30732 Classroom 1/17/2008 19 \$0.00
 Medium Work In Progress E-7 1/17/2008 10:54:33 AM
 Lozoya, Manny NEED KEY# RD025 TO OPEN CABINETS (SAVOIE)
 Rosa Quezada

30797 1/18/2008 18 \$0.00
 Medium Work In Progress 1/18/2008 1:22:35 PM
 Munoz, Michael Neet to install 8ft gate for PNM. 1/18/08 (Fax to Academy Fence)
 David Boyd

30805 Gym 1/18/2008 18 \$0.00
 High Work In Progress 1/18/2008 3:26:09 PM
 Baeza, Eddie 6 breakaway goals where purchsaed for courts. 2 have been installed, please install the remaining 4 and return to the physical plant. THXS

Michael Munoz
 30867 1/23/2008 13 \$0.00
 Medium Work In Progress 1/23/2008 12:00:32 PM
 Lozoya, Manny DOOR AT THE ATTENDANCE OFFICE WILL NOT STAY UNLOCKED.
 Eddie Baeza

30868 1/23/2008 13 \$0.00
 Medium Work In Progress 1/23/2008 12:01:28 PM
 Lozoya, Manny DOOR AT THE CAREER CENTER WILL NOT STAY UNLOCKED
 Eddie Baeza

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

31167					2/1/2008		4		\$0.00
Medium	Work In Progress				2/1/2008 10:18:36 AM				
Lozoya, Manny		A CH-1 CORE IS REQUESTED FOR THE ROOF HATCH AAT THE B-WING.							
Eddie Baeza									

31255					2/3/2008		2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:57 AM				
Baeza, Eddie		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									

30954		Athletic Field			1/25/2008		11		\$0.00
Medium	Work In Progress				1/25/2008 11:25:04 AM				
Ontiveros, Guadalupe		please disc and re-level 2 areas for softball and baseball as per Mr. chavez.							
Thxs									
Michael Munoz									

31011	E-Wing	Classroom			1/29/2008		7		\$0.00
Medium	Work In Progress	E-3			1/29/2008 9:17:45 AM				
Lozoya, Manny		NEED A CH-12 TO OPEN THE WEIGHTLIFTING ROOM FOR HIS CLASS (DIOSDADO)							
Rosa Quezada									

31050		Cafeteria			1/30/2008		6		\$0.00
Medium	Work In Progress	Kitchen			1/30/2008 8:50:54 AM				
Baeza, Eddie		As per Pest Control need to redo door kitchen entry from exterior 1/2 - 1in cap under door.							
Margret Villalobos									

31283					2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 7:49:29 AM				
Munoz, Michael		need gate where gas meter and regulators are at as per d.boyd and pnm.(testing of regulators)							
Michael Munoz									

Count: 78 Work Orders Avg. Age of WO's 114 Total for Chaparral HS 0 \$50.00

Location: Chaparral MS

24411					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:56 AM				
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

24412					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24413					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24707		Cafeteria			7/11/2007		209		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/11/2007 2:27:07 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Walk-In Freezer was at 19 degrees (6:30 a.m.) and now it is at 30 degrees (9:30 a.m.) left message on Danny's cell phone

Paula Sanchez - SNP Manager 824-4376

Alma Terrell

24955					7/20/2007		200		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/20/2007 9:37:06 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny locker room door need fix not lock

Juan Vargas

25624					8/8/2007		181		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/8/2007 3:09:08 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny door on stage need change lock

Juan Vargas

25697		Portables			8/9/2007		180		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	P-10, room 312,			8/9/2007 3:58:38 PM				
--------	------------------	-----------------	--	--	---------------------	--	--	--	--

Lozoya, Manny Need file cabinets for P-10 / Mr. Rueda and room 306 Mr. De La Torre to be rekeyed. Need door key for Room 312 Mr. Montano.

Elena Palacios

25703					8/10/2007		179		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/10/2007 7:52:40 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny I NEED A KEY MADE FOR A FILING CABINET THAT I WILL BE USING TO STORE CONFIDENTIAL INFORMATION.

Robert Gonzalez

25924		Classroom			8/16/2007		173		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Room 107			8/16/2007 10:26:42 AM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Lozoya, Manny lock on door is faulty. cannot lock or unlock properly

Elena Palacios

2/5/2008 6:09:34 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

26037 8/20/2007 169 \$0.00

Medium Work In Progress 8/20/2007 1:20:23 PM

Boyd, David WARRANTY WO. DEADBOLTS NEED TO BE REPLACED IN ALL REST RMS.

Eddie Baeza

26140 Classroom 8/22/2007 167 \$0.00

Medium Work In Progress Science Room 8/22/2007 10:34:43 AM

Lozoya, Manny Need two more sets of keys for the science storage room in 308 for Mr. Turner and Mrs. Zamora

Elena Palacios

26142 Classroom 8/22/2007 167 \$0.00

Medium Work In Progress Room 311 8/22/2007 11:08:39 AM

Lozoya, Manny Need new file cabinet keymade. Cabinet was in storage and now is being used.

Elena Palacios

26195 8/23/2007 166 \$0.00

Medium Work In Progress 8/23/2007 2:20:41 PM

Lozoya, Manny room 302 need fix door lock not closed

Juan Vargas

26196 8/23/2007 166 \$0.00

Medium Work In Progress 8/23/2007 2:23:51 PM

Lozoya, Manny portable # 14 need fix door lock

Juan Vargas

26385 8/29/2007 160 \$160.00

Medium Work In Progress 8/29/2007 7:44:03 AM

Sotelo, Enrique THE LIGHT POLE LIGHTS THAT ARE ON THE POND TURN OFF VERY EARLY TURN BACK ON THAN TURN OFF AGAIN RIGHT AWAY.

Robert Gonzalez

26938 Cafeteria 9/12/2007 146 \$0.00

Medium Work In Progress 9/12/2007 1:25:18 PM

Orozco, Danny Bottom Oven is not heating. Both warmers are taking to long to reach 140 degrees or higher. Warmers have been on since 6:00 a.m. this morning and by 10:44 am it is at 140 degrees but, as soon as they put something in the warmers the temperature drops down real fast.

Sandra Diaz- SNP Manager 8244376

Alma Terrell

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

27016		Cafeteria			9/14/2007		144		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/14/2007 10:28:25 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny DRYER: HARD TO TURN ON AND TAKES SEVERAL CYCLES TO DRY

SANDRA DIAZ SNP MGR 824-4376

Jacqueline Aguilar

27127					9/18/2007		140		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/18/2007 11:19:23 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny we need to change the lock from 405A to 405B and 405B TO 405A. we have computers in room 405A and we do not want people with the A master key to be able to go in there.

Robert Gonzalez

27255					9/21/2007		137		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/21/2007 7:27:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny girls locker room door that leads to the back girls sports locker room is hard to open and lock. choach ramos would like a dead bolt put on there if possible.

Robert Gonzalez

28403					10/23/2007		105		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 11:05:45				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe Repair sprinkler valve and sprinkler system on th NW end.

Michael Munoz

29159		Cafeteria			11/13/2007		84		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 10:39:04				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny BOTTOM BLODGETT OVEN IS STILL NOT WORKING (NEED TO COOK TURKEY ASAP - PLEASE)

SANDRA DIAZ - SNP MANAGER 824-4379

Alma Terrell

29160		Cafeteria			11/13/2007		84		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 10:43:09				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny CLOTHES DRYER IS NO LONGER WORKING PROPERLY

SANDRA DIAZ - SNP MANAGER 824-4376

Alma Terrell

29162					11/13/2007		84		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 12:00:17				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny need replace step on foot lever water for kitchen sink
Juan Vargas

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

29167		Cafeteria			11/13/2007		84		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 1:47:21 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny the floor peddle to the sink broke off. (unable to use at all)

Sandra Diaz -SNP Mgr 824-4376

Jacqueline Aguilar

29496					11/28/2007		69		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/28/2007 9:00:06 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique gym. need replace lamp and acrylic refractor

Juan Vargas

29734					12/3/2007		64		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/3/2007 11:39:29 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe EMERGENCY NEED FIX WATER LEAK IRRIGATE 2 INCHES PVC PIPE ON SCHOOL BUSSES PARKING

Juan Vargas

30023		Classroom			12/12/2007		55		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	ROOM 205			12/12/2007 10:15:38				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Lozoya, Manny MR. ALVA NEEDS HIS LOCK BACK ON HIS CABINET. LOCKS WERE TAKEN TO MAKE KEYS AND NEVER PUT BACK ON.

Elena Palacios

30024		Classroom			12/12/2007		55		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	ROOM 106			12/12/2007 10:17:12				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Lozoya, Manny MR. RAMOS NEEDS HIS FILE CABINETS (2) REKEYED THEYRE LOCKED NOW.

Elena Palacios

30028		Classroom			12/12/2007		55		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	ROOM 305			12/12/2007 10:22:55				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Lozoya, Manny MRS. KROL NEEDS A CABINET REKEYED. CANNOT CLOSE OR LOCK IT AT THE TIME

Elena Palacios

30303					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly- Chapparal MS Range Hood Cleaning - Refer to PMs schedule details.

Margret Villalobos

30645					1/15/2008		21		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Lounge			1/15/2008 1:47:47 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Estrada, Jesus Re-carpet lounge during Spring Break.

Michael Munoz

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

31187					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:30 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Medina, Eric Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.

Margret Villalobos

31295		Gym			2/5/2008		-60		\$0.00
-------	--	-----	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/5/2008 9:00:35 AM	12/7/2007			
--------	------------------	--	--	--	---------------------	-----------	--	--	--

Lozoya, Manny boys and grls. lockers rooms need replace partitions.

Juan Vargas

30296					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

30934		Gym			1/24/2008		12		\$0.00
-------	--	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/24/2008 3:21:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique We are going to need electrical outlets installed at Chaparral Middle IDF (Gym). We have currently extended electrical using 15' power strips, but need the outlets relocated closer to the cabinets contact Silver.

Cora Ramirez

31062					1/30/2008		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 11:06:11 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Michael Fire sprinkler system (pump area) inside the mechanical room is leaking badly. There is water ponding on concrete floor. Please Fix A/S/A/P

Johnny Acuna

31063					1/30/2008		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 11:14:48 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique Chaparral Middle School: There will be a concrete sidewalk poured in the athletic field. Contractor needs a line locate in the field. Please contact Eric Medina (Bldg. Mech.-Ch. Mid) for more details.

Johnny Acuna

31064					1/30/2008		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 11:15:47 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenzo Need a coupling connector for Boiler system water pump in the mechanical Room.

Johnny Acuna

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral MS							
31065					1/30/2008		6		\$0.00
Medium	Work In Progress				1/30/2008 11:20:31 AM				
Ontiveros, Joe		Chaparral Middle School: There will be a concrete sidewalk poured in the athletic field. Contractor needs a line locate in the field. Please contact Eric Medina (Bldg. Mech.-Ch. Mid) for more details.							
Johnny Acuna									
31196					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:33 AM				
Medina, Eric		Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
31198					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:34 AM				
Medina, Eric		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
31242					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:53 AM				
Medina, Eric		Monthly - Chaparral MS Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
31267					2/4/2008		1		\$0.00
Medium	Work In Progress				2/4/2008 1:15:01 PM				
Carbajal, Jimmy		we have a burnisher (advance plus 20) that is making a lot of noise and the motor is loose. we would like to exchange it for another one if possible.							
Robert Gonzalez									
31268					2/4/2008		1		\$0.00
Medium	Work In Progress				2/4/2008 1:20:13 PM				
Hernandez, Guillermo		we are going to need three 55 gal barrels to use as trash cans. for our new shaded patio thats being build. Chuy is aware of this. thanks							
Robert Gonzalez									

Count: 44 Work Orders Avg. Age of WO's 94 Total for Chaparral MS 0 \$160.00

Location:		Desert Pride							
25066		Classroom			7/25/2007		195		\$0.00
Medium	Work In Progress	5,6,8,11.			7/25/2007 10:43:54 AM				
Castillo, Carlos		rooms 5,6,8,11 some of the light fixtures ballast need replacing.							
David Acosta									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Desert Pride
------------------	---------------------

25399					8/3/2007		186		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress	Security			8/3/2007 2:36:23 PM				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Lozoya, Manny
I need a master key and an allen wrench for one of our Security Guards, Ms. Saucedo.

Mary Telles

25834		Office			8/14/2007		175		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/14/2007 8:32:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
need one master key for new security guard.

David Acosta

26455					8/30/2007		159		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	storage building			8/30/2007 12:55:10 PM				
--------	------------------	------------------	--	--	-----------------------	--	--	--	--

Miranda, Danny
storage building- a good size of the ceiling (sheetrock) came down and a light fixture is hanging lose toward the back end of building
Routed to Danny asp Mike 8/31 -mkv

David Acosta

28014					10/10/2007		118		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/10/2007 8:46:19 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
NEED TO LEVEL OUT BUS TURN AROUND AND TEACHERS PARKING LOT.

Guadalupe Ontiveros

28788		Restroom (Girls)			11/1/2007		96		\$0.00
-------	--	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	front office			11/1/2007 10:12:05 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Appelzoller, Fred
Need an ADA toilet installed in the restroom in the front office.

Mary Telles

30473		Classroom			1/10/2008		26		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	11			1/10/2008 1:15:38 PM				
--------	------------------	----	--	--	----------------------	--	--	--	--

Castillo, Carlos
TWO LIGHT FIXTURES NEED NEW BALLAST (BURN OUT)

Mary Telles

30907		Hallway/Corridor			1/24/2008		12		\$0.00
-------	--	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	2ND BUILDING			1/24/2008 10:47:48 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Castillo, Carlos
EMERGENCY LIGHTS WON'T GO ON IN ENTRANCE HALLWAY

David Acosta

30920		Portables			1/24/2008		12		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	6 & 7			1/24/2008 2:00:01 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Castillo, Carlos
ROOMS 6 & 7 NEEDS INDIVIDUAL LIGHT SWITCH TO TURN ON LIGHTS TO THEIR ROOMS. (LAST PORTABLE)

David Acosta

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Pride

31189					2/3/2008	2/9/2008	2		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:31 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acosta, David Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

31199					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acosta, David Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

31203					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acosta, David Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

31306		Portables			2/5/2008		0		\$0.00
-------	--	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	2			2/5/2008 11:01:24 AM				
--------	------------------	---	--	--	----------------------	--	--	--	--

Ambriz, Jose NEED TO REPLACE THERMOSTAT.

David Acosta

31308		Library			2/5/2008		0		\$0.00
-------	--	---------	--	--	----------	--	---	--	--------

Medium	Work In Progress	THIRD BUILDING			2/5/2008 11:18:45 AM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe NEED MORE DIRT IN BETWEEN LIBRARY AND STORAGE BUILDING. ALSO NEED A LOAD DIRT TO FILL IN GROUND BY CORNER OF RAMP (LAST PORTABLE) .

David Acosta

Count: 14 Work Orders			Avg. Age of WO's 70			Total for Desert Pride	0		\$0.00
------------------------------	--	--	----------------------------	--	--	-------------------------------	----------	--	---------------

Location: Desert Trail Intermediate

24362					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:47 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24363					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:47 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Desert Trail Intermediate							
24364					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:48 AM				
Villalobos, David		Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24662					7/10/2007		210		\$0.00
Medium	Work In Progress				7/10/2007 12:42:45 PM				
Ontiveros, Joe		Need a 1" threaded female cap for pvc pipe in the playground area.							
Johnny Acuna									
24805	Main Building	Custodial			7/16/2007		204		\$0.00
Medium	Work In Progress				7/16/2007 2:34:30 PM				
Lozoya, Manny		Por favor. llaves para un escritorio . llaves para un gabinete.cuarto #113. Gracias.							
Marisela Torres									
24900		Custodial			7/19/2007		201		\$0.00
Medium	Work In Progress				7/19/2007 9:01:32 AM				
Lozoya, Manny		Urgente. cambiar las chapas del cuarto 408. nueva chapa para cuarto 201. cambiar chapa de storage. Gracias							
Marisela Torres									
24913		Classroom			7/19/2007		201		\$0.00
Medium	Work In Progress				7/19/2007 1:16:31 PM				
Lozoya, Manny		3 candados para gabinetes cuarto 113.							
Marisela Torres									
25769					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 11:25:24 AM				
Lozoya, Manny		need to install restroom doorknob to portable #408.							
Johnny Acuna									
26241		Classroom			8/24/2007		165		\$0.00
Medium	Work In Progress	RM#115			8/24/2007 2:15:17 PM				
Lozoya, Manny		MR. FERGUSON RM#115 HIS DOOR LOCK DOES NOT WORK							
Elizabeth Hernandez									
28408					10/23/2007		105		\$0.00
Medium	Work In Progress				10/23/2007 11:13:37				
Acuna, Johnny		Digout grass around wells in trees.							
Michael Munoz									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail Intermediate							
25017		Classroom			7/24/2007		196		\$0.00
Medium	Work In Progress				7/24/2007 9:05:54 AM				
Lozoya, Manny		una llave para el cuarto 408 la que tiene el maestro no abre .gracias.							
Marisela Torres									
25133		Classroom			7/26/2007		194		\$0.00
Medium	Work In Progress				7/26/2007 3:58:52 PM				
Lozoya, Manny		Need keys made for (Portable #408, 409) and (classrooms #118, 212). Attn: Blanca (Front Office).							
Johnny Acuna									
25347		Cafeteria			8/2/2007		187		\$0.00
Medium	Work In Progress				8/2/2007 1:47:59 PM				
Orozco, Danny		Kitchen: Washroom Door Frame needs to be replaced. Door Frame is corroded on the bottom.							
Johnny Acuna									
25393		Cafeteria			8/3/2007		186		\$0.00
Medium	Work In Progress				8/3/2007 2:13:27 PM				
Orozco, Danny		WATER IS COMING OUT FROM UNDERNEATH THE WASHING MACHINE							
		PATRICIA CISNEROS - SNP MANAGER 824-3822							
Alma Terrell									
25496		Portables			8/6/2007		183		\$0.00
Medium	Work In Progress	415			8/6/2007 10:24:51 AM				
Lozoya, Manny		Need to fix or Replace Doorknob to main door on portable#415. Doorknob sometimes slips through the inside when trying to open from the inside. (Loose from the inside).							
Johnny Acuna									
25770					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 11:27:51 AM				
Lozoya, Manny		Room #113: 1 large filing cabinet needs a lock (student records), and 3 sets of kitchen cabinet doors need locks. (Parent Liason Room)							
Johnny Acuna									
25836					8/14/2007		175		\$0.00
Medium	Work In Progress				8/14/2007 9:32:52 AM				
Lozoya, Manny		Liz (Front office) requesting 2 locks installed in the workroom cabinets of the kinder hall.							
Johnny Acuna									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail Intermediate

25947 8/16/2007 173 \$0.00

Medium Work In Progress 8/16/2007 4:07:59 PM

Sotelo, Enrique Need help in checking Marquee lighting.
Only half of marquee turns on at night.

Johnny Acuna

26079 Classroom 8/21/2007 168 \$0.00

Medium Work In Progress # 212 8/21/2007 10:42:00 AM

Sotelo, Enrique Strong burned electrical smell inside classroom #212
(main bldg.)Checked A/C system (New motor and
waterpump: No Burned Smell). Need help in
troubleshooting electrical circuits to classroom #212.

Johnny Acuna

26689 9/5/2007 153 \$0.00

Medium Work In Progress 9/5/2007 1:18:39 PM

Lozoya, Manny Need to check Custodial J-Master Key. Key does not
open doorknob lock to portable #415 for her to clean
classroom during her working hours.

Johnny Acuna

26782 9/7/2007 151 \$0.00

Medium Work In Progress 9/7/2007 8:57:11 AM

Lozoya, Manny Custodial Dept. requesting a lock for filing cabinet in the
custodial / maintenance office.

Johnny Acuna

26788 9/7/2007 151 \$0.00

Medium Work In Progress 9/7/2007 10:28:19 AM

Sotelo, Enrique Need to replace (2) Ballasts for Outdoor security light
poles. *-light next to storage shed. *-Light in back of
portables closest to grass area:Also for this light pole
need to replace broken light cover.

Johnny Acuna

26789 9/7/2007 151 \$0.00

Medium Work In Progress 9/7/2007 10:53:19 AM

Sotelo, Enrique Please check lighting to marquee. Only half of the
marquee
turns on at night.

Johnny Acuna

27020 9/14/2007 144 \$0.00

Medium Work In Progress 9/14/2007 10:48:38 AM

Munoz, Michael Need to replace VCT in the kitchen laundry room. VCT
is cracked and faded out. If possible, replace with skid
resistant type. Thank You.

Johnny Acuna

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail Intermediate

28406					10/23/2007		105		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 11:10:46				
--------	------------------	--	--	--	---------------------	--	--	--	--

Acuna, Johnny Please connect existing sidewalk to playground ramp approx. 3 x 5 section after grounds does backfill of dirt.

Michael Munoz

28479		Custodial			10/24/2007		104		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2007 11:26:18				
--------	------------------	--	--	--	---------------------	--	--	--	--

Estrada, Jesus Me podria proporcionar un (diablito)? . Gracias. 1/11/08 - REQUESTED STATUS FROM
Marisela Torres GUILLERMO/JIMMY/CHUY????

28536					10/25/2007		103		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/25/2007 1:01:41 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Acuna, Johnny PLAYGROUND ARE-NEED CONNECTION FROM
SIDEWALK TO SURFACING FOR ADA.

Michael Munoz

28537					10/25/2007		103		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/25/2007 1:05:49 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Acuna, Johnny NOT GOOD FOR 5 YEAR OLD.- NEED SIGN FOR
6YRS AND OLDER.

Michael Munoz

28538					10/25/2007		103		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/25/2007 1:09:02 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Holguin, Ramiro FORD AND AFT SHOULD BE TWICE THE HEIGHT OF
SWING TOP FRAME.

Michael Munoz

28543		Cafeteria			10/25/2007		103		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/25/2007 1:46:11 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny Washing Machine is still out of order

Patricia Cisneros - SNP Manager 824-3822

Alma Terrell

30274					1/6/2008	1/14/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:47 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acuna, Johnny Monthly - Desert Trail Roof Inpsection - Refer to PM
schedule details.

Margret Villalobos

30297					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM
schedule details.

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail Intermediate

30304					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly- Desert Trail Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

30396		Cafeteria			1/8/2008		28		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/8/2008 2:05:00 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny Garbage Disposal is Not Working Again

Patricia Cisneros - SNP Manager 824-3822

Alma Terrell

30774					1/18/2008		18		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/18/2008 8:27:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Chaparral Elementary Kitchen: Dishwasher leaking badly during use.

Johnny Acuna

30861					1/23/2008		13		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/23/2008 10:06:45 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Need a new key for Instructional Assistant in room #118. (Key: J-36)

Johnny Acuna

31003					1/29/2008		7		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/29/2008 7:22:07 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo Replacement a/c's for portable 403/404.

Johnny Acuna

31028		Portables			1/29/2008		7		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/29/2008 2:10:40 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique Portable 413 - Need to replace exit sign asp PM30328.

Johnny Acuna

31052		Cafeteria			1/30/2008		6		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 9:42:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny SLICER IS MAKING WEIRD NOISES WHEN BLADE IS ROTATING

PATRICIA CISNEROS - SNP MANAGER 824-3822

Alma Terrell

31168					2/1/2008		4		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/1/2008 12:07:35 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique DESERT TRAIL: Need a new electrical outlet installed in the front office vault.

Johnny Acuna

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail Intermediate							
31172					2/1/2008		4		\$0.00
Medium	Work In Progress				2/1/2008 2:06:20 PM				
Solis, Lorenzo		Need an exhaust fan motor for NW wing Restroom. (Women's Restroom)							
Johnny Acuna									
31197					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:34 AM				
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
31202					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:36 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
31243					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:53 AM				
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
Count: 44 Work Orders		Avg. Age of WO's 116		Total for Desert Trail Intermediate		0		\$0.00	

Location:		Desert View ES							
27719					10/1/2007		127		\$0.00
Medium	Work In Progress				10/1/2007 11:17:58 AM				
Castillo, Carlos Patricio Aguilar		Emergency Lights need replacing as per PMWO 25451.							
29603					11/30/2007		67		\$0.00
Medium	Work In Progress				11/30/2007 3:36:02 PM				
Ontiveros, Guadalupe		pat aguilar frount drive way need chuck-holes patching repair							
Patricio Aguilar									
25196					7/30/2007		190		\$0.00
Medium	Work In Progress				7/30/2007 8:45:46 AM				
Lozoya, Manny Diana Gonzalez		need a classroom key for the new portable.							
25658		Portables			8/9/2007		180		\$0.00
Medium	Work In Progress	6			8/9/2007 9:52:41 AM				
Lozoya, Manny Diana Gonzalez		TEACHER NEEDS A KEY TO HER NEW PORTABLE.							

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
24378					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24379					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24380					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
25613		Cafeteria			8/8/2007		181		\$0.00
Medium	Work In Progress				8/8/2007 1:25:43 PM				
Orozco, Danny		OVEN IS ACTING UP. NOT HEATING.							
Jacqueline Aguilar		MARTHA FLORES: SNP MGR 589-2425							
25693					8/9/2007		180		\$0.00
Medium	Work In Progress				8/9/2007 3:49:24 PM				
Ambriz, Jose		pat aguilar a/c port 1 not working properly not cold - has new filter							
Patricio Aguilar									
26461	Main Building	Portables			8/30/2007		159		\$0.00
High	Work In Progress				8/30/2007 2:24:40 PM				
Lozoya, Manny		Cylinders in portables 1 - 5 are getting stuck so are the main entrances (outer) 3 doors are hard to open.							
Jesus Estrada									
26767					9/6/2007		152		\$0.00
Medium	Work In Progress				9/6/2007 3:44:41 PM				
Castillo, Carlos		pat aguilar 6 emer lights need replace back door dinning room gym lift side inside door left hall by frount door asspri office lift mid back hall way lift back hall way							
Patricio Aguilar									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
26796		Cafeteria			9/7/2007		151		\$0.00
Medium	Work In Progress				9/7/2007 2:49:54 PM				
Orozco, Danny		REACH-IN FREEZER IS AT 20 DEGREES, I ASKED MARTHA-SNP MANAGER, WHEN THE FREEZER STARTED ACTING UP, SHE SAID 9/6/07 IT WAS AT 20 DEGREES ALSO, SHE THOUGHT IT WAS IN THE DEFROST MODE. SHE CALLED TODAY AT 1:30 PM TO REPORT THIS WORK ORDER.							
		MARTHA FLORES - SNP MANAGER 589-2425							
Alma Terrell									
26799		Cafeteria			9/7/2007		151		\$39.99
Medium	Work In Progress				9/7/2007 2:51:38 PM				
Orozco, Danny		COLD UNIT TO SERVING LINE (LEFT SIDE) IS OUT OF ORDER							
		MARTHA FLORES - SNP MANAGER 589-2425							
Alma Terrell									
27635					9/30/2007	10/21/2007	128		\$0.00
Medium	Work In Progress				9/30/2007 12:17:39 AM				
Orozco, Danny		Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
27839	Main Building	Cafeteria			10/3/2007		125		\$0.00
Medium	Work In Progress				10/3/2007 3:53:38 PM				
Orozco, Danny		SPRAYER TO DISHWASHER IS BROKEN							
		MARTHA FLORES SNP MGR 589-242							
Jacqueline Aguilar									
28090		Cafeteria			10/12/2007		116		\$0.00
Medium	Work In Progress				10/12/2007 9:06:43 AM				
Orozco, Danny		WALK - IN REFRIG. COMPLETELY DEAD.							
		MARTHA FLORES SNP MANAGER 589-2425							
Jacqueline Aguilar									
28670		Cafeteria			10/30/2007		98		\$0.00
Medium	Work In Progress				10/30/2007 12:03:27				
Orozco, Danny		WATER HEATER NEEDS TO BE SET HIGHER. DISHMACHINE FINAL RINSE WAS AT 120 AND THE WASH AT 130, BOTH NEED TO BE HIGHER THAN 140 OR ABOVE.							
		MARTHA FLORES - SNP MANAGER 589-2425							
Alma Terrell									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Desert View ES
------------------	-----------------------

29032		Cafeteria			11/7/2007		90		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/7/2007 9:44:32 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny AS PER HEALTH INSPECTION ON 10/29/07 -- BACK
DOOR MISSING A GOOD SEAL TO PREVENT THE
ENTRY OF INSECTS AND VERMIN.

AIDA SALCEDO - SNP COMPLIANCE COORDINATOR
882-6772
MARTHA FLORES - SNP MANAGER 589-2425

Alma Terrell

29995					12/11/2007		56		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/11/2007 3:27:06 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos pat aguilar
frost incadesent lamps 8 each
dulaxs 13w compact fluorescent 10 each

Patricio Aguilar

30036					12/12/2007		55		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/12/2007 3:15:36 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Carrasco, Danny Gate chain link 4'6" H x 11'6" L Asp Mike route to Danny 1/11/08
hardware 3" pole

Patricio Aguilar

30305					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly - Desert View ES Range Hood Cleaning - Refer
to PMschedule details.

Margret Villalobos

30528		Cafeteria			1/11/2008		25		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/11/2008 11:16:16 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny Plastic Handle to Sprayer above Garbage Disposal is
broken.

Martha Flores, SNP Manager 589-2425

Jacqueline Aguilar

30602		Classroom			1/14/2008		22		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	16			1/14/2008 3:15:19 PM				
--------	------------------	----	--	--	----------------------	--	--	--	--

Lara, Ralph Teacher's door lock was changed and the classroom
key does not work.

Diana Gonzalez

30613					1/14/2008		22		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				1/14/2008 4:18:52 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph need locks installed on new gates on new buss turn
around.THXS

Michael Munoz

2/5/2008 6:09:35 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
31200					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:35 AM				
Aguilar, Patricio		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
31204					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:36 AM				
Aguilar, Patricio		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
31244					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:53 AM				
Aguilar, Patricio		Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
Count: 27 Work Orders		Avg. Age of WO's		110	Total for Desert View ES			0	\$39.99

Location:		GAC							
24381					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24382					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24383					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24815	Pre-K	Classroom			7/16/2007		204		\$0.00
Medium	Work In Progress	PRE-K			7/16/2007 4:18:02 PM				
Boyd, David		AS PER JUAN AMBRIZ-ROOF LEAKED IN 2 OF THE PRE-K CLASSROOMS.				ON HOLD UNTIL MR. BOYD LOOKS INTO THIS, TO MAKE SURE IT IS NOT UNDER WARRENTY.			
Mary Garcia									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
24816	Pre-K	Office			7/16/2007		204		\$0.00
Medium	Work In Progress	PRE K			7/16/2007 4:24:46 PM				
Lozoya, Manny		AS PER YVONNE LOZANO-NEEDS A GRAND MASTER KEY FOR PRE-K CENTER.							
Mary Garcia									
24899		Office			7/19/2007		201		\$0.00
Medium	Work In Progress	C-WING			7/19/2007 8:52:25 AM				
Lozoya, Manny		NEED A KEY #A25 FOR MANUEL LEYVA							
Mary Garcia									
24902	Pre-K	Portables			7/19/2007		201		\$0.00
Medium	Work In Progress	CHAPARRAL			7/19/2007 9:29:27 AM				
Lozoya, Manny		AS PER LUCY MESA-NEED 3 GATE KEYS AND 3 GRAND MASTER KEYS FOR ALL DOORS AND AT CHAPARRAL ELEM. WHEN COMPLETED PLEASE TURN IN TO ANN STIENOFF AS SHE WILL DISTRIBUTE. (IF YOU NEED MORE INFO. ON THIS CALL LUCY MESA @ FEDERAL PROGRAMS @ 882-6788				PERSON TO TALK W/TERESA RAMIREZ OR JUDY ATKINS			
Mary Garcia									
24918	RTC	Classroom			7/19/2007		201		\$0.00
Medium	Work In Progress	ACROSS THE			7/19/2007 2:34:45 PM				
Ontiveros, Guadalupe		AS PER GLORIA SAENZ-IF A SIDE WALK CAN BE INSTALLED BEHIND THE PORTABLE. THERE IS TO MUCH SAND FOR STUDENT TO WALK IN.				1/14 - Asp Mike route to Lupe			
Mary Garcia									
27636					9/30/2007	10/21/2007	128		\$0.00
Medium	Work In Progress				9/30/2007 12:17:39 AM				
Orozco, Danny		Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
29783					12/4/2007		63		\$0.00
Medium	Work In Progress				12/4/2007 9:36:05 AM				
Ambriz, Jose		Receptionist Area - Need to check for additional Heating and Cooling (see Mike)							
Michael Munoz									
29785					12/4/2007		63		\$0.00
Medium	Work In Progress				12/4/2007 9:43:26 AM				
Castillo, Carlos		Receptionist Area - Need additional lighting (see Mike)							
Michael Munoz									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
26058		Office			8/20/2007		169		\$0.00
Medium	Work In Progress	B-WING			8/20/2007 2:44:32 PM				
Lozoya, Manny		AS PER ANNE-THE DOOR KNOB/LOCK IN PRISCILLAS'S OFFICE DOES NOT UNLOCK, NEEDS TO BE FIXED TO WHERE IT LOCKS AND UNLOCKS.							
Mary Garcia									
26441		Cafeteria			8/30/2007		159		\$0.00
Medium	Work In Progress				8/30/2007 9:55:03 AM				
Orozco, Danny		Water leaking from garbage disposal water line area.							
		Gessica Blazquez- SNP Manager 882-6784							
Alma Terrell									
26442		Cafeteria			8/30/2007		159		\$0.00
Medium	Work In Progress				8/30/2007 10:03:59 AM				
Orozco, Danny		Please replace faucet to hand washing sink in Dishwashing Machine Area.							
		Gessica Blazquez- SNP Manager 882-6784							
Alma Terrell									
26842		Portables			9/10/2007		148		\$0.00
Medium	Work In Progress	STORAGE-MS.			9/10/2007 1:33:27 PM				
Ambriz, Juan		AS PER MS. SALINAS-THE STORAGE UNIT NEEDS ADDITIONAL SHELVING AND WOULD LIKE TO HAVE SOME INSTALLED. BILINGUAL DEPT. HAS NO MATERIALS FOR THIS, AND WOULD LIKE TO KNOW IF MAINTENANCE WOULD BE ABLE TO SUPPLY THEM WITH THE MATERIALS NEEDED.				9/19 - Asp Mike route to Juan Ambriz			
Mary Garcia									
27223	RTC	Portables			9/20/2007		138		\$0.00
Medium	Work In Progress	ACROSS THE			9/20/2007 11:46:28 AM				
Villalobos, Margret		AS PER GLORIA SAENZ-NEED TO HAVE ALL 3 PORTABLES EXTERMINATED FOR INSECTS AND MICE.							
Mary Garcia									
28141		Office			10/15/2007		113		\$0.00
Medium	Work In Progress	C-WING			10/15/2007 3:07:50 PM				
Miranda, Danny		AS PER SHEILA RAIHL-NEED TO REMOVE OBSERVATION WINDOW IN HER OFFICE.				ASP Mike route to Danny 10/25			
Mary Garcia									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC
------------------	------------

28143		Office			10/15/2007		113		\$0.00
Medium	Work In Progress	C-WING			10/15/2007 3:09:23 PM				
Miranda, Danny		AS PER MS. RAIHL-AFTER REMOVING THE WINDOW, THE WALL NEEDS TO BE TAPED/TEXTURED AND PAINTED.				10/25 - ASP Mike route to Danny M.			

Mary Garcia

29377	RTC	Stairway			11/20/2007		77		\$0.00
Medium	Work In Progress	Portable ramps			11/20/2007 3:23:11 PM				
Ambriz, Juan		As per Ms. Julie Hinojosa Ramp boards are worpped and seperated. Students tripping need to be replaced as sson as possible for Staff and Student safety							

Juan Ambriz

29423	RTC	Portables			11/26/2007		71		\$0.00
Medium	Work In Progress	ACROSS THE			11/26/2007 3:52:43 PM				
Villalobos, David		AS PER GLORIA SAENZ-THERE'S NO HOT WATER IN THE CHILDREN'S PORTABLES.							

Mary Garcia

29511		Office			11/28/2007		69		\$0.00
Medium	Work In Progress	Front lobby			11/28/2007 3:21:38 PM				
Lara, Ralph		As Per Ms. Nava need to install a door with window in front lobby with Ms. Nancy Segura							

Juan Ambriz

29535		Parking Lot			11/29/2007		68		\$0.00
Medium	Work In Progress	NEAR FRONT			11/29/2007 9:02:05 AM				
Castillo, Carlos		AS PER SELMA NEVAREZ-NIGHT LIGHTS NEAR FRONT OFFICE NEXT TO SIDE WALK ARE NOT WORKING. (AS PER SELMA THIS A SAFETY ISSUE)							

Mary Garcia

29947		Restroom (Girls)			12/10/2007		57		\$0.00
Medium	Work In Progress	A-WING			12/10/2007 1:57:17 PM				
Lara, Ralph		AS PER RAMON MARQUEZ-NEEDS FOR THE DOOR KNOB IN THE BATHROOM FIXED/LOCK IN ORDER TO STORE CUSTODIAN SUPPLIES.							

Mary Garcia

30298					1/6/2008	1/27/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:28:56 AM				
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

30319					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

30384		Office			1/8/2008		28		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	A-WING			1/8/2008 9:25:20 AM				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Lara, Ralph AS PER VICKI ARNOLD NEED AN OFFICE KEY MADE #A38

Mary Garcia

30480	Pre-K	Office			1/10/2008		26		\$0.00
-------	-------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	ROOM 202			1/10/2008 1:45:52 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Ambriz, Juan AS PER MS. BERRY-NEED TO HAVE A COAT HOOK REMOVED AND PLACE IN A DIFFERENT CLASSROOM

Mary Garcia

30698		Computer Lab			1/16/2008		20		\$0.00
-------	--	--------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/16/2008 3:30:49 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben As per Ms. Socorro need to tint windows in computer lab

Juan Ambriz

30739		Office			1/17/2008		19		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2008 11:26:45 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Estrada, Jesus The carpet in Richard Chavez office needs to be replaced. We will schedule this for spring break.

Jesus Estrada

30766		Cafeteria			1/17/2008		19		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Cafeteria Heating			1/17/2008 3:44:54 PM				
--------	------------------	-------------------	--	--	----------------------	--	--	--	--

Ambriz, Jose Need to repair heating unit in cafeteria not working properly

Juan Ambriz

30848					1/22/2008		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/22/2008 3:20:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Juan AS PER IRMA TRUJILLO-SOME OF THE LIGHTS IN CONFERENCE ROOM #2 ARE OUT AND NEED TO BE REPLACED.

Mary Garcia

30962		Parking Lot			1/25/2008		11		\$0.00
-------	--	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Back dirt road			1/25/2008 3:08:19 PM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe need to apply more crusher fine on back dirt road

Juan Ambriz

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC								
------------------	------------	--	--	--	--	--	--	--	--

30972		Hallway/Corridor			1/28/2008		8		\$0.00
-------	--	------------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	C-WING			1/28/2008 8:37:48 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Castillo, Carlos		AS PER JUAN AMBRIZ-IF POSSIBLE NEED TO HAVE A LARGER BREAKER OR MORE POWER TO THE HALLWAY WALL NEXT TO CONFERENCE ROOM #3. BREAKER KEEPS TRIPPING AND LOSES POWER TO IRMA SUAREZ OFFICE AS WELL AND LIGHTS GO OFF TO THAT HALLWAY.				JUAN WILL ALSO CALL CALI TO EXPLAIN			
------------------	--	--	--	--	--	-------------------------------------	--	--	--

Mary Garcia

30975		Cafeteria			1/28/2008		8		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/28/2008 9:57:29 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando		WALK - IN FREEZER - WHEN FAN GOES OFF & ON, ALOT OF WATER AND ICE FORM.							
-------------------	--	---	--	--	--	--	--	--	--

		GESSICA B. - SNP MGR 882-6784							
--	--	-------------------------------	--	--	--	--	--	--	--

Jacqueline Aguilar

30993		Office			1/28/2008		8		\$0.00
-------	--	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Technology Mike			1/28/2008 3:29:50 PM				
--------	------------------	-----------------	--	--	----------------------	--	--	--	--

Ambriz, Juan		Need to replace door stopper in Mike's office							
--------------	--	---	--	--	--	--	--	--	--

Juan Ambriz

31106					1/30/2008		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	CUSTODIAL			1/30/2008 3:40:04 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Ambriz, Juan		AS PER JUAN AMBRIZ-CUSTODIAL CLOSET (NEXT TO MAIL ROOM) NEEDS TO BE PAINTED							
--------------	--	---	--	--	--	--	--	--	--

Mary Garcia

31108					1/30/2008		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	CUSTODIAL			1/30/2008 3:41:35 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Ambriz, Juan		AS PER JUAN AMBRIZ-CUSTODIAL CLOSET HAS A HOLE ON THE FLOOR AND NEEDS TO BE PATCHED UP WITH CEMENT. (DIRT DOES NOT WORK ON THIS)							
--------------	--	--	--	--	--	--	--	--	--

Mary Garcia

31129		Office			1/31/2008		5		\$0.00
-------	--	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	C-WING			1/31/2008 11:12:45 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Ambriz, Juan		AS PER KARLA-NEED TO HAVE THE LIGHT BULBS REPLACED IN SHEILA'S OFFICE.							
--------------	--	--	--	--	--	--	--	--	--

Mary Garcia

31131		Office			1/31/2008		5		\$0.00
-------	--	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	B-WING CLOSET			1/31/2008 1:33:57 PM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Ambriz, Juan		AS PER MELISSA-NEED TO HAVE SHELVING MOVED AROUND IN HER CLOSET BEFORE SATURDAY.							
--------------	--	--	--	--	--	--	--	--	--

Mary Garcia

2/5/2008 6:09:35 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		GAC								
31132		Office			1/31/2008		5		\$0.00	
Medium	Work In Progress	B-WING			1/31/2008 1:39:36 PM					
Ambriz, Juan		AS PER MR. SUTMILLER-NEED TO HAVE LIGHT BULBS CHANGED OUT.								
Mary Garcia										
31201					2/3/2008	2/11/2008	2		\$0.00	
Medium	Work In Progress				2/3/2008 12:30:35 AM					
Ambriz, Juan		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos										
31205					2/3/2008	2/11/2008	2		\$0.00	
Medium	Work In Progress				2/3/2008 12:30:37 AM					
Ambriz, Juan		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos										
31235					2/3/2008	2/9/2008	2		\$0.00	
Medium	Work In Progress				2/3/2008 12:30:50 AM					
Ambriz, Juan		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos										
31273					2/4/2008		1		\$0.00	
Medium	Work In Progress				2/4/2008 2:46:31 PM					
Castillo, Carlos		Power Outage (El Paso Electric Problem)								
Richard Chavez										
31281		Office			2/4/2008		1		\$0.00	
Medium	Work In Progress	A-WING			2/4/2008 4:00:28 PM					
Ambriz, Juan		AS PER VERONICA-NEED TO HAVE SOME LIGHT BULBS TURNED OFF. (HURTING HER EYES, TO MUCH LIGHT)								
Mary Garcia										
Count: 45 Work Orders		Avg. Age of WO's 78					Total for GAC		0	\$0.00

Location:		Gadsden HS							
24385					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
24386					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24387					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24384					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24388					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24474					7/1/2007	8/1/2007	150		\$0.00
Medium	Work In Progress				7/1/2007 12:16:18 AM	11/28/2007			
Moncayo, Fernando		Yearly - Gladsden HS Exit Sign Test: Annual - Refer to PMschedule details.							
Alfredo Holguin									
24475					7/1/2007	7/9/2007	150		\$0.00
Medium	Work In Progress				7/1/2007 12:16:18 AM	11/28/2007			
Moncayo, Fernando		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PMschedule details.							
Alfredo Holguin									
24823					7/17/2007		203		\$0.00
Medium	Work In Progress				7/17/2007 9:44:36 AM				
Lozoya, Manny		Requested byAgustin Garcia Rm. 310AAcademic Building-Door handle to Custodian's storage closet is broken and needs to be replaced before school begins.							
Velia Alarcon									
24836					7/17/2007		203		\$0.00
Medium	Work In Progress				7/17/2007 2:30:46 PM				
Lozoya, Manny		Requested byVelia-Four HK7 keys are needed for the Intervention Staff that will be in Rm. 554.							
Velia Alarcon									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

24912	North Building	Custodial			7/19/2007		201		\$0.00
Medium	Work In Progress				7/19/2007 11:54:19 AM				
Munoz, Joe		The windows in the attendance office need to be washed.							

25059	Pool Pump	Pool			7/25/2007		195		\$0.00
Medium	Work In Progress				7/25/2007 8:10:17 AM				
Castillo, Carlos		AS PER RAUL SANCHEZ ;CIRCULATING PUMP NOT WORKING							

Carlos Castillo

25204	Boys Gym				7/30/2007		190		\$0.00
Medium	Work In Progress	Football Side			7/30/2007 2:49:17 PM				
Lara, Ralph		NEED A NEW DOOR FOR THE BOYS GYM FOOTBALL SIDE LOCKER ROOM DO TO VANDALISM							

Mario Apodaca

25208					7/30/2007		190		\$0.00
Medium	Work In Progress				7/30/2007 3:12:59 PM				
Lozoya, Manny		Requested by Velia for rm. 245 over Varsity Gym-Mr. Foster has placed the Parent Out-Reach Ambassador's in this classroom has their new office. Four HE38 keys are need to issue to the Ambassador's. They will be re-located once a space is found for them.							

Velia Alarcon

25212					7/30/2007		190		\$0.00
Medium	Work In Progress				7/30/2007 3:25:27 PM				
Lozoya, Manny		Requested by Velia-Four HE1 (Gym Keys) are needed for the Parent Out-Reach Ambassador's to open small hallway over the Varsity Gym to access their new office/classroom.							

Velia Alarcon

25221					7/30/2007		190		\$0.00
Medium	Work In Progress				7/30/2007 3:44:32 PM				
Lozoya, Manny		Requested by Velia for Rm. 126A Main Building-Four HH16 keys are needed to office.							

Velia Alarcon

25225					7/30/2007		190		\$0.00
Medium	Work In Progress				7/30/2007 4:00:35 PM				
Lozoya, Manny		Requested by Velia for Rm. 554 Wood Shop-Four HK7 keys are needed for Intervention Staff.							

Velia Alarcon

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden HS

25259					7/31/2007		189		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/31/2007 10:22:16 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Requested by Oscar Menchaca Rm. 123 Custodial Storage Room in Main Building-Door lock does not work.

Velia Alarcon

25260					7/31/2007		189		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/31/2007 10:34:23 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Requested by Debbie Costalez Rm. 118 Bookkeeper's Office in Main Building-The bookkeeping office in the same as the concession stand. The concession stand is going to be used as a Marketing classroom. The bookkeeping office needs to be off master and four keys are needed.

Velia Alarcon

28398	Varsity Gym				10/23/2007		105		\$0.00
-------	-------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 10:59:51				
--------	------------------	--	--	--	---------------------	--	--	--	--

Moncayo, Fernando Please order parts to repair water fountain in lobby area.

Michael Munoz

28480	Agricultural				10/24/2007		104		\$0.00
-------	--------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2007 11:28:25				
--------	------------------	--	--	--	---------------------	--	--	--	--

Appelzoller, Fred REPLACE GAS REGULATORS IN AG BLDG.

Michael Munoz

30796	Computer	Computer Lab			1/18/2008		18		\$0.00
-------	----------	--------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/18/2008 1:15:53 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos OUTSIDE LAMPS NEED TO BE SERVICE

Mario Apodaca

25342	Boys Gym	Dressing Room			8/2/2007		187		\$0.00
-------	----------	---------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/2/2007 1:24:08 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny NEED A NEW DOOR CYLINDER AT THE GIRLS LOCKER ROOM AT BOYS GYM ROOM 404

Mario Apodaca

25343	Cafeteria (1998)	Restroom (Boys)			8/2/2007		187		\$0.00
-------	------------------	-----------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/2/2007 1:26:39 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny BOYS RESTROOM NEED A NEW LEVER LOCKSET FOR THE DOOR

Mario Apodaca

25344	Academic Bldg				8/2/2007		187		\$0.00
-------	---------------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/2/2007 1:30:21 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny A KEY IS BROKEN IN A DOOR CYLINDER AT ACADEMIC BLDG ON THE N-SIDE OF THE BLDG

Mario Apodaca

2/5/2008 6:09:35 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden HS

25682	Old English Bldg	Restroom (Boys)			8/9/2007		180		\$0.00
-------	------------------	-----------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/9/2007 2:51:13 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny	BOYS RESTROOM AT THE TOP FLOOR NEED A NEW KEY CYLINDER								
---------------	--	--	--	--	--	--	--	--	--

Mario Apodaca

25689					8/9/2007		180		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/9/2007 3:38:10 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny	Attn;MR. LATOYA my key is about to break,need one asap THANK YOU!!								
---------------	--	--	--	--	--	--	--	--	--

Fernando Moncayo

25690					8/9/2007		180		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/9/2007 3:40:46 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny	CAFETERIA WEST wing door lock has something inside the cylinder								
---------------	---	--	--	--	--	--	--	--	--

Fernando Moncayo

25691	Varsity Gym	Gym			8/9/2007		180		\$0.00
-------	-------------	-----	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/9/2007 3:43:17 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny	GIRL'S dressing rooms in VARSITY gym, has a broken lock handle								
---------------	--	--	--	--	--	--	--	--	--

Fernando Moncayo

25726	Concession	Football Field			8/10/2007		179		\$0.00
-------	------------	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/10/2007 3:12:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny	CONCESSION STAND AT FOOTBALL NEED A NEW DOOR LEVER FOR BACK ROOM								
---------------	--	--	--	--	--	--	--	--	--

Mario Apodaca

25732					8/10/2007		179		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/10/2007 3:46:07 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos	Requested by Ms. Lerma Rm. 106 Main Building-Need an outlet installed.								
------------------	--	--	--	--	--	--	--	--	--

Velia Alarcon

25743					8/10/2007		179		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/10/2007 4:11:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny	Requested by Ms. Jaraba Rm. 124 Main Building-Rekey desk and three keys will be needed.								
---------------	---	--	--	--	--	--	--	--	--

Velia Alarcon

25760					8/13/2007		176		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 9:52:12 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny	Requested by Ms. Jaraba Rm. 124 Main Building-Replace missing cylinder in closet and three keys will be needed.								
---------------	---	--	--	--	--	--	--	--	--

Velia Alarcon

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
25763					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 9:57:56 AM				
Lozoya, Manny		Requested by Velia for Cafeteria-A dead bolt lock needs to be installed on both doors that connect the Conference rooms to the kitchen area of the Cafeteria and five keys are needed.							
Velia Alarcon									
25767					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 11:07:57 AM				
Lozoya, Manny		Requested by Velia for Main Building and Academic Building Mail Rooms-Combination locks into mail rooms need to be changed, several students have figured out combination. Also, WO# 17300 has not been completed, please review.							
Velia Alarcon									
25771					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 11:37:05 AM				
Lozoya, Manny		Requested by Ms. Lam Rm. 104 Main Building-Lock of the North door can no be locked.							
Velia Alarcon									
25774					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 12:04:00 PM				
Lozoya, Manny		Requested by Chief Arms Rm. 203 North Building-Key does not want to open classroom.							
Velia Alarcon									
25782					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 1:01:42 PM				
Lozoya, Manny		Requested by Velia-Five HJ2 keys are needed for room 801.							
Velia Alarcon									
25783		Gym			8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 1:08:57 PM				
Lozoya, Manny		Requested by Velia-Three HG3 keys are needed (Girl's Gym Office.)							
Velia Alarcon									
25788					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 1:47:30 PM				
Lozoya, Manny		Requested by Velia-Four D Master keys are needed.							
Velia Alarcon									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
25790					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 1:55:05 PM				
Lozoya, Manny		Requested by Velia-Five HEM1 Master keys are needed.							
Velia Alarcon									
25786					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 1:35:55 PM				
Lozoya, Manny		Requested by Velia Rm. 153 Old English Building-Room # 153 needs to have the door knob replaced and re-keyed, four keys will be needed.							
Velia Alarcon									
25791					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 1:59:05 PM				
Lozoya, Manny		Requested by Velia-Two M251 keys are needed for the new Cross Country Coach for restrooms at Football Field.							
Velia Alarcon									
25894					8/15/2007		174		\$0.00
Medium	Work In Progress	GATE			8/15/2007 2:32:57 PM				
Lozoya, Manny		Mr. Joe S. Mendez, would like to request a key for the gate in the back of Gadsden High School by the alfalfa field in the back of schools ground. That he is requesting is (GM-7) master key to lock. If any questions you may reach me at (505) 882-3364.							
Joe Mendez									
25895	Cafeteria (1998)				8/15/2007		174		\$0.00
Medium	Work In Progress				8/15/2007 2:57:18 PM				
Orozco, Danny		THE WALK-IN FREEZER CONDENS IS ICEING -UP AT CAFE							
Mario Apodaca									
25933					8/16/2007		173		\$0.00
Medium	Work In Progress				8/16/2007 2:24:53 PM				
Castillo, Carlos		Emerg. Light not working as per PM24571 Comp. Lab Southside Entrance Comp. Lab. Storage Boys Locker Rm West Wing Panther Hut							
Rudy Arreola									
25977	Cafeteria (1998)	Restroom (Boys)			8/17/2007		172		\$0.00
Medium	Work In Progress				8/17/2007 3:20:32 PM				
Appelzoller, Fred Joe Munoz		the water fountain by the boys restroom is leaking							

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

26031	Counselors				8/20/2007		169		\$0.00
Medium	Work In Progress				8/20/2007 10:30:31 AM				
Lozoya, Manny		NEED LOCK FOR COUNSELING CENTER. PLEASE SEE LUPE ONTIVEROS FOR DETAILS. THANKS.							

Guadalupe Ontiveros

26099					8/21/2007		168		\$0.00
Medium	Work In Progress				8/21/2007 2:10:31 PM				
Lozoya, Manny		NEED SIX NEW LOCK FOR THE NEW POWER PLANT							

Mario Apodaca

26102	Cafeteria (1998)	Restroom (Boys)			8/21/2007		168		\$0.00
Medium	Work In Progress				8/21/2007 2:32:13 PM				
Lozoya, Manny		Requested by Velia for Cafeteria-Door knob for the Boy's Restroom does not lock properly, needs to be repaired.							

Velia Alarcon

26105	Main Building				8/21/2007		168		\$0.00
Medium	Work In Progress				8/21/2007 2:42:35 PM				
Lozoya, Manny		Requested by Ms. Moreno Rm. 126 Main Building-Lock for classroom sticks, can't get in or get out.							

Velia Alarcon

26106	Main Building				8/21/2007		168		\$0.00
Medium	Work In Progress				8/21/2007 2:50:45 PM				
Lozoya, Manny		Requested by Ms. Moreno for Women's Faculty Restroom in Main Building-Key does not open restroom.							

Velia Alarcon

26109	Old English Bldg				8/21/2007		168		\$0.00
Medium	Work In Progress				8/21/2007 3:09:33 PM				
Lozoya, Manny		Requested by Ms. Spivey Rm. 134 Old English Building-Tighten door knob on room 134-keysticks in lock.							

Velia Alarcon

26110	Old English Bldg				8/21/2007		168		\$0.00
Medium	Work In Progress				8/21/2007 3:12:21 PM				
Lozoya, Manny		Requested by Ms. Spivey Rm. 134A Old English Building-Fix door frame on bathroom.							

Velia Alarcon

26114	Old English Bldg				8/21/2007		168		\$0.00
Medium	Work In Progress				8/21/2007 3:32:49 PM				
Lozoya, Manny		Requested by Ms. Zapien Rm. 154 Old English Building-Request to have name plate made to be placed over door.							

Velia Alarcon

2/5/2008 6:09:35 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
26364	Cafeteria (1998)				8/28/2007		161		\$0.00
Medium	Work In Progress				8/28/2007 1:58:54 PM				
Orozco, Danny		ONE NEON SIGN NOT TURNING ON							
Mario Apodaca									
26365		Parking Lot			8/28/2007		161		\$0.00
Medium	Work In Progress				8/28/2007 2:09:51 PM				
Castillo, Carlos		THE LIGHTING AT B PARKING LOT NEEDS TO BE SERVICED.							
Mario Apodaca									
28235	Agricultural				10/17/2007		111		\$0.00
Medium	Work In Progress				10/17/2007 2:55:30 PM				
Appelzoller, Fred		THE GAS REGULATOR AT THE AG BLDG IS LEAKING NEED FIXING							
Mario Apodaca									
28307	North Building				10/19/2007		109		\$0.00
Medium	Work In Progress				10/19/2007 8:03:48 AM				
Moncayo, Fernando		Shingles in North bldg(G wing)are coming off from roof							
Fernando Moncayo									
28397	Cafeteria (1998)				10/23/2007		105		\$0.00
Medium	Work In Progress				10/23/2007 10:56:32				
Moncayo, Fernando		Please paint patio frames around canopy area.							
Michael Munoz									
26444					8/30/2007		159		\$0.00
Medium	Work In Progress				8/30/2007 10:45:01 AM				
Lozoya, Manny		Requested by Linda Solis Rm. 801 Parent Center-The door between room 801 and 800 won't close, latch is stuck.							
Velia Alarcon									
26552					9/2/2007	9/10/2007	87		\$0.00
Medium	Work In Progress				9/2/2007 12:16:17 AM	11/28/2007			
Moncayo, Fernando		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PMs schedule details.							
Margret Villalobos									
26656	Concession	Football Field			9/4/2007		154		\$0.00
Medium	Work In Progress				9/4/2007 11:09:22 AM				
Lozoya, Manny		THE LOCK SET AT CONCESSION STAD NEED WORK							
Mario Apodaca									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

26688 9/5/2007 153 \$0.00

Medium Work In Progress 9/5/2007 12:54:55 PM

Moncayo, Fernando Requested by Ms. Jacquez Rm. 137 Old English Building-Air conditioner is not cooling classroom. The classroom next door does have cool air circulating through classroom, but the air in this classroom is hot. Please check vent in classroom.

Velia Alarcon

26820 9/7/2007 151 \$0.00

Medium Work In Progress 9/7/2007 4:27:46 PM

Ronquillo, Ruben Broken windows in PRESS BOX ;32x69x1/4 and 32x531/2 x1/4 wire glass THANKS!!

Fernando Moncayo

26853 Academic Bldg Restroom (Boys) 9/10/2007 148 \$0.00

Medium Work In Progress 9/10/2007 3:44:28 PM

Munoz, Michael THE PARTITONS AT ACADIMIC BLDG AT THE BOYS RESTROOM ARE VANDALIS ON THE E/SIDE WING

Mario Apodaca

26892 Counselors Portables 9/11/2007 147 \$0.00

Medium Work In Progress 9/11/2007 1:01:38 PM

Lara, Ralph We need the door that seperates RM 823 and 822 to lock students are trying to open the door from the other side.

Rudy Arreola

27104 North Building 9/18/2007 140 \$0.00

Medium Work In Progress 9/18/2007 7:50:53 AM

Castillo, Carlos NEED A NEW OUTLET RUN TO A COPY AT THE COPIER ATTENDNCE OFFICE

Mario Apodaca

27148 9/18/2007 140 \$0.00

Medium Work In Progress 9/18/2007 3:49:19 PM

Lara, Ralph Requested by Ms. Letz Rm. 155 Girl's Gym-The doors between the gym and the girls locker room need a lock. Secure the door even if it's a dead bolt.

Velia Alarcon

27155 9/18/2007 140 \$0.00

Medium Work In Progress 9/18/2007 4:13:38 PM

Moncayo, Fernando Requested by Velia for Rm. 109C Women's Faculty Restroom-Light bulbs are burned out and are flickering, need to be replaced.

Velia Alarcon

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Gadsden HS								
27159	North Building	Hallway/Corridor			9/19/2007		139		\$0.00
Medium	Work In Progress				9/19/2007 7:54:23 AM				
Ronquillo, Ruben		NEED TO REPAIR A GLASS WINDOW UNIT AT THE N-BLDG HALLWAY BY LOCKERS							
Mario Apodaca									
27203					9/19/2007		139		\$0.00
Medium	Work In Progress				9/19/2007 3:47:38 PM				
Moncayo, Fernando		Requested by Carlos Jacquez for Computer Lab- Several light bulbs are burned out and need to be replaced.							
Velia Alarcon									
27346	Counselors				9/24/2007		134		\$0.00
Medium	Work In Progress				9/24/2007 8:18:44 AM				
Moncayo, Fernando		Requested by Marie for Counseling Center- Thermostat does not work and it is very hot in Counseling Center.							
Velia Alarcon									
27519					9/27/2007		131		\$0.00
Medium	Work In Progress				9/27/2007 3:45:50 PM				
Lara, Ralph		Requested by Velia for Rm. 109D Main Building Men's Faculty Restroom- The cylinder lock is missing out of the door knob, please replace.							
Velia Alarcon									
27526					9/27/2007		131		\$0.00
Medium	Work In Progress				9/27/2007 3:53:45 PM				
Moncayo, Fernando		Requested by Ms. Greene- Wall Rm. 505 Annex building - Two ceiling tiles are missing and need to be replaced.							
Velia Alarcon									
27606					9/30/2007	10/8/2007	128		\$0.00
Medium	Work In Progress				9/30/2007 12:17:27 AM				
Apodaca, Mario		Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
27752					10/1/2007		127		\$0.00
Medium	Work In Progress				10/1/2007 9:22:49 PM				
Villalobos, Margret		Need mice pellets [poison] to control mice in storages THANKS!!							
Fernando Moncayo									
27909					10/5/2007		123		\$0.00
Medium	Work In Progress				10/5/2007 2:51:11 PM				
Carrasco, Danny		Greenhouse cooling pads; 4" w x 36" h need 20 feet							
Fernando Moncayo									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

28064		Electrical Room			10/11/2007		117		\$0.00
-------	--	-----------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/11/2007 1:26:26 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario
Jesus Estrada
All numbers in electrical panels need to be updated.

27529					9/27/2007		131		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/27/2007 3:59:03 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando
Requested by Ms. Letz for Tennis Courts-South gate on tennis court has been pried open and can not be secured. The fence part of gate is ripped.
10/1 - asp Mike route to Fernie and have him request thru Ruben.

Velia Alarcon

27575	Pool Pump				9/28/2007		130		\$0.00
-------	-----------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/28/2007 3:53:08 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
As per Alfredo please check irrg. well west of pool house contactor amp. (Coordinate w/Raul Sanchez).

Alfredo Holguin

27637					9/30/2007	10/21/2007	128		\$0.00
-------	--	--	--	--	-----------	------------	-----	--	--------

Medium	Work In Progress				9/30/2007 12:17:40 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny
Monthly- Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

27764	Business	Restroom (Boys)			10/2/2007		126		\$0.00
-------	----------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/2/2007 2:58:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred
THE URINAL AT THE BUS BLDG NEED TO BE REPLACE DOTO WATER LEAKING AT THE TOP FLOOR

Mario Apodaca

27768					10/2/2007		126		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/2/2007 3:23:03 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando
Requested by Ms. Zanotelli Rm. 102 Main Building- Need 2 bullentin boards retrieved from Ms. Hair and installed in new I.E.P. Office.

Velia Alarcon

27772					10/2/2007		126		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/2/2007 3:44:04 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando
Requested by Ms. Zanotelli Rm. 102 Main Building- Need desk moved into room 102, Ms. Hair has the desk.

Velia Alarcon

28136	Academic Bldg	Electrical Room			10/15/2007		113		\$0.00
-------	---------------	-----------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/15/2007 2:42:24 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose
NEED 3 NEW EXHAUST FANS FOR THE ACDAEMIC BLDG ELEATRICAL ROOMS

Mario Apodaca

2/5/2008 6:09:35 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

28138	Business	Hallway/Corridor			10/15/2007		113		\$0.00
-------	----------	------------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/15/2007 3:00:58 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
NEED TO WELD A DOOR HING AT THE BUS BLDG
ON THE N-END BOTT FLOOR

Mario Apodaca

28198	Football Stadium				10/16/2007		112		\$0.00
-------	------------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/16/2007 3:32:06 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando
Need to paint westsideonlyof pressbox maroon. (Pickup
paint w/Ruben or Danny)

Michael Munoz

28317		Electrical Room			10/19/2007		109		\$0.00
-------	--	-----------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/19/2007 8:39:04 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
NEED THE ASSIST OF THE ELECTRICAN TOO HELP
OUT ON NUMBERING THE BREAKER W/O 28064

Mario Apodaca

28401	Academic Bldg				10/23/2007		105		\$0.00
-------	---------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 11:02:57				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe
Please install irr. watering system to all trees and shurbs
around bldg.

Michael Munoz

28437	North Building				10/23/2007		105		\$0.00
-------	----------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 3:45:44 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
Requested by Mr. Belle Rm 213 North Building-Lock on
file cabinet is broken-comes out completely.

Velia Alarcon

28442	Main Building				10/23/2007		105		\$0.00
-------	---------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 3:49:53 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
Requested by Velia for Rm. 109d Main Building Men's
Faculty Restroom-Lock cylinder has being missing for
several months. Students are getting in and ditching,
needs to be replaced as soon as possible.

Velia Alarcon

28631	North Building				10/29/2007		99		\$0.00
-------	----------------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/29/2007 4:13:14 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando
Requested by Ms. Leahy Rm. 215 North Building-
Replace burned out light bulbs in classroom.

Velia Alarcon

28642	Academic Bldg	Restroom (Boys)			10/30/2007		98		\$0.00
-------	---------------	-----------------	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/30/2007 7:47:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Appelzoller, Fred
NEED 8 NEW SINK SET FAUCET FOR ALL
RESTROOMS IN THE ACADEMIC BLDG

Mario Apodaca

2/5/2008 6:09:35 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
28666					10/30/2007		98		\$0.00
Medium	Work In Progress				10/30/2007 11:06:16				
Ontiveros, Guadalupe		Requested by Coach Yanez for baseball field-Lay cement in home team baseball dugout (3rd base side).				1/10 - Asp Mike route to Lupe			
Velia Alarcon									
28668					10/30/2007		98		\$0.00
Medium	Work In Progress				10/30/2007 11:10:42				
Ontiveros, Guadalupe		Requested by Coach Yanez for Baseball Field-Repaint baseball dugouts maroon with gold trim.				12/6- As per Mike, route to Lupe.			
Velia Alarcon									
28707					10/30/2007		98		\$0.00
Medium	Work In Progress				10/30/2007 4:06:05 PM				
Gonzales, Angel		Truck #166 driver's side door won't close, safety issue							
Fernando Moncayo									
28790	Academic Bldg				11/1/2007		96		\$0.00
Medium	Work In Progress				11/1/2007 11:33:00 AM				
Lara, Ralph		Requested by Ms. Kalkwarf for the Faculty Restrooms (both North and South Restroom) in the Academic Building-Door locks do not open at times, difficult to turn key.							
Velia Alarcon									
28792	North Building				11/1/2007		96		\$0.00
Medium	Work In Progress				11/1/2007 12:56:25 PM				
Lara, Ralph		Requested by Ms. Leahy Rm. 215 North Building- Replace door stopper on the south side door.							
Velia Alarcon									
28794	Concession				11/1/2007		96		\$0.00
Medium	Work In Progress				11/1/2007 1:00:55 PM				
Castillo, Carlos		Requested by Ms. I. Ramos for Panther Paw/Concession Stand-Need to have a power outlet put in the backroom of the Concession Stand.							
Velia Alarcon									
28808	Academic Bldg				11/1/2007		96		\$0.00
Medium	Work In Progress				11/1/2007 3:51:30 PM				
Apodaca, Mario		Requested by Ms. Pineda Rm. 303 Academic Building- Remove broken pencil sharpener and install new one (Ms. Pineda has the new sharpener.)							
Velia Alarcon									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

28813					11/1/2007		96		\$0.00
Medium	Work In Progress				11/1/2007 3:53:52 PM				
Moncayo, Fernando		Requested by Velia-Check electricity to the light that iluminates the Flag in front of the school or replace burned out light bulb.							
Velia Alarcon									
28819	North Building				11/1/2007		96		\$0.00
Medium	Work In Progress				11/1/2007 4:13:16 PM				
Villalobos, Margret		North bldg room 202 is infested with mice.Also requesting mouse,powison pellets or blocks for storages and plumbing chases. Thanks!!							
Fernando Moncayo									
28858					11/4/2007	11/10/2007	93		\$0.00
Medium	Work In Progress				11/4/2007 12:16:39 AM				
Moncayo, Fernando		Monthly - Gadsden HS Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
28899					11/4/2007	11/12/2007	93		\$0.00
Medium	Work In Progress				11/4/2007 12:16:55 AM				
Moncayo, Fernando		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
28961	North Building	Hallway/Corridor			11/5/2007		92		\$0.00
Medium	Work In Progress				11/5/2007 1:10:05 PM				
Ambriz, Jose		On Friday 11/2/07 between 3:00-4:00 drinking fountains were vandalized,They broke or removed the front covers							
Fernando Moncayo									
28978	Old English Bldg	Classroom			11/6/2007		91		\$0.00
Medium	Work In Progress				11/6/2007 8:07:59 AM				
Lara, Ralph		OLd English room 148 door is badlybroken complete coming apart,need to be replace ASAP.Thanks!!							
Fernando Moncayo									
28980	North Building				11/6/2007		91		\$0.00
Medium	Work In Progress				11/6/2007 8:17:02 AM				
Carrasco, Danny		Ruben/Danny;Need about ten round roof drain covers,they are about 10" with four bolt ears.Thanks!!							
Fernando Moncayo									
29001	Main Building	Classroom			11/6/2007		91		\$0.00
Medium	Work In Progress				11/6/2007 3:11:51 PM				
Ronquillo, Ruben		BROKEN GLASS WINDOW AT ROOM 127 DOTO VANDALIM (18x37)							
Mario Apodaca									

2/5/2008 6:09:35 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden HS

29046	Varsity Gym				11/7/2007		90		\$0.00
Medium	Work In Progress				11/7/2007 2:19:51 PM				
Castillo, Carlos	NEED A NEW TIMER FOR THE OUTSIDE LAMPS AT THE V-GYM								

Mario Apodaca

29336					11/19/2007		78		\$0.00
Medium	Work In Progress				11/19/2007 1:21:16 PM				
Lara, Ralph	Requested by Mr. McNiece Rm. 213 North Building-2nd door does not shut/lock. (North door)								

Velia Alarcon

29337					11/19/2007		78		\$0.00
Medium	Work In Progress				11/19/2007 1:21:28 PM				
Lara, Ralph	Requested by Mr. McNiece Rm. 213 North Building-2nd door does not shut/lock. (North door)								

Velia Alarcon

29036					11/7/2007		90		\$0.00
Medium	Work In Progress				11/7/2007 10:24:39 AM				
Lara, Ralph	Requested by Mr. Contaldo Rm. 103 Main Building- Make key for drawer locks. I already gave our Locksmith one of the locks which are all keyed alike.								

Velia Alarcon

29135	Pool Pump	Pool			11/13/2007		84		\$0.00
Medium	Work In Progress				11/13/2007 7:51:12 AM				
Castillo, Carlos	As per Alfredo ,meet Lynco Electric at G.H.S. Regarding voltage concerns after upgrade.11-14-07								

Carlos Castillo

29164	North Building	Hallway/Corridor			11/13/2007		84		\$0.00
Medium	Work In Progress				11/13/2007 12:52:11				
Lara, Ralph	A SET OF DOOR HINGES ARE BROKEN AT N-BLDG BY THE OFFICE AT G -WING NEED TOBE REWELD								

Mario Apodaca

29201					11/14/2007		83		\$0.00
Medium	Work In Progress				11/14/2007 9:26:12 AM				
Lara, Ralph	Requested by Bonnie Sloan for Library-Has a key to a desk that used to work, but they put a new key lock and now it doesn't work, please repair.								

Velia Alarcon

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden HS

29202	Library				11/14/2007		83		\$0.00
-------	---------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/14/2007 9:29:18 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Mr. Grubaugh for Library-The lock is failing on the south emergency exit in the Library. If the lock can not be repaired, the door needs to be chained at night.

Velia Alarcon

29229	Academic Bldg	Mechanical Room			11/14/2007		83		\$0.00
-------	---------------	-----------------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/14/2007 2:49:51 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Appelzoller, Fred NEED A NEW BACKFLOW PREVENTR FOR THE BOILER ROOM AT ACADEMIC BLDG

Mario Apodaca

29338					11/19/2007		78		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/19/2007 1:23:31 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando Requested by Ms. Lennox Rm. 650 Business Building- Chalkboard fell off the wall (east). It needs to be rehung.

Velia Alarcon

29467					11/27/2007		70		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/27/2007 4:02:20 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Oscar Menchaca for Rm. 109d Men's Faculty Restroom in Main Building-WORK ORDER # 28442 HAS NOT BEEN COMPLETED. Lock cylinder has been missing for several months. Students are getting in and ditching, needs to be replaced as soon as possible.

Velia Alarcon

29469	North Building				11/27/2007		70		\$0.00
-------	----------------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/27/2007 4:04:53 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Velia for Rm. 217 Men's Faculty Restroom in North Building-Teacher and custodian keys do not open door, something is wrong with cylinder.

Velia Alarcon

29613					12/2/2007	12/8/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:29:52 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

29654					12/2/2007	12/10/2007	65		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:09 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden HS

29797 12/4/2007 63 \$0.00

Medium Work In Progress 12/4/2007 11:06:02 AM

Lozoya, Manny Requested by Ms. I. Ramos for Panter Paw/Concession Stand-Check or replace locks, door knob not closing properly.

Velia Alarcon

29798 12/4/2007 63 \$0.00

Medium Work In Progress 12/4/2007 11:08:16 AM

Castillo, Carlos Requested by Ms. I. Ramos Panther Paw/Concession Stand-Need additional outlets with more power added in Concession Stand.

Velia Alarcon

29799 12/4/2007 63 \$0.00

Medium Work In Progress 12/4/2007 11:10:24 AM

Castillo, Carlos Requested by Ms. I. Ramos for Computer Lab (Lab A)- Need an outlet with more power in Lab A for a laminating machine.

Velia Alarcon

29802 Old English Bldg 12/4/2007 63 \$0.00

Medium Work In Progress 12/4/2007 1:20:37 PM

Castillo, Carlos NEED A NEW SWITCH FOR THE LAMLS AT THE OLD ENG BLDG BASEMENT

Mario Apodaca

30756 1/17/2008 19 \$0.00

Medium Work In Progress 1/17/2008 3:12:10 PM

Lara, Ralph Requested by Velia-Five L Wrenches are needed for classrooms with panic bars.

Velia Alarcon

30792 North Building Classroom 1/18/2008 18 \$0.00

Medium Work In Progress 1/18/2008 1:05:29 PM

Lara, Ralph NEED TO REPLALE A DOOR AT ROOM 202 AT THE N-BLDG

Mario Apodaca

30793 North Building Classroom 1/18/2008 18 \$0.00

Medium Work In Progress 1/18/2008 1:07:28 PM

Lara, Ralph NEED TO REPLACE A DOOR AT ROOM 203 AT THE N-BLDG

Mario Apodaca

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden HS

29820	Boys Gym				12/4/2007		63		\$0.00
Medium	Work In Progress				12/4/2007 3:27:24 PM				
Castillo, Carlos	Securitylights around Boy's gym not working,night Custodians complaining of being too dark								
Fernando Moncayo									
29871		Athletic Field			12/6/2007		61		\$0.00
Medium	Work In Progress				12/6/2007 1:57:16 PM				
Castillo, Carlos	please relocate electrical breaker panel boxfrom back of boys home dug out to the north wall.								
Michael Munoz									
29937	North Building				12/10/2007		57		\$0.00
Medium	Work In Progress				12/10/2007 10:58:08				
Moncayo, Fernando	Requested byMr. Belle Rm. 200 North Building-Install new pencil sharpener.								
Velia Alarcon									
29939					12/10/2007		57		\$0.00
Medium	Work In Progress				12/10/2007 11:29:34				
Lara, Ralph	Requested byMr. Belle Rm. 315 Academic Building-Lock on file cabinet needs to be replaced.								
Velia Alarcon									
29980					12/11/2007		56		\$0.00
Medium	Work In Progress				12/11/2007 9:26:32 AM				
Ambriz, Jose	Computer Lab - Leaking water.								
Fernando Moncayo									
30070	Varsity Gym	Dressing Room			12/13/2007		54		\$0.00
Medium	Work In Progress				12/13/2007 2:29:41 PM				
Ambriz, Jose	THE GIRLS DRESSING ROOM HEATING IS NOT WORKING NEED NEW FAN MOTOR #237								
Mario Apodaca									
30140					12/17/2007		50		\$0.00
Medium	Work In Progress				12/17/2007 2:02:11 PM				
Apodaca, Mario	Requested byMrs. B-Holzhausen Rm. 226 North Building-Replace damaged lab tables.								
Velia Alarcon									
30141					12/17/2007		50		\$0.00
Medium	Work In Progress				12/17/2007 2:04:04 PM				
Appelzoller, Fred	Requested byMrs. B-Holzhausen Rm. 226 North Building-Replace sink with deep tub lab sink and drying board.								
Velia Alarcon									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

30142					12/17/2007		50		\$0.00
Medium	Work In Progress				12/17/2007 2:05:58 PM				
Moncayo, Fernando		Requested by Mrs. B-Holzhausen Rm. 226 North Building-Repair or replace broken floor tiles.							
Velia Alarcon									
30143					12/17/2007		50		\$0.00
Medium	Work In Progress				12/17/2007 2:09:49 PM				
Ontiveros, Guadalupe		Requested by Mr. A. Lopez for Varsity Softball Field-Sprinkler installed on varsity in-field/wet down dirt.							
Velia Alarcon									
30145					12/17/2007		50		\$0.00
Medium	Work In Progress				12/17/2007 2:13:33 PM				
Ontiveros, Guadalupe		Requested by Mr. A. Lopez for JV Softball Field-Dug out shade for JV field.				1/8 - Route to Lupe asp Mike			
Velia Alarcon									
30151	North Building	Office			12/17/2007		50		\$0.00
Medium	Work In Progress				12/17/2007 3:16:51 PM				
Lozoya, Manny		THE DOOR LOCKSET AT THE N-BLDG OFFICE IS NOT LACKING W/KEY							
Mario Apodaca									
30249					1/6/2008	1/12/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:28:37 AM				
Moncayo, Fernando		Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
30276					1/6/2008	1/14/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:28:48 AM				
Apodaca, Mario		Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
30306					1/6/2008	1/27/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:29:00 AM				
Orozco, Danny		Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
30337					1/6/2008	1/14/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:29:12 AM				
Moncayo, Fernando		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
30630					1/15/2008		21		\$0.00
Medium	Work In Progress				1/15/2008 10:08:09 AM				
Ambriz, Jose		Requested by Mr. Milligan Rm. 143 Old English Building -Heater not working.							
Velia Alarcon									
30690	Agricultural				1/16/2008		20		\$0.00
Medium	Work In Progress				1/16/2008 2:47:00 PM				
Castillo, Carlos		THE GREENHOUSE BREAKER BOX NEED TO BE SERVICE							
Mario Apodaca									
30755					1/17/2008		19		\$0.00
Medium	Work In Progress				1/17/2008 3:10:41 PM				
Lara, Ralph		Requested by Velia-Two 1HE25 keys are needed, one for I.A. an one for key box (room 200).							
Velia Alarcon									
30383					1/8/2008		28		\$0.00
Medium	Work In Progress				1/8/2008 8:22:40 AM				
Moncayo, Fernando		NEED TO CHECK ALL WATER FOUNTAINS. ORDER MATERIALS & PARTS TO HAVE THEM ALL WORKING AND FUNCTIONING PROPERLY.							
Michael Munoz									
30491		Athletic Field			1/10/2008		26		\$0.00
Medium	Work In Progress				1/10/2008 2:58:02 PM				
Ontiveros, Guadalupe		Please install concrete floors at home and visitors dug outs baseball.							
Guadalupe Ontiveros									
30492		Athletic Field			1/10/2008		26		\$2,625.00
Medium	Work In Progress				1/10/2008 3:02:10 PM				
Ontiveros, Guadalupe		need concrete floor for Implement Equipment at grounds				1/22 - Rec PO Dept. To protect from the elements.			
Guadalupe Ontiveros									
30493		Athletic Field			1/10/2008		26		\$0.00
Medium	Work In Progress				1/10/2008 3:07:55 PM				
Ontiveros, Guadalupe		Need Storage by home dug -out to be build of cinder block.As per Coach Yanes.							
Guadalupe Ontiveros									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden HS

30612					1/14/2008		22		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/14/2008 4:18:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Velia for Panther Paw (Concession Stand)-WORK ORDER #29797 HAS NOT BEEN COMPLETED-Ms. I. Ramos is concerned that the Panther Paw door is not locking properly.

Velia Alarcon

30629					1/15/2008		21		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/15/2008 10:06:31 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Commander Snarr Rm. 203 North Building-Room door is broken at hinges and swings open freely.

Velia Alarcon

30631		Stairway			1/15/2008		21		\$0.00
-------	--	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/15/2008 10:10:33 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Julio Alcantar (SO1) for Softball Field-West fence by softball fields need repair for safety reasons.

Velia Alarcon

30633	Academic Bldg	Electrical Room			1/15/2008		21		\$0.00
-------	---------------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/15/2008 10:14:59 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario Requested by Ms. Vermillion Rm. 329 Academic Building-Change light bulbs over teachers desk

Velia Alarcon

30648	Main Building				1/15/2008		21		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/15/2008 2:46:56 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Apodaca, Mario Requested by Al Marmolejo (SO6) for outside of Main Building North East corner-Guard rail on north side entrance to Main Building is loose, needs to be fastened.

Velia Alarcon

30724	Library	Restroom (Boys)			1/17/2008		19		\$0.00
-------	---------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2008 9:26:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred Requested by Charlie Jacquez for Boy's Restroom in the Library-One of the urinal won't flush.

Velia Alarcon

30725	Academic Bldg	Classroom			1/17/2008		19		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2008 9:30:07 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Apodaca, Mario Requested by Mr. Wildman Rm. 313 Academic Building-Light out over teacher's desk.

Velia Alarcon

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

30738		Athletic Field			1/17/2008		19		\$0.00
Medium	Work In Progress				1/17/2008 11:13:34 AM				
Ontiveros, Guadalupe		THE TRACK COACH NEED TOW CONCRETE SLABS (7X7) & (7X28) BY THE SOCCER FIELD							

Mario Apodaca

30752					1/17/2008		19		\$0.00
Medium	Work In Progress				1/17/2008 2:49:53 PM				
Lara, Ralph		Requested by Velia-Two HJ11 keys are needed for, one for floating teacher and one for key box (room 660).							

Velia Alarcon

30753					1/17/2008		19		\$0.00
Medium	Work In Progress				1/17/2008 2:53:59 PM				
Lara, Ralph		Requested by Velia-Three F3 keys are needed, one for Security Officer and two for key box.							

Velia Alarcon

30795	Old English Bldg	Gym			1/18/2008		18		\$0.00
Medium	Work In Progress				1/18/2008 1:14:35 PM				
Castillo, Carlos		THE GIRLS GYM THE LAMPS NEED TOBE SERVICE BULBS NEED CHANGE-OUT							

Mario Apodaca

30869	North Building	Classroom			1/23/2008		13		\$0.00
Medium	Work In Progress				1/23/2008 2:05:18 PM				
Ambriz, Jose		NEED A IGNITION CONTROL FOR THE YORK UNIT AT THE N-BLDG TO ROOM 242							

Mario Apodaca

30870	North Building	Classroom			1/23/2008		13		\$0.00
Medium	Work In Progress				1/23/2008 2:08:57 PM				
Ambriz, Jose		NEED A 7" CAM-STAT FOR THE YORK UNIT AT THE N-BLDG							

Mario Apodaca

30929	Main Building	Restroom (Boys)			1/24/2008		12		\$0.00
Medium	Work In Progress				1/24/2008 3:04:11 PM				
Lara, Ralph		MENS RESTROOM AT THE MAIN BLDG NEED TOBE REKEY TO (H-E RO D) KEY							

Mario Apodaca

30960	Main Building	Classroom			1/25/2008		11		\$0.00
Medium	Work In Progress				1/25/2008 2:47:06 PM				
Villalobos, Margret		need pest control - roaches reported in restroom behind towel dispenser. rm 106							

Mario Apodaca

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS									
30995	North Building	Classroom			1/28/2008		8		\$0.00
Medium	Work In Progress				1/28/2008 3:41:18 PM				
Lara, Ralph		Requested by Ms. M. Holguin Rm. 231 North Building- Lost her set of classroom keys. Door needs to be re-keyed as well as file cabinet as soon as possible.							
Velia Alarcon									
30996	Main Building	Classroom			1/28/2008		8		\$0.00
Medium	Work In Progress				1/28/2008 3:43:39 PM				
Villalobos, David		Requested by Ms. Godin Rm. 105 Main Building- Faucet is leaking between base and handle in kitchen 6.							
Velia Alarcon									
30998	Cafeteria (1998)	Cafeteria			1/28/2008		8		\$0.00
Medium	Work In Progress				1/28/2008 3:46:49 PM				
Lara, Ralph		Requested by Marie for entrance to West Conference room in the Cafeteria- Her HE1 key does not open the door. She needs to access her Cum Files located in the West Conference storage room. Please repair as soon as possible.							
Velia Alarcon									
31035		Dressing Room			1/29/2008		7		\$0.00
Medium	Work In Progress				1/29/2008 3:18:16 PM				
Lara, Ralph		Wrestling room (507) - Key cylinder spins but does not engage lock							
Albert Vallejo									
31036	North Building	Restroom (Boys)			1/29/2008		7		\$0.00
Medium	Work In Progress				1/29/2008 3:20:45 PM				
Lara, Ralph		North building (217) - Key will not unlock door (it IS the proper key)							
Albert Vallejo									
31115	Library				1/30/2008		6		\$0.00
Medium	Work In Progress				1/30/2008 4:00:33 PM				
Villalobos, David		The sink and faucet in the library lounge area is in need of repair/replacement. The faucet is very old and corroded and is a possible health issue. It will be difficult to locate a replacement faucet so the basin will have to be replaced as well and the vanity cabinet/countertop modified to accommodate							
Albert Vallejo									
31142	Nursing Center				1/31/2008		0	7	\$175.00
Medium	Work In Progress				1/31/2008 3:28:04 PM	1/31/2008			
Villalobos, David		Sewer outside of nursing center was backing up and had to be cleaned out. I assisted David Villalobos in this task as described in Daily Work Log.				cable out main sewer line			
Albert Vallejo									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Gadsden HS									
31174	Cafeteria (1998)	Cafeteria			2/1/2008		4		\$0.00
Medium	Work In Progress				2/1/2008 3:03:38 PM				
Moncayo, Fernando	NEED NEW BULBS SOCKET FOR THE COOLER AT THE SERVING LINE								
Mario Apodaca									
31185	North Building	Classroom			2/1/2008		4		\$0.00
Medium	Work In Progress	Rm. 220			2/1/2008 4:02:28 PM				
Ronquillo, Ruben	Need to replace window pane in room 220, measures ca. 32" x 18" x 3/16" w/ internal wire. Window has been boarded up to secure.								
Albert Vallejo									
31206					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:37 AM				
Vallejo, Albert	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
31209					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:40 AM				
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
31272	Varsity Gym	Dressing Room			2/4/2008		1		\$0.00
Medium	Work In Progress				2/4/2008 2:40:57 PM				
Ronquillo, Ruben	WINDOW AT GIRLS LOCKERROOM AT THE V-GYM (20"X36")								
Mario Apodaca									
31318	Auto Shop				2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 3:15:37 PM				
Castillo, Carlos	Requested by Mr. Carrasco Rm. 580 Auto Shop-Repair ceiling lights.								
Velia Alarcon									
31236					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:50 AM				
Vallejo, Albert	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
31264	Agricultural				2/4/2008		1		\$0.00
Medium	Work In Progress				2/4/2008 11:36:51 AM				
Lara, Ralph	Requested by Velia for Ms. Hamilton-Her building and classroom keybroke (HK3), needs to be replaced as soon as possible.								
Velia Alarcon									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

31271	Academic Bldg	Choral			2/4/2008		1		\$0.00
Medium	Work In Progress				2/4/2008 2:37:27 PM				
Castillo, Carlos		NEED A NEW LITES SEITCH AT THE ACADEMIC BLBD S-EAST WING							

Mario Apodaca

31315	Main Building	Classroom			2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 3:08:36 PM				
Villalobos, David		Requested by Ms. Jaraba Rm. 124 Main Building-Repair drip in sink.							

Velia Alarcon

31316	Main Building	Dressing Room			2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 3:10:49 PM				
Vallejo, Albert		Requested by Ms. Jaraba Rm. 124 Main Building-Hang a mirror for french classes.							

Velia Alarcon

31317		Gym			2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 3:13:20 PM				
Ontiveros, Guadalupe		Requested by Coach R. Yanez for Baseball Field-Fix rope cord on flag pole behind centerfield wall of baseball field.							

Velia Alarcon

31319					2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 3:19:20 PM				
Lara, Ralph		Requested by Coach R. Yanez for Baseball Field-Extra keys to storage shed lock made for Assistant Coaches or format shed lock and office key to be the same for both. Shed lock key # CG2 (3 extra) Office key # HE43.							

Velia Alarcon

31322	Library	Library			2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 3:23:48 PM				
Lara, Ralph		Requested by Mr. Grubaugh Rm. 275 Library-The front door to the Library is becoming very hard to open. It sticks even when it's unlocked.							

Velia Alarcon

31324	Main Building	Classroom			2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 3:29:01 PM				
Castillo, Carlos		Requested by Cathy Cano for Rm. 106 Main Building-Pre-school bathroom ceiling is caving in, light fixture is hanging and is about to fall. Wires are also exposed.							

Velia Alarcon

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location:		Gadsden HS							
31325	Main Building	Classroom			2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 3:31:03 PM				
Vallejo, Albert		Requested by Cathy Cano for Rm. 106 Main Building- Ceiling tiles are broken and they need to be replaced.							
Velia Alarcon									
31337	Main Building	Classroom			2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 4:01:52 PM				
Villalobos, Margret		Requested by Cathy Cano for Rm. 106 Main Building- Roach and mouse problem.							
Velia Alarcon									
Count: 191 Work Orders		Avg. Age of WO's 97			Total for Gadsden HS			7	\$2,800.00

Location:		Gadsden MS							
24389					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24390					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24391					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24392					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24393					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden MS

24394					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24395					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24396					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24605	Cafeteria	Cafeteria			7/6/2007		214		\$0.00
-------	-----------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				7/6/2007 11:24:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny REACH-IN FREEZER IS NOT FREEZING (TERRY NOTICED THAT IT WAS 50 DEGREES ON 7/5/07, SHE HAD TO MOVE ALL PRODUCTS TO WALK-IN FREEZER, ON 7/6/07 IT WAS 95 DEGREES SO SHE DISCONNECTED IT)

TERRY PORTILLO - SNP MANAGER 882-2824

Alma Terrell

24920					7/19/2007		201		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/19/2007 3:01:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny AS PER ALFREDO YOU NEED TO PICK UP MASTER KEY 6&7 THAT WERE ISSUED TO MR. DANA HAMEL ASAP.

Alfredo Holguin

24956					7/20/2007		200		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/20/2007 9:53:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acosta, Juan NEED TO RELOCATE ATHLETICS TO OLD PURCHASING PORTABLE, PURCHASING (ALLL EXCETP CONFERENCETABLE) TO GM NURSHING AND GM NURSING TO ATHLETICS. CONTACT PERSONS WOULD BE MR. LOWENBERG & DR GARCIA

Alfredo Holguin

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

25021					7/24/2007		196		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/24/2007 11:02:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Manny Lozoya to collect the 6 and 7 master keys that were issued to him. ASAP

Alfredo Holguin

25033					7/24/2007		196		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/24/2007 3:29:03 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben 7/24/07
Inthe Vicky Lopez office need blind 45 1/2 x 45 1/2
thank you

Sebastian Diaz

25116	C-Wing	Office			7/26/2007		194		\$0.00
-------	--------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	ATHLETIC DEPT.			7/26/2007 1:59:10 PM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Lozoya, Manny AS PER MR. LOWENBERG-NEEDS 3 KEYS TO THE PORTABLE BEHIND OLD CENTRAL OFFICE NEXT TO GMS. (PORTABLE WHERE PAM/PURCHASING OFFICE USED TO BE.)

Mary Garcia

25118	C-Wing	Office			7/26/2007		194		\$0.00
-------	--------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	ATHLETIC DEPT.			7/26/2007 2:00:32 PM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Lozoya, Manny AS PER MR. LOWENBERG-NEEDS 3 KEYS FOR THE FRONT GATE (1ST GATE ONLY) NEXT TO OLD CENTRAL OFFICE.

Mary Garcia

25363		Office			8/2/2007		187		\$0.00
-------	--	--------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	A-wing			8/2/2007 5:36:00 PM				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Lozoya, Manny *Need "V3" (6 each) for New Medical Center Employees.
*3 Grand Masters for Administrators per Dr. Garcia
*Lock leading from Nurse's office to NMISSI Director's office need to have "No access" from both sides.
*Change lock in School Secretary's office to WA102 and change vault combinations.

Maricruz Carrasco

25713					8/10/2007		179		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/10/2007 11:02:31 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Need to issue Norma Alvarado keys for GMS.
Norma Alvarado

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden MS							
25751	Main Building	Hallway/Corridor			8/13/2007		176		\$0.00
Medium	Work In Progress	A.B WING			8/13/2007 8:13:43 AM				
Lozoya, Manny		PUSH BAR TO DOORS IN A.B WING DOES NOT LOCK OR NOT UNLOCK, KEY GETS STUCK							
Juan Acosta									
25755	Main Building	Hallway/Corridor			8/13/2007		176		\$0.00
Medium	Work In Progress	A.B WING			8/13/2007 8:23:16 AM				
Diaz, Sebastian		MAROON TILE IN HALLWAY WALLS ARE BROKEN OFF IN THE A.B WING AND CAFEARIA				Route to BM asp Mike- 8/13			
Juan Acosta									
25762	C-Wing	Office			8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 9:54:54 AM				
Lozoya, Manny		Repair Cash Boxlocks.				8/9 - Terryneeds status on this work order - Thanks Margret			
Terry Alvarado									
25817	C-Wing	Portables			8/13/2007		176		\$0.00
Medium	Work In Progress	C wing			8/13/2007 5:46:56 PM				
Lozoya, Manny		Portable byKeyboarding doesn't stayopen.							
Maricruz Carrasco									
25818		Classroom			8/13/2007		176		\$0.00
Medium	Work In Progress	Portable/502			8/13/2007 5:48:55 PM				
Lozoya, Manny		Mrs. Bernal's door does not lock from inside.							
Maricruz Carrasco									
25819		Office			8/13/2007		176		\$0.00
High	Work In Progress	Front office			8/13/2007 5:51:28 PM				
Lozoya, Manny		Need WA-27-8 gate key by C wing portables. Urgent for All Hazards Team							
Maricruz Carrasco									
25976	C-Wing				8/17/2007		172		\$0.00
Medium	Work In Progress				8/17/2007 3:18:12 PM				
Lozoya, Manny		8/17/07		In the C wing need two door knob thank you					
Sebastian Diaz									
26085	C-Wing				8/21/2007		168		\$0.00
Medium	Work In Progress				8/21/2007 12:04:45 PM				
Lozoya, Manny		8/21/07		In C WING NEED TO REPLACE DOOR KNOB IN SOME DOORS					
Sebastian Diaz									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden MS

26086					8/21/2007		168		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 12:07:48 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		8/21/07	In room 401 need key for storage thank you						
---------------	--	---------	--	--	--	--	--	--	--

Sebastian Diaz

25820		Office			8/13/2007		176		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Front Office			8/13/2007 5:54:26 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Lozoya, Manny		D3 keys needed (3) For window-2 keys WA-116, 2 keys WA-120 6 keys-V master, 6 keys-W master for Security officers and All Hazards Team.							
---------------	--	--	--	--	--	--	--	--	--

Maricruz Carrasco

25887	C-Wing	Office			8/15/2007		174		\$0.00
-------	--------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/15/2007 11:37:24 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenz		Rosa Hidalgo would like a ref. unit (like M. Sitters has) installed in her new office.							
---------------	--	---	--	--	--	--	--	--	--

Rosa Hidalgo

25950		Classroom			8/17/2007		172		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Annex/400			8/16/2007 10:57:39 PM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Mr. Martinez's door to storage closet has a lock. Request that door has same lock as room door.							
---------------	--	--	--	--	--	--	--	--	--

Maricruz Carrasco

25951	Main Building	Hallway/Corridor			8/17/2007		172		\$0.00
-------	---------------	------------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	A WING			8/17/2007 7:13:20 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Lozoya, Manny		ELECTRICAL ROOM DOOR IN THE A WING CYLINDER POPPED OUT							
---------------	--	---	--	--	--	--	--	--	--

Juan Acosta

26126	Vocational	Classroom			8/22/2007		167		\$0.00
-------	------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	307			8/22/2007 4:43:47 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny		ROOM 307 OUTSIDE DOOR WENT PUT KEY IN IT GET STUCK A.S.A.P							
---------------	--	---	--	--	--	--	--	--	--

Juan Acosta

26297					8/27/2007		162		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/27/2007 1:23:52 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique		please provide power to sebastians morgan bldg. THXS							
-----------------	--	--	--	--	--	--	--	--	--

Michael Munoz

26354					8/28/2007		161		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/28/2007 10:56:36 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe		Need to move 3 rocks from PPD and place at GMS where flags are placed. (Any ?'s see Mike)							
----------------------	--	--	--	--	--	--	--	--	--

Michael Munoz

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

26674	Gym	Office			9/4/2007		0		\$0.00
-------	-----	--------	--	--	----------	--	---	--	--------

Medium	Work In Progress				9/4/2007 4:29:44 PM	9/4/2007			
--------	------------------	--	--	--	---------------------	----------	--	--	--

Villalobos, Margret
 PE OFFICES - As per Mr. Mitchell something needs to be done about the mice problem in the offices. There are droppings on our desks, cabinets and computer tables. This is a health concern.

Sebastian Diaz

26752	Cafeteria				9/6/2007		152		\$0.00
-------	-----------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2007 2:03:39 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Diaz, Sebastian
 Replace the original tile on the walls by serving doors of cafeteria.
 (Asp Mike route to Sebastian 123086-Act)-mkv

Michael Munoz

26791					9/7/2007		151		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress	Mobile Home			9/7/2007 1:08:36 PM				
--------	------------------	-------------	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe
 Would it be possible for the groundsman, who cuts the grass/weeds, to cut/mow the weeds that are growing underneath the trees in front of my mobile home, and also the ones that are growing underneath the trees by my storage shed.

Thank you.

Yolie Jacquez

26830	C-Wing	Portables			9/10/2007		148		\$0.00
-------	--------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Athletic Office			9/10/2007 8:37:49 AM				
--------	------------------	-----------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
 Repair cash boc barrel for key has broken and needs to be replaced.

Terry Alvarado

26981					9/13/2007		145		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/13/2007 7:48:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
 9/13/07
 Need to fix all main entrance doors thank you

Sebastian Diaz

27102	Cafeteria	Cafeteria			9/18/2007		140		\$0.00
-------	-----------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/18/2007 7:31:22 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
 AT SNP WHS: FREEZER #3 HANDLE FELL OFF.

JOHNNY LECHUGA SNP MGR 882-6772

Jacqueline Aguilar

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

27253		Gym			9/20/2007		138		\$0.00
-------	--	-----	--	--	-----------	--	-----	--	--------

High	Work In Progress	Gym/Lockerroom			9/20/2007 4:00:58 PM				
------	------------------	----------------	--	--	----------------------	--	--	--	--

Diaz, Sebastian Benches need to be replaced in boys lockerroom.

Maricruz Carrasco

27385		Office			9/24/2007		134		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Front Office			9/24/2007 9:48:29 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Keys needed:
(4) V8 for Gym (Outside doors)
(1) A3 for Custodial Storage Room

Maricruz Carrasco

30881					1/23/2008		13		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/23/2008 3:28:41 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
1/23/08
Need to replace two lamps in vocational bldg tank you

Sebastian Diaz

31102	Gym	Gym			1/30/2008		6		\$0.00
-------	-----	-----	--	--	-----------	--	---	--	--------

High	Work In Progress				1/30/2008 3:33:40 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
need to replace bleacher motor and order one for back-up. need asap

Michael Munoz

31266					2/4/2008		1		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress	Near			2/4/2008 1:00:17 PM				
--------	------------------	------	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe
Raise Marquee at least 3 feet higher.

Maricruz Carrasco

31301					2/5/2008		0		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/5/2008 9:22:03 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Joe
2/5/08
Need fix toilet tank is broken in hall boys gym thank you

Sebastian Diaz

27729	C-Wing				10/1/2007		127		\$0.00
-------	--------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/1/2007 1:39:09 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Need to replace bulb on Exit Sign and fix one Emerg. Light as per PMwo's 26553, 26558

Sebastian Diaz

27888	Cafeteria	Cafeteria			10/5/2007		123		\$0.00
-------	-----------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/5/2007 7:43:33 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
SNP WAREHOUSE FREEZER #3 TEMP. IS AT 16. & FREEZER #5 IS AT 34. SHOULD BE BELOW 0.

JOHNNY LECHUGA SNP MGR 882-6927

Jacqueline Aguilar

2/5/2008 6:09:36 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden MS

27917					10/5/2007		123		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/5/2007 3:26:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred		10/5/07	Need to replace two urinal in annexboy's rest. thank you						
-------------------	--	---------	--	--	--	--	--	--	--

Sebastian Diaz

28081	Main Building	Restroom (Boys)			10/12/2007		116		\$0.00
-------	---------------	-----------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/12/2007 7:15:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Diaz, Sebastian	NEED REPLACE NEW MIRRORS IN BOYS RESTROOMS A.B WING								
-----------------	---	--	--	--	--	--	--	--	--

Juan Acosta

28632	Annex	Hallway/Corridor			10/30/2007		98		\$0.00
-------	-------	------------------	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/30/2007 5:45:03 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben	FIRE EXTINGUISHER DOOR ENCLOSURE GLASS IS MISSING .IN CAFETERIA. IN ANNEX BUILDING NEED A NEW DOOR AND GLASS FOR FIRE EXTINGUISHER.								
------------------	---	--	--	--	--	--	--	--	--

Juan Acosta

28830	Cafeteria				11/2/2007		95		\$0.00
-------	-----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/2/2007 1:20:40 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben	NEED A DOOR COVER FOR FIRE EXTINGUISHER ASP PM 27589.								
------------------	---	--	--	--	--	--	--	--	--

Sebastian Diaz

28831	C-Wing				11/2/2007		95		\$0.00
-------	--------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/2/2007 1:27:11 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique	NEED TO REPLACE SOME EMER AND EXIT LIGHTS IN C-WING AS PER PMS.								
-----------------	---	--	--	--	--	--	--	--	--

Sebastian Diaz

28953					11/5/2007		92		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/5/2007 10:10:48 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe	Both fences near base ballfield by canak need to be fixed. They both have holes.								
----------------------	--	--	--	--	--	--	--	--	--

Yolie Jacquez

29144		Cafeteria			11/13/2007		84		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 8:50:54 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny	SNP WAREHOUSE - FREEZER #5 TEMP. IS AT 36. SHOULD BE BELOW 0 DEGREES.								
---------------	---	--	--	--	--	--	--	--	--

JOHNNY LECHUGA - SNP WHS MGR 882-6927									
---------------------------------------	--	--	--	--	--	--	--	--	--

Jacqueline Aguilar

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden MS							
29219	Gym	Gym			11/14/2007		83		\$0.00
Medium	Work In Progress	Gym			11/14/2007 11:47:27				
Munoz, Michael		Bleachers in gym broken, need repair.							
Maricruz Carrasco									
29306					11/16/2007		81		\$0.00
Medium	Work In Progress	GMS Campus			11/16/2007 12:47:39				
Ontiveros, Guadalupe		Set up outside tables on GMS Campus.							
Maricruz Carrasco		11/27 Asp Mike route to Lupe.							
29779	C-Wing				12/4/2007		63		\$0.00
Medium	Work In Progress				12/4/2007 8:58:37 AM				
Sotelo, Enrique		C-Wing need to replace 2 emer. lights and 1 exit light as per PMs 28900 & 28905							
Sebastian Diaz									
29876					12/6/2007		61		\$0.00
Medium	Work In Progress				12/6/2007 3:06:03 PM				
Appelzoller, Fred		12/6/07 In room 140 need to relpace water fauset sink thank you							
Sebastian Diaz									
29927	Gym	Gym			12/8/2007		59		\$0.00
Medium	Work In Progress	Storage area			12/8/2007 11:56:48 AM				
Lozoya, Manny		Doors and hindges need to be replace and installed in the storage are located in the gym.							
Veronica Quinonez									
29945					12/10/2007		57		\$0.00
Medium	Work In Progress				12/10/2007 1:14:49 PM				
Lara, Ralph		12/10/07 Need to fix door knob in couchers storage in the gym thank you							
Sebastian Diaz									
30001					12/11/2007		56		\$0.00
Medium	Work In Progress				12/11/2007 3:48:25 PM				
Sotelo, Enrique		12/11/07 In band room need relocaed switches in the heaters thank you							
Sebastian Diaz									
30307					1/6/2008	1/27/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:29:00 AM				
Orozco, Danny		Monthly - Gadsden MS Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
30391					1/8/2008		28		\$0.00
Medium	Work In Progress				1/8/2008 12:03:19 PM				
Lozoya, Manny		1/8/08	Need glass window in class door's three doors thank you						
Sebastian Diaz									
30734					1/17/2008		19		\$0.00
Medium	Work In Progress				1/17/2008 10:58:02 AM				
Lozoya, Manny		1/17/08	Need fix main entrance doors not closing rights thank you						
Sebastian Diaz									
30415	Gym	Dressing Room			1/9/2008		27		\$0.00
Medium	Work In Progress	Gym/Official's			1/9/2008 8:56:40 AM				
Lozoya, Manny		Replace cylinder in Official's dressing room. Hard to open.							
Maricruz Carrasco									
30682		Office			1/16/2008		20		\$0.00
Medium	Work In Progress	Awing/SRO Office			1/16/2008 10:58:43 AM				
Lozoya, Manny		Need 3 keys to SRO Office- F3 as soon as possible. Thank you!							
Maricruz Carrasco									
30740	C-Wing	Portables			1/17/2008		19		\$0.00
Medium	Work In Progress				1/17/2008 11:29:50 AM				
Estrada, Jesus		The carpets in the Athletics portables need to be replaced. We will schedule this during spring break.							
Jesus Estrada									
30741					1/17/2008		19		\$0.00
Medium	Work In Progress	All GMS Lockers			1/17/2008 11:51:19 AM				
Lozoya, Manny		All lockers should have a screw on door so that students don't hide anything in there. To avoid students access to lockers.							
Maricruz Carrasco									
30817		Office			1/18/2008		18		\$0.00
Medium	Work In Progress	399/100/Secretar			1/18/2008 5:25:38 PM				
Lozoya, Manny		Glass doors needed for room 399, 100-Chacon's Lounge, Secretary's office, and SRO Office as soon as possible.							
Maricruz Carrasco									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location:	Gadsden MS								
31207					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:40 AM				
Diaz, Sebastian		Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
31212					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:41 AM				
Diaz, Sebastian		Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
31245					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:54 AM				
Diaz, Sebastian		Monthly - Gadsden MS Monthly FE Inspection - Refer to PMSchedule details.							
Margret Villalobos									
31265	Main Building	Restroom (Boys)			2/4/2008		1		\$0.00
Medium	Work In Progress	Awing/Boys			2/4/2008 12:10:24 PM				
Diaz, Sebastian		Big hole needs to be fixed as soon as possible, due to the fact that there is insulation (safety issue)							
Maricruz Carrasco									
Count: 73 Work Orders			Avg. Age of WO's	122		Total for Gadsden MS	0		\$0.00

Location:	La Union - JTP Alvarez Farms								
24909					7/19/2007		201		\$0.00
Medium	Work In Progress				7/19/2007 10:26:14 AM				
Lozoya, Manny		Need Master key for Alvarez Farms issued to Hirri Bauman.							
25115					7/26/2007		194		\$0.00
Medium	Work In Progress				7/26/2007 1:46:13 PM				
Lozoya, Manny		Need (1) L200 Key for new teacher A. Franco.							
Margaret Villalobos									
25298					8/1/2007		188		\$0.00
Medium	Work In Progress				8/1/2007 9:31:29 AM				
Lozoya, Manny		Need two (2) L200 keys for new employees (Virginia Chacon, PT and Harri Baumann, PT)							
Margaret Villalobos									
27478					9/26/2007		132		\$0.00
Medium	Work In Progress				9/26/2007 3:40:07 PM				
Castillo, Carlos		Cali Mrs. Avalos from JTP is requiring to install a new circuit. Thanks.							
Salvador Gonzalez									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union - JTP Alvarez Farms

30027					12/12/2007		55		\$0.00
Medium	Work In Progress				12/12/2007 10:22:25				
Castillo, Carlos		J.T.P in alvarezfarm outside lights need to be replaced or fixed.							
Santos Galindo									

Count: 5 Work Orders Avg. Age of WO's 154 Total for La Union - JTP Alvarez Farms 0 \$0.00

Location: La Union ES

24402					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:54 AM				
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24403					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:54 AM				
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24404					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:54 AM				
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24719					7/11/2007		209		\$0.00
Medium	Work In Progress				7/11/2007 3:43:15 PM				
Lozoya, Manny		7/11/07 MannyLinda (cafeteria Manager) is requiring a new KEY because she is having problems with the she has. Thank you							
Salvador Gonzalez									

25129					7/26/2007		194		\$0.00
Medium	Work In Progress				7/26/2007 3:49:29 PM				
Lozoya, Manny		7/26/07 Manny can you change door lock for classroom 210 (child safety). Thank you.							
Salvador Gonzalez									

25172					7/27/2007		193		\$0.00
Medium	Work In Progress				7/27/2007 3:42:58 PM				
Castillo, Carlos		7/27/07 Cali can you install new outlets for room 110 Requested by principal. Thank you.							
Salvador Gonzalez									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

25377		Classroom			8/3/2007		0		\$0.00
Medium	Work In Progress	MR.MOLINA/309			8/3/2007 10:16:07 AM	8/3/2007			
Lozoya, Manny		NEED KEY FOR ROOM 309 (L63) .							
Virginia Galindo									

25378		Classroom			8/3/2007		186		\$0.00
Medium	Work In Progress	MS.WITTERN/10			8/3/2007 10:28:29 AM				
Lozoya, Manny		NEED KEY FOR ROOM 108 (L36) .							
Virginia Galindo		Michelle Cordova-Najera losk key (Need Cost).							

25380		Classroom			8/3/2007		186		\$0.00
Medium	Work In Progress	MS.UXER/209			8/3/2007 10:43:07 AM				
Lozoya, Manny		NEED NEW KEY FOR ROOM 209 (L20).							
Virginia Galindo									

25628		Cafeteria			8/8/2007		181		\$0.00
Medium	Work In Progress				8/8/2007 3:37:08 PM				
Lozoya, Manny		Many, Linda (cafeteria manager requires to replace key because of problems with her. Thank you.							

Salvador Gonzalez

25962					8/17/2007		172		\$0.00
Medium	Work In Progress	Playground/Leach			8/17/2007 10:36:16 AM				
Ontiveros, Guadalupe		Need to remove fence between playground and leach fields, level and plant grass.							

Alfredo Holguin

26481					8/30/2007		159		\$0.00
Medium	Work In Progress				8/30/2007 3:57:38 PM				
Lozoya, Manny		8/30/07 Manny. Linda, the cafeteria manager is having problem with her key can you replace for a new one. thank you							

Salvador Gonzalez

26704					9/5/2007		153		\$0.00
Medium	Work In Progress				9/5/2007 3:26:36 PM				
Lozoya, Manny		9/5/07 Door knob in classroom is not opening, something inside the cilinder is wrong.							

Salvador Gonzalez

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

26916					9/11/2007		147		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/11/2007 3:45:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
 9/11/07
 Cali I need assistance to replace lidth bulbs and ballasts in old bldg., ceiling is high and it's hard to get up and down.
 Can you help me? Thanks.

Salvador Gonzalez

27170					9/19/2007		139		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/19/2007 2:16:07 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
 Michael Munoz
 Remove asphalt bytrash cans where it is buckling.

27171					9/19/2007		139		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/19/2007 2:17:50 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
 Michael Munoz
 Check area bytrash cans to see whyit is buckling.
 (possible leak)

27261		Cafeteria			9/21/2007		137		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/21/2007 7:46:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
 Pass thru Refrig. - is Freezing.

Linda Yanaga. SNP MGR 589-2040

Jacqueline Aguilar

27262		Cafeteria			9/21/2007		137		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/21/2007 7:48:54 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
 NEED TEMP. CONTROL FOR OVEN. NOT WORKING

LINDA YANAGA SNP MGR 589-2040

Jacqueline Aguilar

27263		Cafeteria			9/21/2007		137		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/21/2007 7:50:06 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
 FOOD SLICER NEED TO BE OILED

LINDA YANAGA SNP MGR 589-2040

Jacqueline Aguilar

27889					10/5/2007		123		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/5/2007 8:00:33 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
 Salvador Gonzalez
 10/5/07
 David can you check comode in annexbuilding is not flushing righ.

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		La Union ES							
28522					10/25/2007		103		\$0.00
Medium	Work In Progress				10/25/2007 8:20:29 AM				
Lara, Ralph		10/25/07							
		Manny cafeteria needs to fix locks in store room and lock on walk in.							
Salvador Gonzalez									
29025		Cafeteria			11/7/2007		90		\$0.00
Medium	Work In Progress				11/7/2007 8:51:19 AM				
Orozco, Danny		TWO OVENS DOWN. NOT WORKING							
		LINDA YANAGA SNP MGR 589-2040							
Jacqueline Aguilar									
27864					10/4/2007		124		\$0.00
Medium	Work In Progress				10/4/2007 8:57:15 AM				
Villalobos, David		Need Electrician and Plumber to La Union for locates or can it be scheduled for today or tomorrow?							
Cora Ramirez									
30011	2000 Core	Office			12/12/2007		55		\$0.00
Medium	Work In Progress				12/12/2007 9:15:28 AM				
Lara, Frank		Principal's office door leading outside to the back is leaking water threw the top of the door.							
Santos Galindo									
30015	2000 Core	Hallway/Corridor			12/12/2007		55		\$0.00
Medium	Work In Progress				12/12/2007 9:35:10 AM				
Castillo, Carlos		New hallway in front of boys and girls restrooms bulbs need to be replaced.							
Santos Galindo									
30016	Main Building	Hallway/Corridor			12/12/2007		55		\$0.00
Medium	Work In Progress				12/12/2007 9:41:17 AM				
Castillo, Carlos		Switch right in front of computer lab in hallway needs to be replace.							
Santos Galindo									
30020					12/12/2007		55		\$0.00
Medium	Work In Progress				12/12/2007 10:09:49				
Castillo, Carlos		In annex in front of the art room outside fixture need to be fixed.							
Santos Galindo									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

30025					12/12/2007		55		\$0.00
Medium	Work In Progress				12/12/2007 10:17:21				
Ontiveros, Guadalupe		In the two patios dirt has to be scrap lower then the side walks because water is starting to go into classrooms when it rains.							

Santos Galindo

30052	Main Building	Classroom			12/13/2007		54		\$0.00
Medium	Work In Progress				12/13/2007 7:53:39 AM				
Castillo, Carlos		Same light bulb's need to be replaced in room 107.							
Santos Galindo									

30063	Main Building	Office			12/13/2007		54		\$0.00
Medium	Work In Progress				12/13/2007 12:58:11				
Ambriz, Jose		Office needs a hydraulic valve replaced in heating system.							

Santos Galindo

30308					1/6/2008	1/27/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:29:01 AM				
Orozco, Danny		Monthly - La Union ES Range Hood Cleaning - Refer to PMschedule details.							

Margret Villalobos

30859					1/23/2008		13		\$0.00
Medium	Work In Progress	DP 544			1/23/2008 9:20:21 AM				
Sanchez, Raul		I talked to Melanie Sanchez regarding the Closure monitoring requirements for the La Union and I agreed to do two additional samplings of the monitoring reports on a quarterly basis. The first sampling needs to be accomplished in January 2008 and the next will be in April 2008.							

Alfredo Holguin

30980		Parking Lot			1/28/2008		8		\$0.00
Medium	Work In Progress				1/28/2008 2:21:51 PM				
Ontiveros, Guadalupe		Relocate Marquee to area on right hand side of parent entrance where light pole small chinese elm is located.				2/4/08 - Asp Mike route to Lupe.			
		Power for lighting not required							

Richard Chavez

31210					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:41 AM				
Gonzalez, Salvador		Monthly - La Union ES Emer. Light Test: Monthly - Refer to PMschedule details.							

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

31218					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:44 AM				
Gonzalez, Salvador		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									

31247					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:54 AM				
Gonzalez, Salvador		Monthly - La Union ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									

31262		Custodial			2/4/2008		1		\$0.00
Medium	Work In Progress				2/4/2008 7:29:12 AM				
Carbajal, Jimmy Santos Galindo		I need two dolly wheels fixed.							

Count: 37 Work Orders Avg. Age of WO's 108 Total for La Union ES 0 \$0.00

Location: Loma Linda ES

24400					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									

24397					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									

24398					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									

24399					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

24441					7/1/2007	7/22/2007	219		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:02 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

25163					7/27/2007		193		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/27/2007 10:06:44 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		MANNY THE DOOR IN ROOM 115 NOT WORKING PROPERLY, CATCH ON DOOR WILL NOT CATCH.							
---------------	--	--	--	--	--	--	--	--	--

Grace Alvarado									
----------------	--	--	--	--	--	--	--	--	--

25309		Portables			8/1/2007		188		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/1/2007 2:38:01 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny		MANNY, NEEDING KEY FOR #60 PORTABLE.							
---------------	--	--------------------------------------	--	--	--	--	--	--	--

Grace Alvarado									
----------------	--	--	--	--	--	--	--	--	--

25780					8/13/2007		176		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 12:37:30 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Michael		SIDEWALK IN FRONT OF BUILDING. SIDEWALK IS LIFTED. WANTING TO PREVENT ACCIDENT.							
----------------	--	---	--	--	--	--	--	--	--

Grace Alvarado									
----------------	--	--	--	--	--	--	--	--	--

26185					8/23/2007		166		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/23/2007 11:08:09 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben		REPLACE MARQUEE SECTION WHERE IT WAS BROKEN. ADD SCHOOL LOGO AND NAME.				Route to Ruben asp Mike 8/24/07			
------------------	--	--	--	--	--	---------------------------------	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

26188					8/23/2007		166		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/23/2007 11:27:05 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe		LANDSCAPE/PLANT GRASS AND INSTALL A SPRINKLER SYSTEM BETWEEN WINGS.							
----------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

26935					9/12/2007		146		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/12/2007 12:33:47 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph		Manny, bathroom door (girls) and (boys) in main entrance is not opening							
-------------	--	---	--	--	--	--	--	--	--

Grace Alvarado									
----------------	--	--	--	--	--	--	--	--	--

27760					10/2/2007		126		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/2/2007 2:22:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		Can we spread some sort of weed control in grass area only.							
----------------------	--	---	--	--	--	--	--	--	--

Rudy Arreola									
--------------	--	--	--	--	--	--	--	--	--

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Loma Linda ES							
27964					10/8/2007		120		\$0.00
Medium	Work In Progress				10/8/2007 1:16:59 PM				
Sanchez, Raul		We need the filters changed for the domestic water.							
Rudy Arreola									
28187					10/16/2007		112		\$0.00
Medium	Work In Progress				10/16/2007 1:37:35 PM				
Villalobos, Margret		We have alot of roaches around entire school need to have it fumigated.							
Rudy Arreola									
28459					10/24/2007		104		\$0.00
Medium	Work In Progress				10/24/2007 8:40:57 AM				
Lozoya, Manny		The door is hard to open have to push to lock and unlock and the key is hard to turn already tried some silicone spray but its still hard. Mens RR across mr Ramirez RM.							
Rudy Arreola									
28491					10/24/2007		104		\$0.00
Medium	Work In Progress				10/24/2007 3:13:26 PM				
Sotelo, Enrique		We have four lights in RM 111 not working at all allready changed out bulbs.							
Rudy Arreola									
29071					11/8/2007		89		\$0.00
Medium	Work In Progress				11/8/2007 2:16:13 PM				
Ontiveros, Joe		We have a sink hole on the westside of the parking lot.							
Rudy Arreola									
29225					11/14/2007		83		\$0.00
Medium	Work In Progress				11/14/2007 2:18:38 PM				
Villalobos, Margret		We are have alot of roaches and spiders in side school.							
Rudy Arreola									
29385					11/20/2007		77		\$0.00
Medium	Work In Progress				11/20/2007 3:36:27 PM				
Sotelo, Enrique		Mens Restroom Front Lobby and across from Rm 110 Hallway Emer. Lights not working asp PM28904							
Rudy Arreola									
29728					12/3/2007		64		\$0.00
Medium	Work In Progress				12/3/2007 8:58:58 AM				
Ontiveros, Guadalupe		Aprox 50-FT of fence was damaged poles were bent and fence was torn that was struck by a vehicle over the weekend.				12/4 - Route to Lupe asp Mike			
Rudy Arreola									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

29787					12/4/2007		63		\$0.00
Medium	Work In Progress				12/4/2007 10:29:53 AM				
Ronquillo, Ruben		We need a total of 17 blinds replaced through out the school Mr.Ronquillo allreadyhas a sample of the blind.							
Rudy Arreola									
29788					12/4/2007		63		\$0.00
Medium	Work In Progress				12/4/2007 10:30:33 AM				
Lozoya, Manny		RM 106 Door handle is broken.							
Rudy Arreola									
29789					12/4/2007		63		\$0.00
Medium	Work In Progress				12/4/2007 10:31:11 AM				
Lozoya, Manny		Rm 204 Door is hard to close is hitting the frame of the door.							
Rudy Arreola									
30187		Cafeteria			12/18/2007		49		\$0.00
Medium	Work In Progress				12/18/2007 1:35:31 PM				
Sotelo, Enrique		Exit Sign loose and one in kitchen is not working asp PM 29668.							
Rudy Arreola									
30186					12/18/2007		49		\$0.00
Medium	Work In Progress				12/18/2007 1:34:10 PM				
Sotelo, Enrique		Emergency Light at Mens rr and hallway infront of Rm 109 not working asp PM29659.							
Rudy Arreola									
30299					1/6/2008	1/27/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:28:57 AM				
Orozco, Danny		Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PMschedule details.							
Margret Villalobos									
30309					1/6/2008	1/27/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:29:01 AM				
Orozco, Danny		Monthly - Loma Linda ES Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									
30745					1/17/2008		19		\$0.00
Medium	Work In Progress				1/17/2008 12:50:48 PM				
Ontiveros, Guadalupe		We need to have the cement square on the northside of the bus turn around removed the new playground will be set up in that area.<WILL NEED BACK HOE>.							
Rudy Arreola									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Loma Linda ES							
30748					1/17/2008		19		\$0.00
Medium	Work In Progress				1/17/2008 2:07:18 PM				
Sotelo, Enrique		Emerg. Lights asp PM 30342 - Mens RR front lobby and hallway not working.							
Rudy Arreola									
31119					1/31/2008		5		\$0.00
Medium	Work In Progress				1/31/2008 8:40:51 AM				
Sotelo, Enrique		ELECTRICIAN, LIGHTS CONTINUOUSLY SHUTTING OFF BY ITSELF, HAS BEEN SEEN BY RUDY SEVERAL TIMES ALREADY, NEEDING REPAIR ROOM 204							
Grace Alvarado									
31211					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:41 AM				
Arreola, Rudy		Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
31220					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:44 AM				
Arreola, Rudy		Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
31248					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:55 AM				
Arreola, Rudy		Monthly - Loma Linda ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
Count: 33 Work Orders		Avg. Age of WO's		103	Total for Loma Linda ES			0	\$0.00

Location:		Mesquite ES							
28477					10/24/2007		104		\$0.00
Medium	Work In Progress				10/24/2007 10:14:02				
Solis, Lorenzo		Review all Air Condensers. Order parts as need or replace.							
Michael Munoz									
24405					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

24406					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24407					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24408					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24612		Classroom			7/6/2007		214		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				7/6/2007 2:28:27 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ramirez, Joe		ROOM 402 TEACHER DESK NEED TO BE FIX ASK LUIS SAUCEDO							
--------------	--	---	--	--	--	--	--	--	--

Luis Saucedo									
--------------	--	--	--	--	--	--	--	--	--

24630					7/9/2007		211		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				7/9/2007 2:37:11 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny		mannyne dd 2 c-242							
---------------	--	--------------------	--	--	--	--	--	--	--

Romauldo Apodaca									
------------------	--	--	--	--	--	--	--	--	--

24857	Army Building	Custodial			7/17/2007		203		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

High	Work In Progress				7/17/2007 4:28:09 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		I need 2 keys (A6) for administrators at Mesquite Elem. Administration should have access to room 600 where custodial/maintenance have computers.							
---------------	--	---	--	--	--	--	--	--	--

25019		Portables			7/24/2007		196		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/24/2007 10:58:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		PT 611 - Need to change lever a/s/a/p.							
---------------	--	--	--	--	--	--	--	--	--

Romauldo Apodaca									
------------------	--	--	--	--	--	--	--	--	--

28019					10/10/2007		118		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/10/2007 10:35:17				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny		Need three doors in the barracks to be replace, they are in very bad shape.							
---------------	--	---	--	--	--	--	--	--	--

Joe Ramirez									
-------------	--	--	--	--	--	--	--	--	--

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

28065					10/11/2007		117		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/11/2007 2:16:24 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe
NEED TO REPLEACE (10) TILES ON ROOM #110
THANK YOU LUIS, ANY QUESTIONS ASK LUIS.

Luis Saucedo

25072					7/25/2007		195		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/25/2007 11:38:23 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
AS PER MS. PHILLIPS NEED THE FOLLOWING
KEYS:
3 KEYS FOR RM 607
3 KEYS FOR RM 206

Romauldo Apodaca

25893					8/15/2007		174		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/15/2007 2:12:16 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
need name plates as per names and rm. # attached w/
sheet faxed. thanx per marquez.

Romauldo Apodaca

26216	Main Building	Classroom			8/24/2007		165		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	room 108			8/24/2007 8:04:09 AM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Staff member lost key to room 108.

Priscilla Martinez

26654		Parking Lot			9/4/2007		154		\$0.00
-------	--	-------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/4/2007 10:39:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe
Concrete parking bumpers, to better designate parking
in north end of Mesquite Elementary campus for safety.
Please contact Ms. Phillips for more information.

Priscilla Martinez

26746		Classroom			9/6/2007		152		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	room 604			9/6/2007 11:06:37 AM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Ramirez, Joe
Repair of a shelving unit, that was removed out of room
801, and place in room 604.

The shelving unit was pink.

Priscilla Martinez

26747	Main Building	Classroom			9/6/2007		152		\$0.00
-------	---------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	various locations			9/6/2007 11:41:16 AM				
--------	------------------	-------------------	--	--	----------------------	--	--	--	--

Lara, Ralph
32 name plates to identify staff need to be made.
20 room plate numbers to identify rooms need to be
made.

A list of these is available at the front office for specifics.

Priscilla Martinez

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

26748					9/6/2007		152		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2007 12:07:58 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny mannyneed new lock for filing cabinet,missing key.

Romauldo Apodaca

26940		Portables			9/12/2007		146		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	room 601			9/12/2007 1:45:43 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Lozoya, Manny Change lock on closet in Portable room 601.

Priscilla Martinez

27014	Main Building	Library			9/14/2007		144		\$0.00
-------	---------------	---------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Library			9/14/2007 9:55:30 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Ramirez, Joe Repair ABC roll cart, needs new roll.

Priscilla Martinez

27228	Main Building	Classroom			9/20/2007		138		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	room 607			9/20/2007 2:26:14 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Ramirez, Joe 1-overhead screen-installed on the east wall above white board, take maps down if necessary.

Priscilla Martinez

27229	Main Building	Library			9/20/2007		138		\$0.00
-------	---------------	---------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/20/2007 2:50:45 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe fix 10 chairs that are loose by putting screws.
fix ABC cubby cart (needs wheel)
2nd request, install computer keyboard trays (2)

Priscilla Martinez

27405		Cafeteria			9/25/2007		133		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/25/2007 10:37:34 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny BRAISING PAN IS ONLY LIGHTING UP HALF WAY.

ALICE FLOURNOY SNP MGR 233-2341

Jacqueline Aguilar

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Mesquite ES							
27576					9/29/2007		129		\$0.00
Medium	Work In Progress				9/28/2007 10:40:32 PM				
Ramirez, Joe		REPLACING EXTERIOR LIGHTING				Route to Roma asp Mike 10/2			
		MAIN ENTRANCE LOBBY 6 LIGHT, MAIN OFFICE 16 LIGHT, MAIN OFFICE STORAGE 5 LIGHT, MS. PHILLIPS OFFICE 6 LIGHT, MS. MARQUEZ OFFICE 4 LIGHT, DORA OFFICE 6 LIGHT, CONFERENCE ROOM 6 LIGHT, ENTRANCE MAIN HALLWAY 16 LIGHT, LIBRARY 30 LIGHT, BOY'S RESTROOM NORTH SIDE 2 LIGHT, GIRL'S RESTROOM SOUTH SIDE 2 LIGHT, TEACHER LOUNGE NORTH 4 LIGHT, CLASSROOMS C- WING: No. 113 NEEDS 2 LIGHT, No. 112 1 LIGHT, No. 110 1 LIGHT, No. 107 1 LIGHT. CLASSROOMS B- WING: No. 105 NEEDS 2 LIGHT, No. 103 2 LIGHT, No. 104 2 LIGHT, No. 102 6 LIGHT, No. 101 8 LIGHT, No. 201 7 LIGHT. D- WING: HALLWAY NEEDS 8 LIGHT, COMPUTER LAB. NEEDS 22 LIGHT. CLASS ROOM A- WING: No. 206 NEEDS 20 LIGHT, No. 205 10 LIGHT, No. 204 4 LIGHT, No. 203 8 LIGHT, No. 202 8 LIGTH. GIRL'S RESTROOMS 7 LIGHT, BOY'S RESTROOMS 8 LIGHT, FACULTY RESTROOM, MEN & WOMAN 4 LIGHT PORTABLE: No. 606 NEEDS 6 LIGHT, No. 608 10 LIGHT, No. 610 9 LIGHT, No. 611 2 LIGHT, No. 612 12 LIGHT. BARRACKS: No. 605 NEEDS 6 LIGHT, No. 604 6 LIGHT, No. 603 4 LIGHT, No. 601 4 LIGHT, No. 802 4 LIGHT, No. 801 14 LIGHT. TOTAL OF LIGHTS IS 430 THANK YOU. LUIS SAUCEDO, HC. MQ.							

Luis Saucedo									
27718					10/1/2007		127		\$0.00
Medium	Work In Progress				10/1/2007 10:59:28 AM				
Ramirez, Joe		AS PER PHILLIPS PRINCIPAL REPLACE MODEL SHEET ROCK & PAINT WALL.							
Luis Saucedo									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Mesquite ES							
27986					10/9/2007		119		\$0.00
Medium	Work In Progress				10/9/2007 7:50:27 AM				
Ramirez, Joe		NEEDS TO REPLACED 10 TILES ON ROOM #111							
Luis Saucedo		THANK YOU LUIS							
27987					10/9/2007		119		\$0.00
Medium	Work In Progress				10/9/2007 7:52:37 AM				
Ramirez, Joe		ON PORTABLE #229 GIRLS RESTROOMS NEEDS TO							
Luis Saucedo		REPLACEDE 9 TILES THANK YOU LUIS							
28494					10/24/2007		1		\$0.00
Medium	Work In Progress				10/24/2007 3:21:36 PM	10/25/2007			
Sotelo, Enrique		10/24/07.							
Joe Ramirez		need hand dryer replaced boy's bathroom k-wing,the							
Joe Ramirez		other one is stuck.							
28531		Cafeteria			10/25/2007		103		\$0.00
Medium	Work In Progress				10/25/2007 9:01:55 AM				
Ramirez, Joe		AS PER MS. MARQUEZ. THE CAFETERIA NEED A							
		WALL PAINT BY THAT STAGE, WE HAVE A BOARD							
		MEETING ON 11/8/2007 THANK YOU. ASK LUIS							
Luis Saucedo		LUIS SAUCEDO.							
		HC.MQ.							
28726		Cafeteria			10/31/2007		97		\$0.00
Medium	Work In Progress				10/31/2007 12:42:07				
Ramirez, Joe		need to replaced (10) tiles in that cafeteria thank you.							
Luis Saucedo		luis							
28993					11/6/2007		91		\$0.00
Medium	Work In Progress				11/6/2007 2:45:02 PM				
Sotelo, Enrique		11/06/07.							
Joe Ramirez		porch light ballast needs to be replaced.							
28995					11/6/2007		91		\$0.00
Medium	Work In Progress				11/6/2007 2:47:31 PM				
Ontiveros, Joe		11/06/07.							
Joe Ramirez		double sink and cabinet needs to be relocated from old							
		art rm. to new art rm.							

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

29133					11/13/2007		84		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 6:44:17 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny need to make a key for file cabinet please ask luis.

thank you.
luis

Luis Saucedo

29134					11/13/2007		84		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 7:24:34 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique 11/13/07.
need electrical strip installed in old bathrooms outside
for computers and equipment.

Joe Ramirez

29145					11/13/2007		84		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 9:01:13 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique Emer. lights not working in the following Kitchen, 1st
Cust. Closet and 1st Ladies Restroom as per PM28906.

Joe Ramirez

29146		Classroom			11/13/2007		84		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 9:03:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben Need Fire Extinguishers asp PM28872
Room 608 needs recharge
Room 601 no extinguisher

Joe Ramirez

29340		Parking Lot			11/19/2007		78		\$0.00
-------	--	-------------	--	--	------------	--	----	--	--------

Medium	Work In Progress	gate key			11/19/2007 2:16:04 PM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Lozoya, Manny Texas Migrant Council needs a gate key for the north
entrance. Will Mr. Munoz or Mr. Holguin please approve
this request, and direct me as to how the keys should be
handed over. The director for the Texas Migrant Council
is Olivia Hinojosa.

Priscilla Martinez

29683					12/2/2007	12/3/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM
schedule details.

Margret Villalobos

29684					12/2/2007	12/3/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES A-13 Quarterly WREH - Refer to
PM schedule details.

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Mesquite ES							
29697					12/2/2007	12/3/2007	65		\$0.00
Medium	Work In Progress				12/2/2007 12:30:25 AM				
Ramirez, Joe		Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PMschedule details.							
Margret Villalobos									
29719					12/2/2007	12/3/2007	65		\$0.00
Medium	Work In Progress				12/2/2007 12:30:34 AM				
Ramirez, Joe		Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PMschedule details.							
Margret Villalobos									
30310					1/6/2008	1/27/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:29:01 AM				
Orozco, Danny		Monthly - Mesquite ES Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									
30574					1/14/2008		22		\$0.00
Medium	Work In Progress				1/14/2008 6:39:55 AM				
Lozoya, Manny		the teacher staff bathroom in the 2nd grade wing door lock is not working. thank you luis							
Luis Saucedo									
30575					1/14/2008		22		\$0.00
Medium	Work In Progress				1/14/2008 6:46:08 AM				
Lozoya, Manny		need to make a key for file cabinet for room 204 sedillo class room thank you. luis							
Luis Saucedo									
30826		Classroom			1/22/2008		14		\$0.00
Medium	Work In Progress				1/22/2008 9:46:55 AM				
Estrada, Jesus		Need tile replaced in Rooms 113,111,110 w/carpet instead of tile.							
Michael Munoz									
31249					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:55 AM				
Ramirez, Joe		Monthly - Mesquite ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
30576					1/14/2008		22		\$0.00
Medium	Work In Progress				1/14/2008 7:40:44 AM				
Lozoya, Manny		need to replaced latched on girls & boys restrooms on north side of blg.thank you luis							
Luis Saucedo									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

30679	Main Building	Office			1/16/2008		20		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	front office			1/16/2008 10:19:41 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny Will you please make a door plaque for our new AP.

Jacob Montano
Assistant Principal

Priscilla Martinez

31213					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:42 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

31223					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

31260					2/4/2008		1		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/4/2008 7:05:29 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ramirez, Joe on south hallway under water fountain needs 10 tiles
thank you luis

Luis Saucedo

31261					2/4/2008		1		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/4/2008 7:07:21 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ramirez, Joe ON C WING HALL WAY NEED 8 TILES TO BE
REPLACE THANK YOU LUIS

Luis Saucedo

31303					2/5/2008		0		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/5/2008 9:54:13 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny needs to fix door lock inside of cafeteria by laundry room
please thank you luis

Luis Saucedo

Count: 53 Work Orders			Avg. Age of WO's 105			Total for Mesquite ES	0		\$0.00
------------------------------	--	--	-----------------------------	--	--	------------------------------	----------	--	---------------

Location: Northern On-Track Pre-K (LM)

24401					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:54 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Northern Pre-K (LM) Backflow Inspection -
Refer to PM schedule details.

Alfredo Holguin

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Northern On-Track Pre-K (LM)

25203	Main Building				7/30/2007		190		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/30/2007 2:26:51 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Frank
Need to transport 5 filing cabinets to Chaparral On Track
Pre-k and 3 filing cabinets to Anthony On Track Pre-K.

Concepcion Montalvo

25360					8/2/2007		187		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/2/2007 3:58:02 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ronquillo, Ruben
Danny Miranda
NEED TO REPAIR 3 WINDOWS 32.5 X 15.25

25566					8/7/2007		182		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/7/2007 11:23:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
MANNY NEED TO INSTALL KEY CYLINDERS FOR
OTHER
SIDE OF BUILDING

Frank Lara

25757		Cafeteria			8/13/2007		176		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 9:39:37 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Frank
Michael Munoz
Need to remove dead tree by front entrance of cafeteria.

26146					8/22/2007		167		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/22/2007 1:33:35 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben
8/22/07
NEED TO INSTALL BROKEN FOUR BROKEN
WINDOWES
AT LA MESA 32X15-1/2

Frank Lara

26659					9/4/2007		154		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/4/2007 11:57:06 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben
9/4/07
need to replace two broken windows
32.5"x15" clear glass

Frank Lara

26803					9/7/2007		151		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/7/2007 3:00:03 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe
Need to level area north of main bldg (Any ?'s call
Alfredo)

Alfredo Holguin

26846	Main Building				9/10/2007		148		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/10/2007 2:33:14 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred
Alfredo Holguin
NW Classroom - Provide washer and dryer hook-ups

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Northern On-Track Pre-K (LM)									
26877	Main Building	Office			9/11/2007		147		\$0.00
Medium	Work In Progress				9/11/2007 10:49:41 AM				
Lozoya, Manny	Re-keylock for social workers filing cabinet.								
Concepcion Montalvo									
27061					9/17/2007		141		\$0.00
Medium	Work In Progress				9/17/2007 8:15:39 AM				
Ronquillo, Ruben	RUBEN NEED TO REPLACE BROKEN WINDOW SCREENS 10- 34X31								
Frank Lara									
28578	Main Building				10/26/2007		102		\$0.00
Medium	Work In Progress	Wilma Martinez			10/26/2007 10:14:50				
Lozoya, Manny	Need locks with keys installed onto 2 (two) cabinets that hold Migrant supplies. Please contact Wilma Martinez @ 575-649-4800.								
Lucy Meza									
29464					11/27/2007		70		\$0.00
Medium	Work In Progress				11/27/2007 3:54:41 PM				
Lozoya, Manny	Please have Manny reinstall the key cores in the new hardware sets at La Mesa. He removed the entire cores during const. and needs to be reinstalled. Thanks David								
David Boyd									
29934					12/10/2007		57		\$0.00
Medium	Work In Progress	Infant Room			12/10/2007 10:49:42				
Miranda, Danny	Install new partition in infant room washer and dryer area.								
Ann Steinhoff									
30449	Main Building	Office			1/10/2008		26		\$0.00
Medium	Work In Progress				1/10/2008 9:25:14 AM				
Lozoya, Manny	Second request - Please, re-keylock for social worker's filling cabinet								
Concepcion Montalvo									
31311	Main Building	Restroom (Girls)			2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 1:12:32 PM				
Ontiveros, Joe	Women's toilet is clogged. Water backing up.								
Gilbert Trujillo									
Count: 16 Work Orders			Avg. Age of WO's	132	Total for Northern On-Track Pre-K (LM)			0	\$0.00

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

28986					11/6/2007		91		\$0.00
Medium	Work In Progress				11/6/2007 10:37:20 AM				
Villalobos, Margret		Need Price Quote for Pigeon Control at Barracks.							
Alfredo Holguin									
30093					12/14/2007		53		\$0.00
Medium	Work In Progress				12/14/2007 10:02:27				
Miranda, Danny		TEXTURE MARY SITTERS OFFICE. SPEAK TO LORENZO SOLIS PRIOR.							
Michael Munoz									
24409					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24410					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24589		Office			7/2/2007		218		\$0.00
Medium	Work In Progress	PPD			7/2/2007 11:03:22 AM				
Lozoya, Manny		AS PER SHIELA RHAIL-NEED A TOTAL OF 2 KEYS DC-18 FOR HERSELF AND VICKY LOPEZ.							
Mary Garcia									
24610					7/6/2007		214		\$0.00
Medium	Work In Progress				7/6/2007 1:54:54 PM				
Lozoya, Manny		Need a J3 (Gate Key) for Sebastian Diaz							
Michael Munoz									
24784					7/16/2007		204		\$0.00
Medium	Work In Progress				7/16/2007 8:03:38 AM				
Ronquillo, Ruben		FORKLIFT SHADE YELLOW CANVAS(MAINT.WHS-2, PUR.WHS-1, F.S. WHS.-1.							
Ruben Ronquillo									
24827					7/17/2007		203		\$0.00
Medium	Work In Progress				7/17/2007 11:18:49 AM				
Lozoya, Manny		JULIE IS REQUESTING A J3 GATE KEY (ORIGINAL ONE WAS GIVEN TO VIKKI LOPEZ)							
Juliet Parra									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Physical Plant Complex
-----------	------------------------

25023	Purchasing				7/24/2007		196		\$0.00
-------	------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/24/2007 11:04:34 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
I (Mary Murin) lost the key DC18 opened the one outside door....the same door the Marta and Yoli Jacquez go into the leads to their offices.

Margret Villalobos

25759	Motor Vehicle	Office			8/13/2007		176		\$0.00
-------	---------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Transp. Office			8/13/2007 9:51:35 AM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Need to change myname plate on the door to:

NORMA P. ALVARADO
TRANSPORTATION SPECIALIST

Norma Alvarado

27024					9/14/2007		144		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/14/2007 12:11:11 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique
NEED TO MOVE ELECTRICAL BOXES WERE NEW
DOORS WILL BE PUT IN CUSTODIAL OFFICE

Danny Miranda

27025					9/14/2007		144		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/14/2007 12:15:02 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique
NEED TO MOVE A/C ELECTRICAL WERE NEW
DOORS WILL BE PUT IN

Danny Miranda

27500	Motor Vehicle				9/27/2007		131		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/27/2007 9:30:33 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
PLEASE CHECK WATER PUMP ENGINE, NOT
STARTING.
THANKS RUBEN

Ruben Ronquillo

27765					10/2/2007		126		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/2/2007 3:03:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
RELOCATE DOUBLE DOORS ON BARRACK #1.

Ruben Ronquillo

28418	Motor Vehicle				10/23/2007		105		\$0.00
-------	---------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 2:10:41 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Transp Office - Install a door stop.

Norma Alvarado

28476	Motor Vehicle				10/24/2007		104		\$0.00
-------	---------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2007 10:11:20				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
Install doorstep. Norma Alvarado's office.

Michael Munoz

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Physical Plant Complex

27501	Motor Vehicle				9/27/2007		131		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/27/2007 9:33:12 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
PLEASE CHECK YELLOW DOUBLE AIR TANK COMPRESSOR, IDLE IS NOT WORKING, IT WILL NOT IDLE DOWN WHEN TANKS ARE FULL. THANKS RUBEN

Ruben Ronquillo

28954	Motor Vehicle				11/5/2007		92		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/5/2007 10:12:59 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique
Lights on light pole by gas pump, needs to be replaced.

Yolie Jacquez

28990					11/6/2007		91		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/6/2007 11:58:09 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Hernandez, Guillermo
NEED TO COORDINATE AND SCHEDULE WITH VICKI LOPEZ FOR A HIGH/LOW CLEANING 1/11/08 - REQUESTED STATUS FROM GUILLERMO

Michael Munoz

29073					11/8/2007		89		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Custodial Office			11/8/2007 2:31:43 PM				
--------	------------------	------------------	--	--	----------------------	--	--	--	--

Solis, Lorenzo
Removal of the split system and replace w/a package unit in Mary Sitters Office.

Michael Munoz

30228	Maintenance	Custodial			12/19/2007		48		\$0.00
-------	-------------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/19/2007 9:53:10 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Gonzales, Angel
ANGEL THE BIG TRUCK #82 IS MAKING A LOT OF NOISE SAL WAS PULLED OVER BY THE POLICE AND WAS TOLD NOT TO USE IT UNTILL IT GETS FIXED.THANK YOU

Jimmy Carbajal

30529		Gym			1/11/2008		25		\$0.00
-------	--	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/11/2008 11:20:49 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Michael
need recommendations for the following site (gms, chm, ghs, sths and stms) on bleachers for a preventive plan to see what needs to be done to them so they can operate/function properly.(pm) norcon/ces

Michael Munoz

30671	Food Services	Cafeteria			1/16/2008		20		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/16/2008 7:39:20 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Lights went out in SNP Whse. Light fixture doesn't turn on.

Johnny Lechuga, SNP WHSE MGR 882-6927

Jacqueline Aguilar

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
30818	Purchasing				1/22/2008		14		\$0.00
Medium	Work In Progress				1/22/2008 7:59:57 AM				
Diaz, Sebastian		Need to submit a work order to have some lightbulbs replaced in the warehouse, the hallway and in my office please.							
Vicky Lopez									
31066	Purchasing	Office			1/30/2008		6		\$0.00
Medium	Work In Progress	Inst. Materials			1/30/2008 12:47:42 PM				
Diaz, Sebastian		On February 15th a company will be coming in to dismantle and remove the furniture in the IM offices. While the offices are empty we would like the following done: 1. Paint both offices: Calla Lily White 2. Replace vertical blinds in office #2 with regular horizontal Venetian blinds (the work order for blinds I submitted last fall and Sebastian came over and measured the window.							
Vicky Lopez									
31067	Purchasing	Office			1/30/2008		6		\$0.00
Medium	Work In Progress	Inst. Materials			1/30/2008 12:49:21 PM				
Diaz, Sebastian		On February 14th we need the guys to come over and move the non modular furniture out into the warehouse. After the painting is done, I will need the guys to move one set of furniture (Black Desk set) into Office #1 and hang a few things on the wall.							
Vicky Lopez									
31068	Purchasing	Office			1/30/2008		6		\$0.00
Medium	Work In Progress	Inst. Materials			1/30/2008 12:51:43 PM				
Estrada, Jesus		Remove carpet from Office #2 (bigger office) and replace with tile.							
Vicky Lopez									
31190					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:31 AM				
Diaz, Sebastian		Monthly - Physical Plant FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
31302	Motor Vehicle	Restroom (Girls)			2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 9:38:22 AM				
Villalobos, David		Restroom is out of order. (Informed David)							
Norma Alvarado									
Count: 29 Work Orders			Avg. Age of WO's 106		Total for Physical Plant Complex			0	\$0.00

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

24373					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24374					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:50 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24375					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:50 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24964					7/20/2007		200		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/20/2007 12:11:45 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		MR MANNY LOZOYA SIR PER OFFICE THERE ARE TWO FILE CABINETS THAT NEED TO BE REPAIRED ONE IN CONFERENCE ROOM AND ONE IN ROOM 28 ASAP PLEASE THANK YOU SIR							
---------------	--	---	--	--	--	--	--	--	--

Adan Duran

24971					7/20/2007		200		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/20/2007 3:10:27 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		MR MANNY LOZOYA SIR WE HAVE TWO CABINET DOORS ROOM 116 THAT NEED THE DOOR LATCH REPLACE BROKE THE ONES THAT WHERE THERE THANK YOU SIR							
---------------	--	---	--	--	--	--	--	--	--

Adan Duran

25394		Cafeteria			8/3/2007		186		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/3/2007 2:15:45 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny		SINKS DO NOT STAYED FILLED WITH WATER (3-COMPARTMENT SINK) WATER LEAKS OUT VERY SLOWLY FROM DRAIN							
---------------	--	---	--	--	--	--	--	--	--

		EMILIA CARRILLO - SNP MANAGER 589-2550							
--	--	--	--	--	--	--	--	--	--

Alma Terrell

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

25711					8/10/2007		179		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/10/2007 10:15:31 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
MR MANNY LOZOYA SIR OUR HEAD CUSTODEN
NEEDS MASTER KEY THE ON HE HAS IS ABOUT TO
BREAK AS SOON AS YOU CAN PLEASE THANK YOU
SIR

Adan Duran

26180		Cafeteria			8/23/2007		166		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/23/2007 8:15:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
WHEN SHE CAME IN THIS MORNING AT 6:00 AM,
SHE FOUND THE WALK-IN REFRIGERATOR AT 50
DEGREES, SHE CALLED DANNY AND LEFT
MESSAGE ON HIS CELL PHONE, NOT REALIZING
THAT DANNY'S PHONE IS OUT OF ORDER. I
CALLED HER BACK TO INFORM HER THAT DANNY'S
PHONE IS OUT OF ORDER AND THAT I WOULD PUT
THE WORK ORDER IN THE TOOLBOX. 8/23/07

EMILIA CARRILLO - SNP MANAGER 589-2550

Alma Terrell

26440		Cafeteria			8/30/2007		159		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/30/2007 9:46:18 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
Floor Drain to Vegetable Sink is plugged up. Emilia
Carrillo-SNP Manager called it in late afternoon.

Emilia Carrillo - SNP Manager 589-2550

Alma Terrell

26653					9/4/2007		154		\$5,300.00
-------	--	--	--	--	----------	--	-----	--	------------

Medium	Work In Progress				9/4/2007 10:32:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Holguin, Alfredo
Provide services and materials for installation of new
controller to control existing lighting. Joe V. picked up PO on 9/4-mkv

Alfredo Holguin

27419	New Wing 1/02	Hallway/Corridor			9/25/2007		133		\$0.00
-------	---------------	------------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/25/2007 3:47:27 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
As per Head Custodian,convert hallway 220vplugs to
120v for floor machinery.

Carlos Castillo

27425		Cafeteria			9/25/2007		133		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/25/2007 4:06:38 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
WALK-IN FREEZER BUILDING ICE ON BOTTOM OF
DOOR AREA INSIDE AND OUT. SAFETY HAZARD
ON SLIPS AND FALLS.

EMILIA CARRILLO - SNP MANAGER 589-2550

Alma Terrell

2/5/2008 6:09:37 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Riverside ES							
28414		Gym			10/23/2007		105		\$0.00
Medium	Work In Progress				10/23/2007 11:35:01				
Lara, Ralph		MR. LOZOYA 1 PUERTA DEL GYM NO CIERRA. SI LA PUEDE VENIR A ARREGLAR. GRACIAS R. R.							
Raul Romero									
28486		Cafeteria			10/24/2007		104		\$0.00
Medium	Work In Progress				10/24/2007 2:34:48 PM				
Orozco, Danny		Shelves need to be removed on next session (March, 2008) As per Environment Department - they inspected Riverside on 10/23/07 and their comments were that: Wood shelving in dry storage must be coated with paint or replaced - Repeat violation. Must be corrected within 60 days. Need to inform Maria Nevarez - Inspector, when corrected.							
		Aida Salcedo, SNP Coordinator 882-6772 & Emilia Carrillo, SNP Manager 589-2550							
Alma Terrell									
28720					10/31/2007		97		\$0.00
Medium	Work In Progress				10/31/2007 9:23:23 AM				
Castillo, Carlos		AS PER OUR CONVERSATION, PLEASE PROVIDE A 120 OUTLET FOR THE ENVIRONMENT DEPT.							
Michael Munoz									
29257					11/15/2007		82		\$0.00
Medium	Work In Progress				11/15/2007 9:53:20 AM				
Lara, Ralph		MR RAFAEL LARA SIR WE HAVE A DOOR MIDDLE WING OUT SIDE BATH ROOM IS GIVING US SOME TROUBLE THE KEY WILL NOT TURN SOME TIMES CLEAN TUMBLER ITS ALITTLE BETTER BUT NEEDS TO BE LOOK AT THANK YOU SIR							
Adan Duran									
30097		Cafeteria			12/14/2007		53		\$0.00
Medium	Work In Progress				12/14/2007 10:32:38				
Orozco, Danny		WATER IS DRIPPING TO THE FLOOR AND SPLATTERING ONTO THE WALL MAKING ICE. SMALL AMOUNT - TEMP GOOD							
		EMILIA CARRILLO - SNP MANAGER 589-2550							
Alma Terrell									
30311					1/6/2008	1/27/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:29:02 AM				
Orozco, Danny		Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

30226					12/19/2007		48		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/19/2007 9:04:29 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
MR MANNY LOZOYA SIR WE NEED TO REPLACE 3 THREE OUTSIDE LOCK FOR GATES ONE WAS BROKEN AND THE TWO OTHERS WERE STOLEN THEY ARE FOR OUT SIDE GATES THANK YOU SIR

Adan Duran

30851					1/22/2008		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/22/2008 3:35:20 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose
MR JOSE AMBRIZ SIR THE RELIEF VALUE ON THE BOILER ON NORTH WING IS STAYING OPEN NEED TO REPLACE WAS ABLE TO GET IT TO STOP FOR NOW THANK YOU SIR AND GOD BLESS

Adan Duran

30985					1/28/2008		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/28/2008 2:59:01 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben
41 Northwing & Courtyard - Broken windows small windows. In courtyard cracked widow, alss at main entrance door craked window.

Carlos Hernandez

31016		Cafeteria			1/29/2008		7		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/29/2008 10:44:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
MILK COOLER ELECTRICAL OUTLET IS VERY LOOSE - SHE IS HAVING TO CONNECT AND DISCONNECT THE MILK COOLER ON A DAILY BASIS. EVERY TIME THAT IT'S PLUGGED IN, IT THROWS SPARKS.

EMILIA CARRILLO - SNP MANAGER 589-2550

Alma Terrell

31017		Cafeteria			1/29/2008		7		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/29/2008 10:47:09 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando
NEW FOOD SLICER IS NOT WORKING (THEY HEAR IT TURN ON, BUT IT DOESN'T WORK (ROTATE).

EMILIA CARRILLO - SNP MANAGER 589-2550

Alma Terrell

31215					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Carlos
Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PMschedule details.

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Riverside ES							
31226					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:47 AM				
Hernandez, Carlos		Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
31250					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:55 AM				
Hernandez, Carlos		Monthly - Riverside ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
Count: 26 Work Orders		Avg. Age of WO's 105			Total for Riverside ES			0	\$5,300.00

Location:		San Miguel ES							
24371					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:49 AM				
Villalobos, David		Yearly - San Miguel ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24372					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:49 AM				
Villalobos, David		Yearly - San Miguel ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24730					7/12/2007		208		\$0.00
Medium	Work In Progress	SERVER ROOM			7/12/2007 8:32:57 AM				
Vega, Danny		there is water right behind the Compaq Rack it seems like it is coming from the AC unit. please check ASAP							
Cora Ramirez									
24953					7/20/2007		0		\$0.00
Medium	Work In Progress				7/20/2007 9:08:53 AM	7/20/2007			
Lozoya, Manny		new doors installed in boiler rm#16/need to recore locks on doors/secure before end of day/asap							
Danny Vega									
25065		Classroom			7/25/2007		195		\$0.00
Medium	Work In Progress	2,19,22,30,32,36,			7/25/2007 10:39:20 AM				
Lozoya, Manny		Need the following keys: One of each except B47 need to for that classroom. B7, B11, B22, B47-need two keys of this one, B51, B52, B55, B63, B64							
Barbara Cardenas									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: San Miguel ES

25075					7/25/2007		195		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/25/2007 1:09:11 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny keys made for fire alarm pull station boxes dont work /please pick-up keys in office.please correct or make new keys

Danny Vega

25103		Classroom			7/26/2007		194		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	21			7/26/2007 8:19:00 AM				
--------	------------------	----	--	--	----------------------	--	--	--	--

Lozoya, Manny Rosie Castillo--Rm. 21 one of the doors does not lock with their key or the master key, safety issue we had a lock down the other day and we were not able to secure the room.

Safety Issue--ASAP

Barbara Cardenas

25336		Classroom			8/2/2007		187		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	all classrooms			8/2/2007 10:56:11 AM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Lozoya, Manny Need Name Plates and numbers for the following staff members:
 L. Shoemaker
 K. Andrews
 J. Padilla
 D. Gurrola
 R. Rodriguez
 R. Rhodes
 V. Uranga
 J. Gibbs
 G. Cabral
 J. Llañez
 A. Nuñez
 G. Armendariz-Chavez
 V. Henderson
 M. Lugo
 J. Sachs
 S. Vasquez
 P. Gosnell
 A. Avalos
 M. Gaber
 S. Najera
 D. Sanchez
 R. Gose
 And the following numbers :28,29,30,31,32,33,36,37,38,39,40,42,43,44,45,46,47,48,49,50,51,

Barbara Cardenas

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: San Miguel ES

25374					8/3/2007		186		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/3/2007 8:38:24 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny rm21/door will not lock.please ck this door /damage to core

Danny Vega

26751					9/6/2007		152		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2007 1:51:36 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny Rm 4 - need to check lock.

Barbara Cardenas

27008					9/14/2007		144		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/14/2007 7:44:11 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel need bob-cat w/sweeper attachment/planning to restripe parking lots on school break.this is mysecond request for boob-cat

Danny Vega

27210	Cafeteria	Cafeteria			9/20/2007		138		\$0.00
-------	-----------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/20/2007 7:43:01 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny WALK-IN TEMPS. ALL THREE DIFFERENT 42 / 35 / 45

EVA MIRANDA SNP MGR 233-2860

Jacqueline Aguilar

27217	Classrooms	Classroom			9/20/2007		138		\$0.00
-------	------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	33			9/20/2007 8:54:47 AM				
--------	------------------	----	--	--	----------------------	--	--	--	--

Villalobos, Margret Classroom has a squeakyvisitor that is leaving presents all over the computers. Need traps.

Deanna Gurrola--Rm.33

Barbara Cardenas

28144	Cafeteria	Cafeteria			10/15/2007		113		\$0.00
-------	-----------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/15/2007 3:10:03 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny WALK-IN REFRIGERATOR IS STILL NOT WORKING PROPERLY IT'S AT 55 DEGREES - MANAGER HAD TO LEAVE FREEZER DOOR SLIGHTLY AJAR TO KEEP THE REFRIGERATOR AREA COOL.
EVA MIRANDA - SNP MANAGER 233-2860

Alma Terrell

28874					11/4/2007	11/10/2007	93		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				11/4/2007 12:16:46 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vega, Danny Monthly - San Miguel ES Monthly FE Inpsection - Refer to PMschedule details.

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: San Miguel ES

28909					11/4/2007	11/12/2007	93		\$0.00
Medium	Work In Progress				11/4/2007 12:16:59 AM				
Vega, Danny		Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PMSchedule details.							
Margret Villalobos									

28921					11/4/2007	11/12/2007	93		\$0.00
Medium	Work In Progress				11/4/2007 12:17:04 AM				
Vega, Danny		Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PMSchedule details.							
Margret Villalobos									

29031	Cafeteria	Cafeteria			11/7/2007		90		\$0.00
Medium	Work In Progress				11/7/2007 9:40:29 AM				
Orozco, Danny		AS PER HEALTH INSPECTION: SANITIZER REGISTERING BELOW THE 50 PPM MINIMUM: ECOLAB CHECK DISHMACHINE, REPLACED PICKUP PROBE, SEVERAL FINAL RINSE NOZZLES CLOGGED, UNABLE TO UNPLUG TWO OF THEM. ALL FINAL RINSE NOZZLES OPENINGS ARE TOO LARGE, SPRAYING TOO MUCH WATER. THIS CAUSES AN INCREASE IN WATER USAGE, ENERGY TO HEAT THE WATER, RINSE AID USAGE, -- ALL RINSE NOZZLES SHOULD BE REPLACED.							
		AIDA SALCEDO - SNP COMPLIANCE MANAGER 882-6772 EVA MIRANDA- SNP MANAGER 233-2860							
Alma Terrell									

29729					12/3/2007		64		\$0.00
Medium	Work In Progress				12/3/2007 9:41:08 AM				
Solis, Lorenzo		boiler is down /pump is leaking /back-up pump is down also							
Danny Vega									

29866					12/6/2007		61		\$0.00
Medium	Work In Progress				12/6/2007 1:27:24 PM				
Ontiveros, Joe		pump house main shut-off valve (gate valve 2 in.) wont close to main bldg.need to replace .ck annexvalves also							
Danny Vega									

30312					1/6/2008	1/27/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:29:02 AM				
Orozco, Danny		Monthly - San Miguel ES Range Hood Cleaning - Refer to PMSchedule details.							
Margret Villalobos									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: San Miguel ES									
30925					1/24/2008		12		\$0.00
Medium	Work In Progress				1/24/2008 2:56:17 PM				
Lozoya, Manny	rm#10 needs to be re-cored off key/this is assitant principals office/high priority test papers are to be kept in this office. please re-core asap								
Danny Vega									
30931					1/24/2008		12		\$0.00
Medium	Work In Progress				1/24/2008 3:05:52 PM				
Lozoya, Manny	rm 32 restroom door needs keyed door knob placed thru outside-only to be opened by teacher when needed- thanks please stop by asap								
Danny Vega									
30997	Classrooms	Portables			1/28/2008		8		\$0.00
Medium	Work In Progress	36			1/28/2008 3:45:35 PM				
Lozoya, Manny	Sylvia Najera--Rm. 36 Lost her classroom key needs a replacement								
Barbara Cardenas									
31134	Cafeteria	Cafeteria			1/31/2008		5		\$0.00
Medium	Work In Progress				1/31/2008 2:42:41 PM				
Orozco, Danny	WATER IS LEAKING BEHIND THE DISHMACHINE EVA MIRANDA - SNP MANAGER 233-2860								
Alma Terrell									
31216					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:43 AM				
Vega, Danny	Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
31227					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:47 AM				
Vega, Danny	Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
31251					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:56 AM				
Vega, Danny	Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
Count: 28 Work Orders	Avg. Age of WO's		102	Total for San Miguel ES			0	\$0.00	

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
26407					8/29/2007		160		\$0.00
Medium	Work In Progress				8/29/2007 12:55:06 PM				
Lozoya, Manny		NEED TO PUT LOCKS ON ELECTRICAL PANELS AT NEW PORTABLES.							
Gerardo Marquez									
26772					9/6/2007		152		\$0.00
Medium	Work In Progress				9/6/2007 3:52:06 PM				
Villalobos, David		DAVID, NEED TO CHECK OUT MOP SINK IN C-WING (CASA ROJA) STILL LEAKING.							
Gerardo Marquez									
27412					9/25/2007		133		\$0.00
Medium	Work In Progress				9/25/2007 3:09:02 PM				
Castillo, Carlos		CALI; WILL NEED YOU TO RUN POWER TO MARQUEE.							
Gerardo Marquez									
24432					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:59 AM				
Villalobos, David		Yearly - Santa Teresa ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24433					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:59 AM				
Villalobos, David		Yearly - Santa Teresa ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
25814		Mechanical Room			8/13/2007		176		\$0.00
Medium	Work In Progress	MECHANICAL			8/13/2007 4:50:29 PM				
Lozoya, Manny		NEED KEY FOR NEW PE COACH TO OPEN BOTH THE MECHANICAL ROOM AND STORAGE ROOM NEXT TO CAFETERIA. THANKS.							
Rita Mendez									
26342					8/28/2007		161		\$0.00
Medium	Work In Progress				8/28/2007 8:17:38 AM				
Ambriz, Jose		STERLING UNIT TO CAFET. PREP AREA IS NOT WORKING. ACTUATOR TO THE LOUVERS IS STUCK.							
Gerardo Marquez									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

26401		Classroom			8/29/2007		160		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	RM 102			8/29/2007 10:14:40 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
 WE NEED KEYS TO BE MADE FOR THE FOLLOWING CLASSROOMS: RM 102 KEY #IS33, RM 103 KEY #IS41 AND RM 204 KEY #IS64. THANK YOU MANNY. (ONE OF EACH).

Rita Mendez

26488					8/31/2007		158		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Marquee			8/31/2007 7:40:39 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Marquez, Gerardo
 Please proceed with the installation of the marquee for this site. It has been delivered to the Purchasing Warehouse. Gerry need to pour the foundation.

Michael Munoz

26489					8/31/2007		158		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Marquee			8/31/2007 7:42:56 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Castillo, Carlos
 Installation of the marquee for this site, Kali need electrical hook-up.

Michael Munoz

26862		Classroom			9/10/2007		148		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	RM 108			9/10/2007 4:15:29 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Lozoya, Manny
 NEED 2 KEYS TO BE MADE FOR CLASSROOM. 4 STAFF MEMBERS WORKING IN THIS CLASSROOM. KEY #IS36. THANK YOU.

Rita Mendez

27365					9/24/2007		134		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/24/2007 11:05:33 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
 ALL 3 EMERG. LIGHTS AT CENTER AREA OF PORTABLE C&D FAILED TO COME ON DURING M. INSP. PLEASE CHECK THEM OUT.

Gerardo Marquez

27366					9/24/2007		134		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/24/2007 11:10:28 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
 NEED TO CHECK OUT EXIT SIGNS THAT FAILED DURING M. INSP. THEY ARE AT RM. 211, LIBRARY MAIN ENTRANCE, & HALLWAY BY FACULTY RRMS.

Gerardo Marquez

28177		Cafeteria			10/16/2007		112		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/16/2007 9:59:05 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny
 SPRAYER TO DISHWASHER AREA IS BROKEN - NEEDS TO BE REPLACED

PATRICIA SANCHEZ - SNP MANAGER 589-3439

Alma Terrell

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

28365 Cafeteria 10/22/2007 106 \$0.00

Medium Work In Progress 10/22/2007 9:50:27 AM

Orozco, Danny WALK-IN REFRIGERATOR IS AT 45 DEGREES (AIDA SALCEDO CALLED IN WORK ORDER)

PAT SANCHEZ - SNP MANAGER 589-3439

Alma Terrell

28532 10/25/2007 103 \$0.00

Medium Work In Progress 10/25/2007 11:13:31

Ronquillo, Ruben WINDOWS IN FRONT LOBBY LOST VAPOR BETWEEN DOUBLE PANES. PLEASE FIX.

Michael Munoz

29023 11/7/2007 90 \$0.00

Medium Work In Progress 11/7/2007 8:46:04 AM

Boyd, David STUCCO IS STARTING TO CRACK AND CHIP AT PARAPETS. BLOCK WORK IS ALSO STARTING TO SEPARATE AT MORTAR JOINTS. SHEETROCK IS ALSO BREAKING ABOVE DOORS, AND AROUND DR. JAMBS. EXPANSION JOINTS IN FLOORS SEEM TO BE SEPARATING , THUS CAUSING VCT. TO CRACK.

Gerardo Marquez

29027 11/7/2007 90 \$0.00

Medium Work In Progress 11/7/2007 9:19:35 AM

Ontiveros, Guadalupe LUPE; COULD YOU DELIVER A COUPLE OF LOADS OF THE BROWN SCREENING . I NEED TO SPREAD SOME AROUND BY THE PORTABLES AND FRONT AREAS, WHERE THE RAINS HAVE WASHED IT AWAY. THANKS.

Gerardo Marquez

29375 11/20/2007 77 \$0.00

Medium Work In Progress 11/20/2007 3:03:04 PM

Castillo, Carlos CALI; I STILL HAVN'T RECIEVED THE MATERIAL TO FORM THE REST OF THE SIDEWALK IN ORDER TO POUR THE CONCRETE. YOU CAN TRENCH AND LAY THE ELECTR. CONDUIT.

Gerardo Marquez

29614 12/2/2007 12/8/2007 65 \$0.00

Medium Work In Progress 12/2/2007 12:29:52 AM

Marquez, Gerardo Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

29665					12/2/2007	12/10/2007	65		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:13 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PMschedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

29676					12/2/2007	12/10/2007	65		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:17 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

29709					12/2/2007	12/3/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:30 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo		Monthly - Santa Teresa ES C-6 Quarterly HP - Refer to PMschedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

29712					12/2/2007	12/3/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:31 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo		Monthly - Santa Teresa ES A-6 Quarterly PUG - Refer to PMschedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

29714					12/2/2007	12/3/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:32 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo		Monthly - Santa Teresa ES A-11 Quarterly ERV - Refer to PMschedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

29716					12/2/2007	12/3/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:33 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo		Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PMschedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

29898					12/7/2007		60		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/7/2007 9:17:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		DAVID; THE FAUCET AT THE NURSES OFFICE IS LEAKING. I THINK THE SEATS NEED TO BE REPLACED. WOULD YOU PLEASE CHECK IT OUT.							
-------------------	--	--	--	--	--	--	--	--	--

Gerardo Marquez									
-----------------	--	--	--	--	--	--	--	--	--

30313					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:02 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PMschedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

30642 1/15/2008 21 \$0.00

Medium Work In Progress 1/15/2008 1:17:27 PM

Villalobos, David 2ND REQUEST! FAUCET AT SINK IN NURSES OFFICE IS LEAKING. SENT 1ST REQUEST ON 12/7/07. LEAK IS GETTING WORSE AND NURSE IS GETTING IMPATIENT. HAVE THE SAME PROBLEM IN THE TEACHERS LOUNGE. I THINK THE SEATS NEED REPLACING.

Gerardo Marquez

30643 1/15/2008 21 \$0.00

Medium Work In Progress 1/15/2008 1:22:09 PM

Gonzales, Angel ANGEL, WOULD YOU PUT ME ON THE SCHEDULE FOR THE BOBCAT. I NEED IT TO REMOVE THE DIRT THAT THE CONTRACTOR MOVED WHERE THEY POURED THE SLAB FOR THE DUMPSTERS, AND ALSO TO REMOVE THE OLD SAND BAGS. THANKS.

Gerardo Marquez

30644 1/15/2008 21 \$0.00

Medium Work In Progress 1/15/2008 1:26:14 PM

Munoz, Michael ATTN. MIKE. THE SLAB FOR THE DUMPSTERS HAS ALREADY BEEN POURED. NEED TO HAVE FENCE CONTRACTOR BUILD FENCE , AND GATES LIKE THE ONE IN THE PICTURE YOU SENT US. PLEASE BE SURE THEY INCLUDE THE SLATS.

Gerardo Marquez

31048 1/30/2008 6 \$0.00

Medium Work In Progress 1/30/2008 8:04:07 AM

Ambriz, Jose JOSE, THE TEACHER IN RM. 209 IS COMPLAINING THAT THE HVAC. IS TO LOUD. WOULD YOU CHECK OUT THE COMPRESSOR . AS YOU SAID , MAYBE A BLANKET WOULD HELP.

Gerardo Marquez

31049 1/30/2008 6 \$0.00

Medium Work In Progress 1/30/2008 8:06:20 AM

Castillo, Carlos CALI, WE NEED TO INSTALL AN OUTLET BOX BY THE MARQUEE, AND ALSO AT THE SERVICE PANEL. THANKS.

Gerardo Marquez

31217 2/3/2008 2/11/2008 2 \$0.00

Medium Work In Progress 2/3/2008 12:30:43 AM

Marquez, Gerardo Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PMschedule details.

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

31228					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:47 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

31237					2/3/2008	2/9/2008	2		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

31269					2/4/2008		1		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/4/2008 2:05:25 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose		JOSE; THE HVAC PUMP IN RM. 203 IS MAKING A LOUD NOISE. IT SEEMS TO BE THE IMPELLER. WOULD YOU CHECK IT OUT?							
--------------	--	---	--	--	--	--	--	--	--

Gerardo Marquez

31270					2/4/2008		1		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/4/2008 2:09:30 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose		EXHAUST FAN TO COMPUTER LAB WAS NEVER INSTALLED. NEED TO INSTALL ONE.(DUCTING, AND POWER SWITCH ARE IN PLACE, BUT FOR SOME REASON POWER WAS NOT RUN TO FAN BY CONTRACTOR.)							
--------------	--	--	--	--	--	--	--	--	--

Gerardo Marquez

Count: 38 Work Orders		Avg. Age of WO's 87				Total for Santa Teresa ES	0		\$0.00
------------------------------	--	----------------------------	--	--	--	----------------------------------	----------	--	---------------

Location: Santa Teresa HS

27429					9/25/2007		133		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/25/2007 4:22:41 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael		please pave w/ asphalt where water break was repaired next to cafeteria							
----------------	--	---	--	--	--	--	--	--	--

Michael Munoz

27496					9/27/2007		131		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/27/2007 8:31:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph		NEED THREE (3) EA. HON LOCKS FOR FILING CABINETS, OVAL AND, ROUND.							
-------------	--	--	--	--	--	--	--	--	--

Arturo Nunez

27614					9/30/2007	10/8/2007	128		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium	Work In Progress				9/30/2007 12:17:30 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Nunez, Arturo		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

29446					11/27/2007		70		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/27/2007 10:23:34				
--------	------------------	--	--	--	---------------------	--	--	--	--

Gonzales, Angel		MOFFLER NEEDS TO BE REPLACE FROM TRUCK #8 THANK YOU							
-----------------	--	---	--	--	--	--	--	--	--

Joel Herrera

27017					9/14/2007		144		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/14/2007 10:37:07 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe		Hydrolic System on 935 is not working.							
Guadalupe Ontiveros									

26865					9/11/2007		147		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/11/2007 8:02:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben		BROKEN WINDOW AT R.O.T.C CLASS ROOM SINGLE GLASS SIZE 28 1/4 X29 3/4 A.S.A.P							
------------------	--	--	--	--	--	--	--	--	--

Joel Herrera

24349					7/1/2007	7/9/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:42 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

25604		Custodial			8/8/2007		181		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/8/2007 10:23:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		NEED ONE MASTER -N- ONE M-113 KEY FOR NEW EMPLOYEE A.S.A.P. THANK YOU.							
---------------	--	--	--	--	--	--	--	--	--

Luis Murillo

26176					8/23/2007		166		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/23/2007 8:04:10 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		URGENTE BROKEN DOORS LOCK AND MALLEY AT OUTSIDE DOORS AT G.Y.M AREA.							
---------------	--	--	--	--	--	--	--	--	--

Joel Herrera

24347					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:42 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo		Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24348					7/1/2007	7/7/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:42 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

24419					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24420					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24421					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24422					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24423					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24424					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24425					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24426					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
25499		Cafeteria			8/6/2007		183		\$0.00
Medium	Work In Progress				8/6/2007 10:44:10 AM				
Orozco, Danny		NEEDS WATER HOSE FOR USE NEAR DISHMACHINE (DANNY IS AWARE OF THIS REQUEST)							
		OLGA BUSTAMANTE - SNP MANAGER 589-5332							
Alma Terrell									
25575					8/7/2007		182		\$0.00
Medium	Work In Progress				8/7/2007 12:41:15 PM				
Castillo, Carlos		NEED AN INTERMATIC TIMER FOR VOCATIONAL BUILDING A.C. UNITS, IT IS NOT KEEPING PROPER TIME. / INTERMATIC TIME CONTROLS MODEL : T7801 B.C. 7 DAY , 4 POLE , 2N.O., 2 N.C. 27/7							
Arturo Nunez									
25748					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 8:12:46 AM				
Ambriz, Jose		NEED SOME ASSISTANCE ON A.C. UNITS ON 600'S WING. BREAKERS #90 FOR EF-17, AND #94 FOR EC -2, WILL NOT STAY ON, NEED TO TROUBLE SHOOT.							
Arturo Nunez									
26314					8/27/2007		162		\$0.00
Medium	Work In Progress				8/27/2007 3:46:27 PM				
Lozoya, Manny		EMA VILLALOBOS NEEDS COPY OF MASTER KEY M13 AND THE KEYS ISSUED TO ME THIS YEAR DO NOT WORK. MA 61 AND MA 62							
Joel Herrera									
26477					8/30/2007		159		\$0.00
Medium	Work In Progress				8/30/2007 3:46:27 PM				
Lozoya, Manny		MR.VALENCIA WANTS TO 54B ROOM NEEDS TO BE REKEYED TO MA 51 TO 54 A AND 54 B A.S.S.A.P							
Joel Herrera									
26790					9/7/2007		151		\$0.00
Medium	Work In Progress				9/7/2007 11:56:18 AM				
Carrasco, Danny		NEED 300 EA. ONE INCH LOCKING HASPS FOR GIRLS AND BOYS DRESSING ROOM LOCKERS,AND 2 BOXES SCREWS FOR METAL USE.							
Arturo Nunez									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

27646					9/30/2007	10/21/2007	128		\$0.00
-------	--	--	--	--	-----------	------------	-----	--	--------

Medium	Work In Progress				9/30/2007 12:17:43 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny Monthly- Santa Teresa HS Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

27979					10/8/2007		120		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/8/2007 3:51:38 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose
NEED TO HAVE AN AURORA CIRCULATING WATER PUMP, FOR PUMP #1. 300'S WING. REPAIED OR REPLACED, IT IS LEAKING WATER. MODEL #93-15607-2 , G.P.M. 75, H.F. 48, R.P.M. 1750, TYPE 344 A B F .

Arturo Nunez

28162	Cafeteria (2005)	Cafeteria			10/16/2007		112		\$0.00
-------	------------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/16/2007 8:04:31 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David
NEED TO INSTALL VALVE BOX WITH COVER AT PARKING LOT EAST OF CAFETERIA

David Villalobos

28573	Cafeteria (2005)	Cafeteria			10/26/2007		102		\$0.00
-------	------------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/26/2007 9:01:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny
Having problems with Dishmachine - Tom/Ecolab checked the machine - his recommendation: No sanitizer registering at the final rinse -- final rinse pressure too high at 40 psi, causing reduced levels of sanitizwer (a Pressure Regulator is needed)

Aida Salcedo - SNP Coord. 882-6772 & Olga Bustamante - SNP Manager 589-5332

Alma Terrell

28774					11/1/2007		96		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/1/2007 8:35:20 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
NEED 12 EA. MHC 100/U/M4K ALTO LIGHT BULBS, 6 EA. MH175/U LIGHT BULBS. 6 EA. 277V MULTI TAP BALAST FOR NEW BUILDING LIGHT FIX.

Arturo Nunez

28984					11/6/2007		91		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/6/2007 9:28:54 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
NEED A 3 PHASE CONTACTOR: SD CLASS8501 TYPE PHA SERIES A , FOR AIR COMPRESSOR ON VOC. BLDB.

Arturo Nunez

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

29156	Cafeteria (2005)	Cafeteria			11/13/2007		84		\$0.00
-------	------------------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2007 9:44:53 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny
 WASHING MACHINE THROWING ALOT OF WATER FROM BEHIND THE MACHINE - THEY HAVE TO MOP IT UP CONSTANTLY.

OLGA BUSTAMANTE - SNP MANAGER 589-5332

Alma Terrell

29451	Gymnasium				11/27/2007		70		\$0.00
-------	-----------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/27/2007 12:41:32				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David
 WE NEED REPLACE SINCK'S FAUCETS AND REPAIR URINAL'S LEACK AT NEW BOYS LOCKER ROOM AT G.Y.M AREA

Joel Herrera

29630					12/2/2007	12/8/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:29:59 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Nunez, Arturo
 Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PMschedule details.

Margret Villalobos

29636					12/2/2007	12/23/2007	65		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:01 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny
 Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PMschedule details.

Margret Villalobos

29740					12/3/2007		64		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/3/2007 12:36:05 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
 WE NEED DEAT BOILT IN CLASS #24 AND ALSO RELOCATED TWO LOCKS AT CLASS ROOM #24 ADD ANNEX BUILDING

Joel Herrera

30171					12/18/2007		49		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/18/2007 9:40:57 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Margret
 NEED TO HAVE WORK STATION UP GRADE, CAN'T GET TEMP, DIANOSTICS, ETC. TO FAN COIL UNITS, AND AIR HANDLER UNITS.

Arturo Nunez

30172					12/18/2007		49		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Safety	Work In Progress				12/18/2007 9:46:14 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
 NEED TO REPAIR OR REPLACE 220V. ELECTRICAL CONNECTION FOR WELDERS, SOME ARE BROKEN, OTHERS ARE CRACKED. SAFETY ISSUE.

Arturo Nunez

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

30266					1/6/2008	1/12/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

30284					1/6/2008	1/14/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.

Margret Villalobos

30314					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

30750					1/17/2008		19		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2008 2:17:17 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph MR. VALENCIA HE NEEDS KEY ON HIS GAVENETE AT R.O.T.C. CLASS ROOM

Joel Herrera

30927					1/24/2008		12		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/24/2008 3:00:24 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose NEED TO HAVE ARMSTRONG CIRCULATING PUMP #2 , REPAIRED, LEAKING WATER AND OIL.

Arturo Nunez

30936		Classroom			1/24/2008		12		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	SPED classroom			1/24/2008 3:24:59 PM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Castillo, Carlos Need electrical outlets installed near cabinet at STHS special ed classroom (please call Silver for questions)

Cora Ramirez

31020					1/29/2008		7		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/29/2008 12:16:55 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph CELIA VALDES SHE NEEDS TWO COPIES OF MC53

Joel Herrera

31051					1/30/2008		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 8:58:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Margret As per Jose Ambriz, there is a break in the link to new wing (Cafe). When he connects directly to the BCU he only see one side. Faxed 1/30/08 2/1/08 - Eddie came out to site E030573

Jose Ambriz

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
31121					1/31/2008		5		\$0.00
Medium	Work In Progress				1/31/2008 9:13:36 AM				
Lara, Ralph		MR. WAGNER HE NEEDS TWO KEYS FROM HIS CLASS ROOM							
Joel Herrera									
31135	Cafeteria (2005)	Cafeteria			1/31/2008		5		\$0.00
Medium	Work In Progress				1/31/2008 2:44:30 PM				
Moncayo, Fernando		WATER IS LEAKING FROM DISHMACHING - IGNACIA RELAYED MESSAGE TO SNP DEPT.							
		OLGA BUSTAMANTE - SNP MANAGER 589-5332							
Alma Terrell									
31170					2/1/2008		4		\$0.00
Medium	Work In Progress				2/1/2008 1:08:49 PM				
Lara, Ralph		LOCK AT DUGOUTS AT SOFTBALL NOT OPENING. PLEASE CHECK.							
Guadalupe Ontiveros									
31293					2/5/2008		0		\$0.00
Medium	Work In Progress				2/5/2008 8:36:03 AM				
Lara, Ralph		MEETING ROOMS DOOR LOCK IT DOESNT LOCK AT LIBRARY							
Joel Herrera									
31219					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:44 AM				
Herrera, Joel		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
31229					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:48 AM				
Herrera, Joel		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
31252					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:56 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
Count: 53 Work Orders			Avg. Age of WO's 109			Total for Santa Teresa HS	0		\$0.00

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

25165					7/27/2007		193		\$0.00
Medium	Work In Progress				7/27/2007 2:34:47 PM				
Mijarez, Jaime		Request for sidewalk curb sides be painted yellow (are now red)							
Laura Parra									
24427					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24428					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24429					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24430					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24431					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:59 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24498					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:16:27 AM				
Mijarez, Jaime		Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PMschedule details.							
Alfredo Holguin									
24501					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:16:29 AM				
Mijarez, Jaime		Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PMschedule details.							
Alfredo Holguin									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa MS							
24686	North Building	Office			7/11/2007		209		\$0.00
Medium	Work In Progress	North and South			7/11/2007 7:47:03 AM				
Mijarez, Jaime		Request to paint offices located in the north and south building. As per Ms. Lovelace. Principals offices Assistant Principal Reception Area Counselor Administrative Intem Data Registrar Secretary Bathrooms							
Laura Parra									
24791					7/16/2007		204		\$0.00
Medium	Work In Progress				7/16/2007 8:34:47 AM				
Lozoya, Manny		S.bldg room 54 needs a new door handle and assembly with core. Can this be done before school starts.							
Jaime Mijarez									
24993	South	Portables			7/23/2007		197		\$0.00
Medium	Work In Progress	P 2 B and 3 B			7/23/2007 1:35:16 PM				
Lozoya, Manny		Please repair locks on Portables 2 B and 3B. Keys get stuck in key hole and are unable to remove.							
Laura Parra									
25164	North Building	Office			7/27/2007		193		\$0.00
Medium	Work In Progress	Round Room -			7/27/2007 2:28:41 PM				
Lozoya, Manny		Need to install door lock in the round room. Room will become principals office and needs to be locked. 8/28 - Principal is requesting status - mkv							
Laura Parra									
25332	South	Choral			8/2/2007		187		\$0.00
Medium	Work In Progress	Choir Room			8/2/2007 10:15:43 AM				
Lozoya, Manny		Please re-key office in Choir Room. Office will be assigned to social worker. Please see secretary							
Laura Parra									
25334		Classroom			8/2/2007		187		\$0.00
Medium	Work In Progress	Room 35			8/2/2007 10:31:47 AM				
Lozoya, Manny		Need extra key for Room 35 for new staff member							
Laura Parra									
25386		Classroom			8/3/2007		186		\$0.00
Medium	Work In Progress	Room 54			8/3/2007 12:14:37 PM				
Lozoya, Manny		Door does not lock. As pe Mr. Carmona its missing the tumbler to place key in.							
Laura Parra									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

25722	South	Classroom			8/10/2007		179		\$0.00
-------	-------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	ROOM 35			8/10/2007 2:28:12 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Laura Parra
Need key for filing cabinet

25723	South	Classroom			8/10/2007		179		\$0.00
-------	-------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	36 B			8/10/2007 2:33:23 PM				
--------	------------------	------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Laura Parra
Need key for filing cabinet

25724	North Building	Office			8/10/2007		179		\$0.00
-------	----------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Data			8/10/2007 2:34:10 PM				
--------	------------------	------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Laura Parra
Please re-key data registrar door

25837					8/14/2007		175		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/14/2007 10:09:09 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose
Please order for condensate pump replacement. 35 ea. little giant pumps cat#554200, vcc- 20uls or 2ouls, 35 ea. 1/2" 90 deg. ells. SlipxTHD, 35 ea. SPRTB-6 24x24 metal grilles, 35 ft 3/4"OD x 5/8" ID clear vinyl tube, box of 3 amp fuses, box of 1 amp fuses, box of orange electrical wire nuts, and box of insulated female and male solderless terminals.

Jaime Mijarez

25886	South Building	Classroom			8/15/2007		174		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	room 47			8/15/2007 11:06:16 AM				
--------	------------------	---------	--	--	-----------------------	--	--	--	--

Mijarez, Jaime
Dana Hamel
Install a new pencil sharpener in room 47

25965	North Building	Portables			8/17/2007		172		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	P 3A			8/17/2007 12:38:11 PM				
--------	------------------	------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Laura Parra
Entrance door lock and key are getting stuck. Key will not open or lock door.

26078		Classroom			8/21/2007		168		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Room 21			8/21/2007 10:38:21 AM				
--------	------------------	---------	--	--	-----------------------	--	--	--	--

Castillo, Carlos
Laura Parra
Outlet is loose. Computer cable keeps coming loose.

26183	South	Classroom			8/23/2007		166		\$0.00
-------	-------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/23/2007 8:53:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Ismael Rodriguez
manny, a teacher is requesting a key for his room to get in see mr. rodriguez. Also ms. lovelace need the cylinder key to her office. This is the new administrator. thank you. a.s.a.p.

2/5/2008 6:09:38 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

26272					8/27/2007		162		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/27/2007 8:51:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		Storm drain in back of S.bldg has a section that is bent inward and sand is caving in through a hole. I showed Alfredo Holguin, please give the work order to Alfredo.				ROUTE TO LUPE ASP MIKE 8/30			
----------------------	--	--	--	--	--	-----------------------------	--	--	--

Jaime Mijarez

26357	South	Mechanical Room			8/28/2007		161		\$0.00
-------	-------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Boiler			8/28/2007 11:16:47 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Need key that will open room that is not a 'Q' key.							
---------------	--	---	--	--	--	--	--	--	--

Laura Parra

26928					9/12/2007		146		\$2,383.98
-------	--	--	--	--	-----------	--	-----	--	------------

Medium	Work In Progress				9/12/2007 10:17:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose		Gym a/c's are shutting down. I need parts to keep them running for the volleyball games. There will be a volleyball tournament Sept 13, 14, 15 this weekend.							
--------------	--	--	--	--	--	--	--	--	--

Jaime Mijarez

26930					9/12/2007		146		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/12/2007 10:27:14 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose		North and South bldg condensate failures. I need Joe Ambriz to help me.							
--------------	--	---	--	--	--	--	--	--	--

Jaime Mijarez

27822					10/3/2007		125		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/3/2007 2:16:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		IDENTIFY THE BREAKER THAT GOES TO IRRIGATION CONTROL.							
------------------	--	---	--	--	--	--	--	--	--

Guadalupe Ontiveros

27897	South	Office			10/5/2007		123		\$0.00
-------	-------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	south office			10/5/2007 12:29:40 PM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Lara, Ralph		Need keys for 2 filing cabinets.							
-------------	--	----------------------------------	--	--	--	--	--	--	--

Laura Parra

29907					12/7/2007		60		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/7/2007 10:14:17 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph		Choir room outside door. We are having trouble opening the door with the key.							
-------------	--	---	--	--	--	--	--	--	--

Jaime Mijarez

30716	North Building	Classroom			1/17/2008		19		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room 10			1/17/2008 8:27:51 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Villalobos, David		Faucets are leaking							
-------------------	--	---------------------	--	--	--	--	--	--	--

Laura Parra

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa MS							
30843	South	Choral			1/22/2008		14		\$0.00
Medium	Work In Progress	Choir			1/22/2008 2:48:03 PM				
Lara, Ralph		Need signs over both doors that say "Choir Room"							
Laura Parra									
28261	North Building	Parking Lot			10/18/2007		110		\$0.00
Medium	Work In Progress				10/18/2007 8:49:53 AM				
Gonzales, Angel		lupe,can i borrow the small tracter from riverside to do a small project.see mr.rodriguez or call me thank you.				10/30 - Asp Lupe route to Angel			
Ismael Rodriguez									
28262					10/18/2007		110		\$0.00
Medium	Work In Progress				10/18/2007 8:53:10 AM				
Ambriz, Jose		Gym a/c's. All the wet sections need to be replaced, they are old and corroded. Need to order new ones to replace old ones.							
Jaime Mijarez									
28417	North Building	Cafeteria			10/23/2007		105		\$0.00
Medium	Work In Progress				10/23/2007 12:28:57				
Mijarez, Jaime		Baseboard and walls in kitchen by sinks and dishwashing area need to be replaced. This is by order of the NM Environmental Department and the report and the repair must be completed in 60 days. According to ED this is not the first warning about the repairs in an inspection report				Assign to Jaime and Gerry will assist asp Mike 11/13/07 -mkv			
Dana Hamel									
28722					10/31/2007		97		\$0.00
Medium	Work In Progress				10/31/2007 9:24:59 AM				
Castillo, Carlos		AS PER OUR CONVERSATION, PLEASE PROVIDE A 120 OUTLET FOR THE ENVIRONMENT DEPT.							
Michael Munoz									
29454	North Building	Office			11/27/2007		70		\$0.00
Medium	Work In Progress				11/27/2007 1:54:25 PM				
Lara, Ralph		manny, i need for you to make a key for some kitchen cabnits in the north office as per ms parra.And also check a panic bar ,see mr rodriguez on this one . thank you.							
Ismael Rodriguez									
29516					11/28/2007		69		\$0.00
Medium	Work In Progress				11/28/2007 3:34:25 PM				
Castillo, Carlos		Ms. Mays librarian wants lights replaced in 1st row and to remove big light over circulating desk.							
Jaime Mijarez									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

29979					12/11/2007		56		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/11/2007 8:22:43 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
 North bldg, South bldg, and gym. Locksmiths need to check all new door handle cores and make sure they are opening properly. Architectural products company is replacing all round knob handles and placing the same cores with seven pin. We are getting many complaints from teachers and administrators that doors won't open.

Jaime Mijarez

30315					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
 Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

30823	Gym (1997)	Parking Lot			1/22/2008		14		\$0.00
-------	------------	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/22/2008 9:03:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
 Repair the dripping faucet that continues to cause freezing ice and dangerous conditions

Dana Hamel

30832	South	Classroom			1/22/2008		14		\$0.00
-------	-------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room 50			1/22/2008 11:28:32 AM				
--------	------------------	---------	--	--	-----------------------	--	--	--	--

Lara, Ralph
 Cylinder on door does not unlock, cylinder keeps turning when key is in.

Laura Parra

30838	North Building	Restroom (Girls)			1/22/2008		14		\$0.00
-------	----------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/22/2008 2:09:24 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
 Unisex restroom top floor north building need to have a key CYLINDER THAT ANY KEY WILL OPEN, currently any coin will do and we have found students ditching there.

Dana Hamel

30842	North Building	Classroom			1/22/2008		14		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room 18			1/22/2008 2:46:05 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Castillo, Carlos
 Please remove electrical strip from the floor and pole from the middle of the room

Laura Parra

30844	South	Classroom			1/22/2008		14		\$0.00
-------	-------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room 49			1/22/2008 2:50:38 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Lara, Ralph
 Left door will not open with key. Cylinder turns repeatedly without unlocking.

Laura Parra

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

30845	South	Choral			1/22/2008		14		\$0.00
-------	-------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Choir			1/22/2008 3:11:01 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Castillo, Carlos
Laura Parra
Need active outlets in the west end of the classroom

30935	South Building				1/24/2008		12		\$0.00
-------	----------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/24/2008 3:22:30 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
We are going to need electrical outlets installed at Santa Teresa Middle South Bld IDF. We have currently extended electrical using 15' power strips, but need the outlets relocated closer to the cabinets contact Silver.

Cora Ramirez

31013					1/29/2008		7		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/29/2008 9:36:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
S.bldg water heater room. Need to replace water shut-off valves for irrigation and regulator.

Jaime Mijarez

31221					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime
Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

31230					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime
Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

31253					2/3/2008	2/9/2008	2		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime
Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

31309	Gym (1997)	Athletic Field			2/5/2008		0		\$0.00
-------	------------	----------------	--	--	----------	--	---	--	--------

High	Work In Progress				2/5/2008 12:52:31 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael
LOTS OF CRACKS ON OUTSIDE BASKETBALL COURT. NEED TO REPIAR THEM. STUDENTS CAN TRIP.

Jaime Mijarez

Count: 52 Work Orders			Avg. Age of WO's 119			Total for Santa Teresa MS	0	\$2,383.98	
------------------------------	--	--	-----------------------------	--	--	----------------------------------	----------	-------------------	--

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

25891					8/15/2007		174		\$0.00
Medium	Work In Progress				8/15/2007 12:33:38 PM				
Prospero, Manuel		SET UP SCREEN IN THE COMPUTER LAB.							
Irene Trujillo									
26135					8/22/2007		167		\$0.00
Medium	Work In Progress				8/22/2007 9:00:08 AM				
Prospero, Manuel		PLEASE INSTALL A MARKER BOARD ON THE WALL IN THE LIBRARY.							
Irene Trujillo									
26232					8/24/2007		165		\$0.00
Medium	Work In Progress				8/24/2007 1:20:27 PM				
Prospero, Manuel		2ND REQUEST - PORTABLES NEED PAINTING.							
Irene Trujillo									
24416					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:57 AM				
Villalobos, David		Yearly - Sunland Park ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24417					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:57 AM				
Villalobos, David		Yearly - Sunland Park ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24418					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:15:57 AM				
Villalobos, David		Yearly - Sunland Park ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24527					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:16:39 AM				
Prospero, Manuel		Yearly - Sunland Park ES Exit Sign Test: Annual - Refer to PMschedule details.							
Alfredo Holguin									
24528					7/1/2007	8/1/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:16:39 AM				
Prospero, Manuel		Yearly - Sunland Park ES Emer. Light Test: Annual - Refer to PMschedule details.							
Alfredo Holguin									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunland Park ES							
24529					7/1/2007	7/9/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:16:40 AM				
Prospero, Manuel		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PMschedule details.							
Alfredo Holguin									
24530					7/1/2007	7/9/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:16:40 AM				
Prospero, Manuel		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Alfredo Holguin									
24531					7/1/2007	7/7/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:16:40 AM				
Prospero, Manuel		Monthly - Sunland Park ES Monthly FE Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24532					7/1/2007	7/9/2007	219		\$0.00
Medium	Work In Progress				7/1/2007 12:16:41 AM				
Prospero, Manuel		Monthly - Sunland Park ES Roof Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24962					7/20/2007		200		\$0.00
Medium	Work In Progress				7/20/2007 11:45:33 AM				
Lozoya, Manny		Please help open two filing cabinets that were accidentally locked during the summer break.							
Irene Trujillo									
25022					7/24/2007		196		\$0.00
Medium	Work In Progress				7/24/2007 11:02:33 AM				
Lozoya, Manny		INSTALL A LOCK ON FILING CABINET IN ROOM 10.							
Irene Trujillo									
25405					8/3/2007		186		\$0.00
Medium	Work In Progress				8/3/2007 3:33:00 PM				
Lozoya, Manny		CLASSROOM 28 - PLEASE INSTALL A DOOR KNOB WITH A LOCK IN THE RESTROOM.							
Irene Trujillo									
25805					8/13/2007		176		\$0.00
Medium	Work In Progress				8/13/2007 3:25:32 PM				
Prospero, Manuel		PORTABLE D - PLEASE INSTALL NEW PENCIL SHARPENER.							
Irene Trujillo									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

25127 Main Building 7/26/2007 194 \$0.00

Medium Work In Progress 7/26/2007 3:24:02 PM

Prospero, Manuel 2nd request - Tile in nurse's office is not level. Safety hazard concern, as student/staff may possibly trip and be injured. 8/2 - Route to M. Prospero. This issue was discussed w/him last year. Mike.

Irene Trujillo

25333 8/2/2007 187 \$0.00

Medium Work In Progress 8/2/2007 10:31:13 AM

Lozoya, Manny Please key the following keys to open the back door in the grade level respective halls. Kinder - S. Aguilar TA39 Rm24, L. Oaxaca TA24 Rm 25, S. Barraza TA27 Rm 21 - First Grade- S. Gardea TA35 Rm 38, G. Contreras TA36 Rm 39, and TA37 in the office.

Irene Trujillo

25395 Cafeteria 8/3/2007 186 \$0.00

Medium Work In Progress 8/3/2007 2:20:24 PM

Orozco, Danny COLD UNIT TO SERVING LINE IS NOT COLD
MARINA RAMIREZ - SNP MANAGER 589-2524

Alma Terrell

25396 Cafeteria 8/3/2007 186 \$0.00

Medium Work In Progress 8/3/2007 2:22:25 PM

Orozco, Danny HAVING PROBLEMS WITH BOTTOM BLODGETT OVENS (1 OVER HEATS AND 1 HEATS UP FOR A WHILE THEN SHUTS OFF.

MARINA RAMIREZ - SNP MANAGER - 589-2545

Alma Terrell

25431 8/5/2007 8/11/2007 184 \$0.00

Medium Work In Progress 8/5/2007 12:14:42 AM

Prospero, Manuel Monthly - Sunland Park ES Monthly FE Inspection - Refer to PMs schedule details.

Margret Villalobos

25469 8/5/2007 8/13/2007 184 \$0.00

Medium Work In Progress 8/5/2007 12:14:57 AM

Prospero, Manuel Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PMs schedule details.

Margret Villalobos

25479 8/5/2007 8/13/2007 184 \$0.00

Medium Work In Progress 8/5/2007 12:15:01 AM

Prospero, Manuel Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PMs schedule details.

Margret Villalobos

2/5/2008 6:09:38 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

25550					8/7/2007		182		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/7/2007 9:12:38 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny PLEASE RE-KEY TA3 TO OPEN THE SIDE FRONT DOOR IN THE HALLWAY FOR 5TH AND 6TH GRADE.

Irene Trujillo

25804					8/13/2007		176		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 3:24:36 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel PORTABLE D - NEED A SMALL BOARD SCREWED TO WALL. ALSO, NEED A BACKPACK RACK FIXED.

Irene Trujillo

25848					8/14/2007		175		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/14/2007 2:01:40 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel LIBRARY - NEED TO HAVE HOOKS PLACED INSIDE STORAGE ROOM FOR BOOK PUPPETS. ALSO NEED NAILS TO HANG CHARTS.

Irene Trujillo

25973		Cafeteria			8/17/2007		172		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/17/2007 3:02:49 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny BOILER KEEPS ON SHUTTING OFF - THE SNP LADIES CONSTANTLY NEED TO GO OUTSIDE TO BACK ON.

MARINA RAMIREZ - SNP MANAGER 589-2545

Alma Terrell

25974		Cafeteria			8/17/2007		172		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/17/2007 3:04:40 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny THERE IS A WATER LEAK UNDER DISHWASHER, NOT SURE IF WATER IS LEAKING FROM THE DISPOSAL, WATER LINE TO DISHWASHER.

MARINA RAMIREZ - SNP MANAGER 589-2545

Alma Terrell

26236					8/24/2007		165		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/24/2007 1:31:54 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David CLASSROOM 25 - WATER FLUSING (IT IS STUCK) IN COMMODE. WATER RUNS FOR 15-20 MINS. THEN STOPS.

Irene Trujillo

26344					8/28/2007		161		\$5,300.00
-------	--	--	--	--	-----------	--	-----	--	------------

Medium	Work In Progress				8/28/2007 8:31:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Holguin, Alfredo Provide services and materials for installation of new controller to control existing lighting. Joe V. picked up PO on 9/4-mkv

Alfredo Holguin

2/5/2008 6:09:38 PM

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

26456					8/30/2007		159		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/30/2007 1:00:47 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		CLASSROOM #37 - BACK DOOR IS TOO HARD TO OPEN WITH KNOB AND SQUEAKS ALOT WHEN OPENED.							
---------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

26530					9/2/2007	9/8/2007	156		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:09 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Monthly FE Inspection - Refer to PMschedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

26568					9/2/2007	9/10/2007	156		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:24 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PMschedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

26578					9/2/2007	9/10/2007	156		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:28 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

26623					9/2/2007	9/3/2007	156		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-1 Semiannual EVS - Refer to PMschedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

26624					9/2/2007	9/3/2007	156		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-8 Quarterly HPW Unit - Refer to PMschedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

26625					9/2/2007	9/3/2007	156		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-2 Quarterly H/C IREH - Refer to PMschedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

26626					9/2/2007	9/3/2007	156		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-1 Semiannual MCD - Refer to PMschedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

26627					9/2/2007	9/3/2007	156		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-1 Semiannual MCS2 - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

26628					9/2/2007	9/3/2007	156		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-6 Quarterly PUG - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

26629					9/2/2007	9/3/2007	156		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-5 Quarterly SS - Refer to PM schedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

26630					9/2/2007	9/3/2007	156		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-13 Quarterly WREH - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

26793		Cafeteria			9/7/2007		151		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/7/2007 2:25:07 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny		WATER HEATER MOTOR IS GIVEN OUT							
---------------	--	---------------------------------	--	--	--	--	--	--	--

		MARINA RAMIEZ SNP MGR 589-2545							
--	--	--------------------------------	--	--	--	--	--	--	--

Jacqueline Aguilar

26843					9/10/2007		148		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/10/2007 2:14:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		PLEASE ASSEMBLE KIDNEY TABLE AND PLACE IN ROOM 12 (MS. C. GARCIA.) THANKS							
------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

26874					9/11/2007		147		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/11/2007 10:10:09 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David		9/11/07. WE HAVE A WATER LEAK ON MECHANICAL ROOM.(IS A WATER VALVE). THIS WORK ORDER IS FOR DAVID VILLALOBOS.							
-------------------	--	---	--	--	--	--	--	--	--

Manuel Prospero

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Sunland Park ES

27066					9/17/2007		0		\$0.00
Medium	Work In Progress				9/17/2007 8:45:39 AM	9/17/2007			
Prospero, Manuel	PIGEON PROBLEM IS GETTING WORSE. MANY DROPPINGS AND FEATHERS IN THE FRONT ENTRANCE AND BACK ENTRANCE.		Watson Pest Control was out there on Saturday 9/15. They will be treating this site once a month. Manny Needs to be cleaning up areas as needed.						
Irene Trujillo									
27507					9/27/2007		131		\$0.00
Medium	Work In Progress				9/27/2007 12:32:18 PM				
Villalobos, David	classroom #41 - Toilet needs to be repaired. Do not have enough pressure.								
Irene Trujillo									
27508					9/27/2007		131		\$0.00
Medium	Work In Progress				9/27/2007 12:37:37 PM				
Prospero, Manuel	CLASSROOM #12 - BROKEN DESK - PLEASE FIX IT.								
Irene Trujillo									
27617					9/30/2007	10/8/2007	128		\$0.00
Medium	Work In Progress				9/30/2007 12:17:32 AM				
Prospero, Manuel	Monthly - Sunland Park ES Roof Inspection - Refer to PMschedule details.								
Margret Villalobos									
27168					9/19/2007		139		\$0.00
Medium	Work In Progress				9/19/2007 12:49:02 PM				
Ontiveros, Guadalupe	REMOVE WEEDS AT ENTRANCE BY THE CAMPUS RESIDENT'S TRAILER AND ALONG WALKING TRAIL. THIS AREA ALSO NEEDS FOR THE SAND TO BE LEVELED.								
Irene Trujillo									
27509					9/27/2007		131		\$0.00
Medium	Work In Progress				9/27/2007 12:42:38 PM				
Prospero, Manuel	PLEASE INSTALL BULLETIN BOARDS. ONE IN ROOM 41 (T. PEREZ) AND THE OTHER IN THE COUNSELOR'S OFFICE.								
Irene Trujillo									
27598					9/30/2007	10/6/2007	128		\$0.00
Medium	Work In Progress				9/30/2007 12:17:24 AM				
Prospero, Manuel	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PMschedule details.								
Margret Villalobos									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

27684					9/30/2007	10/8/2007	128		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium	Work In Progress				9/30/2007 12:17:58 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

27694					9/30/2007	10/8/2007	128		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium	Work In Progress				9/30/2007 12:18:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

27903					10/5/2007		123		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Room 20			10/5/2007 1:34:38 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Villalobos, Margret		CLASSROOM #20 - PLEASE FUMIGATE! THERE ARE ROACHES OF ALL SIZES AS WELL AS SOME OTHER BLACK BUGS.							
---------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

28125					10/15/2007		113		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/15/2007 9:00:24 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph		PLEASE CHECK ALL DOORS IN THE BUILDING FOR REPLACEMENT OF ONES IN POOR SHAPE.							
-------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

28127					10/15/2007		113		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/15/2007 10:16:34				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, Margret		NEED HELP! THERE IS A HUGE RAT IN THE CUSTODIAN'S ROOM. THE CUSTODIAN SAW IT CRAWL FROM THE ROOM UP TO THE ROOF AREA.				Need price quote!			
---------------------	--	---	--	--	--	-------------------	--	--	--

Irene Trujillo

28178					10/16/2007		112		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/16/2007 10:01:32				
--------	------------------	--	--	--	---------------------	--	--	--	--

Prospero, Manuel		The ramps on portables need to be painted. Also, this is a reminder portables have not been painted (previously submitted request)							
------------------	--	--	--	--	--	--	--	--	--

Irene Trujillo

28192					10/16/2007		112		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/16/2007 3:07:59 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel		2ND REQUEST TO HAVE THE PORTABLES PAINTED.							
------------------	--	--	--	--	--	--	--	--	--

Irene Trujillo

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

28272					10/18/2007		110		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/18/2007 1:54:04 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph CLASSROOM 41 - DOOR WHICH LEADS TO OUTSIDE NEEDS TO BE REPLACED.

Irene Trujillo

28273					10/18/2007		110		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/18/2007 1:55:04 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph CLASSROOM 25 - THE DOOR WHICH LEADS TO THE OUTSIDE NEEDS TO BE REPLACED.

Irene Trujillo

28325					10/19/2007		109		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/19/2007 10:07:33				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos UPDATE OUTSIDE LIGHTS

Irene Trujillo

28542					10/25/2007		103		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/25/2007 1:24:32 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David CLASSROOM #24 - UNCLOG SINK

Irene Trujillo

28721					10/31/2007		97		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/31/2007 9:24:25 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos AS PER OUR CONVERSATION, PLEASE PROVIDE A 120 OUTLET FOR THE ENVIRONMENT DEPT.

Michael Munoz

29005		Classroom			11/6/2007		91		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/6/2007 3:39:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel Classroom #39 - Move backpack hangers to the back room.

Irene Trujillo

29221					11/14/2007		83		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/14/2007 1:49:39 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel PLEASE HANG 10 FRAMED POSTERS THROUGHOUT THE SCHOOL BUILDING.

Irene Trujillo

29429		Cafeteria			11/27/2007		70		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/27/2007 8:01:33 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny BOTTOM BLODGETT OVEN IS STILL NOT WORKING

MARINA RAMIREZ - SNP MANAGER 589-2545

Alma Terrell

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

29430		Cafeteria			11/27/2007		70		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/27/2007 8:04:18 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny BOILER CONTINUOUSLY TURNS OFF - THEY HAVE CHECK THE BOILER CONSTANTLY BECAUSE IT SHUTS OFF.

MARINA RAMIREZ - SNP MANAGER 589-2545

Alma Terrell

29670					12/2/2007	12/10/2007	65		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:15 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PMschedule details.

Margret Villalobos

29679					12/2/2007	12/10/2007	65		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:18 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PMschedule details.

Margret Villalobos

29692					12/2/2007	12/3/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:23 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel Monthly - Sunland Park ES A-13 Quarterly WREH - Refer to PMschedule details.

Margret Villalobos

29698					12/2/2007	12/3/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel Monthly - Sunland Park ES A-2 Quarterly H/C IREH - Refer to PMschedule details.

Margret Villalobos

29699					12/2/2007	12/3/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel Monthly - Sunland Park ES A-6 Quarterly PUG - Refer to PMschedule details.

Margret Villalobos

29720					12/2/2007	12/3/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:34 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel Monthly - Sunland Park ES A-8 Quarterly HPW Unit - Refer to PMschedule details.

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

29723					12/2/2007	12/3/2007	65		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				12/2/2007 12:30:35 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-5 Quarterly SS - Refer to PM schedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

29778					12/4/2007		63		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/4/2007 8:36:19 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		SUNLAND PARK SIGN SET AT BUS LOADING AREA - REPAIR THE LETTERS AND PAINT.							
------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

30193					12/18/2007		49	1	\$25.00
-------	--	--	--	--	------------	--	----	---	---------

Medium	Work In Progress				12/18/2007 2:07:42 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph		CLASSROOM 35 (SPEECH) - THE WEATHER STRIPPING HAS TO BE REPLACED. THERE ARE LARGE GAPS WHERE CRITTERS CRAWL IN.							
-------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

30268					1/6/2008	1/12/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

30287					1/6/2008	1/14/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:52 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

30316					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:04 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

30353					1/6/2008	1/14/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:19 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

30362					1/6/2008	1/14/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

30957 1/25/2008 11 \$0.00

Medium Work In Progress 1/25/2008 1:32:50 PM

Villalobos, Margret MICE DROPPINGS IN THE TEACHER'S LOUNGE AND OFFICE STORAGE ROOM.

Irene Trujillo

31061 1/30/2008 6 \$0.00

Medium Work In Progress 1/30/2008 11:04:56 AM

Lara, Ralph PLEASE REPAIR THE DOOR STOP ON THE DOOR IN THE BACK EXIT.

Irene Trujillo

30587 1/14/2008 22 \$0.00

Safety Work In Progress 1/14/2008 1:10:53 PM

Ontiveros, Guadalupe KINDER PLAYGROUND - REMOVE METAL HOOP THAT SITS IN THE MIDDLE OF THE PLAYGROUND. IT IS A SAFETY HAZARD.

Irene Trujillo

30589 1/14/2008 22 2 \$50.00

Safety Work In Progress 1/14/2008 1:11:19 PM

Ontiveros, Guadalupe KINDER PLAYGROUND - REMOVE METAL HOOP THAT SITS IN THE MIDDLE OF THE PLAYGROUND. IT IS A SAFETY HAZARD.

Irene Trujillo

30712 Main Building Athletic Field 1/16/2008 20 \$0.00

Medium Work In Progress 1/16/2008 4:17:40 PM

Ontiveros, Guadalupe Clean out drains at main entrance. Also cut weeds around back stop and playarea

Guadalupe Ontiveros

30950 1/25/2008 11 \$0.00

Medium Work In Progress 1/25/2008 11:07:38 AM

Lara, Ralph PLEASE RETURN TO FINISH WELDING BENCHES IN PLACE. THE WEEKEND IS APPROACHING & WE'RE CONCERNED THAT THEY WILL "WALK" AWAY. THANKS!

Irene Trujillo

30974 1/28/2008 8 \$0.00

Medium Work In Progress 1/28/2008 8:57:45 AM

Lara, Ralph 1/28/08/. STORAGE LOCK IS NOT WORKING ON LIBRERIA. PLEACE CHEK. (THIS WORK ORDER IS FOR MANNY LOSOYA.

Manuel Prospero

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

31060					1/30/2008		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2008 11:03:57 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
PLEASE CHECK ONE OF DOORS IN THE MAIN HALL. THE HANDLE IS VERY LOOSE AND WILL BREAK IF PULLED WITH A STRONG JERK.

Irene Trujillo

31118					1/31/2008		5		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/31/2008 8:28:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel
PORTABE A - PLEASE FIX TEACHER'S DESK. THE LEG FALLS OFF CAUSING THE DESK TO TILT.

Irene Trujillo

31222					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel
Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

31231					2/3/2008	2/11/2008	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel
Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

31254					2/3/2008	2/9/2008	2		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/3/2008 12:30:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel
Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

31291					2/5/2008		0		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/5/2008 8:33:46 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
THE DOOR IN THE HALLWAY- PLEASE CHECK THE HANDLE HAS BROKEN AND NEEDS PARTS REPLACED.

Irene Trujillo

Count: 95 Work Orders			Avg. Age of WO's 120			Total for Sunland Park ES	3		\$5,375.00
------------------------------	--	--	-----------------------------	--	--	----------------------------------	----------	--	-------------------

Location: Sunrise ES

24415					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunrise ES

24550					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul Yearly - Sunrise ES Exit Sign Test: Annual - Refer to PM schedule details.

Alfredo Holguin

24414					7/1/2007	8/1/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24549					7/1/2007	7/9/2007	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.

Alfredo Holguin

24666		Office			7/10/2007		210		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	front handicap			7/10/2007 3:10:07 PM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Lozoya, Manny Front door to school needs to be serviced door is jamming. This door is the one located entering the door for handicap entrance.

Joanne Munoz

24667		Classroom			7/10/2007		210		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	sever classrooms			7/10/2007 3:12:28 PM				
--------	------------------	------------------	--	--	----------------------	--	--	--	--

Quinones, Paul Classrooms need to have dipensers replacèd. Jesse head custodian has the list ready need for maint. to pick up list. and install.

Joanne Munoz

24832		Cafeteria			7/17/2007		203		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	stage area			7/17/2007 12:07:26 PM				
--------	------------------	------------	--	--	-----------------------	--	--	--	--

Quinones, Paul Need the cork board that was put on the stage wall to be put up a little higher where the blue line ends

Joanne Munoz

25054		Office			7/24/2007		196		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	supply closet			7/24/2007 4:42:31 PM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Lozoya, Manny Supply Closet door near the the cafeteria is not closing check this out

Joanne Munoz

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunrise ES

25785		Classroom			8/13/2007		176		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Luna Resource			8/13/2007 1:16:30 PM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Michelle Gaytan, luna resouce room, parent ambassador, needs to have a lock put on her filing cabinet and also on her cabinets.

Joanne Munoz

25874		Lift Station			8/15/2007		174		\$0.00
-------	--	--------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/15/2007 8:10:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Ricardo Jacquez
need 2 locks for new fence at wwtp

25995		Classroom			8/17/2007		172		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	ROOM 212			8/17/2007 6:48:54 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Lozoya, Manny
The double doors in Mrs. Sanders room need to have locks installed the black core is still there

Joanne Munoz

25996		Classroom			8/17/2007		172		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	room 201			8/17/2007 6:49:42 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Mrs. Herrera, room 201, bathroom door needs a lock it still has the black core

Joanne Munoz

25997	Main Building	Classroom			8/17/2007		172		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	room 104			8/17/2007 6:50:31 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Mrs. Briones, room 104, double doors need a lock it still has the black core

Joanne Munoz

25998	Main Building	Classroom			8/17/2007		172		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	room 108			8/17/2007 6:51:22 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Mrs. Turner, room 108, double doors need to have lock installed still has the black core.

Joanne Munoz

26741		Cafeteria			9/6/2007		152		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2007 10:26:00 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
PASS THRU WARMER SEAL IS COMING OFF

VIRGINIA PRUIT SNP MGR 824-3194

Jacqueline Aguilar

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunrise ES							
26986		Cafeteria			9/13/2007		145		\$0.00
Medium	Work In Progress				9/13/2007 8:16:30 AM				
Orozco, Danny		PASS THRU REACH IN REFRIG. ONE IS AT 52 AND THE OTHER IS AT 48							
Jacqueline Aguilar		VIRGINIA PRUIT SNP MGR 824-3194							
27581					9/30/2007	10/6/2007	128		\$0.00
Medium	Work In Progress				9/30/2007 12:17:17 AM				
Baeza, Eddie		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
27619					9/30/2007	10/8/2007	128		\$0.00
Medium	Work In Progress				9/30/2007 12:17:32 AM				
Quinones, Paul		Monthly - Sunrise ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
27686					9/30/2007	10/8/2007	128		\$0.00
Medium	Work In Progress				9/30/2007 12:17:59 AM				
Baeza, Eddie		Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
27695					9/30/2007	10/8/2007	128		\$0.00
Medium	Work In Progress				9/30/2007 12:18:02 AM				
Baeza, Eddie		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
28240					10/17/2007		111		\$0.00
Medium	Work In Progress				10/17/2007 3:37:08 PM				
Solis, Lorenzo		A/C UNIT IN SERVER RM. TURNING OFF ON HIGH HEAD PRESSURE.RESET HIGH PRESSURE SWITCH,AND CHECK OUT DOOR FAN MOTOR,MOTOR NOT WORKING							
Paul Quinones									
28335	Main Building	Classroom			10/19/2007		109		\$0.00
Medium	Work In Progress	102			10/19/2007 3:00:50 PM				
Quinones, Paul		Janell Luedwig, 102, needs to have the the shelves secured to the wall brackets.							
Joanne Munoz									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunrise ES

28395		Cafeteria			10/23/2007		105		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 10:17:56				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny
SLICER WILL NOT WORK AT ALL. HAS POWER
CONNECTED, BUT THE MOTOR WILL NOT TURN
ON.

VIRGINIA P. SNP MGR 824-3194

Jacqueline Aguilar

30289					1/6/2008	1/14/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul
Monthly - Sunrise ES Roof Inspection - Refer to PM
schedule details.

Margret Villalobos

30317					1/6/2008	1/27/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:04 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
Monthly - Sunrise ES Range Hood Cleaning - Refer to
PM schedule details.

Margret Villalobos

30910	Main Building	Cafeteria			1/24/2008		12		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	stage			1/24/2008 11:58:48 AM				
--------	------------------	-------	--	--	-----------------------	--	--	--	--

Quinones, Paul
Please install doorstop on closet door on stage.

Joanne Munoz

28860					11/4/2007	11/10/2007	93		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				11/4/2007 12:16:40 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Quinones, Paul
Monthly - Sunrise ES Monthly FE Inspection - Refer to
PM schedule details.

Margret Villalobos

29471					11/27/2007		70		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/27/2007 4:20:26 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
REQUESTING RED COLORD SCREENING FOR
SIDEWALKS
NEXT TO THE PORTABLES,AND BACK OF PRIMARY
PLAY GROUND AREAS

Paul Quinones

30061		Restroom (Girls)			12/13/2007		54		\$0.00
-------	--	------------------	--	--	------------	--	----	--	--------

Medium	Work In Progress	staff restroom-by			12/13/2007 12:28:12				
--------	------------------	-------------------	--	--	---------------------	--	--	--	--

Quinones, Paul
coat holder fell off wall. Please put back if possible. If it
needs to be moved please patch up holes left behind

Joanne Munoz

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunrise ES							
30251					1/6/2008	1/12/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:28:38 AM				
Quinones, Paul		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
30355					1/6/2008	1/14/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:29:20 AM				
Quinones, Paul		Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
30363					1/6/2008	1/14/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:29:23 AM				
Quinones, Paul		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
30386	Main Building	Classroom			1/8/2008		28		\$0.00
Medium	Work In Progress	204			1/8/2008 10:53:28 AM				
Quinones, Paul		Need Door sweeps to be put on door to the outside in Mrs. Farleys room 204.							
Joanne Munoz									
30685		Classroom			1/16/2008		20		\$0.00
Medium	Work In Progress	p-8			1/16/2008 12:56:03 PM				
Lozoya, Manny		I need to have an extra key for portable 8 We will be having detention in this portable and our Coach will need access key# 1c88.							
Joanne Munoz									
30953					1/25/2008		11		\$0.00
Medium	Work In Progress				1/25/2008 11:12:03 AM				
Quinones, Paul		Please relocate soccer goals to CHS as per Lowenburg. thxs							
Michael Munoz									
31155					2/1/2008		4		\$0.00
Medium	Work In Progress				2/1/2008 7:51:39 AM				
Solis, Lorenzø		CIRCULATING PUMP MOTOR OUT,NEED TO REPLACE.IN RM. 302. REQUESTING SEAL KITS,AND 4-J SLEEVES AS WELL. THANKS							
Paul Quinones									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunrise ES

31156 2/1/2008 4 \$0.00

Medium Work In Progress 2/1/2008 7:56:27 AM

Jacquez, Ricardo BACK FENCE LINE, REQUESTING WIND SCREEN ESTIMATE LENGTH OF APPROX. 250'. THANKS

Paul Quinones

31224 2/3/2008 2/11/2008 2 \$0.00

Medium Work In Progress 2/3/2008 12:30:46 AM

Quinones, Paul Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

31232 2/3/2008 2/11/2008 2 \$0.00

Medium Work In Progress 2/3/2008 12:30:49 AM

Quinones, Paul Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

31238 2/3/2008 2/9/2008 2 \$0.00

Medium Work In Progress 2/3/2008 12:30:51 AM

Quinones, Paul Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

31259 2/3/2008 2 \$0.00

Medium Work In Progress 2/3/2008 12:30:59 AM

Jacquez, Ricardo Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.

Margret Villalobos

Count: 41 Work Orders Avg. Age of WO's 105 Total for Sunrise ES 0 \$0.00

Location: Vado ES

31310 Main Building Classroom 2/5/2008 0 \$0.00

Medium Work In Progress 2/5/2008 1:02:35 PM

Miranda, Danny RAISE HANDICAP BAR IN SPECIAL NEEDS ROOM 101

Debra Facio

24634 Office 7/9/2007 211 \$0.00

Medium Work In Progress 7/9/2007 3:02:27 PM

Lozoya, Manny NEED TO HAVE 2 KEYS MADE ONE FOR ROOM 205 AND 207

Debra Facio

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
31188					2/3/2008	2/9/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:30 AM				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
31225					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:46 AM				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
31233					2/3/2008	2/11/2008	2		\$0.00
Medium	Work In Progress				2/3/2008 12:30:49 AM				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
24972					7/20/2007		200		\$0.00
Medium	Work In Progress				7/20/2007 3:13:10 PM				
Lozoya, Manny		NEED 5 SETS OF EACH KEY (M4 AND 2) FOR FLASHING LIGHTS IN VADO. M4 IS DANNY MIRANDA ORIGINAL AND KEY 2 IS COUNTY.							
Carlos Vigil									
25130					7/26/2007		194		\$0.00
Medium	Work In Progress				7/26/2007 3:51:20 PM				
Gonzalez, Salvador		need to weld new brackets & rollers on front gates (see chava)							
Danny Miranda									
25155					7/27/2007		193		\$0.00
Medium	Work In Progress				7/27/2007 8:23:24 AM				
Lozoya, Manny		NURSE OFFICE RESTROOM DOOR WILL NOT OPEN							
Danny Miranda									
25202					7/30/2007		190		\$0.00
Medium	Work In Progress				7/30/2007 1:05:48 PM				
Lozoya, Manny		RM. 202 SP. ED. NEED TO PUT SPECIAL TYPE OF DOOR KNOBE SO THREE YEAR OLD CHILD WILL NOT GET OUT							
Danny Miranda									
26091					8/21/2007		168		\$0.00
High	Work In Progress				8/21/2007 1:10:13 PM				
Lozoya, Manny		please re-key maint door. people are entering afterhours. see mike before.							
Michael Munoz									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
26372					8/28/2007		161		\$0.00
Medium	Work In Progress				8/28/2007 3:52:05 PM				
Sotelo, Enrique		NEED TO CK. LIGHT IN FRONT LOBBY							
Danny Miranda									
27351					9/24/2007		134		\$0.00
Medium	Work In Progress				9/24/2007 9:46:59 AM				
Sotelo, Enrique		NEED LIGHT BULBS FOR LIGHTS ON OUTSIDE OF BUILDING AND BALLAST							
Danny Miranda									
27650					9/30/2007	10/21/2007	128		\$0.00
Medium	Work In Progress				9/30/2007 12:17:45 AM				
Orozco, Danny		Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
27990					10/9/2007		119		\$0.00
Medium	Work In Progress				10/9/2007 9:20:00 AM				
Sotelo, Enrique		need new electrical outlets for tvon walls in library, and front office							
Danny Miranda									
27991					10/9/2007		119		\$0.00
Medium	Work In Progress				10/9/2007 9:21:54 AM				
Sotelo, Enrique		need light bulbs for outside lights							
Danny Miranda									
28773		Cafeteria			11/1/2007		96		\$0.00
Medium	Work In Progress				11/1/2007 8:32:57 AM				
Orozco, Danny		MAIN KITCHEN BACK DOOR DOES NOT CLOSE ANY MORE.							
Jacqueline Aguilar		LAURA B. SNP MGR 233-2945							
29067					11/8/2007		89		\$50.00
Medium	Work In Progress				11/8/2007 9:27:35 AM				
Villalobos, Margret		NEED TO SPRAY CABINETS & CLASSROOMS #301, 303, 305, 307, 309 FOR ANTS				11/13 - Faxed PO			
Danny Miranda									
29199					11/14/2007		83		\$0.00
Medium	Work In Progress				11/14/2007 8:33:58 AM				
Ontiveros, Joe		NEED SIX SMALL VALVE BOXES FOR NEW WATER LINES THAT WERE PUT IN							
Danny Miranda									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Vado ES							
29304		Parking Lot			11/16/2007		81	4	\$100.00
Medium	Work In Progress				11/16/2007 11:29:21				
Briones, Enrique		NEED WAREHOUSE TO PICK UP TV ASAP THANK YOU.				11/19 - 1st attempt Mando did not no much. 11/26 2nd attempt 12/3 3rd attempt 12/10 4th attempt			
Armando Diaz									
29332					11/19/2007		78		\$0.00
Medium	Work In Progress				11/19/2007 9:17:26 AM				
Sotelo, Enrique		need light covers for lights in restroom 100-wing							
Danny Miranda									
29940					12/10/2007		57		\$0.00
Medium	Work In Progress				12/10/2007 11:33:33				
Villalobos, Margret		RMS 211 & 212 WIRES ARE CROSSED AND 210 & 211 ARE ON THE SAME WIRES THIS HAPPENED ON THE INITIAL SETUP A LONG TIME NOW (JUST FIGURED IT OUT NOW) There should be no charge for this - should be under warranty.							
Danny Miranda									
30158					12/17/2007		50		\$0.00
Medium	Work In Progress				12/17/2007 3:53:48 PM				
Carrasco, Danny		NEED A WELDER TO REPAIR FRONT GATES ONE FELL ON CUSTODIAN (THIRD REQUEST)							
Danny Miranda									
30318					1/6/2008	1/27/2008	30		\$0.00
Medium	Work In Progress				1/6/2008 12:29:04 AM				
Orozco, Danny		Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
30762					1/17/2008		19		\$0.00
Medium	Work In Progress				1/17/2008 3:34:50 PM				
Carrasco, Danny		add to w/o # 30761 (warehouse has sample)							
Danny Miranda									
30956					1/25/2008		11		\$0.00
Medium	Work In Progress				1/25/2008 1:06:11 PM				
Sotelo, Enrique		A-Wing - no power to several several classrooms.							
Enrique Sotelo									
30436					1/9/2008		27		\$0.00
Medium	Work In Progress				1/9/2008 3:02:16 PM				
Lozoya, Manny		need to repair teachers restroom door knob door can't be opened from inside teachers are locking themselves inside							
Danny Miranda									

1185 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Vado ES							
30680					1/16/2008		20		\$0.00
Medium	Work In Progress				1/16/2008 10:34:24 AM				
Villalobos, Margret		NEED SOMEONE TO CK. TRACER SUMMIT CLASSROOM'S MUST BE RESET EVERY MORNING AND AGAIN DURING THE DAY SEVERAL TIMES				1/17 - Eddie came out today to check on problem			
Danny Miranda									
30761					1/17/2008		19		\$0.00
Medium	Work In Progress				1/17/2008 3:26:53 PM				
Carrasco, Danny		NEED CEILING TILE TO MATCH EXISTING TILE BEFORE BOARD MEETING ON 1/24/08 THIRD REQUEST LAST ONE THEY SEND LOOKS LIKE SHIT							
Danny Miranda									
30943					1/24/2008		12		\$0.00
Medium	Work In Progress				1/24/2008 3:54:33 PM				
Villalobos, Margret		Asp Jose Ambriz the need to replace board on BCU. Unable to communicate w/site. (Please advise when someone will be coming out so we can send one of our Technicians) Thanks.							
Jose Ambriz									
Count: 29 Work Orders		Avg. Age of WO's 86			Total for Vado ES			4	\$150.00
Count: 1185 Work Orders		Avg. Age of WO's 103			Grand Total			15	\$17,683.97