

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Anthony - On Track Pre-K									
76681		Classroom			8/9/2011		34		\$0.00
Medium	Work In Progress				8/9/2011 8:25:33 AM				
Ronquillo, Ruben	upper primary room 107 needs 4 blinds 59x54								
Hector Villalobos									
75897					7/27/2011		47		\$0.00
Medium	Work In Progress				7/27/2011 1:32:06 PM				
Villalobos, Hector	They want the sand box Border to be raise up								
Hector Villalobos									
Count: 2 Work Orders			Avg. Age of WO's	41	Total for Anthony - On Track Pre-K			0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
77666		Portables			8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 3:38:05 PM					
Appelzoller, Fred	pts 1 to4 replace water heaters in bathrooms								
<u>Hector Villalobos</u>									
77698		Portables			9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 9:27:32 AM					
Appelzoller, Fred	PT1,2 need a hose bibb by water fountain outside								
<u>Hector Villalobos</u>									
78122					9/9/2011		3		\$0.00
Medium	Work In Progress	107		9/9/2011 1:48:05 PM					
Solis, Lorenzo	PLEASE ADJUST TEMPERATURE IT IS VERY HOT!! 84 DEGREES ROOM # 107- COMPUTER LAB								
<u>Jessica Lopez</u>									
75321					7/12/2011		62		\$0.00
Medium	Work In Progress	New Classroom		7/12/2011 9:06:21 AM					
Lozoya, Manny	New cores (with new keys) need to be installed at the new classroom building. Please coordinate with contractor - Kerry Smith / Wooten Construction (575) 650-7779.								
<u>Peggy Jo Hernandez</u>									
75357	Main Building				7/13/2011		61		\$0.00
Medium	Work In Progress			7/13/2011 6:29:09 AM					
Lozoya, Manny	mld blg remove all hardware from doors								
<u>Hector Villalobos</u>									
75596					7/20/2011		54		\$0.00
Medium	Work In Progress	PRE-K		7/20/2011 3:39:41 PM					
Lozoya, Manny	PLEASE CHANGE ALL PRE-K DOORS TO H AND PORTABLES 1-8								
<u>Jessica Lopez</u>									
75948	Main Building				7/28/2011		46		\$0.00
Medium	Work In Progress			7/28/2011 9:37:36 AM					
Flores, Pete	need fuel mixture for weed eaters and blower code #600								
<u>David Vega</u>									
78188					9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 10:37:56 AM					
Martinez, Larry	On September 14, 2011, please deliver 5 boxes of Social Studies material to Anthony Elementary.								
<u>Yolie Jacquez</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Anthony ES								
76227	Main Building				8/1/2011		42		\$0.00	
Medium	Work In Progress			8/1/2011 4:54:41 PM						
Villalobos, Margret		spray for bugs rooms, 111,110,109,108,107,,106, teachers lounge,105,103,pre k office, upper primary(the village) as per pre k coordinator								
David Vega										
77580					8/30/2011		13		\$0.00	
Medium	Work In Progress			8/30/2011 11:32:33 AM						
Villalobos, Margret		PLEASE FUMIGATE, A LOT OF ANTS FOUND IN ALL OF THE UPPER GRADES ROOM #'S 411,400,401,413,410,407, AND 408								
Jessica Lopez										
77655					8/31/2011		12		\$0.00	
Medium	Work In Progress	sped office		8/31/2011 2:47:13 PM						
Villalobos, Margret		SPRAY FOR ANTS IN JULIE HINOJOSA, DIRECTOR'S OFFICE				Waiting on Price Quote				
Margaret Villalobos										
77697		Portables			9/1/2011		11		\$0.00	
Medium	Work In Progress			9/1/2011 9:23:37 AM						
Solis, Lorenzo		PT8 Refrigeration unit not working								
Hector Villalobos										
77754					9/2/2011		10		\$0.00	
Medium	Work In Progress			9/2/2011 9:08:11 AM						
Villalobos, Hector		Need filters for heating pts , drug free								
Hector Villalobos										
77213					8/22/2011		21		\$0.00	
Medium	Work In Progress			8/22/2011 11:46:48 AM						
Villalobos, Hector		LUCKY, A LOT OF THORNS FOUND IN SOCCER FIELD PLEASE CLEAN								
Jessica Lopez										
77860					9/4/2011	9/12/2011	8		\$0.00	
Medium	Work In Progress			9/4/2011 12:24:23 AM						
Villalobos, Hector		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos										
77861					9/4/2011	9/12/2011	8		\$0.00	
Medium	Work In Progress			9/4/2011 12:24:23 AM						
Villalobos, Hector		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos										

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
77859					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:22 AM					
Villalobos, Hector	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75176					7/7/2011		67		\$0.00
Medium	Work In Progress			7/7/2011 7:31:56 AM					
Carrasco, Danny	Need to pick up Dorma hardare for storage at PPD. Check wiht contractor at site (Kerry Smith 650-7779)								
<u>Alfredo Holguin</u>									
76522					8/5/2011		38		\$0.00
Medium	Work In Progress	CAFETERIA		8/5/2011 1:11:57 PM					
Villalobos, Hector	WE NEED TO SEND THE OLD CAFETERIA TABLES TO THE WAREHOUSE THANK YOU								
<u>Jessica Lopez</u>									
76979					8/16/2011		27		\$0.00
Medium	Work In Progress			8/16/2011 8:24:54 AM					
Carrasco, Danny	# 600 weed eater 272031746 gas mix, blower 256867729								
<u>Hector Villalobos</u>									
77711	Main Building				9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 12:57:29 PM					
Carrasco, Danny	need fuel for truck 79								
<u>David Vega</u>									
77964	Cafeteria				9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 10:02:29 AM					
Ronquillo, Ruben	Borken windows old cafetria 23x1/2 x29 1/2, 25x18, wire glass , 19x15								
<u>Hector Villalobos</u>									
77953					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 9:01:14 AM					
Moncayo, Fernando	THIRD FREEZER IS NOT WORKING DUE TO VANDALISM.								
<u>Aida Salcedo</u>									
77385					8/25/2011		18		\$0.00
Medium	Work In Progress			8/25/2011 8:14:02 AM					
Munoz, Michael	upper primary need 30 ft of fence to repair cut fence. electrical power								
<u>Hector Villalobos</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
76477					8/5/2011		38		\$0.00
Medium	Work In Progress			8/5/2011 8:21:09 AM					
Arreola, Rudy	please support with the cutting of the grass. thanks								
<u>Michael Munoz</u>									
77999		Portables			9/7/2011		5		\$0.00
Medium	Work In Progress			9/7/2011 5:57:24 AM					
Lozoya, Manny	PT 2 need to be replace door lock will not open								
<u>Hector Villalobos</u>									
78059					9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 8:29:20 AM					
Lozoya, Manny	MR. HERNANDEZ IS HAVING A HARD TIME LOCKING HIS ROOM WITH HIS KEY HE IS ALSO STATING THAT THE OTHER TEACHERS ARE ABLE TO OPEN HIS ROOM PLEASE CHECK								
<u>Jessica Lopez</u>									
78084					9/8/2011		4		\$0.00
Medium	Work In Progress	NURSE'S		9/8/2011 3:24:11 PM					
Lozoya, Manny	PLEASE CHECK NURSE'S MEDICINE CABINET. NURSE IS HAVING A HARD TIME OPENING THE DOOR PLEASE CHECK								
<u>Jessica Lopez</u>									
75637					7/21/2011		53		\$0.00
Medium	Work In Progress	SPED OFFICE		7/21/2011 2:56:14 PM					
Villalobos, Hector	REMOVE BLUE LIGHTING LIGHTBULBS FROM ROOM 202 (F. NEVAREZ TO ROOM 101 F. NEVAREZ) STUDENT NEEDS								
<u>Margaret Villalobos</u>									
75824	Main Building				7/26/2011		48		\$0.00
Medium	Work In Progress			7/26/2011 10:51:05 AM					
Villalobos, Hector	lounge- replace window blind.								
<u>Alfredo Holguin</u>									
77693					9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 8:52:14 AM					
Villalobos, Hector	LUCKY PLEASE FIX SPRINGLER SYSTEM								
<u>Jessica Lopez</u>									
77061	Cafeteria				8/17/2011		26		\$0.00
Medium	Work In Progress			8/17/2011 1:56:21 PM					
Lozoya, Manny	New cafeteria pad lock chargelock from CD 30 to CD5								
<u>Hector Villalobos</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
77219					8/22/2011		21		\$0.00
Medium	Work In Progress	78 Building		8/22/2011 12:19:39 PM					
Lozoya, Manny		Cores need to be installed in the AE 78 building. Please coordinate with Contractor - Kerry Smith / Wooten Construction (575) 650-7779							
Peggy Jo Hernandez									
77557					8/30/2011		13		\$0.00
Medium	Work In Progress	109 VILLAGE		8/30/2011 8:29:47 AM					
Lozoya, Manny		MS. ARELLANO NEEDS LOCK AND KEY FOR 1 FILING CABINET AND ONE STORAGE CABINET ROOM #109 VILLAGE							
Jessica Lopez									
77663		Portables			8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 3:36:39 PM					
Lozoya, Manny		Need keys made for pts 1to4							
Hector Villalobos									
77692					9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 8:50:56 AM					
Lozoya, Manny		MRS. BENCOMO'S MASTER KEY DOESN'T WORK PLEASE REPLACE THANK YOU							
Jessica Lopez									
77968					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 11:10:21 AM					
Lozoya, Manny		WE NEED A KEY TO OPEN THE SUPPLY ROOM SO WE CAN LEND TO TEACHERS WHEN THEY NEED SUPPLIES (SUPPLY ROOM NEXT TO ROOM #108 NEW ADDITION)							
Jessica Lopez									
Count: 37 Work Orders		Avg. Age of WO's 22		Total for Anthony ES			0	\$0.00	

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
76834					8/11/2011		32		\$0.00
Medium	Work In Progress				8/11/2011 3:11:03 PM				
Sotelo, Enrique	MR ENRIQUE SOTELO SIR NEED 6 FUSES 90 AMPS 600 VOLTS FOR IRRGATION PUMP								
Adan Duran									
77979					9/6/2011		6		\$0.00
Medium	Work In Progress				9/6/2011 3:21:21 PM				
Sotelo, Enrique	MR ENRIQUE SOTELO SIR THE SWITCH RESTROOM PORTABLE 157 IS NOT WORKING NEED TO REPLACE THANK YOU SIR AND GOD BLESS								
Adan Duran									
78028					9/7/2011		5		\$0.00
Medium	Work In Progress				9/7/2011 2:57:49 PM				
Sotelo, Enrique	MR ENRIQUE SOTELO SIR THE BELLAST RM 113 NEEDS TO BE REPLACE CHANGE LIGHT BULBS WILL NOT COME ON THANK YOU SIR AND GOD BLESS								
Adan Duran									
75977					7/28/2011		46		\$0.00
Medium	Work In Progress				7/28/2011 3:14:50 PM				
Duran, Adan	MR DURAN AS PER MR VALTIERRA NEED TO ORDER 240 FT OF 1/2" ROPE FOR PLAYGROUND WILL BE USED FOR JUMP ROPE AND TUG ROPE AND TIE DOWNS ECT								
Adan Duran									
77811					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress				9/4/2011 12:24:02 AM				
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
77812					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress				9/4/2011 12:24:02 AM				
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
77813					9/4/2011		8		\$0.00
Medium	Work In Progress				9/4/2011 12:24:03 AM				
Duran, Adan	Monthly - Berino ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
78160					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:41 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77810					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:01 AM					
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
74948					7/4/2011	7/24/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:21:46 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76615					8/8/2011		35		\$0.00
Medium	Work In Progress			8/8/2011 8:20:53 AM					
Solis, Lorenzo	A/C NOT COOLING RM 155 156								
<u>Jimmy Cortez</u>									
Count: 11 Work Orders			Avg. Age of WO's	21		Total for Berino ES	0		\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
Location: Chaparral Elem East Pre-K									
77521					8/29/2011		14		\$0.00
Medium	Work In Progress				8/29/2011 1:56:05 PM				
Ontiveros, Joe	Need to replace broken toilet in Portable #5. Thank you								
Guillermo Hernandez									
75620					7/21/2011		53		\$0.00
Medium	Work In Progress				7/21/2011 8:16:14 AM				
Estrada, Jesus	VCT tile needs to be replaced, loose and univen floor tiles. Double portable (69 DM1R) Classrooms P #3 and P #4. Thank you.								
Guillermo Hernandez									
75619					7/21/2011		53		\$0.00
Medium	Work In Progress				7/21/2011 8:09:39 AM				
Estrada, Jesus	VCT tile needs to be replaced, loose tiles double portable (68 DMIR) Classroom P #1 and P #2. Thank you								
Guillermo Hernandez									
Count: 3 Work Orders			Avg. Age of WO's	40	Total for Chaparral Elem East Pre-K		0		\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
77520					8/29/2011		14		\$0.00
Medium	Work In Progress			8/29/2011 1:54:15 PM					
Ontiveros, Joe	Need to replace rusted plugs on the sinks in kinder hallway. Thank yuo								
Guillermo Hernandez									
77984					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 3:42:21 PM					
Hernandez, Guillermo	Memo, As per Mrs. Arnold, please paint letters on cement where K and 1st grades line up. (by concession stand) Thank you								
Guillermo Hernandez									
76918	Main Building	Classroom			8/15/2011		28		\$0.00
Medium	Work In Progress	107		8/15/2011 9:32:45 AM					
Lozoya, Manny	need extra key for room 107. see front office								
Jennifer Corral									
75919					7/27/2011		47		\$0.00
Medium	Work In Progress			7/27/2011 3:55:26 PM					
Ontiveros, Guadalupe	Need to replace compressor on top of the irrigation tank at Chaparral Elementary. Needed tu turn on the buster pump to supply water for CHM, DT and CHE. Thank you								
Guillermo Hernandez									
76936					8/15/2011		28		\$0.00
Medium	Work In Progress			8/15/2011 1:58:50 PM					
Ontiveros, Guadalupe	Need to relocate soccer goals nets to the sides on the field. Thank you								
Guillermo Hernandez									
76819					8/11/2011		32		\$0.00
Medium	Work In Progress			8/11/2011 11:56:43 AM					
Flores, Pete	Truck #155 CHE, shifting lever is stock on park and the light for the anti-lock brakes in on, also truck is making a nocking sound when pressing the brake. Please check. Thank you								
Guillermo Hernandez									
76644	E.Building	Classroom			8/8/2011		35		\$0.00
Medium	Work In Progress	414,416,418		8/8/2011 3:41:07 PM					
Villalobos, Margret	spray for roaches, see memo								
Jennifer Corral									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral ES									
76932					8/15/2011		28		\$0.00
Medium	Work In Progress			8/15/2011 1:06:17 PM					
Hernandez, Guillermo	Memo, please replace squirrel cage to exhaust fans in classroom #220 and #212. Thank you								
<u>Guillermo Hernandez</u>									
78018		Custodial			9/7/2011		5		\$0.00
Medium	Work In Progress			9/7/2011 12:49:26 PM					
Carbajal, Jimmy	need;cordles;drill;to;exchange;for;the;one;i;have;								
<u>Daniel Ramirez</u>									
78019		Custodial			9/7/2011		5		\$0.00
Medium	Work In Progress			9/7/2011 12:51:21 PM					
Carbajal, Jimmy	need;four;vaccum;belts;								
<u>Daniel Ramirez</u>									
77852					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:19 AM					
Hernandez, Guillermo	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78167					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:45 AM					
Hernandez, Guillermo	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77853					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:20 AM					
Hernandez, Guillermo	Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77848					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:18 AM					
Hernandez, Guillermo	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76920	Main Building	Office			8/15/2011		28		\$0.00
Medium	Work In Progress	office		8/15/2011 9:34:06 AM					
Lozoya, Manny	need extra N key for front office for Administrative Intern. See Front office								
<u>Jennifer Corral</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
78184	Main Building	Office			9/12/2011		0		\$0.00
Medium	Work In Progress	office		9/12/2011 10:09:05 AM					
Martinez, Larry		Please pick up 3 boxes of cume folders for Tracy. see Cecy Data Clerk							
<u>Jennifer Corral</u>									
77452					8/25/2011		18		\$0.00
Medium	Work In Progress			8/25/2011 4:01:01 PM					
Ontiveros, Guadalupe		Need to replace irrigation valve on the field. Thank you							
<u>Guillermo Hernandez</u>									
76584					8/7/2011	9/7/2011	36		\$0.00
Medium	Work In Progress			8/7/2011 12:16:34 AM					
Hernandez, Guillermo		Yearly - Chaparral ES-A9 Air Cooled Cond (Yearly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
77613					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 12:21:05 AM					
Hernandez, Guillermo		Monthly - Chaparral ES A-16 Exh Fan (Semi Annual) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
77850					9/4/2011	9/25/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:19 AM					
Hernandez, Guillermo		Monthly - Chaparral ES H-11 Unit Heater Semiannual - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
77851					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:19 AM					
Hernandez, Guillermo		Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
77849					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:18 AM					
Hernandez, Guillermo		Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
77180					8/19/2011		24		\$0.00
Medium	Work In Progress			8/19/2011 3:41:04 PM					
Flores, Pete		Need to replace front tires to mower #0403. Tires are dry and cracked. Size 23 x 10.50 - 12 NHS. Thank you							
Guillermo Hernandez									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
75207					7/7/2011		67		\$0.00
Medium	Work In Progress			7/7/2011 3:13:13 PM					
Orozco, Danny	1.Electrical cord hanging from the ceiling needs to be encased in a power pole. Safety Hazard 2.Air vent right above the steam line is in poor condition with paint chips loose. It poses a sanitation concern by contaminating food.								
<u>Maritza Gonzalez</u>									
75779					7/25/2011		49		\$0.00
Medium	Work In Progress			7/25/2011 1:21:24 PM					
Orozco, Danny	Chemical room wall needs to be replace with RFP, it is falling apart. . SNP Manager Esther C. 824.0048								
<u>Maritza Gonzalez</u>									
76935					8/15/2011		28		\$0.00
Medium	Work In Progress			8/15/2011 1:53:42 PM					
Carrasco, Danny	Need 15 Gal of gas for truck #155, Driving to CHS and scraping field. Thank you								
<u>Guillermo Hernandez</u>									
77509					8/29/2011		14		\$0.00
Medium	Work In Progress			8/29/2011 9:42:46 AM					
Carrasco, Danny	Need 5 gal of gas for the steiner tracktor(DT). Thank you								
<u>Guillermo Hernandez</u>									
78143					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 3:50:14 PM					
Carrasco, Danny	Need 10 gal of diesel for Mower #0403 (Shared by CMS/DT). Thank you								
<u>Guillermo Hernandez</u>									
Count: 28 Work Orders		Avg. Age of WO's 20			Total for Chaparral ES			0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
75288					7/11/2011		63		\$0.00
Medium	Work In Progress			7/11/2011 11:37:19 AM					
Ontiveros, Joe	SCIENCE CLASS RM. D-7 WATER FAUCETS IN CLASS RM. NEED TO BE REPLACED.IF YOU CAN BEFORE SCHOOL STARTS ON AUG.4								
Paul Quinones									
75289					7/11/2011		63		\$0.00
Medium	Work In Progress			7/11/2011 11:43:22 AM					
Ontiveros, Joe	WE NEED TO CHK ISIMET CONTROLS IN ALL SCIENCE CLASS RMS SO THAT THE SOLINOID VALVES CAN BE REPLACED. AND CHK ALL SCIENCE CLASS RMS. THAT DO NOT HAVE HOT ,AND COLD DOMESTIC WATER IN CLASS RM.								
Paul Quinones									
77278					8/23/2011		20		\$0.00
Medium	Work In Progress	Bus Lane		8/23/2011 2:11:32 PM					
Appelzoller, Fred	Need Line Locate / Whole Bus Lane from East to West and along the west end fence from the North End of property to the South End of property. If you have any questions please contact Richard Borrego (Gas Co.) at (575) 642-1540								
Peggy Jo Hernandez									
78131					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 3:31:36 PM					
Ontiveros, Joe	FIELD HOUSE COACH SMITH'S OFFICE REST RM. TOILET NOT FLUSHING,ITS A PRESSURE TYPE TOILET								
Paul Quinones									
78133					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 3:36:05 PM					
Ontiveros, Joe	TWO PLUMBING CLEAN OUTS ARE BROKEN INBETWEEN C,AND D WINGS,AND E WINGS								
Paul Quinones									
77778	Field House	Athletic Field			9/2/2011		10		\$0.00
Medium	Work In Progress	football stadium		9/2/2011 2:11:35 PM					
Sotelo, Enrique	NEED TO REPLACE LIGHTBULBS ON STADIUM LIGHT POLES AND WALKWAY TO FIELD HOUSE. (ADRIAN FLORES)								
Rosa Quezada									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
77347	A-Wing	Classroom			8/24/2011		19		\$0.00
Medium	Work In Progress	a 106		8/24/2011 2:38:26 PM					
Solis, Lorenzo		Room is really cold and my thermostat is brocken. (donna Heddleston)							
Diana Mendoza									
78076	A-Wing	Classroom			9/8/2011		4		\$0.00
Medium	Work In Progress	A106		9/8/2011 1:53:55 PM					
Solis, Lorenzo		Classroom is very cold, please set temperature. (Heddleston)							
Diana Mendoza									
78178					9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 8:46:48 AM					
Quinones, Paul		NEED TO INSTALL 4"WALL VENT IN ART CLASS RM. R-BLDG.							
Paul Quinones									
76305	Field House	Athletic Field			8/2/2011		41		\$0.00
Medium	Work In Progress	FB FIELD		8/2/2011 9:51:41 AM					
Garcia, Jose		Football line practice fields for the season as well the football playing fields. (smith)							
Diana Mendoza									
77903					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:42 AM					
Quinones, Paul		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
77766		Mechanical			9/2/2011		10		\$0.00
High	Work In Progress			9/2/2011 11:05:19 AM					
Sotelo, Enrique		please install emergency shut off switch to boiler as per inspection by inspector gene velasces. code(a.s.m.e csd-1) thank you							
Michael Munoz									
77349		Classroom			8/24/2011		19		\$0.00
Medium	Work In Progress	Welding RM		8/24/2011 2:56:59 PM					
Sotelo, Enrique		There is some kindof electrical short in the welding room. I have had 3 different power sources. Please repair voltage outlets.(Ulibarri)							
Diana Mendoza									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
77712		Classroom			9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 1:24:47 PM					
Martinez, Larry	Pick up the following items from JTP and take them to Chaparral High for Mr. Provencio.								
<u>Virginia Galindo</u>									
78079	A-Wing	Office			9/8/2011		4		\$0.00
Medium	Work In Progress	KAREN		9/8/2011 2:49:38 PM					
Martinez, Larry	PLEASE DELIVER THE FOLLOWING ITEMS TO: KAREN NOUGUES PO # 111200243 - 1 BOX (NET) - CHS VOLLEYBALL								
<u>Terry Alvarado</u>									
78151					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 3:54:56 PM					
Martinez, Larry	On September 14, 2011, please deliver 2 boxes of material to Chaparral High School.								
<u>Yolie Jacquez</u>									
77906					9/4/2011	10/5/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:43 AM					
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75056					7/4/2011		70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:34 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76134					7/31/2011		43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:20 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77904					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:42 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75055					7/4/2011		70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:33 AM					
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
9/12/2011 4:16:29 PM									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
76133					7/31/2011		43		\$0.00
Medium	Work In Progress				7/31/2011 9:25:19 AM				
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
74913					7/4/2011		70		\$0.00
Medium	Work In Progress				7/4/2011 12:21:30 AM				
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.								
Margret Villalobos									
76131					7/31/2011		43		\$0.00
Medium	Work In Progress				7/31/2011 9:25:18 AM				
Quinones, Paul	Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
76132					7/31/2011	8/31/2011	43		\$0.00
Medium	Work In Progress				7/31/2011 9:25:19 AM				
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
76135					7/31/2011		43		\$0.00
Medium	Work In Progress				7/31/2011 9:25:20 AM				
Quinones, Paul	Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
77902					9/4/2011		8		\$0.00
Medium	Work In Progress				9/4/2011 12:24:41 AM				
Quinones, Paul	Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
77905					9/4/2011		8		\$0.00
Medium	Work In Progress				9/4/2011 12:24:43 AM				
Quinones, Paul	Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
77907					9/4/2011	9/7/2011	8		\$0.00
Medium	Work In Progress				9/4/2011 12:24:44 AM				
Quinones, Paul	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.								
Margret Villalobos									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
76602					8/7/2011	9/7/2011	36		\$0.00
Medium	Work In Progress			8/7/2011 12:16:42 AM					
Quinones, Paul	Yearly - Chaparral HS A9(Cool Condenser)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75058					7/4/2011	7/11/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:34 AM					
Quinones, Paul	Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75053					7/4/2011		70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:32 AM					
Quinones, Paul	Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75054					7/4/2011	8/3/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:33 AM					
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75057					7/4/2011		70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:34 AM					
Quinones, Paul	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78181					9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 9:28:11 AM					
Orozco, Danny	FIRE PUMP STATION IN MAIN BUILDING,CONTROL PANEL NEEDS TO BE REPLACED.DUE TO SPRINKLER LEAK FROM ROOF IN MECHANICAL RM.BEHIND KITCHEN								
<u>Paul Quinones</u>									
77346		Office			8/24/2011		19		\$0.00
Medium	Work In Progress	front area		8/24/2011 2:35:30 PM					
Garcia, Jose	The front area of the campus needs to be weeded, trees trimmed the shrubs trimmed and shaped, and the dead part of plants cut off.(Vicky Lopez)								
<u>Diana Mendoza</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
77539					8/29/2011		14		\$0.00
Medium	Work In Progress			8/29/2011 3:46:08 PM					
Garcia, Jose	Please clean coves in between Wings.								
<u>Michael Munoz</u>									
77943		Athletic Field			9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 8:31:13 AM					
Ontiveros, Guadalupe	C.H.S. jose garcia is requesting. Blow Gun, Floor Jack, Jack Stands, tire inflator, tire gauge, Chain Saw, vacuum for court yard and blower,								
<u>Guadalupe Ontiveros</u>									
75059					7/4/2011	7/6/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:35 AM					
Quinones, Paul	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76136					7/31/2011	8/3/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:21 AM					
Quinones, Paul	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77246					8/22/2011		21		\$0.00
Medium	Work In Progress			8/22/2011 4:05:00 PM					
Orozco, Danny	toilet seat is cracked and when it flushes water comes out of the crack that is in the toilet seat. SNP Manger Juanita M. 824.4461								
<u>Maritza Gonzalez</u>									
75963					7/28/2011		46		\$0.00
Medium	Work In Progress	all school doors		7/28/2011 11:57:34 AM					
Lozoya, Manny	check all doors - some need adjustments - specially "A" wing courtyard - it stays open (paul)								
<u>Rosa Quezada</u>									
78085					9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 3:26:00 PM					
Flores, Pete	REQUESTING BOB CAT TRACTER TO CLEAN INBETWEEN WINGS PLEASE CONTACT PETE FROM THE MECHANIC SHOP.								
Paul Quinones									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
75960					7/28/2011		46		\$0.00
Medium	Work In Progress	whole school		7/28/2011 11:54:12 AM					
Vargas, Juan		check fire extinguishers - some need pins replaced (Paul)							
Rosa Quezada									
77508					8/29/2011		14		\$0.00
Medium	Work In Progress			8/29/2011 9:33:52 AM					
Carrasco, Danny		need disel for big tank pump							
Juan Vargas									
78083					9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 3:23:53 PM					
Carrasco, Danny		REQUESTING 10 GALLONS OF GASOLINE FOR WORK TRUCK # 139							
Paul Quinones									
76301	G-Wing	Classroom			8/2/2011		41		\$0.00
Medium	Work In Progress			8/2/2011 9:41:51 AM					
Quinones, Paul		support bar on teacher, teacher desk broken.							
Diana Mendoza									
76302	R-Wing	Classroom			8/2/2011		41		\$0.00
Medium	Work In Progress	kitchen		8/2/2011 9:46:01 AM					
Quinones, Paul		Need TV installed(Adams)							
Diana Mendoza									
76625		Classroom			8/8/2011		35		\$0.00
Medium	Work In Progress	b-5		8/8/2011 10:24:51 AM					
,		in lieu of Paul's absence Adrian Flores needs to install a smartboard in ms. hady's class							
Rosa Quezada									
76626		Office			8/8/2011		35		\$0.00
Medium	Work In Progress	see below		8/8/2011 10:27:43 AM					
,		in paul's absence adrian flores (custodial) needs to install door mail holders for all counselors (4) and registrar and data clerk. (quezada)							
Rosa Quezada									
77204	I-Wing	Gym			8/22/2011		21		\$0.00
Medium	Work In Progress	GYM		8/22/2011 9:56:31 AM					
Vargas, Juan		THE MAIN BASKETBALL ON THR SOUTH AND WILL NOT LOWER ALL THE WAY .(HEREDIA)							
Diana Mendoza									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
77344	A-Wing	Classroom			8/24/2011		19		\$0.00
Medium	Work In Progress	A 110			8/24/2011 2:28:43 PM				
Vargas, Juan		Remove a white board so they can install a samrt board. (Encino)							
Diana Mendoza									
78091	A-Wing	Hallway/Corridor			9/8/2011		4		\$0.00
Medium	Work In Progress	by attendance			9/8/2011 3:32:11 PM				
Lozoya, Manny		panic bar is loose outside door next to attendance office by cafeteria (urquidi)							
Rosa Quezada									
78132					9/9/2011		3		\$0.00
Medium	Work In Progress				9/9/2011 3:34:05 PM				
Lozoya, Manny		LOCK TO WEST SIDE GATE NOT OPENING W/ KEY CUSTODIAL,AND SECURITY ARE HAVING THE SAME PROBLEM.							
Paul Quinones									
75118					7/5/2011		69		\$0.00
Medium	Work In Progress				7/5/2011 1:14:12 PM				
Quinones, Paul		the basketball goal on the south side needs to be adjusted 4 inches after wood floor is refinished. It is off as per James Stout 575-640-7418							
Alfredo Holguin									
75961	A-Wing				7/28/2011		46		\$0.00
Medium	Work In Progress	library and art			7/28/2011 11:55:25 AM				
Vargas, Juan		shelves in library and art dept need to be installed (paul)							
Rosa Quezada									
76212	D-Wing	Classroom			8/1/2011		42		\$0.00
Medium	Work In Progress				8/1/2011 3:51:25 PM				
Vargas, Juan		Needs maps mounted on the wall.(Hubble)							
Diana Mendoza									
76218	F-Wing	Classroom			8/1/2011		42		\$0.00
Medium	Work In Progress				8/1/2011 3:58:42 PM				
Lozoya, Manny		Closets do not lock (montoya)							
Diana Mendoza									
78110		Cafeteria			9/9/2011		3		\$0.00
Medium	Work In Progress	Cafeteria			9/9/2011 9:29:24 AM				
Sotelo, Enrique		Neon lights need to be replaced "on a bun" stand and "old faavorties". ASAP as Mr. Rupcich							
Diana Mendoza									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
75421					7/13/2011		61		\$0.00
Medium	Work In Progress	New Chaparral		7/13/2011 3:14:30 PM					
Lozoya, Manny		New cores (with new keys) need to be installed at the new Pre-K building.							
Peggy Jo Hernandez									
75470	A-Wing	Office			7/14/2011		60		\$0.00
Medium	Work In Progress	rosa's office		7/14/2011 1:55:14 PM					
Lozoya, Manny		cannot open front main door with ch86 -							
Rosa Quezada									
75964	A-Wing	Classroom			7/28/2011		46		\$0.00
Medium	Work In Progress	A-107		7/28/2011 11:58:57 AM					
Lozoya, Manny		key doesn't open door in A-107 - it opens after several attempts but doesn't close door with key (henry)							
Rosa Quezada									
78074	Field House	Football Field			9/8/2011		4		\$0.00
Medium	Work In Progress	press box		9/8/2011 1:44:33 PM					
Lozoya, Manny		press box cannot open with ch86 (quezada)							
Rosa Quezada									
78075					9/8/2011		4		\$0.00
Medium	Work In Progress	gates by		9/8/2011 1:47:23 PM					
Lozoya, Manny		locks need clearing by prescott anthony and dona ana branch where buses come in - hard to open with key (de santiago)							
Rosa Quezada									
Count: 64 Work Orders		Avg. Age of WO's 30		Total for Chaparral HS			0	\$0.00	

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
77961		Classroom			9/6/2011		6		\$0.00
Medium	Work In Progress	308			9/6/2011 9:35:28 AM				
Ontiveros, Joe		Replace 3 faucets in lab area that do not work.							
Albert Vallejo									
77705	Main Building	Classroom			9/1/2011		11		\$0.00
Medium	Work In Progress	ROOM 107			9/1/2011 11:37:20 AM				
Sotelo, Enrique		AS PER SAM ALVA IN SPED DEPARTMENT NEED OUTLET FOR HI-LOW TABLE IN RESTROOM							
Elena Palacios									
75953					7/28/2011		46		\$0.00
Medium	Work In Progress				7/28/2011 10:24:32 AM				
Vallejo, Albert		Paint door jambs to signify specific areas							
Albert Vallejo									
77334		Portables			8/24/2011		19		\$0.00
Medium	Work In Progress	PORTABLE 13			8/24/2011 11:44:37 AM				
Lozoya, Manny		DEBBIE HOLGUIN - DOOR TO STORAGE IN PORTABLE NEEDS TO BE REKEYED IN ORDER TO LOCK ITEMS IN THERE							
Elena Palacios									
77974					9/6/2011		6		\$0.00
Medium	Work In Progress				9/6/2011 1:42:02 PM				
Lozoya, Manny		One of the rod iron that we have on the outside of the windows in room 301 does not lock.							
Robert Gonzalez									
76355					8/3/2011		40		\$0.00
Medium	Work In Progress				8/3/2011 10:31:21 AM				
Ontiveros, Guadalupe		Please replace valves for tree line bubblers. Some do not open.							
Albert Vallejo									
77819					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress				9/4/2011 12:24:05 AM				
Vallejo, Albert		Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
74949					7/4/2011	7/24/2011	70		\$0.00
Medium	Work In Progress				7/4/2011 12:21:47 AM				
Orozco, Danny		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
78119					9/9/2011		3		\$0.00
Medium	Work In Progress	Library		9/9/2011 12:42:18 PM					
Martinez, Larry	Please pick up the following broken infocus and dispose T-I 101387, T-I 101375, T-I 101381, T-II 104072, T-II 104070, F02158, T-I 101376, T-I 101377, T-I 101384, T- II 104066,								
Lucia Almeraz									
76053					7/31/2011	8/31/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:24:44 AM					
Vallejo, Albert	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
77814					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:03 AM					
Vallejo, Albert	Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
77815					9/4/2011	10/5/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:04 AM					
Vallejo, Albert	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
77817					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:04 AM					
Vallejo, Albert	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
77818					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:05 AM					
Vallejo, Albert	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
76143					7/31/2011		43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:23 AM					
Sanchez, Raul	Monthly - Chaparral MS - DP-781 - Refer to PM schedule details.								
Margret Villalobos									
78192					9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 11:08:57 AM					
Lozoya, Manny	Repair or replace doors in office area that were damaged during break-in								
Albert Vallejo									

9/12/2011 4:16:29 PM

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
78193					9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 11:11:39 AM					
Munoz, Michael	Repair fence on west side of school that was cut.								
<u>Albert Vallejo</u>									
76054					7/31/2011	8/3/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:24:44 AM					
Vallejo, Albert	Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77816					9/4/2011	9/7/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:04 AM					
Vallejo, Albert	Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76582					8/7/2011	9/7/2011	36		\$0.00
Medium	Work In Progress			8/7/2011 12:16:33 AM					
Vallejo, Albert	Yearly - Chaparral MS A9 (AC Condsr.)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76052					7/31/2011		43		\$0.00
Medium	Work In Progress			7/31/2011 9:24:43 AM					
Vallejo, Albert	Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77059		Classroom			8/17/2011		26		\$0.00
Medium	Work In Progress	PORTABLE 10		8/17/2011 1:17:00 PM					
Vallejo, Albert	PLEASE MOVE TV IN SOCIAL WORKERS PORTABLE 9 TO MR. MARTINEZ'S PORTABLE 10								
<u>Elena Palacios</u>									
77704		Classroom			9/1/2011		11		\$0.00
Medium	Work In Progress	ROOM 107		9/1/2011 11:36:00 AM					
Vallejo, Albert	AS PER SAM ALVA IN SPED DEPARTMENT, BOLTS HOLDING TOILET TO FLOOR LOOSE TOILET WOBBLER WILL FALL OVER IS NOT CAREFUL.								
<u>Elena Palacios</u>									
78191					9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 11:03:53 AM					
Ronquillo, Ruben	Replace (2) 6"x 24"x 1/4", (1) 4"x 22"x 1/4", (1) 36"x 48"x 1/4" windows. All wired glass.								
Albert Vallejo									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral MS								
76354					8/3/2011		40		\$0.00	
Medium	Work In Progress			8/3/2011 10:27:46 AM						
Gonzalez, Salvador	Please fabricate expanded metal guard around exterior water fountain, located outside the gym door.									
Albert Vallejo										
76977					8/16/2011		27		\$0.00	
Medium	Work In Progress			8/16/2011 8:17:26 AM						
Lozoya, Manny	Door to room 404 has damaged hinges and no longer closes properly. they need to be replaced.									
Albert Vallejo										
75538	Main Building	Mechanical			7/19/2011		55		\$0.00	
Medium	Work In Progress			7/19/2011 10:56:27 AM						
Orozco, Danny	Mercury pressure switch on fire suppression system needs to be replaced.									
Albert Vallejo										
Count: 27 Work Orders		Avg. Age of WO's 23		Total for Chaparral MS			0	\$0.00		

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
76480		Classroom			8/5/2011		38		\$0.00
Medium	Work In Progress	4		8/5/2011 8:33:08 AM					
Lara, Ralph	TWO DOOR CABINET NEEDS A KEY IF YOU HAVE ANY OR EXTRA KEY THAT MIGHT FIT TO SECURE SUPPLIES FOR ART TEACHER.								
<u>David Acosta</u>									
78180		Portables			9/12/2011		0		\$0.00
Medium	Work In Progress	ROOM 1		9/12/2011 8:52:32 AM					
Lara, Ralph	CYLINDER CAME OUT OF DOOR HANDLE WHILE REMOVING KEY.								
<u>David Acosta</u>									
78010		Classroom			9/7/2011		5		\$0.00
Medium	Work In Progress	Boxing room		9/7/2011 10:25:23 AM					
Ronquillo, Ruben	JC Fernandez, Boxing coach, needs to transfer 5 punching bags at the warehouse.								
<u>Mary Telles</u>									
76993		Custodial			8/16/2011		27		\$0.00
Medium	Work In Progress			8/16/2011 10:53:55 AM					
Carrasco, Danny	need 5 gallons of fuel for lawnmower- m-dp-0432								
<u>David Acosta</u>									
77826					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:09 AM					
Acosta, David	Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77828					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:09 AM					
Acosta, David	Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77918					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:48 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77827					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:09 AM					
Acosta, David	Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Desert Pride							
77566		Portables			8/30/2011		13		\$0.00
Medium	Work In Progress	ROOM 5			8/30/2011 9:17:14 AM				
Ambriz, Jose		TEACHER REPORTED THAT A/C IS NOT COOLING SUFFICIENTLY FOR AFTER NOON HEAT (REPLACE FILTER LAST THURSDAY).							
David Acosta									
Count: 9 Work Orders		Avg. Age of WO's 13			Total for Desert Pride			0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
78111					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 10:14:18 AM					
Ontiveros, Joe	Room #104: Have checked sink bubbler but no water comes out. Need Assistance.								
<u>Johnny Acuna</u>									
78118					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 12:40:06 PM					
Ontiveros, Joe	Need to borrow floor snake to unclogg floor drain in washing room to kitchen. Water backs up through floor drain.								
<u>Johnny Acuna</u>									
77583					8/30/2011		13		\$0.00
Medium	Work In Progress			8/30/2011 1:33:24 PM					
Solis, Lorenzo	Portable #409: Window unit is not cooling. visual signs of a leak. Already removed unit from wall, clean, and tried to locate leak.								
<u>Johnny Acuna</u>									
75912					7/27/2011		47		\$0.00
Medium	Work In Progress			7/27/2011 3:45:58 PM					
Lozoya, Manny	Need a key issued to open up new covers for irrigation valves underground.								
<u>Johnny Acuna</u>									
77640					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 9:56:24 AM					
Ontiveros, Guadalupe	Please re-locate soccer goals in the playground area.								
<u>Johnny Acuna</u>									
78056					9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 7:47:13 AM					
Ontiveros, Guadalupe	Need to install insulation box to main backflow valves at chaparral elementary Irrigation system. (Main valves next to Lisa Dr.)								
<u>Johnny Acuna</u>									
77864					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:25 AM					
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
74950					7/4/2011	7/24/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:21:47 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
9/12/2011 4:16:29 PM									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
77959					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 9:16:37 AM					
Carbajal, Jimmy	Por favor de arreglar las aspiradora #0056. Las llantas de atras estan quebradas.								
Laura Sandoval									
77862					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:24 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
77863					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:24 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
77865					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:25 AM					
Acuna, Johnny	Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
78169					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:46 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
75105					7/5/2011		69		\$0.00
Medium	Work In Progress			7/5/2011 12:16:34 AM					
Sanchez, Raul	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.								
Margret Villalobos									
77938					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 12:20:02 AM					
Sanchez, Raul	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.								
Margret Villalobos									
78115					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 11:02:39 AM					
Carrasco, Danny	Need to borrow scissor lift.								
Johnny Acuna									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
77095					8/18/2011		25		\$0.00
Medium	Work In Progress			8/18/2011 7:57:01 AM					
Carrasco, Danny	Please fuel up work truck. (Unleaded Gasoline) Worktruck #192								
Johnny Acuna									
77971					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 12:16:24 PM					
Carrasco, Danny	Please fuel up (Unleaded Gasoline) work truck #192, and Diesel for riding mower #403								
Johnny Acuna									
78114					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 10:49:55 AM					
Carrasco, Danny	Please fuel up Steiner tractor (Unleaded Gas)								
Johnny Acuna									
77069					8/17/2011		26		\$0.00
Medium	Work In Progress			8/17/2011 2:53:44 PM					
Munoz, Michael	need to modify the parent drop-off area by adding another gate south of current entrance to parking lot, base course for drive way, signage and painting of payment lines.								
Alfredo Holguin									
76588					8/7/2011	9/7/2011	36		\$0.00
Medium	Work In Progress			8/7/2011 12:16:35 AM					
Acuna, Johnny	Yearly - Desert Trail ES A9(Air Condenser)(Yrly) - Refer to PM schedule details.								
Margret Villalobos									
77576					8/30/2011		13		\$0.00
Medium	Work In Progress			8/30/2011 10:50:54 AM					
Ronquillo, Ruben	Ruben Ronquillo: Need to borrow long trailer. Thank You....								
Johnny Acuna									
76028					7/29/2011		45		\$0.00
Medium	Work In Progress			7/29/2011 3:39:10 PM					
Orozco, Danny	1).milk cooler is making ice 2) the sink where you wash your hands the faucet is leaking water 3) faucet from the salad sink is loose 4) the sink from the pots and pans is also leaking water. SNP Manager Pat C. 824.3822.								
Maritza Gonzalez									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
76883					8/12/2011		31		\$0.00
Medium	Work In Progress			8/12/2011 11:50:32 AM					
Orozco, Danny	1) SNEEZE SHIELD ON ASSEMBLY LINE WERE BROKEN BY STUDENTS. 2) LADIES ARE HAVING A HARD TIME WITH RAILS/COVERS IN OVEN IS, GETTING STUCK. SNP MANAGER PAT C. 824.3822								
Maritza Gonzalez									
77942					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 8:22:19 AM					
Moncayo, Fernando	the milk cooler from the steam line is not working. SNP Manager Pat C. 824.3822								
Maritza Gonzalez									
78002					9/7/2011		5		\$0.00
Medium	Work In Progress			9/7/2011 8:40:13 AM					
Moncayo, Fernando	temperature from the walk-in is at 48 degrees. SNP Manager Pat C. 824.3822								
Maritza Gonzalez									
75597					7/20/2011		54		\$0.00
Medium	Work In Progress			7/20/2011 3:39:53 PM					
Gonzalez, Salvador	Please make (2) ramps for steiner tractor to be used to go in and out of concrete swell in the back and west side of school grounds.								
Johnny Acuna									
Count: 27 Work Orders			Avg. Age of WO's	19	Total for Desert Trail Intermediate			0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
78195					9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 11:58:51 AM					
Villalobos, David	Need line locate from current backflow preventor all the way around rock wall to third portable on the north side. please coordinate with contractor Joe Garcia/ESA Construction (915) 549-4582								
Peggy Jo Hernandez									
75705					7/22/2011		52		\$0.00
Safety	Work In Progress			7/22/2011 2:22:30 PM					
Castillo, Carlos	Freezer in kitchen is making sparks.								
Aida Salcedo									
78194					9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 11:58:11 AM					
Castillo, Carlos	Need line locate from current backflow preventor all the way around rock wall to third portable on the north side. please coordinate with contractor Joe Garcia/ESA Construction (915) 549-4582								
Peggy Jo Hernandez									
77944	Main Building	Office			9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 8:34:47 AM					
Ambriz, Jose	Office A/C not working								
Ruben Ortiz									
76394		Office			8/3/2011		40		\$0.00
Medium	Work In Progress	Teacher's		8/3/2011 3:45:11 PM					
Lara, Ralph	Install a Door Closer in the Teacher's Lounge. (Gonzalez)								
Guadalupe Gonzalez									
75482					7/14/2011		60		\$0.00
Medium	Work In Progress			7/14/2011 4:20:12 PM					
Flores, Pete	Lawnmower not working, need to have it repaired. It doesn't start. Thank you, Ruben								
Ruben Ortiz									
77531		Office			8/29/2011		14		\$0.00
Medium	Work In Progress	Office		8/29/2011 3:18:32 PM					
Munoz, Michael	Move the existing counter towards the window located in the Office and move the Handicap table towards the door. (Gonzalez)								
Guadalupe Gonzalez									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
78124					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 2:44:06 PM					
Munoz, Michael	need to construct concret pad for trash dumpsters								
Alfredo Holguin									
77736		Cafeteria			9/1/2011		11		\$0.00
High	Work In Progress			9/1/2011 3:50:17 PM					
Ortiz, Ruben	a/c is making some loud noises. could you please check and repair. (belt or bearings)thankyou								
Michael Munoz									
77951		Custodial			9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 8:48:32 AM					
Carbajal, Jimmy	This work order is for a broken vaccum cleaner it makes a lot of noise.Also I will need a loaner,THANK YOU IN ADVANCED.								
Hector Rivera									
77925					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:51 AM					
Ortiz, Ruben	Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
77926					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:52 AM					
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
77928					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:53 AM					
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
76606					8/7/2011	8/23/2011	36		\$0.00
Medium	Work In Progress			8/7/2011 12:16:44 AM					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
78175					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:49 AM					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
77927					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:52 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76349					8/3/2011		40		\$0.00
Medium	Work In Progress			8/3/2011 9:39:27 AM					
Orozco, Danny	1) VACUUM BREAKER TO FINAL RINSE TO DISHWASHER. 2) SHUT OFF VALVE TO DISHWASHER IS ON BACK NEED TO RESET TO FRONT. SNP MANAGER DIANA L. 589.2425								
<u>Maritza Gonzalez</u>									
76430					8/4/2011		39		\$0.00
Medium	Work In Progress			8/4/2011 10:19:15 AM					
Orozco, Danny	SCREEN DOOR NEEDS TO BE REPLACED IN KITCHEN. SNP MANAGER EMILIA C. 589.2550								
<u>Maritza Gonzalez</u>									
77283		Athletic Field			8/23/2011		20		\$0.00
Medium	Work In Progress			8/23/2011 3:10:58 PM					
Carrasco, Danny	Need 8 gal of gas for 061 truck and 2gal for 607 weed eaters, blowers and 5gal 402 mower. Thank You Ruben								
<u>Ruben Ortiz</u>									
77701					9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 11:08:36 AM					
Ortiz, Ruben	please purchase new D130 john deere lawn mower to replace existing one.								
<u>Michael Munoz</u>									
76605					8/7/2011	9/7/2011	36		\$0.00
Medium	Work In Progress			8/7/2011 12:16:44 AM					
Ortiz, Ruben	Yearly - Desert View ES A-9 Air Cooled Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77616					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 12:21:06 AM					
Ortiz, Ruben	Monthly - Desert View ES A-16 Fan Exhaust (Semi) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76003					7/29/2011		45		\$0.00
Medium	Work In Progress			7/29/2011 9:00:38 AM					
Ortiz, Ruben	Need to replace 16 120 sprinklers and blubbers								
<u>Ruben Ortiz</u>									
9/12/2011 4:16:29 PM									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
76002					7/29/2011		45		\$0.00
Medium	Work In Progress			7/29/2011 8:59:03 AM					
Ortiz, Ruben	Need to fertilize the grass								
Ruben Ortiz									
76000					7/29/2011		45		\$0.00
Medium	Work In Progress			7/29/2011 8:57:23 AM					
Ortiz, Ruben	Need to remove dirt and drag weeds on school grounds								
Ruben Ortiz									
76623		Classroom			8/8/2011		35		\$0.00
Medium	Work In Progress	Mrs. B.		8/8/2011 9:47:12 AM					
Ortiz, Ruben	Her In Focus projector on the white board is not mounted right. As a matter a fact the screw is stripped. I did not do the stripping. It was already messed up when I went to fix it for her.								
77375					8/24/2011		19		\$0.00
Medium	Work In Progress			8/24/2011 4:27:33 PM					
Ortiz, Ruben	Paint and put up no parking signs								
Ruben Ortiz									
75780					7/25/2011		49		\$0.00
Medium	Work In Progress			7/25/2011 1:22:23 PM					
Orozco, Danny	3-Compartment sink leaking—gaskets need to be replaced per construction manager. They are not responsible for this.								
Aida Salcedo									
Count: 28 Work Orders		Avg. Age of WO's 23		Total for Desert View ES			0	\$0.00	

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
78014					9/7/2011		5		\$0.00
Medium	Work In Progress			9/7/2011 11:17:29 AM					
Villalobos, David	pleaae look into watervlve that was installed for proper installation. this valve was installed this morning on a leak we had the last night.thank you								
Michael Munoz									
77034					8/16/2011		27		\$0.00
Medium	Work In Progress			8/16/2011 3:51:51 PM					
Lara, Ralph	SENSOR TO FRONT DOOR NOT WORKING PROPERLY.								
Maritza Gonzalez									
77515					8/29/2011		14		\$0.00
Medium	Work In Progress			8/29/2011 11:13:43 AM					
Lara, Ralph	NEED ONE A-39 KEY MADE.								
Maritza Gonzalez									
75454					7/14/2011		60		\$0.00
Medium	Work In Progress			7/14/2011 8:29:13 AM					
Ambriz, Juan	WALL UNIT IN CAROLYN LINDAU OFFICE WENT OUT.								
Maritza Gonzalez									
75891	Pre-K				7/27/2011		47		\$0.00
Medium	Work In Progress	Room 201		7/27/2011 11:18:36 AM					
Ambriz, Juan	Please repair dramatic play furniture (stove) in room 201 door fell off & missing hinges Please install new tires & pedals on PreK trikes Thank you								
Lucia Almeraz									
76023					7/29/2011		45		\$0.00
Medium	Work In Progress			7/29/2011 3:15:19 PM					
Ambriz, Juan	As per Mrs. Yturalde the light bulb to be changed in Sofia's and Jesse's office claiming not enough lighting. Thank you								
Maritza Gonzalez									
74951					7/4/2011	7/24/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:21:47 AM					
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
76939					8/15/2011		28		\$0.00
Medium	Work In Progress	motor pool		8/15/2011 2:24:42 PM					
Flores, Pete		Please replace windshield wipers on car #9 Tina Guillen							
Lucia Almeraz									
78001					9/7/2011		5		\$0.00
Medium	Work In Progress			9/7/2011 8:27:40 AM					
Ambriz, Juan		there is a water leak in front of main entrance. please check and repair.							
Michael Munoz									
76594					8/7/2011	9/7/2011	36		\$0.00
Medium	Work In Progress			8/7/2011 12:16:38 AM					
Ambriz, Juan		Yearly - GAC A-9 Air Cooled Condensor Yearly - Refer to PM schedule details.							
Margret Villalobos									
77877					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:30 AM					
Ambriz, Juan		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
77879					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:31 AM					
Ambriz, Juan		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
78170					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:47 AM					
Ambriz, Juan		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
77878					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:31 AM					
Ambriz, Juan		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
77058					8/17/2011		26		\$0.00
Medium	Work In Progress	Ray's office		8/17/2011 12:41:43 PM					
Ambriz, Juan		Please install armrest on Ray's chair							
Lucia Almeraz									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
77504					8/29/2011		14		\$0.00
Medium	Work In Progress			8/29/2011 9:22:23 AM					
Ambriz, Juan	B-WING/PAINT TWO MIRRORS THAT NEED TO BE PLACED IN RESTROOM , IN FRONT OF RECEPTIONIST AREA								
Maritza Gonzalez									
77767					9/2/2011		5		\$0.00
Medium	Work In Progress			9/2/2011 11:08:09 AM	9/7/2011				
Estrada, Jesus	DUMPSTER NEEDS TO BE SWITCHED OUT OR CLEANED. VERY FOUL SMELL.				9/6/11 - DUMPSTERS @ ALL SITES ARE SCHEDULED TO BE EXCHANGED OR WASHED OUT FOR CLEAN ONES.				
Maritza Gonzalez									
78006					9/7/2011		5		\$0.00
Medium	Work In Progress			9/7/2011 9:43:23 AM					
Ambriz, Juan	WATER LEAK IN FRONT LANDSCAPE AREA BY BISTRO.								
Maritza Gonzalez									
78120					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 1:12:32 PM					
Ambriz, Juan	REPAIR SIDEWALK BY MAIN ENTRANCE.								
Maritza Gonzalez									
77986					9/6/2011		6		\$0.00
Medium	Work In Progress	vehicle#140		9/6/2011 3:43:28 PM					
Carrasco, Danny	Need 15gallon of fuel for vehicle #140, 407mower, 608blowe/weedeater								
Juan Ambriz									
Count: 20 Work Orders		Avg. Age of WO's		21		Total for GAC		0 \$0.00	

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		GAC - Pre-K							
75337					7/12/2011		62		\$0.00
Medium	Work In Progress				7/12/2011 3:16:00 PM				
Ontiveros, Guadalupe	NEED MORE SAND FOR SANDBOX IN PRE-K PLAYGROUND.								
<u>Maritza Gonzalez</u>									
75814					7/26/2011		48		\$0.00
Medium	Work In Progress				7/26/2011 8:47:41 AM				
Ambriz, Jose	A/C IN PRE-K CAFETERIA NOT COOLING PROPERLY.								
<u>Maritza Gonzalez</u>									
Count: 2 Work Orders			Avg. Age of WO's	55		Total for GAC - Pre-K	0		\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden ES									
76934					8/15/2011		28		\$0.00
Medium	Work In Progress			8/15/2011 1:35:39 PM					
Appelzoller, Fred	need a hose valve connector on the south side wall... greatly appreciate your assistance in this matter....								
Loraine Gandara									
78182		Classroom			9/12/2011		0		\$0.00
Medium	Work In Progress	rm 206		9/12/2011 10:00:08 AM					
Sotelo, Enrique	electical plug next to sink is not working... please assist in this matter greatly appreciate your assistance								
Loraine Gandara									
77015					8/16/2011		27		\$0.00
Medium	Work In Progress			8/16/2011 3:19:04 PM					
Solis, Lorenzo	need assistance with the vent in room 101... greatly appreciate your assistance in this matter....								
Loraine Gandara									
77694		Classroom			9/1/2011		11		\$0.00
Medium	Work In Progress	washigton wk		9/1/2011 9:11:36 AM					
Lozoya, Manny	requesting an additional key for Mr. Hinojosa for Washington Wk room								
Loraine Gandara									
75638					7/21/2011		53		\$0.00
Medium	Work In Progress			7/21/2011 3:05:18 PM					
Moncayo, Fernando	REQUEST #75636 TO REMOVE BLUE LIGHT BULBS FROM ROOM 202 F NEVAREZ TO ROOM 101 F NEVAREZ SHOULD BE AT GADSDEN ELEMENTARY								
Margaret Villalobos									
76334					8/2/2011		41		\$0.00
Medium	Work In Progress	nurses office		8/2/2011 4:03:53 PM					
Moncayo, Fernando	nurses needs assistance in putting up boards in her office								
Loraine Gandara									
78066		Custodial			9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 10:43:20 AM					
Carbajal, Jimmy	need a 6 ft.step ladder								
Jose Pinion									
77846					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:17 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.								
Margret Villalobos									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden ES									
77847					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:17 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78166					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:44 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77845					9/4/2011	9/15/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:17 AM					
Moncayo, Fernando	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76068					7/31/2011	8/21/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:24:51 AM					
Orozco, Danny	Monthly - Gadsden ES Fire Sprinkler Insp -Qrtly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77196					8/22/2011		21		\$0.00
Medium	Work In Progress			8/22/2011 7:58:56 AM					
Carrasco, Danny	Need diesel fuel for bobcat								
<u>Fernando Moncayo</u>									
77140					8/19/2011		24		\$0.00
Medium	Work In Progress			8/19/2011 9:01:22 AM					
Orozco, Danny	LEAK IN KITCHEN ROOF.SNP MANAGER CUCA P. 882.3410		AS PER FERNANDO, HE IS WORKING ON IT.						
<u>Maritza Gonzalez</u>									
77966					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 10:28:00 AM					
Moncayo, Fernando	DISHWASHER MAKING A LOUD NOISE WHEN IT IS IN REFILL CYCLE. SNP MANAGER CUCA P. 882.3410								
<u>Maritza Gonzalez</u>									
77668					8/31/2011		12	6	\$150.00
Medium	Work In Progress			8/31/2011 3:38:58 PM					
Ronquillo, Ruben	vandalism;Broken windows,1-entrance door glass panel,1-sidelite glass panel and 5-interior door glass windows (201109293)		custodial labor hours under Joe Pinon, completed by J.Pinon, M. Fattorini and O. Esparza (2 hrs ea)						
<u>Fernando Moncayo</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden ES									
76933					8/15/2011		28		\$0.00
Medium	Work In Progress			8/15/2011 1:34:16 PM					
Moncayo, Fernando	please set up irrigation system for new plants in front of the school... greatly appreciate your assistance in this matter...								
<u>Loraine Gandara</u>									
77320					8/24/2011		19		\$0.00
Medium	Work In Progress			8/24/2011 8:18:18 AM					
Moncayo, Fernando	water daily in the morning planters in front of building until irrigation system is in place.. greatly appreciate your assistance in this matter....								
<u>Loraine Gandara</u>									
77844					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:16 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77207					8/22/2011		21		\$0.00
Medium	Work In Progress			8/22/2011 10:38:11 AM					
Moncayo, Fernando	ROOF LEAK IN KITCHEN, SNP MANAGER CUCA P. 882.3410								
<u>Maritza Gonzalez</u>									
77297					8/23/2011		20		\$0.00
Medium	Work In Progress			8/23/2011 3:51:26 PM					
Moncayo, Fernando	need the trenching machine and the line locate for GES								
<u>Fernando Moncayo</u>									
77343		Classroom			8/24/2011		19		\$0.00
Medium	Work In Progress	101		8/24/2011 2:28:03 PM					
Moncayo, Fernando	need assistance with washer and dryer in room 101.... greatly appreciate your assistance....								
<u>Loraine Gandara</u>									
77578					8/30/2011		13		\$0.00
Medium	Work In Progress			8/30/2011 11:21:44 AM					
Marquez, Gerardo	please repair cracks walls, texture and paint thru-out site.thank you								
<u>Michael Munoz</u>									
78065		Computer Lab			9/8/2011		4		\$0.00
Medium	Work In Progress	201		9/8/2011 10:26:56 AM					
Moncayo, Fernando	needs assistance with the vent in room 201 bathroom... greatly appreciate your assistance.								
<u>Loraine Gandara</u>									

9/12/2011 4:16:30 PM

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Gadsden ES							
78093		Classroom			9/8/2011		4		\$0.00
Medium	Work In Progress	204			9/8/2011 3:39:22 PM				
Moncayo, Fernando		please check air vents... rattling and loud noise greatly appreciate your assistance							
Loraine Gandara									
Count: 25 Work Orders		Avg. Age of WO's 17			Total for Gadsden ES			6	\$150.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
77274	North Building	Restroom (Boys)			8/23/2011		20		\$0.00
Medium	Work In Progress			8/23/2011 1:17:36 PM					
Appelzoller, Fred	water line bust at the restroom bldg on the north side of campus by the soccer fields								
<u>Mario Apodaca</u>									
77469					8/26/2011		17		\$0.00
Medium	Work In Progress			8/26/2011 8:46:40 AM					
Appelzoller, Fred	Requested by Coach Banister Football Locker Room Boy's Gym-Commode in Varsity Locker Room is leaking.								
<u>Velia Alarcon</u>									
77759					9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 9:51:16 AM					
Appelzoller, Fred	Requested by Mrs. Pena Rm. 208 & 209 North Building- There is a leak under the sink. Sink on back (south) of room by window. Teacher placed a bowl underneath sink. Please repair as soon as possible.								
<u>Velia Alarcon</u>									
78029	Boys Gym				9/7/2011		5		\$0.00
High	Work In Progress			9/7/2011 2:59:38 PM					
Appelzoller, Fred	please check all dressing rooms and make sure that all urinals, commodes and faucets are operating properly. . this is a priority thank you								
<u>Michael Munoz</u>									
78027	Boys Gym				9/7/2011		5		\$0.00
High	Work In Progress			9/7/2011 2:57:31 PM					
Appelzoller, Fred	please check and repair all showers. make sure they have hot water and that they operate. this is a priority.thank you								
<u>Michael Munoz</u>									
78034	Main Building				9/7/2011		5		\$0.00
High	Work In Progress			9/7/2011 3:34:58 PM					
Appelzoller, Fred	as per our converstion, please connect all condensation drains from hvac units to a drain. water is seeping beneath building. this is a safety concern. thank you								
<u>Michael Munoz</u>									
78069					9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 11:16:53 AM					
Carbajal, Jimmy	Requested by Mr. Cordova for Stage Area in the Varsity Gym-Chair carts under stage need new wheels. Wheels are damaged and will scratch new wood floor.								
<u>Velia Alarcon</u>									

9/12/2011 4:16:30 PM

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

76762					8/10/2011		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/10/2011 9:12:44 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe Requested by Coach Yanez for Baseball Field-Move baseball storage shed directly behind dugout and surround it with a fence and gate to prevent any more thefts of our equipment.

Velia Alarcon

76915	Concession	Football Field			8/15/2011		28		\$0.00
-------	------------	----------------	--	--	-----------	--	----	--	--------

High	Work In Progress			8/15/2011 8:40:08 AM					
------	------------------	--	--	----------------------	--	--	--	--	--

Munoz, Joe Please make sure everthing is clean at Concession Stand...Floor, Windows, Kitchen area and restrooms.

Michael Munoz

77251					8/23/2011		20		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress			8/23/2011 7:12:40 AM					
------	------------------	--	--	----------------------	--	--	--	--	--

Munoz, Joe Trash on grounds has to be picked up on a daily basis. Trash barrels have to be dumped on a daily basis. This si part of your daily duties and part of your job description.

Jesus Estrada

77250	Academic Bldg	Hallway/Corridor			8/23/2011		20		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/23/2011 7:09:44 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Munoz, Joe Hallway walls need to be scrubbed with GP Forward.

Jesus Estrada

77769					9/2/2011		10		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/2/2011 11:12:33 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Munoz, Joe Requested by Velia for New Administrative Building- Three paper towel dispensers are needed. One To be installed in the Women's and Men's Restrooms. The third in the Work Room # 724. PLEASE SEE DEBBIE COSTALEZ or VELIA FOR FURTHER INSTRUCTIONS. 9/6 - e-mailed & mailed work order to joe.

Velia Alarcon

77960					9/6/2011		6		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress			9/6/2011 9:30:38 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Munoz, Joe FIRST HOME GAME TONIGHT, NEED TO CLEAN SPIDER WEBS ON DOORS TO GYM (COMING SOUTH FROM NEW ADMINISTRATION BUILDING)

Margaret Villalobos

76012	Library	Library			7/29/2011		45		\$0.00
-------	---------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/29/2011 12:58:58 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Gallegos, Rafael Warrantly several arius on the carpet are coming ungluedin the new Library

Mario Apodaca

9/12/2011 4:16:30 PM

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
75781	Main Building	Classroom			7/25/2011		49		\$0.00
Medium	Work In Progress				7/25/2011 2:01:50 PM				
Solis, Lorenzo	Need to put new vents for ac units In class room to balance out air on the east side of building								
Mario Apodaca									
76747					8/10/2011		33		\$0.00
High	Work In Progress				8/10/2011 8:05:35 AM				
Ambriz, Jose	Ice Machine not working at grounds shop								
Guadalupe Ontiveros									
77046					8/17/2011		26		\$0.00
Medium	Work In Progress				8/17/2011 9:30:10 AM				
Holguin, Alfredo	Requested by Ms. Seiler for Rm. 134 Old English Building-Room has become increasing in mold and is causing allergic reactions in me and may very possibly in students whom I serve here at GHS. Administration has indicated to me that they are looking for another room to move me to, until they can. Please provide me with an air purifier to purify the air and minimize the health effects of the poor air quality in room 134.								
Velia Alarcon									
77756					9/2/2011		10		\$0.00
Medium	Work In Progress				9/2/2011 9:38:08 AM				
Apodaca, Mario	Requested by Mr. Cordova for Varsity Gym-There are two big blowers on the top of the stairs (inside-on top of the stage) that are not blowing at all. If there is a switch, can you please show us where and how to turn them on. These blowers will need to be turned on for all future plays.								
Velia Alarcon									
76761					8/10/2011		33		\$0.00
Medium	Work In Progress				8/10/2011 9:04:47 AM				
Ontiveros, Guadalupe	Requested by Coach Hite for Practice Football Fields-Need both practice Football Fields marked so that Football and Band can use for practice when Soccer is using stadium field. If possible before the end of the week.								
Velia Alarcon									
75625					7/21/2011		53		\$0.00
Medium	Work In Progress				7/21/2011 10:20:47 AM				
Sanchez, Raul	Domestic Water Storag Tank- Perform cleaning and inspections of interior of tank including the one at GMSI Inspection needs to be performed according to AWWA D101-53 Standard.								

Alfredo Holguin

9/12/2011 4:16:30 PM

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
76903					8/14/2011		29		\$0.00
Medium	Work In Progress			8/14/2011 12:18:19 AM					
Sanchez, Raul		Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
77912					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:46 AM					
Sanchez, Raul		Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
77870					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:27 AM					
Herrera, Joel		Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
78082	Boys Gym				9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 3:11:51 PM					
Munoz, Michael		By boys gym outside site walk needs to be repaired about 20 feet for the wheelchairs that use it everyday							
Mario Apodaca									
77276	North Building	Restroom (Boys)			8/23/2011		20		\$0.00
Medium	Work In Progress			8/23/2011 1:27:49 PM					
Estrada, Jesus		due to a water leak there could be mold growing in the soccer fields restroom bldg and some parts of the floor are bubbling up				ASP CHUY, JOE TO CLEAN UP MOLD AND SEE HOW BAD THE FLOOR IS WARPED. MAILED TO JOE 9/6			
Mario Apodaca									
77867					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:26 AM					
Herrera, Joel		Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
77868					9/4/2011	10/5/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:26 AM					
Herrera, Joel		Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
77871					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:28 AM					
Herrera, Joel		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
77893					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:37 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
77894					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:38 AM					
Apodaca, Mario	Monthly - Gadsden HS - Elevator (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
75447					7/14/2011		60		\$0.00
Medium	Work In Progress			7/14/2011 12:16:25 AM					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
77947		Athletic Field			9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 8:44:38 AM					
Ontiveros, Guadalupe	Mike soria and ramiro are requesting, Sthil blower and Sthil vacum for football P.M.Chain saw,tire inflator, tire gauge. Stock weedeater string,weedeater sthil head complete, 2cycle oil,pointshovel, square shovel.								
Guadalupe Ontiveros									
78153		Football Field			9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 3:55:16 PM					
Holguin, Alfredo	Running Track- needs the ruberized surface repaired at various places and lines repaitted. the long jumb runway also needs repairs.								
Guadalupe Ontiveros									
77869					9/4/2011	9/7/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:27 AM					
Herrera, Joel	Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
78172					9/11/2011		1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:48 AM					
Apodaca, Mario	Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
75039					7/4/2011	7/11/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:27 AM					
Apodaca, Mario		Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
74912					7/4/2011		70		\$0.00
Medium	Work In Progress			7/4/2011 12:21:29 AM					
Holguin, Alfredo		Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									
77763					9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 10:38:16 AM					
Lara, Ralph		Requested by Velia for New Adminstative Building-The door to Office # 702 does not automaticaly close when door is pulled shut.							
Velia Alarcon									
78049					9/7/2011		5		\$0.00
Medium	Work In Progress			9/7/2011 3:57:06 PM					
Lara, Ralph		Requested by Velia for Attendance Office Door-Door is making a popping/screeching noise when door is opened.							
Velia Alarcon									
78123	Football Stadium	Football Field			9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 2:39:05 PM					
Munoz, Michael		1 more section of fence needs to be replaced at the football field on the north end of campus							
Mario Apodaca									
76503					8/5/2011		0		\$0.00
Medium	Work In Progress			8/5/2011 11:12:06 AM	8/5/2011				
Gonzalez, Salvador		Requested by Lupe Quinones for Faculty Parking Lot- Install a cement ramp at the left far end by the "G" hall of the North Building. This ramp will serve as a come and go with the Security Golf Cart as well as for Maintenance Cart. By placing this ramp there well be two parking spaced eliminated. For further instruction please see Lupe Quinones.				8/5/11 - This needs to be approved by new administration. M. Munoz			
Velia Alarcon									
77757					9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 9:42:04 AM					
Herrera, Joel		Requested by Charlie Jacquez for Boy's Restroom in Computer Lab-Restroom needs to be painted. Spray paint will not cover the graffiti.							
Velia Alarcon									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
76311	North Building	Classroom			8/2/2011		41		\$0.00
Medium	Work In Progress				8/2/2011 11:01:44 AM				
Lara, Ralph	Need new door for room 214 Do too vandalism north building								
<u>Mario Apodaca</u>									
76357	Cafeteria (1998)	Cafeteria			8/3/2011		40		\$0.00
Medium	Work In Progress				8/3/2011 11:49:23 AM				
Orozco, Danny	Two. Of the security gates are not opening with the electric motor opening manually at cafeteria serving lines								
<u>Mario Apodaca</u>									
78025					9/7/2011		5		\$0.00
Medium	Work In Progress				9/7/2011 2:42:56 PM				
Moncayo, Fernando	Remove three large portable cafeteria food serving Kiosks from the GHS cafeteria.								
<u>Maritza Gonzalez</u>									
75292	Varsity Gym	Custodial			7/11/2011		63		\$0.00
Medium	Work In Progress				7/11/2011 2:18:37 PM				
Gonzalez, Salvador	Need to weld a top rail to storage cage in the v-gym								
<u>Mario Apodaca</u>									
75465					7/14/2011		60		\$0.00
Medium	Work In Progress	Weight Room			7/14/2011 1:13:44 PM				
Gonzalez, Salvador	Need to re-install punching bag in weight room.								
<u>Michael Munoz</u>									
76665	Main Building				8/8/2011		35		\$0.00
Medium	Work In Progress				8/8/2011 4:22:51 PM				
Lara, Ralph	Requested by Ms. Arredondo Rm. 106 Main Building- Drill door knobs.								
<u>Velia Alarcon</u>									
77624					8/31/2011		12		\$0.00
Medium	Work In Progress				8/31/2011 8:13:12 AM				
Lara, Ralph	Requested by Ms. Hartmann for Girl's Restroom In Main Building-Repair girl's restroom door next to room 107 so that it will not bang upon closing.								
<u>Velia Alarcon</u>									
78031	Boys Gym				9/7/2011		5		\$0.00
High	Work In Progress				9/7/2011 3:03:27 PM				
Herrera, Joel	please check all dressing rooms,. bathrooms and shower to see if any painting needs done, all stalls are functional etc. this is a priority.thank you								
<u>Michael Munoz</u>									

9/12/2011 4:16:30 PM

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
78068					9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 11:11:26 AM					
Herrera, Joel	Requested by Matt Grubaugh for Old Library-The computer tables in the old Library are bolted together. Would it be possible to separate them?								
Velia Alarcon									
78070					9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 11:18:31 AM					
Herrera, Joel	Requested by Velia-Several light bulbs in the north side of the upstairs hallway are burned out. Very dark in hallway on a cloudy day.								
Velia Alarcon									
76510					8/5/2011		38		\$0.00
Medium	Work In Progress			8/5/2011 12:39:31 PM					
Herrera, Joel	Requested by Mr. S. Hernandez Rm. 306 Academic Building-Window screen is needed for classroom window. He thinks someone was trying to steal his screen for someone else's window.								
Velia Alarcon									
75626					7/21/2011		53		\$0.00
Medium	Work In Progress			7/21/2011 10:24:57 AM					
Sanchez, Raul	Domestic Water Storage Tank- install a 24" mesh wire screen or flapper valve on the overflow pipe. Do the same to the tank at GMS								
Alfredo Holguin									
77747	Grounds Shop	Lift Station			9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 4:32:53 PM					
Apodaca, Mario	Need to replace a blow pump at g h s water treatment plant								
Mario Apodaca									
77713					9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 1:59:04 PM					
Perez, Raul	Flat tire truck number 88 Need to be replaced								
Mario Apodaca									
76982	Varsity Gym	Gym			8/16/2011		27		\$0.00
Medium	Work In Progress			8/16/2011 8:57:46 AM					
Ronquillo, Ruben	Central court varsity gym Volleyball post sleeve is coming loose								
Mario Apodaca									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
77463					8/26/2011		17		\$0.00
Medium	Work In Progress			8/26/2011 8:27:00 AM					
Apodaca, Mario	Requested by Coach Rosen for Varsity Gym-Hang State Championship banner.								
Velia Alarcon									
77629					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 9:21:15 AM					
Herrera, Joel	Requested by Ms. G. Nevarez Rm. 125 Main Building- Remove word wall board on south wall (by TV) and re-hang on north wall over couch. Teacher will be receiving a "Smart Board" and in order to have smart board installed the chalk board needs to be removed as soon as possible.								
Velia Alarcon									
77630					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 9:22:51 AM					
Herrera, Joel	Requested by Mrs. Hirsch Rm. 147 Old English Building -Chalkboard (under flags) removed to have "smart board" hung. Teacher will be receiving a "Smart Board" and in order to have smart board installed the chalk board needs to be removed as soon as possible.								
Velia Alarcon									
77654					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 2:42:14 PM					
Herrera, Joel	Requested by Mrs. Gage for Football Concession Stand -Shelving in concession stand (next to door) needs to be re-enforced to wall. Students could get hurt, needs to be repaired before 09/02/11 (first home Football Game)								
Velia Alarcon									
77779					9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 2:12:17 PM					
Lara, Ralph	Requested by Velia-Four HEM 2 (Master Key) keys are needed. Please see Velia for exact key that needs to be copied.								
Velia Alarcon									
78067					9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 11:07:15 AM					
Lara, Ralph	Requested by Velia-The Parent Conference room storage room and room # 720 need to be re-keyed to X38 as soon as possible.								
Velia Alarcon									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
78127		Office			9/9/2011		3		\$0.00
Medium	Work In Progress				9/9/2011 2:57:36 PM				
Lara, Ralph	Need a office at new bldg unlock do to office being off master								
Mario Apodaca									
75452	Main Building	Hallway/Corridor			7/14/2011		60		\$0.00
Medium	Work In Progress				7/14/2011 7:35:13 AM				
Herrera, Joel	Roof leaks main building flat part of roof in hallway and office areas								
Mario Apodaca									
75453	Old English Bldg				7/14/2011		60		\$0.00
Medium	Work In Progress				7/14/2011 7:39:52 AM				
Herrera, Joel	Roof leaks Old english Building hallway. Classroom gym								
Mario Apodaca									
75461	Boys Gym	Dressing Room			7/14/2011		60		\$0.00
Medium	Work In Progress				7/14/2011 11:18:26 AM				
Herrera, Joel	All Boys gym roof is leaking needs a new roof								
Mario Apodaca									
77644					8/31/2011		12		\$0.00
Medium	Work In Progress				8/31/2011 10:16:19 AM				
Lara, Ralph	Requested by Mr. Martin Rm. 506 Annex Building- There's a dead bolt lock in the classroom door labled Therapy 104. There is no key for classroom. This is a very serious safety issue a student might lock themselves in that room and we would have no way to get the door unlocked. Please change cylinder to match the classroom door. Also, the double doors newly installed in the room have no core in the lock and the door leading onto the new patio area does not match any key that I have. Please have keys made to assigned to teacher as soon as possible.								
Velia Alarcon									
77773					9/2/2011		10		\$0.00
Medium	Work In Progress				9/2/2011 1:56:32 PM				
Lara, Ralph	Requested by Velia-Two additional keys of M98-G are needed for Girl's Lockerroom. Three additional keys of M99-B are needed for Boy's Lockerroom.								
Velia Alarcon									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
77774					9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 2:01:00 PM					
Lara, Ralph	Requested by Velia-Two HE211 keys are needed for Rm. 704 (Principal's Office is off master). Extra key is needed for school Secretary.								
Velia Alarcon									
77775					9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 2:04:34 PM					
Lara, Ralph	Requested by Velia-Additional light keys are needed for Girl's Lockerroom. Light switch was not working properly and was changed, but Coaches who use Lockerroom need to turn on lights.								
Velia Alarcon									
77776					9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 2:06:37 PM					
Lara, Ralph	Requested by Velia-Two HE123 keys are needed for Rm. # 311. Computer Lab that different teachers need access to.								
Velia Alarcon									
77777					9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 2:10:01 PM					
Lara, Ralph	Requested by Velia-Four HEM 1 (Master Key) keys are needed. Please see Velia for exact key that needs to be copied.								
Velia Alarcon									
76511					8/5/2011		38		\$0.00
Medium	Work In Progress			8/5/2011 12:41:13 PM					
Lara, Ralph	Requested by Ms. Hamilton Rm. 562 Ag. Shop-The lock is broken to classroom, can't open door with her key.								
Velia Alarcon									
76664					8/8/2011		35		\$0.00
Medium	Work In Progress			8/8/2011 4:18:27 PM					
Lozoya, Manny	Requested by Velia-Three keys to room # 200 are needed, 1HE25, for I.A.'s assigned to the teacher in that classroom.								
Velia Alarcon									
76763					8/10/2011		33		\$0.00
Medium	Work In Progress			8/10/2011 9:13:59 AM					
Lara, Ralph	Requested by Velia-Two HE246 keys are needed for room # 231, for I.A. and key box.								
Velia Alarcon									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
77464					8/26/2011		17		\$0.00
Medium	Work In Progress			8/26/2011 8:28:53 AM					
Lara, Ralph	Requested by Ms. Leahy Rm. 339 Academic Building- The lock on my built-in cabinet needs to be replaced.								
<u>Velia Alarcon</u>									
77470					8/26/2011		17		\$0.00
Medium	Work In Progress			8/26/2011 9:17:09 AM					
Lara, Ralph	Reuquested by Mr. Mora Rm. 403 Boy's Gym-Rear door to Athletic Training Room coming from Girl's locker room to Athletic room does not lock.								
<u>Velia Alarcon</u>									
77528					8/29/2011		14		\$0.00
Medium	Work In Progress			8/29/2011 3:01:48 PM					
Lara, Ralph	Requested by Ms. De La Garza for Rm. 713 New Admin. Building-Key will not open office door.								
<u>Velia Alarcon</u>									
76481					8/5/2011		38		\$0.00
Medium	Work In Progress			8/5/2011 8:41:58 AM					
Ambriz, Jose	Electrical Room in cafeteria too hot, need some kind of A/C Unit. Please contact Silver with questions								
<u>Cora Ramirez</u>									
76489	Boys Gym	Office			8/5/2011		38		\$0.00
Medium	Work In Progress			8/5/2011 9:19:08 AM					
Ambriz, Jose	Boys gymnasium split system short it out I need to replace condenser office 400								
<u>Mario Apodaca</u>									
76629					8/8/2011		35		\$0.00
Medium	Work In Progress			8/8/2011 2:12:09 PM					
Ambriz, Jose	JOSE AMBRIZ ICE MAKER MASHINE AT NURSE IT DOESNT WORK								
<u>Joel Herrera</u>									
77625					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 8:19:37 AM					
Ambriz, Jose	Requested by Ms. V. Gonzales for Computer Lab-A/C continues to not function properly, room continues to get up to 75 degrees. Computers and students need to be comfortable in order to function properly. This a/c was fixed last week according to Mario, but we continue to not be comfortable.								
<u>Velia Alarcon</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

75587	Academic Bldg	Office			7/20/2011		54		\$0.00
Medium	Work In Progress				7/20/2011 3:03:42 PM				

Lozoya, Manny
Need to put a new lock set at the academic blde lunch room 317

Mario Apodaca

76312	North Building	Classroom			8/2/2011		41		\$0.00
Medium	Work In Progress				8/2/2011 11:05:42 AM				

Lara, Ralph
Need to change out key cylinder to room 232 in the north building

Mario Apodaca

77523		Football Field			8/29/2011		14		\$0.00
Medium	Work In Progress				8/29/2011 2:25:14 PM				

Castillo, Carlos
I need an electrician to hook up new air compressor for irrigation well #1; would like to see if compressor worked on automatic mode. If it does not, I would need a switch so it could be turned on manually. Thanks, Raul

Raul Sanchez

77551	Varsity Gym	Hallway/Corridor			8/29/2011		14		\$0.00
Medium	Work In Progress				8/29/2011 5:45:04 PM				

Castillo, Carlos
All light switches in the hallway and lobby needs to be replaced

Mario Apodaca

77765					9/2/2011		10		\$0.00
Medium	Work In Progress				9/2/2011 10:52:10 AM				

Castillo, Carlos
Requested by Velia for New Administrative Building- There is one light bulb not working in the Reception Area of the New Adm. Building. There's also a whole light fixture that does not work. Located in the hallway connecting Office # 706 - # 710.

Velia Alarcon

78015	Cafeteria (1998)	Electrical Room			9/7/2011		5		\$0.00
Medium	Work In Progress				9/7/2011 12:07:00 PM				

Castillo, Carlos
need to services the fluorescent light at cafe electrical room

Mario Apodaca

78030	Boys Gym				9/7/2011		5		\$0.00
High	Work In Progress				9/7/2011 3:01:45 PM				

Castillo, Carlos
please check all light fixtures, switchces etc for proper operation and repair if need be. this is a priority. thankyou

Michael Munoz

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
75530	Boys Gym	Gym			7/19/2011		55		\$0.00
Medium	Work In Progress				7/19/2011 8:43:51 AM				
Herrera, Joel	NEED TO PAINT REPAIRS TO CELING IN BOYS GYM								
<u>Danny Miranda</u>									
76662					8/8/2011		35		\$0.00
Medium	Work In Progress				8/8/2011 4:15:28 PM				
Castillo, Carlos	Requested by Mr. M. Grubaugh for New Library-He has an alarm he needs attached to the emergency exit in the New Library.								
<u>Velia Alarcon</u>									
76710	Varsity Gym	Dressing Room			8/9/2011		34		\$0.00
Medium	Work In Progress				8/9/2011 2:41:46 PM				
Castillo, Carlos	Need to put new light switches in the girls and boys locker room in the varsity gymnasium due to the fact they having a hard time turning lights off and on. A.s.a.p								
<u>Mario Apodaca</u>									
76760					8/10/2011		33		\$0.00
Medium	Work In Progress				8/10/2011 9:02:26 AM				
Castillo, Carlos	Requeted by Ms. Hartmann Rm. 107 Main Building- Please change out two pronged outlets for three pronged on south and west walls.								
<u>Velia Alarcon</u>									
77060	Auto Shop	Auditorium			8/17/2011		26		\$0.00
Medium	Work In Progress				8/17/2011 1:34:45 PM				
Castillo, Carlos	Due to the removal of the telephone poles On the south side of campus Need to put lights on the outside of the building Annex and auto shop								
<u>Mario Apodaca</u>									
77149	Pool Pump	Pump House			8/19/2011		24		\$0.00
Medium	Work In Progress				8/19/2011 10:35:15 AM				
Castillo, Carlos	Need 30 amp fuses 4 domestic well at north building also check the amp ratings on well motor pump								
<u>Mario Apodaca</u>									
77466					8/26/2011		17		\$0.00
Medium	Work In Progress				8/26/2011 8:35:27 AM				
Castillo, Carlos	Requested by Mr. Enriquez Rm. 580 Auto Shop- Three of the six classroom light are out.								
<u>Velia Alarcon</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
78061	Community	Dressing Room			9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 9:52:49 AM					
Appelzoller, Fred		Need shower kerns and shower heads 4 the weight room							
Mario Apodaca									
78062	Community	Mechanical			9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 10:01:29 AM					
Appelzoller, Fred		Neen too turn on water heater at the weight room and checked all showers							
Mario Apodaca									
75527		Football Field			7/19/2011		55		\$0.00
Medium	Work In Progress			7/19/2011 8:11:39 AM					
Castillo, Carlos		Check and service football field lighting systems.							
Carlos Castillo									
76194	Main Building	Classroom			8/1/2011		42		\$0.00
Medium	Work In Progress			8/1/2011 2:40:09 PM					
Castillo, Carlos		Need to put a new outlet. Room 121 on the e/wall							
Mario Apodaca									
76193	Main Building	Classroom			8/1/2011		42		\$0.00
Medium	Work In Progress			8/1/2011 2:39:49 PM					
Castillo, Carlos		Need to put a new outlet. Room 121 on the e/wall							
Mario Apodaca									
76527					8/5/2011		38		\$0.00
Medium	Work In Progress			8/5/2011 1:55:13 PM					
Castillo, Carlos		Requested by Mrs. Crater Rm. 121 Main Building-There is a total of seven sets of extendas (totaling 28 computers) needed for College Success Program. Seven power cables interlinked and powered only by two outlets. What I do know is that there is a continuous and frequent loss of power entirely to all computers, including the teachers computer that occurs at random and inopportune times in this room. Today, day one of intruction the power went out on both the right and left sides of the classroom. None of the computers were operating, when the circuit breakers were reset, it did not remedy the problem. Electricity wiring needs to be checked as soon as possible for proper classroom intructions to continue.							
Velia Alarcon									
Count: 103 Work Orders		Avg. Age of WO's 23			Total for Gadsden HS			0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
77025					8/16/2011		27		\$0.00
Medium	Work In Progress			8/16/2011 3:44:59 PM					
Appelzoller, Fred	Need to check sink in room 129 thank you								
<u>Sebastian Diaz</u>									
77568		Classroom			8/30/2011		13		\$0.00
Medium	Work In Progress	A		8/30/2011 9:54:25 AM					
Sotelo, Enrique	FIX ELECTRICAL OUTLETS IN CHANGING AREA. NEED ELECTRICAL DROP IN KITCHEN FOR REFRIDGERATION AND MICROWAVE (SEE CURRENT CLASSROOM SETUP).								
<u>Maricruz Carrasco</u>									
78157					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 4:14:26 PM					
Sotelo, Enrique	Install 6 ceiling fans.								
<u>Michael Munoz</u>									
75722		Office			7/22/2011		52		\$0.00
Medium	Work In Progress	Administrator		7/22/2011 3:26:19 PM					
Lozoya, Manny	Need locks on four filing cabinets in Administrator's office. Please see Mr. Calleros for more information.								
<u>Maricruz Carrasco</u>									
75914		Office			7/27/2011		47		\$0.00
Medium	Work In Progress	Bwing/124/Diag		7/27/2011 3:47:50 PM					
Lozoya, Manny	Replace lock in cabint in room 124								
<u>Maricruz Carrasco</u>									
75955					7/28/2011		46		\$0.00
Medium	Work In Progress	Bwing/115/l.		7/28/2011 11:08:38 AM					
Lozoya, Manny	Please fix door as soon as possible. Door has been broken for a long time. Thank you!								
<u>Maricruz Carrasco</u>									
78087					9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 3:28:55 PM					
Solis, Lorenzo	Need check A/C in room 152 thank you								
<u>Sebastian Diaz</u>									
78088					9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 3:30:06 PM					
Solis, Lorenzo	N eed to check water fontain in main hall thank you								
Sebastian Diaz									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
78033		Office			9/7/2011		5		\$0.00
Medium	Work In Progress	C-213/Parent			9/7/2011 3:24:10 PM				
Diaz, Sebastian		Change filter in A/C in Parent Resource Center.							
<u>Maricruz Carrasco</u>									
77809					9/4/2011	9/20/2011	8		\$0.00
Medium	Work In Progress				9/4/2011 12:24:00 AM				
Villalobos, Margret		Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
75448					7/14/2011		60		\$0.00
Medium	Work In Progress				7/14/2011 12:16:26 AM				
Sanchez, Raul		Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
77913					9/4/2011		8		\$0.00
Medium	Work In Progress				9/4/2011 12:24:46 AM				
Sanchez, Raul		Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
78186					9/12/2011		0		\$0.00
Medium	Work In Progress				9/12/2011 10:35:15 AM				
Martinez, Larry		On September 13, 2011, please pick-up two boxes of math/SS material from Gadsden Middle School. Contact: Luis Calleros.							
<u>Yolie Jacquez</u>									
77681	C-Wing				8/31/2011		12		\$0.00
Medium	Work In Progress	CHARTER			8/31/2011 4:22:51 PM				
Villalobos, Margret		Charter School - We are currently having a large influx of crickets, spiders and mice. Could we please have the exterminator come by at 3:30 to treat the building?				Waiting on Price Quote			
<u>Melenie Beegle</u>									
76367		Cafeteria			8/3/2011		40		\$0.00
Medium	Work In Progress				8/3/2011 1:35:38 PM				
Sotelo, Enrique		please install ceiling fans in kitchen area. see mike.thanks							
<u>Michael Munoz</u>									
77639	Annex	Classroom			8/31/2011		12		\$0.00
Medium	Work In Progress	Annex/412/Abler			8/31/2011 9:53:08 AM				
Diaz, Sebastian		Drawers of desk keep falling out. Please fix.							
<u>Maricruz Carrasco</u>									

9/12/2011 4:16:30 PM

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
77638	Annex	Classroom			8/31/2011		12		\$0.00
Medium	Work In Progress	Annex/414/Cha			8/31/2011 9:51:28 AM				
Diaz, Sebastian		Teacher's desk drawer falls off when opening. Left side of desk (2 large drawers)							
Maricruz Carrasco									
77602	Vocational				8/30/2011		13		\$0.00
High	Work In Progress				8/30/2011 3:42:57 PM				
Diaz, Sebastian		as per our meeting in classroom, please remove wood beneath all sinks and cabinets, remove covebase and 1 foot of drywall. once remove please clean and apply 10% dilution of bleach for possible mold. once completed replce wood that was removed. thank you							
Michael Munoz									
77626					8/31/2011		12		\$0.00
Medium	Work In Progress	VARIOUS/MR.			8/31/2011 8:29:48 AM				
Diaz, Sebastian		SET-UP INTERACTIVE WHITEBOARDS IN THE FOLLOWING CLASSROOMS: 412,414,411,178,132,169,412,180,188. ANY QUESTIONS, SEE MR. MORA.							
Maricruz Carrasco									
78064					9/8/2011		4		\$0.00
Medium	Work In Progress	A			9/8/2011 10:08:31 AM				
Diaz, Sebastian		REMOVE STAFF/CLASS SCHEDULER DRY ERASE BOARD. RETURN TO MRS. QUINONEZ (NOT SURE WHERE SHE WANTS IT).							
Maricruz Carrasco									
77691					9/1/2011		11		\$0.00
Medium	Work In Progress				9/1/2011 8:37:00 AM				
Sanchez, Raul		9/01/11 I need a work order for the purchasing of plotter paper for the wwtp flowmeter at GMS & GHS;thanks Raul							
Raul Sanchez									
77103		Classroom			8/18/2011		25		\$0.00
Medium	Work In Progress	108/A. Franco			8/18/2011 12:44:26 PM				
Lozoya, Manny		Need lock on cabinet in room 108 as soon as possible.							
Maricruz Carrasco									
77169	Band Room	Classroom			8/19/2011		24		\$0.00
Medium	Work In Progress	Bandroom/Chac			8/19/2011 3:13:48 PM				
Lozoya, Manny		Problems unlocking outside doors. Please lubricate or replace key.							
Maricruz Carrasco									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
77643	Cafeteria	Classroom			8/31/2011		12		\$0.00
Medium	Work In Progress	Cafeteria		8/31/2011 10:05:06 AM					
Lozoya, Manny		Door gets stuck in door jam and is hard to open and close. Please fix.							
<u>Maricruz Carrasco</u>									
77658		Classroom			8/31/2011		12		\$0.00
Medium	Work In Progress	GYM		8/31/2011 3:24:17 PM					
Lozoya, Manny		PLEASE FIX LOCK ON THE FILE CABINET AND STORAGE CABINET IN ROOM 600. NEED TO LOCK AVID MATERIALS A.S.A.P.							
<u>Maricruz Carrasco</u>									
77709		Athletic Field			9/1/2011		11		\$0.00
Medium	Work In Progress	GMS Football		9/1/2011 12:38:47 PM					
Ontiveros, Guadalupe		Need football field lined as soon as possible.							
<u>Maricruz Carrasco</u>									
77166	Vocational	Classroom			8/19/2011		24		\$0.00
Medium	Work In Progress	Vocational/307/J		8/19/2011 3:05:07 PM					
Diaz, Sebastian		Install a white board in Ms. Jacobi's room if available.							
<u>Maricruz Carrasco</u>									
Count: 27 Work Orders		Avg. Age of WO's 19			Total for Gadsden MS			0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		La Union - JTP Alvarez Farms							
77995					9/6/2011		6		\$0.00
Medium	Work In Progress				9/6/2011 4:27:36 PM				
Lara, Ralph	NEED ONE (1) KEY L200 FOR LUJTP (S DOMINGUEZ) DELIVER KEY TO MARGARET S. VILLALOBOS, SPED OFFICE								
Margaret Villalobos									
Count: 1 Work Orders		Avg. Age of WO's	6		Total for La Union - JTP Alvarez Farms		0		\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
76712					8/9/2011		34		\$0.00
Medium	Work In Progress			8/9/2011 2:54:02 PM					
Villalobos, David	need faucet for hand sink in women rest room new wing - also need the two cut off valves under sink								
Patricio Aguilar									
76880					8/12/2011		31		\$0.00
Medium	Work In Progress			8/12/2011 11:23:08 AM					
Castillo, Carlos	need 2 more electrical out lets for room 101 - 102 if possible need a electrical out let replaced room 101 thank you								
Patricio Aguilar									
77636					8/31/2011		12		\$0.00
Medium	Work In Progress	ROOM 207		8/31/2011 9:41:33 AM					
Castillo, Carlos	INSTALL 2 ADDITIONAL ELECTRICAL PLUGS ON THE NORTH SIDE WALL OF ROOM (LUCY FLORES WILL LABEL WHERE, APPROX.) THERE ARE CURRENTLY NO PLUGS THERE AND WE HAVE TWO DIAGNOSTICIANS IN THAT AREA.								
Margaret Villalobos									
77635					8/31/2011		12		\$0.00
Medium	Work In Progress	ROOM 207		8/31/2011 9:39:28 AM					
Castillo, Carlos	FIX ELECTRICAL PLUG THAT IS NOT WORKING								
Margaret Villalobos									
75902					7/27/2011		47		\$0.00
Medium	Work In Progress			7/27/2011 2:25:26 PM					
Aguilar, Patricio	assign to me - need to replace batters to emer lights								
Patricio Aguilar									
76799					8/10/2011		33		\$0.00
Medium	Work In Progress			8/10/2011 4:01:51 PM					
Orozco, Danny	HOBART MIXER IS NOT WORKING PROPERLY, CANT USE ATTACHMENTS. SNP MANAGER LINDA Y. 589.2040								
Maritza Gonzalez									
77901					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:41 AM					
Aguilar, Patricio	Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
78173					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:48 AM					
Aguilar, Patricio	Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77900					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:40 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78003					9/7/2011		5		\$0.00
Medium	Work In Progress			9/7/2011 8:42:07 AM					
Moncayo, Fernando	Dishwasher will not turn on. SNP Manager Linda Y. 882.2040								
<u>Maritza Gonzalez</u>									
76879					8/12/2011		31		\$0.00
Medium	Work In Progress			8/12/2011 11:11:33 AM					
Carrasco, Danny	need 5gal of gas for 419 mower								
<u>Patricio Aguilar</u>									
76601					8/7/2011	9/7/2011	36		\$0.00
Medium	Work In Progress			8/7/2011 12:16:42 AM					
Aguilar, Patricio	Yearly - La Union ES A-9 Air Cooled Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77615					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 12:21:06 AM					
Aguilar, Patricio	Monthly - La Union ES A-16 Fan Exhaust Semimonthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77898					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:40 AM					
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77899					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:40 AM					
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 15 Work Orders			Avg. Age of WO's	19	Total for La Union ES			0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
77512	Main Building	Athletic Field			8/29/2011		14		\$0.00
Medium	Work In Progress			8/29/2011 10:47:46 AM					
Appelzoller, Fred	WATER FOUNTAIN BEHIND LIBRARY NEEDS TO BE REPLACED.								
Rudy Arreola									
77513	Main Building	Restroom (Boys)			8/29/2011		14		\$0.00
Medium	Work In Progress			8/29/2011 10:50:25 AM					
Appelzoller, Fred	URINAL IN 6TH GRADE WING WAS REPLACED. BUT THIS URINAL HAS BEEN CLOGGED AT LEAST 6 TIMES ALLREADY MAYBE WILL NEED A NEW ONE								
Rudy Arreola									
77530	Main Building	Athletic Field			8/29/2011		14		\$0.00
Medium	Work In Progress			8/29/2011 3:03:44 PM					
Appelzoller, Fred	WE NEED A HOSE BIB FOR NEW PROJECT THAT WILL BE DONE BEHIND LIBRARY FOR A DRIP SYSTEM.								
Rudy Arreola									
77589	Main Building	Classroom			8/30/2011		13		\$0.00
Medium	Work In Progress			8/30/2011 2:55:27 PM					
Sotelo, Enrique	EMERGENCY LIGHT IS NOT WORKING IN ROOM 217. NEEDS BOTHS BALLASTS.								
Rudy Arreola									
77231		Athletic Field			8/22/2011		21		\$0.00
Medium	Work In Progress			8/22/2011 2:49:57 PM					
Ontiveros, Guadalupe	NEED TRACTOR TO LEVEL OFF AREAS WHERE WATER HAS WASHED OUT DIRT AROUND PORTABLE AND BUS TURNAROUND BEHIND LIBRARY AND ALONG PINE TREES.								
Rudy Arreola									
77588	Main Building				8/30/2011		13		\$0.00
Medium	Work In Progress			8/30/2011 2:54:13 PM					
Ontiveros, Guadalupe	WE HAVE ANOTHER VALVE THAT IS STUCK. TURNED OFF WATER TO GRASS AREA.								
Rudy Arreola									
78113	Main Building	Custodial			9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 10:41:56 AM					
Carbajal, Jimmy	WE NEED SERVICE FOR LUIS (VACUUM CLEANER).EVERY TIME I TURN ON ,IT MAKES A STRONG NOISE.(C07C00000024) THANKS..								
Luis Solis									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
77911					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:45 AM					
Arreola, Rudy	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78174					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:49 AM					
Arreola, Rudy	Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76138					7/31/2011	8/6/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:21 AM					
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77909					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:45 AM					
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
74952					7/4/2011	7/24/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:21:48 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75282	Main Building				7/11/2011		63		\$0.00
Medium	Work In Progress			7/11/2011 8:57:04 AM					
Estrada, Jesus	Tile needs to be replaced in laundry room and storage. Anti slip flooring.								
<u>Rudy Arreola</u>									
77962	Main Building	Classroom			9/6/2011		6		\$0.00
Medium	Work In Progress	209 & 104		9/6/2011 9:54:33 AM					
Ronquillo, Ruben	Windows in both classrooms were broken and need repair								
<u>Gidget Mora</u>									
76137					7/31/2011		43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:21 AM					
Arreola, Rudy	Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
76139					7/31/2011	8/8/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:22 AM					
Arreola, Rudy	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76140					7/31/2011	8/8/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:22 AM					
Arreola, Rudy	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77908					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:44 AM					
Arreola, Rudy	Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77910					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:45 AM					
Arreola, Rudy	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76486	Main Building	Classroom			8/5/2011		38		\$0.00
Medium	Work In Progress	105		8/5/2011 9:12:56 AM					
Arreola, Rudy	Need wall hooks for backpacks/jackets.								
<u>Gidget Mora</u>									
77972					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 12:57:12 PM					
Carrasco, Danny	please check in with site administrator and support with any work that needs to be done while rudy is out on leave. sal will support. thanks								
<u>Michael Munoz</u>									
78005	Main Building	Classroom			9/7/2011		5		\$0.00
Medium	Work In Progress	215		9/7/2011 9:32:00 AM					
Carrasco, Danny	Please repair screen on wall. One side is completely unscrewed from wall.								
<u>Gidget Mora</u>									
78008	Main Building	Classroom			9/7/2011		5		\$0.00
Medium	Work In Progress	206		9/7/2011 10:08:06 AM					
Carrasco, Danny	Please remove chalkboard in classroom so a whiteboard may be installed.								
<u>Gidget Mora</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
77475	Main Building	Athletic Field			8/26/2011		17		\$0.00
Medium	Work In Progress			8/26/2011 2:52:11 PM					
Gonzalez, Salvador	PLAYGROUND EQUIPMENT IN THE KINDER AREA BROKE OFF NEEDS TO BE WELDED.								
Rudy Arreola									
78012	Main Building	Athletic Field			9/7/2011		5		\$0.00
Medium	Work In Progress	Courtyard		9/7/2011 10:30:14 AM					
Gonzalez, Salvador	Requesting 21 metal grates to cover windows facing the rear courtyard of school. We have experienced numerous break-ins since April.								
Gidget Mora									
Count: 25 Work Orders		Avg. Age of WO's		20	Total for Loma Linda ES			0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
77455					8/26/2011		17		\$0.00
Medium	Work In Progress			8/26/2011 7:45:07 AM					
Sotelo, Enrique	Kitchen - floor outlent in middle of serving line under desk- coordinate wiht kitchen staff and relocated and install cap or install flush wiht floor								
Alfredo Holguin									
76814					8/11/2011		32		\$0.00
Medium	Work In Progress			8/11/2011 8:39:07 AM					
Ramirez, Joe	need to paint rm.404								
Joe Ramirez									
75284					7/11/2011		63		\$0.00
Medium	Work In Progress			7/11/2011 9:09:03 AM					
Solis, Lorenzo	need to rewire a/c rm. 405 it only has high cool.								
Joe Ramirez									
77254					8/23/2011		20		\$0.00
Medium	Work In Progress			8/23/2011 8:18:35 AM					
Solis, Lorenzo	water fountain in kinder wing needs to be repaired compressor is out.								
Joe Ramirez									
77648					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 12:31:07 PM					
Lozoya, Manny	as per mr. moreno asst. principal he is requesting 2 pad locks with the c-master.								
Joe Ramirez									
78022					9/7/2011		5		\$0.00
Medium	Work In Progress			9/7/2011 2:09:06 PM					
Lozoya, Manny	need door strike replace mechanical door rm. 100 wing								
Joe Ramirez									
77940					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 7:55:57 AM					
Ronquillo, Ruben	need to replace broken window 200 hallway 47 7/8x 47 7/8 x 3/8" reflective storm glass.								
Joe Ramirez									
77941					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 7:57:37 AM					
Ronquillo, Ruben	need to replace broken window rm. 604 32x22x 1/4" storm window								
Joe Ramirez									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
77653					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 2:39:29 PM					
Estrada, Jesus	NEED TO REPLACE CARPET IN PORTABLE 5 & 6.								
Jesus Estrada									
76929		Custodial			8/15/2011		28		\$0.00
Medium	Work In Progress			8/15/2011 12:52:37 PM					
Carbajal, Jimmy	PLEASE I NEED 2 VACUMM BELTS. THANK YOU								
Luis Saucedo									
77892					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:37 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
75104					7/5/2011		69		\$0.00
Medium	Work In Progress			7/5/2011 12:16:34 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
Margret Villalobos									
76232					8/2/2011		41		\$0.00
Medium	Work In Progress			8/2/2011 12:17:00 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
Margret Villalobos									
77937					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 12:20:02 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
Margret Villalobos									
77890					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:36 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
75032					7/4/2011	8/3/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:22 AM					
Ramirez, Joe	Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.								
Margret Villalobos									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
77100					8/18/2011		25		\$0.00
Medium	Work In Progress			8/18/2011 9:22:00 AM					
Gonzalez, Salvador	8/18/11 I need welder to fabricate an aluminum cover for the sewage pumps at Mesquite Elementary wwtp ASAP,thanks Raul								
<u>Raul Sanchez</u>									
76422					8/4/2011		39		\$0.00
Medium	Work In Progress			8/4/2011 8:58:36 AM					
Orozco, Danny	requesting boom-truck to run rope up the flag pole								
<u>Joe Ramirez</u>									
78196					8/29/2011		14		\$0.00
Medium	Work In Progress			9/12/2011 12:37:56 PM					
Ronquillo, Ruben	Break-in between 8/26-8/28 2 Fire Ext were discharged, stolen Nextel radio and computer speakers.								
<u>Joe Ramirez</u>									
77888					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:35 AM					
Ramirez, Joe	Monthly - Mesquite ES - Barrack Drainage (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77889					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:36 AM					
Ramirez, Joe	Monthly - Mesquite ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77891					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:37 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78072		Custodial			9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 1:24:37 PM					
Lozoya, Manny	please we need to secure custodial storage the door do not lock at all on north side storage hallway for safety of students.								
	thank you								
Luis Saucedo									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: Mesquite ES										
75536	Main Building				7/19/2011		55		\$0.00	
Medium	Work In Progress	Cafeteria		7/19/2011 10:47:41 AM						
Ramirez, Joe	Due to health issue ceiling tile in cafeteria has been cleaned many time and is old and still very dirty needs to be replaced. Thank you									
<u>Sandra Mora</u>										
78009		Cafeteria			9/7/2011		5		\$0.00	
Medium	Work In Progress			9/7/2011 10:10:12 AM						
Ramirez, Joe	CAFETERIA TABLE BROKEN NOT GOOD THANK YOU									
<u>Luis Saucedo</u>										
75817					7/26/2011		48		\$0.00	
Medium	Work In Progress			7/26/2011 9:29:56 AM						
Orozco, Danny	OVEN IS NOT WORKING. SNP MANAGER ALICE F. 233.2341									
<u>Maritza Gonzalez</u>										
77511					8/29/2011		14		\$0.00	
Medium	Work In Progress			8/29/2011 10:09:39 AM						
Orozco, Danny	DRYER IS SMELLING BURNT, TURNED OFF PLEASE CHECK OUT. SNP MANAGER ALICE. F. 233.2341									
<u>Maritza Gonzalez</u>										
77716					9/1/2011		11		\$0.00	
Medium	Work In Progress			9/1/2011 2:11:09 PM						
Moncayo, Fernando	NO HOT WATER IN HAND SINKS IN KITCHEN CITED BY HEALTH DEPT., THEY WILL NEED PROOF THAT ISSUE HAS BEEN RESOLVED. SNP MANAGER ALICE F. 233-2341									
<u>Maritza Gonzalez</u>										
Count: 28 Work Orders			Avg. Age of WO's	23				Total for Mesquite ES	0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
77725					9/1/2011		11		\$0.00
Medium	Work In Progress				9/1/2011 3:22:26 PM				
Solis, Lorenzo		pecan valley wing water fountains have no cold water/breaker is good seems compressor in not working/							
Danny Vega									
76189					8/1/2011		42		\$0.00
Medium	Work In Progress				8/1/2011 1:13:59 PM				
Lozoya, Manny		need to repair door handle plus core in heat pumps mechanical rm organ trail(exterior)and give a key to joe trane rep							
Danny Vega									
77194					8/22/2011		21		\$0.00
Medium	Work In Progress				8/22/2011 7:54:25 AM				
Lozoya, Manny		mechannical rm organ trail wing/door needs to be secured/door handle lock broken /parts on order/still need this door secured some how -to prevent vandalism to heat pumps gauges and board panels							
Danny Vega									
77687					9/1/2011		11		\$0.00
Medium	Work In Progress				9/1/2011 8:15:06 AM				
Lozoya, Manny		key core fell-off main hallway door by office/h-d custodian key is worn out his key pulled core -out - please secure door by wk end							
Danny Vega									
77553					8/30/2011		13		\$0.00
Medium	Work In Progress				8/30/2011 7:38:58 AM				
Vega, Danny		need sink faucets replaced & flush handle to commode tank rm 106 nve							
Danny Vega									
77772					9/2/2011		10		\$0.00
Medium	Work In Progress				9/2/2011 1:21:00 PM				
Vega, Danny		rm 211(music rm) cover doors to keep sound from disrupting class rm 209							
Danny Vega									
77252					8/23/2011		20		\$0.00
Medium	Work In Progress				8/23/2011 7:33:55 AM				
Carrasco, Danny		need diesel for #422 997 mower							
Danny Vega									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
74914					7/4/2011		70		\$0.00
Medium	Work In Progress			7/4/2011 12:21:30 AM					
Holguin, Alfredo		Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									
77833					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:11 AM					
Vega, Danny		Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
77836					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:13 AM					
Vega, Danny		Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
78163					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:43 AM					
Vega, Danny		Monthly - North Valley ES Playground Inspection - Refer to PM schedule details.							
Margret Villalobos									
77837					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:13 AM					
Vega, Danny		Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
Count: 12 Work Orders		Avg. Age of WO's 19			Total for North Valley ES			0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
77306	Main Building				8/23/2011		20		\$0.00
Medium	Work In Progress			8/23/2011 3:58:31 PM					
Ontiveros, Guadalupe	Remove hedges from outside front entry way. Trees are growing inside hedges.								
<u>Concepcion Montalvo</u>									
77750					9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 8:20:56 AM					
Munoz, Michael	WITH THE REMOVAL OF BUSHES IN FRONT OF THE SCHOOL WE NEED OUR FENCE EXTENDED.								
<u>Adam Montoya</u>									
76755					8/10/2011		33		\$0.00
Medium	Work In Progress			8/10/2011 8:50:05 AM					
Ontiveros, Guadalupe	Remove hedges form both sides of maint entry walkway								
<u>Alfredo Holguin</u>									
77834					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:12 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77835					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:12 AM					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78164					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:43 AM					
Vega, Danny	Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77936					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 12:20:01 AM					
Sanchez, Raul	Monthly - Northern Pre-K- Domestic Water Filters - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77838					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:14 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Northern On-Track Pre-K (LM)									
75818					7/26/2011		48		\$0.00
Medium	Work In Progress				7/26/2011 9:59:35 AM				
Estrada, Jesus	ROOM #108 - UNEVEN TILES ARE A TRIP HAZARD. PLEASE MAKE RECOMMENDATION.								
Jesus Estrada									
77429					8/25/2011		18		\$0.00
Medium	Work In Progress				8/25/2011 1:25:50 PM				
Carbajal, Jimmy	NEED CHAIR DOLLY.								
Adam Montoya									
Count: 10 Work Orders			Avg. Age of WO's	16	Total for Northern On-Track Pre-K (LM)		0		\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
77622	Motor Vehicle				8/31/2011		12		\$0.00
Medium	Work In Progress	vehicle#86		8/31/2011 7:48:08 AM					
Flores, Pete	van is in need of service								
Pete Flores									
77720	Motor Vehicle				9/1/2011		11		\$0.00
Medium	Work In Progress	vehicle #18		9/1/2011 2:54:18 PM					
Flores, Pete	vehicle requires service								
Pete Flores									
77721	Motor Vehicle				9/1/2011		11		\$0.00
Medium	Work In Progress	vehicle #151		9/1/2011 2:55:28 PM					
Flores, Pete	scheduled for maintenance								
Pete Flores									
77722	Motor Vehicle				9/1/2011		11		\$0.00
Medium	Work In Progress	vehicle#112		9/1/2011 2:56:40 PM					
Flores, Pete	routine maintenance required								
Pete Flores									
77784	Motor Vehicle				9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 2:58:29 PM					
Flores, Pete	REPAIR FLAT TIRE ON TRAILER #6								
Danny Carrasco									
78071	Motor Vehicle				9/8/2011		4		\$0.00
Medium	Work In Progress	vehicle#50		9/8/2011 12:56:40 PM					
Flores, Pete	vehicle needs maintenance								
Pete Flores									
77752	Maintenance	Office			9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 8:28:07 AM					
Appelzoller, Fred	utilie knife, cold chisel,channel lock pliers,measureing tape, hexdriver, battery charger 15min,18 volt battery dewalt								
Fred Appelzoller									
77786	Maintenance				9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 3:16:20 PM					
Carrasco, Danny	REQUESTING NEW ROUTER FOR DISTRICT USE (LOANER).								
Danny Carrasco									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
77261	Purchasing				8/23/2011		20		\$0.00
Medium	Work In Progress			8/23/2011 10:58:04 AM					
Munoz, Michael	Please extend the concrete slab outside both garage door in the purchasing warehouse.								
<u>Alfredo Holguin</u>									
78058		Athletic Field			9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 8:26:09 AM					
Gonzalez, Salvador	pull behind scraper needs blade welded. any questions ask lupe.								
<u>Guadalupe Ontiveros</u>									
77935					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:56 AM					
Diaz, Sebastian	Monthly - Physical Plant - Lint Trap (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76167					8/1/2011		42		\$0.00
Medium	Work In Progress			8/1/2011 12:23:44 AM					
Villalobos, Margret	Monthly - PPD - Quarterly Meeting - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78060	Purchasing				9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 9:29:04 AM					
Diaz, Sebastian	I am requesting a work order to have a set of industrial shelving dismantled in the warehouse. It is the west end of the orange shelves as well as the entire top shelf from end to end. Thank you! Tracey								
<u>Tracey Swinford</u>									
76176					8/1/2011		42		\$0.00
Medium	Work In Progress			8/1/2011 9:27:24 AM					
Ronquillo, Ruben	PURCHASE 2 KIT ANTENNAS 1FOR GMS, 1FOR STMS.								
<u>Ruben Ronquillo</u>									
78199	Food Services				9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 2:13:32 PM					
Diaz, Sebastian	Need to ck breaker at FS Warehouse								
<u>Johnny Lechuga</u>									
77652					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 2:12:56 PM					
Moncayo, Fernando	Freezer #4 @ SNP Warehouse needs to be checked. Fan might be hitting cover.								
<u>Maritza Gonzalez</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
77976	Food Services				9/6/2011		6		\$0.00
Medium	Work In Progress				9/6/2011 2:37:45 PM				
Moncayo, Fernando	temp in freezer #5 going up.								
<u>Maritza Gonzalez</u>									
78011	Food Services				9/7/2011		5		\$0.00
Medium	Work In Progress				9/7/2011 10:28:37 AM				
Moncayo, Fernando	FREEZER #3 MOTOR IS ICED UP								
<u>Maritza Gonzalez</u>									
77781					9/2/2011		10		\$0.00
Medium	Work In Progress				9/2/2011 2:28:00 PM				
Gonzalez, Salvador	RE-ADJUST LIFT CRANK ON TRAILER #8								
<u>Danny Carrasco</u>									
Count: 19 Work Orders		Avg. Age of WO's 12		Total for Physical Plant Complex				0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
75986					7/28/2011		46		\$0.00
Medium	Work In Progress			7/28/2011 3:53:24 PM					
Castillo, Carlos	need electrical outlet in gym stroage room								
Carlos Hernandez									
77728					9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 3:27:47 PM					
Castillo, Carlos	lights in rom 76 (old computer lab) one side not working								
Carlos Hernandez									
78198					9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 2:03:44 PM					
Castillo, Carlos	lounge circuits over loading								
Carlos Hernandez									
77782					9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 2:48:52 PM					
Ambriz, Jose	water fountian in cafe not cooling any more need to replace								
Carlos Hernandez									
77117					8/18/2011		25		\$0.00
Medium	Work In Progress			8/18/2011 3:43:03 PM					
Lara, Ralph	need pad locks for small get and water control box and one for trash cans								
Carlos Hernandez									
77981					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 3:27:33 PM					
Lara, Ralph	need new pad locks for side gates								
Carlos Hernandez									
78125					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 2:44:31 PM					
Munoz, Michael	need to construct concret pad for trash dumpsters								
Alfredo Holguin									
76817					8/11/2011		32		\$0.00
Medium	Work In Progress			8/11/2011 10:09:57 AM					
Ambriz, Jose	a/c unit in music portable not cooling right								
Carlos Hernandez									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
77021					8/16/2011		27		\$0.00
Medium	Work In Progress			8/16/2011 3:40:27 PM					
Ambriz, Jose	art portable is very hot has swamp cooler (is there any way to install ref. air)								
Carlos Hernandez									
77323					8/24/2011		19		\$0.00
Medium	Work In Progress			8/24/2011 9:09:57 AM					
Ambriz, Jose	compressor on a/c unit in teachers lounge not working								
Carlos Hernandez									
77677					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 3:57:52 PM					
Ambriz, Jose	need elbow "5 gooseneck and 16x16 register for a/c storage								
Carlos Hernandez									
78197					9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 2:02:49 PM					
Ambriz, Jose	a/c in library not cooling								
Carlos Hernandez									
77702					9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 11:10:02 AM					
Hernandez, Carlos	please purchase new D130 john deere lawn mower to replace existing one.								
Michael Munoz									
77611					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 12:21:04 AM					
Hernandez, Carlos	Monthly - Riverside ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
Margret Villalobos									
77824					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:08 AM					
Hernandez, Carlos	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
77825					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:08 AM					
Hernandez, Carlos	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Riverside ES								
78161					9/11/2011	9/27/2011	1		\$0.00	
Medium	Work In Progress			9/11/2011 12:20:42 AM						
Hernandez, Carlos	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
77823					9/4/2011	9/10/2011	8		\$0.00	
Medium	Work In Progress			9/4/2011 12:24:07 AM						
Hernandez, Carlos	Monthly - Riverside ES Monthly FE Inspection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
78089					9/8/2011		4		\$0.00	
Medium	Work In Progress			9/8/2011 3:30:23 PM						
Flores, Pete	small tractor has flat tire right front need repair									
<u>Carlos Hernandez</u>										
76685					8/9/2011		34		\$0.00	
Medium	Work In Progress			8/9/2011 8:37:59 AM						
Hernandez, Carlos	PICK-UP DESK, OLD CABINETS ETC. NO LONGER IN USE, BROKEN SHELF									
<u>Olga Arias</u>										
76431					8/4/2011		39		\$0.00	
Medium	Work In Progress			8/4/2011 10:24:58 AM						
Orozco, Danny	OVEN IS NOT WORKING PROPERLY. TEMP GOES DOWN. ONLY WORKING WITH 2 OVENS RIGHT NOW. SNP MANAGER EMILIA C. 589.2550									
<u>Maritza Gonzalez</u>										
76890					8/12/2011		31		\$0.00	
Medium	Work In Progress			8/12/2011 3:32:08 PM						
Munoz, Michael	need new fencing around new irrigation control next to art portable									
<u>Carlos Hernandez</u>										
77324					8/24/2011		19		\$0.00	
Medium	Work In Progress			8/24/2011 9:11:17 AM						
Carrasco, Danny	need 8 gal fuel 0423 mower and 6 truck									
<u>Carlos Hernandez</u>										
78177					9/12/2011		0		\$0.00	
Medium	Work In Progress			9/12/2011 8:30:05 AM						
Lara, Ralph	need replace door handle portable 506 due to vandalism									
<u>Carlos Hernandez</u>										
Count: 24 Work Orders			Avg. Age of WO's	15				Total for Riverside ES	0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		RTC - Alliance							
77571					8/30/2011		13		\$0.00
Medium	Work In Progress			8/30/2011 10:29:36 AM					
Ambriz, Juan	1) Please clean the weeds. 2) Student desks need to be assembled Thank you								
<u>Maritza Gonzalez</u>									
78021					9/7/2011		5		\$0.00
Medium	Work In Progress			9/7/2011 1:39:54 PM					
Ambriz, Juan	A/C IN ONE OF THE PORTABLE CLASSROOMS NOT COOLING.								
<u>Maritza Gonzalez</u>									
Count: 2 Work Orders			Avg. Age of WO's	9		Total for RTC - Alliance	0	0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
75820					7/26/2011		48		\$0.00
Medium	Work In Progress			7/26/2011 10:21:30 AM					
Villalobos, David	WATER FOUNTAIN IN CAFET. DOES NOT SHUT OFF. NEEDS TO BE CHECKED OUT. THANKS.								
<u>Gerardo Marquez</u>									
76825	Main Building	Restroom (Boys)			8/11/2011		32		\$0.00
Medium	Work In Progress	boys restrooms		8/11/2011 2:15:27 PM					
Villalobos, David	PLEASE CHECK THE BOYS URINALS IN ALL THE RESTROOMS. THEY SEEM TO BE CLOGGED. THANKS.								
<u>Rita Mendez</u>									
77360					8/24/2011		19		\$0.00
Medium	Work In Progress			8/24/2011 3:35:33 PM					
Villalobos, David	URINALS IN CASA BLANCA ARE NOT DRAINING. I TRIED TO USE A SNAKE & ALSO SHOP VAC BUT STILL WONT DRAIN. NEED TO TAKE OFF WALL & CHECK OUT.								
<u>Gerardo Marquez</u>									
76757					8/10/2011		33		\$0.00
Medium	Work In Progress			8/10/2011 8:58:12 AM					
Castillo, Carlos	HAND DRYER @ BOYS RRM. IN CASA BLANCA NEEDS REPLACING. NOT WORKING. THANKS.								
<u>Gerardo Marquez</u>									
77434		Classroom			8/25/2011		18		\$0.00
Medium	Work In Progress	Mowles/ 108		8/25/2011 3:08:28 PM					
Castillo, Carlos	Teacher needs two electrical plugs installed in her bathroom. Please check. Thank you.								
<u>Rosie Diaz</u>									
75906	Main Building	Classroom			7/27/2011		47		\$0.00
Medium	Work In Progress	PARENT ROOM		7/27/2011 3:27:57 PM					
Lara, Ralph	PLEASE PLACE LOCKS ON ALL THE CABINETS. THANKS.								
<u>Rita Mendez</u>									
76693					8/9/2011		34		\$0.00
Medium	Work In Progress			8/9/2011 10:40:20 AM					
Marquez, Gerardo	NEED TO REPLACE FILTERS IN AC. UNITS.								
<u>Gerardo Marquez</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
77359					8/24/2011		19		\$0.00
Medium	Work In Progress			8/24/2011 3:33:48 PM					
Marquez, Gerardo	NEED TO CHECK OUT HVAC IN RM. 307. NOT COOLING & MOTOR MAKING A LOUD NOISE. THANKS.								
<u>Gerardo Marquez</u>									
77854					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:20 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
74981					7/4/2011	8/3/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:01 AM					
Marquez, Gerardo	Yearly - Santa Teresa ES Emer. Light Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
74982					7/4/2011	8/3/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:01 AM					
Marquez, Gerardo	Yearly - Santa Teresa ES Exit Sign Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78190		Parking Lot			9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 10:56:56 AM					
Munoz, Michael	PARKING LOT HAS DEVELOPED SOME CRACKS & MAY BE TIME FOR SOME CRACKSEALING IN ORDER TO PREVENT FURTHER DAMAGE. THANKS.								
<u>Gerardo Marquez</u>									
77585	Main Building	Athletic Field			8/30/2011		13		\$0.00
Medium	Work In Progress	basketball courts		8/30/2011 2:40:58 PM					
Villalobos, Margret	WE HAVE A LOT OF ANTS BY THE BASKETBALL COURTS AND ALSO BY THE PE PORTABLE. THANKS.								
<u>Rita Mendez</u>									
75198					7/7/2011		67		\$0.00
Medium	Work In Progress			7/7/2011 8:31:31 AM					
Gallegos, Rafael	DOOR LOCK ON ACTIVITY BOYS RESTROOM IN AUX. GYM. NEEDS TO BE CHECKED, DOOR CAN'T BE OPENED DUE TO LOCK NOT WORKING PROPERLY. (MIGHT STILL BE UNDER WARRANTY.)								
<u>Arturo Nunez</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
77856					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:21 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77857					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:22 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77858					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:22 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76586					8/7/2011	8/23/2011	36		\$0.00
Medium	Work In Progress			8/7/2011 12:16:34 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78168					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:46 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76087					7/31/2011	8/6/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:00 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77743	Main Building	Classroom			9/1/2011		11		\$0.00
Medium	Work In Progress	NURSE'S		9/1/2011 4:13:22 PM					
Lara, Ralph	NURSE'S STORAGE DOOR NEEDS TO BE SET UP WHERE IT DOESN'T LOCK. THANKS								
<u>Rita Mendez</u>									
77519					8/29/2011		14		\$0.00
Medium	Work In Progress			8/29/2011 1:45:20 PM					
Carrasco, Danny	NEED FUEL FOR TRUCK 107, BLOWERS-621 & MOWER-424. THANKS.								
Gerardo Marquez									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
77855					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:21 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76088					7/31/2011	8/8/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:00 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76089					7/31/2011	8/8/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:01 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76090					7/31/2011		43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:01 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77514	Main Building	Classroom			8/29/2011		14		\$0.00
Medium	Work In Progress	Perez/ Parent		8/29/2011 10:50:29 AM					
Lara, Ralph	We need a new lock and a key for file cabinet, next to desk. (197-E) Thank you.								
<u>Rosie Diaz</u>									
78189					9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 10:49:21 AM					
Flores, Pete	NEED FOR TRUCK 107 TO BE SERVICED. (TUNE UP, OIL CHANGE & CHECK OUT OIL LEAK.) THANKS.								
<u>Gerardo Marquez</u>									
77549		Classroom			8/29/2011		14		\$0.00
Medium	Work In Progress	ROOM 212		8/29/2011 4:07:45 PM					
Marquez, Gerardo	PLEASE MOVE THE PROJECTION SCREEN TO THE OPPOSITE WALL IN ROOM 212, MS. CONE. THANKS.								
<u>Rita Mendez</u>									
77579		Classroom			8/30/2011		13		\$0.00
Medium	Work In Progress	MS. TAGLE 208		8/30/2011 11:22:21 AM					
Marquez, Gerardo	PLEASE MOVE THE PROJECTION SCREEN FROM ONE WALL TO ANOTHER								
<u>Rita Mendez</u>									

9/12/2011 4:16:31 PM

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Santa Teresa ES							
77717	Main Building	Hallway/Corridor			9/1/2011		11		\$0.00
Medium	Work In Progress	casa blanca and			9/1/2011 2:38:14 PM				
Marquez, Gerardo		PLEASE CHECK THE WATER FOUNTAINS AT THE END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDS UP ON THE FLOOR. WE ALREADY HAD A STUDENT FALL DUE TO WATER ON THE FLOOR. WE ALSO NEED MATS IN BOTH OF THESE AREAS. THANK YOU							
Requester Name									
Rita Mendez									
77002					8/16/2011		27		\$0.00
Medium	Work In Progress				8/16/2011 1:49:05 PM				
Orozco, Danny		SOMETHING BROKE INSIDE DISHWASHER WHILE IN USE, DOES NOT WANT TO WORK. SNP MANAGER PAT S. 589.3439							
Requester Name									
Count: 32 Work Orders		Avg. Age of WO's 26			Total for Santa Teresa ES			0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
76449	Main Building	Restroom (Girls)			8/4/2011		39		\$0.00
Medium	Work In Progress				8/4/2011 3:25:55 PM				
Villalobos, David	Bathrooms boys and girls continue flushing even when no one present and lights are off								
<u>Rosalinda Rodriguez</u>									
76451	Gymnasium	Gym			8/4/2011		39		\$0.00
Medium	Work In Progress				8/4/2011 3:30:28 PM				
Villalobos, David	Athletic locker room, volleyball/basketball area, showers are not working and students need to shower								
<u>Rosalinda Rodriguez</u>									
77398					8/25/2011		18		\$0.00
Medium	Work In Progress				8/25/2011 9:57:13 AM				
Villalobos, David	FAUCETS IN CONCESSION STAND ARE NOT WORKING PROPERLY								
<u>Jorge Perez</u>									
75528		Football Field			7/19/2011		55		\$0.00
Medium	Work In Progress				7/19/2011 8:14:57 AM				
Castillo, Carlos	Check and service footballfield lighting system.								
<u>Carlos Castillo</u>									
76387					8/3/2011		40		\$0.00
Medium	Work In Progress				8/3/2011 3:07:08 PM				
Castillo, Carlos	NEED TWO (2 EA.) 115 V. ELEC. OULETS SO THAT I CAN REPLACED SOME THAT ARE BAD.								
<u>Arturo Nunez</u>									
76875	Vocational	Classroom			8/12/2011		31		\$0.00
Medium	Work In Progress				8/12/2011 9:55:04 AM				
Castillo, Carlos	SHOP 4 drop down cords 110 and 220 volt are broken 1 is 220 male and 3 are 110 female								
<u>Rosalinda Rodriguez</u>									
77182	Main Building	Classroom			8/19/2011		24		\$0.00
Medium	Work In Progress				8/19/2011 3:42:27 PM				
Ambriz, Jose	The following classrooms need AC/HVAC units checked C-1; 203; 306; 301; 401; Mrs. Harper's office								
<u>Rosalinda Rodriguez</u>									
75588					7/20/2011		54		\$0.00
Medium	Work In Progress				7/20/2011 3:04:21 PM				
Gomez, Jose L	PLEASE CLEAN KITCHEN FLOORS. SNP MANAGER OLGA B. 589.5332								
<u>Maritza Gonzalez</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

76744 8/10/2011 33 \$0.00

Medium Work In Progress 8/10/2011 6:51:15 AM

Gomez, Jose L NEED TO DISINFECT AND DETAIL ALL DRESSING AND LOCKER ROOMS.

Jesus Estrada

76820 GYM (2009) Gym 8/11/2011 32 \$0.00

Medium Work In Progress TRAINER 8/11/2011 1:11:49 PM

Carrasco, Danny FRANK MUNOZ, TRAINER AT STHS NEEDS SOME GAS FOR THE SCHOOL GATOR. CAN YOU PLEASE DELIVER 3 GALLONS TO HIM. THANKS!

Terry Alvarado

75206 Library 7/7/2011 67 \$0.00

Medium Work In Progress 7/7/2011 12:50:41 PM

Ambriz, Jose HALLWAY 200 ELECTRICAL ROOM SPLIT SISTEM BREAKER IS TRIPPING.

Manuel Prospero

75290 7/11/2011 63 \$0.00

Medium Work In Progress 7/11/2011 12:29:44 PM

Ambriz, Jose NEED SOME ASSITANCE ON TROBLE SHOOTING CHILLER, RESET ALARMS, BUT CHILLER WILL NOT STAY ON

Arturo Nunez

76015 7/29/2011 45 \$0.00

Medium Work In Progress MRS. 7/29/2011 1:53:52 PM

Prospero, Manuel MAINTENANCE PLEASE CHECK ON HVAC UNITS LOCATED BETWEEN MAIN BUILDING AND CAFETERIA-EXCESSIVE NOISE WHILE RUNNING AND LOUD BANGING WHEN AT LEAST 1 UNIT SHUTS DOWN.

Marylou Jimenez

77113 8/18/2011 25 \$0.00

Medium Work In Progress 8/18/2011 3:29:44 PM

Ambriz, Jose Need some assistance on trouble shooting e.c's on new gym, new dressing rooms, and coaches offices.

Arturo Nunez

77137 Main Building 8/19/2011 24 \$0.00

Medium Work In Progress 8/19/2011 8:59:11 AM

Ambriz, Jose room 501 still leaking
Room 502, 503, 506, 508 reporting AC/HVAC problems
Gym area locker rooms, coaches office and trainers
room not cooling

Rosalinda Rodriguez

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Santa Teresa HS								
77138	Library	Library			8/19/2011		24		\$0.00	
Medium	Work In Progress			8/19/2011 8:59:56 AM						
Nunez, Arturo		Library office AC/HVAC not working								
<u>Rosalinda Rodriguez</u>										
74953					7/4/2011	7/24/2011	70		\$0.00	
Medium	Work In Progress			7/4/2011 12:21:48 AM						
Orozco, Danny		Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
74924					7/4/2011	8/3/2011	70		\$0.00	
Medium	Work In Progress			7/4/2011 12:21:34 AM						
Nunez, Arturo		Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
74925					7/4/2011	8/3/2011	70		\$0.00	
Medium	Work In Progress			7/4/2011 12:21:35 AM						
Nunez, Arturo		Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
77206					8/22/2011		21		\$0.00	
Medium	Work In Progress	MARYLOU		8/22/2011 10:15:41 AM						
Ronquillo, Ruben		CAN STHS BORROW A FORK LIFT TO TRANSPORT A PRINTER FROM FRONT OFFICE STORAGE TO DRAFTING CLASSROOM OUT IN THE VOCATIONAL BLDG.								
<u>Marylou Jimenez</u>										
77737					9/1/2011		11		\$0.00	
Medium	Work In Progress			9/1/2011 3:50:28 PM						
Carrasco, Danny		I NEED 5 GALL OF GASOLINE FOR THE POLARIS AM RUANING ON EMPTY.								
<u>Manuel Prospero</u>										
76937	Applied Science	Classroom			8/15/2011		28		\$0.00	
Medium	Work In Progress			8/15/2011 2:12:03 PM						
Villalobos, Margret		Room 508 recurring problem with mice					Cost 100.00			
<u>Rosalinda Rodriguez</u>										
77895					9/4/2011	10/5/2011	8		\$0.00	
Medium	Work In Progress			9/4/2011 12:24:38 AM						
Prospero, Manuel		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>										

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
77896					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:39 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77897					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:39 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
74926					7/4/2011	7/9/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:21:35 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76057					7/31/2011	8/6/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:24:46 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77820					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:06 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75044					7/4/2011	7/11/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:29 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76124					7/31/2011	8/31/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:15 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76125					7/31/2011	8/8/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:16 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
76126					7/31/2011	8/8/2011	43		\$0.00
Medium	Work In Progress				7/31/2011 9:25:16 AM				
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
76056					7/31/2011		43		\$0.00
Medium	Work In Progress				7/31/2011 9:24:45 AM				
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
77822					9/4/2011		8		\$0.00
Medium	Work In Progress				9/4/2011 12:24:07 AM				
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
77808					9/4/2011	9/20/2011	8		\$0.00
Medium	Work In Progress				9/4/2011 12:24:00 AM				
Villalobos, Margret	Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.								
Margret Villalobos									
75271					7/10/2011	7/26/2011	64		\$0.00
Medium	Work In Progress				7/10/2011 12:16:07 AM				
Meraz, Rafael	Monthly - QRTLTY BLDG INSP REPORT (STH) - Refer to PM schedule details.								
Jesus Estrada									
74927					7/4/2011	7/11/2011	70		\$0.00
Medium	Work In Progress				7/4/2011 12:21:36 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
74929					7/4/2011		70		\$0.00
Medium	Work In Progress				7/4/2011 12:21:37 AM				
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
75042					7/4/2011	8/3/2011	70		\$0.00
Medium	Work In Progress				7/4/2011 12:22:28 AM				
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
75043					7/4/2011	7/11/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:28 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78155		Football Field			9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 3:56:27 PM					
Holguin, Alfredo	Running Track- needs the ruberized surface repaired at various places and lines repainted.								
<u>Guadalupe Ontiveros</u>									
74928					7/4/2011	7/6/2011	70		\$0.00
Medium	Work In Progress			7/4/2011 12:21:36 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76055					7/31/2011	8/3/2011	43		\$0.00
Medium	Work In Progress			7/31/2011 9:24:45 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77821					9/4/2011	9/7/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:06 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75239					7/10/2011	8/10/2011	64		\$0.00
Medium	Work In Progress			7/10/2011 12:15:53 AM					
Nunez, Arturo	Yearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76599					8/7/2011	9/7/2011	36		\$0.00
Medium	Work In Progress			8/7/2011 12:16:41 AM					
Prospero, Manuel	Yearly - Santa Teresa HS A-9 Air Cooled Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77104					8/18/2011		25		\$0.00
Medium	Work In Progress			8/18/2011 12:59:02 PM					
Carrasco, Danny	Need some unleaded fuel for vechile # 70, 15gal. running low. thank you.								
Arturo Nunez									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
76380					8/3/2011		40		\$0.00
Medium	Work In Progress			8/3/2011 2:51:45 PM					
Orozco, Danny	NEED TO GET 6 EA. FULL SPRINKLER HEADS TO REPLEMISH AND REPLACED THE ONES THAT WERE DAMAGED.								
Arturo Nunez									
76518	Main Building				8/5/2011		38		\$0.00
Medium	Work In Progress			8/5/2011 12:53:10 PM					
Valdez, Pedro	Need dead leaves and branches removed from several plants around main and surrounding buildings.								
Rosalinda Rodriguez									
77091	Main Building	Athletic Field			8/17/2011		26		\$0.00
Medium	Work In Progress			8/17/2011 4:13:41 PM					
Valdez, Pedro	Grass and weeds from area between fence and bleachers needs to be trimmed or removed. Other areas also have grass and weeds that are at least 4 inches tall. Also need trash cans on field for players/coaches to dispose of used water bottles and cups								
Rosalinda Rodriguez									
77945		Athletic Field			9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 8:36:56 AM					
Ontiveros, Guadalupe	Perdo Valdez is requesting,Stihl Vacum for removal of sand football.Stihl Blower,Stihl chain Saw, tire gauge and tire inflator,								
Guadalupe Ontiveros									
75574		Athletic Field			7/20/2011		54		\$0.00
Medium	Work In Progress			7/20/2011 9:17:27 AM					
Holguin, Alfredo	Tennis Courts- need cracks repaires and surfacing redone.								
Alfredo Holguin									
76902	Main Building	Classroom			8/12/2011		31		\$0.00
Medium	Work In Progress			8/12/2011 4:35:35 PM					
Nunez, Arturo	Ceiling in room 505 is leaking. Not sure if source is roof or AC								
Rosalinda Rodriguez									
77749	Main Building	Classroom			9/1/2011		11		\$0.00
Medium	Work In Progress	215		9/1/2011 4:54:28 PM					
Prospero, Manuel	Need white board relocated to make room for smart board installation								
Rosalinda Rodriguez									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
78116					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 11:25:30 AM					
Prospero, Manuel		Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign							
<u>Alfredo Holguin</u>									
75589					7/20/2011		54		\$0.00
Medium	Work In Progress			7/20/2011 3:07:28 PM					
Orozco, Danny		the Molino is broken and one of the ovens is not heating. SNP Manager Olga B. 589.5332							
<u>Maritza Gonzalez</u>									
76874	Main Building	Classroom			8/12/2011		31		\$0.00
Medium	Work In Progress			8/12/2011 9:52:08 AM					
Lara, Ralph		Door in counseling center is off balance and very difficult to open and close							
<u>Rosalinda Rodriguez</u>									
77090	GYM (2009)	Dressing Room			8/17/2011		26		\$0.00
Medium	Work In Progress			8/17/2011 4:11:16 PM					
Lara, Ralph		broken lockers need latches installed, coach will purchase latches							
<u>Rosalinda Rodriguez</u>									
76447					8/4/2011		39		\$0.00
Medium	Work In Progress			8/4/2011 3:22:48 PM					
Nunez, Arturo		Please mount chalk board removed from main building in Drama classroom located behind stage in cafeteria							
<u>Rosalinda Rodriguez</u>									
76517	Library	Library			8/5/2011		38		\$0.00
Medium	Work In Progress			8/5/2011 12:51:46 PM					
Nunez, Arturo		Need big screen TV mounted in library, see librarian for location							
<u>Rosalinda Rodriguez</u>									
76525	Main Building	Office			8/5/2011		38		\$0.00
Medium	Work In Progress			8/5/2011 1:37:30 PM					
Solis, Lorenzo		Flag pole cords need to be replaced, cords are broken and cannot be tied							
<u>Rosalinda Rodriguez</u>									
76845	Main Building	Classroom			8/11/2011		32		\$0.00
Medium	Work In Progress			8/11/2011 3:38:38 PM					
Nunez, Arturo		Room 501 has leak that has caused ceiling tiles to saturate and fall.							
<u>Rosalinda Rodriguez</u>									

9/12/2011 4:16:31 PM

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
76877	Vocational	Classroom			8/12/2011		31		\$0.00
Medium	Work In Progress			8/12/2011 10:07:05 AM					
Nunez, Arturo	Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805								
<u>Rosalinda Rodriguez</u>									
77008	Main Building	Classroom			8/16/2011		27		\$0.00
Medium	Work In Progress			8/16/2011 2:28:54 PM					
Nunez, Arturo	Room 511 cabinet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removed								
<u>Rosalinda Rodriguez</u>									
76836	Vocational	Classroom			8/11/2011		32		\$0.00
Medium	Work In Progress			8/11/2011 3:13:22 PM					
Nunez, Arturo	Wood shop rm 805 has roof leak								
<u>Rosalinda Rodriguez</u>									
75464					7/14/2011		60		\$0.00
Medium	Work In Progress			7/14/2011 1:12:03 PM					
Mijarez, Jaime	Need to fix leak in classroom.								
<u>Michael Munoz</u>									
75598					7/20/2011		54		\$0.00
Medium	Work In Progress			7/20/2011 3:42:06 PM					
Nunez, Arturo	NEED TO UNCLOGG MOP SINK IN NEW GYM.								
<u>Arturo Nunez</u>									
76019					7/29/2011		45		\$0.00
Medium	Work In Progress	NEW GYM		7/29/2011 2:04:03 PM					
Prospero, Manuel	NEED BANNERS IN NEW GYM TO BE HUNG UP								
<u>Marylou Jimenez</u>									
76365					8/3/2011		40		\$0.00
Medium	Work In Progress	MR.		8/3/2011 1:24:33 PM					
Prospero, Manuel	SERVICE AIR COMPRESSOR; OIL AND FILTER-OIL SHOWS LOW.								
<u>Marylou Jimenez</u>									
76366		Classroom			8/3/2011		40		\$0.00
Medium	Work In Progress	MR.		8/3/2011 1:32:49 PM					
Prospero, Manuel	SERVICES VACCUM SYSTEM-ROUTING-NOISY.								
<u>Marylou Jimenez</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
77686					9/1/2011		11		\$0.00
Medium	Work In Progress				9/1/2011 8:07:21 AM				
Castillo, Carlos		NEED A LIGHT FIXTURE FOR	I.S.S.	REST ROOM.					
<u>Arturo Nunez</u>									
76017					7/29/2011		45		\$0.00
Medium	Work In Progress	MRS.			7/29/2011 2:01:47 PM				
Nunez, Arturo		URGENT! MAINTENANCE DOORS NEED TO BE							
		PAINTED BEFORE 1ST DAY OF SCHOOL. OUTER							
		AND INNER DOORS.							
<u>Marylou Jimenez</u>									
76018					7/29/2011		45		\$0.00
Medium	Work In Progress	MRS.			7/29/2011 2:03:05 PM				
Prospero, Manuel		ASST. PRINCIPALS OFFICE HAS WET CEILING TILE							
		NEED SOURCE LOCATED AND FRAMES THAT							
		HOLD CEILING TILES NEED TO BE PAINTED.							
<u>Marylou Jimenez</u>									
77089	GYM (2009)	Dressing Room			8/17/2011		26		\$0.00
Medium	Work In Progress				8/17/2011 4:10:08 PM				
Lozoya, Manny		Lock for outside door of the football locker room does							
		not work							
<u>Rosalinda Rodriguez</u>									
77299					8/23/2011		20		\$0.00
Medium	Work In Progress				8/23/2011 3:52:36 PM				
Lara, Ralph		CYLINDERS ON OLD D.O.L. PORTABLE NEED TO							
		BE CHANGED TEACHER HAVING A HARD TIME							
		OPENING .							
<u>Arturo Nunez</u>									
78080					9/8/2011		4		\$0.00
Medium	Work In Progress				9/8/2011 2:50:23 PM				
Lara, Ralph		NEED TWO (2) EA. KEYS FOR ROOM # 602.							
<u>Arturo Nunez</u>									
Count: 76 Work Orders		Avg. Age of WO's	37		Total for Santa Teresa HS		0		\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

75618	Gym (1997)	Restroom (Boys)			7/21/2011		53		\$0.00
Medium	Work In Progress				7/21/2011 7:11:51 AM				

Villalobos, David
Two urinals are leaking water ever time you flush them the floor get puddles of water and smells bad i would like for the plumber to fix them before students return .thanks

Ismael Rodriguez

76723	North Building	Cafeteria			8/9/2011		34		\$0.00
Medium	Work In Progress				8/9/2011 3:46:56 PM				

Villalobos, David
North bldg kitchen, and restroom floor drains were backed up. Please give a work order to David Villalobos he helped me unclog the floor drains.

Jaime Mijarez

77044	South Building	Restroom (Boys)			8/17/2011		26		\$0.00
Medium	Work In Progress				8/17/2011 9:04:34 AM				

Villalobos, David
two urinals in the boys restroom are not working properly, there located in the south upper level east end.

Ismael Rodriguez

77510		Gym			8/29/2011		14		\$0.00
Medium	Work In Progress				8/29/2011 9:50:33 AM				

Villalobos, David
Comode in the 3rd girls restroom needs to be replaced.

Jacob Montano

77952	North Building	Restroom (Boys)			9/6/2011		6		\$0.00
Medium	Work In Progress				9/6/2011 8:51:24 AM				

Villalobos, David
I need 5gallons of cherry mat for drains.

Ismael Rodriguez

77564	South Building	Hallway/Corridor			8/30/2011		13		\$0.00
Medium	Work In Progress	POA CUBICLE			8/30/2011 9:01:06 AM				

Castillo, Carlos
CONNECT ELECTRICITY

Laura Parra

76478					8/5/2011		38		\$0.00
Medium	Work In Progress				8/5/2011 8:21:48 AM				

Ambriz, Jose
S.bldg upper level mechanical room. I need Joe Ambriz to help me find out the problem with this heat pump. It won't come out of heat mode.

Jaime Mijarez

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
76423					8/4/2011		39		\$0.00
Medium	Work In Progress			8/4/2011 9:10:56 AM					
Mijarez, Jaime	S.bldg upper level mechanical room heat pump is not changing to cooling it stays in heating mode. I already did some troubleshooting on tracer summit and it looks ok.								
<u>Jaime Mijarez</u>									
78117	Gym (1997)	Custodial			9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 12:10:18 PM					
Carbajal, Jimmy	Jimmy, i need a 100ft electrical cord to use in the gym to clean the bleachers with a electrical blower.Thanks...								
<u>Ismael Rodriguez</u>									
76499					8/5/2011		38		\$0.00
Medium	Work In Progress			8/5/2011 10:27:29 AM					
Gonzalez, Salvador	as per our conversation, please order material for light poles that are to be installed.thank you (concrete)								
<u>Michael Munoz</u>									
77875					9/4/2011	10/5/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:29 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77876					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:30 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77873					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:29 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76697					8/9/2011		34		\$0.00
Medium	Work In Progress			8/9/2011 11:12:30 AM					
Orozco, Danny	1) DRAIN IS CLOGGED. 2) SPRAYER TO DISHWASHER LEAKS. 3) NEW OVEN IS NOT HEATING UP AT ALL. SNP MANAGER PAULA S. 589.9836								
<u>Maritza Gonzalez</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

77391 North Building Office 8/25/2011 18 \$0.00

Medium Work In Progress 8/25/2011 9:39:58 AM

Ronquillo, Ruben North Bldg office. Windows that run along side of office and the exterior entrance doors next to the office need to be Tinted. The sun rays are causing to much heat and to much problems with the heat pump always running and not satisfying. Please contact building mechanic and principal to decide on darkness of Window Tint. There are a Total of 8 windows and two glass doors.

Jaime Mijarez

75542 North Building Hallway/Corridor 7/19/2011 55 \$0.00

Medium Work In Progress 7/19/2011 12:54:49 PM

Estrada, Jesus Lobby tile needs to be replaced north building.

Jesus Estrada

75769 7/25/2011 49 \$0.00

Medium Work In Progress 7/25/2011 9:28:54 AM

Gonzalez, Salvador Metal portable rooms 3-a, 3-b need window guards installed on all windows. As per Mrs. Lovelace portables rooms will be used for Orchestra music and they will be having expensive music instruments. A.S.A.P

Jaime Mijarez

78039 North Building Parking Lot 9/7/2011 5 \$0.00

Medium Work In Progress GATE ON SIDE 9/7/2011 3:42:16 PM

Gonzalez, Salvador GATE ON SIDE OF NORTH BUILDING NEEDS TO BE WELDED. ASAP.

Laura Parra

76500 8/5/2011 38 \$0.00

Medium Work In Progress 8/5/2011 10:29:52 AM

Ontiveros, Guadalupe please assist with an operator for ditchwitch to excavate 2- 240' trenches for electrical power.thank you

Michael Munoz

77950 Athletic Field 9/6/2011 6 \$0.00

Medium Work In Progress 9/6/2011 8:48:30 AM

Ontiveros, Guadalupe Johnny and many are request, grese gun for P.M on tractors.tire gauge ,tire inflator,

Guadalupe Ontiveros

77872 9/4/2011 9/12/2011 8 \$0.00

Medium Work In Progress 9/4/2011 12:24:28 AM

Mijarez, Jaime Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

9/12/2011 4:16:31 PM

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

77874					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:29 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78179	North Building	Portables			9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 8:49:58 AM					
Lara, Ralph	Rafa , in portable 2 theres a teacher that needs a key for her storage cabnit see Mr.Rodriguez.								
<u>Ismael Rodriguez</u>									
76756	North Building	Custodial			8/10/2011		33		\$0.00
Medium	Work In Progress			8/10/2011 8:57:39 AM					
Flores, Pete	Pete, the small tracter #455 needs tires and the oil to be change.								
<u>Ismael Rodriguez</u>									
77390	North Building	Portables			8/25/2011		18		\$0.00
Medium	Work In Progress	P2B		8/25/2011 9:36:22 AM					
Ronquillo, Ruben	1- WINDOWS NEED TO BE SEALED 2- DOOR WINDOW IS BROKEN PLEASE REPAIR								
<u>Laura Parra</u>									
76841					8/11/2011		32		\$0.00
Medium	Work In Progress			8/11/2011 3:30:22 PM					
Orozco, Danny	OVEN IS NOT HEATING UP AT ALL								
<u>Danny Orozco</u>									
77065					8/17/2011		26		\$0.00
Medium	Work In Progress			8/17/2011 2:24:17 PM					
Orozco, Danny	GARBAGE DISPOSAL NOT DRAINING WATER/FOOD WILL NOT GO DOWN. SNP MANAGER PAT S. 589.9836								
<u>Maritza Gonzalez</u>									
77770					9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 11:53:44 AM					
Moncayo, Fernando	REACH IN FREEZER IS NOT FREEZING PROPERLY. SNP MANAGER PAULA S. 589.9836								
<u>Maritza Gonzalez</u>									
78073	North Building	Cafeteria			9/8/2011		4		\$0.00
Medium	Work In Progress			9/8/2011 1:32:26 PM					
Castillo, Carlos	Safety Issue-As per cafeteria manager:Light fixture at entrance to kitchen not working.								
Carlos Castillo									

9/12/2011 4:16:31 PM

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
76958					8/15/2011		28		\$0.00
Medium	Work In Progress			8/15/2011 3:46:12 PM					
Ambriz, Jose	Gym concession stand ice maker. I am having problems with the ice maker again Joe A. This ice maker is old and to small and is not very dependable for the use of sports is it possible to get a new and bigger ice maker.								
Jaime Mijarez									
75770					7/25/2011		49		\$0.00
Medium	Work In Progress			7/25/2011 9:37:48 AM					
Lara, Ralph	Metal portable room 3-a, 3-a doors need to be secure please check with principal Montano to see if they want dead bolt locks on both room entrance doors. As per Mrs. Lovelace portable rooms will be used for Orchestra music and they will be having expensive music instruments. A.S.A.P								
Jaime Mijarez									
76440					8/4/2011		39		\$0.00
Medium	Work In Progress			8/4/2011 2:05:46 PM					
Lara, Ralph	N.bldg electronic handicap door opener special brass bolt is broken. I removed the bolt so you can see it and order several bolts to have in case others are broken. As per Mr. Montano needs to be fixed ASAP for student in wheel chair.								
Jaime Mijarez									
77317	South Building	Restroom (Girls)			8/24/2011		19		\$0.00
Medium	Work In Progress			8/24/2011 7:48:12 AM					
Lara, Ralph	REplacement of bathroom panel in south upper girls restroom as per Mr. Montano.								
Ismael Rodriguez									
77388	North Building	Hallway/Corridor			8/25/2011		18		\$0.00
Medium	Work In Progress	NEXT TO		8/25/2011 9:33:04 AM					
Lara, Ralph	TROPHY CASE- DOWNSTAIRS NORTH BLD NEXT TO ROOM 8-- NEEDS A LOCK. WOULD LIKE TO USE TO SET UP DISPLAYS FOR STUDENTS.. SECOND REQUEST								
Laura Parra									
Count: 34 Work Orders		Avg. Age of WO's 23		Total for Santa Teresa MS			0	\$0.00	

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
76545	Main Building	Classroom			8/5/2011		38		\$0.00
Medium	Work In Progress	25		8/5/2011 3:22:25 PM					
Medina, Eric	Eric, the bathroom in room 25 needs to be painted. Room was painted but bathroom needs to be painted as well.								
<u>Yvette Cortez</u>									
76704		Restroom (Girls)			8/9/2011		34		\$0.00
Medium	Work In Progress			8/9/2011 1:14:03 PM					
Medina, Eric	Eric, girls bathroom floor needs t be painted.								
<u>Yvette Cortez</u>									
77338	Main Building	Library			8/24/2011		19		\$0.00
Medium	Work In Progress	C. MORENO		8/24/2011 12:18:43 PM					
Medina, Eric	NEED MAIN LIBRARY DOORS AND AUDIO VISUAL DOORS RE-PAINTED.								
<u>David Avila</u>									
77043					8/17/2011		26		\$0.00
Medium	Work In Progress			8/17/2011 8:23:35 AM					
Ambriz, Jose	Jose need to order frames also for the new a/c's at sunland park if possible								
<u>Eric Medina</u>									
77294		Classroom			8/23/2011		20		\$0.00
Medium	Work In Progress	Classroom #22		8/23/2011 3:47:18 PM					
Medina, Eric	Leak in classroom, on top of student work area. 2nd request								
<u>David Avila</u>									
76493	Main Building	Parking Lot			8/5/2011		38		\$0.00
Medium	Work In Progress			8/5/2011 9:40:34 AM					
Medina, Eric	Eric, as per Mrs. Ramirez we need four baracades. Please place an order for them.								
<u>Yvette Cortez</u>									
78165					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:44 AM					
Medina, Eric	Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77839					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:14 AM					
Medina, Eric	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
78126					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 2:44:46 PM					
Munoz, Michael	need to construct concret pad for trash dumpsters								
Alfredo Holguin									
76987	Main Building	Classroom			8/16/2011		27		\$0.00
Medium	Work In Progress	25		8/16/2011 10:36:12 AM					
Medina, Eric	AC in room 25 is still blowing out hot air. It's already been looked at but it's still very hot. It has to be turned on low so students could hear teacher. Also, if switch could be checked, that might be the problem.		8/16 - route to Eric asp Mike						
Yvette Cortez									
76991	Main Building	Classroom			8/16/2011		27		\$0.00
Medium	Work In Progress	15		8/16/2011 10:44:56 AM					
Medina, Eric	Eric, please lower vents on AC and place a deodorizer block in air vent. Also, if you may mount a screen.								
Yvette Cortez									
78020	Main Building	Classroom			9/7/2011		5		\$0.00
Medium	Work In Progress	Classroom 24		9/7/2011 1:39:19 PM					
Medina, Eric	Erick, please check Mrs. Gamboa's air conditioner, she is stating that it is not cooling and it is very hot. Thank you.								
David Avila									
77700					9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 11:06:45 AM					
Medina, Eric	purchase new D130 john deere lawn mower for site to replace existing one.								
Michael Munoz									
77612					8/31/2011		12		\$0.00
Medium	Work In Progress			8/31/2011 12:21:04 AM					
Medina, Eric	Monthly - Sunland Park ES A-16 Fan Exh Semiannual - Refer to PM schedule details.								
Margret Villalobos									
77842					9/4/2011	9/20/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:15 AM					
Medina, Eric	Monthly - Sunland Park ES A-1 Wall Ref Semiannual - Refer to PM schedule details.								
Margret Villalobos									
77843					9/4/2011	9/25/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:16 AM					
Medina, Eric	Monthly - Sunland Park ES C-12 Chem. Feeder (SA) - Refer to PM schedule details.								
Margret Villalobos									
9/12/2011 4:16:31 PM									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Sunland Park ES									
77840					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:14 AM					
Medina, Eric	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77841					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:15 AM					
Medina, Eric	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76375					8/3/2011		40		\$0.00
Medium	Work In Progress			8/3/2011 2:36:41 PM					
Orozco, Danny	ALL OVENS ARE NOT WORKING PROPERLY, THEY DO TURN ON OK BUT AFTER ABOUT 10 MINUTES ONE GOES TOO HIGH AND THE OTHERS WILL STOP HEATING. SNP MANAGER MARINA R. 589.2545								
<u>Maritza Gonzalez</u>									
77723					9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 3:08:06 PM					
Moncayo, Fernando	TEMPERATURE IN REFRIGERATOR GOES UP AND DOWN AND MAKING A CLICKING NOISE. SNP MANAGER MARINA R. 589.2545								
<u>Maritza Gonzalez</u>									
77969					9/6/2011		6		\$0.00
Medium	Work In Progress			9/6/2011 11:16:22 AM					
Moncayo, Fernando	3 COMPARTMENT SANITIZER SINK IS LEAKING. SNP MANAGER MARINA R. 589.2545								
<u>Maritza Gonzalez</u>									
77522	Main Building	Classroom			8/29/2011		14		\$0.00
Medium	Work In Progress	Classroom #15		8/29/2011 2:13:13 PM					
Lara, Ralph	NEED FOR ERICK MEDINA OR RAFA TO CHECK INTO MS. MORALES' BACK DOOR. DOOR IS NOT OPENING, FIRE HAZARD.								
<u>David Avila</u>									
77507					8/29/2011		14		\$0.00
Medium	Work In Progress			8/29/2011 9:33:05 AM					
Carrasco, Danny	need fuel equipment #'s 619, 429, 105								
Eric Medina									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
76419	Main Building	Parking Lot			8/4/2011		39		\$0.00
Medium	Work In Progress			8/4/2011 8:42:20 AM					
Medina, Eric	Eric, the trees out in the parking lot need to be trimmed. We've had several complaints about trees scratching the cars that pass by.								
Yvette Cortez									
76678	Main Building	Classroom			8/9/2011		34		\$0.00
Medium	Work In Progress	14		8/9/2011 8:10:21 AM					
Medina, Eric	Eric, the whiteboard in room 14 is missing. Please install one of the chalkboards in the room.								
Yvette Cortez									
76994	Main Building	Classroom			8/16/2011		27		\$0.00
Medium	Work In Progress	29		8/16/2011 10:58:17 AM					
Medina, Eric	Eric, please move small board to left side of classroom. (rug area).								
Yvette Cortez									
77175					8/19/2011		24		\$0.00
Medium	Work In Progress			8/19/2011 3:29:10 PM					
Ambriz, Jose	Joe need to order (2) two taylor halsey water fountains both have compressors out								
Eric Medina									
77337	Main Building	Library			8/24/2011		19		\$0.00
Medium	Work In Progress	Library (C.		8/24/2011 12:13:29 PM					
Medina, Eric	NEED CLOCK HUNG ON WALL								
David Avila									
77970	Main Building	Office			9/6/2011		6		\$0.00
Medium	Work In Progress	Ms. Terrazas -		9/6/2011 11:54:03 AM					
Medina, Eric	NEED FOR ERICK TO INSTALL A KEYBOARD "PULL-OUT" FOR MRS. TERRAZAS. ALREADY SPOKE TO ERICK, HE KNOWS EXACTLY WHAT HE NEEDS. THANK YOU								
David Avila									
77554					8/30/2011		13		\$0.00
Medium	Work In Progress	PLAYGROUND		8/30/2011 7:53:44 AM					
Medina, Eric	ERIC, CAN YOU PLEASE CLEAN OUT THE TRASH CANS OUTSIDE ON THE PLAYGROUND. THEY ARE FULL AND ARE SPILLING OUT.								
David Avila									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
76546	Main Building	Classroom			8/5/2011		38		\$0.00
Medium	Work In Progress	21		8/5/2011 3:24:04 PM					
Medina, Eric	Eric, some flouresent light bulbs need to be replaced in room 21 please.								
Yvette Cortez									
76550	Main Building	Classroom			8/5/2011		38		\$0.00
Medium	Work In Progress	21		8/5/2011 3:28:34 PM					
Medina, Eric	Eric, please check the faucet in room 21, its dripping and clogged.								
Yvette Cortez									
76561	Main Building	Parking Lot			8/5/2011		38		\$0.00
Medium	Work In Progress	Back Parking		8/5/2011 3:58:54 PM					
Medina, Eric	Eric, Mrs. Althouse (nurse) needs to be assigned a parking space in the back parking lot.								
Yvette Cortez									
76634	Main Building	Classroom			8/8/2011		35		\$0.00
Medium	Work In Progress	13 & 15		8/8/2011 2:45:40 PM					
Medina, Eric	Eric, Mr. Lozano and Ms. Morales both need their T.V. mounted in their classrooms for broadcasting.								
Yvette Cortez									
76670	Main Building	Classroom			8/9/2011		34		\$0.00
Medium	Work In Progress	23		8/9/2011 7:57:13 AM					
Medina, Eric	Eric, please drill holes for a coat rack and hooks.								
Yvette Cortez									
76675	Main Building	Classroom			8/9/2011		34		\$0.00
Medium	Work In Progress	35		8/9/2011 8:04:37 AM					
Medina, Eric	Eric, please set repair shelves in room 35 for Ms. Moran.								
Yvette Cortez									
Count: 36 Work Orders			Avg. Age of WO's	21	Total for Sunland Park ES			0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
77569	Main Building	Classroom			8/30/2011		13		\$0.00
Medium	Work In Progress	101		8/30/2011 10:00:54 AM					
Sotelo, Enrique	EDNA CLARY, 101, NEEDS TWO ELECTRICAL OUTLETS IN THE BATHROOM FOR ELECTRIC CHANGING TABLE. PLACEMENT IS MARKED ON WALLS AS TO WHERE THEY WOULD LIKE THEM PLACED								
<u>Joanne Munoz</u>									
77715					9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 2:02:25 PM					
Sotelo, Enrique	NEED INSTALED NEW OUTLET ON REST ROOM ROOM 101 FOE NEW FURNITURE								
<u>Juan Vargas</u>									
75826					7/26/2011		48		\$0.00
Medium	Work In Progress			7/26/2011 11:28:44 AM					
Solis, Lorenzo	NEED REPLCE WATER POMP AND MOTOR A/C COACH ROOM								
<u>Juan Vargas</u>									
77467					8/26/2011		17		\$0.00
Medium	Work In Progress			8/26/2011 8:35:55 AM					
Lozoya, Manny	need fix gabinete lock not open on parent room								
<u>Juan Vargas</u>									
76168					8/1/2011		42		\$0.00
Medium	Work In Progress			8/1/2011 7:38:41 AM					
Vargas, Juan	councilor room need replace a/c circulation pomp								
<u>Juan Vargas</u>									
76204					8/1/2011		42		\$0.00
Medium	Work In Progress			8/1/2011 3:38:59 PM					
Apodaca, Mario	SEWAGE WATER NEED REPLACE POMP NOT WORK								
<u>Juan Vargas</u>									
75071					7/4/2011		70		\$0.00
Medium	Work In Progress			7/4/2011 12:22:39 AM					
Sanchez, Raul	Monthly - Sunrise ES - DP-1421 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77914					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:47 AM					
Sanchez, Raul	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
77882					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:33 AM					
Vargas, Juan	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78187					9/12/2011		0		\$0.00
Medium	Work In Progress			9/12/2011 10:36:48 AM					
Martinez, Larry	On September 14, 2011, please deliver 17 boxes of Social Studies material to Sunrise Elementary.								
<u>Yolie Jacquez</u>									
76965					8/15/2011		28		\$0.00
Medium	Work In Progress			8/15/2011 3:51:36 PM					
Vargas, Juan	08-15-11	1-check school 3-p.plant	2-76596	2-76595	8/15 -4				
<u>Juan Vargas</u>									
77582	Main Building	Custodial			8/30/2011		13		\$0.00
Medium	Work In Progress			8/30/2011 1:12:02 PM					
Carbajal, Jimmy	Royal up-right vacuum cleaner will not engage in upright position and metal cord holder on handle is broken								
<u>Felipe Gallegos</u>									
77887					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:35 AM					
Vargas, Juan	Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76116					7/31/2011		43		\$0.00
Medium	Work In Progress			7/31/2011 9:25:12 AM					
Vargas, Juan	Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77880					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:32 AM					
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77881					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:32 AM					
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Sunrise ES								
77883					9/4/2011		8		\$0.00	
Medium	Work In Progress			9/4/2011 12:24:33 AM						
Vargas, Juan	Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
78171					9/11/2011	9/27/2011	1		\$0.00	
Medium	Work In Progress			9/11/2011 12:20:47 AM						
Vargas, Juan	Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
77076					8/17/2011		26		\$0.00	
Medium	Work In Progress			8/17/2011 3:33:42 PM						
Carrasco, Danny	need 15 gls, diesel for 430 mover									
<u>Juan Vargas</u>										
77685					9/1/2011		11		\$0.00	
Medium	Work In Progress			9/1/2011 7:52:43 AM						
Carrasco, Danny	NEED DIESEL FOR FIRE POMP ON C.H.S.									
<u>Juan Vargas</u>										
77614					8/31/2011		12		\$0.00	
Medium	Work In Progress			8/31/2011 12:21:05 AM						
Vargas, Juan	Monthly - Sunrise ES A-1 Semiannual MCS - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
77884					9/4/2011		8		\$0.00	
Medium	Work In Progress			9/4/2011 12:24:33 AM						
Vargas, Juan	Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
77885					9/4/2011		8		\$0.00	
Medium	Work In Progress			9/4/2011 12:24:34 AM						
Vargas, Juan	Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
77886					9/4/2011		8		\$0.00	
Medium	Work In Progress			9/4/2011 12:24:34 AM						
Vargas, Juan	Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
Count: 24 Work Orders			Avg. Age of WO's	19				Total for Sunrise ES	0	\$0.00

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
75317					7/12/2011		62		\$0.00
Medium	Work In Progress			7/12/2011 7:54:54 AM					
Sotelo, Enrique	NEED TO REPLACE BULBS ON PARKING LOT LIGHTS								
Danny Miranda									
77703					9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 11:35:18 AM					
Sotelo, Enrique	NEED TWO NEW RECEPTICALS IN RESTROOM RM. 101 SP/ED FOR CHANGING TABLE								
Danny Miranda									
77558					8/30/2011		13		\$0.00
Medium	Work In Progress			8/30/2011 8:31:19 AM					
Lozoya, Manny	NEED TO CK. H/C DOOR CLOSER TO FRONT ENTRANCE								
Danny Miranda									
77706	Main Building	Classroom			9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 11:45:08 AM					
Lozoya, Manny	MS. NAVARRO PRINCIPAL REQUEST THAT WE HAVE 2 KEYS MADE FOR CAFETERIA AND 3 NEW KEYS WITH DIFFERENT LOCK MADE FOR STORAGE UNIT NEXT TO CAFETERIA.								
Debra Facio									
77718					9/1/2011		11		\$0.00
Medium	Work In Progress			9/1/2011 2:41:33 PM					
Lozoya, Manny	NEED TO CK. FRONT DOOR IN RM. 105 PREKINDER CHILD IS GETTING OUT OF CLASSROOM								
Danny Miranda									
78112					9/9/2011		3		\$0.00
Medium	Work In Progress			9/9/2011 10:23:47 AM					
Lozoya, Manny	NEED LOCK AND KEYS MADE FOR DESK IN RM. #105								
Danny Miranda									
77005					8/16/2011		27		\$0.00
Medium	Work In Progress			8/16/2011 2:05:23 PM					
Ontiveros, Guadalupe	NEED TO REPLACE DEAD PINE TREE WITH NEW ONE BY BUSS TURN AROUND								
Danny Miranda									
77830					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:10 AM					
Miranda, Danny	Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
9/12/2011 4:16:31 PM									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
77831					9/4/2011		8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:11 AM					
Miranda, Danny	Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77832					9/4/2011	9/12/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:11 AM					
Miranda, Danny	Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78162					9/11/2011	9/27/2011	1		\$0.00
Medium	Work In Progress			9/11/2011 12:20:42 AM					
Miranda, Danny	Monthly - Vado ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77829					9/4/2011	9/10/2011	8		\$0.00
Medium	Work In Progress			9/4/2011 12:24:10 AM					
Miranda, Danny	Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77753					9/2/2011		10		\$0.00
Medium	Work In Progress			9/2/2011 8:42:19 AM					
Miranda, Danny	NEED TO CHANGE FILTERS								
<u>Danny Miranda</u>									
76418		Cafeteria			8/4/2011		39		\$0.00
Medium	Work In Progress			8/4/2011 8:31:11 AM					
Orozco, Danny	ICE MACHINE NOT WORKING (NO ICE)								
	EVA M. SNP MGR 233-2945								
<u>Jacqueline Aguilar</u>									
78004					9/7/2011		5		\$0.00
Medium	Work In Progress			9/7/2011 9:30:49 AM					
Moncayo, Fernando	NEED WATER FILTER FOR ICE MACHINE- SNP MANAGER EVA M. 233.2945								
<u>Maritza Gonzalez</u>									
75525					7/19/2011		55		\$0.00
Medium	Work In Progress			7/19/2011 7:49:57 AM					
Gonzalez, Salvador	NEED ANCORES FOR SOCCER GOALS								
Danny Miranda									

769 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Vado ES							
77258					8/23/2011		20		\$0.00
Medium	Work In Progress				8/23/2011 9:29:38 AM				
Carrasco, Danny	NEED DIESEL FOR MOWER								
Danny Miranda									
75526		Athletic Field			7/19/2011		55		\$0.00
Medium	Work In Progress				7/19/2011 7:53:18 AM				
Ontiveros, Guadalupe	NEED NEW SOCCER NETS FOR FOR GOALS DUE TO VANDALISM								
Danny Miranda									
Count: 18 Work Orders		Avg. Age of WO's		20	Total for Vado ES			0	\$0.00
Count: 769 Work Orders		Avg. Age of WO's		23	Grand Total			6	\$150.00