Selected Da	ate Range for Request	Dates:7/1/2011 -	6/30/2012 Order By Loca	ition, Status	-			Tota Costs
WOID	Building	Area		Until	Request Date Target Comp Date	Al	Labor	
Priority	Status	Area Number	Reason	Crea	ited Date/Time Actual Comp Date	Aged	Hours	
Assigned	То	Description			Action Taken			
Requester	Name							
Location:	Anthony	- On Track Pre-	K					
76681		Classroom			8/9/2011	70		\$0.00
Medium	Work In Progress			8/9/2	2011 8:25:33 AM			
Ronquillo,	Ruben	upper primary	room 107 needs 4 blind	ds 59x54				
Hector Vill	alobos							
75897					7/27/2011	83		\$0.00
Medium	Work In Progress			7/27/2	2011 1:32:06 PM			
Villalobos,	Hector	They want the	sand box Border to be	e raise up				
Hector Vill	alobos				2/2=/22/			
78842					9/27/2011	21		\$0.00
Medium	Work In Progress	parking lot		9/27/20	11 12:36:43 PM			
Ronquillo,	Ruben	have any ques 1904 -Staff Parking -Parent Parking -Please keep g		ma Sierra				
Lucia Alme								
Count: 3 V	Vork Orders	Α	vg. Age of WO's 58		Total for Anthony - On Track	Pre-K	0	\$0.00

10/18/2011 1:23:06 PM Page 1 of 172

WOID Priority Assigned 1 Requester			eferred By	Until Request Date Ta Created Date/Time Ac	-	Days Aged	Labor Hours	Costs
Location:	Anthony	ES						
77666		Portables		8/31/2011		48		\$0.00
Medium	Work In Progress			8/31/2011 3:38:05 PM				
Appelzoller	, Fred	pts 1 to4 replace	water heaters in	bathrooms				
Hector Villa 77698	alobos	Portables		9/1/2011		47		\$0.00
Medium	Work In Progress			9/1/2011 9:27:32 AM				
Appelzoller	r, Fred	PT1,2 need a hos	se bibb by water	fountain outside				
Hector Villa	alobos			7/40/0044		00		#0.00
75321				7/12/2011		98		\$0.00
Medium	Work In Progress	New Classroom		7/12/2011 9:06:21 AM				
Lozoya, Ma	anny	new classroom b	uilding. Please c	o be installed at the coordinate with Construction (575)				
<u>Peggy Jo F</u> 75357	lernandez Main Building			7/13/2011		97		\$0.00
Medium	Work In Progress			7/13/2011 6:29:09 AM				
Lozoya, Ma	anny	mld blg remove	all hardware from	doors				
Hector Villa	alobos							
75596				7/20/2011		90		\$0.00
Medium	Work In Progress	PRE-K		7/20/2011 3:39:41 PM				
Lozoya, Ma	•	PLEASE CHANG PORTABLES 1-8		DORS TO H AND				
<u>Jessica Lo</u> 77061	pez Cafeteria			8/17/2011		62		\$0.00
Medium	Work In Progress			8/17/2011 1:56:21 PM				
Lozoya, Ma	anny	New cafeteria pa	nd lock chargeloc	k from CD 30 to CD5				
Hector Villa	alobos							
79718				10/13/2011		5		\$0.00
Medium	Work In Progress			10/13/2011 8:03:36 AM				
Flores, Pet		need Antifreeze f broken 153	or truck and heat	er control knob is				
Hector Villa 79284	alobos			10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:28:22 AM				
Orozco, Da	•	Monthly - Anthon PM schedule deta		d Cleaning - Refer to				

10/18/2011 1:23:06 PM Page 2 of 172

WOID Priority Assigned		Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	ES						
75176				7/7/2011		103		\$0.00
Medium	Work In Progress			7/7/2011 7:31:56 AM	1			
Carrasco,	Danny		Dorma hardare fo tractor at site (Keri	or storage at PPD. ry Smith 650-7779)				
Alfredo Ho 78626	lguin			9/21/2011		27		\$0.00
Medium	Work In Progress	PORTABLE 8		9/21/2011 1:53:18 PM	1	21		ψ0.00
Ambriz, Ju	· ·	PLEASE PICK	UP MATH MANIPI TO WAREHOUSE		•			
Jessica Lo	pez			40/5/0044		40		Ф0.00
79425	W 11 B	0050 055105		10/5/2011		13		\$0.00
Medium	Work In Progress	SPED OFFICE		10/5/2011 2:58:56 PM	1			
Martinez, L	arry		EL AND DESK FRO AND BROKEN AN IG USED					
Margaret V	'illalobos			10/17/2011		1		\$0.00
Medium	Work In Progress	SPED OFFICE		10/17/2011 10:07:19	1	'		ψ0.00
Briones, E	•	PO #10110876 PICK UP ON B		10,117,2011 10.01110				
Margaret V	'illalobos			0/2/2011		46		
77754	Mark In Drawnson			9/2/2011		40		\$0.00
Medium	Work In Progress	N. 169 6		9/2/2011 9:08:11 AM	I			
Villalobos,		Need filters for	heating pts, drug	rree				
Hector Villa 79519	alobos			10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress			10/9/2011 12:16:35 AM	1			
Villalobos,	Hector	Monthly - Antho	ony ES A4 (Rooftor hedule details.	o Unit)(S.Annual) -				
Margret Vi	lalobos			40/0/0044	40/40/2044	4.0		<u>Фо оо</u>
79167	Work in Drogram			10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	N (11 A (1	E0.D (1	10/2/2011 12:27:12 AM	I			
Villalobos,		Monthly - Antho schedule detail	ony ES Roof Inspec s.	ction - Refer to PM				
Margret Vil 79198	lalobos			10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:27:32 AM		-		
Villalobos,	· ·	Monthly - Antho		t Test: Monthly - Refer				
Margret Vi	lalobos							
	1 1.22.06 DM							

10/18/2011 1:23:06 PM Page 3 of 172

T9199 Medium Villalobos, H Margret Villa 79252	Anthony Work In Progress lector	10/2/2011 10/2/2011 12:27:32 AM	10/10/2011		
Medium Villalobos, H	•		10/10/2011		
Villalobos, H Margret Villa	•	10/2/2011 12:27:32 AM		16	\$0.00
Margret Villa	lector				
		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.			
79252	alobos	10/2/2011		16	\$0.00
Madium	Mark In Dragraga			10	φυ.υυ
	Work In Progress	10/2/2011 12:28:03 AM			
Sanchez, Ra		Monthly - Anthony ES - Monthly Meter Readings - Refer to PM schedule details.			
Margret Villa 79280	alobos	10/2/2011	10/8/2011	16	\$0.00
	Work In Progress	10/2/2011 12:28:19 AM			·
Villalobos, H	· ·	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.			
Margret Villa	alobos	40/0/044	44/0/0044	40	Ф0.00
79114	W 11 B	10/2/2011	11/2/2011	16	\$0.00
	Work In Progress	10/2/2011 12:26:43 AM			
Villalobos, H		Yearly - Anthony ES U2 (Gas Heat)(Yearly) - Refer to PM schedule details.			
Margret Villa 79109	alobos	10/2/2011	11/2/2011	16	\$0.00
	Work In Progress	10/2/2011 12:26:40 AM			
Villalobos, H	•	Yearly - Anthony ES I4 (Fan Coil)(Yearly) - Refer to PM schedule details.			
Margret Villa	alobos	40/0/044	11/0/0011	40	 Φ0.00
79110		10/2/2011	11/2/2011	16	\$0.00
	Work In Progress	10/2/2011 12:26:41 AM			
Villalobos, H		Monthly - Anthony ES A16 (Fan Exhst.)(Semi. Ann.) - Refer to PM schedule details.			
Margret Villa 79111	alobos	10/2/2011	11/2/2011	16	\$0.00
	Work In Progress	10/2/2011 12:26:41 AM			*
Villalobos, H	•	Yearly - Anthony ES H6 (Furnace Gas)(Yearly) - Refer to PM schedule details.			
Margret Villa	alobos				
79112		10/2/2011	10/18/2011	16	\$0.00
Medium \	Work In Progress	10/2/2011 12:26:42 AM			
Villalobos, H	lector	Monthly - Anthony ES A3(Rooftop Unit)(S.Annual) - Refer to PM schedule details.			

10/18/2011 1:23:06 PM Page 4 of 172

WOID Priority	Building Status	Area Deferred By Unt Area Number Reason	Created Date/Time A	arget Comp Date ctual Comp Date	Days Aged	Labor Hours	
Assigned ²	Го	Description		Action Taken			
Requester	Name						
Location:	Anthony	ES					
79113			10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	1	10/2/2011 12:26:42 AM				
Villalobos,	Hector	Monthly - Anthony ES H11 (Elect.Heat)(S. Refer to PM schedule details.	.Annual) -				
Margret Vil	lalobos Main Building		9/19/2011		29		\$0.00
78494	· ·				29		φυ.υυ
Medium	Work In Progress		9/19/2011 10:07:08 AM				
Carrasco, I	Danny	need fuel for truck #79					
David Vega 79556	a Main Building		10/10/2011		8		\$0.00
Medium	Work In Progress		10/10/2011 10:34:48				******
Carrasco, I	· ·	need fuel for truck #79	10/10/2011 10:01:10				
	•	need identify track #19					
David Vega 79828	d	Classroom	10/17/2011		1		\$0.00
Medium	Work In Progress		10/17/2011 10:34:21				
Carrasco, I	Danny	Need two motors 3/4 ,7 belts 4-L590 ,1 c	copper 1/4 line				
Hector Villa	alobos						
79804		Portables	10/17/2011		1		\$0.00
Medium	Work In Progress	1	10/17/2011 8:44:44 AM				
Ronquillo,	Ruben	PT 5,7 broken windows , bubble glass 21 22x35	1/4x341/4,				
Hector Villa 77953	alobos		9/6/2011		42		\$0.00
Medium	Work In Progress		9/6/2011 9:01:14 AM		12		ψ0.00
Moncayo, I		THIRD FREEZER IS NOT WORKING DU					
Aida Salce		VANDALISM.	E IO				
78813	Main Building		9/27/2011		21		\$0.00
Medium	Work In Progress		9/27/2011 7:49:50 AM				
Ontiveros,	Guadalupe	a 12 x 16 morgan will be delivered. need small pad. contact person on site will be m villalobos (sped). call mike for any questio	nargret				
Michael Mu 75824	unoz Main Building		7/26/2011		84		\$0.00
Medium	Work In Progress	7	7/26/2011 10:51:05 AM		٠.		Ψ0.00
	· ·		,20,2011 10.01.00 AW				
Villalobos,	Hecioi	lounge- replace window blind.					

10/18/2011 1:23:06 PM Page 5 of 172

WOID	Building	Area Deferred By		Target Comp Date	Days Aged	Labor Hours	
Priority	Status	Area Number Reason	Created Date/Time A	-	Ageu	Hours	
Assigned [•] Requester		Description		Action Taken			
<u> </u>							
Location:	Anthony	E8					
78258			9/13/2011		35		\$0.00
Medium	Work In Progress	Alamo - SPED	9/13/2011 1:56:42 PM				
Munoz, Mi	chael	Asp Alfredo, make arrangement Storage Unit from GAC to the Al					
Alfredo Ho	olguin Original Main	Office	9/15/2011		33		\$0.00
78394	-	Office			33		φυ.υυ
Medium	Work In Progress		9/15/2011 2:43:41 PM				
Carrasco,	Danny	need 3 signs for SPED OFFICE					
Hector Villa	alobos		2/17/22/1				
78374			9/15/2011		33		\$0.00
Medium	Work In Progress		9/15/2011 8:05:46 AM				
Gonzalez,	Salvador	Blue long trailer need to be wield	d in some place.				
Hector Villa	alobos						
79605		Portables	10/11/2011		7		\$0.00
Medium	Work In Progress		10/11/2011 8:11:30 AM				
Lozoya, Ma	anny	pt 7,8, need 2 door weatherstrip					
Hector Villa							
78387	Main Building		9/15/2011		33		\$0.00
Medium	Work In Progress		9/15/2011 11:55:50 AM				
Carrasco,	Danny	need fuel mixture for weed eater	rs and blower code#600				
David Veg	a						
77219			8/22/2011		57		\$0.00
Medium	Work In Progress	78 Building	8/22/2011 12:19:39 PM				
Lozoya, M	anny	Cores need to be installed in the coordinate with Contractor - Kerl Construction (575) 650-7779					
	Hernandez		0/00/0044		40		Φο οο
79037			9/30/2011		18		\$0.00
Medium	Work In Progress		9/30/2011 11:20:59 AM				
Lozoya, Ma	anny	ASP PER MIKE MUNOZ, NEED THE CAFETERIS TO KARRIE S CONSTRUCTION TODAY.		9/30/11 - NOTIFED	MANNY		
Michael Mi 79314	unoz Cafeteria		10/3/2011		15		\$0.00
					10		Ψ0.00
Medium	Work In Progress		10/3/2011 8:03:03 AM				
Lozoya, Ma	anny	need to talk to contractor for key	ys for new cafeteria				

10/18/2011 1:23:06 PM Page 6 of 172

Selected Da WOID Priority	ite Range for Request Building Status	Dates:7/1/2011 - Area Area Number	6/30/2012 Order By Loo Deferred By Reason	•	arget Comp Date	Days Aged	Labor Hours	Costs
Assigned '	То	Description			Action Taken			
Requester	Name							
Location:	Anthony	ES						
79805		Office		10/17/2011		1		\$0.00
Medium	Work In Progress			10/17/2011 8:46:45 AM				
Lozoya, Ma	anny	Need a key k 6	2 and install code for	k62 on door. a.s.a.p				
Hector Villa	alobos							
79891				10/18/2011		0		\$0.00
Medium	Work In Progress			10/18/2011 9:03:03 AM				
Lozoya, Ma	anny	upper primary	need pad lock for gate	e praking lot a.s. a.p				
Hector Villa	alobos							
75637				7/21/2011		89		\$0.00
Medium	Work In Progress	SPED OFFICE		7/21/2011 2:56:14 PM				
Villalobos,	Hector		E LIGHTING LIGHTB NEVAREZ TO ROOM EDS					
Margaret V	/illalobos Work Orders		vg. Age of WO's 31		Total for Anthon	- 50	0	\$0.00

10/18/2011 1:23:06 PM Page 7 of 172

WOID Priority Assigned 1 Requester		Area D Area Number R Description	eferred By eason	Until Request Date of Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Berino E	6						
78254				9/13/2011		35		\$0.00
Medium	Work In Progress			9/13/2011 1:21:00 PM				
Appelzoller	, Fred	RM 114 HAS A S	SLANT COVER EED YOUR AS	HAVE A LEAKING SINK WILL NEED TWO SSITANCE THANK YOU				
Adan Durai 79612	า			10/11/2011		7		\$0.00
Medium	Work In Progress			10/11/2011 9:41:14 AM		-		V
Appelzoller	, Fred	GANG RESTROC	OM SOUTH WE	HE TAIL PIPE URNIAL EST SIDE IS LEAKING DU SIR AND GOD				
Adan Durai 79616	า			10/11/2011		7		\$0.00
Medium	Work In Progress			10/11/2011 10:37:03		•		ψ0.00
Appelzoller	, Fred	RESTROOM ACE	ROSS FROM T G WATER VER WATER MIX-V	HE VALUES IN GANG HE NURSE OFFICE Y HOT FOR KIDS 'ALUE THANK YOU SIR				
Adan Durai 79694	า			10/12/2011		6		\$0.00
Medium	Work In Progress			10/12/2011 2:40:39 PM		J		ψ0.00
Appelzoller	· ·	GANG RESTROC	OM SOUTHWE RESTROOM N	THE COMODE IN ST MIDDLE WING IS EED TO REPLACE				
Adan Durai 78760	า	Classroom		9/26/2011		22		\$0.00
Medium	Work In Progress	118		9/26/2011 10:27:16 AM				ψ0.00
,	on an rogicas			NEEDS TO HAVE THE				
Maribel Cha	avez							^ -
78761	=	Classroom		9/26/2011		22		\$0.00
Medium	Work In Progress	143		9/26/2011 10:27:41 AM				
Sotelo, Enr Maribel Cha		RM#143- MARTH REST OF WIRING		EEDS TO HAVE THE ONE				
79725	av c 2			10/13/2011		5		\$0.00
Medium	Work In Progress			10/13/2011 9:09:12 AM				
Carbajal, Ji	mmy	VACCUM TIRE F		DS CAP TO HOLD BRING IT IN				

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By Location Area Deferred By Under Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino E	S					
79796			10/17/2011		1		\$0.00
Medium	Work In Progress		10/17/2011 6:54:35 AM				
Carbajal, J	limmy	VACCUM TIRE FELL OFF OTHER ON	E 06C00000042				
Jimmy Cor	rtez						
74948			7/4/2011	7/24/2011	106		\$0.00
Medium	Work In Progress		7/4/2011 12:21:46 AM				
Orozco, Da		Monthly - Berino ES Fire Sprinkler Insp schedule details.		PENDING AS PER MG	REPORT	9/23/2011	
Margret Vi 79303	llalobos		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:32 AM	. 6/26/20	.0		ψ0.00
Orozco, Da	· ·	Monthly - Berino ES Fire Sprinkler Insp schedule details.					
Margret Vi	llalobos						
79815			10/17/2011		1		\$0.00
Medium	Work In Progress	SPED OFFICE	10/17/2011 10:12:47				
Briones, E	nrique	PO #101108760 PICK UP ONE BOX DELIVER TO SHAUNA TORRESTEACHER-BERIN ELEMENTARY	0				
Margaret \	/illalobos		40/47/2044		4		<u>ФО ОО</u>
79844			10/17/2011		1		\$0.00
Medium	Work In Progress		10/17/2011 12:43:31				
Sitters, Ma	ary	DUMPSTERS NEED TO GET WASHE	D.				
Maritza Go	onzalez		40/44/0044				00.00
79769			10/14/2011		4		\$0.00
Medium	Work In Progress		10/14/2011 11:41:50				
Munoz, Mi	chael	NEED TO SPRAY FOR FLIES IN THE DINING AREA. CLOSED DOWN DUE INSPECTION. O.K. TO SPRAY AS PE MUNOZ. FAXED TO WATSON/ SPOK AND HE WILL BE THERE BY 3:00 P.M.	TO STATE R MIKE E TO MIKIE				
Michael M	unoz	Orfotorio	40/47/0044				# 0.00
79864		Cafeteria	10/17/2011		1		\$0.00
High	Work In Progress		10/17/2011 3:38:03 PM				
Villalobos,	Margret	purchase vector plasma fly light for fly oinspector.	control. as per				

10/18/2011 1:23:06 PM Page 9 of 172

Michael Munoz

WOID	Building	•	Intil Request Date Ta	arget Comp Date	Days Aged	Labor Hours	Costs
Priority	Status	Area Number Reason	Created Date/Time A	Action Taken	Agou	Hours	
Assigned [•] Requester		Description		Action Taken			
Location:	Berino E						
	Derillo L		10/2/2011	10/10/2011	16		\$0.00
79235	Madala Dassassas			10/10/2011	10		φυ.υυ
Medium	Work In Progress		10/2/2011 12:27:54 AM				
Duran, Ada		Monthly - Berino ES Emer. Light Test: I PM schedule details.	Monthly - Refer to				
Margret Vil 79236	llalobos		10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:54 AM				
Duran, Ada	-	Monthly - Berino ES - Clothes Dryer (M PM schedule details.	onthly) - Refer to				
Margret Vi	llalobos		10/0/00				
79504			10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress		10/9/2011 12:16:27 AM				
Duran, Ada		Monthly - Berino ES Monthly Playgroun PM schedule details.	d Insp Refer to				
Margret Vil 79253	llalobos		10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:04 AM				
Sanchez, F	· ·	Monthly - Berino ES - Monthly Meter Ro PM schedule details.	eadings - Refer to				
Margret Vi	llalobos		10/0/00	12/2/22			
79267			10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:12 AM				
Duran, Ada		Monthly - Berino ES Monthly FE Inpsec PM schedule details.	tion - Refer to				
Margret Vil 79285	llalobos		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:22 AM	10/20/2011	10		φυ.σσ
	_	Marathle Barine FO Barana Hand Olana					
Orozco, Da	anny	Monthly - Berino ES Range Hood Clear PM schedule details.	ning - Refer to				
Margret Vi	llalobos		10/0/00				
79136			10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:26:55 AM				
Duran, Ada		Yearly - Berino ES I4 (Fan Coil)(Yearly schedule details.) - Refer to PM				
Margret Vil 79137	llalobos		10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:26:55 AM	· · · _ · _ · · ·	. =		,
	-	Vearly - Berino ES H6 (Europea Goo)(V					
Duran, Ada	वा।	Yearly - Berino ES H6 (Furnace Gas)(Y PM schedule details.	earry) - Neier 10				
	llalobos						

10/18/2011 1:23:06 PM Page 10 of 172

WOID	Building	•	=	arget Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason Created	Date/Time A	ctual Comp Date	Aged	Hours	
Assigned	То	Description		Action Taken			
Requester	r Name						
Location:	Berino E	S					
79138			10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 1	12:26:56 AM				
Duran, Ad	an	Yearly - Berino ES U2 (Heat Gas)(Yearly) - Refer to schedule details.	PM				
Margret Vi	illalobos		10/0/0011	10/10/0011			40.00
79139			10/2/2011	10/18/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 1	12:26:56 AM				
Duran, Ad	an	Monthly - Berino ES A1 (Wall Ref. E/H)(S.Annual) - Refer to PM schedule details.					
Margret Vi 79150	illalobos		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 1	12:27:02 AM				*
Duran, Ad	_	Monthly - Berino ES Roof Inspection - Refer to PM schedule details.					
Margret Vi	illalobos						
79234			10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 1	12:27:53 AM				
Duran, Ad	an	Monthly - Berino ES Exit Sign Insp: Monthly - Refer t PM schedule details.	to				
Margret Vi	illalobos		40/44/0044		7		Φο οσ
79614			10/11/2011		7		\$0.00
Medium	Work In Progress	10/11/2011	9:44:27 AM				
Sotelo, En	rique	MR ENRIQUE SOTELO SIR THE WALL OUTLETS LIBRARY NORTH WALL HAVE NO POWER CHECK BRAKERS OK THANK YOU SIR AND GOD BLESS	K				
Adan Dura	an		9/29/2011		19		\$0.00
78989		2/22/22/			19		φυ.υυ
Medium	Work In Progress	9/29/2011	3:26:44 PM				
Lozoya, M	anny	MR MANNY LOZYOA SIR NEED 2 LOCKS TO LOC MAIN ELETRICAL BOX OUT SIDE KITCHEN HIGH VOTAGE NEED TO LOCK THANK YOU SIR AND G BLESS B-1 WILL BE OK					
Adan Dura	an						A-
79450			10/6/2011		12		\$0.00
Medium	Work In Progress	10/6/2011	1:10:18 PM				
Lozoya, M	anny	MR MANNY LOZOYA SIR NEED TO RE-KEY DOOF TO ELISA'S OFFICE THANK YOU SIR AND GOD BLESS	२				

10/18/2011 1:23:06 PM Page 11 of 172

Adan Duran

WOID Priority Assigned ⁻ Requester		Area Deferred By Area Number Reason Description	Until Request Date Target Comp Dat Created Date/Time Actual Comp Dat Action Taker	e Aged	Labor Hours	
Location:	Berino E	 S				
78317		Cafeteria	9/14/2011	34		\$0.00
Medium	Work In Progress		9/14/2011 9:48:15 AM			
Moncayo, I	Fernando	REACH IN REFRIG. TEMP IS AT	45 AND GOING UP.			
		ELSA C SNP MGR 882-2417				
Jacqueline 79843	Aguilar		10/17/2011	1		\$0.00
Medium	Work In Progress		10/17/2011 12:41:43			ψ0.00
Orozco, Da	_	CHECK REFRIGERATION (WALL COOLER. SNP MANAGER ELSA	K IN AND MILK			
Maritza Go	onzalez		9/30/2011	18		ФО ОО
79008	W 11 D			18		\$0.00
Medium	Work In Progress		9/30/2011 12:22:29 AM			
Duran, Ada		Monthly - Berino ES A16 (Fan Ext PM schedule details.	n.)(S.Annual) - Refer to			
Margret Vil 78762	llalobos	Classroom	9/26/2011	22		\$0.00
Medium	Work In Progress	113	9/26/2011 10:28:06 AM			
Sotelo, Eni	rique	RM#113- SHAUNA TORRES- NE REST OF WIRING /CABLING DO				
Maribel Ch	avez					
78763		Classroom	9/26/2011	22		\$0.00
Medium	Work In Progress	127	9/26/2011 10:28:57 AM			
Sotelo, Eni	•	RM#127- SANDI HINOJOS-NEED REST OF WIRING /CABLING DO				
Maribel Ch 78764	navez	Classroom	9/26/2011	22		\$0.00
Medium	Work In Progress	142	9/26/2011 10:29:24 AM			φ0.00
Sotelo, Eni	-	RM#142- VERONICA BAUTISTA- THE REST OF WIRING /CABLIN	NEEDS TO HAVE			
Maribel Ch	navez					
78765		Classroom	9/26/2011	22		\$0.00
Medium	Work In Progress	106	9/26/2011 10:32:27 AM			
Sotelo, Eni	rique	RM#106 - IRMA SANCHEZ - NEE REST OF WIRING /CABLING DO				
Maribel Ch 78960	navez Main Building	Portables	9/29/2011	19		\$0.00
	_	ו טונמטוכט		19		ψυ.υυ
Medium	Work In Progress		9/29/2011 7:48:50 AM			
Sotelo, En	•	Run power supply to portable, a n will be install. 208/230 1 phase.	ew refrigeration unit			
Lorenzo So	olis					

GOD BLESS

Total Selected Date Range for Request Dates:7/1/2011 - 6/30/2012 Order By Location, Status Costs WOID Building Area **Deferred By** Until **Request Date Target Comp Date** Days Labor Aged Hours **Status** Area Number Reason Created Date/Time Actual Comp Date **Priority** Description **Action Taken Assigned To Requester Name Berino ES** Location: 79353 10/4/2011 14 \$0.00 Medium Work In Progress 10/4/2011 7:32:46 AM Sotelo, Enrique MR ENRIQUE SOTELO SIR THE LIGHT SWITCH IS MENS RESTROOM WEST SIDE NEEDS TO BE REPLACE NOT WORKING THANK YOU SIR AND

Adan Duran

Count: 38 Work Orders Avg. Age of WO's 17 Total for Berino ES 0 \$0.00

10/18/2011 1:23:06 PM Page 13 of 172

		0.0.0		(Tota
Selected Da WOID	ate Range for Request Building	Dates:7/1/2011 - Area	6/30/2012 Order By L Deferred By	•				Costs
Priority	Status	Area Number	Reason	Cre	ated Date/Time Actual Comp	Date Age	d Hours	
Assigned	То	Description			Action T	aken		
Requeste	r Name							
Location:	Chaparra	al Elem East Pre	e-K					
75620					7/21/2011	89		\$0.00
Medium	Work In Progress			7/21/	2011 8:16:14 AM			
Estrada, J	lesus		s to be replaced, loos ortable (69 DM1R) (ou.					
Guillermo	Hernandez							
75619					7/21/2011	89		\$0.00
Medium	Work In Progress			7/21/	2011 8:09:39 AM			
Estrada, J	lesus		s to be replaced, loc MIR) Classroom P #					
Guillermo	Hernandez							
Count: 2 \	Work Orders	Α	vg. Age of WO's	89	Total for Chaparral Elem	East Pre-K	0	\$0.00

10/18/2011 1:23:06 PM Page 14 of 172

WOID	Building	Area Deferred By	Until Request Date Targe	A	Labor Hours	
Priority	Status	Area Number Reason	Created Date/Time Actua	ai comp bate	Hours	
Assigned		Description	•	Action Taken		
Requeste						
Location:	Chaparra	II ES				
77520			8/29/2011	50		\$0.00
Medium	Work In Progress		8/29/2011 1:54:15 PM			
Ontiveros,	, Joe	Need to replace rusted plugs on the hallway. Thank yuo	ne sinks in kinder			
	Hernandez		10/11/0011	_		**
79619		Classroom	10/11/2011	7		\$0.00
Medium	Work In Progress	106	10/11/2011 12:01:16			
Sotelo, En	nrique	need to install electrical outlet for through ceiling. see Moreno	SPED projector			
<u>Jennifer C</u> 79620	Corral	Classroom	10/11/2011	7		\$0.00
				,		φυ.υυ
Medium	Work In Progress	107	10/11/2011 12:01:36			
Sotelo, En	·	need to install electrical outlet for through ceiling. see Quinn	SPED projector			
<u>Jennifer C</u> 79621	Corral	Classroom	10/11/2011	7		\$0.00
Medium	Work In Progress	418	10/11/2011 12:01:41	·		******
Sotelo, Er	_	need to install electrical outlet for through ceiling. see West				
Jennifer C	Corral					
79622		Classroom	10/11/2011	7		\$0.00
Medium	Work In Progress	301	10/11/2011 12:01:46			
Sotelo, En	rique	need to install electrical outlet for through ceiling. see Casares	SPED projector			
Jennifer C	orral		40/44/0044			# 0.00
79623		Classroom	10/11/2011	7		\$0.00
Medium	Work In Progress	211	10/11/2011 12:01:51			
Sotelo, En	nrique	need to install electrical outlet for through ceiling. see Sang	SPED projector			
Jennifer C		Office	9/45/2044	64		ቀለ ለለ
76920	Main Building	Office	8/15/2011	64		\$0.00
Medium	Work In Progress	office	8/15/2011 9:34:06 AM			
Lozoya, M	lanny	need extra N key for front office for See Front office	or Administrative Intern.			
Jennifer C	Corral					

10/18/2011 1:23:06 PM Page 15 of 172

WOID	Building	Area	Deferred By		arget Comp Date	Days Aged	Labor Hours	
Priority	Status	Area Number	Reason	Created Date/Time A	•	Ageu	Hours	
Assigned 1 Requester		Description			Action Taken			
Location:	Chaparra	IES						
78829				9/27/2011		21		\$0.00
Medium	Work In Progress			9/27/2011 9:39:21 AM				
Quinones,		will need every at Chaparral H October 3, 201 before monday	thing to be move igh School no sor 1 if you need to s please talk to Eld uld be in the new	s it is a lot of things we to the new PreK facility nner than Monday tart moving things odia Salinas 824-5382 facility in order to start				
Lucia Alme	eraz			9/29/2011		19		\$0.00
	Work In Progress			9/29/2011 3:49:33 PM		10		ψ0.00
High	· ·							
Lozoya, Ma	anny	Need to ck all a	automatic door op	eners at site.				
Michael Mu 79461	ınoz			10/6/2011		12		\$0.00
						12		φυ.υυ
Medium	Work In Progress			10/6/2011 3:44:05 PM				
Flores, Pet		REQUESTING RUPTURED	NEW TIRE FOR	WORK TRUCK,TIRE				
Paul Quino 79190	nes			10/2/2011		16		\$0.00
Medium	Work In Progress			10/2/2011 12:27:27 AM				,
Quinones,	· ·	Monthly - Chap Refer to PM sc		s Dryer (Monthly) -				
Margret Vil	lalobos							
79191				10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:27:28 AM				
Quinones,	Paul	Monthly - Chap to PM schedule		n Insp: Monthly - Refer				
Margret Vil	lalobos			10/9/2011	10/25/2011	9		\$0.00
79534	W 11 B				10/25/2011	9		φυ.υυ
Medium	Work In Progress			10/9/2011 12:16:42 AM				
Quinones,		Monthly - Chap schedule detail		und Insp - Refer to PM				
Margret Vil 79260	lalobos			10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:28:08 AM	. 5/5/2011	. •		ψ3.00
	-		150					
Quinones,	Paul	Monthly - Chap PM schedule d		FE Inpsection - Refer to				

10/18/2011 1:23:06 PM Page 16 of 172

Priority Assigned [:] Requester		Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time Ac Description	-	Days Aged	Labor Hours	
Location:	Chaparra	IES				
79286		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:23 AM				
Orozco, Da	anny	Monthly - Chapparal ES Range Hood Cleaning - Refer to PM schedule details.				
Margret Vil 79310	llalobos	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:35 AM	19, 19, 29 11	. •		ψ0.00
Quinones,	· ·	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vil	llalobos	40/44/0044				Ф0.00
79608		10/11/2011		7		\$0.00
Medium	Work In Progress	10/11/2011 8:34:58 AM				
Quinones,	Paul	REQUESTING 15 GALLON SPRAYER,FOR WEED CONTROL FOR ALL 3 SCHOOLS CH E, CH.M,AND D.T.				
Paul Quino	ones	9/20/2011		28		\$0.00
78543	Model to Drawna			20		φυ.υυ
Medium Carrasco,	Work In Progress Danny	9/20/2011 11:09:00 AM NEED 10 GAL OF DIESEL FOR MOWER #403,AND 1 GAL OF GAS FOR 2 STROKE BLOWER,AND WEEDEATER				
Paul Quinc	ones					
77452		8/25/2011		54		\$0.00
Medium	Work In Progress	8/25/2011 4:01:01 PM				
Ontiveros,	Guadalupe	Need to replace irrigation valve on the field. Thank you				
Guillermo I 79125	Hernandez	10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:49 AM	11/2/2011	10		ψ0.00
Quinones,	_	Yearly - Chaparral ES H-6 Furnance Gas (Yearly) - Refer to PM schedule details.				
Margret Vil	llalobos					
79512		10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:31 AM				
Ramirez, D		Monthly - QRTLY BLDG INSP REPORT (CE) - Refer to PM schedule details.				
N 4 () (')	lialobos	10/2/2011	10/10/2011	16		\$0.00
Margret Vil 79154						
79154	Work In Progress	10/2/2011 12:27:05 AM				
	-	10/2/2011 12:27:05 AM Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.				

WOID Priority	Building Status	Area Deferred By Area Number Reason	Until Request Date Target Comp Date Created Date/Time Actual Comp Date	AI	Labor Hours	
Assigned [·]		Description Neason	Action Taken	_		
Requester						
Location:	Chaparra	I ES				
79722	•		10/13/2011	5		\$0.00
Medium	Work In Progress		10/13/2011 8:36:18 AM			·
Ronquillo,	· ·	REQUESTING PBV FIBERGLAS FRONT OF SCHOOL SPRINKLE FOR THE WINTER SEASON.ME 16"WX24"HX32"L	R SYSTEM.NEEDED			
Paul Quino 76819	ones		8/11/2011	68		\$0.00
Medium	Work In Progress		8/11/2011 11:56:43 AM	00		ψ0.00
Flores, Pet	_	Truck #155 CHE, shifting lever is light for the anti-lock brakes in on, nocking sound when pressing the Thank you	stock on park and the , also truck is making a			
Guillermo I 77180	Hernandez		8/19/2011	60		\$0.00
Medium	Work In Progress		8/19/2011 3:41:04 PM			φ0.00
Flores, Pet	-	Need to replace front tires to mow dry and cracked. Size 23 x 10.50	ver #0403. Tires are			
	Hernandez		•			
75207			7/7/2011	103		\$0.00
Medium	Work In Progress		7/7/2011 3:13:13 PM			
Orozco, Da	anny	1.Electrical cord hanging from the encased in a power pole. Safety H 2.Air vent right above the steam li with paint chips loose. It poses a contaminating food.	Hazard ine is in poor condition			
Maritza Go	nzalez		7/25/2011	85		\$0.00
75779 Medium	Work In Progress		7/25/2011 1:21:24 PM	03		ψ0.00
Orozco, Da	Work In Progress anny	Chemical room wall needs to be r falling apart SNP Manager Esth	replace with RFP, it is			
Maritza Go	nzalez	Tailing apart Sive Manager Estit	ei C. 824.0048			
79322	TILLATOL		10/3/2011	15		\$0.00
Medium	Work In Progress		10/3/2011 10:38:39 AM			
Orozco, Da	anny	SKILLET GOES OUT ALL OF A S MANGER ESTHER C. 824.0048	SUDDEN. SNP			
Maritza Go	nzalez	Classroom	10/11/2011	7		\$0.00
79624	Work In Drogram			1		φυ.υυ
Medium	Work In Progress	208	10/11/2011 12:01:55			
Sotelo, En	rique	need to install electrical outlet for through ceiling. see Cordero	SPED projector			

10/18/2011 1:23:06 PM Page 18 of 172

Selected Da	ate Range for Request Building	Dates:7/1/2011 - Area	6/30/2012 Order By L Deferred By	*	Target Comp Date	Days	Labor	Total Costs
Priority	Status	Area Number	•	Created Date/Time	•	Aged	Hours	
Assigned		Description			Action Taken			
Requester		•						
Location:	Chaparra	I ES						
79625		Classroom		10/11/2011		7		\$0.00
Medium	Work In Progress	207		10/11/2011 12:01:59				
Sotelo, En	rique	need to install through ceiling	electrical outlet for \$. see Fort	SPED projector				
Jennifer C	orral	01		40/44/0044				Φο οο
79626		Classroom		10/11/2011		7		\$0.00
Medium	Work In Progress	IEP rm		10/11/2011 12:02:03				
Sotelo, En	rique		electrical outlet for \$. see Front office/D					
Jennifer C								
76918	Main Building	Classroom		8/15/2011		64		\$0.00
Medium	Work In Progress	107		8/15/2011 9:32:45 AM				
Lozoya, M	anny	need extra key	for room 107. see	front office				
Jennifer C	orral							
78488				9/19/2011		29		\$0.00
Medium	Work In Progress			9/19/2011 8:38:15 AM				
Lozoya, M	anny	Need to issue site.	keys to Paul Quinio	nes transferring to this				
Margret Vi 75919	llalobos			7/27/2011		83		\$0.00
Medium	Work In Progress			7/27/2011 3:55:26 PM				7
	Guadalupe	at Chaparral E		p of the irrigation tank tu turn on the buster				
	Hernandez	•						
Count: 34	Work Orders	Α	vg. Age of WO's	28	Total for Chaparra	al ES	0	\$0.00

10/18/2011 1:23:06 PM Page 19 of 172

Page 20 of 172

1200 - Work Orders In Progress (Fiscal Year)

10/18/2011 1:23:06 PM

Total Selected Date Range for Request Dates:7/1/2011 - 6/30/2012 Order By Location, Status Costs WOID Building Until **Request Date Target Comp Date** Labor Area **Deferred By Davs** Aged Hours Created Date/Time Actual Comp Date **Status Priority** Area Number Reason Description **Action Taken** Assigned To Requester Name **Chaparral HS** Location: 7/11/2011 99 \$0.00 75288 Medium Work In Progress 7/11/2011 11:37:19 AM SCIENCE CLASS RM. D-7 WATER FAUCETS IN Ontiveros, Joe CLASS RM. NEED TO BE REPLACED. IF YOU CAN BEFORE SCHOOL STARTS ON AUG.4 Paul Quinones 75289 7/11/2011 99 \$0.00 Medium Work In Progress 7/11/2011 11:43:22 AM Ontiveros, Joe WE NEED TO CHK ISIMET CONTROLS IN ALL SCIENCE CLASS RMS SO THAT THE SOLINOID VALVES CAN BE REPLACED. AND CHK ALL SCIENCE CLASS RMS. THAT DO NOT HAVE HOT AND COLD DOMESTIC WATER IN CLASS RM. Paul Quinones 8/23/2011 77278 56 \$0.00 Medium Work In Progress **Bus Lane** 8/23/2011 2:11:32 PM Appelzoller, Fred Need Line Locate / Whole Bus Lane from East to West and along the west end fence from the North End of property to the South End of property. If you have any questions please contact Richard Borrego (Gas Co.) at (575) 642-1540 Peggy Jo Hernandez 9/9/2011 39 \$0.00 78133 Medium Work In Progress 9/9/2011 3:36:05 PM TWO PLUMBING CLEAN OUTS ARE BROKEN Ontiveros, Joe INBETWEEN C,AND D WINGS,AND E WINGS Paul Quinones Field House Choral 9/27/2011 21 \$0.00 78844 Medium Work In Progress 9/27/2011 12:43:01 PM Ontiveros, Joe missing water vale cover cast-iron cap Alfredo Ortiz E-Wing 10/17/2011 1 \$0.00 79797 Medium Work In Progress 10/17/2011 7:29:08 AM need to replace fauset in staff restroom it is broken Ontiveros, Joe Alfredo Ortiz 10/10/2011 8 \$0.00 79544 Medium Work In Progress 10/10/2011 6:23:49 AM AUTO SCRUBBER SR 8000062994 SCRUBBING Carbajal, Jimmy BRUSH IN FRONT NOT TURNING. Jesus Urquidi

WOID	Building	Dates:7/1/2011 - 6/30/2012 Ord Area Deferred B	y Until Request Date Target Comp D	A	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time Actual Comp D		Hours	
Assigned		Description	Action Tak	en		
Requeste	r Name					
Location:	Chaparra	al HS				
79823	Field House	Mechanical	10/17/2011	1		\$0.00
Medium	Work In Progress		10/17/2011 10:24:49			
Solis, Lore	enzo	need to install PVC vent-pipe	e on heater			
Alfredo Or						
79824	A-Wing	Office	10/17/2011	1		\$0.00
Medium	Work In Progress		10/17/2011 10:28:25			
Solis, Lore	enzo	need to replace low-temp se	ensor			
<u>Alfredo Or</u> 79825	r <u>tiz</u> B-Wing	Classroom	10/17/2011	1		\$0.00
Medium	Work In Progress	Oldooroom	10/17/2011 10:30:38	•		ψ0.00
Solis, Lore	_	compresor not working	10/1//2011 10.30.30			
Alfredo Or		compressi not working				
79827	A-Wing	Hallway/Corridor	10/17/2011	1		\$0.00
Medium	Work In Progress		10/17/2011 10:32:54			
Solis, Lore	enzo	AC-unit low on refrigerant				
Alfredo Or	rtiz					
78178			9/12/2011	36		\$0.00
Medium	Work In Progress		9/12/2011 8:46:48 AM			
Quinones,	, Paul	NEED TO INSTALL 4"WALI R-BLDG.	L VENT IN ART CLASS RM.			
Paul Quin 79543	ones		10/10/2011	8		\$0.00
Medium	Work In Progress		10/10/2011 6:20:46 AM	O		ψ0.00
	· ·					
Flores, Pe		CHARGER SR 09-89 TO GO	OLF CART NOT WORKING			
<u>Jesus Urq</u> 79382	ıuıdı A-Wing	Office	10/4/2011	14		\$0.00
Medium	Work In Progress	KAREN	10/4/2011 3:34:44 PM			
Briones, E	_	PLEASE DELIVER THE FO KAREN NOUGUES	LLOWING ITEMS TO:			
		PO # 111201083 - 4 BOXES - CHS BOYS BASKETBALL				
Terry Alva 79402	ırado		10/5/2011	13		\$0.00
Medium	Work In Progress		10/5/2011 7:58:17 AM	10		ψυ.υυ
Briones, E	_	On October 5, 2011, please adoption textbooks and 5 en pallets has cardboard on it.	pick-up 9 boxes of out-of-			
Yolie Jaco	quez	panoto nao oaraboara orrit.				
10/10/004	11 1:23:06 PM					1 of 172
10/10/201						

10/18/2011 1:23:06 PM Page 21 of 172

WOID Priority Assigned ¹ Requester		Area Deferred By Area Number Reason Description	Until Request Date Target Comp Created Date/Time Actual Comp Action Ta	Date Aged	Labor Hours	Costs
Location:	Chaparra	I HS				
79820			10/17/2011	1		\$0.00
Medium	Work In Progress	SPED OFFICE	10/17/2011 10:21:15			
Briones, Er	nrique	PO #101108760 PICK UP ONE BOX DELIVER TO MR. WALMANTEACHER CHAP SCHOOL				
Margaret V 79821	'illalobos		10/17/2011	1		\$0.00
Medium	Work In Progress	SPED OFFICE	10/17/2011 10:22:16			*****
Briones, Er	-	PO #101108760 PICK UP ONE BOX DELIVER TO JOSE SOSA-PROVENCIOTEACHIGH SCHOOL				
Margaret V 79887	<u>′illalobos</u> A-Wing	Office	10/18/2011	0		\$0.00
Medium	Work In Progress	KAREN	10/18/2011 8:14:49 AM	-		*****
Briones, Er	-	PLEASE DELIVER THE FOLLOV KAREN NOUGUES				
		PO #111202308 - 1BOX (MEDIC TRAINER	AL SUPPLIES) - CHS			
<u>Terry Alvar</u> 77347	ado A-Wing	Classroom	8/24/2011	55		\$0.00
Medium	Work In Progress	a 106	8/24/2011 2:38:26 PM	00		Ψ0.00
Solis, Lore	Ü	Room is really cold and my therm (donna Heddleston				
Diana Men	doza		9/30/2011	18		\$0.00
79041	Morte In Drawnag	DDE V		10		φυ.υυ
Medium Carrasco, I	Work In Progress Danny	PRE - K Need to assemble furniture at new (Sal and Danny C. will assist start 2011)				
Michael Mu	ınoz		10/18/2011	0		\$0.00
79894 Medium	Work In Progress	PREK office	10/18/2011 10:13:35	U		ψυ.υυ
Ortiz, Alfre	· ·	Please move 12 pieces of furnitur to La Mesa PreK				
Lucia Alme	eraz					
79045			9/30/2011	18		\$0.00
Medium	Work In Progress		9/30/2011 2:44:11 PM			
Briones, Er	nrique	On October 5, 2011, please delive Studies material to Chaparral Hig				
Yolie Jacqı	uez	. 3				

10/18/2011 1:23:06 PM Page 22 of 172

Page 23 of 172

1200 - Work Orders In Progress (Fiscal Year)

10/18/2011 1:23:06 PM

Total Selected Date Range for Request Dates:7/1/2011 - 6/30/2012 Order By Location, Status Costs WOID Building Until **Request Date Target Comp Date** Labor Area **Deferred By Davs** Aged Hours Created Date/Time Actual Comp Date **Status Priority** Area Number Reason Description **Action Taken** Assigned To Requester Name Chaparral HS Location: A-Wing Office 10/4/2011 14 \$0.00 79378 Medium Work In Progress KAREN 10/4/2011 3:30:15 PM Briones, Enrique PLEASE DELIVER THE FOLLOWING ITEMS TO: KAREN NOUGUES PO# 111201998 - 1BOX (UNIFORM/SOCKS) CHS JV **BOYS SOCCER** SOCKS FOR VARSITY BOYS UNIFORM FOR JV BOYS Terry Alvarado Office 10/4/2011 14 \$0.00 79379 A-Wing Medium Work In Progress KAREN 10/4/2011 3:32:07 PM Briones, Enrique PLEASE DELIVER THE FOLLOWING ITEMS TO: KAREN NOUGUES PO # 111200126 - 2 BOX (GIRLS BASKETBALL SUPPLIES) - CHS GIRLS BASKETBALL PO # 111200125 - 3 BOXES (GIRLS BBKT SUPPLIES) - CHS GIRLS BASKETBALL Terry Alvarado A-Wing Office 10/4/2011 14 \$0.00 79380 Medium Work In Progress **KAREN** 10/4/2011 3:33:33 PM PLEASE DELIVER THE FOLLOWING ITEMS TO: Briones, Enrique KAREN NOUGUES PO # 111200139 - 4BOXES (SOFTBALL SUPPLIES) -**CHS SOFTBALL** Terry Alvarado 75055 7/4/2011 106 \$0.00 Medium Work In Progress 7/4/2011 12:22:33 AM Quinones, Paul Monthly - Chaparral HS Emer. Light Test: Monthly -Refer to PM schedule details. Margret Villalobos 7/31/2011 79 \$0.00 76133 Medium Work In Progress 7/31/2011 9:25:19 AM Monthly - Chaparral HS Emer. Light Test: Monthly -Quinones, Paul Refer to PM schedule details. Margret Villalobos 9/4/2011 44 \$0.00 77903 9/4/2011 12:24:42 AM Medium Work In Progress Monthly - Chaparral HS Emer. Light Test: Monthly -Quinones, Paul Refer to PM schedule details. Margret Villalobos

WOID	Building	Area Deferred By	= = = = = = = = = = = = = = = = = = =	Target Comp Date	Days Aged	Labor Hours	
Priority	Status -	Area Number Reason	Created Date/Time A	-	Ageu	nours	
Assigned [*]		Description		Action Taken			
Requester	Name						
Location:	Chaparra	I HS					
79309			10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:35 AM				
Ortiz, Alfre	do	Monthly - Chaparral HS Emer. Light Refer to PM schedule details.	Гest: Monthly -				
Margret Vil	llalobos						
77766		Mechanical	9/2/2011		46		\$0.00
High	Work In Progress		9/2/2011 11:05:19 AM				
Sotelo, En	rique	please install emergency shut off swir inspection by inspector gene velasces code(a.s.m.e csd-1) thank you					
Michael Mu 78846	unoz		9/27/2011		21		\$0.00
	W 11 D				21		ψ0.00
Medium	Work In Progress	storage in high	9/27/2011 1:01:22 PM				
Ortiz, Alfre	do	Please move all furniture and materia Chaparral High School to the PreK Please assemble all furniture. The Pr classes on Oct. 10, 2011 all furniture	eK will start				
Lucia Alme	eraz		40/0/0044		4.0		(0,00
79227			10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:48 AM				
Ortiz, Alfre		Monthly - Chaparral HS - Clothes Dry Refer to PM schedule details.	ver (Monthly) -				
Margret Vil 75056	llalobos		7/4/2011		106		\$0.00
	Work In Drogram		7/4/2011 12:22:34 AM		100		ψ0.00
Medium	Work In Progress						
Quinones,		Monthly - Chaparral HS Monthly FE In PM schedule details.	nspection - Refer to				
Margret Vil 76134	lialobos		7/31/2011		79		\$0.00
Medium	Work In Progress		7/31/2011 9:25:20 AM				
Quinones,	ŭ	Monthly - Chaparral HS Monthly FE In PM schedule details.					
Margret Vil	llalobos						
77904			9/4/2011		44		\$0.00
Medium	Work In Progress		9/4/2011 12:24:42 AM				
	Paul	Monthly - Chaparral HS Monthly FE I	nonaction Defer to				

10/18/2011 1:23:06 PM Page 24 of 172

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By Lo Area Deferred By Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	ni HS					
79268			10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:13 AM				
Ortiz, Alfre	do	Monthly - Chaparral HS Monthly FE PM schedule details.	Inspection - Refer to				
Margret Vil	llalobos		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:21 AM	10/20/2011	.0		φο.σσ
Orozco, Da		Monthly - Chaparral HS Range Hoo PM schedule details.					
Margret Vil	llalobos		9/4/2011		44		\$0.00
Medium	Work In Progress		9/4/2011 12:24:43 AM		7-7		ψ0.00
Quinones,	· ·	Monthly - Chaprral HS Exit Sign Ins PM schedule details.					
Margret Vil	llalobos		0/4/0044	40/5/0044	4.4		#0.00
77906			9/4/2011	10/5/2011	44		\$0.00
Medium	Work In Progress		9/4/2011 12:24:43 AM				
Quinones,		Monthly - Chaparral HS Bleacher Ir PM schedule details.	nspection - Refer to				
Margret Vil 78663	Field House		9/22/2011		26		\$0.00
Medium	Work In Progress		9/22/2011 10:26:46 AM				
Holguin, Al	lfredo	Collect Equipment data and inventor requirements.	ory per PFSA				
Alfredo Ho	lguin		10/2/2011		16		\$0.00
79238	Model to Dronnes				10		φ0.00
Medium Holguin, Al	Work In Progress	Monthly - Chaparral HS - Fire Pum	10/2/2011 12:27:56 AM p PM (Quarterly) -				
Margret Vil	llalobos	Refer to PM schedule details.					
79232			10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:52 AM				
Ortiz, Alfre	do	Monthly - Chaparral HS Bleacher Ir PM schedule details.	nspection - Refer to				
Margret Vil 79233	llalobos		10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:53 AM		10		ψυ.υυ
Ortiz, Alfre		Monthly - Chaprral HS Exit Sign Ins					
Margret Vil	llalobos	PM schedule details.					

10/18/2011 1:23:06 PM Page 25 of 172

WOID	Building Status O	Dates:7/1/2011 - 6/30/2012 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ad	-	Days Aged	Labor Hours	Costs
Location:	Chaparra	HS					
75057			7/4/2011		106		\$0.00
Medium	Work In Progress		7/4/2011 12:22:34 AM				
Quinones, P	aul	Monthly - Chaprral HS Exit Sign Ins PM schedule details.	p: Monthly - Refer to				
Margret Villa 74913	llobos		7/4/2011		106		\$0.00
	Work In Progress		7/4/2011 12:21:30 AM		100		ψ0.00
Holguin, Alfr	· ·	Monthly - Chaparral HS - Fire Pump Refer to PM schedule details.					
Margret Villa 76131	llobos		7/31/2011		79		\$0.00
	Work In Progress		7/31/2011 9:25:18 AM		73		ψ0.00
Quinones, P	_	Monthly - Chaparral HS - Clothes D Refer to PM schedule details.					
Margret Villa	lobos						
76132			7/31/2011	8/31/2011	79		\$0.00
Medium	Work In Progress		7/31/2011 9:25:19 AM				
Quinones, P		Monthly - Chaparral HS Bleacher In PM schedule details.	spection - Refer to				
Margret Villa 76135	llobos		7/31/2011		79		\$0.00
	Work In Progress		7/31/2011 9:25:20 AM				·
Quinones, P	· ·	Monthly - Chaprral HS Exit Sign Ins PM schedule details.					
Margret Villa	llobos		0/4/0044				40.00
77902			9/4/2011		44		\$0.00
	Work In Progress		9/4/2011 12:24:41 AM				
Quinones, P		Monthly - Chaparral HS - Clothes D Refer to PM schedule details.	ryer (Monthly) -				
Margret Villa 78472	llobos		9/18/2011		30		\$0.00
	Work In Progress		9/18/2011 12:16:58 AM				
Ontiveros, G	· ·	Monthly - Chaparral HS Soil Sampli schedule details.					
Margret Villa	lobos						
79535			10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress		10/9/2011 12:16:43 AM				
Urquidi, Jest	ıs	Monthly - QRTLY BLDG INSP REP PM schedule details.	ORT (CH) - Refer to				

10/18/2011 1:23:06 PM Page 26 of 172

WOID	Building	Area Deferred By Until Request Date Ta	-	Days Aged	Labor Hours	
Priority	Status	Area Number Reason Created Date/Time Ac	tual Comp Date Action Taken	Ageu	nours	
Assigned Requester		Description	Action Taken			
Location:	Chaparra	II LIC				
	Спаратта		7/44/2044	400		#0.00
75058		7/4/2011	7/11/2011	106		\$0.00
Medium	Work In Progress	7/4/2011 12:22:34 AM				
Quinones,		Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.				
Margret Vi 79161	llalobos	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:08 AM	10/10/2011	10		ψ0.00
	-					
Ortiz, Alfre		Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.				
Margret Vi 75053	llalobos	7/4/2011		106		\$0.00
Medium	Work In Progress	7/4/2011 12:22:32 AM				
	-					
Quinones,		Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret Vi 75054	lialobos	7/4/2011	8/3/2011	106		\$0.00
Medium	Work In Progress	7/4/2011 12:22:33 AM				
Quinones,	-	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.				
Margret Vi	llalobos	1 M concede details.				
79065		10/2/2011	10/5/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:16 AM				
Ortiz, Alfre	do	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.				
Margret Vi	llalobos	0.17/0044	0/7/0044	70		Φο οο
76602		8/7/2011	9/7/2011	72		\$0.00
Medium	Work In Progress	8/7/2011 12:16:42 AM				
Quinones,	Paul	Yearly - Chaparral HS A9(Cool Condenser)(Yearly) - Refer to PM schedule details.				
Margret Vi 79020	llalobos	9/30/2011		18		\$0.00
Medium	Work In Progress	9/30/2011 12:22:35 AM		10		φυ.υυ
	· ·					
Ortiz, Alfre		Monthly - Chaparral HS A16 (Fan Exhst.)(S.Annual) - Refer to PM schedule details.				
Margret Vi 79091	llalobos	10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:30 AM				
Ortiz, Alfre	-	Monthly - Chaparral HS H11 (E.Heater)(S.Annual) -				
	llalobos	Refer to PM schedule details.				

10/18/2011 1:23:06 PM Page 27 of 172

Chaparra n Progress	10/2/2011 10/2/2011 12:26:31 AM Yearly - Chaparral HS H6 (Furnace)(Yearly) - Refer to PM schedule details.	11/2/2011	16		\$0.00
n Progress	10/2/2011 10/2/2011 12:26:31 AM Yearly - Chaparral HS H6 (Furnace)(Yearly) - Refer to PM schedule details.	11/2/2011	16		\$0.00
	10/2/2011 12:26:31 AM Yearly - Chaparral HS H6 (Furnace)(Yearly) - Refer to PM schedule details.	11/2/2011	10		Ψ0.00
	Yearly - Chaparral HS H6 (Furnace)(Yearly) - Refer to PM schedule details.				,
n Progress	40/0/2044				
n Progress		44/0/0044	40		Ф0.00
n Progress		11/2/2011	16		\$0.00
	10/2/2011 12:26:31 AM				
	Yearly - Chaparral HS U2 (G.Heater)(Yearly) - Refer to PM schedule details.				
<u> </u>	Restroom (Boys) 10/3/2011		15		\$0.00
n Progress	10/3/2011 7:51:33 AM				
· · · · · · · · · · · · · · · · · · ·	paint the walls over graffity				
	paint the waits over grantly				
	Athletic Field 9/22/2011		26		\$0.00
n Progress	9/22/2011 3:20:42 PM				
	there is a large tree growing beneath the bleachers .please remove before it gets to big and makes it harder to remove. thankyou				
	9/22/2011		26		\$0.00
n Progress	9/22/2011 3:23:17 PM				
3	as per our meeting yesterday. please clean and remove all sand around all curb sides thru-out campus. thankyou				
	7/4/2011	7/6/2011	106		\$0.00
n Progress	7/4/2011 12:22:35 AM	1,6,2011	100		ψ0.00
TT Togress	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.				
	Refer to FW Schedule details.				
	7/31/2011	8/3/2011	79		\$0.00
n Progress	7/31/2011 9:25:21 AM				
	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.				
	0/4/0044	0/7/2044	1 1		<u> </u>
_		9///2011	44		\$0.00
n Progress					
	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.				
		Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details. 9/4/2011 rogress 9/4/2011 12:24:44 AM Monthly - Chaparral HS - Emer. Eyewash (Monthly) -	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details. 9/4/2011 9/7/2011 rogress 9/4/2011 12:24:44 AM Monthly - Chaparral HS - Emer. Eyewash (Monthly) -	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details. 9/4/2011 9/7/2011 44 rogress 9/4/2011 12:24:44 AM Monthly - Chaparral HS - Emer. Eyewash (Monthly) -	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details. 9/4/2011 9/7/2011 44 rogress 9/4/2011 12:24:44 AM Monthly - Chaparral HS - Emer. Eyewash (Monthly) -

10/18/2011 1:23:06 PM Page 28 of 172

Selected Da WOID	Building	Area Deferred By	Until Request Date Target Comp Da		Labor	Costs
Priority	Status _	Area Number Reason	Created Date/Time Actual Comp Da		Hours	
Assigned		Description	Action Take	en		
Requester						
Location:	Chaparra	IHS				
78959		Pump House	9/29/2011	19		\$0.00
Medium	Work In Progress		9/29/2011 7:35:37 AM			
Carrasco,	Danny	need fuel for fire-pump				
<u>Alfredo Or</u> 79641	tiz		10/11/2011	7		\$0.00
Medium	Work In Progress		10/11/2011 3:09:22 PM			
Carrasco,	Danny	need fuel for fire pump and for	blower ,weedaeter			
Alfredo Or	·					
78181			9/12/2011	36		\$0.00
Medium	Work In Progress		9/12/2011 9:28:11 AM			
Orozco, Danny		FIRE PUMP STATION IN MAIN PANEL				
		NEEDS TO BE REPLACED.DU LEAK FROM ROOF IN MECHANICAL RM.BE				
Paul Quind	ones					
78240			9/13/2011	35		\$0.00
Medium	Work In Progress		9/13/2011 8:23:43 AM			
Quinones,		3/4" PVC PIPE FROM JOCKY F REPIPED TO FLOOR DRAIN, F				
Paul Quind 78459	ones		9/16/2011	32		\$0.00
Medium	Work In Progress		9/16/2011 3:51:11 PM			·
Orozco, Da	· ·	TEST FIRE PUMP MANUALY E	NGINE WOULD NOT			
Paul Quind						
79732	D-Wing	Hallway/Corridor	10/13/2011	5		\$0.00
High	Work In Progress		10/13/2011 2:45:28 PM			
Ronquillo,	Ruben	need the scicer-lift to clean the salarm is going off every 3Min.	smoke-detector the fire			
<u>Alfredo Or</u> 79601	tiz		10/11/2011	7		\$0.00
Medium	Work In Progress		10/11/2011 7:51:56 AM	•		ψ0.00
Orozco, Da	· ·	ONE OF THE OVENS IS NOT V	WORKING AT ALL. SNP			
Maritza Go	onzalez		•			
75963			7/28/2011	82		\$0.00
Medium	Work In Progress	all school doors	7/28/2011 11:57:34 AM			
Lozoya, M	anny	check all doors - some need adj wing courtyard - it stays open (p				
		wing countyard - it stays open (p	aui)			

WOID	Building		Deferred By	Until Request Date T	-	Days	Labor	
Priority	Status	Area Number F	Reason	Created Date/Time A	<u>-</u>	Aged	Hours	
Assigned [*]		Description			Action Taken			
Requester	Name							
Location:	Chaparra	II HS						
79840	Pre-K			10/17/2011		1		\$0.00
Medium	Work In Progress			10/17/2011 11:28:38				
Lozoya, Ma	anny	please install a d Paniagua)	oor in rooms 10	1 and102. (Micaela				
Diana Men		A 1'4 '		40/47/0044				# 0.00
79798	A-Wing	Auditorium		10/17/2011		1		\$0.00
Medium	Work In Progress			10/17/2011 7:31:36 AM				
Carrasco,	Danny	need power wasl	ner to clean side	e-walk				
Alfredo Ort	iz							
75960				7/28/2011		82		\$0.00
Medium	Work In Progress	whole school		7/28/2011 11:54:12 AM				
Vargas, Ju	an	check fire extingo (Paul)	uishers - some n	eed pins replaced				
Rosa Quez	ada			9/20/2011		28		\$0.00
78545	Mark In Drawnan					20		φυ.υυ
Medium	Work In Progress			9/20/2011 11:16:08 AM				
Carrasco,	Danny	need fuel for pola	aris gator					
Alfredo Ort	iz	Dootroom (Cirlo)		10/2/2011		15		ድስ ሰብ
79315		Restroom (Girls)		10/3/2011		15		\$0.00
Medium	Work In Progress			10/3/2011 8:08:49 AM				
Ortiz, Alfre	do	need to replace b	oatteries in soom	restrooms				
Alfredo Ort				0/40/0044				Φο οο
78498	B-Wing	Classroom		9/19/2011		11		\$0.00
Medium	Work In Progress	B3		9/19/2011 12:45:59 PM	9/30/2011			
Ortiz, Alfre	do	please install a s	harpener.(Del H	ierro)				
Diana Men	doza							
79373		Cafeteria		10/4/2011		14		\$0.00
Medium	Work In Progress			10/4/2011 2:47:56 PM				
Ortiz, Alfre	do		next to the cafet	nits from Welding room teria and set them up				
Vicky Lope	Z							
79478		Classroom		10/7/2011		11		\$0.00
Medium	Work In Progress	lobo den kitchen		10/7/2011 8:55:43 AM				
Ortiz, Alfre	do	re-locate and ins	tall ty to another	location since it sits				

10/18/2011 1:23:06 PM Page 30 of 172

Priority Assigned [:] Requester		Area Number Reason Description	Created Date/Time Actual Cor Action	np Date Aged Taken	Hours	
Location:	Chaparra	I HS				
79723	A-Wing	Auditorium	10/13/2011	5		\$0.00
Medium	Work In Progress	Additionant	10/13/2011 8:51:33 AM	0		Ψ0.00
Ontiveros,	-	need to install water valve for a w				
Alfredo Ort	tiz		0/44/0044	0.4		Φο οο
78304		Cafeteria	9/14/2011	34		\$0.00
Medium	Work In Progress		9/14/2011 7:28:38 AM			
Moncayo, I		MILK COOLER IS BROKE FROM THE COOLER. WHEN YOU PUT IT ALL FALLS INSIDE THE COO JUANA M. SNP MANAGER 824-	MILK IT TILTS AND LER.			
Jacqueline 76302	<u>Aguilar</u> R-Wing	Classroom	8/2/2011	77		\$0.00
Medium	Work In Progress	kitchen	8/2/2011 9:46:01 AM			,
	_		0/2/2011 3.40.01 / ((v)			
Quinones,		Need TV installed(Adams)				
<u>Diana Men</u> 76625	ndoza	Classroom	8/8/2011	71		\$0.00
Medium	Work In Progress	b-5	8/8/2011 10:24:51 AM			
,		in lieus Paul's absence Adrian Flo smartboard in ms. hady's class	ores needs to install a			
Rosa Quez	zada	Office	8/8/2011	71		\$0.00
76626	W 11 B			71		φυ.υυ
Medium ,	Work In Progress	in paul's absence adrian flores (crinstall door mail holders for all corregistrar and data clerk. (quezada	unselors (4) and			
Rosa Quez 77204	<u>zada</u> I-Wing	Gym	8/22/2011	57		\$0.00
Medium	Work In Progress	GYM	8/22/2011 9:56:31 AM			,
Vargas, Ju	-	THE MAIN BASKETBALL ON TH NOT LOWER ALL THE WAY .(HI	R SOUTH AND WILL			
Diana Men		Oleanne	0/04/0044			Φο οο
77344	A-Wing	Classroom	8/24/2011	55		\$0.00
Medium	Work In Progress	A 110	8/24/2011 2:28:43 PM			
Vargas, Ju	an	Remove a white board so they ca (Encino)	n install a samrt board.			
Diana Men 79027	ndoza	Hallway/Corridor	9/30/2011	18		\$0.00
Medium	Work In Progress	Hallway/OoHlaol	9/30/2011 7:55:08 AM	10		ψ0.00
Ortiz, Alfre	· ·	clean/sweep sand from roof.	-			
J. 112, 7 11116		organia moni 1001.				

10/18/2011 1:23:06 PM Page 31 of 172

Lozoya, Manny Diana Mendoza 75118 Medium Work In Progress Quinones, Paul Alfredo Holguin 75961 A-Wing Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	Area Number Reason Description HS Classroom out side A hall it is hard to open the door with a key (Donna Heddleston) the basketball goal on the south side adjusted 4 inches after wood floor is It is off as per James Stout 575-640- library and art shelves in library and art dept need to Classroom Needs maps mounted on the wall.(Heads in the second state of the	10/17/2011 10/17/2011 11:31:57 If from the inside. 7/5/2011 7/5/2011 1:14:12 PM The needs to be a refinnished. The refinnished. The refinnished of the refinnished of the refinnished of the refinnished. The refinnished of the refinnished. The refinnished of the	Comp Date Aged tion Taken 1 105	\$0.00
Requester Name Location: Chaparral 79841 A-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 75118 Medium Work In Progress Quinones, Paul Alfredo Holguin 75961 A-Wing Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	Classroom out side A hall it is hard to open the door with a key (Donna Heddleston) the basketball goal on the south side adjusted 4 inches after wood floor is It is off as per James Stout 575-640- library and art shelves in library and art dept need to	10/17/2011 10/17/2011 11:31:57 If from the inside. 7/5/2011 7/5/2011 1:14:12 PM The needs to be a refinnished. The refinnished. The refinnished of the refinnished of the refinnished of the refinnished. The refinnished of the refinnished. The refinnished of the	105	\$0.00
Location: Chaparral 79841 A-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 75118 Medium Work In Progress Quinones, Paul Alfredo Holguin 75961 A-Wing Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	Classroom out side A hall it is hard to open the door with a key (Donna Heddleston) the basketball goal on the south side adjusted 4 inches after wood floor is It is off as per James Stout 575-640- library and art shelves in library and art dept need to	10/17/2011 11:31:57 y from the inside. 7/5/2011 7/5/2011 1:14:12 PM e needs to be s refinnished7418 7/28/2011 7/28/2011 7/28/2011 11:55:25 AM to be installed (paul) 8/1/2011 8/1/2011 3:51:25 PM	105 82	\$0.00 \$0.00 \$0.00
79841 A-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 75118 Medium Work In Progress Quinones, Paul Alfredo Holguin 75961 A-Wing Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	Classroom out side A hall it is hard to open the door with a key (Donna Heddleston) the basketball goal on the south side adjusted 4 inches after wood floor is It is off as per James Stout 575-640- library and art shelves in library and art dept need to	10/17/2011 11:31:57 y from the inside. 7/5/2011 7/5/2011 1:14:12 PM e needs to be s refinnished7418 7/28/2011 7/28/2011 7/28/2011 11:55:25 AM to be installed (paul) 8/1/2011 8/1/2011 3:51:25 PM	105 82	\$0.00
Medium Work In Progress Lozoya, Manny Diana Mendoza 75118 Medium Work In Progress Quinones, Paul Alfredo Holguin 75961 A-Wing Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	out side A hall it is hard to open the door with a key (Donna Heddleston) the basketball goal on the south side adjusted 4 inches after wood floor is It is off as per James Stout 575-640- library and art shelves in library and art dept need to	10/17/2011 11:31:57 y from the inside. 7/5/2011 7/5/2011 1:14:12 PM e needs to be s refinnished7418 7/28/2011 7/28/2011 7/28/2011 11:55:25 AM to be installed (paul) 8/1/2011 8/1/2011 3:51:25 PM	105 82	\$0.00
Diana Mendoza 75118 Medium Work In Progress Quinones, Paul Alfredo Holguin 75961 A-Wing Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	it is hard to open the door with a key (Donna Heddleston) the basketball goal on the south side adjusted 4 inches after wood floor is It is off as per James Stout 575-640-library and art shelves in library and art dept need to Classroom	7/5/2011 7/5/2011 1:14:12 PM e needs to be s refinnished7418 7/28/2011 11:55:25 AM to be installed (paul) 8/1/2011 8/1/2011 3:51:25 PM	82	\$0.00
Diana Mendoza 75118 Medium Work In Progress Quinones, Paul Alfredo Holguin 75961 A-Wing Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	(Donna Heddleston) the basketball goal on the south side adjusted 4 inches after wood floor is It is off as per James Stout 575-640-library and art shelves in library and art dept need to Classroom	7/5/2011 7/5/2011 1:14:12 PM e needs to be s refinnished7418 7/28/2011 7/28/2011 11:55:25 AM to be installed (paul) 8/1/2011 8/1/2011 3:51:25 PM	82	\$0.00
75118 Medium Work In Progress Quinones, Paul Alfredo Holguin 75961 A-Wing Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	adjusted 4 inches after wood floor is It is off as per James Stout 575-640-library and art shelves in library and art dept need for Classroom	7/5/2011 1:14:12 PM e needs to be s refinnished7418 7/28/2011 7/28/2011 11:55:25 AM to be installed (paul) 8/1/2011 8/1/2011 3:51:25 PM	82	\$0.00
Medium Work In Progress Quinones, Paul Alfredo Holguin 75961 A-Wing Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	adjusted 4 inches after wood floor is It is off as per James Stout 575-640-library and art shelves in library and art dept need for Classroom	7/5/2011 1:14:12 PM e needs to be s refinnished7418 7/28/2011 7/28/2011 11:55:25 AM to be installed (paul) 8/1/2011 8/1/2011 3:51:25 PM	82	\$0.00
Alfredo Holguin 75961 A-Wing Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	adjusted 4 inches after wood floor is It is off as per James Stout 575-640-library and art shelves in library and art dept need for Classroom	re needs to be serfinnished7418 7/28/2011 7/28/2011 11:55:25 AM to be installed (paul) 8/1/2011 8/1/2011 3:51:25 PM		
Alfredo Holguin 75961 A-Wing Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	adjusted 4 inches after wood floor is It is off as per James Stout 575-640-library and art shelves in library and art dept need for Classroom	7/28/2011 7/28/2011 11:55:25 AM to be installed (paul) 8/1/2011 8/1/2011 3:51:25 PM		
Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	shelves in library and art dept need to	7/28/2011 11:55:25 AM to be installed (paul) 8/1/2011 8/1/2011 3:51:25 PM		
Medium Work In Progress Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	shelves in library and art dept need to	7/28/2011 11:55:25 AM to be installed (paul) 8/1/2011 8/1/2011 3:51:25 PM		
Vargas, Juan Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	shelves in library and art dept need to	8/1/2011 8/1/2011 3:51:25 PM	78	\$0.00
Rosa Quezada 76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	Classroom	8/1/2011 8/1/2011 3:51:25 PM	78	\$0.00
76212 D-Wing Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza		8/1/2011 3:51:25 PM	78	\$0.00
Medium Work In Progress Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza		8/1/2011 3:51:25 PM	78	\$0.00
Vargas, Juan Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	Needs maps mounted on the wall.(H			
Diana Mendoza 76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	Needs maps mounted on the wall.(H	Jubbla)		
76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza		hubble)		
76218 F-Wing Medium Work In Progress Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza				
Lozoya, Manny Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	Classroom	8/1/2011	78	\$0.00
Diana Mendoza 76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza		8/1/2011 3:58:42 PM		
76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza	Closets do not lock (montoya)			
76301 G-Wing Medium Work In Progress Quinones, Paul Diana Mendoza				
Quinones, Paul Diana Mendoza	Classroom	8/2/2011	77	\$0.00
Diana Mendoza		8/2/2011 9:41:51 AM		
Diana Mendoza	support bar on teacher, teacher desl	k broken.		
	,			
ŭ	Hallway/Corridor	9/8/2011	40	\$0.00
Medium Work In Progress	by attendence	9/8/2011 3:32:11 PM		·
Lozoya, Manny	panic bar is loose outside door next by cafeteria (urquidi)			
Rosa Quezada	a, canceran (an quica)			
78487		9/19/2011	29	\$0.00
Medium Work In Progress		9/19/2011 8:37:14 AM		
Lozoya, Manny	Need to issue keys to Alfredo Ortiz,			

10/18/2011 1:23:06 PM Page 32 of 172

WOID Priority Assigned [·] Requester		Area Number Reason Description	Until Request Date Targe Created Date/Time Actua A	A I	Labor Hours	Costs
Location:	Chaparra	I HS				
78520	E-Wing	Classroom	9/19/2011	29		\$0.00
Medium	Work In Progress	E-4	9/19/2011 3:48:52 PM			
Lozoya, M	anny	file cabinet lock does not work - valuables and afraid they might of	•			
Rosa Quez 78974	zada		9/29/2011	19		\$0.00
Medium	Work In Progress	Chaparral Pre-K	9/29/2011 9:48:11 AM			·
Lozoya, M	anny	Need keys for New Pre-K wing, Elodia Salinas (575) 824-5382. locksmith on Friday 9.30.11 at 8	She will meet with			
Peggy Jo I 79040	Hernandez G-Wing	Mechanical	9/30/2011	18		\$0.00
Medium	Work In Progress		9/30/2011 1:43:39 PM			*****
Lozoya, Ma	-	need to change lock in storage r				
Alfredo Ort	-					
79767	12		10/14/2011	4		\$0.00
Medium	Work In Progress		10/14/2011 9:13:57 AM			
Lozoya, M	anny	Master key stuck on front inside pre-kinder building next to c.h.s	main entrance door to			
Jesus Urqı 79026	<u>uidi</u> C-Wing	Computer Lab	9/30/2011	18		\$0.00
Medium	Work In Progress		9/30/2011 7:28:21 AM			,
Solis, Lore	-	High presure cut-out				
Alfredo Ort		3 1				
79422	D-Wing	Computer Lab	10/5/2011	13		\$0.00
Medium	Work In Progress		10/5/2011 2:50:02 PM			
Solis, Lore	nzo	cyber-cafe relative sensor fail.				
Alfredo Ort	iz					
79423	E-Wing	Computer Lab	10/5/2011	13		\$0.00
Medium	Work In Progress		10/5/2011 2:52:42 PM			
Solis, Lore	nzo	compresor cut-out swich fail.				
Alfredo Ort						
79424	F-Wing		10/5/2011	13		\$0.00
Medium	Work In Progress		10/5/2011 2:54:09 PM			
Solis, Lore	nzo	spase temp-fail sensor				

10/18/2011 1:23:06 PM Page 33 of 172

WOID Priority Assigned			Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	I HS						
75470	A-Wing	Office		7/14/2011		96		\$0.00
Medium	Work In Progress	rosa's office		7/14/2011 1:55:14 PM				
Lozoya, Ma	anny	cannot open from	nt main door with o	ch86 -				
Rosa Quez		Classica		7/00/0044		00		PO 00
75964	A-Wing	Classroom		7/28/2011		82		\$0.00
Medium	Work In Progress	A-107		7/28/2011 11:58:57 AM				
Lozoya, Ma	•		n door in A-107 - it esn't close door wi	opens after several th key (henry)				
Rosa Quez 78110	zada	Cafeteria		9/9/2011		39		\$0.00
Medium	Work In Progress	Cafeteria		9/9/2011 9:29:24 AM				
Sotelo, En	rique		d to be replaced "o ASAP as Mr. Rup	on a bun" stand and cich				
Diana Men	idoza			0/00/0044				40.00
78972		_		9/29/2011		19		\$0.00
Medium	Work In Progress	Pre-k		9/29/2011 9:23:57 AM				
Sotelo, En		Chaparral High	electrical outlett in School for a Xerox at the new center	Copier 5665tc. PreK				
Lucia Alme	eraz			9/20/2011		28		\$0.00
Medium	Work In Progress			9/20/2011 11:46:24 AM		20		ψ0.00
	-	water nump from	a tha gas tharmal					
Solis, Lore		water pump non	n the geo thermo l	eeking in Q bild				
Alfredo Ort 78613	A-Wing	Hallway/Corrido	r	9/21/2011		27		\$0.00
Medium	Work In Progress			9/21/2011 10:54:47 AM				
Solis, Lore	nzo	water leakind fro	om unit					
Alfredo Ort	tiz							
78731				9/23/2011		25		\$0.00
Medium	Work In Progress			9/23/2011 2:55:26 PM				
Solis, Lore	nzo		with two a/c water dissassemble to r	units in locker room epair units.				
Alfredo Ort 79025	tiz G-Wing	Computer Lab		9/30/2011		18		\$0.00
Medium	Work In Progress	Joinputor Lab		9/30/2011 7:26:49 AM		10		ψυ.υυ
Solis, Lore	-	no motor in the	unit (1hp. 3phase					
		no motor in the	unit (111p. opnase	400. VOII)				
Alfredo Ort	UZ 5 Work Orders	Av	g. Age of WO's	38	Total for Chaparra	al HS	0	\$0.00

10/18/2011 1:23:07 PM Page 34 of 172

WOID Priority Assigned [*] Requester	Building Status To	Area Number Reason Description	Until Request Date Target (Created Date/Time Actual (AI	Labor Hours	Costs
Location:	Chaparra	I MS				
77961	Опарата	Classroom	9/6/2011	42		\$0.00
Medium	Work In Progress	308	9/6/2011 9:35:28 AM	42		ψ0.00
	_					
Ontiveros,		Replace 3 faucets in lab area that	do not work.			
Albert Valle 78830	ejo Main Building	Gym	9/27/2011	21		\$0.00
Medium	Work In Progress		9/27/2011 9:43:32 AM			
Vallejo, Alk	bert	please repaint gym.				
Albert Valle						
78861	Main Building	Parking Lot	9/27/2011	21		\$0.00
Medium	Work In Progress		9/27/2011 3:18:09 PM			
Vallejo, Alk	pert	Paint handicap and fire lane mark	ings in parking lot.			
Albert Valle	ejo					
77334		Portables	8/24/2011	55		\$0.00
Medium	Work In Progress	PORTABLE 13	8/24/2011 11:44:37 AM			
Lozoya, M	•	DEBBIE HOLGUIN - DOOR TO S PORTABLE NEEDS TO BE REKE LOCK ITEMS IN THERE				
Elena Pala 78838	acios		9/27/2011	21		\$0.00
Medium	Work In Progress		9/27/2011 11:04:59 AM	21		ψ0.00
Lozoya, M	_	Please install sliding glass door lo main hall between 200 and 300 ha	ck on trophy case in			
Albert Valle 79854	ejo	Office	10/17/2011	1		\$0.00
	Mork In Drogroop			'		ψ0.00
Medium Lozoya, M	Work In Progress anny	DOORS IN KEY GETTING STUCK AND NOT SHUT PROPERLY TO THE DOO HALLWAY BETWEEN 100 AND 2	RS IN THE MAIN			
Elena Pala 79304	acios		10/2/2011 1	10/23/2011 16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:32 AM	. 5, 26, 25 1 10		ψ0.00
Orozco, Da	_	Monthly - Chaparral MS Fire Sprir				
C10200, D	шту	PM schedule details.	inioi iliop Neiei to			
Margret Vi	llalobos		40/47/2044			<u></u>
79822 Modium	Work In Brogress	SDED OFFICE	10/17/2011	1		\$0.00
Medium	Work In Progress	SPED OFFICE	10/17/2011 10:23:14			
Briones, E	nrique	PO #101108760 PICK UP ONE BOX DELIVER TO PATRICIA GARCIA-TEACHER-C SCHOOL				
Margaret V	/illalobos					

WOID Priority Assigned 1	Building Status	Area Deferred By Area Number Reason Description	Until Request Date T Created Date/Time A	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester		Description		Action raken			
Location:	Chaparra	II MS					
79325	Main Building	Classroom	10/3/2011		15		\$0.00
Medium	Work In Progress		10/3/2011 11:16:12 AM				
Vallejo, Alb	ert	We need the washer and dryer rer room in room #107 so we can strip					
Jesus Estra	ada		9/20/2011		28		\$0.00
78544	Mark In Drawns				20		φυ.υυ
Medium	Work In Progress		9/20/2011 11:12:30 AM				
Carbajal, Ji	mmy	We have a burnisher that the on so and the side wheels come off som whirl amatic tag # 5602456. Thank	e times. Advance				
Robert Gor 79230	nzalez		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:51 AM	10/10/2011	10		φυ.υυ
Vallejo, Alb	Work In Progress ert	Monthly - Chaparral MS Emer. Lig Refer to PM schedule details.					
Margret Vill	alobos	Troidi to i ivi dolloddio dotallo.					
79231			10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:51 AM				
Vallejo, Alb		Monthly - Chaparral MS Bleacher PM schedule details.	Inspection - Refer to				
Margret Vill 76143	alobos		7/31/2011		79		\$0.00
Medium	Work In Progress		7/31/2011 9:25:23 AM				
Sanchez, R	· ·	Monthly - Chaparral MS - DP-781 schedule details.	- Refer to PM				
Margret Vill	alobos		10/0/00				
79269			10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:13 AM				
Vallejo, Alb		Monthly - Chaparral MS Monthly F to PM schedule details.	E Inpsection - Refer				
Margret Vill 79287	alobos		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:23 AM				
Orozco, Da	nny	Monthly - Chapparal MS Range Ho to PM schedule details.	ood Cleaning - Refer				
Margret Vill	alobos		7///2044	7/24/2014	106		ድስ ሰሳ
74949	Mork In Dra		7/4/2011	7/24/2011	106		\$0.00
Medium	Work In Progress		7/4/2011 12:21:47 AM				
Orozco, Da	nny alobos	Monthly - Chaparral MS Fire Sprin PM schedule details.	kler Insp Refer to				

10/18/2011 1:23:07 PM Page 36 of 172

WOID Priority	Building Status	Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time Ad	ctual Comp Date	Days Aged	Labor Hours	
Assigned		Description	Action Taken			
Requester						
Location:	Chaparra	IMS				
79538		10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:44 AM				
Gonzalez,	Robert	Monthly - QRTLY BLDG INSP REPORTS (CM) - Refer to PM schedule details.				
Margret Vi 76052	llalobos	7/31/2011		79		\$0.00
Medium	Work In Progress	7/31/2011 9:24:43 AM		7.5		ψ0.00
	-					
Vallejo, All		Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret Vi 76053	IIAIODOS	7/31/2011	8/31/2011	79		\$0.00
Medium	Work In Progress	7/31/2011 9:24:44 AM				
Vallejo, All		Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.				
Margret Vi	llalobos					
77818		9/4/2011	9/12/2011	44		\$0.00
Medium	Work In Progress	9/4/2011 12:24:05 AM				
Vallejo, All	pert	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vi 79240	llalobos	10/2/2011		16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:57 AM		10		ψ0.00
	· ·					
Vallejo, All		Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret Vi 79229	lialodos	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:50 AM				
Vallejo, All	_	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vi	llalobos					
79064		10/2/2011	10/5/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:15 AM				
Vallejo, All	bert	Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.				
Margret Vi	llalobos	9/30/2011		18		\$0.00
79009 Modium	Mark In Dragge			10		ψυ.υυ
Medium	Work In Progress	9/30/2011 12:22:29 AM				
Vallejo, All	bert	Monthly - Chaparral MS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.				

10/18/2011 1:23:07 PM Page 37 of 172

Selected Da WOID	Building	•	arget Comp Date	Days	Labor	Total Costs
Priority	Status	Area Number Reason Created Date/Time A	-	Aged	Hours	
Assigned '		Description	Action Taken			
Requester	r Name					
_ocation:	Chaparra	IMS				
79140		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:57 AM				
Vallejo, All	bert	Monthly - Chaparral MS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.				
Margret Vi	llalobos	40/0/0044	44/0/0044	40		Ф0.00
79141		10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:57 AM				
Vallejo, Alt		Yearly - Chaparral MS I4 (Fan Coil)(Yearly) - Refer to PM schedule details.				
<u>Margret Vi</u> 79123	llalobos	10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:47 AM	11/2/2011	10		ψ0.00
	· ·					
Vallejo, All		Yearly - Chaparral MS U2 (G.Heater)(Yearly) - Refer to PM schedule details.				
<u>Margret Vi</u> 79124	IIAIODOS	10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:48 AM				
Vallejo, All	· ·	Yearly - Chaparral MS H6 (Furnace)(Yearly) - Refer to PM schedule details.				
Margret Vi	llalobos	Tivi concurs detaile.				
76977		8/16/2011		63		\$0.00
Medium	Work In Progress	8/16/2011 8:17:26 AM				
Lozoya, M	anny	Door to room 404 has damaged hinges and no longer closes properly. they need to be replaced.				
Albert Valle 79358	ejo	10/4/2011		14		\$0.00
	Mork In Drogross			17		ψ0.00
Medium	Work In Progress	10/4/2011 9:05:28 AM				
Carrasco,	Danny	Please deliver fuel for polaris vehicle #0514 and for lawn equipment #604 - 10 gallons				
Albert Vall		Machanian 7/40/0044		04		Ф0.00
75538	Main Building	Mechanical 7/19/2011		91		\$0.00
Medium	Work In Progress	7/19/2011 10:56:27 AM				
Orozco, Da	•	Mercury pressure switch on fire suppression system needs to be replaced.				
Albert Vall 78192	ejo	9/12/2011		36		\$0.00
Medium	Work In Progress	9/12/2011 11:08:57 AM				ψ5.00
	-					
Lozoya, M		Repair or replace doors in office area that were damaged during break-in				
Albert Vall	ејо					

10/18/2011 1:23:07 PM Page 38 of 172

WOID Priority Assigned [*] Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By Lo Area Deferred By Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	I MS					
78193			9/12/2011		36		\$0.00
Medium	Work In Progress		9/12/2011 11:11:39 AM				
Munoz, Mi	chael	Repair fence on west side of school	I that was cut.				
Albert Valle	ejo		= 10.4 100.4.4	0/0/0044			
76054			7/31/2011	8/3/2011	79		\$0.00
Medium	Work In Progress		7/31/2011 9:24:44 AM				
Vallejo, Alk		Monthly - Chaparral MS - Emerg. E Refer to PM schedule details.	yewash (Monthly) -				
Margret Vil 79855	lalobos	Office	10/17/2011		1		\$0.00
Medium	Work In Progress	MAIN OFFICE	10/17/2011 2:50:31 PM				*
Lozoya, Ma	· ·	NEED AN EXTRA TRASH BIN KEY TO OUR GROUNDS PERSON					
Elena Pala 76355	cios		8/3/2011		76		\$0.00
Medium	Work In Progress		8/3/2011 10:31:21 AM				*****
	Guadalupe	Please replace valves for tree line boot open.					
Albert Valle	ejo	посторон.					
77704		Classroom	9/1/2011		47		\$0.00
Medium	Work In Progress	ROOM 107	9/1/2011 11:36:00 AM				
Vallejo, Alb		AS PER SAM ALVA IN SPED DEP HOLDING TOILET TO FLOOR LOO WOBBLES WILL FALL OVER IS N	OSE TOILÉT				
Elena Pala 79326	<u>icios</u> Main Building	Classroom	10/3/2011		15		\$0.00
High	Work In Progress		10/3/2011 11:18:41 AM				******
vallejo, Alb	· ·	We have a cover missing on the ou in classroom #106					
Jesus Estr	ada						
79845			10/17/2011		1		\$0.00
Medium	Work In Progress		10/17/2011 12:46:00				
Munoz, Mi	chael	INSTALL BASE IN DRY STORAGE INSPECTION.	E. AS PER HEALTH				
Maritza Go 76354	nzalez		8/3/2011		76		\$0.00
Medium	Work In Progress		8/3/2011 10:27:46 AM		, 0		Ψ0.00
Gonzalez,	_	Please fabricate expanded metal graduater fountain, located outside the	uard around exterior				
Albert Valle							
Count: 40	Work Orders	Avg. Age of WO's 3	4	Total for Chaparra	I MS	0	\$0.00

10/18/2011 1:23:07 PM Page 39 of 172

Priority Assigned ⁻ Requester		Area Number Description	Reason	Created Date/Time Ac	tual Comp Date Action Taken	Aged	Hours	
Location:	Desert Pr	ride						
78384				9/15/2011		33		\$0.00
Medium	Work In Progress			9/15/2011 8:46:36 AM				
Appelzollei	r, Fred	Need to make g	as repairs to oper	n gas back up.				
Michael Mu 79568	ınoz	Library		10/10/2011		8		\$0.00
Medium	Work In Progress	READING/LAB		10/10/2011 1:50:21 PM				
Castillo, Ca	arlos	NEED TO INST	ALL ELECTRICAL PROJECTOR	L OUTLET ON				
David Acos 79569	sta	Portables		10/10/2011		8		\$0.00
Medium	Work In Drogram	ROOM 6		10/10/2011 1:52:31 PM		J		ψυ.υυ
Castillo, Ca	Work In Progress arlos	NEED TO INST	ALL ELECTRICAL SMARTBOARD PI	L OUTLET ON				
David Acos	sta							
79570		Portables		10/10/2011		8		\$0.00
Medium	Work In Progress	ROOM 7		10/10/2011 1:55:05 PM				
Castillo, Ca	arlos		ALL ELECTRICAL SMARTBOARD PI					
David Acos	sta	Library		10/14/2011		4		\$0.00
79764		Library				4		φυ.υυ
Medium	Work In Progress	RESTROOM		10/14/2011 8:11:49 AM				
Lara, Ralpi		REQUESTING TO RESTROC		OKEN DOORKNOB				
David Acos 78010	sta	Classroom		9/7/2011		41		\$0.00
Medium	Work In Progress	Boxing room		9/7/2011 10:25:23 AM				
Ronquillo,	· ·	JC Fernandez, I	Boxing coach,nee at the warehouse.					
Mary Telles	3	Occasion dist		0/40/0044		00		# 0.00
78426		Custodial		9/16/2011		32		\$0.00
Medium	Work In Progress			9/16/2011 11:19:12 AM				
Ambriz, Jo	se	AC UNIT NOT V	VORKING IN CUS	STODIAL OFFICE.				
David Acos	sta			10/2/2011	10/10/2014	16		<u></u>
79223	West 5			10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:27:46 AM				
Acosta, Da	vid	Monthly - Deser to PM schedule		nt Test: Monthly - Refer				

10/18/2011 1:23:07 PM Page 40 of 172

WOID	Building	Area Deferred By	Until Request Date Targ	-	Days Aged	Labor Hours	Costs
Priority	Status	Area Number Reason	Created Date/Time Act	ual Comp Date Action Taken	Ayeu	Hours	
Assigned [·] Requester		Description		Action Taken			
ocation:	Desert P	rido					
	Desertif	Tide .	10/2/2011		16		\$0.00
79249	Madala Dasanas		10/2/2011		10		φυ.υυ
Medium	Work In Progress		10/2/2011 12:28:01 AM				
Sanchez, F		Monthly - Desert Pride - Monthly Wato PM schedule details.	iter Samples - Refer				
<u>Margret Vil</u> 79250	llalobos		10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:02 AM				,
Sanchez, I	_	Monthly - Desert Pride - Monthly Me to PM schedule details.					
Margret Vi	llalobos	to Fin concurs detaile.					
79265			10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:11 AM				
Acosta, Da	avid	Monthly - Desert Pride Monthly FE In PM schedule details.	nspection - Refer to				
Margret Vil 79758	llalobos		10/14/2011		4		\$0.00
Medium	Work In Progress		10/14/2011 7:58:09 AM		7		ψ0.00
Briones, E	nrique	On October 18, 2011, please deliver pallets to Desert Pride Academy. Communication Smelser.	· 4 empty Gaylords +				
<u>Yolie Jacq</u> 77566	uez	Portables	8/30/2011		49		\$0.00
Medium	Work In Progress	ROOM 5	8/30/2011 9:17:14 AM				ψ0.00
Ambriz, Jo	_	TEACHER REPORTED THAT A/C SUFFICIENTLY FOR AFTER NOON FILTER LAST THURSDAY).	IS NOT COOLING				
David Acos	sta	Classroom	0/12/2011		25		<u></u>
78252	Madala Dasanas		9/13/2011		35		\$0.00
Medium	Work In Progress	ROOM 9	9/13/2011 1:05:24 PM				
Lara, Ralp	h	DOOR HINGES SCREWS KEEP CO	OMING LOOSE.				
<u>David Aco</u> 79019	sta		9/30/2011		18		\$0.00
Medium	Work In Progress		9/30/2011 12:22:34 AM				ψ0.00
Aguilar, Pa	•	Monthly - Desert Pride HS A16 (Fan					
Aguilai, Fa	atricio	Refer to PM schedule details.	EXII.)(G.AIIIIdai) -				
Margret Vi	llalobos		10/2/2011	10/23/2011	16		\$0.00
79097	Morle la Dr.			10/23/2011	10		φυ.υυ
Medium	Work In Progress		10/2/2011 12:26:34 AM				
Aguilar, Pa	atricio	Monthly - Desert Pride HS H11 (E.H Refer to PM schedule details.	eater)(S.Annual) -				
Margret Vi	llalobos						
0/10/201	1 1:23:07 PM						11 of 172

10/18/2011 1:23:07 PM Page 41 of 172

	ate Range for Request		,	,					Tota Costs
WOID Priority	Building Status	Area Area Number	Deferred By	Until	-	arget Comp Date Actual Comp Date	Days Aged	Labor Hours	
-			Neason	Cie	ateu Date/Tillie A	Action Taken	•		
Assigned		Description				Action Taken			
Requester	Name								
Location:	Desert Pi	ride							
79510					10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress			10/9/20)11 12:16:30 AM				
Acosta, Da	avid	Monthly - QRT PM schedule d	LY BLDG INSP REF letails.	PORT (DP) - I	Refer to				
Margret Vi	llalobos								
79163					10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress			10/2/20)11 12:27:10 AM				
Aguilar, Pa	atricio	Monthly - Dese schedule detai	ert Pride Roof Inspec Is.	ction - Refer t	o PM				
Margret Vi	llalobos								
79243					10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress			10/2/20)11 12:27:58 AM				
Acosta, Da	avid	Monthly - Dese PM schedule d	ert Pride Exit Sign In letails.	sp: Monthly -	Refer to				
Margret Vi									
Count: 19	Work Orders	Α	vg. Age of WO's 1	19		Total for Desert I	Pride	0	\$0.00

10/18/2011 1:23:07 PM Page 42 of 172

WOID	Building	Area Deferred By U		arget Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time A	ctual Comp Date	Aged	Hours	
Assigned	То	Description		Action Taken			
Requester	r Name						
Location:	Desert Ti	ail Intermediate					
78822		Mechanical	9/27/2011		21		\$0.00
Medium	Work In Progress		9/27/2011 8:25:17 AM				
Villalobos,	, David	9/27/11 3" backflow preventor is leaking bad,we out filter cartridges until backflow is fixed Wilkins model.Plumber can call me for c Raul	d.It is a Zurn				
Raul Sano	chez		9/28/2011		20		\$0.00
78941	Marile In Duantage				20		φυ.υυ
Medium	Work In Progress		9/28/2011 4:18:04 PM				
Ontiveros,	, Joe	Need Big snake to unclogg main sewer portables #412 and #413. (Art Room ar Portables)					
Johnny Ac 79559	cuna		10/10/2011		8		\$0.00
Medium	Work In Progress		10/10/2011 11:46:51		Ü		φυ.συ
Ontiveros,	_	Need Plumber to check waterheaters. N					
Johnny Ac	•						
78758	Juna		9/26/2011		22		\$0.00
Medium	Work In Progress		9/26/2011 10:10:54 AM				
Sotelo, En	nrique	Need electrical wiring for Bard Heating/0 portable #409.	Cooling unit to				
Johnny Ad	cuna		40/44/2044		4		\$0.00
79773			10/14/2011		4		\$0.00
Medium	Work In Progress		10/14/2011 12:50:44				
Sotelo, En	nrique	Need 15 Emergency lights and 15 4x4 r	netal boxes.				
Johnny Ac 77583	cuna		8/30/2011		49		\$0.00
Medium	Work In Progress		8/30/2011 1:33:24 PM		43		ψ0.00
Solis, Lore	_	Portable #409: Window unit is not cooli of a leak. Already removed unit from wa tried to locate leak.	ng. visual signs				
Johnny Ac	cuna		40/0/0044	40/0/0044	10		<u></u>
79281	W 11.5		10/2/2011	10/8/2011	16		\$0.00
Medium Acuna, Jol	Work In Progress	Monthly - Desert Trail Monthly FE Inpse	10/2/2011 12:28:20 AM				
, todila, 00	y	PM schedule details.	0				

10/18/2011 1:23:07 PM Page 43 of 172

Margret Villalobos

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time A	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert Ti	ail Intermediate					
79288			10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:24 AM				
Orozco, Da	anny	Monthly - Desert Trail Range Hood (PM schedule details.	Cleaning - Refer to				
Margret Vil	lalobos		7/4/2011	7/24/2011	106		<u></u>
74950			7/4/2011	7/24/2011	106		\$0.00
Medium	Work In Progress		7/4/2011 12:21:47 AM				
Orozco, Da	·	Monthly - Desert Trail Fire Sprinkler schedule details.	Insp Refer to PM				
Margret Vil 79305	lalobos		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:33 AM				
Orozco, Da	ŭ	Monthly - Desert Trail Fire Sprinkler schedule details.					
Margret Vil	lalobos						
79368			10/4/2011		14		\$0.00
Medium	Work In Progress		10/4/2011 10:15:03 AM				
,		NEED CARPET REPAIR/FRONT O ISSUE.	FFICE - SAFETY				
Jesus Estra	ada	Custodial	10/12/2011		6		\$0.00
79690		Custodiai			O		φυ.υυ
Medium	Work In Progress		10/12/2011 12:13:50				
Carbajal, J	•	JIMMY BUENAS TARDES SI ME PI VANDAS DE ASPIRADORA POR F					
Laura Sand 79201	doval		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:33 AM	. 5, . 5, 25			ψ0.00
Acuna, Joh	-	Monthly - Desert Trail Emer. Light In					
Margret Vil	lalahas	to PM schedule details.					
Margret Vil 79202	Iaiobos		10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:34 AM				
Acuna, Joh	· ·	Monthly - Desert Trail ES -Clothes D Refer to PM schedule details.	Oryer (Monthly) -				
Margret Vil	lalobos						A
78169			9/11/2011	9/27/2011	37		\$0.00
Medium	Work In Progress		9/11/2011 12:20:46 AM				
Acuna, Joh	inny	Monthly - Desert Trail Playground In schedule details.	nsp - Refer to PM				

10/18/2011 1:23:07 PM Page 44 of 172

WOID Priority Assigned ^d Requester		Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description	arget Comp Date actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert Tr	ail Intermediate				
79522		10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:36 AM				
Acuna, Joh	nny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.				
Margret Vil	lalobos	7/5/2011		105		\$0.00
75105	Work in Drogram			105		φυ.υυ
Medium	Work In Progress	7/5/2011 12:16:34 AM				
Sanchez, F		Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.				
Margret Vil 77938	lalobos	9/6/2011		42		\$0.00
Medium	Work In Progress	9/6/2011 12:20:02 AM				
Sanchez, F	-	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.				
Margret Vil	lalobos	40/0/0244	11/0/0011			A 2 2 2 2
79116		10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:44 AM				
Acuna, Joh	-	Yearly - Desert Trail ES H6 (Furnace)(Yearly) - Refer to PM schedule details.				
Margret Vil 79117	lalobos	10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:44 AM	,_,	. •		ψ0.00
Acuna, Joh	•	Yearly - Desert Trail ES U2 (Heat/Gas)(Yearly) - Refer to PM schedule details.				
Margret Vil	lalobos					
79118		10/2/2011	10/18/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:45 AM				
Acuna, Joh	inny	Monthly - Desert Trail ES A1 (Air Dryer)(S.Annual) - Refer to PM schedule details.				
Margret Vil 79528	lalobos	10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:39 AM	10/20/2011	J		ψ0.00
Sandoval,	-	Monthly - QRTLY BLDG INSP REPORTS (DT) - Refer to PM schedule details.				
Margret Vil	lalobos	to Fivi Scriedule details.				
79157		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:06 AM				
Acuna, Joh	inny	Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.				

10/18/2011 1:23:07 PM Page 45 of 172

WOID Priority	Building Status	Area Deferred By U Area Number Reason	ntil Request Date Ta Created Date/Time A	arget Comp Date	Days Aged	Labor Hours	
Priority Assigned 1		Description	Greated Date/Time A	Action Taken	O		
Requester		Description		Action Taken			
-		ail Intermediate					
Location:	Desert II	ail Intermediate					
79200			10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:33 AM				
Acuna, Joh	inny	Monthly - Desert Trail Exit Sign Insp: M PM schedule details.	onthly - Refer to				
Margret Vil	lalobos		40/47/0044		4		# 0.00
79879			10/17/2011		1		\$0.00
Medium	Work In Progress		10/17/2011 4:01:10 PM				
Orozco, Da	anny	need a bulb cover for the walk-in. SNP 824.3822	Manager Pat C.				
Maritza Go 75597	nzalez		7/20/2011		90		\$0.00
	Work In Progress				00		ψ0.00
Medium	Work In Progress		7/20/2011 3:39:53 PM				
Gonzalez,	Salvador	Please make (2) ramps for steiner tracting go in and out of concrete swell in the base of school grounds.					
Johnny Act	una		10/3/2011		15		\$0.00
79337	Morte In Drawnson				15		φυ.υυ
Medium	Work In Progress		10/3/2011 3:43:26 PM				
Carrasco, I	-	Need Unleaded Gasoline to fill up tanks #192 and Steiner tractor.	s to worktruck				
Johnny Act 77069	una		8/17/2011		62		\$0.00
	W 11 D				02		ψ0.00
Medium	Work In Progress		8/17/2011 2:53:44 PM				
Munoz, Mid	chael	need to modify the parent drop-off area another gate south of current entrance to base course for drive way, signage and payment lines.	to parking lot,				
Alfredo Hol	lguin		0/20/2011		10		ድስ ሰብ
79013			9/30/2011		18		\$0.00
Medium	Work In Progress		9/30/2011 12:22:31 AM				
Acuna, Joh	•	Monthly - Desert Trail ES A16(Exhst Fa Refer to PM schedule details.	n)(S.Annual) -				
Margret Vil	lalobos		10/2/2011	11/2/2011	16		\$0.00
79115	Modelo Deserve			11/2/2011	10		φυ.υυ
Medium	Work In Progress		10/2/2011 12:26:43 AM				
Acuna, Joh	nny	Yearly - Desert Trail ES I4 (Fan Coil)(Ye PM schedule details.	early) - Refer to				
	lalobos						

10/18/2011 1:23:07 PM Page 46 of 172

WOID	Building	•	st Date Target Comp Date	AI	Labor	
Priority	Status		e/Time Actual Comp Date	Aged	Hours	
Assigned		Description	Action Taken			
Requester	· Name					
Location:	Desert Ti	rail Intermediate				
76028		7/2	29/2011	81		\$0.00
Medium	Work In Progress	7/29/2011 3:39	9:10 PM			
Orozco, Da	anny	1).milk cooler is making ice 2) the sink where you wash your hands the faucet is leaking water 3) faucet from the salad sink is loose 4) the sink from the pots and pans is also leaking water. SNP Manager Pat C. 824.3822.				
Maritza Go 76883	onzalez	8/3	2/2011	67		\$0.00
Medium	Work In Progress	8/12/2011 11:50		O1		ψ0.00
	Work In Progress		J.32 AIVI			
Orozco, Da		1) SNEEZE SHIELD ON ASSEMBLY LINE WERE BROKEN BY STUDENTS. 2) LADIES ARE HAVING A HARD TIME WITH RAILS/COVERS IN OVEN IS, GETTING STUCK. SNP MANAGER PAT C. 824.3822				
<u>Maritza Go</u> 79609	onzalez	10/1	1/2011	7		\$0.00
Medium	Work In Progress	10/11/2011 9:0		•		ψ0.00
Orozco, Da	•	Skillet it doesn't work and I need to use it Thursday and Friday.SNP Manager Pat C. 824.3822				
Maritza Go	onzalez					
79875		10/1	7/2011	1		\$0.00
Medium	Work In Progress	10/17/2011 3:5	7:30 PM			
Orozco, Da	anny	The dial of the oven doesn't work it turns all the way you can tell what temperature it is. SNP Manager Pat C. 824.3822				
Maritza Go	onzalez	40/4	7/0044	4		#0.00
79876			7/2011	1		\$0.00
Medium	Work In Progress	10/17/2011 3:58	3:33 PM			
Orozco, Da	•	the door from the oven stove doesn't close all the way. SNP Manager Pat C. 824.3822				
<u>Maritza Go</u> 79877	onzalez	10/1	7/2011	1		\$0.00
Medium	Work In Progress	10/17/2011 3:59		•		φσ.σσ
Orozco, Da	•	plate from the back door needs to be fix and the plate	9.43 FIVI			
Maritza Go	nzalez	from the walk-in to. SNP Manager Pat C. 824.3822				
79617	JI IZAIGZ	10/1	1/2011	7		\$0.00
Medium	Work In Progress	10/11/2011 1	0:50:04			
Solis, Lore	-	Need assistance and 2 retrofit kits for Reznor rooftop heaters.				
Johnny Ac	una					

10/18/2011 1:23:07 PM Page 47 of 172

Selected Da WOID	ate Range for Request Building	Dates:7/1/2011 - 6/30/2012 Area Deferre		Request Date Target Con	np Date Days	Labor	Costs
Priority	Status	Area Number Reason	n Crea	ated Date/Time Actual Con	np Date Aged	Hours	
Assigned	То	Description		Action	Taken		
Requester	Name						
Location:	Desert Tr	ail Intermediate					
79676				10/12/2011	6		\$0.00
Medium	Work In Progress		10/12/2	2011 8:49:02 AM			
Solis, Lore	nzo	Boiler heating system is	s ready for Start-up.				
Johnny Ac 75912	una			7/27/2011	83		\$0.00
	Mork In Drogroop		7/07/		63		φυ.υυ
Medium	Work In Progress		1/21/2	2011 3:45:58 PM			
Lozoya, M	anny	Need a key issued to op valves underground.	pen up new covers for irr	igation			
Johnny Ac	una			0/0/0044	40		<u>ФО ОО</u>
78056				9/8/2011	40		\$0.00
Medium	Work In Progress		9/8/2	2011 7:47:13 AM			
Ontiveros,	Guadalupe		n box to main backflow v rigation system. (Main va				
Johnny Ac	una			0/00/0044	40		<u> </u>
77576				8/30/2011	49		\$0.00
Medium	Work In Progress		8/30/20)11 10:50:54 AM			
Ronquillo,	Ruben	Ruben Ronquillo: Need You	d to borrow long trailer.	⁻ hank			
Johnny Ac	una			40/47/0044			
79799				10/17/2011	1		\$0.00
Medium	Work In Progress		10/17/2	2011 7:35:31 AM			
Acuna, Jol	nnny	Need to load up tables deliver to Chaparral Hig	from Desert Trail and CN h School.	1S and			
Johnny Ac	una						

10/18/2011 1:23:07 PM Page 48 of 172

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Vi	ew ES					
78755		Custodial	9/26/2011		22		\$0.00
Medium	Work In Progress		9/26/2011 8:26:10 AM				
Villalobos,	David	3 of the outside water faucets are are leaking and the one in the mid teachers use that one to water the is the main problem.Will you pleas fixed.THANK YOU IN ADVANCED	dle of the school the little garden.That one se send sombody to				
Hector Riv 78832	era		9/27/2011		21		\$0.00
Medium	Work In Progress		9/27/2011 9:47:24 AM				ψ0.00
	-						
Villalobos,		Install a deep sink and counter top	for the art room				
Ruben Ort 78834	iz		9/27/2011		21		\$0.00
Medium	Work In Progress		9/27/2011 9:51:10 AM				V 0.00
Villalobos,	· ·	Install a sink and garbage disposa lounge					
Ruben Ort	iz						
75705			7/22/2011		88		\$0.00
Safety	Work In Progress		7/22/2011 2:22:30 PM				
Castillo, C	arlos	Freezer in kitchen is making spark	S.				
Aida Salce	edo						
78918		Classroom	9/28/2011		20		\$0.00
Medium	Work In Progress	Rm 24 Sped	9/28/2011 12:22:16 PM				
Castillo, C	arlos	Need Charles to make a determination focus which is located on the ceiling wire electrical line and Charles to computer. Please send for him to Thanks.	ng. Might need Cali to wire from infocus to				
Cora Ram	irez		9/28/2011		20		\$0.00
78919 Medium	Work In Progress	15A	9/28/2011 12:22:31 PM		20		ψυ.υυ
	· ·						
Castillo, C	arios	Need Charles to make a determine focus which is located on the ceiling wire electrical line and Charles to computer. Please send for him to Thanks.	ng. Might need Cali to wire from infocus to				
Cora Ram 78858	irez	Portables	9/27/2011		21		\$0.00
Medium	Work In Progress	. Stables	9/27/2011 3:05:39 PM		۲.		ψ0.00
	-	Observe of comments and the					
Castillo, C	arios	Check status of wrong circuit brea pump installed by Fand J electric. replace ASAP.					
Carlos Ca	stillo						
10/18/201	1 1:23:07 PM						49 of 172

10/18/2011 1:23:07 PM Page 49 of 172

WOID Priority	Building Status	Area Deferred By Area Number Reason	Until Request Date Ta Created Date/Time A	arget Comp Date	Days Aged	Labor Hours	
Assigned		Description	Created Date/Time At	Action Taken	J		
Requeste		Description		Action Taken			
Location:	Desert Vi	iow FS					
	Desert vi		40/40/0044				Φο οο
79717		Custodial	10/13/2011		5		\$0.00
Medium	Work In Progress		10/13/2011 7:52:31 AM				
Estrada, J	esus	This work order is to repair the ca 16,20,and 22 the crpets are new from the middle of the rooms .TH ADVANCED.	but is coming apart				
Hector Riv	/era		10/2/2011	10/8/2011	16		\$0.00
79257				10/6/2011	16		φυ.υυ
Medium	Work In Progress		10/2/2011 12:28:06 AM				
Ortiz, Rub	en	Monthly - Desert View ES Monthl to PM schedule details.	y FE Inpsection - Refer				
Margret Vi 79289	illalobos		10/2/2011	10/23/2011	16		\$0.00
	Mark In Dragge			10/23/2011	10		Ψ0.00
Medium	Work In Progress		10/2/2011 12:28:24 AM				
Orozco, D	·	Monthly - Desert View ES Range to PM schedule details.	Hood Cleaning - Refer				
Margret Vi 79759	illalobos		10/14/2011		4		\$0.00
Medium	Work In Progress		10/14/2011 7:59:54 AM				•
Briones, E	•	On October 20, 2011, please pick from Desert View Elementary. Concluding Dulovich.					
Yolie Jacq	uez		10/17/2011		1		00.00
79838			10/17/2011		1		\$0.00
Medium	Work In Progress	SPED OFFICE	10/17/2011 11:04:40				
Briones, E	·	PO #101108760 PICK UP ONE BOX DELIVER TO REBECCA GARCIATEACHER- ELEMENTARY					
Margaret \ 77531	Villalobos	Office	8/29/2011		50		\$0.00
Medium	Work In Progress	Office	8/29/2011 3:18:32 PM		50		ψ0.00
	•						
Munoz, Mi	ichael	Move the existing counter toward the Office and move the Handica door. (Gonzalez)					
	e Gonzalez		0/0/0044		20		<u></u>
78124			9/9/2011		39		\$0.00
Medium	Work In Progress		9/9/2011 2:44:06 PM				
Munoz, Mi	ichael	need to construct concret pad for	trash dumpsters				

10/18/2011 1:23:07 PM Page 50 of 172

Alfredo Holguin

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time A Description	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Vi	ew ES				
79530		10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:40 AM				
Rivera, He	ctor	Monthly - QRTLY BLDG INSP REPORT (DV) - Refer to PM schedule details.				
Margret Vil 79159	lalobos	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:07 AM	. 6, . 6, 26	. •		ψ0.00
Ortiz, Rube	-	Monthly - Desert View ES Roof Inpsection - Refer to PM schedule details.				
Margret Vil	lalobos	40/0/0044	40/40/0044	40		# 0.00
79193	Warda ka Duannaa	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:29 AM				
Ortiz, Rube		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vil 79194	IAIODOS	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:29 AM				
Ortiz, Rube	en	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vil 79195	lalobos	10/2/2011		16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:30 AM				ψ0.00
Ortiz, Rube	-	Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret Vil	lalobos	40/0/2044	40/05/0044			# 0.00
79540	Warda ka Duannaa	10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:45 AM				
Ortiz, Rube	en	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.				
Margret Vil	lalobos	0/40/2044		20		<u> </u>
78433	Work In Progress	9/16/2011 0/16/2011 2:12:06 PM		32		\$0.00
Medium	Work In Progress	9/16/2011 3:12:06 PM				
Carrasco, I	Danny	Need 8 gal of Gas for 061 truck and 7gal for 402 Mower. Thank You				
Ruben Orti	z	10/11/2011		7		\$0.00
79631 Medium	Work In Progress			,		φυ.υυ
	Work In Progress	10/11/2011 2:19:08 PM				
Carrasco, I	Danny z	Need 7gal of Gas for 061 truck and 5 gal for 402 mower and 3 gal for 607 blowers and weedeaters. Thank you				

10/18/2011 1:23:07 PM Page 51 of 172

WOID Priority Assigned		Area Area Number Description	Deferred By		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Vi	iew ES						
77701				9/1/2011		47		\$0.00
Medium	Work In Progress			9/1/2011 11:08:36 AM				
Ortiz, Rube	en	please purchas	se new D130 john de g one.	eere lawn mower to				
Michael M	unoz			0/04/0044		40		#0.00
77616				8/31/2011		48		\$0.00
Medium	Work In Progress			8/31/2011 12:21:06 AM				
Ortiz, Rube	en	Monthly - Dese Refer to PM sc	ert View ES A-16 Far hedule details.	n Exhaust (Semi) -				
Margret Vil 79098	llalobos			10/2/2011	11/2/2011	16		\$0.00
	Model to Dronnes				11/2/2011	10		ψ0.00
Medium	Work In Progress			10/2/2011 12:26:34 AM				
Ortiz, Rube		Yearly - Desert Refer to PM sc	: View ES U-2 Unit H hedule details.	leat Gas Yearly -				
Margret Vil 79099	llalobos			10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:26:35 AM				,
Ortiz, Rube	-	Yearly - Desert PM schedule d		Coil Yearly - Refer to				
Margret Vi	llalobos							
78230				9/12/2011		36		\$0.00
Medium	Work In Progress			9/12/2011 4:48:33 PM				
Ortiz, Rube	en	Replace parkin	g signs for staff					
Ruben Ort	iz							
78231				9/12/2011		36		\$0.00
Medium	Work In Progress			9/12/2011 4:55:28 PM				
Ortiz, Rube	en	09/12/11 Put up No Tres to 5 a.m.	spassing sign betwee	en the hours of 9 p.m.				
Ruben Ort	iz							
75780				7/25/2011		85		\$0.00
Medium	Work In Progress			7/25/2011 1:22:23 PM				
Orozco, Da	anny		nt sink leaking—gask onstruction manager this.					

10/18/2011 1:23:07 PM Page 52 of 172

Aida Salcedo

Dalla alter	Building	Area Name Bases	Until Request Date Target C	A I	Labor Hours
Priority	Status	Area Number Reason	Created Date/Time Actual C	omp Date 11904 on Taken	Hours
Assigned [·] Requester		Description	Acti	on raken	
-					
_ocation:	Desert V	lew ES			
76349			8/3/2011	76	\$0.0
Medium	Work In Progress		8/3/2011 9:39:27 AM		
Orozco, Da	anny	1) VACUUM BREAKER TO FINAL DISHWASHER. 2) SHUT OFF VAI DISHWASHER IS ON BACK NEE FRONT. SNP MANAGER DIANA L	LVE TO D TO RESET TO		
Maritza Go	onzalez		8/4/2011	75	\$0.0
76430	\\\			75	φυ.υ
Medium	Work In Progress		8/4/2011 10:19:15 AM		
Orozco, Da	•	SCREEN DOOR NEEDS TO BE R KITCHEN. SNP MANAGER EMILI.	_		
<u>Maritza Go</u> 79895	onzalez	Cafeteria	10/18/2011	0	\$0.0
Medium	Work In Progress		10/18/2011 10:38:43		·
	-	DICLIMACHED IS CLOSSED LID			
Orozco, Da	anny	DISHWASHER IS CLOGGED UP.			
		DIANA L. SNP MGR 589-2425			
<u>Jacqueline</u> 79727	Aguilar	Office	10/13/2011	5	\$0.0
Medium	Work In Progress	Front Office	10/13/2011 9:17:57 AM	O .	ψ0.0
	Work In Progress				
Lara, Ralpl		Need a key for filing cabinet in the (Gonzalez)	office. I hanks.		
<u>Guadaiupe</u> 75482	e Gonzalez		7/14/2011	96	\$0.0
Medium	Work In Progress		7/14/2011 4:20:12 PM		
Flores, Pet	· ·	Lawnmower not working, need to h			
Ruben Orti	i 7	doesn't start. Thank you, Ruben			
76003			7/29/2011	81	\$0.0
Medium	Work In Progress		7/29/2011 9:00:38 AM		
Ortiz, Rube	en	Need to replace 16 120 sprinklers	and blubbers		
Ruben Orti	iz				
76002			7/29/2011	81	\$0.0
Medium	Work In Progress		7/29/2011 8:59:03 AM		
Ortiz, Rube	en	Need to fertilize the grass			
Ruben Orti	iz				
76000			7/29/2011	81	\$0.0
Medium	Work In Progress		7/29/2011 8:57:23 AM		
Ortiz, Rube	en	Need to remove dirt and drag week	ds on school grounds		

10/18/2011 1:23:07 PM Page 53 of 172

WOID Priority Assigned Requeste		Area Deferred By Area Number Reason Description	Until Request Date Targe Created Date/Time Actua	A	Labor Hours	
Location:	Desert Vi	ew ES				
77375			8/24/2011	55		\$0.00
Medium	Work In Progress		8/24/2011 4:27:33 PM			
Ortiz, Rub	en	Paint and put up no parking signs	S			
Ruben Or	tiz					
78966		Parking Lot	9/29/2011	19		\$0.00
Medium	Work In Progress		9/29/2011 8:32:29 AM			
Castillo, C	Carlos	F and J Electric installed wrong c irrigation booster pump. Dead fror fit with this breaker leaving expos to follow up to install correct circu	nt panel covers do not ed hot busbars.Need			
Carlos Ca 79334	stillo		10/3/2011	15		\$0.00
Medium	Work In Progress		10/3/2011 3:41:43 PM	10		ψ0.00
	_	l 11.11 ODED 01				
Castillo, C		need outlet for SPED room 24; sa	afety issue			
Ruben Or 79881	tiz		10/17/2011	1		\$0.00
Medium	Work In Progress		10/17/2011 4:04:45 PM			,
Castillo, C	_	room 36 lights are not working ne				
		Toom so lights are not working he	eds it worked on AGAI			
Ruben Or 78232	tiz		9/12/2011	36		\$0.00
Medium	Work In Progress		9/12/2011 4:59:30 PM			
Ortiz, Rub	_	Paint lower level bathroom floors	arav			
		T diff lower lover battilloom floore	giay			
Ruben Or 79331	uz		10/3/2011	15		\$0.00
Medium	Work In Progress		10/3/2011 3:40:11 PM			
Ambriz, Jo	ose	check office ac unit, not cooling				
Ruben Or		, ,				
76394	uz	Office	8/3/2011	76		\$0.00
Medium	Work In Progress	Teacher's	8/3/2011 3:45:11 PM			
Lara, Ralp	bh	Install a Door Closer in the Teach (Gonzalez)	ner's Lounge.			
Guadalup	e Gonzalez Work Orders	Avg. Age of WO's				\$0.00

10/18/2011 1:23:07 PM Page 54 of 172

Priority	Building Status	Area Deferred By Until Area Number Reason	Request Date Targe created Date/Time Actua	=	Days Aged	Labor Hours	
Assigned		Description		ction Taken			
Requester		2000 I piloti	, and the second	otion ranon			
Location:	GAC						
77515			8/29/2011		50		\$0.00
Medium	Work In Progress	8/29	9/2011 11:13:43 AM		00		ψ0.00
Lara, Ralp	-	NEED ONE A-39 KEY MADE.	7/2011 11.13.43 AW				
-		NEED ONE A-39 KET MADE.					
Maritza Go 79492	mzaiez		10/7/2011		11		\$0.00
Medium	Work In Progress	10	/7/2011 3:28:56 PM				
Lara, Ralp	h	second key need to be made for closet in C-liplease see Calixto for details	Ving -				
Cora Ram	irez		10/10/2011		8		\$0.00
79557	Model to Drawns				0		φυ.υυ
Medium	Work In Progress		0/10/2011 11:11:55				
Lara, Ralp		PLEASE ADJUST DOOR TO LOADING DO	JK.				
Maritza Go 78904	onzalez		9/28/2011		20		\$0.00
Medium	Work In Progress	9/2	28/2011 9:34:54 AM				·
Flores, Pe	-	Silver's van needs servicing # 135					
Cora Ram							
78482			9/19/2011		29		\$0.00
Medium	Work In Progress	9/	19/2011 7:57:11 AM				
Ontiveros,	Guadalupe	as per our coversation please check irrigation and BFP and clean up so that the rock wall a system can be removed. this is in the lower please do so. if not know so that sal can work on a permament of	round the parking lot. let me				
Michael M 76594	unoz		8/7/2011	9/7/2011	72		\$0.00
Medium	Work In Progress	8 <i>1</i>	7/2011 12:16:38 AM	3/1/2011	12		ψ0.00
Ambriz, Ju	_	Yearly - GAC A-9 Air Cooled Condensor Yea to PM schedule details.					
Margret Vi	llalobos	to i ivi donoculo dotalio.					
79306			10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	10/2	2/2011 12:28:33 AM				
Orozco, D	•	Monthly - GAC Fire Sprinkler Insp Refer to schedule details.	PM				
Margret Vi 78971	llalobos		9/29/2011		19		\$0.00
Medium	Work In Progress	Ann's old office 9/2	29/2011 9:13:34 AM				
Marquez,	-	Please move conference table and 6 chairs fold office to Chaparral Elem. Evenstart Progr PreK Office)	rom Ann's				
Lucia Alme	era <i>z</i>	•					

WOID	Building	•	arget Comp Date	Days	Labor	
Priority	Status -	Area Number Reason Created Date/Time A	•	Aged	Hours	
Assigned Decreases		Description	Action Taken			
Requester						
Location:	GAC					
79062		9/30/2011		18		\$0.00
Medium	Work In Progress	9/30/2011 4:29:51 PM				
Lara, Ralp	h	Entrance door on south side currently used to accecs GAC offices - install automatic door opener or door bell/buzzer that can be used by individuals with disabilities of open the door or get assistance to open the door				
Alfredo Ho	olguin	0/45/0044		64		CO. OO
76939		8/15/2011		64		\$0.00
Medium	Work In Progress	motor pool 8/15/2011 2:24:42 PM				
Flores, Pe	te	Please replace windshield wipers on car #9 Tina Guillen				
Lucia Alme	eraz	0/07/0044		04		#0.00
78814		9/27/2011		21		\$0.00
Medium	Work In Progress	9/27/2011 7:53:03 AM				
Carrasco,	·	please pick all the boxes, shelves and other material from the sped morgan maritza will give you access and deliver to the main building in anthony. contact person in anthony is margret villalobos (sped) please deliver to rm 102. thank you				
Michael M 79174	unoz	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:16 AM	10/10/2011	.0		φυ.σσ
	_					
Ambriz, Ju		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vi 79177	llalobos	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:18 AM	. 6, . 6, 26			ψυ.σσ
	_					
Ambriz, Ju	ıan	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vi	llalobos					
79526		10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:38 AM				
Ambriz, Ju	ıan	Monthly - GAC Playground Insp - Refer to PM schedule details.				
Margret Vi	llalobos	40/0/0044	40/0/2044	40		CO. OO
79279		10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:19 AM				
Ambriz, Ju	ıan	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.				
Margret Vi	llalobos					

10/18/2011 1:23:07 PM Page 56 of 172

WOID Priority Assigned Requester		Area Deferred By Until Request Date To Area Number Reason Created Date/Time Area Description	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	
Location:						
79302		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:31 AM				·
Orozco, D	_	Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.				
<u>Margret Vi</u> 74951	illalobos	7/4/2011	7/24/2011	106		\$0.00
Medium	Work In Brogross	7/4/2011 12:21:47 AM	7/24/2011	100		ψ0.00
Orozco, Da	Work In Progress anny	Monthly - GAC Fire Sprinkler Insp Refer to PM schedule details.				
Margret Vi	illalobos	Scriedule details.				
79015		9/30/2011		18		\$0.00
Medium	Work In Progress	9/30/2011 12:22:32 AM				
Marquez, (Gerardo	Monthly - GAC A-16 Fan Exh Roof Semimonthly - Refer to PM schedule details.				
Margret Vi 79106	illalobos	10/2/2011	10/18/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:39 AM	10/10/2011	10		ψ0.00
Ambriz, Ju	· ·	Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.				
Margret Vi	illalobos	40/0/0044	40/00/0044	4.0		<u>Фо оо</u>
79107	W 11 B	10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:39 AM				
Ambriz, Ju		Monthly - GAC F-39 Kitch Exh Makeup Ut Semimonthly - Refer to PM schedule details.				
<u>Margret Vi</u> 79108	illalobos	10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:40 AM				
Ambriz, Ju	•	Yearly - GAC U-2 Unit Heater Gas Yearly - Refer to PM schedule details.				
Margret Vi	illalobos					
79507		10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:29 AM				
Rodriguez		Monthly - QRTLY BLDG INSP REPORT (GAC) - Refer to PM schedule details.				
<u>Margret Vi</u> 79168	illalobos	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:12 AM		-		
Ambriz, Ju	•	Monthly - GAC Roof Inspection - Refer to PM schedule details.				
Margret Vi	illalobos					A
Count: 23	Work Orders	Avg. Age of WO's 26	Total for	GAC	0	\$0.00

10/18/2011 1:23:07 PM Page 57 of 172

Salacted Da	ate Range for Request	Dates:7/1/2011	6/30/2012 Ordor By I	ocation Status					Tota
WOID	Building	Area	Deferred By	Until		arget Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Crea	ated Date/Time A	ctual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requester	r Name								
Location:	GAC - Pr	e-K							
75337					7/12/2011		98		\$0.00
Medium	Work In Progress			7/12/2	2011 3:16:00 PM				
Ontiveros,	Guadalupe	NEED MORE S PLAYGROUNI	SAND FOR SANDE D.	3OX IN PRE-K					
Maritza Go	onzalez								
75814					7/26/2011		84		\$0.00
Medium	Work In Progress			7/26/2	2011 8:47:41 AM				
Ambriz, Jo	ose	A/C IN PRE-K PROPERLY.	CAFETERIA NOT (COOLING					
Maritza Go	onzalez								
79061					9/30/2011		18		\$0.00
Medium	Work In Progress			9/30/2	2011 4:25:11 PM				
Marquez,	Gerardo	Post sign on A ADA Accessab	DA ramp next to Pr el Ramp	e -k Center to	read "				
Alfredo Ho	olguin								
	Vork Orders	Α	vg. Age of WO's	67		Total for GAC - P	re-K	0	\$0.00

10/18/2011 1:23:07 PM Page 58 of 172

WOID Priority Assigned Requester		Area Area Number Description	Deferred By Reason	•	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	ES						
76934				8/15/2011		64		\$0.00
Medium	Work In Progress			8/15/2011 1:35:39 PM	Л			
Appelzollei	r, Fred		lve connector on t	he south side wall e in this matter				
Loraine Ga	ındara			2///22/				
77694		Classroom		9/1/2011		47		\$0.00
Medium	Work In Progress	washigton wk		9/1/2011 9:11:36 AM	Л			
Lozoya, Ma	anny	requesting an a Washington Wl	additional key for M k room	1r. Hinojosa for				
Loraine Ga	ındara	Office		10/17/2011				60.00
79853		Office				1		\$0.00
Medium	Work In Progress			10/17/2011 2:47:07 PM	Л			
Lozoya, Ma	anny	•	locks for weekend assistance in this					
<u>Loraine Ga</u> 79856	ındara	Office		10/17/2011		1		\$0.00
	Work In Drogroop	Omice				'		ψ0.00
Medium	Work In Progress			10/17/2011 2:56:03 PM	/I			
Lozoya, Ma	•	•	to be accompnied ate your assistance	by 18 inch chains e				
Loraine Ga 76334	ındara			8/2/2011		77		\$0.00
Medium	Work In Progress	nurses office		8/2/2011 4:03:53 PM				ψ0.00
Moncayo, I	· ·		ssistance in puttin	g up boards in her	n			
Loraine Ga	ındara	omoo						
77207				8/22/2011		57		\$0.00
Medium	Work In Progress			8/22/2011 10:38:11 AM	Л			
Moncayo, I	Fernando	ROOF LEAK IN 882.3410	I KITCHEN, SNP I	MANAGER CUCA P.				
Maritza Go	nzalez							
78166				9/11/2011	9/27/2011	37		\$0.00
Medium	Work In Progress			9/11/2011 12:20:44 AM	Л			
Moncayo, I		Monthly - Gads schedule detail	den ES - Playgrou s.	nd Insp - Refer to PM				
Margret Vil 79517	lalobos			10/9/2011	10/25/2011	9		\$0.00
	Mank In Dec					J		ψυ.υυ
Medium	Work In Progress			10/9/2011 12:16:34 AM	/I			
Moncayo, I	Fernando	Monthly - Gads schedule detail		nd Insp - Refer to PM				

10/18/2011 1:23:07 PM Page 59 of 172

Costs oor urs		-	Dates:7/1/2011 - 6/30/2012 Order By Location, Status Area Deferred By Until Request Date Tar Area Number Reason Created Date/Time Act Description	D Building ity Status	WOID Priority Assigned
			ES	tion: Gadsden	Location:
\$0.00	44	9/15/2011	9/4/2011	5	77845
			9/4/2011 12:24:17 AM	um Work In Progress	Medium
			Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.	cayo, Fernando	Moncayo,
\$0.00	16	10/13/2011	10/2/2011	ret Villalobos	Margret Vil
φ0.00	10	10/13/2011			
			10/2/2011 12:28:16 AM	3	Medium
			Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.	cayo, Fernando	-
\$0.00	79	8/21/2011	7/31/2011	ret Villalobos 8	Margret Vil 76068
·			7/31/2011 9:24:51 AM		Medium
			Monthly - Gadsden ES Fire Sprinkler Insp -Qrtly - Refer to PM schedule details.	-	Orozco, Da
				ret Villalobos	
\$0.00	35		9/13/2011		78241
			9/13/2011 8:49:13 AM	um Work In Progress	Medium
			Need diesel fuel for lawn mower ge o433	asco, Danny	Carrasco,
\$0.00	7	10/26/2011	10/11/2011	ando Moncayo	
φυ.υυ	,	10/26/2011			79596
			10/11/2011 12:16:20 Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PM schedule details.	Ü	Medium Pinon, Jose
				s Estrada	Jesus Estr
\$0.00	44		9/4/2011	4	77844
			9/4/2011 12:24:16 AM	um Work In Progress	Medium
			Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.	cayo, Fernando	Moncayo, I
\$0.00	26		9/22/2011	ret Villalobos	
φυ.υυ	20				78664
			9/22/2011 10:27:24 AM	3	Medium
			Collect Equipment data and inventory per PFSA requirements.	uin, Alfredo	Holguin, Al
\$0.00	16	10/10/2011	10/2/2011		Alfredo Ho 79219
ψ0.00	10	10/10/2011	10/2/2011 12:27:44 AM		Medium
				_	
			Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.	cayo, Fernando	Moncayo, I
			Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer	cayo, Fernando ret Villalobos	-

10/18/2011 1:23:07 PM Page 60 of 172

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By Lo Area Deferred By Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	ES					
79220			10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:44 AM				
Moncayo,	Fernando	Monthly - Gadsden ES - Emer Ligh Refer to PM schedule details.	t Test - Monthly -				
Margret Vi	llalobos		40/0/0044		40		Φο οο
79222			10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:45 AM				
Moncayo,		Monthly - Gadsden ES - Clothes Dito PM schedule details.	ryer (Monthly) - Refer				
Margret Vi 79774	llalobos	Office	10/14/2011		4		\$0.00
Medium	Work In Progress		10/14/2011 1:29:04 PM		·		Ψ0.00
Lozoya, M	anny	need to replace door closer from or in the main entrancegreatly appre in this matter	ne of the front doors				
Loraine Ga 78975	andara		9/29/2011		19		\$0.00
Medium	Work In Progress		9/29/2011 9:49:31 AM				
Arreola, R	udy	please support with grounds work a you	and irrigating. thank				
Michael M	unoz	Athletic Field	40/40/0044				<u>ФО ОО</u>
79673		Athletic Field	10/12/2011		6		\$0.00
High	Work In Progress		10/12/2011 8:23:02 AM				
	Guadalupe	need to spread out sand for better of holding pond	drianage along				
<u>Guadalupe</u> 76933	Ontiveros		8/15/2011		64		\$0.00
Medium	Work In Progress		8/15/2011 1:34:16 PM				·
Moncayo,	· ·	please set up irrigation system for rethe school greatly appreciate you matter					
Loraine Ga	andara		0/04/0044		EF		ድስ ስሳ
77320	Mould by Day		8/24/2011		55		\$0.00
Medium	Work In Progress		8/24/2011 8:18:18 AM				
Moncayo,	Fernando	water daily in the morning planters until irrigation system is in place g your assistance in this matter					
Loraine Ga	andara						

10/18/2011 1:23:07 PM Page 61 of 172

WOID Priority	Building Status	Area Area Number	6/30/2012 Order By L Deferred By Reason		•	Days Aged	Labor Hours	Costs
Assigned		Description			Action Taken			
Requester								
Location:	Gadsden	ES						
78372		Hallway/Corride	or	9/15/2011		33		\$0.00
Medium	Work In Progress			9/15/2011 7:53:01 AM	1			
Moncayo,	Fernando		rs need to be raked oved greatly appr iis matter					
Loraine Ga	andara			8/23/2011		56		\$0.00
77297						96		\$0.00
Medium	Work In Progress			8/23/2011 3:51:26 PN	Л			
Moncayo,	Fernando	need the trench	ning machine and th	e line locate for GES				
Fernando	Moncayo							
77578				8/30/2011		49		\$0.00
Medium	Work In Progress			8/30/2011 11:21:44 AM	1			
Marquez, (Gerardo	please repair c	racks walls, texture	and paint thru-out				
Michael M	unoz			0/0/0044				Φο οο
78065		Computer Lab		9/8/2011		40		\$0.00
Medium	Work In Progress	201		9/8/2011 10:26:56 AN	Л			
Moncayo,	Fernando		ce with the vent in r ate your assistance	oom 201 bathroom				
Loraine Ga	andara			0/0/0044				Φ0.00
78093		Classroom		9/8/2011		40		\$0.00
Medium	Work In Progress	204		9/8/2011 3:39:22 PN	Л			
Moncayo,	Fernando	please check a appreciate you		d loud noise greatly				
Loraine Ga	andara			0/40/0044				Ф0.00
77140				8/19/2011		60		\$0.00
Medium	Work In Progress			8/19/2011 9:01:22 AM	Л			
Orozco, Da	anny	LEAK IN KITCH 882.3410	HEN ROOF.SNP MA	ANAGER CUCA P.	AS PER FERNAND ON IT.	O, HE IS	WORKING	3
Maritza Go	onzalez							
78964		Office		9/29/2011		19		\$0.00
Medium	Work In Progress	front office		9/29/2011 8:02:33 AM	1			
Lozoya, M	anny		ffice need hing to be r assistance in this i					
Loraine Ga	andara		vg. Age of WO's		Total for Gadsde			\$0.00

10/18/2011 1:23:07 PM Page 62 of 172

	Building	Area Deferred By	Until Request Date Target Comp I	A1	Hours	
Priority	Status -	Area Number Reason	Created Date/Time Actual Comp D	alc -	nours	
Assigned [*]		Description	Action Tal	ken		
Requester						
_ocation:	Gadsden	HS				
78637			9/21/2011	27		\$0.00
Medium	Work In Progress		9/21/2011 3:36:11 PM			
Appelzollei	r, Fred	Please replace leaking electric water panther Hood. Thank you	heater (40 Gal) in			
<u>Guillermo I</u> 78938	<u>-lernandez</u>		9/28/2011	20		\$0.00
Medium	Work In Progress		9/28/2011 3:58:51 PM			
Appelzollei	r, Fred	Requested by Coach Lopez Rm. 105 Water heater is leaking water in one stations.				
<u>Velia Alarc</u> 79418	on		10/5/2011	13		\$0.00
Medium	Work In Progress		10/5/2011 12:29:12 PM	10		ψ0.00
	· ·					
Appelzollei 		URINAL IS BROKEN ON BOYS RI OLD ENGLISH BUILDING.	EST ROOM AT			
<u>Joel Herrei</u> 79579	ra		10/10/2011	8		\$0.00
Medium	Work In Progress		10/10/2011 3:14:19 PM			
Appelzollei	r, Fred	Need assistance to uncloge the sew water started coming out of the clear cafeteria. Thank you				
<u>Guillermo I</u> 79780	Hernandez Business	Restroom (Boys)	10/14/2011	4		\$0.00
		Restroom (Boys)		7		ψ0.00
Medium Appelzollei	Work In Progress r, Fred	Need to replace faucet on the sink in	10/14/2011 3:28:11 PM the mens restroom			
Guillermo I	Hernandez	second floor. Thank you				
79836	Concession		10/17/2011	1		\$0.00
Medium	Work In Progress		10/17/2011 10:53:40			
Appelzollei	r, Fred	Requested by Ms. Servin for Footbal -Replace small sink with a large stair Also, up grade faucet fixtures.				
<u>Velia Alarc</u> 78772	on		9/26/2011	22		\$0.00
Medium	Work In Progress		9/26/2011 11:13:48 AM	22		ψ0.00
	Work In Progress , Guillermo	Requested by Mr. D. Martinez for Ca that the window frames inside and ou cafeteria be painted the same color a doors. -The color for the cafeteria doors was of 09/19/11. We would like to match to the color on the window frames of	feteria-Requesting utside of the us the cafeteria s chosen the week the color requested			
		Administrative/Library Building.				

WOID Priority	Building Status	Dates:7/1/2011 - 6/30/2012 Order By L Area Deferred By Area Number Reason		Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned	То	Description		Action Taken			
Requester		·					
Location:	Gadsden	HS					
78777			9/26/2011		22		\$0.00
Medium	Work In Progress		9/26/2011 11:48:49 AM				
Herrera, Jo	•	Requested by Mr. D. Martinez-Afte 78775 is completed. The short blu the Cafeteria needs to be painted.	er WORK ORDER #				
Velia Alaro 77250	con Academic Bldg	Hallway/Corridor	8/23/2011		56		\$0.00
Medium	Work In Progress		8/23/2011 7:09:44 AM				******
Munoz, Jo	_	Hallway walls need to be scrubbed		9/21/11 - RE-MAILE	D TO JO	E	
Jesus Estr							
77769	lada		9/2/2011		46		\$0.00
Medium	Work In Progress		9/2/2011 11:12:33 AM				
Munoz, Jo	e	Requested by Velia for New Admir Three paper towel dispensers are installed in the Women's and Men' third in the Work Room # 724. PLE COSTALEZ or VELIA FOR FURTH	needed. One To be s Restrooms. The EASE SEE DEBBIE	9/6 - e-mailed & mail 9/21 - re-mailed to jo		order to jo	oe.
Velia Alaro	con		9/6/2011		42		\$0.00
Medium	Work In Progress		9/6/2011 9:30:38 AM				******
Munoz, Jo	e	FIRST HOME GAME TONIGHT, N SPIDER WEBS ON DOORS TO G SOUTH FROM NEW ADMINISTR	SYM (COMING	9/21 - remailed to joe	е		
Margaret \ 78823	<u>/illalobos</u> Business	Restroom (Boys)	9/27/2011		21		\$0.00
		Restroom (boys)			21		φυ.υυ
High	Work In Progress		9/27/2011 8:25:44 AM				
Munoz, Jo	e	Detail all bathrooms in businesss the walls and fixtures. Strip down floor					
Jesus Estr 78673	rada		9/22/2011		26		\$0.00
Medium	Work In Progress		9/22/2011 2:24:22 PM		20		ψ0.00
	_	Need 10 ages of aprovibile prime					
Hernandez	z, Guillermo	Need 10 cases of spray kilz primer paint over grafitti in restrooms wall					
Guillermo 78771	Hernandez		9/26/2011		22		\$0.00
Medium	Work In Progress		9/26/2011 11:08:07 AM				ψ0.00
Hernandez	z, Guillermo	Requested by Mr. D. Martinez for (Requesting to have the awnings lo entrances of the cafeteria painted cafeteria doors.	Cafeteria Entrance- cated outside the				
Velia Alaro	con						

10/18/2011 1:23:07 PM Page 64 of 172

Assigned Requester		Area Number Reason Created Date/Time Description	Actual Comp Date Action Taken	Aged Hours	
Location:	Gadsden	HS			
76762		8/10/2011		69	\$0.00
Medium	Work In Progress	8/10/2011 9:12:44 AM	И		
Ontiveros,	Guadalupe	Requested by Coach Yanez for Baseball Field-Move baseball storage shed directly behind dugout and surround it with a fence and gate to prevent any more thefts of our equipment.			
Velia Alaro	on	9/21/2011	1	27	\$0.00
78598	W 11 B			21	Φ0.00
Medium	Work In Progress	9/21/2011 9:13:59 AN	Л		
	Guadalupe	Requested by Coach Yanez for Baseball Field-Cut out "warning-track" along the inside of the whole baseball field to include outfield, in front of backstop, along left field and along right field fences and in front of dugouts.			
Velia Alaro 79573	on	10/10/2011	<u> </u>	8	\$0.00
Medium	Work In Progress	10/10/2011 2:17:26 PM		-	******
	Guadalupe	Requested by Coach Yanez-Set up batting cage with older brackets/poles. Add new cage set up next to the longer cage already in place to make it a double cage.			
Velia Alaro	on	10/17/2011	1	1	\$0.00
	Madala Dasassa			ı	Φ0.00
Medium	Work In Progress	10/17/2011 10:41:2-	4		
	Guadalupe	Requested by Coach Letz for Tennis Courts-Put new net on court # 5.			
Velia Alaro 79487	con Cafeteria (1998)	Cafeteria 10/7/2011		11	\$0.00
					ψ0.00
	Work In Progress	10/7/2011 3:14:42 PM	Л		
Castillo, Ca	arlos	As per Alfredo Holguin-check two serving line curtains not working as per Ada.			
Carlos Cas					Ф0.00
76915	Concession	Football Field 8/15/2011	I	64	\$0.00
High	Work In Progress	8/15/2011 8:40:08 AM	Л		
Munoz, Jo	е	Please make sure everthing is clean at Concession StandFloor, Windows, Kitchen area and restrooms.	9/21/11 RE-MAILED	TO JOE	
Michael M		Library 7/20/2014	<u> </u>	01	¢0.00
76012	Library	Library 7/29/2011		81	\$0.00
Medium	Work In Progress	7/29/2011 12:58:58 PM	Л		
Gallegos, I	Rafael	Warranty several arius on the carpet are coming			

10/18/2011 1:23:07 PM Page 65 of 172

Page 66 of 172

1200 - Work Orders In Progress (Fiscal Year)

WOID Priority Assigned	Building Status To	Area Deferred By Area Number Reason Description	Until Request Date Targ	A	
Requester		•			
Location:	Gadsden	HS			
75781	Main Building	Classroom	7/25/2011	85	\$0.00
Medium	Work In Progress		7/25/2011 2:01:50 PM		
Solis, Lore	enzo	Need to put new vents for ac units balance out air on the east side of			
<u>Mario Apo</u> 76747	odaca		8/10/2011	69	\$0.00
High	Work In Progress		8/10/2011 8:05:35 AM	00	ψ0.00
	_	Loo Machine not working at groups			
Ambriz, Jo		Ice Machine not working at ground	15 SHOP		
Guadalupe 77046	e Ontiveros		8/17/2011	62	\$0.00
Medium	Work In Progress		8/17/2011 9:30:10 AM		
Holguin, A		Requested by Ms. Seiler for Rm. 1 Building-Room has become increa causing allergic reactions in me ar in students whom I serve here at C has indicated to me that they are I room to move me to, until they car with an air purifier to purify the air health effects of the poor air qualit	asing in mold and is and may very possibly BHS. Administration booking for another by Please provide me and minimize the		
Velia Alaro 78696	con		9/22/2011	26	\$0.00
Medium	Work In Progress		9/22/2011 3:44:54 PM		ψ0.00
Ambriz, Jo	•	Please check ice maker in the train			
	Hernandez	Trouge directives maker in the train	ming room. Thank you		
76761	Hemanuez		8/10/2011	69	\$0.00
Medium	Work In Progress		8/10/2011 9:04:47 AM		
Ontiveros,	, Guadalupe	Requested by Coach Hite for Prac Need both practice Football Fields Football and Band can use for pra using stadium field. If possible before week.	marked so that ctice when Soccer is		
Velia Alaro	con		40/47/0044		ФО О
79832	W 11 5		10/17/2011	1	\$0.00
Medium	Work In Progress		10/17/2011 10:43:22		
Hernande	z, Guillermo	Requested by Cathy Cano-Need a by Oct. 24. PLEASE SEE CATHY			

INSTRUCTIONS.

Velia Alarcon

10/18/2011 1:23:07 PM

WOID Priority Assigned ^o Requester		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Labor Aged Hours	
Location:	Gadsden	HS				
79816			10/17/2011		1	\$0.00
Medium	Work In Progress	SPED OFFICE	10/17/2011 10:16:31	1		
Briones, Eı	nrique	PO #101108760 PICK UP ONE BOX DELIVER TO GILLIAN NEVAREZ-TEACHER-G SCHOOL				
Margaret V 79818	/illalobos		10/17/2011		1	\$0.00
	W 11 D				ı	φυ.υυ
Medium Briones, E		SPED OFFICE PO #101108760 PICK UP ONE BOX DELIVER TO ALBERT LAWRENCETEACHEI SCHOOL				
Margaret V 79819	/IIIaiodos		10/17/2011		1	\$0.00
Medium	Work In Progress	SPED OFFICE	10/17/2011 10:20:26	5		
Briones, Eı	nrique	PO #101108760 PICK UP ON BOX DELIVER TO TOM MARTIN-TEACHER-GADSI	DEN HIGH SCHOOL			
Margaret V 78082	/illalobos Boys Gym		9/8/2011		40	\$0.00
			9/8/2011 3:11:51 PN		40	ψ0.00
Medium Ontiveros,	Work In Progress Guadalupe	By boys gym outside site walk ne about 20 feet for the wheelchairs	eds to be repaired	И		
Mario Apod 77276	daca North Building	Restroom (Boys)	8/23/2011		56	\$0.00
	· ·	Restroom (Boys)			30	ψ0.00
Medium Estrada, Je	Work In Progress	due to a water leak there could be soccer fields restroom bldg and so are bubbling up				
Mario Apod	daca		10/2/2011		16	\$0.00
79244					10	φυ.υυ
Medium Sanchez, F	Work In Progress Raul	Monthly - Gadsden HS - Monthly to PM schedule details.	10/2/2011 12:27:59 AM Water Samples - Refer	1		
Margret Vil	llalobos					
79248			10/2/2011		16	\$0.00
Medium	Work In Progress		10/2/2011 12:28:01 AM	1		
Sanchez, F	Raul	Monthly - Gadsden HS - Monthly Refer to PM schedule details.	Meter Readings -			
Margret Vil	llalobos					

10/18/2011 1:23:07 PM Page 67 of 172

WOID Priority Assigned [:] Requester		Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time Ac Description	-	Days Aged	Labor Hours	
ocation:	Gadsden	HS				
79753		10/14/2011		4		\$0.00
Medium	Work In Progress	10/14/2011 12:17:22				
Sanchez, F	Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.				
Margret Vil	llalobos	10/2/2011	10/8/2011	16		\$0.00
79277 Medium	Work In Progress	10/2/2011 12:28:18 AM	10/0/2011	10		ψ0.00
Herrera, Jo	-	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.				
<u>Margret Vil</u> 79290	llalobos	10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:25 AM	10/20/2011	.0		φοιοι
Orozco, Da	-	Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.				
Margret Vil	llalobos					
78601		9/21/2011		27		\$0.00
Medium	Work In Progress	9/21/2011 9:20:34 AM				
	z, Guillermo	Requested by Mrs. M. Grubaugh-Ms. Jaraba is donating her piano to the choir (Ms. Miller). Piano needs to be carefully moved from room 124 in the Main Building to room #344 in the Academic Building.				
Velia Alarc 79206	on	10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:36 AM				•
Herrera, Jo	-	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.				
Margret Vil	llalobos	12/2/2011				
79207		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:37 AM				
Herrera, Jo		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.				
<u>Margret Vil</u> 75447	llalobos	7/14/2011		96		\$0.00
Medium	Work In Progress	7/14/2011 12:16:25 AM				,
Sanchez, F	_	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.				
	llalobos	(

10/18/2011 1:23:07 PM Page 68 of 172

WOID Priority Assigned		Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ad	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	
Requester		пе					
Location:	Gadsden	по					
75625			7/21/2011		89		\$0.00
Medium	Work In Progress		7/21/2011 10:20:47 AM				
Sanchez, I	Raul	Domestic Water Storag Tank- Perinspections of interior of tank incompection needs to be performed D101-53 Standard.	luding the one at GMSI				
Alfredo Ho 76903	lguin		8/14/2011		65		\$0.00
Medium	Work In Progress		8/14/2011 12:18:19 AM		00		ψ0.00
	Work In Progress						
Sanchez, F		Monthly - Gadsden HS-WWTP ((Monthly) - Refer to PM schedule					
Margret Vil 78298	lalobos		9/14/2011		34		\$0.00
Medium	Work In Progress		9/14/2011 12:17:23 AM				*
Sanchez, I	•	Monthly - Gadsden HS-WWTP C	Chemical Order				
Margret Vi	lalohos	(Monthly) - Refer to PM schedule	e details.				
77893	Idiobos		9/4/2011	9/12/2011	44		\$0.00
Medium	Work In Progress		9/4/2011 12:24:37 AM				
Hernandez	, Guillermo	Monthly - Gadsden HS Exit Sign PM schedule details.	Insp: Monthly - Refer to				
Margret Vi							
78665	New Admin Bldg		9/22/2011		26		\$0.00
Medium	Work In Progress		9/22/2011 10:28:44 AM				
Holguin, Al		Collect Equipment data and inversequirements New Admin, New Gym Addition					
Alfredo Ho 79237	lguin		10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:55 AM		.0		Ψ0.00
Holguin, Al	· ·	Monthly - Gadsden HS Generato					
Margret Vi	lalohos	to Fivi scriedule details.					
79221			10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:45 AM				
Hernandez	, Guillermo	Monthly - Gadsden HS - Elevato PM schedule details.	r (Monthly) - Refer to				

10/18/2011 1:23:07 PM Page 69 of 172

Selected Dat WOID Priority	te Range for Request Building Status	Dates:7/1/2011 - 6/30/2012 Order By Location, Status Area Deferred By Until Request Date T Area Number Reason Created Date/Time A	arget Comp Date	Days Aged	Labor Hours	Costs
Assigned 1		Description Oreated Bate/Time A	Action Taken			
Requester		2.55.4				
Location:	Gadsden	HS				
79224		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:46 AM				
Hernandez	, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vill	alobos	10/2/2011		16		\$0.00
79204	Work In Drogram			10		φυ.υυ
Medium	Work In Progress	10/2/2011 12:27:35 AM				
Herrera, Jo		Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.				
<u>Margret Vill</u> 79082	alobos	10/2/2011	10/18/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:25 AM				
Hernandez	, Guillermo	Monthly - Gadsden HS A1 (Air Dryer)(S.Annual) - Refer to PM schedule details.				
Margret Vill	alobos	40/0/0044	40/00/0044	40		Ф0.00
79083		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:26 AM				
Hernandez		Monthly - Gadsden HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.				
<u>Margret Vill</u> 79525	alobos	10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:38 AM				
Munoz, Joe	•	Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.				
Margret Vill	alobos	7/4/2011	7/11/2011	106		\$0.00
75039	Mantala Dasanasa		7/11/2011	100		φυ.υυ
Medium	Work In Progress	7/4/2011 12:22:27 AM				
Apodaca, N	/lario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.				
Margret Vill	alobos	40/0/0044	40/40/0044	40		Φο οο
79155		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:05 AM				
Hernandez		Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.				
<u>Margret Vill</u> 74912	alobos	7/4/2011		106		\$0.00
Medium	Work In Progress	7/4/2011 12:21:29 AM				
Holguin, Alf	-	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.				
	alobos					

10/18/2011 1:23:07 PM Page 70 of 172

WOID Priority Assigned	Building Status	Area Number Description	6/30/2012 Order By Lo Deferred By Reason		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		•						
Location:	Gadsden	HS						
79067				10/2/2011	10/5/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:26:17 AM				
Herrera, Jo	pel	Monthly - Gads Refer to PM sc	sden HS - Emerg. Ey hedule details.	yewash (Monthly) -				
Margret Vil	lalobos			0/44/0044		0.7		Φο οο
78172				9/11/2011		37		\$0.00
Medium	Work In Progress			9/11/2011 12:20:48 AM				
	r, Guillermo	Monthly - Gads Refer to PM so	den HS A16 (Fan E hedule details.	xh.)(S.Annual) -				
Margret Vil 79142	lalobos			10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:26:58 AM				******
	, Guillermo	Yearly - Gadsd PM schedule d	en HS H6 (Furnace)					
Margret Vil	lalobos	i iii concadio d	otalio:					
79143				10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:26:58 AM				
Hernandez	, Guillermo	Yearly - Gadsd to PM schedule		diator)(Yearly) - Refer				
Margret Vil	lalobos			40/0/0044	44/0/0044	40		<u></u>
79100				10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:26:35 AM				
Herrera, Jo		Yearly - Gadsd schedule detail		Yearly) - Refer to PM				
Margret Vil 79081	lalobos			10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:26:25 AM				*****
	, Guillermo	Yearly - Gadso		(Yearly) - Refer to PM				
Margret Vil	lalobos	corrodate detail	.					
78775				9/26/2011		22		\$0.00
Medium	Work In Progress			9/26/2011 11:42:30 AM				
Ontiveros,	Guadalupe	the dirt be rem the short blue/o *Please let us l	Mr. D. Martinez-Req oved from arond the gray wall in front of t know if this W.O. cal ool Board meeting in	he Cafeteria. n be completed				
Velia Alarc	on		· · · · · · · · · · · · · ·					

10/18/2011 1:23:07 PM Page 71 of 172

WOID	Building	Area Deferred By	Until Request Date Targe		Labor	
Priority	Status	Area Number Reason	Created Date/Time Actu	•	Hours	
Assigned '		Description	•	Action Taken		
Requester						
Location:	Gadsden	HS				
79355		Athletic Field	10/4/2011	14		\$0.00
High	Work In Progress		10/4/2011 8:04:58 AM			
Lara, Ralpl	'n	Jose vasques needs keys- HE163 A70.	-HE160-HE157-MA-			
	Ontiveros		10/12/2011	6		\$0.00
79688	W 11 D			0		φυ.υυ
High	Work In Progress		10/12/2011 11:12:36			
Ontiveros,	Guadalupe	receiced a call that a student had the nurces office. please check ar thank you				
<u>Michael Mı</u> 78269	unoz	Athletic Field	9/13/2011	35		\$0.00
Medium	Work In Progress	7 tanota i loid	9/13/2011 3:25:00 PM	00		φ0.00
	-					
Flores, Pet		Truck # 137 needs transmission o Also motor oil and filter.	il and filter changed.			
78153	Ontiveros	Football Field	9/9/2011	39		\$0.00
Medium	Work In Progress		9/9/2011 3:55:16 PM			
Holguin, A	fredo	Running Track- needs the ruberize various places and lines repaitted also needs repairs.				
	Ontiveros	E 4 11E: 11	0/0/0011			Φ0.00
78123	Football Stadium	Football Field	9/9/2011	39		\$0.00
Medium	Work In Progress		9/9/2011 2:39:05 PM			
,	Guadalupe	1 more section of fence needs to football field on the north end of ca	•			
<u>Mario Apod</u> 76503	daca		8/5/2011	0		\$0.00
Medium	Work In Progress		8/5/2011 11:12:06 AM	8/5/2011		φ0.00
	_					
Gonzalez,		Requested by Lupe Quinones for Install a cement ramp at the left fathe North Building. This ramp will go with the Security Golf Cart as we Maintenance Cart. By placing this two parking spaced eliminated. For please see Lupe Quinones.	or end by the "G" hall of admi serve as a come and well as for ramp there well be	1 - This needs to be applinistration. M. Munoz	proved by I	new
<u>Velia Alaro</u> 79319	on Cafeteria (1998)		10/3/2011	15		\$0.00
Medium			10/3/2011 9:11:20 AM	10		ψυ.υυ
ivieaium Munoz, Mi	Work In Progress	Replace existing red-tagged range				
		system as well as system tanks				

10/18/2011 1:23:07 PM Page 72 of 172

Page 73 of 172

1200 - Work Orders In Progress (Fiscal Year)

10/18/2011 1:23:07 PM

WOID	Building	Area Number Bessen	Until Request Date Target Comp Date	Days Aged	Labor Hours	
Priority Assigned [•]	Status	Area Number Reason Description	Created Date/Time Actual Comp Date Action Taken	Ageu	Hours	
Assigned Requester		Description	Action Taken			
Location:	Gadsden	HS				
79023	Guasacii		9/30/2011	18		\$0.00
Medium	Work In Progress		9/30/2011 7:12:06 AM	10		ψ0.00
Carrasco,	· ·	Need 15 Gal of fuel for truck #28. T				
		Need 15 Gai of fuel for truck #20. I	Halik you			
79775	Hernandez Academic Bldg	Restroom (Boys)	10/14/2011	4		\$0.00
Medium	Work In Progress		10/14/2011 2:06:46 PM			
Lara, Ralp	h	Need to clean out cores on the resof glue. Thank you	stroom doors, core full			
<u>Guillermo l</u> 79674	Hernandez Cafeteria (1998)		10/12/2011	6		\$0.00
79674 Medium	Work In Progress		10/12/2011 8:26:11 AM	U		ψ0.00
Ronquillo,	· ·	BROKEN WINDOW AT CAFETER				
		20 3/4 INCHES SINGLE GLASS				
<u>Joel Herre</u> 76311	<u>ra</u> North Building	Classroom	8/2/2011	77		\$0.00
Medium	Work In Progress		8/2/2011 11:01:44 AM			
Lara, Ralp	h	Need new door for room 214 Do to building	o vandalism north			
<u>Mario Apod</u> 75292	daca Varsity Gym	Custodial	7/11/2011	99		\$0.00
Medium	Work In Progress		7/11/2011 2:18:37 PM			
Gonzalez,	Salvador	Need to weld a top rail to storage of	age in the v-gym			
Mario Apo						
75465			7/14/2011	96		\$0.00
Medium	Work In Progress	Weight Room	7/14/2011 1:13:44 PM			
Gonzalez,	Salvador	Need to re-install punching bag in v	weight room.			
Michael Mi	unoz		9/29/2011	19		\$0.00
78967 Medium	Work In Progress		9/29/2011 8:40:19 AM	19		φυ.υυ
	_	0/00/44	9/29/2011 0.40.19 AWI			
Gonzalez,	Salvadoi	9/28/11 I need welder to fabricate (2) steel blower system at wastewater treatr square valve key for opening water Raul	ment plant, also a			
Raul Sanc			0/0/0044	74		<u></u>
76665	Main Building		8/8/2011	71		\$0.00
Medium	Work In Progress		8/8/2011 4:22:51 PM			
Lara, Ralp	h	Requested by Ms. Arredondo Rm. Drill door knobs.	106 Main Building-			
Velia Alarc	con					

WOID Priority Assigned Requester	Building Status To	_	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
77763			9/2/2011		46		\$0.00
Medium	Work In Progress	9/2/201	1 10:38:16 AM				
Lara, Ralp	h	Requested by Velia for New Adminstative Building door to Office # 702 does not automaticaly close v door is pulled shut.					
Velia Alaro 78901	con Cafeteria (1998)	Mechanical	9/28/2011		20		\$0.00
Medium	Work In Progress		11 8:52:16 AM				,
Carrasco,	_	Need warehousemen to transport scissor lift to GF cafeteria area.					
Carlos Car	stillo		10/17/2011		1		\$0.00
79830 Medium	Work In Progress	10/47/	2011 10:39:41		'		ψ0.00
Herrera, Jo	ŭ	Requested by Mary Barreras Rm. 109 Special EdLight fixture is out and needs to be replaced.					
Velia Alaro	con		40/47/0044		4		Ф0.00
79833		40/47	10/17/2011		1		\$0.00
Medium Hernandez	Work In Progress z, Guillermo	Requested by Mrs. Lerma for Football Concession Stand-Remove grey metal shelf (located on the Nowall) in the Football Concession Stand to make roa new Coke Cola refrigerator.	orth				
Velia Alaro	con		7/04/0044		00		# 0.00
75626	W 11 5	7/04/004	7/21/2011		89		\$0.00
Medium Sanchez,	Work In Progress Raul	Domestic Water Storage Tank- install a 24" mesh screen or flapper valve on the overflow pipe. Do the same to the tank at GMS					
Alfredo Ho	olguin		0/7/0044		44		# 0.00
78025		27/22	9/7/2011		41		\$0.00
Medium	Work In Progress		11 2:42:56 PM				
Moncayo,		Remove three large portable cafeteria food serving Kiosks from the GHS cafeteria.	g				
Maritza Go 79324	onzalez		10/3/2011		15		\$0.00
Medium	Work In Progress	10/3/201	1 10:51:50 AM				40.00
Orozco, Da	_	1) HINGES ON ITALIAN LINE WARMER NEED T REPLACED. 2) 2 BOTTOM OVENS NEED TO BE LOOKED AT, NOT WORKING PROPERLY. SNP MANAGER LILY M. 882.5522	ОВЕ				
Maritza Go	onzalez						

10/18/2011 1:23:07 PM Page 74 of 172

WOID	ite Range for Request Building	Area	Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned '		Description			Action Taken			
Requester	Name							
Location:	Gadsden	HS						
79802				10/17/2011		1		\$0.00
Medium	Work In Progress			10/17/2011 8:28:25 AN	Л			
Orozco, Da	anny	ICE MACHINE LYDIA M. 882.		NG. SNP MANAGER				
Maritza Go	onzalez			2/22/22/				
78667				9/22/2011		26		\$0.00
Medium	Work In Progress			9/22/2011 11:31:34 AN	Л			
Hernandez	z, Guillermo		Com. Dixon Rm. 203 and repair lights as		9/30 - Asp Cali rerou assist if needed.	ute to BN	/I and he wil	I
Velia Alaro	con			9/28/2011		20		\$0.00
Medium	Work In Progress			9/28/2011 10:35:51 AN		20		ψ0.00
	z, Guillermo		Coach Velez for Rm	. 142 Old English	<i>n</i>			
Velia Alaro	ron	building-Ceilin	g continues to leak t	viicii it iaiiis.				
78909				9/28/2011		20		\$0.00
Medium	Work In Progress			9/28/2011 10:37:24 AN	Л			
Herrera, Jo	pel		Coach Velez Rm. 14 new ceiling panels o	12 Old English or cover up the hole in				
Velia Alaro	con			10/11/2011		7		\$0.00
79610	W 11 D					,		φυ.υυ
Medium	Work In Progress			10/11/2011 9:31:34 AN	Л			
	z, Guillermo		Mrs. I. Quinones Rn nble Easel (wooden)					
Velia Alaro 79770	on			10/14/2011		4		\$0.00
Medium	Work In Progress			10/14/2011 11:53:29		-		******
	z, Guillermo	Business Build	Joey for Boy's Restr ing-Sink has been o er needs to be turne	oom/upper level in logged up and water				
Velia Alaro	con	•						
79809				10/17/2011		1		\$0.00
Medium	Work In Progress			10/17/2011 9:42:41 AN	Л			
Hernandez	z, Guillermo	Need to check	lights in #107 Main	building. Thank you				
Guillermo	Hernandez							

10/18/2011 1:23:07 PM Page 75 of 172

WOID	Building	Area Deferred By Until	-	Target Comp Date	Days Agod	Labor	
Priority	Status 		Created Date/Time	-	Aged	Hours	
Assigned '		Description		Action Taken			
Requester							
Location:	Gadsden	HS					
78599			9/21/2011		27		\$0.00
Medium	Work In Progress	9	/21/2011 9:16:30 AM				
	Guadalupe	Requested by Coach Yanez for Baseball Fi seed (grass) to fill first base and third base grass instead fo dirt for the infield.	eld-Plant lines with				
<u>Velia Alarc</u> 75453	con Old English Bldg		7/14/2011		96		\$0.00
Medium	Work In Progress	7	7/14/2011 7:39:52 AM		00		ψ0.00
	-						
Herrera, Jo		Roof leaks Old english Building hallway. Cla	assroom gym				
Mario Apod 75461	daca Boys Gym	Dressing Room	7/14/2011		96		\$0.00
Medium	Work In Progress		.,, .,, <u>.,, ., .,, .,, .,, .,, .,, .,, </u>		00		ψ0.00
	_						
Herrera, Jo	pel	All Boys gym root is leaking needs a new ro	oof				
<u>Mario Apod</u> 76982	daca Varsity Gym	Gym	8/16/2011		63		\$0.00
		•			00		ψ0.00
Medium	Work In Progress		3/16/2011 8:57:46 AM				
Ronquillo,		Central court varsity gym Volleyball post sle coming loose	eeve is				
<u>Mario Apod</u> 78031	daca Boys Gym		9/7/2011		41		\$0.00
High	Work In Progress		9/7/2011 3:03:27 PM				
Herrera, Jo	_	please check all dressing rooms,. bathroom shower to see if any painting needs done, a functional etc. this is a priority.thank you	ns and				
Michael M	unoz		0/0/0044		40		Φο οο
78070			9/8/2011		40		\$0.00
Medium	Work In Progress	9	/8/2011 11:18:31 AM				
Herrera, Jo	pel	Requested by Velia-Several light bulbs in the of the upstairs hallway are burned out. Very hallway on a cloudy day.					
Velia Alaro	con		10/12/2011		6		\$0.00
79689	W 11 B				O		φυ.υυ
Medium	Work In Progress		10/12/2011 11:14:07				
Lara, Ralpi	h	Requested by Lupe Quinones, Security Offi locks on chains need to be changed to an "the Flag Pole area, Intervention and Pool A Parking Lot, Student Parking Lot (as well as student parking lot). This will allow Security case of Emergency and traffic control, espe Athletic or School Activities after school hou FURTHER INSTRUCTIONS PLEASE SEE	F3" key on rea, Staff s far end of access in cially during urs. FOR				

10/18/2011 1:23:07 PM Page 76 of 172

WOID Building Priority Status Assigned To Requester Name	Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description	arget Comp Date Days Labor actual Comp Date Aged Hours Action Taken	
Location: Gadsde	n HS		
79687	10/12/2011	6	\$0.00
Medium Work In Progress	10/12/2011 10:46:55		
Lara, Ralph	Replace padlocks on back exit doors in the Gym. Thank you		
Guillermo Hernandez	40/40/0044		<u>ФО ОО</u>
79686	10/12/2011	6	\$0.00
Medium Work In Progress	10/12/2011 10:45:14		
Lara, Ralph	Need key made for the Pump house. Thank you		
Guillermo Hernandez 79685	10/12/2011	6	\$0.00
Medium Work In Progress	10/12/2011 10:44:11		
Lara, Ralph	Need to install missing padlock on gate by the field. Thank you		
Guillermo Hernandez	40/40/0044		Ф0.00
79684	10/12/2011	6	\$0.00
Medium Work In Progress	10/12/2011 10:25:52		
Lara, Ralph	Requested by Mr. Myers East Wing of Cafeteria-The door knob for the restroom was removed and never replaced. Re-place door knob as soon as possible.		
Velia Alarcon 79771	10/14/2011	4	\$0.00
		-	ψ0.00
Medium Work In Progress			
Lara, Ralph	Requested by Joey fro Boy's Restroom in Business Bulding-Door cylinder has glue in it making impossible to lock door when needed due to vandalism. Cylinder needs to be cleaned as soon as possible.		
Velia Alarcon	0/22/2044	26	ድር ዕር
78660	9/22/2011	26	\$0.00
Medium Work In Progress	9/22/2011 9:35:42 AM		
Lara, Ralph	Need to make a key for elevatorit was lost.		
Mario Apodaca	0/00/0044	00	Ф0.00
78668	9/22/2011	26	\$0.00
Medium Work In Progress	9/22/2011 11:33:46 AM		
Lara, Ralph	Requested by Velia-Coach Lawrence is requesting a key to the North West Gate. Four keys will be needed, one for Coach Lawrence and rest to key in key cabinets.		

10/18/2011 1:23:07 PM Page 77 of 172

Velia Alarcon

Velia Alarcon

Selected Da WOID Priority Assigned ⁷ Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By Location, Status Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description	•	Days Labor Aged Hours	Costs
Location:	Gadsden	HS			
78778		9/26/2011		22	\$0.00
Medium	Work In Progress	9/26/2011 11:51:43 AM			
Lara, Ralph	n	Requested by Ms. Romero for Old Attendance Office in North Building-Replace the tumbler in the old Attendance Office to match the Faculty Restrooms in this building. This will allow all teachers to have access to the office where the copier is located.			
Velia Alarc	on	10/10/2011		8	\$0.00
79550	W 11 D			0	φυ.υυ
Medium Lara, Ralph		10/10/2011 8:55:19 AM Requested by Mr. D. Martinez-Ticket Booth next to the Athletic Trainer's Office does not lock. There have been times that students have been found hiding (ditching) in the ticket booth. Please re-paire as soon as possible.			
Velia Alarc 79628	on	10/11/2011		7	\$0.00
Medium	Work In Progress	10/11/2011 12:39:07			
Lara, Ralph		Need to install padlocks on the chains to keep the lockers close in the North Bulding. Thank you			
Guillermo I 79629	Hernandez Varsity Gym	10/11/2011		7	\$0.00
Medium	Work In Progress	10/11/2011 12:41:37			·
Lara, Ralpł	•	Need to replace latch or locking device in the ticket boot in the varsity Gym. Thank you			
Guillermo I	Hernandez	8/26/2011		53	\$0.00
77464 Medium	Work In Progress	8/26/2011 8:28:53 AM		00	ψ0.00
Lara, Ralph	-	Requested by Ms. Leahy Rm. 339 Academic Building- The lock on my built-in cabinet needs to be replaced.			
Velia Alarc 77528	on	8/29/2011		50	\$0.00
Medium	Work In Progress	8/29/2011 3:01:48 PM		00	ψυ.υυ
Lara, Ralph	-	Requested by Ms. De La Garza for Rm. 713 New Admin. Building-Key will not open office door.			

10/18/2011 1:23:08 PM Page 78 of 172

Total

1200 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2011 - 6/30/2012 Order By Location, Status Costs WOID Building Until **Request Date Target Comp Date** Labor Area **Deferred By Davs** Aged Hours Created Date/Time Actual Comp Date **Status** Area Number Reason **Priority** Description **Action Taken** Assigned To Requester Name Gadsden HS Location: 8/31/2011 48 \$0.00 77644 Medium Work In Progress 8/31/2011 10:16:19 AM Requested by Mr. Martin Rm. 506 Annex Building-Lara, Ralph There's a dead bolt lock in the classroom door labled Therapy 104. There is no key for classroom. This is a very serious safety issue a student might lock themselves in that room and we would have no way to get the door unlocked. Please change cylinder to match the classroom door. Also, the double doors newly installed in the room have no core in the lock and the door leading onto the new patio area does not match any key that I have. Please have keys made to assigned to teacher as soon as possible. Velia Alarcon 9/2/2011 \$0.00 46 77775 Medium Work In Progress 9/2/2011 2:04:34 PM Lara, Ralph Requested by Velia-Additional light keys are needed for Girl's Lockerroom. Light switch was not working properly and was changed, but Coaches who use Lockerroom need to turn on lights. Velia Alarcon 9/14/2011 34 \$0.00 78318 Medium Work In Progress 9/14/2011 9:52:18 AM Lara, Ralph Requested by Coach Letz for Girl's Locker Room in Varsity Gym-Coach Reyes and Coach Letz need a light key for Girl's Locker Room. We have been requesting this since May 2011. 2ND WRITTEN REQUEST SINCE 08/09/11. Velia Alarcon 78518 Pool Dressing 9/19/2011 \$0.00 Medium Work In Progress 9/19/2011 3:44:40 PM Lara, Ralph Need to repair window (?'s please ask Mike) Michael Munoz 76629 8/8/2011 71 \$0.00 Medium Work In Progress 8/8/2011 2:12:09 PM Ambriz, Jose JOSE AMBRIZ ICE MAKER MASHINE AT NURSE IT DOESNT WORK Joel Herrera

10/18/2011 1:23:08 PM Page 79 of 172

WOID Priority	Building Status	Area Area Number	6/30/2012 Order By Lo Deferred By Reason	Until Request Date Ta Created Date/Time Ac	tual Comp Date	Days Aged	Labor Hours	Costs
Assigned Requester		Description			Action Taken			
Location:	Gadsden	HS						
	Jausuen			0/04/0044		40		ФО ОО
77625				8/31/2011		48		\$0.00
Medium	Work In Progress			8/31/2011 8:19:37 AM				
Ambriz, Jo	se	continues to no up to 75 degre comfortable in	es. Computers and so order to function pro according to Mario,	room continues to get students need to be perly. This a/c was				
Velia Alarc	con			2/11/22/1				
78321				9/14/2011		34		\$0.00
Medium	Work In Progress			9/14/2011 10:04:39 AM				
Ambriz, Jo Velia Alarc		Stand-An exha possible. The r Which is causi		installed as soon as es a lot of hot air.				
79553	.011			10/10/2011		8		\$0.00
Medium	Work In Progress			10/10/2011 9:36:04 AM				
	_	ELOWED SHO	OP UNIT IT DOESN					
Ambriz, Jo		FLOWER SITE	OF UNIT IT DOESN	II WORK				
Joel Herre 75587	ra Academic Bldg	Office		7/20/2011		90		\$0.00
Medium	Work In Progress	Cilioo		7/20/2011 3:03:42 PM		00		Ψ0.00
	•							
Lozoya, M	anny	Need to put a room 317	new lock set at the a	cademic blde lunch				
Mario Apo	daca							
76312	North Building	Classroom		8/2/2011		77		\$0.00
Medium	Work In Progress			8/2/2011 11:05:42 AM				
Lara, Ralp	h	Need to chang north building	e out key cylinder to	room 232 in the				
Mario Apo	daca	Darking Lat		10/17/2011		1		\$0.00
79851	\\\	Parking Lot				1		φυ.υυ
Medium	Work In Progress			10/17/2011 2:01:37 PM				
Castillo, Ca	arlos	Bus turnaround	d light poles need rep	pairs.				
Carlos Cas	stillo							

10/18/2011 1:23:08 PM Page 80 of 172

WOID	ate Range for Request Building	Dates: //1/2011 - Area	Deferred By	ocation, Status Until Request Date Targ		Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time Actu	ial Comp Date Aged	Hours	
Assigned		Description			Action Taken		
Requeste	r Name						
Location:	Gadsden	HS					
79888	Boys Gym	Football Field		10/18/2011	0		\$0.00
Medium	Work In Progress	TICKET BOOT	TH .	10/18/2011 8:20:58 AM			
Castillo, C	arlos	BOOTH AND TELECTRICAL ROOM TO TICE GET IT RUNN EVERYONE A OTHER EVEN	TTENDING THE NI	M THE TRAINERS I WOULD LIKE TO ND - SAFETY FOR GHT GAMES OR FIELD. NEXT GAME			
Terry Alva	rado			0/07/0044			<u>Фо</u> о
78828				9/27/2011	21		\$0.00
Medium	Work In Progress			9/27/2011 9:30:43 AM			
Herrera, J	oel	rails leading up	Mr. D. Martinez-Red to the stage and a feteria be painted.	questing for the hand lso along the side			
Velia Alaro	con			0/07/2011	24		<u></u>
78831				9/27/2011	21		\$0.00
Medium	Work In Progress			9/27/2011 9:43:37 AM			
Hernande	z, Guillermo	on both sides of painted. Pleas to Joey Munoz scrub all doors CHECK WITH	of the Cafeteria main e note: A Custodial asking the Custodia before they are pai	W.O. has been given al Team to clean and nted. PLEASE ITING THE DOORS.			
Velia Alaro	con						
79829				10/17/2011	1		\$0.00
Medium	Work In Progress			10/17/2011 10:37:40			
Herrera, J	oel			ld Front Office-All d to be painted before			
Velia Alaro 76489	con Boys Gym	Office		8/5/2011	74		\$0.00
	-	Onice			74		ψυ.υι
Medium	Work In Progress	_		8/5/2011 9:19:08 AM			
Ambriz, Jo	ose	Boys gymnasion replace conde	um split system sho nser office 400	rt it out I need to			
<u>Mario Apo</u> 78899	daca			9/28/2011	20		\$0.00
Medium	Work In Progress			9/28/2011 8:45:13 AM	20		Ψ0.00
Castillo, C	_		LOT AT NORTH	PLACE TWO LAMPS			
Joel Herre	era						
10/18/201	1 1:23:08 PM					Page	81 of 172
						. ~90	

WOID	Building	Area Number Beasen	Until Request Date Ta Created Date/Time A	arget Comp Date	Days Aged	Labor Hours	
Priority Assigned	Status	Area Number Reason Description	Created Date/Time A	Action Taken	g	110410	
Requester		Description		Action Taken			
•							
Location:	Gadsden	HS					
79333			10/3/2011		15		\$0.00
Medium	Work In Progress		10/3/2011 3:41:22 PM				
Castillo, C	arlos	Need to replace emergency light in the cafeteria. Thank you	n the girls restroom at				
Guillermo 79479	Hernandez		10/7/2011		11		\$0.00
Medium	Work In Progress		10/7/2011 9:18:50 AM				ψ0.00
	-	No ed to veniene belleet en limbte e					
Castillo, C	anos	Need to replace ballast on lights a building times 4. Thank you	round the anex				
	Hernandez		10/10/00/1				
79546	Cafeteria (1998)	Cafeteria	10/10/2011		8		\$0.00
High	Work In Progress		10/10/2011 8:16:16 AM				
Castillo, Ca	arlos	need to connect hood suppression Jbox to micro switch, about 6 ft.	n system electrical.				
Danny Ord 79834)ZCO		10/17/2011		1		\$0.00
Medium	Work In Progress		10/17/2011 10:51:08				ψ0.00
Castillo, C	•	Requested by Mrs. Lerma for Foot Stand-Install electrical outlet on N Cola regrigerator as soon as poss INSTRUCTIONS PLEASE SEE M	iball Concession orth wall for new Coke ible. FOR FURTHER				
Velia Alaro 79850	con Cafeteria (1998)	Parking Lot	10/17/2011		1		\$0.00
		Faiking Lot			'		φυ.υυ
Medium	Work In Progress		10/17/2011 1:55:07 PM				
Castillo, Castil	arlos	Sidewalkway from N.parking lot to administration, library, and cafeteria repairs. Most are not working.					
Carlos Cas 79839	stillo		10/17/2011		1		\$0.00
Medium	Work In Progress		10/17/2011 11:10:53		•		ψ0.00
	_	5					
Appelzolle	r, Frea	Requested by Ms. Sevin for Footb Replace sink in the back of Footba with a large stainless steel sink.					
Velia Alaro		A 19	0/47/0044				# 2.22
77060	Auto Shop	Auditorium	8/17/2011		62		\$0.00
Medium	Work In Progress		8/17/2011 1:34:45 PM				
Castillo, Ca	arlos	Due to the removal of the telephor side of campus Need to put lights building Annex and auto shop					
Mario Apo	daca	,					

10/18/2011 1:23:08 PM Page 82 of 172

WOID	ite Range for Request Building		Deferred By		equest Date T	arget Comp Date	Days	Labor	Costs
Priority	Status	Area Number R	Reason	Created	l Date/Time A	ctual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requester	Name								
Location:	Gadsden	HS							
77149	Pool Pump	Pump House			8/19/2011		60		\$0.00
Medium	Work In Progress			8/19/2011	10:35:15 AM				
Castillo, C	arlos	Need 30 amp fus also check the ar		rell at north buildir Il motor pump	ng				
Mario Apo									
77551	Varsity Gym	Hallway/Corridor			8/29/2011		50		\$0.00
Medium	Work In Progress			8/29/201	1 5:45:04 PM				
Castillo, C	arlos	All light switches replaced	in the hallway and	d lobby needs to	be				
Mario Apo	daca								
78030	Boys Gym				9/7/2011		41		\$0.00
High	Work In Progress			9/7/201	1 3:01:45 PM				
Castillo, Ca	arlos	please check all l operation and rep thankyou		hces etc for prope is is a priority.	er				
Michael M	unoz								
78597					9/21/2011		27		\$0.00
Medium	Work In Progress			9/21/201	1 9:10:40 AM				
Castillo, C	arlos			keys for Boy's/Gi n as possible. TH					
Velia Alaro									
Count: 140	Work Orders	Avg	. Age of WO's	31		Total for Gadsde	n HS	0	\$0.00

10/18/2011 1:23:08 PM Page 83 of 172

WOID	Building	Area Deferred By	Until Request Date Target Comp Date	A	Labor Hours	
Priority	Status	Area Number Reason	Created Date/Time Actual Comp Date	•	Hours	
Assigned ¹ Requester		Description	Action Taken			
-		110				
Location:	Gadsden	MS				
77025			8/16/2011	63		\$0.00
Medium	Work In Progress		8/16/2011 3:44:59 PM			
Appelzolle	r, Fred	Need to check sink in room 129	thank you			
Sebastian	Diaz					
78383			9/15/2011	33		\$0.00
Medium	Work In Progress		9/15/2011 8:41:18 AM			
Appelzollei	r, Fred	Need to check black flow in from you	nt C wing is leak thank			
Sebastian	Diaz Main Building	Dootroom (Dovo)	40/44/2044	4		PO 00
79765	Main Building	Restroom (Boys)	10/14/2011	4		\$0.00
Medium	Work In Progress		10/14/2011 8:38:29 AM			
Appelzollei		B. WING RESTROOMS BETW DRAIN PIPES ARE GIVING OL				
Juan Acost 79370	a		10/4/2011	14		\$0.00
Medium	Work In Progress		10/4/2011 12:03:41 PM			•
Sotelo, Enr	-	Need to fix emergency lights in wingthank you	locker roomand B			
Sebastian	Diaz					
79698			10/12/2011	6		\$0.00
Medium	Work In Progress		10/12/2011 3:13:00 PM			
Castillo, Ca	arlos	Need to replace emergency ligh	nts in B wing thank you			
Sebastian	Diaz					
75722		Office	7/22/2011	88		\$0.00
Medium	Work In Progress	Administrator	7/22/2011 3:26:19 PM			
Lozoya, Ma	anny	Need locks on four filing cabine office. Please see Mr. Calleros				
Maricruz C	arrasco		10/10/2011	0		\$0.00
79562			10/10/2011	8		φυ.υυ
Medium	Work In Progress		10/10/2011 12:20:45			
Solis, Lore	nzo	NEED TO FIX WATER FOUNT	AIN IN A wing thank you			
Sebastian	Diaz		0/00/0044	40		фо oo
78999			9/29/2011	19		\$0.00
High	Work In Progress		9/29/2011 3:48:15 PM			
Lozoya, Ma	nn.	Need to ck all automatic door of	nonors at sita			

10/18/2011 1:23:08 PM Page 84 of 172

WOID	Building				Days Aged	Labor Hours	
Priority	Status	Area Number Reason		-	Ageu	nours	
Assigned [:] Requester		Description		Action Taken			
Location:	Gadsden	Me					
	Gausuen	WIS .	40/0/0044		40		#0.00
79251			10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:02 AM				
Sanchez, F		Monthly - Gadsden MS - Mo Refer to PM schedule detail					
<u>Margret Vil</u> 79754	lalobos		10/14/2011		4		\$0.00
Medium	Work In Progress		10/14/2011 12:17:23				
Apodaca, I	-	Monthly - Gadsden MS-WW (Monthly) - Refer to PM sch	VTP Chemical Order				
Margret Vil	lalobos						
79264			10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:11 AM				
Diaz, Seba		Monthly - Gadsden MS Mor PM schedule details.	nthly FE Inspection - Refer to				
<u>Margret Vil</u> 79291	lalobos		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:25 AM	. 0, 20, 20	. •		Ψ0.00
Orozco, Da	anny	Monthly - Gadsden MS Ran PM schedule details.	nge Hood Cleaning - Refer to				
<u>Margret Vil</u> 79810	lalobos		10/17/2011		1		\$0.00
Medium	Work In Progress	sped office	10/17/2011 10:06:11				*****
Briones, E	· ·	PO #101108760 PICK UP ONE BOX DELIVI IVONNE PEREZTEACHE	ER TO				
Margaret V	illalobos	Cofotorio	0/2/2014		76		ФО ОО
76367	W 11 B	Cafeteria	8/3/2011		76		\$0.00
Medium	Work In Progress		8/3/2011 1:35:38 PM				
Sotelo, En		please install ceiling fans in see mike.thanks	kitchen area.				
<u>Michael Mı</u> 79170	Inoz		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:13 AM				
Diaz, Seba	-	Monthly - Gadsden MS Roc schedule details.	of Inspection - Refer to PM				
Margret Vil	lalobos				- 40		^ ^ ^ - -
79196			10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:30 AM				
Diaz, Seba	stian	Monthly - Gadsden MS - Cle to PM schedule details.	othes Dryer (Monthly) - Refer				

10/18/2011 1:23:08 PM Page 85 of 172

WOID Priority Assigned Requester		Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description	arget Comp Date actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	MS				
79171		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:14 AM				
Diaz, Seba	stian	Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vil	lalobos	10/2/2011	10/10/2011	16		\$0.00
79172	Mark In Drawna		10/10/2011	10		φυ.υυ
Medium	Work In Progress	10/2/2011 12:27:15 AM				
Diaz, Seba		Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vil 78299	lalobos	9/14/2011		34		\$0.00
Medium	Work In Progress	9/14/2011 12:17:23 AM				******
Sanchez, F	-	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.				
Margret Vil	lalobos					
79245		10/2/2011		16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:59 AM				
Sanchez, F	Raul	Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details.				
Margret Vil 79070	lalobos	10/2/2011	10/18/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:19 AM	10/10/2011	10		ψ0.00
Diaz, Seba	•	Monthly - Gadsden MS A-1 Wall Ref Elec Semiannual - Refer to PM schedule details.				
Margret Vil	lalobos					
79071		10/2/2011		16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:19 AM				
Diaz, Seba		Monthly - Gadsden MS H-11 Unit Elec Ht Semiannual - Refer to PM schedule details.				
Margret Vil 79072	lalobos	10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:20 AM	,_,_			Ψ0.00
Diaz, Seba	· ·	Yearly - Gadsden MS H-6 Furnance Gas Yearly - Refer to PM schedule details.				
Margret Vil	lalobos	to 1 m concedure details.				
79073		10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:21 AM				
Diaz, Seba	stian	Yearly - Gadsden MS I-4 Fan Coil Unit Yearly - Refer to PM schedule details.				

10/18/2011 1:23:08 PM Page 86 of 172

WOID Priority Assigned Requester		Area Deferred By Until Request Date To Area Number Reason Created Date/Time Area Published Description	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	MS				
79074		10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:21 AM				
Diaz, Seba	astian	Yearly - Gadsden MS U-2 Unit HT Gas/Water Yearly - Refer to PM schedule details.				
Margret Vi 79521	illalobos	10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:36 AM	10/20/2011	J		ψ0.00
Acosta, Ju	-	Monthly - QRTLY BLDG INSP REPORT (GM) - Refer to PM schedule details.				
Margret Vi	illalobos	9/22/2011		26		\$0.00
78669	W 11 B			20		φυ.υυ
Medium	Work In Progress	9/22/2011 12:29:51 PM				
Diaz, Seba	astian	please cut weeds on the fence lines around campus and especially the one that runs parrallel to drainage ditch. also cut and weed eat around bus turn around and surronding areas.				
		thank you				
Michael M 79069	unoz	10/2/2011	10/5/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:18 AM				
Diaz, Seba	•	Monthly - Gadsden MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.				
Margret Vi	illalobos	0/4/0044	0/20/2044	4.4		<u>ФО ОО</u>
77809		9/4/2011	9/20/2011	44		\$0.00
Medium	Work In Progress	9/4/2011 12:24:00 AM				
Villalobos,	-	Monthly - Gadsden MS Monthly Chiller Insp Refer to PM schedule details.				
Margret Vi 79022	illalobos	9/30/2011		18		\$0.00
Medium	Work In Progress	9/30/2011 12:22:36 AM				·
Diaz, Seba	_	Monthly - Gadsden MS A-16 Fan Exhaust Semiannual - Refer to PM schedule details.				
Margret Vi	illalobos					A
79132		10/2/2011	10/18/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:52 AM				
Villalobos,	, Margret	Yearly - Gadsden MS October Chiller Insp Refer to PM schedule details.				

10/18/2011 1:23:08 PM Page 87 of 172

Margret Villalobos

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2011 - 6/30/2 Area Defe Area Number Rea Description	erred By		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
79135				10/2/2011	10/18/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:26:54 AM				
Villalobos,	Margret	Monthly - Gadsden I PM schedule details		niller Insp Refer to				
Margret Vi 77709	llalobos	Athletic Field		9/1/2011		47		\$0.00
Medium	Work In Progress	GMS Football		9/1/2011 12:38:47 PM				ψ0.00
	Guadalupe	Need football field lii	ned as soon as					
Maricruz C	·	1400d 100tball floid lil	100 00 00011 00	, poddibio.				
77166	Vocational	Classroom		8/19/2011		60		\$0.00
Medium	Work In Progress	Vocational/307/J		8/19/2011 3:05:07 PM				
Diaz, Seba	astian	Install a white board	in Ms. Jacobi'	s room if available.				
Maricruz C								
77638	Annex	Classroom		8/31/2011		48		\$0.00
Medium	Work In Progress	Annex/414/Cha		8/31/2011 9:51:28 AM				
Diaz, Seba		Teacher's desk drav of desk (2 large drav		en opening. Left side				
Maricruz C 77691	Carrasco			9/1/2011		47		\$0.00
Medium	Work In Progress			9/1/2011 8:37:00 AM				
Sanchez,		9/01/11 I need a work order for the wwtp flowme						
Raul Sanc 79618	Nocational	Classroom		10/11/2011		7		\$0.00
Medium	Work In Progress	304		10/11/2011 10:52:02				
Lozoya, M	anny	VOCATIONAL OUT SECURITY OFFICE						
Juan Acos 78807	ta			9/26/2011		22		\$0.00
Medium	Work In Progress	GMS Campus		9/26/2011 4:13:14 PM				ψ0.00
	Guadalupe	Clean up GMS cam	nue ae nar Mre					
	·	Cican up Civio cam	ous do per ivils	. Gaillotto2.				
Maricruz C 75914	arrasco	Office		7/27/2011		83		\$0.00
Medium	Work In Progress	Bwing/124/Diag		7/27/2011 3:47:50 PM				
	anny	Replace lock in cabi	nt in room 124					

10/18/2011 1:23:08 PM Page 88 of 172

Selected Da WOID	ate Range for Request Building	Dates:7/1/2011 - Area	6/30/2012 Order By I		arget Comp Date	Days	Labor	Tota Costs
Priority	Status	Area Number	Reason	Created Date/Time A	ctual Comp Date	Aged	Hours	
Assigned	То	Description			Action Taken			
Requeste	r Name							
Location:	Gadsden	MS						
75955				7/28/2011		82		\$0.00
Medium	Work In Progress	Bwing/115/I.		7/28/2011 11:08:38 AM				
Lozoya, M	lanny		as soon as possib					
Maricruz (Carrasco							
77103		Classroom		8/18/2011		61		\$0.00
Medium	Work In Progress	108/A. Franco		8/18/2011 12:44:26 PM				
Lozoya, M	lanny	Need lock on o	abinet in room 108	as soon as possible.				
Maricruz (Carrasco							
78864				9/27/2011		21		\$0.00
Medium	Work In Progress			9/27/2011 3:29:20 PM				
Lozoya, M	lanny	Need to fix har	ndi cup door in B wi	ng thank you				
Sebastian	Diaz							
79630		Classroom		10/11/2011		7		\$0.00
Medium	Work In Progress	В		10/11/2011 1:40:16 PM				
Lozoya, M	lanny		FOR AFTERSCHOPER MRS. QUINC					
Maricruz (Carrasco							
79729				10/13/2011		5		\$0.00
Medium	Work In Progress			10/13/2011 2:06:35 PM				
Lozoya, M	lanny	Need fix main thank you	entrance door in an	nex by main field				
Sebastian								
Count: 44	Work Orders	Α	vg. Age of WO's	27	Total for Gadsder	n MS	0	\$0.00

10/18/2011 1:23:08 PM Page 89 of 172

		· · · · · · · · · · · · · · · · · · ·		Α	and Harrie	
Priority	Status	Area Number Reason	Created Date/Time A	otaai oomp bato	ged Hours	
Assigned ⁻		Description		Action Taken		
Requester	Name					
Location:	La Union	ES				
76712			8/9/2011		70	\$0.00
Medium	Work In Progress		8/9/2011 2:54:02 PM			
Villalobos,	David	need faucet for hand sink in women re-also need the two cut off valves und	· ·			
Patricio Ag	uilar		0/22/2011		25	<u></u>
78717			9/23/2011		25	\$0.00
Medium	Work In Progress		9/23/2011 10:13:59 AM			
Villalobos,		need a new water line for new refriger the new wing teachers lounge	rator ice maker in			
Patricio Ag 76880	uilar		8/12/2011		67	\$0.00
Medium	Work In Progress		8/12/2011 11:23:08 AM			•
	· ·	and O many planting land late for many				
Castillo, Ca	arios	need 2 more electrical out lets for roo possibe need a electrical out let replaced roon				
Patricio Ag 77636	uilar		8/31/2011		48	\$0.00
	Madala Dassassas	DOOM 007			40	φ0.00
Medium	Work In Progress	ROOM 207	8/31/2011 9:41:33 AM			
Castillo, Ca	arlos	INSTALL 2 ADDITIONAL ELECTRICATHE NORTH SIDE WALL OF ROOM WILL LABEL WHERE, APPROX.) THE CURRENTLY NO PLUGS THERE AN TWO DIAGNOSTICIANS IN THAT AF	(LUCY FLORES IERE ARE ID WE HAVE			
Margaret V	/illalobos		8/31/2011		48	\$0.00
77635	Madala Dassassas	DOOM 007			40	φ0.00
Medium	Work In Progress	ROOM 207	8/31/2011 9:39:28 AM			
Castillo, Ca	arlos	FIX ELECTRICAL PLUG THAT IS NO	OT WORKING			
Margaret V	/illalobos		10/5/2011		13	\$0.00
79421 Madium	Work In Progress				13	φυ.υι
Medium	Work In Progress		10/5/2011 1:52:11 PM			
Castillo, Ca	arlos	need to relocate elect outlet from wall may need to use gfi - thank you	to above counter			
Patricio Ag	uilar		10/14/2011		4	\$0.00
79762	Madala D				7	φυ.υι
Medium	Work In Progress		10/14/2011 8:08:02 AM			
Briones, Er	nrique	On October 18, 2011, please deliver of pallet to La Union Elementary. Conta Rapanut.				

10/18/2011 1:23:08 PM Page 90 of 172

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By Location, Status Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description	arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	La Union	ES				
79186		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:23 AM				
Aguilar, Pa	atricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vil	llalobos	10/2/2011		16		\$0.00
	Model In Drawns			10		ф0.00
Medium	Work In Progress	10/2/2011 12:27:26 AM				
Aguilar, Pa		Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret Vil 79531	llalobos	10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:41 AM				,
Aguilar, Pa	· ·	Monthly - La Union ES Playground Insp - Refer to PM schedule details.				
Margret Vil	llalobos					
79247		10/2/2011		16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:00 AM				
Sanchez, F		Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details.				
Margret Vil 79259	llalobos	10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:07 AM				,
Aguilar, Pa	· ·	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.				
Margret Vil	llalobos					
79292		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:26 AM				
Orozco, Da	-	Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.				
Margret Vil 79088	llalobos	10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:29 AM	, _,			40.00
Aguilar, Pa	· ·	Yearly - La Union ES H-6 Furance Gas Yearly - Refer to PM schedule details.				
Margret Vil	llalobos					
79089		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:29 AM				
Aguilar, Pa	atricio	Monthly - La Union ES H-11 Unit Elec Ht Semiannual - Refer to PM schedule details.				
	llalobos					

10/18/2011 1:23:08 PM Page 91 of 172

WOID Priority	Building Status	Area Deferred By Area Number Reason	Until Request Date Ta Created Date/Time Ac	-	Days Aged	Labor Hours	
Assigned		Description	Oroatou Dato, Timo / to	Action Taken			
Requeste		·					
Location:	La Union	ES					
79090			10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:26:30 AM				
Aguilar, Pa	atricio	Yearly - La Union ES U-2 Unit Heater Refer to PM schedule details.	r Gas Yearly -				
Margret Vi	illalobos		10/9/2011	10/25/2011	9		\$0.00
79541 Medium	Work In Brogross		10/9/2011 12:16:46 AM	10/23/2011	9		φυ.υι
	Work In Progress	M. AL. COTIVE DO NOT DEDO					
Galindo, S		Monthly - QRTLY BLDG INSP REPO PM schedule details.	RT (LU) - Refer to				
Margret Vi 79162	illalobos		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:09 AM				
Aguilar, Pa	atricio	Monthly - La Union ES Roof Inpsection schedule details.	on - Refer to PM				
Margret Vi	illalobos		10/2/2011	10/10/2011	16		\$0.00
79185	Work In Drogram			10/10/2011	10		φυ.υι
Medium	Work In Progress	M 41 1 11 5 50 5 70 1	10/2/2011 12:27:23 AM				
Aguilar, Pa	atricio	Monthly - La Union ES Exit Sign Insp PM schedule details.	: Monthly - Refer to				
Margret Vi	illalobos		40/5/2044		40		<u>ФО ОС</u>
79420			10/5/2011		13		\$0.00
Medium	Work In Progress		10/5/2011 1:43:14 PM				
Aguilar, Pa		w.o. to myself - replace motors to exh	n fans				
Patricio Aç 76799	guilar		8/10/2011		69		\$0.00
Medium	Work In Progress		8/10/2011 4:01:51 PM				•
Orozco, D	_	HOBART MIXER IS NOT WORKING CANT USE ATTACHMENTS. SNP M Y. 589.2040	PROPERLY,				
Maritza Go	onzalez		0/7/2011		44		<u></u>
78003	W 11 5		9/7/2011		41		\$0.00
Medium Moncayo,	Work In Progress Fernando	Dishwasher will not turn on. SNP Mar	9/7/2011 8:42:07 AM nager Linda Y.				
Maritza Go	onzalez	882.2040					
78965			9/29/2011		19		\$0.00
Medium	Work In Progress		9/29/2011 8:31:02 AM				
Carrasco,	Danny	need 5gal gas for 419 mower - thank	you				

10/18/2011 1:23:08 PM Page 92 of 172

WOID	Building	Dates:7/1/2011 - 6/30/2012 Order By Location, Status Area Deferred By Until Request Date 1	arget Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason Created Date/Time A	•	Aged	Hours	
Assigned		Description	Action Taken			
Requeste	r Name					
Location:	La Union	ES				
77615		8/31/2011		48		\$0.00
Medium	Work In Progress	8/31/2011 12:21:06 AM				
Aguilar, Pa	atricio	Monthly - La Union ES A-16 Fan Exhaust Semimonthly - Refer to PM schedule details.				
Margret V	illalobos	10/2/2011	11/2/2011	16		\$0.00
79087	Madala Dasanas		11/2/2011	10		φυ.υυ
Medium	Work In Progress	10/2/2011 12:26:28 AM				
Aguilar, Pa		Yearly - La Union ES I-4 Fan Coil Unit Yearly - Refer to PM schedule details.				
Margret V 79696	illalobos	10/12/2011		6		\$0.00
Medium	Work In Progress	10/12/2011 2:50:58 PM				·
Castillo, C	_	need a three way light switch for new wing hall wat				
Patricio A	guilar					
79695		10/12/2011		6		\$0.00
Medium	Work In Progress	10/12/2011 2:46:16 PM				
Castillo, C	carlos	need ballast for light fixer with emer light in it - need new emer light fixer set up				
Patricio Ag	guilar	7/27/2011		83		\$0.00
	Madala Dasanas			03		ψ0.00
Medium	Work In Progress	7/27/2011 2:25:26 PM				
Aguilar, Pa	atricio	assign to me - need to replace batters to emer lights				
Patricio Ag	guilar	9/14/2011		34		\$0.00
	Work In Progress	9/14/2011 1:49:12 PM		01		Ψ0.00
	Work In Progress					
Aguilar, Pa		w.o. to myself need to replace mini-blind r306				
Patricio Ag 78718	guilar	9/23/2011		25		\$0.00
Medium	Work In Progress	9/23/2011 10:19:46 AM		20		ψ0.00
Aguilar, Pa	•	w.o. to myself - need to install hooks on wall r208 stage for p.e.				
Patricio A	guilar					
78789		9/26/2011		22		\$0.00
Medium	Work In Progress	9/26/2011 3:12:04 PM				
Aguilar, Pa	atricio	w.o. to myself - need to replace window screen office				
Patricio A	guilar					
Count: 31	Work Orders	Avg. Age of WO's 27	Total for La Unio	n ES	0	\$0.00

10/18/2011 1:23:08 PM Page 93 of 172

WOID	Building	Area Deferred By	Until Request Date Tar	A		
Priority	Status	Area Number Reason	Created Date/Time Act	uai Comp Date	nours	
Assigned 1 Requester		Description		Action Taken		
-		1. 50				
Location:	Loma Lin					
77512	Main Building	Athletic Field	8/29/2011	50		\$0.00
Medium	Work In Progress		8/29/2011 10:47:46 AM			
Appelzoller	, Fred	WATER FOUNTAIN BEHIND LIE REPLACED.	BRARY NEEDS TO BE			
Rudy Arrec 77513	ola Main Building	Restroom (Boys)	8/29/2011	50		\$0.00
Medium	•	Restroom (Doys)	8/29/2011 10:50:25 AM	00		ψ0.00
	Work In Progress					
Appelzoller		URINAL IN 6TH GRADE WING V BUT THIS URINAL HAS BEEN C TIMES ALLREADY MAYBE WILL	CLOGGED AT LEAST 6			
Rudy Arrec 77530	ola Main Building	Athletic Field	8/29/2011	50		\$0.00
Medium	Work In Progress		8/29/2011 3:03:44 PM			• • • • •
Appelzoller	·	WE NEED A HOSE BIB FOR NE WILL BE DONE BEHIND LIBRAR SYSTEM.	W PROJECT THAT			
Rudy Arrec 79321	ıla	Mechanical	10/3/2011	15		\$0.00
Medium	Work In Progress		10/3/2011 10:36:39 AM			
Appelzoller	· ·	NEED TO REPLACE BURNED O	OUT RECURLITAING			
Rudy Arrec	ıla					
79484			10/7/2011	11		\$0.00
Medium	Work In Progress		10/7/2011 1:40:11 PM			
Villalobos,		BACKFLOW IN MECHANICAL R	OOM IS LEAKING.			
Rudy Arrec 77589	ola Main Building	Classroom	8/30/2011	49		\$0.00
Medium	Work In Progress		8/30/2011 2:55:27 PM			·
Sotelo, Enr	· ·	EMERGENCY LIGHT IS NOT WO	ORKING IN ROOM			
Rudy Arrec	ola					
79001			9/29/2011	19		\$0.00
High	Work In Progress		9/29/2011 3:49:12 PM			
Lozoya, Ma	anny	Need to ck all automatic door ope	eners at site.			
Michael Mu 79293	inoz		10/2/2011	10/23/2011 16		\$0.00
	\\\\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			10/20/2011 10		ψυ.υυ
Medium	Work In Progress		10/2/2011 12:28:26 AM			
Orozco, Da	inny	Monthly - Loma Linda ES Range to PM schedule details.	Hood Cleaning - Refer			

10/18/2011 1:23:08 PM Page 94 of 172

Selected Da WOID Priority Assigned Requester	Building Status To	Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Loma Lir	nda ES					
74952			7/4/2011	7/24/2011	106		\$0.00
Medium	Work In Progress		7/4/2011 12:21:48 AM				
Orozco, Da	anny	Monthly - Loma Linda ES Fire Sprinkle PM schedule details.	er Insp Refer to				
Margret Vil 79307	llalobos		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:34 AM	10/23/2011	10		ψ0.00
	Work In Progress						
Orozco, Da	anny	Monthly - Loma Linda ES Fire Sprinkle PM schedule details.	er Insp Refer to				
Margret Vil			7/11/2011		00		<u></u>
75282	Main Building		7/11/2011		99		\$0.00
Medium	Work In Progress		7/11/2011 8:57:04 AM				
Estrada, Je		Tile needs to be replaced in laundry ro Anti slip flooring.	oom and storage.				
Rudy Arred 78264	ola Main Building	Classroom	9/13/2011		35		\$0.00
Medium	Work In Progress		9/13/2011 2:30:13 PM				
Estrada, Je	esus	need moulding in room 222					
Rudy Arred	ola						
79640	Main Building	Electrical Room	10/11/2011		7		\$0.00
Medium	Work In Progress		10/11/2011 3:04:34 PM				
Solis, Lore	nzo	NEED MOTOR FOR EXHAUST FAN I ROOM.	N ELECTRICAL				
Rudy Arred 79192	ola		10/2/2011		16		\$0.00
	Work In Progress				10		ψ0.00
Medium Arreola, Ru	Work In Progress udy	Monthly - Loma Linda ES - Clothes Dr Refer to PM schedule details.	10/2/2011 12:27:28 AM yer (Monthly) -				
Margret Vil	llalobos	Refer to Fivi scriedule details.					
79187			10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:25 AM				
Arreola, Ru	udy	Monthly - Loma Linda ES Emer. Light Refer to PM schedule details.	Test: Monthly -				
Margret Vil	llalobos		10/0/04	40/40/204	10		00.00
79188			10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:26 AM				
Arreola, Ru	udy	Monthly - Loma Linda ES Exit Sign Insto PM schedule details.	sp: Monthly - Refer				
Margret Vil	llalobos						

10/18/2011 1:23:08 PM Page 95 of 172

WOID Priority Assigned 1 Requester		Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ad	-	Days Aged	Labor Hours	
Location:	Loma Lir	ida ES					
79536			10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress		10/9/2011 12:16:43 AM				
Arreola, Ru	ıdy	Monthly - Loma Linda ES Playgrouschedule details.	und Insp - Refer to PM				
Margret Vil	lalobos						
76138			7/31/2011	8/6/2011	79		\$0.00
Medium	Work In Progress		7/31/2011 9:25:21 AM				
Arreola, Ru	udy	Monthly - Loma Linda ES Monthly to PM schedule details.	FE Inpsection - Refer				
Margret Vil	lalobos		10/0/0011	10/8/2011	16		ድስ ሰብ
79258			10/2/2011	10/8/2011	10		\$0.00
Medium	Work In Progress		10/2/2011 12:28:07 AM				
Arreola, Ru		Monthly - Loma Linda ES Monthly to PM schedule details.	FE Inpsection - Refer				
Margret Vill 79096	lalobos		10/2/2011	11/2/2011	16		\$0.00
	Work In Progress		10/2/2011 12:26:33 AM	11/2/2011	10		ψ0.00
Medium	Work In Progress						
Arreola, Ru	•	Yearly - Loma Linda ES H6 (Furna PM schedule details.	ace)(Yearly) - Refer to				
Margret Vill 79529	lalobos		10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress		10/9/2011 12:16:40 AM		·		ψ0.00
Solis, Luis	Work in Progress	Monthly - QRTLY BLDG INSP REF					
		PM schedule details.					
Margret Vill	lalobos		10/2/2011	10/10/2011	16		\$0.00
79160	Waste In December			10/10/2011	10		ψ0.00
Medium	Work In Progress		10/2/2011 12:27:08 AM				
Arreola, Ru	•	Monthly - Loma Linda ES Roof Inp schedule details.	section - Refer to PM				
Margret Vill 76137	lalobos		7/31/2011		79		\$0.00
Medium	Work In Progress		7/31/2011 9:25:21 AM				ψ0.00
Arreola, Ru	Work In Progress udy	Monthly - Loma Linda ES - Clothes Refer to PM schedule details.					
Margret Vill	lalohos	TOTAL TO LIVE SUITEURIE REPORTS.					
76139	idiobos		7/31/2011	8/8/2011	79		\$0.00
Medium	Work In Progress		7/31/2011 9:25:22 AM				
Arreola, Ru	-	Monthly - Loma Linda ES Emer. Li					

10/18/2011 1:23:08 PM Page 96 of 172

WOID Priority Assigned ¹ Requester		Area Number Reason Description	By Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Loma Lir	da ES					
76140			7/31/2011	8/8/2011	79		\$0.00
Medium	Work In Progress		7/31/2011 9:25:22 AM				
Arreola, Ru	udy	Monthly - Loma Linda ES I to PM schedule details.	Exit Sign Insp: Monthly - Refer				
Margret Vil 78730	llalobos		9/23/2011		25		\$0.00
Medium	Work In Progress		9/23/2011 2:47:06 PM		20		ψ0.00
Flores, Pet	-	NEED BOBCAT TO REMO WALL WHERE PINE TRE AROUND PORTABLES.	OVE SAND ALONG ROCK				
Rudy Arrec	ola Main Building	Cafeteria	9/27/2011		21		\$0.00
78825	_	Careteria			21		\$0.00
Medium	Work In Progress		9/27/2011 8:27:44 AM				
Carrasco, I	•	NEED LIFT TO CHANGE (AND LAMPS.	OUT FILTERS IN CAFTERIA				
Rudy Arrec 79545	Main Building	Classroom	10/10/2011		8		\$0.00
Medium	Work In Progress		10/10/2011 7:54:11 AM				
Ronquillo,	Ruben	BROKEN WINDOW IN RO	OOM 111. 28 1/4 X 29 1/2				
Rudy Arrec	ola		9/30/2011		18		\$0.00
79021	Madala Dassassa				10		φυ.υυ
Medium	Work In Progress		9/30/2011 12:22:35 AM				
Arreola, Ru	•	Monthly - Loma Linda ES / Refer to PM schedule deta					
Margret Vil 79094	llalobos		10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:26:32 AM				
Arreola, Ru	-	Yearly - Loma Linda ES U2 PM schedule details.	2 (Heater)(Yearly) - Refer to				
Margret Vil	llalobos		10/0/0011	1.10.10.0.1			# 0.00
79095			10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:26:33 AM				
Arreola, Ru	•	Yearly - Loma Linda ES I4 PM schedule details.	(Fan Coil)(Yearly) - Refer to				
Margret Vil 78896	<u>llalobos</u> Main Building	Classroom	9/28/2011		20		\$0.00
Medium	Work In Progress	106	9/28/2011 8:31:38 AM				Ψ0.00
	· ·						
Arreola, Ru	uuy	Light bulb needs to be repl	aceu.				

10/18/2011 1:23:08 PM Page 97 of 172

WOID Priority Assigned Requester		Area Area Number Description	Deferred By		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Loma Lir	ida ES						
78897	Main Building	Classroom		9/28/2011		20		\$0.00
Medium	Work In Progress	106		9/28/2011 8:34:58 AM				
Arreola, Rι	ıdy	Mini blind broke	e and is hanging					
Gidget Mor								
79560	Main Building	Classroom		10/10/2011		8		\$0.00
Medium	Work In Progress	218		10/10/2011 12:10:49				
Arreola, Rι	udy	Screen is falling	g from the wall					
<u>Gidget Mor</u> 79572	ra Main Building	Athletic Field		10/10/2011		8		\$0.00
Medium	Work In Progress	, unouo i ioid		10/10/2011 2:17:01 PM		Ü		ψ0.00
Arreola, Ru	· ·	NEED TO SPR	EAD TURE RUII D	ER GRASS AREA.				
		NEED TO SEN	LAD TONI BOILD	LIN GINAGO AINLA.				
Rudy Arrec 77475	Main Building	Athletic Field		8/26/2011		53		\$0.00
Medium	Work In Progress			8/26/2011 2:52:11 PM				
Gonzalez,	Salvador		EQUIPMENT IN TEEDS TO BE WEL	THE KINDER AREA .DED.				
Rudy Arrec 78012	o <u>la</u> Main Building	Athletic Field		9/7/2011		41		\$0.00
Medium	Work In Progress	Courtyard		9/7/2011 10:30:14 AM				V
Gonzalez,	· ·	Requesting 21 rear courtyard	metal grates to cov of school. We have k-ins since April.	er windows facing the experienced				
Gidget Mor 78675	ra			9/22/2011		26		\$0.00
Medium	Work In Progress			9/22/2011 3:05:44 PM		20		ψ0.00
Sotelo, Enr	· ·	Front office sto working asp PN	rage room and rm 2 // 77910	217 emerg. light not				
Rudy Arrec	ola	01		40/40/0044				Ф0.00
79561	Main Building	Classroom		10/10/2011		8		\$0.00
Medium	Work In Progress	209		10/10/2011 12:12:16				
Sotelo, Enr	rique	Install outlet for	infocus machine o	n ceiling				
Gidget Mor 78821	ra Main Building	Hallway/Corrid	or	9/27/2011		21		\$0.00
Medium	Work In Progress			9/27/2011 8:23:47 AM		•		,
Solis, Lore	-		TAIN KEEPS RUN UST WATER FLO' OPERLY.	NING SLOWLY.				

10/18/2011 1:23:08 PM Page 98 of 172

			9		,			Tota
	ate Range for Request		,	•		n Data Dava	Labar	Cost
WOID	Building	Area	Deferred By	Until	Request Date Target Com	أ مما	Labor Hours	
Priority	Status	Area Number	Reason	Cre	Created Date/Time Actual Comp Date A			
Assigned	То	Description			Action Taken			
Requester	r Name							
Location:	Loma Lir	nda ES						
77588	Main Building				8/30/2011	49		\$0.00
Medium	Work In Progress			8/30/	2011 2:54:13 PM			
Ontiveros,	Guadalupe		OTHER VALVE TH WATER TO GRAS					
Rudy Arre	ola							
78243					9/13/2011	35		\$0.00
Medium	Work In Progress			9/13/	2011 9:00:27 AM			
Flores, Pe	te	NEED A NEW	BATTERY FOR TE	RUCK #31				
Rudy Arre	ola							
78895	Main Building	Classroom			9/28/2011	20		\$0.00
Medium	Work In Progress	112		9/28/	2011 8:30:19 AM			
Arreola, R	udy	Needs a manu	al sharperner anch	ored to the wa	all			
Gidget Mo	ora							
	Work Orders	Α	vg. Age of WO's	32	Total for Lo	ma Linda ES	0	\$0.00

10/18/2011 1:23:08 PM Page 99 of 172

WOID	Building	Area Deferred By Until Request Date Target Comp I	A	Labor Hours	
Priority	Status	Area Number Reason Created Date/Time Actual Comp I	Jaic -	nours	
Assigned Requester		Description Action Tal	ken		
Location:		ES			
	wesquite		33		\$0.00
78369	Mark In Drawns	9/15/2011	33		φυ.υυ
Medium	Work In Progress	9/15/2011 7:12:39 AM			
Sotelo, En	•	i have 3 parking lot lights that are out need new bulbs 1 will need a ballast			
<u>Joe Ramir</u> 79615	rez	10/11/2011	7		\$0.00
Medium	Work In Progress	10/11/2011 10:21:47			,
Sotelo, En	_	need to install electricals strips in rms. 505,506 west wall			
	•	need to install electricals strips in mis. 555,500 west wall			
<u>Joe Ramir</u> 79642	<u>rez</u>	10/11/2011	7		\$0.00
Medium	Work In Progress	10/11/2011 3:16:20 PM			
Sotelo, En	nrique	breaker in the electrical panel box100 wing has a short in it			
<u>Joe Ramir</u> 76814	rez	8/11/2011	68		\$0.00
Medium	Work In Progress	8/11/2011 8:39:07 AM			,
Ramirez, c	_	need to paint rm.404			
Joe Ramir	rez				
77254		8/23/2011	56		\$0.00
Medium	Work In Progress	8/23/2011 8:18:35 AM			
Solis, Lore	enzo	water fountain in kinder wing needs to be repaired compressor is out.			
<u>Joe Ramir</u> 79318	rez	10/3/2011	15		\$0.00
	Work In Progress	10/3/2011 8:25:37 AM	.0		ψ0.00
Solis, Lore	•	water fountain 100 wing need to repair possilble			
Joe Ramir	ra7	compressor line leak also replace angle stop.			
79756	162	10/14/2011	4		\$0.00
Medium	Work In Progress	10/14/2011 7:01:47 AM			
Carbajal, 、	Jimmy	please i need a water hose if possible of 100ft			
		thank you			
Luis Sauc	edo	40/44/0044			Φο οο
79755		10/14/2011	4		\$0.00
Medium	Work In Progress	10/14/2011 6:59:56 AM			
Carbajal, 、	Jimmy	please #1178 vaccum not working no power at all			
		thank you			
Luis Sauc	edo				

10/18/2011 1:23:08 PM Page 100 of 172

Priority Assigned ⁻ Requester		Area Number Reason Created Date/Time Action	ctual Comp Date Action Taken	Aged	Hours	
Location:	Mesquite	ES				
79350		10/4/2011		14		\$0.00
Medium	Work In Progress	10/4/2011 12:18:54 AM				
Apodaca, I	Vlario	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.				
Margret Vil 79255	lalobos	10/2/2011		16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:05 AM		10		ψ0.00
Sanchez, F	•	Monthly - Mesquite ES - Monthly Meter Readings - Refer to PM schedule details.				
Margret Vil	lalobos	10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:09 AM	10/0/2011	10		ψ0.00
Ramirez, J	-	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.				
Margret Vil	lalobos					
79294		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:27 AM				
Orozco, Da	•	Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.				
Margret Vil 75032	lalobos	7/4/2011	8/3/2011	106		\$0.00
Medium	Work In Progress	7/4/2011 12:22:22 AM				
Ramirez, J	•	Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.				
Margret Vil	lalobos					
77653		8/31/2011		48		\$0.00
Medium	Work In Progress	8/31/2011 2:39:29 PM				
Estrada, Je	esus	NEED TO REPLACE CARPET IN PORTABLE 5 & 6.				
Jesus Estra 79165	ada	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:11 AM	10/10/2011	10		ψ0.00
Ramirez, J	-	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.				
Margret Vil	lalobos					
79179		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:19 AM				
Ramirez, J	oe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to				

10/18/2011 1:23:08 PM Page 101 of 172

WOID	Building	Area Deferred By Until Request Date Ta	-	Days Aged	Labor Hours	
Priority Assigned	Status	Area Number Reason Created Date/Time Ac Description	Action Taken	Agou	Hours	
Requeste		Description	Action Taken			
Location:		ES				
79180	·	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:20 AM				
Ramirez, .	Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.				
<u>Margret V</u> 79181	illalobos	10/2/2011		16		\$0.00
	Work In Brogross			10		φυ.υυ
Medium	Work In Progress	10/2/2011 12:27:20 AM				
Ramirez,		Monthly - Mesquite ES - Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret V 75104	illalobos	7/5/2011		105		\$0.00
Medium	Work In Progress	7/5/2011 12:16:34 AM				
Sanchez,	Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.				
Margret V	illalobos	0/0/0044		77		<u> </u>
76232		8/2/2011		77		\$0.00
Medium	Work In Progress	8/2/2011 12:17:00 AM				
Sanchez,		Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.				
Margret V 79068	illalobos	10/2/2011		16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:17 AM		. •		ψ0.00
Ramirez,	_	Monthly - Mesquite ES - Barrack Drainage (Monthly) - Refer to PM schedule details.				
Margret V	illalobos					
79017		9/30/2011		18		\$0.00
Medium	Work In Progress	9/30/2011 12:22:33 AM				
Ramirez, .	Joe	Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.				
Margret V 79077	illalobos	10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:23 AM	11/2/2011	10		φυ.υυ
Ramirez,	_	Yearly - Mesquite ES U-2 Unit Heater Gas Yearly - Refer to PM schedule details.				
Margret V	illalobos	Note: to 1 W sortedule details.				
79078		10/2/2011	10/18/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:23 AM				
Ramirez,	Joe	Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.				

10/18/2011 1:23:08 PM Page 102 of 172

WOID Priority Assigned Requeste		•		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Mesquite	ES					
79079		1	0/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:2	26:24 AM				
Ramirez,	Joe	Yearly - Mesquite ES I-4 Fan Coil Unit Yearly - Refer to PM schedule details.					
Margret V 79080	illalobos	1	0/2/2011	11/2/2011	16		\$0.00
	W 11 B			11/2/2011	10		φυ.υυ
Medium Ramirez,	Work In Progress Joe	10/2/2011 12:2 Yearly - Mesquite ES H-6 Rooftop Furnance Yearly - Refer to PM schedule details.	26:24 AIVI				
Margret V	illalobos	10	/13/2011		5		\$0.00
79716	W 11 B				3		φυ.υυ
Medium	Work In Progress	10/13/2011 6:3	36:20 AM				
,		i need 5 gals. diesel for the lawn mower					
Joe Ramii 78196	rez	8.	/29/2011		50		\$0.00
Medium	Work In Progress	9/12/2011 12:	37:56 PM				
Ronquillo,	, Ruben	Break-in between 8/26-8/28 2 Fire Ext were discharged, stolen Nextel radio and computer speakers.					
Joe Ramii	rez	0	/22/2011		26		ФО ОО
78677			/22/2011		26		\$0.00
Medium Ramirez,	Work In Progress Joe	9/22/2011 3: please pick-up trash, debre and cut along fence line and area between fence and canal on the east side of campus.thank you	13:46 PM				
Michael M	lunoz						
78678		9,	/22/2011		26		\$0.00
Medium	Work In Progress	9/22/2011 3:	15:16 PM				
Ramirez,	Joe	please trim pine trees next to play ground on the east side of campus. (by left field on the baseball park).thank you	(
Michael M	lunoz	40	/4.0./2044		^		<u></u>
79890			/18/2011		0		\$0.00
High	Work In Progress	10/18/2011 8:5	52:04 AM				
Ramirez,	Joe	nned to hook up to the existing irrigation system on the playing fields to irragate when ebid does not provide water.					
Michael M	lunoz						

10/18/2011 1:23:08 PM Page 103 of 172

WOID	Building	•	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned 7		Description	Action Taken			
Requester	Name					
Location:	Mesquite	ES				
78951		9/29/2011		19		\$400.00
Medium	Work In Progress	9/29/2011 12:21:21 AN	1			
Orozco, Da	anny	Monthly - Mesquite ES - Grease Trap (Monthly) - Refer to PM schedule details.				
Margret Vil		7/40/0044		04		<u>Фо</u> оо
75536	Main Building	7/19/2011		91		\$0.00
Medium	Work In Progress	Cafeteria 7/19/2011 10:47:41 AN	1			
Ramirez, J	oe	Due to health issue ceiling tile in cafeteria has been cleaned many time and is old and still very dirty needs to be replaced. Thank you				
Sandra Mo 78604	ora	9/21/2011		27		\$0.00
	Madala Dassassas			21		ψ0.00
Medium	Work In Progress	9/21/2011 9:42:09 AN	l			
Ramirez, J	oe	need to replace ceiling tiles in the kitchen.				
Joe Ramire	ez	8/29/2011		50		\$0.00
77511				50		\$0.00
Medium	Work In Progress	8/29/2011 10:09:39 AN				
Orozco, Da	-	DRYER IS SMELLING BURNT, TURNED OFF PLEASE CHECK OUT. SNP MANAGER ALICE. F. 233.2341				
Maritza Go 77716	nzalez	9/1/2011		47		\$0.00
	Work In Drogross	9/1/2011 2:11:09 PM	•	.,		ψ0.00
Medium	Work In Progress		I			
Moncayo, I	Fernando	NO HOT WATER IN HAND SINKS IN KITCHEN CITED BY HEALTH DEPT., THEY WILL NEED PROOF THAT ISSUE HAS BEEN RESOLVED. SNP MANAGER ALICE F. 233-2341				
Maritza Go	nzalez	8/18/2011		61		\$0.00
77100			_	61		\$0.00
Medium	Work In Progress	8/18/2011 9:22:00 AN				
Gonzalez,	Salvador	8/18/11 I need welder to fabricate an aluminum cover for the sewage pumps at Mesquite Elementary wwtp ASAP,thanks Raul				
Raul Sanch	hez					A.
79320		10/3/2011		15		\$0.00
Medium	Work In Progress	10/3/2011 10:30:01 AN	1			
Lozoya, Ma	anny	door latch and door srike plate needs to be replaced on the lib. door				
Joe Ramire	ez					

10/18/2011 1:23:08 PM Page 104 of 172

Selected Da WOID	ate Range for Request Building	Dates:7/1/2011 - Area	6/30/2012 Order By Loo Deferred By		Farget Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Created Date/Time	-	Aged	Hours	
Assigned		Description			Action Taken			
Requester	r Name	•						
Location:	Mesquite	ES						
79565				10/10/2011		8		\$0.00
Medium	Work In Progress			10/10/2011 12:48:36				
Solis, Lore	enzo	compressor for be replaced.	water fountain kinde	r hallway needs to				
Joe Ramir				0/00/0044				Ф0.00
78910	Main Building			9/28/2011		20		\$0.00
Medium	Work In Progress	Main Office		9/28/2011 11:01:22 AM				
Lozoya, M	lanny	Mr. Moreno/As on his door.	sistant Principal need	to change his lock				
Sandra Mo	ora							
79547				10/10/2011		8		\$0.00
Medium	Work In Progress			10/10/2011 8:20:49 AM				
Lozoya, M	lanny	nurses' medicion a.s.a.p. and pro	ne rm. needs to have otective plate.	a keyed door latch.				
Joe Ramir	ez			40/40/0044				Ф0.00
79548				10/10/2011		8		\$0.00
Medium	Work In Progress			10/10/2011 8:22:17 AM				
Lozoya, M	lanny	asst. principal's principal.	s door needs to be re-	keyed as per asst				
Joe Ramir	ez							
79564				10/10/2011		8		\$0.00
Medium	Work In Progress			10/10/2011 12:46:24				
Flores, Pe	te	truck number 1	41 needs a battery					
Joe Ramir	ez							
79808				10/17/2011		1		\$0.00
Medium	Work In Progress			10/17/2011 9:21:31 AM				
Flores, Pe	te	voltage regulat	or needs to be replac	ed				
Joe Ramir	·ez							
	Work Orders	Α	vg. Age of WO's 28	1	Total for Mesquit	e ES	0	\$400.00

10/18/2011 1:23:08 PM Page 105 of 172

Selected Daw WOID Priority Assigned 1 Requester	Building Status To	Area Area Number Description	Deferred By Reason	Until Request Date of Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	North Va	lley ES						
78766		Classroom		9/26/2011		22		\$0.00
Medium	Work In Progress	306		9/26/2011 10:40:05 AM				
Sotelo, Enr	ique	Send Electricia Starboard equi	n to set up wiring a oment.	nd cabling for				
Priscilla Ma	artinez			0/00/0044				Φο οο
78767		Classroom		9/26/2011		22		\$0.00
Medium	Work In Progress	room 204		9/26/2011 10:42:48 AM				
Sotelo, Enr	ique	Send Electricia	n for wiring/cable fo	or Starboard.				
Priscilla Ma	artinez	Classroom		9/26/2011		22		\$0.00
78768	Mark la Dassassas					22		φυ.υυ
Medium	Work In Progress	308		9/26/2011 10:44:59 AM				
Sotelo, Enr	ique	Send Electricia equipment.	n to set up wiring/c	able for Starboard				
<u>Priscilla Ma</u> 78769	artinez	Classroom		9/26/2011		22		\$0.00
Medium	Work In Progress	room 107		9/26/2011 10:47:05 AM				ψ0.00
Sotelo, Enr	· ·		n for wiring/cabling					
Priscilla Ma	artinez							
78770		Classroom		9/26/2011		22		\$0.00
Medium	Work In Progress	room 300		9/26/2011 10:49:13 AM				
Sotelo, Enr	ique	Send Electricia equipment.	n to set up wiring/c	abling for Starboard				
Priscilla Ma 77725	artinez			9/1/2011		47		\$0.00
Medium	Work In Progress			9/1/2011 3:22:26 PM				·
Solis, Lorer	•		ing water fountains					
Danny Veg	a			•				
79282				10/2/2011		16		\$0.00
Medium	Work In Progress			10/2/2011 12:28:21 AM				
Orozco, Da	inny	Monthly - North Refer to PM sc	ı Valley ES - Range hedule details.	Hood Cleaning -				
Margret Vill	lalobos	Machanical		0/20/2011		10		ድስ ስስ
78978	Model - De-	Mechanical		9/29/2011		19		\$0.00
High	Work In Progress			9/29/2011 10:16:01 AM				
Munoz, Mic	chael		s performing pm or p in smoke.faulty ba r and batteries.					

10/18/2011 1:23:08 PM Page 106 of 172

Status o Name North Val Work In Progress	Description	Actual Comp Date Action Taken			
Name North Val Work In Progress	lley ES				
Work In Progress					
-	7/4/201				
-		1	106		\$0.00
	7/4/2011 12:21:30 A	M			
redo	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.				
alobos	10/2/201	1	16		\$0.00
Work In Progress	10/2/2011 12:27:56 A		10		ψ0.00
redo	Monthly - North Valley ES-Fire Pump PM (Quarterly) -	IVI			
alobos					
	10/2/201	1 10/10/2011	16		\$0.00
Work In Progress	10/2/2011 12:27:38 A	M			
у	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.				
alobos	10/2/201	1 10/10/2011	16		\$0.00
Work In Progress					*****
у	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.				
alobos	40/0/004	40/05/0044			<u> </u>
			9		\$0.00
-		M			
у	Monthly - North Valley ES Playground Inspection - Refer to PM schedule details.				
alobos	10/2/201	1 10/8/2011	16		\$0.00
Work In Progress	10/2/2011 12:28:17 A	M			
у	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.				
alobos					
			26		\$0.00
Work In Progress	9/22/2011 3:17:14 P	M			
у	please cut weeds and pick up and rake area on the west side of building(south of parking lot) and trim trees. thank you				
noz					
			1		\$0.00
Work In Progress	10/17/2011 8:31:19 A	M			
anny	please support with the grounds around campus. thankyou				
	redo alobos Work In Progress y alobos	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details. 10/2/201 Work In Progress Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details. 10/2/201 Work In Progress Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details. Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details. 10/9/201 Work In Progress Monthly - North Valley ES Playground Inspection - Refer to PM schedule details. 10/2/201 Work In Progress Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details. 10/2/201 Work In Progress Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details. 10/2/201 Work In Progress 9/22/2011 3:17:14 P please cut weeds and pick up and rake area on the west side of building(south of parking lot) and trim trees. thank you 10/17/201 Work In Progress 10/17/2011 8:31:19 Aid and pick up and campus. thankyou	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details. 10/2/2011 10/2/2011 10/10/2011 Work In Progress 10/2/2011 12:27:38 AM y Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details. 10/2/2011 10/10/2011 Work In Progress 10/2/2011 12:27:40 AM y Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details. 10/9/2011 10/9/2011 10/9/2011 10/25/2011 Work In Progress 10/9/2011 12:16:33 AM y Monthly - North Valley ES Playground Inspection - Refer to PM schedule details. 10/2/2011 10/9/2011 12:28:17 AM Work In Progress 10/2/2011 12:28:17 AM y Monthly - North Valley ES Monthly FE Inspection - Refer to PM schedule details. 10/2/2011 13:17:14 PM y Monthly - North Valley ES Monthly FE Inspection - Refer to PM schedule details. 10/2/2011 3:17:14 PM please cut weeds and pick up and rake area on the west side of building(south of parking lot) and trim trees. thank you 10/2/2011 8:31:19 AM please support with the grounds around campus.	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details. 10/2/2011 10/10/2011 16 Work In Progress 10/2/2011 12:27:38 AM y Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details. 10/2/2011 10/10/2011 16 Work In Progress 10/2/2011 10/10/2011 16 Work In Progress 10/2/2011 12:27:40 AM y Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details. 10/9/2011 10/25/2011 9 Work In Progress 10/9/2011 12:16:33 AM y Monthly - North Valley ES Playground Inspection - Refer to PM schedule details. 10/2/2011 10/8/2011 16 Work In Progress 10/2/2011 10/8/2011 16 Work In Progress 9/22/2011 10/8/2011 26 Work In Progress 9/22/2011 26 Work In Progress 9/22/2011 26 Work In Progress 9/22/2011 3:17:14 PM y please cut weeds and pick up and rake area on the west side of building(south of parking lot) and trim trees. thank you noz 10/17/2011 8:31:19 AM please support with the grounds around campus.	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details. 10/2/2011 10/10/2011 16 Work In Progress 10/2/2011 12:27:38 AM y Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details. 10/2/2011 10/10/2011 16 Work In Progress 10/2/2011 12:27:40 AM y Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details. 10/9/2011 10/9/2011 10/25/2011 9 Work In Progress 10/9/2011 12:16:33 AM y Monthly - North Valley ES Playground Inspection - Refer to PM schedule details. 10/2/2011 12:28:17 AM y Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details. 40/2/2011 12:28:17 AM y Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details. 9/22/2011 2:28:17 AM y Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details. 10/17/2011 2:01 2:01 2:01 2:01 2:01 2:01 2:01

10/18/2011 1:23:08 PM Page 107 of 172

WOID Priority Assigned 1 Requester		•	te Target Comp Date e Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	North Val	lley ES				
78947		9/29/20	l1	19		\$750.00
Medium	Work In Progress	9/29/2011 12:21:19 A	M			
Orozco, Da	nny	Monthly - North Valley ES - Grease Trap (Monthly) - Refer to PM schedule details.				
<u>Margret Vill</u> 79122	alobos	10/2/20	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:47 /		10		ψ0.00
Vega, Danr	•	Yearly - North Valley ES H6 (Furnace)(Yearly) - Refer to PM schedule details.				
Margret Vill	alobos					
79509		10/9/20	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:30 A	AM			
Parra, Javie		Monthly - QRTLY BLDG INSP REPORT (NV) - Refer to PM schedule details.				
<u>Margret Vill</u> 79152	alobos	10/2/20 ⁻	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:03 A				·
Vega, Danr	-	Monthly - North Valley ES Roof Inspection - Refer to PM schedule details.				
Margret Vill	alobos	8/1/20	11	78		\$0.00
76189 Medium	Work In Progress	8/1/2011 1:13:59 F		70		φυ.υυ
Lozoya, Ma	•	need to repair door handle plus core in heat pumps mechcanical rm organ trail(exterior)and give a key to joe trane rep	TVI			
<u>Danny Veg</u> 77687	a	9/1/20	11	47		\$0.00
Medium	Work In Progress	9/1/2011 8:15:06 A		41		ψ0.00
Lozoya, Ma	-	key core fell-off main hallway door by office/h-d custodian key is worn out his key pulled core -out - please secure door by wk end	VVI			
Danny Veg 78415	a	9/16/20 ⁻		32		\$0.00
Medium	Work In Progress	9/16/2011 7:42:13 /		02		ψ0.00
Lozoya, Ma	· ·	maintenance -custodial office by computer door will not open/core will not turn				
Danny Veg 78416	a	9/16/20 ⁻	<u> </u>	32		\$0.00
Medium	Work In Progress	9/16/2011 7:43:49 /		- •		
Lozoya, Ma	-	assit principal key will not open locks you made for plygrd walk-in gates.please ck				
Danny Veg	•	F.73 9				

Selected Da	ate Range for Request	Dates:7/1/2011 -	6/30/2012 Order By L	_ocation, Statu	IS			Total Costs
WOID	Building	Area	Deferred By	Until	Request Date Target Com	p Date Days n Date Aged		
Priority	Status	Area Number Reason		Created Date/Time Actual Comp Date			Hours	
Assigned '	То	Description			Action	Taken		
Requester	Name							
Location:	North Va	lley ES						
77772					9/2/2011	46		\$0.00
Medium	Work In Progress			9/2	/2011 1:21:00 PM			
Vega, Dan	ny	rm 211(music disrupting clas	rm) cover doors to k s rm 209	reep sound fi	rom			
Danny Veg	ga							
78751					9/26/2011	22		\$0.00
Medium	Work In Progress			9/26	/2011 7:37:10 AM			
Carrasco,	Danny	9-26-11 need diesel fue need gas for #						
Danny Veg	ga							
Count: 26	Work Orders	Α	vg. Age of WO's	28	Total for Nor	th Valley ES	0	\$750.00

10/18/2011 1:23:08 PM Page 109 of 172

WOID	Building	Area Deferred By	Until Request Date Ta	-	Days	Labor	
Priority	Status	Area Number Reason	Created Date/Time Ac	•	Aged	Hours	
Assigned Requester		Description		Action Taken			
-		On Tarak Bas K (LM)					
Location:		On-Track Pre-K (LM)	2/22/22				^
78806	Main Building		9/26/2011		22		\$0.00
Medium	Work In Progress		9/26/2011 4:06:11 PM				
Ontiveros,	Joe	NEED WATER HEATER CHECKED CLOSET (KEEPS TRIPPING GFCI).	IN CUSTODIAL				
Adam Mor 77750	ntoya		9/2/2011		46		\$0.00
	Mork In Drogroop				70		ψ0.00
Medium	Work In Progress		9/2/2011 8:20:56 AM				
Munoz, Mi		WITH THE REMOVAL OF BUSHES SCHOOL WE NEED OUR FENCE EX					
Adam Mor 78680	ntoya		9/22/2011		26		\$0.00
Medium	Work In Progress		9/22/2011 3:18:48 PM				
Vega, Dan	_	please cut dead mexican elder infront					
	•	trim remaining trees and bushes.than					
Michael Mi 79665	unoz	Athletic Field	10/12/2011		6		\$0.00
Medium	Work In Progress		10/12/2011 7:17:54 AM				
Ramirez, J	loe	could you please support with the mo	eing of the grass.				
Michael M	unoz	anariik you					
79119			10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:26:45 AM				
Vega, Dan	ny	Yearly - Northern Prek I4 (Fan Coil)(YPM schedule details.	early) - Refer to				
Margret Vi	llalobos		10/2/2011	11/2/2011	16		\$0.00
79120	W 11 5			11/2/2011	10		\$0.00
Medium	Work In Progress		10/2/2011 12:26:46 AM				
Vega, Dan	-	Yearly - Northern Prek H6 (Furnace)(PM schedule details.	Yearly) - Refer to				
Margret Vi 79254	llalobos		10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:04 AM		.0		ψ5.00
	-	Monthly Northern Dra W Manthian					
Sanchez, I		Monthly - Northern Pre-K - Monthly M Refer to PM schedule details.	etet Reaulilys -				
Margret Vi 79276	IIaiodos		10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:17 AM				
Vega, Dan	-	Monthly - La Mesa ES Monthly FE Inp PM schedule details.					
Mararat \/	llalobos	i in solicatio actalis.					

10/18/2011 1:23:08 PM Page 110 of 172

Total Selected Date Range for Request Dates:7/1/2011 - 6/30/2012 Order By Location, Status Costs WOID Building Until **Request Date Target Comp Date** Labor Area **Deferred By Davs** Aged Hours Area Number Reason Created Date/Time Actual Comp Date **Status Priority** Description **Action Taken** Assigned To Requester Name Location: Northern On-Track Pre-K (LM) 10/13/2011 0 \$0.00 79728 Medium Work In Progress 10/13/2011 11:01:34 10/13/2011 We are infested with small roaches especially in 10-13-11 - fax to Watson for Quote as per Munoz, Michael teacher's lounge area and in classroom 103 we have Mike M. centipedes and large ants. Concepcion Montalvo 7/26/2011 84 \$0.00 75818 Work In Progress 7/26/2011 9:59:35 AM Medium ROOM #108 - UNEVEN TILES ARE A TRIP HAZARD. Estrada, Jesus PLEASE MAKE RECOMMENDATION. Jesus Estrada Main Building 9/28/2011 20 \$0.00 78891 Work In Progress 9/28/2011 7:55:57 AM Medium NEED A/C CHECKED. (WILL NOT TURN ON) Solis, Lorenzo Adam Montoya 8/25/2011 54 \$0.00 77429 Medium Work In Progress 8/25/2011 1:25:50 PM NEED CHAIR DOLLY. Carbajal, Jimmy Adam Montova 10/2/2011 11/2/2011 \$0.00 79121 16 Medium Work In Progress 10/2/2011 12:26:46 AM Yearly - Northern Prek U2 (G.Heat)(Yearly) - Refer to Vega, Danny PM schedule details. Margret Villalobos 79156 10/2/2011 10/10/2011 16 \$0.00 Work In Progress 10/2/2011 12:27:06 AM Medium Vega, Danny Monthly - La Mesa ES Roof Inpsection - Refer to PM schedule details. Margret Villalobos 79211 10/2/2011 10/10/2011 16 \$0.00 Medium Work In Progress 10/2/2011 12:27:39 AM Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to Vega, Danny PM schedule details. Margret Villalobos 10/10/2011 79212 10/2/2011 16 \$0.00 Medium Work In Progress 10/2/2011 12:27:40 AM Monthly - La Mesa ES Emer. Light Test: Monthly - Refer Vega, Danny to PM schedule details. Margret Villalobos

10/18/2011 1:23:08 PM Page 111 of 172

Selected Da	ate Range for Request		6/30/2012 Order By	•	•				Tota Costs
WOID	Building	Area	Deferred By	Until		arget Comp Date	Days	Labor	00313
Priority	Status	Area Number	Reason	Cre	Created Date/Time Actual Comp Date			Hours	
Assigned '	То	Description				Action Taken			
Requester	Name								
Location:	Northern	On-Track Pre-l	(LM)						
79514					10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress			10/9/2	011 12:16:32 AM				
Vega, Dan	iny	Monthly - North schedule detai	nern Pre-K Playgro ls.	und Insp - Re	fer to PM				
Margret Vi	llalobos								
79349					10/4/2011		14		\$0.00
Medium	Work In Progress			10/4/2	011 12:18:53 AM				
Apodaca, I	Mario	Monthly - North Refer to PM so	nern Pre-K- Domes hedule details.	tic Water Filte	rs -				
Margret Vi	llalobos								
Count: 18	Work Orders	Α	vg. Age of WO's	23	Total for Northern	n On-Track Pre-K	(LM)	0	\$0.00

10/18/2011 1:23:08 PM Page 112 of 172

WOID Priority Assigned		Area Deferred By Area Number Reason Description	Until Request Date 1 Created Date/Time A	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester		Diant Compley					
Location:	Pnysical	Plant Complex	0/00/0044		40		Φο οο
79038		Parking Lot	9/30/2011		18		\$0.00
Medium	Work In Progress		9/30/2011 12:31:17 PM				
Villalobos,	David	ASP Mike remove upright connection and water	s to sewer, gas,				
David Villa 79627	lobos		10/11/2011		7		\$0.00
Medium	Work In Progress		10/11/2011 12:02:29		,		ψ0.00
Sotelo, Enr	_	Womana BB. Bloose shange out ligh					
	•	Womens RR - Please change out ligh	IL				
<u>Juliet Parra</u> 79042	a Purchasing	Office	9/30/2011		18		\$0.00
Medium	Work In Progress		9/30/2011 2:29:58 PM				
Lozoya, Ma	· ·	As per Alfredo Juan needs a key mad					
		ASAP					
<u>Larry Marti</u> 79806	nez Purchasing	Custodial	10/17/2011		1		\$0.00
Medium	Work In Progress	Custodiai	10/17/2011 8:55:40 AM		•		ψ0.00
Lozoya, Ma	-	POR FABOR. NECESITO CANDADO GABINETE PARA ASEGURAR MATI LIMPIEZA. MARISELA.) EN UN				
Marisela To			0/44/0044		0.4		<u>Фо оо</u>
78336	Motor Vehicle		9/14/2011		34		\$0.00
Medium	Work In Progress	vehicle#118	9/14/2011 2:07:25 PM				
Flores, Pet	e	vehicle is in need of maintenance					
Pete Flores 78551	S Motor Vehicle		9/20/2011		28		\$0.00
Medium	Work In Progress	vehicle#33	9/20/2011 2:07:20 PM		20		Ψοίοο
	-						
Flores, Pet		power steering-leaking fluid and very	difficult to turn.				
Pete Flores 79675	s Maintenance		10/12/2011		6		\$0.00
Medium	Work In Progress		10/12/2011 8:41:35 AM				
Flores, Pet	e	Vehicle#152 -one brakelight not work	ing.				
Carlos Cas	stillo						
79669	Motor Vehicle		10/12/2011		6		\$0.00
Medium	Work In Progress	vehicle#81	10/12/2011 8:05:04 AM				
Flores, Pet	e	heater leaking coolant inside of truck worn excessively	cab, front tires				
Pete Flores	_						

10/18/2011 1:23:08 PM Page 113 of 172

WOID	Building	Area Number Become	Until Request Date Target Co	A	Labor Hours	
Priority	Status	Area Number Reason	Created Date/Time Actual Co	inp bate	Hours	
Assigned ⁻ Requester		Description	Actio	n Taken		
<u> </u>		Diam's Commission				
Location:	-	Plant Complex				
79768	Motor Vehicle		10/14/2011	4		\$0.00
Medium	Work In Progress		10/14/2011 10:21:06			
Flores, Pet	е	bucket truck is leaking hydraulic oi truck needs to be taken to private services, please do so.thank you				
Michael Mu 78238	ınoz		9/13/2011	35		\$0.00
	Made la Deserva			33		ψ0.00
Medium	Work In Progress		9/13/2011 8:07:46 AM			
Gonzalez,	Salvador	Requesting new paint gun old one	is broken.			
Salvador G	Sonzalez		40/0/044	2/2/2244		Ф0.00
79263			10/2/2011 10	0/8/2011 16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:10 AM			
Diaz, Seba	stian	Monthly - Physical Plant FE Inspect schedule details.	ction - Refer to PM			
Margret Vil	lalobos Maintenance		9/26/2011	22		\$0.00
78783				22		φυ.υυ
Medium	Work In Progress		9/26/2011 1:23:26 PM			
Ambriz, Jo	se	Maint Office - one of the coils bust	ed.			
Michael Mu			40/4/0044			Ф0.00
79372	Motor Vehicle		10/4/2011	14		\$0.00
Medium	Work In Progress		10/4/2011 2:33:58 PM			
Flores, Pet	е	truck needs oil change.				
Lorenzo So	olis					
78534			9/20/2011	28		\$0.00
Medium	Work In Progress		9/20/2011 8:11:53 AM			
Carrasco, I	Danny	ATTN, DANNY CARRASCO; need an electrical reciprocating sa charge reciprocating saw with lethi				
Lorenzo So			10/10/00/1			Ф0.00
79724	Motor Vehicle		10/13/2011	5		\$0.00
Medium	Work In Progress		10/13/2011 8:59:09 AM			
Torres, Ma	risela	NEED TO CLEAN OUTSIDE OF A SPIDER WEBS	UTO SHOP BLDG/			
Jesus Estra 79481	ada Motor Vehicle		10/7/2011	11		\$0.00
				1.1		ψ0.00
Medium	Work In Progress	vehicle#110	10/7/2011 10:30:00 AM			
Flores, Pet	е	van leaking coolant & is requiring r	outine service.			
Pete Flores	6					

10/18/2011 1:23:08 PM Page 114 of 172

WOID	Building	Area Deferred By	Until Request Date Tar	-	Days	Labor	
Priority	Status	Area Number Reason	Created Date/Time Ac	-	Aged	Hours	
Assigned		Description		Action Taken			
Requeste							
Location:	Physical	Plant Complex					
78847			9/27/2011		21		\$0.00
Medium	Work In Progress		9/27/2011 1:14:25 PM				
Ontiveros,	, Guadalupe	please order new 8' disc, 3 point h projects. thanks	nitch for district				
Michael M	lunoz		0/07/0044		04		<u>ФО ОО</u>
78848			9/27/2011		21		\$0.00
Medium	Work In Progress		9/27/2011 1:15:56 PM				
	, Guadalupe	need new z-trac mower to cut new southern schools.thanks	/ landscaping in the				
<u>Michael M</u> 78058	lunoz	Athletic Field	9/8/2011		40		\$0.00
	Maria la Duanca	Athletic Field			40		ψ0.00
Medium	Work In Progress		9/8/2011 8:26:09 AM				
	Salvador	pull behind scraper needs blade wask lupe.	elded. any questions				
<u>Guadalup</u> 78268	e Ontiveros	Athletic Field	9/13/2011		35		\$0.00
Medium	Work In Progress	7.11.11.01.01.01.01.01.01.01.01.01.01.01.	9/13/2011 3:21:06 PM				Ψ0.00
	•						
Gonzalez,	Salvador	PULL BEHIND SCRAPER NEEDS	S BLADE WELDED.				
<u>Guadalup</u> 79169	e Ontiveros		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:13 AM	10,10,2011			ψ0.00
	ŭ	Manthly Dhysical Diget Doof Income					
Diaz, Seba	astian	Monthly - Physical Plant Roof Insp schedule details.	Dection - Refer to Pivi				
Margret V	illalobos						
79203			10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:34 AM				
Carbajal, 、	Jimmy	Monthly - Physical Plant - Clothes Refer to PM schedule details.	Dryer (Monthly) -				
Margret V			40/4/2044		4.4		ФО ОО
79369	Purchasing		10/4/2011		14		\$0.00
Medium	Work In Progress	Student Records	10/4/2011 10:48:54 AM				
Lozoya, M	lanny	The latch (I think that is what it's c times I can't get the door to lock w day. The key # is DC18. Thank y	hen I leave for the				
Tracey Sw	vinford		0/0/0044		46		ድለ ለሳ
77786			9/2/2011		46		\$0.00
Medium	Work In Progress		9/2/2011 3:16:20 PM				
Carrasco,	•	REQUESTING NEW ROUTER FO (LOANER).	OR DISTRICT USE				
Danny Ca	rrasco						
0/18/201	11 1:23:08 PM					Dono 1	15 of 172

10/18/2011 1:23:08 PM Page 115 of 172

	Building	Area Deferred By Until Request Date Target Com		Labor
Priority	Status	Area Number Reason Created Date/Time Actual Comp	p Date Aged	Hours
Assigned [*]		Description Action 7	Гaken	
Requester				
Location:	Physical	Plant Complex		
78884	Maintenance	9/27/2011	21	\$0.0
Medium	Work In Progress	9/27/2011 4:16:22 PM		
Carrasco,	Danny	REQUESTING 16' TRAILER FOR PPD (DISTRICT USE).(NEW)		
Danny Car 78885	rrasco Maintenance	9/27/2011	21	\$0.0
Medium	Work In Progress	9/27/2011 4:18:57 PM		Ψ0.0
	_			
Carrasco,	Danny	REQUESTING (NEW) 16' TRAILER FOR CHAPARRAL SCHOOLS		
Danny Car		8/23/2011	56	\$0.0
77261	Purchasing		56	φυ.υ
Medium	Work In Progress	8/23/2011 10:58:04 AM		
Munoz, Mi		Please extend the concrete slab outside both garage door in the purchasing warehouse.		
Alfredo Ho 78650	Motor Vehicle	Parking Lot 9/22/2011	26	\$0.0
Medium	Work In Progress	9/22/2011 7:56:36 AM		
Ontiveros,	Guadalupe	re layout complete parking lot to add additional row and install signage.		
Alfredo Ho	lguin	40/44/0044	7	
79638		10/11/2011	7	\$0.0
Medium	Work In Progress	10/11/2011 2:38:58 PM		
Flores, Pet		Mr. Giovas vehicle 172 needs to be serviced. Mr. Baker will be out Oct. 12 - Oct 14. Thank you.		
Maritza Go 76176	onzalez	8/1/2011	78	\$0.0
Medium	Work In Progress	8/1/2011 9:27:24 AM		
Ronquillo,		PURCHASE 2 KIT ANTENNAS 1FOR GMS, 1FOR STMS.		
Ruben Roi	nquillo	0/00/00/4		
79036		9/30/2011	18	\$0.0
Medium	Work In Progress	9/30/2011 11:16:55 AM		
Ronquillo,	Ruben	REPAIR RIDGID PRESSURE JETTER		
Ruben Roi	nquillo	40/44/0044		* ***********************************
79600	\\\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	10/11/2011	7	\$0.0
Medium	Work In Progress	10/11/2011 7:44:35 AM		
Carrasco,	Danny	Att. Danny Carrasco need tune up kit for miller 250 gas welder.		

10/18/2011 1:23:08 PM Page 116 of 172

WOID	Building	Area	Deferred By	Until Request Date Targ	·		Costs
Priority	Status	Area Number	Reason	Created Date/Time Actu	•	ed Hours	
Assigned ⁻		Description			Action Taken		
Requester	Name						
Location:	Physical	Plant Complex					
79699				10/12/2011	(6	\$0.00
Medium	Work In Progress			10/12/2011 3:16:12 PM			
Diaz, Seba	stian	_	LACE LIGHT BUL CUSTODAIL WAR				
Mary Sitter				40/7/0044	4.		#0.00
79480	Maintenance			10/7/2011	11		\$0.00
Medium	Work In Progress			10/7/2011 9:34:08 AM			
Gonzalez,	Salvador	NEED METAL I	DRAG(PULL ALOI	NG) FOR PPD USE.			
Danny Car							
78661	Motor Vehicle			9/22/2011	26	5	\$0.00
Medium	Work In Progress	vehicle#144		9/22/2011 9:42:00 AM			
Flores, Pet	e	vehicle #144 re	quires scheduled r	maintenance			
Pete Flores							
79366	Motor Vehicle			10/4/2011	14	1	\$0.00
Medium	Work In Progress	vehicle#111		10/4/2011 10:10:56 AM			
Flores, Pet		please prepare	vehicle#111 for su	perintendent			
Pete Flores 79367	Motor Vehicle			10/4/2011	14	1	\$0.00
Medium	Work In Progress	vehicle#19		10/4/2011 10:13:40 AM			
Flores, Pet		truck will not sta switch	art has sustained d	lamage to ignition			
Pete Flores	s Motor Vehicle			10/5/2011	1;	₹	\$0.00
		vobiolo#00				,	ψ0.00
Medium	Work In Progress	vehicle#98		10/5/2011 7:59:00 AM			
Flores, Pet		check engine lig	ght has illuminated	-check&advise			
Pete Flores	Motor Vehicle			10/5/2011	1;	<u> </u>	\$0.00
		vahiala#05			1.	,	ψ0.00
Medium	Work In Progress	vehicle#25		10/5/2011 9:01:54 AM			
Flores, Pet	e	truck loses pow	er after engine wa	rms up .stalls at times.			
Pete Flores	s Motor Vehicle			10/5/2011		3	\$0.00
Medium		vehicle#148			10	•	Ψ0.00
	Work In Progress			10/5/2011 9:03:49 AM			
Flores, Pet		suburban needs maintenance	s battery replacem	ent and routine			
Pete Flores	s Work Orders	Λ.	g. Age of WO's	20 Total for Phy	sical Plant Complex	0	\$0.00

10/18/2011 1:23:08 PM Page 117 of 172

WOID Priority	Building Status	Area Deferred By Area Number Reason	Until Request Date T Created Date/Time A	arget Comp Date	Days Aged	Labor Hours	
Assigned ⁻		Description	Oroatou Bato, Timo A	Action Taken			
Requester		P					
Location:	Riverside	ES					
78421			9/16/2011		32		\$0.00
Medium	Work In Progress		9/16/2011 8:51:05 AM				
Castillo, Ca	arlos	need new light switch in cafe					
Carlos Her	nandez						
77782			9/2/2011		46		\$0.00
Medium	Work In Progress		9/2/2011 2:48:52 PM				
Ambriz, Jo	se	water fountian in cafe not cooling any replace	more need to				
Carlos Her 77117	nandez		8/18/2011		61		\$0.00
	Madala Dassassa				O I		φυ.υυ
Medium	Work In Progress		8/18/2011 3:43:03 PM				
Lara, Ralpl		need pad locks for small get and wate one for trash cans	er control box and				
Carlos Her 79486	nandez		10/7/2011		11		\$0.00
Medium	Work In Progress		10/7/2011 2:53:59 PM				
Lara, Ralpl	h	need cores need to be clean locks are room 141,145,and room 20	e hard to open in				
Carlos Her	nandez		10/10/0044				
79566			10/10/2011		8		\$0.00
Medium	Work In Progress		10/10/2011 12:53:13				
Lara, Ralpl	h	need new master key					
Carlos Her	nandez		40/40/0044		0		#0.00
79567			10/10/2011		8		\$0.00
Medium	Work In Progress		10/10/2011 12:54:25				
Lara, Ralpl	h	need new lock for cabinet room 29					
Carlos Her	nandez		0/04/0044				Ф0.00
77323			8/24/2011		55		\$0.00
Medium	Work In Progress		8/24/2011 9:09:57 AM				
Ambriz, Jo	se	compressor on a/c unit in teachers lou	unge not working				
Carlos Her	nandez		9/24/2014		10		ድብ ብብ
77677	Wastala D		8/31/2011		48		\$0.00
Medium	Work In Progress		8/31/2011 3:57:52 PM				
Ambriz, Jo	se	need elbow "5 gooseneck and 16x16 storage	register for a/c				
Carlos Her	nandez	3 -					

10/18/2011 1:23:08 PM Page 118 of 172

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By Location, Status Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description	Target Comp Date actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	ES				
78335		9/14/2011		34		\$0.00
Medium	Work In Progress	9/14/2011 1:58:32 PM				
Ambriz, Jo	ose	room 76 (old computer lab) a/c not working needs new compressor				
Carlos Her 79721	rnandez	10/13/2011		5		\$0.00
Medium	Work In Progress	10/13/2011 8:26:51 AM		· ·		ψ0.00
Flores, Pet	-	need 15gal gas for truck				
Carlos Her						
79242	mandez	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:58 AM				
Hernandez	z, Carlos	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vil 79508	illalobos	10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:29 AM	10/20/2011	J		ψ0.00
Hernandez	· ·	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.				
Margret Vi	illalobos					
79270		10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:14 AM				
Hernandez	•	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.				
Margret Vil 79295	Illalobos	10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:27 AM				
Orozco, Da	anny	Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.				
Margret Vi	illalobos	0/0/2044		20		<u>Фо оо</u>
78125	Wash la Dassassa	9/9/2011		39		\$0.00
Medium	Work In Progress	9/9/2011 2:44:31 PM				
Munoz, Mi		need to construct concret pad for trash dumpsters				
Alfredo Ho 77021	olguin	8/16/2011		63		\$0.00
Medium	Work In Progress	8/16/2011 3:40:27 PM				
Ambriz, Jo	_	art portable is very hot has swamp cooler (is there any way to install ref. air)				
	rnandez	· , · · · · · · · · · · · · · · · · · · ·				

10/18/2011 1:23:08 PM Page 119 of 172

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By Location, Status Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time A Description	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	ES				
79144		10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:59 AM				
Hernandez	, Carlos	Yearly - Riverside ES H-6 Rooftop Furnance Yearly - Refer to PM schedule details.				
Margret Vil 79145	lalobos	10/2/2011	11/2/2011	16		\$0.00
	Mark In Drawna		11/2/2011	10		φυ.υυ
Medium	Work In Progress	10/2/2011 12:27:00 AM				
Hernandez	•	Yearly - Riverside ES I-4 Fan Coil Unit Yearly - Refer to PM schedule details.				
Margret Vil 79146	IAIODOS	10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:00 AM				
Hernandez	, Carlos	Yearly - Riverside ES U-2 Unit Heater Gas Yearly - Refer to PM schedule details.				
Margret Vil	lalobos	400004	10/05/0044			Φο οο
79537		10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:44 AM				
Romero, R		Monthly - QRTLY BLDG INSP REPORT (RS) - Refer to PM schedule details.				
Margret Vil 79148	IAIODOS	10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:01 AM				
Hernandez	, Carlos	Monthly - Riverside ES Roof Inpsection - Refer to PM schedule details.				
Margret Vil	lalobos					
79241		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:57 AM				
Hernandez	, Carlos	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vil 79861	lalobos	10/17/2011		1		\$0.00
Medium	Work In Progress	10/17/2011 3:28:26 PM				ψ0.00
	-					
Lara, Ralph		need 3 padlocks to lock side gates				
Carlos Her 78089	nandez	9/8/2011		40		\$0.00
Medium	Work In Progress	9/8/2011 3:30:23 PM				
Flores, Pet	-	small tractor has flat tire right front need repair				
0.00, 1 61	~	small tractor had hat the right front flood repair				

10/18/2011 1:23:09 PM Page 120 of 172

Selected Da	ate Range for Request Building	Dates:7/1/2011 - Area	6/30/2012 Order By Loc Deferred By	cation, Status Until		arget Comp Date	Days	Labor	Total Costs
Priority	Status	Area Number	Reason	Crea	ted Date/Time A	ctual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Riverside	ES							
78925					9/28/2011		20		\$0.00
Medium	Work In Progress			9/28/2	011 3:34:20 PM				
Hernande	z, Carlos	need to post si	gns in principals parki	ng					
Carlos He	rnandez								
79323					10/3/2011		15		\$0.00
Medium	Work In Progress			10/3/20	11 10:42:10 AM				
Orozco, D	anny	HAND SINK LE 589.2550	EAKING. SNP MANA	GER EMILIA	. C.				
Maritza Go	onzalez								
76890					8/12/2011		67		\$0.00
Medium	Work In Progress			8/12/2	011 3:32:08 PM				
Munoz, Mi	ichael	need new fend art portable	cing around new irraga	ation control	next to				
Carlos He	rnandez								
77702					9/1/2011		47		\$0.00
Medium	Work In Progress			9/1/20	11 11:10:02 AM				
Hernande:	z, Carlos	please purchas replace existing	se new D130 john dee g one.	ere lawn mo	wer to				
Michael M									
Count: 28	Work Orders	Α	vg. Age of WO's 27			Total for Riversid	e ES	0	\$0.00

10/18/2011 1:23:09 PM Page 121 of 172

Total Selected Date Range for Request Dates:7/1/2011 - 6/30/2012 Order By Location, Status Costs Building WOID Area **Deferred By** Until **Request Date Target Comp Date** Days Labor Aged Hours **Status** Area Number Reason Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description **Requester Name RTC - Alliance** Location: 79345 10/3/2011 15 \$0.00 Medium Work In Progress 10/3/2011 4:29:40 PM Castillo, Carlos AS PER GLORIA, WOULD LIKE TO SEE IF THEY CAN HAVE ELECTRICAL OUTLESTS INSTALLED IN CLASSROOM. THERE ARE 15 NEW COMPUTERS THAT ARE BEING SET UP. Maritza Gonzalez 79763 10/14/2011 4 \$0.00 Medium Work In Progress 10/14/2011 8:09:51 AM On October 20, 2011, please pick-up some obsolete Briones, Enrique monitors and towers from RTC. Contact Person: Gloria Saenz. Yolie Jacquez

Count: 2 Work Orders Avg. Age of WO's 10 Total for RTC - Alliance 0 \$0.00

10/18/2011 1:23:09 PM Page 122 of 172

WOID	Building	Area	6/30/2012 Order By Lo Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Crea	ted Date/Time	Actual Comp Date	Aged	Hours	
Assigned [*]	Го	Description				Action Taken			
Requester	Name								
Location:	San Migu	iel ES							
78853	Pump House	Pump House			9/27/2011		21		\$0.00
Medium	Work In Progress			9/27/2	011 2:05:16 PM				
Castillo, Ca	arlos	Need to discon	nect well and remove	e all electrical	panels				
Mario Apod	daca				40/0/0044		40		<u> </u>
79447					10/6/2011		12		\$0.00
Medium	Work In Progress			10/6/2	011 8:42:46 AM				
Lozoya, Ma	anny	Need to replac	e missing locks at kite	chen area.					
Michael Mu	unoz								
78981					9/29/2011		19		\$0.00
Medium	Work In Progress			9/29/20	11 11:55:26 AM				
Vega, Dan	ny	graffiti at main	bldg and potables						
Danny Veg	ıa								
79375					10/4/2011		14		\$0.00
Medium	Work In Progress			10/4/2	011 2:58:34 PM				
Ronquillo,	Ruben	PURCHASE S PURPOSES. FOR RUBEN 1	ECURITY SYSTEM F	FOR VANDAI	_ISM				
Ruben Ror	nguillo								
	ork Orders	Α	vg. Age of WO's 17	7	•	Total for San Migue	el ES	0	\$0.00

10/18/2011 1:23:09 PM Page 123 of 172

WOID Priority	Building Status	Area Number Reason	Until Request Date 1 Created Date/Time A	Target Comp Date Actual Comp Date	Days Aged	Labor Hours	
Assigned		Description		Action Taken			
Requester	r Name						
Location:	Santa Te	resa ES					
75820			7/26/2011		84		\$0.00
Medium	Work In Progress		7/26/2011 10:21:30 AM				
Villalobos,		WATER FOUNTAIN IN CAFET. DOFF. NEEDS TO BE CHECKED					
Gerardo M 76825	larquez Main Building	Restroom (Boys)	8/11/2011		68		\$0.00
Medium	Work In Progress	boys restrooms	8/11/2011 2:15:27 PM		00		φο.σσ
Villalobos,	•	PLEASE CHECK THE BOYS URI RESTROOMS. THEY SEEM TO	INALS IN ALL THE				
Dita Mand		THANKS.					
Rita Mend 76757	ez		8/10/2011		69		\$0.00
Medium	Work In Progress		8/10/2011 8:58:12 AM				
Castillo, C	_	HAND DRYER @ BOYS RRM. IN NEEDS REPLACING. NOT WOR					
<u>Gerardo M</u> 77434	<u>larquez</u>	Classroom	8/25/2011		54		\$0.00
Medium	Work In Progress	Mowles/ 108	8/25/2011 3:08:28 PM		01		φ0.00
Castillo, C	•	Teacher needs two electrical plug bathroom. Please check. Thank y	s installed in her				
Rosie Diaz	z Main Building	Classroom	7/27/2011		83		\$0.00
75906	· ·				03		ф0.00
Medium Lara, Ralp	Work In Progress	PARENT ROOM PLEASE PLACE LOCKS ON ALL THANKS.	7/27/2011 3:27:57 PM THE CABINETS.				
Rita Mend		Classican	0/20/2044		50		<u>ФО ОО</u>
77514	Main Building	Classroom	8/29/2011		50		\$0.00
Medium	Work In Progress	Perez/ Parent	8/29/2011 10:50:29 AM				
Lara, Ralp	h	We need a new lock and a key for desk. (197-E) Thank you.	r file cabinet, next to				
Rosie Diaz 76693	<u>z</u>		8/9/2011		70		\$0.00
Medium	Work In Progress		8/9/2011 10:40:20 AM		70		ψ0.00
	•	NEED TO DEDLACE EU TEDO IA					
Marquez,		NEED TO REPLACE FILTERS IN	I AC. UNI I S.				
<u>Gerardo M</u> 77359	larquez		8/24/2011		55		\$0.00
Medium	Work In Progress		8/24/2011 3:33:48 PM				,
Marquez, (_	NEED TO CHECK OUT HVAC IN COOLING & MOTOR MAKING A THANKS.	RM. 307. NOT				
Gerardo M 10/18/201	1arquez 1 1:23:09 PM					Page 12	24 of 172

Page 124 of 1/2

1200 - Work Orders In Progress (Fiscal Year)

WOID Priority Assigned Requeste	Building Status To	•	ate Target Comp Date ne Actual Comp Date Action Taken	ام م م	Labor Hours	Costs
Location:	Santa Te	resa ES				
79272		10/2/20	011 10/8/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:15	AM			
Marquez,	Gerardo	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.				
Margret Vi 79296	illalobos	10/2/2	011 10/23/2011	16		\$0.00
	Work In Drogram			10		ψ0.00
Medium	Work In Progress	10/2/2011 12:28:28	AIVI			
Orozco, D	·	Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.				
Margret Vi 78826	Main Building	Auditorium 9/27/20)11	21		\$0.00
Medium	Work In Progress	OTHER 9/27/2011 8:47:34	AM			
Marquez,	Gerardo	MS. JOHNSON WILL NEED ASSISTANCE WITH SETTING UP THE SCHOOL DISPLAY AND TAKE ART PROJECTS TO THE STATE FAIR IN LAS CRUCES, NM.				
Rita Mend 79814	ez	10/17/2)11	1		\$0.00
Medium	Work In Progress	SPED OFFICE 10/17/2011 10:17				·
Briones, E	•	PO #101108760 PICK UP TWO BOXES DELIVER TO ELIZABETH MOWLES-TEACHER-SANTA TERESA ELEMENTARY				
Margaret \ 78190	Villalobos	Parking Lot 9/12/20	111	36		\$0.00
	Waste In Drawage			30		ψ0.00
Medium	Work In Progress	9/12/2011 10:56:56	AIVI			
Munoz, Mi	ichael	PARKING LOT HAS DEVELOPED SOME CRACKS & MAY BE TIME FOR SOME CRACKSEALING IN ORDER TO PREVENT FURTHER DAMAGE. THANKS.				
Gerardo M	<u>larquez</u>	7/7/2	71.1	103		\$0.00
75198	W 11 B			103		φυ.υυ
Medium	Work In Progress	7/7/2011 8:31:31	AM			
Gallegos,	Rafael	DOOR LOCK ON ACTIVITY BOYS RESTROOM IN AUX. GYM. NEEDS TO BE CHECKED, DOOR CAN'T BE OPENED DUE TO LOCK NOT WORKING PROPERLY. (MIGHT STILL BE UNDER WARRANTY.)				
Arturo Nur 79532	nez	10/9/2	011 10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:41		J		ψυ.υυ
Diaz, Pabl	•	Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.	AIVI			
Margret Vi	illalobos	to 1 m solieudie details.				
10/18/201	1 1:23:09 PM				Page 1	25 of 172

WOID Priority Assigned 1 Requester			Deferred By		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa ES						
79158				10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:27:07 AM				
Marquez, G	Serardo	Monthly - Santa PM schedule de		Inspection - Refer to				
Margret Vill	alobos			10/2/2011	10/10/2011	16		<u></u>
79225				10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:27:47 AM				
Marquez, G		Monthly - Santa Refer to PM sch		Light Test: Monthly -				
Margret Vill 79226	alobos			10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:27:47 AM				******
Marquez, G	-	Monthly - Santa Refer to PM sch		ign Insp: Monthly -				
Margret Vill	alobos							
79197				10/2/2011		16		\$0.00
Medium	Work In Progress			10/2/2011 12:27:31 AM				
Marquez, G	Serardo	Monthly - Santa Refer to PM sch		nes Dryer (Monthly) -				
Margret Vill	alobos			10/9/2011	10/25/2011	9		\$0.00
79518	Mantala Dasanasa				10/25/2011	9		φυ.υυ
Medium Marquez, G	Work In Progress Serardo	Monthly - Santa PM schedule de		10/9/2011 12:16:34 AM round Insp - Refer to				
Margret Vill	alobos							
79681	Main Building	Classroom		10/12/2011		6		\$0.00
Medium	Work In Progress	TAGLE ROOM		10/12/2011 9:30:16 AM				
Marquez, G	Gerardo		TO BE SET UP (SROOM. THANK	,				
Rosie Diaz	Main Duillian	01		0/4/0044		47		# 0.00
77743	Main Building	Classroom		9/1/2011		47		\$0.00
Medium	Work In Progress	NURSE'S		9/1/2011 4:13:22 PM				
Lara, Ralph			RAGE DOOR NEE ESN'T LOCK. TH	EDS TO BE SET UP ANKS				
Rita Mende 77855	Z			9/4/2011		44		\$0.00
Medium	Work In Progress			9/4/2011 12:24:21 AM				ψ3.00
Marquez, G	· ·	Monthly - Santa		Quarterly MSS - Refer				

10/18/2011 1:23:09 PM Page 126 of 172

Page	Selected D	ate Range for Request Building	Dates:7/1/2011 - 6/30/2012 Order By Area Deferred By		rget Comp Date	Days	Labor	Total Costs
Santa Teresa ES	Priority Assigned	Status To	Area Number Reason	•	tual Comp Date	-		
10/2/2011 16 \$0.00	•		rosa FS					
Marquez, Gerardo Monthly - Santa Teresa ES-A-16 Fan Exhaust (SemiA) - Refer to PM schedule details. 10/2/2011 11/2/2011 16 \$0.00		Janta Te		10/2/2011		16		90.00
Marquez, Gerardo Monthly - Santa Teresa ES-A-16 Fan Exhaust (SemiA) - Refer to PM schedule details.		Work In Progress				10		ψ0.00
Medium Work In Progress 10/2/2011 11/2/2011 16 \$0.00		_						
Marquez, Gerardo Yearly - Santa Teresa ES-H6 Rooftop Fur (Yearly) - Refer to PM schedule details. 10/2/2011 11/2/2011 16 \$0.00		illalobos		40/0/0044	44/0/0044	40		<u>Фо</u> оо
Marquez, Gerardo Yearly - Santa Teresa ES-H6 Rooftop Fur (Yearly) - Refer to PM schedule details.					11/2/2011	10		\$0.00
Refer to PM schedule details. Alargret Villalobos 9128 10/2/2011 11/2/2011 16 \$0.00 Aledium Work In Progress Alarquez, Gerardo Yearly - Santa Teresa ES-U2 Heat Gas (Yearly) - Refer to PM schedule details. Alargret Villalobos 8189 9/12/2011 36 \$0.00 Aledium Work In Progress 9/12/2011 10.49.21 AM Fibres, Pete NEED FOR TRUCK 107 TO BE SERVICED. (TUNE UP, OIL CHANGE & CHECK OUT OIL LEAK.) THANKS. Berardo Marquez 7549 Classroom 8/29/2011 50 \$0.00 Aledium Work In Progress ROOM 212 8/29/2011 4.07.45 PM Alarquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN TO THE OPPOSITE WALL IN ROOM 212, MS. CONE. THANKS. Altia Mendez 77579 Classroom 8/30/2011 49 \$0.00 Aledium Work In Progress MS. TAGLE 208 8/30/2011 11:22:21 AM Alarquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN FROM ONE WALL TO ANOTHER Altia Mendez 77717 Main Building Hallway/Corridor 9/1/2011 47 \$0.00 Aledium Work In Progress casa blanca and 9/1/2011 2:38:14 PM Alarquez, Gerardo PLEASE CHECK THE WATER FOUNTAINS AT THE END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDSU PO NT HE FLOOR. WE ALERADY HAD A STUDENT FALL DUE TO WATER ON THE FLOOR. WE ALERADY HAD A STUDENT FALL DUE TO WATER ON THE FLOOR. WE ALESO NEED MATS IN BOTH OF THESE AREAS. THANK YOU		•						
10/2/2011 11/2/2011 16 \$0.00	•		•	oftop Fur (Yearly) -				
Aarquez, Gerardo Yearly - Santa Teresa ES-U2 Heat Gas (Yearly) - Refer to PM schedule details. Aargret Villalobos 81819 9/12/2011 10:49:21 AM Allow Work In Progress NEED FOR TRUCK 107 TO BE SERVICED. (TUNE UP, OIL CHANGE & CHECK OUT OIL LEAK.) THANKS. Berardo Marquez 7549 Classroom 8/29/2011 50 \$0.00 Addium Work In Progress ROOM 212 8/29/2011 4:07:45 PM Aarquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN TO THE OPPOSITE WALL IN ROOM 212, MS. CONE. THANKS. Rita Mendez 7579 Classroom 8/30/2011 11:22:21 AM Aarquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN FROM ONE WALL TO ANOTHER Rita Mendez 7717 Main Building Hallway/Corridor Aarquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN FROM ONE WALL TO ANOTHER Rita Mendez 7717 Main Building Hallway/Corridor PLEASE CHECK THE WATER FOUNTAINS AT THE END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDS UP ON THE FLOOR. WE ALROADY HAD A STUDENT FALL DUE TO WATER ON THE FLOOR. WE ALSO NEED MATS IN BOTH OF THESE AREAS. THANK YOU	Margret V 79128	illalobos		10/2/2011	11/2/2011	16		\$0.00
Aarquez, Gerardo Yearly - Santa Teresa ES-U2 Heat Gas (Yearly) - Refer to PM schedule details. Aargret Villalobos 81819 9/12/2011 10:49:21 AM Allow Work In Progress NEED FOR TRUCK 107 TO BE SERVICED. (TUNE UP, OIL CHANGE & CHECK OUT OIL LEAK.) THANKS. Berardo Marquez 7549 Classroom 8/29/2011 50 \$0.00 Addium Work In Progress ROOM 212 8/29/2011 4:07:45 PM Aarquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN TO THE OPPOSITE WALL IN ROOM 212, MS. CONE. THANKS. Rita Mendez 7579 Classroom 8/30/2011 11:22:21 AM Aarquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN FROM ONE WALL TO ANOTHER Rita Mendez 7717 Main Building Hallway/Corridor Aarquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN FROM ONE WALL TO ANOTHER Rita Mendez 7717 Main Building Hallway/Corridor PLEASE CHECK THE WATER FOUNTAINS AT THE END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDS UP ON THE FLOOR. WE ALROADY HAD A STUDENT FALL DUE TO WATER ON THE FLOOR. WE ALSO NEED MATS IN BOTH OF THESE AREAS. THANK YOU	Medium	Work In Progress		10/2/2011 12:26:50 AM				
18189 9/12/2011 36 \$0.00	Marquez,	Gerardo		at Gas (Yearly) - Refer				
Medium Work In Progress Warrengt Work In Progress Work In Progress Warrengt		illalobos		0/40/0044				Φο οο
Riores, Pete NEED FOR TRUCK 107 TO BE SERVICED. (TUNE UP, OIL CHANGE & CHECK OUT OIL LEAK.) THANKS. Serardo Marquez Classroom 8/29/2011 50 \$0.00 Medium Work In Progress ROOM 212 8/29/2011 4:07:45 PM Marquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN TO THE OPPOSITE WALL IN ROOM 212, MS. CONE. THANKS. Rita Mendez Classroom 8/30/2011 4:9 \$0.00 Medium Work In Progress MS. TAGLE 208 8/30/2011 11:22:21 AM Marquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN FROM ONE WALL TO ANOTHER Rita Mendez T7717 Main Building Hallway/Corridor 9/1/2011 47 \$0.00 Medium Work In Progress casa blanca and 9/1/2011 2:38:14 PM Marquez, Gerardo PLEASE CHECK THE WATER FOUNTAINS AT THE END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDS UP ON THE FLOOR. WE ALSO NEED MATS IN BOTH OF THESE AREAS. THANK YOU						36		\$0.00
OIL CHANGE & CHECK OUT OIL LEAK.) THANKS. Serardo Marquez Classroom 8/29/2011 50 \$0.00 Medium Work In Progress ROOM 212 8/29/2011 4:07:45 PM Marquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN TO THE OPPOSITE WALL IN ROOM 212, MS. CONE. THANKS. Rita Mendez 77579 Classroom 8/30/2011 49 \$0.00 Medium Work In Progress MS. TAGLE 208 8/30/2011 11:22:21 AM Marquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN FROM ONE WALL TO ANOTHER Rita Mendez 77777 Main Building Hallway/Corridor 9/1/2011 47 \$0.00 Medium Work In Progress casa blanca and 9/1/2011 2:38:14 PM Marquez, Gerardo PLEASE CHECK THE WATER FOUNTAINS AT THE END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDS UP ON THE FLOOR. WE ALSO NEED MATS IN BOTH OF THESE AREAS. THANK YOU	Medium	Work In Progress		9/12/2011 10:49:21 AM				
Acquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN TO THE OPPOSITE WALL IN ROOM 212, MS. CONE. THANKS. Rita Mendez T57579 Classroom MS. TAGLE 208 MS. T								
Medium Work In Progress ROOM 212 8/29/2011 4:07:45 PM Marquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN TO THE OPPOSITE WALL IN ROOM 212, MS. CONE. THANKS. Rita Mendez 17579 Classroom 8/30/2011 49 \$0.00 Medium Work In Progress MS. TAGLE 208 8/30/2011 11:22:21 AM Marquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN FROM ONE WALL TO ANOTHER Rita Mendez 17717 Main Building Hallway/Corridor 9/1/2011 47 \$0.00 Medium Work In Progress casa blanca and 9/1/2011 2:38:14 PM Marquez, Gerardo PLEASE CHECK THE WATER FOUNTAINS AT THE END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDS UP ON THE FLOOR. WE ALREADY HAD A STUDENT FALL DUE TO WATER ON THE FLOOR. WE ALSO NEED MATS IN BOTH OF THESE AREAS. THANK YOU	Gerardo N 77549	Marquez	Classroom	8/29/2011		50		\$0.00
Marquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN TO THE OPPOSITE WALL IN ROOM 212, MS. CONE. THANKS. Rita Mendez 7579 Classroom Mork In Progress MS. TAGLE 208 MS.		Work In Progress						ψ0.00
Classroom 8/30/2011 49 \$0.00 Medium Work In Progress MS. TAGLE 208 8/30/2011 11:22:21 AM Marquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN FROM ONE WALL TO ANOTHER Rita Mendez T7717 Main Building Hallway/Corridor 9/1/2011 47 \$0.00 Medium Work In Progress casa blanca and 9/1/2011 2:38:14 PM Marquez, Gerardo PLEASE CHECK THE WATER FOUNTAINS AT THE END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDS UP ON THE FLOOR. WE ALREADY HAD A STUDENT FALL DUE TO WATER ON THE FLOOR. WE ALSO NEED MATS IN BOTH OF THESE AREAS. THANK YOU	Marquez,	Gerardo	PLEASE MOVE THE PROJECTION OPPOSITE WALL IN ROOM 212	ON SCREEN TO THE				
Marquez, Gerardo PLEASE MOVE THE PROJECTION SCREEN FROM ONE WALL TO ANOTHER Rita Mendez PART Main Building Hallway/Corridor Medium Work In Progress Casa blanca and PLEASE CHECK THE WATER FOUNTAINS AT THE END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDS UP ON THE FLOOR. WE ALREADY HAD A STUDENT FALL DUE TO WATER ON THE FLOOR. WE ALSO NEED MATS IN BOTH OF THESE AREAS. THANK YOU	77579	lez	Classroom	8/30/2011		49		\$0.00
ONE WALL TO ANOTHER Rita Mendez 17717 Main Building Hallway/Corridor 9/1/2011 47 \$0.00 Medium Work In Progress casa blanca and 9/1/2011 2:38:14 PM Marquez, Gerardo PLEASE CHECK THE WATER FOUNTAINS AT THE END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDS UP ON THE FLOOR. WE ALREADY HAD A STUDENT FALL DUE TO WATER ON THE FLOOR. WE ALSO NEED MATS IN BOTH OF THESE AREAS. THANK YOU	Medium	Work In Progress	MS. TAGLE 208	8/30/2011 11:22:21 AM				
7717 Main Building Hallway/Corridor 9/1/2011 47 \$0.00 Medium Work In Progress casa blanca and 9/1/2011 2:38:14 PM Marquez, Gerardo PLEASE CHECK THE WATER FOUNTAINS AT THE END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDS UP ON THE FLOOR. WE ALREADY HAD A STUDENT FALL DUE TO WATER ON THE FLOOR. WE ALSO NEED MATS IN BOTH OF THESE AREAS. THANK YOU	Marquez,	Gerardo		ON SCREEN FROM				
Medium Work In Progress casa blanca and 9/1/2011 2:38:14 PM Marquez, Gerardo PLEASE CHECK THE WATER FOUNTAINS AT THE END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDS UP ON THE FLOOR. WE ALREADY HAD A STUDENT FALL DUE TO WATER ON THE FLOOR. WE ALSO NEED MATS IN BOTH OF THESE AREAS. THANK YOU	Rita Meno		Hallway/Corridor	9/1/2011		47		\$0.00
END OF CASA BLANCA AND ALSO THE ONES BY THE CAFETERIA'S BACK DOOR. NEED TO BE ADJUSTED. ALOT OF WATER ENDS UP ON THE FLOOR. WE ALREADY HAD A STUDENT FALL DUE TO WATER ON THE FLOOR. WE ALSO NEED MATS IN BOTH OF THESE AREAS. THANK YOU	Medium	_	casa blanca and	9/1/2011 2:38:14 PM				
Rita Mendez	Marquez,	Gerardo	END OF CASA BLANCA AND AL THE CAFETERIA'S BACK DOOR ADJUSTED. ALOT OF WATER IF FLOOR. WE ALREADY HAD A STO WATER ON THE FLOOR. W	SO THE ONES BY E. NEED TO BE ENDS UP ON THE STUDENT FALL DUE E ALSO NEED MATS				
	Rita Meno	lez						

10/18/2011 1:23:09 PM Page 127 of 172

Salastad Da	ate Range for Request	Dotoo:7/1/2011	6/20/2012 Order By Le	saction Status	•				Tota
WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Cost
Priority	Status	Area Number	Reason	Crea	ted Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requester	r Name								
Location:	Santa Te	resa ES							
78537	Main Building	Classroom			9/20/2011		28		\$0.00
Medium	Work In Progress	ROOM 101		9/20/2	011 9:38:06 AM	1			
Marquez,	Gerardo	NEED ANOTH RESTROOM.	ER MIRROR PLACE THANKS.	D IN THE					
Rita Mend	ez								
78836	Main Building	Classroom			9/27/2011		21		\$0.00
Medium	Work In Progress	Tuthill/ 011		9/27/20	11 10:24:57 AM	1			
Marquez,	Gerardo	Bulletin board	needs to be set up. th	hanks.					
Rosie Diaz	Z								
Count: 32	Work Orders	Α	vg. Age of WO's 3	7	Т	otal for Santa Teres	a ES	0	\$0.00

10/18/2011 1:23:09 PM Page 128 of 172

WOID	Building	Dates:7/1/2011 - 6/30/2012 Order By Area Deferred By	Until Request Date	Target Comp Date	Days Aged	Labor Hours	Costs
Priority	Status	Area Number Reason	Created Date/Time	•	Ageu	Hours	
Assigned Requeste		Description		Action Taken			
Location:	Santa Te	rosa US					
			8/4/2011		75		ቀስ ሰስ
76449	Main Building	Restroom (Girls)			75		\$0.00
Medium	Work In Progress		8/4/2011 3:25:55 PM	1			
Villalobos,		Bathrooms boys and girls continuous one present and lights are off	ue flushing even when				
Rosalinda 76451	Rodriguez Gymnasium	Gym	8/4/2011		75		\$0.00
Medium	Work In Progress	•	8/4/2011 3:30:28 PM	1			
Villalobos,	•	Athletic locker room, volleyball/baare not working and students nee	asketball area, showers				
	Rodriguez						
78366			9/14/2011		34		\$0.00
Medium	Work In Progress		9/14/2011 6:22:42 PM	1			
Villalobos,	David	sinks in locker rooms need to be water doesnt come out in some	replaced				
Jorge Pere 78368	ez		9/14/2011		34		\$0.00
Medium	Work In Progress		9/14/2011 6:26:46 PM	1	04		ψ0.00
Villalobos,	•	drains in shower need to be uncled		'			
Jorge Pere	ez		0/00/0044				Ф0.00
78532			9/20/2011	_	28		\$0.00
Medium	Work In Progress		9/20/2011 7:59:50 AM	1			
Villalobos,		NEED TO HAVE "P" TRAPS FOI OLD BOYS DRESSING ROOM F					
Arturo Nur 76387	nez		8/3/2011		76		\$0.00
Medium	Work In Progress		8/3/2011 3:07:08 PM	1			
Castillo, C	•	NEED TWO (2 EA.) 115 V. ELE I CAN REPLACED SOME THAT	C. OULETS SO THAT				
Arturo Nur							
79682	Cafeteria (2005)		10/12/2011		6		\$0.00
Medium	Work In Progress		10/12/2011 9:30:19 AM	1			
Perez, Jor	ge	SOAP DISPENSER NEEDS TO KITCHEN AREA. SNP MANAGE					
Maritza Go 78720	onzalez GYM (2009)	Gym	9/23/2011		25		\$0.00
Medium	Work In Progress	STHS TRAINER	9/23/2011 11:40:40 AM	1			+ 0.00
Flores, Pe	•	PLEASE DELIVER 5 GALLONS FRANK MUNOZ - TRAINER AT : PLEASE CHARGE ATHELTIC O GASOLINE. THANK YOU!	OF GASOLINE TO STHS FOR GATOR.				
Terry Alva	rado						
	1 1·23·09 PM					Pogo 1	

10/18/2011 1:23:09 PM Page 129 of 172

WOID	Building	• • • • • •	-	Target Comp Date	Days	Labor	
Priority	Status	Area Number Reason	Created Date/Time	•	Aged	Hours	
Assigned		Description		Action Taken			
Requester							
Location:	Santa Te	resa HS					
78382			9/15/2011		33		\$0.00
Medium	Work In Progress		9/15/2011 8:27:35 AM				
Ambriz, Jo	ose	NEED A 200,000 BTU HEATER FOR S	HOP # 807				
Arturo Nur	nez		40/47/0044				Φο οο
79871			10/17/2011		1		\$0.00
Medium	Work In Progress		10/17/2011 3:51:16 PM				
Ambriz, Jo		NEED TO INSTALL VENT PIPE AND M NEW PLASMA ZING MACINE CUTTER 602					
<u>Arturo Nur</u> 78512	nez Main Building	Hallway/Corridor	9/19/2011		29		\$0.00
Medium	Work In Progress	,	9/19/2011 3:37:15 PM				
Prospero,	· ·	ON 9/16/11 JUAN TELLEZ THE HEAD					
•		CALL ME AT 6;30 PM FOR WATER LE HALLWAY ON ROOF.					
<u>Manuel Pr</u> 78262	ospero	Athletic Field	9/13/2011		35		\$0.00
Medium	Work In Progress		9/13/2011 2:22:22 PM				Ψ0.00
Gonzalez,	· ·	please replace wood roofing on tennis or colored metal panels. See mike on color. thank you	ourt shades with				
Michael M		·					
78701	Main Building	Classroom	9/22/2011		26		\$0.00
Medium	Work In Progress		9/22/2011 3:48:27 PM				
Perez, Jor William Di		Room 505 need to sweep and picked up).	CALLED AND NOTI WORK ORDER TO		RGE, FA>	KED
79374	CKSOII		10/4/2011		14		\$0.00
Medium	Work In Progress		10/4/2011 2:50:10 PM				
Perez, Jor	ge	Need to change toilet paper dispensers restroom located in the main hall.	on girls				
Jorge Pere 78376	ez		9/15/2011		33		\$0.00
Medium	Work In Progress		9/15/2011 8:15:55 AM		00		Ψ0.00
	-	NEED A 000 00 DTH HEATER FOR OH					
Ambriz, Jo		NEED A 200,00 BTU HEATER FOR SH	UF # 0U I.				
<u>Arturo Nur</u> 78377	nez		9/15/2011		33		\$0.00
Medium	Work In Progress		9/15/2011 8:18:20 AM				, , , ,
Ambriz, Jo	_	NEED A 125,000 BTU HEATER FOR F SHOP # 803.					
Arturo Nur		55. # 505.					

10/18/2011 1:23:09 PM Page 130 of 172

WOID	Building	Area Deferred By Until	Request Date Target Comp Date	Days	Labor	
Priority	Status	Area Number Reason Crea	ted Date/Time Actual Comp Date	Aged	Hours	
Assigned 1	Го	Description	Action Taken			
Requester	Name					
Location:	Santa Tei	resa HS				
78378			9/15/2011	33		\$0.00
Medium	Work In Progress	9/15/20	011 8:19:30 AM			
Ambriz, Jos	se	NEED A 300,000 B.T.U HEATER FOR SHOP #	803.			
Arturo Nun	ez					
78379			9/15/2011	33		\$0.00
Medium	Work In Progress	9/15/20	011 8:24:15 AM			
Ambriz, Jos	se	NEED A 125,000 BTU HEATER FOR OFFICE IN # 805.	SHOP			
Arturo Nun 78380	ez		9/15/2011	33		\$0.00
Medium	Work In Progress	9/15/20	011 8:25:20 AM			*****
Ambriz, Jos	_	NEED A 300,00 BTU HEATER FOR SHOP # 805				
,		NEED A 300,00 BTO HEATERT ON SHOT # 800).			
<u>Arturo Nun</u> 78381	ez		9/15/2011	33		\$0.00
Medium	Work In Progress	9/15/20	011 8:26:26 AM			
Ambriz, Jos	se	NEED A 125,000 HEATER FOR OFFICE IN SHO 807.	DP#			
Arturo Nun	ez		7/00/0044			Φο οο
76015			7/29/2011	81		\$0.00
Medium	Work In Progress	MRS. 7/29/20	011 1:53:52 PM			
Prospero, I	Manuel	MAINTENANCE PLEASE CHECK ON HVAC UN LOCATED BETWEEN MAIN BUILDING AND CAFETERIA-EXCESSIVE NOISE WHILE RUNN AND LOUD BANGING WHEN AT LEAST 1 UNIT SHUTS DOWN.	ING			
Marylou Jir 77113	nenez		8/18/2011	61		\$0.00
Medium	Work In Progress	9/49/20	0/10/2011 011 3:29:44 PM	O I		ψ0.00
	· ·					
Ambriz, Jos		Need some assistance on trouble shooting e.c's of gym, new dressing rooms, and coaches offices.	on new			
<u>Arturo Nun</u> 77137	ez Main Building		8/19/2011	60		\$0.00
Medium	Work In Progress	8/19/20	011 8:59:11 AM			
Ambriz, Jos	-	room 501 still leaking Room 502, 503, 506, 508 reporting AC/HVAC pro Gym area locker rooms, coaches office and traine	oblems			

10/18/2011 1:23:09 PM Page 131 of 172

Rosalinda Rodriguez

Priority Assigned [·]		Area Number Reason Description	Created Date/Time	Actual Comp Date Action Taken	Aged	Hours	
Requester	Name						
Location:	Santa Te	resa HS					
77138	Library	Library	8/19/2011		60		\$0.00
Medium	Work In Progress		8/19/2011 8:59:56 AM				
Nunez, Art	uro	Library office AC/HVAC not work	ing				
Rosalinda		Classroom	8/19/2011		60		\$0.00
77182	Main Building	Classiooni			60		\$0.00
Medium	Work In Progress		8/19/2011 3:42:27 PM				
Ambriz, Jo	se	The following classrooms need A C-1; 203; 306; 301; 401; Mrs. Ha					
Rosalinda	Rodriguez		•				
78375			9/15/2011		33		\$0.00
Medium	Work In Progress		9/15/2011 8:14:09 AM				
Ambriz, Jo		NEED A 125,000 BTU HEATER SHOP, ROOM # 801.	FOR OFFICE IN				
Arturo Nun 79835	iez		10/17/2011		1		\$0.00
Medium	Work In Progress	SPED OFFICE	10/17/2011 10:52:16				·
Briones, E	nrique	PO #101108760 PICK UP ONE BOX DELIVER TO SAL AVILATEACHER-SANTA SCHOOL					
Margaret V	/illalobos		40/47/0044		4		<u></u>
79837			10/17/2011		1		\$0.00
Medium	Work In Progress	SPED OFFICER	10/17/2011 11:03:40				
Briones, E	nrique	PO #101108760 PICK UP ONW BOX DELIVER T TANYA RIOSFACILITATOR FO FOR G. GOODMAN/SANTA TER	OR REPLACEMENT				
Margaret V	/illalobos		8/22/2011		57		\$0.00
Medium	Work In Progress	MARYLOU	8/22/2011 10:15:41 AM		O1		Ψ0.00
	Ü	CAN STHS BORROW A FORK L					
Ronquillo,	Kuben	A PRINTER FROM FRONT OFF DRAFTING CLASSROOM OUT I BLDG.	ICE STORAGE TO				
Marylou Jir 78414	menez	Classroom	9/16/2011		32		\$0.00
Medium	Work In Progress	5.300.00	9/16/2011 7:38:49 AM		02		Ψ0.00
	-	places remove all salling tiles are					
Prospero, I	ivianuei	please remove all ceiling tiles and removed from the cullinary art room					

10/18/2011 1:23:09 PM Page 132 of 172

WOID	Building	Area Deferred By	Until Request Date Ta	-	Days	Labor	
Priority	Status	Area Number Reason	Created Date/Time Ac	-	Aged	Hours	
Assigned		Description		Action Taken			
Requester	Name						
Location:	Santa Te	resa HS					
78491	Gymnasium	Dressing Room	9/19/2011		29		\$0.00
Medium	Work In Progress		9/19/2011 9:28:15 AM				
Estrada, Je	esus	Replace the carpet in football lock tile.	er room with anti slip				
Jesus Estr	ada		=////				
75290			7/11/2011		99		\$0.00
Medium	Work In Progress		7/11/2011 12:29:44 PM				
Ambriz, Jo	se	NEED SOME ASSITANCE ON TE CHILLER, RESET ALARMS, BUT STAY ON					
Arturo Nun	nez		40/0/0044	40/02/2044	4.0		#0.00
79308			10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:34 AM				
Orozco, Da	anny	Monthly - Santa Teresa HS Fire S to PM schedule details.	Sprinkler Insp Refer				
Margret Vil	llalobos		7/4/2011	8/3/2011	106		\$0.00
_				0/3/2011	100		φυ.υυ
Medium	Work In Progress		7/4/2011 12:21:34 AM				
Nunez, Art		Yearly - Santa Teresa HS Emer. I Refer to PM schedule details.	Light Test: Annual -				
Margret Vil 74925	llalobos		7/4/2011	8/3/2011	106		\$0.00
	Mark In Drawage			0/3/2011	100		ψ0.00
Medium	Work In Progress		7/4/2011 12:21:35 AM				
Nunez, Art		Yearly - Santa Teresa HS Exit Siç to PM schedule details.	gn Test: Annual - Refer				
Margret Vil 79634	<u>llalobos</u> Main Building	Office	10/11/2011		7		\$0.00
Medium	Work In Progress		10/11/2011 2:32:19 PM		-		ψ0.00
	· ·	FRANK MUNOZ					
Martinez, L	_arry	PLEASE DELIVER THE FOLLOV FRANK MUNOZ	VING ITEMS TO:				
		PO# 111200242 - 1BOX(MEDICA TRAINER	AL SUPPLIES) - STHS				
Terry Alvai 79761	rado		10/14/2011		4		\$0.00
	Work In Progress		10/14/2011 8:04:34 AM		7		ψυ.υυ
Medium	Work In Progress						
Briones, E	nrique	On October 18, 2011, please pick from Santa Teresa High School. empty Gaylord + pallet. Contact I Hernandez.	Also, deliver another				
		Herriandez.					

10/18/2011 1:23:09 PM Page 133 of 172

WOID Priority Assigned Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS						
79812				10/17/2011		1		\$0.00
Medium	Work In Progress	SPED OFFICE		10/17/2011 10:08:33				
Briones, Er	nrique		OX DELIVER TO	ITA TERESA HIGH				
Margaret V	'illalobos			7/4/2011	7/9/2011	106		\$0.00
74926	Work In Drogram			7/4/2011 12:21:35 AM		100		φυ.υυ
Medium	Work In Progress		T 110.14 11					
Nunez, Artı		Monthly - Santa Refer to PM scl	a Teresa HS Month hedule details.	ly FE Inspection -				
<u>Margret Vil</u> 76057	lalobos			7/31/2011	8/6/2011	79		\$0.00
Medium	Work In Progress			7/31/2011 9:24:46 AM	1			
Nunez, Artı	•	Monthly - Santa Refer to PM scl	a Teresa HS Month hedule details.	ly FE Inspection -				
Margret Vil	lalobos			9/4/2011	9/10/2011	44		\$0.00
77820 Madium	Work In Drogram					44		φυ.υυ
Medium	Work In Progress		T 110.14 11	9/4/2011 12:24:06 AM				
Nunez, Artı		Refer to PM scl	a Teresa HS Month hedule details.	ly FE Inspection -				
<u>Margret Vil</u> 79271	lalobos			10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:28:15 AM				,
Nunez, Artı	•	Monthly - Santa Refer to PM scl	a Teresa HS Month hedule details.					
Margret Vil	lalobos			40/0/0044	40/00/0044	40		# 0.00
79297				10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		_	10/2/2011 12:28:28 AM				
Orozco, Da	•	Monthly - Santa Refer to PM scl	a Teresa HS Range hedule details.	e Hood Cleaning -				
<u>Margret Vil</u> 74953	lalobos			7/4/2011	7/24/2011	106		\$0.00
Medium	Work In Progress			7/4/2011 12:21:48 AM				
Orozco, Da	-	Monthly - Santa to PM schedule		prinkler Insp Refer				
Margret Vil	lalobos			0/4/0044		11		<u></u>
77822	Mank In December			9/4/2011		44		\$0.00
Medium	Work In Progress			9/4/2011 12:24:07 AM				
Nunez, Artı		Monthly - Santa Refer to PM scl		es Dryer (Monthly) -				
Margret Vil	lalobos							

WOID	Building	•	Target Comp Date	Days Aged	Labor Hours	
Priority	Status		Actual Comp Date Action Taken	Ageu	Hours	
Assigned Requester		Description	Action Taken			
Location:	Santa Te	resa HS				
78666	- Canta To	9/22/2011	1	26		\$0.00
Medium	Work In Progress	9/22/2011 10:29:40 A		20		ψ0.00
Holguin, A	_	Collect Equipment data and inventory per PFSA requirements new Gym	vi			
Alfredo Ho	olguin			- 40		
79228		10/2/201		16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:48 Al	М			
Nunez, Ari		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret Vi 79182	llalobos	10/2/201	1 11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:21 AF	M			
Prospero,	Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.				
Margret Vi	llalobos	40/0/04	40/40/0044	40		Φο οο
79183		10/2/201		16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:21 Al	VI			
Prospero,		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.				
Margret Vi 79184	llalobos	10/2/2011	1 10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:22 A	M			
Prospero,	Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vi	llalobos					
75043		7/4/2011		106		\$0.00
Medium	Work In Progress	7/4/2011 12:22:28 Al	М			
Prospero,		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.				
Margret Vi 75044	llalobos	7/4/201	7/11/2011	106		\$0.00
Medium	Work In Progress	7/4/2011 12:22:29 AF				
Prospero,	_	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vi	llalobos					
76124		7/31/201		79		\$0.00
Medium	Work In Progress	7/31/2011 9:25:15 AI	M			
Prospero,	Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.				

10/18/2011 1:23:09 PM Page 135 of 172

WOID	Building	•	ate Target Comp Date		Labor	Total Costs
Priority	Status		ne Actual Comp Date	Aged	Hours	
Assigned		Description	Action Taken			
Requeste						
ocation:	Santa Te	resa HS				
76125		7/31/20	11 8/8/2011	79		\$0.00
Medium	Work In Progress	7/31/2011 9:25:16	AM			
Prospero,	Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.				
<u>Margret V</u> 76126	illalobos	7/31/20	11 8/8/2011	79		\$0.00
	W 11 B			19		φυ.υυ
Medium	Work In Progress	7/31/2011 9:25:16	AM			
Prospero,		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.				
<u>Margret V</u> 76056	IIIAIODOS	7/31/20	11	79		\$0.00
Medium	Work In Progress	7/31/2011 9:24:45	AM			
Nunez, Ar	ŭ	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret V	illalobos					
75271		7/10/20	7/26/2011	100		\$0.00
Medium	Work In Progress	7/10/2011 12:16:07	AM			
Meraz, Ra	afael	Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.				
<u>Jesus Est</u> 79524	rada	10/9/20	11 10/25/2011	9		\$0.00
	Mark In Drograda			3		ψ0.00
Medium Gomez, Jo	Work In Progress ose L	10/9/2011 12:16:37 Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.	AW			
Margret V	'illalobos	to i in soriedule details.				
74927	maiosoo	7/4/20	7/11/2011	106		\$0.00
Medium	Work In Progress	7/4/2011 12:21:36	AM			
Nunez, Ar	turo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.				
Margret V	illalobos	10/0/0				
79151		10/2/20		16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:03	AM			
Nunez, Ar	rturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.				
<u>Margret V</u> 74929	illalobos	7/4/20	11	106		\$0.00
	Work In Drograss			100		ψυ.υυ
Medium	Work In Progress	7/4/2011 12:21:37	MIVI			
Nunez, Ar		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret V	illalobos					

10/18/2011 1:23:09 PM Page 136 of 172

WOID Priority Assigned Requester			Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS				
75042		7/4/2011	8/3/2011	106		\$0.00
Medium	Work In Progress	7/4/2011 12:22:28 AM	1			
Prospero,	Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.				
Margret Vi 79133	llalobos	10/2/2011	10/18/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:53 AM	Л			
Villalobos,	Margret	Yearly - Santa Teresa HS October Chiller Insp Refer to PM schedule details.				
Margret Vi 79134	llalobos	10/2/2011	10/18/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:54 AN		.0		φοίσο
Villalobos,	•	Monthly - Santa Teresa HS Monthly Chiller Insp Refer to PM schedule details.				
Margret Vi	llalobos	10/0/04	10/00/0044			Φο οο
79084		10/2/2011		16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:26 AN	Л			
Prospero,		Monthly - Santa Teresa HS C-12 Chm Feeder Semimtly - Refer to PM schedule details.				
Margret Vi 79085	IIAIODOS	10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:27 AN	Л			
Prospero,	Manuel	Yearly - Santa Teresa HS I-4 Fan Coil Unit Yearly - Refer to PM schedule details.				
Margret Vi	llalobos	10/2/2011	11/2/2011	16		\$0.00
79086 Medium	Mork In Drogram	10/2/2011 12:26:28 AN		10		φυ.υυ
Prospero,	Work In Progress Manuel	Yearly - Santa Teresa HS U-2 Unit Ht Gas Yearly -	И			
Margret Vi	llalohos	Refer to PM schedule details.				
79505	naioboo	10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:28 AM	Л			
Nunez, Art	turo	Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.				
Margret Vi 76599	llalobos	8/7/2011	9/7/2011	72		\$0.00
Medium	Work In Progress	8/7/2011 12:16:41 AN		12		ψυ.υυ
Prospero,	-	Yearly - Santa Teresa HS A-9 Air Cooled Yearly - Refer to PM schedule details.				

10/18/2011 1:23:09 PM Page 137 of 172

Margret Villalobos 79018 Medium Work Prospero, Manuel Margret Villalobos 79129 Medium Work Nunez, Arturo Margret Villalobos 79130	In Progress	9/4/2011 12 Monthly - Santa Teresa HS Monthly Chiller Insp Refeto PM schedule details.	9/30/2011 22:34 AM	9/20/2011	44	\$0.00
Medium Work Villalobos, Margret Margret Villalobos 79018 Medium Work Prospero, Manuel Margret Villalobos 79129 Medium Work Nunez, Arturo Margret Villalobos 79130	In Progress	Monthly - Santa Teresa HS Monthly Chiller Insp Refeto PM schedule details. 9/30/2011 12 Monthly - Santa Teresa HS A-16 Roof/Exh Semiannua	24:00 AM er 9/30/2011 22:34 AM	9/20/2011		\$0.00
Villalobos, Margrei Margret Villalobos 79018 Medium Work Prospero, Manuel Margret Villalobos 79129 Medium Work Nunez, Arturo Margret Villalobos 79130	In Progress	Monthly - Santa Teresa HS Monthly Chiller Insp Refeto PM schedule details. 9/30/2011 12 Monthly - Santa Teresa HS A-16 Roof/Exh Semiannua	9/30/2011 22:34 AM		18	
Margret Villalobos 79018 Medium Work Prospero, Manuel Margret Villalobos 79129 Medium Work Nunez, Arturo Margret Villalobos 79130	In Progress	to PM schedule details. 9/30/2011 12 Monthly - Santa Teresa HS A-16 Roof/Exh Semiannua	9/30/2011 22:34 AM		18	
79018 Medium Work Prospero, Manuel Margret Villalobos 79129 Medium Work Nunez, Arturo Margret Villalobos 79130	In Progress	9/30/2011 12 Monthly - Santa Teresa HS A-16 Roof/Exh Semiannua	22:34 AM		18	
Medium Work Prospero, Manuel Margret Villalobos 79129 Medium Work Nunez, Arturo Margret Villalobos 79130	3	9/30/2011 12 Monthly - Santa Teresa HS A-16 Roof/Exh Semiannua	22:34 AM		18	<u>Φ</u> Ω ΩΩ
Prospero, Manuel Margret Villalobos 79129 Medium Work Nunez, Arturo Margret Villalobos 79130	3	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannua	-			\$0.00
Margret Villalobos 79129 Medium Work I Nunez, Arturo Margret Villalobos 79130	3		l -			
79129 Medium Work Nunez, Arturo Margret Villalobos 79130						
Medium Work Nunez, Arturo Margret Villalobos 79130		·	10/2/2011	10/23/2011	16	 \$0.00
Nunez, Arturo Margret Villalobos 79130	In Drograce	10/2/2011 12		10/20/2011	10	φσ.σσ
79130	III Flogiess	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.	20.51 AW			
	3					
Modium Work		•	10/2/2011	11/2/2011	16	\$0.00
Wedium Work	In Progress	10/2/2011 12	26:51 AM			
Nunez, Arturo		Yearly - Santa Teresa HS H-6 Rftop Furn Yearly - Refeto PM schedule details.	er			
Margret Villalobos	3		10/2/2011	10/18/2011	16	 \$0.00
79131	. 5			10/10/2011	10	φυ.υυ
Medium Work Nunez, Arturo	In Progress	10/2/2011 12 Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.	26:52 AM			
Margret Villalobos	5					
78155		Football Field	9/9/2011		39	\$0.00
Medium Work	In Progress	9/9/2011 3	56:27 PM			
Holguin, Alfredo		Running Track- needs the ruberized surface repaired a various places and lines repainted.	t			
Guadalupe Ontive	eros		7/4/2011	7/6/2011	106	 <u> </u>
74928			7/4/2011	7/6/2011	106	\$0.00
Medium Work	In Progress	7/4/2011 12	21:36 AM			
Nunez, Arturo		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) Refer to PM schedule details.	-			
Margret Villalobos 76055	3	-	7/31/2011	8/3/2011	79	 \$0.00
	In Progress	7/31/2011 9		0,0,2011		40.00
Nunez, Arturo	logiess	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) Refer to PM schedule details.				

10/18/2011 1:23:09 PM Page 138 of 172

Santa Ter	resa HS					
Ü						
Ü		9/4/2011	9/7/2011	44		\$0.00
	9/4/201	1 12:24:06 AM				
	Monthly - Santa Teresa HS - Emerg. Eyewash (M Refer to PM schedule details.	thly) -				
obos		10/2/2011	10/5/2011	16		\$0.00
ork In Progress	10/2/201	1 12:26:16 AM		10		Ψ0.00
onk iiri rogicos	Monthly - Santa Teresa HS - Emerg. Eyewash (M Refer to PM schedule details.					
obos		7/10/00/11	0/40/0044	100		
		7/10/2011	8/10/2011	100		\$0.00
ork In Progress	7/10/201	1 12:15:53 AM				
	Yearly - Santa Teresa HS A-11 Air Han Unit Year Refer to PM schedule details.	y -				
obos		10/14/2011		4		\$0.00
ork In Progress	10/14/20	11 8:50:30 AM				
lvador	SOMEBODY DROVE INTO FENCE AFTER SOC GAME ON 10-13-2011. REPORTED BY MR. GAR SECURITY AND REPORT TAKEN BY DASO DE RODRIGUEZ REPORT #2011-11009. NEEDS TO FIXED ASAP HAVING FOOTBALL GAME TONIG	RCIA PUTY) BE				
ero		8/5/2011		7/		\$0.00
-	9/5/201			74		φυ.υυ
J						
	need dead leaves and branches removed from se plants around main and surrounding buildings.	veral				
ariguez ain Building	Athletic Field	8/17/2011		62		\$0.00
ork In Progress	8/17/20	11 4:13:41 PM				
	also have grass and weeds that are at least 4 inch tall. Also need trash cans on field for players/coaches	nes				
driguez	dispose of used water bottles and cups					
	Athletic Field	9/22/2011		26		\$0.00
ork In Progress	9/22/20	11 8:13:34 AM				
	WE are requesting Bacterside to clean out pathage both football fields. G.H.S & S.T.H.S	ens on				
	ain Building ork In Progress Iriguez ain Building ork In Progress	Need dead leaves and branches removed from se plants around main and surrounding buildings. Iriguez ain Building Athletic Field Ork In Progress 8/17/20 Grass and weeds from area between fence and bleachers needs to be trimmed or removed. Other also have grass and weeds that are at least 4 inch tall. Also need trash cans on field for players/coaches dispose of used water bottles and cups Iriguez Athletic Field Ork In Progress 9/22/20 WE are requesting Bacterside to clean out pathag both football fields. G.H.S & S.T.H.S	Need dead leaves and branches removed from several plants around main and surrounding buildings. Iriguez ain Building Athletic Field 8/17/2011 Ork In Progress 8/17/2011 4:13:41 PM Grass and weeds from area between fence and bleachers needs to be trimmed or removed. Other areas also have grass and weeds that are at least 4 inches tall. Also need trash cans on field for players/coaches to dispose of used water bottles and cups Iriguez Athletic Field 9/22/2011 Ork In Progress 9/22/2011 8:13:34 AM WE are requesting Bacterside to clean out pathagens on both football fields. G.H.S & S.T.H.S	Athletic Field Also need trash cans on field for players/coaches to dispose of used water bottles and cups Athletic Field By/22/2011 By/22/2011	As an Building 8/5/2011 74 Ork In Progress 8/5/2011 12:53:10 PM Need dead leaves and branches removed from several plants around main and surrounding buildings. Irriguez Ain Building Athletic Field 8/17/2011 62 Ork In Progress 8/17/2011 4:13:41 PM Grass and weeds from area between fence and bleachers needs to be trimmed or removed. Other areas also have grass and weeds that are at least 4 inches tall. Also need trash cans on field for players/coaches to dispose of used water bottles and cups Irriguez Athletic Field 9/22/2011 26 Ork In Progress 9/22/2011 8:13:34 AM WE are requesting Bacterside to clean out pathagens on both football fields. G.H.S & S.T.H.S	Athletic Field 9/22/2011 8:13:34 AM WE are requesting Bacterside to clean out pathagens on both football fields. G.H.S & S.T.H.S

10/18/2011 1:23:09 PM Page 139 of 172

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2011 - 6/30/20′ Area Defer Area Number Reaso Description	red By Until		Target Comp Date Days Actual Comp Date Aged Action Taken	Labor Hours	Costs
Location:	Santa Te	resa HS					
75574		Athletic Field		7/20/2011	90		\$0.00
Medium	Work In Progress		7	7/20/2011 9:17:27 AM			
Holguin, A	fredo	Tennis Courts- need credone.	racks repaires and su	urfacing			
Alfredo Ho				0/04/0044	07		#0.00
78605	Concession			9/21/2011	27		\$0.00
High	Work In Progress		9	/21/2011 9:49:40 AM			
Nunez, Art		as per e-mail sent toda covers for the waterlin need to be insulated a sheetmetal covers will done asap	es that were installed nd secured better to t	. the lines the wall and	9/27 - Route to Art asp Mike	•	
Michael Mi 77090	unoz GYM (2009)	Dressing Room		8/17/2011	62		\$0.00
Medium	Work In Progress	ŭ	8	3/17/2011 4:11:16 PM			
Lara, Ralp	· ·	broken lockers need la purchase latches	tches installed, coacl	h will			
Rosalinda	Rodriguez			0/42/2044	25		<u></u>
78263				9/13/2011	35		\$0.00
Medium	Work In Progress			/13/2011 2:28:57 PM			
Lara, Ralp	n	NEED TO REPLACE I TO A HALF DOOR W		EAR LOBBY			
Arturo Nun		01		0/40/0044			<u>Фо</u> ос
78471	Main Building	Classroom	- 4	9/16/2011	32		\$0.00
Medium	Work In Progress		9/1	16/2011 11:15:48 PM			
Prospero,		Gloria Goodman need repaired. Also check A					
William Did 78645	ckson Main Building	Classroom		9/21/2011	27		\$0.00
Medium	Work In Progress		9)/21/2011 4:50:12 PM			,
Lara, Ralpi	•	Room 215 has some of properly. As a matter of keys broken off in a locand a couple more keys	loors and locks that n of fact there has been ck. They will need to g	not working a couple of			
William Die	ckson			40/40/0044			ФО О
79558				10/10/2011	8		\$0.00
Medium	Work In Progress			10/10/2011 11:15:19			
Carrasco,	Danny	I NEED SOME GASO RUANING ON EMPTY		ARIS AM			

10/18/2011 1:23:09 PM Page 140 of 172

Manuel Prospero

WOID	Building	Area Deferred By	Until Request Date Target Comp	AI	Labor
Priority	Status	Area Number Reason	Created Date/Time Actual Comp	Date Aged	Hours
Assigned	То	Description	Action T	aken	
Requeste	r Name				
Location:	Santa Te	resa HS			
78364			9/14/2011	34	\$0.00
Medium	Work In Progress		9/14/2011 6:16:41 PM		
Gonzalez,		Bench inside the showers in gym both boy and girls they've been rip			
Jorge Pere 78850	ez	Classroom	9/27/2011	21	\$0.00
	Work In Drogram	MR.		21	ψ0.00
Medium -	Work In Progress		9/27/2011 1:24:13 PM		
Prospero,	Manuel	MOUNT PROJECTOR TO CEILIN	NG.		
Marylou Ji 79039	imenez Gymnasium	Dressing Room	9/30/2011	18	\$0.00
	•	Diessing Room	9/30/2011 1:14:44 PM	10	ψ0.00
Medium Prospero,	Work In Progress Manuel	Need to replace Delaney flushvalv dressing rooms, asp per David, Zu flushvalves should be installed	ves throughout		
Manuel Pr	rospero		7/00/0044		Ф0.00
75589			7/20/2011	90	\$0.00
Medium	Work In Progress		7/20/2011 3:07:28 PM		
Orozco, D	anny	the Molino is broken and one of th SNP Manager Olga B. 589.5332	ne ovens is not heating.		
Maritza Go	onzalez	Cofeteria	0/16/2011	32	\$0.00
78437	W 11 B	Cafeteria	9/16/2011	32	\$0.00
Medium Moncayo,	Work In Progress Fernando	MILK COOLER TO THE ITALIAN WORK.	9/16/2011 3:25:06 PM LINE DOES NOT		
		OLGA B. SNP MGR 589-5332			
Jacqueline 79602	e Aguilar		10/11/2011	7	\$0.00
Medium	Work In Progress		10/11/2011 7:53:26 AM	•	V OIOX
Orozco, D	_	ICE MACHINE IS NOT MAKING I OLGA B. 589.5332			
Maritza Go					
76874	Main Building	Classroom	8/12/2011	67	\$0.00
Medium	Work In Progress		8/12/2011 9:52:08 AM		
Lara, Ralp	bh	Door in counseling center is off batto open and close	alance and very difficult		
Rosalinda	Rodriguez				

10/18/2011 1:23:09 PM Page 141 of 172

Total

1200 - Work Orders In Progress (Fiscal Year)

Priority Status Area Number Reason Created Date/Time Actual Comp Date Action Taken 49d Mority Assigned To Requester Name Action Taken 49d Mority Requester Santa Teresa HS 45/2011 12:51:46 PM 76517 Library Library 8/5/2011 12:51:46 PM Nunez, Arturo Need big screen TV mounted in library, see librarian for location 48/11/2011 68 Rosalinda Podriquez 8/11/2011 3:38:38 PM 68 48/11/2011 68 Medium Work In Progress 8/11/2011 3:38:38 PM 7 8/11/2011 67 Nunez, Arturo Room 501 has leak that has caused ceiling tiles to saturate and fall. 8/12/2011 67 Rosalinda Podriguez Rodium Work In Progress 8/12/2011 10:07:05 AM 8/12/2011 67 Rosalinda Podriguez Roed Drill Press and Band Saw moved to main floor from 2nd floor in shop 805 8/16/2011 63 63 Rosalinda Podriguez Rosalinda Podriguez Rosalinda Rodriguez 8/16/2011 2:28:54 PM 7 Rosalinda Rodriguez Rosalinda Rodriguez Rosalinda Rodriguez	pe	∍qu	ues	st Da	ate	Target	Com	р Da		Days		bor	Cos	sts
Requester Name Location: Santa Teresa HS 76517 Library Library 8/5/2011 12:51:46 PM Medium Work In Progress 8/5/2011 12:51:46 PM Nunez, Arturo Need big screen TV mounted in library, see librarian for location Rosalinda Rodriguez Rosalinda Rodriguez 76845 Main Building Classroom 8/11/2011 3:38:38 PM Nunez, Arturo Room 501 has leak that has caused ceiling tiles to saturate and fall. 8/12/2011 67 Rosalinda Rodriguez Rosalinda Rodriguez 8/12/2011 10:07:05 AM 67 Medium Work In Progress 8/12/2011 10:07:05 AM 67 Nunez, Arturo Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805 8/16/2011 2:28:54 PM Nunez, Arturo Rosalinda Rodriguez Rosalinda Rodriguez Rosalinda Rodriguez Rosalinda Rodriguez Rosalinda Rodriguez	1 E	l Da	ate	:/Tim	ne	Actual	Com	p Da	te	Aged	Но	urs		
Location: Santa Teresa HS 76517 Library Library 8/5/2011 74 Medium Work In Progress 8/5/2011 12:51:46 PM Nunez, Arturo Need big screen TV mounted in library, see librarian for location 68 Rosalinda Rodriguez 76845 Main Building Classroom 8/11/2011 68 Medium Work In Progress Room 501 has leak that has caused ceiling tiles to saturate and fall. 8/12/2011 67 Rosalinda Rodriguez Rosmot Sol has leak that has caused ceiling tiles to saturate and fall. 8/12/2011 67 Rosalinda Rodriguez Rosmot Sol has leak that has caused ceiling tiles to saturate and fall. 67 67 Rosalinda Rodriguez Nunez, Arturo Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805 8/12/2011 63 Rosalinda Rodriguez Rosmot Sol In Calssroom 8/16/2011 63 Medium Work In Progress 8/16/2011 63 Rosalinda Rodriguez Rosmot Sol In calainet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removed 67 Rosalinda Rodriguez <t< th=""><th></th><th></th><th></th><th></th><th></th><th>Ac</th><th>tion</th><th>Take</th><th>n</th><th></th><th></th><th></th><th></th><th></th></t<>						Ac	tion	Take	n					
Test														
Medium Work In Progress 8/5/2011 12:51:46 PM Nunez, Arturo Need big screen TV mounted in library, see librarian for location Rosalinda Rodriguez 76845 Main Building Classroom 8/11/2011 3:38:38 PM Medium Work In Progress 8/11/2011 3:38:38 PM Nunez, Arturo Room 501 has leak that has caused ceiling tiles to saturate and fall. Rosalinda Rodriguez 76877 Vocational Classroom 8/12/2011 0:07:05 AM Nunez, Arturo Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805 8/16/2011 2:28:54 PM Nunez, Arturo Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805 8/16/2011 2:28:54 PM Nunez, Arturo Room 511 cabinet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removed Rosalinda Rodriguez 76902 Main Building Classroom 8/12/2011 67 Medium Work In Progress 8/12/2011 4:35:35 PM Nunez, Arturo Ceiling in room 505 is leaking. Not sure if source is roof or AC Rosalinda Rodriguez 78012 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Ple														
Nunez, Arturo Need big screen TV mounted in library, see librarian for location			8/	5/20	11					74			\$0	.00
location	12	12:	:51	:46	PΜ	1								
Medium Work In Progress Room 501 has leak that has caused ceiling tiles to saturate and fall. Rosalinda Rodriguez 76877 Vocational Classroom 8/12/2011 0:07:05 AM Medium Work In Progress Rosalinda Rodriguez 77008 Main Building Classroom 8/12/2011 0:07:05 AM Nunez, Arturo Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805 Rosalinda Rodriguez 77008 Main Building Classroom 8/16/2011 2:28:54 PM Nunez, Arturo Room 511 cabinet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removed Rosalinda Rodriguez 76902 Main Building Classroom 8/12/2011 67 Medium Work In Progress Rosalinda Rodriguez 76902 Main Building Classroom 8/12/2011 67 Medium Work In Progress Rosalinda Rodriguez 76902 Main Building Classroom 8/12/2011 67 Medium Work In Progress Rosalinda Rodriguez 78902 Main Building Classroom 8/12/2011 39 Medium Work In Progress Rosalinda Rodriguez 78116 9/9/2011 39 Medium Work In Progress Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26	n f	ı foı	or											
Nunez, Arturo Room 501 has leak that has caused ceiling tiles to saturate and fall. Rosalinda Rodriguez 76877 Vocational Classroom 8/12/2011 10:07:05 AM Medium Work In Progress 8/12/2011 10:07:05 AM Nunez, Arturo Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805 Rosalinda Rodriguez 77008 Main Building Classroom 8/16/2011 2:28:54 PM Nunez, Arturo Room 511 cabinet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removed Rosalinda Rodriguez 76902 Main Building Classroom 8/12/2011 67 Medium Work In Progress 8/12/2011 4:35:35 PM Nunez, Arturo Ceiling in room 505 is leaking. Not sure if source is roof or AC Rosalinda Rodriguez 78116 9/9/2011 39 Medium Work In Progress 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26		8	8/1	1/20)11					68			\$0	.00
Rosalinda Rodriguez 76877 Vocational Classroom 8/12/2011 10:07:05 AM Medium Work In Progress 8/12/2011 10:07:05 AM Nunez, Arturo Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805 Rosalinda Rodriguez 77008 Main Building Classroom 8/16/2011 2:28:54 PM Nunez, Arturo Room 511 cabinet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removed Rosalinda Rodriguez 76902 Main Building Classroom 8/12/2011 4:35:35 PM Nunez, Arturo Room 505 is leaking. Not sure if source is roof or AC Rosalinda Rodriguez 78116 9/9/2011 1:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26	1 3	1 3:	:38	:38	PΝ	1								
76877 Vocational Classroom 8/12/2011 67 Medium Work In Progress 8/12/2011 10:07:05 AM Nunez, Arturo Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805 Rosalinda Rodriguez 77008 Main Building Classroom 8/16/2011 2:28:54 PM Nunez, Arturo Room 511 cabinet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removed Rosalinda Rodriguez Rosalinda Rodriguez 76902 Main Building Classroom 8/12/2011 4:35:35 PM Nunez, Arturo Ceiling in room 505 is leaking. Not sure if source is roof or AC Rosalinda Rodriguez 9/9/2011 39 78116 9/9/2011 39 Medium Work In Progress 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin Rolling Building Classroom 9/22/2011 26														
Medium Work In Progress 8/12/2011 10:07:05 AM Nunez, Arturo Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805 Rosalinda Rodriguez 77008 Main Building Classroom 8/16/2011 63 Medium Work In Progress 8/16/2011 2:28:54 PM Nunez, Arturo Room 511 cabinet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removed Rosalinda Rodriguez 76902 Main Building Classroom 8/12/2011 67 Medium Work In Progress 8/12/2011 4:35:35 PM Nunez, Arturo Ceiling in room 505 is leaking. Not sure if source is roof or AC Rosalinda Rodriguez 78116 9/9/2011 39 Medium Work In Progress 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26			0/1	2/20	111					67			\$0	00
Nunez, Arturo Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805 Rosalinda Rodriguez										67			ΦU	.00
From 2nd floor in shop 805 Rosalinda Rodriguez 77008 Main Building Classroom 8/16/2011 63 Medium Work In Progress 8/16/2011 2:28:54 PM Nunez, Arturo Room 511 cabinet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removed Rosalinda Rodriguez 76902 Main Building Classroom 8/12/2011 67 Medium Work In Progress 8/12/2011 4:35:35 PM Nunez, Arturo Ceiling in room 505 is leaking. Not sure if source is roof or AC Rosalinda Rodriguez 78116 9/9/2011 39 Medium Work In Progress 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26	10	10:0	:07	:05 /	ΑM	l								
77008Main BuildingClassroom8/16/201163MediumWork In Progress8/16/2011 2:28:54 PMNunez, ArturoRoom 511 cabinet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removedRosalinda Rodriguez76902Main BuildingClassroom8/12/201167MediumWork In Progress8/12/2011 4:35:35 PMNunez, ArturoCeiling in room 505 is leaking. Not sure if source is roof or ACRosalinda Rodriguez9/9/201139MediumWork In Progress9/9/2011 11:25:30 AMProspero, ManuelParking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop SignAlfredo HolquinAlfredo HolquinClassroom9/22/201126	r	Γ												
Medium Work In Progress 8/16/2011 2:28:54 PM Nunez, Arturo Room 511 cabinet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removed Rosalinda Rodriguez 76902 Main Building Classroom 8/12/2011 67 Medium Work In Progress 8/12/2011 4:35:35 PM Nunez, Arturo Ceiling in room 505 is leaking. Not sure if source is roof or AC Rosalinda Rodriguez 9/9/2011 39 Medium Work In Progress 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin Alfredo Holguin 9/22/2011 26			0/4	<u>C/20</u>	44					60				
Nunez, Arturo Room 511 cabinet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removed Rosalinda Rodriguez 76902 Main Building Classroom 8/12/2011 67 Medium Work In Progress 8/12/2011 4:35:35 PM Nunez, Arturo Ceiling in room 505 is leaking. Not sure if source is roof or AC Rosalinda Rodriguez 78116 9/9/2011 39 Medium Work In Progress 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26		8	8/1	6/20	111					63			\$0	.00
has handles needs screws Lab table doors stick and graffitti needs to be removed Rosalinda Rodriguez 76902 Main Building Classroom 8/12/2011 67 Medium Work In Progress 8/12/2011 4:35:35 PM Nunez, Arturo Ceiling in room 505 is leaking. Not sure if source is roof or AC Rosalinda Rodriguez 78116 9/9/2011 39 Medium Work In Progress 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26	1 2	1 2:	:28	:54	PΝ	1								
76902Main BuildingClassroom8/12/201167MediumWork In Progress8/12/2011 4:35:35 PMNunez, ArturoCeiling in room 505 is leaking. Not sure if source is roof or ACRosalinda Rodriguez														
Medium Work In Progress 8/12/2011 4:35:35 PM Nunez, Arturo Ceiling in room 505 is leaking. Not sure if source is roof or AC Rosalinda Rodriguez 78116 9/9/2011 39 Medium Work In Progress 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26				- /									•	
Nunez, Arturo Ceiling in room 505 is leaking. Not sure if source is roof or AC Rosalinda Rodriguez 78116 9/9/2011 39 Medium Work In Progress 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom Oceiling in room 505 is leaking. Not sure if source is roof or AC 9/9/2011 39 Alfredo Holguin 78692 Main Building Classroom Oceiling in room 505 is leaking. Not sure if source is roof or AC 9/9/2011 39 9/9/2011 26		8	8/1	2/20	11					67			\$0	.00
r AC Rosalinda Rodriguez 78116 9/9/2011 39 Medium Work In Progress 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26	1 4	1 4:	:35	:35	PΝ	1								
78116 9/9/2011 39 Medium Work In Progress 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26	rc	roo	of											
Medium Work In Progress 9/9/2011 11:25:30 AM Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26														
Prospero, Manuel Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26			9/	9/20)11					39			\$0	.00
intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign Alfredo Holguin 78692 Main Building Classroom 9/22/2011 26	11	11:	:25	:30	ΑM	l								
78692 Main Building Classroom 9/22/2011 26														
			0/0	2/20	111					20			ው ለ	00
Medium Work In Progress 9/22/2011 3:40:50 PM										26			\$0.	.00
	13	1 3:4	:40	:50	PΝ	1								
Nunez, Arturo Cheif Trejo is have water accumalate on the floor from the ceiling. He has a leak in the ceiling. Could we check this out.														
William Dickson														

10/18/2011 1:23:09 PM Page 142 of 172

Selected Da WOID Priority Assigned Requester	Building Status To	Area Number Reason Description	Until Request Date Ta Created Date/Time Ac	A	Costs
Location:	Santa Te	resa HS			
78694	Main Building	Classroom	9/22/2011	26	\$0.00
Medium	Work In Progress		9/22/2011 3:44:13 PM		
Prospero,	Manuel	There are several problems in roc leaking, 2. air conditioner quit wo wanted to get it checked out.			
William Did	ckson		10/3/2011	15	\$0.00
Medium	Work In Progress		10/3/2011 3:49:35 PM		ψ0.00
Flores, Pet	-	NEED TO HAVE POLARIS SEVE HAS 34 HOURS, DUE FOR A SE	ICED , IT ALREADY		
Manuel Pro	ospero		7/14/2011	96	\$0.00
Medium	Work In Progress		7/14/2011 1:12:03 PM	90	ψ0.00
	-	Need to fix look in algorithm	7/14/2011 1.12.03 FW		
Mijarez, Ja		Need to fix leak in classroom.			
Michael Mi 75598	unoz		7/20/2011	90	\$0.00
Medium	Work In Progress		7/20/2011 3:42:06 PM		
Nunez, Art	uro	NEED TO UNCLOGG MOP SINK	IN NEW GYM.		
Arturo Nun	ez				
76447			8/4/2011	75	\$0.00
Medium	Work In Progress		8/4/2011 3:22:48 PM		
Nunez, Art		Please mount chalk board remove in Drama classroom located behind			
Rosalinda 79846	Rodriguez		10/17/2011	1	\$0.00
Medium	Work In Progress		10/17/2011 12:46:05		
Lara, Ralpl	_	need to replace broken cilinder in	a gym door		
Jorge Pere					
79847			10/17/2011	1	\$0.00
Medium	Work In Progress		10/17/2011 12:47:18		
Lara, Ralp	า	Need to replace a cilinder in girls	locker room door		
Jorge Pere	z		40/47/0044		Ф0.00
79848			10/17/2011	1	\$0.00
Medium	Work In Progress		10/17/2011 12:49:26		
Lara, Ralp	า	Replace broken cilinder for Mr. Po	ortillos class room		

10/18/2011 1:23:09 PM Page 143 of 172

Selected Da WOID	ate Range for Request Building	Dates:7/1/2011 - 6/30/2012 Order By L Area Deferred By	ocation, Status Until Request Date Target Comp Da	ate Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time Actual Comp Da	AI	Hours	
Assigned	То	Description	Action Take	en		
Requeste	r Name					
Location:	Santa Te	resa HS				
79852			10/17/2011	1		\$0.00
Medium	Work In Progress		10/17/2011 2:02:32 PM			
Lara, Ralp	bh	Having trouble opening a custodia loose replace handle or cilinder ple				
<u>Jorge Per</u> 76836	ez Vocational	Classroom	8/11/2011	68		\$0.00
Medium	Work In Progress	Oldooroom	8/11/2011 3:13:22 PM	00		ψ0.00
	_	Mandahan wa 005 has reaffeeld	0/11/2011 3.13.22 1 W			
Nunez, Ar		Wood shop rm 805 has roof leak				
<u>Rosalinda</u> 78553	Rodriguez		9/20/2011	28		\$0.00
Medium	Work In Progress		9/20/2011 2:15:26 PM			
Prospero,	_	Ms. Rogers has a leaky roof, air co	onditioner not working.			
William Di			3 ,			
78646	Vocational	Classroom	9/21/2011	27		\$0.00
Medium	Work In Progress		9/21/2011 5:07:40 PM			
Lara, Ralp		Need four keys one for the gates a 801 and 807.	and a couple for rooms			
<u>William Di</u> 78708	ickson Main Building		9/22/2011	26		\$0.00
Medium	Work In Progress		9/22/2011 3:59:04 PM			·
Lara, Ralp	_	We need 2-MA 50 extra keys for ro				
William Di		TO HOOK E WILL OF OMIC NOTO TO	33.11 002.			
78780	ICKSOII		9/26/2011	22		\$0.00
Medium	Work In Progress		9/26/2011 12:29:42 PM			
Lara, Ralp	bh	NEED SOME ASSISTANCE ON C CULINARY KITCHEN, DOOR IS F OPEN, AFRAID TO BREAK KEY.	PRETTY HARD TO			
Arturo Nur 78962	nez		9/29/2011	19		\$0.00
Medium	Work In Progress		9/29/2011 7:55:54 AM	13		ψυ.υυ
Lara, Ralp	_	NEED TO HAVE FIVE (5) KEYS I SECURITY OFFICE				
Arturo Nur	nez					
79427			10/5/2011	13		\$0.00
Medium	Work In Progress		10/5/2011 3:14:14 PM			
Lara, Ralp		Requesting keys for new employer for school doors and custodial room				
Jorge Per	ez	TOT SCHOOL GOOTS AND CUSTOGIAL TOOL	TIS. Master and M. 113			

10/18/2011 1:23:09 PM Page 144 of 172

NOID Priority Assigned Requester		Area Deferred By U Area Number Reason Description	Jntil Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
ocation:	Santa Te	resa HS					
79678			10/12/2011		6		\$0.00
High	Work In Progress		10/12/2011 9:05:07 AM				
₋ara, Ralp	h	need new pad lock for storage.					
	Ontiveros		0/00/0044				
78559	Vocational		9/20/2011		28		\$0.00
Medium	Work In Progress		9/20/2011 2:49:05 PM				
Castillo, Ca	arlos	LIGHTS ON BLDG NEED TO BE CHE	CKED				
Manuel Pro 78557	ospero GYM (2009)		9/20/2011		28		\$0.00
Medium	Work In Progress		9/20/2011 2:46:59 PM		20		φυ.σσ
Castillo, Ca	-	SOME LIGHTS IN FRONT NOT ON, A #4 BURNED OUT					
Manuel Pro			0/00/0044		00		#0.00
78558	Gymnasium		9/20/2011		28		\$0.00
Medium	Work In Progress		9/20/2011 2:48:04 PM				
Castillo, Ca		MOST LIGHTS BURNED OUT, NEED BULB OR BALLAST	REPLACING				
Manuel Pro 76017	ospero		7/29/2011		81		\$0.00
Medium	Work In Progress	MRS.	7/29/2011 2:01:47 PM				
Nunez, Art	uro	URGENT! MAINTENANCE DOORS N PAINTED BEFORE 1ST DAY OF SCH AND INNER DOORS.	=				
Marylou Jii 77089	menez GYM (2009)	Dressing Room	8/17/2011		62		\$0.00
Medium	Work In Progress	Diessing Room	8/17/2011 4:10:08 PM		02		ψ0.00
	-						
_ozoya, M	anny	Lock for outside door of the football loc not work	ker room does				
	Rodriguez		0/22/2011		F.C.		ФО ОО
77299	W 11 D		8/23/2011		56		\$0.00
Medium	Work In Progress		8/23/2011 3:52:36 PM				
₋ara, Ralp	h	CYLINDERS ON OLD D.O.L. PORTA BE CHANGED TEACHER HAVING A OPENING .					
Arturo Nur	nez		9/1/2011		47		\$0.00
77686	Work in Drosses				41		φυ.υυ
Medium	Work In Progress		9/1/2011 8:07:21 AM				
Castillo, Ca	arlos	NEED A LIGHT FIXTURE FOR 1.S.S	S. KEST ROOM.				

10/18/2011 1:23:09 PM Page 145 of 172

WOID	Building	Area Deferred By	•		Days Labor Aged Hours	Costs
Priority	Status -	Area Number Reason	Created Date/Time /	Actual Comp Bate	aged Hours	
Assigned '		Description		Action Taken		
Requester	Name					
Location:	Santa Te	resa HS				
78353			9/14/2011		34	\$0.00
Medium	Work In Progress		9/14/2011 3:43:21 PM			
Castillo, Ca	arlos	NEED SOME ASSITANCE ON T PROBLEM WITH HAND DRIER RESTROOM IN CONSESSION	S IN BOYS			
Arturo Nur	nez					
78367			9/14/2011		34	\$0.00
Medium	Work In Progress		9/14/2011 6:24:35 PM			
Castillo, Ca	arlos	hand dryers need to be fixed in I outside concession stand	ocker rooms and in			
Jorge Pere			0/20/2044		20	<u>Фо</u> оо
78554	Vocational		9/20/2011		28	\$0.00
Medium	Work In Progress		9/20/2011 2:42:16 PM			
Castillo, Ca	arlos	fIVE OUT OF SIX LIGHT POLES LIGHT BULBS	S OUT, NEED NEW			
Manuel Pro		Cofetavia	0/20/2044		20	<u>Фо</u> оо
78555	Cafeteria (2005)	Cafeteria	9/20/2011		28	\$0.00
Medium	Work In Progress		9/20/2011 2:43:41 PM			
Castillo, Ca	arlos	TIMER NOT WORKING, NEEDS	S TO BE REPLACED			
Manuel Pro						
78556	Applied Science		9/20/2011		28	\$0.00
Medium	Work In Progress		9/20/2011 2:45:27 PM			
Castillo, Ca	arlos	MOST LIGHTS BEHIND SCINC NEW BULBS OR BALLAST	E WING OUT, NEED			
Manuel Pro	ospero 4 Work Orders	Avg. Age of WO's		tal for Santa Teresa		\$0.00

10/18/2011 1:23:09 PM Page 146 of 172

Selected Da WOID Priority Assigned Requester	Building Status To	Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS					
75618	Gym (1997)	Restroom (Boys)	7/21/2011		89		\$0.00
Medium	Work In Progress		7/21/2011 7:11:51 AM				
Villalobos,	David	Two urinals are leaking water ever the floor get puddles of water and s for theplumber to fix them before st	smells bad i would like				
Ismael Ro		Destruction (Circle)	0/45/0044		00		#0.00
78393	Gym (1997)	Restroom (Girls)	9/15/2011		33		\$0.00
Medium	Work In Progress	SNYDER	9/15/2011 2:34:40 PM				
Villalobos,	David	RESTROOMS LEAKING FROM BO	OTTOM SEAL.				
Laura Parr	a						
78511			9/19/2011		29		\$0.00
Medium	Work In Progress		9/19/2011 3:35:42 PM				
Villalobos,	David	N.bldg, S.bldg, and Gym. I need he urinals that are leaking from the ba toilets that are leaking from wax rin of rusted toilet bolts, also several fl new plumbing parts. David might n the materials if we don't heave ther	ck seal, several g and loose because ush valves that need eed to order some of				
Jaime Mija	rez		0/40/0044		0.5		# 0.00
78246			9/13/2011		35		\$0.00
Medium	Work In Progress		9/13/2011 9:25:38 AM				
Castillo, Ca	arlos	Football field. Mrs. Lovelace is requout in the field for athletic events. Fused for P.A sytem,outdoor snack sthings.	Power source will be				
Jaime Mija	irez		9/26/2011		22		\$0.00
78756					22		φυ.υυ
Medium	Work In Progress		9/26/2011 8:59:26 AM				
Castillo, Castil	arlos	Timer to north bldg exterior lights a working properly. Every day I have are either on or off at the wrong tim might need to be replaced. Staff the in the morning have to use flash lig being on.	to adjust and lights ne. Timer is old and at come to work early				
Jaime Mija	ırez	-					
75770			7/25/2011		85		\$0.00
Medium	Work In Progress		7/25/2011 9:37:48 AM				
Lara, Ralp	h	Metal portable room 3-a, 3-a doors please check with principal Montan dead bolt locks on both room entra Mrs. Lovelace portable rooms will be music and they will be having experinstruments. A.S.A.P	o to see if they want nce doors. As per oe used for Orchestra				

10/18/2011 1:23:09 PM Page 147 of 172

Jaime Mijarez

WOID Priority Assigned ⁻ Requester		Area Number Reason Description	By Until Request Date Ta Created Date/Time Ac	-	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS					
78245			9/13/2011		35		\$0.00
Medium	Work In Progress		9/13/2011 9:07:07 AM				
Munoz, Mid	chael	North Bldg side walk going causing the slab to shift, cr does look like a trip hazard	ack and lift. I inspected and it				
<u>Jaime Mija</u> 75542	rez North Building	Hallway/Corridor	7/19/2011		91		\$0.00
	_	i laliway/Comuoi			91		ψ0.00
Medium	Work In Progress	Labby tile needs to be real	7/19/2011 12:54:49 PM				
Estrada, Je		Lobby tile needs to be repla	aced north building.				
Jesus Estra 76423	ada		8/4/2011		75		\$0.00
Medium	Work In Progress		8/4/2011 9:10:56 AM				
Mijarez, Ja	ime		ical room heat pump is not s in heating mode. I already on tracer summit and it looks				
Jaime Mija			0/00/0044				**
78658	North Building		9/22/2011		26		\$0.00
High	Work In Progress		9/22/2011 8:42:12 AM				
Villalobos,	David	as per our conversation, pl cleanout, this will require c and installing material.than					
Michael Mu	ınoz		8/5/2011		74		\$0.00
76499	Madala Dasans				74		Φ0.00
Medium	Work In Progress		8/5/2011 10:27:29 AM				
Gonzalez,	Salvador	as per ourconversation, ple poles that are to be installe	ease order material for light ed.thank you				
		(concrete)					
Michael Mu 79298	ınoz		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:29 AM	10/20/2011	10		ψ0.00
Orozco, Da	-	Monthly - Santa Teresa MS					
010200, De	шпу	Refer to PM schedule deta					
Margret Vil	lalobos		0/00/0044		00		#0.00
78670			9/22/2011		26		\$0.00
High	Work In Progress		9/22/2011 12:32:04 PM				
Mijarez, Ja	ime	fire lines are in need of pair and paint curbs red to inclu curbs.thank you					

10/18/2011 1:23:09 PM Page 148 of 172

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS					
76697			8/9/2011		70		\$0.00
Medium	Work In Progress		8/9/2011 11:12:30 AM	I			
Orozco, Da	anny	1) DRAIN IS CLOGGED. 2) SPRA DISHWASHER LEAKS. 3) NEW O HEATING UP AT ALL. SNP MANA 589.9836	OVEN IS NOT				
Maritza Go 79813	onzalez		10/17/2011		1		\$0.00
Medium	Work In Progress	SPED OFFICE	10/17/2011 10:09:59)	·		ψ0.00
Briones, E	_	PO #101108760 PICK UP ON BOX DELIVER TO LUIS MERAZ-TEACHER-STMS	10/11/2011 10:00:00				
Margaret \	<u>/illalobos</u> Gym (1997)	Gym	9/21/2011		27		\$0.00
Medium	Work In Progress	<i>- - - - - - - - - -</i>	9/21/2011 9:17:58 AM	1			ψ0.00
Holguin, A	· ·	Volley Ball Court Lines need to r color (brown) is hard for officials to	epaint black. Current	•			
Rose Love		Office	0/05/0044		<i></i>		<u>Фо оо</u>
77391	North Building	Office	8/25/2011		54		\$0.00
Medium	Work In Progress		8/25/2011 9:39:58 AN	1			
Ronquillo,	Ruben	North Bldg office. Windows that ru and the exterior entrance doors not be Tinted. The sun rays are cau to much problems with the heat pu and not satisfying. Please contact and principal to decide on darkness There are a Total of 8 windows and	ext to the office need sing to much heat and imp always running building mechanic is of Window Tint.				
Jaime Mija 77876	arez		9/4/2011		44		\$0.00
	Mork In Drogram			1	44		φυ.υυ
Medium	Work In Progress	M 41 0 1 T MO 014	9/4/2011 12:24:30 AN	I			
Mijarez, Ja	aime	Monthly - Santa Teresa MS -Cloth Refer to PM schedule details.	es Dryer (Monthly) -				
Margret Vi	llalobos		10/2/2011	10/10/2011	16		<u>\$0.00</u>
79208 Medium	Work In Progress		10/2/2011 10/2/2011 12:27:37 AM	10/10/2011	10		\$0.00
	· ·	Monthly Conta Tara - MO C		ı			
Mijarez, Ja		Monthly - Santa Teresa MS Emer Refer to PM schedule details.	Lignt Test: Monthly -				
Margret Vi 79209	llalobos		10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:38 AM		10		ψυ.υυ
Mijarez, Ja	•	Monthly - Santa Teresa MS Bleach to PM schedule details.		l			
Margret Vi	llalobos	to i ivi soliedule detalis.					
40/40/004	1 1·23·09 PM						10 of 172

10/18/2011 1:23:09 PM Page 149 of 172

Oriority	Status	Area Number Reason Created Date/Time A	Aged			
Priority Assigned ⁻		Description Created Date/Time A	Action Taken		Hours	
Requester		Description	Action Taken			
Location:	Santa Te	resa MS				
79205		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:35 AM		-		*
Mijarez, Ja	-	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vil	lalobos	10/2/2011		16		\$0.00
79178 Medium	Work In Progress	10/2/2011 12:27:19 AM		10		φυ.υυ
	Work In Progress					
Mijarez, Ja		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.				
<u>Margret Vil</u> 79278	Ialobos	10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:28:18 AM				
Mijarez, Ja	ime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.				
<u>Margret Vil</u> 78903	lalobos North Building	9/28/2011		20		\$0.00
Medium	Work In Progress	9/28/2011 9:08:18 AM		20		ψ0.00
Aldaz, Bob	· ·	please remove conctrete that was cut and dug-out and dispose of. thank you				
<u>Michael Μι</u> 79014	unoz	9/30/2011		18		\$0.00
Medium	Work In Progress	9/30/2011 12:22:32 AM		10		ψ0.00
Mijarez, Ja	-	Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.				
Margret Vil	lalobos	10/2/2011	11/2/2011	16		\$0.00
79104	Work In Drogross	10/2/2011	11/2/2011	10		φυ.υυ
Medium Mijarez, Ja	Work In Progress	10/2/2011 12:26:38 AM Yearly - Santa Teresa MS U2 (Heat Gas)(Yearly) - Refer to PM schedule details.				
Margret Vil	lalobos	to Pivi scriedule details.				
79105	indicated in the second in the	10/2/2011	10/18/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:38 AM				
Mijarez, Ja	ime	Monthly - Santa Teresa MS A1(Wall Refr.E/H)(Semi) - Refer to PM schedule details.				
Margret Vil 79520	lalobos	10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:35 AM	. 0, 20, 20 1 1	Ü		ψ0.00
Rodriguez,	· ·	Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PM schedule details.				
Margret Vil	lalobos	to 1 M Soffedure details.				

10/18/2011 1:23:09 PM Page 150 of 172

WOID Priority Assigned Requester		Area Area Number Description	Deferred By Reason	Until Request Date T Created Date/Time A	arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS						
79166				10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress			10/2/2011 12:27:11 AM				
Mijarez, Ja	aime	Monthly - Santa PM schedule d	a Teresa MS Roof Ins etails.	spection - Refer to				
Margret Vi 78815	llalobos			9/27/2011		21		\$0.00
Medium	Work In Progress			9/27/2011 7:54:15 AM				
Carrasco,	Danny	Need gas for P	olariz Ranger vehicle).				
Jaime Mija	arez			9/5/2011		7.1		PO 00
76500				8/5/2011		74		\$0.00
Medium	Work In Progress			8/5/2011 10:29:52 AM				
	Guadalupe		ith an operator for di es for electrical powe	tchwitch to excavate r.thank you				
Michael M 78278	unoz	Gym		9/13/2011		35		\$0.00
Medium	Work In Progress	Cy		9/13/2011 3:50:39 PM		00		ψ0.00
Valles, Joh	· ·		nd replace hot box fo st side of gym.thank	r irrigation back flow				
Michael M	unoz			0/40/0044				Φο οο
78280				9/13/2011		35		\$0.00
Medium	Work In Progress			9/13/2011 3:52:24 PM				
Valles, Joh	nnny		eds around all buildir e need be. also arour					
Michael M 78284	unoz	Athletic Field		9/13/2011		35		\$0.00
Medium	Work In Progress	AUTIONS FIEID		9/13/2011 4:03:07 PM		30		ψυ.υυ
	· ·	mlaaaa	aada aad					
Valles, Joh	nny	fence line and		emical along football				
Michael M 78329	unoz North Building	Athletic Field		9/14/2011		34		\$0.00
Medium	Work In Progress			9/14/2011 11:21:55 AM				
Valles, Joh	_		ter snakes are hiding	around the atheletic in them as per				
Ismael Ro	driguez							

10/18/2011 1:23:09 PM Page 151 of 172

WOID Priority Assigned [:] Requester		Area Deferred By Area Number Reason Description	Until Request Date T Created Date/Time A	· .	ays Labor led Hours	
Location:	Santa Te	resa MS				
79361			10/4/2011	1	4	\$0.00
Medium	Work In Progress		10/4/2011 9:24:16 AM			
Gonzalez,	Salvador	Need for welder to fabricate 4 mullians for cafeteria doors an				
Jaime Mija						
79607	South Building	Parking Lot	10/11/2011		7	\$0.00
Medium	Work In Progress	SOUTH FENCE	10/11/2011 8:25:10 AM			
Gonzalez,		FENCE NEEDS TO BE REPA AND IS BEING HELD TOGET				
Laura Parr 79691	a Library	Library	10/12/2011		6	\$0.00
Medium	Work In Progress	CRISTINE RUIZ	10/12/2011 12:32:10			
Lara, Ralpl		3RD REQUEST BACK DOO! NOT CLOSE OR LOCK. HING TILE INSTALLERS BACK IN J	E WAS BROKEN BY			
Laura Parr 79849	a North Building	Office	10/17/2011		1	\$0.00
Medium	Work In Progress	MAIN DOORS	10/17/2011 12:53:09			
Lara, Ralpl	1	DOOR NEED TO BE HANDIC DOORS AND DOORS THAT L PARKING LOT.				
Laura Parr 79400	a North Building	Custodial	10/5/2011	1	3	\$0.00
Medium	Work In Progress		10/5/2011 6:55:06 AM	·		ψ0.00
Carbajal, J	· ·	Jimmey, i have a burnisher that the handle the serial #110	it has electrical short in			
Ismael Roo	driguez					
78907			9/28/2011	2	20	\$0.00
Medium	Work In Progress		9/28/2011 10:20:54 AM			
Munoz, Mic		Gym parking. Principal is requirement by the boys dressing roo				
<u>Jaime Mija</u> 77065	rez		8/17/2011	6	62	\$0.00
Medium	Work In Progress		8/17/2011 2:24:17 PM	_		,
Orozco, Da	-	GARBAGE DISPOSAL NOT D WILL NOT GO DOWN. SNP N	RAINING WATER/FOOD			

10/18/2011 1:23:09 PM Page 152 of 172

WOID	Building	Area Deferred By	Until Request Date Target (A	Costs Labor Hours
Priority	Status	Area Number Reason	Created Date/Time Actual (Somp Date	Tiours
Assigned		Description	Act	ion Taken	
Requester					
Location:	Santa Te	resa MS			
77770			9/2/2011	46	\$0.00
Medium	Work In Progress		9/2/2011 11:53:44 AM		
Moncayo,	Fernando	REACH IN FREEZER IS NOT FR SNP MANAGER PAULA S. 589.9			
Maritza Go	onzalez		0/44/0044	0.4	# 0.00
78337		Cafeteria	9/14/2011	34	\$0.00
Medium	Work In Progress		9/14/2011 2:18:10 PM		
Moncayo,	Fernando	CLOGGED DRAIN AT THE WAS	HING MACHINE.		
		PAULA SANCHEZ, SNP MGR 5	89-9836		
Jacqueline 75769	e Aguilar		7/25/2011	85	\$0.00
	Madala Dasanasa			00	Ψ0.00
Medium	Work In Progress		7/25/2011 9:28:54 AM		
Gonzalez,	Salvador	Metal portable rooms 3-a, 3-b nee installed on all windows. As per M rooms will be used for Orchestra rhaving expensive music instrumer	rs. Lovelace portables music and they will be		
Jaime Mija		5.1.	0.770044		Ф0.00
78039	North Building	Parking Lot	9/7/2011	41	\$0.00
Medium	Work In Progress	GATE ON SIDE	9/7/2011 3:42:16 PM		
Gonzalez,	Salvador	GATE ON SIDE OF NORTH BUIL WELDED. ASAP.	DING NEEDS TO BE		
Laura Pari	ra		9/28/2011	20	\$0.00
78912				20	φ0.00
Medium	Work In Progress		9/28/2011 11:19:14 AM		
Gonzalez,		please install railing by the parking continue with the design of exixtin details.thankyou			
Michael M 79734	unoz South Building	Classroom	10/13/2011	5	\$0.00
Medium	Work In Progress	36A	10/13/2011 2:52:11 PM		·
Lara, Ralp	· ·	NEED ADDITIONAL KEY FOR NE ROOM 36A			
Laura Parı	ra	NOON OOM			
79826	South Building	Custodial	10/17/2011	1	\$0.00
. 0020			10/17/2011 10:30:57		
Medium	Work In Progress		10/11/2011 10:00:01		
	· ·	The custodial closet in the southbodoesnt open see Mr.Rodriguez			

10/18/2011 1:23:09 PM Page 153 of 172

Selected Da	ate Range for Request Building	Dates:7/1/2011 - 6/30/2012 Order By Area Deferred By	Location, Status Until Request Date Target Con	np Date Days	Total Costs Labor
Priority	Status	Area Number Reason	Created Date/Time Actual Con	A	Hours
Assigned		Description		Taken	
Requeste	r Name	•			
Location:	Santa Te	resa MS			
76756	North Building	Custodial	8/10/2011	69	\$0.00
Medium	Work In Progress		8/10/2011 8:57:39 AM		
Flores, Pe	ete	Pete, the small tracter #455 need change.	ls tires and the oil to be		
Ismael Ro		Dayling Lat	40/42/2044		\$0.00
79733	South Building	Parking Lot	10/13/2011	5	\$0.00
Medium	Work In Progress	NORTH AND	10/13/2011 2:46:54 PM		
Mijarez, Ja		NEED AT LEAST 2 ADDITIONAL PARKING SPACES FOR THE SOBUILDINGS.			
Laura Par 77390	ra North Building	Portables	8/25/2011	54	\$0.00
Medium	Work In Progress	P2B	8/25/2011 9:36:22 AM		·
	· ·	1- WINDOWS NEED TO BE SEA			
Ronquillo,	Ruben	2- DOOR WINDOW IS BROKEN			
Laura Par	ra		0/44/0044		
76841			8/11/2011	68	\$0.00
Medium	Work In Progress		8/11/2011 3:30:22 PM		
Orozco, D	anny	OVEN IS NOT HEATING UP AT	ALL		
Danny Ord	ozco				
76440			8/4/2011	75	\$0.00
Medium	Work In Progress		8/4/2011 2:05:46 PM		
Lara, Ralp	bh	N.bldg electronic handicap door of bolt is broken. I removed the bolt order several bolts to have in casper Mr. Montano needs to be fixe wheel chair.	so you can see it and e others are broken. As		
Jaime Mija					
77317	South Building	Restroom (Girls)	8/24/2011	55	\$0.00
Medium	Work In Progress		8/24/2011 7:48:12 AM		
Lara, Ralp	oh	REplacement of bathroom panel restroom as per Mr. Montano.	in south upper girls		
Ismael Ro	driguez	Halloway/Carridan	0/05/0044		ФО ОО
77388	North Building	Hallway/Corridor	8/25/2011	54	\$0.00
Medium	Work In Progress	NEXT TO	8/25/2011 9:33:04 AM		
Lara, Ralp		TROPHY CASE- DOWNSTAIRS TO ROOM 8 NEEDS A LOCK. V TO SET UP DISPLAYS FOR STU REQUEST	WOULD LIKE TO USE		
Laura Par	ra				

10/18/2011 1:23:09 PM Page 154 of 172

WOID	Building	Area	Deferred By		Request Date Target Co			
Priority	Status	Area Number	Reason	Create	ed Date/Time Actual Co	•	Hours	
Assigned '	Го	Description			Actio	n Taken		
Requester	Name							
Location:	Santa Te	resa MS						
78385	Gym (1997)	Dressing Roon	n		9/15/2011	33		\$0.00
Medium	Work In Progress			9/15/20	11 9:02:25 AM			
Lara, Ralpi	1	boys locker roo	the weather strip oom we found a snakes per Mr.Montano	ke under the boy	S			
Ismael Roo								
79352	North Building	Cafeteria			10/4/2011	14		\$0.00
Medium	Work In Progress			10/4/20	11 7:20:52 AM			
Lara, Ralp	n	Rafa, two door see Mr.Rodrig	s in the cafeteria ne uez thanks	eed the brakets t	o lock			
Ismael Ro	driguez							
79364					10/4/2011	14		\$0.00
Medium	Work In Progress			10/4/20	11 9:36:11 AM			
Lara, Ralpi	า	cafeteria doors screwed on fra when they hav has to be taken moved into the	uesting Door Mullia and lobby doors. E me with brackets a e to be removed wh n out or when delive lobby. The south b with key too but firs	Existing mullians nd makes it a ha nen caferteria fur eries on pallets a bullding will requi	are ssle niture re			
Jaime Mija	rez Work Orders		vg. Age of WO's			inta Teresa MS	0	\$0.00

10/18/2011 1:23:09 PM Page 155 of 172

WOID Priority Assigned Requester	Building Status To	Area Number Description	6/30/2012 Order By Lo Deferred By Reason		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES						
78324	Main Building	Classroom		9/14/2011		34		\$0.00
Medium	Work In Progress			9/14/2011 10:39:24 AM				
Villalobos,	David	David need for install washer and dry	you to come and sever in room 20	e what we need to				
Eric Medin 79726	а	Mechanical		10/13/2011		5		\$0.00
Medium	Work In Progress			10/13/2011 9:13:11 AM		Ū		Ψ0.00
Villalobos,	-		nat supplies kitchen lve or ignitor probler	with hot water had				
Eric Medin 78325	a	Classroom		9/14/2011		34		\$0.00
Medium	Work In Progress	Classicom		9/14/2011 10:41:03 AM		04		ψ0.00
Castillo, Ca	· ·		ou to come and see and dryer in room 20	what we need to				
Eric Medin	a			0/40/0044				<u> </u>
78435				9/16/2011		32		\$0.00
Medium	Work In Progress	ROOM		9/16/2011 3:19:21 PM				
Castillo, Ca	arlos		(ARLA HERRRA RO	OUTLET FOR SMART DOM 22 /SUNLAND				
Margaret V	illalobos Main Building	Classroom		8/5/2011		74		\$0.00
76545	J					74		φυ.υυ
Medium	Work In Progress	25		8/5/2011 3:22:25 PM				
Medina, Er	IC		oom in room 25 need nted but bathroom n	ds to be painted. eeds to be painted as				
Yvette Cor	ez	D t (O:-l	- \	0/0/0044		70		<u> </u>
76704		Restroom (Girl	S)	8/9/2011		70		\$0.00
Medium	Work In Progress			8/9/2011 1:14:03 PM				
Medina, Er	ic	Eric, girls bathı	oom floor needs t be	e painted.				
Yvette Cor	ez			40/4/0044				Φο οο
79359		Portables		10/4/2011		14		\$0.00
Medium	Work In Progress			10/4/2011 9:06:54 AM				
Lara, Ralpl	1	DEL PORTABI	S PUEDE CAMBIAF LE D PARA PODER LVE PARA LAS PEF	ABRIRLO CON				
	stillo	- -						

10/18/2011 1:23:09 PM Page 156 of 172

WOID	Building	Dates:7/1/2011 - 6/30/2012 Order By Area Deferred By	Until Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time	•	Aged	Hours	
Assigned 1		Description		Action Taken			
Requester	Name						
Location:	Sunland	Park ES					
79360		Cafeteria	10/4/2011		14		\$0.00
Medium	Work In Progress		10/4/2011 9:12:45 AM				
Lara, Ralph	า	MR. LARA NOS PUEDE ARREG CAFETERIA, SE LE CAYO LA B. Y NO LA PODEMOS CERRAR B KEDA ABIERTA.MUCHAS GRAC	ARRA DE ADENTRO BIEN,POR FUERA				
<u>Valeria Cas</u> 79413	stillo	Classroom	10/5/2011		13		\$0.00
	Mark In Drawna	Classicom			13		ψ0.00
Medium	Work In Progress		10/5/2011 8:50:58 AM				
Lara, Ralph	1	MR LARA POR FAVOR VIENE A PUERTA DE AFUERA DEL CUA BIEN AL JALARLA DE AFUERA	RTO 40 NO CIERRA				
<u>Valeria Cas</u> 79299	stillo		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:29 AM	10/20/2011	10		ψ0.00
	· ·	M 41 0 1 15 1505					
Orozco, Da	anny	Monthly - Sunland Park ES Rang Refer to PM schedule details.	e Hood Cleaning -				
Margret Vil	lalobos		0/40/0044				Φο οο
78508			9/19/2011		29		\$0.00
Medium	Work In Progress		9/19/2011 3:32:46 PM				
Carrasco, I	Danny	Danny need a window fixed on po	ortable a				
Eric Medina	a		0/0/0044				Φο οο
78126			9/9/2011		39		\$0.00
Medium	Work In Progress		9/9/2011 2:44:46 PM				
Munoz, Mic	chael	need to construct concret pad for	trash dumpsters				
Alfredo Hol		Deutin a Let	40/44/0044				Ф0.00
79598	Main Building	Parking Lot	10/11/2011		7		\$0.00
Medium	Work In Progress	MAIN SCHOOL	10/11/2011 7:15:18 AM				
Munoz, Mic	chael	NEED FOR SOMEONE TO COM OUR MAIN ENTRANCE TURN-A HAVE FORMED DUE TO THE IF GRASS IN FRONT OF THE SCH PARENTS AND STAFF MEMBER TO COMPLAIN ABOUT POTHOR MAINTENANCE AND SAFETY OF PARENTS ALSO COMPLAINING SAFETY, AS STUDENTS DO WA TURN-ABOUT AFTER SCHOOL GATES.	BOUT. POTHOLES RRIGATION OF NEW IOOL. MANY RS ARE STARTING LES AND THE DF THEIR VEHICLES. G ABOUT STUDENT ALK THROUGH THE				
	l						

10/18/2011 1:23:09 PM Page 157 of 172

WOID Priority	Building Status	Area Deferred By Area Number Reason	Until Request Date Ta Created Date/Time A	-	Days Aged	Labor Hours	
Assigned T		Description		Action Taken			
Requester	Name						
Location:	Sunland	Park ES					
76991	Main Building	Classroom	8/16/2011		63		\$0.00
Medium	Work In Progress	15	8/16/2011 10:44:56 AM				
Medina, Eri	С	Eric, please lower vents on AC and block in air vent. Also, if you may r					
Yvette Cort	ez	Office	10/4/2011		14		\$0.00
79357	Mark In Duagnas	Office			14		φυ.υυ
Medium	Work In Progress		10/4/2011 9:00:49 AM				
Lara, Ralph	l	MR. LARA PODRIA HACERNOS E A ABRIR LA PUERTA DE MRS. RA PODER LAVAR EL PISO Y PONE	AMIREZ PARA				
Valeria Cas 79103	stillo		10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:26:37 AM	11/2/2011	10		ψ0.00
Medina, Eri	· ·	Yearly - Sunland Park ES U-2 Gas to PM schedule details.					
Margret Vill	alobos	to i Wischedule details.					
79153			10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:04 AM				
Medina, Eri	С	Monthly - Sunland Park ES Roof In PM schedule details.	spection - Refer to				
<u>Margret Vill</u> 79217	alobos		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:42 AM	10, 10, 2011	.0		ψ0.00
Medina, Eri	_	Monthly - Sunland Park ES Emer L Refer to PM schedule details.					
Margret Vill	alobos						
79218			10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:43 AM				
Medina, Eri		Monthly - Sunland Park ES Exit Sig Refer to PM schedule details.	gn Insp: Monthly -				
<u>Margret Vill</u> 79516	alobos		10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress		10/9/2011 12:16:33 AM		-		,
Medina, Eri	· ·	Monthly - Sunland Park ES Playgro					
Margret Vill	alobos						<u> </u>
79274			10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:16 AM				
Medina, Eri	С	Monthly - Sunland Park ES Monthly Refer to PM schedule details.	FE Inspection -				

10/18/2011 1:23:09 PM Page 158 of 172

WOID Priority Assigned Requester	Building Status To	Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES					
76419	Main Building	Parking Lot	8/4/2011		75		\$0.00
Medium	Work In Progress		8/4/2011 8:42:20 AM				
Medina, Eı	ric	Eric, the trees out in the parking I We've had several complaints ab cars that pass by.					
Yvette Cor 78955	tez		9/29/2011		19		\$0.00
Medium	Work In Progress	EARLY	9/29/2011 7:00:17 AM				,
Medina, Eı	ric	ERIC, AS PER MS. HERRERA - WATER IN THE KINDER PLAYG PROBLEMS WITH SPRINKLERS	BIG PUDDLES OF ROUND, DUE TO				
David Avila 78957	a		9/29/2011		19		\$0.00
Medium	Work In Progress	SCHOOL	9/29/2011 7:04:10 AM				******
Medina, Eı	· ·	ERIC, WE NEED FRONT COUR' PLEASE SWEEP, CUT WEEDS PIGEON DROPPINGS FROM FR THANK YOU.	AND REMOVE ALL				
David Avila	a		9/1/2011		47		\$0.00
Medium	Work In Progress		9/1/2011 11:06:45 AM		.,		ψ0.00
Medina, Eı	-	purchase new D130 john deere la replace existing one.					
Michael M	unoz		10/0/0				
79101			10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:26:36 AM				
Medina, Ei		Yearly - Sunland Park ES H-6 Fu to PM schedule details.	rnance Yearly - Refer				
Margret Vi 79102	liaiodos		10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:26:37 AM				
Medina, Eı	-	Yearly - Sunland Park ES I-4 Fan PM schedule details.	Coil Yearly - Refer to				
Margret Vi	llalobos	Cofeteria	0/4/4/00/4/4		24		<u></u>
78310	Mark In Decem	Cafeteria	9/14/2011		34		\$0.00
Medium Moncayo,	Work In Progress Fernando	2nd REQUEST: REFRIGERATO GOING UP AND DOWN.	9/14/2011 8:38:44 AM OR TEMP KEEPS				
Jacqueline	a Aguilar	MARINA R. SNP MGR 589-2545	5				

10/18/2011 1:23:10 PM Page 159 of 172

WOID	Building	Area Deferred By	Until Request Date Ta	A		
Priority	Status -	Area Number Reason	Created Date/Time Ac	•	u nours	
Assigned T		Description		Action Taken		
Requester						
Location:	Sunland	Park ES				
79742			10/13/2011	5		\$0.00
Medium	Work In Progress		10/13/2011 3:39:53 PM			
Orozco, Da	anny	NO HOT WATER IN HAND SINK MARINA R. 8589.2545	. SNP MANAGER			
Maritza Go	nzalez		0 100 100 1 1	-		Φο οο
78573			9/20/2011	28		\$0.00
Medium	Work In Progress		9/20/2011 3:38:10 PM			
Gonzalez,	Salvador	chava need drag for weeds at sur	nlandpark			
Eric Medin						
79597	Main Building	Hallway/Corridor	10/11/2011	7		\$0.00
Medium	Work In Progress	PLEASE SEE	10/11/2011 7:11:33 AM			
Lara, Ralpł		NEED FOR RALPH TO CHECK OF TO OUTSIDE IN HALLWAYS. RECHECK DOORS TO MAKE SURICLOSING CORRECTLY. IF YOU CLARIFICATION PLEASE SEE MAKES	ALPH PLEASE E THEY ARE J NEED			
David Avila 78463	1		9/16/2011	32		\$0.00
Medium	Work In Progress		9/16/2011 3:53:42 PM	0_		Ψ0.00
	· ·		3/10/2011 3.33. 1 2 1 W			
Carrasco, I	-	need fuel for truck #105				
Eric Medina 79842	a		10/17/2011	1		\$0.00
	Madala Dassassa			'		ψ0.00
Medium	Work In Progress		10/17/2011 12:25:31			
Carrasco, I	Danny	need fuel for truck #105				
Eric Medin		Oleanne	0/00/0044	40		#0.00
78954	Main Building	Classroom	9/29/2011	19		\$0.00
Medium	Work In Progress	CLASSROOM	9/29/2011 6:57:39 AM			
Medina, Er	ic	ERIC, MS. ARMENDARIZ SINK I WATER IS RISING NEAR SPILL YOU.				
David Avila	a		9/29/2011	19	<u> </u>	\$0.00
78956	Work In Drograss	EADLV		18		φυ.υυ
Medium	Work In Progress	EARLY	9/29/2011 7:01:53 AM			
Medina, Er	ic	ERICK - AS PER MS. SMITH - TI THE SWINGS IN THE EARLY CI PLAYGROUND THAT CONTINU. WATER, PLEASE CHECK. THA	HILDHOOD ALLY FILLS WITH			
		With Ent, I believe on Lord. This	1111 1 00.,			

10/18/2011 1:23:10 PM Page 160 of 172

WOID Priority	Building Status	Area Area Number	Deferred By Reason	Until Request Date Ta Created Date/Time Ad	ctual Comp Date	Days Aged	Labor Hours	Costs
Assigned		Description			Action Taken			
Requester	Name							
Location:	Sunland	Park ES						
78969	Main Building	Classroom		9/29/2011		19		\$0.00
Medium	Work In Progress	Classroom #16	6	9/29/2011 8:50:58 AM				
Medina, E	ric	THE ROOMS \ REPLACED. L	E PLEASE CHECK T WHERE THE DOORS .ARGE PIECES OF C . THIS IS A SAFETY	S ARE BEING GLASS ARE BEING				
David Avila				40/44/2044		7		ቀስ ሰብ
79599	Main Building	DI AVGDOLINI	_	10/11/2011		7		\$0.00
Medium	Work In Progress	PLAYGROUNI	J	10/11/2011 7:20:40 AM				
Medina, E	ric	HOLE - NEEDS GRADER BRO	GUTIERREZ, PLAYGI S REPAIR. LAST YE OKER HER HAND WI MS. GUTIERREZ FO	AR A FIRST HEN SHE TRIPPED.				
David Avila	a			8/3/2011		76		\$0.00
Medium	Work In Progress			8/3/2011 2:36:41 PM		70		ψ0.00
Orozco, Da	· ·	DO TURN ON ONE GOES TO	RE NOT WORKING OK BUT AFTER ABO DO HIGH AND THE O IG. SNP MANAGER I	PROPERLY, THEY DUT 10 MINUTES DTHERS WILL				
Maritza Go	onzalez			0/0/0044		40		#0.00
77969				9/6/2011		42		\$0.00
Medium	Work In Progress			9/6/2011 11:16:22 AM				
Moncayo,			IENT SANITIZER SIN ER MARINA R. 589.25					
Maritza Go 77175	onzalez			8/19/2011		60		\$0.00
Medium	Work In Progress			8/19/2011 3:29:10 PM				
Ambriz, Jo	-	Joe need to ord	der (2) two taylor hals pressors out					
Eric Medin 77337	ia Main Building	Library		8/24/2011		55		\$0.00
	_	· ·				JJ		ψυ.υυ
Medium	Work In Progress	Library (C.		8/24/2011 12:13:29 PM				
Medina, E	ric	NEED CLOCK	HUNG ON WALL					
David Avila	а							

10/18/2011 1:23:10 PM Page 161 of 172

WOID Priority Assigned Requester			Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
_ocation:	Sunland	Park ES						
77970	Main Building	Office		9/6/2011		42		\$0.00
Medium	Work In Progress	Ms. Terrazas -		9/6/2011 11:54:03 AM				
Medina, Er		OUT" FOR MRS		KEYBOARD "PULL- READY SPOKE TO HAT HE NEEDS.				
<u>David Avila</u> 78326	a Main Building	Classroom		9/14/2011		34		\$0.00
Medium	Work In Progress	BRIONES		9/14/2011 10:55:45 AM				
Medina, Er			ED A PENCIL SHA IES CLASSROOM	RPNER INSTALLED RM#11. THANK				
<u>David Avila</u> 78504	a Main Building	Classroom		9/19/2011		29		\$0.00
Medium	Work In Progress	CLASSROOM		9/19/2011 3:21:12 PM				
Medina, Er	ric	ERICK, MS. CO SHARPNER.	RDERO NEEDS A	NEW PENCIL				
<u>David Avila</u> 78570	a Main Building	Classroom		9/20/2011		28		\$0.00
Medium	Work In Progress	CLASSROOM		9/20/2011 3:35:46 PM				*
Medina, Er	ric		E FIX LEAK IN MRS R MS. HERRERA T ANK YOU.					
David Avila 76546	a Main Building	Classroom		8/5/2011		74		\$0.00
Medium	Work In Progress	21		8/5/2011 3:24:04 PM				*
Medina, Er	_	Eric, some flour room 21 please.		ed to be replaced in				
<u>Yvette Cor</u> 76561	tez Main Building	Parking Lot		8/5/2011		74		\$0.00
Medium	Work In Progress	Back Parking		8/5/2011 3:58:54 PM		- *		, , , , ,
Medina, Er	· ·	Eric, Mrs. Althou	use (nurse) needs to n the back parking lo	b be assigned a				
Yvette Cor		Classroom		8/8/2011		71		\$0.00
76634 Medium	Main Building Work In Progress	13 & 15		8/8/2011 2:45:40 PM		/ 1		φυ.υυ
	_		and Ma Maralas h					
Medina, Er	IG		and Ms. Morales b classrooms for bro					
Yvette Cor	tez	mounted in their	olassioonis ioi bio	aavasiirig.				

10/18/2011 1:23:10 PM Page 162 of 172

WOID Priority Assigned T Requester		Area Deferred By Area Number Reason Description	Until Request Date Targ Created Date/Time Act		Labor Hours	Costs
Location:	Sunland	Park ES				
76675	Main Building	Classroom	8/9/2011	70		\$0.00
Medium	Work In Progress	35	8/9/2011 8:04:37 AM			
Medina, Er	ic	Eric, please set repair shelves in	room 35 for Ms. Moran.			
Yvette Cort			0/0/0044	70		Ф0.00
76678	Main Building	Classroom	8/9/2011	70		\$0.00
Medium	Work In Progress	14	8/9/2011 8:10:21 AM			
Medina, Er		Eric, the whiteboard in room 14 is one of the chalkboards in the room				
<u>Yvette Cort</u> 76994	<u>ez</u> Main Building	Classroom	8/16/2011	63		\$0.00
Medium	Work In Progress	29	8/16/2011 10:58:17 AM			
Medina, Er	Ŭ	Eric, please move small board to (rug area).	left side of classroom.			
Yvette Cort	ez	(1.15 1.1 1.1)				
77338	Main Building	Library	8/24/2011	55		\$0.00
Medium	Work In Progress	C. MORENO	8/24/2011 12:18:43 PM			
Medina, Er		NEED MAIN LIBRARY DOORS ADOORS RE-PAINTED.	AND AUDIO VISUAL			
David Avila 78786			9/26/2011	22		\$0.00
Medium	Work In Progress		9/26/2011 2:29:22 PM			
Medina, Er	•	Need paint for graffitti and hand	rails			
Eric Medina		rioca paint for gramm and mana				
78817	Main Building	Portables	9/27/2011	21		\$0.00
Medium	Work In Progress	PORTABLE E	9/27/2011 8:16:17 AM			
Medina, Er	ic	WOULD LIKE TO HAVE PORTA IS SERVING AS THE OFFICE F COUNSELOR, PARENT AMBAS THERAPIST.	OR THE SCHOOL			
David Avila 77043			8/17/2011	62		\$0.00
Medium	Work In Progress		8/17/2011 8:23:35 AM	V-		ψ0.00
Ambriz, Jos	_	Jose need to order frames also f sunland park if possible				
Eric Medina						
79371	Main Building		10/4/2011	14		\$0.00
Medium	Work In Progress		10/4/2011 2:31:53 PM			
Lara, Ralph	1	Custodian need to strip and wax (principals request) and the lock				

10/18/2011 1:23:10 PM Page 163 of 172

Total Selected Date Range for Request Dates:7/1/2011 - 6/30/2012 Order By Location, Status Costs WOID Building Area **Deferred By** Until **Request Date Target Comp Date** Days Labor Hours Aged Area Number Reason **Status** Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description **Requester Name Sunland Park ES** Location: 76493 Main Building Parking Lot 8/5/2011 74 \$0.00 8/5/2011 9:40:34 AM Medium Work In Progress Medina, Eric Eric, as per Mrs. Ramirez we need four baracades. Please place an order for them.

Yvette Cortez

Count: 57 Work Orders Avg. Age of WO's 34 Total for Sunland Park ES 0 \$0.00

10/18/2011 1:23:10 PM Page 164 of 172

WOID Priority Assigned Requeste		Area Deferred By Until Request Date Target Comp Date Area Number Reason Created Date/Time Actual Comp Date Description Action Taken	Days Aged	Labor Hours	
Location:		ES			
78542		9/20/2011	28		\$0.00
Medium	Work In Progress	9/20/2011 10:51:51 AM			
Ontiveros,	_	need fix water lleck front area closed to sprinkler buster pomp			
Juan Varg	jas	9/28/2011	20		\$0.00
78889	Mark In Drawns		20		\$0.00
Medium	Work In Progress	9/28/2011 7:44:39 AM			
Sotelo, En	nrique	need replace two outside lamps on portables 3 and 7			
Juan Varg 79488	jas	10/7/2011	11		\$0.00
Medium	Work In Progress	10/7/2011 3:17:25 PM			ψ0.00
Solis, Lore	•	a/c on room 309 need replace water pomp not work leken			
Juan Varg	jas				
77467		8/26/2011	53		\$0.00
Medium	Work In Progress	8/26/2011 8:35:55 AM			
Lozoya, M	lanny	need fix gabinete lock not open on parent room			
Juan Varg	jas	0.004.0044	07		Φο οο
78619		9/21/2011	27		\$0.00
Medium	Work In Progress	9/21/2011 11:04:59 AM			
	, Guadalupe	nesesito un pino de 8 ft. para ponerlo donde el aire tunbo un pino			
Juan Varg 76204	jas	8/1/2011	78		\$0.00
	Work In Progress	8/1/2011 3:38:59 PM			*****
Apodaca,		SEWAGE WATER NEED REPLACE POMP NOT WORK			
Juan Varg	ıas	WORK			
78202	,	9/12/2011	36		\$0.00
Medium	Work In Progress	9/12/2011 3:22:28 PM			
Vargas, Ju	uan	09-12-11 1-check school 2-fix a/c counselor room 1-fix 9/12-6 a/x room 103 2-cut weed front area			
Juan Varg	jas	10/5/2011	13		\$0.00
79404 Modium	Work In Progress		13		φυ.υυ
Medium	Work In Progress	10/5/2011 8:10:15 AM			
Vargas, Ju	uan	10-1-11 1-check school 7-asamblin furniture on pre-k 10/1 - Not entered of	n a Time	ely Manner	

10/18/2011 1:23:10 PM Page 165 of 172

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By Area Deferred By Area Number Reason Description	Until Request Dat	e Target Comp Date e Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunrise I	 ES					
79033	Main Building	Classroom	9/30/201	1	18		\$0.00
Medium	Work In Progress	202	9/30/2011 10:37:22 A	M			
Sotelo, Enr	ique	GEORGE MCKAMY, 202, NEEDS ELECTRICAL BOX IN CEILING	S TO INSTALL				
Joanne Mu			0/00/004		40		Φο οο
79034	Main Building	Classroom	9/30/201		18		\$0.00
Medium	Work In Progress	201	9/30/2011 10:38:26 A	M			
Sotelo, Enr	ique	TERESA MARQUEZ, 201, NNED ELECTRICAL BOX INSTALLED I					
Joanne Mu 79035	<u>noz</u> Main Building	Classroom	9/30/201	1	18		\$0.00
	_				10		ψ0.00
Medium Sotelo, Enr	Work In Progress	101 EDNA CLARY, 101, NEEDS TO I BOX INSTALLED IN CEILING.	9/30/2011 10:58:15 A HAVE ELECTRICAL	IVI			
Joanne Mu							
79053	Main Building	Classroom	9/30/201	1	18		\$0.00
Medium	Work In Progress	CONFERENCE	9/30/2011 3:38:15 P	M			
Sotelo, Enr		CECILIA DORAN, CONFERENC HAVE ELECTRICAL BOX INSTA CEILING					
Joanne Mu 79896	noz		10/18/201	1	0		\$0.00
	Mark In Duanna				O		ψ0.00
Medium	Work In Progress		10/18/2011 10:56:2	27			
Solis, Lorei	nzo	need check speech room unite	e not on				
Juan Varga	is		8/15/201	1	64		\$0.00
76965	W 11 B				04		ψ0.00
Medium	Work In Progress		8/15/2011 3:51:36 P	M			
Vargas, Ju	an	08-15-11 1-check school 3-p.pla	ant 2-76596 2-76595	8/15 -4			
Juan Varga	as		7/4/004		100		Φο οο
75071			7/4/201		106		\$0.00
Medium	Work In Progress		7/4/2011 12:22:39 A	M			
Sanchez, F		Monthly - Sunrise ES - DP-1421 - details.	Refer to PM schedule				
Margret Vil 79246	lalobos		10/2/201	1	16		\$0.00
	Mork In Drasins -				10		ψυ.υυ
Medium	Work In Progress		10/2/2011 12:28:00 A	IVI			
Sanchez, F	Raul	Monthly - Sunrise ES - DP-1421 - details.	Refer to PM schedule				

10/18/2011 1:23:10 PM Page 166 of 172

WOID Priority Assigned Requester		Area Number Reason Description	Created Date/Time	Actual Comp Date Action Taken	Aged	Hours	
Location:	Sunrise I	ES .					
79256			10/2/2011		16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:05 AM				
Sanchez, l	Raul	Monthly - Sunrise ES - Wastewater Refer to PM schedule details.	Weed Control -				
<u>Margret Vi</u> 79262	llalobos		10/2/2011	10/8/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:09 AM	19,9,2011	. •		Ψ0.00
Vargas, Ju	_	Monthly - Sunrise ES Monthly FE In PM schedule details.					
Margret Vi	llalobos		40/0/0044	40/00/0044	40		Ф0.00
79300			10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:30 AM				
Orozco, Da	•	Monthly - Sunrise ES Range Hood PM schedule details.	Cleaning - Refer to				
<u>Margret Vi</u> 79032	<u>llalobos</u> Main Building	Classroom	9/30/2011		18		\$0.00
Medium	Work In Progress	211	9/30/2011 10:36:15 AM				
Sotelo, En	rique	LA TOYA SALIU, 211, NEEDS TO ECLECRIAL BOX IN CEILING	INSTALL				
Joanne Mu 79533	unoz		10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress		10/9/2011 12:16:42 AM	10/23/2011	9		ψ0.00
Gallegos, l	-	Monthly - QRTLY BLDG INSP REPPM schedule details.					
Margret Vi	llalobos		10/2/2011	10/10/2011	16		\$0.00
79164	Mork In Drogroop		10/2/2011 12:27:10 AM	10/10/2011	10		φυ.υυ
Medium Vargas, Ju	Work In Progress	Monthly - Sunrise ES Roof Inspecti					
Margret Vi	llalohos	schedule details.					
79175	iidiobos		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:17 AM				
Vargas, Ju	ian	Monthly - Sunrise ES Exit Sign Insp PM schedule details.	o: Monthly - Refer to				
<u>Margret Vi</u> 79176	llalobos		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:18 AM	13, 13,2011			Ψ0.00
Vargas, Ju	_	Monthly - Sunrise ES Emer. Light T to PM schedule details.					

10/18/2011 1:23:10 PM Page 167 of 172

WOID	Building	· · · · · · · · · · · · · · · · · · ·	arget Comp Date	Days Aged	Labor	Costs
Priority	Status	Area Number Reason Created Date/Time A	-	Aged	Hours	
Assigned Requeste		Description	Action Taken			
Location:		-s				
79173		10/2/2011		16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:15 AM		10		ψ0.00
	_					
Vargas, Jı	uan	Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret V	illalobos					
79527		10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress	10/9/2011 12:16:39 AM				
Vargas, Ju		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.				
<u>Margret V</u> 78530	illalobos	9/20/2011		28		\$0.00
Medium	Work In Progress	9/20/2011 7:46:54 AM				ψσ.σ.
	•					
Carrasco,	-	need chiansow to cut pine tree				
<u>Juan Varg</u> 78893	gas	9/28/2011		20		\$0.00
Medium	Work In Progress	9/28/2011 7:58:18 AM				****
Carrasco,	_	need 15 gas gls. for 156 truck and 5 gls. dises for mower				
Juan Varg	jas					
78348		9/14/2011		34		\$0.00
Medium	Work In Progress	9/14/2011 3:38:34 PM				
Munoz, M	ichael	need replace gate on front parking hit by someone. Case# 9844				
Juan Varg 79016	gas	9/30/2011		18		\$0.00
Medium	Mark In Drogram			10		ψ0.00
	Work In Progress	9/30/2011 12:22:33 AM				
Vargas, Ju	uan	Monthly - Sunrise ES A16 (Fan Exh.)(S. Annual) - Refer to PM schedule details.				
<u>Margret V</u> 79075	illalobos	10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Drogram	10/2/2011 12:26:22 AM	11/2/2011	10		ψ0.00
	Work In Progress					
Vargas, Ju	uan	Yearly - Sunrise ES H6 (Furnace)(Yearly) - Refer to PM schedule details.				
Margret V	illalobos					
79076		10/2/2011	11/2/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:26:22 AM				
Vargas, Jı		Yearly - Sunrise ES U2 (Gas Heater)(Yearly) - Refer to PM schedule details.				
Margret V	illalobos Work Orders	Avg. Age of WO's 25	Total for Sunris		0	\$0.00

10/18/2011 1:23:10 PM Page 168 of 172

WOID Priority	Building Status	Area Number Reason Until Request Date Tail Created Date/Time Action		ays Labor ged Hours	
Assigned '	То	Description	Action Taken		
Requester	Name				
Location:	Vado ES				
78781		9/26/2011		22	\$0.00
Medium	Work In Progress	9/26/2011 12:31:55 PM			
Sotelo, En	rique	need to ck. emergency lights in restrooms 100-wing and 300-wing			
Danny Mira 78785	anda	9/26/2011		22	\$0.00
Medium	Work In Progress	9/26/2011 2:26:58 PM	_		ψ0.00
Sotelo, En	· ·	need to replace backup lighting in gym checked batterys breackers and power			
Danny Mira	anda				Φο οο
79637		10/11/2011		7	\$0.00
Medium	Work In Progress	10/11/2011 2:38:48 PM			
Sotelo, En	•	NEED TO PUT IN NEW ELECTRICAL OUTLETS ON CELING FOR SMART BOARDS IN SIX CLASSROOMS			
<u>Danny Mira</u> 79552	anda	10/10/2011		8	\$0.00
Medium	Work In Progress	10/10/2011 9:06:39 AM			
Solis, Lore	nzo	NEED TI REPAIR WATER LEAK ON 3" LINES IN 100- WING BOILER ROOM			
Danny Mira		Classroom 9/1/2011		47	ድር ሰር
77706	Main Building		2	47	\$0.00
Medium Lozoya, M	Work In Progress anny	9/1/2011 11:45:08 AM MS. NAVARRO PRINCIPAL REQUEST THAT WE HAVE 2 KEYS MADE FOR CAFETERIA AND 3 NEW KEYS WITH DIFFERENT LOCK MADE FOR STORAGE UNIT NEXT TO CAFETERIA.			
Debra Fac	io	0/4/0044		47	<u>Фо</u> оо
77718		9/1/2011	2	47	\$0.00
Medium	Work In Progress	9/1/2011 2:41:33 PM			
Lozoya, Ma	•	NEED TO CK. FRONT DOOR IN RM. 105 PREKINDER CHILD IS GETTING OUT OF CLASSROOM			
<u>Danny Mira</u> 79511	anda	10/9/2011	10/25/2011	9	\$0.00
Medium	Work In Progress	10/9/2011 12:16:31 AM			
Miranda, D	anny	Monthly - Vado ES Playground Insp - Refer to PM schedule details.			
Margret Vil 79266	lalobos	10/2/2011	10/8/2011	16	\$0.00
	Work In Progress		10/0/2011	10	ψυ.υυ
Medium Miranda, D	Work In Progress	Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.			
	lalobos	Scriedule detalls.			

WOID	Building Status	Area Deferred By Area Number Reason	Until Request Date Ta Created Date/Time Ac	-	Days Aged	Labor Hours	
Priority Assigned		Description	Created Date/Time Ad	Action Taken			
Requester		Description		Action Taken			
Location:	Vado ES						
79301			10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:28:31 AM				*****
Orozco, Da	_	Monthly - Vado ES Range Hood Cleaschedule details.	aning - Refer to PM				
Margret Vi	llalobos		10/17/2011		- 1		\$0.00
79817	W				1		\$0.00
Medium	Work In Progress	SPED OFFICE	10/17/2011 10:18:45				
Briones, E	nrique	PO #101108760 PICK UP ONE BOX DELIVER TO MARISA LUCEROTEACHERVAD	O ELEMENTARY				
Margaret \		Custodial	10/10/2011		0		<u></u>
79555	Main Building	Custodiai	10/10/2011		8		\$0.00
Medium	Work In Progress		10/10/2011 10:22:13				
Carbajal, c	•	Jimmy the other buffer serial # is 04	9 THANK you.				
<u>Armando I</u> 79554	<u>Diaz</u> Main Building	Custodial	10/10/2011		8		\$0.00
Medium	Work In Progress		10/10/2011 10:16:00				•
Carbajal, J	· ·	Jimmy have 2 buffer that won't start 1					
Armando I	•	ommy have 2 baner that wern etail	i lo dellar de l'				
79147	Jiaz		10/2/2011	10/23/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:01 AM				
Orozco, Da	anny	Monthly - Vado ES F-39 Kitchen Exh Refer to PM schedule details.	Unit Semiannual -				
Margret Vi 79506	llalobos		10/9/2011	10/25/2011	9		\$0.00
Medium	Work In Progress		10/9/2011 12:16:28 AM	10/23/2011	3		ψ0.00
Diaz, Arma	_	Monthly - QRTLY BLDG INSP REPC PM schedule details.					
Margret Vi	llalobos	i w scriedule details.					
79149			10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:02 AM				
Miranda, Danny		Monthly - Vado ES Roof Inspection - schedule details.	Refer to PM				
Margret Vi 79214	llalobos		10/2/2011	10/10/2011	16		\$0.00
Medium	Work In Progress		10/2/2011 12:27:41 AM	. 5, . 6, 20 1 1	. •		\$3.00
Miranda, [· ·	Monthly - Vado ES Emer. Light Test: PM schedule details.					

10/18/2011 1:23:10 PM Page 170 of 172

WOID	Building	•	te Target Comp Date	Days Aged	Labor Hours	
Priority	Status		e Action Tokan	Ageu	nours	
Assigned Requester		Description	Action Taken			
-						
_ocation:	Vado ES					
79215		10/2/20	11 10/10/2011	16		\$0.00
Medium	Work In Progress	10/2/2011 12:27:41 <i>A</i>	AM			
Miranda, D	Danny	Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.				
<u>Margret Vi</u> 79216	illalobos	10/2/20	11	16		\$0.00
	Wash la Dansas			10		ψ0.00
Medium	Work In Progress	10/2/2011 12:27:42 /	AIVI			
Miranda, D	•	Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details.				
<u>Margret Vi</u> 76418	illalobos	Cafeteria 8/4/20	11	75		\$0.00
Medium	Work In Progress	8/4/2011 8:31:11 /				·
Orozco, Da	· ·	ICE MACHINE NOT WORKING (NO ICE)				
		EVA M. SNP MGR 233-2945				
Jacqueline	e Aguilar					
78004	•	9/7/20	11	41		\$0.00
Medium	Work In Progress	9/7/2011 9:30:49 A	AM			
Moncayo,	Fernando	NEED WATER FILTER FOR ICE MACHINE- SNP MANAGER EVA M. 233.2945				
Maritza Go 75525	onzalez	7/19/20	11	91		\$0.00
Medium	Work In Progress	7/19/2011 7:49:57 /		0.		Ψ0.00
	· ·		AIVI			
Gonzalez,		NEED ANCORES FOR SOCCER GOALS				
Danny Mir. 75526	anda	Athletic Field 7/19/20	11	91		\$0.00
Medium	Work In Progress	7/19/2011 7:53:18 /		0.		ψ0.00
	· ·		AIVI			
	, Guadalupe	NEED NEW SOCCER NETS FOR FOR GOALS DUE TO VANDALISM				
Danny Mir. 77005	anda	8/16/20 ⁻	11	63		\$0.00
Medium	Work In Progress	8/16/2011 2:05:23 F	PM			
	Guadalupe	NEED TO REPLACE DEAD PINE TREE WITH NEW ONE BY BUSS TURN AROUND				
Danny Mir	anda	ONE DI BUSS TURN ARCOND				
79010	anda	9/30/20	11	18		\$0.00
Medium	Work In Progress	9/30/2011 12:22:30 A	AM			
Miranda, D	Danny	Monthly - Vado ES A-16 - Fan Exhaust Semiannual - Refer to PM schedule details.				
Margret Vi	illalobos					
	1 1:23:10 PM					

WOID Priority Assigned ¹ Requester	Building Status To	Dates:7/1/2011 - 6/30/2012 Order By Location, Status Area Deferred By Until Request Date Tal Area Number Reason Created Date/Time Ac Description	A	Costs abor ours
Location:	Vado ES			
78112		9/9/2011	39	\$0.00
Medium	Work In Progress	9/9/2011 10:23:47 AM		
Lozoya, Ma	anny	NEED LOCK AND KEYS MADE FOR DESK IN RM. #105		
Danny Mira 77753	anda	9/2/2011	46	\$0.00
Medium	Work In Progress	9/2/2011 8:42:19 AM	40	φ0.00
	-			
Miranda, D	anny	NEED TO CHANGE FILTERS		
Danny Mira 78627	anda	9/21/2011	27	\$0.00
Medium	Work In Progress	9/21/2011 2:30:44 PM	- -	Ψ0.00
Miranda, D	-	NEED TO PUT PARKING SIGN FOR PRINCIPAL, ASST PRINCIPAL, SECRETARY, AND RECEPTIONIST		
Danny Mira	anda	10/11/00/1		Ф0.00
79654		10/11/2011	7	\$0.00
Medium	Work In Progress	10/11/2011 3:48:43 PM		
Miranda, D	anny	NEED TO REPAIR 1/2" AND 3/4" DRIP WATER LINES		
Danny Mira	anda	40/44/0044		Ф0.00
79772		10/14/2011	4	\$0.00
Medium	Work In Progress	10/14/2011 12:17:50		
Miranda, D		NEED TO REPLACE FAN MOTOR IN TEACHERS LOUNGE AND COMM. ROOM 100-WING		
Danny Mira 79779	anua	10/14/2011	4	\$0.00
Medium	Work In Progress	10/14/2011 3:21:45 PM		
Miranda, D	anny	NEED TO REPLACE FAN MOTOR IN COMM. ROOM AND CK. NOISE IN ELECTRICAL RM. 300-WING		
Danny Mira		Ave. Are of WOIs . 27	Total for Volta FO	0 60.00
Count: 30	Work Orders	Avg. Age of WO's 27	Total for Vado ES	0 \$0.00

10/18/2011 1:23:10 PM Page 172 of 172