

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
104674					7/24/2013		54		\$0.00
Medium	Work In Progress	DIRECTOR'S		7/24/2013 9:24:52 AM					
Nunez, Arturo	Install short throw project in Mr. Rapanut's office. Equipment and mount are in that room.								
<u>Margaret Villalobos</u>									
107425					9/13/2013		3		\$0.00
High	Work In Progress			9/13/2013 11:53:01 AM					
Marquez, Gerardo	Please install remainder of cores on all Anthony Pre-K closets and mechanical closet doors. Also, please cut one (1) key of installed cores to be checked out to Sandoval Construction today. For questions or more information, please contact Mr. Ralph Gallegos at 575-882-6921.								
<u>Dominique Esparza</u>									
106090					8/15/2013		32		\$0.00
Medium	Work In Progress			8/15/2013 2:51:26 PM					
Nunez, Arturo	trim shrubs in front of office								
<u>Laura Vazquez</u>									
106330					8/21/2013		26		\$0.00
Medium	Work In Progress			8/21/2013 10:31:09 AM					
Nunez, Arturo	please assemble new furniture!								
<u>Laura Vazquez</u>									
106089		Office			8/15/2013		32		\$0.00
Medium	Work In Progress	575882-1904		8/15/2013 2:49:43 PM					
Nunez, Arturo	fix tiles in receptions area								
<u>Laura Vazquez</u>									
105728		Office			8/9/2013		38		\$0.00
Medium	Work In Progress			8/9/2013 8:56:27 AM					
Nunez, Arturo	Replace broken floor tiles in receptionist area								
<u>Estrella Becerra</u>									
Count: 6 Work Orders			Avg. Age of WO's	31	Total for Anthony - On Track Pre-K (Village)		0		\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
105237					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:20 AM					
Nunez, Arturo	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107051					9/4/2013		12		\$0.00
Medium	Work In Progress	310		9/4/2013 10:31:05 AM					
Villalobos, Margret	Please fumigate room for roaches Room #310 Mrs. Nunez		Approved - 37.50						
<u>Jessica Lopez</u>									
106052					8/15/2013		32		\$0.00
Medium	Work In Progress			8/15/2013 8:04:46 AM					
Gonzalez, Salvador	As per Ms. Perez please repair fence, parents are crossing the field Location: Soccer field								
<u>Jessica Lopez</u>									
106874					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:29 AM					
Nunez, Arturo	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106875					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:29 AM					
Nunez, Arturo	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106055					8/15/2013		32		\$0.00
Medium	Work In Progress			8/15/2013 8:08:32 AM					
Nunez, Arturo	Mr. Nunez please assemble new coffee rolling cart box located in teacher's lounge								
<u>Jessica Lopez</u>									
106056					8/15/2013		32		\$0.00
Medium	Work In Progress			8/15/2013 8:09:56 AM					
Nunez, Arturo	Mr. Nunez please assemble 2 rolling carts boxes are located in teacher's lounge								
<u>Jessica Lopez</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
103957					7/2/2013		76		\$0.00
Medium	Work In Progress	SPED OFFICE			7/2/2013 9:37:24 AM				
Nunez, Arturo		INSTALL WINDOW BLINDS IN THE FRONT OFFICE WINDOW (PREFERABLY BIG SLATS BUT LITTLE SLATS WILL DO)							
<u>Margaret Villalobos</u>									
103966					7/2/2013		76		\$0.00
Medium	Work In Progress	SPED OFFICE			7/2/2013 3:02:37 PM				
Nunez, Arturo		MOVE DESK FROM BUDGET CLERK OFFICE INTO OTHER OFFICE SEE MARGARET							
<u>Margaret Villalobos</u>									
103967					7/2/2013		76		\$0.00
Medium	Work In Progress	SPED OFFICE			7/2/2013 3:03:37 PM				
Nunez, Arturo		MOVE DESK AND SHELVES FROM MARGARET'S OFFICE INTO NEW EARLY CHILDHOOD OFFICE (SEE MARGARET)							
<u>Margaret Villalobos</u>									
104475					7/18/2013		60		\$0.00
Medium	Work In Progress				7/18/2013 12:04:28 PM				
Nunez, Arturo		Mr. Nunez as per Ms. Perez please move tv located in Ms. Barajas office and move it to Room #401 (Susana Garcia)							
<u>Jessica Lopez</u>									
104557					7/22/2013		56		\$0.00
Medium	Work In Progress	SPED OFFICE			7/22/2013 12:29:17 PM				
Nunez, Arturo		INSTALL WHITE BOARD IN MR. RAPANUTS CONFERENCE ROOM							
<u>Margaret Villalobos</u>									
106983					9/3/2013		13		\$0.00
Medium	Work In Progress				9/3/2013 9:05:00 AM				
Medina, Eric		As per Ms. Perez grass and weeds need to be cut							
<u>Jessica Lopez</u>									
107005					9/3/2013		13		\$0.00
Medium	Work In Progress	400			9/3/2013 12:00:11 PM				
Medina, Eric		Elmo table needs screws please see Ms. S Ramos Room #400							
Jessica Lopez									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
106806					8/30/2013		17		\$0.00
Medium	Work In Progress			8/30/2013 3:06:05 PM					
Medina, Eric	Cut soccer field on Church St.								
<u>Michael Munoz</u>									
105552					8/7/2013		40		\$0.00
Medium	Work In Progress	SPED OFFICE		8/7/2013 7:58:25 AM					
Nunez, Arturo	ASSEMBLE DESK FOR MARGARET (SEE MARGARET OR JULIE)								
<u>Margaret Villalobos</u>									
107358		Office			9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 1:57:34 PM					
Gonzales, Camilo	PLEASE DELIVER 20 BOXES K-2 MATH ENVISIONS TE								
<u>Larry Martinez</u>									
106962					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:30:04 AM					
Nunez, Arturo	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105342					8/4/2013	8/10/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:07 AM					
Nunez, Arturo	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105310					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:54 AM					
Munoz, Michael	Yearly - Anthony ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107317					9/10/2013		6		\$0.00
Medium	Work In Progress	109		9/10/2013 3:45:02 PM					
Marquez, Gerardo	As per Ms. Sarah Garcia Room #109 please change storage lock to classroom lock								
<u>Jessica Lopez</u>									
106994					9/3/2013		13		\$0.00
Medium	Work In Progress			9/3/2013 9:55:44 AM					
Sotelo, Enrique	Outside lights are not working please check								
<u>Jessica Lopez</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
105809					8/11/2013	9/11/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:39 AM					
Nunez, Arturo	Yearly - Anthony ES A9 (AC Condenser)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
104198					7/10/2013		68		\$0.00
Medium	Work In Progress			7/10/2013 3:55:29 PM					
Solis, Lorenzo	A.C. unit in pre k office work room needs to be replaced								
<u>Arturo Nunez</u>									
107121					9/5/2013		11		\$0.00
Medium	Work In Progress	413		9/5/2013 11:12:09 AM					
Solis, Lorenzo	Mrs. V. Ramos Room #413 Airconditioner is not cooling please check								
<u>Jessica Lopez</u>									
105362					8/5/2013		42		\$0.00
Medium	Work In Progress			8/5/2013 7:57:27 AM					
Marquez, Gerardo	Door knobs in pre k rooms 108 to 111, need to be replaced from door knob type to lever type								
<u>Arturo Nunez</u>									
107296	Main Building				9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 1:08:17 PM					
Estrada, Jesus	vacuum cleaner serial#00223 electrical problem								
<u>David Vega</u>									
107337	Main Building				9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 8:53:11 AM					
Apodaca, Mario	alarm in pump house is on, needs to be reset								
<u>David Vega</u>									
107472	Main Building				9/16/2013		0		\$0.00
Medium	Work In Progress			9/16/2013 7:49:41 AM					
Marquez, Gerardo	need 30" of chain too lock walk through gates								
<u>David Vega</u>									
106543	Main Building				8/27/2013		20		\$0.00
High	Work In Progress			8/27/2013 7:27:16 AM					
Medina, Eric	weeds need to be cut and removed from the front of the Alamo parking lot and around site.								
Michael Munoz									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Anthony ES									
103994					7/3/2013		75		\$0.00
High	Work In Progress				7/3/2013 10:18:49 AM				
Ronquillo, Ruben	please order new batteries for fire pump and install. thank you.								
<u>Michael Munoz</u>									
103971	Pump House	Pump House			7/2/2013		76		\$0.00
Medium	Work In Progress				7/2/2013 3:36:43 PM				
Apodaca, Mario	need to order a new irrigation water meter reader due to the one that is there is no longer working								
<u>Mario Apodaca</u>									
Count: 32 Work Orders			Avg. Age of WO's	34			Total for Anthony ES	0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

104833 7/29/2013 49 \$0.00

Medium Work In Progress 7/29/2013 1:01:51 PM

Solis, Lorenzo MR LORENZO SOLIS SIR THE BOOSTER PUMP #2
RED ALARM LIGHT IS ON PLEASE CHECK THANK
YOU AND GOD BLESS

Adan Duran

107457 9/15/2013 1 \$0.00

Medium Work In Progress 9/15/2013 12:17:48 AM

Villalobos, Margret Monthly - Berino ES - PC Automated Quarterly - Refer 9/16/13 Emailed Aide
to PM schedule details.

Margret Villalobos

106415 8/22/2013 25 \$0.00

Medium Work In Progress 8/22/2013 3:01:14 PM

Solis, Lorenzo MR LORENZO SOLIS SIR NEED TO REPLACE TWO
FAN MOTORS BOTH IN ELETICAL ROOMS EAST
WING AND MIDDLE WING GETTING HOT THANK
YOU SIR AND GOD BLESS

Adan Duran

107488 9/16/2013 0 \$0.00

Medium Work In Progress LINE LOCATE 9/16/2013 9:22:13 AM

Sotelo, Enrique Need to line locate where the new Desert Pride school
will be built. Any questions, please contact Adan Duran.

Michael Munoz

107489 9/16/2013 0 \$0.00

Medium Work In Progress LINE LOCATE 9/16/2013 9:23:39 AM

Villalobos, David Need to line locate where the new Desert Pride school
will be built. Any questions, please contact Adan Duran.

Michael Munoz

107134 9/5/2013 11 \$0.00

Medium Work In Progress 9/5/2013 3:29:36 PM

Villalobos, David MR DAVID VILLALOBOS SIR BETWEEN ROOM
100&102 KIDS RESTROOM THE COMODE HAS A
HOLE AND IS CRACK NEED TO REPLACE WHOLE
THING CAN NOT BE USED THANK YOU AND GOD
BLESS

Adan Duran

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
104905					7/30/2013		48		\$0.00
Medium	Work In Progress			7/30/2013 10:19:55 AM					
Cortez, Jimmy	CARPET WILL BE INSTALLED IN PORTABLES 155 & 156 STARTING ON THURSDAY, AUG 1ST. NEED TO PULL OUT ALL FURNITURE FROM 156 INTO 155 BY WEDNESDAY, JULY 31. AS SOON AS CARPET HAS BEEN INSTALLED IN 156, ALL FURNITURE NEEDS TO BE MOVED FROM 155 TO 156 SO THAT CARPET CAN BE INSTALLED (IN 155).								
Jesus Estrada									
105311					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:54 AM					
Munoz, Michael	Yearly - Berino ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
107059					9/4/2013		12		\$0.00
Medium	Work In Progress			9/4/2013 12:56:28 PM					
Carbajal, Jimmy	vaccum has a short I06c000000198								
Jimmy Cortez									
107071					9/4/2013		12		\$0.00
Medium	Work In Progress			9/4/2013 3:16:40 PM					
Duran, Adan	MR ADURAN SIR NEED TO INSTALL WIND SCREEN AROUND IRRGATION TANKS TORN BY DOGS								
Adan Duran									
104920					7/30/2013		48		\$0.00
Medium	Work In Progress			7/30/2013 2:31:53 PM					
Duran, Adan	North Playground - rockwall 2nd time tagged.								
Adan Duran									
107212					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:08 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
Count: 12 Work Orders			Avg. Age of WO's	21		Total for Berino ES	0		\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
107210					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:07 AM					
Quinones, Paul	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105826					8/11/2013	8/27/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:46 AM					
Quinones, Paul	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
104065					7/7/2013	7/23/2013	71		\$0.00
Medium	Work In Progress			7/7/2013 12:22:51 AM					
Quinones, Paul	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105334					8/4/2013	8/10/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:04 AM					
Quinones, Paul	Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106947					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:57 AM					
Quinones, Paul	Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107385					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 4:10:00 PM					
Marquez, Gerardo	door dragging on floor door hinges are bend,and hinge screws are stripped rm.106								
<u>Paul Quinones</u>									
105312					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:55 AM					
Munoz, Michael	Yearly - Chaparral ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106966					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:30:06 AM					
Quinones, Paul	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
105357					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:14 AM					
Quinones, Paul	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107351					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 10:37:44 AM					
Ontiveros, Guadalupe	sink hole between the portables, and the cafeteria. requesting gravel and the impacter								
<u>Paul Quinones</u>									
107095					9/4/2013		12		\$0.00
Medium	Work In Progress			9/4/2013 4:03:38 PM					
Ontiveros, Guadalupe	irrigation water line next to the water tank water leak water line connecting pump and motor								
<u>Paul Quinones</u>									
106927					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:49 AM					
Quinones, Paul	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106919					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:46 AM					
Quinones, Paul	Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107334					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 8:32:43 AM					
Quinones, Paul	requesting heavy duty coat hooks 3" type for class rms. need for student back packs								
<u>Paul Quinones</u>									
106592					8/27/2013		20		\$0.00
Medium	Work In Progress			8/27/2013 2:53:40 PM					
Quinones, Paul	girls rest rm. in e-wing, metal latches are broken that secure doors. latches need to be replaced								
<u>Paul Quinones</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral ES									
106601					8/27/2013		20		\$0.00
Medium	Work In Progress			8/27/2013 3:27:56 PM					
Quinones, Paul	reorder sprinklers for restock,and to replace broken sprinklers								
Paul Quinones									
106779					8/30/2013		17		\$0.00
Medium	Work In Progress			8/30/2013 8:01:24 AM					
Quinones, Paul	NEED PAINT TO PAINT STUDENT CROSS WALK IN FRONT OF SCHOOL WHITE COLORED PAINT								
Paul Quinones									
105287					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:43 AM					
Quinones, Paul	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
105286					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:43 AM					
Quinones, Paul	Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
104309					7/15/2013		63		\$0.00
Medium	Work In Progress			7/15/2013 8:14:21 AM					
Quinones, Paul	NEED PVC GLUE AND PRIMER FOR IRRIGATION PROJECT REQUESTING A QUART OF EACH.								
Paul Quinones									
107397					9/12/2013		4		\$0.00
Medium	Work In Progress			9/12/2013 11:16:30 AM					
Quinones, Paul	REORDER AIR FILTERS HEATING AND COOLING FOR RESTOCK AND HEATING SEASON								
Paul Quinones									
107352					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 10:39:50 AM					
Appelzoller, Fred	requesting toilet replacement in the girls,and boys rest rm.in the front entrance.								
Paul Quinones									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
107273					9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 4:06:27 PM					
Appelzoller, Fred	water faucet leaking water,requesting a new water faucet in the womens staffs rest rm.								
<hr/>									
106281					8/20/2013		27		\$0.00
Medium	Work In Progress			8/20/2013 12:22:23 PM					
Vallejo, Albert	requesting 2,and 4 lamp ballast for portables								
<hr/>									
106282					8/20/2013		27		\$0.00
Medium	Work In Progress			8/20/2013 12:27:46 PM					
Vallejo, Albert	front entrance of school replace 2 lights cieling type.1 light needs a ballast 70 watt type bulb.requesting reorder light bulbs and ballast for restock								
<hr/>									
104492					7/18/2013		60		\$0.00
Medium	Work In Progress	office		7/18/2013 2:23:46 PM					
Vallejo, Albert	need one more electrical outlet. see Front office								
<hr/>									
106828					8/31/2013		16		\$0.00
Medium	Work In Progress			8/31/2013 12:25:35 AM					
Quinones, Paul	Monthly - Chaparral ES A-16 Exh Fan (Semi Annual) - Refer to PM schedule details.								
<hr/>									
106850					9/1/2013	9/22/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:19 AM					
Quinones, Paul	Monthly - Chaparral ES H-11 Unit Heater Semiannual - Refer to PM schedule details.								
<hr/>									
106851					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:19 AM					
Quinones, Paul	Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.								
<hr/>									
Margret Villalobos									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral ES								
105984					8/14/2013		33		\$0.00	
Medium	Work In Progress			8/14/2013 7:59:24 AM						
Marquez, Gerardo	requesting 3 panic bar allen wrench keys for the principle,requested by principle ms.pargas. attn;gerardo									
Paul Quinones										
107160	Main Building	Classroom			9/6/2013		10		\$0.00	
Medium	Work In Progress	307		9/6/2013 9:39:35 AM						
Marquez, Gerardo	classroom key doesnt work to open the other doors outside and need to open to get back to classroom. See Waldmann									
Jennifer Corral										
106791	Main Building	Classroom			8/30/2013		17		\$0.00	
Medium	Work In Progress	312		8/30/2013 10:11:59 AM						
Vallejo, Albert	need electrical cables for new computer lab. See Davd and Ms. El-Kurdi									
Jennifer Corral										
Count: 32 Work Orders		Avg. Age of WO's 24		Total for Chaparral ES			0	\$0.00		

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
106655	Pre-K	Exterior			8/28/2013		19		\$0.00
Medium	Work In Progress			8/28/2013 1:34:33 PM					
Gallegos, Rafael	Warranty work order, Cinder block wall at play ground is falling apart.								
<u>Alfredo Ortiz</u>									
105967	Pre-K				8/13/2013		34		\$0.00
Medium	Work In Progress			8/13/2013 3:55:48 PM					
Ortiz, Alfredo	Need to put some concrete around water fountain, out side at sand area.								
<u>Alfredo Ortiz</u>									
105662	Pre-K	Classroom			8/8/2013		39		\$0.00
Medium	Work In Progress			8/8/2013 9:59:11 AM					
Ortiz, Alfredo	Need to replace thermastats in classrooms.								
<u>Alfredo Ortiz</u>									
104223	Pre-K				7/11/2013		67		\$0.00
Medium	Work In Progress			7/11/2013 1:04:54 PM					
Ontiveros, Guadalupe	build raised planters								
<u>Alfredo Holguin</u>									
106965					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:30:05 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107426	A-Wing	Hallway/Corridor			9/13/2013		3		\$0.00
Medium	Work In Progress			9/13/2013 12:32:45 PM					
Ronquillo, Ruben	One of the window's between D and E hallway has a crack and in danger of breaking. (Mireya Meza)								
<u>Mireya Meza</u>									
107348	A-Wing	Hallway/Corridor			9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 9:35:09 AM					
Ortiz, Alfredo	Rain water is running down the inside of the main hallway walls in the main corridor. (Ms. V. Lopez)								
<u>Mireya Meza</u>									
106053	A-Wing	Office			8/15/2013		32		\$0.00
Medium	Work In Progress			8/15/2013 8:05:31 AM					
Ortiz, Alfredo	Desk drawers do not open/close correctly in new counselors office. (Mr. Encina)								
<u>Mireya Meza</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
104752	A-Wing	Exterior			7/25/2013		53		\$0.00
Medium	Work In Progress			7/25/2013 3:46:15 PM					
Appelzoller, Fred		Need to repair pumps for rain water.							
<u>Alfredo Ortiz</u>									
106689	A-Wing	Roof			8/28/2013		19		\$0.00
Medium	Work In Progress			8/28/2013 3:50:38 PM					
Solis, Lorenzo		A/C unit squirrel cage blower wheel broken.							
<u>Alfredo Ortiz</u>									
104285	A-Wing	Roof			7/12/2013		66		\$0.00
Medium	Work In Progress			7/12/2013 3:17:27 PM					
Appelzoller, Fred		need a water line on the roof to maintain roof clean from dirty and wash it down the roof drain s ,							
<u>Fred Appelzoller</u>									
105990	A-Wing	Office			8/14/2013		33		\$0.00
Medium	Work In Progress			8/14/2013 10:02:43 AM					
Marquez, Gerardo		Please disregard work order #105914. I only need one CH master key and have one picked up to destroy. (Mireya Meza)							
<u>Mireya Meza</u>									
105363	A-Wing	Office			8/5/2013		42		\$0.00
Medium	Work In Progress			8/5/2013 8:11:06 AM					
Marquez, Gerardo		Please make 1 copy of keys #238 & #142 for the nurse's filing cabinet. These are the Fire king cabinets. (Ms. deCastro)							
<u>Mireya Meza</u>									
107166	A-Wing	Exterior			9/6/2013		10		\$0.00
Medium	Work In Progress			9/6/2013 10:19:47 AM					
Marquez, Gerardo		Need small locks for exterior electricl panals about 7							
<u>Alfredo Ortiz</u>									
107350	A-Wing	Classroom			9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 10:09:26 AM					
Munoz, Michael		Rain water seeps in thru the east windows. (Ms. V. Lopez)							
<u>Mireya Meza</u>									
107171	A-Wing	Cafeteria			9/6/2013		10		\$0.00
Medium	Work In Progress			9/6/2013 11:37:08 AM					
Marquez, Gerardo		Repair hinge-arm at top of door on the double doors by attendance going to the cafeteria. (Ms. Lopez)							
<u>Mireya Meza</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
107429	A-Wing	Office			9/13/2013		3		\$0.00
Medium	Work In Progress	SOFIA PAYEN			9/13/2013 1:34:21 PM				
Gonzales, Camilo	PLEASE DELIVER THE FOLLOWING ITEMS TO: SOFIA PAYEN								
	PO # 131400808 - 3BOXES (TRAVEL GEAR) - CHS G BASKETBALL								
Terry Alvarado									
107430	A-Wing	Office			9/13/2013		3		\$0.00
Medium	Work In Progress	SOFIA PAYEN			9/13/2013 1:36:11 PM				
Gonzales, Camilo	PLEASE DELIVER THE FOLLOWING ITEMS TO: SOFIA PAYEN								
	PO # 131400417 - 1 BOX (MISC. SUPPLIES) CHS B BASKETBALL								
Terry Alvarado									
107431	A-Wing	Office			9/13/2013		3		\$0.00
Medium	Work In Progress	SOFIA PAYEN			9/13/2013 1:37:27 PM				
Gonzales, Camilo	PLEASE DELIVER THE FOLLOWING ITEMS TO: SOFIA PAYEN								
	PO # 131400809 - 7BOXES (TAPE) CHS TRAINER								
Terry Alvarado									
106726	A-Wing	Library			8/29/2013		18		\$0.00
Medium	Work In Progress				8/29/2013 10:52:42 AM				
Marquez, Gerardo	Main entrance door to library does not lock. Please fix. (Ms. DeVine, library)								
Mireya Meza									
105657	B-Wing	Classroom			8/8/2013		39		\$0.00
Medium	Work In Progress				8/8/2013 9:40:42 AM				
Marquez, Gerardo	Outside door needs a door handle from the inside to be able to lock. (sped room B2, Ms. Perez)								
Mireya Meza									
107424	B-Wing	Classroom			9/13/2013		3		\$0.00
Medium	Work In Progress				9/13/2013 11:41:44 AM				
Marquez, Gerardo	Need to replace locking lach broken, emergency cut off door.								
Alfredo Ortiz									
105648	B-Wing	Classroom			8/8/2013		39		\$0.00
Medium	Work In Progress				8/8/2013 8:06:35 AM				
Ortiz, Alfredo	Special Ed room in B2 needs door stopper, paper towel dispenser and entrance plastic (glue). (room B2, Ms. Perez)								
Mireya Meza									
9/16/2013 4:20:13 PM									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
107347	C-Wing	Classroom			9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 9:32:52 AM					
Munoz, Michael	Water leaks into room from outside windows in rooms C7 & G4. (Ms. V. Lopez)								
<u>Mireya Meza</u>									
106728	E-Wing	Classroom			8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 10:56:37 AM					
Ortiz, Alfredo	Please patch hole above in focus. (Ms. Godin, E4)								
<u>Mireya Meza</u>									
105369	F-Wing	Classroom			8/5/2013		42		\$0.00
Medium	Work In Progress			8/5/2013 9:20:34 AM					
Ortiz, Alfredo	Please remove mounted overhead screen and maps. (Ms. Salcedo F5)								
<u>Mireya Meza</u>									
107481	G-Wing	Computer Lab			9/16/2013		0		\$0.00
Medium	Work In Progress			9/16/2013 8:10:37 AM					
Marquez, Gerardo	I need 2 keys for the G-computer lab but I don't know the key #. (Mireya Meza)								
<u>Mireya Meza</u>									
105851	Q-Wing	Classroom			8/12/2013		35		\$0.00
Medium	Work In Progress			8/12/2013 10:14:14 AM					
Marquez, Gerardo	The wrestling/tennis room share a door with Q2. This door is locked on my side but it can be opened from the neighboring room without a key. There is a large amount of valuable equipment in Q2 and I would feel better knowing that all access points were secure. Perhaps it would be possible to have the door lock both directions. (Mr. Woodard)								
<u>Mireya Meza</u>									
106511	Q-Wing	Classroom			8/26/2013		21		\$0.00
Medium	Work In Progress			8/26/2013 2:19:49 PM					
Vallejo, Albert	I would like to request a 220 outlet so I can plug in a welder. (Mr. Galvan, Q6)								
<u>Mireya Meza</u>									
107294	Q-Wing	Roof			9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 12:42:15 PM					
Ortiz, Alfredo	Need to replace water pumps and clean machinge on A/C units Q-wing roof.								
Alfredo Ortiz									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
104619	Q-Wing	Classroom			7/23/2013		55		\$0.00
Medium	Work In Progress			7/23/2013 10:39:03 AM					
Ontiveros, Guadalupe		Construction lab: move storage shed from construction lab to outside of art building. Lay concrete slab for shed. fence in storage shed. (LUPE SEE MIKE ON THIS)							
<u>Mireya Meza</u>									
105149	Q-Wing	Hallway/Corridor			8/2/2013		45		\$0.00
Medium	Work In Progress			8/2/2013 2:12:13 PM					
Gonzalez, Salvador		Secure lockers with cable so students won't use.							
<u>Alfredo Ortiz</u>									
104550	Q-Wing	Classroom			7/22/2013		56		\$0.00
Medium	Work In Progress			7/22/2013 8:54:19 AM					
Ortiz, Alfredo		Construction lab: (1)move a construction equipment into storage & cages in welding & construction lab. (2) build fence around electrical boxes in construction lab. (AS PER MIKE MUNOZ, THERE IS A WORK ORDER IN PROGRESS ON THIS)							
<u>Mireya Meza</u>									
106057	Q-Wing	Classroom			8/15/2013		32		\$0.00
Medium	Work In Progress			8/15/2013 8:13:34 AM					
Munoz, Michael		Need to install a fence around electrical panels at Q-building Construction Lab.							
<u>Alfredo Ortiz</u>									
105111	R-Wing	Classroom			8/2/2013		45		\$0.00
Medium	Work In Progress			8/2/2013 9:23:52 AM					
Ortiz, Alfredo		Need the two bulletin boards outside D5 installed in R4. They are part of my Perkins inventory. (Ms. Holguin)							
<u>Mireya Meza</u>									
104747	R-Wing	Mechanical			7/25/2013		53		\$0.00
Medium	Work In Progress			7/25/2013 3:41:23 PM					
Solis, Lorenzo		Need to replace contactors and fuses at Q and R-buildings, for Geo thermal pumps.							
<u>Alfredo Ortiz</u>									
106316	Field House	Athletic Field			8/21/2013		26		\$0.00
Medium	Work In Progress			8/21/2013 8:21:33 AM					
Marquez, Gerardo		Unfortunately the locks were cut during the summer. These locks were used to close gates at the football field and to stop coaches from driving thru side walk. It is a safety issue. I need 5 locks. (Lupe Quinones, security)							
<u>Mireya Meza</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
106972	Field House	Football Field			9/3/2013		13		\$0.00
Medium	Work In Progress				9/3/2013 7:40:52 AM				
Vallejo, Albert	Ticket booth has no eletrical power. Need for football games.								
<u>Alfredo Ortiz</u>									
106493	Field House	Athletic Field			8/26/2013		21		\$0.00
Medium	Work In Progress				8/26/2013 8:49:08 AM				
Vallejo, Albert	There are several lights in the football field that do not work. The lights directly outside the trainers office are not working. The two small light post on walk way from concession stand to bleachers do not turn on. The two small light post on walk way on the guest side do not turn on. Please have these fixed ASAP. Our next game is Friday August 30th. (Mireya Meza)								
<u>Mireya Meza</u>									
107162	Field House	Athletic Field			9/6/2013		10		\$0.00
Medium	Work In Progress				9/6/2013 9:44:13 AM				
Vallejo, Albert	Need key for staidium lights								
<u>Alfredo Ortiz</u>									
105087	Field House	Roof			8/1/2013		46		\$0.00
Medium	Work In Progress				8/1/2013 3:47:29 PM				
Vallejo, Albert	Need to replace contactores at field house also fuses.								
<u>Alfredo Ortiz</u>									
104321	Field House	Classroom			7/15/2013		63		\$0.00
Medium	Work In Progress				7/15/2013 2:43:16 PM				
Ortiz, Alfredo	Boys soccer coaches would like to have blinds installed in the weight room. This is now coaches office. (Fernie Mendoza)								
<u>Mireya Meza</u>									
105773	Field House	Athletic Field			8/9/2013		38		\$0.00
Medium	Work In Progress	KAREN			8/9/2013 2:22:11 PM				
Gonzalez, Salvador	CHS - SOCCER FIELDS (2) PERMANENT CANOPIES - ONE FOR VISITORS AND ONE FOR HOME TEAM. THANK YOU!								
<u>Terry Alvarado</u>									
104731	Field House	Laundry Room			7/25/2013		53		\$0.00
Medium	Work In Progress				7/25/2013 11:02:29 AM				
Ortiz, Alfredo	Laundry machine not working in field house. (Mr. Beets)				ALFREDO - IF YOU NEED ASSISTANCE, CALL MIKE				
Mireya Meza									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

105660	H-Wing	Dressing Room			8/8/2013		39		\$0.00
--------	--------	---------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/8/2013 9:52:01 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo
Please put the metal door back on. The door that is suppose to be between the girls basketball locker room and showers. (Ms. Lydia Guerrero, girls dressing room)

Mireya Meza

104299	H-Wing	Gym			7/12/2013		66		\$0.00
--------	--------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/12/2013 3:46:04 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Carrasco, Danny
Need scisor lift to clean smok detectors and beam in gym

Alfredo Ortiz

106345	H-Wing	Auditorium			8/21/2013		26		\$0.00
--------	--------	------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/21/2013 1:23:54 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ortiz, Alfredo
Banners hung from rafters on the west side of gym. I have the banners. (Erika Guerrero, gym)

Mireya Meza

105901	H-Wing	Gym			8/13/2013		34		\$0.00
--------	--------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/13/2013 7:39:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael
The wood floor in the Gym is buckling again.

Alfredo Ortiz

106064	H-Wing	Dressing Room			8/15/2013		32		\$0.00
--------	--------	---------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/15/2013 10:06:47 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ortiz, Alfredo
Basket ball coach needs wall painted black strip.

Alfredo Ortiz

105802					8/11/2013	9/11/2013	36		\$0.00
--------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				8/11/2013 12:17:35 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ortiz, Alfredo
Yearly - Chaparral HS A9(Cool Condenser)(Yearly) - Refer to PM schedule details.

Margret Villalobos

105456					8/6/2013		41		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	LINE LOCATE			8/6/2013 8:28:25 AM				
--------	------------------	-------------	--	--	---------------------	--	--	--	--

Vallejo, Albert
NORTH BOUNDARY BETWEEN HIGH SCHOOL AND GRADE SCHOOL AT THE TENNIS COURTS

Company:RCI POWER AND LIGHTING
Contact Name: BENNIE WILLIAMS Phone:
(575)532-1110

Alfredo Holguin

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
106973		Restroom (Boys)			9/3/2013		13		\$0.00
Medium	Work In Progress				9/3/2013 7:45:28 AM				
Ortiz, Alfredo	Need to paint restrooms to remove graffitty.								
Alfredo Ortiz									
104177					7/10/2013		0		\$0.00
Medium	Work In Progress	LINE LOCATE			7/10/2013 2:08:26 PM	7/10/2013			
Appelzoller, Fred	SPOT A 60FT RADIUS AROUND THE STAKE MAKED WITH TETRA TECH APROX 40FT W OF COUNTY LINE RD BEHIND THE CENTURY LINK PEDESTAL								
	Company: TETRA TECH Contact Name: SHANE OLERICH Contact Phone: (602)768-3447								
Alfredo Holguin									
106842					9/1/2013	9/4/2013	15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:15 AM				
Ortiz, Alfredo	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
107458					9/15/2013		1		\$0.00
Medium	Work In Progress				9/15/2013 12:17:48 AM				
Valdez, Pedro	Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.								
Margret Villalobos									
106602		Lift Station			8/27/2013		20		\$0.00
Medium	Work In Progress				8/27/2013 3:28:14 PM				
Gonzalez, Salvador	need to retro fit pump bracket at storm water lift pump station out side and theater. (welding job)								
Mario Apodaca									
106821		Gym			8/30/2013		17		\$0.00
High	Work In Progress				8/30/2013 4:23:26 PM				
Ortiz, Alfredo	please cut gym wood floor 3/4" at the southwest entrance for expansion. call mike for more info. thank you								
Michael Munoz									
105327					8/4/2013		43		\$0.00
Medium	Work In Progress				8/4/2013 12:20:01 AM				
Munoz, Michael	Yearly - Chaparral HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral HS								
107357		Roof			9/11/2013		5		\$0.00	
Medium	Work In Progress			9/11/2013 1:40:48 PM						
Ortiz, Alfredo	Need to replace filters for heating season start-up.									
<u>Alfredo Ortiz</u>										
106937					9/1/2013		15		\$0.00	
Medium	Work In Progress			9/1/2013 12:29:53 AM						
Apodaca, Mario	Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
106065					8/15/2013		32		\$0.00	
Medium	Work In Progress			8/15/2013 10:09:59 AM						
Ortiz, Alfredo	Need to replace broken ratchet and order metal drill bit set.									
<u>Alfredo Ortiz</u>										
106867					9/1/2013		15		\$0.00	
Medium	Work In Progress			9/1/2013 12:29:26 AM						
Ortiz, Alfredo	Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
106872					9/1/2013		15		\$0.00	
Medium	Work In Progress			9/1/2013 12:29:28 AM						
Ortiz, Alfredo	Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
106873					9/1/2013	10/2/2013	15		\$0.00	
Medium	Work In Progress			9/1/2013 12:29:28 AM						
Ortiz, Alfredo	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
107380		Exterior			9/11/2013		5		\$0.00	
Medium	Work In Progress			9/11/2013 3:49:48 PM						
Ortiz, Alfredo	Need to seal several security light outside walls									
<u>Alfredo Ortiz</u>										
Count: 65 Work Orders		Avg. Age of WO's 27		Total for Chaparral HS			0	\$0.00		

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
106870					9/1/2013	10/2/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:27 AM					
Vallejo, Albert	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106871					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:27 AM					
Vallejo, Albert	Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106866					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:26 AM					
Vallejo, Albert	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106865					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:25 AM					
Vallejo, Albert	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107344					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 9:29:23 AM					
Vallejo, Albert	Replace damaged doors in 300 hallway restroom.								
<u>Albert Vallejo</u>									
104559					7/22/2013		56		\$0.00
Medium	Work In Progress			7/22/2013 2:49:04 PM					
Carrasco, Danny	I need the large scissor lift to remove items from gym rafters.								
<u>Albert Vallejo</u>									
107341					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 9:28:29 AM					
Munoz, Michael	Replace cracked/ damaged skylights in 300 hallway.								
<u>Albert Vallejo</u>									
106963					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:30:05 AM					
Vallejo, Albert	Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
105418					8/5/2013		42		\$0.00
Medium	Work In Progress			8/5/2013 3:32:31 PM					
Carrasco, Danny	Please send large scissor-lift to remove items from gym ceiling.								
Albert Vallejo									
105326					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:01 AM					
Munoz, Michael	Yearly - Chaparral MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
107340					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 9:26:28 AM					
Marquez, Gerardo	Need padlocks for trash cans in football field. Key to 'A' master.								
Albert Vallejo									
106841					9/1/2013	9/4/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:15 AM					
Vallejo, Albert	Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
106560		Storage			8/27/2013		20		\$0.00
Medium	Work In Progress			8/27/2013 10:42:55 AM					
Appelzoller, Fred	senesecita arreglar escusado de los banos #300 hallway es elsegundo escusado seba muy despacio el agua es delo boys GRACIAS								
M. Carmen Perez									
106129					8/16/2013		31		\$0.00
Medium	Work In Progress			8/16/2013 8:32:44 AM					
Appelzoller, Fred	Install valve on line leading to the pressure pump south of the school.								
Albert Vallejo									
106995					9/3/2013		13		\$0.00
Medium	Work In Progress			9/3/2013 10:22:54 AM					
Solis, Lorenzo	Water fountain in girls locker room sounds like a lawn mower when the compressor turns on. The fan is not hitting the shroud. If the fountain is replaced, save the front cover for the fountain in the boys locker room.								
Albert Vallejo									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
107405		Gym			9/12/2013		4		\$0.00
Medium	Work In Progress	boys locker			9/12/2013 5:53:53 PM				
Solis, Lorenzo		The water fountain is producing hot water also the cover has come off.							
<u>Gidget Mora</u>									
107339					9/11/2013		5		\$0.00
Medium	Work In Progress				9/11/2013 9:25:04 AM				
Solis, Lorenzo		Install refrigeration unit for comp lab in 406.							
<u>Albert Vallejo</u>									
107464	Main Building	Classroom			9/15/2013		1		\$0.00
Medium	Work In Progress	301			9/15/2013 1:12:37 PM				
Marquez, Gerardo		Key is stuck in closet key hole							
<u>Gidget Mora</u>									
104768	Main Building	Office			7/26/2013		52		\$0.00
Medium	Work In Progress	Merry			7/26/2013 8:31:49 AM				
Marquez, Gerardo		Needs keys for desk							
<u>Gidget Mora</u>									
106128	Main Building	Computer Lab			8/16/2013		31		\$0.00
Medium	Work In Progress				8/16/2013 8:31:15 AM				
Solis, Lorenzo		Install refrigeration units for computer labs. Rooms 406 and 207.							
<u>Albert Vallejo</u>									
104133	Main Building	Gym			7/9/2013		69		\$0.00
Medium	Work In Progress				7/9/2013 3:33:23 PM				
Ronquillo, Ruben		Have canopy reupholstered.							
<u>Albert Vallejo</u>									
105402	Main Building	Office			8/5/2013		42		\$0.00
Medium	Work In Progress	security			8/5/2013 2:02:00 PM				
Vallejo, Albert		Requesting 2 shelves in the security office							
<u>Gidget Mora</u>									
107406	Main Building	Classroom			9/12/2013		4		\$0.00
Medium	Work In Progress	303			9/12/2013 5:55:41 PM				
Vallejo, Albert		please install new sharpeners							
<u>Gidget Mora</u>									
107462	Main Building	Classroom			9/15/2013		1		\$0.00
Medium	Work In Progress	100			9/15/2013 1:09:20 PM				
Vallejo, Albert		Air conditioner blowing hot air							
<u>Gidget Mora</u>									
9/16/2013 4:20:14 PM									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
107463	Main Building	Classroom			9/15/2013		1		\$0.00
Medium	Work In Progress	300		9/15/2013 1:11:06 PM					
Vallejo, Albert		Please replace missing ceiling tiles.							
<u>Gidget Mora</u>									
107465	Main Building	Classroom			9/15/2013		1		\$0.00
Medium	Work In Progress			9/15/2013 1:22:19 PM					
Vallejo, Albert		Handle on air conditioner was taken by a student-so cant be turned on or off.							
<u>Gidget Mora</u>									
107466	Main Building	Classroom			9/15/2013		1		\$0.00
Medium	Work In Progress	309		9/15/2013 1:28:55 PM					
Vallejo, Albert		please put up a white board							
<u>Gidget Mora</u>									
107467	Main Building	Classroom			9/15/2013		1		\$0.00
Medium	Work In Progress	408		9/15/2013 1:42:41 PM					
Vallejo, Albert		Fire escape window does not open correctly and the screen is bolted so screen door is not removeable							
<u>Gidget Mora</u>									
107468	Main Building	Classroom			9/15/2013		1		\$0.00
Medium	Work In Progress	100		9/15/2013 1:44:16 PM					
Vallejo, Albert		two ceiling light bulbs went out							
<u>Gidget Mora</u>									
Count: 29 Work Orders		Avg. Age of WO's 18		Total for Chaparral MS				0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
107291	Curriculum and	Classroom			9/10/2013		6		\$0.00
Medium	Work In Progress	8		9/10/2013 11:00:58 AM					
Lara, Ralph	KEY TUMBLER ON DOOR FACING WEST NEEDS TO BE FIXED. HAVING DIFFICULTY UNLOCKING AND LOCKING DOOR.								
<u>Yvette Cortez</u>									
105804					8/11/2013	9/11/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:36 AM					
Acosta, David	Yearly - Desert Pride HS A9 (Condenser)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106084		Office			8/15/2013		32		\$0.00
Medium	Work In Progress	restroom		8/15/2013 2:00:27 PM					
Lara, Ralph	need to replace bended key to restroom door.								
<u>David Acosta</u>									
105370		Classroom			8/5/2013		42		\$0.00
Medium	Work In Progress	# 9		8/5/2013 9:27:09 AM					
Lara, Ralph	need to replace door jam.								
<u>David Acosta</u>									
105329					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:02 AM					
Munoz, Michael	Yearly - Desert Pride HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106957					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:30:02 AM					
Acosta, David	Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
104412		Gym			7/17/2013		61		\$0.00
Medium	Work In Progress	Boxing Area		7/17/2013 9:21:11 AM					
Ronquillo, Ruben	PLEASE PERFORM MAINTENANCE ON FITNESS EQUIPMENT ON A QUARTERLY BASIS.								
<u>Yvette Cortez</u>									
105738		Gym			8/9/2013		38		\$0.00
Medium	Work In Progress	Boxing Area		8/9/2013 11:10:51 AM					
Ronquillo, Ruben	PLEASE REPAIR OR REPLACE THE CANVAS BY THE BOXING RING.								
<u>Yvette Cortez</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
107454					9/14/2013		2		\$0.00
Medium	Work In Progress			9/14/2013 12:19:42 AM					
Sanchez, Raul	Monthly - Desert Pride - Water Filters - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106931					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:51 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107490		Parking Lot			9/16/2013		0		\$0.00
Medium	Work In Progress	bus turnaround		9/16/2013 9:37:39 AM					
Carrasco, Danny	Need help with pumping water out of students parking area.								
<u>David Acosta</u>									
106885					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:34 AM					
Acosta, David	Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106886					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:34 AM					
Acosta, David	Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 13 Work Orders			Avg. Age of WO's	25			Total for Desert Pride	0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
105036					8/1/2013		46		\$0.00
Medium	Work In Progress			8/1/2013 9:27:19 AM					
Gonzalez, Salvador	Please install diamond metal plate to new portable ramps and decks.								
<u>Johnny Acuna</u>									
106208					8/19/2013		28		\$0.00
Medium	Work In Progress			8/19/2013 12:27:46 PM					
Orozco, Daniel	Need to re-install threshold to walk-in refrigerator. It came off completely. SNP Manager Pat C. 824.3822								
<u>Maritza Gonzalez</u>									
107205					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:05 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
104070					7/7/2013	7/23/2013	71		\$0.00
Medium	Work In Progress			7/7/2013 12:22:53 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105831					8/11/2013	8/27/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:48 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107398		Custodial			9/12/2013		4		\$0.00
Medium	Work In Progress			9/12/2013 11:33:17 AM					
Carbajal, Jimmy	Jimmy buenos dias la aspiradora num .1177 se le callo la rueda de atras si la puede revisar por favor gracias								
<u>Laura Sandoval</u>									
107399		Custodial			9/12/2013		4		\$0.00
Medium	Work In Progress			9/12/2013 11:44:31 AM					
Carbajal, Jimmy	Jimmy necesito 3 vandas de aspiradora por favor gracias								
<u>Laura Sandoval</u>									
106306					8/20/2013		27		\$0.00
Medium	Work In Progress			8/20/2013 4:22:10 PM					
Gonzalez, Salvador	Need to measure, order material to install skirting around new portable.								
<u>Johnny Acuna</u>									
9/16/2013 4:20:14 PM									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
105313					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:55 AM					
Munoz, Michael	Yearly - Desert Trail ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106953					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:30:00 AM					
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105593					8/7/2013		40		\$0.00
Medium	Work In Progress			8/7/2013 12:53:35 PM					
Munoz, Michael	Asp inspection on PM Fire Sprinkler by Dimar the following was found: Retard system is leaking.								
<u>Michael Munoz</u>									
107227					9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 10:17:23 AM					
Marquez, Gerardo	Security Officer for Chaparral (Elementary) Schools: His keys do not open Chaparral Elementary. Please check keys.								
<u>Johnny Acuna</u>									
106307					8/20/2013		27		\$0.00
Medium	Work In Progress			8/20/2013 4:23:33 PM					
Ontiveros, Guadalupe	Need assistance in leveling out new portable ramps and decks.								
<u>Johnny Acuna</u>									
104417					7/17/2013		61		\$0.00
Medium	Work In Progress			7/17/2013 11:07:47 AM					
Carbajal, Jimmy	Jimmy buenos dias necesito una extactora para labar las alfombras por favor gracias								
<u>Laura Sandoval</u>									
105234					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:19 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105235					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:19 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
106736					8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 12:26:54 PM					
Acuna, Johnny	Need a replacement part for an Electric Clothes Dryer in Room #107.								
	(Need Start Switch W/Knob) Make: General Electric Model: #DVL223EA0WW Serial: #FA731018W								
<u>Johnny Acuna</u>									
106896					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:38 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106897					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:38 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106904					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:41 AM					
Acuna, Johnny	Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106714					8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 9:54:22 AM					
Vallejo, Albert	Need to replace (Warm Air Hand Dryer) Make: Dayton, Model : # 3NXE9, 115V, 20A (Boy's Restroom 2nd Grd. Hall)								
<u>Johnny Acuna</u>									
106549					8/27/2013		20		\$0.00
Medium	Work In Progress			8/27/2013 8:21:41 AM					
Vallejo, Albert	Need to replace light fixture to Restroom in Rm. #206.								
<u>Johnny Acuna</u>									
106697					8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 8:02:00 AM					
Solis, Lorenzo	Need (2) waterfountains for Gym/Cafeteria								
<u>Johnny Acuna</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail Intermediate									
106698					8/29/2013		18		\$0.00
Medium	Work In Progress				8/29/2013 8:03:40 AM				
Solis, Lorenzo		Need (2) 3-N-1 relays for waterfountains. (1) second grade Hall, (1) Third grade hall							
Johnny Acuna									
106403					8/22/2013		25		\$0.00
Medium	Work In Progress				8/22/2013 11:43:03 AM				
Solis, Lorenzo		Need to replace (2) new Nat. Gas Heating units to new portable.							
Johnny Acuna									
106462					8/23/2013		24		\$0.00
Medium	Work In Progress				8/23/2013 12:13:52 PM				
Appelzoller, Fred		Need a replacement comode for RR to room #205. (Tank and Bowl: Elongated							
Johnny Acuna									
Count: 26 Work Orders			Avg. Age of WO's	27		Total for Desert Trail Intermediate	0		\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
107338		Office			9/11/2013		5		\$0.00
Medium	Work In Progress	AP Office			9/11/2013 9:17:35 AM				
Ontiveros, Joe		Unclog the sink. (Gonzalez)							
Guadalupe Gonzalez									
105819					8/11/2013	9/11/2013	36		\$0.00
Medium	Work In Progress				8/11/2013 12:17:43 AM				
Ortiz, Ruben		Yearly - Desert View ES A-9 Air Cooled Yearly - Refer to PM schedule details.							
Margret Villalobos									
106829					8/31/2013		16		\$0.00
Medium	Work In Progress				8/31/2013 12:25:35 AM				
Ortiz, Ruben		Monthly - Desert View ES A-16 Fan Exhaust (Semi) - Refer to PM schedule details.							
Margret Villalobos									
104156		Classroom			7/10/2013		68		\$0.00
Medium	Work In Progress				7/10/2013 8:03:53 AM				
Castillo, Carlos		Need to replace broken light diffusers.							
Carlos Castillo									
104086					7/8/2013		70		\$0.00
Medium	Work In Progress				7/8/2013 1:30:24 PM				
Ambriz, Jose		A/C UNIT IN KITCHEN WENT OUT. SNP MANAGER DELORES R. 589.2425							
Maritza Gonzalez									
103915					7/1/2013		77		\$0.00
Medium	Work In Progress				7/1/2013 1:06:14 PM				
Ambriz, Jose		Water fountain needs to be replaced in the front office on the east side of the school.							
Ruben Ortiz									
104880		Exterior			7/30/2013		48		\$0.00
Medium	Work In Progress				7/30/2013 7:32:55 AM				
Castillo, Carlos		After checking scool sites after rain storms, Found broken grey conduit-identified as main phone line. Will report for repair.							
Carlos Castillo									
107099					9/4/2013		12		\$0.00
Medium	Work In Progress				9/4/2013 4:30:38 PM				
Ortiz, Ruben		need blades for weed eater/edger need a heavy duty hole and metal leaf rake							
Ruben Ortiz									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
104660					7/23/2013		55		\$0.00
Medium	Work In Progress				7/23/2013 8:40:09 PM				
Ortiz, Ruben			Need to remove the sand from the road on the westside of the school. Thank you, Ruben			7/29 - Route to Ruben asp Lupe			
Ruben Ortiz									
104662					7/23/2013		55		\$0.00
Medium	Work In Progress				7/23/2013 8:44:48 PM				
Ortiz, Ruben			Need to drain the pond. Thank you, Ruben			7/29 - Route to Ruben asp Lupe			
Ruben Ortiz									
103916					7/1/2013		77		\$0.00
Medium	Work In Progress				7/1/2013 1:08:03 PM				
Ontiveros, Guadalupe			Sprinkler on the new soccer field does not shut off; the valve is not working properly.						
Ruben Ortiz									
106703					8/29/2013		18		\$0.00
Medium	Work In Progress				8/29/2013 8:26:01 AM				
Ortiz, Ruben			replace sprinklers in the soccer field						
Ruben Ortiz									
106668					8/28/2013		19		\$0.00
Medium	Work In Progress				8/28/2013 3:19:37 PM				
Ortiz, Ruben			In front of the						
			Need to seal the trash can with concrete so that it won't be stolen.						
Guadalupe Gonzalez									
106670					8/28/2013		19		\$0.00
Medium	Work In Progress				8/28/2013 3:27:03 PM				
Ortiz, Ruben			Front of the						
			Need to fix or remove the base to where the flag poles use to be. It is dangerous someone can get hurt.						
Guadalupe Gonzalez									
107498					9/16/2013		0		\$0.00
Medium	Work In Progress				9/16/2013 11:53:55 AM				
Ortiz, Ruben			Need to seal for leaks in the ac's.						
Ruben Ortiz									
105293					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress				8/4/2013 12:19:46 AM				
Ortiz, Ruben			Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.						
Margret Villalobos									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
105291					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:45 AM					
Ortiz, Ruben	Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105292					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:45 AM					
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105070					8/1/2013		46		\$0.00
Medium	Work In Progress			8/1/2013 2:32:03 PM					
Ortiz, Ruben	Need a Heavy Duty Brush 18 or 24 inches a Lawn Rake a Landscape Rake 48 Inches and post hole digger								
<u>Ruben Ortiz</u>									
105074					8/1/2013		46		\$0.00
Medium	Work In Progress			8/1/2013 2:55:59 PM					
Ortiz, Ruben	Need Face shield ,Ear Muffs and on the Bosch Job site AC power charger								
<u>Ruben Ortiz</u>									
106928					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:50 AM					
Ortiz, Ruben	Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106929					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:50 AM					
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106930					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:50 AM					
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105903		Classroom			8/13/2013		34		\$0.00
Medium	Work In Progress	Rm. 22		8/13/2013 8:01:35 AM					
Ortiz, Ruben	Install a bulletin board outside Ms. Chavira's room. (R. Chavira)								
<u>Guadalupe Gonzalez</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
105484		Classroom			8/6/2013		41		\$0.00
Medium	Work In Progress	Front of the		8/6/2013 11:16:22 AM					
Ortiz, Ruben	Little Free Library to be reinstalled at the same spot. Thank you. (C. Gallegos)								
<u>Guadalupe Gonzalez</u>									
104985		Classroom			7/31/2013		47		\$0.00
Medium	Work In Progress	Port. #4		7/31/2013 1:40:04 PM					
Ortiz, Ruben	Lights out in room. (Rees)								
<u>Guadalupe Gonzalez</u>									
105590		Classroom			8/7/2013		40		\$0.00
Medium	Work In Progress	Rm. #34		8/7/2013 12:44:57 PM					
Ortiz, Ruben	Install a white dry erase board in the classroom. (B. Aley)								
<u>Guadalupe Gonzalez</u>									
106767		Office			8/29/2013		18		\$0.00
Medium	Work In Progress	Office		8/29/2013 4:00:39 PM					
Ortiz, Ruben	Assemble desk. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
106769		Office			8/29/2013		18		\$0.00
Medium	Work In Progress	Office		8/29/2013 4:01:20 PM					
Ortiz, Ruben	Assemble Podium (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
106770		Office			8/29/2013		18		\$0.00
Medium	Work In Progress	Office		8/29/2013 4:02:03 PM					
Ortiz, Ruben	Assemble bookshelf (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
104702		Classroom			7/24/2013		54		\$0.00
Medium	Work In Progress	Rm. #29		7/24/2013 3:38:04 PM					
Ortiz, Ruben	Large leak above the air conditioner and another by the shelf. (Autry)								
<u>Guadalupe Gonzalez</u>									
106773		Classroom			8/29/2013		18		\$0.00
Medium	Work In Progress	Rm. #22		8/29/2013 4:05:13 PM					
Ortiz, Ruben	Install a bulletin board outside of her classroom (R. Chavira)								
<u>Guadalupe Gonzalez</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
106634		Classroom			8/28/2013		19		\$0.00
Medium	Work In Progress	Rm. #34			8/28/2013 7:53:54 AM				
Ortiz, Ruben		Take out TV and shelf. (B. Aley)							
<u>Guadalupe Gonzalez</u>									
105864		Classroom			8/12/2013		35		\$0.00
Medium	Work In Progress	Port. #6			8/12/2013 1:30:44 PM				
Ortiz, Ruben		3rd Request: Air conditioner isn't working. (R. Larriva)							
<u>Guadalupe Gonzalez</u>									
105889		Classroom			8/12/2013		35		\$0.00
Medium	Work In Progress	Rm. #31`			8/12/2013 3:54:36 PM				
Ortiz, Ruben		Hang the maps in the classrooms. (A. Spencer)							
<u>Guadalupe Gonzalez</u>									
106257		Classroom			8/20/2013		27		\$0.00
Medium	Work In Progress	Rm. #16			8/20/2013 7:44:28 AM				
Ortiz, Ruben		There are ants in the classroom. If can put caulking around the window. (M. Mack)							
<u>Guadalupe Gonzalez</u>									
106509		Gym			8/26/2013		21		\$0.00
Medium	Work In Progress	Gym			8/26/2013 1:22:05 PM				
Ortiz, Ruben		Install 2 bulletin boards on wall. (Reade)							
<u>Guadalupe Gonzalez</u>									
103917					7/1/2013		77		\$0.00
Medium	Work In Progress				7/1/2013 1:11:33 PM				
Ortiz, Ruben		Need to remove branches from the front mesquite tree							
<u>Ruben Ortiz</u>									
105798					8/9/2013		38		\$0.00
High	Work In Progress				8/9/2013 3:59:33 PM				
Munoz, Michael		a vehicle ran into the front gate on july 31st,2013. need to replace gates.thank you							
<u>Ruben Ortiz</u>									
105314					8/4/2013		43		\$0.00
Medium	Work In Progress				8/4/2013 12:19:55 AM				
Munoz, Michael		Yearly - Desert View ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
106569		Classroom			8/27/2013		20		\$0.00
Medium	Work In Progress	Rm. #37		8/27/2013 12:12:02 PM					
Estrada, Jesus		Carpet needs repair. (E. Martinez)							
Guadalupe Gonzalez									
106445		Office			8/23/2013		24		\$0.00
Medium	Work In Progress			8/23/2013 8:36:36 AM					
Gonzales, Camilo		PLEASE DELIVER 54 BOXES MATH MATERIALS GRADES 3-6							
Larry Martinez									
104815					7/29/2013		49		\$0.00
Medium	Work In Progress			7/29/2013 10:45:19 AM					
Carbajal, Jimmy		NEED HURRICAN BLOWER REPAIRED							
Jesus Estrada									
106408		Classroom			8/22/2013		25		\$0.00
Medium	Work In Progress	Lower Grade		8/22/2013 2:15:14 PM					
Lara, Ralph		Per parent complaint: Need to check the bathroom stalls some don't have doors.							
Guadalupe Gonzalez									
107114		Custodial			9/5/2013		11		\$0.00
Medium	Work In Progress			9/5/2013 10:00:03 AM					
Carbajal, Jimmy		Hi Jimmy, one of our extractor carpet cleaners is leaking from the bottom it has a plastic angle that is broken in which a hose goes connected to. If you could help us out with that I would appreciate it. Thank you.							
Israel Ortega									
107116		Custodial			9/5/2013		11		\$0.00
Medium	Work In Progress			9/5/2013 10:03:26 AM					
Carbajal, Jimmy		Hi Jimmy, we have another extractor carpet cleaner broken this one is not spraying the water and soap mixture on to the carpet and you can't hear the pump working. If you could help us out with that one too we would appreciate it. Thank you							
Israel Ortega									
107421		Office			9/13/2013		3		\$0.00
Medium	Work In Progress			9/13/2013 11:19:49 AM					
Gonzales, Camilo		PLEASE DELIVER 20 BOXES AND 6 BOOKS TO DESERT VIEW ELEM. OF K-2 SE BOOKS 13-14 MATH ADOPTION							
Larry Martinez									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
106701					8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 8:23:55 AM					
Ortiz, Ruben	lower level girls and boys bathroom panels and doors are corroded and need to be replaced.								
Ruben Ortiz									
106944					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:56 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
105337					8/4/2013	8/10/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:05 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
107211					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:07 AM					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
104961					7/31/2013		47		\$0.00
Medium	Work In Progress			7/31/2013 8:06:23 AM					
Gonzalez, Salvador	Need to install chains to close the gates to the side entrance of the school. Thank you, Ruben								
Ruben Ortiz									
104962					7/31/2013		47		\$0.00
Medium	Work In Progress			7/31/2013 8:07:41 AM					
Gonzalez, Salvador	Vandalism; need a new library stand the was destroyed in vandalism. Thank you, Ruben								
Ruben Ortiz									
106745	Main Building	Football Field			8/29/2013		18		\$0.00
Medium	Work In Progress	Soccer		8/29/2013 2:13:50 PM					
Ortiz, Ruben	Talked to Ralph Gallegos about 15 minutes ago. Requesting that someone come down and chalk our soccer field with lines. It has become a hazard because kids are playing outside the field. And when kicking the ball, the ball hits another student in the head. With a chalk the kids know the boundaries. Thank you very much								
Albert Ortiz									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Desert View ES							
107332	Main Building	Restroom (Boys)			9/11/2013		5		\$0.00
Medium	Work In Progress				9/11/2013 7:44:44 AM				
Ontiveros, Joe		Need to Rework on Toilet in boys RRM in Lower grade Level Lecking water agian.							
Joe Ontiveros									
Count: 55 Work Orders		Avg. Age of WO's 32		Total for Desert View ES				0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
106754		Electrical Room			8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 3:37:47 PM					
Castillo, Carlos		Need to order lumber for storage shelving.							
Carlos Castillo									
105830					8/11/2013	8/27/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:47 AM					
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
107219					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:11 AM					
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
105463					8/6/2013		41		\$0.00
Medium	Work In Progress			8/6/2013 8:32:36 AM					
Moncayo, Fernando		C-WING, MRS. CASILLAS A/C NEEDS TO BE CAWLKED ETC. A NEW UNIT WAS PLACED.							
Maritza Gonzalez									
105626					8/7/2013		40		\$0.00
Medium	Work In Progress			8/7/2013 3:42:47 PM					
Moncayo, Fernando		8/17/13-1-ckd bldgs, 2-105481, 2.5-105451, 1.5-applied roundup on weeds, 1-daily work log							
Fernando Moncayo									
106824					8/30/2013		17		\$0.00
High	Work In Progress			8/30/2013 4:28:45 PM					
Moncayo, Fernando		please remove all sand from parking lots. thank you							
Richard Chavez									
106718					8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 10:35:13 AM					
Moncayo, Fernando		PLEASE PATCH UP HOLES IN WENDY TAYLOR AND LUZ AVILA OFFICE.							
Maritza Gonzalez									
106720					8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 10:35:57 AM					
Moncayo, Fernando		PLEASE PATCH UP HOLES IN GEORGE MANRIQUEZ OFFICE.							
Maritza Gonzalez									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
106893					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:37 AM					
Moncayo, Fernando	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106894					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:37 AM					
Moncayo, Fernando	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107237					9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 11:25:19 AM					
Moncayo, Fernando	work order to have the ceiling lights in Eloisa and Georgina's office replaced								
<u>Maritza Gonzalez</u>									
107159					9/6/2013		10		\$0.00
Medium	Work In Progress			9/6/2013 9:36:49 AM					
Moncayo, Fernando	INSTALL 2 OVERHEAD CABINETS IN SNP OFFICES. THANK YOU								
<u>Maritza Gonzalez</u>									
107163					9/6/2013		10		\$0.00
Medium	Work In Progress			9/6/2013 9:51:03 AM					
Moncayo, Fernando	C-WING-NEED TO REPLACE SEVERAL FLOURESCENT LIGHTS REPLACED IN HALLWAY								
<u>Maritza Gonzalez</u>									
106954					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:30:00 AM					
Moncayo, Fernando	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107396					9/12/2013		4		\$0.00
Medium	Work In Progress	Fed. Progs.		9/12/2013 10:52:08 AM					
Gonzales, Camilo	From PO # 111207825 - Please deliver 5 projectors to Technology Dept. attn: Cora Ramirez or contact Sandra								
<u>Sandra Almeraz</u>									
105331					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:02 AM					
Munoz, Michael	Yearly - GAC Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
107288					9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 10:23:03 AM					
Lara, Ralph	I need to place a work order to have name plates made for the following individuals:								
	Lucia Almeraz Linda Castro Mary A. Chavez Luz Garcia								
	Thank you.								
	Anne De Los Santos								
Maritza Gonzalez									
104973					7/31/2013		47		\$0.00
Medium	Work In Progress			7/31/2013 11:01:11 AM					
Rodriguez, Arturo	As per Rosy Villalobos, needs furniture moved in her office.								
Maritza Gonzalez									
104127					7/9/2013		69		\$0.00
Medium	Work In Progress			7/9/2013 2:31:32 PM					
Rodriguez, Arturo	HUMAN RESOURCES WING - PLEASE MOP/WAX OFFICES.								
Maritza Gonzalez									
105820					8/11/2013	9/11/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:43 AM					
Moncayo, Fernando	Yearly - GAC A-9 Air Cooled Condensor Yearly - Refer to PM schedule details.								
Margret Villalobos									
107503					9/16/2013		0		\$0.00
Medium	Work In Progress			9/16/2013 1:28:18 PM					
Ambriz, Jose	A/C UNIT NOT WORKING IN C-WING								
Cora Ramirez									
106359					8/21/2013		26		\$0.00
Medium	Work In Progress			8/21/2013 3:32:02 PM					
Castillo, Carlos	Check existing security door electrical system wiring for reconnection of security doors.								
Carlos Castillo									
107153		Electrical Room			9/6/2013		10		\$0.00
Medium	Work In Progress			9/6/2013 8:01:26 AM					
Castillo, Carlos	Install electrical service to maintance morgon storage building.								
Carlos Castillo									
9/16/2013 4:20:15 PM									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
106778		Electrical Room			8/30/2013		17		\$0.00
Medium	Work In Progress				8/30/2013 7:24:47 AM				
Castillo, Carlos		Order material and equipment for maintanance storage morgon electrical installation.							
Carlos Castillo									
104452					7/18/2013		60		\$0.00
Medium	Work In Progress				7/18/2013 9:00:12 AM				
Ontiveros, Joe		SEWER VENT ON ROOF FALLING.							
Maritza Gonzalez									
Count: 25 Work Orders		Avg. Age of WO's	23			Total for GAC	0		\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
Location:		GAC - Pre-K							
106574					8/27/2013		20		\$0.00
Medium	Work In Progress				8/27/2013 1:16:12 PM				
Moncayo, Fernando	PRE-K, work order for the installation of a loft in room 102 with Ms. Martha Valtierra. If possible this Friday, Aug. 30th when we do not have students, if not either September 13th or 27th which are also days when we do not have students. Thank you!								
	Nancy Bellagamba								
Maritza Gonzalez									
Count: 1 Work Orders	Avg. Age of WO's		20	Total for GAC - Pre-K		0	\$0.00		

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden ES							
106188		Classroom			8/19/2013		28		\$0.00
Medium	Work In Progress	wk room in		8/19/2013 8:09:27 AM					
Medina, Eric	back in March there was a break in in the Washington Wk room... windows were broken and so were the blinds... we got the windows fixed... but now we need the blinds to be replaced... please need assistance in this matter... thank you....								
<u>Loraine Gandara</u>									
106890					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:36 AM					
Medina, Eric	Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106891					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:36 AM					
Medina, Eric	Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106892					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:36 AM					
Medina, Eric	Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107217					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:11 AM					
Medina, Eric	Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105309					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:53 AM					
Munoz, Michael	Yearly - Gadsden ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106955					9/1/2013	9/12/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:30:01 AM					
Medina, Eric	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107423		Custodial			9/13/2013		3		\$0.00
Medium	Work In Progress			9/13/2013 11:40:17 AM					
Solis, Lorenzo	air is not working in the communications room								
<u>Jose Pinion</u>									
9/16/2013 4:20:15 PM									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Gadsden ES								
104416					7/17/2013		61		\$0.00	
Medium	Work In Progress			7/17/2013 11:02:33 AM						
Pinion, Jose	asp Ms. Marquez... need all the vents to please be cleaned thru out the school... thank you greatly....									
<u>Loraine Gandara</u>										
107295		Football Field			9/10/2013		6		\$0.00	
Medium	Work In Progress			9/10/2013 1:03:59 PM						
Carrasco, Danny	need assistance with weeds being cut.... please assist thank you....									
<u>Loraine Gandara</u>										
107496		Custodial			9/16/2013		0		\$0.00	
Medium	Work In Progress			9/16/2013 11:26:02 AM						
Carrasco, Danny	In the kitchen they had a water leak need to change sealing tile and hallways of the school									
<u>Jose Pinion</u>										
106191		Classroom			8/19/2013		28		\$0.00	
Medium	Work In Progress	all classrooms		8/19/2013 8:42:36 AM						
Carrasco, Danny	need assistance with hanging file wall storages in every classroom... thank you greatly appreciate your assistance in this matter....									
<u>Loraine Gandara</u>										
104967		Library			7/31/2013		47		\$0.00	
Medium	Work In Progress			7/31/2013 9:14:16 AM						
Carrasco, Danny	need assistance in hanging up some cork strips in the library thank you....									
<u>Loraine Gandara</u>										
107107					9/5/2013		11		\$0.00	
Medium	Work In Progress	every classroom		9/5/2013 7:57:21 AM						
Carrasco, Danny	2nd Notice... need assistance in hanging some file folders in the classrooms... this will include drilling on the wall please assist thank you....									
<u>Loraine Gandara</u>										
107293		Football Field			9/10/2013		6		\$0.00	
Medium	Work In Progress			9/10/2013 12:24:02 PM						
Ontiveros, Guadalupe	need assistance with the grass being cut.... please assist thank you....									
<u>Loraine Gandara</u>										
Count: 15 Work Orders			Avg. Age of WO's	20				Total for Gadsden ES	0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
105950					8/13/2013		34		\$0.00
Medium	Work In Progress			8/13/2013 3:24:35 PM					
Ontiveros, Guadalupe	Requested by Mr. Villa-Need the practice fields lined for band rehearsal as soon as possible and to continue up until the middle of November.								
Velia Alarcon									
107495					9/16/2013		0		\$0.00
Medium	Work In Progress			9/16/2013 11:17:58 AM					
Lara, Ralph	Requested by Velia-Four keys are needed of HE114 for room # 345 in Academic Building. Due to the ceiling leaks and water damage the Sp.Ed. Offices will be moved to room 345 and additional keys are needed.								
Velia Alarcon									
106903					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:40 AM					
Herrera, Joel	Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
106906					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:42 AM					
Herrera, Joel	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
106907					9/1/2013	10/2/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:42 AM					
Herrera, Joel	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
105250					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:26 AM					
Herrera, Joel	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
107000		Portables			9/3/2013		8		\$0.00
Medium	Work In Progress	PORT 13		9/3/2013 11:11:05 AM		9/11/2013			
Herrera, Jaime	MOVE ITEMS FROM PORTABLE 13 TO DIFFERENT LOCATIONS ON CAMPUS. PLEASE SEE JAIME								
Cathy Ramos	All items were removed from portable.								

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
104916					7/30/2013		48		\$0.00
Medium	Work In Progress			7/30/2013 12:55:58 PM					
Solis, Lorenzo	Need assistance to trouble shoot A/C's on the Old English no communication.								
<u>Guillermo Hernandez</u>									
107333					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 8:28:43 AM					
Ambriz, Jose	Requested by Mr. Mora Rm. 403 Athletic Training Room -The ice machine is not functioning and not producing ice.								
<u>Velia Alarcon</u>									
107034					9/3/2013		13		\$0.00
Medium	Work In Progress			9/3/2013 3:52:55 PM					
Ambriz, Jose	Need to replace exhaust fan motors in the weight room (Jose has sample motor).								
<u>Guillermo Hernandez</u>									
104512					7/19/2013		59		\$0.00
Medium	Work In Progress			7/19/2013 7:45:38 AM					
Ambriz, Jose	Need to replace sensor to ice maker in the Administration building, teacher lounge.								
<u>Guillermo Hernandez</u>									
105469					8/6/2013		41		\$0.00
Medium	Work In Progress			8/6/2013 9:25:16 AM					
Ambriz, Jose	Requested by Staff in Academic Building-Water fountain near boy's restroom closest to cafeteria is not working.								
<u>Velia Alarcon</u>									
105909					8/13/2013		34		\$0.00
Medium	Work In Progress			8/13/2013 8:54:59 AM					
Marquez, Gerardo	Please locate and install two (2) metal doors at the shed east of the green house at Gadsden High School. Installation to include hardware and should be completed by August 27, 2013. For questions or more information please contact Mr. Ralph Gallegos at 575-882-6921.								
<u>Dominique Esparza</u>									
107204					9/8/2013		8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:04 AM					
Hernandez, Guillermo	Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
105808					8/11/2013	9/11/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:38 AM					
Hernandez, Guillermo	Yearly - Gadsden HS A9 (Air Condnsr)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107456					9/15/2013		1		\$0.00
Medium	Work In Progress			9/15/2013 12:17:47 AM					
Villalobos, Margret	Monthly - Gadsden HS - PC Automated Quarterly - Refer to PM schedule details.				9/16/13	Emailed Aide			
<u>Margret Villalobos</u>									
106843					9/1/2013	9/4/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:16 AM					
Hernandez, Guillermo	Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105217					8/4/2013	8/7/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:11 AM					
Herrera, Joel	Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105910					8/13/2013		34		\$0.00
Medium	Work In Progress			8/13/2013 9:04:18 AM					
Sotelo, Enrique	Please locate and install two (2) light fixtures at the shed east of the green house at Gadsden High School. Use 4' florescent lamps either 2 or 4 bulb. Lights should be completed by August 27, 2013 OR after new roof is installed. For questions or information on locates please contact Mr. Ralph Gallegos at 575- 882-6921.								
<u>Dominique Esparza</u>									
104583					7/22/2013		56		\$0.00
Medium	Work In Progress			7/22/2013 3:49:21 PM					
Villalobos, David	Need to replace gasket to shower in the Sped classroom at the Annex building.								
<u>Guillermo Hernandez</u>									
104585					7/22/2013		56		\$0.00
Medium	Work In Progress			7/22/2013 3:51:40 PM					
Villalobos, David	Need to replace circulating pump on water heater that supplies water for the teacher's restroom at Academic building.(boiler room)								
<u>Guillermo Hernandez</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
105840					8/12/2013		35		\$0.00
Medium	Work In Progress				8/12/2013 7:42:09 AM				
Villalobos, David	Need assistance to check all gas regulators.								
Guillermo Hernandez									
104733					7/25/2013		53		\$0.00
Medium	Work In Progress				7/25/2013 11:52:51 AM				
Villalobos, David	Please install gas line for the new refrigeration unit on the band room, Annex building.								
Guillermo Hernandez									
107321					9/10/2013		6		\$0.00
Medium	Work In Progress				9/10/2013 3:47:02 PM				
Sotelo, Enrique	Need to connect electric wires to welder machines, material is in the welding shop.								
Guillermo Hernandez									
106845					9/1/2013		15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:17 AM				
Munoz, Michael	Monthly - Gadsden HS - Grease Trap (Culinary/Auto) - Refer to PM schedule details.								
Margret Villalobos									
107058					9/4/2013		12		\$0.00
Medium	Work In Progress				9/4/2013 12:02:49 PM				
Sotelo, Enrique	Light fixture on the marquee is broken on the terminal and is burning the lamps, light fixture needs to be replaced.								
Guillermo Hernandez									
107395					9/12/2013		4		\$0.00
Medium	Work In Progress				9/12/2013 10:51:15 AM				
Sotelo, Enrique	CAFETERIA - WATER LEAK ON ROOF ABOVE "ON THE BUN" SERVING LINE								
Maritza Gonzalez									
105328					8/4/2013		43		\$0.00
Medium	Work In Progress				8/4/2013 12:20:01 AM				
Munoz, Michael	Yearly - Gadsden HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
106631					8/27/2013		20		\$0.00
Medium	Work In Progress				8/27/2013 4:00:30 PM				
Gonzalez, Salvador	Need to weld metal base to install smart board in Portable #2.								
Guillermo Hernandez									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
107493					9/16/2013		0		\$0.00
Medium	Work In Progress			9/16/2013 11:07:13 AM					
Gonzales, Camilo	Requested by Marie Acosta-10 boxes need to be picked up and sent to Tracy at the Warehouse.								
<u>Velia Alarcon</u>									
107226					9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 9:27:23 AM					
Gonzalez, Salvador	Requested by Coach Bailey for Boys Gym-The basketball goal on the south end (Main Court) needs to be changed out.								
<u>Velia Alarcon</u>									
107324					9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 3:49:14 PM					
Gonzalez, Salvador	Need to install expanded metal plates to the openings of transformers by the treatment plant. size 6inch x 20 inch (6 total).								
<u>Guillermo Hernandez</u>									
107355					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 11:02:08 AM					
Carbajal, Jimmy	I got two NSS wet and dries that are obsolete and need to be removed.								
<u>Jaime Herrera</u>									
107356					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 11:04:08 AM					
Carbajal, Jimmy	I got two red dollies that need there tires replaced.								
<u>Jaime Herrera</u>									
105935					8/13/2013		34		\$0.00
Medium	Work In Progress			8/13/2013 2:37:28 PM					
Munoz, Michael	Requested by Coach Yanez for Baseball Cages-Spoke with Mike Munoz regarding removing old batting cage frames and replacing with fence.								
<u>Velia Alarcon</u>									
107249		Lift Station			9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 1:53:29 PM					
Carrasco, Danny	need to refill the diesel generator at GHS Waste water treatment plant To keep running Until power is restored								
Mario Apodaca									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
105060					8/1/2013		46		\$0.00
Medium	Work In Progress			8/1/2013 1:53:41 PM					
Estrada, Jesus	Requested by Matt Grubaugh for Library-There are multiple places where the carpet is coming ut. They need to be fixed before someone trips on them. This is on going problem.								
<u>Velia Alarcon</u>									
106949					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:58 AM					
Herrera, Joel	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106999		Portables			9/3/2013		13		\$0.00
Medium	Work In Progress	PORT / 13		9/3/2013 11:09:27 AM					
Hernandez, Guillermo	TRAILER REQUEST TO BE ABLE TO MOVE ITEMS FROM PORTABLE 13 TO DIFFERENT LOCATIONS ON CAMPUS.								
<u>Cathy Ramos</u>									
106715	Boys Gym	Custodial			8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 10:18:57 AM					
Lara, Ralph	The custodial door in the boys gym (girls locker room) needs to be replaced cause of all the holes it has in it.								
<u>Jaime Herrera</u>									
106717	Boys Gym	Custodial			8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 10:29:42 AM					
Lara, Ralph	The custodial door in the boys gym (football locker room) needs some kind of support on it cause if you pull the door, it bows out and opens.								
<u>Jaime Herrera</u>									
106716	Boys Gym	Custodial			8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 10:25:46 AM					
Lara, Ralph	There is no door handle on the custodial door in the boys gym (girls locker room) and we can not store any supplies in there cause it always ends up missing. I need it fixed ASAP cause next sometime next week I will be a custodian for that area and he needs that closet to store his supplies in order to clean the area. (Key # m200)								
<u>Jaime Herrera</u>									
106976	Cafeteria (1998)				9/3/2013		13		\$0.00
Medium	Work In Progress			9/3/2013 8:16:34 AM					
Hernandez, Guillermo	Replace light bulbs in Cafeteria ceiling.								
<u>Jaime Herrera</u>									
9/16/2013 4:20:16 PM									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
105231					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:17 AM					
Hernandez, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107089					9/4/2013		12		\$0.00
Medium	Work In Progress			9/4/2013 3:52:26 PM					
Ronquillo, Ruben	Need to replace broken wire glass at the entrance door for the Old main building size (24 inch x 36 inch) and one regular glass on window of North building #226 (size 31 3/4 x 14 1/2).								
<u>Guillermo Hernandez</u>									
107108		Pool			9/5/2013		11		\$0.00
Medium	Work In Progress			9/5/2013 8:54:25 AM					
Gonzalez, Salvador	9/5/13 We need a welder to repair the stainlees steel recirculating channel where some of the seams are leaking								
<u>Raul Sanchez</u>									
106135					8/16/2013		31		\$0.00
Medium	Work In Progress			8/16/2013 8:50:03 AM					
Orozco, Daniel	kitchen-ladies restroom – toilet, has a crack in the bottom. It is leaking out water and the exhaust does not work.								
<u>Maritza Gonzalez</u>									
107235					9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 11:21:25 AM					
Orozco, Daniel	Hobart chopper - it will not turn on the shredding attachment. SNP Manager Frances B. 882.5522								
<u>Maritza Gonzalez</u>									
107236					9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 11:22:18 AM					
Orozco, Daniel	Univex mixer – it has a very loud noise on the shredding attachment. SNP Manager Frances B. 882.5522								
<u>Maritza Gonzalez</u>									
106932					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:51 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

106933					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:51 AM					
Sanchez, Raul	Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.								

Margret Villalobos

105305					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:52 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								

Margret Villalobos

105981					8/14/2013		33		\$0.00
Medium	Work In Progress			8/14/2013 12:16:36 AM					
Sanchez, Raul	Monthly - Gadsden HS- Filters (Pump Rm) Quarterly - Refer to PM schedule details.								

Margret Villalobos

105896					8/12/2013		35		\$0.00
Medium	Work In Progress	LINE LOCATE		8/12/2013 4:12:18 PM					
Sanchez, Raul	W1308121357340 FROM N. MAIN ST & WASHINGTON ST IN ANTHONY, GO W ON WASHINGTON ST FOR 1.70 MI TO LEVEE RD. LOCATE A 100' RADIUS AT THE CONCRETE SPILLWAY LOCATED ON THE SOUTHEAST SIDE OF THE RIVER								

Company: TRIPLE J EXCAVATION
 Contact Name: ANNETTE GRANADO
 Contact Phone: (575)527-1763

Alfredo Holguin

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

104094 7/8/2013 70 \$0.00

Medium Work In Progress LINE LOCATE 7/8/2013 3:02:41 PM

Sanchez, Raul

FROM N MAIN ST & WASHINGTON ST IN
ANTHONY, GO W ON WASHINGTON ST
FOR 1.70 MI TO
LEVEE RD, LOCATE ENTIRE LENGTH &
WIDTH OF BRIDGE
ON WASHINGTON ST TO INCLUDE ALL
OF THE AREA UNDERNEATH THE BRIDGE AS
WELL

Company: TRIPLE J EXCAVATION
Contact Name: ANNETTE GRANADO
Contact Phone: (575)527-1763

Alfredo Holguin

107253 9/9/2013 7 \$0.00

Medium Work In Progress 9/9/2013 2:16:38 PM

Apodaca, Mario

Wastewater treatment plant Power outage Transformers
Fuse burnt out running on back up generator

Mario Apodaca

104772 7/26/2013 52 \$0.00

Medium Work In Progress 7/26/2013 10:51:44 AM

Holguin, Alfredo

Football field artificial Turf - Perform G-max Testing

Alfredo Holguin

107117 9/5/2013 11 \$0.00

Medium Work In Progress 9/5/2013 10:10:08 AM

Hernandez, Guillermo

Requested by Mr. Kiolbasa Rm. 301 Academic Building-
Light bulbs need replacing at the front of the room.

Velia Alarcon

107225 9/9/2013 7 \$0.00

Medium Work In Progress 9/9/2013 9:19:42 AM

Hernandez, Guillermo

Requested by Mrs. L. Melendrez-Room number plate
has fallen off. Please glue it back on the outside wall.

Velia Alarcon

107238 9/9/2013 7 \$0.00

Medium Work In Progress 9/9/2013 11:45:18 AM

Hernandez, Guillermo

Requested by Mrs. Lerma Rm. 105 Main Building-Fridge
handle is broken and a cabinet handle fell off.

Velia Alarcon

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
107240					9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 12:47:37 PM					
Hernandez, Guillermo	Requested by Maria D. J. Grubaugh for New Admin Building-Need to hang up "Teacher of the Year" plaque. SEE MARIA FOR LOCATION.								
<u>Velia Alarcon</u>									
106895					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:37 AM					
Hernandez, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106785					8/30/2013		17		\$0.00
Medium	Work In Progress			8/30/2013 9:09:39 AM					
Hernandez, Guillermo	Requested by Velia for Rm. 343 Faculty Restroom in Academic Building-The exhaust fan has given out and needs to be replaced.								
<u>Velia Alarcon</u>									
106789					8/30/2013		17		\$0.00
Medium	Work In Progress			8/30/2013 9:25:14 AM					
Hernandez, Guillermo	Requested by Mr. Martinez for Football Field-Need to replace missing sign and vandalized sign.								
<u>Velia Alarcon</u>									
107492					9/16/2013		0		\$0.00
Medium	Work In Progress			9/16/2013 11:03:17 AM					
Hernandez, Guillermo	Requested by Mr. Martinez-Install a solid wall to block traffic between Main Building and Old English Building. SEE MEMO HERNANDEZ FOR FURTHER INSTRUCTION.								
<u>Velia Alarcon</u>									
105386					8/5/2013		42		\$0.00
Medium	Work In Progress			8/5/2013 11:42:15 AM					
Miranda, Danny	AS PER SNP MANAGER, THERE ARE HOLES IN STORAGE ROOM WALL. SNP MANAGER FRANCES B. 882.5522								
<u>Maritza Gonzalez</u>									
107286	Academic Bldg	Classroom			9/10/2013		6		\$0.00
Medium	Work In Progress	315		9/10/2013 9:45:42 AM					
Lara, Ralph	Requested by Ms. Jurus-Door handle is getting stuck up and is hard to open.								
<u>Velia Alarcon</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
107491	Main Building				9/16/2013		0		\$0.00
Medium	Work In Progress			9/16/2013 10:57:51 AM					
Hernandez, Guillermo	Requested by Ms. Lam for Rm. 109 C in Main Building- The light bulb in the Women's Faculty Restroom needs to be replaced.								
<u>Velia Alarcon</u>									
105583	Nursing Center				8/7/2013		40		\$0.00
Medium	Work In Progress			8/7/2013 11:27:47 AM					
Ontiveros, Guadalupe	Requested by Mr. D. Martinez for Parking Area next to Nurse's Office-Requesting parking stops to be added to parking spaces from Nurse's Office area to Cafeteria area. PLEASE SEE MR. MARTINEZ FOR FURTHER INSTRUCTION.								
<u>Velia Alarcon</u>									
107130	Pool Pump	Pool			9/5/2013		11		\$0.00
Medium	Work In Progress			9/5/2013 3:11:42 PM					
Sotelo, Enrique	Need an electrician to connect power to the newly installed garage door. This job was left out of the specs for the remodel job done by contractors. Thanks, Raul								
<u>Raul Sanchez</u>									
107354	Community	Restroom (Boys)			9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 10:58:30 AM					
Hernandez, Guillermo	Door on the partition in the boys bathroom has fell off and needs to be put back on.								
<u>Jaime Herrera</u>									
107422	New Admin Bldg	Office			9/13/2013		3		\$0.00
Medium	Work In Progress	Lorraine Soriano		9/13/2013 11:38:02 AM					
Gonzales, Camilo	Please deliver the following items to: Lorraine Soriano PO # 131400405 - 3boxes (shorts, tops & hoodies) - GHS G BASKETBALL								
<u>Terry Alvarado</u>									
107427	New Admin Bldg	Office			9/13/2013		3		\$0.00
Medium	Work In Progress	LORRAINE		9/13/2013 1:26:54 PM					
Gonzales, Camilo	PLEASE DELIVER THE FOLLOWING ITEMS TO: LORRAINE SORIANO PO # 131401187 - 1BOX (TENNIS GRIPS) GHS TENNIS								
Terry Alvarado									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To	Description		Action Taken							
Requester Name										
Location:		Gadsden HS								
107428	New Admin Bldg	Office			9/13/2013		3		\$0.00	
Medium	Work In Progress	LORRAINE			9/13/2013 1:28:35 PM					
Gonzales, Camilo	PLEASE DELIVER THE FOLLOWING ITEMS TO: LORRAINE SORIANO									
	PO # 131400997 - 2BOXES (UNIFORM) = GHS G SOCCER									
Terry Alvarado										
Count: 74 Work Orders			Avg. Age of WO's	21				Total for Gadsden HS	0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
105902	Main Building	Football Field			8/13/2013		34		\$0.00
Medium	Work In Progress			8/13/2013 8:01:14 AM					
Munoz, Michael	I WOULD LIKE TO ORDER A STORAGE SHED FOR HOUSING OUR JOHN DEER GATOR								
<u>Juan Acosta</u>									
104894	Main Building	Classroom			7/30/2013		48		\$0.00
Medium	Work In Progress	Room 124		7/30/2013 8:55:31 AM					
Lara, Ralph	Need a key for filing cabinet, please see Mr. Mora or Mrs. Leslie Leyva.								
<u>Nancy Tinajero</u>									
106407	Annex	Classroom			8/22/2013		25		\$0.00
Medium	Work In Progress	Room 415		8/22/2013 1:35:06 PM					
Diaz, Sebastian	Need Air conditioner please								
<u>Nancy Tinajero</u>									
106140	Annex	Restroom			8/16/2013		31		\$0.00
Medium	Work In Progress	STAFF		8/16/2013 10:16:55 AM					
Marquez, Gerardo	CAN NOT OPEN DOOR WITH KEY A.S.A.P								
<u>Juan Acosta</u>									
106993	Annex	Classroom			9/3/2013		13		\$0.00
Medium	Work In Progress	Room 400		9/3/2013 9:52:23 AM					
Estrada, Jesus	Please remove carpet. The carpet gives off a strong odor. It's about 30-35 years old.								
<u>Nancy Tinajero</u>									
107228	Vocational				9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 10:19:26 AM					
Diaz, Sebastian	please cut weeds and pick-up around vocational building and others as well.								
<u>Richard Chavez</u>									
106581	Gymnasium				8/27/2013		20		\$0.00
Medium	Work In Progress	Concession		8/27/2013 2:06:53 PM					
Marquez, Gerardo	We need locks on four cabinets in the concession stand. Please see Nancy.								
<u>Nancy Tinajero</u>									
106969					9/3/2013		13		\$0.00
Medium	Work In Progress			9/3/2013 12:21:24 AM					
Apodaca, Mario	Monthly - Gadsden MS - Domestic Water Filters - Refer to PM schedule details.								
Margret Villalobos									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
106934					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:52 AM					
Apodaca, Mario	Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106935					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:52 AM					
Apodaca, Mario	Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105387					8/5/2013		42		\$0.00
Medium	Work In Progress			8/5/2013 11:44:20 AM					
Orozco, Daniel	ICE MACHINE NOT WORKING. SNP MANAGER TERRY P. 882.2824								
<u>Maritza Gonzalez</u>									
104947					7/31/2013		47		\$0.00
Medium	Work In Progress			7/31/2013 12:22:49 AM					
Apodaca, Mario	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107504	C-Wing				9/16/2013		0		\$0.00
High	Work In Progress			9/16/2013 1:32:59 PM					
Diaz, Sebastian	Nurses Portable - light fixture above Liza's Desk is full of water.								
<u>Judy Creegan</u>									
106049	C-Wing	Portables			8/15/2013		32		\$0.00
Medium	Work In Progress	ATHletics		8/15/2013 7:32:48 AM					
Diaz, Sebastian	THE ATHLETIC DEPARTMENT WOULD LIKE TO REQUEST AGAIN FOR THE 2 or 3RD TIME, SOME KIND OF PROTECTION PUT ON THE FRONT DOOR TO PREVENT THE WATER FROM COMING IN. CARPET GETS WET EVERYTIME IT RAINS!		9/3/13 - Reroute to Sebastian asp Mike.						
<u>Terry Alvarado</u>									
106738		Gym			8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 1:27:37 PM					
Gonzalez, Salvador	Need to install new scoreboard at gym. (Scoreboard is at Purchasing Warehouse)								
<u>Michael Munoz</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
105324					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:00 AM					
Munoz, Michael	Yearly - Gadsden MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107494		Classroom			9/16/2013		0		\$0.00
Medium	Work In Progress	B wing room 112		9/16/2013 11:11:36 AM					
Sotelo, Enrique	Need Z outlets installed. There is outlets there already but they are covered by plates. Need 1 near computer area and one on back wall.								
<u>Nancy Tinajero</u>									
107301					9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 2:54:04 PM					
Villalobos, David	Need to replace sink on girl's restroom old annex thank you ASP								
<u>Sebastian Diaz</u>									
107049					9/4/2013		12		\$0.00
Medium	Work In Progress	New Annex		9/4/2013 9:31:21 AM					
Villalobos, David	We are still having issues with the sewage odor in our hall. Well we're still experiencing the smell in the afternoons. (Sonia Abler, Teacher)								
<u>Michael Munoz</u>									
106517		Pump House			8/26/2013		21		\$0.00
Medium	Work In Progress			8/26/2013 3:21:04 PM					
Sotelo, Enrique	Need the assistance of the district electrician To replace the switch floats At G M S Water demestic storage tank								
<u>Mario Apodaca</u>									
106740		Gym			8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 1:28:50 PM					
Sotelo, Enrique	Need to hookup electrical to new scoreboard at gym. (Coordinate w/Sal)								
<u>Michael Munoz</u>									
106478					8/23/2013		24		\$0.00
Medium	Work In Progress			8/23/2013 3:41:06 PM					
Solis, Lorenzo	Need to fix two water fountain on B wing thank you								
<u>Sebastian Diaz</u>									
106860					9/1/2013	9/17/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:23 AM					
Villalobos, Margret	Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details.					Sept			
Margret Villalobos						E-mailed Arlene			
9/16/2013 4:20:16 PM									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
105924		Custodial			8/13/2013		34		\$0.00
Medium	Work In Progress			8/13/2013 12:53:11 PM					
Marquez, Gerardo	WE ALSO NEED AN EXTRA KEY MADE FOR OUR NIGHT CUSTODIAN THIS KEY IS FOR THE JOHN DEER GATOR								
Juan Acosta									
104459					7/18/2013		60		\$0.00
Medium	Work In Progress			7/18/2013 9:47:33 AM					
Marquez, Gerardo	Need to check main entrance door by main field thank you								
Sebastian Diaz									
106081		Restroom			8/15/2013		32		\$0.00
Medium	Work In Progress	A and B wing		8/15/2013 1:56:13 PM					
Diaz, Sebastian	Please paint boys and girls restrooms in A and B wing.								
Nancy Tinajero									
107011					9/3/2013		13		\$0.00
Medium	Work In Progress			9/3/2013 1:20:03 PM					
Diaz, Sebastian	please cut weeds and pick-up around buss turnaround and along fence lines. thank you								
Michael Munoz									
106328		Classroom			8/21/2013		26		\$0.00
Medium	Work In Progress	A wing room 164		8/21/2013 10:13:29 AM					
Marquez, Gerardo	Please fix lock to filing cabinet.								
Nancy Tinajero									
107287					9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 10:17:37 AM					
Diaz, Sebastian	Spray and remove weeds on north entrance (band room) for parent teacher conference.								
Nancy Tinajero									
Count: 29 Work Orders			Avg. Age of WO's 23			Total for Gadsden MS	0		\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: La Union ES

106916					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:45 AM					
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
106092					8/15/2013		32		\$0.00
Medium	Work In Progress			8/15/2013 3:17:38 PM					
Aguilar, Patricio	wo to myself - need to replace door hinge girls rest room stall								
Patricio Aguilar									
107360					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 2:53:28 PM					
Aguilar, Patricio	wo to myself - need to replace filter on new ac old hall way								
Patricio Aguilar									
106917					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:46 AM					
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
106918					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:46 AM					
Aguilar, Patricio	Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
106827					8/31/2013		16		\$0.00
Medium	Work In Progress			8/31/2013 12:25:34 AM					
Aguilar, Patricio	Monthly - La Union ES A-16 Fan Exhaust Semimonthly - Refer to PM schedule details.								
Margret Villalobos									
105815					8/11/2013	9/11/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:41 AM					
Aguilar, Patricio	Yearly - La Union ES A-9 Air Cooled Yearly - Refer to PM schedule details.								
Margret Villalobos									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
107469					9/16/2013		0		\$0.00
High	Work In Progress			9/16/2013 7:20:19 AM					
Ontiveros, Joe	need to install sweat copper fittings to copper and cap off to connect domestic to irrigation water for the future. please leave the rest of the material to connect the water in the boiler room to use in case of no water or emergency supply.								
Michael Munoz									
107470					9/16/2013		0		\$0.00
High	Work In Progress			9/16/2013 7:26:03 AM					
Aguilar, Patricio	please make sure all water to fountains are shut off to include outside hose bibs till further notice. thank you								
Michael Munoz									
106942					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:55 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
106448		Custodial			8/23/2013		24		\$0.00
Medium	Work In Progress			8/23/2013 9:00:49 AM					
Carbajal, Jimmy	The bottom plate of the Adfinity shower scubber is not making full contact with the machine itself. Does not spin properly.								
Rudy Ramos									
107361					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 2:58:39 PM					
Gonzalez, Salvador	need to cut metal poles in ground in far back yard - need hand grinder - cutting blade and generator - thanks for the help								
Patricio Aguilar									
105315					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:56 AM					
Munoz, Michael	Yearly - La Union ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
105825					8/11/2013	8/27/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:45 AM					
Aguilar, Patricio	Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		La Union ES							
107209					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress				9/8/2013 12:16:07 AM				
Aguilar, Patricio	Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
107436	Main Building	Mechanical			9/13/2013		3		\$0.00
Medium	Work In Progress				9/13/2013 2:44:55 PM				
Ontiveros, Joe	No Domestic water to school property Cause to County water Service Issues. Tie water well to Domestic water with County Approval. As per Supervisor.								
Joe Ontiveros									
105729	Main Building	Classroom			8/9/2013		38		\$0.00
Medium	Work In Progress				8/9/2013 9:10:44 AM				
Marquez, Gerardo	One of the doors in room 102 needs a cylinder.								
Rudy Ramos									
Count: 17 Work Orders		Avg. Age of WO's 18		Total for La Union ES			0	\$0.00	

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Loma Linda ES

107111	Main Building	Custodial			9/5/2013		11		\$0.00
Medium	Work In Progress				9/5/2013 9:41:34 AM				
Carbajal, Jimmy	NEED SERVICE TO THE VACUUM CLEANER (SILVA) NO POWER ON THE EXTENTION CORD. SERIAL # F07COOOOOO761. THANK YOU.								

Luis Solis									
107112	Main Building	Custodial			9/5/2013		11		\$0.00
Medium	Work In Progress				9/5/2013 9:46:29 AM				
Carbajal, Jimmy	NEED SERVICE FOR THE VACUUM CLEANER (ONTIVEROS)THE MOTOR IS NOT WORKING., SERIAL # EO8COOOOOO464.,THANK YOU.								

Luis Solis									
107113	Main Building	Custodial			9/5/2013		11		\$0.00
Medium	Work In Progress				9/5/2013 9:52:45 AM				
Carbajal, Jimmy	NEED SERVICE TO THE EXTRACTOR (AQUA CLEANER)THE CABLE IS COMING OFF FROM THE HANDLE.,SERIAL # 1378021 ., TAG # OO-02267., THANK YOU.								

Luis Solis									
107115	Main Building	Custodial			9/5/2013		11		\$0.00
Medium	Work In Progress				9/5/2013 10:01:11 AM				
Carbajal, Jimmy	NEED SERVICE TO THE EXTRACTOR (AQUA CLEAN CLASSIC) IS THROING ALOT OF WATER , NOT PROPERLY WHENT THE MACHINE IS ON AND OFF.,SERIAL # 1212249 , TAG # 98-00211., THANK YOU.								

Luis Solis									
106997	Main Building	Office			9/3/2013		13		\$0.00
Medium	Work In Progress	Principals Office			9/3/2013 10:48:31 AM				
Estrada, Jesus	Carpet in the office has a hole, needs to be repaired								

Angie Flores									
105109	Main Building	Restroom			8/2/2013		45		\$0.00
Medium	Work In Progress				8/2/2013 8:04:50 AM				
Villalobos, David	Need to replace remaining wash basins at bys and girls restroom								

David Villalobos									
107012	Main Building	Exterior			9/3/2013		13		\$0.00
High	Work In Progress				9/3/2013 1:34:54 PM				
Medina, Eric	Outer walls on portables and outer walls (South- East) of building were tagged and need to be repainted with matching paint. Case #2013-00531				see 107015				

Jesus Estrada

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
106797	Main Building	Restroom (Boys)			8/30/2013		17		\$0.00
Medium	Work In Progress	In Front of Mrs.		8/30/2013 10:48:44 AM					
Marquez, Gerardo	Stall doors in the boys restroom infront of Mrs. Whites room dont lock								
<u>Angie Flores</u>									
106798	Main Building	Parking Lot			8/30/2013		17		\$0.00
Medium	Work In Progress			8/30/2013 11:09:02 AM					
Medina, Eric	Please remove graffiti on the sign that is in the parking lot, the one that says "Do Not Park between the hours" Thank you!								
<u>Angie Flores</u>									
106202	Main Building	Classroom			8/19/2013		28		\$0.00
Medium	Work In Progress	110		8/19/2013 10:43:28 AM					
Medina, Eric	Change light bulb thake one light bulb out								
<u>Angie Flores</u>									
104902	Main Building	Restroom			7/30/2013		48		\$0.00
Medium	Work In Progress	Teacher		7/30/2013 9:37:00 AM					
Medina, Eric	Toilet not flushing properly leaks water								
<u>Angie Flores</u>									
107044	Main Building	Classroom			9/4/2013		12		\$0.00
Medium	Work In Progress	222		9/4/2013 9:19:05 AM					
Medina, Eric	AC Not Working								
<u>Angie Flores</u>									
107045	Main Building	Classroom			9/4/2013		12		\$0.00
Medium	Work In Progress	209		9/4/2013 9:19:51 AM					
Medina, Eric	AC Not Working								
<u>Angie Flores</u>									
107415	Main Building	Classroom			9/13/2013		3		\$0.00
Medium	Work In Progress	201		9/13/2013 9:34:12 AM					
Medina, Eric	Plaster on cieling by window is falling off								
<u>Angie Flores</u>									
105916	Main Building	Classroom			8/13/2013		34		\$0.00
Medium	Work In Progress	Portable Mr.		8/13/2013 10:30:22 AM					
Medina, Eric	Replace Light Bulbs								
<u>Angie Flores</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
105564	Main Building	Classroom			8/7/2013		40		\$0.00
Medium	Work In Progress	106			8/7/2013 9:09:14 AM				
Medina, Eric	Center light off and light by 2nd door flickering								
Angie Flores									
107218					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress				9/8/2013 12:16:11 AM				
Medina, Eric	Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
106970					9/3/2013		13		\$0.00
Medium	Work In Progress				9/3/2013 12:21:24 AM				
Apodaca, Mario	Monthly - Loma Linda ES - Domestic Water Filters - Refer to PM schedule details.								
Margret Villalobos									
107119					9/5/2013		11		\$0.00
Medium	Work In Progress				9/5/2013 10:14:24 AM				
Orozco, Daniel	EXHAUST FAN IN CHEMICAL ROOM IS NOT WORKING. SNP MANAGER DELORES R. 882.4707								
Maritza Gonzalez									
106887					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:34 AM				
Medina, Eric	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
106888					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:35 AM				
Medina, Eric	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
106889					9/1/2013		15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:35 AM				
Medina, Eric	Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
107342					9/11/2013		5		\$0.00
Medium	Work In Progress				9/11/2013 9:28:56 AM				
Medina, Eric	Please pick up items from SAMS								
Angie Flores									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
105316					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:56 AM					
Munoz, Michael	Yearly - Loma Linda ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
107499					9/16/2013		0		\$0.00
Medium	Work In Progress			9/16/2013 12:11:18 PM					
Ontiveros, Guadalupe	Lupe need to request bobcat for rain erosion								
Eric Medina									
106474					8/23/2013		24		\$0.00
Medium	Work In Progress			8/23/2013 3:28:34 PM					
Gonzalez, Salvador	Chava need a square drag for loma linda thank you								
Eric Medina									
106960					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:30:04 AM					
Medina, Eric	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
104696					7/24/2013		54		\$0.00
Medium	Work In Progress			7/24/2013 3:10:54 PM					
Villalobos, David	David need to replace 6 restroom faucets								
Eric Medina									
105076					8/1/2013		46		\$0.00
Medium	Work In Progress			8/1/2013 3:07:50 PM					
Sotelo, Enrique	Enrique need to replace two broken lights on east side near cafeteria								
Eric Medina									
107363					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 3:06:21 PM					
Solis, Lorenzo	Lorenzo need to replace two waterfountains in 6th grade hall								
Eric Medina									
Count: 30 Work Orders			Avg. Age of WO's	20	Total for Loma Linda ES		0	0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
107277		Custodial			9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 8:02:01 AM					
Marquez, Gerardo	please on the storage supply door knob the key slot is very hard to turn with the key to open it								
Luis Saucedo									
107234					9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 11:03:49 AM					
Solis, Lorenzo	need assistance with the installation of a new water fountain.								
Joe Ramirez									
107392					9/12/2013		4		\$0.00
Medium	Work In Progress			9/12/2013 10:20:17 AM					
Villalobos, David	need to replace back flow preventor in the community park.								
Joe Ramirez									
106246					8/19/2013		28		\$0.00
Medium	Work In Progress			8/19/2013 3:52:32 PM					
Flores, Pete	p.to. on lawnmower 735 (m.e.0421) does not engage needs to be repaired.								
Joe Ramirez									
105289					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:44 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
107191					9/6/2013		10		\$0.00
Medium	Work In Progress			9/6/2013 3:46:53 PM					
Ramirez, Joe	9/6/13. .5 building walk thru. 1.5 marquee. .5 barrack drainage insp. 1.5 exit sign insp. 1.0 sprinkler repair. .5 adj desks. 1.0 work on water fountain. .5 hang banner. .5 clean up		9/6						
Joe Ramirez									
106372					8/21/2013		26		\$0.00
Medium	Work In Progress			8/21/2013 4:14:44 PM					
Ramirez, Joe	Remove piece of broken concrete and replace with new in sidewalk on west side of barrack								
Alfredo Holguin									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
105670					8/8/2013		39		\$0.00
Medium	Work In Progress			8/8/2013 1:02:18 PM					
Flores, Pete	front tire on lawnmower needs to be repaired								
Joe Ramirez									
105671					8/8/2013		39		\$0.00
Medium	Work In Progress			8/8/2013 1:03:55 PM					
Marquez, Gerardo	door and door jamb for rm.608 needs to be replaced it is in really bad shape.								
Joe Ramirez									
105317					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:57 AM					
Munoz, Michael	Yearly - Mesquite ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
106939					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:54 AM					
Apodaca, Mario	Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
106371	Main Building				8/21/2013		26		\$0.00
Medium	Work In Progress			8/21/2013 4:11:47 PM					
Marquez, Gerardo	check door openers for proper operation (less the 5 lbs force to open) in rooms (regular classroom, PE portable, library and other common areas) in door ways that will be used by student with special needs.								
Alfredo Holguin									
107019	Pump House	Pump House			9/3/2013		13		\$0.00
Medium	Work In Progress			9/3/2013 3:26:54 PM					
Marquez, Gerardo	the door to the Pump Room at mesquite elementary needs to be replaced door hinges are broken up and very hard to open								
Mario Apodaca									
106645	2003 Classroom	Classroom			8/28/2013		19		\$0.00
Medium	Work In Progress	Room # 202		8/28/2013 10:16:43 AM					
Marquez, Gerardo	Kelli Coniglio/4th, need her file cabinet opened no key for that file, please re key. Thank you,								
Sandra Mora									
Count: 14 Work Orders		Avg. Age of WO's 23			Total for Mesquite ES			0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
107215					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:10 AM					
Vega, Danny	Monthly - North Valley ES Playground Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106883					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:33 AM					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106082					8/15/2013		32		\$0.00
Medium	Work In Progress			8/15/2013 1:58:27 PM					
Vega, Danny	need replacement exhaust fans motor for boys and girls restrooms by east exit doors. sent sample to re-order- also need fans for classrooms								
<u>Danny Vega</u>									
105318					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:57 AM					
Munoz, Michael	Yearly - North Valley ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106675		Classroom			8/28/2013		19		\$0.00
Medium	Work In Progress	212		8/28/2013 3:32:46 PM					
Vega, Danny	Please install Starboard on wall, please check with teacher for supplies.								
<u>Priscilla Martinez</u>									
106958					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:30:03 AM					
Vega, Danny	Monthly - North Valley ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
104093					7/8/2013		70		\$0.00
Medium	Work In Progress			7/8/2013 2:34:01 PM					
Lara, Ralph	997 diesel mower needs new battery/have to jump start daily/12 volt john deere will not start on its own								
<u>Danny Vega</u>									
107394					9/12/2013		4		\$0.00
Medium	Work In Progress			9/12/2013 10:46:52 AM					
Ontiveros, Guadalupe	need to use bobcat tractor level off rain erosion on playgrounds								
<u>Danny Vega</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
106388					8/22/2013		25		\$0.00
Medium	Work In Progress			8/22/2013 8:52:10 AM					
Vega, Danny	need replacement filters for nve a/c units sizes are on supply order forms								
Danny Vega									
106881					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:32 AM					
Vega, Danny	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
104472					7/18/2013		60		\$0.00
Medium	Work In Progress			7/18/2013 10:56:44 AM					
Villalobos, David	need replacement faucets for rms 301-302 (4 in. centers) gooseneck spout two handle type (2ea.)								
Danny Vega									
105027					8/1/2013		46		\$0.00
Medium	Work In Progress			8/1/2013 8:05:12 AM					
Sotelo, Enrique	emergency lamp ballast are out in mechanical rms by rms 102-104-210-208-203 total of 5 ea. please replace								
Danny Vega									
107393					9/12/2013		4		\$0.00
Medium	Work In Progress			9/12/2013 10:43:03 AM					
Sotelo, Enrique	emergency ballast lamp is out in rm 103 .please replace								
Danny Vega									
104931		Classroom			7/30/2013		48		\$0.00
Medium	Work In Progress	101		7/30/2013 3:37:54 PM					
Marquez, Gerardo	Please send locksmith, having trouble with 1 beige file cabinet lock.								
Priscilla Martinez									
105550					8/7/2013		40		\$0.00
Medium	Work In Progress			8/7/2013 7:46:50 AM					
Marquez, Gerardo	NEED GATE KEY FOR EL PASO DISPOSAL. PLEASE GIVE TO MARY SITTERS. THANKS								
Jesus Estrada									
Count: 15 Work Orders			Avg. Age of WO's	30	Total for North Valley ES			0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
106882					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:32 AM					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106959					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:30:03 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105333					8/4/2013	8/15/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:03 AM					
Munoz, Michael	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106884					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:33 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107216					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:10 AM					
Vega, Danny	Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107285	Main Building	Hallway/Corridor			9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 8:52:57 AM					
Villalobos, David	HALLWAY WATER FOUNTAIN (NEAR BOILER ROOM) IS ARCHING TO HIGH AND LANDING ON THE WALL/FLOOR.								
<u>Adam Montoya</u>									
105965	Main Building				8/13/2013		34		\$0.00
High	Work In Progress			8/13/2013 3:52:10 PM					
Vega, Danny	Daycare - please paint rooms 112,114 first and then proceed to 108 & 110. Please call mike for details.								
	thank you								
Alfredo Holguin									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Northern On-Track Pre-K (LM)									
105992	Main Building	Mechanical			8/14/2013		33		\$0.00
Medium	Work In Progress				8/14/2013 10:31:53 AM				
Miranda, Danny	ATTN. Danny Miranda; make ceiling opening larger to be able to work on air relief vent.								
<u>Lorenzo Solis</u>									
104543	Main Building	Roof			7/19/2013		59		\$0.00
Medium	Work In Progress				7/19/2013 3:50:28 PM				
Vega, Danny	NEED SHINGLES ON WEST END OF ROOF REPLACED. DAMAGED AND LEAKING ONTO CEILING TILES.								
<u>Adam Montoya</u>									
Count: 9 Work Orders			Avg. Age of WO's	25	Total for Northern On-Track Pre-K (LM)			0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
105409					8/5/2013		42		\$0.00
Medium	Work In Progress			8/5/2013 2:28:23 PM					
Gonzalez, Salvador	Vehicle # 64 - install metal plating, floor and sides - Check with Enrique on specifics								
Enrique Briones									
104499					7/18/2013		60		\$0.00
Medium	Work In Progress			7/18/2013 3:31:09 PM					
Apodaca, Mario	Low water pressure in Men's Restroom								
Rafael Gallegos									
104080	Motor Vehicle				7/8/2013		70		\$0.00
Medium	Work In Progress			7/8/2013 9:02:41 AM					
Holguin, Alfredo	Fueling Station - Perform annual leak detector testing								
Alfredo Holguin									
104728	Motor Vehicle				7/25/2013		53		\$0.00
Medium	Work In Progress	5510 tractor		7/25/2013 10:19:26 AM					
Flores, Pete	tractor's warning lights are inoperative, and fuel gage is inaccurate. please check.								
Pete Flores									
104631	Motor Vehicle				7/23/2013		55		\$0.00
Medium	Work In Progress	vehicle#81		7/23/2013 3:13:18 PM					
Flores, Pete	left front outrigger leaking excessive hydraulic oil. please check and advise.								
Pete Flores									
107353	Motor Vehicle				9/11/2013		5		\$0.00
Medium	Work In Progress	vehicle#133		9/11/2013 10:42:39 AM					
Flores, Pete	please service vehicle as needed and check serpentine belt tensioner.								
Pete Flores									
107366	Motor Vehicle				9/11/2013		5		\$0.00
Medium	Work In Progress	#103		9/11/2013 3:26:36 PM					
Flores, Pete	Please check brakes on car 103, the brake goes all the way down on it (losing pressure?). Thank you								
Sandra Almeraz									
107299	Motor Vehicle				9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 2:16:07 PM					
Flores, Pete	vehicle #103 doesn't start								
Sandra Almeraz									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
107449	Motor Vehicle				9/13/2013		3		\$0.00
Medium	Work In Progress	vehicle#08			9/13/2013 3:50:41 PM				
Flores, Pete		please check for service and perform any required maintenance.							
<u>Pete Flores</u>									
107093	Motor Vehicle				9/4/2013		12		\$0.00
Medium	Work In Progress	vehicle#135			9/4/2013 3:59:57 PM				
Flores, Pete		please check for any required maintenance and service accordingly							
<u>Pete Flores</u>									
107098	Motor Vehicle				9/4/2013		12		\$0.00
Medium	Work In Progress	vehicles			9/4/2013 4:14:48 PM				
Flores, Pete		prepare vehicles according to daily trip schedule.also check left turn signal on vehicle#168							
<u>Pete Flores</u>									
107120	Motor Vehicle				9/5/2013		11		\$0.00
Medium	Work In Progress	vehicle#146			9/5/2013 11:08:34 AM				
Flores, Pete		vehicle's tires weatherbeaten and in need of replacement.							
<u>Pete Flores</u>									
104418	Motor Vehicle				7/17/2013		61		\$0.00
Medium	Work In Progress	Vehicle #44			7/17/2013 11:09:58 AM				
Flores, Pete		check and advise vehicle lost serpentine belt,possibly damaged water pump.							
<u>Pete Flores</u>									
107010	Motor Vehicle	Restroom			9/3/2013		13		\$0.00
Medium	Work In Progress				9/3/2013 1:19:34 PM				
Diaz, Sebastian		lights in restroom keep flickering.							
<u>Maria Ruiz</u>									
105467	Motor Vehicle				8/6/2013		41		\$0.00
Medium	Work In Progress	997-z-trac			8/6/2013 9:02:48 AM				
Flores, Pete		need battery replaced on 997 mower located at north valley elem. tag#5602706							
<u>Pete Flores</u>									
105069	Motor Vehicle				8/1/2013		46		\$0.00
Medium	Work In Progress	vehicle#168			8/1/2013 2:12:10 PM				
Flores, Pete		please check vehicle for any scheduled maintenance.							
<u>Pete Flores</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
104981	Motor Vehicle				7/31/2013		47		\$0.00
Medium	Work In Progress	vehicle#194		7/31/2013 1:27:31 PM					
Flores, Pete	please service vehicle as needed and install side steps.								
<u>Pete Flores</u>									
107151	Purchasing	Office			9/6/2013		10		\$0.00
Medium	Work In Progress			9/6/2013 7:53:25 AM					
Flores, Pete	Please replace tires on Vehicle 146.								
<u>Larry Martinez</u>									
104180	Purchasing				7/10/2013		68		\$0.00
Medium	Work In Progress			7/10/2013 2:47:43 PM					
Solis, Lorenzo	Ref Unit is not turning on in office.								
<u>Enrique Briones</u>									
104121	Purchasing	Restroom (Girls)			7/9/2013		69		\$0.00
Medium	Work In Progress			7/9/2013 7:12:04 AM					
Villalobos, David	THE GIRLS BATHROOM IS LEAKING WTER FROM CEILING IN THE RECIEVING WAREHOUSE .								
<u>Jimmy Carbajal</u>									
106142	Purchasing				8/16/2013		31		\$0.00
Medium	Work In Progress	auto shop		8/16/2013 10:43:35 AM					
Ronquillo, Ruben	requesting new shop vac's,magnetic pick-up tool, and bench grinder-to replace worn ones.								
<u>Pete Flores</u>									
106379					8/22/2013		25		\$0.00
High	Work In Progress			8/22/2013 7:31:33 AM					
Carrasco, Danny	bearings to large sewer snake broke. need to replace all 3.								
	Thank you								
<u>Michael Munoz</u>									
106946					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:57 AM					
Diaz, Sebastian	Monthly - Physical Plant FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105865					8/12/2013		35		\$0.00
Medium	Work In Progress			8/12/2013 1:35:30 PM					
Ronquillo, Ruben	Scissor Lift - Repair oil leak								
<u>Alfredo Holguin</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
106038					8/14/2013		33		\$0.00
Medium	Work In Progress				8/14/2013 3:50:55 PM				
Ronquillo, Ruben	REPAIR LEAK,CABLE AND IGNITION SWITCH ON GS -3246 GENIE SCISSOR LIFT.								
Ruben Ronquillo									
105332					8/4/2013		43		\$0.00
Medium	Work In Progress				8/4/2013 12:20:03 AM				
Munoz, Michael	Yearly - Physical Plant Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
107502					9/16/2013		0		\$0.00
Medium	Work In Progress				9/16/2013 1:21:35 PM				
Diaz, Sebastian	Refrigeration Unit - In Julie/Alfredo's office is not working.								
Juliet Parra									
107222					9/9/2013		7		\$0.00
Medium	Work In Progress	TRANSPORTAT			9/9/2013 8:20:14 AM				
Flores, Pete	GENERAL MAINTENANCE ON SUBURBAN #55								
Margaret Villalobos									
106267					8/20/2013		27		\$0.00
Medium	Work In Progress				8/20/2013 8:57:23 AM				
Flores, Pete	SHIFTER IS LOOSE ON VEHICLE #32. NEED TO SET HAND BRAKE, SOMETIMES SHIFTER WILL NOT LOCK. ENGINE IS KNOCKING. THANK YOU								
Ruben Ronquillo									
106505					8/26/2013		21		\$0.00
Medium	Work In Progress	Vehicle 99			8/26/2013 12:45:10 PM				
Flores, Pete	Vehicle 99 is leaking gas.								
Michael Munoz									
106974					9/3/2013		13		\$0.00
Medium	Work In Progress				9/3/2013 8:04:24 AM				
Flores, Pete	Vehicle 138 - AC does not cool very well. check filter								
Alfredo Holguin									
104735					7/25/2013		53		\$0.00
Medium	Work In Progress				7/25/2013 2:09:29 PM				
Ronquillo, Ruben	PURCHASE TIRES AND SWITCHES FOR POLARIS								
Ruben Ronquillo									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
107331					9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 7:33:13 AM					
Lara, Ralph	Rafa, as per Alfredo need a key log for all sites that have been issued key for El Paso Disposal. This information is needed by Mary Sitters. thank you.								
Alfredo Holguin									
106552		Athletic Field			8/27/2013		20		\$0.00
Medium	Work In Progress			8/27/2013 8:41:44 AM					
Marquez, Gerardo	need copies of keys for new fuel cap that was install on John Deere Backhoe L110								
Guadalupe Ontiveros									
106847					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:17 AM					
Munoz, Michael	Monthly - Physical Plant - Grease Trap (Custodial) - Refer to PM schedule details.								
Margret Villalobos									
106265					8/20/2013		27		\$0.00
High	Work In Progress			8/20/2013 8:31:02 AM					
Diaz, Sebastian	Light bulbs need to be replaced in Mr. Gallegos office located in the construction office. Meeting scheduled for this afternoon. If light bulbs can please be replaced by 1:00 pm today, it would be greatly appreciated.								
Dominique Esparza									
Count: 36 Work Orders			Avg. Age of WO's	29	Total for Physical Plant Complex			0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
106011					8/14/2013		33		\$0.00
Medium	Work In Progress			8/14/2013 3:02:09 PM					
Ontiveros, Joe	Please check all restrooms for proper operation around campus for site visit from Congressman Pearce.								
<u>Michael Munoz</u>									
104146					7/9/2013		69		\$0.00
Medium	Work In Progress			7/9/2013 3:49:10 PM					
Castillo, Carlos	need to replace light covers several missing or broken (electrician ordered)								
<u>Carlos Hernandez</u>									
104716					7/24/2013		54		\$0.00
Medium	Work In Progress			7/24/2013 3:47:31 PM					
Ontiveros, Joe	SECURE ALL WATER FOUNTAINS, REMOVE OLD CAULKING AND INSTALL NEW CAULKING (ONLY IF NEEDED)								
<u>Michael Munoz</u>									
106826					8/31/2013		16		\$0.00
Medium	Work In Progress			8/31/2013 12:25:33 AM					
Ambriz, Juan	Monthly - Riverside ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105803					8/11/2013	9/11/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:36 AM					
Hernandez, Carlos	Yearly - Riverside ES A-9 Air Cooled Cond Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107390					9/12/2013		4		\$0.00
Medium	Work In Progress			9/12/2013 7:53:22 AM					
Ontiveros, Guadalupe	need the Bobcat at Riverside Elementary ThankYou!!								
<u>Fernando Moncayo</u>									
106224					8/19/2013		28		\$0.00
Medium	Work In Progress			8/19/2013 3:19:02 PM					
Ontiveros, Guadalupe	main sidewalk needs to be replaced due to rain washed it out				8/30 - Asp Mike, route to Lupe				
<u>Carlos Hernandez</u>									
106659					8/28/2013		19		\$0.00
Medium	Work In Progress			8/28/2013 2:25:15 PM					
Sonora, Miguel	NEED TO SHOWER SCRUB & WAX FLOORS IN REST ROOM BETWEEN ROOMS 503 & 506								
<u>Jesus Estrada</u>									
9/16/2013 4:20:17 PM									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
107303					9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 2:56:25 PM					
Sonora, Miguel	NEED TO SWEEP UNDER BOTH CANOPIES ON A WEEKLY BASIS								
<u>Jesus Estrada</u>									
105254					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:28 AM					
Ambriz, Juan	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105255					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:28 AM					
Ambriz, Juan	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105866		Classroom			8/12/2013		35		\$0.00
Medium	Work In Progress	room 30		8/12/2013 1:44:37 PM					
Ambriz, Juan	air not working (palma)								
<u>Rosa Quezada</u>									
106952					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:59 AM					
Moncayo, Fernando	Monthly - Riverside ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106796					8/30/2013		17		\$0.00
Medium	Work In Progress			8/30/2013 10:33:29 AM					
Carbajal, Jimmy	Por favor si nos pueden reparar una maquina para pulir los pisos								
<u>Miguel Sonora</u>									
107065					9/4/2013		12		\$0.00
Medium	Work In Progress			9/4/2013 2:50:30 PM					
Gonzalez, Salvador	need chain and locks welded to gates								
<u>Carlos Hernandez</u>									
105319					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:57 AM					
Munoz, Michael	Yearly - Riverside ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
105350					8/4/2013	8/10/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:10 AM					
Ambriz, Juan	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
105392					8/5/2013		42		\$0.00
Medium	Work In Progress			8/5/2013 12:44:03 PM					
Orozco, Daniel	AS PER MANAGER OVENS ARE NOT WORKING PROPERLY. SNP MANAGER EMILIA C. 589.2550								
Maritza Gonzalez									
105393					8/5/2013		42		\$0.00
Medium	Work In Progress			8/5/2013 12:44:23 PM					
Orozco, Daniel	AS PER MANAGER EXHAUST NOT WORKING PROPERLY. SNP MANAGER EMILIA C. 589.2550								
Maritza Gonzalez									
107290					9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 10:50:21 AM					
Moncayo, Fernando	Lawn is not being cut consistently.								
Teresa Navarro									
107206					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:05 AM					
Moncayo, Fernando	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
104067					7/7/2013	7/23/2013	71		\$0.00
Medium	Work In Progress			7/7/2013 12:22:52 AM					
Ambriz, Juan	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
105827					8/11/2013	8/27/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:46 AM					
Ambriz, Juan	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
107289					9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 10:47:31 AM					
Hernandez, Carlos	Graffiti under the canopy outside the playground.								
Teresa Navarro									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
107446		Cafeteria			9/13/2013		3		\$0.00
Medium	Work In Progress	CAFETERIA		9/13/2013 3:46:12 PM					
Moncayo, Fernando		INSTALL LARGE BOX IN CAFETERIA (MONCAYO)							
Rosa Quezada									
106868					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:26 AM					
Moncayo, Fernando		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
106869					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:27 AM					
Moncayo, Fernando		Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
107364	Main Building	Classroom			9/11/2013		5		\$0.00
Medium	Work In Progress	room 117		9/11/2013 3:08:01 PM					
Ambriz, Jose		AIR CONDITIONER NOT WORKING SINCE FRIDAY. IT IS VERY HOT AND MAKES UGLY NOISE (JUAREZ)							
Rosa Quezada									
106346	Main Building	Cafeteria			8/21/2013		26		\$0.00
Medium	Work In Progress	cafeteria and		8/21/2013 2:07:10 PM					
Ambriz, Jose		a/c not working in cafeteria and teacher's lounge (Sonora)							
Rosa Quezada									
105476	Main Building	Office			8/6/2013		41		\$0.00
Medium	Work In Progress	work room		8/6/2013 10:12:17 AM					
Ambriz, Jose		work room needs refrigerated air; if possible (navarro)							
Rosa Quezada									
107444	Main Building	Classroom			9/13/2013		3		\$0.00
Medium	Work In Progress	room 39		9/13/2013 3:45:17 PM					
Sanchez, Raul		clean north wall - FULL OF MOLD. SUTDENTS AND PARENTS COMPLAINED ABOUT WATER BUBBLES. (M. RAMIREZ)							
Rosa Quezada									
105705	Main Building	Restroom (Girls)			8/8/2013		39		\$0.00
Medium	Work In Progress			8/8/2013 3:27:56 PM					
Sonora, Miguel		need to install soap dispensers in girls bathrooms by 2nd and 3rd grade wing and main hallway...(r.alvarez)							
Rosa Quezada									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
107173	Main Building	Custodial			9/6/2013		10		\$0.00
Medium	Work In Progress			9/6/2013 12:38:02 PM					
Carbajal, Jimmy	jimmy tenemos dos aspiradoras descompuestas si por favor nos las puede arreglar y si por favor nos puede prestar dos aspiradoras mientras nos las arregla gracias.								
<u>Miguel Sonora</u>									
105043	Main Building	Office			8/1/2013		46		\$0.00
Medium	Work In Progress	teachers lounge		8/1/2013 10:57:29 AM					
Ontiveros, Joe	Please check to see if a ice machine could be installed in the teacher's lounge. (quezada) (Electrical, Plumbing and HVAC)				8/5/13- As per A. Holguin, PPD does not fund ice machines for school sites. The site needs to purchase on their own.				
<u>Rosa Quezada</u>									
106640	Main Building	Office			8/28/2013		19		\$0.00
Medium	Work In Progress	nurses outside		8/28/2013 9:20:28 AM					
Castillo, Carlos	lights outside nurses station are not working (quezada)								
<u>Rosa Quezada</u>									
106639	Main Building	Restroom (Boys)			8/28/2013		19		\$0.00
Medium	Work In Progress	6th grade area		8/28/2013 9:00:11 AM					
Castillo, Carlos	the lights went out yesterday at riverside and the emergency lights in the boys restroom and nurses station failed to come on. (quezada)								
<u>Rosa Quezada</u>									
105474	Main Building				8/6/2013		41		\$0.00
Medium	Work In Progress			8/6/2013 10:08:22 AM					
Moncayo, Fernando	bathrooms and main hallways need painting (navarro)								
<u>Rosa Quezada</u>									
105859	Main Building	Classroom			8/12/2013		35		\$0.00
Medium	Work In Progress	room 33		8/12/2013 1:06:44 PM					
Ambriz, Juan	airconditioning not working in room 33 (franco)								
<u>Rosa Quezada</u>									
105475	Main Building	Restroom (Boys)			8/6/2013		41		\$0.00
Medium	Work In Progress	restrooms in		8/6/2013 10:10:29 AM					
Ambriz, Juan	bathrooms need tiles placed on floor (navarro)								
<u>Rosa Quezada</u>									
106276	Main Building	Office			8/20/2013		27		\$0.00
Medium	Work In Progress	DATA ENTRY		8/20/2013 10:15:08 AM					
Ambriz, Juan	NEED TO MOVE CUM FILE CABINETS (FIREPROOF) TO OTHER SIDE OF OFFICE. (SOTO)								
<u>Rosa Quezada</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
105401	Main Building	Office			8/5/2013		42		\$0.00
Medium	Work In Progress	Assistant			8/5/2013 2:01:45 PM				
Ambriz, Juan	need to move smart board from room 106 to New SPED room #18. (hernandez)								
<u>Rosa Quezada</u>									
105405	Main Building	Office			8/5/2013		42		\$0.00
Medium	Work In Progress	front office			8/5/2013 2:08:02 PM				
Ambriz, Juan	need to move Prinicipal sign to conference room and place a new Assistant Principal sign in front office. (navarro)								
<u>Rosa Quezada</u>									
105663	Main Building	Classroom			8/8/2013		39		\$0.00
Medium	Work In Progress	room #30			8/8/2013 10:06:38 AM				
Ambriz, Juan	air conditioner not working								
<u>Rosa Quezada</u>									
106273	Main Building	Classroom			8/20/2013		27		\$0.00
Medium	Work In Progress	ROOM 123			8/20/2013 10:10:58 AM				
Ambriz, Juan	NEED TO MOVE THE SCREENT TO OTHER WALL (TUCKER)								
<u>Rosa Quezada</u>									
106116	Main Building	Classroom			8/16/2013		31		\$0.00
Medium	Work In Progress	Room #33			8/16/2013 7:59:21 AM				
Ambriz, Juan	need to check a/c in room #33 not working								
<u>Juan Ambriz</u>									
105998	Main Building	Classroom			8/14/2013		33		\$0.00
Medium	Work In Progress	room #104			8/14/2013 1:49:58 PM				
Ambriz, Juan	1. CHAIRS WITH WHEELS NEED TO BE TIGHTENED. 2. EASEL NEEDS SCREWS, IT COLLAPSES. (PALOMARES)								
<u>Rosa Quezada</u>									
105999	Main Building	Classroom			8/14/2013		33		\$0.00
Medium	Work In Progress	ROOM #35			8/14/2013 1:52:00 PM				
Ambriz, Juan	WATER POURING INTO THE ROOM AT REGULAR INTERVALS FROM THE CEILING NEAR THE A/C UNIT FROM THE BOTTOM OF THE HEATER. (B. JUAREZ)								
<u>Rosa Quezada</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
105775	Main Building	Classroom			8/9/2013		38		\$0.00
Medium	Work In Progress	room 106			8/9/2013 2:31:40 PM				
Ambriz, Juan	1. NEED TO MOVE SMART BOARD FROM ROOM 106 TO NEW SPED ROOM #18. 2. NEED CEILING BRACKET MOUNTED FOR SMART BOARD IN ROOM #21 (R. PARRA)								
Rosa Quezada									
107050	Main Building	Classroom			9/4/2013		12		\$0.00
Medium	Work In Progress	ROOM 104			9/4/2013 9:57:51 AM				
Ambriz, Juan	LARGE CLASSROOM EASEL HAS MISING SCREWS. IT FALLS EASITLY IF NOT HELD DOWN AS I WRITE ON IT. SAFETY HAZARD!!! (PALOMARES)								
Rosa Quezada									
104917	Main Building	Classroom			7/30/2013		48		\$0.00
Medium	Work In Progress	Room 14			7/30/2013 1:14:59 PM				
Ambriz, Juan	1. need a flag stand/holder in classroom to hold up flag 2. Replace light bulbs 3. drill rail to hold name plate (ruby alvarez)								
Rosa Quezada									
104800	Main Building	Classroom			7/26/2013		52		\$0.00
Medium	Work In Progress	Room #30			7/26/2013 3:42:51 PM				
Ambriz, Juan	Need to Install 2 white boards in room #30								
Juan Ambriz									
105478	Main Building	Classroom			8/6/2013		41		\$0.00
Medium	Work In Progress	144			8/6/2013 10:25:18 AM				
Ambriz, Juan	classroom needs 8 light bulbs replaced (R. Alvarez)								
Rosa Quezada									
105479	Main Building	Classroom			8/6/2013		41		\$0.00
Medium	Work In Progress	144			8/6/2013 10:28:17 AM				
Ambriz, Juan	large heavy bulletin board is falling of the wall. hanging by a thread. needs immediate attention (r. alvarez)								
Rosa Quezada									
105480	Main Building	Classroom			8/6/2013		41		\$0.00
Medium	Work In Progress	104			8/6/2013 10:32:40 AM				
Ambriz, Juan	easel is broken. screws are loose and/or missing. it's a safety hazard. can tip over and hurt someone. please repair a.s.a.p. (palomares)								
Rosa Quezada									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
105559	Main Building	Classroom			8/7/2013		40		\$0.00
Medium	Work In Progress	room 18			8/7/2013 8:50:07 AM				
Ambriz, Juan		there is a leak in the roof that fills lights up - drips on teachers desk and computer desk. please fix a.s.a.p. (j. Nunez)							
Rosa Quezada									
105389	Main Building	Classroom			8/5/2013		42		\$0.00
Medium	Work In Progress	rooms 29 and 34			8/5/2013 12:10:27 PM				
Ortiz, Ruben		air conditioner not working in rooms 29 & 34 (flavian)							
Rosa Quezada									
104259	New Wing 1/02				7/12/2013		66		\$0.00
Medium	Work In Progress				7/12/2013 8:49:10 AM				
Ambriz, Juan		check irrigation system to pine tress for proper operation. trees are dying							
Richard Chavez									
Count: 57 Work Orders		Avg. Age of WO's		31	Total for Riverside ES			0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		RTC - Alliance							
105451					8/6/2013		41		\$0.00
Medium	Work In Progress				8/6/2013 7:58:08 AM				
Moncayo, Fernando	I placed a work order to clean our ground. Fernando came but left and hasn't returned. I also need for him to run a cord already installed thru the ceiling to Mrs. Hirsch computer								
Gloria Delgado									
Count: 1 Work Orders	Avg. Age of WO's		41	Total for RTC - Alliance			0	\$0.00	

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		San Miguel ES							
106936					9/1/2013		15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:53 AM				
Apodaca, Mario	Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 1 Work Orders			Avg. Age of WO's	15		Total for San Miguel ES	0	0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
105828					8/11/2013	8/27/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:47 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
107207					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:06 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
107024		Athletic Field			9/3/2013		13		\$0.00
Medium	Work In Progress	Basketball		9/3/2013 3:38:44 PM					
Ambriz, Juan	Need to repair pole pads								
Juan Ambriz									
105320					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:58 AM					
Munoz, Michael	Yearly - Santa Teresa ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
106951					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:59 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
105349					8/4/2013	8/10/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:10 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
107081					9/4/2013		12		\$0.00
Medium	Work In Progress	Maintenance		9/4/2013 3:40:33 PM					
Ambriz, Juan	Need air compressor for maintenace purposes								
Juan Ambriz									
107501					9/16/2013		0		\$0.00
Medium	Work In Progress	Vehicle#140		9/16/2013 12:47:40 PM					
Flores, Pete	Need to replace wiper blades, muffler making loud noise, rear right light is not working								
Juan Ambriz									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
106898					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:39 AM					
Ambriz, Juan	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106899					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:39 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106900					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:39 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
104532					7/19/2013		59		\$0.00
Medium	Work In Progress			7/19/2013 3:29:17 PM					
Ambriz, Juan	Need to order 2 50' water hoses and a set of drill bits								
<u>Juan Ambriz</u>									
105244					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:24 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105245					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:24 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105243					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:23 AM					
Ambriz, Juan	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107009					9/3/2013		13		\$0.00
Medium	Work In Progress			9/3/2013 1:18:39 PM					
Ambriz, Juan	please cut weeds and pick up in ponding areas. thank you								
<u>Michael Munoz</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
104056					7/7/2013	7/23/2013	15		\$0.00
Medium	Work In Progress			7/7/2013 12:22:47 AM	7/22/2013				
Diaz, Pablo	Monthly - QRTL BLDG INSP REPORT (STE) - Refer to PM schedule details.		completed						
Jesus Estrada									
106351					8/21/2013		26		\$0.00
Medium	Work In Progress			8/21/2013 3:26:48 PM					
Diaz, Pablo	ALL RESTROOMS, BOYS AND GIRLS, NEED TO BE DETAILED. WALLS STALLS AND FLOORS								
Jesus Estrada									
106354					8/21/2013		26		\$0.00
Medium	Work In Progress			8/21/2013 3:27:59 PM					
Diaz, Pablo	HALLWAY WALLS NEED TO BE WASHED								
Jesus Estrada									
106355					8/21/2013		26		\$0.00
Medium	Work In Progress			8/21/2013 3:28:52 PM					
Diaz, Pablo	HALLWAY FLOORS NEED TO BE BURNISHED								
Jesus Estrada									
106356					8/21/2013		26		\$0.00
Medium	Work In Progress			8/21/2013 3:29:42 PM					
Diaz, Pablo	ALL WINDOWS AND ENTRANCES NEED TO BE CLEANED								
Jesus Estrada									
106357					8/21/2013		26		\$0.00
Medium	Work In Progress			8/21/2013 3:30:39 PM					
Diaz, Pablo	ALL OFFICES NEED HIGH TO LOW DUSTING								
Jesus Estrada									
106857					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:22 AM					
Ambriz, Juan	Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos									
106258					8/20/2013		27		\$0.00
Medium	Work In Progress			8/20/2013 7:44:48 AM					
Castillo, Carlos	As per Juan Ambriz doorbell not working again.								
Carlos Castillo									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
105398		Classroom			8/5/2013		42		\$0.00
Medium	Work In Progress	Mrs. Gorman's		8/5/2013 1:27:05 PM					
Castillo, Carlos		Mrs. Gorman needs the Smart board set up. Electricity needs to be installed in the ceiling of her classroom. Thanks.							
<u>Rita Mendez</u>									
107443	Main Building				9/13/2013		3		\$0.00
Medium	Work In Progress	Conference		9/13/2013 3:44:02 PM					
Ambriz, Juan		Need to replace lights in conference room							
<u>Juan Ambriz</u>									
104926	Main Building	Classroom			7/30/2013		48		\$0.00
Medium	Work In Progress	Room #303		7/30/2013 3:28:10 PM					
Ambriz, Juan		Need to Install maps on wall							
<u>Juan Ambriz</u>									
105079	Main Building	Classroom			8/1/2013		46		\$0.00
Medium	Work In Progress	Room #108		8/1/2013 3:34:39 PM					
Ambriz, Juan		Need to assemble new shelves in room #108							
<u>Juan Ambriz</u>									
105081	Main Building	Classroom			8/1/2013		46		\$0.00
Medium	Work In Progress	Room #209		8/1/2013 3:35:47 PM					
Ambriz, Juan		Need to relocate maps hanging from the wall							
<u>Juan Ambriz</u>									
105082	Main Building	Classroom			8/1/2013		46		\$0.00
Medium	Work In Progress	Room #210		8/1/2013 3:37:01 PM					
Ambriz, Juan		Need to relocate maps hanging from wall							
<u>Juan Ambriz</u>									
105986	Main Building	Classroom			8/14/2013		33		\$0.00
Medium	Work In Progress	room 303		8/14/2013 9:16:17 AM					
Ambriz, Juan		World map need to be installed in the classroom. Please check with Mr. Rivas where he would like it. Thank you.							
<u>Rita Mendez</u>									
105083	Main Building	Parking Lot			8/1/2013		46		\$0.00
Medium	Work In Progress			8/1/2013 3:38:27 PM					
Ambriz, Juan		Need to Install parking signs for office staff							
<u>Juan Ambriz</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa ES									
106635	Main Building	Parking Lot			8/28/2013		19		\$0.00
Medium	Work In Progress	gates			8/28/2013 7:55:00 AM				
Ambriz, Juan	Need to replace wheels on front gates								
<u>Juan Ambriz</u>									
105103	Main Building	Library			8/2/2013		45		\$0.00
Medium	Work In Progress				8/2/2013 7:46:48 AM				
Ambriz, Juan	Need to replace lights in the library								
<u>Juan Ambriz</u>									
106746	Main Building	Library			8/29/2013		18		\$0.00
Medium	Work In Progress	library office			8/29/2013 2:18:28 PM				
Ambriz, Juan	a/c unit in library office is leaking water need to replace ceiling tiles								
<u>Juan Ambriz</u>									
106302	Main Building	Office			8/20/2013		27		\$0.00
Medium	Work In Progress	front office			8/20/2013 3:58:38 PM				
Castillo, Carlos	Need to replace door bell not working								
<u>Juan Ambriz</u>									
107183	Main Building				9/6/2013		10		\$0.00
Medium	Work In Progress				9/6/2013 3:09:23 PM				
Ontiveros, Joe	Need to Replaces sink facset in Confrances room will not stop dripping.								
<u>Joe Ontiveros</u>									
106737	Main Building	Office			8/29/2013		18		\$0.00
Medium	Work In Progress	Casa Azul			8/29/2013 1:20:34 PM				
Lara, Ralph	Need to have a key made for Bilingual Speech Therapist. Do not want to issue the original on file. (2 keys needed)								
<u>Melynda Menchaca</u>									
106980	Main Building	Classroom			9/3/2013		13		\$0.00
Medium	Work In Progress	Room 303			9/3/2013 8:48:32 AM				
Ambriz, Jose	Need HVAC TECH to check a/c unit in room #303 not cooling								
<u>Juan Ambriz</u>									
106570	Main Building	Classroom			8/27/2013		20		\$0.00
Medium	Work In Progress	Room #103			8/27/2013 1:03:00 PM				
Ambriz, Jose	Need HVAC TECH to check a/c unit in room #103 making loud noise								
<u>Juan Ambriz</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Santa Teresa ES							
106365	Main Building	Classroom			8/21/2013		26		\$0.00
Medium	Work In Progress	Room #101			8/21/2013 3:49:58 PM				
Lara, Ralph		Need locksmith to replace deadbolt in classroom getting stuck (ASAP) SPECIAL ED CLASSROOM							
Juan Ambriz									
Count: 41 Work Orders		Avg. Age of WO's 27			Total for Santa Teresa ES			0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
107302	Main Building	Kitchen			9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 2:55:30 PM					
Lara, Ralph	Need a couple of keys made for the kitchen cabinets in the main building. As of right now we have only one key.								
William Dickson									
107101	Main Building	Foyer			9/5/2013		11		\$0.00
Medium	Work In Progress			9/5/2013 5:52:04 AM					
Ambriz, Jose	water fountain in 400 hallway is leaking								
Isaac Holguin									
106456	Main Building	Classroom			8/23/2013		24		\$0.00
Medium	Work In Progress	203		8/23/2013 10:56:44 AM					
Ambriz, Jose	The A/C in room 203 is VERY loud!. Teacher has to speak loudly and it's hard to students to hear. Please make this a priority. Thanks.								
Kathryn Harper									
106278	Main Building	Classroom			8/20/2013		14		\$0.00
Medium	Work In Progress			8/20/2013 10:32:25 AM		9/3/2013			
Holguin, Isaac	We are witnessing more mold in the 500 hallway. Room 501 also has reported additional mold growing in the walls. This has become a big problem and it will continue to grow unless something is changed. Thanks!								
William Dickson									
106067	Main Building	Classroom			8/15/2013		32		\$0.00
Medium	Work In Progress			8/15/2013 11:01:00 AM					
Ontiveros, Joe	3 clogged sinks in science classroom room #511 mrs stevens								
Isaac Holguin									
107311	Main Building	Classroom			9/10/2013		6		\$0.00
Medium	Work In Progress	610		9/10/2013 3:32:39 PM					
Ontiveros, Joe	Remove the gas stove from room 610. The others are all electric. This one turns on by itself, and is malfunctioning.								
Kathryn Harper									
107386	Main Building	Restroom			9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 7:39:51 PM					
Ontiveros, Joe	The restroom in room 215 when flushed does not stop running. Need to be checked and fixed. Thanks!								
William Dickson									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
107104	Main Building	Classroom			9/5/2013		11		\$0.00
Medium	Work In Progress	300			9/5/2013 7:29:11 AM				
Castillo, Carlos		Broken light switch in 300 hallway where it intersects with main hall							
Kathryn Harper									
106642	Main Building				8/28/2013		19		\$0.00
Medium	Work In Progress				8/28/2013 9:31:35 AM				
Mijarez, Jaime		Teacher wants 21 chairs taken out of classroom.							
William Dickson									
107274	Main Building				9/9/2013		7		\$0.00
Medium	Work In Progress				9/9/2013 4:49:11 PM				
Mijarez, Jaime		Mr. Gutierrez is wanting a white board mounted in his room. He is also wanting the light bulbs that are out replaced.							
William Dickson									
106643	Main Building	Classroom			8/28/2013		19		\$0.00
Medium	Work In Progress	606			8/28/2013 9:34:08 AM				
Mijarez, Jaime		Room 405 needs ceiling tiles replaced.							
William Dickson									
106268	Main Building	Classroom			8/20/2013		27		\$0.00
Medium	Work In Progress				8/20/2013 9:04:44 AM				
Mijarez, Jaime		Jaime asp Mike need to change out all ceiling tiles that are stained w/mold in this area. Also, to include in other areas as needed. We are witnessing more mold in the 500 hallway. Room 509 has reported mold in the ceiling tile. Room 501 also has reported additional mold growing in the walls and ceiling tile. This has become a big problem and it will continue to grow unless something is changed. Thanks!							
William Dickson									
106459	Main Building	Classroom			8/23/2013		24		\$0.00
Medium	Work In Progress				8/23/2013 11:20:00 AM				
Mijarez, Jaime		Need light bulbs for classroom C-2. Classroom very dark. It is a computer lab.							
William Dickson									
105148	Main Building	Classroom			8/2/2013		45		\$0.00
Medium	Work In Progress				8/2/2013 2:12:07 PM				
Mijarez, Jaime		Need to get a white board and project monted in room 607 for our SPED teacher.							
William Dickson									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
107461	Main Building	Classroom			9/15/2013		1		\$0.00
Medium	Work In Progress			9/15/2013 11:08:32 AM					
Mijarez, Jaime	Room 206 has two lights that are out and needs replacement								
William Dickson									
107105	Main Building	Classroom			9/5/2013		11		\$0.00
Medium	Work In Progress	water pumps		9/5/2013 7:30:16 AM					
Mijarez, Jaime	Please replace water pumps								
Kathryn Harper									
106578	Main Building	Classroom			8/27/2013		20		\$0.00
Medium	Work In Progress	band room		8/27/2013 1:36:28 PM					
Miranda, Danny	Right outside band room, there's a hole in the wall								
Kathryn Harper									
106121	Main Building	Classroom			8/16/2013		31		\$0.00
Medium	Work In Progress	Nurses station		8/16/2013 8:18:56 AM					
Estrada, Jesus	Carpet in nurses office needs to be repaired.								
Kathryn Harper									
107486	Gymnasium	Football Field			9/16/2013		0		\$0.00
Medium	Work In Progress			9/16/2013 9:08:07 AM					
Ontiveros, Guadalupe	We continue to have a sink hold by the football and it is very bad at this moment. Will you send someone here to fill it in again. We have a game here tomorrow and it is in a dangerous place.								
William Dickson									
107388	Vocational	Classroom			9/11/2013		5		\$0.00
Medium	Work In Progress			9/11/2013 7:47:22 PM					
Ambriz, Jose	The fan unit in room 805 is not working. Need s attention please. Thanks!								
William Dickson									
107224	Vocational	Classroom			9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 8:30:07 AM					
Castillo, Carlos	It has been reported that the eletrical box or emergency shut off is not working in the ceramic shop inn the 800 wing.								
William Dickson									
107314	Vocational	Classroom			9/10/2013		6		\$0.00
Medium	Work In Progress	800 classroms		9/10/2013 3:38:42 PM					
Gonzales, Camilo	Remove unwanted items from the lots in front of the vocational classrooms.								
Kathryn Harper									
9/16/2013 4:20:18 PM									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
107313	Library	Library			9/10/2013		6		\$0.00
Medium	Work In Progress	Library			9/10/2013 3:37:35 PM				
Mijarez, Jaime	Put pictures of Classes in library on wall.								
<u>Kathryn Harper</u>									
106455	Annex Building	Classroom			8/23/2013		24		\$0.00
Medium	Work In Progress	705			8/23/2013 10:54:59 AM				
Gallegos, Rafael	Roof in ROTC leaks								
<u>Kathryn Harper</u>									
107074	Main Building	Classroom			9/4/2013		12		\$0.00
Medium	Work In Progress				9/4/2013 3:22:32 PM				
Lara, Ralph	There is a gate in room 215 that needs a lock. Can we please have the lock smith come by and provide us a lock that matches the teachers front door key.								
<u>William Dickson</u>									
107387	Main Building	Classroom			9/11/2013		5		\$0.00
Medium	Work In Progress				9/11/2013 7:42:07 PM				
Lara, Ralph	We are still waiting for a key to open the back gate in room 215. Teacher and students are not able to get out of the gate.								
<u>William Dickson</u>									
105146	Main Building				8/2/2013		45		\$0.00
Medium	Work In Progress				8/2/2013 1:56:09 PM				
Lara, Ralph	Still need to get keys made for a few doors and cabinets.								
<u>William Dickson</u>									
106002	Main Building	Office			8/14/2013		33		\$0.00
Medium	Work In Progress	Main office			8/14/2013 1:54:22 PM				
Ambriz, Jose	Fan in office restroom not working								
<u>Kathryn Harper</u>									
107174	Main Building	Classroom			9/6/2013		10		\$0.00
Medium	Work In Progress	Outside Culinary			9/6/2013 1:37:34 PM				
Ontiveros, Joe	Hot water not working								
<u>Kathryn Harper</u>									
107460	Main Building	Classroom			9/15/2013		1		\$0.00
Medium	Work In Progress				9/15/2013 11:06:56 AM				
Mijarez, Jaime	The culinary kitchen needs a can opener installed needs to see the Teacher for position of installment.								
<u>William Dickson</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

106340	Locker Room	Football Field			8/21/2013		26		\$0.00
Medium	Work In Progress	Turf			8/21/2013 11:21:44 AM				
Ontiveros, Guadalupe		Graffiti remains on turf, needs to be removed. (See Coach Vierra or Ms. Harper)							

Kathryn Harper

106125	Locker Room	Gym			8/16/2013		31		\$0.00
Medium	Work In Progress	Pe locker room			8/16/2013 8:25:08 AM				
Gonzalez, Salvador		Removal of bent or broken locker doors in PE boys dressing room.							

Kathryn Harper

106153	Locker Room	Gym			8/16/2013		31		\$0.00
Medium	Work In Progress	Pe locker room			8/16/2013 3:24:08 PM				
Estrada, Jesus		Carpet square in back of weight room need to be replaced.							

Kathryn Harper

107157	Concession	Football Field			9/6/2013		10		\$0.00
Medium	Work In Progress				9/6/2013 8:12:06 AM				
Ambriz, Jose		The ice machine in the training room and in the concession stand are not producing ice. With all the activities we are having throughout the week we would like to get them working please. Help!							

William Dickson

105668	Cafeteria (2005)	Cafeteria			8/8/2013		39		\$0.00
Medium	Work In Progress				8/8/2013 12:51:24 PM				
Ambriz, Jose		water fountains in cafeteria are leaking							

Isaac Holguin

107201	Cafeteria (2005)	Cafeteria			9/6/2013		10		\$0.00
Medium	Work In Progress				9/6/2013 4:59:00 PM				
Ambriz, Jose		Neither freezer works in the culinary kitchen. It does not turn on or off or reset to the correct temperature.							

William Dickson

107200	Cafeteria (2005)	Kitchen			9/6/2013		10		\$0.00
Medium	Work In Progress				9/6/2013 4:56:33 PM				
Ontiveros, Joe		The hot water is not running and needs to be fixed.				9/9/13 - Informed Joe Ontiveros			

William Dickson

106000	Cafeteria (2005)	Cafeteria			8/14/2013		33		\$0.00
Medium	Work In Progress				8/14/2013 1:53:13 PM				
Castillo, Carlos		We need bulbs replaced in the cafeteria. Lighting is very dim							

Kathryn Harper

9/16/2013 4:20:18 PM

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
107202	Cafeteria (2005)	Cafeteria			9/6/2013		10		\$0.00
Medium	Work In Progress				9/6/2013 5:00:50 PM				
Mijarez, Jaime	Culinary kitchen needs the shelves reinstalled in dining room counter area see teacher.								
<u>William Dickson</u>									
106338	GYM (2009)	Gym			8/21/2013		26		\$0.00
Medium	Work In Progress	New boys			8/21/2013 11:17:00 AM				
Ontiveros, Joe	In new boys athletic locker room repair leaky student shower (will not full shut off) see coach douglas								
<u>Kathryn Harper</u>									
106977	GYM (2009)	Restroom			9/3/2013		13		\$0.00
Medium	Work In Progress				9/3/2013 8:18:36 AM				
Ontiveros, Joe	Restroom in the new gym is not flushing. Can the plumber or maintenance check out the problem and get it fixed before our next sporting event.								
<u>William Dickson</u>									
106377	GYM (2009)	Gym			8/21/2013		26		\$0.00
Medium	Work In Progress	PE storage area			8/21/2013 4:30:21 PM				
Castillo, Carlos	Check lights in PE storage areas. Not working. Please see Coach Bailon								
<u>Kathryn Harper</u>									
105453	GYM (2009)	Gym			8/6/2013		41		\$0.00
Medium	Work In Progress				8/6/2013 8:02:18 AM				
Castillo, Carlos	Need to adjust limit switch for projector screen.								
<u>Carlos Castillo</u>									
105136	GYM (2009)	Gym			8/2/2013		45		\$0.00
Medium	Work In Progress				8/2/2013 1:19:54 PM				
Ambriz, Jose	New gym. Double media A/C has a burned Mag Starter that needs to be replaced.								
<u>Jaime Mijarez</u>									
106333	GYM (2009)	Gym			8/21/2013		26		\$0.00
Medium	Work In Progress	Weight room			8/21/2013 11:06:11 AM				
Estrada, Jesus	Replace carpet tiles in weightroom								
<u>Kathryn Harper</u>									
106341	GYM (2009)	Gym			8/21/2013		26		\$0.00
Medium	Work In Progress	Basketball gym			8/21/2013 11:22:54 AM				
Mijarez, Jaime	Foam rubber edging around basketball backboards in both gyms coming off, needs to be replaced/repared (see Coach Haack or Coach Dotson)								
<u>Kathryn Harper</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
107106					9/5/2013		11		\$0.00
Medium	Work In Progress			9/5/2013 7:48:15 AM					
Castillo, Carlos	Exterior light poles that run along side the fence are turning off due to a broken wire that is tripping the circuit.								
Jaime Mijarez									
107149					9/5/2013		11		\$0.00
Medium	Work In Progress			9/5/2013 8:18:13 PM					
Castillo, Carlos	Two lights are out in the training room. Need to be replaced. Thank You								
William Dickson									
107041					9/4/2013		12		\$0.00
Medium	Work In Progress			9/4/2013 7:58:01 AM					
Castillo, Carlos	Parking lot. All of the lights are not turning on with the timer.								
Jaime Mijarez									
105814					8/11/2013	9/11/2013	36		\$0.00
Medium	Work In Progress			8/11/2013 12:17:41 AM					
Prospero, Manuel	Yearly - Santa Teresa HS A-9 Air Cooled Yearly - Refer to PM schedule details.								
Margret Villalobos									
105455					8/6/2013		41		\$0.00
Medium	Work In Progress			8/6/2013 8:12:37 AM					
Castillo, Carlos	New Gym projector screen. Need to adjust limit switch and help install screen back into its housing. The screen fell off completely.								
Jaime Mijarez									
106130					8/16/2013		31		\$0.00
Medium	Work In Progress			8/16/2013 8:39:24 AM					
Castillo, Carlos	Old gym area. Coaches storages problem with light switch location and one broken switch. Need to relocate light switches closer to the entry doors. Replaced bulbs and two light fixtures won't turn on.								
Jaime Mijarez									
106846					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:17 AM					
Munoz, Michael	Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PM schedule details.								
Margret Villalobos									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
107155					9/6/2013		10		\$0.00
Medium	Work In Progress			9/6/2013 8:08:16 AM					
Ontiveros, Joe	Showers in football locker room are backing up with sewage								
<u>Kathryn Harper</u>									
105218					8/4/2013	8/7/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:11 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106844					9/1/2013	9/4/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:16 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107283		Library			9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 8:35:23 AM					
Ontiveros, Joe	Library - Faucet in bathroom library has very little stream.								
<u>William Dickson</u>									
106136					8/16/2013		31		\$0.00
Medium	Work In Progress			8/16/2013 9:10:53 AM					
Ambriz, Juan	Trainers ice machine condenser fan is not working. Manitowoc Model-SD0502A, Serial-050164906, 115 volt, 1 phase								
<u>Jaime Mijarez</u>									
106859					9/1/2013	9/17/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:23 AM					
Villalobos, Margret	Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.					Sept Emailed Arlene			
<u>Margret Villalobos</u>									
104672					7/24/2013		54		\$0.00
Medium	Work In Progress			7/24/2013 8:52:31 AM					
Ambriz, Jose	HU2 airhandler at cafeteria is single phasing. Disconnected the line legs to motor and turned off power to unit.								
<u>Jaime Mijarez</u>									
107500					9/16/2013		0		\$0.00
Medium	Work In Progress			9/16/2013 12:34:31 PM					
Ambriz, Jose	New gym concession stand ice machine is not working.								
<u>Jaime Mijarez</u>									

9/16/2013 4:20:18 PM

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
106495					8/26/2013		21		\$0.00
Medium	Work In Progress			8/26/2013 9:08:31 AM					
Ambriz, Jose	Room 203. Slave fan coil unit has a noisy squerrel cage. I had to shutdown unit through tracer summit so it won't disrupt the classroom.								
Jaime Mijarez									
104038					7/7/2013	8/7/2013	71		\$0.00
Medium	Work In Progress			7/7/2013 12:22:38 AM					
Mijarez, Jaime	Yearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.								
Margret Villalobos									
106139					8/16/2013		31		\$0.00
Medium	Work In Progress			8/16/2013 9:32:23 AM					
Ontiveros, Guadalupe	Behind the old gym next to the football bleachers there is an area that is badly eroded and will be unsafe for the football games. There is also erosion along the fence line by the road and is exposing several of the fence post.								
Jaime Mijarez									
104227		Athletic Field			7/11/2013		67		\$0.00
Medium	Work In Progress			7/11/2013 2:10:31 PM					
Vasquez, Jose	water leak on main line for irrigation needs to be fixed and electric valves need to be replaced.								
Guadalupe Ontiveros									
106194		Athletic Field			8/19/2013		28		\$0.00
Medium	Work In Progress			8/19/2013 9:37:48 AM					
Vasquez, Jose	As per Mr. Dickson and softball coach, fence has to be removed and set out side post.								
Guadalupe Ontiveros									
107102		Custodial			9/5/2013		11		\$0.00
Medium	Work In Progress			9/5/2013 5:53:22 AM					
Lara, Ralph	water hose key								
Isaac Holguin									
107103		Custodial			9/5/2013		11		\$0.00
Medium	Work In Progress			9/5/2013 5:54:14 AM					
Lara, Ralph	light switch key								
Isaac Holguin									
104718		Athletic Field			7/24/2013		54		\$0.00
High	Work In Progress			7/24/2013 4:04:36 PM					
Gonzalez, Salvador	grounds shop at S.T.H.S roof has to be replaced.								
Guadalupe Ontiveros									
9/16/2013 4:20:19 PM									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
106327					8/21/2013		26		\$0.00
Medium	Work In Progress			8/21/2013 9:56:59 AM					
Holguin, Alfredo	Attn: Alfredo Holguin. Roof goose neck vents in old main bldg areas total of 18 count from 12", 24" and 36". These vents are causing roof leaks and ceiling tile damage which produces mold on tiles. Several of the dampers are not functional, screens are detached or torn. One of the problems we've had is cats going into the building and also accessible to intruders breaking in. I viewed the additions to the building and they have a newer and better vent design with a cap on top for better rain water protection and intruder protection. Let me know if you need more information.								
<hr/>									
Jaime Mijarez									
105124		Classroom			8/2/2013		32		\$0.00
Medium	Work In Progress	ROOM #501		8/2/2013 11:15:59 AM		9/3/2013			
Holguin, Isaac	MOLD IN ROOM #501 TO BE ADDRESSED ASAP.								
<hr/>									
Marylou Jimenez									
106908					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:42 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<hr/>									
Margret Villalobos									
106909					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:43 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<hr/>									
Margret Villalobos									
106910					9/1/2013	10/2/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:43 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<hr/>									
Margret Villalobos									
106911					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:44 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<hr/>									
Margret Villalobos									
105252					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:27 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<hr/>									
Margret Villalobos									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
105253					8/4/2013	8/12/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:27 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106369					8/21/2013		26		\$0.00
Medium	Work In Progress			8/21/2013 4:00:02 PM					
Mijarez, Jaime	Classrooms and hallways. Replace all ceiling tiles with visible mold or damage from water.								
<u>Jaime Mijarez</u>									
105281					8/4/2013	9/4/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:40 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105232					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:18 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
104626					7/23/2013		55		\$0.00
Medium	Work In Progress			7/23/2013 2:12:58 PM					
Mijarez, Jaime	Will need to replace ceiling tiles in several gym dressing rooms. Ceiling tile is a different texture can you please order 4 ea. Bundles of the sample that I gave you or at least match it.								
<u>Jaime Mijarez</u>									
107284		Library			9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 8:38:41 AM					
Mijarez, Jaime	Library - The security mirror in the back of the library needs to be hung.								
<u>William Dickson</u>									
106948					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:58 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
105345					8/4/2013	8/10/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:08 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105592					8/7/2013		40		\$0.00
Medium	Work In Progress			8/7/2013 12:52:27 PM					
Mijarez, Jaime	Asp inspection on PM Fire Sprinkler by Dimar the following was found: FDC missing cap								
<u>Michael Munoz</u>									
107229		Office			9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 10:21:09 AM					
Gonzales, Camilo	PLEASE DELIVER 1 BOX AND 1 PALLET WITH 89 INCH DUAL BOARD WIRELESS, ADJUST PRO ULTRA SHORT THROW WALL MOUNT TO MARYLOU JIMENEZ								
<u>Larry Martinez</u>									
105330					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:02 AM					
Munoz, Michael	Yearly - Santa Teresa HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106284		Custodial			8/20/2013		27		\$0.00
Medium	Work In Progress			8/20/2013 1:54:32 PM					
Flores, Pete	gas blower draw string broke		ROUTE TO AUTO SHOP AS PER JIMMY						
	284793207								
104773					7/26/2013		52		\$0.00
Medium	Work In Progress			7/26/2013 10:52:26 AM					
Holguin, Alfredo	Football field artificial Turf - Perform G-max Testing								
<u>Alfredo Holguin</u>									
107275		Library			9/9/2013		7		\$0.00
Medium	Work In Progress			9/9/2013 8:36:23 PM					
Villalobos, Margret	Library - Spray copy room, AV and bathroom for bugs.		Waiting on Price Quote						
<u>William Dickson</u>									
106744					8/29/2013		18		\$0.00
Medium	Work In Progress			8/29/2013 1:58:53 PM					
Villalobos, Margret	Room 310 - please spray room for spiders.		8/29 - Sent e-mail to Bennie to service asp Mike.						
<u>Jesus Estrada</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Santa Teresa HS							
105868					8/12/2013		35		\$0.00
Medium	Work In Progress				8/12/2013 2:12:56 PM				
Miranda, Danny	Showers in football dressing rooms - found 2 walls in showers with holes as large as 3 feet where students have been kicking in the walls.								
Alfredo Holguin									
105388					8/5/2013		42		\$0.00
Medium	Work In Progress				8/5/2013 11:45:06 AM				
Orozco, Daniel	PLEASE CHECK FLOOR IN FREEZER AND CAN OPENER NOT WORKING. SNP MANAGER OLGA B. 589.5332								
Maritza Gonzalez									
Count: 93 Work Orders		Avg. Age of WO's 24			Total for Santa Teresa HS			0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
105307					8/4/2013	8/10/2013	43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:52 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105325					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:20:00 AM					
Munoz, Michael	Yearly - Santa Teresa MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106941					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:55 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
105897	North Building	Classroom			8/12/2013		35		\$0.00
Medium	Work In Progress	ROOM 12		8/12/2013 4:20:05 PM					
Prospero, Manuel	REMOVE TV MONITOR FROM CLASSROOM								
<u>Laura Parra</u>									
105107	North Building	Classroom			8/2/2013		45		\$0.00
Medium	Work In Progress	ROOM 12		8/2/2013 7:52:45 AM					
Prospero, Manuel	RAISE SMART BOARD TO A HIGHER LEVEL								
<u>Laura Parra</u>									
105561	North Building	Custodial			8/7/2013		40		\$0.00
Medium	Work In Progress			8/7/2013 9:04:08 AM					
Flores, Pete	Truck #88 needs replacement of water pump.								
<u>Ismael Rodriguez</u>									
106996	North Building	Classroom			9/3/2013		13		\$0.00
Medium	Work In Progress	NORTH AND		9/3/2013 10:42:19 AM					
Prospero, Manuel	AS PER MS LOVELACE: PLEASE REMOVE ALL TV MONITORS FROM CLASSROOMS								
<u>Laura Parra</u>									
107164	North Building	Office			9/6/2013		10		\$0.00
Medium	Work In Progress	ROOM 8		9/6/2013 9:52:14 AM					
Lara, Ralph	KEY FOR MAJOR FIRE RESISTANT CABINET BROKE IN HALF--- NEED KEY... STUDENT FILES ARE IN CABINET AND UNABLE TO ACCESS THEM WITH OUT THE KEY								
<u>Laura Parra</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
107401	North Building	Gym			9/12/2013		4		\$0.00
Medium	Work In Progress			9/12/2013 12:03:07 PM					
Ontiveros, Guadalupe	Make a trench with the tractor in order to keep the rain away from the gym door entrances a.s.a.p								
<u>Ismael Rodriguez</u>									
107412	North Building	Gym			9/13/2013		3		\$0.00
Medium	Work In Progress			9/13/2013 8:45:25 AM					
Ontiveros, Guadalupe	Remove mud from the gym sidewalk entrance theirs a game on 9-14-13 as per Mr.Montano 7th grade principal as per saftey concerns thank you..								
<u>Ismael Rodriguez</u>									
106421	North Building	Classroom			8/22/2013		25		\$0.00
Medium	Work In Progress	ROOM 36B		8/22/2013 3:31:43 PM					
Lara, Ralph	KEY TO ROOM 36B DOES NOT UNLOCK DOOR								
<u>Laura Parra</u>									
105106	North Building	Classroom			8/2/2013		45		\$0.00
Medium	Work In Progress	ROOM 14		8/2/2013 7:51:42 AM					
Marquez, Gerardo	NEED KEY FOR BLACK FILING CABINET								
<u>Laura Parra</u>									
104884	North Building	Electrical Room			7/30/2013		48		\$0.00
Medium	Work In Progress			7/30/2013 7:49:52 AM					
Castillo, Carlos	Need to replace broken wall light fixture at back entrance to kitchen.								
<u>Carlos Castillo</u>									
106447	North Building	Cafeteria			8/23/2013		24		\$0.00
Medium	Work In Progress			8/23/2013 8:48:10 AM					
Castillo, Carlos	As per D.Orozco-check for power for 240v food warmer.								
<u>Carlos Castillo</u>									
106605	North Building	Football Field			8/27/2013		20		\$0.00
Medium	Work In Progress			8/27/2013 3:34:39 PM					
Ontiveros, Joe	Need to Replace broken 4inch pvc Clean out pipe next to football field.								
<u>Joe Ontiveros</u>									
107165	North Building	Office			9/6/2013		10		\$0.00
Medium	Work In Progress	SECURITY		9/6/2013 9:58:57 AM					
Lara, Ralph	DOOR IS CRACKED WHERE HINGES ARE PLACED-								
Laura Parra									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
105126	North Building	Custodial			8/2/2013		45		\$0.00
Medium	Work In Progress			8/2/2013 11:31:05 AM					
Carbajal, Jimmy		Jimmy i need an extra pannel mover.							
<u>Ismael Rodriguez</u>									
106729	South Building	Classroom			8/29/2013		18		\$0.00
Medium	Work In Progress	SOUTH BLDG		8/29/2013 11:09:55 AM					
Castillo, Carlos		NO EMERGENCY LIGHTS DURING POWER OUTAGE: 1-LOWER LEVEL GIRLS RESTROOM EAST END 2- UPPER LEVEL BOYS & GIRLS RESTROOMS WEST AND EAST 3- ROOM 44- MS ALLEN 4- ROOM 53 MS DE LA ROSA 5- ROOM 52 MR ARNOLD							
<u>Laura Parra</u>									
106420	South Building	Classroom			8/22/2013		25		\$0.00
Medium	Work In Progress	ROOM 36B		8/22/2013 3:30:57 PM					
Lara, Ralph		NEED KEY TO LOCK AND UNLOCK CABINET--- (LOCATED ON LEFT SIDE OF ROOM IN FRONT OF WHITE BOARD)							
<u>Laura Parra</u>									
104771	South Building	Classroom			7/26/2013		52		\$0.00
Medium	Work In Progress	ROOM 44		7/26/2013 10:33:21 AM					
Lara, Ralph		NEED KEY FOR BLACK FILING CABINET							
<u>Laura Parra</u>									
107052	South Building	Classroom			9/4/2013		12		\$0.00
Medium	Work In Progress	ROOM 44		9/4/2013 10:49:09 AM					
Lara, Ralph		NEED LOCK AND KEY FOR FILING CABINET							
<u>Laura Parra</u>									
106730	South Building	Classroom			8/29/2013		18		\$0.00
Medium	Work In Progress	ROOM 46		8/29/2013 11:11:17 AM					
Prospero, Manuel		WHITE BOARD IS COMING OFF WALL							
<u>Laura Parra</u>									
107320	South Building	Restroom			9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 3:45:59 PM					
Prospero, Manuel		I NEED TO REPLACE 2 MOTOS ON MAIN RESTROOMS OFFICE. EMERSON MODEL SA55NXGWH-5026. HP 1/4. RPM 1725. SF 1.35 VOLT 115. HZ 60 PH 1 CODE N A 4.9 S.F.A.5.8 AMB40 C.							
Manuel Prospero									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
107304	Gym (1997)	Football Field			9/10/2013		6		\$0.00
Medium	Work In Progress	FOOTBALL			9/10/2013 3:02:15 PM				
Castillo, Carlos		PLEASE CHECK IF SCOREBOARD HAS POWER							
<u>Laura Parra</u>									
105772	Gym (1997)	Mechanical			8/9/2013		38		\$0.00
Medium	Work In Progress	Karen Nougues			8/9/2013 2:19:52 PM				
Gonzalez, Salvador		PLAYERS BENCH FOR STMS LOCKER ROOM - (2) BENCHES SIZE TO FIT LOCKER ROOM.							
<u>Terry Alvarado</u>									
106822		Parking Lot			8/30/2013		17		\$0.00
High	Work In Progress				8/30/2013 4:24:34 PM				
Prospero, Manuel		please remove sand from parking lots. thank you							
<u>Michael Munoz</u>									
106823					8/30/2013		17		\$0.00
Medium	Work In Progress				8/30/2013 4:27:45 PM				
Prospero, Manuel		please clean up around both morgan building. discard in trash anything that we cannot use. also remove wood pile.							
<u>Michael Munoz</u>									
106922					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:48 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
106923					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:48 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
106920					9/1/2013		15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:47 AM				
Prospero, Manuel		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
106921					9/1/2013	10/2/2013	15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:47 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: Santa Teresa MS										
106061					8/15/2013		32		\$0.00	
Medium	Work In Progress			8/15/2013 8:59:45 AM						
Ontiveros, Guadalupe	IN THE GAC AREA NEED RELEVEL CAMPUS GROUND ALOT OF RAIN DAMAGE									
Manuel Prospero										
106099					8/15/2013		32		\$0.00	
Medium	Work In Progress			8/15/2013 3:39:50 PM						
Ontiveros, Guadalupe	THEY NEED COME RELEVEL THE SCHOOL CAMPUS GROUND DO TO ALOT OF RAIN DAMAGE AND LINES EXPOSE.									
Manuel Prospero										
105812					8/11/2013	9/11/2013	36		\$0.00	
Medium	Work In Progress			8/11/2013 12:17:40 AM						
Mijarez, Jaime	Yearly - Santa Teresa MS- A-9 Air Cooled (Yearly) - Refer to PM schedule details.									
Margret Villalobos										
105222					8/4/2013	9/4/2013	43		\$0.00	
Medium	Work In Progress			8/4/2013 12:19:13 AM						
Prospero, Manuel	Yearly - Santa Teresa MS C-11(Evap.Down)(Yearly) - Refer to PM schedule details.									
Margret Villalobos										
106609					8/27/2013		20		\$0.00	
Medium	Work In Progress			8/27/2013 3:39:29 PM						
Ontiveros, Joe	Need to Replace broken 4inch pvc pipe next to football field.									
Joe Ontiveros										
Count: 36 Work Orders	Avg. Age of WO's 25		Total for Santa Teresa MS				0	\$0.00		

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
106679		Restroom			8/28/2013		19		\$0.00
Medium	Work In Progress			8/28/2013 3:38:28 PM					
Ontiveros, Joe	Need to fine out on main sewer lines how they run in BLDG.								
Joe Ontiveros									
107040					9/4/2013		12		\$0.00
Medium	Work In Progress	TEACHER'S		9/4/2013 7:57:55 AM					
Ontiveros, Joe	AS PER MS. DUQUE----- NEED TO HAVE SINK INSTALLED IN THE TEACHER'S LOUNGE. PLEASE SEE MS. DUQUE ABOUT THIS IF THERE ARE ANY QUESTIONS. THANK YOU.								
David Avila									
104485					7/18/2013		60		\$0.00
Medium	Work In Progress	LINE LOCATE		7/18/2013 12:21:48 PM					
Castillo, Carlos	START AT THE WEST MOST ENTRANCE OF THE SCHOOL. FROM THIS POINT SPOT NORTH ACROSS THE PROPERTY TO ALTO VISTA DR. SPOT A 50' WIDE PATH USING WHITE LINE AS CENTER LINE OF PATH								
Company: TETRA TECH Contact Name: MONTY MILLER Phone:(406)241-5451									
Alfredo Holguin									
105045					8/1/2013		46		\$0.00
Medium	Work In Progress			8/1/2013 11:37:29 AM					
Castillo, Carlos	need to replace electrical outlet in cafe broken(hazzard)								
Carlos Hernandez									
104144					7/9/2013		69		\$0.00
Medium	Work In Progress			7/9/2013 3:47:49 PM					
Castillo, Carlos	need to replace several broken light covers (electrician did a special order) in classrooms								
Carlos Hernandez									
104155		Classroom			7/10/2013		68		\$0.00
Medium	Work In Progress			7/10/2013 7:58:26 AM					
Castillo, Carlos	Need to rplace broken light diffusers.								
Carlos Castillo									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
106259					8/20/2013		27		\$0.00
Medium	Work In Progress			8/20/2013 7:47:57 AM					
Castillo, Carlos	Need to order and install heavy duty doorbell equipment for all s.side elementaries.								
Carlos Castillo									
106739					8/29/2013		18		\$0.00
Medium	Work In Progress	SCHOOL WIDE		8/29/2013 1:28:10 PM					
Hernandez, Carlos	AS PER MR. VAN NOSDALE - CARLOS - DURING FALL BREAK PLEASE RE-PAINT HALLWAYS TO MAKE THEM LOOK BETTER. ALOT OF THE PAINT HAS BEEN CHIPPED AND NEEDS TO BE RE-TOUCHED.								
David Avila									
106741					8/29/2013		18		\$0.00
Medium	Work In Progress	PORTABLE A		8/29/2013 1:29:14 PM					
Hernandez, Carlos	AS PER MR. VAN NOSDALE - CARLOS - DURING FALL BREAK PLEASE PAINT THE MUSIC AND ART ROOM (PORT A AND B). MR. VAN NOSDALE WOULD LIKE THIS DONE BEFORE STUDENTS AND TEACHERS RETURN. TAHNK YOU.								
David Avila									
106858					9/1/2013	9/17/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:22 AM					
Hernandez, Carlos	Monthly - Sunland Park ES A-1 Wall Ref Semiannual - Refer to PM schedule details.								
Margret Villalobos									
106825					8/31/2013		16		\$0.00
Medium	Work In Progress			8/31/2013 12:25:33 AM					
Hernandez, Carlos	Monthly - Sunland Park ES A-16 Fan Exh Semiannual - Refer to PM schedule details.								
Margret Villalobos									
106228					8/19/2013		28		\$0.00
Medium	Work In Progress			8/19/2013 3:21:34 PM					
Ambriz, Jose	room 33 needs new a/c unit (43)								
Carlos Hernandez									
104012					7/3/2013		75		\$0.00
Medium	Work In Progress			7/3/2013 3:37:41 PM					
Ambriz, Jose	Air conditioner in the kitchen is not working; need system replaced.								
Ruben Ortiz									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
104020					7/3/2013		75		\$0.00
Medium	Work In Progress			7/3/2013 3:45:13 PM					
Ambriz, Jose	Air conditioner in the gym is not working; need system replaced.								
Ruben Ortiz									
104021					7/3/2013		75		\$0.00
Medium	Work In Progress			7/3/2013 3:47:01 PM					
Ambriz, Jose	Air conditioner in the dining room is not working; need system replaced.								
Ruben Ortiz									
106155					8/16/2013		31		\$0.00
Medium	Work In Progress			8/16/2013 3:26:33 PM					
Flores, Pete	need new front right tire on truck 191 (has a ball)								
Carlos Hernandez									
106226					8/19/2013		28		\$0.00
Medium	Work In Progress			8/19/2013 3:19:59 PM					
Flores, Pete	truck 191 needs new tires								
Carlos Hernandez									
107001					9/3/2013		13		\$0.00
Medium	Work In Progress	COMPUTER		9/3/2013 11:53:59 AM					
Castillo, Valeria	AS PER MR. VAN NOSDALE - DURING FALL BREAK NEED COMPUTER LAB FLOOR SHINED AND WAXED. NEED THIS DONE BEFORE STUDENTS RETURN FROM FALL BREAK.								
David Avila									
107002					9/3/2013		13		\$0.00
Medium	Work In Progress	SCHOOL WIDE-		9/3/2013 11:55:04 AM					
Castillo, Valeria	AS PER MR. VAN NOSDALE- DURING FALL BREAK, NEED TO HAVE ALL CLASSROOMS MOPPED AND CLEANED. NEED TO HAVE THIS DONE BEFORE STUDENTS RETURN. THANK YOU.								
David Avila									
107003					9/3/2013		13		\$0.00
Medium	Work In Progress	LIBRARY - MS.		9/3/2013 11:56:13 AM					
Castillo, Valeria	AS PER MS. VAN NOSDALE - DURING FALL BREAK, NEED TO HAVE THE CARPET IN THE LIBRARY CLEANED OUT. SHAMPOOED AND VACUMMED. THANK YOU.								
David Avila									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Sunland Park ES									
106658					8/28/2013		19		\$0.00
Medium	Work In Progress			8/28/2013 2:23:40 PM					
Castillo, Valeria	NEED TO WSH WALLS, SHOWER SCRUB & WAX FLOORS IN ROOM #19								
Jesus Estrada									
106742					8/29/2013		18		\$0.00
Medium	Work In Progress	MAIN		8/29/2013 1:34:05 PM					
Castillo, Valeria	AS PER MR. VAN NOSDALE - VALERIA/CARLOS M- DURING FALL BREAK PLEASE MAKE SURE TO WAX AND SHINE ALL FLOORS IN THE MAIN HALLWAY/ CAFETERIA AND GYM. HE WOULD LIKE THIS PROJECT COMPLETE BEFORE STUDENTS RETURN AFTER FALL BREAK. THANK YOU.,								
David Avila									
107016					9/3/2013		13		\$0.00
Medium	Work In Progress			9/3/2013 2:28:25 PM					
Flores, Pete	tire needs repair on tractor 445								
Carlos Hernandez									
107017					9/3/2013		13		\$0.00
Medium	Work In Progress			9/3/2013 2:29:28 PM					
Flores, Pete	need new blades for lawn mower 130								
Carlos Hernandez									
104563					7/22/2013		56		\$0.00
Medium	Work In Progress			7/22/2013 3:24:58 PM					
Flores, Pete	970 tractor needs repair clutch								
Carlos Hernandez									
104722					7/25/2013		53		\$0.00
Medium	Work In Progress			7/25/2013 8:16:27 AM					
Flores, Pete	Sunland Park; there is oil leaking by the front tire of the tractor; need it repaired. Thank you, Ruben								
Ruben Ortiz									
105321					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:58 AM					
Munoz, Michael	Yearly - Sunland Park ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
106961					9/1/2013	9/7/2013	15		\$0.00
Medium	Work In Progress			9/1/2013 12:30:04 AM					
Hernandez, Carlos	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107064					9/4/2013		12		\$0.00
Medium	Work In Progress			9/4/2013 2:48:55 PM					
Gonzalez, Salvador	need poles install with chain around front circle to control traffic (hazard parents dropping off students in middle)								
<u>Carlos Hernandez</u>									
105075					8/1/2013		46		\$0.00
Medium	Work In Progress			8/1/2013 3:07:31 PM					
Lara, Ralph	front doors and north and south side doors need new panic bars								
<u>Carlos Hernandez</u>									
107213					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:08 AM					
Hernandez, Carlos	Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
104854					7/29/2013		49		\$0.00
Medium	Work In Progress			7/29/2013 3:32:54 PM					
Hernandez, Carlos	need these tools 2 garden hose 50ft 1 25ft drain cleaner (snake) 1 fertilizer spreader 1 fit 5/26 and 1/4 1" scraper 1" tube cutter areator stihl weed eater head								
<u>Carlos Hernandez</u>									
107123					9/5/2013		11		\$0.00
Medium	Work In Progress	COMPUTER		9/5/2013 11:19:43 AM					
,	AS PER MR. VAN NOSDALE- MR. VAN NOSDALE WOULD LIKE TO SEE IF IT IS POSSIBLE TO INSTALL TILE FLOORING IN THE COMPUTER LAB. AS PER MS. VILLA OUR COMPUTER IA- SHE IS GETTING NEW COMPUTERS AND WOULD LIKE TO PUT IN THE NEW FLOOR TO MAKE IT BRIGHTER AND MORE INVITING FOR THE STUDENTS. THANK YOU.								
<u>David Avila</u>									
Count: 33 Work Orders			Avg. Age of WO's	33	Total for Sunland Park ES			0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
107208					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:06 AM					
Vargas, Juan	Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106169					8/16/2013		31		\$0.00
Medium	Work In Progress			8/16/2013 3:39:45 PM					
Ronquillo, Ruben	Replace glass lens for lamp at Sunrise Elementary. Danny has the frame.								
<u>Albert Vallejo</u>									
106938					9/1/2013		15		\$0.00
Medium	Work In Progress			9/1/2013 12:29:53 AM					
Apodaca, Mario	Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
106427					8/22/2013		25		\$0.00
Medium	Work In Progress			8/22/2013 3:40:03 PM					
Marquez, Gerardo	doors between rooms 309 307 and 212 210 need fix is broken								
<u>Juan Vargas</u>									
107280					9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 8:19:22 AM					
Carrasco, Danny	need lift to instaled blinds in cafeteria								
<u>Juan Vargas</u>									
105322					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:59 AM					
Munoz, Michael	Yearly - Sunrise ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
107279					9/10/2013		6		\$0.00
Medium	Work In Progress			9/10/2013 8:17:26 AM					
Flores, Pete	430 mower need replace blade								
<u>Juan Vargas</u>									
104528					7/19/2013		59		\$0.00
Medium	Work In Progress			7/19/2013 2:47:01 PM					
Vargas, Juan	need replace office car casters wehlls								
<u>Juan Vargas</u>									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
104529					7/19/2013		59		\$0.00
Medium	Work In Progress				7/19/2013 2:48:57 PM				
Vargas, Juan	need 250 lb. weed and feed for play ground grass								
Juan Vargas									
107110					9/5/2013		11		\$0.00
Medium	Work In Progress				9/5/2013 9:09:34 AM				
Vargas, Juan	need tools and tool bag								
Juan Vargas									
106424					8/22/2013		25		\$0.00
Medium	Work In Progress				8/22/2013 3:36:46 PM				
Marquez, Gerardo	marqui need replace locks								
Juan Vargas									
105697					8/8/2013		39		\$0.00
Medium	Work In Progress				8/8/2013 3:06:53 PM				
Marquez, Gerardo	doors betwen in rooms 307 and 309 need fix								
Juan Vargas									
105518					8/6/2013		41		\$0.00
Medium	Work In Progress				8/6/2013 2:13:55 PM				
Vallejo, Albert	need replace outside lights contactor and fix electrical troable shooting								
Juan Vargas									
107256					9/9/2013		7		\$0.00
Medium	Work In Progress				9/9/2013 3:10:00 PM				
Vallejo, Albert	need instaled electrical wire 120 volt. for a/c unite in room 306								
Juan Vargas									
107257					9/9/2013		7		\$0.00
Medium	Work In Progress				9/9/2013 3:12:01 PM				
Solis, Lorenzo	need help to fix a/c unite in library								
Juan Vargas									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

Location:	Sunrise ES								
106389					8/22/2013			25	\$0.00

Medium Work In Progress LINE LOCATE 8/22/2013 9:09:37 AM

Vallejo, Albert SPOT 25 FT RADIUS OF EXISTING WATER METER CONNECTION LOCATED IN FRONT OF THE SCHOOL

Company: LAKE SECTION WATER CO
 Contact Name: BECKY LAWRENCE
 Contact Phone: (575)824-4731

Alfredo Holguin									
Count: 16 Work Orders	Avg. Age of WO's 25			Total for Sunrise ES				0	\$0.00

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
106787					8/30/2013		17		\$0.00
Medium	Work In Progress			8/30/2013 9:19:14 AM					
Solis, Lorenzo		Check unit in testing room.							
Danny Miranda									
104519					7/19/2013		59		\$0.00
Medium	Work In Progress			7/19/2013 1:33:04 PM					
Estrada, Jesus		need new carpet in front office area							
Danny Miranda									
105323					8/4/2013		43		\$0.00
Medium	Work In Progress			8/4/2013 12:19:59 AM					
Munoz, Michael		Yearly - Vado ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
104680					7/24/2013		54		\$0.00
Medium	Work In Progress			7/24/2013 10:11:48 AM					
Estrada, Jesus		need carpet in computer room							
Danny Miranda									
105493					8/6/2013		41		\$0.00
Medium	Work In Progress			8/6/2013 12:07:19 PM					
Marquez, Gerardo		need to replace back door to kitchen							
Danny Miranda									
105494					8/6/2013		41		\$0.00
Medium	Work In Progress			8/6/2013 12:10:54 PM					
Marquez, Gerardo		need to replace back door going to bus exit							
Danny Miranda									
107214					9/8/2013	9/24/2013	8		\$0.00
Medium	Work In Progress			9/8/2013 12:16:09 AM					
Miranda, Danny		Monthly - Vado ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
104836					7/29/2013		49		\$0.00
Medium	Work In Progress			7/29/2013 2:33:24 PM					
Miranda, Danny		need to change filters							
Danny Miranda									
104687					7/24/2013		54		\$0.00
Medium	Work In Progress			7/24/2013 1:19:22 PM					
Miranda, Danny		need to repaint parking lot strips							
Danny Miranda									
9/16/2013 4:20:19 PM									

828 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
104762					7/26/2013		52		\$0.00
Medium	Work In Progress				7/26/2013 7:55:04 AM				
Miranda, Danny	need seafy cones put up in parking lot to parent drop off								
Danny Miranda									
106880					9/1/2013		15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:32 AM				
Miranda, Danny	Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
106878					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:31 AM				
Miranda, Danny	Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
106879					9/1/2013	9/9/2013	15		\$0.00
Medium	Work In Progress				9/1/2013 12:29:31 AM				
Miranda, Danny	Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
106399					8/22/2013		25		\$0.00
Medium	Work In Progress				8/22/2013 10:40:01 AM				
Miranda, Danny	need 3 1" brass sprinklers to water manually and one w/hose bibb								
Danny Miranda									
104726		Library			7/25/2013		53		\$0.00
Medium	Work In Progress				7/25/2013 9:17:32 AM				
Estrada, Jesus	NEED CARPET REPLACED IN LIBRARY								
Jesus Estrada									
Count: 15 Work Orders		Avg. Age of WO's		36	Total for Vado ES			0	\$0.00
Count: 828 Work Orders		Avg. Age of WO's		26	Grand Total			0	\$0.00