

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Location Not Assigned</b>							
111654					1/6/2014		66		\$0.00
Medium	Work In Progress				1/6/2014 12:24:14 AM				
Flores, Pete		Monthly - District Tractors - Full Service PM - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>66</b>			<b>Total for &lt;Blank&gt;</b>	<b>0</b>		<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony - On Track Pre-K (Village)</b>									
107866		Office			9/24/2013		170		\$0.00
Medium	Work In Progress	575-882-1904			9/24/2013 2:01:38 PM				
Nunez, Arturo		restroom form the office is making a noise (when we flash it).							
Laura Vazquez									
113214		Cafeteria			2/10/2014		31		\$0.00
Medium	Work In Progress	575-882-1904			2/10/2014 1:50:52 PM				
Nunez, Arturo		please move white bulletin board and assemble it at the outside wall by the cafeteria... thank you							
Laura Vazquez									
106090					8/15/2013		210		\$0.00
Medium	Work In Progress				8/15/2013 2:51:26 PM				
Nunez, Arturo		trim shrubs in front of office							
Laura Vazquez									
114452		Classroom			3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 3:23:06 PM				
Nunez, Arturo		PLEASE REMOVE WOODEN BOARDS IN THE ANTHONY PRE-K CLASSROOM FOR NEW ANTHONY FAMILY LITERACY CENTER AND INSTALL WHITE BOARDS IN PLACE OF THEM. THANK YOU. FOR FURTHER QUESTIONS PLEASE CALL RAY LARA AT 882-6799.							
Karla Quesada									
110293					11/15/2013		118		\$0.00
Medium	Work In Progress	TEACHER'S			11/15/2013 9:14:07 AM				
Nunez, Arturo		NEED A DOOR THRESHOLD INSTALLED TO PREVENT DIRT FROM COMING IN UNDER THE DOOR (M. HIDALGO 575-618-7459)							
Margaret Villalobos									
112584		Classroom			1/29/2014		43		\$0.00
Medium	Work In Progress	575-882-1904			1/29/2014 9:25:50 AM				
Nunez, Arturo		please paint all classrooms walls for rooms 101,102,103 and 104 thank you							
Laura Vazquez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Anthony - On Track Pre-K (Village)</b>										
114450		Restroom			3/10/2014		3		\$0.00	
Medium	Work In Progress				3/10/2014 3:20:18 PM					
Vega, David		RESTROOMS NEED TO BE THOROUGHLY CLEANED FOR NEW ANTHONY FAMILY LITERACY CENTER LOCATED AT THE ANTHONY PRE-K. THANK YOU. FOR FURTHER QUESTIONS PLEASE CALL RAY LARA @ 882-6799.								
Karla Quesada										
114371		Office			3/7/2014		6		\$0.00	
Medium	Work In Progress				3/7/2014 8:56:33 AM					
Gonzales, Camilo		Deliver 1 bx. Attn: Estrella Becerra, Family Literacy Center. PO# 131405360								
Theresa Ramirez										
114372		Office			3/7/2014		6		\$0.00	
Medium	Work In Progress				3/7/2014 8:58:07 AM					
Gonzales, Camilo		Deliver 1 bx. attn: Estrella Becerra, Family Literacy Center. PO#131405361								
Theresa Ramirez										
114373		Office			3/7/2014		6		\$0.00	
Medium	Work In Progress				3/7/2014 8:59:27 AM					
Gonzales, Camilo		Deliver 1 bx. attn: Estrella Becerra, Family Literacy Center. PO# 131405362								
Theresa Ramirez										
<b>Count: 10 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>60</b>	<b>Total for Anthony - On Track Pre-K (Village)</b>			<b>0</b>	<b>\$0.00</b>	

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
105552					8/7/2013		218		\$0.00
Medium	Work In Progress	SPED OFFICE			8/7/2013 7:58:25 AM				
Nunez, Arturo		ASSEMBLE DESK FOR MARGARET (SEE MARGARET OR JULIE)							
Margaret Villalobos									
114126					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:27:00 AM				
Nunez, Arturo		Monthly - Anthony ES Monthly FE Inspection - Refer to PMs schedule details.							
Margret Villalobos									
113939					2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:58 AM				
Munoz, Michael		Yearly - Anthony ES - Fire Pump Inspection - Refer to PMs schedule details.							
Margret Villalobos									
114440	Main Building				3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 12:46:04 PM				
Carrasco, Danny		need 2 50ft hoses and 2 sprinklers							
David Vega									
114376	Main Building				3/7/2014		6		\$0.00
Medium	Work In Progress				3/7/2014 10:45:52 AM				
Carbajal, Jimmy		vaccum cleaner serial#05372 does not turn on							
David Vega									
114435	Main Building				3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 10:27:32 AM				
Carbajal, Jimmy		need vaccum brush							
David Vega									
114496	Main Building				3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 11:09:31 AM				
Carbajal, Jimmy		vaccum cleaner serial #05387, electrical plug is not working							
David Vega									
113266					2/11/2014		30		\$0.00
Medium	Work In Progress				2/11/2014 2:09:00 PM				
Solis, Lorenzø		As per Silver, Fire panel going off. Sound & Signal has check the panel. The A/C units are causing the system to go off.							
Cora Ramirez									
3/13/2014 10:49:48 AM									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Anthony ES</b>							
113912					2/28/2014	3/31/2014	13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:43 AM				
Nunez, Arturo		Yearly - Anthony ES C-11 (Evap.Down)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
114016					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:07 AM				
Nunez, Arturo		Yearly - Anthony ES A10(Heat Pumps)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
114017					3/2/2014	4/2/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:08 AM				
Nunez, Arturo		Yearly - Anthony ES R3 (Ref. Unit)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
107934					9/25/2013		169		\$0.00
Medium	Work In Progress				9/25/2013 3:15:54 PM				
Marquez, Gerardo		Lock on wall marque in foyer area needs to be replaced.							
Arturo Nunez									
112747					1/31/2014		41		\$0.00
Medium	Work In Progress				1/31/2014 3:57:45 PM				
Sotelo, Enrique		Out side lights around building needs to be replaced, will need 20 bulbs, and bucket truck.							
Arturo Nunez									
109941					11/5/2013		128		\$0.00
Medium	Work In Progress				11/5/2013 3:58:09 PM				
Sotelo, Enrique		Need a emergency light balast for boys restroom.(lay in light fix.)							
Arturo Nunez									
110042					11/7/2013		126		\$0.00
Medium	Work In Progress				11/7/2013 3:55:07 PM				
Villalobos, David		Water pressure relief valve needs to be replaced on boiler.							
Arturo Nunez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
111475					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:16 AM				
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
113707					2/24/2014		17		\$0.00
Medium	Work In Progress	SPED OFFICE			2/24/2014 12:44:13 PM				
Nunez, Arturo		INSTALL BOARD IN FRONT OFFICE FOR DATA CLERKS (SEE DINO OR MARY)							
Margaret Villalobos									
114061					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:30 AM				
Nunez, Arturo		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114062					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:30 AM				
Nunez, Arturo		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111246					12/13/2013		90		\$0.00
Medium	Work In Progress				12/13/2013 11:58:48				
Nunez, Arturo		As per Ms. Perez, we need a sign that reads "Right turn only" for our drop off zone							
Jessica Lopez									
107813					9/23/2013		171		\$0.00
Medium	Work In Progress	office			9/23/2013 1:42:18 PM				
Nunez, Arturo		Mr. Nunez please hang flags Location : office							
Jessica Lopez									
107732					9/20/2013		174		\$0.00
Medium	Work In Progress	SPED			9/20/2013 9:21:01 AM				
Nunez, Arturo		NEED TO RE-CAULK THE WINDOW PANES IN THE DIRECTORS OFFICE (CAULKING IS FALLING OFF)							
Margaret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
103957					7/2/2013		254		\$0.00
Medium	Work In Progress	SPED OFFICE			7/2/2013 9:37:24 AM				
Nunez, Arturo		INSTALL WINDOW BLINDS IN THE FRONT OFFICE WINDOW (PREFERABLY BIG SLATS BUT LITTLE SLATS WILL DO)							
Margaret Villalobos									
103966					7/2/2013		254		\$0.00
Medium	Work In Progress	SPED OFFICE			7/2/2013 3:02:37 PM				
Nunez, Arturo		MOVE DESK FROM BUDGET CLERK OFFICE INTO OTHER OFFICE SEE MARGARET							
Margaret Villalobos									
103967					7/2/2013		254		\$0.00
Medium	Work In Progress	SPED OFFICE			7/2/2013 3:03:37 PM				
Nunez, Arturo		MOVE DESK AND SHELVES FROM MARGARET'S OFFICE INTO NEW EARLY CHILDHOOD OFFICE (SEE MARGARET)							
Margaret Villalobos									
111532					1/5/2014		67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:48 AM				
Holguin, Alfredo		Monthly - Anthony ES - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
108415					10/6/2013		158		\$0.00
Medium	Work In Progress				10/6/2013 12:24:12 AM				
Holguin, Alfredo		Monthly - Anthony ES - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
111185					12/11/2013		92		\$0.00
Medium	Work In Progress				12/11/2013 3:52:18 PM				
Flores, Pete		Need to have vechile # 70 checked starter is dragging, having trouble getting started.							
Arturo Nunez									
114407					3/9/2014	3/25/2014	4		\$0.00
Medium	Work In Progress				3/9/2014 12:18:56 AM				
Nunez, Arturo		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
113155					2/9/2014	2/25/2014	32		\$0.00
Medium	Work In Progress				2/9/2014 12:20:53 AM				
Nunez, Arturo		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 30 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>81</b>			<b>Total for Anthony ES</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Berino ES

114406 3/9/2014 3/25/2014 4 \$0.00

Medium Work In Progress 3/9/2014 12:18:55 AM

Duran, Adan Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.

Margret Villalobos

113310 2/12/2014 29 \$0.00

Medium Work In Progress 2/12/2014 9:26:34 AM

Holguin, Alfredo MR MIKE MUNOZ SIR WILL NEED ENGINEERED WOOD FIBER FOR THREE SET OF SWINGS HAVE SAND ALSO NMSU HEAD START HAS A SMALL CLIMMING EQUIPMENT IN THE EARLY CHILDHOOD PLAYGROUND ALSO HAS SAND THANK YOU SIR AND GOD BLESS

Adan Duran

113361 2/13/2014 28 \$0.00

Medium Work In Progress 2/13/2014 8:13:24 AM

Sanchez, Raul MR RUAL SANCHEZ SIR THE AIR RELIFE VALUE IS LEAKING WATER IRRIGATION WELL CAN YOU CHECK PLEASE THANK YOU AND GOD BLESS

Adan Duran

108416 10/6/2013 158 \$0.00

Medium Work In Progress 10/6/2013 12:24:12 AM

Holguin, Alfredo Monthly - Berino ES - Fire Pump Engine - Refer to PM schedule details.

Margret Villalobos

111476 1/5/2014 2/5/2014 67 \$0.00

Medium Work In Progress 1/5/2014 12:23:16 AM

Villalobos, David Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

114278 3/5/2014 8 \$0.00

Medium Work In Progress 3/5/2014 3:06:08 PM

Villalobos, David MR DAVID VILLALOBOS SIR NEED TWO FLUSHMATE CARTRIDGES FOR COMODE C-100500 KITS THANK YOU SIR AND GOD BLESS

Adan Duran

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Berino ES</b>									
113967					2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 3:19:40 PM				
Sotelo, Enrique		MR ENRIQUE SOTELO SIR NEED THREE BOXS OF LIGHT BULBS SP-35 2 FT LONG NEW RESTROOMS THANK YOU SIR AND GOD BLESS							
Adan Duran									
109171					10/22/2013		142		\$0.00
Medium	Work In Progress				10/22/2013 1:13:52 PM				
Sotelo, Enrique		MR ENRIQUE SOTELO SIR NEED TO REPLACE LIGHT BULBS ON POST NEAR MR MORGAN BUILDING AND PUMP HOUSE TO LIGHTS TOO DARK THANK YOU SIR AND GOD BLESS PS WILL NEED LIFT							
Adan Duran									
113940					2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:58 AM				
Munoz, Michael		Yearly - Berino ES - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
111198					12/12/2013		91		\$0.00
Medium	Work In Progress				12/12/2013 9:16:28 AM				
Marquez, Gerardo		MR JERRY MARQUEZ SIR ROOM 140 IS SPECAIL ED FOR HANDY-CAP NEED TO SECURE THE DOOR FROM THE INSIDE HAVE KIDS THAT ARE RUNNERS DOOR HAS HANDLE AND THEY ARE ABLE TO OPEN VERY EASY NEED A SAFETY COVER ITS A SAFETY CONCERN THANK YOU SIR AND GOD BLESS MRS RAMIREZ WANTS IT ASAP							
Adan Duran									
114554					3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 10:04:34 AM				
Carbajal, Jimmy		vaccum has a short lo6c00000198							
Jimmy Cortez									
<b>Count: 11 Work Orders</b>		<b>Avg. Age of WO's 50</b>		<b>Total for Berino ES</b>		<b>0</b>	<b>\$0.00</b>		

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
111236					12/12/2013		91		\$0.00
Medium	Work In Progress				12/12/2013 4:03:00 PM				
Marquez, Gerardo		warranty 1 of the 8 new doors installed oil leaking from door closer.							
Paul Quinones									
114123					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:59 AM				
Quinones, Paul		Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
112851					2/2/2014	2/8/2014	39		\$0.00
Medium	Work In Progress				2/2/2014 12:26:44 AM				
Quinones, Paul		Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
112869					2/2/2014	2/10/2014	39		\$0.00
Medium	Work In Progress				2/2/2014 12:26:52 AM				
Quinones, Paul		Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114138					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:27:06 AM				
Quinones, Paul		Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
113761	E. Building	Classroom			2/25/2014		16		\$0.00
Medium	Work In Progress	414			2/25/2014 12:59:26 PM				
Marquez, Gerardo		cabinet keys, file cabinet, storage cabinet need new keys. See Ms. Quinn							
Jennifer Corral									
112922					2/3/2014		38		\$0.00
Medium	Work In Progress				2/3/2014 3:35:34 PM				
Vallejo, Albert		NEED AN ELECTRICAL OUTLET FOR EPSON PROJECTOR SCREEN IN THE BOOK RM.							
Paul Quinones									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
112632					1/29/2014		43		\$0.00
Medium	Work In Progress				1/29/2014 3:59:28 PM				
Vallejo, Albert		e-wing porching areas requesting more lighting on both sides of porches.							
Paul Quinones									
113925					2/28/2014	3/31/2014	13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:50 AM				
Quinones, Paul		Yearly - Chaparral ES C-11 Evap (Annual) - Refer to PM schedule details.							
Margret Villalobos									
113998					3/2/2014	3/23/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:25:57 AM				
Quinones, Paul		Monthly - Chaparral ES H-11 Unit Heater Semiannual - Refer to PM schedule details.							
Margret Villalobos									
114000					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:25:59 AM				
Quinones, Paul		Yearly - Chaparral ES A-10 HP Rooftop Yearly - Refer to PM schedule details.							
Margret Villalobos									
113999					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:25:58 AM				
Quinones, Paul		Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.							
Margret Villalobos									
113926					2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:51 AM				
Quinones, Paul		Monthly - Chaparral ES A-16 Exh Fan (Semi Annual) - Refer to PM schedule details.							
Margret Villalobos									
114260					3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 8:32:09 AM				
Villalobos, David		back flow leaking water from vent location front of school fence line.							
Paul Quinones									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
111474					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress			1/5/2014 12:23:15 AM					
Villalobos, David		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
113065					2/6/2014		35		\$0.00
Medium	Work In Progress			2/6/2014 9:05:27 AM					
Quinones, Paul		need to paint rest rms.main building,and e-wing.							
Paul Quinones									
113626					2/20/2014		21		\$0.00
Medium	Work In Progress			2/20/2014 3:55:07 PM					
Quinones, Paul		paint bus turnaround traffic yellow							
Paul Quinones									
110568					11/22/2013		111		\$0.00
Medium	Work In Progress			11/22/2013 3:51:45 PM					
Ontiveros, Guadalupe		pressure tank will not stop draining water shut off back flow in front of che,and at the middle school and gate valves next to pressure tank							
Paul Quinones									
107095					9/4/2013		190		\$0.00
Medium	Work In Progress			9/4/2013 4:03:38 PM					
Ontiveros, Guadalupe		irragation water line next to the water tank water leak water line connecting pump and motor							
Paul Quinones									
114271		Classroom			3/5/2014		8		\$0.00
Medium	Work In Progress	414		3/5/2014 9:47:57 AM					
Marquez, Gerardo		cabinet keys, file cabinet, storage cabinet need new keys. See Ms. Quinn							
Jennifer Corral									
107334					9/11/2013		183		\$0.00
Medium	Work In Progress			9/11/2013 8:32:43 AM					
Quinones, Paul		requesting heavy duty coat hooks 3" type for class rms.need for student back packs							
Paul Quinones									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
106592					8/27/2013		198		\$0.00
Medium	Work In Progress				8/27/2013 2:53:40 PM				
Quinones, Paul		girls rest rm. in e-wing,metal latches are broken that secure doors.latches need to be replaced							
Paul Quinones									
108667					10/10/2013		154		\$0.00
Medium	Work In Progress				10/10/2013 7:56:32 AM				
Quinones, Paul		need 18" thermocouples for wall heaters universal type							
Paul Quinones									
107982					9/26/2013		168		\$0.00
Medium	Work In Progress				9/26/2013 9:31:41 AM				
Quinones, Paul		need leather washers for the blower wheel housing shaft for 6500 and 4800 evap.coolers							
Paul Quinones									
110213					11/13/2013		120		\$0.00
Medium	Work In Progress				11/13/2013 3:50:22 PM				
Quinones, Paul		need a gas valve for a roof top heater rm.205							
Paul Quinones									
109444					10/28/2013		136		\$0.00
Medium	Work In Progress				10/28/2013 3:58:57 PM				
Quinones, Paul		module board for heater in rm.214							
Paul Quinones									
110760					12/3/2013		100		\$0.00
Medium	Work In Progress				12/3/2013 8:40:13 AM				
Quinones, Paul		needing hvac parts for heater repair and restock							
Paul Quinones									
111045					12/9/2013		94		\$0.00
Medium	Work In Progress				12/9/2013 1:11:15 PM				
Quinones, Paul		need a gas valve for wall heater in rm.510 requesting 3 gas valves 2 for stock							
Paul Quinones									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Chaparral ES

112827 2/2/2014 2/10/2014 39 \$0.00

Medium Work In Progress 2/2/2014 12:26:33 AM

Quinones, Paul Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PMschedule details.

Margret Villalobos

112640 1/30/2014 42 \$0.00

Medium Work In Progress 1/30/2014 8:53:46 AM

Quinones, Paul need exhaust fan motors and and blower wheels for rest rm.for the 200 wing class rm.rest rms.

Paul Quinones

114090 3/2/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:43 AM

Quinones, Paul Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PMschedule details.

Margret Villalobos

114091 3/2/2014 3/10/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:43 AM

Quinones, Paul Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PMschedule details.

Margret Villalobos

113282 2/11/2014 30 \$0.00

Medium Work In Progress 2/11/2014 3:46:16 PM

Quinones, Paul need 2"x12"x12' boards for portable ramps

Paul Quinones

112474 1/27/2014 45 \$0.00

Medium Work In Progress 1/27/2014 9:28:12 AM

Quinones, Paul need door kick plates for 8 doors in the main building,and cafeteria

Paul Quinones

110886 12/5/2013 98 \$0.00

Medium Work In Progress 12/5/2013 9:29:57 AM

Gonzalez, Salvador DOUBLE DOORS IN BACK OF KITCHEN EXIT NEED A DOOR HEADER TO SUPPORT THE DOOR CLOSER.

Paul Quinones

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
113279					2/11/2014		30		\$0.00
Medium	Work In Progress				2/11/2014 3:42:24 PM				
Holguin, Alfredo		playground surfacing upgrade total of 4 playgrounds pre -k playground no borders supporting sand measurements 20'x30' total of 3 5 to 12 playgrounds need to replace approx. 30 biege borders for 2 playgrounds							
<b>Paul Quinones</b>									
113168					2/9/2014	2/25/2014	32		\$0.00
Medium	Work In Progress				2/9/2014 12:21:00 AM				
Quinones, Paul		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
<b>Margret Villalobos</b>									
114421					3/9/2014	3/25/2014	4		\$0.00
Medium	Work In Progress				3/9/2014 12:19:04 AM				
Quinones, Paul		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
<b>Margret Villalobos</b>									
<b>Count: 38 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>60</b>		<b>Total for Chaparral ES</b>	<b>0</b>		<b>\$0.00</b>



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral High - Pre-K</b>									
114439					3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 11:19:16 AM				
Villalobos, Margret		Need to fumigate Pre-k to many ants.				Approved 50.00			
Alfredo Ortiz									
113131		Exterior			2/7/2014		34		\$0.00
Medium	Work In Progress				2/7/2014 2:44:26 PM				
Appelzoller, Fred		Need to replace broken bubblers on drinking fountain, on playground.							
Alfredo Ortiz									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>19</b>		<b>Total for Chaparral High - Pre-K</b>	<b>0</b>		<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Chaparral HS</b>							
111495					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:26 AM				
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
113315		Gym			2/12/2014		29		\$0.00
Medium	Work In Progress				2/12/2014 10:50:23 AM				
Vallejo, Albert		please check controller to scoreboard and scoreboard for proper operation. thank you							
Michael Munoz									
113398		Parking Lot			2/13/2014		28		\$0.00
Medium	Work In Progress				2/13/2014 3:35:44 PM				
Marquez, Gerardo		Need six new locks for gates							
Alfredo Ortiz									
110544		Exterior			11/22/2013		111		\$0.00
Medium	Work In Progress				11/22/2013 10:19:33				
Marquez, Gerardo		Need to install Security doors on baseball and softball storage sheds							
Alfredo Ortiz									
111783		Lift Station			1/8/2014		64		\$0.00
Medium	Work In Progress				1/8/2014 9:34:54 AM				
Marquez, Gerardo		Need key for gate on pump station.							
Alfredo Ortiz									
112715		Athletic Field			1/31/2014		41		\$0.00
Medium	Work In Progress				1/31/2014 11:54:52 AM				
Valdez, Pedro		Need to move the portable bleachers to Baseball and softball fields							
Alfredo Ortiz									
114269					3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 9:38:14 AM				
Valdez, Pedro		Running Track - grass is growing between concrete curb and running track need to spray (kill) weeds.							
Alfredo Holguin									
111278					12/15/2013		88		\$0.00
Medium	Work In Progress				12/15/2013 12:18:11				
Valdez, Pedro		Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.							
Margret Villalobos									
3/13/2014 10:49:48 AM									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Chaparral HS**

114326 Athletic Field 3/6/2014 7 \$0.00

Medium Work In Progress 3/6/2014 12:18:54 PM

Ontiveros, Guadalupe Attention to Athletics Grounds request 1 pallet of sod for soccer field goal area.

Alfredo Ortiz

114015 3/2/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:07 AM

Ortiz, Alfredo Yearly - Chaparral HS A10 (Heat Pump)(Yearly) - Refer to PM schedule details.

Margret Villalobos

113911 2/28/2014 3/31/2014 13 \$0.00

Medium Work In Progress 2/28/2014 12:32:43 AM

Ortiz, Alfredo Yearly - Chaparral HS C11 (Evaporative)(Yearly) - Refer to PM schedule details.

Margret Villalobos

114111 3/2/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:53 AM

Apodaca, Mario Monthly - Chaparral HS - Grease Trap (Cul/Auto) - Refer to PM schedule details.

Margret Villalobos

114107 3/2/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:51 AM

Apodaca, Mario Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.

Margret Villalobos

114145 3/3/2014 10 \$0.00

Medium Work In Progress 3/3/2014 8:40:17 AM

Gonzalez, Salvador BLDG. MECH. IS REQUESTING INSTALLATION OF METAL SECURITY DRS. ON ALL ATHLETICS STORAGE SHEDS AND TICKET OFFICE. ONE OF THE STORAGE SHEDS IS AN ODD SIZE AND NEEDS TO BE FABRICATED. WOULD YOU PLEASE CHECK IT OUT ASAP. PLEASE. THANKS.

Gerardo Marquez

112824 2/2/2014 39 \$0.00

Medium Work In Progress 2/2/2014 12:26:31 AM

Flores, Pete Monthly - CHS-UV-0513 PM Service - Refer to PM schedule details.

Margret Villalobos

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
110329					11/16/2013		117		\$0.00
Medium	Work In Progress				11/16/2013 12:18:08				
Flores, Pete		Yearly - Chaparral HS M-0405 (Z-Track) Grounds - Refer to PM schedule details.							
Margret Villalobos									
108413					10/6/2013		158		\$0.00
Medium	Work In Progress				10/6/2013 12:24:11 AM				
Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
111530					1/5/2014		67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:47 AM				
Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
112607					1/29/2014		43		\$0.00
High	Work In Progress				1/29/2014 3:27:57 PM				
Ortiz, Alfredo		alfredo, please install reflectors to gates on east and west entrances to lobo lanes. to many accidents. thank you							
Michael Munoz									
114267					3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 9:33:15 AM				
Ortiz, Alfredo		Need to replace broken Bolt Cutter. Old one won't cut lock just bends. A greas gun old one don't work.							
Alfredo Ortiz									
114058					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:28 AM				
Ortiz, Alfredo		Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
114059					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:29 AM				
Ortiz, Alfredo		Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Chaparral HS

114060					3/2/2014	4/2/2014	11		\$0.00
--------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				3/2/2014 12:26:29 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ortiz, Alfredo Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

113792	A-Wing	Roof			2/25/2014		16		\$0.00
--------	--------	------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2014 3:37:04 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ortiz, Alfredo Need to remove sand from roof-top.

Alfredo Ortiz

113966	A-Wing	Office			2/28/2014		13		\$0.00
--------	--------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/28/2014 3:18:18 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ortiz, Alfredo Need to fix walls corners broken and repaint.

Alfredo Ortiz

110845	A-Wing	Cafeteria			12/4/2013		99		\$0.00
--------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/4/2013 2:06:04 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo Need to replace compressor On unit: TRANE MO# CSHC075K0Aoo SER# 063310MG2A PART# 570008750800 # 3D- SCROLL LRA 95.

Alfredo Ortiz

105363	A-Wing	Office			8/5/2013		220		\$0.00
--------	--------	--------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/5/2013 8:11:06 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo Please make 1 copy of keys #238 & #142 for the nurse's filing cabinet. These are the Fire king cabinets. (Ms. deCastro)

Mireya Meza

110188	A-Wing	Hallway/Corridor			11/13/2013		120		\$0.00
--------	--------	------------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2013 11:12:20				
--------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo The outside door to A wing by ISS class room is not working. When I put my key in it just turns and keeps turning all the way around. Please fix ASAP for security reasons. The rooms close to this door are ISS and CAP. (Lupe Quinones, security)

Mireya Meza

114320	A-Wing	Office			3/6/2014		7		\$0.00
--------	--------	--------	--	--	----------	--	---	--	--------

Medium	Work In Progress	Front Office			3/6/2014 8:52:15 AM				
--------	------------------	--------------	--	--	---------------------	--	--	--	--

Gonzales, Camilo Please pick up one box of toner for Sharp printers that are not longer with the district. (Mireya Meza)

Mireya Meza

3/13/2014 10:49:49 AM

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
113954	A-Wing				2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 8:20:12 AM				
Carrasco, Danny		Direct to Danny Warehouse	Need escotching for fire						
Alfredo Ortiz		sprinkler system heads							
112967	B-Wing	Classroom			2/4/2014		37		\$0.00
Medium	Work In Progress				2/4/2014 3:30:31 PM				
Appelzoller, Fred		Need to replace faucets in B-2 restroom,	need hot						
Alfredo Ortiz		water.							
113596	B-Wing	Restroom			2/20/2014		21		\$0.00
Medium	Work In Progress				2/20/2014 12:40:26 PM				
Appelzoller, Fred		In B-wing staff restroom faucet broke	need to replace.						
Alfredo Ortiz									
113024	C-Wing	Classroom			2/5/2014		36		\$0.00
Medium	Work In Progress	C3			2/5/2014 1:56:27 PM				
Sotelo, Enrique		The wall plug that connects my computer	to my projector						
Mireya Meza		is not working. I need to have it checked	please. (Ms. Jamagin, C3)						
112571	C-Wing	Classroom			1/29/2014		43		\$0.00
Medium	Work In Progress	work room in C			1/29/2014 8:14:54 AM				
Solis, Lorenzo		Refrigerator is not working in C printer	room. (Mr. Velarde)						
Mireya Meza									
113090	F-Wing	Hallway/Corridor			2/6/2014		35		\$0.00
Medium	Work In Progress				2/6/2014 3:19:13 PM				
Appelzoller, Fred		No hot water in F-wing water heater	will not start.						
Alfredo Ortiz									
114301	F-Wing	Classroom			3/5/2014		8		\$0.00
Medium	Work In Progress	F3			3/5/2014 4:08:42 PM				
Ortiz, Alfredo		5 broken chairs from ECHS top half/back	of chair came off metal frame, found in storage room. (Ms. Locke, room F3)						
Mireya Meza									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
114317	G-Wing	Classroom			3/6/2014		7		\$0.00
Medium	Work In Progress	G3			3/6/2014 8:17:41 AM				
Marquez, Gerardo		The lock to my desk is broken. (Ms. Pranses, G3)							
Mireya Meza									
109908	I-Wing	Classroom			11/5/2013		128		\$0.00
Medium	Work In Progress				11/5/2013 12:41:09 PM				
Marquez, Gerardo		Need to replace door in Band room broken.							
Alfredo Ortiz									
111037	I-Wing	Kitchen			12/9/2013		94		\$0.00
Medium	Work In Progress				12/9/2013 11:16:02 AM				
Gonzalez, Salvador		Rack on oven broke need to weld together.							
Alfredo Ortiz									
105851	Q-Wing	Classroom			8/12/2013		213		\$0.00
Medium	Work In Progress				8/12/2013 10:14:14 AM				
Marquez, Gerardo		The wrestling/tennis room share a door with Q2. This door is locked on my side but it can be opened from the neighboring room without a key. There is a large amount of valuable equipment in Q2 and I would feel better knowing that all access points were secure. Perhaps it would be possible to have the door lock both directions. (Mr. Woodard)							
Mireya Meza									
110349	Q-Wing	Hallway/Corridor			11/18/2013		115		\$0.00
Medium	Work In Progress				11/18/2013 2:44:10 PM				
Ortiz, Alfredo		Need to order fan duct for exhaust fans with squirl cage.							
Alfredo Ortiz									
114227	Q-Wing	Roof			3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 3:40:57 PM				
Ortiz, Alfredo		Need to replace filters on Industrial A/C units in Q-build.							
Alfredo Ortiz									
113215	Q-Wing	Roof			2/10/2014		31		\$0.00
Medium	Work In Progress				2/10/2014 1:51:09 PM				
Ortiz, Alfredo		Need to replace motor on A/C unit burn-out. Replace clean machine too. Industrial unit.							
Alfredo Ortiz									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
113575	Q-Wing	Classroom			2/19/2014		22		\$0.00
Medium	Work In Progress				2/19/2014 3:56:36 PM				
Ortiz, Alfredo		Need to install a Line Duct Exhaust Fan in Q-4 for Laicer.							
Alfredo Ortiz									
111112	Q-Wing	Classroom			12/10/2013		93		\$0.00
Medium	Work In Progress				12/10/2013 3:29:18 PM				
Marquez, Gerardo		Need to replace door handle broke off.In Q-6 Auto shop.							
Alfredo Ortiz									
109849	Q-Wing	Classroom			11/4/2013		129		\$0.00
Medium	Work In Progress				11/4/2013 2:26:13 PM				
Vallejo, Albert		Please lower some of the power supplies so that we could use them for setting up the computers (south side of the room), please see me to clarify request. (Mr. Woodard, Q2)							
Mireya Meza									
109910	R-Wing	Classroom			11/5/2013		128		\$0.00
Medium	Work In Progress				11/5/2013 12:48:59 PM				
Marquez, Gerardo		Need to install pull handle in Culinary classroom.							
Alfredo Ortiz									
112063	Field House	Athletic Field			1/14/2014		58		\$0.00
Medium	Work In Progress	SOCCER FIELD			1/14/2014 10:21:30 AM				
Valdez, Pedro		GROUNDS - CHAPARRAL HS BACKSTOP - SOCCER FIELD ON LOBO LANE SIDE.							
Terry Alvarado									
112230	Field House	Athletic Field			1/17/2014		55		\$0.00
Medium	Work In Progress	Baseball Fields			1/17/2014 9:42:07 AM				
Valdez, Pedro		Install wind screen at baseball field. (Mr. Martinez, baseball varsity asst. coach)							
Mireya Meza									
112702	Field House	Athletic Field			1/31/2014		41		\$0.00
Medium	Work In Progress	Softball field			1/31/2014 9:07:26 AM				
Sotelo, Enrique		Can I get an electric outlet out by my batting cage and an outlet by 3rd base dug out. (Donna Heddleston, softball field)							
Mireya Meza									



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
108497	Field House	Exterior			10/7/2013		157		\$0.00
Medium	Work In Progress				10/7/2013 9:26:28 AM				
Marquez, Gerardo		Need to fix door knob and Locksets can't lock doors. At the ticket booth Field house.							
Alfredo Ortiz									
113314	Field House	Athletic Field			2/12/2014		29		\$0.00
Medium	Work In Progress				2/12/2014 10:45:25 AM				
Marquez, Gerardo		May need to change corse to trainer rooms to minimum access only to K3 keys. (Mireya Meza)							
Mireya Meza									
112029	Field House	Restroom			1/13/2014		59		\$0.00
Medium	Work In Progress				1/13/2014 3:42:07 PM				
Marquez, Gerardo		Old CH86 keys are not matching new cylinder in field house boys restroom area. Please check that all CH86 (athletics keys) match cylinder in field house area. (Mireya Meza)							
Mireya Meza									
112703	Field House	Athletic Field			1/31/2014		41		\$0.00
Medium	Work In Progress	softball field			1/31/2014 9:09:57 AM				
Valdez, Pedro		Can I get the softball shed by 3rd base painted. Preferably dark grey with black trim. (Donna Heddleston, softball field)							
Mireya Meza									
114192	H-Wing	Roof			3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 7:46:11 AM				
Vallejo, Albert		Need to replace switch and contactors on the Gym air handler.							
Alfredo Ortiz									
110273	H-Wing	Gym			11/14/2013		119		\$0.00
Medium	Work In Progress				11/14/2013 3:47:14 PM				
Vallejo, Albert		Need to replace several Ballast and light bulbs in Gym.							
Alfredo Ortiz									
113891	H-Wing	Gym			2/27/2014		14		\$0.00
Medium	Work In Progress				2/27/2014 3:43:40 PM				
Vallejo, Albert		Need to fix and replace the main. switche in one of the exauhst fans in the Gym.				3/6 Route to Albert asp Lorenzo			
Alfredo Ortiz									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
111885	H-Wing	Restroom			1/10/2014		62		\$0.00
Medium	Work In Progress				1/10/2014 9:09:39 AM				
Appelzoller, Fred		Need to replace several faucets in boys and girls restroom bent and sinks are loose.							
Alfredo Ortiz									
113501	H-Wing	Gym			2/18/2014		23		\$0.00
Medium	Work In Progress				2/18/2014 3:36:19 PM				
Ortiz, Alfredo		Need to service the Air handlers on the gym roof.							
Alfredo Ortiz									
113505	H-Wing	Gym			2/18/2014		23		\$0.00
Medium	Work In Progress				2/18/2014 3:44:27 PM				
Ortiz, Alfredo		Need to service the Air handlers on the gym roof.							
Alfredo Ortiz									
114259	H-Wing	Roof			3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 8:29:42 AM				
Carrasco, Danny		Attention to Dannywarehouse Need to order filters for cooling season.							
Alfredo Ortiz									
108049	H-Wing	Gym			9/27/2013		167		\$0.00
Medium	Work In Progress				9/27/2013 2:57:56 PM				
Marquez, Gerardo		Need to install door louvers on two storage doors because mole is growing on everything. Girls locker rooms in Gym.							
Alfredo Ortiz									
105660	H-Wing	Dressing Room			8/8/2013		217		\$0.00
Medium	Work In Progress				8/8/2013 9:52:01 AM				
Marquez, Gerardo		Please put the metal door back on. The door that is suppose to be between the girls basketball locker room and showers. (Ms. Lydia Guerrero, girls dressing room)							
Mireya Meza									
114266	Pre-K	Restroom			3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 9:22:44 AM				
Ortiz, Alfredo		Need to install floor drain sealers to stop drain odors.							
Alfredo Ortiz									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
106602		Lift Station			8/27/2013		198		\$0.00
Medium	Work In Progress				8/27/2013 3:28:14 PM				
Gonzalez, Salvador		need to retro fit pump bracket at storm water lift pump station outside and theater. (welding job)							
Mario Apodaca									
110070		Exterior			11/8/2013		125		\$0.00
Medium	Work In Progress				11/8/2013 3:20:29 PM				
Gonzalez, Salvador		Need to install Fence gate spoppers at main entrances.							
Alfredo Ortiz									
114248					3/5/2014		8		\$0.00
Medium	Work In Progress	AMBER			3/5/2014 7:27:11 AM				
Gonzales, Camilo		DELIVER PO #131405201 EL PASO OFFICE PRODUCTS 1 BOX AMBER DRISKILL, TEACHER							
Margaret Villalobos									
113466		Parking Lot			2/18/2014		23		\$0.00
Medium	Work In Progress				2/18/2014 8:20:48 AM				
Munoz, Michael		Need to fix fence, car hit and bent pole and fence.							
Alfredo Ortiz									
114483					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 7:17:17 AM				
Carbajal, Jimmy		vaccum sr 41100001164 needs plug. Plug in is broken.							
Jesus Urquidi									
114137					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:27:05 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
113941					2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:59 AM				
Munoz, Michael		Yearly - Chaparral HS - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 71 Work Orders</b>			<b>Avg. Age of WO's 57</b>			<b>Total for Chaparral HS</b>	<b>0</b>		<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral MS</b>									
109889					11/5/2013		128		\$0.00
Medium	Work In Progress				11/5/2013 8:53:26 AM				
Marquez, Gerardo		Doors by Band room will not close.							
Albert Vallejo									
113694					2/24/2014		17		\$0.00
Medium	Work In Progress				2/24/2014 10:33:49 AM				
Marquez, Gerardo		Door jamb is broken and needs to be welded. There is also a hole punched in the outer shell. Closer is also leaking oil.				route to Gerardo asp mike			
Albert Vallejo									
114246					3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 4:07:26 PM				
Munoz, Michael		need 8 -4x4 concrete pads poured in court yard for new green houses.							
Albert Vallejo									
111106					12/10/2013		93		\$0.00
Medium	Work In Progress				12/10/2013 3:17:58 PM				
Marquez, Gerardo		Please replace door closer. It has leaked the oil and cannot be adjusted.							
Albert Vallejo									
114322		Custodial			3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 9:31:06 AM				
Carbajal, Jimmy		nesecito un adjust ho rite plate para la aspiradora thank you							
M. Carmen Perez									
114127					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:27:01 AM				
Vallejo, Albert		Monthly - Chaparral MS Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
113944					2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 12:33:00 AM				
Munoz, Michael		Yearly - Chaparral MS - Fire Pump Inspection - Refer to PMschedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral MS</b>									
114361	Main Building	Restroom			3/7/2014		6		\$0.00
Medium	Work In Progress				3/7/2014 7:36:01 AM				
Perez, M. Carmen		Make sure all urinals have a urinal block with screens. This will make a big difference on the foul odor coming from the urinals. Assign : Perez, M. Carmen							
Jesus Estrada									
111055	Main Building	Computer Lab			12/9/2013		94		\$0.00
Medium	Work In Progress	311			12/9/2013 2:38:18 PM				
Vallejo, Albert		Please turn off heat-too warm							
Gidget Mora									
114494	Main Building	Classroom			3/11/2014		2		\$0.00
Medium	Work In Progress	201			3/11/2014 10:57:48 AM				
Vallejo, Albert		4 light need to be replaced							
Gidget Mora									
104768	Main Building	Office			7/26/2013		230		\$0.00
Medium	Work In Progress	Merry			7/26/2013 8:31:49 AM				
Marquez, Gerardo		Needs keys for desk							
Gidget Mora									
106128	Main Building	Computer Lab			8/16/2013		209		\$0.00
Medium	Work In Progress				8/16/2013 8:31:15 AM				
Solis, Lorenzo		Install refrigeration units for computer labs. Rooms 406 and 207.							
Albert Vallejo									
113486	Main Building	Classroom			2/18/2014		23		\$0.00
Medium	Work In Progress	405b			2/18/2014 2:27:27 PM				
Vallejo, Albert		Please install electrical outlet for projector							
Gidget Mora									
108954	Main Building	Restroom			10/16/2013		148		\$0.00
Medium	Work In Progress				10/16/2013 2:09:57 PM				
Appelzoller, Fred		Please replace 5 multiple sensor sinks. Not working, also install new basins.				asp Mike - Assign to Fred, but please add on to description to install new basins.			
Gidget Mora									
108717	Main Building	Hallway/Corridor			10/11/2013		153		\$0.00
Medium	Work In Progress	400 hall			10/11/2013 9:16:30 AM				
Vallejo, Albert		Please paint wall in 400 hallway							
Gidget Mora									
3/13/2014 10:49:49 AM									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral MS</b>									
114089					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:43 AM				
Flores, Pete		Monthly - CHM-UV-0514 PM Service - Refer to PM schedule details.							
Margret Villalobos									
113788					2/25/2014		16		\$0.00
Medium	Work In Progress	courtyard			2/25/2014 3:26:24 PM				
Vallejo, Albert		Please supply water for courtyard garden							
Gidget Mora									
113969					2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 3:25:25 PM				
Vallejo, Albert		(2-28-14) 6 hrs—Collect phones and time sheets, report to plant, then distribute materials; 1 hr—(112480) Install fixtures at fountain (CMS); 1 hr—Enter work log.				2/28/14 - 6 hrs			
Albert Vallejo									
114054					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:27 AM				
Vallejo, Albert		Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114055					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:27 AM				
Vallejo, Albert		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114056					3/2/2014	4/2/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:28 AM				
Vallejo, Albert		Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
114057					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:28 AM				
Vallejo, Albert		Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Chaparral MS</b>							
113693					2/24/2014		17		\$0.00
Medium	Work In Progress				2/24/2014 10:32:03 AM				
Vallejo, Albert		Need to repair hole in wall in boys athletic hallway.							
Albert Vallejo									
107344					9/11/2013		183		\$0.00
Medium	Work In Progress				9/11/2013 9:29:23 AM				
Vallejo, Albert		Replace damaged doors in 300 hallway restroom.							
Albert Vallejo									
111887					1/10/2014		62		\$0.00
Medium	Work In Progress				1/10/2014 9:52:13 AM				
Vallejo, Albert		Please order tools: 1. Transmitter 2. Line Locator 3. Inductive clamp 4. Phillips Drive bits 5. Hex Drive 4" Extension 6. Hex Drive 6" Extension							
Albert Vallejo									
113695					2/24/2014		17		\$0.00
Medium	Work In Progress				2/24/2014 10:36:05 AM				
Gonzalez, Salvador		Need retainers for drive gates at bus turn around.							
Albert Vallejo									
113696					2/24/2014		17		\$0.00
Medium	Work In Progress				2/24/2014 10:37:14 AM				
Gonzalez, Salvador		Need retaining clips at entrance to back hall.							
Albert Vallejo									
109831					11/4/2013		129		\$0.00
Medium	Work In Progress				11/4/2013 9:53:19 AM				
Gonzalez, Maritza		CHEMICAL CART IS RUSTED. SNP MANAGER SANDRA D. 824.4376.							
Maritza Gonzalez									
114505					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 3:05:02 PM				
Orozco, Daniel		I need to put in a work order for the pipe under the salad sink. The pipe leaks a lot. Thank you. SNP Manager Sandra D. 824.4376							
Maritza Gonzalez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Chaparral MS</b>							
113910					2/28/2014	3/31/2014	13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:42 AM				
Vallejo, Albert		Yearly - Chaparral MS C-11 (Swamp Coolers)Yearly) - Refer to PM schedule details.							
Margret Villalobos									
114018					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:08 AM				
Vallejo, Albert		Yearly - Chaparral MS A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
114444					3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 1:49:30 PM				
Solis, Lorenzø		The following A/C's are in need of replacement: AERO-CHM-004 (room 204); MCD-CHM-021 (room 309); MCD-CHM-025 (room 306); MCD-CHM-030 (room 205); MCD-CHM-048 (room 107); MCD-CHM-052 (room 104).							
Albert Vallejo									
113228					2/10/2014		31		\$0.00
Medium	Work In Progress				2/10/2014 3:31:45 PM				
Solis, Lorenzø		Compressor for A/C that serves 208 is not working properly. American Standard unit Model #BAYHTRN110A							
Albert Vallejo									
107339					9/11/2013		183		\$0.00
Medium	Work In Progress				9/11/2013 9:25:04 AM				
Solis, Lorenzø		Install refrigeration unit for comp lab in 406.							
Albert Vallejo									
114377					3/7/2014		6		\$0.00
Medium	Work In Progress				3/7/2014 10:57:09 AM				
Vallejo, Albert		Please paint locker rooms before new lockers are installed.							
Albert Vallejo									
112490					1/27/2014		45		\$0.00
Medium	Work In Progress				1/27/2014 3:03:21 PM				
Vallejo, Albert		Repair damaged light fixtures on fountain.							
Albert Vallejo									



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral MS</b>									
113787					2/25/2014		16		\$0.00
Medium	Work In Progress	courtyard			2/25/2014 3:25:13 PM				
Vallejo, Albert Please supply electricity for courtyard garden.									
Gidget Mora									
108615		Cafeteria			10/9/2013		155		\$0.00
Medium	Work In Progress				10/9/2013 11:06:30 AM				
Vallejo, Albert senesecita poner 5 lamparas en cafeteria GRACIAS									
M. Carmen Perez									
108618		Restroom			10/9/2013		155		\$0.00
Medium	Work In Progress				10/9/2013 11:17:29 AM				
Vallejo, Albert senesecita areglar swich del #300 hallway restroom boys GRACIAS									
M. Carmen Perez									
114378					3/7/2014		6		\$0.00
Medium	Work In Progress				3/7/2014 10:58:49 AM				
Valles, Johnny Repair soffit lighting.									
Albert Vallejo									
111477					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:16 AM				
Villalobos, David Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.									
Margret Villalobos									
111389		Hallway/Corridor			12/18/2013		85		\$0.00
Medium	Work In Progress				12/18/2013 7:52:00 AM				
Appelzoller, Fred senesecita areglar fuente de agua de tomar agua esta likiando agua del paciyo 100 GRACIAS									
M. Carmen Perez									
113987					3/2/2014	3/5/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:25:51 AM				
Vallejo, Albert Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.									
Margret Villalobos									
<b>Count: 43 Work Orders</b>			<b>Avg. Age of WO's 57</b>		<b>Total for Chaparral MS</b>			<b>0</b>	<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Desert Pride</b>							
112495		Pump House			1/27/2014		45		\$0.00
Medium	Work In Progress				1/27/2014 3:16:13 PM				
Villalobos, David		need your assistance on installing a new water meter and upgrading a water filter hous for the domestic water							
Mario Apodaca									
113997					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:25:57 AM				
Aguilar, Patricio		Yearly - Deset Pride HS A10(Heat Pumps)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
113922					2/28/2014	3/31/2014	13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:49 AM				
Aguilar, Patricio		Yearly - Desert Pride HS C11 (Evap.)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
113325		Parking Lot			2/12/2014		29		\$0.00
Medium	Work In Progress	front entrance			2/12/2014 2:00:14 PM				
Ontiveros, Guadalupe		need to add crusher fine and smooth out uneven front entrance ground.							
David Acosta									
111725		Custodial			1/7/2014		65		\$0.00
Medium	Work In Progress				1/7/2014 11:14:05 AM				
Lara, Ralph		Need to replace master key. Having problems opening doors.							
David Acosta									
112835					2/2/2014		39		\$0.00
Medium	Work In Progress				2/2/2014 12:26:36 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Water Samples - Refer to PMschedule details.							
Margret Villalobos									
113419					2/14/2014		27		\$0.00
Medium	Work In Progress				2/14/2014 12:22:33 AM				
Sanchez, Raul		Monthly - Desert Pride - Water Filters - Refer to PM schedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Pride</b>									
108955					10/16/2013		148		\$0.00
Medium	Work In Progress				10/16/2013 2:17:32 PM				
Gonzalez, Salvador		Need poles to divide the drop off and pick up parking area for safety of the children. Parents are double parking and kids are running in between the cars and could get hurt. Thank you, Ruben							
Ruben Ortiz									
114102					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:49 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
114066					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:32 AM				
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114067					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:32 AM				
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114124					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:59 AM				
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 12 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>35</b>		<b>Total for Desert Pride</b>	<b>0</b>		<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Trail Intermediate</b>									
105036					8/1/2013		224		\$0.00
Medium	Work In Progress				8/1/2013 9:27:19 AM				
Gonzalez, Salvador		Please install diamond metal plate to new portable ramps and decks.							
Johnny Acuna									
114560		Custodial			3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 11:40:20 AM				
Carbajal, Jimmy		Bueos dias Jimmypor favor puede revisar la aspiradora num.1162 el gendel no se detiene se cae gracias							
Laura Sandoval									
113198					2/10/2014		31		\$0.00
Medium	Work In Progress				2/10/2014 11:19:50 AM				
Ontiveros, Guadalupe		Need to borrow Bobcat tractor to finish up W.o. #112625							
Johnny Acuna									
114273		Cafeteria			3/5/2014		8		\$0.00
Medium	Work In Progress	cafeteria			3/5/2014 10:22:42 AM				
Gonzales, Camilo		Our custodian Laura needs broken convertible cafeteria benches picked up.							
Elizabeth Hernandez									
114323		Custodial			3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 10:29:14 AM				
Carbajal, Jimmy		Buenos dias Jimmyla aspiradora num.0214 se le callo la llantita si puede revisarla por favor gracias							
Laura Sandoval									
114324		Custodial			3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 10:39:43 AM				
Carbajal, Jimmy		Jimmy me puede remplasar los 3 cepillos de las aspiradoras que estan quebrados por favor gracias							
Laura Sandoval									
112970					2/4/2014		37		\$0.00
Medium	Work In Progress				2/4/2014 3:33:48 PM				
Lara, Ralph		main door in the front lobby, both main doors going out to the portables W/Door closures (middle hallway), Portable #409 main door W/Door closure, Portable #410 W/Door closure Need Doors to be Replaced.							
Johnny Acuna									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Trail Intermediate</b>									
113307					2/12/2014		29		\$0.00
Medium	Work In Progress				2/12/2014 8:46:33 AM				
Flores, Pete		Need to replace Bearing connected to Hydraulic steering shaft for the Steiner Tractor.							
Johnny Acuna									
111155					12/11/2013		92		\$0.00
Medium	Work In Progress				12/11/2013 11:20:25				
Flores, Pete		please check radiator to work truck #192. Radiator has a small pin hole leak on the side.							
Johnny Acuna									
114416					3/9/2014	3/25/2014	4		\$0.00
Medium	Work In Progress				3/9/2014 12:19:01 AM				
Acuna, Johnny		Monthly - Desert Trail Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
113826					2/26/2014		15		\$0.00
Medium	Work In Progress				2/26/2014 11:10:19 AM				
Holguin, Alfredo		Need more sand to kinder playground area, Need more sand to swing sets area, W.o. #113599: Need new soccer nets for Playground soccer goals, W.o. #111044: Need top soil to fill in low areas to playground grass area, Need 12 swing hangers with 12 S-Hooks for playground swings, Need approx. 22 borders for playground sand to the bigger playground area sets, Need to fix ground border area around swing sets.							
Johnny Acuna									
114315					3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 8:10:25 AM				
Acuna, Johnny		(Need a 24 gauge sheetmetal transition duct fitting) Base: 22" square all around with a 2" Height overlapping X 20 3/4" square with a 2" Lip all around.							
Johnny Acuna									
113259					2/11/2014		30		\$0.00
Medium	Work In Progress				2/11/2014 12:48:08 PM				
Orozco, Daniel		DRYER OUT. SNP MANAGER 824.3822							
Maritza Gonzalez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Trail Intermediate</b>									
113470					2/18/2014		23		\$0.00
Medium	Work In Progress				2/18/2014 10:12:09 AM				
Orozco, Daniel		GOOD MORNING: I'M HAVING PROBLEMS WITH THE ELECTRICAL FOR THE MILK COOLER. PLEASE REPLACE BOX (BROKEN), CHECK ELECTRICAL WIRING AND BREAKER CAUSE BREAKER SOMETIMES DOES NOT RESET. SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
114265					3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 9:09:45 AM				
Acuna, Johnny		Need 2 large rolls of vinyl window screen to repair torn or worn out screening to main building. Also, need 4 fix a flat cans for steiner tractor tires.							
Johnny Acuna									
110171					11/13/2013		120		\$0.00
Medium	Work In Progress				11/13/2013 7:51:21 AM				
Acuna, Johnny		Need new threshold for SW hall main doors.				11/20 - Reroute to J. Acuna			
Johnny Acuna									
112778					2/2/2014	2/10/2014	39		\$0.00
Medium	Work In Progress				2/2/2014 12:26:10 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114029					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:14 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
113599					2/20/2014		21		\$0.00
Medium	Work In Progress				2/20/2014 1:10:13 PM				
Ontiveros, Guadalupe		Need 2 sets of soccer goal nets for soccer goals in the playground grass area. Info and measurements have been mailed through District mail. Thank You.....							
Johnny Acuna									
111044					12/9/2013		94		\$0.00
Medium	Work In Progress				12/9/2013 12:40:09 PM				
Ontiveros, Guadalupe		Need to add top soil and level out playground grass area.							
Johnny Acuna									
3/13/2014 10:49:50 AM									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Desert Trail Intermediate

114244 3/4/2014 9 \$0.00

Medium Work In Progress 3/4/2014 4:01:11 PM

Ontiveros, Guadalupe Requesting 3 more loads of Primary Screening for portables area.

Johnny Acuna

108601 10/9/2013 155 \$0.00

Medium Work In Progress 10/9/2013 8:29:51 AM

Solis, Lorenzo Rooftop Reznor Heating Unit: South Unit on Westside on main building. Make: Reznor, Model: #HRPB200, Serial: #EAUD66Q2N28275 Needing Pressure Switch for Unit.  
(Unit does not ignite and turn on)

Johnny Acuna

113917 2/28/2014 3/31/2014 13 \$0.00

Medium Work In Progress 2/28/2014 12:32:46 AM

Acuna, Johnny Yearly - Desert Trail ES C-11 (Evap.Cool)(Yearly) - Refer to PM schedule details.

Margret Villalobos

114027 3/2/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:13 AM

Acuna, Johnny Yearly - Desert Trail ES A10 (Heat Pump)(Yearly) - Refer to PM schedule details.

Margret Villalobos

114552 3/12/2014 1 \$0.00

Medium Work In Progress cafeteria 3/12/2014 9:15:13 AM

Marquez, Gerardo We need a key made (J25) for Coach Dial.

Elizabeth Hernandez

113961 2/28/2014 13 \$0.00

Medium Work In Progress front office 2/28/2014 2:13:45 PM

Marquez, Gerardo Our secretary Elizabeth needs key made for display cabinet

Elizabeth Hernandez

113477 2/18/2014 23 \$0.00

Medium Work In Progress 2/18/2014 11:30:08 AM

Vallejo, Albert Need assistance in new installation of a Security light outside of wall to portable #413. Need electrical wiring, elect. box, etc.

Johnny Acuna

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Desert Trail Intermediate</b>										
112659					1/30/2014		42		\$0.00	
Medium	Work In Progress				1/30/2014 2:38:18 PM					
Appelzoller, Fred		Need to replace corroded flange to staff restroom								
Johnny Acuna										
111478					1/5/2014	2/5/2014	67		\$0.00	
Medium	Work In Progress				1/5/2014 12:23:17 AM					
Villalobos, David		Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
<b>Count: 29 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>39</b>	<b>Total for Desert Trail Intermediate</b>			<b>0</b>	<b>\$0.00</b>	



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert View ES</b>									
111479					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:17 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
114526					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 4:02:14 PM				
Ontiveros, Joe		Boys lower level urinal clogged. Tried to unclog but was unsuccessful. Thank you, Ruben							
Ruben Ortiz									
112082					1/14/2014		58		\$0.00
Medium	Work In Progress				1/14/2014 1:45:30 PM				
Ontiveros, Joe		Boys urinals upper level flush valves are not working; they are not shutting off							
Ruben Ortiz									
113602					2/20/2014		21		\$0.00
Medium	Work In Progress				2/20/2014 2:36:36 PM				
Ontiveros, Joe		The toilet in the nurses office is not flushing right. Thank you, Ruben							
Ruben Ortiz									
114449					3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 3:18:42 PM				
Ontiveros, Joe		Water leak in the library. Need is repaired ASAP. Thank you, Ruben							
Ruben Ortiz									
109214					10/22/2013		142		\$0.00
Medium	Work In Progress				10/22/2013 3:49:08 PM				
Castillo, Carlos		Need a light and switch outlet in the morgon.							
Ruben Ortiz									
107805					9/23/2013		171		\$0.00
Medium	Work In Progress				9/23/2013 10:04:11 AM				
Castillo, Carlos		Replace 26 light diffusers							
Ruben Ortiz									
113928					2/28/2014	3/31/2014	13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:52 AM				
Ortiz, Ruben		Yearly - Desert View ES C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
3/13/2014 10:49:50 AM									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert View ES</b>									
113994					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:25:55 AM				
Ortiz, Ruben		Yearly - Desert View ES A-10 HP Rooftop Yearly - Refer to PM schedule details.							
Margret Villalobos									
113328					2/12/2014		29		\$0.00
Medium	Work In Progress				2/12/2014 2:05:28 PM				
Ambriz, Jose		Lower level water fountain by the teacher's lounge is not working; needs to be replaced. Thank you, Ruben							
Ruben Ortiz									
114329					3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 1:34:07 PM				
Castillo, Carlos		In teachers lounge two lights are not working need to replace ballast. Thank you, Ruben							
Ruben Ortiz									
114525					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 4:01:17 PM				
Castillo, Carlos		Need set up of electricity for the 3rd Annual Desert View Carnival for Friday, May 2, 2014. Thank you, Ruben							
Ruben Ortiz									
104086					7/8/2013		248		\$0.00
Medium	Work In Progress				7/8/2013 1:30:24 PM				
Ambriz, Jose		A/C UNIT IN KITCHEN WENT OUT. SNP MANAGER DELORES R. 589.2425							
Maritza Gonzalez									
103915					7/1/2013		255		\$0.00
Medium	Work In Progress				7/1/2013 1:06:14 PM				
Ambriz, Jose		Water fountain needs to be replaced in the front office on the east side of the school.							
Ruben Ortiz									
113604					2/20/2014		21		\$0.00
Medium	Work In Progress				2/20/2014 2:39:18 PM				
Ontiveros, Guadalupe		The buster pump is not working for irrigation. Need it ASAP. Thank you, Ruben							
Ruben Ortiz									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Desert View ES</b>							
112520					1/28/2014		44		\$0.00
Medium	Work In Progress				1/28/2014 1:19:08 PM				
Lara, Ralph		Portable 6 room A; need a new door and frame replaced due to safety hazard							
Ruben Ortiz									
113004		Classroom			2/5/2014		36		\$0.00
Medium	Work In Progress	Portable A			2/5/2014 8:56:47 AM				
Lara, Ralph		2nd Request: The lock to the door is broken. (Sanchez)							
Guadalupe Gonzalez									
113005		Classroom			2/5/2014		36		\$0.00
Medium	Work In Progress	Rm. 15A			2/5/2014 9:00:44 AM				
Lara, Ralph		2nd Request: The lock on the door is broken. (Garcia)							
Guadalupe Gonzalez									
112567		Classroom			1/29/2014		43		\$0.00
Medium	Work In Progress	Rm. #15 A			1/29/2014 7:49:55 AM				
Lara, Ralph		The lock to the door broke. (Garcia)							
Guadalupe Gonzalez									
114422					3/9/2014	3/25/2014	4		\$0.00
Medium	Work In Progress				3/9/2014 12:19:04 AM				
Ortiz, Ruben		Monthly - Desert View ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
114528					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 4:03:46 PM				
Ortiz, Ruben		Items needed for Carnival 100 feet heavy duty extension cord 50 feet heavy duty extension cord 25 feet heavy duty extension cord							
Ruben Ortiz									
114531					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 4:05:13 PM				
Ortiz, Ruben		Items needed for Carnival 100 feet heavy duty water holes 2 of 50 feet heavy duty water holes 1 heavy duty rake							
Ruben Ortiz									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert View ES</b>									
114328					3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 1:32:46 PM				
Ortiz, Ruben		Need to weed and feed the grass in the front circle and on the side of the school							
Ruben Ortiz									
114330					3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 1:58:56 PM				
Ortiz, Ruben		Need to change light bulbs in classrooms.							
Ruben Ortiz									
114095					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:45 AM				
Ortiz, Ruben		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
113308					2/12/2014		29		\$0.00
Medium	Work In Progress				2/12/2014 9:04:05 AM				
Ortiz, Ruben		Need to patch up or retile the front entrance of the school; due to safety hazard.							
Ruben Ortiz									
112602					1/29/2014		43		\$0.00
Medium	Work In Progress				1/29/2014 2:55:08 PM				
Ortiz, Ruben		AS PER HEALTH ENVIRONMENT INSPECTION DAMAGED WALLS NEED TO BE ADDRESSED IN DISHWASHING ROOM.							
Maritza Gonzalez									
108895					10/15/2013		149		\$0.00
Medium	Work In Progress	Lower Grade			10/15/2013 12:54:01				
Ortiz, Ruben		Repair the swings; some are broken and/or tangled.							
Guadalupe Gonzalez									
108896					10/15/2013		143		\$0.00
Medium	Work In Progress	Outside the			10/15/2013 1:06:30 PM	3/7/2014			
Ortiz, Ruben		Put trash cans on the outside of the north upper grade level.				3/7/14-work order was forwarded to building mechanic, need trash barrels - I. Ortega			
Guadalupe Gonzalez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert View ES</b>									
106257		Classroom			8/20/2013		205		\$0.00
Medium	Work In Progress	Rm. #16			8/20/2013 7:44:28 AM				
Ortiz, Ruben		There are ants in the classroom. If can put caulking around the window. (M. Mack)							
Guadalupe Gonzalez									
113907		Computer Lab			2/27/2014		14		\$0.00
Medium	Work In Progress	Rm 76			2/27/2014 9:51:49 PM				
Ortiz, Ruben		Install Infocus projector on ceiling.							
Albert Ortiz									
104962					7/31/2013		225		\$0.00
Medium	Work In Progress				7/31/2013 8:07:41 AM				
Gonzalez, Salvador		Vandalism; need a new library stand the was destroyed in vandalism. Thank you, Ruben							
Ruben Ortiz									
114337		Library			3/6/2014		7		\$0.00
Medium	Work In Progress	Library			3/6/2014 3:22:43 PM				
Gonzales, Camilo		Pick up a Blue Multimedia Display from the Library and deliver to Desert Pride Academy. (A. Segura)							
Guadalupe Gonzalez									
114120					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:57 AM				
Ortiz, Ruben		Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
114375	Main Building	Restroom			3/7/2014		6		\$0.00
Medium	Work In Progress				3/7/2014 9:59:06 AM				
Ortiz, Ruben		We have a sink in the lower grade boys restroom that is clogged if you can unclogg it i have already tried the plunger but the water won't go down and there all that black mildew that accumulates on the pipes comming out. If you can unclog it please.							
Israel Ortega									
114476	Main Building	Office			3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 4:11:27 PM				
Gonzales, Camilo		Pick up (36) CPU, (20) Monitors, (3) bx. of technology equipments for Equipment Turn In.							
Theresa Ramirez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
114500	Main Building	Computer Lab			3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 2:24:34 PM				
Gonzales, Camilo		Deliver (10) bx. HP Monitors. Attn: Computer Lab. PO# 131405538							
Theresa Ramirez									
<b>Count: 37 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>56</b>	<b>Total for Desert View ES</b>			<b>0</b>	<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC</b>							
113757					2/25/2014		16		\$0.00
Medium	Work In Progress	Technology			2/25/2014 11:42:35 AM				
Estrada, Jesus		carpet has couple of holes, unraveling . please take it out of Calixto and Cora Office							
Cora Ramirez									
114135					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:27:04 AM				
Moncayo, Fernando		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
107761		Parking Lot			9/20/2013		174		\$0.00
Medium	Work In Progress				9/20/2013 3:45:35 PM				
Ontiveros, Joe		Need to Work on Shed Recived on Constrution shelf ,ect .							
Joe Ontiveros									
112358					1/23/2014		49		\$0.00
Medium	Work In Progress				1/23/2014 7:35:42 AM				
Munoz, Michael		new fence 6' and gates for vehicles for techs stationed at site.							
Alfredo Holguin									
108418					10/6/2013		158		\$0.00
Medium	Work In Progress				10/6/2013 12:24:13 AM				
Holguin, Alfredo		Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PMschedule details.							
Margret Villalobos									
106754		Electrical Room			8/29/2013		196		\$0.00
Medium	Work In Progress				8/29/2013 3:37:47 PM				
Castillo, Carlos		Need to order lumber for storage shelving.							
Carlos Castillo									
114033					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:16 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: GAC</b>									
114034					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:16 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114370					3/7/2014		6		\$0.00
Medium	Work In Progress				3/7/2014 8:35:13 AM				
Moncayo, Fernando		As per Elisa,Mr. Y will be out next week for a conference. Please tell Fernando if he could come and finish fixing his office and painting where they cut in the wall (water leak) on Tuesday. I can then work in Mr. Y's office on Wednesday while he paints my office. Let me know if this is ok so that I can take things off of my walls.							
Maritza Gonzalez									
113073					2/6/2014		35		\$0.00
Medium	Work In Progress				2/6/2014 10:16:16 AM				
Rodriguez, Arturo		ROSA APODACA OFFCE-POWER TO OUTLET WHERE COMPUTER IS CONNECTED WENT OUT.							
Maritza Gonzalez									
111535					1/5/2014		67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:50 AM				
Holguin, Alfredo		Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									
114414					3/9/2014	3/25/2014	4		\$0.00
Medium	Work In Progress				3/9/2014 12:19:00 AM				
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
113162					2/9/2014	2/25/2014	32		\$0.00
Medium	Work In Progress				2/9/2014 12:20:57 AM				
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
113530					2/19/2014		22		\$0.00
Medium	Work In Progress				2/19/2014 9:10:37 AM				
Ontiveros, Joe		EXPANSION TANK IS LEAKING IN MECHANICAL ROOM.							
Fernando Moncayo									



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: GAC</b>									
112439					1/24/2014		48		\$0.00
Medium	Work In Progress				1/24/2014 10:47:46 AM				
Moncayo, Fernando		REPLACE MISSING TILES IN MARY CHAVEZ AREA.							
Maritza Gonzalez									
112330					1/22/2014		50		\$0.00
Medium	Work In Progress				1/22/2014 3:12:10 PM				
Moncayo, Fernando		refrigerated air conditioners filter change							
Fernando Moncayo									
113858					2/27/2014		14		\$0.00
Medium	Work In Progress				2/27/2014 9:25:45 AM				
Moncayo, Fernando		FLOURESCENT LIGHT IN RICHARD ACOSTA OFFICE IS OUT.							
Maritza Gonzalez									
113859					2/27/2014		14		\$0.00
Medium	Work In Progress				2/27/2014 9:26:26 AM				
Moncayo, Fernando		AS PER LUCY, PLEASE INSTAL WALL POCKET FILES IN MELISSA ALVARADO OFFICE.							
Maritza Gonzalez									
113748					2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 8:52:07 AM				
Ontiveros, Joe		LEAK OUTSIDE OF MR. YTURRALDE OFFICE, PLEASE CHECK.							
Maritza Gonzalez									
112121					1/15/2014		57		\$0.00
Medium	Work In Progress				1/15/2014 9:20:02 AM				
Ontiveros, Joe		COMODE AND SINK NEED TO BE CHECKED IN RR AT POOL AREA, ALSO A WATER LINE IN RR NEEDS TO BE CANCELLED OUT.							
Maritza Gonzalez									
113771					2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 2:07:12 PM				
Moncayo, Fernando		please repair pot holes in dock area. thank you							
Michael Munoz									
113710					2/24/2014		17		\$0.00
Medium	Work In Progress				2/24/2014 1:33:06 PM				
Moncayo, Fernando		AS PER MR. CHAVEZ, GROUNDS NEED TO BE CLEANED UP.							
Maritza Gonzalez									
3/13/2014 10:49:50 AM									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: GAC</b>									
113759					2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 12:46:33 PM				
Moncayo, Fernando		need to replace broken or leaking irrigation sprinklers							
Fernando Moncayo									
114504					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 3:00:04 PM				
Lara, Ralph		as per Mrs. Yturralde, please put in a work order for her office to be "Off Master" and have Rafa make only two keys one for her and one for Karla Quesada.							
Maritza Gonzalez									
111437					12/19/2013		84		\$0.00
Medium	Work In Progress				12/19/2013 11:44:45				
Lara, Ralph		our door in the server room - battery not working anymore							
Cora Ramirez									
113770					2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 2:06:15 PM				
Moncayo, Fernando		maintenance rake and pick-up debris. also please start watering and clean other areas around site.yard needs grounds work ( pine trees)							
Michael Munoz									
112219					1/16/2014		56		\$0.00
Medium	Work In Progress				1/16/2014 4:10:45 PM				
Flores, Pete		Vehicle 172 (Mr. Giovas) needs windshield wipers checked.							
Maritza Gonzalez									
113948					2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 7:23:22 AM				
Ontiveros, Guadalupe		Need more primer or crusher fine around maintainanœ morgan bldg at the Gac.							
Carlos Castillo									
114457		Office			3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 3:30:19 PM				
Ambriz, Jose		rOSA HIDALGO wall unit is tripping the breaker							
Fernando Moncayo									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: GAC</b>									
114509					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 3:27:57 PM				
Ambriz, Jose		Mrs Reyes wall unit is not working properly							
Fernando Moncayo									
114511					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 3:31:10 PM				
Ambriz, Jose		wall unit at CRRUA's receptionist area need's to be replace							
Fernando Moncayo									
108942		Parking Lot			10/16/2013		148		\$0.00
Medium	Work In Progress				10/16/2013 7:49:09 AM				
Moncayo, Fernando		need to repaint all parking lot lines - work can be done in phases over weekends by doing schedule adjustment.							
Alfredo Holguin									
113769		Restroom			2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 2:04:37 PM				
Moncayo, Fernando		please paint restrooms next to the cafeteria. thank you							
Michael Munoz									
112603					1/29/2014		43		\$0.00
Medium	Work In Progress				1/29/2014 3:00:07 PM				
Solis, Lorenzø		IGNITION CONTROL BOARD NEEDS TO BE REPLACED IN MRS. AVILA, AND MRS. TAYLOR OFFICE, A WING.							
Maritza Gonzalez									
114025					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:12 AM				
Moncayo, Fernando		Yearly - GAC A-10 Heat Pump Cooling Only Yearly - Refer to PM schedule details.							
Margret Villalobos									
114252		Electrical Room			3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 7:32:59 AM				
Castillo, Carlos		Order material and equipment for stock.							
Carlos Castillo									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>	<b>GAC</b>
------------------	------------

112181		Electrical Room			1/16/2014		56		\$0.00
--------	--	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/16/2014 8:13:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		Requesting bench grinder-solder station-blower vacuum for electrical shop(morgan bldg)for maintainance and cleaning purposes.Also requesting replacement nutsetter set and impact driver set hand tools.
------------------	--	--

Carlos Castillo
-----------------

109302					10/24/2013		140		\$0.00
--------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2013 3:18:13 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos		emergencypower to Jesus Reyes office - technology department
------------------	--	--

Cora Ramirez
--------------

113952					2/28/2014		13		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/28/2014 8:06:06 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		There is 3 lamps out at staffing parking on North side of building.
------------------	--	---

Alfredo Holguin
-----------------

113853					2/27/2014		14		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				2/27/2014 7:56:50 AM				
------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		circuit board to generator is bad. need to have rocky mountain cummins order and replace.
------------------	--	---

Michael Munoz
---------------

112142					1/15/2014		57		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/15/2014 2:54:39 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique		Asp CIRT (Crisis Intervention Response Team) need to mark Electrical on site plans that were provided by Mike.
-----------------	--	--

Michael Munoz
---------------

114534					3/11/2014		2		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/11/2014 4:07:11 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe		REPLACE FAUCETS ON MOP SINK-CUSTODIAL CLOSET A-WING.
----------------	--	--

Maritza Gonzalez
------------------

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: GAC</b>									
113699					2/24/2014		17		\$0.00
Medium	Work In Progress				2/24/2014 11:07:35 AM				
Ontiveros, Joe		need Plumbing line locate for: Address: 4950 MCNUTT RD subdivision: GADSDEN HIGH SCHOOL ADMIN OFFI Location of Work: SPOT: 15FT RAD AROUND THE STORAGE SHED LOCATED BEHIND THE MOBILE HOME AT THE E END OF THE PROPERTY (AT THE DIP IN THE ROAD). DIG SITE IS MARKED W/FLAGS & MAROON PAINT.							
Alfredo Holguin									
114159					3/3/2014		10		\$0.00
Medium	Work In Progress				3/3/2014 2:43:44 PM				
Ontiveros, Joe		As per Mrs. Yurralde she would like for a garbage disposal to be installed in the kitchen sink in C-Wing.							
Maritza Gonzalez									
111480					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:18 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 45 Work Orders</b>		<b>Avg. Age of WO's 40</b>			<b>Total for GAC</b>			<b>0</b>	<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: GAC - Pre-K</b>									
113704					2/24/2014		17		\$0.00
Medium	Work In Progress				2/24/2014 11:26:02 AM				
Ontiveros, Guadalupe		provide water to new raised planters							
Alfredo Holguin									
113703					2/24/2014		17		\$0.00
Medium	Work In Progress				2/24/2014 11:24:57 AM				
Ontiveros, Guadalupe		Build an install two raised planters.							
Alfredo Holguin									
113705					2/24/2014		17		\$0.00
Medium	Work In Progress				2/24/2014 11:27:40 AM				
Ontiveros, Guadalupe		provide topsoil and compost for Metal Planters (4)-							
Alfredo Holguin									
114536					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 4:08:34 PM				
Moncayo, Fernando		ROOM 203-LAMP OUTSIDE NEED TO SECURE SO BIRDS WILL NOT LAND AND MAKE A MESS.							
Maritza Gonzalez									
114191					3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 7:43:46 AM				
Moncayo, Fernando		We need to create a work order for the paper towel dispenser in room 103. It's coming off the wall. Also before the custodians come fix it could you have them talk with Ms. Viola or Ms. Pauline, that way they can move it to where the kids can reach it. Thank you.							
Maritza Gonzalez									
113551					2/19/2014		22		\$0.00
Medium	Work In Progress				2/19/2014 2:44:55 PM				
Moncayo, Fernando		PRE-K/SEWAGE BACKING UP.							
Maritza Gonzalez									
112420					1/23/2014		49		\$0.00
Medium	Work In Progress				1/23/2014 3:55:03 PM				
Moncayo, Fernando		ROOM 101-CLICKING NOISE IN THE LIGHT SWITCH.							
Maritza Gonzalez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: GAC - Pre-K</b>									
113760					2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 12:52:47 PM				
Ronquillo, Ruben		need to order bolts for dobbble slide from (recreation creations)							
Fernando Moncayo									
113848					2/26/2014		15		\$0.00
Medium	Work In Progress				2/26/2014 4:02:50 PM				
Holguin, Alfredo		Playground area is 60'x48'+or= and the surface is crushed rubber Glued and painted w/o # 113760 and is for a missing bolt The patio also have two small areas filled with sand							
Fernando Moncayo									
114342					3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 3:39:51 PM				
Moncayo, Fernando		relocate wooden shed and sealed around it,so animals won't crawl in							
Fernando Moncayo									
<b>Count: 10 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>17</b>		<b>Total for GAC - Pre-K</b>	<b>0</b>		<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location: Gadsden ES</b>									
112579		Classroom			1/29/2014		43		\$0.00
Medium	Work In Progress	211			1/29/2014 8:42:55 AM				
Appelzoller, Fred		need assistance with putting some shelves in room 211... I would greatly appreciate your assistance in this matter...							
Loraine Gandara									
114039					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:19 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.							
Margret Villalobos									
114038					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:18 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.							
Margret Villalobos									
114045					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:22 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
114484					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 7:27:39 AM				
Appelzoller, Fred		please cut weeds on the outside of the fence along hwy 478, in utility fenced area, back pond and surrounding areas around site. also grass has weeds growing, could use a cut.							
Richard Chavez									
114512		Hallway/Corridor			3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 3:35:56 PM				
Appelzoller, Fred		need battery packs for emergency lighting in hallways T-8 lights . also 4 pin lamps for recess lights in lobby area and hall ways ( 4 pin GE- Biax T/E, F26TBX/830/A/ECO							
Fred Appelzoller									



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden ES

113593 Hallway/Corridor 2/20/2014 21 \$0.00

Medium Work In Progress 2/20/2014 10:56:06 AM

Appelzoller, Fred need assistance with the wall molding in Jefferson wing...there is none next to the water fountain.. thank you...

Loraine Gandara

114413 3/9/2014 3/25/2014 4 \$0.00

Medium Work In Progress 3/9/2014 12:18:59 AM

Appelzoller, Fred Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.

Margret Villalobos

104416 7/17/2013 239 \$0.00

Medium Work In Progress 7/17/2013 11:02:33 AM

Pinon, Jose asp Ms. Marquez... need all the vents to please be cleaned thru out the school... thank you greatly....

Loraine Gandara

111977 1/12/2014 1/28/2014 60 \$0.00

Medium Work In Progress 1/12/2014 12:17:54 AM

Pinon, Jose Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PM schedule details.

Margret Villalobos

114002 3/2/2014 3/18/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:00 AM

Appelzoller, Fred Yearly - Gadsden ES A-10 Heat Pump Yearly - Refer to PM schedule details.

Margret Villalobos

114486 Office 3/11/2014 2 \$0.00

Medium Work In Progress Mr. Pinon 3/11/2014 8:15:02 AM

Solis, Lorenzo Mr. Pinon needs access for him to be able to control ac in school.... he had access once before but now cannot get in.... greatly appreciate your assistance in this matter...

Loraine Gandara

111043 12/9/2013 94 \$0.00

Medium Work In Progress 12/9/2013 12:13:30 PM

Marquez, Gerardo Silver working with DOT on setting up new flashing lights at GE. He cannot open box. need help with keys

Cora Ramirez

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden ES

112124 1/15/2014 57 \$0.00

Medium Work In Progress 1/15/2014 11:08:10 AM

Marquez, Gerardo need to to have keys made for Zern lock boxes outside ...thank you....

Loraine Gandara

111498 1/5/2014 2/5/2014 67 \$0.00

Medium Work In Progress 1/5/2014 12:23:27 AM

Villalobos, David Yearly - Gadsden ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

113762 2/25/2014 16 \$0.00

Medium Work In Progress 2/25/2014 1:00:26 PM

Sotelo, Enrique need lamps for 2x2 light fixtures and 2' faculty r-rm's ... thank you greatly

Loraine Gandara

112199 Parking Lot 1/16/2014 56 \$0.00

Medium Work In Progress 1/16/2014 3:09:58 PM

Sotelo, Enrique One of the lights is not working in the parking lot. Please see Mrs. Grace Marquez to find out which light.

Rafael Gallegos

112205 Parking Lot 1/16/2014 56 \$0.00

Medium Work In Progress 1/16/2014 3:36:46 PM

Sotelo, Enrique . He indicated that he and Lorenzo were out checking the problem and determined that there is an electrical issue with the exterior lights. Supposedly Lorenzo was entering a work order, so the electrician could work on it.

Loraine Gandara

113309 Cafeteria 2/12/2014 29 \$0.00

Medium Work In Progress 2/12/2014 9:22:49 AM

Sotelo, Enrique need assistance with lights in the multipurpose room with a lift.... greatly appreciate your assistance in this matter...

Loraine Gandara

111145 Classroom 12/11/2013 92 \$0.00

Medium Work In Progress 205 12/11/2013 9:15:45 AM

Solis, Lorenzo " Under Warranty" room 205 air is coming our cold... thank you...

Loraine Gandara

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
114132					3/2/2014	3/13/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:27:03 AM				
Appelzoller, Fred		Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 21 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>43</b>			<b>Total for Gadsden ES</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
114134					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress			3/2/2014 12:27:04 AM					
Hernandez, Guillermo	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
109350		Athletic Field			10/25/2013		139		\$0.00
Medium	Work In Progress			10/25/2013 3:35:29 PM					
Gonzalez, Salvador	please replace door to morgan building by batting cages. boys baseball. thank you								
Michael Munoz									
113585		Athletic Field			2/20/2014		21		\$0.00
Medium	Work In Progress			2/20/2014 8:29:12 AM					
Gonzalez, Salvador	Requested by Ms. L. Chavez-Move batting tee structure back take poles off fence and attach to metal structure. Add chain link fence to existing poles. ANY QUESTIONS PLEASE SEE COACH LILLY CHAVEZ.								
Velia Alarcon									
112875					2/3/2014		38		\$0.00
Medium	Work In Progress			2/3/2014 7:54:45 AM					
Ronquillo, Ruben	Need to replace two HALOTRON fire extinguishers for the Auto shop.								
Guillermo Hernandez									
113942					2/28/2014		13		\$0.00
Medium	Work In Progress			2/28/2014 12:32:59 AM					
Munoz, Michael	Yearly - Gadsden HS - Fire Pump Inspection - Refer to PM schedule details.								
Margret Villalobos									
114364					3/7/2014		6		\$0.00
Medium	Work In Progress			3/7/2014 8:08:05 AM					
Carbajal, Jimmy	Jimmy I need about 10 AA batteries for flashlights.								
Jaime Herrera									
113751		Office			2/25/2014		16		\$0.00
Medium	Work In Progress			2/25/2014 9:10:06 AM					
Gonzales, Camilo	Pick-up obsolete equipment. See R. Rodriguez								
Theresa Ramirez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden HS

114196 Cafeteria (1998) 3/4/2014 9 \$0.00

Medium Work In Progress 3/4/2014 8:10:05 AM

Hernandez, Guillermo There are some ceiling lights that are out in the cafeteria that need to be replaced.

Jaime Herrera

114254 Cafeteria (1998) 3/5/2014 8 \$0.00

Medium Work In Progress 3/5/2014 7:51:10 AM

Sotelo, Daniel There are some ceiling tiles that need to be changed out, there are milk or water stains.

Jaime Herrera

113815 Varsity Gym 2/25/2014 16 \$0.00

Medium Work In Progress 2/25/2014 4:09:37 PM

Sotelo, Daniel need to replace a few stair plank's on bleachers

Daniel Sotelo

112089 Varsity Gym Gym 1/14/2014 58 \$0.00

Medium Work In Progress Boy's Soccer 1/14/2014 3:33:02 PM

Sotelo, Daniel Requested by Coach Lawrence/Mrs. Soriano for Boy's Soccer Locker Room - Paint window and put blinds on windows.

Velia Alarcon

113062 Varsity Gym Gym 2/6/2014 35 \$0.00

Medium Work In Progress 2/6/2014 8:46:53 AM

Gallegos, Rafael WARRANTY WORK ON GYM FLOOR  
need to fix two broken planks on gym floor they are located on the southeast corner right outside of basketball court

Daniel Sotelo

114553 Academic Bldg Classroom 3/12/2014 1 \$0.00

Medium Work In Progress 341 3/12/2014 9:59:44 AM

Ambriz, Jose Requested by Coach Lawrence Rm. 341 Academic Building - Classroom is getting really stuffy and the vent selection is not working. Please take a look at it for him.

Velia Alarcon

112979 Academic Bldg Classroom 2/4/2014 37 \$0.00

Medium Work In Progress 331 2/4/2014 3:45:51 PM

Villalobos, David Requested by Ms. Hartmann Rm. 331 Academic Building - Relocate sink cabinet from room 107 in the Main Building to room 331 in the Academic Building.

Velia Alarcon

3/13/2014 10:49:51 AM

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: Gadsden HS</b>									
113598	Academic Bldg	Classroom			2/20/2014		21		\$0.00
Medium	Work In Progress	331			2/20/2014 1:00:38 PM				
Sotelo, Enrique	Requested by Ms. Hartmann Rm. 331 Academic Building-Please install a light to existing electrical wiring on stage.								
Velia Alarcon									
112094	Academic Bldg	Classroom			1/14/2014		58		\$0.00
Medium	Work In Progress	331			1/14/2014 3:38:14 PM				
Lara, Ralph	Requested by Ms. Hartmann Rm. 331 Academic Building-Please re-key classroom door, which includes two door into the court yard, to a different key number.								
Velia Alarcon									
113875	Academic Bldg	Classroom			2/27/2014		14		\$0.00
Medium	Work In Progress	328			2/27/2014 1:54:36 PM				
Sotelo, Daniel	Requested by Ms. Roth Rm. 328 Academic Building-Replace window shade, string about to break off.								
Velia Alarcon									
113876	Academic Bldg				2/27/2014		14		\$0.00
Medium	Work In Progress	342			2/27/2014 1:56:30 PM				
Sotelo, Daniel	Requested by Ms. Roth for Teacher's Lounge of the South Side of the Academic Building-Replace shade, string is about to break off after screen was busted out.								
Velia Alarcon									
105583	Nursing Center				8/7/2013		218		\$0.00
Medium	Work In Progress				8/7/2013 11:27:47 AM				
Ontiveros, Guadalupe	Requested by Mr. D. Martinez for Parking Area next to Nurse's Office-Requesting parking stops to be added to parking spaces from Nurse's Office area to Cafeteria area. PLEASE SEE MR. MARTINEZ FOR FURTHER INSTRUCTION.								
Velia Alarcon									
113765	Auto Shop				2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 1:10:51 PM				
Hernandez, Guillermo	Requested by Mr. Enriquez Rm. 509 New CTE Building Auto Shop-Install 2 post lift in auto shop. SEE MR. ENRIQUEZ FOR LOCATION OF LIFT AND LOCATION HE WOULD LIKE LIFT INSTALLED.								
Velia Alarcon									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
109015	Pool Pump	Pool			10/17/2013		147		\$0.00
Medium	Work In Progress				10/17/2013 3:07:03 PM				
Apodaca, Mario	need to replace all pool ladders at pool do to wear and tear								
Mario Apodaca									
109016	Pool Pump	Pool			10/17/2013		147		\$0.00
Medium	Work In Progress				10/17/2013 3:10:55 PM				
Apodaca, Mario	need to order pool chemicals and equipment								
Mario Apodaca									
113083	Grounds Shop				2/6/2014		35		\$0.00
Medium	Work In Progress				2/6/2014 2:31:25 PM				
Solis, Lorenz	please order new ice machine and install. thank you								
Michael Munoz									
111671	Community				1/6/2014		66		\$0.00
Medium	Work In Progress				1/6/2014 1:20:40 PM				
Ronquillo, Ruben	Re-upholster all benches and torn pads on weight training equipment								
Alfredo Holguin									
114436	New Admin Bldg	Computer Lab			3/10/2014		3		\$0.00
Medium	Work In Progress	718			3/10/2014 10:29:08 AM				
Gonzales, Camilo	Requested by Ms. Servin-Classroom 718 in the New Admin Building has old books that need to be picked up and room # 342 in the Academic Building has a gaylord that needs to be picked up.								
Velia Alarcon									
114489	New Admin Bldg	Office			3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 8:46:53 AM				
Gonzales, Camilo	Deliver 1 bx. Edge Mat Cutter. Attn: Debbie Hartman. PO# 131404659								
Theresa Ramirez									
108046					9/27/2013		167		\$0.00
Medium	Work In Progress				9/27/2013 2:28:05 PM				
Sotelo, Enrique	Bus Turnaround - Need to provide power to lift station to prevent future flooding. (See Mike for details).								
Michael Munoz									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
113594					2/20/2014		21		\$0.00
Medium	Work In Progress				2/20/2014 12:17:33 PM				
Sotelo, Enrique		Need to replace 4 lamps to lighting on the south side of campus by the tennis court and swimming pool. We will need the bucket truck.							
Guillermo Hernandez									
113671					2/21/2014		20		\$0.00
Medium	Work In Progress				2/21/2014 3:46:48 PM				
Sotelo, Enrique		Need to replace light fixture on the outside by the entrance to the Panther Paw. (Vocational building)							
Guillermo Hernandez									
110294					11/15/2013		118		\$0.00
Medium	Work In Progress				11/15/2013 9:48:05 AM				
Ambriz, Jose		Need assistance trouble shooting fresh air heaters units for the Old English building.							
Guillermo Hernandez									
110323					11/15/2013		118		\$0.00
Medium	Work In Progress				11/15/2013 3:56:44 PM				
Ambriz, Jose		Need to replace motors for the heating units in Old English #148,#146 and mechanical room.							
Guillermo Hernandez									
107034					9/3/2013		191		\$0.00
Medium	Work In Progress				9/3/2013 3:52:55 PM				
Ambriz, Jose		Need to replace exhaust fan motors in the weight room ( Jose has sample motor).							
Guillermo Hernandez									
113915					2/28/2014	3/31/2014	13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:45 AM				
Hernandez, Guillermo		Yearly - Gadsden HS C-11 (Evap.Condnser)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
114026					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:12 AM				
Hernandez, Guillermo		Yearly - Gadsden HS A10 (Heat Pumps)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
114415					3/9/2014		4		\$0.00
Medium	Work In Progress				3/9/2014 12:19:01 AM				
Hernandez, Guillermo		Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
113464					2/18/2014		23		\$0.00
High	Work In Progress				2/18/2014 7:54:48 AM				
Ambriz, Jose		Need to replace heating assembly to H/C unit for Portable #1. Carrier model CPHEATER051A00, SERIAL #4501G00017. (208/240/1HP/60HZ)							
Guillermo Hernandez									
113571					2/19/2014		22		\$0.00
Medium	Work In Progress				2/19/2014 3:54:22 PM				
Ambriz, Jose		Need to replace coupling on the cooling side of the water fountain by the concession stand at the football field.							
Guillermo Hernandez									
108987					10/16/2013		148		\$0.00
Medium	Work In Progress				10/16/2013 4:12:21 PM				
Villalobos, David		Annex building in special ed classroom shower head is leaking needs to be replaced							
Daniel Sotelo									
108988					10/16/2013		148		\$0.00
Medium	Work In Progress				10/16/2013 4:13:50 PM				
Villalobos, David		In weight room girls bathroom shower head is leaking needs to be replaced							
Daniel Sotelo									
109631					11/1/2013		132		\$0.00
Medium	Work In Progress				11/1/2013 2:50:12 PM				
Villalobos, David		Need assistance to repair hanging toilet, water is leaking behind the wall. Boys restroom Annex building.							
Guillermo Hernandez									
111481					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:18 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Gadsden HS</b>							
112648					1/30/2014		42		\$0.00
Medium	Work In Progress				1/30/2014 10:44:24 AM				
Villalobos, David		Need to replace faucets boys restroom on the south side in the Academic building.							
Guillermo Hernandez									
112874					2/3/2014		38		\$0.00
Medium	Work In Progress				2/3/2014 7:50:35 AM				
Villalobos, David		Need to replace leaking faucets in the boys restroom at the cafeteria.							
Guillermo Hernandez									
112079					1/14/2014		58		\$0.00
Medium	Work In Progress				1/14/2014 1:25:02 PM				
Villalobos, David		Fire Pump Valves - Install air relief Valve - Mario A. and Guillermo know location							
Alfredo Holguin									
112080					1/14/2014		58		\$0.00
Medium	Work In Progress				1/14/2014 1:27:21 PM				
Villalobos, David		Fire Pump- re-plumb drain line from floor sink so it drains to the outside of the building. Mario A. or Guillermo can provide specifics.							
Alfredo Holguin									
104583					7/22/2013		234		\$0.00
Medium	Work In Progress				7/22/2013 3:49:21 PM				
Villalobos, David		Need to replace gasket to shower in the Sped classroom at the Annex building.							
Guillermo Hernandez									
114283					3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 3:27:32 PM				
Ambriz, Jose		Need to replace (7) 6800 Evap. coolers from Academic: EVAP-GHS-23, EVAP-GHS-027, EVAP-GHS-030, EVAP-GHS-31, EVAP-GHS-033, EVAP-GHS-34, EVAP-GHS-38.							
Guillermo Hernandez									
114285					3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 3:35:45 PM				
Ambriz, Jose		Need to replace 1 down draft 6800 Evap cooler MCD-GHS-024 and 2 commercial Evap. cooler, side draft one wet section MCD-GHS-022 and MCD-GHS-023. on the kitchen roof.							
Guillermo Hernandez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location: Gadsden HS</b>									
114290					3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 3:44:45 PM				
Ambriz, Jose		Need to replace commercial Evap. cooler, side draft two wet sections for the Weight room.							
Guillermo Hernandez									
114193					3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 7:55:41 AM				
Ambriz, Jose		Need to replace Damper Actuator to RTU #62 at the North building.							
Guillermo Hernandez									
105469					8/6/2013		219		\$0.00
Medium	Work In Progress				8/6/2013 9:25:16 AM				
Ambriz, Jose		Requested by Staff in Academic Building-Water fountain near boy's restroom closest to cafeteria is not working.							
Velia Alarcon									
112430					1/24/2014		48		\$0.00
Medium	Work In Progress				1/24/2014 9:03:35 AM				
Flores, Pete		Requested by Mr. Mora Athletic Training Room-Athletic Training gator will not charge. Batteries need to be tested to make sure they are still good.							
Velia Alarcon									
114559		Athletic Field			3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 11:26:28 AM				
Ontiveros, Guadalupe		Requested by Coach Walker for East Long Jump Runway on Track Field-Repair/replace wood, take off boards.							
Velia Alarcon									
114221					3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 2:46:17 PM				
Lara, Ralph		need a new key to mail box the one I have is about to break thanks							
Daniel Sotelo									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location: Gadsden HS</b>									
114535					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 4:07:57 PM				
Lara, Ralph		Need two (2) locks keyed to the Master Key on the light control boxes at the baseball and softball fields at Gadsden High School. Please drop off at the Construction office when ready. Should you have any questions please contact Mr. Ralph Gallegos at 575-882-6921. Thank You							
Dominique Esparza									
112644					1/30/2014		42		\$0.00
Medium	Work In Progress				1/30/2014 10:19:28 AM				
Lara, Ralph		Requested by Velia-An extra key is needed for mailbox # 31 and # 96.							
Velia Alarcon									
112645					1/30/2014		42		\$0.00
Medium	Work In Progress				1/30/2014 10:21:00 AM				
Lara, Ralph		Requested by Velia-Mailbox # 72 is ver hard to open. SEE MARIA FOR EXTRA KEY TO MAILBOX.							
Velia Alarcon									
114495		Pool			3/11/2014		2		\$0.00
High	Work In Progress				3/11/2014 10:58:53 AM				
Lara, Ralph		Keys lost by contractor. Please replace DC20 Pool key and HE157 Southgate key. Invoice Contractor for all keys that need to be made for replacing lost keys. Should you have any questions please contact Mr. Ralph Gallegos at 575- 882-6921. "Gadsden HS Swimming Pool Upgrades" project							
Dominique Esparza									
113213					2/10/2014		31		\$0.00
Medium	Work In Progress				2/10/2014 1:43:43 PM				
Lara, Ralph		Requested by Mrs. Munoz Rm. 207 North Building-Door from kitchen to classroom needs to have a double side lock. Only has lock from kitchen to classroom and not from classroom to kitchen.							
Velia Alarcon									
111244					12/13/2013		90		\$0.00
High	Work In Progress				12/13/2013 11:16:36				
Villalobos, Margaret		please spray for bugs in rm 106. ms.arredondos.							
Michael Munoz									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
114487					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 8:24:14 AM				
Carrasco, Danny		ATT:DANNY C. Need a tool box for polaris thanks							
Daniel Sotelo									
114103					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:49 AM				
Sanchez, Raul		Monthly - Gadsden HS - Monthly Water Samples - Refer to PMschedule details.							
Margret Villalobos									
106135					8/16/2013		209		\$0.00
Medium	Work In Progress				8/16/2013 8:50:03 AM				
Orozco, Daniel		kitchen-ladies restroom – toilet, has a crack in the bottom. It is leaking out water and the exhaust does not work.							
Maritza Gonzalez									
110536					11/22/2013		111		\$0.00
Medium	Work In Progress				11/22/2013 9:11:34 AM				
Orozco, Daniel		FLOOR LIFTED IN WALK IN REFRIGERATOR. SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
113420					2/14/2014		27		\$0.00
Medium	Work In Progress				2/14/2014 12:22:34 AM				
Sanchez, Raul		Monthly - Gadsden HS- Filters (Pump Rm) Quarterly - Refer to PMschedule details.							
Margret Villalobos									
114101					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:48 AM				
Sanchez, Raul		Monthly - Gadsden HS - Lift Station Inspection - Refer to PMschedule details.							
Margret Villalobos									
114099					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:47 AM				
Sanchez, Raul		Monthly - Gadsden HS - Grease Trap (Culinary/Auto) - Refer to PMschedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: Gadsden HS</b>									
112693					1/31/2014		41		\$0.00
Medium	Work In Progress				1/31/2014 12:27:12 AM				
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
112834					2/2/2014		39		\$0.00
Medium	Work In Progress				2/2/2014 12:26:36 AM				
Sanchez, Raul	Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.								
Margret Villalobos									
114074					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:36 AM				
Hernandez, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
114579					3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 3:48:48 PM				
Hernandez, Guillermo	Please replace bad door sweeper on all doors to the cafeteria.								
Guillermo Hernandez									
111798					1/8/2014		64		\$0.00
Medium	Work In Progress	Girls Softball			1/8/2014 12:57:41 PM				
Gonzalez, Salvador	Secure gate to dugout and install new gate on right field fence.								
Michael Munoz									
114197					3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 8:13:41 AM				
Sotelo, Enrique	Most of the outside lights on the portables are out and need to be replaced. It is very dark over in that area at night and early in the morning.								
Jaime Herrera									
114275					3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 1:10:45 PM				
Carrasco, Danny	ATT; DANNY C. need you to order me a little giant from grainger part # 40P124 talked to Mike said it was ok thanks								
Daniel Sotelo									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Gadsden HS**

114068 3/2/2014 3/10/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:33 AM

Sotelo, Daniel Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

114069 3/2/2014 4/2/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:33 AM

Sotelo, Daniel Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

114437 3/10/2014 3 \$0.00

Medium Work In Progress 3/10/2014 10:32:53 AM

Sotelo, Daniel Requested by Coach Gerela for Football Locker Room - Light bulbs need to be replaced in football equipment room, lights are burned out.

Velia Alarcon

108417 10/6/2013 158 \$0.00

Medium Work In Progress 10/6/2013 12:24:13 AM

Holguin, Alfredo Monthly - Gadsden HS - Fire Pump Engine - Refer to PM schedule details.

Margret Villalobos

108412 10/6/2013 143 \$0.00

Medium Work In Progress 10/6/2013 12:24:10 AM 2/26/2014

Holguin, Alfredo Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.

Margret Villalobos

113257 2/11/2014 30 \$0.00

Medium Work In Progress Culinary Arts 2/11/2014 10:30:10 AM

Ronquillo, Ruben Need (2) signs made for this area that read:

Culinary Arts  
Loading/Unloading  
Only

Panther Hut  
Staff Parking  
Only

Once you receive the signs, please contact Orlando Garcia @ 575-997-7557 for placement of signs.

Margret Villalobos

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
110330					11/16/2013		117		\$0.00
Medium	Work In Progress				11/16/2013 12:18:09				
Flores, Pete		Yearly- Gadsden HS- Mow (0408/0419/0428) Grounds - Refer to PM schedule details.							
Margret Villalobos									
113749					2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 8:53:22 AM				
Flores, Pete		Requested by Mr. Mora-Athletic training gator not running, needs to be checked for battery functions.							
Velia Alarcon									
<b>Count: 82 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>53</b>	<b>Total for Gadsden HS</b>			<b>0</b>	<b>\$0.00</b>



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
114537					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 4:10:58 PM				
Flores, Pete		VEHICLE 150(MR. BAKER) FLASHER/BLINKER NOT WORKING. WILL BE AVAILABLE MARCH 20-28.							
Maritza Gonzalez									
114348					3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 3:45:54 PM				
Diaz, Sebastian		3/6/14 2-check exhaust fan on restroom 2-replace lights on gym 3-finish to paint gym 1-paper log							
Sebastian Diaz									
114467					3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 3:43:20 PM				
Diaz, Sebastian		Need to replace lights on room 150 thank you							
Sebastian Diaz									
114149		Classroom			3/3/2014		10		\$0.00
Medium	Work In Progress	Rm 169			3/3/2014 10:18:35 AM				
Lara, Ralph		Door is not locking. Door hands too low.							
Nancy Tinajero									
113011					2/5/2014		36		\$0.00
Medium	Work In Progress	Outside			2/5/2014 10:03:10 AM				
Diaz, Sebastian		Leveling of back right hand corner so that shed can be delivered							
Nancy Tinajero									
113591					2/20/2014		21		\$0.00
Medium	Work In Progress				2/20/2014 9:37:27 AM				
Diaz, Sebastian		Clean debris around Morgan Building.							
Michael Munoz									
112683					1/31/2014		41		\$0.00
Medium	Work In Progress				1/31/2014 12:27:06 AM				
Apodaca, Mario		Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
114105					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:50 AM				
Apodaca, Mario		Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
112252					1/17/2014		55		\$0.00
Medium	Work In Progress				1/17/2014 3:49:17 PM				
Marquez, Gerardo		Need to check doors and replace for new on gym thank you							
Sebastian Diaz									
112198					1/16/2014		56		\$0.00
Medium	Work In Progress				1/16/2014 3:04:51 PM				
Marquez, Gerardo		Need to fix handicap doors around the entire school.							
Nancy Tinajero									
105924		Custodial			8/13/2013		212		\$0.00
Medium	Work In Progress				8/13/2013 12:53:11 PM				
Marquez, Gerardo		WE ALSO NEED AN EXTRA KEY MADE FOR OUR NIGHT CUSTODIAN THIS KEY IS FOR THE JOHN DEER GATOR							
Juan Acosta									
113295					2/11/2014		30		\$0.00
Safety	Work In Progress				2/11/2014 4:15:31 PM				
Ontiveros, Guadalupe		Basketball Courts - need to put gravel around area.							
Michael Munoz									
113592					2/20/2014		21		\$0.00
Medium	Work In Progress				2/20/2014 9:43:05 AM				
Ontiveros, Guadalupe		Need a Crusher Fine pad for Morgan to be delivered between the two existing storages on the south end.							
Michael Munoz									
114431					3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 8:54:19 AM				
Solis, Lorenzo		On boiler cafeteria need to check water pump thank you							
Sebastian Diaz									
114432					3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 8:58:01 AM				
Solis, Lorenzo		On boiler east need to replace circulate pump thank you							
Sebastian Diaz									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden MS

114428 3/10/2014 3 3/10/2014 8:51:05 AM \$0.00

Medium Work In Progress 3/10/2014 8:51:05 AM

Marquez, Gerardo Need to fix door gym by the hall thank you

Sebastian Diaz

114430 3/10/2014 3 3/10/2014 8:52:10 AM \$0.00

Medium Work In Progress 3/10/2014 8:52:10 AM

Marquez, Gerardo Need to fix door inside annex thank you

Sebastian Diaz

113867 Athletic Field 2/27/2014 14 2/27/2014 11:26:14 AM \$0.00

High Work In Progress 2/27/2014 11:26:14 AM

Marquez, Gerardo NURSES LOCKED KEYS IN THERE OFFICE. NEED A LOCKSMITH TO OPEN DR. ASAP. THANKS.

Juan Acosta

114020 3/2/2014 3/18/2014 11 3/2/2014 12:26:09 AM \$0.00

Medium Work In Progress 3/2/2014 12:26:09 AM

Villalobos, Margret Monthly - Gadsden MS Monthly Chiller Insp. - Refer to emailed Arlene 3/4/14 PMs schedule details. serviced 3/6/14

Margret Villalobos

114382 3/7/2014 6 3/7/2014 1:51:26 PM \$0.00

High Work In Progress 3/7/2014 1:51:26 PM

Villalobos, David there is an odor of sewer in the annex building. site received complaint from an irate parent. please check

Michael Munoz

114199 3/4/2014 9 3/4/2014 8:39:55 AM \$0.00

Medium Work In Progress 3/4/2014 8:39:55 AM

Sotelo, Enrique Need to connect wall heater on concession stand thank you

Sebastian Diaz

111482 1/5/2014 2/5/2014 67 1/5/2014 12:23:19 AM \$0.00

Medium Work In Progress 1/5/2014 12:23:19 AM

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

110842 12/4/2013 99 12/4/2013 11:47:22 AM \$0.00

Medium Work In Progress 12/4/2013 11:47:22 AM

Villalobos, David Need to check drain pipe on B w2ing thank you

Sebastian Diaz

3/13/2014 10:49:51 AM

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
113993					3/2/2014		11		\$0.00
Medium	Work In Progress			3/2/2014 12:25:55 AM					
Diaz, Sebastian	Yearly - Gadsden MS A-10 HP Rooftop Yearly - Refer to PMschedule details.								
Margret Villalobos									
113930					2/28/2014	3/31/2014	13		\$0.00
Medium	Work In Progress			2/28/2014 12:32:53 AM					
Diaz, Sebastian	Yearly - Gadsden MS C-11 Evap Coolers Yearly - Refer to PMschedule details.								
Margret Villalobos									
111752					1/7/2014		65		\$0.00
Medium	Work In Progress			1/7/2014 3:28:48 PM					
Sotelo, Enrique	need assistance in changing out a switch float at the domestic water tank gadsden middle school								
Mario Apodaca									
111897	Main Building				1/10/2014		62		\$0.00
Medium	Work In Progress	Door next to		1/10/2014 11:33:51 AM					
Marquez, Gerardo	Handicap door in B wing will not open. Its the door close to room 118.								
Nancy Tinajero									
113962	Band Room	Pump House			2/28/2014		13		\$0.00
Medium	Work In Progress			2/28/2014 2:58:46 PM					
Marquez, Gerardo	need to issue out a key for the pump room to the building mechanic a DC15								
Mario Apodaca									
106140	Annex	Restroom			8/16/2013		209		\$0.00
Medium	Work In Progress	STAFF		8/16/2013 10:16:55 AM					
Marquez, Gerardo	CAN NOT OPEN DOOR WITH KEY A.S.A.P								
Juan Acosta									
114516	Annex				3/11/2014		2		\$0.00
High	Work In Progress			3/11/2014 3:43:32 PM					
Miranda, Danny	please install vents to all 4 walls on the parapet. thank you. please see mike for details								
Michael Munoz									
112197	Vocational				1/16/2014		56		\$0.00
Medium	Work In Progress	Room 306		1/16/2014 3:03:38 PM					
Marquez, Gerardo	Cylinder on lock to cage is not working.								
Nancy Tinajero									
3/13/2014 10:49:51 AM									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location: Gadsden MS</b>									
112592	Gymnasium	Gym			1/29/2014		43		\$0.00
Medium	Work In Progress	Gym Lobby			1/29/2014 11:38:45 AM				
Solis, Lorenzø Please fix heater in gym lobby it is not working.									
Nancy Tinajero									
112115	Gymnasium				1/15/2014		57		\$0.00
Medium	Work In Progress				1/15/2014 6:40:53 AM				
Diaz, Sebastian please paint lobby before tile is placed. working on doing tile in spring break.									
Michael Munoz									
114540	Gymnasium	Gym			3/12/2014		1		\$0.00
Medium	Work In Progress	concession			3/12/2014 8:07:10 AM				
Solis, Lorenzø Ice machine in concession stand is broken....needs repair not making ice.									
Nancy Tinajero									
111358	C-Wing				12/17/2013		86		\$0.00
Safety	Work In Progress				12/17/2013 12:21:17				
Diaz, Sebastian All Portable Ramps at C-Wing - Asp Mr. Chavez he wants all ramps replaced w/new boards. Please see him.									
Richard Chavez									
114383	C-Wing				3/7/2014		6		\$0.00
Medium	Work In Progress	(Old Central			3/7/2014 2:44:21 PM				
Solis, Lorenzø Need to check unit at thank you									
Sebastian Diaz									
113124	C-Wing				2/7/2014		34		\$0.00
Medium	Work In Progress				2/7/2014 11:06:34 AM				
Diaz, Sebastian Old Central Office - Need to start painting this area (See Mike for details)									
Richard Chavez									
113306	C-Wing	Parking Lot			2/12/2014		29		\$0.00
Medium	Work In Progress				2/12/2014 8:14:59 AM				
Villalobos, David Constant flow on fire protection bfp, have continuously taken opout debris from unit.									
David Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
113296	C-Wing				2/11/2014		30		\$0.00
Medium	Work In Progress				2/11/2014 4:16:55 PM				
Villalobos, David		Old Central Office - Need to replace all plumbing fixtures to include commode in Main Lobby.							
Michael Munoz									
112149	Gym	Mechanical			1/15/2014		57		\$0.00
Medium	Work In Progress				1/15/2014 3:28:01 PM				
Solis, Lorenzø		need to replace old Bryant boiler with new raypac. to include new piping, valves and 2 new motors							
Michael Munoz									
112116	Gym	Dressing Room			1/15/2014		57		\$0.00
Medium	Work In Progress				1/15/2014 6:44:11 AM				
Solis, Lorenzø		please replace existing heating coils with new modern ones.(boys and girls)							
Michael Munoz									
112117	Gym	Dressing Room			1/15/2014		57		\$0.00
High	Work In Progress				1/15/2014 6:46:31 AM				
Solis, Lorenzø		p.e teacher mentioned that there was no cooling in dressing rooms . please check, also check for a vent relief. thank you							
Michael Munoz									
113647		Office			2/21/2014		20		\$0.00
Medium	Work In Progress				2/21/2014 11:39:57 AM				
Briones, Enrique		Pick up 1 bx. marked for MLewya.							
Theresa Ramirez									
<b>Count: 43 Work Orders</b>		<b>Avg. Age of WO's 38</b>		<b>Total for Gadsden MS</b>		<b>0</b>		<b>\$0.00</b>	

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: La Union - JTP Alvarez Farms</b>									
112573					1/29/2014		43		\$0.00
Medium	Work In Progress				1/29/2014 8:24:23 AM				
Aguilar, Patricio		big toy in playground in bad need of repair. slide cracked bys un age - step broken and rust - taped with caution tape				1/31-Route back to Pat asp Mike			
Patricio Aguilar									
113118					2/7/2014		34		\$0.00
Medium	Work In Progress				2/7/2014 8:52:39 AM				
Aguilar, Patricio		wo to myself - need gopher pellets for playground							
Patricio Aguilar									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>39</b>		<b>Total for La Union - JTP Alvarez Farms</b>	<b>0</b>		<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** La Union ES

114420 3/9/2014 3/25/2014 4 \$0.00

Medium Work In Progress 3/9/2014 12:19:03 AM

Aguilar, Patricio Monthly - La Union ES Playground Insp - Refer to PM schedule details.

Margret Villalobos

113253 2/11/2014 30 \$0.00

Medium Work In Progress 2/11/2014 8:57:03 AM

Holguin, Alfredo changing sand with wood fiber  
3 areas  
1 - back playground toy 50' x 70' with border need replace 4  
2 - back playground swing set 20' x60' has no borders  
3 - courtyard toy 50' x 60' with border need replace 14

Patricio Aguilar

114082 3/2/2014 3/10/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:40 AM

Aguilar, Patricio Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

114080 3/2/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:39 AM

Aguilar, Patricio Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

114081 3/2/2014 3/10/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:39 AM

Aguilar, Patricio Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

113861 2/27/2014 14 \$0.00

Medium Work In Progress 2/27/2014 10:10:21 AM

Aguilar, Patricio wo to myself - to move infocus & bracket - screen from r106 to r301 need butterfly anchors

Patricio Aguilar

114316 3/6/2014 7 \$0.00

Medium Work In Progress 3/6/2014 8:17:30 AM

Aguilar, Patricio wo to myself - need to replace master cool medias - belts gym office new wing

Patricio Aguilar



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: La Union ES</b>									
113924					2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:50 AM				
Aguilar, Patricio		Monthly - La Union ES A-16 Fan Exhaust Semimonthly - Refer to PM schedule details.							
Margret Villalobos									
111485					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:20 AM				
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
113923					2/28/2014	3/31/2014	13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:49 AM				
Aguilar, Patricio		Yearly - La Union ES C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
114151					3/3/2014		10		\$0.00
Medium	Work In Progress				3/3/2014 10:48:17 AM				
Ontiveros, Guadalupe		need the use of a utility tractor with loader - rear blade for the fare back yard thanks for the help.							
Patricio Aguilar									
114152					3/3/2014		10		\$0.00
Medium	Work In Progress				3/3/2014 10:52:06 AM				
Aguilar, Patricio		wo to myself need to water back yard - need 2" water hose about 200 ft							
Patricio Aguilar									
114119					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:57 AM				
Aguilar, Patricio		Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 13 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>16</b>		<b>Total for La Union ES</b>	<b>0</b>		<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Loma Linda ES

106474					8/23/2013		202		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/23/2013 3:28:34 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador		Chava need a square drag for loma linda thank you							
--------------------	--	---	--	--	--	--	--	--	--

Eric Medina

114131					3/2/2014	3/8/2014	11		\$0.00
--------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				3/2/2014 12:27:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Medina, Eric		Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

106797	Main Building	Restroom			8/30/2013		195		\$0.00
--------	---------------	----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	In Front of Mrs.			8/30/2013 10:48:44 AM				
--------	------------------	------------------	--	--	-----------------------	--	--	--	--

Marquez, Gerardo		Stall doors in the boys restroom in front of Mrs. Whites room dont lock							
------------------	--	---	--	--	--	--	--	--	--

Angie Flores

108825	Main Building				10/14/2013		150		\$0.00
--------	---------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress	Nurses Office			10/14/2013 11:36:02				
--------	------------------	---------------	--	--	---------------------	--	--	--	--

Marquez, Gerardo		New Lock for Large Medicine Cabinet							
------------------	--	-------------------------------------	--	--	--	--	--	--	--

Angie Flores

113376	Main Building	Gym			2/13/2014		28		\$0.00
--------	---------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Stage			2/13/2014 2:17:21 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Sotelo, Enrique		Knobs that control the lighting for the stage where completely broken off, need to be replaced							
-----------------	--	--	--	--	--	--	--	--	--

Angie Flores

113003	Main Building	Classroom			2/5/2014		36		\$0.00
--------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	108			2/5/2014 8:45:45 AM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Medina, Eric		Blinds will not open or close "both"							
--------------	--	--------------------------------------	--	--	--	--	--	--	--

Angie Flores

114445	Main Building	Classroom			3/10/2014		3		\$0.00
--------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Computer Lab			3/10/2014 2:15:19 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Medina, Eric		Three light fixtures in the computer lab are still not working and need to be repaired or replaced.							
--------------	--	---	--	--	--	--	--	--	--

Angie Flores

111837	Main Building	Classroom			1/9/2014		63		\$0.00
--------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	205			1/9/2014 1:26:31 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Medina, Eric		Lights flick on and off, some missing							
--------------	--	---------------------------------------	--	--	--	--	--	--	--

Angie Flores

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Loma Linda ES</b>							
113773					2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 2:12:28 PM				
Solis, Lorenzo		Lorenzo unit b in portable 1 is not cooling							
Eric Medina									
114001					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:25:59 AM				
Medina, Eric		Yearly - Loma Linda ES A10 (Heat Pumps)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
113927					2/28/2014	3/31/2014	13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:51 AM				
Medina, Eric		Yearly - Loma Linda ES C11(Evap.Condnsr)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
111483					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:20 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PMschedule details.							
Margret Villalobos									
112414					1/23/2014		49		\$0.00
Medium	Work In Progress				1/23/2014 3:42:30 PM				
Sotelo, Enrique		need to replace 9 outdated light fixtures in rm 207							
Eric Medina									
112542					1/28/2014		44		\$0.00
Medium	Work In Progress				1/28/2014 3:27:25 PM				
Sotelo, Enrique		need 6 pole light bulbs replaced							
Eric Medina									
110300					11/15/2013		118		\$0.00
Safety	Work In Progress				11/15/2013 12:28:27				
Flores, Pete		Pete the seat belt in truck 31 fixed or replaced please thank you							
Eric Medina									
114561					3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 1:04:27 PM				
Medina, Eric		need to extracted several basketball from ceiling							
Eric Medina									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Loma Linda ES</b>									
114562					3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 1:17:13 PM				
Medina, Eric		need to unclogg two waterfountain drains cafeteria and 6th hall							
Eric Medina									
114380					3/7/2014		6		\$0.00
Medium	Work In Progress				3/7/2014 12:38:08 PM				
Medina, Eric		Need to replace basketball goals							
Eric Medina									
112719					1/31/2014		41		\$0.00
Medium	Work In Progress				1/31/2014 2:17:51 PM				
Medina, Eric		need to replace sprinkler valve covers and sprinklers on secondary playground							
Eric Medina									
114044					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:22 AM				
Medina, Eric		Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PMSchedule details.							
Margret Villalobos									
114043					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:21 AM				
Medina, Eric		Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
114042					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:20 AM				
Medina, Eric		Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
113304					2/12/2014		29		\$0.00
Medium	Work In Progress				2/12/2014 8:06:11 AM				
Holguin, Alfredo		need to replace sand with woodchips on primary playground and replace 12 borders							
Eric Medina									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Loma Linda ES</b>										
113305					2/12/2014		29		\$0.00	
Medium	Work In Progress				2/12/2014 8:08:01 AM					
Holguin, Alfredo		need to replace sand with woodchips in secondary playground and replace 6 borders								
Eric Medina										
114381					3/7/2014		6		\$0.00	
Medium	Work In Progress				3/7/2014 12:39:29 PM					
Gonzalez, Salvador		Sal need to lower two basketball goals to six feet								
Eric Medina										
114506					3/11/2014		2		\$0.00	
Medium	Work In Progress				3/11/2014 3:05:49 PM					
Orozco, Daniel		The drain from the ice maker is not draining and is full please advice.								
Maritza Gonzalez										
114412					3/9/2014	3/25/2014	4		\$0.00	
Medium	Work In Progress				3/9/2014 12:18:59 AM					
Medina, Eric		Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos										
<b>Count: 27 Work Orders</b>		<b>Avg. Age of WO's 43</b>		<b>Total for Loma Linda ES</b>			<b>0</b>	<b>\$0.00</b>		

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Mesquite ES</b>							
113365					2/13/2014		28		\$0.00
Medium	Work In Progress				2/13/2014 9:35:07 AM				
Ronquillo, Ruben		need 3 canvass playground covers repaired							
Joe Ramirez									
112896					2/3/2014		38		\$0.00
Medium	Work In Progress				2/3/2014 1:44:33 PM				
Ramirez, Joe		need to replace 3" closet flange in girls kinder bathroom.							
Joe Ramirez									
114083					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:40 AM				
Ramirez, Joe		Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114084					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:40 AM				
Ramirez, Joe		Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
113366					2/13/2014		28		\$0.00
Medium	Work In Progress				2/13/2014 9:52:19 AM				
Holguin, Alfredo		need 3 sand play areas replaced with engineered wood fiber. area 2 needs 62 pieces of border replaced							
Joe Ramirez									
114109					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:52 AM				
Apodaca, Mario		Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
111219					12/12/2013		91		\$0.00
Medium	Work In Progress				12/12/2013 3:32:59 PM				
Holguin, Alfredo		Demo - Remove septic tank and electrical							
Alfredo Holguin									
114313					3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 7:58:27 AM				
Villalobos, David		need to replace 4 sensor activated lavatories in 2 bathrooms they are not working properly.							
Joe Ramirez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Mesquite ES</b>									
111486					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress			1/5/2014 12:23:21 AM					
Villalobos, David	Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
111343					12/17/2013		86		\$0.00
Medium	Work In Progress			12/17/2013 8:30:22 AM					
Villalobos, David	need to re-pipe hydronic system.								
Joe Ramirez									
114423		Parking Lot			3/10/2014		3		\$0.00
Medium	Work In Progress			3/10/2014 7:36:55 AM					
Sotelo, Enrique	please around the school and the parking lot is to dark can you please set timer earlier so is not so dark in the morning for safety								
Luis Saucedo									
111996					1/13/2014		59		\$0.00
Medium	Work In Progress			1/13/2014 8:11:26 AM					
Marquez, Gerardo	automatic door closer needs to be installed								
Joe Ramirez									
113996					3/2/2014		11		\$0.00
Medium	Work In Progress			3/2/2014 12:25:56 AM					
Ramirez, Joe	Yearly - Mesquite ES A-10 HP Rooftop Yearly - Refer to PMs schedule details.								
Margret Villalobos									
113919					2/28/2014	3/31/2014	13		\$0.00
Medium	Work In Progress			2/28/2014 12:32:47 AM					
Ramirez, Joe	Yearly - Mesquite ES C-11 Evap Coolers Yearly - Refer to PMs schedule details.								
Margret Villalobos									
107019	Pump House	Pump House			9/3/2013		191		\$0.00
Medium	Work In Progress			9/3/2013 3:26:54 PM					
Marquez, Gerardo	the door to the Pump Room at mesquite elementary needs to be replaced door hinges are broken up and very hard to open								
Mario Apodaca									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Mesquite ES</b>									
113958	1995 Addition	Office			2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 11:36:00 AM				
Sotelo, Enrique		Mr. Moreno's Office- bypass switch for AC in Multipurpose Room.							
Alfredo Holguin									
114113					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:54 AM				
Ramirez, Joe		Monthly - Mesquite ES Monthly FE Inpsection - Refer to PMs schedule details.							
Margret Villalobos									
105671					8/8/2013		217		\$0.00
Medium	Work In Progress				8/8/2013 1:03:55 PM				
Marquez, Gerardo		door and door jamb for rm .608 needs to be replaced it is in reall ybad shape.							
Joe Ramirez									
<b>Count: 18 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>50</b>		<b>Total for Mesquite ES</b>	<b>0</b>		<b>\$0.00</b>



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>North Valley ES</b>							
113943					2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 12:33:00 AM				
Munoz, Michael		Yearly - North Valley ES - Fire Pump Inspection - Refer to PMschedule details.							
Margret Villalobos									
114130					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:27:02 AM				
Vega, Danny		Monthly - North Valley ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
114022					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:10 AM				
Vega, Danny		Yearly - North Valley ES A10 (Heat Pumps)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
111035		Office			12/9/2013		94		\$0.00
Medium	Work In Progress	nurses office rm			12/9/2013 11:08:57 AM				
Marquez, Gerardo		Please send locksmith, we have purchased 2 new locks for our medicine cabinet that need to be installed.							
Priscilla Martinez									
114148					3/3/2014		10		\$0.00
Medium	Work In Progress				3/3/2014 10:16:02 AM				
Ontiveros, Guadalupe		Attention Lupe o-/need fertilzer on grass field(weed and feed type)had alot of weed spread out last year /never gave grass a chance to grow its starting come back.APPRX 40 SACKS							
Danny Vega									
113301					2/12/2014		29		\$0.00
Medium	Work In Progress				2/12/2014 7:41:12 AM				
Sotelo, Enrique		emergency lite ballast are burnt out in mechanical rms byrms 301-303-304-308-309-311-mechanical rm by staff lounge and pipe chase closet bybys rr peach wing and rio grand wing piope chase also these are for heater unit closets							
Danny Vega									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** North Valley ES

111496 1/5/2014 2/5/2014 67 \$0.00

Medium Work In Progress 1/5/2014 12:23:26 AM

Villalobos, David Yearly - North Valley ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

108414 10/6/2013 158 \$0.00

Medium Work In Progress 10/6/2013 12:24:11 AM

Holguin, Alfredo Monthly - North Valley ES - Fire Pump Engine - Refer to PM schedule details.

Margret Villalobos

111531 1/5/2014 67 \$0.00

Medium Work In Progress 1/5/2014 12:23:47 AM

Holguin, Alfredo Monthly - North Valley ES - Fire Pump Engine - Refer to PM schedule details.

Margret Villalobos

113536 2/19/2014 22 \$0.00

Medium Work In Progress 2/19/2014 11:44:10 AM

Holguin, Alfredo have (3ea)sand box sections need sand removed and fill w/wood chips (borders are all good )

Danny Vega

113808 2/25/2014 16 \$0.00

Medium Work In Progress 2/25/2014 3:49:10 PM

Vega, Danny 2-25-14 2/25/14 - 8 hrs / \$80

1-ck heat pumps at nve  
1-ck boiler at Im pre-k  
2.5-clean sidewalks w/blower and wheelbarrow nve  
3.5-service roof top units and chng filters Total \$80.00  
nve

Danny Vega

114410 3/9/2014 3/25/2014 4 \$0.00

Medium Work In Progress 3/9/2014 12:18:58 AM

Vega, Danny Monthly - North Valley ES Playground Inspection - Refer to PM schedule details.

Margret Villalobos

114049 3/2/2014 3/10/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:24 AM

Vega, Danny Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: North Valley ES</b>									
114047					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:23 AM				
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
113640					2/21/2014		20		\$0.00
Medium	Work In Progress				2/21/2014 7:49:34 AM				
Vega, Danny	need replacement filters for nve and lm pre-k/sizes included on forms								
Danny Vega									
<b>Count: 15 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>36</b>	<b>Total for North Valley ES</b>			<b>0</b>	<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
114046					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress			3/2/2014 12:26:22 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
112356					1/23/2014		49		\$0.00
Medium	Work In Progress			1/23/2014 6:32:36 AM					
Vega, Danny	need to tie in to existing irrigation system in front of campus.								
Michael Munoz									
114411					3/9/2014	3/25/2014	4		\$0.00
Medium	Work In Progress			3/9/2014 12:18:58 AM					
Vega, Danny	Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
113535					2/19/2014		22		\$0.00
Medium	Work In Progress			2/19/2014 11:41:20 AM					
Holguin, Alfredo	need sand removed from 3 (ea) plygrd section sand boxes and filled w/wood chips total of 20 (ea) borders that in need of replacement								
Danny Vega									
114048					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress			3/2/2014 12:26:24 AM					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
113264					2/11/2014		30		\$0.00
Medium	Work In Progress			2/11/2014 2:06:05 PM					
Ronquillo, Ruben	NEED PLASTIC THAT HOLDS LETTERS FOR MARQUEE REPLACED. MANY PARTS HAVE BROKEN OFF.(BOTH SIDES)					Asp Danny V. route to Ruben will be sending Company			
Adam Montoya									
113267					2/11/2014		30		\$0.00
Medium	Work In Progress			2/11/2014 2:29:40 PM					
Ronquillo, Ruben	NEED REPLACEMENT FLAGS FOR BOTH AMERICAN AND NEW MEXICO FLAGS.								
Adam Montoya									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
111484					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:20 AM				
Villalobos, David	Yearly - Northern Pre-K Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
114155					3/3/2014		10		\$0.00
Medium	Work In Progress				3/3/2014 11:30:24 AM				
Ontiveros, Guadalupe	NEED FERTILIZER ON GRASS FIELD (WWED N FEED) APPRX 20 SACKS								
Danny Vega									
111683					1/6/2014		66		\$0.00
Medium	Work In Progress				1/6/2014 3:05:45 PM				
Ontiveros, Guadalupe	need 1 load fill dirt for sidewalks at Im pre-k and small bucket tractor to level off								
Danny Vega									
114129					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:27:02 AM				
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
109121	Main Building				10/21/2013		143		\$0.00
Medium	Work In Progress				10/21/2013 2:21:43 PM				
Gonzales, Camilo	NEED OUTSIDE CLASSROOM (ROOM 17) CLEARED OUT. OLD/BROKEN DESKS AND FURNITURE. AS PER ROSIE REYES.								
Adam Montoya									
113263	Main Building				2/11/2014		30		\$0.00
Medium	Work In Progress				2/11/2014 1:59:49 PM				
Solis, Lorenzo	NEED BOILER FIXED. BOILER KEEPS SHUTTING OFF AND BLOWING OUT COLD AIR.								
Adam Montoya									
113854	Main Building	Classroom			2/27/2014		14		\$0.00
Medium	Work In Progress				2/27/2014 7:57:11 AM				
Solis, Lorenzo	AS PER THE DAYCARE, (CLASSROOM 114) WATER LEAK FROM PIPES ALONG CEILING.								
Adam Montoya									
<b>Count: 14 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>36</b>	<b>Total for Northern On-Track Pre-K (LM)</b>		<b>0</b>		<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To	Description				Action Taken				
Requester Name									

<b>Location:</b>		<b>Physical Plant Complex</b>							
114203	Food Services				3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 9:06:40 AM				
Sotelo, Enrique		LIGHTS IN OFFICE ARE GOING OUT.							
Maritza Gonzalez									
113587	Motor Vehicle				2/20/2014		21		\$0.00
Medium	Work In Progress				2/20/2014 9:01:17 AM				
Flores, Pete		Connie Sifuentes called vehicle #111 is overheating. She is stranded on Westside Dr/South Vinton							
Maria Ruiz									
113644	Motor Vehicle				2/21/2014		20		\$0.00
Medium	Work In Progress				2/21/2014 10:55:21 AM				
Perez, Raul		vehicle #48 has a dead battery							
Maria Ruiz									
104728	Motor Vehicle				7/25/2013		231		\$0.00
Medium	Work In Progress	5510 tractor			7/25/2013 10:19:26 AM				
Flores, Pete		tractor's warning lights are inoperative, and fuel gage is inaccurate. please check.							
Pete Flores									
113740	Motor Vehicle				2/24/2014		17		\$0.00
Medium	Work In Progress				2/24/2014 4:15:21 PM				
Flores, Pete		please service vehicle # 100. once serviced assign to the grounds department.							
thank you									
Michael Munoz									
114194	Motor Vehicle				3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 7:57:06 AM				
Flores, Pete		veeder root printing messages probe out & low temp warning. Alfredo is going to call Kachina to have them come out.				Pete removed probe and inserted back in tank... it cleared messages for a few minutes and then messages started printing again.			
111176	Motor Vehicle				12/11/2013		92		\$0.00
Medium	Work In Progress	vehicle 48			12/11/2013 3:36:30 PM				
Flores, Pete		please check and advise on malfunctioning anti-lock braking system and inoperative a/c.							
Pete Flores									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Physical Plant Complex**

114321 Motor Vehicle 3/6/2014 7 \$0.00

Medium Work In Progress Fed. Programs 3/6/2014 8:58:54 AM

Flores, Pete On Fed. Programs car #180 check engine and change oil lights turned on

Noemi Duron

114333 Motor Vehicle 3/6/2014 7 \$0.00

Medium Work In Progress kubota tractor 3/6/2014 2:37:10 PM

Flores, Pete right front blistered, needs to be replaced.

Pete Flores

112014 Motor Vehicle 1/13/2014 59 \$0.00

Medium Work In Progress ditchwitch rt45 1/13/2014 1:05:57 PM

Flores, Pete please check cause of burning smell.

Pete Flores

110392 Motor Vehicle 11/19/2013 114 \$0.00

Medium Work In Progress 11/19/2013 9:49:47 AM

Gonzalez, Salvador need door installed to addition to auto shop metal back building. thank you.

Michael Munoz

113968 Purchasing 2/28/2014 13 \$0.00

Medium Work In Progress 2/28/2014 3:20:17 PM

Carrasco, Danny need a combination receiver ball set for truck 38 with lock set

Mario Apodaca

112432 Purchasing Office 1/24/2014 48 \$0.00

Medium Work In Progress 1/24/2014 9:12:13 AM

Chavez, Saul Please shampoo carpet, Instructional Material Office (Mr. Leyva). Thank You.

Theresa Ramirez

113855 Purchasing 2/27/2014 14 \$0.00

Medium Work In Progress 2/27/2014 8:02:26 AM

Villalobos, David Men's Restroom in Custodial Warehouse - Raise urinal

Alfredo Holguin

110715 Purchasing 12/2/2013 101 \$0.00

Medium Work In Progress 12/2/2013 11:15:53 AM

Solis, Lorenz Men's and Women's restroom. Provide heating

Alfredo Holguin

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
113750					2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 8:56:19 AM				
Munoz, Michael		purchase tv for new conference/training/lounge.							
Michael Munoz									
114268					3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 9:36:06 AM				
Ronquillo, Ruben		PURCHASE 7'X12' DUMP TRAILER. THANK YOU!							
Ruben Ronquillo									
114204					3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 9:13:41 AM				
Ronquillo, Ruben		PURCHASE 2EA. LINE LOCATORS. THANK YOU!							
Ruben Ronquillo									
114230					3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 3:42:38 PM				
Ronquillo, Ruben		PURCHASE ELECTRIC SPRAY GUN AND AIRLESS SPRAYER. THANK YOU!							
Ruben Ronquillo									
113297					2/11/2014		30		\$0.00
Medium	Work In Progress				2/11/2014 4:18:10 PM				
Marquez, Gerardo		New Lounge - Need to install doors in Heater & Pantry Closets.							
Michael Munoz									
112175					1/16/2014		56		\$0.00
Medium	Work In Progress				1/16/2014 7:28:50 AM				
Flores, Pete		please service truck # 119 (jose ambriz) and wash. thank you							
Michael Munoz									
113554					2/19/2014		22		\$0.00
Medium	Work In Progress				2/19/2014 3:10:07 PM				
Flores, Pete		vehicle 99 is overheating. please check. thank you							
Michael Munoz									



**892 - Work Orders In Progress (Fiscal Year)**

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Physical Plant Complex**

113055					2/6/2014		35		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

High	Work In Progress				2/6/2014 7:48:34 AM				
------	------------------	--	--	--	---------------------	--	--	--	--

Chavez, Saul  
Detail work is needed in the following: Walls need dusting (custodial warehouse), Doors need cleaning (all offices), Walls need cleaning(all bathrooms), Light fixtures need cleaning (all offices)

Jesus Estrada

113583					2/20/2014		21		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/20/2014 8:01:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo  
Lock to Margret's office is hard to lock/unlock asp Saul, Custodian.

Saul Chavez

106552		Athletic Field			8/27/2013		198		\$0.00
--------	--	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/27/2013 8:41:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo  
need copies of keys for new fuel cap that was install on John Deere Backhoe L110

Guadalupe Ontiveros

113812					2/25/2014		16		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2014 3:56:53 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo  
need a spare set of keys for trucks 38 For Expedition & toolbox

Mario Apodaca

109051					10/17/2013		147		\$0.00
--------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/17/2013 4:11:07 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenzø  
please install heating and cooling unit in old electrical/hvac shop and remove existing furnace and a/c. thank you

Michael Munoz

111487					1/5/2014	2/5/2014	67		\$0.00
--------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				1/5/2014 12:23:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David  
Yearly - Physical Plant Backflow Inspection - Refer to PMschedule details.

Margret Villalobos

109289					10/24/2013		140		\$0.00
--------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2013 10:51:56				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David  
ice machine will be placed in lobby area of rest rooms in the old hvac/ electrical shop. will need sewer and water. thankyou

Michael Munoz

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
111139					12/11/2013		92		\$0.00
Medium	Work In Progress				12/11/2013 8:25:15 AM				
Sotelo, Enrique		Need to install light on pole where mobile home use to be.							
Michael Munoz									
110384					11/19/2013		114		\$0.00
Medium	Work In Progress				11/19/2013 7:56:50 AM				
Sotelo, Enrique		please provide lighting to new conference room . where old electrical/hvac shop used to be.							
Michael Munoz									
113953					2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 8:18:47 AM				
Gonzalez, Salvador		2-27-14 Attn Danny Carrasco Requesting 20 ton shop press for welding shop.							
Salvador Gonzalez									
113669					2/21/2014		20		\$0.00
Medium	Work In Progress				2/21/2014 3:45:38 PM				
Ronquillo, Ruben		ford truck 38 need order dash covers and floor mats							
Mario Apodaca									
113673					2/21/2014		20		\$0.00
Medium	Work In Progress				2/21/2014 3:48:32 PM				
Ronquillo, Ruben		ORDER DASH MATS AND FLOOR MATS FOR VEHICLE #37							
Ruben Ronquillo									
109372					10/28/2013		136		\$0.00
Medium	Work In Progress				10/28/2013 7:25:31 AM				
Diaz, Sebastian		Maint Office - Need to paint inside of main door and replace covebase.							
Michael Munoz									
112596					1/29/2014		43		\$0.00
Medium	Work In Progress				1/29/2014 1:18:59 PM				
Ronquillo, Ruben		PURCHASE 3EA INGERSOLL/1EA CHARGER, AND 2EA. TRAILER JACKS							
Ruben Ronquillo									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
113320					2/12/2014		29		\$0.00
Medium	Work In Progress				2/12/2014 11:29:30 AM				
Ronquillo, Ruben		Ballast disposal							
Alfredo Holguin									
111570					1/5/2014		67		\$0.00
Medium	Work In Progress				1/5/2014 12:24:12 AM				
Flores, Pete		Monthly - PPD-MP-0143 DT PM Service - by SWP - Refer to PM schedule details.							
Margret Villalobos									
111656					1/6/2014		66		\$0.00
Medium	Work In Progress				1/6/2014 12:24:15 AM				
Flores, Pete		Monthly - PPD - UV-0516 PM Service - Refer to PM schedule details.							
Margret Villalobos									
112825					2/2/2014		39		\$0.00
Medium	Work In Progress				2/2/2014 12:26:32 AM				
Flores, Pete		Monthly - PPD-T-0529 PM (Trencher) - by SWP - Refer to PM schedule details.							
Margret Villalobos									
114551					3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 8:47:43 AM				
Flores, Pete		need to order one pair of side steps for vehicle 38							
Mario Apodaca									
113418					2/14/2014		27		\$0.00
Medium	Work In Progress				2/14/2014 12:22:32 AM				
Flores, Pete		Yearly - PPD-T-0524 Bobcat PM Service - Refer to PM schedule details.							
Margret Villalobos									
113453					2/14/2014		27		\$0.00
Medium	Work In Progress				2/14/2014 3:45:58 PM				
Miranda, Danny		Installation of cabinets and appliances in PPD Lounge room assigned to Danny M.							
Danny Carrasco									
108706					10/10/2013		154		\$0.00
Medium	Work In Progress				10/10/2013 3:53:08 PM				
Flores, Pete		No back lights when I turn on the switch and front windshield is cracked							
David Villalobos									
3/13/2014 10:49:52 AM									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Physical Plant Complex</b>							
110835					12/4/2013		99		\$0.00
Medium	Work In Progress				12/4/2013 10:47:58 AM				
Holguin, Alfredo		Acquire "Right of Use Permit" for 40ft of left bank of Anthony drain for parking access, fence and landscaping.							
Alfredo Holguin									
114327					3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 1:26:39 PM				
Ronquillo, Ruben		PURCHASE 10EA. 18V DE-WALT COMBO KITS. THANK YOU!							
Ruben Ronquillo									
114051					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:25 AM				
Ruiz, Maria		Monthly - PPD - Fueling Station Monthly Inspection - Refer to PMSchedule details.							
Margret Villalobos									
114110					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:52 AM				
Apodaca, Mario		Monthly - Physical Plant - Grease Trap (Custodial) - Refer to PMSchedule details.							
Margret Villalobos									
114567					3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 2:46:44 PM				
Apodaca, Mario		need to order accessories truck 38 need a jobox ,ladder carrier and installed							
Mario Apodaca									
113676		Lift Station			2/21/2014		20		\$0.00
Medium	Work In Progress				2/21/2014 3:53:57 PM				
Ronquillo, Ruben		need to sign 4 wastewater treatment plant at the PPD Facility That reads gadaden Independent School District wastewater treatment plant							
Mario Apodaca									
111444					12/19/2013		84		\$0.00
Medium	Work In Progress				12/19/2013 2:56:01 PM				
Gonzalez, Salvador		fence behind ppd barracks is down. please install poles to fence for temporary repair. thank you							
Michael Munoz									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Physical Plant Complex</b>										
109287					10/24/2013		140		\$0.00	
Medium	Work In Progress				10/24/2013 10:47:27					
Gonzalez, Salvador		old blue trailer. please raise the sides for scrap metal. see mike for details. thank you								
Michael Munoz										
114530					3/11/2014		2		\$0.00	
Medium	Work In Progress				3/11/2014 4:04:58 PM					
Gonzalez, Salvador		please make pole hangers for ppd banner. please see mike for details. thank you								
Michael Munoz										
<b>Count: 53 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>52</b>	<b>Total for Physical Plant Complex</b>			<b>0</b>	<b>\$0.00</b>	

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Riverside ES</b>									
114419					3/9/2014	3/25/2014	4		\$0.00
Medium	Work In Progress				3/9/2014 12:19:03 AM				
Martinez, Mario		Monthly - Riverside ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
113362					2/13/2014		28		\$0.00
Medium	Work In Progress				2/13/2014 8:16:43 AM				
Holguin, Alfredo		Riverside Elementary has four sand playgrounds. North side has three. 1 is 3149 sq ft. Another is 2760 sq ft. The third is 4545 sq ft. Those are all on North side playground. South side has one sand playground with a sq footage of 11,200 sq feet.							
Mario Martinez									
109227					10/23/2013		141		\$0.00
Medium	Work In Progress				10/23/2013 9:43:53 AM				
Moncayo, Fernando		please cut weeds and clean area where mobile home used to be. In the fenced area and surrounding areas as well. thank you							
Michael Munoz									
111719		Restroom			1/7/2014		65		\$0.00
Medium	Work In Progress				1/7/2014 9:04:31 AM				
Martinez, Mario		Need to repair or replace 4 inch lavatory faucets in Boys/Girls bathrooms.							
Mario Martinez									
114384		Athletic Field			3/7/2014		6		\$0.00
Medium	Work In Progress				3/7/2014 2:48:40 PM				
Martinez, Mario		Need to repair broken, and missing sprinkler heads and sprinkler lines.							
Mario Martinez									
113382					2/13/2014		28		\$0.00
Medium	Work In Progress				2/13/2014 2:43:44 PM				
Martinez, Mario		Need to fill in broken 6 inch red tiles with concrete.							
Mario Martinez									
113384					2/13/2014		28		\$0.00
Medium	Work In Progress				2/13/2014 2:47:36 PM				
Martinez, Mario		Need to replace water damaged ceiling tiles.							
Mario Martinez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
113115					2/7/2014		34		\$0.00
Medium	Work In Progress			2/7/2014 8:06:31 AM					
Martinez, Mario	Need to change out florescent lighting through out entire South and Middle wings, Computer lab, and main office. North wing completed on 2/06/14.								
Mario Martinez									
113499					2/18/2014		23		\$0.00
Medium	Work In Progress			2/18/2014 3:30:44 PM					
Martinez, Mario	Need to purchase and install 25 window blinds. Color and size on request. 10 42 inch X 80 inch, 10 24inch X 80 inch, 4 24 inch X 64 inch, and 1 72 inch X 80 inch.								
Mario Martinez									
114092					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress			3/2/2014 12:26:44 AM					
Martinez, Mario	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
114501		Restroom			3/11/2014		2		\$0.00
Medium	Work In Progress			3/11/2014 2:27:53 PM					
Ontiveros, Joe	Need plumber Joe O. to unstop one lavatory in boys restroom in middle wing.								
Mario Martinez									
112046					1/14/2014		58		\$0.00
Medium	Work In Progress			1/14/2014 7:22:53 AM					
Castillo, Carlos	Need lights at Southwest portables fixed.		2/26 -Reroute to Cali						
Mario Martinez									
113114					2/7/2014		34		\$0.00
Medium	Work In Progress			2/7/2014 7:56:35 AM					
Castillo, Carlos	Need Carlos C. to replace or repair light fixtures in rooms 116/117/121/123/137/148, also in music portable and art portable.								
Mario Martinez									
111430		Electrical Room			12/19/2013		84		\$0.00
Medium	Work In Progress			12/19/2013 9:20:46 AM					
Castillo, Carlos	Annual electrical equipment inspection.								
Carlos Castillo									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Riverside ES**

111488 1/5/2014 2/5/2014 67 \$0.00

Medium Work In Progress 1/5/2014 12:23:22 AM

Villalobos, David Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

110787 12/3/2013 100 \$0.00

Medium Work In Progress 12/3/2013 2:41:42 PM

Villalobos, David please check backflow preventers. as per Mario one is leaking every 3 minutes. thankyou 3/7-Route to David

Michael Munoz

113206 2/10/2014 31 \$0.00

Medium Work In Progress 2/10/2014 12:57:10 PM

Villalobos, David On 2/06/2014 Horizon Mechanical came by to work on backflow but were not able to repair it due to not having the repair kit needed. Will return 7 to 10 days later to fix it. Attention David Villalobos.

Mario Martinez

114160 3/3/2014 10 \$0.00

Medium Work In Progress 3/3/2014 3:20:58 PM

Ambriz, Jose Need Jose Ambriz to repair leaking gasket on on heating valve at mechanical room next to sixth grade wing.

Mario Martinez

113921 2/28/2014 3/31/2014 13 \$0.00

Medium Work In Progress 2/28/2014 12:32:48 AM

Martinez, Mario Yearly - Riverside ES C-11 Evap Coolers Yearly - Refer to PM schedule details.

Margret Villalobos

114004 3/2/2014 11 \$0.00

Medium Work In Progress 3/2/2014 12:26:01 AM

Martinez, Mario Yearly - Riverside ES A-10 HP Rooftop Yearly - Refer to PM schedule details.

Margret Villalobos

112541 1/28/2014 44 \$0.00

Medium Work In Progress 1/28/2014 3:20:59 PM

Flores, Pete Attention, Pete Flores would like your assistance on blades and belts adjustments on John Deere LA 125 riding mower.

Mario Martinez



**892 - Work Orders In Progress (Fiscal Year)**

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Riverside ES</b>									
110138					11/12/2013		121		\$0.00
Medium	Work In Progress				11/12/2013 2:53:05 PM				
Ontiveros, Guadalupe		Pine tress on south side next to playground. Need to check irrigation system, trees are dead or dying.							
Alfredo Holguin									
110158					11/12/2013		121		\$0.00
Medium	Work In Progress				11/12/2013 4:02:42 PM				
Ontiveros, Guadalupe		replace damaged soccer goal was hit by a car.							
Alfredo Holguin									
109972	Main Building	Parking Lot			11/6/2013		127		\$0.00
Medium	Work In Progress				11/6/2013 12:30:33 PM				
Ontiveros, Joe		Joe, por favor si nos podia revisar la toma de el agua que esta afuera de la area de kinder para enfrente de la Macnutt, porque necesitamos lavar la entrada y no tiene agua muchas gracias.+							
Miguel Sonora									
108675	Main Building	Restroom			10/10/2013		154		\$0.00
Medium	Work In Progress	RESTROOM			10/10/2013 10:21:47				
Ambriz, Jose		VENT IN MAIN OFFICE RESTROOM IS NOT WORKING							
Rosa Quezada									
113489	Main Building	Office			2/18/2014		23		\$0.00
Medium	Work In Progress	teacher's lounge			2/18/2014 2:59:33 PM				
Ambriz, Jose		we received the ice maker and need it installed in the teacher's lounge. please have Joe come out to install (navarro)							
Rosa Quezada									
105474	Main Building				8/6/2013		219		\$0.00
Medium	Work In Progress				8/6/2013 10:08:22 AM				
Moncayo, Fernando		bathrooms and main hallways need painting (navarro)							
Rosa Quezada									
113856	Main Building	Office			2/27/2014		14		\$0.00
Medium	Work In Progress				2/27/2014 8:42:44 AM				
Carbajal, Jimmy		we need to move the fire filing cabinets, and if, you could borrow the special dolly to do that. Thank you.							
Miguel Sonora									
<b>Count: 28 Work Orders</b>			<b>Avg. Age of WO's 57</b>				<b>Total for Riverside ES</b>	<b>0</b>	<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: RTC - Alliance</b>									
112426		Classroom			1/24/2014		48		\$0.00
Medium	Work In Progress				1/24/2014 8:30:33 AM				
Moncayo, Fernando		the rooms and office need filters replace							
Gloria Delgado									
112166		Classroom			1/15/2014		57		\$0.00
Medium	Work In Progress				1/15/2014 4:13:38 PM				
Moncayo, Fernando		we need doorstops on all portable and to clean grounds							
Gloria Delgado									
113600		Classroom			2/20/2014		21		\$0.00
Medium	Work In Progress				2/20/2014 2:14:57 PM				
Moncayo, Fernando		Please replace air filters and if possible air ducts cleaned.							
Gloria Delgado									
114538		Classroom			3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 7:57:03 AM				
Villalobos, Margret		we are in need of a medium to small teacher's desk in good to fair condition							
Gloria Delgado									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>32</b>		<b>Total for RTC - Alliance</b>	<b>0</b>		<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: San Miguel ES</b>									
114106					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:50 AM				
Apodaca, Mario	Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
111490					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:23 AM				
Villalobos, David	Yearly - San Miguel ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>39</b>	<b>Total for San Miguel ES</b>				<b>0</b>	<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa ES</b>									
111494					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:25 AM				
Villalobos, David		Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
114007					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:03 AM				
Ambriz, Juan		Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.							
Margret Villalobos									
114006					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:02 AM				
Ambriz, Juan		Yearly - Santa Teresa ES A-10 HEAT PUMPS (ANNUAL) - Refer to PM schedule details.							
Margret Villalobos									
114417					3/9/2014	3/25/2014	4		\$0.00
Medium	Work In Progress				3/9/2014 12:19:02 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
114076					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:37 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114075					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:36 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114072					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:35 AM				
Ambriz, Juan		Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa ES

111888	Main Building				1/10/2014		62		\$0.00
Medium	Work In Progress				1/10/2014 10:26:51 AM				
Lara, Ralph		I need a copy of the fire alarm key (front office has original) this key is for Principal Tarin.							

113386	Main Building	Parking Lot			2/13/2014		28		\$0.00
Medium	Work In Progress	front gates			2/13/2014 2:56:50 PM				
Ambriz, Juan		Need to replace wheels on all gates. Hard to open							
Juan Ambriz									

113656	Main Building	Mechanical			2/21/2014		20		\$0.00
Medium	Work In Progress				2/21/2014 2:47:16 PM				
Ambriz, Juan		Need to clean out mechanical room							
Juan Ambriz									

114367	Main Building	Football Field			3/7/2014		6		\$0.00
Medium	Work In Progress	all playground			3/7/2014 8:25:35 AM				
Ambriz, Juan		Need to fertilize back field							
Juan Ambriz									

112574	Main Building	Exterior			1/29/2014		43		\$0.00
Medium	Work In Progress	Basketball			1/29/2014 8:24:37 AM				
Ambriz, Juan		Need to cover cracks on cement on basketball courts							
Juan Ambriz									

112618	Main Building	Exterior			1/29/2014		43		\$0.00
Medium	Work In Progress				1/29/2014 3:42:03 PM				
Ambriz, Juan		As per Mrs. Tarin need to install school signs in front of school							
Juan Ambriz									

112572	Main Building	Hallway/Corridor			1/29/2014		43		\$0.00
Medium	Work In Progress	300 Hallway			1/29/2014 8:18:17 AM				
Ambriz, Juan		Need to replace fire extinguisher cover broken by student							
Juan Ambriz									

114215	Main Building	Cafeteria			3/4/2014		9		\$0.00
Medium	Work In Progress	kitchen			3/4/2014 12:39:16 PM				
Ambriz, Juan		Need to install shelves in kitchen office							
Juan Ambriz									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Santa Teresa ES**

113780	Main Building	Classroom			2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 2:50:23 PM				

Ambriz, Jose  
Need to check heating unit in room #103 motor making noise

Juan Ambriz

106980	Main Building	Classroom			9/3/2013		191		\$0.00
Medium	Work In Progress	Room 303			9/3/2013 8:48:32 AM				

Ambriz, Jose  
Need HVAC TECH to check a/c unit in room #303 not cooling

Juan Ambriz

107573	Main Building	Office			9/17/2013		177		\$0.00
Medium	Work In Progress	coaches office			9/17/2013 2:45:45 PM				

Ambriz, Jose  
Need to check a/c unit not cooling

Juan Ambriz

109418	Main Building	Classroom			10/28/2013		136		\$0.00
Medium	Work In Progress	Room #206			10/28/2013 2:05:48 PM				

Ambriz, Jose  
Need to check a/c unit in room #206 not working properly

Juan Ambriz

111841	Main Building	Hallway/Corridor			1/9/2014		63		\$0.00
Medium	Work In Progress	200 hallway			1/9/2014 3:04:10 PM				

Ontiveros, Joe  
Need to repair leak in 2 1/2" main domestic water

Juan Ambriz

110057	Main Building	Portables			11/8/2013		125		\$0.00
Medium	Work In Progress	Art portable			11/8/2013 9:49:09 AM				

Gonzalez, Salvador  
New storage bldg. (by art portable) needs a ramp. Thank you,

Rita Mendez

112234	Main Building	Parking Lot			1/17/2014		55		\$0.00
Medium	Work In Progress	Student Pick			1/17/2014 12:56:02 PM				

Gonzalez, Salvador  
The school needs a metal shade frame to be located at the student drop off/pick up area. Thank you.

Rita Mendez

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

<b>Location:</b>		<b>Santa Teresa ES</b>							
113441	Main Building	Exterior			2/14/2014		27		\$0.00
Medium	Work In Progress	Playgrounds			2/14/2014 3:25:01 PM				
Holguin, Alfredo		As per Alfredo playground sand needs to be removed and replaced with Engineered wood fibers, 2 playgrounds and a total of 41 borders							
Juan Ambriz									
114558					3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 11:22:25 AM				
Carbajal, Jimmy		HEIGHT ADJUSTMENT DOESNT WORK ON VAC #1163							
Jimmy Carbajal									
114118					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:56 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 25 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>47</b>	<b>Total for Santa Teresa ES</b>			<b>0</b>	<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa HS</b>									
114117					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress			3/2/2014 12:26:56 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
108087		Exterior			9/29/2013		165		\$0.00
Medium	Work In Progress			9/29/2013 12:19:45 PM					
Gonzalez, Salvador	The fence by the arroyo has been cut again. Could we get the welder to come in and redo the area. Thanks!								
William Dickson									
113248		Exterior			2/10/2014		31		\$0.00
Medium	Work In Progress			2/10/2014 10:32:42 PM					
Gonzalez, Salvador	The fence behind the vocational room needs repair. As a matter of fact the entire fence row needs attention. There are several holes in it.								
William Dickson									
108661		Exterior			10/9/2013		155		\$0.00
Medium	Work In Progress			10/9/2013 10:15:53 PM					
Gonzalez, Salvador	The Arroyo fence has been cut again. Will need repair please.								
William Dickson									
111909					1/10/2014		62		\$0.00
Medium	Work In Progress			1/10/2014 2:26:29 PM					
Mijarez, Jaime	Asp PM serviced by Dimar - need to add oil and rotate FDC.								
Michael Munoz									
111913					1/10/2014		62		\$0.00
Medium	Work In Progress			1/10/2014 2:30:03 PM					
Mijarez, Jaime	Asp PM serviced by Dimar - FAC cap missing in 200 Wing								
Michael Munoz									
111914					1/10/2014		62		\$0.00
Medium	Work In Progress			1/10/2014 2:30:43 PM					
Mijarez, Jaime	Asp PM serviced by Dimar - FAC cap missing in 300 Wing								
Michael Munoz									



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
105592					8/7/2013		218		\$0.00
Medium	Work In Progress				8/7/2013 12:52:27 PM				
Mijarez, Jaime		Asp inspection on PM Fire Sprinkler by Dimar the following was found: FDC missing cap							
Michael Munoz									
107461	Main Building	Classroom			9/15/2013		179		\$0.00
Medium	Work In Progress				9/15/2013 11:08:32 AM				
Mijarez, Jaime		Room 206 has two lights that are out and needs replacement							
William Dickson									
107105	Main Building	Classroom			9/5/2013		189		\$0.00
Medium	Work In Progress	water pumps			9/5/2013 7:30:16 AM				
Mijarez, Jaime		Please replace water pumps							
Kathryn Harper									
107779	Main Building	Computer Lab			9/20/2013		174		\$0.00
Medium	Work In Progress				9/20/2013 4:59:04 PM				
Mijarez, Jaime		Relocate a white board so students can review their work.							
William Dickson									
107780	Main Building	Computer Lab			9/20/2013		174		\$0.00
Medium	Work In Progress				9/20/2013 5:03:05 PM				
Mijarez, Jaime		The classroom that needed the white board moved is C2							
William Dickson									
106459	Main Building	Classroom			8/23/2013		202		\$0.00
Medium	Work In Progress				8/23/2013 11:20:00 AM				
Mijarez, Jaime		Need light bulbs for classroom C-2. Classroom very dark. It is a computer lab.							
William Dickson									
105148	Main Building	Classroom			8/2/2013		223		\$0.00
Medium	Work In Progress				8/2/2013 2:12:07 PM				
Mijarez, Jaime		Need to get a white board and project monted in room 607 for our SPED teacher.							
William Dickson									
107930	Main Building	Classroom			9/25/2013		169		\$0.00
Medium	Work In Progress	404			9/25/2013 2:52:28 PM				
Mijarez, Jaime		Please mount two dryerase boards to replace two chalkboards in Ms. Renteria's room.							
Kathryn Harper									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
106456	Main Building	Classroom			8/23/2013		202		\$0.00
Medium	Work In Progress	203			8/23/2013 10:56:44 AM				
Ambriz, Jose		The A/C in room 203 is VERY loud!. Teacher has to speak loudly and it's hard to students to hear. Please make this a priority. Thanks.							
Kathryn Harper									
107918	Main Building	Hallway/Corridor			9/25/2013		169		\$0.00
Medium	Work In Progress				9/25/2013 12:23:23 PM				
Ambriz, Jose		The water fountain new the front office is leaking non stop. will a plumber come by and fix it. Thanks!				3/7 - Asp Joe route to Jose			
William Dickson									
107101	Main Building	Foyer			9/5/2013		189		\$0.00
Medium	Work In Progress				9/5/2013 5:52:04 AM				
Ambriz, Jose		water fountain in 400 hallway is leaking							
Isaac Holguin									
109618	Main Building	Classroom			11/1/2013		132		\$0.00
Medium	Work In Progress	406, 410, 402,			11/1/2013 10:48:10 AM				
Mijarez, Jaime		These classrooms received smartboards. The walls need to be painted where old chalkboards were removed.							
Kathryn Harper									
110077	Main Building	Mechanical			11/8/2013		125		\$0.00
Medium	Work In Progress				11/8/2013 3:38:05 PM				
Ontiveros, Joe		Need to Replaces 1 inch Gas Riser rusted out outside boiler RM.							
Joe Ontiveros									
113371	Main Building	Classroom			2/13/2014		28		\$0.00
Medium	Work In Progress	200 -700			2/13/2014 10:58:52 AM				
Escobar, David		Replace mini blinds in 15 classrooms as needed Paint the classrooms that had smartboards installed							
Kathryn Harper									
106578	Main Building	Classroom			8/27/2013		198		\$0.00
Medium	Work In Progress	band room			8/27/2013 1:36:28 PM				
Escobar, David		Right outside band room, there's a hole in the wall				2/20/14 - Asp Mike, route to David			
Kathryn Harper									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

106642	Main Building				8/28/2013		197		\$0.00
--------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/28/2013 9:31:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime Teacher wants 21 chairs taken out of classroom.

William Dickson

107274	Main Building				9/9/2013		185		\$0.00
--------	---------------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/9/2013 4:49:11 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Mijarez, Jaime Mr. Gutierrez is wanting a white board mounted in his room. He is also wanting the light bulbs that are out replaced.

William Dickson

111174	Dressing Rooms	Dressing Room			12/11/2013		92		\$0.00
--------	----------------	---------------	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/11/2013 3:35:47 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos Dressing room time clocks need off-on switch to avoid coaching staff to be turning off circuit breakers.

Carlos Castillo

112316	Vocational	Kitchen			1/22/2014		48		\$0.00
--------	------------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/22/2014 9:58:40 AM	3/11/2014			
--------	------------------	--	--	--	----------------------	-----------	--	--	--

Escobar, David Attach can opener to table in culinary arts classroom. Room 707.

William Dickson

112317	Vocational	Kitchen			1/22/2014		48		\$0.00
--------	------------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/22/2014 9:59:52 AM	3/11/2014			
--------	------------------	--	--	--	----------------------	-----------	--	--	--

Escobar, David Attach 2 legged table to wall in kitchen room 707.

William Dickson

111903	Vocational				1/10/2014		62		\$0.00
--------	------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/10/2014 1:40:49 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador Cover small windows on doors that vandals have used to gain access into rooms with expanded metal. Check with site administration or security Tellez for specifics.

Alfredo Holguin

111874	Vocational	Classroom			1/9/2014		63		\$0.00
--------	------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/9/2014 10:47:57 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime The kids in studio to cook ceramic is not working. One braked in the box is taped. Please check it out. Thanks.

William Dickson

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

111875 Vocational Classroom 1/9/2014 63 \$0.00

Medium Work In Progress 1/9/2014 10:51:22 PM

Mijarez, Jaime Heat will not come on in the clays hop.  
Need paper dispenser added to sink area.  
Room is covered with spider webs may have a black widow in the area.  
Please check out.

William Dickson

107313 Library Library 9/10/2013 184 \$0.00

Medium Work In Progress Library 9/10/2013 3:37:35 PM

Mijarez, Jaime Put pictures of Classes in library on wall.

Kathryn Harper

111904 Library Library 1/10/2014 62 \$0.00

Medium Work In Progress 1/10/2014 1:41:56 PM

Lara, Ralph Alarm buzzer on Emergency Egress doors are not working

Alfredo Holguin

108991 Annex Building Kitchen 10/16/2013 148 \$0.00

Medium Work In Progress 10/16/2013 9:48:40 PM

Mijarez, Jaime Room 703 has a water leak from the pipes under the sink. It is causing damages to the wooden cabinet.

William Dickson

114447 Annex Building Classroom 3/10/2014 3 \$0.00

Medium Work In Progress 3/10/2014 2:31:25 PM

Lara, Ralph The keys to unlock the culinary arts kitchen doors keeps getting stuck in the lock. Need to get it fixed.

William Dickson

113430 Main Building Classroom 2/14/2014 25 \$0.00

Medium Work In Progress 2/14/2014 1:57:03 PM 3/11/2014

Escobar, David Room 213 lights bulbs are out needs replacing.  
Thanks!

William Dickson

109502 Main Building Classroom 10/29/2013 135 \$0.00

Medium Work In Progress 10/29/2013 4:13:17 PM

Mijarez, Jaime Room 215 needs two broom holders mounted on the left wall after entering the front door, a pattern is taped to the wall where the holder is to be placed. The hardware is taped to the pattern. The other broom holder pattern is taped on the wall in the storage closet.

William Dickson

3/13/2014 10:49:53 AM

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

107460 Main Building Classroom 9/15/2013 179 \$0.00

Medium Work In Progress 9/15/2013 11:06:56 AM

Mijarez, Jaime The culinary kitchen needs a can opener installed needs to see the Teacher for position of installment.

William Dickson

106125 Locker Room Gym 8/16/2013 209 \$0.00

Medium Work In Progress Pe locker room 8/16/2013 8:25:08 AM

Gonzalez, Salvador Removal of bent or broken locker doors in PE boys dressing room.

Kathryn Harper

114502 Locker Room Office 3/11/2014 2 \$0.00

Medium Work In Progress 3/11/2014 2:32:57 PM

Escobar, David Football locker room missing ceiling tiles. Need to get the projector screen screen put up. Fix broken shower tiles.

William Dickson

114448 Locker Room Dressing Room 3/10/2014 3 \$0.00

Medium Work In Progress 3/10/2014 2:34:38 PM

Lara, Ralph The girls locker room leading out to the football has a bad cylinder and it does not open well. Need attention.

William Dickson

114503 Locker Room Office 3/11/2014 2 \$0.00

Medium Work In Progress 3/11/2014 2:50:04 PM

Lara, Ralph Football locker - install locker clasp to 8 lockers with a blue X on it. Lock mechanism.

William Dickson

114446 Locker Room 3/10/2014 3 \$0.00

Medium Work In Progress 3/10/2014 2:25:29 PM

Lara, Ralph The restroom doors boys and girls are having a hard time opening. The key does not work. These are the hallways leading to Dotson's office.

William Dickson

111876 Cafeteria (2005) Classroom 1/9/2014 63 \$0.00

Medium Work In Progress 1/9/2014 10:53:38 PM

Escobar, David The curtains for the stage are in and need to be hung. Will you hang these up please. Thanks.

William Dickson

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Santa Teresa HS**

107203	Cafeteria (2005)				9/6/2013		188		\$0.00
--------	------------------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2013 5:03:35 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Mijarez, Jaime		Culinary Kitchen has a table that needs two legs that attaches to the wall (or existing counter) in dish area. 2nd notice				12/18/13 - One year warranty ran out in December 2012. This is a Building Mechanic work order. R. Gallegos			
----------------	--	--	--	--	--	--	--	--	--

William Dickson

108549	Cafeteria (2005)	Restroom			10/7/2013		157		\$0.00
--------	------------------	----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/7/2013 7:45:26 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime		The restroom in the cafeteria needs a paper dispenser. The one that was there is broken.							
----------------	--	--	--	--	--	--	--	--	--

William Dickson

107202	Cafeteria (2005)	Cafeteria			9/6/2013		188		\$0.00
--------	------------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2013 5:00:50 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Mijarez, Jaime		Culinary kitchen needs the shelves reinstalled in dining room counter area see teacher.							
----------------	--	---	--	--	--	--	--	--	--

William Dickson

106341	GYM (2009)	Gym			8/21/2013		204		\$0.00
--------	------------	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Basketball gym			8/21/2013 11:22:54 AM				
--------	------------------	----------------	--	--	-----------------------	--	--	--	--

Mijarez, Jaime		Foam rubber edging around basketball backboards in both gyms coming off, needs to be replaced/repared (see Coach Haack or Coach Dotson)							
----------------	--	---	--	--	--	--	--	--	--

Kathryn Harper

112064	GYM (2009)	Football Field			1/14/2014		58		\$0.00
--------	------------	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	FB & SOCCER			1/14/2014 10:23:13 AM				
--------	------------------	-------------	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe		GROUNDS - TOP DRESSING - SANTA TERESA HS THE LOWER FOOTBALL FIELD AND SOCCER FIELD.							
----------------------	--	--	--	--	--	--	--	--	--

Terry Alvarado

113247	GYM (2009)	Storage			2/10/2014		31		\$0.00
--------	------------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/10/2014 10:29:36 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe		need to move the metal storage from the storage room to the old concession stands.							
----------------------	--	--	--	--	--	--	--	--	--

William Dickson

108657		Kitchen			10/9/2013		155		\$0.00
--------	--	---------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/9/2013 10:07:49 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Mijarez, Jaime		Culinary Arts Kitchen needs 2 leg table attached to the wall in dish room.							
----------------	--	--	--	--	--	--	--	--	--

William Dickson

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
108658		Kitchen			10/9/2013		155		\$0.00
Medium	Work In Progress				10/9/2013 10:09:06 PM				
Mijarez, Jaime		Culinary Arts Kitchen needs the can opener attached to the table.							
William Dickson									
108659		Kitchen			10/9/2013		155		\$0.00
Medium	Work In Progress				10/9/2013 10:10:33 PM				
Mijarez, Jaime		Culinary Arts Kitchen attach self to the wall see teacher for directions							
William Dickson									
107284		Library			9/10/2013		184		\$0.00
Medium	Work In Progress				9/10/2013 8:38:41 AM				
Mijarez, Jaime		Library - The security mirror in the back of the library needs to be hung.							
William Dickson									
110896		Classroom			12/5/2013		98		\$0.00
Medium	Work In Progress	ROOM #404			12/5/2013 2:26:42 PM				
Mijarez, Jaime		JAIME CAN YOU PLEASE MOUNT 2 PROJECTION SCREENS IN MRS. RENTERIA'S ROOM #404 AND MR. HELM ROOM #700							
Marylou Jimenez									
104626					7/23/2013		233		\$0.00
Medium	Work In Progress				7/23/2013 2:12:58 PM				
Mijarez, Jaime		Will need to replace ceiling tiles in several gym dressing rooms. Ceiling tile is a different texture can you please order 4 ea. Bundles of the sample that I gave you or at least match it.							
Jaime Mijarez									
114032					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:15 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
114037					3/2/2014	4/2/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:18 AM				
Escobar, David		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Santa Teresa HS</b>							
114035					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:17 AM				
Escobar, David		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114036					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:17 AM				
Escobar, David		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
113197		Gym			2/10/2014		31		\$0.00
Medium	Work In Progress				2/10/2014 11:15:16 AM				
Munoz, Michael		New Gym Lobby concession stand. (Please give w/o to Mike Munoz and a copy to Alfredo H). Can we have a new candy/snack shelve built and installed in the new concession stand. I spoke to Mrs. Harper and told her that I would get with Mike and Alfredo and see if we could go that route instead of having to sand and repainting the old gym concession stand wooden shelve that we installed. Please call me for more info.							
Jaime Mijarez									
114100					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:48 AM				
Sanchez, Raul		Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PM schedule details.							
Margret Villalobos									
114211					3/4/2014		9		\$0.00
High	Work In Progress				3/4/2014 10:51:59 AM				
Gonzalez, Salvador		Build and install "harvest gates" as per diagram sent by e-mail							
Rafael Gallegos									
113006					2/5/2014		36		\$0.00
Medium	Work In Progress				2/5/2014 9:15:29 AM				
Orozco, Daniel		BOTTOM SWITCH TO TURN OF DISHWASHER IS BROKEN-SNP MANAGER OLGA B.589.5332							
Maritza Gonzalez									



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Santa Teresa HS</b>							
110332					11/16/2013		117		\$0.00
Medium	Work In Progress				11/16/2013 12:18:10				
Flores, Pete		Yearly - Santa Teresa HS - Mower 0425 - Grounds - Refer to PM schedule details.							
Margret Villalobos									
114264					3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 9:07:18 AM				
Ronquillo, Ruben		Please order 3 classroom wall signs like the sample that sent you. 1 ea. Room 312, 1 ea. Room 313, 1 ea. Room 314. include braille under the room and number on all three signs.							
Jaime Mijarez									
111325					12/16/2013		87		\$0.00
Medium	Work In Progress				12/16/2013 4:00:06 PM				
Holguin, Alfredo		Old gym bleachers. Please give work order to (Alfredo H.) I spoke to him. Wood swinging boards that run along the bottom of the bleachers are missing several pins on the hindges, The boards are uneven and won't stay flush with each other. I don't know when was the last time they were serviced.							
Jaime Mijarez									
113631					2/20/2014		21		\$0.00
Medium	Work In Progress				2/20/2014 4:01:52 PM				
Carrasco, Danny		Please order mini blinds on list so that we can install on classroom windows through out the buildings.							
Jaime Mijarez									
112770					2/2/2014	3/5/2014	39		\$0.00
Medium	Work In Progress				2/2/2014 12:26:05 AM				
Escobar, David		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
112662					1/30/2014		42		\$0.00
Medium	Work In Progress				1/30/2014 3:19:19 PM				
Mijarez, Jaime		Marylou Jimenez is requesting paint for the vault door in her office.							
Jaime Mijarez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa HS</b>									
104672					7/24/2013		232		\$0.00
Medium	Work In Progress			7/24/2013 8:52:31 AM					
Ambriz, Jose	HU2 airhandler at cafeteria is single phasing. Disconnected the line legs to motor and turned off power to unit.								
Jaime Mijarez									
113018					2/5/2014		36		\$0.00
Medium	Work In Progress			2/5/2014 11:13:13 AM					
Mijarez, Jaime	Councilors and 700 wing heating units. Please order 10 ea. fan/limit combo controls. We need 4 and the other 6 will stay with Joe and Lorenzo. Renznor HU.								
Jaime Mijarez									
113995					3/2/2014	4/2/2014	11		\$0.00
Medium	Work In Progress			3/2/2014 12:25:56 AM					
Mijarez, Jaime	Yearly - Santa Teresa HS A-10 HP Yearly - Refer to PM schedule details.								
Margret Villalobos									
113916					2/28/2014	3/31/2014	13		\$0.00
Medium	Work In Progress			2/28/2014 12:32:46 AM					
Escobar, David	Yearly - Santa Teresa HS C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									
114019					3/2/2014	3/18/2014	11		\$0.00
Medium	Work In Progress			3/2/2014 12:26:08 AM					
Villalobos, Margret	Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.				emailed Arlene 3/4/14				
Margret Villalobos									
106327					8/21/2013		204		\$0.00
Medium	Work In Progress			8/21/2013 9:56:59 AM					
Holguin, Alfredo	Attn: Alfredo Holguin. Roof goose neck vents in old main bldg areas total of 18 count from 12", 24" and 36". These vents are causing roof leaks and ceiling tile damage which produces mold on tiles. Several of the dampers are not functional, screens are detached or torn. One of the problems weve had is cats going into the building and also accessible to intruders breaking in. I viewed the additions to the building and they have a newer and better vent design with a cap on top for better rain water protection and intruder protection. Let me know if you need more information.								
Jaime Mijarez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa HS</b>									
113531					2/19/2014		22		\$0.00
Medium	Work In Progress			2/19/2014 9:18:29 AM					
Flores, Pete	hey Pete I'm trying to touch base as to getting a new windshield on my work truck. its been severely cracked since I received it and needs to be replaced. Thank you.								
David Escobar									
114549					3/12/2014		1		\$0.00
Medium	Work In Progress			3/12/2014 8:36:05 AM					
Ontiveros, Guadalupe	Gilbert Bailon/Baseball field. Need new bases. The ones we have are old and worn out. Last game one of our players twisted his ankles.								
Jaime Mijarez									
113638		Custodial			2/21/2014		20		\$0.00
Medium	Work In Progress			2/21/2014 7:25:06 AM					
Carbajal, Jimmy	need 3 new dollys for custodians use								
Isaac Holguin									
114529					3/11/2014		2		\$0.00
High	Work In Progress			3/11/2014 4:04:06 PM					
Lara, Ralph	Need two (2) locks keyed to the Master Key on the light control boxes at the baseball and softball fields at Santa Teresa High School. Please drop off keys at the Construction office by Thursday March 13th afternoon. Should you have any questions please contact Mr. Ralph Gallegos at 575- 882-6921. Thank You								
Dominique Esparza									
112962		Athletic Field			2/4/2014		37		\$0.00
Medium	Work In Progress			2/4/2014 3:22:07 PM					
Ontiveros, Guadalupe	as per conversation, please laydown compost on the southeast corner of baseball field by marquee. thank you								
Michael Munoz									
114547					3/12/2014		1		\$0.00
Medium	Work In Progress			3/12/2014 8:22:05 AM					
Lara, Ralph	Varsity gym concession stand. L. Villalobos. Locking mechanisms on concession gates are failing and not locking at all.								
Jaime Mijarez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Santa Teresa HS</b>							
114545					3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 8:16:58 AM				
Llanez, Rick		L. Gallegos. Soccer penalty spot on north end of football field is loose and detaches from surface. - Several other seams are loose and turf can be lifted. - Field needs grooming and more rubber pellets.							
Jaime Mijarez									
114548					3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 8:29:36 AM				
Llanez, Rick		L. Gallegos. Please line the soccer field grass for off season use.							
Jaime Mijarez									
114550					3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 8:39:59 AM				
Llanez, Rick		Gilbert Bailon/Baseball field. Need to have the soccer bleachers moved to the baseball field and placed by the first base side.							
Jaime Mijarez									
111492					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:24 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
113990					3/2/2014	3/5/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:25:53 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.							
Margret Villalobos									
110010					11/7/2013		126		\$0.00
Medium	Work In Progress				11/7/2013 8:07:10 AM				
Ontiveros, Joe		Gas line outside by 300 wing boiler room is cracked. Needs to be repaired before we get colder weather. Gas line supplies to the 300 wing hydraunic heating system boiler.							
Jaime Mijarez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
111738					1/7/2014		65		\$0.00
Medium	Work In Progress				1/7/2014 2:48:17 PM				
Ontiveros, Joe		cafeteria kitchen could not locate a shut off water valve for 3/8 water line to make up air system for kitchen hood. Will need to install a shut off valve. water line burst during holiday break and couldn't shut off water due to no shut off valve present.							
David Escobar									
109208					10/22/2013		142		\$0.00
Medium	Work In Progress				10/22/2013 3:45:56 PM				
Castillo, Carlos		Main entrance hallway. All the ivory light switches need to be replaced they are broken and are not working properly. Please check with me (Jaime).							
Jaime Mijarez									
111353		Parking Lot			12/17/2013		86		\$0.00
Medium	Work In Progress				12/17/2013 10:38:20				
Castillo, Carlos		Some of the parking light lites are not working. Needs attention because it is very dark at night in some spots.							
William Dickson									
114464		Athletic Field			3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 3:40:18 PM				
Castillo, Carlos		Need to attend new softball field lights training at Sta. Teresa hi.							
Carlos Castillo									
112118		Athletic Field			1/15/2014		57		\$0.00
Medium	Work In Progress				1/15/2014 7:34:04 AM				
Castillo, Carlos		Lay conduit in Lynco's open trench at baseball field for future use.							
Carlos Castillo									
106495					8/26/2013		199		\$0.00
Medium	Work In Progress				8/26/2013 9:08:31 AM				
Ambriz, Jose		Room 203. Slave fan coil unit has a noisysquerrel cage. I had to shutdown unit through tracer summit so it won't disrupt the classroom.							
Jaime Mijarez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
111205					12/12/2013		91		\$0.00
Medium	Work In Progress				12/12/2013 10:35:37				
Ambriz, Jose		Do you know what is going on with the heating at STHS in the area listed on the subject line? We need to check these systems to see if they are functioning correctly. It seems that at the time I looked at the system, when it was 25 degrees outside. The main gym is the only one at the correct temperature. Please check on them. Thanks				Called Trane			
Rafael Gallegos									
109373					10/28/2013		136		\$0.00
Medium	Work In Progress				10/28/2013 7:58:20 AM				
Castillo, Carlos		Cafeteria area indoor lights went off except kitchen area. Breaker panel H-5 breaker 14 was tripped by sub panel H-5 breaker 18, and breaker 8 both breakers are for chorus room storages. I left the 2 breakers off to reset breaker 14 and turned on all of the cafeteria lights.							
Jaime Mijarez									
113687					2/24/2014		17		\$0.00
Medium	Work In Progress				2/24/2014 9:14:18 AM				
Castillo, Carlos		We need the utilities (electrical) located at Santa Teresa High School for the electrical trenching for the ball fields. On 2/26/14, We will be trenching around the outside of the ball fields between the poles.							
Rafael Gallegos									
111713					1/7/2014		65		\$0.00
Medium	Work In Progress	LINE LOCATE			1/7/2014 8:25:58 AM				
Sotelo, Enrique		Lynco will be drilling at Santa Teresa on Tuesday, 01/14/2014 and will need utilities located. They have the piers marked on the ground and will need your district to locate any utilities underground at these locations.							
Rafael Gallegos									
<b>Count: 97 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>91</b>	<b>Total for Santa Teresa HS</b>		<b>0</b>	<b>\$0.00</b>	

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa MS</b>									
114005					3/2/2014		11		\$0.00
Medium	Work In Progress			3/2/2014 12:26:02 AM					
Prospero, Manuel	Yearly - Santa Teresa MS A10 (Heat Pump)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
111431		Electrical Room			12/19/2013		84		\$0.00
Medium	Work In Progress			12/19/2013 9:23:50 AM					
Castillo, Carlos	Annual electrical equipment inspection.								
Carlos Castillo									
111493					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress			1/5/2014 12:23:25 AM					
Villalobos, David	Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
112591					1/29/2014		43		\$0.00
High	Work In Progress			1/29/2014 11:18:07 AM					
Ontiveros, Guadalupe	We need the dirt under ramps in portables 1 and 2 removed before the winds start kicking up, the accumulation of dirt has reached the top of ramps and is going into portables.								
110331					11/16/2013		117		\$0.00
Medium	Work In Progress			11/16/2013 12:18:09					
Flores, Pete	Yearly - Santa Teresa MS - Mower 0416 - Grounds - Refer to PM schedule details.								
Margret Villalobos									
112819					2/2/2014	2/10/2014	39		\$0.00
Medium	Work In Progress			2/2/2014 12:26:29 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
112820					2/2/2014	2/10/2014	39		\$0.00
Medium	Work In Progress			2/2/2014 12:26:29 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa MS</b>									
112812					2/2/2014	3/5/2014	39		\$0.00
Medium	Work In Progress				2/2/2014 12:26:26 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
112811					2/2/2014		39		\$0.00
Medium	Work In Progress				2/2/2014 12:26:25 AM				
Prospero, Manuel		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
113270		Classroom			2/11/2014		30		\$0.00
Medium	Work In Progress				2/11/2014 2:39:38 PM				
Prospero, Manuel		WE NEED CHANGED AIR FILTERS ALL BUILDINGS AND PORTABLES.							
Manuel Prospero									
114087					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:42 AM				
Prospero, Manuel		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
114088					3/2/2014	4/2/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:42 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
114085					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:41 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114086					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:41 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa MS</b>									
113767					2/25/2014		16		\$0.00
Medium	Work In Progress			2/25/2014 1:35:22 PM					
Carrasco, Danny	2/25/14. I NEED SOME 5 GALLONS OF GASOLINE FOR POLARIS								
Manuel Prospero									
111739					1/7/2014		65		\$0.00
High	Work In Progress			1/7/2014 2:54:01 PM					
Munoz, Michael	please replace all fire hydrants at site they are old and do not work as per fire inspector from sunland								
Alfredo Holguin									
112136					1/15/2014		57		\$0.00
Medium	Work In Progress			1/15/2014 2:33:10 PM					
Munoz, Michael	Replacement of (5) Fire Hydrants.								
Michael Munoz									
112847					2/2/2014	2/8/2014	39		\$0.00
Medium	Work In Progress			2/2/2014 12:26:42 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
114115					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress			3/2/2014 12:26:55 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
107746	North Building	Office			9/20/2013		174		\$0.00
Medium	Work In Progress	ROOM 8		9/20/2013 1:50:16 PM					
Marquez, Gerardo	NEED KEY FOR CABINET LOCATED OUTSIDE NURSES OFFICE								
Laura Parra									
114427	North Building				3/10/2014		3		\$0.00
Medium	Work In Progress			3/10/2014 8:25:29 AM					
Ontiveros, Joe	As per Mr.Soria he needs the plumer to run water near his morgon.								
Ismael Rodriguez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa MS

112443 North Building Classroom 1/24/2014 48 \$0.00

Medium Work In Progress 1/24/2014 12:40:37 PM

Ontiveros, Joe WE NEED TO CHANGED 6 WATER FOUSET ON ROOM 10 AND TRAMPS.

Manuel Prospero

112960 North Building Classroom 2/4/2014 37 \$0.00

Medium Work In Progress 2/4/2014 1:56:28 PM

Ontiveros, Joe WE NEED TO REPLACE WATER FOUSET AND TRUMP ROOM 7.

Manuel Prospero

111910 North Building Classroom 1/10/2014 62 \$0.00

Medium Work In Progress 20 1/10/2014 2:27:34 PM

Ontiveros, Joe LEAKY FAUCET

Laura Parra

108607 North Building Classroom 10/9/2013 155 \$0.00

Medium Work In Progress 8 10/9/2013 9:43:38 AM

Castillo, Carlos NEED EXTRA OUTLETS

Laura Parra

114426 North Building Custodial 3/10/2014 3 \$0.00

Medium Work In Progress 3/10/2014 8:11:37 AM

Castillo, Carlos Set the custdian morgan building with electricity for the Gator thanks.

Ismael Rodriguez

112528 North Building Office 1/28/2014 44 \$0.00

Medium Work In Progress SEE MS 1/28/2014 2:28:39 PM

Prospero, Manuel PLEASE HANG ATHLETE FRAMES IN LOBBY AREA

Laura Parra

112282 North Building Portables 1/21/2014 51 \$0.00

Medium Work In Progress 1/21/2014 11:15:26 AM

Prospero, Manuel Portable 2a the heater is not working properly need to be check.

Ismael Rodriguez

113825 North Building Custodial 2/26/2014 15 \$0.00

Medium Work In Progress 2/26/2014 11:01:28 AM

Ontiveros, Guadalupe Lupe we need some crusher fine dirt to level the ground for the morgan building see Mr.Rodriguez thank you..

Ismael Rodriguez

3/13/2014 10:49:54 AM

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa MS</b>									
113250	North Building	Football Field			2/11/2014		30		\$0.00
Medium	Work In Progress				2/11/2014 8:19:14 AM				
Soria, Mike		Clean along the fence coming down the hill south building custodians are going to help.							
Ismael Rodriguez									
114563	North Building	Office			3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 1:22:05 PM				
Lara, Ralph		Rafa Ms.Montez needs a key to come in and out during testing 2nd floor ramp area.							
Ismael Rodriguez									
113755	North Building	Custodial			2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 11:33:34 AM				
Lara, Ralph		Pete i need two extra gator keys send them with Rafa thank you..							
Ismael Rodriguez									
113181	North Building	Custodial			2/10/2014		31		\$0.00
Medium	Work In Progress				2/10/2014 9:05:46 AM				
Lara, Ralph		Rafa two extra gater keys..							
Ismael Rodriguez									
114497	North Building	Classroom			3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 11:30:19 AM				
Lara, Ralph		Rafa, classroom #9 the teacher needs a key for a file cabnit for testing materials .							
Ismael Rodriguez									
114485	North Building	Office			3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 8:06:05 AM				
Carrasco, Danny		Fuel for administration Gators.							
Ismael Rodriguez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa MS

112016	North Building	Office			1/13/2014		59		\$0.00
--------	----------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	SEE MS			1/13/2014 2:37:03 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Munoz, Michael

BUILD AN ENCLOSURE ON AN EXISTING WALL  
 AREA:  
 1- SPACE IS 15 1/2X 16  
 2- ADD 2 ROWS OF CINDER BLOCK TO AN EXISTING 3 SIDE AREA  
 3- PURCHASE 4 POSTS  
 4- PURCHASE GALVANIZED STEEL FOR ROOF  
 5- ADD A CHAIN LINK FENCE FOR GATE  
 PURPOSE:  
 HOUSE FOR 1 OR 2 POLARIS/ CUSTODIANS TRACTOR. MS LOVELACE WILL PROVIDE THE HEAVY DUTY LOCK

Laura Parra

112017	South Building	Office			1/13/2014		59		\$0.00
--------	----------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	SEE MS			1/13/2014 2:40:11 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Munoz, Michael

ADD A SECURE CHAIN LINK GATE TO AN EXISTING COVERED AREA TO PARK A POLARIS.  
 1- ADD A 9FT WIDE GATE  
 MS. LOVELACE WILL PROVIDE THE HEAVY DUTY LOCK

Laura Parra

113654	South Building	Restroom			2/21/2014		20		\$0.00
--------	----------------	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/21/2014 2:38:41 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel

RESTROOMS ON SOUTH BUILDING NEED CHENGE BELT 4L 200.

Manuel Prospero

114482	South Building	Office			3/11/2014		2		\$0.00
--------	----------------	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/11/2014 7:04:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph

Rafa, the 7th grade counsler Ms. Murillo need for to change the core for testing materials thanks.

Ismael Rodriguez

114555	South Building	Classroom			3/12/2014		1		\$0.00
--------	----------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/12/2014 10:15:08 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph

Rafa, also Ms. Gold needs a key for her filing cabnit to secure her testing material.

Ismael Rodriguez

106730	South Building	Classroom			8/29/2013		196		\$0.00
--------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	ROOM 46			8/29/2013 11:11:17 AM				
--------	------------------	---------	--	--	-----------------------	--	--	--	--

Prospero, Manuel

WHITE BOARD IS COMING OFF WALL

Laura Parra

3/13/2014 10:49:54 AM

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa MS</b>									
112526	South Building	Classroom			1/28/2014		44		\$0.00
Medium	Work In Progress	35-BREITLING			1/28/2014 2:27:20 PM				
Castillo, Carlos		1-NEE4D ELECTRICAL OUTLET FOR SMARTBOARD AND PROJECTOR							
Laura Parra									
114564	South Building	Classroom			3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 1:26:30 PM				
Ambriz, Jose		ClassRoom #31 south building lower level the heating and ventation is not working properly needs to be check thanks.							
Ismael Rodriguez									
109966	Gym (1997)	Gym			11/6/2013		127		\$0.00
Medium	Work In Progress				11/6/2013 11:11:20 AM				
Prospero, Manuel		As per administration basketball courts lanes outside the gym need to be painted there are faded and are use for basketball practice.							
Ismael Rodriguez									
114209	Gym (1997)	Gym			3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 10:16:39 AM				
Ambriz, Jose		WE NEED TO CHANGED BURN BLOWER MOTOR ON LABY HEATER.							
Manuel Prospero									
<b>Count: 45 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>43</b>		<b>Total for Santa Teresa MS</b>	<b>0</b>		<b>\$0.00</b>

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Sunland Park ES

114309 3/6/2014 7 \$0.00

Medium Work In Progress KARLA 3/6/2014 7:33:17 AM

Gonzales, Camilo DELIVER PO 131405265 SCHOOL SPECIALTIES CO.  
1 BOX  
KARLA HERRERA, SPED TEACHER

Margaret Villalobos

114374 3/7/2014 6 \$0.00

Medium Work In Progress CLASSROOM 3/7/2014 9:12:52 AM

Hernandez, Carlos CARLOS - Will order glue traps asp BM, there is a lot  
CAN YOU PLEASE CHECK MS. TERRAZAS of food in this room.  
CLASSROOM. SHE SAID SHE HAS FOUND MICE  
DROPPINGS. PLEASE LOOK INTO IT. THANK YOU.

David Avila

114331 3/6/2014 7 \$0.00

Medium Work In Progress 3/6/2014 2:11:10 PM

Carrasco, Danny need 10 bags weed and feed and 10 door stoppers

Carlos Hernandez

114408 3/9/2014 3/25/2014 4 \$0.00

Medium Work In Progress 3/9/2014 12:18:57 AM

Hernandez, Carlos Monthly - Sunland Park ES Playground Insp - Refer to  
PM schedule details.

Margret Villalobos

113223 2/10/2014 31 \$0.00

Medium Work In Progress 2/10/2014 3:10:42 PM

Holguin, Alfredo as per alfredo need playground sand removed and  
replaced with engineered wood fiber (its at total of 9  
playground equipment and 50 border need replacement

Carlos Hernandez

113784 2/25/2014 16 \$0.00

Medium Work In Progress 2/25/2014 2:58:36 PM

Flores, Pete need new light bulb for trailer

Carlos Hernandez

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
112263					1/21/2014		51		\$0.00
Medium	Work In Progress				1/21/2014 7:46:41 AM				
Hernandez, Carlos		chilo, by the mobile home there are some fence post with concrete. please remove the part of the pole a s close as possible to the concrete and let me know when done. if you fell breaking the concrete is easier, then go that route. thank you							
Michael Munoz									
114332					3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 2:13:17 PM				
Hernandez, Carlos		need filters 16x25x2 40							
Carlos Hernandez									
114261					3/5/2014		8		\$0.00
Medium	Work In Progress				3/5/2014 8:33:16 AM				
Hernandez, Carlos		requesting these materials gal concrete bonder and kick downs for doors							
Carlos Hernandez									
114207					3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 9:43:18 AM				
Hernandez, Carlos		need these tools dolly hand tree trimer caulking gun portable battery charger 10-1 screw driver schiffler torque screw driver tool pouch acilen torch and tank gfi outlet tester							
Carlos Hernandez									
113493					2/18/2014		23		\$0.00
Medium	Work In Progress				2/18/2014 3:08:43 PM				
Ontiveros, Guadalupe		soccer feild needs to be arreated and fertilized							
Carlos Hernandez									
112127					1/15/2014		57		\$0.00
Medium	Work In Progress				1/15/2014 12:15:43 PM				
Flores, Pete		need new belt for lawn mower 130							
Carlos Hernandez									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Sunland Park ES</b>							
112128					1/15/2014		57		\$0.00
Medium	Work In Progress				1/15/2014 12:17:08 PM				
Flores, Pete		lawn mower ztrack 997 needs new blades							
Carlos Hernandez									
113914					2/28/2014	3/31/2014	13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:45 AM				
Hernandez, Carlos		Yearly - Sunland Park ES C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
113913					2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 12:32:44 AM				
Hernandez, Carlos		Monthly - Sunland Park ES A-16 Fan Exh Semiannual - Refer to PM schedule details.							
Margret Villalobos									
113782					2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 2:56:35 PM				
Ambriz, Jose		need new water fountain north side							
Carlos Hernandez									
111491					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:23 AM				
Villalobos, David		Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
114557					3/12/2014		1		\$0.00
Medium	Work In Progress	CLASSROOM#			3/12/2014 11:17:05 AM				
Ontiveros, Joe		AS PER MS. ARMENDARIZ -							
		CARLOS CAN YOU PLEASE CHECK MS. ARMENDARIZ SINK, IT IS CLOGGED. THANK YOU.							
David Avila									
107040					9/4/2013		190		\$0.00
Medium	Work In Progress	TEACHER'S			9/4/2013 7:57:55 AM				
Ontiveros, Joe		AS PER MS. DUQUE-----							
		NEED TO HAVE SINK INSTALLED IN THE TEACHER'S LOUNGE. PLEASE SEE MS. DUQUE ABOUT THIS IF THERE ARE ANY QUESTIONS. THANK YOU.							
David Avila									



# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
113559					2/19/2014		22		\$0.00
Medium	Work In Progress				2/19/2014 3:30:32 PM				
Ontiveros, Joe		need new toilet in boys bathroom old one cracked leaking water							
Carlos Hernandez									
114568					3/12/2014		1		\$0.00
Medium	Work In Progress				3/12/2014 3:18:41 PM				
Castillo, Carlos		need lights in storage							
Carlos Hernandez									
114443					3/10/2014		3		\$0.00
Medium	Work In Progress				3/10/2014 12:53:51 PM				
Castillo, Carlos		there are 9 primeriter lights that need replaced							
Carlos Hernandez									
110843					12/4/2013		99		\$0.00
Medium	Work In Progress				12/4/2013 1:24:14 PM				
Ambriz, Jose		need new heating and cooling system for portable f							
Carlos Hernandez									
109022					10/17/2013		147		\$0.00
Medium	Work In Progress				10/17/2013 3:23:57 PM				
Castillo, Carlos		need new light fixture in nurses bathroom							
Carlos Hernandez									
113364					2/13/2014		28		\$0.00
Medium	Work In Progress				2/13/2014 8:59:02 AM				
Castillo, Carlos		need power run to a/c unit portable f							
Carlos Hernandez									
<b>Count: 25 Work Orders</b>		<b>Avg. Age of WO's 35</b>		<b>Total for Sunland Park ES</b>		<b>0</b>	<b>0</b>	<b>\$0.00</b>	

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
113963					2/28/2014		13		\$0.00
Medium	Work In Progress			2/28/2014 3:09:35 PM					
Vallejo, Albert		need instaled 120 volts cable for a/c water pomp							
Juan Vargas									
114340					3/6/2014		7		\$0.00
Medium	Work In Progress			3/6/2014 3:27:28 PM					
Appelzoller, Fred		room 303 need fix sink has leak in la canasta							
Juan Vargas									
111489					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress			1/5/2014 12:23:22 AM					
Villalobos, David		Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
114003					3/2/2014		11		\$0.00
Medium	Work In Progress			3/2/2014 12:26:01 AM					
Vargas, Juan		Yearly - Sunrise ES A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
114008					3/2/2014		11		\$0.00
Medium	Work In Progress			3/2/2014 12:26:03 AM					
Vargas, Juan		Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM schedule details.							
Margret Villalobos									
114012					3/2/2014		11		\$0.00
Medium	Work In Progress			3/2/2014 12:26:05 AM					
Vargas, Juan		Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.							
Margret Villalobos									
106424					8/22/2013		203		\$0.00
Medium	Work In Progress			8/22/2013 3:36:46 PM					
Marquez, Gerardo		marqui need replace locks							
Juan Vargas									
113087					2/6/2014		35		\$0.00
Medium	Work In Progress			2/6/2014 3:07:02 PM					
Flores, Pete		need fix gas tank have leck							
Juan Vargas									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunrise ES</b>									
114338					3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 3:24:38 PM				
Ontiveros, Guadalupe		need grass sed for athletic field							
Juan Vargas									
109922					11/5/2013		128		\$0.00
Medium	Work In Progress				11/5/2013 3:18:06 PM				
Ontiveros, Guadalupe		need 12 tons lavo stone in front parking pond							
Juan Vargas									
112022					1/13/2014		59		\$0.00
Medium	Work In Progress				1/13/2014 3:25:37 PM				
Ontiveros, Guadalupe		need fix 2 in. sprinkler valve							
Juan Vargas									
111927					1/10/2014		62		\$0.00
Medium	Work In Progress				1/10/2014 3:12:34 PM				
Ontiveros, Guadalupe		need replace 6 tress							
Juan Vargas									
107279					9/10/2013		184		\$0.00
Medium	Work In Progress				9/10/2013 8:17:26 AM				
Flores, Pete		430 mower need replace blade							
Juan Vargas									
113791					2/25/2014		16		\$0.00
Medium	Work In Progress				2/25/2014 3:36:08 PM				
Holguin, Alfredo		I have two playground areas Northside 100x90 Southside 120x100 need repair of plastic borders.							
Juan Vargas									
114418					3/9/2014	3/25/2014	4		\$0.00
Medium	Work In Progress				3/9/2014 12:19:02 AM				
Vargas, Juan		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
114108					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:51 AM				
Apodaca, Mario		Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunrise ES</b>									
114492					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 10:19:09 AM				
Vargas, Juan		need repair outside cement block wall							
Juan Vargas									
114493					3/11/2014		2		\$0.00
Medium	Work In Progress				3/11/2014 10:32:26 AM				
Vargas, Juan		need a/c filters for summer season							
Juan Vargas									
114073					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:35 AM				
Vargas, Juan		Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
114078					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:38 AM				
Vargas, Juan		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111144					12/11/2013		92		\$0.00
Medium	Work In Progress				12/11/2013 8:59:01 AM				
Vargas, Juan		need relace exauhst fan in 300 hall electical closed							
Juan Vargas									
113879					2/27/2014		14		\$0.00
Medium	Work In Progress				2/27/2014 3:14:25 PM				
Vargas, Juan		need replace all door sweepers							
Juan Vargas									
112272	Main Building	Office			1/21/2014		51		\$0.00
Medium	Work In Progress	FRONT OFFICE			1/21/2014 9:02:01 AM				
Marquez, Gerardo		JOANNE MUNOZ, FRONT OFFICE, NEED TWO KEYS TS101 FOR MRS. DORAN AND MR WIGGS							
Joanne Munoz									
<b>Count: 23 Work Orders</b>		<b>Avg. Age of WO's 44</b>		<b>Total for Sunrise ES</b>		<b>0</b>	<b>0</b>	<b>\$0.00</b>	

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Vado ES</b>									
114311	Main Building	Dressing Room			3/6/2014		7		\$0.00
Medium	Work In Progress				3/6/2014 7:51:49 AM				
Carbajal, Jimmy      Need propane tank fill for buffer !									
Armando Diaz									
113957	Main Building	Custodial			2/28/2014		13		\$0.00
Medium	Work In Progress				2/28/2014 11:25:27 AM				
Carbajal, Jimmy      burn vacuum motor serial # 1176									
Armando Diaz									
114133					3/2/2014	3/8/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:27:04 AM				
Miranda, Danny      Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.									
Margret Villalobos									
105493					8/6/2013		219		\$0.00
Medium	Work In Progress				8/6/2013 12:07:19 PM				
Marquez, Gerardo      need to replace back door to kitchen									
Danny Miranda									
105494					8/6/2013		219		\$0.00
Medium	Work In Progress				8/6/2013 12:10:54 PM				
Marquez, Gerardo      need to replace back door going to bus exit									
Danny Miranda									
114409					3/9/2014	3/25/2014	4		\$0.00
Medium	Work In Progress				3/9/2014 12:18:57 AM				
Miranda, Danny      Monthly - Vado ES Playground Insp - Refer to PM schedule details.									
Margret Villalobos									
114222					3/4/2014		9		\$0.00
Medium	Work In Progress				3/4/2014 3:20:53 PM				
Miranda, Danny      need to paint or repair ceiling tile as needed									
Danny Miranda									
114065					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:32 AM				
Miranda, Danny      Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details.									
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
114041					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:20 AM				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
114040					3/2/2014	3/10/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:19 AM				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PMs schedule details.							
Margret Villalobos									
113302					2/12/2014		29		\$0.00
Medium	Work In Progress				2/12/2014 7:46:07 AM				
Holguin, Alfredo		need to replace sand w/wood fiber in playground							
Danny Miranda									
113483					2/18/2014		23		\$0.00
Medium	Work In Progress				2/18/2014 1:11:34 PM				
Miranda, Danny		need to change filters							
Danny Miranda									
112074					1/14/2014		58		\$0.00
Medium	Work In Progress				1/14/2014 11:41:34 AM				
Marquez, Gerardo		need to change core from 200-w/r to roon 202 storage							
Danny Miranda									
114023					3/2/2014		11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:11 AM				
Miranda, Danny		Yearly - Vado ES A-10 Heat Pump Yearly - Refer to PM schedule details.							
Margret Villalobos									
114024					3/2/2014	4/2/2014	11		\$0.00
Medium	Work In Progress				3/2/2014 12:26:11 AM				
Miranda, Danny		Yearly - Vado ES R-3 Ref. Unit Yearly - Refer to PM schedule details.							
Margret Villalobos									
111497					1/5/2014	2/5/2014	67		\$0.00
Medium	Work In Progress				1/5/2014 12:23:26 AM				
Villalobos, David		Yearly - Vado ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

# 892 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Vado ES

Count: 16 Work Orders	Avg. Age of WO's	45	Total for Vado ES	0	\$0.00
Count: 892 Work Orders	Avg. Age of WO's	53	Grand Total	0	\$0.00