

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Location Not Assigned							
111654					1/6/2014		91		\$0.00
Medium	Work In Progress				1/6/2014 12:24:14 AM				
Flores, Pete		Monthly - District Tractors - Full Service PM - Refer to PM schedule details.							
Margret Villalobos									
Count: 1 Work Orders		Avg. Age of WO's	91			Total for <Blank>	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
113214		Cafeteria			2/10/2014		56		\$0.00
Medium	Work In Progress	575-882-1904			2/10/2014 1:50:52 PM				
Nunez, Arturo		please move white bulletin board and assemble it at the outside wall by the cafeteria... thank you							
Laura Vazquez									
107866		Office			9/24/2013		195		\$0.00
Medium	Work In Progress	575-882-1904			9/24/2013 2:01:38 PM				
Nunez, Arturo		restroom form the office is making a noise (when we flash it).							
Laura Vazquez									
106090					8/15/2013		235		\$0.00
Medium	Work In Progress				8/15/2013 2:51:26 PM				
Nunez, Arturo		trim shrubs in front of office							
Laura Vazquez									
110293					11/15/2013		143		\$0.00
Medium	Work In Progress	TEACHER'S			11/15/2013 9:14:07 AM				
Nunez, Arturo		NEED A DOOR THRESHOLD INSTALLED TO PREVENT DIRT FROM COMING IN UNDER THE DOOR (M. HIDALGO 575-618-7459)							
Margaret Villalobos									
112584		Classroom			1/29/2014		68		\$0.00
Medium	Work In Progress	575-882-1904			1/29/2014 9:25:50 AM				
Nunez, Arturo		please paint all classrooms walls for rooms 101,102,103 and 104 thank you							
Laura Vazquez									
115342		Parking Lot			4/2/2014		5		\$0.00
Medium	Work In Progress				4/2/2014 10:32:37 AM				
Marquez, Gerardo		Please provide to the gate of head-start with a chain and a lock with 2 H1 key thank you.							
Laura Vazquez									
115453		Office			4/4/2014		3		\$0.00
Medium	Work In Progress				4/4/2014 3:19:42 PM				
Gonzales, Camilo		Pick up obsolete Xerox. See Laura Vasquez							
Theresa Ramirez									
Count: 7 Work Orders			Avg. Age of WO's	101		Total for Anthony - On Track Pre-K (Village)	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
105552					8/7/2013		243		\$0.00
Medium	Work In Progress	SPED OFFICE		8/7/2013 7:58:25 AM					
Nunez, Arturo	ASSEMBLE DESK FOR MARGARET (SEE MARGARET OR JULIE)								
Margaret Villalobos									
114617					3/13/2014		25		\$0.00
Medium	Work In Progress			3/13/2014 3:28:23 PM					
Gonzalez, Salvador	please add metal build on top concrete slab next to morgan building. for lawn mower coverage. thank you								
Michael Munoz									
115006					3/25/2014		13		\$0.00
Medium	Work In Progress	SPECIAL ED		3/25/2014 1:05:24 PM					
Briones, Enrique	DELIVER PO131404359 SCHOOL SPECIALITY ED 4 BOXES SAM AVALOS/ISTRUCTIONAL SPECIALIST								
Margaret Villalobos									
114407					3/9/2014	3/25/2014	29		\$0.00
Medium	Work In Progress			3/9/2014 12:18:56 AM					
Nunez, Arturo	Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
113155					2/9/2014	2/25/2014	57		\$0.00
Medium	Work In Progress			2/9/2014 12:20:53 AM					
Nunez, Arturo	Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
115289					4/1/2014		6		\$0.00
Medium	Work In Progress			4/1/2014 9:41:26 AM					
Orozco, Daniel	A BIG BLOCK OF ICE HAS FORMED ON FREEZER FLOOR, SAFETY HAZARD. SNP MANAGER BECKY S. 882.3410.								
Maritza Gonzalez									
115633					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:32:19 AM					
Nunez, Arturo	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
115639					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:32:23 AM					
Orozco, Daniel		Monthly - Anthony ES Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									
115664					4/6/2014		1		\$0.00
Medium	Work In Progress			4/6/2014 12:32:40 AM					
Munoz, Michael		Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to PMschedule details.							
Margret Villalobos									
113939					2/28/2014		38		\$0.00
Medium	Work In Progress			2/28/2014 12:32:58 AM					
Munoz, Michael		Yearly - Anthony ES - Fire Pump Inspection - Refer to PMschedule details.							
Margret Villalobos									
114440	Main Building				3/10/2014		28		\$0.00
Medium	Work In Progress			3/10/2014 12:46:04 PM					
Carbajal, Jimmy		need 2 50ft hoses and 2 sprinklers				routed to Art 3/27/14; ROUTED TO JIMMY AS PER CHUY 4/2/14			
David Vega									
107934					9/25/2013		194		\$0.00
Medium	Work In Progress			9/25/2013 3:15:54 PM					
Marquez, Gerardo		Lock on wall marque in foyer area needs to be replaced.							
Arturo Nunez									
114841					3/20/2014		18		\$0.00
Medium	Work In Progress	Office		3/20/2014 8:18:14 AM					
Nunez, Arturo		Mr. Nunez as per Ms. Perez please touch up the office during our summer break							
Jessica Lopez									
114017					3/2/2014	4/2/2014	36		\$0.00
Medium	Work In Progress			3/2/2014 12:26:08 AM					
Nunez, Arturo		Yearly - Anthony ES R3 (Ref. Unit)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
114016					3/2/2014		36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:07 AM				
Nunez, Arturo		Yearly - Anthony ES A10(Heat Pumps)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
113912					2/28/2014	3/31/2014	38		\$0.00
Medium	Work In Progress				2/28/2014 12:32:43 AM				
Nunez, Arturo		Yearly - Anthony ES C-11 (Evap.Down)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
115191					3/31/2014	5/1/2014	7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:07 AM				
Nunez, Arturo		Yearly - Anthony ES A8(Rooftop Unit)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
115196					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:11 AM				
Nunez, Arturo		Yearly - Anthony ES A6 (Rooftop Unit)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
115495					4/6/2014	4/22/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:37 AM				
Nunez, Arturo		Monthly - Anthony ES A3(Rooftop Unit)(S.Annual) - Refer to PMschedule details.							
Margret Villalobos									
115494					4/6/2014	5/7/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:36 AM				
Nunez, Arturo		Monthly - Anthony ES A16 (Fan Exhst.)(Semi. Ann.) - Refer to PMschedule details.							
Margret Villalobos									
115488					4/6/2014	5/7/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:31 AM				
Nunez, Arturo		Yearly - Anthony ES A13 (AC Wall Mount)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
111475					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:16 AM				
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
110042					11/7/2013		151		\$0.00
Medium	Work In Progress				11/7/2013 3:55:07 PM				
Villalobos, David		Water pressure relief valve needs to be replaced on boiler.							
Arturo Nunez									
109941					11/5/2013		153		\$0.00
Medium	Work In Progress				11/5/2013 3:58:09 PM				
Sotelo, Enrique		Need a emergency light balast for boys restroom.(lay in light fix.)							
Arturo Nunez									
112747					1/31/2014		66		\$0.00
Medium	Work In Progress				1/31/2014 3:57:45 PM				
Sotelo, Enrique		Out side lights around building needs to be replaced, will need 20 bulbs, and bucket truck.							
Arturo Nunez									
114846					3/20/2014		18		\$0.00
Medium	Work In Progress	SPED LOUNGE			3/20/2014 9:39:25 AM				
Sotelo, Enrique		CHECK ELECTRICAL OUTLETS IN STAFF LOUNGE (THREE ARE NOT WORKING)							
Margaret Villalobos									
111246					12/13/2013		115		\$0.00
Medium	Work In Progress				12/13/2013 11:58:48				
Nunez, Arturo		As per Ms. Perez, we need a sign that reads "Right turn only" for our drop off zone							
Jessica Lopez									
115579					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:45 AM				
Nunez, Arturo		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

115587 4/6/2014 4/14/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:31:50 AM

Nunez, Arturo Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

103957 7/2/2013 279 \$0.00

Medium Work In Progress SPED OFFICE 7/2/2013 9:37:24 AM

Nunez, Arturo INSTALL WINDOW BLINDS IN THE FRONT OFFICE WINDOW (PREFERRABLY BIG SLATS BUT LITTLE SLATS WILL DO)

Margaret Villalobos

103966 7/2/2013 279 \$0.00

Medium Work In Progress SPED OFFICE 7/2/2013 3:02:37 PM

Nunez, Arturo MOVE DESK FROM BUDGET CLERK OFFICE INTO OTHER OFFICE SEE MARGARET

Margaret Villalobos

103967 7/2/2013 279 \$0.00

Medium Work In Progress SPED OFFICE 7/2/2013 3:03:37 PM

Nunez, Arturo MOVE DESK AND SHELVES FROM MARGARET'S OFFICE INTO NEW EARLY CHILDHOOD OFFICE (SEE MARGARET)

Margaret Villalobos

107813 9/23/2013 196 \$0.00

Medium Work In Progress office 9/23/2013 1:42:18 PM

Nunez, Arturo Mr. Nunez please hang flags Location : office

Jessica Lopez

107732 9/20/2013 199 \$0.00

Medium Work In Progress SPED 9/20/2013 9:21:01 AM

Nunez, Arturo NEED TO RE-CAULK THE WINDOW PANES IN THE DIRECTORS OFFICE (CAULKING IS FALLING OFF)

Margaret Villalobos

111532 1/5/2014 92 \$0.00

Medium Work In Progress 1/5/2014 12:23:48 AM

Holguin, Alfredo Monthly - Anthony ES - Fire Pump Engine - Refer to PM schedule details.

Margret Villalobos

4/7/2014 2:48:52 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Anthony ES									
115593					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:54 AM				
Holguin, Alfredo	Monthly - Anthony ES - Fire Pump Engine - Refer to PM schedule details.								
Margret Villalobos									
113707					2/24/2014		42		\$0.00
Medium	Work In Progress	SPED OFFICE			2/24/2014 12:44:13 PM				
Nunez, Arturo	INSTALL BOARD IN FRONT OFFICE FOR DATA CLERKS (SEE DINO OR MARY)								
Margaret Villalobos									
114619					3/13/2014		25		\$0.00
Medium	Work In Progress				3/13/2014 3:30:29 PM				
Nunez, Arturo	Mr. Nunez Ms. Mason needs your help April setting up for the art show April 24, 2014. Location: Santa Teresa Middle School **Please see Ms. Mason for additional information								
Jessica Lopez									
111185					12/11/2013		117		\$0.00
Medium	Work In Progress				12/11/2013 3:52:18 PM				
Flores, Pete	Need to have vechile # 70 checked starter is dragging, having trouble getting started.								
Arturo Nunez									
115502					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:42 AM				
Nunez, Arturo	Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 40 Work Orders			Avg. Age of WO's	72		Total for Anthony ES	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Berino ES							
115500					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:41 AM				
Duran, Adan		Monthly - Berino ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
115588					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:51 AM				
Duran, Adan		Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115589					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:51 AM				
Duran, Adan		Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115594					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:54 AM				
Holguin, Alfredo		Monthly - Berino ES - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
115028					3/25/2014		13		\$0.00
Medium	Work In Progress				3/25/2014 3:12:34 PM				
Duran, Adan		MR ADURAN NEED TO REPLACE KICKDOWN DOOR STOPS IN CAFETERIA AND CUSTODIAL ROOM BROKEN							
Adan Duran									
115599					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:57 AM				
Duran, Adan		Monthly - Berino ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
109171					10/22/2013		167		\$0.00
Medium	Work In Progress				10/22/2013 1:13:52 PM				
Sotelo, Enrique		MR ENRIQUE SOTELO SIR NEED TO REPLACE LIGHT BULBS ON POST NEAR MR MORGAN BUILDING AND PUMP HOUSE TO LIGHTS TOO DARK THANK YOU SIR AND GOD BLESS PS WILL NEED LIFT							
Adan Duran									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
113967					2/28/2014		38		\$0.00
Medium	Work In Progress			2/28/2014 3:19:40 PM					
Sotelo, Enrique	MR ENRIQUE SOTELO SIR NEED THREE BOXS OF LIGHT BULBS SP-35 2 FT LONG NEW RESTROOMS THANK YOU SIR AND GOD BLESS								
Adan Duran									
115071					3/26/2014		12		\$0.00
Medium	Work In Progress			3/26/2014 3:11:32 PM					
Sotelo, Enrique	MR ENRIQUE SOTELO SIR THE GFI BEHIND WATER FOUNTAIN IN CAFETERA NOT WORKING NEED TO REPLACE THANK YOU AND GOD BLESS								
Adan Duran									
114278					3/5/2014		33		\$0.00
Medium	Work In Progress			3/5/2014 3:06:08 PM					
Villalobos, David	MR DAVID VILLALOBOS SIR NEED TWO FLUSHMATE CARTRIDGES FOR COMODE C-100500 KITS THANK YOU SIR AND GOD BLESS								
Adan Duran									
111476					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress			1/5/2014 12:23:16 AM					
Villalobos, David	Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
115188					3/31/2014		7		\$0.00
Medium	Work In Progress			3/31/2014 12:54:03 AM					
Duran, Adan	Monthly - Berino ES A16 (Fan Exh.)(S.Annual) - Refer to PMs schedule details.								
Margret Villalobos									
115050	Main Building	Mechanical			3/26/2014		12		\$0.00
Medium	Work In Progress			3/26/2014 7:32:54 AM					
Villalobos, David	The storage tank to the water heater boiler is rotting out and will need to be replaced								
David Villalobos									
113940					2/28/2014		38		\$0.00
Medium	Work In Progress			2/28/2014 12:32:58 AM					
Munoz, Michael	Yearly - Berino ES - Fire Pump Inspection - Refer to PM schedule details.								
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Berino ES									
115658					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:36 AM				
Munoz, Michael		Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
115640					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:23 AM				
Orozco, Daniel		Monthly - Berino ES Range Hood Cleaning - Refer to PMs schedule details.							
Margret Villalobos									
115632					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:19 AM				
Duran, Adan		Monthly - Berino ES Monthly FE Inpsection - Refer to PMs schedule details.							
Margret Villalobos									
115353					4/2/2014		5		\$0.00
Medium	Work In Progress				4/2/2014 1:51:49 PM				
Orozco, Daniel		NO WATER COMING OUT ON DISHWASHER. SNP MANAGER ELSA C. 882.2417							
Maritza Gonzalez									
113310					2/12/2014		54		\$0.00
Medium	Work In Progress				2/12/2014 9:26:34 AM				
Holguin, Alfredo		MR MIKE MUNOZ SIR WILL NEED ENGINEERED WOOD FIBER FOR THREE SET OF SWINGS HAVE SAND ALSO NMSU HEAD START HAS A SMALL CLIMMING EQUIPMENT IN THE EARLY CHILDHOOD PLAYGROUND ALSO HAS SAND THANK YOU SIR AND GOD BLESS							
Adan Duran									
111198					12/12/2013		116		\$0.00
Medium	Work In Progress				12/12/2013 9:16:28 AM				
Marquez, Gerardo		MR JERRY MARQUEZ SIR ROOM 140 IS SPECAIL ED FOR HANDY-CAP NEED TO SECURE THE DOOR FROM THE INSIDE HAVE KIDS THAT ARE RUNNERS DOOR HAS HANDLE AND THEY ARE ABLE TO OPEN VERY EASY NEED A SAFETY COVER ITS A SAFETY CONCERN THANK YOU SIR AND GOD BLESS MRS RAMIREZ WANTS IT ASAP							
Adan Duran									
Count: 20 Work Orders			Avg. Age of WO's 30			Total for Berino ES	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral ES							
111236					12/12/2013		116		\$0.00
Medium	Work In Progress				12/12/2013 4:03:00 PM				
Marquez, Gerardo		warranty 1 of the 8 new doors installed oil leaking from door closer.							
Paul Quinones									
110886					12/5/2013		123		\$0.00
Medium	Work In Progress				12/5/2013 9:29:57 AM				
Gonzalez, Salvador		DOUBLE DOORS IN BACK OF KITCHEN EXIT NEED A DOOR HEADER TO SUPPORT THE DOOR CLOSER.							
Paul Quinones									
115103		Custodial			3/27/2014		11		\$0.00
Medium	Work In Progress				3/27/2014 9:38:31 AM				
Carbajal, Jimmy		need, to, fix, vaccum, electric, cord, by, switch, turns, on, and, off, l, o, 6, c, o, o, o, o, o, 3, 5.							
Daniel Ramirez									
115615					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:08 AM				
Quinones, Paul		Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
113279					2/11/2014		55		\$0.00
Medium	Work In Progress				2/11/2014 3:42:24 PM				
Holguin, Alfredo		playground surfacing upgrade total of 4 playgrounds pre -k playground no borders supporting sand measurements 20'x30' total of 3 5 to 12 playgrounds need to replace approx. 30 biege borders for 2 playgrounds							
Paul Quinones									
114421					3/9/2014	3/25/2014	29		\$0.00
Medium	Work In Progress				3/9/2014 12:19:04 AM				
Quinones, Paul		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

115641 4/6/2014 4/27/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:32:24 AM

Orozco, Daniel Monthly - Chapparal ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

115670 4/6/2014 4/14/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:32:44 AM

Quinones, Paul Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

113761 E. Building Classroom 2/25/2014 41 \$0.00

Medium Work In Progress 414 2/25/2014 12:59:26 PM

Marquez, Gerardo cabinet keys, file cabinet, storage cabinet need new keys. See Ms. Quinn

Jennifer Corral

113926 2/28/2014 38 \$0.00

Medium Work In Progress 2/28/2014 12:32:51 AM

Quinones, Paul Monthly - Chaparral ES A-16 Exh Fan (Semi Annual) - Refer to PM schedule details.

Margret Villalobos

113925 2/28/2014 3/31/2014 38 \$0.00

Medium Work In Progress 2/28/2014 12:32:50 AM

Quinones, Paul Yearly - Chaparral ES C-11 Evap (Annual) - Refer to PM schedule details.

Margret Villalobos

115473 4/6/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:30:18 AM

Quinones, Paul Yearly - Chaparral ES A-13 A/C Wall Mount Yearly - Refer to PM schedule details.

Margret Villalobos

113626 2/20/2014 46 \$0.00

Medium Work In Progress 2/20/2014 3:55:07 PM

Quinones, Paul paint bus turnaround traffic yellow

Paul Quinones

113065 2/6/2014 60 \$0.00

Medium Work In Progress 2/6/2014 9:05:27 AM

Quinones, Paul need to paint rest rms. main building, and e-wing.

Paul Quinones

4/7/2014 2:48:52 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

114271 Classroom 3/5/2014 33 \$0.00

Medium Work In Progress 414 3/5/2014 9:47:57 AM

Marquez, Gerardo cabinet keys, file cabinet, storage cabinet need new keys. See Ms. Quinn

Jennifer Corral

114591 3/13/2014 25 \$0.00

Medium Work In Progress 3/13/2014 8:48:57 AM

Appelzoller, Fred girls rest rm .300wing need to replace a broken water faucet
pop up type faucet.

Paul Quinones

111474 1/5/2014 2/5/2014 92 \$0.00

Medium Work In Progress 1/5/2014 12:23:15 AM

Villalobos, David Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

112922 2/3/2014 63 \$0.00

Medium Work In Progress 2/3/2014 3:35:34 PM

Vallejo, Albert NEED AN ELECTRICAL OUTLET FOR EPSON PROJECTOR SCREEN IN THE BOOK RM.

Paul Quinones

107095 9/4/2013 215 \$0.00

Medium Work In Progress 9/4/2013 4:03:38 PM

Ontiveros, Guadalupe irrigation water line next to the water tank water leak
water
line connecting pump and motor

Paul Quinones

110568 11/22/2013 136 \$0.00

Medium Work In Progress 11/22/2013 3:51:45 PM

Ontiveros, Guadalupe pressure tank will not stop draining water shut off back
flow in
front of che, and at the middle school and gate valves
next to pressure tank

Paul Quinones

115521 4/6/2014 4/14/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:30:59 AM

Quinones, Paul Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.

Margret Villalobos

4/7/2014 2:48:53 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral ES									
115537					4/6/2014		1		\$0.00
Medium	Work In Progress			4/6/2014 12:31:15 AM					
Quinones, Paul	Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
115538					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:31:16 AM					
Quinones, Paul	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
106592					8/27/2013		223		\$0.00
Medium	Work In Progress			8/27/2013 2:53:40 PM					
Quinones, Paul	girls rest rm. in e-wing, metal latches are broken that secure doors. latches need to be replaced								
Paul Quinones									
108667					10/10/2013		179		\$0.00
Medium	Work In Progress			10/10/2013 7:56:32 AM					
Quinones, Paul	need 18" thermocouples for wall heaters universal type								
Paul Quinones									
107334					9/11/2013		208		\$0.00
Medium	Work In Progress			9/11/2013 8:32:43 AM					
Quinones, Paul	requesting heavy duty coat hooks 3" type for class rms. need for student back packs								
Paul Quinones									
107982					9/26/2013		193		\$0.00
Medium	Work In Progress			9/26/2013 9:31:41 AM					
Quinones, Paul	need leather washers for the blower wheel housing shaft for 6500 and 4800 evap. coolers								
Paul Quinones									
109444					10/28/2013		161		\$0.00
Medium	Work In Progress			10/28/2013 3:58:57 PM					
Quinones, Paul	module board for heater in rm. 214								
Paul Quinones									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral ES									
114091					3/2/2014	3/10/2014	36		\$0.00
Medium	Work In Progress			3/2/2014 12:26:43 AM					
Quinones, Paul	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
115149					3/27/2014		11		\$0.00
Medium	Work In Progress			3/27/2014 3:57:08 PM					
Quinones, Paul	need motor belts for evap.coolers for up coming summer								
Paul Quinones									
114945					3/24/2014		14		\$0.00
Medium	Work In Progress			3/24/2014 10:26:53 AM					
Quinones, Paul	start up cafeteria evap.cooler motor has bad windings remove motor requesting new motor								
Paul Quinones									
112474					1/27/2014		70		\$0.00
Medium	Work In Progress			1/27/2014 9:28:12 AM					
Quinones, Paul	need door kick plates for 8 doors in the main building, and cafeteria								
Paul Quinones									
112640					1/30/2014		67		\$0.00
Medium	Work In Progress			1/30/2014 8:53:46 AM					
Quinones, Paul	need exhaust fan motors and and blower wheels for rest rm. for the 200 wing class rm. rest rms.								
Paul Quinones									
Count: 33 Work Orders	Avg. Age of WO's 69			Total for Chaparral ES			0	\$0.00	

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Chaparral High - Pre-K										
114976		Exterior			3/24/2014		14		\$0.00	
Medium	Work In Progress				3/24/2014 3:59:17 PM					
Ortiz, Alfredo		Need to replace gaskett on outside ZURN hose bibb.								
Alfredo Ortiz										
115442					4/4/2014		3		\$0.00	
High	Work In Progress				4/4/2014 11:00:35 AM					
Appelzoller, Fred		Check to see why there is no water in the fire hydrent								
Dominique Esparza										
113131		Exterior			2/7/2014		59		\$0.00	
Medium	Work In Progress				2/7/2014 2:44:26 PM					
Appelzoller, Fred		Need to replace broken bubblers on drinking fountain, on playground.								
Alfredo Ortiz										
Count: 3 Work Orders			Avg. Age of WO's	25	Total for Chaparral High - Pre-K			0	\$0.00	

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
114901		Football Field			3/21/2014		17		\$0.00
Medium	Work In Progress				3/21/2014 12:56:55 PM				
Appelzoller, Fred		Need to install water line and bubbler on drinking water fountain outside next to tennise courts							
Alfredo Ortiz									
115468					4/6/2014	4/9/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:15 AM				
Ortiz, Alfredo		Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111495					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:26 AM				
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
113315		Gym			2/12/2014		54		\$0.00
Medium	Work In Progress				2/12/2014 10:50:23 AM				
Vallejo, Albert		please check controller to scoreboard and scoreboard for proper operation. thank you							
Michael Munoz									
110544		Exterior			11/22/2013		136		\$0.00
Medium	Work In Progress				11/22/2013 10:19:33				
Marquez, Gerardo		Need to install Security doors on baseball and softball storage sheds							
Alfredo Ortiz									
115493					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:35 AM				
Ortiz, Alfredo		Monthly - Chaparral HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
115190					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:06 AM				
Ortiz, Alfredo		Monthly - Chaparral HS A16 (Fan Exhst.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
113911					2/28/2014	3/31/2014	38		\$0.00
Medium	Work In Progress				2/28/2014 12:32:43 AM				
Ortiz, Alfredo		Yearly - Chaparral HS C11 (Evaporative)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
114267					3/5/2014		33		\$0.00
Medium	Work In Progress				3/5/2014 9:33:15 AM				
Ortiz, Alfredo		Need to replace broken Bolt Cutter. Old one won't cut lock just bends. Agreeas gun old one don't work.							
Alfredo Ortiz									
111530					1/5/2014		92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:47 AM				
Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump Engine - Refer to PMschedule details.							
Margret Villalobos									
115591					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:53 AM				
Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump Engine - Refer to PMschedule details.							
Margret Villalobos									
115585					4/6/2014	5/7/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:49 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
115586					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:49 AM				
Ortiz, Alfredo		Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
115580					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:45 AM				
Ortiz, Alfredo		Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral HS									
112607					1/29/2014		68		\$0.00
High	Work In Progress			1/29/2014 3:27:57 PM					
Ortiz, Alfredo	alfredo, please install reflectors to gates on east and west entrances to lobo lanes. to many accidents. thank you								
Michael Munoz									
110329					11/16/2013		142		\$0.00
Medium	Work In Progress			11/16/2013 12:18:08					
Flores, Pete	Yearly - Chaparral HS M-0405 (Z-Track) Grounds - Refer to PM schedule details.								
Margret Villalobos									
112824					2/2/2014		64		\$0.00
Medium	Work In Progress			2/2/2014 12:26:31 AM					
Flores, Pete	Monthly - CHS-UV-0513 PM Service - Refer to PM schedule details.								
Margret Villalobos									
114645					3/14/2014		24		\$0.00
Medium	Work In Progress	Security		3/14/2014 9:30:49 AM					
Flores, Pete	pick up security gulf cart at CHS and deliver to ppd auto shop / cart not work possible needs new (6) batteries and new cable								
Irene Herrera									
115501					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:30:42 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
114326		Athletic Field			3/6/2014		32		\$0.00
Medium	Work In Progress			3/6/2014 12:18:54 PM					
Ontiveros, Guadalupe	Attention to Athletics Grounds request 1 pallet of sod for soccer field goal area.								
Alfredo Ortiz									
114931		Gym			3/21/2014		17		\$0.00
Medium	Work In Progress			3/21/2014 4:16:50 PM					
Munoz, Michael	PM - Annual Bleacher Service performed by A.K. Sales.								
Michael Munoz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
115669					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:43 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
113941					2/28/2014		38		\$0.00
Medium	Work In Progress				2/28/2014 12:32:59 AM				
Munoz, Michael		Yearly - Chaparral HS - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
115638					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:22 AM				
Orozco, Daniel		Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
115665					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:40 AM				
Munoz, Michael		Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
115668					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:42 AM				
Munoz, Michael		Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PM schedule details.							
Margret Villalobos									
115634					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:20 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
114107					3/2/2014		36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:51 AM				
Apodaca, Mario		Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
115606					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:02 AM				
Apodaca, Mario		Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
106602		Lift Station			8/27/2013		223		\$0.00
Medium	Work In Progress				8/27/2013 3:28:14 PM				
Gonzalez, Salvador		need to retro fit pump bracket at storm water lift pump station outside and theater. (welding job)							
Mario Apodaca									
110070		Exterior			11/8/2013		150		\$0.00
Medium	Work In Progress				11/8/2013 3:20:29 PM				
Gonzalez, Salvador		Need to install Fence gate spoppers at main entrances.							
Alfredo Ortiz									
115436		Office			4/4/2014		3		\$0.00
Medium	Work In Progress				4/4/2014 9:46:51 AM				
Gonzales, Camilo		Deliver 2 bx. PO# 131406145 Attn: Mark Rucpich.							
Theresa Ramirez									
114145					3/3/2014		35		\$0.00
Medium	Work In Progress				3/3/2014 8:40:17 AM				
Gonzalez, Salvador		BLDG. MECH. IS REQUESTING INSTALLATION OF METAL SECURITY DRS. ON ALL ATHLETICS STORAGE SHEDS AND TICKET OFFICE. ONE OF THE STORAGE SHEDS IS AN ODD SIZE AND NEEDS TO BE FABRICATED. WOULD YOU PLEASE CHECK IT OUT ASAP. PLEASE. THANKS.							
Gerardo Marquez									
113966	A-Wing	Office			2/28/2014		38		\$0.00
Medium	Work In Progress				2/28/2014 3:18:18 PM				
Ortiz, Alfredo		Need to fix walls corners broken and repaint.							
Alfredo Ortiz									
113792	A-Wing	Roof			2/25/2014		41		\$0.00
Medium	Work In Progress				2/25/2014 3:37:04 PM				
Ortiz, Alfredo		Need to remove sand from roof-top.							
Alfredo Ortiz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
105363	A-Wing	Office			8/5/2013		245		\$0.00
Medium	Work In Progress				8/5/2013 8:11:06 AM				
Marquez, Gerardo Please make 1 copy of keys #238 & #142 for the nurse's filing cabinet. These are the Fire king cabinets. (Ms. deCastro)									
Mireya Meza									
115675	A-Wing	Classroom			4/7/2014		0		\$0.00
Medium	Work In Progress				4/7/2014 9:04:19 AM				
Marquez, Gerardo Please add safety plates on doors that don't already have it. Plate can prevent future break ins. (Lupe Quinones, security)									
Mireya Meza									
110188	A-Wing	Hallway/Corridor			11/13/2013		145		\$0.00
Medium	Work In Progress				11/13/2013 11:12:20				
Marquez, Gerardo The outside door to A wing by ISS class room is not working. When I put my key in it just turns and keeps turning all the way around. Please fix ASAP for security reasons. The rooms close to this door are ISS and CAP. (Lupe Quinones, security)									
Mireya Meza									
115433	B-Wing	Classroom			4/4/2014		3		\$0.00
Medium	Work In Progress	B3			4/4/2014 9:03:39 AM				
Marquez, Gerardo Store room cabinets need to be opened. Tried opening with key and the lock comes out. Need them open as soon as possible. (Ms. Del Hierro)									
Mireya Meza									
113596	B-Wing	Restroom			2/20/2014		46		\$0.00
Medium	Work In Progress				2/20/2014 12:40:26 PM				
Appelzoller, Fred In B-wing staff restroom faucet broke need to replace.									
Alfredo Ortiz									
113024	C-Wing	Classroom			2/5/2014		61		\$0.00
Medium	Work In Progress	C3			2/5/2014 1:56:27 PM				
Sotelo, Enrique The wall plug that connects my computer to my projector is not working. I need to have it checked please. (Ms. Jarnagin, C3)									
Mireya Meza									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral HS									
115346	D-Wing	Classroom			4/2/2014		5		\$0.00
Medium	Work In Progress	D storage room			4/2/2014 11:13:22 AM				
Marquez, Gerardo									
Please change cylinder in D storage room to match key for room D4 for Mr. Ruiz. This will be the Tennis storage room. (Ms. Payen)									
Mireya Meza									
114301	F-Wing	Classroom			3/5/2014		33		\$0.00
Medium	Work In Progress	F3			3/5/2014 4:08:42 PM				
Ortiz, Alfredo									
5 broken chairs from ECHS top half/back of chair came off metal frame, found in storage room. (Ms. Locke, room F3)									
Mireya Meza									
113090	F-Wing	Hallway/Corridor			2/6/2014		60		\$0.00
Medium	Work In Progress				2/6/2014 3:19:13 PM				
Appelzoller, Fred									
No hot water in F-wing water heater will not start.									
Alfredo Ortiz									
115396	F-Wing	Restroom (Girls)			4/3/2014		4		\$0.00
Medium	Work In Progress				4/3/2014 11:17:53 AM				
Appelzoller, Fred									
girls restroom 1st stall toilet still clogged up starting to smell.									
Jesus Urquidi									
115158	F-Wing	Restroom (Girls)			3/28/2014		10		\$0.00
Medium	Work In Progress				3/28/2014 8:35:16 AM				
Appelzoller, Fred									
girls restroom 1st stall toilet clogged up. tried to unplug but could not.									
Jesus Urquidi									
115395	F-Wing	Restroom			4/3/2014		4		\$0.00
Medium	Work In Progress				4/3/2014 11:16:09 AM				
Appelzoller, Fred									
boys restroom 1st urinal clogged up.									
Jesus Urquidi									
114317	G-Wing	Classroom			3/6/2014		32		\$0.00
Medium	Work In Progress	G3			3/6/2014 8:17:41 AM				
Marquez, Gerardo									
The lock to my desk is broken. (Ms. Pranses, G3)									
Mireya Meza									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
109908	I-Wing	Classroom			11/5/2013		153		\$0.00
Medium	Work In Progress				11/5/2013 12:41:09 PM				
Marquez, Gerardo		Need to replace door in Band room broken.							
Alfredo Ortiz									
111037	I-Wing	Kitchen			12/9/2013		119		\$0.00
Medium	Work In Progress				12/9/2013 11:16:02 AM				
Gonzalez, Salvador		Rack on oven broke need to weld together.							
Alfredo Ortiz									
113575	Q-Wing	Classroom			2/19/2014		47		\$0.00
Medium	Work In Progress				2/19/2014 3:56:36 PM				
Ortiz, Alfredo		Need to install a Line Duct Exhaust Fan in Q-4 for Laicer.							
Alfredo Ortiz									
114227	Q-Wing	Roof			3/4/2014		34		\$0.00
Medium	Work In Progress				3/4/2014 3:40:57 PM				
Ortiz, Alfredo		Need to replace filters on Industrial A/C units in Q-build.							
Alfredo Ortiz									
113215	Q-Wing	Roof			2/10/2014		56		\$0.00
Medium	Work In Progress				2/10/2014 1:51:09 PM				
Ortiz, Alfredo		Need to replace motor on A/C unit burn-out. Replace clean machine too. Industrial unit.							
Alfredo Ortiz									
105851	Q-Wing	Classroom			8/12/2013		238		\$0.00
Medium	Work In Progress				8/12/2013 10:14:14 AM				
Marquez, Gerardo		The wrestling/tennis room share a door with Q2. This door is locked on my side but it can be opened from the neighboring room without a key. There is a large amount of valuable equipment in Q2 and I would feel better knowing that all access points were secure. Perhaps it would be possible to have the door lock both directions. (Mr. Woodard)							
Mireya Meza									
109910	R-Wing	Classroom			11/5/2013		153		\$0.00
Medium	Work In Progress				11/5/2013 12:48:59 PM				
Marquez, Gerardo		Need to install pull handle in Culinary classroom.							
Alfredo Ortiz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
114717	R-Wing				3/17/2014		21		\$0.00
Medium	Work In Progress				3/17/2014 3:33:14 PM				
Ortiz, Alfredo		Need to replace light bulbs in R-1, C-1 and hall-way.							
Alfredo Ortiz									
114716	R-Wing	Restroom			3/17/2014		21		\$0.00
Medium	Work In Progress				3/17/2014 3:29:39 PM				
Ortiz, Alfredo		Need to replace broken toilet.							
Alfredo Ortiz									
113314	Field House	Athletic Field			2/12/2014		54		\$0.00
Medium	Work In Progress				2/12/2014 10:45:25 AM				
Marquez, Gerardo		May need to change corse to trainer rooms to minimum access only to K3 keys. (Mireya Meza)							
Mireya Meza									
114594	Field House	Classroom			3/13/2014		25		\$0.00
Medium	Work In Progress	Trainer facilities			3/13/2014 10:38:01 AM				
Marquez, Gerardo		Please change key and cylinder for trainer rooms. No CHS master or any other keys should be allowed to open these facilities. Please make 3 keys. We will give old K3 keys back to destroy when job is done. (Sofia Payen)							
Mireya Meza									
112029	Field House	Restroom			1/13/2014		84		\$0.00
Medium	Work In Progress				1/13/2014 3:42:07 PM				
Marquez, Gerardo		Old CH86 keys are not matching new cylinder in field house boys restroom area. Please check that all CH86 (athletics keys) match cylinder in field house area. (Mireya Meza)							
Mireya Meza									
108497	Field House	Exterior			10/7/2013		182		\$0.00
Medium	Work In Progress				10/7/2013 9:26:28 AM				
Marquez, Gerardo		Need to fix door knob and Locksets can't lock doors. At the ticket booth Field house.							
Alfredo Ortiz									
112230	Field House	Athletic Field			1/17/2014		80		\$0.00
Medium	Work In Progress	Baseball Fields			1/17/2014 9:42:07 AM				
Valdez, Pedro		Install wind screen at baseball field. (Mr. Martinez, baseball varsity asst. coach)							
Mireya Meza									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
112063	Field House	Athletic Field			1/14/2014		83		\$0.00
Medium	Work In Progress	SOCCER FIELD			1/14/2014 10:21:30 AM				
Valdez, Pedro		GROUPS - CHAPARRAL HS BACKSTOP - SOCCER FIELD ON LOBO LANE SIDE.							
Terry Alvarado									
112702	Field House	Athletic Field			1/31/2014		66		\$0.00
Medium	Work In Progress	Softball field			1/31/2014 9:07:26 AM				
Sotelo, Enrique		Can I get an electric outlet out by my batting cage and an outlet by 3rd base dug out. (Donna Heddleston, softball field)							
Mireya Meza									
114192	H-Wing	Roof			3/4/2014		34		\$0.00
Medium	Work In Progress				3/4/2014 7:46:11 AM				
Vallejo, Albert		Need to replace switch and contactors on the Gym air handler.							
Alfredo Ortiz									
111885	H-Wing	Restroom			1/10/2014		87		\$0.00
Medium	Work In Progress				1/10/2014 9:09:39 AM				
Appelzoller, Fred		Need to replace several faucets in boys and girls restroom bent and sinks are loose.							
Alfredo Ortiz									
113891	H-Wing	Gym			2/27/2014		39		\$0.00
Medium	Work In Progress				2/27/2014 3:43:40 PM				
Vallejo, Albert		Need to fix and replace the main. switche in one of the exauhst fans in the Gym.				3/6 Route to Albert asp Lorenzo			
Alfredo Ortiz									
113505	H-Wing	Gym			2/18/2014		48		\$0.00
Medium	Work In Progress				2/18/2014 3:44:27 PM				
Ortiz, Alfredo		Need to service the Air handlers on the gym roof.							
Alfredo Ortiz									
105660	H-Wing	Dressing Room			8/8/2013		242		\$0.00
Medium	Work In Progress				8/8/2013 9:52:01 AM				
Marquez, Gerardo		Please put the metal door back on. The door that is suppose to be between the girls basketball locker room and showers. (Ms. Lydia Guerrero, girls dressing room)							
Mireya Meza									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
108049	H-Wing	Gym			9/27/2013		192		\$0.00
Medium	Work In Progress				9/27/2013 2:57:56 PM				
Marquez, Gerardo		Need to install door louvers on two storage doors because mole is growing on everything. Girls locker rooms in Gym.							
Alfredo Ortiz									
114266	Pre-K	Restroom			3/5/2014		33		\$0.00
Medium	Work In Progress				3/5/2014 9:22:44 AM				
Ortiz, Alfredo		Need to install floor drain sealers to stop drain odors.							
Alfredo Ortiz									
Count: 71 Work Orders				Avg. Age of WO's	58		Total for Chaparral HS	0	\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

113944 2/28/2014 38 \$0.00

Medium Work In Progress 2/28/2014 12:33:00 AM

Munoz, Michael Yearly - Chaparral MS - Fire Pump Inspection - Refer to PM schedule details.

Margret Villalobos

104768 Main Building Office 7/26/2013 255 \$0.00

Medium Work In Progress Merry 7/26/2013 8:31:49 AM

Marquez, Gerardo Needs keys for desk

Gidget Mora

106128 Main Building Computer Lab 8/16/2013 234 \$0.00

Medium Work In Progress 8/16/2013 8:31:15 AM

Solis, Lorenz Install refrigeration units for computer labs. Rooms 406 and 207.

Albert Vallejo

108717 Main Building Hallway/Corridor 10/11/2013 178 \$0.00

Medium Work In Progress 400 hall 10/11/2013 9:16:30 AM

Vallejo, Albert Please paint wall in 400 hallway

Gidget Mora

108954 Main Building Restroom 10/16/2013 173 \$0.00

Medium Work In Progress 10/16/2013 2:09:57 PM

Appelzoller, Fred Please replace 5 multiple sensor sinks. Not working, also install new basins. asp Mike - Assign to Fred, but please add on to description to install new basins.

Gidget Mora

111055 Main Building Computer Lab 12/9/2013 119 \$0.00

Medium Work In Progress 311 12/9/2013 2:38:18 PM

Vallejo, Albert Please turn off heat-too warm

Gidget Mora

113695 2/24/2014 42 \$0.00

Medium Work In Progress 2/24/2014 10:36:05 AM

Gonzalez, Salvador Need retainers for drive gates at bus turn around.

Albert Vallejo

113696 2/24/2014 42 \$0.00

Medium Work In Progress 2/24/2014 10:37:14 AM

Gonzalez, Salvador Need retaining clips at entrance to back hall.

Albert Vallejo

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral MS							
111106					12/10/2013		118		\$0.00
Medium	Work In Progress				12/10/2013 3:17:58 PM				
Marquez, Gerardo		Please replace door closer. It has leaked the oil and cannot be adjusted.							
Albert Vallejo									
109889					11/5/2013		153		\$0.00
Medium	Work In Progress				11/5/2013 8:53:26 AM				
Marquez, Gerardo		Doors by Band room will not close.							
Albert Vallejo									
113694					2/24/2014		42		\$0.00
Medium	Work In Progress				2/24/2014 10:33:49 AM				
Marquez, Gerardo		Door jamb is broken and needs to be welded. There is also a hole punched in the outer shell. Closer is also leaking oil.							
Albert Vallejo		route to Gerardo asp mike							
Albert Vallejo									
114505					3/11/2014		27		\$0.00
Medium	Work In Progress				3/11/2014 3:05:02 PM				
Orozco, Daniel		I need to put in a work order for the pipe under the salad sink. The pipe leaks a lot. Thank you. SNP Manager Sandra D. 824.4376							
Maritza Gonzalez									
109831					11/4/2013		154		\$0.00
Medium	Work In Progress				11/4/2013 9:53:19 AM				
Gonzalez, Maritza		CHEMICAL CART IS RUSTED. SNP MANAGER SANDRA D. 824.4376.							
Maritza Gonzalez									
115631					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:18 AM				
Vallejo, Albert		Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
114246					3/4/2014		34		\$0.00
Medium	Work In Progress				3/4/2014 4:07:26 PM				
Munoz, Michael		need 8 -4x4 concrete pads poured in court yard for new green houses.							
Albert Vallejo									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral MS									
115642					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:32:25 AM					
Orozco, Daniel	Monthly - Chapparal MS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
115659					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:32:37 AM					
Munoz, Michael	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
114953		Gym			3/24/2014		14		\$0.00
Medium	Work In Progress			3/24/2014 1:56:12 PM					
Munoz, Michael	PM - Annual Bleacher Service performed by A.K. Sales.								
Michael Munoz									
115021					3/25/2014		13		\$0.00
Medium	Work In Progress			3/25/2014 2:29:59 PM					
Carrasco, Danny	Please bring fuel for Ditch-Witch								
Albert Vallejo									
115106		Athletic Field			3/27/2014		11		\$0.00
Medium	Work In Progress	Soccer/Softball/		3/27/2014 11:03:47 AM					
Valles, Johnny	Please level and pack the soccer/softball/baseball fields. presently dirt from CHS football field was thrown and spread but not leveled as promised by Lupe. First day of practice is Tuesday April 1, 2014. Please address immediately								
Gidget Mora									
114089					3/2/2014		36		\$0.00
Medium	Work In Progress			3/2/2014 12:26:43 AM					
Flores, Pete	Monthly - CHM-UV-0514 PM Service - Refer to PM schedule details.								
Margret Villalobos									
113788					2/25/2014		41		\$0.00
Medium	Work In Progress	courtyard		2/25/2014 3:26:24 PM					
Vallejo, Albert	Please supply water for courtyard garden								
Gidget Mora									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

113693 2/24/2014 42 \$0.00

Medium Work In Progress 2/24/2014 10:32:03 AM

Vallejo, Albert Need to repair hole in wall in boys athletic hallway.

Albert Vallejo

115597 4/6/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:31:56 AM

Vallejo, Albert Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

114898 3/21/2014 17 \$0.00

Medium Work In Progress 3/21/2014 10:25:03 AM

Vallejo, Albert Replace pump for decorative fountain.

Albert Vallejo

115601 4/6/2014 4/14/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:31:59 AM

Vallejo, Albert Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

115602 4/6/2014 4/14/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:31:59 AM

Vallejo, Albert Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

115600 4/6/2014 5/7/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:31:58 AM

Vallejo, Albert Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

107344 9/11/2013 208 \$0.00

Medium Work In Progress 9/11/2013 9:29:23 AM

Vallejo, Albert Replace damaged doors in 300 hallway restroom.

Albert Vallejo

114018 3/2/2014 36 \$0.00

Medium Work In Progress 3/2/2014 12:26:08 AM

Vallejo, Albert Yearly - Chaparral MS A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.

Margret Villalobos

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
113910					2/28/2014	3/31/2014	38		\$0.00
Medium	Work In Progress				2/28/2014 12:32:42 AM				
Vallejo, Albert		Yearly - Chaparral MS C-11 (Swamp Coolers)Yearly) - Refer to PM schedule details.							
Margret Villalobos									
115496					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:38 AM				
Vallejo, Albert		Yearly - Chaparral MS A13(AC Wall)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
115497					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:38 AM				
Vallejo, Albert		Monthly - Chaparral MS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
115189					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:05 AM				
Vallejo, Albert		Monthly - Chaparral MS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
107339					9/11/2013		208		\$0.00
Medium	Work In Progress				9/11/2013 9:25:04 AM				
Solis, Lorenzo		Install refrigeration unit for comp lab in 406.							
Albert Vallejo									
108618		Restroom			10/9/2013		180		\$0.00
Medium	Work In Progress				10/9/2013 11:17:29 AM				
Vallejo, Albert		senesecita areglar swich del #300 hallway restroom boys GRACIAS							
M. Carmen Perez									
114378					3/7/2014		31		\$0.00
Medium	Work In Progress				3/7/2014 10:58:49 AM				
Valles, Johnny		Repair soffit lighting.							
Albert Vallejo									
114377					3/7/2014		31		\$0.00
Medium	Work In Progress				3/7/2014 10:57:09 AM				
Vallejo, Albert		Please paint locker rooms before new lockers are installed.							
Albert Vallejo									

4/7/2014 2:48:53 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
114444					3/10/2014		28		\$0.00
Medium	Work In Progress				3/10/2014 1:49:30 PM				
Solis, Lorenzo		The following A/C's are in need of replacement: AERO-CHM-004 (room 204); MCD-CHM-021 (room 309); MCD-CHM-025 (room 306); MCD-CHM-030 (room 205); MCD-CHM-048 (room 107); MCD-CHM-052 (room 104).							
Albert Vallejo									
113787					2/25/2014		41		\$0.00
Medium	Work In Progress	courtyard			2/25/2014 3:25:13 PM				
Vallejo, Albert		Please supply electricity for courtyard garden.							
Gidget Mora									
111477					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:16 AM				
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
115467					4/6/2014	4/9/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:14 AM				
Vallejo, Albert		Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111389		Hallway/Corridor			12/18/2013		110		\$0.00
Medium	Work In Progress				12/18/2013 7:52:00 AM				
Appelzoller, Fred		senesecita areglar fuente de agua de tomar agua esta likiando agua del paciyo 100 GRACIAS							
M. Carmen Perez									
Count: 43 Work Orders		Avg. Age of WO's 65		Total for Chaparral MS			0	\$0.00	

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Pride									
112495		Pump House			1/27/2014		70		\$0.00
Medium	Work In Progress				1/27/2014 3:16:13 PM				
Villalobos, David		need your assistance on installing a new water meter and upgrading a water filter hous for the domestic water							
Mario Apodaca									
115478					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:23 AM				
Aguilar, Patricio		Monthly - Desert Pride HS H11 (E.Heater)(S.Annual) - Refer to PMschedule details.							
Margret Villalobos									
115203					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:18 AM				
Aguilar, Patricio		Monthly - Desert Pride HS A16 (Fan Exh.)(S.Annual) - Refer to PMschedule details.							
Margret Villalobos									
111725		Custodial			1/7/2014		90		\$0.00
Medium	Work In Progress				1/7/2014 11:14:05 AM				
Lara, Ralph		Need to replace master key. Having problems opening doors.							
David Acosta									
115104		Portables			3/27/2014		11		\$0.00
Medium	Work In Progress	room 7			3/27/2014 10:51:51 AM				
Lara, Ralph		door handle to restroom door pull off accidentally.							
David Acosta									
114066					3/2/2014	3/10/2014	36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:32 AM				
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
114067					3/2/2014	3/10/2014	36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:32 AM				
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Pride							
115583					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:47 AM				
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115584					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:48 AM				
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115526					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:05 AM				
Ronquillo, Ruben		Monthly - Desert Pride - (Qtrly) Fitness Equipment - Refer to PM schedule details.							
Margret Villalobos									
115393		Classroom			4/3/2014		4		\$0.00
Medium	Work In Progress	17			4/3/2014 10:48:39 AM				
Aguilar, Patricio		PLEASE ASSIST MR. SANCHEZ IN TRANSPORTING HIS ART DISPLAY ON THURSDAY, APRIL 24TH BY 7:30 AM TO STMS FOR THE ART FAIR COMPETITION.							
Yvette Cortez									
113325		Parking Lot			2/12/2014		54		\$0.00
Medium	Work In Progress	front entrance			2/12/2014 2:00:14 PM				
Ontiveros, Guadalupe		need to add crusher fine and smooth out uneven front entrance ground.							
David Acosta									
115518					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:56 AM				
Aguilar, Patricio		Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
115404		Custodial			4/3/2014		4		\$0.00
Medium	Work In Progress				4/3/2014 1:59:09 PM				
Carbajal, Jimmy		need to replace rear wheels axle assemble on the royal vacuum cleaner.							
David Acosta									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Pride							
115635					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:20 AM				
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
114641					3/14/2014		24		\$0.00
Medium	Work In Progress				3/14/2014 12:27:15 AM				
Sanchez, Raul		Monthly - Desert Pride - Water Filters - Refer to PM schedule details.							
Margret Villalobos									
115208					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:22 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details.							
Margret Villalobos									
115610					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:04 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
114124					3/2/2014	3/8/2014	36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:59 AM				
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
108955					10/16/2013		173		\$0.00
Medium	Work In Progress				10/16/2013 2:17:32 PM				
Gonzalez, Salvador		Need poles to divide the drop off and pick up parking area for safety of the children. Parents are double parking and kids are running in between the cars and could get hurt. Thank you, Ruben							
Ruben Ortiz									
Count: 20 Work Orders		Avg. Age of WO's		28	Total for Desert Pride			0	\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail Intermediate									
105036					8/1/2013		249		\$0.00
Medium	Work In Progress				8/1/2013 9:27:19 AM				
Gonzalez, Salvador		Please install diamond metal plate to new portable ramps and decks.							
Johnny Acuna									
114857					3/20/2014		18		\$0.00
Medium	Work In Progress				3/20/2014 1:15:14 PM				
Carbajal, Jimmy		Buenos dias Jimmyla aspiradora num.0214 se le callo la llantita si la puede revisar por favor gracias							
Laura Sandoval									
112970					2/4/2014		62		\$0.00
Medium	Work In Progress				2/4/2014 3:33:48 PM				
Lara, Ralph		main door in the front lobby, both main doors going out to the portables W/Door closures (middle hallway), Portable #409 main door W/Door closure, Portable #410 W/Door closure Need Doors to be Replaced.							
Johnny Acuna									
115099		Custodial			3/27/2014		11		\$0.00
Medium	Work In Progress				3/27/2014 7:53:38 AM				
Carbajal, Jimmy		buenos dias Jimmy por favor de revisar la aspiradora Num. 01177 al prenderla el motor se oye muy raro gracias							
Laura Sandoval									
115100		Custodial			3/27/2014		11		\$0.00
Medium	Work In Progress				3/27/2014 7:56:57 AM				
Carbajal, Jimmy		Jimmyla aspiradora Num. 01162 se le callo la llantita podria revisarla por favor gracias							
Laura Sandoval									
115096					3/26/2014		12		\$0.00
Medium	Work In Progress				3/26/2014 4:28:15 PM				
Orozco, Daniel		ICE MACHINE NOT MAKING ICE. SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
113259					2/11/2014		55		\$0.00
Medium	Work In Progress				2/11/2014 12:48:08 PM				
Orozco, Daniel		DRYER OUT. SNP MANAGER 824.3822							
Maritza Gonzalez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail Intermediate							
113470					2/18/2014		48		\$0.00
Medium	Work In Progress				2/18/2014 10:12:09 AM				
Orozco, Daniel		GOOD MORNING: I'M HAVING PROBLEMS WITH THE ELECTRICAL FOR THE MILK COOLER. PLEASE REPLACE BOX (BROKEN), CHECK ELECTRICAL WIRING AND BREAKER CAUSE BREAKER SOMETIMES DOES NOT RESET. SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
114416					3/9/2014	3/25/2014	29		\$0.00
Medium	Work In Progress				3/9/2014 12:19:01 AM				
Acuna, Johnny		Monthly - Desert Trail Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
113826					2/26/2014		40		\$0.00
Medium	Work In Progress				2/26/2014 11:10:19 AM				
Holguin, Alfredo		Need more sand to kinder playground area, Need more sand to swing sets area, W.o. #113599: Need new soccer nets for Playground soccer goals, W.o. #111044: Need top soil to fill in low areas to playground grass area, Need 12 swing hangers with 12 S-Hooks for playground swings, Need approx. 22 borders for playground sand to the bigger playground area sets, Need to fix ground border area around swing sets.							
Johnny Acuna									
115625					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:14 AM				
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
115643					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:26 AM				
Orozco, Daniel		Monthly - Desert Trail Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
115660					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:37 AM				
Munoz, Michael		Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail Intermediate									
115506					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:46 AM				
Acuna, Johnny		Monthly - Desert Trail Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
113307					2/12/2014		54		\$0.00
Medium	Work In Progress				2/12/2014 8:46:33 AM				
Flores, Pete		Need to replace Bearing connected to Hydraulic steering shaft for the Steiner Tractor.							
Johnny Acuna									
115305					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 2:41:37 PM				
Ontiveros, Guadalupe		Coaches requesting for volleyball field to be marked in the playground grass area.							
Johnny Acuna									
111044					12/9/2013		119		\$0.00
Medium	Work In Progress				12/9/2013 12:40:09 PM				
Ontiveros, Guadalupe		Need to add top soil and level out playground grass area.							
Johnny Acuna									
113961					2/28/2014		38		\$0.00
Medium	Work In Progress	front office			2/28/2014 2:13:45 PM				
Marquez, Gerardo		Our secretary Elizabeth needs key made for display cabinet							
Elizabeth Hernandez									
115344					4/2/2014		5		\$0.00
Medium	Work In Progress	Portalbes #418			4/2/2014 11:08:18 AM				
Marquez, Gerardo		Mrs. Moreno and Mrs. Contreras need connecting door to stay unlocked.							
Elizabeth Hernandez									
115441					4/4/2014		3		\$0.00
Medium	Work In Progress				4/4/2014 10:30:35 AM				
Marquez, Gerardo		Need to replace cylinder locks to Assistant Principal's office doors. (Mrs. Gilpin) Please see Bldg. Mech. for replacement door cylinders.							
Johnny Acuna									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail Intermediate									
111155					12/11/2013		117		\$0.00
Medium	Work In Progress				12/11/2013 11:20:25				
Flores, Pete		please check radiator to work truck #192. Radiator has a small pin hole leak on the side.							
Johnny Acuna									
115563					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:34 AM				
Acuna, Johnny		Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
115562					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:33 AM				
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
115569					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:38 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
112778					2/2/2014	2/10/2014	64		\$0.00
Medium	Work In Progress				2/2/2014 12:26:10 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
110171					11/13/2013		145		\$0.00
Medium	Work In Progress				11/13/2013 7:51:21 AM				
Acuna, Johnny		Need new threshold for SW hall main doors.				11/20 - Reroute to J. Acuna			
Johnny Acuna									
114029					3/2/2014	3/10/2014	36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:14 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
114809					3/19/2014		19		\$0.00
Medium	Work In Progress				3/19/2014 8:43:08 AM				
Acuna, Johnny		Need pleated Air-Filters for Portables A/c Units.							
Johnny Acuna									

4/7/2014 2:48:54 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Desert Trail Intermediate									
114315					3/6/2014		32		\$0.00
Medium	Work In Progress			3/6/2014 8:10:25 AM					
Acuna, Johnny	(Need a 24 gauge sheetmetal transition duct fitting) Base: 22" square all around with a 2" Height overlapping X 20 3/4" square with a 2" Lip all around.								
Johnny Acuna									
114265					3/5/2014		33		\$0.00
Medium	Work In Progress			3/5/2014 9:09:45 AM					
Acuna, Johnny	Need 2 large rolls of vinyl window screen to repair torn or worn out screening to main building. Also, need 4 fix a flat cans for steiner tractor tires.								
Johnny Acuna									
113599					2/20/2014		46		\$0.00
Medium	Work In Progress			2/20/2014 1:10:13 PM					
Ontiveros, Guadalupe	Need 2 sets of soccer goal nets for soccer goals in the playground grass area. Info and measurements have been mailed through District mail. Thank You.....								
Johnny Acuna									
113917					2/28/2014	3/31/2014	38		\$0.00
Medium	Work In Progress			2/28/2014 12:32:46 AM					
Acuna, Johnny	Yearly - Desert Trail ES C-11 (Evap.Cool)(Yearly) - Refer to PMschedule details.								
Margret Villalobos									
115197					3/31/2014		7		\$0.00
Medium	Work In Progress			3/31/2014 12:54:12 AM					
Acuna, Johnny	Monthly - Desert Trail ES A16(Exhst Fan)(S.Annual) - Refer to PMschedule details.								
Margret Villalobos									
115489					4/6/2014	4/22/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:30:33 AM					
Acuna, Johnny	Monthly - Desert Trail ES A1 (Air Dryer)(S.Annual) - Refer to PMschedule details.								
Margret Villalobos									
114027					3/2/2014		36		\$0.00
Medium	Work In Progress			3/2/2014 12:26:13 AM					
Acuna, Johnny	Yearly - Desert Trail ES A10 (Heat Pump)(Yearly) - Refer to PMschedule details.								
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail Intermediate							
113477					2/18/2014		48		\$0.00
Medium	Work In Progress				2/18/2014 11:30:08 AM				
Vallejo, Albert		Need assistance in new installation of a Securitylight outside of wall to portable #413. Need electrical wiring, elect. box, etc.							
Johnny Acuna									
115073					3/26/2014		12		\$0.00
Medium	Work In Progress				3/26/2014 3:17:32 PM				
Appelzoller, Fred		Room #101: Need to replace drain pipe coming from the wall to the p-trap. Leaking/Threads Corroded							
Johnny Acuna									
111478					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:17 AM				
Villalobos, David		Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
Count: 38 Work Orders			Avg. Age of WO's		39	Total for Desert Trail Intermediate		0	\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
111479					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress			1/5/2014 12:23:17 AM					
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
112082					1/14/2014		83		\$0.00
Medium	Work In Progress			1/14/2014 1:45:30 PM					
Ontiveros, Joe	Boys urinals upper level flush valves are not working; they are not shutting off								
Ruben Ortiz									
109214					10/22/2013		167		\$0.00
Medium	Work In Progress			10/22/2013 3:49:08 PM					
Castillo, Carlos	Need a light and switch outlet in the morgon.								
Ruben Ortiz									
115437					4/4/2014		3		\$0.00
Medium	Work In Progress			4/4/2014 10:01:57 AM					
Ontiveros, Joe	the water fountain by the cafeteria on the south side is clogged; needs to be unclogged.								
Ruben Ortiz									
114525					3/11/2014		27		\$0.00
Medium	Work In Progress			3/11/2014 4:01:17 PM					
Castillo, Carlos	Need set up of electricity for the 3rd Annual Desert View Carnival for Friday, May 2, 2014. Thank you, Ruben								
Ruben Ortiz									
104086					7/8/2013		273		\$0.00
Medium	Work In Progress			7/8/2013 1:30:24 PM					
Ambriz, Jose	A/C UNIT IN KITCHEN WENT OUT. SNP MANAGER DELORES R. 589.2425								
Maritza Gonzalez									
103915					7/1/2013		280		\$0.00
Medium	Work In Progress			7/1/2013 1:06:14 PM					
Ambriz, Jose	Water fountain needs to be replaced in the front office on the east side of the school.								
Ruben Ortiz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
113928					2/28/2014	3/31/2014	38		\$0.00
Medium	Work In Progress				2/28/2014 12:32:52 AM				
Ortiz, Ruben		Yearly - Desert View ES C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
113604					2/20/2014		46		\$0.00
Medium	Work In Progress				2/20/2014 2:39:18 PM				
Ontiveros, Guadalupe		The buster pump is not working for irrigation. Need it ASAP. Thank you, Ruben							
Ruben Ortiz									
113004		Classroom			2/5/2014		61		\$0.00
Medium	Work In Progress	Portable A			2/5/2014 8:56:47 AM				
Lara, Ralph		2nd Request: The lock to the door is broken. (Sanchez)							
Guadalupe Gonzalez									
115349		Classroom			4/2/2014		5		\$0.00
Medium	Work In Progress	Rm. 15A			4/2/2014 12:51:47 PM				
Lara, Ralph		2nd Request: The lock to the door came off. Need to install a new lock. (R. Garcia) See Lupe G. in the office to explain to you. Thank you (Gonzalez)							
Guadalupe Gonzalez									
115303					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 2:40:37 PM				
Lara, Ralph		Front entrance door needs to be adjusted for the security of locking for the kids.							
Ruben Ortiz									
115304					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 2:41:31 PM				
Lara, Ralph		The door needs to be adjusted for the security of locking for the kids.							
Ruben Ortiz									
115373					4/2/2014		5		\$0.00
Medium	Work In Progress				4/2/2014 3:52:32 PM				
Lara, Ralph		NEED A SECOND SET OF KEYS TO BE MADE FOR CAFETERIA MANAGER. PLEASE SEE ELIZABETH DUKE FOR KEYS.							
Maritza Gonzalez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
113308					2/12/2014		54		\$0.00
Medium	Work In Progress				2/12/2014 9:04:05 AM				
Ortiz, Ruben		Need to patch up or retile the front entrance of the school; due to safety hazard.							
Ruben Ortiz									
112602					1/29/2014		68		\$0.00
Medium	Work In Progress				1/29/2014 2:55:08 PM				
Ortiz, Ruben		AS PER HEALTH ENVIRONMENT INSPECTION DAMAGED WALLS NEED TO BE ADDRESSED IN DISHWASHING ROOM.							
Maritza Gonzalez									
115525					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:03 AM				
Ortiz, Ruben		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115524					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:02 AM				
Ortiz, Ruben		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115523					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:01 AM				
Ortiz, Ruben		Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
115390		Gym			4/3/2014		4		\$0.00
Medium	Work In Progress	Gym			4/3/2014 10:28:55 AM				
Ortiz, Ruben		Set up on Tuesday April 15, 2014 for the Science Fair. (Gonzalez)							
Guadalupe Gonzalez									
106257		Classroom			8/20/2013		230		\$0.00
Medium	Work In Progress	Rm. #16			8/20/2013 7:44:28 AM				
Ortiz, Ruben		There are ants in the classroom. If can put caulking around the window. (M. Mack)							
Guadalupe Gonzalez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
108895					10/15/2013		174		\$0.00
Medium	Work In Progress	Lower Grade			10/15/2013 12:54:01				
Ortiz, Ruben		Repair the swings; some are broken and/or tangled.							
Guadalupe Gonzalez									
114993		Office			3/25/2014		13		\$0.00
Medium	Work In Progress	Asst. Principal			3/25/2014 10:01:32 AM				
Ortiz, Ruben		Install a cork board in the office. (Campos)							
Guadalupe Gonzalez									
113907		Computer Lab			2/27/2014		39		\$0.00
Medium	Work In Progress	Rm 76			2/27/2014 9:51:49 PM				
Ortiz, Ruben		Install Infocus projector on ceiling.							
Albert Ortiz									
114328					3/6/2014		32		\$0.00
Medium	Work In Progress				3/6/2014 1:32:46 PM				
Ortiz, Ruben		Need to weed and feed the grass in the front circle and on the side of the school							
Ruben Ortiz									
114330					3/6/2014		32		\$0.00
Medium	Work In Progress				3/6/2014 1:58:56 PM				
Ortiz, Ruben		Need to change light bulbs in classrooms.							
Ruben Ortiz									
114528					3/11/2014		27		\$0.00
Medium	Work In Progress				3/11/2014 4:03:46 PM				
Ortiz, Ruben		Items needed for Carnival 100 feet heavy duty extension cord 50 feet heavy duty extension cord 25 feet heavy duty extension cord							
Ruben Ortiz									
114531					3/11/2014		27		\$0.00
Medium	Work In Progress				3/11/2014 4:05:13 PM				
Ortiz, Ruben		Items needed for Carnival 100 feet heavy duty water holes 2 of 50 feet heavy duty water holes 1 heavy duty rake							
Ruben Ortiz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
115336					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 5:34:10 PM				
Ontiveros, Guadalupe		Need to replace 4 pine trees in the front circle of the school entrance.							
Ruben Ortiz									
115337					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 5:35:18 PM				
Ontiveros, Guadalupe		Need to replace 1 pine trees and 4 oak trees on the level playground.							
Ruben Ortiz									
115338					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 5:36:24 PM				
Ontiveros, Guadalupe		Need to replace 2 inch water valve for the sprinkler system.							
Ruben Ortiz									
115522					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:00 AM				
Ortiz, Ruben		Monthly - Desert View ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
115644					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:26 AM				
Orozco, Daniel		Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
115360					4/2/2014		5		\$0.00
Medium	Work In Progress				4/2/2014 3:26:55 PM				
Carrasco, Danny		Need 10 gals of gas for Mower #402 and 5 gals for 2 stroke (Blowers, weedeaters) #607 Thank you Ruben							
Ruben Ortiz									
114375	Main Building	Restroom			3/7/2014		31		\$0.00
Medium	Work In Progress				3/7/2014 9:59:06 AM				
Ortiz, Ruben		We have a sink in the lower grade boys restroom that is clogged if you can unclogg it i have already tried the plunger but the water won't go down and there all that black mildew that accumulates on the pipes comming out. If you can unclog it please.							
Israel Ortega									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
115429					4/3/2014		4		\$0.00
Medium	Work In Progress				4/3/2014 4:27:48 PM				
Orozco, Daniel		LOOSE PIECE INSIDE OF DISHWASHER, PLEASE CHECK OUT. SNP MANAGER ELIZABETH D. 589.2425							
Maritza Gonzalez									
114751		Custodial			3/18/2014		20		\$0.00
Medium	Work In Progress				3/18/2014 8:19:55 AM				
Carbajal, Jimmy		Hi Jimmy I have two vaccums that are broken one of them smells like burned and the other one is very noisy and it vibrates so much that the adjuster on the back comes off.							
Israel Ortega									
114758		Custodial			3/18/2014		20		\$0.00
Medium	Work In Progress				3/18/2014 9:43:37 AM				
Carbajal, Jimmy		Hi Jimmy I have two vaccums that are broken one of them smells like burned and the other one is very noisy and it vibrates so much that the adjuster on the back comes off.							
Israel Ortega									
114804		Custodial			3/19/2014		19		\$0.00
Medium	Work In Progress				3/19/2014 8:20:23 AM				
Carbajal, Jimmy		Hi Jimmy we got a vaccum cleaner that is broken it smells like if the motor was burning. Vaccum Cleaner number is c08c000003300. Thank you							
Israel Ortega									
114805		Custodial			3/19/2014		19		\$0.00
Medium	Work In Progress				3/19/2014 8:22:46 AM				
Carbajal, Jimmy		Hi Jimmy we have another vaccum cleaner that needs repair. It started to get very noisy and it vibrates even the adjuster in the back is getting loose. Thank you							
Israel Ortega									
115383		Custodial			4/3/2014		4		\$0.00
Medium	Work In Progress				4/3/2014 8:28:23 AM				
Carbajal, Jimmy		Hi Jimmy we have a vaccum cleaner that started to smell like burned and the motor started slow down. If you could fix it we would really appreciate it. Thank you.							
Israel Ortega									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
115614					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:07 AM				
Ortiz, Ruben		Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
104962					7/31/2013		250		\$0.00
Medium	Work In Progress				7/31/2013 8:07:41 AM				
Gonzalez, Salvador		Vandalism; need a new library stand the was destroyed in vandalism. Thank you, Ruben							
Ruben Ortiz									
Count: 43 Work Orders			Avg. Age of WO's	51		Total for Desert View ES	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
114757					3/18/2014		20		\$0.00
Medium	Work In Progress				3/18/2014 9:26:41 AM				
Gonzalez, Salvador		ENTRANCE GATE NEED TO BE WELDED.							
Maritza Gonzalez									
115451		Office			4/4/2014		3		\$0.00
Medium	Work In Progress				4/4/2014 3:17:38 PM				
Gonzales, Camilo		Pick up obsolete HP Photosmart at Fed. Programs. See Nohemi Duron							
Theresa Ramirez									
114414					3/9/2014	3/25/2014	29		\$0.00
Medium	Work In Progress				3/9/2014 12:19:00 AM				
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
115657					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:35 AM				
Orozco, Daniel		Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
115624					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:14 AM				
Moncayo, Fernando		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
112358					1/23/2014		74		\$0.00
Medium	Work In Progress				1/23/2014 7:35:42 AM				
Munoz, Michael		new fence 6' and gates for vehicles for techs stationed at site.							
Alfredo Holguin									
113757					2/25/2014		41		\$0.00
Medium	Work In Progress	Technology			2/25/2014 11:42:35 AM				
Estrada, Jesus		carpet has couple of holes, unraveling . please take it out of Calixto and Cora Office							
Cora Ramirez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		GAC							
115661					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:38 AM				
Munoz, Michael		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
115505					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:45 AM				
Moncayo, Fernando		Monthly - GAC Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
112219					1/16/2014		81		\$0.00
Medium	Work In Progress				1/16/2014 4:10:45 PM				
Flores, Pete		Vehicle 172 (Mr. Giovas) needs windshield wipers checked.							
Maritza Gonzalez									
114685					3/17/2014		21		\$0.00
Medium	Work In Progress				3/17/2014 9:34:48 AM				
Flores, Pete		<p>Good morning Maria, I just wanted to let you know that we had our Suburban over here at GAC since Friday, but just took it back to the lot. Just wanted to advise you on the problems that it's having:</p> <ul style="list-style-type: none"> • No Power Steering – it's hard to turn • Signal Lights are not working • Left side brake lights are not working either <p>Please have it checked and serviced thoroughly as time to time we use it for our various needs. Also, if you can please let me know when it's completed and ready for use. Thank you and have a good day. &#9786;</p> <p>Karla M. Quesada</p>							
Karla Quesada									
113530					2/19/2014		47		\$0.00
Medium	Work In Progress				2/19/2014 9:10:37 AM				
Ontiveros, Joe		EXPANSION TANK IS LEAKING IN MECHANICAL ROOM.							
Fernando Moncayo									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC
------------------	------------

112439					1/24/2014		73		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/24/2014 10:47:46 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando		REPLACE MISSING TILES IN MARY CHAVEZ AREA.							
-------------------	--	--	--	--	--	--	--	--	--

Maritza Gonzalez									
------------------	--	--	--	--	--	--	--	--	--

113759					2/25/2014		41		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2014 12:46:33 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando		need to replace broken or leaking irrigation sprinklers							
-------------------	--	---	--	--	--	--	--	--	--

Fernando Moncayo									
------------------	--	--	--	--	--	--	--	--	--

113771					2/25/2014		41		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2014 2:07:12 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando		please repair pot holes in dock area. thank you							
-------------------	--	---	--	--	--	--	--	--	--

Michael Munoz									
---------------	--	--	--	--	--	--	--	--	--

113858					2/27/2014		39		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2014 9:25:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando		FLOURESCENT LIGHT IN RICHARD ACOSTA OFFICE IS OUT.							
-------------------	--	--	--	--	--	--	--	--	--

Maritza Gonzalez									
------------------	--	--	--	--	--	--	--	--	--

113859					2/27/2014		39		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2014 9:26:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando		AS PER LUCY, PLEASE INSTAL WALL POCKET FILES IN MELISSA ALVARADO OFFICE.							
-------------------	--	--	--	--	--	--	--	--	--

Maritza Gonzalez									
------------------	--	--	--	--	--	--	--	--	--

113710					2/24/2014		42		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/24/2014 1:33:06 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando		AS PER MR. CHAVEZ, GROUNDS NEED TO BE CLEANED UP.							
-------------------	--	---	--	--	--	--	--	--	--

Maritza Gonzalez									
------------------	--	--	--	--	--	--	--	--	--

115065					3/26/2014		12		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/26/2014 1:14:51 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando		C-WING KITCHENETTE-SINK CLOGGED.							
-------------------	--	----------------------------------	--	--	--	--	--	--	--

Maritza Gonzalez									
------------------	--	--	--	--	--	--	--	--	--

114760					3/18/2014		20		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/18/2014 9:57:07 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando		TILES ON HALLWAY IN A-WING IN FRONT OF RESTROOMS ARE CRACKED AND MISSING A PIECE.							
-------------------	--	---	--	--	--	--	--	--	--

Maritza Gonzalez									
------------------	--	--	--	--	--	--	--	--	--

4/7/2014 2:48:54 PM									
---------------------	--	--	--	--	--	--	--	--	--

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
114776					3/18/2014		20		\$0.00
Medium	Work In Progress				3/18/2014 3:10:53 PM				
Moncayo, Fernando		pool & patio area irrigation timer shorting out, only one station works							
Fernando Moncayo									
115290					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 9:51:24 AM				
Moncayo, Fernando		PHILLIP MEDINA OFFICE- THERE IS A SWITCH THAT HE WOULD LIKE REMOVED/COVERED.							
Maritza Gonzalez									
115439					4/4/2014		3		\$0.00
Medium	Work In Progress				4/4/2014 10:25:21 AM				
Moncayo, Fernando		please assign scrapper to Fernando.							
Michael Munoz									
112330					1/22/2014		75		\$0.00
Medium	Work In Progress				1/22/2014 3:12:10 PM				
Moncayo, Fernando		refrigerated air conditioners filter change							
Fernando Moncayo									
115567					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:37 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115566					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:36 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111535					1/5/2014		92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:50 AM				
Holguin, Alfredo		Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									
115596					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:56 AM				
Holguin, Alfredo		Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									

4/7/2014 2:48:54 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
113073					2/6/2014		60		\$0.00
Medium	Work In Progress				2/6/2014 10:16:16 AM				
Rodriguez, Arturo		ROSA APODACA OFFCE-POWER TO OUTLET WHERE COMPUTER IS CONNECTED WENT OUT.							
Maritza Gonzalez									
111437					12/19/2013		109		\$0.00
Medium	Work In Progress				12/19/2013 11:44:45				
Lara, Ralph		our door in the server room - battery not working anymore							
Cora Ramirez									
112603					1/29/2014		68		\$0.00
Medium	Work In Progress				1/29/2014 3:00:07 PM				
Solis, Lorenzo		IGNITION CONTROL BOARD NEEDS TO BE REPLACED IN MRS. AVILA, AND MRS. TAYLOR OFFICE, A WING.							
Maritza Gonzalez									
113770					2/25/2014		41		\$0.00
Medium	Work In Progress				2/25/2014 2:06:15 PM				
Moncayo, Fernando		maintenance rake and pick-up debris. also please start watering and clean other areas around site.yard needs grounds work (pine trees)							
Michael Munoz									
114252		Electrical Room			3/5/2014		33		\$0.00
Medium	Work In Progress				3/5/2014 7:32:59 AM				
Castillo, Carlos		Order material and equipment for stock.							
Carlos Castillo									
115219		Electrical Room			3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 8:34:24 AM				
Castillo, Carlos		Order vehicle cleaning maintanance equipment							
Carlos Castillo									
114642					3/14/2014		24		\$0.00
Medium	Work In Progress				3/14/2014 7:46:14 AM				
Castillo, Carlos		Start contacting bldg.mech. about summer projects and about material that will need to be ordered with sufficient time.							
Carlos Castillo									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
113952					2/28/2014		38		\$0.00
Medium	Work In Progress				2/28/2014 8:06:06 AM				
Castillo, Carlos		There is 3 lamps out at staffing parking on North side of building.							
Alfredo Holguin									
113853					2/27/2014		39		\$0.00
High	Work In Progress				2/27/2014 7:56:50 AM				
Castillo, Carlos		circuit board to generator is bad. need to have rocky mountain cummins order and replace.							
Michael Munoz									
112142					1/15/2014		82		\$0.00
Medium	Work In Progress				1/15/2014 2:54:39 PM				
Sotelo, Enrique		Asp CIRT (Crisis Intervention Response Team) need to mark Electrical on site plans that were provided by Mike.							
Michael Munoz									
113769		Restroom			2/25/2014		41		\$0.00
Medium	Work In Progress				2/25/2014 2:04:37 PM				
Moncayo, Fernando		please paint restrooms next to the cafeteria. thank you							
Michael Munoz									
108942		Parking Lot			10/16/2013		173		\$0.00
Medium	Work In Progress				10/16/2013 7:49:09 AM				
Moncayo, Fernando		need to repaint all parking lot lines - work can be done in phases over weekends by doing schedule adjustment.							
Alfredo Holguin									
115194					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:09 AM				
Moncayo, Fernando		Monthly - GAC A-16 Fan Exh Roof Semimonthly - Refer to PM schedule details.							
Margret Villalobos									
115484					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:28 AM				
Moncayo, Fernando		Monthly - GAC F-39 Kitch Exh Makeup Ut Semimonthly - Refer to PM schedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
115483					4/6/2014	4/22/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:27 AM				
Moncayo, Fernando		Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.							
Margret Villalobos									
114025					3/2/2014		36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:12 AM				
Moncayo, Fernando		Yearly - GAC A-10 Heat Pump Cooling Only Yearly - Refer to PM schedule details.							
Margret Villalobos									
114534					3/11/2014		27		\$0.00
Medium	Work In Progress				3/11/2014 4:07:11 PM				
Ontiveros, Joe		REPLACE FAUCETS ON MOP SINK-CUSTODIAL CLOSET A-WING.							
Maritza Gonzalez									
114159					3/3/2014		35		\$0.00
Medium	Work In Progress				3/3/2014 2:43:44 PM				
Ontiveros, Joe		As per Mrs. Yturralde she would like for a garbage disposal to be installed in the kitchen sink in C-Wing.							
Maritza Gonzalez									
115151					3/27/2014		11		\$0.00
High	Work In Progress				3/27/2014 4:03:43 PM				
Villalobos, David		back flow to fire protection system is leaking. please repair.							
Michael Munoz									
111480					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:18 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
Count: 48 Work Orders			Avg. Age of WO's	36			Total for GAC	0	\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC - Pre-K									
113704					2/24/2014		42		\$0.00
Medium	Work In Progress				2/24/2014 11:26:02 AM				
Ontiveros, Guadalupe		provide water to new raised planters							
Alfredo Holguin									
113705					2/24/2014		42		\$0.00
Medium	Work In Progress				2/24/2014 11:27:40 AM				
Ontiveros, Guadalupe		provide topsoil and compost for Metal Planters (4)-							
Alfredo Holguin									
113703					2/24/2014		42		\$0.00
Medium	Work In Progress				2/24/2014 11:24:57 AM				
Ontiveros, Guadalupe		Build an install two raised planters.							
Alfredo Holguin									
113551					2/19/2014		47		\$0.00
Medium	Work In Progress				2/19/2014 2:44:55 PM				
Moncayo, Fernando		PRE-K/SEWAGE BACKING UP.							
Maritza Gonzalez									
112420					1/23/2014		74		\$0.00
Medium	Work In Progress				1/23/2014 3:55:03 PM				
Moncayo, Fernando		ROOM 101-CLICKING NOISE IN THE LIGHT SWITCH.							
Maritza Gonzalez									
114342					3/6/2014		32		\$0.00
Medium	Work In Progress				3/6/2014 3:39:51 PM				
Moncayo, Fernando		relocate wooden shed and sealed around it,so animals won't crawl in							
Fernando Moncayo									
114191					3/4/2014		34		\$0.00
Medium	Work In Progress				3/4/2014 7:43:46 AM				
Moncayo, Fernando		We need to create a work order for the paper towel dispenser in room 103. It's coming off the wall. Also before the custodians come fixit could you have them talk with Ms. Viola or Ms. Pauline, that way they can move it to where the kids can reach it. Thank you.							
Maritza Gonzalez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: GAC - Pre-K									
114536					3/11/2014		27		\$0.00
Medium	Work In Progress				3/11/2014 4:08:34 PM				
Moncayo, Fernando	ROOM 203-LAMP OUTSIDE NEED TO SECURE SO BIRDS WILL NOT LAND AND MAKE A MESS.								
Maritza Gonzalez									
113760					2/25/2014		41		\$0.00
Medium	Work In Progress				2/25/2014 12:52:47 PM				
Ronquillo, Ruben	need to order bolts for dobbble slide from(recreation creations)								
Fernando Moncayo									
113848					2/26/2014		40		\$0.00
Medium	Work In Progress				2/26/2014 4:02:50 PM				
Holguin, Alfredo	Playground area is 60'x48'+or= and the surface is crushed rubber Glued and painted w/o # 113760 and is for a missing bolt The patio also have two small areas filled with sand								
Fernando Moncayo									
115376					4/2/2014		5		\$0.00
Medium	Work In Progress				4/2/2014 3:56:25 PM				
Gonzales, Camilo	Please Pick up two carts with televisions and VCR's to be delivered to Chaparral Pre-k								
Noemi Duron									
Count: 11 Work Orders			Avg. Age of WO's	39		Total for GAC - Pre-K	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden ES							
114895		Exterior			3/21/2014		17		\$0.00
Medium	Work In Progress				3/21/2014 9:20:56 AM				
Holguin, Alfredo		need wood chips for east playground equipment , needs refilling							
Fred Appelzoller									
115171					3/28/2014		10		\$0.00
Medium	Work In Progress				3/28/2014 3:06:00 PM				
Orozco, Daniel		LIGHT ON HOOD WENT OUT. SNP MANAGER EVA M. 882.3410							
Maritza Gonzalez									
111145		Classroom			12/11/2013		117		\$0.00
Medium	Work In Progress	205			12/11/2013 9:15:45 AM				
Solis, Lorenzo		" Under Warranty" room 205 air is coming our cold... thank you...							
Loraine Gandara									
115627					4/6/2014	4/17/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:15 AM				
Appelzoller, Fred		Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PMschedule details.							
Margret Villalobos									
115286		Classroom			4/1/2014		6		\$0.00
Medium	Work In Progress	101			4/1/2014 8:41:05 AM				
Appelzoller, Fred		need assistance once again the tile in the bathroom keeps falling off...need assistance since this our SCC unit and the students get scared when tile breaks... thank you...							
Loraine Gandara									
112579		Classroom			1/29/2014		68		\$0.00
Medium	Work In Progress	211			1/29/2014 8:42:55 AM				
Appelzoller, Fred		need assistance with putting some shelves in room 211... I would greatly appreciate your assistance in this matter...							
Loraine Gandara									
115553					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:27 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden ES

115560 4/6/2014 4/14/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:31:32 AM

Appelzoller, Fred Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.

Margret Villalobos

115561 4/6/2014 4/14/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:31:32 AM

Appelzoller, Fred Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.

Margret Villalobos

114484 3/11/2014 27 \$0.00

Medium Work In Progress 3/11/2014 7:27:39 AM

Appelzoller, Fred please cut weeds on the outside of the fence along hwy 478, in utility fenced area, back pond and surrounding areas around site. also grass has weeds growing, could use a cut.

Richard Chavez

114512 Hallway/Corridor 3/11/2014 27 \$0.00

Medium Work In Progress 3/11/2014 3:35:56 PM

Appelzoller, Fred need battery packs for emergency lighting in hallways T-8 lights . also 4 pin lamps for recess lights in lobby area and hall ways (4 pin GE- Biax T/E, F26TBX/830/A/ECO

Fred Appelzoller

113593 Hallway/Corridor 2/20/2014 46 \$0.00

Medium Work In Progress 2/20/2014 10:56:06 AM

Appelzoller, Fred need assistance with the wall molding in Jefferson wing...there is none next to the water fountain.. thank you...

Loraine Gandara

112124 1/15/2014 82 \$0.00

Medium Work In Progress 1/15/2014 11:08:10 AM

Marquez, Gerardo need to to have keys made for Zern lock boxes outside ...thank you....

Loraine Gandara

111043 12/9/2013 119 \$0.00

Medium Work In Progress 12/9/2013 12:13:30 PM

Marquez, Gerardo Silver working with DOT on setting up new flashing lights at GE. He cannot open box. need help with keys

Cora Ramirez

4/7/2014 2:48:55 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden ES

114772		Classroom			3/18/2014		20		\$0.00
--------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Work room in			3/18/2014 2:19:14 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Lara, Ralph
need immediate assistance... cannot open door or get into room...thank you....

Loraine Gandara

115204					3/31/2014		7		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/31/2014 12:54:18 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Appelzoller, Fred
Monthly - Gadsden ES - A-16 Fan Exhaust Semiannual
- Refer to PM schedule details.

Margret Villalobos

112205		Parking Lot			1/16/2014		81		\$0.00
--------	--	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/16/2014 3:36:46 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
. He indicated that he and Lorenzo were out checking the problem and determined that there is an electrical issue with the exterior lights. Supposedly Lorenzo was entering a work order, so the electrician could work on it.

Loraine Gandara

111498					1/5/2014	2/5/2014	92		\$0.00
--------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				1/5/2014 12:23:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Yearly - Gadsden ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

115298		Office			4/1/2014		6		\$0.00
--------	--	--------	--	--	----------	--	---	--	--------

Medium	Work In Progress				4/1/2014 1:51:10 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Sotelo, Enrique
need immediate assistance for tonight... need to replace outlet in cafeteria in order for us to use copy machine for us to register thank you.....

Loraine Gandara

114996		Cafeteria			3/25/2014		13		\$0.00
--------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/25/2014 10:55:18 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Appelzoller, Fred
as per Mr.Munoz and Ms. Marquez conversation
cafeteria must be painted... thank you...

Loraine Gandara

114995		Foyer			3/25/2014		13		\$0.00
--------	--	-------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/25/2014 10:53:53 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique
as per Mr. Munoz and Ms. Marquez conversation... a light fixture must be installed in the foyer... thank you...

Loraine Gandara

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Gadsden ES							
113762					2/25/2014		41		\$0.00
Medium	Work In Progress				2/25/2014 1:00:26 PM				
Sotelo, Enrique		need lamps for 2x2 light fixtures and 2' faculty r-rm's ... thank you greatly							
Loraine Gandara									
Count: 22 Work Orders		Avg. Age of WO's	36			Total for Gadsden ES	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
108046					9/27/2013		192		\$0.00
Medium	Work In Progress				9/27/2013 2:28:05 PM				
Sotelo, Enrique		Bus Turnaround - Need to provide power to lift station to prevent future flooding. (See Mike for details).							
Michael Munoz									
113594					2/20/2014		46		\$0.00
Medium	Work In Progress				2/20/2014 12:17:33 PM				
Sotelo, Enrique		Need to replace 4 lamps to lighting on the south side of campus by the tennis court and swimming pool. We will need the bucket truck.							
Guillermo Hernandez									
115677					4/7/2014		0		\$0.00
Medium	Work In Progress	LINE LOCATE			4/7/2014 9:30:25 AM				
Sotelo, Enrique		They can check with Allen Journey he should know. This work is being done by one of their subcontractors for the GHS project. Or they may need to attend the conference @ 9am on April 8th.							
Alfredo Holguin									
113915					2/28/2014	3/31/2014	38		\$0.00
Medium	Work In Progress				2/28/2014 12:32:45 AM				
Hernandez, Guillermo		Yearly - Gadsden HS C-11 (Evap.Condnser)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
114415					3/9/2014		29		\$0.00
Medium	Work In Progress				3/9/2014 12:19:01 AM				
Hernandez, Guillermo		Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PMschedule details.							
Margret Villalobos									
115487					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:31 AM				
Hernandez, Guillermo		Monthly - Gadsden HS H11 (E.Heater)(S.Annual) - Refer to PMschedule details.							
Margret Villalobos									
115486					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:30 AM				
Hernandez, Guillermo		Yearly - Gadsden HS A13 (Ceil/Wall Unit)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
115485					4/6/2014	4/22/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:29 AM				
Hernandez, Guillermo		Monthly - Gadsden HS A1 (Air Dryer)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
115195					3/31/2014	5/1/2014	7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:10 AM				
Hernandez, Guillermo		Yearly - Gadsden HS A8 (Window Unit)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
112079					1/14/2014		83		\$0.00
Medium	Work In Progress				1/14/2014 1:25:02 PM				
Villalobos, David		Fire Pump Valves - Install air relief Valve - Mario A. and Guillermo know location							
Alfredo Holguin									
112080					1/14/2014		83		\$0.00
Medium	Work In Progress				1/14/2014 1:27:21 PM				
Villalobos, David		Fire Pump- re-plumb drain line from floor sink so it drains to the outside of the building. Mario A. or Guillermo can provide specifics.							
Alfredo Holguin									
111481					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:18 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
115676					4/7/2014		0		\$0.00
Medium	Work In Progress	LINE LOCATE			4/7/2014 9:29:03 AM				
Villalobos, David		They can check with Allen Journey he should know. This work is being done by one of their subcontractors for the GHS project. Or they may need to attend the conference @ 9am on April 8th.							
Alfredo Holguin									
115464					4/4/2014		3		\$0.00
Medium	Work In Progress				4/4/2014 3:56:55 PM				
Villalobos, David		Need to replace gaskets on hanging toilets in the boys restroom and girls restroom at the Annex building.							
Guillermo Hernandez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
108987					10/16/2013		173		\$0.00
Medium	Work In Progress				10/16/2013 4:12:21 PM				
Villalobos, David		Annexbuilding in special ed classroom shower head is leaking needs to be replaced							
Daniel Sotelo									
108988					10/16/2013		173		\$0.00
Medium	Work In Progress				10/16/2013 4:13:50 PM				
Villalobos, David		In weight room girls bathroom shower head is leaking needs to be replaced							
Daniel Sotelo									
104583					7/22/2013		259		\$0.00
Medium	Work In Progress				7/22/2013 3:49:21 PM				
Villalobos, David		Need to replace gasket to shower in the Sped classroom at the Annex building.							
Guillermo Hernandez									
114797					3/18/2014		20		\$0.00
Medium	Work In Progress				3/18/2014 3:55:42 PM				
Villalobos, David		Need assistance to unclog urinal in the weight room. Unclogged but still no working right.							
Guillermo Hernandez									
115469					4/6/2014	4/9/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:16 AM				
Sotelo, Daniel		Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
109631					11/1/2013		157		\$0.00
Medium	Work In Progress				11/1/2013 2:50:12 PM				
Villalobos, David		Need assistance to repair hanging toilet, water is leaking behind the wall. Boys restroom Annexbuilding.							
Guillermo Hernandez									
110294					11/15/2013		143		\$0.00
Medium	Work In Progress				11/15/2013 9:48:05 AM				
Ambriz, Jose		Need assistance trouble shooting fresh air heaters units for the Old English building.							
Guillermo Hernandez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
110323					11/15/2013		143		\$0.00
Medium	Work In Progress				11/15/2013 3:56:44 PM				
Ambriz, Jose		Need to replace motors for the heating units in Old English #148,#146 and mechanical room.							
Guillermo Hernandez									
107034					9/3/2013		216		\$0.00
Medium	Work In Progress				9/3/2013 3:52:55 PM				
Ambriz, Jose		Need to replace exhaust fan motors in the weight room (Jose has sample motor).							
Guillermo Hernandez									
105469					8/6/2013		244		\$0.00
Medium	Work In Progress				8/6/2013 9:25:16 AM				
Ambriz, Jose		Requested by Staff in Academic Building-Water fountain near boy's restroom closest to cafeteria is not working.							
Velia Alarcon									
114283					3/5/2014		33		\$0.00
Medium	Work In Progress				3/5/2014 3:27:32 PM				
Ambriz, Jose		Need to replace (7) 6800 Evap. coolers from Academic: EVAP-GHS-23, EVAP-GHS-027, EVAP-GHS-030, EVAP-GHS-31, EVAP-GHS-033, EVAP-GHS-34, EVAP-GHS-38.							
Guillermo Hernandez									
114285					3/5/2014		33		\$0.00
Medium	Work In Progress				3/5/2014 3:35:45 PM				
Ambriz, Jose		Need to replace 1 down draft 6800 Evap cooler MCD-GHS-024 and 2 commercial Evap. cooler, side draft one wet section MCD-GHS-022 and MCD-GHS-023. on the kitchen roof.							
Guillermo Hernandez									
114290					3/5/2014		33		\$0.00
Medium	Work In Progress				3/5/2014 3:44:45 PM				
Ambriz, Jose		Need to replace commercial Evap. cooler, side draft two wet sections for the Weight room.							
Guillermo Hernandez									
113464					2/18/2014		48		\$0.00
High	Work In Progress				2/18/2014 7:54:48 AM				
Ambriz, Jose		Need to replace heating assembly to H/C unit for Portable #1. Carrier model CPHEATER051A00, SERIAL #4501G00017. (208/240/1HP/60HZ)							
Guillermo Hernandez									

4/7/2014 2:48:55 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
114193					3/4/2014		34		\$0.00
Medium	Work In Progress				3/4/2014 7:55:41 AM				
Ambriz, Jose		Need to replace Damper Actuator to RTU #62 at the North building.							
Guillermo Hernandez									
114742					3/17/2014		21		\$0.00
Medium	Work In Progress				3/17/2014 4:00:22 PM				
Ambriz, Jose		Need to reroute return duct to H/C unit in Portable #2.							
Guillermo Hernandez									
114962					3/24/2014		14		\$0.00
Medium	Work In Progress				3/24/2014 3:37:22 PM				
Ambriz, Jose		Need to replace gaskets to water supplylines on the boiler room for the heating system on the Old English building.							
Guillermo Hernandez									
115355					4/2/2014		5		\$0.00
Medium	Work In Progress				4/2/2014 3:15:21 PM				
Lara, Ralph		Requested by Velia-Mailbox# 110 key was lost and an extra keys needs to be made.							
Velia Alarcon									
113213					2/10/2014		56		\$0.00
Medium	Work In Progress				2/10/2014 1:43:43 PM				
Lara, Ralph		Requested by Mrs. Munoz Rm. 207 North Building-Door from kitchen to classroom needs to have a double side lock. Only has lock from kitchen to classroom and not from classroom to kitchen.							
Velia Alarcon									
115380					4/3/2014		4		\$0.00
Medium	Work In Progress				4/3/2014 7:53:37 AM				
Lara, Ralph		Rafa, I need to replace keys 7GM and 6GM, having problems with doors.							
Guillermo Hernandez									
115381					4/3/2014		4		\$0.00
Medium	Work In Progress				4/3/2014 7:54:48 AM				
Lara, Ralph		Need to replace door knob to the mechanic room by the Old Panther hut at North building.							
Guillermo Hernandez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

115382 4/3/2014 4 4/3/2014 7:56:08 AM \$0.00

Medium Work In Progress

Lara, Ralph Need to replace core to door for Mr. Marques classroom at the Annex building.

Guillermo Hernandez

114677 3/16/2014 22 3/16/2014 12:21:01 AM \$0.00

Medium Work In Progress

Villalobos, Margret Monthly - Gadsden HS - PC Automated Quarterly - Emailed 3/17/14
Refer to PM schedule details.

Margret Villalobos

114221 3/4/2014 34 3/4/2014 2:46:17 PM \$0.00

Medium Work In Progress

Lara, Ralph need a new key to mail box the one I have is about to break thanks

Daniel Sotelo

112644 1/30/2014 67 1/30/2014 10:19:28 AM \$0.00

Medium Work In Progress

Lara, Ralph Requested by Velia-An extra key is needed for mailbox # 31 and # 96.

Velia Alarcon

112645 1/30/2014 67 1/30/2014 10:21:00 AM \$0.00

Medium Work In Progress

Lara, Ralph Requested by Velia-Mailbox # 72 is ver hard to open. SEE MARIA FOR EXTRA KEY TO MAILBOX.

Velia Alarcon

114495 Pool 3/11/2014 27 3/11/2014 10:58:53 AM \$0.00

High Work In Progress

Lara, Ralph Keys lost by contractor. Please replace DC20 Pool key and HE157 Southgate key. Invoice Contractor for all keys that need to be made for replacing lost keys. Should you have any questions please contact Mr. Ralph Gallegos at 575- 882-6921. "Gadsden HS Swimming Pool Upgrades" project

Dominique Esparza

115568 4/6/2014 4/14/2014 1 4/6/2014 12:31:37 AM \$0.00

Medium Work In Progress

Hernandez, Guillermo Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

4/7/2014 2:48:55 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

114991 Classroom 3/25/2014 13 \$0.00

Medium Work In Progress 519 3/25/2014 9:25:58 AM

Hernandez, Guillermo Requested by Mr. Villa Rm. 519 Annex Building-Light bulbs in the band room need to be replaced.

Velia Alarcon

114845 Classroom 3/20/2014 18 \$0.00

Medium Work In Progress Portable 9 3/20/2014 8:59:28 AM

Hernandez, Guillermo Requested by Mr. Gerela Pt. 9-Mount the pencil sharpener on wall.

Velia Alarcon

115435 Classroom 4/4/2014 3 \$0.00

Medium Work In Progress 604 4/4/2014 9:42:36 AM

Hernandez, Guillermo Requested by Mrs. Lam Rm. 604 New Science Building- ATTENTION MEMO HERNANDEZ-Remove 4 paper towel dispensers in room 604. Put one paper towel dispenser in teacher's lounge (bottom floor of the New Science Building) by the sink.

Velia Alarcon

114778 Classroom 3/18/2014 20 \$0.00

Safety Work In Progress Annex Building- 3/18/2014 3:18:20 PM

Hernandez, Guillermo Requested by Mr. Martin Rm. 518 Annex Building-Part of the floor is cracked around an electric outlet and may be a hazard. Please have someone check it out for safety. THIS IS A SP.ED. CLASSROOM.

Velia Alarcon

115595 4/6/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:31:55 AM

Holguin, Alfredo Monthly - Gadsden HS - Fire Pump Engine - Refer to PM schedule details.

Margret Villalobos

115590 4/6/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:31:52 AM

Holguin, Alfredo Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.

Margret Villalobos

114068 3/2/2014 3/10/2014 36 \$0.00

Medium Work In Progress 3/2/2014 12:26:33 AM

Sotelo, Daniel Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

4/7/2014 2:48:55 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
115392		Classroom			4/3/2014		4		\$0.00
Medium	Work In Progress	617			4/3/2014 10:47:38 AM				
Sotelo, Daniel		Requested by Mr. R. Ramos Rm. 617 New Science Building-Need to have the U.S. and state flags put in classroom.							
Velia Alarcon									
115572					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:40 AM				
Sotelo, Daniel		Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
115570					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:39 AM				
Sotelo, Daniel		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115571					4/6/2014	5/7/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:39 AM				
Sotelo, Daniel		Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
115394					4/3/2014		4		\$0.00
Medium	Work In Progress				4/3/2014 10:50:56 AM				
Sotelo, Daniel		Requested by Mr. R. Ramos Rm. 617 New Science Building-Would like a shelf from old Science Storage Room to storage room in 617.							
Velia Alarcon									
114487					3/11/2014		27		\$0.00
Medium	Work In Progress				3/11/2014 8:24:14 AM				
Carrasco, Danny		ATT:DANNY C. Need a tool box for polaris thanks							
Daniel Sotelo									
115220					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 8:40:48 AM				
Carrasco, Danny		att: Danny C. need a basin wrench grainger part number 4a503, small tube cutter 1ath6, and a hitch for Polaris with 5 3/4 rise on it and two inch ball							
		Thank you							
Daniel Sotelo									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

114817 3/19/2014 19 \$0.00

Medium Work In Progress 3/19/2014 2:10:03 PM

Flores, Pete All the gators tires need to be replaced, the ones in the front are going bald again and the back are going out as well.

Jaime Herrera

115535 4/6/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:31:14 AM

Flores, Pete Monthly - GHS-UV-0515 PM Service - Refer to PM schedule details.

Margret Villalobos

110330 11/16/2013 142 \$0.00

Medium Work In Progress 11/16/2013 12:18:09

Flores, Pete Yearly - Gadsden HS - Mow (0408/0419/0428) Grounds - Refer to PM schedule details.

Margret Villalobos

113749 2/25/2014 41 \$0.00

Medium Work In Progress 2/25/2014 8:53:22 AM

Flores, Pete Requested by Mr. Mora-Athletic training gator not running, needs to be checked for battery functions.

Velia Alarcon

115218 3/31/2014 7 \$0.00

Medium Work In Progress 3/31/2014 8:33:48 AM

Flores, Pete att: Pete need to check Polaris ignition switch is going bad will not completely turn off lights stay on draining battery

thanks

Daniel Sotelo

115512 4/6/2014 4/14/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:30:50 AM

Hernandez, Guillermo Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.

Margret Villalobos

112430 1/24/2014 73 \$0.00

Medium Work In Progress 1/24/2014 9:03:35 AM

Flores, Pete Requested by Mr. Mora Athletic Training Room-Athletic Training gator will not charge. Batteries need to be tested to make sure they are still good.

Velia Alarcon

4/7/2014 2:48:55 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Gadsden HS									
115623					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:13 AM				
Hernandez, Guillermo	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
115645					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:27 AM				
Orozco, Daniel	Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
115666					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:41 AM				
Munoz, Michael	Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
113942					2/28/2014		38		\$0.00
Medium	Work In Progress				2/28/2014 12:32:59 AM				
Munoz, Michael	Yearly - Gadsden HS - Fire Pump Inspection - Refer to PM schedule details.								
Margret Villalobos									
115276					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 12:53:16 AM				
Hernandez, Guillermo	Weekly - Gadsden HS - Fire Pump (Biweekly) - Refer to PM schedule details.								
Margret Villalobos									
114818	Old English Bldg	Hallway/Corridor			3/19/2014		19		\$0.00
Medium	Work In Progress	Second Floor			3/19/2014 2:14:54 PM				
Hernandez, Guillermo	There are five floor tiles that are missing and two more that are coming off.								
Jaime Herrera									
115072	Academic Bldg	Classroom			3/26/2014		12		\$0.00
Medium	Work In Progress	339			3/26/2014 3:15:30 PM				
Hernandez, Guillermo	Requested Ms. Leahy Rm. 339 Academic Building-A/C is blowing warm air and lots of dirt and grit.								
Velia Alarcon									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Gadsden HS									
113876	Academic Bldg				2/27/2014		39		\$0.00
Medium	Work In Progress	342			2/27/2014 1:56:30 PM				
Sotelo, Daniel	Requested by Ms. Roth for Teacher's Lounge of the South Side of the Academic Building-Replace shade, string is about to break off after screen was busted out.								
Velia Alarcon									
114990	Academic Bldg	Classroom			3/25/2014		13		\$0.00
Medium	Work In Progress	305			3/25/2014 9:23:19 AM				
Sotelo, Daniel	Requested by Ms. Lennox Rm. 305 Academic Building- Three of the light panels (fluorescent lights) are burned out.								
Velia Alarcon									
113875	Academic Bldg	Classroom			2/27/2014		39		\$0.00
Medium	Work In Progress	328			2/27/2014 1:54:36 PM				
Sotelo, Daniel	Requested by Ms. Roth Rm. 328 Academic Building- Replace window shade, string about to break off.								
Velia Alarcon									
112094	Academic Bldg	Classroom			1/14/2014		83		\$0.00
Medium	Work In Progress	331			1/14/2014 3:38:14 PM				
Lara, Ralph	Requested by Ms. Hartmann Rm. 331 Academic Building-Please re-key classroom door, which includes two door into the court yard, to a different key number.								
Velia Alarcon									
112979	Academic Bldg	Classroom			2/4/2014		62		\$0.00
Medium	Work In Progress	331			2/4/2014 3:45:51 PM				
Villalobos, David	Requested by Ms. Hartmann Rm. 331 Academic Building-Relocate sink cabinet from room 107 in the Main Building to room 331 in the Academic Building.								
Velia Alarcon									
114669	Boys Gym				3/14/2014		24		\$0.00
High	Work In Progress				3/14/2014 3:50:59 PM				
Estrada, Jesus	Need to repair a bump on the wood floor by the west side basket. This is a safety issue.					3/17/14 - ASP CHUY, (1) NEED TO: FIX (4) CORNERS/AREAS - THEY ARE BUCKLEING; (2) SHAVE COMPLETE FLOOR; (3) REPAINT LINES; (4) REFINISH. FAXED TO STOUT HARDWOODS.			
Guillermo Hernandez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
115123	Cafeteria (1998)	Cafeteria			3/27/2014		11		\$0.00
Medium	Work In Progress	East Wing of the			3/27/2014 2:55:54 PM				
Sotelo, Daniel		Requested by Velia for East Wing of Cafeteria-The conference room is very hot. The a/c need to be turn on.							
Velia Alarcon									
114858	Cafeteria (1998)	Restroom			3/20/2014		18		\$0.00
Medium	Work In Progress				3/20/2014 2:00:22 PM				
Lara, Ralph		All of the partitions are all rusted out on the bottom and need to be replaced.							
Jaime Herrera									
114254	Cafeteria (1998)				3/5/2014		33		\$0.00
Medium	Work In Progress				3/5/2014 7:51:10 AM				
Sotelo, Daniel		There are some ceiling tiles that need to changed out, there are milk or water stains.							
Jaime Herrera									
113062	Varsity Gym	Gym			2/6/2014		60		\$0.00
Medium	Work In Progress				2/6/2014 8:46:53 AM				
Gallegos, Rafael		WARRANTY WORK ON GYM FLOOR need to fix two broken planks on gym floor they are located on the southeast corner right out side of basketball court							
Daniel Sotelo									
114930	Varsity Gym				3/21/2014		17		\$0.00
Medium	Work In Progress				3/21/2014 4:15:43 PM				
Munoz, Michael		PM - Annual Bleacher Service performed by A.K. Sales.							
Michael Munoz									
112089	Varsity Gym	Gym			1/14/2014		83		\$0.00
Medium	Work In Progress	Boy's Soccer			1/14/2014 3:33:02 PM				
Sotelo, Daniel		Requested by Coach Lawrence/Mrs. Soriano for Boy's Soccer Locker Room-Paint window and put blinds on windows.							
Velia Alarcon									
113815	Varsity Gym				2/25/2014		41		\$0.00
Medium	Work In Progress				2/25/2014 4:09:37 PM				
Sotelo, Daniel		need to replaces a few stair plank's on bleachers							
Daniel Sotelo									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
115169					3/28/2014		10		\$0.00
Medium	Work In Progress				3/28/2014 3:01:53 PM				
Orozco, Daniel		MOP SINK IS LEAKING FROM HOSE, DOES NOT HOLD WATER. SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
113420					2/14/2014		52		\$0.00
Medium	Work In Progress				2/14/2014 12:22:34 AM				
Sanchez, Raul		Monthly - Gadsden HS- Filters (Pump Rm) Quarterly - Refer to PM schedule details.							
Margret Villalobos									
115207					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:21 AM				
Sanchez, Raul		Monthly - Gadsden HS - Monthly Meter Readings - Refer to PM schedule details.							
Margret Villalobos									
115611					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:05 AM				
Sanchez, Raul		Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
115609					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:04 AM				
Sanchez, Raul		Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
114101					3/2/2014		36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:48 AM				
Sanchez, Raul		Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
114688					3/17/2014		21		\$0.00
Medium	Work In Progress				3/17/2014 9:44:44 AM				
Orozco, Daniel		Sink is leaking – vegetable sink Washing machine is not working properly Light bulbs for exhaust are out SNP Manager Frances B. 882.5522							
Maritza Gonzalez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

113585 Athletic Field 2/20/2014 46 \$0.00

Medium Work In Progress 2/20/2014 8:29:12 AM

Gonzalez, Salvador Requested by Ms. L. Chavez-Move batting tee structure back take poles off fence and attach to metal structure. Add chain link fence to existing poles. ANY QUESTIONS PLEASE SEE COACH LILLY CHAVEZ.

Velia Alarcon

110536 11/22/2013 136 \$0.00

Medium Work In Progress 11/22/2013 9:11:34 AM

Orozco, Daniel FLOOR LIFTED IN WALK IN REFRIGERATOR. SNP MANAGER FRANCES B. 882.5522

Maritza Gonzalez

106135 8/16/2013 234 \$0.00

Medium Work In Progress 8/16/2013 8:50:03 AM

Orozco, Daniel kitchen-ladies restroom – toilet, has a crack in the bottom. It is leaking out water and the exhaust does not work.

Maritza Gonzalez

115418 4/3/2014 4 \$0.00

Medium Work In Progress 4/3/2014 3:51:10 PM

Gonzalez, Salvador Need to cover openings on the outside wall of the Boys gym, size 8ft. x 3ft. and 32 inch x 94 inch.

Guillermo Hernandez

115419 4/3/2014 4 \$0.00

Medium Work In Progress 4/3/2014 3:53:22 PM

Gonzalez, Salvador Need to secure metal screen on the east wall in the boys gym, screen is coming off and balls may go in to the next area used for the football team.

Guillermo Hernandez

115247 3/31/2014 7 \$0.00

Medium Work In Progress 3/31/2014 3:18:18 PM

Gonzalez, Salvador please primer backstop to boys baseball as per mr. chavez

Michael Munoz

109350 Athletic Field 10/25/2013 164 \$0.00

Medium Work In Progress 10/25/2013 3:35:29 PM

Gonzalez, Salvador please replace door to morgan building by batting cages. boys baseball. thank you

Michael Munoz

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
114999		Athletic Field			3/25/2014		13		\$0.00
High	Work In Progress			3/25/2014 11:12:01 AM					
Holguin, Ramiro	Contractors that are installing power to lites at G.H.S have broken four 2" main line that water baseball field. They are trenching softball field this week.								
Guadalupe Ontiveros									
114989	New Admin Bldg				3/25/2014		13		\$0.00
Medium	Work In Progress	Mailboxes		3/25/2014 9:17:31 AM					
Hernandez, Guillermo	Requested by Velia-There's a piece of black formica stripping that is becoming unglued and needs to be repaired before it comes off and lost.								
Velia Alarcon									
113765	Auto Shop				2/25/2014		41		\$0.00
Medium	Work In Progress			2/25/2014 1:10:51 PM					
Hernandez, Guillermo	Requested by Mr. Enriquez Rm. 509 New CTE Building Auto Shop-Install 2 post lift in auto shop. SEE MR. ENRIQUEZ FOR LOCATION OF LIFT AND LOCATION HE WOULD LIKE LIFT INSTALLED.								
Velia Alarcon									
114854	Counselors				3/20/2014		18		\$0.00
Medium	Work In Progress			3/20/2014 11:14:59 AM					
Gonzalez, Salvador	football field bleachers - Remove top bench including angle support and cover bottom opening on back rail with welded wire fabric/miners screen.								
Alfredo Holguin									
114774	Pool Pump	Pool			3/18/2014		20		\$0.00
Medium	Work In Progress			3/18/2014 3:06:20 PM					
Apodaca, Mario	Annual Pool Start-up; prepare pool for the summer program to include cleaning of pool & pump house & passing of pool inspection by NMED. Please provide copies of work order to both Mario & Raul Thanks								
Raul Sanchez									
114777	Pool Pump	Pool			3/18/2014		20		\$0.00
Medium	Work In Progress			3/18/2014 3:17:47 PM					
Apodaca, Mario	need to a new a pool lift seat to meet with the code complains for ada								
Mario Apodaca									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
114707	Pool Pump	Pool			3/17/2014		21		\$0.00
Medium	Work In Progress				3/17/2014 2:30:07 PM				
Apodaca, Mario		Need some aluminum signs made up for the pool area I will put up the signs							
Mario Apodaca									
109015	Pool Pump	Pool			10/17/2013		172		\$0.00
Medium	Work In Progress				10/17/2013 3:07:03 PM				
Apodaca, Mario		need to replace all pool ladders at pool do to wear and tear							
Mario Apodaca									
109016	Pool Pump	Pool			10/17/2013		172		\$0.00
Medium	Work In Progress				10/17/2013 3:10:55 PM				
Apodaca, Mario		need to order pool chemicals and equipment							
Mario Apodaca									
115438	Pool Pump				4/4/2014		3		\$0.00
Medium	Work In Progress				4/4/2014 10:18:09 AM				
Hernandez, Guillermo		patch hole in roof on NW corner							
Alfredo Holguin									
113083	Grounds Shop				2/6/2014		60		\$0.00
Medium	Work In Progress				2/6/2014 2:31:25 PM				
Solis, Lorenzo		please order new ice machine and install. thank you							
Michael Munoz									
114853	Football Stadium				3/20/2014		18		\$0.00
Medium	Work In Progress				3/20/2014 11:11:32 AM				
Sotelo, Enrique		Press Box- Complete installation of electrical outlet in football field electrical vault.							
Alfredo Holguin									
111671	Community				1/6/2014		91		\$0.00
Medium	Work In Progress				1/6/2014 1:20:40 PM				
Ronquillo, Ruben		Re-upholster all benches and torn pads on weight training equipment.							
Alfredo Holguin									
Count: 110 Work Orders		Avg. Age of WO's 46		Total for Gadsden HS		0		\$0.00	

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

111897 Main Building 1/10/2014 87 \$0.00

Medium Work In Progress Door next to 1/10/2014 11:33:51 AM

Marquez, Gerardo Handicap door in B wing will not open. Its the door close to room 118.

Nancy Tinajero

113962 Band Room Pump House 2/28/2014 38 \$0.00

Medium Work In Progress 2/28/2014 2:58:46 PM

Marquez, Gerardo need to issue out a key for the pump room to the building mechanic a DC15

Mario Apodaca

106140 Annex Restroom 8/16/2013 234 \$0.00

Medium Work In Progress STAFF 8/16/2013 10:16:55 AM

Marquez, Gerardo CAN NOT OPEN DOOR WITH KEY A.S.A.P

Juan Acosta

112197 Vocational 1/16/2014 81 \$0.00

Medium Work In Progress Room 306 1/16/2014 3:03:38 PM

Marquez, Gerardo Cylinder on lock to cage is not working.

Nancy Tinajero

114540 Gymnasium Gym 3/12/2014 26 \$0.00

Medium Work In Progress concession 3/12/2014 8:07:10 AM

Solis, Lorenzø Ice machine in concession stand is broken....needs repair not making ice.

Nancy Tinajero

112592 Gymnasium Gym 1/29/2014 68 \$0.00

Medium Work In Progress Gym Lobby 1/29/2014 11:38:45 AM

Solis, Lorenzø Please fix heater in gym lobby it is not working.

Nancy Tinajero

115613 4/6/2014 4/12/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:32:06 AM

Diaz, Sebastian Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

114984 3/25/2014 13 \$0.00

Medium Work In Progress 3/25/2014 7:42:37 AM

Gonzalez, Salvador please fabricate new mail box like the high school. contact person commie avalos

Michael Munoz

4/7/2014 2:48:56 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
115603					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:00 AM				
Apodaca, Mario		Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
112683					1/31/2014		66		\$0.00
Medium	Work In Progress				1/31/2014 12:27:06 AM				
Apodaca, Mario		Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
115604					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:01 AM				
Apodaca, Mario		Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
114105					3/2/2014		36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:50 AM				
Apodaca, Mario		Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
114618	C-Wing	Portables			3/13/2014		25		\$0.00
Medium	Work In Progress				3/13/2014 3:30:27 PM				
Diaz, Sebastian		gutter is missing in back to athletic and chavez portable. wall is exposed. please install new ones. see mike for details. thank you							
Michael Munoz									
114848	C-Wing	Exterior			3/20/2014		18		\$0.00
Medium	Work In Progress	207-c			3/20/2014 10:19:41 AM				
Ontiveros, Guadalupe		Our compound would appreciate a shade tree planted where the old palm tree that died was. Thank you , Colleen							
Colleen Runyan									
114383	C-Wing				3/7/2014		31		\$0.00
Medium	Work In Progress	(Old Central			3/7/2014 2:44:21 PM				
Solis, Lorenzo		Need to check unit at thank you							
Sebastian Diaz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
113296	C-Wing				2/11/2014		55		\$0.00
Medium	Work In Progress				2/11/2014 4:16:55 PM				
Villalobos, David		Old Central Office - Need to replace all plumbing fixtures to include commode in Main Lobby.							
Michael Munoz									
113306	C-Wing	Parking Lot			2/12/2014		54		\$0.00
Medium	Work In Progress				2/12/2014 8:14:59 AM				
Villalobos, David		Constant flow on fire protection bfp, have continuously taken out debris from unit.							
David Villalobos									
111358	C-Wing				12/17/2013		111		\$0.00
Safety	Work In Progress				12/17/2013 12:21:17				
Diaz, Sebastian		All Portable Ramps at C-Wing - Asp Mr. Chavez he wants all ramps replaced w/new boards. Please see him.							
Richard Chavez									
112149	Gym	Mechanical			1/15/2014		82		\$0.00
Medium	Work In Progress				1/15/2014 3:28:01 PM				
Solis, Lorenzo		need to replace old Bryant boiler with new raypac. to include new piping, valves and 2 new motors							
Michael Munoz									
112116	Gym	Dressing Room			1/15/2014		82		\$0.00
Medium	Work In Progress				1/15/2014 6:44:11 AM				
Solis, Lorenzo		please replace existing heating coils with new modern ones.(boys and girls)							
Michael Munoz									
112117	Gym	Dressing Room			1/15/2014		82		\$0.00
High	Work In Progress				1/15/2014 6:46:31 AM				
Solis, Lorenzo		p.e teacher mentioned that there was no cooling in dressing rooms. please check, also check for a vent relief. thank you							
Michael Munoz									
114933		Gym			3/21/2014		17		\$0.00
Medium	Work In Progress				3/21/2014 4:18:31 PM				
Munoz, Michael		PM - Annual Bleacher Service performed by A.K. Sales.							
Michael Munoz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Gadsden MS									
115646					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:28 AM				
Orozco, Daniel	Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
115517					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:55 AM				
Diaz, Sebastian	Monthly - Gadsden MS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
115388					4/3/2014		4		\$0.00
Medium	Work In Progress	Front office			4/3/2014 9:20:04 AM				
Marquez, Gerardo	The small vault that is in the walk-in vault does not want to open. Neither the key or key pad work.								
Nancy Tinajero									
112252					1/17/2014		80		\$0.00
Medium	Work In Progress				1/17/2014 3:49:17 PM				
Marquez, Gerardo	Need to check doors and replace for new on gym thank you								
Sebastian Diaz									
115527					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:06 AM				
Diaz, Sebastian	Monthly - Gadsden MS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
115541					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:18 AM				
Diaz, Sebastian	Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
115542					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:19 AM				
Diaz, Sebastian	Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
113591					2/20/2014		46		\$0.00
Medium	Work In Progress				2/20/2014 9:37:27 AM				
Diaz, Sebastian		Clean debris around Morgan Building.							
Michael Munoz									
114675					3/14/2014		24		\$0.00
Medium	Work In Progress				3/14/2014 4:23:29 PM				
Diaz, Sebastian		please cut weeds in front of campus and parking lot. thank you							
Michael Munoz									
114537					3/11/2014		27		\$0.00
Medium	Work In Progress				3/11/2014 4:10:58 PM				
Flores, Pete		VEHICLE 150(MR. BAKER) FLASHER/BLINKER NOT WORKING. WILL BE AVAILABLE MARCH 20-28.							
Maritza Gonzalez									
115440		Classroom			4/4/2014		3		\$0.00
Medium	Work In Progress	Room 301			4/4/2014 10:26:08 AM				
Marquez, Gerardo		Door does not lock.							
Nancy Tinajero									
113867		Athletic Field			2/27/2014		39		\$0.00
High	Work In Progress				2/27/2014 11:26:14 AM				
Marquez, Gerardo		NURSES LOCKED KEYS IN THERE OFFICE. NEED A LOCKSMITH TO OPEN DR. ASAP. THANKS.							
Juan Acosta									
105924		Custodial			8/13/2013		237		\$0.00
Medium	Work In Progress				8/13/2013 12:53:11 PM				
Marquez, Gerardo		WE ALSO NEED AN EXTRA KEY MADE FOR OUR NIGHT CUSTODIAN THIS KEY IS FOR THE JOHN DEER GATOR							
Juan Acosta									
112198					1/16/2014		81		\$0.00
Medium	Work In Progress				1/16/2014 3:04:51 PM				
Marquez, Gerardo		Need to fix handicap doors around the entire school.							
Nancy Tinajero									
113295					2/11/2014		55		\$0.00
Safety	Work In Progress				2/11/2014 4:15:31 PM				
Ontiveros, Guadalupe		Basketball Courts - need to put gravel around area.							
Michael Munoz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
115499					4/6/2014	4/22/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:30:40 AM					
Villalobos, Margret	Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details.		Emailed 4/7/14						
Margret Villalobos									
115434		Hallway/Corridor			4/4/2014		3		\$0.00
Medium	Work In Progress	B wing by room		4/4/2014 9:05:49 AM					
Solis, Lorenz	Water fountain by room 111 has a leaking pipe.								
Nancy Tinajero									
114431					3/10/2014		28		\$0.00
Medium	Work In Progress			3/10/2014 8:54:19 AM					
Solis, Lorenz	On boiler cafeteria need to check water pump thank you								
Sebastian Diaz									
114432					3/10/2014		28		\$0.00
Medium	Work In Progress			3/10/2014 8:58:01 AM					
Solis, Lorenz	On boiler east need to replace circulate pump thank you								
Sebastian Diaz									
115481					4/6/2014		1		\$0.00
Medium	Work In Progress			4/6/2014 12:30:25 AM					
Diaz, Sebastian	Yearly - Gadsden MS A-13 A/C Wall Mount Yearly - Refer to PM schedule details.								
Margret Villalobos									
115480					4/6/2014	4/22/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:30:24 AM					
Diaz, Sebastian	Monthly - Gadsden MS A-1 Wall Ref Elec Semiannual - Refer to PM schedule details.								
Margret Villalobos									
115479					4/6/2014		1		\$0.00
Medium	Work In Progress			4/6/2014 12:30:23 AM					
Diaz, Sebastian	Monthly - Gadsden MS H-11 Unit Elec Ht Semiannual - Refer to PM schedule details.								
Margret Villalobos									
115205					3/31/2014		7		\$0.00
Medium	Work In Progress			3/31/2014 12:54:20 AM					
Diaz, Sebastian	Monthly - Gadsden MS A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
115074					3/26/2014		12		\$0.00
Medium	Work In Progress				3/26/2014 3:17:36 PM				
Villalobos, David		Vocational Bldg - water leak in wall.							
Michael Munoz									
110842					12/4/2013		124		\$0.00
Medium	Work In Progress				12/4/2013 11:47:22 AM				
Villalobos, David		Need to check drain pipe on B w2ing thank you							
Sebastian Diaz									
115472					4/6/2014	4/9/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:18 AM				
Diaz, Sebastian		Monthly - Gadsden MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111482					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:19 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
Count: 49 Work Orders			Avg. Age of WO's	43		Total for Gadsden MS	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union - JTP Alvarez Farms									
112573					1/29/2014		68		\$0.00
Medium	Work In Progress				1/29/2014 8:24:23 AM				
Aguilar, Patricio		big toy in playground in bad need of repair. slide cracked bys un age - step broken and rust - taped with caution tape				1/31-Route back to Pat asp Mike			
Patricio Aguilar									
113118					2/7/2014		59		\$0.00
Medium	Work In Progress				2/7/2014 8:52:39 AM				
Aguilar, Patricio		wo to myself - need gopher pellets for playground							
Patricio Aguilar									
Count: 2 Work Orders			Avg. Age of WO's	64		Total for La Union - JTP Alvarez Farms	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

114649 3/14/2014 24 \$0.00

Medium Work In Progress 3/14/2014 1:04:54 PM

Aguilar, Patricio wo to myself - slide cracked by sum age - step broken and rusted - putting in order to warehouse for parts

Patricio Aguilar

113253 2/11/2014 55 \$0.00

Medium Work In Progress 2/11/2014 8:57:03 AM

Holguin, Alfredo changing sand with wood fiber
3 areas
1 - back playground toy 50' x 70' with border need replace 4
2 - back playground swing set 20' x 60' has no borders
3 - courtyard toy 50' x 60' with border need replace 14

Patricio Aguilar

115206 3/31/2014 7 \$0.00

Medium Work In Progress 3/31/2014 12:54:21 AM

Sanchez, Raul Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details.

Margret Villalobos

115612 4/6/2014 4/12/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:32:06 AM

Aguilar, Patricio Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.

Margret Villalobos

115647 4/6/2014 4/27/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:32:28 AM

Orozco, Daniel Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

111485 1/5/2014 2/5/2014 92 \$0.00

Medium Work In Progress 1/5/2014 12:23:20 AM

Villalobos, David Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

114951 Classroom 3/24/2014 14 \$0.00

Medium Work In Progress 3/24/2014 1:10:21 PM

Castillo, Carlos an opening will be cut out between rooms 108 & 109. some electrical plugs will need to be removed or re-located.

Patricio Aguilar

4/7/2014 2:48:56 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
115308					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 3:17:52 PM				
Ontiveros, Joe		clogged rest room toilet - floor drain - will need snake kitchen							
Patricio Aguilar									
115020					3/25/2014		13		\$0.00
Medium	Work In Progress				3/25/2014 2:08:10 PM				
Aguilar, Patricio		wo to myself - need to replace fluorescent lamps r305							
Patricio Aguilar									
114648					3/14/2014		24		\$0.00
Medium	Work In Progress				3/14/2014 12:55:19 PM				
Ronquillo, Ruben		Here the list of a/c pads for the old wing and annex b - a/c r210 uses 4 - 16" x 25" x 1" and old wing 15 a/c use 1 - 20" x 22" x 1" may be good to double order that. Thanks for all you help.							
Patricio Aguilar									
113923					2/28/2014	3/31/2014	38		\$0.00
Medium	Work In Progress				2/28/2014 12:32:49 AM				
Aguilar, Patricio		Yearly - La Union ES C-11 Evap Coolers Yearly - Refer to PMschedule details.							
Margret Villalobos									
115477					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:22 AM				
Aguilar, Patricio		Monthly - La Union ES H-11 Unit Elec Ht Semiannual - Refer to PMschedule details.							
Margret Villalobos									
114151					3/3/2014		35		\$0.00
Medium	Work In Progress				3/3/2014 10:48:17 AM				
Ontiveros, Guadalupe		need the use of a utility tractor with loader - rear blade for the fare back yard thanks for the help.							
Patricio Aguilar									
115534					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:13 AM				
Aguilar, Patricio		Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
115540					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:18 AM				
Aguilar, Patricio		Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115539					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:17 AM				
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
113861					2/27/2014		39		\$0.00
Medium	Work In Progress				2/27/2014 10:10:21 AM				
Aguilar, Patricio		wo to myself - to move infocus & bracket - screen from r106 to r301 need butterfly anchors							
Patricio Aguilar									
114316					3/6/2014		32		\$0.00
Medium	Work In Progress				3/6/2014 8:17:30 AM				
Aguilar, Patricio		wo to myself - need to replace master cool medias - belts gym office new wing							
Patricio Aguilar									
114152					3/3/2014		35		\$0.00
Medium	Work In Progress				3/3/2014 10:52:06 AM				
Aguilar, Patricio		wo to myself need to water back yard - need 2" water hose about 200 ft							
Patricio Aguilar									
115520					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:58 AM				
Aguilar, Patricio		Monthly - La Union ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
114842					3/20/2014		18		\$0.00
Medium	Work In Progress				3/20/2014 8:28:36 AM				
Miranda, Danny		cut opening on wall from room 108 to room 109 - wo as per mike munoz							
Patricio Aguilar									
Count: 21 Work Orders			Avg. Age of WO's	21		Total for La Union ES	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Loma Linda ES							
115405					4/3/2014		4		\$0.00
Medium	Work In Progress				4/3/2014 2:54:47 PM				
Medina, Eric		need to weed and feed all fields at alamo also							
Eric Medina									
114561					3/12/2014		26		\$0.00
Medium	Work In Progress				3/12/2014 1:04:27 PM				
Medina, Eric		need to extracted several basketball from ceiling							
Eric Medina									
114380					3/7/2014		31		\$0.00
Medium	Work In Progress				3/7/2014 12:38:08 PM				
Medina, Eric		Need to replace basketball goals							
Eric Medina									
115558					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:30 AM				
Medina, Eric		Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115552					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:26 AM				
Medina, Eric		Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
115559					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:31 AM				
Medina, Eric		Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115510					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:49 AM				
Medina, Eric		Monthly - Loma Linda ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
115307					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 3:07:24 PM				
Flores, Pete		Pete need to request gator							
Eric Medina									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
110300					11/15/2013		143		\$0.00
Safety	Work In Progress				11/15/2013 12:28:27				
Flores, Pete		Pete the seat belt in truck 31 fixed or replaced please thank you							
Eric Medina									
113927					2/28/2014	3/31/2014	38		\$0.00
Medium	Work In Progress				2/28/2014 12:32:51 AM				
Medina, Eric		Yearly - Loma Linda ES C11(Evap.Condnsr)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
115193					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:09 AM				
Medina, Eric		Monthly - Loma Linda ES A16(Fan Exh.)(S.Annual) - Refer to PMschedule details.							
Margret Villalobos									
115474					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:19 AM				
Medina, Eric		Yearly - Loma Linda ES A13(AC Wall Mount)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
112542					1/28/2014		69		\$0.00
Medium	Work In Progress				1/28/2014 3:27:25 PM				
Sotelo, Enrique		need 6 pole light bulbs replaced							
Eric Medina									
112414					1/23/2014		74		\$0.00
Medium	Work In Progress				1/23/2014 3:42:30 PM				
Sotelo, Enrique		need to replace 9 outdated light fixtures in rm 207							
Eric Medina									
111483					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:20 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PMschedule details.							
Margret Villalobos									
115648					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:29 AM				
Orozco, Daniel		Monthly - Loma Linda ES Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
115626					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:15 AM				
Medina, Eric		Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
115662					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:39 AM				
Munoz, Michael		Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
106474					8/23/2013		227		\$0.00
Medium	Work In Progress				8/23/2013 3:28:34 PM				
Gonzalez, Salvador		Chava need a square drag for loma linda thank you							
Eric Medina									
114381					3/7/2014		31		\$0.00
Medium	Work In Progress				3/7/2014 12:39:29 PM				
Gonzalez, Salvador		Sal need to lower two basketball goals to six feet							
Eric Medina									
115350					4/2/2014		5		\$0.00
Medium	Work In Progress				4/2/2014 1:49:11 PM				
Orozco, Daniel		CORD CONNECTION ON SERVING LINE SPARKED AND MADE POPPING NOISE. SNP MANAGER DOLORES R. 882.4707							
Maritza Gonzalez									
115351					4/2/2014		5		\$0.00
Medium	Work In Progress				4/2/2014 1:50:13 PM				
Orozco, Daniel		OVEN NOT HEATING PROPERLY. SNP MANAGER DOLORES R. 882.4707							
Maritza Gonzalez									
115172					3/28/2014		10		\$0.00
Medium	Work In Progress				3/28/2014 3:11:32 PM				
Orozco, Daniel		AS PER ECO LAB -VACUUM BREAKER AND FINAL RINSE JETS NEED TO BE REPLACED ON THE DISHWASHER.							
Maritza Gonzalez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
114506					3/11/2014		27		\$0.00
Medium	Work In Progress				3/11/2014 3:05:49 PM				
Orozco, Daniel		The drain from the ice maker is not draining and is full please advice.							
Maritza Gonzalez									
113304					2/12/2014		54		\$0.00
Medium	Work In Progress				2/12/2014 8:06:11 AM				
Holguin, Alfredo		need to replace sand with woodchips on primary playground and replace 12 borders							
Eric Medina									
113305					2/12/2014		54		\$0.00
Medium	Work In Progress				2/12/2014 8:08:01 AM				
Holguin, Alfredo		need to replace sand with woodchips in secondary playground and replace 6 borders							
Eric Medina									
113003	Main Building	Classroom			2/5/2014		61		\$0.00
Medium	Work In Progress	108			2/5/2014 8:45:45 AM				
Medina, Eric		Blinds will not open or close "both"							
Angie Flores									
115238	Main Building	Classroom			3/31/2014		7		\$0.00
Medium	Work In Progress	204			3/31/2014 12:57:29 PM				
Medina, Eric		Light is turning on/off consequently							
Angie Flores									
114445	Main Building	Classroom			3/10/2014		28		\$0.00
Medium	Work In Progress	Computer Lab			3/10/2014 2:15:19 PM				
Medina, Eric		Three light fixtures in the computer lab are still not working and need to be repaired or replaced.							
Angie Flores									
108825	Main Building				10/14/2013		175		\$0.00
Medium	Work In Progress	Nurses Office			10/14/2013 11:36:02				
Marquez, Gerardo		New Lock for Large Medicine Cabinet							
Angie Flores									
106797	Main Building	Restroom			8/30/2013		220		\$0.00
Medium	Work In Progress	In Front of Mrs.			8/30/2013 10:48:44 AM				
Marquez, Gerardo		Stall doors in the boys restroom in front of Mrs. Whites room dont lock							
Angie Flores									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Loma Linda ES							
113376	Main Building	Gym			2/13/2014		53		\$0.00
Medium	Work In Progress	Stage			2/13/2014 2:17:21 PM				
Sotelo, Enrique		Knobs that control the lighting for the stage where completely broken off, need to be replaced							
Angie Flores									
Count: 32 Work Orders		Avg. Age of WO's		45	Total for Loma Linda ES			0	\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
115397	Main Building	Office			4/3/2014		4		\$0.00
Medium	Work In Progress			4/3/2014 11:19:47 AM					
Gonzales, Camilo	Pick up obsolete items , (36), tecnology, furniture, equipment								
Theresa Ramirez									
107019	Pump House	Pump House			9/3/2013		216		\$0.00
Medium	Work In Progress			9/3/2013 3:26:54 PM					
Marquez, Gerardo	the door to the Pump Room at mesquite elementary needs to be replaced door hinges are broken up and very hard to open								
Mario Apodaca									
114109					3/2/2014		36		\$0.00
Medium	Work In Progress			3/2/2014 12:26:52 AM					
Apodaca, Mario	Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
113366					2/13/2014		53		\$0.00
Medium	Work In Progress			2/13/2014 9:52:19 AM					
Holguin, Alfredo	need 3 sand play areas replaced with engineered wood fiber. area 2 needs 62 pieces of border replaced								
Joe Ramirez									
115608					4/6/2014		1		\$0.00
Medium	Work In Progress			4/6/2014 12:32:03 AM					
Apodaca, Mario	Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
115164					3/28/2014		10		\$0.00
Medium	Work In Progress			3/28/2014 11:42:45 AM					
Gonzalez, Salvador	need to modify projector bracket so that it can be mounted								
Joe Ramirez									
115620					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:32:11 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Mesquite ES							
105671					8/8/2013		242		\$0.00
Medium	Work In Progress				8/8/2013 1:03:55 PM				
Marquez, Gerardo		door and door jamb for rm.608 needs to be replaced it is in reall ybad shape.							
Joe Ramirez									
115649					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:30 AM				
Orozco, Daniel		Monthly - Mesquite ES Range Hood Cleaning - Refer to PMs schedule details.							
Margret Villalobos									
111486					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:21 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
115471					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:17 AM				
Ramirez, Joe		Monthly - Mesquite ES - Barrack Drainage (Monthly) - Refer to PMs schedule details.							
Margret Villalobos									
115163					3/28/2014		10		\$0.00
Medium	Work In Progress				3/28/2014 11:41:14 AM				
Villalobos, David		gate valve at community park back flow preventor is broken needs to be replaced.							
Joe Ramirez									
114313					3/6/2014		32		\$0.00
Medium	Work In Progress				3/6/2014 7:58:27 AM				
Villalobos, David		need to replace 4 sensor activated lavatories in 2 bathrooms they are not working properly.							
Joe Ramirez									
114843					3/20/2014		18		\$0.00
Medium	Work In Progress				3/20/2014 8:46:22 AM				
Sotelo, Enrique		photo-cell on barrack bldg is not working needs to be replaced.							
Joe Ramirez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Mesquite ES							
115301					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 2:10:08 PM				
Sotelo, Enrique		need power run to automatic door operator							
Joe Ramirez									
114844					3/20/2014		18		\$0.00
Medium	Work In Progress				3/20/2014 8:47:45 AM				
Ramirez, Joe		food pantry and laundry rm in the kitchen need to be painted.							
Joe Ramirez									
111996					1/13/2014		84		\$0.00
Medium	Work In Progress				1/13/2014 8:11:26 AM				
Marquez, Gerardo		automatic door closer needs to be installed							
Joe Ramirez									
115201					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:16 AM				
Ramirez, Joe		Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.							
Margret Villalobos									
115482					4/6/2014	4/22/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:25 AM				
Ramirez, Joe		Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.							
Margret Villalobos									
115102		Computer Lab			3/27/2014		11		\$0.00
Medium	Work In Progress				3/27/2014 8:58:31 AM				
Estrada, Jesus		Mr. Estrada, On the computer lab the carpet is torn out need new carpet. If you have a chance, could you please stop by and see it. Thank you							
Luis Saucedo									
115513					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:51 AM				
Ramirez, Joe		Monthly - Mesquite ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
115296					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 1:46:56 PM				
Marquez, Gerardo		rm .302 door does not close right.							
Joe Ramirez									
4/7/2014 2:48:56 PM									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
115545					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:31:21 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
115543					4/6/2014		1		\$0.00
Medium	Work In Progress			4/6/2014 12:31:20 AM					
Ramirez, Joe	Monthly - Mesquite ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
115544					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:31:20 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
111219					12/12/2013		116		\$0.00
Medium	Work In Progress			12/12/2013 3:32:59 PM					
Holguin, Alfredo	Demo -Remove septic tank and electrical								
Alfredo Holguin									
Count: 26 Work Orders		Avg. Age of WO's 37		Total for Mesquite ES			0	\$0.00	

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		North Valley ES							
111531					1/5/2014		92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:47 AM				
Holguin, Alfredo		Monthly - North Valley ES - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
115592					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:53 AM				
Holguin, Alfredo		Monthly - North Valley ES - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
114916					3/21/2014		17		\$0.00
Medium	Work In Progress				3/21/2014 3:43:59 PM				
Vega, Danny		3-21-14 1-ck heat pumps at nve 7-wk od#112356 total \$230.00							
Danny Vega									
115554					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:28 AM				
Vega, Danny		Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115555					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:28 AM				
Vega, Danny		Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115507					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:47 AM				
Vega, Danny		Monthly - North Valley ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
114764					3/18/2014		20		\$0.00
Medium	Work In Progress				3/18/2014 10:21:57 AM				
Ronquillo, Ruben		ATTENTION RUBEN RONQUILLO-damage to marquee sign 4ftx8ft door frame plus plexi-glass cover 4ftx8ft-need major repairs-new locks							
Danny Vega									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: North Valley ES									
111035		Office			12/9/2013		119		\$0.00
Medium	Work In Progress	nurses office rm		12/9/2013 11:08:57 AM					
Marquez, Gerardo Please send locksmith, we have purchased 2 new locks for our medicine cabinet that need to be installed.									
Priscilla Martinez									
114148					3/3/2014		35		\$0.00
Medium	Work In Progress			3/3/2014 10:16:02 AM					
Ontiveros, Guadalupe Attention Lupe o-/need fertilizer on grass field(weed and feed type)had alot of weed spread out last year /never gave grass a chance to grow its starting come back.APPRX 40 SACKS									
Danny Vega									
115386					4/3/2014		4		\$0.00
Medium	Work In Progress			4/3/2014 8:39:42 AM					
Vega, Danny need to paint parking lot stripes and handi-cap parkings/west parking lot									
Danny Vega									
113301					2/12/2014		54		\$0.00
Medium	Work In Progress			2/12/2014 7:41:12 AM					
Sotelo, Enrique emergency lite ballast are burnt out in mechanical rms by rms 301-303-304-308-309-311-mechanical rm by staff lounge and pipe chase closet by bys rr peach wing and rio grand wing piope chase also these are for heater unit closets									
Danny Vega									
114700					3/17/2014		21		\$0.00
Medium	Work In Progress			3/17/2014 11:13:53 AM					
Villalobos, David boilers that feeds kitchen is leaking .cant exactly see from where but it looks like relief valve is bad									
Danny Vega									
111496					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress			1/5/2014 12:23:26 AM					
Villalobos, David Yearly - North Valley ES Backflow Inspection - Refer to PM schedule details.									
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
115637					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:22 AM				
Orozco, Daniel		Monthly - North Valley ES - Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
115667					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:42 AM				
Munoz, Michael		Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
113943					2/28/2014		38		\$0.00
Medium	Work In Progress				2/28/2014 12:33:00 AM				
Munoz, Michael		Yearly - North Valley ES - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
115629					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:17 AM				
Vega, Danny		Monthly - North Valley ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
114840					3/20/2014		18		\$0.00
Medium	Work In Progress				3/20/2014 7:45:36 AM				
Orozco, Daniel		THE CHOPPER WAS ASSEMBLED WRONG, TO TIGHT CANT USE IT. SNP MANAGER LAURA B. 233.3658.							
Maritza Gonzalez									
113536					2/19/2014		47		\$0.00
Medium	Work In Progress				2/19/2014 11:44:10 AM				
Holguin, Alfredo		have (3ea)sand boxsections need sand removed and fill w/wood chips (borders are all good)							
Danny Vega									
Count: 19 Work Orders			Avg. Age of WO's	30		Total for North Valley ES	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

113535 2/19/2014 47 \$0.00

Medium Work In Progress 2/19/2014 11:41:20 AM

Holguin, Alfredo need sand removed from 3 (ea) plygrd section sand boxes and filled w/wood chips total of 20 (ea) borders that in need of replacement

Danny Vega

115628 4/6/2014 4/12/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:32:16 AM

Vega, Danny Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.

Margret Villalobos

114650 3/14/2014 24 \$0.00

Medium Work In Progress 3/14/2014 1:15:29 PM

Gonzalez, Salvador Do Repair work on utility trailer #4/-straighten out A-FRAME jack-weld ramp chain lock pins-reinforce expanded metal ramp-weld tie down insert on sides for rope-this is used to transport mowers from lm to sme to nve

Danny Vega

115447 Main Building Classroom 4/4/2014 3 \$0.00

Medium Work In Progress 4/4/2014 2:37:10 PM

Marquez, Gerardo CLASSROOM 108 (DAYCARE) DOOR HANDLE FOR CLOSET IN RESTROOM IS MISSING CORE AND HANDLE IS LOOSE.

Adam Montoya

115448 Main Building Classroom 4/4/2014 3 \$0.00

Medium Work In Progress 4/4/2014 2:38:53 PM

Marquez, Gerardo CLASSROOM 114 (DAYCARE). BATHROOM DOOR HANDLE IS LOOSE AND LOCK IS STICKING.

Adam Montoya

115454 Main Building Office 4/4/2014 3 \$0.00

Medium Work In Progress 4/4/2014 3:21:17 PM

Gonzales, Camilo Pick up obsolete Xerox. See Concha

Theresa Ramirez

111484 1/5/2014 2/5/2014 92 \$0.00

Medium Work In Progress 1/5/2014 12:23:20 AM

Villalobos, David Yearly - Northern Pre-K Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

4/7/2014 2:48:57 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
114155					3/3/2014		35		\$0.00
Medium	Work In Progress			3/3/2014 11:30:24 AM					
Ontiveros, Guadalupe	NEED FERTILIZER ON GRASS FIELD (WWED N FEED)APPRX 20 SACKS								
Danny Vega									
113264					2/11/2014		55		\$0.00
Medium	Work In Progress			2/11/2014 2:06:05 PM					
Ronquillo, Ruben	NEED PLASTIC THAT HOLDS LETTERS FOR MARQUEE REPLACED. MANY PARTS HAVE BROKEN OFF.(BOTH SIDES)				Asp Danny V. route to Ruben will be sending Company				
Adam Montoya									
113267					2/11/2014		55		\$0.00
Medium	Work In Progress			2/11/2014 2:29:40 PM					
Ronquillo, Ruben	NEED REPLACEMENT FLAGS FOR BOTH AMERICAN AND NEW MEXICO FLAGS.								
Adam Montoya									
115509					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:30:48 AM					
Vega, Danny	Monthly - La Mesa ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
111683					1/6/2014		91		\$0.00
Medium	Work In Progress			1/6/2014 3:05:45 PM					
Ontiveros, Guadalupe	need 1 load fill dirt for sidewalks at lm pre-k and small bucket tractor to level off								
Danny Vega									
115557					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:31:30 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
115556					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:31:29 AM					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
Count: 14 Work Orders			Avg. Age of WO's	29	Total for Northern On-Track Pre-K (LM)		0	\$0.00	

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
113953					2/28/2014		38		\$0.00
Medium	Work In Progress				2/28/2014 8:18:47 AM				
Gonzalez, Salvador		2-27-14 Attn Danny Carrasco Requesting 20 ton shop press for welding shop.							
Salvador Gonzalez									
113453					2/14/2014		52		\$0.00
Medium	Work In Progress				2/14/2014 3:45:58 PM				
Miranda, Danny		Installation of cabinets and appliances in PPD Lounge room assigned to DannyM.							
Danny Carrasco									
110835					12/4/2013		124		\$0.00
Medium	Work In Progress				12/4/2013 10:47:58 AM				
Holguin, Alfredo		Acquire "Right of Use Permit" for 40ft of left bank of Anthony drain for parking access, fence and landscaping.							
Alfredo Holguin									
115598					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:57 AM				
Ruiz, Maria		Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.							
Margret Villalobos									
114051					3/2/2014		36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:25 AM				
Ruiz, Maria		Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.							
Margret Villalobos									
115674					4/7/2014		0		\$0.00
Medium	Work In Progress				4/7/2014 8:18:23 AM				
Villalobos, Margret		PPD Park - Need to apply something for grubs on grass area.							
Michael Munoz									
114832		Parking Lot			3/19/2014		19		\$0.00
Medium	Work In Progress				3/19/2014 3:53:37 PM				
Ontiveros, Guadalupe		need to trim saltcedders by parking area of district vechles as per Mr.Holgiun.							
Guadalupe Ontiveros									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
115224		Athletic Field			3/31/2014		7		\$0.00
Medium	Work In Progress			3/31/2014 9:29:49 AM					
Aldaz, Bobby	MX5000 Kubota tractor back tires need to be fill up with water for when loading up with front bucket.								
Guadalupe Ontiveros									
113812					2/25/2014		41		\$0.00
Medium	Work In Progress			2/25/2014 3:56:53 PM					
Marquez, Gerardo	need a spare set of keys for trucks 38 For Expedition & toolbox								
Mario Apodaca									
113583					2/20/2014		46		\$0.00
Medium	Work In Progress			2/20/2014 8:01:56 AM					
Marquez, Gerardo	Lock to Margret's office is hard to lock/unlock asp Saul, Custodian.								
Saul Chavez									
115516					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:30:53 AM					
Diaz, Sebastian	Monthly - Physical Plant Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
114997		Athletic Field			3/25/2014		13		\$0.00
Medium	Work In Progress			3/25/2014 11:07:29 AM					
Flores, Pete	Dump Truck #143 Tail Gate Valve Leaking Air. Dump Cylinder Leaking Hyd OIL. Check Brakes to low. Front Bearings need to be repack.								
Bobby Aldaz									
112175					1/16/2014		81		\$0.00
Medium	Work In Progress			1/16/2014 7:28:50 AM					
Flores, Pete	please service truck # 119 (jose ambriz) and wash. thank you								
Michael Munoz									
108706					10/10/2013		179		\$0.00
Medium	Work In Progress			10/10/2013 3:53:08 PM					
Flores, Pete	No back lights when I turn on the switch and front windshield is cracked								
David Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
114551					3/12/2014		26		\$0.00
Medium	Work In Progress				3/12/2014 8:47:43 AM				
Flores, Pete		need to order one pair of side steps for vehicle 38							
Mario Apodaca									
113554					2/19/2014		47		\$0.00
Medium	Work In Progress				2/19/2014 3:10:07 PM				
Flores, Pete		vehicle 99 is overheating. please check. thank you							
Michael Munoz									
113669					2/21/2014		45		\$0.00
Medium	Work In Progress				2/21/2014 3:45:38 PM				
Ronquillo, Ruben		ford truck 38 need order dash covers and floor mats							
Mario Apodaca									
113673					2/21/2014		45		\$0.00
Medium	Work In Progress				2/21/2014 3:48:32 PM				
Ronquillo, Ruben		ORDER DASH MATS AND FLOOR MATS FOR VEHICLE #37							
Ruben Ronquillo									
112825					2/2/2014		64		\$0.00
Medium	Work In Progress				2/2/2014 12:26:32 AM				
Flores, Pete		Monthly - PPD-T-0529 PM (Trencher) - by SWP - Refer to PM schedule details.							
Margret Villalobos									
115299					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 1:59:48 PM				
Ronquillo, Ruben		ORDER 12V SUMP PUMPS 8EA. THANK YOU!							
Ruben Ronquillo									
114327					3/6/2014		32		\$0.00
Medium	Work In Progress				3/6/2014 1:26:39 PM				
Ronquillo, Ruben		PURCHASE 10EA. 18V DE-WALT COMBO KITS. THANK YOU!							
Ruben Ronquillo									
111656					1/6/2014		91		\$0.00
Medium	Work In Progress				1/6/2014 12:24:15 AM				
Flores, Pete		Monthly - PPD - UV-0516 PM Service - Refer to PM schedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
111570					1/5/2014		92		\$0.00
Medium	Work In Progress				1/5/2014 12:24:12 AM				
Flores, Pete		Monthly - PPD-MP-0143 DT PM Service - by SWP - Refer to PM schedule details.							
Margret Villalobos									
113418					2/14/2014		52		\$0.00
Medium	Work In Progress				2/14/2014 12:22:32 AM				
Flores, Pete		Yearly - PPD-T-0524 Bobcat PM Service - Refer to PM schedule details.							
Margret Villalobos									
115536					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:15 AM				
Flores, Pete		Monthly - PPD-MP-0143 DT PM Service - by SWP - Refer to PM schedule details.							
Margret Villalobos									
109372					10/28/2013		161		\$0.00
Medium	Work In Progress				10/28/2013 7:25:31 AM				
Diaz, Sebastian		Maint Office - Need to paint inside of main door and replace covebase.							
Michael Munoz									
106552		Athletic Field			8/27/2013		223		\$0.00
Medium	Work In Progress				8/27/2013 8:41:44 AM				
Marquez, Gerardo		need copies of keys for new fuel cap that was install on John Deere Backhoe L110							
Guadalupe Ontiveros									
109051					10/17/2013		172		\$0.00
Medium	Work In Progress				10/17/2013 4:11:07 PM				
Solis, Lorenz		please install heating and cooling unit in old electrical/hvac shop and remove existing furnace and a/c. thank you							
Michael Munoz									
114601					3/13/2014		25		\$0.00
Medium	Work In Progress				3/13/2014 11:31:13 AM				
Vallejo, Albert		Eastern Area - please check all electrical panels, and install blank covers were breakers are not needed. (Any questions, please call Mike)							
Michael Munoz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
111487					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:21 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
115234					3/31/2014		7		\$0.00
Medium	Work In Progress	LINE LOCATE			3/31/2014 11:36:01 AM				
Villalobos, David		TRIPLE J EXCAVATION Name: ANNETTE GRANADO Phone: (575)527-1763 New Warehouse Area - FROM THE INTERSECTION OF S. MAIN ST & E. WASHINGTON ST IN ANTHONY, GO TO WEST ON WASHINGTON ST FOR APPROX. 1.44MI TO ANTHONY CHARTER SCHOOL. GO INTO SCHOOL PROPERTY AND GO PAST THE GAS PUMPS AND BEHIND THE FOOTBALL FIELD, Remarks: LOCATE A 300FT RADIUS AT THE BUILDING LOCATED BEHIND THE FOOTBALL FIELD							
Alfredo Holguin									
109289					10/24/2013		165		\$0.00
Medium	Work In Progress				10/24/2013 10:51:56				
Villalobos, David		ice machine will be placed in lobby area of rest rooms in the old hvac/electrical shop. will need sewer and water. thank you							
Michael Munoz									
114600					3/13/2014		25		\$0.00
Medium	Work In Progress				3/13/2014 11:30:23 AM				
Sotelo, Enrique		Northern Area - please check all electrical panels, and install blank covers were breakers are not needed. (Any questions, please call Mike)							
Michael Munoz									
114599					3/13/2014		25		\$0.00
Medium	Work In Progress				3/13/2014 11:29:04 AM				
Castillo, Carlos		Southern Area - please check all electrical panels, and install blank covers were breakers are not needed. (Any questions, please call Mike)							
Michael Munoz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
110384					11/19/2013		139		\$0.00
Medium	Work In Progress				11/19/2013 7:56:50 AM				
Sotelo, Enrique		please provide lighting to new conference room . where old electrical/hvac shop used to be.							
Michael Munoz									
111139					12/11/2013		117		\$0.00
Medium	Work In Progress				12/11/2013 8:25:15 AM				
Sotelo, Enrique		Need to install light on pole where mobile home use to be.							
Michael Munoz									
115170	Food Services				3/28/2014		10		\$0.00
Medium	Work In Progress				3/28/2014 3:03:04 PM				
Orozco, Daniel		WALK IN REFRIGERATOR IS DROPPING THE TEMP.							
Maritza Gonzalez									
110392	Motor Vehicle				11/19/2013		139		\$0.00
Medium	Work In Progress				11/19/2013 9:49:47 AM				
Gonzalez, Salvador		need door installed to addition to auto shop metal back building. thank you.							
Michael Munoz									
112014	Motor Vehicle				1/13/2014		84		\$0.00
Medium	Work In Progress	ditchwitch rt45			1/13/2014 1:05:57 PM				
Flores, Pete		please check cause of burning smell.							
Pete Flores									
113740	Motor Vehicle				2/24/2014		42		\$0.00
Medium	Work In Progress				2/24/2014 4:15:21 PM				
Flores, Pete		please service vehicle # 100. once serviced assign to the grounds department.							
		thank you							
Michael Munoz									
114731	Motor Vehicle				3/17/2014		21		\$0.00
Medium	Work In Progress	vehicle-149			3/17/2014 3:46:11 PM				
Flores, Pete		fuel and temperature gauges erratic and inaccurate. please check and advise.							
Pete Flores									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
114732	Motor Vehicle				3/17/2014		21		\$0.00
Medium	Work In Progress	vehicle-149		3/17/2014 3:47:09 PM					
Flores, Pete	fuel and temperature gauges erratic and inaccurate. please check and advise. mileage-89805, also check for any scheduled maintenance.								
Pete Flores									
114734	Motor Vehicle				3/17/2014		21		\$0.00
Medium	Work In Progress	vehicle#163		3/17/2014 3:51:13 PM					
Flores, Pete	please check for any scheduled maintenance. mileage-80291								
Pete Flores									
114736	Motor Vehicle				3/17/2014		21		\$0.00
Medium	Work In Progress	vehicle#164		3/17/2014 3:54:19 PM					
Flores, Pete	check engine light has illuminated, please check cause and advise-mileage 73514								
Pete Flores									
114763	Motor Vehicle				3/18/2014		20		\$0.00
Medium	Work In Progress			3/18/2014 10:18:39 AM					
Flores, Pete	as per discussion, please services old 110 lawn mower with out deck for ghs baseball/softball program. thank you								
Richard Chavez									
115069	Motor Vehicle				3/26/2014		12		\$0.00
Medium	Work In Progress	vehicle#158		3/26/2014 2:55:08 PM					
Flores, Pete	please check for loss of brake pressure and, check for any required maintenance.								
Pete Flores									
115070	Motor Vehicle				3/26/2014		12		\$0.00
Medium	Work In Progress	vehicles-		3/26/2014 2:57:13 PM					
Flores, Pete	please refuel, clean, wash & prepare to meet trip schedule								
Pete Flores									
104728	Motor Vehicle				7/25/2013		256		\$0.00
Medium	Work In Progress	5510 tractor		7/25/2013 10:19:26 AM					
Flores, Pete	tractor's warning lights are inoperative, and fuel gage is inaccurate. please check.								
Pete Flores									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
115423	Motor Vehicle				4/3/2014		4		\$0.00
Medium	Work In Progress	vehicle#21			4/3/2014 4:14:08 PM				
Flores, Pete		please check for service mi.-3586							
Pete Flores									
115425	Motor Vehicle				4/3/2014		4		\$0.00
Medium	Work In Progress	vehicles-			4/3/2014 4:18:06 PM				
Flores, Pete		please refuel, clean, wash, and prepare to meet daily trip schedule							
Pete Flores									
115227	Motor Vehicle				3/31/2014		7		\$0.00
Medium	Work In Progress	vehicle#125			3/31/2014 10:48:30 AM				
Flores, Pete		please check cause of strong fuel odor.							
Pete Flores									
114321	Motor Vehicle				3/6/2014		32		\$0.00
Medium	Work In Progress	Fed. Programs			3/6/2014 8:58:54 AM				
Flores, Pete		On Fed. Programs car #180 check engine and change oil lights turned on							
Noemi Duron									
114333	Motor Vehicle				3/6/2014		32		\$0.00
Medium	Work In Progress	kubota tractor			3/6/2014 2:37:10 PM				
Flores, Pete		right front blistered, needs to be replaced.							
Pete Flores									
114194	Motor Vehicle				3/4/2014		34		\$0.00
Medium	Work In Progress				3/4/2014 7:57:06 AM				
Flores, Pete		veeder root printing messages probe out & low temp warning. Alfredo is going to call Kachina to have them come out.				Pete removed probe and inserted back in tank... it cleared messages for a few minutes and then messages started printing again.			
113587	Motor Vehicle				2/20/2014		46		\$0.00
Medium	Work In Progress				2/20/2014 9:01:17 AM				
Flores, Pete		Connie Sifuentes called vehicle #111 is overheating. She is stranded on Westside Dr/South Vinton							
Maria Ruiz									
113644	Motor Vehicle				2/21/2014		45		\$0.00
Medium	Work In Progress				2/21/2014 10:55:21 AM				
Perez, Raul		vehicle #48 has a dead battery							
Maria Ruiz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
113855	Purchasing				2/27/2014		39		\$0.00
Medium	Work In Progress				2/27/2014 8:02:26 AM				
Villalobos, David		Men's Restroom in Custodial Warehouse - Raise urinal							
Alfredo Holguin									
114593	Purchasing				3/13/2014		25		\$0.00
Medium	Work In Progress				3/13/2014 10:33:50 AM				
Diaz, Sebastian		PPD Reception Area- Paint							
Alfredo Holguin									
114893	Purchasing	Office			3/21/2014		17		\$0.00
Medium	Work In Progress				3/21/2014 8:53:47 AM				
Diaz, Sebastian		Please service the heating/cooling system in the office.							
Theresa Ramirez									
112432	Purchasing	Office			1/24/2014		73		\$0.00
Medium	Work In Progress				1/24/2014 9:12:13 AM				
Chavez, Saul		Please shampoo carpet, Instructional Material Office (Mr. Leyva). Thank You.							
Theresa Ramirez									
115300					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 2:01:52 PM				
Ronquillo, Ruben		INSTALL NEW GAS/DIESEL TANKS NEW TRUCK #37							
Ruben Ronquillo									
114268					3/5/2014		33		\$0.00
Medium	Work In Progress				3/5/2014 9:36:06 AM				
Ronquillo, Ruben		PURCHASE 7'X12' DUMP TRAILER. THANK YOU!							
Ruben Ronquillo									
114204					3/4/2014		34		\$0.00
Medium	Work In Progress				3/4/2014 9:13:41 AM				
Ronquillo, Ruben		PURCHASE 2EA. LINE LOCATORS. THANK YOU!							
Ruben Ronquillo									
113750					2/25/2014		41		\$0.00
Medium	Work In Progress				2/25/2014 8:56:19 AM				
Munoz, Michael		purchase tv for new conference/training/lounge.							
Michael Munoz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
114706					3/17/2014		21		\$0.00
Medium	Work In Progress			3/17/2014 2:19:13 PM					
Gonzalez, Salvador	the wastewater treatment plant at the PPD Gonna need some custom welding on Aluminum surface area in the context chamber								
Mario Apodaca									
111444					12/19/2013		109		\$0.00
Medium	Work In Progress			12/19/2013 2:56:01 PM					
Gonzalez, Salvador	fence behind ppd barracks is down. please install poles to fence for temporary repair. thank you								
Michael Munoz									
109287					10/24/2013		165		\$0.00
Medium	Work In Progress			10/24/2013 10:47:27					
Gonzalez, Salvador	old blue trailer. please raise the sides for scrap metal. see mike for details. thank you								
Michael Munoz									
114530					3/11/2014		27		\$0.00
Medium	Work In Progress			3/11/2014 4:04:58 PM					
Gonzalez, Salvador	please make pole hangers for ppd banner. please see mike for details. thank you								
Michael Munoz									
115617					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:32:09 AM					
Diaz, Sebastian	Monthly - Physical Plant FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
113297					2/11/2014		55		\$0.00
Medium	Work In Progress			2/11/2014 4:18:10 PM					
Marquez, Gerardo	New Lounge - Need to install doors in Heater & Pantry Closets.								
Michael Munoz									
114567					3/12/2014		26		\$0.00
Medium	Work In Progress			3/12/2014 2:46:44 PM					
Apodaca, Mario	need to order accessories truck 38 need a jobox ,ladder carrier and installed								
Mario Apodaca									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Physical Plant Complex							
115564					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:34 AM				
Carbajal, Jimmy	Monthly - Physical Plant - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
115209					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:23 AM				
Apodaca, Mario	Monthly - PPD/GHS - WW Monthly Sampling - Refer to PM schedule details.								
Margret Villalobos									
113676		Lift Station			2/21/2014		45		\$0.00
Medium	Work In Progress				2/21/2014 3:53:57 PM				
Ronquillo, Ruben	need to sign 4 wastewater treatment plant at the PPD Facility That reads gadaden Independent School District wastewater treatment plant								
Mario Apodaca									
Count: 74 Work Orders		Avg. Age of WO's	52	Total for Physical Plant Complex				0	\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
113362					2/13/2014		53		\$0.00
Medium	Work In Progress				2/13/2014 8:16:43 AM				
Holguin, Alfredo		Riverside Elementary has four sand playgrounds. North side has three. 1 is 3149 sq ft. Another is 2760 sq ft. The third is 4545 sq ft. Those are all on North side playground. South side has one sand playground with a sq footage of 11,200 sq feet.							
Mario Martinez									
115618					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:10 AM				
Martinez, Mario		Monthly - Riverside ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
115275		Classroom			3/31/2014		7		\$0.00
Medium	Work In Progress	6th grade blg			3/31/2014 4:48:05 PM				
Gonzales, Camilo		we need 200 student high-pressure laminate Fusion maple top front desks (Navarro)							
Rosa Quezada									
115650					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:30 AM				
Orozco, Daniel		Monthly - Riverside ES Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									
115098					3/27/2014		11		\$0.00
Medium	Work In Progress				3/27/2014 7:17:03 AM				
Carrasco, Danny		To Danny C. or Ruben R. Need 12 gallon containers filled for 2 weed eaters, 2 blowers, and for riding lawn mower. Thanks.							
Mario Martinez									
115444	Main Building	Custodial			4/4/2014		3		\$0.00
Medium	Work In Progress				4/4/2014 11:30:34 AM				
Carbajal, Jimmy		Jimmyel dolly se le salio una rueda, ahi si por favor nos lo puede arreglar ,muchas gracias.							
Miguel Sonora									
105474	Main Building				8/6/2013		244		\$0.00
Medium	Work In Progress				8/6/2013 10:08:22 AM				
Martinez, Mario		bathrooms and main hallways need painting (navarro)				4/4/14-Route to Mario			
Rosa Quezada									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
108675	Main Building	Restroom			10/10/2013		179		\$0.00
Medium	Work In Progress	RESTROOM			10/10/2013 10:21:47				
Ambriz, Jose		VENT IN MAIN OFFICE RESTROOM IS NOT WORKING							
Rosa Quezada									
109972	Main Building	Parking Lot			11/6/2013		152		\$0.00
Medium	Work In Progress				11/6/2013 12:30:33 PM				
Ontiveros, Joe		Joe, por favor si nos podia revisar la toma de el agua que esta afuera de la area de kinder para enfrente de la Macnutt, porque necesitamos lavar la entrada y no tiene agua muchas gracias.+							
Miguel Sonora									
115295					4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 1:30:12 PM				
Ontiveros, Joe		Need plumber Joe O. to repair Kohler one piece toilet flush valve and flapper in room 114. Joe if you have an extra flush valve and flapper I would like to have one for in the future.							
Mario Martinez									
113114					2/7/2014		59		\$0.00
Medium	Work In Progress				2/7/2014 7:56:35 AM				
Castillo, Carlos		Need Carlos C. to replace or repair light fixtures in rooms 116/117/121/123/137/148, also in music portable and art portable.							
Mario Martinez									
111430		Electrical Room			12/19/2013		109		\$0.00
Medium	Work In Progress				12/19/2013 9:20:46 AM				
Castillo, Carlos		Annual electrical equipment inspection.							
Carlos Castillo									
112046					1/14/2014		83		\$0.00
Medium	Work In Progress				1/14/2014 7:22:53 AM				
Castillo, Carlos		Need lights at Southwest portables fixed.				2/26 -Reroute to Cali			
Mario Martinez									
115245					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 3:14:41 PM				
Castillo, Carlos		please meet with Ben Rosey to discuss electrical at site (11:00 am)							
Alfredo Holguin									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
115154					3/28/2014		10		\$0.00
Medium	Work In Progress			3/28/2014 7:29:56 AM					
Castillo, Carlos	Need Carlos C. to check on several bad electrical outlets in hallways.								
Mario Martinez									
113206					2/10/2014		56		\$0.00
Medium	Work In Progress			2/10/2014 12:57:10 PM					
Villalobos, David	On 2/06/2014 Horizon Mechanical came by to work on backflow but were not able to repair it due to not having the repair kit needed. Will return 7 to 10 days later to fix it. Attention David Villalobos.								
Mario Martinez									
110787					12/3/2013		125		\$0.00
Medium	Work In Progress			12/3/2013 2:41:42 PM					
Villalobos, David	please check backflow preventers. as per Mario one is leaking every 3 minutes. thankyou		3/7-Route to David						
Michael Munoz									
111488					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress			1/5/2014 12:23:22 AM					
Villalobos, David	Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
115475					4/6/2014		1		\$0.00
Medium	Work In Progress			4/6/2014 12:30:20 AM					
Martinez, Mario	Yearly - Riverside ES A-13 A/C Wall Mount Yearly - Refer to PM schedule details.								
Margret Villalobos									
113921					2/28/2014	3/31/2014	38		\$0.00
Medium	Work In Progress			2/28/2014 12:32:48 AM					
Martinez, Mario	Yearly - Riverside ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									
114160					3/3/2014		35		\$0.00
Medium	Work In Progress			3/3/2014 3:20:58 PM					
Ambriz, Jose	Need Jose Ambriz to repair leaking gasket on on heating valve at mechanical room next to sixth grade wing.								
Mario Martinez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
115384					4/3/2014		4		\$0.00
Medium	Work In Progress			4/3/2014 8:29:33 AM					
Ambriz, Jose	as per mike munoz need to mark a/c units that are good and bad before contractors remove units								
Mario Martinez									
115339					4/2/2014		5		\$0.00
Medium	Work In Progress			4/2/2014 7:13:15 AM					
Lara, Ralph	Need Rafa L. to work on EAST side main entrance door and key.								
Mario Martinez									
115370					4/2/2014		5		\$0.00
Medium	Work In Progress			4/2/2014 3:47:24 PM					
Martinez, Mario	4/02/2014.					4/2-8			
	1 hr open gates, walk through campus, pick up trash, and monitor school bus drop off.								
	6 hrs complete A/C start up on north wing. Need to replace 1 A/C motor which has only low speed. Room #41.								
	1 hr pick up clean up and log in work day.								
Mario Martinez									
109227					10/23/2013		166		\$0.00
Medium	Work In Progress			10/23/2013 9:43:53 AM					
Martinez, Mario	please cut weeds and clean area where mobile home used to be. In the fenced area and surrounding areas as well. thank you					4/4/14 - Routed to Mario			
Michael Munoz									
114384		Athletic Field			3/7/2014		31		\$0.00
Medium	Work In Progress			3/7/2014 2:48:40 PM					
Martinez, Mario	Need to repair broken, and missing sprinkler heads and sprinkler lines.								
Mario Martinez									
112541					1/28/2014		69		\$0.00
Medium	Work In Progress			1/28/2014 3:20:59 PM					
Flores, Pete	Attention, Pete Flores would like your assistance on blades and belts adjustments on John Deere LA 125 riding mower.								
Mario Martinez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
115515					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:53 AM				
Martinez, Mario		Monthly - Riverside ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
110138					11/12/2013		146		\$0.00
Medium	Work In Progress				11/12/2013 2:53:05 PM				
Ontiveros, Guadalupe		Pine tress on south side next to playground. Need to check irrigation system, trees are dead or dying.							
Alfredo Holguin									
110158					11/12/2013		146		\$0.00
Medium	Work In Progress				11/12/2013 4:02:42 PM				
Ontiveros, Guadalupe		replace damaged soccer goal was hit by a car.							
Alfredo Holguin									
115532					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:11 AM				
Martinez, Mario		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115531					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:10 AM				
Martinez, Mario		Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
113115					2/7/2014		59		\$0.00
Medium	Work In Progress				2/7/2014 8:06:31 AM				
Martinez, Mario		Need to change out florescent lighting through out entire South and Middle wings, Computer lab, and main office. North wing completed on 2/06/14.							
Mario Martinez									
113499					2/18/2014		48		\$0.00
Medium	Work In Progress				2/18/2014 3:30:44 PM				
Martinez, Mario		Need to purchase and install 25 window blinds. Color and size on request. 10 42 inch X 80 inch, 10 24inch X 80 inch, 4 24 inch X 64 inch, and 1 72 inch X 80 inch.							
Mario Martinez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Riverside ES							
113382					2/13/2014		53		\$0.00
Medium	Work In Progress				2/13/2014 2:43:44 PM				
Martinez, Mario	Need to fill in broken 6 inch red tiles with concrete.								
Mario Martinez									
Count: 35 Work Orders		Avg. Age of WO's 57			Total for Riverside ES			0	\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: RTC - Alliance									
115107		Classroom			3/27/2014		11		\$0.00
Medium	Work In Progress				3/27/2014 11:14:10 AM				
Moncayo, Fernando		repair classroom wall by the entrance (student punched the wall as he was exiting)							
Gloria Delgado									
112426		Classroom			1/24/2014		73		\$0.00
Medium	Work In Progress				1/24/2014 8:30:33 AM				
Moncayo, Fernando		the rooms and office need filters replace							
Gloria Delgado									
112166		Classroom			1/15/2014		82		\$0.00
Medium	Work In Progress				1/15/2014 4:13:38 PM				
Moncayo, Fernando		we need doorstops on all portable and to clean grounds							
Gloria Delgado									
113600		Classroom			2/20/2014		46		\$0.00
Medium	Work In Progress				2/20/2014 2:14:57 PM				
Moncayo, Fernando		Please replace air filters and if possible air ducts cleaned.							
Gloria Delgado									
Count: 4 Work Orders			Avg. Age of WO's	53		Total for RTC - Alliance	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: San Miguel ES									
115327		Cafeteria			4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 3:59:45 PM				
Vega, Danny	1/2 of dining area will be getting flooring along with stage and the restrooms. please remove the partitions for flooring and paint restrooms. please call mike for date. (tentative the week after spring break, floor will go in) call mike for details. thank you								
Michael Munoz									
111490					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:23 AM				
Villalobos, David	Yearly - San Miguel ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
115329		Cafeteria			4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 4:01:43 PM				
Vega, David	please remove commodes as discussed for new flooring. please call mike for date of floor installation. thank you								
Michael Munoz									
114897		Cafeteria			3/21/2014		17		\$0.00
High	Work In Progress				3/21/2014 9:47:22 AM				
Munoz, Michael	need to install new flooring in the dining, stage and restrooms.								
Alfredo Holguin									
114106					3/2/2014		36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:50 AM				
Apodaca, Mario	Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
115605					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:01 AM				
Apodaca, Mario	Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 6 Work Orders			Avg. Age of WO's	26		Total for San Miguel ES	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
115651					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:31 AM				
Orozco, Daniel		Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
115622					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:12 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
111841	Main Building	Hallway/Corridor			1/9/2014		88		\$0.00
Medium	Work In Progress	200 hallway			1/9/2014 3:04:10 PM				
Ontiveros, Joe		Need to repair leak in 2 1/2" main domestic water							
Juan Ambriz									
109418	Main Building	Classroom			10/28/2013		161		\$0.00
Medium	Work In Progress	Room #206			10/28/2013 2:05:48 PM				
Ambriz, Jose		Need to check a/c unit in room #206 not working properly							
Juan Ambriz									
113780	Main Building	Classroom			2/25/2014		41		\$0.00
Medium	Work In Progress				2/25/2014 2:50:23 PM				
Ambriz, Jose		Need to check heating unit in room #103 motor making noise							
Juan Ambriz									
115025	Main Building	Parking Lot			3/25/2014		13		\$0.00
Medium	Work In Progress				3/25/2014 2:53:57 PM				
Ambriz, Juan		As per Mrs. Tarin need to paint car stoppers in parking lot							
Juan Ambriz									
106980	Main Building	Classroom			9/3/2013		216		\$0.00
Medium	Work In Progress	Room 303			9/3/2013 8:48:32 AM				
Ambriz, Jose		Need HVAC TECH to check a/c unit in room #303 not cooling							
Juan Ambriz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa ES							
112234	Main Building	Parking Lot			1/17/2014		80		\$0.00
Medium	Work In Progress	Student Pick			1/17/2014 12:56:02 PM				
Gonzalez, Salvador		The school needs a metal shade frame to be located at the student drop off/pick up area. Thank you.							
Rita Mendez									
112574	Main Building	Exterior			1/29/2014		68		\$0.00
Medium	Work In Progress	Basketball			1/29/2014 8:24:37 AM				
Ambriz, Juan		Need to cover cracks on cement on basketball courts							
Juan Ambriz									
114367	Main Building	Football Field			3/7/2014		31		\$0.00
Medium	Work In Progress	all playground			3/7/2014 8:25:35 AM				
Ambriz, Juan		Need to fertilize back field							
Juan Ambriz									
114215	Main Building	Cafeteria			3/4/2014		34		\$0.00
Medium	Work In Progress	kitchen			3/4/2014 12:39:16 PM				
Ambriz, Juan		Need to install shelves in kitchen office							
Juan Ambriz									
115116	Main Building	Office			3/27/2014		11		\$0.00
Medium	Work In Progress				3/27/2014 2:17:17 PM				
Ambriz, Juan		As per Mrs. Tarin need to install blinds in front office							
Juan Ambriz									
115117	Main Building	Restroom			3/27/2014		11		\$0.00
Medium	Work In Progress	adult 100			3/27/2014 2:34:25 PM				
Ambriz, Juan		Need to replace doughnut on toilet							
Juan Ambriz									
115406	Main Building	Classroom			4/3/2014		4		\$0.00
Medium	Work In Progress	Room #302			4/3/2014 2:55:34 PM				
Ambriz, Juan		Need to replace broken soap dispenser in room # 301							
Juan Ambriz									
115026	Main Building	Classroom			3/25/2014		13		\$0.00
Medium	Work In Progress				3/25/2014 2:55:13 PM				
Ambriz, Juan		Need to assemble shelves for room #108							
Juan Ambriz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

113386 Main Building Parking Lot 2/13/2014 53 \$0.00

Medium Work In Progress front gates 2/13/2014 2:56:50 PM

Ambriz, Juan Need to replace wheels on all gates. Hard to open

Juan Ambriz

113441 Main Building Exterior 2/14/2014 52 \$0.00

Medium Work In Progress Playgrounds 2/14/2014 3:25:01 PM

Holguin, Alfredo As per Alfredo playground sand needs to be removed and replaced with Engineered wood fibers, 2 playgrounds and a total of 41 borders

Juan Ambriz

111494 1/5/2014 2/5/2014 92 \$0.00

Medium Work In Progress 1/5/2014 12:23:25 AM

Villalobos, David Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

115229 3/31/2014 7 \$0.00

Medium Work In Progress LINE LOCATE 3/31/2014 10:51:21 AM

Castillo, Carlos Need to line locate at the parent pickup turnaround area will be marked white.

Salvador Gonzalez

115228 3/31/2014 7 \$0.00

Medium Work In Progress LINE LOCATE 3/31/2014 10:49:41 AM

Ontiveros, Joe Need to line locate at the parent pickup turnaround area will be marked white.

Salvador Gonzalez

114592 3/13/2014 25 \$0.00

Medium Work In Progress 3/13/2014 9:43:14 AM

Ontiveros, Guadalupe Asprinkler head is leaking by the basketball courts.

114006 3/2/2014 36 \$0.00

Medium Work In Progress 3/2/2014 12:26:02 AM

Ambriz, Juan Yearly - Santa Teresa ES A-10 HEAT PUMPS (ANNUAL) - Refer to PM schedule details.

Margret Villalobos

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
115199					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:14 AM				
Ambriz, Juan		Monthly - Santa Teresa ES-A-16 Fan Exhaust (SemiA) - Refer to PMschedule details.							
Margret Villalobos									
115547					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:23 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
115548					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:23 AM				
Ambriz, Juan		Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
115546					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:22 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
115511					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:50 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Roof Inspection - Refer to PMschedule details.							
Margret Villalobos									
Count: 27 Work Orders			Avg. Age of WO's	39		Total for Santa Teresa ES	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

115503 4/6/2014 4/14/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:30:43 AM

Escobar, David Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.

Margret Villalobos

113531 2/19/2014 47 \$0.00

Medium Work In Progress 2/19/2014 9:18:29 AM

Flores, Pete hey Pete I'm trying to touch base as to getting a new windshield on my work truck. its been severely cracked since I received it and needs to be replaced. Thank you.

David Escobar

112962 Athletic Field 2/4/2014 62 \$0.00

Medium Work In Progress 2/4/2014 3:22:07 PM

Ontiveros, Guadalupe as per conversation, please laydown compost on the southeast corner of baseball field by marquee. thank you

Michael Munoz

114689 3/17/2014 21 \$0.00

Medium Work In Progress 3/17/2014 9:57:31 AM

Holguin, Isaac Hello Maritza,

I need to place a work order for a cleaned up the kitchen floors on 04/07/2013.

Thank you!!!

Olga B, SNP Manager 882.5332

Maritza Gonzalez

106327 8/21/2013 229 \$0.00

Medium Work In Progress 8/21/2013 9:56:59 AM

Holguin, Alfredo Attn: Alfredo Holguin. Roof goose neck vents in old main bldg areas total of 18 count from 12", 24" and 36". These vents are causing roof leaks and ceiling tile damage which produces mold on tiles. Several of the dampers are not functional, screens are detached or torn. One of the problems weve had is cats going into the building and also accessible to intruders breaking in. I viewed the additions to the building and they have a newer and better vent design with a cap on top for better rain water protection and intruder protection. Let me know if you need more information.

Jaime Mijarez

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

113197 Gym 2/10/2014 56 \$0.00

Medium Work In Progress 2/10/2014 11:15:16 AM

Munoz, Michael
New Gym Lobby concession stand. (Please give w/o to Mike Munoz and a copy to Alfredo H). Can we have a new candy/snack shelve built and installed in the new concession stand. I spoke to Mrs. Harper and told her that I would get with Mike and Alfredo and see if we could go that route instead of having to sand and repainting the old gym concession stand wooden shelve that we installed. Please call me for more info.

Jaime Mijarez

111325 12/16/2013 112 \$0.00

Medium Work In Progress 12/16/2013 4:00:06 PM

Munoz, Michael
Old gym bleachers. Please give work order to (Alfredo H.) I spoke to him. Wood swinging boards that run along the bottom of the bleachers are missing several pins on the hindges, The boards are uneven and won't stay flush with each other. I don't know when was the last time they were serviced.
3/26/14
Margret I believe Mike will be addressing this with AK Sales Please reassign WO asp A. Holguin.

Jaime Mijarez

110332 11/16/2013 142 \$0.00

Medium Work In Progress 11/16/2013 12:18:10

Flores, Pete
Yearly - Santa Teresa HS - Mower 0425 - Grounds - Refer to PM schedule details.

Margret Villalobos

115565 4/6/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:31:35 AM

Mijarez, Jaime
Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

115673 4/7/2014 0 \$0.00

Medium Work In Progress 4/7/2014 7:46:11 AM

Ronquillo, Ruben
Main entrance to the library exterior windows. Students broke a window, i covered it up. Please send glass company to repair.

Jaime Mijarez

107284 Library 9/10/2013 209 \$0.00

Medium Work In Progress 9/10/2013 8:38:41 AM

Mijarez, Jaime
Library - The security mirror in the back of the library needs to be hung.

William Dickson

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
114596					3/13/2014		25		\$0.00
Medium	Work In Progress				3/13/2014 10:52:45 AM				
Carrasco, Danny		I have no T5 light bulbs and I need to replace a few bulbs in the culinary arts kitchen. I think 2 boxes of T5 bulbs will be more than enough for the repair.							
David Escobar									
115328		Kitchen			4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 4:01:26 PM				
Escobar, David		Fix 3 back legs on table that holds the 2 grills they are to heavy							
William Dickson									
115330		Kitchen			4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 4:03:11 PM				
Escobar, David		CulinaryArts re-install shelf in pantry							
William Dickson									
108658		Kitchen			10/9/2013		180		\$0.00
Medium	Work In Progress				10/9/2013 10:09:06 PM				
Escobar, David		CulinaryArts Kitchen needs the can opener attached to the table.				3/28/14 Asp Jaime, David E. is working on this, waiting on parts			
William Dickson									
115578					4/6/2014	5/7/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:44 AM				
Escobar, David		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
115576					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:43 AM				
Escobar, David		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
115577					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:43 AM				
Escobar, David		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

112770 2/2/2014 3/5/2014 64 \$0.00

Medium Work In Progress 2/2/2014 12:26:05 AM

Escobar, David Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

113631 2/20/2014 46 \$0.00

Medium Work In Progress 2/20/2014 4:01:52 PM

Carrasco, Danny Please order mini blinds on list so that we can install on classroom windows through out the buildings.

Jaime Mijarez

115401 Classroom 4/3/2014 4 4 \$0.00

Medium Work In Progress VARIOUS 4/3/2014 11:55:21 AM

Escobar, David INSTALL BRACKETS AND NM FLAGS AND US FLAGS IN CLASSROOMS. PLEASE SEE MARYLOU FOR LIST OF CLASSROOMS.

Marylou Jimenez

112662 1/30/2014 67 \$0.00

Medium Work In Progress 1/30/2014 3:19:19 PM

Mijarez, Jaime Marylou Jimenez is requesting paint for the vault door in her office.

Jaime Mijarez

106495 8/26/2013 224 \$0.00

Medium Work In Progress 8/26/2013 9:08:31 AM

Ambriz, Jose Room 203. Slave fan coil unit has a noisy squerrel cage. I had to shutdown unit through tracer summit so it won't disrupt the classroom.

Jaime Mijarez

115288 4/1/2014 6 \$0.00

Medium Work In Progress 4/1/2014 9:29:06 AM

Ambriz, Jose Attn; Joe the water heater circulating pump that sends hot water to the special ed classroom gave out. I gave Ruben the info on the pump. I need your help so we can do the repair soon. Thanks.

Jaime Mijarez

113916 2/28/2014 3/31/2014 38 \$0.00

Medium Work In Progress 2/28/2014 12:32:46 AM

Escobar, David Yearly - Santa Teresa HS C-11 Evap Coolers Yearly - Refer to PM schedule details.

Margret Villalobos

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

115491 4/6/2014 4/27/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:30:34 AM

Escobar, David Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PMschedule details.

Margret Villalobos

115490 4/6/2014 4/27/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:30:33 AM

Escobar, David Monthly - Santa Teresa HS C-12 Chm Feeder Semimty - Refer to PMschedule details.

Margret Villalobos

114549 3/12/2014 26 \$0.00

Medium Work In Progress 3/12/2014 8:36:05 AM

Ontiveros, Guadalupe Gilbert Bailon/Baseball field. Need new bases. The ones we have are old and worn out. Last game one of our players twisted his ankles.

Jaime Mijarez

114891 3/21/2014 17 \$0.00

Medium Work In Progress 3/21/2014 8:42:39 AM

Ontiveros, Guadalupe Will need to transport lift from Sta.Teresa Hi to the Gac.I will give you advance notice when we are ready for transport.

Carlos Castillo

115236 3/31/2014 7 \$0.00

Medium Work In Progress 3/31/2014 12:31:54 PM

Lara, Ralph We are having trouble with the lock in the culinary kitchen. Teacher has gotten her key stuck in the lock. Please have rafa come by to adjust or fix the lock.

William Dickson

115498 4/6/2014 4/22/2014 1 \$0.00

Medium Work In Progress 4/6/2014 12:30:39 AM

Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PMschedule details. Emailed 4/7/14

Margret Villalobos

111713 1/7/2014 90 \$0.00

Medium Work In Progress LINE LOCATE 1/7/2014 8:25:58 AM

Sotelo, Enrique Lynco will be drilling at Santa Teresa on Tuesday, 01/14/2014 and will need utilities located. They have the piers marked on the ground and will need your district to locate any utilities underground at these locations.

Rafael Gallegos

4/7/2014 2:48:58 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
114948					3/24/2014		14		\$0.00
Medium	Work In Progress				3/24/2014 11:12:07 AM				
Castillo, Carlos		Request by Rick Llanez. Please repair lighting at grounds shop.							
Jaime Mijarez									
114982					3/25/2014		13		\$0.00
Medium	Work In Progress				3/25/2014 6:56:29 AM				
Castillo, Carlos		Counciling center/Requested by Mrs. Rodriguez. Will need more recepticles for 10 computers to be installed against the wall including copy machine's that are already connected by the same wall.							
Jaime Mijarez									
115223					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 9:18:04 AM				
Castillo, Carlos		Mr. Dots on. Several lights need to be replaced and one of the basketball courts is not raising up from the new gym.							
Jaime Mijarez									
115112		Gym			3/27/2014		11		\$0.00
Medium	Work In Progress	COACH TROY			3/27/2014 1:57:19 PM				
Castillo, Carlos		REMOVE BROKEN ELECTRICAL PLUG FROM OUTLET LOCATED IN WRESTLING ROOM.							
Marylou Jimenez									
111353		Parking Lot			12/17/2013		111		\$0.00
Medium	Work In Progress				12/17/2013 10:38:20				
Castillo, Carlos		Some of the parking light lites are not working. Needs attention because it is very dark at night in some spots.							
William Dickson									
109208					10/22/2013		167		\$0.00
Medium	Work In Progress				10/22/2013 3:45:56 PM				
Castillo, Carlos		Main entrance hallway. All the ivory light switches need to be replaced they are broken and are not working properly. Please check with me (Jaime).							
Jaime Mijarez									
115324		Kitchen			4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 3:59:29 PM				
Castillo, Carlos		Culinary Arts kitchen bottom conversion oven quit (Check Breakers)							
William Dickson									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
113018					2/5/2014		61		\$0.00
Medium	Work In Progress				2/5/2014 11:13:13 AM				
Mijarez, Jaime		Councilors and 700 wing heating units. Please order 10 ea. fan/limit combo controls. We need 4 and the other 6 will stay with Joe and Lorenzo. Renznor HU.							
Jaime Mijarez									
115198					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:13 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.							
Margret Villalobos									
111492					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:24 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
115470					4/6/2014	4/9/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:16 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.							
Margret Villalobos									
114610		Exterior			3/13/2014		25		\$0.00
Medium	Work In Progress				3/13/2014 1:55:24 PM				
Ontiveros, Joe		Over by our marque there is a sewer smell that is really getting bad. This looks like what was happening over by the baseball field. Need to get the city out here to pump out the system.							
William Dickson									
111738					1/7/2014		90		\$0.00
Medium	Work In Progress				1/7/2014 2:48:17 PM				
Ontiveros, Joe		Cafeteria kitchen could not locate a shut off water valve for 3/8 water line to make up air system for kitchen hood. Will need to install a shut off valve. Water line burst during holiday break and couldn't shut off water due to no shut off valve present.							
David Escobar									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
110010					11/7/2013		151		\$0.00
Medium	Work In Progress				11/7/2013 8:07:10 AM				
Ontiveros, Joe		Gas line outside by 300 wing boiler room is cracked. Needs to be repaired before we get colder weather. Gas line supplies to the 300 wing hydraunic heating system boiler.							
Jaime Mijarez									
109618	Main Building	Classroom			11/1/2013		157		\$0.00
Medium	Work In Progress	406, 410, 402,			11/1/2013 10:48:10 AM				
Mijarez, Jaime		These classrooms received smart boards. The walls need to be painted where old chalkboards were removed.							
Kathryn Harper									
106456	Main Building	Classroom			8/23/2013		227		\$0.00
Medium	Work In Progress	203			8/23/2013 10:56:44 AM				
Ambriz, Jose		The A/C in room 203 is VERY loud!. Teacher has to speak loudly and it's hard to students to hear. Please make this a priority. Thanks.							
Kathryn Harper									
110077	Main Building	Mechanical			11/8/2013		150		\$0.00
Medium	Work In Progress				11/8/2013 3:38:05 PM				
Ontiveros, Joe		Need to Replaces 1 inch Gas Riser rusted out outside boiler RM.							
Joe Ontiveros									
115294	Main Building	Restroom (Girls)			4/1/2014		6		\$0.00
Medium	Work In Progress				4/1/2014 12:30:38 PM				
Ontiveros, Joe		main hallway near library girls restroom last stall not working							
Isaac Holguin									
113371	Main Building	Classroom			2/13/2014		53		\$0.00
Medium	Work In Progress	200 -700			2/13/2014 10:58:52 AM				
Escobar, David		Replace mini blinds in 15 classrooms as needed Paint the classrooms that had smartboards installed							
Kathryn Harper									
106578	Main Building	Classroom			8/27/2013		223		\$0.00
Medium	Work In Progress	band room			8/27/2013 1:36:28 PM				
Escobar, David		Right outside band room, there's a hole in the wall				2/20/14 - Asp Mike, route to David			
Kathryn Harper									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
115341	Main Building	Classroom			4/2/2014		5		\$0.00
Medium	Work In Progress			4/2/2014 8:18:39 AM					
Mijarez, Jaime	Room 600 has a exposed broken plug creating a safety issue. Please check it out and fix. Thanks!								
William Dickson									
107779	Main Building	Computer Lab			9/20/2013		199		\$0.00
Medium	Work In Progress			9/20/2013 4:59:04 PM					
Mijarez, Jaime	Relocate a white board so students can review their work.								
William Dickson									
107780	Main Building	Computer Lab			9/20/2013		199		\$0.00
Medium	Work In Progress			9/20/2013 5:03:05 PM					
Mijarez, Jaime	The classroom that needed the white board moved is C2								
William Dickson									
114609	Gymnasium	Hallway/Corridor			3/13/2014		25		\$0.00
Medium	Work In Progress			3/13/2014 1:53:09 PM					
Mijarez, Jaime	There is a tile next to the concession stand in the gym that has been broken. Need to get it replaced please.								
William Dickson									
111874	Vocational	Classroom			1/9/2014		88		\$0.00
Medium	Work In Progress			1/9/2014 10:47:57 PM					
Mijarez, Jaime	The kids in studio to cook ceramic is not working. One braked in the box is taped. Please check it out. Thanks.								
William Dickson									
111875	Vocational	Classroom			1/9/2014		88		\$0.00
Medium	Work In Progress			1/9/2014 10:51:22 PM					
Mijarez, Jaime	Heat will not come on in the clayshop. Need paper dispenser added to sink area. Room is covered with spider webs may have a black widow in the area. Please check out.								
William Dickson									
111903	Vocational				1/10/2014		87		\$0.00
Medium	Work In Progress			1/10/2014 1:40:49 PM					
Gonzalez, Salvador	Cover small windows on doors that vandals have used to gain access into rooms with expanded metal. Check with site administration or security Tellez for specifics.								
Alfredo Holguin									
4/7/2014 2:48:58 PM									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
111904	Library				1/10/2014		87		\$0.00
Medium	Work In Progress				1/10/2014 1:41:56 PM				
Lara, Ralph		Alarm buzzer on Emergency Egress doors are not working							
Alfredo Holguin									
107313	Library	Library			9/10/2013		209		\$0.00
Medium	Work In Progress	Library			9/10/2013 3:37:35 PM				
Mijarez, Jaime		Put pictures of Classes in library on wall.							
Kathryn Harper									
115060	Annex Building				3/26/2014		12		\$0.00
Medium	Work In Progress				3/26/2014 10:35:47 AM				
Mijarez, Jaime		The concrete by the steps needs to be reinforced. It poses a danger to staff and students when they use the side walk.							
William Dickson									
115062	Annex Building				3/26/2014		12		\$0.00
Medium	Work In Progress				3/26/2014 10:47:50 AM				
Lara, Ralph		Door locks need to be replaced in bathroom, replace lock or make key for cabinet #8 on counter desk, Repair handle for file cabinet, Raise desk top computer, move mirror forward, replace carpet with tile, all of this is in the Nurse's office.							
William Dickson									
115340	Main Building	Classroom			4/2/2014		5		\$0.00
Medium	Work In Progress				4/2/2014 8:16:40 AM				
Ambriz, Jose		Teacher in room 307 is complaining about the heat in the classroom in the afternoon. She claims the air condition does not function correctly. It throws out hot air.							
William Dickson									
109502	Main Building	Classroom			10/29/2013		160		\$0.00
Medium	Work In Progress				10/29/2013 4:13:17 PM				
Mijarez, Jaime		Room 215 needs two broom holders mounted on the left wall after entering the front door, a pattern is taped to the wall where the holder is to be placed. The hardware is taped to the pattern. The other broom holder pattern is taped on the wall in the storage closet.							
William Dickson									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

106125	Locker Room	Gym			8/16/2013		234		\$0.00
--------	-------------	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Pe locker room			8/16/2013 8:25:08 AM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Gonzalez, Salvador
Removal of bent or broken locker doors in PE boys dressing room.

Kathryn Harper

114446	Locker Room				3/10/2014		28		\$0.00
--------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2014 2:25:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
The restroom doors boys and girls are having a hard time opening. The key does not work. These are the hallways leading to Dotson's office.

William Dickson

114448	Locker Room	Dressing Room			3/10/2014		28		\$0.00
--------	-------------	---------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2014 2:34:38 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
The girls locker room leading out to the football has a bad cylinder and it does not open well. Need attention.

William Dickson

114503	Locker Room	Office			3/11/2014		27		\$0.00
--------	-------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2014 2:50:04 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
Football locker - install locker clasp to 8 lockers with a blue X on it. Lock mechanism.

William Dickson

114502	Locker Room	Office			3/11/2014		27		\$0.00
--------	-------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2014 2:32:57 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Escobar, David
Football locker room missing ceiling tiles. Need to get the projector screen screen put up. Fix broken shower tiles.

William Dickson

108549	Cafeteria (2005)	Restroom			10/7/2013		182		\$0.00
--------	------------------	----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/7/2013 7:45:26 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime
The restroom in the cafeteria needs a paper dispenser. The one that was there is broken.

William Dickson

106341	GYM (2009)	Gym			8/21/2013		229		\$0.00
--------	------------	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Basketball gym			8/21/2013 11:22:54 AM				
--------	------------------	----------------	--	--	-----------------------	--	--	--	--

Mijarez, Jaime
Foam rubber edging around basketball backboards in both gyms coming off, needs to be replaced/repared (see Coach Haack or Coach Dotson)

Kathryn Harper

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
115287	GYM (2009)				4/1/2014		6		\$0.00
Medium	Work In Progress			4/1/2014 8:50:19 AM					
Carrasco, Danny	W.O.#115223 Need scissor lift transported to STa.Teresa Hi. ASAP								
Carlos Castillo									
113247	GYM (2009)	Storage			2/10/2014		56		\$0.00
Medium	Work In Progress			2/10/2014 10:29:36 PM					
Ontiveros, Guadalupe	need to move the metal storage from the storage room to the old concession stands.								
William Dickson									
113248		Exterior			2/10/2014		56		\$0.00
Medium	Work In Progress			2/10/2014 10:32:42 PM					
Gonzalez, Salvador	The fence behind the vocational room needs repair. As a matter of fact the entire fence row needs attention. There are several holes in it.								
William Dickson									
115621					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:32:12 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
115652					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:32:32 AM					
Orozco, Daniel	Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
105592					8/7/2013		243		\$0.00
Medium	Work In Progress			8/7/2013 12:52:27 PM					
Mijarez, Jaime	Asp inspection on PM Fire Sprinkler by Dimar the following was found: FDC missing cap								
Michael Munoz									
111909					1/10/2014		87		\$0.00
Medium	Work In Progress			1/10/2014 2:26:29 PM					
Mijarez, Jaime	Asp PM serviced by Dimar - need to add oil and rotate FDC.								
Michael Munoz									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
111913					1/10/2014		87		\$0.00
Medium	Work In Progress				1/10/2014 2:30:03 PM				
Mijarez, Jaime		Asp PM serviced by Dimar - FAC cap missing in 200 Wing							
Michael Munoz									
111914					1/10/2014		87		\$0.00
Medium	Work In Progress				1/10/2014 2:30:43 PM				
Mijarez, Jaime		Asp PM serviced by Dimar - FAC cap missing in 300 Wing							
Michael Munoz									
115663					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:39 AM				
Munoz, Michael		Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
114932		Gym			3/21/2014		17		\$0.00
Medium	Work In Progress				3/21/2014 4:17:38 PM				
Munoz, Michael		PM - Annual Bleacher Service performed by A.K. Sales.							
Michael Munoz									
114100					3/2/2014		36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:48 AM				
Sanchez, Raul		Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PM schedule details.							
Margret Villalobos									
114686					3/17/2014		21		\$0.00
Medium	Work In Progress				3/17/2014 9:36:54 AM				
Orozco, Daniel		NO WATER IN BATHROOM SINK.SNP MANAGER OLGA B.							
Maritza Gonzalez									
113006					2/5/2014		61		\$0.00
Medium	Work In Progress				2/5/2014 9:15:29 AM				
Orozco, Daniel		BOTTOM SWITCH TO TURN OF DISHWASHER IS BROKEN-SNP MANAGER OLGA B.589.5332							
Maritza Gonzalez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
115243					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 2:57:44 PM				
Orozco, Daniel		FIRE CURTAINS WENT DOWN . SNP MANAGER OLGA B. 589.5332							
Maritza Gonzalez									
115244					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 3:10:34 PM				
Orozco, Daniel		AS PER MANAGER, PLEASE CHECK FLOOR IN FREEZER. SAFETY HAZARD. SNP MANAGER OLGA B. 589.5332.							
Maritza Gonzalez									
104626					7/23/2013		258		\$0.00
Medium	Work In Progress				7/23/2013 2:12:58 PM				
Mijarez, Jaime		Will need to replace ceiling tiles in several gym dressing rooms . Ceiling tile is a different texture can you please order 4 ea. Bundles of the sample that I gave you or at least match it.							
Jaime Mijarez									
108657		Kitchen			10/9/2013		180		\$0.00
Medium	Work In Progress				10/9/2013 10:07:49 PM				
Mijarez, Jaime		Culinary Arts Kitchen needs 2 leg table attached to the wall in dish room.							
William Dickson									
108659		Kitchen			10/9/2013		180		\$0.00
Medium	Work In Progress				10/9/2013 10:10:33 PM				
Mijarez, Jaime		Culinary Arts Kitchen attach self to the wall see teacher for directions							
William Dickson									
115400		Classroom			4/3/2014		4		\$0.00
Medium	Work In Progress	MRS.			4/3/2014 11:54:00 AM				
Mijarez, Jaime		I HAVE A COUPLE OF TILES COMING UNGLUED ON FLOOR. THIS IS A SPED CLASS AND HAZARDOUS TO STUDENTS.							
Marylou Jimenez									
Count: 92 Work Orders			Avg. Age of WO's 72			Total for Santa Teresa HS	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
114950					3/24/2014		14		\$0.00
Medium	Work In Progress	TR-STM-0783		3/24/2014 11:39:56 AM					
Rodriguez, Ismael	DELIVER NEW WHITE TRAILER WITH RAMP TO STMS CUTODIAL ISMAEL. THANK YOU!								
Ruben Ronquillo									
115616					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:32:08 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
115352					4/2/2014		5		\$0.00
Medium	Work In Progress			4/2/2014 1:51:14 PM					
Orozco, Daniel	LINES ON DISHWASHER IS LEAKING. SNP MANAGER GESSICA M. 589.9836								
Maritza Gonzalez									
114934		Gym			3/21/2014		17		\$0.00
Medium	Work In Progress			3/21/2014 4:19:40 PM					
Munoz, Michael	PM - Annual Bleacher Service performed by A.K. Sales.								
Michael Munoz									
115681	North Building	Classroom			4/7/2014		0		\$0.00
Medium	Work In Progress			4/7/2014 12:28:38 PM					
Lara, Ralph	Classroom #15 the cylinder is not locking needs replacement								
Ismael Rodriguez									
114497	North Building	Classroom			3/11/2014		27		\$0.00
Medium	Work In Progress			3/11/2014 11:30:19 AM					
Lara, Ralph	Rafa, classroom #9 the teacher needs a key for a file cabinet for testing materials .								
Ismael Rodriguez									
114426	North Building	Custodial			3/10/2014		28		\$0.00
Medium	Work In Progress			3/10/2014 8:11:37 AM					
Castillo, Carlos	Set the custodian morgan building with electricity for the Gator thanks.								
Ismael Rodriguez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
114427	North Building				3/10/2014		28		\$0.00
Medium	Work In Progress				3/10/2014 8:25:29 AM				
Ontiveros, Joe		As per Mr.Soria he needs the plumber to run water near his morgan.							
Ismael Rodriguez									
112960	North Building	Classroom			2/4/2014		62		\$0.00
Medium	Work In Progress				2/4/2014 1:56:28 PM				
Ontiveros, Joe		WE NEED TO REPLACE WATER FOUSET AND TRUMP ROOM 7.							
Manuel Prospero									
112443	North Building	Classroom			1/24/2014		73		\$0.00
Medium	Work In Progress				1/24/2014 12:40:37 PM				
Ontiveros, Joe		WE NEED TO CHANGED 6 WATER FOUSET ON ROOM 10 AND TRAMPS.							
Manuel Prospero									
111910	North Building	Classroom			1/10/2014		87		\$0.00
Medium	Work In Progress	20			1/10/2014 2:27:34 PM				
Ontiveros, Joe		LEAKY FAUCET							
Laura Parra									
115387	North Building	Football Field			4/3/2014		4		\$0.00
Medium	Work In Progress				4/3/2014 8:51:36 AM				
Ontiveros, Guadalupe		Lupe as per Mr.Soria he needs white paint to paint soccer goals.							
Ismael Rodriguez									
107746	North Building	Office			9/20/2013		199		\$0.00
Medium	Work In Progress	ROOM 8			9/20/2013 1:50:16 PM				
Marquez, Gerardo		NEED KEY FOR CABINET LOCATED OUTSIDE NURSES OFFICE							
Laura Parra									
112282	North Building	Portables			1/21/2014		76		\$0.00
Medium	Work In Progress				1/21/2014 11:15:26 AM				
Prospero, Manuel		Portable 2a the heater is not working properly need to be check.							
Ismael Rodriguez									
112528	North Building	Office			1/28/2014		69		\$0.00
Medium	Work In Progress	SEE MS			1/28/2014 2:28:39 PM				
Prospero, Manuel		PLEASE HANG ATHLETE FRAMES IN LOBBY AREA							
Laura Parra									
4/7/2014 2:48:58 PM									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
115051	North Building	Custodial			3/26/2014		12		\$0.00
Medium	Work In Progress				3/26/2014 7:39:18 AM				
Prospero, Manuel		Adjust water pressure in water fountain in cafeteria thank you..							
Ismael Rodriguez									
113250	North Building	Football Field			2/11/2014		55		\$0.00
Medium	Work In Progress				2/11/2014 8:19:14 AM				
Soria, Mike		Clean along the fence coming down the hill south building custodians are going to help.							
Ismael Rodriguez									
106730	South Building	Classroom			8/29/2013		221		\$0.00
Medium	Work In Progress	ROOM 46			8/29/2013 11:11:17 AM				
Prospero, Manuel		WHITE BOARD IS COMING OFF WALL							
Laura Parra									
115157	South Building	Hallway/Corridor			3/28/2014		10		\$0.00
Medium	Work In Progress				3/28/2014 8:07:25 AM				
Ontiveros, Joe		A water fountain is overflowing in the hallway due to clog up.							
Ismael Rodriguez									
115156	South Building	Restroom			3/28/2014		10		\$0.00
Medium	Work In Progress				3/28/2014 8:04:31 AM				
Ontiveros, Joe		Theres a urinal in boys restroom thats clog up tried it with a pluunger and still it over flows its located in southbuilding second floor to your right thanks.							
Ismael Rodriguez									
112526	South Building	Classroom			1/28/2014		69		\$0.00
Medium	Work In Progress	35-BREITLING			1/28/2014 2:27:20 PM				
Castillo, Carlos		1-NEE4D ELECTRICAL OUTLET FOR SMARTBOARD AND PROJECTOR							
Laura Parra									
114555	South Building	Classroom			3/12/2014		26		\$0.00
Medium	Work In Progress				3/12/2014 10:15:08 AM				
Lara, Ralph		Rafa, also Ms.Gold needs a key for her filing cabnit to secure her testing material.							
Ismael Rodriguez									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa MS							
109966	Gym (1997)	Gym			11/6/2013		152		\$0.00
Medium	Work In Progress				11/6/2013 11:11:20 AM				
Prospero, Manuel		As per administration basketball courts lanes outside the gym need to be painted there are faded and are use for basketball practice.							
Ismael Rodriguez									
114781	Gym (1997)	Roof			3/18/2014		20		\$0.00
Medium	Work In Progress				3/18/2014 3:28:02 PM				
Ontiveros, Joe		RE INSTALL CONDESATION DRAIN TO A/C COOLER ON GYM AREA.							
Manuel Prospero									
115109	Gym (1997)	Gym			3/27/2014		11		\$0.00
Medium	Work In Progress				3/27/2014 1:28:30 PM				
Ontiveros, Joe		Theres a urinal clog up in the boys dressing room gym area.							
Ismael Rodriguez									
111739					1/7/2014		90		\$0.00
High	Work In Progress				1/7/2014 2:54:01 PM				
Munoz, Michael		please replace all fire hydrants at site they are old and do not work as per fire inspector from sunland							
Alfredo Holguin									
112136					1/15/2014		82		\$0.00
Medium	Work In Progress				1/15/2014 2:33:10 PM				
Munoz, Michael		Replacement of (5) Fire Hydrants.							
Michael Munoz									
115653					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:32 AM				
Orozco, Daniel		Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
111493					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:25 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

111431 Electrical Room 12/19/2013 109 \$0.00

Medium Work In Progress 12/19/2013 9:23:50 AM

Castillo, Carlos Annual electrical equipment inspection.

Carlos Castillo

115354 Athletic Field 4/2/2014 5 \$0.00

Medium Work In Progress 4/2/2014 3:11:57 PM

Castillo, Carlos Need to replace two corroded light poles at football field.

Carlos Castillo

115281 4/1/2014 6 \$0.00

Medium Work In Progress Line Locate 4/1/2014 8:17:53 AM

Castillo, Carlos SMITH & AGUIRRE CONSTRUCTION
Contact: FREDDIE TORRES
Phone: (575)527-2500

SPOT: 15FT RAD OF 5 FIRE HYDRANTS, N
SIDE OF N BLDG; SW CORNER OF N
BLDG; NE
CORNER OF GYMNASIUM; NW CORNER
OF S BLDG; AND S
SIDE OF S BLDG JUST E OF GREEN
ELECTRIC
TRANSFORMER.

Remarks: REMOVE & REPLACE 5 FIRE HYDRANTS
LOCATED INSIDE
SANTA TERESA MIDDLE SCHOOL PROPERTY.
CALL FREDDIE
WITH ANY QUESTIONS. THANKS.

115285 4/1/2014 6 \$0.00

Medium Work In Progress Line Locate 4/1/2014 8:22:12 AM

Castillo, Carlos SMITH & AGUIRRE CONSTRUCTION
Contact: FREDDIE TORRES
Phone: (575)527-2500

WATER VALVE IS LOCATED BEHIND THE
SW CORNER OF THE SOUTHERN
BUILDING. SPOT: AREA
FLAGGED AND PAINTED IN WHITE.
DUE TO WINDY SEASON, PLEASE USE
PAINT AND FLAGS.
CALL FREDDIE WITH QUESTIONS.
THANKS.

Alfredo Holguin

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

115246 3/31/2014 7 \$0.00

Medium Work In Progress 3/31/2014 3:16:37 PM

Ontiveros, Joe please meet with dean cd mechanical to discuss water shut offs for fire hydrants.

Michael Munoz

115280 4/1/2014 6 \$0.00

Medium Work In Progress Line Locate 4/1/2014 8:14:58 AM

Ontiveros, Joe SMITH & AGUIRRE CONSTRUCTION
Contact: FREDDIE TORRES
Phone: (575)527-2500

SPOT:15FT RAD OF 5 FIRE HYDRANTS, N
SIDE OF N BLDG; SW CORNER OF N
BLDG; NE
CORNER OF GYMNASIUM; NW CORNER
OF S BLDG; AND S
SIDE OF S BLDG JUST E OF GREEN
ELECTRIC
TRANSFORMER.

Remarks: REMOVE & REPLACE 5 FIRE HYDRANTS
LOCATED INSIDE
SANTA TERESA MIDDLE SCHOOL PROPERTY.
CALL FREDDIE
WITH ANY QUESTIONS. THANKS.

115284 4/1/2014 6 \$0.00

Medium Work In Progress Line Locate 4/1/2014 8:21:36 AM

Ontiveros, Joe SMITH & AGUIRRE CONSTRUCTION
Contact: FREDDIE TORRES
Phone: (575)527-2500

WATER VALVE IS LOCATED BEHIND THE
SW CORNER OF THE SOUTHERN
BUILDING.SPOT: AREA
FLAGGED AND PAINTED IN WHITE.
DUE TO WINDY SEASON, PLEASE USE
PAINT AND FLAGS.
CALL FREDDIE WITH QUESTIONS.
THANKS.

Alfredo Holguin

114005 3/2/2014 36 \$0.00

Medium Work In Progress 3/2/2014 12:26:02 AM

Prospero, Manuel Yearly - Santa Teresa MS A10 (Heat Pump)(Yearly) -
Refer to PM schedule details.

Margret Villalobos

4/7/2014 2:48:58 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS									
115476					4/6/2014	4/22/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:21 AM				
Prospero, Manuel		Monthly - Santa Teresa MS A1 (Wall Refr.E/H)(Semi) - Refer to PM schedule details.							
Margret Villalobos									
115202					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 12:54:17 AM				
Prospero, Manuel		Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.							
Margret Villalobos									
112591					1/29/2014		68		\$0.00
High	Work In Progress				1/29/2014 11:18:07 AM				
Ontiveros, Guadalupe		We need the dirt under ramps in portables 1 and 2 removed before the winds start kicking up, the accumulation of dirt has reached the top of ramps and is going into portables.							
114899		Classroom			3/21/2014		17		\$0.00
Medium	Work In Progress				3/21/2014 10:46:32 AM				
Ambriz, Jose		WE NEED TO HAVE 8 BOOSTER PUMP PL-36 ON STACK.							
Manuel Prospero									
110331					11/16/2013		142		\$0.00
Medium	Work In Progress				11/16/2013 12:18:09				
Flores, Pete		Yearly - Santa Teresa MS - Mower 0416 - Grounds - Refer to PM schedule details.							
Margret Villalobos									
113270		Classroom			2/11/2014		55		\$0.00
Medium	Work In Progress				2/11/2014 2:39:38 PM				
Prospero, Manuel		WE NEED CHANGED AIR FILTERS ALL BUILDINGS AND PORTABLES.							
Manuel Prospero									
114703		Classroom			3/17/2014		21		\$0.00
Medium	Work In Progress				3/17/2014 1:41:56 PM				
Prospero, Manuel		TROBLE SHUTRING LAB TAB TRACER SUMER A.P. ADRESSES.							
Manuel Prospero									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
115530					4/6/2014	5/7/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:09 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
115529					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:08 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115528					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:06 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115533					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:12 AM				
Prospero, Manuel		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
115680					4/7/2014		0		\$0.00
Medium	Work In Progress				4/7/2014 12:12:19 PM				
Soria, Mike		please clean lila tree as discussed. thank you							
Michael Munoz									
115519					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:58 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
Count: 50 Work Orders			Avg. Age of WO's	41		Total for Santa Teresa MS	0		\$0.00

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunland Park ES							
115504					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:44 AM				
Hernandez, Carlos		Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
113784					2/25/2014		41		\$0.00
Medium	Work In Progress				2/25/2014 2:58:36 PM				
Flores, Pete		need new light bulb for trailer							
Carlos Hernandez									
115241					3/31/2014		7		\$0.00
Medium	Work In Progress				3/31/2014 2:50:22 PM				
Gallegos, Rafael		AS PER ENVIRONMENT INSPECTION REPORT ON MARCH 31, 2014. 1.) SPRING LOADED FAUCETS NOT ALLOWED ANYMORE, PROVIDE LEVER FAUCET, EMPLOYEE RESTROOM HAS SPRING LOADED FAUCET. 2.) INSUFFICIENT BACK DOOR SEALS TO DOOR. 3.) DRY STORAGE CEILING HAS TILES THAT DONT MEET SMOOTH DEFENITION. 4.) DIM BULBS IN FREEZER (DANNY REPLACED).							
Maritza Gonzalez									
115582					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:47 AM				
Hernandez, Carlos		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115581					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:46 AM				
Hernandez, Carlos		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunland Park ES							
114207					3/4/2014		34		\$0.00
Medium	Work In Progress				3/4/2014 9:43:18 AM				
Hernandez, Carlos		need these tools dolly hand tree trimmer caulking gun portable battery charger 10-1 screw driver schiffler torque screw driver tool pouch acilen torch and tank gfi outlet tester							
Carlos Hernandez									
113782					2/25/2014		41		\$0.00
Medium	Work In Progress				2/25/2014 2:56:35 PM				
Ambriz, Jose		need new water fountain north side							
Carlos Hernandez									
113493					2/18/2014		48		\$0.00
Medium	Work In Progress				2/18/2014 3:08:43 PM				
Ontiveros, Guadalupe		soccer feild needs to be arreated and fertilized							
Carlos Hernandez									
114443					3/10/2014		28		\$0.00
Medium	Work In Progress				3/10/2014 12:53:51 PM				
Castillo, Carlos		there are 9 primeriter lights that need replaced							
Carlos Hernandez									
113364					2/13/2014		53		\$0.00
Medium	Work In Progress				2/13/2014 8:59:02 AM				
Castillo, Carlos		need power run to a/c unit portable f							
Carlos Hernandez									
111491					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:23 AM				
Villalobos, David		Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: Sunland Park ES										
107040					9/4/2013		215		\$0.00	
Medium	Work In Progress	TEACHER'S		9/4/2013 7:57:55 AM						
Ontiveros, Joe	AS PER MS. DUQUE----- NEED TO HAVE SINK INSTALLED IN THE TEACHER'S LOUNGE. PLEASE SEE MS. DUQUE ABOUT THIS IF THERE ARE ANY QUESTIONS. THANK YOU.									
David Avila										
115654					4/6/2014	4/27/2014	1		\$0.00	
Medium	Work In Progress			4/6/2014 12:32:33 AM						
Orozco, Daniel	Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.									
Margret Villalobos										
115391					4/3/2014		4		\$0.00	
Medium	Work In Progress			4/3/2014 10:41:17 AM						
Gallegos, Rafael	SEAL IS OFF ON THE BOTTOM OF 3 COMPARTMENT SINK, WATER LEAKS WHEN TRYING TO WASH.									
Maritza Gonzalez										
113223					2/10/2014		56		\$0.00	
Medium	Work In Progress			2/10/2014 3:10:42 PM						
Holguin, Alfredo	as per alfredo need playground sand removed and replaced with engineered wood fiber (its at total of 9 playground equipment and 50 border need replacement									
Carlos Hernandez										
115636					4/6/2014	4/12/2014	1		\$0.00	
Medium	Work In Progress			4/6/2014 12:32:21 AM						
Hernandez, Carlos	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.									
Margret Villalobos										
Count: 16 Work Orders	Avg. Age of WO's 39		Total for Sunland Park ES				0	\$0.00		

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location:		Sunrise ES							
115607					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:03 AM				
Apodaca, Mario		Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
114108					3/2/2014		36		\$0.00
Medium	Work In Progress				3/2/2014 12:26:51 AM				
Apodaca, Mario		Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
113791					2/25/2014		41		\$0.00
Medium	Work In Progress				2/25/2014 3:36:08 PM				
Holguin, Alfredo		I have two playground areas Northside 100x90 Southside 120x100 need repair of plastic borders.							
Juan Vargas									
115432					4/4/2014		3		\$0.00
Medium	Work In Progress				4/4/2014 7:49:38 AM				
Orozco, Daniel		. I WOULD LIKE TO PUT ONE IN FOR MY LAUNDRY ROOM. I HAVE SEVERAL WALLS WITHOUT THEM AND ON ONE OF THE WALLS THE SHEETROCK IS WET AND COMING APART. I SHOWED THE SCHOOLS MAINTANCE MAN AND HE THINKS THAT MY DRAIN BASIN HAS A CRACK IN IT AND THAT IS WHY IT IS LIKE THAT WAY. SNP MANAGER GLENDA G.824.3194							
Maritza Gonzalez									
115097					3/26/2014		12		\$0.00
Medium	Work In Progress				3/26/2014 4:29:52 PM				
Orozco, Daniel		WASHER DIED, STOPPED WORKING ON THE RINSE CYCLE AND WILL NOT GO BACK ON . SNP MANAGER GLENDA G. 824.3194							
Maritza Gonzalez									
115655					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:34 AM				
Orozco, Daniel		Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
115619					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:32:10 AM					
Vargas, Juan	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
115023					3/25/2014		13		\$0.00
Medium	Work In Progress			3/25/2014 2:35:14 PM					
Estrada, Jesus	portable # 2 need replace the flor tile the tile has raised the students teachers and student slip								
Juan Vargas									
115024					3/25/2014		13		\$0.00
Medium	Work In Progress			3/25/2014 2:39:22 PM					
Estrada, Jesus	library need replace carpet o repair front part								
Juan Vargas									
115126					3/27/2014		11		\$0.00
Medium	Work In Progress			3/27/2014 3:21:31 PM					
Appelzoller, Fred	outside water founting need fix or replace								
Juan Vargas									
115128					3/27/2014		11		\$0.00
Medium	Work In Progress			3/27/2014 3:24:08 PM					
Appelzoller, Fred	urinal in r.room next to cafeteria unclog								
Juan Vargas									
111489					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress			1/5/2014 12:23:22 AM					
Villalobos, David	Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
114942					3/24/2014		14		\$0.00
Medium	Work In Progress			3/24/2014 9:58:58 AM					
Ontiveros, Guadalupe	needn 10 tons crashionfine for portables rain gaters								
Juan Vargas									
114338					3/6/2014		32		\$0.00
Medium	Work In Progress			3/6/2014 3:24:38 PM					
Ontiveros, Guadalupe	need grass sed for athletic field								
Juan Vargas									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Sunrise ES									
106424					8/22/2013		228		\$0.00
Medium	Work In Progress			8/22/2013 3:36:46 PM					
Marquez, Gerardo	marqui need replace locks								
Juan Vargas									
115200					3/31/2014		7		\$0.00
Medium	Work In Progress			3/31/2014 12:54:15 AM					
Vargas, Juan	Monthly - Sunrise ES A16 (Fan Exh.)(S. Annual) - Refer to PMschedule details.								
Margret Villalobos									
113963					2/28/2014		38		\$0.00
Medium	Work In Progress			2/28/2014 3:09:35 PM					
Vallejo, Albert	need instaled 120 volts cable for a/c water pump								
Juan Vargas									
114943					3/24/2014		14		\$0.00
Medium	Work In Progress			3/24/2014 10:01:59 AM					
Vargas, Juan	need paint all boys and grls. r.rooms								
Juan Vargas									
114944					3/24/2014		14		\$0.00
Medium	Work In Progress			3/24/2014 10:03:53 AM					
Vargas, Juan	need to paint rooms 310 206 203								
Juan Vargas									
114652					3/14/2014		24		\$0.00
Medium	Work In Progress			3/14/2014 1:59:37 PM					
Vallejo, Albert	recovery ventilator need replace contactor and 4L 620 velts								
Juan Vargas									
111144					12/11/2013		117		\$0.00
Medium	Work In Progress			12/11/2013 8:59:01 AM					
Vargas, Juan	need relace exauhstfan in 300 hall electical closed								
Juan Vargas									
115551					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:31:26 AM					
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PMschedule details.								
Margret Villalobos									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
115550					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:25 AM				
Vargas, Juan		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115549					4/6/2014		1		\$0.00
Medium	Work In Progress				4/6/2014 12:31:24 AM				
Vargas, Juan		Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
113879					2/27/2014		39		\$0.00
Medium	Work In Progress				2/27/2014 3:14:25 PM				
Vargas, Juan		need replace all door sweepers							
Juan Vargas									
114492					3/11/2014		27		\$0.00
Medium	Work In Progress				3/11/2014 10:19:09 AM				
Vargas, Juan		need repair outside cement block wall							
Juan Vargas									
113087					2/6/2014		60		\$0.00
Medium	Work In Progress				2/6/2014 3:07:02 PM				
Flores, Pete		need fix gas tank have leak							
Juan Vargas									
107279					9/10/2013		209		\$0.00
Medium	Work In Progress				9/10/2013 8:17:26 AM				
Flores, Pete		430 mower need replace blade							
Juan Vargas									
115514					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:30:52 AM				
Vargas, Juan		Monthly - Sunrise ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
111927					1/10/2014		87		\$0.00
Medium	Work In Progress				1/10/2014 3:12:34 PM				
Ontiveros, Guadalupe		need replace 6 tress							
Juan Vargas									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
112022					1/13/2014		84		\$0.00
Medium	Work In Progress				1/13/2014 3:25:37 PM				
Ontiveros, Guadalupe		need fix 2 in. sprinkler valve							
Juan Vargas									
109922					11/5/2013		153		\$0.00
Medium	Work In Progress				11/5/2013 3:18:06 PM				
Ontiveros, Guadalupe		need 12 tons lavo stone in front parking pond							
Juan Vargas									
Count: 32 Work Orders		Avg. Age of WO's 43		Total for Sunrise ES		0	\$0.00		

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
115508					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:30:47 AM					
Miranda, Danny	Monthly - Vado ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
114222					3/4/2014		34		\$0.00
Medium	Work In Progress			3/4/2014 3:20:53 PM					
Miranda, Danny	need to paint or repair ceiling tile as needed								
Danny Miranda									
115575					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:31:42 AM					
Miranda, Danny	Monthly - Vado ES Emer. Light Test: Monthly - Refer to PMs schedule details.								
Margret Villalobos									
115573					4/6/2014		1		\$0.00
Medium	Work In Progress			4/6/2014 12:31:41 AM					
Miranda, Danny	Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PMs schedule details.								
Margret Villalobos									
115574					4/6/2014	4/14/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:31:41 AM					
Miranda, Danny	Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
115492					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress			4/6/2014 12:30:35 AM					
Orozco, Daniel	Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PMs schedule details.								
Margret Villalobos									
115192					3/31/2014		7		\$0.00
Medium	Work In Progress			3/31/2014 12:54:08 AM					
Miranda, Danny	Monthly - Vado ES A-16 - Fan Exhaust Semiannual - Refer to PMs schedule details.								
Margret Villalobos									
112074					1/14/2014		83		\$0.00
Medium	Work In Progress			1/14/2014 11:41:34 AM					
Marquez, Gerardo	need to change core from 200-w/r to roon 202 storage								
Danny Miranda									
4/7/2014 2:48:59 PM									

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
111497					1/5/2014	2/5/2014	92		\$0.00
Medium	Work In Progress				1/5/2014 12:23:26 AM				
Villalobos, David		Yearly - Vado ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
115656					4/6/2014	4/27/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:34 AM				
Orozco, Daniel		Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
113302					2/12/2014		54		\$0.00
Medium	Work In Progress				2/12/2014 7:46:07 AM				
Holguin, Alfredo		need to replace sand w/wood fiber in playground							
Danny Miranda									
115630					4/6/2014	4/12/2014	1		\$0.00
Medium	Work In Progress				4/6/2014 12:32:17 AM				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
105493					8/6/2013		244		\$0.00
Medium	Work In Progress				8/6/2013 12:07:19 PM				
Marquez, Gerardo		need to replace back door to kitchen							
Danny Miranda									
105494					8/6/2013		244		\$0.00
Medium	Work In Progress				8/6/2013 12:10:54 PM				
Marquez, Gerardo		need to replace back door going to bus exit							
Danny Miranda									
115402	Main Building	Custodial			4/3/2014		4		\$0.00
Medium	Work In Progress				4/3/2014 12:17:43 PM				
Carbajal, Jimmy		vacuum cleaner has elec short							
Armando Diaz									
115120	Main Building	Office			3/27/2014		11		\$0.00
Medium	Work In Progress	Nurses Office			3/27/2014 2:45:13 PM				
Marquez, Gerardo		Nurse has only one key to file cabinet and it is bending. Could you please make another key for her. Thank you.							
Colleen Runyan									
Count: 16 Work Orders			Avg. Age of WO's	49		Total for Vado ES	0	\$0.00	

4/7/2014 2:48:59 PM

1025 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Count: 1025 Work Orders		Avg. Age of WO's 49				Grand Total		0	\$0.00