	ate Range for Request Building Status To	Dates:7/1/2014 - 11/30/2014 (Area Deferred Area Number Reason Description	order By Location, Status By Until	Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Total Costs
Location:	Location	Not Assigned						
125240				11/6/2014		25		\$0.00
Medium	Work In Progress		11/6/2	014 3:04:25 PN	Λ			
Ambriz, Jo	ose	As per Mrs. Gilpin, could her office replaced due to						
Maritza Go	onzalez							
124340				10/20/2014		42		\$0.00
Medium	Work In Progress		10/20)/2014 12:33:32	2			
Orozco, Da	aniel	AS PER HEALTH DEPAR BACK DOOR NEEDS TO DOES NOT SHUT COMP PUSHING IT SHUT.SNP 824.4376	FIXED. WALK IN DOOF	-				
Maritza Go	onzalez							
Count: 2 W	Vork Orders	Avg. Age of	WO's 34		Total for <b< td=""><td>ank></td><td>0</td><td>\$0.00</td></b<>	ank>	0	\$0.00

Selected Da WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time A Description	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Total Costs
Location:	Alta Vista	a Early College HS				
125742		11/19/2014		12		\$0.00
Medium	Work In Progress	11/19/2014 10:04:15				
Gonzalez,	, Salvador	Instal window gards on window 3 doors new instal.				
Alfredo An	nbriz					
125546		11/14/2014		17		\$0.00
Medium	Work In Progress	11/14/2014 12:44:48				
Sanchez,	Raul	Monthly - Alta Vista ECHS- Water Filters - Refer to PM schedule details.				
Margret V	illalobos					* ••••
124974		11/2/2014		29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:01 AM				
Sanchez,		Monthly - Desert Pride - Monthly Water Samples - Refer to PMschedule details.				
Margret Vi	illalobos	11/30/2014		1		\$0.00
125991 Medium		11/30/2014 12:47:28		I		φ0.00
Sanchez,	Work In Progress Raul	Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.				
Margret Vi	illalobos					
125992		11/30/2014		1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:29				
Sanchez,	Raul	Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details.				
Margret Vi	illalobos					
124993		11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:12 AM				
Ambriz, Al	fredo	Monthly - Alta Vista ECHS Monthly FE Inspection - Refer to PMschedule details.				
Margret V	illalobos					
126018		11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:46				
Ambriz, Al	fredo	Monthly - Alta Vista ECHS Monthly FE Inspection - Refer to PMschedule details.				
Margret Vi	illalobos					

WOID	Building	Area	Deferred By	=	Target Comp Date	Days	Labor	
Priority	Status	Area Number	Reason	Created Date/Time	•	Aged	Hours	
Assigned T		Description			Action Taken			
Requester								
Location:	Alta Vista	Early College H	S					
120352				8/3/2014		120		\$0.00
Medium	Work In Progress			8/3/2014 12:33:50 AN	1			
Munoz, Mic	hael	Yearly - Desert to PMschedule	Pride HS Fire Ext. Ins details.	sp. (Yearly) - Refer				
Margret Vill	alobos							
120509				8/5/2014		118		\$0.00
Medium	Work In Progress			8/5/2014 7:47:20 AN	1			
Ronquillo,			desk and furniture fro se of furniture that is r					
Michael Mu	inoz			44/00/0044	40/0/0044			
125908				11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress			11/30/2014 12:46:33				
Ambriz, Alfr		Monthly - Alta V Refer to PMsch	ista ECHS Emer Ligl nedule details.	nt Test: Monthly-				
Margret Vill	alobos			11/30/2014	12/8/2014	1		<u>م</u>
125909						I		\$0.00
Medium	Work In Progress			11/30/2014 12:46:34				
Ambriz, Alfr		Monthly - Alta V Refer to PMsch	ista ECHS Exit Sign I nedule details.	nsp: Monthly -				
Margret Vill	alobos			44/0/0044	44/40/2044			
124951				11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress			11/2/2014 12:35:48 AN	1			
Ambriz, Alfr		Monthly - Alta V Refer to PMsch	ista ECHS Exit Sign I nedule details.	nsp: Monthly-				
Margret Vill	alobos			44/0/0044	44/40/0044			
124952				11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress			11/2/2014 12:35:48 AN	1			
Ambriz, Alfr	edo	Monthly - Alta V Refer to PMsch	ïsta ECHS Emer Ligl nedule details.	nt Test: Monthly -				
Margret Vill	alobos							
125845				11/21/2014		10		\$0.00
Medium	Work In Progress			11/21/2014 11:44:13	i			
	Danny		one window in the pe		see Mike Munozon	41-1-		

Selected Da WOID Priority Assigned	te Range for Request Building Status To	Dates:7/1/2014 - 1 Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Tota Costs
Requester								
Location:	Alta Vista	a Early College H	IS					
120783	Curriculum and	Classroom		8/8/2014		115		\$0.00
Medium	Work In Progress			8/8/2014 8:03:48 AN	1			
Ambriz, Jo	se	Install a refrige and Rm 501 of		1 504 old PE portable				
Minerva M	enchaca							
119421		Classroom		7/15/2014		139		\$0.00
Medium	Work In Progress	2nd bldg		7/15/2014 10:04:15 AN	1			
Lara, Ralp	h	Having hard tim	ne opening entrand	ce door				
David Acos	sta							
125744				11/19/2014		12		\$0.00
Medium	Work In Progress			11/19/2014 10:11:16	3			
Lara, Ralp	h	Need replace of	ilinder match our k	eys for 3 doors.				
Alfredo Am	briz							
125678				11/18/2014		13		\$0.00
Medium	Work In Progress			11/18/2014 2:12:51 PM	1			
Lara, Ralp	h		G CABINET KEYS GE. PLEASE COM MORE INFO.					
Yvette Cor	tez							
119862				7/25/2014		129		\$0.00
Medium	Work In Progress			7/25/2014 2:25:32 PM	Λ			
Lara, Ralp	h	cores off maste to e-mail for pic keys and issue Gema Salcedo contact Mr. Ral	er. Door was the nucture and sketch fo one (1) to George	esert Pride) change rse's office door. Refer or door location. Make 2 Foster and one (1) to anyquestions please - 882-6921 in the				
Dominique	e Esparza							
119335				7/13/2014	7/29/2014	141		\$0.00
Medium	Work In Progress			7/13/2014 12:24:06 AN	1			
Ambriz, Alf	redo	Monthly - QRTL PMschedule d		PORT (DP) - Refer to				
Jesus Est	rada							
124043				10/12/2014		50		\$0.00
Medium	Work In Progress			10/12/2014 12:29:04	1			
Laguna, Lo		Monthly - QRTL PMschedule d		PORT (DP) - Refer to				
Jesus Est	rada							

WOID	Building	Area	1/30/2014 Order By Lo Deferred By	Until Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time	-	Aged	Hours	
Assigned		Description			Action Taken			
Requester								
Location:	Alta Vista	a Early College H	IS					
124394	Curriculum and	Portables		10/21/2014		41		\$0.00
Medium	Work In Progress			10/21/2014 12:03:40)			
Aguilar, Pa	atricio	PE portable (50)4) roof continues to l	eak.				
Minerva M	lenchaca							
125427				11/12/2014		19		\$0.00
Medium	Work In Progress			11/12/2014 9:54:38 AM	1			
Villalobos	, David	(575)526-5442 Best Time to C 526-1057 Location of Wo WASHINGTON THE SCHOOL	JOHNNY'S SEPTIC PALOMA REYNA all: Fa rk: FROM INTERS. C ST (NM-225), GO S. ON R. AT INTERS. C POT WITHIN THE AF	Contact Phone: ax No: (575) DF NM-28 & ON NM-28 TO DF				
Dominiqu	e Esparza							
120833				8/8/2014		115		\$0.00
Medium	Work In Progress			8/8/2014 1:58:33 PM	1			
Villalobos	, David	Need to repair	water line between th	e morgan bldg.				
Michael M	lunoz							
123089		Classroom		9/23/2014		69		\$0.00
Medium	Work In Progress			9/23/2014 3:28:10 PM	1			
Sotelo, En	rique	Connect all new the internet/wi-	w treadmills in the PE fi	portable #504 to				
Minerva M	lenchaca							
121826	Curriculum and	Portables		8/27/2014		96		\$0.00
Medium	Work In Progress			8/27/2014 8:16:27 AN	1			
Sotelo, En	rique		ower outlet strip on t E portable #504	he west side wall of				
Minerva M	lenchaca							

125426 11/12/2014 Medium Work In Progress 11/12/2014 Sotelo, Enrique Company: JOHNNY'S SEPTIC TANK Contact Name: PALOMA REYNA Contact Phon (575)526-5442 Best Time to Call: Fax No: (575) Sotelo, Enrique Location of Work: FROM INTERS. OF NM-28 & WASHINGTON ST (NM-225), GO S. ON NM-28 TO THE SCHOOL ON R. AT INTERS. OF LITTLE RD SPOT WITHIN THE AREA MARKED IN WHITE. Dominique Esparza 122643 Curriculum and Office Medium Work In Progress 9/11/2014 1 Carrasco, Danny Walls in main office and main hallwaypainted. Wall o the outside of main office to be repaired and painted. Ceiling tiles need to be replaced in main hallway, libra bathroom and whenever else needed. Per Mr. Yturralor Minerva Menchaca 124395 Curriculum and Classroom Medium Work In Progress 10/21/20*	ate/Time Actual Comp Date Action Taken	Aged H	Labor Hours
125426 11/12/2014 Medium Work In Progress 11/12/2014 Sotelo, Enrique Company: JOHNNY'S SEPTIC TANK Contact Name: PALOMA REYNA Contact Phone (575)526-5442 Best Time to Call: Fax No: (575) 526-1057 Location of Work: FROM INTERS. OF NM-28 & WASHINGTON ST (NM-225), GO S. ON NM-28 TO THE SCHOOL ON R. AT INTERS. OF LITTLE RD SPOT WITHIN THE AREA MARKED IN WHITE. Dominique Esparza 122643 Curriculum and Office Medium Work In Progress 9/11/2014 1 Carrasco, Danny Walls in main office and main hallwaypainted. Wall o the outside of main office to be repaired and painted. Ceiling tiles need to be replaced in main hallway, libra bathroom and whenever else needed. Per Mr. Yturrate Minerva Menchaca 124395 Curriculum and Classroom 10/21/2014			
Medium Work In Progress 11/12/2014 Sotelo, Enrique Company: JOHNNY'S SEPTIC TANK Contact Name: PALOMA REYNA Contact Phon (575)526-5442 Best Time to Call: Fax No: (575) 526-1057 Location of Work: FROM INTERS. OF NM-28 & WASHINGTON ST (NM-225), GO S. ON NM-28 TO THE SCHOOL ON R. AT INTERS. OF LITTLE RD SPOT WITHIN THE AREA MARKED IN WHITE. Dominique Esparza 11/12/2014 122643 Curriculum and Office 9/11/2014 1 Carrasco, Danny Walls in main office and main hallwaypainted. Wall o the outside of main office to be repaired and painted. Ceiling tiles need to be replaced in main hallway, libra bathroom and whenever else needed. Per Mr. Yturralor Minerva Menchaca Medium Work In Progress 10/21/2014			
Sotelo, Enrique Company: JOHNNY'S SEPTIC TANK Contact Name: PALOMA REYNA Contact Phon (575)526-5442 Best Time to Call: Fax No: (575) 526-1057 Location of Work: FROM INTERS. OF NM-28 & WASHINGTON ST (NM-225), GO S. ON NM-28 TO THE SCHOOL ON R. AT INTERS. OF LITTLE RD SPOT WITHIN THE AREA MARKED IN WHITE. Dominique Esparza 122643 Curriculum and Office Medium Work In Progress 9/11/2014 1 Carrasco, Danny Walls in main office and main hallwaypainted. Wall o the outside of main office to be repaired and painted. Ceiling tiles need to be replaced in main hallway, libra bathroom and whenever else needed. Per Mr. Yturralo Minerva Menchaca Medium Work In Progress 124395 Curriculum and Classroom 10/21/201	1/12/2014	19	\$0.00
Contact Name: PALOMA REYNA Contact Phone (575)526-5442 Best Time to Call: Fax No: (575) 526-1057 Location of Work: FROM INTERS. OF NM-28 & WASHINGTON ST (NM-225), GO S. ON NM-28 TO THE SCHOOL ON R. AT INTERS. OF LITTLE RD SPOT WITHIN THE AREA MARKED IN WHITE. Dominique Esparza 122643 Curriculum and Office Medium Work In Progress 9/11/2014 1 Carrasco, Danny Walls in main office and main hallwaypainted. Wall o the outside of main office to be repaired and painted. Ceiling tiles need to be replaced in main hallway, libra bathroom and whenever else needed. Per Mr. Yturralo Minerva Menchaca 124395 Curriculum and Classroom Medium Work In Progress 10/21/2014):54:09 AM		
526-1057 Location of Work: FROM INTERS. OF NM-28 & WASHINGTON ST (NM-225), GO S. ON NM-28 TO THE SCHOOL ON R. AT INTERS. OF LITTLE RD SPOT WITHIN THE AREA MARKED IN WHITE. Dominique Esparza 122643 Curriculum and Office Medium Work In Progress 9/11/2014 1 Carrasco, Danny Walls in main office and main hallwaypainted. Wall o the outside of main office to be repaired and painted. Ceiling tiles need to be replaced in main hallway, libra bathroom and whenever else needed. Per Mr. Yturrate bathroom and whenever else needed. Per Mr. Yturrate Medium Minerva Menchaca 124395 Curriculum and Classroom Medium Work In Progress 124395 Curriculum and Classroom 10/21/207	ə:		
WASHINGTON ST (NM-225), GO S. ON NM-28 TO THE SCHOOL ON R. AT INTERS. OF LITTLE RD SPOT WITHIN THE AREA MARKED IN WHITE.Dominique Esparza122643Curriculum andMediumWork In Progress9/11/2014 1Carrasco, DannyWalls in main office and main hallwaypainted. Wall o the outside of main office to be repaired and painted. Ceiling tiles need to be replaced in main hallway, libra bathroom and whenever else needed. Per Mr. YturraloMinerva Menchaca124395Curriculum andClassroom10/21/207			
122643 Curriculum and Office Medium Work In Progress 9/11/2014 1 Carrasco, Danny Walls in main office and main hallway painted. Wall o the outside of main office to be repaired and painted. Ceiling tiles need to be replaced in main hallway, libra bathroom and whenever else needed. Per Mr. Yturralo Minerva Menchaca Minerva Menchaca 1 124395 Curriculum and Medium Work In Progress 10/21/207			
Medium Work In Progress 9/11/2014 1 Carrasco, Danny Walls in main office and main hallwaypainted. Wall o the outside of main office to be replaced and painted. Ceiling tiles need to be replaced in main hallway, libra bathroom and whenever else needed. Per Mr. Yturralo Minerva Menchaca 124395 Curriculum and Classroom Medium Work In Progress 10/21/207			
Carrasco, Danny Walls in main office and main hallwaypainted. Wall of the outside of main office to be repaired and painted. Ceiling tiles need to be replaced in main hallway, librate bathroom and whenever else needed. Per Mr. Yturrated Minerva Menchaca Minerva Menchaca 124395 Curriculum and Classroom Medium Work In Progress	9/11/2014	81	\$0.00
the outside of main office to be repaired and painted. Ceiling tiles need to be replaced in main hallway, libra bathroom and whenever else needed. Per Mr. Yturrale Minerva Menchaca 124395 Curriculum and Classroom Medium Work In Progress 10/21/207	:33:24 AM		
124395Curriculum andClassroomMediumWork In Progress10/21/207	ry		
Medium Work In Progress 10/21/207			
C C	0/21/2014	41	\$0.00
Aquilar Datricia Need Coope of block approximate point the window	4 12:07:07		
Aguilar, Patricio Need 6 cans of black spraypaint to paint the window guards on the classrooms. Blue paint to paint the handicap parking barrier.			
Minerva Menchaca			

WOID Priority Assigned T Requester	Building Status o	Dates:7/1/2014 - 11/30/2014 Orde Area Deferred B Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	- On Track Pre-K (Village)					
125171			11/5/2014		26		\$0.00
Medium	Work In Progress		11/5/2014 12:28:43 PM	I			
Solis, Lore		need to have both units on the heat not working need to repl and the other one need help t	ace relays on one for sure				
Daniel Sote	elo	01	0/04/0044		40		<u> </u>
121563		Classroom	8/21/2014		19		\$0.00
Medium Sotelo, Dar	Work In Progress niel	575-882-1904 please paint outside the On class room doors form rooms 102 we already have the pai company donated if you have contact Estrella thank you, Laura	s 111,110,109,108, 101 and nt from a parent the their	1 9/9/2014			
Laura Vazq	luez		14/5/0044				* •••••
125163 Medium	Work In Progress	Classroom 575-882-1904	11/5/2014 11/5/2014 9:36:07 AN		26		\$0.00
Sotelo, Dar	niel	classroom 108 it is licking wa check it out it starting to do thank you, Laura					
Laura Vazq	luez						
125849			11/21/2014		10		\$0.00
Medium	Work In Progress		11/21/2014 2:33:12 PM	l			
Vega, Davi	d	please wash the carpet that is K office thank you	s in the entrance of the pre-				
Laura Vazq	luez						
125567			11/14/2014		17		\$0.00
Medium	Work In Progress	882-1904	11/14/2014 12:14:27				
Marquez, G	Gerardo	please provide us with a new to lock the little storage where by it self when we pulled it d if any question please ask me thank you	e we put the bikes it open own				
Laura Vazq	luez						
121769			8/26/2014		97		\$0.00
Medium	Work In Progress		8/26/2014 9:12:18 AN	1			
Marquez, G David Vega		speech therapist is having tro speech therapy room	ouble locking door to				
	a						

12/1/2014 3:28:24 PM

	ate Range for Request		•	(FISCAL LEAL)			Total Costs
WOID	Building	Area	Deferred By	Until Request Date Target Con		Labor	COSIS
Priority	Status -	Area Number	Reason	Created Date/Time Actual Con	•	Hours	
Assigned Requester		Description	ription Action Taken				
Location:		· On Track Pre-					
	Anthony	On mack Fre-	r (village)				
124372				10/21/2014	41		\$0.00
Medium	Work In Progress			10/21/2014 8:07:56 AM			
Marquez, (Gerardo		r top for new sink in t estrella. thank you	he 1st portable.			
Michael M	lunoz						
122602				9/10/2014	82		\$0.00
Medium	Work In Progress			9/10/2014 3:37:10 PM			
Sotelo, Da	aniel	need to replace	e filters on units				
Daniel So	telo						
123855				10/8/2014	54		\$0.00
Medium	Work In Progress			10/8/2014 8:02:17 AM			
Ronquillo	, Ruben		he end of slide.I hav	f it can be fixed it has e it closed but need			
Daniel So	telo						
123971				10/9/2014	53		\$0.00
Medium	Work In Progress			10/9/2014 4:29:08 PM			
Carrasco,	Danny	att: Danny C. fi	lters i need 10@12x	36x1 10@10x24x1			
Daniel So	telo						
Count: 10	Work Orders	A	vg. Age of WO's 4	3 Total for Anthony - On Track P	re-K (Village)	0	\$0.00

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Target Area Number Reason Created Date/Time Actual Description Area	A	Costs
Location:	Anthony	ES		
121985		8/29/2014	94	\$0.00
Medium	Work In Progress	8/29/2014 3:13:57 PM		
Orozco, Da	aniel	THERE IS A LEAK ON SPRAYER HOSE. SNP MANAGER BECKY S. 882.3507		
Maritza Go	onzalez			
121986		8/29/2014	94	\$0.00
Medium	Work In Progress	8/29/2014 3:14:16 PM		
Orozco, Da	aniel	SERVING LINE CLOGGED. SNP MANAGER BECKY S. 882.3507		
Maritza Go	onzalez			
121438		8/19/2014	104	\$0.00
Medium	Work In Progress	8/19/2014 2:55:31 PM		
Orozco, Da		EXHAUST FAN SWITCH IS NOT WORKING AGAIN. SNP MANAGER BECKY S. 882.3507		
Maritza Go	onzalez	0/40/0044	404	.
121439		8/19/2014	104	\$0.00
Medium	Work In Progress	8/19/2014 2:56:27 PM		
Orozco, Da	aniel	NEED METAL COVERS FOR FAN INSIDE WALK IN REFRIGERATOR, SAFETY HAZARD. SNP MANAGER BECKY S. 882.3507		
Maritza Go	onzalez			
123057		9/23/2014	69	\$0.00
Medium	Work In Progress	9/23/2014 9:58:08 AM		
Orozco, Da	aniel	PRONG TO SLICER STAYED STUCK IN OUTLET. SNP MANAGER BECKY S. 882.3507		
Maritza Go	onzalez			
120712		8/7/2014	116	\$0.00
Medium	Work In Progress	8/7/2014 12:12:51 PM		
Gonzalez,	Salvador	Sal we need to build a ladder rack for the gater as per Mike thanks		
Daniel So				
125756	Pump House	Athletic Field 11/19/2014	12	\$0.00
Medium	Work In Progress	11/19/2014 1:56:05 PM		
Apodaca,	Mario	AnthonyElementaryirrigation water pressure tank upper side of campus is water logged need to troubleshoot		
Mario Apo	daca			

Selected Da WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	ES				
125979		11/30/2014		1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:20	1			
Apodaca, I	Mario	Monthly - Anthony ES - Monthly Meter Readings - Refer to PMschedule details.				
Margret Vil	llalobos		/			
125008		11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:21 AN	l			
Orozco, Da		Monthly - Anthony ES Range Hood Cleaning - Refer to PMschedule details.				
Margret Vil	llalobos	10/21/2014		41		\$0.00
-				41		φ0.00
Medium	Work In Progress	10/21/2014 3:16:07 PN				
Munoz, Mic		need to replace side walk that was broken by el paso disposal				
Daniel Sot	telo	11/18/2014		13		\$0.00
Medium	Work In Progress	11/18/2014 8:19:52 AM	I	15		φ0.00
Sotelo, Da	-	need to replace wood planks on the ramps for sped storage barracks				
Daniel Sot	telo					
120082		7/31/2014		123		\$0.00
Medium	Work In Progress	7/31/2014 9:12:51 AM	I			
Carrasco,	Danny	att: Danny C. need a extension ladder 24'				
Daniel Sot	telo					
126015		11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:44				
Sotelo, Da	niel	Monthly - Anthony ES Monthly FE Inspection - Refer to PMschedule details.				
Margret Vil	llalobos					
124996		11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:14 AM	l			
Sotelo, Da	niel	Monthly - Anthony ES Monthly FE Inspection - Refer to PMschedule details.				
Margret Vil	llalobos					6 0
125560		11/14/2014		17		\$0.00
Medium	Work In Progress	11/14/2014 9:27:17 AN	I			
Carbajal, J	Jimmy	vaccum cleaner serial#5372 has electrical short				
David Vega	a					
12/1/2014	3:28:24 PM				Page ?	10 of 195

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By L Area Deferred By Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	ES					
120333			8/3/2014		120		\$0.00
Medium	Work In Progress		8/3/2014 12:33:36 AM				
Munoz, Mio	chael	Yearly - Anthony ES Fire Ext. Insp. PMschedule details.	(Yearly) - Refer to				
Margret Vi	llalobos						
120090			7/31/2014		123		\$0.00
Medium	Work In Progress	OLD	7/31/2014 9:54:14 AM				
Sotelo, Da	niel	INSTALL WINDOW BLINDS (SMAL WINDOWS (6) IN CAFETERIA	LL SLATS) IN				
Margaret \	/illalobos		- // - / /				<u> </u>
121107			8/13/2014		110		\$0.00
Medium	Work In Progress	SPED	8/13/2014 11:34:37 AM				
Sotelo, Da	niel	INSTALL SMALL SLAT WINDOW E AE CAFETERIA TO DECREASE SU (PRESENTATIONS NOT VISIBLE E MUCH SUNLIGHT)	JNLIGHT				
Margaret \	/illalobos						
125413			11/12/2014		19		\$0.00
Medium	Work In Progress	SPED OFFICE	11/12/2014 7:24:29 AM				
Sotelo, Da	niel	NEED HEATER IN WOMEN'S BAT	HROOM				
Margaret \	/illalobos						
125664			11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 8:10:34 AM				
Sotelo, Da	niel	need to fix water leak in old cafeter line that go's to swamp coolers	ria by Alamo. water				
Daniel Sot	telo						
125919			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:41				
Sotelo, Da	niel	Monthly - Anthony ES Emer. Light ⁻ to PMschedule details.	Test: Monthly - Refer				
Margret Vi	llalobos						
125940			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:55				
Sotelo, Da	niel	Monthly - Anthony ES Exit Sign Ins PMschedule details.	o: Monthly - Refer to				
Margret Vil	llalobos						

WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Lo Area Deferred By Area Number Reason Description		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	ES					
124923			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:32 AM				
Sotelo, Da	aniel	Monthly - Anthony ES Emer. Light 1 to PMschedule details.	est: Monthly - Refer				
Margret Vi	llalobos						
124924			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:32 AM				
Sotelo, Da	aniel	Monthly - Anthony ES Exit Sign Insp PMschedule details.	o: Monthly - Refer to				
Margret Vi	llalobos						
124740			10/29/2014		33		\$0.00
Medium	Work In Progress		10/29/2014 3:17:03 PM				
Sotelo, Da		need to fixholes in drywall from old paint in room 311	white board and				
Daniel So	telo		44/0/0044				<u> </u>
125055			11/3/2014		28		\$0.00
Medium	Work In Progress	SPED OFFICE	11/3/2014 7:50:45 AM				
Sotelo, Da	aniel	PLEASE MOVE TWO LARGE BOXE SPED OFFICE TO THE SPED POF JULIE OR MARGARET FOR KEY)					
Margaret	Villalobos						
125058			11/3/2014		28		\$0.00
Medium	Work In Progress		11/3/2014 8:10:54 AM				
Sotelo, Da	aniel	need to reprogram lights theyare st	taying on all night				
Daniel So	telo						
125326			11/7/2014		24		\$0.00
Medium	Work In Progress		11/7/2014 3:44:38 PM				
Carrasco	Danny	att Danny C. need you to order me s you the request form thank you	ome tools all send				
Daniel So	telo						
125333			11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress		11/9/2014 12:41:27 AM				
Sotelo, Da	aniel	Monthly - Anthony ES Monthly Playo to PMschedule details.	ground Insp Refer				
Margret Vi	llalobos						

Margret Villalobos 125843 Medium Work In Progress Sotelo, Daniel need to playgrou Daniel Sotelo 123059 Medium Work In Progress Marquez, Gerardo KEEYS I Maritza Gonzalez 123529 Medium Work In Progress Sotelo, Daniel Yearly - PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Yearly - PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to	Anthony ES - Fire Pump e details. un some extensions cord nd for jumping balloon's	11/21/20 11/21/2014 10:4 rds from building to 9/23/2014 10:30:35	5 AM 014 023 014 5 AM		57		\$0.00
123640 Medium Work In Progress Holguin, Alfredo Monthly schedul Margret Villalobos 125843 Medium Work In Progress Sotelo, Daniel need to playgrou Daniel Sotelo 123059 Medium Work In Progress Marquez, Gerardo KEEYS I Maritza Gonzalez 123529 Medium Work In Progress Sotelo, Daniel Yearly - PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Yearly - PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Yearly - PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to	e details. un some extensions coro nd for jumping balloon's	10/5/2014 12:43:25 p Engine - Refer to PM 11/21/2 11/21/2014 10:4 rds from building to 9/23/2014 10:30:35 LE 132.	5 AM 014 023 014 5 AM		10		\$0.00
MediumWork In ProgressHolguin, AlfredoMonthly schedulMargret Villalobos125843MediumWork In ProgressSotelo, Danielneed to playgrouDaniel Sotelo123059MediumWork In ProgressMarquez, GerardoKEEYS IMaritza Gonzalez123529MediumWork In ProgressSotelo, DanielYearly - PMscheMargret Villalobos123531MediumWork In ProgressSotelo, DanielYearly - PMscheMargret Villalobos123531MediumWork In ProgressSotelo, DanielMonthly Refer to	e details. un some extensions coro nd for jumping balloon's	p Engine - Refer to PM 11/21/20 11/21/2014 10:40 rds from building to 9/23/2014 10:30:35 LE 132.	014 0:23 014 5 AM				
Margret Villalobos 125843 Medium Work In Progress Sotelo, Daniel need to playgrou Daniel Sotelo 123059 Medium Work In Progress Marquez, Gerardo KEEYS I Maritza Gonzalez 123529 Medium Work In Progress Sotelo, Daniel Yearly - PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Yearly - PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to	e details. un some extensions coro nd for jumping balloon's	11/21/20 11/21/2014 10:4 rds from building to 9/23/2014 10:30:35 LE 132.	0:23 014 5 AM				
125843 Medium Work In Progress Sotelo, Daniel need to playgrou Daniel Sotelo 123059 Medium Work In Progress Marquez, Gerardo KEEYS I Maritza Gonzalez 123529 Medium Work In Progress Sotelo, Daniel Yearly - PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to	nd for jumping balloon's	11/21/2014 10:44 rds from building to 9/23/2014 10:30:35 LE 132.	0:23 014 5 AM				
Medium Work In Progress Sotelo, Daniel need to playgroup Daniel Sotelo 123059 Medium Work In Progress Marquez, Gerardo KEEYS I Maritza Gonzalez 123529 Medium Work In Progress Sotelo, Daniel Yearly - PMscher Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Yearly - PMscher Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to	nd for jumping balloon's	11/21/2014 10:44 rds from building to 9/23/2014 10:30:35 LE 132.	0:23 014 5 AM				
Sotelo, Daniel need to playgrou Daniel Sotelo 123059 Medium Work In Progress Marquez, Gerardo KEEYS I Maritza Gonzalez 123529 Medium Work In Progress Sotelo, Daniel Yearly - PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to	nd for jumping balloon's	rds from building to 9/23/2 9/23/2014 10:30:35 LE 132.	014 5 AM		69		\$0.00
Daniel Sotelo 123059 Medium Work In Progress Marquez, Gerardo KEEYS I Maritza Gonzalez 123529 Medium Work In Progress Sotelo, Daniel Yearly - PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to	nd for jumping balloon's	9/23/20 9/23/2014 10:30:35 LE 132.	5 AM		69		\$0.00
123059 Medium Work In Progress Marquez, Gerardo KEEYS I Maritza Gonzalez 123529 Medium Work In Progress Sotelo, Daniel Yearly - PMscher Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to	OCKED IN SNP VEHICI	9/23/2014 10:30:35 LE 132.	5 AM		69		\$0.00
MediumWork In ProgressMarquez, GerardoKEEYS IMaritza Gonzalez123529MediumWork In ProgressSotelo, DanielYearly - PMscheitMargret Villalobos123531MediumWork In ProgressSotelo, DanielMorthly Refer to	OCKED IN SNP VEHICI	9/23/2014 10:30:35 LE 132.	5 AM		69		\$0.00
Marquez, Gerardo KEEYS Maritza Gonzalez 123529 Medium Work In Progress Sotelo, Daniel Yearly - PMschei Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to	OCKED IN SNP VEHICI	LE 132.					
Maritza Gonzalez 123529 Medium Work In Progress Sotelo, Daniel Yearly- PMscher Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to	OCKED IN SNP VEHICI		014 11				
123529 Medium Work In Progress Sotelo, Daniel Yearly - PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to		10/5/2	014 11				
MediumWork In ProgressSotelo, DanielYearly - PMscherMargret Villalobos123531MediumWork In ProgressSotelo, DanielMonthly Refer to		10/5/2	014 11				
Sotelo, Daniel Yearly - PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to			014 11	/5/2014	57		\$0.00
PMsche Margret Villalobos 123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to		10/5/2014 12:41:57	AM				
123531 Medium Work In Progress Sotelo, Daniel Monthly Refer to	Anthony ES U2 (Gas Hea dule details.	at)(Yearly) - Refer to					
Medium Work In Progress Sotelo, Daniel Monthly Refer to							
Sotelo, Daniel Monthly Refer to		10/5/2	014 11	/5/2014	57		\$0.00
Referto		10/5/2014 12:41:58	s AM				
Managet \ /illalahaa	Anthony ES A16 (Fan E PMschedule details.	Exhst.)(Semi. Ann.) -					
Margret Villalobos		- // - /-		/			
120884		8/10/2		10/2014	113		\$0.00
Medium Work In Progress		8/10/2014 12:25:12	AM				
	Anthony ES A9 (AC Cond nedule details.	denser)(Yearly) - Refer	Done, nee equipment			ne	
Margret Villalobos							
124897		11/2/2	014		29		\$0.00
Medium Work In Progress		11/2/2014 12:35:16	5 AM				
Villalobos, Margret Monthly PMsche	Anthony ES - Trane PM	Quarterly - Refer to	Emailed 1	1/3/14			

Marquez, Gera Jessica Lopez 125743 Medium Wo Marquez, Gera Margaret Villalo 125670 Medium Wo	z ork In Progress Irdo	Office Mr. Marquez, Please check office door, we are having trou it. SPED OFFICE	11/19/2014 11/19/2014 10:37:53 uble opening 11/19/2014	12	\$0.00
Medium Wo Marquez, Gera Jessica Lopez 125743 Medium Wo Marquez, Gera Margaret Villalo 125670 Medium Wo	ork In Progress	Mr. Marquez, Please check office door, we are having trou it. SPED OFFICE	11/19/2014 10:37:53 uble opening	12	\$0.00
Marquez, Gera Jessica Lopez 125743 Medium Wo Marquez, Gera Margaret Villalo 125670 Medium Wo	ork In Progress	Mr. Marquez, Please check office door, we are having trou it. SPED OFFICE	uble opening		
Jessica Lopez 125743 Medium Wo Marquez, Gera Margaret Villalo 125670 Medium Wo	z ork In Progress Irdo	Please check office door, we are having trou it. SPED OFFICE			
125743 Medium Wo Marquez, Gera Margaret Villalo 125670 Medium Wo	ork In Progress Irdo		11/19/2014		
Medium Wo Marquez, Gera Margaret Villalo 125670 Medium Wo	irdo		11/19/2014		
Marquez, Gera Margaret Villalo 125670 Medium Wo	irdo			12	\$0.00
Margaret Villalo 125670 Medium Wo			11/19/2014 10:10:48		
125670 Medium Wo	ohos	NEED KEY #221E FOR CABINET OR REP (J PORTER) SEE JULIE OR MARGARET	LACE LOCK		
Medium Wo	0003		11/18/2014	13	\$0.00
				13	Ф 0.00
	ork In Progress		11/18/2014 10:22:41		
Marquez, Gera	ırdo	DOOR IN STORAGE ROOM IN PATIO NEX ELECTRICAL ROOO 233 DOES NOT CLO	-		
David Vega			44/44/0044	47	<u> </u>
125572			11/14/2014	17	\$0.00
Medium Wo	ork In Progress	300 11	I/14/2014 1:42:46 PM		
Marquez, Gera	ırdo	Mr. Marquez, As per Ms. Perez we need a key for the des the IEP Room # 300 Thank you	sk located in		
Jessica Lopez	2			- 10	
125520			11/13/2014	18	\$0.00
Medium Wo	ork In Progress	11	I/13/2014 2:11:04 PM		
Marquez, Gera	irdo	Mr. Marquez, We are unable to open our mail boxplease	checkasap		
Jessica Lopez	2		0/5/0044	4.40	
120520			8/5/2014	118	\$0.00
Medium Wo	ork In Progress		8/5/2014 8:28:32 AM		
Estrada, Jesus	i	need set of tools hammer,channel locks, el screw drivers etc	llen wrenches		
David Vega			44/40/00/1	40	
125737			11/19/2014	12	\$0.00
Medium Wo	ork In Progress	11	1/19/2014 8:51:31 AM		
Solis, Lorenzo		need assistance to trouble shoot heat coil in the Alamo ASAP thank you	n room 109 in		
Daniel Sotelo					

WOID Priority Assigned	Building Status	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description	arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		Description	Action Taken			
Location:	Anthony	ES				
125454		11/12/2014		19		\$0.00
Medium	Work In Progress	11/12/2014 3:43:16 PM				
Solis, Lore	enzo	furnace in the boiler room in the alamo is not turnning on need help trouble shooting ASAP				
Daniel So	otelo					
125464		11/12/2014		19		\$0.00
Medium	Work In Progress	11/12/2014 3:54:17 PM				
Solis, Lore		Mr. Sotelo, Please adjust temperature in the offfice it is very cold				
Jessica L	opez	8/3/2014		100		\$0.00
120239				120		\$0.0C
Medium	Work In Progress	8/3/2014 12:32:31 AM				
Villalobos	-	Monthly - Anthony ES - Trane PM Quarterly - Refer to E PMschedule details.	Emailed 8/4/14			
Margret Vi	illalobos	11/0/0014				
124891		11/2/2014		29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:13 AM				
Orozco, Da		Yearly - Anthony ES - Grease Trap - Refer to PM schedule details.				
Margret Vi	illalobos					
123692		10/5/2014		57		\$0.00
Medium	Work In Progress	10/5/2014 12:44:04 AM				
Munoz, Mi	chael	Monthly - Anthony ES - Fire Sprinkler Insp Refer to PMschedule details.				
Margret Vi	illalobos					
125029		11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:35 AM				
Orozco, Da	aniel	Monthly - Anthony ES Fire Suppression Insp Refer to PMschedule details.				
Margret Vi	illalobos					
Count: 49	Work Orders	Avg. Age of WO's 47	Total for Anthon	y ES	0	\$0.00

Selected Dat WOID Priority Assigned 7 Requester	Building Status To	•	te Target Comp Date le Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino ES	5				
125030		11/2/20	14 11/23/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:35	AM			
Orozco, Da	aniel	Monthly - Berino ES Fire Suppression Insp Refer to PMschedule details.				
Margret Vil	lalobos					
123686		10/5/20	14 10/26/2014	57		\$0.00
Medium	Work In Progress	10/5/2014 12:43:59	AM			
Munoz, Mic	chael	Monthly - Berino ES Fire Sprinkler Insp Refer to PM schedule details.				
Margret Vil	lalobos					
118857		7/1/20	14	153		\$0.00
High	Work In Progress	7/1/2014 9:56:44	AM			
Munoz, Mic	chael	need to install new water gong fire bell. district electrician will provide power.				
Michael Mu	unoz					
120112		7/31/20	14	123		\$0.00
Medium	Work In Progress	7/31/2014 2:44:15	PM			
Sotelo, Enr	rique	MR ENRIQUE SOTELO SIR BREAKER ON AC UNIT ROOMS 105 AND 107 NEEDS TO BE REPLACE IT HAS A 20 AMP AND THE UNIT CALLS FOR A 25 AMP THANK YOU SIR AND GOD BLESS				
Adan Dura	in					
121143		8/13/20	14	110		\$0.00
High	Work In Progress	8/13/2014 3:44:29	PM			
Sotelo, Enr	rique	a new water gong bell will be installed in the main mechanical room by dimar systems. need to provide power.				
Michael Mu	unoz					
124886		11/2/20	14	29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:10	AM			
Orozco, Da	aniel	Yearly - Berino ES - Grease Trap - Refer to PM schedule details.				
Margret Vil	lalobos					
125839		11/21/20	14	10		\$0.00
Medium	Work In Progress	11/21/2014 9:19:34	AM			
Solis, Lorenzo		MR LORENZO SOLIS SIR HEATER PORTABLE 151 IS HOT WORKING CHECK BREAKERS WON'T START CAN YOU PLEASE CHECK THANK YOU AND GOD BLESS				
Adan Dura	in					
	2.20.24 DM					

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino Es	3				
125514		11/13/2014		18		\$0.00
Medium	Work In Progress	11/13/2014 12:57:09)			
Flores, Pe	te	MR PETE FLORES SIR THE BATTERY ON TRUCK 007 IS DEAD NEED A REPLACEMENT PLEASE THANK YOU SIR AND GOD BLESS				
Adan Dura	an					
120406		Custodial 8/4/2014		119		\$0.00
Medium	Work In Progress	8/4/2014 9:29:22 AN	1			
Flores, Pe	te	Leaf Blower (G.I.S.D 98-2229) needs repair, it does not want to start .				
Marin Her	rera					
125910		11/30/2014		1		\$0.00
Medium	Work In Progress	11/30/2014 12:46:35	5			
Duran, Ada	an	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PMschedule details.				
Margret Vi	llalobos					
125911		11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:46:35	5			
Duran, Ada	an	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PMschedule details.				
Margret Vi	llalobos					
123641		10/5/2014		57		\$0.00
Medium	Work In Progress	10/5/2014 12:43:26 AM	1			
Holguin, A		Monthly - Berino ES - Fire Pump Engine - Refer to PM schedule details.				
Margret Vi	llalobos					
125905		11/30/2014		1		\$0.00
Medium	Work In Progress	11/30/2014 12:46:31				
Duran, Ada	an	Monthly - Berino ES - Clothes Dryer (Monthly) - Refer to PMschedule details.				
Margret Vi	llalobos					
125331		11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress	11/9/2014 12:41:23 AM	1			
Duran, Ada	an	Monthly - Berino ES Monthly Playground Insp Refer to PMschedule details.				
Margret Vi	llalobos					

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loc Area Deferred By Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino ES	;					
120334			8/3/2014		120		\$0.00
Medium	Work In Progress		8/3/2014 12:33:37 AM				
Munoz, Mi	chael	Yearly - Berino ES Fire Ext. Insp. (Ye schedule details.	early) - Refer to PM				
Margret Vi	llalobos		11/0/0011				.
125221		Custodial	11/6/2014		25		\$0.00
Medium	Work In Progress		11/6/2014 9:58:22 AM				
Carbajal,	Jimmy	Cord is tangled bad on Vacuum (212	9) and shorting out				
Marin Her	rera						
126017			11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:45				
Duran, Ada	an	Monthly - Berino ES Monthly FE Inps PMschedule details.	ection - Refer to				
Margret Vi	llalobos						
125009			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:22 AM				
Orozco, Da	aniel	Monthly - Berino ES Range Hood Cl PMschedule details.	eaning - Refer to				
Margret Vi	llalobos						
125980			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:21				
Apodaca,	Mario	Monthly - Berino ES - Monthly Meter PMschedule details.	Readings - Refer to				
Margret Vi	llalobos						
124129			10/14/2014		48		\$0.00
Medium	Work In Progress		10/14/2014 10:08:48				
Orozco, Da	aniel	OVEN DOWN. SNP MANAGER ELS	A C. 882.2417				
Maritza Go	onzalez						
Count: 20	Work Orders	Avg. Age of WO's 48		Total for Berin	o ES	0	\$0.00

WOID Priority Assigned Requester	Building Status To	•		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	IES					
124735		10/2	9/2014		33		\$0.00
Medium	Work In Progress	10/29/2014 12	2:28:02				
Orozco, Da	aniel	BROKEN GASKETS ON FREEZER AND WARMER. SNP MANAGER ESTHER C. 824.0048					
Maritza Go	onzalez						
125345		11/	/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress	11/9/2014 12:41	1:43 AM				
Quinones		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.					
Margret Vi	llalobos	10/0	4/0044				.
124382			1/2014		41		\$0.00
Medium	Work In Progress	10/21/2014 9:56	5:01 AM				
Ronquillo,	, Ruben	need playground hardware,if you could please send donnie gonzalez for samples of what i need thanks.					
Paul Quin	ones						
123783		10/	7/2014		55		\$0.00
Medium	Work In Progress	10/7/2014 8:55	5:51 AM				
Orozco, Da	aniel	DISHWASHER IS LEAKING. SNP MANAGER ESTHER C. 824.0048					
Maritza Go							
121424	Main Building	Office 8/1	9/2014		104		\$0.00
Medium	Work In Progress	concession 8/19/2014 1:31	1:30 PM				
Quinones	, Paul	need changing table moved from Chaparral Elementary to GSAC room 109 to Ms. Ruiz. See front office or Mrs. Pargas					
Jennifer C	Corral						
125010		11/2	/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36	5:23 AM				
Orozco, Da	aniel	Monthly-Chapparal ES Range Hood Cleaning - Refer to PMschedule details.					
Margret Vi	llalobos						
124828			1/2014		31		\$0.00
Medium	Work In Progress	10/31/2014 9:03	3:35 AM				
Munoz, Mio		Parking lot fence line damaged by vehicle. (Case# 2014-10812 J. Espana #989)					
Paul Quin	ones						

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	cation, Status Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	I ES					
125602			11/14/2014		17		\$0.00
Medium	Work In Progress		11/14/2014 4:03:25 PM				
Munoz, Mio	chael	4'fence line in front of school was run damaged next to sidewalk in front of school	overed and				
Paul Quin	ones						
120335			8/3/2014		120		\$0.00
Medium	Work In Progress		8/3/2014 12:33:38 AM				
Munoz, Mie		Yearly - Chaparral ES Fire Ext. Insp. PMschedule details.	(Yearly) - Refer to				
Margret Vi	lalobos		11/20/2011	4.0/0/2044	4		¢0.00
125994			11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:30				
Quinones	, Paul	Monthly - Chaparral ES Monthly FE I PMschedule details.	npsection - Refer to				
Margret Vi	lalobos		44/0/0044	4.4.10.10.04.4			<u> </u>
124998			11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:15 AM				
Quinones		Monthly - Chaparral ES Monthly FE I PMschedule details.	npsection - Refer to				
Margret Vi	lalobos		10/20/2014		22		¢0.00
124774			10/30/2014		32		\$0.00
Medium	Work In Progress		10/30/2014 12:24:34				
Villalobos	, Margret	scorpions in class rms 206 and 208		waiting on waiver for	rm.		
Paul Quin	ones		11/00/0011				* •••••
125950			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:01				
Quinones	, Paul	Monthly - Chaparral ES - Clothes Dr Refer to PMschedule details.	yer (Monthly) -				
Margret Vi	lalobos						
125972			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:16				
Quinones	, Paul	Monthly - Chaparral ES Exit Sign Ins to PMschedule details.	p: Monthly - Refer				
Margret Vi	lalobos						

Selected Da WOID Priority Assigned	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	II ES				
123161		9/24/2014		68		\$0.00
Medium	Work In Progress	9/24/2014 11:15:46 AM	l			
Quinones,	, Paul	reorder,and replace exhaust fan motors in classroom rest rooms in the 100 wing.				
Paul Quine	ones					
120305		8/3/2014	8/11/2014	120		\$0.00
Medium	Work In Progress	8/3/2014 12:33:17 AV	I			
Quinones,	, Paul	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PMschedule details.				
Margret Vil	lalobos					* ••••
124971		11/2/2014		29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:59 AV	l			
Quinones,		Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PMschedule details.				
Margret Vil	lalobos	11/2/2014	11/10/2014	29		\$0.00
Medium	Mark In Drograda	11/2/2014 12:36:00 AV		23		φ0.00
Quinones,	Work In Progress Paul	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PMschedule details.	I			
Margret Vil	lalobos					
124762		10/29/2014		33		\$0.00
Medium	Work In Progress	10/29/2014 3:55:01 PM				
Quinones,	, Paul	reorder module boards for roof top heaters				
Paul Quine	ones					
124069		10/13/2014		49		\$0.00
Medium	Work In Progress	10/13/2014 11:52:13	i de la construcción de la constru			
Quinones,	, Paul	filters for heaters winter season				
Paul Quine	ones					
124497		10/23/2014		39		\$0.00
Medium	Work In Progress	10/23/2014 7:45:46 AN	I			
Quinones,	, Paul	need snap disclimit controls for wall furnaces				
Paul Quine	ones					
124462		10/22/2014		40		\$0.00
Medium	Work In Progress	10/22/2014 1:27:50 PM				
Quinones,	, Paul	need to replace emergency light exit unit combo,monthly schedule p/m's				
Paul Quine	ones					
	2.29.25 DM					

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	al FS					
125569	enaparre		11/14/2014		17		\$0.00
Medium	Work In Progress		11/14/2014 1:07:06 PM				\$0.00
Marquez, (-	double doors located on the west s cafeteria doors are hard to open w	ide of building next to				
Paul Quin	ones		,				
125070	Main Building	Office	11/3/2014		28		\$0.00
Medium	Work In Progress	office	11/3/2014 9:53:38 AM				
Marquez, (Gerardo	need one keyto open all doors. se Principal	e Mrs. Pargas				
Jennifer C							
122854	WestCentral	Classroom	9/16/2014		76		\$0.00
Medium	Work In Progress	402	9/16/2014 3:28:45 PM	I			
Marquez, (Gerardo	Lost keyand need as soon as poss to secretary. See Ms. Jackson	sible. Wrote a letter				
Jennifer C	orral						
125893			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:23				
Quinones		Monthly - Chaparral ES A-2 Quarte schedule details.	rly H/C - Refer to PM				
Margret Vi	llalobos		0/40/0044				.
121112			8/13/2014		110		\$0.00
Medium	Work In Progress		8/13/2014 1:08:27 PM				
Marquez, (teacher in class rm.306,key will no coming from outside 300 wing.teac					
Paul Quin	ones		11/10/0011		10		<u> </u>
125444			11/12/2014		19		\$0.00
Medium	Work In Progress		11/12/2014 2:58:22 PM				
Solis, Lore	enzo	not heat reznor heater in the 100 wi	ng				
Paul Quin	ones						
123014			9/19/2014		73		\$0.00
Medium	Work In Progress		9/19/2014 4:04:07 PM	I			
Vallejo, All		need a electrical hand dryer boys broken element	rest rm. 120 volt				
Paul Quin	ones						

VOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	al ES				
121386		8/18/2014		105		\$0.00
Medium	Work In Progress	8/18/2014 4:01:38 PM				
Vallejo, Al	bert	need a new lamp 2x4 type lamp in principles office,3 lamp				
Paul Quin	iones					
124887		11/2/2014		29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:10 AM				
Orozco, Da	aniel	Yearly - Chaparral ES - Grease Trap - Refer to PM schedule details.				
Margret Vi	illalobos					
122825		9/16/2014		76		\$0.00
Medium	Work In Progress	9/16/2014 10:49:15 AM				
Appelzolle	er, Fred	requesting self closing drinking fountain 1/2"female connection type.				
Paul Quin	iones		/ . /			
126020		11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:47				
Quinones		Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PMschedule details.				
Margret Vi	illalobos					.
125051		11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:48 AM				
Quinones		Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vi 120378	illalobos	8/3/2014	8/11/2014	120		\$0.00
Medium	Work In Progress	8/3/2014 12:34:07 AM	0/11/2014	120		ψ0.00
Quinones	C C	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PMschedule details.				
Margret Vi	illalobos					
125031		11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:36 AM				
Orozco, Da	aniel	Monthly-Chaparral ES Fire Suppression Insp Refer to PMschedule details.				
Margret Vi	illalobos					
Count: 36	Work Orders	Avg. Age of WO's 45	Total for Chaparr	al ES	0	\$0.00

WOID Priority Assigned Requeste	Building Status To r Name	Dates:7/1/2014 - 11/30/2014 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken		Labor Hours	Costs
Location:	Chaparra	ll High - Pre-K					
121223			8/14/2014		109		\$0.00
Medium	Work In Progress		8/14/2014 3:58:37 PM				
Vallejo, A	lbert	rm.218 emergency light upgrade res	trm hallway				
Paul Quir	nones						
119691		Classroom	7/22/2014		132		\$0.00
Medium	Work In Progress		7/22/2014 9:21:08 AM				
Solis, Lor	enzo	Having problom with A/C unit can't ge 103 Pre-K.	t it going Room				
Alfredo O	rtiz						
125638			11/17/2014		14		\$0.00
High	Work In Progress	Office, Rooms	11/17/2014 3:12:26 PM				
Ortiz, Alfre	edo	Heating system isn't turning on. Nee ASAP due to cold weather.	ds to be repaired				
Micaela P	aniagua						
125712		Mechanical	11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 3:45:59 PM				
Ortiz, Alfre	edo	Need to replace heating filters at Pre-	-К.				
Alfredo O	rtiz						
120159			8/1/2014		122		\$0.00
Medium	Work In Progress	building back	8/1/2014 8:03:09 AM				
Marquez,	Gerardo	Repair the back entrance door to the handle is broken and having trouble unlocking the door.					
Noemi Du	uron						
Count: 5 V	Vork Orders	Avg. Age of WO's 78	Total for	r Chaparral High - P	Pre-K	0	\$0.00

Selected Da WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Tota Costs
Location:	Chaparra	al HS					
125551	R-Wing	Classroom	11/14/2014		17		\$0.00
Medium	Work In Progress		11/14/2014 7:53:56 AN	1			
Carrasco,	, Danny	Attention to Warehouse Need to b heaters for Q-2.	orrow two portable				
Alfredo Or	rtiz						
123340			9/29/2014		63		\$0.00
Medium	Work In Progress		9/29/2014 8:09:29 AN	1			
Marquez,	Gerardo	We will need to add door openers	to 4 doors:				
		1. The east exit door by the wall of 2. The west exit door by the wall of 3. The east exit doors (2 doors – one into the building) by the wall	on Wing F. one into the foyer and				
Alfredo Ho	<u> </u>	· · · · · - · · ·					
121690	Field House	Athletic Field	8/25/2014		98		\$0.00
Medium	Work In Progress	Baseballshed	8/25/2014 10:20:10 AN	1			
Marquez,		Requesting a metal door with kno system to secure inventory of equ shed. Please see Gregg Martine report. (Mr. Martinez, baseball sh	ipment in baseball zfor pictures and				
Mireya Me		Office	10/10/2014		46		¢0.00
124236	A-Wing	Office	10/16/2014		46		\$0.00
Medium Marquez,	Work In Progress Gerardo	Front reception The left side door right in front of the not locking properly. (Mireya Mez					
Mireya Me	za		,				
121551	R-Wing	Foyer	8/20/2014		103		\$0.00
Medium	Work In Progress	Front Door to R	8/20/2014 4:24:57 PM	1			
Marquez,	Gerardo	The right side front door going into broken latch. (Mireya Meza)	o the R building has a				
Mireya Me	za						
119780		Athletic Field	7/24/2014		130		\$0.00
Medium	Work In Progress		7/24/2014 7:57:00 AN	1			
Gonzalez,	Salvador	fertilizer spreader handle needs t	o be weld.				
Guadalup	e Ontiveros						
124825		Exterior	10/31/2014		31		\$0.00
Medium	Work In Progress		10/31/2014 7:50:32 AN	1			
Gonzalez,	Salvador	Main gate for bus entrance broker welded.	n. Need to replace hing				
Alfredo Or	tiz						
	1 2.20.25 DM						

12/1/2014 3:28:25 PM

WOID Priority Assigned Requester	Building Status To		nte Target Comp Date ne Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Chaparra	IHS				
125985		11/30/20)14	1		\$0.00
Medium	Work In Progress	11/30/2014 12:47	24			
Apodaca,	Mario	Monthly - Chaparral HS - Lift Station Inspection - Refer to PMschedule details.				
Margret Vi	llalobos					
124978		11/2/20)14	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:03	AM			
Apodaca,	Mario	Monthly - Chaparral HS - Lift Station Inspection - Refer to PMschedule details.				
Margret Vi	llalobos					
126001		11/30/20)14	1		\$0.00
Medium	Work In Progress	11/30/2014 12:47	7:35			
Ortiz, Alfre		Monthly - Chaparral HS Monthly FE Inspection - Refer to PMschedule details.				
Margret Vi	llalobos	44.0.00				* • • • •
124997		11/2/20		29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:15	AM			
Ortiz, Alfre		Monthly - Chaparral HS Monthly FE Inspection - Refer to PMschedule details.				
Margret Vi	llalobos	11/0/07	44/00/0044			* 0.00
125006		11/2/20		29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:20	AM			
Orozco, Da		Monthly- Chaparral HS Range Hood Cleaning - Refer to PMschedule details.				
Margret Vi						
123160	A-Wing	Library 9/24/20)14	68		\$0.00
High	Work In Progress	Library 9/24/2014 10:26:33	AM			
Estrada, J	esus	Please replace carpet. Alfredo Ortiz will be removing section that was wet due to foundation leak.				
Mireya Me	za					<u> </u>
120350		8/3/20		120		\$0.00
Medium	Work In Progress	8/3/2014 12:33:48	AM			
Munoz, Mie	chael	Yearly - Chaparral HS Fire Ext. Insp. (Yearly) - Refer to PMschedule details.				
Margret Vi	llalobos					

WOID Priority Assigned		Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	I HS						
125601	Field House	Mechanical		11/14/2014		17		\$0.00
Medium	Work In Progress			11/14/2014 3:56:48 PM				
Ortiz, Alfred	do	Need to replace	e filters at Field hou	se heaters.				
Alfredo Ort	tiz							
125877	A-Wing	Mechanical		11/21/2014		10		\$0.00
Medium	Work In Progress			11/21/2014 3:52:39 PM				
Ortiz, Alfred	do	Need to replace breaker on fauc	e washers on floor ets.	sink and vacuum				
Alfredo Ort	·							
124126	R-Wing	Classroom		10/14/2014		48		\$0.00
Medium	Work In Progress	R4		10/14/2014 9:49:11 AN	l			
Ortiz, Alfree	do	Please install t Holguin, R4)	wo bulletin boards	and move one. (Ms.				
Mireya Mez								
124772	A-Wing	Gym		10/30/2014		32		\$0.00
Medium	Work In Progress	Gym		10/30/2014 12:01:03				
Ortiz, Alfred		Please put up Rupcich)	he soccer banner	in the gym. (Mr.				
Mireya Mez		Liberry		0/04/0044		<u></u>		¢0.00
123153	A-Wing	Library		9/24/2014		68		\$0.00
High	Work In Progress	Library		9/24/2014 9:38:44 AN				
Ortiz, Alfred	do	MOLDING DUE RECENT RAIN	TO FOUNDATION STORMS. MOLDIN O STUDENTS AN	IG AND SMELL IS				
Mireya Mez								
125747	B-Wing	Classroom		11/19/2014		12		\$0.00
Medium	Work In Progress			11/19/2014 11:05:42				
Ortiz, Alfred	do	Need to replace stopped workir	e electrical heater i g.	n Sped restroon				
Alfredo Ort								
124612	Field House	Office		10/27/2014		35		\$0.00
Medium	Work In Progress			10/27/2014 10:11:00	1			
Ortiz, Alfred	do tiz	Need to install room.	wonew sink mirro	rs in both trainers				

Selected Da WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By L Area Deferred By Area Number Reason Description	Until Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	II HS					
125914			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:3	7			
Ortiz, Alfree	do	Monthly - Chaprral HS Exit Sign In PMschedule details.	sp: Monthly - Refer to				
Margret Vi	llalobos						
125915			11/30/2014	12/31/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:3	8			
Ortiz, Alfree	do	Monthly - Chaparral HS Bleacher PMschedule details.	Inspection - Refer to				
Margret Vi	llalobos		1.1/0.0/0.01				* • • • •
125918			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:4	0			
Ortiz, Alfree	do	Monthly - Chaparral HS - Clothes Refer to PMschedule details.	Dryer (Monthly) -				
Margret Vi	llalobos						
125275		Exterior	11/7/2014	ļ	24		\$0.00
Medium	Work In Progress		11/7/2014 10:15:16 AM	M			
Ortiz, Alfre	do	Need to replace door sweeps on s	everal doors.				
Alfredo Or	tiz						
124920			11/2/2014	Ļ	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:30 AM	Ν			
Ortiz, Alfree	do	Monthly - Chaprral HS Exit Sign In PMschedule details.	sp: Monthly - Refer to				
Margret Vi	llalobos						
124829		Kitchen	10/31/2014	ļ	31		\$0.00
Medium	Work In Progress		10/31/2014 9:08:50 AM	N			
Villalobos	, Margret	Need Pest Control to come to Kitch traps some heve mice.	nen to replace mouse	Emailed 11/13/14			
Alfredo Or							
123156	A-Wing	Library	9/24/2014	Ļ	68		\$0.00
High	Work In Progress	Library	9/24/2014 10:07:24 AM	Ν			
Holguin, A	lfredo	URGENT: Repair foundation gap t to leak onto library flooring. (Ms. I		9/29/14 Not a warra Alfredo. Thanks. RC		please ta	lk to
Mireya Me	za						

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	al HS					
123638			10/5/2014		57		\$0.00
Medium	Work In Progress		10/5/2014 12:43:23 AM	1			
Holguin, Al	fredo	Monthly - Chaparral HS - Fire Pu PMschedule details.	Imp Engine - Refer to				
Margret Vil	lalobos						
125603			11/15/2014		16		\$0.00
Medium	Work In Progress		11/15/2014 12:45:32	2			
Flores, Pet	e	Yearly - Chaparral HS M-0405 (Refer to PMschedule details.	Z-Track) Grounds -				
Margret Vil							<u> </u>
123083	A-Wing	Library	9/23/2014		69		\$0.00
Medium	Work In Progress	Library	9/23/2014 3:15:03 PM	1			
Marquez, G		Please unbolt 2 library shelf units can be moved away from water 1 DeVine, library)					
Mireya Mez	za Field House	Athletic Field	11/13/2014		18		\$0.00
125511		Aumene riela			10		Φ 0.00
Medium	Work In Progress		11/13/2014 12:03:10				
Solis, Lore	nzo	Need to fixice maching at field ho	ouse snak bar				
Alfredo Ort							
125512	Q-Wing	Classroom	11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 12:05:50)			
Solis, Lore	nzo	Heater in Q-2 not working.					
Alfredo Ort	iz						
125071	A-Wing	Office	11/3/2014		28		\$0.00
Medium	Work In Progress	Dr. Roskosky's	11/3/2014 10:06:31 AM	1			
Solis, Lore	nzo	No air is coming out of AC. Offic Roskosky, counselor)	ce is very warm. (Dr.				
Mireya Mez	za		0/17/00/1				
122910		Football Field	9/17/2014		75		\$0.00
Medium	Work In Progress		9/17/2014 12:08:33 PN				
Vallejo, Alb		Need to run electricity from pres Bleachers at football fiald.	s-box to front of				
Alfredo Ort		Classman	0/04/0044		100		@
121594	B-Wing	Classroom	8/21/2014		102		\$0.00
Medium	Work In Progress		8/21/2014 3:32:10 PM	1			
Vallejo, Alb	pert	Need to install new wall outlet in l	B-2 classroon.				
Alfredo Ort	iz						

Assigned ⁻ Requester		Area Number Reason Description	Created Date/Time Ad	ctual Comp Date Aged Action Taken	Hours	
Location:	Chaparra	IHS				
125496	Q-Wing	Classroom	11/13/2014	18		\$0.00
Medium	Work In Progress	Q3	11/13/2014 8:41:40 AM			
Vallejo, Alt	pert	One electrical unit in classro student computers. Please a possible. (Ms. Campbell, Q3	address as soon as			
Mireya Mez	za					
119549	Field House	Restroom	7/17/2014	137		\$0.00
Medium	Work In Progress		7/17/2014 3:54:07 PM			
Vallejo, Alt	pert	Need to replace several light restrooms and waight room.	switches in Field house			
Alfredo Ort	iz					
119901			7/28/2014	126		\$0.00
Medium	Work In Progress		7/28/2014 10:48:00 AM			
Vallejo, Alt	pert	PLEASE CHECK EXTERIOR NORTH TOWARDS FOOTB/ NOT WORKING, CONTRAC THEM.	ALL FIELD, THEY ARE			
Alfredo Ho	Iguin					
125274	A-Wing	Library	11/7/2014	24		\$0.00
Medium	Work In Progress	Library	11/7/2014 9:38:20 AM			
Vallejo, Alt	pert	Several lights on back wall no (Ms. DeVine, library)	eed replacement bulbs.			
Mireya Mez	za					
125723		Restroom	11/18/2014	13		\$0.00
Medium	Work In Progress		11/18/2014 4:00:46 PM			
Ortiz, Alfred	ob	Need to paint restrooms and graffitty.	exterior walls to remove			
Alfredo Ort						
121794	Field House	Dressing Room	8/26/2014	97		\$0.00
Medium	Work In Progress		8/26/2014 3:03:15 PM			
Vallejo, Alt	pert	do not have power to exaults	st fans will not start.			
Alfredo Ort	iz					
122946	R-Wing		9/18/2014	74		\$0.00
Medium	Work In Progress		9/18/2014 7:52:08 AM			
Appelzolle	r, Fred	Welding Shop-pressure tes oxygen and acetylene gas lin check with Mr. Lawler, he has	es to welding stations-			

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	al HS					
124773	R-Wing	Classroom	10/30/2014		32		\$0.00
Medium	Work In Progress	R-Kitchen	10/30/2014 12:10:16				
Appelzollei	r, Fred	Handsink is missing hot water ar off because it runs as if the wate our state inspection this needs to culinaryclass needs to use it in e assignments. (Ms. Davis, R-Kitc	r was turned on. Per be fixed ASAP as our veryday class room				
Mireya Mez							
119847	G-Wing	Classroom	7/25/2014		129		\$0.00
Medium	Work In Progress		7/25/2014 10:24:10 AM				
Appelzollei	r, Fred	Need to replace soilinoid and ba leaking in G-6 science classroon water valve to wing.					
Alfredo Ort	iz						
125746	R-Wing	Classroom	11/19/2014		12		\$0.00
Medium	Work In Progress		11/19/2014 11:02:22				
Appelzollei		In art class room Q-Build. Needs drain-pipes for a indoor power wa					
Alfredo Ort	IZ A-Wing	Destroom (Cirlo)	10/9/2014		53		\$0.00
123910	-	Restroom (Girls)			55		Ф 0.00
Medium	Work In Progress		10/9/2014 7:39:07 AM				
Appelzolle		Need to replace 4 toilets cracked locker room, and 3 in cafeteria gir					
Alfredo Ort	iz		11/0/0011		20		\$0.00
124890			11/2/2014		29		Ф 0.00
Medium	Work In Progress		11/2/2014 12:35:12 AM				
Orozco, Da		Yearly - Chaparral HS - Grease schedule details.	Frap - Refer to PM				
Margret Vil	lalobos		1.1.100.100.1.1	10/0/0011			* ••••
125887			11/30/2014	12/3/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:18				
Ortiz, Alfred		Monthly - Chaparral HS - Emer. Refer to PMschedule details.	Eyewash (Monthly) -				
Margret Vil							
124130	B-Wing		10/14/2014		48		\$0.00
Medium	Work In Progress		10/14/2014 10:14:54				
Marquez, G	Serardo	Need to fix cylinder on door key g	jets stuck				
Alfredo Ort	iz						

WOID Priority Assigned - Requester		Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	I HS						
124546	F-Wing	Classroom		10/23/2014		39		\$0.00
Medium	Work In Progress	F3		10/23/2014 3:50:19 PM				
Marquez, (Gerardo	is to open the b	reaker boxin his roo in that room. This o	n F3. AL101, this key om as the electricity auses problems with				
Mireya Mez								
125785	Field House	Athletic Field		11/19/2014		12		\$0.00
Medium	Work In Progress	Tennis Courts		11/19/2014 5:18:19 PM				
Marquez, (Gerardo	welded. The w		t #4 needs to be re- ne wrong side of the oach Ruiz, tennis				
Mireya Mez								
125112	H-Wing	Gym		11/3/2014		28		\$0.00
Medium	Work In Progress			11/3/2014 3:47:28 PM				
Marquez, O	Gerardo	Need to make	keys for Amplifier b	oxin Gym.				
Alfredo Ort	iz							
125367	B-Wing	Classroom		11/10/2014		21		\$0.00
Medium	Work In Progress	B2		11/10/2014 1:53:32 PM				
Marquez, (Gerardo		en getting stuck, I ca r. Inchaurriga, B2)	an't open B2 or the				
Mireya Mez	za							
124830		Hallway/Corrid	or	10/31/2014		31		\$0.00
Medium	Work In Progress			10/31/2014 9:10:44 AM				
Marquez, O	Gerardo	Need to install	cylinders for doors t	o the serving lines.				
Alfredo Ort	iz							
125719	A-Wing	Office		11/18/2014		13		\$0.00
Medium	Work In Progress	Diana's office		11/18/2014 3:55:31 PM				
Marquez, 0	Gerardo	Please rekeyD up. (Mireya Me		ke extra keyfor back				
Mireya Mez	za							
124831	A-Wing	Office		10/31/2014		31		\$0.00
Medium	Work In Progress	Nurse office		10/31/2014 9:23:18 AM				
Marquez, (Serardo	•	he nurse's filing ca e. (Fireking, Medeco					

Selected Date Range for Request WOID Building Priority Status	Area Deferred		Target Comp Date	Days Aged	Labor Hours	Costs
Priority Status Assigned To	Area Number Reason Description	Created Date/Time	Action Taken			
Requester Name			Action ruken			
Location: Chaparra	II HS					
124515 B-Wing	Storage	10/23/2014		39		\$0.00
Medium Work In Progress	2.2.2.32	10/23/2014 1:39:32 PM	I			+
Marquez, Gerardo	Need to replace key Cilindo open door.					
Alfredo Ortiz						
125513 A-Wing		11/13/2014		18		\$0.00
Medium Work In Progress		11/13/2014 12:07:33	5			
Marquez, Gerardo	At nurses office key broke	n in cabinet.				
Alfredo Ortiz						
125115	Exterior	11/3/2014		28		\$0.00
Medium Work In Progress		11/3/2014 3:49:24 PM	1			
Marquez, Gerardo	Need 5 new locks for gates	s need to be replaced.				
Alfredo Ortiz						
125431		11/12/2014		19		\$0.00
Medium Work In Progress		11/12/2014 11:13:15	i			
Flores, Pete	front and rear tires driver s	side of gator flat.				
Jesus Urquidi						
125191 A-Wing	Roof	11/5/2014		26		\$0.00
Medium Work In Progress		11/5/2014 3:33:46 PM	1			
Ortiz, Alfredo	Need to have sand remove	ed around A/C units.				
Alfredo Ortiz						
125225		11/6/2014		25		\$0.00
Medium Work In Progress		11/6/2014 10:53:09 AM	1			
Carbajal, Jimmy	need a sweeper for long m	ain hallway.				
Jesus Urquidi						
125053	Athletic Field	11/3/2014		28		\$0.00
Medium Work In Progress		11/3/2014 7:35:53 AM	1			
Valdez, Pedro	Need to fixbaseball bleach	ners bent and broken.				
Alfredo Ortiz						
119906 Field House	Athletic Field	7/28/2014		126		\$0.00
Medium Work In Progress	Main Soccer	7/28/2014 11:42:35 AM	1			
Valdez, Pedro		rass soccer field lined for this Ve are having and inter squad Coach Mendoza)				
Mireya Meza						

WOID	ate Range for Request Building	Area	Deferred By	Until Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time	-	Aged	Hours	
Assigned		Description			Action Taken			
Requester	r Name							
Location:	Chaparra	I HS						
124685	A-Wing	Office		10/28/2014		34		\$0.00
Medium	Work In Progress	Athletic Data		10/28/2014 2:54:52 PM				
Marquez, (Gerardo		keyhole and make r athletic data clerk offi	new keyfor file ce. (Diana Salazar)				
Mireya Me	za							
123349		Elevator		9/29/2014		63		\$0.00
Medium	Work In Progress			9/29/2014 12:06:17 PM				
Ontiveros,	Guadalupe	Need to bring <i>f</i> truck loads.	1/2 in. gravel for bus	entrance about 4				
Alfredo Or	tiz							
123693				10/5/2014		57		\$0.00
Medium	Work In Progress			10/5/2014 12:44:05 AM				
Munoz, Mio	chael	Monthly - Chap PMschedule d	arral HS - Fire Sprin etails.	kler Insp Refer to				
Margret Vi	llalobos							
123696				10/5/2014		57		\$0.00
Medium	Work In Progress			10/5/2014 12:44:07 AM				
Munoz, Mio	chael	Monthly - Chap Refer to PMsch	arral HS Pre-K- Fire nedule details.	Sprinkler Insp -				
Margret Vi	llalobos							
126019				11/30/2014		1		\$0.00
Medium	Work In Progress			11/30/2014 12:47:47				
Ortiz, Alfre	do	Monthly - Chap Refer to PMsch	arral HS Emer. Ligh nedule details.	t Test: Monthly -				
Margret Vi	llalobos							
125049				11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress			11/2/2014 12:36:47 AM				
Orozco, Da	aniel	Monthly-Chap to PMschedule	arral HS Fire Suppre details.	ssion Insp Refer				
Margret Vil	llalobos							
Count: 71	Work Orders	Α	vg. Age of WO's 4	3	Total for Chaparra	al HS	0	\$0.00

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	IMS					
121146			8/13/2014		110		\$0.00
High	Work In Progress		8/13/2014 3:45:54 PM	1			
Vallejo, All	bert	a new water gong will be installed in room by dimar systems. need to pro					
Michael M	unoz						
118858			7/1/2014		153		\$0.00
High	Work In Progress		7/1/2014 9:58:32 AN	1			
Munoz, Mio	chael	need to install new water gong bell for system. district electrician will provid					
Michael M	unoz						
123687			10/5/2014	10/26/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:44:00 AN	1			
Munoz, Mie		Monthly - Chaparral MS Fire Sprinkle PMschedule details.	er Insp Refer to				
Margret Vi	llalobos		44/0/0044	44/00/0044			<u> </u>
125032			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:36 AN	1			
Orozco, Da		Monthly - Chaparral MS Fire Suppre to PMschedule details.	ssion Insp Refer				
Margret Vil	llalobos		9/23/2014		69		\$0.00
Medium	Mork In Drogroop		9/23/2014 3:39:33 PM	A	03		ψ0.00
	Work In Progress		9/23/2014 3.39.33 FW	1			
Gallegos,		Roof leaks in 400 hallway.					
Albert Vall	ejo		44/0/0044	11/10/2014	29		\$0.00
124899			11/2/2014		29		Φ 0.00
Medium	Work In Progress		11/2/2014 12:35:17 AN	l			
Vallejo, All		Monthly - Chapparral MS Roof Inspe schedule details.	ection - Refer to PM				
Margret Vi			44/0/2044		05		¢0.00
125220	Main Building	Classroom	11/6/2014		25		\$0.00
Medium	Work In Progress	450	11/6/2014 9:52:25 AN	1			
Vallejo, All	bert	Water leak from ceiling in band room	1				
Gidget Mo		<u>.</u>					
123044	Main Building	Classroom	9/23/2014		69		\$0.00
Medium	Work In Progress	310	9/23/2014 8:49:37 AN	1			
Marquez, (Classroom door is hard to open and doors do not lock	unlock and cabinet				
Gidget Mo							
12/1/2014	3:28:25 PM					Page 3	35 of 195

Selected Da WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	al MS					
123436		Kitchen	10/1/2014		61		\$0.00
Medium	Work In Progress		10/1/2014 9:50:53 AN	1			
Marquez,	Gerardo	senesecita areglar candado dela #400/hallway GRACIAS	puerta dela salida del				
M. Carme	n Perez						
122690		Hallway/Corridor	9/12/2014		80		\$0.00
Medium	Work In Progress		9/12/2014 9:12:02 AN	1			
Marquez,	Gerardo	senesecita arglar chapa delas pu GRACIAS	uertas de 400/hallway				
M. Carme		•					
123710	Main Building	Classroom	10/6/2014		56		\$0.00
Medium	Work In Progress	310	10/6/2014 8:58:44 AN	1			
Marquez,	Gerardo	Cabinet locks are veryflims yand	can be easily opened				
Gidget Mo	ora						
123711	Main Building	Classroom	10/6/2014		56		\$0.00
Medium	Work In Progress	310	10/6/2014 9:04:11 AN	1			
Marquez,	Gerardo	Desk middle drawer is hard to ope stuck and wont lock.	en because the lock is				
Gidget Mo	ora						
123372			9/30/2014		62		\$0.00
Medium	Work In Progress		9/30/2014 12:51:19 AN	1			
Vallejo, Al	bert	Monthly - Chaparral MS A16 (Fan Refer to PM schedule details.	Exh.)(S.Annual) -				
Margret V	illalobos			/= /=			<u> </u>
123545			10/5/2014		57		\$0.00
Medium	Work In Progress		10/5/2014 12:42:10 AN	1			
Vallejo, Al		Yearly - Chaparral MS R9 (Radia PMschedule details.	tion)(Yearly) - Refer to				
Margret V	illalobos		44/00/0044	4.0/0/004.4	4		<u> </u>
125885			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:16	i			
Vallejo, Al		Monthly - Chaparral MS - Emerg. Refer to PMschedule details.	Eyewash (Monthly) -				
Margret V		Classroom	0.000000		445		<u> </u>
120809	Main Building	Classroom	8/8/2014		115		\$0.00
Medium	Work In Progress	205	8/8/2014 10:47:57 AN	1			
Appelzolle	er, Fred	pipes on sinks need to be fixed					
Gidget Mo	ora						
12/1/2014	4 3:28:25 PM					Page	36 of 195

WOID Priority Assigned 1 Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra							
	Chaparra			40/04/0044		- 04		<u> </u>
124812				10/31/2014		31		\$0.00
Medium	Work In Progress			10/31/2014 12:37:08	5			
Orozco, Da		Yearly - Chapa schedule detail		rap - Refer to PM				
Margret Vill				4.4./00/004.4				<u> </u>
125798	Main Building	Gym		11/20/2014		11		\$0.00
Medium	Work In Progress			11/20/2014 2:02:05 PM				
Sotelo, Enr			es not work on ma witches be change	in entry into gym. ed to toggle s witch				
Gidget Mor		0:		0/40/0044				<u> </u>
121010	Main Building	Gym		8/12/2014	_	111		\$0.00
Medium	Work In Progress	400 Hallway		8/12/2014 9:58:13 AN	1			
Vallejo, Alb	pert	Resume painti	ng of gym /400 hall	way				
Gidget Mor	a							
123347		Classroom		9/29/2014		63		\$0.00
Medium	Work In Progress	311		9/29/2014 11:05:45 AN	1			
Vallejo, Alb	ert	Electricaloutlet	s not covered					
Gidget Mor								
125799	Main Building	Classroom		11/20/2014		11		\$0.00
Medium	Work In Progress	301		11/20/2014 2:03:30 PM	l			
Solis, Lore	nzo	Very little to no	heat					
Gidget Mor	a							
125802	Main Building	Classroom		11/20/2014		11		\$0.00
Medium	Work In Progress	105		11/20/2014 2:27:53 PM	I			
Solis, Lore	nzo	Heater is not we	orking in classroon	ı				
Gidget Mor	a							
121096				8/13/2014		110		\$0.00
Medium	Work In Progress			8/13/2014 10:19:11 AN	1			
Solis, Lore	nzo	Pleaseinsulate	supplyducts on r	ew refrigeration units.				
Albert Valle	ejo							
125222	Main Building	Gym		11/6/2014		25		\$0.00
Medium	Work In Progress			11/6/2014 10:20:59 AN	1			
Vallejo, Alb	pert	Blue pads in the glued or re-bol		pards need to be re-				
Gidget Mor	a							

WOID Priority Assigned			Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	IMS						
124934				11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress			11/2/2014 12:35:38 AM				
Vallejo, Alt	pert	Monthly - Chapar to PMschedule d		Insp: Monthly - Refer				
Margret Vil	llalobos							
124935				11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress			11/2/2014 12:35:39 AM				
Vallejo, Alt	pert	Monthly - Chapar Refer to PMschee		ht Test: Monthly -				
Margret Vil								
122338	Main Building	Restroom (Girls)		9/4/2014		88		\$0.00
Medium	Work In Progress	Office ladies		9/4/2014 3:13:32 PM				
Vallejo, Alt	pert	Fan is broken-Ma	aking noise					
Gidget Mo	ra							
125912				11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress			11/30/2014 12:46:36				
Vallejo, Alt	pert	Monthly - Chapar to PMschedule d		Insp: Monthly - Refer				
Margret Vil	llalobos			11/00/0011				<u> </u>
125913				11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress			11/30/2014 12:46:37				
Vallejo, Alt		Monthly - Chapar Refer to PMschee		yht Test: Monthly -				
Margret Vil								
123056	Main Building	Classroom		9/23/2014		69		\$0.00
Medium	Work In Progress	311		9/23/2014 9:57:12 AM				
Vallejo, Albert Teacher has a couple of ceiling tiles that are stained and need to be replaced								
Gidget Mo								A
125168	Main Building	Classroom		11/5/2014		26		\$0.00
Medium	Work In Progress	107		11/5/2014 11:10:25 AM				
Vallejo, Alt	pert	Ms.Garcia needs the students	s therapeutic bike	assembled for one of				
Gidget Mo	ra							

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loca Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	I MS					
123067	Main Building	Classroom	9/23/2014		69		\$0.00
Medium	Work In Progress	205	9/23/2014 2:47:21 PM	1			
Vallejo, Alt	C C	Please replace ceiling tiles that are st mold	ained and with				
Gidget Mo	ra						
123709	Main Building	Classroom	10/6/2014		56		\$0.00
Medium	Work In Progress	310	10/6/2014 8:56:40 AN	l			
Vallejo, Alt	pert	Ceiling tiles have water spots					
Gidget Mo	ra						
125906			11/30/2014	12/31/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:32				
Vallejo, Alt	pert	Monthly - Chaparral MS Bleacher Ins PMschedule details.	pection - Refer to				
Margret Vil	llalobos						
125907			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:33				
Vallejo, Alt	pert	Monthly - Chaparral MS - Clothes Dry Refer to PMschedule details.	er (Monthly) -				
Margret Vil							
125797	Main Building	Classroom	11/20/2014		11		\$0.00
Medium	Work In Progress	103	11/20/2014 1:59:36 PM				
Vallejo, Alt	pert	Light fixture is falling off the ceiling					
Gidget Mo	ra						
125801	Main Building	Classroom	11/20/2014		11		\$0.00
Medium	Work In Progress	103	11/20/2014 2:08:48 PM				
Vallejo, Alt	pert	needs rubber sealing strip on outside sand blow in under door.	door. Dust and				
Gidget Mo	ra						
125846	Main Building	Restroom	11/21/2014		10		\$0.00
	Work In Progress		11/21/2014 1:47:29 PM				
Medium		Fans in restrooms are not working					
Medium Vallejo, Alt	pert	Women's Restroom in 100 hallway Mens Restroom in 300 hallway					
Vallejo, Alt Gidget Mo			11/20/2014		11		\$0.00
Vallejo, Alt	ra	Mens Restroom in 300 hallway	11/20/2014 11/20/2014 2:06:16 PM		11		\$0.00
Vallejo, Alt Gidget Mo 125800	ra Main Building Work In Progress	Mens Restroom in 300 hallway	11/20/2014 2:06:16 PM		11		\$0.00

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ad		Days Aged	Labor Hours	Costs
Location:	Chaparra	al MS					
120349			8/3/2014		120		\$0.00
Medium	Work In Progress		8/3/2014 12:33:48 AM				
Munoz, Mic	chael	Yearly - Chaparral MS Fire Ext. In: PMschedule details.	sp. (Yearly) - Refer to				
Margret Vil	llalobos						
125011			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:23 AM				
Orozco, Da		Monthly-Chapparal MS Range Ho to PM schedule details.	ood Cleaning - Refer				
Margret Vil		()	7/4 0/004 4		400		<u> </u>
119504	Main Building	Gym	7/16/2014		138		\$0.00
High	Work In Progress		7/16/2014 4:11:34 PM				
Estrada, Je		Replace warped floor boards in g	ym (southwest)				
Jesus Est	rada		11/00/0011	10/0/0011			.
126016			11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:45				
Vallejo, Alt		Monthly - Chaparral MS Monthly F to PMschedule details.	E Inpsection - Refer				
Margret Vil	llalobos		4.4.10.10.0.4.4				<u> </u>
124994			11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:13 AM				
Vallejo, Alt		Monthly - Chaparral MS Monthly F to PMschedule details.	E Inpsection - Refer				
Margret Vil	llalobos		7/40/0044		4.00		<u> </u>
119581		Athletic Field	7/18/2014		136		\$0.00
Medium	Work In Progress		7/18/2014 1:31:26 PM				
Ontiveros,	Guadalupe	playing fields need to be reseed a	s per site admin.				
	e Ontiveros						
124842			10/31/2014		31		\$0.00
Medium	Work In Progress		10/31/2014 2:26:36 PM				
Orozco, Da	aniel	The back doors to warmer seems from both top hinges. This could b takes forever to reach its holding to Manager Sandra D.824.4376	e why that warmer				
	nzalez						

Selected Da WOID	te Range for Request Building	Dates:7/1/2014 - 11/30/2014 Order Area Deferred By		Target Comp Date	Days	Labor	Costs
Priority Assigned	Status To	Area Number Reason Description	Created Date/Time	Actual Comp Date Action Taken	Aged	Hours	
Requester		·					
Location:	Chaparra	IMS					
120816	Main Building	Gym	8/8/2014	ļ.	115		\$0.00
Medium	Work In Progress		8/8/2014 11:17:35 A	И			
Gonzalez,	Salvador	Coach would like 3 tether ball outside basketball courts	poles installed near the	Route to Sal 10/22/1	4		
Gidget Mo	ra						
119869			7/25/2014	Ļ	129		\$0.00
Medium	Work In Progress		7/25/2014 3:18:22 PI	N			
Marquez, 0	Gerardo	Need new closers for south m	ain hall exit doors.				
Albert Vall	ejo						
118903			7/2/2014	ļ	152		\$0.00
Medium	Work In Progress		7/2/2014 12:29:48 PI	N			
Marquez, (Gerardo	Replace or repair gym south e	xitdoors				
Albert Vall	ejo						
123092	Main Building	Classroom	9/23/2014	ŀ	69		\$0.00
Medium	Work In Progress	205	9/23/2014 3:31:01 PI	N			
Marquez, 0	Gerardo	Please fix front door handle					
Gidget Mo	ra						
122894	Main Building	Classroom	9/17/2014	ŀ	75		\$0.00
Medium	Work In Progress	200	9/17/2014 9:32:09 A	Ν			
Marquez, (Gerardo	Door Slams shut every time, n	eeds to be adjusted				
Gidget Mo	ra						
120454	Main Building	Classroom	8/4/2014		119		\$0.00
Medium	Work In Progress	203	8/4/2014 1:56:06 PI	N			
Marquez, (Gerardo	Please repair all cabinet doors	s to close properly	8/13 route to Gerry			
Gidget Mo	ra						
	Work Orders	Avg. Age of WO	's 57	Total for Chaparra	I MS	0	\$0.00

Assigned To Requester Name	Area Number Reason Description	Greated Date/Time	Actual Comp Date Aged Action Taken	Hours
Location: Des	sert Pride HS			
124401	Portables	10/21/2014	41	\$0.00
Medium Work In Prog	ress room no.10	10/21/2014 12:25:05		
Marquez, Gerardo	Doorslams heavy and very closer as ap.	yhard. Need to replace door		
David Acosta				
125635		11/17/2014	14	\$0.00
Medium Work In Prog	ress	11/17/2014 2:12:32 PM		
Ambriz, Jose	Build ramp for Morgan.			
Michael Munoz				
125228	Portables	11/6/2014	25	\$0.00
Medium Work In Prog	ress room 19	11/6/2014 12:44:45 PM		
Marquez, Gerardo	door closer needs to be rep	blaced (doorslams)		
David Acosta				
123170	Gym	9/24/2014	68	\$0.00
Medium Work In Prog	ress GYMNASIUM	9/24/2014 3:12:51 PM		
Ronquillo, Ruben	1. ANCHOR BAG STANDS 2. INSTALL SPEED BAG T 3. ANCHOR BENCHES TO	O WALL.		
Yvette Cortez				
120715		8/7/2014	116	\$0.00
Medium Work In Prog	ress	8/7/2014 1:07:49 PM		
Duran, Adan	Portables - change out filte	rs to all a/c units.		
Michael Munoz				
125509	Gym	11/13/2014	18	\$0.00
Medium Work In Prog	ress	11/13/2014 11:15:13		
Duran, Adan	Boxing speed racks need to	obesetupingym		
Yvette Cortez				
124614	Parking Lot	10/27/2014	35	\$0.00
Medium Work In Prog	ress Student Parking	10/27/2014 11:00:13		
Ronquillo, Ruben	NEED SIGN IN STUDENT READS:	PARKING LOT THAT		
		v		
	STUDENT PARKING ONL	I		

WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description	Until Request Date Target Created Date/Time Actual	· · · · ·	Labor Hours	Costs
Location:	Desert P	ride HS				
124615		Parking Lot	10/27/2014	35		\$0.00
Medium	Work In Progress	STAFF &	10/27/2014 11:06:46			
Ronquillo	, Ruben	NEED PARKING LOT SIGN THA	T READS:			
		STAFF & VISITOR PARKING ON	LY			
Yvette Co	rtez					
125502		Portables	11/13/2014	18		\$0.00
Medium	Work In Progress	room 15	11/13/2014 9:28:35 AM			
Solis, Lor	enzo	heater is not turning on.				
David Acc	osta					
125741			11/19/2014	12		\$0.00
Medium	Work In Progress		11/19/2014 9:46:05 AM			
Solis, Lor	enzo	MR LORENZO SOLIS SIR PORT PORTABLE 9 HEATER ARE NO COLD CAN YOU PLEASE CHEC	T WORKING VERY			
Adan Dur	an					
124335			10/20/2014	42		\$0.00
Medium	Work In Progress		10/20/2014 10:31:12			
Duran, Ad	lan	PAINT LINES ON BASKETBALL	COURT.			
Yvette Co	rtez					
124725		Portables	10/29/2014	33		\$0.00
Medium	Work In Progress	room 1	10/29/2014 9:49:22 AM			
Sotelo, Er	nrique	need to replace ballast on two lig	htfixtures.			
David Acc	osta					
125438		Portables	11/12/2014	19		\$0.00
Medium	Work In Progress	room 18	11/12/2014 12:07:54			
Sotelo, Er	nrique	light fixture needs a lens cover				
David Acc	osta					
124443		Office	10/22/2014	40		\$0.00
Medium	Work In Progress	Conference Rm.	10/22/2014 9:41:40 AM			
Sotelo, Er	nrique	NEED CEILING OUTLET (ELEC INSTALLED TO CONNECT CEIL				
Yvette Co	rtez					

Yvette Cortez

WOID Priority Assigned Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert P	ride HS						
121923				8/28/2014		95		\$0.00
Medium	Work In Progress	11 & 12		8/28/2014 1:40:28 PM				
Appelzolle	er, Fred		CLOGGED IN POR XK TO SEE WHAT	RTABLE 11 & 12. IS CLOGGING THE				
Yvette Cor	rtez							
124127		Office		10/14/2014		48		\$0.00
Medium	Work In Progress	Conference Rn	n.	10/14/2014 9:54:48 AM				
Villalobos	, David	WATER LINE N MAKER.	IEEDS TO BE CO	NNECTED TO ICE				
Yvette Cor	rtez			11/10/0011		- 10		
125776				11/19/2014		12		\$0.00
Medium	Work In Progress			11/19/2014 3:49:54 PM				
Villalobos	, David	FOUNTAIN IS L	LEAKING NEED TI HE RIGHT TOOLS					
Adan Dura	an							
124388		Office		10/21/2014		41		\$0.00
Medium	Work In Progress	Conference Rn	n.	10/21/2014 10:30:05				
Villalobos	, David	Drainage line n	eeds to be installe	ed in conference rm. 1				
Yvette Cor	rtez							
121689		Classroom		8/25/2014		98		\$0.00
Medium	Work In Progress	101		8/25/2014 10:10:50 AM				
Marquez, (Gerardo	NEED KEY TO	READING LAB 18	0 IN ROOM 101.				
Yvette Cor	rtez							
120451				8/4/2014		119		\$0.00
Medium	Work In Progress			8/4/2014 1:51:09 PM				
Marquez, (Gerardo	drop off at Con have anyquest	struction office wh ions please conta	aster keys. Please en ready. Should you ct Mr. Ralph Gallegos ion office. Thank You				
Dominiqu	e Esnarza							

Dominique Esparza

WOID	Building	Area	1/30/2014 Order By Loc Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description			Action Taken			
Requeste	r Name							
Location:	Desert P	ride HS						
121338		Portables		8/18/2014		105		\$0.00
Medium	Work In Progress	1 & 2		8/18/2014 11:30:07 AN	Λ			
Marquez, (Gerardo	1 & 2 NEEDS T REPLACING C	DER TO STORGE RC TO BE REPLACED. A YLINDER, PLEASE (COTT AND MS. JAME	ALSO, WHEN GIVE STORAGE				
Yvette Cor	rtez							
125795		Portables		11/20/2014		11		\$0.00
Medium	Work In Progress	Portable 13 &		11/20/2014 11:09:41	1			
Marquez,	Gerardo	(MECHANICAL	EEN PORTABLES 13 & CLASSROOM DO ITS A TOTAL OF 6 D	ORS) NEED TO				
Yvette Cor	rtez							
122577		Portables		9/10/2014		82		\$0.00
Medium	Work In Progress	room#10		9/10/2014 1:29:31 PM	Л			
Marquez,	Gerardo	need to replace	doorcloser					
David Aco	sta							
123797				10/7/2014		55		\$0.00
Medium	Work In Progress			10/7/2014 10:48:30 AN	Λ			
Munoz, Mi	chael	order new tuff s	hed for custodial gate	or 12x12				
Alfredo Ho	olguin							
124563		Portables		10/24/2014		38		\$0.00
Medium	Work In Progress	15		10/24/2014 8:52:05 AN	Λ			
Acosta, Da	avid	White board ne	eds to be installed in	portable 15.				
Yvette Cor	rtez							
Count: 25	Work Orders	Α	vg. Age of WO's 49	•	Total for Desert Prid	le HS	0	\$0.00

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loc Area Deferred By Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Ti	rail ES					
123915			10/9/2014		53		\$0.00
Medium	Work In Progress		10/9/2014 9:00:01 AM				
Ontiveros,	, Guadalupe	Need to borrow tractor and scraper to school grounds (Desert Trail)	o clear up weeds in				
Johnny Ac	cuna						
121962			8/29/2014		94		\$0.00
Medium	Work In Progress		8/29/2014 11:22:18 AM				
Ontiveros,	, Guadalupe	Need to borrow tractor with scraper.					
Johnny Ac	una						
123562			10/5/2014	10/13/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:42:23 AM				
Acuna, Jo	hnny	Monthly - Desert Trail ES - Roof Inp PMschedule details.	section - Refer to				
Margret Vi	llalobos						
125121			11/3/2014		28		\$0.00
Medium	Work In Progress		11/3/2014 4:00:00 PM				
Flores, Pe		Need replacement battery for steine replace valve stem/fix flat to steiner					
Johnny Ac	cuna		44/5/0044				<u> </u>
125181			11/5/2014		26		\$0.00
Medium	Work In Progress		11/5/2014 2:44:50 PM				
Flores, Pe	ete	Please fix fuel gauge to work truck #	[‡] 192				
Johnny Ac							
125517	Main Building	Hallway/Corridor	11/13/2014		18		\$0.00
Medium	Work In Progress	hallway	11/13/2014 1:57:35 PM				
Marquez, (Gerardo	The hallwaydoors not working prope stuck.	erly, are getting				
	Hernandez						
124613		Custodial	10/27/2014		35		\$0.00
Medium	Work In Progress		10/27/2014 10:18:20				
Marquez, (Gerardo	Buenos dias gerardo la llave que me teniendo problemas para habrir una revisar por favor gracias					

Laura Sandoval

WOID Priority Assigned 7 Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loc Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ad		Days Aged	Labor Hours	Costs
Location:	Desert Ti	rail ES					
125573			11/14/2014		17		\$0.00
Medium	Work In Progress	119	11/14/2014 1:56:53 PM				
Marquez, G	Gerardo	Office needs a keys made (J-37)					
Elizabeth H	Hernandez						
121108			8/13/2014		110		\$0.00
Medium	Work In Progress		8/13/2014 11:37:57 AM				
Vallejo, Alt	pert	Need assistance with electrical to ca	afeteria A/c units.				
Johnny Aci	una						
125219			11/6/2014		25		\$0.00
Medium	Work In Progress		11/6/2014 9:48:51 AM				
Marquez, C	Gerardo	Need to replace head custodian ma	ster key. (J-key)				
Johnny Aci	una						
125290			11/7/2014		24		\$0.00
Medium	Work In Progress		11/7/2014 1:06:57 PM				
Marquez, C		Need lock for new storage shed loca enclosed area.	ated in mobile home				
Johnny Act 125162	una		11/5/2014		26		\$0.00
	Mork In Drogrado				20		Ф 0.00
Medium	Work In Progress		11/5/2014 9:35:34 AM				
Marquez, C		As per Custodial, Need a door name Hernandez)	eplate (Jesus				
Johnny Aci 123497	una		10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Prograss		10/5/2014 12:41:31 AM	11/3/2014	57		ψ0.00
Acuna, Joł	Work In Progress	Yearly - Desert Trail ES I4 (Fan Coil PMschedule details.					
Margret Vil	lalohos	Phischedule details.					
124888			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:11 AM				·
Orozco, Da	-	Yearly - Desert Trail ES - Grease Tr schedule details.					
Margret Vil	lalobos						
125313			11/7/2014		24		\$0.00
Medium	Work In Progress		11/7/2014 3:31:45 PM				
Appelzolle	r, Fred	please replace faucet (kitchen type)	to nurse's office.				
Johnny Aci	ana						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert T	ail ES					
125675		Custodial	11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 11:39:59				
Appelzolle	er, Fred	Buenos dias Fred el horinal del port liquiando agua de abajo del tubo po revisar gracias					
Laura San	ndoval						
119597			7/18/2014		136		\$0.00
Medium	Work In Progress		7/18/2014 3:05:40 PM				
Appelzolle	er, Fred	Need parts to repair broken clean-or	ut.				
Johnny Ac	una						
118894			7/2/2014		152		\$0.00
Medium	Work In Progress		7/2/2014 8:23:42 AM				
Acuna, Jol	-	Need to patch and re-stitch playgrou Blue Canvas Shade.	nd picnic table area				
Johnny Ac	una		0/0/0044	0/11/1/00/11			.
120246			8/3/2014	8/11/2014	120		\$0.00
Medium	Work In Progress		8/3/2014 12:32:36 AM				
Acuna, Jol	-	Monthly - Desert Trail ES- Emer Lig Refer to PMschedule details.	ht Insp:Monthly-				
Margret Vi	llalobos		0/04/0044	0/0/0044			<u> </u>
122068			8/31/2014	9/8/2014	92		\$0.00
Medium	Work In Progress		8/31/2014 12:54:12 AM				
Acuna, Jol	-	Monthly - Desert Trail ES- Emer Lig Refer to PMschedule details.	ht Insp:Monthly-				
Margret Vi	llalobos		0/04/0044	0/0/2044			<u> </u>
122069			8/31/2014	9/8/2014	92		\$0.00
Medium	Work In Progress		8/31/2014 12:54:12 AM				
Acuna, Jol	hnny	Monthly - Desert Trail ES - Exit Sign Refer to PM schedule details.	Insp:Monthly-				
Margret Vi	llalobos		/= /= -				A
124964			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:55 AM				
Acuna, Jol	hnny	Monthly - Desert Trail ES -Clothes I Refer to PM schedule details.	Dryer (Monthly) -				
Margret Vi	llalobos						

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date 1 Created Date/Time	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert Ti	rail ES					
124736			10/29/2014		33		\$0.00
Medium	Work In Progress		10/29/2014 1:33:41 PM				
Acuna, Jol	nnny	Need a handicap grab bar for wall to portable #412.36" to 43" range	o restroom in				
Johnny Ac	una						
124903			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:20 AM				
Acuna, Jol	nny	Monthly - Desert Trail ES- Emer Li Refer to PMschedule details.	ght Insp:Monthly-				
Margret Vi	llalobos						
124904			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:20 AM				
Acuna, Jol	nnny	Monthly - Desert Trail ES - Exit Sig Refer to PMschedule details.	n Insp:Monthly-				
Margret Vi	llalobos						
125945			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:58				
Acuna, Jol	nny	Monthly - Desert Trail ES- Emer Li Refer to PMschedule details.	ght Insp:Monthly-				
Margret Vi	llalobos						
125946			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:59				
Acuna, Jol	nny	Monthly - Desert Trail ES - Exit Sig Refer to PMschedule details.	n Insp:Monthly-				
Margret Vi	llalobos						
125947			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:59				
Acuna, Jol	nny	Monthly - Desert Trail ES -Clothes Refer to PMschedule details.	Dryer (Monthly) -				
Margret Vi	llalobos						
122915			9/17/2014		75		\$0.00
Medium	Work In Progress		9/17/2014 1:29:41 PM				
Munoz, Mie	chael	purchase new tuff shed 16x20 for s	torage at site.				

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert T	rail ES					
125487		Custodial	11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 7:53:28 AM				
Carbajal,	Jimmy	Buenos dias jimmyla aspiradora n del enchufe la puede revisar por fav					
Laura San	ndoval		·				
125224		Custodial	11/6/2014		25		\$0.00
Medium	Work In Progress		11/6/2014 10:42:22 AM				
Carbajal,	Jimmy	Buenos dias Jimmyla aspiradora r extencion no prende por favor la pue					
Laura San	ndoval						
125414		Custodial	11/12/2014		19		\$0.00
Medium	Work In Progress		11/12/2014 7:27:22 AM				
Carbajal,	-	BUenos dias Jimmyla aspiradora i la llanta si la puede revisar por favo					
Laura San	ndoval		0/0/0044		100		<u> </u>
120336			8/3/2014		120		\$0.00
Medium	Work In Progress		8/3/2014 12:33:39 AM				
Munoz, Mio		Yearly - Desert Trail ES Fire Ext. Ins to PMschedule details.	sp. (Yearly) - Refer				
Margret Vi	llalobos		44/0/0044	4.4./00./004.4			.
125012			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:24 AM				
Orozco, Da		Monthly - Desert Trail ES - Range H Refer to PMschedule details.	lood Cleaning -				
Margret Vi	llalobos		44/0/0044	4.4.10.10.04.4			* 0.00
125000			11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:17 AM				
Acuna, Jol	hnny	Monthly - Desert Trail ES - Monthly Refer to PMschedule details.	FE Inpsection -				
Margret Vi	llalobos		- / /				A
122129			8/31/2014	9/6/2014	92		\$0.00
Medium	Work In Progress		8/31/2014 12:54:51 AM				
Acuna, Jol	hnny	Monthly - Desert Trail ES - Monthly Refer to PMschedule details.	FE Inpsection -				
Margret Vi	llalobos						

Acuna, Johnny Margret Villalobos 125611 Medium Work In Marquez, Gerardo Gerardo Marquez 121619 Medium Work In Marquez, Gerardo Johnny Acuna 124672	Desert Tr	1' Monthly - Desert Trail ES - Monthly FE Inpsec Refer to PMschedule details. Classroom 11/1 NEED TO LOCATE AND DELIVER A URINAL FOR WORK BEING DONE ON PORTABLE R REMODEL.	11/17/2014 7/2014 8:58:15 AM SCREEN	12/6/2014	1	
Medium Work In Acuna, Johnny Margret Villalobos 125611 Medium Work In Marquez, Gerardo Gerardo Marquez 121619 Medium Work In Marquez, Gerardo Johnny Acuna 124672 Medium Work In	n Progress	Monthly - Desert Trail ES - Monthly FE Inpsed Refer to PMschedule details. Classroom 11/1 NEED TO LOCATE AND DELIVER A URINAL FOR WORK BEING DONE ON PORTABLE R REMODEL.	1/30/2014 12:47:35 ction - 11/17/2014 7/2014 8:58:15 AM SCREEN .RM.	12/6/2014		\$0.00 \$0.00
Acuna, Johnny Margret Villalobos 125611 Medium Work In Marquez, Gerardo Gerardo Marquez 121619 Medium Work In Marquez, Gerardo Johnny Acuna 124672 Medium Work In	n Progress	Monthly - Desert Trail ES - Monthly FE Inpsed Refer to PMschedule details. Classroom 11/1 NEED TO LOCATE AND DELIVER A URINAL FOR WORK BEING DONE ON PORTABLE R REMODEL.	2tion - 11/17/2014 7/2014 8:58:15 AM SCREEN .RM.		14	\$0.00
Margret Villalobos 125611 Medium Work In Marquez, Gerardo Gerardo Marquez 121619 Medium Work In Marquez, Gerardo Johnny Acuna 124672 Medium Work In		Refer to PMschedule details. Classroom 11/1 NEED TO LOCATE AND DELIVER A URINAL FOR WORK BEING DONE ON PORTABLE R REMODEL.	11/17/2014 7/2014 8:58:15 AM SCREEN .RM.		14	\$0.00
125611 Medium Work In Marquez, Gerardo Gerardo Marquez 121619 Medium Work In Marquez, Gerardo Johnny Acuna 124672 Medium Work In		11/1 NEED TO LOCATE AND DELIVER A URINAL FOR WORK BEING DONE ON PORTABLE R REMODEL.	7/2014 8:58:15 AM SCREEN .RM.		14	 \$0.00
Medium Work In Marquez, Gerardo Gerardo Marquez 121619 Medium Work In Marquez, Gerardo Johnny Acuna 124672 Medium Work In		11/1 NEED TO LOCATE AND DELIVER A URINAL FOR WORK BEING DONE ON PORTABLE R REMODEL.	7/2014 8:58:15 AM SCREEN .RM.		14	\$0.00
Marquez, Gerardo Gerardo Marquez 121619 Medium Work In Marquez, Gerardo Johnny Acuna 124672 Medium Work In		NEED TO LOCATE AND DELIVER A URINAL FOR WORK BEING DONE ON PORTABLE R REMODEL.	SCREEN .RM.			
Gerardo Marquez 121619 Medium Work In Marquez, Gerardo Johnny Acuna 124672 Medium Work In	Progress	FOR WORK BEING DONE ON PORTABLE R REMODEL.	.RM.			
121619 Medium Work In Marquez, Gerardo Johnny Acuna 124672 Medium Work In	Progress	0/0	8/22/2014			
Medium Work In Marquez, Gerardo Johnny Acuna 124672 Medium Work In	Progress	0/0	8/22/2014			
Marquez, Gerardo Johnny Acuna 124672 Medium Work In	n Progress	0/0	0/22/2014		101	\$0.00
Johnny Acuna 124672 Medium Work In		0/2	2/2014 7:53:35 AM			
124672 Medium Work In		Please straighten out door to frame in portable Top hinge plate on door is broken and needs r				
Medium Work In						
			10/28/2014		34	\$0.00
Gonzales, Camilo	n Progress	library 10)/28/2014 11:44:05			
		We need some computers (COWS) pick up. T warehouse. ID #'s 001643,001644,001279,001285,001264,001 ,001293001277,001288,001640,001281,001 ,001292,001280,001290,001624,001626,00 3,001275,001269,001267,001641,001286,00 72,5600303,1000000002337 this one come keyboard and monitor together. Monitor #'s 001295,001607,001297,001620,001296,001 ,001614,001602,001621,001336,001326,007 2,001314,001606,001609,001617,001600,00 30,001605,001612,001323,5600976,560166 , and one monitor has no tag.	284,001276 289,001282 1287,,00128 01274,0012 with 317,001604 1616,00133 01294,0013			
Elizabeth Hernand	ez					
125439			11/12/2014		19	\$0.00
Medium Work In	Progress	1'	1/12/2014 12:27:58			
Gonzalez, Salvadoı	r	Need to secure storage shed in mobile home concrete.	area to			
Johnny Acuna						
124678			10/28/2014		34	\$0.00
Medium Work In	Progress	10)/28/2014 12:31:36			
Gonzalez, Salvadoi Johnny Acuna	r	Need plate replacement for sidewalk on west main building portables area.	side of			

12/1/2014 3:28:26 PM

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert T	rail ES				
122696		9/12/2014		80		\$0.00
Medium	Work In Progress	9/12/2014 11:12:08 AM				
Orozco, Da	aniel	As per Health Inspection Report-foot pedal (walk-in)door pedal and freezer foot pedal from sinks are leaking.				
Maritza Go	onzalez					
119265		7/10/2014		144		\$0.00
Medium	Work In Progress	7/10/2014 9:56:12 AM				
Orozco, Da	aniel	TIRE ON PIZZA CART FELL OFF. PLEASE CHECK. SNP MANAGER 824.3822				
Maritza Go	onzalez					
125126		11/4/2014		27		\$0.00
Medium	Work In Progress	11/4/2014 12:35:57 AM				
Apodaca,	Mario	Monthly - Desert Trail ES - Domestic Water Filter - Refer to PMschedule details.				
Margret Vi	llalobos	44/0/0044	44/05/0044			
125340		11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress	11/9/2014 12:41:37 AM				
Acuna, Jo	-	Monthly - Desert Trail ES - Playground Insp - Refer to PMschedule details.				
Margret Vi	llalobos		- / / / -			
120902		8/10/2014	8/26/2014	113		\$0.00
Medium	Work In Progress	8/10/2014 12:25:25 AM				
Acuna, Jo	hnny	Monthly - Desert Trail ES - Playground Insp - Refer to PMschedule details.				
Margret Vi	llalobos	7/00/004				.
120033		7/30/2014		124		\$0.00
Medium	Work In Progress	7/30/2014 2:18:04 PM				
Acuna, Jo	hnny	As per Alfredo please order borders needed. Need approx. 22 borders for playground sand to the bigger playground area sets.				
Johnny Ac	cuna					
122421		9/7/2014	9/23/2014	85		\$0.00
Medium	Work In Progress	9/7/2014 12:33:39 AM				
Acuna, Jo	hnny	Monthly - Desert Trail ES - Playground Insp - Refer to PMschedule details.				
Margret Vi	illalobos					

1231			riogress	5 (1 150	aiiteaij				Total
WOID Priority Assigned		Dates:7/1/2014 - 1 Area Area Number Description	Deferred By	Until	Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requeste		rail ES							
125033					11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress			11/2/2	2014 12:36:37 AN	1			
Orozco, D	aniel	Monthly - Dese Refer to PMscł	ert Trail ES - Fire S nedule details.	uppression Ir	nsp				
Margret Vi	illalobos								
123688					10/5/2014	10/26/2014	57		\$0.00
Medium	Work In Progress			10/5/2	2014 12:44:01 AN	1			
Munoz, Mi	chael	Monthly - Dese PMschedule d	ert Trail ES - Fire S etails.	prinkler Insp.	- Refer to				
Margret Vi	illalobos								
Count: 51	Work Orders	A	vg. Age of WO's	52		Total for Desert Tra	ail ES	0	\$0.00

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert V	iew ES					
125034			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:38 AM				
Orozco, Da	aniel	Monthly - Desert View ES Fire Supp to PMschedule details.	pression Insp Refer				
Margret Vi	llalobos						
122428			9/7/2014	9/23/2014	85		\$0.00
Medium	Work In Progress		9/7/2014 12:33:44 AM				
Ortiz, Rube		Monthly - Desert View ES Playgrou PMschedule details.	nd Insp - Refer to				
Margret Vi	llalobos		44/0/0044	44/05/0044			<u> </u>
125346			11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress		11/9/2014 12:41:44 AM				
Ortiz, Rube		Monthly - Desert View ES Playgrou PMschedule details.	nd Insp - Refer to				
Margret Vi	llalobos		10/28/2014		34		\$0.00
124694					34		Φ 0.00
Safety Ortiz, Rube	Work In Progress en	Need to remove all chains and seat in the upper level playground as per					
Ruben Orf	tiz						
124687			10/28/2014		34		\$0.00
Safety	Work In Progress		10/28/2014 3:23:14 PM				
Ortiz, Rube	en	Replace all the swing sets in the pla	ayground				
Ruben Orf	tiz						
122564			9/10/2014		82		\$0.00
Medium	Work In Progress		9/10/2014 9:42:24 AM				
Orozco, Da	aniel	THE RISE PART ON 3 COMPARTM CLOGGED. SNP MANAGER ELIZA					
Maritza Go	onzalez						
125013			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:24 AM				
Orozco, Da		Monthly - Desert View ES Range H to PMschedule details.	ood Cleaning - Refer				
Margret Vi	llalobos						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Lo Area Deferred By Area Number Reason Description		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert V	iew ES					
125536			11/13/2014		18		\$0.00
Medium	Work In Progress	Front of School	11/13/2014 3:46:34 PM				
Munoz, Mi	chael	Repair broken sidewalk in the front cause someone to trip. (Araujo)	ofschool. It can				
Guadalup	e Gonzalez						
120337			8/3/2014		120		\$0.00
Medium	Work In Progress		8/3/2014 12:33:39 AM				
Munoz, Mi	chael	Yearly - Desert View ES Fire Ext. In to PMschedule details.	sp. (Yearly) - Refer				
Margret Vi	llalobos						
125003			11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:18 AM				
Ortiz, Rub		Monthly - Desert View ES Monthly F to PM schedule details.	E Inpsection - Refer				
Margret Vi	llalobos		44/00/0044	40/0/0044			<u> </u>
125998			11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:33				
Ortiz, Rub		Monthly - Desert View ES Monthly F to PM schedule details.	E Inpsection - Refer				
Margret Vi	llalobos		10/5/2014	10/13/2014	57		¢0.00
123573				10/13/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:42:32 AM				
Ortiz, Rub		Monthly - Desert View ES Exit Sign Refer to PMschedule details.	Insp: Monthly -				
Margret Vi	llalobos		0/00/0044		70		<u> </u>
123025			9/22/2014		70		\$0.00
Medium	Work In Progress	School Campus	9/22/2014 9:06:41 AM				
Ortiz, Rub		Need weather strips for doors throu (Gonzalez)	ighoutcampus.				
	e Gonzalez		- /				A
121789			8/26/2014		97		\$0.00
Medium	Work In Progress		8/26/2014 2:41:33 PM				
Ortiz, Rub	en	The sink in the kitchen is clogged. N ASAP	Need it repaired				
Ruben Or	tiz						

WOID Priority Assigned			Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert V	iew ES						
121790				8/26/2014		97		\$0.00
Medium	Work In Progress			8/26/2014 2:42:35 PM	1	0.		<i>\\</i>
Ortiz, Rube	-	The upper level g and the other is b		e one faucet is leaking				
Ruben Ort	iz							
120664				8/6/2014		117		\$0.00
Medium	Work In Progress	Rm.#33		8/6/2014 2:42:09 PN	1			
Ortiz, Rube	en	Air Conditioner n	ot working. (Guti	errez)				
Guadalupe	e Gonzalez							
120313				8/3/2014	8/11/2014	120		\$0.00
Medium	Work In Progress			8/3/2014 12:33:22 AM	l			
Ortiz, Rube	en	Monthly - Desert Refer to PMsche		ight Test: Monthly -				
Margret Vil	lalobos							
120105		Library		7/31/2014		123		\$0.00
Medium	Work In Progress	Library		7/31/2014 2:01:36 PN	1			
Ortiz, Rube	en	Move projection s (Sanchez-Segura		rds circulations desk.				
	e Gonzalez							
123919		Classroom		10/9/2014		53		\$0.00
Medium	Work In Progress	Rm.#28		10/9/2014 11:55:43 AM	l			
Ortiz, Rube	en	Install a bulletin b	ooard. (Trujillo)					
Guadalup	e Gonzalez							
120662		Classroom		8/6/2014		117		\$0.00
Medium	Work In Progress	Rm.#14		8/6/2014 2:40:13 PN	1			
Ortiz, Rube	en	Air Conditioner n	ot working. (Buer	0)				
Guadalup	e Gonzalez							
120663		Classroom		8/6/2014		117		\$0.00
Medium	Work In Progress	Rm.#16		8/6/2014 2:40:57 PN	1			
Ortiz, Rube	en	Air Conditioner n	ot working. (Mac	k)				
Guadalup	e Gonzalez							
122783		Classroom		9/15/2014		77		\$0.00
Medium	Work In Progress	Rm.#12		9/15/2014 3:49:22 PN	1			
Ortiz, Rube	-	Take TV down an	d remove from cl	assroom.(Ramos)				
				/				

WOID Priority Assigned ⁻ Requester		Area D Area Number R Description	eferred By eason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert Vi	ew ES						
123052		Classroom		9/23/2014		69		\$0.00
Medium	Work In Progress	School Campus		9/23/2014 9:21:13 AM				
Ortiz, Rube	en			tion need weather s from coming into the				
Guadalupe	e Gonzalez							
125186		Office		11/5/2014		26		\$0.00
Medium	Work In Progress	Office		11/5/2014 3:01:33 PM				
Ortiz, Rube	en	Assemblythreeb	ig book storage	boxes.(Lopez)				
Guadalupe	e Gonzalez							
125187		Office		11/5/2014		26		\$0.00
Medium	Work In Progress	Office		11/5/2014 3:05:59 PM				
Ortiz, Rube	en	Assembleapodi	um. (Gonzalez)					
Guadalupe	e Gonzalez							
120111		Office		7/31/2014		123		\$0.00
Medium	Work In Progress	Office		7/31/2014 2:16:37 PM				
Ortiz, Rube	en	Put banners up o	n the fence. (Go	onzalez)				
Guadalupe	e Gonzalez							
125969				11/30/2014		1		\$0.00
Medium	Work In Progress			11/30/2014 12:47:14				
Ortiz, Rube	en	Monthly - Desert Refer to PMscheo		es Dryer (Monthly) -				
Margret Vil	lalobos							
125970				11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress			11/30/2014 12:47:15				
Ortiz, Rube	en	Monthly - Desert V Refer to PMscheo		gn Insp: Monthly-				
Margret Vil	lalobos							
125971				11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress			11/30/2014 12:47:15				
Ortiz, Rube	en	Monthly - Desert Refer to PMschee	/iew ES Emer. Iule details	Light Test: Monthly -				

WOID Priority Assigned	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date 1 Area Number Reason Created Date/Time / Description Created Date/Time /	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Vi	iew ES				
124804		10/30/2014		32		\$0.00
Medium	Work In Progress	10/30/2014 4:01:59 PM				
Ortiz, Rube	en	The unit in portable 2 room 4 is not working; need it repaired. Thank you, Ruben				
Ruben Ort	iz					
124956		11/2/2014		29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:51 AM				
Ortiz, Rube	en	Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PMschedule details.				
Margret Vil	lalobos					* ••••
124957		11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:51 AM				
Ortiz, Rube		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PMschedule details.				
Margret Vil	lalobos	44/0/0044	44/40/0044			<u> </u>
124960		11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:53 AM				
Ortiz, Rube		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vil	lalobos	0/00/2014		<u></u>		¢0.00
123369		9/29/2014		63		\$0.00
Medium	Work In Progress	9/29/2014 4:01:13 PM				
Sotelo, En	rique	Company:CALIPER CONSTRUCTIONContact Name:FERNIE REYES(575)635-8919Alternate Contact:BLANCA CRUZAlternate Contact:BLANCA CRUZBest Time to Call:Fax No:Cell Phone:Pager No:Email:blanca@caliperconstcom				
	_	Location of Work: LOCATE PER ZONE 1 WORK PLAN				
Dominique	e Esparza			20		<u> </u>
124881		11/2/2014		29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:07 AM				
Orozco, Da		Yearly - Desert View ES - Grease Trap - Refer to PM schedule details.				
Margret Vil	lalobos					

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert V	iew ES					
124436			10/22/2014		40		\$0.00
Medium	Work In Progress		10/22/2014 9:03:34 AM				
,		Company: CALIPER CONSTR Contact Name: FERNIE REYES (575)635-8919 Alternate Contact: BLANCA CRUZ Cell Phone: (575)635-8919 Email: blanca@caliperconstcom	JCTION Contact Phone:				
		Location of Work: SPOT: 100FT RAD	FROMCENTER				
Dominiqu	-		40/47/0044		45		.
124300	Main Building	Restroom	10/17/2014		45		\$0.00
Medium	Work In Progress		10/17/2014 12:37:11				
Ontiveros,		hi Joe we have a urinal in the boys res clogged. Can you unclogg it please					
Israel Orte	ega		10/14/2014		48		\$0.00
Medium	Work In Progress		10/14/2014 9:28:45 AM		-10		ψ0.00
Ontiveros,	-	Company: CALIPER CONSTR Contact Name: FERNIE REYES (575)635-8919 Alternate Contact: BLANCA CRUZ Cell Phone: (575)635-8919 Email: blanca@caliperconstcom					
Dominiqu	e Esparza	Location of Work: SPOT: AREA WITH MARKS, SW CORNER OF SCHOOL Type of Work: DIG OUT WATER LINE	PROPERTY.				
124833			10/31/2014		31		\$0.00
Medium	Work In Progress		10/31/2014 9:25:14 AM				
Ontiveros,	Joe	Company: CARVER ELECTRIC Contact Name: JACOB CARVER (575)527-2127 Alternate Contact: DANIEL CARVER	Contact Phone: Alternate				
		Phone: (575)649-9142 Cell Phone: (575)649-9207 Email: carver@carverelectric.com	Pager No:				
		Location of Work: LOCATE PER THE ELEMENTERY WORK PLAN	DESERT VIEW				
Dominiqu	e Esparza						

WOID Priority Assigned	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Target Con Area Number Reason Created Date/Time Actual Con Description Action		Costs Labor Hours
Location:	Desert V	ew ES		
125160		11/5/2014	26	\$0.00
Medium	Work In Progress	11/5/2014 9:04:16 AM		
Ontiveros,	Joe	Company: METRO MECHANICAL Contact Name: RICHARD MUNOZ Contact Phone: (575)527-1044 Best Time to Call: Fax No: (575) 527-8309 Cell Phone: (575)649-5554 Pager No: Location of Work: SPOT ENTIRE PROPERTY and CONTACT RICHARD MUNOZ AT (575)-649-5554 FOR A CONFERENCE TO DEVELOP A WIDE AREA WORK PLAN		
Dominique 124809	e Esparza	10/30/2014	32	\$0.00
Medium	Work In Progress	10/30/2014 4:06:31 PM		
Ontiveros,	Joe	On the west side by the bathroom the water faucet is leaking and need to be replaced. Thank you, Ruben		
Ruben Ort	tiz	44/40/0044		.
125425		11/12/2014	19	\$0.00
Medium Ontiveros,	Work In Progress Joe	11/12/2014 9:41:12 AM Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Email: blanca@caliperconstcom		
		Location of Work: LOCATE PER ZONE 1 WORK PLAN		
Dominique	e Esparza	44/40/0044	40	<u>۴</u> ۵.۵۵
125761		11/19/2014	12	\$0.00
Medium Ontiveros,	Work In Progress Joe	11/19/2014 2:45:02 PMCompany:METRO MECHANICALContact Name:RICHARD MUNOZ(575)527-1044Fax No:(575)527-8309Cell Phone:(575)649-5554Location of Work:SPOT ENTIRE PROPERTY.		

WOID Priority Assigned	ate Range for Request Building Status To		Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	r Name							
Location:	Desert V	iew ES						
125442		Office		11/12/2014		19		\$0.00
Medium	Work In Progress	Office		11/12/2014 2:16:48 PM	1			
Ontiveros,	,Joe	Check office ba	throom there is a fo	ul odor. (Gonzalez)				
Guadalup	e Gonzalez							
125613				11/17/2014		14		\$0.00
Medium	Work In Progress			11/17/2014 9:04:27 AN	1			
Ontiveros	, Joe	Alternate Phone Cell Phone: Email:carver@o	27-2127 ict: DANIEL CARVEF e: (575)649-9142 (575)649-9207 carverelectric.com	Contact				
		Location of Wor	rk: LOCATE PER TH WORK PLAN	E DESERT VIEW				
	e Esparza			4.0.14.10.04.4				* ••••
123442				10/1/2014		61		\$0.00
Medium	Work In Progress			10/1/2014 2:07:47 PN	Λ			
Castillo, C	Carlos		cylights replaced by ybetween the kitche oen					
Ruben Or	tiz							
125140				11/4/2014		27		\$0.00
Medium	Work In Progress			11/4/2014 2:24:35 PM	Λ			
Castillo, C	Carlos	camera monito	e electrical outlet wh r and tvplug in. has b t couple of weeks	5				
Cora Ram	nirez							
124806				10/30/2014		32		\$0.00
Medium	Work In Progress			10/30/2014 4:04:18 PN	1			
Castillo, C		Two lights in the Thank you, Rub	e office are not workir ben	ng; need it repaired.				
Ruben Or	tiz							

Lotation: Desert View ES 10/22/2014 40 124435 10/22/2014 9:03:17 AM 40 Castillo, Carlos Company: CALLPER CONSTRUCTION Contact Name: 10/22/2014 9:03:17 AM Castillo, Carlos Company: CALLPER CONSTRUCTION Contact Name: FERNIE REVES Contact Phone: FCF3/935-8919 FCF Auternate Contact: BLANCA CRUZ Cell Phone: Coston for Nork: SPOT: 100FT RAD FROM CENTER FCF Dominique Esparat 11/19/2014 12 Medium Work In Progress 11/19/2014 2:44:47 PM 12 Castillo, Carlos Company: KETRO MECHANICAL Contact Name: Contact Phone: FCF Castillo, Carlos Company: KETRO MECHANICAL Contact Name: FCF FCF Castillo, Carlos Company: KETRO MECHANICAL Contact Name: FCF FCF T25672 T1/19/2014 2:44:47 PM 13 FCF FCF FCF T25672 T1/18/2014 11:14:38 FCF	Selected Date Rang WOID Build Priority State Assigned To Requester Name	ling us	Dates:7/1/2014 - 1 Area Area Number Description	1/30/2014 Order By Loc Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Medium Work In Progress 0/22/2014 9:03:17 AM Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Cell Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Coll Phone: Cell Phone: (575)635-8919 Medium Work: SPOT: 100FT RAD FROM CENTER DOF Dominique Esparza 11/19/2014 12 125760 11/19/2014 2:44:47 PM Contact Name: RICHARD MUNOZ Contact Phone: Contact Name: METRO MECHANICAL Contact Phone: (575)627-104 Contact Name: RICHARD MUNOZ Contact Phone: (575)627-104 Castillo, Carlos Company: METRO MECHANICAL Contact Phone: Contact Name: SPOT ENTIRE PROPERTY. 13 125672 11/18/2014 11:14:38 13 Medium Work In Progress 11/12/2014 11:14:38 14 Castillo, Carlos The switch in the nurse's office is not working: needs to be worked on 11/12/2014 19 Medium Work In Progress 11/12/2014 9:40:57 AM	Location:	Desert Vi	iew ES						
Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Cell Phone: (575)635-8919 Location of Work: SPOT: 100FT RAD FROM CENTER OF INTERSECTION. Dominique Esparza 125760 11/19/2014 2:44:47 PM Castillo, Carlos Company: METRO MECHANICAL Contact Name: RICHARD MUNOZ Contact Phone: (575)527-104 Fax No: (575)527-8309 Cell Phone: (575)527 Cell Phone: (575)527 C	124435				10/22/2014		40		\$0.00
Contact Name: (575)635-8919 Atternate Contact BLANCA CRUZ Cell Phone: (575)635-8919 Email: blanca@caliperconstoonDominique Esparza12576011/19/201412MediumWork In ProgressCompany: (575)527-8309 Cell Phone: (575)527-8309 Cell Phone: Cell Phone: (575)527-8309 Cell Phone: (575)527-8309 Cell Phone: (575)527-8309 Cell Phone: (575)527-8309 Cell Phone: Cell Ph	Medium Work	k In Progress			10/22/2014 9:03:17 AM	1			
OF INTERSECTION. Dominique Esparza 125760 11/19/2014 Medium Work In Progress Castillo, Carlos Company: METRO MECHANICAL Contact Name: RICHARD MUNOZ Castillo, Carlos Company: METRO MECHANICAL Contact Name: RICHARD MUNOZ Castillo, Carlos Company: (575)527-8309 Cell Phone: (575)649-5554 Location of Work: SPOT ENTIRE PROPERTY. 125672 11/18/2014 13 Medium Work In Progress 11/18/2014 11:14:38 Castillo, Carlos The switch in the nurse's office is not working; needs to be worked on Ruben Ortiz 11/12/2014 9:40:57 AM Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Email: blanca @caliperconstcom Location of Work: LOCATE PER ZONE 1 WORK PLAN Location of Work: LOCATE PER ZONE 1 WORK PLAN	Castillo, Carlos		Contact Name (575)635-8919 Alternate Conta Cell Phone:	E FERNIE REYES act: BLANCA CRUZ (575)635-8919					
125760 11/19/2014 12 Medium Work In Progress 11/19/2014 2:44:47 PM Castillo, Carlos Company: METRO MECHANICAL Contact Name: RICHARD MUNOZ Contact Phone: (575)527-1044 Fax No: (575)527-1044 Fax No: Fax No: (575)527-1044 Fax No: (575)527-1044 Location of Work: SPOT ENTIRE PROPERTY. 12 125672 11/18/2014 13 Medium Work In Progress 11/18/2014 11:14:38 Castillo, Carlos The switch in the nurse's office is not working; needs to be worked on Ruben Ortiz 11/12/2014 19 Medium Work In Progress 11/12/2014 9:40:57 AM Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Email: blanca@caliperconstoom Location of Work: LOCATE PER ZONE 1 WORK PLAN Location of Work: LOCATE PER ZONE 1 WORK PLAN					D FROM CENTER				
Medium Work In Progress 11/19/2014 2:44:47 PM Castillo, Carlos Company: RICHARD MUNOZ Contact Phone: (575)527-1044 Fax No: (575)527-8309 Cell Phone: (575)527-8309 Cell Phone: (575)527-8309 Location of Work: SPOT ENTIRE PROPERTY. 12 125672 11/18/2014 13 Medium Work In Progress 11/18/2014 11:14:38 Castillo, Carlos The switch in the nurse's office is not working; needs to be worked on 11/12/2014 Ruben Ortiz 11/12/2014 19 Medium Work In Progress 11/12/2014 9:40:57 AM Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)63-8919 Atternate Contact: BLANCA CRUZ Email: blanca@caliperconstcom Location of Work: LOCATE PER ZONE 1 WORK PLAN Location of Work: LOCATE PER ZONE 1 WORK PLAN Location of Work: LOCATE PER ZONE 1 WORK PLAN		arza			11/10/2014		12		\$0.00
Castillo, Carlos Company: METRO MECHANICAL Contact Name: RICHARD MUNOZ Contact Phone: (575)527-1044 Fax No: (575)527-8309 Cell Phone: (575)649-5554 Location of Work: SPOT ENTIRE PROPERTY. 125672 11/18/2014 13 Medium Work In Progress 11/18/2014 11:14:38 Castillo, Carlos The switch in the nurse's office is not working; needs to be worked on Ruben Ortiz 125424 11/12/2014 9:40:57 AM Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Email: blanca@caliperconstoom Location of Work: LOCATE PER ZONE 1 WORK PLAN						I	12		ψ0.00
125672 11/18/2014 13 Medium Work In Progress 11/18/2014 11:14:38 Castillo, Carlos The switch in the nurse's office is not working; needs to be worked on Ruben Ortiz 11/12/2014 125424 11/12/2014 Medium Work In Progress 11/12/2014 9:40:57 AM Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Name: FERNIE REYES Contact Name: FERNIE REYES Contact: BLANCA CRUZ Email: blanca@caliperconstcom Location of Work: LOCATE PER ZONE 1 WORK PLAN			Contact Name (575)527-1044 Fax No: (5	RICHARD MUNOZ	CAL				
Medium Work In Progress 11/18/2014 11:14:38 Castillo, Carlos The switch in the nurse's office is not working; needs to be worked on Ruben Ortiz 11/12/2014 125424 11/12/2014 Medium Work In Progress Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Name: FERNIE REYES Contact: BLANCA CRUZ Email: blanca@caliperconstcom Location of Work: LOCATE PER ZONE 1 WORK PLAN			Location of Wo	rk: SPOT ENTIRE PR	OPERTY.				
Castillo, Carlos The switch in the nurse's office is not working; needs to be worked on Ruben Ortiz 11/12/2014 19 125424 11/12/2014 9:40:57 AM 19 Medium Work In Progress 11/12/2014 9:40:57 AM 11/12/2014 9:40:57 AM Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919	125672				11/18/2014		13		\$0.00
Be worked on Ruben Ortiz 125424 11/12/2014 Medium Work In Progress Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Email: blanca@caliperconstcom Location of Work: LOCATE PER ZONE 1 WORK PLAN Location of Work: LOCATE PER ZONE 1 WORK PLAN	Medium Work	k In Progress			11/18/2014 11:14:38	5			
125424 11/12/2014 19 Medium Work In Progress 11/12/2014 9:40:57 AM Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Email: blanca@caliperconstcom Location of Work: LOCATE PER ZONE 1 WORK PLAN	Castillo, Carlos			e nurse's office is no	tworking; needs to				
Medium Work In Progress 11/12/2014 9:40:57 AM Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Email: blanca@caliperconstcom Location of Work: LOCATE PER ZONE 1 WORK PLAN Location of Work: LOCATE PER ZONE 1 WORK PLAN					44/40/0044		40		<u> </u>
Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Email: blanca@caliperconstcom Location of Work: LOCATE PER ZONE 1 WORK PLAN	-						19		\$0.00
Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Email: blanca@caliperconstcom Location of Work: LOCATE PER ZONE 1 WORK PLAN		In Progress	Component			1			
	Casuno, Canos		Contact Name (575)635-8919 Alternate Conta	FERNIE REYES					
Dominique Esparza			Location of Wo	rk: LOCATE PER ZOI	NE 1 WORK PLAN				
Dominique Loparza	Dominique Espa	arza							

Castillo, Carlos Dominique Es 122258 Medium We Castillo, Carlos Carlos Castillo 122256		Company: CARVER ELECTRIC Contact Name: JACOB CARVER Phone: (575)527-2127 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142 Cell Phone: (575)649-9207 Email: carver@carverelectric.com Location of Work: LOCATE PER THE ELEMENTERY WORK PLAN	11/17/2014 11/17/2014 9:04:06 AM Contact DESERT VIEW		14	\$0.00
Medium Wo Castillo, Carlos 122258 Medium Wo Castillo, Carlos Carlos Castillo Medium Wo Castillo, Carlos	sparza	Contact Name: JACOB CARVER Phone: (575)527-2127 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142 Cell Phone: (575)649-9207 Email: carver@carverelectric.com Location of Work: LOCATE PER THE ELEMENTERY WORK PLAN	11/17/2014 9:04:06 AN Contact		14	\$0.00
Castillo, Carlos Dominique Es 122258 Medium Wa Castillo, Carlos Carlos Castilla 122256 Medium Wa Castillo, Carlos Carlos Castilla	sparza	Contact Name: JACOB CARVER Phone: (575)527-2127 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142 Cell Phone: (575)649-9207 Email: carver@carverelectric.com Location of Work: LOCATE PER THE ELEMENTERY WORK PLAN	Contact	1		
Dominique Es 122258 Medium Wa Castillo, Carlos Carlos Castilla 122256 Medium Wa Castillo, Carlos Carlos Castilla	sparza	Contact Name: JACOB CARVER Phone: (575)527-2127 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142 Cell Phone: (575)649-9207 Email: carver@carverelectric.com Location of Work: LOCATE PER THE ELEMENTERY WORK PLAN				
122258MediumWoCastillo, CarlosCarlos Castillo122256MediumWoCastillo, CarlosCarlos Castillo	-	ELEMENTERY WORK PLAN	DESERT VIEW			
122258MediumWoCastillo, CarlosCarlos Castillo122256MediumWoCastillo, CarlosCarlos Castillo	-					
Medium Wo Castillo, Carlos Carlos Castillo 122256 Medium Wo Castillo, Carlos Carlos Castillo	lork in Progress	Parking Lot	9/3/2014		89	\$0.00
Castillo, Carlos Carlos Castillo 122256 Medium Wo Castillo, Carlos Carlos Castillo			9/3/2014 3:34:01 PM		03	ψ0.00
Carlos Castillo 122256 Medium Wo Castillo, Carlos Carlos Castillo	U	As non-quotodian norking lat lighta are		1		
122256 Medium Wo Castillo, Carlos Carlos Castillo		As per custodian, parking lot lights are	notworking.			
Medium Wo Castillo, Carlos Carlos Castillo	10	ParkingLot	9/3/2014		89	 \$0.00
Castillo, Carlos Carlos Castillo	/ork In Progress	·	9/3/2014 3:26:46 PM			
Carlos Castille	U U	As per custodian, parking lot lights are				
			notwonding.			
			11/13/2014		18	\$0.00
Medium Wo	/ork In Progress		11/13/2014 10:28:57	,		
Ambriz, Jose	C C	Room 27 - Heater is not working				
Israel Ortega		5				
125673			11/18/2014		13	\$0.00
Medium We	/ork In Progress		11/18/2014 11:15:44	Ļ		
Ambriz, Jose		The heater in room 28 is not turning or	l			
Ruben Ortiz						
120106		Library	7/31/2014		123	\$0.00
Medium We	/ork In Progress	Library	7/31/2014 2:02:45 PM	1		
Ortiz, Ruben		Paint white window on left side of entra maroon. (Sanchez-Segura)	ance door to			
Guadalupe Go	onzalez		7/04/0044		100	
120107		Library	7/31/2014		123	\$0.00
	/ork In Progress	Library	7/31/2014 2:06:39 PM	Λ		
Ortiz, Ruben Guadalupe Go	onzalez	Paint upper corner triangle of south wa Yellow like the NM Flag. (Sanchez-Se				
12/1/2014 3:2	01120102					

12/1/2014 3:28:26 PM

Selected Da WOID	te Range for Request Building	Dates:7/1/2014 - 1 Area	1/30/2014 Order By L Deferred By	ocation, Status Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Tota Costs
Priority Assigned	Status To	Area Number Description	Reason	Crea	ted Date/Time	Actual Comp Date Action Taken	Agoa	nour o	
Requester		Description				Action Taken			
Location:	Desert Vi	iew ES							
123481					10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress			10/5/20	14 12:41:17 AN	1			
Ortiz, Rube	en	Yearly - Deser PMschedule d	t View ES I-04 Fan (etails.	Coil Yearly - R	efer to				
Margret Vil	llalobos								
123482					10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress			10/5/20	14 12:41:18 AN	1			
Ortiz, Rube	en	Yearly - Deser Refer to PMsch	t View ES U-2 Unit H nedule details.	Heat Gas Year	ly -				
Margret Vil	llalobos								
125739					11/19/2014		12		\$0.00
Medium	Work In Progress			11/19/2	014 9:42:36 AN	1			
Lara, Ralp	h	The door to the fixed or replace Thank you, Ru		Illing down; ne	ed it				
Ruben Ort	iz								
Count: 62	Work Orders	Δ	vg. Age of WO's	50		Total for Desert Vie	w ES	0	\$0.00

WOID Priority Assigned	Building Status	Dates:7/1/2014 - 11/30 Area De Area Number Re Description	eferred By	Until Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	Name							
Location:	GAC							
123447				10/1/2014		61		\$0.00
Medium	Work In Progress			10/1/2014 2:49:10 PM	Л			
Lara, Ralp	h	AS PER MR. GIOV KITCHENS TO BE OF EMERGENCY. JACKIE)	KEPT IN SNP	OFFICES IN CASE				
Demetriou	is Giovas							
123515				10/5/2014	10/21/2014	57		\$0.00
Medium	Work In Progress			10/5/2014 12:41:46 AM	Λ			
Moncayo,	Fernando	Monthly - GAC A-1 Refer to PMsched	Wall Ref. Elec ule details.	Heat Semimonthly -				
Margret Vi	llalobos							
123516				10/5/2014	10/26/2014	57		\$0.00
Medium	Work In Progress			10/5/2014 12:41:47 AM	Λ			
Moncayo,	Fernando	Monthly - GAC F-3 - Refer to PMschee		eup Ut Semimonthly				
Margret Vi	llalobos							
123502				10/5/2014		57		\$0.00
Medium	Work In Progress			10/5/2014 12:41:35 AN	Л			
Moncayo,	Fernando	Yearly - GAC U-2 l schedule details.	Jnit Heater Gas	Yearly - Refer to PM				
Margret Vi	llalobos							
121916				8/28/2014		95		\$0.00
Medium	Work In Progress			8/28/2014 12:23:26 PN	1			
Ambriz, Jo	se			place a work order for in her office. Approved				
Maritza Go	onzalez							
119435				7/15/2014		139		\$0.00
Medium	Work In Progress			7/15/2014 1:29:36 PM	Л			
Ambriz, Jo	se	chiller libert circuit compressors,mal						
Jose Amb	riz							
119230				7/9/2014		145		\$0.00
Medium	Work In Progress			7/9/2014 2:40:00 PM	Л			
Ambriz, Jo	se			like a wall a/c unit scilla Escobar office.				
Maritza Go	onzalez							

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	GAC						
124253			10/16/2014		46		\$0.00
Medium	Work In Progress		10/16/2014 3:47:13 PM	I			
Flores, Pet	te	vehicle 172 back window doesn't roll	up				
Demetriou	is Giovas						
124267			10/16/2014		46		\$0.00
Medium	Work In Progress	FED PROGS	10/16/2014 4:20:48 PM	I			
Flores, Pet	te	CHANGE OIL LIGHT ON					
Noemi Du	ron						
124239			10/16/2014		46		\$0.00
Medium	Work In Progress		10/16/2014 3:05:52 PM	l			
Flores, Pet	te	AS PER MR. BAKER SNP VEHICLE SIDE REAR WINDOW DOES NOT G					
Maritza Go	nzalez						
124231			10/16/2014		46		\$0.00
Medium	Work In Progress		10/16/2014 9:43:06 AN	1			
Lara, Ralpl	h	NEED KEY TO ROOM 113 IN C WIN VILLALOBOS) TO BE PUT BACK ON NOW IT IS OFF MASTER.					
Maritza Go	nzalez						
119593			7/18/2014		136		\$0.00
Medium	Work In Progress		7/18/2014 2:11:02 PM	1			
Lara, Ralpl	h	PLEASE CHECK SNP STORAGE IN STUCK CANNOT OPEN.	BISTRO, LOCK				
Maritza Go	nzalez		14/40/0044		40		* •••••
125500			11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 9:16:11 AN	1			
Lara, Ralpl	h	broken master key-please see Cora	ì				
Cora Ram	irez						
125499			11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 9:12:15 AN	1			
Ambriz, Jos	se	REPLACE UNIT IN KITCHEN AREA COMPRESSOR SECTIONG.	LEAKING FROM				
Maritza Go	nzalez		10/18/02/1				• ••••
124167		Electrical Room	10/15/2014		23		\$0.00
Medium	Work In Progress		10/15/2014 8:10:52 AN	l 11/7/2014			
Castillo, C	arlos	Order stock material and equipment					
	stillo						

12/1/2014 3:28:27 PM

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	GAC						
125102		Hallway/Corridor	11/3/2014		28		\$0.00
Medium	Work In Progress		11/3/2014 3:28:00 PM	1			
Castillo, C	arlos	Check hallway dark areas for eme installation.And install where nee					
Carlos Ca	stillo						
125787		Electrical Room	11/20/2014		11		\$0.00
Medium	Work In Progress		11/20/2014 7:57:56 AN	1			
Castillo, C	arlos	Organize, inventory and clean elec	ctrical storage.				
Carlos Ca	stillo						
125841		Electrical Room	11/21/2014		10		\$0.00
Medium	Work In Progress		11/21/2014 9:30:05 AN	1			
Castillo, C	arlos	Order replacement hand tools.					
Carlos Ca	stillo						
125858			11/21/2014		10		\$0.00
Medium	Work In Progress		11/21/2014 3:08:07 PN	l			
Castillo, C	arlos	Vehicle #152 -Inspection and mai	intenanœ.				
Carlos Ca		·					
125422			11/12/2014		19		\$0.00
Medium	Work In Progress		11/12/2014 9:22:04 AN	1			
Castillo, C	-	C-WING HALLWAY-BALLAST NE REPLACED IN FRONT OF KARL					
Maritza Go	nzalez						
123425			9/30/2014		62		\$0.00
Medium	Work In Progress		9/30/2014 3:42:13 PM	1			
3		PROJECT MANAGEMENT & FINA ASBESTOS ABATEMENT AT GAC "A" WING					
Alfredo Ho	Iguin						
124879			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:06 AM	1			
Orozco, Da	niel	Yearly - GAC - Grease Trap - Ret details.	fer to PM schedule				
Margret Vil	lalobos						
125790			11/20/2014		11		\$0.00
Medium	Work In Progress		11/20/2014 8:18:52 AM	1			
Moncayo, F	Fernando	CLEAN OUTSIDE LIGHTS ON AL	L EXITS.				
	nzalez						

12/1/2014 3:28:27 PM

Location: GAC 125779 11/19/2014 12 Medium Work In Progress 11/19/2014 3.53.344 PM Moncayo, Fernando LINDA CASTRO NEEDS SEVERAL BOXES MOVED FROMLUDYM STORAGE. 11/13/2014 Maritza Gonzalez 11/13/2014 8.36.40 AM 18 Medium Work In Progress 11/13/2014 8.36.40 AM 14 Moncayo, Fernando A-WING-WALL NEEDS TO BE FIXED IN MENS HANDICAP RR. 11/13/2014 8.36.40 AM 18 Maritza Gonzalez 9/11/2014 9.48.04 AM 81 11/13/2014 8.36.40 AM 11/13/2014 8.36.40 AM 11/13/2014 8.36.40 AM 11/13/2014 9.48.04 AM 11/13/2014 9.18.11 AM 11/13/2014 9.12.11 AM 11/12/2014 9.12.11 AM 11/12/2014 9.12.1	WOID Priority Assigned Requester	Building Status To	•	te Target Comp Date ne Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Medium Work In Progress 11/19/20143:53:44 PM Moncayo, Fernando LINDA CASTRO NEEDS SEVERAL BOXES MOVED FROM LUDYM STORAGE. Invalue Maritza Gonzalez 11/13/2014 18 125495 11/13/2014 8:36:40 AM Invalue Moncayo, Fernando A-WING-WALL NEEDS TO BE FIXED IN MENS HANDICAP RR. Invalue Maritza Gonzalez 9/11/2014 81 Medium Work In Progress 9/11/2014 9/1 Moncayo, Fernando ROSA APODACA OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 81 Medium Work In Progress 9/11/2014 9/11/2014 Moncayo, Fernando MARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 81 Medium Work In Progress 9/11/2014 9/14 Moncayo, Fernando MARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 90 Medium Work In Progress 9/12/2014 9/14 Moncayo, Fernando BALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO. 90 Medium Work In Progress 9/2/2014 90 Medium Work In Progress 9/2/2014 9	-						
Moncayo, Fernando LINDA CASTRO NEEDS SEVERAL BOXES MOVED FROM LUDYM STORAGE. Maritza Gonzalez 11/13/2014 18 Sedafo 11/13/2014 8:36:40 AM 18 Medium Work In Progress 11/13/2014 8:36:40 AM 10 Moncayo, Fernando AWING-WALL NEEDS TO BE FIXED IN MENS HANDICAP RR. 81 Maritza Gonzalez 9/11/2014 84:04 AM Moncayo, Fernando ROSA APODACA OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 81 Medium Work In Progress 9/11/2014 9:48:24 AM 81 Moncayo, Fernando MARY TELLEZ OFFICE-BURNT SMELL COMING OUT OUT OF WALL UNIT. 81 Medium Work In Progress 9/11/2014 9:48:24 AM 81 Moncayo, Fernando MARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 90 Maritza Gonzalez 9/2/2014 9:18:11 AM 90 Moncayo, Fernando BALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO. 90 Maritza Gonzalez 9/2/2014 9:18:11 AM 90 Medium Work In Progress 9/2/2014 9:18:10 AM 90 Medium Work In Progress 11/2/2014 12:35:37 AM	125779		11/19/20	14	12		\$0.00
Maritza Gonzalez 11/13/2014 18 Medium Work In Progress 11/13/2014 8.36:40 AM 18 Medium Work In Progress 11/13/2014 8.36:40 AM 18 Moncayo, Fernando A-WING-WALL NEEDS TO BE FIXED IN MENS HANDICAP RR. 11/13/2014 8.36:40 AM 11/13/2014 9.48:04 AM Meritza Gonzalez 9/11/2014 9.48:04 AM 81 11/13/2014 9.48:04 AM 11/12/10 AM 11/13/2014 9.48:04 AM 11/13/2014 9.48:04 AM 11/13/2014 9.48:04 AM 11/12/10 AM 11/11/10/10 AM 11/11/10/10 AM 11/11/10/10 AM 11/11/10/10 AM 11/11/10/10 AM 11/11/10/10 AM 11/11/10/2014 9/18:11 AM 11/12/2014 11/10/2014 11/10/2014 9/18:11 AM 11/12/2014 11/10/2014 11/10/2014 11/10/2014 11/10/2014 11/10/2014 11/10/2014 11/10/2014 11/10/2014 11/10/2014 11/10/2014 11/10/2014 11/10/2014 11/1	Medium	Work In Progress	11/19/2014 3:53:44	PM			
125495 11/13/2014 18 Medium Work In Progress 11/13/2014 8:36:40 AM Moncayo, Fernando A-WING-WALL NEEDS TO BE FIXED IN MENS HANDICAP RR. 11/12/2014 Maritza Gonzalez 9/11/2014 81 122634 9/11/2014 9:48:04 AM 81 Medium Work In Progress 9/11/2014 9:48:04 AM 81 Moncayo, Fernando ROSA APODACA OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 81 Medium Work In Progress 9/11/2014 9:48:04 AM 81 Medium Work In Progress 9/11/2014 81 Medium Work In Progress 9/11/2014 9:48:04 AM 81 Moncayo, Fernando MARY TELLE ZOFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 81 Maritza Gonzalez 9/11/2014 9:48:24 AM 81 122154 9/2/2014 9:18:11 AM 90 Medium Work In Progress 9/2/2014 9:18:11 AM 90 Moncayo, Fernando BALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO. 11/12/2014 11/10/2014 29 Medium Work In Progress 11/12/2014 11/10/2014 29 11/12/2014 11/10/2014 29 Moncayo, Fernando Monthly - GAC Emer. Light Test: Monthly	Moncayo,	Fernando					
Netion Work In Progress 11/13/2014 8:36:40 AM Moncayo, Fernando A-WING-WALL NEEDS TO BE FIXED IN MENS HANDICAP RR.	Maritza Go	onzalez					
Moncayo, Fernando AWING-WALL NEEDS TO BE FIXED IN MENS HANDICAP RR. Maritza Gonzalez 9/11/2014 9/8 122634 9/11/2014 9/8 Medium Work In Progress 9/11/2014 9/8 Moncayo, Fernando ROSA APODACA OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 81 Medium Work In Progress 9/11/2014 9/8 Moncayo, Fernando MARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 81 Medium Work In Progress 9/11/2014 9/11/2014 Moncayo, Fernando MARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 9/11/2014 9/11/2014 Maritza Gonzalez 9/2/2014 9/2/2014 9/11/2014 9/11/2014 Medium Work In Progress 9/2/2014 9/2/2014 9/2/2014 Moncayo, Fernando BALLAST NEEDS TO BE CHANGED OUT IN ROSA 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/2/2014 29 Medium Work In Progress 11/2/2014 11/2/2014 29 Medium Work In Progress	125495		11/13/20	14	18		\$0.00
Manitza Gonzalez Manitza Gonzalez 122634 9/11/2014 81 Medium Work In Progress 9/11/2014 9/8 Moncayo, Fernando ROSA APODACA OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 81 Maritza Gonzalez 122635 9/11/2014 81 Medium Work In Progress 9/11/2014 9/8 9/11/2014 Medium Work In Progress 9/11/2014 9/11/2014 81 Medium Work In Progress 9/11/2014 9/11/2014 81 Medium Work In Progress 9/11/2014 9/11/2014 9/11/2014 Maritza Gonzalez	Medium	Work In Progress	11/13/2014 8:36:40	AM			
122634 9/11/2014 81 Medium Work In Progress 9/11/2014 9:48:04 AM Moncayo, Fernando ROSA APODACA OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. Maritza Gonzalez 81 Maritza Gonzalez 9/11/2014 9:48:04 AM 81 Medium Work In Progress 9/11/2014 9:48:02 AM 81 Medium Work In Progress 9/11/2014 9:48:02 AM 81 Moncayo, Fernando MARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 81 9/2/2014 9:48:02 AM Maritza Gonzalez 9/2/2014 9:48:02 AM 90 90 Medium Work In Progress 9/2/2014 91 90 Medium Work In Progress 9/2/2014 9:18:11 AM 90 Moncayo, Fernando BALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO. 90 90 90 Medium Work In Progress 11/2/2014 11/10/2014 29 90 Medium Work In Progress 11/2/2014 11/10/2014 29 90 90 90 90 <td< td=""><td>Moncayo,</td><td>Fernando</td><td></td><td></td><td></td><td></td><td></td></td<>	Moncayo,	Fernando					
Medium Work In Progress 9/11/2014 9:48:04 AM Moncayo, Fernando ROSA APODACA OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 81 Maritza Gonzalez 9/11/2014 9:48:24 AM 81 Medium Work In Progress 9/11/2014 9:48:24 AM 9 Moncayo, Fernando MARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT. 91 90 Maritza Gonzalez 9/2/2014 9:48:24 AM 90 90 Maritza Gonzalez 9/2/2014 9:48:24 AM 90 90 Maritza Gonzalez 9/2/2014 9:48:24 AM 90 90 Moncayo, Fernando BALLAST NEELO STOFICE-BURNT SMELL COMING OUT OF WALL UNIT. 90 90 Medium Work In Progress 9/2/2014 9:18:11 AM 90 90 Moncayo, Fernando BALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDAGO. 91 11/2/2014 12:35:37 AM 91 Moncayo, Fernando Monthly- GAC Emer. Light Test: Monthly - Refer to PM schedule details. 91 92 Margret Villalobos 11/2/2014 12:35:37 AM 91 92 Margret Villalobos 11/2/2014 12:35:19 AM 92 92 <tr< td=""><td>Maritza Go</td><td>onzalez</td><td></td><td></td><td></td><td></td><td></td></tr<>	Maritza Go	onzalez					
Moncayo, FernandoROSA APODACA OFFICE-BURNT SMELL COMING OUT OF WALL UNIT.Maritza Gonzalez9/11/20141226359/11/2014MediumWork In ProgressMoncayo, FernandoMARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT.Maritza Gonzalez1/1/20141221549/2/20141221549/2/2014Moncayo, FernandoBALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO.Maritza Gonzalez11/2/201412493311/2/201411/2/201411/10/2014Moncayo, FernandoMonthly- GAC Emer. Light Test: Monthly - Refer to PM schedule details.Margret Villalobos11/2/201411/2/201411/10/201412490211/2/2014Moncayo, FernandoMonthly- GAC Exit Sign Insp: Monthly - Refer to PM schedule details.Moncayo, FernandoMonthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.	122634		9/11/20	14	81		\$0.00
Maritza Gonzalez1226359/11/201481MediumWork In Progress9/11/2014 9:48:24 AMMoncayo, FernandoMARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT.9/11/2014 9:48:24 AMMaritza Gonzalez1221549/2/20141221549/2/2014 9:18:11 AM90MediumWork In Progress9/2/2014 9:18:11 AMMoncayo, FernandoBALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO.11/2/2014Maritza Gonzalez11/2/201411/10/201412493311/2/201411/10/2014Moncayo, FernandoMonthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.11/2/2014Margret Villalobos11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429Margret Villalobos11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/2/201429MediumWork In Progress11/2/201411/10/201429Medium<	Medium	Work In Progress	9/11/2014 9:48:04	AM			
1226359/11/201481MediumWork In Progress9/11/2014 9:48:24 AMKMoncayo, FernandoMARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT.OF WALL UNIT.Maritza Gonzalez9/2/201490MediumWork In Progress9/2/2014 9:18:11 AMMoncayo, FernandoBALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO.FMaritza Gonzalez11/2/201411/10/201412493311/2/201411/10/2014Moncayo, FernandoMonthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.11/2/2014Margret Villalobos11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429Margret Villalobos11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/10/201429MediumWork In Progress11/2/201411/2/201411/2/2014Moncayo, FernandoMonthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.Schedule details.	Moncayo,	Fernando					
MediumWork In Progress9/11/2014 9:48:24 AMMoncayo, FernandoMARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT.Maritza Gonzalez1221549/2/20141221549/2/2014 9:18:11 AMMoncayo, FernandoBALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO.Maritza Gonzalez12493311/2/201411/2/201411/10/201429MediumWork In ProgressMoncayo, FernandoMonthly- GAC Emer. Light Test: Monthly- Refer to PM schedule details.Margret Villalobos11/2/201412490211/2/201411/2/201411/10/20142911/2/2014MediumWork In ProgressMoncayo, FernandoMonthly- GAC Emer. Light Test: Monthly- Refer to PM schedule details.Margret Villalobos11/2/201411/2/201411/10/20142911/2/2014MediumWork In ProgressMoncayo, FernandoMonthly- GAC Exit Sign Insp: Monthly- Refer to PM schedule details.Moncayo, FernandoMonthly- GAC Exit Sign Insp: Monthly- Refer to PM schedule details.	Maritza Go	onzalez					
Moncayo, FernandoMARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT.Maritza Gonzalez9/2/20141221549/2/2014 9:18:11 AMMoncayo, FernandoBALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO.Maritza Gonzalez11/2/201411/293311/2/2014Moncayo, FernandoMonthly- GAC Emer. Light Test: Monthly- Refer to PM schedule details.Margret Villalobos11/2/201412490211/2/201411/2/201411/10/20142929Medium Work In Progress11/2/2014Moncayo, FernandoMonthly- GAC Emer. Light Test: Monthly- Refer to PM schedule details.Margret Villalobos11/2/201411/2/201411/10/20142911/2/2014Moncayo, FernandoMonthly- GAC Exit Sign Insp: Monthly- Refer to PM schedule details.Moncayo, FernandoMonthly- GAC Exit Sign Insp: Monthly- Refer to PM schedule details.	122635		9/11/20	14	81		\$0.00
Maritza Gonzalez 9/2/2014 122154 9/2/2014 9:18:11 AM Moncayo, Fernando BALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO. Maritza Gonzalez 11/2/2014 124933 11/2/2014 Moncayo, Fernando Monthly- GAC Emer. Light Test: Monthly- Refer to PM schedule details. Margret Villalobos 11/2/2014 124902 11/2/2014 Moncayo, Fernando Monthly- GAC Emer. Light Test: Monthly- Refer to PM schedule details. Margret Villalobos 11/2/2014 124902 11/2/2014 Moncayo, Fernando Monthly- GAC Exit Sign Insp: Monthly- Refer to PM schedule details.	Medium	Work In Progress	9/11/2014 9:48:24	AM			
1221549/2/201490MediumWork In Progress9/2/2014 9:18:11 AMMoncayo, FernandoBALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO.Maritza Gonzalez11/2/201412493311/2/2014MediumWork In ProgressMoncayo, FernandoMonthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.Margret Villalobos11/2/201412490211/2/2014MediumWork In ProgressMoncayo, FernandoMonthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.Margret Villalobos11/2/201411/2/201411/10/20142911/2/2014MediumWork In ProgressMoncayo, FernandoMonthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.	Moncayo,	Fernando					
Medium Work In Progress 9/2/2014 9:18:11 AM Moncayo, Fernando BALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO. Maritza Gonzalez 1 124933 11/2/2014 Medium Work In Progress Moncayo, Fernando Monthly- GAC Emer. Light Test: Monthly - Refer to PM schedule details. Margret Villalobos 11/2/2014 124902 11/2/2014 Medium Work In Progress Margret Villalobos 11/2/2014 124902 11/2/2014 Medium Work In Progress Medium Work In Progress Margret Villalobos 11/2/2014 Medium Work In Progress Moncayo, Fernando Monthly- GAC Exit Sign Insp: Monthly- Refer to PM schedule details. Moncayo, Fernando Monthly- GAC Exit Sign Insp: Monthly- Refer to PM schedule details.		onzalez					
Moncayo, FernandoBALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO.Maritza Gonzalez11/2/201412493311/2/201411/10/2014MediumWork In Progress11/2/2014 12:35:37 AMMoncayo, FernandoMonthly- GAC Emer. Light Test: Monthly- Refer to PM schedule details	122154		9/2/20	14	90		\$0.00
Maritza Gonzalez12493311/2/201411/10/201429Medium Work In Progress11/2/2014 12:35:37 AMMoncayo, FernandoMonthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.Margret Villalobos11/2/201411/10/20142912490211/2/201411/10/201429Medium Work In Progress11/2/201411/10/201429Medium Work In Progress11/2/201412:35:19 AMMoncayo, FernandoMonthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.	Medium	Work In Progress	9/2/2014 9:18:11	AM			
12493311/2/201411/10/201429MediumWork In Progress11/2/2014 12:35:37 AM11/2/2014 12:35:37 AMMoncayo, FernandoMonthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.11/2/2014 12:35:37 AMMargret Villalobos11/2/201411/10/20142912490211/2/201411/10/201429MediumWork In Progress11/2/2014 12:35:19 AM11/2/2014Moncayo, FernandoMonthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.Monthly - Refer to PM	Moncayo,	Fernando					
Medium Work In Progress 11/2/2014 12:35:37 AM Moncayo, Fernando Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details. Margret Villalobos 11/2/2014 124902 11/2/2014 11/0/2014 29 Medium Work In Progress 11/2/2014 12:35:19 AM 11/0/2014 29 Moncayo, Fernando Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details. 11/0/2014 29		onzalez					
Moncayo, Fernando Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details. Margret Villalobos 11/2/2014 124902 11/2/2014 11/0/2014 29 Medium Work In Progress 11/2/2014 12:35:19 AM 11/2/2014 29 Moncayo, Fernando Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details. 11/2/2014 11/2/2014 11/2/2014	124933		11/2/20	14 11/10/2014	29		\$0.00
Margret Villalobos 11/2/2014 11/10/2014 29 124902 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 12:35:19 AM Moncayo, Fernando Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details. Vorte PM	Medium	Work In Progress	11/2/2014 12:35:37	AM			
124902 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 12:35:19 AM Moncayo, Fernando Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details. 10	Moncayo,	Fernando					
Medium Work In Progress 11/2/2014 12:35:19 AM Moncayo, Fernando Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.		llalobos					
Moncayo, Fernando Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.	124902		11/2/20	14 11/10/2014	29		\$0.00
schedule details.	Medium	Work In Progress	11/2/2014 12:35:19	AM			
Margret Villalohos	Moncayo,	Fernando					
	Margret Vi	llalobos					

WOID Priority Assigned 7 Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	GAC					
124699		10/28/2014		34		\$0.00
Medium	Work In Progress	10/28/2014 3:42:02 PM				
Moncayo, F	Fernando	As per Mike, please check outside of building for holes on walls and cover up, due to mice problems.				
Michael Mu	unoz					
123988		10/10/2014		52		\$0.00
Medium	Work In Progress	10/10/2014 10:41:48				
Moncayo, F	Fernando	As per Mr. Yturralde some ceiling tiles that are rain stained need to be replaced in all of the halls here at GAC. Also, the pile of dirt at the entrance entering from McNutt needs to be removed.				
Efren Yturr	alde					
125939		11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:46:54				
Moncayo, F	Fernando	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vil	lalobos					* •••••
125941		11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:46:55				
Moncayo, F		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vil	lalobos			- 10		* •••••
125757		11/19/2014		12		\$0.00
Medium	Work In Progress	11/19/2014 2:18:32 PM				
Moncayo, F		HR REQEUSTING TO HAVE HR CONFERENCE ROOM PAINTED.				
Maritza Go	nzalez					
125758		11/19/2014		12		\$0.00
Medium	Work In Progress	11/19/2014 2:19:08 PM				
Moncayo, F	Fernando	AS PER ELISA,LIGHT ABOVE ENTRANCE DOOR NEEDS TO CLEANED OUT.				
Maritza Go	nzalez					
121836		8/27/2014		96		\$0.00
Medium	Work In Progress	8/27/2014 12:18:38 PM				
Moncayo, F	Fernando	As per Mrs. Yturralde she would like for you to put in a work order to have the bathroom painted, the one right across Karla Quezada office.				
Maritza Go	nzalez					

WOID Priority Assigned Requester	Building Status To		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	GAC					
121419		8/19/2014	ļ	104		\$0.00
Medium	Work In Progress	8/19/2014 11:43:45 AN	Л			
Moncayo,	Fernando	NO POWER TO WALL UNIT IN ROSA HIDALGO OFFICE.				
Maritza Go	onzalez					
124679		10/28/2014		34		\$0.00
Medium	Work In Progress	10/28/2014 12:42:22	2			
Villalobos	, Margret	HR Wing - Lupita's Office issue with mice in her office, have set traps and have caught some, but problem persists.	emailed 10/28/14 and receiv	ed waiver	form.	
Lucy Garc	ia					
123643		10/5/2014	Ļ	57		\$0.00
Medium	Work In Progress	10/5/2014 12:43:27 AN	Л			
Holguin, A	lfredo	Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PMschedule details.				
Margret Vi	llalobos					
125339		11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress	11/9/2014 12:41:36 AN	Л			
Moncayo,	Fernando	Monthly - GAC Playground Insp - Refer to PM schedule details.				
Margret Vi	llalobos					
125268		11/7/2014	Ļ	24		\$0.00
Medium	Work In Progress	11/7/2014 8:23:49 AN	Л			
Moncayo,	Fernando	MRS. FIELDS WOULD LIKE A DOOR STOP INSTALLED.				
Maritza Go	onzalez					
126009		11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:40	0			
Moncayo,	Fernando	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.				
Margret Vi	llalobos					
124987		11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:09 AM	Л			
Moncayo,	Fernando	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.				
Margret Vi	llalobos					

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Locatic Area Deferred By U Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	GAC						
125214			11/6/2014		25		\$0.00
Medium	Work In Progress		11/6/2014 8:50:43 AN	I			
Ronquillo,	, Ruben	need to borrow the chain zaw and chain	oil				
Fernando	Moncayo						
125026			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:33 AN	I			
Orozco, Da	aniel	Monthly - GAC Range Hood Cleaning - schedule details.	Refer to PM				
Margret Vil	llalobos						
123748		Restroom (Girls)	10/6/2014		56		\$0.00
High	Work In Progress		10/6/2014 3:43:57 PM	1			
Estrada, J	esus	Replace tile in bathroom it was removed c wing	d over fall break				
Jesus Est	trada						
120354			8/3/2014		120		\$0.00
Medium	Work In Progress		8/3/2014 12:33:51 AN	l			
Munoz, Mio	chael	Yearly - GAC Fire Ext. Insp. (Yearly) - Re schedule details.	efer to PM				
Margret Vil	llalobos			1.1.100.100.1.1			
125035			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:38 AN	l			
Orozco, Da		Monthly - GAC Fire Suppression Insp schedule details.	Refer to PM				
Margret Vi	llalobos						
123689			10/5/2014	10/26/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:44:02 AN	I			
Munoz, Mio	chael	Monthly - GAC Fire Sprinkler Insp Ref schedule details.	fer to PM				
Margret Vi							
Count: 50	Work Orders	Avg. Age of WO's 46		Total for	GAC	0	\$0

1237		uei 5 III	riogress	5 (1 150	aiiteaij				Total
Selected Da	ate Range for Request Building	Dates:7/1/2014 - 1 Area	1/30/2014 Order By Deferred By	Location, Stati Until		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Cr	eated Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requester	r Name								
Location:	GAC - Pre	ə-K							
125810					11/20/2014		11		\$0.00
Medium	Work In Progress			11/20)/2014 3:06:53 PM				
Moncayo,	Fernando	PRE-K, RM 20 [.] PROPERLY.	1 HEATER IS NOT	HEATING					
Maritza Go	onzalez								
124226					10/16/2014		46		\$0.00
Medium	Work In Progress			10/16	6/2014 8:57:29 AM				
Moncayo,	Fernando	RM. 103- SINK	IS LEAKING.						
Maritza Go	onzalez								
Count: 2 W	Vork Orders	A	vg. Age of WO's	29		Total for GAC - F	Pre-K	0	\$0.00

11/2/2014 29 Medium Work In Progress 11/2/2014 12:34:59 AM Villalobos, Margret Monthly- Gads den ES - Trane PM Quarterly - Refer to PM schedule details. Emailed 11/3/14 Margret Villalobos 9/4/2014 9:12:27 AM 88 122237 Athletic Field 9/4/2014 9:12:27 AM 88 Appelzoller, Fred need to cut weeds through out site, inside and outside offence. also the weeds that have been killed with round up need to be cut as well. school is in dire need of weed control. need to include ponds. 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Margret Villalobos 11/2/2014 11/10/2014 29 Margret Villalobos 11/2/2014 11/2/2014 1 Medium Work In Progress 11/10/2014	Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By L Area Deferred By Area Number Reason Description	Until Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Network Work In Progress 11/2/2014 12:34:59 AM Villalobos Margret Monthly- Gadsden ES - Trane PM Quarterly - Refer to PM Schedule details. Emailed 11/3/14 Margret Villalobos Athletic Field 9/4/2014 9:12:27 AM 88 T22297 Athletic Field 9/4/2014 9:12:27 AM 88 Appelzoller, Fred need to cut weeds through out site, inside and outside offence, also the weeds that have been killed with round up need to be cut as well, school is in dire need of weed control. need to include ponds. 11/10/2014 29 Mchael Munoz 11/2/2014 12:35:36 AM 29 11/2/2014 11/10/2014 29 Medium Work In Progress Monthly- Gadsden ES - Exit Sign Insp-Monthly- Refer to PM Schedule details. 11/2/2014 11/10/2014 29 Medium Work In Progress 11/3/2/2014 1 1 Appelzoller, Fred Monthly- Gadsden ES - Clothes Dryer (Monthly) - Ref	Location:	Gadsden	ES					
Milalobos, Margret Margret Villalobos Monthly- Gadsden ES - Trane PM Quarterly - Refer to PMschedule details. Emailed 11/3/14 Margret Villalobos 4Ahletic Field 9/4/2014 88 High Work In Progress 9/4/2014 9:12:27 AM 88 Appelzoller, Fred need to cutweeds through out sile, inside and outside or fence, also the weeds that have been killed with round up need to be cut as well school is in dire need of weed control, need to include ponds. 11/1/2014 19 Michael Munoz 11/2/2014 11/1/2/2014 29 Medium Work In Progress 11/2/2014 12:35:36 AM 9 Appelzoller, Fred Monthly- Gadsden ES - Exit Sign Insp-Monthly- Refer to PMschedule details. 9 9 Margret Villalobos 11/2/2014 11/10/2014 29 Medium Work In Progress 11/30/2014 1 1 Medium Work In Progress 11/30/2014<	124868			11/2/2014	ļ	29		\$0.00
PMschedule details. Margret Villalobos 88 122297 Athletic Field 9/4/2014 9/3 122297 Athletic Field 9/4/2014 9/3 Appelzoller, Fred need to cut weeds through out site, inside and outside of fence. also the weeds that have been killed with round up need to be cut as well. school is in dire need of weed control. need to include ponds. Int/2/2014 11/10/2014 29 Michael Munoz 11/2/2014 11/10/2014 29 Introduction 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 12/35:36 AMI 29 Medium Work In Progress 11/2/2014 12/30:2014 29 Medium Work In Progress 11/2/2014 12/30:2014 29 Medium Work In Progress 11/2/2014 12/30:2014 1 Medium Work In Progress 11/30/2014 1 1 Stargret Villalobos 11/30/2014 1<	Medium	Work In Progress		11/2/2014 12:34:59 AM	Л			
122297 Athletic Field 9/4/2014 88 High Work In Progress 9/4/2014 9:12:27 AM 88 Appelzoller, Fred need to cut weeds that have been killed with round up need to be cut as well, school is in dire need of weed control. need to include ponds. 11/2/2014 11/10/2014 29 Michael Munoz 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Margret Villalobos 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 1 1 Medium Work In Progress 11/30/2014 1 1		-		Quarterly - Refer to	Emailed 11/3/14			
NumberAppelzoller, Fredneed to cut weeds through out site, inside and outside orfence. also the weeds that have been killed with round up need to be cut as well, school is indire need of weed control. need to include ponds.Michael Munoz11/2/201411/10/20142912493111/2/201411/10/201429MediumWork In Progress11/2/201412/35:36 AMAppelzoller, FredMonthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PMschedule details.11/10/201429MediumWork In Progress11/12/201411/10/201429MediumWork In Progress11/13/0/201411MediumWork In Progress11/13/0/201411MediumWork In Progress11/13/0/201411MediumWork In Progress11/13/0/201412/8/20141MediumWork In Progress11/13/0/201411MediumWork In Progress11/13/0/201412/8/20141MediumWork In Progress11/13/0/201412/8/20141MediumWor		llalobos		0/4/2044	1	00		¢0.00
Appelzoller, Fred need to cut weeds that have been killed with round up need to be cut as well, school is in dire need of weed control. need to include ponds. Michael Munoz 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 12/35:36 AM 9 Appelzoller, Fred Monthly- Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details. 9 9 Margret Villalobos 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 12/10/2014 29 Medium Work In Progress 11/2/2014 12/10/2014 29 Medium Work In Progress 11/2/2014 1 1 Medium Work In Progress 11/2/2014 1 1 Medium Work In Progress 11/30/2014 1 1 Medium Work In Progress 11/30/2014 1 1			Athletic Field			88		\$0.00
offence. also the weeds fhat have been killed with round up need to be cut as well. school is in dire need of weed control. need to include ponds.Michael Munoz11/2/201411/10/20142912493111/2/2014 12:35:36 AM29MediumWork In Progress11/2/2014 12:35:36 AM4Appelzoller, FredMonthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PMschedule details.11/10/201429MediumWork In Progress11/12/201411/10/201429MediumWork In Progress11/12/201411/10/201429MediumWork In Progress11/12/201411/10/201429MediumWork In Progress11/12/201411/10/201429MediumWork In Progress11/130/201411/10/201429MediumWork In Progress11/30/201411/10/1429Margret Villalobos11/30/2014111/10/142912593611/30/201411/130/2014111/10/1411/10/14MediumWork In Progress11/130/2014111/14Margret Villalobos11/130/201412/8/20141112593711/130/201412/8/201411MediumWork In Progress11/130/201412/8/20141MediumWork In Progress11/130/201412/8/20141MediumWork In Progress11/130/201412/8/20141MediumWork In Progress11/130/201412/8/20141MediumWork In Prog	-	-			И			
124931 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 12:35:36 AM 4 Appelzoller, Fred Monthly- Gadsden ES - Exit Sign Insp-Monthly - Refer to PMschedule details. 4 4 Margret Villalobos 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Margret Villalobos 11/2/2014 12/2014 1 Medium Work In Progress 11/30/2014 1 Medium Work In Progress 11/30/2014 1 Medium Work In Progress 11/30/2014 1 Appelzoller, Fred Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PMschedule details. 1 Margret Villalobos 1 11/30/2014 1 125937 11/30/2014 1 1 Medium Work In Progress 11/30/2014 1 Appelzoller, Fred Monthly - Gadsden ES - Exit Sign Insp-Monthly -	Appelzolle	r, Fred	of fence. also the weeds that have a round up need to be cut as well. scl	been killed with hool is in dire need of				
Medium Work In Progress 11/2/2014 12:35:36 AM Appelzoller, Fred Monthly- Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details. Margret Villalobos 124932 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 11/10/2014 29 Margret Villalobos 11/2/2014 11/30/2014 29 Medium Work In Progress 11/30/2014 1 Medium Work In Progress 11/30/2014 1 Medium Work In Progress 11/30/2014 1 Appelzoller, Fred Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details. 1 Margret Villalobos 1 1 1 125937 11/30/2014 1 1 Medium Work In Progress 11/30/2014 1 1 Medium Work In Progress 11/30/2014 1 1		unoz		4.4/0/0044				* • • • •
Appelzoller, FredMonthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PMschedule details.Margret Villalobos11/2/201411/10/201429MediumWork In Progress11/2/2014 12:35:37 AM29MediumWork In Progress11/2/2014 12:35:37 AM4Appelzoller, FredMonthly - Gadsden ES - Emer Light Test - Monthly - Refer to PMschedule details.4Margret Villalobos11/30/2014112593611/30/20141MediumWork In Progress11/30/2014 12:46:524Appelzoller, FredMonthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.4Margret Villalobos11/30/2014 12:46:524Margret Villalobos11/30/201412/8/20141MediumWork In Progress11/30/2014 12:46:534Appelzoller, FredMonthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.4Margret Villalobos11/30/2014 12:46:534Appelzoller, FredMonthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.4Margret Villalobos11/30/2014 12:46:534Appelzoller, FredMonthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.4Margret Villalobos11/30/2014 12:40:531Margret Villalobos11/30/2014 12:40:531MediumWork In Progress11/30/2014 12:46:531						29		\$0.00
Margret Villalobos12493211/2/201411/10/201429MediumWork In Progress11/2/2014 12:35:37 AM29Appelzoller, FredMonthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.1Margret Villalobos11/30/2014112593611/30/2014 12:46.521Appelzoller, FredMonthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.1Margret Villalobos11/30/2014 12:46.521Appelzoller, FredMonthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.1Margret Villalobos11/30/2014 12:46.531Margret Villalobos11/30/2014 12:46.531Margret Villalobos11/30/2014 12:46.531MediumWork In Progress11/30/2014 12:46.531Margret Villalobos11/30/2014 12:46.531MediumWork In Progress11/30/2014 12:46.531Appelzoller, FredMonthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.1Margret Villalobos11/30/2014 12:46.531Margret Villalobos11/30/2014 12:46.531Margret Villalobos11/30/2014 12:46.531Margret Villalobos11/30/2014 12:46.531Margret Villalobos11/30/2014 12:46.531MediumWork In Progress11/30/2014 12:46.531	Medium	Work In Progress		11/2/2014 12:35:36 AM	Л			
124332 11/2/2014 11/10/2014 29 Medium Work In Progress 11/2/2014 12:35:37 AM Appelzoller, Fred Monthly - Gadsden ES - Emer Light Test - Monthly- Refer to PMschedule details. Margret Villalobos 1 1 1 Medium Work In Progress 11/30/2014 1 Medium Work In Progress 11/30/2014 12:46:52 4 Appelzoller, Fred Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PMschedule details. 1 Margret Villalobos 11/30/2014 12:46:52 4 125937 11/30/2014 12:46:53 1 Medium Work In Progress 11/30/2014 12:46:53 1 Appelzoller, Fred Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PMschedule details. 1 Medium Work In Progress 11/30/2014 12:46:53 1 Appelzoller, Fred Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PMschedule details. 1 Margret Villalobos 11/30/2014 12:46:53 1 125938 11/30/2014 12/8/2014 1 Medium Work In Progress 11/30/2014 12:46:53 1				nsp-Monthly - Refer				
MediumWork In Progress11/2/2014 12:35:37 AMAppelzoller, FredMonthly - Gads den ES - Emer Light Test - Monthly - Refer to PM schedule details.Margret Villalobos11/30/201412593611/30/2014 12:46:52Appelzoller, FredMonthly - Gads den ES - Clothes Dryer (Monthly) - Refer to PM schedule details.Margret Villalobos11/30/2014 12:46:52Appelzoller, FredMonthly - Gads den ES - Clothes Dryer (Monthly) - Refer to PM schedule details.Margret Villalobos11/30/2014 12:46:53Appelzoller, FredMonthly - Gads den ES - Exit Sign Insp-Monthly - Refer to PM schedule details.MediumWork In Progress11/30/2014 12:46:53Appelzoller, FredMonthly - Gads den ES - Exit Sign Insp-Monthly - Refer to PM schedule details.Margret Villalobos11/30/2014 12:46:53Appelzoller, FredMonthly - Gads den ES - Exit Sign Insp-Monthly - Refer to PM schedule details.Margret Villalobos11/30/2014 12:46:53Margret Villalobos11/30/2014 12:46:53Margret Villalobos11/30/2014 12:46:53Margret Villalobos11/30/2014 12:46:53Margret Villalobos11/30/2014 12:46:53Margret Villalobos11/30/2014 12:46:53Margret Villalobos11/30/2014 12:46:53		llalobos		44/0/0044	44/40/0044			<u> </u>
Appelzoller, FredMonthly - Gadsden ES - Emer Light Test - Monthly- Refer to PMschedule details.Margret Villalobos11/30/2014112593611/30/2014 12:46:521MediumWork In Progress11/30/2014 12:46:521Appelzoller, FredMonthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PMschedule details.1Margret Villalobos112/8/2014112593711/30/2014 12:46:531MediumWork In Progress11/30/2014 12:46:531Appelzoller, FredMonthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PMschedule details.1Margret Villalobos112/8/20141MediumWork In Progress11/30/2014 12:46:531Margret Villalobos111Margret Villalobos111Margret Villalobos111Margret Villalobos111Margret Villalobos111Margret Villalobos111/30/2014 12:46:531Margret Villalobos111/30/2014 12:46:531Margret Villalobos111MediumWork In Progress11/30/2014 12:46:531						29		\$0.00
Margret Villalobos12593611/30/20141MediumWork In Progress11/30/2014 12:46:52Appelzoller, FredMonthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PMschedule details					И			
12593611/30/20141MediumWork In Progress11/30/2014 12:46:521Appelzoller, FredMonthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.1Margret Villalobos11/30/201412/8/2014112593711/30/201412/8/20141MediumWork In Progress11/30/2014 12:46:531Appelzoller, FredMonthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.1Margret Villalobos11/30/2014 12:46:531Margret Villalobos11/30/20141Margret Villalobos11/30/201412/8/2014Margret Villalobos11/30/201412/8/2014Margret Villalobos11/30/201412/8/2014MediumWork In Progress11/30/201412/8/2014MediumWork In Progress11/30/201412/8/2014MediumWork In Progress11/30/201412/8/2014				nt Test - Monthly -				
MediumWork In Progress11/30/2014 12:46:52Appelzoller, FredMonthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.Margret Villalobos11/30/201412593711/30/2014MediumWork In ProgressAppelzoller, FredMonthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.Margret Villalobos11/30/2014 12:46:53Appelzoller, FredMonthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.Margret Villalobos11/30/2014 12:46:53Margret Villalobos11/30/201412593811/30/2014MediumWork In Progress11/30/2014 12:46:531		llalobos		11/20/2014	1	1		¢0.00
Appelzoller, FredMonthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.Margret Villalobos11/30/201412/8/2014112593711/30/2014 12:46:531MediumWork In Progress11/30/2014 12:46:531Appelzoller, FredMonthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.1Margret Villalobos1112593811/30/201412/8/2014MediumWork In Progress11/30/20141MediumWork In Progress11/30/20141						I		\$0.00
Margret Villalobos12593711/30/201412/8/20141MediumWork In Progress11/30/2014 12:46:531Appelzoller, FredMonthly- Gadsden ES - Exit Sign Insp-Monthly - Refer to PMschedule detailsMargret Villalobos11/30/2014 12:46:53112593811/30/201412/8/20141MediumWork In Progress11/30/2014 12:46:53-		-			2			
125937 11/30/2014 12/8/2014 1 Medium Work In Progress 11/30/2014 12:46:53 1 Appelzoller, Fred Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details. 1 Margret Villalobos 11/30/2014 12/8/2014 1 125938 11/30/2014 12/8/2014 1 Medium Work In Progress 11/30/2014 12:46:53 1				ryer (Monthly) - Refer				
Medium Work In Progress 11/30/2014 12:46:53 Appelzoller, Fred Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details. Margret Villalobos 11/30/2014 125938 11/30/2014 12/8/2014 Medium Work In Progress 11/30/2014 12:46:53		llalobos		11/20/2014	12/0/2014	1		¢0.00
Appelzoller, Fred Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details. Margret Villalobos 11/30/2014 125938 11/30/2014 12/8/2014 Medium Work In Progress 11/30/2014 12:46:53						I		\$0.00
Margret Villalobos 11/30/2014 12/8/2014 1 Medium Work In Progress 11/30/2014 12:46:53 1					3			
125938 11/30/2014 12/8/2014 1 Medium Work In Progress 11/30/2014 12:46:53 1	Appelzolle	r, Fred		nsp-Monthly - Refer				
Medium Work In Progress 11/30/2014 12:46:53		llalobos		4.4.100.1004.4				* ••••
						1		\$0.00
Appelzeller, Fred Monthly, Gadsden FS, Emer Light Test, Monthly,	Medium	Work In Progress		11/30/2014 12:46:53	3			
Refer to PMschedule details.	Appelzolle		Monthly - Gadsden ES - Emer Ligh Refer to PMschedule details.	nt Test - Monthly -				

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	ES				
125625		Office 11/17/2014		14		\$0.00
Medium	Work In Progress	11/17/2014 10:31:47				
Appelzolle	er, Fred	need assistance in setting up butcher paper rack would greatly appreciate your assistance in this matter				
Loraine G	andara					
125338		11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress	11/9/2014 12:41:35 AM				
Appelzolle	er, Fred	Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.				
Margret Vi	llalobos					
120332		8/3/2014		120		\$0.00
Medium	Work In Progress	8/3/2014 12:33:36 AM				
Munoz, Mi	chael	Yearly - Gadsden ES Fire Ext. Insp. (Yearly) - Refer to PMschedule details.				
Margret Vi	llalobos					
125027		11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:33 AM				
Orozco, Da	aniel	Monthly-Gadsden ES - Range Hood Cleaning - Refer to PMschedule details.				
Margret Vi	llalobos					
124986		11/2/2014	11/13/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:08 AM				
Appelzolle	er, Fred	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PMschedule details.				
Margret Vi	llalobos					
126010		11/30/2014	12/11/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:41				
Appelzolle	er, Fred	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PMschedule details.				
Margret Vi	llalobos					
125129		11/4/2014		27		\$0.00
Medium	Work In Progress	11/4/2014 12:36:00 AM				
Apodaca,	Mario	Monthly - Gadsden ES - Domestic Water Filter - Refer to PMschedule details.				
Margret Vi	llalobos					

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loo Area Deferred By Area Number Reason Description	Until Request Date Tai Created Date/Time Ac	-	Costs
Location:	Gadsden	ES			
124877			11/2/2014	29	\$0.00
Medium	Work In Progress		11/2/2014 12:35:05 AM		
Orozco, Da	niel	Yearly - Gadsden ES - Grease Trap schedule details.	- Refer to PM		
Margret Vil	lalobos				
123039		Parking Lot	9/23/2014	69	\$0.00
Medium	Work In Progress		9/23/2014 8:35:17 AM		
Sotelo, Enr	rique	need for the lights to be replaced out lotgreatly appreciate your assistan			
Loraine Ga	andara				
120937		Exterior	8/11/2014	112	\$0.00
Medium	Work In Progress		8/11/2014 1:54:30 PM		
Sotelo, Enr	rique	need (40) 50 watt metal /hi blubs for (10) fluorescent 4 Pin 30 watt lamp a lighting			
Fred Appel	Izoller				
120231			8/3/2014	120	\$0.00
Medium	Work In Progress		8/3/2014 12:32:24 AM		
Villalobos,	Margret	Monthly - Gadsden ES - Trane PM C PMschedule details.	Quarterly - Refer to En	ailed 8/4/14	
Margret Vil	lalobos				
125788		Office	11/20/2014	11	\$0.00
Medium	Work In Progress		11/20/2014 8:00:37 AM		
Appelzollei	r, Fred	need spray can s to paint , flower po 15 cans of almond or white	ots out in front about		
Fred Appel	Izoller				
122373		Parking Lot	9/5/2014	87	\$0.00
Medium	Work In Progress		9/5/2014 9:46:47 AM		
Ontiveros,	Guadalupe	need for cement barriers to be mour would really appreciate if this could b thank you			
Loraine Ga	andara				
121431		Football Field	8/19/2014	104	\$0.00
Medium	Work In Progress		8/19/2014 2:07:17 PM		
Ontiveros,	Guadalupe	need new nets for Goal Posts befor will begin their games by thenPer appreciate your assistance in this m	r Mr. Munoz greatly		
Loraine Ga	andara				

1201			riogress	5 (1 130	arrear				Tota
Selected Da WOID Priority	ate Range for Request Building Status	Dates:7/1/2014 - 1 Area Area Number	Deferred By	Until	Request Date	Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned		Description	Reason			Action Taken	•		
Requeste	r Name								
Location:	Gadsden	ES							
121434		Football Field			8/19/2014		104		\$0.00
Medium	Work In Progress			8/19	/2014 2:15:01 PN	1			
Ontiveros	, Guadalupe	•	ing for another Goa ppreciate your ass						
Loraine G	andara								
125028					11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress			11/2/2	2014 12:36:34 AM	1			
Orozco, Da	aniel	Monthly-Gads to PMschedule	den ES - Fire Supp details.	ression Insp	- Refer				
Margret Vi	llalobos								
Count: 23	Work Orders	Α	vg. Age of WO's	47		Total for Gadsde	en ES	0	\$0.00

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	HS						
124657				10/28/2014		34		\$0.00
Medium	Work In Progress			10/28/2014 12:39:16				
Hernande	z, Guillermo	Weekly - Gadso PMschedule do		(Biweekly) - Refer to				
Margret Vil	lalobos							
125412				11/11/2014		20		\$0.00
Medium	Work In Progress			11/11/2014 12:45:12				
Hernande	z, Guillermo	Weekly - Gadso PMschedule do		(Biweekly) - Refer to				
Margret Vil	lalobos			44/05/0044				.
125884				11/25/2014		6		\$0.00
Medium	Work In Progress			11/25/2014 12:45:22				
Hernande	z, Guillermo	Weekly - Gadso PMschedule do		(Biweekly) - Refer to				
Margret Vil	lalobos							
123694				10/5/2014		57		\$0.00
Medium	Work In Progress			10/5/2014 12:44:06 AM				
Munoz, Mic	chael	Monthly - Gads PMschedule de	den HS - Fire Sprin etails.	kler Insp Refer to				
Margret Vil	lalobos				1.1.100.100.1.1			* • • • •
125036				11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress			11/2/2014 12:36:39 AM				
Orozco, Da	aniel	Monthly-Gadso PMscheduledo		ssion Insp Refer to				
Margret Vil	lalobos			44/04/0044		- 10		.
125866		Athletic Field		11/21/2014		10		\$0.00
Medium	Work In Progress			11/21/2014 3:30:35 PM				
Ontiveros,	Guadalupe	track needs to b replace the san tracks was add warning track a	Ms. L. Chavez for So be widened and ther ad that was placed th ed. The spoiler in the rea between left field is is also a safety is	ere when warning at area floods the d foul line and				
Velia Alarc	on	μιαγει δ.						

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2014 - 11/30/2014 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	HS					
125868		Athletic Field	11/21/2014		10		\$0.00
Medium	Work In Progress		11/21/2014 3:36:35 PM				
Ontiveros,	Guadalupe	Requested by Ms. L. Chavez for So located near batting cages area (so warning track area. Need to be read replaced.	ftball field) flood the				
Velia Alarc	on						
121888			8/28/2014		95		\$0.00
Medium	Work In Progress		8/28/2014 9:19:01 AM				
Lara, Ralph	h	Need some assistance on door loc room, lock is stuck, teacher needs room frequently.					
Arturo Nun							
121586	Concession		8/21/2014		102		\$0.00
Medium	Work In Progress		8/21/2014 1:47:38 PM				
Holguin, Is		Requested by Cathy for Football Co Stand-There are cob webs, live and needs to be sprayed.					
Velia Alarc		Destroom	11/17/2014		14		¢0.00
125607	Academic Bldg	Restroom			14		\$0.00
High Holguin, Is	Work In Progress aac	Bathroom missing a paper towel di ASAP.	11/17/2014 8:10:54 AM spenser replace				
Jesus Estr	rada						
125608	Academic Bldg	Restroom	11/17/2014		14		\$0.00
High	Work In Progress		11/17/2014 8:12:48 AM				
Holguin, Is	aac	Both bathrooms need ceilings clea	ned off.				
Jesus Estr		C C					
125609	Cafeteria (1998)	Exterior	11/17/2014		14		\$0.00
High	Work In Progress		11/17/2014 8:15:35 AM				
Holguin, Is	-	All windows and doors need to be c spider webs in all entrances.					
Jesus Estr	rada						
125765			11/19/2014		12		\$0.00
Medium	Work In Progress		11/19/2014 3:30:49 PM				
Ontiveros,	Guadalupe	Please paint BB dugouts.					
Michael Mu	-	-					

Selected Da WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS				
123567		10/5/2014	10/13/2014	57		\$0.00
Medium	Work In Progress	10/5/2014 12:42:27 AM				
Hernande	ez, Guillemo	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.				
Margret V	illalobos					
119630		7/21/2014		133		\$0.00
Medium	Work In Progress	7/21/2014 10:01:42 AM				
Flores, Pe	ete	Requested by Mr. Smythe-Ag. tractor needs to be serviced. Engine oil and filter need to be replaced. Both batteries need to be replaced. Hydraulic/trans fluid and filters need to be changed/replaced. Inner and outer air filters need to be replaced. Cab fresh air filters need to be replaced. Injection pump needs to be repaired; fuel system will not hold a prime. Air filter bowl needs to be replaced as well, broken at base. All grease fittings need to be examined in order to take grease.				
Velia Alar	con					
123068		Athletic Field 9/23/2014		69		\$0.00
High	Work In Progress	9/23/2014 2:48:05 PM				
Flores, Pe		truck # 25 F-250 will not start. starter needs to be replaced.				
	e Ontiveros	4.4/2/2044		20		\$0.00
125057		11/3/2014		28		Ф 0.00
Medium	Work In Progress	11/3/2014 7:53:57 AM				
Ambriz, Jo	DS e	Joe, the VAB box started making the noise again, please check. Requested byMs. Leal Rm. 513 in New CTE Building- High pitched noises still coming through the a/c vent and it is very loud during 1st period.				
	Hernandez					
125483		11/13/2014		18		\$0.00
Medium	Work In Progress	11/13/2014 7:44:53 AM				
Ambriz, Jo		Need to replace broken water fountain in the north building by the boys restroom.				
	Hernandez	01		40		<u> </u>
125881	Academic Bldg	Classroom 11/21/2014		10		\$0.00
Medium	Work In Progress	11/21/2014 4:03:18 PM				
Ambriz, Jo		Requested by Carmen Pereida Rm. 334 Academic Building-The heater in the classroom is not working. It's very cold.				
Velia Alar						
12/1/2014	4 3:28:27 PM				Page	79 of 195

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loo Area Deferred By Area Number Reason Description		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
124483			10/22/2014		40		\$0.00
Medium	Work In Progress		10/22/2014 3:47:53 PM				
Ambriz, Jos	se	Need to replace pressure switches and high. Academic #311.	for Trane unit, low				
Guillermo	Hernandez						
125714			11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 3:47:59 PM				
Ambriz, Jos	se	Need assistance to repair rusted HV girls gym.	VS for fan coil in the				
Guillermo	Hernandez						
121445			8/19/2014		104		\$0.00
Medium	Work In Progress		8/19/2014 3:12:05 PM				
Ambriz, Jos	se	Unit need in Portable #4 to be upgra To manystudents, the existing unit is 2Ton unit					
Guillermo	Hernandez						
123520			10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:41:50 AM				
Hernandez	z, Guillermo	Yearly - Gadsden HS I4 (Fan Coil)(\ schedule details.	Yearly) - Refer to PM				
Margret Vil	lalobos						
123521			10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:41:50 AM				
Hernandez	z, Guillemo	Yearly - Gadsden HS R9 (H.W.Radi to PMschedule details.	ator)(Yearly) - Refer				
Margret Vil	lalobos						
125521			11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 2:12:10 PM				
Hernandez	z, Guillermo	Please check heater in Portable #10), not working.				
Guillermo	Hernandez						
125515		Gym	11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 1:00:43 PM				
Lara, Ralpł	h	The door in the Varsitygym concess tamper with. It looks like some tried t bent the door. Will Rafa come by an lock.	o break into it and				
William Die	ckson						

WOID Priority	te Range for Request Building Status		Deferred By		Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned ⁻		Description			Action Taken			
Requester	Name							
Location:	Gadsden	HS						
125389				11/10/2014		21		\$0.00
Medium	Work In Progress			11/10/2014 3:31:34 PM				
Lara, Ralpl	h	Need to install co Main building.	ores to doors in th	e new building Old				
Guillermo	Hernandez							
125484				11/13/2014		18		\$0.00
Medium	Work In Progress			11/13/2014 7:45:55 AN	1			
Lara, Ralpl	h	Need to make ex	tra MO keys for t	he contractor.				
Guillermo	Hernandez							
125657	Computer	Computer Lab		11/17/2014		14		\$0.00
Medium	Work In Progress			11/17/2014 4:36:10 PM				
Lara, Ralpl	h	core in door at co hard to open	omputer lap need	ds to be replaced, very				
Isaac Holg	guin							
122312	New Admin Bldg	Computer Lab		9/4/2014		88		\$0.00
Medium	Work In Progress	718		9/4/2014 10:14:43 AN	1			
Lara, Ralpl	h	Building-Three k is currentlybeing	eys are needed fo used for student larship opportun	m. 718 New Admin. or room # 718. The lab is to access different ities and the lab has ured.				
Velia Alarc	on							
124837		Classroom		10/31/2014		31		\$0.00
Medium	Work In Progress	Portable #4		10/31/2014 12:27:22				
Lara, Ralpl	h		ortable re-keyed v	rtable # 4-Have all file vith three keys made				
Velia Alarc	con							
125669				11/18/2014		13		\$0.00
Medium	Work In Progress			11/18/2014 8:46:59 AN	1			
Castillo, C	arlos	Assist with replac	cementofdamag	jed lightpoles at GHS				
Carlos Ca	stillo							

WOID Priority	Building Status		/30/2014 Order By Loc Deferred By Reason		Target Comp Date Actual Comp Date	Days Aged	Labor Hours	
Assigned 1		Description			Action Taken			
Requester	Name	•						
Location:	Gadsden	HS						
125854				11/21/2014		10		\$0.00
Medium	Work In Progress			11/21/2014 2:53:44 PM	1			
Sotelo, Eni	rique	(575)635-8919	CALIPER CONSTR FERNIE REYES	UCTION Contact Phone:				
		Cell Phone:	ct: BLANCA CRUZ (575)635-8919 caliperconstcom	Pager No:				
		THE INTERSEC STARTING @ T ON THE WEST HIGH SCHOOL	k: FRM LAS CRUCE CTION W/ WASHING HE INTERSECTION SIDE OF NM 28 TO TRN WEST 1000FT EAST BACK TO THE	TON :: SPOT NORTH 1000FT THE GADSDEN TRN SOUTH				
		Remarks: ARE	AS BOUNDED WITH	Ν				
Dominique	e Esparza							
120592	AcademicBldg	Classroom		8/5/2014		118		\$0.00
Medium	Work In Progress	306		8/5/2014 3:54:18 PM	Л			
Nunez, Arti	uro	Requested by M Paint wall with w	lr.NunezRm.306Aca rritting.	ademic Building-				
Velia Alarc	on							
124871				11/2/2014	11/5/2014	29		\$0.00
Medium	Work In Progress			11/2/2014 12:35:01 AN	Л			
Nunez, Artı	uro	Monthly - Gadso Refer to PMsch	den HS - Emerg. Eye edule details.	wash (Monthly) -				
Margret Vil	lalobos							
123467				10/5/2014	10/8/2014	57		\$0.00
Medium	Work In Progress			10/5/2014 12:41:05 AN	Л			
Nunez, Arti	uro	Monthly - Gadso Refer to PMsch	den HS - Emerg. Eye edule details.	wash (Monthly) -				
Margret Vil	lalobos							
125886				11/30/2014	12/3/2014	1		\$0.00
Medium	Work In Progress			11/30/2014 12:46:18	3			
Nunez, Arti	uro	Monthly - Gadso Refer to PMsch	den HS - Emerg. Eye edule details.	wash (Monthly) -				
Margret Vil	lalobos							

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loca Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	HS					
125853			11/21/2014		10		\$0.00
Medium	Work In Progress		11/21/2014 2:52:20 PM				
Villalobos	, David	Company: CALIPER CONSTRU Contact Name: FERNIE REYES (575)635-8919 Alternate Contact: BLANCA CRUZ Cell Phone: (575)635-8919 Email: blanca@caliperconstcom	ICTION Contact Phone: Pager No:				
		Location of Work: FRM LAS CRUCES THE INTERSECTION W/ WASHINGT STARTING @ THE INTERSECTION N ON THE WEST SIDE OF NM 28 TO T HIGH SCHOOL TRN WEST 1000FT 1000FT THEN EAST BACK TO THE II ALL	ON :: SPOT NORTH 1000FT HE GADSDEN TRN SOUTH				
	_	Remarks: AREAS BOUNDED WITHIN	٨				
	e Esparza		44/40/0044		- 40		.
125480			11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 7:40:30 AN	I			
Villalobos	, David	Need assistance to repair water leak l fountain in the Old English first floor.	by the water				
Guillermo	Hernandez	Ū.					
125481			11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 7:42:20 AN	I			
Villalobos	, David	Need assistance to unclog sink in the drain snake.	weight room, need				
	Hernandez		44/40/0044		40		.
125482			11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 7:43:50 AN				
Villalobos	, David	Need assistance to unclog sink in the the east wing (testing room) of the cafe snake.					
Guillermo	Hernandez						
119303	Auto Shop		7/11/2014		143		\$0.00
Medium	Work In Progress		7/11/2014 12:42:51 PM				
Sotelo, En	rique	NEED FOR ELECTRICAL POWER TO FOR NEW LIFT.	OBE INSTALLED				
Gerardo N	larquez						

WOID Priority Assigned		Area Area Number Description	Deferred By	Until	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS							
122944					9/18/2014		74		\$0.00
Medium	Work In Progress			9/18/2	014 7:38:30 AN	1			
Sotelo, En	rique	school, area by	e burn out lamps of the swimming poo l one by grounds.	ol. This area ha	is now				
	Hernandez								
124206		Gym			10/15/2014		47		\$0.00
Medium	Work In Progress			10/15/2	014 3:48:24 PM	1			
Sotelo, En			t bulbs replace in t dent. The place is (efore				
William Di	ckson				11/0/0014				<u> </u>
124874					11/2/2014		29		\$0.00
Medium	Work In Progress				14 12:35:03 AN	1			
Orozco, Da		Yearly - Gadsde schedule detaik	en HS - Grease Tr s.	ap - Refer to F	M				
Margret Vil	llalobos				10/22/2014		40		\$0.00
124485	Mark In Drograda			10/00/0			40		φ0.00
Medium	Work In Progress				:0143:49:00 PM	I			
Villalobos,		Need to replace Lilly Chavez.	e vandalize sink fau	icet in Science	#600,				
	Hernandez				44/40/0044		40		¢0.00
125533					11/13/2014		18		\$0.00
Medium	Work In Progress				:014 3:42:37 PM	1			
Orozco, Da	aniel		es notgethoteno ng enough to clea						
Maritza Go	onzalez								
125993					11/30/2014		1		\$0.00
Medium	Work In Progress			11/3	0/201412:47:29)			
Sanchez, F	Raul	Monthly - Gads to PMschedule	den HS - Lift Statio details.	on Inspection	Refer				
Margret Vil	llalobos								
124975					11/2/2014		29		\$0.00
Medium	Work In Progress			11/2/20	14 12:36:02 AN	1			
Sanchez, F	Raul	Monthly - Gads to PMschedule	den HS - Monthly details.	Nater Sample:	s - Refer				
Margret Vil	llalobos								

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Target Area Number Reason Created Date/Time Actual Description Actual		Costs Labor Hours
Location:	Gadsden	HS		
125990		11/30/2014	1	\$0.00
Medium	Work In Progress	11/30/2014 12:47:28		
Sanchez, I	Raul	Monthly - Gadsden HS - Monthly Meter Readings - Refer to PM schedule details.		
Margret Vi	llalobos			
122810		9/16/2014	76	\$0.00
High	Work In Progress	9/16/2014 8:04:14 AM		
Sanchez, I	Raul	Need to asses storm drain pump by the cafeteria and CTE building, pump is constantly clogging.		
	Hernandez			
123387		9/30/2014	62	\$0.00
Medium	Work In Progress	9/30/2014 12:51:30 AM		
Sanchez, I		Monthly - Gadsden HS - Monthly Meter Readings - Refer to PMschedule details.		
Margret Vi	llalobos	4444/2014		.
125547		11/14/2014	17	\$0.00
Medium	Work In Progress	11/14/2014 12:44:48		
Sanchez, I		Monthly - Gadsden HS- Filters (Pump Rm) Quarterly - Refer to PMschedule details.		
Margret Vi	llalobos	44/00/0044		.
125988		11/30/2014	1	\$0.00
Medium	Work In Progress	11/30/2014 12:47:26		
Sanchez, I	Raul	Monthly - Gadsden HS - Monthly Water Samples - Refer to PMschedule details.		
Margret Vi	llalobos			
121162		8/14/2014	109	\$0.00
Medium	Work In Progress	8/14/2014 12:35:13 AM		
Sanchez, I	Raul	Monthly - Gadsden HS- Filters (Pump Rm) Quarterly - Refer to PMschedule details.		
Margret Vi	llalobos			
124821		10/31/2014	31	\$0.00
Medium	Work In Progress	10/31/2014 12:37:14		
Sanchez, I	Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.		
Margret Vi	llalobos			

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	U	Days Labor Aged Hours	Costs
Location:	Gadsden	HS			
125272		11/7/2014		24	\$0.00
Medium	Work In Progress	11/7/2014 9:03:59 AM	I		
Sanchez,	Raul	Domestic Water Well #1 - install sanitary seal properly around electrical wires.			
Alfredo Ho	olguin				
124973		11/2/2014		29	\$0.00
Medium	Work In Progress	11/2/2014 12:36:00 AM	I		
Sanchez,		Monthly - Gadsden HS - Lift Station Inspection - Refer to PMschedule details.			
Margret Vi	illalobos	0/00/0044			* 0.00
123327		9/26/2014	_	66	\$0.00
Medium	Work In Progress	9/26/2014 3:51:00 PM	1		
Orozco, Da	aniel	Walk-in floor has lifted – safety issue. SNP MANAGER FRANCES B. 882.5522			
Maritza Go	onzalez				^
123328		9/26/2014		66	\$0.00
Medium	Work In Progress	9/26/2014 3:51:26 PM	1		
Orozco, Da	aniel	Mop sink is leaking from the floor.SNP MANAGER FRANCES B. 882.5522			
Maritza Go	onzalez				
123329		9/26/2014		66	\$0.00
Medium	Work In Progress	9/26/2014 3:51:53 PM	1		
Orozco, Da	aniel	Reach-in refrigerator on the Red and Green serving area is not cooling.SNP MANAGER FRANCES B. 882.5522			
Maritza Go	onzalez				
121946		8/29/2014		94	\$0.00
Medium	Work In Progress	8/29/2014 7:38:31 AN	I		
Gonzalez,	Salvador	Need to cut hole on the cage inside the storage room in the V. Gym to gain access to the inspector valve for the fire sprinkler system. (See Memo for questions).			
Guillermo	Hernandez				
122189		9/2/2014		90	\$0.00
Medium	Work In Progress	9/2/2014 3:47:46 PM	1		
Gonzalez,	Salvador	Need to install gate stop and chain to the new gate by grounds.			
Guillermo	Hernandez				

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description	Until Request Date Target Cor Created Date/Time Actual Cor	· · · · · · · · · · · ·	
Location:	Gadsden	HS			
119747			7/23/2014	131	\$0.00
Medium	Work In Progress		7/23/2014 10:08:37 AM		
Orozco, Da	aniel	WARMER-OLD FAVORITES-INSI SNP MANAGER FRANCES B. 88			
Maritza Go	onzalez				
125271			11/7/2014	24	\$0.00
Medium	Work In Progress		11/7/2014 9:01:04 AM		
Gonzalez,	Salvador	Domestic Water Well #2 - install b head.	ollards to protect well		
Alfredo Ho	olguin				
125292		Football Field	11/7/2014	24	\$0.00
Medium	Work In Progress		11/7/2014 1:12:07 PM		
Gonzalez,	Salvador	Coach Vasquez would like a door area to store some of his equipme welded.			
William D	ickson				
124632		Athletic Field	10/27/2014	35	\$0.00
Medium	Work In Progress		10/27/2014 2:47:26 PM		
Gonzalez,	Salvador	need to install new cables for new cages.boys baseball.contact per Bones.thank you			
Michael M	lunoz				
125861		Athletic Field	11/21/2014	10	\$0.00
Medium	Work In Progress		11/21/2014 3:17:50 PM		
Gonzalez,	Salvador	Requested by Ms. L. Chavez for S old batting cage. Add a third batti Field. Add an area for batting off t area from fence (left side) welded	ng cage on Softball ees. Remove old tee		
Velia Alar	con				
125862		Athletic Field	11/21/2014	10	\$0.00
Medium	Work In Progress		11/21/2014 3:21:11 PM		
Gonzalez,	Salvador	Requested by Ms. L. Chavez for S on Softball Field needs to be repla There are white stakes keeping fe stated that those stakes were a sa players.	aced (safetyissue). ence down. Officials		
Velia Alaro	con	- •			

Selected Da WOID Priority Assigned Requester	Building Status To	-	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
126007			11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress	11/30/2	2014 12:47:39				
Hernande	z, Guillermo	Monthly - Gadsden HS Monthly FE Inspection - Re PMschedule details.	fer to				
Margret Vi	llalobos						
124985			11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress	11/2/2014	12:36:08 AM				
Hernande	z, Guille m o	Monthly - Gadsden HS Monthly FE Inspection - Re PMschedule details.	fer to				
Margret Vi	llalobos						
125493			11/13/2014		18		\$0.00
Medium	Work In Progress	11/13/201	4 8:27:30 AM				
Carrasco,	Danny	Need to borrow manual scuffling to service fan coil in girls gym.	unit				
Arturo Nur	nez		/				
124622			10/27/2014		35		\$0.00
Medium	Work In Progress	10/27/2	2014 12:01:27				
Carrasco,	Danny	Danny, requesting 1- Manifold gauges set R-22/R-4 Grainger #3KU64 and I set of pulley puller 8 inch, 4 Grainger #4YT16. Thank you					
Guillermo	Hernandez						
121243		Football Field	8/15/2014		108		\$0.00
Medium	Work In Progress	8/15/201	4 9:53:18 AM				
Ontiveros,	, Guadalupe	Need to place lines on the middle grass field so the football team can practice.					
William Di	ickson						
119592		Athletic Field	7/18/2014		136		\$0.00
Medium	Work In Progress	7/18/201	4 2:08:10 PM				
Ontiveros,	, Guadalupe	Would like to get the grass fields line for competition First field should be lined as a soccer field and the c lined up as football fields. Thank you!					
William Di	ickson						
125522			11/13/2014		18		\$0.00
Medium	Work In Progress	11/13/201	4 2:13:44 PM				
Ronquillo	, Ruben	Need to borrow 2 portable heaters for Portables heat not working.	ater				
Guillermo	Hernandez						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loca Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
122352			9/4/2014		88		\$0.00
Medium	Work In Progress		9/4/2014 3:46:33 PM	1			
Ontiveros,	, Guadalupe	Need to replace about 200 ft. of 3 ft. I foot ball field visitors side, fence is fac field. Safety issue.					
	Hernandez						
124297			10/17/2014		45		\$0.00
Medium	Work In Progress		10/17/2014 12:18:07				
Carbajal,	Jimmy	Need to replace 1/4 of floor for the N main entrance , tiles are lose and war					
	Hernandez						
121330	Library	Library	8/18/2014		105		\$0.00
Medium	Work In Progress	Library	8/18/2014 9:20:11 AM	l			
Estrada, J	lesus	Requested by Matt Grubaugh for Libra coming up all over the library floor.	ary-Carpetis				
Velia Alaro	con						
123810	Library	Library	10/7/2014		55		\$0.00
Medium	Work In Progress		10/7/2014 12:59:31 PN				
Estrada, J	lesus	Requested by Matt Grubaugh for Lib the library continues to come up. He's are going to trip on it and hurt themse	afraid students				
Velia Alaro	con						
119657			7/21/2014		133		\$0.00
Medium	Work In Progress		7/21/2014 3:31:25 PM	1			
Gallegos,	Rafael	Warranty work order. Mullen on the w door to the Theater building is not work keygets stock and can not remove the	king properly. The				
Guillermo	Hernandez						
121304			8/18/2014		105		\$0.00
Medium	Work In Progress		8/18/2014 7:54:25 AN	I			
Gallegos,	Rafael	TRANE WARRANTY W/O. Science c CO sensor is not reading.	lassroom #619				
Guillermo	Hernandez						
121342			8/18/2014		105		\$0.00
Medium	Work In Progress		8/18/2014 12:19:58 PM				
Gallegos,	Rafael	Warranty work order for roof leak in the shop. water seems to be coming from the welded part looks like is crack as roof leak.	n the A/C roof jack,				
	Hernandez						

12/1/2014 3:28:27 PM

Priority Assigned 1 Requester		Area Number Description	Reason	Created Date	/Time A	ctual Comp Date Action Taken	Aged	Hours	
Location:	Gadsden	HS							
120351				8/3	3/2014		120		\$0.00
Medium	Work In Progress			8/3/2014 12:33	:49 AM				
Munoz, Mic	chael	Yearly - Gadsdo PMschedule do		o. (Yearly) - Refer to					
Margret Vil	lalobos								
125014				11/2	2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress			11/2/2014 12:36	:25 AM				
Orozco, Da	aniel	Monthly-Gadso PMschedulede		d Cleaning - Refer to					
Margret Vil									
121848	AcademicBldg			8/2	7/2014		96		\$0.00
Medium	Work In Progress			8/27/2014 2:30	:48 PM				
Nunez, Arti	uro	Please replace	all window screens						
Michael Mu	unoz								
123642				10/	5/2014		57		\$0.00
Medium	Work In Progress			10/5/2014 12:43	:26 AM				
Holguin, Al	lfredo	Monthly - Gads PMschedule de		p Engine - Refer to					
Margret Vil									
124587	North Building	Storage		10/24	4/2014		4	0.25	\$6.25
Medium	Work In Progress	207S		10/24/2014 3:03	:37 PM	10/28/2014			
Villalobos,	-		/Irs. Munoz Rm. 207 needed for store roc		E	mailed 10/28/14			
Velia Alarc					0.004.4		- 10		
125516	Old English Bldg				3/2014		18		\$0.00
Safety	Work In Progress			11/13/2014 1:56	:57 PM				
Villalobos,	Margret		g - Mice infestation please service a/s		E	-mailed Bennie			
Alfredo Ho	Iguin								
123637					5/2014		57		\$0.00
Medium	Work In Progress			10/5/2014 12:43	:23 AM				
	lfredo			PM (Quarterly) - Refer					

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Locati Area Deferred By U Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
124921			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:31 AN	l			
Nunez, Art	uro	Monthly - Gadsden HS Emer. Light Tes Refer to PMschedule details.	st: Monthly -				
Margret Vi	llalobos						
124922			11/2/2014	12/3/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:31 AN	l			
Nunez, Art	uro	Monthly - Gadsden HS Bleacher Inspe PMschedule details.	ction - Refer to				
Margret Vi	llalobos						
124936			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:39 AN	l			
Nunez, Art		Monthly - Gadsden HS-Clothes Dryer (to PMschedule details.	Monthly) - Refer				
Margret Vi	llalobos		40/04/0044				.
124586			10/24/2014		38		\$0.00
Medium	Work In Progress		10/24/2014 3:01:16 PM				
Nunez, Art		Requested by Mrs. Munoz Rm. 210 Nor Ceiling tile is stained, possible leak.	th Building-				
Velia Alaro	con		40/5/2044	44/5/2044	F7		<u> </u>
123622			10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:43:11 AN				
Nunez, Art		Monthly - Gadsden HS Bleacher Inspe PMschedule details.	ction - Refer to				
Margret Vi	llalobos		40/5/0044	4.0/4.0/0.04.4	F7		<u> </u>
123623			10/5/2014	10/13/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:43:11 AN				
Nunez, Art	uro	Monthly - Gadsden HS Emer. Light Tes Refer to PMschedule details.	st: Monthly -				
Margret Vi	llalobos						
123624			10/5/2014		57		\$0.00
Medium	Work In Progress		10/5/2014 12:43:12 AN	I			
Nunez, Art	uro	Monthly - Gadsden HS-Clothes Dryer (to PMschedule details.	Monthly) - Refer				
Margret Vi	llalobos						

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loca Area Deferred By Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
124498	Academic Bldg	Classroom	10/23/2014		39		\$0.00
Medium	Work In Progress		10/23/2014 8:56:50 AM				
Nunez, Art	uro	Requested by Mrs. Valtierra Rm. 320 / -Three ceiling lights in front of the clas working and need to be replaced.					
Velia Alarc	on						
125920			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:41				
Nunez, Art	uro	Monthly - Gadsden HS Emer. Light To Refer to PMschedule details.	est: Monthly-				
Margret Vil	lalobos		11/22/2211				
125916			11/30/2014	12/31/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:39				
Nunez, Arti	uro	Monthly - Gadsden HS Bleacher Insp PMschedule details.	ection - Refer to				
Margret Vil	lalobos						
125917			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:39				
Nunez, Arti	uro	Monthly - Gadsden HS-Clothes Dryer to PMschedule details.	(Monthly) - Refer				
Margret Vil	lalobos		11/10/0011		- 10		
125489			11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 8:05:47 AM				
Nunez, Art	uro	Danny Need a tool tote 11x9x18 in, Grainger # 3XUV2.	23 pocket				
Arturo Nun	ez		4.0/0/0044				.
123863			10/8/2014		54		\$0.00
Medium	Work In Progress		10/8/2014 10:14:09 AM				
Hernande	z, Guillermo	please check all emergencylightings operation and order batteries if need b					
Alfredo Ho	-				45		A =
125724	Varsity Gym		11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 4:29:36 PM				
Hernande	z, Guillermo	Please check to see if covers are put o gym.	on a/c units in				
Michael Mu	unoz						

WOID Priority Assigned 1 Requester		Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS						
125734	Varsity Gym			11/19/2014		12		\$0.00
Medium	Work In Progress			11/19/2014 8:32:33 AM	1			
Hernandez	z, Guillermo	Pour cherry odd	or down drains in re	estrooms.				
Michael Mu	inoz							
125870	Academic Bldg			11/21/2014		10		\$0.00
Medium	Work In Progress			11/21/2014 3:43:16 PN	1			
	z, Guillermo	-Water faucet a	erator was plugge we use the faucet i	42 Academic Building d up and the faucet is t leaks on the counter				
Velia Alarc 125873	on			11/21/2014		10		\$0.00
Medium				11/21/2014 3:49:19 PN		10		ψ0.00
	Work In Progress				I			
	z, Guillermo	Need to check r boys gym.	unning toilet in the	boys restroom at				
	Hernandez			11/20/2014	12/0/2014	1		¢0.00
125944				11/30/2014		1		\$0.00
Medium	Work In Progress			11/30/2014 12:46:57				
Hernandez	z, Guillermo	Monthly - Gads PMschedule de		nsp: Monthly - Refer to				
Margret Vil	lalobos							
124838		Classroom		10/31/2014		31		\$0.00
Medium	Work In Progress			10/31/2014 12:52:21				
Hernandez	z, Guille <i>r</i> mo	High pitched no		n New CTE Building- hrough the a/c vent and				
Velia Alarc	on			44/40/0044				.
125352		Classroom		11/10/2014		21		\$0.00
Medium	Work In Progress			11/10/2014 10:16:39)			
Hernandez	z, Guillermo			3 Annex Building-Had Ild have taken care of it				
Velia Alarc	on							
125073	Academic Bldg	Classroom		11/3/2014		28		\$0.00
Medium	Work In Progress	339		11/3/2014 11:12:58 AM	1			
Hernandez	z, Guillermo			Academic Building- d out in my class room.				
Velia Alarc	on							

WOID Priority Assigned	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS				
124963		11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:55 AM				
Hernande	z, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PMschedule details.				
Margret Vil	lalobos					
125236	New Admin Bldg	11/6/2014		25		\$0.00
Medium	Work In Progress	11/6/2014 2:32:11 PM				
Hernande	z, Guillermo	Requested byCathyCano-Put together two media carts for projectors. SEE CATHY FOR LOCATION OF CARTS.				
Velia Alarc	on					
125485		11/13/2014		18		\$0.00
Medium	Work In Progress	11/13/2014 7:50:23 AM				
Carrasco,	Danny	Danny requesting the following tools. Dewalt 4 tool combo set 18v kit. # DCK425C,Cresent wrench set 6" to 10".Klein nut drivers set 6" handles. Channel lock plier set, screw driver set. heavy duty heat gun. klein 11 in 1 tool. 1/4 ,and 5/16 nut drive bits (2 ea.)				
Arturo Nun	iez					
119662		7/21/2014		133		\$0.00
Medium	Work In Progress	7/21/2014 3:37:51 PM				
Ronquillo,	Ruben	Ruben, need to order two light poles to be replaced. Questions ask Enrique S. as per Alfredo.				
Guillermo	Hernandez					
125604		11/15/2014		16		\$0.00
Medium	Work In Progress	11/15/2014 12:45:33				
Flores, Pe	te	Yearly-Gadsden HS-Mow (0408/0419/0428) Grounds - Refer to PMschedule details.				
Margret Vil	lalobos					
125490		Custodial 11/13/2014		18		\$0.00
Medium	Work In Progress	11/13/2014 8:16:49 AM				
Flores, Pe	te	gator at ghs needs lights light switch went out or lights need to be replaced				
Isaac Holg	guin					
123727		Custodial 10/6/2014		56		\$0.00
Medium	Work In Progress	10/6/2014 2:35:11 PM				
Flores, Pe	te	gator at ghs headlight dont work				
Isaac Holg	guin					
Count: 118	Work Orders	Avg. Age of WO's 43	Total for Gadsde	n HS	0.25	\$6.25

Selected Da WOID Priority Assigned Requester		Dates:7/1/2014 - 1 Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
124955				11/2/2014	12/3/2014	29		\$0.00
Medium	Work In Progress			11/2/2014 12:35:50 AN	1			
Diaz, Seba	astian	Monthly - Gads PMschedule de		r Inspection - Refer to				
Margret Vi	llalobos							
125847				11/21/2014		10		\$0.00
Medium	Work In Progress			11/21/2014 1:52:55 PM	l			
Diaz, Seba	astian	Heater in comp	outer lab by athletics	s office is not working.	1/21/14 -notified Sel	oastian		
Sylvia Mor								
125784	Gym			11/19/2014		12		\$0.00
Medium	Work In Progress			11/19/2014 4:24:32 PM	l			
Diaz, Seba	astian	Order window : (See Mike)	screens for Gym a	nd Gym Lobby.				
Michael M	unoz							
125973				11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress			11/30/2014 12:47:17	, ,			
Diaz, Seba		Monthly - Gads to PMschedule		nsp: Monthly - Refer				
Margret Vi 125974	llalobos			11/30/2014	12/8/2014	1		\$0.00
						I		φ0.00
Medium	Work In Progress			11/30/2014 12:47:17				
Diaz, Seba		Monthly - Gads Refer to PMsch	den MS Emer. Lig nedule details.	ht Test: Monthly -				
Margret Vi 125975	llalobos			11/30/2014		1		\$0.00
Medium	Work In Progress			11/30/2014 12:47:18				ψ0.00
Diaz, Seba	-	Monthly - Gads to PMschedule		Dryer (Monthly) - Refer				
Margret Vi	llalobos	lo FINISCHEQUIE	details.					
125968				11/30/2014	12/31/2014	1		\$0.00
Medium	Work In Progress			11/30/2014 12:47:13	5			
Diaz, Seba	astian	Monthly - Gads PMschedule de		r Inspection - Refer to				
Margret Vi	llalobos							
125852		Pump House		11/21/2014		10		\$0.00
Medium	Work In Progress			11/21/2014 2:42:53 PM	l			
Apodaca,	Mario	need to run nev	v control wires to th	e gms irrigation tank				
Mario Apo	daca							
12/1/2014	3:28:28 PM						Page	95 of 195

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location Area Deferred By Ur Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS					
125237	Gym		11/6/2014		25		\$0.00
Medium	Work In Progress		11/6/2014 2:41:40 PM	1			
Munoz, Mic	chael	The new bleachers not working on the gy	m thank you				
Sebastian	Diaz						
121844	C-Wing		8/27/2014		96		\$0.00
Medium	Work In Progress		8/27/2014 1:19:05 PM	1			
Marquez, C	Gerardo	please change all windows around build thank you	ling.double pane				
Michael Mu	unoz						
125015			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:26 AN	l			
Orozco, Da		Monthly - Gadsden MS Range Hood Cle PM schedule details.	aning - Refer to				
Margret Vil	lalobos				4.00		* ••••
120347			8/3/2014		120		\$0.00
Medium	Work In Progress		8/3/2014 12:33:46 AN	1			
Munoz, Mic		Yearly - Gadsden MS Fire Ext. Insp. (Yea PMschedule details.	arly) - Refer to				
Margret Vil	lalobos		44/00/0044	40/0/0044	4		<u> </u>
125999			11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:33				
Diaz, Seba		Monthly - Gadsden MS Monthly FE Inspe PM schedule details.	ection - Refer to				
Margret Vil 125856	lalobos	Athletic Field	11/21/2014		10		\$0.00
					10		φ0.00
Medium	Work In Progress		11/21/2014 3:02:54 PM				
Gonzalez,		please install baseball scoreboard on fie mike for details.gracias	eld. please see				
Michael Mu	C-Wing		10/24/2014		20		\$0.00
124571 Madium	0				38		φU.UU
Medium	Work In Progress		10/24/2014 10:14:02				
Gonzalez,		Need to fix ramps on C wing replace for	metal thank you				
Sebastian							#0 00
124501	Gym		10/23/2014		39		\$0.00
Medium	Work In Progress	Boys locker	10/23/2014 10:00:49				
Marquez, G	Gerardo	Outside door cylinder needs repair					
Nancy Tina	ajero						

Location:Gadsden MS124502Gym10/23/201439124502Gym10/23/201439MediumWork In ProgressGym Lobby10/23/201410:02.45Marquez, GerardoFristsetol double doors going from gym lobby to gym, need cylinder repair.45Nancy Tinajero10/17/201445124293Classroom10/17/2014145MediumWork In Progressroom 14810/17/201414Marquez, GerardoClassroom entrydoor needs to be adjusted.11/17/201414Marquez, GerardoClassroom11/17/201414MediumWork In Progressroom 16911/17/201414Marquez, GerardoNeed a half door installed in room 169 for student safety.11/12/201419MediumWork In ProgressConcession stand door needs adjusting. Door needs to be lifted in order to be closed.11/12/201411Marquez, GerardoConcession stand door needs adjusting. Door needs to be lifted in order to be closed.11/12/201410MediumWork In ProgressAwing11/21/201410MediumWork In ProgressAwing11/21/201410MediumWork In ProgressAwing11/42/1427Marquez, GerardoPlease check Mulliun @ back double doors, notworking properly.11/42/01427Nancy Tinajero11/42/01411/42/01427MediumWork In Progress11/42/01427MediumWork In Progress11/42/01427 <th>Costs</th> <th>Labor Hours</th> <th>Days Aged</th> <th>Target Comp Date Actual Comp Date Action Taken</th> <th></th> <th>Deferred By</th> <th>Area Number Description</th> <th></th> <th>WOID Priority Assigned 1 Requester</th>	Costs	Labor Hours	Days Aged	Target Comp Date Actual Comp Date Action Taken		Deferred By	Area Number Description		WOID Priority Assigned 1 Requester
Medium Work In Progress Gyn Lobby 10/23/201410:0245 Marquez, Gerardo First set of double doors going from gym lobby to gym, need cylinder repair. Nancy Tinajero Classroom 10/17/2014 45 Medium Work In Progress room 148 10/17/2014 11:47:27 Marquez, Gerardo Classroom entry door needs to be adjusted. 11/17/2014 14 Nancy Tinajero room 169 11/17/2014 9:24:51 AM 14 Medium Work In Progress room 169 11/17/2014 9:24:51 AM 14 Marquez, Gerardo Need a half door installed in room 169 forstudent safety. 19 11/12/2014 11:15:17 Marquez, Gerardo Concession stand door needs adjusting. Door needs belifted in order to be closed. 11/12/2014 11:15:17 Marquez, Gerardo Concession stand door needs adjusting. Door needs belifted in order to be closed. 11/21/2014 11:15:17 Marquez, Gerardo Awing 11/21/2014 11:15:17 10 Medium Work In Progress Awing 11/21/2014 11:15:17 Marquez, Gerardo Please check Mulliun @ back double doors, not working progreyr. 10 Medium Work In Progress Awing 11/21/2014 11:15:17							MS	Gadsden	Location:
Marquez, GerardoFirst set of double doors going from gym lobby to gym, need cylinder repair.Nancy TinajeroClassroom10/17/201445MediumWork In Progressroom 14810/17/2014 11:4727Marquez, GerardoClassroom entry door needs to be adjusted.11/17/2014Nancy Tinajeroroom 16911/17/2014 9:24:51 AMMarquez, GerardoNeed a half door installed in room 169 for student safety.11/12/2014Nancy Tinajeroroom 16911/17/2014 9:24:51 AMMarquez, GerardoNeed a half door installed in room 169 for student safety.11/12/2014Nancy Tinajeroconcession11/12/2014 11:15:17Marquez, GerardoConcession stand door needs adjusting. Door needs be lifted in order to be closed.11/2/2014 11:15:17Marquez, GerardoPlease check Mulliun @ back double doors, not working property.11/2/2014 11:19:17Marquez, GerardoPlease check Mulliun @ back double doors, not working property.27Nancy Tinajero11/4/2014 9:2:2:00 AM27Muroz, Michaelorder and install scoreboard for baseball liekd27MediumWork In Progress11/4/2014 9:2:2:00 AM77MediumWork In Progress9/15/2014 4:13:11 PM77MediumWork In Progress9/15/2014 4:13:11 PM71Marquez, GerardoSymbol Scoreboard for baseball liekd77Marquez, GerardoSymbol Scoreboard for baseball liekd77Marquez, GerardoSymbol Scoreboard for baseball liekd77Marquez, GerardoSymbol Scoreboard fo	\$0.00		39		10/23/2014			Gym	124502
Nancy Tinajero124293Classroom10/17/201445124293Classroom entry door needs to be adjusted.Nancy TinajeroClassroom entry door needs to be adjusted.125614Main BuildingClassroom entry door needs to be adjusted.Nancy Tinajero11/17/201414125614Main BuildingClassroom entry door needs to be adjusted.Nancy Tinajero11/17/201414MediumWork In Progressroom 16911/17/2014Marquez, GerardoNeed a half door installed in room 169 for student safety.11/12/2014Nancy Tinajero11/12/201419MediumWork In ProgressConcession stand door needs adjusting. Door needs to be lifted in order to be closed.Nancy Tinajero11/12/201411/21/2014125434Main Building11/21/2014MediumWork In ProgressConcession stand door needs adjusting. Door needs to be lifted in order to be closed.Nancy Tinajero11/12/201410125434Main Building11/12/12014MediumWork In ProgressA wing11/12/1201411/21/201427125133Alhetic Field11/4/2014Nancy Tinajero11/4/201427125133Alhetic Field11/4/2014122804Gvin Progress9/15/2014Munoz, Michaelorder and install scoreboard for baseball fieldMunoz, MichaelSouth bleachers do notgo in or outautomatically.Sebastian DiazSouth bleachers do notgo in or outautomatically. <td></td> <td></td> <td></td> <td></td> <td>10/23/2014 10:02:45</td> <td></td> <td>Gym Lobby</td> <td>Work In Progress</td> <td>Medium</td>					10/23/2014 10:02:45		Gym Lobby	Work In Progress	Medium
124293Classroom10/17/201445MediumWork In Progressroom 14810/17/2014 11:4727Marquez, GerardoClassroom entrydoor needs to be adjusted.Nancy Tinajero11/17/2014 11:4727125614Main BuildingClassroom125614Main BuildingClassroom on 169Marquez, Gerardoneed a half door installed in room 169 for student safety.Nancy Tinajero11/17/2014 9:24:51 AMMarquez, GerardoNeed a half door installed in room 169 for student safety.Nancy Tinajero11/12/201412543411/12/2014MediumWork In ProgressConcession stand door needs adjusting. Door needs to be lifted in order to be closed.Nancy Tinajero11/21/201412544Main BuildingNancy Tinajero11/21/201412544Main BuildingMarquez, GerardoConcession stand door needs adjusting. Door needs to be lifted in order to be closed.Nancy Tinajero11/21/201412544Main BuildingMarquez, GerardoPlease check Mulliun @ back double doors, not working property.Nancy Tinajero11/4/201412513Athetic Field11/4/2014 9:22:00 AMMunoz, Michaelorder and install scoreboard for baseball fieldAlfredo Holguin11/2/2014 4:13:11 PMMunoz, Michaelsouth bleachers do not go in or out automatically.Sebastian Diazsouth bleachers do not go in or out automatically.					gym lobby to gym,			Gerardo	Marquez, G
Median Work In Progress room 148 10/17/2014 11:47:27 Marquez, Gerardo Classroom entry door needs to be adjusted. Nancy Tinajero 11/17/2014 14 125614 Main Building Classroom 11/17/2014 9:24:51 AM Marquez, Gerardo Need a half door installed in room 169 for student safety. Nancy Tinajero Nancy Tinajero 11/12/2014 19 Medium Work In Progress Concession 11/12/2014 119 Medium Work In Progress Concession stand door needs adjusting. Door needs to be lifted in order to be closed. Nancy Tin2/2014 10 Medium Work In Progress Awing 11/21/2014 10 Medium Work In Progress Awing 11/21/2014 10 Medium Work In Progress Awing 11/21/2014 11 Marquez, Gerardo Please check Mulliun @ back double doors, not working properly. 10 Marquez, Gerardo Vork In Progress Athletic Field 11/4/2014 27 Medium Work In Progress Athletic Field 11/4/2014 27 Medium Work In Progress order and instal								ajero	Nancy Tina
Marquez, Gerardo Class room entry door needs to be adjusted. Nancy Tinajero 11/17/2014 14 125614 Main Building Classroom n169 11/17/2014 9:24:51 AM Marquez, Gerardo Need a half door installed in room 169 for student safety. 1 Nancy Tinajero 11/12/2014 9:24:51 AM 19 Ved a half door installed in room 169 for student safety. 1 19 Nancy Tinajero 11/12/2014 11:15:17 19 Medium Work In Progress Concession stand door needs adjusting. Door needs to be lefted in order to be closed. 11/21/2014 11:15:17 Marquez, Gerardo Concession stand door needs adjusting. Door needs to be lefted in order to be closed. 10 Nancy Tinajero Verk In Progress A wing 11/21/2014 11:19:17 Varquez, Gerardo Please check Mulliun @ back double doors, not working properly. 10 Nancy Tinajero Verk In Progress A wing 11/4/2014 9:22:00 AM Nunoz, Michael order and install scoreboard for baseball field 27 Medium Work In Progress order and install scoreboard for baseball field 77 Medium Work In Progress 9/15/2014 4:13:11 PM 77	\$0.00		45		10/17/2014		Classroom		124293
Nancy Tinajero125614Main BuildingClassroom11/17/201414MediumWork In Progressroom 16911/17/2014 9:24:51 AMMarquez, GerardoNeed a half door installed in room 169 for student safety.11/12/201419MediumWork In ProgressConcession11/12/2014 11:15:17Marquez, GerardoConcession stand door needs adjusting. Door needs b be lifted in order to be closed.11/21/2014 11:15:17Marquez, GerardoConcession stand door needs adjusting. Door needs b be lifted in order to be closed.11/21/2014 11:19:17MediumWork In ProgressA wing11/21/2014 11:19:17MediumWork In ProgressA wing11/21/2014 11:19:17Marquez, GerardoPlease check Mulliun @ back double doors, not working properly.27Marquez, Gerardoorder and install scoreboard for baseball field27MediumWork In Progress11/4/2014 9:22:00 AM27Munoz, Michaelorder and install scoreboard for baseball field77MediumWork In Progress9/15/2014 4:13:11 PM77Munoz, Michaelsouth bleachers do not go in or out automatically.77					10/17/2014 11:47:27		room 148	Work In Progress	Medium
125614 Main Building Classroom 11/17/2014 14 Medium Work In Progress room 169 11/17/2014 9:24:51 AM Marquez, Gerardo Need a half door installed in room 169 for student safety. 11/12/2014 Nancy Tinajero 11/12/2014 19 Medium Work In Progress Concession 11/12/2014 11:15:17 Marquez, Gerardo Concession stand door needs adjusting. Door needs b belifted in order to be closed. 11/21/2014 11:15:17 Marquez, Gerardo Concession stand door needs adjusting. Door needs b belifted in order to be closed. Nancy Tinajero 11/21/2014 10 Medium Work In Progress A wing 11/21/2014 11:19:17 Marquez, Gerardo Please check Mulliun @ back double doors, not working properly. 11/21/2014 11:19:17 Marquez, Gerardo Please check Mulliun @ back double doors, not working properly. 27 Nancy Tinajero 11/4/2014 9:22:00 AM 27 Medium Work In Progress 11/4/2014 9:22:00 AM 77 Munoz, Michael order and install scoreboard for baseball field 77 Medium Work In Progress 9/15/2014 4:13:11 PM 77					adjusted.	trydoor needs to be	Classroom ent	Serardo	Marquez, G
MediumWork In Progressroom 16911/17/2014 9:24:51 AMMarquez, GerardoNeed a half door installed in room 169 for student safety.11/12/201419Nancy Tinajero11/12/20141919MediumWork In ProgressConcession stand door needs adjusting. Door needs to be lifted in order to be closed.11/12/201411Nancy TinajeroConcession stand door needs adjusting. Door needs to be lifted in order to be closed.11/21/201410MediumWork In ProgressA wing11/21/201410MediumWork In ProgressA wing11/21/201411Marquez, GerardoPlease check Mulliun @ back double doors, not working properly.11/4/201427Marquez, GerardoVerk In ProgressAthletic Field11/4/201427Marquez, Gerardoorder and install scoreboard for baseball field27MediumWork In Progressorder and install scoreboard for baseball field77MediumWork In Progress9/15/201477MediumWork In Progress<								ajero	Nancy Tina
Marquez, Gerardo Need a half door installed in room 169 for student safety. Nancy Tinajero 11/12/2014 125434 11/12/2014 11:15:17 Marquez, Gerardo Concession stand door needs adjusting. Door needs to be lifted in order to be closed. Nancy Tinajero Concession stand door needs adjusting. Door needs to be lifted in order to be closed. Nancy Tinajero 11/21/2014 11:15:17 Marquez, Gerardo Concession stand door needs adjusting. Door needs to be lifted in order to be closed. Nancy Tinajero 11/21/2014 11:19:17 Medium Work In Progress A wing 11/21/2014 11:19:17 10 Marquez, Gerardo Please check Mulliun @ back double doors, not working properly. Nancy Tinajero 11/4/2014 9:22:00 AM Munoz, Michael order and install scoreboard for baseball field Alfredo Holguin 11/4/2014 9:22:00 AM 1122802 Gym 9/15/2014 4:13:11 PM Munoz, Michael south bleachers do not go in or out automatically. Sebastian Diaz South bleachers do not go in or out automatically.	\$0.00		14		11/17/2014		Classroom	Main Building	125614
Nancy Tinajero12543411/12/2014125434ConcessionMarquez, GerardoConcession stand door needs adjusting. Door needs to be lifted in order to be closed.Nancy TinajeroConcession stand door needs adjusting. Door needs to be lifted in order to be closed.Nancy Tinajero11/21/2014125844Main BuildingWork In ProgressA wing11/21/201410MediumWork In ProgressA wing11/21/2014Marquez, GerardoPlease check Mulliun @ back double doors, not working properly.Nancy Tinajero11/4/2014125133Athletic FieldMediumWork In ProgressMunoz, Michaelorder and install scoreboard for baseball fieldAlfredo Holguin0rder and install scoreboard for baseball field22802Gym9/15/2014Munoz, Michaelsouth bleachers do not go in or out automatically.Sebastian Diazsouth bleachers do not go in or out automatically.					11/17/2014 9:24:51 AM		room 169	Work In Progress	Medium
12543411/12/201419MediumWork In ProgressConcession11/12/2014 11:15:17Marquez, GerardoConcession stand door needs adjusting. Door needs to be lifted in order to be closed.Nancy Tinajero11/21/201410MediumWork In ProgressA wing11/21/2014 11:19:17Marquez, GerardoPlease check Mulliun @ back double doors, not working properly.11/4/2014 11:19:17Nancy Tinajero11/21/2014 11:19:1727Marquez, GerardoPlease check Mulliun @ back double doors, not working properly.27MediumWork In Progress11/4/2014 9:22:00 AMMunoz, Michaelorder and install scoreboard for baseball field27MediumWork In Progress9/15/2014 4:13:11 PMMunoz, Michaelsouth bleachers do not go in or out automatically.9/15/2014 4:13:11 PM					69 for student	or installed in room		Gerardo	Marquez, G
MediumWork In ProgressConcession11/12/2014 11:15:17Marquez, GerardoConcession stand door needs adjusting. Door needs to be lifted in order to be closed.Nancy Tinajero11/21/201410MediumWork In ProgressA wing11/21/2014 11:19:17Marquez, GerardoPlease check Mulliun @ back double doors, not working properly.11/21/2014 11:19:17Marquez, GerardoPlease check Mulliun @ back double doors, not working properly.27Nancy Tinajero11/4/2014 9:22:00 AM27MediumWork In ProgressAthletic Field11/4/2014 9:22:00 AMMunoz, Michaelorder and install scoreboard for baseball field77MediumWork In Progress9/15/2014 4:13:11 PMMunoz, Michaelsouth bleachers do not go in or out automatically.77Sebastian DiazSouth bleachers do not go in or out automatically.50								ajero	Nancy Tina
Marquez, GerardoConcession stand door needs adjusting. Door needs to be lifted in order to be closed.Nancy Tinajero11/21/201410MediumWork In ProgressA wing11/21/2014 11:19:17Marquez, GerardoPlease check Mulliun @ back double doors, not working properly.11/4/2014 11:19:17Nancy Tinajero11/21/2014 11:19:1727MediumWork In ProgressAthletic Field11/4/2014125133Athletic Field11/4/2014 9:22:00 AMMunoz, Michaelorder and install scoreboard for baseball field77MediumWork In Progress9/15/2014 4:13:11 PMMunoz, Michaelsouth bleachers do not go in or out automatically.9/15/2014 4:13:11 PM	\$0.00		19		11/12/2014				125434
Nancy Tinajero125844Main Building11/21/201410MediumWork In ProgressA wing11/21/2014 11:19:17Marquez, GerardoPlease check Mulliun @ back double doors, not working properly.11/21/2014 11:19:17Nancy Tinajero11/21/2014 11:19:1710125133Athletic Field11/4/201427MediumWork In ProgressAthletic Field11/4/2014 9:22:00 AMMunoz, Michaelorder and install scoreboard for baseball field11/2014 9:22:00 AMAffredo Holguin					11/12/2014 11:15:17		Concession	Work In Progress	Medium
125844Main Building11/21/201410MediumWork In ProgressA wing11/21/2014 11:19:17Marquez, GerardoPlease check Mulliun @ back double doors, not working properly.Please check Mulliun @ back double doors, not working properly.Nancy Tinajero11/4/201427125133Athletic Field11/4/201427MediumWork In Progress11/4/2014 9:22:00 AM27Munoz, Michaelorder and install scoreboard for baseball field11/20007712802Gym9/15/201477MediumWork In Progress9/15/2014 4:13:11 PM77Munoz, Michaelsouth bleachers do not go in or out automatically.Sebastian Diaz11/2000					usting. Door needs to			Gerardo	Marquez, G
MediumWork In ProgressA wing11/21/2014 11:19:17Marquez, GerardoPlease check Mulliun @ back double doors, not working properly.Nancy Tinajero11/4/2014125133Athletic Field125133Athletic FieldMediumWork In ProgressMunoz, Michaelorder and install scoreboard for baseball fieldAlfredo Holguin9/15/2014122802GymGym9/15/2014 4:13:11 PMMunoz, Michaelsouth bleachers do not go in or out automatically.Sebastian Diaz									-
Marquez, Gerardo Please check Mulliun @ back double doors, not working properly. Nancy Tinajero 11/4/2014 125133 Athletic Field 11/4/2014 9:22:00 AM Munoz, Michael order and install scoreboard for baseball field Alfredo Holguin 11/4/2014 122802 Gym Medium Work In Progress Munoz, Michael south bleachers do not go in or out automatically. Sebastian Diaz Vork In Progress	\$0.00		10		11/21/2014			Main Building	125844
Nancy Tinajero125133Athletic Field11/4/201427MediumWork In Progress11/4/2014 9:22:00 AMMunoz, Michaelorder and install scoreboard for baseball fieldAlfredo Holguin122802Gym9/15/2014122802Gym9/15/2014 4:13:11 PMMediumWork In Progress9/15/2014 4:13:11 PMMunoz, Michaelsouth bleachers do not go in or out automatically.Sebastian Diaz					11/21/2014 11:19:17		Awing	Work In Progress	Medium
125133Athletic Field11/4/201427125133Work In Progress11/4/2014 9:22:00 AM27Munoz, Michaelorder and install scoreboard for baseball field11/4/2014 9:22:00 AMAlfredo Holguin11/4/2014 9:22:00 AM77122802Gym9/15/2014 77MediumWork In Progress9/15/2014 4:13:11 PMMunoz, Michaelsouth bleachers do not go in or out automatically.Sebastian Diaz					le doors , not working	<i>I</i> ulliun @ back dou		Gerardo	Marquez, G
MediumWork In Progress11/4/2014 9:22:00 AMMunoz, Michaelorder and install scoreboard for baseball fieldAlfredo Holguin122802GymMediumWork In ProgressMunoz, Michaelsouth bleachers do not go in or out automatically.Sebastian Diaze								ajero	
Munoz, Michael order and install scoreboard for baseball field Alfredo Holguin 122802 Gym 9/15/2014 122802 Gym 9/15/2014 4:13:11 PM Medium Work In Progress 9/15/2014 4:13:11 PM Munoz, Michael south bleachers do not go in or out automatically. Sebastian Diaz Image: Sebastian Diaz	\$0.00		27				Athletic Field		
Alfredo Holguin 122802 Gym 9/15/2014 77 Medium Work In Progress 9/15/2014 4:13:11 PM 9/15/2014 4:13:11 PM Munoz, Michael south bleachers do not go in or out automatically. Sebastian Diaz					11/4/2014 9:22:00 AM			Work In Progress	Medium
122802Gym9/15/201477MediumWork In Progress9/15/2014 4:13:11 PMMunoz, Michaelsouth bleachers do not go in or out automatically.Sebastian Diaz					seball field	Il scoreboard for ba	order and insta	chael	Munoz, Mic
Medium Work In Progress 9/15/2014 4:13:11 PM Munoz, Michael south bleachers do not go in or out automatically. Sebastian Diaz								lguin	Alfredo Ho
Munoz, Michael south bleachers do not go in or out automatically. Sebastian Diaz	\$0.00		77		9/15/2014			Gym	122802
Sebastian Diaz					9/15/2014 4:13:11 PM			Work In Progress	Medium
					automatically.	rs do notgo in or ou	south bleacher	hael	Munoz, Mic
121722 8/25/2014 98								Diaz	Sebastian
	\$0.00		98		8/25/2014				121722
Medium Work In Progress 8/25/2014 2:32:18 PM					8/25/2014 2:32:18 PM			Work In Progress	Medium
Apodaca, Mario need to replace fiow switch in water storage tank at GMS					storage tank at	e fiow switch in wate		Mario	Apodaca, N
Mario Apodaca								laca	Mario Apoc

12/1/2014 3:28:28 PM

WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description	•	,	Costs bor urs
Location:	Gadsden	MS			
124820		10/31/2014		31	\$0.00
Medium	Work In Progress	10/31/2014 12:37:13			
Apodaca,	Mario	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.			
Margret V	illalobos				
124976		11/2/2014		29	\$0.00
Medium	Work In Progress	11/2/2014 12:36:02 AM			
Apodaca,	Mario	Monthly - Gadsden MS - Lift Station Inspection - Refer to PMschedule details.			
Margret V	illalobos				
125127		11/4/2014		27	\$0.00
Medium	Work In Progress	11/4/2014 12:35:58 AM			
Apodaca,		Monthly - Gadsden MS - Domestic Water Filter - Refer to PMschedule details.			
Margret Vi	illalobos	44/00/0044			.
125978		11/30/2014		1	\$0.00
Medium	Work In Progress	11/30/2014 12:47:20			
Apodaca,	Mario	Monthly - Gadsden MS - Monthly Meter Readings - Refer to PM schedule details.			
Margret V	illalobos				
125983		11/30/2014		1	\$0.00
Medium	Work In Progress	11/30/2014 12:47:23			
Apodaca,	Mario	Monthly - Gadsden MS - Lift Station Inspection - Refer to PMschedule details.			
Margret V		10/00/001			.
124709	Gym	10/29/2014		33	\$0.00
Medium	Work In Progress	10/29/2014 7:43:56 AM			
Villalobos	, David	Urinals in boys gym locker room do not have water needs to be fixed A.S.A.P in order to clean by custodian right			
Mario Her	rera				
124711		10/29/2014		33	\$0.00
Medium	Work In Progress	10/29/2014 7:45:12 AM			
Villalobos	, David	Sink in girls restroom next to b-wing and main hallway there is no running water			
Mario Her	rera				

WOID Priority Assigned Requeste		Area Deferred By Area Number Reason Description	Until Request Date Targe Created Date/Time Actua A		Labor Hours	
Location:	Gadsden	MS				
124873			11/2/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:03 AM			
Orozco, D	aniel	Yearly - Gadsden MS - Grease Tra schedule details.	p - Refer to PM			
Margret Vi	illalobos					
125505	Annex	Classroom	11/13/2014	18		\$0.00
Medium	Work In Progress	room 403	11/13/2014 10:17:40			
Villalobos	, David	We have a strong gas odor in roon building. Please check.	n 403 in Annex			
Nancy Tin	ajero					
125229		Classroom	11/6/2014	25		\$0.00
Medium	Work In Progress	room 169	11/6/2014 1:09:14 PM			
Villalobos	, David	Washerleaks				
Nancy Tin	ajero					
121391	Vocational		8/19/2014	104		\$0.00
Medium	Work In Progress		8/19/2014 6:59:54 AM			
Villalobos	, David	outside water for water hoses do no building	ot work on the whole			
Mario Her	rera					
121677			8/25/2014	98		\$0.00
Medium	Work In Progress		8/25/2014 8:10:22 AM			
Villalobos		Need o replace sink faucet on rest r you	oom Awing thank			
Sebastiar			-//-//			
119501	C-Wing		7/16/2014	138		\$0.00
Medium	Work In Progress		7/16/2014 3:49:11 PM			
Villalobos	, David	Portable - Where restrooms are loc underneath the sink, water has bee Please check this first thing in the m	n shut off for now.			
Mario Her	rera					
125857		Athletic Field	11/21/2014	10		\$0.00
Medium	Work In Progress		11/21/2014 3:04:22 PM			
Sotelo, Er	nrique	please provide power to baseball s installed. please see mike for locat				
Michael M	lunoz					

	Description	Reason	Cre	Request Date ated Date/Time	Actual Comp Date Action Taken	Days Aged	Labor Hours	
ocation: G	adsden MS							
25390				11/10/2014		21		\$0.00
Medium Work In Pro	ogress		11/10/	2014 3:32:04 PM				
Sotelo, Enrique	Need to install o you	outlet on room 601 fc	or computers	thank				
Sebastian Diaz								
25851	Pump House			11/21/2014		10		\$0.00
Medium Work In Pro	ogress		11/21/	2014 2:41:06 PM				
Sotelo, Enrique	need to pull new gms irrigation t	v control wires for the ank	e switch floa	tatthe				
Mario Apodaca								
24747				10/29/2014		33		\$0.00
Medium Work In Pro	ogress		10/29/	2014 3:28:03 PM				
Sotelo, Enrique	Need to fix lamp	os on charter school	thank you					
Sebastian Diaz								
25702				11/18/2014		13		\$0.00
Medium Work In Pro	ogress		11/18/	2014 3:38:24 PM				
/illalobos,David	(575)527-2500 Alternate Conta	SMITH & AGUIRRE FREDDIE TORRES Inct: TOM AUSTIN		t Phone:				
	(575)642-1048 Best Time to C	all: F	ax No:	(575)				
	527-0529 Cell Phone: Email:ftorres@	(575)642-6198 runbox.com	Pager N	lo:				
	DR & WASHING GADSDEN MID INSIDE THE PO ON THE EAST	rk: W141118132643 GTON ST, GO W ON DLE SCHOOL. LOO DND/BUS TURN-A-F SIDE OF THE PROF ILD CONCRETE RU S).	WASHING CATE ALL U ROUND LOO PERTY. CLE	FON TO FILITIES CATED				
	Remarks: ARE CALL FREDDIE WITH QUE		E PAINT & F	ELAGS,				
Dominique Esparza								

WOID Priority Assigned T Requester	Building Status o	Dates:7/1/2014 - 11/30/2014 C Area Deferred Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS					
125692			11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 3:23:26 PM	1			
Villalobos,	David	Contact Name: FREDI Phone: (575)527-250 Alternate Contact: TOM Al (575)642-1048 Best Time to Call: 527-0529 Cell Phone: (575)642 Email: ftorres @runbox.co Location of Work: W1411 DR & WASHINGTON ST, GADSDEN MIDDLE SCH UTILITIES INSIDE BOTH ON WEST SIDE OF PRC WHITE PAINT & FLAGS, (Fax No: (575) 2-6198 Pager No: m 181302380 FROM ANTHONY GO W ON WASHINGTON TO OOL. LOCATE ALL ROCK PONDS LOCATED PERTY. AREA MARKED IN				
Dominique	Esparza	QUESTIONS.					
125695			11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 3:30:36 PM	1			
Villalobos,	David	Contact Name: FREDDI (575)527-2500 Alternate Contact: TOM Al (575)642-1048 Best Time to Call: 527-0529 Cell Phone: (575)642 Email: ftorres @runbox.co Location of Work: W1411 DR & WASHINGTON ST, GADSDEN MIDDLE SCH INSIDE THE SHALLOW F SCHOOL BUILDINGS AN (TO THE SOUTH OF THE MAIN SC	USTIN Alternate Phone: Fax No: (575) 2-6198 Pager No: m 181320390 FROM ANTHONY GO W ON WASHINGTON TO OOL. LOCATE ALL UTILITIES POND AREA BETWEEN THE ID THE RUNNING TRACK				
Dominique	Esparza						
124628		Gym	10/27/2014		35		\$0.00
Medium	Work In Progress	baseball field	10/27/2014 2:00:21 PM	1			
Villalobos,	David	Water fountain outside gy not working.	m area near baseball field is				
Nancy Tina	ioro						

WOID Priority Assigned Requeste		Area Area Number Description	Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	MS						
124188		Classroom		10/15/2014		47		\$0.00
Safety	Work In Progress	room 129 and		10/15/2014 1:55:35 PM	1			
Villalobos	, Da <i>v</i> id		g out of the wall betw rs are against that wa al shock issue.					
Nancy Tin	ajero							
119801	Main Building	Classroom		7/24/2014		130		\$0.00
Medium	Work In Progress	Room 152		7/24/2014 11:57:42 AM	Л			
Villalobos	, David	Sink is dripping leaking into the	g continuously; does cabinet.	n't drain and is				
Nancy Tin	ajero							
124404		Library		10/21/2014		41		\$0.00
Medium	Work In Progress	Library		10/21/2014 12:30:4	5			
Villalobos	, David	Clogged sink ir	n libraryoffice.					
Nancy Tin	ajero							
119660				7/21/2014		133		\$0.00
High	Work In Progress			7/21/2014 3:36:20 PM	N			
Sanchez,	Raul	marked byCD I	licated between the s Mechanical, need to the tank to the pump					
		Company: CD Contact Name: (575)382-8474		Contact Phone:				
		State: NM C	ounty: DONA ANA	City: RURAL				
		Nearest Interse 2nd Intersectin	ecting Street: BERRY g Street: GRACIE ASDEN MIDDLE SC	/RD PL				
		Latitude: 31.99 Zip Code: 8802	971983 Longitude 1	:-106.63006583				
		rownsnip: 26S	S Range: 03E Section	UN 1/4: 34 SVV				
		ST AND NM-47 WASHINGTON E.SIDE OF PRO	rk: FROM INTERS. ('8 IN ANTHONY, GO ST TO ADDRESS. OPERTY, IN THE PO	O W. ON - SPOT ON THE DNDING AREA				
		BETWEEN THI GYM.	E WATER STORAGE	E TANK AND THE				
Dominiqu	e Esparza							

Location: Gadsden MS 125890 11/30/2014 12/3/2014 1 Medium Work In Progress 11/30/2014 12:46:20 1 Diaz, Sebastian Monthly - Gadsden MS - Emerg. Eyewash (Monthly) - Refer to PMs chedule details. 1 Margnet Villalobos 11/7/2014 24 125267 11/7/2014 8:19:52 AM 24 Medium Work In Progress 11/7/2014 8:19:52 AM 24 Diaz, Sebastian Room 169 - Remove ceramic tile and gyps um to provide access to plumbers to repair plumbing. 133 Alfredo Holguin 7/21/2014 3:36:41 PM 133 High Work In Progress 7/21/2014 3:36:41 PM Apodaca, Mario ***The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house*** Company: CD MECHANICAL Contact Name:DEAN POGUE Contact Phone: (575)382-8474 State: NM County: DONA ANA City: RURAL DONA ANA Address 1: 301, WASHINGTON ST Nearest Intersecting Street: BERPY RD 2nd Intersecting Street: BERPY RD 2nd Intersecting Street: 3: 301, WASHINGTON ST AND NM-478 IN ANTHONY, GOW. ON WASHINGTON ST TO ADDRESSSPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA BETWEEN THE WATER STORAGE FAMK AND THE		Labor Hours	Days Aged	rget Comp Date tual Comp Date Action Taken		1/30/2014 Order By Loo Deferred By Reason	Area Area Number Description	Building Status To	WOID Priority Assigned 7 Requester		
Marcine Work In Progress 11/30/2014 12:46:20 Diaz, Sebastian Monthly - Gadsden MS - Emerg. Eyewash (Monthly) - Refer to PMschedule details. Margret Villalobos 11/7/2014 125:267 11/7/2014 8:19:52 AM Diaz, Sebastian Room 169 - Remove ceramic tile and gypsum to provide access to plumbers to repair plumbing. Alfredo Holguin 7/21/2014 8:19:52 AM 119661 7/21/2014 High Work In Progress Apodaca, Mario ***The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house*** Company: CD MECHANICAL Contact Name:DEAN POGUE Contact Phone: (575)382-8474 State: NM County: DONA ANA Address: 1301, WASHINGTON ST Nearest Intersecting Street: GRACIE PL Subdivision: GASDEN MIDDLE SCHOOL Latitude: 31, 99971983 Longitude:-106.63006583 Zip Code: 88021 Township: 265 Range: 03E Section 1/4: 34 SW Location of Work: FROMINTERS. OF WASHINGTON ST AND NM478 IN ANTHONY, GO W, ON WASHINGTON ST TO ADDRESS - SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA							MS	Gadsden	Location:		
Diaz, Sebastian Monthly - Gadsden MS - Emerg. Eyewash (Monthly) - Refer to PMschedule details. Margret Villalobos 125267 11/7/2014 8:19:52 AM Diaz, Sebastian Room 169 - Remove ceramic tile and gyps un to provide access to plumbers to repair plumbing. Alfredo Holguin 119661 7/21/2014 3:36:41 PM Apodaca, Mario ***The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house*** Company: CD MECHANICAL Contact Name:DEAN POGUE Contact Phone: (575)382-8474 State: NM County: DONA ANA City: RURAL DONA ANA Address: 1301, WASHINGTON ST Nearest Intersecting Street: GRACIE PL Subdivision: GASDEN MDDLE SCHOOL Latitude: 31, 99971983 Longitude: -106.63006583 Zip Code: 88021 Township: 265 Range: 03E Section 1/4: 34 SW Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W, ON WASHINGTON ST TO ADDRESS - SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA	\$0.00		1	12/3/2014	11/30/2014				125890		
Margret Villalobos 11/7/2014 24 125267 11/7/2014 8:19:52 AM 24 Medium Work In Progress 11/7/2014 8:19:52 AM 11/7/2014 8:19:52 AM Diaz, Sebastian Room 169 - Remove ceramic tile and gyps um to provide access to plumbers to repair plumbing. 11/7/2014 8:19:52 AM Alfredo Holguin 7/21/2014 3:36:41 PM 133 High Work In Progress 7/21/2014 3:36:41 PM Apodaca, Mario ***The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house*** Company: CD MECHANICAL Connact Name:DEAN POGUE Contact Phone: (575)382-8474 State: NM County: DONA ANA City: RURAL DONA ANA Address: 130, WASHINGTON ST Nearest Intersecting Street: BERRYRD 2nd Intersecting Street: GRACIE PL Subdivision: GASDEN MIDDLE SCHOOL Latitude: 31.99971983 Longitude:-1106.63006583 2ip Code: 88021 Township: 26S Range: 03E Section 1/4: 34 SW Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA Side DOT PROPERTY, IN THE PONDING AREA <td></td> <td></td> <td></td> <td></td> <td>11/30/2014 12:46:20</td> <td></td> <td></td> <td>Work In Progress</td> <td>Medium</td>					11/30/2014 12:46:20			Work In Progress	Medium		
125267 11/7/2014 24 Medium Work In Progress 11/7/2014 8:19:52 AM Diaz, Sebastian Room 169 - Remove ceramic tile and gypsum to provide access to plumbers to repair plumbing. Alfredo Holguin 7/21/2014 119661 7/21/2014 High Work In Progress Apodaca, Mario ***The area indicated between the storage tank and gym marked byCD Mechanical, need to know where main feed runs from the tank to the pump house*** Company: CD MECHANICAL Contact Name:DEAN POGUE Contact Name:DEAN POGUE Contact Phone: (575)382-8474 State: NM State: NM County: DONA ANA Address: 130, WASHINGTON ST Nearest Intersecting Street: GRACIE PL Subdivision: GASDEN MIDDLE SCHOOL Latitude: 31.99971983 Longitude:-106.63006583 Zip Code: 88021 Township: 26S Range: 03E Section 1/4: 34 SW Location of Work: FROMINTERS. OF WASHINGTON ST AND NM-478 IN State: OF PROPERTY, IN THE PONDING AREA State: SPOT ON THE					sh (Monthly) -			stian	Diaz, Seba		
Medium Work In Progress 11/7/2014 8:19:52 AM Diaz, Sebastian Room 169 - Remove ceramic tile and gypsum to provide access to plumbers to repair plumbing. Alfredo Holguin 119661 119661 7/21/2014 Apodaca, Mario ***The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house*** Company: CD MECHANICAL Contact Phone: (675)382-8474 State: NM State: NM County: DONA ANA Address: 1301, WASHINGTON ST Nearest Intersecting Street: GRACIE PL Subdivision: GASDEN MIDDLE SCHOOL Latitude: 31.99971983 Longitude: -106.63006583 Zip Code: 88021 Township: 26S Range: 03E Section 1/4: 34 SW Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA								lalobos	Margret Vil		
Diaz, Sebastian Room 169 - Remove ceramic tile and gyps un to provide access to plumbers to repair plumbing. Alfredo Holguin 119661 7/21/2014 133 High Work In Progress 7/21/2014 3:36:41 PM Apodaca, Mario ***The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house*** Company: CD MECHANICAL Contact Name:DEAN POGUE Contact Phone: (575)382-8474 State: NM County: DONA ANA City: RURAL DONA ANA Address: 1301, WASHINGTON ST Nearest Intersecting Street: BERRY RD 2nd Intersecting Street: Street: BERRY RD 2nd Intersecting Street: Street: Street: 106.63006583 Zip Code: 88021 Township: 26S Range: 03E Section 1/4: 34 SW Location of Work: FROMINTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA	\$0.00		24		11/7/2014				125267		
Alfredo Holguin Alfredo Holguin 119661 7/21/2014 133 High Work In Progress 7/21/2014 3:36:41 PM Apodaca, Mario ****The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house*** Company: CD MECHANICAL Contact Name: DEAN POGUE Contact Phone: (575)382-8474 State: NM County: DONA ANA City: RURAL DONA ANA City: RURAL DONA ANA Address: 1301, WASHINGTON ST Nearest intersecting Street: BERRY RD 2nd Intersecting Street: BERRY RD 2nd Intersecting Street: 31.9971983 Location of Work: FROM INTERS. OF WASHINGTON ST Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA					11/7/2014 8:19:52 AM			Work In Progress	Medium		
119661 7/21/2014 133 High Work In Progress 7/21/2014 3:36:41 PM Apodaca, Mario ***The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house*** Company: CD MECHANICAL Contact Name:DEAN POGUE Contact Phone: (575)382-8474 State: NM County: DONA ANA City: RURAL DONA ANA City: RURAL DONA ANA Address: 130 MASHINGTON ST Nearest Intersecting Street: BERRY RD 2nd Intersecting Street: GRACIE PL Subdivision: GASDEN MIDDLE SCHOOL Latitude: 31.99971983 Longitude:-106.63006583 Zip Code: 88021 Township: 26S Range: 03E Section 1/4: 34 SW Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST ON DON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA								stian	Diaz, Seba		
High Work In Progress 7/21/2014 3:36:41 PM Apodaca, Mario ***The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house*** Company: CD MECHANICAL Contact Name:DEAN POGUE Contact Phone: (575)382-8474 State: NM County: DONA ANA City: RURAL DONA ANA Address: 1301, WASHINGTON ST Nearest Intersecting Street: BERRY RD 2nd Intersecting Street: GRACIE PL Subdivision: GASDEN MIDDLE SCHOOL Latitude: 31.99971983 Longitude:-106.63006583 Zip Code: 88021 Township: 26S Range: 03E Section 1/4: 34 SW Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA								Iguin	Alfredo Ho		
Apodaca, Mario ****The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house*** Company: CD MECHANICAL Contact Name:DEAN POGUE Contact Phone: (575)382-8474 State: NM County: DONA ANA City: RURAL DONA ANA Address: 1301, WASHINGTON ST Nearest Intersecting Street: BERRY RD 2nd Intersecting Street: GRACIE PL Subdivision: GASDEN MIDDLE SCHOOL Latitude: 31.99971983 Longitude: -106.63006583 Zip Code: 88021 Township: 26S Range: 03E Section 1/4: 34 SW Location of Work: FROM INTERS. OF WASHINGTON St AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA	\$0.00		133		7/21/2014				119661		
marked by CD Mechanical, need to know where main feed runs from the tank to the pump house*** Company: CD MECHANICAL Contact Name:DEAN POGUE Contact Phone: (575)382-8474 State: NM County: DONA ANA City: RURAL DONA ANA Address: 1301, WASHINGTON ST Nearest Intersecting Street: BERRYRD 2nd Intersecting Street: GRACIE PL Subdivision: GASDEN MIDDLE SCHOOL Latitude: 31.99971983 Longitude: -106.63006583 Zip Code: 88021 Township: 26S Range: 03E Section 1/4: 34 SW Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA					7/21/2014 3:36:41 PM			Work In Progress	High		
Contact Name:DEAN POGUE Contact Phone: (575)382-8474 State: NM County: DONA ANA City: RURAL DONA ANA Address: 1301, WASHINGTON ST Nearest Intersecting Street: BERRYRD 2nd Intersecting Street: GRACIE PL Subdivision: GASDEN MIDDLE SCHOOL Latitude: 31.99971983 Longitude: -106.63006583 Zip Code: 88021 Township: 26S Range: 03E Section 1/4: 34 SW Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA					w where main	Mechanical, need to k	marked byCD I	Mario	Apodaca, I		
Address: 1301, WASHINGTON ST Nearest Intersecting Street: BERRY RD 2nd Intersecting Street: GRACIE PL Subdivision: GASDEN MIDDLE SCHOOL Latitude: 31.99971983 Longitude: -106.63006583 Zip Code: 88021 Township: 26S Range: 03E Section 1/4: 34 SW Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA						DEAN POGUE	Contact Name (575)382-8474 State: NM C				
Zip Code: 88021 Township: 26S Range: 03E Section 1/4: 34 SW Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA					DL	ecting Street: BERRY g Street: GRACIE I ASDEN MIDDLE SCH	Address: 130 Nearest Interse 2nd Intersectin Subdivision: G				
ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA						.1	Zip Code: 8802				
GYM.					. ON OT ON THE ING AREA	8 IN ANTHONY, GC ST TO ADDRESS OPERTY, IN THE PO	ST AND NM-47 WASHINGTON E.SIDE OF PRO BETWEEN THI				
Dominique Esparza								e Esparza	Dominique		

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description	Until	Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
125694				11/18/2014		13		\$0.00
Medium	Work In Progress		11/	18/2014 3:29:41 PM	1			
Sotelo, En	rique	Company: SMITH & AGUIRR Contact Name: FREDDIE TORF (575)527-2500 Alternate Contact: TOM AUSTIN (575)642-1048 Best Time to Call: 527-0529 Cell Phone: (575)642-6198 Email: ftorres@runbox.com Location of Work: W1411181320 DR & WASHINGTON ST, GO W C GADSDEN MIDDLE SCHOOL. LO INSIDE THE SHALLOW POND A SCHOOL BUILDINGS AND THE (TO THE SOUTH OF THE MAIN SCHOOL	RES Con Alterna Fax No: Page 390 FROM ON WASHIN OCATE ALL REA BETW RUNNING	tact Phone: ate Phone: (575) er No: ANTHONY IGTON TO UTILITIES EEN THE TRACK				
Dominique	e Esparza	Remarks: AREA MARKED IN WH CALL FREDDIE WITH QUESTIONS.						
125691				11/18/2014		13		\$0.00
Medium	Work In Progress		11/	18/2014 3:20:44 PM	1			
Sotelo, Eni	rique	Company: SMITH & AGUIR Contact Name: FREDDIE TOF Phone: (575)527-250 Alternate Contact: TOM AUSTIN (575)642-1048 Best Time to Call: 527-0529 Cell Phone: (575)642-6198 Email: ftorres@runbox.com Location of Work: W1411181302 DR & WASHINGTON ST, GO W (GADSDEN MIDDLE SCHOOL. LO UTILITIES INSIDE BOTH ROCK I ON WEST SIDE OF PROPERTY WHITE PAINT & FLAGS, CALL FR QUESTIONS.	RES Con Alterna Fax No: Page 380 FROM DN WASHIN DCATE ALI PONDS LO AREA MAF	ANTHONY IGTON TO CATED RKED IN				
Dominique	e Esparza							

WOID Priority Assigned			Deferred By	Until Request Date	e Target Comp Date e Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
125701				11/18/201	4	13		\$0.00
Medium	Work In Progress			11/18/2014 3:37:57 P	M			
Sotelo, En	Ū.	(575)527-2500 Alternate Conta (575)642-1048 Best Time to Ca 527-0529 Cell Phone: Email: ftorres @ Location of Wor DR & WASHING GADSDEN MIDI INSIDE THE PC ON THE EAST S POND AND BUI (STRUCTURES	FREDDIE TORF ct: TOM AUSTIN all: (575)642-6198 runbox.com k: W1411181326 GTON ST, GO W 0 DLE SCHOOL. L OND/BUS TURN- SIDE OF THE PR ILD CONCRETE S).	RE CONSTRUCTION RES Contact Phone: Alternate Phone: Fax No: (575) Pager No: 6430 FROM ANTHONY ON WASHINGTON TO OCATE ALL UTILITIES A-ROUND LOCATED OPERTY. CLEAN	ν.			
		CALL FREDDIE WITH QUE						
Dominique	e Esparza							
125820				11/20/201	4	11		\$0.00
Medium	Work In Progress			11/20/2014 3:40:30 P	M			
Sotelo, En	rique	Need to fix lamp	o on room 304 th	ank you				
Sebastian								
124534	C-Wing			10/23/201	4	39		\$0.00
Medium	Work In Progress			10/23/2014 3:38:25 P	M			
Diaz, Seba		Ruben; NEED ON C WING TH		PAINT FOR RAMPS				
Sebastian	Diaz C-Wing			8/27/201	Λ	96		\$0.00
Medium	Work In Progress			8/27/2014 1:15:58 P		30		ψ0.00
Diaz, Seba	Ū.	as per conversa thank you	tion, please pain	tall rooms inside.	IVI			
Michael M	unoz							
121673				8/25/201	4	98		\$0.00
Medium	Work In Progress			8/25/2014 7:39:32 A	М			
Solis, Lore	enzo	Need to check p	ump on boiler roo	om eastside thank you				
	Diaz							

WOID Priority Assigned	Building Status	Dates:7/1/2014 - 11/30/2014 Ord Area Deferred E Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	Name	-					
Location:	Gadsden	MS					
120241			8/3/2014	8/19/2014	120		\$0.00
Medium	Work In Progress		8/3/2014 12:32:32 AM	1			
Villalobos	, Margret	Monthly - Gadsden MS Mon PMschedule details.	thly Chiller Insp Refer to	Emailed 8/4/14			
Margret Vi	llalobos						
123539			10/5/2014	10/21/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:42:05 AM	1			
Villalobos	, Margret	Yearly - Gadsden MS Octob PMschedule details.	er Chiller Insp Refer to				
Margret Vi	llalobos						
125557			11/14/2014		17		\$0.00
Medium	Work In Progress		11/14/2014 8:29:10 AM	1			
Solis, Lore	enzo	Need to check monoxide or	n annex thank you				
Sebastian	Diaz						
125628			11/17/2014		14		\$0.00
Medium	Work In Progress		11/17/2014 11:17:24	ŀ			
Solis, Lore	enzo	Need to check heater on an	inex thank you				
Sebastian	Diaz						
125629			11/17/2014		14		\$0.00
Medium	Work In Progress		11/17/2014 11:18:34	ļ			
Solis, Lore	enzo	Need to check boiler west th	ank you				
Sebastian	Diaz						
125750	Main Building	Classroom	11/19/2014		12		\$0.00
Medium	Work In Progress	room 158	11/19/2014 12:17:41				
Solis, Lore	enzo	Heater not working, blowing	cold air.				
Nancy Tina	ajero						
125755		Classroom	11/19/2014		12		\$0.00
Medium	Work In Progress	room 416	11/19/2014 1:39:58 PM	1			
Marquez, 0	Gerardo	Please check door lock. Hav	ing trouble locking door.				
Nancy Tin			-				

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2 Area Defe Area Number Rea Description	erred By	Until	Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS							
125796					11/20/2014		11		\$0.00
High	Work In Progress			11/20/	2014 1:45:47 PM	1			
Marquez, (Gerardo	Need (1) one "J3" ga construction office by 20114. Should you h Mr. Ralph Gallegos a office. Thank You	y Friday mornir have any questi	ng November ions please o	contact				
Dominiqu	e Esparza								
124896					11/2/2014	11/18/2014	29		\$0.00
Medium	Work In Progress			11/2/2	014 12:35:15 AN	1			
Villalobos		Monthly - Gadsden M PMschedule details		iller Insp R	efer to	E-mailed 11/3/14			
Margret Vi					0/0/0044				* •••••
122454	Band Room	Classroom			9/8/2014		84		\$0.00
Medium	Work In Progress	room 100		9/8/2	014 12:34:39 PN	1			
Marquez, (Request for ten pad band Room. Makes							
Nancy Tin	ajero				7/00/0044		4.05		* •••••
119972				_ / /-	7/29/2014		125		\$0.00
Medium	Work In Progress	front office		7/29/2	014 10:04:45 AN	1			
Marquez, (Gerardo	Need key (A-57) for	custodian						
Nancy Tin	ajero								
119973					7/29/2014		125		\$0.00
Medium	Work In Progress	front office-		7/29/2	014 10:06:01 AN	1			
Marquez, (Gerardo	Need Keys for new I V-15, one each pleas		4-62, V-8, WA	\-64, 01,				
Nancy Tin	-								
125559	C-Wing	Cafeteria			11/14/2014		17		\$0.00
Medium	Work In Progress	storage room		11/14/	2014 9:27:09 AN	1			
Marquez,	Gerardo	Change key to stora	ge room from	a J to a C.					
Nancy Tin	ajero								
125576		Classroom			11/14/2014		17		\$0.00
Medium	Work In Progress	room 304		11/14/	2014 2:49:31 PN	1			
Marquez, (Gerardo	door cylinder is brok locked. Need to repa			notbe				
Nancy Tin	ajero								

WOID Priority Assigned ⁻ Requester		Area [Area Number F Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	MS						
125428				11/12/2014		19		\$0.00
Medium	Work In Progress	Room 108		11/12/2014 10:17:38	3			
Marquez, C	Gerardo	Re-Key2 cabinet	ts.					
Nancy Tina	ajero							
118865				7/1/2014		153		\$0.00
Medium	Work In Progress			7/1/2014 2:09:02 PM	1			
Diaz, Seba	istian	PC Automated - E Mechanic tried to						
Michael M	unoz							
125892				11/30/2014	12/16/2014	1		\$0.00
Medium	Work In Progress			11/30/2014 12:46:22	2			
Villalobos,	Margret	Monthly - Gadsde PMschedule det		hiller Insp Refer to				
Margret Vil	lalobos							
123861				10/8/2014		54		\$0.00
Medium	Work In Progress			10/8/2014 9:48:04 AN	1			
Flores, Pe		weed eater 1274 out of exhaust. Re		arting fuel is coming one				
Mario Herr				0/00/0044		4.04		.
121631	Gym	Gym		8/22/2014		101		\$0.00
Medium	Work In Progress	GYM		8/22/2014 11:04:49 AN	1			
Diaz, Seba	istian		e a safetystrap a	goal on north side is nd its no longer there. ⁄e it.				
Nancy Tina	ajero							
120719		Parking Lot		8/7/2014		116		\$0.00
Medium	Work In Progress	Mail box in		8/7/2014 1:21:57 PN	1			
Diaz, Seba	stian	Please put weath rain goes in. Mai		ew mail box. Dirt and ged.				
Nancy Tina	ajero							
124836		Classroom		10/31/2014		31		\$0.00
Medium	Work In Progress	room 148		10/31/2014 12:22:35	5			
Diaz, Seba	Istian			aced where teacher r. Please see Mrs.				
Nancy Tina	ajero							

Selected Dat WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS					
125504	Main Building	Classroom	11/13/2014		18		\$0.00
Medium	Work In Progress	room 110	11/13/2014 9:56:08 AM				
Diaz, Seba	0	Second Request-Need bulletin bo	ard strips in hall wall.				
Nancy Tina							
125674		Classroom	11/18/2014		13		\$0.00
Medium	Work In Progress	room 100	11/18/2014 11:36:40				
Diaz, Seba	stian	Please put together a music stand	storage cart.				
Nancy Tina	ajero						
125751	Main Building	Classroom	11/19/2014		12		\$0.00
Medium	Work In Progress	room 158	11/19/2014 12:18:21				
Diaz, Seba	istian	Two light bulbs not working.					
Nancy Tina	ajero						
125359	Main Building	Classroom	11/10/2014		21		\$0.00
Medium	Work In Progress	room 110	11/10/2014 1:06:14 PM				
Diaz, Seba	istian	Need bulletin board strips in the ha	ll wall.				
Nancy Tina	ajero						
121935			8/28/2014		95		\$0.00
Medium	Work In Progress		8/28/2014 3:44:19 PM				
	Guadalupe	Need to bring tractor use for wat vocational and front A wing thank					
Sebastian 125855	Diaz	Athletic Field	11/21/2014		10		\$0.00
Medium	Work In Progress	Americ Field	11/21/2014 3:01:34 PM		10		ψ0.00
Untiveros,	Guadalupe	please plant trees around basebal irrigation as discussed. thank you					
Michael Mu	unoz						
124573			10/24/2014		38		\$0.00
Medium	Work In Progress		10/24/2014 12:35:53				
Ontiveros,	Guadalupe	Need dirt between vocation and ba	nd room thank you				
Sebastian	Diaz						
125037			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:39 AM				
Orozco, Da	aniel	Monthly - Gadsden MS Fire Suppre PMschedule details.	ession Insp Refer to				
Margret Vil				_			A -
Count: 88 \	Work Orders	Avg. Age of WO's	1	Total for Gadsde	n MS	0	\$0.00

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	La Union	ES					
125038			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:40 AM				
Orozco, Da	•	Monthly - La Union ES Fire Suppres PMschedule details.	sion Insp Refer to				
Margret Vil	lalobos						
124965			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:56 AM				
Aguilar, Pa	tricio	Monthly - La Union ES Exit Sign Insp PMschedule details.	: Monthly - Refer to				
Margret Vil	lalobos						* • • • •
124966			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:56 AM				
Aguilar, Pa		Monthly - La Union ES Emer. Light T Refer to PMschedule details.	est: Monthly-				
Margret Vil	lalobos		11/0/0011				<u> </u>
124967			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:57 AM				
Aguilar, Pa		Monthly - La Union ES - Clothes Dry to PMschedule details.	er (Monthly) - Refer				
Margret Vil	lalobos		44/20/2044	40/0/2044	4		<u> </u>
125957			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:06				
Aguilar, Pa		Monthly - La Union ES Exit Sign Insp PMschedule details.	: Monthly - Refer to				
Margret Vil	lalobos		44/00/0044	40/0/0044	4		<u> </u>
125958			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:07				
Aguilar, Pa	atricio	Monthly - La Union ES Emer. Light T Refer to PMschedule details.	est: Monthly-				
Margret Vil	lalobos						
125951			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:02				
Aguilar, Pa	tricio	Monthly - La Union ES - Clothes Dry to PMschedule details.	er (Monthly) - Refer				
Margret Vil	lalobos						

Selected Dat WOID Priority Assigned 7 Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Locati Area Deferred By L Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Total Costs
Location:	La Union	ES					
124738			10/29/2014		33		\$0.00
Medium	Work In Progress		10/29/2014 2:49:48 PN	1			
Aguilar, Pa	atricio	work order to myself - need to replace fi cover not working - alta vista	re pull station				
Patricio Ag	juilar						
124739			10/29/2014		33		\$0.00
Medium	Work In Progress		10/29/2014 2:54:02 PN	1			
Aguilar, Pa		work order to myself - need to install do wall teacher lounge - holl on wall	or nob stop on				
Patricio Ag	juilar		40/00/0044		40		<u> </u>
124446			10/22/2014		40		\$0.00
Medium	Work In Progress		10/22/2014 10:35:54	Ļ			
Aguilar, Pa		wo to myself - remove and order new r fan elect.room.	notor for exhaust				
Patricio Ag	juilar		10/0/2011		50		¢0.00
123946			10/9/2014		53		\$0.00
Medium	Work In Progress		10/9/2014 3:15:21 PN	//			
Ambriz, Jos	se	need thermostat for heater in gym - tha	ank you				
Patricio Ag	juilar						
125491			11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 8:18:47 AM	1			
Ambriz, Jos	se	the heater valve is not closing room get valve replaced r308 - thank you for you					
Patricio Ag	juilar						<u> </u>
124303		Electrical Room	10/17/2014		45		\$0.00
Medium	Work In Progress		10/17/2014 3:01:26 PN	1			
Castillo, Ca		Walk-thru electrical room.Inspect equip generate w.oexhaust fan not working					
Carlos Ca	stillo		44/04/0044		40		<u> </u>
125842			11/21/2014		10		\$0.00
Medium	Work In Progress		11/21/2014 10:36:29)			
Aguilar, Pa	tricio	floor drain in mech. room clog - will nee	dsnake				
Patricio Ag	juilar						
124875			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:04 AM	1			
Orozco, Da	aniel	Yearly - La Union ES - Grease Trap - I schedule details.	Refer to PM				
Margret Vil	lalobos						
12/1/2014	3:28:28 PM					Page 11	1 of 195

WOID Priority Assigned	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description Description	arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	La Union	ES				
121824		8/27/2014		96		\$0.00
Medium	Work In Progress	8/27/2014 7:45:14 AM				
Ronquillo,	Ruben	REPAIR BROKEN SLIDE				
Ruben Ro	nquillo					
125989	-	11/30/2014		1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:27				
Sanchez, F	Raul	Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details.				
Margret Vil	lalobos					
125995		11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:31				
Aguilar, Pa	itricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PMschedule details.				
Margret Vil	lalobos					
124982		11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:06 AM				
Aguilar, Pa	itricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PMschedule details.				
Margret Vil	lalobos					
120338		8/3/2014		120		\$0.00
Medium	Work In Progress	8/3/2014 12:33:40 AM				
Munoz, Mic		Yearly - La Union ES Fire Ext. Insp. (Yearly) - Refer to PMschedule details.				
Margret Vil	lalobos		/			
125016		11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:26 AM				
Orozco, Da		Monthly - La Union ES Range Hood Cleaning - Refer to PMschedule details.				
Margret Vil	lalobos		/			
125344		11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress	11/9/2014 12:41:42 AM				
Aguilar, Pa		Monthly - La Union ES Playground Insp - Refer to PM schedule details.				
Margret Vil	lalobos					

Priority S Assigned To Requester Na	itatus ame	Area Deferred By Area Number Reason Description	Until Request Date T Created Date/Time A		Days Aged	Labor Hours	
Location:	Loma Lin	da ES					
125337			11/9/2014	11/25/2014	22		\$0.00
Medium V	Vork In Progress		11/9/2014 12:41:34 AM				
Medina, Eric		Monthly - Loma Linda ES Playgro schedule details.	und Insp - Refer to PM				
Margret Villal	obos						
124929			11/2/2014	11/10/2014	29		\$0.00
Medium V	Vork In Progress		11/2/2014 12:35:35 AM				
Medina, Eric		Monthly - Loma Linda ES Emer. L Refer to PMschedule details.	ight Test: Monthly -				
Margret Villal	obos						
124930			11/2/2014	11/10/2014	29		\$0.00
Medium V	Vork In Progress		11/2/2014 12:35:36 AM				
Medina, Eric		Monthly - Loma Linda ES Exit Sign to PM schedule details.	n Insp: Monthly - Refer				
Margret Villal	obos		44/40/0044		10		* •••••
125786			11/19/2014		12		\$0.00
Medium V	Vork In Progress		11/19/2014 6:23:01 PM				
Medina, Eric		need to replace belt for fan coil in	cafe				
Eric Medina							
125377			11/10/2014		21		\$0.00
Medium V	Vork In Progress	Nurses Office	11/10/2014 2:13:04 PM				
Medina, Eric		Lights Flickering					
Angie Flores							
125286			11/7/2014		24		\$0.00
Medium V	Vork In Progress		11/7/2014 11:27:39 AM				
Medina, Eric		Area in front of building with colore rake and level out crushed rock pre rake or landscaping rake. remove left by drag and truck on sidewalks	eferable with a hand piles of crushed rock				
Alfredo Holgu	uin						
122798		Portables	9/15/2014		77		\$0.00
Medium V	Vork In Progress		9/15/2014 4:03:39 PM				
Miranda, Dan	ny	portable 1a/1b will need a 6'fur for mike for details.	new plumbing. call				
	oz						

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By I Area Deferred By Area Number Reason Description	Location, Status Until Request Date Target Comp Da Created Date/Time Actual Comp Da Action Tak	ate Aged	Labor Hours	Costs
Location:	Loma Lir	nda ES				
125284		Portables	11/7/2014	24		\$0.00
Medium	Work In Progress		11/7/2014 11:21:43 AM			
Miranda, I	Danny	Spec Ed Portable- Need to move v minimum of 4 ft out (west)	vest wall in restroom			
Alfredo Ho	olguin					
125494		Classroom	11/13/2014	18		\$0.00
Medium	Work In Progress	108	11/13/2014 8:35:22 AM			
Medina, E	ric	Sink is clogged-mayneed snake				
Angie Flor	es					
125731		Classroom	11/19/2014	12		\$0.00
Medium	Work In Progress	111	11/19/2014 8:00:13 AM			
Medina, E	ric	Heater we cannot get off				
Angie Flor	es					
125732		Classroom	11/19/2014	12		\$0.00
Medium	Work In Progress	106	11/19/2014 8:08:59 AM			
Medina, E	ric	Paperorganizerassembly				
Angie Flor	es					
125378		Classroom	11/10/2014	21		\$0.00
Medium	Work In Progress	Medina	11/10/2014 2:13:53 PM			
Medina, E	ric	AC Vent no working				
Angie Flor	es					
123908	Main Building	Classroom	10/9/2014	53		\$0.00
Medium	Work In Progress	212	10/9/2014 7:33:29 AM			
Medina, E	ric	Lights are flickering and also plea same height	se raise all desks to			
Angie Flor	es					
123315			9/26/2014	66		\$0.00
Medium	Work In Progress		9/26/2014 3:34:50 PM			
Medina, E	ric	9/26 1. check s chool and check in with a 2. leak checked all gas lines along 4. worked on wo# 122752 1. enter data				
Eric Medir	na					

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Loma Lir	ida ES					
122493			9/9/2014		83		\$0.00
Medium	Work In Progress		9/9/2014 8:41:31 AM				
Medina, E	ric	Soccer Goals - Remove overgrown v install new soccer nets.	veeds and order and				
Alfredo Ho	lguin						
122497			9/9/2014		83		\$0.00
Medium	Work In Progress		9/9/2014 8:46:31 AM				
Medina, E	ric	Pine Trees along rock wall on wests up pine needles and pine cones	side of campus -Pick				
Alfredo Ho	lguin						
122498			9/9/2014		83		\$0.00
Medium	Work In Progress		9/9/2014 8:56:19 AM				
Medina, E	ric	Portable area sidewalks- Order fill d screenings) and backfill eroded are -					
Alfredo Ho	lguin						
124961			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:54 AM				
Medina, E	ric	Monthly - Loma Linda ES - Clothes Refer to PMschedule details.	Dryer (Monthly) -				
Margret Vi	llalobos						
125285		Portables	11/7/2014		24		\$0.00
Medium	Work In Progress		11/7/2014 11:23:17 AM				
Medina, E	ric	Spec Ed Portable- Remove west wa Danny M can install new one a min (west)					
Alfredo Ho	lguin						
125933			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:50				
Medina, E	ric	Monthly - Loma Linda ES - Clothes Refer to PMschedule details.	Dryer (Monthly) -				
Margret Vi	llalobos						
125934			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:51				
Medina, E	ric	Monthly - Loma Linda ES Emer. Lig Refer to PMschedule details.	ht Test: Monthly -				
Margret Vi							

29		
29		\$0.00
29		
		\$0.00
		\$0.00
		\$0.00
		\$0.00
75		
75		
75		
75		
		\$0.00
120		\$0.00
1		\$0.00
29		\$0.00
12		\$0.00
	29	29

Selected Dar WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Loma Lin	ida ES					
125630	Main Building	Custodial	11/17/2014		14		\$0.00
Medium	Work In Progress		11/17/2014 12:27:59				
Carbajal, J	limmy	need service for the vacuum clea (Ruben)strong noise on the moto firm .,thanks.					
Luis Solis			44/40/0044		40		<u> </u>
125671			11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 10:48:05				
Orozco, Da	aniel	AS PER ENVIRONMENT INSPECT HOT WATER TO 3 COMPARTME MANAGER DOLORES R. 882.47	NT SINK. SNP				
Maritza Go	nzalez						
119567			7/18/2014		136		\$0.00
Medium	Work In Progress		7/18/2014 10:50:19 AM				
Orozco, Da	aniel	BROKEN GLASS ON SERVING	_INE.				
Maritza Go	nzalez						
125234			11/6/2014		25		\$0.00
Medium	Work In Progress		11/6/2014 1:49:02 PM				
Orozco, Da	aniel	STAND ON LEFT HAND SIDE NO PROPERLY, HAVE TO WIGGLE TIMES FOR IT TO TURN ON. SN DOLORES R. 882.4707	CORD SEVERAL				
Maritza Go	nzalez						
125128			11/4/2014		27		\$0.00
Medium	Work In Progress		11/4/2014 12:35:59 AM				
Apodaca, I	Mario	Monthly - Loma Linda ES - Dome to PMschedule details.	estic Water Filter - Refer				
Margret Vil	lalobos						
123928			10/9/2014		53		\$0.00
Medium	Work In Progress	rm 105	10/9/2014 1:50:51 PM				
Marquez, G	Gerardo	need to replace class room door					
Eric Medin	а						
120081			7/31/2014		123		\$0.00
Medium	Work In Progress		7/31/2014 9:06:08 AM				
Marquez, C	Gerardo	Gerrydoor handle in portable 4 w	as broken by vandals				
Eric Medin	_						

WOID Priority Assigned T Requester	Building Status Fo	Dates:7/1/2014 - 11/30/2014 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Loma Lin	ida ES					
121440			8/19/2014		104		\$0.00
Medium	Work In Progress		8/19/2014 3:03:42 PN	I			
Orozco, Da	niel	LATCH THAT LOCKS THE WALK I MANAGER DOLORES R. 882.470					
Maritza Go	nzalez						
125379		Classroom	11/10/2014		21		\$0.00
Medium	Work In Progress	215	11/10/2014 2:14:48 PM				
Villalobos,	David	Sink clogged, water doesn't drain o	ut				
Angie Flore	es						
124872			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:02 AM				
Orozco, Da	niel	Yearly - Loma Linda ES - Grease ⁻ schedule details.	Frap - Refer to PM				
Margret Vil	lalobos						
122774		Portables	9/15/2014		77		\$0.00
Medium	Work In Progress		9/15/2014 3:36:17 PM	l			
Sotelo, Eni	rique	need to provide power to new wash and to new restroom. also will need table.					
Michael Mu	unoz						
122754		Pool	9/15/2014		77		\$0.00
Medium	Work In Progress		9/15/2014 10:42:21 AM				
Villalobos,	David	As discussed, need to remove con rest room and plumb out for washe and sink need to be plumbed out in across existing restroom. will need	r and drier, commode the storage room				
Michael Mu	unoz						
125640			11/17/2014		14		\$0.00
Medium	Work In Progress		11/17/2014 3:20:41 PM				
Sotelo, Eni	rique	need to replace 6 emergency light l	patteries in portable 1				
Eric Medin	а						
125218			11/6/2014		25		\$0.00
Medium	Work In Progress		11/6/2014 9:10:49 AM				
Solis, Lore	nzo	Lorenzo circulating pump electrica	panel wont come on				

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Loma Lin	nda ES					
122752		Portables	9/15/2014		77		\$0.00
Medium	Work In Progress		9/15/2014 10:31:43 AN	I			
Medina, E	ric	Please paint inside and out of Pol include ramps and stairs.	table 1A&1B, to				
Alfredo Ho	olguin						
120944			8/11/2014		112		\$0.00
Medium	Work In Progress		8/11/2014 2:13:05 PM	1			
Medina, E	ric	Paint all stalls					
Eric Medir	na						
125287	Main Building		11/7/2014		24		\$0.00
Medium	Work In Progress		11/7/2014 11:30:08 AN	I			
Medina, E	ric	east Side exit doors need to be re	painted properly				
Alfredo Ho	olguin						
120710	Main Building		8/7/2014		116		\$0.0
Medium	Work In Progress	Entrance Doors	8/7/2014 10:29:16 AN	I			
Marquez, (Gerardo	Need to switch out push bar so t	hat we can use a kev				
Angie Flor			,				
122152	Main Building	Portables	9/2/2014		90		\$0.00
Medium	Work In Progress	C1 & C2	9/2/2014 8:25:02 AN	I			
Marquez, (Gerardo	Replace the door handles in the r room with a non locking knob. If care of this before Monday Septe	you can please take				
Angie Flor	es						
121485			8/20/2014		103		\$0.00
Medium	Work In Progress		8/20/2014 7:41:13 AN	l			
Marquez, (Gerardo	Entrance Door in between 3rd and core broke, its not working at all, that school can be closed and loc	need to have this fix so				
Angie Flor	es						
120403		Classroom	8/4/2014		119		\$0.00
Medium	Work In Progress	101	8/4/2014 9:23:06 AN	l			
Lara, Ralp	h	We need a cabinet lock					
Angie Flor	es						
125217			11/6/2014		25		\$0.00
Medium	Work In Progress		11/6/2014 9:09:39 AN	I			
Ontiveros,	Guadalupe	Pete need to request bobcat plea	se				
Eric Medir	na						
2/1/2014	3:28:29 PM					Daga (4	19 of 195

12/1/2014 3:28:29 PM

Selected Da	te Range for Request Building	Dates:7/1/2014 - 1 Area	1/30/2014 Order By Loo Deferred By	cation, Status Until	Request Date	Target Comp Date	Days	Labor	Tota Costs
Priority	Status	Area Number	•		-	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requester		•							
Location:	Loma Lin	da ES							
122169	Main Building	Hallway/Corric	lor		9/2/2014		90		\$0.00
Medium	Work In Progress			9/2/20	14 12:23:15 PN	1			
Solis, Luis		office, and also	ax floors in the Lobby main hall. Needs to eptember 24th. Need th.	be waxed on	the				
Angie Flor	es								
122170	Main Building	Office			9/2/2014		90		\$0.00
Medium	Work In Progress	Office		9/2/20	14 12:27:19 PN	1			
Solis,Luis			the chairs in front of t nat chairs are not wob		Ineed				
Angie Flor	es								
125039					11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress			11/2/20	14 12:36:41 AN	1			
Orozco, Da	aniel	Monthly-Loma to PMschedule	a Linda ES Fire Suppre e details.	ession Insp.	- Refer				
Margret Vi	llalobos								
123690					10/5/2014	10/26/2014	57		\$0.00
Medium	Work In Progress			10/5/20	14 12:44:03 AN	1			
Munoz, Mio	chael	Monthly - Loma PMschedule d	a Linda ES Fire Sprin etails.	kler Insp F	efer to				
Margret Vi	llalobos								
Count: 54	Work Orders	A	vg. Age of WO's 49			Total for Loma Lind	la ES	0	\$0.00

WOID Priority Assigned	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	Target Comp Date Actual Comp Date Action Taken		Labor Hours	Costs
Location:	Mesquite	ES				
125040		11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:41 AM	I			
Orozco, Da	aniel	Monthly - Mesquite ES Fire Suppression Insp Refer to PMschedule details.				
Margret Vil	llalobos					
125623		Custodial 11/17/2014		14		\$0.00
Medium	Work In Progress	11/17/2014 10:21:20	1			
Marquez, C	Gerardo	please my key #M195 key is not working having problems to open doors.thank you				
Luis Sauc	edo					
125497		11/13/2014		18		\$0.00
Medium	Work In Progress	11/13/2014 8:50:03 AV	I			
Gallegos,	Rafael	atten.mr. Gallegos unit in rm.206 is showing no flame message also admin offices are cold.				
Joe Ramir	rez					
122438		9/8/2014		84		\$0.00
Medium	Work In Progress	9/8/2014 8:47:31 AV	l			
Ramirez, J	loe	need to paint math intervention rm.				
Joe Ramir	rez					
125350		11/10/2014		21		\$0.00
Medium	Work In Progress	11/10/2014 8:47:52 AV	l			
Solis, Lore	enzo	the unit in rm.505 is not working				
Joe Ramir	rez					
125492		11/13/2014		18		\$0.00
Medium	Work In Progress	11/13/2014 8:24:42 AV	I			
Solis, Lore	enzo	portable 609 heating unit is not working at all				
Joe Ramir	ez					
125417		11/12/2014		19		\$0.00
Medium	Work In Progress	11/12/2014 7:58:21 AV	I			
Solis, Lore	-	need to replace water fountain in front of south lounge				
Joe Ramir						
125679	02	11/18/2014		13		\$0.00
Medium	Work In Progress	11/18/2014 2:15:41 PM		-		
	-					
Sotelo, En	nque	Room 403 Restroom - need to replace ballast.				

Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Target Comp Created Date/Time Actual Comp Action Ta	Date Aged	Labor Hours	
Location:	Mesquite	ES				
125889			11/30/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:20			
Ramirez, .	Joe	Monthly - Mesquite ES - Barrack Dra Refer to PM schedule details.	ainage (Monthly) -			
Margret Vi	llalobos					
124066			10/13/2014	49		\$0.00
Medium	Work In Progress		10/13/2014 10:36:12			
Sotelo, En	rique	need to raise elec. strip in the lib.				
Joe Rami	rez					
123402	Main Building		9/30/2014	62		\$0.00
Medium	Work In Progress		9/30/2014 9:12:30 AM			
Villalobos	, David	contract services for roto rooter to ma lines at cafeteria and main building	aintain main sewer			
David Villa	alobos					
125182			11/5/2014	26		\$0.00
Medium	Work In Progress		11/5/2014 2:48:10 PM			
Villalobos	, David	need to replace lavatory in bathroom one came off the wall and broke.	rm.401 the other			
Joe Rami	rez					
124884			11/2/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:09 AM			
Orozco, Da	aniel	Yearly - Mesquite ES - Grease Trap schedule details.	- Refer to PM			
Margret Vi						
125562	Main Building		11/14/2014	17		\$0.00
Medium	Work In Progress	Main Office	11/14/2014 10:36:26			
Marquez, (Gerardo	As per Ms. Silvaggio/Principal, she is new plaque for our Counselor Sonn for his office front door.				
Sandra M	ora					
125987			11/30/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:26			
Apodaca,	Mario	Monthly - Mesquite ES - Lift Station to PMschedule details.	Inspection - Refer			

WOID Priority Assigned ⁻ Requester		Area Deferred By Until Area Number Reason Description	Request Date Tar Created Date/Time Ac		Days Aged	Labor Hours	
Location:	Mesquite	ES					
125982			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:22				
Apodaca, I	Mario	Monthly - Mesquite ES - Monthly Meter Read Refer to PMschedule details.	dings -				
Margret Vil	lalobos						
124980			11/2/2014		29		\$0.00
Medium	Work In Progress	11,	/2/2014 12:36:04 AM				
Apodaca, I	Mario	Monthly - Mesquite ES - Lift Station Inspecti to PMschedule details.	on - Refer				
Margret Vil	lalobos						
120340			8/3/2014		120		\$0.00
Medium	Work In Progress	8,	/3/2014 12:33:41 AM				
Munoz, Mic		Yearly - Mesquite ES Fire Ext. Insp. (Yearly) PMschedule details.	- Refer to				
Margret Vil		0#	0/05/0044				^
121721	Main Building	Office	8/25/2014		98		\$0.00
Medium	Work In Progress		/25/2014 2:28:47 PM				
Estrada, Je		Carpet is coming apart at the seam entrance office.	e to the first				
Jesus Estr 121639	rada		8/22/2014		101		\$0.00
					101		φ 0. 00
Medium	Work In Progress		/22/2014 1:25:52 PM				
Estrada, Je		carpet in portable #601 needs to be repaired	1.				
Luis Sauc	edo		11/0/0011	44/00/0044			.
125018			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress	11,	/2/2014 12:36:28 AM				
Orozco, Da		Monthly - Mesquite ES Range Hood Cleaning PMschedule details.	ng - Refer to				
Margret Vil	lalobos						
124984			11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress	11,	/2/2014 12:36:07 AM				
Ramirez, J	oe	Monthly - Mesquite ES Monthly FE Inpsectic PMschedule details.	on - Refer to				

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order B Area Deferred By Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Mesquite	ES					
126006			11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:38				
Ramirez,	Joe	Monthly - Mesquite ES Monthly PMschedule details.	FE Inpsection - Refer to				
Margret Vi	illalobos						
125477			11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 7:36:35 AM				
Carrasco,	, Danny	Move old libraryshelving from M to disposal. will need truck with to assist					
Alfredo Ho	olguin						
125963			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:10				
Ramirez,	Joe	Monthly - Mesquite ES Emer. Li to PMschedule details.	ght Test: Monthly - Refer				
Margret Vi	illalobos						
125964			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:11				
Ramirez,	Joe	Monthly - Mesquite ES Exit Sign PMschedule details.	Insp: Monthly - Refer to				
Margret Vi	illalobos		11/20/2011				
125965			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:11				
Ramirez, .	Joe	Monthly - Mesquite ES - Clothes to PMschedule details.	s Dryer (Monthly) - Refer				
Margret Vi							
125753	Main Building	Classroom	11/19/2014		12		\$0.00
Medium	Work In Progress	Room # 303	11/19/2014 1:13:00 PM				
Marquez,	Gerardo	Martha Martinez/Sped., her doo need to work on it.	r lock was not working,				
Sandra M							
Count: 28	Work Orders	Avg. Age of WO's	30	Total for Mesquit	te ES	0	\$0.00

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Stat Area Deferred By Until Area Number Reason Cr Description	Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	North Va	ley ES					
124765			10/30/2014		32		\$0.00
Medium	Work In Progress	10/30)/2014 7:38:18 AN	1			
Vega, Dar	nny	need exhaust fan motors #303041 and #3048 each 8total	42 /4 of				
Danny Veg	ga						
124925			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress	11/2/	2014 12:35:33 AN	1			
Vega, Dar	ny	Monthly - North Valley ES Exit Sign Insp: Mont Refer to PMschedule details.	nly -				
Margret Vi	llalobos			/ /			
124926			11/2/2014		29		\$0.00
Medium	Work In Progress	11/2/	2014 12:35:33 AN	1			
Vega, Dar		Monthly - North Valley ES Emer Light Test: Mo Refer to PMschedule details.	nthly -				
Margret Vi 125932	llalobos		11/30/2014	12/8/2014	1		\$0.00
					I		φ0.00
Medium Vega, Dar	Work In Progress	Monthly - North Valley ES Exit Sign Insp: Mont Refer to PMschedule details.	/30/2014 12:46:49 nly -	,			
Margret Vi	llalobos						
125335			11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress	11/9/	2014 12:41:31 AM	1			
Vega, Dar	nny	Monthly - North Valley ES Playground Inspectito PMschedule details.	on - Refer				
Margret Vi	llalobos						
123639			10/5/2014		57		\$0.00
Medium	Work In Progress	10/5/	2014 12:43:24 AM	1			
Holguin, A	lfredo	Monthly - North Valley ES - Fire Pump Engine PMschedule details.	- Refer to				
Margret Vi	llalobos						
125930			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress	11	/30/2014 12:46:48	3			
Vega, Dar	ny	Monthly - North Valley ES Emer Light Test: Mo Refer to PMschedule details.	nthly -				
Margret Vi	llalobos						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	North Va	llev ES				
125007		11/2/2014		29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:21 AM		20		φ0.00
Orozco, Da	•	Monthly - North Valley ES - Range Hood Cleaning - Refer to PMschedule details.				
Margret Vi	llalobos					
120341		8/3/2014		120		\$0.00
Medium	Work In Progress	8/3/2014 12:33:42 AM				
Munoz, Mio	chael	Yearly - North Valley ES Fire Ext. Insp. (Yearly) - Refer to PMschedule details.				
Margret Vi	llalobos					
126013		11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:43				
Vega, Dan		Monthly - North Valley ES Monthly FE Inpsection - Refer to PMschedule details.				
Margret Vi	llalobos	44.0.004	4.4.10.10.04.4			.
124991		11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:11 AM				
Vega, Dan		Monthly - North Valley ES Monthly FE Inpsection - Refer to PMschedule details.				
Margret Vi	llalobos		40/44/0044	67		<u> </u>
123679		10/5/2014	10/11/2014	57		\$0.00
Medium	Work In Progress	10/5/2014 12:43:54 AM				
Vega, Dan		Monthly - North Valley ES Monthly FE Inpsection - Refer to PMschedule details.				
Margret Vi	llalobos	10/00/001				
124541		10/23/2014		39		\$0.00
Medium	Work In Progress	10/23/2014 3:48:58 PM				
Carrasco,	Danny	10-23-14 need scissor lift to use for plumbing wk od				
Danny Veç	ga					
125976		11/30/2014		1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:19				
Apodaca,	Mario	Monthly - North Valley ES -Lift Station Inspection - Refer to PMschedule details.				
Margret Vi	llalobos					

Selected Da WOID Priority Assigned	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Total Costs
Location:	North Va	lley ES					
118856			7/1/2014		153		\$0.00
Medium	Work In Progress		7/1/2014 8:39:58 AM				
Ronquillo,	Ruben	(attention ruben ronquillo)progess five broken platform parts 46 1/2 beams-also missing stairs-remo solutoins-safety hazard-please ch parts-(800-585-3131)@progessiv	L x5 1/2 W x3 1/2 H ved by green contractor reck into replacment				
Danny Veg	ga						
123956		Athletic Field	10/9/2014		53		\$0.00
High	Work In Progress		10/9/2014 3:38:52 PM				
Munoz, Mio		play ground has broken platforms replace.	and a slide. need to				
Alfredo Ho	olguin		44/44/0044		47		<u> </u>
125558			11/14/2014		17		\$0.00
Medium	Work In Progress		11/14/2014 9:04:00 AM				
Marquez, (Freezer Door-remove hinges in or and reinstalled.	der to open the door				
Alfredo Ho	olguin						
122505			9/9/2014		83		\$0.00
Medium	Work In Progress		9/9/2014 10:21:14 AM				
Gonzalez,	Salvador	Principal would like to request a m turnaround, like the one at STE.	etal canopyat the bus				
Maria Herr	nandez						
124883			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:08 AM				
Orozco, Da	aniel	Yearly - North Valley ES - Grease schedule details.	Trap - Refer to PM				
Margret Vi	llalobos						
124383			10/21/2014		41		\$0.00
Medium	Work In Progress		10/21/2014 9:58:58 AM				
Villalobos	, David	underground water leak by backfl small plygrd	ow preventer box/by				
Danny Veg	ga						

WOID Priority Assigned ⁻ Requester		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	North Val	lley ES					
121456			8/19/2014		104		\$0.00
Medium	Work In Progress		8/19/2014 3:33:06 PM	1			
Sotelo, En	rique	Ticket No: 2014341177 Seq. N Original Call Date: 08/19/2014 PM OP: 190 Transmit Date: 08/19/2014 PM Work to Begin Date: 08/21/20 PM Company: GADSDEN IND DIST Contact Name: DAVID LOBO (575)882-6913 Alternate Contact: MIKE MUNOZ (575)882-6907 Fax No: (575)882-6945 Email: dwillalobos @gisb.k12.nn State: NM County: DONA AN/ DONA ANA Address: 300 , CASCADE / To Address: Nearest Intersecting Street: OZ/ 2nd Intersecting Street: Subdivision: SAN MIGUEL/ NOR Latitude: 32.14765050 Longitu Zip Code: 88046 Grid: Township: 25S Range: 02E Set Location of Work: FROM INTERS 228, GO S. ON NM-28 FOR APP CASCADE AVE GO APPX 0.25M ON S.SIDE OF ROAD SPOT O THE SCHOOL PROPERTY, 20F AREA MARKED IN WHITE ON TH LOCATED S. OF Remarks: THE LARGE WATER BLDG. Type of Work: REROUTING WAT Private Property: Street: Blasting:	ATÉ ATE est Type: No: 4 4 Time: 01:01:52 4 Time: 01:09:13 14 Time: 12:55:00 EPENDENT SCHOOL S Contact Phone: 2 Alternate Phone: Alternate Phone: 10 A City: RURAL AVE ARK ST RTH VALLEY ELEM. Ide: -106.72130800 ection 1/4: 10 NE S. OF NM-28 & NM- 2X 1MI, L.(E) ON I TO THE SCHOOL ON THE NE.SIDE OF T RADIUS OF THE HE ASPHALT TANK AND PUMP TER LINE Overhead Lines: Boring: Premarked:				

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	North Val	ley ES					
Dominique							
120825		ParkingLot	8/8/2014		115		\$0.00
Medium	Work In Progress	front door area	8/8/2014 12:15:43 PM				
Villalobos,	, David	As per Principal, please install a wa front of the building. Please visit Prin					
Priscilla M	artinez						
125876			11/21/2014		10		\$0.00
Medium	Work In Progress		11/21/2014 3:51:57 PM				
Villalobos,	, David	11-21-14 no hot water in classrm sinks at rio g mechanical rm is out/wont lite-up p					
Danny Veg	ja						
125626			11/17/2014		14		\$0.00
Medium	Work In Progress		11/17/2014 10:41:46				
Solis, Lore		OFFICE UNIT NOT HEATING PLEA NOT RESET	SE CK ASAP/WILL				
Danny Veg	ja		7/10/0011				* 0.00
119269			7/10/2014		144		\$0.00
Medium	Work In Progress		7/10/2014 11:49:44 AM				
Solis, Lore	en zo	circulating pump at rio grand wing m leaking water.model#ks2500ae2 jc 1750 cap 240 gal.please ckeck out a turned off to 6th grade wing	a633m hp10-rpm				
Danny Veg	ja						
125169			11/5/2014		26		\$0.00
Medium	Work In Progress		11/5/2014 11:25:04 AM				
Solis, Lore	enzo	RM 102-NO COOLING THIS IS NE RM/UNIT WILL NOT START.PLEAS					
Danny Veg	ja						
125901			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:28				
Vega, Dan		Monthly - North Valley ES A16 (Fan Refer to PMschedule details.	Exhst)(S.Ann.) -				
Margret Vil	lalobos		44/00/0044	40/04/0044			^
125902			11/30/2014	12/21/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:29				
Vega, Dan	ny Ilalobos	Monthly - North Valley ES H11(E.He Refer to PMschedule details.	eat)(S.Annual) -				

Selected Da WOID Priority Assigned Requester		Dates:7/1/2014 - 1 Area Area Number Description	Deferred By	Until I	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Total Costs
Location:	North Val	ley ES							
122514					9/9/2014		83		\$0.00
Medium	Work In Progress			9/9/20	14 1:47:49 PN	1			
Ontiveros,	, Guadalupe		O.)alarm on spklr ti t out -rain bird mod						
Danny Veg	ga								
123695					10/5/2014		57		\$0.00
Medium	Work In Progress			10/5/201	4 12:44:07 AM	l			
Munoz, Mi	chael	Monthly - North to PMschedule	Valley ES - Fire Sp details.	rinkler Insp R	efer				
Margret Vi	llalobos								
125042					11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress			11/2/201	4 12:36:43 AM	l			
Orozco, Da	aniel	Monthly - North to PMschedule	Valley ES Fire Sup details.	pression Insp.	- Refer				
Margret Vi	llalobos								
Count: 31	Work Orders	A	vg. Age of WO's	45		Total for North Valle	ey ES	0	\$0.00

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loc Area Deferred By Area Number Reason Description		arget Comp Date actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Northern	On-Track Pre-K (LM)					
123558			10/5/2014	10/13/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:42:20 AM				
Vega, Dar	ny	Monthly - La Mesa ES Roof Inpsections schedule details.	on - Refer to PM				
Margret Vi	llalobos						
123511			10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:41:42 AM				
Vega, Dar	nny	Yearly - Northern Prek I4 (Fan Coil)(PMschedule details.	Yearly) - Refer to				
Margret Vi	llalobos						
123512			10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:41:43 AM				
Vega, Dar	ıny	Yearly - Northern Prek H6 (Furnace) PMschedule details.	(Yearly) - Refer to				
Margret Vi	llalobos						
125898			11/30/2014	12/21/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:26				
Vega, Dar	nny	Monthly-Northern Pre-KC12-Chem Refer to PMschedule details.	.Feeder(S.Annual) -				
Margret Vi	llalobos						
125899			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:27				
Vega, Dar		Monthly - Northern Pre-K A16(Fan E Refer to PMschedule details.	xhst)(S. Annual) -				
Margret Vi	llalobos		1.1/00/0011	40/04/0044			.
125900			11/30/2014	12/21/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:28				
Vega, Dar		Monthly - Northern Prek H11(E.Heat to PMschedule details.)(S.Annual) - Refer				
Margret Vi					40		.
125440	Main Building		11/12/2014		19		\$0.00
Medium	Work In Progress		11/12/2014 1:41:32 PM				
Solis, Lore	enzo	NEED BOILER TURNED ON FOR V	VINTER.				
Adam Mor	ntoya						

WOID Priority Assigned Requester		•		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:		On-Track Pre-K (LM)					
125981		1	1/30/2014		1		\$0.00
Medium	Work In Progress	11/30/201	4 12:47:22				
Apodaca,	Mario	Monthly - Northern Pre-K - Monthly Meter Readings - Refer to PMschedule details.					
Margret Vi	llalobos						
125736	Pump House	Lift Station 1	1/19/2014		12		\$0.00
Medium	Work In Progress	11/19/2014 8	8:41:34 AM				
Apodaca,	Mario	need a backup lift pump for the lift station					
Mario Apo	daca						
124990			11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12	2:36:11 AM				
Vega, Dar	nny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PMschedule details.	C				
Margret Vi	llalobos						
126012		1	1/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress	11/30/201	4 12:47:42				
Vega, Dar	ny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PMschedule details.	C				
Margret Vi	llalobos		/= /				
123678			10/5/2014	10/11/2014	57		\$0.00
Medium	Work In Progress	10/5/2014 12	2:43:53 AM				
Vega, Dar	-	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PMschedule details.	C				
Margret Vi	llalobos		0 10 10 0 1 1	0/4.4/0.04.4	4.00		
120356			8/3/2014	8/14/2014	120		\$0.00
Medium	Work In Progress	8/3/2014 12	2:33:53 AM				
Munoz, Mi	chael	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.					
Margret Vi	llalobos						
125931		1	1/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress	11/30/201	4 12:46:49				
Vega, Dar	nny	Monthly - La Mesa ES Emer. Light Test: Monthly - Ref to PM schedule details.	er				
Morarot \/i	llalobos						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Loca Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Northern	On-Track Pre-K (LM)					
125929			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:47				
Vega, Dan	าทy	Monthly - La Mesa ES Exit Sign Insp: PMschedule details.	Monthly - Refer to				
Margret Vi	illalobos						
125336			11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress		11/9/2014 12:41:32 AN	I			
Vega, Dan	-	Monthly - Northern Pre-K Playground schedule details.	Insp - Refer to PM				
Margret Vi	llalobos		40/40/0044	4.0/00/004.4			
124027			10/12/2014	10/28/2014	50		\$0.00
Medium	Work In Progress		10/12/2014 12:28:50				
Vega, Dan	nny	Monthly - Northern Pre-K Playground schedule details.	Insp - Refer to PM				
Margret Vi	llalobos		4.4.10.10.0.4.4				
124927			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:34 AN	l			
Vega, Dan	nny	Monthly - La Mesa ES Exit Sign Insp: PMschedule details.	Monthly - Refer to				
Margret Vi	llalobos						
124928			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:35 AN	l			
Vega, Dan	nny	Monthly - La Mesa ES Emer. Light Te to PM schedule details.	est: Monthly - Refer				
Margret Vi	llalobos		40/5/0044	4.0.14.0.10.0.4.4			
123611			10/5/2014	10/13/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:43:02 AN				
Vega, Dan	-	Monthly - La Mesa ES Emer. Light Te to PM schedule details.	est: Monthly - Refer				
Margret Vi	llalobos			10/10/0011			
123612			10/5/2014	10/13/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:43:02 AN	l			
Vega, Dan	าทy	Monthly - La Mesa ES Exit Sign Insp: PMschedule details.	Monthly - Refer to				
Margret Vi							
Count: 21	Work Orders	Avg. Age of WO's 31	Total for North	ern On-Track Pre-K	(LM)	0	\$0.00

Medium Wor Ronquillo, Ruber 123029 Medium Wor Ronquillo, Ruber Ruben Ronquill 122947 Medium Wor Ronquillo, Ruber Alfredo Holguin 125948	chasing rk In Progress en ez rk In Progress en lo	Plant Complex Office 11/4/2014 11/4/2014 8:16:41 AM Please place a screen on the window of the Instructional Materials Dept. for ventilation. 9/22/2014 9/22/2014 10:05:10 AM PURCHASE 2EA NEW GENIE GS-3246 SCISSOR LIFTS AND 2EA. TILT TRAILERS W/CHAINS AND BINDERS. THANK YOU! 9/18/2014 9/18/2014 8:49:23 AM	27 70	-
Medium Wor Ronquillo, Ruber 123029 Medium Wor Ronquillo, Ruber Ruben Ronquill 122947 Medium Wor Ronquillo, Ruber Alfredo Holguin 125948 Medium Wor	rk In Progress en ez rk In Progress en lo	11/4/2014 8:16:41 AM Please place a screen on the window of the Instructional Materials Dept. for ventilation. 9/22/2014 9/22/2014 10:05:10 AM PURCHASE 2EA NEW GENIE GS-3246 SCISSOR LIFTS AND 2EA. TILT TRAILERS W/CHAINS AND BINDERS. THANK YOU!	70	\$0.00
Ronquillo, Ruber Theresa Ramire 123029 Medium Wor Ronquillo, Ruber Ruben Ronquill 122947 Medium Wor Ronquillo, Ruber Alfredo Holguin 125948 Medium Wor	er ez rk In Progress en lo	Please place a screen on the window of the Instructional Materials Dept. for ventilation. 9/22/2014 9/22/2014 10:05:10 AM PURCHASE 2EA NEW GENIE GS-3246 SCISSOR LIFTS AND 2EA. TILT TRAILERS W/CHAINS AND BINDERS. THANK YOU! 9/18/2014		 \$0.00
Theresa Ramire 123029 Medium Wor Ronquillo, Rube Ruben Ronquill 122947 Medium Wor Ronquillo, Rube Alfredo Holguin 125948 Medium Wor	ez rk In Progress en lo rk In Progress	Materials Dept. for ventilation. 9/22/2014 9/22/2014 10:05:10 AM PURCHASE 2EA NEW GENIE GS-3246 SCISSOR LIFTS AND 2EA. TILT TRAILERS W/CHAINS AND BINDERS. THANK YOU! 9/18/2014		 \$0.00
123029 Medium Wor Ronquillo, Ruber Ruben Ronquill 122947 Medium Wor Ronquillo, Ruber Alfredo Holguin 125948 Medium Wor	rk In Progress en Io rk In Progress	9/22/2014 10:05:10 AM PURCHASE 2EA NEW GENIE GS-3246 SCISSOR LIFTS AND 2EA. TILT TRAILERS W/CHAINS AND BINDERS. THANK YOU! 9/18/2014		\$0.00
Medium Wor Ronquillo, Rube Ruben Ronquill 122947 Medium Wor Ronquillo, Rube Alfredo Holguin 125948 Medium Wor	en Io rk In Progress	9/22/2014 10:05:10 AM PURCHASE 2EA NEW GENIE GS-3246 SCISSOR LIFTS AND 2EA. TILT TRAILERS W/CHAINS AND BINDERS. THANK YOU! 9/18/2014		\$0.00
Ronquillo, Ruber Ruben Ronquill 122947 Medium Wor Ronquillo, Ruber Alfredo Holguin 125948 Medium Wor	en Io rk In Progress	PURCHASE 2EA NEW GENIE GS-3246 SCISSOR LIFTS AND 2EA. TILT TRAILERS W/CHAINS AND BINDERS. THANK YOU! 9/18/2014		
Ruben Ronquill 122947 Medium Wor Ronquillo, Rube Alfredo Holguin 125948 Medium Wor	lo rk In Progress	LIFTS AND 2EA. TILT TRAILERS W/CHAINS AND BINDERS. THANK YOU! 9/18/2014		
122947 Medium Wor Ronquillo, Rube Alfredo Holguin 125948 Medium Wor	rk In Progress		 	
Medium Wor Ronquillo, Rube Alfredo Holguin 125948 Medium Wor	-			
Ronquillo, Rube Alfredo Holguin 125948 Medium Wor	-	0/10/2011/0-2020 11	74	\$0.00
Alfredo Holguin 125948 Medium Wor		9/10/2014 0.49:23 AM		
125948 Medium Wor	en	New Warehouse - need new signs for storage shelving (District Warehouse, General Maintenance, Custodial) check with Mary Sitters and Alfredo on additional signage ie. floor products ects.		
Medium Wor	1			
		11/30/2014	1	\$0.00
Carbaial Jimmy	rk In Progress	11/30/2014 12:47:00		
earbajai, erriny	y	Monthly - Physical Plant - Clothes Dryer (Monthly) - Refer to PMschedule details.		
Margret Villalob	OS			
125627		11/17/2014	14	\$0.00
Medium Wor	rk In Progress	11/17/2014 10:55:37		
Ronquillo, Rube	en	need signs for 'custodial products' for new warehouse as per Alfredo		
Mary Sitters				
124743 Pure	chasing	10/29/2014	33	\$0.00
Medium Wor	rk In Progress	10/29/2014 3:23:09 PM		
Diaz, Sebastian	l	The toilet is overflowing in the men bathroom, water is coming through at the base of the toilet.		
Theresa Ramire	ez			
124950		11/2/2014	29	\$0.00
Medium Wor	rk In Progress	11/2/2014 12:35:47 AM		
Ruiz, Maria		Monthly - PPD - Fueling Station Monthly Inspection - Refer to PMschedule details.		

Selected Da WOID Priority Assigned Requester	Building Status To	•	ate Target Comp Date ne Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex				
125904		11/30/20)14	1		\$0.00
Medium	Work In Progress	11/30/2014 12:4	6:31			
Ruiz, Maria	а	Monthly - PPD - Fueling Station Monthly Inspection - Refer to PMschedule details.				
Margret Vi	llalobos					
121840		8/27/20	014	96		\$0.00
Medium	Work In Progress	8/27/2014 1:12:27	PM			
Miranda, D	Danny	please replace plywood with smart board on training room where a/c was vented. thank you				
Michael M	unoz					
120355		8/3/20)14	120		\$0.00
Medium	Work In Progress	8/3/2014 12:33:52	AM			
Munoz, Mio	chael	Yearly - Physical Plant Fire Ext. Insp. (Yearly) - Refer to PMschedule details.				
Margret Vi	llalobos					<u> </u>
126000		11/30/20		1		\$0.00
Medium	Work In Progress	11/30/2014 12:4	7:34			
Diaz, Seba		Monthly - Physical Plant FE Inspection - Refer to PM schedule details.				
Margret Vil	llalobos	44/0/0				
125005		11/2/20		29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:20	AM			
Diaz, Seba		Monthly - Physical Plant FE Inspection - Refer to PM schedule details.				
Margret Vil	llalobos	0/0/0/	NA 4			<u> </u>
122221		9/3/20		89		\$0.00
Medium	Work In Progress	9/3/2014 7:56:36	AM			
Ronquillo,		ORDER NEW FORKLIFT EXTENSIONS AND NEW WORK PLATFORM FOR NEW FORKLIFT				
Ruben Ro	nquillo					A
122868		9/16/20		76		\$0.00
Medium	Work In Progress	9/16/2014 3:48:24	PM			
Ronquillo,	Ruben	ORDER 4EA. ENGINE DRIVEN WATER PUMPS, WITH HOSES. THANK YOU				
Ruben Ro	nquillo					

	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description	• •	Days Labor Aged Hours	Total Costs
	Plant Complex			
124385	10/21/2014		41	\$0.00
Medium Work In Progress	10/21/2014 10:09:26			
Ronquillo, Ruben	REPAIR ARMSTRONG PUMP FOR STOCK			
Ruben Ronquillo				
124289	10/17/2014		45	\$0.00
Medium Work In Progress	10/17/2014 11:00:18			
Ronquillo, Ruben	ORDER NEW 77" X 10' TRAILER W/RAMP AND HITCH RECEIVER.THANK YOU			
Ruben Ronquillo				
123767	10/7/2014		55	\$0.00
Medium Work In Progress	10/7/2014 7:35:32 AM			
Apodaca, Mario	control panel relayes for the lift pump station			
Mario Apodaca				
125977	11/30/2014		1	\$0.00
Medium Work In Progress	11/30/2014 12:47:19			
Apodaca, Mario	Monthly - PPD/GHS - WW Monthly Sampling - Refer to PMschedule details.			
Margret Villalobos	10/17/2014		45	\$0.00
124274			40	\$0.00
Medium Work In Progress	10/17/2014 7:49:55 AM			
Apodaca, Mario	enzo snake to maintain lift stations and district wide use			
Mario Apodaca	40/04/0044		04	* 0.00
124819	10/31/2014		31	\$0.00
Medium Work In Progress	10/31/2014 12:37:12			
Apodaca, Mario	Monthly - PPD/GHS - WW Monthly Sampling - Refer to PMschedule details.			
Margret Villalobos 121435 Maintenanœ	Mechanical 8/19/2014		104	\$0.00
Medium Work In Progress	8/19/2014 2:21:44 PM		104	φ0.00
Apodaca, Mario	need a high strength epoxy to fill in the hand rail post to			
Mario Apodaca	concrete at the water treatment plant			
125789	Athletic Field 11/20/2014		11	\$0.00
Medium Work In Progress	11/20/2014 8:16:22 AM			
Gonzalez, Salvador	top bar that holds tarp is broken needs to be weld to be able to transport material.			
Guadalupe Ontiveros	•			

12/1/2014 3:28:29 PM

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Request Date Target Comp Date Days Area Deferred By Until Request Date Target Comp Date Days Area Number Reason Created Date/Time Actual Comp Date Aged Description Action Taken	Labor Hours	Costs
Location:	Physical	Plant Complex		
125633		11/17/2014 14		\$0.00
Medium	Work In Progress	11/17/2014 2:08:39 PM		
Solis, Lore	nzo	New Lounge - Need to startup heater.		
Michael Mu	unoz			
122888	Maintenance	9/17/2014 75		\$0.00
Medium	Work In Progress	9/17/2014 8:14:58 AM		
Villalobos,	David	New Lounge - Men's Restroom, urinal is leaking.		
Michael Mu	unoz			
124720	Motor Vehicle	10/29/2014 33		\$0.00
Medium	Work In Progress	10/29/2014 8:23:36 AM		
Marquez, G	Gerardo	COULD YOU PLEASE REPLACE A LOCK ON CABINET IN AUTO SHOP USED FOR CUSTODIAL SUPPLIES IF YOU HAVE ANY QUESTIONS PLEASE CONTACT FERNANDA THE MORNING CUSTODIAN. (2ND REQUEST)		
Jimmy Car	bajal			
122948		9/18/2014 74		\$0.00
Medium	Work In Progress	9/18/2014 8:57:40 AM		
Marquez, G		New Warehouse- Rekey off grand Master - Check with Mike - Alfredo on keying		
Alfredo Ho 125634	Iguin	11/17/2014 14		\$0.00
Medium	Work In Progress	11/17/2014 2:09:32 PM		ψ0.00
	C C			
Ambriz, Jos		New Warehouse - Need to startup heater.		
Alfredo Ho 125503	Food Services	11/13/2014 18		\$0.00
Medium	Work In Progress	11/13/2014 9:32:14 AM		φ0.00
Marquez, G	Ū	Please change key to the SNP key for the office at the SNP Warehouse		
Dominique	e Esparza			
125501	Food Services	11/13/2014 18		\$0.00
Medium	Work In Progress	11/13/2014 9:28:33 AM		
Marquez, G	Ū	Change door knob at the SNP freezer to a class room knob that it can be left unlocked or be locked as needed		

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description	Until Request Date Target C Created Date/Time Actual C		Costs Labor Hours
Location:	Physical	Plant Complex			
125131		Parking Lot	11/4/2014	27	\$0.00
Medium	Work In Progress		11/4/2014 9:14:02 AM		
Ontiveros,	, Guadalupe	New Warehouse- Area west of pa unloading area and north of the ne 2-3 inches of 1/2 to 3/4 inch crush	ew fenced in area- add		
Alfredo Ho	olguin				
123857		Athletic Field	10/8/2014	54	\$0.00
Medium	Work In Progress		10/8/2014 8:43:08 AM		
Flores, Pe	te	Goose neck trialer needs tire replender of the second second second second second second second second second s	ced and rim missing		
Guadalup	e Ontiveros				
125061		Athletic Field	11/3/2014	28	\$0.00
High	Work In Progress		11/3/2014 8:39:27 AM		
Flores, Pe	te	Truck # 39 needs Break Control a Wiring. Also floor Mats and dash			
Guadalup	e Ontiveros				
122443	Motor Vehicle		9/8/2014	84	\$0.00
Medium	Work In Progress	ag trailer	9/8/2014 9:06:23 AM		
Flores, Pe	te	please prepare trailer as required dept.	l for use by agriculture		
Pete Flore					
125418	Motor Vehicle		11/12/2014	19	\$0.00
Medium	Work In Progress	vehicle#159	11/12/2014 8:04:28 AM		
Flores, Pe	te	please check condition of tires,ma	ayneed replacement.		
Pete Flore	es				
125165	Motor Vehicle		11/5/2014	26	\$0.00
Medium	Work In Progress	equip#0423	11/5/2014 9:41:37 AM		
Flores, Pe	te	please check mower #0423 for ar maintenance.	nyrequired		
Pete Flore	es				
125432	Motor Vehicle		11/12/2014	19	\$0.00
Medium	Work In Progress	vehicle#137	11/12/2014 11:13:38		
Flores, Pe	te	vehicle running rough at idle and t ranges . not working on all cylinde			
Pete Flore	es				

WOID Priority Assigned		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester		Plant Complex						
124642				10/27/2014		35		\$0.00
Medium	Work In Progress			10/27/2014 3:34:05 PM				
Flores, Pe	-	Backhoe trailer r	needs new tires					
Pete Flore		Ducharlos d'alleri						
125226	Motor Vehicle			11/6/2014		25		\$0.00
Medium	Work In Progress			11/6/2014 11:12:33 AN	I			
Flores, Pe	-	batteries need to for Johnny Acun		r veh 136 & Steiner DT				
Pete Flore	s							
124843	Motor Vehicle			10/31/2014		31		\$0.00
Medium	Work In Progress	vehicle#58		10/31/2014 2:29:54 PM				
Flores, Pe	te	requesting brake equiped with ele		for towing trailers				
Pete Flore	S							
120665				8/6/2014		117		\$0.00
Medium	Work In Progress			8/6/2014 2:43:32 PN	1			
Flores, Pe		routine service oil (3468 miles)	on truck 38 need	to change the motor				
Mario Apo 119759	daca			7/23/2014		131		\$0.00
Medium	Work In Progress			7/23/2014 2:32:20 PM	1	101		ψ0.00
Flores, Pe	Ū.	MAINTANCE ON SUBMIT INVOIC		IICLES	I			
Margaret \	/illalobos							
125688	Motor Vehicle			11/18/2014		13		\$0.00
Medium	Work In Progress	vehicle#138		11/18/2014 3:01:54 PM				
Flores, Pe	te	please check ca	use of vehicle no	ot starting.				
Pete Flore	s							
125689	Motor Vehicle			11/18/2014		13		\$0.00
Medium	Work In Progress	equip.#0524-		11/18/2014 3:06:04 PM				
Flores, Pe	te	sweeperimplen please check an		ne hoses losing fluid.				
Pete Flore	s							
124450				10/22/2014		40		\$0.00
Medium	Work In Progress			10/22/2014 11:21:12				
Flores, Pe	te	vehicle 01, need on and turned o		eck engine light turned eresa Ortega)				

1257 - WOIR Olders III Flogress (Fiscal Teal)							Total		
WOID	Building	t Dates:7/1/2014 - 11/30/2014 Order By L Area Deferred By Area Number Reason		Until Request Date Target Comp Date			ام م م	Labor Hours	Costs
Priority Assigned	Status	Area Number Description	Reason	Cre	Created Date/Time Actual Comp Date Action Taken			nouro	
Requeste		Description				ACTION TAKEN			
Location:	Physical	Plant Complex							
124250					10/16/2014		46		\$0.00
Medium	Work In Progress			10/16	/2014 3:46:21 PM				
Flores, Pe	ete	vehicle #18 sto	p working; needs n	ew alternato					
Julie Herr	nandez								
124609					10/27/2014		35		\$0.00
Medium	Work In Progress			10/27	/2014 8:38:33 AM				
Flores, Pe	ete	vehicle #118 he (reported by Sh	eadlights do not wo nae Vierra)	rk only high b	eams.				
Maria Rui	Z								
Count: 46	Work Orders	А	vg. Age of WO's	43	Total for F	Physical Plant Com	plex	0	\$0.00

WOID	Building	Area	1/30/2014 Order By Loo Deferred By		e Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Tim	e Actual Comp Date	Aged	Hours	
Assigned		Description			Action Taken			
Requester	r Name							
Location:	Riverside	ES						
124633				10/27/201	4	35		\$0.00
Medium	Work In Progress			10/27/2014 3:17:04 F	М			
Gallegos,	Rafael	10/27/2014. Need TPO roof computer room	above teachers loung #2 looked at for poss	ge and above ible re roofing.				
Mario Mari	tinez							
119633				7/21/201	4	133		\$0.00
Medium	Work In Progress			7/21/2014 10:19:47	М			
Ontiveros,	,Guadalupe		or main irrigation spr ing up. Need assista					
Mario Mar	tinez							
120025				7/30/201	4	124		\$0.00
Medium	Work In Progress			7/30/2014 1:46:51 F	M			
Lara, Ralp	h	Rekeylocks fro (DannyC.has t	m storage bins from I he locks)	DP to RS.				
Michael M	unoz							
124407				10/21/201	4	41		\$0.00
Medium	Work In Progress			10/21/2014 1:30:42 P	Μ			
Lara, Ralp	h	10/21/2014. Need Rafa L. to #76,	o rekey cylinders to o	ff master at room				
Mario Mar	tinez							
119185				7/8/201	4	146		\$0.00
Medium	Work In Progress			7/8/2014 7:28:48 /	M			
Marquez, (Gerardo	7/08/2014. Need Rafa L. to	o fix door lock at libra	ry.				
Mario Mar	tinez							
125696				11/18/201		13		\$0.00
Medium	Work In Progress			11/18/2014 3:30:52 F	Μ			
Ambriz, Jo	se	11/18/2014. Need Jose A. to Units not workir	assistwith filling of b	poilersystems.				
Mario Mari	tinez							

WOID Priority Assigned ⁻ Requester	Building Status To	•	Date Target Comp Date Time Actual Comp Date Action Taken		Labor Hours	Costs
Location:	Riverside	ES				
121093		8/13/	/2014	110		\$0.00
Medium	Work In Progress	8/13/2014 10:09:0	D2 AM			
Ambriz, Jo	se	Need Jose A to check two inside water fountains that are not cooling water.				
Mario Mart	linez					
123033		9/22/	/2014	70		\$0.00
Medium	Work In Progress	9/22/2014 10:24:	19 AM			
Ambriz, Jo	se	9/22/2014. Need Jose A. to check out 4 units, (existing) to see why fan does not come on.				
Mario Mart	linez					
122686			/2014	80		\$0.00
Medium	Work In Progress	9/12/2014 8:17:	14 AM			
Ambriz, Jo	se	check cooling in room 136				
Michael M	unoz					
124880		11/2	/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:	06 AM			
Orozco, Da	aniel	Yearly - Riverside ES - Grease Trap - Refer to PM schedule details.				
Margret Vil	llalobos					
121199		8/14/	/2014	109		\$0.00
Medium	Work In Progress	8/14/2014 2:56:	52 PM			
Ontiveros,	Joe	Need plumber Joe O. to replace sixtiolets in Kinder wing. Rooms #104/101/116/137/126/141, and would like seats changed in rooms #145 and #148.				
Mario Mart	linez					
121838		8/27/	/2014	96		\$0.00
Medium	Work In Progress	8/27/2014 12:58:5	57 PM			
Ontiveros,	Joe	Need plumber Joe O. to fix leaky urinal in boys restroom at north wing.				
Mario Mart	linez	· · · ·	10011			A
125700		11/18,		13		\$0.00
Medium	Work In Progress	11/18/2014 3:36:2	23 PM			
Ontiveros,	Joe	11/18/2014. Need PLUMBER Joe O. to replace 8 inch center faucets in rooms # 117, 141, and 137.				
Mario Mart	linoz					

WOID Priority Assigned 1 Requester		Area Deferred By Area Number Reason Description	Until Request Date Tai Created Date/Time Ac	- · · · · ·	Labor Hours	
Location:	Riverside	ES				
124675			10/28/2014	34		\$0.00
Medium	Work In Progress		10/28/2014 12:04:00			
Martinez, N	lario	10/28/2014. Need to remove several anchore from classroom walls and paint				
Mario Marti	inez					
122842			9/16/2014	76		\$0.00
Medium	Work In Progress		9/16/2014 1:45:43 PM			
Castillo, Ca	arlos	9/16/2014. Need Carlos C. to run wiring to bathroom.	exhaust fan in office			
Mario Marti	inez					
124465			10/22/2014	40		\$0.00
Medium	Work In Progress		10/22/2014 2:54:48 PM			
Castillo, Ca	arlos	10/22/2014. Need Carlos C. to fixelectrical po room.	ower line at Special Ed			
Mario Marti	inez					
124091			10/13/2014	49		\$0.00
Medium	Work In Progress		10/13/2014 3:41:03 PM			
Castillo, Ca	arlos	10/13/2014. Need Carlos C. to check lighting Room # 116.	in new Nurses office			
Mario Marti	inez					
124083		Classroom	10/13/2014	49		\$0.00
Medium	Work In Progress	nurses station	10/13/2014 3:02:00 PM			
Castillo, Ca	arlos	need electrician to check lighting of lights) (martinez)	g in room 116 (two rows			
Rosa Quez	zada					
125498			11/13/2014	18		\$0.00
Medium	Work In Progress		11/13/2014 9:05:14 AM			
Gallegos, F	Rafael	WATER VALVE NEXT TO STOVE TIGHTENED. WATER COMES O ON.SNP MANAGER S.NAVA				
	nzalez					

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2014 - 11/30 Area De Area Number Re Description	ferred By	Until Reques		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	ES							
125443				11/1	2/2014		19		\$0.00
Medium	Work In Progress			11/12/2014 2:42	2:17 PM				
Gallegos, F	Rafael	SERVING LINE- EI HAVE NEUTRAL T REFRIGERATOR.							
Maritza Go	nzalez								
120342				8/	3/2014		120		\$0.00
Medium	Work In Progress			8/3/2014 12:33	3:43 AM				
Munoz, Mic		Yearly - Riverside I PMschedule detail		o. (Yearly) - Refer to					
Margret Vil	lalobos			11	/2/2014	11/8/2014	29		\$0.00
124999							29		\$0.00
Medium Martinez, N	Work In Progress Iario	Monthly - Riverside PMschedule detail		11/2/2014 12:36 Inpsection - Refer to	5:16 AIVI				
Margret Vil	lalobos		0.						
125997				11/3	0/2014	12/6/2014	1		\$0.00
Medium	Work In Progress			11/30/20141	2:47:32				
Martinez, M	lario	Monthly - Riverside PMschedule detail		Inpsection - Refer to					
Margret Vil	lalobos								
125019				11/	/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress			11/2/2014 12:36	5:28 AM				
Orozco, Da	niel	Monthly - Riverside PMschedule detail		od Cleaning - Refer to					
Margret Vil	lalobos			0/0	0/0044				<u> </u>
121876					8/2014		95		\$0.00
Medium	Work In Progress			8/28/2014 7:33	3:04 AM				
Gallegos, F		Warranty Work Ord at rooms #21,25,33		ing at roof and walls and#41.					
Mario Marti	inez				/6/2014		05		¢0.00
125211							25		\$0.00
Medium	Work In Progress			11/6/2014 7:30	j:04 AM				
Estrada, Je	esus	Need carpet remov First need construct then remove and in	tion crew to do	alled in room #15. all construction work					
Mario Marti	inez								

Selected Da WOID Priority Assigned Requester			Deferred By	Until	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	e ES							
119526	Main Building	Classroom			7/17/2014		137		\$0.00
Medium	Work In Progress	Room 17		7/17/20	014 2:21:41 PN	1			
Estrada, J	esus	need tile to be ir	nstalled a.s.a.p. in	room 17 (flaviar	ı)	pending as of 9/29/1	4, p.o. #	141500240)
Rosa Que	zada								
125343					11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress			11/9/201	14 12:41:40 AM	l			
Martinez, N	Mario	Monthly - Rivers schedule details	ide ES Playgrour 3.	nd Insp - Refer t	o PM				
Margret Vi									
121247	Main Building	Classroom			8/15/2014		108		\$0.00
Medium	Work In Progress	nurses station		8/15/201	14 10:30:55 AM				
Martinez, N	Mario		stalled two SECUF with lock and keyfo						
Rosa Que	zada				/= /=				
124969					11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress			11/2/201	14 12:35:58 AM				
Martinez, N		Monthly - Rivers Refer to PMs ch	ide ES Emer. Lig edule details.	ht Test: Monthly	-				
Margret Vi	llalobos				11/2/2014	11/10/2014	29		\$0.00
124970				11/2/20			29		Ф 0.00
Medium	Work In Progress				14 12:35:59 AM				
Martinez, N		Monthly - Rivers PMschedule de	side ES Exit Sign I etails.	Insp: Monthly - F	tefer to				
Margret Vi 124523					10/23/2014		39		\$0.00
Medium	Work In Progress			10/23/20)14 3:19:44 PM				Q 0.00
Martinez, N	•		essor and electric lease purchase fo	chammer drill fo					
Mario Mart	tinez								
125966					11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress			11/30	/2014 12:47:12				
Martinez, N	Mario	Monthly - Rivers Refer to PMsch	ide ES Emer. Lig edule details.	ht Test: Monthly	-				
Margret Vi	llalobos								

1237	ZJI - WOIK OIGEIS III FIOGIESS (FISCAI TEAL)								
Selected Da WOID Priority Assigned Requester		Dates:7/1/2014 - 1 Area Area Number Description	Deferred By	Until	Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	e ES							
125967					11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress			11.	/30/2014 12:47:13	3			
Martinez, I	Mario	Monthly - River PMschedule d	rside ES Exit Sign I letails.	nsp: Monthly	- Refer to				
Margret Vi	illalobos								
125041					11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress			11/2/2	2014 12:36:42 AN	1			
Orozco, Da	aniel	Monthly - River PMschedule d	side ES Fire Supp letails.	ression Insp	Refer to				
Margret Vi	illalobos								
Count: 35	Work Orders	A	Avg. Age of WO's	57		Total for Riversion	le ES	0	\$0.00

		5	•	/				Total
te Range for Request Building	Dates:7/1/2014 - 1 Area	1/30/2014 Order By Deferred By	Location, State Until		Target Comp Date	Days	Labor	Costs
Status	Area Number	Reason	Cr	eated Date/Time	Actual Comp Date	Aged	Hours	
То	Description				Action Taken			
Name								
RTC - Alli	ance							
	Portables			10/23/2014		39		\$0.00
Work In Progress			10	/23/2014 12:17:58	3			
Fernando	securitywindo	ws keep opening s		•				
gado								
Vork Orders	Α	vg. Age of WO's	39		Total for RTC - Alli	ance	0	\$0.00
	Building Status To Name RTC - Alli Work In Progress Fernando	BuildingAreaStatusArea NumberToDescriptionNamePoscriptionRTC - AlliancePortablesWork In ProgressPortablesFernandoNeed light bulb security window maintaing safegadoSecurity window	Building Area Deferred By Status Area Number Reason To Description Name Portables Work In Progress Portables Fernando Need light bulbs changed in the or security windows keep opening smaintaing safety egress gado	Building Area Deferred By Until Status Area Number Reason Crophysics To Description Crophysics Crophysics Name Portables Portables 10 Work In Progress 10 Need light bulbs changed in the office. Fire esc security windows keep opening secure locks with maintaing safety egress gado gado 10	Status Area Number Reason Created Date/Time To Description Name RTC - Alliance Portables Portables 10/23/2014 Work In Progress 10/23/2014 12:17:58 Fernando Need light bulbs changed in the office. Fire escape security windows keep opening secure locks while maintaing safety egress gado gado	Building Area Deferred By Until Request Date Target Comp Date Status Area Number Reason Created Date/Time Actual Comp Date To Description Action Taken Name Portables 10/23/2014 Work In Progress 10/23/2014 12:17:58 Fernando Need light bulbs changed in the office. Fire escape security windows keep opening secure locks while maintaing safety egress gado Status	Building Status Area Area Number Area Number Name Deferred By Reason Until Until Request Date To Created Date/Time Actual Comp Date Action Taken Days Aged To Description Action Taken Action Taken<	Building Status Area Area Number Description Deferred By Reason Until Until Created Date/Time Actual Comp Date Action Taken Days Aged Labor Hours To Description Action Taken Action

WOID	Building	Dates:7/1/2014 - 11/30/2014 Order By Loca Area Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description		Action Taken			
Requester	r Name						
Location:	San Migu	el ES					
124977			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:03 AN	1			
Apodaca,	Mario	Monthly - San Miguel ES - Lift Station to PM schedule details.	Inspection - Refer				
Margret Vi	llalobos						
125984			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:24	L			
Apodaca,	Mario	Monthly - San Miguel ES - Lift Station to PMschedule details.	Inspection - Refer				
Margret Vi	llalobos						
125059			11/3/2014		28		\$0.00
Medium	Work In Progress		11/3/2014 8:30:43 AN	1			
Solis, Lore	enzo	11-3-14 water leak at boiler at sme /on circulat 1/2 copper lines to gauges	ng pumps also on				
Danny Veg	ga						
125060			11/3/2014		28		\$0.00
Medium	Work In Progress		11/3/2014 8:32:54 AN	1			
Villalobos	, David	11-3-14 water leak on main water supplyline to boiler/on outside wall	o main bldg in				
Danny Veg	ga						
125715			11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 3:48:01 PM	l			
Ontiveros,	, Guadalupe	As per discussion please clean groun	ds.				
Michael M	lunoz						
Count: 5 W	Vork Orders	Avg. Age of WO's 20		Total for San Migu	el ES	0	\$0.00

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa ES					
125686	Main Building	Office	11/18/2014		13		\$0.00
Medium	Work In Progress	frontmain	11/18/2014 2:48:18 PM				
Ambriz, Jos	se	Need to check heating unit in fro properly	ont office not working				
Juan Ambi	riz						
125749	Main Building	Portables	11/19/2014		12		\$0.00
Medium	Work In Progress	D-054	11/19/2014 12:13:50	1			
Ambriz, Jos	se	Need to repair heating unit in por	table not working				
Juan Ambi	riz						
125550	Main Building	Computer Lab	11/14/2014		17		\$0.00
Medium	Work In Progress		11/14/2014 7:45:48 AN	I			
Ambriz, Jos	se	Need HVAC TECH to check hea	ting unit in computer lab				
Juan Ambi	riz						
124876			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:04 AN	I			
Orozco, Da	niel	Yearly - Santa Teresa ES - Grea schedule details.	se Trap - Refer to PM				
Margret Vil	lalobos						
123501			10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:41:35 AN	l			
Ambriz, Jua		Yearly - Santa Teresa ES-U2 He to PMschedule details.	at Gas (Yearly) - Refer				
Margret Vil	lalobos		0/00/0044				.
123380			9/30/2014		62		\$0.00
Medium	Work In Progress		9/30/2014 12:51:25 AN				
Ambriz, Jua		Monthly - Santa Teresa ES-A-16 Refer to PMschedule details.	Fan Exhaust (SemiA) -				
Margret Vil	lalobos		11/12/2014		19		\$0.00
125429					19		φ 0. 00
Medium	Work In Progress		11/12/2014 10:23:41				
Ambriz, Jua		PAINT ON WINDOWS ABOVE S SNP MANAGER MARINA R. 589					
Maritza Go	nzalez		4 4 100 100				.
125891			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:21				
Ambriz, Jua		Monthly - Santa Teresa ES C-4 (to PMschedule details.	Quarterly MSS - Refer				
Margret Vil	lalobos						

WOID Priority Assigned Requester		Area Area Number Description	Deferred By	Until F	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa ES							
125840	Main Building	Computer Lab			11/21/2014		10		\$0.00
Medium	Work In Progress	New Computer		11/21/20	14 9:25:24 AM				
Castillo, C	arlos		uter lab will need 2 c 8 tables). Thank y		outer				
Rita Mend	ez								
124302		Electrical Room	1		10/17/2014		45		\$0.00
Medium	Work In Progress			10/17/20	14 2:58:32 PM				
Castillo, C	arlos		rical room.Inspecte exhaust fan not wor						
Carlos Ca	stillo				44/5/0044				.
125153		Parking Lot			11/5/2014		26		\$0.00
Medium	Work In Progress	outsidelights		11/5/20	14 8:05:29 AM				
Castillo, C		Need to repair of while throwing of the second s	outside lights too da out trash	irk for custodian	S				
Juan Amb	riz				44/0/2044	44/05/0044			¢0.00
125341					11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress				4 12:41:38 AM				
Ambriz, Ju		Monthly - Santa PMschedule de	Teresa ES Playgro etails.	ound Insp - Ref	er to				
Margret Vi	llalobos				9/26/2014		66		\$0.00
123325				0/00/00			00		φ 0. 00
Medium	Work In Progress				14 3:48:47 PM	I			
Orozco, Da			OR SIDE OF STAND AGER MARINA R. 5						
Maritza Go	onzalez				10/21/2014		41		\$0.00
124391							41		Ф 0.00
Medium	Work In Progress				2014 10:54:28				
Orozco, Da			ANCE-FLOOR IS L RINA R. 589.3436	IFTING. SNP					
Maritza Go	onzalez				/ /				
126004					11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress			11/30/	2014 12:47:37				
Ambriz, Ju	an	Monthly - Santa Refer to PMsch	Teresa ES Monthl edule details.	y FE Inspection	-				
Margret Vi	llalobos								

Location:	Name	Description	Created Date/Time	Action Taken	Aged	Hours	
105000	Santa Te	resa ES					
125002			11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:18 AM				
Ambriz, Jua	In	Monthly - Santa Teresa ES Monthly FE I Refer to PMschedule details.	nspection -				
Margret Villa	alobos						
125848			11/21/2014		10		\$0.00
Medium	Work In Progress		11/21/2014 2:28:51 PM				
Munoz, Mich	nael	need new fencing with gates to prevent s going into parking lots	students from				
Juan Ambri	Z			1.1.100.100.1.1			
125020			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:29 AM				
Orozco, Dar		Monthly-Santa Teresa ES Range Hood Refer to PMschedule details.	Cleaning -				
Margret Villa	alobos		0/0/0044		100		
120343			8/3/2014		120		\$0.00
	Work In Progress		8/3/2014 12:33:43 AM				
Munoz, Mich		Yearly - Santa Teresa ES Fire Ext. Insp. to PMschedule details.	(Yearly) - Refer				
Margret Villa	alobos		10/15/2014		47		¢0.00
124169			10/15/2014		47		\$0.00
Medium	Work In Progress		10/15/2014 8:37:24 AM				
Ambriz, Jua	in	Need to replace sink faucet in adults res	troom				
Juan Ambri	Z			/ /			
124907			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:22 AM				
Ambriz, Jua	IN	Monthly - Santa Teresa ES Emer Light Refer to PMschedule details.	Test: Monthly -				
Margret Villa	alobos						A
124908			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:23 AM				
Ambriz, Jua Margret Villa		Monthly - Santa Teresa ES Exit Sign Ins Refer to PMschedule details.	sp: Monthly -				

WOID Priority Assigned 1		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester								
Location:	Santa Te	resa ES						
124909				11/2/2014		29		\$0.00
Medium	Work In Progress			11/2/2014 12:35:23 AN	1			
Ambriz, Jua	an	Monthly - Santa Refer to PMsch		es Dryer (Monthly) -				
Margret Vill								
124145	Main Building	Classroom		10/14/2014		48		\$0.00
Medium	Work In Progress	Room #304		10/14/2014 3:03:02 PN				
Ambriz, Jua	an	Need to replace	sink faucet in roor	n #304(leaking water)				
Juan Ambr	iz							
122592	Main Building	Classroom		9/10/2014		82		\$0.00
Medium	Work In Progress	allclassrooms		9/10/2014 3:26:31 PM	1			
Ambriz, Jua	an	Need to Install f	lags in class rooms					
Juan Ambr	iz							
121732	Main Building	Classroom		8/25/2014		98		\$0.00
Medium	Work In Progress	Portable #C-05	3	8/25/2014 3:00:38 PM	1			
Ambriz, Jua	an	Need to replace	blinds in portable					
Juan Ambr								
125791	Main Building	Classroom		11/20/2014		11		\$0.00
Medium	Work In Progress	Room #206		11/20/2014 8:31:30 AN	1			
Ambriz, Jua		Need to replace	e sink faucets in roo	um #206				
Juan Ambr								
121851	Main Building	Office		8/27/2014		96		\$0.00
Medium	Work In Progress	main office		8/27/2014 3:10:20 PM	1			·
Ambriz, Jua	-		ooling unit in front					
Juan Ambr	iz	property						
124144	Main Building	Cafeteria		10/14/2014		48		\$0.00
Medium	Work In Progress	Restroom		10/14/2014 3:01:07 PN				
Ambriz, Jua	an	Need to replace	sink faucet in kitch	nen's restroom				
Juan Ambr								
125961	12			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress			11/30/2014 12:47:09				
Ambriz, Jua		Monthly - Santa Refer to PMsch		Light Test: Monthly -				
Margret Vill	lalobos							

Assigned To Requester I Location: 125962 Medium Ambriz, Jua Margret Villa 125959 Medium	Name Santa Ter Work In Progress		Teresa ES Exit Sig edule details.				 \$0.00
Location: 125962 Medium Ambriz, Jua Margret Villa 125959	Santa Ter Work In Progress In alobos	Monthly - Santa		11/30/2014 12:47: gn Insp: Monthly -		l 1	 \$0.00
125962 Medium Ambriz, Jua Margret Villa 125959	Work In Progress In alobos	Monthly - Santa		11/30/2014 12:47: gn Insp: Monthly -		i 1	\$0.00
Medium Ambriz, Jua Margret Villa 125959	alobos			11/30/2014 12:47: gn Insp: Monthly -		k 1	\$0.00
Ambriz, Jua Margret Villa 125959	alobos			gn Insp: Monthly -	10		
Margret Villa 125959	alobos						
125959							
	Work In Progress						
Medium	Work In Progress			11/30/201	4	1	\$0.00
Wearan				11/30/2014 12:47:	07		
Ambriz, Jua	in	Monthly - Santa Refer to PMsch		es Dryer (Monthly) -			
Margret Villa	alobos						
123815	Main Building			10/7/201	4	55	\$0.00
Medium	Work In Progress	allbuilding		10/7/2014 2:26:32 F	M		
Ambriz, Jua	in	Need to replace	e filters in all cooling	g and heating units			
Juan Ambri	z						
125809	Main Building	Restroom		11/20/201	4	11	\$0.00
Medium	Work In Progress	Casa roja 300		11/20/2014 2:58:53 P	М		
Ambriz, Jua	in	Need to replace	hand dryers in boy	<i>i</i> s restrom			
Juan Ambri	z						
125043				11/2/201	4 11/23/2014	l 29	\$0.00
Medium	Work In Progress			11/2/2014 12:36:43 A	M		
Orozco, Dar	niel	Monthly-Santa Refer to PMsch	Teresa ES Fire Sup edule details.	opression Insp			
Margret Villa	alobos Vork Orders				Total for Santa Ter		

WOID Priority Assigned Requester		Area Deferred B Area Number Reason Description	y Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa HS					
125044			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:44 AM				+
Orozco, Da	0	Monthly-Santa Teresa HS Fi Refer to PMschedule details					
Margret Vi	llalobos						
119124			7/6/2014	8/6/2014	148		\$0.00
Medium	Work In Progress		7/6/2014 12:30:34 AM				
Mijarez, Ja	aime	Yearly - Santa Teresa HS Er Refer to PMschedule details					
Margret Vi	llalobos						
119125			7/6/2014	8/6/2014	148		\$0.00
Medium	Work In Progress		7/6/2014 12:30:34 AM				
Mijarez, Ja		Yearly - Santa Teresa HS Ex to PMschedule details.	it Sign Test: Annual - Refer				
Margret Vi	llalobos		4.0/5/0044	10/00/0011			
123691			10/5/2014	10/26/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:44:03 AM				
Munoz, Mi		Monthly - Santa Teresa HS F to PMschedule details.	Fire Sprinkler Insp Refer				
Margret Vi			40/00/0044				
124792	Main Building	Athletic Field	10/30/2014		32		\$0.00
Medium	Work In Progress	football field	10/30/2014 3:49:56 PM				
Munoz, Mi	chael	Football/soccer score board Scoreboard is about 21 years					
Loraine S	oriano		/= /=				
123596			10/5/2014		57		\$0.00
Medium	Work In Progress		10/5/2014 12:42:50 AM				
Mijarez, Ja	aime	Monthly - Santa Teresa HS - Refer to PMschedule details					
Margret Vi							
123220	Main Building	Library	9/25/2014		67		\$0.00
Medium	Work In Progress	library	9/25/2014 8:26:27 AM				
Mijarez, Ja	aime	Air conditioning in office need not working	ds to be looked at as it is				
Loraine S	oriano						

Selected Da WOID Priority Assigned	te Range for Request Building Status To	Dates:7/1/2014 - 1 Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	Name							
Location:	Santa Te	resa HS						
119430	Concession	Athletic Field		7/15/2014		139		\$0.00
Medium	Work In Progress			7/15/2014 11:48:16 AM	1			
Mijarez, Ja	ime	Holes in conce exposed coppe		r water fountain have				
	Rodriguez							
122803	Cafeteria (2005)	Auditorium		9/15/2014		77		\$0.00
Medium	Work In Progress	Theater area		9/15/2014 4:14:10 PN	1			
Mijarez, Ja	ime	Workshop light	s, restroom not wo	rking				
Loraine So	oriano							
121267	Main Building	Classroom		8/15/2014		108		\$0.00
Medium	Work In Progress	608		8/15/2014 2:08:18 PN	1			
Mijarez, Ja	ime	Anchor cabinet	S					
Loraine So	oriano							
121272	Main Building	Classroom		8/15/2014		108		\$0.00
Medium	Work In Progress	206		8/15/2014 2:15:43 PM	1			
Mijarez, Ja	ime	Remove old wh	nite board and old s	creen				
Loraine So	oriano							
123084	Main Building	Classroom		9/23/2014		69		\$0.00
Medium	Work In Progress	Lab C-1		9/23/2014 3:16:04 PM	1			
Mijarez, Ja	ime	Cabinetdoorir	computer lab offic	e in broken.				
Loraine So	oriano							
124222				10/16/2014		46		\$0.00
Medium	Work In Progress			10/16/2014 7:56:45 AM	1			
Mijarez, Ja	ime	teacher. The a	cooling in the after ′c motor gave out. ullyand clamps to	l will need a new 3/4				
Jaime Mija	arez							
124906				11/2/2014		29		\$0.00
Medium	Work In Progress			11/2/2014 12:35:21 AM	1			
Mijarez, Ja	ime	Monthly - Santa Refer to PMsch		nes Dryer (Monthly) -				
Margret Vi	llalobos							
122072				8/31/2014		92		\$0.00
Medium	Work In Progress			8/31/2014 12:54:14 AM	1			
Mijarez, Ja		Monthly - Santa Refer to PMsch		nes Dryer (Monthly) -				
Margret Vil	llalobos							
0/4/004 4	3.28.30 PM						Page 1	

12/1/2014 3:28:30 PM

	te Range for Request Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description	Location, Status	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Total Costs
Location:	Santa Te	resa HS					
120624	Gymnasium	Restroom	8/6/2014		117		\$0.00
Medium	Work In Progress	soccerlocker	8/6/2014 9:19:21 AM				
Mijarez, Ja	ime	Missing toilet seat in one of the sta	alls				
Loraine So	oriano						
125687			11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 3:00:31 PM				
Ronquillo,		window at double door to locker ro broken. glass measures 25 1/4" > has the wire in the glass.					
David Esc		0	0/11/0011				.
122642	Main Building	Classroom	9/11/2014		81		\$0.00
Medium	Work In Progress		9/11/2014 11:25:53 AM				
Flores, Pe	te	Need warehouse pick up golf cart High School, need to check the b tires.					
Irene Herr	era						
125606			11/15/2014		16		\$0.00
Medium	Work In Progress		11/15/2014 12:45:35				
Flores, Pe	te	Yearly - Santa Teresa HS - Mowe Refer to PMschedule details.	r 0425 - Grounds -				
Margret Vil							
124455	Main Building	Classroom	10/22/2014		40		\$0.00
Medium	Work In Progress	314	10/22/2014 12:30:35				
Mijarez, Ja	ime	Map strips need center screws, P Thornly for further clarification	lease refer to Ms.				
Loraine So							
124131	Main Building	Classroom	10/14/2014		48		\$0.00
Medium	Work In Progress	509	10/14/2014 10:21:33				
Mijarez, Ja	ime	replace ceiling tile					
Loraine So							
124299	AnnexBuilding	Classroom	10/17/2014		45		\$0.00
Medium	Work In Progress	culinaryarts	10/17/2014 12:25:41				
Mijarez, Ja	ime	Lockers need to be moved to clas mounted if possible. Please see clarification.					
Loraine So	oriano						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS					
124301	Main Building	Classroom	10/17/2014		45		\$0.00
Medium	Work In Progress	209	10/17/2014 2:45:48 PM				
Mijarez, Ja	ime	Needs a safetygoggle sanitation ca classroom. There might be a possi maybe required for this cabinet. Ple for further information and placeme	bilitythat an outlet ease see Mrs. Nunez				
Loraine So							
120179	Main Building	Classroom	8/1/2014		122		\$0.00
Medium	Work In Progress	505	8/1/2014 11:56:03 AM				
Mijarez, Ja	ime	Replacepencilsharpner					
Loraine So	oriano						
124096	Main Building	Office	10/13/2014		49		\$0.00
Medium	Work In Progress	Training room	10/13/2014 3:46:12 PM				
Mijarez, Ja	ime	Mr. Munozneeds assistance with s see mr. Munoz for further clarificati					
Loraine So	oriano						
125949			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:01				
Mijarez, Ja	ime	Monthly - Santa Teresa HS -Clothe Refer to PMschedule details.	es Dryer (Monthly) -				
Margret Vi	llalobos						
123632			10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:43:19 AM				
Escobar, [David	Monthly - Santa Teresa HS Bleach to PMschedule details.	er Inspection - Refer				
Margret Vi	llalobos						
125926			11/30/2014	12/31/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:45				
Escobar, [David	Monthly - Santa Teresa HS Bleach to PMschedule details.	er Inspection - Refer				
Margret Vi	llalobos						
125927			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:46				
Escobar, [David	Monthly - Santa Teresa HS Exit Sig Refer to PMschedule details.	n Insp: Monthly-				
Margret Vi	llalobos						

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		resa HS					
125928			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:47				
Escobar, I	David	Monthly - Santa Teresa HS Emer Refer to PMschedule details.	Light Test: Monthly -				
Margret Vi	illalobos						
124942			11/2/2014	12/3/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:43 AN	1			
Escobar, I	David	Monthly - Santa Teresa HS Bleac to PMschedule details.	her Inspection - Refer				
Margret Vi	illalobos						
124943			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:43 AN	1			
Escobar, [David	Monthly - Santa Teresa HS Exit S Refer to PMschedule details.	ign Insp: Monthly-				
Margret Vi	illalobos						
124944			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:44 AN	1			
Escobar, I	David	Monthly - Santa Teresa HS Emer Refer to PMschedule details.	Light Test: Monthly -				
Margret Vi			- / / / / / / / / / /				
123304	Main Building	Classroom	9/26/2014		66		\$0.00
Medium	Work In Progress	215	9/26/2014 2:17:29 PM	1			
Mijarez, Ja	aime	Have mice in class room					
Loraine S	oriano						
119429	Cafeteria (2005)	Cafeteria	7/15/2014		139		\$0.00
Medium	Work In Progress		7/15/2014 11:10:21 AN	1			
Escobar, I	David	Several cracked, broken or missir area and dining area around stag					
Rosalinda	a Rodriguez						
120185	Main Building	Classroom	8/1/2014		122		\$0.00
Medium	Work In Progress	mainbuilding	8/1/2014 12:28:03 PM	1			
Escobar, I	David	Several classrooms leaking. Plea determine locations	ase see me for map to				
Loraine S							
120466	Main Building	Classroom	8/4/2014		119		\$0.00
Medium	Work In Progress	507	8/4/2014 2:40:28 PM	1			
Escobar, I	David	Install pencil sharpner					
Loraine S	oriano						
10/1/201/	4 3:28:30 PM					Page 1	58 of 195

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS					
124118	Main Building	Classroom	10/14/2014		48		\$0.00
Medium	Work In Progress	312	10/14/2014 8:19:40 AM				
Escobar, D	David	Need a pencil sharpner installed					
Loraine So	oriano						
123684			10/5/2014	10/11/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:43:58 AM				
Mijarez, Ja		Monthly - Santa Teresa HS Mont Refer to PMschedule details.	hly FE Inspection -				
Margret Vil	llalobos		8/31/2014	9/6/2014	92		\$0.00
122125					92		Ф 0.00
Medium Mijarez, Ja	Work In Progress ime	Monthly - Santa Teresa HS Montl Refer to PMschedule details.	8/31/2014 12:54:48 AM hly FE Inspection -				
Margret Vil	llalobos						
125001			11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:17 AM				
Mijarez, Ja	ime	Monthly - Santa Teresa HS Mont Refer to PMschedule details.	hly FE Inspection -				
Margret Vi					- 10		.
125519	AnnexBuilding	Classroom	11/13/2014		18		\$0.00
Medium	Work In Progress	portable 2	11/13/2014 2:07:26 PM				
Lara, Ralp		door doesn't lock appropriately					
Loraine So	oriano	Athlatia Field	7/10/2014		100		¢0.00
119578		Athletic Field	7/18/2014		136		\$0.00
High Ontiveros,	Work In Progress Guadalupe	need to line locate along pinetree gas lines. any? rick will assit	7/18/2014 12:51:51 PM es.anysewer line and				
Guadalup	e Ontiveros	gas mestany : nek win assit					
119584		Athletic Field	7/18/2014		136		\$0.00
Medium	Work In Progress		7/18/2014 1:44:53 PM	I			
Ontiveros,	Guadalupe	JD tractor 3005 clutch needs to be	e replaced.				
	e Ontiveros		·				
125021			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:30 AM				
Orozco, Da	aniel	Monthly-Santa Teresa HS Range Refer to PMschedule details.	e Hood Cleaning -				
Margret Vil	llalobos						
	2.20.20 DM						

WOID Priority Assigned Requester		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa HS						
120353				8/3/2014		120		\$0.00
Medium	Work In Progress			8/3/2014 12:33:50 AM				
Munoz, Mi	chael	Yearly - Santa to PMschedule		Insp. (Yearly) - Refer				
Margret Vi	llalobos							
120628		Athletic Field		8/6/2014		117		\$0.00
Medium	Work In Progress	Shot put		8/6/2014 9:28:16 AM				
Ontiveros	, Guadalupe			e is there. Crucial for ano or Ms. Noughes.				
Loraine S	oriano							
126003				11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress			11/30/2014 12:47:36				
Mijarez, Ja	aime	Monthly - Santa Refer to PMsch	a Teresa HS Monthl nedule details.	yFE Inspection -				
Margret Vi	llalobos							
124074				10/13/2014		49		\$0.00
Medium	Work In Progress			10/13/2014 1:10:14 PM				
Gonzalez,	Salvador		cage for a window u e BM2 for specs.	nit to be installed in				
David Esc								
124793	Main Building	Athletic Field		10/30/2014		32		\$0.00
Medium	Work In Progress	softball		10/30/2014 3:50:48 PM				
Gonzalez,		In need of battir to Mr. Munoz.	ng cages, dimensio	ns have been emailed				
Loraine S	oriano	Athletic Field		0/0/0044		447		<u> </u>
120627		Athletic Field		8/6/2014		117		\$0.00
Medium	Work In Progress	Baseball		8/6/2014 9:26:03 AM				
Gonzalez,			needed in baseball a noz on infrastructure	area. Email previously of batting cages.				
Loraine S	Main Building	Auditorium		10/17/2014		45		\$0.00
124291	-					40		φ 0. 00
Medium	Work In Progress	Basketball		10/17/2014 11:31:42				
Lara, Ralp	bh	Door is falling o	offhinges					
Loraine S	oriano							

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS					
124298	Main Building	Classroom	10/17/2014		45		\$0.00
Medium	Work In Progress	215	10/17/2014 12:24:15				<i>QU</i> .UU
Lara, Ralpl	Ū	Bathroom door and front class room		,			
Loraine Sc	oriano						
125684	Main Building	Office	11/18/2014		13		\$0.00
Medium	Work In Progress	MARYLOU	11/18/2014 2:39:18 PN	1			
Gonzales,	Camilo	PLEASE DELIVER THE FOLLOWI MARYLOU	NG ITEM TO:				
		PO # 141500415 - 1BAG (UNIFOR	RMS) - STHS TRACK				
Terry Alvar	ado		-,				
125735			11/19/2014		12		\$0.00
Medium	Work In Progress	K. Arambasic	11/19/2014 8:38:15 AM	1			
Gonzales,	Camilo	Pick up gait trainer, swing and old r and a bike from Mr. Arambasik's cla to Physical therapists storage porta Julie or Margaret for the key to the	ssroom and deliver able in Anthony. See				
Margaret V	/illalobos						
124085			10/13/2014		49		\$0.00
Medium	Work In Progress		10/13/2014 3:17:01 PN	1			
Orozco, Da	aniel	DISHWASHER MACHINE (NO PO	WER).				
Maritza Go	nzalez						
124086			10/13/2014		49		\$0.00
Medium	Work In Progress		10/13/2014 3:18:16 PN	1			
Orozco, Da	aniel	OVEN IS NOT WORKING SNP MA 589.5332	NAGER OLGA B.				
Maritza Go	nzalez						
122098			8/31/2014		92		\$0.00
Medium	Work In Progress		8/31/2014 12:54:31 AN	1			
Sanchez, F		Monthly - Santa Teresa HS-Greas Refer to PMschedule details.	e Trap (Cul/Auto) -				
Margret Vil	lalobos		44/47/0044		4.4		<u> </u>
125616			11/17/2014		14		\$0.00
Medium	Work In Progress		11/17/2014 9:28:11 AM	1			
Castillo, C	arlos	Science Room 515 - Check electric tables make sure the power is work workstations.					
Alfredo Ho	lauin						

WOID Priority Assigned	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description	Until Request Date Target C Created Date/Time Actual C	· · · · ·	Costs Labor Hours
Location:	Santa Te	resa HS			
125617			11/17/2014	14	\$0.00
Medium	Work In Progress		11/17/2014 9:28:59 AM		
Castillo, C	carlos	Science Room 511 - Check electri tables make sure the power is wo workstations.			
Alfredo Ho	olguin				
125618			11/17/2014	14	\$0.00
Medium	Work In Progress		11/17/2014 9:29:24 AM		
Castillo, C	carlos	Science Room 508 - Check electri tables make sure the power is wo workstations.			
Alfredo Ho	olguin				
120024			7/30/2014	124	\$0.00
Medium	Work In Progress		7/30/2014 12:57:15 PM		
Castillo, C	arlos	Grounds shop. Install electrical fo	rnew a/cinstallation.		
Jaime Mija	arez				
122487			9/9/2014	83	\$0.00
Medium	Work In Progress		9/9/2014 8:35:24 AM		
Castillo, C	arlos	ACADEMY FENCE JOE COCA - (575)523-0779			
		FROM INTERS. OF MCNUTT RD HWY (NM-136), GO S. ON MCNU 2MI, R.(W) ON AIRPORT RD GO HIGH SCHOOL SPOT ON THE E.SIDE OF THE F AREA BETWEEN THE TRACK AN BLEECHERS.	ITT RD FOR APPX APPX 0.5MI TO THE OOTBALL FIELD,		
Alfredo Ho	<u> </u>				
125179	Main Building	Classroom	11/5/2014	26	\$0.00
Medium	Work In Progress	313 romero	11/5/2014 1:59:31 PM		
Castillo, C	arlos	half the lights in class room do not	function		
Loraine So					
125409	AnnexBuilding	Classroom	11/10/2014	21	\$0.00
Medium	Work In Progress	culinary	11/10/2014 4:25:12 PM		
Castillo, C	arlos	Dryer has not been hooked			
Loraine So	oriano				

Location: Santa Teresa HS 121961 Vocational Parking Lot 8/29/2014 94 Medium Work In Progress 8/29/2014 8:03:16 AM 94 Castillo, Carlos As per security dept. Several parking lotlights and vocational building lights are not turning on. 711/13/2014 18 Carlos Castillo 125518 Main Building Exterior 11/13/2014 2:06:40 PM 18 Castillo, Carlos Several lights are not working in parking area 20:06:40 PM 3 Loraine Soriano 11/14/2014 2:51:00 PM 11/17/2014 3 Veriane Soriano 11/14/2014 2:51:00 PM 11/17/2014 42 124325 Football Field 10/20/2014 42 Veriane Soriano 124325 Football Field 10/20/2014 42 Veriance Soriano 124325 Football Field 10/20/2014 42 Veriance Soriano 124325 Football Field 10/20/2014 42 Veriance Soriano 124325 Verianse Soriano 32 124301 Main Building Ahletic Field 10/20/2014 32 Rafael Callegos 7/13/2014	WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By Reason		-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
121961VocationalParking Lot8/29/20149/4MediumWork In Progress8/29/2014 8:03:16 AM9/4Castillo, CarlosAs per security dept, Several parking tot lights and vocational building lights are not turning on.5/29/2014 8:03:16 AMCarlos Castillo11/13/201418MediumWork In Progresslightoutside in11/13/2014 2:06:40 PMCastillo, CarlosSeveral lights are not working in parking area5/29/2014Loraine Soriano11/14/2014 2:06:40 PM3MediumWork In Progressflag pole11/14/2014 2:51:00 PMMediumWork In Progressflag pole11/14/2014 2:51:00 PM11/17/2014Castillo, CarlosFlag pole pulley is broken, will need bucket truck.10/20/201442Loraine Soriano10/20/20144242MediumWork In ProgressFootball Field10/20/201442MediumWork In ProgressCheck the STHS football field lights. There was an issue with them on Friday. Maybe a problem with a breaker. For information talk to Jamie. Thanks.22Rafael Gallegos10/30/2014 3:58:07 PM22Loraine Soriano10/30/2014 3:58:07 PM22Sociano7/13/20148/13/2014141MediumWork In Progresssottball10/30/2014 3:58:07 PMEscobar, DavdNeed some painting done, please see Ms. Contreras for specifications.7/13/20148/13/2014Loraine Soriano11/13/2014 1/13/2014 1/14/14/14/14/14/14/14/14/14/14/14/14/14	•		resa HS							
Medium Work In Progress 8/29/2014 8:03:16 AM Castillo, Catos As per security/dept,Several parking lotlights and vocational building lights are not turning on.						8/29/2014		94		\$0.00
Castillo. Carlos Castillo As per security dept, Several parking lot lights and vocational building lights are not turning on. Carlos Castillo 125518 Main Building Exterior 11/13/2014 18 Medium Work In Progress lighto tuside in 11/13/2014 2.06:40 PM 18 Castillo, Carlos Several lights are not working in parking area 11/14/2014 3 Loraine Soriano 11/14/2014 3 Medium Work In Progress flag pole 11/14/2014 3 Medium Work In Progress flag pole pulley is broken, will need bucket truck. 11/14/2014 42 Loraine Soriano 10/20/2014 8:18:19 AM 42 Medium Work In Progress Check the STHS football field lights. There was an is sue with them on Friday. Maybe a problem with a breaker. For information talk to Jamie. Thanks. 124325 Rafael Gallegos 11/14/2014 32 10/30/2014 32 Rafael Gallegos 11/14/2014 32 10/30/2014 32 Rafael Gallegos 11/14/2014 32 11/14/2014 32 Rafael Gallegos 11/14/2014 32 11/14/2014 32			- a		8/29/201			01		φυ.υυ
Carlos Castillo Exterior 11/13/2014 18 125518 Main Building Exterior 11/13/2014 2:06:40 PM 18 Medium Work In Progress lightoutside in 11/13/2014 2:06:40 PM 18 Castillo, Carlos Several lights are not working in parking area 12577 Main Building Exterior 11/14/2014 3 Medium Work In Progress flag pole 11/14/2014 2:51:00 PM 11/17/2014 3 Medium Work In Progress flag pole pulley is broken, will need bucket truck. 11/14/2014 2:51:00 PM 11/17/2014 Castillo, Carlos Flag pole pulley is broken, will need bucket truck. 11/14/2014 2:51:00 PM 11/17/2014 Castillo, Carlos Flog pole pulley is broken, will need bucket truck. 11/14/2014 2:51:00 PM 11/17/2014 Castillo, Carlos Football Field 10/20/2014 8:18:19 AM 42 Medium Work In Progress Check the STHS football field lights. There was an issue with them on Fiday. Maybe a problem with a breaker. For information talk to Jamie. Thanks. 11/14/2014 32 32 Rafael Callegos 11/14/2014 3:58:07 PM 124801 Main Building Athletic Field 10/30/2014 3:58:07 PM Escobar, David Need some painting done, please see Ms. Contreras for specifications. 119327 7/13/2014 12:24:00 AM		Ū.			ng lot lights and					
MediumWork In Progresslightoutside in11/13/2014 2:06:40 PMCastillo, CarlosSeveral lights are not working in parking areaLoraine Soriano125577Main BuildingExterior11/14/20143MediumWork In Progressflag pole11/14/2014 2:51:00 PM11/17/2014Castillo, CarlosFlag pole pulley is broken, will need buckettruck.11/14/2014 2:51:00 PM11/17/2014Loraine Soriano11/14/2014 2:51:00 PM11/17/201442124325Football Field10/20/2014 8:18:19 AM42MediumWork In ProgressCheck the STHS football field lights. There was an issue with them on Firday. Maybe a problem with a breaker. For information talk to Jamie. Thanks.Rafael GallegosRafael Gallegos10/30/2014 3:58:07 PM32MediumWork In Progresssoftball10/30/2014 3:58:07 PMEscobar, DavidNeed some painting done, please see Ms. Contreras for specifications.27/13/2014 8/13/2014 141MediumWork In Progress7/13/2014 12:24:00 AMMijarez, JaimeYearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.8/31/2014 9/16/2014 92Margret Villalobos8/31/2014 12:53:40 AM92WediumWork In Progress8/31/2014 9/16/2014 92	Carlos Ca	stillo								
Castillo, Caitos Several lights are not working in parking area Loraine Soriano Loraine Soriano L25577 Main Building Exterior 11/14/2014 2:51:00 PM 11/17/2014 Castillo, Caitos Flag pole pulleyis broken, will need bucket truck. Loraine Soriano 124325 Football Field 10/20/2014 42 Medium Work In Progress football Field 10/20/2014 8:18:19 AM Castillo, Caitos Check the STHS football field lights. There was an issue with them on Friday. Maybe a problem with a breaker. For information talk to Jamie. Thanks. Rafael Gallegos 124801 Main Building Athletic Field 10/30/2014 32 Medium Work In Progress softball 10/30/2014 358:07 PM Escobar, David Need some painting done, please see Ms. Contreras for specifications. Loraine Soriano 119327 7/13/2014 8/13/2014 141 Medium Work In Progress 7/13/2014 12:24:00 AM Mjarez, Jaime Yearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PMschedule details. Margret Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp Refer to PMschedule details.	125518	Main Building	Exterior			11/13/2014		18		\$0.00
Loraine Soriano 125577 Main Building Exterior 11/14/2014 3 Medium Work In Progress flag pole 11/14/2014 2:51:00 PM 11/17/2014 Castillo, Carlos Flag pole pulley is broken, will need bucket truck. 11/14/2014 42 Loraine Soriano 124325 Football Field 10/20/2014 42 Medium Work In Progress 10/20/2014 8:18:19 AM 42 Castillo, Carlos Check the STHS football field lights. There was an issue with them on Friday. Maybe a problem with a breaker. For information talk to Jamie. Thanks. 32 Rafael Gallegos 10/30/2014 32 Medium Work In Progress softball 10/30/2014 32 Medium Work In Progress softball 10/30/2014 3:58:07 PM 32 Escobar, David Need some painting done, please see Ms. Contreras for specifications. 1119327 7/13/2014 8/13/2014 141 Medium Work In Progress 7/13/2014 12:24:00 AM 41 41 Margnet Willalobos Yearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details. 8/31/2014 9/16/2014 92 9/16/2014 92 Medium Work In Progress <td>Medium</td> <td>Work In Progress</td> <td>lightoutsidein</td> <td></td> <td>11/13/201</td> <td>4 2:06:40 PM</td> <td></td> <td></td> <td></td> <td></td>	Medium	Work In Progress	lightoutsidein		11/13/201	4 2:06:40 PM				
125577Main BuildingExterior11/14/20143MediumWork In Progressflag pole11/14/2014 2:51:00 PM11/17/2014Castillo, CarlosFlag pole pulley is broken, will need bucket truck.11/14/2014 2:51:00 PM11/17/2014Loraine Soriano124325Football Field10/20/201442MediumWork In Progress10/20/2014 8:18:19 AM42Castillo, CarlosCheck the STHS football field lights. There was an issue with them on Friday. Maybe a problem with a breaker. For information talk to Jamie. Thanks.32Rafael Gallegos10/30/2014 3:58:07 PM32MediumWork In Progresssoftball10/30/2014 3:58:07 PMEscobar, DavidNeed some painting done, please see Ms. Contreras for specifications.7/13/20148/13/2014Loraine Soriano7/13/2014 12:24:00 AM8/13/2014141MediumWork In Progress7/13/2014 12:24:00 AM42Migrez, JaimeYearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.8/31/20149/16/201492MediumWork In Progress8/31/20149/16/201492MediumWork In Progress8/31/20149/16/201492Margret Villalobos8/31/20149/16/201492MediumWork In Progress8/31/20149/16/201492MediumWork In Progress8/31/20149/16/201492Margret VillalobosMonthly - Santa Teresa HS Monthly Chiller Insp Refer10/16/201492	Castillo, C	arlos	Several lights a	re not working in pa	arkingarea					
MediumWork In Progressflag pole11/14/2014 2:51:00 PM11/17/2014Castillo, CarlosFlag pole pulley is broken, will need bucket truck.Loraine Soriano124325Football Field10/20/201442MediumWork In Progress10/20/2014 8:18:19 AM42Castillo, CarlosCheck the STHS football field lights. There was an issue with them on Friday. Maybe a problem with a breaker. For information talk to Jamie. Thanks.42Rafael Gallegos10/20/201432MediumWork In Progresssoftball10/30/201432MediumWork In Progresssoftball10/30/2014 3:58:07 PM32Loraine SorianoNeed some painting done, please see Ms. Contreras for specifications.11193277/13/20148/13/2014141MediumWork In Progress7/13/2014 12:24:00 AM141141141141MediumWork In Progress8/31/2014 12:24:00 AM928/31/20149/16/201492Margret Villalobos8/31/2014 12:53:40 AM9/16/201492120228/31/2014 12:53:40 AMVillalobos, MargretMonthly - Santa Teresa HS Monthly Chiller Insp Refer to PMschedule details.8/31/2014 12:53:40 AM9/16/201492	Loraine So	oriano								
Castillo, Carlos Flag pole pulley is broken, will need bucket truck. Loraine Soriano 10/20/2014 124325 Football Field 10/20/2014 42 Medium Work In Progress 10/20/2014 8:18:19 AM 42 Castillo, Carlos Check the STHS football field lights. There was an issue with them on Friday. Maybe a problem with a breaker. For information talk to Jamie. Thanks. 42 Rafael Gallegos 124801 Main Building Athletic Field 10/30/2014 32 Medium Work In Progress softball 10/30/2014 3:58:07 PM 32 Escobar, David Need some painting done, please see Ms. Contreras for specifications. 4119327 7/13/2014 8/13/2014 141 Medium Work In Progress 7/13/2014 8/13/2014 141 Medium Work In Progress 7/13/2014 12:24:00 AM 42 Mijarez, Jaime Yearly - Santa Teresa HS A:11 Air Han Unit Yearly - Refer to PMschedule details. 431/2014 92 Margret Villalobos 8/31/2014 9/16/2014 92 Medium Work In Progress 8/31/2014 1/16/2014 92 Medium Work In Progress 8/31/2014	125577	Main Building	Exterior			11/14/2014		3		\$0.00
Loraine Soriano 124325 Football Field 10/20/2014 42 Medium Work In Progress 10/20/2014 8:18:19 AM 42 Castillo, Carlos Check the STHS football field lights. There was an issue with them on Friday. Maybe a problem with a breaker. For information talk to Jamie. Thanks. 10/30/2014 32 Rafael Gallegos 10/30/2014 32 32 Medium Work In Progress softball 10/30/2014 32 Medium Work In Progress softball 10/30/2014 3:58:07 PM 32 Escobar, David Need some painting done, please see Ms. Contreras for specifications. 5 5 Loraine Soriano 7/13/2014 8/13/2014 141 Medium Work In Progress 8/31/2014 141 Medium Work In Progress 8/31/2014 9/16/2014 9/2 Margret Villalobos 8/31/2014 9/16/2014 9/2 9	Medium	Work In Progress	flagpole		11/14/201	4 2:51:00 PM	11/17/2014			
124325Football Field10/20/201442MediumWork In Progress10/20/2014 8:18:19 AM42Castillo, CarlosCheck the STHS football field lights. There was an issue with them on Friday. Maybe a problem with a breaker. For information talk to Jamie. Thanks.42Rafael Gallegos10/20/2014 8:18:19 AM32124801Main BuildingAthletic Field10/30/201432MediumWork In Progresssoftball10/30/2014 3:58:07 PM32Escobar, DavidNeed some painting done, please see Ms. Contreras for specifications.7/13/20148/13/2014141MediumWork In Progress7/13/2014 12:24:00 AM8/13/2014141MediumWork In Progress7/13/2014 12:24:00 AM42Mijarez, JaimeYearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.8/31/20149/16/201492MediumWork In Progress8/31/2014 12:53:40 AM9/16/201492Villalobos, MargretMonthly - Santa Teresa HS Monthly Chiller Insp Refer to PM schedule details.9/16/201492	Castillo, C	arlos	Flag pole pulley	yis broken, will nee	d bucket truck.					
Medium Work In Progress 10/20/2014 8:18:19 AM Castillo, Carlos Check the STHS football field lights. There was an issue with them on Friday. Maybe a problem with a breaker. For information talk to Jamie. Thanks. Rafael Gallegos 124801 Main Building Athletic Field 10/30/2014 32 Medium Work In Progress softball 10/30/2014 3:58:07 PM 32 Escobar, David Need some painting done, please see Ms. Contreras for specifications. 119327 7/13/2014 8/13/2014 141 Medium Work In Progress 8/31/2014 12:24:00 AM 9/16/2014 92 Margret Villalobos 8/31/2014 9/16/2014 92 9/16/2014 92 Medium Work In Progress 8/31/2014 9/16/2014 92 Medium Work In Progress 8/31/2014 9/16/2014	Loraine So	oriano								
Castillo, CarlosCheck the STHS football field lights. There was an issue with them on Friday. Maybe a problem with a breaker. For information talk to Jamie. Thanks.Rafael Gallegos124801Main BuildingAthletic Field10/30/201432MediumWork In Progresssoftball10/30/2014 3:58:07 PM32Escobar, DavidNeed some painting done, please see Ms. Contreras for specifications.11/32/2014 3:2014141In BuildingWork In Progress7/13/20148/13/2014141MediumWork In Progress7/13/2014 12:24:00 AM141MediumWork In Progress7/13/2014 12:24:00 AM141Margret VillalobosYearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PMschedule details.8/31/20149/16/20141220228/31/20149/16/201492MediumWork In Progress8/31/2014 12:53:40 AM9/16/2014Villalobos, MargretMonthly - Santa Teresa HS Monthly Chiller Insp Refer to PMschedule details.9/16/2014	124325		Football Field			10/20/2014		42		\$0.00
issue with them on Friday. Maybe a problem with a breaker. For information talk to Jamie. Thanks.Rafael Gallegos124801Main BuildingAthletic Field10/30/201432124801Main BuildingAthletic Field10/30/2014 3:58:07 PM32MediumWork In Progresssoftball10/30/2014 3:58:07 PM58:07 PMEscobar, DavidNeed some painting done, please see Ms. Contreras for specifications.57Loraine Soriano7/13/20148/13/2014141MediumWork In Progress7/13/2014 12:24:00 AM141MediumWork In Progress7/13/2014 12:24:00 AM141Mijarez, JaimeYearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.8/31/20149/16/2014Margret Villalobos8/31/20149/16/201492MediumWork In Progress8/31/20149/16/201492Villalobos, MargretMonthly - Santa Teresa HS Monthly Chiller Insp Refer to PM schedule details.S/31/201412:53:40 AM	Medium	Work In Progress			10/20/201	4 8:18:19 AM				
124801Main BuildingAthletic Field10/30/201432MediumWork In Progresssoftball10/30/2014 3:58:07 PM32Escobar, DavidNeed some painting done, please see Ms. Contreras for specifications.8/13/2014141Loraine Soriano7/13/20148/13/2014141MediumWork In Progress7/13/2014 12:24:00 AM8/13/2014141MediumWork In Progress7/13/2014 12:24:00 AM141Mijarez, JaimeYearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.8/31/20149/16/201492MediumWork In Progress8/31/2014 12:53:40 AM9/16/201492MediumWork In Progress8/31/2014 12:53:40 AMVillalobos, MargretMonthly - Santa Teresa HS Monthly Chiller Insp Refer to PM schedule details.8/31/2014 12:53:40 AM	Castillo, C	arlos	issue with them	n on Friday. Maybe a	a problem with a					
Medium Work In Progress softball 10/30/2014 3:58:07 PM Escobar, David Need some painting done, please see Ms. Contreras for specifications.	Rafael Gal	llegos								
Escobar, David Need some painting done, please see Ms. Contreras for specifications. Loraine Soriano 119327 7/13/2014 8/13/2014 141 Medium Work In Progress 7/13/2014 12:24:00 AM Mijarez, Jaime Yearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details. Margret Villalobos 122022 8/31/2014 9/16/2014 92 Medium Work In Progress 8/31/2014 12:53:40 AM Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp Refer to PM schedule details.	124801	Main Building	Athletic Field			10/30/2014		32		\$0.00
specifications.Loraine Soriano1193277/13/20148/13/2014141MediumWork In Progress7/13/2014 12:24:00 AM141Mijarez, JaimeYearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.*********************************	Medium	Work In Progress	softball		10/30/201	4 3:58:07 PM				
1193277/13/20148/13/2014141MediumWork In Progress7/13/2014 12:24:00 AM141Mijarez, JaimeYearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.1220228/31/2014Margret Villalobos8/31/20149/16/201492MediumWork In Progress8/31/2014 12:53:40 AM9/16/2014Villalobos, MargretMonthly - Santa Teresa HS Monthly Chiller Insp Refer to PM schedule details.1000000000000000000000000000000000000	Escobar, D	David		inting done, please	eseeMs.Contrer	as for				
Medium Work In Progress 7/13/2014 12:24:00 AM Mijarez, Jaime Yearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details. Margret Villalobos 122022 8/31/2014 9/16/2014 92 Medium Work In Progress 8/31/2014 12:53:40 AM Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp Refer to PM schedule details. Sefer	Loraine So	oriano								
Mijarez, Jaime Yearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PMschedule details. Margret Villalobos 122022 122022 8/31/2014 9/16/2014 92 Medium Work In Progress 8/31/2014 12:53:40 AM Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp Refer to PMschedule details.								141		\$0.00
Margret Villalobos Margret Villalobos 122022 8/31/2014 9/16/2014 92 Medium Work In Progress 8/31/2014 12:53:40 AM 92 Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp Refer to PM schedule details. Villalobos - Refer to PM schedule details.	Medium	Work In Progress			7/13/2014	12:24:00 AM				
122022 8/31/2014 9/16/2014 92 Medium Work In Progress 8/31/2014 12:53:40 AM 92 Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp Refer to PM schedule details. 92	Mijarez, Ja	ime			Han Unit Yearly	-				
Medium Work In Progress 8/31/2014 12:53:40 AM Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp Refer to PMschedule details.	-	lalobos								
Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp Refer to PM schedule details.								92		\$0.00
to PMschedule details.	Medium	Work In Progress			8/31/2014	12:53:40 AM				
	Villalobos,	Margret			lyChiller Insp I	Refer				
Margret Villalobos	Margret Vil	lalobos								

WOID Priority Assigned ⁻	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester						
Location:	Santa Te					
125568		11/14/2014		17		\$0.00
Medium	Work In Progress	11/14/2014 12:32:11				
Ambriz, Jo	se	not sure if this room has heater - please check. it is our computer tech office.				
Cora Ram	irez					
123540		10/5/2014	10/21/2014	57		\$0.00
Medium	Work In Progress	10/5/2014 12:42:06 AM				
Villalobos,	, Margret	Yearly - Santa Teresa HS October Chiller Insp Refer to PMschedule details.				
Margret Vil	llalobos					
123541		10/5/2014	10/21/2014	57		\$0.00
Medium	Work In Progress	10/5/2014 12:42:06 AM				
Villalobos,	, Margret	Monthly - Santa Teresa HS Monthly Chiller Insp Refer to PMschedule details.				
Margret Vil	llalobos					
123522		10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress	10/5/2014 12:41:51 AM				
Mijarez, Ja	ime	Yearly - Santa Teresa HS R-9 Radiator Ht Wtr 2yr - Refer to PMschedule details.				
Margret Vil	llalobos		/ /			
123523		10/5/2014	10/21/2014	57		\$0.00
Medium	Work In Progress	10/5/2014 12:41:52 AM				
Mijarez, Ja	ime	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PMschedule details.				
Margret Vil	llalobos					
124038		10/12/2014	10/28/2014	50		\$0.00
Medium	Work In Progress	10/12/2014 12:28:59				
Mijarez, Ja	ime	Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PMschedule details.				
Margret Vil	llalobos					
123379		9/30/2014		62		\$0.00
Medium	Work In Progress	9/30/2014 12:51:24 AM				
Mijarez, Ja	ime	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PMschedule details.				

VOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS					
120240			8/3/2014	8/19/2014	120		\$0.00
Medium	Work In Progress		8/3/2014 12:32:31 AN	1			
Villalobos	, Margret	Monthly - Santa Teresa HS Month to PMschedule details.	ly Chiller Insp Refer	Emailed 8/4/14			
Margret Vil	llalobos						
124878			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:05 AN	1			
Orozco, Da	aniel	Yearly - Santa Teresa HS - Greas schedule details.	e Trap - Refer to PM				
Margret Vi	llalobos		// /				
125681			11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 2:29:47 PM				
Ontiveros,	Joe	a 1" copper water pipe busted du new gym.pipe is roughly 100' long 6 commercial AC units.					
David Esc	obar						
125615			11/17/2014		14		\$0.00
Medium	Work In Progress		11/17/2014 9:25:00 AN	1			
Ontiveros,	Joe	Science Room 515 - Repair water tables - install new signs on Gas S locations					
Alfredo Ho	olguin						
124173	AnnexBuilding	Classroom	10/15/2014		47		\$0.00
Medium	Work In Progress	culinary	10/15/2014 9:51:56 AN	1			
Ontiveros,	Joe	Dryer not working					
Loraine So	oriano						
123303	Main Building	Classroom	9/26/2014		66		\$0.00
Medium	Work In Progress	215	9/26/2014 2:16:35 PM	1			
Ontiveros,	Joe	Toiletmalfunctioning					
Loraine So	oriano						
124457	Gymnasium	Auditorium	10/22/2014		40		\$0.00
Medium	Work In Progress	gym girls	10/22/2014 12:33:01				
Ontiveros,	Joe	sink leaking in girls restroom.					
Loraine So	oriano						

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS					
125620			11/17/2014		14		\$0.00
Medium	Work In Progress		11/17/2014 9:37:18 AM	1			
Ontiveros	, Joe	Science Room 508 - Repair gas a tables and install new signs at loo Valve.					
Alfredo Ho	olguin						
125544			11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 4:25:33 PM	l			
Ontiveros	, Joe	Room 511 Order and access par access to gas shut off.	el under sink to provide				
Alfredo Ho	olguin		11/12/2014		19		\$0.00
125436					19		Ф 0.00
Medium	Work In Progress		11/12/2014 12:03:08	i			
Ontiveros		toilets clogged in culinaryarts bat up from floordrains.	hrooms.water comes				
David Esc 125437	cobar		11/12/2014		19		\$0.00
Medium	Work In Progress		11/12/2014 12:04:49		10		ψ0.00
Ontiveros	-	toilet clogged in vocational buildir		,			
Chavoroo	,000	and wood shop.	ig botwoon an oldoo				
David Esc	cobar						
125545		Classroom	11/13/2014		18		\$0.00
Medium	Work In Progress		11/13/2014 4:29:17 PN	l			
Ontiveros		Science Room 511- Install new s access panels 2) to read "gas S					
Alfredo Ho	-	Classman	44/40/2044		04		¢0.00
125410	AnnexBuilding	Classroom	11/10/2014		21		\$0.00
Medium	Work In Progress	culinary	11/10/2014 4:27:44 PN				
Ontiveros	, Joe	The exhaust vent to the convection	on oven				
Loraine S			11/10/0011				* ••••
125411	AnnexBuilding	Classroom	11/10/2014		21		\$0.00
Medium	Work In Progress	culinary	11/10/2014 4:28:51 PN	l			
Ontiveros	, Joe	The three compartment sink need	ds the drain				
Loraine S							A
122789	AnnexBuilding	Classroom	9/15/2014		77		\$0.00
Medium	Work In Progress	Culinary	9/15/2014 3:55:04 PN	1			
Ontiveros	,Joe	Dryer is not working.					
Loraine S	oriano						
12/1/2014	4 3:28:31 PM					Page 16	66 of

WOID Priority Assigned	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS					
120184	Main Building	Classroom	8/1/2014		122		\$0.00
Medium	Work In Progress	610	8/1/2014 12:26:38 PM	1			
Ontiveros,	Joe	Install new range in room 610					
Loraine So	oriano	·					
120191	AnnexBuilding	Classroom	8/1/2014		122		\$0.00
Medium	Work In Progress	culinary	8/1/2014 12:47:05 PN	1			
Ontiveros,	Joe	Three compartment sink need dr	ain handles.				
Loraine So	oriano						
123468			10/5/2014	10/8/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:41:06 AM	I			
Mijarez, Ja	ime	Monthly - Santa Teresa HS - Em Refer to PMschedule details.	erg. Eyewash (Mthly) -				
Margret Vil	llalobos						
122004			8/31/2014	9/3/2014	92		\$0.00
Medium	Work In Progress		8/31/2014 12:53:27 AM	l			
Mijarez, Ja		Monthly - Santa Teresa HS - Em Refer to PMschedule details.	erg. Eyewash (Mthly) -				
Margret Vil			Q/1E/2014		108		\$0.00
121254	Cafeteria (2005)		8/15/2014		108		\$0.00
Medium	Work In Progress		8/15/2014 10:49:31 AM				
Mijarez, Ja		mens restroom in cafeteria urina pressure	l not enough water				
Isaac Holg 124894	guin		11/2/2014	11/5/2014	29		\$0.00
Medium	Work In Brogroop		11/2/2014 12:35:14 AM		23		ψ0.00
Mijarez, Ja	Work In Progress ime	Monthly - Santa Teresa HS - Em					
Margret Vil	llalabas	Refer to PMschedule details.					
125888	lialobos		11/30/2014	12/3/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:19				
Mijarez, Ja	-	Monthly - Santa Teresa HS - Em Refer to PMschedule details.					
Margret Vil	llalobos						
125803			11/20/2014		11		\$0.00
Medium	Work In Progress		11/20/2014 2:27:54 PM				
Ontiveros,	Joe	floor drains in restrooms in main	hallwayare clogged.				
David Esc							

12/1/2014 3:28:31 PM

Priority Assigned ⁻ Requester		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa HS					
125804			11/20/2014		11		\$0.00
Medium	Work In Progress		11/20/2014 2:29:05 PN	l			
Ontiveros,	Joe	sinks in boys restroom do not work.					
David Esc	obar						
125808			11/20/2014		11		\$0.00
Medium	Work In Progress		11/20/2014 2:39:55 PM	l			
Ontiveros,	Joe	need to replace 2 expansion tanks.					
David Esc	obar						
122290			9/4/2014		88		\$0.00
Medium	Work In Progress		9/4/2014 8:13:30 AM	1			
Ontiveros,		There is a manhole next to the marq needs some attention (see email for					
Rafael Gal	llegos		40/45/0014		47		<u> </u>
124192			10/15/2014		47		\$0.00
Medium Ontiveros,	Work In Progress Joe	need to replace man hole @ tennis co Rd. fence line.	10/15/2014 3:17:25 PN ourts along Airport				
David Esc	obar						
124608			10/27/2014		35		\$0.00
Medium	Work In Progress		10/27/2014 8:31:27 AM	1			
Ambriz, Jo	se	Please assist David Escobar w/Boile startup. Jaime will be out all week. (Lorenzo will also assist)	r and Heating				
124375			10/21/2014		41		\$0.00
Medium	Work In Progress		10/21/2014 8:25:12 AN	1			
Ambriz, Jos	se	"Belimo" actuators for kitchen, stage, AHU's . 2 per AHU total of 6 actuators					
David Esc	obar						
119914			7/28/2014		126		\$0.00
Medium	Work In Progress		7/28/2014 1:21:02 PM	1			
Ambriz, Jos		Grounds shop. Please install a ductle cooling in the grounds office/shop bu					
Jaime Mija	Concession	Football Field	8/29/2014		94		\$0.00
121992 Madium				A	34		φU.UU
Medium	Work In Progress	ticketbooth	8/29/2014 3:40:04 PN	1			
Ambriz, Jos		Replace window unit due to coil is sue	9S				
	oriano						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS					
124898			11/2/2014	11/18/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:17 AM				
Villalobos	, Margret	Monthly - Santa Teresa HS Monthly to PMschedule details.	/Chiller Insp Refer	E-mailed 11/3/14			
Margret Vi	llalobos						
125903			11/30/2014	12/16/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:30				
Villalobos	, Margret	Monthly - Santa Teresa HS Monthly to PMschedule details.	/ Chiller Insp Refer				
Margret Vi	llalobos						
123532			10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:41:59 AM				
Escobar, I	David	Yearly - Santa Teresa HS U-2 Unit Refer to PMschedule details.	Ht Gas Yearly -				
Margret Vi	llalobos						
123534			10/5/2014	10/26/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:42:01 AM				
Escobar, I		Monthly - Santa Teresa HS H-11 U Refer to PMschedule details.	nit Elec Semimly -				
Margret Vi	llalobos		4.0/5/0.044	44/5/0044			.
123535			10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:42:02 AM				
Escobar, I		Yearly - Santa Teresa HS H-6 Rfto to PMschedule details.	p Furn Yearly - Refer				
Margret Vi	llalobos						* •••••
123536			10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:42:02 AM				
Escobar, I	David	Yearly - Santa Teresa HS I-4 Fan C Refer to PMschedule details.	Coil Unit Yearly -				
Margret Vi	llalobos			_ / /			A
120911			8/10/2014	9/10/2014	4		\$0.00
Medium	Work In Progress		8/10/2014 12:25:31 AM	8/14/2014			
Escobar, I	David	Yearly - Santa Teresa HS A-9 Air C to PMschedule details.	ooled Yearly - Refer				
Margret Vi	llalobos						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order Area Deferred By Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		resa HS					
125508	Main Building	Classroom	11/13/2014		18		\$0.00
Medium	Work In Progress	610	11/13/2014 10:37:54				·
Lara, Ralp	0	Third request for assistance in lab					
Loraine S	oriano						
125733	Main Building	Classroom	11/19/2014		12		\$0.00
Medium	Work In Progress	606	11/19/2014 8:31:25 AM				
Lara, Ralp		Key core came out of door knol main building and needs to be					
	a Rodriguez Main Building	Cum	11/14/2014		17		\$0.00
125565 Medium	Ŭ	Gym Football locker	11/14/2014 11:48:10		17		φ 0. 00
Lara, Ralp	Work In Progress	Football lockers have broken h be locked or opened, need clas be usable	andles and can no longer				
Loraine S	oriano						
124116	Main Building	Classroom	10/14/2014		48		\$0.00
Medium	Work In Progress	610	10/14/2014 8:18:04 AM				
Lara, Ralp	bh	locks on cabinets need to be lo	ooked at				
Loraine S	oriano						
124117	Main Building	Classroom	10/14/2014		48		\$0.00
Medium	Work In Progress	610	10/14/2014 8:18:47 AM				
Lara, Ralp	bh	Need a key for room 610					
Loraine S	oriano						
124171			10/15/2014		47		\$0.00
Medium	Work In Progress		10/15/2014 9:15:07 AM				
Ontiveros	, Guadalupe	Attn: Lupe Ontiveros. Mr. Char you provided him with the last t of more scrap steal to clean the	ime. He needs to get rid				
Jaime Mij	arez						
125680			11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 2:27:31 PM				
Lara, Ralp		bldg.mech.needs M113 keyto that have A/C water valves.	access custodial closets				
David Esc	cobar						

WOID Priority Assigned	Building Status	Dates:7/1/2014 - 11/30/2014 Order Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	Name						
Location:	Santa Te	resa HS					
123302			9/26/2014		66		\$0.00
Medium	Work In Progress		9/26/2014 1:59:51 PN	1			
Lara, Ralpl	h	doors to dock entrance at dayc need repair.	are will not open and				
David Esc	obar						
123989			10/10/2014		52		\$0.00
Medium	Work In Progress		10/10/2014 11:00:23	5			
Llanez, Ric	:k	Please fixhole in sidewalk at the Please see e-mail for pictures any questions please contact N - 882-6921 in the Construction	of area. Should you have Mr. Ralph Gallegos at 575				
Dominique	e Esparza						
120625		Athletic Field	8/6/2014		117		\$0.00
Medium	Work In Progress	Football field	8/6/2014 9:23:08 AN	1			
Llanez, Ric		Turf field in dire need of brushin Pellets needed and field needs month. Schedule dates are new equipment needed to brush fie crucial as season begins in tw	s to be maintained twice a eded for proper care and Id as well as pellets. It is				
Loraine Sc			10/00/0011				
124797	Main Building	Athletic Field	10/30/2014		32		\$0.00
Medium	Work In Progress	softball	10/30/2014 3:55:12 PN				
Llanez, Ric	:k	Bullpen in need of work on visi	tors side.				
Loraine Sc							
124799	Main Building	Athletic Field	10/30/2014		32		\$0.00
Medium	Work In Progress	softball	10/30/2014 3:57:02 PN	l			
Llanez, Ric		Windscreen missing to compl in the outfield.	ete the field. Not complete				
Loraine Sc		Football Field	10/30/2014		32		\$0.00
124787 Medium	GYM (2009)		10/30/2014 3:46:38 PM		32		Ф 0.00
	Work In Progress	baseball		I			
Llanez, Ric		Overseed baseball field, with w	vinter rye				
Loraine Sc 121492	Main Building	Exterior	8/20/2014		103		\$0.00
Medium	-	sidewalk	8/20/2014 8:59:58 AM		100		ψ0.00
Llanez, Ric	Work In Progress			1			
	CK	Sidewalk toward arroyo has ha	llow areas where water				

WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Labor Aged Hours	Costs
Location:		resa HS				
122320	Main Building	Exterior	9/4/2014		88	\$0.00
Medium	Work In Progress	Admin/handicap	9/4/2014 11:39:20 AM			·
Ontiveros	, Guadalupe	If concrete curbs can be placed in p from obstructing access to sidewa				
Loraine S	oriano	Ū.				
123552			10/5/2014	10/13/2014	57	\$0.00
Medium	Work In Progress		10/5/2014 12:42:15 AM			
Escobar,	David	Monthly - Santa Teresa HS Roof Ir PMschedule details.	nspection - Refer to			
Margret V	illalobos					
120999			8/12/2014		111	\$0.00
Medium	Work In Progress		8/12/2014 9:29:38 AM			
Ontiveros	, Guadalupe	Sidewalk attached to black cinder b to arroyo has a lot of erosion from S and can collapse into arroyo with a and was reported by Security Juan heavily used by the students and ne attention.	Sundays rain storm nother heavyrain. n Tellez. Side walk is			
Jaime Mij	arez					
121003			8/12/2014		111	\$0.00
Medium	Work In Progress		8/12/2014 9:38:36 AM			
Ontiveros	, Guadalupe	Sidewalk behind the 500 wing exit t has a lot of erosion from Sundays r collapse. Right now it is unsafe, I w to keep students off this area. need Attention Lupe for this work order 120999.	ain storm and can ill have to barricade I immediate attention.			
Jaime Mij	arez					
122288	Main Building	Hallway/Corridor	9/4/2014		88	\$0.00
Medium	Work In Progress		9/4/2014 8:02:23 AM			
Lucero, A	rnold	Make sure all hallways are burnish (Assign to Arnold Lucero)	ed 2 times a week.	10/17/14 - REMAILE	ED TO ARNOLD	
Jesus Es	trada					
124017			10/12/2014	10/28/2014	50	\$0.00
Medium	Work In Progress		10/12/2014 12:28:43			
Lucero, Ai	rnold	Monthly - QRTLY BLDG INSP REP to PMschedule details.	ORT (STH) - Refer			
Jesus Es	trada					

	ate Range for Request Building Status To	Dates:7/1/2014 - 11/30/2014 Area Deferre Area Number Reason Description	Order By Loc	Until Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Total Costs
Location:	Santa Te	esa HS						
124334				10/20/2014	ļ	42		\$0.00
Medium	Work In Progress			10/20/2014 10:18:4	1			
Flores, Pe	te	need headligths for the g	ator					
Arnold Luc	cero							
125433				11/12/2014	ŀ	19		\$0.00
Medium	Work In Progress			11/12/2014 11:14:5	0			
Flores, Pe	te	need headlights for the g	atorplease					
Arnold Luc	cero							
121481		Storage		8/19/2014	ŀ	104		\$0.00
Medium	Work In Progress	band truck		8/19/2014 3:59:40 PI	M			
Flores, Pe	te	Band truck needs to be fix	ed for use c	ofequipment				
Loraine So	oriano							
Count: 140) Work Orders	Avg. Age o	WO's 56	1	otal for Santa Teres	a HS	0	\$0.00

Location: Santa Teresa MS 123870 North Building Office 10/8/2014 154 Medium Work In Progress MR. POKLUDA 10/8/2014 11:40:04 AM Flores, Pete GATOR NEEDS: CARB OVERHAUL- CHECK BRAKES - CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS) 11 Laura Parra - - 123:377 South Building Office 8/4/2014 119 Medium Work In Progress MEDINA 8/4/2014 9:05:29 AM 119 Medium Work In Progress MEDINA 8/4/2014 9:05:29 AM 111 Laura Parra - CATOR NEEDS WORK DONE: CARB OVERHAUL, CHECK BRAKES, CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS) - 111 Laura Parra - - 11/12/2014 19 Medium Work In Progress 11/12/2014 3:56:05 PM Prospero, Manuel KITCHEN-1-2 CEILING TILES MISSING IN THE PRODUCT STORE ROOM Medium Work In Progress 11/12/2014 3:56:52 PM Prospero, Manuel Corroded bottom wall paneling lose from wall in janitor storeroom and into bathroom. Maritza Gonzalez - 125477 <th>WOID Priority Assigned Requester</th> <th></th> <th>Area Deferred By Area Number Reason Description</th> <th>Until Request Date Ta Created Date/Time Ac</th> <th> Days Aged</th> <th>Labor Hours</th> <th></th>	WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ac	 Days Aged	Labor Hours	
Medium Work In Progress MR. POKLUDA 10/8/2014 11:40:04 AM Flores, Pete GATOR NEEDS: CARB OVERHAUL- CHECK BRAKES - CHECK TRANSMSSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS)	Location:	Santa Te	resa MS				
Flores, Peter GATOR NEEDS: CARB OVERHAUL- CHECK BRAKES -CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS) Laura Parra 120397 South Building Office 8/4/2014 119 Medium Work In Progress GATOR NEEDS WORK DONE: CARB OVERHAUL, CHECK BRAKES, CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS) 119 Laura Parra CHECK BRAKES, CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS) 11/12/2014 Laura Parra Kitchen 11/12/2014 19 Medium Work In Progress Kitchen 11/12/2014 19 Medium Work In Progress Kitchen 11/12/2014 19 Medium Work In Progress 11/12/2014 19 Maritza Gonzalez Cororded bottom wall paneling lose from wall in janitor storeroom and into bathroom. 11/12/2014 19 Medium Work In Progress Kitchen 11/12/2014 19 Medium Work In Progress 11/12/2014 <t< td=""><td>123870</td><td>North Building</td><td>Office</td><td>10/8/2014</td><td>54</td><td></td><td>\$0.00</td></t<>	123870	North Building	Office	10/8/2014	54		\$0.00
CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS)Laura Parz120397South BuildingOffice8/4/2014119MediumWork In ProgressMEDINA-8/4/2014 9.05.29 AMFlores, PerCATOR NEEDS WORK DONE: CARB OVERHAULL, CHECK BRAKES, CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS)1Laura Parz	Medium	Work In Progress	MR. POKLUDA	10/8/2014 11:40:04 AM			
120397 South Building Office 8/4/2014 119 Medium Work In Progress MEDINA- 8/4/2014 9:05:29 AM 119 Flores, Pete GATOR NEEDS WORK DONE: CARB OVERHAUL, CHECK BRAKES, CHECK TRANSMISSION WHILE ENSAGING (DRIVE AND REVERSE GRINDS) 1112/2014 19 Laura Parra 11/12/2014 3:56:05 PM 11/12/2014 3:56:05 PM 11/12/2014 3:56:05 PM Prospero, Manuel KITCHEN-1:2 CEILING TILES MISSING IN THE PRODUCT STORE ROOM. 11/12/2014 3:56:52 PM Medium Work In Progress 11/12/2014 3:56:52 PM 19 Medium Work In Progress 11/12/2014 3:56:52 PM 19 Medium Work In Progress 11/12/2014 3:56:52 PM 19 Medium Work In Progress 11/12/2014 3:56:52 PM 11 Prospero, Manuel Coroded bottom wall paneling lose from wall in janitor storeroom and into bathroom. 11 19 Medium Work In Progress 11/12/2014 3:58:00 PM 19 Medium Work In Progress 11/12/2014 3:58:00 PM 19 Prospero, Manuel Outside door insulation loose. 11/12/2014 3:58:30 PM 19 <tr< td=""><td>Flores, Pe</td><td>te</td><td>- CHECK TRANSMISSION WHILE</td><td></td><td></td><td></td><td></td></tr<>	Flores, Pe	te	- CHECK TRANSMISSION WHILE				
Medium Work In Progress MEDINA- 8/4/2014 9:05:29 AM Flores, Pete GATOR NEEDS WORK DONE: CARB OVERHAUL, CHECK BRAKES, CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS)	Laura Par	ra					
Flores, Pete GATOR NEEDS WORK DONE: CARB OVERHAUL, CHECK BRAKES, CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS) Laura Parra 11/12/2014 3:56:05 PM 125466 Kitchen 11/12/2014 3:56:05 PM Prospero, Manuel KITCHEN-1-2 CEILING TILES MISSING IN THE PRODUCT STORE ROOM. 11/12/2014 3:56:05 PM Maritza Gonzalez 11/12/2014 3:56:52 PM 19 Medium Work In Progress 11/12/2014 3:56:52 PM Prospero, Manuel Corroded bottom wall paneling lose from wall in janitor storeroom and into bathroom. 19 Maritza Gonzalez 11/12/2014 3:56:52 PM 19 Medium Work In Progress 11/12/2014 3:56:52 PM 19 Maritza Gonzalez 11/12/2014 3:56:52 PM 19 Maritza Gonzalez 11/12/2014 3:58:00 PM 19 Medium Work In Progress 11/12/2014 3:58:00 PM 19 Prospero, Manuel Outside door insulation loose. 11/12/2014 3:58:42 PM 19 Medium Work In Progress 11/12/2014 3:58:42 PM 19 Prospero, Manuel Holes and uncovered outlet in the storeroom. 11/12/2014 3:58:42 PM Prospero, Manuel Holes and uncovered outlet in the storeroom. 11/14/2014 7:	120397	South Building	Office	8/4/2014	119		\$0.00
CHECK BRAKES, CHECK TRANSMISSION WHILE BNGAGING (DRIVE AND REVERSE GRINDS) Laura Parra 125466 Kitchen 11/12/2014 3:56:05 PM Prospero, Manuel KITCHEN-1-2 CEILING TILES MISSING IN THE PRODUCT STORE ROOM. 1 Maritza Gonzalez Kitchen 11/12/2014 3:56:52 PM Prospero, Manuel Kitchen 11/12/2014 3:56:52 PM Medium Work In Progress Kitchen 11/12/2014 3:56:52 PM Prospero, Manuel Corroded bottom wall paneling lose from wall in janitor storeroom and into bathroom. 11/12/2014 3:56:52 PM Medium Work In Progress Kitchen 11/12/2014 3:58:00 PM Prospero, Manuel Corroded bottom wall paneling lose from wall in janitor storeroom and into bathroom. 11/12/2014 3:58:00 PM Medium Work In Progress 11/12/2014 3:58:00 PM 11/12/2014 3:58:00 PM Prospero, Manuel Outside door insulation loose. 11/12/2014 3:58:42 PM Medium Work In Progress 11/12/2014 3:58:42 PM Prospero, Manuel Holes and uncovered outlet in the storeroom. 11/12/2014 3:58:42 PM Medium Work In Progress 11/12/2014 3:58:42 PM 17 Prospero, Manuel Holes and uncovered outlet in the storeroom.	Medium	Work In Progress	MEDINA-	8/4/2014 9:05:29 AM			
125466Kitchen11/12/201419MediumWork In Progress11/12/2014 3:56:05 PM19Prospero, ManuelKITCHEN-1-2 CEILING TILES MISSING IN THE PRODUCT STORE ROOM.11/12/201419Maritza Gonzalez11/12/2014 3:56:52 PM19MediumWork In Progress11/12/2014 3:56:52 PM19Prospero, ManuelCorroded bottom wall paneling lose from wall in janitor storeroom and into bathroom.11/12/2014 3:56:52 PMMaritza Gonzalez11/12/2014 3:56:52 PM19MediumWork In Progress11/12/2014 3:58:00 PMProspero, ManuelOutside door insulation loose.11/12/2014 3:58:00 PMProspero, ManuelOutside door insulation loose.11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.11/12/2014 19Maritza Gonzalez11/12/2014 3:58:42 PM19Prospero, ManuelHoles and uncovered outlet in the storeroom.11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.11/12/2014 19Maritza Gonzalez11/12/2014 3:58:42 PM17Prospero, ManuelHoles and uncovered outlet in the storeroom.11/14/2014 17Prospero, ManuelPleas efill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.11/14/2014 17	Flores, Pe	te	CHECK BRAKES, CHECK TRANS	MISSION WHILE			
Medium Work In Progress 11/12/2014 3:56:05 PM Prospero, Manuel KITCHEN-1-2 CEILING TILES MISSING IN THE PRODUCT STORE ROOM. Maritza Gonzalez 125467 Kitchen 11/12/2014 3:56:52 PM Prospero, Manuel Corroded bottom wall paneling lose from wall in janitor storeroom and into bathroom. Maritza Gonzalez 125470 Kitchen 11/12/2014 3:58:00 PM Prospero, Manuel Corroded bottom wall paneling lose from wall in janitor storeroom and into bathroom. Maritza Gonzalez 125470 Kitchen 11/12/2014 3:58:00 PM Prospero, Manuel Outside door insulation loose. Maritza Gonzalez 125471 Kitchen 11/12/2014 3:58:42 PM Prospero, Manuel Holes and uncovered outlet in the storeroom. Maritza Gonzalez 125552 Kitchen 11/12/2014 3:58:42 PM Prospero, Manuel Holes and uncovered outlet in the storeroom. Maritza Gonzalez 125552 Kitchen 11/14/2014 7:57:47 AM Prospero, Manuel Please fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.	Laura Par	ra					
Prospero, Manuel KITCHEN-1-2 CELLING TILES MISSING IN THE PRODUCT STORE ROOM. Maritza Gonzalez 125467 Kitchen 125467 Kitchen Maritza Gonzalez Prospero, Manuel Corroded bottom wall paneling lose from wall in janitor storeroom and into bathroom. Maritza Gonzalez 125470 Kitchen 125470 Kitchen Vork In Progress 11/12/2014 3:58:00 PM Prospero, Manuel Outside door insulation loose. Maritza Gonzalez 11/12/2014 3:58:40 PM Prospero, Manuel Outside door insulation loose. Maritza Gonzalez 11/12/2014 3:58:42 PM Prospero, Manuel Holes and uncovered outlet in the storeroom. Maritza Gonzalez 11/12/2014 3:58:42 PM Prospero, Manuel Holes and uncovered outlet in the storeroom. Maritza Gonzalez 11/12/2014 3:58:42 PM Prospero, Manuel Kitchen 11/12/2014 3:58:42 PM Prospero, Manuel Kitchen 11/14/2014 19 Maritza Gonzalez 11/12/2014 3:58:42 PM Prospero, Manuel Holes and uncovered outlet in the storeroom. Maritza Gonzalez 11/14/2014 7:57:47 AM Prospero, Manuel Please fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.	125466		Kitchen	11/12/2014	19		\$0.00
Maritza Gonzalez125467Kitchen11/12/201419MediumWork In Progress11/12/2014 3:56:52 PMProspero, ManuelCorroded bottom wall paneling lose from wall in janitor storeroom and into bathroom.11/12/2014 3:56:52 PMMaritza Gonzalez11/12/2014 3:58:00 PM125470Kitchen11/12/2014 3:58:00 PMProspero, ManuelOutside door insulation loose.11/12/2014 3:58:00 PMProspero, ManuelOutside door insulation loose.11/12/2014 3:58:00 PMProspero, ManuelOutside door insulation loose.11/12/2014 3:58:00 PMProspero, ManuelNerk in Progress11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.11/12/2014 3:58:42 PMProspero, ManuelKitchen11/14/2014 7:57:47 AM17HighWork In Progress11/14/2014 7:57:47 AM17Prospero, ManuelPlease fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.11/14/2014 7:57:47 AM	Medium	Work In Progress		11/12/2014 3:56:05 PM			
125467Kitchen11/12/201419MediumWork In Progress11/12/2014 3:56:52 PM19Prospero, ManuelCorroded bottom wall paneling lose from wall in janitor storeroom and into bathroom.11/12/2014 3:56:52 PMMaritza Gonzalez11/12/201419MediumWork In Progress11/12/2014 3:58:00 PMProspero, ManuelOutside door insulation loose.11/12/2014 3:58:00 PMMaritza Gonzalez11/12/2014 3:58:00 PMProspero, ManuelOutside door insulation loose.Maritza Gonzalez11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.Maritza Gonzalez11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.Maritza Gonzalez11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.Maritza Gonzalez11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.Maritza Gonzalez11/12/2014 3:58:42 PMProspero, ManuelProsperoProspero, ManuelPlease fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.	Prospero,	Manuel		SING IN THE			
Medium Work In Progress 11/12/2014 3:56:52 PM Prospero, Manuel Corroded bottom wall paneling lose from wall in janitor storeroom and into bathroom. Maritza Gonzalez 11/12/2014 3:58:00 PM Prospero, Manuel Kitchen 11/12/2014 3:58:00 PM Prospero, Manuel Outside door insulation loose. 11/12/2014 3:58:00 PM Maritza Gonzalez 11/12/2014 3:58:00 PM 11/12/2014 3:58:00 PM Prospero, Manuel Outside door insulation loose. 11/12/2014 3:58:42 PM Medium Work In Progress 11/12/2014 3:58:42 PM 19 Medium Work In Progress 11/12/2014 3:58:42 PM 19 Maritza Gonzalez 11/12/2014 3:58:42 PM 19 Medium Work In Progress 11/12/2014 3:58:42 PM 19 Maritza Gonzalez 11/12/2014 3:58:42 PM 19 Maritza Gonzalez 11/12/2014 3:58:42 PM 10 Maritza Gonzalez 11/12/2014 3:58:42 PM 11/12/2014 3:58:42 PM Prospero, Manuel Holes and uncovered outlet in the storeroom. 11/12/2014 3:58:42 PM Maritza Gonzalez 11/14/2014 7:57:47 AM 17 High Work In Progress 11/14/2014 7:57:47 AM	Maritza Go	onzalez					
Prospero, ManuelCorroded bottom wall paneling lose from wall in janitor storeroom and into bathroom.Maritza GonzalezKitchen11/12/201419125470Kitchen11/12/2014 3:58:00 PMProspero, ManuelOutside door insulation loose.Maritza Gonzalez11/12/2014 3:58:00 PMProspero, ManuelOutside door insulation loose.Maritza Gonzalez11/12/2014 3:58:42 PMProspero, ManuelKitchenModiumWork In ProgressProspero, ManuelHoles and uncovered outlet in the storeroom.Maritza Gonzalez11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.Maritza Gonzalez11/14/2014 7:57:47 AMProspero, ManuelPlease fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.	125467		Kitchen	11/12/2014	19		\$0.00
Maritza Gonzalez125470Kitchen11/12/201419MediumWork In Progress11/12/2014 3:58:00 PM19Prospero, ManuelOutside door insulation loose.11/12/2014 3:58:00 PMMaritza Gonzalez11/12/2014 3:58:40 PM19125471Kitchen11/12/2014 19MediumWork In Progress11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.11/12/2014 3:58:42 PMMaritza Gonzalez11/12/2014 3:58:42 PM19Prospero, ManuelHoles and uncovered outlet in the storeroom.11/14/2014 3:58:42 PMProspero, ManuelKitchen11/14/2014 7:57:47 AMProspero, ManuelPlease fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.11/14/2014 7:57:47 AM	Medium	Work In Progress		11/12/2014 3:56:52 PM			
125470Kitchen11/12/201419MediumWork In Progress11/12/2014 3:58:00 PM19Prospero, ManuelOutside door insulation loose.11/12/2014 3:58:00 PMMaritza Gonzalez11/12/201419125471Kitchen11/12/2014 3:58:42 PMMediumWork In Progress11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.11/12/2014 3:58:42 PMMaritza Gonzalez11/12/2014 3:58:42 PM10125552Kitchen11/14/2014 17HighWork In Progress11/14/2014 7:57:47 AMProspero, ManuelPlease fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.				se from wall in janitor			
MediumWork In Progress11/12/2014 3:58:00 PMProspero, ManuelOutside door insulation loose.Maritza Gorzalez125471KitchenMaritza GorzalezNediumWork In ProgressProspero, ManuelHoles and uncovered outlet in the storeroom.Maritza Gorzalez125552Kitchen11/12/201411/12/2014125552Kitchen11/14/2014HighWork In ProgressProspero, ManuelPlease fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.		onzalez					
Prospero, Manuel Outside door insulation loose. Maritza Gonzalez 125471 Kitchen 11/12/2014 19 Medium Work In Progress Holes and uncovered outlet in the storeroom. Maritza Gonzalez 125552 Kitchen Area 11/14/2014 17 High Work In Progress Kitchen area) before health inspector visit.	125470		Kitchen		19		\$0.00
Maritza Gonzalez125471Kitchen11/12/201419MediumWork In Progress11/12/2014 3:58:42 PM19Prospero, ManuelHoles and uncovered outlet in the storeroom.11/12/2014 3:58:42 PMMaritza Gonzalez11/14/2014 3:58:42 PM10125552Kitchen11/14/2014 17HighWork In Progress11/14/2014 7:57:47 AMProspero, ManuelPlease fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.11/14/2014 7:57:47 AM	Medium	Work In Progress		11/12/2014 3:58:00 PM			
125471Kitchen11/12/201419MediumWork In Progress11/12/2014 3:58:42 PM10Prospero, ManuelHoles and uncovered outlet in the storeroom.11/12/2014 3:58:42 PMMaritza Gonzalez11/14/201417125552Kitchen11/14/201417HighWork In Progress11/14/2014 7:57:47 AMProspero, ManuelPlease fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.11/14/2014	Prospero,	Manuel	Outside door insulation loose.				
MediumWork In Progress11/12/2014 3:58:42 PMProspero, ManuelHoles and uncovered outlet in the storeroom.Maritza Gonzalez125552KitchenHighWork In ProgressProspero, ManuelPlease fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.	Maritza Go	onzalez					
Prospero, Manuel Holes and uncovered outlet in the storeroom. Maritza Gonzalez 11/14/2014 125552 Kitchen 11/14/2014 17 High Work In Progress Prospero, Manuel Please fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.	125471		Kitchen	11/12/2014	19		\$0.00
Maritza Gonzalez 125552 Kitchen 11/14/2014 17 High Work In Progress 11/14/2014 7:57:47 AM 17 Prospero, Manuel Please fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit. 11/14/2014 7:57:47 AM	Medium	Work In Progress		11/12/2014 3:58:42 PM			
125552 Kitchen 11/14/2014 17 High Work In Progress 11/14/2014 7:57:47 AM 17 Prospero, Manuel Please fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit. 11/14/2014 7:57:47 AM	Prospero,	Manuel	Holes and uncovered outlet in the s	storeroom.			
HighWork In Progress11/14/2014 7:57:47 AMProspero, ManuelPlease fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.	Maritza Go	onzalez					
Prospero, Manuel Please fill in holes in the ceiling in small storage room (kitchen area) before health inspector visit.	125552		Kitchen	11/14/2014	17		\$0.00
(kitchen area) before health inspector visit.	High	Work In Progress		11/14/2014 7:57:47 AM			
Jesus Estrada							
	Jesus Est	trada					

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date 1 Area Number Reason Created Date/Time / Description Created Date/Time /	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS				
125553	North Building	Kitchen 11/14/2014		17		\$0.00
High	Work In Progress	11/14/2014 8:01:31 AM				
Prospero,	Manuel	Please replace the wet ceiling tiles in the main storage (kitchen area) before health inspector visit.				
Jesus Es	trada					
125953		11/30/2014	12/31/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:04				
Prospero,	Manuel	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PMschedule details.				
Margret Vi	llalobos					
125954		11/30/2014		1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:04				
Prospero,	, Manuel	Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMschedule details.				
Margret Vi	llalobos		/ . /			
125955		11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:05				
Prospero,		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vi	llalobos		/ . /			
125956		11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:06				
Prospero,	Manuel	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PMschedule details.				
Margret Vi	llalobos					
124913		11/2/2014		29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:25 AM				
Prospero,	Manuel	Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMschedule details.				
Margret Vi	llalobos					
124914		11/2/2014	12/3/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:26 AM				
Prospero,	Manuel	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PMschedule details.				
Margret Vi	illalobos					

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By I Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS					
124915			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:27 AM				
Prospero,	Manuel	Monthly - Santa Teresa MS Exit Si Refer to PM schedule details.	gn Insp: Monthly-				
Margret Vi	llalobos						
124916			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:27 AM				
Prospero,	Manuel	Monthly - Santa Teresa MS Emer Refer to PM schedule details.	Light Test: Monthly-				
Margret Vi	llalobos						
122257	South Building	Hallway/Corridor	9/3/2014		89		\$0.00
Medium	Work In Progress	HALL WAY	9/3/2014 3:33:19 PM	I			
Prospero,	Manuel	REMOVE LOCKERS FROM WALL 44-45. SECOND REQUEST	OUTSIDE ROOM				
Laura Par	ra						
124584	South Building	Hallway/Corridor	10/24/2014		38		\$0.00
Medium	Work In Progress	#44-ALLEN	10/24/2014 2:56:08 PM				
Prospero,	Manuel	REMOVE LOCKERS. STUDENTS TRASH IN THEM	ARE PUTTING				
Laura Par							
120786	South Building	Hallway/Corridor	8/8/2014		115		\$0.00
Medium	Work In Progress	UPSTAIRS	8/8/2014 8:31:33 AM				
Prospero,	Manuel	PLEASE REMOVE LOCKERS AN (SEE MS SNYDER)	D INSTALL IN P.E				
Laura Par							
125158	South Building	Classroom	11/5/2014		26		\$0.00
Medium	Work In Progress	47-	11/5/2014 8:33:40 AM				
Prospero,	Manuel	AIR CONDITIONER MAKING LOU	D NOISES				
Laura Par	ra						
122262	South Building	Classroom	9/3/2014		89		\$0.00
Medium	Work In Progress	55-WOLLARD	9/3/2014 3:35:43 PM	I			
Prospero,	Manuel	AIR CONDITIONER IS EXTREME ARE GETTING WET	LY LOUD AND TILES				
Laura Par	ra						
124448	North Building	Classroom	10/22/2014		40		\$0.00
Medium	Work In Progress	6-BAILEY	10/22/2014 10:51:27				
Prospero,	Manuel	CEILING LEAKING.					
Laura Par							
	3:28:31 PM						76 of 195

WOID	te Range for Request Building	Area	Deferred By	Until Request Date	Target Comp Date	Days Aged	Labor Hours	Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date Action Taken	Agea	nouro	
Assigned [·] Requester		Description			ACTION TAKEN			
-								
Location:	Santa Te							
123945	North Building	Classroom		10/9/2014		53		\$0.00
Medium	Work In Progress	12-CRAVENS		10/9/2014 3:13:19 PM	1			
Prospero,	Manuel			T SINK /ED WITH SCREWS				
Laura Par	ra							
125754				11/19/2014		12		\$0.00
Medium	Work In Progress			11/19/2014 1:29:20 PM	l			
Prospero,	Manuel	BUILDING MEC	AGE ROOM IN KIT CHANIC A/C UNIT SSICA M. 589.983	IS LEAKING.SNP				
Maritza Go	onzalez							
125952				11/30/2014		1		\$0.00
Medium	Work In Progress			11/30/2014 12:47:03				
Flores, Pe	te	Monthly - STM- schedule detail	JV-0518 PM Servi s.	ce - Refer to PM				
Margret Vi								
125355	North Building	Portables		11/10/2014		21		\$0.00
Medium	Work In Progress			11/10/2014 11:43:10)			
Ontiveros,	Guadalupe	order for the co	nstruction compar	bles with fill dirt in y to have access to n equipment thanks.				
Ismael Ro	odriguez							
123565				10/5/2014	10/13/2014	57		\$0.00
Medium	Work In Progress			10/5/2014 12:42:26 AN	1			
Prospero,	Manuel	Monthly - Santa PMschedule de		Inspection - Refer to				
Margret Vil	llalobos							
125663	North Building	Exterior		11/18/2014		13		\$0.00
Medium	Work In Progress			11/18/2014 8:02:54 AN	1			
Alvarado,	Julio		s before Thursday turkeyluncheon as					
Ismael Ro	odriguez							
120010	North Building	Custodial		7/30/2014		124		\$0.00
Medium	Work In Progress			7/30/2014 7:35:01 AN	1			
Lara, Ralp	h	Rafa Mr.Mendo not working we		nents of keys his are				

WOID Priority Assigned Requeste		Area Deferred B Area Number Reason Description	y Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa MS					
125564	North Building	Custodial	11/14/2014		17		\$0.00
Medium	Work In Progress		11/14/2014 11:12:42				
Lara, Ralp	-	Rafa,the key cylinders in the locking need to be check as p					
Ismael R	odriguez	-					
125415	North Building	Custodial	11/12/2014		19		\$0.00
Medium	Work In Progress		11/12/2014 7:48:40 AM	I			
Lara, Ralı	bh	Rafa i need for you to make it broke thanks	a key for Efren the "P" key				
Ismael R	-	0					<u> </u>
125619	North Building	Custodial	11/17/2014		14		\$0.00
Medium	Work In Progress		11/17/2014 9:36:20 AM	l			
Lara, Ralp	bh	Make a " Q " key for Mr.Rodri	guez				
Ismael R	odriguez						
125838			11/21/2014		10		\$0.00
High	Work In Progress		11/21/2014 8:56:40 AM	I			
Lara, Ralp	bh	Gate key is need at STMS. F construction office. Key need Should you have any questio Ralph Gallegos at 575-882- office. Thank You	led as soon as possible. ns please contact Mr.				
	ie Esparza						
125157	North Building	Custodial	11/5/2014		26		\$0.00
Medium	Work In Progress	CUSTODIAL	11/5/2014 8:32:57 AM	l			
Marquez,	Gerardo	NEED TWO MADE TO HAVE COMPRESSOR	ACCESS TO AIR				
Laura Pa	rra						
123214		Cafeteria	9/25/2014		67		\$0.00
Medium	Work In Progress		9/25/2014 8:17:41 AM	l			
Lara, Ralı	bh	Due to construction going on Teresa Middle School has be for Riverside, there has beer keys, please accept this requ Middle School kitchen area w Riverside	een used to prepare meals o discrepancies with the uest to rekey Santa Teresa				
Demetrio	us Giovas						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By L Area Deferred By Area Number Reason Description		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS					
123487			10/5/2014	11/5/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:41:23 AM				
Prospero,	-	Yearly - Santa Teresa MS U2 (Hea to PMschedule details.					
Margret Vi	llalobos						
123488			10/5/2014	10/21/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:41:24 AM				
Prospero,	Manuel	Monthly - Santa Teresa MS A1 (Wa Refer to PMschedule details.	ll Refr.E/H)(Semi) -				
Margret Vi							
119474	North Building	Office	7/16/2014		138		\$0.00
Medium	Work In Progress		7/16/2014 8:51:30 AM				
Ambriz, Jo	se	7/16/14. CUSTODIAN OFFICE A/C FREON.	SIS LOW PRESSON				
Manuel Pr	-						
124639	South Building	Mechanical	10/27/2014		35		\$0.00
Medium	Work In Progress		10/27/2014 3:30:16 PM				
Ambriz, Jo	se	10/27/14. A/C MECANICAL ROOM NOT WORKING.	I SOUH BUILDING IS				
Manuel Pr	-		11/10/0011				* ••••
125354	Gym (1997)	Restroom	11/10/2014		21		\$0.00
Medium	Work In Progress		11/10/2014 11:37:18				
Ontiveros,	Joe	The toilet in the coaches restroom need to be fix as per coach.	the water doest stop				
Ismael Ro	odriguez	. .	- 100 / 000 / 1				
119987		Restroom	7/29/2014		125		\$0.00
Medium	Work In Progress		7/29/2014 2:43:21 PM				
Ontiveros,	Joe	ROOM 14 SINK IS LEAKING TRAF REPLACE WATER FAUCET.	P AND NEED TO				
Manuel Pr		-					
124583	South Building	Restroom	10/24/2014		38		\$0.00
Medium	Work In Progress	Faculty	10/24/2014 2:55:21 PM				
Ontiveros,	Joe	INSTALL TOILET SEAT COVERS RESTROOM	IN FACULTY				
Laura Par	ra						

WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date Target Con Created Date/Time Actual Con	· · · · · · · · ·	Costs bor urs
Location:	Santa Te	resa MS			
123993	North Building	Classroom	10/10/2014	52	\$0.00
Medium	Work In Progress		10/10/2014 11:16:43		
Ontiveros	, Joe	Need to replace p-trap in RM#12			
Ismael Ro	odriguez				
124892			11/2/2014	29	\$0.00
Medium	Work In Progress		11/2/2014 12:35:13 AM		
Orozco, D	aniel	Yearly - Santa Teresa MS - Grease schedule details.	Trap - Refer to PM		
Margret V					
125668	North Building	Cafeteria	11/18/2014	13	\$0.00
Medium	Work In Progress		11/18/2014 8:20:19 AM		
Prospero	, Manuel	Paint cafeteria interior doors and to turkey luncheon per principle.	uch up before the		
Ismael Ro	-				
124172	South Building	Parking Lot	10/15/2014	47	\$0.00
Medium	Work In Progress		10/15/2014 9:39:22 AM		
Castillo, C	Carlos	10/15/14. THE PHOTO CELL IN SO NOT WORKING NEED REPLACEM			
Manuel P	-				
125690	South Building	Classroom	11/18/2014	13	\$0.00
Medium	Work In Progress	50	11/18/2014 3:08:04 PM		
Castillo, C	Carlos	SET UP OUTLETS FOR 28 COMP FELIX	JTERS- SEE MR.		
Laura Pa					
124447	North Building	Classroom	10/22/2014	40	\$0.00
Medium	Work In Progress	8-VALENZUELA	10/22/2014 10:47:15		
Castillo, C	Carlos	ADD ADDITIONAL OUTLETS TO O LIGHT SWITCH TO BACK ENTRAM OFFICE			
Laura Pai	rra				
125241	Gym (1997)	Parking Lot	11/6/2014	25	\$0.00
Medium	Work In Progress		11/6/2014 3:08:50 PM		
Castillo, C	Carlos	OUTSIDE LIGHTS PARKING LOT (WORK.	GYM AREA DO NOT		
Manuel P	rospero				

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Lo Area Deferred By Area Number Reason Description	ocation, Status Until Request Date Tar Created Date/Time Act			abor Iours	Costs
Location:	Santa Te	resa MS					
125242	North Building	Parking Lot	11/6/2014		25		\$0.00
Medium	Work In Progress		11/6/2014 3:11:37 PM				
Castillo, C	arlos	LIGHTS AROUND BUILDING DO N BUILDING).	IOT WORK (NORTH				
Manuel Pr	ospero						
125243		Parking Lot	11/6/2014		25		\$0.00
Medium	Work In Progress		11/6/2014 3:13:10 PM				
Castillo, C	arlos	11/6/14. SOM LIGHTS PARKING LO WORKING.	DT IS NOT				
Manuel Pr							
120039	South Building	Office	7/30/2014		124		\$0.00
Medium	Work In Progress	MEDINA-	7/30/2014 3:12:13 PM				
Lara, Ralp	h	REMOVE DOOR WITH FRAME AND THE SECURITY OFFICE. OFFICE N LOCKED WHEN ILLEGAL ITEMS H CONFISCATED	NEEDS TO BE				
Laura Par	ra						
125794			11/20/2014		11		\$0.00
Medium	Work In Progress		11/20/2014 10:59:18				
Prospero,	Manuel	Issued new Trane Laptop to Manue	I Prospero.				
125468		Kitchen	11/12/2014		19		\$0.00
Medium	Work In Progress		11/12/2014 3:57:18 PM				
Estrada, J	esus	Section in bathroom & storage not t	iled.				
Maritza Go	onzalez						
120348			8/3/2014		120		\$0.00
Medium	Work In Progress		8/3/2014 12:33:47 AM				
Munoz, Mio	chael	Yearly - Santa Teresa MS Fire Ext. I to PMschedule details.	nsp. (Yearly) - Refer				
Margret Vil	llalobos						
125022			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:30 AM				
Orozco, Da	aniel	Monthly - Santa Teresa MS Range Refer to PMschedule details.	Hood Cleaning -				
Margret Vil	llalobos						

Selected Da WOID Priority	ate Range for Request Building Status	Dates:7/1/2014 - 11/30/2014 Order By Lo Area Deferred By Area Number Reason		Target Comp Date	Days Aged	Labor Hours	Costs
Assigned Requeste	То	Description	oreated Date/Time	Action Taken	C		
Location:		resa MS					
125996			11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:31	1			·
Prospero	, Manuel	Monthly - Santa Teresa MS Monthly Refer to PMschedule details.	/FE Inspection -				
Margret Vi	illalobos						
124981			11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:05 AM	Λ			
Prospero	, Manuel	Monthly - Santa Teresa MS Monthly Refer to PM schedule details.	/FE Inspection -				
Margret Vi	illalobos						
122118			8/31/2014	9/6/2014	92		\$0.00
Medium	Work In Progress		8/31/2014 12:54:43 AN	Л			
Prospero	, Manuel	Monthly - Santa Teresa MS Monthly Refer to PMschedule details.	/FE Inspection -				
Margret Vi	illalobos						
125624		Hallway/Corridor	11/17/2014		14		\$0.00
Medium	Work In Progress		11/17/2014 10:22:57	7			
Ronquillo	, Ruben	11/17/14. WE NEED 8 FERE EXTIN CAUTIONARY MEASURES DUE TO CONSTRUCTION.					
Manuel P	rospero						
125605			11/15/2014		16		\$0.00
Medium	Work In Progress		11/15/2014 12:45:34	1			
Flores, Pe	ete	Yearly - Santa Teresa MS - Mower Refer to PMschedule details.	0416 - Grounds -				
Margret V	illalobos						
125045			11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:44 AN	Λ			
Orozco, D	aniel	Monthly - Santa Teresa MS Fire Su Refer to PMschedule details.	ppression Insp				
Margret Vi							
Count: 62	Work Orders	Avg. Age of WO's 4	0 Te	otal for Santa Teres	a MS	0	\$0.00

WOID Priority Assigned Requeste		Area Area Number Description	Deferred By	Until R	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES							
125046					11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress			11/2/2014	12:36:45 AM				
Orozco, Da	aniel	Monthly-Sunla Refer to PMsch	nd Park ES Fire Sup nedule details.	pression Insp					
Margret Vi	llalobos								
125759					11/19/2014		12		\$0.00
Medium	Work In Progress			11/19/201	4 2:37:48 PM				
Carrasco	Danny	need these filte 20x25x2 = 64 20x30x2=30 16x25x2=64 20x25x1=30 20x22x1=90	ers for new hvac sys	tem					
Carlos He	ernandez								
122203					9/3/2014		89		\$0.00
Medium	Work In Progress	PLAYGROUND)	9/3/201	4 7:24:39 AM				
Hernande	z, Carlos	EQUIPMENT. BROKEN AND BE A SLIDE TH PARTS. PLEA	ASE CHECK PLAY THERE IS A WHITE IS DANGEROUS. IERE, NOW THERE SE SEE MS. DUQU IS. THANK YOU.	ERAIL THAT IS THERE USED T EARE HANGING	6				
David Avil	a								
125269					11/7/2014		24		\$0.00
Medium	Work In Progress	CLASSROOM		11/7/201	4 8:29:47 AM				
Hernande	z, Carlos		N YOU PLEASE CH THE EXHAUST FAN		-				
David Avil	а								
123123					9/24/2014		68		\$0.00
Medium	Work In Progress	MS. CANO -		9/24/201	4 7:21:37 AM				
Hernande	ez, Carlos	MS. CANO'S P NEED TO BE A PORTABLE IS	ED TO HAVE SOME ORTABLE. THERE ADDRESSED QUIC HOUSING THE BO KS WILL BE DAMA HANK YOU.	ARE LEAKS TH KLY. THE OKROOM AND	AT				
David Avil	а								

David Avila

WOID Priority Assigned	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES					
123198			9/25/2014		67		\$0.00
Medium	Work In Progress	KINDER	9/25/2014 7:18:32 AM				
Hernande	z, Carlos	CARLOS- AS PER MR. VANNOSD/ DUQUE: WEEDS ON MAIN AND KINDER PI OVERGROWN; STUDENTS ARE G CAUGHT ON THEIR CLOTHES. PI	AYGROUND ARE GETTING STICKERS				
David Avila	a		0/05/0044		07		* •••••
123208			9/25/2014		67		\$0.00
Medium	Work In Progress	ALL	9/25/2014 7:50:37 AM				
Hernande.	z, Carlos	CARLOS AS PER MR. VAN NOSDA DUQUE: SIDEWALKS AROUND CLASSROO TO BE CHECKED FOR LEVELING AREAS ARE ELEVATED AND ARE CHILDREN AS WELL AS STAFF M AND FALL DURING RECESS AND DISMISSALS.	OM AREAS NEED , SOME OF THESE CAUSING SMALL EMBERS TO TRIP				
David Avila	a						
125332			11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress		11/9/2014 12:41:25 AM				
Hernande	z, Carlos	Monthly - Sunland Park ES Playgro PMschedule details.	und Insp - Refer to				
Margret Vi	llalobos						
125921			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:42				
Hernande	z, Carlos	Monthly - Sunland Park ES Emer L Refer to PMschedule details.	ight Test: Monthly-				
Margret Vi	llalobos						
125922			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:43				
Hernande	z, Carlos	Monthly - Sunland Park ES Exit Sig Refer to PMschedule details.	n Insp: Monthly-				
Margret Vi	llalobos						
124937			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:40 AM				
Hernande		Monthly - Sunland Park ES Exit Sig Refer to PMschedule details.	n Insp: Monthly-				
Margret Vil	llalobos						

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time A		Days Aged	Labor Hours	
Location:	Sunland	Park ES					
124938			11/2/2014	11/10/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:40 AM				
Hernande	z, Carlos	Monthly - Sunland Park ES Emer Refer to PMschedule details.	Light Test: Monthly -				
Margret Vi	llalobos						
124503			10/23/2014		39		\$0.00
Medium	Work In Progress	CLASSROOM	10/23/2014 10:06:57				
Hernande		AS PER MS. CORDERO - PLEASE CHECK UNDERNEATH LEAK AND WATER IS SITTING AN ARE MOSQUITOES.					
David Avila	a		11/5/2014		26		\$0.00
	Mork In Drograda		11/5/2014 9:52:29 AM		20		φ0.00
Medium Hernande	Work In Progress	CLASSROOM CARLOS -	11/5/2014 9.52.29 AW				
		MS. GARCIA MOVED TO CLASSR NEEDS THE SOAP DISPENSER, DISPENSER AND SHELVES FRO IN PREVIOUS ROOM #21. PLEAS FOR INSTRUCTIONS. THANK YO	PAPER TOWEL DM THE BATHROOM SE SEE MS. GARCIA				
David Avila	a						
120344			8/3/2014		120		\$0.00
Medium	Work In Progress		8/3/2014 12:33:44 AM				
Munoz, Mi	chael	Yearly - Sunland Park ES Fire Ext to PMschedule details.	. Insp. (Yearly) - Refer				
Margret Vi	llalobos						
124995			11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:14 AM				
Hernande	z, Carlos	Monthly - Sunland Park ES Month Refer to PMschedule details.	ly FE Inspection -				
Margret Vi	llalobos						
126014			11/30/2014	12/6/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:47:43				
Hernande	z, Carlos	Monthly - Sunland Park ES Month Refer to PMschedule details.	ly FE Inspection -				
Margret Vi	llalobos						

Priority Assigned 1 Requester		Area Number Reason Created Date/Time / Description	Actual Comp Date Action Taken	Aged	Hours	
Location:	Sunland	Park ES				
125023		11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:31 AM				
Orozco, Da		Monthly-Sunland Park ES Range Hood Cleaning - Refer to PMschedule details.				
Margret Vil		01				<u> </u>
123862	Main Building	Classroom 10/8/2014		54		\$0.00
Medium Estrada, Je		10/8/2014 10:05:34 AM the tile is lifting up and could become a safetyproblem this is in room 39.				
Jesus Luc 123705	ero	10/6/2014		56		\$0.00
Medium	Work In Progress	10/6/2014 8:34:47 AM		50		ψ0.00
Lara, Ralph	-	NEED TO SHAVE DOOR DOWN, NEW CARPET WAS INSTALLED IN FRONT ENTRANCE TO LIBRARY.				
Jesus Estr	rada					
120657		8/6/2014		117		\$0.00
Medium	Work In Progress	8/6/2014 1:56:14 PM				
Gallegos, I	Rafael	WALK IN REFRIGERATOR IS NOT COOLING. SNP MANAGER IGNACIA C. 589.2545				
Maritza Go	nzalez					
124000		10/10/2014		52		\$0.00
Medium	Work In Progress	10/10/2014 3:22:39 PM				
Castillo, Ca		electrical panel outside portable Aneeds to be replaced (rotted out)				
Carlos Hei	rnandez	Portables 8/14/2014		109		\$0.00
121178 Madium	Mork In Drogrado	8/14/2014 10:13:09 AM		109		φ0.00
Medium Castillo, Ca	Work In Progress arlos	need to raise/relocate the electrical service drop to portable to meet code as per attached. this would be the portable on the east side of the school/inside the rock wall (2 class room/metal portable)				
Alfredo Ho	Iguin					
124882		11/2/2014		29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:08 AM				
Orozco, Da	niol	Yearly - Sunland Park ES - Grease Trap - Refer to PM				

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES						
125395				11/10/2014		21		\$0.00
Medium	Work In Progress			11/10/2014 3:34:18 PM	1			
Ontiveros,	Joe	need to replace	toilet room 26					
Carlos He	rnandez							
125246				11/6/2014		25		\$0.00
Medium	Work In Progress			11/6/2014 3:25:51 PM	Л			
Ontiveros,	Joe	need new toilet	for room 21 (has n	niniature toilet)				
Carlos He	rnandez							
123831				10/7/2014		55		\$0.00
Medium	Work In Progress			10/7/2014 3:35:15 PM	Л			
Ambriz, Jo	se	a/c to portable a	a not cooling comp	ressor not turning on				
Carlos He	rnandez							
125622				11/17/2014		14		\$0.00
Medium	Work In Progress	OFFICE		11/17/2014 10:10:07	7			
Lara, Ralp	h		AN NOSDALE - NE STODIAN. PLEASI	ED 1 MASTER KEY E THANK YOU.				
David Avila	a							
125561				11/14/2014		17		\$0.00
Medium	Work In Progress	CLASSROOM		11/14/2014 10:20:49)			
Lara, Ralp	h	20-A. THEY KE	EY THAT IS ASSIGI	CYLINDER IN ROOM NED TO THAT NRK. THANK YOU!				
David Avila								
124522	Main Building	Office		10/23/2014		39		\$0.00
Medium	Work In Progress	Nurses Office		10/23/2014 3:18:25 PM	1			
Lara, Ralp	h	office door, file		2 sets of keys for their ine cabinets . They ank you, Colleen				
Colleen R	unyan							
123555				10/5/2014	10/13/2014	57		\$0.00
Medium	Work In Progress			10/5/2014 12:42:17 AN	1			
Hernande	z, Carlos	Monthly - Sunla PMschedule de		nspection - Refer to				
Margret Vil	lalobos							

WOID	ate Range for Request Building	Area	Deferred By	Until Request Date	Target Comp Date	Days Aged	Labor Hours	Costs
Priority Assigned	Status	Area Number Description	Reason	Created Date/Time	Actual Comp Date Action Taken	Agou	nouro	
Requeste		Description			ACTION TAKEN			
Location:	Sunland	Pork ES						
	Sunianu							
120578				8/5/2014		118		\$0.00
Medium	Work In Progress			8/5/2014 3:30:30 PM	Л			
Ontiveros	, Guadalupe	Pleaseassistw	ith erosion due to ra	in.				
Michael M	lunoz							
124374				10/21/2014		41		\$0.00
Medium	Work In Progress	SCHOOL		10/21/2014 8:19:39 AM	Λ			
Ronquillo	, Ruben	CARLOS-						
		MARQUEE? TH PANELS WHICH WE ARE NOT A THE MARQUEE	N NOSDALE: Y TO FIX THE SCH IERE IS A HOLE IN H MAKES IT LOOK I BLE TO PUT FULL . PLEASE LET US HAT CAN BE DONE	ONE OF THE REALLY BAD AND MESSAGES ON KNOW IF THERE				
David Avila	a							
125812				11/20/2014		11		\$0.00
Medium	Work In Progress			11/20/2014 3:22:02 PN	1			
Ronquillo	, Ruben	need new marq	ue the old one is bro	ken				
Carlos He	ernandez							
123415				9/30/2014		62		\$0.00
Medium	Work In Progress			9/30/2014 3:17:45 P	Л			
Flores, Pe	ete	need tow tires re	paired on lawn mo	werd130 has leak				
Carlos He	ernandez							
Count: 35	Work Orders	Αν	g. Age of WO's 4	5 1	otal for Sunland Par	k ES	0	\$0.00

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Tota Costs
Location:	Sunrise I	ES					
123784			10/7/2014		55		\$0.00
Medium	Work In Progress		10/7/2014 8:57:27 AM	1			
Flores, Pe	te	430 mower need fix not work					
Juan Varg	as						
120861			8/8/2014		115		\$0.00
Medium	Work In Progress		8/8/2014 3:25:05 PN	1			
	Guadalupe	need fix o r replace relase valve pomp	in irrigation buster				
Juan Varg 124146	as Main Building	Restroom	10/14/2014		48		\$0.00
Medium	Work In Progress		10/14/2014 3:13:04 PM	1	10		φ0.00
Gallegos,		Please make sure all urinals hav the screens.					
Debra Fac	cio						
125113			11/3/2014		28		\$0.00
Medium	Work In Progress		11/3/2014 3:48:14 PN	1			
Ontiveros,	Guadalupe	need arena for 2 playgrounds 40) tons.				
Juan Varg	as						
125566	Main Building	Office	11/14/2014		17		\$0.00
Medium	Work In Progress	FRONT OFFICE	11/14/2014 11:51:29)			
Marquez, (Gerardo	JOANNE MUNOZ, FRONT OFFIC CABINET KEY REPLACE THE C IN HALF.					
Joanne Mu	unoz						
124889			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:35:12 AM	1			
Orozco, Da		Yearly - Sunrise ES - Grease Tra schedule details.	ap - Refer to PM				
Margret Vil	llalobos		7/01/0014		100		¢0.00
120097 Madium			7/31/2014		123		\$0.00
Medium	Work In Progress		7/31/2014 12:37:15 PN	I			
Appelzolle		replasar llave pegada ala pare	d tiene lick in 200 wing				
Juan Varg	as		014/0014		4.00		.
120182			8/1/2014		122		\$0.00
Medium	Work In Progress		8/1/2014 12:10:52 PN	1			
Appelzolle	r, Fred	need replace map sinck and fou	iset is broke				
Juan Varg	as						
12/1/2014	3:28:32 PM					Dogo 19	39 of 195

12/1/2014 3:28:32 PM

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2014 - 11/30/2014 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunrise E	ES					
124690			10/28/2014		34		\$0.00
Medium	Work In Progress		10/28/2014 3:28:58 PM	I			
Appelzollei	r, Fred	200 boy r.room need fix or replace	sink foucet				
Juan Varga	as						
122835			9/16/2014		76		\$0.00
Medium	Work In Progress		9/16/2014 12:45:28 PN	I			
Vallejo, Alb	pert	NEED REPLACE LIGHTS IN R.R.	DOMS				
Juan Varga	as						
125894			11/30/2014		1		\$0.0
Medium	Work In Progress		11/30/2014 12:46:24	ļ			
Vargas, Ju	an	Monthly - Sunrise ES A-11 Quarterly schedule details.	ERV - Refer to PM				
Margret Vil	lalobos		4.4./00/004.4				
125895			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:24	ļ			
Vargas, Ju		Monthly - Sunrise ES C-6 Quarterly schedule details.	HP - Refer to PM				
Margret Vill 125896	laiodos		11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:25		•		φ0.00
		Monthly - Sunrise ES C-4 Quarterly		,			
Vargas, Ju	an	schedule details.					
Margret Vil	lalobos						
125897			11/30/2014		1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:26	i			
Vargas, Ju		Monthly - Sunrise ES A-6 Quarterly I schedule details.	PUG - Refer to PM				
Margret Vil	lalobos		44/0/0044				<u> </u>
124979			11/2/2014		29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:04 AM	1			
Apodaca, N		Monthly - Sunrise ES - Lift Station In PMschedule details.	spection - Refer to				
Margret Vil	lalobos		44/0/0044	11/05/0014	<u></u>		¢0.00
125342			11/9/2014		22		\$0.00
Medium	Work In Progress		11/9/2014 12:41:39 AM	1			
Vargas, Ju		Monthly - Sunrise ES Playground In schedule details.	sp - Refer to PM				
Margret Vil	lalobos 3:28:32 PM						

WOID Priority Assigned	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunrise I	ES				
125986		11/30/2014		1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:25	i			
Apodaca, I	Mario	Monthly - Sunrise ES - Lift Station Inspection - Refer to PMschedule details.				
Margret Vil	llalobos					
125762		11/19/2014		12		\$0.00
Medium	Work In Progress	11/19/2014 3:14:55 PM	l			
Estrada, Jo	esus	need replace floor tiles in 100 work room				
Juan Varg	as					
122989		9/19/2014		73		\$0.00
Medium	Work In Progress	9/19/2014 11:25:15 AM	1			
Estrada, Jo	esus	Library carpet has two runs in it south side and north side entrance. Also a pebble underneath a tile is breaking through by main desk.				
Jesus Est	rada					
125024		11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:32 AN	1			
Orozco, Da		Monthly - Sunrise ES Range Hood Cleaning - Refer to PMschedule details.				
Margret Vil	llalobos					
124983		11/2/2014	11/8/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:06 AN	1			
Vargas, Ju		Monthly - Sunrise ES Monthly FE Inspection - Refer to PMschedule details.				
Margret Vil	llalobos	11/00/0011	10/0/0011			
126005		11/30/2014		1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:37				
Vargas, Ju	ian	Monthly - Sunrise ES Monthly FE Inspection - Refer to PMschedule details.				
Margret Vi	llalobos					A = = =
120345		8/3/2014		120		\$0.00
Medium	Work In Progress	8/3/2014 12:33:45 AN	1			
Munoz, Mio		Yearly - Sunrise ES Fire Ext. Insp. (Yearly) - Refer to PMschedule details.				
Margret Vil	llalobos					

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time A Description	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunrise I	ES				
121160	Main Building	Classroom 8/13/2014		110		\$0.00
Medium	Work In Progress	P-8 8/13/2014 4:23:28 PM				
Villalobos	, Margaret	NILDA MATA, P-8, HAS LITTLE SPIDERS IN HER ROOM PLEASE SPRAY				
Joanne M	unoz					
123305		9/26/2014		66		\$0.00
Medium	Work In Progress	9/26/2014 2:42:57 PM				
Vargas, Ju		pick up computer tables in san Miguel and installed new computer room				
Juan Varg	as	44/44/0044		17		\$0.00
125570		11/14/2014		17		\$0.00
Medium	Work In Progress	11/14/2014 1:15:20 PM				
Vargas, Ju	Jan	need replace playground plastic borders north side				
Juan Varg	as					
125960		11/30/2014		1		\$0.00
Medium	Work In Progress	11/30/2014 12:47:08				
Vargas, Ju		Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PMschedule details.				
Margret Vi	llalobos	44/00/0044	4.0/0/0044	4		<u> </u>
125942		11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress	11/30/2014 12:46:56				
Vargas, Ju		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PMschedule details.				
Margret Vi 125943	llalobos	11/30/2014	12/8/2014	1		\$0.00
	Mork In Drogroop		12/0/2014	I		φ0.00
Medium Vargas, Ju	Work In Progress Jan	11/30/2014 12:46:57 Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vi	llalobos					
125047		11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:46 AM				
Orozco, Da	aniel	Monthly-Sunrise ES Fire Suppression Insp Refer to PMschedule details.				
Margret Vi	llalobos					
Count: 30	Work Orders	Avg. Age of WO's 40	Total for Sunris	e ES	0	\$0.00

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2014 - 11/30/2014 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Vado ES						
125048	Vado Lo		11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress		11/2/2014 12:36:46 AM	11/23/2014	23		φ0.00
	0	Manthly Mada EO Eiro Ourragasi					
Orozco, Da	aniei	Monthly - Vado ES Fire Suppression schedule details.	on insp Refer to PM				
Margret Vil	lalobos						
119473	Main Building	Office	7/16/2014		138		\$0.00
Medium	Work In Progress		7/16/2014 8:36:17 AM				
Munoz, Michael		NEED TO REPLACE COUNTER T LOUNGE AND FRONT OFFICE. A					
Debra Fac	bio		0/00/0044		07		* •••••
121807			8/26/2014		97		\$0.00
Medium	Work In Progress		8/26/2014 3:44:16 PM				
Ronquillo,	Ruben	need ceramic tile floor bullnose 4x	4 almond				
Danny Mira	anda						
121347			8/18/2014		105		\$0.00
Medium	Work In Progress		8/18/2014 12:53:38 PM				
Miranda, D	-	need 12 playground swing clamps seats	and 6 rubber swing				
Danny Mira	anda						* • • • •
125334			11/9/2014	11/25/2014	22		\$0.00
Medium	Work In Progress		11/9/2014 12:41:28 AM				
Miranda, D	-	Monthly - Vado ES Playground Ins schedule details.	p - Refer to PM				
Margret Vil	lalobos		44/00/0044	40/0/0044			
125923			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:43				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: I schedule details.	Monthly - Refer to PM				
Margret Vi	lalobos						
125924			11/30/2014	12/8/2014	1		\$0.00
Medium	Work In Progress		11/30/2014 12:46:44				
Miranda, Danny		Monthly - Vado ES Emer. Light Tes PMschedule details.	st: Monthly - Refer to				
Margret Vil	lalobos						

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2014 - 11/30/2014 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Vado ES					
125925		11/30/2014		1		\$0.00
Medium	Work In Progress	11/30/2014 12:46:45				
Miranda, Danny		Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PMschedule details.				
Margret Vil	lalobos					
120346		8/3/2014		120		\$0.00
Medium	Work In Progress	8/3/2014 12:33:46 AV	l			
Munoz, Michael		Yearly - Vado ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.				
Margret Vil	lalobos	11/30/2014	12/6/2014	1		\$0.00
126008				I		φ 0. 0(
Medium	Work In Progress	11/30/2014 12:47:39				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.				
Margret Vil 125025	Ialodos	11/2/2014	11/23/2014	29		\$0.00
Medium	Work In Progress	11/2/2014 12:36:32 AV		20		φ0.00
Orozco, Daniel		Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.				
Margret Vil	lalobos					
123297		9/26/2014		66		\$0.00
Medium	Work In Progress	9/26/2014 1:15:23 PM	1			
Miranda, D	anny	need to paint directioal lines in kitchen, cafeteria area				
Danny Mira	anda					
124232		10/16/2014		46		\$0.00
Medium	Work In Progress	10/16/2014 9:44:09 AM	I			
Solis, Lore	nzo	need to replace blower motor in room 108				
Danny Mira	anda					
124885		11/2/2014		29		\$0.00
Medium	Work In Progress	11/2/2014 12:35:09 AM	I			
Orozco, Daniel		Yearly - Vado ES - Grease Trap - Refer to PM schedule details.				
Margret Vil	lalobos					
124695		10/28/2014		34		\$0.00
Medium	Work In Progress	10/28/2014 3:37:56 PM				
Villalobos,	David	need a new commode put in room 107. tested ran snake, and removed needs to be replaced				
Danny Mira	anda					

Selected Da WOID Priority Assigned Requester	Building Status To				Days Aged	Labor Hours	Total Costs
Location:	Vado ES						
123510			10/5/2014	10/26/2014	57		\$0.00
Medium	Work In Progress		10/5/2014 12:41:42 AM				
Orozco, Da		Monthly - Vado ES F-39 Kitchen Ex Refer to PMschedule details.	h Unit Semiannual -				
Margret Vi	llalobos						
125659			11/18/2014		13		\$0.00
Medium	Work In Progress		11/18/2014 7:38:08 AM				
Ontiveros,	, Guadalupe	need to remove cement slabs from spring rocking horses were	playground were 2				
Danny Mir	anda						
121015			8/12/2014		111		\$0.00
Medium	Work In Progress		8/12/2014 10:20:14 AM				
Ontiveros,	, Guadalupe	need soccor goals two 19ft. (gold m two 12ft. (kwik goal	,				
Danny Mir	anda						
124496			10/23/2014		39		\$0.00
Medium	Work In Progress		10/23/2014 7:38:58 AM				
Flores, Pe	te	need to ck. transmision # 153 slipp warm @ 50- 55 rpm	ing or shifting when				
Danny Mir	anda						
Count: 19	Work Orders	Avg. Age of WO's	9	Total for Vad	o ES	0	\$0.00
Count: 12	257 Work Orders	Avg. Age of WO's	16	Grand Total	0.	25	\$6.25