

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Alta Vista Early College HS									
129721		Office			3/3/2015		15		\$0.00
Medium	Work In Progress	main Office			3/3/2015 2:29:14 PM				
Ambriz, Alfredo Need burnish for a desk (1 qt).									
Alfredo Ambriz									
120833					8/8/2014		222		\$0.00
Medium	Work In Progress				8/8/2014 1:58:33 PM				
Villalobos, David Need to repair water line between the morgan bldg.									
Michael Munoz									
122643	Curriculum and	Office			9/11/2014		188		\$0.00
Medium	Work In Progress				9/11/2014 11:33:24 AM				
Carrasco, Danny Walls in main office and main hallway painted. Wall on the outside of main office to be repaired and painted. Ceiling tiles need to be replaced in main hallway, library bathroom and whenever else needed. Per Mr. Yturralde.									
Minerva Menchaca									
123089		Classroom			9/23/2014		176		\$0.00
Medium	Work In Progress				9/23/2014 3:28:10 PM				
Sotelo, Enrique Connect all new treadmills in the PE portable #504 to the internet/wi-fi									
Minerva Menchaca									
121826	Curriculum and	Portables			8/27/2014		203		\$0.00
Medium	Work In Progress				8/27/2014 8:16:27 AM				
Sotelo, Enrique Ned to fix the power outlet strip on the west side wall of the portable. PE portable #504									
Minerva Menchaca									
128585		Exterior			2/6/2015		40		\$0.00
Medium	Work In Progress	Front Section			2/6/2015 10:40:45 AM				
Ontiveros, Guadalupe NEED TO REMOVE PINE TREES IN FRONT OF MAIN BUILDING.									
Yvette Cortez									
120783	Curriculum and	Classroom			8/8/2014		222		\$0.00
Medium	Work In Progress				8/8/2014 8:03:48 AM				
Ambriz, Jose Install a refrigerated unit in the Rm 504 old PE portable and Rm 501 old Art Room.									
Minerva Menchaca									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Alta Vista Early College HS									
126152					12/3/2014		105		\$0.00
Medium	Work In Progress			12/3/2014 8:43:42 AM					
Munoz, Michael	He is also asking if the remaining concrete can be used as a border for a volley ball court but I need to talk to you on this one.								
Alfredo Holguin									
124395	Curriculum and	Classroom			10/21/2014		148		\$0.00
Medium	Work In Progress			10/21/2014 12:07:07					
Aguilar, Patricio	Need 6 cans of black spraypaint to paint the window guards on the classrooms. Blue paint to paint the handicap parking barrier.								
Minerva Menchaca									
126459		Office			12/10/2014		98		\$0.00
Medium	Work In Progress	Main Office		12/10/2014 10:09:54					
Aguilar, Patricio	NEED SIX STEEL LEG TABLES TO ASSEMBLE DESK AND TABLE IN ADMINISTRATIVE ASSISTANT'S OFFICE AT ALTA VISTA EARLY COLLEGE. PLEASE CONTACT YVETTE FOR ANY INFORMATION.								
Yvette Cortez									
129468					3/1/2015		17		\$0.00
Medium	Work In Progress			3/1/2015 12:45:39 AM					
Aguilar, Patricio	Yearly - Deset Pride HS A10(Heat Pumps)(Yearly) - Refer to PMschedule details.								
Margret Villalobos									
129437					2/28/2015	3/31/2015	18		\$0.00
Medium	Work In Progress			2/28/2015 12:34:48 AM					
Aguilar, Patricio	Yearly - Desert Pride HS C11 (Evap.)(Yearly) - Refer to PMschedule details.								
Margret Villalobos									
129067		Office			2/19/2015		27		\$0.00
Medium	Work In Progress	SECURITY		2/19/2015 10:07:54 AM					
Flores, Pete	PICK UP SECURITY GOLF CART AT SANTA TERESA HIGH SCHOOL AND DELIVER TO PHYSICAL PLANT AUTO SHOP FOR MAINTENANCE AND REPAIRS. CONTACT JUAN TELLEZ AT STHS (915) 355-8887 FOR FURTHER INFORMATION.								
Yvette Cortez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Alta Vista Early College HS

129985 Storage 3/10/2015 8 \$0.00

Medium Work In Progress 3/10/2015 10:29:26 AM

Lara, Ralph Can you come by to make me a lock for my morgan it doesn't lock any more i think i need a knew one thank.

Alfredo Ambriz

127536 Office 1/14/2015 63 \$0.00

Medium Work In Progress Main Office 1/14/2015 2:04:52 PM

Lara, Ralph DOOR TO ASST. PRINCIPAL NEED TO BE REPLACED WITH NEW DOOR.

Yvette Cortez

127540 Office 1/14/2015 63 \$0.00

Medium Work In Progress Principal's Office 1/14/2015 2:10:29 PM

Lara, Ralph DOOR TO PRINCIAPL'S OFFICE IS UNEVEN NEEDS TO BE REPALCED WITH NEW DOOOR.

Yvette Cortez

119421 Classroom 7/15/2014 246 \$0.00

Medium Work In Progress 2nd bldg 7/15/2014 10:04:15 AM

Lara, Ralph Having hard time opening entrance door

David Acosta

119862 7/25/2014 236 \$0.00

Medium Work In Progress 7/25/2014 2:25:32 PM

Lara, Ralph At Alta Vista Early College (Old Desert Pride) change cores off master. Door was the nurse's office door. Refer to e-mail for picture and sketch for door location. Make 2 keys and issue one (1) to George Foster and one (1) to Gema Salcedo. Should you have any questions please contact Mr. Ralph Gallegos at 575- 882-6921 in the Construction office. Thank You

Dominique Esparza

129583 3/1/2015 17 \$0.00

Medium Work In Progress 3/1/2015 12:46:47 AM

Sanchez, Raul Monthly - Desert Pride - Monthly Water Samples - Refer to PMschedule details.

Margret Villalobos

129462 2/28/2015 18 \$0.00

Medium Work In Progress 2/28/2015 12:35:05 AM

Sanchez, Raul Monthly - Desert Pride - Monthly Meter Readings - Refer to PMschedule details.

Margret Villalobos

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Alta Vista Early College HS									
130171					3/14/2015		4		\$0.00
Medium	Work In Progress				3/14/2015 12:21:47 AM				
Sanchez, Raul		Monthly - Alta Vista ECHS- Water Filters - Refer to PM schedule details.							
Margret Villalobos									
128272					2/1/2015		45		\$0.00
Medium	Work In Progress				2/1/2015 12:50:32 AM				
Ronquillo, Ruben		Monthly - Alta Vista ECHS - (Qtrly) Fitness Equip - Refer to PM schedule details.							
Margret Villalobos									
128603					2/6/2015		40		\$0.00
Medium	Work In Progress				2/6/2015 2:35:23 PM				
Ronquillo, Ruben		BELTS ON CARDIO SMART TREADMILLS NEED TO BE REPLACED.							
Yvette Cortez									
129571					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:41 AM				
Ronquillo, Ruben		Monthly - Alta Vista ECHS - (Qtrly) Fitness Equip - Refer to PM schedule details.							
Margret Villalobos									
126236					12/4/2014		104		\$0.00
Medium	Work In Progress				12/4/2014 11:24:06 AM				
Gonzalez, Salvador		Gate does not work property hard to open and close please repair.							
Alfredo Ambriz									
127109					1/6/2015		71		\$0.00
Medium	Work In Progress				1/6/2015 10:14:38 AM				
Gonzalez, Salvador		Can you please come by and weld a pick nick table its one of the the students where they eat for breakfast and lunch thank you.							
Alfredo Ambriz									
Count: 26 Work Orders			Avg. Age of WO's 93			Total for Alta Vista Early College HS	0		\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
128982					2/17/2015		29		\$0.00
Medium	Work In Progress				2/17/2015 3:49:14 PM				
Ronquillo, Ruben		canopy has not been replace this is the second work order since May 2014							
Laura Vazquez									
128783					2/11/2015		35		\$0.00
Medium	Work In Progress				2/11/2015 11:09:42 AM				
Ronquillo, Ruben		02/11/2015. slide at pre k playground has a tear at the bottom end and is potential cut hazard.							
David Escobar									
129315					2/25/2015		21		\$0.00
Medium	Work In Progress				2/25/2015 4:00:19 PM				
Solis, Lorenz		As per Ms. Juana request literacy program rm. 103							
		I had mention to you this morning that the FLC had a leak from one of the pipes, can I request a work order for the maintenance to fix the leak here at the FLC. Thank you							
Laura Vazquez									
121769					8/26/2014		204		\$0.00
Medium	Work In Progress				8/26/2014 9:12:18 AM				
Marquez, Gerardo		speech therapist is having trouble locking door to speech therapy room							
David Vega									
124372					10/21/2014		148		\$0.00
Medium	Work In Progress				10/21/2014 8:07:56 AM				
Marquez, Gerardo		cut out counter top for new sink in the 1st portable. contact person estrella. thank you							
Michael Munoz									
130030					3/11/2015		7		\$0.00
Medium	Work In Progress	Room #105			3/11/2015 11:45:44 AM				
Marquez, Gerardo		REQUESTING KEY FOR DOOR AND KEY FOR GATE							
Noemi Duron									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony - On Track Pre-K (Village)

128397 2/3/2015 43 \$0.00

Medium Work In Progress 2/3/2015 10:11:02 AM

Carrasco, Danny 02/03/2015.
BM needs 5 tubes of 3M acrylic to repair a tear on spiral slide at Pre K village .

David Escobar

130233 3/17/2015 1 \$0.00

Medium Work In Progress 3/17/2015 8:23:58 AM

Carrasco, Danny BMis requesting 5 gallons of white on white paint to finish painting room 105 in village pre-k.

David Escobar

130246 3/17/2015 1 \$0.00

Medium Work In Progress Room # 105 3/17/2015 9:28:39 AM

Escobar, David repair the insulation on the pipes near the ceiling

Noemi Duron

128990 Cafeteria 2/17/2015 29 \$0.00

Medium Work In Progress 882-1904 2/17/2015 4:01:23 PM

Escobar, David please finish painting inside of cafeteria room 101 thank you if any questions please ask Laura or Estrella

Laura Vazquez

129719 Classroom 3/3/2015 15 \$0.00

Medium Work In Progress 882-1904 3/3/2015 2:02:52 PM

Escobar, David David Escobar please find us an other file cabinet for classroom 108 teacher needs to put away some IPODs. the one that she has the lock and key doesn't lock... Thank you, Laura

Laura Vazquez

128989 2/17/2015 29 \$0.00

Medium Work In Progress 882-1904 2/17/2015 3:58:18 PM

Escobar, David finish painting the pre-k we already have the paint that a parent donated since the beginning of the year if any question please ask Laura or Estrella

Laura Vazquez

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
130273		Cafeteria			3/17/2015		1		\$0.00
Medium	Work In Progress	882-1904			3/17/2015 3:22:44 PM				
Vega, David		David starting today please clean the cafeterias when our AM session is over a lot of food is on the floor and yesterday one of employee's had an accident. Thank you, Laura							
Laura Vazquez									
129405		Cafeteria			2/27/2015		19		\$0.00
Medium	Work In Progress	882-1904			2/27/2015 2:20:39 PM				
Vega, David		we are going to received new furniture for the cafeteria rm 101 and 102, when we received the furniture please take out all tables and put away the chairs that are in those rooms. thank you, Laura							
Laura Vazquez									
130187		Classroom			3/16/2015		2		\$0.00
Medium	Work In Progress	882-1904			3/16/2015 11:23:06 AM				
Vega, David		As per Ms. Denise request please clean the bathroom from room 108, vacuum the carpets and mop the classroom.							
Laura Vazquez									
130248					3/17/2015		1		\$0.00
Medium	Work In Progress	Room #105			3/17/2015 10:49:58 AM				
Vega, David		Clean the bathroom and the counter w/ the sink .							
Noemi Duron									
125163		Classroom			11/5/2014		133		\$0.00
Medium	Work In Progress	575-882-1904			11/5/2014 9:36:07 AM				
Sotelo, Daniel		classroom 108 it is licking water next to the light please check it out... it starting to do it on Monday with the rain thank you, Laura							
Laura Vazquez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
121563		Classroom			8/21/2014		19		\$0.00
Medium	Work In Progress	575-882-1904			8/21/2014 9:46:57 AM	9/9/2014			
Sotelo, Daniel		please paint outside the On Track Pre-K @ Anthony the classroom doors form rooms 111,110,109,108, 101 and 102 we already have the paint from a parent the their company donated if you have any questions please contact Estrella thank you, Laura							
Laura Vazquez									
129874					3/6/2015		12		\$0.00
Medium	Work In Progress	ROOM #105			3/6/2015 11:54:22 AM				
Escobar, David		Painting of the walls Cleaning/buffing of the floors Gate and room keys							
Noemi Duron									
Count: 19 Work Orders		Avg. Age of WO's		39	Total for Anthony - On Track Pre-K (Village)			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
130168					3/14/2015		4		\$0.00
Medium	Work In Progress			3/14/2015 12:21:44 AM					
Escobar, David	Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details.								
Margret Villalobos									
129974					3/9/2015		9		\$0.00
Medium	Work In Progress			3/9/2015 4:09:59 PM					
Escobar, David	need to replace 1/2 inch water supplyline and 1/4 inch lines to coolers in Alamo building and off cafeteria.								
David Escobar									
129767					3/4/2015		14		\$0.00
Medium	Work In Progress	DIAGNOSTICIA		3/4/2015 10:44:33 AM					
Escobar, David	INSTALL WALL CABINETS IN DIAGNOSTICIAN ROOM SEE MARGARET FOR CABINETS								
Margaret Villalobos									
129911					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress			3/9/2015 12:35:42 AM					
Escobar, David	Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
125664					11/18/2014		120		\$0.00
Medium	Work In Progress			11/18/2014 8:10:34 AM					
Sotelo, Daniel	need to fix water leak in old cafeteria by Alamo. water line that go's to swamp coolers								
Daniel Sotelo									
126613					12/15/2014		93		\$0.00
Medium	Work In Progress	nurse's hallway		12/15/2014 10:45:01					
Sotelo, Daniel	As per Ms. Perez please check ceiling tile by the nurse entrance (possible leak)								
Jessica Lopez									
126184					12/3/2014		105		\$0.00
Medium	Work In Progress			12/3/2014 3:22:21 PM					
Sotelo, Daniel	Mr. Sotelo, as per Ms. Perez please blow leaves from landscaping								
Jessica Lopez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
126074					12/1/2014		107		\$0.00
Medium	Work In Progress				12/1/2014 3:59:52 PM				
Sotelo, Daniel		need to clean up dead leaves from trees							
Daniel Sotelo									
126091					12/2/2014		106		\$0.00
Medium	Work In Progress				12/2/2014 8:41:34 AM				
Sotelo, Daniel		p-trap in boys bathroom is leaking need to be replaced							
Daniel Sotelo									
126092					12/2/2014		106		\$0.00
Medium	Work In Progress				12/2/2014 8:44:14 AM				
Sotelo, Daniel		need to check light that's out see if its just light bulbs or ballast in room 408							
Daniel Sotelo									
121107					8/13/2014		217		\$0.00
Medium	Work In Progress	SPED			8/13/2014 11:34:37 AM				
Sotelo, Daniel		INSTALL SMALL SLAT WINDOW BLINDS (5) IN OLD AE CAFETERIA TO DECREASE SUNLIGHT (PRESENTATIONS NOT VISIBLE BECAUSE OF TOO MUCH SUNLIGHT)							
Margaret Villalobos									
130177					3/16/2015		2		\$0.00
Medium	Work In Progress	PT OFFICE			3/16/2015 7:41:15 AM				
Gonzales, Camilo		I have a chair that is in my office that I would like to be moved to Ms. Castillo's early childhood classroom at Mesquite elementary. Katrina Garza, PT							
Margaret Villalobos									
129601					3/1/2015	3/7/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:58 AM				
Escobar, David		Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
126873					1/4/2015	1/12/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:12 AM				
Escobar, David		Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
129478					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:45 AM				
Escobar, David		Yearly - Anthony ES A10(Heat Pumps)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
129479					3/1/2015	4/1/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:46 AM				
Escobar, David		Yearly - Anthony ES R3 (Ref. Unit)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
129521					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:11 AM				
Escobar, David		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
129522					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:12 AM				
Escobar, David		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
129429					2/28/2015	3/31/2015	18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:42 AM				
Escobar, David		Yearly - Anthony ES C-11 (Evap.Down)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
125008					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress				11/2/2014 12:36:21 AM				
Orozco, Daniel		Monthly - Anthony ES Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									
123059					9/23/2014		176		\$0.00
Medium	Work In Progress				9/23/2014 10:30:35 AM				
Marquez, Gerardo		KEEYS LOCKED IN SNP VEHICLE 132.							
Maritza Gonzalez									
129065					2/19/2015		27		\$0.00
Medium	Work In Progress				2/19/2015 8:54:24 AM				
Marquez, Gerardo		replace broken door latch due to vandelizm							
David Vega									
3/18/2015 12:54:21 PM									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
128486					2/4/2015		42		\$0.00
Medium	Work In Progress				2/4/2015 3:46:09 PM				
Marquez, Gerardo		BMneeds 10 bathroom stall latches . need to replace missing and broken ones.							
David Escobar									
129888					3/6/2015		12		\$0.00
Medium	Work In Progress				3/6/2015 3:32:13 PM				
Ontiveros, Guadalupe		need to repair 4 sprinkler heads that have been broken and leaking water at main campus soccer field.							
David Escobar									
129973					3/9/2015		9		\$0.00
Medium	Work In Progress				3/9/2015 4:08:17 PM				
Marquez, Gerardo		03/09/2015. need a new key and lock for a file cabinet at pre-k area.							
David Escobar									
129984					3/10/2015		8		\$0.00
Medium	Work In Progress				3/10/2015 10:28:52 AM				
Marquez, Gerardo		Mr. Escobar, As per Ms. Barajas please replace restroom stall locks							
Jessica Lopez									
129782					3/4/2015		14		\$0.00
Medium	Work In Progress	SPED OFFICE			3/4/2015 3:25:14 PM				
Sotelo, Enrique		REPLACE LIGHT BULB IN VAULT IN CHILDFIND OFFICE (SEE MARGARET)							
Margaret Villalobos									
123057					9/23/2014		176		\$0.00
Medium	Work In Progress				9/23/2014 9:58:08 AM				
Orozco, Daniel		PRONG TO SLICER STAYED STUCK IN OUTLET. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									
121985					8/29/2014		201		\$0.00
Medium	Work In Progress				8/29/2014 3:13:57 PM				
Orozco, Daniel		THERE IS A LEAK ON SPRAYER HOSE. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
121986					8/29/2014		201		\$0.00
Medium	Work In Progress				8/29/2014 3:14:16 PM				
Orozco, Daniel		SERVING LINE CLOGGED. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									
121438					8/19/2014		211		\$0.00
Medium	Work In Progress				8/19/2014 2:55:31 PM				
Orozco, Daniel		EXHAUST FAN SWITCH IS NOT WORKING AGAIN. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									
121439					8/19/2014		211		\$0.00
Medium	Work In Progress				8/19/2014 2:56:27 PM				
Orozco, Daniel		NEED METAL COVERS FOR FAN INSIDE WALK IN REFRIGERATOR, SAFETY HAZARD. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									
128740					2/10/2015		36		\$0.00
Medium	Work In Progress				2/10/2015 2:51:21 PM				
Orozco, Daniel		AS PER ADELE INSPECTION REPORT- CAN OPENER DOES NOT WORK CORRECTLY . HARD TO OPEN.							
Maritza Gonzalez									
129443					2/28/2015		18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:52 AM				
Munoz, Michael		Yearly - Anthony ES - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
120333					8/3/2014		227		\$0.00
Medium	Work In Progress				8/3/2014 12:33:36 AM				
Munoz, Michael		Yearly - Anthony ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.				PM not completed as per schedule			
Margret Villalobos									
126975					1/4/2015		73		\$0.00
Medium	Work In Progress				1/4/2015 12:41:35 AM				
Munoz, Michael		Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Anthony ES									
120712					8/7/2014		223		\$0.00
Medium	Work In Progress				8/7/2014 12:12:51 PM				
Gonzalez, Salvador	Sal we need to build a ladder rack for the gater as per Mike thanks								
Daniel Sotelo									
129343					2/26/2015		20		\$0.00
Medium	Work In Progress				2/26/2015 10:55:35 AM				
Flores, Pete	need weed eater fixed trigger is broken serial#285195352								
David Vega									
Count: 38 Work Orders			Avg. Age of WO's	81	Total for Anthony ES			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Berino ES									
129809					3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 8:43:00 AM				
Flores, Pete		PETE FLORES SIR FRONT TIRE HAS A SLOW LEAK NEED TO FIX TRUCK 007 FRONT LEFT THANK YOU SIR AND GOD BLESS							
Adan Duran									
120406		Custodial			8/4/2014		226		\$0.00
Medium	Work In Progress				8/4/2014 9:29:22 AM				
Flores, Pete		Leaf Blower (G.I.S.D 98-2229) needs repair, it does not want to start .							
Marin Herrera									
128758					2/10/2015		36		\$0.00
Medium	Work In Progress				2/10/2015 3:45:29 PM				
Gonzalez, Salvador		MR SAL GONZLES SIR HAVE TWO MORE BENCHES THAT NEED TO BE REPAIR AND WELDED AND REINSTALLED THANK YOU SIR AND GOD BLESS							
Adan Duran									
130134					3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 12:56:51 PM				
Sanchez, Raul		MR RUAL SANCHEZ SIR NEED TO REPLACE WATER FILTERS FOR MAIN BUILDING WATER TURNING BROWN THANK YOU SIR AND GOD BLESS							
Adan Duran									
126969					1/4/2015	1/25/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:41:30 AM				
Munoz, Michael		Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
130174					3/15/2015		3		\$0.00
Medium	Work In Progress				3/15/2015 12:26:54 AM				
Villalobos, Margret		Monthly - Berino ES - PC Automated Quarterly - Refer to PM schedule details.							
Margret Villalobos									
129444					2/28/2015		18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:53 AM				
Munoz, Michael		Yearly - Berino ES - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Berino ES									
118857					7/1/2014		260		\$0.00
High	Work In Progress				7/1/2014 9:56:44 AM				
Munoz, Michael		need to install new water gong fire bell. district electrician will provide power.							
Michael Munoz									
128332					2/2/2015		44		\$0.00
Medium	Work In Progress				2/2/2015 9:30:43 AM				
Solis, Lorenzo		MR LORENZO SOLIS SIR DESERT PRIDE PORTABLE NOT WORKING PROPERLY NEED TO CHECK THANK YOU SIR AND GOD BLESS							
Adan Duran									
129623					3/2/2015		16		\$0.00
Medium	Work In Progress				3/2/2015 10:01:45 AM				
Ontiveros, Guadalupe		MR LUPE ONTIVEROS SIR CAN YOU PLEASE CHECK SPRINKLER SYSTEM ALARM CAME ON STATION 15-16-17 NOT COMING ON NEED TO START WATERING THANK YOU SIR AND GOD BLESS							
Adan Duran									
128857					2/12/2015		34		\$0.00
Medium	Work In Progress				2/12/2015 3:02:03 PM				
Orozco, Daniel		AS PER ADELES INSPECTION - OVENS ARE NOT HEATING PROPERLY.							
Maritza Gonzalez									
128858					2/12/2015		34		\$0.00
Medium	Work In Progress				2/12/2015 3:03:38 PM				
Orozco, Daniel		AS PER ADELES INSPECTION - TILT SKILLET GOES OFF CONSTANTLY.							
Maritza Gonzalez									
129158					2/23/2015		23		\$0.00
Medium	Work In Progress				2/23/2015 11:24:40 AM				
Sotelo, Enrique		MR ENRIQUE SOTELO SIR HAVE BURN OUT EMERGENCY LIGHT MIDDLE WING NORTH SIDE MEN REST ROOM NEED TO REPLACE TO REPLACE THANK YOU SIR AND GOD BLESS							
Adan Duran									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

120112 7/31/2014 230 \$0.00

Medium Work In Progress 7/31/2014 2:44:15 PM

Sotelo, Enrique MR ENRIQUE SOTELO SIR BREAKER ON AC UNIT ROOMS 105 AND 107 NEEDS TO BE REPLACE IT HAS A 20 AMP AND THE UNIT CALLS FOR A 25 AMP THANK YOU SIR AND GOD BLESS

Adan Duran

130136 Main Building Office 3/13/2015 5 \$0.00

Medium Work In Progress Front Office 3/13/2015 2:05:16 PM

Marquez, Gerardo AS PER MR. GARDEA ASSISTANT PRINCIPAL ADVISED ME TO ORDER A SET OF KEYS, B-1 AND B-2 FOR MARCO ALVARADO THE NEW SECRETARY. THANK YOU PLEASE SEND KEYS B-1 AND KEYS B-2 THANK YOU

Marco Alvarado

130036 3/11/2015 7 \$0.00

Medium Work In Progress 3/11/2015 1:11:41 PM

Ontiveros, Guadalupe MR ALFREDO HOLGUIN SIR NEED BACK HOE HAVE A WATER LEAK BY FIRE LANE ITS DEEP THANK YOU SIR AND GOD BLESS

Adan Duran

125009 11/2/2014 11/23/2014 136 \$0.00

Medium Work In Progress 11/2/2014 12:36:22 AM

Orozco, Daniel Monthly - Berino ES Range Hood Cleaning - Refer to PMschedule details.

Margret Villalobos

126424 12/9/2014 99 \$0.00

Medium Work In Progress 12/9/2014 3:42:21 PM

Orozco, Daniel WARMER IS NOT HEATING. SNP MANAGER ELSA C. 882.2417

Maritza Gonzalez

124129 10/14/2014 155 \$0.00

Medium Work In Progress 10/14/2014 10:08:48

Orozco, Daniel OVEN DOWN. SNP MANAGER ELSA C. 882.2417

Maritza Gonzalez

129772 3/4/2015 14 \$0.00

Medium Work In Progress 3/4/2015 12:22:39 PM

Orozco, Daniel SKILLET KEEPS GOING OFF. SNP MANAGER ELSA C. 882.3410

Maritza Gonzalez

3/18/2015 12:54:21 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
126887					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress			1/4/2015 12:40:24 AM					
Villalobos, David	Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
129199	Main Building	Restroom			2/24/2015		22		\$0.00
Medium	Work In Progress			2/24/2015 7:35:30 AM					
Duran, Adan	There are a total of (7) mirrors in our restrooms that need to be replaced they are stained and it wont come off.				2/25/15 - Adan, asp Alfredo, please verify these are needed, if so, please order mirrors and install.				
Marin Herrera									
129909					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress			3/9/2015 12:35:40 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PMs schedule details.								
Margret Villalobos									
130129					3/13/2015		5		\$0.00
Medium	Work In Progress			3/13/2015 11:01:03 AM					
Holguin, Alfredo	MR ALFREDO HOLGUIN SIR THE GATES HAVE BEEN INSTALL BETWEEN BERINO AND DESERT PRIDE NOW WE NEED TO INSTALL SIDEWALK THANK YOU SIR AND GOD BLESS								
Adan Duran									
Count: 24 Work Orders		Avg. Age of WO's 64			Total for Berino ES			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
129200					2/24/2015		22		\$0.00
Medium	Work In Progress				2/24/2015 7:54:13 AM				
Vallejo, Albert		Repair control panel for irrigation pump.							
Albert Vallejo									
130022					3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 9:00:51 AM				
Vallejo, Albert		requesting 2 pin compact fluorescent lamps pl-c26w philips							
Paul Quinones									
130023					3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 9:11:37 AM				
Vallejo, Albert		requesting L E D EMERGENCY LIGHT type. requesting 12 thanks							
Paul Quinones									
126885					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:22 AM				
Villalobos, David		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
124735					10/29/2014		140		\$0.00
Medium	Work In Progress				10/29/2014 12:28:02				
Orozco, Daniel		BROKEN GASKETS ON FREEZER AND WARMER. SNP MANAGER ESTHER C. 824.0048							
Maritza Gonzalez									
130081					3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 10:08:11 AM				
Ontiveros, Guadalupe		requesting tracter to weed control all open areas @ che,and dte.requesting a permanent tracter @ school site due to only 1 work truck @ che,dte							
Paul Quinones									
122854	WestCentral	Classroom			9/16/2014		183		\$0.00
Medium	Work In Progress	402			9/16/2014 3:28:45 PM				
Marquez, Gerardo		Lost key and need as soon as possible. Wrote a letter to secretary. See Ms. Jackson							
Jennifer Corral									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
125569					11/14/2014		124		\$0.00
Medium	Work In Progress				11/14/2014 1:07:06 PM				
Marquez, Gerardo		double doors located on the west side of building next to cafeteria doors are hard to open with key.							
Paul Quinones									
127588					1/15/2015		62		\$0.00
Medium	Work In Progress				1/15/2015 12:32:10 PM				
Marquez, Gerardo		cafeteria double doors on the west side of cafeteria core fell off and lost.need a new core							
Paul Quinones									
123783					10/7/2014		162		\$0.00
Medium	Work In Progress				10/7/2014 8:55:51 AM				
Orozco, Daniel		DISHWASHER IS LEAKING. SNP MANAGER ESTHER C. 824.0048							
Maritza Gonzalez									
129064					2/19/2015		27		\$0.00
Medium	Work In Progress				2/19/2015 8:45:50 AM				
Orozco, Daniel		AS PER ADELE INSPECTION REPORT.SEAL ON WARMER TORN AND LOOSE.							
Maritza Gonzalez									
128900					2/13/2015		33		\$0.00
Medium	Work In Progress				2/13/2015 11:49:44 AM				
Quinones, Paul		reorder mastercool media celdeck pads to replace the ones that need to be replaced on the existing coolers							
Paul Quinones									
128334					2/2/2015		44		\$0.00
Medium	Work In Progress				2/2/2015 9:35:39 AM				
Quinones, Paul		repipe pvc water lines for the air conditioners in the e-wing, and the 400 wing.							
Paul Quinones									
129439					2/28/2015	3/31/2015	18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:49 AM				
Quinones, Paul		Yearly - Chaparral ES C-11 Evap (Annual) - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
121424	Main Building	Office			8/19/2014		211		\$0.00
Medium	Work In Progress	concession			8/19/2014 1:31:30 PM				
Quinones, Paul		need changing table moved from Chaparral Elementary to GSAC room 109 to Ms. Ruiz. See front office or Mrs. Pargas							
Jennifer Corral									
130264					3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 2:18:13 PM				
Quinones, Paul		need to replace metal partitions in boys rst rm. wing 100							
Paul Quinones									
129923					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:49 AM				
Quinones, Paul		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
129868					3/6/2015		12		\$0.00
Medium	Work In Progress				3/6/2015 10:01:25 AM				
Quinones, Paul		need to replace exhaust fans in portable bathrooms							
Paul Quinones									
128701					2/9/2015		37		\$0.00
Medium	Work In Progress				2/9/2015 4:07:26 PM				
Flores, Pete		please check the brakes to work truck #123							
Paul Quinones									
Count: 19 Work Orders			Avg. Age of WO's 62			Total for Chaparral ES	0		\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral High - Pre-K									
130303					3/18/2015		0		\$0.00
Medium	Work In Progress	Outside			3/18/2015 9:55:00 AM				
Valdez, Pedro		Sprayweeds all around building and set up stake to straighten one of the pine trees.							
Micaela Paniagua									
130045					3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 3:30:22 PM				
Marquez, Gerardo		Gerry - Please get a quote: The NM Mexico Pre-K Department has responded to the situation at Chaparral Pre-K with a suggestion to split the bathroom doors into a "Dutch Door" as we have in the Anthony Pre-K.							
		Jeanne Fields							
Alfredo Holguin									
120159					8/1/2014		229		\$0.00
Medium	Work In Progress	building back			8/1/2014 8:03:09 AM				
Marquez, Gerardo		Repair the back entrance door to the Pre-k Center the handle is broken and having trouble locking and unlocking the door.							
Noemi Duron									
Count: 3 Work Orders		Avg. Age of WO's 79			Total for Chaparral High - Pre-K			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
123340					9/29/2014		170		\$0.00
Medium	Work In Progress				9/29/2014 8:09:29 AM				
Marquez, Gerardo		We will need to add door openers to 4 doors:							
		1. The east exit door by the wall on Wing E.							
		2. The west exit door by the wall on Wing F.							
		3. The east exit doors (2 doors – one into the foyer and one into the building) by the wall on Wing R.							
Alfredo Holguin									
125513	A-Wing				11/13/2014		125		\$0.00
Medium	Work In Progress				11/13/2014 12:07:33				
Marquez, Gerardo		At nurses office key broken in cabinet.							
Alfredo Ortiz									
123083	A-Wing	Library			9/23/2014		176		\$0.00
Medium	Work In Progress	Library			9/23/2014 3:15:03 PM				
Marquez, Gerardo		Please unbolt 2 library shelf units from the wall so they can be moved away from water leaking into library. (Ms. DeVine, library)							
Mireya Meza									
130195					3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 2:34:59 PM				
Marquez, Gerardo		Have Gerry give me an estimate on what it will cost to rekey asp email for Stadium Lights.							
Alfredo Holguin									
125112	H-Wing	Gym			11/3/2014		135		\$0.00
Medium	Work In Progress				11/3/2014 3:47:28 PM				
Marquez, Gerardo		Need to make keys for Amplifier box in Gym.							
Alfredo Ortiz									
130190	Field House	Athletic Field			3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 12:21:59 PM				
Marquez, Gerardo		Need for lock smith install locks and chains on all gates on football field also need to be welded.							
Alfredo Ortiz									
121690	Field House	Athletic Field			8/25/2014		205		\$0.00
Medium	Work In Progress	Baseball shed			8/25/2014 10:20:10 AM				
Marquez, Gerardo		Requesting a metal door with knob & dead bolt locking system to secure inventory of equipment in baseball shed. Please see Gregg Martinez for pictures and report. (Mr. Martinez, baseball shed)							
Mireya Meza									
3/18/2015 12:54:21 PM									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

124515 B-Wing Storage 10/23/2014 146 \$0.00

Medium Work In Progress 10/23/2014 1:39:32 PM

Marquez, Gerardo Need to replace key Cilinder on door, teachers can't open door.

Alfredo Ortiz

124236 A-Wing Office 10/16/2014 153 \$0.00

Medium Work In Progress Front reception 10/16/2014 10:22:52

Marquez, Gerardo The left side door right in front of the reception desk is not locking properly. (Mireya Meza)

Mireya Meza

124831 A-Wing Office 10/31/2014 138 \$0.00

Medium Work In Progress Nurse office 10/31/2014 9:23:18 AM

Marquez, Gerardo Key for one of the nurse's filing cabinet broke off. Please replace. (Fireking, Medeco, #238) (Ms. de Castro, Nurse)

Mireya Meza

130258 Q-Wing Classroom 3/17/2015 1 \$0.00

Medium Work In Progress Q3 3/17/2015 12:13:40 PM

Marquez, Gerardo Door to room Q3 must be looked at because students are able to put a pencil through frame and door which allows them to get in without a key. Please see Amy Garcia or Sara Campbell

Mireya Meza

129945 D-Wing Classroom 3/9/2015 9 \$0.00

Medium Work In Progress D3 3/9/2015 12:25:54 PM

Marquez, Gerardo The key that was made for Mr. Pringle's teacher desk is still not working properly. (Mireya Meza, D3)

Mireya Meza

129875 A-Wing Dressing Room 3/6/2015 12 \$0.00

Medium Work In Progress GBB Storage 3/6/2015 12:14:44 PM

Marquez, Gerardo Need storage room re-keyed due to various items being stolen/taken from storage. Please make two keys. One for head coach and one will stay in office. (Sofia Payen)

Mireya Meza

130183 3/16/2015 2 \$0.00

Medium Work In Progress 3/16/2015 8:59:52 AM

Ontiveros, Guadalupe Outside Basketball Courts. Missing valve box cover and broken concrete please replace.

Alfredo Holguin

3/18/2015 12:54:21 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

129180 Athletic Field 2/23/2015 23 \$0.00

High Work In Progress 2/23/2015 3:28:21 PM

Ontiveros, Guadalupe wrestling room need to install pads along wall on south-east-west as per Ms. Nougues. 80'

Guadalupe Ontiveros

128087 1/29/2015 48 \$0.00

Medium Work In Progress 1/29/2015 10:12:50 AM

Orozco, Daniel ONE OF THE OVENS IS NOT HEATING AT ALL. SNP
MANAGER JUANITA M. 824.4461

Maritza Gonzalez

128773 Custodial 2/11/2015 35 \$0.00

Medium Work In Progress 2/11/2015 8:07:13 AM

Appelzoller, Fred Need to replace circulating water pump burned out.

Alfredo Ortiz

129032 H-Wing Dressing Room 2/18/2015 28 \$0.00

Medium Work In Progress 2/18/2015 2:13:05 PM

Appelzoller, Fred Need to replace broken toilet in girls locker room.

Alfredo Ortiz

126411 H-Wing Gym 12/9/2014 99 \$0.00

Medium Work In Progress 12/9/2014 11:49:08 AM

Appelzoller, Fred No water pressure on cold side floor sink in Gym
custodians closet

Alfredo Ortiz

128357 G-Wing Restroom 2/2/2015 44 \$0.00

Medium Work In Progress 2/2/2015 3:49:59 PM

Appelzoller, Fred Need to replace broken toilet in G-wing boys restroom.

Alfredo Ortiz

128848 R-Wing Classroom 2/12/2015 34 \$0.00

Medium Work In Progress R3 2/12/2015 12:37:28 PM

Appelzoller, Fred Sinks in room drain slowly. Partially clogged. (Mr.
Soria, R3)

Mireya Meza

125746 R-Wing Classroom 11/19/2014 119 \$0.00

Medium Work In Progress 11/19/2014 11:02:22

Appelzoller, Fred In art classroom Q-Build. Needs new water line and run
drain-pipes for a indoor power washer.

Alfredo Ortiz

3/18/2015 12:54:21 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

128970 2/17/2015 29 \$0.00

Medium Work In Progress 2/17/2015 3:22:54 PM

Appelzoller, Fred Water fountains (they will accommodate both the Baseball & Softball programs)

Terry Alvarado

126794 E-Wing Classroom 12/19/2014 89 \$0.00

Medium Work In Progress E7 12/19/2014 9:43:19 AM

Appelzoller, Fred Please install gas jets in room E7. It is a chemistry room without gas jets. (Ms. Gonzalez, E7)

Mireya Meza

125049 11/2/2014 11/23/2014 136 \$0.00

Medium Work In Progress 11/2/2014 12:36:47 AM

Orozco, Daniel Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

130027 3/11/2015 7 \$0.00

Medium Work In Progress 3/11/2015 10:59:32 AM

Orozco, Daniel Can you please put a work order for my freezer was at 13 yesterday and today its already at 15 the food in there is frozen but I just want to make sure. Thanks for your help!! Juanita

Maritza Gonzalez

130028 3/11/2015 7 \$0.00

Medium Work In Progress 3/11/2015 11:01:06 AM

Orozco, Daniel Can you also put a work order for one of our ovens it isn't heating at all since this morning. Thank you. Juanita

Maritza Gonzalez

126140 A-Wing Kitchen 12/3/2014 105 \$0.00

Medium Work In Progress 12/3/2014 7:41:36 AM

Orozco, Daniel A hot water circulating pump for the Kitchen not working. Need to be replaced.

Alfredo Ortiz

126906 1/4/2015 2/4/2015 73 \$0.00

Medium Work In Progress 1/4/2015 12:40:38 AM

Villalobos, David Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

3/18/2015 12:54:21 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
122910		Football Field			9/17/2014		182		\$0.00
Medium	Work In Progress				9/17/2014 12:08:33 PM				
Vallejo, Albert		Need to run electricity from press-box to front of Bleachers at football field.							
Alfredo Ortiz									
119549	Field House	Restroom			7/17/2014		244		\$0.00
Medium	Work In Progress				7/17/2014 3:54:07 PM				
Vallejo, Albert		Need to replace several light switches in Field house restrooms and waight room.							
Alfredo Ortiz									
130199	A-Wing	Office			3/16/2015		2		\$0.00
Medium	Work In Progress	Sofia Payen			3/16/2015 3:18:03 PM				
Gonzales, Camilo		PLEASE DELIVER THE FOLLOWING ITEMS TO: SOFIA PAYEN							
		PO #141505474 - 6 BOXES (TRACK SUPPLIES) - CHS TRACK							
Terry Alvarado									
121794	Field House	Dressing Room			8/26/2014		204		\$0.00
Medium	Work In Progress				8/26/2014 3:03:15 PM				
Vallejo, Albert		do not have power to exauhst fans will not start.							
Alfredo Ortiz									
128506		Exterior			2/5/2015		41		\$0.00
Medium	Work In Progress				2/5/2015 7:55:49 AM				
Ortiz, Alfredo		Need to caulk and seal windows to prevent water leaks.							
Alfredo Ortiz									
128862		Exterior			2/12/2015		34		\$0.00
Medium	Work In Progress				2/12/2015 3:22:48 PM				
Ortiz, Alfredo		Need to order and replace A/C pads Mastercool.							
Alfredo Ortiz									
130170					3/14/2015		4		\$0.00
Medium	Work In Progress				3/14/2015 12:21:46 AM				
Ortiz, Alfredo		Daily - Chaparral HS - Fire Pump (Biweekly) - Refer to PMschedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

130259 3/17/2015 1 1 \$0.00

Medium Work In Progress 3/17/2015 1:30:54 PM

Ortiz, Alfredo Need to order screws, blabk covers, door stoppers and other supply from grainger

Alfredo Ortiz

129638 A-Wing Gym 3/2/2015 16 1 \$0.00

Medium Work In Progress Trainer room 3/2/2015 2:10:11 PM

Ortiz, Alfredo Need large heavy desk moved from office in gym to field house office. (Stacy Walsh, training room)

Mireya Meza

129033 H-Wing Gym 2/18/2015 28 1 \$0.00

Medium Work In Progress 2/18/2015 2:25:26 PM

Ortiz, Alfredo Need to dis-assemble air handlers two stage cooling system, clogged don't let air go through on both air handlers on Gym roof.

Alfredo Ortiz

129765 F-Wing Restroom (Girls) 3/4/2015 14 1 \$0.00

Medium Work In Progress 3/4/2015 10:36:20 AM

Ortiz, Alfredo Need to replace two flush valves in F-wing restrooms.

Alfredo Ortiz

128839 Field House Storage 2/12/2015 34 1 \$0.00

Medium Work In Progress Football 2/12/2015 9:03:58 AM

Ortiz, Alfredo Ms. Nougues (AD) would like some bars installed in the equipment room. These would be used to hang football jerseys. (Coach Aguilar)

Mireya Meza

130189 B-Wing Classroom 3/16/2015 2 1 \$0.00

Medium Work In Progress 3/16/2015 12:17:22 PM

Ortiz, Alfredo Need to replace several lights bulbs in B-wing classrooms burned out bulbs.

Alfredo Ortiz

129342 Field House Classroom 2/26/2015 20 1 \$0.00

Medium Work In Progress Athletic Training 2/26/2015 10:38:16 AM

Ortiz, Alfredo Wire shelving needs to be hung up on wall. Paper towel dispenser needs to be put on wall. I have both already, along with required hardware. (Mrs. Walsh, athletic training room)

Mireya Meza

3/18/2015 12:54:22 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
130163		Hallway/Corridor			3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 3:57:49 PM				
Ortiz, Alfredo		Need to install new scoching flangeon missing fire sprinkler heads.							
Alfredo Ortiz									
129879		Hallway/Corridor			3/6/2015		12		\$0.00
Medium	Work In Progress				3/6/2015 1:26:15 PM				
Ortiz, Alfredo		Need to clean strainers on Geo thermal water lines on each heating and cooling units.							
Alfredo Ortiz									
129548					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:27 AM				
Ortiz, Alfredo		Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
129549					3/1/2015	4/1/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:28 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
129503					3/1/2015	3/4/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:01 AM				
Ortiz, Alfredo		Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
129477					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:45 AM				
Ortiz, Alfredo		Yearly - Chaparral HS A10 (Heat Pump)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
129428					2/28/2015	3/31/2015	18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:42 AM				
Ortiz, Alfredo		Yearly - Chaparral HS C11 (Evaporative)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

128971 2/17/2015 29 \$0.00

Medium Work In Progress 2/17/2015 3:24:15 PM

Vallejo, Albert Electrical power source at each dugouts.
(Baseball & Softball Fields)

Terry Alvarado

121594 B-Wing Classroom 8/21/2014 209 \$0.00

Medium Work In Progress 8/21/2014 3:32:10 PM

Vallejo, Albert Need to install new wall outlet in B-2 classroom.

Alfredo Ortiz

125053 Athletic Field 11/3/2014 135 \$0.00

Medium Work In Progress 11/3/2014 7:35:53 AM

Valdez, Pedro Need to fix baseball bleachers bent and broken.

Alfredo Ortiz

119906 Field House Athletic Field 7/28/2014 233 \$0.00

Medium Work In Progress Main Soccer 7/28/2014 11:42:35 AM

Valdez, Pedro We are needing the main grass soccer field lined for this Thursday July 31, 2014. We are having an inter squad scrimmage that evening. (Coach Mendoza)

Mireya Meza

130087 Football Field 3/12/2015 6 \$0.00

Medium Work In Progress 3/12/2015 10:22:10 AM

Valdez, Pedro Running Track - There is grass and weeds growing on the inside and outside perimeter of the running track- Apply roundup herbicide

Alfredo Holguin

128279 2/1/2015 45 \$0.00

Medium Work In Progress 2/1/2015 12:50:37 AM

Flores, Pete Monthly - CHS-UV-0513 PM Service - Refer to PM schedule details.

Margret Villalobos

123054 A-Wing Kitchen 9/23/2014 84 \$0.00

Medium Work In Progress Kitchen Area 9/23/2014 9:29:22 AM 12/16/2014

Gallegos, Rafael Kitchen has a water leak coming from the ceiling and its under one of our conventional ovens and it's next to where we prepare most of the food for students. This is a hazard to all the ladies working here as they can slip and fall. (Juanita Montelongo, Kitchen)

Mireya Meza

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
129153					2/23/2015		23		\$0.00
Medium	Work In Progress				2/23/2015 9:47:36 AM				
Ronquillo, Ruben		Cost to repair bleachers as per quote from AK Sales							
Alfredo Holguin									
130244	A-Wing	Exterior			3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 9:16:01 AM				
Ronquillo, Ruben		Attention to Ruben Warehouse Need to send glass company to replace broken window on Cafeteria door 23 1/2 in. X 22 1/2 in. smoked double pain.							
Alfredo Ortiz									
128785	Field House	Storage			2/11/2015		35		\$0.00
Medium	Work In Progress				2/11/2015 12:32:14 PM				
Gonzalez, Salvador		Need welder to fabricate four angle to support a pole to hang football jerseys in football storage room.							
Alfredo Ortiz									
127914	A-Wing	Library			1/26/2015		51		\$0.00
Medium	Work In Progress				1/26/2015 11:07:29 AM				
Solis, Lorenzø		Need to replace circuit board on unit burn out.							
Alfredo Ortiz									
125511	Field House	Athletic Field			11/13/2014		125		\$0.00
Medium	Work In Progress				11/13/2014 12:03:10				
Solis, Lorenzø		Need to fix ice machine at field house snack bar							
Alfredo Ortiz									
129445					2/28/2015		18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:53 AM				
Munoz, Michael		Yearly - Chaparral HS - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
129588					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:50 AM				
Apodaca, Mario		Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
126517	B-Wing	Hallway/Corridor			12/11/2014		97		\$0.00
Medium	Work In Progress				12/11/2014 10:11:40				
Solis, Lorenzø		In cyber cafe Bad odor coming from heating vents.							
Alfredo Ortiz									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Chaparral HS										
130141	R-Wing	Classroom			3/13/2015		5		\$0.00	
Medium	Work In Progress	R-Kitchen / Lobo			3/13/2015 2:55:07 PM					
Solis, Lorenzø		Freezer is not working. Thermostat is running hot. (Ms. Davis, Lobo Den)								
Mireya Meza										
129880	D-Wing	Classroom			3/6/2015		12		\$0.00	
Medium	Work In Progress				3/6/2015 1:28:49 PM					
Solis, Lorenzø		Having trouble with heating unit won't start.								
Alfredo Ortiz										
126976					1/4/2015		73		\$0.00	
Medium	Work In Progress				1/4/2015 12:41:36 AM					
Munoz, Michael		Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos										
126979					1/4/2015		73		\$0.00	
Medium	Work In Progress				1/4/2015 12:41:38 AM					
Munoz, Michael		Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PM schedule details.								
Margret Villalobos										
Count: 69 Work Orders		Avg. Age of WO's 63		Total for Chaparral HS				0	\$0.00	

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
126970					1/4/2015	1/25/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:41:31 AM				
Munoz, Michael		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
118858					7/1/2014		260		\$0.00
High	Work In Progress				7/1/2014 9:58:32 AM				
Munoz, Michael		need to install new water gong bell for fire sprinkler system. district electrician will provide power.							
Michael Munoz									
129448					2/28/2015		18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:56 AM				
Munoz, Michael		Yearly - Chaparral MS - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
119504	Main Building	Gym			7/16/2014		245		\$0.00
High	Work In Progress				7/16/2014 4:11:34 PM				
Estrada, Jesus		Replace warped floor boards in gym (southwest)							
Jesus Estrada									
120816	Main Building	Gym			8/8/2014		222		\$0.00
Medium	Work In Progress				8/8/2014 11:17:35 AM				
Gonzalez, Salvador		Coach would like 3 tether ball poles installed near the outside basketball courts				Route to Sal 10/22/14			
Gidget Mora									
129978		Classroom			3/10/2015		8		\$0.00
Medium	Work In Progress	402			3/10/2015 8:14:08 AM				
Ronquillo, Ruben		Please repair double pane window. Sash is approximately 30"x 60".							
Albert Vallejo									
123096					9/23/2014		176		\$0.00
Medium	Work In Progress				9/23/2014 3:39:33 PM				
Gallegos, Rafael		Roof leaks in 400 hallway.							
Albert Vallejo									
129491					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:53 AM				
Flores, Pete		Monthly - CHM-UV-0514 PM Service - Refer to PM schedule details.							
Margret Villalobos									
3/18/2015 12:54:22 PM									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

125846	Main Building	Restroom			11/21/2014		117		\$0.00
--------	---------------	----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/21/2014 1:47:29 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vallejo, Albert
Fans in restrooms are not working
Women's Restroom in 100 hallway
Mens Restroom in 300 hallway

Gidget Mora

121096					8/13/2014		217		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2014 10:19:11 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vallejo, Albert
Please insulate supply ducts on new refrigeration units.

Albert Vallejo

128084	Main Building	Classroom			1/29/2015		48		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	311			1/29/2015 9:50:55 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Vallejo, Albert
Garden tower project needs the shed to be built

Gidget Mora

130082	Main Building	Classroom			3/12/2015		6		\$0.00
--------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	208			3/12/2015 10:09:46 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Vallejo, Albert
Teacher needs air filters
Teacher needs air filters

Gidget Mora

128722		Classroom			2/10/2015		36		\$0.00
--------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	103			2/10/2015 10:45:18 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Vallejo, Albert
Please repair raised beds

Gidget Mora

128723		Classroom			2/10/2015		36		\$0.00
--------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	103			2/10/2015 10:46:24 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Vallejo, Albert
Please seal outside gardening shed

Gidget Mora

128209					2/1/2015	2/9/2015	45		\$0.00
--------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				2/1/2015 12:49:50 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert
Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.

Margret Villalobos

129427					2/28/2015	3/31/2015	18		\$0.00
--------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				2/28/2015 12:34:41 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vallejo, Albert
Yearly - Chaparral MS C-11 (Swamp Coolers) Yearly - Refer to PM schedule details.

Margret Villalobos

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral MS							
129480					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:46 AM				
Vallejo, Albert		Yearly - Chaparral MS A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
129502					3/1/2015	3/4/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:00 AM				
Vallejo, Albert		Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
129532					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:18 AM				
Vallejo, Albert		Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
129533					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:18 AM				
Vallejo, Albert		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
129535					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:20 AM				
Vallejo, Albert		Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
129536					3/1/2015	4/1/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:20 AM				
Vallejo, Albert		Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
129604					3/1/2015	3/7/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:47:00 AM				
Vallejo, Albert		Monthly - Chaparral MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

129983	Main Building	Classroom			3/10/2015		8		\$0.00
Medium	Work In Progress	103			3/10/2015 9:49:03 AM				
Vallejo, Albert		Please replace pencil sharpener							
Gidget Mora									

129698	Main Building				3/3/2015		15		\$0.00
Medium	Work In Progress	Garden tower			3/3/2015 10:31:26 AM				
Vallejo, Albert		Please kill all weeds in courtyard							
Gidget Mora									

122338	Main Building	Restroom (Girls)			9/4/2014		195		\$0.00
Medium	Work In Progress	Office ladies			9/4/2014 3:13:32 PM				
Vallejo, Albert		Fan is broken-Making noise							
Gidget Mora									

129810	Main Building	Office			3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 8:59:51 AM				
Vallejo, Albert		Please assemble 25 task chairs							
Gidget Mora									

121010	Main Building	Gym			8/12/2014		218		\$0.00
Medium	Work In Progress	400 Hallway			8/12/2014 9:58:13 AM				
Vallejo, Albert		Resume painting of gym /400 hallway							
Gidget Mora									

125222	Main Building	Gym			11/6/2014		132		\$0.00
Medium	Work In Progress				11/6/2014 10:20:59 AM				
Vallejo, Albert		Blue pads in the main gym backboards need to be re-glued or re-bolted. All 6							
Gidget Mora									

126888					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:25 AM				
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

124340					10/20/2014		149		\$0.00
Medium	Work In Progress				10/20/2014 12:33:32				
Orozco, Daniel		AS PER HEALTH DEPARTMENT WALK IN DOOR DOES NOT SHUT COMPLETELY WITH OUT PUSHING IT SHUT.SNP MANAGER SANDRA D. 824.4376							
Maritza Gonzalez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
124842					10/31/2014		138		\$0.00
Medium	Work In Progress				10/31/2014 2:26:36 PM				
Orozco, Daniel		The back doors to warmer seems to be hanging a little from both top hinges. This could be why that warmer takes forever to reach its holding temperature. SNP Manager Sandra D.824.4376							
Maritza Gonzalez									
129771					3/4/2015		14		\$0.00
Medium	Work In Progress				3/4/2015 12:21:39 PM				
Orozco, Daniel		REACH IN REFRIGERATOR IS AT 60 DEGREES. SNP MANAGER SANDRA D. 824-4376							
Maritza Gonzalez									
120809	Main Building	Classroom			8/8/2014		222		\$0.00
Medium	Work In Progress	205			8/8/2014 10:47:57 AM				
Appelzoller, Fred		pipes on sinks need to be fixed							
Gidget Mora									
129626		Restroom			3/2/2015		16		\$0.00
Medium	Work In Progress				3/2/2015 11:05:36 AM				
Appelzoller, Fred		senesecita areglar horinal del 200 hallway esta tirando agua GRACIAS							
M. Carmen Perez									
129627		Restroom			3/2/2015		16		\$0.00
Medium	Work In Progress				3/2/2015 11:09:26 AM				
Appelzoller, Fred		senesecita destapar horinal del 200 hallway GRACIAS							
M. Carmen Perez									
129628		Custodial			3/2/2015		16		\$0.00
Medium	Work In Progress				3/2/2015 11:15:35 AM				
Appelzoller, Fred		senesecita areglar yabe del agua del 400/hallway del cuarto del custodian esta tirando mucha agua GRACIAS							
M. Carmen Perez									
129218		Gym			2/24/2015		22		\$0.00
Medium	Work In Progress				2/24/2015 9:29:32 AM				
Appelzoller, Fred		senesecita areglar escusado delos lockers delas Girls esta tapado senesecita des taparlo							
M. Carmen Perez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
125798	Main Building	Gym			11/20/2014		118		\$0.00
Medium	Work In Progress				11/20/2014 2:02:05 PM				
Sotelo, Enrique		Light switch does not work on main entry into gym. Request all 4 switches be changed to toggle switch							
Gidget Mora									
128088					1/29/2015		48		\$0.00
Medium	Work In Progress				1/29/2015 10:23:00 AM				
Orozco, Daniel		AIR CURTAIN AT BACK DOOR IS NOT WORKING, NEEDS A NEW MOTOR FAN. SNP MANAGER SANDRA D. 824.4376							
Maritza Gonzalez									
128514					2/5/2015		41		\$0.00
Medium	Work In Progress				2/5/2015 10:24:42 AM				
Orozco, Daniel		I need to place a work order for the washer. It doesn't start right away and when it finally does, it doesn't want to drain/spin. SNP Manager Sandra D. 824.4376							
Maritza Gonzalez									
128515					2/5/2015		41		\$0.00
Medium	Work In Progress				2/5/2015 10:26:15 AM				
Orozco, Daniel		Back door seal worn out, needs to be replaced. (as per environment dept.). SNP Manager Sandra D. 824.4376							
Maritza Gonzalez									
128516					2/5/2015		41		\$0.00
Medium	Work In Progress				2/5/2015 10:26:50 AM				
Orozco, Daniel		Freezer door doesn't close completely without having to push it shut. (as per environment dept.) SNP Manager Sandra D. 824.4376							
Maritza Gonzalez									
129777		Classroom			3/4/2015		14		\$0.00
Medium	Work In Progress	205			3/4/2015 1:20:15 PM				
Marquez, Gerardo		Please replace classroom door. It has a large crack on the jamb, hinge side and will not tighten to close properly.							
Albert Vallejo									
119581		Athletic Field			7/18/2014		243		\$0.00
Medium	Work In Progress				7/18/2014 1:31:26 PM				
Ontiveros, Guadalupe		playing fields need to be reseed as per site admin.							
Guadalupe Ontiveros									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
129966	Main Building				3/9/2015		9		\$0.00
Medium	Work In Progress	Security			3/9/2015 3:51:51 PM				
Marquez, Gerardo Girls restroom in security office will not lock									
Gidget Mora									
123710	Main Building	Classroom			10/6/2014		163		\$0.00
Medium	Work In Progress	310			10/6/2014 8:58:44 AM				
Marquez, Gerardo Cabinet locks are very flimsy and can be easily opened									
Gidget Mora									
122690		Hallway/Corridor			9/12/2014		187		\$0.00
Medium	Work In Progress				9/12/2014 9:12:02 AM				
Marquez, Gerardo senesecita arglar chapa delas puertas de 400/hallway GRACIAS									
M. Carmen Perez									
120454	Main Building	Classroom			8/4/2014		226		\$0.00
Medium	Work In Progress	203			8/4/2014 1:56:06 PM				
Marquez, Gerardo Please repair all cabinet doors to close properly 8/13 route to Gerry									
Gidget Mora									
130268	Main Building	Restroom (Girls)			3/17/2015		1		\$0.00
Medium	Work In Progress	300 hallway			3/17/2015 2:59:22 PM				
Marquez, Gerardo Teachers continue to get locked in the restroom. It has been recommended to replace door and door frame									
Gidget Mora									
130019	Main Building	Office			3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 8:03:26 AM				
Marquez, Gerardo Please create key for office of new administrator ASAP (Key should only work for her office and the restroom)									
Gidget Mora									
129066					2/19/2015		27		\$0.00
Medium	Work In Progress				2/19/2015 9:32:26 AM				
Marquez, Gerardo AS PER HEALTH DEPARTMENT DOOR SEAL TO BACK DOOR NEEDS TO FIXED. SNP MANAGER SANDRA D. 824.4376									
Maritza Gonzalez									
118903					7/2/2014		259		\$0.00
Medium	Work In Progress				7/2/2014 12:29:48 PM				
Marquez, Gerardo Replace or repair gym south exit doors									
Albert Vallejo									
3/18/2015 12:54:22 PM									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
119869					7/25/2014		236		\$0.00
Medium	Work In Progress				7/25/2014 3:18:22 PM				
Marquez, Gerardo		Need new closers for south main hall exit doors.							
Albert Vallejo									
Count: 54 Work Orders			Avg. Age of WO's	85		Total for Chaparral MS	0		\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Pride HS

120451 8/4/2014 226 \$0.00

Medium Work In Progress 8/4/2014 1:51:09 PM

Marquez, Gerardo For Desert Pride need three (3) Master keys. Please drop off at Construction office when ready. Should you have any questions please contact Mr. Ralph Gallegos at 575- 882-6921 in the Construction office. Thank You

Dominique Esparza

121338 Portables 8/18/2014 212 \$0.00

Medium Work In Progress 1 & 2 8/18/2014 11:30:07 AM

Marquez, Gerardo DOOR CYLINDER TO STORGE ROOM IN PORTABLE 1 & 2 NEEDS TO BE REPLACED. ALSO, WHEN REPLACING CYLINDER, PLEASE GIVE STORAGE KEY TO MS. SCOTT AND MS. JAMESON-SPED TEACHERS.

Yvette Cortez

124401 Portables 10/21/2014 148 \$0.00

Medium Work In Progress room no.10 10/21/2014 12:25:05

Marquez, Gerardo Door slams heavy and very hard. Need to replace door closer asap.

David Acosta

129936 Portables 3/9/2015 9 \$0.00

Medium Work In Progress room #12 3/9/2015 10:30:47 AM

Marquez, Gerardo door will not shut properly.

David Acosta

121689 Classroom 8/25/2014 205 \$0.00

Medium Work In Progress 101 8/25/2014 10:10:50 AM

Marquez, Gerardo NEED KEY TO READING LAB 180 IN ROOM 101.

Yvette Cortez

130181 Cafeteria 3/16/2015 2 \$0.00

Medium Work In Progress closets 3/16/2015 8:25:39 AM

Marquez, Gerardo need locks for both closets doors were equipment are kept.

David Acosta

121923 8/28/2014 202 \$0.00

Medium Work In Progress 11 & 12 8/28/2014 1:40:28 PM

Appelzoller, Fred TOILET GETS CLOGGED IN PORTABLE 11 & 12. PLEASE CHECK TO SEE WHAT IS CLOGGING THE TOILET.

Yvette Cortez

3/18/2015 12:54:22 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Pride HS							
124127		Office			10/14/2014		155		\$0.00
Medium	Work In Progress	Conference Rm.			10/14/2014 9:54:48 AM				
Villalobos, David		WATER LINE NEEDS TO BE CONNECTED TO ICE MAKER.							
Yvette Cortez									
124388		Office			10/21/2014		148		\$0.00
Medium	Work In Progress	Conference Rm.			10/21/2014 10:30:05				
Villalobos, David		Drainage line needs to be installed in conference rm. 1							
Yvette Cortez									
130251		Restroom			3/17/2015		1		\$0.00
Medium	Work In Progress	portable			3/17/2015 11:09:38 AM				
Villalobos, David		urinal continue to run when flushed.							
David Acosta									
129157		Portables			2/23/2015		23		\$0.00
Medium	Work In Progress	room 1&2			2/23/2015 10:35:05 AM				
Duran, Adan		Principal request: to have wall that divides classroom 1&2 to be removed so it can become one classroom.				3/2/15 Route to Adan, asp A. Holguin, Eric Medina will assist. Please coordinate with him when you are ready.			
David Acosta									
129908					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:40 AM				
Acosta, David		Monthly - QRTLY BLDG INSP REPORT (DP) - Refer to PM's schedule details.							
Margret Villalobos									
124563		Portables			10/24/2014		145		\$0.00
Medium	Work In Progress	15			10/24/2014 8:52:05 AM				
Acosta, David		White board needs to be installed in portable 15.							
Yvette Cortez									
126753		Portables			12/18/2014		90		\$0.00
Medium	Work In Progress	room #14			12/18/2014 11:19:14				
Gallegos, Rafael		Heater is working, blower won't start.							
David Acosta									
127415					1/12/2015		65		\$0.00
Medium	Work In Progress				1/12/2015 3:16:17 PM				
Gallegos, Rafael		MR LORENZO SOLIS SIR THE HEATER AT DESERT PRIDE IN NOT TURNING ON CAN YOU PLEASE CHECK THANK YOU AND GOD BLESS							
Adan Duran									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Pride HS									
130021					3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 8:44:22 AM				
Ronquillo, Ruben		Multi- Purpose/Boxing - Purchase new boxing equipment							
Richard Chavez									
129986		Portables			3/10/2015		8		\$0.00
Medium	Work In Progress	room 1&2			3/10/2015 10:54:31 AM				
Estrada, Jesus		carpet repair is needed where wall was remove in portable							
David Acosta									
129716		Portables			3/3/2015		15		\$0.00
Medium	Work In Progress	room 11 & 12			3/3/2015 1:31:15 PM				
Estrada, Jesus		need to replace floor tile in hallway and restroom between classrooms.							
David Acosta									
124335					10/20/2014		149		\$0.00
Medium	Work In Progress				10/20/2014 10:31:12				
Ontiveros, Guadalupe		PAINT LINES ON BASKETBALL COURT.				Asp Mike, route to Grounds			
Yvette Cortez									
129689		Custodial			3/3/2015		15		\$0.00
Medium	Work In Progress				3/3/2015 10:22:26 AM				
Carbajal, Jimmy		need two more trash barrows.							
David Acosta									
Count: 20 Work Orders			Avg. Age of WO's	92		Total for Desert Pride HS	0		\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail ES							
130186		Custodial			3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 10:18:26 AM				
Estrada, Jesus		Buenos dia Chuy. estos son los portables que se necesitan alfombrar Num,400 se necesita reparar la alfombra se esta desilando. 401 , 402, 403, 404, 408, 410, 411, Arte 413 tiene piso , y final mente 416 y quedarian perfectos.							
Laura Sandoval									
128658					2/9/2015		37		\$0.00
Medium	Work In Progress				2/9/2015 9:19:58 AM				
Ontiveros, Guadalupe		Need to relocate swing set with 2 swings to other side. Please see Coach Scott. Thanks							
Johnny Acuna									
118894					7/2/2014		259		\$0.00
Medium	Work In Progress				7/2/2014 8:23:42 AM				
Acuna, Johnny		Need to patch and re-stitch playground picnic table area Blue Canvas Shade.							
Johnny Acuna									
120033					7/30/2014		231		\$0.00
Medium	Work In Progress				7/30/2014 2:18:04 PM				
Acuna, Johnny		As per Alfredo please order borders needed. Need approx. 22 borders for playground sand to the bigger playground area sets.							
Johnny Acuna									
129433					2/28/2015	3/31/2015	18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:45 AM				
Acuna, Johnny		Yearly - Desert Trail ES C-11 (Evap.Cool)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
129487					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:51 AM				
Acuna, Johnny		Yearly - Desert Trail ES A10 (Heat Pump)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
129512					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:06 AM				
Acuna, Johnny		Monthly - Desert Trail ES- Emer Light Insp:Monthly - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail ES

129513 3/1/2015 3/9/2015 17 \$0.00

Medium Work In Progress 3/1/2015 12:46:07 AM

Acuna, Johnny Monthly - Desert Trail ES - Exit Sign Insp:Monthly -
Refer to PM schedule details.

Margret Villalobos

129514 3/1/2015 17 \$0.00

Medium Work In Progress 3/1/2015 12:46:07 AM

Acuna, Johnny Monthly - Desert Trail ES -Clothes Dryer (Monthly) -
Refer to PM schedule details.

Margret Villalobos

128592 2/6/2015 40 \$0.00

Medium Work In Progress 2/6/2015 11:58:23 AM

Acuna, Johnny Need oil based paint for main building doors.

Johnny Acuna

128593 2/6/2015 40 \$0.00

Medium Work In Progress 2/6/2015 12:01:10 PM

Acuna, Johnny Need 6 swing clamps with swivels for swings top rail.

Johnny Acuna

128594 2/6/2015 40 \$0.00

Medium Work In Progress 2/6/2015 12:03:04 PM

Acuna, Johnny Need 6 (replacement) swing seats

Johnny Acuna

128152 1/30/2015 47 \$0.00

Medium Work In Progress 1/30/2015 12:41:08 PM

Acuna, Johnny Need 4 Drinking classroom bubblers

Johnny Acuna

129610 3/1/2015 3/7/2015 17 \$0.00

Medium Work In Progress 3/1/2015 12:47:03 AM

Acuna, Johnny Monthly - Desert Trail ES - Monthly FE Inpsection -
Refer to PM schedule details.

Margret Villalobos

128895 2/13/2015 33 \$0.00

Medium Work In Progress 2/13/2015 9:16:15 AM

Acuna, Johnny Need a sink faucet goose neck (single lever) Cold Only
for Room #108

Johnny Acuna

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail ES

129889 3/6/2015 12 3/6/2015 3:32:45 PM \$0.00

Medium Work In Progress 3/6/2015 3:32:45 PM

Acuna, Johnny 3-6-15 3/6

.5-check boiler heating system
 3.5-(Front Lobby) remove waterfountain, replace P-trap, make adjustments to measurements on the wall, install new fountain, test for leaks and proper operation.
 2.0-Replace faucet to room #108 classroom sink. \$97.00
 2.0-cut weeds.

Johnny Acuna

129918 3/9/2015 3/24/2015 9 \$0.00

Medium Work In Progress 3/9/2015 12:35:46 AM

Acuna, Johnny Monthly - Desert Trail ES - Playground Insp - Refer to PM schedule details.

Margret Villalobos

129830 3/5/2015 13 \$0.00

Medium Work In Progress 3/5/2015 1:37:00 PM

Acuna, Johnny AS PER ADELE BALESH MONITORING REPORT (2.24.15)- HOLE ON WALL BY MOP SINK IN KITCHEN STORE ROOM.

Maritza Gonzalez

129831 3/5/2015 13 \$0.00

Medium Work In Progress 3/5/2015 1:38:02 PM

Acuna, Johnny AS PER ADELE BALESH MONITORING REPORT (2.24.15)- PEELING CIELING TILES.

Maritza Gonzalez

129338 2/26/2015 20 \$0.00

Medium Work In Progress 2/26/2015 9:32:58 AM

Acuna, Johnny Need Latex (Water Based) and (Oil Based) paint

Johnny Acuna

129679 3/3/2015 15 \$0.00

Medium Work In Progress 3/3/2015 8:02:01 AM

Solis, Lorenzø Need Refrigeration window unit on west wall to be replaced.

Johnny Acuna

126971 1/4/2015 1/25/2015 73 \$0.00

Medium Work In Progress 1/4/2015 12:41:32 AM

Munoz, Michael Monthly - Desert Trail ES - Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

3/18/2015 12:54:22 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail ES									
124678					10/28/2014		141		\$0.00
Medium	Work In Progress				10/28/2014 12:31:36				
Gonzalez, Salvador		Need plate replacement for sidewalk on westside of main building portables area.							
Johnny Acuna									
125181					11/5/2014		133		\$0.00
Medium	Work In Progress				11/5/2014 2:44:50 PM				
Flores, Pete		Please fix fuel gauge to work truck #192							
Johnny Acuna									
129382	Main Building	Classroom			2/26/2015		20		\$0.00
Medium	Work In Progress	304,201			2/26/2015 3:59:03 PM				
Villalobos, Margret		Need treatment in rooms 304,201 due to head lice activity.				2/27/Emailed Bennie			
Elizabeth Hernandez									
129178	Main Building	Classroom			2/23/2015		23		\$0.00
Medium	Work In Progress	110,202,210,41			2/23/2015 3:24:29 PM				
Villalobos, Margret		Need treatment in these room due to head lice activity.				Emailed			
Elizabeth Hernandez									
121108					8/13/2014		217		\$0.00
Medium	Work In Progress				8/13/2014 11:37:57 AM				
Vallejo, Albert		Need assistance with electrical to cafeteria A/c units.							
Johnny Acuna									
129770					3/4/2015		14		\$0.00
Medium	Work In Progress				3/4/2015 12:02:45 PM				
Vallejo, Albert		Main Bldg. (Room #107: Mr. Salas): Please tap into an existing electrical outlet, run conduit on outside of wall, and add and additional 115voutlet for teacher's computer.							
Johnny Acuna									
126889					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:25 AM				
Villalobos, David		Yearly - Desert Trail ES - Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail ES									
122696					9/12/2014		187		\$0.00
Medium	Work In Progress				9/12/2014 11:12:08 AM				
Orozco, Daniel		As per Health Inspection Report-foot pedal (walk-in)door pedal and freezer foot pedal from sinks are leaking.							
Maritza Gonzalez									
125012					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress				11/2/2014 12:36:24 AM				
Orozco, Daniel		Monthly - Desert Trail ES - Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
129828					3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 1:16:35 PM				
Orozco, Daniel		DRYER DOES NOT WANT TO WORK LEAVES TOWELS WET . SNP MANGER PAT C.							
Maritza Gonzalez									
127155					1/6/2015		71		\$0.00
Medium	Work In Progress				1/6/2015 4:06:08 PM				
Appelzoller, Fred		Portable #408: Need a 1/2" water supply valve with (2) 3/8" outlet water supplies to sink and drinking fountain.							
Johnny Acuna									
119597					7/18/2014		243		\$0.00
Medium	Work In Progress				7/18/2014 3:05:40 PM				
Appelzoller, Fred		Need parts to repair broken clean-out.							
Johnny Acuna									
129832					3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 1:38:45 PM				
Appelzoller, Fred		AS PER ADELE BALESH MONITORING REPORT (2.24.15)- WASHER FLOODS ON WASH CYCLE.							
Maritza Gonzalez									
128688					2/9/2015		37		\$0.00
Medium	Work In Progress				2/9/2015 3:43:35 PM				
Orozco, Daniel		METAL FROM THE WALK-IN FLOOR COMING OFF. SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail ES									
128415					2/3/2015		43		\$0.00
Medium	Work In Progress				2/3/2015 2:48:33 PM				
Orozco, Daniel		FAUCET ON DRAIN IN 3 COMPARTMENT SINK IS BROKEN SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
125611		Classroom			11/17/2014		121		\$0.00
Medium	Work In Progress				11/17/2014 8:58:15 AM				
Marquez, Gerardo		NEED TO LOCATE AND DELIVER A URINAL SCREEN FOR WORK BEING DONE ON PORTABLE R.RM. REMODEL.							
Gerardo Marquez									
127657					1/16/2015		61		\$0.00
Medium	Work In Progress				1/16/2015 2:26:12 PM				
Marquez, Gerardo		Please replace main doors and door closures on the westside of main building. (Portables Area)							
Johnny Acuna									
129833					3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 1:39:57 PM				
Marquez, Gerardo		AS PER ADELE BALESH MONITORING REPORT (2.24.15)- RUSTY DOOR FRAME IN STORE ROOM.							
Maritza Gonzalez									
128967					2/17/2015		29		\$0.00
Medium	Work In Progress				2/17/2015 2:14:39 PM				
Appelzoller, Fred		Water is coming out under the washer machine. Thank you. SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
Count: 41 Work Orders			Avg. Age of WO's 63			Total for Desert Trail ES	0		\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

129807	Main Building	Classroom			3/5/2015		13		\$0.00
--------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Portable B			3/5/2015 7:24:30 AM				
--------	------------------	------------	--	--	---------------------	--	--	--	--

Marquez, Gerardo
 The Door is hard to open from the inside out. We are having a hard time trying to leave the room. In addition, opening the door from the outside is also hard. Replace the door please. It is not something that our staff can fix. We need our friendly lock smith. Thank you.

Albert Ortiz

130261					3/17/2015		1		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Outside upper			3/17/2015 1:47:31 PM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
 The sprinklers aren't working properly out there. There are creating puddles and causing for the trees to dry out. (Araujo)

Guadalupe Gonzalez

128066					1/28/2015		49		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/28/2015 3:56:37 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Daniel
 SNOUT ON DRAIN IN 3 COMPARTMENT SINK IS BROKEN SNP MANAGER ELIZABETH D. 589.2425

Maritza Gonzalez

123369					9/29/2014		170		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/29/2014 4:01:13 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
 Company: CALIPER CONSTRUCTION
 Contact Name: FERNIE REYES Contact Phone: (575)635-8919
 Alternate Contact: BLANCA CRUZ Alternate Phone:
 Best Time to Call: Fax No:
 Cell Phone: Pager No:
 Email: blanca@caliperconst.com

Location of Work: LOCATE PER ZONE 1 WORK PLAN

Dominique Esparza

125013					11/2/2014	11/23/2014	136		\$0.00
--------	--	--	--	--	-----------	------------	-----	--	--------

Medium	Work In Progress				11/2/2014 12:36:24 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Daniel
 Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

122564					9/10/2014		189		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/10/2014 9:42:24 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Daniel
 THE RISE PART ON 3 COMPARTMENT SINK IS CLOGGED. SNP MANAGER ELIZABETH D. 589.2425

Maritza Gonzalez

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Desert View ES

126890 1/4/2015 2/4/2015 73 \$0.00

Medium Work In Progress 1/4/2015 12:40:26 AM

Villalobos, David Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

130231 3/17/2015 1 \$0.00

Medium Work In Progress 3/17/2015 8:20:22 AM

Castillo, Carlos
 Company: CARVER ELECTRIC
 Contact Name: JACOB CARVER Contact Phone: (575)527-2127
 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142
 Cell Phone: (575)649-9207 Email: carver@carverelectric.com

Location of Work: LOCATE PER THE DESERT VIEW ELEMENTERY WORK PLAN

Dominique Esparza

130240 3/17/2015 1 \$0.00

Medium Work In Progress 3/17/2015 9:01:54 AM

Castillo, Carlos
 Company: CALIPER CONSTRUCTION
 Contact Name: FERNIE REYES Contact Phone: (575)635-8919
 Email: blanca@caliperconst.com
 Location of Work: CONTACT FERNIE REYES AT (575)-635-8919 TO DEVELOP A WIDE AREA WORK PLAN.

Remarks: CALLER ASKS TO HOLD THE CONFERENCE ON THURSDAY THE 19TH OF MARCH, AT 11:00AM AT 1105 VALLE VISTA DR IN SUNLAND PARK.

Dominique Esparza

129817 3/5/2015 13 \$0.00

Medium Work In Progress 3/5/2015 10:28:49 AM

Castillo, Carlos
 Company: METRO MECHANICAL
 Contact Name: RICHARD MUNOZ Contact Phone: (575)649-5554
 Email: metromechinc@qwestoffice.net

Location of Work: SPOT ENTIRE PROPERTY. OPEN ACCESS; NO HAZARDS

Dominique Esparza

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
128072		Parking Lot			1/29/2015		48		\$0.00
Medium	Work In Progress				1/29/2015 7:23:19 AM				
Castillo, Carlos		As per custodial dept., parking lot light poles are not turning on.							
Carlos Castillo									
128711					2/10/2015		36		\$0.00
Medium	Work In Progress				2/10/2015 8:42:16 AM				
Castillo, Carlos		Due to construction, light pole were disconnected. Need to repair perimeter lighting.							
Carlos Castillo									
124435					10/22/2014		147		\$0.00
Medium	Work In Progress				10/22/2014 9:03:17 AM				
Castillo, Carlos		Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Cell Phone: (575)635-8919 Email: blanca@caliperconstoom							
		Location of Work: SPOT: 100FT RAD FROM CENTER OF INTERSECTION.							
Dominique Esparza									
124806					10/30/2014		139		\$0.00
Medium	Work In Progress				10/30/2014 4:04:18 PM				
Castillo, Carlos		Two lights in the office are not working; need it repaired. Thank you, Ruben							
Ruben Ortiz									
129957		Office			3/9/2015		9		\$0.00
Medium	Work In Progress	In the back of			3/9/2015 3:39:43 PM				
Lara, Ralph		Replace the lock to the door in the back of the front office. It's the door going outside. It doesn't lock properly. (Gonzalez)							
Guadalupe Gonzalez									
130255	Main Building	Gym			3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 11:45:52 AM				
Lara, Ralph		Hi Rafa, as per the principal the coaches need a key that can open their office and the also the locks in the gym. If you could provide them with a key we would really appreciate it. Thank you							
Israel Ortega									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
130260					3/17/2015		1		\$0.00
Medium	Work In Progress	In the back of			3/17/2015 1:35:33 PM				
Lara, Ralph		2nd Request: Replace the lock to the door in the back of the front office. It's the door going outside. It doesn't lock properly. (Araujo)							
Guadalupe Gonzalez									
129866		Exterior			3/6/2015		12		\$0.00
Medium	Work In Progress				3/6/2015 9:54:32 AM				
Ortiz, Ruben		Hi Ruben according to Chuy Estrada there were some cd's and fish line given to you. The purpose for that material is to be used as a pest control to get rid of the pigeon problem that we have here on campus. If you could help us out and install that material we would appreciate it. Thank you and have a nice day							
Israel Ortega									
120662		Classroom			8/6/2014		224		\$0.00
Medium	Work In Progress	Rm. #14			8/6/2014 2:40:13 PM				
Ortiz, Ruben		Air Conditioner not working. (Bueno)							
Guadalupe Gonzalez									
120663		Classroom			8/6/2014		224		\$0.00
Medium	Work In Progress	Rm. #16			8/6/2014 2:40:57 PM				
Ortiz, Ruben		Air Conditioner not working. (Mack)							
Guadalupe Gonzalez									
123052		Classroom			9/23/2014		176		\$0.00
Medium	Work In Progress	School Campus			9/23/2014 9:21:13 AM				
Ortiz, Ruben		2nd Request: Due to the construction need weather strips for the doors to keep insects from coming into the school.							
Guadalupe Gonzalez									
120111		Office			7/31/2014		230		\$0.00
Medium	Work In Progress	Office			7/31/2014 2:16:37 PM				
Ortiz, Ruben		Put banners up on the fence. (Gonzalez)							
Guadalupe Gonzalez									
120105		Library			7/31/2014		230		\$0.00
Medium	Work In Progress	Library			7/31/2014 2:01:36 PM				
Ortiz, Ruben		Move projection screen back towards circulations desk. (Sanchez-Segura)							
Guadalupe Gonzalez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
120106		Library			7/31/2014		230		\$0.00
Medium	Work In Progress	Library			7/31/2014 2:02:45 PM				
Ortiz, Ruben		Paint white window on left side of entrance door to maroon. (Sanchez-Segura)							
Guadalupe Gonzalez									
120107		Library			7/31/2014		230		\$0.00
Medium	Work In Progress	Library			7/31/2014 2:06:39 PM				
Ortiz, Ruben		Paint upper corner triangle of south wall in Golden Yellow like the NM Flag. (Sanchez-Segura)							
Guadalupe Gonzalez									
122783		Classroom			9/15/2014		184		\$0.00
Medium	Work In Progress	Rm. #12			9/15/2014 3:49:22 PM				
Ortiz, Ruben		Take TV down and remove from classroom. (Ramos)							
Guadalupe Gonzalez									
129924					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:50 AM				
Ortiz, Ruben		Monthly - Desert View ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
129742					3/3/2015		15		\$0.00
Medium	Work In Progress				3/3/2015 3:45:03 PM				
Ortiz, Ruben		Upper boys bathroom two toilets are clogged and a urinal; need it worked on. Thank you, Ruben							
Ruben Ortiz									
130137					3/13/2015		5		\$0.00
Medium	Work In Progress	Trees in the			3/13/2015 2:10:59 PM				
Ortiz, Ruben		The trees need to be watered. They are all dying especially an Oak tree.							
Guadalupe Gonzalez									
121789					8/26/2014		204		\$0.00
Medium	Work In Progress				8/26/2014 2:41:33 PM				
Ortiz, Ruben		The sink in the kitchen is clogged. Need it repaired ASAP							
Ruben Ortiz									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
121790					8/26/2014		204		\$0.00
Medium	Work In Progress				8/26/2014 2:42:35 PM				
Ortiz, Ruben		The upper level girl's bathroom, the one faucet is leaking and the other is broken. Need it replaced.							
Ruben Ortiz									
120664					8/6/2014		224		\$0.00
Medium	Work In Progress	Rm. #33			8/6/2014 2:42:09 PM				
Ortiz, Ruben		Air Conditioner not working. (Gutierrez)							
Guadalupe Gonzalez									
129021					2/18/2015		28		\$0.00
Medium	Work In Progress				2/18/2015 9:31:15 AM				
Ortiz, Ruben		Need weed and feed fertilizer for the grass by the rock wall.							
Ruben Ortiz									
129574					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:42 AM				
Ortiz, Ruben		Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
129575					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:43 AM				
Ortiz, Ruben		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
129606					3/1/2015	3/7/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:47:01 AM				
Ortiz, Ruben		Monthly - Desert View ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
129465					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:37 AM				
Ortiz, Ruben		Yearly - Desert View ES A-10 HP Rooftop Yearly - Refer to PMschedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

129441 2/28/2015 3/31/2015 18 \$0.00

Medium Work In Progress 2/28/2015 12:34:51 AM

Ortiz, Ruben Yearly - Desert View ES C-11 Evap Coolers Yearly - Refer to PM schedule details.

Margret Villalobos

129451 2/28/2015 18 \$0.00

Medium Work In Progress 2/28/2015 12:34:58 AM

Ortiz, Ruben Monthly - Desert View ES A-16 Fan Exhaust (Semi) - Refer to PM schedule details.

Margret Villalobos

125536 11/13/2014 125 \$0.00

Medium Work In Progress Front of School 11/13/2014 3:46:34 PM

Munoz, Michael Repair broken sidewalk in the front of school. It can cause someone to trip. (Araujo)

Guadalupe Gonzalez

129818 3/5/2015 13 \$0.00

Medium Work In Progress 3/5/2015 10:29:04 AM

Ontiveros, Joe Company: METRO MECHANICAL
 Contact Name: RICHARD MUNOZ Contact Phone: (575)649-5554
 Email: metromechinc@qwestoffice.net

Location of Work: SPOT ENTIRE PROPERTY. OPEN ACCESS; NO HAZARDS

Dominique Esparza

130241 3/17/2015 1 \$0.00

Medium Work In Progress 3/17/2015 9:02:10 AM

Ontiveros, Joe Company: CALIPER CONSTRUCTION
 Contact Name: FERNIE REYES Contact Phone: (575)635-8919
 Email: blanca@caliperconst.com
 Location of Work: CONTACT FERNIE REYES AT (575)-635-8919 TO DEVELOP A WIDE AREA WORK PLAN.

Remarks: CALLER ASKS TO HOLD THE CONFERENCE ON THURSDAY THE 19TH OF MARCH, AT 11:00AM AT 1105 VALLE VISTA DR IN SUNLAND PARK.

Dominique Esparza

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

130232 3/17/2015 1 \$0.00

Medium Work In Progress 3/17/2015 8:20:44 AM

Ontiveros, Joe
 Company: CARVER ELECTRIC
 Contact Name: JACOB CARVER Contact Phone: (575)527-2127
 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142
 Cell Phone: (575)649-9207 Email: carver@carverelectric.com

Location of Work: LOCATE PER THE DESERT VIEW ELEMENTERY WORK PLAN

Dominique Esparza

128600 2/6/2015 40 \$0.00

Medium Work In Progress 2/6/2015 1:43:42 PM

Ontiveros, Guadalupe Buster pump for irrigation is not working; need it fixed ASAP

Ruben Ortiz

128601 2/6/2015 40 \$0.00

Medium Work In Progress 2/6/2015 1:44:28 PM

Ontiveros, Guadalupe The upper level playground valve no. 1 is not working; need it fixed.

Ruben Ortiz

129979 Custodial 3/10/2015 8 \$0.00

Medium Work In Progress 3/10/2015 8:32:30 AM

Carbajal, Jimmy Hi Jimmy I got a vacuum cleaner that is not working part #C08C00000151. If you could fix it for us please. Thank you

Israel Ortega

129980 Custodial 3/10/2015 8 \$0.00

Medium Work In Progress 3/10/2015 8:34:38 AM

Carbajal, Jimmy Hi Jimmy, I have another vacuum cleaner not working part #20002038. If you could fix it for us please. Thank you

Israel Ortega

129165 Main Building Restroom 2/23/2015 23 \$0.00

Medium Work In Progress 2/23/2015 12:58:21 PM

Ontiveros, Joe Hi Joe we have a leak in one of the urinals in the boys lower grade restrooms. Could you fix that for us please. Thank you

Israel Ortega

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
129819	Main Building	Restroom			3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 10:31:50 AM				
Ontiveros, Joe		Hi Joe the urinal in the boys upper grade level restroom is overflowing and clogged can you please unclogg it thank you							
Israel Ortega									
130256	Main Building	Restroom			3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 11:53:17 AM				
Ontiveros, Joe		Hi Joe, one of the urinals in the boys lower grade level restrooms is clogged. Could you unclogg it please. Thank you							
Israel Ortega									
128045	Main Building	Storage			1/28/2015		49		\$0.00
Medium	Work In Progress				1/28/2015 1:57:31 PM				
Ontiveros, Joe		Hi Joe on the storage that is next to the upper grade level restroom the release valve on the water is leaking. It needs to be replaced. Thank you.							
Israel Ortega									
128046	Main Building	Storage			1/28/2015		49		\$0.00
Medium	Work In Progress				1/28/2015 2:02:36 PM				
Ontiveros, Joe		Hi Joe on the storage next to the restroom the back flow pleventer is leaking can you fix it please. Thank you							
Israel Ortega									
128044	Main Building	Restroom			1/28/2015		49		\$0.00
Medium	Work In Progress				1/28/2015 1:54:55 PM				
Ontiveros, Joe		Hi Joe on the boys upper grade level restrooms the sink faucet is broke. Can you replace it please. Thank you.							
Israel Ortega									
Count: 53 Work Orders			Avg. Age of WO's 75		Total for Desert View ES			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
129266		Hallway/Corridor			2/25/2015		21		\$0.00
High	Work In Progress				2/25/2015 7:53:29 AM				
Estrada, Jesus		Hallway exit inside Human Resources hallway tiles are coming loose.							
Jesus Estrada									
121916					8/28/2014		202		\$0.00
Medium	Work In Progress				8/28/2014 12:23:26 PM				
Ambriz, Jose		Anne de Los Santos would like to place a work order for the possibility of installing an A/C in her office. Approved by Mr. Suggs							
Maritza Gonzalez									
123748		Restroom (Girls)			10/6/2014		163		\$0.00
High	Work In Progress				10/6/2014 3:43:57 PM				
Estrada, Jesus		Replace tile in bathroom it was removed over fall break c wing							
Jesus Estrada									
119230					7/9/2014		252		\$0.00
Medium	Work In Progress				7/9/2014 2:40:00 PM				
Ambriz, Jose		As per Mr. Steve Suggs, he would like a wall a/c unit installed in Richard Acosta and Priscilla Escobar office.							
Maritza Gonzalez									
125499					11/13/2014		125		\$0.00
Medium	Work In Progress				11/13/2014 9:12:15 AM				
Ambriz, Jose		REPLACE UNIT IN KITCHEN AREA. LEAKING FROM COMPRESSOR SECTIONG.							
Maritza Gonzalez									
125240					11/6/2014		132		\$0.00
Medium	Work In Progress				11/6/2014 3:04:25 PM				
Ambriz, Jose		As per Mrs. Gilpin, could you please have the A/C unit in her office replaced due to the very loud noise it makes.							
Maritza Gonzalez									
130031					3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 12:19:59 PM				
Ambriz, Jose		03/11/15-sever room unit there is refrigerant oil in circuit 1.							
Fernando Moncayo									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
128148					1/30/2015		47		\$0.00
Medium	Work In Progress				1/30/2015 11:31:18 AM				
Ontiveros, Joe		A-WING, WOMENS RR BACKING UP.							
Maritza Gonzalez									
126413					12/9/2014		99		\$0.00
Medium	Work In Progress				12/9/2014 1:10:45 PM				
Munoz, Michael		AS PER MR. CHAVEZ, WEST WALL AT PRE-K BETWEEN WINDOWS/GENERATOR NEEDS TO BE REPAIRED.							
Maritza Gonzalez									
126972					1/4/2015	1/25/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:41:32 AM				
Munoz, Michael		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
130018					3/11/2015		7		\$0.00
High	Work In Progress				3/11/2015 8:00:37 AM				
Gonzalez, Salvador		One of the Main Gates has fallen off, need to reweld.							
Richard Chavez									
124231					10/16/2014		153		\$0.00
Medium	Work In Progress				10/16/2014 9:43:06 AM				
Lara, Ralph		NEED KEY TO ROOM 113 IN C WING (ROSIE VILLALOBOS) TO BE PUT BACK ON MASTER, RIGHT NOW IT IS OFF MASTER.							
Maritza Gonzalez									
119593					7/18/2014		243		\$0.00
Medium	Work In Progress				7/18/2014 2:11:02 PM				
Lara, Ralph		PLEASE CHECK SNP STORAGE IN BISTRO, LOCK STUCK CANNOT OPEN.							
Maritza Gonzalez									
129344					2/26/2015		20		\$0.00
Medium	Work In Progress				2/26/2015 12:03:46 PM				
Flores, Pete		need a d110 lawn tractor							
Fernando Moncayo									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
128710		Electrical Room			2/10/2015		36		\$0.00
Medium	Work In Progress				2/10/2015 8:26:17 AM				
Castillo, Carlos		Get quotes and order material for Veh.152 stock.							
Carlos Castillo									
129389		Electrical Room			2/27/2015		19		\$0.00
Medium	Work In Progress				2/27/2015 8:10:09 AM				
Castillo, Carlos		Order replacement hand tools ,truck bumper vise,and traffic cones.							
Carlos Castillo									
129271					2/25/2015		21		\$0.00
Medium	Work In Progress				2/25/2015 8:25:22 AM				
Castillo, Carlos		LIGHTS IN PARKING LOT ARE NOT WORKING PROPERLY.							
Maritza Gonzalez									
130034					3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 12:57:18 PM				
Gonzales, Camilo		AS PER MR. CHAVEZ, PLEASE PICK UP FURNITURE AND BOXES FROM GAC OFFICE AND DELIVER TO WAREHOUSE OFFICE. SEE ARTURO RODRIGUEZ.							
Maritza Gonzalez									
125102		Hallway/Corridor			11/3/2014		135		\$0.00
Medium	Work In Progress				11/3/2014 3:28:00 PM				
Castillo, Carlos		Check hallway dark areas for emergency lighting installation.And install where needed.							
Carlos Castillo									
130234		Office			3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 8:36:08 AM				
Gonzales, Camilo		Deliver 2 boxes. PO# 141505986. ATTN: Finance Department							
Theresa Ramirez									
123425					9/30/2014		169		\$0.00
Medium	Work In Progress				9/30/2014 3:42:13 PM				
,		PROJECT MANAGEMENT & FINAL CLEARANCE FOR ASBESTOS ABATEMENT AT GAC - RESTROOM IN "A" WING							
Alfredo Holguin									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
126891					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:27 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
125026					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress				11/2/2014 12:36:33 AM				
Orozco, Daniel		Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
130184					3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 9:08:12 AM				
Orozco, Daniel		1 MICROWAVE DOWN. SNP MANAGER IRMA V.882.6784							
Maritza Gonzalez									
130185					3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 9:09:03 AM				
Orozco, Daniel		WATER NOZZLE ON COFFEE MACHINE LEAKING. SNP MANAGER IRMA V.882.6784							
Maritza Gonzalez									
122634					9/11/2014		188		\$0.00
Medium	Work In Progress				9/11/2014 9:48:04 AM				
Moncayo, Fernando		ROSA APODACA OFFICE-BURNT SMELL COMING OUT OF WALL UNIT.							
Maritza Gonzalez									
122635					9/11/2014		188		\$0.00
Medium	Work In Progress				9/11/2014 9:48:24 AM				
Moncayo, Fernando		MARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT.							
Maritza Gonzalez									
122154					9/2/2014		197		\$0.00
Medium	Work In Progress				9/2/2014 9:18:11 AM				
Moncayo, Fernando		BALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO.							
Maritza Gonzalez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
121419					8/19/2014		211		\$0.00
Medium	Work In Progress				8/19/2014 11:43:45 AM				
Moncayo, Fernando		NO POWER TO WALL UNIT IN ROSA HIDALGO OFFICE.							
Maritza Gonzalez									
129510					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:05 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
129511					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:05 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
129485					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:49 AM				
Moncayo, Fernando		Yearly - GAC A-10 Heat Pump Cooling Only Yearly - Refer to PM schedule details.							
Margret Villalobos									
130143					3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 3:18:34 PM				
Ontiveros, Guadalupe		please deliver two loads of base coarse							
Fernando Moncayo									
130144					3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 3:20:53 PM				
Ontiveros, Guadalupe		I need to borrow the bobcat please							
Fernando Moncayo									
128774		Electrical Room			2/11/2015		35		\$0.00
Medium	Work In Progress				2/11/2015 8:18:16 AM				
Ontiveros, Guadalupe		Due to bad mud situation when it rains, requesting crusher fine to be spread inside and around electrical-plumbing storage at the Gac.							
Carlos Castillo									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
129917					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:45 AM				
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
130123					3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 8:45:53 AM				
Moncayo, Fernando		Need to relocate white board in this office. Please talk to Calixto							
Cora Ramirez									
130073					3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 7:53:33 AM				
Moncayo, Fernando		ck and service refrigerated air rooftop a/c units							
Fernando Moncayo									
130298					3/18/2015		0		\$0.00
Medium	Work In Progress				3/18/2015 8:42:24 AM				
Moncayo, Fernando		CLOGGED DRAIN AT BISTRO KITCHEN. SNP MANAGER IRMA V. 882.6784							
Maritza Gonzalez									
130176					3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 7:34:32 AM				
Moncayo, Fernando		AS PER ANNE DE LOS SANTOS MR. SUGGS A/C UNIT IS NOT WORKING.							
Maritza Gonzalez									
127997					1/27/2015		50		\$0.00
Medium	Work In Progress				1/27/2015 3:24:10 PM				
Moncayo, Fernando		ck and replace broken or leaking irrigation sprinklers							
Fernando Moncayo									
129596					3/1/2015	3/7/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:55 AM				
Moncayo, Fernando		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
129618					3/2/2015		16		\$0.00
Medium	Work In Progress				3/2/2015 8:00:59 AM				
Moncayo, Fernando		AS PER MARY CHAVEZ, RR IN FRONT OF RECEPTIONIST AREA- SEALS ARE LEAKING.							
Maritza Gonzalez									
3/18/2015 12:54:23 PM									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
129028					2/18/2015		28		\$0.00
Medium	Work In Progress				2/18/2015 11:19:40 AM				
Moncayo, Fernando		CMT RM. PORTABLE HEATER NOT HEATING.							
Maritza Gonzalez									
129029					2/18/2015		28		\$0.00
Medium	Work In Progress				2/18/2015 11:53:36 AM				
Moncayo, Fernando		BROKEN/LOOSE TILE IN FRONT OF ERICA VILLAREAL AND LUPITA CHAVEZ OFFICES , SAFETY HAZARD.							
Maritza Gonzalez									
126541					12/11/2014		97		\$0.00
Medium	Work In Progress				12/11/2014 2:59:29 PM				
Moncayo, Fernando		Conference Room next to Mary Chavez - Re glue wall paper at all areas where its coming lose, properly patch any unused holes in walls, paint entire room							
Alfredo Holguin									
126166					12/3/2014		105		\$0.00
Medium	Work In Progress				12/3/2014 10:24:20 AM				
Moncayo, Fernando		C-WING -LIGHTS NEED TO BE INSTALLED IN HALLWAY WHERE MRS. YTURRALDE IS LOCATED.							
Maritza Gonzalez									
127465					1/13/2015		64		\$0.00
Medium	Work In Progress				1/13/2015 9:54:51 AM				
Moncayo, Fernando		AS PER TORI GILPIN FOUL SMELL COMING FROM VENTS IN C-WING.							
Maritza Gonzalez									
125757					11/19/2014		119		\$0.00
Medium	Work In Progress				11/19/2014 2:18:32 PM				
Moncayo, Fernando		HR REQEUSTING TO HAVE HR CONFERENCE ROOM PAINTED.							
Maritza Gonzalez									
125495					11/13/2014		125		\$0.00
Medium	Work In Progress				11/13/2014 8:36:40 AM				
Moncayo, Fernando		A-WING-WALL NEEDS TO BE FIXED IN MENS HANDICAP RR.							
Maritza Gonzalez									
Count: 50 Work Orders			Avg. Age of WO's	74			Total for GAC	0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		GAC - Pre-K							
124226					10/16/2014		153		\$0.00
Medium	Work In Progress				10/16/2014 8:57:29 AM				
Moncayo, Fernando		RM. 103- SINK IS LEAKING.							
Maritza Gonzalez									
128682		Office			2/9/2015		37		\$0.00
Medium	Work In Progress	work room			2/9/2015 3:36:29 PM				
Moncayo, Fernando		We received our multimedia work station and needs to be assembled.							
Leticia Tangonan									
128085		Classroom			1/29/2015		48		\$0.00
Medium	Work In Progress	103			1/29/2015 9:58:09 AM				
Moncayo, Fernando		We need a pencil sharpener installed in room 103							
Leticia Tangonan									
127751		Classroom			1/21/2015		56		\$0.00
Medium	Work In Progress	101			1/21/2015 10:19:18 AM				
Moncayo, Fernando		please install pencil sharpener in room 101							
Leticia Tangonan									
130072					3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 7:50:48 AM				
Moncayo, Fernando		ckd and service refrigerated air a/c units							
Fernando Moncayo									
128684					2/9/2015		37		\$0.00
Safety	Work In Progress	playground			2/9/2015 3:38:31 PM				
Moncayo, Fernando		The screw holding slide to the structure is coming off (loose).							
Leticia Tangonan									
127305		Athletic Field			1/9/2015		68		\$0.00
Medium	Work In Progress	playground			1/9/2015 2:50:09 PM				
Gonzalez, Salvador		Morgan building, where playground equipment is stored needs a ramp to facilitate/easy access to trikes. Morgan building where playground equipment is stored needs a ramp to make for easy access to trikes, wagons and other playground toys.							
Leticia Tangonan									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC - Pre-K									
127302		Cafeteria			1/9/2015		68		\$0.00
Medium	Work In Progress				1/9/2015 2:40:16 PM				
Ontiveros, Joe		We need our small sink in our cafeteria replaced with a large deep utility/kitchen sink with counters and cabinets.							
Leticia Tangonan									
128391		Classroom			2/3/2015		43		\$0.00
Medium	Work In Progress	201			2/3/2015 9:40:41 AM				
Ontiveros, Joe		The sink faucet in room 201 needs to be replaced. It has been leaking.							
Leticia Tangonan									
Count: 9 Work Orders			Avg. Age of WO's	57		Total for GAC - Pre-K	0		\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden ES									
130193		Football Field			3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 2:14:57 PM				
Ronquillo, Ruben		need immediate assistance...we need three signs " NO TRASPASSING" "EXIT ONLY" " ENTRANCE ONLY"...would greatly appreciate your assistance...							
Loraine Gandara									
129822		Classroom			3/5/2015		13		\$0.00
Medium	Work In Progress	Washigton Work			3/5/2015 10:45:09 AM				
Ronquillo, Ruben		need assistance..one of the windows is slightly broken...need for it to replaced...would greatly appreciate your assistance in this matter....							
Loraine Gandara									
128950					2/17/2015		29		\$0.00
Medium	Work In Progress				2/17/2015 9:23:52 AM				
Ronquillo, Ruben		Basketball Courts - Need to be resurfaced, it's too slippery.							
Richard Chavez									
128953					2/17/2015		29		\$0.00
Medium	Work In Progress				2/17/2015 10:21:24 AM				
Appelzoller, Fred		Remove dead pine trees and check irrigation system to see if its working properly.							
Richard Chavez									
128954					2/17/2015		29		\$0.00
Medium	Work In Progress				2/17/2015 10:26:40 AM				
Appelzoller, Fred		The outside shade north of the school building is rusted. (not sure if there are one or two) both if there are two.							
		It needs to be clean, primed and paint all of the rustic areas.							
		He said, if you look up at it you can see the rust, all must be cleaned, primed and repainted.							
Richard Chavez									
126534					12/11/2014		97		\$0.00
Medium	Work In Progress				12/11/2014 1:56:03 PM				
Appelzoller, Fred		need assistance with repairing jungle gym on the premises... would greatly appreciate your assistance in this matter...							
Loraine Gandara									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden ES									
130049		Mechanical			3/11/2015		7		\$0.00
Medium	Work In Progress			3/11/2015 3:35:33 PM					
Appelzoller, Fred	need a new circulating pump for water heater on C-wing. need one for water heater and a spare one . Taco 009-SF5, 1/8 hp, 120 volts, 3259 rpm.								
Fred Appelzoller									
129916					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress			3/9/2015 12:35:45 AM					
Appelzoller, Fred	Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
129820		Football Field			3/5/2015		13		\$0.00
Medium	Work In Progress			3/5/2015 10:33:27 AM					
Appelzoller, Fred	Good Morning Mr. Applezoller,								
	I do not get to see you in the morning. So would you please check the drippers to see if the plants are getting enough water. Maybe we can save the trees that are still green in the back playground. The gentleman from La Semilla said that we have too much salt in the water and that the drippers might be clogged up. I will be planting Ash Fan Tex trees in the summer. I need to know if they can place another dripper for the trees to receive enough water. And also the plants in front of the school.								
	Thank you,								
	Grace Marquez								
Loraine Gandara									
125788		Office			11/20/2014		118		\$0.00
Medium	Work In Progress			11/20/2014 8:00:37 AM					
Appelzoller, Fred	need spray cans to paint , flower pots out in front about 15 cans of almond or white								
Fred Appelzoller									
128955		Classroom			2/17/2015		29		\$0.00
Medium	Work In Progress			2/17/2015 10:38:06 AM					
Appelzoller, Fred	need 24 PSQ500QD MVOLT FLUORESECT BATTERY PACKS FOR CLASS ROOM LIGHTING FIXTURES								
Fred Appelzoller									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden ES							
129594					3/1/2015	3/12/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:54 AM				
Appelzoller, Fred		Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.							
Margret Villalobos									
129520					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:11 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
129523					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:12 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.							
Margret Villalobos									
129524					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:13 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.							
Margret Villalobos									
129471					3/1/2015	3/17/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:41 AM				
Appelzoller, Fred		Yearly - Gadsden ES A-10 Heat Pump Yearly - Refer to PM schedule details.							
Margret Villalobos									
127977		Mechanical			1/27/2015		50		\$0.00
Medium	Work In Progress				1/27/2015 8:04:13 AM				
Sotelo, Enrique		need electrical outlets in Mech room							
Fred Appelzoller									
123039		Parking Lot			9/23/2014		176		\$0.00
Medium	Work In Progress				9/23/2014 8:35:17 AM				
Sotelo, Enrique		need for the lights to be replaced outside in the parking lot...greatly appreciate your assistance							
Loraine Gandara									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Gadsden ES								
122297		Athletic Field			9/4/2014		195		\$0.00
High	Work In Progress				9/4/2014 9:12:27 AM				
Appelzoller, Fred		need to cut weeds through out site, inside and outside of fence. also the weeds that have been killed with round up need to be cut as well. school is in dire need of weed control. need to include ponds.							
Michael Munoz									
128647					2/9/2015		37		\$0.00
Medium	Work In Progress				2/9/2015 7:43:31 AM				
Orozco, Daniel		ICE MACHINE DOWN. SNP MANAGER EVA M. 882.3410							
Maritza Gonzalez									
128788					2/11/2015		35		\$0.00
Medium	Work In Progress				2/11/2015 2:11:55 PM				
Orozco, Daniel		AS PER ADELE'S INSPECTION REPORT- SLICER MAKES A GRINDING NOISE.							
Maritza Gonzalez									
128789					2/11/2015		35		\$0.00
Medium	Work In Progress				2/11/2015 2:13:11 PM				
Orozco, Daniel		AS PER ADELE'S INSPECTION REPORT- CHOPPER LEAKS OIL.							
Maritza Gonzalez									
129756					3/4/2015		14		\$0.00
Medium	Work In Progress				3/4/2015 7:48:23 AM				
Ontiveros, Guadalupe		need assistance with parking cement barriers....some of them have been moved....would greatly appreciate your assistance in this matter.,							
Loraine Gandara									
122373		Parking Lot			9/5/2014		194		\$0.00
Medium	Work In Progress				9/5/2014 9:46:47 AM				
Ontiveros, Guadalupe		need for cement barriers to be mounted to the asphalt...I would really appreciate if this could be done asap... thank you...							
Loraine Gandara									
127755					1/21/2015		56		\$0.00
Medium	Work In Progress				1/21/2015 11:30:47 AM				
Orozco, Daniel		REACH IN REFRIGERATOR IS FREEZING ITEMS. SNP MANAGER EVA M. 882.3410							
Maritza Gonzalez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden ES							
125027					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress			11/2/2014 12:36:33 AM					
Orozco, Daniel	Monthly - Gadsden ES - Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
125028					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress			11/2/2014 12:36:34 AM					
Orozco, Daniel	Monthly - Gadsden ES - Fire Suppression Insp - Refer to PM schedule details.								
Margret Villalobos									
126909					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress			1/4/2015 12:40:40 AM					
Villalobos, David	Yearly - Gadsden ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
130138		Office			3/13/2015		5		\$0.00
Medium	Work In Progress			3/13/2015 2:27:42 PM					
Gonzales, Camilo	need for warehouse to pick up a CUM box of dead files and send it to Tracy Swinford to warehouse....greatly appreciate your assistance in this matter.....								
Loraine Gandara									
Count: 29 Work Orders		Avg. Age of WO's		55	Total for Gadsden ES			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
125669					11/18/2014		120		\$0.00
Medium	Work In Progress			11/18/2014 8:46:59 AM					
Castillo, Carlos	Assist with replacement of damaged light poles at GHS								
Carlos Castillo									
129676					3/3/2015		15		\$0.00
Medium	Work In Progress			3/3/2015 7:55:21 AM					
Vallejo, Albert	Albert, we need assistance to replace ballasts and lamps around the CTE building and light poles to the south side of campus. We will need 400w MH large base lamps.								
Guillermo Hernandez									
129504					3/1/2015	3/4/2015	17		\$0.00
Medium	Work In Progress			3/1/2015 12:46:01 AM					
Nunez, Arturo	Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
129543					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress			3/1/2015 12:46:24 AM					
Nunez, Arturo	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
121848	Academic Bldg				8/27/2014		203		\$0.00
Medium	Work In Progress			8/27/2014 2:30:48 PM					
Nunez, Arturo	Please replace all window screens.								
Michael Munoz									
129146	Varsity Gym	Restroom (Girls)			2/23/2015		23		\$0.00
Medium	Work In Progress			2/23/2015 9:09:53 AM					
Nunez, Arturo	varsity gym girls coaches office restroom toilet not working tudy already knows about it								
Isaac Holguin									
126221		Dressing Room			12/4/2014		104		\$0.00
Medium	Work In Progress			12/4/2014 9:06:09 AM					
Nunez, Arturo	Requested by Coach J. Vasquez for Football Locker Rooms in Boy's Gym - Fix Lockers.								
Velia Alarcon									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

126051	Boys Gym	Dressing Room			12/1/2014		107		\$0.00
--------	----------	---------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Boys Football			12/1/2014 1:35:09 PM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Nunez, Arturo
Requested by Coach J. Vasquez for Football Locker Room in Boy's Gym - Painting of both locker rooms.

Velia Alarcon

124485					10/22/2014		147		\$0.00
--------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/22/2014 3:49:00 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David
Need to replace vandalize sink faucet in Science #600, Lilly Chavez.

Guillermo Hernandez

125480					11/13/2014		125		\$0.00
--------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2014 7:40:30 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David
Need assistance to repair water leak by the water fountain in the Old English first floor.

Guillermo Hernandez

125481					11/13/2014		125		\$0.00
--------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2014 7:42:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David
Need assistance to unclog sink in the weight room, need drain snake.

Guillermo Hernandez

125482					11/13/2014		125		\$0.00
--------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2014 7:43:50 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David
Need assistance to unclog sink in the girls restroom at the east wing (testing room) of the cafeteria, Need drain snake.

Guillermo Hernandez

127152					1/6/2015		71		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/6/2015 3:58:15 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David
Requested by Mr. G. Jordan for Portable # 10-Toilet is running continuously and not working.

Velia Alarcon

126892					1/4/2015	2/4/2015	73		\$0.00
--------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				1/4/2015 12:40:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

130069 3/12/2015 6 \$0.00

Medium Work In Progress 3/12/2015 7:40:04 AM

Villalobos, David Need assistance or small drain snake to unclog sinks in the weight room girls restroom and testing room girls restroom east wing of the cafeteria.

Guillermo Hernandez

130070 3/12/2015 6 \$0.00

Medium Work In Progress 3/12/2015 7:42:25 AM

Villalobos, David David we need assistance to trouble shoot smell in the restroom at he Administration building, possible self priming valve for the floor drains is not working.

Guillermo Hernandez

130237 3/17/2015 1 \$0.00

Medium Work In Progress 3/17/2015 8:39:17 AM

Villalobos, David Company: CALIPER CONSTRUCTION
Contact Name: FERNIE REYES Contact Phone: (575)635-8919
Email: blanca@caliperconstoom

Location of Work: FRMLAS CRUCES E I-10 TAKE EXIT FOR ANOTHONY APPX 15.0MI, TRN W OHARA RD APPX 4.0MI, TRN S NM-28 APPX 1.0MI TO LOCATION ON RIGHT HAND SIDE OF THE RD SPOT: FRM THE WEST EDGE OF THE RD OF NM-28 APPX 1000FT INTO THE SCHOOL PROPERTY GOING FRM

Remarks: WASHINGTON ST TO HAASVILLE RD NO HAZARDS/OPEN ACCESS

Dominique Esparza

130223 3/16/2015 2 \$0.00

Medium Work In Progress 3/16/2015 3:57:02 PM

Villalobos, David Line locates are needed. Please see e-mail for site layout. For questions please contact Allan Journey of GenCon at 575-644-0810.

Dominique Esparza

123327 9/26/2014 173 \$0.00

Medium Work In Progress 9/26/2014 3:51:00 PM

Orozco, Daniel Walk-in floor has lifted – safety issue. SNP MANAGER FRANCES B. 882.5522

Maritza Gonzalez

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
123328					9/26/2014		173		\$0.00
Medium	Work In Progress				9/26/2014 3:51:26 PM				
Orozco, Daniel		Mop sink is leaking from the floor.SNP MANAGER							
FRANCES B. 882.5522									
Maritza Gonzalez									
126699					12/17/2014		91		\$0.00
Medium	Work In Progress				12/17/2014 8:51:44 AM				
Orozco, Daniel		THREE OVENS NOT HEATING. SNP MANAGER							
FRANCES B. 882.5522.									
Maritza Gonzalez									
126391					12/8/2014		100		\$0.00
Medium	Work In Progress				12/8/2014 3:56:51 PM				
Orozco, Daniel		DISHWASHER-PANS NOT GETTING CLEANED AND							
NOT ENOUGH HOT WATER.SNP MANAGER									
FRANCES B. 882.5522									
Maritza Gonzalez									
121243		Football Field			8/15/2014		215		\$0.00
Medium	Work In Progress				8/15/2014 9:53:18 AM				
Ontiveros, Guadalupe		Need to place lines on the middle grass field so the							
football team can practice.									
William Dickson									
129976					3/10/2015		8		\$0.00
Medium	Work In Progress				3/10/2015 7:37:05 AM				
Ontiveros, Guadalupe		Need to level ground by the stairs on the southwest							
entrance of the Old English.									
Guillermo Hernandez									
129977					3/10/2015		8		\$0.00
Medium	Work In Progress				3/10/2015 7:39:01 AM				
Ontiveros, Guadalupe		Lupe, we need assistance pruning trees in the patio							
inside the Academic building.									
Guillermo Hernandez									
127401					1/12/2015		65		\$0.00
Medium	Work In Progress				1/12/2015 2:37:01 PM				
Ontiveros, Guadalupe		Requested by Coach Lawrence for Grass Soccer Field-							
Update watering system to automatic system. Talked to									
Lupe Ontiveros and he agreed to it.									
Velia Alarcon									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
119592		Athletic Field			7/18/2014		243		\$0.00
Medium	Work In Progress				7/18/2014 2:08:10 PM				
Ontiveros, Guadalupe		Would like to get the grass fields line for competition. First field should be lined as a soccer field and the other lined up as football fields. Thank you!							
William Dickson									
125866		Athletic Field			11/21/2014		117		\$0.00
Medium	Work In Progress				11/21/2014 3:30:35 PM				
Ontiveros, Guadalupe		Requested by Ms. L. Chavez for Softball Field-Warning track needs to be widened and then red dirt needs to replace the sand that was placed there when warning tracks was added. The spoiler in that area floods the warning track area between left field foul line and scoreboard. This is also a safety issue for all softball players.							
Velia Alarcon									
130172					3/14/2015		4		\$0.00
Medium	Work In Progress				3/14/2015 12:21:47 AM				
Hernandez, Guillermo		Daily - Gadsden HS - Fire Pump (Biweekly) - Refer to PM schedule details.							
Margret Villalobos									
129839					3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 3:34:22 PM				
Hernandez, Guillermo		Need to replace missing plastic cover for the lamps in P#12 and P#15.							
Guillermo Hernandez									
129841					3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 3:35:27 PM				
Hernandez, Guillermo		Need to check lights in Mr. Calderon's office at the Academic building.							
Guillermo Hernandez									
129907					3/9/2015		9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:39 AM				
Hernandez, Guillermo		Monthly - Gadsden HS A16 (Fan Exh.)(S. Annual) - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

129787 3/4/2015 14 \$0.00

Medium Work In Progress 3/4/2015 3:35:15 PM

Hernandez, Guillermo Please remove and replace ceiling tiles grid for Italian serving line in the kitchen.

Guillermo Hernandez

129324 2/26/2015 20 \$0.00

Medium Work In Progress 2/26/2015 7:40:34 AM

Hernandez, Guillermo Need assistance to troubleshoot H/C unit for the Library.

Guillermo Hernandez

129183 2/23/2015 23 \$0.00

Medium Work In Progress 2/23/2015 3:32:32 PM

Hernandez, Guillermo Need to replace hanging fluorescent light in the cafeteria.

Guillermo Hernandez

128829 2/12/2015 34 \$0.00

Medium Work In Progress 2/12/2015 7:46:28 AM

Hernandez, Guillermo Need to order filters for the H/C units.

Guillermo Hernandez

129595 3/1/2015 3/7/2015 17 \$0.00

Medium Work In Progress 3/1/2015 12:46:54 AM

Hernandez, Guillermo Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

129566 3/1/2015 3/9/2015 17 \$0.00

Medium Work In Progress 3/1/2015 12:46:38 AM

Hernandez, Guillermo Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

128473 2/4/2015 42 \$0.00

Medium Work In Progress 2/4/2015 1:16:02 PM

Hernandez, Guillermo Please check switch for the bleachers, having problems opening and closing bleachers.

Guillermo Hernandez

129431 2/28/2015 3/31/2015 18 \$0.00

Medium Work In Progress 2/28/2015 12:34:44 AM

Hernandez, Guillermo Yearly - Gadsden HS C-11 (Evap.Condnser)(Yearly) - Refer to PM schedule details.

Margret Villalobos

3/18/2015 12:54:24 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
127137					1/6/2015		71		\$0.00
Medium	Work In Progress				1/6/2015 3:36:00 PM				
Marquez, Gerardo		Requested by Mr. Enriquez Rm. 500 New CTE Building- Need to level floor in shop to install a twin port lift.							
Velia Alarcon									
129292					2/25/2015		21		\$0.00
Medium	Work In Progress				2/25/2015 2:49:14 PM				
Orozco, Daniel		DRAINS BACKING UP. SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
128855					2/12/2015		34		\$0.00
Medium	Work In Progress				2/12/2015 2:49:48 PM				
Orozco, Daniel		AS PER ADELES INSPECTION REPORT - GRATER ATTACHMENTS TO CHOPER DOES NOT WORK.							
Maritza Gonzalez									
127022					1/5/2015		72		\$0.00
High	Work In Progress				1/5/2015 7:42:35 AM				
Sotelo, Enrique		Need to replace ballasts or lamps to the outside lights of the weight room, this area is to dark at night.							
Guillermo Hernandez									
128646					2/9/2015		37		\$0.00
Medium	Work In Progress				2/9/2015 7:40:31 AM				
Orozco, Daniel		As per Mr. Bakers inspection report, water on floor by the 3 compartment sink (been a problem for some time).							
Maritza Gonzalez									
119747					7/23/2014		238		\$0.00
Medium	Work In Progress				7/23/2014 10:08:37 AM				
Orozco, Daniel		WARMER-OLD FAVORITES-INSIDE HAS FALLEN. SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
128329					2/2/2015		44		\$0.00
Medium	Work In Progress				2/2/2015 8:58:09 AM				
Orozco, Daniel		COLD HOLDING UNIT (MILK BOX) IN RED AND GREEN LINE NOT WORKING. SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS									
128830					2/12/2015		34		\$0.00
Medium	Work In Progress				2/12/2015 7:48:40 AM				
Orozco, Daniel		ZIA NEON AND RED AND GREEN CHILE NEON LIGHTS IN CAFETERIA ARE FLICKERING. SNP MANAGER FRANCES B. 882.5522				2/24/15 As per Enrique, route to Danny O.			
Maritza Gonzalez									
130222					3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 3:56:41 PM				
Sotelo, Enrique		Line locates are needed. Please see e-mail for site layout. For questions please contact Allan Journey of GenCon at 575-644-0810.							
Dominique Esparza									
130236					3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 8:38:39 AM				
Sotelo, Enrique		Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Email: blanca@caliperconstoom							
		Location of Work: FRMLAS CRUCES E I-10 TAKE EXIT FOR ANOTHONY APPX 15.0MI, TRN W OHARA RD APPX 4.0MI, TRN S NM-28 APPX 1.0MI TO LOCATION ON RIGHT HAND SIDE OF THE RD SPOT: FRM THE WEST EDGE OF THE RD OF NM-28 APPX 1000FT INTO THE SCHOOL PROPERTY GOING FRM							
		Remarks: WASHINGTON ST TO HAASVILLE RD NO HAZARDS/OPEN ACCESS							
Dominique Esparza									
119303	Auto Shop				7/11/2014		250		\$0.00
Medium	Work In Progress				7/11/2014 12:42:51 PM				
Sotelo, Enrique		NEED FOR ELECTRICAL POWER TO BE INSTALLED FOR NEW LIFT.							
Gerardo Marquez									
126662	North Building				12/16/2014		92		\$0.00
High	Work In Progress				12/16/2014 10:14:03				
Sotelo, Enrique		need lighting on the west wall of the rotc building. very dark at night. thank you							
Michael Munoz									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
122944					9/18/2014		181		\$0.00
Medium	Work In Progress				9/18/2014 7:38:30 AM				
Sotelo, Enrique		Need to replace burn out lamps on the south side of school, area by the swimming pool. This area has now 4 lights out and one by grounds. Need bucket truck.							
Guillermo Hernandez									
129938	Pool Dressing	Pool			3/9/2015		9		\$0.00
Medium	Work In Progress				3/9/2015 11:00:06 AM				
Sotelo, Enrique		GHS pool need to service light in dressing room Pump Room and outside area also check all control switches on pumps for upcoming season							
Mario Apodaca									
128335					2/2/2015		44		\$0.00
Medium	Work In Progress				2/2/2015 9:38:45 AM				
Ronquillo, Ruben		Requested by Coach Yanez for Baseball Field-Set up square batting cage with cables, clamps, and net at the baseball field. Spoke with Mike Munoz and Ruben Ronquillo regarding the batting cage.							
Velia Alarcon									
119657					7/21/2014		240		\$0.00
Medium	Work In Progress				7/21/2014 3:31:25 PM				
Gallegos, Rafael		Warranty work order. Mullen on the west double back door to the Theater building is not working properly. The key gets stuck and can not remove the mullen.							
Guillermo Hernandez									
121304					8/18/2014		212		\$0.00
Medium	Work In Progress				8/18/2014 7:54:25 AM				
Gallegos, Rafael		TRANE WARRANTY W/O. Science classroom #619 CO sensor is not reading.							
Guillermo Hernandez									
121342					8/18/2014		212		\$0.00
Medium	Work In Progress				8/18/2014 12:19:58 PM				
Gallegos, Rafael		Warranty work order for roof leak in the manufacturing shop. water seems to be coming from the A/C roof jack, the welded part looks like is crack as possible cause of roof leak.							
Guillermo Hernandez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
129492					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:54 AM				
Sanchez, Raul		Monthly - Gadsden HS - Grease Trap (Culinary/Auto) - Refer to PM schedule details.							
Margret Villalobos									
129582					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:47 AM				
Sanchez, Raul		Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
129461					2/28/2015		18		\$0.00
Medium	Work In Progress				2/28/2015 12:35:04 AM				
Sanchez, Raul		Monthly - Gadsden HS - Monthly Meter Readings - Refer to PM schedule details.							
Margret Villalobos									
129584					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:48 AM				
Sanchez, Raul		Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
128198					1/31/2015		46		\$0.00
Medium	Work In Progress				1/31/2015 12:39:15 AM				
Sanchez, Raul		Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
128074					1/29/2015		48		\$0.00
Medium	Work In Progress				1/29/2015 7:46:54 AM				
Gonzalez, Salvador		Need to replace broken main sign pole by the flag poles.							
Guillermo Hernandez									
119662					7/21/2014		240		\$0.00
Medium	Work In Progress				7/21/2014 3:37:51 PM				
Ronquillo, Ruben		Ruben, need to order two light poles to be replaced. Questions ask Enrique S. as per Alfredo.				2/4/15 - See wo 125669			
Guillermo Hernandez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
124632		Athletic Field			10/27/2014		142		\$0.00
Medium	Work In Progress			10/27/2014 2:47:26 PM					
Gonzalez, Salvador	need to install new cables for new batting net on batting cages. boys baseball. contact person @ site. coach Bones. thank you								
Michael Munoz									
125861		Athletic Field			11/21/2014		117		\$0.00
Medium	Work In Progress			11/21/2014 3:17:50 PM					
Gonzalez, Salvador	Requested by Ms. L. Chavez for Softball Field-Replace old batting cage. Add a third batting cage on Softball Field. Add an area for batting off tees. Remove old tee area from fence (left side) welded into fence.		125862						
Velia Alarcon									
125862		Athletic Field			11/21/2014		117		\$0.00
Medium	Work In Progress			11/21/2014 3:21:11 PM					
Gonzalez, Salvador	Requested by Ms. L. Chavez for Softball Field-Backstop on Softball Field needs to be replaced (safety issue). There are white stakes keeping fence down. Officials stated that those stakes were a safety issue to all players.								
Velia Alarcon									
125292		Football Field			11/7/2014		131		\$0.00
Medium	Work In Progress			11/7/2014 1:12:07 PM					
Gonzalez, Salvador	Coach Vasquez would like a door placed in the shower area to store some of his equipment. Door needs to be welded.								
William Dickson									
120351					8/3/2014		227		\$0.00
Medium	Work In Progress			8/3/2014 12:33:49 AM					
Munoz, Michael	Yearly - Gadsden HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.		PM not completed as per schedule						
Margret Villalobos									
126403		Athletic Field			12/9/2014		99		\$0.00
Medium	Work In Progress			12/9/2014 8:26:59 AM					
Flores, Pete	JD Mower Isolator needs to be replaced.								
Guadalupe Ontiveros									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
129019	North Building	Kitchen			2/18/2015		28		\$0.00
Medium	Work In Progress				2/18/2015 9:28:00 AM				
Villalobos, Margret		Requested by Mrs. Lerma Rm. 206 & 207 North Building				Emailed			
		-There is a mice and ant infestation in the kitchen labs.							
Velia Alarcon									
130173					3/15/2015		3		\$0.00
Medium	Work In Progress				3/15/2015 12:26:54 AM				
Villalobos, Margret		Monthly - Gadsden HS - PC Automated Quarterly - Refer to PM schedule details.							
Margret Villalobos									
127810					1/22/2015		55		\$0.00
Medium	Work In Progress				1/22/2015 2:52:14 PM				
Munoz, Michael		Could you please purchase new sewing machines for new sewing lab. Purchase 4							
Michael Munoz									
130039		Athletic Field			3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 2:55:24 PM				
Lara, Ralph		Coach Chavez is request two pad locks for gates at softball and baseball fields to keep all cars out for safety. HE 157							
Guadalupe Ontiveros									
121888					8/28/2014		202		\$0.00
Medium	Work In Progress				8/28/2014 9:19:01 AM				
Lara, Ralph		Need some assistance on door lock in intervention room, lock is stuck, teacher needs to lock and open room frequently.							
Arturo Nunez									
127412					1/12/2015		65		\$0.00
Medium	Work In Progress				1/12/2015 3:02:03 PM				
Lara, Ralph		Requested by Maria Grubaugh-Mailbox# 4 needs to have a second key made.							
Velia Alarcon									
125272					11/7/2014		131		\$0.00
Medium	Work In Progress				11/7/2014 9:03:59 AM				
Sanchez, Raul		Domestic Water Well #1 - install sanitary seal properly around electrical wires.							
Alfredo Holguin									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
130179					3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 8:05:50 AM				
Lara, Ralph		Need extra padlocks for the electric panels for the Main building and gates.							
Guillermo Hernandez									
128733					2/10/2015		36		\$0.00
Medium	Work In Progress				2/10/2015 1:36:34 PM				
Lara, Ralph		Requested by Ms. Scott-Mailbox # 84 is not opening easily with the key assigned to the teacher or the spare in the key box.							
Velia Alarcon									
128889					2/13/2015		33		\$0.00
Medium	Work In Progress				2/13/2015 7:51:06 AM				
Lara, Ralph		Rafa, we need 24 door stops the ones that we talked about to prevent the V. Gym doors from being damaged.							
Guillermo Hernandez									
127726		Custodial			1/21/2015		56		\$0.00
Medium	Work In Progress				1/21/2015 5:24:46 AM				
Flores, Pete		red electric blower not blowing #1258							
Isaac Holguin									
119630					7/21/2014		240		\$0.00
Medium	Work In Progress				7/21/2014 10:01:42 AM				
Flores, Pete		Requested by Mr. Smythe-Ag. tractor needs to be serviced. Engine oil and filter need to be replaced. Both batteries need to be replaced. Hydraulic/trans fluid and filters need to be changed/replaced. Inner and outer air filters need to be replaced. Cab fresh air filters need to be replaced. Injection pump needs to be repaired; fuel system will not hold a prime. Air filter bowl needs to be replaced as well, broken at base. All grease fittings need to be examined in order to take grease.							
Velia Alarcon									
123810	Library	Library			10/7/2014		162		\$0.00
Medium	Work In Progress				10/7/2014 12:59:31 PM				
Estrada, Jesus		Requested by Matt Grubaugh for Library-The carpet in the library continues to come up. He's afraid students are going to trip on it and hurt themselves.							
Velia Alarcon									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
121586	Concession				8/21/2014		113		\$0.00
Medium	Work In Progress				8/21/2014 1:47:38 PM	12/12/2014			
Holguin, Isaac Requested by Cathy for Football Concession/Kitchen Stand-There are cob webs, live and dead roaches, needs to be sprayed.									
Velia Alarcon									
122352					9/4/2014		195		\$0.00
Medium	Work In Progress				9/4/2014 3:46:33 PM				
Ontiveros, Guadalupe Need to replace about 200 ft. of 3 ft. high fence on the foot ball field visitors side, fence is facing the football field. Safety issue.									
Guillermo Hernandez									
129925					3/9/2015		9		\$0.00
Medium	Work In Progress				3/9/2015 7:35:33 AM				
Ambriz, Jose Joe, we need to replace the t-stat (5 wires) for the fan coils in the girls gym.									
Guillermo Hernandez									
130161					3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 3:56:18 PM				
Ambriz, Jose Need to recharge walking cooler for the flower shop.									
Guillermo Hernandez									
128797					2/11/2015		35		\$0.00
Medium	Work In Progress				2/11/2015 3:35:36 PM				
Ambriz, Jose A.C. in boys locker room in boys gym needs to be replaced Model # mc 44.									
Arturo Nunez									
128799					2/11/2015		35		\$0.00
Medium	Work In Progress				2/11/2015 3:37:30 PM				
Ambriz, Jose A.C in coaches office in boys gym , needs to be replaced model # mc 38.									
Arturo Nunez									
128802					2/11/2015		35		\$0.00
Medium	Work In Progress				2/11/2015 3:40:02 PM				
Ambriz, Jose A.C in coaches football office needs to be replaced model # mc 38.									
Arturo Nunez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
128803					2/11/2015		35		\$0.00
Medium	Work In Progress				2/11/2015 3:41:20 PM				
Ambriz, Jose		A.C. in football locker room needs to be replaced model # mc 44.							
Arturo Nunez									
128826					2/12/2015		34		\$0.00
Medium	Work In Progress				2/12/2015 7:38:12 AM				
Ambriz, Jose		A.C. in girls dressing room in boys gym. needs to be replaced mc 44.							
Arturo Nunez									
128827					2/12/2015		34		\$0.00
Medium	Work In Progress				2/12/2015 7:41:14 AM				
Ambriz, Jose		A.C. in wrestling dressing room in boys gym. needs to be replaced. mc. 44.							
Arturo Nunez									
128828					2/12/2015		34		\$0.00
Medium	Work In Progress				2/12/2015 7:43:42 AM				
Ambriz, Jose		A.C. in swimming pool needs to be replaced. mc. 64 .							
Arturo Nunez									
128750					2/10/2015		36		\$0.00
Medium	Work In Progress				2/10/2015 3:38:06 PM				
Ambriz, Jose		Need some assistance on looking for Freon leak in walk in freezer in flower shop.							
Arturo Nunez									
126977					1/4/2015		73		\$0.00
Medium	Work In Progress				1/4/2015 12:41:36 AM				
Munoz, Michael		Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
129406	Pool Pump	Pump House			2/27/2015		19		\$0.00
Medium	Work In Progress				2/27/2015 2:57:02 PM				
Apodaca, Mario		need to order pool water testing chemicals and pool supplies							
Mario Apodaca									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
129407	Pool Pump	Pump House			2/27/2015		19		\$0.00
Medium	Work In Progress				2/27/2015 3:05:30 PM				
Apodaca, Mario	recycle pool water filters needed need to change out for upcoming season								
Mario Apodaca									
129446					2/28/2015		18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:54 AM				
Munoz, Michael	Yearly - Gadsden HS - Fire Pump Inspection - Refer to PMs schedule details.								
Margret Villalobos									
126410		Classroom			12/9/2014		99		\$0.00
Medium	Work In Progress				12/9/2014 11:45:08 AM				
Munoz, Michael	could you please services all sewing machines in the sewing lab. thank you								
Velia Alarcon									
129295	Pool Pump	Pool			2/25/2015		21		\$0.00
Medium	Work In Progress				2/25/2015 3:04:17 PM				
Apodaca, Mario	Received the new lifeguard chair need to assemble and install								
Mario Apodaca									
129123	Pool Pump	Pool			2/20/2015		26		\$0.00
Medium	Work In Progress				2/20/2015 2:50:50 PM				
Apodaca, Mario	Need to order wind screen to install is a canopy for shade on pool deck for this coming season								
Mario Apodaca									
Count: 103 Work Orders		Avg. Age of WO's 74			Total for Gadsden HS			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

128187 1/31/2015 46 \$0.00

Medium Work In Progress 1/31/2015 12:39:07 AM

Apodaca, Mario Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details. PM not performed as per schedule 2/9/15

Margret Villalobos

128617 2/6/2015 40 \$0.00

Medium Work In Progress 2/6/2015 3:46:24 PM

Solis, Lorenz Need to fix pump on boiler room eastside thank you

Sebastian Diaz

119661 7/21/2014 240 \$0.00

High Work In Progress 7/21/2014 3:36:41 PM

Apodaca, Mario ***The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house***

Company: CD MECHANICAL
 Contact Name: DEAN POGUE Contact Phone: (575)382-8474
 State: NM County: DONA ANA City: RURAL
 DONA ANA
 Address: 1301, WASHINGTON ST
 Nearest Intersecting Street: BERRY RD
 2nd Intersecting Street: GRACIE PL
 Subdivision: GASDEN MIDDLE SCHOOL
 Latitude: 31.99971983 Longitude: -106.63006583
 Zip Code: 88021
 Township: 26S Range: 03E Section 1/4: 34 SW

Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS. - SPOT ON THE E. SIDE OF PROPERTY, IN THE PONDING AREA BETWEEN THE WATER STORAGE TANK AND THE GYM.

Dominique Esparza

125852 Pump House 11/21/2014 117 \$0.00

Medium Work In Progress 11/21/2014 2:42:53 PM

Apodaca, Mario need to run new control wires to the gms irrigation tank

Mario Apodaca

129586 3/1/2015 17 \$0.00

Medium Work In Progress 3/1/2015 12:46:49 AM

Apodaca, Mario Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.

Margret Villalobos

3/18/2015 12:54:24 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden MS									
129869	Main Building				3/6/2015		12		\$0.00
Medium	Work In Progress				3/6/2015 10:49:55 AM				
Herrera, Mario	Need to strip and waxfront office during spring break								
Mario Herrera									
125237	Gym				11/6/2014		132		\$0.00
Medium	Work In Progress				11/6/2014 2:41:40 PM				
Munoz, Michael	The new bleachers not working on the gym thank you								
Sebastian Diaz									
127471	Cafeteria	Cafeteria			1/13/2015		64		\$0.00
Medium	Work In Progress				1/13/2015 11:20:12 AM				
Estrada, Jesus	Needs new VCT tile in cafeteria a lot of pieces missing and cracking								
Mario Herrera									
121935					8/28/2014		202		\$0.00
Medium	Work In Progress				8/28/2014 3:44:19 PM				
Ontiveros, Guadalupe	Need to bring tractor use for water damegs on vocational and front A wing thank you								
Sebastian Diaz									
127468	Main Building	Hallway/Corridor			1/13/2015		64		\$0.00
Medium	Work In Progress				1/13/2015 11:15:04 AM				
Estrada, Jesus	New to replace (VCT tile) in west wing tile is coming up and un done pieces of VCT missing								
Mario Herrera									
127469	Main Building	Hallway/Corridor			1/13/2015		64		\$0.00
Medium	Work In Progress				1/13/2015 11:17:19 AM				
Estrada, Jesus	Need to replace VCT tile is coming up and breaking off in different sections								
Mario Herrera									
127470	Main Building	Hallway/Corridor			1/13/2015		64		\$0.00
Medium	Work In Progress				1/13/2015 11:18:30 AM				
Estrada, Jesus	VCT tile needs to be replaced cracking and coming off								
Mario Herrera									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Gadsden MS								
------------------	-------------------	--	--	--	--	--	--	--	--

119660					7/21/2014		240		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

High Work In Progress 7/21/2014 3:36:20 PM
 Sanchez, Raul ***The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house***

Company: CD MECHANICAL
 Contact Name: DEAN POGUE Contact Phone: (575)382-8474
 State: NM County: DONA ANA City: RURAL DONA ANA
 Address: 1301, WASHINGTON ST
 Nearest Intersecting Street: BERRY RD
 2nd Intersecting Street: GRACIE PL
 Subdivision: GASDEN MIDDLE SCHOOL
 Latitude: 31.99971983 Longitude: -106.63006583
 Zip Code: 88021
 Township: 26S Range: 03E Section 1/4: 34 SW

Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS. - SPOT ON THE E. SIDE OF PROPERTY, IN THE PONDING AREA BETWEEN THE WATER STORAGE TANK AND THE GYM.

Dominique Esparza					3/1/2015	3/17/2015	17		\$0.00
-------------------	--	--	--	--	----------	-----------	----	--	--------

Medium Work In Progress 3/1/2015 12:46:04 AM
 Villalobos, Margret Monthly - Gadsden MS Monthly Chiller Insp. - Refer to 3/2 - Emailed PM schedule details.

Margret Villalobos					3/13/2015		5		\$0.00
--------------------	--	--	--	--	-----------	--	---	--	--------

Medium Work In Progress 3/13/2015 12:48:33 PM
 Ronquillo, Ruben Room 307 Glass window on door is broken fix ASAP
 Thank you

Mario Herrera					2/28/2015	3/31/2015	18		\$0.00
---------------	--	--	--	--	-----------	-----------	----	--	--------

Medium Work In Progress 2/28/2015 12:34:51 AM
 Diaz, Sebastian Yearly - Gadsden MS C-11 Evap Coolers Yearly - Refer to PM schedule details.

Margret Villalobos

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

128518	C-Wing				2/5/2015		41		\$0.00
--------	--------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	Old Central			2/5/2015 10:37:36 AM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Gonzalez, Salvador Fabricate mail drop box by Old Central Office.

Richard Chavez

128092		Cafeteria			1/29/2015		48		\$0.00
--------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	kitchen			1/29/2015 10:26:35 AM				
--------	------------------	---------	--	--	-----------------------	--	--	--	--

Diaz, Sebastian Repaint damaged rooms.
Clean and paint light fixtures that have not been cleaned in the storage area.

Nancy Tinajero

127120		Gym			1/6/2015		71		\$0.00
--------	--	-----	--	--	----------	--	----	--	--------

Medium	Work In Progress	Gym athletic			1/6/2015 2:39:38 PM				
--------	------------------	--------------	--	--	---------------------	--	--	--	--

Diaz, Sebastian Add shelving, fix cabinets and add security locks.

Nancy Tinajero

130306	Gym	Gym			3/18/2015		0		\$0.00
--------	-----	-----	--	--	-----------	--	---	--	--------

Medium	Work In Progress	GYM			3/18/2015 10:47:06 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Diaz, Sebastian Main Basketball Goal frame is coming apart. Also check switch box for practice goal because it will not come up or down.

Nancy Tinajero

130252	C-Wing				3/17/2015		1		\$0.00
--------	--------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	AVECHS			3/17/2015 11:24:15 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Diaz, Sebastian Primer, paint new walls and patch walls that were remodel.

Danny Miranda

130253	C-Wing				3/17/2015		1		\$0.00
--------	--------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	AVECHS			3/17/2015 11:26:24 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Diaz, Sebastian Remove wall or patch wall that was cut by Gerry in order to install window. (See Alfredo before you start)

Alfredo Holguin

130051	Band Room				3/11/2015		7		\$0.00
--------	-----------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	room 100 and			3/11/2015 3:42:21 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Diaz, Sebastian Fixhole in outside Band room wall and wall outside room 150.

Nancy Tinajero

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
130041					3/11/2015		7		\$0.00
Medium	Work In Progress	Storage room			3/11/2015 3:05:55 PM				
Diaz, Sebastian		Install rod in storage room near SPED room to hang polo shirts for dress code violations.							
Nancy Tinajero									
121842	C-Wing				8/27/2014		203		\$0.00
Medium	Work In Progress	Old Central			8/27/2014 1:15:58 PM				
Diaz, Sebastian		as per conversation, please paint all rooms inside. thank you							
Michael Munoz									
125784	Gym				11/19/2014		119		\$0.00
Medium	Work In Progress				11/19/2014 4:24:32 PM				
Diaz, Sebastian		Order window screens for Gym and Gym Lobby. (See Mike)							
Michael Munoz									
129164					2/23/2015		23		\$0.00
Medium	Work In Progress				2/23/2015 12:54:06 PM				
Diaz, Sebastian		Need bottom door sweep for computer lab thank you							
Sebastian Diaz									
129117	C-Wing				2/20/2015		26		\$0.00
Medium	Work In Progress	Old Central			2/20/2015 10:55:51 AM				
Diaz, Sebastian		Old Central Office Paint newly installed doors and jams Paint or Repaint interior door jams white.							
Margret Villalobos									
128509					2/5/2015		41		\$0.00
Medium	Work In Progress				2/5/2015 8:44:34 AM				
Diaz, Sebastian		Need to replace pads on vocational thank you							
Sebastian Diaz									
127838					1/23/2015		54		\$0.00
Medium	Work In Progress				1/23/2015 10:15:02 AM				
Sotelo, Enrique		Need to enough power for meting on cafeteria FEB 6 thank you							
Sebastian Diaz									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

125851 Pump House 11/21/2014 117 \$0.00

Medium Work In Progress 11/21/2014 2:41:06 PM

Sotelo, Enrique need to pull new control wires for the switch float at the gms irrigation tank

Mario Apodaca

130257 3/17/2015 1 \$0.00

Medium Work In Progress 3/17/2015 12:07:36 PM

Sotelo, Enrique Need to connect motor on B wing exhaust fan thank you

Sebastian Diaz

128328 2/2/2015 44 \$0.00

Medium Work In Progress 2/2/2015 8:56:42 AM

Orozco, Daniel WALK IN FREEZER AT 69 DEGREES. SNP MANAGER TERRY P. 882.2824

Maritza Gonzalez

130188 3/16/2015 2 \$0.00

Medium Work In Progress 3/16/2015 11:44:19 AM

Marquez, Gerardo AS PER THE STATE FIRE INSPECTOR PLEASE CHECK ALL EXTERIOR DOORS THROUGH OUT ENTIRE GADSDEN MIDDLE CAMPUS FOR PROPER FUNCTION. FIX ANY PROBLEMS THAT ARE FOUND. SHOULD YOU HAVE ANY QUESTIONS PLEASE CONTACT MR. RALPH GALLEGOS AT 575-882-6921 IN THE CONSTRUCTION OFFICE.

Dominique Esparza

121844 C-Wing 8/27/2014 203 6 \$150.00

Medium Work In Progress Old Central 8/27/2014 1:19:05 PM

Marquez, Gerardo please change all windows around building. double pane Will be replaced by APCO thank you

Michael Munoz

119972 7/29/2014 232 \$0.00

Medium Work In Progress front office 7/29/2014 10:04:45 AM

Marquez, Gerardo Need key (A-57) for custodian

Nancy Tinajero

119973 7/29/2014 232 \$0.00

Medium Work In Progress front office- 7/29/2014 10:06:01 AM

Marquez, Gerardo Need Keys for new PE teacher, WA-62, V-8, WA-64, 01, V-15, one each please.

Nancy Tinajero

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
128957					2/17/2015		29		\$0.00
Medium	Work In Progress			2/17/2015 10:48:14 AM					
Marquez, Gerardo	Need to replace main entrance doors AB thank you								
Sebastian Diaz									
129621	Gymnasium				3/2/2015		16		\$0.00
Medium	Work In Progress			3/2/2015 8:46:52 AM					
Marquez, Gerardo	room 601 in gym lobby (W) master key will not open								
Mario Herrera									
125855		Athletic Field			11/21/2014		117		\$0.00
Medium	Work In Progress			11/21/2014 3:01:34 PM					
Ontiveros, Guadalupe	please plant trees around baseball field along with irrigation as discussed. thank you (Arizona ash)								
Michael Munoz									
126661					12/16/2014		92		\$0.00
Medium	Work In Progress			12/16/2014 10:07:58					
Ontiveros, Guadalupe	please clean court yard where planters are at and remove Chinese elm. also will need a run off for proper drainage. would like floor covering and grave/rock on top. please see mike for details								
Michael Munoz									
125614	Main Building	Classroom			11/17/2014		121		\$0.00
Medium	Work In Progress	room 169		11/17/2014 9:24:51 AM					
Marquez, Gerardo	Need a half door installed in room 169 for student safety.								
Nancy Tinajero									
124293		Classroom			10/17/2014		152		\$0.00
Medium	Work In Progress	room 148		10/17/2014 11:47:27					
Marquez, Gerardo	Classroom entry door needs to be adjusted.								
Nancy Tinajero									
129661		Computer Lab			3/2/2015		16		\$0.00
Medium	Work In Progress	room 601		3/2/2015 3:48:16 PM					
Marquez, Gerardo	Still having trouble with locking and unlocking door to room 601								
Nancy Tinajero									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

128786 Library 2/11/2015 35 \$0.00

Medium Work In Progress library front 2/11/2015 1:07:51 PM

Marquez, Gerardo Adjust the front doors in the library

Nancy Tinajero

128784 Main Building Library 2/11/2015 35 \$0.00

Medium Work In Progress Library storage 2/11/2015 11:18:55 AM

Marquez, Gerardo Need WA-27 key replaced. Broken key in lock.

Nancy Tinajero

127946 1/26/2015 51 \$0.00

Medium Work In Progress 1/26/2015 2:43:41 PM

Orozco, Daniel MILK MACHIINE BROKEN, DOOR HANGING OFF HINGES. SNP MANAGER TERRY P. 882.2824

Maritza Gonzalez

125015 11/2/2014 11/23/2014 136 \$0.00

Medium Work In Progress 11/2/2014 12:36:26 AM

Orozco, Daniel Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

127753 1/21/2015 56 \$0.00

Medium Work In Progress 1/21/2015 11:25:29 AM

Orozco, Daniel WALK IN FREEZER RAMP NEEDS TO BE REPAIRED, IT LIFTS AND KEEP DOOR AJAR. SNP MANAGER TERRY P. 882.2824

Maritza Gonzalez

127754 1/21/2015 56 \$0.00

Medium Work In Progress 1/21/2015 11:28:32 AM

Orozco, Daniel RACKS IN WARMING CABINET NEED ANCHORS RACKS ARE LOOSE AND CAN CAUSE SOMEONE TO GET BURNED. SNP MANAGER TERRY P. 882.2824

Maritza Gonzalez

129870 3/6/2015 12 \$0.00

Medium Work In Progress 3/6/2015 11:10:11 AM

Orozco, Daniel Maritza, the three compartment sink is not functioning properly. The water over flows and spreads all over the floor and into Mr. Bakers office. His office smells like stagnant water. Also, I have a leak on the vegetable sink pipes underneath. Can you please place a work order for these problems. Thanks! SNP Manager Terry P.882.2824

Maritza Gonzalez

3/18/2015 12:54:24 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
130302					3/18/2015		0		\$0.00
Medium	Work In Progress				3/18/2015 8:55:48 AM				
Orozco, Daniel		LEAK IN VEGETABLE SINK.SNP MANAGER TERRY P. 882.2824							
Maritza Gonzalez									
129825					3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 11:54:05 AM				
Orozco, Daniel		As per Mr. Baker, please place a work order for both walk-in freezer and fridge. The doors don't close properly. He would like to see them close on their own. Thank you!							
Maritza Gonzalez									
129886					3/6/2015		12		\$0.00
Medium	Work In Progress				3/6/2015 3:18:16 PM				
Villalobos, David		Need to replace sink faucets on B wing thank you							
Sebastian Diaz									
124628		Gym			10/27/2014		142		\$0.00
Medium	Work In Progress	baseball field			10/27/2014 2:00:21 PM				
Villalobos, David		Water fountain outside gym area near baseball field is not working.							
Nancy Tinajero									
124404		Library			10/21/2014		148		\$0.00
Medium	Work In Progress	Library			10/21/2014 12:30:45				
Villalobos, David		Clogged sink in library office.							
Nancy Tinajero									
130054		Restroom			3/11/2015		7		\$0.00
Medium	Work In Progress	A wing boys			3/11/2015 3:45:12 PM				
Villalobos, David		The faucet in boys restroom is continuously running.							
Nancy Tinajero									
119801	Main Building	Classroom			7/24/2014		237		\$0.00
Medium	Work In Progress	Room 152			7/24/2014 11:57:42 AM				
Villalobos, David		Sink is dripping continuously; doesn't drain and is leaking into the cabinet.							
Nancy Tinajero									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
124188		Classroom			10/15/2014		154		\$0.00
Safety	Work In Progress	room 129 and			10/15/2014 1:55:35 PM				
Villalobos, David		Water is leaking out of the wall between room 129 and 140. Computers are against that wall. Could be a severe electrical shock issue.							
Nancy Tinajero									
126893					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:28 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
128576	Main Building	Restroom			2/6/2015		40		\$0.00
Medium	Work In Progress	B wing			2/6/2015 9:27:12 AM				
Villalobos, David		Stench in the boys restroom B wing, replace pipes.							
Nancy Tinajero									
121391	Vocational				8/19/2014		211		\$0.00
Medium	Work In Progress				8/19/2014 6:59:54 AM				
Villalobos, David		outside water for water hoses do not work on the whole building							
Mario Herrera									
121677					8/25/2014		205		\$0.00
Medium	Work In Progress				8/25/2014 8:10:22 AM				
Villalobos, David		Need o replace sink faucet on rest room A wing thank you							
Sebastian Diaz									
119501	C-Wing				7/16/2014		245		\$0.00
Medium	Work In Progress				7/16/2014 3:49:11 PM				
Villalobos, David		Portable - Where restrooms are located. There is a leak underneath the sink, water has been shut off for now. Please check this first thing in the morning.							
Mario Herrera									
124709	Gym				10/29/2014		140		\$0.00
Medium	Work In Progress				10/29/2014 7:43:56 AM				
Villalobos, David		Urinals in boys gym locker room do not have water needs to be fixed A.S.A.P in order to clean by custodian right							
Mario Herrera									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Gadsden MS										
124711					10/29/2014		140		\$0.00	
Medium	Work In Progress				10/29/2014 7:45:12 AM					
Villalobos, David		Sink in girls restroom next to b-wing and main hallway there is no running water								
Mario Herrera										
128396	C-Wing				2/3/2015		43		\$0.00	
Medium	Work In Progress	Old Central			2/3/2015 10:03:34 AM					
Miranda, Danny		Repair walls in classroom and restrooms.								
Michael Munoz										
129703	C-Wing				3/3/2015		15		\$0.00	
Medium	Work In Progress				3/3/2015 11:08:09 AM					
Miranda, Danny		Mr. Miranda, As per Alfredo Holguin; cover openings where old A/C's used to be. Thanks!								
Lorenzo Solis										
Count: 68 Work Orders		Avg. Age of WO's 82		Total for Gadsden MS				6	\$150.00	

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
130277					3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 3:39:15 PM				
Castillo, Carlos		have 2 parking pole lights out and 7 building lights out - need replaced							
Patricio Aguilar									
130074					3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 7:56:28 AM				
Carrasco, Danny		need the use of the scissor lift to work on heater in gym.							
Patricio Aguilar									
125016					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress				11/2/2014 12:36:26 AM				
Orozco, Daniel		Monthly - La Union ES Range Hood Cleaning - Refer to PMs schedule details.							
Margret Villalobos									
126360					12/8/2014		100		\$0.00
Medium	Work In Progress				12/8/2014 12:38:51 PM				
Orozco, Daniel		DISHWASHER IS DOWN. SNP MANAGER LINDA Y. 589.2040							
Maritza Gonzalez									
128739					2/10/2015		36		\$0.00
Medium	Work In Progress				2/10/2015 2:38:17 PM				
Orozco, Daniel		AS PER ADELE'S INSPECTION. SLICER NEEDS REPAIR.							
Maritza Gonzalez									
128081					1/29/2015		48		\$0.00
Medium	Work In Progress				1/29/2015 9:25:07 AM				
Orozco, Daniel		FREEZER AT 29. SNP MANAGER LINDA Y. 589.2040							
Maritza Gonzalez									
129460					2/28/2015		18		\$0.00
Medium	Work In Progress				2/28/2015 12:35:03 AM				
Sanchez, Raul		Monthly - La Union ES - Monthly Meter Readings - Refer to PMs schedule details.							
Margret Villalobos									
130095	Main Building	Hallway/Corridor			3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 3:03:19 PM				
Ramos, Rudy		Please remove dead bugs from inside light fixture in front of office.							
Jesus Estrada									
3/18/2015 12:54:24 PM									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
124738					10/29/2014		140		\$0.00
Medium	Work In Progress				10/29/2014 2:49:48 PM				
Aguilar, Patricio		work order to myself - need to replace fire pull station cover not working - alta vista							
Patricio Aguilar									
129564					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:36 AM				
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
129565					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:37 AM				
Aguilar, Patricio		Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
129577					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:44 AM				
Aguilar, Patricio		Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
129613					3/1/2015	3/7/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:47:05 AM				
Aguilar, Patricio		Monthly - La Union ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
129234					2/24/2015		22		\$0.00
Medium	Work In Progress				2/24/2015 2:09:15 PM				
Aguilar, Patricio		wo to myself - need to replace # to class rooms as per fire marshal							
Patricio Aguilar									
128832					2/12/2015		34		\$0.00
Medium	Work In Progress				2/12/2015 7:52:06 AM				
Aguilar, Patricio		wo to myself - need replacement filter for ac old wing - annex							
Patricio Aguilar									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
128911					2/13/2015		33		\$0.00
Medium	Work In Progress				2/13/2015 3:22:32 PM				
Aguilar, Patricio		need a elect. out lite replacer in comp. room - 2 elect out lite changed to G F I out lite old wing hall way.							
Patricio Aguilar									
129449					2/28/2015		18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:56 AM				
Aguilar, Patricio		Monthly - La Union ES A-16 Fan Exhaust Semimonthly - Refer to PM schedule details.							
Margret Villalobos									
129922					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:49 AM				
Aguilar, Patricio		Monthly - La Union ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
129438					2/28/2015	3/31/2015	18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:49 AM				
Aguilar, Patricio		Yearly - La Union ES C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
123946					10/9/2014		160		\$0.00
Medium	Work In Progress				10/9/2014 3:15:21 PM				
Ambriz, Jose		need thermostat for heater in gym - thank you							
Patricio Aguilar									
120338					8/3/2014		227		\$0.00
Medium	Work In Progress				8/3/2014 12:33:40 AM				
Munoz, Michael		Yearly - La Union ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.				PM not completed as per schedule			
Margret Villalobos									
129347					2/26/2015		20		\$0.00
Medium	Work In Progress				2/26/2015 1:03:30 PM				
Ontiveros, Joe		water heater mech room old wing leaking from bottom of tank. Will need to be replaced.							
Patricio Aguilar									
Count: 22 Work Orders			Avg. Age of WO's	50		Total for La Union ES	0		\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

120339 8/3/2014 227 \$0.00

Medium Work In Progress 8/3/2014 12:33:41 AM

Munoz, Michael Yearly - Loma Linda ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details. PM not completed as per schedule

Margret Villalobos

126973 1/4/2015 1/25/2015 73 \$0.00

Medium Work In Progress 1/4/2015 12:41:33 AM

Munoz, Michael Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

129988 Main Building 3/10/2015 8 \$0.00

Medium Work In Progress Casianos 3/10/2015 1:02:08 PM

Villalobos, Margret Please fumigate classroom for head lice outbreak 3/10/15 Emailed Waiver Form

Angie Flores

129672 3/3/2015 15 \$0.00

Medium Work In Progress 3/3/2015 12:25:22 AM

Apodaca, Mario Monthly - Loma Linda ES - Domestic Water Filter - Refer to PM schedule details.

Margret Villalobos

127636 Office 1/16/2015 61 \$0.00

Medium Work In Progress Mr. Smiths 1/16/2015 9:33:57 AM

Estrada, Jesus New carpet that was just installed this summer break is already tearing, please fix work order # 113380??

Angie Flores

127477 1/13/2015 64 \$0.00

Medium Work In Progress 1/13/2015 1:33:17 PM

Ontiveros, Guadalupe Pete need to request bobcat

Eric Medina

122914 Portables 9/17/2014 182 \$0.00

Medium Work In Progress 9/17/2014 1:23:41 PM

Estrada, Jesus provide new flooring to portable 1a/1b

Alfredo Holguin

130247 Main Building Classroom 3/17/2015 1 \$0.00

Medium Work In Progress 212,214,220,10 3/17/2015 10:41:46 AM

Villalobos, Margret Need to fumigate classrooms for head lice outbreak

Angie Flores

3/18/2015 12:54:24 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

130092 3/12/2015 6 \$0.00

Medium Work In Progress 3/12/2015 12:51:47 PM

Gonzalez, Salvador Sal need assistance in moving broken see saw

Eric Medina

122774 Portables 9/15/2014 184 \$0.00

Medium Work In Progress 9/15/2014 3:36:17 PM

Sotelo, Enrique need to provide power to new washer and drier room , and to new restroom. also will need a circuit for a lift table.

Michael Munoz

130079 Hallway/Corridor 3/12/2015 6 \$0.00

Medium Work In Progress 3/12/2015 9:29:09 AM

Sotelo, Enrique WE HAVE SOME LIGHTS OFF FROM THE HALLWAYS AND TWO BOYS RESTROOMS, ALSO THE SECURITY LIGHTS FROM THE BUILDING MAIN ENTRANCE TREE OF FOUR LIGHTS ARE NOT WORKING PROPERLY IS VERY DARK IN THE MORNING., THANKS.

Luis Solis

121440 8/19/2014 211 \$0.00

Medium Work In Progress 8/19/2014 3:03:42 PM

Orozco, Daniel LATCH THAT LOCKS THE WALK IN IS BROKEN. SNP MANAGER DOLORES R. 882.4707

Maritza Gonzalez

128522 2/5/2015 41 \$0.00

Medium Work In Progress 2/5/2015 11:52:58 AM

Orozco, Daniel DRAINS BACKING UP IN KITCHEN AREA. SNP MANAGER DOLORES R. 882.4707

Maritza Gonzalez

119567 7/18/2014 243 \$0.00

Medium Work In Progress 7/18/2014 10:50:19 AM

Orozco, Daniel BROKEN GLASS ON SERVING LINE.

Maritza Gonzalez

128871 2/12/2015 34 \$0.00

Medium Work In Progress 2/12/2015 3:38:53 PM

Orozco, Daniel AS PER ECO-LAB (BUD) DISHWASHER MOTOR CONTRACTOR ON UPPER CONTROL BOX NEEDS TO BE REPAIRED CORRECTLY.

Maritza Gonzalez

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
128872					2/12/2015		34		\$0.00
Medium	Work In Progress				2/12/2015 3:40:29 PM				
Orozco, Daniel		PER THE FIRE MARSHALL NEED TO CHANGE THE LIGHT BULB COVERS IN THE WALK IN AND FREEZER.							
Maritza Gonzalez									
129915					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:44 AM				
Medina, Eric		Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
129697	Main Building	Classroom			3/3/2015		15		\$0.00
Medium	Work In Progress	206			3/3/2015 10:31:14 AM				
Medina, Eric		Broken water faucet							
Angie Flores									
129760	Main Building	Classroom			3/4/2015		14		\$0.00
Medium	Work In Progress	211			3/4/2015 8:20:05 AM				
Medina, Eric		Several Lights are going out							
Angie Flores									
127596		Classroom			1/15/2015		62		\$0.00
Medium	Work In Progress	Arenas,			1/15/2015 1:31:35 PM				
Medina, Eric		Replace screen for windows in the following classrooms, Arenas, Talamantez, and Casiano							
Angie Flores									
129599					3/1/2015	3/7/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:57 AM				
Medina, Eric		Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
128154					1/30/2015		47		\$0.00
Medium	Work In Progress				1/30/2015 12:53:44 PM				
Medina, Eric		please fix lights in book room							
Eric Medina									
128394					2/3/2015		43		\$0.00
Medium	Work In Progress				2/3/2015 9:58:58 AM				
Medina, Eric		Need to paint and install covebase in SPED Portable.							
Danny Miranda									
3/18/2015 12:54:24 PM									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Loma Linda ES							
129440					2/28/2015	3/31/2015	18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:50 AM				
Medina, Eric		Yearly - Loma Linda ES C11 (Evap.Condnsr)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
129470					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:40 AM				
Medina, Eric		Yearly - Loma Linda ES A10 (Heat Pumps)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
129517					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:09 AM				
Medina, Eric		Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
129518					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:09 AM				
Medina, Eric		Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
129519					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:10 AM				
Medina, Eric		Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
122493					9/9/2014		190		\$0.00
Medium	Work In Progress				9/9/2014 8:41:31 AM				
Medina, Eric		Soccer Goals- Remove overgrown weeds and order and install new soccer nets.							
Alfredo Holguin									
122497					9/9/2014		190		\$0.00
Medium	Work In Progress				9/9/2014 8:46:31 AM				
Medina, Eric		Pine Trees along rock wall on west side of campus -Pick up pine needles and pine cones							
Alfredo Holguin									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
122498					9/9/2014		190		\$0.00
Medium	Work In Progress				9/9/2014 8:56:19 AM				
Medina, Eric		Portable area sidewalks- Order fill dirt (crusher fines or screenings) and backfill eroded areas next to sidewalks							
Alfredo Holguin									
125287	Main Building				11/7/2014		131		\$0.00
Medium	Work In Progress				11/7/2014 11:30:08 AM				
Medina, Eric		east Side exit doors need to be repainted properly							
Alfredo Holguin									
125786					11/19/2014		119		\$0.00
Medium	Work In Progress				11/19/2014 6:23:01 PM				
Medina, Eric		need to replace belt for fan coil in cafe							
Eric Medina									
130243		Classroom			3/17/2015		1		\$0.00
Medium	Work In Progress	Speech Room			3/17/2015 9:15:30 AM				
Marquez, Gerardo		Unable to open door to the speech room							
Angie Flores									
125217					11/6/2014		132		\$0.00
Medium	Work In Progress				11/6/2014 9:09:39 AM				
Ontiveros, Guadalupe		Pete need to request bobcat please							
Eric Medina									
130127					3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 10:53:59 AM				
Ontiveros, Guadalupe		Lupe need to order several loads of crusher fine for front campus please							
Eric Medina									
130128					3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 10:55:57 AM				
Ontiveros, Guadalupe		Lupe need to order several loads of playground sand for playground in front campus thank you							
Eric Medina									
128725					2/10/2015		36		\$0.00
Medium	Work In Progress	6th Grade			2/10/2015 11:19:10 AM				
Marquez, Gerardo		Cannot open with key, key just turns and turns but does not unlock							
Angie Flores									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Loma Linda ES							
123928					10/9/2014		160		\$0.00
Medium	Work In Progress	rm 105			10/9/2014 1:50:51 PM				
Marquez, Gerardo		need to replace classroom door							
Eric Medina									
120081					7/31/2014		230		\$0.00
Medium	Work In Progress				7/31/2014 9:06:08 AM				
Marquez, Gerardo		Gerrydoor handle in portable 4 was broken by vandals							
Eric Medina									
121485					8/20/2014		210		\$0.00
Medium	Work In Progress				8/20/2014 7:41:13 AM				
Marquez, Gerardo		Entrance Door in between 3rd and 6th grade hall, the core broke, its not working at all, need to have this fix so that school can be closed and locked.							
Angie Flores									
125017					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress				11/2/2014 12:36:27 AM				
Orozco, Daniel		Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
127651					1/16/2015		61		\$0.00
Medium	Work In Progress				1/16/2015 1:23:52 PM				
Orozco, Daniel		SLICER NOT WORKING AT ALL. SNP MANAGER DOLORES R. 882.4707							
Maritza Gonzalez									
126894					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:29 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
130126		Classroom			3/13/2015		5		\$0.00
Medium	Work In Progress	220			3/13/2015 10:30:09 AM				
Villalobos, David		Sink is cloged and also would like for t.x to be removed							
Angie Flores									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
130078		Restroom			3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 9:18:04 AM				
Villalobos, David		WE HAVE FIVE (5) TOILETS CLOGGED AND SOME ARE LEAKING WATER FROM THE PIPE LINES. AND ONE (1) UNIRAL IS OVERFLOWING , THESE TOILETS ARE COVER WITH PLASTIC BAGS FOR FEW DAYS ALREADY., PLEASE HELP US WITH THIS PROBLEM., THANKS.							
Luis Solis									
128649	Main Building	Restroom			2/9/2015		37		\$0.00
Medium	Work In Progress				2/9/2015 8:03:22 AM				
Villalobos, David		need to jet main sewer lines through out campus to sewer main							
David Villalobos									
122754		Pool			9/15/2014		184		\$0.00
Medium	Work In Progress				9/15/2014 10:42:21 AM				
Villalobos, David		As discussed , need to remove commode and sink in rest room and plumb out for washer and drier, commode and sink need to be plumbed out in the storage room across existing restroom . will need hot water also.							
Michael Munoz									
129884					3/6/2015		12		\$0.00
Medium	Work In Progress				3/6/2015 2:44:36 PM				
Villalobos, David		David need housing for j3 coupling for circulating pump for water heater							
Eric Medina									
Count: 49 Work Orders		Avg. Age of WO's 77			Total for Loma Linda ES			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
129946					3/9/2015		9		\$0.00
Medium	Work In Progress				3/9/2015 1:39:52 PM				
Villalobos, David		need assist. with a broken sprinkler line we will need the backhoe.							
Joe Ramirez									
128001		Mechanical			1/27/2015		50		\$0.00
Medium	Work In Progress				1/27/2015 3:30:39 PM				
Villalobos, David		Need to replace leaking water heater at mechanical room							
David Villalobos									
126897					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:31 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
129930					3/9/2015		9		\$0.00
Medium	Work In Progress				3/9/2015 9:19:40 AM				
Orozco, Daniel		ICE BUILD UP IN FREEZER FLOOR (SAFETY HAZARD). SNP MANAGER EMILIA C. 233-2341							
Maritza Gonzalez									
125018					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress				11/2/2014 12:36:28 AM				
Orozco, Daniel		Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
126417					12/9/2014		99		\$0.00
Medium	Work In Progress				12/9/2014 3:12:51 PM				
Orozco, Daniel		REPLACE WHEELS IN WALK IN AND REFRIGERATOR SHELVES. SNP MANAGER EMILIA C. 233.2341							
Maritza Gonzalez									
130229		Office			3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 8:07:18 AM				
Gonzales, Camilo		Pick up 1 Gaylord box and return to IMWHSE. See Arthur Moreno.							
Theresa Ramirez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Mesquite ES							
130245		Office			3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 9:17:25 AM				
Gonzales, Camilo		Deliver 10 boxes. PO# 141505663.							
Theresa Ramirez									
130215					3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 3:51:42 PM				
Marquez, Gerardo		we need front door handicap entrance to be repaired it does not open with a push of the button also the door stike and latch are not the right ones.							
Joe Ramirez									
130119					3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 8:01:49 AM				
Ontiveros, Guadalupe		i am requesting a case of pgm sprinklers atten. lupe o.							
Joe Ramirez									
128416	ArmyBuilding	Classroom			2/3/2015		43		\$0.00
Medium	Work In Progress	classrooms			2/3/2015 3:07:21 PM				
Marquez, Gerardo		Luis Saucedo/Head Custodian, needs C-Master made for classrooms.							
Sandra Mora									
128915					2/13/2015		33		\$0.00
Medium	Work In Progress				2/13/2015 3:27:50 PM				
Orozco, Daniel		AS PER ADELE'S INSPECTION REPORT- BUTTON ON MILK COOLER GETS STUCK.							
Maritza Gonzalez									
128912					2/13/2015		33		\$0.00
Medium	Work In Progress				2/13/2015 3:24:17 PM				
Orozco, Daniel		AS PER ADELE'S INSPECTION REPORT-GARBAGE DISPOSAL NOT WORKING PROPERLY.							
Maritza Gonzalez									
130088					3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 10:38:21 AM				
Sotelo, Enrique		need to install electrical strip in nurses' office							
Joe Ramirez									
130089					3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 10:39:23 AM				
Sotelo, Enrique		need to install electrical strip in computer lab.							
Joe Ramirez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To	Description				Action Taken				
Requester Name									
Location: Mesquite ES									
128861					2/12/2015		34		\$0.00
Medium	Work In Progress				2/12/2015 3:19:31 PM				
Ronquillo, Ruben	ramp leading to jungle jim set is in need of replacement there is rust and corrosion (safety issue).								
Joe Ramirez									
125497					11/13/2014		125		\$0.00
Medium	Work In Progress				11/13/2014 8:50:03 AM				
Gallegos, Rafael	atten. mr. Gallegos unit in rm.206 is showing no flame message also admin offices are cold.								
Joe Ramirez									
121639					8/22/2014		208		\$0.00
Medium	Work In Progress				8/22/2014 1:25:52 PM				
Estrada, Jesus	carpet in portable #601 needs to be repaired.								
Luis Saucedo									
128469					2/4/2015		42		\$0.00
Medium	Work In Progress				2/4/2015 12:35:41 PM				
Ontiveros, Guadalupe	eastside fenceline needs to be replaced (poor condition) this will be at the community park.								
Joe Ramirez									
129288		Custodial			2/25/2015		21		\$0.00
Medium	Work In Progress				2/25/2015 1:15:24 PM				
Estrada, Jesus	Mr. Estrada as per Mrs. silvaggio On room # 105 the carpet is torn out as per principal would like to replace it with tile. if it's possible can this be done during the summer break. If you have a chance, could you please stop by and see it. Thank you								
Luis Saucedo									
129590					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:51 AM				
Apodaca, Mario	Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
120340					8/3/2014		227		\$0.00
Medium	Work In Progress				8/3/2014 12:33:41 AM				
Munoz, Michael	Yearly - Mesquite ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.				PM not completed as per schedule				
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
122438					9/8/2014		191		\$0.00
Medium	Work In Progress				9/8/2014 8:47:31 AM				
Ramirez, Joe		need to paint math intervention rm.							
Joe Ramirez									
129592					3/1/2015	3/7/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:52 AM				
Ramirez, Joe		Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
Count: 24 Work Orders			Avg. Age of WO's	58		Total for Mesquite ES	0		\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		North Valley ES							
120341					8/3/2014		227		\$0.00
Medium	Work In Progress				8/3/2014 12:33:42 AM				
Munoz, Michael		Yearly - North Valley ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.				PM not completed as per schedule			
Margret Villalobos									
126978					1/4/2015		73		\$0.00
Medium	Work In Progress				1/4/2015 12:41:37 AM				
Munoz, Michael		Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
129447					2/28/2015		18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:55 AM				
Munoz, Michael		Yearly - North Valley ES - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
123956		Athletic Field			10/9/2014		160		\$0.00
High	Work In Progress				10/9/2014 3:38:52 PM				
Munoz, Michael		playground has broken platforms and a slide. need to replace.							
Alfredo Holguin									
126161		Exterior			12/3/2014		105		\$0.00
High	Work In Progress				12/3/2014 9:55:25 AM				
Ortiz, Ruben		Make sure all trash stuck to the fence line is picked up.							
Jesus Estrada									
130153					3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 3:47:08 PM				
Gonzalez, Salvador		need poles welded on to tire rims for volleyball nets 4 ea							
Danny Vega									
122505					9/9/2014		190		\$0.00
Medium	Work In Progress				9/9/2014 10:21:14 AM				
Gonzalez, Salvador		Principal would like to request a metal canopy at the bus turnaround, like the one at STE.							
Maria Hernandez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: North Valley ES

118856 7/1/2014 260 \$0.00

Medium Work In Progress 7/1/2014 8:39:58 AM

Ronquillo, Ruben (attention ruben ronquillo)progressive plygrd equip-have five broken platform parts 46 1/2 L x5 1/2 W x3 1/2 H beams-also missing stairs-removed by green contractor solutoins-safety hazard-please check into replacment parts-(800-585-3131)@progressive design equip.

Danny Vega

129712 3/3/2015 15 \$0.00

Medium Work In Progress 3/3/2015 1:11:00 PM

Sotelo, Enrique organ trail emergencyballast in hallwayby RM103 AND THROPY CASE

Danny Vega

129713 3/3/2015 15 \$0.00

Medium Work In Progress 3/3/2015 1:12:44 PM

Sotelo, Enrique pecan wing- emergencylamp ballast out byrm201-205-211

Danny Vega

129714 3/3/2015 15 \$0.00

Medium Work In Progress 3/3/2015 1:14:13 PM

Sotelo, Enrique rio grande wing emergencylamp ballast out byelectricl rm-byrm 310

Danny Vega

129715 3/3/2015 15 \$0.00

Medium Work In Progress 3/3/2015 1:21:12 PM

Sotelo, Enrique light switch bynurses office there is sparks when turned on also on the one bylounge/ total of two(2).please replacæ

Danny Vega

129168 2/23/2015 23 \$0.00

Medium Work In Progress 2/23/2015 2:17:23 PM

Sotelo, Enrique emergency lamp ballast are out in these mechanical rms byrm 101-109-203-201-207-301-304-303-306-308-311

Danny Vega

129169 2/23/2015 23 \$0.00

Medium Work In Progress 2/23/2015 2:20:22 PM

Sotelo, Enrique emergency lamp ballast are out in pipe chase rms organ trail by girls restrooms-pecan wing both pipe chases bys and girls

Danny Vega

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		North Valley ES							
129291					2/25/2015		21		\$0.00
Medium	Work In Progress				2/25/2015 2:39:24 PM				
Orozco, Daniel		SWITCH COVER TO SKILLET TO TURN ON IS MISSING.SNP MANANGER LAURA B. 233-3658							
Maritza Gonzalez									
126484					12/10/2014		98		\$0.00
Medium	Work In Progress				12/10/2014 3:37:49 PM				
Sotelo, Enrique		emergency lamp by rm310 is out bad ballast							
Danny Vega									
127224					1/8/2015		69		\$0.00
Medium	Work In Progress				1/8/2015 9:45:21 AM				
Sotelo, Enrique		emergency ballast out by hallway by rm 104-girls rr by rm 107-hallway by rm 202 by rm 206-by rm 211-by rm 305-by rm 300 conference- also pipe chase rm rio grand valley							
Danny Vega									
129685					3/3/2015		15		\$0.00
Medium	Work In Progress				3/3/2015 9:26:28 AM				
Vega, Danny		need 8ea splash blocks for bldg roof drains							
Danny Vega									
130169					3/14/2015		4		\$0.00
Medium	Work In Progress				3/14/2015 12:21:45 AM				
Vega, Danny		Daily - North Valley ES - Fire Pump (Biweekly) - Refer to PMschedule details.							
Margret Villalobos									
129992					3/10/2015		8		\$0.00
Medium	Work In Progress				3/10/2015 3:20:09 PM				
Vega, Danny		need 4 tires cemented with a pole for volleyball tennis and variuos activitys							
Danny Vega									
129993					3/10/2015		8		\$0.00
Medium	Work In Progress				3/10/2015 3:23:09 PM				
Vega, Danny		need 3 basketball rims replaced/they are broken and welded before							
Danny Vega									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
129202					2/24/2015		22		\$0.00
Medium	Work In Progress				2/24/2015 8:05:39 AM				
Vega, Danny		need weed and feed fertilizer spread on grass fields- 35ea bags.have clover and other types of weeds taking over grass.							
Danny Vega									
130304		Classroom			3/18/2015		0		\$0.00
Medium	Work In Progress	305			3/18/2015 10:08:11 AM				
Vega, Danny		Please lower a few desks in order to make them all the same height							
Gloria Reyes									
129876					3/6/2015		12		\$0.00
Medium	Work In Progress				3/6/2015 1:08:53 PM				
Vega, Danny		need to replace bad sprinklers 12 ea 1-25 hunters ss (adjustable)6 ea 1-25-hunter 36s plus 2 bad silinoids rainbird #20953202							
Danny Vega									
129913					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:43 AM				
Vega, Danny		Monthly - North Valley ES Playground Inspection - Refer to PMschedule details.							
Margret Villalobos									
125007					11/2/2014		136		\$0.00
Medium	Work In Progress				11/2/2014 12:36:21 AM				
Orozco, Daniel		Monthly - North Valley ES - Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									
129926					3/9/2015		9		\$0.00
Medium	Work In Progress				3/9/2015 8:03:18 AM				
Orozco, Daniel		ICE MACHINE DOWN, NO ICE. SNP MANAGER LAURAB.233-3658							
Maritza Gonzalez									
127844					1/23/2015		54		\$0.00
Medium	Work In Progress				1/23/2015 10:40:59 AM				
Orozco, Daniel		FLOOR LOOSE INSIDE WALK IN.SNP MANAGER LAURA B. 233.3658							
Maritza Gonzalez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: North Valley ES										
127944					1/26/2015		51		\$0.00	
Medium	Work In Progress				1/26/2015 2:42:14 PM					
Orozco, Daniel	ICE MACHINE IS NOT WORKING, NOT MAKING ICE. SNP MANAGER LAURA B. 233.3658									
Maritza Gonzalez										
126907					1/4/2015	2/4/2015	73		\$0.00	
Medium	Work In Progress				1/4/2015 12:40:39 AM					
Villalobos, David	Yearly - North Valley ES Backflow Inspection - Refer to PM schedule details.									
Margret Villalobos										
128779					2/11/2015		35		\$0.00	
Medium	Work In Progress				2/11/2015 9:42:33 AM					
Villalobos, David	need boiler hot water circulating replaced in rio grande wing mechanical rm/hot water takes a while to reach rms									
Danny Vega										
128098		Classroom			1/29/2015		48		\$0.00	
Medium	Work In Progress	Nurse's office			1/29/2015 12:00:31 PM					
Villalobos, David	As per Mrs. Hernandez, nurse's office is requesting a small hot water heater to provide warm water for washing hands, gargles, etc.									
Gloria Reyes										
120825		Parking Lot			8/8/2014		222		\$0.00	
Medium	Work In Progress	front door area			8/8/2014 12:15:43 PM					
Villalobos, David	As per Principal, please install a water hose bit in the front of the building. Please visit Principal for specifics.									
Priscilla Martinez										
Count: 33 Work Orders		Avg. Age of WO's 62		Total for North Valley ES			0	\$0.00		

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

129949 3/9/2015 9 \$0.00

Medium Work In Progress 3/9/2015 3:02:16 PM

Villalobos, David WATER FOUNTAIN BEHIND BUILDING IS CONTINUOUSLY RUNNING, AND LEAKING. SHUT-OFF VALVE IN BOILER ROOM TO PREVENT ANY FURTHER LEAKING.

Adam Montoya

129646 Main Building 3/2/2015 16 \$0.00

Medium Work In Progress 3/2/2015 3:13:38 PM

Villalobos, David DAYCARE CLASSROOMS 112 AND 114, HOT WATER IS NOT WORKING.

Adam Montoya

126895 1/4/2015 2/4/2015 73 \$0.00

Medium Work In Progress 1/4/2015 12:40:30 AM

Villalobos, David Yearly - Northern Pre-K Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

129914 3/9/2015 3/24/2015 9 \$0.00

Medium Work In Progress 3/9/2015 12:35:44 AM

Vega, Danny Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.

Margret Villalobos

130294 Main Building Hallway/Corridor 3/17/2015 1 \$0.00

Medium Work In Progress reception area 3/17/2015 4:36:59 PM

Vega, Danny Please remove small bulletin board and replace with new one.

Concepcion Montalvo

129779 Main Building Hallway/Corridor 3/4/2015 14 \$0.00

Medium Work In Progress 3/4/2015 3:08:17 PM

Sotelo, Enrique GFCI ACROSS FROM CLASSROOM 110 IS NOT WORKING. NEEDED FOR HALLWAY WATER FOUNTAIN.

Adam Montoya

126790 Main Building 12/19/2014 89 \$0.00

Medium Work In Progress 12/19/2014 8:00:45 AM

Ontiveros, Guadalupe (AS PER THE DAYCARE) NEED SAND DELIVERED FOR FRONT OF BUILDING SANDBOX.

Adam Montoya

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Northern On-Track Pre-K (LM)									
129585					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:49 AM				
Apodaca, Mario	Monthly - Northern Pre-K -Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 8 Work Orders			Avg. Age of WO's	29	Total for Northern On-Track Pre-K (LM)			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
126289		Office			12/5/2014		103		\$0.00
Medium	Work In Progress			12/5/2014 2:19:58 PM					
Solis, Lorenzo	the evaporative cooler at service the locks smith and water/wastewater and maintenance warehouse needs to be updated due to the one that's on its all rusted out								
Mario Apodaca									
128609					2/6/2015		40		\$0.00
Medium	Work In Progress			2/6/2015 3:36:55 PM					
Apodaca, Mario	meet to order a powerverter for truck 38 to mount in the toolbox								
Mario Apodaca									
129459					2/28/2015		18		\$0.00
Medium	Work In Progress			2/28/2015 12:35:03 AM					
Apodaca, Mario	Monthly - PPD/GHS - WW Monthly Sampling - Refer to PM schedule details.								
Margret Villalobos									
129494					3/1/2015		17		\$0.00
Medium	Work In Progress			3/1/2015 12:45:55 AM					
Apodaca, Mario	Monthly - Physical Plant - Grease Trap (Custodial) - Refer to PM schedule details.								
Margret Villalobos									
129184					2/23/2015		23		\$0.00
Medium	Work In Progress			2/23/2015 3:33:12 PM					
Apodaca, Mario	Need to reorder Dynasty orange cream To maintain lift stations District wide And other uses								
Mario Apodaca									
129009					2/18/2015		28		\$0.00
Medium	Work In Progress			2/18/2015 8:34:35 AM					
Apodaca, Mario	need to reorder domestic water filter for district wide uses								
Mario Apodaca									
127600		Office			1/15/2015		62		\$0.00
Medium	Work In Progress			1/15/2015 3:30:01 PM					
Estrada, Jesus	NEED QUOTE FOR VCT TO BE REPLACED IN PPD FRONT ENTRANCE & OFFICE.								
Jesus Estrada									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
127534					1/14/2015		63		\$0.00
Medium	Work In Progress				1/14/2015 1:58:36 PM				
Estrada, Jesus	Install new carpet in Julie's office, once office is painted to match Alfredo's carpet.								
Michael Munoz									
122868					9/16/2014		183		\$0.00
Medium	Work In Progress				9/16/2014 3:48:24 PM				
Ronquillo, Ruben	ORDER 4EA. ENGINE DRIVEN WATER PUMPS, WITH HOSES. THANK YOU								
Ruben Ronquillo									
130002					3/10/2015		8		\$0.00
Medium	Work In Progress				3/10/2015 3:42:29 PM				
Ronquillo, Ruben	DISCHARGE PERMIT APPLICATION SIGN NEW SHCOOL AT CHAPARRAL								
Ruben Ronquillo									
130029					3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 11:02:35 AM				
Ronquillo, Ruben	DISPOSE OF OBSOLETE HAVC PARTS AND MATERIALS								
Ruben Ronquillo									
128728					2/10/2015		36		\$0.00
Medium	Work In Progress				2/10/2015 12:07:15 PM				
Diaz, Sebastian	light in Alfredo office needs to be replaced								
Mary Sitters									
128720	Maintenance				2/10/2015		36		\$0.00
Medium	Work In Progress	Old Energy			2/10/2015 10:38:57 AM				
Diaz, Sebastian	Replace all light bulbs and dust out light fixtures.								
Cynthia Maes									
130098		Custodial			3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 3:10:02 PM				
Gonzalez, Salvador	BRACKET ON WASHER BROKE CAUSING WASHER TO SHAKE AND MAKE ALOT OF NOISE WHEN RUNNING ALFERDO WANTS IT TO BE WELDED AGAIN								
Jimmy Carbajal									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

129808 3/5/2015 13 \$0.00

Medium Work In Progress 3/5/2015 8:00:32 AM

Gonzalez, Salvador 3-5-15
Requesting impact gun with sockets

Salvador Gonzalez

130227 3/17/2015 1 \$0.00

Medium Work In Progress 3/17/2015 8:03:09 AM

Gonzalez, Salvador need to fabricate plate and tubing lifter

Salvador Gonzalez

129939 Motor Vehicle 3/9/2015 9 \$0.00

Medium Work In Progress FED VEHICLE 3/9/2015 11:15:22 AM

Perez, Raul CAR WASH

Noemi Duron

129940 Motor Vehicle 3/9/2015 9 \$0.00

Medium Work In Progress FED VEHICLE 3/9/2015 11:20:25 AM

Perez, Raul CAR WASH

Noemi Duron

129941 Motor Vehicle 3/9/2015 9 \$0.00

Medium Work In Progress FED VEHICLE 3/9/2015 11:21:40 AM

Perez, Raul CAR WASH

Noemi Duron

130033 Motor Vehicle 3/11/2015 7 \$0.00

Medium Work In Progress vehicles#35,36 3/11/2015 12:44:55 PM

Flores, Pete please check for any required maintenance.mileage
for#35 is 7957,9353 for #36

Pete Flores

129937 Motor Vehicle 3/9/2015 9 \$0.00

Medium Work In Progress FEDERAL 3/9/2015 10:34:07 AM

Flores, Pete OIL CHANGE LIGHT ON

Noemi Duron

129982 Motor Vehicle 3/10/2015 8 \$0.00

Medium Work In Progress equip#0411 3/10/2015 9:43:46 AM

Flores, Pete please check electrical system for proper starting and
any additional scheduled maintenance

Pete Flores

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
129947	Motor Vehicle				3/9/2015		9		\$0.00
Medium	Work In Progress				3/9/2015 2:01:14 PM				
Flores, Pete		vehicle 187 passenger window doesn't roll up or down							
130133					3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 12:51:34 PM				
Flores, Pete		(SNP Warehouse) Electrical pallet jack electrical identification cover broke.							
		Thx Jose							
Maritza Gonzalez									
129395	Motor Vehicle				2/27/2015		19		\$0.00
Medium	Work In Progress	FED. VEHICLE			2/27/2015 10:33:32 AM				
Flores, Pete		VEHICLE WILL BE TRAVELING TO ALBUQUERQUE REQUESTING A QUICK GENERAL CHECK UP.							
Noemi Duron									
129690	Motor Vehicle				3/3/2015		15		\$0.00
Medium	Work In Progress				3/3/2015 10:23:53 AM				
Flores, Pete		vehicle 188; gas gauge doesn't work correctly reported by Gilbert Bailon							
Maria Ruiz									
129692	Motor Vehicle				3/3/2015		15		\$0.00
Medium	Work In Progress				3/3/2015 10:26:26 AM				
Flores, Pete		locks on don't work 178 & 179 bad actuator (driver's side)							
Maria Ruiz									
129694	Motor Vehicle				3/3/2015		15		\$0.00
Medium	Work In Progress	vehicle#136			3/3/2015 10:27:34 AM				
Flores, Pete		please check condition of front brakes.							
Pete Flores									
129700	Motor Vehicle				3/3/2015		15		\$0.00
Medium	Work In Progress	vehicle#46			3/3/2015 10:34:42 AM				
Flores, Pete		check and advise on cause of engine coolant loss.							
Pete Flores									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex									
129701	Motor Vehicle				3/3/2015		15		\$0.00
Medium	Work In Progress	vehicle#183			3/3/2015 10:38:07 AM				
Flores, Pete		please check on cause of driver's window not rolling up and down							
Pete Flores									
129705	Motor Vehicle				3/3/2015		15		\$0.00
Medium	Work In Progress	vehicle#148			3/3/2015 11:16:53 AM				
Flores, Pete		please check cause of a/c refrigerant loss							
Pete Flores									
130297	Motor Vehicle				3/18/2015		0		\$0.00
Medium	Work In Progress	vehicle#151			3/18/2015 8:36:01 AM				
Flores, Pete		please check for a/c refrigerant loss							
Pete Flores									
130305	Motor Vehicle				3/18/2015		0		\$0.00
Medium	Work In Progress				3/18/2015 10:15:56 AM				
Flores, Pete		Please service and check vehicle 99.							
Alfredo Holguin									
129017	Purchasing	Office			2/18/2015		28		\$0.00
Medium	Work In Progress				2/18/2015 9:18:44 AM				
Flores, Pete		The forklift in the Instructional Materials Department will not start. It is also in need of a tune-up, oil change, etc. Please see Theresa or Larry.							
Theresa Ramirez									
128280	Motor Vehicle				2/1/2015		45		\$0.00
Medium	Work In Progress				2/1/2015 12:50:37 AM				
Flores, Pete		Monthly - PPD-MP-0143 DT PM Service - by SWP - Refer to PM schedule details.							
Margret Villalobos									
128281	Motor Vehicle				2/1/2015		45		\$0.00
Medium	Work In Progress				2/1/2015 12:50:38 AM				
Flores, Pete		Monthly - PPD-T-0529 PM (Trencher) - by SWP - Refer to PM schedule details.							
Margret Villalobos									
128130	Motor Vehicle				1/30/2015		47		\$0.00
Medium	Work In Progress	tilt trailer			1/30/2015 8:20:03 AM				
Flores, Pete		battery is more than 5 years old, requires replacement.							
Pete Flores									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

129350 Motor Vehicle 2/26/2015 20 \$0.00

Medium Work In Progress 1050 tractor- 2/26/2015 2:22:42 PM

Flores, Pete please check cause of tractor not starting.

Pete Flores

128931 2/14/2015 32 \$0.00

Medium Work In Progress 2/14/2015 12:21:53 AM

Flores, Pete Yearly - PPD-T-0524 Bobcat PM Service - Refer to PM schedule details.

Margret Villalobos

127922 Main Warehouse 1/26/2015 51 \$0.00

Medium Work In Progress 1/26/2015 1:30:57 PM

Flores, Pete SNP VEHHICLE 56 NEEDS TO BE SERVICED.

Maritza Gonzalez

127923 Main Warehouse 1/26/2015 51 \$0.00

Medium Work In Progress 1/26/2015 1:31:10 PM

Flores, Pete SNP VEHHICLE 52 NEEDS TO BE SERVICED.

Maritza Gonzalez

127924 Main Warehouse 1/26/2015 51 \$0.00

Medium Work In Progress 1/26/2015 1:31:21 PM

Flores, Pete SNP VEHHICLE 43 NEEDS TO BE SERVICED.

Maritza Gonzalez

127958 Motor Vehicle 1/26/2015 51 \$0.00

Medium Work In Progress Federal vehicle 1/26/2015 3:44:58 PM

Flores, Pete When driving in a long road and picking up speed the vehicle starts to jerk. Also, windows on driver side front and passenger back do not work.

Noemi Duron

127462 Motor Vehicle 1/13/2015 64 \$0.00

Medium Work In Progress vehicle#147 1/13/2015 9:39:06 AM

Flores, Pete rear driver's side window inoperative, please check cause of malfunction.

Pete Flores

127289 Motor Vehicle 1/9/2015 68 \$0.00

Medium Work In Progress vehicle#100 1/9/2015 10:33:33 AM

Flores, Pete please check cause of vehicle leaning excessively to one side.

Pete Flores

3/18/2015 12:54:25 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Physical Plant Complex									
127546	Motor Vehicle				1/14/2015		63		\$0.00
Medium	Work In Progress	chaparral golf			1/14/2015 3:17:18 PM				
Flores, Pete	please prepare fairplay golf cart for use by chaparral security								
Pete Flores									
127251					1/8/2015		69		\$0.00
Medium	Work In Progress				1/8/2015 3:20:43 PM				
Flores, Pete	TRUCK #32 NEEDS FUEL PUMP REPLACED								
Ruben Ronquillo									
119759					7/23/2014		238		\$0.00
Medium	Work In Progress				7/23/2014 2:32:20 PM				
Flores, Pete	MAINTANCE ON ALL SPED VEHICLES SUBMIT INVOICE TO JULIE HERNANDEZ								
Margaret Villalobos									
124450					10/22/2014		147		\$0.00
Medium	Work In Progress				10/22/2014 11:21:12				
Flores, Pete	vehicle 01, needs wipers and check engine light turned on and turned off (reported by Teresa Ortega)								
Maria Ruiz									
122443	Motor Vehicle				9/8/2014		191		\$0.00
Medium	Work In Progress	ag trailer			9/8/2014 9:06:23 AM				
Flores, Pete	please prepare trailer as required for use by agriculture dept.								
Pete Flores									
128653	Maintenance	Office			2/9/2015		37		\$0.00
Medium	Work In Progress				2/9/2015 8:16:17 AM				
Lara, Ralph	WE NEED TWO TRIPP POWER VERTAR 3000W TO USED THEM ON DISTRICT VANS, FOR CUTTING KEYS ON DIFFRENT SCHOOL SITES.								
Ralph Lara									
129010		Athletic Field			2/18/2015		28		\$0.00
High	Work In Progress				2/18/2015 8:37:22 AM				
Ontiveros, Guadalupe	Dump truck needs tarp replaced in order to transport material.								
Guadalupe Ontiveros									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
128508		Lift Station			2/5/2015		41		\$0.00
Medium	Work In Progress				2/5/2015 8:24:35 AM				
Ontiveros, Guadalupe	need the assistance of a heavy equipment operator and tractor to help us replace a air relief check valve on the west side of the river bank								
Mario Apodaca									
129929					3/9/2015		9		\$0.00
Medium	Work In Progress				3/9/2015 8:36:25 AM				
Marquez, Gerardo	NEED TO ORDER TOOLS AND MATERIAL FOR USE DISTRICTWIDE.								
Gerardo Marquez									
126240					12/4/2014		104		\$0.00
Medium	Work In Progress				12/4/2014 12:43:22 PM				
Marquez, Gerardo	One (1) key needed for electrical room at New Food WHS. Please drop off key at the construction office. Key needed as soon as possible. Should you have any questions please contact Mr. Ralph Gallegos at 575-882-6921 in the Construction office. Thank You								
Dominique Esparza									
124720	Motor Vehicle				10/29/2014		140		\$0.00
Medium	Work In Progress				10/29/2014 8:23:36 AM				
Marquez, Gerardo	COULD YOU PLEASE REPLACE A LOCK ON CABINET IN AUTO SHOP USED FOR CUSTODIAL SUPPLIES IF YOU HAVE ANY QUESTIONS PLEASE CONTACT FERNANDA THE MORNING CUSTODIAN. (2ND REQUEST)								
Jimmy Carbajal									
122948					9/18/2014		181		\$0.00
Medium	Work In Progress				9/18/2014 8:57:40 AM				
Marquez, Gerardo	New Warehouse- Rekey off grand Master - Check with Mike - Alfredo on keying								
Alfredo Holguin									
128464	Motor Vehicle				2/4/2015		42		\$0.00
Medium	Work In Progress	New Annex Bldg			2/4/2015 10:58:49 AM				
Marquez, Gerardo	Need to install doors on Metal Bldg on westside of Autoshop (see Alfredo H. for ?'s)								
Alfredo Holguin									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

128702 Purchasing 2/9/2015 37 \$0.00

Medium Work In Progress New Warehouse 2/9/2015 4:11:54 PM

Marquez, Gerardo
Keys to be assigned to Cynthia Maes for the New Warehouse Offices, storage room and restrooms. I would like to meet Jerry out there when he is done making the keys he can call me-Cynthia at 882-6949.

Cynthia Maes

129073 2/19/2015 27 \$0.00

Medium Work In Progress 2/19/2015 1:50:46 PM

Sotelo, Enrique
In the Construction Office fix/ change outlets or add more outlets under desk. For questions please see Dominique Esparza for more information

Dominique Esparza

126898 1/4/2015 2/4/2015 73 \$0.00

Medium Work In Progress 1/4/2015 12:40:32 AM

Villalobos, David
Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

130120 3/13/2015 5 \$0.00

Medium Work In Progress 3/13/2015 8:02:08 AM

Villalobos, David
need replacement cables and accessories to Rigid sewer machines

David Villalobos

127567 1/15/2015 62 \$0.00

Medium Work In Progress 1/15/2015 7:52:14 AM

Carrasco, Danny
need to remove Julies desk modular, carpet will be replaced. this needs to be done by tomorrow so that carpet be installed over the weekend.

Jesus Estrada

128562 2/6/2015 40 \$0.00

Medium Work In Progress 2/6/2015 8:10:24 AM

Carrasco, Danny
need to reorder alcohol to disinfect water sampling points and distilled water to rinse off pH meter and other testing equipment

Mario Apodaca

127533 1/14/2015 63 \$0.00

Medium Work In Progress 1/14/2015 1:56:21 PM

Carrasco, Danny
Paint Juliet's Office.

Michael Munoz

3/18/2015 12:54:25 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
128463	Maintenance				2/4/2015		42		\$0.00
Medium	Work In Progress				2/4/2015 10:57:20 AM				
Holguin, Alfredo	Need quote to insulate Metal Bldg on westside of Autoshop.								
Alfredo Holguin									
129537					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:21 AM				
Ruiz, Maria	Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.								
Margret Villalobos									
129769	Motor Vehicle				3/4/2015		14		\$0.00
Medium	Work In Progress				3/4/2015 11:50:51 AM				
Ruiz, Maria	replace/repair windshield vehicles 40,109,171 & 183								
Maria Ruiz									
129148	Motor Vehicle				2/23/2015		23		\$0.00
Medium	Work In Progress	New Annex Bldg			2/23/2015 9:38:06 AM				
Vallejo, Albert	Need to install Electrical power outlets in metal bldg behind Auto Shop - (see Alfredo H. for ?'s)								
Alfredo Holguin									
127691					1/20/2015		57		\$0.00
Medium	Work In Progress				1/20/2015 10:04:05 AM				
Miranda, Danny	PPD Offices - remodeling new office.								
Alfredo Holguin									
Count: 70 Work Orders			Avg. Age of WO's	45		Total for Physical Plant Complex	0		\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

126797 12/19/2014 89 \$0.00

Medium Work In Progress 12/19/2014 9:48:59 AM

Castillo, Carlos Need Carlos C. to fix bad lighting fixtures in room 101.

Mario Martinez

128336 2/2/2015 44 \$0.00

Medium Work In Progress 2/2/2015 9:50:24 AM

Castillo, Carlos 2/02/2015.
Need Carlos C to fix non working lights in South wing and main wing.

Mario Martinez

126703 12/17/2014 91 \$0.00

Medium Work In Progress 12/17/2014 9:35:14 AM

Orozco, Daniel AS PER INSPECTION REPORT, DRAINS ON LEFT SIDE OF SERVING LANE ARE NOT WORKING PROPERLY, WATER IS BEING DISPENSED MANUALLY.

Maritza Gonzalez

125019 11/2/2014 11/23/2014 136 \$0.00

Medium Work In Progress 11/2/2014 12:36:28 AM

Orozco, Daniel Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

126899 1/4/2015 2/4/2015 73 \$0.00

Medium Work In Progress 1/4/2015 12:40:33 AM

Villalobos, David Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

129011 2/18/2015 28 \$0.00

Medium Work In Progress 2/18/2015 8:38:40 AM

Orozco, Daniel OVEN IS NOT HEATING PROPERLY. SNP MANAGER SANTA N. 589.2550

Maritza Gonzalez

128738 2/10/2015 36 \$0.00

Medium Work In Progress 2/10/2015 2:35:35 PM

Orozco, Daniel AS PER ADELE INSPECTION REPORT- BLODGET- TOP OVEN LOOSES TEMPATURE, WAS ONCE REPAIRED AND WAS WORKING WELL FOR A WHILE. DOING THE SAME THING AGAIN.

Maritza Gonzalez

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
119185					7/8/2014		253		\$0.00
Medium	Work In Progress				7/8/2014 7:28:48 AM				
Marquez, Gerardo		7/08/2014.							
		Need Rafa L. to fix door lock at library.							
Mario Martinez									
129759					3/4/2015		14		\$0.00
Medium	Work In Progress	main school			3/4/2015 8:19:53 AM				
Marquez, Gerardo		second request for front main door closer. reference work order# 128792. this work order shows it's been closed but door remains non-functional. please send Rafa a.s.a.p. (Navarro)							
Rosa Quezada									
126186	Main Building	Cafeteria			12/3/2014		105		\$0.00
Medium	Work In Progress	cafeteria			12/3/2014 3:23:58 PM				
Lara, Ralph		need to install a doorbell in north side door of the cafeteria for incoming deliveries to the cafeteria. vendors waiting outside to deliver because we don't know they are out there and we can hear them knocking on the door. (santa Nava)							
Rosa Quezada									
129758		Office			3/4/2015		14		\$0.00
Medium	Work In Progress	IEP STORAGE			3/4/2015 7:54:46 AM				
Lara, Ralph		NEED RAFA TO RE-KEY THE IEP STORAGE ROOM TO OPEN WITH A F62 KEY. NEED EXTRA KEY ALSO. (NAVARRO)							
Rosa Quezada									
127176					1/7/2015		70		\$0.00
Medium	Work In Progress				1/7/2015 10:42:19 AM				
Lara, Ralph		1/07/2015.							
		Need Rafa L. to replace old double door Mullions with new single key Mullions, also need panic bar door handle fixed. Would also like new hardware kits for all door mullions.							
Mario Martinez									
129163					2/23/2015		23		\$0.00
Medium	Work In Progress				2/23/2015 12:30:22 PM				
Lara, Ralph		2/23/2015.							
		Need Rafa L. to fix or replace broken Handicap automatic door opener/closer.							
Mario Martinez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
124407					10/21/2014		148		\$0.00
Medium	Work In Progress				10/21/2014 1:30:42 PM				
Lara, Ralph		10/21/2014. Need Rafa L. to rekey cylinders to off master at room #76,							
Mario Martinez									
120025					7/30/2014		231		\$0.00
Medium	Work In Progress				7/30/2014 1:46:51 PM				
Lara, Ralph		Rekeylocks from storage bins from DP to RS. (Danny C. has the locks)							
Michael Munoz									
130254					3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 11:33:57 AM				
Lara, Ralph		Lost Keys on Riverside Kitchen Upgrade Project. one (1) RS/ST gate key, two (2) ST 1 keys, & two (2) CD keys. Please process paper work so we can bill G. Sandoval Construction for lost keys. Should you have any questions please contact Mr. Gallegos at 575-882-6925.							
Dominique Esparza									
129221	Main Building				2/24/2015		22		\$0.00
Medium	Work In Progress				2/24/2015 10:50:22 AM				
Perez, Raul		vehicle 46 is leaking and smoke was coming out reported by Rocio Herrera							
Maria Ruiz									
121876					8/28/2014		202		\$0.00
Medium	Work In Progress				8/28/2014 7:33:04 AM				
Gallegos, Rafael		Warranty Work Order!!! Water leaking at roof and walls at rooms #21,25,37,28,33,39,34, and#41.							
Mario Martinez									
125498					11/13/2014		125		\$0.00
Medium	Work In Progress				11/13/2014 9:05:14 AM				
Gallegos, Rafael		WATER VALVE NEXT TO STOVE NEEDS TO BE TIGHTENED. WATER COMES OUT WHEN TURNED ON.SNP MANAGER S.NAVA							
Maritza Gonzalez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Riverside ES							
125443					11/12/2014		126		\$0.00
Medium	Work In Progress				11/12/2014 2:42:17 PM				
Gallegos, Rafael		SERVING LINE- ELECTRIC OUTLET DOES NOT HAVE NEUTRAL TO 120V TO CONNECT TO REFRIGERATOR.							
Maritza Gonzalez									
124633					10/27/2014		142		\$0.00
Medium	Work In Progress				10/27/2014 3:17:04 PM				
Gallegos, Rafael		10/27/2014. Need TPO roof above teachers lounge and above computer room #2 looked at for possible re roofing.							
Mario Martinez									
127260					1/8/2015		69		\$0.00
High	Work In Progress				1/8/2015 3:41:48 PM				
Ambriz, Jose		please clean all strainers to coils for proper heating. the contract did not include flushing lines. thank you							
Michael Munoz									
122686					9/12/2014		187		\$0.00
Medium	Work In Progress				9/12/2014 8:17:14 AM				
Ambriz, Jose		check cooling in room 136							
Michael Munoz									
119633					7/21/2014		240		\$0.00
Medium	Work In Progress				7/21/2014 10:19:47 AM				
Ontiveros, Guadalupe		7/21/2014. Booster pump for main irrigation sprinkler not working. Soccer field drying up. Need assistance with booster pump.							
Mario Martinez									
129001					2/18/2015		28		\$0.00
Medium	Work In Progress				2/18/2015 7:55:14 AM				
Ontiveros, Guadalupe		Need assistance with locating buried and lost sprinkler valves							
Mario Martinez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
130032					3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 12:22:11 PM				
Ontiveros, Joe		3/11/2015. Need plumber Joe O. to unstop main sewer line at Middle wing. Emergency, ASAP. Thanks.							
Mario Martinez									
121838					8/27/2014		203		\$0.00
Medium	Work In Progress				8/27/2014 12:58:57 PM				
Ontiveros, Joe		Need plumber Joe O. to fix leaky urinal in boys restroom at north wing.							
Mario Martinez									
127174					1/7/2015		70		\$0.00
Medium	Work In Progress				1/7/2015 10:13:02 AM				
Ontiveros, Joe		1/07/2015. Need Joe O. to repair or replace five flush valves at boys and girls bathrooms. Also need to replace open elongated toilet seat							
Mario Martinez									
125700					11/18/2014		120		\$0.00
Medium	Work In Progress				11/18/2014 3:36:23 PM				
Ontiveros, Joe		11/18/2014. Need PLUMBER Joe O. to replace 8 inch center faucets in rooms # 117, 141, and 137.							
Mario Martinez									
124523					10/23/2014		146		\$0.00
Medium	Work In Progress				10/23/2014 3:19:44 PM				
Martinez, Mario		10/23/2014. Need air compressor and electric hammer drill for future use. If you can please purchase for Riverside Elementary.							
Mario Martinez									
129569					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:39 AM				
Martinez, Mario		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Riverside ES							
129570					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:40 AM				
Martinez, Mario		Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
129609					3/1/2015	3/7/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:47:03 AM				
Martinez, Mario		Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
129345					2/26/2015		20		\$0.00
Medium	Work In Progress				2/26/2015 12:36:28 PM				
Martinez, Mario		2/26/2015. Need to purchase 4 tarps to cover furniture left out side of buildinds.							
Mario Martinez									
129473					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:42 AM				
Martinez, Mario		Yearly - Riverside ES A-10 HP Rooftop Yearly - Refer to PM schedule details.							
Margret Villalobos									
129452					2/28/2015		18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:58 AM				
Martinez, Mario		Monthly - Riverside ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.							
Margret Villalobos									
129436					2/28/2015	3/31/2015	18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:47 AM				
Martinez, Mario		Yearly - Riverside ES C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
129921					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:48 AM				
Martinez, Mario		Monthly - Riverside ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
121247	Main Building	Classroom			8/15/2014		215		\$0.00
Medium	Work In Progress	nurses station			8/15/2014 10:30:55 AM				
Martinez, Mario		we need two installed two SECURED cabinets in the nurses station with lock and key for medicine storage. (navarro)							
Rosa Quezada									
130266					3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 2:40:58 PM				
Martinez, Mario		Need to fertilize soccer field and entire lawn.							
Mario Martinez									
Count: 40 Work Orders		Avg. Age of WO's 85			Total for Riverside ES			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: RTC - Alliance									
126234		Office			12/4/2014		104		\$0.00
Medium	Work In Progress				12/4/2014 11:06:49 AM				
Moncayo, Fernando		the office heater has not turned on/ it has been below 50 for the past 2days/ have tried to turn on and off to reset and even walked in and out rooms for the sensor /have the dial up to 90 it does not turn on							
Gloria Delgado									
129838		Portables			3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 3:32:44 PM				
Moncayo, Fernando		1. mount a pencil sharpener in Ms. Arreola's class 2. change a wall organizer to another wall in the office							
Gloria Delgado									
127239		Portables			1/8/2015		69		\$0.00
Medium	Work In Progress				1/8/2015 1:15:33 PM				
Moncayo, Fernando		ramps very slippery and Mrs. Hirsch's classroom heater not working Mr. Moncada came in salted ramps and fixed heater							
Gloria Delgado									
124511		Portables			10/23/2014		146		\$0.00
Medium	Work In Progress				10/23/2014 12:17:58				
Moncayo, Fernando		Need light bulbs changed in the office. Fire escape security windows keep opening secure locks while maintaing safety egress							
Gloria Delgado									
Count: 4 Work Orders		Avg. Age of WO's 83			Total for RTC - Alliance			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: San Miguel ES									
126901					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:34 AM				
Villalobos, David		Yearly - San Miguel ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
129587					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:50 AM				
Apodaca, Mario		Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
Count: 2 Work Orders		Avg. Age of WO's	45			Total for San Miguel ES	0		\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
125848					11/21/2014		117		\$0.00
Medium	Work In Progress				11/21/2014 2:28:51 PM				
Munoz, Michael		need new fencing with gates to prevent students from going into parking lots							
Juan Ambriz									
129475					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:43 AM				
Ambriz, Juan		Yearly - Santa Teresa ES A-10 HEAT PUMPS (ANNUAL) - Refer to PM schedule details.							
Margret Villalobos									
129526					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:14 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
129527					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:15 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
129528					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:15 AM				
Ambriz, Juan		Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
129211					2/24/2015		22		\$0.00
Medium	Work In Progress				2/24/2015 8:48:29 AM				
Ambriz, Juan		Need to Install covers in all electrical outlets							
Juan Ambriz									
129612					3/1/2015	3/7/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:47:05 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa ES							
129496					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:56 AM				
Ambriz, Juan		Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.							
Margret Villalobos									
129275	Main Building	Library			2/25/2015		21		\$0.00
Medium	Work In Progress				2/25/2015 9:30:35 AM				
Ambriz, Juan		Need to Install blinds in Library in case of a lockdown							
Juan Ambriz									
129919					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:47 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
129267	Main Building	Classroom			2/25/2015		21		\$0.00
Medium	Work In Progress	Parent room -			2/25/2015 7:53:50 AM				
Ambriz, Juan		Need to move furniture from parent room to book room							
Juan Ambriz									
129662		Classroom			3/2/2015		16		\$0.00
Medium	Work In Progress	Room #103			3/2/2015 3:55:40 PM				
Ambriz, Juan		Need to mount smart board on wall							
Juan Ambriz									
129663	Main Building	Classroom			3/2/2015		16		\$0.00
Medium	Work In Progress	Room #205			3/2/2015 3:56:29 PM				
Ambriz, Juan		Need to mount smart board on wall							
Juan Ambriz									
129265	Main Building	Classroom			2/25/2015		21		\$0.00
Medium	Work In Progress	Room # 207			2/25/2015 7:50:57 AM				
Ambriz, Juan		Need to relocate smart board. Hang up on wall.							
Juan Ambriz									
128833	Main Building	Classroom			2/12/2015		34		\$0.00
Medium	Work In Progress	Room			2/12/2015 7:54:57 AM				
Ambriz, Juan		Need to replace toilet handle in room # 102 & 104							
Juan Ambriz									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa ES							
127761	Main Building	Classroom			1/21/2015		56		\$0.00
Medium	Work In Progress	Room #301			1/21/2015 12:44:54 PM				
Ambriz, Juan		Need to replace blinds in room #301							
Juan Ambriz									
127595	Main Building	Classroom			1/15/2015		62		\$0.00
Medium	Work In Progress	coaches office			1/15/2015 1:20:03 PM				
Ambriz, Juan		Need to hang up hooks for coaches							
Juan Ambriz									
129325	Main Building	Portables			2/26/2015		20		\$0.00
Medium	Work In Progress	Portable A-051			2/26/2015 7:49:42 AM				
Ambriz, Juan		Need to Install shelve							
Juan Ambriz									
128453	Main Building	Restroom			2/4/2015		42		\$0.00
Medium	Work In Progress				2/4/2015 9:23:39 AM				
Ambriz, Juan		As per Mrs. Tarin need to replace hand dryers in boys restroom in 300 hallway							
Juan Ambriz									
128454	Main Building	Restroom (Girls)			2/4/2015		42		\$0.00
Medium	Work In Progress				2/4/2015 9:25:22 AM				
Ambriz, Juan		Need to replace sink faucets in girls 300 hallway restroom							
Juan Ambriz									
128455	Main Building	Restroom (Girls)			2/4/2015		42		\$0.00
Medium	Work In Progress				2/4/2015 9:29:07 AM				
Ambriz, Juan		As per Mrs. Tarin Need to replace Hand dryers in girls 200 hallway							
Juan Ambriz									
128456	Main Building	Restroom (Girls)			2/4/2015		42		\$0.00
Medium	Work In Progress				2/4/2015 9:33:07 AM				
Ambriz, Juan		Need to replace faucet in girls 100 halllway							
Juan Ambriz									
128411	Main Building	Kitchen			2/3/2015		43		\$0.00
Medium	Work In Progress				2/3/2015 2:26:05 PM				
Ambriz, Juan		Need to replace pilot switch in kitchen							
Juan Ambriz									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

129276	Main Building	Office			2/25/2015		21		\$0.00
Medium	Work In Progress	Parent room			2/25/2015 9:41:19 AM				
Ambriz, Juan		Need to Install blinds in old Parent Room now book room office 101" x 90"							
Juan Ambriz									

129645	Main Building	Exterior			3/2/2015		16		\$0.00
Medium	Work In Progress				3/2/2015 3:11:04 PM				
Ambriz, Juan		Need to order fertilizer for back field							
Juan Ambriz									

127846	Main Building	Storage			1/23/2015		54		\$0.00
Medium	Work In Progress	new storage			1/23/2015 11:18:22 AM				
Gonzalez, Salvador		Need a new ramp on new storage							
Juan Ambriz									

127742	Main Building	Storage			1/21/2015		56		\$0.00
Medium	Work In Progress	New storage			1/21/2015 9:12:36 AM				
Gonzalez, Salvador		Need to install ramp in new storage building							
Juan Ambriz									

127847	Main Building	Exterior			1/23/2015		54		\$0.00
Medium	Work In Progress				1/23/2015 11:20:13 AM				
Gonzalez, Salvador		Need to remove steel posts behind kitchen due to new fence installed							
Juan Ambriz									

130265	Main Building	Hallway/Corridor			3/17/2015		1		\$0.00
Medium	Work In Progress	Hallway/nurse			3/17/2015 2:20:32 PM				
Lara, Ralph		As per Mrs. Tarin wants a door Installed on the main hallway wall entering the Nurse's office. Preferably made between May 22 to May 27.							
Juan Ambriz									

129115	Main Building				2/20/2015		26		\$0.00
Medium	Work In Progress	Haall way doors			2/20/2015 10:11:08 AM				
Lara, Ralph		Need to adjust all hallway doors							
Juan Ambriz									

129723	Main Building	Exterior			3/3/2015		15		\$0.00
Medium	Work In Progress	Pad locks			3/3/2015 3:05:22 PM				
Lara, Ralph		Need to clean all padlocks due to windy days							
Juan Ambriz									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
126164	Main Building	Office			12/3/2014		105		\$0.00
Medium	Work In Progress	Office		12/3/2014 10:02:39 AM					
Lara, Ralph		We need an additional master key so that when we have custodial substitutes and/or computer technician, office staff does not lend their key out. Thank you.							
Rita Mendez									
126167	Main Building	Office			12/3/2014		105		\$0.00
Medium	Work In Progress	Office		12/3/2014 10:25:37 AM					
Lara, Ralph		We need Fire Pull Station keys. The only key that we have is dented. Sort of an emergency. Thank you.							
Rita Mendez									
125020					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress			11/2/2014 12:36:29 AM					
Orozco, Daniel		Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
123325					9/26/2014		173		\$0.00
Medium	Work In Progress			9/26/2014 3:48:47 PM					
Orozco, Daniel		REFRIGERATOR SIDE OF STAND FAN BROKEN OFF. SNP MANAGER MARINA R. 589.3439							
Maritza Gonzalez									
126298					12/5/2014		103		\$0.00
Medium	Work In Progress			12/5/2014 3:32:07 PM					
Orozco, Daniel		ICE MAKER LEAKING. SNP MANAGER MARINA R. 589.3439							
Maritza Gonzalez									
124391					10/21/2014		148		\$0.00
Medium	Work In Progress			10/21/2014 10:54:28					
Orozco, Daniel		WALK IN ENTRANCE-FLOOR IS LIFTING. SNP MANAGER MARINA R. 589.3436							
Maritza Gonzalez									
130299					3/18/2015		0		\$0.00
Medium	Work In Progress			3/18/2015 8:48:47 AM					
Orozco, Daniel		DOOR STRIP ON WALK IN DOOR IS COMING OFF. SAFETY HAZARD. SNP MANAGER MARINA R. 589-3439.							
Maritza Gonzalez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
130300					3/18/2015		0		\$0.00
Medium	Work In Progress				3/18/2015 8:49:54 AM				
Orozco, Daniel		TEMPERATURE ON REACH IN REFRIGERATURE IS NOT WORKING PROPERLY, TOO COLD. SNP MANAGER MARINA R. 589-3439.							
Maritza Gonzalez									
130196					3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 2:41:20 PM				
Orozco, Daniel		As per fire inspection, exhaust fan not working.							
Maritza Gonzalez									
126905					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:37 AM				
Villalobos, David		Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
126573					12/12/2014		96		\$0.00
Medium	Work In Progress				12/12/2014 9:22:46 AM				
Castillo, Carlos		As per our conversation, please check for power for a Double Portable on the Eastside of campus.							
Margret Villalobos									
126757	Main Building	Classroom			12/18/2014		90		\$0.00
Medium	Work In Progress	parent room 300			12/18/2014 1:16:34 PM				
Castillo, Carlos		Need to Install electrical outlet for smart board							
Juan Ambriz									
Count: 43 Work Orders			Avg. Age of WO's 47		Total for Santa Teresa ES			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
126710	GYM (2009)	Gym			12/17/2014		91		\$0.00
Medium	Work In Progress	girls lockerroom			12/17/2014 12:21:52				
Castillo, Carlos		extra electrical outlets in locker needed for use							
Loraine Soriano									
130194	GYM (2009)	Athletic Field			3/16/2015		2		\$0.00
Medium	Work In Progress	baseball			3/16/2015 2:22:49 PM				
Castillo, Carlos		Check lights breaker may have been tripped							
Loraine Soriano									
129680	GYM (2009)	Athletic Field			3/3/2015		15		\$0.00
Medium	Work In Progress	Track			3/3/2015 8:17:05 AM				
Castillo, Carlos		Connectivity from score board to area for timing system and scoring cameras within the finish line.							
Loraine Soriano									
129390					2/27/2015		19		\$0.00
Medium	Work In Progress				2/27/2015 8:20:56 AM				
Castillo, Carlos		Baseball Field. The baseball field lights are not turning on. it was also reported that on Tuesday that it was raining there were sparks coming out from one of the light poles.							
Jaime Mijarez									
130084	Gymnasium				3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 10:13:39 AM				
Castillo, Carlos		Boys Dressing Room - Repair/replace 2 damaged 2x4 ceiling lights.							
Alfredo Holguin									
127839	Dressing Rooms	Dressing Room			1/23/2015		54		\$0.00
Medium	Work In Progress				1/23/2015 10:19:52 AM				
Castillo, Carlos		As per Coach Dots on, the basketball timers in dressing rooms are not working properly.							
Carlos Castillo									
127805		Office			1/22/2015		55		\$0.00
Medium	Work In Progress	OFFICE			1/22/2015 12:18:36 PM				
Castillo, Carlos		NEED AN ELECTRICAL OUTLET IN OFFICE STORAGE ROOM. WILL BE MOVING IN A REFRIGERATOR.							
Marylou Jimenez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
120024					7/30/2014		231		\$0.00
Medium	Work In Progress				7/30/2014 12:57:15 PM				
Castillo, Carlos		Grounds shop. Install electrical for new a/c installation.							
Jaime Mijarez									
126364					12/8/2014		100		\$0.00
Medium	Work In Progress				12/8/2014 1:35:42 PM				
Castillo, Carlos		several exterior elec. outlets need to be repaired due to broken weather covers as per NMPSIA standard report.							
David Escobar									
126510	Gymnasium	Gym			12/11/2014		97		\$0.00
Medium	Work In Progress	auxillary gym			12/11/2014 9:09:48 AM				
Holguin, Alfredo		Score board and control box not functioning properly missing buttons. Equipment old and in need of replacing.							
Loraine Soriano									
129432					2/28/2015	3/31/2015	18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:44 AM				
,		Yearly - Santa Teresa HS C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
129553					3/1/2015	4/1/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:30 AM				
,		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
129554					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:31 AM				
,		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
129555					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:31 AM				
,		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
130239		Office			3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 8:49:26 AM				
Gonzales, Camilo		Deliver 5 boxes. PO# 141505843.							
Theresa Ramirez									
122288	Main Building	Hallway/Corridor			9/4/2014		91		\$0.00
Medium	Work In Progress				9/4/2014 8:02:23 AM	12/4/2014			
Lucero, Arnold		Make sure all hallways are burnished 2 times a week. (Assign to Arnold Lucero)				10/17/14 - REMAILED TO ARNOLD			
Jesus Estrada									
127342					1/11/2015	1/27/2015	66		\$0.00
Medium	Work In Progress				1/11/2015 12:29:46 AM				
Lucero, Arnold		Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.							
Jesus Estrada									
130182					3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 8:54:04 AM				
Orozco, Daniel		I need to place a work order, The Environmental Health Department Came for inspection and he wants as soon as possible to fix a leak from the washer machine, also one of hand wash sink has a leak he wants the water with more heat. He will come back in two weeks to check if everything is fixed. Thank you!!! Olga							
Maritza Gonzalez									
127169					1/7/2015		70		\$0.00
Medium	Work In Progress				1/7/2015 9:00:42 AM				
Orozco, Daniel		DISHWASHER MAKING A LOUD NOISE. SNP MANAGER OLGA B. 589.5332							
Maritza Gonzalez									
126903					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:36 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
127042	Main Building	Office			1/5/2015		72		\$0.00
Medium	Work In Progress	Counseling		1/5/2015 10:46:12 AM					
Escobar, David		Lights in need of replacing							
Loraine Soriano									
119429	Cafeteria (2005)	Cafeteria			7/15/2014		246		\$0.00
Medium	Work In Progress			7/15/2014 11:10:21 AM					
Escobar, David		Several cracked, broken or missing tiles in serving line area and dining area around stage need to be replaced.							
Rosalinda Rodriguez									
126447	Main Building	Parking Lot			12/10/2014		98		\$0.00
Medium	Work In Progress	flag pole		12/10/2014 9:15:39 AM					
Escobar, David		Flag pole is not working the pulley is broken							
Loraine Soriano									
120185	Main Building	Classroom			8/1/2014		229		\$0.00
Medium	Work In Progress	main building		8/1/2014 12:28:03 PM					
Escobar, David		Several classrooms leaking. Please see me for map to determine locations							
Loraine Soriano									
124118	Main Building	Classroom			10/14/2014		155		\$0.00
Medium	Work In Progress	312		10/14/2014 8:19:40 AM					
Escobar, David		Need a pencil sharpner installed							
Loraine Soriano									
122320	Main Building	Exterior			9/4/2014		195		\$0.00
Medium	Work In Progress	Admin/handicap		9/4/2014 11:39:20 AM					
Ontiveros, Guadalupe		If concrete curbs can be placed in parking to keep cars from obstructing access to sidewalks for wheelchairs							
Loraine Soriano									
119578		Athletic Field			7/18/2014		243		\$0.00
High	Work In Progress			7/18/2014 12:51:51 PM					
Ontiveros, Guadalupe		need to line locate along pinetrees.anysewer line and gas lines. any? rick will assit							
Guadalupe Ontiveros									
119584		Athletic Field			7/18/2014		243		\$0.00
Medium	Work In Progress			7/18/2014 1:44:53 PM					
Ontiveros, Guadalupe		JD tractor 3005 clutch needs to be replaced.							
Guadalupe Ontiveros									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
129003	GYM (2009)	Athletic Field			2/18/2015		28		\$0.00
Medium	Work In Progress	track			2/18/2015 8:07:01 AM				
Ontiveros, Guadalupe Check long jump area and clean track area									
Loraine Soriano									
128389	GYM (2009)	Athletic Field			2/3/2015		43		\$0.00
Medium	Work In Progress	Tennis Courts			2/3/2015 9:34:51 AM				
Ontiveros, Guadalupe Tennis courts cement is cracked, along playing surface.									
Loraine Soriano									
120628		Athletic Field			8/6/2014		224		\$0.00
Medium	Work In Progress	Shot put			8/6/2014 9:28:16 AM				
Ontiveros, Guadalupe Fence surrounding shot put as none is there. Crucial for athlete safety. Please see Ms. Soriano or Ms. Noughes.									
Loraine Soriano									
128091					1/29/2015		48		\$0.00
Medium	Work In Progress				1/29/2015 10:25:58 AM				
Orozco, Daniel The technician from Ecolab came and checked dishwasher, He stated that the wash tank Gauge needs to be replaced is not working at all. SNP Manager Olga B. 589.5332									
Maritza Gonzalez									
124298	Main Building	Classroom			10/17/2014		152		\$0.00
Medium	Work In Progress	215			10/17/2014 12:24:15				
Lara, Ralph Bathroom door and front classroom door do not stay open									
Loraine Soriano									
127117	Main Building	Classroom			1/6/2015		71		\$0.00
Medium	Work In Progress	215			1/6/2015 2:13:42 PM				
Lara, Ralph keys for patio area in room 215									
Loraine Soriano									
126446	Annex Building	Classroom			12/10/2014		98		\$0.00
Medium	Work In Progress	705			12/10/2014 9:14:03 AM				
Lara, Ralph Main door from outside, door handle is broken and makes it very difficult to lock and unlock door. Door falling off hinges									
Loraine Soriano									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
130121	Main Building	Classroom			3/13/2015		5		\$0.00
Medium	Work In Progress	215			3/13/2015 8:19:03 AM				
Lara, Ralph		Need key for patio outside room 215							
Loraine Soriano									
130122	Main Building	Classroom			3/13/2015		5		\$0.00
Medium	Work In Progress	computer lab C4			3/13/2015 8:20:14 AM				
Lara, Ralph		lock in C4 not working							
Loraine Soriano									
130124	Main Building	Classroom			3/13/2015		5		\$0.00
Medium	Work In Progress	teachers lounge			3/13/2015 8:54:59 AM				
Lara, Ralph		door handle lock not working							
Loraine Soriano									
130125	Main Building	Classroom			3/13/2015		5		\$0.00
Medium	Work In Progress	311			3/13/2015 8:56:28 AM				
Lara, Ralph		Keysticks and handle difficult to open							
Loraine Soriano									
129161	Vocational	Classroom			2/23/2015		23		\$0.00
Medium	Work In Progress	805			2/23/2015 12:20:03 PM				
Lara, Ralph		Needs keys for flammable cabinets							
Loraine Soriano									
121481		Storage			8/19/2014		211		\$0.00
Medium	Work In Progress	band truck			8/19/2014 3:59:40 PM				
Flores, Pete		Band truck needs to be fixed for use of equipment							
Loraine Soriano									
125606					11/15/2014		123		\$0.00
Medium	Work In Progress				11/15/2014 12:45:35				
Flores, Pete		Yearly - Santa Teresa HS - Mower 0425 - Grounds - Refer to PM schedule details.							
Margret Villalobos									
129005	Locker Room	Football Field			2/18/2015		28		\$0.00
Medium	Work In Progress	football locker			2/18/2015 8:10:50 AM				
Lara, Ralph		second request football locker room door is not locking appropriately							
Loraine Soriano									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
123302					9/26/2014		173		\$0.00
Medium	Work In Progress				9/26/2014 1:59:51 PM				
Lara, Ralph		doors to dock entrance at daycare will not open and need repair.							
David Escobar									
128908	Main Building	Classroom			2/13/2015		33		\$0.00
Medium	Work In Progress	405			2/13/2015 3:14:41 PM				
Lara, Ralph		Door is falling off hinges as well as the ability to lock to the door							
Loraine Soriano									
128817	Main Building	Classroom			2/11/2015		35		\$0.00
Medium	Work In Progress	704			2/11/2015 4:03:59 PM				
Lara, Ralph		key for room 704							
Loraine Soriano									
128909	Main Building	Library			2/13/2015		33		\$0.00
Medium	Work In Progress	library lobby			2/13/2015 3:17:40 PM				
Lara, Ralph		locks for displaycase							
Loraine Soriano									
124291	Main Building	Auditorium			10/17/2014		152		\$0.00
Medium	Work In Progress	Basketball			10/17/2014 11:31:42				
Lara, Ralph		Door is falling off hinges							
Loraine Soriano									
128914	GYM (2009)	Gym			2/13/2015		33		\$0.00
Medium	Work In Progress	Varsity gym			2/13/2015 3:26:46 PM				
Lara, Ralph		Entry doors to locker room from lobby area the door missing a screw							
Loraine Soriano									
129734	AnnexBuilding	Classroom			3/3/2015		15		\$0.00
Medium	Work In Progress	classroom			3/3/2015 3:39:32 PM				
Lara, Ralph		locker does not lock							
Loraine Soriano									
129731	AnnexBuilding	Classroom			3/3/2015		15		\$0.00
Medium	Work In Progress	culinary			3/3/2015 3:37:58 PM				
Lara, Ralph		Doors do not lock and front door has problems opening							
Loraine Soriano									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
128818	Main Building	Hallway/Corridor			2/11/2015		35		\$0.00
Medium	Work In Progress	mailbox 123			2/11/2015 4:05:28 PM				
Lara, Ralph		lock not functioning with key							
Loraine Soriano									
129834					3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 3:13:12 PM				
Lara, Ralph		Nursing Portable on La Clinica De Familia Side- rekey exterior door and doors leading to school nurse side like the school nurse side.							
Alfredo Holguin									
129633					3/2/2015		16		\$0.00
Medium	Work In Progress				3/2/2015 12:56:18 PM				
Lara, Ralph		Cafeteria. Three exit door hydraulic closers are not working and are leaking fluid causing doors to slam. They need to be replaced.							
Jaime Mijarez									
129639		Athletic Field			3/2/2015		16		\$0.00
Medium	Work In Progress				3/2/2015 2:28:47 PM				
Flores, Pete		kubota RTV 400 needs to be service S.T.H.S and G.H.S							
Guadalupe Ontiveros									
122642	Main Building	Classroom			9/11/2014		188		\$0.00
Medium	Work In Progress				9/11/2014 11:25:53 AM				
Flores, Pete		Need warehouse pick up golf cart from Santa Teresa High School, need to check the bolt joint on cart and tires.							
Irene Herrera									
129509					3/1/2015	3/17/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:04 AM				
Villalobos, Margret		Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.				3/2 - Emailed			
Margret Villalobos									
130086		Parking Lot			3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 10:19:14 AM				
Gonzalez, Salvador		Main Entrance to parking area- Need to replace two large roll gates with swing gates - 4 each							
Alfredo Holguin									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
127645	Main Building	Parking Lot			1/16/2015		61		\$0.00
Medium	Work In Progress	student parking			1/16/2015 11:30:59 AM				
Gonzalez, Salvador Traffic control for after and before school see Rick for further assistance. There has been parental concerns with this issue and we need address the problem.									
Loraine Soriano									
127644	Main Building	Athletic Field			1/16/2015		61		\$0.00
Medium	Work In Progress	Softball			1/16/2015 11:27:24 AM				
Gonzalez, Salvador Batting cage for softball field please see Ms Contreras and Rick for futher guidance									
Loraine Soriano									
124074					10/13/2014		156		\$0.00
Medium	Work In Progress				10/13/2014 1:10:14 PM				
Gonzalez, Salvador need a tamper cage for a window unit to be installed in ticket both . See BM2 for specs.									
David Escobar									
128386		Athletic Field			2/3/2015		43		\$0.00
Medium	Work In Progress	Softball			2/3/2015 9:30:39 AM				
Ronquillo, Ruben Season started 02/02/2015. Please order nets for softball cages once they're complete. Please get measurements from Sal Gonzalez									
Loraine Soriano									
127419					1/12/2015		65		\$0.00
Medium	Work In Progress				1/12/2015 3:25:10 PM				
Gonzalez, Salvador the wire mesh to some goose neck has fallen off need to be replace with some expandable metal or new wire mesh need two at 37x38									
Daniel Sotelo									
128387	GYM (2009)	Athletic Field			2/3/2015		43		\$0.00
Medium	Work In Progress	Track area			2/3/2015 9:31:46 AM				
Llanez, Rick Shot putt area and discuss area several request since last semester. Season has started and no progress has been made.									
Loraine Soriano									
128388	Gymnasium	Athletic Field			2/3/2015		43		\$0.00
Medium	Work In Progress	baseball field			2/3/2015 9:33:05 AM				
Llanez, Rick Baseball field several request for wind screen, season has started and no progress has been made									
Loraine Soriano									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
124797	Main Building	Athletic Field			10/30/2014		139		\$0.00
Medium	Work In Progress	softball			10/30/2014 3:55:12 PM				
Llanez, Rick		Bullpen in need of work on visitors side.							
Loraine Soriano									
124799	Main Building	Athletic Field			10/30/2014		139		\$0.00
Medium	Work In Progress	softball			10/30/2014 3:57:02 PM				
Llanez, Rick		Windscreen missing to complete the field. Not complete in the outfield.							
Loraine Soriano									
120625		Athletic Field			8/6/2014		224		\$0.00
Medium	Work In Progress	Football field			8/6/2014 9:23:08 AM				
Llanez, Rick		Turf field in dire need of brushing and maintenance. Pellets needed and field needs to be maintained twice a month. Schedule dates are needed for proper care and equipment needed to brush field as well as pellets. It is crucial as season begins in two weeks.							
Loraine Soriano									
126284					12/5/2014		103		\$0.00
Medium	Work In Progress				12/5/2014 11:00:49 AM				
Llanez, Rick		Clean sand around track.							
Michael Munoz									
123989					10/10/2014		159		\$0.00
Medium	Work In Progress				10/10/2014 11:00:23				
Llanez, Rick		Please fix hole in sidewalk at the end of Science Wing. Please see e-mail for pictures of area. Should you have any questions please contact Mr. Ralph Gallegos at 575 - 882-6921 in the Construction office. Thank You							
Dominique Esparza									
121492	Main Building	Exterior			8/20/2014		210		\$0.00
Medium	Work In Progress	sidewalk			8/20/2014 8:59:58 AM				
Llanez, Rick		Sidewalk toward arroyo has hallow areas where water has taken sand out from under it.							
Loraine Soriano									
129493					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:54 AM				
Sanchez, Raul		Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PMSchedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
128385					2/3/2015		43		\$0.00
Medium	Work In Progress				2/3/2015 8:58:48 AM				
Ronquillo, Ruben		Need to purchase nets for BB Batting Cages (4) 24L x 10H x 10W							
Alfredo Holguin									
128821	Cafeteria (2005)	Exterior			2/11/2015		35		\$0.00
Medium	Work In Progress	sidewalk			2/11/2015 4:25:36 PM				
Ronquillo, Ruben		Demo and upgrade sidewalk to create new entry way, also add landscaping to entrance area. Please see Mr. W. for further direction as well as Mr. Ruben Ronquillo							
Loraine Soriano									
128822	Main Building	Exterior			2/11/2015		35		\$0.00
Medium	Work In Progress	annex/library			2/11/2015 4:26:48 PM				
Ronquillo, Ruben		Various signage upgrades please see Mr. W or Mr. Ronquillo for further direction							
Loraine Soriano									
128823	Main Building	Exterior			2/11/2015		35		\$0.00
Medium	Work In Progress	outside front			2/11/2015 4:29:15 PM				
Ronquillo, Ruben		Small visitors signs to attached to present handicap signs, aluminum signage above culinary arts and NJROTC classroom. Install sign posts in faculty parking lot for administration for further direction please see Mr. W or Mr. Ronquillo							
Loraine Soriano									
125544					11/13/2014		125		\$0.00
Medium	Work In Progress				11/13/2014 4:25:33 PM				
Ontiveros, Joe		Room 511 Order and access panel under sink to provide access to gas shut off.							
Alfredo Holguin									
125615					11/17/2014		121		\$0.00
Medium	Work In Progress				11/17/2014 9:25:00 AM				
Ontiveros, Joe		Science Room 515 - Repair water and gas lines to lab tables - install new signs on Gas Shut Off Valve locations							
Alfredo Holguin									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
125620					11/17/2014		121		\$0.00
Medium	Work In Progress			11/17/2014 9:37:18 AM					
Ontiveros, Joe	Science Room 508 - Repair gas and water lines to lab tables and install new signs at locations of Gas Shut Off Valve.								
Alfredo Holguin									
130155	GYM (2009)	Roof			3/13/2015		5		\$0.00
Medium	Work In Progress			3/13/2015 3:48:27 PM					
Ontiveros, Joe	Need to Repipe 3/4 main broken on Roof top gym do to freezing temperture and 6 commercial A/C units.								
Joe Ontiveros									
128133	Main Building	Hallway/Corridor			1/30/2015		47		\$0.00
Medium	Work In Progress	in back of 200		1/30/2015 9:23:22 AM					
Estrada, Jesus	tile damaged in front of 200 and 300 wing in front of exiting. Please see Jaime for assistance								
Loraine Soriano									
130097					3/12/2015		6		\$0.00
Medium	Work In Progress			3/12/2015 3:09:43 PM					
Ontiveros, Joe	home ec. grease trap was clogged and over flowing from clean out.								
Jaime Mijarez									
126974					1/4/2015	1/25/2015	73		\$0.00
Medium	Work In Progress			1/4/2015 12:41:34 AM					
Munoz, Michael	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
124792	Main Building	Athletic Field			10/30/2014		139		\$0.00
Medium	Work In Progress	football field		10/30/2014 3:49:56 PM					
Munoz, Michael	Football/soccer score board due to malfunction to box. Scoreboard is about 21 years old.								
Loraine Soriano									
126771	Main Building	Classroom			12/18/2014		90		\$0.00
Medium	Work In Progress	outside behind		12/18/2014 3:30:35 PM					
Munoz, Michael	tire ramps to have access to class room for grocery drop off								
Loraine Soriano									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
120999					8/12/2014		218		\$0.00
Medium	Work In Progress				8/12/2014 9:29:38 AM				
Ontiveros, Guadalupe		Sidewalk attached to black cinder block wall and going to arroyo has a lot of erosion from Sundays rain storm and can collapse into arroyo with another heavy rain. and was reported by Security Juan Tellez. Side walk is heavily used by the students and needs immediate attention.							
Jaime Mijarez									
121003					8/12/2014		218		\$0.00
Medium	Work In Progress				8/12/2014 9:38:36 AM				
Ontiveros, Guadalupe		Sidewalk behind the 500 wing exit to the football field has a lot of erosion from Sundays rain storm and can collapse. Right now it is unsafe, I will have to barricade to keep students off this area. need immediate attention. Attention Lupe for this work order and work order # 120999.							
Jaime Mijarez									
128114	Main Building	Classroom			1/29/2015		48		\$0.00
Medium	Work In Progress	601			1/29/2015 3:51:50 PM				
Ambriz, Jose		Heater not working							
Loraine Soriano									
127812	Main Building	Computer Lab			1/22/2015		55		\$0.00
Medium	Work In Progress	C-4			1/22/2015 2:59:03 PM				
Estrada, Jesus		TILE NEEDS REPLACEMENT							
Loraine Soriano									
129717		Cafeteria			3/3/2015		15		\$0.00
Medium	Work In Progress				3/3/2015 1:43:50 PM				
Carbajal, Jimmy		floor cleaning machine battery is not holding power please need a replacement asap.							
Arnold Lucero									
130130	Cafeteria (2005)	Custodial			3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 11:08:58 AM				
Carbajal, Jimmy		repair two wet drys vacuum machines							
Arnold Lucero									
129836					3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 3:16:09 PM				
Estrada, Jesus		Nursing Portable - replace carpet with VCT or Linoleum with welded seams.							
Alfredo Holguin									
3/18/2015 12:54:26 PM									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
124173	AnnexBuilding	Classroom			10/15/2014		154		\$0.00
Medium	Work In Progress	culinary			10/15/2014 9:51:56 AM				
Ontiveros, Joe		Dryer not working							
Loraine Soriano									
120184	Main Building	Classroom			8/1/2014		229		\$0.00
Medium	Work In Progress	610			8/1/2014 12:26:38 PM				
Ontiveros, Joe		Install new range in room 610							
Loraine Soriano									
123303	Main Building	Classroom			9/26/2014		173		\$0.00
Medium	Work In Progress	215			9/26/2014 2:16:35 PM				
Ontiveros, Joe		Toilet malfunctioning							
Loraine Soriano									
125545		Classroom			11/13/2014		125		\$0.00
Medium	Work In Progress				11/13/2014 4:29:17 PM				
Ontiveros, Joe		Science Room 511- Install new signs on Gas shut off access panels 2) to read "gas Shut Off Valve"							
Alfredo Holguin									
127480	Main Building	Classroom			1/13/2015		64		\$0.00
Medium	Work In Progress	215			1/13/2015 2:26:17 PM				
Ontiveros, Joe		Student shower needs a knob.							
Loraine Soriano									
125409	AnnexBuilding	Classroom			11/10/2014		128		\$0.00
Medium	Work In Progress	culinary			11/10/2014 4:25:12 PM				
Ontiveros, Joe		Dryer has not been hooked							
Loraine Soriano									
127270	Vocational	Classroom			1/8/2015		69		\$0.00
Medium	Work In Progress	801			1/8/2015 3:55:21 PM				
Ontiveros, Joe		Water leak, replace valves in water stations please see Jaime							
Loraine Soriano									
128577	Main Building	Classroom			2/6/2015		40		\$0.00
Medium	Work In Progress	215			2/6/2015 9:54:47 AM				
Ontiveros, Joe		Kitchen sink is leaking							
Loraine Soriano									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
129516					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:08 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
129506					3/1/2015	3/4/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:03 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.							
Margret Villalobos									
129466					3/1/2015	4/1/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:38 AM				
Mijarez, Jaime		Yearly - Santa Teresa HS A-10 HP Yearly - Refer to PM schedule details.							
Margret Villalobos									
129611					3/1/2015	3/7/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:47:04 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
129069					2/19/2015		27		\$0.00
Medium	Work In Progress				2/19/2015 10:32:22 AM				
Mijarez, Jaime		Chiller Alarm - 6:37 PM February 18, 2015 Starter Did Not Transition Cprsr 2A. Chiller serviced by David on 2/18/2015.							
Jaime Mijarez									
121254	Cafeteria (2005)				8/15/2014		215		\$0.00
Medium	Work In Progress				8/15/2014 10:49:31 AM				
Mijarez, Jaime		mens restroom in cafeteria urinal not enough water pressure							
Isaac Holguin									
124222					10/16/2014		153		\$0.00
Medium	Work In Progress				10/16/2014 7:56:45 AM				
Mijarez, Jaime		Room 400. No cooling in the after noon reported by teacher. The a/c motor gave out. I will need a new 3/4 hp motor with pully and clamps to replace.							
Jaime Mijarez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
123220	Main Building	Library			9/25/2014		174		\$0.00
Medium	Work In Progress	library			9/25/2014 8:26:27 AM				
Mijarez, Jaime		Air conditioning in office needs to be looked at as it is not working							
Loraine Soriano									
119430	Concession	Athletic Field			7/15/2014		246		\$0.00
Medium	Work In Progress				7/15/2014 11:48:16 AM				
Mijarez, Jaime		Holes in concession building near water fountain have exposed copper tubing							
Rosalinda Rodriguez									
126451	Gymnasium	Auditorium			12/10/2014		98		\$0.00
Medium	Work In Progress	Varsity gym			12/10/2014 9:23:31 AM				
Mijarez, Jaime		Locker room water fountain clogged							
Loraine Soriano									
121267	Main Building	Classroom			8/15/2014		215		\$0.00
Medium	Work In Progress	608			8/15/2014 2:08:18 PM				
Mijarez, Jaime		Anchor cabinets							
Loraine Soriano									
121272	Main Building	Classroom			8/15/2014		215		\$0.00
Medium	Work In Progress	206			8/15/2014 2:15:43 PM				
Mijarez, Jaime		Remove old white board and old screen							
Loraine Soriano									
122803	Cafeteria (2005)	Auditorium			9/15/2014		184		\$0.00
Medium	Work In Progress	Theater area			9/15/2014 4:14:10 PM				
Mijarez, Jaime		Workshop lights, restroom not working							
Loraine Soriano									
129113	Gymnasium	Athletic Field			2/20/2015		26		\$0.00
Medium	Work In Progress	entrance soccer			2/20/2015 10:00:30 AM				
Mijarez, Jaime		Install signs stating employees only so parents and students do not enter from those areas							
Loraine Soriano									
126748	Main Building	Parking Lot			12/18/2014		90		\$0.00
Medium	Work In Progress	parking lot			12/18/2014 9:41:16 AM				
Mijarez, Jaime		Painting parking barriers to prevent accidents							
Loraine Soriano									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
130283	Cafeteria (2005)	Parking Lot			3/17/2015		1		\$0.00
Medium	Work In Progress	gate next to			3/17/2015 3:45:27 PM				
Mijarez, Jaime		Gate next to cafeteria needs to be looked at very difficult to open and close.							
Loraine Soriano									
129022	Main Building	Parking Lot			2/18/2015		28		\$0.00
Medium	Work In Progress	parking lot			2/18/2015 10:12:27 AM				
Mijarez, Jaime		Painting of directionality symbols on parking lot to make traffic flow better							
Loraine Soriano									
128400	Main Building	Parking Lot			2/3/2015		43		\$0.00
Medium	Work In Progress	Parking Lot			2/3/2015 11:04:36 AM				
Mijarez, Jaime		Work order placed last year for painting of parking lot for arrows etc., for better flow of traffic.							
Loraine Soriano									
130083	Gymnasium				3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 10:12:11 AM				
Mijarez, Jaime		Boys Dressing Room- Holes in ceiling (3 each) patch with drywall and tape texture and paint or order access doors and install							
Alfredo Holguin									
128886	Main Building	Classroom			2/12/2015		34		\$0.00
Medium	Work In Progress	610			2/12/2015 4:01:11 PM				
Mijarez, Jaime		Second request install mirror for demo table, please see ms lusk for further direction							
Loraine Soriano									
128671	Main Building	Classroom			2/9/2015		37		\$0.00
Medium	Work In Progress	610			2/9/2015 12:19:12 PM				
Mijarez, Jaime		Overhead mirror to demo table not working, please see Ms. Lusk for further clarification.							
Loraine Soriano									
129735	Annex Building	Classroom			3/3/2015		15		\$0.00
Medium	Work In Progress	culinary			3/3/2015 3:40:30 PM				
Mijarez, Jaime		Shelves needs holder							
Loraine Soriano									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
129736	AnnexBuilding	Classroom			3/3/2015		15		\$0.00
Medium	Work In Progress	culinary			3/3/2015 3:41:20 PM				
Mijarez, Jaime		coat rack needs hanging							
Loraine Soriano									
130192	Main Building	Classroom			3/16/2015		2		\$0.00
Medium	Work In Progress	610			3/16/2015 1:47:04 PM				
Mijarez, Jaime		Need a spice rack hung on wall							
Loraine Soriano									
129733	AnnexBuilding	Classroom			3/3/2015		15		\$0.00
Medium	Work In Progress	culinary			3/3/2015 3:38:40 PM				
Mijarez, Jaime		Racks and picture frames need hanging							
Loraine Soriano									
124455	Main Building	Classroom			10/22/2014		147		\$0.00
Medium	Work In Progress	314			10/22/2014 12:30:35				
Mijarez, Jaime		Map strips need center screws, Please refer to Ms. Thornly for further clarification							
Loraine Soriano									
120179	Main Building	Classroom			8/1/2014		229		\$0.00
Medium	Work In Progress	505			8/1/2014 11:56:03 AM				
Mijarez, Jaime		Replace pencil sharpner							
Loraine Soriano									
124299	AnnexBuilding	Classroom			10/17/2014		152		\$0.00
Medium	Work In Progress	culinaryarts			10/17/2014 12:25:41				
Mijarez, Jaime		Lockers need to be moved to classroom as well as mounted if possible. Please see Ms. Perez for clarification.							
Loraine Soriano									
124301	Main Building	Classroom			10/17/2014		152		\$0.00
Medium	Work In Progress	209			10/17/2014 2:45:48 PM				
Mijarez, Jaime		Needs a safetygoggle sanitation cabinet installed in classroom. There might be a possibility that an outlet maybe required for this cabinet. Please see Mrs. Nunez for further information and placement of cabinet.							
Loraine Soriano									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS									
127813	Main Building	Classroom			1/22/2015		55		\$0.00
Medium	Work In Progress	211			1/22/2015 2:59:55 PM				
Mijarez, Jaime		Air conditioner does not turn off							
Loraine Soriano									
128512	Main Building	Classroom			2/5/2015		41		\$0.00
Medium	Work In Progress	608			2/5/2015 9:43:04 AM				
Mijarez, Jaime		Heater blowing cold air							
Loraine Soriano									
123084	Main Building	Classroom			9/23/2014		176		\$0.00
Medium	Work In Progress	Lab C-1			9/23/2014 3:16:04 PM				
Mijarez, Jaime		Cabinet door in computer lab office in broken.							
Loraine Soriano									
126449	Vocational	Classroom			12/10/2014		98		\$0.00
Medium	Work In Progress	807			12/10/2014 9:20:47 AM				
Mijarez, Jaime		paper towel dispenser							
Loraine Soriano									
126450	Vocational	Classroom			12/10/2014		98		\$0.00
Medium	Work In Progress	807			12/10/2014 9:21:54 AM				
Mijarez, Jaime		paper towel dispenser near sink area							
Loraine Soriano									
128380	GYM (2009)	Football Field			2/3/2015		43		\$0.00
Medium	Work In Progress	outside football			2/3/2015 8:16:52 AM				
Mijarez, Jaime		Wall on the outside of football field house needs to be painted the same as the other buildings. Also wall along football field needs painting.							
Loraine Soriano									
120624	Gymnasium	Restroom			8/6/2014		224		\$0.00
Medium	Work In Progress	soccer locker			8/6/2014 9:19:21 AM				
Mijarez, Jaime		Missing toilet seat in one of the stalls							
Loraine Soriano									
128511	Locker Room	Restroom (Girls)			2/5/2015		41		\$0.00
Medium	Work In Progress	girls locker room			2/5/2015 9:41:59 AM				
Mijarez, Jaime		Water spilling over in sink							
Loraine Soriano									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
129948	Main Building	Office			3/9/2015		9		\$0.00
Medium	Work In Progress	Attendance			3/9/2015 2:13:27 PM				
Mijarez, Jaime		If you could please fix the plastic mold on the floor by the fire extinguisher in the attendance office?							
Loraine Soriano									
129012	Main Building	Classroom			2/18/2015		28		\$0.00
Medium	Work In Progress	215			2/18/2015 8:44:09 AM				
Mijarez, Jaime		Mice in classroom							
Loraine Soriano									
124096	Main Building	Office			10/13/2014		156		\$0.00
Medium	Work In Progress	Training room			10/13/2014 3:46:12 PM				
Mijarez, Jaime		Mr. Munoz needs assistance with some hooks please see mr. Munoz for further clarification							
Loraine Soriano									
128820	GYM (2009)	Exterior			2/11/2015		35		\$0.00
Medium	Work In Progress	wall outside			2/11/2015 4:23:11 PM				
Mijarez, Jaime		wall in the exterior of football locker room in need of painting. Please try to match new gym exterior							
Loraine Soriano									
Count: 141 Work Orders		Avg. Age of WO's 84		Total for Santa Teresa HS		0		\$0.00	

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

130228	North Building	Kitchen			3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 8:03:34 AM				
Ontiveros, Joe		Replace water faucet in principles kitchen.							
Ismael Rodriguez									

127311	Gym (1997)	Mechanical			1/9/2015		68		\$0.00
Medium	Work In Progress				1/9/2015 3:15:27 PM				
Ontiveros, Joe		1/9/15. WE NEED TO REPLACE WATER HEATER ON GYM, IS BROCK (96GALL).							
Manuel Prospero									

130226	North Building	Restroom (Girls)			3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 7:52:46 AM				
Ontiveros, Joe		Replace North and South Building girls restroom water faucets with new ones their in bad shape.							
Ismael Rodriguez									

123993	North Building	Classroom			10/10/2014		159		\$0.00
Medium	Work In Progress				10/10/2014 11:16:43				
Ontiveros, Joe		Need to replace p-trap in RM #12							
Ismael Rodriguez									

130191	North Building	Custodial			3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 12:29:32 PM				
Carbajal, Jimmy		Need 2 vaccum bags.							
Ismael Rodriguez									

129811	North Building	Custodial			3/5/2015		13		\$0.00
Medium	Work In Progress				3/5/2015 9:06:59 AM				
Carbajal, Jimmy		Vaccum #018 needs service..							
Ismael Rodriguez									

124639	South Building	Mechanical			10/27/2014		142		\$0.00
Medium	Work In Progress				10/27/2014 3:30:16 PM				
Ambriz, Jose		10/27/14. A/C MECANICAL ROOM SOUH BUILDING IS NOT WORKING.							
Manuel Prospero									

130091		Parking Lot			3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 12:42:30 PM				
Prospero, Manuel		3/12/15. WE NEED TO REPAINTING ALL PARKING LINES (NORTH PARKING AND SOUTH PARKING).							
Manuel Prospero									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
130076	Gym (1997)	Gym			3/12/2015		6		\$0.00
Medium	Work In Progress	MS SNYDER			3/12/2015 8:37:03 AM				
Prospero, Manuel	REPAIR POST ON THE NORTH BASKETBALL COURTS FOR A TENNIS NET. PAINT LINES ON THE COURTS OUTSIDE								
Laura Parra									
122262	South Building	Classroom			9/3/2014		196		\$0.00
Medium	Work In Progress	55-WOLLARD			9/3/2014 3:35:43 PM				
Prospero, Manuel	AIR CONDITIONER IS EXTREMELY LOUD AND TILES ARE GETTING WET								
Laura Parra									
126039	North Building	Kitchen			12/1/2014		107		\$0.00
High	Work In Progress				12/1/2014 11:12:42 AM				
Prospero, Manuel	Please remove toilet so floor can be tiled. Rodriguez upholsterys should be there on December 2, 2014 at around 2:00 pm.								
Jesus Estrada									
129286	North Building	Office			2/25/2015		21		\$0.00
Medium	Work In Progress	BONNIE			2/25/2015 12:45:02 PM				
Prospero, Manuel	1. REPLACE CEILING TILE IN NORTH OFFICE 2. PAINT FRAMES ON DOORS AND MAIN DOORS								
Laura Parra									
129170	North Building	Classroom			2/23/2015		23		\$0.00
Medium	Work In Progress	3-PORTILLLO			2/23/2015 2:24:50 PM				
Prospero, Manuel	WALL NEEDS REPAINTING AFTER THE REPAIRS MADE FROM CONSTRUCTION CREW THAT INSTALLED THE STAIRS								
Laura Parra									
120786	South Building	Hallway/Corridor			8/8/2014		222		\$0.00
Medium	Work In Progress	UPSTAIRS			8/8/2014 8:31:33 AM				
Prospero, Manuel	PLEASE REMOVE LOCKERS AND INSTALL IN P.E (SEE MS SNYDER)								
Laura Parra									
122257	South Building	Hallway/Corridor			9/3/2014		196		\$0.00
Medium	Work In Progress	HALL WAY			9/3/2014 3:33:19 PM				
Prospero, Manuel	REMOVE LOCKERS FROM WALL OUTSIDE ROOM 44-45. SECOND REQUEST								
Laura Parra									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
124584	South Building	Hallway/Corridor			10/24/2014		145		\$0.00
Medium	Work In Progress	#44-ALLEN			10/24/2014 2:56:08 PM				
Prospero, Manuel		REMOVE LOCKERS. STUDENTS ARE PUTTING TRASH IN THEM							
Laura Parra									
129166	North Building	Classroom			2/23/2015		23		\$0.00
Medium	Work In Progress				2/23/2015 1:17:15 PM				
Prospero, Manuel		2/23/15. WE NEED TO CHANGED 3 ELECTRIC MOTORS ON ROOM 3. 1 EXHAUST FAN MOTOT ON KITCHEN MODEL NUM 76.000-G 120 VOLTS60 HZ3 AMPSCFMHQR 200 SONES 6.0RANGE HOOO 39A. CLEAN FAN FILTER AND GREASE. AND 2 MORE FOR RESTROOM AND CLOUSET. MODEL NUM SP-117 SERIAL NUM 93F09530 115 VOLTS							
Manuel Prospero									
126528	North Building	Classroom			12/11/2014		97		\$0.00
Medium	Work In Progress	3-PORTILLO			12/11/2014 12:45:36				
Prospero, Manuel		1- EXHAUST FAN IN THE BATHROOM IS NOT WORKING PROPERLY. 2- EXHAUST FAN OVER THE STOVE IS NOT WORKING							
Laura Parra									
123945	North Building	Classroom			10/9/2014		160		\$0.00
Medium	Work In Progress	12-CRAVENS			10/9/2014 3:13:19 PM				
Prospero, Manuel		1- SINK PIPE IS LEAKING- RIGHT SINK 2- BRACKS NEED TO BE REMOVED WITH SCREWS FROM BACK WALL							
Laura Parra									
125158	South Building	Classroom			11/5/2014		133		\$0.00
Medium	Work In Progress	47-			11/5/2014 8:33:40 AM				
Prospero, Manuel		AIR CONDITIONER MAKING LOUD NOISES							
Laura Parra									
124448	North Building	Classroom			10/22/2014		147		\$0.00
Medium	Work In Progress	6-BAILEY			10/22/2014 10:51:27				
Prospero, Manuel		CEILING LEAKING.							
Laura Parra									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Santa Teresa MS									
129474					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:43 AM				
Prospero, Manuel		Yearly - Santa Teresa MS A10 (Heat Pump)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
128140					1/30/2015		47		\$0.00
Medium	Work In Progress				1/30/2015 10:43:09 AM				
Prospero, Manuel		Both Bldgs Girls Restrooms - Please clean up or paint over graffiti.							
Richard Chavez									
129614					3/1/2015	3/7/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:47:06 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
129560					3/1/2015	4/1/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:34 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
129561					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:35 AM				
Prospero, Manuel		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
129562					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:35 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
129563					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:36 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									
Location: Santa Teresa MS									
125794					11/20/2014		118		\$0.00
Medium	Work In Progress			11/20/2014 10:59:18					
Prospero, Manuel Issued new Trane Laptop to Manuel Prospero.									
Margret Villalobos									
130093	Gym (1997)	Gym			3/12/2015		6		\$0.00
Medium	Work In Progress			3/12/2015 12:53:47 PM					
Ontiveros, Joe Boys dressing room urinal is clog up need to be check.									
Ismael Rodriguez									
128962	North Building	Custodial			2/17/2015		29		\$0.00
Medium	Work In Progress			2/17/2015 11:59:58 AM					
Gonzalez, Salvador Need to weld a stand for lights see Mr.Rodriguez.									
Ismael Rodriguez									
130131	North Building	Classroom			3/13/2015		5		\$0.00
Medium	Work In Progress	ROOM 3		3/13/2015 12:28:22 PM					
Villalobos, Margret ABNORMAL AMOUT OF SPIDERS INSIDE AND OUTSIDE CLASSROOM. STUDENT WAS BITTEN Emailed Waiver 3/17/15									
Laura Parra									
120397	South Building	Office			8/4/2014		226		\$0.00
Medium	Work In Progress	MEDINA-		8/4/2014 9:05:29 AM					
Flores, Pete GATOR NEEDS WORK DONE: CARB OVERHAUL, CHECK BRAKES, CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS)									
Laura Parra									
123870	North Building	Office			10/8/2014		161		\$0.00
Medium	Work In Progress	MR. POKLUDA		10/8/2014 11:40:04 AM					
Flores, Pete GATOR NEEDS: CARB OVERHAUL- CHECK BRAKES - CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS)									
Laura Parra									
125605					11/15/2014		123		\$0.00
Medium	Work In Progress			11/15/2014 12:45:34					
Flores, Pete Yearly - Santa Teresa MS - Mower 0416 - Grounds - Refer to PMschedule details.									
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

125952					11/30/2014		108		\$0.00
Medium	Work In Progress				11/30/2014 12:47:03				
Flores, Pete		Monthly - STM-UV-0518 PM Service - Refer to PM schedule details.							
Margret Villalobos									

128139					1/30/2015		47		\$0.00
Medium	Work In Progress				1/30/2015 10:38:32 AM				
Lara, Ralph		Both Bldgs Girls Restrooms - Please check latches on stall doors, they do not align and not able to lock when in use.							
Richard Chavez									

120010	North Building	Custodial			7/30/2014		231		\$0.00
Medium	Work In Progress				7/30/2014 7:35:01 AM				
Lara, Ralph		Rafa Mr.Mendoza needs replacements of keys his are not working well.							
Ismael Rodriguez									

129709	South Building	Custodial			3/3/2015		15		\$0.00
Medium	Work In Progress				3/3/2015 11:50:02 AM				
Lara, Ralph		Rey key office door for Ms.Parra							
Ismael Rodriguez									

120039	South Building	Office			7/30/2014		231		\$0.00
Medium	Work In Progress	MEDINA-			7/30/2014 3:12:13 PM				
Lara, Ralph		REMOVE DOOR WITH FRAME AND RELOCATE TO THE SECURITY OFFICE. OFFICE NEEDS TO BE LOCKED WHEN ILLEGAL ITEMS HAVE BEEN CONFISCATED							
Laura Parra									

130250	South Building	Classroom			3/17/2015		1		\$0.00
Medium	Work In Progress	CHOIR ROOM			3/17/2015 11:00:53 AM				
Lara, Ralph		DOOR HARDWARE IS VERY LOSE. DOES NOT LOCK PROPERLY. PLEASE INSTALL NEW LOCK AND DEADBOLT LOCK. INSTRUMENTS ARE STORED IN THIS ROOM.							
Laura Parra									

126361	North Building	Office			12/8/2014		100		\$0.00
Medium	Work In Progress	MAIN			12/8/2014 12:53:00 PM				
Lara, Ralph		FRONT MAIN DOORS NEED TO BE REPLACED. FALLING OFF TOP HINGE AND AS PER MR. LARA UNABLE TO REPAIR.							
Laura Parra									

3/18/2015 12:54:27 PM

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa MS							
128565	South Building	Office			2/6/2015		40		\$0.00
Medium	Work In Progress	SECURITY			2/6/2015 8:29:57 AM				
Lara, Ralph		AS PER MR LARA- REMOVE AND REPLACE DOOR							
Laura Parra									
128517					2/5/2015		41		\$0.00
Medium	Work In Progress				2/5/2015 10:28:03 AM				
Orozco, Daniel		OVEN (1) NOT HEATING PROPERLY. SNP MANAGER GESSICA M. 589.9836							
Maritza Gonzalez									
126904					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:36 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMs schedule details.							
Margret Villalobos									
125022					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress				11/2/2014 12:36:30 AM				
Orozco, Daniel		Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PMs schedule details.							
Margret Villalobos									
129981					3/10/2015		8		\$0.00
Medium	Work In Progress				3/10/2015 9:22:12 AM				
Carrasco, Danny		3/10/15. THE POLARIS NEED GASOLINE (5 galls)							
Manuel Prospero									
130080					3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 9:59:47 AM				
Orozco, Daniel		EXHAUST FAN IS NOT WORKING-RED TAGGED BY FIRE MARSHAL. SNP MANAGER GESSICA M.							
Maritza Gonzalez									
130272		Office			3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 3:20:24 PM				
Gonzales, Camilo		Deliver 20 boxes. PO# 141505820, Federal Programs.							
Theresa Ramirez									
127696	North Building	Office			1/20/2015		57		\$0.00
Medium	Work In Progress	8- Nurses Office			1/20/2015 10:56:02 AM				
Castillo, Carlos		Install light switch on the back entry door							
Laura Parra									
Count: 50 Work Orders		Avg. Age of WO's		76	Total for Santa Teresa MS			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

Location: Sunland Park ES									
128376	Main Building	Gym			2/3/2015		43		\$0.00
Medium	Work In Progress				2/3/2015 7:35:25 AM				
Castillo, Carlos		requesting the scissor lift to clean the air conditioning ducting on top full of dust. If i could get it on the 21st of february and would be using it 22 and 23 no students on those days. thanks							
Jesus Lucero									
130075		Office			3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 8:13:39 AM				
Gonzales, Camilo		Pick up obsolete items at the school and deliver to IMWHSE.							
Theresa Ramirez									
130020		Library			3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 8:40:05 AM				
Gonzales, Camilo		LIBRARY- NEEDS TO HAVE EQUIPMENT PICKED UP.WILL SEND THE LIST THRU ENTER DEPARTMENT MAIL.							
Maribel Chavez									
129357					2/26/2015		20		\$0.00
Medium	Work In Progress				2/26/2015 3:10:50 PM				
Castillo, Carlos		need light fixture replace in bathroom to portable a							
Carlos Hernandez									
129038					2/18/2015		28		\$0.00
Medium	Work In Progress				2/18/2015 3:30:04 PM				
Castillo, Carlos		need to replace light on pole front of school							
Carlos Hernandez									
129910					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:41 AM				
Hernandez, Carlos		Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
130262					3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 2:10:41 PM				
Hernandez, Carlos		need to replace irrigation valve and couplings							
Carlos Hernandez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
130238		Library			3/17/2015		1		\$0.00
Medium	Work In Progress	LIBRARY			3/17/2015 8:44:01 AM				
Hernandez, Carlos		LIBRARY- NEED BANNERS HUNG IN THE MAIN HALLWAY WILL NEED ACCESS TO THE SCISSOR LEFT TO PLACE THESE UP							
Maribel Chavez									
130242		Portables			3/17/2015		1		\$0.00
Medium	Work In Progress	PORTABLE A			3/17/2015 9:03:20 AM				
Hernandez, Carlos		PORTABLE A - CANO- LIGHT IN RESTROOM WENT OUT, IT NEEDS TO BE REPLACED							
Maribel Chavez									
128591		Classroom			2/6/2015		40		\$0.00
Medium	Work In Progress	32			2/6/2015 11:56:37 AM				
Hernandez, Carlos		RM#32 ARAPI- NEED TO HAVE A HANDICAP BAR INSTALLED IN THERE BATHROOM							
Maribel Chavez									
130038		Classroom			3/11/2015		7		\$0.00
Medium	Work In Progress	16			3/11/2015 2:11:37 PM				
Hernandez, Carlos		RM#16- RUBIO- PUT BACK TOGETHER A BOOKSHELF WITH SCREWS FIX A BOOKSHELF AS SOON AS POSSIBLE							
Maribel Chavez									
129873		Classroom			3/6/2015		12		\$0.00
Medium	Work In Progress	16			3/6/2015 11:20:38 AM				
Hernandez, Carlos		RM#16- RUBIO- LOWER MY WHITE BOARD AND REPLACE PENCIL SHARPNER IF WE HAVE ANY NEW ONES IN OFFICE							
Maribel Chavez									
122203					9/3/2014		196		\$0.00
Medium	Work In Progress	PLAYGROUND			9/3/2014 7:24:39 AM				
Hernandez, Carlos		CARLOS - PLEASE CHECK PLAYGROUND EQUIPMENT. THERE IS A WHITE RAIL THAT IS BROKEN AND IS DANGEROUS. THERE USED TO BE A SLIDE THERE, NOW THERE ARE HANGING PARTS. PLEASE SEE MS. DUQUE FOR FURTHER INSTRUCTIONS. THANK YOU.							
David Avila									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Sunland Park ES							
129544					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:25 AM				
Hernandez, Carlos	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PMschedule details.								
Margret Villalobos									
129545					3/1/2015	3/9/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:26 AM				
Hernandez, Carlos	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PMschedule details.								
Margret Villalobos									
129600					3/1/2015	3/7/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:57 AM				
Hernandez, Carlos	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PMschedule details.								
Margret Villalobos									
129476					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:44 AM				
Hernandez, Carlos	Yearly - Sunland Park ES A-10 HP Rooftop Yearly - Refer to PMschedule details.								
Margret Villalobos									
129490					3/1/2015	3/17/2015	17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:52 AM				
Hernandez, Carlos	Monthly - Sunland Park ES A-1 Wall Ref Semiannual - Refer to PMschedule details.								
Margret Villalobos									
129430					2/28/2015	3/31/2015	18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:43 AM				
Hernandez, Carlos	Yearly - Sunland Park ES C-11 Evap Coolers Yearly - Refer to PMschedule details.								
Margret Villalobos									
129453					2/28/2015		18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:59 AM				
Hernandez, Carlos	Monthly - Sunland Park ES A-16 Fan Exh Semiannual - Refer to PMschedule details.								
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Sunland Park ES									
128770	Main Building	Custodial			2/11/2015		35		\$0.00
Medium	Work In Progress				2/11/2015 7:19:56 AM				
Castillo, Carlos	requesting two 50ft electric power extensions. we do not have any here at sunland park . Thanks								
Jesus Lucero									
129786					3/4/2015		14		\$0.00
Medium	Work In Progress				3/4/2015 3:32:31 PM				
Castillo, Carlos	need outlet for projector screen in portable a								
Carlos Hernandez									
128572		Classroom			2/6/2015		40		\$0.00
Medium	Work In Progress	COACHES			2/6/2015 9:01:46 AM				
Castillo, Carlos	COACHES OFFICE- ANOTHER OUTLET FOR A NEW COMPUTER THERES ONE ALREADY BUT WE NEED ANOTHER ONE THERE WILL 2 NEW COMPUTERS IN THERE OFFICE								
Maribel Chavez									
130201					3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 3:21:45 PM				
Castillo, Carlos	as per principal need power to marquee								
Carlos Hernandez									
127809		Classroom			1/22/2015		55		\$0.00
Medium	Work In Progress	LIBRARY			1/22/2015 1:26:00 PM				
Holguin, Alfredo	LIBRARY- NEED TO HAVE CEMENT COMPLETED ON THE SIDE WALK ON THE NORTH SIDE OF THE BUILDING RIGHT NEXT TO ROAD. (BOOK FAIR WILL ARRIVE FEB. 11,2015)								
Maribel Chavez									
130263					3/17/2015		1		\$0.00
Medium	Work In Progress				3/17/2015 2:12:15 PM				
Carrasco, Danny	need 5 sacks weed and feed and 25 sacks fertilizer for soccer field and in feild								
Carlos Hernandez									
127545					1/14/2015		63		\$0.00
Medium	Work In Progress				1/14/2015 3:16:36 PM				
Carrasco, Danny	need these tools 6 in one screw driver 5/16 bit 8 ft fiberglass ladder channel locks								
Carlos Hernandez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunland Park ES							
125023					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress				11/2/2014 12:36:31 AM				
Orozco, Daniel		Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
126902					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:35 AM				
Villalobos, David		Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
127845					1/23/2015		54		\$0.00
Medium	Work In Progress	Front Main Gate			1/23/2015 11:09:20 AM				
Lara, Ralph		OFFICE - NEEDS A EXTRA KEY FOR THE FRONT MAIN GATE							
Maribel Chavez									
129353					2/26/2015		20		\$0.00
Medium	Work In Progress				2/26/2015 2:58:02 PM				
Lara, Ralph		need to replace 8 panic bars (out dated no parts)							
Carlos Hernandez									
129354					2/26/2015		20		\$0.00
Medium	Work In Progress				2/26/2015 2:59:19 PM				
Lara, Ralph		need door mullens on west and north doors							
Carlos Hernandez									
130071					3/12/2015		6		\$0.00
Medium	Work In Progress				3/12/2015 7:44:24 AM				
Flores, Pete		lawn mower d130 not working properly needs repair							
Carlos Hernandez									
130235					3/17/2015		1		\$0.00
Medium	Work In Progress	FOOTBALL			3/17/2015 8:37:45 AM				
Gonzalez, Salvador		FOOTBALL FIELD- SOCCER GOAL NEEDS TO BE ANCHORED DOWN AND WATER FOUNTAIN NEED TO FIXED AS WELL							
Maribel Chavez									
129176					2/23/2015		23		\$0.00
Medium	Work In Progress				2/23/2015 3:22:09 PM				
Gonzalez, Salvador		need to weld metal to ramps on portable d							
Carlos Hernandez									
3/18/2015 12:54:27 PM									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

129355					2/26/2015		20		\$0.00
Medium	Work In Progress				2/26/2015 3:00:44 PM				
Gonzalez, Salvador		need metal steps for portable e							
Carlos Hernandez									

124374					10/21/2014		148		\$0.00
Medium	Work In Progress	SCHOOL			10/21/2014 8:19:39 AM				
Ronquillo, Ruben		CARLOS-							
David Avila		AS PER MR. VAN NOSDALE: IS THERE A WAY TO FIX THE SCHOOL'S MARQUEE? THERE IS A HOLE IN ONE OF THE PANELS WHICH MAKES IT LOOK REALLY BAD AND WE ARE NOT ABLE TO PUT FULL MESSAGES ON THE MARQUEE. PLEASE LET US KNOW IF THERE IS ANYTHING THAT CAN BE DONE. THANK YOU.							

128894					2/13/2015		33		\$0.00
Medium	Work In Progress				2/13/2015 9:03:22 AM				
Ronquillo, Ruben		PARKING IN THE BACK OF CAFETERIA-Put up signs and missing signs in rear parking lot that state custodian, counselor, office staff							

129356					2/26/2015		20		\$0.00
Medium	Work In Progress				2/26/2015 3:02:52 PM				
Ronquillo, Ruben		need blinds for portable a and b 2=30x58 and 4= 34x46							
Carlos Hernandez									

120657					8/6/2014		224		\$0.00
Medium	Work In Progress				8/6/2014 1:56:14 PM				
Gallegos, Rafael		WALK IN REFRIGERATOR IS NOT COOLING. SNP MANAGER IGNACIA C. 589.2545							
Maritza Gonzalez									

127098	Main Building	Classroom			1/6/2015		71		\$0.00
Medium	Work In Progress				1/6/2015 8:05:49 AM				
Gallegos, Rafael		Since yesterday monday 1-5-15 there have been a few rooms that seems like the heaters are not turning on at all carlos building mechanic for sunland park elementary has been out for the past days. thanks							

Jesus Lucero

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
124503					10/23/2014		146		\$0.00
Medium	Work In Progress	CLASSROOM			10/23/2014 10:06:57				
Ontiveros, Joe		AS PER MS. CORDERO - PLEASE CHECK UNDERNEATH SINK - THERE IS A LEAK AND WATER IS SITTING AND NOW THERE ARE MOSQUITOES.							
David Avila									
126029					12/1/2014		107		\$0.00
Medium	Work In Progress				12/1/2014 8:49:10 AM				
Ontiveros, Joe		need new drain kit for sink in nurses office							
Carlos Hernandez									
120344					8/3/2014		227		\$0.00
Medium	Work In Progress				8/3/2014 12:33:44 AM				
Munoz, Michael		Yearly - Sunland Park ES Fire Ext. Insp. (Yearly) - Refer to PMschedule details.				PMnot completed as per schedule			
Margret Villalobos									
128762					2/10/2015		36		\$0.00
Medium	Work In Progress				2/10/2015 3:47:58 PM				
Ontiveros, Guadalupe		need 25 bags of fertilizer							
Carlos Hernandez									
130025	Main Building	Custodial			3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 9:17:16 AM				
Carbajal, Jimmy		one of our vacuums broke this week i believe its the extension court if you could please check it out thanks jimmy.							
Jesus Lucero									
128859					2/12/2015		34		\$0.00
Medium	Work In Progress				2/12/2015 3:07:13 PM				
Ambriz, Jose		need to reroute return in portable A							
Carlos Hernandez									
127268					1/8/2015		69		\$0.00
High	Work In Progress				1/8/2015 3:52:21 PM				
Ambriz, Jose		need to flush system to all hvac coils, flushing was not included on contract. thank you							
Michael Munoz									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Sunland Park ES							
129872		Classroom			3/6/2015		12		\$0.00
Medium	Work In Progress	PORTABLE A			3/6/2015 11:16:04 AM				
Ontiveros, Joe		PORTABLE A- CANO - PIPES NEEDED TO BE REMOVED FROM UNDERNEATH THE SMART BOARD							
Maribel Chavez									
123862	Main Building	Classroom			10/8/2014		161		\$0.00
Medium	Work In Progress				10/8/2014 10:05:34 AM				
Estrada, Jesus		the tile is lifting up and could become a safety problem this is in room 39.							
Jesus Lucero									
127906		Restroom (Girls)			1/26/2015		51		\$0.00
Medium	Work In Progress				1/26/2015 9:16:04 AM				
Ontiveros, Joe		GIRL RESTROOM- SINK BROKEN							
Maribel Chavez									
Count: 51 Work Orders		Avg. Age of WO's 47			Total for Sunland Park ES			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunrise ES							
128595					2/6/2015		40		\$0.00
Medium	Work In Progress				2/6/2015 12:05:54 PM				
Estrada, Jesus		portables 6 and 8 need replacing floor tiles							
Juan Vargas									
122989					9/19/2014		180		\$0.00
Medium	Work In Progress				9/19/2014 11:25:15 AM				
Estrada, Jesus		Library carpet has two runs in its south side and north side entrance. Also a pebble underneath a tile is breaking through by main desk.							
Jesus Estrada									
129107					2/20/2015		26		\$0.00
Medium	Work In Progress				2/20/2015 8:16:41 AM				
Ontiveros, Guadalupe		need replace 7 dry trees for Arizona ash trees							
Juan Vargas									
120861					8/8/2014		222		\$0.00
Medium	Work In Progress				8/8/2014 3:25:05 PM				
Ontiveros, Guadalupe		need fix or replace release valve in irrigation buster pump							
Juan Vargas									
129589					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:51 AM				
Apodaca, Mario		Monthly - Sunrise ES - Lift Station Inspection - Refer to PMs schedule details.							
Margret Villalobos									
129920					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:47 AM				
Vargas, Juan		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
129501					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:46:00 AM				
Vargas, Juan		Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.							
Margret Villalobos									
129105					2/20/2015		26		\$0.00
Medium	Work In Progress				2/20/2015 7:48:37 AM				
Vargas, Juan		need replace playfield sprinklers							
Juan Vargas									
3/18/2015 12:54:28 PM									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
129106					2/20/2015		26		\$0.00
Medium	Work In Progress				2/20/2015 7:55:13 AM				
Vargas, Juan		need repainting parking lines							
Juan Vargas									
129472					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:42 AM				
Vargas, Juan		Yearly - Sunrise ES A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
129434					2/28/2015	3/31/2015	18		\$0.00
Medium	Work In Progress				2/28/2015 12:34:46 AM				
Vargas, Juan		Yearly - Sunrise ES C-11 (Evap.Cooler)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
128009					1/27/2015		50		\$0.00
Medium	Work In Progress				1/27/2015 3:43:20 PM				
Vargas, Juan		need trimming all tress				3/9/15 - Asp Lupe, route to Juan V.			
Juan Vargas									
128557					2/6/2015		40		\$0.00
Medium	Work In Progress				2/6/2015 7:44:57 AM				
Vargas, Juan		need replacing units in kitchen and cafeteria							
Juan Vargas									
125570					11/14/2014		124		\$0.00
Medium	Work In Progress				11/14/2014 1:15:20 PM				
Vargas, Juan		need replace playground plastic borders north side							
Juan Vargas									
126900					1/4/2015	2/4/2015	73		\$0.00
Medium	Work In Progress				1/4/2015 12:40:33 AM				
Villalobos, David		Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
125024					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress				11/2/2014 12:36:32 AM				
Orozco, Daniel		Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
129103					2/20/2015		26		\$0.00
Medium	Work In Progress				2/20/2015 7:44:19 AM				
Carrasco, Danny		need grass seed for playfield							
Juan Vargas									
130301					3/18/2015		0		\$0.00
Medium	Work In Progress				3/18/2015 8:51:52 AM				
Orozco, Daniel		ICE MACHINE NOT MAKING ICE. SNP MANAGER GLENDA G. 824.3194							
Maritza Gonzalez									
122835					9/16/2014		183		\$0.00
Medium	Work In Progress				9/16/2014 12:45:28 PM				
Vallejo, Albert		NEED REPLACE LIGHTS IN R.ROOMS							
Juan Vargas									
130216					3/16/2015		2		\$0.00
Medium	Work In Progress				3/16/2015 3:52:07 PM				
Appelzoller, Fred		grls. r,rooms next.to cafeteria need replace fouset broken							
Juan Vargas									
124690					10/28/2014		141		\$0.00
Medium	Work In Progress				10/28/2014 3:28:58 PM				
Appelzoller, Fred		200 boy r.room need fix or replace sink fouset							
Juan Vargas									
120182					8/1/2014		229		\$0.00
Medium	Work In Progress				8/1/2014 12:10:52 PM				
Appelzoller, Fred		need replace map sinck and fouset is broke							
Juan Vargas									
120097					7/31/2014		230		\$0.00
Medium	Work In Progress				7/31/2014 12:37:15 PM				
Appelzoller, Fred		replasar llave pegada ala pared tiene lick in 200 wing							
Juan Vargas									
125113					11/3/2014		135		\$0.00
Medium	Work In Progress				11/3/2014 3:48:14 PM				
Ontiveros, Guadalupe		need arena for 2 playgrounds 40 tons.							
Juan Vargas									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Sunrise ES							
130230	Main Building	Classroom			3/17/2015		1		\$0.00
Medium	Work In Progress	SPEECH			3/17/2015 8:12:49 AM				
Marquez, Gerardo		JOANNE MUNOZ, FRONT OFFICE, WE HAVE ANOTHER SPEECH THERAPIST AND SHE IS NEEDING A KEY FOR OUR SPEECH ROOM IC43 PLEASE.							
Joanne Munoz									
Count: 25 Work Orders		Avg. Age of WO's 79			Total for Sunrise ES			0	\$0.00

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Vado ES							
130026	Main Building	Custodial			3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 10:34:12 AM				
Marquez, Gerardo		Custodian office broken door handle !							
Armando Diaz									
130139					3/13/2015		5		\$0.00
Medium	Work In Progress				3/13/2015 2:30:38 PM				
Ontiveros, Guadalupe		need red screening/red dirt for ground around raised gardens (work will be done on FRIDAY APRIL 10th)							
Danny Miranda									
129283					2/25/2015		21		\$0.00
Medium	Work In Progress				2/25/2015 10:11:06 AM				
Sotelo, Enrique		neer to repair ballast in office area, room 303, and girls restroom 300-hallway							
Danny Miranda									
129317		Classroom			2/25/2015		21		\$0.00
Medium	Work In Progress	Room #403			2/25/2015 4:01:44 PM				
Sotelo, Enrique		Computers need to be connected to a different power strips, because sparks are coming from electrical drops.							
Cary, Sylvia									
128036					1/28/2015		49		\$0.00
Medium	Work In Progress				1/28/2015 12:37:24 PM				
Orozco, Daniel		REACH IN IS NOT COOLING. SNP MANAGER ELIZABETH M. 233.2945							
Maritza Gonzalez									
128037					1/28/2015		49		\$0.00
Medium	Work In Progress				1/28/2015 12:38:28 PM				
Orozco, Daniel		ICE MAKER NOT MAKING ICE. SNP MANAGER ELIZABETH M. 233.2945							
Maritza Gonzalez									
128901					2/13/2015		33		\$0.00
Medium	Work In Progress				2/13/2015 1:57:28 PM				
Orozco, Daniel		DRAINS BACKING UP IN KITCHEN AREA. SNP MANAGER ELIZABTEH M. 233.2945							
Maritza Gonzalez									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Vado ES							
129483					3/1/2015		17		\$0.00
Medium	Work In Progress				3/1/2015 12:45:48 AM				
Miranda, Danny	Yearly - Vado ES A-10 Heat Pump Yearly - Refer to PM schedule details.								
Margret Villalobos									
129912					3/9/2015	3/24/2015	9		\$0.00
Medium	Work In Progress				3/9/2015 12:35:42 AM				
Miranda, Danny	Monthly - Vado ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
129280					2/25/2015		21		\$0.00
Medium	Work In Progress				2/25/2015 10:02:24 AM				
Miranda, Danny	need weed and feed for grounds								
Danny Miranda									
125025					11/2/2014	11/23/2014	136		\$0.00
Medium	Work In Progress				11/2/2014 12:36:32 AM				
Orozco, Daniel	Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
126444					12/10/2014		98		\$0.00
Medium	Work In Progress				12/10/2014 9:11:12 AM				
Orozco, Daniel	SINK - WHEN SHUT OFF WATER LEAKS.SNP MANAGER ELIZABETH M. 233.2945								
Maritza Gonzalez									
127039					1/5/2015		72		\$0.00
Medium	Work In Progress				1/5/2015 10:26:16 AM				
Orozco, Daniel	REGRIGERATOR DOWN. SNP MANAGER ELIZABETH MARRUFO 233.2945								
Maritza Gonzalez									
129213					2/24/2015		22		\$0.00
Medium	Work In Progress				2/24/2015 9:08:06 AM				
Villalobos, David	need to replace outside drinking fountain								
Danny Miranda									
130040					3/11/2015		7		\$0.00
Medium	Work In Progress				3/11/2015 2:56:03 PM				
Villalobos, David	need to run snake at 3 1/2 cleanout that runs under track								
Danny Miranda									
3/18/2015 12:54:28 PM									

1207 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Vado ES									
129871					3/6/2015		12		\$0.00
Medium	Work In Progress				3/6/2015 11:12:03 AM				
Solis, Lorenzo	need to ck. unit in room 307, I checked pump but will not stay on, and will go to alarm mode								
Danny Miranda									
129137					2/20/2015		26		\$0.00
Medium	Work In Progress				2/20/2015 3:43:11 PM				
Solis, Lorenzo	need to replace motor, blower, and bearings to blower in 200-wing recovery wheel								
Danny Miranda									
119473	Main Building	Office			7/16/2014		245		\$0.00
Medium	Work In Progress				7/16/2014 8:36:17 AM				
Munoz, Michael	NEED TO REPLACE COUNTER TOP IN TEACHERS LOUNGE AND FRONT OFFICE. ASAP								
Debra Facio									
129766	Main Building	Custodial			3/4/2015		14		\$0.00
Medium	Work In Progress				3/4/2015 10:36:36 AM				
Carbajal, Jimmy	Need propane tank 4 buffer refill. Thank u !								
Armando Diaz									
128163					1/30/2015		47		\$0.00
Medium	Work In Progress				1/30/2015 2:59:13 PM				
Flores, Pete	truck # 135 transmittion slipping bad, bad, bad!!!!								
Danny Miranda									
Count: 20 Work Orders			Avg. Age of WO's 46		Total for Vado ES			0	\$0.00
Count: 1207 Work Orders			Avg. Age of WO's 70		Grand Total			6	\$150.00