

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Alta Vista Early College HS									
130889					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:07 AM				
Ambriz, Alfredo		Monthly - Alta Vista ECHS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130890					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:07 AM				
Ambriz, Alfredo		Monthly - Alta Vista ECHS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
131227					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:32 AM				
Ambriz, Alfredo		Monthly - QRTLY BLDG INSP REPORT (DP) - Refer to PM schedule details.							
Margret Villalobos									
130954					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:41 AM				
Ambriz, Alfredo		Monthly - Alta Vista ECHS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
129721		Office			3/3/2015		43		\$0.00
Medium	Work In Progress	main Office			3/3/2015 2:29:14 PM				
Ambriz, Alfredo		Need burnish for a desk (1 qt).							
Alfredo Ambriz									
120833					8/8/2014		250		\$0.00
Medium	Work In Progress				8/8/2014 1:58:33 PM				
Villalobos, David		Need to repair water line between the morgan bldg.							
Michael Munoz									
123089		Classroom			9/23/2014		204		\$0.00
Medium	Work In Progress				9/23/2014 3:28:10 PM				
Sotelo, Enrique		Connect all new treadmills in the PE portable #504 to the internet/wi-fi							
Minerva Menchaca									
121826	Curriculum and	Portables			8/27/2014		231		\$0.00
Medium	Work In Progress				8/27/2014 8:16:27 AM				
Sotelo, Enrique		Ned to fix the power outlet strip on the west side wall of the portable. PE portable #504							
Minerva Menchaca									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Alta Vista Early College HS

128585 Exterior 2/6/2015 68 \$0.00

Medium Work In Progress Front Section 2/6/2015 10:40:45 AM

Ontiveros, Guadalupe NEED TO REMOVE PINE TREES IN FRONT OF MAIN BUILDING.

Yvette Cortez

130674 Parking Lot 3/27/2015 19 \$0.00

Medium Work In Progress Front Parking 3/27/2015 3:13:45 PM

Ontiveros, Guadalupe LOG/UTILITY POLE NEEDS TO BE CUT BACK DUE TO STUDENT SAFETY ISSUES: POSING A TRIP HAZARD FOR PEDESTRIANS AND RUNNERS (PE CLASS).

Yvette Cortez

131426 Portables 4/15/2015 0 \$0.00

Medium Work In Progress 504 4/15/2015 9:29:14 AM

Ambriz, Jose AC UNIT IN PE CLASSROOM NEEDS TO BE TURNED ON. CLASSROOM IS TOO HOT FOR STUDENTS TO CONDUCT THEIR PE CLASS.

Yvette Cortez

120783 Curriculum and Classroom 8/8/2014 250 \$0.00

Medium Work In Progress 8/8/2014 8:03:48 AM

Ambriz, Jose Install a refrigerated unit in the Rm 504 old PE portable and Rm 501 old Art Room.

Minerva Menchaca

131369 4/14/2015 1 \$0.00

Medium Work In Progress 4/14/2015 9:43:10 AM

Carbajal, Jimmy the machine broke the adjustment that makes it go up and down.

Alfredo Ambriz

126152 12/3/2014 133 \$0.00

Medium Work In Progress 12/3/2014 8:43:42 AM

Munoz, Michael He is also asking if the remaining concrete can be used as a border for a volley ball court but I need to talk to you on this one.

Alfredo Holguin

131106 4/8/2015 7 \$0.00

Medium Work In Progress 4/8/2015 2:18:21 PM

Villalobos, Margret can you come and instal an irrigation system for some trees thank you.

Alfredo Ambriz

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Alta Vista Early College HS

131368 4/14/2015 1 \$0.00

Medium Work In Progress 4/14/2015 9:38:38 AM

Villalobos, Margret I'm going to need black gloss paint for the widows security bars for my site thank you.

Alfredo Ambriz

131285 4/13/2015 2 \$0.00

Medium Work In Progress 4/13/2015 10:04:52 AM

Aguilar, Patricio Can you please come and fix two leaks one on the Library roof and the other one on PE classroom thank you.

Alfredo Ambriz

130745 3/31/2015 15 \$0.00

Medium Work In Progress 3/31/2015 12:38:13 AM

Aguilar, Patricio Monthly - Desert Pride HS A16 (Fan Exh.)(S. Annual) - Refer to PM schedule details.

Margret Villalobos

124395 Curriculum and Classroom 10/21/2014 176 \$0.00

Medium Work In Progress 10/21/2014 12:07:07

Aguilar, Patricio Need 6 cans of black spray paint to paint the window guards on the classrooms. Blue paint to paint the handicap parking barrier.

Minerva Menchaca

126459 Office 12/10/2014 126 \$0.00

Medium Work In Progress Main Office 12/10/2014 10:09:54

Aguilar, Patricio NEED SIX STEEL LEG TABLES TO ASSEMBLE DESK AND TABLE IN ADMINISTRATIVE ASSISTANT'S OFFICE AT ALTA VISTA EARLY COLLEGE. PLEASE CONTACT YVETTE FOR ANY INFORMATION.

Yvette Cortez

130845 4/5/2015 4/13/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:29:42 AM

Aguilar, Patricio Monthly - Alta Vista ECHS - Roof Inspection - Refer to PM schedule details.

Margret Villalobos

130792 4/5/2015 4/26/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:29:14 AM

Aguilar, Patricio Monthly - Desert Pride HS H11 (E.Heater)(S. Annual) - Refer to PM schedule details.

Margret Villalobos

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Alta Vista Early College HS							
127536		Office			1/14/2015		91		\$0.00
Medium	Work In Progress	Main Office			1/14/2015 2:04:52 PM				
Lara, Ralph		DOOR TO ASST. PRINCIPAL NEED TO BE REPLACED WITH NEW DOOR.							
Yvette Cortez									
127540		Office			1/14/2015		91		\$0.00
Medium	Work In Progress	Principal's Office			1/14/2015 2:10:29 PM				
Lara, Ralph		DOOR TO PRINCIPAL'S OFFICE IS UNEVEN NEEDS TO BE REPLACED WITH NEW DOOR.							
Yvette Cortez									
130982		Office			4/6/2015		9		\$0.00
Medium	Work In Progress	Main Office			4/6/2015 9:59:01 AM				
Lara, Ralph		NEED KEY TO MS. SALCEDO'S OFFICE IN CASE OF AN EMERGENCY.							
Yvette Cortez									
129462					2/28/2015		46		\$0.00
Medium	Work In Progress				2/28/2015 12:35:05 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details.							
Margret Villalobos									
130934					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:31 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
131333					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 12:23:17 AM				
Sanchez, Raul		Monthly - Alta Vista ECHS- Water Filters - Refer to PM schedule details.							
Margret Villalobos									
128603					2/6/2015		68		\$0.00
Medium	Work In Progress				2/6/2015 2:35:23 PM				
Ronquillo, Ruben		BELTS ON CARDIO SMART TREADMILLS NEED TO BE REPLACED.							
Yvette Cortez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Alta Vista Early College HS									
130922					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:24 AM				
Ronquillo, Ruben		Monthly - Alta Vista ECHS - (Qtrly) Fitness Equip - Refer to PM schedule details.							
Margret Villalobos									
131171		Cafeteria			4/9/2015		6		\$0.00
Medium	Work In Progress	Cafeteria			4/9/2015 4:29:45 PM				
Gonzalez, Salvador		THE STAIRS TO THE BACK DOOR IN THE CAFETERIA PORTABLE ARE DETERIORATING AND DISINTEGRATING. STAIRS MAY COLLAPSE AT ANYTIME AND CAUSE INJURY TO STUDENTS AND STAFF. NEEDS TO BE REPLACED IMMEDIATELY.							
Yvette Cortez									
127109					1/6/2015		99		\$0.00
Medium	Work In Progress				1/6/2015 10:14:38 AM				
Gonzalez, Salvador		Can you please come by and weld a pick nick table its one of the the students where they eat for breakfast and lunch thank you.							
Alfredo Ambriz									
126236					12/4/2014		132		\$0.00
Medium	Work In Progress				12/4/2014 11:24:06 AM				
Gonzalez, Salvador		Gate does not work property hard to open and close please repair.							
Alfredo Ambriz									
Count: 33 Work Orders		Avg. Age of WO's 65		Total for Alta Vista Early College HS				0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony - On Track Pre-K (Village)									
128783					2/11/2015		63		\$0.00
Medium	Work In Progress				2/11/2015 11:09:42 AM				
Ronquillo, Ruben		02/11/2015.							
		slide at pre k playground has a tear at the bottom end and is potential cut hazard.							
David Escobar									
128982					2/17/2015		57		\$0.00
Medium	Work In Progress				2/17/2015 3:49:14 PM				
Ronquillo, Ruben		canopy has not been replace this is the second work order since May 2014							
Laura Vazquez									
131296					4/13/2015		2		\$0.00
Medium	Work In Progress	ROOM # 105			4/13/2015 1:02:54 PM				
Sotelo, Enrique		Requesting power lines/sources for the 6 work stations and copier that will be at the PAT Center							
Noemi Duron									
124372					10/21/2014		176		\$0.00
Medium	Work In Progress				10/21/2014 8:07:56 AM				
Marquez, Gerardo		cut out counter top for new sink in the 1st portable. contact person estrella. thank you							
Michael Munoz									
121769					8/26/2014		232		\$0.00
Medium	Work In Progress				8/26/2014 9:12:18 AM				
Marquez, Gerardo		speech therapist is having trouble locking door to speech therapy room							
David Vega									
128397					2/3/2015		71		\$0.00
Medium	Work In Progress				2/3/2015 10:11:02 AM				
Carrasco, Danny		02/03/2015.							
		BM needs 5 tubes of 3M acrylic to repair a tear on spiral slide at Pre K village .							
David Escobar									
128989					2/17/2015		57		\$0.00
Medium	Work In Progress	882-1904			2/17/2015 3:58:18 PM				
Escobar, David		finish painting the pre-k we already have the paint that a parent donated since the beginning of the year if any question please ask Laura or Estrella							
Laura Vazquez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony - On Track Pre-K (Village)

129405		Cafeteria			2/27/2015		47		\$0.00
--------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	882-1904			2/27/2015 2:20:39 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Vega, David
 we are going to received new furniture for the cafeteria rm 101 and 102, when we received the furniture please take out all tables and put away the chairs that are in those rooms.
 thank you, Laura

Laura Vazquez

130273		Cafeteria			3/17/2015		29		\$0.00
--------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	882-1904			3/17/2015 3:22:44 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Vega, David
 David starting today please clean the cafeterias when our AM session is over a lot of food is on the floor and yesterday one of employee's had an accident.
 Thank you,
 Laura

Laura Vazquez

130248					3/17/2015		29		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room #105			3/17/2015 10:49:58 AM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Vega, David
 Clean the bathroom and the counter w/ the sink .

Noemi Duron

130187		Classroom			3/16/2015		30		\$0.00
--------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	882-1904			3/16/2015 11:23:06 AM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Vega, David
 As per Ms. Denise request please clean the bathroom from room 108, vacuum the carpets and mop the classroom.

Laura Vazquez

130363					3/19/2015		27		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	882-1904			3/19/2015 10:09:22 AM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Escobar, David
 Please repaint the arrows that are in the sidewalk where the children's ride the tricycles
 thank you, Laura

Laura Vazquez

130246					3/17/2015		29		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room # 105			3/17/2015 9:28:39 AM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Escobar, David
 repair the insulation on the pipes near the ceiling

Noemi Duron

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
130409					3/19/2015		27		\$0.00
Medium	Work In Progress	ROOM#105			3/19/2015 4:55:08 PM				
Holguin, Alfredo		REQUESTING TO EXTEND COUNTER BY SINK.				Routed to A. Holguin			
Noemi Duron									
131381		Office			4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 1:32:06 PM				
Gonzales, Camilo		Deliver 6 boxes. PO# 141506639. Attn: Julie Soto, RM. 105. Thank you.							
Theresa Ramirez									
Count: 15 Work Orders			Avg. Age of WO's	58	Total for Anthony - On Track Pre-K (Village)		0		\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

131340 4/14/2015 1 \$0.00

Medium Work In Progress CALVARY 4/14/2015 7:42:07 AM

Gonzales, Camilo DELIVER PO141505279 SADDLEBACK EDUCATIONAL 1 BOX ELIZABETH GONZALEZ, CALVARY WEST HIGH SCHOOL

Margaret Villalobos

131347 4/14/2015 1 \$0.00

Medium Work In Progress SPED OFFICE 4/14/2015 7:47:49 AM

Gonzales, Camilo DELIVER PO 141505129 EL PASO OFFICE PRODUCTS 1 BOX LUPE CAMPOS, CHILD FIND

Margaret Villalobos

131348 4/14/2015 1 \$0.00

Medium Work In Progress SPED OFFICE 4/14/2015 7:49:33 AM

Gonzales, Camilo DELIVER PO 141504560 MULTI-HEALTH 1 PKG RUTH HERRERA, PSYCHOLOGIST

Margaret Villalobos

131357 4/14/2015 1 \$0.00

Medium Work In Progress SPED OFFICE 4/14/2015 8:07:19 AM

Gonzales, Camilo DELIVER PO 141506604 ORIENTAL TRADING 1 BOX CLAUDIA PEREZ, INSTRUCTIONAL SPECIALIST

Margaret Villalobos

131359 4/14/2015 1 \$0.00

Medium Work In Progress SPED OFFICE 4/14/2015 8:08:42 AM

Gonzales, Camilo DELIVER PO 141504561 PEARSON ASSESSMENT 1 BOX RUTH HERRERA, PSYCHOLOGIST

Margaret Villalobos

131334 4/14/2015 1 \$0.00

Medium Work In Progress SPED OFFICE 4/14/2015 7:33:42 AM

Gonzales, Camilo DELIVER PO #141505980 ADCO HEARING PRODUCTS 1 BOX MARGARET VILLALOBOS/L. MCCULLER

Margaret Villalobos

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

131336 4/14/2015 1 \$0.00

Medium Work In Progress SPED OFFICE 4/14/2015 7:35:42 AM

Gonzales, Camilo DELIVER PO #141506605 EP OFFICE PRODUCTS
2 BOXES
MARGARET VILLALOBOS PARENT CONFERENCE

Margaret Villalobos

131337 4/14/2015 1 \$0.00

Medium Work In Progress SPED OFFICE 4/14/2015 7:37:26 AM

Gonzales, Camilo DELIVER PO141505020 RIFTON EQUIPMENT
3 BOXES
VIRGINIA CHACON, PT

Margaret Villalobos

131338 4/14/2015 1 \$0.00

Medium Work In Progress CALVARY 4/14/2015 7:38:57 AM

Gonzales, Camilo DELIVER PO 141505281 BARNES AND NOBLE
3 BOXES
ELIZABETH GONZALEZ, CALVARY WEST HIGH
SCHOOL

Margaret Villalobos

130813 4/5/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:29:25 AM

Holguin, Alfredo Monthly - Anthony ES - Fire Pump Engine - Refer to PM
schedule details.

Margret Villalobos

129601 3/1/2015 3/7/2015 45 \$0.00

Medium Work In Progress 3/1/2015 12:46:58 AM

Escobar, David Monthly - Anthony ES Monthly FE Inspection - Refer to
PM schedule details.

Margret Villalobos

130788 4/5/2015 5/6/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:29:12 AM

Escobar, David Yearly - Anthony ES A13 (AC Wall Mount)(Yearly) -
Refer to PM schedule details.

Margret Villalobos

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Anthony ES							
130313					3/18/2015		28		\$0.00
Medium	Work In Progress				3/18/2015 1:47:15 PM				
Escobar, David		Jessica, Mr. Escobar, As per Ms. Perez please lower 2 of the swings in the kinder playground.							
Jessica Lopez									
130803					4/5/2015	5/6/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:20 AM				
Escobar, David		Monthly - Anthony ES A16 (Fan Exhst.)(Semi. Ann.) - Refer to PM schedule details.							
Margret Villalobos									
129429					2/28/2015	3/31/2015	46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:42 AM				
Escobar, David		Yearly - Anthony ES C-11 (Evap.Down)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
126873					1/4/2015	1/12/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:40:12 AM				
Escobar, David		Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
130873					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:56 AM				
Escobar, David		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
131267					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 12:26:49 AM				
Escobar, David		Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details.							
Margret Villalobos									
131379					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 11:31:17 AM				
Escobar, David		04/14/2015. replace several T8 light bulbs in room 310.							
David Escobar									
4/15/2015 3:50:34 PM									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

131286 4/13/2015 2 \$0.00

Medium Work In Progress 4/13/2015 10:11:45 AM

Escobar, David As per Mrs. Mason,
Please transport and set up mesh art display at
Gadsden Middle School on Thursday 23, 2015 and
please take down load and transport display back to
Anthony Elementary on Monday April 27, 2015 by 11
AM

Jessica Lopez

130952 4/5/2015 4/11/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:30:40 AM

Escobar, David Monthly - Anthony ES Monthly FE Inspection - Refer to
PM schedule details.

Margret Villalobos

130693 3/29/2015 17 \$0.00

Medium Work In Progress 3/29/2015 12:21:48 AM

Escobar, David Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM
schedule details.

Margret Villalobos

130729 3/31/2015 5/1/2015 15 \$0.00

Medium Work In Progress 3/31/2015 12:38:03 AM

Escobar, David Yearly - Anthony ES A8(Rooftop Unit)(Yearly) - Refer to
PM schedule details.

Margret Villalobos

130731 3/31/2015 15 \$0.00

Medium Work In Progress 3/31/2015 12:38:05 AM

Escobar, David Yearly - Anthony ES A6 (Rooftop Unit)(Yearly) - Refer to
PM schedule details.

Margret Villalobos

131234 4/12/2015 4/28/2015 3 \$0.00

Medium Work In Progress 4/12/2015 12:23:36 AM

Vega, David Monthly - QRTL BLDG INSP REPORT (AE) - Refer to
PM schedule details.

Margret Villalobos

129478 3/1/2015 45 \$0.00

Medium Work In Progress 3/1/2015 12:45:45 AM

Escobar, David Yearly - Anthony ES A10(Heat Pumps)(Yearly) - Refer
to PM schedule details.

Margret Villalobos

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
129479					3/1/2015	4/1/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:45:46 AM				
Escobar, David		Yearly - Anthony ES R3 (Ref. Unit)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
129974					3/9/2015		37		\$0.00
Medium	Work In Progress				3/9/2015 4:09:59 PM				
Escobar, David		need to replace 1/2 inch water supplyline and 1/4 inch lines to coolers in Alamo building and off cafeteria.							
David Escobar									
129767					3/4/2015		42		\$0.00
Medium	Work In Progress	DIAGNOSTICIA			3/4/2015 10:44:33 AM				
Escobar, David		INSTALL WALL CABINETS IN DIAGNOSTICIAN ROOM SEE MARGARET FOR CABINETS							
Margaret Villalobos									
130819					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:28 AM				
Escobar, David		Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
123059					9/23/2014		204		\$0.00
Medium	Work In Progress				9/23/2014 10:30:35 AM				
Marquez, Gerardo		KEEYS LOCKED IN SNP VEHICLE 132.							
Maritza Gonzalez									
130613					3/26/2015		20		\$0.00
Medium	Work In Progress	office			3/26/2015 9:21:43 AM				
Marquez, Gerardo		Extra key needed for our alarm box thank you							
Jessica Lopez									
128486					2/4/2015		70		\$0.00
Medium	Work In Progress				2/4/2015 3:46:09 PM				
Marquez, Gerardo		BMneeds 10 bathroom stall latches . need to replace missing and broken ones.							
David Escobar									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
130456					3/23/2015		23		\$0.00
Medium	Work In Progress				3/23/2015 9:57:06 AM				
Sotelo, Enrique		Power Outage at the Alamo Building							
Alfredo Holguin									
129782					3/4/2015		42		\$0.00
Medium	Work In Progress	SPED OFFICE			3/4/2015 3:25:14 PM				
Sotelo, Enrique		REPLACE LIGHT BULB IN VAULT IN CHILDFIND OFFICE (SEE MARGARET)							
Margaret Villalobos									
131073					4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 4:10:10 PM				
Carrasco, Danny		Broken male hose connector on Electric pump sprayer. need replacement asap.							
David Escobar									
131373					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 10:16:33 AM				
Orozco, Daniel		BUFFALO CHOPPER BLADES STUCK. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									
128740					2/10/2015		64		\$0.00
Medium	Work In Progress				2/10/2015 2:51:21 PM				
Orozco, Daniel		AS PER ADELE INSPECTION REPORT- CAN OPENER DOES NOT WORK CORRECTLY . HARD TO OPEN.							
Maritza Gonzalez									
121438					8/19/2014		239		\$0.00
Medium	Work In Progress				8/19/2014 2:55:31 PM				
Orozco, Daniel		EXHAUST FAN SWITCH IS NOT WORKING AGAIN. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									
121439					8/19/2014		239		\$0.00
Medium	Work In Progress				8/19/2014 2:56:27 PM				
Orozco, Daniel		NEED METAL COVERS FOR FAN INSIDE WALK IN REFRIGERATOR, SAFETY HAZARD. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
121985					8/29/2014		229		\$0.00
Medium	Work In Progress				8/29/2014 3:13:57 PM				
Orozco, Daniel		THERE IS A LEAK ON SPRAYER HOSE. SNP							
Maritza Gonzalez		MANAGER BECKY S. 882.3507							
121986					8/29/2014		229		\$0.00
Medium	Work In Progress				8/29/2014 3:14:16 PM				
Orozco, Daniel		SERVING LINE CLOGGED. SNP MANAGER BECKY							
Maritza Gonzalez		S. 882.3507							
123057					9/23/2014		204		\$0.00
Medium	Work In Progress				9/23/2014 9:58:08 AM				
Orozco, Daniel		PRONG TO SLICER STAYED STUCK IN OUTLET.							
Maritza Gonzalez		SNP MANAGER BECKY S. 882.3507							
129343					2/26/2015		48		\$0.00
Medium	Work In Progress				2/26/2015 10:55:35 AM				
Flores, Pete		need weed eater fixed trigger is broken							
David Vega		serial#285195352							
130655					3/27/2015		19		\$0.00
Medium	Work In Progress	401			3/27/2015 9:42:43 AM				
Villalobos, Margret		Please check room # 401 teacher is having trouble							
Jessica Lopez		opening the door							
		thank you							
126975					1/4/2015		101		\$0.00
Medium	Work In Progress				1/4/2015 12:41:35 AM				
Munoz, Michael		Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to							
Margret Villalobos		PM schedule details.							
120333					8/3/2014		255		\$0.00
Medium	Work In Progress				8/3/2014 12:33:36 AM				
Munoz, Michael		Yearly - Anthony ES Fire Ext. Insp. (Yearly) - Refer to				PM not completed as per schedule			
Margret Villalobos		PM schedule details.							

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
129443					2/28/2015		46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:52 AM				
Munoz, Michael		Yearly - Anthony ES - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
130851					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:45 AM				
Villalobos, Margret		Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details.							
Margret Villalobos									
130838					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:39 AM				
Munoz, Michael		Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
130749					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:15 AM				
Apodaca, Mario		Monthly - Anthony ES - Monthly Meter Readings - Refer to PM schedule details.							
Margret Villalobos									
130423					3/20/2015		26		\$0.00
Medium	Work In Progress				3/20/2015 1:13:25 PM				
Carbajal, Jimmy		vacuum cleaner serial #5381 through dirt out between two housings							
David Vega									
131047					4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 12:59:23 PM				
Carbajal, Jimmy		repair wet n dry vac supersuction nss hose is broken							
David Vega									
129065					2/19/2015		55		\$0.00
Medium	Work In Progress				2/19/2015 8:54:24 AM				
Marquez, Gerardo		replace broken door latch due to vandelizm							
David Vega									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
131416					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 4:20:59 PM				
Solis, Lorenzo		04/14/2015. replace supply and return flexlines at heat coil in Alamo directors office.							
David Escobar									
131363					4/13/2015		2		\$0.00
Medium	Work In Progress				4/14/2015 9:00:43 AM				
Solis, Lorenzo		Room 401 - Unit has a diagnostic, needs to be reset manually. - informed Lorenzo							
David Vega									
120712					8/7/2014		251		\$0.00
Medium	Work In Progress				8/7/2014 12:12:51 PM				
Gonzalez, Salvador		Sal we need to build a ladder rack for the gater as per Mike thanks							
Daniel Sotelo									
Count: 57 Work Orders			Avg. Age of WO's 51		Total for Anthony ES			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
128758					2/10/2015		64		\$0.00
Medium	Work In Progress			2/10/2015 3:45:29 PM					
Gonzalez, Salvador	MR SAL GONZLES SIR HAVE TWO MORE BENCHES THAT NEED TO BE REPAIR AND WELDED AND REINSTALLED THANK YOU SIR AND GOD BLESS								
Adan Duran									
129623					3/2/2015		44		\$0.00
Medium	Work In Progress			3/2/2015 10:01:45 AM					
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR CAN YOU PLEASE CHECK SPRINKLER SYSTEM ALARM CAME ON STATION 15-16-17 NOT COMING ON NEED TO START WATERING THANK YOU SIR AND GOD BLESS								
Adan Duran									
130129					3/13/2015		33		\$0.00
Medium	Work In Progress			3/13/2015 11:01:03 AM					
Ontiveros, Guadalupe	MR ALFREDO HOLGUIN SIR THE GATES HAVE BEEN INSTALL BETWEEN BERINO AND DESERT PRIDE NOW WE NEED TO INSTALL SIDEWALK THANK YOU SIR AND GOD BLESS								
Adan Duran									
130750					3/31/2015		15		\$0.00
Medium	Work In Progress			3/31/2015 12:38:15 AM					
Apodaca, Mario	Monthly - Berino ES - Monthly Meter Readings - Refer to PMschedule details.								
Margret Villalobos									
128332					2/2/2015		72		\$0.00
Medium	Work In Progress			2/2/2015 9:30:43 AM					
Solis, Lorenzø	MR LORENZO SOLIS SIR DESERT PRIDE PORTABLE NOT WORKING PROPERLY NEED TO CHECK THANK YOU SIR AND GOD BLESS								
Adan Duran									
131245					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress			4/12/2015 12:23:42 AM					
Herrera, Marin	Monthly - QRTLY BLDG INSP REPORTS (BE) - Refer to PMschedule details.								
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Berino ES									
130832					4/5/2015	4/26/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:36 AM				
Munoz, Michael		Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
129444					2/28/2015		46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:53 AM				
Munoz, Michael		Yearly - Berino ES - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
118857					7/1/2014		288		\$0.00
High	Work In Progress				7/1/2014 9:56:44 AM				
Munoz, Michael		need to install new water gong fire bell. district electrician will provide power.							
Michael Munoz									
126969					1/4/2015	1/25/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:41:30 AM				
Munoz, Michael		Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
130970					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:50 AM				
Villalobos, Margret		Monthly - Berino ES - Enviro Controls Quarterly - Refer to PM schedule details.							
Margret Villalobos									
130134					3/13/2015		33		\$0.00
Medium	Work In Progress				3/13/2015 12:56:51 PM				
Sanchez, Raul		MR RUAL SANCHEZ SIR NEED TO REPLACE WATER FILTERS FOR MAIN BUILDING WATER TURNING BROWN THANK YOU SIR AND GOD BLESS							
Adan Duran									
128857					2/12/2015		62		\$0.00
Medium	Work In Progress				2/12/2015 3:02:03 PM				
Orozco, Daniel		AS PER ADELES INSPECTION - OVENS ARE NOT HEATING PROPERLY.							
Maritza Gonzalez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: Berino ES										
126424					12/9/2014		127		\$0.00	
Medium	Work In Progress			12/9/2014 3:42:21 PM						
Orozco, Daniel	WARMER IS NOT HEATING. SNP MANAGER ELSA C. 882.2417									
Maritza Gonzalez										
129158					2/23/2015		51		\$0.00	
Medium	Work In Progress			2/23/2015 11:24:40 AM						
Sotelo, Enrique	MR ENRIQUE SOTELO SIR HAVE BURN OUT EMERGENCY LIGHT MIDDLE WING NORTH SIDE MEN REST ROOM NEED TO REPLACE TO REPLACE THANK YOU SIR AND GOD BLESS									
Adan Duran										
130491		Athletic Field			3/23/2015		23		\$0.00	
High	Work In Progress			3/23/2015 4:11:35 PM						
Sotelo, Enrique	line locate for any power lines between berino and alta vista. Mr. Adan will show area.									
Guadalupe Ontiveros										
120112					7/31/2014		258		\$0.00	
Medium	Work In Progress			7/31/2014 2:44:15 PM						
Sotelo, Enrique	MR ENRIQUE SOTELO SIR BREAKER ON AC UNIT ROOMS 105 AND 107 NEEDS TO BE REPLACE IT HAS A 20 AMP AND THE UNIT CALLS FOR A 25 AMP THANK YOU SIR AND GOD BLESS									
Adan Duran										
130490		Athletic Field			3/23/2015		23		\$0.00	
High	Work In Progress			3/23/2015 4:08:25 PM						
Villalobos, David	line locate between berino and alta vista. sidewalk to be install. Mr. adan could show area.									
Guadalupe Ontiveros										
130814					4/5/2015		10		\$0.00	
Medium	Work In Progress			4/5/2015 12:29:26 AM						
Holguin, Alfredo	Monthly - Berino ES - Fire Pump Engine - Refer to PM schedule details.									
Margret Villalobos										
131251					4/12/2015	4/28/2015	3		\$0.00	
Medium	Work In Progress			4/12/2015 12:23:46 AM						
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.									
Margret Villalobos										
Count: 20 Work Orders			Avg. Age of WO's	64				Total for Berino ES	0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral ES							
130022					3/11/2015		35		\$0.00
Medium	Work In Progress				3/11/2015 9:00:51 AM				
Vallejo, Albert		requesting 2 pin compact fluorescent lamps pl-c26w philips							
Paul Quinones									
130023					3/11/2015		35		\$0.00
Medium	Work In Progress				3/11/2015 9:11:37 AM				
Vallejo, Albert		requesting L E D EMERGENCY LIGHT type. requesting 12 thanks							
Paul Quinones									
131346					4/14/2015		1		\$0.00
Medium	Work In Progress	DOROTHY			4/14/2015 7:46:27 AM				
Gonzales, Camilo		DELIVER PO 141506418 ORIENTAL TRADING 1 BOX DOROTHY SANG, TEACHER							
Margaret Villalobos									
131354					4/14/2015		1		\$0.00
Medium	Work In Progress	DOROTHY			4/14/2015 8:01:48 AM				
Gonzales, Camilo		DELIVER PO 141506414 LAKESHORE LEARNING 1 BOX DOROTHY SANG, TEACHER							
Margaret Villalobos									
126885					1/4/2015	2/4/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:40:22 AM				
Villalobos, David		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
131233					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:36 AM				
Ramirez, Daniel		Monthly - QRTLY BLDG INSP REPORT (CE) - Refer to PM schedule details.							
Margret Villalobos									
123783					10/7/2014		190		\$0.00
Medium	Work In Progress				10/7/2014 8:55:51 AM				
Orozco, Daniel		DISHWASHER IS LEAKING. SNP MANAGER ESTHER C. 824.0048							
Maritza Gonzalez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
124735					10/29/2014		168		\$0.00
Medium	Work In Progress				10/29/2014 12:28:02				
Orozco, Daniel		BROKEN GASKETS ON FREEZER AND WARMER. SNP MANAGER ESTHER C. 824.0048							
Maritza Gonzalez									
129064					2/19/2015		55		\$0.00
Medium	Work In Progress				2/19/2015 8:45:50 AM				
Orozco, Daniel		AS PER ADELE INSPECTION REPORT. SEAL ON WARMER TORN AND LOOSE.							
Maritza Gonzalez									
127588					1/15/2015		90		\$0.00
Medium	Work In Progress				1/15/2015 12:32:10 PM				
Marquez, Gerardo		cafeteria double doors on the west side of cafeteria core fell off and lost. need a new core							
Paul Quinones									
125569					11/14/2014		152		\$0.00
Medium	Work In Progress				11/14/2014 1:07:06 PM				
Marquez, Gerardo		double doors located on the west side of building next to cafeteria doors are hard to open with key.							
Paul Quinones									
122854	West Central	Classroom			9/16/2014		211		\$0.00
Medium	Work In Progress	402			9/16/2014 3:28:45 PM				
Marquez, Gerardo		Lost key and need as soon as possible. Wrote a letter to secretary. See Ms. Jackson							
Jennifer Corral									
131221					4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 3:51:44 PM				
Lara, Ralph		portable 6 and 7 custodial staff having a hard time opening and closing entrance door with issued keys							
Paul Quinones									
131265					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:53 AM				
Quinones, Paul		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
131362					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 8:53:20 AM				
Quinones, Paul		reorder motor belts for evap.coolers							
Paul Quinones									
130956					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:42 AM				
Quinones, Paul		Monthly - Chaparral ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
130967					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:49 AM				
Quinones, Paul		Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
130446					3/23/2015		23		\$0.00
Medium	Work In Progress				3/23/2015 7:54:43 AM				
Quinones, Paul		Old Wastewater Treatment Plant Area - Cut and remove weeds							
Alfredo Holguin									
130929					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:28 AM				
Quinones, Paul		Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
130930					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:28 AM				
Quinones, Paul		Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
131439					4/15/2015		0		\$0.00
Medium	Work In Progress				4/15/2015 1:29:01 PM				
Quinones, Paul		need keytype electric switches for rest rooms @ chm.							
Paul Quinones									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
128334					2/2/2015		72		\$0.00
Medium	Work In Progress				2/2/2015 9:35:39 AM				
Quinones, Paul		repipe pvc water lines for the air conditioners in the e-wing, and the 400 wing.							
Paul Quinones									
128900					2/13/2015		61		\$0.00
Medium	Work In Progress				2/13/2015 11:49:44 AM				
Quinones, Paul		reorder mastercool media celdeck pads to replace the ones that need to be replaced on the existing coolers							
Paul Quinones									
129439					2/28/2015	3/31/2015	46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:49 AM				
Quinones, Paul		Yearly - Chaparral ES C-11 Evap (Annual) - Refer to PM schedule details.							
Margret Villalobos									
130783					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:09 AM				
Quinones, Paul		Yearly - Chaparral ES A-13 A/C Wall Mount Yearly - Refer to PM schedule details.							
Margret Villalobos									
130338					3/18/2015		28		\$0.00
Medium	Work In Progress				3/18/2015 4:06:44 PM				
Quinones, Paul		there is a water leak in room 402. Silver has replaced the heat detector several times because it is rusted. Please check and if you have questions please call Silver							
Cora Ramirez									
130264					3/17/2015		29		\$0.00
Medium	Work In Progress				3/17/2015 2:18:13 PM				
Quinones, Paul		need to replace metal partitions in boys rest rm. wing 100							
Paul Quinones									
130846					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:43 AM				
Quinones, Paul		Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
129868					3/6/2015		40		\$0.00
Medium	Work In Progress				3/6/2015 10:01:25 AM				
Quinones, Paul		need to replace exhaust fans in portable bathrooms							
Paul Quinones									
129923					3/9/2015	3/24/2015	37		\$0.00
Medium	Work In Progress				3/9/2015 12:35:49 AM				
Quinones, Paul		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
121424	Main Building	Office			8/19/2014		239		\$0.00
Medium	Work In Progress	concession			8/19/2014 1:31:30 PM				
Quinones, Paul		need changing table moved from Chaparral Elementary to GSAC room 109 to Ms. Ruiz. See front office or Mrs. Pargas							
Jennifer Corral									
128701					2/9/2015		65		\$0.00
Medium	Work In Progress				2/9/2015 4:07:26 PM				
Flores, Pete		please check the brakes to work truck #123							
Paul Quinones									
131438					4/15/2015		0		\$0.00
Medium	Work In Progress				4/15/2015 1:27:13 PM				
Solis, Lorenz		coolers need to be replaced 3]6500 side draft,and 1] 4500 down draft master cools.							
Paul Quinones									
130457		Custodial			3/23/2015		23		\$0.00
Medium	Work In Progress				3/23/2015 9:57:55 AM				
Carbajal, Jimmy		fix,handle,on,vaccum.e,98,oooo2778.							
Daniel Ramirez									
130458		Custodial			3/23/2015		23		\$0.00
Medium	Work In Progress				3/23/2015 10:07:04 AM				
Carbajal, Jimmy		fix,vaccum,electrical,cord.eoogoooo4090.							
Daniel Ramirez									
Count: 35 Work Orders			Avg. Age of WO's 51		Total for Chaparral ES			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral High - Pre-K									
120159					8/1/2014		257		\$0.00
Medium	Work In Progress	building back			8/1/2014 8:03:09 AM				
Marquez, Gerardo		Repair the back entrance door to the Pre-k Center the handle is broken and having trouble locking and unlocking the door.							
Noemi Duron									
130045					3/11/2015		35		\$0.00
Medium	Work In Progress				3/11/2015 3:30:22 PM				
Marquez, Gerardo		Gerry - Please get a quote: The NM Mexico Pre-K Department has responded to the situation at Chaparral Pre-K with a suggestion to split the bathroom doors into a "Dutch Door" as we have in the Anthony Pre-K.							
Jeanne Fields									
Alfredo Holguin									
130303					3/18/2015		28		\$0.00
Medium	Work In Progress	Outside			3/18/2015 9:55:00 AM				
Valdez, Pedro		Sprayweeds all around building and set up stake to straighten one of the pine trees.							
Micaela Paniagua									
130471		Exterior			3/23/2015		23		\$0.00
Medium	Work In Progress				3/23/2015 3:13:09 PM				
Ortiz, Alfredo		At Pre-K need to unclog outside water fountain.							
Alfredo Ortiz									
131078		Office			4/8/2015		7		\$0.00
Medium	Work In Progress				4/8/2015 7:59:33 AM				
Ronquillo, Ruben		Atencion to Ruben warehouse Need to order sign for Pre-K For security reasons all doors are locked. Please ring door bell for assistance. Thank you. Its also written in spanish.							
Alfredo Ortiz									
Count: 5 Work Orders		Avg. Age of WO's 70			Total for Chaparral High - Pre-K			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

129153 2/23/2015 51 \$0.00

Medium Work In Progress 2/23/2015 9:47:36 AM

Ronquillo, Ruben Cost to repair bleachers as per quote from AK Sales

Alfredo Holguin

130244 A-Wing Exterior 3/17/2015 29 \$0.00

Medium Work In Progress 3/17/2015 9:16:01 AM

Ronquillo, Ruben Attention to Ruben Warehouse Need to send glass company to replace broken window on Cafeteria door
23 1/2 in. X 22 1/2 in. smoked double pain.

Alfredo Ortiz

128785 Field House Storage 2/11/2015 63 \$0.00

Medium Work In Progress 2/11/2015 12:32:14 PM

Gonzalez, Salvador Need welder to fabricate four angle to support a pole to hang football jerseys in football storage room.

Alfredo Ortiz

128862 Exterior 2/12/2015 62 \$0.00

Medium Work In Progress 2/12/2015 3:22:48 PM

Ortiz, Alfredo Need to order and replace A/C pads Mastercool.

Alfredo Ortiz

129765 F-Wing Restroom (Girls) 3/4/2015 42 \$0.00

Medium Work In Progress 3/4/2015 10:36:20 AM

Ortiz, Alfredo Need to replace two flush valves in F-wing restrooms.

Alfredo Ortiz

130686 G-Wing Storage 3/27/2015 19 \$0.00

Medium Work In Progress 3/27/2015 3:48:08 PM

Ortiz, Alfredo Need to build two shelves with poles to hang uniforms.

Alfredo Ortiz

130734 3/31/2015 15 \$0.00

Medium Work In Progress 3/31/2015 12:38:06 AM

Ortiz, Alfredo Monthly - Chaparral HS A16 (Fan Exhst.)(S.Annual) - Refer to PM schedule details.

Margret Villalobos

130695 3/29/2015 17 \$0.00

Medium Work In Progress 3/29/2015 12:21:49 AM

Ortiz, Alfredo Daily - Chaparral HS - Fire Pump (Biweekly) - Refer to PM schedule details.

Margret Villalobos

4/15/2015 3:50:35 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
130968					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:49 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
130966					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:48 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
130897					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:11 AM				
Ortiz, Alfredo		Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
131269					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 12:26:50 AM				
Ortiz, Alfredo		Daily - Chaparral HS - Fire Pump (Biweekly) - Refer to PMschedule details.							
Margret Villalobos									
130654		Restroom			3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 9:11:07 AM				
Ortiz, Alfredo		Need to paint over graffitti to in the boys restrooms and hallways.							
Alfredo Ortiz									
129879		Hallway/Corridor			3/6/2015		40		\$0.00
Medium	Work In Progress				3/6/2015 1:26:15 PM				
Ortiz, Alfredo		Need to clean strainers on Geo thermal water lines on each heating and cooling units.							
Alfredo Ortiz									
131208	F-Wing	Hallway/Corridor			4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 3:04:54 PM				
Ortiz, Alfredo		Need to build a stand made out of PVC.for a classroom.							
Alfredo Ortiz									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
130189	B-Wing	Classroom			3/16/2015		30		\$0.00
Medium	Work In Progress				3/16/2015 12:17:22 PM				
Ortiz, Alfredo		Need to replace several lights bulbs in B-wing classrooms burned out bulbs.							
Alfredo Ortiz									
129477					3/1/2015		45		\$0.00
Medium	Work In Progress				3/1/2015 12:45:45 AM				
Ortiz, Alfredo		Yearly - Chaparral HS A10 (Heat Pump)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
130899					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:12 AM				
Ortiz, Alfredo		Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130900					4/5/2015	5/6/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:12 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
130817					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:27 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
130807					4/5/2015	4/26/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:22 AM				
Ortiz, Alfredo		Monthly - Chaparral HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
130259					3/17/2015		29		\$0.00
Medium	Work In Progress				3/17/2015 1:30:54 PM				
Ortiz, Alfredo		Need to order screws, blabk covers, door stoppers and other supply from grainger							
Alfredo Ortiz									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

130811 4/5/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:29:24 AM

Holguin, Alfredo Monthly - Chaparral HS - Fire Pump Engine - Refer to PM schedule details.

Margret Villalobos

131389 Office 4/14/2015 1 \$0.00

Medium Work In Progress 4/14/2015 3:05:30 PM

Gonzales, Camilo Deliver 4 boxes, PO# 141506763. Thank you.

Theresa Ramirez

128971 2/17/2015 57 \$0.00

Medium Work In Progress 2/17/2015 3:24:15 PM

Vallejo, Albert Electrical power source at each dugouts. (Baseball & Softball Fields)

Terry Alvarado

121794 Field House Dressing Room 8/26/2014 232 \$0.00

Medium Work In Progress 8/26/2014 3:03:15 PM

Vallejo, Albert do not have power to exauhst fans will not start.

Alfredo Ortiz

119549 Field House Restroom 7/17/2014 272 \$0.00

Medium Work In Progress 7/17/2014 3:54:07 PM

Vallejo, Albert Need to replace several light switches in Field house restrooms and waight room.

Alfredo Ortiz

121594 B-Wing Classroom 8/21/2014 237 \$0.00

Medium Work In Progress 8/21/2014 3:32:10 PM

Vallejo, Albert Need to install new wall outlet in B-2 classroom.

Alfredo Ortiz

131083 Field House 4/8/2015 7 \$0.00

Medium Work In Progress 4/8/2015 8:47:09 AM

Vallejo, Albert Booster Pump for Irrigation System - breaker trips overnight and sprinklers are not working properly.

Alfredo Holguin

122910 Football Field 9/17/2014 210 \$0.00

Medium Work In Progress 9/17/2014 12:08:33 PM

Vallejo, Albert Need to run electricity from press-box to front of Bleachers at football field.

Alfredo Ortiz

4/15/2015 3:50:35 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
131200		Office			4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 1:52:05 PM				
Gonzales, Camilo		Deliver 1 box. PO# 141506275. Attn: Mark Rupcich.							
Theresa Ramirez									
126906					1/4/2015	2/4/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:40:38 AM				
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
125112	H-Wing	Gym			11/3/2014		163		\$0.00
Medium	Work In Progress				11/3/2014 3:47:28 PM				
Marquez, Gerardo		Need to make keys for Amplifier box in Gym.							
Alfredo Ortiz									
123083	A-Wing	Library			9/23/2014		204		\$0.00
Medium	Work In Progress	Library			9/23/2014 3:15:03 PM				
Marquez, Gerardo		Please unbolt 2 library shelf units from the wall so they can be moved away from water leaking into library. (Ms. DeVine, library)							
Mireya Meza									
130764	F-Wing	Hallway/Corridor			3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 11:56:10 AM				
Marquez, Gerardo		Door in Fwing cyber cafe won't stay unlocked.							
Alfredo Ortiz									
130575	D-Wing	Hallway/Corridor			3/25/2015		21		\$0.00
Medium	Work In Progress				3/25/2015 12:00:32 PM				
Marquez, Gerardo		Need to replace door closer. Broken.							
Alfredo Ortiz									
130661	A-Wing	Hallway/Corridor			3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 12:31:39 PM				
Marquez, Gerardo		The double door between A and G-Wing do not lock need for it to lock during lunch.							
Alfredo Ortiz									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

130375	A-Wing	Office			3/19/2015		27		\$0.00
--------	--------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Nurse			3/19/2015 12:32:33 PM				
--------	------------------	-------	--	--	-----------------------	--	--	--	--

Marquez, Gerardo
 One of the fireproof file cabinets in the nurse office was removed (a key had broken off in the lock) I would like to know if the lock can be replaced so the cabinet may be locked. (it doesn't have to be originals type of mechanism, just so long as there is a working lock on the cabinet). Ms. de Castro, nurse

Mireya Meza

130190	Field House	Athletic Field			3/16/2015		30		\$0.00
--------	-------------	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/16/2015 12:21:59 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo
 Need for lock smith install locks and chains on all gates on football field also need to be welded.

Alfredo Ortiz

121690	Field House	Athletic Field			8/25/2014		233		\$0.00
--------	-------------	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Baseball shed			8/25/2014 10:20:10 AM				
--------	------------------	---------------	--	--	-----------------------	--	--	--	--

Marquez, Gerardo
 Requesting a metal door with knob & dead bolt locking system to secure inventory of equipment in baseball shed. Please see Gregg Martinez for pictures and report. (Mr. Martinez, baseball shed)

Mireya Meza

125513	A-Wing				11/13/2014		153		\$0.00
--------	--------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2014 12:07:33				
--------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo
 At nurses office key broken in cabinet.

Alfredo Ortiz

123340					9/29/2014		198		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/29/2014 8:09:29 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo
 We will need to add door openers to 4 doors:

1. The east exit door by the wall on Wing E.
2. The west exit door by the wall on Wing F.
3. The east exit doors (2 doors – one into the foyer and one into the building) by the wall on Wing R.

Alfredo Holguin

126794	E-Wing	Classroom			12/19/2014		117		\$0.00
--------	--------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	E7			12/19/2014 9:43:19 AM				
--------	------------------	----	--	--	-----------------------	--	--	--	--

Appelzoller, Fred
 Please install gas jets in room E7. It is a chemistry room without gas jets. (Ms. Gonzalez, E7)

Mireya Meza

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
125746	R-Wing	Classroom			11/19/2014		147		\$0.00
Medium	Work In Progress				11/19/2014 11:02:22				
Appelzoller, Fred		In art classroom Q-Build. Needs new water line and run drain-pipes for a indoor power washer.							
Alfredo Ortiz									
126411	H-Wing	Gym			12/9/2014		127		\$0.00
Medium	Work In Progress				12/9/2014 11:49:08 AM				
Appelzoller, Fred		No water pressure on cold side floor sink in Gym custodians closet.							
Alfredo Ortiz									
131070	H-Wing	Gym			4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 4:05:57 PM				
Appelzoller, Fred		Gym restrooms craked need to be replaced.							
Alfredo Ortiz									
131069	Field House	Restroom			4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 4:03:48 PM				
Appelzoller, Fred		Need to replace toilets in G-wing restroom broken.							
Alfredo Ortiz									
128848	R-Wing	Classroom			2/12/2015		62		\$0.00
Medium	Work In Progress	R3			2/12/2015 12:37:28 PM				
Appelzoller, Fred		Sinks in room drain slowly. Partially clogged. (Mr. Soria, R3)							
Mireya Meza									
128970					2/17/2015		57		\$0.00
Medium	Work In Progress				2/17/2015 3:22:54 PM				
Appelzoller, Fred		Water fountains (they will accommodate both the Baseball & Softball programs)							
Terry Alvarado									
126140	A-Wing	Kitchen			12/3/2014		133		\$0.00
Medium	Work In Progress				12/3/2014 7:41:36 AM				
Appelzoller, Fred		A hot water circulating pump for the Kitchen not working. Need to be replaced.				3/18/15 - Asp Mr. Holguin, route to Plumber, he will check on cir pumps and purchase.			
Alfredo Ortiz									
129032	H-Wing	Dressing Room			2/18/2015		56		\$0.00
Medium	Work In Progress				2/18/2015 2:13:05 PM				
Appelzoller, Fred		Need to replace broken toilet in girls locker room.							
Alfredo Ortiz									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
128357	G-Wing	Restroom			2/2/2015		72		\$0.00
Medium	Work In Progress				2/2/2015 3:49:59 PM				
Appelzoller, Fred		Need to replace broken toilet in G-wing boys restroom.							
Alfredo Ortiz									
128773		Custodial			2/11/2015		63		\$0.00
Medium	Work In Progress				2/11/2015 8:07:13 AM				
Appelzoller, Fred		Need to replace circulating water pump burned out.							
Alfredo Ortiz									
125053		Athletic Field			11/3/2014		163		\$0.00
Medium	Work In Progress				11/3/2014 7:35:53 AM				
Valdez, Pedro		Need to fix baseball bleachers bent and broken.							
Alfredo Ortiz									
119906	Field House	Athletic Field			7/28/2014		261		\$0.00
Medium	Work In Progress	Main Soccer			7/28/2014 11:42:35 AM				
Valdez, Pedro		We are needing the main grass soccer field lined for this Thursday July 31, 2014. We are having an inter squad scrimmage that evening. (Coach Mendoza)							
Mireya Meza									
131248					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:44 AM				
Urquidi, Jesus		Monthly - QRTLY BLDG INSP REPORT (CH) - Refer to PM schedule details.							
Margret Villalobos									
130087		Football Field			3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 10:22:10 AM				
Valdez, Pedro		Running Track - There is grass and weeds growing on the inside and outside perimeter of the running track- Apply roundup herbicide							
Alfredo Holguin									
128279					2/1/2015		73		\$0.00
Medium	Work In Progress				2/1/2015 12:50:37 AM				
Flores, Pete		Monthly - CHS-UV-0513 PM Service - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

126517 B-Wing Hallway/Corridor 12/11/2014 125 \$0.00

Medium Work In Progress 12/11/2014 10:11:40

Solis, Lorenzo In cybor cafe Bad odor coming from heating vents.

Alfredo Ortiz

127914 A-Wing Library 1/26/2015 79 \$0.00

Medium Work In Progress 1/26/2015 11:07:29 AM

Solis, Lorenzo Need to replace circuit board on unit burn out.

Alfredo Ortiz

130595 Q-Wing Classroom 3/25/2015 21 \$0.00

Medium Work In Progress 3/25/2015 3:48:42 PM

Solis, Lorenzo Need to replace two burn-out compressors in Q-7.

Alfredo Ortiz

130513 G-Wing Classroom 3/24/2015 22 \$0.00

Medium Work In Progress G5 3/24/2015 12:29:28 PM

Solis, Lorenzo It is too hot in here. Please help. (Mr. Sanchez, G5)

Mireya Meza

129588 3/1/2015 45 \$0.00

Medium Work In Progress 3/1/2015 12:46:50 AM

Apodaca, Mario Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.

Margret Villalobos

130839 4/5/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:29:39 AM

Munoz, Michael Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

130842 4/5/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:29:41 AM

Munoz, Michael Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PM schedule details.

Margret Villalobos

130939 4/5/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:30:33 AM

Apodaca, Mario Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.

Margret Villalobos

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
126976					1/4/2015		101		\$0.00
Medium	Work In Progress				1/4/2015 12:41:36 AM				
Munoz, Michael		Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
126979					1/4/2015		101		\$0.00
Medium	Work In Progress				1/4/2015 12:41:38 AM				
Munoz, Michael		Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PM schedule details.							
Margret Villalobos									
129445					2/28/2015		46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:53 AM				
Munoz, Michael		Yearly - Chaparral HS - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
124515	B-Wing	Storage			10/23/2014		174		\$0.00
Medium	Work In Progress				10/23/2014 1:39:32 PM				
Marquez, Gerardo		Need to replace key Cilinder on door, teachers can't open door.							
Alfredo Ortiz									
124831	A-Wing	Office			10/31/2014		166		\$0.00
Medium	Work In Progress	Nurse office			10/31/2014 9:23:18 AM				
Marquez, Gerardo		Key for one of the nurse's filing cabinet broke off. Please replace. (Fireking, Medeco, #238) (Ms. de Castro, Nurse)							
Mireya Meza									
124236	A-Wing	Office			10/16/2014		181		\$0.00
Medium	Work In Progress	Front reception			10/16/2014 10:22:52				
Marquez, Gerardo		The left side door right in front of the reception desk is not locking properly. (Mireya Meza)							
Mireya Meza									
130183					3/16/2015		30		\$0.00
Medium	Work In Progress				3/16/2015 8:59:52 AM				
Ontiveros, Guadalupe		Outside Basketball Courts. Missing valve box cover and broken concrete please replace.							
Alfredo Holguin									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
131290					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 11:14:06 AM				
Carbajal, Jimmy		wet an dryvac does not work sr sn18wd-06096							
Jesus Urquidi									
130990		Gym			4/6/2015		9		\$0.00
Medium	Work In Progress				4/6/2015 11:31:40 AM				
Estrada, Jesus		varnish gym floor							
Jesus Estrada									
Count: 75 Work Orders		Avg. Age of WO's 70		Total for Chaparral HS		0		\$0.00	

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
130998		Gym			4/6/2015		9		\$0.00
Medium	Work In Progress				4/6/2015 11:44:54 AM				
Estrada, Jesus		1) Sand down floor 2) Repaint volleyball and basketball lines (same color as we have now) 3) Repaint mascot (same as we have now) 4) Varnish gym floor							
Jesus Estrada									
131412					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 4:01:54 PM				
Solis, Lorenz		Need (6) 6500 A/c's and (2) 4500 A/c's for Chaparral Middle school main building. (Downdraft)							
Johnny Acuna									
130501		Custodial			3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 9:25:03 AM				
Carbajal, Jimmy		senesecita arreglar maquina de labar alfombra tira agua par abago GRACIAS							
M. Carmen Perez									
131424		Custodial			4/15/2015		0		\$0.00
Medium	Work In Progress				4/15/2015 9:22:10 AM				
Carbajal, Jimmy		senesecita arreglar maquina de lebantar la agua no lebanta bien GRACIAS							
M. Carmen Perez									
131425		Custodial			4/15/2015		0		\$0.00
Medium	Work In Progress				4/15/2015 9:25:11 AM				
Carbajal, Jimmy		senesecita arreglar maquina de lebantar el agua no esta lebantando bien el agua GRACIAS							
M. Carmen Perez									
130503		Custodial			3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 9:31:30 AM				
Carbajal, Jimmy		senesecita cambiar yantas del dollypor unas duras GRACIAS							
M. Carmen Perez									
131271		Kitchen			4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 7:55:19 AM				
Acuna, Johnny		senesecita checar gotera en la cosine GRACIAS							
M. Carmen Perez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
131274		Hallway/Corridor			4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 7:59:32 AM				
Acuna, Johnny		senesecita arreglar gotera en el techo del #400/hallway serca del cuarto de banda GRACIAS							
M. Carmen Perez									
129066					2/19/2015		55		\$0.00
Medium	Work In Progress				2/19/2015 9:32:26 AM				
Marquez, Gerardo		AS PER HEALTH DEPARTMENT DOOR SEAL TO BACK DOOR NEEDS TO FIXED. SNP MANAGER SANDRA D. 824.4376							
Maritza Gonzalez									
119869					7/25/2014		264		\$0.00
Medium	Work In Progress				7/25/2014 3:18:22 PM				
Marquez, Gerardo		Need new closers for south main hall exit doors.							
Albert Vallejo									
130988	Main Building	Athletic Field			4/6/2015		9		\$0.00
Medium	Work In Progress	Charlene			4/6/2015 11:14:01 AM				
Ontiveros, Guadalupe		Lupe - Grounds = This is regarding the Dug outs at CMS = Requesting a chain link fence for the chain link dug outs to complete the Softball area.							
Terry Alvarado									
119581		Athletic Field			7/18/2014		271		\$0.00
Medium	Work In Progress				7/18/2014 1:31:26 PM				
Ontiveros, Guadalupe		playing fields need to be reseed as per site admin.							
Guadalupe Ontiveros									
129448					2/28/2015		46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:56 AM				
Munoz, Michael		Yearly - Chaparral MS - Fire Pump Inspection - Refer to PMs schedule details.							
Margret Villalobos									
118858					7/1/2014		288		\$0.00
High	Work In Progress				7/1/2014 9:58:32 AM				
Munoz, Michael		need to install new water gong bell for fire sprinkler system. district electrician will provide power.							
Michael Munoz									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
126970					1/4/2015	1/25/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:41:31 AM				
Munoz, Michael		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PMschedule details.							
Margret Villalobos									
130511					3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 11:55:50 AM				
Villalobos, Margret		we need Assurance Fire to place pin on the system in the kitchen							
Cora Ramirez									
130833					4/5/2015	4/26/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:36 AM				
Munoz, Michael		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PMschedule details.							
Margret Villalobos									
131244					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:42 AM				
Perez, M. Carmen		Monthly - QRTLY BLDG INSP REPORTS (CM) - Refer to PMschedule details.							
Margret Villalobos									
129491					3/1/2015		45		\$0.00
Medium	Work In Progress				3/1/2015 12:45:53 AM				
Flores, Pete		Monthly - CHM-UV-0514 PM Service - Refer to PM schedule details.							
Margret Villalobos									
120809	Main Building	Classroom			8/8/2014		250		\$0.00
Medium	Work In Progress	205			8/8/2014 10:47:57 AM				
Appelzoller, Fred		pipes on sinks need to be fixed							
Gidget Mora									
125798	Main Building	Gym			11/20/2014		146		\$0.00
Medium	Work In Progress				11/20/2014 2:02:05 PM				
Sotelo, Enrique		Light switch does not work on main entryinto gym. Request all 4 switches be changed to toggle switch							
Gidget Mora									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
124842					10/31/2014		166		\$0.00
Medium	Work In Progress				10/31/2014 2:26:36 PM				
Orozco, Daniel		The back doors to warmer seems to be hanging a little from both top hinges. This could be why that warmer takes forever to reach its holding temperature. SNP Manager Sandra D.824.4376							
Maritza Gonzalez									
128088					1/29/2015		76		\$0.00
Medium	Work In Progress				1/29/2015 10:23:00 AM				
Orozco, Daniel		AIR CURTAIN AT BACK DOOR IS NOT WORKING, NEEDS A NEW MOTOR FAN. SNP MANAGER SANDRA D. 824.4376							
Maritza Gonzalez									
128514					2/5/2015		69		\$0.00
Medium	Work In Progress				2/5/2015 10:24:42 AM				
Orozco, Daniel		I need to place a work order for the washer. It doesn't start right away and when it finally does, it doesn't want to drain/spin. SNP Manager Sandra D. 824.4376							
Maritza Gonzalez									
128515					2/5/2015		69		\$0.00
Medium	Work In Progress				2/5/2015 10:26:15 AM				
Orozco, Daniel		Back door seal worn out, needs to be replaced. (as per environment dept.). SNP Manager Sandra D. 824.4376							
Maritza Gonzalez									
128516					2/5/2015		69		\$0.00
Medium	Work In Progress				2/5/2015 10:26:50 AM				
Orozco, Daniel		Freezer door doesn't close completely without having to push it shut. (as per environment dept.) SNP Manager Sandra D. 824.4376							
Maritza Gonzalez									
131046					4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 12:55:22 PM				
Appelzoller, Fred		Please fix commode to girls restroom in the 200 hall. 3rd stall. Need to replace and secure bottom bolts to hold down commode.							
Johnny Acuna									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

131034 Main Building Athletic Field 4/7/2015 8 \$0.00

Medium Work In Progress Coach Castillo 4/7/2015 10:09:23 AM

Appelzoller, Fred Please install water fountains outside near the gym

Gidget Mora

118903 7/2/2014 287 \$0.00

Medium Work In Progress 7/2/2014 12:29:48 PM

Marquez, Gerardo Replace or repair gym south exit doors

Albert Vallejo

130610 Restroom 3/26/2015 20 \$0.00

Medium Work In Progress 3/26/2015 8:25:39 AM

Marquez, Gerardo Need to get a price quote/tech. support from Joe Lagunas (APCO) for dr. hardware for women's Faculty Rest Rm. in 300 wing.

Gerardo Marquez

122690 Hallway/Corridor 9/12/2014 215 \$0.00

Medium Work In Progress 9/12/2014 9:12:02 AM

Marquez, Gerardo senesecita arglar chapa delas puertas de 400/hallway GRACIAS

M. Carmen Perez

131042 Main Building Gym 4/7/2015 8 \$0.00

Medium Work In Progress 4/7/2015 11:52:26 AM

Marquez, Gerardo Please make 6 more A34 keys

Gidget Mora

126888 1/4/2015 2/4/2015 101 \$0.00

Medium Work In Progress 1/4/2015 12:40:25 AM

Villalobos, David Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

122338 Main Building Restroom (Girls) 9/4/2014 223 \$0.00

Medium Work In Progress Office ladies 9/4/2014 3:13:32 PM

Vallejo, Albert Fan is broken-Making noise

Gidget Mora

130955 4/5/2015 4/11/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:30:42 AM

Vallejo, Albert Monthly - Chaparral MS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

4/15/2015 3:50:35 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

130733 3/31/2015 15 \$0.00

Medium Work In Progress 3/31/2015 12:38:06 AM

Vallejo, Albert Monthly - Chaparral MS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.

Margret Villalobos

125222 Main Building Gym 11/6/2014 160 \$0.00

Medium Work In Progress 11/6/2014 10:20:59 AM

Vallejo, Albert Blue pads in the main gym backboards need to be re-glued or re-bolted. All 6

Gidget Mora

130459 Library 3/23/2015 23 \$0.00

Medium Work In Progress 205 3/23/2015 11:14:08 AM

Vallejo, Albert Please reassemble the c.o.w carts for laptops

Gidget Mora

129698 Main Building 3/3/2015 43 \$0.00

Medium Work In Progress Garden tower 3/3/2015 10:31:26 AM

Vallejo, Albert Please kill all weeds in courtyard

Gidget Mora

129427 2/28/2015 3/31/2015 46 \$0.00

Medium Work In Progress 2/28/2015 12:34:41 AM

Vallejo, Albert Yearly - Chaparral MS C-11 (Swamp Coolers)Yearly) - Refer to PM schedule details.

Margret Villalobos

128209 2/1/2015 2/9/2015 73 \$0.00

Medium Work In Progress 2/1/2015 12:49:50 AM

Vallejo, Albert Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.

Margret Villalobos

121096 8/13/2014 245 \$0.00

Medium Work In Progress 8/13/2014 10:19:11 AM

Vallejo, Albert Please insulate supply ducts on new refrigeration units.

Albert Vallejo

128722 Classroom 2/10/2015 64 \$0.00

Medium Work In Progress 103 2/10/2015 10:45:18 AM

Vallejo, Albert Please repair raised beds

Gidget Mora

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral MS							
128723		Classroom			2/10/2015		64		\$0.00
Medium	Work In Progress	103			2/10/2015 10:46:24 AM				
Vallejo, Albert		Please seal outside gardening shed							
Gidget Mora									
128084	Main Building	Classroom			1/29/2015		76		\$0.00
Medium	Work In Progress	311			1/29/2015 9:50:55 AM				
Vallejo, Albert		Garden tower project needs the shed to be built							
Gidget Mora									
129983	Main Building	Classroom			3/10/2015		36		\$0.00
Medium	Work In Progress	103			3/10/2015 9:49:03 AM				
Vallejo, Albert		Please replace pencil sharpener							
Gidget Mora									
130082	Main Building	Classroom			3/12/2015		34		\$0.00
Medium	Work In Progress	208			3/12/2015 10:09:46 AM				
Vallejo, Albert		Teacher needs air filters				Teacher needs air filters			
Gidget Mora									
125846	Main Building	Restroom			11/21/2014		145		\$0.00
Medium	Work In Progress				11/21/2014 1:47:29 PM				
Vallejo, Albert		Fans in restrooms are not working Women's Restroom in 100 hallway Mens Restroom in 300 hallway							
Gidget Mora									
130789					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:12 AM				
Vallejo, Albert		Yearly - Chaparral MS A13(AC Wall)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
130806					4/5/2015	4/26/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:21 AM				
Vallejo, Albert		Monthly - Chaparral MS H11 (E.Heater)(S.Annual) - Refer to PMschedule details.							
Margret Villalobos									
130853					4/5/2015	4/8/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:46 AM				
Vallejo, Albert		Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PMschedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
130883					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:02 AM				
Vallejo, Albert		Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130884					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:03 AM				
Vallejo, Albert		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130886					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:04 AM				
Vallejo, Albert		Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
130887					4/5/2015	5/6/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:05 AM				
Vallejo, Albert		Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
129604					3/1/2015	3/7/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:47:00 AM				
Vallejo, Albert		Monthly - Chaparral MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
130502		Custodial			3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 9:28:30 AM				
,		senesecita cambiar yantas del dolly por unas duras GRACIAS							
M. Carmen Perez									
120816	Main Building	Gym			8/8/2014		250		\$0.00
Medium	Work In Progress				8/8/2014 11:17:35 AM				
Gonzalez, Salvador		Coach would like 3 tether ball poles installed near the outside basketball courts				Route to Sal 10/22/14			
Gidget Mora									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral MS							
130560	Main Building	Parking Lot			3/25/2015		21		\$0.00
Medium	Work In Progress				3/25/2015 8:51:19 AM				
Ronquillo, Ruben		Please make parking signs for Assistant Principal and Teacher of the year							
Gidget Mora									
Count: 59 Work Orders		Avg. Age of WO's	73			Total for Chaparral MS	0		\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride HS							
131284		Gym			4/13/2015		2		\$0.00
Medium	Work In Progress			4/13/2015 9:47:57 AM					
Ronquillo, Ruben		need to have stationary punching bags stances fasten or secure on to the floor.							
David Acosta									
130848					4/5/2015		10		\$0.00
Medium	Work In Progress			4/5/2015 12:29:44 AM					
Ronquillo, Ruben		Monthly - Desert Pride - (Qtrly) Fitness Equipment - Refer to PM schedule details.							
Margret Villalobos									
130452		Portables			3/23/2015		23		\$0.00
Medium	Work In Progress	portable 4		3/23/2015 9:11:23 AM					
Duran, Adan		Requesting assistance for the art teachers Art Show at GMS on April 23rd and April 27th to pick up art exhibits at DPA on April 23rd and to set up and to take down on April 27th and return to DPA.							
Maria Carbajal									
129908					3/9/2015	3/24/2015	37		\$0.00
Medium	Work In Progress			3/9/2015 12:35:40 AM					
Acosta, David		Monthly - QRTLY BLDG INSP REPORT (DP) - Refer to PM schedule details.							
Margret Villalobos									
121689		Classroom			8/25/2014		233		\$0.00
Medium	Work In Progress	101		8/25/2014 10:10:50 AM					
Marquez, Gerardo		NEED KEY TO READING LAB 180 IN ROOM 101.							
Yvette Cortez									
121923					8/28/2014		230		\$0.00
Medium	Work In Progress	11 & 12		8/28/2014 1:40:28 PM					
Appelzoller, Fred		TOILET GETS CLOGGED IN PORTABLE 11 & 12. PLEASE CHECK TO SEE WHAT IS CLOGGING THE TOILET.							
Yvette Cortez									
131040		Portables			4/7/2015		8		\$0.00
Medium	Work In Progress	room #18		4/7/2015 11:26:32 AM					
Sotelo, Enrique		one of the light fixture needs a new ballast.							
David Acosta									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Pride HS									
127415					1/12/2015		93		\$0.00
Medium	Work In Progress				1/12/2015 3:16:17 PM				
Gallegos, Rafael		MR LORENZO SOLIS SIR THE HEATER AT DESERT PRIDE IN NOT TURNING ON CAN YOU PLEASE CHECK THANK YOU AND GOD BLESS							
Adan Duran									
131039		Portables			4/7/2015		8		\$0.00
Medium	Work In Progress	room #9			4/7/2015 11:24:05 AM				
Solis, Lorenzo		a/c not working properly and may need a new thermostat							
David Acosta									
131172		Portables			4/10/2015		5		\$0.00
Medium	Work In Progress	room #6			4/10/2015 7:14:42 AM				
Solis, Lorenzo		thermostat not working properly for cooling room.							
David Acosta									
130987		Athletic Field			4/6/2015		9		\$0.00
Medium	Work In Progress	baseket court			4/6/2015 11:13:53 AM				
Ontiveros, Guadalupe		need to paint courts line and marking.							
David Acosta									
124335					10/20/2014		177		\$0.00
Medium	Work In Progress				10/20/2014 10:31:12				
Ontiveros, Guadalupe		PAINT LINES ON BASKETBALL COURT.				Asp Mike, route to Grounds			
Yvette Cortez									
120451					8/4/2014		254		\$0.00
Medium	Work In Progress				8/4/2014 1:51:09 PM				
Marquez, Gerardo		For Desert Pride need three (3) Master keys. Please drop off at Construction office when ready. Should you have any questions please contact Mr. Ralph Gallegos at 575-882-6921 in the Construction office. Thank You							
Dominique Esparza									
124401		Portables			10/21/2014		176		\$0.00
Medium	Work In Progress	room no.10			10/21/2014 12:25:05				
Marquez, Gerardo		Door slams heavy and very hard. Need to replace door closer asap.							
David Acosta									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Pride HS									
121338		Portables			8/18/2014		240		\$0.00
Medium	Work In Progress	1 & 2			8/18/2014 11:30:07 AM				
Marquez, Gerardo		DOOR CYLINDER TO STORGE ROOM IN PORTABLE 1 & 2 NEEDS TO BE REPLACED. ALSO, WHEN REPLACING CYLINDER, PLEASE GIVE STORAGE KEY TO MS. SCOTT AND MS. JAMESON-SPED TEACHERS.							
Yvette Cortez									
130980		Portables			4/6/2015		9		\$0.00
Medium	Work In Progress	room# 7 & 8			4/6/2015 9:39:49 AM				
Marquez, Gerardo		doors need a latch guard for security purpose.							
David Acosta									
131330		Portables			4/13/2015		2		\$0.00
Medium	Work In Progress	portable 5			4/13/2015 4:06:02 PM				
Marquez, Gerardo		Door between portable 5 & 6 needs a lock. Filing cabinets need to be keyed.							
Maria Carbajal									
129986		Portables			3/10/2015		36		\$0.00
Medium	Work In Progress	room 1&2			3/10/2015 10:54:31 AM				
Estrada, Jesus		carpet repair is needed where wall was remove in portable							
David Acosta									
129716		Portables			3/3/2015		43		\$0.00
Medium	Work In Progress	room 11 & 12			3/3/2015 1:31:15 PM				
Estrada, Jesus		need to replace floor tile in hallway and restroom between classrooms.							
David Acosta									
Count: 19 Work Orders		Avg. Age of WO's 84			Total for Desert Pride HS			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Desert Trail ES								
130186		Custodial			3/16/2015		30		\$0.00
Medium	Work In Progress				3/16/2015 10:18:26 AM				
Estrada, Jesus		Buenos dia Chuy. estos son los portables que se necesitan alfombrar Num,400 se necesita reparar la alfombra se esta desilando. 401 , 402, 403, 404, 408, 410, 411, Arte 413 tiene piso , y final mente 416 y quedarian perfectos.							
Laura Sandoval									
131241					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:40 AM				
Sandoval, Laura		Monthly - QRTLY BLDG INSP REPORTS (DT) - Refer to PM schedule details.							
Margret Villalobos									
131043					4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 12:48:55 PM				
Solis, Lorenzo		Need assistance with Bucket truck to replace rope to flag poles.							
Johnny Acuna									
131044					4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 12:51:41 PM				
Solis, Lorenzo		Need assistance in removing and replacing window unit to Portable #406 classroom.							
Johnny Acuna									
131045					4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 12:53:09 PM				
Solis, Lorenzo		Need assistance in replacing and wiring up 480 voltage to Commercial A.c. unit motor in cafeteria.							
Johnny Acuna									
131096					4/8/2015		7		\$0.00
Medium	Work In Progress				4/8/2015 11:50:28 AM				
Solis, Lorenzo		Need (2) 18" x 18" A/c supply adjustable registers for portable #418, 419.							
Johnny Acuna									
131380					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 1:31:07 PM				
Solis, Lorenzo		Please order corrugated metal covers to cover up outdoor walls where old refrigerated units used to be.							
Johnny Acuna									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail ES							
131382					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 1:35:07 PM				
Solis, Lorenzo		(Lorenzo): Need to install electrical to new refrigeration unit installation to portable #406.							
Johnny Acuna									
129833					3/5/2015		41		\$0.00
Medium	Work In Progress				3/5/2015 1:39:57 PM				
Marquez, Gerardo		AS PER ADELE BALESH MONITORING REPORT (2.24.15)- RUSTY DOOR FRAME IN STORE ROOM.							
Maritza Gonzalez									
128658					2/9/2015		65		\$0.00
Medium	Work In Progress				2/9/2015 9:19:58 AM				
Ontiveros, Guadalupe		Need to relocate swing set with 2 swings to other side. Please see Coach Scott. Thanks							
Johnny Acuna									
128592					2/6/2015		68		\$0.00
Medium	Work In Progress				2/6/2015 11:58:23 AM				
Acuna, Johnny		Need oil based paint for main building doors.							
Johnny Acuna									
128593					2/6/2015		68		\$0.00
Medium	Work In Progress				2/6/2015 12:01:10 PM				
Acuna, Johnny		Need 6 swing clamps with swivels for swings top rail.							
Johnny Acuna									
128594					2/6/2015		68		\$0.00
Medium	Work In Progress				2/6/2015 12:03:04 PM				
Acuna, Johnny		Need 6 (replacement) swing seats							
Johnny Acuna									
129433					2/28/2015	3/31/2015	46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:45 AM				
Acuna, Johnny		Yearly - Desert Trail ES C-11 (Evap.Cool)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
120033					7/30/2014		259		\$0.00
Medium	Work In Progress				7/30/2014 2:18:04 PM				
Acuna, Johnny		As per Alfredo please order borders needed. Need approx. 22 borders for playground sand to the bigger playground area sets.							
Johnny Acuna									
4/15/2015 3:50:36 PM									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail ES							
118894					7/2/2014		287		\$0.00
Medium	Work In Progress				7/2/2014 8:23:42 AM				
Acuna, Johnny		Need to patch and re-stitch playground picnic table area Blue Canvas Shade.							
Johnny Acuna									
130795					4/5/2015	4/21/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:15 AM				
Acuna, Johnny		Monthly - Desert Trail ES A1 (Air Dryer)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
130827					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:33 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
130863					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:51 AM				
Acuna, Johnny		Monthly - Desert Trail ES- Emer Light Insp:Monthly - Refer to PM schedule details.							
Margret Villalobos									
130864					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:52 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Exit Sign Insp:Monthly - Refer to PM schedule details.							
Margret Villalobos									
130865					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:52 AM				
Acuna, Johnny		Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
129889					3/6/2015		40		\$0.00
Medium	Work In Progress				3/6/2015 3:32:45 PM				
Acuna, Johnny		3-6-15				3/6			
.5-check boiler heating system									
3.5-(Front Lobby) remove water fountain, replace P-trap, make adjustments to measurements on the wall, install new fountain, test for leaks and proper operation.									
2.0-Replace faucet to room #108 classroom sink. \$97.00									
2.0-cut weeds.									
Johnny Acuna									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Desert Trail ES									
129830					3/5/2015		41		\$0.00
Medium	Work In Progress			3/5/2015 1:37:00 PM					
Acuna, Johnny	AS PER ADELE BALESH MONITORING REPORT (2.24.15)- HOLE ON WALL BY MOP SINK IN KITCHEN STORE ROOM.								
Maritza Gonzalez									
129610					3/1/2015	3/7/2015	45		\$0.00
Medium	Work In Progress			3/1/2015 12:47:03 AM					
Acuna, Johnny	Monthly - Desert Trail ES - Monthly FE Inpsection - Refer to PMschedule details.								
Margret Villalobos									
129512					3/1/2015	3/9/2015	45		\$0.00
Medium	Work In Progress			3/1/2015 12:46:06 AM					
Acuna, Johnny	Monthly - Desert Trail ES- Emer Light Insp:Monthly - Refer to PMschedule details.								
Margret Villalobos									
129513					3/1/2015	3/9/2015	45		\$0.00
Medium	Work In Progress			3/1/2015 12:46:07 AM					
Acuna, Johnny	Monthly - Desert Trail ES - Exit Sign Insp:Monthly - Refer to PMschedule details.								
Margret Villalobos									
129487					3/1/2015		45		\$0.00
Medium	Work In Progress			3/1/2015 12:45:51 AM					
Acuna, Johnny	Yearly - Desert Trail ES A10 (Heat Pump)(Yearly) - Refer to PMschedule details.								
Margret Villalobos									
129338					2/26/2015		48		\$0.00
Medium	Work In Progress			2/26/2015 9:32:58 AM					
Acuna, Johnny	Need Latex(Water Based) and (Oil Based) paint								
Johnny Acuna									
131100					4/8/2015		7		\$0.00
Medium	Work In Progress			4/8/2015 1:07:57 PM					
Acuna, Johnny	Need A/c filters for Cooling Season.								
Johnny Acuna									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail ES							
131260					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:51 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Playground Insp - Refer to PMschedule details.							
Margret Villalobos									
131384					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 2:08:28 PM				
Acuna, Johnny		Need to pick up art displays and set up at GMS on 4-23, and pick up on 4-27. (DT, CH. Elem., CMS)							
Johnny Acuna									
130961					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:45 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
130739					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:09 AM				
Acuna, Johnny		Monthly - Desert Trail ES A16(Exhst Fan)(S.Annual) - Refer to PMschedule details.							
Margret Villalobos									
131001					4/6/2015		9		\$0.00
Medium	Work In Progress				4/6/2015 2:16:59 PM				
Acuna, Johnny		Need to replace fire extinguisher to portable #419							
Johnny Acuna									
131189		Custodial			4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 11:44:38 AM				
Carbajal, Jimmy		Jimmybuenos dias por favor necesito Gas propano para la maquina gracias							
Laura Sandoval									
130834					4/5/2015	4/26/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:37 AM				
Munoz, Michael		Monthly - Desert Trail ES - Fire Sprinkler Insp. - Refer to PMschedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail ES							
129382	Main Building	Classroom			2/26/2015		48		\$0.00
Medium	Work In Progress	304,201		2/26/2015 3:59:03 PM					
Villalobos, Margret		Need treatment in rooms 304, 201 due to head lice activity.				2/27/Emailed Bennie			
Elizabeth Hernandez									
129178	Main Building	Classroom			2/23/2015		51		\$0.00
Medium	Work In Progress	110,202,210,41		2/23/2015 3:24:29 PM					
Villalobos, Margret		Need treatment in these room due to head lice activity.				Emailed			
Elizabeth Hernandez									
126971					1/4/2015	1/25/2015	101		\$0.00
Medium	Work In Progress			1/4/2015 12:41:32 AM					
Munoz, Michael		Monthly - Desert Trail ES - Fire Sprinkler Insp. - Refer to PMs schedule details.							
Margret Villalobos									
125181					11/5/2014		161		\$0.00
Medium	Work In Progress			11/5/2014 2:44:50 PM					
Flores, Pete		Please fix fuel gauge to work truck #192							
Johnny Acuna									
130429					3/20/2015		26		\$0.00
Medium	Work In Progress			3/20/2015 2:40:47 PM					
Orozco, Daniel		The dryer doesn't want to dry the towels. Thank you. SNP Manager Pat C.824.3822							
Maritza Gonzalez									
128415					2/3/2015		71		\$0.00
Medium	Work In Progress			2/3/2015 2:48:33 PM					
Orozco, Daniel		FAUCET ON DRAIN IN 3 COMPARTMENT SINK IS BROKEN SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
131370					4/14/2015		1		\$0.00
Medium	Work In Progress			4/14/2015 9:43:48 AM					
Orozco, Daniel		DISHWASHER MACHINE IS NOT WORKING, WATER WONT STAY. SNP MANAGER PAT CISNEROS							
Maritza Gonzalez									
128688					2/9/2015		65		\$0.00
Medium	Work In Progress			2/9/2015 3:43:35 PM					
Orozco, Daniel		METAL FROM THE WALK-IN FLOOR COMING OFF. SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
4/15/2015 3:50:36 PM									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail ES									
122696					9/12/2014		215		\$0.00
Medium	Work In Progress				9/12/2014 11:12:08 AM				
Orozco, Daniel		As per Health Inspection Report-foot pedal (walk-in)door pedal and freezer foot pedal from sinks are leaking.							
Maritza Gonzalez									
128967					2/17/2015		57		\$0.00
Medium	Work In Progress				2/17/2015 2:14:39 PM				
Appelzoller, Fred		Water is coming out under the washer machine. Thank you. SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
119597					7/18/2014		271		\$0.00
Medium	Work In Progress				7/18/2014 3:05:40 PM				
Appelzoller, Fred		Need parts to repair broken clean-out.							
Johnny Acuna									
129832					3/5/2015		41		\$0.00
Medium	Work In Progress				3/5/2015 1:38:45 PM				
Appelzoller, Fred		AS PER ADELE BALESH MONITORING REPORT (2.24.15)- WASHER FLOODS ON WASH CYCLE.							
Maritza Gonzalez									
125611		Classroom			11/17/2014		149		\$0.00
Medium	Work In Progress				11/17/2014 8:58:15 AM				
Marquez, Gerardo		NEED TO LOCATE AND DELIVER A URINAL SCREEN FOR WORK BEING DONE ON PORTABLE R.RM. REMODEL.							
Gerardo Marquez									
127657					1/16/2015		89		\$0.00
Medium	Work In Progress				1/16/2015 2:26:12 PM				
Marquez, Gerardo		Please replace main doors and door closures on the westside of main building. (Portables Area)							
Johnny Acuna									
130498					3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 8:49:33 AM				
Marquez, Gerardo		Portable #406: Please change out core to portable door to be same as teachers key. Thank You.....							
Johnny Acuna									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail ES									
126889					1/4/2015	2/4/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:40:25 AM				
Villalobos, David		Yearly - Desert Trail ES - Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
121108					8/13/2014		245		\$0.00
Medium	Work In Progress				8/13/2014 11:37:57 AM				
Vallejo, Albert		Need assistance with electrical to cafeteria A/c units.							
Johnny Acuna									
129770					3/4/2015		42		\$0.00
Medium	Work In Progress				3/4/2015 12:02:45 PM				
Vallejo, Albert		Main Bldg. (Room #107: Mr. Salas): Please tap into an existing electrical outlet, run conduit on outside of wall, and add and additional 115v outlet for teacher's computer.							
Johnny Acuna									
124678					10/28/2014		169		\$0.00
Medium	Work In Progress				10/28/2014 12:31:36				
Gonzalez, Salvador		Need plate replacement for sidewalk on westside of main building portables area.							
Johnny Acuna									
Count: 55 Work Orders		Avg. Age of WO's 60			Total for Desert Trail ES			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
131187					4/10/2015		5		\$0.00
Medium	Work In Progress	Outside on the			4/10/2015 11:04:20 AM				
Ortiz, Ruben		Set up caution barriers to block off a hose that is being used due to construction. This will keep students and staff from tripping over it. (Gonzalez)							
Guadalupe Gonzalez									
131266					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:54 AM				
Ortiz, Ruben		Monthly - Desert View ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
130957					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:43 AM				
Ortiz, Ruben		Monthly - Desert View ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
130971					4/6/2015		9		\$0.00
Medium	Work In Progress	Front Gate			4/6/2015 8:12:03 AM				
Ortiz, Ruben		The wheels to the front gate are broken and it's hard to open and close. The need to be fixed. (Gonzalez)							
Guadalupe Gonzalez									
130925					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:26 AM				
Ortiz, Ruben		Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
130926					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:26 AM				
Ortiz, Ruben		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130927					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:27 AM				
Ortiz, Ruben		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
131137		Classroom			4/9/2015		6		\$0.00
Medium	Work In Progress	Rm. #19			4/9/2015 9:36:23 AM				
Ortiz, Ruben		Move 6 boxes (labeled by door), 4 drawer filing cabinet (labeled under the "big ear" on right, and standing 2 door locker with handle (labeled on left) to Sunland Park Elementary (Room 20 - Speech). (Griswold)							
Guadalupe Gonzalez									
131141		Classroom			4/9/2015		6		\$0.00
Medium	Work In Progress	Port. #8			4/9/2015 10:38:57 AM				
Ortiz, Ruben		Help Mr. Lee (Art Teacher) transport Art Displays to Gadsden Middle School on April 23, 2015. (Lee)							
Guadalupe Gonzalez									
131142		Classroom			4/9/2015		6		\$0.00
Medium	Work In Progress	Port. #8			4/9/2015 10:45:57 AM				
Ortiz, Ruben		Help Mr. Lee (Art Teacher) transport Art Displays to Desert View Elementary on April 27, 2015. (Lee)							
Guadalupe Gonzalez									
120105		Library			7/31/2014		258		\$0.00
Medium	Work In Progress	Library			7/31/2014 2:01:36 PM				
Ortiz, Ruben		Move projection screen back towards circulations desk. (Sanchez-Segura)							
Guadalupe Gonzalez									
120106		Library			7/31/2014		258		\$0.00
Medium	Work In Progress	Library			7/31/2014 2:02:45 PM				
Ortiz, Ruben		Paint white window on left side of entrance door to maroon. (Sanchez-Segura)							
Guadalupe Gonzalez									
120107		Library			7/31/2014		258		\$0.00
Medium	Work In Progress	Library			7/31/2014 2:06:39 PM				
Ortiz, Ruben		Paint upper corner triangle of south wall in Golden Yellow like the NM Flag. (Sanchez-Segura)							
Guadalupe Gonzalez									
122783		Classroom			9/15/2014		212		\$0.00
Medium	Work In Progress	Rm. #12			9/15/2014 3:49:22 PM				
Ortiz, Ruben		Take TV down and remove from classroom. (Ramos)							
Guadalupe Gonzalez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

120662 Classroom 8/6/2014 252 \$0.00

Medium Work In Progress Rm. #14 8/6/2014 2:40:13 PM

Ortiz, Ruben Air Conditioner not working. (Bueno)

Guadalupe Gonzalez

120663 Classroom 8/6/2014 252 \$0.00

Medium Work In Progress Rm. #16 8/6/2014 2:40:57 PM

Ortiz, Ruben Air Conditioner not working. (Mack)

Guadalupe Gonzalez

120664 8/6/2014 252 \$0.00

Medium Work In Progress Rm. #33 8/6/2014 2:42:09 PM

Ortiz, Ruben Air Conditioner not working. (Gutierrez)

Guadalupe Gonzalez

121789 8/26/2014 232 \$0.00

Medium Work In Progress 8/26/2014 2:41:33 PM

Ortiz, Ruben The sink in the kitchen is clogged. Need it repaired ASAP

Ruben Ortiz

121790 8/26/2014 232 \$0.00

Medium Work In Progress 8/26/2014 2:42:35 PM

Ortiz, Ruben The upper level girl's bathroom, the one faucet is leaking and the other is broken. Need it replaced.

Ruben Ortiz

129465 3/1/2015 45 \$0.00

Medium Work In Progress 3/1/2015 12:45:37 AM

Ortiz, Ruben Yearly - Desert View ES A-10 HP Rooftop Yearly - Refer to PMschedule details.

Margret Villalobos

129441 2/28/2015 3/31/2015 46 \$0.00

Medium Work In Progress 2/28/2015 12:34:51 AM

Ortiz, Ruben Yearly - Desert View ES C-11 Evap Coolers Yearly - Refer to PMschedule details.

Margret Villalobos

129451 2/28/2015 46 \$0.00

Medium Work In Progress 2/28/2015 12:34:58 AM

Ortiz, Ruben Monthly - Desert View ES A-16 Fan Exhaust (Semi) - Refer to PMschedule details.

Margret Villalobos

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
129742					3/3/2015		43		\$0.00
Medium	Work In Progress				3/3/2015 3:45:03 PM				
Ortiz, Ruben		Upper boys bathroom two toilets are clogged and a urinal; need it worked on. Thank you, Ruben							
Ruben Ortiz									
129021					2/18/2015		56		\$0.00
Medium	Work In Progress				2/18/2015 9:31:15 AM				
Ortiz, Ruben		Need weed and feed fertilizer for the grass by the rock wall.							
Ruben Ortiz									
129606					3/1/2015	3/7/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:47:01 AM				
Ortiz, Ruben		Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
130137					3/13/2015		33		\$0.00
Medium	Work In Progress	Trees in the			3/13/2015 2:10:59 PM				
Ortiz, Ruben		The trees need to be watered. They are all dying especially an Oak tree.							
Guadalupe Gonzalez									
130847					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:43 AM				
Ortiz, Ruben		Monthly - Desert View ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
130580		Cafeteria			3/25/2015		21		\$0.00
Medium	Work In Progress	Cafeteria/Gym			3/25/2015 3:14:58 PM				
Ortiz, Ruben		Please set-up cafeteria tables and long tables in the gym on Wednesday, April 15, 2015. This is for the Science Fair to be held on Thursday. (L. Gonzalez)							
Guadalupe Gonzalez									
120111		Office			7/31/2014		258		\$0.00
Medium	Work In Progress	Office			7/31/2014 2:16:37 PM				
Ortiz, Ruben		Put banners up on the fence. (Gonzalez)							
Guadalupe Gonzalez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

130703 Office 3/30/2015 16 \$0.00

Medium Work In Progress 3/30/2015 8:23:19 AM

Gonzales, Camilo Pick up Obsolete items and deliver to IM/WHSE for disposal. See daily delivery log for list of items.

Theresa Ramirez

131140 Classroom 4/9/2015 6 \$0.00

Medium Work In Progress Front Office 4/9/2015 10:26:41 AM

Gonzales, Camilo Pick up a Risograph machine. Thanks (Gonzalez)

Guadalupe Gonzalez

124435 10/22/2014 175 \$0.00

Medium Work In Progress 10/22/2014 9:03:17 AM

Castillo, Carlos
 Company: CALIPER CONSTRUCTION
 Contact Name: FERNIE REYES Contact Phone: (575)635-8919
 Alternate Contact: BLANCA CRUZ
 Cell Phone: (575)635-8919
 Email: blanca@caliperconst.com

Location of Work: SPOT: 100FT RAD FROM CENTER OF INTERSECTION.

Dominique Esparza

124806 10/30/2014 167 \$0.00

Medium Work In Progress 10/30/2014 4:04:18 PM

Castillo, Carlos Two lights in the office are not working; need it repaired. Thank you, Ruben

Ruben Ortiz

129817 3/5/2015 41 \$0.00

Medium Work In Progress 3/5/2015 10:28:49 AM

Castillo, Carlos
 Company: METRO MECHANICAL
 Contact Name: RICHARD MUNOZ Contact Phone: (575)649-5554
 Email: metromechinc@qwestoffice.net

Location of Work: SPOT ENTIRE PROPERTY. OPEN ACCESS; NO HAZARDS

Dominique Esparza

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

Location: Desert View ES

130380					3/19/2015		27		\$0.00
Medium	Work In Progress				3/19/2015 2:34:38 PM				
Castillo, Carlos	Company: METRO MECHANICAL Email: metromechinc@qwestoffice.net Location of Work: SPOT ENTIRE PROPERTY. OPEN ACCESS; NO HAZARDS Remarks: RELOCATE DUE TO TAKING LONGER THAN EXPECTED								

Dominique Esparza

131287					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 10:12:02 AM				
Castillo, Carlos	Line Locates needed: Company: CARVER ELECTRIC Contact Name: JACOB CARVER Contact Phone: (575)527-2127 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142 Cell Phone: (575)649-9207 Email: carver@carverelectric.com Location of Work: LOCATE PER THE DESERT VIEW ELEMENTERY WORK PLAN								

Dominique Esparza

130518	Main Building	Restroom			3/24/2015		22		\$0.00
Medium	Work In Progress	Outside			3/24/2015 2:13:59 PM				
Marquez, Gerardo	We like to have two keys made for outside restroom. Thanks a million								

Albert Ortiz

122564					9/10/2014		217		\$0.00
Medium	Work In Progress				9/10/2014 9:42:24 AM				
Orozco, Daniel	THE RISE PART ON 3 COMPARTMENT SINK IS CLOGGED. SNP MANAGER ELIZABETH D. 589.2425								

Maritza Gonzalez

123369					9/29/2014		198		\$0.00
Medium	Work In Progress				9/29/2014 4:01:13 PM				
Sotelo, Enrique	Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Alternate Phone: Best Time to Call: Fax No: Cell Phone: Pager No: Email: blanca@caliperconstcom								

Location of Work: LOCATE PER ZONE 1 WORK PLAN

Dominique Esparza

4/15/2015 3:50:36 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
131430					4/15/2015		0		\$0.00
Medium	Work In Progress				4/15/2015 10:09:31 AM				
Lara, Ralph		Please open storage room having problems getting in.							
Albert Vallejo									
131428	Main Building	Office			4/15/2015		0		\$0.00
Medium	Work In Progress				4/15/2015 9:54:19 AM				
Lara, Ralph		the office rear doors are giving us problems we can't open them with the key							
Israel Ortega									
130519		Exterior			3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 2:15:07 PM				
Lara, Ralph		Hi Rafa, I am having some trouble opening some of these padlocks specially the one on the gate. Can you service them. Thank you							
Israel Ortega									
125536					11/13/2014		153		\$0.00
Medium	Work In Progress	Front of School			11/13/2014 3:46:34 PM				
Munoz, Michael		Repair broken sidewalk in the front of school. It can cause someone to trip. (Araujo)							
Guadalupe Gonzalez									
131365		Custodial			4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 9:17:39 AM				
Carbajal, Jimmy		I have vacuum cleaner#20002017 that is not working. Can you repair it for us thank you.							
Israel Ortega									
131366		Custodial			4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 9:19:22 AM				
Carbajal, Jimmy		I also have vacuum cleaner #C08C0000051 that is broken. Can you repair it for us thank you.							
Israel Ortega									
130451	Main Building	Custodial			3/23/2015		23		\$0.00
Medium	Work In Progress				3/23/2015 8:41:30 AM				
Carbajal, Jimmy		Hi Jimmy, I have a vacuum cleaner #c08000000330 that is not working. Please fix it for us. Thank you							
Israel Ortega									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
130680					3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 3:38:29 PM				
Ambriz, Jose		Portable 2 room 4 refrigerated unit is not working it needs to be replaced. Thank you, Ruben							
Ruben Ortiz									
131236					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:37 AM				
Ortega, Israel		Monthly - QRTLY BLDG INSP REPORT (DV) - Refer to PMs schedule details.							
Margret Villalobos									
128601					2/6/2015		68		\$0.00
Medium	Work In Progress				2/6/2015 1:44:28 PM				
Ontiveros, Guadalupe		The upper level playground valve no. 1 is not working; need it fixed.							
Ruben Ortiz									
130261					3/17/2015		29		\$0.00
Medium	Work In Progress	Outside upper			3/17/2015 1:47:31 PM				
Ontiveros, Guadalupe		The sprinklers aren't working properly out there. There are creating puddles and causing for the trees to dry out. (Araujo)							
Guadalupe Gonzalez									
131288					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 10:12:21 AM				
Ontiveros, Joe		Line Locates needed: Company: CARVER ELECTRIC Contact Name: JACOB CARVER Contact Phone: (575)527-2127 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142 Cell Phone: (575)649-9207 Email: carver@carverelectric.com Location of Work: LOCATE PER THE DESERT VIEW ELEMENTERY WORK PLAN							
Dominique Esparza									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Desert View ES

130974 4/6/2015 9 \$0.00

Medium Work In Progress 4/6/2015 8:25:00 AM

Ontiveros, Joe
 Company: METRO MECHANICAL
 Contact Name: RICHARD MUNOZ Contact Phone: (575)649-5554
 Email: metromechinc@qwestoffice.net
 Location of Work: SPOT ENTIRE PROPERTY. OPEN ACCESS; NO HAZARDS
 Remarks: RELOCATE DUE TO TAKING LONGER THAN EXPECTED

Dominique Esparza

130977 4/6/2015 9 \$0.00

Medium Work In Progress 4/6/2015 8:34:23 AM

Ontiveros, Joe
 Company: CALIPER CONSTRUCTION
 Contact Name: FERNIE REYES Contact Phone: (575)635-8919
 Email: blanca@caliperconst.com
 Location of Work: DESERT VIEW ELEMENTARY SCHOOL WIDE AREA WORK PLAN

Dominique Esparza

128045 Main Building Storage 1/28/2015 77 \$0.00

Medium Work In Progress 1/28/2015 1:57:31 PM

Ontiveros, Joe
 Hi Joe on the storage that is next to the upper grade level restroom the release valve on the water is leaking. It needs to be replaced. Thank you.

Israel Ortega

128046 Main Building Storage 1/28/2015 77 \$0.00

Medium Work In Progress 1/28/2015 2:02:36 PM

Ontiveros, Joe
 Hi Joe on the storage next to the restroom the back flow pleventer is leaking can you fix it please. Thank you

Israel Ortega

130460 Main Building Custodial 3/23/2015 23 \$0.00

Medium Work In Progress 3/23/2015 12:13:11 PM

Carbajal, Jimmy
 Hi Jimmy, I have a vacuum cleaner that is not working part #c08c00000155. Can you please fix it for us. Thank you

Israel Ortega

Count: 56 Work Orders Avg. Age of WO's 76 Total for Desert View ES 0 \$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
129266		Hallway/Corridor			2/25/2015		49		\$0.00
High	Work In Progress				2/25/2015 7:53:29 AM				
Estrada, Jesus		Hallway exit inside Human Resources hallway tiles are coming loose.							
Jesus Estrada									
128148					1/30/2015		75		\$0.00
Medium	Work In Progress				1/30/2015 11:31:18 AM				
Ontiveros, Joe		A-WING, WOMENS RR BACKING UP.							
Maritza Gonzalez									
130143					3/13/2015		33		\$0.00
Medium	Work In Progress				3/13/2015 3:18:34 PM				
Ontiveros, Guadalupe		please deliver two loads of base coarse							
Fernando Moncayo									
130144					3/13/2015		33		\$0.00
Medium	Work In Progress				3/13/2015 3:20:53 PM				
Ontiveros, Guadalupe		I need to borrow the bobcat please							
Fernando Moncayo									
128774		Electrical Room			2/11/2015		63		\$0.00
Medium	Work In Progress				2/11/2015 8:18:16 AM				
Ontiveros, Guadalupe		Due to bad mud situation when it rains, requesting crusher fine to be spread inside and around electrical-plumbing storage at the Gac.							
Carlos Castillo									
121916					8/28/2014		230		\$0.00
Medium	Work In Progress				8/28/2014 12:23:26 PM				
Ambriz, Jose		Anne de Los Santos would like to place a work order for the possibility of installing an A/C in her office. Approved by Mr. Suggs							
Maritza Gonzalez									
125499					11/13/2014		153		\$0.00
Medium	Work In Progress				11/13/2014 9:12:15 AM				
Ambriz, Jose		REPLACE UNIT IN KITCHEN AREA. LEAKING FROM COMPRESSOR SECTIONG.							
Maritza Gonzalez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
119230					7/9/2014		280		\$0.00
Medium	Work In Progress				7/9/2014 2:40:00 PM				
Ambriz, Jose		As per Mr. Steve Suggs, he would like a wall a/c unit installed in Richard Acosta and Priscilla Escobar office.							
Maritza Gonzalez									
126972					1/4/2015	1/25/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:41:32 AM				
Munoz, Michael		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
126413					12/9/2014		127		\$0.00
Medium	Work In Progress				12/9/2014 1:10:45 PM				
Munoz, Michael		AS PER MR. CHAVEZ, WEST WALL AT PRE-K BETWEEN WINDOWS/GENERATOR NEEDS TO BE REPAIRED.							
Maritza Gonzalez									
130835					4/5/2015	4/26/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:37 AM				
Munoz, Michael		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
130495		Parking Lot			3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 7:59:20 AM				
Lara, Ralph		NEED SIX PADLOCKS FOR PRE-K AND FRONT GATES.							
Ralph Lara									
129344					2/26/2015		48		\$0.00
Medium	Work In Progress				2/26/2015 12:03:46 PM				
Flores, Pete		need a d110 lawn tractor							
Fernando Moncayo									
131259					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:50 AM				
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
131386					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 2:43:53 PM				
Moncayo, Fernando		(B-WING) RESTROOM BEHIND RECEPTION AREA - DOOR JAMMING.							
Maritza Gonzalez									
131387					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 2:45:00 PM				
Moncayo, Fernando		(C-WING) KITCHENETTE-GARBAGE DISPOSAL BACKING UP.							
Maritza Gonzalez									
130947					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:38 AM				
Moncayo, Fernando		Monthly - GAC Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
130738					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:09 AM				
Moncayo, Fernando		Monthly - GAC A-16 Fan Exh Roof Semimonthly - Refer to PM schedule details.							
Margret Villalobos									
125757					11/19/2014		147		\$0.00
Medium	Work In Progress				11/19/2014 2:18:32 PM				
Moncayo, Fernando		HR REQUESTING TO HAVE HR CONFERENCE ROOM PAINTED.							
Maritza Gonzalez									
126166					12/3/2014		133		\$0.00
Medium	Work In Progress				12/3/2014 10:24:20 AM				
Moncayo, Fernando		C-WING -LIGHTS NEED TO BE INSTALLED IN HALLWAY WHERE MRS. YTURRALDE IS LOCATED.							
Maritza Gonzalez									
130861					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:50 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
130862					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:51 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130825					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:31 AM				
Moncayo, Fernando		Monthly - GAC Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
130123					3/13/2015		33		\$0.00
Medium	Work In Progress				3/13/2015 8:45:53 AM				
Moncayo, Fernando		Need to relocate white board in this office. Please talk to Calixto							
Cora Ramirez									
130176					3/16/2015		30		\$0.00
Medium	Work In Progress				3/16/2015 7:34:32 AM				
Moncayo, Fernando		AS PER ANNE DE LOS SANTOS MR. SUGGS A/C UNIT IS NOT WORKING.							
Maritza Gonzalez									
126541					12/11/2014		125		\$0.00
Medium	Work In Progress				12/11/2014 2:59:29 PM				
Moncayo, Fernando		Conference Room next to Mary Chavez - Re glue wall paper at all areas where its coming lose, properly patch any unused holes in walls, paint entire room							
Alfredo Holguin									
127465					1/13/2015		92		\$0.00
Medium	Work In Progress				1/13/2015 9:54:51 AM				
Moncayo, Fernando		AS PER TORI GILPIN FOUL SMELL COMING FROM VENTS IN C-WING.							
Maritza Gonzalez									
127997					1/27/2015		78		\$0.00
Medium	Work In Progress				1/27/2015 3:24:10 PM				
Moncayo, Fernando		ck and replace broken or leaking irrigation sprinklers							
Fernando Moncayo									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
121419					8/19/2014		239		\$0.00
Medium	Work In Progress				8/19/2014 11:43:45 AM				
Moncayo, Fernando		NO POWER TO WALL UNIT IN ROSA HIDALGO OFFICE.							
Maritza Gonzalez									
122154					9/2/2014		225		\$0.00
Medium	Work In Progress				9/2/2014 9:18:11 AM				
Moncayo, Fernando		BALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO.							
Maritza Gonzalez									
122634					9/11/2014		216		\$0.00
Medium	Work In Progress				9/11/2014 9:48:04 AM				
Moncayo, Fernando		ROSA APODACA OFFICE-BURNT SMELL COMING OUT OF WALL UNIT.							
Maritza Gonzalez									
122635					9/11/2014		216		\$0.00
Medium	Work In Progress				9/11/2014 9:48:24 AM				
Moncayo, Fernando		MARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT.							
Maritza Gonzalez									
125495					11/13/2014		153		\$0.00
Medium	Work In Progress				11/13/2014 8:36:40 AM				
Moncayo, Fernando		A-WING-WALL NEEDS TO BE FIXED IN MENS HANDICAP RR.							
Maritza Gonzalez									
130073					3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 7:53:33 AM				
Moncayo, Fernando		ck and service refrigerated air rooftop a/c units							
Fernando Moncayo									
130298					3/18/2015		28		\$0.00
Medium	Work In Progress				3/18/2015 8:42:24 AM				
Moncayo, Fernando		CLOGGED DRAIN AT BISTRO KITCHEN. SNP MANAGER IRMA V. 882.6784							
Maritza Gonzalez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
130798					4/5/2015	4/21/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:17 AM				
Moncayo, Fernando		Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.							
Margret Villalobos									
130799					4/5/2015	4/26/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:18 AM				
Moncayo, Fernando		Monthly - GAC F-39 Kitch Exh Makeup Ut Semimonthly - Refer to PM schedule details.							
Margret Villalobos									
129917					3/9/2015	3/24/2015	37		\$0.00
Medium	Work In Progress				3/9/2015 12:35:45 AM				
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
129028					2/18/2015		56		\$0.00
Medium	Work In Progress				2/18/2015 11:19:40 AM				
Moncayo, Fernando		CMT RM. PORTABLE HEATER NOT HEATING.							
Maritza Gonzalez									
129029					2/18/2015		56		\$0.00
Medium	Work In Progress				2/18/2015 11:53:36 AM				
Moncayo, Fernando		BROKEN/LOOSE TILE IN FRONT OF ERICA VILLAREAL AND LUPITA CHAVEZ OFFICES , SAFETY HAZARD.							
Maritza Gonzalez									
129485					3/1/2015		45		\$0.00
Medium	Work In Progress				3/1/2015 12:45:49 AM				
Moncayo, Fernando		Yearly - GAC A-10 Heat Pump Cooling Only Yearly - Refer to PM schedule details.							
Margret Villalobos									
129510					3/1/2015	3/9/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:05 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
129511					3/1/2015	3/9/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:05 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
129618					3/2/2015		44		\$0.00
Medium	Work In Progress				3/2/2015 8:00:59 AM				
Moncayo, Fernando		AS PER MARY CHAVEZ, RR IN FRONT OF RECEPTIONIST AREA- SEALS ARE LEAKING.							
Maritza Gonzalez									
129596					3/1/2015	3/7/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:55 AM				
Moncayo, Fernando		Monthly - GAC Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
125102		Hallway/Corridor			11/3/2014		163		\$0.00
Medium	Work In Progress				11/3/2014 3:28:00 PM				
Castillo, Carlos		Check hallway dark areas for emergency lighting installation. And install where needed.							
Carlos Castillo									
131328					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 4:03:55 PM				
Castillo, Carlos		Carmen Moreno office-We were asked to rearrange one of our areas and our initial cords do not reach and they keep blowing the circuit with surge protectors, so could we pretty please have Cali move the plug over and increase ampage. I spoke to him so he could give me some advice on what we needed							
Maritza Gonzalez									
129271					2/25/2015		49		\$0.00
Medium	Work In Progress				2/25/2015 8:25:22 AM				
Castillo, Carlos		LIGHTS IN PARKING LOT ARE NOT WORKING PROPERLY.							
Maritza Gonzalez									
131201		Office			4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 2:25:28 PM				
Gonzales, Camilo		Deliver 1 box. PO# 141506588. Attn: Noemi Duron, Federal Programs.							
Theresa Ramirez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

131202 Office 4/10/2015 5 \$0.00
 Medium Work In Progress 4/10/2015 2:26:45 PM
 Gonzales, Camilo Deliver 1 box. PO# 141506587. Attn: Noemi Duron.
 Theresa Ramirez

129389 Electrical Room 2/27/2015 47 \$0.00
 Medium Work In Progress 2/27/2015 8:10:09 AM
 Castillo, Carlos Order replacement hand tools, truck bumper vise, and traffic cones.
 Carlos Castillo

130701 Electrical Room 3/30/2015 16 \$0.00
 Medium Work In Progress 3/30/2015 8:19:13 AM
 Castillo, Carlos Order hantool(cordless screwdriver) for vehicle#152
 Carlos Castillo

126891 1/4/2015 2/4/2015 101 \$0.00
 Medium Work In Progress 1/4/2015 12:40:27 AM
 Villalobos, David Yearly - GAC Backflow Inspection - Refer to PM schedule details.
 Margret Villalobos

131367 4/14/2015 1 \$0.00
 Medium Work In Progress 4/14/2015 9:30:56 AM
 Gonzales, Camilo I need to see if you could send me 12 bankers boxes, I am asking early because I know everyone will be asking for them all at once.
 Please let me know, and thank you for all you do.
 Mary Telles
 Maritza Gonzalez

131401 Office 4/14/2015 1 \$0.00
 Medium Work In Progress 4/14/2015 3:45:04 PM
 Gonzales, Camilo Pick up obsolete items from Technology Department and Data Analysis & Info Systems. See Delivery Log for list of items. Thank you.
 Theresa Ramirez

131231 4/12/2015 4/28/2015 3 \$0.00
 Medium Work In Progress 4/12/2015 12:23:34 AM
 Rodriguez, Arturo Monthly - QRTLY BLDG INSP REPORT (GAC) - Refer to PM schedule details.
 Margret Villalobos

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
123425					9/30/2014		197		\$0.00
Medium	Work In Progress				9/30/2014 3:42:13 PM				
		PROJECT MANAGEMENT & FINAL CLEARANCE FOR ASBESTOS ABATEMENT AT GAC - RESTROOM IN "A" WING							
Alfredo Holguin									
130816					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:27 AM				
Holguin, Alfredo		Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									
130565					3/25/2015		21		\$0.00
Medium	Work In Progress				3/25/2015 9:07:22 AM				
Ronquillo, Ruben		AMERICAN FENCE-RELOCATE FENCE DOOR AT MORGAN BUILDING.							
Joe Ontiveros									
Count: 59 Work Orders			Avg. Age of WO's 69		Total for GAC			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC - Pre-K									
127305		Athletic Field			1/9/2015		96		\$0.00
Medium	Work In Progress	playground			1/9/2015 2:50:09 PM				
Gonzalez, Salvador		Morgan building, where playground equipment is stored needs a ramp to facilitate/easy access to trikes. Morgan building where playground equipment is stored needs a ramp to make for easy access to trikes, wagons and other playground toys.							
Leticia Tangonan									
130568		Kitchen			3/25/2015		21		\$0.00
Medium	Work In Progress				3/25/2015 9:31:02 AM				
Castillo, Carlos		provide electrical outlet for garbage disposal for new counter to be installed. Also make sure we will have outlets above counter. If none are present install this also. Counter is on order so this work needs to be done before counter arrives.							
Alfredo Holguin									
128682		Office			2/9/2015		65		\$0.00
Medium	Work In Progress	work room			2/9/2015 3:36:29 PM				
Moncayo, Fernando		We received our multimedia work station and needs to be assembled.							
Leticia Tangonan									
124226					10/16/2014		181		\$0.00
Medium	Work In Progress				10/16/2014 8:57:29 AM				
Moncayo, Fernando		RM. 103- SINK IS LEAKING.							
Maritza Gonzalez									
128085		Classroom			1/29/2015		76		\$0.00
Medium	Work In Progress	103			1/29/2015 9:58:09 AM				
Moncayo, Fernando		We need a pencil sharpener installed in room 103							
Leticia Tangonan									
127751		Classroom			1/21/2015		84		\$0.00
Medium	Work In Progress	101			1/21/2015 10:19:18 AM				
Moncayo, Fernando		please install pencil sharpener in room 101							
Leticia Tangonan									
131080		Classroom			4/8/2015		7		\$0.00
Medium	Work In Progress	202			4/8/2015 8:13:21 AM				
Moncayo, Fernando		Please assemble our loft in room 202- Teacher Ms. Sylvia will let you know where to put it.							
Leticia Tangonan									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC - Pre-K									
130072					3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 7:50:48 AM				
Moncayo, Fernando		ckd and service refrigerated air a/c units							
Fernando Moncayo									
130676					3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 3:32:07 PM				
Moncayo, Fernando		AS PER JOSE ONTIVEROS, REPAIR HOLE IN PRE-K LOUNGE.							
Joe Ontiveros									
128684					2/9/2015		65		\$0.00
Safety	Work In Progress	playground			2/9/2015 3:38:31 PM				
Moncayo, Fernando		The screw holding slide to the structure is coming off (loose).							
Leticia Tangonan									
130659					3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 11:15:06 AM				
Lara, Ralph		main entrance door to Pre K won't open from outside with the key							
Fernando Moncayo									
127302		Cafeteria			1/9/2015		96		\$0.00
Medium	Work In Progress				1/9/2015 2:40:16 PM				
Ontiveros, Joe		We need our small sink in our cafeteria replaced with a large deep utility/kitchen sink with counters and cabinets.							
Leticia Tangonan									
131431		Classroom			4/15/2015		0		\$0.00
Medium	Work In Progress	102			4/15/2015 10:19:51 AM				
Ontiveros, Joe		flapper in toilet needs to be replaced in room 102-							
Leticia Tangonan									
Count: 13 Work Orders			Avg. Age of WO's	59			Total for GAC - Pre-K	0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden ES							
131240					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:40 AM				
Pinon, Jose		Monthly - QRTL BLDG INSP REPORT (GES) - Refer to PM schedule details.							
Margret Villalobos									
131036		Custodial			4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 10:35:06 AM				
Carbajal, Jimmy		need propane refill							
Jose Pinon									
130308		Football Field			3/18/2015		28		\$0.00
Medium	Work In Progress				3/18/2015 11:39:36 AM				
Ontiveros, Guadalupe		The field needs to be aerated and fertilized. Spoke to Mr. Lupe Ontiveros.							
Loraine Gandara									
130747					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:14 AM				
Apodaca, Mario		Monthly - Gadsden ES - Monthly Meter Readings - Refer to PM schedule details.							
Margret Villalobos									
130852					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:46 AM				
Villalobos, Margret		Monthly - Gadsden ES - Enviro Controls Quarterly - Refer to PM schedule details.							
Margret Villalobos									
126534					12/11/2014		125		\$0.00
Medium	Work In Progress				12/11/2014 1:56:03 PM				
Appelzoller, Fred		need assistance with repairing jungle gym on the premises... would greatly appreciate your assistance in this matter...							
Loraine Gandara									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location:		Gadsden ES							
128954					2/17/2015		57		\$0.00
Medium	Work In Progress			2/17/2015 10:26:40 AM					
Appelzoller, Fred	The outside shade north of the school building is rusted. (not sure if there are one or two) both if there are two.								
	It needs to be clean, primed and paint all of the rustic areas.								
	He said, if you look up at it you can see the rust, all must be cleaned, primed and repainted.								
Richard Chavez									
130737					3/31/2015		15		\$0.00
Medium	Work In Progress			3/31/2015 12:38:08 AM					
Appelzoller, Fred	Monthly - Gadsden ES - A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
Margret Villalobos									
130945					4/5/2015	4/16/2015	10		\$0.00
Medium	Work In Progress			4/5/2015 12:30:37 AM					
Appelzoller, Fred	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.								
Margret Villalobos									
130871					4/5/2015		10		\$0.00
Medium	Work In Progress			4/5/2015 12:29:55 AM					
Appelzoller, Fred	Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
130874					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress			4/5/2015 12:29:57 AM					
Appelzoller, Fred	Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.								
Margret Villalobos									
130875					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress			4/5/2015 12:29:57 AM					
Appelzoller, Fred	Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.								
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									
Location: Gadsden ES									
122297		Athletic Field			9/4/2014		223		\$0.00
High	Work In Progress			9/4/2014 9:12:27 AM					
Appelzoller, Fred		need to cut weeds through out site, inside and outside of fence. also the weeds that have been killed with round up need to be cut as well. school is in dire need of weed control. need to include ponds.							
Michael Munoz									
128955		Classroom			2/17/2015		57		\$0.00
Medium	Work In Progress			2/17/2015 10:38:06 AM					
Appelzoller, Fred		need 24 PSQ500QD MVOLT FLUORESECT BATTERY PACKS FOR CLASS ROOM LIGHTING FIXTURES							
Fred Appelzoller									
131258					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress			4/12/2015 12:23:49 AM					
Appelzoller, Fred		Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
130049		Mechanical			3/11/2015		35		\$0.00
Medium	Work In Progress			3/11/2015 3:35:33 PM					
Appelzoller, Fred		need a new circulating pump for water heater on C-wing. need one for water heater and a spare one . Taco 009-SF5, 1/8 hp, 120 volts, 3259 rpm.							
Fred Appelzoller									
125788		Office			11/20/2014		146		\$0.00
Medium	Work In Progress			11/20/2014 8:00:37 AM					
Appelzoller, Fred		need spray can s to paint , flower pots out in front about 15 cans of almond or white							
Fred Appelzoller									
123039		Parking Lot			9/23/2014		204		\$0.00
Medium	Work In Progress			9/23/2014 8:35:17 AM					
Sotelo, Enrique		need for the lights to be replaced outside in the parking lot...greatly appreciate your assistance							
Loraine Gandara									
127977		Mechanical			1/27/2015		78		\$0.00
Medium	Work In Progress			1/27/2015 8:04:13 AM					
Sotelo, Enrique		need electrical outlets in Mech room							
Fred Appelzoller									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden ES									
128647					2/9/2015		65		\$0.00
Medium	Work In Progress				2/9/2015 7:43:31 AM				
Orozco, Daniel		ICE MACHINE DOWN. SNP MANAGER EVA M. 882.3410							
Maritza Gonzalez									
128788					2/11/2015		63		\$0.00
Medium	Work In Progress				2/11/2015 2:11:55 PM				
Orozco, Daniel		AS PER ADELE'S INSPECTION REPORT- SLICER MAKES A GRINDING NOISE.							
Maritza Gonzalez									
128789					2/11/2015		63		\$0.00
Medium	Work In Progress				2/11/2015 2:13:11 PM				
Orozco, Daniel		AS PER ADELE'S INSPECTION REPORT- CHOPPER LEAKS OIL.							
Maritza Gonzalez									
131356					4/14/2015		1		\$0.00
Medium	Work In Progress	FELICIA			4/14/2015 8:06:00 AM				
Gonzales, Camilo		DELIVER PO141506603 DISCOUNT SCHOOL SUPPLY 2 BOXES FELICIA NEVAREZ, TEACHER							
Margaret Villalobos									
128950					2/17/2015		57		\$0.00
Medium	Work In Progress				2/17/2015 9:23:52 AM				
Ronquillo, Ruben		Basketball Courts - Need to be resurfaced, it's too slippery.							
Richard Chavez									
Count: 24 Work Orders			Avg. Age of WO's	54			Total for Gadsden ES	0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

130933 4/5/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:30:30 AM

Sanchez, Raul Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.

Margret Villalobos

131143 Cafeteria (1998) 4/9/2015 6 \$0.00

Medium Work In Progress 4/9/2015 11:53:50 AM

Ronquillo, Ruben Gate to Compactor is to narrow- Install additional 3 FT 4/9/15-route to chuy asp Alfredo;

Alfredo Holguin

gate for easier access to dump trash into compactor- Check with custodial on specifics

4/10/15 - asp per Chuy, install an extra door to make it a double door, current one is 5' 9' length x 3' wide.

asp alfredo, need quote from academy fence, contact person will be chuy if they have any question; work order routed back to ruben.

128335 2/2/2015 72 \$0.00

Medium Work In Progress 2/2/2015 9:38:45 AM

Ronquillo, Ruben Requested by Coach Yanez for Baseball Field-Set up square batting cage with cables, clamps, and net at the baseball field. Spoke with Mike Munoz and Ruben Ronquillo regarding the batting cage.

Velia Alarcon

128074 1/29/2015 76 \$0.00

Medium Work In Progress 1/29/2015 7:46:54 AM

Gonzalez, Salvador Need to replace broken main sign pole by the flag poles.

Guillermo Hernandez

124632 Athletic Field 10/27/2014 170 \$0.00

Medium Work In Progress 10/27/2014 2:47:26 PM

Gonzalez, Salvador need to install new cables for new batting net on batting cages. boys baseball. contact person @ site. coach Bones. thank you

Michael Munoz

125861 Athletic Field 11/21/2014 145 \$0.00

Medium Work In Progress 11/21/2014 3:17:50 PM

Gonzalez, Salvador Requested by Ms. L. Chavez for Softball Field-Replace old batting cage. Add a third batting cage on Softball Field. Add an area for batting off tees. Remove old tee area from fence (left side) welded into fence.

Velia Alarcon

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

125862 Athletic Field 11/21/2014 145 \$0.00

Medium Work In Progress 11/21/2014 3:21:11 PM

Gonzalez, Salvador Requested by Ms. L. Chavez for Softball Field-Backstop on Softball Field needs to be replaced (safety issue). There are white stakes keeping fence down. Officials stated that those stakes were a safety issue to all players.

Velia Alarcon

125292 Football Field 11/7/2014 159 \$0.00

Medium Work In Progress 11/7/2014 1:12:07 PM

Gonzalez, Salvador Coach Vasquez would like a door placed in the shower area to store some of his equipment. Door needs to be welded.

William Dickson

126892 1/4/2015 2/4/2015 101 \$0.00

Medium Work In Progress 1/4/2015 12:40:27 AM

Villalobos, David Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

125480 11/13/2014 153 \$0.00

Medium Work In Progress 11/13/2014 7:40:30 AM

Villalobos, David Need assistance to repair water leak by the water fountain in the Old English first floor.

Guillermo Hernandez

125481 11/13/2014 153 \$0.00

Medium Work In Progress 11/13/2014 7:42:20 AM

Villalobos, David Need assistance to unclog sink in the weight room, need drain snake.

Guillermo Hernandez

125482 11/13/2014 153 \$0.00

Medium Work In Progress 11/13/2014 7:43:50 AM

Villalobos, David Need assistance to unclog sink in the girls restroom at the east wing (testing room) of the cafeteria, Need drain snake.

Guillermo Hernandez

124485 10/22/2014 175 \$0.00

Medium Work In Progress 10/22/2014 3:49:00 PM

Villalobos, David Need to replace vandalized sink faucet in Science #600, Lilly Chavez.

Guillermo Hernandez

4/15/2015 3:50:37 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
127152					1/6/2015		99		\$0.00
Medium	Work In Progress				1/6/2015 3:58:15 PM				
Villalobos, David		Requested by Mr. G. Jordan for Portable # 10-Toilet is running continuously and not working.							
Velia Alarcon									
130069					3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 7:40:04 AM				
Villalobos, David		Need assistance or small drain snake to unclog sinks in the weight room girls restroom and testing room girls restroom east wing of the cafeteria.							
Guillermo Hernandez									
130070					3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 7:42:25 AM				
Villalobos, David		David we need assistance to trouble shoot smell in the restroom at the Administration building, possible self priming valve for the floor drains is not working.							
Guillermo Hernandez									
130662					3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 1:36:57 PM				
Villalobos, David		Line locates are needed at GHS. Please see e-mail for site layout. For questions please contact Allan Journey of GenCon at 575-644-0810.							
Dominique Esparza									
130810					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:24 AM				
Holguin, Alfredo		Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									
130815					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:26 AM				
Holguin, Alfredo		Monthly - Gadsden HS - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
130855					4/5/2015	4/8/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:47 AM				
Nunez, Arturo		Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
130893					4/5/2015	5/6/2015	10		\$0.00
Medium	Work In Progress			4/5/2015 12:30:09 AM					
Nunez, Arturo	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
130894					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress			4/5/2015 12:30:09 AM					
Nunez, Arturo	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
121848	Academic Bldg				8/27/2014		231		\$0.00
Medium	Work In Progress			8/27/2014 2:30:48 PM					
Nunez, Arturo	Please replace all window screens.								
Michael Munoz									
131420	Nursing Center				4/15/2015		0		\$0.00
Medium	Work In Progress			4/15/2015 9:01:26 AM					
Nunez, Arturo	Requested by Minnie Singh for Nurse's Office-Toilet was leaking and as per maintenance staff, toilet may need to be replaced in Staff Restroom.								
Velia Alarcon									
131091		Parking Lot			4/8/2015		7		\$0.00
Medium	Work In Progress			4/8/2015 10:40:19 AM					
Nunez, Arturo	Requested by Mr. D. Martinez for Fence Along the South Side of the Fence-Requesting to paint the curb along the fence line on the south side of campus. This will be a no parking zone. At this time there are many cars parking on this side and this is creating a safety hazard on campus.								
Velia Alarcon									
131160	North Building				4/9/2015		6		\$0.00
Medium	Work In Progress			4/9/2015 3:45:57 PM					
Nunez, Arturo	Requested by Mrs. Munoz Rm. 210 North Building- Spikes are needed for exterior light of back door. Birds are roasting on light and leaving a mess on the back door.								
Velia Alarcon									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
131309	North Building				4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 3:21:58 PM				
Nunez, Arturo		Requested by Ms. Schapekahm Rm. 208 North Building -Door sweep placed for kitchen door.							
Velia Alarcon									
130898					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:11 AM				
Nunez, Arturo		Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
131422	Academic Bldg	Restroom (Girls)			4/15/2015		0		\$0.00
Medium	Work In Progress				4/15/2015 9:08:11 AM				
Nunez, Arturo		Requested by Bea Marquez Rm. 327 Academic Building -Girl's Restroom sink is clogged.							
Velia Alarcon									
129146	Varsity Gym	Restroom (Girls)			2/23/2015		51		\$0.00
Medium	Work In Progress				2/23/2015 9:09:53 AM				
Nunez, Arturo		varsity gym girls coaches office restroom toilet not working tudy already knows about it							
Isaac Holguin									
126051	Boys Gym	Dressing Room			12/1/2014		135		\$0.00
Medium	Work In Progress	Boys Football			12/1/2014 1:35:09 PM				
Nunez, Arturo		Requested by Coach J. Vasquez for Football Locker Room in Boy's Gym - Painting of both locker rooms.							
Velia Alarcon									
126221		Dressing Room			12/4/2014		132		\$0.00
Medium	Work In Progress				12/4/2014 9:06:09 AM				
Nunez, Arturo		Requested by Coach J. Vasquez for Football Locker Rooms in Boy's Gym - Fix Lockers.							
Velia Alarcon									
129676					3/3/2015		43		\$0.00
Medium	Work In Progress				3/3/2015 7:55:21 AM				
Vallejo, Albert		Albert, we need assistance to replace ballasts and lamps around the CTE building and light poles to the south side of campus. We will need 400w MH large base lamps.							
Guillermo Hernandez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
128855					2/12/2015		62		\$0.00
Medium	Work In Progress				2/12/2015 2:49:48 PM				
Orozco, Daniel		AS PER ADELES INSPECTION REPORT - GRATER ATTACHMENTS TO CHOPER DOES NOT WORK.							
Maritza Gonzalez									
128646					2/9/2015		65		\$0.00
Medium	Work In Progress				2/9/2015 7:40:31 AM				
Orozco, Daniel		As per Mr. Bakers inspection report, water on floor by the 3 compartment sink (been a problem for some time).							
Maritza Gonzalez									
119747					7/23/2014		266		\$0.00
Medium	Work In Progress				7/23/2014 10:08:37 AM				
Orozco, Daniel		WARMER-OLD FAVORITES-INSIDE HAS FALLEN. SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
128830					2/12/2015		62		\$0.00
Medium	Work In Progress				2/12/2015 7:48:40 AM				
Orozco, Daniel		ZIA NEON AND RED AND GREEN CHILE NEON LIGHTS IN CAFETERIA ARE FLICKERING. SNP MANAGER FRANCES B. 882.5522				2/24/15 As per Enrique, route to Danny O.			
Maritza Gonzalez									
123327					9/26/2014		201		\$0.00
Medium	Work In Progress				9/26/2014 3:51:00 PM				
Orozco, Daniel		Walk-in floor has lifted – safety issue. SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
123328					9/26/2014		201		\$0.00
Medium	Work In Progress				9/26/2014 3:51:26 PM				
Orozco, Daniel		Mop sink is leaking from the floor.SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
119303	Auto Shop				7/11/2014		278		\$0.00
Medium	Work In Progress				7/11/2014 12:42:51 PM				
Sotelo, Enrique		NEED FOR ELECTRICAL POWER TO BE INSTALLED FOR NEW LIFT.							
Gerardo Marquez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

130516					3/24/2015		22		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				3/24/2015 1:41:33 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique Please remove broken old light pole bases and install new light poles, one by the cafeteria and the other between Academic building and North building.

Guillermo Hernandez

122944					9/18/2014		209		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/18/2014 7:38:30 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique Need to replace burn out lamps on the south side of school, area by the swimming pool. This area has now 4 lights out and one by grounds. Need bucket truck.

Guillermo Hernandez

130343					3/19/2015		27		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/19/2015 7:34:37 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique Need to check cord reels in the welding shop, currently there are two cord reels that are not working.

Guillermo Hernandez

126662	North Building				12/16/2014		120		\$0.00
--------	----------------	--	--	--	------------	--	-----	--	--------

High	Work In Progress				12/16/2014 10:14:03				
------	------------------	--	--	--	---------------------	--	--	--	--

Sotelo, Enrique need lighting on the west wall of the rotc building. very dark at night. thank you

Michael Munoz

127022					1/5/2015		100		\$0.00
--------	--	--	--	--	----------	--	-----	--	--------

High	Work In Progress				1/5/2015 7:42:35 AM				
------	------------------	--	--	--	---------------------	--	--	--	--

Sotelo, Enrique Need to replace ballasts or lamps to the outside lights of the weight room, this area is to dark at night.

Guillermo Hernandez

131198	Pool Dressing	Pool			4/10/2015		5		\$0.00
--------	---------------	------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/10/2015 1:48:20 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillemo 4/10/15
Need bldg. mechanics help to repaint the 4 exterior doors to pool dressing rooms building in order to get ready for the annual pool inspection in May. Thanks

Raul Sanchez

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

131105	Concession	Football Field			4/8/2015		7		\$0.00
--------	------------	----------------	--	--	----------	--	---	--	--------

Medium	Work In Progress				4/8/2015 1:51:22 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Hernandez, Guillermo
Please remove the stove from the concession stand by the football field to meet requirements by the NM State Fire Marshal Office as it does not meet code. Please deliver stove to the PPD for storage. If the stove is required in the future, have GHS Administration enter a work order so that it can be reinstalled to meet code. If you have any questions please call Ralph Gallegos. Thanks

Dominique Esparza

129183					2/23/2015		51		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/23/2015 3:32:32 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillermo
Need to replace hanging fluorescent light in the cafeteria.

Guillermo Hernandez

129907					3/9/2015		37		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/9/2015 12:35:39 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillermo
Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.

Margret Villalobos

129324					2/26/2015		48		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/26/2015 7:40:34 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillermo
Need assistance to troubleshoot H/C unit for the Library.

Guillermo Hernandez

130787					4/5/2015		10		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/5/2015 12:29:11 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillermo
Yearly - Gadsden HS A13 (Ceil/Wall Unit)(Yearly) - Refer to PM schedule details.

Margret Villalobos

130342					3/19/2015		27		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/19/2015 7:30:34 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillermo
Need to order 4 1/2 inch metal flushing guard for the swimming pool roof.

Guillermo Hernandez

130826					4/5/2015	4/13/2015	10		\$0.00
--------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/5/2015 12:29:32 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillermo
Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.

Margret Villalobos

4/15/2015 3:50:37 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

129431 2/28/2015 3/31/2015 46 \$0.00

Medium Work In Progress 2/28/2015 12:34:44 AM

Hernandez, Guillermo Yearly - Gadsden HS C-11 (Evap.Condnser)(Yearly) - Refer to PM schedule details.

Margret Villalobos

130946 4/5/2015 4/11/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:30:37 AM

Hernandez, Guillermo Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

130917 4/5/2015 4/13/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:30:22 AM

Hernandez, Guillermo Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

131331 4/13/2015 2 \$0.00

Medium Work In Progress 4/13/2015 4:09:15 PM

Hernandez, Guillermo Requested by Ms. Lam Rm. 604 New Science Building- Replace electric outlet on the south east corner of the lab bench.

Velia Alarcon

131108 4/8/2015 7 \$0.00

Medium Work In Progress 4/8/2015 2:48:18 PM

Hernandez, Guillermo For Building Mechanic to please remove washers where lock attaches on the patio gate in room 518. Please see e-mail for picture of problem. For more information visit with Mr. Martin for details or call Ralph Gallegos.

Dominique Esparza

131270 4/13/2015 2 \$0.00

Medium Work In Progress 4/13/2015 12:26:50 AM

Hernandez, Guillermo Daily - Gadsden HS - Fire Pump (Biweekly) - Refer to PM schedule details.

Margret Villalobos

131155 Classroom 4/9/2015 6 \$0.00

Medium Work In Progress 616 4/9/2015 3:40:37 PM

Hernandez, Guillermo Requested by Mr. Contaldo Rm. 616 New Science Building-A/C unit already fixed, but it had not been working.

Velia Alarcon

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

131158	North Building	Classroom			4/9/2015		6		\$0.00
--------	----------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	210			4/9/2015 3:41:48 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Hernandez, Guillermo Requested by Mr. Munoz Rm. 210 North Building-Put up a bulletin board.

Velia Alarcon

131163	Academic Bldg	Classroom			4/9/2015		6		\$0.00
--------	---------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress				4/9/2015 3:47:47 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Hernandez, Guillermo Requested by Ms. Moreno Rm. 322 Academic Building- Still does not have a/c in classroom.

Velia Alarcon

131421	Academic Bldg	Classroom			4/15/2015		0		\$0.00
--------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/15/2015 9:03:24 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillermo Requested by Ms. Hart Rm. 314 Academic Building-A/C does not work. It is not cooling the room at all.

Velia Alarcon

131402					4/14/2015		1		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/14/2015 3:45:41 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillermo Please assist contractor to gain access to building and check motors for auto shop and construction shop.

Guillermo Hernandez

131090		Parking Lot			4/8/2015		7		\$0.00
--------	--	-------------	--	--	----------	--	---	--	--------

Medium	Work In Progress				4/8/2015 10:38:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillermo Requested by Mr. D. Martinez for Fence Along the South Side of the Fence-Requesting to have "No Parking" signs placed on the fence along the south side of campus. This will be a no parking zone. At this time there are many cars parking on this side and this is creating a safety hazard on campus.

Velia Alarcon

131397					4/14/2015		1		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/14/2015 3:41:18 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillermo Please check A/C for Academic #314.

Guillermo Hernandez

127137					1/6/2015		99		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/6/2015 3:36:00 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo Requested by Mr. Enriquez Rm. 500 New CTE Building- Need to level floor in shop to install a twin port lift.

Velia Alarcon

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
120351					8/3/2014		255		\$0.00
Medium	Work In Progress				8/3/2014 12:33:49 AM				
Munoz, Michael		Yearly - Gadsden HS Fire Ext. Insp. (Yearly) - Refer to PMschedule details.				PMnot completed as per schedule			
Margret Villalobos									
129019	North Building	Kitchen			2/18/2015		56		\$0.00
Medium	Work In Progress				2/18/2015 9:28:00 AM				
Villalobos, Margret		Requested by Mrs. Lerna Rm. 206 & 207 North Building - There is a mice and ant infestation in the kitchen labs.				Emailed			
Velia Alarcon									
127810					1/22/2015		83		\$0.00
Medium	Work In Progress				1/22/2015 2:52:14 PM				
Munoz, Michael		Could you please purchase new sewing machines for new sewing lab. Purchase 4							
Michael Munoz									
129446					2/28/2015		46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:54 AM				
Munoz, Michael		Yearly - Gadsden HS - Fire Pump Inspection - Refer to PMschedule details.							
Margret Villalobos									
126977					1/4/2015		101		\$0.00
Medium	Work In Progress				1/4/2015 12:41:36 AM				
Munoz, Michael		Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PMschedule details.							
Margret Villalobos									
130969					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:50 AM				
Villalobos, Margret		Monthly - Gadsden HS - Enviro Controls Quarterly - Refer to PMschedule details.							
Margret Villalobos									
131206					4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 2:54:03 PM				
Apodaca, Mario		GHS annual pool inspection for 2015							
Mario Apodaca									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
129406	Pool Pump	Pump House			2/27/2015		47		\$0.00
Medium	Work In Progress				2/27/2015 2:57:02 PM				
Apodaca, Mario		need to order pool water testing chemicals and pool supplies							
Mario Apodaca									
131301	Pool Pump	Pump House			4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 2:38:50 PM				
Apodaca, Mario		need to replacethe life guard rescue tude at the ghs pool							
Mario Apodaca									
129123	Pool Pump	Pool			2/20/2015		54		\$0.00
Medium	Work In Progress				2/20/2015 2:50:50 PM				
Apodaca, Mario		Need to order wind screen to install is a canopy for shade on pool deck for this coming season							
Mario Apodaca									
126410		Classroom			12/9/2014		127		\$0.00
Medium	Work In Progress				12/9/2014 11:45:08 AM				
Munoz, Michael		could you please services all sewing machines in the sewing lab. thank you							
Velia Alarcon									
130840					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:40 AM				
Munoz, Michael		Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PMschedule details.							
Margret Villalobos									
130517					3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 1:44:33 PM				
Lara, Ralph		Rafa, grounds need an extra padlock key #157 for the baseball field.							
Guillermo Hernandez									
130512					3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 12:11:49 PM				
Lara, Ralph		Need to replace the core for the door in Old English #130 and the storage bythe entrance on the west side bythe girls restrooms.							
Guillermo Hernandez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

130522 Athletic Field 3/24/2015 22 \$0.00

Medium Work In Progress 3/24/2015 3:20:30 PM

Lara, Ralph need pad lock for gate at soccer field.

Guadalupe Ontiveros

131136 4/9/2015 6 \$0.00

Medium Work In Progress 4/9/2015 8:34:19 AM

Lara, Ralph For GHS room 518 please order and install an "Electronic Delayed Egress Panic (self-contained) with 15 second delay" panic bar at the main door. For More details please visit with Mr. Thomas Martin at GHS or contact Mr. Ralph Gallegos at 575- 882-6921. Thank You

Dominique Esparza

119630 7/21/2014 268 \$0.00

Medium Work In Progress 7/21/2014 10:01:42 AM

Flores, Pete Requested by Mr. Smythe-Ag. tractor needs to be serviced. Engine oil and filter need to be replaced. Both batteries need to be replaced. Hydraulic/trans fluid and filters need to be changed/replaced. Inner and outer air filters need to be replaced. Cab fresh air filters need to be replaced. Injection pump needs to be repaired; fuel system will not hold a prime. Air filter bowl needs to be replaced as well, broken at base. All grease fittings need to be examined in order to take grease.

Velia Alarcon

130496 3/24/2015 22 \$0.00

Medium Work In Progress 3/24/2015 8:44:57 AM

Lara, Ralph NEED GATE KEY TO ISSUE TO EL PASO DISPOSAL, O.K. ASP ALFREDO.

Mary Sitters

131113 Main Building Restroom 4/8/2015 7 \$0.00

Medium Work In Progress 4/8/2015 3:31:02 PM

Lara, Ralph Requested by Velia for New Main Building Faculty Restrooms-Five keys are needed for both the men's and women's faculty restrooms.

Velia Alarcon

125272 11/7/2014 159 \$0.00

Medium Work In Progress 11/7/2014 9:03:59 AM

Sanchez, Raul Domestic Water Well #1 - install sanitary seal properly around electrical wires.

Alfredo Holguin

4/15/2015 3:50:37 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

130669 Grounds Shop Exterior 3/27/2015 19 \$0.00

Medium Work In Progress 3/27/2015 2:48:02 PM

Sanchez, Raul 03/27/15
The wastewater techs need the assistance of an electrician & a welder's winch truck to help us disconnect a burned -out blower motor, lift it out & put new motor in place. ASAP

Raul Sanchez

128198 1/31/2015 74 \$0.00

Medium Work In Progress 1/31/2015 12:39:15 AM

Sanchez, Raul Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.

Margret Villalobos

128889 2/13/2015 61 \$0.00

Medium Work In Progress 2/13/2015 7:51:06 AM

Lara, Ralph Rafa, we need 24 door stops the ones that we talked about to prevent the V. Gym doors from being damaged.

Guillermo Hernandez

128733 2/10/2015 64 \$0.00

Medium Work In Progress 2/10/2015 1:36:34 PM

Lara, Ralph Requested by Ms. Scott-Mailbox # 84 is not opening easily with the key assigned to the teacher or the spare in the key box.

Velia Alarcon

130935 4/5/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:30:31 AM

Sanchez, Raul Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.

Margret Villalobos

129492 3/1/2015 45 \$0.00

Medium Work In Progress 3/1/2015 12:45:54 AM

Sanchez, Raul Monthly - Gadsden HS - Grease Trap (Culinary/Auto) - Refer to PM schedule details.

Margret Villalobos

129461 2/28/2015 46 \$0.00

Medium Work In Progress 2/28/2015 12:35:04 AM

Sanchez, Raul Monthly - Gadsden HS - Monthly Meter Readings - Refer to PM schedule details.

Margret Villalobos

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

129584 3/1/2015 45 \$0.00

Medium Work In Progress 3/1/2015 12:46:48 AM

Sanchez, Raul Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.

Margret Villalobos

130808 4/5/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:29:23 AM

Flores, Pete Monthly - GHS-UV-0515 PM Service - Refer to PM schedule details.

Margret Villalobos

121243 Football Field 8/15/2014 243 \$0.00

Medium Work In Progress 8/15/2014 9:53:18 AM

Ontiveros, Guadalupe Need to place lines on the middle grass field so the football team can practice.

William Dickson

129976 3/10/2015 36 \$0.00

Medium Work In Progress 3/10/2015 7:37:05 AM

Ontiveros, Guadalupe Need to level ground by the stairs on the southwest entrance of the Old English.

Guillermo Hernandez

129977 3/10/2015 36 \$0.00

Medium Work In Progress 3/10/2015 7:39:01 AM

Ontiveros, Guadalupe Lupe, we need assistance pruning trees in the patio inside the Academic building.

Guillermo Hernandez

131307 4/13/2015 2 \$0.00

Medium Work In Progress 4/13/2015 3:18:17 PM

Ontiveros, Guadalupe Requested by Mr. Dickson-ATTENTION LUPE ONTIVEROS. We need bleachers to be transported from different schools for the "Every 15 Minutes" presentation by or before April 29, 2015.

Velia Alarcon

131308 4/13/2015 2 \$0.00

Medium Work In Progress 4/13/2015 3:20:35 PM

Ontiveros, Guadalupe Requested by Coach Letz for Tennis Courts-We have Home District Tennis Matches on April 18, 11, and 28. Court need to be blown off and wind screen on Court #1 tied down.

Velia Alarcon

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

Location: Gadsden HS									
122352					9/4/2014		223		\$0.00
Medium	Work In Progress				9/4/2014 3:46:33 PM				
Ontiveros, Guadalupe	Need to replace about 200 ft. of 3 ft. high fence on the foot ball field visitors side, fence is facing the football field. Safety issue.								
Guillermo Hernandez									
131235					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:37 AM				
Holguin, Isaac	Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.								
Margret Villalobos									
127401					1/12/2015		93		\$0.00
Medium	Work In Progress				1/12/2015 2:37:01 PM				
Ontiveros, Guadalupe	Requested by Coach Lawrence for Grass Soccer Field- Update watering system to automatic system. Talked to Lupe Ontiveros and he agreed to it.								
Velia Alarcon									
125866		Athletic Field			11/21/2014		145		\$0.00
Medium	Work In Progress				11/21/2014 3:30:35 PM				
Ontiveros, Guadalupe	Requested by Ms. L. Chavez for Softball Field-Warning track needs to be widened and then red dirt needs to replace the sand that was placed there when warning tracks was added. The spoiler in that area floods the warning track area between left field foul line and scoreboard. This is also a safety issue for all softball players.								
Velia Alarcon									
119592		Athletic Field			7/18/2014		271		\$0.00
Medium	Work In Progress				7/18/2014 2:08:10 PM				
Ontiveros, Guadalupe	Would like to get the grass fields line for competition. First field should be lined as a soccer field and the other lined up as football fields. Thank you!								
William Dickson									
130538					3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 3:48:26 PM				
Ambriz, Jose	Need assistance to trouble shoot dampers for the V. Gym, having problems with the west side heating units.								
Guillermo Hernandez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
Location: Gadsden HS									
131325					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 3:53:02 PM				
Ambriz, Jose	Need assistance to replace high voltage/3 ph motor for the commercial A/C unit #5. cafeteria area.								
Guillermo Hernandez									
131215					4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 3:47:18 PM				
Ambriz, Jose	Please check H/C unit for Room #216. I started trouble shooting unit due to burned transformer.								
Guillermo Hernandez									
128750					2/10/2015		64		\$0.00
Medium	Work In Progress				2/10/2015 3:38:06 PM				
Ambriz, Jose	Need some assistance on looking for Freon leak in walk in freezer in flower shop.								
Arturo Nunez									
129925					3/9/2015		37		\$0.00
Medium	Work In Progress				3/9/2015 7:35:33 AM				
Ambriz, Jose	Joe, we need to replace the t-stat (5 wires) for the fan coils in the girls gym.								
Guillermo Hernandez									
123810	Library	Library			10/7/2014		190		\$0.00
Medium	Work In Progress				10/7/2014 12:59:31 PM				
Estrada, Jesus	Requested by Matt Grubaugh for Library-The carpet in the library continues to come up. He's afraid students are going to trip on it and hurt themselves.				3/18/15 - ASP CHUY, WAITING ON QUOTE FROM CASY CARPETS				
Velia Alarcon									
130991		Gym			4/6/2015		9		\$0.00
Medium	Work In Progress				4/6/2015 11:33:56 AM				
Estrada, Jesus	varnish (3) gym floors								
Jesus Estrada									
Count: 113 Work Orders		Avg. Age of WO's 66		Total for Gadsden HS		0		\$0.00	

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
130992		Gym			4/6/2015		9		\$0.00
Medium	Work In Progress				4/6/2015 11:35:28 AM				
Estrada, Jesus		varnish gym floor							
Jesus Estrada									
127468	Main Building	Hallway/Corridor			1/13/2015		92		\$0.00
Medium	Work In Progress				1/13/2015 11:15:04 AM				
Estrada, Jesus		New to replace (VCT tile) in west wing tile is coming up and un done pieces of VCT missing							
Mario Herrera									
127469	Main Building	Hallway/Corridor			1/13/2015		92		\$0.00
Medium	Work In Progress				1/13/2015 11:17:19 AM				
Estrada, Jesus		Need to replace VCT tile is coming up and breaking off in different sections							
Mario Herrera									
127470	Main Building	Hallway/Corridor			1/13/2015		92		\$0.00
Medium	Work In Progress				1/13/2015 11:18:30 AM				
Estrada, Jesus		VCT tile needs to be replaced cracking and coming off							
Mario Herrera									
130523		Athletic Field			3/24/2015		22		\$0.00
High	Work In Progress				3/24/2015 3:23:23 PM				
Vasquez, Jose		need to run new wires to electric valves for baseball field.							
Guadalupe Ontiveros									
131291					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 11:42:38 AM				
Carbajal, Jimmy		wet n dry S# 1587885 is not sucking							
Mario Herrera									
131292					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 11:43:28 AM				
Carbajal, Jimmy		wet n dry S# 1372817 is not sucking							
Mario Herrera									
131293					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 11:45:08 AM				
Carbajal, Jimmy		Roto BFR201150944 doesn't throw water							
Mario Herrera									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
130650					3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 8:36:26 AM				
Carbajal, Jimmy		Need Propane tank re filled for burnisher							
Mario Herrera									
130499	Main Building				3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 8:53:00 AM				
Estrada, Jesus		Requesting new VTC flooring in office 168A							
Mario Herrera									
130500	Main Building				3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 8:54:04 AM				
Estrada, Jesus		Requesting new VCT Flooring in Attendance office							
Mario Herrera									
126661					12/16/2014		120		\$0.00
Medium	Work In Progress				12/16/2014 10:07:58				
Ontiveros, Guadalupe		please clean courtyard where planters are at and remove Chinese elm. also will need a run off for proper drainage. would like floor covering and grave/rock on top. please see mike for details							
Michael Munoz									
131276					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 8:09:29 AM				
Ontiveros, Guadalupe		patches of grass behind main building "in front of portables" would like for those to be removed							
Mario Herrera									
121935					8/28/2014		230		\$0.00
Medium	Work In Progress				8/28/2014 3:44:19 PM				
Ontiveros, Guadalupe		Need to bring tractor use for water damage on vocational and front A wing thank you							
Sebastian Diaz									
128957					2/17/2015		57		\$0.00
Medium	Work In Progress				2/17/2015 10:48:14 AM				
Marquez, Gerardo		Need to replace main entrance doors AB thank you							
Sebastian Diaz									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden MS

130188					3/16/2015		30		\$0.00
Medium	Work In Progress				3/16/2015 11:44:19 AM				
Marquez, Gerardo	AS PER THE STATE FIRE INSPECTOR PLEASE CHECK ALL EXTERIOR DOORS THROUGH OUT ENTIRE GADSDEN MIDDLE CAMPUS FOR PROPER FUNCTION. FIX ANY PROBLEMS THAT ARE FOUND. SHOULD YOU HAVE ANY QUESTIONS PLEASE CONTACT MR. RALPH GALLEGOS AT 575-882-6921 IN THE CONSTRUCTION OFFICE.								

Dominique Esparza

119660					7/21/2014		268		\$0.00
High	Work In Progress				7/21/2014 3:36:20 PM				
Sanchez, Raul	***The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house***								

Company: CD MECHANICAL
 Contact Name: DEAN POGUE Contact Phone: (575)382-8474
 State: NM County: DONA ANA City: RURAL
 DONA ANA
 Address: 1301, WASHINGTON ST
 Nearest Intersecting Street: BERRY RD
 2nd Intersecting Street: GRACIE PL
 Subdivision: GASDEN MIDDLE SCHOOL
 Latitude: 31.99971983 Longitude: -106.63006583
 Zip Code: 88021
 Township: 26S Range: 03E Section 1/4: 34 SW

Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS. - SPOT ON THE E.SIDE OF PROPERTY, IN THE PONDING AREA BETWEEN THE WATER STORAGE TANK AND THE GYM.

Dominique Esparza

125237	Gym				11/6/2014		160		\$0.00
Medium	Work In Progress				11/6/2014 2:41:40 PM				
Munoz, Michael	The new bleachers not working on the gym thank you								

Sebastian Diaz

130937					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:32 AM				
Apodaca, Mario	Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.								

Margret Villalobos

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden MS							
125852		Pump House			11/21/2014		145		\$0.00
Medium	Work In Progress				11/21/2014 2:42:53 PM				
Apodaca, Mario		need to run new control wires to the gms irrigation tank							
Mario Apodaca									
131243					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:41 AM				
Herrera, Mario		Monthly - QRTLY BLDG INSP REPORT (GM) - Refer to PM schedule details.							
Margret Villalobos									
129869	Main Building				3/6/2015		40		\$0.00
Medium	Work In Progress				3/6/2015 10:49:55 AM				
Herrera, Mario		Need to strip and wax front office during spring break							
Mario Herrera									
130330					3/18/2015		28		\$0.00
Medium	Work In Progress				3/18/2015 3:45:32 PM				
Solis, Lorenz		Need to check A/C duct on locker room boy's thank you							
Sebastian Diaz									
128617					2/6/2015		68		\$0.00
Medium	Work In Progress				2/6/2015 3:46:24 PM				
Solis, Lorenz		Need to fix pump on boiler room eastside thank you							
Sebastian Diaz									
131400					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 3:44:57 PM				
Solis, Lorenz		Need to check A/C on annex bldg. thank you							
Sebastian Diaz									
129586					3/1/2015		45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:49 AM				
Apodaca, Mario		Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
128187					1/31/2015		74		\$0.00
Medium	Work In Progress				1/31/2015 12:39:07 AM				
Apodaca, Mario		Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.				PM not performed as per schedule 2/9/15			
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
130748					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:14 AM				
Apodaca, Mario Monthly - Gadsden MS - Monthly Meter Readings - Refer to PM schedule details.									
Margret Villalobos									
129508					3/1/2015	3/17/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:04 AM				
Villalobos, Margret Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details. 3/2 - Emailed									
Margret Villalobos									
130859					4/5/2015	4/21/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:49 AM				
Villalobos, Margret Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details.									
Margret Villalobos									
131002		Classroom			4/6/2015		9		\$0.00
Medium	Work In Progress	room 139			4/6/2015 2:26:07 PM				
Marquez, Gerardo Need to check door cylinder. Not working.									
Nancy Tinajero									
131082					4/8/2015		7		\$0.00
Medium	Work In Progress				4/8/2015 8:24:29 AM				
Marquez, Gerardo Need to open vault asp Connie.									
Connie Avalos									
131374	Band Room				4/14/2015		1		\$0.00
Medium	Work In Progress	room 100			4/14/2015 10:18:06 AM				
Marquez, Gerardo Please check key core on guitar case in band room.									
Nancy Tinajero									
131372					4/14/2015		1		\$0.00
Medium	Work In Progress	front office			4/14/2015 10:14:46 AM				
Marquez, Gerardo Check key core in the front office. The key is getting stuck.									
Nancy Tinajero									
130651	C-Wing				3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 8:37:56 AM				
Marquez, Gerardo Please install cores on the new Dr. dogging devices.									
Gerardo Marquez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
119972					7/29/2014		260		\$0.00
Medium	Work In Progress	front office			7/29/2014 10:04:45 AM				
Marquez, Gerardo		Need key (A-57) for custodian							
Nancy Tinajero									
119973					7/29/2014		260		\$0.00
Medium	Work In Progress	front office-			7/29/2014 10:06:01 AM				
Marquez, Gerardo		Need Keys for new PE teacher, WA-62, V-8, WA-64, 01, V-15, one each please.							
Nancy Tinajero									
128784	Main Building	Library			2/11/2015		63		\$0.00
Medium	Work In Progress	Library storage			2/11/2015 11:18:55 AM				
Marquez, Gerardo		Need WA-27 key replaced. Broken key in lock.							
Nancy Tinajero									
128786		Library			2/11/2015		63		\$0.00
Medium	Work In Progress	library front			2/11/2015 1:07:51 PM				
Marquez, Gerardo		Adjust the front doors in the library							
Nancy Tinajero									
125614	Main Building	Classroom			11/17/2014		149		\$0.00
Medium	Work In Progress	room 169			11/17/2014 9:24:51 AM				
Marquez, Gerardo		Need a half door installed in room 169 for student safety.							
Nancy Tinajero									
124293		Classroom			10/17/2014		180		\$0.00
Medium	Work In Progress	room 148			10/17/2014 11:47:27				
Marquez, Gerardo		Classroom entry door needs to be adjusted.							
Nancy Tinajero									
131300		Gym			4/13/2015		2		\$0.00
Medium	Work In Progress	East new gate			4/13/2015 2:33:15 PM				
Marquez, Gerardo		Mr. Coles, Security, needs key to lock to new east gate behind baseball field.							
Nancy Tinajero									
130761	C-Wing				3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 10:26:34 AM				
Sotelo, Enrique		CR on NE Corner - provide outlets for computers							
Alfredo Holguin									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
131341	C-Wing				4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 7:42:19 AM				
Sotelo, Enrique		Please line locate area mark in white by 1st gate by C-Wing. (Any ?'s see Sal)							
Albert Vallejo									
127838					1/23/2015		82		\$0.00
Medium	Work In Progress				1/23/2015 10:15:02 AM				
Sotelo, Enrique		Need to enough power for meting on cafeteria FEB 6 thank you							
Sebastian Diaz									
125851		Pump House			11/21/2014		145		\$0.00
Medium	Work In Progress				11/21/2014 2:41:06 PM				
Sotelo, Enrique		need to pull new control wires for the switch float at the gms irrigation tank							
Mario Apodaca									
130986	C-Wing	Classroom			4/6/2015		9		\$0.00
Medium	Work In Progress				4/6/2015 11:00:30 AM				
Sotelo, Enrique		Room on NE corner needs to wire as lab for computers.							
Alfredo Holguin									
129825					3/5/2015		41		\$0.00
Medium	Work In Progress				3/5/2015 11:54:05 AM				
Orozco, Daniel		As per Mr. Baker, please place a work order for both walk-in freezer and fridge. The doors don't close properly. He would like to see them close on their own. Thank you!							
Maritza Gonzalez									
131086					4/8/2015		7		\$0.00
Medium	Work In Progress				4/8/2015 9:38:13 AM				
Carrasco, Danny		Need two speed motor for A/C locker room boy's thank you							
Sebastian Diaz									
131103					4/8/2015		7		\$0.00
Medium	Work In Progress				4/8/2015 1:29:07 PM				
Carrasco, Danny		Danny; NEED TO ORDER Vbelt A97& 4199 thank you							
Sebastian Diaz									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

131085					4/8/2015		7		\$0.00
Medium	Work In Progress				4/8/2015 9:08:27 AM				

Orozco, Daniel
 Maritza Gonzalez
 GARBAGE DISPOSAL NOT DISPENSING WATER. SNP MANAGER TERRY P. 882.2824

131375					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 10:20:36 AM				

Orozco, Daniel
 Maritza Gonzalez
 GARBAGE DISPOSAL LEAKING GOING INTO DINING ROOM. SNP MANAGER TERRY P. 882.2824

127753					1/21/2015		84		\$0.00
Medium	Work In Progress				1/21/2015 11:25:29 AM				

Orozco, Daniel
 Maritza Gonzalez
 WALK IN FREEZER RAMP NEEDS TO BE REPAIRED, IT LIFTS AND KEEP DOOR AJAR. SNP MANAGER TERRY P. 882.2824

127754					1/21/2015		84		\$0.00
Medium	Work In Progress				1/21/2015 11:28:32 AM				

Orozco, Daniel
 Maritza Gonzalez
 RACKS IN WARMING CABINET NEED ANCHORS RACKS ARE LOOSE AND CAN CAUSE SOMEONE TO GET BURNED. SNP MANAGER TERRY P. 882.2824

127946					1/26/2015		79		\$0.00
Medium	Work In Progress				1/26/2015 2:43:41 PM				

Orozco, Daniel
 Maritza Gonzalez
 MILK MACHIINE BROKEN, DOOR HANGING OFF HINGES. SNP MANAGER TERRY P. 882.2824

131342	C-Wing				4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 7:43:05 AM				

Villalobos, David
 Albert Vallejo
 Please line locate area mark in white by 1st gate by C-Wing. (Any ?'s see Sal)

131403					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 3:46:21 PM				

Villalobos, David
 Sebastian Diaz
 Need to check domestic water heater for restrooms thank you

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
124628		Gym			10/27/2014		170		\$0.00
Medium	Work In Progress	baseball field			10/27/2014 2:00:21 PM				
Villalobos, David Water fountain outside gym area near baseball field is not working.									
Nancy Tinajero									
129886					3/6/2015		40		\$0.00
Medium	Work In Progress				3/6/2015 3:18:16 PM				
Villalobos, David Need to replace sink faucets on B wing thank you									
Sebastian Diaz									
131203	Band Room	Classroom			4/10/2015		5		\$0.00
Medium	Work In Progress	Room 100			4/10/2015 2:32:26 PM				
Villalobos, David Need hot water in band room.									
Nancy Tinajero									
119801	Main Building	Classroom			7/24/2014		265		\$0.00
Medium	Work In Progress	Room 152			7/24/2014 11:57:42 AM				
Villalobos, David Sink is dripping continuously; doesn't drain and is leaking into the cabinet.									
Nancy Tinajero									
124188		Classroom			10/15/2014		182		\$0.00
Safety	Work In Progress	room 129 and			10/15/2014 1:55:35 PM				
Villalobos, David Water is leaking out of the wall between room 129 and 140. Computers are against that wall. Could be a severe electrical shock issue.									
Nancy Tinajero									
124404		Library			10/21/2014		176		\$0.00
Medium	Work In Progress	Library			10/21/2014 12:30:45				
Villalobos, David Clogged sink in library office.									
Nancy Tinajero									
130054		Restroom			3/11/2015		35		\$0.00
Medium	Work In Progress	A wing boys			3/11/2015 3:45:12 PM				
Villalobos, David The faucet in boys restroom is continuously running.									
Nancy Tinajero									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
124709	Gym				10/29/2014		168		\$0.00
Medium	Work In Progress				10/29/2014 7:43:56 AM				
Villalobos, David		Urinals in boys gym locker room do not have water needs to be fixed A.S.A.P in order to clean by custodian right							
Mario Herrera									
124711					10/29/2014		168		\$0.00
Medium	Work In Progress				10/29/2014 7:45:12 AM				
Villalobos, David		Sink in girls restroom next to b-wing and main hallway there is no running water							
Mario Herrera									
121677					8/25/2014		233		\$0.00
Medium	Work In Progress				8/25/2014 8:10:22 AM				
Villalobos, David		Need o replace sink faucet on rest room A wing thank you							
Sebastian Diaz									
121391	Vocational				8/19/2014		239		\$0.00
Medium	Work In Progress				8/19/2014 6:59:54 AM				
Villalobos, David		outside water for water hoses do not work on the whole building							
Mario Herrera									
119501	C-Wing				7/16/2014		273		\$0.00
Medium	Work In Progress				7/16/2014 3:49:11 PM				
Villalobos, David		Portable - Where restrooms are located. There is a leak underneath the sink, water has been shut off for now. Please check this first thing in the morning.							
Mario Herrera									
126893					1/4/2015	2/4/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:40:28 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
129442					2/28/2015	3/31/2015	46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:51 AM				
Diaz, Sebastian		Yearly - Gadsden MS C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
129117	C-Wing				2/20/2015		54		\$0.00
Medium	Work In Progress	Old Central			2/20/2015 10:55:51 AM				
Diaz, Sebastian		Old Central Office							
		Paint newly installed doors and jams							
		Paint or Repaint interior door jams white.							
Margret Villalobos									
130051	Band Room				3/11/2015		35		\$0.00
Medium	Work In Progress	room 100 and			3/11/2015 3:42:21 PM				
Diaz, Sebastian		Fixhole in outside Band room wall and wall outside							
		room 150.							
Nancy Tinajero									
130850					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:45 AM				
Diaz, Sebastian		Monthly - Gadsden MS Roof Inspection - Refer to PM							
		schedule details.							
Margret Villalobos									
130858					4/5/2015	4/8/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:49 AM				
Diaz, Sebastian		Monthly - Gadsden MS - Emerg. Eyewash (Monthly) -							
		Refer to PM schedule details.							
Margret Villalobos									
130252	C-Wing				3/17/2015		29		\$0.00
Medium	Work In Progress	AVECHS			3/17/2015 11:24:15 AM				
Diaz, Sebastian		Primer, paint new walls and patch walls that were							
		remodel.							
Danny Miranda									
130786					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:10 AM				
Diaz, Sebastian		Yearly - Gadsden MS A-13 A/C Wall Mount Yearly -							
		Refer to PM schedule details.							
Margret Villalobos									
130790					4/5/2015	4/21/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:13 AM				
Diaz, Sebastian		Monthly - Gadsden MS A-1 Wall Ref Elec Semiannual -							
		Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
130791					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:13 AM				
Diaz, Sebastian		Monthly - Gadsden MS H-11 Unit Elec Ht Semiannual - Refer to PM schedule details.							
Margret Villalobos									
128092		Cafeteria			1/29/2015		76		\$0.00
Medium	Work In Progress	kitchen			1/29/2015 10:26:35 AM				
Diaz, Sebastian		Repaint damaged rooms. Clean and paint light fixtures that have not been cleaned in the storage area.							
Nancy Tinajero									
128518	C-Wing				2/5/2015		69		\$0.00
Medium	Work In Progress	Old Central			2/5/2015 10:37:36 AM				
Gonzalez, Salvador		Fabricate mail drop box by Old Central Office.							
Richard Chavez									
131018					4/6/2015		9		\$0.00
Medium	Work In Progress				4/6/2015 3:51:09 PM				
Gonzalez, Salvador		Need to replace ramp on portable C wing thank you							
Sebastian Diaz									
130574		Gym			3/25/2015		21		\$0.00
Medium	Work In Progress	Gym			3/25/2015 11:42:43 AM				
Gonzalez, Salvador		Please cover for switch boxes for basketball courts in gym. Please see Sebastian							
Nancy Tinajero									
131364					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 9:02:22 AM				
Gonzalez, Salvador		The poles for the tennis nets on the tennis courts at Gadsden Middle School need to be removed ASAP							
Terry Alvarado									
130520					3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 2:21:42 PM				
Diaz, Sebastian		Margret Need to sent the Company to start the chiller thank you							
Sebastian Diaz									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
130746					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:13 AM				
Diaz, Sebastian		Monthly - Gadsden MS A-16 Fan Exhaust Semiannual - Refer to PM schedule details.							
Margret Villalobos									
130306	Gym	Gym			3/18/2015		28		\$0.00
Medium	Work In Progress	GYM			3/18/2015 10:47:06 AM				
Diaz, Sebastian		Main Basketball Goal frame is coming apart. Also check switch box for practice goal because it will not come up or down.							
Nancy Tinajero									
130448		Athletic Field			3/23/2015		23		\$0.00
Medium	Work In Progress	Baseball			3/23/2015 8:04:49 AM				
Diaz, Sebastian		Baseball dugouts are tagged. Please paint.							
Nancy Tinajero									
125784	Gym				11/19/2014		147		\$0.00
Medium	Work In Progress				11/19/2014 4:24:32 PM				
Diaz, Sebastian		Order window screens for Gym and Gym Lobby. (See Mike)							
Michael Munoz									
128509					2/5/2015		69		\$0.00
Medium	Work In Progress				2/5/2015 8:44:34 AM				
Diaz, Sebastian		Need to replace pads on vocational thank you							
Sebastian Diaz									
130923					4/5/2015	5/6/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:25 AM				
Diaz, Sebastian		Monthly - Gadsden MS - Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
130924					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:25 AM				
Diaz, Sebastian		Monthly - Gadsden MS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Gadsden MS							
130931					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:29 AM				
Diaz, Sebastian	Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
130932					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:30 AM				
Diaz, Sebastian	Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
130958					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:44 AM				
Diaz, Sebastian	Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 95 Work Orders		Avg. Age of WO's		64	Total for Gadsden MS			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
130095	Main Building	Hallway/Corridor			3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 3:03:19 PM				
Ramos, Rudy	Please remove dead bugs from inside light fixture in front of office.								
Jesus Estrada									
131249					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:44 AM				
Ramos, Rudy	Monthly - QRTLY BLDG INSP REPORT (LU) - Refer to PMs schedule details.								
Margret Villalobos									
130667	Main Building	Mechanical			3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 2:22:55 PM				
Villalobos, David	Water heater is rusted and leaking at the bottom - Replace								
Alfredo Holguin									
130277					3/17/2015		29		\$0.00
Medium	Work In Progress				3/17/2015 3:39:15 PM				
Castillo, Carlos	have 2 parking pole lights out and 7 building lights out - need replaced								
Patricio Aguilar									
128739					2/10/2015		64		\$0.00
Medium	Work In Progress				2/10/2015 2:38:17 PM				
Orozco, Daniel	AS PER ADELE'S INSPECTION. SLICER NEEDS REPAIR.								
Maritza Gonzalez									
126360					12/8/2014		128		\$0.00
Medium	Work In Progress				12/8/2014 12:38:51 PM				
Orozco, Daniel	DISHWASHER IS DOWN.SNP MANAGER LINDA Y. 589.2040								
Maritza Gonzalez									
120338					8/3/2014		255		\$0.00
Medium	Work In Progress				8/3/2014 12:33:40 AM				
Munoz, Michael	Yearly - La Union ES Fire Ext. Insp. (Yearly) - Refer to PMs schedule details.								PM not completed as per schedule
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		La Union ES							
131299					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 2:24:18 PM				
Aguilar, Patricio		wo to myself - need to bait grounds for moles - gophers							
Patricio Aguilar									
129460					2/28/2015		46		\$0.00
Medium	Work In Progress				2/28/2015 12:35:03 AM				
Sanchez, Raul		Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details.							
Margret Villalobos									
130754					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:17 AM				
Sanchez, Raul		Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details.							
Margret Villalobos									
131264					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:53 AM				
Aguilar, Patricio		Monthly - La Union ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
130964					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:47 AM				
Aguilar, Patricio		Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
129565					3/1/2015	3/9/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:37 AM				
Aguilar, Patricio		Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
129613					3/1/2015	3/7/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:47:05 AM				
Aguilar, Patricio		Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		La Union ES							
129922					3/9/2015	3/24/2015	37		\$0.00
Medium	Work In Progress				3/9/2015 12:35:49 AM				
Aguilar, Patricio		Monthly - La Union ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
129234					2/24/2015		50		\$0.00
Medium	Work In Progress				2/24/2015 2:09:15 PM				
Aguilar, Patricio		wo to myself - need to replace # to class rooms asper fire marshal							
Patricio Aguilar									
129449					2/28/2015		46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:56 AM				
Aguilar, Patricio		Monthly - La Union ES A-16 Fan Exhaust Semimonthly - Refer to PM schedule details.							
Margret Villalobos									
129438					2/28/2015	3/31/2015	46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:49 AM				
Aguilar, Patricio		Yearly - La Union ES C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
128911					2/13/2015		61		\$0.00
Medium	Work In Progress				2/13/2015 3:22:32 PM				
Aguilar, Patricio		need a elect. out lite replacer in comp. room - 2 elect out lite changed to G F I out lite old wing hall way.							
Patricio Aguilar									
130794					4/5/2015	4/26/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:15 AM				
Aguilar, Patricio		Monthly - La Union ES H-11 Unit Elec Ht Semiannual - Refer to PM schedule details.							
Margret Villalobos									
130315					3/18/2015		28		\$0.00
Medium	Work In Progress				3/18/2015 3:08:10 PM				
Aguilar, Patricio		wo to myself - need to weed and feed grass.							
Patricio Aguilar									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
130844					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:42 AM				
Aguilar, Patricio		Monthly - La Union ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
130915					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:21 AM				
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130916					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:21 AM				
Aguilar, Patricio		Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130928					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:27 AM				
Aguilar, Patricio		Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
129347					2/26/2015		48		\$0.00
Medium	Work In Progress				2/26/2015 1:03:30 PM				
Ontiveros, Joe		water heater mech room old wing leaking from bottom of tank. Will need to be replaced.							
Patricio Aguilar									
Count: 26 Work Orders		Avg. Age of WO's 41			Total for La Union ES			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
130359		Classroom			3/19/2015		27		\$0.00
Medium	Work In Progress				3/19/2015 9:39:31 AM				
Estrada, Jesus	THE CARPETS FROM THESE (7) CLASSROOMS ARE IN VERY BAD SHAPE , ROOMS # 211,213,215,217,218,220 AND 222, AFTER 20 YEARS OLD, WE THINK IS TIME TO REPLACED IT, BUT WITH TILE. (NO CARPET) ALSO IN THE HALLWAYS, WE HAVE SOME TILES THAT NEED TO REPLACED WITH A NEW ONES., THANK YOU.								
Luis Solis									
127636		Office			1/16/2015		89		\$0.00
Medium	Work In Progress	Mr. Smiths			1/16/2015 9:33:57 AM				
Estrada, Jesus	New carpet that was just installed this summer break is alreadytearing, please fix work order # 113380??								
Angie Flores									
131418		Portables			4/15/2015		0		\$0.00
Medium	Work In Progress				4/15/2015 8:23:11 AM				
Marquez, Gerardo	Spec Ed Portable - build shelf for water heater. Check with David V. or Alfredo on specifics.								
Alfredo Holguin									
130127					3/13/2015		33		\$0.00
Medium	Work In Progress				3/13/2015 10:53:59 AM				
Ontiveros, Guadalupe	Lupe need to order several loads of crusher fine for front campus please								
Eric Medina									
130128					3/13/2015		33		\$0.00
Medium	Work In Progress				3/13/2015 10:55:57 AM				
Ontiveros, Guadalupe	Lupe need to order several loads of playground sand for playground in front campus thank you								
Eric Medina									
127477					1/13/2015		92		\$0.00
Medium	Work In Progress				1/13/2015 1:33:17 PM				
Ontiveros, Guadalupe	Pete need to request bobcat								
Eric Medina									
125217					11/6/2014		160		\$0.00
Medium	Work In Progress				11/6/2014 9:09:39 AM				
Ontiveros, Guadalupe	Pete need to request bobcat please								
Eric Medina									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

129988 Main Building 3/10/2015 36 \$0.00

Medium Work In Progress Casianos 3/10/2015 1:02:08 PM

Villalobos, Margret Please fumigate classroom for head lice outbreak 3/10/15 Emailed Waiver Form

Angie Flores

131183 Classroom 4/10/2015 5 \$0.00

Medium Work In Progress 211 & 213 4/10/2015 10:33:58 AM

Villalobos, Margret Please fumigate classrooms 211 & 213 for head lice outbreak notified Watson, o.k. asp alfredo, Mickie to be out there after 3:00/4:00 p.m. today.

Angie Flores

130247 Main Building Classroom 3/17/2015 29 \$0.00

Medium Work In Progress 212,214,220,10 3/17/2015 10:41:46 AM

Villalobos, Margret Need to fumigate classrooms for head lice outbreak

Angie Flores

131275 4/13/2015 2 \$0.00

Medium Work In Progress 4/13/2015 8:03:26 AM

Villalobos, Margret Request to have rooms 211 & 213 fumigated for head lice.

James Lawler

120339 8/3/2014 255 \$0.00

Medium Work In Progress 8/3/2014 12:33:41 AM

Munoz, Michael Yearly - Loma Linda ES Fire Ext. Insp. (Yearly) - Refer to PMschedule details. PMnot completed as per schedule

Margret Villalobos

126973 1/4/2015 1/25/2015 101 \$0.00

Medium Work In Progress 1/4/2015 12:41:33 AM

Munoz, Michael Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PMschedule details.

Margret Villalobos

131242 4/12/2015 4/28/2015 3 \$0.00

Medium Work In Progress 4/12/2015 12:23:41 AM

Solis, Luis Monthly - QRTLY BLDG INSP REPORT (LL) - Refer to PMschedule details.

Margret Villalobos

130836 4/5/2015 4/26/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:29:38 AM

Munoz, Michael Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PMschedule details.

Margret Villalobos

4/15/2015 3:50:38 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

119567 7/18/2014 271 \$0.00

Medium Work In Progress 7/18/2014 10:50:19 AM

Orozco, Daniel BROKEN GLASS ON SERVING LINE.

Maritza Gonzalez

121440 8/19/2014 239 \$0.00

Medium Work In Progress 8/19/2014 3:03:42 PM

Orozco, Daniel LATCH THAT LOCKS THE WALK IN IS BROKEN. SNP
MANAGER DOLORES R. 882.4707

Maritza Gonzalez

128871 2/12/2015 62 \$0.00

Medium Work In Progress 2/12/2015 3:38:53 PM

Orozco, Daniel AS PER ECO-LAB (BUD) DISHWASHER MOTOR
CONTRACTOR ON UPPER CONTROL BOX NEEDS
TO BE REPAIRED CORRECTLY.

Maritza Gonzalez

130079 Hallway/Corridor 3/12/2015 34 \$0.00

Medium Work In Progress 3/12/2015 9:29:09 AM

Sotelo, Enrique WE HAVE SOME LIGTHS OFF FROM THE
HALLWAYS AND TWO BOYSRESTROOMS, ALSO
THE SECURITY LIGTHS FROM THE BUILDING MAIN
ENTRANCE TREE OF FOUR LIGTHS ARE NOT
WORKING PROPERLY IS VERY DARK IN THE
MORNING., THANKS.

Luis Solis

122774 Portables 9/15/2014 212 \$0.00

Medium Work In Progress 9/15/2014 3:36:17 PM

Sotelo, Enrique need to provide power to new washer and drier room ,
and to new restroom. also will need a circuit for a lift
table.

Michael Munoz

127596 Classroom 1/15/2015 90 \$0.00

Medium Work In Progress Arenas, 1/15/2015 1:31:35 PM

Medina, Eric Replace screen for windows in the following classrooms,
Arenas, Talamantez, and Casiano

Angie Flores

129697 Main Building Classroom 3/3/2015 43 \$0.00

Medium Work In Progress 206 3/3/2015 10:31:14 AM

Medina, Eric Broken water faucet

Angie Flores

4/15/2015 3:50:38 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
131257					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:49 AM				
Medina, Eric		Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
130736					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:08 AM				
Medina, Eric		Monthly - Loma Linda ES A16(Fan Exh.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
130577					3/25/2015		21		\$0.00
Medium	Work In Progress				3/25/2015 3:06:55 PM				
Medina, Eric		need to weed and feed feilds							
Eric Medina									
130950					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:39 AM				
Medina, Eric		Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
129915					3/9/2015	3/24/2015	37		\$0.00
Medium	Work In Progress				3/9/2015 12:35:44 AM				
Medina, Eric		Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
130824					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:31 AM				
Medina, Eric		Monthly - Loma Linda ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
130868					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:54 AM				
Medina, Eric		Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Loma Linda ES							
130869					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:54 AM				
Medina, Eric		Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
130870					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:55 AM				
Medina, Eric		Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
130784					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:09 AM				
Medina, Eric		Yearly - Loma Linda ES A13(AC Wall Mount)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
125287	Main Building				11/7/2014		159		\$0.00
Medium	Work In Progress				11/7/2014 11:30:08 AM				
Medina, Eric		east Side exit doors need to be repainted properly							
Alfredo Holguin									
125786					11/19/2014		147		\$0.00
Medium	Work In Progress				11/19/2014 6:23:01 PM				
Medina, Eric		need to replace belt for fan coil in cafe							
Eric Medina									
122493					9/9/2014		218		\$0.00
Medium	Work In Progress				9/9/2014 8:41:31 AM				
Medina, Eric		Soccer Goals- Remove overgrown weeds and order and install new soccer nets.							
Alfredo Holguin									
122497					9/9/2014		218		\$0.00
Medium	Work In Progress				9/9/2014 8:46:31 AM				
Medina, Eric		Pine Trees along rock wall on west side of campus -Pick up pine needles and pine cones							
Alfredo Holguin									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
122498					9/9/2014		218		\$0.00
Medium	Work In Progress				9/9/2014 8:56:19 AM				
Medina, Eric		Portable area sidewalks- Order fill dirt (crusher fines or screenings) and backfill eroded areas next to sidewalks							
Alfredo Holguin									
128394					2/3/2015		71		\$0.00
Medium	Work In Progress				2/3/2015 9:58:58 AM				
Medina, Eric		Need to paint and install covebase in SPED Portable.							
Danny Miranda									
129440					2/28/2015	3/31/2015	46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:50 AM				
Medina, Eric		Yearly - Loma Linda ES C11 (Evap.Condnsr)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
121485					8/20/2014		238		\$0.00
Medium	Work In Progress				8/20/2014 7:41:13 AM				
Marquez, Gerardo		Entrance Door in between 3rd and 6th grade hall, the core broke, its not working at all, need to have this fix so that school can be closed and locked.							
Angie Flores									
120081					7/31/2014		258		\$0.00
Medium	Work In Progress				7/31/2014 9:06:08 AM				
Marquez, Gerardo		Gerrydoor handle in portable 4 was broken by vandals							
Eric Medina									
128725					2/10/2015		64		\$0.00
Medium	Work In Progress	6th Grade			2/10/2015 11:19:10 AM				
Marquez, Gerardo		Cannot open with key, key just turns and turns but does not unlock							
Angie Flores									
123928					10/9/2014		188		\$0.00
Medium	Work In Progress	rm 105			10/9/2014 1:50:51 PM				
Marquez, Gerardo		need to replace classroom door							
Eric Medina									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
130657					3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 10:47:33 AM				
Marquez, Gerardo		Gerry need to replace laundry room door in portable 1a							
Eric Medina									
122754		Pool			9/15/2014		212		\$0.00
Medium	Work In Progress				9/15/2014 10:42:21 AM				
Villalobos, David		As discussed , need to remove com mode and sink in rest room and plumb out for washer and drier, com mode and sink need to be plumbed out in the storage room across existing restroom. will need hot water also.							
Michael Munoz									
129884					3/6/2015		40		\$0.00
Medium	Work In Progress				3/6/2015 2:44:36 PM				
Villalobos, David		David need housing for j3 coupling for circulating pump for water heater							
Eric Medina									
128649	Main Building	Restroom			2/9/2015		65		\$0.00
Medium	Work In Progress				2/9/2015 8:03:22 AM				
Villalobos, David		need to jet main sewer lines through out campus to sewer main							
David Villalobos									
Count: 47 Work Orders		Avg. Age of WO's 88		Total for Loma Linda ES		0		\$0.00	

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Mesquite ES							
130551					3/25/2015		21		\$0.00
Medium	Work In Progress				3/25/2015 6:25:50 AM				
Villalobos, David		we have clogged sewer lines ,need david and the elect. drain auger							
Joe Ramirez									
128001		Mechanical			1/27/2015		78		\$0.00
Medium	Work In Progress				1/27/2015 3:30:39 PM				
Villalobos, David		Need to replace leaking water heater at mechanical room							
David Villalobos									
131279					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 9:07:01 AM				
Carrasco, Danny		Prepare both water tanks and deliver today, water will be shutoff tomorrow.							
Alfredo Holguin									
131281					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 9:11:15 AM				
Carrasco, Danny		Del drinking water and supplies tomorrow morning due to water shutdown.							
Alfredo Holguin									
128416	ArmyBuilding	Classroom			2/3/2015		71		\$0.00
Medium	Work In Progress	classrooms			2/3/2015 3:07:21 PM				
Marquez, Gerardo		Luis Saucedo/Head Custodian, needs C-Master made for classrooms.							
Sandra Mora									
130088					3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 10:38:21 AM				
Sotelo, Enrique		need to install electrical strip in nurses' office							
Joe Ramirez									
130089					3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 10:39:23 AM				
Sotelo, Enrique		need to install electrical strip in computer lab.							
Joe Ramirez									
129930					3/9/2015		37		\$0.00
Medium	Work In Progress				3/9/2015 9:19:40 AM				
Orozco, Daniel		ICE BUILD UP IN FREEZER FLOOR (SAFETY HAZARD). SNP MANAGER EMILIA C. 233-2341							
Maritza Gonzalez									
4/15/2015 3:50:39 PM									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Mesquite ES								
126417					12/9/2014		127		\$0.00	
Medium	Work In Progress				12/9/2014 3:12:51 PM					
Orozco, Daniel		REPLACE WHEELS IN WALK IN AND REFRIGERATOR SHELVES. SNP MANAGER EMILIA C. 233.2341								
Maritza Gonzalez										
128915					2/13/2015		61		\$0.00	
Medium	Work In Progress				2/13/2015 3:27:50 PM					
Orozco, Daniel		AS PER ADELE'S INSPECTION REPORT- BUTTON ON MILK COOLER GETS STUCK.								
Maritza Gonzalez										
130752					3/31/2015		15		\$0.00	
Medium	Work In Progress				3/31/2015 12:38:16 AM					
Apodaca, Mario		Monthly - Mesquite ES - Monthly Meter Readings - Refer to PM schedule details.								
Margret Villalobos										
129590					3/1/2015		45		\$0.00	
Medium	Work In Progress				3/1/2015 12:46:51 AM					
Apodaca, Mario		Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos										
130941					4/5/2015		10		\$0.00	
Medium	Work In Progress				4/5/2015 12:30:34 AM					
Apodaca, Mario		Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos										
131102	Pump House	Pump House			4/8/2015		7		\$0.00	
Medium	Work In Progress				4/8/2015 1:28:27 PM					
Apodaca, Mario		mesquite elementary irrigation well need to troubleshoot control panel								
Mario Apodaca										
120340					8/3/2014		255		\$0.00	
Medium	Work In Progress				8/3/2014 12:33:41 AM					
Munoz, Michael		Yearly - Mesquite ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.					PM not completed as per schedule			
Margret Villalobos										

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Mesquite ES							
128469					2/4/2015		70		\$0.00
Medium	Work In Progress				2/4/2015 12:35:41 PM				
Ontiveros, Guadalupe		eastside fenceline needs to be replaced (poor condition) this will be at the community park.							
Joe Ramirez									
130972					4/6/2015		9		\$0.00
Medium	Work In Progress				4/6/2015 8:24:23 AM				
Ontiveros, Guadalupe		my irrigation system is not working at all need lupe to come and check it thank you							
Joe Ramirez									
130215					3/16/2015		30		\$0.00
Medium	Work In Progress				3/16/2015 3:51:42 PM				
Marquez, Gerardo		we need front door handicap entrance to be repaired it does not open with a push of the button also the door stike and latch are not the right ones.							
Joe Ramirez									
130416		Custodial			3/20/2015		26		\$0.00
Medium	Work In Progress				3/20/2015 8:24:33 AM				
Carbajal, Jimmy		please vaccumm #0089 the motor is not working. thank you							
Luis Saucedo									
131032		Custodial			4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 9:40:46 AM				
Carbajal, Jimmy		please the handle from the vaccum is broken # 0498 there is no power thank you							
Luis Saucedo									
130697					3/30/2015		16		\$0.00
Medium	Work In Progress				3/30/2015 6:31:02 AM				
Ambriz, Jose		need to replace burnt out relays on hvac unit in rm.505							
Joe Ramirez									
121639					8/22/2014		236		\$0.00
Medium	Work In Progress				8/22/2014 1:25:52 PM				
Estrada, Jesus		carpet in portable #601 needs to be repaired.				3/15/15 - ASP CHUY, SCHEDULED FOR 3/23/15			
Luis Saucedo									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
129288		Custodial			2/25/2015		49		\$0.00
Medium	Work In Progress			2/25/2015 1:15:24 PM					
Estrada, Jesus	Mr. Estrada as per Mrs. silvaggio On room # 105 the carpet is torn out as per principal would like to replace it with tile. if it's possible can this be done during the summer break. If you have a chance, could you please stop by and see it. Thank you								
Luis Saucedo									
130743					3/31/2015		15		\$0.00
Medium	Work In Progress			3/31/2015 12:38:12 AM					
Ramirez, Joe	Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
Margret Villalobos									
130943					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress			4/5/2015 12:30:35 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
130919					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress			4/5/2015 12:30:23 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
122438					9/8/2014		219		\$0.00
Medium	Work In Progress			9/8/2014 8:47:31 AM					
Ramirez, Joe	need to paint math intervention rm.								
Joe Ramirez									
130796					4/5/2015	4/21/2015	10		\$0.00
Medium	Work In Progress			4/5/2015 12:29:16 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.								
Margret Villalobos									
130830					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress			4/5/2015 12:29:35 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
130856					4/5/2015		10		\$0.00
Medium	Work In Progress			4/5/2015 12:29:48 AM					
Ramirez, Joe	Monthly - Mesquite ES - Barrack Drainage (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
131250					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress			4/12/2015 12:23:45 AM					
Saucedo, Luis	Monthly - QRTLY BLDG INSP REPORT (MQ) - Refer to PM schedule details.								
Margret Villalobos									
128861					2/12/2015		62		\$0.00
Medium	Work In Progress			2/12/2015 3:19:31 PM					
Ronquillo, Ruben	ramp leading to jungle jim set is in need of replacement there is rust and corrosion (safety issue).								
Joe Ramirez									
Count: 32 Work Orders		Avg. Age of WO's 50			Total for Mesquite ES			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
118856					7/1/2014		288		\$0.00
Medium	Work In Progress				7/1/2014 8:39:58 AM				
Ronquillo, Ruben		(attention ruben ronquillo)progressive plygrd equip-have five broken platform parts 46 1/2 L x5 1/2 W x3 1/2 H beams -also missing stairs-removed by green contractor solutoins-safety hazard-please check into replacment parts-(800-585-3131)@progressive design equip.							
Danny Vega									
122505					9/9/2014		218		\$0.00
Medium	Work In Progress				9/9/2014 10:21:14 AM				
Gonzalez, Salvador		Principal would like to request a metal canopy at the bus turnaround, like the one at STE.							
Maria Hernandez									
130709					3/30/2015		16		\$0.00
Medium	Work In Progress				3/30/2015 12:13:36 PM				
Gonzalez, Salvador		need tabs welded on poles in front of school /for traffic control /on fire lanes -run 1/4 inch armored cable to poles end to end							
Danny Vega									
130153					3/13/2015		33		\$0.00
Medium	Work In Progress				3/13/2015 3:47:08 PM				
Gonzalez, Salvador		need poles welded on to tire rims for volleyball nets 4 ea							
Danny Vega									
131088		Custodial			4/8/2015		7		\$0.00
Medium	Work In Progress				4/8/2015 10:04:06 AM				
Carbajal, Jimmy		need a 50ft water hose. for use of the presure washer and benifit of a school fundraiser car wash.							
Brian Pacheco									
131035		Custodial			4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 10:20:09 AM				
Carbajal, Jimmy		need a refill on propane tank for burnisher.							
Brian Pacheco									
120341					8/3/2014		255		\$0.00
Medium	Work In Progress				8/3/2014 12:33:42 AM				
Munoz, Michael		Yearly - North Valley ES Fire Ext. Insp. (Yearly) - Refer to PMschedule details.				PMnot completed as per schedule			
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		North Valley ES							
126978					1/4/2015		101		\$0.00
Medium	Work In Progress				1/4/2015 12:41:37 AM				
Munoz, Michael		Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
129447					2/28/2015		46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:55 AM				
Munoz, Michael		Yearly - North Valley ES - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
130841					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:40 AM				
Munoz, Michael		Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
127844					1/23/2015		82		\$0.00
Medium	Work In Progress				1/23/2015 10:40:59 AM				
Orozco, Daniel		FLOOR LOOSE INSIDE WALK IN.SNP MANAGER LAURA B. 233.3658							
Maritza Gonzalez									
129291					2/25/2015		49		\$0.00
Medium	Work In Progress				2/25/2015 2:39:24 PM				
Orozco, Daniel		SWITCH COVER TO SKILLET TO TURN ON IS MISSING.SNP MANANGER LAURA B. 233-3658							
Maritza Gonzalez									
130169					3/14/2015		32		\$0.00
Medium	Work In Progress				3/14/2015 12:21:45 AM				
Vega, Danny		Daily - North Valley ES - Fire Pump (Biweekly) - Refer to PM schedule details.							
Margret Villalobos									
129876					3/6/2015		40		\$0.00
Medium	Work In Progress				3/6/2015 1:08:53 PM				
Vega, Danny		need to replace bad sprinklers 12 ea 1-25 hunters ss (adjustable)6 ea 1-25-hunter 36s plus 2 bad silinoids rainbird #20953202							
Danny Vega									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		North Valley ES							
130822					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:30 AM				
Vega, Danny		Monthly - North Valley ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
130949					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:39 AM				
Vega, Danny		Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
130907					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:16 AM				
Vega, Danny		Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
127224					1/8/2015		97		\$0.00
Medium	Work In Progress				1/8/2015 9:45:21 AM				
Sotelo, Enrique		emergency ballast out by hallway by rm 104-girls rr by rm 107-hallway by rm 202 by rm 206-by rm 211-by rm 305-by rm 300 conference- also pipe chase rm rio grand valley							
Danny Vega									
130304		Classroom			3/18/2015		28		\$0.00
Medium	Work In Progress	305			3/18/2015 10:08:11 AM				
Vega, Danny		Please lower a few desks in order to make them all the same height							
Gloria Reyes									
130910					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:18 AM				
Vega, Danny		Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130653					3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 9:04:37 AM				
Vega, Danny		install 1/4 inch armored cables and poles with clamps in front of parking lot front entrance to bldg/remove plastic saw horses/traffic control							
Danny Vega									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		North Valley ES							
130694					3/29/2015		17		\$0.00
Medium	Work In Progress				3/29/2015 12:21:49 AM				
Vega, Danny		Daily - North Valley ES - Fire Pump (Biweekly) - Refer to PMschedule details.							
Margret Villalobos									
131255					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:48 AM				
Vega, Danny		Monthly - North Valley ES Playground Inspection - Refer to PMschedule details.							
Margret Villalobos									
129992					3/10/2015		36		\$0.00
Medium	Work In Progress				3/10/2015 3:20:09 PM				
Vega, Danny		need 4 tires cemented with a pole for volleyball tennis and variuos activitys							
Danny Vega									
129202					2/24/2015		50		\$0.00
Medium	Work In Progress				2/24/2015 8:05:39 AM				
Vega, Danny		need weed and feed fertilizer spread on grass fields- 35ea bags .have clover and other types of weeds taking over grass.							
Danny Vega									
131268					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 12:26:49 AM				
Vega, Danny		Daily - North Valley ES - Fire Pump (Biweekly) - Refer to PMschedule details.							
Margret Villalobos									
131217					4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 3:48:46 PM				
Vega, Danny		set up for district art show at gms /on 4-23-15-take down on 4-27 -15							
Danny Vega									
129168					2/23/2015		51		\$0.00
Medium	Work In Progress				2/23/2015 2:17:23 PM				
Sotelo, Enrique		emergency lamp ballast are out in these mechanical rms byrm 101-109-203-201-207-301-304-303-306-308-311							
Danny Vega									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: North Valley ES

129169 2/23/2015 51 \$0.00

Medium Work In Progress 2/23/2015 2:20:22 PM

Sotelo, Enrique emergency lamp ballast are out in pipe chase rms organ trail by girls restrooms-pecan wing both pipe chases bys and girls

Danny Vega

129712 3/3/2015 43 \$0.00

Medium Work In Progress 3/3/2015 1:11:00 PM

Sotelo, Enrique organ trail emergency ballast in hallway by RM103 AND THROPY CASE

Danny Vega

129713 3/3/2015 43 \$0.00

Medium Work In Progress 3/3/2015 1:12:44 PM

Sotelo, Enrique pecan wing- emergency lamp ballast out by rm201-205-211

Danny Vega

129714 3/3/2015 43 \$0.00

Medium Work In Progress 3/3/2015 1:14:13 PM

Sotelo, Enrique rio grande wing emergency lamp ballast out by electricl rm-byrm 310

Danny Vega

129715 3/3/2015 43 \$0.00

Medium Work In Progress 3/3/2015 1:21:12 PM

Sotelo, Enrique light switch by nurses office there is sparks when turned on also on the one by lounge/total of two(2). please replace

Danny Vega

130492 3/24/2015 22 \$0.00

Medium Work In Progress 3/24/2015 7:52:32 AM

Villalobos, David rm 101-sink faucet wont stop running water/both angle stops are broken and cant find supply lines to this sink /need faucet replacment time delay type 4 inch centers-please help

Danny Vega

120825 Parking Lot 8/8/2014 250 \$0.00

Medium Work In Progress front door area 8/8/2014 12:15:43 PM

Villalobos, David As per Principal, please install a water hose bit in the front of the building. Please visit Principal for specifics.

Priscilla Martinez

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
128098		Classroom			1/29/2015		76		\$0.00
Medium	Work In Progress	Nurse's office			1/29/2015 12:00:31 PM				
Villalobos, David									
As per Mrs. Hernandez, nurse's office is requesting a small hot water heater to provide warm water for washing hands, gargles, etc.									
Gloria Reyes									
131232					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:35 AM				
Pacheco, Brian									
Monthly - QRTLY BLDG INSP REPORT (NV) - Refer to PMs schedule details.									
Margret Villalobos									
126161		Exterior			12/3/2014		133		\$0.00
High	Work In Progress				12/3/2014 9:55:25 AM				
Pacheco, Brian									
Make sure all trash stuck to the fence line is picked up.									
Jesus Estrada									
3/26/15 - RE-ROUTED TO BRIAN AS PER CHUY									
130812					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:25 AM				
Holguin, Alfredo									
Monthly - North Valley ES - Fire Pump Engine - Refer to PMs schedule details.									
Margret Villalobos									
130648					3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 7:53:47 AM				
,									
need exterior and interior of campus bldg sprayed for infestation of spider and small cockroaches									
3/31/15 - approved as per Alfredo, e-mailed Benny (\$150.00)									
Danny Vega									
131385					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 2:08:43 PM				
Ruiz, Maria									
#107 will not start/stand on plygrd field/will not jump start.plz help.									
Danny Vega									
Count: 41 Work Orders		Avg. Age of WO's 55			Total for North Valley ES			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Northern On-Track Pre-K (LM)									
131228					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:33 AM				
Montoya, Adam		Monthly - QRTLY BLDG INSP REPORT (LM/PRE-K) - Refer to PM schedule details.							
Margret Villalobos									
129646	Main Building				3/2/2015		44		\$0.00
Medium	Work In Progress				3/2/2015 3:13:38 PM				
Villalobos, David		DAYCARE CLASSROOMS 112 AND 114, HOT WATER IS NOT WORKING.							
Adam Montoya									
129949					3/9/2015		37		\$0.00
Medium	Work In Progress				3/9/2015 3:02:16 PM				
Villalobos, David		WATER FOUNTAIN BEHIND BUILDING IS CONTINUOUSLY RUNNING, AND LEAKING. SHUT-OFF VALVE IN BOILER ROOM TO PREVENT ANY FURTHER LEAKING.							
Adam Montoya									
131302					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 2:40:08 PM				
Villalobos, David		PLAYGROUND WATER FOUNTAIN SPOUT CAME OFF. AND WATER IS CONTINUOUSLY RUNNING AS PER WORK ORDER 129949. WATER SUPPLY IS SHUT OFF FROM BOILER ROOM.							
Adam Montoya									
130294	Main Building	Hallway/Corridor			3/17/2015		29		\$0.00
Medium	Work In Progress	reception area			3/17/2015 4:36:59 PM				
Vega, Danny		Please remove small bulletin board and replace with new one.							
Concepcion Montalvo									
130948					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:38 AM				
Vega, Danny		Monthly - La Mesa ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
131256					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:48 AM				
Vega, Danny		Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
4/15/2015 3:50:39 PM									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Northern On-Track Pre-K (LM)									
130908					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:17 AM				
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
130909					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:17 AM				
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
130823					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:30 AM				
Vega, Danny	Monthly - La Mesa ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
130936					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:32 AM				
Apodaca, Mario	Monthly - Northern Pre-K -Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
129585					3/1/2015		45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:49 AM				
Apodaca, Mario	Monthly - Northern Pre-K -Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
130751					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:16 AM				
Apodaca, Mario	Monthly - Northern Pre-K - Monthly Meter Readings - Refer to PM schedule details.								
Margret Villalobos									
130978	Main Building	Classroom			4/6/2015		9		\$0.00
Medium	Work In Progress				4/6/2015 8:43:04 AM				
Solis, Lorenzø	CLASSROOM 114 (DAYCARE) - PIPES LEAKING ABOVE DOORWAY. POSSIBLY DUE TO BOILER BEING SHUT DOWN BEFORE SPRING BREAK.								
Adam Montoya									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Northern On-Track Pre-K (LM)									
126790	Main Building				12/19/2014		117		\$0.00
Medium	Work In Progress				12/19/2014 8:00:45 AM				
Ontiveros, Guadalupe	(AS PER THE DAYCARE) NEED SAND DELIVERED FOR FRONT OF BUILDING SANDBOX.								
Adam Montoya									
130493	Main Building				3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 7:57:12 AM				
Solis, Lorenzø	NEED BOILER TURNED OFF.								
Adam Montoya									
Count: 16 Work Orders			Avg. Age of WO's	24	Total for Northern On-Track Pre-K (LM)		0		\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
127534					1/14/2015		91		\$0.00
Medium	Work In Progress				1/14/2015 1:58:36 PM				
Estrada, Jesus		Install new carpet in Julie's office, once office is painted to match Alfredo's carpet.							
Michael Munoz									
127600		Office			1/15/2015		90		\$0.00
Medium	Work In Progress				1/15/2015 3:30:01 PM				
Estrada, Jesus		NEED QUOTE FOR VCT TO BE REPLACED IN PPD FRONT ENTRANCE & OFFICE.							
Jesus Estrada									
129010		Athletic Field			2/18/2015		56		\$0.00
High	Work In Progress				2/18/2015 8:37:22 AM				
Ontiveros, Guadalupe		Dump truck needs tarp replaced in order to transport material.							
Guadalupe Ontiveros									
129929					3/9/2015		37		\$0.00
Medium	Work In Progress				3/9/2015 8:36:25 AM				
Marquez, Gerardo		NEED TO ORDER TOOLS AND MATERIAL FOR USE DISTRICTWIDE.							
Gerardo Marquez									
128508		Lift Station			2/5/2015		69		\$0.00
Medium	Work In Progress				2/5/2015 8:24:35 AM				
Ontiveros, Guadalupe		need the assistance of a heavy equipment operator and tractor to help us replace a air relief check valve on the west side of the river bank							
Mario Apodaca									
130769					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 1:12:52 PM				
Carbajal, Jimmy		please install roll paper dispenser in ppd lounge							
Mary Sitters									
130583		Custodial			3/25/2015		21		\$0.00
Medium	Work In Progress				3/25/2015 3:31:04 PM				
Solis, Lorenz		THE WATER FOUNTAIN IN THE CUSTODIAL WHSE BETWEEN THE RESTROOMS IS LEAKING I HAVE CUT THE POWER AND SHUT OFF WATER BUT NEEDS REPAIR.							
Jimmy Carbajal									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
131335		Office			4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 7:33:56 AM				
Herrera, Mario		Old energy management office needs dusting of the outer metal wall.							
Jesus Estrada									
128609					2/6/2015		68		\$0.00
Medium	Work In Progress				2/6/2015 3:36:55 PM				
Apodaca, Mario		meet to order a powerverter for truck 38 to mount in the toolbox							
Mario Apodaca									
130605					3/26/2015		20		\$0.00
Medium	Work In Progress				3/26/2015 6:28:23 AM				
Apodaca, Mario		the 4 in check ball valve at lift pump station need to be replaced due to wear and tear at gms/ sunrise							
Mario Apodaca									
130753					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:17 AM				
Apodaca, Mario		Monthly - PPD/GHS - WW Monthly Sampling - Refer to PM schedule details.							
Margret Villalobos									
129350	Motor Vehicle				2/26/2015		48		\$0.00
Medium	Work In Progress	1050 tractor-			2/26/2015 2:22:42 PM				
Flores, Pete		please check cause of tractor not starting.							
Pete Flores									
129395	Motor Vehicle				2/27/2015		47		\$0.00
Medium	Work In Progress	FED. VEHICLE			2/27/2015 10:33:32 AM				
Flores, Pete		VEHICLE WILL BE TRAVELING TO ALBUQUERQUE REQUESTING A QUICK GENERAL CHECK UP.							
Noemi Duron									
129690	Motor Vehicle				3/3/2015		43		\$0.00
Medium	Work In Progress				3/3/2015 10:23:53 AM				
Flores, Pete		vehicle 188; gas gauge doesn't work correctly reported by Gilbert Bailon							
Maria Ruiz									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

129692 Motor Vehicle 3/3/2015 43 \$0.00

Medium Work In Progress 3/3/2015 10:26:26 AM

Flores, Pete locks on don't work 178 & 179 bad actuator (driver's side)

Maria Ruiz

129694 Motor Vehicle 3/3/2015 43 \$0.00

Medium Work In Progress vehicle#136 3/3/2015 10:27:34 AM

Flores, Pete please check condition of front brakes.

Pete Flores

129701 Motor Vehicle 3/3/2015 43 \$0.00

Medium Work In Progress vehicle#183 3/3/2015 10:38:07 AM

Flores, Pete please check on cause of driver's window not rolling up and down

Pete Flores

129705 Motor Vehicle 3/3/2015 43 \$0.00

Medium Work In Progress vehicle#148 3/3/2015 11:16:53 AM

Flores, Pete please check cause of a/c refrigerant loss

Pete Flores

129947 Motor Vehicle 3/9/2015 37 \$0.00

Medium Work In Progress 3/9/2015 2:01:14 PM

Flores, Pete vehicle 187 passenger window doesn't roll up or down

129982 Motor Vehicle 3/10/2015 36 \$0.00

Medium Work In Progress equip#0411 3/10/2015 9:43:46 AM

Flores, Pete please check electrical system for proper starting and any additional scheduled maintenance

Pete Flores

127251 1/8/2015 97 \$0.00

Medium Work In Progress 1/8/2015 3:20:43 PM

Flores, Pete TRUCK #32 NEEDS FUEL PUMP REPLACED

Ruben Ronquillo

127289 Motor Vehicle 1/9/2015 96 \$0.00

Medium Work In Progress vehicle#100 1/9/2015 10:33:33 AM

Flores, Pete please check cause of vehicle leaning excessively to one side.

Pete Flores

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

127546 Motor Vehicle 1/14/2015 91 \$0.00

Medium Work In Progress chaparral golf 1/14/2015 3:17:18 PM

Flores, Pete please prepare fairplay golf cart for use by chaparral security

Pete Flores

127922 Main Warehouse 1/26/2015 79 \$0.00

Medium Work In Progress 1/26/2015 1:30:57 PM

Flores, Pete SNP VEHHICLE 56 NEEDS TO BE SERVICED.

Maritza Gonzalez

127923 Main Warehouse 1/26/2015 79 \$0.00

Medium Work In Progress 1/26/2015 1:31:10 PM

Flores, Pete SNP VEHHICLE 52 NEEDS TO BE SERVICED.

Maritza Gonzalez

127924 Main Warehouse 1/26/2015 79 \$0.00

Medium Work In Progress 1/26/2015 1:31:21 PM

Flores, Pete SNP VEHHICLE 43 NEEDS TO BE SERVICED.

Maritza Gonzalez

127958 Motor Vehicle 1/26/2015 79 \$0.00

Medium Work In Progress Federal vehicle 1/26/2015 3:44:58 PM

Flores, Pete When driving in a long road and picking up speed the vehicle starts to jerk. Also, windows on driver side front and passenger back do not work.

Noemi Duron

130305 3/18/2015 28 \$0.00

Medium Work In Progress 3/18/2015 10:15:56 AM

Flores, Pete Please service and check vehicle 99.

Alfredo Holguin

128931 2/14/2015 60 \$0.00

Medium Work In Progress 2/14/2015 12:21:53 AM

Flores, Pete Yearly - PPD-T-0524 Bobcat PM Service - Refer to PM schedule details.

Margret Villalobos

130297 Motor Vehicle 3/18/2015 28 \$0.00

Medium Work In Progress vehicle#151 3/18/2015 8:36:01 AM

Flores, Pete please check for a/c refrigerant loss

Pete Flores

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
128280					2/1/2015		73		\$0.00
Medium	Work In Progress				2/1/2015 12:50:37 AM				
Flores, Pete		Monthly - PPD-MP-0143 DT PM Service - by SWP - Refer to PM schedule details.							
Margret Villalobos									
127462	Motor Vehicle				1/13/2015		92		\$0.00
Medium	Work In Progress	vehicle#147			1/13/2015 9:39:06 AM				
Flores, Pete		rear driver's side window inoperative, please check cause of malfunction.							
Pete Flores									
128130	Motor Vehicle				1/30/2015		75		\$0.00
Medium	Work In Progress	tilt trailer			1/30/2015 8:20:03 AM				
Flores, Pete		battery is more than 5 years old, requires replacement.							
Pete Flores									
131282		Athletic Field			4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 9:15:54 AM				
Flores, Pete		trailer #0774 need bearing packed.							
Guadalupe Ontiveros									
131283		Athletic Field			4/13/2015		2		\$0.00
High	Work In Progress				4/13/2015 9:21:42 AM				
Flores, Pete		Trailer #0751 breaks not working, when hook to dump truck #143							
Guadalupe Ontiveros									
130649					3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 8:35:06 AM				
Flores, Pete		Would you please do a work order to have the oil changed on vehicle # 150? The computer system says to change oil.							
		The vehicle will be available Monday and Tuesday, parked along the tree line.							
		Thanks,							
		Larry D. Baker							
Maritza Gonzalez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
130999	Motor Vehicle				4/6/2015		9		\$0.00
Medium	Work In Progress	Fed Vehicle #		4/6/2015 12:16:15 PM					
Flores, Pete	REQUESTING MAINTENACE FOR VEHICLE, IT WILL BE TRAVELING ON 4/16/15 TO ALBUQUERQUE, N.M.								
Noemi Duron									
131388					4/14/2015		1		\$0.00
High	Work In Progress	Vehicle 93		4/14/2015 3:01:52 PM					
Flores, Pete	Please service a/c unit Vehicle 93.								
Albert Vallejo									
131361	Motor Vehicle				4/14/2015		1		\$0.00
Medium	Work In Progress	vehicle#47		4/14/2015 8:34:33 AM					
Flores, Pete	please check for anyscheduled maintenance								
Pete Flores									
131376					4/14/2015		1		\$0.00
Medium	Work In Progress			4/14/2015 10:26:43 AM					
Gallegos, Rafael	SNP WAREHOUSE-There is a small roof leak where the racking starts. This is straight by bay 6. Please advise, Jose								
Maritza Gonzalez									
130453					3/23/2015		23		\$0.00
Medium	Work In Progress			3/23/2015 9:28:50 AM					
Gallegos, Rafael	SNP WAREHOUSE-As per Jose, buttons getting stuck on the control box, see attached photo. Need to check and correct the issue a.s.a.p. For details or information call Jose at 575-882-6939. Thanks								
Maritza Gonzalez									
128653	Maintenance	Office			2/9/2015		65		\$0.00
Medium	Work In Progress			2/9/2015 8:16:17 AM					
Lara, Ralph	WE NEED TWO TRIPP POWER VERTAR 3000W TO USED THEM ON DISTRICT VANS, FOR CUTTING KEYS ON DIFFRENT SCHOOL SITES.								
Ralph Lara									
119759					7/23/2014		266		\$0.00
Medium	Work In Progress			7/23/2014 2:32:20 PM					
Flores, Pete	MAINTANCE ON ALL SPED VEHICLES SUBMIT INVOICE TO JULIE HERNANDEZ								
Margaret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

122443 Motor Vehicle 9/8/2014 219 \$0.00

Medium Work In Progress ag trailer 9/8/2014 9:06:23 AM

Flores, Pete please prepare trailer as required for use by agriculture dept.

Pete Flores

124450 10/22/2014 175 \$0.00

Medium Work In Progress 10/22/2014 11:21:12

Flores, Pete vehicle 01, needs wipers and check engine light turned on and turned off (reported by Teresa Ortega)

Maria Ruiz

131110 Main Warehouse 4/8/2015 7 \$0.00

Medium Work In Progress 4/8/2015 3:19:19 PM

Sotelo, Enrique Need to install power/electrical outlets (See Enrique Briones)

Alfredo Holguin

130506 Purchasing 3/24/2015 22 \$0.00

Medium Work In Progress 3/24/2015 10:21:37 AM

Sotelo, Enrique NEED TO DROP ELECTRICAL OUTLET FOR WRAPPING MACHINE

Enrique Briones

131185 4/10/2015 5 \$0.00

Medium Work In Progress 4/10/2015 10:58:50 AM

Marquez, Gerardo PROVIDE ALBERT V. WITH MIKES KEYS

Ruben Ronquillo

126240 12/4/2014 132 \$0.00

Medium Work In Progress 12/4/2014 12:43:22 PM

Marquez, Gerardo One (1) key needed for electrical room at New Food WHS. Please drop off key at the construction office. Key needed as soon as possible. Should you have any questions please contact Mr. Ralph Gallegos at 575-882-6921 in the Construction office. Thank You

Dominique Esparza

128702 Purchasing 2/9/2015 65 \$0.00

Medium Work In Progress New Warehouse 2/9/2015 4:11:54 PM

Marquez, Gerardo Keys to be assigned to Cynthia Maes for the New Warehouse Offices, storage room and restrooms. I would like to meet Jerry out there when he is done making the keys he can call me-Cynthia at 882-6949.

Cynthia Maes

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
130508	Motor Vehicle				3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 11:03:26 AM				
Marquez, Gerardo	cut J3 key for Natalie Cruz (FEDS)								
Maria Ruiz									
124720	Motor Vehicle				10/29/2014		168		\$0.00
Medium	Work In Progress				10/29/2014 8:23:36 AM				
Marquez, Gerardo	COULD YOU PLEASE REPLACE A LOCK ON CABINET IN AUTO SHOP USED FOR CUSTODIAL SUPPLIES IF YOU HAVE ANY QUESTIONS PLEASE CONTACT FERNANDA THE MORNING CUSTODIAN. (2ND REQUEST)								
Jimmy Carbajal									
122948					9/18/2014		209		\$0.00
Medium	Work In Progress				9/18/2014 8:57:40 AM				
Marquez, Gerardo	New Warehouse- Rekey off grand Master - Check with Mike - Alfredo on keying								
Alfredo Holguin									
128464	Motor Vehicle				2/4/2015		70		\$0.00
Medium	Work In Progress	New Annex Bldg			2/4/2015 10:58:49 AM				
Marquez, Gerardo	Need to install doors on Metal Bldg on westside of Autoshop (see Alfredo H. for ?'s)								
Alfredo Holguin									
130454					3/23/2015		23		\$0.00
Medium	Work In Progress				3/23/2015 9:32:13 AM				
Duran, Fernanda	Please move out all furniture from Energy Office.								
Lisa Sanchez									
131049					4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 1:33:25 PM				
Duran, Fernanda	NEED TO PLEASE THOURGHLY CLEAN MAINTENANCE SUPERVISORS OFFICE								
Alfredo Holguin									
130415	Main Warehouse	Office			3/20/2015		26		\$0.00
Medium	Work In Progress				3/20/2015 8:16:49 AM				
Duran, Fernanda	Dust top to bottom, wash window and clean walls, shower scrub and waxold energy office floor.								
Jesus Estrada									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
131383	Purchasing	Restroom			4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 1:42:10 PM				
Villalobos, David		If possible to change sink faucet in restroom, valve getting stuck. Change to normal faucet.							
Enrique Briones									
130120					3/13/2015		33		\$0.00
Medium	Work In Progress				3/13/2015 8:02:08 AM				
Villalobos, David		need replacement cables and accessories to Rigid sewer machines							
David Villalobos									
127533					1/14/2015		91		\$0.00
Medium	Work In Progress				1/14/2015 1:56:21 PM				
Carrasco, Danny		Paint Juliet's Office.							
Michael Munoz									
127567					1/15/2015		90		\$0.00
Medium	Work In Progress				1/15/2015 7:52:14 AM				
Carrasco, Danny		need to remove Julies desk modular, carpet will be replaced. this needs to be done bytomorrow so that carpet be installed over the weekend.							
Jesus Estrada									
126898					1/4/2015	2/4/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:40:32 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PMschedule details.							
Margret Villalobos									
127691					1/20/2015		85		\$0.00
Medium	Work In Progress				1/20/2015 10:04:05 AM				
Miranda, Danny		PPD Offices - remodeling new office.							
Alfredo Holguin									
130422					3/20/2015		26		\$0.00
Medium	Work In Progress				3/20/2015 10:57:33 AM				
Miranda, Danny		Need to upholster seat on Truck #153							
Pete Flores									
130888					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:06 AM				
Ruiz, Maria		Monthly - PPD - Fueling Station Monthly Inspection - Refer to PMschedule details.							
Margret Villalobos									
4/15/2015 3:50:39 PM									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
131092	Motor Vehicle				4/8/2015		7		\$0.00
Medium	Work In Progress	vehicle#49			4/8/2015 11:12:55 AM				
Ruiz, Maria	please check condition of tires - repair or replace as required								
Pete Flores									
128463	Maintenance				2/4/2015		70		\$0.00
Medium	Work In Progress				2/4/2015 10:57:20 AM				
Holguin, Alfredo	Need quote to insulate Metal Bldg on westside of Autoshop.								
Alfredo Holguin									
129148	Motor Vehicle				2/23/2015		51		\$0.00
Medium	Work In Progress	New Annex Bldg			2/23/2015 9:38:06 AM				
Vallejo, Albert	Need to install Electrical power outlets in metal bldg behind Auto Shop - (see Alfredo H. for ?'s)								
Alfredo Holguin									
130227					3/17/2015		29		\$0.00
Medium	Work In Progress				3/17/2015 8:03:09 AM				
Gonzalez, Salvador	need to fabricate plate and tubing lifter								
Salvador Gonzalez									
129808					3/5/2015		41		\$0.00
Medium	Work In Progress				3/5/2015 8:00:32 AM				
Gonzalez, Salvador	3-5-15 Requesting impact gun with sockets								
Salvador Gonzalez									
130636		Athletic Field			3/26/2015		20		\$0.00
Medium	Work In Progress				3/26/2015 3:56:06 PM				
Gonzalez, Salvador	Dump truck needs angle iron weld to prevent flappers getting stock on tires.								
Guadalupe Ontiveros									
130849					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:44 AM				
Diaz, Sebastian	Monthly - Physical Plant Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Physical Plant Complex

131084 Purchasing 4/8/2015 7 \$0.00

Medium Work In Progress 4/8/2015 8:54:05 AM

Diaz, Sebastian The Men bathroom has been clogging up and is unusable by the staff in the Instructional Materials Department

Theresa Ramirez

131209 Maintenance 4/10/2015 5 \$0.00

Medium Work In Progress 4/10/2015 3:28:28 PM

Ronquillo, Ruben engrave serial number on 2 homemade trailers

Lisa Sanchez

131050 4/7/2015 8 \$0.00

High Work In Progress 4/7/2015 2:05:46 PM

Ronquillo, Ruben Need 5 signs:

Maintenance Personnel
Departure/Arrival

All work preparations must be accomplished prior to departure in the morning no later than 8:15 a.m. Personnel should not return to the Maintenance Shop/Site no earlier than 3:45 p.m. unless prior approval by Supervisor.

Alfredo Holguin

131303 4/13/2015 2 \$0.00

Medium Work In Progress 4/13/2015 2:44:24 PM

Ronquillo, Ruben ORDER PALLET RACK WIRE FLARED DECKING, CROSSBEAM FOR SHELVING FOR NEW WAREHOUSE

Ruben Ronquillo

131432 4/15/2015 0 \$0.00

Medium Work In Progress 4/15/2015 10:26:32 AM

Ronquillo, Ruben LEATHERMAN TOOL

Ruben Ronquillo

130959 4/5/2015 4/11/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:30:44 AM

Diaz, Sebastian Monthly - Physical Plant FE Inspection - Refer to PM schedule details.

Margret Villalobos

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
130603	Purchasing	Office			3/25/2015		21		\$0.00
Medium	Work In Progress				3/25/2015 4:11:51 PM				
Diaz, Sebastian	The AC units need to be serviced in the Instructional Materials offices and the warehouse.								
Theresa Ramirez									
131280	Purchasing	Office			4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 9:09:25 AM				
Diaz, Sebastian	One of the light fixture fell from its brackets, needs to be re-hung and lights bulbs replaced. Located in the IMWHSE. Thank you.								
Theresa Ramirez									
128728					2/10/2015		64		\$0.00
Medium	Work In Progress				2/10/2015 12:07:15 PM				
Diaz, Sebastian	light in Alfredo office needs to be replaced								
Mary Sitters									
130668	Main Warehouse				3/27/2015		19		\$0.00
Medium	Work In Progress				3/27/2015 2:25:08 PM				
Diaz, Sebastian	new warehouse - Sweep concrete where trucks back up to loading dock								
Alfredo Holguin									
122868					9/16/2014		211		\$0.00
Medium	Work In Progress				9/16/2014 3:48:24 PM				
Ronquillo, Ruben	ORDER 4EA. ENGINE DRIVEN WATER PUMPS, WITH HOSES. THANK YOU								
Ruben Ronquillo									
130029					3/11/2015		35		\$0.00
Medium	Work In Progress				3/11/2015 11:02:35 AM				
Ronquillo, Ruben	DISPOSE OF OBSOLETE HAVC PARTS AND MATERIALS								
Ruben Ronquillo									
129939	Motor Vehicle				3/9/2015		37		\$0.00
Medium	Work In Progress	FED VEHICLE			3/9/2015 11:15:22 AM				
Perez, Raul	CAR WASH								
Noemi Duron									
Count: 85 Work Orders			Avg. Age of WO's	52	Total for Physical Plant Complex			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: **Riverside ES**

129221	Main Building				2/24/2015		50		\$0.00
--------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/24/2015 10:50:22 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Perez, Raul
vehicle 46 is leaking and smoke was coming out reported by Rocio Herrera

Maria Ruiz

131098	Main Building	Classroom			4/8/2015		7		\$0.00
--------	---------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	whole school			4/8/2015 12:02:08 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Ronquillo, Ruben
As per Mr. Gallegos, need to purchase and install window blinds. Color - WHITE, - (navarro)

- 80 - 24" x 24"
- 35 - 16" x 48"
- 17 - 24" x 48"
- 15 - 9" x 42"
- 18 - 25" x 67"
- 4 - 23" x 48"
- 2 - 72" x 80"

Rosa Quezada

131197					4/10/2015		5		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/10/2015 1:38:30 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert
4/10/2015.
As per Mrs Navarro, she is asking if the 5th and 6th grade boys and girls restrooms can be remodeled in the summer?

Mario Martinez

130611		Classroom			3/26/2015		20		\$0.00
--------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	IEP room			3/26/2015 8:39:26 AM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Castillo, Carlos
install electrical outlet on ceiling for the projector (Navarro)

Rosa Quezada

131030					4/7/2015		8		\$0.00
--------	--	--	--	--	----------	--	---	--	--------

High	Work In Progress				4/7/2015 9:28:48 AM				
------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos
Power outage at school site.

Mario Martinez

130762					3/31/2015		15		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/31/2015 11:18:15 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
need an electrical outlet on ceiling for projector. IEP Room

Cora Ramirez

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Riverside ES									
128336					2/2/2015		72		\$0.00
Medium	Work In Progress				2/2/2015 9:50:24 AM				
Castillo, Carlos	2/02/2015. Need Carlos C to fix non working lights in South wing and main wing.								
Mario Martinez									
126797					12/19/2014		117		\$0.00
Medium	Work In Progress				12/19/2014 9:48:59 AM				
Castillo, Carlos	Need Carlos C. to fix bad lighting fixtures in room 101.								
Mario Martinez									
119185					7/8/2014		281		\$0.00
Medium	Work In Progress				7/8/2014 7:28:48 AM				
Marquez, Gerardo	7/08/2014. Need Rafa L. to fix door lock at library.								
Mario Martinez									
128738					2/10/2015		64		\$0.00
Medium	Work In Progress				2/10/2015 2:35:35 PM				
Orozco, Daniel	AS PER ADELE INSPECTION REPORT- BLODGET- TOP OVEN LOOSES TEMPERTURE, WAS ONCE REPAIRED AND WAS WORKING WELL FOR A WHILE. DOING THE SAME THING AGAIN.								
Maritza Gonzalez									
126703					12/17/2014		119		\$0.00
Medium	Work In Progress				12/17/2014 9:35:14 AM				
Orozco, Daniel	AS PER INSPECTION REPORT, DRAINS ON LEFT SIDE OF SERVING LANE ARE NOT WORKING PROPERLY, WATER IS BEING DISPENSED MANUALLY.								
Maritza Gonzalez									
126186	Main Building	Cafeteria			12/3/2014		133		\$0.00
Medium	Work In Progress	cafeteria			12/3/2014 3:23:58 PM				
Lara, Ralph	need to install a doorbell in north side door of the cafeteria for incoming deliveries to the cafeteria. vendors waiting outside to deliver because we don't know they are out there and we can hear them knocking on the door. (santa Nava)								
Rosa Quezada									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

127176					1/7/2015		98		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/7/2015 10:42:19 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
1/07/2015.
Need Rafa L. to replace old double door Mullions with new single keyMullions, also need panic bar door handle fixed. Would also like new hardware kits for all door mullions.

Mario Martinez

130920					4/5/2015	4/13/2015	10		\$0.00
--------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/5/2015 12:30:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Martinez, Mario
Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

130921					4/5/2015	4/13/2015	10		\$0.00
--------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/5/2015 12:30:24 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Martinez, Mario
Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

130960					4/5/2015	4/11/2015	10		\$0.00
--------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/5/2015 12:30:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Martinez, Mario
Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.

Margret Villalobos

130562					3/25/2015		21		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/25/2015 8:57:07 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Martinez, Mario
Need to cut down five trees from the tree trunk. Need a chainsaw from P.P.D.

Mario Martinez

131263					4/12/2015	4/28/2015	3		\$0.00
--------	--	--	--	--	-----------	-----------	---	--	--------

Medium	Work In Progress				4/12/2015 12:23:52 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Martinez, Mario
Monthly - Riverside ES Playground Insp - Refer to PM schedule details.

Margret Villalobos

131298	Main Building	Classroom			4/13/2015		2		\$0.00
--------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	art classroom			4/13/2015 1:55:58 PM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Martinez, Mario
we need Mr. Martinez, our maintenance man, to transport our art display to Gadsden Middles School on April 23, 2015 and leave the art display in the gym. (saucedo)

Rosa Quezada

4/15/2015 3:50:40 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
121247	Main Building	Classroom			8/15/2014		243		\$0.00
Medium	Work In Progress	nurses station			8/15/2014 10:30:55 AM				
Martinez, Mario		we need two installed two SECURED cabinets in the nurses station with lock and key for medicine storage. (navarro)							
Rosa Quezada									
124523					10/23/2014		174		\$0.00
Medium	Work In Progress				10/23/2014 3:19:44 PM				
Martinez, Mario		10/23/2014. Need air compressor and electric hammer drill for future use. If you can please purchase for Riverside Elementary.							
Mario Martinez									
129921					3/9/2015	3/24/2015	37		\$0.00
Medium	Work In Progress				3/9/2015 12:35:48 AM				
Martinez, Mario		Monthly - Riverside ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
129345					2/26/2015		48		\$0.00
Medium	Work In Progress				2/26/2015 12:36:28 PM				
Martinez, Mario		2/26/2015. Need to purchase 4 tarps to cover furniture left out side of buildinds.							
Mario Martinez									
130266					3/17/2015		29		\$0.00
Medium	Work In Progress				3/17/2015 2:40:58 PM				
Martinez, Mario		Need to fertilize soccer field and entire lawn.							
Mario Martinez									
130785					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:10 AM				
Martinez, Mario		Yearly - Riverside ES A-13 A/C Wall Mount Yearly - Refer to PM schedule details.							
Margret Villalobos									
130831					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:35 AM				
Martinez, Mario		Monthly - Riverside ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
131246					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:43 AM				
Sonora, Miguel		Monthly - QRTLY BLDG INSP REPORT (RS) - Refer to PM schedule details.							
Margret Villalobos									
131173					4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 7:22:39 AM				
Ambriz, Jose		4/10/2015. Need Jose A. to take a look at A/C unit at communications room. Unit not working.							
Mario Martinez									
127260					1/8/2015		97		\$0.00
High	Work In Progress				1/8/2015 3:41:48 PM				
Ambriz, Jose		please clean all strainers to coils for proper heating. the contract did not include flushing lines. thank you							
Michael Munoz									
122686					9/12/2014		215		\$0.00
Medium	Work In Progress				9/12/2014 8:17:14 AM				
Ambriz, Jose		check cooling in room 136							
Michael Munoz									
129001					2/18/2015		56		\$0.00
Medium	Work In Progress				2/18/2015 7:55:14 AM				
Ontiveros, Guadalupe		Need assistance with locating buried and lost sprinkler valves							
Mario Martinez									
129759					3/4/2015		42		\$0.00
Medium	Work In Progress	main school			3/4/2015 8:19:53 AM				
Marquez, Gerardo		second request for front main door closer. reference work order# 128792. this work order shows it's been closed but door remains non-functional. please send Rafa a.s.a.p. (Navarro)							
Rosa Quezada									
127174					1/7/2015		98		\$0.00
Medium	Work In Progress				1/7/2015 10:13:02 AM				
Ontiveros, Joe		1/07/2015. Need Joe O. to repair or replace five flush valves at boys and girls bathrooms. Also need to replace open elongated toilet seat							
Mario Martinez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
130467					3/23/2015		23		\$0.00
Medium	Work In Progress				3/23/2015 3:02:27 PM				
Ontiveros, Joe		Need plumber Joe O. to unstop water fountain in hallway across office.							
Mario Martinez									
121838					8/27/2014		231		\$0.00
Medium	Work In Progress				8/27/2014 12:58:57 PM				
Ontiveros, Joe		Need plumber Joe O. to fix leaky urinal in boys restroom at north wing.							
Mario Martinez									
Count: 35 Work Orders			Avg. Age of WO's	68	Total for Riverside ES			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: RTC - Alliance									
126234		Office			12/4/2014		132		\$0.00
Medium	Work In Progress				12/4/2014 11:06:49 AM				
Moncayo, Fernando		the office heater has not turned on/it has been below 50 for the past 2days/ have tried to turn on and off to reset and even walked in and out rooms for the sensor /have the dial up to 90 it does not turn on							
Gloria Delgado									
129838		Portables			3/5/2015		41		\$0.00
Medium	Work In Progress				3/5/2015 3:32:44 PM				
Moncayo, Fernando		1.mount a pencil sharpener in Ms. Arreola's class 2. change a wall organizer to another wall in the office							
Gloria Delgado									
127239		Portables			1/8/2015		97		\$0.00
Medium	Work In Progress				1/8/2015 1:15:33 PM				
Moncayo, Fernando		ramps very slippery and Mrs. Hirsch's classroom heater not working Mr. Moncada came in salted ramps and fixed heater							
Gloria Delgado									
124511		Portables			10/23/2014		174		\$0.00
Medium	Work In Progress				10/23/2014 12:17:58				
Moncayo, Fernando		Need light bulbs changed in the office. Fire escape security windows keep opening secure locks while maintaing safety egress							
Gloria Delgado									
Count: 4 Work Orders			Avg. Age of WO's	111		Total for RTC - Alliance	0		\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		San Miguel ES							
130938					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:33 AM				
Apodaca, Mario		Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
129587					3/1/2015		45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:50 AM				
Apodaca, Mario		Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
Count: 2 Work Orders		Avg. Age of WO's	28			Total for San Miguel ES	0		\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
125848					11/21/2014		145		\$0.00
Medium	Work In Progress				11/21/2014 2:28:51 PM				
Munoz, Michael		need new fencing with gates to prevent students from going into parking lots							
Juan Ambriz									
130608	Main Building	Exterior			3/26/2015		20		\$0.00
Medium	Work In Progress	Fencil locks			3/26/2015 8:05:07 AM				
Lara, Ralph		Need to repair all locks on fence. Staff having problems opening.							
Juan Ambriz									
130265	Main Building	Hallway/Corridor			3/17/2015		29		\$0.00
Medium	Work In Progress	Hallway/nurse			3/17/2015 2:20:32 PM				
Lara, Ralph		As per Mrs. Tarin wants a door Installed on the main hallway wall entering the Nurse's office. Preferably made between May 22 to May 27.							
Juan Ambriz									
131261					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:51 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
130741					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:11 AM				
Ambriz, Juan		Monthly - Santa Teresa ES-A-16 Fan Exhaust (SemiA) - Refer to PM schedule details.							
Margret Villalobos									
130963					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:46 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
129276	Main Building	Office			2/25/2015		49		\$0.00
Medium	Work In Progress	Parent room			2/25/2015 9:41:19 AM				
Ambriz, Juan		Need to Install blinds in old Parent Room now book room office 101" x 90"							
Juan Ambriz									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

130399	Main Building	Classroom			3/19/2015		27		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room #108			3/19/2015 3:44:18 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Ambriz, Juan		Need to replace leaky sink faucet in room #108							
--------------	--	--	--	--	--	--	--	--	--

Juan Ambriz									
-------------	--	--	--	--	--	--	--	--	--

129662		Classroom			3/2/2015		44		\$0.00
--------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Room #103			3/2/2015 3:55:40 PM				
--------	------------------	-----------	--	--	---------------------	--	--	--	--

Ambriz, Juan		Need to mount smartboard on wall							
--------------	--	----------------------------------	--	--	--	--	--	--	--

Juan Ambriz									
-------------	--	--	--	--	--	--	--	--	--

129663	Main Building	Classroom			3/2/2015		44		\$0.00
--------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Room #205			3/2/2015 3:56:29 PM				
--------	------------------	-----------	--	--	---------------------	--	--	--	--

Ambriz, Juan		Need to mount smartboard on wall							
--------------	--	----------------------------------	--	--	--	--	--	--	--

Juan Ambriz									
-------------	--	--	--	--	--	--	--	--	--

129275	Main Building	Library			2/25/2015		49		\$0.00
--------	---------------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2015 9:30:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Juan		Need to Install blinds in Library in case of a lockdown							
--------------	--	---	--	--	--	--	--	--	--

Juan Ambriz									
-------------	--	--	--	--	--	--	--	--	--

129919					3/9/2015	3/24/2015	37		\$0.00
--------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/9/2015 12:35:47 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Juan		Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

129475					3/1/2015		45		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/1/2015 12:45:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Juan		Yearly - Santa Teresa ES A-10 HEAT PUMPS (ANNUAL) - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

129612					3/1/2015	3/7/2015	45		\$0.00
--------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				3/1/2015 12:47:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Juan		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

129211					2/24/2015		50		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/24/2015 8:48:29 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Juan		Need to Install covers in all electrical outlets							
--------------	--	--	--	--	--	--	--	--	--

Juan Ambriz									
-------------	--	--	--	--	--	--	--	--	--

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
130828					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:34 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
130877					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:59 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130878					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:59 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130879					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:00 AM				
Ambriz, Juan		Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
130431	Main Building	Portables			3/20/2015		26		\$0.00
Medium	Work In Progress	music portable E			3/20/2015 3:08:39 PM				
Ambriz, Juan		Need to hang sound deflectors in music portable							
Juan Ambriz									
129325	Main Building	Portables			2/26/2015		48		\$0.00
Medium	Work In Progress	Portable A-051			2/26/2015 7:49:42 AM				
Ambriz, Juan		Need to Install shelve							
Juan Ambriz									
128453	Main Building	Restroom			2/4/2015		70		\$0.00
Medium	Work In Progress				2/4/2015 9:23:39 AM				
Ambriz, Juan		As per Mrs. Tarin need to replace hand dryers in boys restroom in 300 hallway							
Juan Ambriz									
129645	Main Building	Exterior			3/2/2015		44		\$0.00
Medium	Work In Progress				3/2/2015 3:11:04 PM				
Ambriz, Juan		Need to order fertilizer for back field							
Juan Ambriz									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES									
128454	Main Building	Restroom (Girls)			2/4/2015		70		\$0.00
Medium	Work In Progress				2/4/2015 9:25:22 AM				
Ambriz, Juan		Need to replace sink faucets in girls 300 hallway restroom							
Juan Ambriz									
128455	Main Building	Restroom (Girls)			2/4/2015		70		\$0.00
Medium	Work In Progress				2/4/2015 9:29:07 AM				
Ambriz, Juan		As per Mrs. Tarin Need to replace Hand dryers in girls 200 hallway							
Juan Ambriz									
128456	Main Building	Restroom (Girls)			2/4/2015		70		\$0.00
Medium	Work In Progress				2/4/2015 9:33:07 AM				
Ambriz, Juan		Need to replace faucet in girls 100 hallway							
Juan Ambriz									
131238					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:38 AM				
Rodriguez, Ivan		Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.							
Margret Villalobos									
126298					12/5/2014		131		\$0.00
Medium	Work In Progress				12/5/2014 3:32:07 PM				
Orozco, Daniel		ICE MAKER LEAKING. SNP MANAGER MARINA R. 589.3439							
Maritza Gonzalez									
130196					3/16/2015		30		\$0.00
Medium	Work In Progress				3/16/2015 2:41:20 PM				
Orozco, Daniel		As per fire inspection, exhaust fan not working.							
Maritza Gonzalez									
130299					3/18/2015		28		\$0.00
Medium	Work In Progress				3/18/2015 8:48:47 AM				
Orozco, Daniel		DOOR STRIP ON WALK IN DOOR IS COMING OFF. SAFETY HAZARD. SNP MANAGER MARINA R. 589-3439.							
Maritza Gonzalez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
130300					3/18/2015		28		\$0.00
Medium	Work In Progress				3/18/2015 8:49:54 AM				
Orozco, Daniel		TEMPERATURE ON REACH IN REFRIGERATURE IS NOT WORKING PROPERLY, TOO COLD. SNP MANAGER MARINA R. 589-3439.							
Maritza Gonzalez									
124391					10/21/2014		176		\$0.00
Medium	Work In Progress				10/21/2014 10:54:28				
Orozco, Daniel		WALK IN ENTRANCE-FLOOR IS LIFTING. SNP MANAGER MARINA R. 589.3436							
Maritza Gonzalez									
131295		Office			4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 11:59:12 AM				
Gonzales, Camilo		Deliver 42 Boxes. PO# 141505765.							
Theresa Ramirez									
126757	Main Building	Classroom			12/18/2014		118		\$0.00
Medium	Work In Progress	parent room 300			12/18/2014 1:16:34 PM				
Castillo, Carlos		Need to Install electrical outlet for smart board							
Juan Ambriz									
126573					12/12/2014		124		\$0.00
Medium	Work In Progress				12/12/2014 9:22:46 AM				
Castillo, Carlos		As per our conversation, please check for power for a Double Portable on the Eastside of campus.							
Margret Villalobos									
126905					1/4/2015	2/4/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:40:37 AM				
Villalobos, David		Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
127847	Main Building	Exterior			1/23/2015		82		\$0.00
Medium	Work In Progress				1/23/2015 11:20:13 AM				
Gonzalez, Salvador		Need to remove steel posts behind kitchen due to new fence installed							
Juan Ambriz									
127742	Main Building	Storage			1/21/2015		84		\$0.00
Medium	Work In Progress	New storage			1/21/2015 9:12:36 AM				
Gonzalez, Salvador		Need to install ramp in new storage building							
Juan Ambriz									
4/15/2015 3:50:40 PM									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa ES							
127846	Main Building	Storage			1/23/2015		82		\$0.00
Medium	Work In Progress	new storage			1/23/2015 11:18:22 AM				
Gonzalez, Salvador		Need a new ramp on new storage							
Juan Ambriz									
Count: 39 Work Orders		Avg. Age of WO's		52	Total for Santa Teresa ES			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
127419					1/12/2015		93		\$0.00
Medium	Work In Progress				1/12/2015 3:25:10 PM				
Gonzalez, Salvador		the wire mesh to some goose neck has fallen off need to be replace with some expandable metal or new wire mesh need two at 37x38							
Daniel Sotelo									
130086		Parking Lot			3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 10:19:14 AM				
Gonzalez, Salvador		Main Entrance to parking area- Need to replace two large roll gates with swing gates - 4 each							
Alfredo Holguin									
127644	Main Building	Athletic Field			1/16/2015		89		\$0.00
Medium	Work In Progress	Softball			1/16/2015 11:27:24 AM				
Gonzalez, Salvador		Batting cage for softball field please see Ms Contreras and Rick for futher guidance							
Loraine Soriano									
127645	Main Building	Parking Lot			1/16/2015		89		\$0.00
Medium	Work In Progress	student parking			1/16/2015 11:30:59 AM				
Gonzalez, Salvador		Traffic control for after and before school see Rick for further assistance. There has been parental concerns with this issue and we need address the problem.							
Loraine Soriano									
128386		Athletic Field			2/3/2015		71		\$0.00
Medium	Work In Progress	Softball			2/3/2015 9:30:39 AM				
Ronquillo, Ruben		Season started 02/02/2015. Please order nets for softball cages once they're complete. Please get measurements from Sal Gonzalez							
Loraine Soriano									
128385					2/3/2015		71		\$0.00
Medium	Work In Progress				2/3/2015 8:58:48 AM				
Ronquillo, Ruben		Need to purchase nets for BB Batting Cages (4) 24L x 10H x 10W							
Alfredo Holguin									
128821	Cafeteria (2005)	Exterior			2/11/2015		63		\$0.00
Medium	Work In Progress	sidewalk			2/11/2015 4:25:36 PM				
Ronquillo, Ruben		Demo and upgrade sidewalk to create new entryway, also add landscaping to entrance area. Please see Mr. W. for further direction as well as Mr. Ruben Ronquillo							
Loraine Soriano									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
128822	Main Building	Exterior			2/11/2015		63		\$0.00
Medium	Work In Progress	annex/library			2/11/2015 4:26:48 PM				
Ronquillo, Ruben		Various signage upgrades please see Mr. W or Mr. Ronquillo for further direction							
Loraine Soriano									
128823	Main Building	Exterior			2/11/2015		63		\$0.00
Medium	Work In Progress	outside front			2/11/2015 4:29:15 PM				
Ronquillo, Ruben		Small visitors signs to attached to present handicap signs, aluminum signage above culinary arts and NJROTC classroom. Install sign posts in faculty parking lot for administration for further direction please see Mr. W or Mr. Ronquillo							
Loraine Soriano									
126903					1/4/2015	2/4/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:40:36 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
119429	Cafeteria (2005)	Cafeteria			7/15/2014		274		\$0.00
Medium	Work In Progress				7/15/2014 11:10:21 AM				
Escobar, David		Several cracked, broken or missing tiles in serving line area and dining area around stage need to be replaced.							
Rosalinda Rodriguez									
127042	Main Building	Office			1/5/2015		100		\$0.00
Medium	Work In Progress	Counseling			1/5/2015 10:46:12 AM				
Escobar, David		Lights in need of replacing							
Loraine Soriano									
130984	Main Building	Classroom			4/6/2015		9		\$0.00
Medium	Work In Progress	610			4/6/2015 10:47:46 AM				
Castillo, Carlos		Electricity out to three plugs and garbage disposal in kitchen 2							
Loraine Soriano									
126710	GYM (2009)	Gym			12/17/2014		119		\$0.00
Medium	Work In Progress	girls lockerroom			12/17/2014 12:21:52				
Castillo, Carlos		extra electrical outlets in locker needed for use							
Loraine Soriano									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS									
131378					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 11:09:26 AM				
Castillo, Carlos		Nursing Portable - La Clinica De Familia side - disconnect/remove service to outlets in interior walls that will be removed by Contractor .							
Alfredo Holguin									
131194		Office			4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 12:42:25 PM				
Gonzales, Camilo		Deliver 1 box. PO# 141504101. Attn: M.A. Vasquez							
Theresa Ramirez									
127839	Dressing Rooms	Dressing Room			1/23/2015		82		\$0.00
Medium	Work In Progress				1/23/2015 10:19:52 AM				
Castillo, Carlos		As per Coach Dots on, the basketball timers in dressing rooms are not working properly.							
Carlos Castillo									
126364					12/8/2014		128		\$0.00
Medium	Work In Progress				12/8/2014 1:35:42 PM				
Castillo, Carlos		several exterior elec. outlets need to be repaired due to broken weather covers as per NMPSIA standard report.							
David Escobar									
130084	Gymnasium				3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 10:13:39 AM				
Castillo, Carlos		Boys Dressing Room - Repair/ replace 2 damaged 2x4 ceiling lights.							
Alfredo Holguin									
130821					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:29 AM				
Escobar, David		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
130804					4/5/2015	4/26/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:20 AM				
Escobar, David		Monthly - Santa Teresa HS C-12 Chm Feeder Semimntly - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS									
130805					4/5/2015	4/26/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:21 AM				
Escobar, David		Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PMschedule details.							
Margret Villalobos									
126447	Main Building	Parking Lot			12/10/2014		126		\$0.00
Medium	Work In Progress	flag pole			12/10/2014 9:15:39 AM				
Escobar, David		Flag pole is not working the pulley is broken							
Loraine Soriano									
124118	Main Building	Classroom			10/14/2014		183		\$0.00
Medium	Work In Progress	312			10/14/2014 8:19:40 AM				
Escobar, David		Need a pencil sharpner installed							
Loraine Soriano									
120185	Main Building	Classroom			8/1/2014		257		\$0.00
Medium	Work In Progress	main building			8/1/2014 12:28:03 PM				
Escobar, David		Several classrooms leaking. Please see me for map to determine locations							
Loraine Soriano									
129432					2/28/2015	3/31/2015	46		\$0.00
Medium	Work In Progress				2/28/2015 12:34:44 AM				
,		Yearly - Santa Teresa HS C-11 Evap Coolers Yearly - Refer to PMschedule details.							
Margret Villalobos									
129553					3/1/2015	4/1/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:30 AM				
,		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
129554					3/1/2015	3/9/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:31 AM				
,		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
129555					3/1/2015	3/9/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:31 AM				
,		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

131229					4/12/2015	4/28/2015	3		\$0.00
--------	--	--	--	--	-----------	-----------	---	--	--------

Medium	Work In Progress				4/12/2015 12:23:33 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lucero, Arnold Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.

Margret Villalobos

122288	Main Building	Hallway/Corridor			9/4/2014		91		\$0.00
--------	---------------	------------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/4/2014 8:02:23 AM	12/4/2014			
--------	------------------	--	--	--	---------------------	-----------	--	--	--

Lucero, Arnold Make sure all hallways are burnished 2 times a week. (Assign to Arnold Lucero)

Jesus Estrada 10/17/14 - REMAILED TO ARNOLD; 3/26/15 - REMAILED OUT TO ARNOLD, ASP CHUY - ARNOLD PLEASE MAKE SURE TO TAKE CARE OF THIS ON A WEEKLY BASIS.

127342					1/11/2015	1/27/2015	94		\$0.00
--------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				1/11/2015 12:29:46 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lucero, Arnold Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.

Jesus Estrada

130414	Main Building				3/20/2015		26		\$0.00
--------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/20/2015 8:11:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lucero, Arnold clean off dead bugs inside light fixtures they are all down the hallways

Jesus Estrada

128091					1/29/2015		76		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/29/2015 10:25:58 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Daniel The technician from Ecolab came and checked dishwasher, He stated that the wash tank Gauge needs to be replaced is not working at all. SNP Manager Olga B. 589.5332

Maritza Gonzalez

130619					3/26/2015		20		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	OFFICE			3/26/2015 12:18:42 PM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Ambriz, Jose TWO WATER FOUNTAINS IN 600 HALLWAY DOES NOT DRAIN.

Marylou Jimenez

131028					4/7/2015		8		\$0.00
--------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				4/7/2015 8:38:35 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose Trainers Ice machine is not making ice.

Jaime Mijarez

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS									
128114	Main Building	Classroom			1/29/2015		76		\$0.00
Medium	Work In Progress	601			1/29/2015 3:51:50 PM				
Ambriz, Jose Heater notworking									
Loraine Soriano									
131352	Locker Room	Roof			4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 7:58:27 AM				
Ambriz, Jose order new H & C rooftop units for the locker rooms. Installation to be done by roofing contractor									
Alfredo Holguin									
131048	Cafeteria (2005)	Cafeteria			4/7/2015		8		\$0.00
Medium	Work In Progress				4/7/2015 1:21:01 PM				
Ambriz, Jose Having problems with air handler from dinning need contactors and axiliries. thank you									
Jaime Mijarez									
122320	Main Building	Exterior			9/4/2014		223		\$0.00
Medium	Work In Progress	Admin/handicap			9/4/2014 11:39:20 AM				
Ontiveros, Guadalupe If concrete curbs can be placed in parking to keep cars from obstructing access to sidewalks for wheelchairs									
Loraine Soriano									
119578		Athletic Field			7/18/2014		271		\$0.00
High	Work In Progress				7/18/2014 12:51:51 PM				
Ontiveros, Guadalupe need to line locate along pinetrees.anysewer line and gas lines. any? rick will assit									
Guadalupe Ontiveros									
119584		Athletic Field			7/18/2014		271		\$0.00
Medium	Work In Progress				7/18/2014 1:44:53 PM				
Ontiveros, Guadalupe JD tractor 3005 clutch needs to be replaced.									
Guadalupe Ontiveros									
120999					8/12/2014		246		\$0.00
Medium	Work In Progress				8/12/2014 9:29:38 AM				
Ontiveros, Guadalupe Sidewalk attached to black cinder block wall and going to arroyo has a lot of erosion from Sundays rain storm and can collapse into arroyo with another heavyrain. and was reported by Security Juan Tellez. Side walk is heavily used bythe students and needs immediate attention.									
Jaime Mijarez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
121003					8/12/2014		246		\$0.00
Medium	Work In Progress				8/12/2014 9:38:36 AM				
Ontiveros, Guadalupe		Sidewalk behind the 500 wing exit to the football field has a lot of erosion from Sundays rain storm and can collapse. Right now it is unsafe, I will have to barricade to keep students off this area. need immediate attention. Attention Lupe for this work order and work order # 120999.							
Jaime Mijarez									
128389	GYM (2009)	Athletic Field			2/3/2015		71		\$0.00
Medium	Work In Progress	Tennis Courts			2/3/2015 9:34:51 AM				
Ontiveros, Guadalupe		Tennis courts cement is cracked, along playing surface.							
Loraine Soriano									
125544					11/13/2014		153		\$0.00
Medium	Work In Progress				11/13/2014 4:25:33 PM				
Ontiveros, Joe		Room 511 Order and access panel under sink to provide access to gas shut off.							
Alfredo Holguin									
125615					11/17/2014		149		\$0.00
Medium	Work In Progress				11/17/2014 9:25:00 AM				
Ontiveros, Joe		Science Room 515 - Repair water and gas lines to lab tables - install new signs on Gas Shut Off Valve locations							
Alfredo Holguin									
125620					11/17/2014		149		\$0.00
Medium	Work In Progress				11/17/2014 9:37:18 AM				
Ontiveros, Joe		Science Room 508 - Repair gas and water lines to lab tables and install new signs at locations of Gas Shut Off Valve.							
Alfredo Holguin									
130618		Restroom			3/26/2015		20		\$0.00
Medium	Work In Progress	600 WING			3/26/2015 12:10:07 PM				
Ontiveros, Joe		RESTROOM IN 600 WING TOILET IS NOT WORKING PROPERLY. WATER FLUSHES OUT INTO HALLWAY.							
Marylou Jimenez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
130487					3/23/2015		23		\$0.00
High	Work In Progress				3/23/2015 3:57:48 PM				
Ontiveros, Joe		we need to line locate where sidewalk is to be install. will mark area. gas and water. Mr. rick can show area.							
Guadalupe Ontiveros									
131377					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 11:06:56 AM				
Ontiveros, Joe		Nursing Portable - Install lavatory and commode for new staff restroom in room on east side between school nurse area and area formerly used by La Clinica De Familia							
Alfredo Holguin									
130704					3/30/2015		16		\$0.00
Medium	Work In Progress	600 HALLWAY			3/30/2015 9:48:46 AM				
Ontiveros, Joe		NEED A PLUMBER TO UNPLUG THE DRAIN ON THE WATER FOUNTAIN IN 600 HALLWAY.							
Marylou Jimenez									
131419					4/15/2015		0		\$0.00
Medium	Work In Progress				4/15/2015 8:34:00 AM				
Alvarado, Julio		Remove sand from inside block wall where gas meter is located next to north entrance gate							
Alfredo Holguin									
131022	Gymnasium	Dressing Room			4/6/2015		9		\$0.00
Medium	Work In Progress	boys locker room			4/6/2015 4:06:42 PM				
Ontiveros, Joe		restroom in boys locker room clogged up							
Loraine Soriano									
128133	Main Building	Hallway/Corridor			1/30/2015		75		\$0.00
Medium	Work In Progress	in back of 200			1/30/2015 9:23:22 AM				
Estrada, Jesus		tile damaged in front of 200 and 300 wing in front of exiting. Please see Jaime for assistance							
Loraine Soriano									
130994		Gym			4/6/2015		9		\$0.00
Medium	Work In Progress				4/6/2015 11:38:23 AM				
Estrada, Jesus		varnish (2) gym floors							
Jesus Estrada									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

129836 3/5/2015 41 \$0.00

Medium Work In Progress 3/5/2015 3:16:09 PM

Estrada, Jesus Nursing Portable - replace carpet with VCT or Linoleum with welded seams.

Alfredo Holguin

131021 Gymnasium Hallway/Corridor 4/6/2015 9 \$0.00

Medium Work In Progress bathroom across 4/6/2015 4:05:20 PM

Ontiveros, Joe clogged toilet in boys restroom across from auxiliary gym

Loraine Soriano

128577 Main Building Classroom 2/6/2015 68 \$0.00

Medium Work In Progress 215 2/6/2015 9:54:47 AM

Ontiveros, Joe Kitchen sink is leaking

Loraine Soriano

127480 Main Building Classroom 1/13/2015 92 \$0.00

Medium Work In Progress 215 1/13/2015 2:26:17 PM

Ontiveros, Joe Student shower needs a knob.

Loraine Soriano

125409 AnnexBuilding Classroom 11/10/2014 156 \$0.00

Medium Work In Progress culinary 11/10/2014 4:25:12 PM

Ontiveros, Joe Dryer has not been hooked

Loraine Soriano

127270 Vocational Classroom 1/8/2015 97 \$0.00

Medium Work In Progress 801 1/8/2015 3:55:21 PM

Ontiveros, Joe Water leak, replace valves in water stations please see Jaime

Loraine Soriano

125545 Classroom 11/13/2014 153 \$0.00

Medium Work In Progress 11/13/2014 4:29:17 PM

Ontiveros, Joe Science Room 511- Install new signs on Gas shut off access panels 2) to read "gas Shut Off Valve"

Alfredo Holguin

123303 Main Building Classroom 9/26/2014 201 \$0.00

Medium Work In Progress 215 9/26/2014 2:16:35 PM

Ontiveros, Joe Toilet malfunctioning

Loraine Soriano

4/15/2015 3:50:41 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
124173	AnnexBuilding	Classroom			10/15/2014		182		\$0.00
Medium	Work In Progress	culinary			10/15/2014 9:51:56 AM				
Ontiveros, Joe		Dryer not working							
Loraine Soriano									
120184	Main Building	Classroom			8/1/2014		257		\$0.00
Medium	Work In Progress	610			8/1/2014 12:26:38 PM				
Ontiveros, Joe		Install new range in room 610							
Loraine Soriano									
127812	Main Building	Computer Lab			1/22/2015		83		\$0.00
Medium	Work In Progress	C-4			1/22/2015 2:59:03 PM				
Estrada, Jesus		TILE NEEDS REPLACEMENT							
Loraine Soriano									
124096	Main Building	Office			10/13/2014		184		\$0.00
Medium	Work In Progress	Training room			10/13/2014 3:46:12 PM				
Mijarez, Jaime		Mr. Munoz needs assistance with some hooks please see mr. Munoz for further clarification							
Loraine Soriano									
128820	GYM (2009)	Exterior			2/11/2015		63		\$0.00
Medium	Work In Progress	wall outside			2/11/2015 4:23:11 PM				
Mijarez, Jaime		wall in the exterior of football locker room in need of painting. Please try to match new gym exterior							
Loraine Soriano									
120624	Gymnasium	Restroom			8/6/2014		252		\$0.00
Medium	Work In Progress	soccer locker			8/6/2014 9:19:21 AM				
Mijarez, Jaime		Missing toilet seat in one of the stalls							
Loraine Soriano									
128380	GYM (2009)	Football Field			2/3/2015		71		\$0.00
Medium	Work In Progress	outside football			2/3/2015 8:16:52 AM				
Mijarez, Jaime		Wall on the outside of football field house needs to be painted the same as the other buildings. Also wall along football field needs painting.							
Loraine Soriano									
121254	Cafeteria (2005)				8/15/2014		243		\$0.00
Medium	Work In Progress				8/15/2014 10:49:31 AM				
Mijarez, Jaime		mens restroom in cafeteria urinal not enough water pressure							
Isaac Holguin									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Santa Teresa HS									
124222					10/16/2014		181		\$0.00
Medium	Work In Progress				10/16/2014 7:56:45 AM				
Mijarez, Jaime	Room 400. No cooling in the after noon reported by teacher. The a/c motor gave out. I will need a new 3/4 hp motor with pully and clamps to replace.								
Jaime Mijarez									
129466					3/1/2015	4/1/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:45:38 AM				
Mijarez, Jaime	Yearly - Santa Teresa HS A-10 HP Yearly - Refer to PM schedule details.								
Margret Villalobos									
129069					2/19/2015		55		\$0.00
Medium	Work In Progress				2/19/2015 10:32:22 AM				
Mijarez, Jaime	Chiller Alarm- 6:37 PM February 18,2015 Starter Did Not Transition Cprsr 2A. Chiller serviced by David on 2/18/2015.								
Jaime Mijarez									
129516					3/1/2015		45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:08 AM				
Mijarez, Jaime	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
129611					3/1/2015	3/7/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:47:04 AM				
Mijarez, Jaime	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
129506					3/1/2015	3/4/2015	45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:03 AM				
Mijarez, Jaime	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
Margret Villalobos									
130083	Gymnasium				3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 10:12:11 AM				
Mijarez, Jaime	Boys Dressing Room- Holes in ceiling (3 each) patch with drywall and tape texture and paint or order access doors and install								
Alfredo Holguin									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
130802					4/5/2015	4/21/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:19 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.							
Margret Villalobos									
130867					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:53 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
130904					4/5/2015	5/6/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:14 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
130905					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:15 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130906					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:16 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130857					4/5/2015	4/8/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:48 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.							
Margret Villalobos									
129948	Main Building	Office			3/9/2015		37		\$0.00
Medium	Work In Progress	Attendance			3/9/2015 2:13:27 PM				
Mijarez, Jaime		If you could please fix the plastic mold on the floor by the fire extinguisher in the attendance office?							
Loraine Soriano									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
130192	Main Building	Classroom			3/16/2015		30		\$0.00
Medium	Work In Progress	610			3/16/2015 1:47:04 PM				
Mijarez, Jaime		Need a spice rack hung on wall							
Loraine Soriano									
128512	Main Building	Classroom			2/5/2015		69		\$0.00
Medium	Work In Progress	608			2/5/2015 9:43:04 AM				
Mijarez, Jaime		Heater blowing cold air							
Loraine Soriano									
126449	Vocational	Classroom			12/10/2014		126		\$0.00
Medium	Work In Progress	807			12/10/2014 9:20:47 AM				
Mijarez, Jaime		paper towel dispenser							
Loraine Soriano									
126450	Vocational	Classroom			12/10/2014		126		\$0.00
Medium	Work In Progress	807			12/10/2014 9:21:54 AM				
Mijarez, Jaime		paper towel dispenser near sink area							
Loraine Soriano									
128671	Main Building	Classroom			2/9/2015		65		\$0.00
Medium	Work In Progress	610			2/9/2015 12:19:12 PM				
Mijarez, Jaime		Overhead mirror to demo table not working, please see Ms. Lusk for further clarification.							
Loraine Soriano									
130985	Main Building	Classroom			4/6/2015		9		\$0.00
Medium	Work In Progress	610			4/6/2015 10:49:32 AM				
Mijarez, Jaime		Attach overhead mirror to demo table							
Loraine Soriano									
129012	Main Building	Classroom			2/18/2015		56		\$0.00
Medium	Work In Progress	215			2/18/2015 8:44:09 AM				
Mijarez, Jaime		Mice in classroom							
Loraine Soriano									
128886	Main Building	Classroom			2/12/2015		62		\$0.00
Medium	Work In Progress	610			2/12/2015 4:01:11 PM				
Mijarez, Jaime		Second request install mirror for demo table, please see ms lusk for further direction							
Loraine Soriano									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

127813	Main Building	Classroom			1/22/2015		83		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	211			1/22/2015 2:59:55 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Mijarez, Jaime Air conditioner does not turn off

Loraine Soriano

129733	AnnexBuilding	Classroom			3/3/2015		43		\$0.00
--------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	culinary			3/3/2015 3:38:40 PM				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Mijarez, Jaime Racks and picture frames need hanging

Loraine Soriano

129735	AnnexBuilding	Classroom			3/3/2015		43		\$0.00
--------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	culinary			3/3/2015 3:40:30 PM				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Mijarez, Jaime Shelves needs holder

Loraine Soriano

129736	AnnexBuilding	Classroom			3/3/2015		43		\$0.00
--------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	culinary			3/3/2015 3:41:20 PM				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Mijarez, Jaime coat rack needs hanging

Loraine Soriano

130283	Cafeteria (2005)	Parking Lot			3/17/2015		29		\$0.00
--------	------------------	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	gate next to			3/17/2015 3:45:27 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Mijarez, Jaime Gate next to cafeteria needs to be looked at very difficult to open and close.

Loraine Soriano

129022	Main Building	Parking Lot			2/18/2015		56		\$0.00
--------	---------------	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	parking lot			2/18/2015 10:12:27 AM				
--------	------------------	-------------	--	--	-----------------------	--	--	--	--

Mijarez, Jaime Painting of directionality symbols on parking lot to make traffic flow better

Loraine Soriano

128400	Main Building	Parking Lot			2/3/2015		71		\$0.00
--------	---------------	-------------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Parking Lot			2/3/2015 11:04:36 AM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Mijarez, Jaime Work order placed last year for painting of parking lot for arrows etc., for better flow of traffic.

Loraine Soriano

126748	Main Building	Parking Lot			12/18/2014		118		\$0.00
--------	---------------	-------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	parking lot			12/18/2014 9:41:16 AM				
--------	------------------	-------------	--	--	-----------------------	--	--	--	--

Mijarez, Jaime Painting parking barriers to prevent accidents

Loraine Soriano

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

123084	Main Building	Classroom			9/23/2014		204		\$0.00
--------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Lab C-1			9/23/2014 3:16:04 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Mijarez, Jaime Cabinet door in computer lab office in broken.

Loraine Soriano

122803	Cafeteria (2005)	Auditorium			9/15/2014		212		\$0.00
--------	------------------	------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Theater area			9/15/2014 4:14:10 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Mijarez, Jaime Workshop lights, restroom not working

Loraine Soriano

124299	AnnexBuilding	Classroom			10/17/2014		180		\$0.00
--------	---------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	culinary arts			10/17/2014 12:25:41				
--------	------------------	---------------	--	--	---------------------	--	--	--	--

Mijarez, Jaime Lockers need to be moved to classroom as well as mounted if possible. Please see Ms. Perez for clarification.

Loraine Soriano

124301	Main Building	Classroom			10/17/2014		180		\$0.00
--------	---------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	209			10/17/2014 2:45:48 PM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Mijarez, Jaime Needs a safety goggle sanitation cabinet installed in classroom. There might be a possibility that an outlet maybe required for this cabinet. Please see Mrs. Nunez for further information and placement of cabinet.

Loraine Soriano

123220	Main Building	Library			9/25/2014		202		\$0.00
--------	---------------	---------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	library			9/25/2014 8:26:27 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Mijarez, Jaime Air conditioning in office needs to be looked at as it is not working

Loraine Soriano

129113	Gymnasium	Athletic Field			2/20/2015		54		\$0.00
--------	-----------	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	entrance soccer			2/20/2015 10:00:30 AM				
--------	------------------	-----------------	--	--	-----------------------	--	--	--	--

Mijarez, Jaime Install signs stating employees only so parents and students do not enter from those areas

Loraine Soriano

119430	Concession	Athletic Field			7/15/2014		274		\$0.00
--------	------------	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/15/2014 11:48:16 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Mijarez, Jaime Holes in concession building near water fountain have exposed copper tubing

Rosalinda Rodriguez

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

120179 Main Building Classroom 8/1/2014 257 \$0.00

Medium Work In Progress 505 8/1/2014 11:56:03 AM

Mijarez, Jaime Replace pencil sharpner

Loraine Soriano

121267 Main Building Classroom 8/15/2014 243 \$0.00

Medium Work In Progress 608 8/15/2014 2:08:18 PM

Mijarez, Jaime Anchor cabinets

Loraine Soriano

121272 Main Building Classroom 8/15/2014 243 \$0.00

Medium Work In Progress 206 8/15/2014 2:15:43 PM

Mijarez, Jaime Remove old white board and old screen

Loraine Soriano

124455 Main Building Classroom 10/22/2014 175 \$0.00

Medium Work In Progress 314 10/22/2014 12:30:35

Mijarez, Jaime Map strips need center screws, Please refer to Ms. Thornly for further clarification

Loraine Soriano

130740 3/31/2015 15 \$0.00

Medium Work In Progress 3/31/2015 12:38:10 AM

Mijarez, Jaime Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.

Margret Villalobos

130962 4/5/2015 4/11/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:30:46 AM

Mijarez, Jaime Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

131226 4/12/2015 4/28/2015 3 \$0.00

Medium Work In Progress 4/12/2015 12:23:32 AM

Mijarez, Jaime Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.

Margret Villalobos

131321 4/13/2015 2 \$0.00

Medium Work In Progress COUNSELING 4/13/2015 3:48:34 PM

Mijarez, Jaime BULLETIN BOARD NEEDS TO BE MOUNTED IN THE COUNSELING CTR.

Marylou Jimenez

4/15/2015 3:50:41 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
128818	Main Building	Hallway/Corridor			2/11/2015		63		\$0.00
Medium	Work In Progress	mailbox 123			2/11/2015 4:05:28 PM				
Lara, Ralph		lock not functioning with key							
Loraine Soriano									
131033	Concession	Athletic Field			4/7/2015		8		\$0.00
Medium	Work In Progress	baseball field			4/7/2015 9:45:10 AM				
Lara, Ralph		Door knob on concession stand needs to be replaced as soon as possible							
Loraine Soriano									
127117	Main Building	Classroom			1/6/2015		99		\$0.00
Medium	Work In Progress	215			1/6/2015 2:13:42 PM				
Lara, Ralph		keys for patio area in room 215							
Loraine Soriano									
128817	Main Building	Classroom			2/11/2015		63		\$0.00
Medium	Work In Progress	704			2/11/2015 4:03:59 PM				
Lara, Ralph		key for room 704							
Loraine Soriano									
129161	Vocational	Classroom			2/23/2015		51		\$0.00
Medium	Work In Progress	805			2/23/2015 12:20:03 PM				
Lara, Ralph		Needs keys for flammable cabinets							
Loraine Soriano									
130124	Main Building	Classroom			3/13/2015		33		\$0.00
Medium	Work In Progress	teachers lounge			3/13/2015 8:54:59 AM				
Lara, Ralph		door handle lock not working							
Loraine Soriano									
130125	Main Building	Classroom			3/13/2015		33		\$0.00
Medium	Work In Progress	311			3/13/2015 8:56:28 AM				
Lara, Ralph		Keysticks and handle difficult to open							
Loraine Soriano									
129734	Annex Building	Classroom			3/3/2015		43		\$0.00
Medium	Work In Progress	classroom			3/3/2015 3:39:32 PM				
Lara, Ralph		locker does not lock							
Loraine Soriano									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
129731	AnnexBuilding	Classroom			3/3/2015		43		\$0.00
Medium	Work In Progress	culinary			3/3/2015 3:37:58 PM				
Lara, Ralph		Doors do not lock and front door has problems opening							
Loraine Soriano									
130121	Main Building	Classroom			3/13/2015		33		\$0.00
Medium	Work In Progress	215			3/13/2015 8:19:03 AM				
Lara, Ralph		Need key for patio outside room 215							
Loraine Soriano									
130122	Main Building	Classroom			3/13/2015		33		\$0.00
Medium	Work In Progress	computer lab C4			3/13/2015 8:20:14 AM				
Lara, Ralph		lock in C4 not working							
Loraine Soriano									
129639		Athletic Field			3/2/2015		44		\$0.00
Medium	Work In Progress				3/2/2015 2:28:47 PM				
Flores, Pete		kubota RTV 400 needs to be service S.T.H.S and G.H.S							
Guadalupe Ontiveros									
129633					3/2/2015		44		\$0.00
Medium	Work In Progress				3/2/2015 12:56:18 PM				
Lara, Ralph		Cafeteria. Three exit door hydraulic closers are not working and are leaking fluid causing doors to slam. They need to be replaced.							
Jaime Mijarez									
129005	Locker Room	Football Field			2/18/2015		56		\$0.00
Medium	Work In Progress	football locker			2/18/2015 8:10:50 AM				
Lara, Ralph		second request football locker room door is not locking appropriately							
Loraine Soriano									
128388	Gymnasium	Athletic Field			2/3/2015		71		\$0.00
Medium	Work In Progress	baseball field			2/3/2015 9:33:05 AM				
Llanez, Rick		Baseball field several request for wind screen, season has started and no progress has been made							
Loraine Soriano									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

120625 Athletic Field 8/6/2014 252 \$0.00

Medium Work In Progress Football field 8/6/2014 9:23:08 AM

Llanez, Rick Turf field in dire need of brushing and maintenance. Pellets needed and field needs to be maintained twice a month. Schedule dates are needed for proper care and equipment needed to brush field as well as pellets. It is crucial as season begins in two weeks.

Lorraine Soriano

124799 Main Building Athletic Field 10/30/2014 167 \$0.00

Medium Work In Progress softball 10/30/2014 3:57:02 PM

Llanez, Rick Windscreen missing to complete the field. Not complete in the outfield.

Lorraine Soriano

126284 12/5/2014 131 \$0.00

Medium Work In Progress 12/5/2014 11:00:49 AM

Llanez, Rick Clean sand around track.

Michael Munoz

123989 10/10/2014 187 \$0.00

Medium Work In Progress 10/10/2014 11:00:23

Llanez, Rick Please fix hole in sidewalk at the end of Science Wing. Please see e-mail for pictures of area. Should you have any questions please contact Mr. Ralph Gallegos at 575 - 882-6921 in the Construction office. Thank You

Dominique Esparza

121492 Main Building Exterior 8/20/2014 238 \$0.00

Medium Work In Progress sidewalk 8/20/2014 8:59:58 AM

Llanez, Rick Sidewalk toward arroyo has hollow areas where water has taken sand out from under it.

Lorraine Soriano

129493 3/1/2015 45 \$0.00

Medium Work In Progress 3/1/2015 12:45:54 AM

Sanchez, Raul Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PM schedule details.

Margret Villalobos

131064 4/7/2015 8 \$0.00

Medium Work In Progress 4/7/2015 3:53:59 PM

Flores, Pete Maintenance truck has a flat tire.

Jaime Mijarez

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

130837 4/5/2015 4/26/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:29:38 AM

Munoz, Michael Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

126771 Main Building Classroom 12/18/2014 118 \$0.00

Medium Work In Progress outside behind 12/18/2014 3:30:35 PM

Munoz, Michael tire ramps to have access to classroom for grocery drop off

Loraine Soriano

124792 Main Building Athletic Field 10/30/2014 167 \$0.00

Medium Work In Progress football field 10/30/2014 3:49:56 PM

Munoz, Michael Football/soccer score board due to malfunction to box. Scoreboard is about 21 years old.

Loraine Soriano

130533 Main Building Athletic Field 3/24/2015 22 \$0.00

Medium Work In Progress concession 3/24/2015 3:45:14 PM

Villalobos, Margret Two pine trees removed from the west side of the concession. Please see Rick for further instructions.

Loraine Soriano

130607 3/26/2015 20 \$0.00

Medium Work In Progress 3/26/2015 7:56:47 AM

Villalobos, Margret Chiller Plant
3:04 PM Mar 20, 2015
Low Evaporator Rfgr temp- ckt 2

Jaime Mijarez

130860 4/5/2015 4/21/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:29:50 AM

Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.

Margret Villalobos

129509 3/1/2015 3/17/2015 45 \$0.00

Medium Work In Progress 3/1/2015 12:46:04 AM

Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details. 3/2 - Emailed

Margret Villalobos

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
126974					1/4/2015	1/25/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:41:34 AM				
Munoz, Michael		Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
Count: 147 Work Orders			Avg. Age of WO's	87	Total for Santa Teresa HS			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
130131	North Building	Classroom			3/13/2015		33		\$0.00
Medium	Work In Progress	ROOM 3			3/13/2015 12:28:22 PM				
Villalobos, Margret		ABNORMAL AMOUT OF SPIDERS INSIDE AND OUTSIDE CLASSROOM. STUDENT WAS BITTEN				Emailed Waiver 3/17/15			
Laura Parra									
130965					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:48 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
130911					4/5/2015	5/6/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:18 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
130912					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:19 AM				
Prospero, Manuel		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
130913					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:19 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
130914					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:20 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
130744					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:12 AM				
Prospero, Manuel		Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PMschedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

130531 3/24/2015 22 \$0.00

Medium Work In Progress 3/24/2015 3:44:07 PM

Prospero, Manuel 3/24/15. 2HRS FIXING DOOR ON ROOM 32. 1HR INSTALL DOOR STOPER ROO 31. 2HRS WO 130510. 3HRS REPLACE CEILING TILES ROOM 9.

Manuel Prospero

130091 Parking Lot 3/12/2015 34 \$0.00

Medium Work In Progress 3/12/2015 12:42:30 PM

Prospero, Manuel 3/12/15. WE NEED TO REPAINTING ALL PARKING LINES (NORTH PARKING AND SOUTH PARKING).

Manuel Prospero

130076 Gym (1997) Gym 3/12/2015 34 \$0.00

Medium Work In Progress MS SNYDER 3/12/2015 8:37:03 AM

Prospero, Manuel REPAIR POST ON THE NORTH BASKETBALL COURTS FOR A TENNIS NET. PAINT LINES ON THE COURTS OUTSIDE

Laura Parra

125158 South Building Classroom 11/5/2014 161 \$0.00

Medium Work In Progress 47- 11/5/2014 8:33:40 AM

Prospero, Manuel AIR CONDITIONER MAKING LOUD NOISES

Laura Parra

124448 North Building Classroom 10/22/2014 175 \$0.00

Medium Work In Progress 6-BAILEY 10/22/2014 10:51:27

Prospero, Manuel CEILING LEAKING.

Laura Parra

123945 North Building Classroom 10/9/2014 188 \$0.00

Medium Work In Progress 12-CRAVENS 10/9/2014 3:13:19 PM

Prospero, Manuel 1- SINK PIPE IS LEAKING- RIGHT SINK
2- BRACKS NEED TO BE REMOVED WITH SCREWS FROM BACK WALL

Laura Parra

122262 South Building Classroom 9/3/2014 224 \$0.00

Medium Work In Progress 55-WOLLARD 9/3/2014 3:35:43 PM

Prospero, Manuel AIR CONDITIONER IS EXTREMELY LOUD AND TILES ARE GETTING WET

Laura Parra

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

124584	South Building	Hallway/Corridor			10/24/2014		173		\$0.00
--------	----------------	------------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	#44-ALLEN			10/24/2014 2:56:08 PM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Prospero, Manuel REMOVE LOCKERS. STUDENTS ARE PUTTING TRASH IN THEM

Laura Parra

120786	South Building	Hallway/Corridor			8/8/2014		250		\$0.00
--------	----------------	------------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	UPSTAIRS			8/8/2014 8:31:33 AM				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Prospero, Manuel PLEASE REMOVE LOCKERS AND INSTALL IN P.E (SEE MS SNYDER)

Laura Parra

122257	South Building	Hallway/Corridor			9/3/2014		224		\$0.00
--------	----------------	------------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	HALL WAY			9/3/2014 3:33:19 PM				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Prospero, Manuel REMOVE LOCKERS FROM WALL OUTSIDE ROOM 44-45. SECOND REQUEST

Laura Parra

129286	North Building	Office			2/25/2015		49		\$0.00
--------	----------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	BONNIE			2/25/2015 12:45:02 PM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Prospero, Manuel 1. REPLACE CEILING TILE IN NORTH OFFICE
2. PAINT FRAMES ON DOORS AND MAIN DOORS

Laura Parra

131099	North Building	Classroom			4/8/2015		7		\$0.00
--------	----------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	1- MEISTER			4/8/2015 12:20:21 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Prospero, Manuel 1-10X10X10 MESH ART DISPLAY WITH METAL POLES NEEDS TO BE TAKEN TO GMS ON APRIL 22 FOR GISD ART SHOW. PICK UP ON APRIL 26

Laura Parra

129166	North Building	Classroom			2/23/2015		51		\$0.00
--------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/23/2015 1:17:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel 2/23/15. WE NEED TO CHANGED 3 ELECTRIC MOTORS ON ROOM 3. 1 EXAUST FAN MOTOT ON KITCHEN MODEL NUM 76.000-G 120 VOLTS60 HZ3 AMPSCFMHQR 200 SONES 6.0RANGE HOOO 39A. CLEAN FAN FILTER AND GREASE. AND 2 MORE FOR RESTROOM AND CLOUSET. MODEL NUM SP-117 SERIAL NUM 93F09530 115 VOLTS

Manuel Prospero

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
130425	North Building	Classroom			3/20/2015		26		\$0.00
Medium	Work In Progress	22-PRADO			3/20/2015 2:19:57 PM				
Prospero, Manuel		REPLACE MISSING CEILING TILES AND STAINED TILES FROM LEAK							
Laura Parra									
130510	South Building	Classroom			3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 11:53:57 AM				
Prospero, Manuel		Fix 4 broken desk for Mr.Santillan.							
Ismael Rodriguez									
130666	South Building	Classroom			3/27/2015		19		\$0.00
Medium	Work In Progress	39 TATUM			3/27/2015 2:20:36 PM				
Prospero, Manuel		REPLACE 4 CEILING TILES DISCOLORED DUE TO AIR CONDITIONER LEAK							
Laura Parra									
126528	North Building	Classroom			12/11/2014		125		\$0.00
Medium	Work In Progress	3-PORTILLO			12/11/2014 12:45:36				
Prospero, Manuel		1- EXHAUST FAN IN THE BATHROOM IS NOT WORKING PROPERLY. 2- EXHAUST FAN OVER THE STOVE IS NOT WORKING							
Laura Parra									
129561					3/1/2015		45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:35 AM				
Prospero, Manuel		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
130843					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:41 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Roof Inspection - Refer to PMschedule details.							
Margret Villalobos									
130793					4/5/2015	4/21/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:14 AM				
Prospero, Manuel		Monthly - Santa Teresa MS A1(Wall Refr.E/H)(Semi) - Refer to PMschedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
129474					3/1/2015		45		\$0.00
Medium	Work In Progress			3/1/2015 12:45:43 AM					
Prospero, Manuel	Yearly - Santa Teresa MS A10 (Heat Pump)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
126039	North Building	Kitchen			12/1/2014		135		\$0.00
High	Work In Progress			12/1/2014 11:12:42 AM					
Prospero, Manuel	Please remove toilet so floor can be tiled. Rodriguez upholsterys should be there on December 2, 2014 at around 2:00 pm.								
Jesus Estrada									
131025	North Building	Custodial			4/7/2015		8		\$0.00
Medium	Work In Progress			4/7/2015 7:43:08 AM					
Prospero, Manuel	The Fridge in custodial lounge is not working need to be check.								
Ismael Rodriguez									
131138		Football Field			4/9/2015		6		\$0.00
Medium	Work In Progress			4/9/2015 9:52:41 AM					
Lara, Ralph	NEED TO REPLACE 6 PAD LOCKS FOT THE FOOTBALL FIELD AREA . PAD LOCKS ARE RUSTED. ALSO NEED THE PAD LOCK CLRAN AND LUBRICATED FOR ALL OF AUR GATES TO OUR SCHOOL IF NEED REPLACE THEM ALSO. ALSO NEED A CHAIN EITH A PAD LOCK FOR THE LAST GATE BY THE PORTABLE.								
Manuel Prospero									
128139					1/30/2015		75		\$0.00
Medium	Work In Progress			1/30/2015 10:38:32 AM					
Lara, Ralph	Both Bldgs Girls Restrooms - Please check latches on stall doors , theydo not align and not able to lock when in use.								
Richard Chavez									
128565	South Building	Office			2/6/2015		68		\$0.00
Medium	Work In Progress	SECURITY			2/6/2015 8:29:57 AM				
Lara, Ralph	AS PER MR LARA- REMOVE AND REPLACE DOOR								
Laura Parra									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
130447	Gym (1997)				3/23/2015		23		\$0.00
Medium	Work In Progress				3/23/2015 7:57:20 AM				
Lara, Ralph		Exterior Doors on North Side of Gym - Doors are sagging on hinges, binding							
Alfredo Holguin									
131175	North Building	Athletic Field			4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 7:41:28 AM				
Lara, Ralph		Replace locks in atheletic field back gates there old hard to open thanks.							
Ismael Rodriguez									
131371	Gym (1997)	Gym			4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 10:07:27 AM				
Lara, Ralph		Gym boys dressing room exit door the panic bar doest work and niether the key.							
Ismael Rodriguez									
131094	North Building	Classroom			4/8/2015		7		\$0.00
Medium	Work In Progress				4/8/2015 11:40:15 AM				
Lara, Ralph		Replace the keycore on room#21							
Ismael Rodriguez									
123993	North Building	Classroom			10/10/2014		187		\$0.00
Medium	Work In Progress				10/10/2014 11:16:43				
Ontiveros, Joe		Need to replace p-trap in RM #12							
Ismael Rodriguez									
130093	Gym (1997)	Gym			3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 12:53:47 PM				
Ontiveros, Joe		Boys dressing room urinal is clog up need to be check.							
Ismael Rodriguez									
131179	South Building	Foyer			4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 8:50:17 AM				
Estrada, Jesus		Replace with vct in south lobby the tile is in bad shape.							
Ismael Rodriguez									
130993		Gym			4/6/2015		9		\$0.00
Medium	Work In Progress				4/6/2015 11:36:53 AM				
Estrada, Jesus		varnish gym floor							
Jesus Estrada									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
131007					4/6/2015		9		\$0.00
Medium	Work In Progress				4/6/2015 3:23:55 PM				
Alvarado, Julio		need to remove dirt inside where gas meter is located.							
Guadalupe Ontiveros									
130228	North Building	Kitchen			3/17/2015		29		\$0.00
Medium	Work In Progress				3/17/2015 8:03:34 AM				
Ontiveros, Joe		Replace water faucet in principles kitchen.							
Ismael Rodriguez									
127311	Gym (1997)	Mechanical			1/9/2015		96		\$0.00
Medium	Work In Progress				1/9/2015 3:15:27 PM				
Ontiveros, Joe		1/9/15. WE NEED TO REPLACE WATER HEATER ON GYM, IS BROCK (96GALL).							
Manuel Prospero									
131423	North Building	Restroom			4/15/2015		0		\$0.00
Medium	Work In Progress				4/15/2015 9:18:36 AM				
Ontiveros, Joe		Sink in boys restroom is clog north upper level.							
Ismael Rodriguez									
130226	North Building	Restroom (Girls)			3/17/2015		29		\$0.00
Medium	Work In Progress				3/17/2015 7:52:46 AM				
Ontiveros, Joe		Replace North and South Building girls restroom water faucets with new ones their in bad shape.							
Ismael Rodriguez									
130509	North Building	Athletic Field			3/24/2015		22		\$0.00
Medium	Work In Progress				3/24/2015 11:51:11 AM				
Ontiveros, Guadalupe		I still need 5 metal drums to replace old one and pick up the old trash drums.							
Ismael Rodriguez									
131237					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:38 AM				
Rodriguez, Ismael		Monthly - QRTLTY BLDG INSP REPORT (STM) - Refer to PM schedule details.							
Margret Villalobos									
124639	South Building	Mechanical			10/27/2014		170		\$0.00
Medium	Work In Progress				10/27/2014 3:30:16 PM				
Ambriz, Jose		10/27/14. A/C MECANICAL ROOM SOUH BUILDING IS NOT WORKING.							
Manuel Prospero									
4/15/2015 3:50:41 PM									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa MS							
130699					3/30/2015		16		\$0.00
Medium	Work In Progress				3/30/2015 7:48:17 AM				
		NEED TO REPAIR GAS METER BLOCK WALL							
Alfredo Holguin									
127696	North Building	Office			1/20/2015		85		\$0.00
Medium	Work In Progress	8- Nurses Office			1/20/2015 10:56:02 AM				
Castillo, Carlos		Install light switch on the back entry door							
Laura Parra									
131353	North Building	Custodial			4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 8:00:46 AM				
Carrasco, Danny		Fuel for groundsman and custodial equipment thanks.							
Ismael Rodriguez									
131273	South Building				4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 7:59:20 AM				
Carrasco, Danny		There are two windows broken one in lower level and top level floor replace a.s.a.p...							
Ismael Rodriguez									
131294	North Building	Office			4/13/2015		2		\$0.00
Medium	Work In Progress	Ms Parra/Mr.			4/13/2015 11:56:31 AM				
Carrasco, Danny		FUEL NEEDED FOR ADMINISTRATOR'S GATORS							
Laura Parra									
130617	Gym (1997)	Gym			3/26/2015		20		\$0.00
Medium	Work In Progress				3/26/2015 10:39:09 AM				
Ronquillo, Ruben		3/26/15. WE NEED REPLACE AT LOBY WINDOW GLASS 47 3/4. X 45 1/4							
Manuel Prospero									
131360					4/14/2015		1		\$0.00
Medium	Work In Progress				4/14/2015 8:31:06 AM				
Ronquillo, Ruben		Room 504 broken window 36'3/8" x 29'3/8"							
Jaime Mijarez									
131176	North Building	Portables			4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 7:45:00 AM				
Gonzalez, Salvador		A piece of pipe need to be welded in order to secure the back gate behind the portables thanks.							
Ismael Rodriguez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Santa Teresa MS							
128962	North Building	Custodial			2/17/2015		57		\$0.00
Medium	Work In Progress				2/17/2015 11:59:58 AM				
Gonzalez, Salvador		Need to weld a stand for lights see Mr.Rodriguez.							
Ismael Rodriguez									
Count: 58 Work Orders		Avg. Age of WO's 53			Total for Santa Teresa MS			0	\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunland Park ES							
129176					2/23/2015		51		\$0.00
Medium	Work In Progress				2/23/2015 3:22:09 PM				
Gonzalez, Salvador		need to weld metal to ramps on portable d							
Carlos Hernandez									
129355					2/26/2015		48		\$0.00
Medium	Work In Progress				2/26/2015 3:00:44 PM				
Gonzalez, Salvador		need metal steps for portable e							
Carlos Hernandez									
130235					3/17/2015		29		\$0.00
Medium	Work In Progress	FOOTBALL			3/17/2015 8:37:45 AM				
Gonzalez, Salvador		FOOTBALL FIELD- SOCCER GOAL NEEDS TO BE ANCHORED DOWN AND WATER FOUNTAIN NEED TO FIXED AS WELL							
Maribel Chavez									
131212					4/10/2015		5		\$0.00
Medium	Work In Progress				4/10/2015 3:39:40 PM				
Gonzalez, Salvador		need to weld or replace hinges to front gate.(safety hazard fell off on 4-10-15)							
Carlos Hernandez									
124374					10/21/2014		176		\$0.00
Medium	Work In Progress	SCHOOL			10/21/2014 8:19:39 AM				
Ronquillo, Ruben		CARLOS-							
David Avila		AS PER MR. VAN NOSDALE: IS THERE A WAY TO FIX THE SCHOOL'S MARQUEE? THERE IS A HOLE IN ONE OF THE PANELS WHICH MAKES IT LOOK REALLY BAD AND WE ARE NOT ABLE TO PUT FULL MESSAGES ON THE MARQUEE. PLEASE LET US KNOW IF THERE IS ANYTHING THAT CAN BE DONE. THANK YOU.							
129356					2/26/2015		48		\$0.00
Medium	Work In Progress				2/26/2015 3:02:52 PM				
Ronquillo, Ruben		need blinds for portable a and b 2=30x58 and 4= 34x46							
Carlos Hernandez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
127545					1/14/2015		91		\$0.00
Medium	Work In Progress				1/14/2015 3:16:36 PM				
Carrasco, Danny		need these tools 6 in one screw driver 5/16 bit 8 ft fiberglass ladder channel locks							
Carlos Hernandez									
129357					2/26/2015		48		\$0.00
Medium	Work In Progress				2/26/2015 3:10:50 PM				
Castillo, Carlos		need light fixture replace in bathroom to portable a							
Carlos Hernandez									
130702		Office			3/30/2015		16		\$0.00
Medium	Work In Progress				3/30/2015 8:21:47 AM				
Gonzales, Camilo		Pick Up obsolete items and deliver to IM/WHSE. See daily delivery log for list.							
Theresa Ramirez									
127809		Classroom			1/22/2015		83		\$0.00
Medium	Work In Progress	LIBRARY			1/22/2015 1:26:00 PM				
Holguin, Alfredo		LIBRARY- NEED TO HAVE CEMENT COMPLETED ON THE SIDE WALK ON THE NORTH SIDE OF THE BUILDING RIGHT NEXT TO ROAD. (BOOK FAIR WILL ARRIVE FEB. 11,2015)							
Maribel Chavez									
131339					4/14/2015		1		\$0.00
Medium	Work In Progress	KARLA			4/14/2015 7:40:44 AM				
Gonzales, Camilo		DELIVER PO 141526419 EL PASO OFFICE PRODUCTS 1 BOX KARLA HERRERA, TEACHER							
Margaret Villalobos									
131343					4/14/2015		1		\$0.00
Medium	Work In Progress	KARLA			4/14/2015 7:43:42 AM				
Gonzales, Camilo		DELIVER PO 141506416 ORIENTAL TRADING 1 BOX KARLA HERRERA, TEACHER							
Margaret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunland Park ES							
131345					4/14/2015		1		\$0.00
Medium	Work In Progress	KARLA			4/14/2015 7:45:10 AM				
Gonzales, Camilo		DELIVER PO 141506417 ORIENTAL TRADING 1 BOX KARLA HERRERA, TEACHER							
Margaret Villalobos									
131349					4/14/2015		1		\$0.00
Medium	Work In Progress	KARLA			4/14/2015 7:51:27 AM				
Gonzales, Camilo		DELIVER PO 141506411 LAKESHORE LEARNING 4 BOXES KARLA HERRERA, TEACHER							
Margaret Villalobos									
131350					4/14/2015		1		\$0.00
Medium	Work In Progress	KARLA			4/14/2015 7:54:18 AM				
Gonzales, Camilo		DELIVER PO #141506412 LAKESHORE LEARNING 1 BOX KARLA HERRERA, TEACHER							
Margaret Villalobos									
131351					4/14/2015		1		\$0.00
Medium	Work In Progress	KARLA			4/14/2015 7:55:45 AM				
Gonzales, Camilo		DELIVER PO 141506414 LAKESHORE LEARNING 1 BOX KARLA HERRERA, TEACHER							
Margaret Villalobos									
131355					4/14/2015		1		\$0.00
Medium	Work In Progress	KARLA			4/14/2015 8:04:36 AM				
Gonzales, Camilo		DELIVER PO 141506415 LAKESHORE LEARNING 1 BOX KARLA HERRERA, TEACHER							
Margaret Villalobos									
129873		Classroom			3/6/2015		40		\$0.00
Medium	Work In Progress	16			3/6/2015 11:20:38 AM				
Hernandez, Carlos		RM#16- RUBIO- LOWER MY WHITE BOARD AND REPLACE PENCIL SHARPNER IF WE HAVE ANY NEW ONES IN OFFICE							
Maribel Chavez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
130038		Classroom			3/11/2015		35		\$0.00
Medium	Work In Progress	16			3/11/2015 2:11:37 PM				
Hernandez, Carlos		RM#16- RUBIO- PUT BACK TOGETHER A BOOKSHELF WITH SCREWS FIX A BOOKSHELF AS SOON AS POSSIBLE							
Maribel Chavez									
131134		Classroom			4/9/2015		6		\$0.00
Medium	Work In Progress	24			4/9/2015 8:26:33 AM				
Hernandez, Carlos		RM#24- L MARRUFO - WINDOWS WONT CLOSE PROPERLY GRIFFITTI ON WINDOW GLASS.							
Maribel Chavez									
128591		Classroom			2/6/2015		68		\$0.00
Medium	Work In Progress	32			2/6/2015 11:56:37 AM				
Hernandez, Carlos		RM#32 ARAPI- NEED TO HAVE A HANDICAP BAR INSTALLED IN THERE BATHROOM							
Maribel Chavez									
130385		Office			3/19/2015		27		\$0.00
Medium	Work In Progress	OFFICE			3/19/2015 3:06:50 PM				
Hernandez, Carlos		OFFICE - DUQUE- REPLACE LIGHT BULBS IN HER OFFICE							
Maribel Chavez									
130365		Classroom			3/19/2015		27		\$0.00
Medium	Work In Progress	24			3/19/2015 10:13:59 AM				
Hernandez, Carlos		RM#24- K. HERRERA- PLEASE CHECK WASHER AND DRYER, GIVE MAINTENANCE TO SEE IF ITS WORKING PROPERLY OR IF NEEDS PARTS.							
Maribel Chavez									
130367		Classroom			3/19/2015		27		\$0.00
Medium	Work In Progress				3/19/2015 10:24:53 AM				
Hernandez, Carlos		RM#22-K.HERRERA-BICYCLE NEEDS SCREW TO PUT SIT BACK ON IT. BICYCLE IS USED FOR A STUDENT WHEN USING CALMING TECHNIQUES ON BIP SCREW MISSING							
Maribel Chavez									
131027		Library			4/7/2015		8		\$0.00
Medium	Work In Progress	LIBRARY			4/7/2015 8:31:41 AM				
Hernandez, Carlos		LIBRARY - VILLA - NEEDS BULBS REPLACED							
Maribel Chavez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

130238 Library 3/17/2015 29 \$0.00

Medium Work In Progress LIBRARY 3/17/2015 8:44:01 AM

Hernandez, Carlos LIBRARY- NEED BANNERS HUNG IN THE MAIN HALLWAY WILL NEED ACCESS TO THE SCISSOR LEFT TO PLACE THESE UP

Maribel Chavez

131152 4/9/2015 6 \$0.00

Medium Work In Progress 4/9/2015 3:36:18 PM

Hernandez, Carlos need to replace windows room 39 and 35 10x10 due to vandalism case #201500433

Carlos Hernandez

131252 4/12/2015 4/28/2015 3 \$0.00

Medium Work In Progress 4/12/2015 12:23:46 AM

Hernandez, Carlos Monthly - Sunland Park ES Playground Insp - Refer to PMschedule details.

Margret Villalobos

130262 3/17/2015 29 \$0.00

Medium Work In Progress 3/17/2015 2:10:41 PM

Hernandez, Carlos need to replace irrigation valve and couplings

Carlos Hernandez

130818 4/5/2015 4/13/2015 10 \$0.00

Medium Work In Progress 4/5/2015 12:29:28 AM

Hernandez, Carlos Monthly - Sunland Park ES Roof Inspection - Refer to PMschedule details.

Margret Villalobos

129910 3/9/2015 3/24/2015 37 \$0.00

Medium Work In Progress 3/9/2015 12:35:41 AM

Hernandez, Carlos Monthly - Sunland Park ES Playground Insp - Refer to PMschedule details.

Margret Villalobos

122203 9/3/2014 224 \$0.00

Medium Work In Progress PLAYGROUND 9/3/2014 7:24:39 AM

Hernandez, Carlos CARLOS - PLEASE CHECK PLAYGROUND EQUIPMENT. THERE IS A WHITE RAIL THAT IS BROKEN AND IS DANGEROUS. THERE USED TO BE A SLIDE THERE, NOW THERE ARE HANGING PARTS. PLEASE SEE MS. DUQUE FOR FURTHER INSTRUCTIONS. THANK YOU.

David Avila

4/15/2015 3:50:42 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

130242 Portables 3/17/2015 29 \$0.00

Medium Work In Progress PORTABLE A 3/17/2015 9:03:20 AM

Hernandez, Carlos PORTABLE A - CANO- LIGHT IN RESTROOM WENT OUT, IT NEEDS TO BE REPLACED

Maribel Chavez

127268 1/8/2015 97 \$0.00

High Work In Progress 1/8/2015 3:52:21 PM

Ambriz, Jose need to flush system to all hvac coils, flushing was not included on contract. thank you

Michael Munoz

131181 Main Building Custodial 4/10/2015 5 \$0.00

Medium Work In Progress 4/10/2015 10:00:31 AM

Carbajal, Jimmy automatic scrubber does not pick up water if you could plz check it out. thanks

Jesus Lucero

131239 4/12/2015 4/28/2015 3 \$0.00

Medium Work In Progress 4/12/2015 12:23:39 AM

Lucero, Jesus Monthly - QRTLY BDLG INSP REPORT (SP) - Refer to PM schedule details.

Margret Villalobos

128762 2/10/2015 64 \$0.00

Medium Work In Progress 2/10/2015 3:47:58 PM

Ontiveros, Guadalupe need 25 bags of fertilizer

Carlos Hernandez

127906 Restroom (Girls) 1/26/2015 79 \$0.00

Medium Work In Progress 1/26/2015 9:16:04 AM

Ontiveros, Joe GIRL RESTROOM- SINK BROKEN

Maribel Chavez

126029 12/1/2014 135 \$0.00

Medium Work In Progress 12/1/2014 8:49:10 AM

Ontiveros, Joe need new drain kit for sink in nurses office

Carlos Hernandez

123862 Main Building Classroom 10/8/2014 189 \$0.00

Medium Work In Progress 10/8/2014 10:05:34 AM

Estrada, Jesus the tile is lifting up and could become a safety problem this is in room 39. 3/18/15 - ASP CHUY, WILL BE DONE MARCH 30TH - APRIL 3RD.

Jesus Lucero

4/15/2015 3:50:42 PM

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
130324					3/18/2015		28		\$0.00
Medium	Work In Progress				3/18/2015 3:40:50 PM				
Estrada, Jesus		need carpet repaired in portable a							
Carlos Hernandez									
130325					3/18/2015		28		\$0.00
Medium	Work In Progress				3/18/2015 3:42:05 PM				
Estrada, Jesus		need tile door strip in room 32							
Carlos Hernandez									
129353					2/26/2015		48		\$0.00
Medium	Work In Progress				2/26/2015 2:58:02 PM				
Lara, Ralph		need to replace 8 panic bars (out dated no parts)							
Carlos Hernandez									
129354					2/26/2015		48		\$0.00
Medium	Work In Progress				2/26/2015 2:59:19 PM				
Lara, Ralph		need door mullens on west and north doors							
Carlos Hernandez									
127845					1/23/2015		82		\$0.00
Medium	Work In Progress	Front Main Gate			1/23/2015 11:09:20 AM				
Lara, Ralph		OFFICE - NEEDS A EXTRA KEY FOR THE FRONT MAIN GATE							
Maribel Chavez									
130071					3/12/2015		34		\$0.00
Medium	Work In Progress				3/12/2015 7:44:24 AM				
Flores, Pete		lawn mower d130 not working properlyneeds repair							
Carlos Hernandez									
120344					8/3/2014		255		\$0.00
Medium	Work In Progress				8/3/2014 12:33:44 AM				
Munoz, Michael		Yearly - Sunland Park ES Fire Ext. Insp. (Yearly) - Refer to PMschedule details.				PMnot completed as per schedule			
Margret Villalobos									
Count: 47 Work Orders		Avg. Age of WO's	49		Total for Sunland Park ES		0		\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Sunrise ES							
130940					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:34 AM				
Apodaca, Mario	Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
129589					3/1/2015		45		\$0.00
Medium	Work In Progress				3/1/2015 12:46:51 AM				
Apodaca, Mario	Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
131247					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:43 AM				
Gallegos, Felipe	Monthly - QRTLY BLDG INSP REPORT (SR) - Refer to PM schedule details.								
Margret Villalobos									
128595					2/6/2015		68		\$0.00
Medium	Work In Progress				2/6/2015 12:05:54 PM				
Estrada, Jesus	portables 6 and 8 need replacing floor tiles								
Juan Vargas									
130880					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:00 AM				
Vargas, Juan	Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
130881					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:01 AM				
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
130882					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:02 AM				
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunrise ES							
130829					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:34 AM				
Vargas, Juan		Monthly - Sunrise ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
130355					3/19/2015		27		\$0.00
Medium	Work In Progress				3/19/2015 9:06:20 AM				
Vargas, Juan		need replace 1/2 in. poly drip in pine trees							
Juan Vargas									
129106					2/20/2015		54		\$0.00
Medium	Work In Progress				2/20/2015 7:55:13 AM				
Vargas, Juan		need repainting parking lines							
Juan Vargas									
125570					11/14/2014		152		\$0.00
Medium	Work In Progress				11/14/2014 1:15:20 PM				
Vargas, Juan		need replace playground plastic borders north side							
Juan Vargas									
128557					2/6/2015		68		\$0.00
Medium	Work In Progress				2/6/2015 7:44:57 AM				
Vargas, Juan		need replacing units in kitchen and cafeteria							
Juan Vargas									
130942					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:35 AM				
Vargas, Juan		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
130742					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:11 AM				
Vargas, Juan		Monthly - Sunrise ES A16 (Fan Exh.)(S. Annual) - Refer to PM schedule details.							
Margret Villalobos									
131262					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress				4/12/2015 12:23:52 AM				
Vargas, Juan		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
125113					11/3/2014		163		\$0.00
Medium	Work In Progress				11/3/2014 3:48:14 PM				
Ontiveros, Guadalupe		need arena for 2 playgrounds 40 tons.							
Juan Vargas									
120861					8/8/2014		250		\$0.00
Medium	Work In Progress				8/8/2014 3:25:05 PM				
Ontiveros, Guadalupe		need fix o r replace relase valve in irrigation buster pump							
Juan Vargas									
130658					3/27/2015		19		\$0.00
Medium	Work In Progress	SLP TESTING			3/27/2015 11:14:32 AM				
Gonzales, Camilo		PICK UP HP COLOR LASTERJET 1500L PRINTER #SE6159 PRINTER OBSOLETE/NOT WORKING DISPOSE							
Margaret Villalobos									
130384					3/19/2015		27		\$0.00
Medium	Work In Progress				3/19/2015 3:06:35 PM				
Vallejo, Albert		need 120 volt for a/c unite motor in testin room							
Juan Vargas									
131297		Office			4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 1:38:33 PM				
Gonzales, Camilo		Deliver 1 box. PO# 141506726. Thank you.							
Theresa Ramirez									
126900					1/4/2015	2/4/2015	101		\$0.00
Medium	Work In Progress				1/4/2015 12:40:33 AM				
Villalobos, David		Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
130301					3/18/2015		28		\$0.00
Medium	Work In Progress				3/18/2015 8:51:52 AM				
Orozco, Daniel		ICE MACHINE NOT MAKING ICE. SNP MANAGER GLENDA G. 824.3194							
Maritza Gonzalez									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
131434					4/15/2015		0		\$0.00
Medium	Work In Progress				4/15/2015 11:31:18 AM				
Marquez, Gerardo		please check mans r. room stock lock							
Juan Vargas									
124690					10/28/2014		169		\$0.00
Medium	Work In Progress				10/28/2014 3:28:58 PM				
Appelzoller, Fred		200 boy r.room need fix or replace sink foucet							
Juan Vargas									
120182					8/1/2014		257		\$0.00
Medium	Work In Progress				8/1/2014 12:10:52 PM				
Appelzoller, Fred		need replace map sinck and fouset is broke							
Juan Vargas									
130216					3/16/2015		30		\$0.00
Medium	Work In Progress				3/16/2015 3:52:07 PM				
Appelzoller, Fred		grls. r,roms next.to cafeteria need replace fouset broken							
Juan Vargas									
Count: 26 Work Orders			Avg. Age of WO's	59		Total for Sunrise ES	0		\$0.00

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
131139					4/9/2015		6		\$0.00
Medium	Work In Progress				4/9/2015 9:56:28 AM				
Marquez, Gerardo		staff restroom by teachers lounge needs to be able to be locked							
Armando Diaz									
130660		Classroom			3/27/2015		19		\$0.00
Medium	Work In Progress	Room # 202			3/27/2015 12:28:22 PM				
Marquez, Gerardo		Mr. Sullivan need the lock from the back room (closet test room) in room #202 to switch back the way it was before.							
Sylvia Cary									
130797					4/5/2015	4/26/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:16 AM				
Orozco, Daniel		Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.							
Margret Villalobos									
126444					12/10/2014		126		\$0.00
Medium	Work In Progress				12/10/2014 9:11:12 AM				
Orozco, Daniel		SINK - WHEN SHUT OFF WATER LEAKS. SNP MANAGER ELIZABETH M. 233.2945							
Maritza Gonzalez									
128036					1/28/2015		77		\$0.00
Medium	Work In Progress				1/28/2015 12:37:24 PM				
Orozco, Daniel		REACH IN IS NOT COOLING. SNP MANAGER ELIZABETH M. 233.2945							
Maritza Gonzalez									
128037					1/28/2015		77		\$0.00
Medium	Work In Progress				1/28/2015 12:38:28 PM				
Orozco, Daniel		ICE MAKER NOT MAKING ICE. SNP MANAGER ELIZABETH M. 233.2945							
Maritza Gonzalez									
131310					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 3:30:06 PM				
Sotelo, Enrique		need to replace ballast in 100-hallway							
Danny Miranda									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Vado ES							
131311					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 3:31:37 PM				
Sotelo, Enrique		need to replace ballast in rooo 205							
Danny Miranda									
131313					4/13/2015		2		\$0.00
Medium	Work In Progress				4/13/2015 3:32:44 PM				
Sotelo, Enrique		need to replace ballast in rooms 308 and 310							
Danny Miranda									
129283					2/25/2015		49		\$0.00
Medium	Work In Progress				2/25/2015 10:11:06 AM				
Sotelo, Enrique		neer to repair ballast in office area, room 303, and girls restroom 300-hallway							
Danny Miranda									
131076					4/8/2015		7		\$0.00
Medium	Work In Progress				4/8/2015 7:35:27 AM				
Villalobos, David		neede to run large snake in drains at 100-hallways restrooms drains are all clogged							
Danny Miranda									
129213					2/24/2015		50		\$0.00
Medium	Work In Progress				2/24/2015 9:08:06 AM				
Villalobos, David		need to replace outside drinking fountain							
Danny Miranda									
130040					3/11/2015		35		\$0.00
Medium	Work In Progress				3/11/2015 2:56:03 PM				
Villalobos, David		need to run snake at 3 1/2 cleanout that runs under track							
Danny Miranda									
131278		Classroom			4/13/2015		2		\$0.00
Medium	Work In Progress	Room 201 Mrs.			4/13/2015 8:54:22 AM				
Miranda, Danny		Mrs. Facio need the blue light (blue screen) in her classroom							
Sylvia Cary									
130700					3/30/2015		16		\$0.00
Medium	Work In Progress				3/30/2015 8:00:16 AM				
Miranda, Danny		need to replace blower motor in staff r.r. byteachers lounge							
Danny Miranda									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
130735					3/31/2015		15		\$0.00
Medium	Work In Progress				3/31/2015 12:38:07 AM				
Miranda, Danny		Monthly - Vado ES A-16 - Fan Exhaust Semiannual - Refer to PM schedule details.							
Margret Villalobos									
130944					4/5/2015	4/11/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:36 AM				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
129280					2/25/2015		49		\$0.00
Medium	Work In Progress				2/25/2015 10:02:24 AM				
Miranda, Danny		need weed and feed for grounds							
Danny Miranda									
130820					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:29:29 AM				
Miranda, Danny		Monthly - Vado ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
130901					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:13 AM				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130902					4/5/2015	4/13/2015	10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:13 AM				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
130903					4/5/2015		10		\$0.00
Medium	Work In Progress				4/5/2015 12:30:14 AM				
Miranda, Danny		Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									

1363 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
131254					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress			4/12/2015 12:23:47 AM					
Miranda, Danny	Monthly - Vado ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
131230					4/12/2015	4/28/2015	3		\$0.00
Medium	Work In Progress			4/12/2015 12:23:34 AM					
Diaz, Armando	Monthly - QRTLY BLDG INSP REPORT (VE) - Refer to PMs schedule details.								
Margret Villalobos									
119473	Main Building	Office			7/16/2014		273		\$0.00
Medium	Work In Progress			7/16/2014 8:36:17 AM					
Munoz, Michael	NEED TO REPLACE COUNTER TOP IN TEACHERS LOUNGE AND FRONT OFFICE. ASAP								
Debra Facio									
Count: 25 Work Orders		Avg. Age of WO's 35			Total for Vado ES			0	\$0.00
Count: 1363 Work Orders		Avg. Age of WO's 64			Grand Total			0	\$0.00