

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-----------|--------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: | | Location Not Assigned | | | | | | | |
| 132032 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 2:51:49 PM | | | | |
| Orozco, Daniel | | The disposal doesn't want to turn on the water and the food from the disposal doesn't want to drain. Thank you . SNP Manager Pat C. 824.3822 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| Count: 1 Work Orders | | Avg. Age of WO's | | 19 | Total for <Blank> | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days | Labor | Total |
|--|---|-------------|--------------|-------|-----------------------|------------------|------|-------|--------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | Aged | Hours | Costs |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Alta Vista Early College HS | | | | | | | | | |
| 131543 | | Office | | | 4/17/2015 | | 31 | | \$0.00 |
| Medium | Work In Progress | | | | 4/17/2015 12:23:08 PM | | | | |
| Carrasco, Danny | I need clear burnish for a desk in the office thank you. | | | | | | | | |
| Alfredo Ambriz | | | | | | | | | |
| 123089 | | Classroom | | | 9/23/2014 | | 237 | | \$0.00 |
| Medium | Work In Progress | | | | 9/23/2014 3:28:10 PM | | | | |
| Sotelo, Enrique | Connect all new treadmills in the PE portable #504 to the internet/wi-fi | | | | | | | | |
| Minerva Menchaca | | | | | | | | | |
| 121826 | Curriculum and | Portables | | | 8/27/2014 | | 264 | | \$0.00 |
| Medium | Work In Progress | | | | 8/27/2014 8:16:27 AM | | | | |
| Sotelo, Enrique | Ned to fix the power outlet strip on the west side wall of the portable. PE portable #504 | | | | | | | | |
| Minerva Menchaca | | | | | | | | | |
| 132268 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:10 AM | | | | |
| Ambriz, Alfredo | Monthly - Alta Vista ECHS Emer Light Test: Monthly - Refer to PMschedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132269 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:10 AM | | | | |
| Ambriz, Alfredo | Monthly - Alta Vista ECHS Exit Sign Insp: Monthly - Refer to PMschedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132332 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:47 AM | | | | |
| Ambriz, Alfredo | Monthly - Alta Vista ECHS Monthly FE Inspection - Refer to PMschedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132745 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 2:52:56 PM | | | | |
| Ambriz, Alfredo | Front Building/Back Door - Paint door | | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 129721 | | Office | | | 3/3/2015 | | 76 | | \$0.00 |
| Medium | Work In Progress | main Office | | | 3/3/2015 2:29:14 PM | | | | |
| Ambriz, Alfredo | Need burnish for a desk (1 qt). | | | | | | | | |
| Alfredo Ambriz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|----------------------|------------------|---|--|--|-----------------------|--|-----|--|--------|
| Location: | | Alta Vista Early College HS | | | | | | | |
| 120833 | | | | | 8/8/2014 | | 283 | | \$0.00 |
| Medium | Work In Progress | | | | 8/8/2014 1:58:33 PM | | | | |
| Villalobos, David | | Need to repair water line between the morgan bldg. | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 132419 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 10:09:35 AM | | | | |
| Carrasco, Danny | | I'm requesting a 7 1\4" circular saw left blade for here for my site thank you. | | | | | | | |
| Alfredo Ambriz | | | | | | | | | |
| 131368 | | | | | 4/14/2015 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | | 4/14/2015 9:38:38 AM | | | | |
| Carrasco, Danny | | I'm going to need black gloss paint for the widows security bars for my site thank you. | | | | | | | |
| Alfredo Ambriz | | | | | | | | | |
| 128585 | | Exterior | | | 2/6/2015 | | 101 | | \$0.00 |
| Medium | Work In Progress | Front Section | | | 2/6/2015 10:40:45 AM | | | | |
| Ontiveros, Guadalupe | | NEED TO REMOVE PINE TREES IN FRONT OF MAIN BUILDING. | | | | | | | |
| Yvette Cortez | | | | | | | | | |
| 131106 | | | | | 4/8/2015 | | 40 | | \$0.00 |
| Medium | Work In Progress | | | | 4/8/2015 2:18:21 PM | | | | |
| Ontiveros, Guadalupe | | can you come and instal an irrigation system for some trees thank you. | | | | | | | |
| Alfredo Ambriz | | | | | | | | | |
| 131974 | | Cafeteria | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | 502 | | | 4/28/2015 12:47:45 PM | | | | |
| Estrada, Jesus | | PLEASE REMOVE CARPET IN CAFETERIA PORTABLE AND INSTALL TILE FLOORS. PLEASE CONTACT MR. RICHARD CHAVEZ FOR FURTHER DETAILS IF NEEDED. | | | | | | | |
| Yvette Cortez | | | | | | | | | |
| 131973 | | Office | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | Main Building | | | 4/28/2015 12:46:29 PM | | | | |
| Estrada, Jesus | | PLEASE REMOVE CARPET IN MAIN BUILDING (ADMINISTRATION BUILDING) AND INSTALL TILE FLOORS. PLEASE CONTACT MR. RICHARD CHAVEZ FOR FURTHER DETAILS IF NEEDED. | | | | | | | |
| Yvette Cortez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Alta Vista Early College HS

132905 Office 5/14/2015 4 \$0.00

Medium Work In Progress 5/14/2015 1:28:19 PM

Solis, Lorenzo Can you please come and change the condensation pops from the front of the office.

Alfredo Ambriz

132593 Storage A Pump House 5/8/2015 10 \$0.00

Medium Work In Progress 5/8/2015 2:15:26 PM

Apodaca, Mario routine domestic water distribution system water sampling for (HAA5-IND-DS) for the month june -01 to 30-2015

Mario Apodaca

132594 Storage A Pump House 5/8/2015 10 \$0.00

Medium Work In Progress 5/8/2015 2:20:29 PM

Apodaca, Mario routine domestic distribution system water sampling for (LEAD AND CAPPER) in the month of june 01 to july 31 2015

Mario Apodaca

132598 Storage A Pump House 5/8/2015 10 \$0.00

Medium Work In Progress 5/8/2015 2:29:17 PM

Apodaca, Mario routine domestic distribution system water sampling for (TTHM-IND-DS)for june -01 to 30-2015

Mario Apodaca

126152 12/3/2014 166 \$0.00

Medium Work In Progress 12/3/2014 8:43:42 AM

Munoz, Michael He is also asking if the remaining concrete can be used as a border for a volley ball court but I need to talk to you on this one.

Alfredo Holguin

127536 Office 1/14/2015 124 \$0.00

Medium Work In Progress Main Office 1/14/2015 2:04:52 PM

Lara, Ralph DOOR TO ASST. PRINCIPAL NEED TO BE REPLACED WITH NEW DOOR.

Yvette Cortez

127540 Office 1/14/2015 124 \$0.00

Medium Work In Progress Principal's Office 1/14/2015 2:10:29 PM

Lara, Ralph DOOR TO PRINCIPAL'S OFFICE IS UNEVEN NEEDS TO BE REPLACED WITH NEW DOOR.

Yvette Cortez

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|-----------------------|--|-----|--|--------|
| Location: | | Alta Vista Early College HS | | | | | | | |
| 131777 | | Office | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 7:41:49 AM | | | | |
| Lara, Ralph | | NEED TO REPLACED EXIT DOOR AS PER FIRE CODE, AND PRINCIPAL. | | | | | | | |
| Ralph Lara | | | | | | | | | |
| 132080 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 12:36:48 AM | | | | |
| Sanchez, Raul | | Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131333 | | | | | 4/14/2015 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | | 4/14/2015 12:23:17 AM | | | | |
| Sanchez, Raul | | Monthly - Alta Vista ECHS- Water Filters - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129462 | | | | | 2/28/2015 | | 79 | | \$0.00 |
| Medium | Work In Progress | | | | 2/28/2015 12:35:05 AM | | | | |
| Sanchez, Raul | | Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132312 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:35 AM | | | | |
| Sanchez, Raul | | Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132864 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 12:24:25 AM | | | | |
| Sanchez, Raul | | Monthly - Alta Vista ECHS- Water Filters - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 128603 | | | | | 2/6/2015 | | 101 | | \$0.00 |
| Medium | Work In Progress | | | | 2/6/2015 2:35:23 PM | | | | |
| Ronquillo, Ruben | | BELTS ON CARDIO SMART TREADMILLS NEED TO BE REPLACED. | | | | | | | |
| Yvette Cortez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Alta Vista Early College HS | | | | | | | | | |
| 130922 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:30:24 AM | | | | |
| Ronquillo, Ruben | | Monthly - Alta Vista ECHS - (Qtrly) Fitness Equip - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 126236 | | | | | 12/4/2014 | | 165 | | \$0.00 |
| Medium | Work In Progress | | | | 12/4/2014 11:24:06 AM | | | | |
| Gonzalez, Salvador | | Gate does not work property hard to open and close please repair. | | | | | | | |
| Alfredo Ambriz | | | | | | | | | |
| 127109 | | | | | 1/6/2015 | | 132 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2015 10:14:38 AM | | | | |
| Gonzalez, Salvador | | Can you please come by and weld a pick nick table its one of the the students where they eat for breakfast and lunch thank you. | | | | | | | |
| Alfredo Ambriz | | | | | | | | | |
| 132898 | | Parking Lot | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | MAIN GATE | | | 5/14/2015 10:51:16 AM | | | | |
| Gonzalez, Salvador | | MAIN GATE IS OUT OF RAIL NEEDS TO BE ADJUSTED ASAP MAY CAUSE INJURY WHEN CLOSING/OPENING GATE. | | | | | | | |
| Yvette Cortez | | | | | | | | | |
| 131171 | | Cafeteria | | | 4/9/2015 | | 39 | | \$0.00 |
| Medium | Work In Progress | Cafeteria | | | 4/9/2015 4:29:45 PM | | | | |
| Gonzalez, Salvador | | THE STAIRS TO THE BACK DOOR IN THE CAFETERIA PORTABLE ARE DETERIORATING AND DISINTEGRATING. STAIRS MAY COLLAPSE AT ANYTIME AND CAUSE INJURY TO STUDENTS AND STAFF. NEEDS TO BE REPLACED IMMEDIATELY. | | | | | | | |
| Yvette Cortez | | | | | | | | | |
| Count: 34 Work Orders Avg. Age of WO's 67 Total for Alta Vista Early College HS 0 \$0.00 | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|--|-------------|-------|-----------------------|--------------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony - On Track Pre-K (Village) | | | | | | | | | |
| 131793 | | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 1:36:41 PM | | | | |
| Gonzalez, Salvador | | Repair a tear in fence directly behind Pre K office portable. | | | | | | | |
| David Escobar | | | | | | | | | |
| 128783 | | | | | 2/11/2015 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | | 2/11/2015 11:09:42 AM | | | | |
| Ronquillo, Ruben | | 02/11/2015. slide at pre k playground has a tear at the bottom end and is potential cut hazard. | | | | | | | |
| David Escobar | | | | | | | | | |
| 132725 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 10:27:46 AM | | | | |
| Villalobos, Margret | | Please sent pest control to room 110 due to a spider problem in class room . teacher has already caught 3 large specimens of spiders since Monday 5/11/2015. | | | | Emailed waiver - 5/12/15 | | | |
| David Escobar | | | | | | | | | |
| 132955 | | | | | 5/15/2015 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | | 5/15/2015 8:41:06 AM | | | | |
| Villalobos, David | | REMOVE LEFT OVER 4INX 20FT SEWER PIPE FROM CUSTODIAL BARRACK ASAP TRIP HAZZARD | | | | | | | |
| David Vega | | | | | | | | | |
| 130246 | | | | | 3/17/2015 | | 62 | | \$0.00 |
| Medium | Work In Progress | Room # 105 | | | 3/17/2015 9:28:39 AM | | | | |
| Escobar, David | | repair the insulation on the pipes near the ceiling | | | | | | | |
| Noemi Duron | | | | | | | | | |
| 128989 | | | | | 2/17/2015 | | 90 | | \$0.00 |
| Medium | Work In Progress | 882-1904 | | | 2/17/2015 3:58:18 PM | | | | |
| Escobar, David | | finish painting the pre-k we already have the paint that a parent donated since the beginning of the year if any question please ask Laura or Estrella | | | | | | | |
| Laura Vazquez | | | | | | | | | |
| 131481 | | Cafeteria | | | 4/16/2015 | | 32 | | \$0.00 |
| Medium | Work In Progress | 882-1904 | | | 4/16/2015 10:26:17 AM | | | | |
| Escobar, David | | hang out 10 poster frames in the cafeterias 5 in each one please ask Estrella where she wants them to be install | | | | | | | |
| Laura Vazquez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|---|----------------------------|-------|---|----------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony - On Track Pre-K (Village) | | | | | | | | | |
| 132838 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | ROOM #105 | | | 5/13/2015 3:34:40 PM | | | | |
| Escobar, David | | assemble shelves and cabinet | | | | | | | |
| Noemi Duron | | | | | | | | | |
| 132812 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | ROOM -105 | | | 5/13/2015 10:42:25 AM | | | | |
| Escobar, David | | PUT TOGETHER A CONFERENCE TABLE. | | | | | | | |
| Noemi Duron | | | | | | | | | |
| 130409 | | | | | 3/19/2015 | | 60 | | \$0.00 |
| Medium | Work In Progress | ROOM #105 | | | 3/19/2015 4:55:08 PM | | | | |
| Holguin, Alfredo | | REQUESTING TO EXTEND COUNTER BY SINK. | | | | Routed to A. Holguin | | | |
| Noemi Duron | | | | | | | | | |
| 131296 | | | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | ROOM # 105 | | | 4/13/2015 1:02:54 PM | | | | |
| Sotelo, Enrique | | Requesting power lines/sources for the 6 work stations and copier that will be at the PAT Center | | | | | | | |
| Noemi Duron | | | | | | | | | |
| 128397 | | | | | 2/3/2015 | | 104 | | \$0.00 |
| Medium | Work In Progress | | | | 2/3/2015 10:11:02 AM | | | | |
| Carrasco, Danny | | 02/03/2015. BM needs 5 tubes of 3M acrylic to repair a tear on spiral slide at Pre K village . | | | | | | | |
| David Escobar | | | | | | | | | |
| Count: 12 Work Orders | | | Avg. Age of WO's 44 | | Total for Anthony - On Track Pre-K (Village) | | 0 | | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony ES | | | | | | | | | |
| 132169 | | | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 3:33:50 PM | | | | |
| Carrasco, Danny | | 05/01/2015. | | | | | | | |
| | | requesting 1 gallon of 181 ductsealer | | | | | | | |
| David Escobar | | | | | | | | | |
| 128740 | | | | | 2/10/2015 | | 97 | | \$0.00 |
| Medium | Work In Progress | | | | 2/10/2015 2:51:21 PM | | | | |
| Orozco, Daniel | | AS PER ADELE INSPECTION REPORT- CAN | | | | | | | |
| | | OPENER DOES NOT WORK CORRECTLY . HARD TO | | | | | | | |
| | | OPEN. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 123057 | | | | | 9/23/2014 | | 237 | | \$0.00 |
| Medium | Work In Progress | | | | 9/23/2014 9:58:08 AM | | | | |
| Orozco, Daniel | | PRONG TO SLICER STAYED STUCK IN OUTLET. | | | | | | | |
| | | SNP MANAGER BECKY S. 882.3507 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 121438 | | | | | 8/19/2014 | | 272 | | \$0.00 |
| Medium | Work In Progress | | | | 8/19/2014 2:55:31 PM | | | | |
| Orozco, Daniel | | EXHAUST FAN SWITCH IS NOT WORKING AGAIN. | | | | | | | |
| | | SNP MANAGER BECKY S. 882.3507 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 121439 | | | | | 8/19/2014 | | 272 | | \$0.00 |
| Medium | Work In Progress | | | | 8/19/2014 2:56:27 PM | | | | |
| Orozco, Daniel | | NEED METAL COVERS FOR FAN INSIDE WALK IN | | | | | | | |
| | | REFRIGERATOR, SAFETY HAZARD. SNP MANAGER | | | | | | | |
| | | BECKY S. 882.3507 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 121986 | | | | | 8/29/2014 | | 262 | | \$0.00 |
| Medium | Work In Progress | | | | 8/29/2014 3:14:16 PM | | | | |
| Orozco, Daniel | | SERVING LINE CLOGGED. SNP MANAGER BECKY | | | | | | | |
| | | S. 882.3507 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132188 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:22 AM | | | | |
| Orozco, Daniel | | Monthly - Anthony ES Range Hood Cleaning - Refer to | | | | | | | |
| | | PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|---|-------------|-------------|----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony ES | | | | | | | | | |
| 132209 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:34 AM | | | | | |
| Orozco, Daniel | Monthly - Anthony ES Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131678 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | 4/21/2015 2:25:02 PM | | | | | |
| Medina, Eric | Please control weeds @ AE. | | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 130456 | | | | | 3/23/2015 | | 56 | | \$0.00 |
| Medium | Work In Progress | | | 3/23/2015 9:57:06 AM | | | | | |
| Sotelo, Enrique | Power Outage at the Alamo Building | | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 129782 | | | | | 3/4/2015 | | 75 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | 3/4/2015 3:25:14 PM | | | | | |
| Sotelo, Enrique | REPLACE LIGHT BULB IN VAULT IN CHILDFIND OFFICE (SEE MARGARET) | | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132520 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | 5/7/2015 11:37:45 AM | | | | | |
| Marquez, Gerardo | please adjust door closer to north "diamond" entrance . door slams shut and is a potential danger to students and staff . | | | | | | | | |
| David Escobar | | | | | | | | | |
| 132741 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 5/12/2015 1:39:39 PM | | | | | |
| Marquez, Gerardo | Re-key Room where we store testing materials back to original cylinder Please see Ms. Barajas for any questions | | | | | | | | |
| Jessica Lopez | | | | | | | | | |
| 130813 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | 4/5/2015 12:29:25 AM | | | | | |
| Holguin, Alfredo | Monthly - Anthony ES - Fire Pump Engine - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony ES | | | | | | | | | |
| 132874 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/14/2015 7:41:52 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507436 ESTR PUBLICATIONS 1 BOX CAROL ZIMMERMAN, REHAB COUNSELOR | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132875 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/14/2015 7:43:08 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507424 CRISIS PREVENTION INSTITUTE 1 BOX JODIE PORTER, INSTRUCTIONAL SPECIALIST | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132876 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/14/2015 7:44:23 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507433 HANDWRITING WITHOUT TEARS 5 BOXES ALEX RUIZ, INSTRUCTIONAL SPECIALIST | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132877 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/14/2015 7:45:48 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507443 PEARSON ASSESSMENTS 1 BOX KATHY BRENNAN, PSYCHOLOGIST | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132878 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/14/2015 7:46:57 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507444 ULINE 1 BOX CLAUDIA PEREZ, INSTRUCTIONAL SPECIALIST | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132880 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/14/2015 7:51:41 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507432 TOPBULB 2 BOXES MARGARET S. VILLALOBOS | | | | | | | |
| Margaret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Anthony ES

132886 5/14/2015 4 \$0.00

Medium Work In Progress SPED OFFICE 5/14/2015 8:00:57 AM

Gonzales, Camilo DELIVER PO 141507594 PEARSON ASSESSMENTS
1 BOX
LAURA MCNIECE, COTA

Margaret Villalobos

132887 5/14/2015 4 \$0.00

Medium Work In Progress SPED OFFICE 5/14/2015 8:02:21 AM

Gonzales, Camilo DELIVER PO 141507586 LAKESHORE LEARNING
3 BOXES
LAURA MCNIECE, COTA

Margaret Villalobos

132888 5/14/2015 4 \$0.00

Medium Work In Progress SPED OFFICE 5/14/2015 8:05:28 AM

Gonzales, Camilo DELIVER PO 141507583 DISCOUNT SCHOOL
SUPPLY
1 PKG
LAURA MCNIECE, COTA

Margaret Villalobos

132889 5/14/2015 4 \$0.00

Medium Work In Progress SPED OFFICE 5/14/2015 8:14:26 AM

Gonzales, Camilo DELIVER PO 141507584 HANDWRITING WITHOUT
TEARS
5 BOXES
LAURA MCNIECE, COTA

Margaret Villalobos

132890 5/14/2015 4 \$0.00

Medium Work In Progress SPED OFFICE 5/14/2015 8:15:54 AM

Gonzales, Camilo DELIVER PO 141507590 THERAPRO
1 BOX
LAURA MCNIECE, COTA

Margaret Villalobos

132891 5/14/2015 4 \$0.00

Medium Work In Progress SPED OFFICE 5/14/2015 8:17:31 AM

Gonzales, Camilo DELIVER PO 141507589 PATTERSON MEDICAL
SUPPLY
3 BOXES
LAURA MCNIECE, COTA

Margaret Villalobos

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony ES | | | | | | | | | |
| 132892 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/14/2015 8:19:00 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507591 THERAPY SHOPPE 1 BOX LAURA MCNIECE, COTA | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132866 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/14/2015 7:33:17 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141506806 FLAGHOUSE INC. 1 BOX CLAUDIA PEREZ, INSTRUCTIONAL SPECIALIST | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132867 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/14/2015 7:34:37 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141506809 AUTISM ASPERGER PUBLISHING 1 BOX CLAUDIA PEREZ, INSTRUCTIONAL SPECIALIST | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132869 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | CAVALRY | | | 5/14/2015 7:36:15 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141506890 LAKESHORE LEARNING 8 BOXES ELIZABETH GONZALEZ, PRINCIPAL, CAVALRY WEST | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132506 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/7/2015 7:48:07 AM | | | | |
| Gonzales, Camilo | | PICK UP THE PRINTER CARTRIDGES FOR CORA RAMIREZ @ TECHNOLOGY (SEE MARGARET OR MARY) | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132627 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 5/10/2015 12:23:40 AM | | | | |
| Escobar, David | | Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|--------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|---|-------------------|--|--|-----------------------|-----------|----|--|--------|
| Location: | | Anthony ES | | | | | | | |
| 132330 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:46 AM | | | | |
| Escobar, David | Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132423 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | 310 | | | 5/5/2015 10:48:33 AM | | | | |
| Escobar, David | Room is too hot please check asap Room # 310 Mrs. Nunez | | | | | | | | |
| Jessica Lopez | | | | | | | | | |
| 131267 | | | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 4/13/2015 12:26:49 AM | | | | |
| Escobar, David | Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131495 | | | | | 4/16/2015 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 4/16/2015 2:10:59 PM | | | | |
| Escobar, David | Mr. Escobar, As per Ms. Perez please power wash trash cans and blue steel benches | | | | | | | | |
| Jessica Lopez | | | | | | | | | |
| 132251 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:00 AM | | | | |
| Escobar, David | Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132252 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:00 AM | | | | |
| Escobar, David | Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131946 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 4/28/2015 12:25:28 AM | | | | |
| Escobar, David | Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|---------------------|------------------|---|--|--|----------------------|-----------|-----|--|--------|
| Location: | | Anthony ES | | | | | | | |
| 131956 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | 245 | | | 4/28/2015 9:13:04 AM | | | | |
| Escobar, David | | Please check toilet in room # 245 asap, not flushing. | | | | | | | |
| Jessica Lopez | | | | | | | | | |
| 132882 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/14/2015 7:54:35 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507593 SCHOOL OUTFITTERS 4 BOXES DEANNA WILKINSON, INSTRUCTIONAL SPECIALIST | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132883 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/14/2015 7:56:16 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507581 WESTERN PSYCHOLOGICAL 1 PK KATHY BRENNAN, PSYCHOLOGIST | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132884 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 5/14/2015 7:58:08 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507585 LAKESHORE LEARNING 1 BOX CLAUDIA PEREZ, INSTRUCTIONAL SPECIALIST | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 126873 | | | | | 1/4/2015 | 1/12/2015 | 134 | | \$0.00 |
| Medium | Work In Progress | | | | 1/4/2015 12:40:12 AM | | | | |
| Escobar, David | | Monthly - Anthony ES Roof Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130788 | | | | | 4/5/2015 | 5/6/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:12 AM | | | | |
| Escobar, David | | Yearly - Anthony ES A13 (AC Wall Mount)(Yearly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130803 | | | | | 4/5/2015 | 5/6/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:20 AM | | | | |
| Escobar, David | | Monthly - Anthony ES A16 (Fan Exhst.)(Semi. Ann.) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony ES | | | | | | | | | |
| 129974 | | | | | 3/9/2015 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | | 3/9/2015 4:09:59 PM | | | | |
| Escobar, David | | need to replace 1/2 inch water supplyline and 1/4 inch lines to coolers in Alamo building and off cafeteria. | | | | | | | |
| David Escobar | | | | | | | | | |
| 132082 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 8:35:13 AM | | | | |
| Villalobos, David | | remove left over 4' pipe from custodial storage | | | | | | | |
| David Vega | | | | | | | | | |
| 132588 | | | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 11:29:32 AM | | | | |
| Villalobos, David | | BUSTED WATER LINE ON DISHWASHER. SNP MANAGER BECKY S. 882.3507 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 130851 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:45 AM | | | | |
| Villalobos, Margret | | Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129343 | | | | | 2/26/2015 | | 81 | | \$0.00 |
| Medium | Work In Progress | | | | 2/26/2015 10:55:35 AM | | | | |
| Flores, Pete | | need weed eater fixed trigger is broken serial#285195352 | | | | | | | |
| David Vega | | | | | | | | | |
| 130838 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:39 AM | | | | |
| Munoz, Michael | | Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132073 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 12:36:44 AM | | | | |
| Apodaca, Mario | | Monthly - Anthony ES - Monthly Meter Readings - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-------|-----------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony ES | | | | | | | | | |
| 129443 | | | | | 2/28/2015 | | 79 | | \$0.00 |
| Medium | Work In Progress | | | | 2/28/2015 12:34:52 AM | | | | |
| Munoz, Michael | | Yearly - Anthony ES - Fire Pump Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132472 | | | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 11:57:51 AM | | | | |
| Ontiveros, Guadalupe | | 05/06/2015. short in irrigation system at main building soccer field. valves wont shut and allow sprinkler to shut off. | | | | | | | |
| David Escobar | | | | | | | | | |
| 128486 | | | | | 2/4/2015 | | 103 | | \$0.00 |
| Medium | Work In Progress | | | | 2/4/2015 3:46:09 PM | | | | |
| Marquez, Gerardo | | BMneeds 10 bathroom stall latches . need to replace missing and broken ones. | | | | | | | |
| David Escobar | | | | | | | | | |
| 131539 | | | | | 4/17/2015 | | 31 | | \$0.00 |
| Medium | Work In Progress | | | | 4/17/2015 10:59:39 AM | | | | |
| Gonzalez, Salvador | | 04/17/2015. need to repair hole in fence behind Pre K portable. | | | | | | | |
| David Escobar | | | | | | | | | |
| 120712 | | | | | 8/7/2014 | | 284 | | \$0.00 |
| Medium | Work In Progress | | | | 8/7/2014 12:12:51 PM | | | | |
| Gonzalez, Salvador | | Sal we need to build a ladder rack for the gater as per Mike thanks | | | | | | | |
| Daniel Sotelo | | | | | | | | | |
| Count: 58 Work Orders | | Avg. Age of WO's 46 | | | Total for Anthony ES | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Berino ES | | | | | | | | | |
| 128758 | | | | | 2/10/2015 | | 97 | | \$0.00 |
| Medium | Work In Progress | | | | 2/10/2015 3:45:29 PM | | | | |
| Gonzalez, Salvador | | MR SAL GONZLES SIR HAVE TWO MORE BENCHES THAT NEED TO BE REPAIR AND WELDED AND REINSTALLED THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 130134 | | | | | 3/13/2015 | | 66 | | \$0.00 |
| Medium | Work In Progress | | | | 3/13/2015 12:56:51 PM | | | | |
| Sanchez, Raul | | MR RUAL SANCHEZ SIR NEED TO REPLACE WATER FILTERS FOR MAIN BUILDING WATER TURNING BROWN THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 129623 | | | | | 3/2/2015 | | 77 | | \$0.00 |
| Medium | Work In Progress | | | | 3/2/2015 10:01:45 AM | | | | |
| Ontiveros, Guadalupe | | MR LUPE ONTIVEROS SIR CAN YOU PLEASE CHECK SPRINKLER SYSTEM ALARM CAME ON STATION 15-16-17 NOT COMING ON NEED TO START WATERING THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 130129 | | | | | 3/13/2015 | | 66 | | \$0.00 |
| Medium | Work In Progress | | | | 3/13/2015 11:01:03 AM | | | | |
| Ontiveros, Guadalupe | | MR ALFREDO HOLGUIN SIR THE GATES HAVE BEEN INSTALL BETWEEN BERINO AND DESERT PRIDE NOW WE NEED TO INSTALL SIDEWALK THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 131482 | | Custodial | | | 4/16/2015 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 4/16/2015 10:27:54 AM | | | | |
| Carbajal, Jimmy | | I need a chair dolly that can fit all chair sizes for the summer. I do not have one | | | | | | | |
| Marin Herrera | | | | | | | | | |
| 132418 | | Custodial | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 9:50:31 AM | | | | |
| Carbajal, Jimmy | | Need (3) front caps for vacuums. | | | | | | | |
| Marin Herrera | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Berino ES | | | | | | | | | |
| 129444 | | | | | 2/28/2015 | | 79 | | \$0.00 |
| Medium | Work In Progress | | | | 2/28/2015 12:34:53 AM | | | | |
| Munoz, Michael | | Yearly - Berino ES - Fire Pump Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132074 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 12:36:45 AM | | | | |
| Apodaca, Mario | | Monthly - Berino ES - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130832 | | | | | 4/5/2015 | 4/26/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:36 AM | | | | |
| Munoz, Michael | | Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 118857 | | | | | 7/1/2014 | | 321 | | \$0.00 |
| High | Work In Progress | | | | 7/1/2014 9:56:44 AM | | | | |
| Munoz, Michael | | need to install new water gong fire bell. district electrician will provide power. | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 128332 | | | | | 2/2/2015 | | 105 | | \$0.00 |
| Medium | Work In Progress | | | | 2/2/2015 9:30:43 AM | | | | |
| Solis, Lorenzo | | MR LORENZO SOLIS SIR DESERT PRIDE PORTABLE NOT WORKING PROPERLY NEED TO CHECK THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 130970 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:30:50 AM | | | | |
| Villalobos, Margret | | Monthly - Berino ES - Enviro Controls Quarterly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132568 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 4:00:25 PM | | | | |
| Villalobos, David | | PILOT ON TILT SKILLET WENT OFF.SNP MANAGER ELSA C. 882.2417 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Berino ES | | | | | | | | | |
| 132431 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 2:43:57 PM | | | | |
| Villalobos, David | | DAVID VILLALOBOS SIR HAVE A SINK PLUG ROOM 104 REMOVE P-TRAP PUT IN CABLE BUT IT WAS TO SHORT WILL NEED LONGER ONE TO REACH PLUG THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 132362 | | Parking Lot | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 11:00:38 AM | | | | |
| Villalobos, David | | need to line locate for water line comeing from berino elementaryto alta vista. sidewalk to be install. | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 132815 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| High | Work In Progress | | | | 5/13/2015 11:44:31 AM | | | | |
| Villalobos, David | | Please check on gas odor at site. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 130490 | | Athletic Field | | | 3/23/2015 | | 56 | | \$0.00 |
| High | Work In Progress | | | | 3/23/2015 4:08:25 PM | | | | |
| Villalobos, David | | line locate between berino and alta vista. sidewalk to be install. Mr. adan coild show area. | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 132964 | | | | | 5/15/2015 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | | 5/15/2015 12:43:17 PM | | | | |
| Carrasco, Danny | | MR DANNY CARASCO SIR NEED FUEL FOR FIRE PUMP 15 GAL OF DIESEL ALSO NEED ABOUT 5 GAL OF GASOLINE FOR BERINO THANK SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 131802 | | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 2:46:50 PM | | | | |
| Villalobos, David | | MR DAVID VILLALOBOS SIR THE MIX VALUE IN RESTROOM IS NOT WORKING WATER TO HOT BOTH SIDES MAY NEED TO REPLACE THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|--|-------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Berino ES | | | | | | | | | |
| 132870 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | ANALIS | | 5/14/2015 7:37:41 AM | | | | | |
| Gonzales, Camilo | DELIVER PO 141507155 EL PASO OFFICE PRODUCTS 14 BOXES ANALIS AVALOS, TEACHER/BERINO ELEMENTARY | | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132879 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | SANDI | | 5/14/2015 7:50:00 AM | | | | | |
| Gonzales, Camilo | DELIVER PO 141507441 BEST BUY GOV LLC 3 BOXES SANDI HINOJOS, TEACHER/BE | | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 130814 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | 4/5/2015 12:29:26 AM | | | | | |
| Holguin, Alfredo | Monthly - Berino ES - Fire Pump Engine - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132625 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 5/10/2015 12:23:39 AM | | | | | |
| Duran, Adan | Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132331 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:46 AM | | | | | |
| Duran, Adan | Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132270 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:11 AM | | | | | |
| Duran, Adan | Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132271 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:11 AM | | | | | |
| Duran, Adan | Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Berino ES | | | | | | | | | |
| 132264 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:07 AM | | | | |
| Duran, Adan | | Monthly - Berino ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132581 | | | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 9:46:01 AM | | | | |
| Marquez, Gerardo | | MR GERRY MARQUEZ SIR THE TUMBLER WOMEN RESTROOM EAST HALL WAY KEEPS COMING OUT MAY NEED TO REPLACE THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 132663 | | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 10:12:27 AM | | | | |
| Marquez, Gerardo | | MR GERRY MARQUEZ SIR THE HINGE IN ROOM 121 NEED ADJUSTING THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 120112 | | | | | 7/31/2014 | | 291 | | \$0.00 |
| Medium | Work In Progress | | | | 7/31/2014 2:44:15 PM | | | | |
| Sotelo, Enrique | | MR ENRIQUE SOTELO SIR BREAKER ON AC UNIT ROOMS 105 AND 107 NEEDS TO BE REPLACE IT HAS A 20 AMP AND THE UNIT CALLS FOR A 25 AMP THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 129158 | | | | | 2/23/2015 | | 84 | | \$0.00 |
| Medium | Work In Progress | | | | 2/23/2015 11:24:40 AM | | | | |
| Sotelo, Enrique | | MR ENRIQUE SOTELO SIR HAVE BURN OUT EMERGENCY LIGHT MIDDLE WING NORTH SIDE MEN REST ROOM NEED TO REPLACE TO REPLACE THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 132582 | | | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 9:48:07 AM | | | | |
| Sotelo, Enrique | | MR ENRIQUE SOTELO SIR NEED TO REPLACE EMERGENCY LIGHT MIDDLE WING BROKEN THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|--|----------------|-------------------------|-----------------------|------------------|------------------|----------------------------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Berino ES | | | | | | | | | |
| 131958 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | 4/28/2015 10:38:01 AM | | | | | |
| Sotelo, Enrique | MR ENRIQUE SOTELO SIR LIGHTS IN HALL WAY WENT OFF NEED TO CHECK I CHECKED BREAKERS AND CHANGE LIGHT BULBS ? THANK YOU SIR AND GOD BLESS | | | | | | | | |
| Adan Duran | | | | | | | | | |
| 132361 | | Parking Lot | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | 5/4/2015 10:56:38 AM | | | | | |
| Sotelo, Enrique | need to line locate for power running from Bernio elementary to DP. sidewalk is to be install. any questions make contact with Mr. Adan. | | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 130491 | | Athletic Field | | | 3/23/2015 | | 56 | | \$0.00 |
| High | Work In Progress | | | 3/23/2015 4:11:35 PM | | | | | |
| Sotelo, Enrique | line locate for any power lines between berino and alta vista. Mr. Adan will show area. | | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 132210 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:35 AM | | | | | |
| Orozco, Daniel | Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132189 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:23 AM | | | | | |
| Orozco, Daniel | Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 126424 | | | | | 12/9/2014 | | 160 | | \$0.00 |
| Medium | Work In Progress | | | 12/9/2014 3:42:21 PM | | | | | |
| Orozco, Daniel | WARMER IS NOT HEATING. SNP MANAGER ELSA C. 882.2417 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| Count: 38 Work Orders | | | Avg. Age of WO's | 50 | | | Total for Berino ES | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral ES | | | | | | | | | |
| 124735 | | | | | 10/29/2014 | | 201 | | \$0.00 |
| Medium | Work In Progress | | | | 10/29/2014 12:28:02 | | | | |
| Orozco, Daniel | | BROKEN GASKETS ON FREEZER AND WARMER. SNP MANAGER ESTHER C. 824.0048 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 123783 | | | | | 10/7/2014 | | 223 | | \$0.00 |
| Medium | Work In Progress | | | | 10/7/2014 8:55:51 AM | | | | |
| Orozco, Daniel | | DISHWASHER IS LEAKING. SNP MANAGER ESTHER C. 824.0048 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132190 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:23 AM | | | | |
| Orozco, Daniel | | Monthly- Chapparral ES Range Hood Cleaning - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129064 | | | | | 2/19/2015 | | 88 | | \$0.00 |
| Medium | Work In Progress | | | | 2/19/2015 8:45:50 AM | | | | |
| Orozco, Daniel | | AS PER ADELE INSPECTION REPORT. SEAL ON WARMER TORN AND LOOSE. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132211 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:36 AM | | | | |
| Orozco, Daniel | | Monthly- Chaparral ES Fire Suppression Insp. - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132731 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 11:05:54 AM | | | | |
| Marquez, Gerardo | | teacher having a hard time opening door with key rm .506. thanks | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 132761 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 3:41:53 PM | | | | |
| Marquez, Gerardo | | entrance door rm.205 door falling from hinges @ chm | | | | | | | |
| Paul Quinones | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral ES | | | | | | | | | |
| 132805 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 8:52:14 AM | | | | |
| Appelzoller, Fred | | broken water faucets in class rm.205 shut off water supply @ chm | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 132881 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | DOROTHY | | | 5/14/2015 7:52:58 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507426 FLAGHOUSE 1 BOX DOROTHY SANG, TEACHER/CHAPARRAL ELEMENTARY | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132718 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 9:40:27 AM | | | | |
| Carrasco, Danny | | fuel for polaris sports gasoline | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 132885 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | DOROTHY | | | 5/14/2015 7:59:33 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507588 ORIENTAL TRADING CO. 1 BOX DOROTHY SANG, TEACHER/CHE | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 131233 | | | | | 4/12/2015 | 4/28/2015 | 36 | | \$0.00 |
| Medium | Work In Progress | | | | 4/12/2015 12:23:36 AM | | | | |
| Ramirez, Daniel | | Monthly - QRTLY BLDG INSP REPORT (CE) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 128701 | | | | | 2/9/2015 | | 98 | | \$0.00 |
| Medium | Work In Progress | | | | 2/9/2015 4:07:26 PM | | | | |
| Flores, Pete | | please check the brakes to work truck #123 | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 132345 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:54 AM | | | | |
| Quinones, Paul | | Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral ES | | | | | | | | | |
| 132307 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:32 AM | | | | |
| Quinones, Paul | | Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132308 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:33 AM | | | | |
| Quinones, Paul | | Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132334 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:48 AM | | | | |
| Quinones, Paul | | Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132639 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 5/10/2015 12:23:46 AM | | | | |
| Quinones, Paul | | Monthly - Chaparral ES Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131901 | | | | | 4/27/2015 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 4/27/2015 9:06:55 AM | | | | |
| Quinones, Paul | | paint rest rooms in the 200 wing total of 19 rest rms. | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 132054 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 3:46:43 PM | | | | |
| Quinones, Paul | | need to paint gym walls at chm, send request for paint | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 132056 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 3:49:37 PM | | | | |
| Quinones, Paul | | need to paint wing between 1, and 3, order paint at chm | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 130846 | | | | | 4/5/2015 | 4/13/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:43 AM | | | | |
| Quinones, Paul | | Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|------------------|------------------|--|--|--|-----------------------|--|-----|--|--------|
| Location: | | Chaparral ES | | | | | | | |
| 130264 | | | | | 3/17/2015 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | | 3/17/2015 2:18:13 PM | | | | |
| Quinones, Paul | | need to replace metal partitions in boys rst rm. wing 100 | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 128900 | | | | | 2/13/2015 | | 94 | | \$0.00 |
| Medium | Work In Progress | | | | 2/13/2015 11:49:44 AM | | | | |
| Quinones, Paul | | reorder mastercool media celdeck pads to replace the ones that need to be replaced on the existing coolers | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 131438 | | | | | 4/15/2015 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | | 4/15/2015 1:27:13 PM | | | | |
| Solis, Lorenz | | coolers need to be replaced 3]6500 side draft,and 1] 4500 down draft master cools. | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 131680 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 2:39:08 PM | | | | |
| Solis, Lorenz | | 4-21-15 evap.cooler needs to be replaced rm.107 mcd 006 4800 | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 131681 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 2:40:53 PM | | | | |
| Solis, Lorenz | | evap needs to be replaced mcs che 011 rm.208 6800 | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 131682 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 2:42:50 PM | | | | |
| Solis, Lorenz | | evap cooler needs to be replaced mcs che 014 rm,212 6800 | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 131684 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 2:44:32 PM | | | | |
| Solis, Lorenz | | evap.cooler needs to be replaced mcs 013 rm.209 6800 | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 127588 | | | | | 1/15/2015 | | 123 | | \$0.00 |
| Medium | Work In Progress | | | | 1/15/2015 12:32:10 PM | | | | |
| Marquez, Gerardo | | cafeteria double doors on the west side of cafeteria core fell off and lost.need a new core | | | | | | | |
| Paul Quinones | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|-----------------------|--------------|------------------|----|--|--|------------------------|---|--------|--|
| Location: | Chaparral ES | | | | | | | | |
| Count: 30 Work Orders | | Avg. Age of WO's | 43 | | | Total for Chaparral ES | 0 | \$0.00 | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|--|-------------|-------------------------|-----------|---|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral High - Pre-K | | | | | | | | | |
| 130045 | | | | | 3/11/2015 | | 68 | | \$0.00 |
| Medium | Work In Progress | | | | 3/11/2015 3:30:22 PM | | | | |
| Marquez, Gerardo | Gerry - Please get a quote: The NM Mexico Pre-K Department has responded to the situation at Chaparral Pre-K with a suggestion to split the bathroom doors into a "Dutch Door" as we have in the Anthony Pre-K. | | | | | | | | |
| | Jeanne Fields | | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 131672 | | Exterior | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 12:54:24 PM | | | | |
| Marquez, Gerardo | Need to remove all door cylinders and clean then, do to wing full of sand. | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| Count: 2 Work Orders | | | Avg. Age of WO's | 48 | Total for Chaparral High - Pre-K | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--|------------------|------------------|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 132948 | E-Wing | Classroom | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | E1 | | | 5/14/2015 4:39:13 PM | | | | |
| Marquez, Gerardo Please install locks for the 2 wall cabinets. (Ms. Joseph, E1) | | | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 123340 | | | | | 9/29/2014 | | 231 | | \$0.00 |
| Medium | Work In Progress | | | | 9/29/2014 8:09:29 AM | | | | |
| Marquez, Gerardo We will need to add door openers to 4 doors: | | | | | | | | | |
| 1. The east exit door by the wall on Wing E. | | | | | | | | | |
| 2. The west exit door by the wall on Wing F. | | | | | | | | | |
| 3. The east exit doors (2 doors – one into the foyer and one into the building) by the wall on Wing R. | | | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 125513 | A-Wing | | | | 11/13/2014 | | 186 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2014 12:07:33 | | | | |
| Marquez, Gerardo At nurses office key broken in cabinet. | | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 131905 | | | | | 4/27/2015 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 4/27/2015 10:50:11 AM | | | | |
| Marquez, Gerardo keys were lost. please get an estimate on cost to rekey doors. | | | | | | | | | |
| Gerardo Marquez | | | | | | | | | |
| 130990 | | Gym | | | 4/6/2015 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | | 4/6/2015 11:31:40 AM | | | | |
| Estrada, Jesus varnish gym floor | | | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 126517 | B-Wing | Hallway/Corridor | | | 12/11/2014 | | 158 | | \$0.00 |
| Medium | Work In Progress | | | | 12/11/2014 10:11:40 | | | | |
| Solis, Lorenzo In cybor cafe Bad odor coming from heating vents. | | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 132433 | Q-Wing | Classroom | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 2:48:31 PM | | | | |
| Solis, Lorenzo Unit tripping breaker, posible bad compressor. | | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--|------------------|----------------|--|--|-----------------------|--|----|--|--------|
| Location: Chaparral HS | | | | | | | | | |
| 130595 | Q-Wing | Classroom | | | 3/25/2015 | | 54 | | \$0.00 |
| Medium | Work In Progress | | | | 3/25/2015 3:48:42 PM | | | | |
| Solis, Lorenzo Need to replace two burn-out compressors in Q-7. | | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 132035 | H-Wing | Dressing Room | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | Boys PE office | | | 4/29/2015 3:06:36 PM | | | | |
| Solis, Lorenzo Please install refrigerated air due to humidity and the false operation of computer and printer. (Coach Yturralde) | | | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 132921 | F-Wing | Mechanical | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 2:48:53 PM | | | | |
| Solis, Lorenzo Having problem with A/C unit in server room to hot. Possible low on refrigerant. | | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 132317 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:38 AM | | | | |
| Apodaca, Mario Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130939 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:30:33 AM | | | | |
| Apodaca, Mario Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130839 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:39 AM | | | | |
| Munoz, Michael Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129445 | | | | | 2/28/2015 | | 79 | | \$0.00 |
| Medium | Work In Progress | | | | 2/28/2015 12:34:53 AM | | | | |
| Munoz, Michael Yearly - Chaparral HS - Fire Pump Inspection - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--|------------------|----------------|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 125053 | | Athletic Field | | | 11/3/2014 | | 196 | | \$0.00 |
| Medium | Work In Progress | | | | 11/3/2014 7:35:53 AM | | | | |
| Valdez, Pedro Need to fix baseball bleachers bent and broken. | | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 132363 | | Athletic Field | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 11:02:36 AM | | | | |
| Flores, Pete JD 735 mower needs new tire. | | | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 132093 | Field House | Office | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | Trainer | | | 4/30/2015 1:02:20 PM | | | | |
| Flores, Pete Cart brakes are not working properly. They do not stop the cart. (Stacy Walsh) | | | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 132100 | Field House | Classroom | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | Trainer | | | 4/30/2015 2:56:41 PM | | | | |
| Flores, Pete Battery indicator giving full charge signal even when the cart dies & has no more power. (Stacy Walsh) | | | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 132101 | Field House | Classroom | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | fieldhouse | | | 4/30/2015 2:59:02 PM | | | | |
| Flores, Pete Any yearly maintenance that needs to be completed. I will need the cart until May 10 but then I can find other methods of moving things around campus. (Stacy Walsh) | | | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 130842 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:41 AM | | | | |
| Munoz, Michael Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132380 | | | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 3:15:10 PM | | | | |
| Carrasco, Danny Attention to Warehouse Danny or Ruben Need to order Grinder, screws, and replace broken clamp meter. | | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 132920 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 2:44:00 PM | | | | |
| Vallejo, Albert | | Order crossover track protector. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 130811 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:24 AM | | | | |
| Holguin, Alfredo | | Monthly - Chaparral HS - Fire Pump Engine - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132344 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:54 AM | | | | |
| Ortiz, Alfredo | | Monthly - Chaparral HS Monthly FE Inspection - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132346 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:55 AM | | | | |
| Ortiz, Alfredo | | Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132278 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:15 AM | | | | |
| Ortiz, Alfredo | | Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132279 | | | | | 5/3/2015 | 6/3/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:16 AM | | | | |
| Ortiz, Alfredo | | Monthly - Chaparral HS Bleacher Inspection - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132276 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:14 AM | | | | |
| Ortiz, Alfredo | | Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131208 | F-Wing | Hallway/Corridor | | | 4/10/2015 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 4/10/2015 3:04:54 PM | | | | |
| Ortiz, Alfredo | | Need to build a stand made out of PVC for a classroom. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral HS

| | | | | | | | | | |
|--------|--------|-----------|--|--|-----------|--|----|--|--------|
| 131865 | Q-Wing | Classroom | | | 4/24/2015 | | 24 | | \$0.00 |
|--------|--------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/24/2015 2:20:11 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ortiz, Alfredo Replaced filters in classrooms. Q and R-build.

Alfredo Ortiz

| | | | | | | | | | |
|--------|--------|-----------|--|--|----------|--|----|--|--------|
| 132511 | I-Wing | Classroom | | | 5/7/2015 | | 11 | | \$0.00 |
|--------|--------|-----------|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/7/2015 7:53:12 AM | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Ortiz, Alfredo Need to clean coils on A/C units in side Band room they are in the cieling.

Alfredo Ortiz

| | | | | | | | | | |
|--------|--|----------|--|--|-----------|--|---|--|--------|
| 132802 | | Restroom | | | 5/13/2015 | | 5 | | \$0.00 |
|--------|--|----------|--|--|-----------|--|---|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/13/2015 8:30:49 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ortiz, Alfredo Need to paint restrooms to cover graffiti.

Alfredo Ortiz

| | | | | | | | | | |
|--------|--|----------|--|--|-----------|--|----|--|--------|
| 130654 | | Restroom | | | 3/27/2015 | | 52 | | \$0.00 |
|--------|--|----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 3/27/2015 9:11:07 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ortiz, Alfredo Need to paint over graffitti to in the boys restrooms and hallways.

Alfredo Ortiz

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|---|--|--------|
| 132944 | | | | | 5/14/2015 | | 4 | | \$0.00 |
|--------|--|--|--|--|-----------|--|---|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/14/2015 3:57:22 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ortiz, Alfredo

5-14-15
 .5 Chacked E-mail / got tools and materials.
 2.0 Tighten several loose faucets in F and C-wing restrooms.
 3.0 WO# 132276 C.
 2.0 Unclogged urinals F-wing, had to take off wall to remove stuck object.
 .5 Enter daily work log.

Alfredo Ortiz

| | | | | | | | | | |
|--------|-------|------|--|--|-----------|--|---|--|--------|
| 132712 | Pre-K | Roof | | | 5/12/2015 | | 6 | | \$0.00 |
|--------|-------|------|--|--|-----------|--|---|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/12/2015 8:58:56 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ortiz, Alfredo Need to replace filters and belts on A/C units.

Alfredo Ortiz

| | | | | | | | | | |
|--------|--|----------------|--|--|----------|--|----|--|--------|
| 132519 | | Athletic Field | | | 5/7/2015 | | 11 | | \$0.00 |
|--------|--|----------------|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | field house | | | 5/7/2015 10:59:19 AM | | | | |
|--------|------------------|-------------|--|--|----------------------|--|--|--|--|

Ortiz, Alfredo Dryer vent cover is missing from dryer vent for athletic training room (exterior) at the field house

Vicky Lopez

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral HS

131948 4/28/2015 20 \$0.00

Medium Work In Progress 4/28/2015 12:25:29 AM

Ortiz, Alfredo Daily - Chaparral HS - Fire Pump (Biweekly) - Refer to PMschedule details.

Margret Villalobos

132233 5/3/2015 5/6/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:49 AM

Ortiz, Alfredo Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PMschedule details.

Margret Villalobos

132801 Field House Dressing Room 5/13/2015 5 \$0.00

Medium Work In Progress 5/13/2015 8:28:07 AM

Ortiz, Alfredo Need to replace several light bulbs in locker rooms.

Alfredo Ortiz

132505 Field House Dressing Room 5/7/2015 11 \$0.00

Medium Work In Progress 5/7/2015 7:46:16 AM

Ortiz, Alfredo Need to paint metal doors. summer project.

Alfredo Ortiz

121794 Field House Dressing Room 8/26/2014 265 \$0.00

Medium Work In Progress 8/26/2014 3:03:15 PM

Ortiz, Alfredo do not have power to exauhst fans will not start. 5/1/15 - As per A. Vallejo, route to Alfredo

Alfredo Ortiz

128862 Exterior 2/12/2015 95 \$0.00

Medium Work In Progress 2/12/2015 3:22:48 PM

Ortiz, Alfredo Need to order and replace A/C pads Mastercool.

Alfredo Ortiz

132178 Exterior 5/1/2015 17 \$0.00

Medium Work In Progress 5/1/2015 3:56:06 PM

Ortiz, Alfredo Need to order paint for extrior doors for summer project. Need to paint all metal doors. Over 30 doors.

Alfredo Ortiz

131771 R-Wing Classroom 4/22/2015 26 \$0.00

Medium Work In Progress R3 4/22/2015 4:42:09 PM

Appelzoller, Fred PVC drain for washout booth. Please see Mr. Soria in R3.

Mireya Meza

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--|------------------|--------------|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 131772 | R-Wing | Classroom | | | 4/22/2015 | | 26 | | \$0.00 |
| Medium | Work In Progress | R3 | | | 4/22/2015 4:42:59 PM | | | | |
| Appelzoller, Fred Hose bibb for pressure washer. Please see Mr. Soria. | | | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 131069 | Field House | Restroom | | | 4/7/2015 | | 41 | | \$0.00 |
| Medium | Work In Progress | | | | 4/7/2015 4:03:48 PM | | | | |
| Appelzoller, Fred Need to replace toilets in G-wing restroom broken. | | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 125746 | R-Wing | Classroom | | | 11/19/2014 | | 180 | | \$0.00 |
| Medium | Work In Progress | | | | 11/19/2014 11:02:22 | | | | |
| Appelzoller, Fred In art classroom Q-Build. Needs new water line and run drain-pipes for a indoor power washer. | | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 126411 | H-Wing | Gym | | | 12/9/2014 | | 160 | | \$0.00 |
| Medium | Work In Progress | | | | 12/9/2014 11:49:08 AM | | | | |
| Appelzoller, Fred No water pressure on cold side floor sink in Gym custodians closet. | | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 130375 | A-Wing | Office | | | 3/19/2015 | | 60 | | \$0.00 |
| Medium | Work In Progress | Nurse | | | 3/19/2015 12:32:33 PM | | | | |
| Marquez, Gerardo One of the fireproof file cabinets in the nurse office was removed (a key had broken off in the lock) I would like to know if the lock can be replaced so the cabinet may be locked. (it doesn't have to be originals type of mechanism, just so long as there is a working lock on the cabinet). Ms. de Castro, nurse | | | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 124831 | A-Wing | Office | | | 10/31/2014 | | 199 | | \$0.00 |
| Medium | Work In Progress | Nurse office | | | 10/31/2014 9:23:18 AM | | | | |
| Marquez, Gerardo Key for one of the nurse's filing cabinet broke off. Please replace. (Fireking, Medeco, #238) (Ms. de Castro, Nurse) | | | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 132373 | | | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 1:28:23 PM | | | | |
| Marquez, Gerardo As per Ms. Hemphill, need vault opened lock her keys in there and Mireya is out. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-------|----------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 131070 | H-Wing | Gym | | | 4/7/2015 | | 41 | | \$0.00 |
| Medium | Work In Progress | | | | 4/7/2015 4:05:57 PM | | | | |
| Appelzoller, Fred | | Gym restrooms craked need to be replaced. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 128971 | | | | | 2/17/2015 | | 90 | | \$0.00 |
| Medium | Work In Progress | | | | 2/17/2015 3:24:15 PM | | | | |
| Sotelo, Enrique | | Electrical power source at each dugouts. (Baseball & Softball Fields) | | | | 5/1/15 - As per A. Vallejo, route to Enrique | | | |
| Terry Alvarado | | | | | | | | | |
| 132649 | A-Wing | Mechanical | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 8:30:17 AM | | | | |
| Appelzoller, Fred | | Need to repair circulating pump leaking water. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 128970 | | | | | 2/17/2015 | | 90 | | \$0.00 |
| Medium | Work In Progress | | | | 2/17/2015 3:22:54 PM | | | | |
| Appelzoller, Fred | | Water fountains (they will accomodate both the Baseball & Softball programs) | | | | | | | |
| Terry Alvarado | | | | | | | | | |
| 121594 | B-Wing | Classroom | | | 8/21/2014 | | 270 | | \$0.00 |
| Medium | Work In Progress | | | | 8/21/2014 3:32:10 PM | | | | |
| Sotelo, Enrique | | Need to install new wall outlet in B-2 classroom. | | | | 4/21/15 - Asp Albert, route to Enrique to complete | | | |
| Alfredo Ortiz | | | | | | | | | |
| 131770 | R-Wing | Classroom | | | 4/22/2015 | | 26 | | \$0.00 |
| Medium | Work In Progress | R3 | | | 4/22/2015 4:41:12 PM | | | | |
| Sotelo, Enrique | | 208v / 240v dedicated outlet for conveyor dryer is needed for print shop machine. Please see Mr. Soria in room R3. | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 132355 | B-Wing | Classroom | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 9:51:24 AM | | | | |
| Sotelo, Enrique | | B-3 science room No power in outlets can't find problem. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 132186 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:21 AM | | | | |
| Orozco, Daniel | | Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------------------|-----------------------|------------------|-------------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 132229 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:47 AM | | | | | |
| Orozco, Daniel | | Monthly- Chaparral HS Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129153 | | | | | 2/23/2015 | | 84 | | \$0.00 |
| Medium | Work In Progress | | | 2/23/2015 9:47:36 AM | | | | | |
| Ronquillo, Ruben | | Cost to repair bleachers as per quote from AK Sales | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 132799 | Pre-K | Office | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | 5/13/2015 8:18:36 AM | | | | | |
| Ronquillo, Ruben | | Attention to Ruben Warehouse. Need to order Sign for Pre-K Doors. Decal : For Security Reasons All Doors Are Locked Please Ring Doorbell for Assistance Thank You. Also in spanish. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 132033 | Field House | Office | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | Ticket Booth | | 4/29/2015 2:52:06 PM | | | | | |
| Ronquillo, Ruben | | Window in ticket booth out of place. Bottom portion frame is still present, but glass broken out onto floor of ticket booth. (Stacy Walsh) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 132912 | H-Wing | Kitchen | | | 5/14/2015 | | 4 | | \$0.00 |
| Safety | Work In Progress | | | 5/14/2015 1:51:43 PM | | | | | |
| Gonzalez, Salvador | | At kitchen next to dishwasher platfore is separating needs to be welded back together. Two ladies cut their hands. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 128785 | Field House | Storage | | | 2/11/2015 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 2/11/2015 12:32:14 PM | | | | | |
| Gonzalez, Salvador | | Need welder to fabricate four angle to support a pole to hang football jerseys in football storage room. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| Count: 65 Work Orders | | | Avg. Age of WO's | 53 | | Total for Chaparral HS | 0 | | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral MS

120816 Main Building Gym 8/8/2014 283 \$0.00

Medium Work In Progress 8/8/2014 11:17:35 AM

Gonzalez, Salvador Coach would like 3 tether ball poles installed near the outside basketball courts Route to Sal 10/22/14

Gidget Mora

132473 5/6/2015 12 5/6/2015 12:06:26 PM \$0.00

Medium Work In Progress 5/6/2015 12:06:26 PM

Gonzalez, Salvador Please make and install 2 metal ladders to CMS rooftop. One ladder to go down from cafeteria to kitchen roof. The other ladder to go down from cafeteria to classrooms and hallways roof.

Johnny Acuna

132744 5/12/2015 6 5/12/2015 2:49:35 PM \$0.00

Medium Work In Progress 5/12/2015 2:49:35 PM

Gonzalez, Salvador Need assistance with generator and grinder to remove benches in the outdoor basketball courts.

Johnny Acuna

131853 4/24/2015 24 4/24/2015 11:02:33 AM \$0.00

Medium Work In Progress 4/24/2015 11:02:33 AM

Orozco, Daniel 3 compartment sink is leaking from the handle to drain the water, due to this the floor is lifting and starting to come off. SNP Manager Sandra D. 824.4376

Maritza Gonzalez

132212 5/3/2015 5/24/2015 15 5/3/2015 12:32:36 AM \$0.00

Medium Work In Progress 5/3/2015 12:32:36 AM

Orozco, Daniel Monthly - Chaparral MS Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

125798 Main Building Gym 11/20/2014 179 11/20/2014 2:02:05 PM \$0.00

Medium Work In Progress 11/20/2014 2:02:05 PM

Sotelo, Enrique Light switch does not work on main entry into gym. Request all 4 switches be changed to toggle switch

Gidget Mora

132191 5/3/2015 5/24/2015 15 5/3/2015 12:32:24 AM \$0.00

Medium Work In Progress 5/3/2015 12:32:24 AM

Orozco, Daniel Monthly - Chapparal MS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral MS | | | | | | | | | |
| 124842 | | | | | 10/31/2014 | | 199 | | \$0.00 |
| Medium | Work In Progress | | | | 10/31/2014 2:26:36 PM | | | | |
| Orozco, Daniel | | The back doors to warmer seems to be hanging a little from both top hinges. This could be why that warmer takes forever to reach its holding temperature. SNP Manager Sandra D.824.4376 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 128088 | | | | | 1/29/2015 | | 109 | | \$0.00 |
| Medium | Work In Progress | | | | 1/29/2015 10:23:00 AM | | | | |
| Orozco, Daniel | | AIR CURTAIN AT BACK DOOR IS NOT WORKING, NEEDS A NEW MOTOR FAN. SNP MANAGER SANDRA D. 824.4376 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 128514 | | | | | 2/5/2015 | | 102 | | \$0.00 |
| Medium | Work In Progress | | | | 2/5/2015 10:24:42 AM | | | | |
| Orozco, Daniel | | I need to place a work order for the washer. It doesn't start right away and when it finally does, it doesn't want to drain/spin. SNP Manager Sandra D. 824.4376 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 128515 | | | | | 2/5/2015 | | 102 | | \$0.00 |
| Medium | Work In Progress | | | | 2/5/2015 10:26:15 AM | | | | |
| Orozco, Daniel | | Back door seal worn out, needs to be replaced. (as per environment dept.). SNP Manager Sandra D. 824.4376 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 128516 | | | | | 2/5/2015 | | 102 | | \$0.00 |
| Medium | Work In Progress | | | | 2/5/2015 10:26:50 AM | | | | |
| Orozco, Daniel | | Freezer door doesn't close completely without having to push it shut. (as per environment dept.) SNP Manager Sandra D. 824.4376 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132134 | | Cafeteria | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 10:54:14 AM | | | | |
| Appelzoller, Fred | | senesecita arreglar fuente de tomar agua tira mucha agua GRACIAS | | | | | | | |
| M. Carmen Perez | | | | | | | | | |
| 132516 | | Restroom (Girls) | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 9:17:56 AM | | | | |
| Appelzoller, Fred | | senesecita arreglar yave de agua del labamanos esta tirando agua GRACIAS | | | | | | | |
| M. Carmen Perez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral MS | | | | | | | | | |
| 132131 | Main Building | Restroom | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 9:21:50 AM | | | | |
| Appelzoller, Fred | | senesecita des tapar horinal de los Boys #200 hallway | | | | | | | |
| M. Carmen Perez | | GRACIAS | | | | | | | |
| 131789 | | Restroom | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 12:54:17 PM | | | | |
| Appelzoller, Fred | | senesecita areglar orinales de los boys #300/hallway | | | | | | | |
| M. Carmen Perez | | GRACIAS | | | | | | | |
| 132039 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 3:15:35 PM | | | | |
| Appelzoller, Fred | | Please install water fountain by gym doors. See Mr. Cardona for specifics. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 132530 | Main Building | Restroom (Girls) | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | 103 | | | 5/7/2015 1:23:23 PM | | | | |
| Sotelo, Enrique | | Girls RR in 100 hall does not have a working hand dryer | | | | | | | |
| Gidget Mora | | | | | | | | | |
| 132533 | Main Building | Gym | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | girls locker room | | | 5/7/2015 1:50:43 PM | | | | |
| Marquez, Gerardo | | Lock on outside door to girl's locker room doesnt work. Lock on Athletic locker room going into the PE locker room doesnt work | | | | | | | |
| Gidget Mora | | | | | | | | | |
| 131034 | Main Building | Athletic Field | | | 4/7/2015 | | 41 | | \$0.00 |
| Medium | Work In Progress | Coach Castillo | | | 4/7/2015 10:09:23 AM | | | | |
| Appelzoller, Fred | | Please install water fountains outside near the gym | | | | | | | |
| Gidget Mora | | | | | | | | | |
| 120809 | Main Building | Classroom | | | 8/8/2014 | | 283 | | \$0.00 |
| Medium | Work In Progress | 205 | | | 8/8/2014 10:47:57 AM | | | | |
| Appelzoller, Fred | | pipes on sinks need to be fixed | | | | | | | |
| Gidget Mora | | | | | | | | | |
| 132643 | | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 7:47:59 AM | | | | |
| Vallejo, Albert | | Install lettering and Logo on gym exterior. | | | | | | | |
| Albert Vallejo | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--|------------------|-------------|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral MS | | | | | | | | | |
| 132910 | | Office | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 1:38:53 PM | | | | |
| Gonzales, Camilo Deliver items from PO# 141507677. Attn: Ella Davis. Thank you. | | | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 132067 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 4:06:56 PM | | | | |
| Carrasco, Danny Need to bring any items from Maintenance portable at CMS that can be returned to stock. | | | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 132789 | | Gym | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 7:33:30 AM | | | | |
| Carrasco, Danny Please move Scissor lift to CMS gym for Graduation ceremony on May 20. | | | | | | | | | |
| 129491 | | | | | 3/1/2015 | | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 3/1/2015 12:45:53 AM | | | | |
| Flores, Pete Monthly - CHM-UV-0514 PM Service - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132333 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:47 AM | | | | |
| Quinones, Paul Monthly - Chaparral MS Monthly FE Inpsection - Refer to PMs schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132058 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 3:52:01 PM | | | | |
| Quinones, Paul painting is needed to paint back porch.@ chm | | | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 132232 | | | | | 5/3/2015 | 5/6/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:49 AM | | | | |
| Quinones, Paul Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PMs schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132655 | Main Building | Classroom | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | 205 | | | 5/11/2015 9:09:57 AM | | | | |
| Quinones, Paul Please turn off water from faucets that were never fixed | | | | | | | | | |
| Gidget Mora | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral MS | | | | | | | | | |
| 132732 | | Classroom | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | 203 | | | 5/12/2015 12:13:01 PM | | | | |
| Quinones, Paul | | All electrical outlets are out. only one microwave oven is working. teacher has tried resetting each individual outlet and they still will not work | | | | | | | |
| Gidget Mora | | | | | | | | | |
| 131975 | | Kitchen | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 4/28/2015 12:48:24 PM | | | | |
| Quinones, Paul | | senesecita poner un abrelatas en el teachers lounge GRACIAS | | | | | | | |
| M. Carmen Perez | | | | | | | | | |
| 132904 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 1:27:05 PM | | | | |
| Quinones, Paul | | Please assist with raising of balloons in gym on May 19th. See Mr Cardona for instruction. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 132534 | Main Building | Gym | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 1:54:33 PM | | | | |
| Quinones, Paul | | Tile on floor of equipment room is coming the floor | | | | | | | |
| Gidget Mora | | | | | | | | | |
| 131957 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 4/28/2015 9:48:45 AM | | | | |
| Quinones, Paul | | re-glue blue pads in main gym backboards all 6 | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 132262 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:06 AM | | | | |
| Quinones, Paul | | Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130833 | | | | | 4/5/2015 | 4/26/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:36 AM | | | | |
| Munoz, Michael | | Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-------|-----------------------|--|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral MS | | | | | | | | | |
| 118858 | | | | | 7/1/2014 | | 321 | | \$0.00 |
| High | Work In Progress | | | | 7/1/2014 9:58:32 AM | | | | |
| Munoz, Michael | | need to install new water gong bell for fire sprinkler system. district electrician will provide power. | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 129448 | | | | | 2/28/2015 | | 79 | | \$0.00 |
| Medium | Work In Progress | | | | 2/28/2015 12:34:56 AM | | | | |
| Munoz, Michael | | Yearly - Chaparral MS - Fire Pump Inspection - Refer to PMs schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 121096 | | | | | 8/13/2014 | | 278 | | \$0.00 |
| Medium | Work In Progress | | | | 8/13/2014 10:19:11 AM | | | | |
| Solis, Lorenzø | | Please insulate supplyducts on new refrigeration units. | | | | 5/1/15 - As per A. Vallejo, route to Lorenzo | | | |
| Albert Vallejo | | | | | | | | | |
| 132128 | | | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 8:48:50 AM | | | | |
| Solis, Lorenzø | | Need 2 spider bearings for a/c cooler in 308 | | | | | | | |
| M. Carmen Perez | | | | | | | | | |
| 132529 | Main Building | Classroom | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | 308 | | | 5/7/2015 1:18:32 PM | | | | |
| Solis, Lorenzø | | Air conditioner stopped working | | | | | | | |
| Gidget Mora | | | | | | | | | |
| 132525 | | Classroom | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 12:02:57 PM | | | | |
| Solis, Lorenzø | | Air conditioner has been turned on and needs to be able to have control on temperature because of classrooms pets and plants. | | | | | | | |
| Gidget Mora | | | | | | | | | |
| 132038 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 3:13:49 PM | | | | |
| Solis, Lorenzø | | Need to order 30 air vents for hydronic system at CMS. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 131654 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 11:04:40 AM | | | | |
| Solis, Lorenzø | | Need to replace mastercool 6500 downdraft to Girls locker room | | | | | | | |
| Johnny Acuna | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral MS

131656 4/21/2015 27 \$0.00

Medium Work In Progress 4/21/2015 11:07:16 AM

Solis, Lorenzø Need to replace mastercool 6500 downdraft to Classroom #105 (052)

Johnny Acuna

131657 4/21/2015 27 \$0.00

Medium Work In Progress 4/21/2015 11:08:37 AM

Solis, Lorenzø Need to replace mastercool 6500 downdraft to Main office. (049)

Johnny Acuna

131658 4/21/2015 27 \$0.00

Medium Work In Progress 4/21/2015 11:10:52 AM

Solis, Lorenzø Need to replace mastercool 6500 downdraft to Main Offices. (048)

Johnny Acuna

131659 4/21/2015 27 \$0.00

Medium Work In Progress 4/21/2015 11:12:17 AM

Solis, Lorenzø Need to replace mastercool 6500 downdraft to main Offices. (047)

Johnny Acuna

131660 4/21/2015 27 \$0.00

Medium Work In Progress 4/21/2015 11:13:26 AM

Solis, Lorenzø Need to replace mastercool 6500 downdraft to Main Offices. (046)

Johnny Acuna

131661 4/21/2015 27 \$0.00

Medium Work In Progress 4/21/2015 11:15:05 AM

Solis, Lorenzø Need to replace mastercool 6500 downdraft to Main Offices. (044)

Johnny Acuna

131662 4/21/2015 27 \$0.00

Medium Work In Progress 4/21/2015 11:16:12 AM

Solis, Lorenzø Need to replace mastercool 4500 downdraft to Main Offices.

Johnny Acuna

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral MS

131663 4/21/2015 27 \$0.00

Medium Work In Progress 4/21/2015 11:17:59 AM

Solis, Lorenzø Need to replace mastercool 4500 downdraft to Main Offices.

Johnny Acuna

131665 4/21/2015 27 \$0.00

Medium Work In Progress 4/21/2015 12:18:41 PM

Solis, Lorenzø Need to replace mastercool 6500 downdraft to Lobby. (043)

Johnny Acuna

131667 4/21/2015 27 \$0.00

Medium Work In Progress 4/21/2015 12:20:02 PM

Solis, Lorenzø Need to replace mastercool 6500 downdraft to Cafeteria. (060)

Johnny Acuna

131668 4/21/2015 27 \$0.00

Medium Work In Progress 4/21/2015 12:23:52 PM

Solis, Lorenzø Need to replace mastercool 6500 downdraft to Cafeteria. (061)

Johnny Acuna

131669 4/21/2015 27 \$0.00

Medium Work In Progress 4/21/2015 12:25:27 PM

Solis, Lorenzø Need to replace mastercool 6500 downdraft to classroom #203 (028)

Johnny Acuna

131412 4/14/2015 34 \$0.00

Medium Work In Progress 4/14/2015 4:01:54 PM

Solis, Lorenzø Need (6) 6500 A/c's and (2) 4500 A/c's for Chaparral Middle school main building. (Downdraft)

Johnny Acuna

131982 4/28/2015 20 \$0.00

Medium Work In Progress 4/28/2015 2:50:29 PM

Estrada, Jesus PLEASE QUOTE ON RE-UPHOLSTERING THE PROTECTIVE PADS ON THE GYM WALL (APPROXIMATELY 10 OF THEM). PLEASE CALL CHUY IF YOU HAVE ANY QUESTIONS. THANK YOU.

Jesus Estrada

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral MS

132263 5/3/2015 5/11/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:33:07 AM

Acuna, Johnny Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

132265 5/3/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:33:08 AM

Acuna, Johnny Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

132266 5/3/2015 6/3/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:33:08 AM

Acuna, Johnny Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

132535 Main Building 5/7/2015 11 \$0.00

Medium Work In Progress outside 5/7/2015 2:01:51 PM

Acuna, Johnny Bench broken off base outside basketball court

Gidget Mora

132703 5/11/2015 7 \$0.00

Medium Work In Progress 5/11/2015 4:18:22 PM

Acuna, Johnny Rm. #203: Need (25) 20 amp GFCI Outlets for Home Ec. classroom.

Johnny Acuna

132608 5/8/2015 10 \$0.00

Medium Work In Progress 5/8/2015 3:39:30 PM

Acuna, Johnny Need 15 wall Corner Moldings for CMS

Johnny Acuna

132515 Gym 5/7/2015 11 \$0.00

Medium Work In Progress 5/7/2015 9:12:43 AM

Acuna, Johnny senesecita revisar aire delos locker delas girl.s no esta trabagando GRACIAS

M. Carmen Perez

132523 Main Building Classroom 5/7/2015 11 \$0.00

Medium Work In Progress 200 5/7/2015 11:45:33 AM

Acuna, Johnny Handles on (2) cabinets need to be repaired. They are broken

Gidget Mora

5/18/2015 9:32:27 AM

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral MS | | | | | | | | | |
| 132675 | Main Building | Classroom | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | 105 | | | 5/11/2015 2:06:38 PM | | | | |
| Acuna, Johnny | | Class needs to have all light bulbs replaced | | | | | | | |
| Gidget Mora | | | | | | | | | |
| 132536 | Main Building | Classroom | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | 308 | | | 5/7/2015 2:11:38 PM | | | | |
| Acuna, Johnny | | Air conditioner does not work | | | | | | | |
| Gidget Mora | | | | | | | | | |
| 132132 | | Hallway/Corridor | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 9:25:26 AM | | | | |
| Acuna, Johnny | | senesecita remplasar lamparas que prenden del #100 hallway GRACIAS | | | | | | | |
| M. Carmen Perez | | | | | | | | | |
| 132133 | | Hallway/Corridor | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 9:28:05 AM | | | | |
| Acuna, Johnny | | senesecita remplasar lampara del #200 hallway GRACIAS | | | | | | | |
| M. Carmen Perez | | | | | | | | | |
| 132151 | | | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 12:31:14 PM | | | | |
| Herrera, Jaime | | Need to pick up stage from Utep on May 20 and take back on May 21. Person to contact at Utep is: Ricky Nichols (Assistant Director): Adress is 151 Glory Rd. (El Paso, Tx) (Set up and teardown is at CMS Gym) | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 132041 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 3:17:21 PM | | | | |
| Marquez, Gerardo | | Please repair or replace handle to exit door from boys locker room to west exterior of building. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 130988 | Main Building | Athletic Field | | | 4/6/2015 | | 42 | | \$0.00 |
| Medium | Work In Progress | Charlene | | | 4/6/2015 11:14:01 AM | | | | |
| Ontiveros, Guadalupe | | Lupe - Grounds = This is regarding the Dug outs at CMS = Requesting a chain link fence for the chain link dug outs to complete the Softball area. | | | | | | | |
| Terry Alvarado | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|---|----------------------------|-----------------------------------|-----------------------|-------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral MS | | | | | | | |
| 131813 | | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | 4/23/2015 3:35:52 PM | | | | | |
| Acuna, Johnny | Need 2 Commercial medias for Gym rooftop a/c's. 47 1/2" wide X 44 1/2" Long X 12" Thick | | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 131816 | | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | 4/23/2015 3:37:30 PM | | | | | |
| Acuna, Johnny | Need 4 fan belts for Gym a/c's. 4L-970 | | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 132013 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | 4/28/2015 4:10:48 PM | | | | | |
| Acuna, Johnny | Need to replace burned out ballasts and bulbs to kitchen. Lots of fixtures are off. Kitchen is dark. | | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 132230 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:48 AM | | | | | |
| Acuna, Johnny | Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130998 | | Gym | | | 4/6/2015 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 4/6/2015 11:44:54 AM | | | | | |
| Estrada, Jesus | 1) Sand down floor 2) Repaint volleyball and basketball lines (same color as we have now) 3) Repaint mascot (same as we have now) 4) Varnish gym floor | | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 119581 | | Athletic Field | | | 7/18/2014 | | 304 | | \$0.00 |
| Medium | Work In Progress | | | 7/18/2014 1:31:26 PM | | | | | |
| Vasquez, Jose | playing fields need to be reseed as per site admin. | | Summer Project asp report 3/11/15 | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 131589 | Main Building | Classroom | | | 4/20/2015 | | 28 | | \$0.00 |
| Medium | Work In Progress | 402 | | 4/20/2015 10:24:22 AM | | | | | |
| Vargas, Juan | 2 lights are out in classroom | | | | | | | | |
| Gidget Mora | | | | | | | | | |
| Count: 81 Work Orders | | Avg. Age of WO's 46 | | | Total for Chaparral MS | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|----------------------|------------------|---|--|--|-----------------------|----------------------------|-----|--|--------|
| Location: | | Desert Pride HS | | | | | | | |
| 124335 | | | | | 10/20/2014 | | 210 | | \$0.00 |
| Medium | Work In Progress | | | | 10/20/2014 10:31:12 | | | | |
| Ontiveros, Guadalupe | | PAINT LINES ON BASKETBALL COURT. | | | | Asp Mike, route to Grounds | | | |
| Yvette Cortez | | | | | | | | | |
| 132430 | | Portables | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | room# 7 | | | 5/5/2015 1:01:03 PM | | | | |
| Marquez, Gerardo | | server room door handle needs a core. | | | | | | | |
| David Acosta | | | | | | | | | |
| 132368 | | Portables | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | room# 7 | | | 5/4/2015 12:09:33 PM | | | | |
| Marquez, Gerardo | | Flimsy door need to be replace | | | | | | | |
| David Acosta | | | | | | | | | |
| 132369 | | Portables | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | room #8 | | | 5/4/2015 12:12:04 PM | | | | |
| Marquez, Gerardo | | flimsy door needs to be replace to this computer room | | | | | | | |
| David Acosta | | | | | | | | | |
| 132021 | | Portables | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | room #14 | | | 4/29/2015 10:34:03 AM | | | | |
| Marquez, Gerardo | | Need to replace door closer. | | | | | | | |
| David Acosta | | | | | | | | | |
| 121338 | | Portables | | | 8/18/2014 | | 273 | | \$0.00 |
| Medium | Work In Progress | 1 & 2 | | | 8/18/2014 11:30:07 AM | | | | |
| Marquez, Gerardo | | DOOR CYLINDER TO STORGE ROOM IN PORTABLE 1 & 2 NEEDS TO BE REPLACED. ALSO, WHEN REPLACING CYLINDER, PLEASE GIVE STORAGE KEY TO MS. SCOTT AND MS. JAMESON-SPED TEACHERS. | | | | | | | |
| Yvette Cortez | | | | | | | | | |
| 132822 | | Portables | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | restrooms #17 | | | 5/13/2015 12:17:51 PM | | | | |
| Villalobos, David | | No hot water for restrooms. Water heater keeps tripping out at breaker box | | | | | | | |
| David Acosta | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Desert Pride HS | | | | | | | | | |
| 132417 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 9:20:41 AM | | | | |
| Duran, Adan | | Excessive number of weeds coming through rock. For more information, contact Mr. Ralph Gallegos at 575-882-6921. | | | | | | | |
| Dominique Esparza | | | | | | | | | |
| 132370 | | Portables | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | portable 4 | | | 5/4/2015 12:49:46 PM | | | | |
| Duran, Adan | | Pick up Art racks to store at warehouse. Teacher has no use for them. | | | | | | | |
| Maria Carbajal | | | | | | | | | |
| 131480 | | Gym | | | 4/16/2015 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 4/16/2015 10:13:24 AM | | | | |
| Duran, Adan | | need to have benches fasten or secure to floor | | | | | | | |
| David Acosta | | | | | | | | | |
| 121923 | | | | | 8/28/2014 | | 263 | | \$0.00 |
| Medium | Work In Progress | 11 & 12 | | | 8/28/2014 1:40:28 PM | | | | |
| Appelzoller, Fred | | TOILET GETS CLOGGED IN PORTABLE 11 & 12. PLEASE CHECK TO SEE WHAT IS CLOGGING THE TOILET. | | | | | | | |
| Yvette Cortez | | | | | | | | | |
| 132900 | | Office | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 12:36:50 PM | | | | |
| Marquez, Gerardo | | Administration bldg. front entrance door closers are in need of adjustment for safety reason. | | | | | | | |
| David Acosta | | | | | | | | | |
| 132736 | | Portables | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | room# 7 | | | 5/12/2015 12:34:35 PM | | | | |
| Sotelo, Enrique | | class room light do not turn on .light switch not working properly. | | | | | | | |
| David Acosta | | | | | | | | | |
| 132818 | | Portables | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | room 5 | | | 5/13/2015 12:04:57 PM | | | | |
| Sotelo, Enrique | | Need electrical socket to plug-in overhead projector mounted on ceiling. | | | | | | | |
| David Acosta | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|----------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Desert Pride HS | | | | | | | | | |
| 132819 | | Portables | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | room 6 | | | 5/13/2015 12:06:51 PM | | | | |
| Sotelo, Enrique | | Need electrical socket to plug-in overhead projector mounted on ceiling. | | | | | | | |
| David Acosta | | | | | | | | | |
| 132817 | | Classroom | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | 101 reading/lab | | | 5/13/2015 12:00:31 PM | | | | |
| Sotelo, Enrique | | Need electrical socket to plug-in overhead projector mounted on ceiling. | | | | | | | |
| David Acosta | | | | | | | | | |
| 131284 | | Gym | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 4/13/2015 9:47:57 AM | | | | |
| Ronquillo, Ruben | | need to have stationary punching bags stances fasten or secure on to the floor. | | | | | | | |
| David Acosta | | | | | | | | | |
| 130848 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:44 AM | | | | |
| Ronquillo, Ruben | | Monthly - Desert Pride - (Qtrly) Fitness Equipment - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 127415 | | | | | 1/12/2015 | | 126 | | \$0.00 |
| Medium | Work In Progress | | | | 1/12/2015 3:16:17 PM | | | | |
| Gallegos, Rafael | | MR LORENZO SOLIS SIR THE HEATER AT DESERT PRIDE IN NOT TURNING ON CAN YOU PLEASE CHECK THANK YOU AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| Count: 19 Work Orders | | Avg. Age of WO's 58 | | | Total for Desert Pride HS | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Desert Trail ES | | | | | | | | | |
| 131676 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 1:39:20 PM | | | | |
| Gonzalez, Salvador | | P.E. Coach requesting a Baseball Pitchers protective screen for after-school Baseball Program for students. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 131630 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 7:49:09 AM | | | | |
| Gonzalez, Salvador | | Please make metal base frame for Refrigeration Bard unit to portable #406 and weld to existing metal base of portable. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 124678 | | | | | 10/28/2014 | | 202 | | \$0.00 |
| Medium | Work In Progress | | | | 10/28/2014 12:31:36 | | | | |
| Gonzalez, Salvador | | Need plate replacement for sidewalk on westside of main building portables area. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 119597 | | | | | 7/18/2014 | | 304 | | \$0.00 |
| Medium | Work In Progress | | | | 7/18/2014 3:05:40 PM | | | | |
| Appelzoller, Fred | | Need parts to repair broken clean-out. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 132126 | | | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 7:58:40 AM | | | | |
| Marquez, Gerardo | | Please fix (main building) doors to westside middle wing going out to the portable classrooms. Custodial is having a hard time trying to lock and secure doors at the end of their work shift. (Doors need to be replaced when possible. Broken on the hinges) Thanks. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 128688 | | | | | 2/9/2015 | | 98 | | \$0.00 |
| Medium | Work In Progress | | | | 2/9/2015 3:43:35 PM | | | | |
| Orozco, Daniel | | METAL FROM THE WALK-IN FLOOR COMING OFF. SNP MANAGER PAT C. 824.3822 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 128415 | | | | | 2/3/2015 | | 104 | | \$0.00 |
| Medium | Work In Progress | | | | 2/3/2015 2:48:33 PM | | | | |
| Orozco, Daniel | | FAUCET ON DRAIN IN 3 COMPARTMENT SINK IS BROKEN SNP MANAGER PAT C. 824.3822 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------|---|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert Trail ES | | | | | | | |
| 132192 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:24 AM | | | | | |
| Orozco, Daniel | Monthly - Desert Trail ES - Range Hood Cleaning - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 122696 | | | | | 9/12/2014 | | 248 | | \$0.00 |
| Medium | Work In Progress | | | 9/12/2014 11:12:08 AM | | | | | |
| Orozco, Daniel | As per Health Inspection Report-foot pedal (walk-in)door pedal and freezer foot pedal from sinks are leaking. | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 130429 | | | | | 3/20/2015 | | 59 | | \$0.00 |
| Medium | Work In Progress | | | 3/20/2015 2:40:47 PM | | | | | |
| Orozco, Daniel | The dryer doesn't want to dry the towels. Thank you. SNP Manager Pat C.824.3822 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132213 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:37 AM | | | | | |
| Orozco, Daniel | Monthly - Desert Trail ES - Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132954 | | | | | 5/15/2015 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 5/15/2015 7:50:58 AM | | | | | |
| Vallejo, Albert | Need electrical service for additional portables. | | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 131746 | | | | | 4/22/2015 | | 26 | | \$0.00 |
| Medium | Work In Progress | | | 4/22/2015 3:16:02 PM | | | | | |
| Gonzales, Camilo | Office needs handbook supplies picked up and delivered to Carmen Moreno at the GAC. | | | | | | | | |
| Elizabeth Hernandez | | | | | | | | | |
| 130498 | | | | | 3/24/2015 | | 55 | | \$0.00 |
| Medium | Work In Progress | | | 3/24/2015 8:49:33 AM | | | | | |
| Marquez, Gerardo | Portable #406: Please change out core to portable door to be same as teachers key. Thank You..... | | | | | | | | |
| Johnny Acuna | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Desert Trail ES | | | | | | | | | |
| 127657 | | | | | 1/16/2015 | | 122 | | \$0.00 |
| Medium | Work In Progress | | | | 1/16/2015 2:26:12 PM | | | | |
| Marquez, Gerardo | | Please replace main doors and door closures on the westside of main building. (Portables Area) | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 129833 | | | | | 3/5/2015 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | | 3/5/2015 1:39:57 PM | | | | |
| Marquez, Gerardo | | AS PER ADELE BALES MONITORING REPORT (2.24.15)- RUSTY DOOR FRAME IN STORE ROOM. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 129830 | | | | | 3/5/2015 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | | 3/5/2015 1:37:00 PM | | | | |
| Acuna, Johnny | | AS PER ADELE BALES MONITORING REPORT (2.24.15)- HOLE ON WALL BY MOP SINK IN KITCHEN STORE ROOM . | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 129889 | | | | | 3/6/2015 | | 73 | | \$0.00 |
| Medium | Work In Progress | | | | 3/6/2015 3:32:45 PM | | | | |
| Acuna, Johnny | | 3-6-15 | | | | 3/6 | | | |
| | | .5-check boiler heating system 3.5-(Front Lobby) remove waterfountain, replace P-trap, make adjustments to measurements on the wall, install new fountain, test for leaks and proper operation. 2.0-Replace faucet to room #108 classroom sink. \$97.00 2.0-cut weeds. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 120033 | | | | | 7/30/2014 | | 292 | | \$0.00 |
| Medium | Work In Progress | | | | 7/30/2014 2:18:04 PM | | | | |
| Acuna, Johnny | | As per Alfredo please order borders needed. Need approx. 22 borders for playground sand to the bigger playground area sets. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 118894 | | | | | 7/2/2014 | | 320 | | \$0.00 |
| Medium | Work In Progress | | | | 7/2/2014 8:23:42 AM | | | | |
| Acuna, Johnny | | Need to patch and re-stitch playground picnic table area Blue Canvas Shade. | | | | | | | |
| Johnny Acuna | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Desert Trail ES | | | | | | | | | |
| 132464 | | | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 9:03:35 AM | | | | |
| Acuna, Johnny | | Need 2 (5-Gallon Buckets) of Vanilla Bean (Latex-Water Based Paint) for Summer projects at DT | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 132154 | | | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 1:59:53 PM | | | | |
| Acuna, Johnny | | Need to replace A/c motor to Cafeteria air-conditioner. 480 Volts, 2-speed | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 132339 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:51 AM | | | | |
| Acuna, Johnny | | Monthly - Desert Trail ES - Monthly FE Inpsection - Refer to PMSchedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132242 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:55 AM | | | | |
| Acuna, Johnny | | Monthly - Desert Trail ES- Emer Light Insp:Monthly - Refer to PMSchedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132243 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:55 AM | | | | |
| Acuna, Johnny | | Monthly - Desert Trail ES - Exit Sign Insp:Monthly - Refer to PMSchedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132244 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:56 AM | | | | |
| Acuna, Johnny | | Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PMSchedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132614 | | | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 3:48:43 PM | | | | |
| Acuna, Johnny | | Paint Portable #413 classroom | | | | | | | |
| Johnny Acuna | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|-----------------------|-----------|----|--|--------|
| Location: | | Desert Trail ES | | | | | | | |
| 132634 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 5/10/2015 12:23:44 AM | | | | |
| Acuna, Johnny | | Monthly - Desert Trail ES - Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131260 | | | | | 4/12/2015 | 4/28/2015 | 36 | | \$0.00 |
| Medium | Work In Progress | | | | 4/12/2015 12:23:51 AM | | | | |
| Acuna, Johnny | | Monthly - Desert Trail ES - Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130827 | | | | | 4/5/2015 | 4/13/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:33 AM | | | | |
| Acuna, Johnny | | Monthly - Desert Trail ES - Roof Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131895 | | Custodial | | | 4/27/2015 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 4/27/2015 8:14:57 AM | | | | |
| Carbajal, Jimmy | | Jimmy la aspiradora Num. 0056 el suich no prende on/off la puede revisar por favor gracias | | | | | | | |
| Laura Sandoval | | | | | | | | | |
| 130186 | | Custodial | | | 3/16/2015 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | | 3/16/2015 10:18:26 AM | | | | |
| Estrada, Jesus | | Buenos dia Chuy. estos son los portables que se necesitan alfombrar Num,400 se necesita reparar la alfombra se esta desilando. 401 , 402, 403, 404, 408, 410, 411, Arte 413 tiene piso , y final mente 416 y quedarian perfectos. | | | | | | | |
| Laura Sandoval | | | | | | | | | |
| 128658 | | | | | 2/9/2015 | | 98 | | \$0.00 |
| Medium | Work In Progress | | | | 2/9/2015 9:19:58 AM | | | | |
| Vasquez, Jose | | Need to relocate swing set with 2 swings to other side. Please see Coach Scott. Thanks | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 131096 | | | | | 4/8/2015 | | 40 | | \$0.00 |
| Medium | Work In Progress | | | | 4/8/2015 11:50:28 AM | | | | |
| Solis, Lorenzo | | Need (2) 18" x 18" A/c supply adjustable registers for portable #418, 419. | | | | | | | |
| Johnny Acuna | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|-----------------------|-----------|-----|--|--------|
| Location: | | Desert Trail ES | | | | | | | |
| 131650 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 11:00:40 AM | | | | |
| Solis, Lorenzo | | Need to replace mastercool 4500 downdraft to portable #411 | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 131651 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 11:01:58 AM | | | | |
| Solis, Lorenzo | | Need to replace mastercool 4500 downdraft to portable #412 | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 131652 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 11:03:01 AM | | | | |
| Solis, Lorenzo | | Need to replace mastercool 4500 downdraft to portable #413 | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 132405 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 12:24:20 AM | | | | |
| Apodaca, Mario | | Monthly - Desert Trail ES - Domestic Water Filter - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131380 | | | | | 4/14/2015 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | | 4/14/2015 1:31:07 PM | | | | |
| Solis, Lorenzo | | Please order corrugated metal covers to cover up outdoor walls where old refrigerated units used to be. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 130834 | | | | | 4/5/2015 | 4/26/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:37 AM | | | | |
| Munoz, Michael | | Monthly - Desert Trail ES - Fire Sprinkler Insp. - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 125181 | | | | | 11/5/2014 | | 194 | | \$0.00 |
| Medium | Work In Progress | | | | 11/5/2014 2:44:50 PM | | | | |
| Flores, Pete | | Please fix fuel gauge to work truck #192 | | | | | | | |
| Johnny Acuna | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|--|----------------------------|---------------------------|-------|----------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Desert Trail ES | | | | | | | | | |
| 132816 | Main Building | Classroom | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | 409 | | | 5/13/2015 11:56:30 AM | | | | |
| Villalobos, Margret | We need emergency treatment in playground and in portable #409 due to some type of lice, not sure if bird lice or seed ticks. Please help. | | Emailed waiver to Bennie. | | | | | | |
| Elizabeth Hernandez | | | | | | | | | |
| 132590 | | | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 12:20:40 PM | | | | |
| Flores, Pete | Please fix Gas Gauge to work truck #192 at D.T. | | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| Count: 43 Work Orders | | Avg. Age of WO's 68 | | | Total for Desert Trail ES | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Desert View ES | | | | | | | | | |
| 132950 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 4:59:10 PM | | | | |
| Flores, Pete | | The switch to turn on the truck is broken, need it repaired. Thank you, Ruben | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 132572 | Main Building | Classroom | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 7:53:33 AM | | | | |
| Lara, Ralph | | NEED TO GET A COUNT OF CORE CYINDERS THAT ARE GOING TO BE INSTALLED BY ME AT NEW SCHOOL D.V.E.. | | | | | | | |
| Ralph Lara | | | | | | | | | |
| 132087 | Main Building | Restroom | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 10:25:59 AM | | | | |
| Lara, Ralph | | The staff restroom door still needs to be repaired it is still hanging and the building mechanic already tried to fix it but got loose again and its hanging again. It needs to be fixed. Thank you | | | | | | | |
| Israel Ortega | | | | | | | | | |
| 132503 | Main Building | Portables | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | Portable B | | | 5/7/2015 6:48:51 AM | | | | |
| Lara, Ralph | | ASAP Please. Came in this morning and the door would not open up no matter which way I turned the key. I have to come in through portable A. That is not good because I have kids filtering every 30 minutes. I also can't have the door open because of the dirt road that is in front of the building. I am just getting over a sever case of ASTHMA. Office knows about it. So Please, send the Locksmith ASAP to fix the door. Thank you very much for reading this work order | | | | | | | |
| Albert Ortiz | | | | | | | | | |
| 125536 | | | | | 11/13/2014 | | 186 | | \$0.00 |
| Medium | Work In Progress | Front of School | | | 11/13/2014 3:46:34 PM | | | | |
| Munoz, Michael | | Repair broken sidewalk in the front of school. It can cause someone to trip. (Araujo) | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |
| 128045 | Main Building | Storage | | | 1/28/2015 | | 110 | | \$0.00 |
| Medium | Work In Progress | | | | 1/28/2015 1:57:31 PM | | | | |
| Ontiveros, Joe | | Hi Joe on the storage that is next to the upper grade level restroom the release valve on the water is leaking. It needs to be replaced. Thank you. | | | | | | | |
| Israel Ortega | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Desert View ES

128046 Main Building Storage 1/28/2015 110 \$0.00

Medium Work In Progress 1/28/2015 2:02:36 PM

Ontiveros, Joe Hi Joe on the storage next to the restroom the back flow pleventer is leaking can you fix it please. Thank you

Israel Ortega

132907 5/14/2015 4 \$0.00

Medium Work In Progress 5/14/2015 1:30:25 PM

Ontiveros, Joe CARVER ELECTRIC
BOBBY CARVER
(575)527-2127

SPOT PER WORK PLAN

Alfredo Holguin

131897 Main Building Restroom 4/27/2015 21 \$0.00

Medium Work In Progress 4/27/2015 8:29:11 AM

Ontiveros, Joe According to Mrs. Aguilar there is a leak coming from the bottom of the toilet in the restroom that is in the Special Ed Room It needs to be fixed. Thank you

Israel Ortega

132871 5/14/2015 4 \$0.00

Medium Work In Progress 5/14/2015 7:38:06 AM

Ontiveros, Joe CARVER ELECTRIC
BOBBY CARVER
(575)527-2127

FROM RIO VISTA AND VALLE VISTA - SPOT LINE
MARKED IN WHITE FROM UNDERGROUND
JUNCTION BOX LOCATED APPR 50 YARDS INSIDE
CONSTRUCTION FENCE AND 30 YARDS WEST OF
CONSTRUCTION ACCESS ROAD. SPOT THE
ENTIRE LENGTH OF THE WHITE LINE.

Alfredo Holguin

132674 5/11/2015 7 \$0.00

Medium Work In Progress 5/11/2015 1:53:00 PM

Ontiveros, Joe Company: CALIPER CONSTRUCTION
Contact Name: FERNIE REYES Contact Phone:
(575)635-8919
Email: blanca@caliperconstoom

Location of Work: DESERT VIEW ELEMENTARY
SCHOOL WIDE AREA WORK PLAN

Dominique Esparza

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|------------------|---|-----------------------|------------------------------|--|----------------------|--|---|--|--------|
| Location: | | Desert View ES | | | | | | | |
| 132651 | | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 8:44:24 AM | | | | |
| Ontiveros, Joe | Company: METRO MECHANICAL | | | | | | | | |
| | Contact Name: RICHARD MUNOZ | | Contact Phone: (575)649-5554 | | | | | | |
| | Fax No: (575)527-8309 | | | | | | | | |
| | Location of Work: SPOT: ENTIRE PROPERTY AT ADDRESS. | | | | | | | | |
| | Remarks: OPEN ACCESS; NO HAZARDS. RELOCATE: LONGER THAN EXPECTED. | | | | | | | | |

| | | | | | | | | | |
|------------------|---|-----------------------|------------------------------|--|---------------------|--|----|--|--------|
| Location: | | Desert View ES | | | | | | | |
| 130974 | | | | | 4/6/2015 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | | 4/6/2015 8:25:00 AM | | | | |
| Ontiveros, Joe | Company: METRO MECHANICAL | | | | | | | | |
| | Contact Name: RICHARD MUNOZ | | Contact Phone: (575)649-5554 | | | | | | |
| | Email: metromechinc@qwestoffice.net | | | | | | | | |
| | Location of Work: SPOT ENTIRE PROPERTY. OPEN ACCESS; NO HAZARDS | | | | | | | | |
| | Remarks: RELOCATE DUE TO TAKING LONGER THAN EXPECTED | | | | | | | | |

| | | | | | | | | | |
|------------------|--------------------------------------|-----------------------|----------------------------------|--|-----------------------|--|----|--|--------|
| Location: | | Desert View ES | | | | | | | |
| 132086 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 10:13:56 AM | | | | |
| Ontiveros, Joe | Company: CARVER ELECTRIC | | | | | | | | |
| | Contact Name: BOBBY CARVER | | Contact Phone: (575)527-2127 | | | | | | |
| | Alternate Contact: DANIEL CARVER | | Alternate Phone: (575)649-9142 | | | | | | |
| | Cell Phone: (575)644-4313 | | Email: carver@carverelectric.com | | | | | | |
| | Location of Work: SPOT PER WORK PLAN | | | | | | | | |

| | | | | | | | | | |
|------------------|---|-----------------------|------------------------------|--|-----------------------|--|----|--|--------|
| Location: | | Desert View ES | | | | | | | |
| 131965 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 4/28/2015 11:21:32 AM | | | | |
| Ontiveros, Joe | Company: CALIPER CONSTRUCTION | | | | | | | | |
| | Contact Name: FERNIE REYES | | Contact Phone: (575)635-8919 | | | | | | |
| | Email: blanca@caliperconstoom | | | | | | | | |
| | Location of Work: DESERT VIEW ELEMENTARY SCHOOL WIDE AREA WORK PLAN | | | | | | | | |

Dominique Esparza

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | |

Location: Desert View ES

131979 4/28/2015 20 \$0.00

Medium Work In Progress 4/28/2015 2:37:13 PM

Ontiveros, Joe
 Company: METRO MECHANICAL
 Contact Name: RICHARD MUNOZ Contact Phone: (575)649-5554
 Fax No: (575)527-8309

Location of Work: SPOT: ENTIRE PROPERTY AT ADDRESS.

Dominique Esparza

131908 4/27/2015 21 \$0.00

Medium Work In Progress 4/27/2015 11:38:23 AM

Ontiveros, Joe
 Company: CARVER ELECTRIC
 Contact Name: BOBBY CARVER Contact Phone: (575)527-2127
 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142
 Cell Phone: (575)644-4313
 Email: carver@carverelectric.com

Location of Work: CONTACT BOBBY CARVER @ 575-644-4313 TO DEVELOP A WIDE AREA WORK PLAN

Remarks: CONFERENCE TO BE HELD @ 1105 VALLE VISTA @ 10:30AM ON THE 29TH OF APRIL,2015

Dominique Esparza

131914 4/27/2015 21 \$0.00

Medium Work In Progress 4/27/2015 1:21:10 PM

Ontiveros, Joe It looks like a duplicate for 2015180197

Company: CARVER ELECTRIC
 Contact Name: JACOB CARVER Contact Phone: (575)527-2127
 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142
 Cell Phone: (575)649-9207
 Email: carver@carverelectric.com

Location of Work: LOCATE PER THE DESERT VIEW ELEMENTERY WORK PLAN

Dominique Esparza

132737 Custodial 5/12/2015 6 \$0.00

Medium Work In Progress 5/12/2015 12:35:05 PM

Carbajal, Jimmy Hi Jimmy vacuum cleaner #C08C00000330 broke. It needs to be repaired. Thank you.

Israel Ortega

5/18/2015 9:32:29 AM

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Desert View ES | | | | | | | | | |
| 132738 | | Custodial | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 12:37:21 PM | | | | |
| Carbajal, Jimmy | | Hi Jimmy, vacuum cleaner #20002017 broke. It needs to be fixed. Thank you | | | | | | | |
| Israel Ortega | | | | | | | | | |
| 132734 | | Custodial | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 12:29:22 PM | | | | |
| Carbajal, Jimmy | | Hi Jimmy we are going to need a new pressure washer the one we had the engine blew. All fluids were at level but the engine just started jerking and it blew a rod. | | | | | | | |
| Israel Ortega | | | | | | | | | |
| 132735 | | Custodial | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 12:32:32 PM | | | | |
| Carbajal, Jimmy | | Hi Jimmy your pressure washer broke #1019839464 disregard previous work order. The engine blew so we are in need of a new one. Thank you | | | | | | | |
| Israel Ortega | | | | | | | | | |
| 130261 | | | | | 3/17/2015 | | 62 | | \$0.00 |
| Medium | Work In Progress | Outside upper | | | 3/17/2015 1:47:31 PM | | | | |
| Ontiveros, Guadalupe | | The sprinklers aren't working properly out there. There are creating puddles and causing for the trees to dry out. (Araujo) | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |
| 132949 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 4:49:58 PM | | | | |
| Aldaz, Bobby | | Strong winds knocked down a pine tree in front of the school, need it removed. Thank you, Ruben | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 132664 | | Office | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 10:19:19 AM | | | | |
| Gonzales, Camilo | | Deliver 1 Gaylord. Thank you. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 132017 | Main Building | Office | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 8:20:06 AM | | | | |
| Gonzales, Camilo | | Please deliver one Gaylord and pallet to DVE. | | | | | | | |
| Larry Martinez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|--------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |

Location: Desert View ES

132463 Computer Lab 5/6/2015 12 \$0.00

Medium Work In Progress 5/6/2015 8:42:58 AM

Gonzales, Camilo Pick up obsolete computer monitors and deliver to IMWHSE for disposal. Located in the computer lab, 8 items. Thank you.

Theresa Ramirez

132868 5/14/2015 4 \$0.00

Medium Work In Progress 5/14/2015 7:34:55 AM

Castillo, Carlos CARVER ELECTRIC BOBBY CARVER (575)527-2127

FROM RIO VISTA AND VALLE VISTA - SPOT LINE MARKED IN WHITE FROM UNDERGROUND JUNCTION BOX LOCATED APPR 50 YARDS INSIDE CONSTRUCTION FENCE AND 30 YARDS WEST OF CONSTRUCTION ACCESS ROAD. SPOT THE ENTIRE LENGTH OF THE WHITE LINE.

Alfredo Holguin

132650 5/11/2015 7 \$0.00

Medium Work In Progress 5/11/2015 8:44:09 AM

Castillo, Carlos Company: METRO MECHANICAL Contact Name: RICHARD MUNOZ Contact Phone: (575)649-5554 Fax No: (575)527-8309

Location of Work: SPOT: ENTIRE PROPERTY AT ADDRESS. Remarks: OPEN ACCESS; NO HAZARDS. RELOCATE: LONGER THAN EXPECTED.

Dominique Esparza

132673 5/11/2015 7 \$0.00

Medium Work In Progress 5/11/2015 12:46:39 PM

Castillo, Carlos Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Email: blanca@caliperconst.com

Location of Work: DESERT VIEW ELEMENTARY SCHOOL WIDE AREA WORK PLAN

Dominique Esparza

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | |

Location: Desert View ES

131964 4/28/2015 20 \$0.00

Medium Work In Progress 4/28/2015 11:21:19 AM

Castillo, Carlos
 Company: CALIPER CONSTRUCTION
 Contact Name: FERNIE REYES Contact Phone:
 (575)635-8919
 Email: blanca@caliperconstoom

Location of Work: DESERT VIEW ELEMENTARY
 SCHOOL WIDE AREA WORK PLAN

Dominique Esparza

131978 4/28/2015 20 \$0.00

Medium Work In Progress 4/28/2015 2:36:54 PM

Castillo, Carlos
 Company: METRO MECHANICAL
 Contact Name: RICHARD MUNOZ Contact Phone:
 (575)649-5554
 Fax No: (575)527-8309

Location of Work: SPOT: ENTIRE PROPERTY AT
 ADDRESS.

Dominique Esparza

131541 4/17/2015 31 \$0.00

Medium Work In Progress 4/17/2015 11:20:29 AM

Castillo, Carlos Need electrical power for May 19, 2015 for the Field 4/21/15 Asp Cali request, change to
 Day. Thank you, Ruben Project

Ruben Ortiz

131907 4/27/2015 21 \$0.00

Medium Work In Progress 4/27/2015 11:38:03 AM

Castillo, Carlos
 Company: CARVER ELECTRIC
 Contact Name: BOBBY CARVER Contact Phone:
 (575)527-2127
 Alternate Contact: DANIEL CARVER Alternate
 Phone: (575)649-9142
 Cell Phone: (575)644-4313
 Email: carver@carverelectric.com

Location of Work: CONTACT BOBBY CARVER @ 575-
 644-4313 TO DEVELOP A WIDE AREA WORK PLAN

Remarks: CONFERENCE TO BE HELD @ 1105 VALLE
 VISTA @ 10:30AM
 ON THE 29TH OF APRIL, 2015

Dominique Esparza

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | |

Location: Desert View ES

131913 4/27/2015 21 \$0.00

Medium Work In Progress 4/27/2015 1:20:55 PM

Castillo, Carlos It looks like a duplicate for 2015180197

Company: CARVER ELECTRIC
 Contact Name: JACOB CARVER Contact Phone: (575)527-2127
 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142
 Cell Phone: (575)649-9207 Email: carver@carverelectric.com

Location of Work: LOCATE PER THE DESERT VIEW ELEMENTERY WORK PLAN

Dominique Esparza

132085 4/30/2015 18 \$0.00

Medium Work In Progress 4/30/2015 10:13:37 AM

Castillo, Carlos Company: CARVER ELECTRIC
 Contact Name: BOBBY CARVER Contact Phone: (575)527-2127
 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142
 Cell Phone: (575)644-4313 Email: carver@carverelectric.com

Location of Work: SPOT PER WORK PLAN

Dominique Esparza

132906 5/14/2015 4 \$0.00

Medium Work In Progress 5/14/2015 1:29:46 PM

Castillo, Carlos CARVER ELECTRIC
 BOBBY CARVER (575)527-2127

SPOT PER WORK PLAN

Alfredo Holguin

132953 5/15/2015 3 \$0.00

Medium Work In Progress 5/15/2015 7:47:13 AM

Castillo, Carlos Check school during and after power outage.

Carlos Castillo

132214 5/3/2015 5/24/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:37 AM

Orozco, Daniel Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

5/18/2015 9:32:29 AM

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|--|--|--|-----------------------|-----------|-----|--|--------|
| Location: | | Desert View ES | | | | | | | |
| 132358 | | | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 10:32:36 AM | | | | |
| Orozco, Daniel | | REACH IN REGRIGERATOR IS NOT COOLING. SNP MANAGER ELIZABETH D. 589.2425 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 122564 | | | | | 9/10/2014 | | 250 | | \$0.00 |
| Medium | Work In Progress | | | | 9/10/2014 9:42:24 AM | | | | |
| Orozco, Daniel | | THE RISE PART ON 3 COMPARTMENT SINK IS CLOGGED. SNP MANAGER ELIZABETH D. 589.2425 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132193 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:25 AM | | | | |
| Orozco, Daniel | | Monthly - Desert View ES Range Hood Cleaning - Refer to PMSchedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 123369 | | | | | 9/29/2014 | | 231 | | \$0.00 |
| Medium | Work In Progress | | | | 9/29/2014 4:01:13 PM | | | | |
| Sotelo, Enrique | | Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Alternate Phone: Best Time to Call: Fax No: Cell Phone: Pager No: Email: blanca@caliperconstoom Location of Work: LOCATE PER ZONE 1 WORK PLAN | | | | | | | |
| Dominique Esparza | | | | | | | | | |
| 131856 | | Portables | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | | | | 4/24/2015 11:40:52 AM | | | | |
| Ortiz, Ruben | | Portable inside rock wall - Clean rain gutters - pine needles | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 122783 | | Classroom | | | 9/15/2014 | | 245 | | \$0.00 |
| Medium | Work In Progress | Rm. #12 | | | 9/15/2014 3:49:22 PM | | | | |
| Ortiz, Ruben | | Take TV down and remove from classroom. (Ramos) | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|---|-----------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert View ES | | | | | | | |
| 132701 | | Classroom | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | Rm. #19 | | 5/11/2015 4:00:02 PM | | | | | |
| Ortiz, Ruben | Clear the bird's/pigeon nests located in the front of the school by the school. (Gonzalez) | | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |
| 132722 | | Classroom | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | Rm. # 19 | | 5/12/2015 10:12:59 AM | | | | | |
| Ortiz, Ruben | Please move the following items to Sunland Park, Rm. 204: Tall 2 door cabinet, 4 Drawer Filing Cabinet, Rolling Bookshelf, 5 Boxes by the door. (All marked with bright pink labels) (Griswold) | | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |
| 132335 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:49 AM | | | | | |
| Ortiz, Ruben | Monthly - Desert View ES Monthly FE Inpsection - Refer to PMschedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132303 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:30 AM | | | | | |
| Ortiz, Ruben | Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PMschedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132304 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:30 AM | | | | | |
| Ortiz, Ruben | Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PMschedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132305 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:31 AM | | | | | |
| Ortiz, Ruben | Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PMschedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132640 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 5/10/2015 12:23:47 AM | | | | | |
| Ortiz, Ruben | Monthly - Desert View ES Playground Insp - Refer to PMschedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|--|-------------|-----------|---------------------------------|---|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert View ES | | | | | | | |
| 130847 | | | | | 4/5/2015 | 4/13/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:43 AM | | | | |
| Ortiz, Ruben | | Monthly - Desert View ES Roof Inpsection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 128601 | | | | | 2/6/2015 | | 101 | | \$0.00 |
| Medium | Work In Progress | | | | 2/6/2015 1:44:28 PM | | | | |
| Ortiz, Ruben | | The upper level playground valve no. 1 is not working; need it fixed. | | | | 4/28/15 - Asp A. Vallejo, route to Bldg Mechanic. | | | |
| Ruben Ortiz | | | | | | | | | |
| Count: 54 Work Orders | | Avg. Age of WO's | | 36 | Total for Desert View ES | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|---|-------------|-------------|----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 130565 | | | | | 3/25/2015 | | 54 | | \$0.00 |
| Medium | Work In Progress | | | 3/25/2015 9:07:22 AM | | | | | |
| Ronquillo, Ruben | AMERICAN FENCE-RELOCATE FENCE DOOR AT MORGAN BUILDING. | | | | | | | | |
| Joe Ontiveros | | | | | | | | | |
| 129618 | | | | | 3/2/2015 | | 77 | | \$0.00 |
| Medium | Work In Progress | | | 3/2/2015 8:00:59 AM | | | | | |
| Moncayo, Fernando | AS PER MARY CHAVEZ, RR IN FRONT OF RECEPTIONIST AREA- SEALS ARE LEAKING. | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 130798 | | | | | 4/5/2015 | 4/21/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 4/5/2015 12:29:17 AM | | | | | |
| Moncayo, Fernando | Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PMSchedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132240 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:53 AM | | | | | |
| Moncayo, Fernando | Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132241 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:54 AM | | | | | |
| Moncayo, Fernando | Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131862 | | | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | | | 4/24/2015 1:05:27 PM | | | | | |
| Moncayo, Fernando | As per Mary Chavez, The Handicap Door Opener to enter GAC (GISD entrance) is not working! Would you please ask Fernando to fix it? We have had problems with this door before. Thank you and have a nice day! | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 131721 | | | | | 4/22/2015 | | 26 | | \$0.00 |
| Medium | Work In Progress | Federal | | 4/22/2015 8:02:25 AM | | | | | |
| Moncayo, Fernando | help needed to move furniture in the office. | | | | | | | | |
| Noemi Duron | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 131259 | | | | | 4/12/2015 | 4/28/2015 | 36 | | \$0.00 |
| Medium | Work In Progress | | | | 4/12/2015 12:23:50 AM | | | | |
| Moncayo, Fernando | | Monthly - GAC Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132829 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 2:58:53 PM | | | | |
| Moncayo, Fernando | | As per Mr. Suggs- Would you enter a work order to have the cement parking barrier put back in place? | | | | | | | |
| | | Just at the entrance to the dirt parking lots someone ran over one of the parking barriers and it now sticks out into the entrance way to the dirt lot. | | | | | | | |
| | | It has been like this for several days and at some point someone is going to hit it and damage their vehicle. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132708 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 8:09:31 AM | | | | |
| Moncayo, Fernando | | B-WING-NO ELECTRICITY IN VANESSA GARCIA OFFICE. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132633 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 5/10/2015 12:23:43 AM | | | | |
| Moncayo, Fernando | | Monthly - GAC Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132325 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:43 AM | | | | |
| Moncayo, Fernando | | Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132206 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:33 AM | | | | |
| Orozco, Daniel | | Monthly - GAC Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------|------------------|---|-------------|-------|----------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: GAC | | | | | | | | | |
| 132215 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:38 AM | | | | |
| Orozco, Daniel | | Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131328 | | | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 4/13/2015 4:03:55 PM | | | | |
| Castillo, Carlos | | Carmen Moreno office-We were asked to rearrange one of our areas and our initial cords do not reach and they keep blowing the circuit with surge protectors, so could we pretty please have Cali move the plug over and increase ampage. I spoke to him so he could give me some advice on what we needed | | | | 4/21/15 Asp Cali request, change to Project | | | |
| Maritza Gonzalez | | | | | | | | | |
| 131835 | | | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | | | | 4/24/2015 7:31:51 AM | | | | |
| Castillo, Carlos | | Project: Installation of 20amp 220volt circuit for new refrigeration unit in R.Acosta's office in B-Wing. | | | | | | | |
| Carlos Castillo | | | | | | | | | |
| 129271 | | | | | 2/25/2015 | | 82 | | \$0.00 |
| Medium | Work In Progress | | | | 2/25/2015 8:25:22 AM | | | | |
| Castillo, Carlos | | LIGHTS IN PARKING LOT ARE NOT WORKING PROPERLY. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132005 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 4/28/2015 3:51:30 PM | | | | |
| Castillo, Carlos | | ACADEMY FENCE JOE COCA (575)523-0779 | | | | | | | |
| | | SPOT AREA MARKED IN WHITE AT GATE ON W SIDE OF EXISTING CHAIN LINK FENCE AROUND MOBILE HOME AT BOTTOM OF INCLINE AT REAR OF ADDRESS. OPEN ACCESS; NO HAZARDS | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 125102 | | Hallway/Corridor | | | 11/3/2014 | | 196 | | \$0.00 |
| Medium | Work In Progress | | | | 11/3/2014 3:28:00 PM | | | | |
| Castillo, Carlos | | Check hallway dark areas for emergency lighting installation. And install where needed. | | | | | | | |
| Carlos Castillo | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: GAC | | | | | | | | | |
| 132575 | | Electrical Room | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 8:24:31 AM | | | | |
| Castillo, Carlos | | Submitt request for summer projects and general maintainance material. | | | | | | | |
| Carlos Castillo | | | | | | | | | |
| 132782 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 4:30:54 PM | | | | |
| Castillo, Carlos | | lights went off and generator kicked on. We understood Calixto computer and the copier to be on same circuit as generator. But both items turned off. please see Calixto for additional information | | | | | | | |
| Cora Ramirez | | | | | | | | | |
| 131909 | | Office | | | 4/27/2015 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 4/27/2015 12:31:04 PM | | | | |
| Gonzales, Camilo | | Deliver 9 boxes. PO# 14157446. Attn: Noemi Duron, Federal Programs. Thank you. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 132918 | | Office | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 2:34:07 PM | | | | |
| Gonzales, Camilo | | Deliver 1 box. PO# 141506851. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 130816 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:27 AM | | | | |
| Holguin, Alfredo | | Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131831 | | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 3:55:45 PM | | | | |
| Gonzales, Camilo | | Would you please put in a work order for 10 empty boxes to be picked up from the warehouse and deliver to me Lucia Almeraz Finance Department. | | | | | | | |
| | | Thank you | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------|--|-------------|-------------|----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 131984 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | 4/28/2015 3:06:37 PM | | | | | |
| Gonzales, Camilo | I need to place a work order for Camilo to bring a cart to our department from the warehouse. Teresa will let him know which cart to bring. Thank you. | | | | | | | | |
| | Anne De Los Santos | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 130144 | | | | | 3/13/2015 | | 66 | | \$0.00 |
| Medium | Work In Progress | | | 3/13/2015 3:20:53 PM | | | | | |
| Aldaz, Bobby | I need to borrow the bobcat please | | | | | | | | |
| Fernando Moncayo | | | | | | | | | |
| 132029 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | 4/29/2015 2:47:55 PM | | | | | |
| Gonzales, Camilo | ANNE DE LOS SANTOS-I need to place a work order for Tracey to forward our department 30 recycled boxes so A/P staff can send vouchers to store at the warehouse. | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 123425 | | | | | 9/30/2014 | | 230 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2014 3:42:13 PM | | | | | |
| , | PROJECT MANAGEMENT & FINAL CLEARANCE FOR ASBESTOS ABATEMENT AT GAC - RESTROOM IN "A" WING | | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 131690 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | 4/21/2015 3:22:11 PM | | | | | |
| Ontiveros, Guadalupe | irrigation timer for the front area is not following the program | | | | | | | | |
| Fernando Moncayo | | | | | | | | | |
| 119230 | | | | | 7/9/2014 | | 313 | | \$0.00 |
| Medium | Work In Progress | | | 7/9/2014 2:40:00 PM | | | | | |
| Ambriz, Jose | As per Mr. Steve Suggs, he would like a wall a/c unit installed in Richard Acosta and Priscilla Escobar office. | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 125499 | | | | | 11/13/2014 | | 186 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2014 9:12:15 AM | | | | |
| Ambriz, Jose | | REPLACE UNIT IN KITCHEN AREA. LEAKING FROM COMPRESSOR SECTIONG. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132051 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 3:39:40 PM | | | | |
| Ambriz, Jose | | the a/c unit in the server room making some strange noises. please check asap | | | | | | | |
| | | THANK YOU | | | | | | | |
| Cora Ramirez | | | | | | | | | |
| 132006 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 4/28/2015 3:52:09 PM | | | | |
| Ontiveros, Joe | | ACADEMY FENCE JOE COCA (575)523-0779 | | | | | | | |
| | | SPOT AREA MARKED IN WHITE AT GATE ON W SIDE OF EXISTING CHAIN LINK FENCE AROUND MOBILE HOME AT BOTTOM OF INCLINE AT REAR OF ADDRESS. OPEN ACCESS; NO HAZARDS | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 128148 | | | | | 1/30/2015 | | 108 | | \$0.00 |
| Medium | Work In Progress | | | | 1/30/2015 11:31:18 AM | | | | |
| Ontiveros, Joe | | A-WING, WOMENS RR BACKING UP. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 129266 | | Hallway/Corridor | | | 2/25/2015 | | 82 | | \$0.00 |
| High | Work In Progress | | | | 2/25/2015 7:53:29 AM | | | | |
| Estrada, Jesus | | Hallway exit inside Human Resources hallway tiles are coming loose. | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 126413 | | | | | 12/9/2014 | | 160 | | \$0.00 |
| Medium | Work In Progress | | | | 12/9/2014 1:10:45 PM | | | | |
| Munoz, Michael | | AS PER MR. CHAVEZ, WEST WALL AT PRE-K BETWEEN WINDOWS/GENERATOR NEEDS TO BE REPAIRED. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|--|-------------|-------|-----------------------|----------------------|-----------|---------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 130835 | | | | | 4/5/2015 | 4/26/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:37 AM | | | | |
| Munoz, Michael | | Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132808 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 9:28:15 AM | | | | |
| Lara, Ralph | | Please retrieve and store doors from GAC that were removed from new office to be used later. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 130495 | | Parking Lot | | | 3/24/2015 | | 55 | | \$0.00 |
| Medium | Work In Progress | | | | 3/24/2015 7:59:20 AM | | | | |
| Lara, Ralph | | NEED SIX PADLOCKS FOR PRE-K AND FRONT GATES. | | | | | | | |
| Ralph Lara | | | | | | | | | |
| 129344 | | | | | 2/26/2015 | | 81 | | \$0.00 |
| Medium | Work In Progress | | | | 2/26/2015 12:03:46 PM | | | | |
| Flores, Pete | | need a d110 lawn tractor | | | | | | | |
| Fernando Moncayo | | | | | | | | | |
| Count: 41 Work Orders | | Avg. Age of WO's | 55 | | | Total for GAC | 0 | \$0.00 | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: GAC - Pre-K | | | | | | | | | |
| 127302 | | Cafeteria | | | 1/9/2015 | | 129 | | \$0.00 |
| Medium | Work In Progress | | | | 1/9/2015 2:40:16 PM | | | | |
| Ontiveros, Joe | | We need our small sink in our cafeteria replaced with a large deep utility/kitchen sink with counters and cabinets. | | | | | | | |
| Leticia Tangonan | | | | | | | | | |
| 131431 | | Classroom | | | 4/15/2015 | | 33 | | \$0.00 |
| Medium | Work In Progress | 102 | | | 4/15/2015 10:19:51 AM | | | | |
| Ontiveros, Joe | | flapper in toilet needs to be replaced in room 102- | | | | | | | |
| Leticia Tangonan | | | | | | | | | |
| 132083 | | Cafeteria | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 8:56:11 AM | | | | |
| Marquez, Gerardo | | Please install cabinets and counter top. Prep counter for sink. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 130568 | | Kitchen | | | 3/25/2015 | | 54 | | \$0.00 |
| Medium | Work In Progress | | | | 3/25/2015 9:31:02 AM | | | | |
| Castillo, Carlos | | provide electrical outlet for garbage disposal for new counter to be installed. Also make sure we will have outlets above counter. If none are present install this also. Counter is on order so this work needs to be done before counter arrives. | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 132410 | | Office | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 7:44:52 AM | | | | |
| Castillo, Carlos | | Need to relocate electrical outlet on wall where shelves will be installed. | | | | | | | |
| Carlos Castillo | | | | | | | | | |
| 128085 | | Classroom | | | 1/29/2015 | | 109 | | \$0.00 |
| Medium | Work In Progress | 103 | | | 1/29/2015 9:58:09 AM | | | | |
| Moncayo, Fernando | | We need a pencil sharpener installed in room 103 | | | | | | | |
| Leticia Tangonan | | | | | | | | | |
| 127751 | | Classroom | | | 1/21/2015 | | 117 | | \$0.00 |
| Medium | Work In Progress | 101 | | | 1/21/2015 10:19:18 AM | | | | |
| Moncayo, Fernando | | please install pencil sharpener in room 101 | | | | | | | |
| Leticia Tangonan | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|-------------------------|-------------|-----------|------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: GAC - Pre-K | | | | | | | | | |
| 132432 | | Classroom | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | 101 | | | 5/5/2015 2:43:58 PM | | | | |
| Moncayo, Fernando please replace flickering light bulbs in room 101 and also add more light bulbs in her classroom. | | | | | | | | | |
| Leticia Tangonan | | | | | | | | | |
| 131080 | | Classroom | | | 4/8/2015 | | 40 | | \$0.00 |
| Medium | Work In Progress | 202 | | | 4/8/2015 8:13:21 AM | | | | |
| Moncayo, Fernando Please assemble our loft in room 202- Teacher Ms. Sylvia will let you know where to put it. | | | | | | | | | |
| Leticia Tangonan | | | | | | | | | |
| 128682 | | Office | | | 2/9/2015 | | 98 | | \$0.00 |
| Medium | Work In Progress | work room | | | 2/9/2015 3:36:29 PM | | | | |
| Moncayo, Fernando We received our multimedia work station and needs to be assembled. | | | | | | | | | |
| Leticia Tangonan | | | | | | | | | |
| 128684 | | | | | 2/9/2015 | | 98 | | \$0.00 |
| Safety | Work In Progress | playground | | | 2/9/2015 3:38:31 PM | | | | |
| Moncayo, Fernando The screw holding slide to the structure is coming off (loose). | | | | | | | | | |
| Leticia Tangonan | | | | | | | | | |
| 130676 | | | | | 3/27/2015 | | 52 | | \$0.00 |
| Medium | Work In Progress | | | | 3/27/2015 3:32:07 PM | | | | |
| Moncayo, Fernando AS PER JOSE ONTIVEROS, REPAIR HOLE IN PRE-K LOUNGE. | | | | | | | | | |
| Joe Ontiveros | | | | | | | | | |
| 127305 | | Athletic Field | | | 1/9/2015 | | 129 | | \$0.00 |
| Medium | Work In Progress | playground | | | 1/9/2015 2:50:09 PM | | | | |
| Gonzalez, Salvador Morgan building, where playground equipment is stored needs a ramp to facilitate/easy access to trikes. Morgan building where playground equipment is stored needs a ramp to make for easy access to trikes, wagons and other playground toys. | | | | | | | | | |
| Leticia Tangonan | | | | | | | | | |
| Count: 13 Work Orders | | Avg. Age of WO's | | 69 | Total for GAC - Pre-K | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--|------------------|----------------|-------------|----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden ES | | | | | | | | | |
| 132518 | | Classroom | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | 303 | | 5/7/2015 10:43:47 AM | | | | | |
| Ronquillo, Ruben | | | | | | | | | |
| Need assistance with broken windows.. windows from door are broken need to be replaced asap...thank you.... | | | | | | | | | |
| Loraine Gandara | | | | | | | | | |
| 132911 | | Classroom | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | 204 | | 5/14/2015 1:40:05 PM | | | | | |
| Marquez, Gerardo | | | | | | | | | |
| need assistance...door know is broken (outside) having a hard time to lock...need immidate assistance thank you.... | | | | | | | | | |
| Loraine Gandara | | | | | | | | | |
| 122297 | | Athletic Field | | | 9/4/2014 | | 256 | | \$0.00 |
| High | Work In Progress | | | 9/4/2014 9:12:27 AM | | | | | |
| Appelzoller, Fred | | | | | | | | | |
| need to cut weeds through out site, inside and outside of fence. also the weeds that have been killed with round up need to be cut as well. school is in dire need of weed control. need to include ponds. | | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 132469 | | | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | 5/6/2015 11:29:42 AM | | | | | |
| Sotelo, Enrique | | | | | | | | | |
| Need to setup electricity for Fiesta at 7am on Friday, May 8, 2015. | | | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 127977 | | Mechanical | | | 1/27/2015 | | 111 | | \$0.00 |
| Medium | Work In Progress | | | 1/27/2015 8:04:13 AM | | | | | |
| Sotelo, Enrique | | | | | | | | | |
| need electrical outlets in Mech room | | | | | | | | | |
| Fred Appelzoller | | | | | | | | | |
| 132250 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:59 AM | | | | | |
| Appelzoller, Fred | | | | | | | | | |
| Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PMschedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132253 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:01 AM | | | | | |
| Appelzoller, Fred | | | | | | | | | |
| Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PMschedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden ES | | | | | | | | | |
| 132254 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:01 AM | | | | |
| Appelzoller, Fred | | Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132231 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:48 AM | | | | |
| Appelzoller, Fred | | Monthly - Gadsden ES - Roof Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131860 | | Football Field | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | | | | 4/24/2015 12:41:09 PM | | | | |
| Appelzoller, Fred | | need assistance...one of the swings split in half.... we are requesting for it to be replaced or removed...don't want our students to be injured with this...thank you greatly..... | | | | | | | |
| Loraine Gandara | | | | | | | | | |
| 128954 | | | | | 2/17/2015 | | 90 | | \$0.00 |
| Medium | Work In Progress | | | | 2/17/2015 10:26:40 AM | | | | |
| Appelzoller, Fred | | The outside shade north of the school building is rusted. (not sure if there are one or two) both if there are two. It needs to be clean, primed and paint all of the rustic areas. He said, if you look up at it you can see the rust, all must be cleaned, primed and repainted. | | | | | | | |
| Richard Chavez | | | | | | | | | |
| 132323 | | | | | 5/3/2015 | 5/14/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:41 AM | | | | |
| Appelzoller, Fred | | Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132632 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 5/10/2015 12:23:43 AM | | | | |
| Appelzoller, Fred | | Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden ES | | | | | | | | | |
| 132591 | | | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 12:25:30 PM | | | | |
| Appelzoller, Fred | | FLOOR DRAINS BACKING UP IN DISHWASHER AREA. SNP MANAGER EVA M. 882.3410 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132207 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:33 AM | | | | |
| Orozco, Daniel | | Monthly- Gadsden ES - Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132208 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:34 AM | | | | |
| Orozco, Daniel | | Monthly- Gadsden ES - Fire Suppression Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 123039 | | Parking Lot | | | 9/23/2014 | | 237 | | \$0.00 |
| Medium | Work In Progress | | | | 9/23/2014 8:35:17 AM | | | | |
| Sotelo, Enrique | | need for the lights to be replaced outside in the parking lot...greatly appreciate your assistance | | | | | | | |
| Loraine Gandara | | | | | | | | | |
| 128647 | | | | | 2/9/2015 | | 98 | | \$0.00 |
| Medium | Work In Progress | | | | 2/9/2015 7:43:31 AM | | | | |
| Orozco, Daniel | | ICE MACHINE DOWN. SNP MANAGER EVA M. 882.3410 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132470 | | | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 11:30:41 AM | | | | |
| Carrasco, Danny | | Need to setup for Fiesta at 7am on Friday, May 8, 2015. Danny M and Danny V will assist. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 132727 | | Custodial | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 10:46:20 AM | | | | |
| Carbajal, Jimmy | | vacuum cleaner is broken | | | | | | | |
| Jose Pinon | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|--|-------------|-------|-----------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden ES | | | | | | | | | |
| 132404 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 12:24:19 AM | | | | |
| Apodaca, Mario | | Monthly - Gadsden ES - Domestic Water Filter - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132071 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 12:36:43 AM | | | | |
| Apodaca, Mario | | Monthly - Gadsden ES - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130852 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:46 AM | | | | |
| Villalobos, Margret | | Monthly - Gadsden ES - Enviro Controls Quarterly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 23 Work Orders | | Avg. Age of WO's 46 | | | Total for Gadsden ES | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|--------|--|--|--|--|----------|--|----|--|--------|
| 130969 | | | | | 4/5/2015 | | 43 | | \$0.00 |
|--------|--|--|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/5/2015 12:30:50 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, Margret Monthly - Gadsden HS - Enviro Controls Quarterly - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|--------|--|--|--|--|----------|--|----|--|--------|
| 130808 | | | | | 4/5/2015 | | 43 | | \$0.00 |
|--------|--|--|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/5/2015 12:29:23 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Flores, Pete Monthly - GHS-UV-0515 PM Service - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|-----|--|--------|
| 119630 | | | | | 7/21/2014 | | 301 | | \$0.00 |
|--------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/21/2014 10:01:42 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Flores, Pete Requested by Mr. Smythe-Ag. tractor needs to be serviced. Engine oil and filter need to be replaced. Both batteries need to be replaced. Hydraulic/trans fluid and filters need to be changed/replaced. Inner and outer air filters need to be replaced. Cab fresh air filters need to be replaced. Injection pump needs to be repaired; fuel system will not hold a prime. Air filter bowl needs to be replaced as well, broken at base. All grease fittings need to be examined in order to take grease.

Velia Alarcon

| | | | | | | | | | |
|--------|--|--|--|--|----------|--|----|--|--------|
| 132460 | | | | | 5/6/2015 | | 12 | | \$0.00 |
|--------|--|--|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/6/2015 7:31:17 AM | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Holguin, Ramiro Please fill uneven area by the Nurse building where the Morgan building use to be.

Guillermo Hernandez

| | | | | | | | | | |
|--------|--|-----|--|--|-----------|--|---|--|--------|
| 132960 | | Gym | | | 5/15/2015 | | 3 | | \$0.00 |
|--------|--|-----|--|--|-----------|--|---|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/15/2015 11:23:05 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lara, Ralph please i need a key # HE200 weight room thank yuo

Luis Saucedo

| | | | | | | | | | |
|--------|--|-----|--|--|----------|--|----|--|--------|
| 132347 | | Gym | | | 5/3/2015 | | 15 | | \$0.00 |
|--------|--|-----|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/3/2015 5:40:12 PM | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Lara, Ralph please needs to changes the locks from varsity gym, boys gyms, old English gym as they going to varnish the floors needs to change the locks before may26th.

thank you

Luis Saucedo

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

132623 Parking Lot 5/8/2015 10 \$0.00

Medium Work In Progress 5/8/2015 6:35:02 PM

Lara, Ralph please I need 2 keys # F3 for my co-workers to open the gates in morning one key for Saul and did other for Rudy.

thank you

Luis Saucedo

132755 5/12/2015 6 \$0.00

Medium Work In Progress 5/12/2015 3:22:34 PM

Lara, Ralph Need to install two kick plates to doors in the swimming pool.

Guillermo Hernandez

132797 5/13/2015 5 \$0.00

Medium Work In Progress 5/13/2015 8:07:57 AM

Lara, Ralph Need to adjust all the inside doors going in to the Gym at the V. Gym and install door stopper to prevent damaging doors.

Guillermo Hernandez

132367 5/4/2015 14 \$0.00

Medium Work In Progress 5/4/2015 11:46:46 AM

Lara, Ralph Requested by Velia-Three HE23 keys are needed for room # 605 of the Science Building.

Velia Alarcon

132422 5/5/2015 13 \$0.00

Medium Work In Progress 5/5/2015 10:32:04 AM

Lara, Ralph need key for gate by north west corner for El Paso Disposal. o.k. as per Alfredo (will turn in HE157)

Mary Sitters

130496 3/24/2015 55 \$0.00

Medium Work In Progress 3/24/2015 8:44:57 AM

Lara, Ralph NEED GATE KEY TO ISSUE TO EL PASO DISPOSAL, O.K. ASP ALFREDO.

Mary Sitters

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

131136 4/9/2015 39 \$0.00

Medium Work In Progress 4/9/2015 8:34:19 AM

Lara, Ralph For GHS room 518 please order and install an "Electronic Delayed Egress Panic (self-contained) with 15 second delay" panic bar at the main door. For More details please visit with Mr. Thomas Martin at GHS or contact Mr. Ralph Gallegos at 575- 882-6921. Thank You

Dominique Esparza

132019 4/29/2015 19 \$0.00

Medium Work In Progress 4/29/2015 9:43:02 AM

Lara, Ralph Requested by Velia-Four HE33 keys are needed for room # 110 in the Main Building. A pilot migrant program for parents will begin and keys are needed for the teachers who will be having the classes.

Velia Alarcon

131980 4/28/2015 20 \$0.00

Medium Work In Progress 4/28/2015 2:46:08 PM

Lara, Ralph Requested by Mr. Gonzales Rm. 509 CTE Building- Classroom key does not open Teacher's Lounge in the CTE Building. Teacher needs access to the Xerox Copier in lounge.

Velia Alarcon

131981 4/28/2015 20 \$0.00

Medium Work In Progress 4/28/2015 2:48:54 PM

Lara, Ralph Requested by Mr. Rivas for Portable # 9-Connecting door in the portable needs to be keyed to Mr. Rivas classroom key. Items have been taken from teachers classroom and he needs to secure his classroom. SEE MR. RIVAS FOR KEY.

Velia Alarcon

131976 4/28/2015 20 \$0.00

Medium Work In Progress 4/28/2015 1:39:05 PM

Lara, Ralph PLEASE REPLACE DOOR HARDWARE ON THE SMALL 10 X 12 PORTABLE THAT IS CURRENTLY LOCATED AT GHS NEAR THE NURSES' OFFICE THAT WILL BE MOVED TO PPD. SHOULD YOU HAVE ANY QUESTIONS PLEASE CONTACT MR. RALPH GALLEGOS AT 575-882-6921 IN THE CONSTRUCTION OFFICE. THANK YOU

Dominique Esparza

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|---------------------|------------------|---|--|--|-----------------------|--|----|--|--------|
| Location: | | Gadsden HS | | | | | | | |
| 132711 | | Custodial | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 8:32:48 AM | | | | |
| Lara, Ralph | | please I need 1keyHE 252 to open the office in morning thank you | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 132962 | | Storage | | | 5/15/2015 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | | 5/15/2015 11:25:03 AM | | | | |
| Lara, Ralph | | please i need akey# HE133 to open the storage. thank you | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 130669 | Grounds Shop | Exterior | | | 3/27/2015 | | 52 | | \$0.00 |
| Medium | Work In Progress | | | | 3/27/2015 2:48:02 PM | | | | |
| Sanchez, Raul | | 03/27/15 The wastewater techs need the assistance of an electrician & a welder's winch truck to help us disconnect a burned -out blower motor, lift it out & put new motor in place. ASAP | | | | | | | |
| Raul Sanchez | | | | | | | | | |
| 131478 | Pool Pump | Pool | | | 4/16/2015 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 4/16/2015 9:59:37 AM | | | | |
| Sanchez, Raul | | Annual Pool Start-up Project; approx. 3 weeks to get pool, dressing room building, pool water chemistry, pool safety equipment & pool pump room ready for inspection on 5/14/2015. Water techs to use same work order, thanks | | | | | | | |
| Raul Sanchez | | | | | | | | | |
| 132079 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 12:36:47 AM | | | | |
| Sanchez, Raul | | Monthly - Gadsden HS - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 128889 | | | | | 2/13/2015 | | 94 | | \$0.00 |
| Medium | Work In Progress | | | | 2/13/2015 7:51:06 AM | | | | |
| Lara, Ralph | | Rafa, we need 24 door stops the ones that we talked about to prevent the V. Gym doors from being damaged. | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 128733 | | | | | 2/10/2015 | | 97 | | \$0.00 |
| Medium | Work In Progress | | | | 2/10/2015 1:36:34 PM | | | | |
| Lara, Ralph | | Requested by Ms. Scott-Mailbox # 84 is not opening easily with the key assigned to the teacher or the spare in the key box. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 129123 | Pool Pump | Pool | | | 2/20/2015 | | 87 | | \$0.00 |
| Medium | Work In Progress | | | | 2/20/2015 2:50:50 PM | | | | |
| Apodaca, Mario | | Need to order wind screen to install is a canopy for shade on pool deck for this coming season | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 131751 | Pool Pump | Pump House | | | 4/22/2015 | | 26 | | \$0.00 |
| Medium | Work In Progress | | | | 4/22/2015 3:41:15 PM | | | | |
| Apodaca, Mario | | need to order lifeguards chairs caover to get the sunlight off the chairs | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 129446 | | | | | 2/28/2015 | | 79 | | \$0.00 |
| Medium | Work In Progress | | | | 2/28/2015 12:34:54 AM | | | | |
| Munoz, Michael | | Yearly - Gadsden HS - Fire Pump Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132381 | Pool Pump | Pump House | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 3:28:09 PM | | | | |
| Apodaca, Mario | | the pump motor is getting too hot need to ck the power going to motor | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 126410 | | Classroom | | | 12/9/2014 | | 160 | | \$0.00 |
| Medium | Work In Progress | | | | 12/9/2014 11:45:08 AM | | | | |
| Munoz, Michael | | could you please services all sewing machines in the sewing lab. thank you | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 132599 | Main Building | Pump House | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 2:33:38 PM | | | | |
| Apodaca, Mario | | routine domestic distribution system (LEAD AND CAPPER) in june 01 to july 30 2015 | | | | | | | |
| Mario Apodaca | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| Location: Gadsden HS | | | | | | | | | |
|---|------------------|------------|--|--|----------------------|--|-----|--|--------|
| 132600 | Old English Bldg | Pump House | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 2:37:33 PM | | | | |
| Apodaca, Mario routine domestic distribution system water sampling for (HAA5-IND-DS) in july 01 to 31- 2015 | | | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 132601 | Main Building | Pump House | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 2:41:47 PM | | | | |
| Apodaca, Mario routine domestic distribution system water sampling for (TTHM-ING-DS) IN AUGUST 01 TO 31- 2015 | | | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 131301 | Pool Pump | Pump House | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 4/13/2015 2:38:50 PM | | | | |
| Apodaca, Mario need to replacethe life guard rescue tude at the ghs pool | | | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 131502 | Pool Pump | Pump House | | | 4/16/2015 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 4/16/2015 3:12:31 PM | | | | |
| Apodaca, Mario the backfiow preventer leaking water at the pool pump room | | | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 129406 | Pool Pump | Pump House | | | 2/27/2015 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | | 2/27/2015 2:57:02 PM | | | | |
| Apodaca, Mario need to order pool water testing chemicals and pool supplies | | | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 130840 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:40 AM | | | | |
| Munoz, Michael Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PMs schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 127810 | | | | | 1/22/2015 | | 116 | | \$0.00 |
| Medium | Work In Progress | | | | 1/22/2015 2:52:14 PM | | | | |
| Munoz, Michael Could you please purchase new sewing machines for new sewing lab. Purchase 4 | | | | | | | | | |
| Michael Munoz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 132371 | | | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 12:56:59 PM | | | | |
| Apodaca, Mario | | Requested by Mrs. Hamilton for Greenhouse in CTE Building-Filtering system for the greenhouse due to salt build up and pump failure for cooling system. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 131206 | | | | | 4/10/2015 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 4/10/2015 2:54:03 PM | | | | |
| Apodaca, Mario | | GHS annual pool inspection for 2015 | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 128750 | | | | | 2/10/2015 | | 97 | | \$0.00 |
| Medium | Work In Progress | | | | 2/10/2015 3:38:06 PM | | | | |
| Ambriz, Jose | | Need some assistance on looking for Freon leak in walk in freezer in flower shop. | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| 130991 | | Gym | | | 4/6/2015 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | | 4/6/2015 11:33:56 AM | | | | |
| Estrada, Jesus | | varnish (3) gym floors | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 130538 | | | | | 3/24/2015 | | 55 | | \$0.00 |
| Medium | Work In Progress | | | | 3/24/2015 3:48:26 PM | | | | |
| Ambriz, Jose | | Need assistance to trouble shoot dampers for the V. Gym, having problems with the west side heating units. | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 131325 | | | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 4/13/2015 3:53:02 PM | | | | |
| Ambriz, Jose | | Need assistance to replace high voltage/3 ph motor for the commercial A/C unit #5. cafeteria area. | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 132372 | | | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 12:58:55 PM | | | | |
| Ambriz, Jose | | Requested by Mrs. Hamilton for Greenhouse in CTE Building-Pump for cooling system in the greenhouse went out. Please order two extra pumps for emergency. | | | | | | | |
| Velia Alarcon | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

132399 5/4/2015 14 \$0.00

High Work In Progress 5/4/2015 3:57:12 PM

Ambriz, Jose
Need to replace gasket on hot water supplyline for the CTE building, pumps turned off and valves turned off also. The leak is above office of the manufacturing shop.

Guillermo Hernandez

132459 5/6/2015 12 \$0.00

Medium Work In Progress 5/6/2015 7:27:12 AM

Ambriz, Jose
Compressor in the H/C unit for the band room is short cycling.

Guillermo Hernandez

127137 1/6/2015 132 \$0.00

Medium Work In Progress 1/6/2015 3:36:00 PM

Marquez, Gerardo
Requested by Mr. Enriquez Rm. 500 New CTE Building- Need to level floor in shop to install a twin port lift.

Velia Alarcon

131307 4/13/2015 35 \$0.00

Medium Work In Progress 4/13/2015 3:18:17 PM

Ontiveros, Guadalupe
Requested by Mr. Dickson-ATTENTION LUPE ONTIVEROS. We need bleachers to be transported from different schools for the "Every 15 Minutes" presentation by or before April 29, 2015.

Velia Alarcon

122352 9/4/2014 256 \$0.00

Medium Work In Progress 9/4/2014 3:46:33 PM

Ontiveros, Guadalupe
Need to replace about 200 ft. of 3 ft. high fence on the foot ball field visitors side, fence is facing the football field. Safety issue.

Guillermo Hernandez

131235 4/12/2015 4/28/2015 36 \$0.00

Medium Work In Progress 4/12/2015 12:23:37 AM

Holguin, Isaac
Monthly - QRTLTY BLDG INSP REPORT (GH) - Refer to PMs schedule details.

Margret Villalobos

123810 Library Library 10/7/2014 223 \$0.00

Medium Work In Progress 10/7/2014 12:59:31 PM

Estrada, Jesus
Requested by Matt Grubaugh for Library-The carpet in the library continues to come up. He's afraid students are going to trip on it and hurt themselves. 3/18/15 - ASP CHUY, WAITING ON QUOTE FROM CASY CARPETS

Velia Alarcon

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|-------------|--|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 132480 | | | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 3:29:51 PM | | | | |
| Villalobos, David | | Emergency | Need some assistance on clogged sinks in east wing classroom in cafeteria, Ladies restroom. | | | | | | |
| Arturo Nunez | | | | | | | | | |
| 132991 | Boys Gym | Restroom | | | 5/17/2015 | | 1 | | \$0.00 |
| Medium | Work In Progress | | | | 5/17/2015 4:24:57 PM | | | | |
| Villalobos, David | | | please on the north side boys restrooms the urinal is clogged and over flows i tried to uncloged but no luck thank you | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 127152 | | | | | 1/6/2015 | | 132 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2015 3:58:15 PM | | | | |
| Villalobos, David | | | Requested by Mr. G. Jordan for Portable # 10-Toilet is running continuously and not working. | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 130069 | | | | | 3/12/2015 | | 67 | | \$0.00 |
| Medium | Work In Progress | | | | 3/12/2015 7:40:04 AM | | | | |
| Villalobos, David | | | Need assistance or small drain snake to unclog sinks in the weight room girls restroom and testing room girls restroom east wing of the cafeteria. | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 124485 | | | | | 10/22/2014 | | 208 | | \$0.00 |
| Medium | Work In Progress | | | | 10/22/2014 3:49:00 PM | | | | |
| Villalobos, David | | | Need to replace vandalize sink faucet in Science #600, Lilly Chavez. | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 125480 | | | | | 11/13/2014 | | 186 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2014 7:40:30 AM | | | | |
| Villalobos, David | | | Need assistance to repair water leak by the water fountain in the Old English first floor. | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 125481 | | | | | 11/13/2014 | | 186 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2014 7:42:20 AM | | | | |
| Villalobos, David | | | Need assistance to unclog sink in the weight room, need drain snake. | | | | | | |
| Guillermo Hernandez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-------|-----------------------|-----------------------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 125482 | | | | | 11/13/2014 | | 186 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2014 7:43:50 AM | | | | |
| Villalobos, David | | Need assistance to unclog sink in the girls restroom at the east wing (testing room) of the cafeteria, Need drain snake. | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 132089 | | Office | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 10:47:53 AM | | | | |
| Gonzales, Camilo | | Deliver 1 cabinet. PO# 141507118. PO# 141507118. Attn: Debbie Hartmann. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 130815 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:26 AM | | | | |
| Holguin, Alfredo | | Monthly - Gadsden HS - Fire Pump Engine - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130810 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:24 AM | | | | |
| Holguin, Alfredo | | Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 126221 | | Dressing Room | | | 12/4/2014 | | 165 | | \$0.00 |
| Medium | Work In Progress | | | | 12/4/2014 9:06:09 AM | | | | |
| Nunez, Arturo | | Requested by Coach J. Vasquez for Football Locker Rooms in Boy's Gym-Fix Lockers. | | | | Summer Project asp report 3/11/15 | | | |
| Velia Alarcon | | | | | | | | | |
| 126051 | Boys Gym | Dressing Room | | | 12/1/2014 | | 168 | | \$0.00 |
| Medium | Work In Progress | Boys Football | | | 12/1/2014 1:35:09 PM | | | | |
| Nunez, Arturo | | Requested by Coach J. Vasquez for Football Locker Room in Boy's Gym-Painting of both locker rooms. | | | | Summer Project asp report 3/11/15 | | | |
| Velia Alarcon | | | | | | | | | |
| 132234 | | | | | 5/3/2015 | 5/6/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:50 AM | | | | |
| Nunez, Arturo | | Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|--------|----------------|--|--|--|----------|--|----|--|--------|
| 131160 | North Building | | | | 4/9/2015 | | 39 | | \$0.00 |
|--------|----------------|--|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/9/2015 3:45:57 PM | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Nunez, Arturo
Requested by Mrs. Munoz Rm. 210 North Building- Spikes are needed for exterior light of back door. Birds are roasting on light and leaving a mess on the back door.

Velia Alarcon

| | | | | | | | | | |
|--------|---------------|--|--|--|-----------|--|-----|--|--------|
| 121848 | Academic Bldg | | | | 8/27/2014 | | 264 | | \$0.00 |
|--------|---------------|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/27/2014 2:30:48 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Nunez, Arturo
Please replace all window screens.

Michael Munoz

| | | | | | | | | | |
|--------|--|-------------|--|--|----------|--|----|--|--------|
| 131091 | | Parking Lot | | | 4/8/2015 | | 40 | | \$0.00 |
|--------|--|-------------|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/8/2015 10:40:19 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Nunez, Arturo
Requested by Mr. D. Martinez for Fence Along the South Side of the Fence-Requesting to paint the curb along the fence line on the south side of campus. This will be a no parking zone. At this time there are many cars parking on this side and this is creating a safety hazard on campus.

Velia Alarcon

| | | | | | | | | | |
|--------|--|--|--|--|----------|--|----|--|--------|
| 132277 | | | | | 5/3/2015 | | 15 | | \$0.00 |
|--------|--|--|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/3/2015 12:33:15 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Nunez, Arturo
Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|--------|--|--|--|--|----------|----------|----|--|--------|
| 132272 | | | | | 5/3/2015 | 6/3/2015 | 15 | | \$0.00 |
|--------|--|--|--|--|----------|----------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/3/2015 12:33:12 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Nunez, Arturo
Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|--------|--|--|--|--|----------|-----------|----|--|--------|
| 132273 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
|--------|--|--|--|--|----------|-----------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/3/2015 12:33:12 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Nunez, Arturo
Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|---|--|--------|
| 132730 | | | | | 5/12/2015 | | 6 | | \$0.00 |
|--------|--|--|--|--|-----------|--|---|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/12/2015 11:00:24 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Nunez, Arturo
Requested by Coach Lawrence Portable # 13 & 14-An exhaust fan in restroom (heavy duty) is needed.

Velia Alarcon

5/18/2015 9:32:29 AM

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|------------------|------------------|--|--|--|----------------------|--|---|--|--------|
| 132908 | New Admin Bldg | Office | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 1:36:01 PM | | | | |
| Gonzales, Camilo | | Deliver 14 boxes. PO# 141507656. Attn: Hector Giron. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |

| | | | | | | | | | |
|------------------|------------------|---|--|--|---------------------|--|----|--|--------|
| 128646 | | | | | 2/9/2015 | | 98 | | \$0.00 |
| Medium | Work In Progress | | | | 2/9/2015 7:40:31 AM | | | | |
| Orozco, Daniel | | As per Mr. Bakers inspection report, water on floor by the 3 compartment sink (been a problem for some time). | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

| | | | | | | | | | |
|-----------------|------------------|---|--|--|---------------------|--|----|--|--------|
| 132377 | | Pool | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 2:26:09 PM | | | | |
| Carrasco, Danny | | We need several items to finish the installation of shade covers around pool deck area. They are 24 - 2.5" diameter by 5" long by 5/16" U bolt, small paint rollers (3) & 2 gallons of Thompsons Water Seal. Thanks, Raul | | | | | | | |
| Raul Sanchez | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|----------------------|-----------|----|--|--------|
| 132194 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:26 AM | | | | |
| Orozco, Daniel | | Monthly- Gadsden HS Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

| | | | | | | | | | |
|------------------|------------------|--|--|--|----------------------|--|-----|--|--------|
| 123327 | | | | | 9/26/2014 | | 234 | | \$0.00 |
| Medium | Work In Progress | | | | 9/26/2014 3:51:00 PM | | | | |
| Orozco, Daniel | | Walk-in floor has lifted – safety issue. SNP MANAGER FRANCES B. 882.5522 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

| | | | | | | | | | |
|------------------|------------------|---|--|--|-----------------------|--|-----|--|--------|
| 119747 | | | | | 7/23/2014 | | 299 | | \$0.00 |
| Medium | Work In Progress | | | | 7/23/2014 10:08:37 AM | | | | |
| Orozco, Daniel | | WARMER-OLD FAVORITES-INSIDE HAS FALLEN. SNP MANAGER FRANCES B. 882.5522 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

| | | | | | | | | | |
|-----------------|------------------|--|--|--|---------------------|--|----|--|--------|
| 132624 | | Parking Lot | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 6:41:49 PM | | | | |
| Sotelo, Enrique | | please around the parking lot is to dark can you please set timer earlier so is not so dark in the morning for safety. thank you | | | | | | | |
| Luis Saucedo | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-------|-----------------------|--|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 132216 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:39 AM | | | | |
| Orozco, Daniel | | Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 128830 | | | | | 2/12/2015 | | 95 | | \$0.00 |
| Medium | Work In Progress | | | | 2/12/2015 7:48:40 AM | | | | |
| Orozco, Daniel | | ZIA NEON AND RED AND GREEN CHILE NEON LIGHTS IN CAFETERIA ARE FLICKERING. SNP MANAGER FRANCES B. 882.5522 | | | | 2/24/15 As per Enrique, route to Danny O. | | | |
| Maritza Gonzalez | | | | | | | | | |
| 128855 | | | | | 2/12/2015 | | 95 | | \$0.00 |
| Medium | Work In Progress | | | | 2/12/2015 2:49:48 PM | | | | |
| Orozco, Daniel | | AS PER ADELES INSPECTION REPORT - GRATER ATTACHMENTS TO CHOPER DOES NOT WORK. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 122944 | | | | | 9/18/2014 | | 242 | | \$0.00 |
| Medium | Work In Progress | | | | 9/18/2014 7:38:30 AM | | | | |
| Sotelo, Enrique | | Need to replace burn out lamps on the south side of school, area by the swimming pool. This area has now 4 lights out and one by grounds. Need bucket truck. | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 119303 | Auto Shop | | | | 7/11/2014 | | 311 | | \$0.00 |
| Medium | Work In Progress | | | | 7/11/2014 12:42:51 PM | | | | |
| Sotelo, Enrique | | NEED FOR ELECTRICAL POWER TO BE INSTALLED FOR NEW LIFT. | | | | | | | |
| Gerardo Marquez | | | | | | | | | |
| 129676 | | | | | 3/3/2015 | | 76 | | \$0.00 |
| Medium | Work In Progress | | | | 3/3/2015 7:55:21 AM | | | | |
| Sotelo, Enrique | | Albert, we need assistance to replace ballasts and lamps around the CTE building and light poles to the south side of campus. We will need 400w MH large base lamps. | | | | 5/1/15 - As per A. Vallejo, route to Lorenzo | | | |
| Guillermo Hernandez | | | | | | | | | |
| 130343 | | | | | 3/19/2015 | | 60 | | \$0.00 |
| Medium | Work In Progress | | | | 3/19/2015 7:34:37 AM | | | | |
| Sotelo, Enrique | | Need to check cord reels in the welding shop, currently there are two cord reels that are not working. | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|----------------------|------------------|--|--|--|-----------------------|-----------|----|--|--------|
| Location: | | Gadsden HS | | | | | | | |
| 132793 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 7:37:48 AM | | | | |
| Sotelo, Enrique | | Please troubleshoot kitchen hood cut off system. | | | | | | | |
| 132467 | Cafeteria (1998) | | | | 5/6/2015 | | 12 | | \$0.00 |
| High | Work In Progress | | | | 5/6/2015 11:23:25 AM | | | | |
| Appelzoller, Fred | | Cafe (West Wing) - Backing up | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 131198 | Pool Dressing | Pool | | | 4/10/2015 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 4/10/2015 1:48:20 PM | | | | |
| Hernandez, Guillermo | | 4/10/15 Need bldg. mechanics help to repaint the 4 exterior doors to pool dressing rooms building in order to get ready for the annual pool inspection in May. Thanks | | | | | | | |
| Raul Sanchez | | | | | | | | | |
| 130826 | | | | | 4/5/2015 | 4/13/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:32 AM | | | | |
| Hernandez, Guillermo | | Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131949 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 4/28/2015 12:25:30 AM | | | | |
| Hernandez, Guillermo | | Daily - Gadsden HS - Fire Pump (Biweekly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131819 | | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 3:41:47 PM | | | | |
| Hernandez, Guillermo | | Please assist Dimar System to have access to building they will be performing fire sprinkler system inspection. | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 131845 | | | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | | | | 4/24/2015 10:27:48 AM | | | | |
| Hernandez, Guillermo | | Requested by Mr. Mora Rm. 403 Boy's Gym-Ice machine descale light is on, the machine needs to be cleaned. | | | | | | | |
| Velia Alarcon | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|--------|--|--|--|--|----------|--|----|--|--------|
| 130787 | | | | | 4/5/2015 | | 43 | | \$0.00 |
|--------|--|--|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/5/2015 12:29:11 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Hernandez, Guillermo Yearly - Gadsden HS A13 (Ceil/Wall Unit)(Yearly) - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|----|--|--------|
| 130342 | | | | | 3/19/2015 | | 60 | | \$0.00 |
|--------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 3/19/2015 7:30:34 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Hernandez, Guillermo Need to order 4 1/2 inch metal flushing guard for the swimming pool roof.

Guillermo Hernandez

| | | | | | | | | | |
|--------|--|--|--|--|----------|--|----|--|--------|
| 129907 | | | | | 3/9/2015 | | 70 | | \$0.00 |
|--------|--|--|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 3/9/2015 12:35:39 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Hernandez, Guillermo Monthly - Gadsden HS A16 (Fan Exh.)(S. Annual) - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|--------|--|-------------|--|--|----------|--|----|--|--------|
| 131090 | | Parking Lot | | | 4/8/2015 | | 40 | | \$0.00 |
|--------|--|-------------|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/8/2015 10:38:15 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Hernandez, Guillermo Requested by Mr. D. Martinez for Fence Along the South Side of the Fence-Requesting to have "No Parking" signs placed on the fence along the south side of campus. This will be a no parking zone. At this time there are many cars parking on this side and this is creating a safety hazard on campus.

Velia Alarcon

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|---|--|--------|
| 132932 | | | | | 5/14/2015 | | 4 | | \$0.00 |
|--------|--|--|--|--|-----------|--|---|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/14/2015 3:43:08 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Hernandez, Guillermo Please check Mrs. Bea's office #319 at the Academic building for roof leak.

Guillermo Hernandez

| | | | | | | | | | |
|--------|--|--|--|--|----------|----------|----|--|--------|
| 132324 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
|--------|--|--|--|--|----------|----------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/3/2015 12:33:42 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Hernandez, Guillermo Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|--------|--|--|--|--|----------|-----------|----|--|--------|
| 132296 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
|--------|--|--|--|--|----------|-----------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/3/2015 12:33:26 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Hernandez, Guillermo Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|--------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |

| Location: | Gadsden HS | | | | | | | | |
|----------------------|---|--|--|--|-----------------------|--|----|--|--------|
| 132491 | | | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 3:47:59 PM | | | | |
| Hernandez, Guillermo | PLease check cooling unit for Academic #311. | | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 132507 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 7:49:48 AM | | | | |
| Hernandez, Guillermo | Summer project; Check portables and repair damages, paint and change lamps. | | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 132508 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 7:50:58 AM | | | | |
| Hernandez, Guillermo | summer project; touch up walls and doors in Administration building. | | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 132385 | | | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 3:37:04 PM | | | | |
| Hernandez, Guillermo | Requested by Ms. Roth Rm. 328 Academic Building- A/C's water pump has gone out, needs to be replaced. | | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 132409 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 7:32:59 AM | | | | |
| Hernandez, Guillermo | Need to install rain cap to exhaust pipe for the fire pump size 8 5/8 inch OD. | | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 132354 | | | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 9:11:25 AM | | | | |
| Hernandez, Guillermo | Please replace missing Fire extinguisher in Science building second floor hallway. | | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 132113 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 3:49:31 PM | | | | |
| Hernandez, Guillermo | Check existing H/C units for North building. | | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 132670 | | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 11:45:43 AM | | | | |
| Hernandez, Guillermo | Please remove graffiti on walls in the Main building (New Building) by the restrooms. | | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|----------------------|------------------|---|--|--|-----------------------|---|-----|--|--------|
| Location: | | Gadsden HS | | | | | | | |
| 132603 | | | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | | | | 5/8/2015 2:56:07 PM | | | | |
| Hernandez, Guillermo | | Requested by Ms. Moreno Rm. 322 Academic Building- A/C is not working, it is running but not cooling. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 129461 | | | | | 2/28/2015 | | 79 | | \$0.00 |
| Medium | Work In Progress | | | | 2/28/2015 12:35:04 AM | | | | |
| Sanchez, Raul | | Monthly - Gadsden HS - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 128074 | | | | | 1/29/2015 | | 109 | | \$0.00 |
| Medium | Work In Progress | | | | 1/29/2015 7:46:54 AM | | | | |
| Gonzalez, Salvador | | Need to replace broken main sign pole by the flag poles. | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 132895 | | Athletic Field | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 9:22:29 AM | | | | |
| Gonzalez, Salvador | | need to weld 3 point hitch on fertilizer cone. | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 125292 | | Football Field | | | 11/7/2014 | | 192 | | \$0.00 |
| Medium | Work In Progress | | | | 11/7/2014 1:12:07 PM | | | | |
| Gonzalez, Salvador | | Coach Vasquez would like a door placed in the shower area to store some of his equipment. Door needs to be welded. | | | | | | | |
| William Dickson | | | | | | | | | |
| 131143 | Cafeteria (1998) | | | | 4/9/2015 | | 39 | | \$0.00 |
| Medium | Work In Progress | | | | 4/9/2015 11:53:50 AM | | | | |
| Ronquillo, Ruben | | Gate to Compactor is too narrow- Install additional 3 FT gate for easier access to dump trash into compactor- Check with custodial on specifics | | | | 4/9/15-route to chuy asp Alfredo; | | | |
| Alfredo Holguin | | | | | | | | | |
| | | | | | | 4/10/15 - asp per Chuy, install an extra door to make it a double door, current one is 5' 9' length x 3' wide. | | | |
| | | | | | | asp alfredo, need quote from academy fence, contact person will be chuy if they have any question; work order routed back to ruben. | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 132353 | | | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 9:07:36 AM | | | | |
| Gallegos, Rafael | | WARRANTY WORK ORDER Main Building Classroom #110 AHU-5 is not working. Computer Lab room to hot. | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 132311 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:34 AM | | | | |
| Sanchez, Raul | | Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132313 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:36 AM | | | | |
| Sanchez, Raul | | Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132863 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 12:24:25 AM | | | | |
| Sanchez, Raul | | Monthly - Gadsden HS- Filters (Pump Rm) Quarterly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129492 | | | | | 3/1/2015 | | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 3/1/2015 12:45:54 AM | | | | |
| Sanchez, Raul | | Monthly - Gadsden HS - Grease Trap (Culinary/Auto) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 125272 | | | | | 11/7/2014 | | 192 | | \$0.00 |
| Medium | Work In Progress | | | | 11/7/2014 9:03:59 AM | | | | |
| Sanchez, Raul | | Domestic Water Well #1 - install sanitary seal properly around electrical wires. | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 128198 | | | | | 1/31/2015 | | 107 | | \$0.00 |
| Medium | Work In Progress | | | | 1/31/2015 12:39:15 AM | | | | |
| Sanchez, Raul | | Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|--|-------------|-------------------------|-----------|-----------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 132070 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 12:36:42 AM | | | | |
| Sanchez, Raul | Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130935 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:30:31 AM | | | | |
| Sanchez, Raul | Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 123 Work Orders | | | Avg. Age of WO's | 61 | Total for Gadsden HS | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|--------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden MS

119660 7/21/2014 301 \$0.00

High Work In Progress 7/21/2014 3:36:20 PM

Sanchez, Raul ***The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house***

Company: CD MECHANICAL
 Contact Name: DEAN POGUE Contact Phone: (575)382-8474
 State: NM County: DONA ANA City: RURAL
 DONA ANA
 Address: 1301, WASHINGTON ST
 Nearest Intersecting Street: BERRY RD
 2nd Intersecting Street: GRACIE PL
 Subdivision: GASDEN MIDDLE SCHOOL
 Latitude: 31.99971983 Longitude: -106.63006583
 Zip Code: 88021
 Township: 26S Range: 03E Section 1/4: 34 SW

Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS. - SPOT ON THE E. SIDE OF PROPERTY, IN THE PONDING AREA BETWEEN THE WATER STORAGE TANK AND THE GYM.

Dominique Esparza

132003 4/28/2015 20 \$0.00

Medium Work In Progress 4/28/2015 3:50:53 PM

Diaz, Sebastian Need paint for locker rooms Mistaya color

Sebastian Diaz

132237 5/3/2015 5/6/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:52 AM

Diaz, Sebastian Monthly - Gadsden MS - Emerg. Eyewash (Monthly) - Refer to PMSchedule details.

Margret Villalobos

129117 C-Wing 2/20/2015 87 \$0.00

Medium Work In Progress Old Central 2/20/2015 10:55:51 AM

Diaz, Sebastian Old Central Office
 Paint newly installed doors and jams
 Paint or Repaint interior door jams white.

Margret Villalobos

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden MS

130051 Band Room 3/11/2015 68 \$0.00

Medium Work In Progress room 100 and 3/11/2015 3:42:21 PM

Diaz, Sebastian Fixhole in outside Band room wall and wall outside room 150.

Nancy Tinajero

125784 Gym 11/19/2014 180 \$0.00

Medium Work In Progress 11/19/2014 4:24:32 PM

Diaz, Sebastian Order window screens for Gym and Gym Lobby.
(See Mike)

Michael Munoz

132914 C-Wing Portables 5/14/2015 4 \$0.00

Medium Work In Progress Karen - Athletics 5/14/2015 2:05:55 PM

Diaz, Sebastian Karen Nougues, would like to see when someone could come over to help her move her furniture from her office to the new section of the Athletic Portable. Please come see her on Monday, May 18th to see what furniture she wants to move and where she wants it placed in the new area.

Thank You!

Terry Alvarado

132574 C-Wing Portables 5/8/2015 10 \$0.00

Medium Work In Progress Karen - Athletics 5/8/2015 8:04:23 AM

Diaz, Sebastian The Athletic Office would like to request the removal of some cabinets taken down from the old Transportation Office. We will be cleaning and painting out the room next week.

Thanks, Terry

Terry Alvarado

130306 Gym Gym 3/18/2015 61 \$0.00

Medium Work In Progress GYM 3/18/2015 10:47:06 AM

Diaz, Sebastian Main Basketball Goal frame is coming apart. Also check switch box for practice goal because it will not come up or down.

Nancy Tinajero

132028 Classroom 4/29/2015 19 \$0.00

Medium Work In Progress room 169 4/29/2015 1:25:59 PM

Diaz, Sebastian Varnish the split door in room 169.

Nancy Tinajero

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden MS | | | | | | | |
| 131961 | | Classroom | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | room 146 | | 4/28/2015 11:08:44 AM | | | | | |
| Diaz, Sebastian | | Air conditioner not working. Computer lab classroom get very hot in the afternoon with all computers in there. | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 132661 | | Classroom | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | room 129 | | 5/11/2015 10:05:11 AM | | | | | |
| Diaz, Sebastian | | need a door stop | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 132662 | | Classroom | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | room 129 | | 5/11/2015 10:10:17 AM | | | | | |
| Diaz, Sebastian | | Change light bulb | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 132301 | | | | | 5/3/2015 | 6/3/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:29 AM | | | | | |
| Diaz, Sebastian | | Monthly - Gadsden MS - Bleacher Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132302 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:29 AM | | | | | |
| Diaz, Sebastian | | Monthly - Gadsden MS - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132309 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:33 AM | | | | | |
| Diaz, Sebastian | | Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132310 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:34 AM | | | | | |
| Diaz, Sebastian | | Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132336 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:49 AM | | | | | |
| Diaz, Sebastian | | Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|------------------|--|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden MS | | | | | | | |
| 130574 | | Gym | | | 3/25/2015 | | 54 | | \$0.00 |
| Medium | Work In Progress | Gym | | | 3/25/2015 11:42:43 AM | | | | |
| Gonzalez, Salvador | | Please cover for switch boxes for basketball courts in gym. Please see Sebastian | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 131018 | | | | | 4/6/2015 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | | 4/6/2015 3:51:09 PM | | | | |
| Gonzalez, Salvador | | Need to replace ramp on portable C wing thank you | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 132676 | Cafeteria | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 2:08:15 PM | | | | |
| Marquez, Gerardo | | Need keys for all doors at the old SNP Offices by Cafeteria. | | | | | | | |
| Richard Chavez | | | | | | | | | |
| 132475 | | | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 12:21:25 PM | | | | |
| Sotelo, Enrique | | Need to check breaker on computer lab thank you | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 130986 | C-Wing | Classroom | | | 4/6/2015 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | | 4/6/2015 11:00:30 AM | | | | |
| Sotelo, Enrique | | Room on NE corner needs to wire as lab for computers. | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 130761 | C-Wing | | | | 3/31/2015 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | | 3/31/2015 10:26:34 AM | | | | |
| Sotelo, Enrique | | CR on NE Corner - provide outlets for computers | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 127838 | | | | | 1/23/2015 | | 115 | | \$0.00 |
| Medium | Work In Progress | | | | 1/23/2015 10:15:02 AM | | | | |
| Sotelo, Enrique | | Need to enough power for meting on cafeteria FEB 6 thank you | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 125851 | | Pump House | | | 11/21/2014 | | 178 | | \$0.00 |
| Medium | Work In Progress | | | | 11/21/2014 2:41:06 PM | | | | |
| Sotelo, Enrique | | need to pull new control wires for the switch float at the gms irrigation tank | | | | | | | |
| Mario Apodaca | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden MS | | | | | | | | | |
| 132217 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:39 AM | | | | |
| Orozco, Daniel | | Monthly - Gadsden MS Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132195 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:26 AM | | | | |
| Orozco, Daniel | | Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 127946 | | | | | 1/26/2015 | | 112 | | \$0.00 |
| Medium | Work In Progress | | | | 1/26/2015 2:43:41 PM | | | | |
| Orozco, Daniel | | MILK MACHIINE BROKEN, DOOR HANGING OFF HINGES. SNP MANAGER TERRY P. 882.2824 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132810 | C-Wing | Portables | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 9:59:50 AM | | | | |
| Carrasco, Danny | | Requesting Paint and Supplies to paint Athletic Portable, we will do the painting. | | | | | | | |
| Terry Alvarado | | | | | | | | | |
| 127753 | | | | | 1/21/2015 | | 117 | | \$0.00 |
| Medium | Work In Progress | | | | 1/21/2015 11:25:29 AM | | | | |
| Orozco, Daniel | | WALK IN FREEZER RAMP NEEDS TO BE REPAIRED, IT LIFTS AND KEEP DOOR AJAR. SNP MANAGER TERRY P. 882.2824 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 127754 | | | | | 1/21/2015 | | 117 | | \$0.00 |
| Medium | Work In Progress | | | | 1/21/2015 11:28:32 AM | | | | |
| Orozco, Daniel | | RACKS IN WARMING CABINET NEED ANCHORS RACKS ARE LOOSE AND CAN CAUSE SOMEONE TO GET BURNED. SNP MANAGER TERRY P. 882.2824 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132909 | | Office | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 1:37:19 PM | | | | |
| Gonzales, Camilo | | Deliver items from PO# 141507120. Attn: Cecilia Anzula. Thank you. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden MS

131605 C-Wing 4/20/2015 28 \$0.00

Medium Work In Progress Support 4/20/2015 3:15:58 PM

Gonzales, Camilo Request to move Support Services to Physical Plant Warehouse, new Support Services Office on 4/30/2015. Access to the offices are the first door on the right. All furniture and boxes will be labeled.

Asp Alfred, assign to Camilo

Cynthia Maes

131712 C-Wing 4/21/2015 27 \$0.00

Medium Work In Progress Transportation 4/21/2015 3:53:10 PM

Gonzales, Camilo Requesting to move Transportation on 4/30/2015. Transportation will be moving to the old Energy Office. All items will be labeled Transportation. If there are any questions please contact Lisa Sanchez - 882-6949.

Cynthia Maes

132811 C-Wing Portables 5/13/2015 5 5 \$0.00

Medium Work In Progress Karen - Athletics 5/13/2015 10:29:49 AM

Gonzales, Camilo ENRIQUE CAN YOU PLEASE DELIVER THE FOLLOWING ITEMS TO THE ATHLETIC OFFICE FOR KAREN.

PO # 141507666 - 6 STORAGE CABINETS - ATHLETIC OFFICE

Terry Alvarado

132872 5/14/2015 4 \$0.00

Medium Work In Progress NICOLE ORTIZ 5/14/2015 7:38:56 AM

Gonzales, Camilo DELIVER PO 141507435 NASCO INTERNATIONAL 6 BOXES NICOLE ORTIZ, TEACHER/GADSDEN MIDDLE SCHOOL

Margaret Villalobos

129886 3/6/2015 73 \$0.00

Medium Work In Progress 3/6/2015 3:18:16 PM

Villalobos, David Need to replace sink faucets on B wing thank you

Sebastian Diaz

124709 Gym 10/29/2014 201 \$0.00

Medium Work In Progress 10/29/2014 7:43:56 AM

Villalobos, David Urinals in boys gym locker room do not have water needs to be fixed A.S.A.P in order to clean by custodian right

Mario Herrera

5/18/2015 9:32:30 AM

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden MS | | | | | | | | | |
| 124711 | | | | | 10/29/2014 | | 201 | | \$0.00 |
| Medium | Work In Progress | | | | 10/29/2014 7:45:12 AM | | | | |
| Villalobos, David | | Sink in girls restroom next to b-wing and main hallway there is no running water | | | | | | | |
| Mario Herrera | | | | | | | | | |
| 130054 | | Restroom | | | 3/11/2015 | | 68 | | \$0.00 |
| Medium | Work In Progress | A wing boys | | | 3/11/2015 3:45:12 PM | | | | |
| Villalobos, David | | The faucet in boys restroom is continuously running. | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 131403 | | | | | 4/14/2015 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | | 4/14/2015 3:46:21 PM | | | | |
| Villalobos, David | | Need to check domestic water heater for restrooms thank you | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 121677 | | | | | 8/25/2014 | | 266 | | \$0.00 |
| Medium | Work In Progress | | | | 8/25/2014 8:10:22 AM | | | | |
| Villalobos, David | | Need o replace sink faucet on rest room A wing thank you | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 121391 | Vocational | | | | 8/19/2014 | | 272 | | \$0.00 |
| Medium | Work In Progress | | | | 8/19/2014 6:59:54 AM | | | | |
| Villalobos, David | | outside water for water hoses do not work on the whole building | | | | | | | |
| Mario Herrera | | | | | | | | | |
| 119501 | C-Wing | | | | 7/16/2014 | | 306 | | \$0.00 |
| Medium | Work In Progress | | | | 7/16/2014 3:49:11 PM | | | | |
| Villalobos, David | | Portable - Where restrooms are located. There is a leak underneath the sink, water has been shut off for now. Please check this first thing in the morning. | | | | | | | |
| Mario Herrera | | | | | | | | | |
| 124188 | | Classroom | | | 10/15/2014 | | 215 | | \$0.00 |
| Safety | Work In Progress | room 129 and | | | 10/15/2014 1:55:35 PM | | | | |
| Villalobos, David | | Water is leaking out of the wall between room 129 and 140. Computers are against that wall. Could be a severe electrical shock issue. | | | | | | | |
| Nancy Tinajero | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|-----------------------------|------------------|--|--|--|-----------------------|--|-----|--|--------|
| Location: Gadsden MS | | | | | | | | | |
| 119801 | Main Building | Classroom | | | 7/24/2014 | | 298 | | \$0.00 |
| Medium | Work In Progress | Room 152 | | | 7/24/2014 11:57:42 AM | | | | |
| Villalobos, David | | Sink is dripping continuously; doesn't drain and is leaking into the cabinet. | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 124404 | | Library | | | 10/21/2014 | | 209 | | \$0.00 |
| Medium | Work In Progress | Library | | | 10/21/2014 12:30:45 | | | | |
| Villalobos, David | | Clogged sink in library office. | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 132585 | Gym | | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | girls locker room | | | 5/8/2015 10:19:51 AM | | | | |
| Villalobos, David | | Water coming out of floor drain in Girls locker room. | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 127468 | Main Building | Hallway/Corridor | | | 1/13/2015 | | 125 | | \$0.00 |
| Medium | Work In Progress | | | | 1/13/2015 11:15:04 AM | | | | |
| Estrada, Jesus | | New to replace (VCT tile) in west wing tile is coming up and un done pieces of VCT missing | | | | | | | |
| Mario Herrera | | | | | | | | | |
| 127469 | Main Building | Hallway/Corridor | | | 1/13/2015 | | 125 | | \$0.00 |
| Medium | Work In Progress | | | | 1/13/2015 11:17:19 AM | | | | |
| Estrada, Jesus | | Need to replace VCT tile is coming up and breaking off in different sections | | | | | | | |
| Mario Herrera | | | | | | | | | |
| 127470 | Main Building | Hallway/Corridor | | | 1/13/2015 | | 125 | | \$0.00 |
| Medium | Work In Progress | | | | 1/13/2015 11:18:30 AM | | | | |
| Estrada, Jesus | | VCT tile needs to be replaced cracking and coming off | | | | | | | |
| Mario Herrera | | | | | | | | | |
| 132749 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | FOOTBALL | | | 5/12/2015 3:07:07 PM | | | | |
| Vasquez, Jose | | LUPE - KAREN WOULD LIKE TO REQUEST THAT THE GADSDEN MS FOOTBALL FIELDS BE RESEEDED AFTER SCHOOL LETS OUT IN MAY, 2015. GMS ADMINISTRATION IS AWARE THAT THE FB FIELD WILL NOT BE AVAILABLE TO THEM FROM JUNE - AUGUST. | | | | | | | |
| | | THANKS, TERRY | | | | | | | |
| Terry Alvarado | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden MS

131276 4/13/2015 35 \$0.00

Medium Work In Progress 4/13/2015 8:09:29 AM

Vasquez, Jose patches of grass behind main building "in front of portables" would like for those to be removed

Mario Herrera

131464 Gym Athletic Field 4/16/2015 32 \$0.00

Medium Work In Progress Lupe 4/16/2015 7:43:43 AM

Ontiveros, Guadalupe Lupe, can you please move the larger set of bleachers that is close to the Tennis Courts over to the area where the Parents sit.

WELDING: Also on the Bleachers that is in the Parents area: one of the bleachers seats had come off and needs to be welded back into place.

Thank you!

Terry Alvarado

131647 Gym Athletic Field 4/21/2015 27 \$0.00

Medium Work In Progress Karen - Athletics 4/21/2015 10:23:09 AM

Ontiveros, Guadalupe Gadsden MS - TENNIS COURTS - Small Fence on the East side of the courts needs to be cut down. If you have any Questions, please contact Karen in Athletics.

Thank You!

Terry Alvarado

128957 2/17/2015 90 \$0.00

Medium Work In Progress 2/17/2015 10:48:14 AM

Marquez, Gerardo Need to replace main entrance doors AB thank you

Sebastian Diaz

119973 7/29/2014 293 \$0.00

Medium Work In Progress front office- 7/29/2014 10:06:01 AM

Marquez, Gerardo Need Keys for new PE teacher, WA-62, V-8, WA-64, 01, V-15, one each please.

Nancy Tinajero

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden MS

130188 3/16/2015 63 \$0.00

Medium Work In Progress 3/16/2015 11:44:19 AM

Marquez, Gerardo AS PER THE STATE FIRE INSPECTOR PLEASE CHECK ALL EXTERIOR DOORS THROUGH OUT ENTIRE GADSDEN MIDDLE CAMPUS FOR PROPER FUNCTION. FIX ANY PROBLEMS THAT ARE FOUND. SHOULD YOU HAVE ANY QUESTIONS PLEASE CONTACT MR. RALPH GALLEGOS AT 575-882-6921 IN THE CONSTRUCTION OFFICE.

Dominique Esparza

132421 C-Wing Portables 5/5/2015 13 \$0.00

Medium Work In Progress atheltics 5/5/2015 10:20:57 AM

Marquez, Gerardo The doors in the Athletic Portable are getting stuck and do not close properly. Need someone to check them so that they close and are not left open.

Jerry is working on rekeying the doors and also noticed that they door did not close correctly, so he is working on that for us.

Thanks, Terry

Terry Alvarado

132573 C-Wing Portables 5/8/2015 10 \$0.00

Medium Work In Progress atheltics 5/8/2015 7:59:25 AM

Marquez, Gerardo Jerry, can you please make another key for the front door for the Athletic Office. I gave (1) key to Mario Herrera, Head Custodian at GMS in order for them to come over to clean the office. So then I will need one extra key for Karen Nougues.

Thanks, Terry

Terry Alvarado

131869 C-Wing 4/24/2015 24 \$0.00

Medium Work In Progress 4/24/2015 2:36:04 PM

Marquez, Gerardo Please change Support Services Office lock to open with Athletics Key ck w/Ms. Nougues.

(Wait until all of Support Services has moved out completely)

Lisa Sanchez

130992 Gym 4/6/2015 42 \$0.00

Medium Work In Progress 4/6/2015 11:35:28 AM

Estrada, Jesus varnish gym floor

Jesus Estrada

5/18/2015 9:32:30 AM

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|--|--|--|-----------------------|---|-----|--|--------|
| Location: | | Gadsden MS | | | | | | | |
| 130499 | Main Building | | | | 3/24/2015 | | 55 | | \$0.00 |
| Medium | Work In Progress | | | | 3/24/2015 8:53:00 AM | | | | |
| Estrada, Jesus | | Requesting new VTC flooring in office 168A | | | | | | | |
| Mario Herrera | | | | | | | | | |
| 130500 | Main Building | | | | 3/24/2015 | | 55 | | \$0.00 |
| Medium | Work In Progress | | | | 3/24/2015 8:54:04 AM | | | | |
| Estrada, Jesus | | Requesting new VCT Flooring in Attendance office | | | | | | | |
| Mario Herrera | | | | | | | | | |
| 130937 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:30:32 AM | | | | |
| Apodaca, Mario | | Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132315 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:37 AM | | | | |
| Apodaca, Mario | | Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 128187 | | | | | 1/31/2015 | | 107 | | \$0.00 |
| Medium | Work In Progress | | | | 1/31/2015 12:39:07 AM | | | | |
| Apodaca, Mario | | Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details. | | | | PM not performed as per schedule 2/9/15 | | | |
| Margret Villalobos | | | | | | | | | |
| 132406 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 12:24:20 AM | | | | |
| Apodaca, Mario | | Monthly - Gadsden MS - Domestic Water Filter - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 128617 | | | | | 2/6/2015 | | 101 | | \$0.00 |
| Medium | Work In Progress | | | | 2/6/2015 3:46:24 PM | | | | |
| Solis, Lorenzo | | Need to fix pump on boiler room eastside thank you | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 131833 | | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 4:25:41 PM | | | | |
| Solis, Lorenzo | | Need to replace A/C 65 SIDE DRAFT | | | | | | | |
| Sebastian Diaz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--|------------------|--------------|----------------------------|-------|-----------------------|-----------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden MS | | | | | | | | | |
| 131400 | | | | | 4/14/2015 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | | 4/14/2015 3:44:57 PM | | | | |
| Solis, Lorenzo Need to check A/C on annex bldg. thank you | | | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 125237 | Gym | | | | 11/6/2014 | | 193 | | \$0.00 |
| Medium | Work In Progress | | | | 11/6/2014 2:41:40 PM | | | | |
| Munoz, Michael The new bleachers not working on the gym thank you | | | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 132069 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 12:36:42 AM | | | | |
| Apodaca, Mario Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132072 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 12:36:43 AM | | | | |
| Apodaca, Mario Monthly - Gadsden MS - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132238 | | | | | 5/3/2015 | 5/19/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:52 AM | | | | |
| Villalobos, Margret Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132583 | Gymnasium | | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | concession | | | 5/8/2015 10:18:10 AM | | | | |
| Villalobos, Margret Spray for roaches | | | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 132584 | Gym | | | | 5/8/2015 | | 10 | | \$0.00 |
| Medium | Work In Progress | Girls Locker | | | 5/8/2015 10:18:36 AM | | | | |
| Villalobos, Margret Spray for roaches | | | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 129508 | | | | | 3/1/2015 | 3/17/2015 | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 3/1/2015 12:46:04 AM | | | | |
| Villalobos, Margret Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details. 3/2 - Emailed | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 79 Work Orders | | | Avg. Age of WO's 73 | | | Total for Gadsden MS | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: La Union ES | | | | | | | | | |
| 131299 | | | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 4/13/2015 2:24:18 PM | | | | |
| Aguilar, Patricio | | wo to myself - need to bait grounds for moles - gophers | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 129438 | | | | | 2/28/2015 | 3/31/2015 | 79 | | \$0.00 |
| Medium | Work In Progress | | | | 2/28/2015 12:34:49 AM | | | | |
| Aguilar, Patricio | | Yearly - La Union ES C-11 Evap Coolers Yearly - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129234 | | | | | 2/24/2015 | | 83 | | \$0.00 |
| Medium | Work In Progress | | | | 2/24/2015 2:09:15 PM | | | | |
| Aguilar, Patricio | | wo to myself - need to replace # to class rooms asper fire marshal | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 128911 | | | | | 2/13/2015 | | 94 | | \$0.00 |
| Medium | Work In Progress | | | | 2/13/2015 3:22:32 PM | | | | |
| Aguilar, Patricio | | need a elect. out lite replacer in comp. room - 2 elect out lite changed to G F I out lite old wing hall way. | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 132294 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:25 AM | | | | |
| Aguilar, Patricio | | Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132295 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:25 AM | | | | |
| Aguilar, Patricio | | Monthly - La Union ES Emer. Light Test: Monthly - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132306 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:32 AM | | | | |
| Aguilar, Patricio | | Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: La Union ES | | | | | | | | | |
| 132342 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:53 AM | | | | |
| Aguilar, Patricio | | Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132638 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 5/10/2015 12:23:46 AM | | | | |
| Aguilar, Patricio | | Monthly - La Union ES Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132550 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 3:10:09 PM | | | | |
| Aguilar, Patricio | | wo to myself - summer project - gym - clean sound deflectors | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 132552 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 3:11:45 PM | | | | |
| Aguilar, Patricio | | wo to myself - new wing - paint some of the class rooms | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 132553 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 3:13:48 PM | | | | |
| Aguilar, Patricio | | wo to myself - throw out school - replace ceiling tiles | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 132554 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 3:15:56 PM | | | | |
| Aguilar, Patricio | | wo to my self - front office - paint hall ways | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 132078 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 12:36:47 AM | | | | |
| Sanchez, Raul | | Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132728 | 2000 Core | Gym | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 10:48:02 AM | | | | |
| Lara, Ralph | | One of the doors under the stage does not want to open | | | | | | | |
| Rudy Ramos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|--|-------------|-------|-----------------------|------------------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: La Union ES | | | | | | | | | |
| 129347 | | | | | 2/26/2015 | | 81 | | \$0.00 |
| Medium | Work In Progress | | | | 2/26/2015 1:03:30 PM | | | | |
| Ontiveros, Joe | | water heater mech room old wing leaking from bottom of tank. Will need to be replaced. | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 131503 | | | | | 4/16/2015 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 4/16/2015 3:14:43 PM | | | | |
| Ontiveros, Joe | | the top part of urinal likes were line in may need bushing. old wing boyrestroom | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 132716 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 9:30:02 AM | | | | |
| Carrasco, Danny | | summer break project - need use of scissor lift and vacuum to clean sound damper in gym. | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 131786 | | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 11:27:27 AM | | | | |
| Castillo, Carlos | | need a new emerg. light installed - new fluorescent light fixer installed libr. storage room. | | | | 5/15- Asp Pat, route to Cali | | | |
| Patricio Aguilar | | | | | | | | | |
| 130277 | | | | | 3/17/2015 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | | 3/17/2015 3:39:15 PM | | | | |
| Castillo, Carlos | | have 2 parking pole lights out and 7 building lights out - need replaced | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 131846 | | | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | | | | 4/24/2015 10:36:39 AM | | | | |
| Castillo, Carlos | | Would like to have the building entrylights replaced. Parts are no longer available for them and half are out. Some LED mayjust be the answer. | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 126360 | | | | | 12/8/2014 | | 161 | | \$0.00 |
| Medium | Work In Progress | | | | 12/8/2014 12:38:51 PM | | | | |
| Orozco, Daniel | | DISHWASHER IS DOWN.SNP MANAGER LINDA Y. 589.2040 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|--|-------------------------|-----------|-----------------------|------------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: La Union ES | | | | | | | | | |
| 128739 | | | | | 2/10/2015 | | 97 | | \$0.00 |
| Medium | Work In Progress | | | | 2/10/2015 2:38:17 PM | | | | |
| Orozco, Daniel | | AS PER ADELE'S INSPECTION. SLICER NEEDS REPAIR. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132196 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:27 AM | | | | |
| Orozco, Daniel | | Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132218 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:40 AM | | | | |
| Orozco, Daniel | | Monthly - La Union ES Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129460 | | | | | 2/28/2015 | | 79 | | \$0.00 |
| Medium | Work In Progress | | | | 2/28/2015 12:35:03 AM | | | | |
| Sanchez, Raul | | Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 26 Work Orders | | | Avg. Age of WO's | 39 | | Total for La Union ES | 0 | | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Loma Linda ES

132219 5/3/2015 5/24/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:41 AM

Orozco, Daniel Monthly - Loma Linda ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

132359 5/4/2015 14 \$0.00

Medium Work In Progress 5/4/2015 10:35:08 AM

Orozco, Daniel The dishwasher is leaking/squirting water from on top of one of the pipes. SNP Manager Dolores R. 882.4707

Maritza Gonzalez

132658 Portables 5/11/2015 7 \$0.00

Medium Work In Progress LSC 5/11/2015 9:40:49 AM

Medina, Eric Remove weeds from roof

Angie Flores

132644 Portables 5/11/2015 7 \$0.00

Medium Work In Progress LSC 5/11/2015 8:03:34 AM

Medina, Eric Paint exterior of portable.

Angie Flores

132645 Portables 5/11/2015 7 \$0.00

Medium Work In Progress IEP Portable 5/11/2015 8:04:28 AM

Medina, Eric Repair exterior gutter which is falling off

Angie Flores

131791 Restroom (Girls) 4/23/2015 25 \$0.00

Medium Work In Progress 4/23/2015 1:10:01 PM

Medina, Eric need to replace three toilets including flush valves

Eric Medina

132091 4/30/2015 18 \$0.00

Medium Work In Progress 4/30/2015 12:43:02 PM

Medina, Eric Please pick up items from the warehouse on 4/30/2015

Angie Flores

132247 5/3/2015 5/11/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:57 AM

Medina, Eric Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Loma Linda ES

132248 5/3/2015 5/11/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:58 AM

Medina, Eric Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

132249 5/3/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:59 AM

Medina, Eric Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

131792 4/23/2015 25 \$0.00

Medium Work In Progress 4/23/2015 1:29:22 PM

Medina, Eric Deliver and help set up art show display on Thursday 4/23 at Gadsden Middle School and pick up art show display on Monday 4/27

Angie Flores

130577 3/25/2015 54 \$0.00

Medium Work In Progress 3/25/2015 3:06:55 PM

Medina, Eric need to weed and feed feilds

Eric Medina

122493 9/9/2014 251 \$0.00

Medium Work In Progress 9/9/2014 8:41:31 AM

Medina, Eric Soccer Goals- Remove overgrown weeds and order and install new soccer nets.

Alfredo Holguin

122498 9/9/2014 251 \$0.00

Medium Work In Progress 9/9/2014 8:56:19 AM

Medina, Eric Portable area sidewalks- Order fill dirt (crusher fines or screenings) and backfill eroded areas next to sidewalks

Alfredo Holguin

125287 Main Building 11/7/2014 192 \$0.00

Medium Work In Progress 11/7/2014 11:30:08 AM

Medina, Eric east Side exit doors need to be repainted properly

Alfredo Holguin

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|-----------------------|-----------|----|--|--------|
| Location: | | Loma Linda ES | | | | | | | |
| 132328 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:44 AM | | | | |
| Medina, Eric | | Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132631 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 5/10/2015 12:23:42 AM | | | | |
| Medina, Eric | | Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132542 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 2:56:05 PM | | | | |
| Medina, Eric | | paint room 222 | | | | | | | |
| Eric Medina | | | | | | | | | |
| 132543 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 2:56:47 PM | | | | |
| Medina, Eric | | paint room 217 | | | | | | | |
| Eric Medina | | | | | | | | | |
| 132544 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 2:57:27 PM | | | | |
| Medina, Eric | | paint room 220 | | | | | | | |
| Eric Medina | | | | | | | | | |
| 132546 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 2:58:03 PM | | | | |
| Medina, Eric | | paint room 215 | | | | | | | |
| Eric Medina | | | | | | | | | |
| 132547 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 2:58:59 PM | | | | |
| Medina, Eric | | paint room 214 | | | | | | | |
| Eric Medina | | | | | | | | | |
| 132548 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 3:00:55 PM | | | | |
| Medina, Eric | | paint room 210 | | | | | | | |
| Eric Medina | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|--|--|--|-----------------------|-----------|----|--|--------|
| Location: | | Loma Linda ES | | | | | | | |
| 132549 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 3:03:17 PM | | | | |
| Medina, Eric | | paint portable 1a | | | | | | | |
| Eric Medina | | | | | | | | | |
| 132540 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 2:55:15 PM | | | | |
| Medina, Eric | | paint all outside doors | | | | | | | |
| Eric Medina | | | | | | | | | |
| 132646 | | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | All around the | | | 5/11/2015 8:07:24 AM | | | | |
| Medina, Eric | | Re paint fire zones in front of school and along main parking lot sidewalk | | | | | | | |
| Angie Flores | | | | | | | | | |
| 132893 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 8:52:51 AM | | | | |
| Medina, Eric | | Please drill hole in new cabinet for water heater in remodeled portable. Remove electrical cord from water heater and pass it through new hole and reinstall. Please call me if this is unclear. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 132667 | | Classroom | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | 109 | | | 5/11/2015 11:31:31 AM | | | | |
| Medina, Eric | | Air conditioner switch not working at all spins loosely without turning air on. | | | | | | | |
| Angie Flores | | | | | | | | | |
| 131790 | | Parking Lot | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 1:08:34 PM | | | | |
| Medina, Eric | | need to repaint fire lanes handicap parking and yellow parking spots | | | | | | | |
| Eric Medina | | | | | | | | | |
| 132197 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:27 AM | | | | |
| Orozco, Daniel | | Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Loma Linda ES | | | | | | | | | |
| 119567 | | | | | 7/18/2014 | | 304 | | \$0.00 |
| Medium | Work In Progress | | | | 7/18/2014 10:50:19 AM | | | | |
| Orozco, Daniel | | BROKEN GLASS ON SERVING LINE. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 121440 | | | | | 8/19/2014 | | 272 | | \$0.00 |
| Medium | Work In Progress | | | | 8/19/2014 3:03:42 PM | | | | |
| Orozco, Daniel | | LATCH THAT LOCKS THE WALK IN IS BROKEN. SNP MANAGER DOLORES R. 882.4707 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 128871 | | | | | 2/12/2015 | | 95 | | \$0.00 |
| Medium | Work In Progress | | | | 2/12/2015 3:38:53 PM | | | | |
| Orozco, Daniel | | AS PER ECO-LAB (BUD) DISHWASHER MOTOR CONTRACTOR ON UPPER CONTROL BOX NEEDS TO BE REPAIRED CORRECTLY. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 122774 | | Portables | | | 9/15/2014 | | 245 | | \$0.00 |
| Medium | Work In Progress | | | | 9/15/2014 3:36:17 PM | | | | |
| Sotelo, Enrique | | need to provide power to new washer and drier room , and to new restroom. also will need a circuit for a lift table. | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 132468 | | Restroom | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 11:28:12 AM | | | | |
| Sotelo, Enrique | | WE HAVE SOME LIGHTS OFF FROM THE HALLWAYS AND BOYSBATHROOMS., (THANKS). | | | | | | | |
| Luis Solis | | | | | | | | | |
| 130079 | | Hallway/Corridor | | | 3/12/2015 | | 67 | | \$0.00 |
| Medium | Work In Progress | | | | 3/12/2015 9:29:09 AM | | | | |
| Sotelo, Enrique | | WE HAVE SOME LIGTHS OFF FROM THE HALLWAYS AND TWO BOYSRESTROOMS, ALSO THE SECURITY LIGTHS FROM THE BUILDING MAIN ENTRANCE TREE OF FOUR LIGTHS ARE NOT WORKING PROPERLY IS VERY DARK IN THE MORNING.,THANKS. | | | | | | | |
| Luis Solis | | | | | | | | | |
| 132791 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 7:35:32 AM | | | | |
| Sotelo, Enrique | | Troubleshoot fire suppression cut off under kitchen hood. | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|---------------------|------------------|--|--|--|-----------------------|--|-----|--|--------|
| Location: | | Loma Linda ES | | | | | | | |
| 132528 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 12:42:37 PM | | | | |
| Marquez, Gerardo | | Need a G Key and check core for music portable | | | | | | | |
| Angie Flores | | | | | | | | | |
| 131839 | | Restroom | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | Next to the Art | | | 4/24/2015 7:39:47 AM | | | | |
| Villalobos, David | | Sink in boys restroom keeps running, wáter does not stop flowing, its flowing day and night and its overflowing to the floor, need to get it fixed ASAP | | | | | | | |
| Angie Flores | | | | | | | | | |
| 122754 | | Pool | | | 9/15/2014 | | 245 | | \$0.00 |
| Medium | Work In Progress | | | | 9/15/2014 10:42:21 AM | | | | |
| Villalobos, David | | As discussed , need to remove com mode and sink in rest room and plumb out for washer and drier, com mode and sink need to be plumbed out in the storage room across existing restroom . will need hot water also. | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 132835 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | LSC | | | 5/13/2015 3:32:13 PM | | | | |
| Gonzales, Camilo | | MOVE HI-LO TABLE FROM WAREHOUSE TO LOMA LINDA ELEMENTARY NEW LSC CLASSROOM (SEE MR. SMITH/MR. LAWLER) | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 132803 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 8:36:06 AM | | | | |
| Vallejo, Albert | | Repair broken and/or missing sidewalks near bus turn-around and east gate. | | | | | | | |
| 130359 | | Classroom | | | 3/19/2015 | | 60 | | \$0.00 |
| Medium | Work In Progress | | | | 3/19/2015 9:39:31 AM | | | | |
| Estrada, Jesus | | THE CARPETS FROM THESE (7) CLASSROOMS ARE IN VERY BAD SHAPE , ROOMS # 211,213,215,217,218,220 AND 222, AFTER 20 YEARS OLD, WE THINK IS TIME TO REPLACED IT, BUT WITH TILE. (NO CARPET) ALSO IN THE HALLWAYS, WE HAVE SOME TILES THAT NEED TO REPLACED WITH A NEW ONES., THANK YOU. | | | | | | | |
| Luis Solis | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------------|------------------|---|-------------|-------|-----------------------|-----------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Loma Linda ES | | | | | | | | | |
| 127636 | | Office | | | 1/16/2015 | | 122 | | \$0.00 |
| Medium | Work In Progress | Mr. Smiths | | | 1/16/2015 9:33:57 AM | | | | |
| Estrada, Jesus | | New carpet that was just installed this summer break is already tearing, please fix | | | | work order # 113380?? | | | |
| Angie Flores | | | | | | | | | |
| 130127 | | | | | 3/13/2015 | | 66 | | \$0.00 |
| Medium | Work In Progress | | | | 3/13/2015 10:53:59 AM | | | | |
| Herrera, Jaime | | Lupe need to order several loads of crusher fine for front campus please | | | | | | | |
| Eric Medina | | | | | | | | | |
| 130128 | | | | | 3/13/2015 | | 66 | | \$0.00 |
| Medium | Work In Progress | | | | 3/13/2015 10:55:57 AM | | | | |
| Herrera, Jaime | | Lupe need to order several loads of playground sand for playground in front campus thank you | | | | | | | |
| Eric Medina | | | | | | | | | |
| 131795 | | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 2:17:05 PM | | | | |
| Herrera, Jaime | | need to request tractor with spreader to weed and feed fields | | | | | | | |
| Eric Medina | | | | | | | | | |
| 132125 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 6:43:54 PM | | | | |
| Herrera, Jaime | | Pete need to request spreader and Polaris to weed and feed fields | | | | | | | |
| Eric Medina | | | | | | | | | |
| 131640 | | Office | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | Nurses Office | | | 4/21/2015 8:44:41 AM | | | | |
| Marquez, Gerardo | | Cabinet Locks for three cabinets, please see nurse for details | | | | | | | |
| Angie Flores | | | | | | | | | |
| 131418 | | Portables | | | 4/15/2015 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | | 4/15/2015 8:23:11 AM | | | | |
| Marquez, Gerardo | | Spec Ed Portable - build shelf for water heater. Check with David V. or Alfredo on specifics. | | | | | | | |
| Alfredo Holguin | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------------|------------------|---|-------------------------|-----------|----------------------|--------------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Loma Linda ES | | | | | | | | | |
| 132541 | | Restroom (Girls) | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 2:56:03 PM | | | | |
| Marquez, Gerardo | | 5th Grade girls bathroom door not closing | | | | | | | |
| Angie Flores | | | | | | | | | |
| 123928 | | | | | 10/9/2014 | | 221 | | \$0.00 |
| Medium | Work In Progress | rm 105 | | | 10/9/2014 1:50:51 PM | | | | |
| Marquez, Gerardo | | need to replace classroom door | | | | | | | |
| Eric Medina | | | | | | | | | |
| 130836 | | | | | 4/5/2015 | 4/26/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:38 AM | | | | |
| Munoz, Michael | | Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132407 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 12:24:21 AM | | | | |
| Apodaca, Mario | | Monthly - Loma Linda ES - Domestic Water Filter - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 54 Work Orders | | | Avg. Age of WO's | 57 | | Total for Loma Linda ES | 0 | | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Mesquite ES | | | | | | | | | |
| 132403 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 12:24:19 AM | | | | |
| Apodaca, Mario | | Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132319 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:39 AM | | | | |
| Apodaca, Mario | | Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130941 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:30:34 AM | | | | |
| Apodaca, Mario | | Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132733 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 12:13:37 PM | | | | |
| Solis, Lorenzo | | need to replace circulating pumps and piping in the mech. rm. | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 131735 | Pump House | Pump House | | | 4/22/2015 | | 26 | | \$0.00 |
| Medium | Work In Progress | | | | 4/22/2015 1:38:51 PM | | | | |
| Apodaca, Mario | | irrigation well compressor cycling off and on | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 132076 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 12:36:46 AM | | | | |
| Apodaca, Mario | | Monthly - Mesquite ES - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130215 | | | | | 3/16/2015 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | | 3/16/2015 3:51:42 PM | | | | |
| Marquez, Gerardo | | we need front door handicap entrance to be repaired it does not open with a push of the button also the door stike and latch are not the right ones. | | | | | | | |
| Joe Ramirez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|---|-------------|-------------|-----------------------|------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Mesquite ES | | | | | | | | | |
| 131854 | | | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | | | 4/24/2015 11:03:41 AM | | | | | |
| Marquez, Gerardo | Lost one (1) CMME key. Please process paper work so we can bill ESA Construction for lost key. Should you have any questions please contact Mr. Gallegos at 575-882-6925. | | | | | | | | |
| Dominique Esparza | | | | | | | | | |
| 128469 | | | | | 2/4/2015 | | 103 | | \$0.00 |
| Medium | Work In Progress | | | 2/4/2015 12:35:41 PM | | | | | |
| Ontiveros, Guadalupe | eastside fenceline needs to be replaced (poor condition) this will be at the community park. | | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 130697 | | | | | 3/30/2015 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | 3/30/2015 6:31:02 AM | | | | | |
| Ambriz, Jose | need to replace burnt out relays on hvac unit in rm .505 | | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 121639 | | | | | 8/22/2014 | | 269 | | \$0.00 |
| Medium | Work In Progress | | | 8/22/2014 1:25:52 PM | | | | | |
| Estrada, Jesus | carpet in portable #601 needs to be repaired. | | | | | 3/15/15 - ASP CHUY, SCHEDULED FOR 3/23/15 | | | |
| Luis Saucedo | | | | | | | | | |
| 129288 | | Custodial | | | 2/25/2015 | | 82 | | \$0.00 |
| Medium | Work In Progress | | | 2/25/2015 1:15:24 PM | | | | | |
| Estrada, Jesus | Mr. Estrada as per Mrs. silvaggio On room # 105 the carpet is torn out as per principal would like to replace it with tile. if it's possible can this be done during the summer break. If you have a chance, could you please stop by and see it. Thank you | | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 130856 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | 4/5/2015 12:29:48 AM | | | | | |
| Ramirez, Joe | Monthly - Mesquite ES - Barrack Drainage (Monthly) - Refer to PMSchedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132235 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:50 AM | | | | | |
| Ramirez, Joe | Monthly - Mesquite ES - Barrack Drainage (Monthly) - Refer to PMSchedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Mesquite ES | | | | | | | | | |
| 132255 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:02 AM | | | | |
| Ramirez, Joe | | Monthly - Mesquite ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132321 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:40 AM | | | | |
| Ramirez, Joe | | Monthly - Mesquite ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132297 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:26 AM | | | | |
| Ramirez, Joe | | Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132298 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:27 AM | | | | |
| Ramirez, Joe | | Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132641 | | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 7:05:08 AM | | | | |
| Ramirez, Joe | | 5/11/15. need to paint a and e hallway | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 132873 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | ROSIE | | | 5/14/2015 7:40:39 AM | | | | |
| Gonzales, Camilo | | DELIVER PO 141507434 LAKESHORE LEARNING 2 BOXES ROSIE CASTILLO, TEACHER/MQ | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 128001 | | Mechanical | | | 1/27/2015 | | 111 | | \$0.00 |
| Medium | Work In Progress | | | | 1/27/2015 3:30:39 PM | | | | |
| Villalobos, David | | Need to replace leaking water heater at mechanical room | | | | | | | |
| David Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Mesquite ES | | | | | | | | | |
| 132775 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 3:57:13 PM | | | | |
| Villalobos, David | | need to replace closet flange in girls bathroom | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 132656 | | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 9:23:43 AM | | | | |
| Villalobos, David | | KELLY CABLE ALBERT MARQUEZ (505)250-6593 | | | | | | | |
| | | FRM LAS CRUCES S ON NM-478, E ON NM-228 TO ADDRESS ON NORTHSIDE. LOCATION IS MOBILE HOME ON SCHOOL PROPERTY ACCESSIBLE ON POST ST. SPOT: FRM TERMINAL ON POST ST IN FRONT OF MOBILE HOME THEN E ALONG TEMP ON GROUND 100FT | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 128416 | ArmyBuilding | Classroom | | | 2/3/2015 | | 104 | | \$0.00 |
| Medium | Work In Progress | classrooms | | | 2/3/2015 3:07:21 PM | | | | |
| Marquez, Gerardo | | Luis Saucedo/Head Custodian, needs C-Master made for classrooms. | | | | | | | |
| Sandra Mora | | | | | | | | | |
| 132792 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 7:36:45 AM | | | | |
| Sotelo, Enrique | | Troubleshoot kitchen hood cut off system. | | | | | | | |
| 132647 | | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 8:21:55 AM | | | | |
| Sotelo, Enrique | | KELLY CABLE ALBERT MARQUEZ (505)250-6593 | | | | | | | |
| | | FRM LAS CRUCES S ON NM-478, E ON NM-228 TO ADDRESS ON NORTHSIDE. LOCATION IS MOBILE HOME ON SCHOOL PROPERTY ACCESSIBLE ON POST ST. SPOT: FRM TERMINAL ON POST ST IN FRONT OF MOBILE HOME THEN E ALONG TEMP ON GROUND 100FT | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|--|-------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Mesquite ES | | | | | | | | | |
| 129930 | | | | | 3/9/2015 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | 3/9/2015 9:19:40 AM | | | | | |
| Orozco, Daniel | ICE BUILD UP IN FREEZER FLOOR (SAFETY HAZARD). SNP MANAGER EMILIA C. 233-2341 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 130088 | | | | | 3/12/2015 | | 67 | | \$0.00 |
| Medium | Work In Progress | | | 3/12/2015 10:38:21 AM | | | | | |
| Sotelo, Enrique | need to install electrical strip in nurses' office | | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 130089 | | | | | 3/12/2015 | | 67 | | \$0.00 |
| Medium | Work In Progress | | | 3/12/2015 10:39:23 AM | | | | | |
| Sotelo, Enrique | need to install electrical strip in computer lab. | | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 128915 | | | | | 2/13/2015 | | 94 | | \$0.00 |
| Medium | Work In Progress | | | 2/13/2015 3:27:50 PM | | | | | |
| Orozco, Daniel | AS PER ADELE'S INSPECTION REPORT- BUTTON ON MILK COOLER GETS STUCK. | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132198 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:28 AM | | | | | |
| Orozco, Daniel | Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 126417 | | | | | 12/9/2014 | | 160 | | \$0.00 |
| Medium | Work In Progress | | | 12/9/2014 3:12:51 PM | | | | | |
| Orozco, Daniel | REPLACE WHEELS IN WALK IN AND REFRIGERATOR SHELVES. SNP MANAGER EMILIA C. 233.2341 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132220 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:41 AM | | | | | |
| Orozco, Daniel | Monthly - Mesquite ES Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------------------|-----------|----------------------|------------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Mesquite ES | | | | | | | | | |
| 128861 | | | | | 2/12/2015 | | 95 | | \$0.00 |
| Medium | Work In Progress | | | | 2/12/2015 3:19:31 PM | | | | |
| Ronquillo, Ruben | | ramp leading to jungle jim set is in need of replacement there is rust and corrosion (safety issue). | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 132642 | | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 7:08:03 AM | | | | |
| Ronquillo, Ruben | | I am requesting the generator for the 20 th of may | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| Count: 35 Work Orders | | | Avg. Age of WO's | 48 | | Total for Mesquite ES | 0 | | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: North Valley ES | | | | | | | | | |
| 118856 | | | | | 7/1/2014 | | 321 | | \$0.00 |
| Medium | Work In Progress | | | | 7/1/2014 8:39:58 AM | | | | |
| Ronquillo, Ruben | | (attention ruben ronquillo)progressive plygrd equip-have five broken platform parts 46 1/2 L x5 1/2 W x3 1/2 H beams-also missing stairs-removed by green contractor solutoins-safety hazard-please check into replacment parts-(800-585-3131)@progressive design equip. | | | | | | | |
| Danny Vega | | | | | | | | | |
| 122505 | | | | | 9/9/2014 | | 251 | | \$0.00 |
| Medium | Work In Progress | | | | 9/9/2014 10:21:14 AM | | | | |
| Gonzalez, Salvador | | Principal would like to request a metal canopy at the bus turnaround, like the one at STE. | | | | | | | |
| Maria Hernandez | | | | | | | | | |
| 132187 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:22 AM | | | | |
| Orozco, Daniel | | Monthly - North Valley ES - Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132222 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:42 AM | | | | |
| Orozco, Daniel | | Monthly - North Valley ES Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132521 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 11:39:54 AM | | | | |
| Vega, Danny | | paint rms thru out school bldg/bypriority. will need paint (white) | | | | | | | |
| Danny Vega | | | | | | | | | |
| 132629 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 5/10/2015 12:23:41 AM | | | | |
| Vega, Danny | | Monthly - North Valley ES Playground Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132286 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:20 AM | | | | |
| Vega, Danny | | Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|---|-------------|--------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |
| Location: North Valley ES | | | | | | | | | |
| 132289 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:22 AM | | | | |
| Vega, Danny | Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132327 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:44 AM | | | | |
| Vega, Danny | Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131947 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 4/28/2015 12:25:29 AM | | | | |
| Vega, Danny | Daily - North Valley ES - Fire Pump (Biweekly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 127844 | | | | | 1/23/2015 | | 115 | | \$0.00 |
| Medium | Work In Progress | | | | 1/23/2015 10:40:59 AM | | | | |
| Orozco, Daniel | FLOOR LOOSE INSIDE WALK IN.SNP MANAGER LAURA B. 233.3658 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 129291 | | | | | 2/25/2015 | | 82 | | \$0.00 |
| Medium | Work In Progress | | | | 2/25/2015 2:39:24 PM | | | | |
| Orozco, Daniel | SWITCH COVER TO SKILLET TO TURN ON IS MISSING.SNP MANANGER LAURA B. 233-3658 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 129712 | | | | | 3/3/2015 | | 76 | | \$0.00 |
| Medium | Work In Progress | | | | 3/3/2015 1:11:00 PM | | | | |
| Sotelo, Enrique | organ trail emergency ballast in hallway by RM103 AND THROPY CASE | | | | | | | | |
| Danny Vega | | | | | | | | | |
| 129713 | | | | | 3/3/2015 | | 76 | | \$0.00 |
| Medium | Work In Progress | | | | 3/3/2015 1:12:44 PM | | | | |
| Sotelo, Enrique | pecan wing- emergency lamp ballast out by rm201-205-211 | | | | | | | | |
| Danny Vega | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: North Valley ES

129714 3/3/2015 76 \$0.00

Medium Work In Progress 3/3/2015 1:14:13 PM

Sotelo, Enrique rio grande wing emergency lamp ballast out by electrician by rm 310

Danny Vega

129715 3/3/2015 76 \$0.00

Medium Work In Progress 3/3/2015 1:21:12 PM

Sotelo, Enrique light switch by nurses office there is sparks when turned on also on the one by lounge/ total of two(2). please replace

Danny Vega

129168 2/23/2015 84 \$0.00

Medium Work In Progress 2/23/2015 2:17:23 PM

Sotelo, Enrique emergency lamp ballast are out in these mechanical rms by rm 101-109-203-201-207-301-304-303-306-308-311

Danny Vega

129169 2/23/2015 84 \$0.00

Medium Work In Progress 2/23/2015 2:20:22 PM

Sotelo, Enrique emergency lamp ballast are out in pipe chase rms organ trail by girls restrooms-pecan wing both pipe chases bys and girls

Danny Vega

127224 1/8/2015 130 \$0.00

Medium Work In Progress 1/8/2015 9:45:21 AM

Sotelo, Enrique emergency ballast out by hallway by rm 104-girls rr by rm 107-hallway by rm 202 by rm 206-by rm 211-by rm 305-by rm 300 conference- also pipe chase rm rio grand valley

Danny Vega

132865 5/14/2015 4 \$0.00

Medium Work In Progress 5/14/2015 7:28:04 AM

Marquez, Gerardo cafeteria entrance door (interior) will not open core will not turn/ needs to be secured by end of day

Danny Vega

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: North Valley ES

130492 3/24/2015 55 \$0.00

Medium Work In Progress 3/24/2015 7:52:32 AM

Villalobos, David rm 101-sink faucet wont stop running water/both angle stops are broken and cant find supplylines to this sink /need faucet replacment time delay type 4 inch centers-please help

Danny Vega

128098 Classroom 1/29/2015 109 \$0.00

Medium Work In Progress Nurse's office 1/29/2015 12:00:31 PM

Villalobos, David As per Mrs. Hernandez, nurse's office is requesting a small hot water heater to provide warm water for washing hands, gargles, etc.

Gloria Reyes

132894 Office 5/14/2015 4 \$0.00

Medium Work In Progress 5/14/2015 9:07:57 AM

Gonzales, Camilo Deliver 6 boxes, (3) 1st Grade; (3) 3rd Grade, English Math TR. Thank you.

Theresa Ramirez

132897 Office 5/14/2015 4 \$0.00

Medium Work In Progress 5/14/2015 9:33:24 AM

Gonzales, Camilo Deliver 34 boxes. PO# 141507652. Thank you.

Theresa Ramirez

131542 4/17/2015 31 \$0.00

Medium Work In Progress 4/17/2015 11:36:01 AM

Holguin, Alfredo (attention) Alfredo Holguin-need repairs on cracked platform equipment at nve/platforms are cracked and buckled soon to crack in some areas

Danny Vega

130648 3/27/2015 52 \$0.00

Medium Work In Progress 3/27/2015 7:53:47 AM

, need exterior and interior of campus bldg sprayed for infestation of spider and small cockroaches 3/31/15 - approved as per Alfredo, e-mailed Benny (\$150.00)

Danny Vega

131385 4/14/2015 34 \$0.00

Medium Work In Progress 4/14/2015 2:08:43 PM

Ruiz, Maria #107 will not start/stand on plygrd field/will not jump start.plzhelp.

Danny Vega

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: North Valley ES | | | | | | | | | |
| 130812 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:25 AM | | | | |
| Holguin, Alfredo | | Monthly - North Valley ES - Fire Pump Engine - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132916 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 2:26:03 PM | | | | |
| Vallejo, Albert | | Repair / replace canopies over playgrounds. | | | | | | | |
| 132826 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 2:06:34 PM | | | | |
| Solis, Lorenzø | | rm 212 a/c unit is down /has a pin hole leak on supply line/water is off -unit is off-please check asap | | | | | | | |
| Danny Vega | | | | | | | | | |
| 132719 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 9:41:14 AM | | | | |
| Carbajal, Jimmy | | vacuum #2095 does not turning on. | | | | | | | |
| Brian Pacheco | | | | | | | | | |
| 129447 | | | | | 2/28/2015 | | 79 | | \$0.00 |
| Medium | Work In Progress | | | | 2/28/2015 12:34:55 AM | | | | |
| Munoz, Michael | | Yearly - North Valley ES - Fire Pump Inspection - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130841 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:40 AM | | | | |
| Munoz, Michael | | Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132757 | | Mechanical | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 3:23:53 PM | | | | |
| Solis, Lorenzø | | Run new copper line for new geothermal circulating pump. | | | | | | | |
| Lorenzo Solis | | | | | | | | | |
| 132966 | | | | | 5/15/2015 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | | 5/15/2015 12:48:26 PM | | | | |
| Flores, Pete | | mower #422 need blades replaced /john deer 970 | | | | | | | |
| Danny Vega | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: North Valley ES

Count: 35 Work Orders Avg. Age of WO's 56 Total for North Valley ES 0 \$0.00

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--|------------------|-----------|--|--|-----------------------|--|-----|--|--------|
| Location: Northern On-Track Pre-K (LM) | | | | | | | | | |
| 132314 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:36 AM | | | | |
| Apodaca, Mario Monthly - Northern Pre-K -Lift Station Inspection - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130936 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:30:32 AM | | | | |
| Apodaca, Mario Monthly - Northern Pre-K -Lift Station Inspection - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131977 | Main Building | Classroom | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 4/28/2015 2:23:59 PM | | | | |
| Solis, Lorenzo AS PER DAYCARE - CLASSROOM 114 - WATER STILL LEAKING ABOVE DOORWAY. | | | | | | | | | |
| Adam Montoya | | | | | | | | | |
| 130493 | Main Building | | | | 3/24/2015 | | 55 | | \$0.00 |
| Medium | Work In Progress | | | | 3/24/2015 7:57:12 AM | | | | |
| Solis, Lorenzo NEED BOILER TURNED OFF. | | | | | | | | | |
| Adam Montoya | | | | | | | | | |
| 132075 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 12:36:45 AM | | | | |
| Apodaca, Mario Monthly - Northern Pre-K - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 126790 | Main Building | | | | 12/19/2014 | | 150 | | \$0.00 |
| Medium | Work In Progress | | | | 12/19/2014 8:00:45 AM | | | | |
| Herrera, Jaime (AS PER THE DAYCARE) NEED SAND DELIVERED FOR FRONT OF BUILDING SANDBOX. | | | | | | | | | |
| Adam Montoya | | | | | | | | | |
| 132849 | Main Building | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 3:50:35 PM | | | | |
| Solis, Lorenzo CLASSROOM 104 IS NOT COOLING DOWN, AIR IS BLOWING FROM VENTS BUT ROOM FEELS WARM. | | | | | | | | | |
| Adam Montoya | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Northern On-Track Pre-K (LM)

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|----|--|--------|
| 131302 | | | | | 4/13/2015 | | 35 | | \$0.00 |
|--------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/13/2015 2:40:08 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, David
PLAYGROUND WATER FOUNTAIN SPOUT CAME OFF.
AND WATER IS CONTINUOUSLY RUNNING AS PER WORK ORDER 129949. WATER SUPPLY IS SHUT OFF FROM BOILER ROOM.

Adam Montoya

| | | | | | | | | | |
|--------|--|--|--|--|----------|--|----|--|--------|
| 129949 | | | | | 3/9/2015 | | 70 | | \$0.00 |
|--------|--|--|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 3/9/2015 3:02:16 PM | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Villalobos, David
WATER FOUNTAIN BEHIND BUILDING IS CONTINUOUSLY RUNNING, AND LEAKING. SHUT-OFF VALVE IN BOILER ROOM TO PREVENT ANY FURTHER LEAKING.

Adam Montoya

| | | | | | | | | | |
|--------|---------------|-----------|--|--|-----------|--|----|--|--------|
| 131920 | Main Building | Cafeteria | | | 4/27/2015 | | 21 | | \$0.00 |
|--------|---------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|------------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | teacher's lounge | | | 4/27/2015 2:38:22 PM | | | | |
|--------|------------------|------------------|--|--|----------------------|--|--|--|--|

Vega, Danny
Removal of mail boxes from teacher's lounge.

Concepcion Montalvo

| | | | | | | | | | |
|--------|--|--|--|--|----------|----------|----|--|--------|
| 132326 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
|--------|--|--|--|--|----------|----------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/3/2015 12:33:43 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Vega, Danny
Monthly - La Mesa ES Monthly FE Inpsection - Refer to PMschedule details.

Margret Villalobos

| | | | | | | | | | |
|--------|--|--|--|--|----------|-----------|----|--|--------|
| 132287 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
|--------|--|--|--|--|----------|-----------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/3/2015 12:33:21 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Vega, Danny
Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PMschedule details.

Margret Villalobos

| | | | | | | | | | |
|--------|--|--|--|--|----------|-----------|----|--|--------|
| 132288 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
|--------|--|--|--|--|----------|-----------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/3/2015 12:33:21 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Vega, Danny
Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PMschedule details.

Margret Villalobos

| | | | | | | | | | |
|--------|--|--|--|--|-----------|-----------|---|--|--------|
| 132630 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
|--------|--|--|--|--|-----------|-----------|---|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/10/2015 12:23:42 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Vega, Danny
Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.

Margret Villalobos

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|---|-------------------------|-----------|---|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Northern On-Track Pre-K (LM) | | | | | | | | | |
| 132522 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 11:42:51 AM | | | | |
| Vega, Danny | | paint rms in bldg by priority/shown by adam (hd) that need paint | | | | | | | |
| Danny Vega | | | | | | | | | |
| 132524 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 11:55:18 AM | | | | |
| Vega, Danny | | trace leaks in old cafeteria rms used for storage - polyurethane roof | | | | | | | |
| Danny Vega | | | | | | | | | |
| Count: 16 Work Orders | | | Avg. Age of WO's | 32 | Total for Northern On-Track Pre-K (LM) | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days | Labor | Total |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|------|-------|-------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | Aged | Hours | Costs |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Physical Plant Complex

127567 1/15/2015 123 \$0.00

Medium Work In Progress 1/15/2015 7:52:14 AM

Carrasco, Danny need to remove Julies desk modular, carpet will be replaced. this needs to be done bytomorrow so that carpet be installed over the weekend.

Jesus Estrada

132779 5/12/2015 6 \$0.00

Medium Work In Progress 5/12/2015 4:20:34 PM

Marquez, Gerardo need a gm 7 keymade for Fernanda. Giving her access to my office for cleaning purposes.

Lisa Sanchez

132824 Maintenance 5/13/2015 5 \$0.00

Medium Work In Progress 5/13/2015 1:28:02 PM

Duran, Fernanda Please polish Albert's office furniture.

Albert Vallejo

132415 5/5/2015 13 \$0.00

Medium Work In Progress 5/5/2015 9:01:04 AM

Marquez, Gerardo FILE CABINET DOES NOT LOCK... i NEED A LOCK INSTALLED AND WILL NEED A KEY.

DRIVING RECORDS FOR DISTRICT EMPLOYEES ARE KEPT IN FILE CABINET. NEED TO HAVE IT SECURED.

Lisa Sanchez

132129 5/1/2015 17 \$0.00

Medium Work In Progress 5/1/2015 9:00:41 AM

Marquez, Gerardo Please make a DC2 keythe Custodial Warehouse Door for Lisa Sanchez a/s/a/p.

Lisa Sanchez

132098 Motor Vehicle 4/30/2015 18 \$0.00

Medium Work In Progress bay door #1 4/30/2015 2:47:16 PM

Marquez, Gerardo please connect electrical supply to bay door #1. Door is inoperable, and will not open.

Pete Flores

132135 5/1/2015 17 \$0.00

Medium Work In Progress 5/1/2015 11:45:16 AM

Marquez, Gerardo need keys for desk

Cynthia Maes

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 132414 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 8:57:52 AM | | | | |
| Sotelo, Enrique | | outlet on east wall does not work. Can we have it checked? | | | | | | | |
| Lisa Sanchez | | | | | | | | | |
| 130506 | Purchasing | | | | 3/24/2015 | | 55 | | \$0.00 |
| Medium | Work In Progress | | | | 3/24/2015 10:21:37 AM | | | | |
| Sotelo, Enrique | | NEED TO DROP ELECTRICAL OUTLET FOR WRAPPING MACHINE | | | | | | | |
| Enrique Briones | | | | | | | | | |
| 131110 | Main Warehouse | | | | 4/8/2015 | | 40 | | \$0.00 |
| Medium | Work In Progress | | | | 4/8/2015 3:19:19 PM | | | | |
| Sotelo, Enrique | | Need to install power/electrical outlets (See Enrique Briones) | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 132715 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 9:23:09 AM | | | | |
| Appelzoller, Fred | | tools: klein nut drivers, eklind allen wrenches, Ideal receptacle tester, channel locks 440, and 426 | | | | | | | |
| Fred Appelzoller | | | | | | | | | |
| 131775 | Maintenance | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 7:31:20 AM | | | | |
| Villalobos, David | | need sewer machine replacement for broken one | | | | | | | |
| David Villalobos | | | | | | | | | |
| 131522 | Maintenance | | | | 4/16/2015 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 4/16/2015 3:55:23 PM | | | | |
| Villalobos, David | | need tool and accessory replacement | | | | | | | |
| David Villalobos | | | | | | | | | |
| 130120 | | | | | 3/13/2015 | | 66 | | \$0.00 |
| Medium | Work In Progress | | | | 3/13/2015 8:02:08 AM | | | | |
| Villalobos, David | | need replacement cables and accessories to Rigid sewer machines | | | | | | | |
| David Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--|------------------|-------------|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 132182 | Main Warehouse | | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | Support | | | 5/1/2015 4:24:39 PM | | | | |
| Villalobos, David Replace faucets in both bathrooms. The water shoots out so strong they spray water every where. | | | | | | | | | |
| Cynthia Maes | | | | | | | | | |
| 130422 | | | | | 3/20/2015 | | 59 | | \$0.00 |
| Medium | Work In Progress | | | | 3/20/2015 10:57:33 AM | | | | |
| Miranda, Danny Need to upholster seat on Truck #153 | | | | | | | | | |
| Pete Flores | | | | | | | | | |
| 131664 | Purchasing | Office | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 11:37:20 AM | | | | |
| Villalobos, David The men's restroom is clogged and water is seeping out at the base. | | | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 132705 | Purchasing | Office | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 7:19:13 AM | | | | |
| Carrasco, Danny At the Instruction Materials Department, requesting If possible, the floors in the warehouse need to be painted and sealed. Thank you. | | | | | | | | | |
| (Asp Albert, Sebastian to assist) | | | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 127533 | | | | | 1/14/2015 | | 124 | | \$0.00 |
| Medium | Work In Progress | | | | 1/14/2015 1:56:21 PM | | | | |
| Carrasco, Danny Paint Juliet's Office. | | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 127691 | | | | | 1/20/2015 | | 118 | | \$0.00 |
| Medium | Work In Progress | | | | 1/20/2015 10:04:05 AM | | | | |
| Miranda, Danny PPD Offices - remolding new office. | | | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 131716 | Maintenance | Office | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 4:13:09 PM | | | | |
| Miranda, Danny Ceiling in Locksmith office has many cracks and holes. insulation and or fibers are falling through. Would it be possible to install a suspended ceiling. | | | | | | | | | |
| Gerardo Marquez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|--|--|--|----------------------|--|-----|--|--------|
| Location: | | Physical Plant Complex | | | | | | | |
| 128463 | Maintenance | | | | 2/4/2015 | | 103 | | \$0.00 |
| Medium | Work In Progress | | | | 2/4/2015 10:57:20 AM | | | | |
| Holguin, Alfredo | | Need quote to insulate Metal Bldg on westside of Autosshop. | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 129148 | Motor Vehicle | | | | 2/23/2015 | | 84 | | \$0.00 |
| Medium | Work In Progress | New Annex Bldg | | | 2/23/2015 9:38:06 AM | | | | |
| Vallejo, Albert | | Need to install Electrical power outlets in metal bldg behind Auto Shop - (see Alfredo H. for ?'s) | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 132267 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:09 AM | | | | |
| Ruiz, Maria | | Monthly - PPD - Fueling Station Monthly Inspection - Refer to PMSchedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 127600 | | Office | | | 1/15/2015 | | 123 | | \$0.00 |
| Medium | Work In Progress | | | | 1/15/2015 3:30:01 PM | | | | |
| Estrada, Jesus | | NEED QUOTE FOR VCT TO BE REPLACED IN PPD FRONT ENTRANCE & OFFICE. | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 128508 | | Lift Station | | | 2/5/2015 | | 102 | | \$0.00 |
| Medium | Work In Progress | | | | 2/5/2015 8:24:35 AM | | | | |
| Herrera, Jaime | | need the assistance of a heavy equipment operator and tractor to help us replace a air relief check valve on the west side of the river bank | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 132245 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:56 AM | | | | |
| Carbajal, Jimmy | | Monthly - Physical Plant - Clothes Dryer (Monthly) - Refer to PMSchedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132771 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 3:54:44 PM | | | | |
| Ambriz, Jose | | tools | | | | | | | |
| Jose Ambriz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|---|----------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 127534 | | | | | 1/14/2015 | | 124 | | \$0.00 |
| Medium | Work In Progress | | | 1/14/2015 1:58:36 PM | | | | | |
| Estrada, Jesus | Install new carpet in Julie's office, once office is painted to match Alfredo's carpet. | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 128702 | Purchasing | | | | 2/9/2015 | | 98 | | \$0.00 |
| Medium | Work In Progress | New Warehouse | | 2/9/2015 4:11:54 PM | | | | | |
| Marquez, Gerardo | Keys to be assigned to Cynthia Maes for the New Warehouse Offices, storage room and restrooms. I would like to meet Jerry out there when he is done making the keys he can call me-Cynthia at 882-6949. | | | | | | | | |
| Cynthia Maes | | | | | | | | | |
| 129929 | | | | | 3/9/2015 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | 3/9/2015 8:36:25 AM | | | | | |
| Marquez, Gerardo | NEED TO ORDER TOOLS AND MATERIAL FOR USE DISTRICTWIDE. | | | | | | | | |
| Gerardo Marquez | | | | | | | | | |
| 128464 | Motor Vehicle | | | | 2/4/2015 | | 103 | | \$0.00 |
| Medium | Work In Progress | New Annex Bldg | | 2/4/2015 10:58:49 AM | | | | | |
| Marquez, Gerardo | Need to install doors on Metal Bldg on westside of AutoShop (see Alfredo H. for ?'s) | | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 132077 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | 4/30/2015 12:36:46 AM | | | | | |
| Apodaca, Mario | Monthly - PPD/GHS - WW Monthly Sampling - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132348 | | | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | 5/4/2015 12:31:37 AM | | | | | |
| Villalobos, Margret | Monthly - PPD - Quarterly Meeting - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132350 | | | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | 5/4/2015 8:23:55 AM | | | | | |
| Villalobos, Margret | PLEASE SPRAY BARRACKS FOR BEES. THANK YOU! | | | | | | | | |
| Ruben Ronquillo | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|--------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|------------------|--|-------------------------------|--|--|-----------------------|--|-----|--|--------|
| Location: | | Physical Plant Complex | | | | | | | |
| 130605 | | | | | 3/26/2015 | | 53 | | \$0.00 |
| Medium | Work In Progress | | | | 3/26/2015 6:28:23 AM | | | | |
| Apodaca, Mario | the 4 in check ball valve at lift pump station need to be replaced due to wear and tear at gms/sunrise | | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 128609 | | | | | 2/6/2015 | | 101 | | \$0.00 |
| Medium | Work In Progress | | | | 2/6/2015 3:36:55 PM | | | | |
| Apodaca, Mario | meet to order a powerverter for truck 38 to mount in the toolbox | | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 131722 | | | | | 4/22/2015 | | 26 | | \$0.00 |
| Medium | Work In Progress | | | | 4/22/2015 8:39:03 AM | | | | |
| Apodaca, Mario | need to replace the burned out battery charger for the cordless power tools | | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 132666 | Purchasing | Office | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 11:05:30 AM | | | | |
| Herrera, Mario | At the Instruction Materials Department, requesting the office and foyer floor be cleaned and waxed. The carpet in Mr. Leyva's office need to be shampooed. Thank you. | | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 132972 | Motor Vehicle | | | | 5/15/2015 | | 3 | | \$0.00 |
| Medium | Work In Progress | vehicle#25 | | | 5/15/2015 2:50:05 PM | | | | |
| Flores, Pete | please check for any scheduled maintenance | | | | | | | | |
| Pete Flores | | | | | | | | | |
| 132657 | Motor Vehicle | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | vehicle #149 | | | 5/11/2015 9:40:09 AM | | | | |
| Flores, Pete | please check for any scheduled maintenance. | | | | | | | | |
| Pete Flores | | | | | | | | | |
| 132659 | Motor Vehicle | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | vehicle#147 | | | 5/11/2015 9:46:08 AM | | | | |
| Flores, Pete | please check for any scheduled maintenance. | | | | | | | | |
| Pete Flores | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|--|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 132648 | Motor Vehicle | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | vehicle#148 | | | 5/11/2015 8:29:12 AM | | | | |
| Flores, Pete | | please check vehicle for any scheduled maintenance. | | | | | | | |
| Pete Flores | | | | | | | | | |
| 132654 | Motor Vehicle | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | vehicle#165 | | | 5/11/2015 9:04:44 AM | | | | |
| Flores, Pete | | please perform any required service. | | | | | | | |
| Pete Flores | | | | | | | | | |
| 132746 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 2:54:37 PM | | | | |
| Flores, Pete | | Vehicle #138 - AC is not cooling very well | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 132426 | Motor Vehicle | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | vehicle#178 | | | 5/5/2015 11:11:15 AM | | | | |
| Flores, Pete | | please check for any required maintenance. | | | | | | | |
| Pete Flores | | | | | | | | | |
| 131282 | | Athletic Field | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 4/13/2015 9:15:54 AM | | | | |
| Flores, Pete | | trailer #0774 need bearing packed. | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 131283 | | Athletic Field | | | 4/13/2015 | | 35 | | \$0.00 |
| High | Work In Progress | | | | 4/13/2015 9:21:42 AM | | | | |
| Flores, Pete | | Trailer #0751 breaks not working, when hook to dump truck #143 | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 132526 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | Federal vehicle - | | | 5/7/2015 12:10:19 PM | | | | |
| Flores, Pete | | OIL CHANGE | | | | | | | |
| Noemi Duron | | | | | | | | | |
| 132527 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | FED VEHICLE - | | | 5/7/2015 12:38:27 PM | | | | |
| Flores, Pete | | RIGHT BACK TAIL LIGHT NOT WORKING. | | | | | | | |
| Noemi Duron | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 122443 | Motor Vehicle | | | | 9/8/2014 | | 252 | | \$0.00 |
| Medium | Work In Progress | ag trailer | | | 9/8/2014 9:06:23 AM | | | | |
| Flores, Pete | | please prepare trailer as required for use by agriculture dept. | | | | | | | |
| Pete Flores | | | | | | | | | |
| 127462 | Motor Vehicle | | | | 1/13/2015 | | 125 | | \$0.00 |
| Medium | Work In Progress | vehicle#147 | | | 1/13/2015 9:39:06 AM | | | | |
| Flores, Pete | | rear driver's side window inoperative, please check cause of malfunction. | | | | | | | |
| Pete Flores | | | | | | | | | |
| 127546 | Motor Vehicle | | | | 1/14/2015 | | 124 | | \$0.00 |
| Medium | Work In Progress | chaparral golf | | | 1/14/2015 3:17:18 PM | | | | |
| Flores, Pete | | please prepare fairplay golf cart for use by chaparral security | | | | | | | |
| Pete Flores | | | | | | | | | |
| 127289 | Motor Vehicle | | | | 1/9/2015 | | 129 | | \$0.00 |
| Medium | Work In Progress | vehicle#100 | | | 1/9/2015 10:33:33 AM | | | | |
| Flores, Pete | | please check cause of vehicle leaning excessively to one side. | | | | | | | |
| Pete Flores | | | | | | | | | |
| 127251 | | | | | 1/8/2015 | | 130 | | \$0.00 |
| Medium | Work In Progress | | | | 1/8/2015 3:20:43 PM | | | | |
| Flores, Pete | | TRUCK #32 NEEDS FUEL PUMP REPLACED | | | | | | | |
| Ruben Ronquillo | | | | | | | | | |
| 128130 | Motor Vehicle | | | | 1/30/2015 | | 108 | | \$0.00 |
| Medium | Work In Progress | tilt trailer | | | 1/30/2015 8:20:03 AM | | | | |
| Flores, Pete | | battery is more than 5 years old, requires replacement. | | | | | | | |
| Pete Flores | | | | | | | | | |
| 127958 | Motor Vehicle | | | | 1/26/2015 | | 112 | | \$0.00 |
| Medium | Work In Progress | Federal vehicle | | | 1/26/2015 3:44:58 PM | | | | |
| Flores, Pete | | When driving in a long road and picking up speed the vehicle starts to jerk. Also, windows on driver side front and passenger back do not work. | | | | | | | |
| Noemi Duron | | | | | | | | | |
| 127922 | Main Warehouse | | | | 1/26/2015 | | 112 | | \$0.00 |
| Medium | Work In Progress | | | | 1/26/2015 1:30:57 PM | | | | |
| Flores, Pete | | SNP VEHICLE 56 NEEDS TO BE SERVICED. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 127924 | Main Warehouse | | | | 1/26/2015 | | 112 | | \$0.00 |
| Medium | Work In Progress | | | | 1/26/2015 1:31:21 PM | | | | |
| Flores, Pete | | SNP VEHHCILE 43 NEEDS TO BE SERVICED. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 131361 | Motor Vehicle | | | | 4/14/2015 | | 34 | | \$0.00 |
| Medium | Work In Progress | vehicle#47 | | | 4/14/2015 8:34:33 AM | | | | |
| Flores, Pete | | please check for any scheduled maintenance | | | | | | | |
| Pete Flores | | | | | | | | | |
| 129947 | Motor Vehicle | | | | 3/9/2015 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | | 3/9/2015 2:01:14 PM | | | | |
| Flores, Pete | | vehicle 187 passenger window doesn't roll up or down | | | | | | | |
| 129982 Motor Vehicle 3/10/2015 69 \$0.00 | | | | | | | | | |
| Medium | Work In Progress | equip#0411 | | | 3/10/2015 9:43:46 AM | | | | |
| Flores, Pete | | please check electrical system for proper starting and any additional scheduled maintenance | | | | | | | |
| Pete Flores | | | | | | | | | |
| 124450 | | | | | 10/22/2014 | | 208 | | \$0.00 |
| Medium | Work In Progress | | | | 10/22/2014 11:21:12 | | | | |
| Flores, Pete | | vehicle 01, needs wipers and check engine light turned on and turned off (reported by Teresa Ortega) | | | | | | | |
| Maria Ruiz | | | | | | | | | |
| 130305 | | | | | 3/18/2015 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | | 3/18/2015 10:15:56 AM | | | | |
| Flores, Pete | | Please service and check vehicle 99. | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 130297 | Motor Vehicle | | | | 3/18/2015 | | 61 | | \$0.00 |
| Medium | Work In Progress | vehicle#151 | | | 3/18/2015 8:36:01 AM | | | | |
| Flores, Pete | | please check for a/c refrigerant loss | | | | | | | |
| Pete Flores | | | | | | | | | |
| 129690 | Motor Vehicle | | | | 3/3/2015 | | 76 | | \$0.00 |
| Medium | Work In Progress | | | | 3/3/2015 10:23:53 AM | | | | |
| Flores, Pete | | vehicle 188; gas gauge doesn't work correctly reported by Gilbert Bailon | | | | | | | |
| Maria Ruiz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Physical Plant Complex

129692 Motor Vehicle 3/3/2015 76 \$0.00

Medium Work In Progress 3/3/2015 10:26:26 AM

Flores, Pete locks on don't work 178 & 179 bad actuator (driver's side)

Maria Ruiz

129694 Motor Vehicle 3/3/2015 76 \$0.00

Medium Work In Progress vehicle#136 3/3/2015 10:27:34 AM

Flores, Pete please check condition of front brakes.

Pete Flores

129705 Motor Vehicle 3/3/2015 76 \$0.00

Medium Work In Progress vehicle#148 3/3/2015 11:16:53 AM

Flores, Pete please check cause of a/c refrigerant loss

Pete Flores

129350 Motor Vehicle 2/26/2015 81 \$0.00

Medium Work In Progress 1050 tractor- 2/26/2015 2:22:42 PM

Flores, Pete please check cause of tractor not starting.

Pete Flores

132386 Athletic Field 5/4/2015 14 \$0.00

Medium Work In Progress 5/4/2015 3:38:44 PM

Flores, Pete Gooseneck Treiler #0758 tire needs to be replace.

Guadalupe Ontiveros

128931 2/14/2015 93 \$0.00

Medium Work In Progress 2/14/2015 12:21:53 AM

Flores, Pete Yearly - PPD-T-0524 Bobcat PM Service - Refer to PM schedule details.

Margret Villalobos

128653 Maintenance Office 2/9/2015 98 \$0.00

Medium Work In Progress 2/9/2015 8:16:17 AM

Lara, Ralph WE NEED TWO TRIPP POWER VERTAR 3000W TO USED THEM ON DISTRICT VANS, FOR CUTTING KEYS ON DIFFRENT SCHOOL SITES.

Ralph Lara

131801 Motor Vehicle 4/23/2015 25 \$0.00

Medium Work In Progress 4/23/2015 2:42:18 PM

Flores, Pete get vehicle 136 ready for Technology Department

Maria Ruiz

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 130636 | | Athletic Field | | | 3/26/2015 | | 53 | | \$0.00 |
| Medium | Work In Progress | | | | 3/26/2015 3:56:06 PM | | | | |
| Gonzalez, Salvador | | Dump truck needs angle iron weld to prevent flappers getting stock on tires. | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 122868 | | | | | 9/16/2014 | | 244 | | \$0.00 |
| Medium | Work In Progress | | | | 9/16/2014 3:48:24 PM | | | | |
| Ronquillo, Ruben | | ORDER 4EA. ENGINE DRIVEN WATER PUMPS, WITH HOSES. THANK YOU | | | | | | | |
| Ruben Ronquillo | | | | | | | | | |
| 131303 | | | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 4/13/2015 2:44:24 PM | | | | |
| Ronquillo, Ruben | | ORDER PALLET RACK WIRE FLARED DECKING, CROSSBEAM FOR SHELVING FOR NEW WAREHOUSE | | | | | | | |
| Ruben Ronquillo | | | | | | | | | |
| 131432 | | | | | 4/15/2015 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | | 4/15/2015 10:26:32 AM | | | | |
| Ronquillo, Ruben | | LEATHERMAN TOOL | | | | | | | |
| Ruben Ronquillo | | | | | | | | | |
| 131638 | Purchasing | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | New Support | | | 4/21/2015 8:23:56 AM | | | | |
| Ronquillo, Ruben | | Need sign outside replaced with sign that says "Support Services" White with Black Letters | | | | | | | |
| Cynthia Maes | | | | | | | | | |
| 132010 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 4/28/2015 3:58:55 PM | | | | |
| Ronquillo, Ruben | | ORDER 5 AND 10 LB. FIRE EXTINGUISHERS | | | | | | | |
| Ruben Ronquillo | | | | | | | | | |
| 132337 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:50 AM | | | | |
| Diaz, Sebastian | | Monthly - Physical Plant FE Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|--|-----------------|-------------------------|-----------|---|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 131376 | | | | | 4/14/2015 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | | 4/14/2015 10:26:43 AM | | | | |
| Gallegos, Rafael | SNP WAREHOUSE-There is a small roof leak where the racking starts. This is straight by bay 6. Please advise, Jose | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 130453 | | | | | 3/23/2015 | | 56 | | \$0.00 |
| Medium | Work In Progress | | | | 3/23/2015 9:28:50 AM | | | | |
| Gallegos, Rafael | SNP WAREHOUSE-As per Jose, buttons getting stuck on the control box, see attached photo. Need to check and correct the issue a.s.a.p. For details or information call Jose at 575-882-6939. Thanks | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132713 | Motor Vehicle | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | Federal Vehicle | | | 5/12/2015 9:00:03 AM | | | | |
| Perez, Raul | car wash and vacuum. | | | | | | | | |
| Noemi Duron | | | | | | | | | |
| Count: 84 Work Orders | | | Avg. Age of WO's | 58 | Total for Physical Plant Complex | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Riverside ES

129221 Main Building 2/24/2015 83 \$0.00

Medium Work In Progress 2/24/2015 10:50:22 AM

Perez, Raul vehicle 46 is leaking and smoke was coming out reported by Rocio Herrera

Maria Ruiz

131098 Main Building Classroom 4/8/2015 40 \$0.00

Medium Work In Progress whole school 4/8/2015 12:02:08 PM

Ronquillo, Ruben As per Mr. Gallegos, need to purchase and install window blinds. Color - WHITE, - (navarro)

80 - 24" x 24"
35 - 16" x 48"
17 - 24" x 48"
15 - 9" x 42"
18 - 25" x 67"
4 - 23" x 48"
2 - 72" x 80"

Rosa Quezada

126186 Main Building Cafeteria 12/3/2014 166 \$0.00

Medium Work In Progress cafeteria 12/3/2014 3:23:58 PM

Lara, Ralph need to install a doorbell in north side door of the cafeteria for incoming deliveries to the cafeteria. vendors waiting outside to deliver because we don't know they are out there and we can hear them knocking on the door. (santa Nava)

Rosa Quezada

131807 Restroom 4/23/2015 25 \$0.00

Medium Work In Progress 4/23/2015 3:00:48 PM

Lara, Ralph Please install new restroom partitions in 5th and 6th grade restrooms in coordination with remodel.

Albert Vallejo

127176 1/7/2015 131 \$0.00

Medium Work In Progress 1/7/2015 10:42:19 AM

Lara, Ralph 1/07/2015.
Need Rafa L. to replace old double door Mullions with new single key Mullions, also need panic bar door handle fixed. Would also like new hardware kits for all door mullions.

Mario Martinez

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days | Labor | Total |
|-------------------------------|------------------|---|-------------|-------|-----------------------|------------------|------|-------|--------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | Aged | Hours | Costs |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Riverside ES | | | | | | | | | |
| 132790 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 7:35:17 AM | | | | |
| Lara, Ralph | | Need Rafa L. to change or fix door knob at room #114. ASAP. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 132412 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 8:02:11 AM | | | | |
| Lara, Ralph | | Need Master key made for Miguel S. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 132739 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 1:11:43 PM | | | | |
| Villalobos, Margret | | SCORPIONS IN STORAGE ROOM. SNP MANAGER | | | | emailed Bennie | | | |
| | | SANTA NAVA 589.2550. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132023 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 11:12:16 AM | | | | |
| Martinez, Mario | | Need to install 4 locking clasps on cabinets in room #123. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 131671 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 12:42:25 PM | | | | |
| Martinez, Mario | | Need to replace all filters throughout entire school. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 131582 | | | | | 4/20/2015 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | | 4/20/2015 9:05:28 AM | | | | |
| Martinez, Mario | | Need to install 170 Blinds through out entire school. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 129345 | | | | | 2/26/2015 | | 81 | | \$0.00 |
| Medium | Work In Progress | | | | 2/26/2015 12:36:28 PM | | | | |
| Martinez, Mario | | 2/26/2015. Need to purchase 4 tarps to cover furniture left out side of buildinds. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 130785 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:10 AM | | | | |
| Martinez, Mario | | Yearly - Riverside ES A-13 A/C Wall Mount Yearly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 5/18/2015 9:32:33 AM | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: | | Riverside ES | | | | | | | |
| 130266 | | | | | 3/17/2015 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | | 3/17/2015 2:40:58 PM | | | | |
| Martinez, Mario | | Need to fertilize soccer field and entire lawn. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 132299 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:28 AM | | | | |
| Martinez, Mario | | Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132300 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:28 AM | | | | |
| Martinez, Mario | | Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132443 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 3:44:05 PM | | | | |
| Martinez, Mario | | Need assistance with rehangng 2 inch conduit for communication. Carlos C. assisted. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 132375 | | | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 2:16:50 PM | | | | |
| Martinez, Mario | | Summer break projects. Need to paint classrooms. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 132376 | | | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 2:20:13 PM | | | | |
| Martinez, Mario | | Need to change out bad light bulbs in each class room. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 132338 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:50 AM | | | | |
| Martinez, Mario | | Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132825 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 2:05:00 PM | | | | |
| Martinez, Mario | | Need to aerate soccer field. | | | | | | | |
| Mario Martinez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Riverside ES | | | | | | | | | |
| 132637 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 5/10/2015 12:23:45 AM | | | | |
| Martinez, Mario | | Monthly - Riverside ES Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131805 | | Restroom | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 2:56:58 PM | | | | |
| Martinez, Mario | | Please paint restroom walls in coordination with remodel. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 121247 | Main Building | Classroom | | | 8/15/2014 | | 276 | | \$0.00 |
| Medium | Work In Progress | nurses station | | | 8/15/2014 10:30:55 AM | | | | |
| Martinez, Mario | | we need two installed two SECURED cabinets in the nurses station with lock and key for medicine storage. (navarro) | | | | | | | |
| Rosa Quezada | | | | | | | | | |
| 129759 | | | | | 3/4/2015 | | 75 | | \$0.00 |
| Medium | Work In Progress | main school | | | 3/4/2015 8:19:53 AM | | | | |
| Marquez, Gerardo | | second request for front main door closer. reference work order# 128792. this work order shows it's been closed but door remains non-functional. please send Rafa a.s.a.p. (Navarro) | | | | | | | |
| Rosa Quezada | | | | | | | | | |
| 129001 | | | | | 2/18/2015 | | 89 | | \$0.00 |
| Medium | Work In Progress | | | | 2/18/2015 7:55:14 AM | | | | |
| Ontiveros, Guadalupe | | Need assistance with locating buried and lost sprinkler valves | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 122686 | | | | | 9/12/2014 | | 248 | | \$0.00 |
| Medium | Work In Progress | | | | 9/12/2014 8:17:14 AM | | | | |
| Ambriz, Jose | | check cooling in room 136 | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 127260 | | | | | 1/8/2015 | | 130 | | \$0.00 |
| High | Work In Progress | | | | 1/8/2015 3:41:48 PM | | | | |
| Ambriz, Jose | | please clean all strainers to coils for proper heating. the contract did not include flushing lines. thank you | | | | | | | |
| Michael Munoz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|------------------|------------------|---|--|--|-----------------------|--|-----|--|--------|
| Location: | | Riverside ES | | | | | | | |
| 131806 | | Restroom | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 2:58:22 PM | | | | |
| Estrada, Jesus | | Please install VCT tile in 5th and 6th grade restrooms in coordination with remodel. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 131636 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 8:21:26 AM | | | | |
| Ontiveros, Joe | | 4/21/2015. Need Joe O. to replace 4 outside water fountain faucets. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 121838 | | | | | 8/27/2014 | | 264 | | \$0.00 |
| Medium | Work In Progress | | | | 8/27/2014 12:58:57 PM | | | | |
| Ontiveros, Joe | | Need plumber Joe O. to fix leaky urinal in boys restroom at north wing. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 132031 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 2:51:09 PM | | | | |
| Ontiveros, Joe | | 4/29/2015. Need plumber Joe O. to replace water faucet at Nurses office. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 131954 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 4/28/2015 8:25:40 AM | | | | |
| Ontiveros, Joe | | Need plumber Joe O. to replace leaky hot water heater in north side custodial room. 10 gallon electric. ASAP. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 131809 | | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 3:02:24 PM | | | | |
| Ontiveros, Joe | | Please install new fixtures in 5th and 6th grade restrooms in coordination with remodel. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 131836 | | | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | | | | 4/24/2015 7:33:57 AM | | | | |
| Ontiveros, Joe | | Need plumber Joe O. to pull up stopped up toilet at kinder wing. | | | | | | | |
| Mario Martinez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Riverside ES | | | | | | | | | |
| 131837 | | | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | | | | 4/24/2015 7:37:01 AM | | | | |
| Ontiveros, Joe | | Need plumber Joe O. to fix urinal flush valve in boys restroom, North wing. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 132103 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 3:23:32 PM | | | | |
| Ontiveros, Joe | | Install water supply, sink and drain at PTO portable. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 127174 | | | | | 1/7/2015 | | 131 | | \$0.00 |
| Medium | Work In Progress | | | | 1/7/2015 10:13:02 AM | | | | |
| Ontiveros, Joe | | 1/07/2015. Need Joe O. to repair or replace five flush valves at boys and girls bathrooms. Also need to replace open elongated toilet seat | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 130467 | | | | | 3/23/2015 | | 56 | | \$0.00 |
| Medium | Work In Progress | | | | 3/23/2015 3:02:27 PM | | | | |
| Ontiveros, Joe | | Need plumber Joe O. to unstop water fountain in hallway across office. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 131197 | | | | | 4/10/2015 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 4/10/2015 1:38:30 PM | | | | |
| Vallejo, Albert | | As per Mrs Navarro, she is asking if the 5th and 6th grade boys and girls restrooms can be remodeled in the summer? | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 132046 | | | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 3:32:38 PM | | | | |
| Vallejo, Albert | | Install new marquee. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 132148 | | Office | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 12:23:15 PM | | | | |
| Gonzales, Camilo | | Deliver 59 boxes of SPAN/ENGL Math/Science Foldable Instructional materials. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Riverside ES | | | | | | | | | |
| 132671 | | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 12:00:57 PM | | | | |
| Aldaz, Bobby | | Need excavator and operator to excavate broken water line and to excavate lost sprinkler valves at front of school. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 131030 | | | | | 4/7/2015 | | 41 | | \$0.00 |
| High | Work In Progress | | | | 4/7/2015 9:28:48 AM | | | | |
| Castillo, Carlos | | Power outage at school site. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 130611 | | Classroom | | | 3/26/2015 | | 53 | | \$0.00 |
| Medium | Work In Progress | IEP room | | | 3/26/2015 8:39:26 AM | | | | |
| Castillo, Carlos | | install electrical outlet on ceiling for the projector (Navarro) | | | | | | | |
| Rosa Quezada | | | | | | | | | |
| 130762 | | | | | 3/31/2015 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | | 3/31/2015 11:18:15 AM | | | | |
| Castillo, Carlos | | need an electrical outlet on ceiling for projector. IEP Room | | | | | | | |
| Cora Ramirez | | | | | | | | | |
| 126797 | | | | | 12/19/2014 | | 150 | | \$0.00 |
| Medium | Work In Progress | | | | 12/19/2014 9:48:59 AM | | | | |
| Castillo, Carlos | | Need Carlos C. to fix bad lighting fixtures in room 101. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 128336 | | | | | 2/2/2015 | | 105 | | \$0.00 |
| Medium | Work In Progress | | | | 2/2/2015 9:50:24 AM | | | | |
| Castillo, Carlos | | 2/02/2015. Need Carlos C to fix non working lights in South wing and main wing. | | | | | | | |
| Mario Martinez | | | | | | | | | |
| 132794 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 7:40:03 AM | | | | |
| Carrasco, Danny | | Attention Ruben R, or Danny C. need fuel for gas operated tools and diesel fuel for tractor. | | | | | | | |
| Mario Martinez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|--|-------------|-------------------------|-----------------------|------------------|-------------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Riverside ES | | | | | | | | | |
| 126703 | | | | | 12/17/2014 | | 152 | | \$0.00 |
| Medium | Work In Progress | | | 12/17/2014 9:35:14 AM | | | | | |
| Orozco, Daniel | AS PER INSPECTION REPORT, DRAINS ON LEFT SIDE OF SERVING LANE ARE NOT WORKING PROPERLY, WATER IS BEING DISPENSED MANUALLY. | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132199 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:28 AM | | | | | |
| Orozco, Daniel | Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132678 | | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 5/11/2015 2:35:22 PM | | | | | |
| Orozco, Daniel | OVEN IS NOT HEATING. SNP MANAGER SANTA N. 589.2550 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 131963 | | | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | 4/28/2015 11:18:46 AM | | | | | |
| Orozco, Daniel | FREEZER AT 20 DEGREES. SNP MANAGER SANTA N. 589-2550 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132221 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:42 AM | | | | | |
| Orozco, Daniel | Monthly - Riverside ES Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 54 Work Orders | | | Avg. Age of WO's | 55 | | Total for Riverside ES | 0 | | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|--|----------------------------|--------------|-------|---------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | RTC - Alliance | | | | | | | |
| 131585 | | | | | 4/20/2015 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | | 4/20/2015 9:48:35 AM | | | | |
| Moncayo, Fernando | Mr. Avalos is requesting ramp be fixed post and blanks separated Mr. Hawkins and Arreola's portables and to clean campus | | | | | | | | |
| Gloria Delgado | | | | | | | | | |
| 131942 | | Portables | | | 4/27/2015 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 4/27/2015 5:28:31 PM | | | | |
| Moncayo, Fernando | need ramps painted for the summer all 3 ramps | | | | | | | | |
| Gloria Delgado | | | | | | | | | |
| 132571 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 4:59:40 PM | | | | |
| Moncayo, Fernando | Would it be possible for the RTC to have hose on campus we planted and need one. We need to bother the Peak every time we need to water. Thank you | | | | | | | | |
| Gloria Delgado | | | | | | | | | |
| 132899 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 11:27:02 AM | | | | |
| Aldaz, Bobby | Need barriers between portables to stop the accumulation of sand in the sidewalks Bring the front loader remove access sand | | | | | | | | |
| Gloria Delgado | | | | | | | | | |
| Count: 4 Work Orders | | Avg. Age of WO's 16 | | | Total for RTC - Alliance | | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------------|------------------|---|-------------------------|-------|----------------------|--------------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: San Miguel ES | | | | | | | | | |
| 132316 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:37 AM | | | | |
| Apodaca, Mario | | Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130938 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:30:33 AM | | | | |
| Apodaca, Mario | | Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 2 Work Orders | | | Avg. Age of WO's | | 29 | Total for San Miguel ES | | 0 | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|--|------------------|--------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa ES | | | | | | | | | |
| 131635 | Main Building | Exterior | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 8:15:52 AM | | | | |
| Ontiveros, Joe | Need to replace 4" sewer line covers | | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 125848 | | | | | 11/21/2014 | | 178 | | \$0.00 |
| Medium | Work In Progress | | | | 11/21/2014 2:28:51 PM | | | | |
| Munoz, Michael | need new fencing with gates to prevent students from going into parking lots | | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 131779 | | | | | 4/23/2015 | | 25 | | \$0.00 |
| High | Work In Progress | | | | 4/23/2015 8:41:34 AM | | | | |
| Ontiveros, Joe | Need the locations of the sewer and the electrical conduits at Santa Teresa Elementary. Need to locate the sewer line between 4 feet and 6 feet from the end of the fire lane off of the C wing Please check e-mail for photo 218 and 219. Will need a measurement from the ground level to the top of the sewer pipe, including photos and size of pipe. Need to locate the conduits from 2 feet to 4 feet from the fire lane. See e-mail for photo 220 and 221. Also will need a measurement from the ground level to the top and bottom of the conduits, the number of conduits, including photos and size of conduits. If possible need measurements by April 24, 2015 to share with Engineer for drawing requested by next week. For information or details call Ralph Gallegos at 882-6921. Thanks | | | | | | | | |
| Dominique Esparza | | | | | | | | | |
| 129325 | Main Building | Portables | | | 2/26/2015 | | 81 | | \$0.00 |
| Medium | Work In Progress | Portable A-051 | | | 2/26/2015 7:49:42 AM | | | | |
| Ambriz, Juan | Need to Install shelve | | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 130431 | Main Building | Portables | | | 3/20/2015 | | 59 | | \$0.00 |
| Medium | Work In Progress | music portable E | | | 3/20/2015 3:08:39 PM | | | | |
| Ambriz, Juan | Need to hang sound deflectors in music portable | | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 131634 | Main Building | Portables | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 8:14:25 AM | | | | |
| Ambriz, Juan | Need to paint portables A-051, B-052, F-057, and E-056 | | | | | | | | |
| Juan Ambriz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa ES

| | | | | | | | | | |
|--------------|------------------|--|--|--|----------------------|--|----|--|--------|
| 131986 | Main Building | Custodial | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | 200 wing | | | 4/28/2015 3:17:33 PM | | | | |
| Ambriz, Juan | | Need to replace lights in custodial closet | | | | | | | |
| Juan Ambriz | | | | | | | | | |

| | | | | | | | | | |
|--------------|------------------|--|--|--|---------------------|--|-----|--|--------|
| 128454 | Main Building | Restroom (Girls) | | | 2/4/2015 | | 103 | | \$0.00 |
| Medium | Work In Progress | | | | 2/4/2015 9:25:22 AM | | | | |
| Ambriz, Juan | | Need to replace sink faucets in girls 300 hallway restroom | | | | | | | |
| Juan Ambriz | | | | | | | | | |

| | | | | | | | | | |
|--------------|------------------|---|--|--|---------------------|--|-----|--|--------|
| 128456 | Main Building | Restroom (Girls) | | | 2/4/2015 | | 103 | | \$0.00 |
| Medium | Work In Progress | | | | 2/4/2015 9:33:07 AM | | | | |
| Ambriz, Juan | | Need to replace faucet in girls 100 hallway | | | | | | | |
| Juan Ambriz | | | | | | | | | |

| | | | | | | | | | |
|--------------|------------------|-----------------------------------|--|--|----------------------|--|----|--|--------|
| 131798 | Main Building | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 2:22:54 PM | | | | |
| Ambriz, Juan | | Need to set-up art display at GMS | | | | | | | |
| Juan Ambriz | | | | | | | | | |

| | | | | | | | | | |
|--------------|------------------|--|--|--|----------------------|--|----|--|--------|
| 131639 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 8:24:21 AM | | | | |
| Ambriz, Juan | | As per Ms. Tarin need to paint cafeteria | | | | | | | |
| Juan Ambriz | | | | | | | | | |

| | | | | | | | | | |
|--------------|------------------|-----------------------------|--|--|----------------------|--|----|--|--------|
| 131505 | | | | | 4/16/2015 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 4/16/2015 3:18:28 PM | | | | |
| Ambriz, Juan | | Need to replace old ladders | | | | | | | |
| Juan Ambriz | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|----------------------|----------|----|--|--------|
| 132341 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:52 AM | | | | |
| Ambriz, Juan | | Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

| | | | | | | | | | |
|--------------|------------------|--|--|--|---------------------|--|----|--|--------|
| 132156 | Main Building | | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | Conference | | | 5/1/2015 2:54:50 PM | | | | |
| Ambriz, Juan | | As per Ms. Barraza need to install window blinds in conference room (almond) | | | | | | | |
| Juan Ambriz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa ES | | | | | | | | | |
| 132256 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:03 AM | | | | |
| Ambriz, Juan | | Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132257 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:03 AM | | | | |
| Ambriz, Juan | | Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132258 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:04 AM | | | | |
| Ambriz, Juan | | Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132635 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 5/10/2015 12:23:44 AM | | | | |
| Ambriz, Juan | | Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129276 | Main Building | Office | | | 2/25/2015 | | 82 | | \$0.00 |
| Medium | Work In Progress | Parent room | | | 2/25/2015 9:41:19 AM | | | | |
| Ambriz, Juan | | Need to Install blinds in old Parent Room now book room office 101" x 90" | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 131796 | Main Building | Hallway/Corridor | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | 100 hallway | | | 4/23/2015 2:18:54 PM | | | | |
| Ambriz, Juan | | Need to replace lights in 100 hallway | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 130399 | Main Building | Classroom | | | 3/19/2015 | | 60 | | \$0.00 |
| Medium | Work In Progress | Room #108 | | | 3/19/2015 3:44:18 PM | | | | |
| Ambriz, Juan | | Need to replace leaky sink faucet in room #108 | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 129662 | | Classroom | | | 3/2/2015 | | 77 | | \$0.00 |
| Medium | Work In Progress | Room #103 | | | 3/2/2015 3:55:40 PM | | | | |
| Ambriz, Juan | | Need to mount smart board on wall | | | | | | | |
| Juan Ambriz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|------------------|------------------|---|--|--|-----------------------|--|----|--|--------|
| Location: | | Santa Teresa ES | | | | | | | |
| 129663 | Main Building | Classroom | | | 3/2/2015 | | 77 | | \$0.00 |
| Medium | Work In Progress | Room #205 | | | 3/2/2015 3:56:29 PM | | | | |
| Ambriz, Juan | | Need to mount smartboard on wall | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 129275 | Main Building | Library | | | 2/25/2015 | | 82 | | \$0.00 |
| Medium | Work In Progress | | | | 2/25/2015 9:30:35 AM | | | | |
| Ambriz, Juan | | Need to Install blinds in Library in case of a lockdown | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 132729 | Main Building | Classroom | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | Room #212 | | | 5/12/2015 10:53:19 AM | | | | |
| Ambriz, Jose | | Need to check cooling unit in room #212 not working properly | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 132848 | Main Building | Classroom | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | Room #104 | | | 5/13/2015 3:49:23 PM | | | | |
| Ambriz, Jose | | Need to repair cooling unit leaking water | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 132901 | Main Building | Custodial | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 12:58:46 PM | | | | |
| Carbajal, Jimmy | | Jimmy buenas tardes.... Tengo un aspiradora que tiene falso contacto en el switch. Porfavor si me la puede arreglar. Gracias. | | | | | | | |
| Ivan Rodriguez | | | | | | | | | |
| 132902 | | Office | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 1:12:58 PM | | | | |
| Gonzales, Camilo | | Pick up obsolete items and return to IMWHSE for disposal. Thank you. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 132435 | | Office | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 3:05:14 PM | | | | |
| Gonzales, Camilo | | Pick up obsolete computer monitors (44). Return to IMWHSE for disposal. Thank You. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa ES

131778 4/23/2015 25 \$0.00

High Work In Progress 4/23/2015 8:40:05 AM

Castillo, Carlos

Need the locations of the sewer and the electrical conduits at Santa Teresa Elementary. Need to locate the sewer line between 4 feet and 6 feet from the end of the fire lane off of the C wing Please check e-mail for photo 218 and 219. Will need a measurement from the ground level to the top of the sewer pipe, including photos and size of pipe. Need to locate the conduits from 2 feet to 4 feet from the fire lane. See e-mail for photo 220 and 221. Also will need a measurement from the ground level to the top and bottom of the conduits, the number of conduits, including photos and size of conduits. If possible need measurements by April 24, 2015 to share with Engineer for drawing requested by next week. For information or details call Ralph Gallegos at 882-6921. Thanks

Dominique Esparza

126757 Main Building Classroom 12/18/2014 151 \$0.00

Medium Work In Progress parent room 300 12/18/2014 1:16:34 PM

Castillo, Carlos

Need to Install electrical outlet for smart board

Juan Ambriz

131918 Main Building Exterior 4/27/2015 21 \$0.00

Medium Work In Progress P.E. Canopy 4/27/2015 2:29:22 PM

Castillo, Carlos

Electrical breakers keep tripping

Juan Ambriz

132223 5/3/2015 5/24/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:43 AM

Orozco, Daniel

Monthly- Santa Teresa ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

131723 4/22/2015 26 \$0.00

Medium Work In Progress 4/22/2015 9:53:33 AM

Orozco, Daniel

REACH IN REFRIGERATOR IS AT 42 DEGREES. SNP MANAGER MARINA R. 589.3439

Maritza Gonzalez

132200 5/3/2015 5/24/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:29 AM

Orozco, Daniel

Monthly- Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

5/18/2015 9:32:33 AM

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|----------------------------------|-----------------------|------------------|---------------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa ES | | | | | | | | | |
| 130299 | | | | | 3/18/2015 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | | 3/18/2015 8:48:47 AM | | | | |
| Orozco, Daniel | | DOOR STRIP ON WALK IN DOOR IS COMING OFF. SAFETY HAZARD. SNP MANAGER MARINA R. 589-3439. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 130196 | | | | | 3/16/2015 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | | 3/16/2015 2:41:20 PM | | | | |
| Orozco, Daniel | | As per fire inspection, exhaust fan not working. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 124391 | | | | | 10/21/2014 | | 209 | | \$0.00 |
| Medium | Work In Progress | | | | 10/21/2014 10:54:28 | | | | |
| Orozco, Daniel | | WALK IN ENTRANCE-FLOOR IS LIFTING. SNP MANAGER MARINA R. 589.3436 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 127742 | Main Building | Storage | | | 1/21/2015 | | 117 | | \$0.00 |
| Medium | Work In Progress | New storage | | | 1/21/2015 9:12:36 AM | | | | |
| Gonzalez, Salvador | | Need to install ramp in new storage building | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 127846 | Main Building | Storage | | | 1/23/2015 | | 115 | | \$0.00 |
| Medium | Work In Progress | new storage | | | 1/23/2015 11:18:22 AM | | | | |
| Gonzalez, Salvador | | Need a new ramp on new storage | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 127847 | Main Building | Exterior | | | 1/23/2015 | | 115 | | \$0.00 |
| Medium | Work In Progress | | | | 1/23/2015 11:20:13 AM | | | | |
| Gonzalez, Salvador | | Need to remove steel posts behind kitchen due to new fence installed | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| Count: 41 Work Orders | | Avg. Age of WO's 53 | | Total for Santa Teresa ES | | 0 | \$0.00 | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|-----------------------|--|-----|--|--------|
| Location: | | Santa Teresa HS | | | | | | | |
| 130086 | | Parking Lot | | | 3/12/2015 | | 67 | | \$0.00 |
| Medium | Work In Progress | | | | 3/12/2015 10:19:14 AM | | | | |
| Gonzalez, Salvador | | Main Entrance to parking area- Need to replace two large roll gates with swing gates - 4 each | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 127645 | Main Building | Parking Lot | | | 1/16/2015 | | 122 | | \$0.00 |
| Medium | Work In Progress | student parking | | | 1/16/2015 11:30:59 AM | | | | |
| Gonzalez, Salvador | | Traffic control for after and before school see Rick for further assistance. There has been parental concerns with this issue and we need address the problem. | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 127644 | Main Building | Athletic Field | | | 1/16/2015 | | 122 | | \$0.00 |
| Medium | Work In Progress | Softball | | | 1/16/2015 11:27:24 AM | | | | |
| Gonzalez, Salvador | | Batting cage for softball field please see Ms Contreras and Rick for futher guidance | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 132752 | Vocational | Classroom | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | 805/800 | | | 5/12/2015 3:14:17 PM | | | | |
| Gonzalez, Salvador | | chain-link fence in area needs to be fixed | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 127419 | | | | | 1/12/2015 | | 126 | | \$0.00 |
| Medium | Work In Progress | | | | 1/12/2015 3:25:10 PM | | | | |
| Gonzalez, Salvador | | the wire mesh to some goose neck has fallen off need to be replace with some expandable metal or new wire mesh need two at 37x38 | | | | | | | |
| Daniel Sotelo | | | | | | | | | |
| 128823 | Main Building | Exterior | | | 2/11/2015 | | 96 | | \$0.00 |
| Medium | Work In Progress | outside front | | | 2/11/2015 4:29:15 PM | | | | |
| Ronquillo, Ruben | | Small visitors signs to attached to present handicap signs, aluminum signage above culinary arts and NJROTC classroom. Install sign posts in faculty parking lot for administration for further direction please see Mr. W or Mr. Ronquillo | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 130533 | Main Building | Athletic Field | | | 3/24/2015 | | 55 | | \$0.00 |
| Medium | Work In Progress | concession | | | 3/24/2015 3:45:14 PM | | | | |
| Llanez, Rick | | Two pine trees removed from the west side of the concession. Please see Rick for further instructions. | | | | | | | |
| Loraine Soriano | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------|--|------------------------|-------------|-------------------|-----------------------|--------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 124799 | Main Building | Athletic Field | | | 10/30/2014 | | 200 | | \$0.00 |
| Medium | Work In Progress | softball | | | 10/30/2014 3:57:02 PM | | | | |
| Llanez, Rick | Windscreen missing to complete the field. Not complete in the outfield. | | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 128388 | Gymnasium | Athletic Field | | | 2/3/2015 | | 104 | | \$0.00 |
| Medium | Work In Progress | baseball field | | | 2/3/2015 9:33:05 AM | | | | |
| Llanez, Rick | Baseball field several request for wind screen, season has started and no progress has been made | | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 131968 | Gymnasium | Athletic Field | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | soccer field | | | 4/28/2015 12:30:00 PM | | | | |
| Llanez, Rick | Soccer field is in need of reseeding and/or sod replacement for next season. Work order placed earlier in the year. Lots of holes and is unsafe for athletes. | | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 131969 | Main Building | Athletic Field | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | soccer field | | | 4/28/2015 12:30:49 PM | | | | |
| Llanez, Rick | Place extra goal post in soccer field for extra field for football use | | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 131970 | Main Building | Athletic Field | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | football visitor | | | 4/28/2015 12:32:36 PM | | | | |
| Llanez, Rick | Bleachers on visitor side need either a rail to hold on to as fans are walking up bleachers or replace bleachers as they as it is very difficult to walk up without rails. | | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 131971 | Main Building | Athletic Field | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | Football field | | | 4/28/2015 12:34:07 PM | | | | |
| Llanez, Rick | Bleachers were not finished on the home side of football field, we are requesting if there is anyway we can finish the bleachers. | | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 121492 | Main Building | Exterior | | | 8/20/2014 | | 271 | | \$0.00 |
| Medium | Work In Progress | sidewalk | | | 8/20/2014 8:59:58 AM | | | | |
| Llanez, Rick | Sidewalk toward arroyo has hallow areas where water has taken sand out from under it. | | | | | PENDING CONTRACTOR | | | |
| Loraine Soriano | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 128091 | | | | | 1/29/2015 | | 109 | | \$0.00 |
| Medium | Work In Progress | | | | 1/29/2015 10:25:58 AM | | | | |
| Orozco, Daniel | | The technician from Ecolab came and checked dishwasher, He stated that the wash tank Gauge needs to be replaced is not working at all. SNP Manager Olga B. 589.5332 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132201 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:30 AM | | | | |
| Orozco, Daniel | | Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PMSchedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132224 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:44 AM | | | | |
| Orozco, Daniel | | Monthly - Santa Teresa HS Fire Suppression Insp. - Refer to PMSchedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 127839 | Dressing Rooms | Dressing Room | | | 1/23/2015 | | 115 | | \$0.00 |
| Medium | Work In Progress | | | | 1/23/2015 10:19:52 AM | | | | |
| Castillo, Carlos | | As per Coach Dotson, the basketball timers in dressing rooms are not working properly. | | | | | | | |
| Carlos Castillo | | | | | | | | | |
| 132707 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 7:50:07 AM | | | | |
| Castillo, Carlos | | Please disconnect and reconnect power to Nurses desk while flooring is being installed. Check with local staff for times and dates. | | | | | | | |
| 131627 | | | | | | | | | |
| Medium | Work In Progress | Portables | | | 4/20/2015 | | 28 | | \$0.00 |
| Castillo, Carlos | | Nurse | | | 4/20/2015 4:24:44 PM | | | | |
| Castillo, Carlos | | Please install electrical outlet in Nurses portable by cabinet | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 132424 | Main Building | Classroom | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | 312 | | | 5/5/2015 11:07:32 AM | | | | |
| Diaz, David | | white boards need to be set up in classroom | | | | | | | |
| Loraine Soriano | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--|------------------|--------------|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 132821 | Main Building | Office | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | Admin office | | | 5/13/2015 12:08:36 PM | | | | |
| Diaz, David | | | | | | | | | |
| Move shelves in storage area to make room for refrigerator | | | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 132283 | | | | | 5/3/2015 | 6/3/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:18 AM | | | | |
| Diaz, David | | | | | | | | | |
| Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132284 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:19 AM | | | | |
| Diaz, David | | | | | | | | | |
| Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132285 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:19 AM | | | | |
| Diaz, David | | | | | | | | | |
| Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132706 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 7:38:04 AM | | | | |
| Diaz, David | | | | | | | | | |
| Please install cabinets in Nurses portable, as per nurses instruction. Discard any unwanted or damaged cabinets. | | | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 131548 | Vocational | Classroom | | | 4/17/2015 | | 31 | | \$0.00 |
| Medium | Work In Progress | 805 | | | 4/17/2015 2:01:48 PM | | | | |
| Castillo, Carlos | | | | | | | | | |
| Add new circuit of 120vas well as adding switch for compressor. Please see Mr. Bautista for further explanation | | | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 132820 | Main Building | Restroom | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | Girls locker | | | 5/13/2015 12:07:35 PM | | | | |
| Castillo, Carlos | | | | | | | | | |
| Lights are not working in bathroom. | | | | | | | | | |
| Loraine Soriano | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-------|-----------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 126710 | GYM (2009) | Gym | | | 12/17/2014 | | 152 | | \$0.00 |
| Medium | Work In Progress | girls lockerroom | | | 12/17/2014 12:21:52 | | | | |
| Castillo, Carlos | | extra electrical outlets in locker needed for use | | | | 4/21/15 Asp Cali request, change to Project | | | |
| Loraine Soriano | | | | | | | | | |
| 132958 | | | | | 5/15/2015 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | | 5/15/2015 9:36:32 AM | | | | |
| Carrasco, Danny | | GISD issued truck 141 needs fuel. Requesting fuel for Polaris and one gallon of fuel mixture for blowers. | | | | | | | |
| David Diaz | | | | | | | | | |
| 132476 | | Office | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 2:49:43 PM | | | | |
| Gonzales, Camilo | | Deliver 1 Gaylord. Thank you. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 132925 | | Office | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 3:18:00 PM | | | | |
| Gonzales, Camilo | | Camilio, please take 2 Gaylords to Emma. Also there is 1 Gaylord that needs to be picked up and delivered to IMWHSE. Thank you. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 132665 | | Office | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 5/11/2015 10:21:02 AM | | | | |
| Gonzales, Camilo | | Pick up obsolete student desks and file cabinet. Deliver to San Miguel for storage. Thank you. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 132037 | | Parking Lot | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 3:13:18 PM | | | | |
| Vallejo, Albert | | Have new entry gate constructed. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 132919 | | | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 2:35:24 PM | | | | |
| Vallejo, Albert | | Replace Auxiliary Gym scoreboard | | | | | | | |
| 129432 | | | | | 2/28/2015 | 3/31/2015 | 79 | | \$0.00 |
| Medium | Work In Progress | | | | 2/28/2015 12:34:44 AM | | | | |
| , | | Yearly - Santa Teresa HS C-11 Evap Coolers Yearly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|--|--|--|----------------------|----------|----|--|--------|
| Location: | | Santa Teresa HS | | | | | | | |
| 129553 | | | | | 3/1/2015 | 4/1/2015 | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 3/1/2015 12:46:30 AM | | | | |
| , | | Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129554 | | | | | 3/1/2015 | 3/9/2015 | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 3/1/2015 12:46:31 AM | | | | |
| , | | Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129555 | | | | | 3/1/2015 | 3/9/2015 | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 3/1/2015 12:46:31 AM | | | | |
| , | | Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132742 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 1:55:02 PM | | | | |
| Lucero, Arnold | | need to empty all storage portables inside shop gate so that site administration can go thru & see what needs to be thrown away. need to generate a separate work order to request trailer on the week of June 1 - 5. Also, do not block shop entrances. | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 132531 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 1:27:26 PM | | | | |
| Lucero, Arnold | | Rodriguez Upholstery will be there on May 15 for Carpet/VCT installation. Please remove all furniture from Marylou's office by May 14 in the afternoon. Call Chuy if you have any questions. thank you. | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 132532 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 1:38:25 PM | | | | |
| Lucero, Arnold | | need to wax "new" vct (only) on May 18th in Marylou's office. | | | | | | | |
| Jesus Estrada | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|---|------------------|---|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 122288 | Main Building | Hallway/Corridor | | | 9/4/2014 | | 91 | | \$0.00 |
| Medium | Work In Progress | | | 9/4/2014 8:02:23 AM | 12/4/2014 | | | | |
| Lucero, Arnold | Make sure all hallways are burnished 2 times a week. (Assign to Arnold Lucero) | | 10/17/14 - REMAILED TO ARNOLD; 3/26/15 - REMAILED OUT TO ARNOLD, ASP CHUY - ARNOLD PLEASE MAKE SURE TO TAKE CARE OF THIS ON A WEEKLY BASIS. | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 127342 | | | | | 1/11/2015 | 1/27/2015 | 127 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2015 12:29:46 AM | | | | | |
| Lucero, Arnold | Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details. | | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 130414 | Main Building | | | | 3/20/2015 | | 59 | | \$0.00 |
| Medium | Work In Progress | | | 3/20/2015 8:11:26 AM | | | | | |
| Lucero, Arnold | clean off dead bugs inside light fixtures they are all down the hallways | | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 131229 | | | | | 4/12/2015 | 4/28/2015 | 36 | | \$0.00 |
| Medium | Work In Progress | | | 4/12/2015 12:23:33 AM | | | | | |
| Lucero, Arnold | Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132374 | Cafeteria (2005) | Restroom | | | 5/4/2015 | | 14 | | \$0.00 |
| High | Work In Progress | | | 5/4/2015 1:47:15 PM | | | | | |
| Lucero, Arnold | Scrub all walls and stalls top to bottom | | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 129836 | | | | | 3/5/2015 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 3/5/2015 3:16:09 PM | | | | | |
| Estrada, Jesus | Nursing Portable - replace carpet with VCT or Linoleum with welded seams. | | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 130994 | | Gym | | | 4/6/2015 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 4/6/2015 11:38:23 AM | | | | | |
| Estrada, Jesus | varnish (2) gym floors | | | | | | | | |
| Jesus Estrada | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa HS

| | | | | | | | | | |
|--------|-------------|------|--|--|-----------|--|----|--|--------|
| 131352 | Locker Room | Roof | | | 4/14/2015 | | 34 | | \$0.00 |
|--------|-------------|------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/14/2015 7:58:27 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ambriz, Jose
order new H & C rooftop units for the locker rooms.
Installation to be done by roofing contractor

Alfredo Holguin

| | | | | | | | | | |
|--------|----------------|--|--|--|-----------|--|---|--|--------|
| 132677 | Annex Building | | | | 5/11/2015 | | 7 | | \$0.00 |
|--------|----------------|--|--|--|-----------|--|---|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/11/2015 2:19:40 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ambriz, Jose
Need to replace both boards (display setting) on
Beverage -aired freezer

David Diaz

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|----|--|--------|
| 131613 | | | | | 4/20/2015 | | 28 | | \$0.00 |
|--------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/20/2015 3:42:19 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ambriz, Jose
Please re-charge chiller and monitor for leaks.

Albert Vallejo

| | | | | | | | | | |
|--------|------------|----------------|--|--|----------|--|-----|--|--------|
| 128389 | GYM (2009) | Athletic Field | | | 2/3/2015 | | 104 | | \$0.00 |
|--------|------------|----------------|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | Tennis Courts | | | 2/3/2015 9:34:51 AM | | | | |
|--------|------------------|---------------|--|--|---------------------|--|--|--|--|

Ontiveros, Guadalupe
Tennis courts cement is cracked, along playing surface.

Loraine Soriano

| | | | | | | | | | |
|--------|--|----------------|--|--|-----------|--|-----|--|--------|
| 119584 | | Athletic Field | | | 7/18/2014 | | 304 | | \$0.00 |
|--------|--|----------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/18/2014 1:44:53 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ontiveros, Guadalupe
JD tractor 3005 clutch needs to be replaced.

Guadalupe Ontiveros

| | | | | | | | | | |
|--------|---------------|----------|--|--|----------|--|-----|--|--------|
| 122320 | Main Building | Exterior | | | 9/4/2014 | | 256 | | \$0.00 |
|--------|---------------|----------|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Admin/handicap | | | 9/4/2014 11:39:20 AM | | | | |
|--------|------------------|----------------|--|--|----------------------|--|--|--|--|

Ontiveros, Guadalupe
If concrete curbs can be placed in parking to keep cars
from obstructing access to sidewalks for wheelchairs

Loraine Soriano

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|----|--|--------|
| 131915 | | | | | 4/27/2015 | | 21 | | \$0.00 |
|--------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/27/2015 1:35:18 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ontiveros, Joe
KITCHEN-TOILET IS NOT FLUSHING SNP MANAGER
OLGA B. 589.5332

Maritza Gonzalez

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|----|--|--------|
| 130704 | | | | | 3/30/2015 | | 49 | | \$0.00 |
|--------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | 600 HALLWAY | | | 3/30/2015 9:48:46 AM | | | | |
|--------|------------------|-------------|--|--|----------------------|--|--|--|--|

Ontiveros, Joe
NEED A PLUMBER TO UNPLUG THE DRAIN ON THE
WATER FOUNTAIN IN 600 HALLWAY.

Marylou Jimenez

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 130487 | | | | | 3/23/2015 | | 56 | | \$0.00 |
| High | Work In Progress | | | | 3/23/2015 3:57:48 PM | | | | |
| Ontiveros, Joe | | we need to line locate where sidewalk is to be install. will mark area. gas and water. Mr. rick can show area. | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 131377 | | | | | 4/14/2015 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | | 4/14/2015 11:06:56 AM | | | | |
| Ontiveros, Joe | | Nursing Portable - Install lavatory and commode for new staff restroom in room on east side between school nurse area and area formerly used by La Clinica De Familia | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 125544 | | | | | 11/13/2014 | | 186 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2014 4:25:33 PM | | | | |
| Ontiveros, Joe | | Room 511 Order and access panel under sink to provide access to gas shut off. | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 125615 | | | | | 11/17/2014 | | 182 | | \$0.00 |
| Medium | Work In Progress | | | | 11/17/2014 9:25:00 AM | | | | |
| Ontiveros, Joe | | Science Room 515 - Repair water and gas lines to lab tables - install new signs on Gas Shut Off Valve locations | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 125620 | | | | | 11/17/2014 | | 182 | | \$0.00 |
| Medium | Work In Progress | | | | 11/17/2014 9:37:18 AM | | | | |
| Ontiveros, Joe | | Science Room 508 - Repair gas and water lines to lab tables and install new signs at locations of Gas Shut Off Valve. | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 132806 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 9:20:33 AM | | | | |
| Ontiveros, Joe | | Varsity football locker room restrooms are backing up. | | | | | | | |
| Jaime Mijarez | | | | | | | | | |
| 132807 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 9:22:55 AM | | | | |
| Ontiveros, Joe | | Culinary restrooms are backing up. | | | | | | | |
| Jaime Mijarez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa HS

| | | | | | | | | | |
|--------|------------------|--------|--|--|----------------------|--|----|--|--------|
| 131875 | Main Building | Office | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | | | | 4/24/2015 3:23:03 PM | | | | |

Estrada, Jesus
 Marylou Jimenez/office
 Marylou will be receiving new furniture for her office on May 26,2015. She is requesting to have the carpet and floor tile to be replaced. The carpet is old faded,worn out,and when shampooed it lets out a very bad Oder. Floor Tile is just as old with visible cracks and scratches. Marylou will let you know of the carpet and floor tile colors she wants. Cove base will be changed to black. Requesting if possible for work to be done on the first week of June and then she will call the furniture company to have them deliver her office furniture.

Jaime Mijarez

| | | | | | | | | | |
|--------|------------------|------------------|--|--|---------------------|--|-----|--|--------|
| 128380 | GYM (2009) | Football Field | | | 2/3/2015 | | 104 | | \$0.00 |
| Medium | Work In Progress | outside football | | | 2/3/2015 8:16:52 AM | | | | |

Mijarez, Jaime
 Wall on the outside of football field house needs to be painted the same as the other buildings. Also wall along football field needs painting.

Loraine Soriano

| | | | | | | | | | |
|--------|------------------|---------------|--|--|---------------------|--|-----|--|--------|
| 120624 | Gymnasium | Restroom | | | 8/6/2014 | | 285 | | \$0.00 |
| Medium | Work In Progress | soccer locker | | | 8/6/2014 9:19:21 AM | | | | |

Mijarez, Jaime
 Missing toilet seat in one of the stalls

Loraine Soriano

| | | | | | | | | | |
|--------|------------------|--------------|--|--|----------------------|--|----|--|--------|
| 128820 | GYM (2009) | Exterior | | | 2/11/2015 | | 96 | | \$0.00 |
| Medium | Work In Progress | wall outside | | | 2/11/2015 4:23:11 PM | | | | |

Mijarez, Jaime
 wall in the exterior of football locker room in need of painting. Please try to match new gym exterior

Loraine Soriano

| | | | | | | | | | |
|--------|------------------|-----------|--|--|----------------------|--|----|--|--------|
| 132425 | AnnexBuilding | Classroom | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | 707 | | | 5/5/2015 11:08:50 AM | | | | |

Ontiveros, Joe
 Garbage disposal is not functioning

Loraine Soriano

| | | | | | | | | | |
|--------|------------------|------------------|--|--|---------------------|--|----|--|--------|
| 131021 | Gymnasium | Hallway/Corridor | | | 4/6/2015 | | 42 | | \$0.00 |
| Medium | Work In Progress | bathroom across | | | 4/6/2015 4:05:20 PM | | | | |

Ontiveros, Joe
 clogged toilet in boys restroom across from auxiliary gym

Loraine Soriano

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 123303 | Main Building | Classroom | | | 9/26/2014 | | 234 | | \$0.00 |
| Medium | Work In Progress | 215 | | | 9/26/2014 2:16:35 PM | | | | |
| Ontiveros, Joe | | Toilet malfunctioning | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 124173 | AnnexBuilding | Classroom | | | 10/15/2014 | | 215 | | \$0.00 |
| Medium | Work In Progress | culinary | | | 10/15/2014 9:51:56 AM | | | | |
| Ontiveros, Joe | | Dryer not working | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 120184 | Main Building | Classroom | | | 8/1/2014 | | 290 | | \$0.00 |
| Medium | Work In Progress | 610 | | | 8/1/2014 12:26:38 PM | | | | |
| Ontiveros, Joe | | Install new range in room 610 | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 125545 | | Classroom | | | 11/13/2014 | | 186 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2014 4:29:17 PM | | | | |
| Ontiveros, Joe | | Science Room 511- Install new signs on Gas shut off access panels 2) to read "gas Shut Off Valve" | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 125409 | AnnexBuilding | Classroom | | | 11/10/2014 | | 189 | | \$0.00 |
| Medium | Work In Progress | culinary | | | 11/10/2014 4:25:12 PM | | | | |
| Ontiveros, Joe | | Dryer has not been hooked | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 127480 | Main Building | Classroom | | | 1/13/2015 | | 125 | | \$0.00 |
| Medium | Work In Progress | 215 | | | 1/13/2015 2:26:17 PM | | | | |
| Ontiveros, Joe | | Student shower needs a knob. | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 127270 | Vocational | Classroom | | | 1/8/2015 | | 130 | | \$0.00 |
| Medium | Work In Progress | 801 | | | 1/8/2015 3:55:21 PM | | | | |
| Ontiveros, Joe | | Water leak, replace valves in water stations please see Jaime | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 132957 | | | | | 5/15/2015 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | | 5/15/2015 9:25:02 AM | | | | |
| Ontiveros, Joe | | science room 511 floor drain backing up with dirty water. | | | | | | | |
| David Diaz | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa HS

| | | | | | | | | | |
|--------|---------------|--------|--|--|----------|--|----|--|--------|
| 129948 | Main Building | Office | | | 3/9/2015 | | 70 | | \$0.00 |
|--------|---------------|--------|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|------------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | Attendance | | | 3/9/2015 2:13:27 PM | | | | |
|--------|------------------|------------|--|--|---------------------|--|--|--|--|

Mijarez, Jaime If you could please fix the plastic mold on the floor by the fire extinguisher in the attendance office?

Loraine Soriano

| | | | | | | | | | |
|--------|---------------|--------|--|--|------------|--|-----|--|--------|
| 124096 | Main Building | Office | | | 10/13/2014 | | 217 | | \$0.00 |
|--------|---------------|--------|--|--|------------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | Training room | | | 10/13/2014 3:46:12 PM | | | | |
|--------|------------------|---------------|--|--|-----------------------|--|--|--|--|

Mijarez, Jaime Mr. Munoz needs assistance with some hooks please see mr. Munoz for further clarification

Loraine Soriano

| | | | | | | | | | |
|--------|----------------|-----------|--|--|----------|--|----|--|--------|
| 129733 | Annex Building | Classroom | | | 3/3/2015 | | 76 | | \$0.00 |
|--------|----------------|-----------|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | culinary | | | 3/3/2015 3:38:40 PM | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|

Mijarez, Jaime Racks and picture frames need hanging

Loraine Soriano

| | | | | | | | | | |
|--------|----------------|-----------|--|--|----------|--|----|--|--------|
| 129735 | Annex Building | Classroom | | | 3/3/2015 | | 76 | | \$0.00 |
|--------|----------------|-----------|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | culinary | | | 3/3/2015 3:40:30 PM | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|

Mijarez, Jaime Shelves needs holder

Loraine Soriano

| | | | | | | | | | |
|--------|----------------|-----------|--|--|----------|--|----|--|--------|
| 129736 | Annex Building | Classroom | | | 3/3/2015 | | 76 | | \$0.00 |
|--------|----------------|-----------|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | culinary | | | 3/3/2015 3:41:20 PM | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|

Mijarez, Jaime coat rack needs hanging

Loraine Soriano

| | | | | | | | | | |
|--------|--|-----------|--|--|-----------|--|----|--|--------|
| 131745 | | Classroom | | | 4/22/2015 | | 26 | | \$0.00 |
|--------|--|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | MARYLOU | | | 4/22/2015 3:03:36 PM | | | | |
|--------|------------------|---------|--|--|----------------------|--|--|--|--|

Mijarez, Jaime 10 BOOK SHELVES NEED TO BE ASSEMBLED.

Marylou Jimenez

| | | | | | | | | | |
|--------|---------------|-----------|--|--|----------|--|----|--|--------|
| 132427 | Main Building | Classroom | | | 5/5/2015 | | 13 | | \$0.00 |
|--------|---------------|-----------|--|--|----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | 409 | | | 5/5/2015 11:11:27 AM | | | | |
|--------|------------------|-----|--|--|----------------------|--|--|--|--|

Mijarez, Jaime Window does not open and shut properly.

Loraine Soriano

| | | | | | | | | | |
|--------|---------------|-----------|--|--|-----------|--|----|--|--------|
| 130192 | Main Building | Classroom | | | 3/16/2015 | | 63 | | \$0.00 |
|--------|---------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | 610 | | | 3/16/2015 1:47:04 PM | | | | |
|--------|------------------|-----|--|--|----------------------|--|--|--|--|

Mijarez, Jaime Need a spice rack hung on wall

Loraine Soriano

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa HS

| | | | | | | | | | |
|--------|---------------|-----------|--|--|-----------|--|-----|--|--------|
| 127813 | Main Building | Classroom | | | 1/22/2015 | | 116 | | \$0.00 |
|--------|---------------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | 211 | | | 1/22/2015 2:59:55 PM | | | | |
|--------|------------------|-----|--|--|----------------------|--|--|--|--|

Mijarez, Jaime Air conditioner does not turn off

Loraine Soriano

| | | | | | | | | | |
|--------|---------------|-----------|--|--|----------|--|-----|--|--------|
| 128512 | Main Building | Classroom | | | 2/5/2015 | | 102 | | \$0.00 |
|--------|---------------|-----------|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | 608 | | | 2/5/2015 9:43:04 AM | | | | |
|--------|------------------|-----|--|--|---------------------|--|--|--|--|

Mijarez, Jaime Heater blowing cold air

Loraine Soriano

| | | | | | | | | | |
|--------|---------------|-----------|--|--|-----------|--|----|--|--------|
| 129012 | Main Building | Classroom | | | 2/18/2015 | | 89 | | \$0.00 |
|--------|---------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | 215 | | | 2/18/2015 8:44:09 AM | | | | |
|--------|------------------|-----|--|--|----------------------|--|--|--|--|

Mijarez, Jaime Mice in classroom

Loraine Soriano

| | | | | | | | | | |
|--------|------------|-----------|--|--|------------|--|-----|--|--------|
| 126449 | Vocational | Classroom | | | 12/10/2014 | | 159 | | \$0.00 |
|--------|------------|-----------|--|--|------------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | 807 | | | 12/10/2014 9:20:47 AM | | | | |
|--------|------------------|-----|--|--|-----------------------|--|--|--|--|

Mijarez, Jaime paper towel dispenser

Loraine Soriano

| | | | | | | | | | |
|--------|------------|-----------|--|--|------------|--|-----|--|--------|
| 126450 | Vocational | Classroom | | | 12/10/2014 | | 159 | | \$0.00 |
|--------|------------|-----------|--|--|------------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | 807 | | | 12/10/2014 9:21:54 AM | | | | |
|--------|------------------|-----|--|--|-----------------------|--|--|--|--|

Mijarez, Jaime paper towel dispenser near sink area

Loraine Soriano

| | | | | | | | | | |
|--------|---------------|-----------|--|--|------------|--|-----|--|--------|
| 124455 | Main Building | Classroom | | | 10/22/2014 | | 208 | | \$0.00 |
|--------|---------------|-----------|--|--|------------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | 314 | | | 10/22/2014 12:30:35 | | | | |
|--------|------------------|-----|--|--|---------------------|--|--|--|--|

Mijarez, Jaime Map strips need center screws, Please refer to Ms. Thornly for further clarification

Loraine Soriano

| | | | | | | | | | |
|--------|----------------|-----------|--|--|------------|--|-----|--|--------|
| 124299 | Annex Building | Classroom | | | 10/17/2014 | | 213 | | \$0.00 |
|--------|----------------|-----------|--|--|------------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | culinary arts | | | 10/17/2014 12:25:41 | | | | |
|--------|------------------|---------------|--|--|---------------------|--|--|--|--|

Mijarez, Jaime Lockers need to be moved to classroom as well as mounted if possible. Please see Ms. Perez for clarification.

Loraine Soriano

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 124301 | Main Building | Classroom | | | 10/17/2014 | | 213 | | \$0.00 |
| Medium | Work In Progress | 209 | | | 10/17/2014 2:45:48 PM | | | | |
| Mijarez, Jaime | | Needs a safety goggle sanitation cabinet installed in classroom. There might be a possibility that an outlet maybe required for this cabinet. Please see Mrs. Nunez for further information and placement of cabinet. | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 123084 | Main Building | Classroom | | | 9/23/2014 | | 237 | | \$0.00 |
| Medium | Work In Progress | Lab C-1 | | | 9/23/2014 3:16:04 PM | | | | |
| Mijarez, Jaime | | Cabinet door in computer lab office in broken. | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 120179 | Main Building | Classroom | | | 8/1/2014 | | 290 | | \$0.00 |
| Medium | Work In Progress | 505 | | | 8/1/2014 11:56:03 AM | | | | |
| Mijarez, Jaime | | Replace pencil sharpner | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 123220 | Main Building | Library | | | 9/25/2014 | | 235 | | \$0.00 |
| Medium | Work In Progress | library | | | 9/25/2014 8:26:27 AM | | | | |
| Mijarez, Jaime | | Air conditioning in office needs to be looked at as it is not working | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 122803 | Cafeteria (2005) | Auditorium | | | 9/15/2014 | | 245 | | \$0.00 |
| Medium | Work In Progress | Theater area | | | 9/15/2014 4:14:10 PM | | | | |
| Mijarez, Jaime | | Workshop lights, restroom not working | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 121267 | Main Building | Classroom | | | 8/15/2014 | | 276 | | \$0.00 |
| Medium | Work In Progress | 608 | | | 8/15/2014 2:08:18 PM | | | | |
| Mijarez, Jaime | | Anchor cabinets | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 121272 | Main Building | Classroom | | | 8/15/2014 | | 276 | | \$0.00 |
| Medium | Work In Progress | 206 | | | 8/15/2014 2:15:43 PM | | | | |
| Mijarez, Jaime | | Remove old white board and old screen | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 119430 | Concession | Athletic Field | | | 7/15/2014 | | 307 | | \$0.00 |
| Medium | Work In Progress | | | | 7/15/2014 11:48:16 AM | | | | |
| Mijarez, Jaime | | Holes in concession building near water fountain have exposed copper tubing | | | | | | | |
| Rosalinda Rodriguez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa HS

129113 Gymnasium Athletic Field 2/20/2015 87 \$0.00

Medium Work In Progress entrance soccer 2/20/2015 10:00:30 AM

Mijarez, Jaime Install signs stating employees only so parents and students do not enter from those areas

Lorraine Soriano

129022 Main Building Parking Lot 2/18/2015 89 \$0.00

Medium Work In Progress parking lot 2/18/2015 10:12:27 AM

Mijarez, Jaime Painting of directionality symbols on parking lot to make traffic flow better

Lorraine Soriano

126748 Main Building Parking Lot 12/18/2014 151 \$0.00

Medium Work In Progress parking lot 12/18/2014 9:41:16 AM

Mijarez, Jaime Painting parking barriers to prevent accidents

Lorraine Soriano

128400 Main Building Parking Lot 2/3/2015 104 \$0.00

Medium Work In Progress Parking Lot 2/3/2015 11:04:36 AM

Mijarez, Jaime Work order placed last year for painting of parking lot for arrows etc., for better flow of traffic.

Lorraine Soriano

132804 5/13/2015 5 \$0.00

Medium Work In Progress 5/13/2015 8:51:25 AM

Mijarez, Jaime Paint for summer projects.

Jaime Mijarez

132340 5/3/2015 5/9/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:33:51 AM

Mijarez, Jaime Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

130083 Gymnasium 3/12/2015 67 \$0.00

Medium Work In Progress 3/12/2015 10:12:11 AM

Mijarez, Jaime Boys Dressing Room - Holes in ceiling (3 each) patch with drywall and tape texture and paint or order access doors and install

Alfredo Holguin

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|-----------------------|-----------|----|--|--------|
| Location: | | Santa Teresa HS | | | | | | | |
| 130740 | | | | | 3/31/2015 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | | 3/31/2015 12:38:10 AM | | | | |
| Mijarez, Jaime | | Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130802 | | | | | 4/5/2015 | 4/21/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:19 AM | | | | |
| Mijarez, Jaime | | Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129516 | | | | | 3/1/2015 | | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 3/1/2015 12:46:08 AM | | | | |
| Mijarez, Jaime | | Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129611 | | | | | 3/1/2015 | 3/7/2015 | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 3/1/2015 12:47:04 AM | | | | |
| Mijarez, Jaime | | Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129466 | | | | | 3/1/2015 | 4/1/2015 | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 3/1/2015 12:45:38 AM | | | | |
| Mijarez, Jaime | | Yearly - Santa Teresa HS A-10 HP Yearly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129506 | | | | | 3/1/2015 | 3/4/2015 | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 3/1/2015 12:46:03 AM | | | | |
| Mijarez, Jaime | | Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 129069 | | | | | 2/19/2015 | | 88 | | \$0.00 |
| Medium | Work In Progress | | | | 2/19/2015 10:32:22 AM | | | | |
| Mijarez, Jaime | | Chiller Alarm - 6:37 PM February 18,2015 Starter Did Not Transition Cprsr 2A. Chiller serviced by David on 2/18/2015. | | | | | | | |
| Jaime Mijarez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|--|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 121254 | Cafeteria (2005) | | | | 8/15/2014 | | 276 | | \$0.00 |
| Medium | Work In Progress | | | 8/15/2014 10:49:31 AM | | | | | |
| Mijarez, Jaime | mens restroom in cafeteria urinal not enough water pressure | | | | | | | | |
| Isaac Holguin | | | | | | | | | |
| 124222 | | | | | 10/16/2014 | | 214 | | \$0.00 |
| Medium | Work In Progress | | | 10/16/2014 7:56:45 AM | | | | | |
| Mijarez, Jaime | Room 400. No cooling in the after noon reported by teacher. The a/c motor gave out. I will need a new 3/4 hp motor with pully and clamps to replace. | | | | | | | | |
| Jaime Mijarez | | | | | | | | | |
| 130857 | | | | | 4/5/2015 | 4/8/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 4/5/2015 12:29:48 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130867 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | 4/5/2015 12:29:53 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130905 | | | | | 4/5/2015 | 4/13/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 4/5/2015 12:30:15 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130906 | | | | | 4/5/2015 | 4/13/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 4/5/2015 12:30:16 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130962 | | | | | 4/5/2015 | 4/11/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 4/5/2015 12:30:46 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 131321 | | | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | COUNSELING | | | 4/13/2015 3:48:34 PM | | | | |
| Mijarez, Jaime | | BULLETIN BOARD NEEDS TO BE MOUNTED IN THE COUNSELING CTR. | | | | | | | |
| Marylou Jimenez | | | | | | | | | |
| 132246 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:57 AM | | | | |
| Mijarez, Jaime | | Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132236 | | | | | 5/3/2015 | 5/6/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:51 AM | | | | |
| Mijarez, Jaime | | Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130837 | | | | | 4/5/2015 | 4/26/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:38 AM | | | | |
| Munoz, Michael | | Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 124792 | Main Building | Athletic Field | | | 10/30/2014 | | 200 | | \$0.00 |
| Medium | Work In Progress | football field | | | 10/30/2014 3:49:56 PM | | | | |
| Munoz, Michael | | Football/soccer score board due to malfunction to box. Scoreboard is about 21 years old. | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 126771 | Main Building | Classroom | | | 12/18/2014 | | 151 | | \$0.00 |
| Medium | Work In Progress | outside behind | | | 12/18/2014 3:30:35 PM | | | | |
| Munoz, Michael | | tire ramps to have access to class room for grocery drop off | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 129509 | | | | | 3/1/2015 | 3/17/2015 | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 3/1/2015 12:46:04 AM | | | | |
| Villalobos, Margret | | Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PMschedule details. | | | | 3/2 - Emailed | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa HS

132239 5/3/2015 5/19/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:53 AM

Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.

Margret Villalobos

130860 4/5/2015 4/21/2015 43 \$0.00

Medium Work In Progress 4/5/2015 12:29:50 AM

Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.

Margret Villalobos

132185 5/3/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:20 AM

Flores, Pete Monthly - STH-UV-0517 PM Service - Refer to PM schedule details.

Margret Villalobos

129734 AnnexBuilding Classroom 3/3/2015 76 \$0.00

Medium Work In Progress classroom 3/3/2015 3:39:32 PM

Lara, Ralph locker does not lock

Loraine Soriano

130124 Main Building Classroom 3/13/2015 66 \$0.00

Medium Work In Progress teachers lounge 3/13/2015 8:54:59 AM

Lara, Ralph door handle lock not working

Loraine Soriano

129731 AnnexBuilding Classroom 3/3/2015 76 \$0.00

Medium Work In Progress culinary 3/3/2015 3:37:58 PM

Lara, Ralph Doors do not lock and front door has problems opening

Loraine Soriano

131857 4/24/2015 24 \$0.00

Medium Work In Progress 4/24/2015 11:43:31 AM

Lara, Ralph Nursing Portable side where Clinica De Familis used to be - window is lose and north side pane does not open.

Alfredo Holguin

129005 Locker Room Football Field 2/18/2015 89 \$0.00

Medium Work In Progress football locker 2/18/2015 8:10:50 AM

Lara, Ralph second request football locker room door is not locking appropriately

Loraine Soriano

5/18/2015 9:32:34 AM

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|----------------------------------|-----------------------|------------------|-----------|---------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 132751 | Main Building | Storage | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | Gator in storage | | | 5/12/2015 3:13:21 PM | | | | |
| Flores, Pete | | Gator needs to be repaired. Tires and other maintenance. | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 129161 | Vocational | Classroom | | | 2/23/2015 | | 84 | | \$0.00 |
| Medium | Work In Progress | 805 | | | 2/23/2015 12:20:03 PM | | | | |
| Lara, Ralph | | Needs keys for flammable cabinets | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 128818 | Main Building | Hallway/Corridor | | | 2/11/2015 | | 96 | | \$0.00 |
| Medium | Work In Progress | mailbox 123 | | | 2/11/2015 4:05:28 PM | | | | |
| Lara, Ralph | | lock not functioning with key | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 131967 | GYM (2009) | Gym | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | Varsity gym | | | 4/28/2015 12:28:32 PM | | | | |
| Lara, Ralph | | We are in need of extra keys for basketball backboards | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| 131033 | Concession | Athletic Field | | | 4/7/2015 | | 41 | | \$0.00 |
| Medium | Work In Progress | baseball field | | | 4/7/2015 9:45:10 AM | | | | |
| Lara, Ralph | | Door knob on concession stand needs to be replaced as soon as possible | | | | | | | |
| Loraine Soriano | | | | | | | | | |
| Count: 142 Work Orders | | Avg. Age of WO's 89 | | Total for Santa Teresa HS | | 0 | | \$0.00 | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa MS | | | | | | | | | |
| 132094 | Gym (1997) | Gym | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | LOBBY | | | 4/30/2015 2:23:09 PM | | | | |
| Lara, Ralph | | 1- FOYER ENTRANCE DOORS DO NOT CLOSE PROPERLY. SECURITY ISSUE. 2- EXTERIOR DOORS NORTHSIDE OF GYM DO NOT CLOSE PROPERLY. SECURITY ISSUE | | | | | | | |
| Laura Parra | | | | | | | | | |
| 132814 | North Building | Hallway/Corridor | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 11:38:29 AM | | | | |
| Lara, Ralph | | Main entrance doors to north building need to be adjusted- | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |
| 131466 | South Building | Office | | | 4/16/2015 | | 32 | | \$0.00 |
| Medium | Work In Progress | SECURITY | | | 4/16/2015 8:32:38 AM | | | | |
| Lara, Ralph | | REMOVE DOOR AND FRAME AND RELOCATE TO A DIFFERENT AREA IN THE SECURITY OFFICE. OFFICE NNEDS TO BE LOCKED WHEN ILLEGAL ITEMS HAVE BEEN CONFISCATED. | | | | | | | |
| Laura Parra | | | | | | | | | |
| 132823 | North Building | Mechanical | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 12:45:07 PM | | | | |
| Lara, Ralph | | Theres a missing handle that needs to be replace in boiler room in northbuilding order to lock door. | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |
| 132352 | North Building | Custodial | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 8:59:29 AM | | | | |
| Villalobos, Margret | | Need Pest Control to fumigate both buildings North and South buildings. | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |
| 132095 | North Building | Portables | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | PORTABLES | | | 4/30/2015 2:24:08 PM | | | | |
| Prospero, Manuel | | PAINTE LABELS OVER ENTRANCE DOORS AS FOLLOWS: 1A 1B 2A 2B 3A 3B | | | | | | | |
| Laura Parra | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|--|-------------|-------------|----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa MS | | | | | | | | | |
| 132343 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:53 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132481 | | | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | 5/6/2015 3:32:30 PM | | | | | |
| Prospero, Manuel | 5/5/15. 2HRS REPLACE CONDENSATE PUMP ON ROOM 50. 2HRS REPLACE CIRCULATION PUMP 500 38. 2HRS TROUBLE SHUTTER A/C ROOM 31. 2HRS REPLACE CEILIN TILES ROOMS 38 40 AND 31. | | | | | | | | |
| Manuel Prospero | | | | | | | | | |
| 132290 | | | | | 5/3/2015 | 6/3/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:22 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132291 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:23 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132292 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:23 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132293 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:24 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132827 | North Building | Classroom | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | 3 & 4 | | 5/13/2015 2:52:41 PM | | | | | |
| Prospero, Manuel | PAINT CLASSROOM DURING SUMMER | | | | | | | | |
| Laura Parra | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days | Labor | Total |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|------|-------|-------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | Aged | Hours | Costs |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa MS

| | | | | | | | | | |
|--------|----------------|-----------|--|--|-----------|--|---|--|--------|
| 132828 | North Building | Classroom | | | 5/13/2015 | | 5 | | \$0.00 |
|--------|----------------|-----------|--|--|-----------|--|---|--|--------|

| | | | | | | | | | |
|--------|------------------|----------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | 16 SAENZ | | | 5/13/2015 2:53:21 PM | | | | |
|--------|------------------|----------|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|-----------------------------------|--|--|--|--|--|--|--|
| Prospero, Manuel | | INSTALL CEILING PROJECTOR BRACKET | | | | | | | |
|------------------|--|-----------------------------------|--|--|--|--|--|--|--|

Laura Parra

| | | | | | | | | | |
|--------|----------------|-----------|--|--|-----------|--|----|--|--------|
| 131924 | North Building | Classroom | | | 4/27/2015 | | 21 | | \$0.00 |
|--------|----------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/27/2015 3:31:26 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|---|--|--|--|--|--|--|--|
| Prospero, Manuel | | WE NEED TO CHANGED 2 CIRCULATION PUMPS ROOM 10. | | | | 4/30/15 As per A. Vallejo, route to BM | | | |
|------------------|--|---|--|--|--|--|--|--|--|

Manuel Prospero

| | | | | | | | | | |
|--------|----------------|-----------|--|--|-----------|--|----|--|--------|
| 130510 | South Building | Classroom | | | 3/24/2015 | | 55 | | \$0.00 |
|--------|----------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 3/24/2015 11:53:57 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|-------------------------------------|--|--|--|--|--|--|--|
| Prospero, Manuel | | Fix 4 broken desk for Mr.Santillan. | | | | | | | |
|------------------|--|-------------------------------------|--|--|--|--|--|--|--|

Ismael Rodriguez

| | | | | | | | | | |
|--------|----------------|---------|--|--|-----------|--|-----|--|--------|
| 126039 | North Building | Kitchen | | | 12/1/2014 | | 168 | | \$0.00 |
|--------|----------------|---------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|-----------------------|--|--|--|--|
| High | Work In Progress | | | | 12/1/2014 11:12:42 AM | | | | |
|------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Prospero, Manuel | | Please remove toilet so floor can be tiled. Rodriguez upholsterys should be there on December 2, 2014 at around 2:00 pm. | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

Jesus Estrada

| | | | | | | | | | |
|--------|----------------|------------------|--|--|------------|--|-----|--|--------|
| 124584 | South Building | Hallway/Corridor | | | 10/24/2014 | | 206 | | \$0.00 |
|--------|----------------|------------------|--|--|------------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | #44-ALLEN | | | 10/24/2014 2:56:08 PM | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Prospero, Manuel | | REMOVE LOCKERS. STUDENTS ARE PUTTING TRASH IN THEM | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

Laura Parra

| | | | | | | | | | |
|--------|----------------|------------------|--|--|----------|--|-----|--|--------|
| 120786 | South Building | Hallway/Corridor | | | 8/8/2014 | | 283 | | \$0.00 |
|--------|----------------|------------------|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | UPSTAIRS | | | 8/8/2014 8:31:33 AM | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|---|--|--|--|--|--|--|--|
| Prospero, Manuel | | PLEASE REMOVE LOCKERS AND INSTALL IN P.E (SEE MS SNYDER) | | | | | | | |
|------------------|--|---|--|--|--|--|--|--|--|

Laura Parra

| | | | | | | | | | |
|--------|----------------|------------------|--|--|----------|--|-----|--|--------|
| 122257 | South Building | Hallway/Corridor | | | 9/3/2014 | | 257 | | \$0.00 |
|--------|----------------|------------------|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | HALL WAY | | | 9/3/2014 3:33:19 PM | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|---|--|--|--|--|--|--|--|
| Prospero, Manuel | | REMOVE LOCKERS FROM WALL OUTSIDE ROOM 44-45. SECOND REQUEST | | | | | | | |
|------------------|--|---|--|--|--|--|--|--|--|

Laura Parra

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa MS | | | | | | | | | |
| 132096 | North Building | Office | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | NORTH OFFICE | | | 4/30/2015 2:25:11 PM | | | | |
| Prospero, Manuel | | 1- PAINT ENTRY DOORS BLACK GLOSS OIL BASED ENAMEL 2- PAINT RAILS ON OUTDOOR STAIRWELLS BLACK | | | | | | | |
| Laura Parra | | | | | | | | | |
| 126528 | North Building | Classroom | | | 12/11/2014 | | 158 | | \$0.00 |
| Medium | Work In Progress | 3-PORTILLO | | | 12/11/2014 12:45:36 | | | | |
| Prospero, Manuel | | 1- EXHAUST FAN IN THE BATHROOM IS NOT WORKING PROPERLY. 2- EXHAUST FAN OVER THE STOVE IS NOT WORKING | | | | | | | |
| Laura Parra | | | | | | | | | |
| 124448 | North Building | Classroom | | | 10/22/2014 | | 208 | | \$0.00 |
| Medium | Work In Progress | 6-BAILEY | | | 10/22/2014 10:51:27 | | | | |
| Prospero, Manuel | | CEILING LEAKING. | | | | | | | |
| Laura Parra | | | | | | | | | |
| 125158 | South Building | Classroom | | | 11/5/2014 | | 194 | | \$0.00 |
| Medium | Work In Progress | 47- | | | 11/5/2014 8:33:40 AM | | | | |
| Prospero, Manuel | | AIR CONDITIONER MAKING LOUD NOISES | | | | | | | |
| Laura Parra | | | | | | | | | |
| 122262 | South Building | Classroom | | | 9/3/2014 | | 257 | | \$0.00 |
| Medium | Work In Progress | 55-WOLLARD | | | 9/3/2014 3:35:43 PM | | | | |
| Prospero, Manuel | | AIR CONDITIONER IS EXTREMELY LOUD AND TILES ARE GETTING WET | | | | | | | |
| Laura Parra | | | | | | | | | |
| 123945 | North Building | Classroom | | | 10/9/2014 | | 221 | | \$0.00 |
| Medium | Work In Progress | 12-CRAVENS | | | 10/9/2014 3:13:19 PM | | | | |
| Prospero, Manuel | | 1- SINK PIPE IS LEAKING- RIGHT SINK 2- BRACKS NEED TO BE REMOVED WITH SCREWS FROM BACK WALL | | | | | | | |
| Laura Parra | | | | | | | | | |
| 130076 | Gym (1997) | Gym | | | 3/12/2015 | | 67 | | \$0.00 |
| Medium | Work In Progress | MS SNYDER | | | 3/12/2015 8:37:03 AM | | | | |
| Prospero, Manuel | | REPAIR POST ON THE NORTH BASKETBALL COURTS FOR A TENNIS NET. PAINT LINES ON THE COURTS OUTSIDE | | | | | | | |
| Laura Parra | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa MS | | | | | | | | | |
| 130744 | | | | | 3/31/2015 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | | 3/31/2015 12:38:12 AM | | | | |
| Prospero, Manuel | | Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130793 | | | | | 4/5/2015 | 4/21/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:14 AM | | | | |
| Prospero, Manuel | | Monthly - Santa Teresa MS A1 (Wall Refr.E/H)(Semi) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130843 | | | | | 4/5/2015 | 4/13/2015 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 4/5/2015 12:29:41 AM | | | | |
| Prospero, Manuel | | Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130531 | | | | | 3/24/2015 | | 55 | | \$0.00 |
| Medium | Work In Progress | | | | 3/24/2015 3:44:07 PM | | | | |
| Prospero, Manuel | | 3/24/15. 2HRS FIXING DOOR ON ROOM 32. 1HR INSTALL DOOR STOPER ROO 31. 2HRS WO 130510. 3HRS REPLACE CEILING TILES ROOM 9. | | | | 3/24/15 - 5 hrs | | | |
| Manuel Prospero | | | | | | | | | |
| 131499 | Gym (1997) | Exterior | | | 4/16/2015 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 4/16/2015 3:09:54 PM | | | | |
| Ontiveros, Joe | | Need to fixed out side drinking fountain next to Mecanical rm in gym area. | | | | | | | |
| Joe Ontiveros | | | | | | | | | |
| 127311 | Gym (1997) | Mechanical | | | 1/9/2015 | | 129 | | \$0.00 |
| Medium | Work In Progress | | | | 1/9/2015 3:15:27 PM | | | | |
| Ontiveros, Joe | | 1/9/15. WE NEED TO REPLACE WATER HEATER ON GYM, IS BROCK (96GALL). | | | | | | | |
| Manuel Prospero | | | | | | | | | |
| 130226 | North Building | Restroom (Girls) | | | 3/17/2015 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | | 3/17/2015 7:52:46 AM | | | | |
| Ontiveros, Joe | | Replace North and South Building girls restroom water faucets with new ones their in bad shape. | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa MS | | | | | | | | | |
| 132956 | North Building | Kitchen | | | 5/15/2015 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | | 5/15/2015 9:11:16 AM | | | | |
| Ontiveros, Joe | | THE LITTLE KITCHEN SINK ON PRPINCIPAL OFFICE IS CLOGG | | | | | | | |
| Manuel Prospero | | | | | | | | | |
| 131952 | North Building | Cafeteria | | | 4/28/2015 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 4/28/2015 7:43:56 AM | | | | |
| Mijarez, Jaime | | Building Mechanic from S.T.H.S to pick up 4 piece stage from S.T.M.S cafeteria from Earth Day event blocking exit doors from cafeteria as per administration thanks. | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |
| 132672 | North Building | Classroom | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | # 3/4 | | | 5/11/2015 12:11:06 PM | | | | |
| Ontiveros, Joe | | BATHROOM FAUCETS CONTINUE TO RUN AFTER USING | | | | | | | |
| Laura Parra | | | | | | | | | |
| 132036 | | Restroom | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 4/29/2015 3:10:50 PM | | | | |
| Ontiveros, Joe | | WE NEED TO REPLACE 6 BROKEN BUBBLERS OUTSIDE. | | | | | | | |
| Manuel Prospero | | | | | | | | | |
| 131788 | North Building | Classroom | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 4/23/2015 12:46:09 PM | | | | |
| Ontiveros, Joe | | The water faucet in room #3 the water keeps running doest shut off. | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |
| 123993 | North Building | Classroom | | | 10/10/2014 | | 220 | | \$0.00 |
| Medium | Work In Progress | | | | 10/10/2014 11:16:43 | | | | |
| Ontiveros, Joe | | Need to replace p-trap in RM#12 | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |
| 130228 | North Building | Kitchen | | | 3/17/2015 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | | 3/17/2015 8:03:34 AM | | | | |
| Ontiveros, Joe | | Replace water faucet in principles kitchen. | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa MS | | | | | | | | | |
| 132016 | Gym (1997) | Exterior | | | 4/29/2015 | | 19 | | \$0.00 |
| Medium | Work In Progress | OUTSIDE GYM | | | 4/29/2015 8:01:09 AM | | | | |
| Ontiveros, Joe | | NEED AVAILABLE WATER/HOSE BIB OUTSIDE GYM AREA | | | | | | | |
| Laura Parra | | | | | | | | | |
| 130509 | North Building | Athletic Field | | | 3/24/2015 | | 55 | | \$0.00 |
| Medium | Work In Progress | | | | 3/24/2015 11:51:11 AM | | | | |
| Ontiveros, Guadalupe | | I still need 5 metal drums to replace old one and pick up the old trash drums. | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |
| 124639 | South Building | Mechanical | | | 10/27/2014 | | 203 | | \$0.00 |
| Medium | Work In Progress | | | | 10/27/2014 3:30:16 PM | | | | |
| Ambriz, Jose | | 10/27/14. A/C MECANICAL ROOM SOUH BUILDING IS NOT WORKING. | | | | | | | |
| Manuel Prospero | | | | | | | | | |
| 132830 | North Building | Classroom | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 3:07:06 PM | | | | |
| Ambriz, Jose | | 5/13/15. HAVING PROBLEM A/C ROOM 10 AND CAFETERIA. | | | | | | | |
| Manuel Prospero | | | | | | | | | |
| 130993 | | Gym | | | 4/6/2015 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | | 4/6/2015 11:36:53 AM | | | | |
| Estrada, Jesus | | varnish gym floor | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 131179 | South Building | Foyer | | | 4/10/2015 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 4/10/2015 8:50:17 AM | | | | |
| Estrada, Jesus | | Replace with vct in south lobby the tile is in bad shape. | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |
| 130699 | | | | | 3/30/2015 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | | 3/30/2015 7:48:17 AM | | | | |
| Vallejo, Albert | | NEED TO REPAIR GAS METER BLOCK WALL | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 131850 | | Office | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | | | | 4/24/2015 10:44:43 AM | | | | |
| Gonzales, Camilo | | Deliver 1 box. PO# 141507141. Attn: Joe Jacobo. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-------|-----------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa MS | | | | | | | | | |
| 132478 | | Office | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 3:03:43 PM | | | | |
| Gonzales, Camilo | | Pick up obsolete computers and monitors. Deliver to IMWHSE for disposal. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 132161 | | Office | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 3:23:51 PM | | | | |
| Gonzales, Camilo | | Pick up obsolete items and return to IMWHSE for disposal. See dailyjournal log for list of items. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 131904 | | | | | 4/27/2015 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 4/27/2015 10:17:30 AM | | | | |
| Gonzales, Camilo | | Please pickup 6pkgs from Tracey and deliver to STMS to Terry Griego | | | | | | | |
| Tracey Swinford | | | | | | | | | |
| 131294 | North Building | Office | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | Ms Parra/Mr. | | | 4/13/2015 11:56:31 AM | | | | |
| Carrasco, Danny | | FUEL NEEDED FOR ADMINISTRATOR'S GATORS | | | | | | | |
| Laura Parra | | | | | | | | | |
| 132668 | North Building | Office | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | Administration | | | 5/11/2015 11:31:55 AM | | | | |
| Carrasco, Danny | | DELIVER FUEL FOR ADMIN BUGGIES. | | | | | | | |
| Laura Parra | | | | | | | | | |
| 127696 | North Building | Office | | | 1/20/2015 | | 118 | | \$0.00 |
| Medium | Work In Progress | 8- Nurses Office | | | 1/20/2015 10:56:02 AM | | | | |
| Castillo, Carlos | | Install light switch on the back entry door | | | | 4/21/15 Asp Cali request, change to Project | | | |
| Laura Parra | | | | | | | | | |
| 132225 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:44 AM | | | | |
| Orozco, Daniel | | Monthly - Santa Teresa MS Fire Suppression Insp. - Refer to PMSchedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132202 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:30 AM | | | | |
| Orozco, Daniel | | Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PMSchedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|----------------------------------|-----------------------|------------------|-----------|---------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa MS | | | | | | | | | |
| 131360 | | | | | 4/14/2015 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | | 4/14/2015 8:31:06 AM | | | | |
| Ronquillo, Ruben | | Room 504 broken window 36'3/8" x29'3/8" | | | | | | | |
| Jaime Mijarez | | | | | | | | | |
| 132092 | | | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 4/30/2015 12:59:06 PM | | | | |
| Gonzalez, Salvador | | Please weld a spacer onto door mullion to make door latch work properly. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 132097 | North Building | Office | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | SEE MS | | | 4/30/2015 2:26:22 PM | | | | |
| Gonzalez, Salvador | | WELD LIGHT STAND- LIGHTS NEEDED FOR PROMOTION CEREMONY. PLEASE SEE MS PARRA | | | | | | | |
| Laura Parra | | | | | | | | | |
| 132514 | Gym (1997) | Athletic Field | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 8:43:38 AM | | | | |
| Gonzalez, Salvador | | Replace tennis pole see Manny Prospero.. | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |
| 128962 | North Building | Custodial | | | 2/17/2015 | | 90 | | \$0.00 |
| Medium | Work In Progress | | | | 2/17/2015 11:59:58 AM | | | | |
| Gonzalez, Salvador | | Need to weld a stand for lights see Mr.Rodriguez. | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |
| 132160 | Gym (1997) | Exterior | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 3:21:06 PM | | | | |
| Gonzalez, Salvador | | 5/1/15. WE NEED TO REPLACE BASKETBALL NET POST AND NORTH SIDE . | | | | | | | |
| Manuel Prospero | | | | | | | | | |
| Count: 63 Work Orders | | Avg. Age of WO's 62 | | Total for Santa Teresa MS | | 0 | | \$0.00 | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Sunland Park ES

132127 5/1/2015 17 \$0.00

Medium Work In Progress 5/1/2015 8:01:36 AM

Gonzalez, Salvador need to weld bracket and new wheels to front gate

Carlos Hernandez

130235 3/17/2015 62 \$0.00

Medium Work In Progress FOOTBALL 3/17/2015 8:37:45 AM

Gonzalez, Salvador FOOTBALL FIELD- SOCCER GOAL NEEDS TO BE ANCHORED DOWN AND WATER FOUNTAIN NEED TO FIXED AS WELL

Maribel Chavez

129176 2/23/2015 84 \$0.00

Medium Work In Progress 2/23/2015 3:22:09 PM

Gonzalez, Salvador need to weld metal to ramps on portable d

Carlos Hernandez

129355 2/26/2015 81 \$0.00

Medium Work In Progress 2/26/2015 3:00:44 PM

Gonzalez, Salvador need metal steps for portable e

Carlos Hernandez

132203 5/3/2015 5/24/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:31 AM

Orozco, Daniel Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

132351 Main Building Custodial 5/4/2015 14 \$0.00

Medium Work In Progress 5/4/2015 8:26:37 AM

Carrasco, Danny requesting 5 gallon refill of gas and high performance 2 cycle engine oil 2 please

Jesus Lucero

132226 5/3/2015 5/24/2015 15 \$0.00

Medium Work In Progress 5/3/2015 12:32:45 AM

Orozco, Daniel Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

132952 5/15/2015 3 \$0.00

Medium Work In Progress 5/15/2015 7:43:14 AM

Castillo, Carlos Check school during and after power outage.

Carlos Castillo

5/18/2015 9:32:35 AM

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Sunland Park ES | | | | | | | | | |
| 129357 | | | | | 2/26/2015 | | 81 | | \$0.00 |
| Medium | Work In Progress | | | | 2/26/2015 3:10:50 PM | | | | |
| Castillo, Carlos | | need light fixture replace in bathroom to portable a | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 132833 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 3:31:18 PM | | | | |
| Carrasco, Danny | | 4gal D130 Lawnmower 5gal Truck 1gal Weed eater 5gal Ztrac 997 | | | | | | | |
| | | 6gal Diesel for tractor 970 | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 127545 | | | | | 1/14/2015 | | 124 | | \$0.00 |
| Medium | Work In Progress | | | | 1/14/2015 3:16:36 PM | | | | |
| Carrasco, Danny | | need these tools 6 in one screw driver 5/16 bit 8 ft fiberglass ladder channel locks | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 132153 | | Office | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 1:22:18 PM | | | | |
| Vallejo, Albert | | OFFICE - NEED TO HAVE THE MASTER KEY CHANGED WE HAVE SOMEONE GETTING INTO CLASSROOMS AND TAKING STUFF FROM TEACHERS. | | | | | | | |
| Maribel Chavez | | | | | | | | | |
| 132149 | | Office | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 12:25:12 PM | | | | |
| Gonzales, Camilo | | Deliver 30 boxes of SPAN/ENGL Math/Science Foldable Instructional materials. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 132484 | | | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 3:38:03 PM | | | | |
| Hernandez, Carlos | | as per principal need to paint room 18 after moving furniture | | | | | | | |
| Carlos Hernandez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Sunland Park ES | | | | | | | | | |
| 132274 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:13 AM | | | | |
| Hernandez, Carlos | | Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132275 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:14 AM | | | | |
| Hernandez, Carlos | | Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132329 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:45 AM | | | | |
| Hernandez, Carlos | | Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132537 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 2:40:41 PM | | | | |
| Hernandez, Carlos | | need to replace broken floor tile front entrance | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 132538 | | | | | 5/7/2015 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 5/7/2015 2:41:43 PM | | | | |
| Hernandez, Carlos | | need to paint portables from outside | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 132626 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 5/10/2015 12:23:39 AM | | | | |
| Hernandez, Carlos | | Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132364 | | Classroom | | | 5/4/2015 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 5/4/2015 11:21:39 AM | | | | |
| Hernandez, Carlos | | RM#18 - NEED TO MOVE THE STUFF FROM THAT ROOM TO THE PORTABLE. | | | | | | | |
| Maribel Chavez | | | | | | | | | |
| 131534 | | Classroom | | | 4/17/2015 | | 31 | | \$0.00 |
| Medium | Work In Progress | 23 | | | 4/17/2015 9:56:17 AM | | | | |
| Hernandez, Carlos | | RM#23- V.GARCIA-THE VENT IN THE BATHROOM DOES NOT WORK | | | | | | | |
| Maribel Chavez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Sunland Park ES | | | | | | | | | |
| 130238 | | Library | | | 3/17/2015 | | 62 | | \$0.00 |
| Medium | Work In Progress | LIBRARY | | | 3/17/2015 8:44:01 AM | | | | |
| Hernandez, Carlos | | LIBRARY- NEED BANNERS HUNG IN THE MAIN HALLWAY WILL NEED ACCESS TO THE SCISSOR LEFT TO PLACE THESE UP | | | | | | | |
| Maribel Chavez | | | | | | | | | |
| 128591 | | Classroom | | | 2/6/2015 | | 101 | | \$0.00 |
| Medium | Work In Progress | 32 | | | 2/6/2015 11:56:37 AM | | | | |
| Hernandez, Carlos | | RM#32 ARAPI- NEED TO HAVE A HANDICAP BAR INSTALLED IN THERE BATHROOM | | | | | | | |
| Maribel Chavez | | | | | | | | | |
| 131695 | | | | | 4/21/2015 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 4/21/2015 3:30:07 PM | | | | |
| Hernandez, Carlos | | need to screw all windows shut due to break ins | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 130262 | | | | | 3/17/2015 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | | 3/17/2015 2:10:41 PM | | | | |
| Hernandez, Carlos | | need to replace irrigation valve and couplings | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 127809 | | Classroom | | | 1/22/2015 | | 116 | | \$0.00 |
| Medium | Work In Progress | LIBRARY | | | 1/22/2015 1:26:00 PM | | | | |
| Holguin, Alfredo | | LIBRARY- NEED TO HAVE CEMENT COMPLETED ON THE SIDE WALK ON THE NORTH SIDE OF THE BUILDING RIGHT NEXT TO ROAD. (BOOK FAIR WILL ARRIVE FEB. 11,2015) | | | | | | | |
| Maribel Chavez | | | | | | | | | |
| 130324 | | | | | 3/18/2015 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | | 3/18/2015 3:40:50 PM | | | | |
| Estrada, Jesus | | need carpet repaired in portable a | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 131181 | Main Building | Custodial | | | 4/10/2015 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 4/10/2015 10:00:31 AM | | | | |
| Carbajal, Jimmy | | automatic scrubber does not pick up water if you could plz check it out. thanks | | | | | | | |
| Jesus Lucero | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|------------------|------------------|---|--|--|-----------------------|--|-----|--|--------|
| Location: | | Sunland Park ES | | | | | | | |
| 132903 | Main Building | Custodial | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 1:16:35 PM | | | | |
| Carbajal, Jimmy | | requesting an 8ft ladder that wold be use for maintaining building. cleaning wall exc. thanks | | | | | | | |
| Jesus Lucero | | | | | | | | | |
| 127268 | | | | | 1/8/2015 | | 130 | | \$0.00 |
| High | Work In Progress | | | | 1/8/2015 3:52:21 PM | | | | |
| Ambriz, Jose | | need to flush system to all hvac coils, flushing was not included on contract. thank you | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 126029 | | | | | 12/1/2014 | | 168 | | \$0.00 |
| Medium | Work In Progress | | | | 12/1/2014 8:49:10 AM | | | | |
| Ontiveros, Joe | | need new drain kit for sink in nurses office | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 132084 | | Classroom | | | 4/30/2015 | | 18 | | \$0.00 |
| Medium | Work In Progress | 24 | | | 4/30/2015 9:11:28 AM | | | | |
| Ontiveros, Joe | | RM#24 - MARRUFO- CLASSROOM BATHROOM IS NOT FLUSHING SINCE 04/21/15 | | | | | | | |
| Maribel Chavez | | | | | | | | | |
| 131912 | | Office | | | 4/27/2015 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 4/27/2015 1:16:21 PM | | | | |
| Ontiveros, Joe | | OFFICE BATHROOM CLOGGED | | | | | | | |
| Maribel Chavez | | | | | | | | | |
| 127906 | | Restroom (Girls) | | | 1/26/2015 | | 112 | | \$0.00 |
| Medium | Work In Progress | | | | 1/26/2015 9:16:04 AM | | | | |
| Ontiveros, Joe | | GIRL RESTROOM- SINK BROKEN | | | | | | | |
| Maribel Chavez | | | | | | | | | |
| 127845 | | | | | 1/23/2015 | | 115 | | \$0.00 |
| Medium | Work In Progress | Front Main Gate | | | 1/23/2015 11:09:20 AM | | | | |
| Lara, Ralph | | OFFICE - NEEDS A EXTRA KEY FOR THE FRONT MAIN GATE | | | | | | | |
| Maribel Chavez | | | | | | | | | |
| 129353 | | | | | 2/26/2015 | | 81 | | \$0.00 |
| Medium | Work In Progress | | | | 2/26/2015 2:58:02 PM | | | | |
| Lara, Ralph | | need to replace 8 panic bars (out dated no parts) | | | | | | | |
| Carlos Hernandez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs | |
|----------------------------------|------------------|--|-------------|----------------------------------|----------------------|------------------|-----------|---------------|-------------|--|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | | |
| Assigned To | | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | | |
| Location: Sunland Park ES | | | | | | | | | | |
| 129354 | | | | | 2/26/2015 | | 81 | | \$0.00 | |
| Medium | Work In Progress | | | | 2/26/2015 2:59:19 PM | | | | | |
| Lara, Ralph | | need door mullens on west and north doors | | | | | | | | |
| Carlos Hernandez | | | | | | | | | | |
| 132679 | Main Building | Office | | | 5/11/2015 | | 7 | | \$0.00 | |
| Medium | Work In Progress | Nurses Office | | | 5/11/2015 2:43:09 PM | | | | | |
| Lara, Ralph | | 3 drawer file cabinet, one of the drawers is stuck closed and the Nurse can not get to her files! Thank you very much, Colleen | | | | | | | | |
| Colleen Runyan | | | | | | | | | | |
| 130071 | | | | | 3/12/2015 | | 67 | | \$0.00 | |
| Medium | Work In Progress | | | | 3/12/2015 7:44:24 AM | | | | | |
| Flores, Pete | | lawn mower d130 not working properly needs repair | | | | | | | | |
| Carlos Hernandez | | | | | | | | | | |
| Count: 40 Work Orders | | Avg. Age of WO's 48 | | Total for Sunland Park ES | | | 0 | \$0.00 | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|--|-------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Sunrise ES | | | | | | | |
| 130940 | | | | | 4/5/2015 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | 4/5/2015 12:30:34 AM | | | | | |
| Apodaca, Mario | Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132318 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:38 AM | | | | | |
| Apodaca, Mario | Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132636 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 5/10/2015 12:23:45 AM | | | | | |
| Vargas, Juan | Monthly - Sunrise ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132652 | | | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 5/11/2015 8:57:42 AM | | | | | |
| Vargas, Juan | need replace floor tiles in room 107 | | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 132259 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:04 AM | | | | | |
| Vargas, Juan | Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132260 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:05 AM | | | | | |
| Vargas, Juan | Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132261 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:33:06 AM | | | | | |
| Vargas, Juan | Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|-----------------------|----------|-----|--|--------|
| Location: | | Sunrise ES | | | | | | | |
| 132320 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:40 AM | | | | |
| Vargas, Juan | | Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132159 | | | | | 5/1/2015 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 5/1/2015 3:09:14 PM | | | | |
| Vargas, Juan | | need repainting walls 100 200 and 300 wings | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 132465 | | | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 9:46:16 AM | | | | |
| Vargas, Juan | | replace all class rooms ceiling tiles | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 131598 | | | | | 4/20/2015 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | | 4/20/2015 2:02:46 PM | | | | |
| Vargas, Juan | | need tools utilityknife wrenchs manifold gauge set line mens pilers wire striper tubin cuter lazer digital themometer | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 129106 | | | | | 2/20/2015 | | 87 | | \$0.00 |
| Medium | Work In Progress | | | | 2/20/2015 7:55:13 AM | | | | |
| Vargas, Juan | | need repainting parking lines | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 125570 | | | | | 11/14/2014 | | 185 | | \$0.00 |
| Medium | Work In Progress | | | | 11/14/2014 1:15:20 PM | | | | |
| Vargas, Juan | | need replace playground plastic borders north side | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 128557 | | | | | 2/6/2015 | | 101 | | \$0.00 |
| Medium | Work In Progress | | | | 2/6/2015 7:44:57 AM | | | | |
| Vargas, Juan | | need replacing units in kitchen and cafeteria | | | | | | | |
| Juan Vargas | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|---|-------------|-------|----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Sunrise ES | | | | | | | | | |
| 128595 | | | | | 2/6/2015 | | 101 | | \$0.00 |
| Medium | Work In Progress | | | | 2/6/2015 12:05:54 PM | | | | |
| Estrada, Jesus | | portables 6 and 8 need replacing floor tiles | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 120861 | | | | | 8/8/2014 | | 283 | | \$0.00 |
| Medium | Work In Progress | | | | 8/8/2014 3:25:05 PM | | | | |
| Ontiveros, Guadalupe | | need fix or replace release valve in irrigation buster pump | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 132917 | | Office | | | 5/14/2015 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 5/14/2015 2:29:53 PM | | | | |
| Gonzales, Camilo | | Deliver 1 box. PO# 141507195. Thank you. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 132227 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:46 AM | | | | |
| Orozco, Daniel | | Monthly- Sunrise ES Fire Suppression Insp. - Refer to PMs schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132204 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:31 AM | | | | |
| Orozco, Daniel | | Monthly- Sunrise ES Range Hood Cleaning - Refer to PMs schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 130301 | | | | | 3/18/2015 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | | 3/18/2015 8:51:52 AM | | | | |
| Orozco, Daniel | | ICE MACHINE NOT MAKING ICE. SNP MANAGER GLENDA G. 824.3194 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132461 | | | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 7:58:56 AM | | | | |
| Marquez, Gerardo | | portable # 6 need fix core the teacher key stok | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 120182 | | | | | 8/1/2014 | | 290 | | \$0.00 |
| Medium | Work In Progress | | | | 8/1/2014 12:10:52 PM | | | | |
| Appelzoller, Fred | | need replace map sinck and fouset is broke | | | | | | | |
| Juan Vargas | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-------|----------------------|-----------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: | | Sunrise ES | | | | | | | |
| 130216 | | | | | 3/16/2015 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | | 3/16/2015 3:52:07 PM | | | | |
| Appelzoller, Fred | | grls. r,roms next.to cafeteria need replace fouset broken | | | | | | | |
| Juan Vargas | | | | | | | | | |
| Count: 23 Work Orders | | Avg. Age of WO's | 61 | | | Total for Sunrise ES | 0 | | \$0.00 |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Vado ES | | | | | | | | | |
| 131310 | | | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 4/13/2015 3:30:06 PM | | | | |
| Sotelo, Enrique | | need to replace ballast in 100-hallway | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 131311 | | | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 4/13/2015 3:31:37 PM | | | | |
| Sotelo, Enrique | | need to replace ballast in rooo 205 | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 131313 | | | | | 4/13/2015 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 4/13/2015 3:32:44 PM | | | | |
| Sotelo, Enrique | | need to replace ballast in rooms 308 and 310 | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 132420 | | | | | 5/5/2015 | | 13 | | \$0.00 |
| Medium | Work In Progress | | | | 5/5/2015 10:15:28 AM | | | | |
| Sotelo, Enrique | | need to replace ballast in rooms 301 and 306 | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 132795 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 7:48:20 AM | | | | |
| Sotelo, Enrique | | need to replace emerg. lights in gym | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 132796 | | | | | 5/13/2015 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | | 5/13/2015 7:50:01 AM | | | | |
| Sotelo, Enrique | | need to replace emer. lights in boys and girls r.r. bybus exit | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 132205 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:32:32 AM | | | | |
| Orozco, Daniel | | Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 128036 | | | | | 1/28/2015 | | 110 | | \$0.00 |
| Medium | Work In Progress | | | | 1/28/2015 12:37:24 PM | | | | |
| Orozco, Daniel | | REACH IN IS NOT COOLING. SNP MANAGER ELIZABETH M. 233.2945 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------|------------------|---|-------------|-----------------------|------------------|--|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Vado ES | | | | | | | | | |
| 128037 | | | | | 1/28/2015 | | 110 | | \$0.00 |
| Medium | Work In Progress | | | 1/28/2015 12:38:28 PM | | | | | |
| Orozco, Daniel | | ICE MAKER NOT MAKING ICE. SNP MANAGER ELIZABETH M. 233.2945 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 126444 | | | | | 12/10/2014 | | 159 | | \$0.00 |
| Medium | Work In Progress | | | 12/10/2014 9:11:12 AM | | | | | |
| Orozco, Daniel | | SINK - WHEN SHUT OFF WATER LEAKS.SNP MANAGER ELIZABETH M. 233.2945 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132228 | | | | | 5/3/2015 | 5/24/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | 5/3/2015 12:32:46 AM | | | | | |
| Orozco, Daniel | | Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 131785 | | | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | 4/23/2015 11:16:04 AM | | | | | |
| Orozco, Daniel | | NEED TO REPLACE HOSE BIBBS IN KITCHEN SERVING TRAYS | | | | 5/15/15 - Asp D. Miranda, route to D. Orozco | | | |
| Danny Miranda | | | | | | | | | |
| 131851 | | | | | 4/24/2015 | | 24 | | \$0.00 |
| Medium | Work In Progress | | | 4/24/2015 10:49:13 AM | | | | | |
| Orozco, Daniel | | STAND IS NOT HOLDING WATER. SNP MANAGER ELIZABETH M. 233.2945 | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 132669 | | Office | | | 5/11/2015 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 5/11/2015 11:44:51 AM | | | | | |
| Gonzales, Camilo | | Pick up obsolete items and return to the IMWHSE for disposal. You will find the items at the stage in the cafeteria room. See Daily delivery log for list of items. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 131230 | | | | | 4/12/2015 | 4/28/2015 | 36 | | \$0.00 |
| Medium | Work In Progress | | | 4/12/2015 12:23:34 AM | | | | | |
| Diaz, Armando | | Monthly - QRTLY BLDG INSP REPORT (VE) - Refer to PMs schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Vado ES

| | | | | | | | | | |
|--------|---------------|--|--|--|-----------|--|---|--|--------|
| 132778 | Main Building | | | | 5/12/2015 | | 6 | | \$0.00 |
|--------|---------------|--|--|--|-----------|--|---|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|
| High | Work In Progress | | | | 5/12/2015 4:05:53 PM | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|

Diaz, Armando 100 wing bathroom we need a napkin receptacle installed this has to be done immediately.

Jesus Estrada

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|----|--|--------|
| 130040 | | | | | 3/11/2015 | | 68 | | \$0.00 |
|--------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 3/11/2015 2:56:03 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, David need to run snake at 3 1/2 cleanout that runs under track

Danny Miranda

| | | | | | | | | | |
|--------|---------------|------------------|--|--|-----------|--|----|--|--------|
| 132004 | Main Building | Restroom (Girls) | | | 4/28/2015 | | 20 | | \$0.00 |
|--------|---------------|------------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/28/2015 3:51:04 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, David need Roto-Rooter for contract services to inspect and clean out any problems

David Villalobos

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|----|--|--------|
| 129280 | | | | | 2/25/2015 | | 82 | | \$0.00 |
|--------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 2/25/2015 10:02:24 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Miranda, Danny need weed and feed for grounds

Danny Miranda

| | | | | | | | | | |
|--------|--|-----------|--|--|-----------|--|----|--|--------|
| 131278 | | Classroom | | | 4/13/2015 | | 35 | | \$0.00 |
|--------|--|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Room 201 Mrs. | | | 4/13/2015 8:54:22 AM | | | | |
|--------|------------------|---------------|--|--|----------------------|--|--|--|--|

Miranda, Danny Mrs. Facio need the blue light (blue screen) in her classroom

Sylvia Cary

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|---|--|--------|
| 132963 | | | | | 5/15/2015 | | 3 | | \$0.00 |
|--------|--|--|--|--|-----------|--|---|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 5/15/2015 11:40:10 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Miranda, Danny need to replace air filters

Danny Miranda

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|----|--|--------|
| 131474 | | | | | 4/16/2015 | | 32 | | \$0.00 |
|--------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/16/2015 9:39:38 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Miranda, Danny need to replace exhaust fan motors

Danny Miranda

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|----|--|--------|
| 131599 | | | | | 4/20/2015 | | 28 | | \$0.00 |
|--------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 4/20/2015 2:19:19 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Miranda, Danny NEED TO CK HEAT PUMP IN RM. 205 ON AND OFF HIGH AND LOW PREASURE CUT OUT

Danny Miranda

5/18/2015 9:32:36 AM

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: | | Vado ES | | | | | | | |
| 131794 | | Computer Lab | | | 4/23/2015 | | 25 | | \$0.00 |
| Medium | Work In Progress | Computer Lab | | | 4/23/2015 2:05:48 PM | | | | |
| Miranda, Danny | | Light bulbs have burnt out and need to be replaced. | | | | | | | |
| Sylvia Cary | | | | | | | | | |
| 132714 | | | | | 5/12/2015 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 5/12/2015 9:16:18 AM | | | | |
| Miranda, Danny | | need to repair pvc water lines in kitchen | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 132628 | | | | | 5/10/2015 | 5/26/2015 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 5/10/2015 12:23:41 AM | | | | |
| Miranda, Danny | | Monthly - Vado ES Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132322 | | | | | 5/3/2015 | 5/9/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:41 AM | | | | |
| Miranda, Danny | | Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132280 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:16 AM | | | | |
| Miranda, Danny | | Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132281 | | | | | 5/3/2015 | 5/11/2015 | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:17 AM | | | | |
| Miranda, Danny | | Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132282 | | | | | 5/3/2015 | | 15 | | \$0.00 |
| Medium | Work In Progress | | | | 5/3/2015 12:33:18 AM | | | | |
| Miranda, Danny | | Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 132471 | | | | | 5/6/2015 | | 12 | | \$0.00 |
| Medium | Work In Progress | | | | 5/6/2015 11:43:41 AM | | | | |
| Miranda, Danny | | NEED TO UNCLOG STAFF, AND GIRLS RESTROOM IN 100-WING | | | | | | | |
| Danny Miranda | | | | | | | | | |

5/18/2015 9:32:36 AM

1368 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------------|------------------|---|-------------------------|-----------|----------------------|------------------|--------------------------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Vado ES | | | | | | | | | |
| 131139 | | | | | 4/9/2015 | | 39 | | \$0.00 |
| Medium | Work In Progress | | | | 4/9/2015 9:56:28 AM | | | | |
| Marquez, Gerardo | | staff restroom by teachers lounge needs to be able to be locked | | | | | | | |
| Armando Diaz | | | | | | | | | |
| 119473 | Main Building | Office | | | 7/16/2014 | | 306 | | \$0.00 |
| Medium | Work In Progress | | | | 7/16/2014 8:36:17 AM | | | | |
| Munoz, Michael | | NEED TO REPLACE COUNTER TOP IN TEACHERS LOUNGE AND FRONT OFFICE. ASAP | | | | | | | |
| Debra Facio | | | | | | | | | |
| Count: 33 Work Orders | | | Avg. Age of WO's | 41 | | | Total for Vado ES | 0 | \$0.00 |
| Count: 1368 Work Orders | | | Avg. Age of WO's | 58 | | | Grand Total | 0 | \$0.00 |