Vandalism Report

Last Month (04/01/2018 - 04/30/2018)

Vandalism

Chaparral HS

		Trns Type Request	Description Su	pplierName	Invoice/Reference Requester	Quantity	Unit Cost	Sales Tax	Total Cost
Trns Dte	WOID	Request Date	e Requested Completion Date	Target Completion Date	Completion Date				
5/2/2018 1	193859	Contract	24x34 double safety			1.00	\$370.00	\$0.00	\$370.00
		Please replac 4/27/2018	ce broken Glass on main door to the	end of G-wing. Double pane	Johnny Acuna 5/2/2018				
5/2/2018	193859	Labor	Danny Carrasco			.15	\$25.00	\$0.00	\$3.75
		Please replac 4/27/2018	ce broken Glass on main door to the	end of G-wing. Double pane	Johnny Acuna 5/2/2018				
5/2/2018	193859	Labor	Ruben Ronquillo			.15	\$25.00	\$0.00	\$3.75
		Please replac 4/27/2018	ce broken Glass on main door to the	end of G-wing. Double pane	Johnny Acuna 5/2/2018				
Gadsden	HS								
		Trns Type	Description Su	pplierName	Invoice/Reference	Quantity	Unit Cost	Sales Tax	Total Cost
		Request			Requester				
Trns Dte	WOID	Request Date	e Requested Completion Date	Target Completion Date	Completion Date				
4/26/2018				raiget eempletien bate	Completion Date				
4/26/2018	193786	Labor	David Escobar			2.00	\$25.00	\$0.00	\$50.00
4/26/2018	193786	Labor unclog comm	•		David Escobar	2.00	\$25.00	\$0.00	\$50.00
4/26/2018	193786	Labor	David Escobar		-	2.00	\$25.00	\$0.00	\$50.00
		Labor unclog comm	David Escobar		David Escobar	2.00	\$25.00	\$0.00	\$50.00 \$50.00
		Labor unclog comn 4/26/2018 Labor	David Escobar node atold main bldg.		David Escobar		·	·	·
		Labor unclog comn 4/26/2018 Labor	David Escobar node atold main bldg. Manuel Prospero		David Escobar 5/4/2018		·	·	·
4/26/2018		Labor unclog comn 4/26/2018 Labor unclog comn	David Escobar node atold main bldg. Manuel Prospero		David Escobar 5/4/2018 David Escobar		·	·	·
4/26/2018 4/26/2018 5/4/2018	193786	Labor unclog comn 4/26/2018 Labor unclog comn 4/26/2018 Labor	David Escobar node atold main bldg. Manuel Prospero node atold main bldg.		David Escobar 5/4/2018 David Escobar	2.00	\$25.00	\$0.00	\$50.00

Vandal 5/4/2018	193786	Materials	wax ring				1.00	\$1.30	\$0.00	\$1.30
		unclog comr	modeatold main bld	g.		David Escobar				
		4/26/2018				5/4/2018				
Gadsden	MS									
		Trns Type	Description	Sup	plierName	Invoice/Reference	Quantity	Unit Cost	Sales Tax	Total Cost
		Request				Requester				
Trns Dte	WOID	Request Dat	e Requested	Completion Date	Target Completion Date	Completion Date				
4/25/2018	193616	Labor	Jesus Avila				2.00	\$25.00	\$0.00	\$50.00
		Broken wall i	in boys restroom (B	ig Hole in wall (18"	X 18")	Hilda Adler				
		4/24/2018	4/24/2018			4/25/2018				
4/25/2018	193616	Materials	grout				1.00	\$11.99	\$0.00	\$11.99
		Broken wall i	in boys restroom (B	ig Hole in wall (18"	X 18")	Hilda Adler				
		4/24/2018	4/24/2018			4/25/2018				
4/25/2018 1	193616	Materials	4x4 Tiles				6.00	\$1.50	\$0.00	\$9.00
		Broken wall i	in boys restroom (B	ig Hole in wall (18"	X 18")	Hilda Adler				
		4/24/2018	4/24/2018			4/25/2018				
4/25/2018	193616	Materials	1x4 Board				1.00	\$2.99	\$0.00	\$2.99
		Broken wall i	in boys restroom (B	ig Hole in wall (18"	X 18")	Hilda Adler				
		4/24/2018	4/24/2018			4/25/2018				
4/25/2018	193616	Materials	4x8 Sheetrock				1.00	\$10.99	\$0.00	\$10.99
		Broken wall i	in boys restroom (B	ig Hole in wall (18"	X 18")	Hilda Adler				
		4/24/2018	4/24/2018			4/25/2018				
4/25/2018	193616	Materials	liquid nails				1.00	\$3.19	\$0.00	\$3.19
		Broken wall i	in boys restroom (B	ig Hole in wall (18"	X 18")	Hilda Adler				
		4/24/2018	4/24/2018			4/25/2018				
Mesquite	ES									
		Trns Type	Description	Sup	plierName	Invoice/Reference	Quantity	Unit Cost	Sales Tax	Total Cost
		Request				Requester				
Trns Dte	WOID	Request Dat	e Requested	Completion Date	Target Completion Date	Completion Date				

Vandalism						
4/13/2018 192895	Contract 23 14 x 35 14 bronze unit ALL AMERICAN GLASS		1.00	\$420.00	\$0.00	\$420.00
	need to replace broken window bus turn around area $23 1/2 x 35 1/2$ safety glass	Joe Ramirez				
	4/11/2018	4/13/2018				
4/13/2018 192895	Labor Ruben Ronquillo		.15	\$25.00	\$0.00	\$3.75
	need to replace broken window bus turn around area 23 1/2 x 35 1/2 safety glass	Joe Ramirez				
	4/11/2018	4/13/2018				
Santa Teresa MS						
	Trns Type Description SupplierName	Invoice/Reference	Quantity	Unit Cost	Sales Tax	Total Cost
	Request	Requester				
Trns Dte WOID	Request Date Requested Completion Date Target Completion Date	Completion Date				
4/16/2018 193094	Contract 37x36 double SUNCITY GLASS		1.00	\$355.00	\$0.00	\$355.00
	S.bldg North facing exterior lobby window by library entrance. student threw a rock	Jaime Mijarez				
	4/13/2018	4/16/2018				
4/16/2018 193094	Labor Ruben Ronquillo		.15	\$25.00	\$0.00	\$3.75
	S.bldg North facing exterior lobby window by library entrance. student threw a rock	Jaime Mijarez				
	4/13/2018	4/16/2018				
	Total Labor Costs \$177.50 Total Hours 7.10					
	Total Material Costs \$1,184.46					
	Total Costs for Vandalism					\$1,361.96
			R	eport Grand	Total	\$1,361.96