

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Alta Vista ECHS | | | | | | | | | |
| 207480 | | | | | 12/13/2018 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | 12/13/2018 9:32:37 AM | | | | | |
| Chavez, Santos | | Please replace (4) portables exterior lights with LEDs fixtures. | | | | | | | |
| | | Portables#s 5,6,8,and 18. | | | | | | | |
| | | Thank you | | | | | | | |
| Marin Herrera | | | | | | | | | |
| 205840 | | | | | 11/8/2018 | | 70 | | \$143.56 |
| Medium | Work In Progress | | | 11/8/2018 3:04:40 PM | | | | | |
| Herrera, Marin | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 206823 | | | | | 12/3/2018 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | 12/3/2018 9:39:44 AM | | | | | |
| Herrera, Marin | | Replace the water filter in the water fountain. | | | | | | | |
| Melanie Beegle | | | | | | | | | |
| 206666 | | | | | 11/29/2018 | | 49 | | \$0.00 |
| Medium | Work In Progress | 12 | | 11/29/2018 12:53:23 | | | | | |
| Briones, Enrique | | GMS donated drum equipment to AVECHS. AVECHS teacher reports having extra drum pieces - cannot make a complete drum. In speaking with Mr. Sanchez at GMS he requests that the warehouse pick up the extra drum pieces and store them at the Warehouse. | | | | | | | |
| Melanie Beegle | | | | | | | | | |
| 207055 | | Office | | | 12/6/2018 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2018 8:10:48 AM | | | | | |
| Briones, Enrique | | Pick up obsolete equipment and deliver to the Instructional Materials Warehouse. | | | | | | | |
| Theresa Ramirez | | | | | | | | | |
| 207475 | | Classroom | | | 12/13/2018 | | 35 | | \$0.00 |
| Medium | Work In Progress | DPA | | 12/13/2018 8:17:07 AM | | | | | |
| Carrasco, Danny | | Student threw his shoe up into the ceiling rafters at the DPA multipurpose room. If we could please have maintenance use the scissor lift to retrieve the students shoe. | | | | | | | |
| Melanie Beegle | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| Selected Date Range for Request Dates:7/1/2018 - 12/31/2018 Order By Location, Status | | | | | | | | | Total Costs |
|---|------------------|--|-------------|----------------------|---------------------------|--|-----------|-------------|-------------|
| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | |
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Location: | | Alta Vista ECHS | | | | | | | |
| <hr/> | | | | | | | | | |
| 199761 | | | | | 8/8/2018 | | 162 | | \$0.00 |
| Medium | Work In Progress | | | 8/8/2018 1:28:32 PM | | | | | |
| Marquez, Gerardo | | Portable 17 student restroom , please have them to close by them self. when a student or staff member leaves the restroom the door stays open | | | | Contracted Service asp report 10/30/18 | | | |
| Laura Vazquez | | | | | | | | | |
| 200331 | | | | | 8/15/2018 | | 155 | | \$0.00 |
| Medium | Work In Progress | | | 8/15/2018 1:10:15 PM | | | | | |
| Marquez, Gerardo | | requesting 3 little windows in door entrance from portable 1, 2, and 17 please follow up with Mr. Jerry Marquez for any question please ask Ms. De La Garza. thank you, LV | | | | Contracted Service asp report 10/30/18 | | | |
| Laura Vazquez | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Count: 8 Work Orders | | Avg. Age of WO's 74 | | | Total for Alta Vista ECHS | | | 0 | \$143.56 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony - On Track Pre-K (Village) | | | | | | | | | |
| 206753 | | Portables | | | 11/30/2018 | | 48 | | \$74.97 |
| Medium | Work In Progress | | | | 11/30/2018 1:38:34 PM | | | | |
| Rincon, Jesus | | 11/30/2018. In Needed Of 3 Emergency Bug Light | | | | | | | |
| Jesus Rincon | | | | | | | | | |
| 206650 | | Exterior | | | 11/29/2018 | | 49 | | \$17.50 |
| Medium | Work In Progress | gates at the turn | | | 11/29/2018 11:39:40 | | | | |
| Carrasco, Danny | | Please create signs indicating entrance to pre-k turn around. | | | | | | | |
| Michelle Soto | | | | | | | | | |
| 207548 | | Exterior | | | 12/14/2018 | | 34 | | \$0.00 |
| Medium | Work In Progress | playground | | | 12/14/2018 10:32:43 | | | | |
| Rincon, Jesus | | Please fix red swing under the canopy. | | | | | | | |
| Michelle Soto | | | | | | | | | |
| 207489 | | Classroom | | | 12/13/2018 | | 35 | | \$0.00 |
| Medium | Work In Progress | 110 | | | 12/13/2018 12:33:09 | | | | |
| Marquez, Gerardo | | Room 110 needs chain locks on both doors. ASAP | | | | | | | |
| Michelle Soto | | | | | | | | | |
| 198199 | | | | | 7/17/2018 | | 184 | | \$0.00 |
| Medium | Work In Progress | | | | 7/17/2018 10:35:18 AM | | | | |
| Ontiveros, Guadalupe | | Relocate Morgan shed closer to the pre-k classrooms. | | | | | | | |
| Michelle Soto | | | | | | | | | |
| 206646 | | Storage | | | 11/29/2018 | | 49 | | \$0.00 |
| Medium | Work In Progress | outside area | | | 11/29/2018 11:30:13 | | | | |
| Ontiveros, Guadalupe | | Please move Morgan shed closer to the pre-k classrooms. Resubmitting request that was done on 7/17/18. | | | | | | | |
| Michelle Soto | | | | | | | | | |
| 207547 | | Exterior | | | 12/14/2018 | | 34 | | \$0.00 |
| Medium | Work In Progress | outside area | | | 12/14/2018 10:29:03 | | | | |
| Ontiveros, Guadalupe | | Resubmitting request from 7/17/18 & 11/29/18. Please remove Morgan shed closer to the pre-k classrooms. Staff would like access to shed by January 7, 2019. | | | | | | | |
| Michelle Soto | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------|------------------------------------|--|------------------|-----------------------|--|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Location: | Anthony - On Track Pre-K (Village) | | | | | | | | |
| 205898 | | | | | 11/9/2018 | | 69 | | \$534.60 |
| Medium | Work In Progress | | | 11/9/2018 10:39:59 AM | | | | | |
| Rincon, Jesus | | 11/9/2018. | | | | | | | |
| | | Requesting 22 Battery For Pre-K Exit Sings | | | | | | | |
| Jesus Rincon | | | | | | | | | |
| 205844 | | | | | 11/8/2018 | | 7 | 1 | \$60.89 |
| Medium | Work In Progress | | | 11/8/2018 3:11:34 PM | 11/15/2018 | | | | |
| Rincon, Jesus | | ADACConcerns - Install interior pull on all ADA Stalls and | | | | done | | | |
| | | install knee guard covers on exposed pipes underneath | | | | | | | |
| | | sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Count: 9 Work Orders | | | Avg. Age of WO's | 57 | Total for Anthony - On Track Pre-K (Village) | | | 1 | \$687.96 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony ES | | | | | | | | | |
| 205843 | | | | | 11/8/2018 | | 70 | | \$35.89 |
| Medium | Work In Progress | | | 11/8/2018 3:10:34 PM | | | | | |
| Rincon, Jesus | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 206161 | | | | | 11/15/2018 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | 11/15/2018 12:42:28 | | | | | |
| Flores, Pete | | Yearly - Anthony ES M-0405 (Z-Track) Grounds - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 206468 | Pump House | | | | 11/27/2018 | | 51 | | \$0.00 |
| Medium | Work In Progress | | | 11/27/2018 2:57:43 PM | | | | | |
| Ontiveros, Guadalupe | | Today, I turned on The Motor In The Pump House To Check The System, And I Saw It Has A Water Leak By A Valve, It Already Have Rust Around The Pipe. | | | | | | | |
| Jesus Rincon | | | | | | | | | |
| 207056 | | | | | 12/6/2018 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2018 8:13:04 AM | | | | | |
| Flores, Pete | | 12/6/2018. Work Truck #191 Is In Need Of Power Steering Fluid. | | | | | | | |
| Jesus Rincon | | | | | | | | | |
| 204294 | | | | | 10/18/2018 | | 91 | | \$0.00 |
| Medium | Work In Progress | | | 10/18/2018 7:41:05 AM | | | | | |
| Flores, Pete | | 10/18/2018. Right Wheel Was Damaged On Gator, That Day With The Accident Of The Vandalism. | | | | | | | |
| Jesus Rincon | | | | | | | | | |
| 203172 | | | | | 9/30/2018 | 10/31/2018 | 18 | 4 | \$364.78 |
| Medium | Work In Progress | | | 9/30/2018 2:09:33 AM | 10/18/2018 | | | | |
| Rincon, Jesus | | Yearly - Anthony ES I4 (Fan Coil)(Yearly) - Refer to PM schedule details. | | | | done | | | |
| Margret Villalobos | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony ES | | | | | | | | | |
| 205197 | | Storage | | | 11/1/2018 | | 77 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2018 10:27:13 AM | | | | | |
| Chavez, Santos | | 11/1/2018. In Need To Replace A Exit Combo Light With Bug Light In A Storage. | | | | | | | |
| Jesus Rincon | | | | | | | | | |
| 205575 | | Kitchen | | | 11/5/2018 | | 73 | | \$0.00 |
| High | Work In Progress | | | 11/5/2018 1:11:05 PM | | | | | |
| Medina, Eric | | Check serving line lights don't work | | | | | | | |
| Dino Facio | | | | | | | | | |
| 207122 | | | | | 12/6/2018 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2018 3:47:10 PM | | | | | |
| Carrasco, Danny | | 12/6/2018. In Need Of A Bulb For A projector. | | | | | | | |
| Jesus Rincon | | | | | | | | | |
| 205359 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:30 AM | | | | | |
| Facio, Dino | | Yearly - Anthony ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205382 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:47 AM | | | | | |
| Facio, Dino | | Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207770 | | | | | 12/20/2018 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | 12/20/2018 8:50:06 AM | | | | | |
| Medina, Eric | | SLICER TABLE NEEDS TO BE LOWERED. THANK YOU. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 207612 | | | | | 12/17/2018 | | 31 | | \$0.00 |
| Medium | Work In Progress | | | 12/17/2018 2:01:15 PM | | | | | |
| Marquez, Gerardo | | As per Mr. Carmona two restroom stalls are missing a latch please replace as soon as possible 1. boys restroom next to room # 401 (missing latch) 2. girls restroom next to cafeteria (latch installed incorrectly please replace) | | | | | | | |
| Jessica Lopez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| Selected Date Range for Request Dates:7/1/2018 - 12/31/2018 Order By Location, Status | | | | | | | | | Total Costs |
|---|------------------|---|---------------------|-----------------------|-------------------|----------------------|-----------|-------------|-------------|
| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | |
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| | | | | | | | | | |
| Location: | | Anthony ES | | | | | | | |
| | | | | | | | | | |
| 207769 | | | | | 12/20/2018 | | 28 | | \$79.50 |
| Medium | Work In Progress | | | 12/20/2018 8:49:15 AM | | | | | |
| Rincon, Jesus | | FIRE EXTINGUISHER NEEDED IN KITCHEN THANK YOU. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 207309 | | | | | 12/11/2018 | | 37 | | \$0.00 |
| Medium | Work In Progress | | | 12/11/2018 12:48:40 | | | | | |
| Rincon, Jesus | | Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 15 Work Orders | | | Avg. Age of WO's 53 | | | Total for Anthony ES | | 4 | \$480.17 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Berino ES | | | | | | | | | |
| 205383 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:48 AM | | | | | |
| Facio, Dino | | Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205353 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:24 AM | | | | | |
| Facio, Dino | | Yearly - Berino ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 206345 | Main Building | Pump House | | | 11/26/2018 | | 52 | | \$0.00 |
| Medium | Work In Progress | outside building | | 11/26/2018 11:32:32 | | | | | |
| Apodaca, Mario | | On pump house icon in the front of the school states low battery again | | | | | | | |
| Michelle Guerra | | | | | | | | | |
| 205841 | | | | | 11/8/2018 | | 70 | | \$287.12 |
| Medium | Work In Progress | | | 11/8/2018 3:06:16 PM | | | | | |
| Herrera, Marin | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 207163 | | | | | 12/7/2018 | | 41 | | \$0.00 |
| Medium | Work In Progress | | | 12/7/2018 1:31:25 PM | | | | | |
| Herrera, Marin | | Need (1) Hole saw kit item#301536 and (1) utility knife item#364867 both from Lowes hardware | | | | | | | |
| Marin Herrera | | | | | | | | | |
| 205609 | | Office | | | 11/5/2018 | | 73 | | \$13.20 |
| Medium | Work In Progress | | | 11/5/2018 3:41:50 PM | | | | | |
| Chavez, Santos | | need electrical for ice maker in the teacher lounge | | | | | | | |
| Fred Appelzoller | | | | | | | | | |
| 205073 | | | | | 10/30/2018 | | 79 | | \$0.00 |
| Medium | Work In Progress | | | 10/30/2018 3:57:44 PM | | | | | |
| Ambriz, Jose | | Can you please have HVAC look into room 140 at BE. | | | | | | | |
| Dominique Esparza | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| Selected Date Range for Request Dates:7/1/2018 - 12/31/2018 Order By Location, Status | | | | | | | | | | Total Costs |
|---|------------------|--|--------------|-------|-----------------------|------------------|-----------|-------------|----------|-------------|
| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | | |
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | | |
| Assigned To | Description | | Action Taken | | | | | | | |
| Requester Name | | | | | | | | | | |
| Location: | | Berino ES | | | | | | | | |
| 206197 | | | | | 11/15/2018 | | 63 | | \$0.00 | |
| Medium | Work In Progress | | | | 11/15/2018 1:55:00 PM | | | | | |
| Ontiveros, Guadalupe | | Please scrape inside bus turn around with tractor I did most of it with my Kubota but can not get into some spots. Thank you | | | | | | | | |
| Marin Herrera | | | | | | | | | | |
| Count: 8 Work Orders | | Avg. Age of WO's | | 66 | Total for Berino ES | | | 0 | \$300.32 | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral ES | | | | | | | | | |
| 202495 | Main Building | Parking Lot | | | 9/18/2018 | | 121 | | \$112.71 |
| Medium | Work In Progress | | | 9/18/2018 9:02:01 AM | | | | | |
| Saucedo, Luis | | handicap sidewalk need to repaint blue | | | | | | | |
| Adrian Flores | | | | | | | | | |
| 205845 | | | | | 11/8/2018 | | 70 | | \$380.56 |
| Medium | Work In Progress | | | 11/8/2018 3:12:39 PM | | | | | |
| Juzdowski, Jimmie | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 201574 | Main Building | Office | | | 9/4/2018 | | 135 | | \$704.53 |
| Medium | Work In Progress | | | 9/4/2018 9:30:05 AM | | | | | |
| Ambriz, Jose | | Custodian and maintenance office room 401 need a heater for upcoming winter | | | | | | | |
| Adrian Flores | | | | | | | | | |
| 206347 | | Kitchen | | | 11/26/2018 | | 52 | | \$0.00 |
| High | Work In Progress | | | 11/26/2018 12:45:28 | | | | | |
| Tellez, Hector | | Need door bell installed in back door to new cafeteria | | | | | | | |
| Dino Facio | | | | | | | | | |
| 203653 | Main Building | Classroom | | | 10/8/2018 | | 101 | | \$0.00 |
| Medium | Work In Progress | 123 | | 10/8/2018 9:12:34 AM | | | | | |
| Tellez, Hector | | lights on one section of the library do not work. See Library | | | | | | | |
| Jennifer Corral | | | | | | | | | |
| 205741 | | | | | 11/7/2018 | | 0 | 14 | \$969.18 |
| Medium | Work In Progress | | | 11/7/2018 2:22:08 PM | 11/7/2018 | | | | |
| Vargas, Juan | | need replace a/c filters in chaparral el. | | | | replaced filters | | | |
| Juan Vargas | | | | | | | | | |
| 205355 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:26 AM | | | | | |
| Facio, Dino | | Yearly - Chaparral ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|---------------------|--|-------------|-----------------------|-------------------------------|------------------|-----------|-------------|-------------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Location: | Chaparral ES | | | | | | | | |
| 205384 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:49 AM | | | | | |
| Facio, Dino | | Monthly - Chaparral ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 206904 | P.E. Building | Office | | | 12/4/2018 | | 44 | | \$0.00 |
| Medium | Work In Progress | | | 12/4/2018 11:04:27 AM | | | | | |
| Ambriz, Jose | | need portable heater in custodial office please Thank You | | | | | | | |
| Adrian Flores | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Count: 9 Work Orders | | Avg. Age of WO's 75 | | | Total for Chaparral ES | | | 14 | \$2,166.98 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| Selected Date Range for Request Dates:7/1/2018 - 12/31/2018 Order By Location, Status | | | | | | | | | | Total Costs |
|---|------------------|--|------------------|-----------------------|-------------------|------------------|----------------------------------|-------------|--------|-------------|
| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | | |
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | | |
| Assigned To | | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | | |
| <hr/> | | | | | | | | | | |
| Location: | | Chaparral High - Pre-K | | | | | | | | |
| <hr/> | | | | | | | | | | |
| 206229 | | | | | 11/15/2018 | | 63 | | \$0.00 | |
| Medium | Work In Progress | | | 11/15/2018 3:46:53 PM | | | | | | |
| Acuna, Johnny | | please cover hole and cracks that are in the wall where the multipurpose room is. any questions please ask Laura or Angelic. thank you, LV | | | | | | | | |
| Laura Vazquez | | | | | | | | | | |
| <hr/> | | | | | | | | | | |
| Count: 1 Work Orders | | | Avg. Age of WO's | | 63 | | Total for Chaparral High - Pre-K | | | 0 \$0.00 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-----------------------|------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 200885 | H-Wing | Auditorium | | | 8/23/2018 | | 147 | | \$0.00 |
| Medium | Work In Progress | main gym girls | | 8/23/2018 2:26:21 PM | | | | | |
| Acuna, Johnny | | Please remove the middle section lockers in the girls basketball dressing room in the main gym. (Ms. Lopez, principal) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 203764 | | | | | 10/9/2018 | | 100 | | \$0.00 |
| High | Work In Progress | | | 10/9/2018 3:19:19 PM | | | | | |
| Acuna, Johnny | | Install door sweeps as needed on all exterior doors. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 203016 | R-Wing | Classroom | | | 9/26/2018 | | 113 | | \$21.60 |
| Medium | Work In Progress | R5 | | 9/26/2018 4:42:23 PM | | | | | |
| Acuna, Johnny | | 1st cooler is leaking water from inside: top condensation hose is cracked / broken. (Mrs. Garcia, R5) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 205644 | Field House | Classroom | | | 11/6/2018 | | 72 | | \$0.00 |
| Medium | Work In Progress | weight room | | 11/6/2018 8:58:31 AM | | | | | |
| Acuna, Johnny | | Due to fire code restrictions, the panels around the perimeter of the weight room must be in place. However, when athletes are working out and performing pull-ups these panels must be removed in order for them not to hit their heads. the ceiling is too low to accommodate our pull-up exercise equipment therefore needing the ceiling to be raised in order to meet compliance. Please see coach Yturralde or Mr. Gregg Martinez if you have any questions in reference to this work order. (Mr. Martinez, AP) | | | | Route to Johnny, have discussed - A. Vallejo 11/14/18 | | | |
| Mireya Meza | | | | | | | | | |
| 205824 | R-Wing | Classroom | | | 11/8/2018 | | 70 | | \$0.00 |
| Medium | Work In Progress | R5 | | 11/8/2018 12:31:57 PM | | | | | |
| Acuna, Johnny | | Dish machine is not working; motor is grinding. (Mrs. Garcia, R5) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 205748 | A-Wing | Gym | | | 11/7/2018 | | 71 | | \$0.00 |
| Medium | Work In Progress | New gym | | 11/7/2018 3:15:13 PM | | | | | |
| Acuna, Johnny | | Please mount display board on new auxiliary gym wall top floor. West wall next to the bars and at that level. If you have questions ask Mireya or coach Guillermo. | | | | | | | |
| Mireya Meza | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 205196 | A-Wing | Office | | | 11/1/2018 | | 77 | | \$0.00 |
| Medium | Work In Progress | counselor | | | 11/1/2018 10:20:47 AM | | | | |
| Acuna, Johnny | | Please put together a new office chair for Mrs. Monzon. (Mireya Meza) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 204944 | A-Wing | Office | | | 10/29/2018 | | 80 | | \$0.00 |
| Medium | Work In Progress | front office | | | 10/29/2018 1:37:18 PM | | | | |
| Acuna, Johnny | | The frig in the front office is not making ice. Johnny will you please check for problem. (Mireya Meza) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 204246 | A-Wing | Library | | | 10/17/2018 | | 92 | | \$0.00 |
| Medium | Work In Progress | Library | | | 10/17/2018 12:15:05 | | | | |
| Acuna, Johnny | | Multiple lights need bulbs replaced in the library. (Ms. DeVine, librarian) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 204147 | Q-Wing | Classroom | | | 10/16/2018 | | 93 | | \$0.00 |
| Medium | Work In Progress | Q3 | | | 10/16/2018 10:12:40 | | | | |
| Acuna, Johnny | | Must make hole in wall for exhaust fan for Epilog Laser in Q1. Used for computer graphics curriculum to train students. (Mrs. Campbell, Q3) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 207493 | G-Wing | Classroom | | | 12/13/2018 | | 35 | | \$0.00 |
| Medium | Work In Progress | G7 | | | 12/13/2018 1:54:05 PM | | | | |
| Acuna, Johnny | | Will you please place two cord strips right outside my classroom. (Mr. Stearns, G7) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 207330 | H-Wing | Auditorium | | | 12/11/2018 | | 37 | | \$0.00 |
| Medium | Work In Progress | main gym/old | | | 12/11/2018 10:30:24 | | | | |
| Acuna, Johnny | | Bleacher step behind score table is loose and unsecure. Please see coach Rojas. (Ms. Lopez, principal) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 207331 | H-Wing | Auditorium | | | 12/11/2018 | | 37 | | \$0.00 |
| Medium | Work In Progress | main gym/old | | | 12/11/2018 10:31:35 | | | | |
| Acuna, Johnny | | North scoreboard lights on 1st set of time numbers burned out. (Ms. Lopez, principal) | | | | | | | |
| Mireya Meza | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 207003 | A-Wing | Auditorium | | | 12/5/2018 | | 43 | | \$0.00 |
| Medium | Work In Progress | Auxiliary gym | | | 12/5/2018 1:12:27 PM | | | | |
| Acuna, Johnny | | Johnny we have a white board in room A-103 that needs to be placed in the new auxiliary gym for the wrestling coach. It should replace the small one that is there. (Mireya Meza) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 207068 | R-Wing | Classroom | | | 12/6/2018 | | 42 | | \$0.00 |
| Medium | Work In Progress | R5 | | | 12/6/2018 10:51:28 AM | | | | |
| Acuna, Johnny | | Second freezer is not at temperature. (Mrs. Garcia, R5) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 207826 | | | | | 12/31/2018 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 12/31/2018 1:46:39 AM | | | | |
| Flores, Pete | | Monthly - District Tractors - Full Service PM - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 206462 | Field House | Athletic Field | | | 11/27/2018 | | 51 | | \$0.00 |
| Medium | Work In Progress | soccer field | | | 11/27/2018 2:34:07 PM | | | | |
| Ontiveros, Guadalupe | | Please winterize the soccer fields. (Mireya Meza) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 206160 | | | | | 11/15/2018 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | | 11/15/2018 12:42:28 | | | | |
| Villalobos, Jose | | Yearly - Chaparral HS Mower M-CHS-0428 PM Service - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205872 | | | | | 11/8/2018 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | | 11/8/2018 3:46:48 PM | | | | |
| Vallejo, Albert | | Please send contractor to repair main back flow Irrigation valve. Valve is leaking. (Located on County line Road at CHS next to Sunrise Elementary) | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 207725 | | | | | 12/19/2018 | | 29 | | \$0.00 |
| Medium | Work In Progress | | | | 12/19/2018 3:09:01 PM | | | | |
| Tellez, Hector | | need recessed light in section E bathroom | | | | | | | |
| Hector Tellez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-----------------------|------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 200241 | | | | | 8/14/2018 | | 156 | | \$0.00 |
| Medium | Work In Progress | | | 8/14/2018 11:19:22 AM | | | | | |
| Tellez, Hector | | Please wire up Air-Compressor outside of Art Room in back of the Q-Bldg. | | | | Pending - Asp report 10/30/18 - have not gotten to it | | | |
| Johnny Acuna | | | | | | | | | |
| 204768 | | | | | 10/25/2018 | | 84 | | \$0.00 |
| Medium | Work In Progress | | | 10/25/2018 3:06:37 PM | | | | | |
| Acuna, Johnny | | Need (2) AP81 Fan Belts for Auto Shop rooftop Exhausts Fans. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 206935 | | | | | 12/4/2018 | | 44 | | \$0.00 |
| Medium | Work In Progress | | | 12/4/2018 3:43:24 PM | | | | | |
| Ambriz, Jose | | Need assistance with mini split unit inside the riser room in the pre-k Bldg. Unit making lots of noise from the blower coil section. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 207721 | R-Wing | Classroom | | | 12/19/2018 | | 29 | | \$0.00 |
| Medium | Work In Progress | R5 | | 12/19/2018 2:04:41 PM | | | | | |
| Ambriz, Jose | | Freezer Motor is grinding. (Mrs. Garcia, R5) | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 206569 | | | | | 11/28/2018 | | 50 | | \$0.00 |
| High | Work In Progress | | | 11/28/2018 10:21:29 | | | | | |
| Marquez, Gerardo | | The rear egress door in the culinary arts class has a double sided key lock. Only one lock can be used on this door in accordance with this code, must complete within 7 days. | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 206636 | | Gym | | | 11/29/2018 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | 11/29/2018 9:26:41 AM | | | | | |
| Villalobos, Jose | | Need 2 100 ft extension cords for blowers in both gyms. | | | | | | | |
| Jesus Urquidi | | | | | | | | | |
| 204395 | Q-Wing | Hallway/Corridor | | | 10/19/2018 | | 90 | | \$0.00 |
| Medium | Work In Progress | sidewalk going | | 10/19/2018 10:59:30 | | | | | |
| Vallejo, Albert | | Sidewalk leading up to the Q building has a large broken section that needs to be repaired. (Victoria Lopez, principal) | | | | | | | |
| Mireya Meza | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-----------------------|------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 204182 | | | | | 10/16/2018 | | 93 | | \$0.00 |
| Medium | Work In Progress | | | 10/16/2018 3:40:11 PM | | | | | |
| Acuna, Johnny | | Need to make concrete curb outdoors next to door in Boy's locker room to old Gym. Also, need to caulk around all corners and joints. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 204941 | | | | | 10/29/2018 | | 80 | 2 | \$50.00 |
| Medium | Work In Progress | | | 10/29/2018 1:28:11 PM | | | | | |
| Vallejo, Albert | | Need to replace corroded pipe to the fire sprinkler system inside the Electric fire pump room located within the main building. Pipe is located on the left bottom side going into the Electric fire pump room and also check the valves are corroded. | | | | 10/31/18 - Checked by Joe, need to send Dimar | | | |
| Johnny Acuna | | | | | | | | | |
| 206929 | | | | | 12/4/2018 | | 44 | | \$0.00 |
| Medium | Work In Progress | | | 12/4/2018 3:41:32 PM | | | | | |
| Vallejo, Albert | | Need to replace some corroded fittings on the fire protection and geothermal system above the walk in inside the kitchen in the main building. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 206993 | | | | | 12/5/2018 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/5/2018 11:24:32 AM | | | | | |
| Villalobos, Jose | | stihl back pac blower having problems with the string starter gets stuck when you pull it. stihl back-pac blower # 1614. | | | | | | | |
| Javier Villalva | | | | | | | | | |
| 205401 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:49:00 AM | | | | | |
| Facio, Dino | | Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205358 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:29 AM | | | | | |
| Facio, Dino | | Yearly - Chaparral HS - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|----------------------------|-----------------------|------------------|-------------------------------|-----------|-------------|-----------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 207397 | | | | | 12/12/2018 | | 36 | | \$0.00 |
| Medium | Work In Progress | | | 12/12/2018 8:34:24 AM | | | | | |
| Carrasco, Danny | | Need to Borrow and transport small scissor lift to clean out strainers to Refrigeration units in the band room Attic area. Thanks. (need the one from warehouse) | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 201964 | | Kitchen | | | 9/10/2018 | | 129 | | \$62.00 |
| High | Work In Progress | | | 9/10/2018 9:09:27 AM | | | | | |
| Villalobos, David | | Ice machine not making ice (defrost) SNP Mgr. Juanita M. (575) 882-6717 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 207462 | | Kitchen | | | 12/13/2018 | | 35 | | \$0.00 |
| High | Work In Progress | | | 12/13/2018 7:03:38 AM | | | | | |
| Villalobos, David | | Check steam line drain pipe disconnected water flowing out onto floor | | | | | | | |
| Dino Facio | | | | | | | | | |
| Count: 36 Work Orders | | | Avg. Age of WO's 68 | | | Total for Chaparral HS | | 2 | \$133.60 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-----------------------|------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral MS | | | | | | | | | |
| 206581 | | Kitchen | | | 11/28/2018 | | 50 | | \$0.00 |
| High | Work In Progress | | | 11/28/2018 1:53:26 PM | | | | | |
| Medina, Eric | | On/Off switch on milk cooler broken | | | | | | | |
| Dino Facio | | | | | | | | | |
| 201897 | | Classroom | | | 9/7/2018 | | 132 | | \$0.00 |
| Medium | Work In Progress | | | 9/7/2018 3:27:11 PM | | | | | |
| Vallejo, Albert | | Attention to Ruben Warehouse, Need 3 windows and several screens replaced. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 201757 | Main Building | Restroom | | | 9/6/2018 | | 133 | | \$0.00 |
| Medium | Work In Progress | various locations | | 9/6/2018 10:25:03 AM | | | | | |
| Perez, M. Carmen | | Please install paper dispensers and soap dispensers in all restrooms | | | | | | | |
| Maria Garcia | | | | | | | | | |
| 205354 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:25 AM | | | | | |
| Facio, Dino | | Yearly - Chaparral MS - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205385 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:50 AM | | | | | |
| Facio, Dino | | Monthly - Chapparral MS Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 200165 | Main Building | Office | | | 8/13/2018 | | 157 | | \$0.00 |
| Medium | Work In Progress | front office | | 8/13/2018 3:46:37 PM | | | | | |
| Marquez, Gerardo | | Requesting secretaries door to be a concession door (door that the top is open and the bottom can be closed) ~Mrs. Maria Hernandez | | | | APCO | | | |
| Maria Garcia | | | | | | | | | |
| 204069 | | Kitchen | | | 10/15/2018 | | 94 | | \$0.00 |
| High | Work In Progress | | | 10/15/2018 9:23:47 AM | | | | | |
| Carbajal, Jimmy | | Floor tiles and wall molding underneath three compartment sink are coming apart need to be repaired as per State Insp. SNP Mgr. (575) 882-6708 | | | | Asp A. Ortiz, spoke to Jimmy - Warranty Issue | | | |
| Dino Facio | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-----------------------|------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral MS | | | | | | | | | |
| 206750 | | Custodial | | | 11/30/2018 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2018 1:06:15 PM | | | | | |
| Villalobos, Jose | | necesitamos Requesting a 13 inch scrubber for restrooms GRACIAS | | | | | | | |
| M. Carmen Perez | | | | | | | | | |
| 204671 | Main Building | Classroom | | | 10/24/2018 | | 85 | | \$0.00 |
| Medium | Work In Progress | various locations | | 10/24/2018 1:56:47 PM | | | | | |
| Marquez, Gerardo | | Please change locks on all doors as per fire Marshall inspection see Alfredo Ortiz for better explanation | | | | | | | |
| Maria Garcia | | | | | | | | | |
| 201992 | | | | | 9/10/2018 | | 129 | | \$0.00 |
| Medium | Work In Progress | | | 9/10/2018 1:28:09 PM | | | | | |
| Marquez, Gerardo | | Need locksmith in room 301, can't open filing cabinet, key just turns. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 206631 | | | | | 11/29/2018 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | 11/29/2018 8:38:03 AM | | | | | |
| Holguin, Ramiro | | need to treat football field for grab warm. | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 207700 | | Gym | | | 12/19/2018 | | 29 | 1.5 | \$37.50 |
| Medium | Work In Progress | | | 12/19/2018 7:12:49 AM | | | | | |
| Ambriz, Jose | | senesecita areglar water fountain de los locker delas Girls Gracias | | | | removed cover and probed contact pints, unit has power at switch with an audible click (relay)? Route to HVAC | | | |
| M. Carmen Perez | | | | | | | | | |
| 204933 | | Mechanical | | | 10/29/2018 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/29/2018 10:52:14 | | | | | |
| Ambriz, Jose | | Need assistance to repair water leak on heating hot water lines. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 200571 | Main Building | Hallway/Corridor | | | 8/20/2018 | | 150 | | \$795.00 |
| Medium | Work In Progress | | | 8/20/2018 9:51:26 AM | | | | | |
| Ambriz, Jose | | The Refrigerated water Fountain won't stop running. Water coming out all the time. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| Selected Date Range for Request Dates:7/1/2018 - 12/31/2018 Order By Location, Status | | | | | | | | | | Total Costs |
|---|------------------|--|-------------|-----------------------|-------------------|---|-----------|-------------|--------|-------------|
| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | | |
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | | |
| Assigned To | | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | | |
| Location: Chaparral MS | | | | | | | | | | |
| 199851 | Main Building | Classroom | | | 8/9/2018 | | 161 | | \$0.00 | |
| Medium | Work In Progress | Baseball Field | | 8/9/2018 9:59:41 AM | | | | | | |
| Tellez, Hector | | Need Electricity at Baseball Field for use of pitching machine. We are having to use three 50' extension cords to power up machine.This could lead to a very dangerous situation for our student athletes and coaching staff. See Mr. Owen | | | | Pending - Asp report 10/30/18 - Project | | | | |
| Maria Garcia | | | | | | | | | | |
| 203532 | | Classroom | | | 10/3/2018 | | 106 | | \$0.00 | |
| Medium | Work In Progress | | | 10/3/2018 9:10:05 AM | | | | | | |
| Ontiveros, Joe | | Having problem with water valve in Science room need assistance. | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | | |
| 206473 | | | | | 11/27/2018 | | 51 | | \$0.00 | |
| High | Work In Progress | | | 11/27/2018 3:05:10 PM | | | | | | |
| Marquez, Gerardo | | Double side key locks need to be removed from all plumbing chases, boys and girls locker rooms. Replace so that anyone from inside can open if they get locked in. In the football locker room pad locks need to be removed from doors including cages, must complete within 7 days. | | | | | | | | |
| Rafael Gallegos | | | | | | | | | | |
| 206474 | | | | | 11/27/2018 | | 51 | | \$0.00 | |
| High | Work In Progress | | | 11/27/2018 3:06:23 PM | | | | | | |
| Marquez, Gerardo | | On the outside gate there was a chain and lock. If it is going to be locked, anyone who will need to use this gate as an emergency exit needs to have a key., must complete within 7 days. | | | | | | | | |
| Rafael Gallegos | | | | | | | | | | |
| 202945 | | | | | 9/26/2018 | | 113 | | \$0.00 | |
| Medium | Work In Progress | various locations | | 9/26/2018 8:09:42 AM | | | | | | |
| Perez, M. Carmen | | Please replace all soap dispensers | | | | | | | | |
| Maria Garcia | | | | | | | | | | |
| 202947 | Main Building | Restroom | | | 9/26/2018 | | 113 | | \$0.00 | |
| Medium | Work In Progress | various locations | | 9/26/2018 8:12:58 AM | | | | | | |
| Perez, M. Carmen | | replace toilet paper dispensers | | | | | | | | |
| Maria Garcia | | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-----------------------|-------------------------------|------------------|-----------|-------------|-------------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral MS | | | | | | | | | |
| 206469 | | | | | 11/27/2018 | | 51 | | \$0.00 |
| High | Work In Progress | | | 11/27/2018 2:58:43 PM | | | | | |
| Juzdowski, Jimmie | | Replace missing sprinkler heads, must complete within 7 days. | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 206470 | | | | | 11/27/2018 | | 51 | | \$0.00 |
| High | Work In Progress | | | 11/27/2018 3:00:26 PM | | | | | |
| Juzdowski, Jimmie | | Replace missing ceiling tiles in portable 4, must complete within 7 days. | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 206471 | | | | | 11/27/2018 | | 51 | | \$0.00 |
| High | Work In Progress | | | 11/27/2018 3:01:31 PM | | | | | |
| Juzdowski, Jimmie | | Opening in the ceiling of the counselors storage closet needs to be repaired, must complete within 7 days. | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 206472 | | | | | 11/27/2018 | | 51 | | \$0.00 |
| High | Work In Progress | | | 11/27/2018 3:02:33 PM | | | | | |
| Juzdowski, Jimmie | | Rescue windows in portables need to be labeled, must complete within 7 days. | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 205939 | | | | | 11/9/2018 | | 69 | | \$380.56 |
| Medium | Work In Progress | | | 11/9/2018 1:27:45 PM | | | | | |
| Juzdowski, Jimmie | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| Count: 25 Work Orders | | Avg. Age of WO's 86 | | | Total for Chaparral MS | | | 1.5 | \$1,213.06 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|----------------------------------|------------------|------------------------------|-----------|---------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Desert Pride HS | | | | | | | | | |
| 202449 | | | | | 9/17/2018 | | 122 | | \$0.00 |
| Medium | Work In Progress | | | 9/17/2018 2:40:51 PM | | | | | |
| Saucedo, Luis | | need to replace few chrome plated hinge kit for restroom partitions | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 202687 | | Exterior | | | 9/20/2018 | | 119 | | \$0.00 |
| Medium | Work In Progress | | | 9/20/2018 3:42:54 PM | | | | | |
| Ontiveros, Guadalupe | | Move the Security Guard Shack next to the Tuff shed by the trash can's where it was originally going to be. It is getting damaged in the spot its at. Already replaced pexi glass once. | | | | | | | |
| Maria Carbajal | | | | | | | | | |
| 200862 | | Office | | | 8/23/2018 | | 147 | | \$0.00 |
| Medium | Work In Progress | Confemoe | | 8/23/2018 10:06:08 AM | | | | | |
| Ambriz, Jose | | Ice machine switch has to be switched off and on to make ice. | | | | | | | |
| Maria Carbajal | | | | | | | | | |
| 202044 | | | | | 9/11/2018 | | 128 | | \$0.00 |
| Medium | Work In Progress | | | 9/11/2018 8:07:34 AM | | | | | |
| Marquez, Gerardo | | LATCH WAS PULLED OFF MAIN ENTRY DOOR. PLEASE CHECK IT OUT. | | | | | | | |
| Gerardo Marquez | | | | | | | | | |
| 207822 | | | | | 12/31/2018 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | 12/31/2018 1:46:37 AM | | | | | |
| Herrera, Marin | | Monthly - Desert Pride HS - Fire Ext. Insp (M) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 206101 | | | | | 11/14/2018 | | 64 | | \$0.00 |
| Medium | Work In Progress | | | 11/14/2018 1:02:51 PM | | | | | |
| Carbajal, Jimmy | | make cover for boxing ring | | | | faxed to Rodriguez for quote | | | |
| Jimmy Carbajal | | | | | | | | | |
| 200243 | | | | | 8/14/2018 | | 156 | | \$0.00 |
| Medium | Work In Progress | | | 8/14/2018 11:56:57 AM | | | | | |
| Marquez, Gerardo | | doors to portables #7, and 8 need replacing both doors from the bottom are rusted out from threshold. | | | | APCO | | | |
| Paul Quinones | | | | | | | | | |
| Count: 7 Work Orders | | Avg. Age of WO's 108 | | Total for Desert Pride HS | | | 0 | \$0.00 | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-----------------------|------------------|--|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Desert Trail ES | | | | | | | | | |
| 206570 | | Custodial | | | 11/28/2018 | | 50 | | \$0.00 |
| Medium | Work In Progress | | | 11/28/2018 11:06:06 | | | | | |
| Villalobos, Jose | | la aspiradora num 2234 el enchufe no prende por favor de revisarla gracias | | | | | | | |
| Laura Sandoval | | | | | | | | | |
| 206187 | Main Building | Portables | | | 11/15/2018 | | 63 | | \$0.00 |
| Medium | Work In Progress | ALL Portables | | 11/15/2018 9:24:31 AM | | | | | |
| Marquez, Gerardo | | Portable doors MUST be replaced. They lock up with the cold weather and are difficult to open. Jerry locksmith, has to be called to DTE to open the doors. This is a problem as students do arrive to DTE at 7:30 am. Doors are too old. | | | | | | | |
| | | ATTENTION: Vallejo | | | | | | | |
| Elizabeth Hernandez | | | | | | | | | |
| 198480 | Main Building | | | | 7/23/2018 | | 178 | | \$0.00 |
| Medium | Work In Progress | 412/411 | | 7/23/2018 10:26:31 AM | | | | | |
| Carbajal, Jimmy | | the linoleum immediately located around the toilet has lifted and will allow the urine to flow in and under the tiles | | | | 10/31/18 - on schedule for summer 2019 | | | |
| Elizabeth Hernandez | | | | | | | | | |
| 199197 | | | | | 8/2/2018 | | 168 | | \$0.00 |
| Medium | Work In Progress | | | 8/2/2018 11:04:47 AM | | | | | |
| Carbajal, Jimmy | | Portables 420,421 need carpet removed and replaced with tile/linoleum. | | | | 11/01/18 - IN PROCESS | | | |
| Elizabeth Hernandez | | | | | | | | | |
| 200697 | Main Building | Classroom | | | 8/21/2018 | | 149 | | \$0.00 |
| Medium | Work In Progress | 420-421 | | 8/21/2018 2:07:26 PM | | | | | |
| Gonzalez, Salvador | | For portables 420-421 wooden ramps need to be replaces with metal ones. | | | | | | | |
| Elizabeth Hernandez | | | | | | | | | |
| 205386 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:50 AM | | | | | |
| Facio, Dino | | Monthly - Desert Trail ES - Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-------|-----------------------|-----------------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Desert Trail ES | | | | | | | | | |
| 205356 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | | 11/4/2018 12:48:26 AM | | | | |
| Facio, Dino | | Yearly - Desert Trail ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 199093 | | | | | 8/1/2018 | | 169 | | \$0.00 |
| Medium | Work In Progress | | | | 8/1/2018 9:20:25 AM | | | | |
| Gonzalez, Salvador | | please I need a truck rack for ladder , truck # 110 | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 206016 | | | | | 11/13/2018 | | 65 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2018 10:38:23 | | | | |
| Vargas, Juan | | Coil Heating unit to kitchen office is not working. Possibly bad motor. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 207560 | Main Building | Classroom | | | 12/14/2018 | | 34 | | \$0.00 |
| Medium | Work In Progress | 207 | | | 12/14/2018 1:33:22 PM | | | | |
| Villalobos, Margret | | Need treatment in room 207 due to bed bugs | | | | Approved 12/14/18 EM Waiver | | | |
| Elizabeth Hernandez | | | | | | | | | |
| 205237 | Main Building | Exterior | | | 11/1/2018 | | 77 | | \$3.98 |
| Medium | Work In Progress | front of the | | | 11/1/2018 3:36:02 PM | | | | |
| Vargas, Juan | | repair small bench that serves as a decoration if unable to repair please see Ms. Barajas | | | | | | | |
| Elizabeth Hernandez | | | | | | | | | |
| 205900 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | | 11/9/2018 11:04:21 AM | | | | |
| Vargas, Juan | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 207463 | | Kitchen | | | 12/13/2018 | | 35 | | \$0.00 |
| High | Work In Progress | | | | 12/13/2018 7:06:06 AM | | | | |
| Medina, Eric | | Check steam line no power not functioning | | | | | | | |
| Dino Facio | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Desert Trail ES | | | | | | | | | |
| 207346 | | Kitchen | | | 12/11/2018 | | 37 | | \$0.00 |
| High | Work In Progress | | | | 12/11/2018 2:16:19 PM | | | | |
| Villalobos, David | | Check the floor in walk in bolts coming up | | | | | | | |
| Dino Facio | | | | | | | | | |
| 207464 | | Kitchen | | | 12/13/2018 | | 35 | | \$0.00 |
| High | Work In Progress | | | | 12/13/2018 7:08:18 AM | | | | |
| Villalobos, David | | Check rubber seal on warmer coming off door wont close completely | | | | | | | |
| Dino Facio | | | | | | | | | |
| 205742 | | Kitchen | | | 11/7/2018 | | 71 | | \$0.00 |
| High | Work In Progress | | | | 11/7/2018 2:23:37 PM | | | | |
| Villalobos, David | | salad sink has broken tube leaking | | | | | | | |
| Dino Facio | | | | | | | | | |
| 199980 | | Kitchen | | | 8/10/2018 | | 160 | | \$0.00 |
| High | Work In Progress | | | | 8/10/2018 2:06:25 PM | | | | |
| Villalobos, David | | Check disposal making loud noise when in use SNP Mgr. Patricia C. (575) 882-6717 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 198152 | | | | | 7/16/2018 | | 185 | | \$0.00 |
| Medium | Work In Progress | | | | 7/16/2018 3:29:33 PM | | | | |
| Ontiveros, Guadalupe | | need to replace 2 dead tree in the front office | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 204256 | | | | | 10/17/2018 | | 92 | | \$867.44 |
| Medium | Work In Progress | | | | 10/17/2018 3:28:42 PM | | | | |
| Ambriz, Jose | | in portable 404 need replaced transformer in heat unite | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 207468 | | Kitchen | | | 12/13/2018 | | 35 | | \$0.00 |
| High | Work In Progress | | | | 12/13/2018 7:34:24 AM | | | | |
| Tellez, Hector | | Electrical pole in kitchen area needs to be covered wires are exposed | | | | | | | |
| Dino Facio | | | | | | | | | |
| 201689 | | | | | 9/5/2018 | | 134 | | \$78.27 |
| Medium | Work In Progress | | | | 9/5/2018 1:15:45 PM | | | | |
| Tellez, Hector | | need to hook up serving line in kitchen | | | | | | | |
| Hector Tellez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| Selected Date Range for Request Dates:7/1/2018 - 12/31/2018 Order By Location, Status | | | | | | | | | Total Costs |
|---|------------------|--|------------------|-----------------------|-------------------|------------------|---------------------------|-------------|-------------|
| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | |
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | Action Taken | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert Trail ES | | | | | | | |
| 207668 | | | | | 12/18/2018 | | 30 | | \$0.00 |
| Medium | Work In Progress | | | 12/18/2018 3:15:12 PM | | | | | |
| Tellez, Hector | | need fix lamp in lobby area | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 205292 | | | | | 11/2/2018 | | 76 | | \$0.00 |
| Medium | Work In Progress | | | 11/2/2018 2:33:13 PM | | | | | |
| Tellez, Hector | | Wall clock in room 204 is not working, not sure if able to be fixed. | | | | | | | |
| Elizabeth Hernandez | | | | | | | | | |
| Count: 23 Work Orders | | | Avg. Age of WO's | | 90 | | Total for Desert Trail ES | | 0 \$949.69 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Desert View ES | | | | | | | | | |
| 206451 | | | | | 11/27/2018 | | 51 | | \$0.00 |
| Medium | Work In Progress | | | | 11/27/2018 1:46:17 PM | | | | |
| Pacheco, Hector | | Bathrooms in 305 the urinal is clogged and overflowing. | | | | | | | |
| Ruben Ortiz | | Thank you Ruben | | | | | | | |
| 206439 | | | | | 11/27/2018 | | 51 | | \$0.00 |
| High | Work In Progress | | | | 11/27/2018 1:17:33 PM | | | | |
| Lara, Ralph | | In nurses office locks and latches on the screen door need to be removed, must complete within 7 days. | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 207242 | | | | | 12/10/2018 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 12/10/2018 9:19:36 AM | | | | |
| Ontiveros, Guadalupe | | Need to borrow a Tractor for work order # 205556 at Desert View ES. Thank you Ruben | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 207827 | | | | | 12/31/2018 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | | 12/31/2018 1:46:40 AM | | | | |
| Flores, Pete | | Monthly - Desert View - UV-DV-0516 PM Service - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 206438 | | | | | 11/27/2018 | | 51 | | \$0.00 |
| High | Work In Progress | | | | 11/27/2018 1:14:17 PM | | | | |
| Ortiz, Ruben | | Need to order for restock (6) sprinkler heads and wrench, must complete within 7 days. | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 204651 | | | | | 10/24/2018 | | 85 | | \$0.00 |
| Medium | Work In Progress | Back of the | | | 10/24/2018 9:10:42 AM | | | | |
| Ortiz, Ruben | | There is a lot of weeds in the back of the school campus. | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |
| 205556 | | | | | 11/5/2018 | | 73 | | \$0.00 |
| Medium | Work In Progress | Lower | | | 11/5/2018 10:40:23 AM | | | | |
| Ortiz, Ruben | | Fill the sidewalk (by the lower playground) with dirt because it cracked. | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------------|------------------|--|----------------------------|-----------------------|---------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Desert View ES | | | | | | | | | |
| 205387 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:51 AM | | | | | |
| Facio, Dino | | Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205348 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:21 AM | | | | | |
| Facio, Dino | | Yearly - Desert View ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 204659 | | | | | 10/24/2018 | | 85 | | \$3.49 |
| Medium | Work In Progress | | | 10/24/2018 11:44:15 | | | | | |
| Villalobos, Jose | | Tiller is not working correctly, need it repaired. Thank you, Ruben | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| Count: 10 Work Orders | | | Avg. Age of WO's 60 | | Total for Desert View ES | | | 0 | \$3.49 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 206829 | | | | | 12/3/2018 | | 45 | | \$0.00 |
| Medium | Work In Progress | CRRUA | | 12/3/2018 11:26:24 AM | | | | | |
| Lara, Ralph | | SLIDING DOOR FROM CRRUA MAIN ENTRANCE DOES NOT CLOSE COMPLETELY. EMPLOYEES ARE HAVING TO PUSH THE DOOR OPEN AND SHUT. | | | | | | | |
| Marylou Delgado | | | | | | | | | |
| 205346 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:20 AM | | | | | |
| Facio, Dino | | Yearly - GAC - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205400 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:59 AM | | | | | |
| Facio, Dino | | Monthly - GAC Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 197869 | | Kitchen | | | 7/10/2018 | | 191 | | \$0.00 |
| High | Work In Progress | | | 7/10/2018 9:42:18 AM | | | | | |
| Villalobos, David | | Oven not working properly (circuit board) SNP Mgr. Irma V. (575) 882-6784 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 205903 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2018 11:06:46 AM | | | | | |
| Ortiz, Ruben | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 205064 | | Office | | | 10/30/2018 | | 79 | | \$0.00 |
| Medium | Work In Progress | C-WING | | 10/30/2018 3:51:22 PM | | | | | |
| Rodriguez, Arturo | | PLEASE MOVE 2 FILING CABINETS FROM HALLWAY TO OFFICES (1 CABINET TO OFFICE #112 AND 1 TO OFFICE #217) AND 3 CHAIRS. THANK YOU. | | | | | | | |
| Karla Quesada | | | | | | | | | |
| 205577 | | | | | 11/5/2018 | | 73 | | \$0.00 |
| Medium | Work In Progress | WORK CTR 200 | | 11/5/2018 1:13:05 PM | | | | | |
| Soriano, David | | WORK ROOM CENTER NEEDS 12 SETS OF BLINDS ON WINDOWS | | | | | | | |
| Marylou Delgado | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-------|-----------------------|----------------------|-----------|-----------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 207552 | | Hallway/Corridor | | | 12/14/2018 | | 34 | | \$34.50 |
| Medium | Work In Progress | | | | 12/14/2018 11:16:43 | | | | |
| Soriano, David | | Felipa, our custodian, mentioned to me that the three hallway ceiling lights closet to Erica and Georgina's offices do not light up. Please replace blubs. Thank you. | | | | | | | |
| Anne De Los Santos | | | | | | | | | |
| 205739 | | | | | 11/7/2018 | | 71 | | \$379.86 |
| Medium | Work In Progress | | | | 11/7/2018 2:12:36 PM | | | | |
| Hernandez, Guillermo | | As per Albert change filters at GAC. | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 207244 | | Custodial | | | 12/10/2018 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 12/10/2018 9:29:35 AM | | | | |
| Pacheco, Hector | | Broken faucet in the custodial room by the 200 wing. Need it replace. Thank you Ruben | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 207246 | | Office | | | 12/10/2018 | | 38 | | \$0.00 |
| Medium | Work In Progress | C-WING | | | 12/10/2018 9:40:13 AM | | | | |
| Castillo, Carlos | | PLEASE ADD AN ELECTRICAL OUTLET TO OFFICE #117 (MS. YS) IN C-WING FOR THE MONITOR PLUG. THANK YOU! | | | | | | | |
| Karla Quesada | | | | | | | | | |
| 205580 | | | | | 11/5/2018 | | 73 | | \$409.89 |
| Medium | Work In Progress | 200 WING | | | 11/5/2018 1:23:30 PM | | | | |
| Soriano, David | | CONFERENCE ROOM #2 & #3 NEEDS PAINTING AND CEILING TILES REPLACED. | | | | | | | |
| Marylou Delgado | | | | | | | | | |
| Count: 12 Work Orders | | Avg. Age of WO's | 72 | | | Total for GAC | 0 | \$824.25 | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------|------------------|---------------------------------|------------------|-----------------------|------------------|-----------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Location: | GAC - Pre-K | | | | | | | | |
| 203990 | | | | | 10/12/2018 | | 97 | | \$0.00 |
| High | Work In Progress | Main entrance | | 10/12/2018 9:22:50 AM | | | | | |
| Lara, Ralph | | The front left door won't open. | | | | | | | |
| | | Thank you! | | | | | | | |
| | | Micaela | | | | | | | |
| Micaela Paniagua | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Count: 1 Work Orders | | | Avg. Age of WO's | 97 | | Total for GAC - Pre-K | 0 | | \$0.00 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden ES | | | | | | | | | |
| 206453 | | Kitchen | | | 11/27/2018 | | 51 | | \$0.00 |
| High | Work In Progress | | | 11/27/2018 1:48:28 PM | | | | | |
| Villalobos, David | | Check tomato slicer locked up | | | | | | | |
| Dino Facio | | | | | | | | | |
| 207771 | | | | | 12/20/2018 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | 12/20/2018 9:06:58 AM | | | | | |
| Medina, Eric | | OVEN FRONT PANEL, BUTTONS HARD TO PRESS TO TURN ON. THANK YOU. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 205404 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:49:04 AM | | | | | |
| Facio, Dino | | Monthly - Gadsden ES - Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205344 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:18 AM | | | | | |
| Facio, Dino | | Yearly - Gadsden ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 206635 | | | | | 11/29/2018 | | 49 | | \$110.17 |
| Medium | Work In Progress | | | 11/29/2018 9:15:07 AM | | | | | |
| Carrasco, Danny | | requesting caulking gun to seal expansion joints at Gadsden elementary | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 206202 | | | | | 11/15/2018 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | 11/15/2018 3:06:30 PM | | | | | |
| Ontiveros, Guadalupe | | requesting wood chips for west end playground approximately 4 truck loads | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 207722 | | | | | 12/19/2018 | | 29 | | \$0.00 |
| Medium | Work In Progress | | | 12/19/2018 2:13:21 PM | | | | | |
| Quinones, Paul | | double doors between classrooms need door handles to open and close doors. teachers are having a hard time opening and closing doors with key | | | | | | | |
| Paul Quinones | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|-------------------|---|-------------------------|-----------------------|------------------|-----------------------------|-----------|-------------|-----------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Location: | Gadsden ES | | | | | | | | |
| 205905 | | | | | 11/9/2018 | | 69 | | \$547.48 |
| Medium | Work In Progress | | | 11/9/2018 11:08:14 AM | | | | | |
| Quinones, Paul | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Count: 8 Work Orders | | | Avg. Age of WO's | 55 | | Total for Gadsden ES | 0 | | \$657.65 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 207823 | | | | | 12/31/2018 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | 12/31/2018 1:46:38 AM | | | | | |
| Flores, Pete | | Monthly - District Tractors - Full Service PM - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207824 | | | | | 12/31/2018 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | 12/31/2018 1:46:38 AM | | | | | |
| Flores, Pete | | Monthly - District Tractors - Full Service PM - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 203121 | | | | | 9/28/2018 | | 111 | | \$0.00 |
| Medium | Work In Progress | | | 9/28/2018 2:11:19 PM | | | | | |
| Ontiveros, Guadalupe | | Requested by Mr. David Martinez-The weeds in the retention pond between the Annex and CTE Building need to be removed over the Fall Break. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 207234 | Varsity Gym | Gym | | | 12/10/2018 | | 38 | | \$0.00 |
| Medium | Work In Progress | DAVID | | 12/10/2018 8:21:31 AM | | | | | |
| Ontiveros, Guadalupe | | LUPE, CAN YOU PLEASE MOVE 1 WRESTLING MAT FROM SANTA TERESA HS TO GADSDEN HS ON JAN. 3, 2019 IN THE MORNING. GHS WILL HAVE A JV WRESTLING TOURNAMENT ON JAN. 3RD AT 3PM. IF YOU HAVE ANY QUESTIONS, PLEASE CONTACT KAREN IN ATHLETIC DEPT. THANK YOU! | | | | | | | |
| Terry Alvarado | | | | | | | | | |
| 206159 | | | | | 11/15/2018 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | 11/15/2018 12:42:27 | | | | | |
| Villalobos, Jose | | Yearly - Gadsden HS- Mower M-GHS-0408 Grounds - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 203601 | | | | | 10/8/2018 | 10/23/2018 | 101 | | \$0.00 |
| Medium | Work In Progress | | | 10/8/2018 2:38:16 AM | | | | | |
| Chavez, Miguel | | Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details. | | | | | | | |
| Jimmy Carbajal | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 201313 | | | | | 8/30/2018 | | 140 | | \$0.00 |
| Medium | Work In Progress | | | 8/30/2018 2:38:13 PM | | | | | |
| Prospero, Manuel | | Requested by Chief Jesus Escudero Rm. 200A North Building-ROTC Uniform storage room rood is leaking. Water maybe leaking to ROTC Uniforms. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 200832 | Vocational | Restroom | | | 8/22/2018 | | 148 | | \$285.00 |
| Medium | Work In Progress | | | 8/22/2018 5:06:30 PM | | | | | |
| Escobar, David | | Boys restroom in the Tech/vocational building exhaust fan is not working | | | | | | | |
| Miguel Chavez | | | | | | | | | |
| 203856 | | | | | 10/10/2018 | | 99 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2018 3:33:40 PM | | | | | |
| Escobar, David | | install of 2 canister water filters at varsity gym concession stand. | | | | | | | |
| David Escobar | | | | | | | | | |
| 205906 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2018 11:09:06 AM | | | | | |
| Escobar, David | | ADAConcerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 205928 | | | | | 11/9/2018 | | 69 | | \$215.65 |
| Medium | Work In Progress | | | 11/9/2018 11:34:27 AM | | | | | |
| Escobar, David | | Fields - Install Wheelchair Signs on all ADA spaces on bleachers. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 207422 | | | | | 12/12/2018 | | 36 | | \$0.00 |
| Medium | Work In Progress | | | 12/12/2018 2:48:26 PM | | | | | |
| Escobar, David | | trouble shoot RTU at room 609 science bldg. no heating. | | | | | | | |
| David Escobar | | | | | | | | | |
| 202283 | | | | | 9/13/2018 | | 90 | 22.5 | \$632.76 |
| Medium | Work In Progress | | | 9/13/2018 1:56:19 PM | 12/12/2018 | | | | |
| Escobar, David | | Requested by Coach Andrew Moralez for Tennis Courts- Assemble and stain three picnic tables for Tennis Courts. Tables located on Tennis Courts. | | | | built tables | | | |
| Velia Alarcon | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|--------------------|------------------|--|--|--|-----------------------|------------|-----|--|----------|
| 206098 | | | | | 11/14/2018 | | 64 | | \$0.00 |
| Medium | Work In Progress | | | | 11/14/2018 12:47:24 | | | | |
| Vallejo, Albert | | Install infrastructure for GHS domestic water feed. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 207636 | Cafeteria (1998) | Restroom (Girls) | | | 12/17/2018 | | 31 | | \$445.45 |
| Medium | Work In Progress | | | | 12/17/2018 3:45:58 PM | | | | |
| Appelzoller, Fred | | water leaking on flush valve need to shut off water to restroom to repair | | | | | | | |
| Fred Appelzoller | | | | | | | | | |
| 204924 | | | | | 10/29/2018 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | | 10/29/2018 9:20:06 AM | | | | |
| Appelzoller, Fred | | Requested by Mr. Ken Bailey for Weight Room-The Weight Room must have a shower Drain as soon as possible in the girl's dressing room. This is a health hazard. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 204318 | | | | | 10/18/2018 | | -3 | | \$0.00 |
| Medium | Work In Progress | | | | 10/18/2018 11:26:15 | 10/15/2018 | | | |
| Appelzoller, Fred | | Girls shower in the weight room is backed up ever since there the boys shower was unclogged with the snake tool. If more information is needed please ask Joey Munoz | | | | | | | |
| 203663 | | | | | 10/8/2018 | | 101 | | \$35.97 |
| Medium | Work In Progress | | | | 10/8/2018 10:59:43 AM | | | | |
| Appelzoller, Fred | | 10/8/18. SHOWERAY WAIT ROOM IS CLOGG.NEED ASSISTIN | | | | | | | |
| Manuel Prospero | | | | | | | | | |
| 207601 | | | | | 12/16/2018 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 12/16/2018 12:51:29 | | | | |
| Prospero, Manuel | | Monthly - Gadsden HS Grease Treatment - Culinary - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 199626 | | | | | 8/7/2018 | | 163 | | \$25.80 |
| Medium | Work In Progress | | | | 8/7/2018 10:18:22 AM | | | | |
| Chavez, Santos | | Requested by Mr. Ramon Quiroga Rm. 516 CTE Building-Instaalaation of new electrical outlet in flower shop area. | | | | | | | |
| Velia Alarcon | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|--------|--|--|--|--|------------|--|----|--|--------|
| 206410 | | | | | 11/27/2018 | | 51 | | \$0.00 |
|--------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|-----------------------|--|--|--|--|--|
| Medium | Work In Progress | | | 11/27/2018 8:28:35 AM | | | | | |
|--------|------------------|--|--|-----------------------|--|--|--|--|--|

Chavez, Santos Please fix 4th pole light on south side gate

Manuel Prospero

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|----|--|------------|
| 205530 | | | | | 11/5/2018 | | 30 | | \$1,648.56 |
|--------|--|--|--|--|-----------|--|----|--|------------|

| | | | | | | | | | |
|--------|------------------|--|--|----------------------|-----------|--|--|--|--|
| Medium | Work In Progress | | | 11/5/2018 7:54:34 AM | 12/5/2018 | | | | |
|--------|------------------|--|--|----------------------|-----------|--|--|--|--|

Hernandez, Guillermo Need to order and replace module actuator/ module actuator economizer to units at North building RTU's, as per the Intelligent Service Building Performance Report done by Trane.

Guillermo Hernandez

| | | | | | | | | | |
|--------|--|--|--|--|------------|--|----|--|--------|
| 206319 | | | | | 11/16/2018 | | 62 | | \$0.00 |
|--------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|-----------------------|--|--|--|--|--|
| Medium | Work In Progress | | | 11/16/2018 4:21:42 PM | | | | | |
|--------|------------------|--|--|-----------------------|--|--|--|--|--|

Ambriz, Jose Requested by Mr. Ramon Quiroga for Flower Shop in CTE Building-Floral cooler keeps freezing.

Velia Alarcon

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|-----|--|--------|
| 203116 | | | | | 9/28/2018 | | 111 | | \$0.00 |
|--------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|----------------------|--|--|--|--|--|
| Medium | Work In Progress | | | 9/28/2018 1:12:59 PM | | | | | |
|--------|------------------|--|--|----------------------|--|--|--|--|--|

Lara, Ralph Requested by Mrs. Virginia Lerma Rm. 210 North Building-Lock on desk does not work and needs to be repaired.

Velia Alarcon

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|-----|--|--------|
| 203120 | | | | | 9/28/2018 | | 111 | | \$0.00 |
|--------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|----------------------|--|--|--|--|--|
| Medium | Work In Progress | | | 9/28/2018 1:32:58 PM | | | | | |
|--------|------------------|--|--|----------------------|--|--|--|--|--|

Lara, Ralph Requested by Velia-WORK ORDER # 200423 WAS COMPLETED, BUT ALL FOUR KEYS DO NOT OPEN THE BOYS BASKETBALL LOCKER ROOM. PLEASE PICK UP THE KEYS FROM VELIA'S OFFICE AND RE-KEY AS SOON AS POSSIBLE.

Velia Alarcon

| | | | | | | | | | |
|--------|--|--|--|--|-----------|--|-----|--|--------|
| 202574 | | | | | 9/19/2018 | | 120 | | \$0.00 |
|--------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|----------------------|--|--|--|--|--|
| Medium | Work In Progress | | | 9/19/2018 8:35:57 AM | | | | | |
|--------|------------------|--|--|----------------------|--|--|--|--|--|

Vasquez, Jose JD 997 Mower #0436 blades need to be replaced

Guadalupe Ontiveros

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|---|-------------|-------|-----------------------|--------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 200595 | | | | | 8/20/2018 | | 10 | 2 | \$131.00 |
| Medium | Work In Progress | | | | 8/20/2018 1:00:54 PM | 8/30/2018 | | | |
| Lara, Ralph | | Requested by Ms. Susana Arredondo Rm. 306 Academic Building-Staff member had her vehicle broken into on Friday morning. Everything was taken from her vehicle. Which includes her set of classroom keys. Keys are HE138 (classroom Key), 109, 110, 112 (all to built in cabinets), and mailbox # 6. COST OF RE-KEYING OR REPLACING KEYS NEED TO BE MADE TO MS. SUSANAARREDONDO. | | | | re keyed classroom | | | |
| Velia Alarcon | | | | | | | | | |
| 204565 | | | | | 10/23/2018 | | 86 | | \$0.00 |
| Medium | Work In Progress | | | | 10/23/2018 11:18:57 | | | | |
| Lara, Ralph | | Requested by Velia-Three additional J31 keys are needed for Portable #'s 7 & 8. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 204748 | | | | | 10/25/2018 | | 84 | | \$0.00 |
| Medium | Work In Progress | | | | 10/25/2018 11:00:53 | | | | |
| Lara, Ralph | | Requested by Ms. Keeley Muncrief Rm. 616 Science Building-Desk key (# 272) broke off and is in the desk cylinder and needs to be removed. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 204847 | | | | | 10/26/2018 | | 83 | | \$0.00 |
| Medium | Work In Progress | | | | 10/26/2018 10:46:06 | | | | |
| Lara, Ralph | | please look at bollards at GHS site for new lock mechanism and rekey and lock system. | | | | | | | |
| David Escobar | | | | | | | | | |
| 207358 | | | | | 12/11/2018 | | 37 | | \$0.00 |
| Medium | Work In Progress | | | | 12/11/2018 3:35:01 PM | | | | |
| Gonzalez, Salvador | | Need a custom built splash guard for the Wastewater plant | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 206088 | | | | | 11/14/2018 | | 64 | | \$0.00 |
| Medium | Work In Progress | | | | 11/14/2018 8:13:40 AM | | | | |
| Gonzalez, Salvador | | build frame extension for RTU at band portable. see BM for details and location. | | | | | | | |
| David Escobar | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 204471 | | | | | 10/22/2018 | | 87 | | \$0.00 |
| Medium | Work In Progress | | | | 10/22/2018 10:07:11 | | | | |
| Gonzalez, Salvador | | requesting frame be built for valve box by football field area. | | | | | | | |
| Fred Appelzoller | | | | | | | | | |
| 205341 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | | 11/4/2018 12:48:15 AM | | | | |
| Facio, Dino | | Yearly - Gadsden HS - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207145 | | Kitchen | | | 12/7/2018 | | 41 | | \$3.58 |
| High | Work In Progress | | | | 12/7/2018 8:17:33 AM | | | | |
| Villalobos, David | | Check washer draining water without even washing | | | | | | | |
| Dino Facio | | | | | | | | | |
| 205388 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | | 11/4/2018 12:48:51 AM | | | | |
| Facio, Dino | | Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 206106 | | | | | 11/14/2018 | | 64 | | \$0.00 |
| Medium | Work In Progress | | | | 11/14/2018 1:26:35 PM | | | | |
| Villalobos, David | | Vegetable sink has a leak in the strainer (down the drain), which is leaking to the floor. The plumber has fixed the leak in the line leading up from the floor. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 199022 | | Kitchen | | | 7/31/2018 | | 170 | | \$0.00 |
| High | Work In Progress | | | | 7/31/2018 2:21:32 PM | | | | |
| Medina, Eric | | Replace disposer on dish machine SNP Mgr. Frances B. (575) 882-6721 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 206460 | | Pump House | | | 11/27/2018 | | 51 | | \$0.00 |
| Medium | Work In Progress | | | | 11/27/2018 2:31:46 PM | | | | |
| Apodaca, Mario | | domestic water supply hook-up need to order water accessories | | | | | | | |
| Mario Apodaca | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 207820 | | | | | 12/31/2018 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | 12/31/2018 1:46:35 AM | | | | | |
| Apodaca, Mario | | Monthly - Gadsden HS- Filters (Pump Rm) Quarterly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207661 | | | | | 12/18/2018 | | 30 | | \$378.78 |
| Medium | Work In Progress | | | 12/18/2018 12:56:59 | | | | | |
| Prospero, Manuel | | 12/18/18. NEED TO CHANGED 2 EXIT SINGS ON NORTH BUILDING AND CHANGED LIGTH BULBS ON RESTROOMS. | | | | | | | |
| Manuel Prospero | | | | | | | | | |
| 202521 | Main Building | Restroom | | | 9/18/2018 | | 121 | | \$0.00 |
| Medium | Work In Progress | | | 9/18/2018 2:02:49 PM | | | | | |
| Prospero, Manuel | | Boys restroom in Old Main building urinal clogged and spilling water. Custodian shut water off and bagged urinal. | | | | | | | |
| Miguel Chavez | | | | | | | | | |
| 202428 | | | | | 9/17/2018 | | 122 | | \$0.00 |
| Medium | Work In Progress | | | 9/17/2018 11:01:51 AM | | | | | |
| Prospero, Manuel | | Requested by Mrs. Elizabeth Cuevas Rm. 206 North Building-Book shelf had a shelf fall. The shelf is now missing brackets. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 201849 | | | | | 9/7/2018 | | 132 | | \$0.00 |
| Medium | Work In Progress | | | 9/7/2018 9:21:18 AM | | | | | |
| Prospero, Manuel | | Requested by Ms. Miller for Girl's Restroom in the Annex Building-The 3rd stall toilet does not flush. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 199132 | | | | | 8/1/2018 | | 0 | 1 | \$146.70 |
| Medium | Work In Progress | | | 8/1/2018 3:14:32 PM | 8/1/2018 | | | | |
| Prospero, Manuel | | NEED REPLACE LIGHT BULLBS ON CAFETERIA. OSRAM DU LUX L 55W/830 CE V Z4N5 C | | | | | | | |
| Manuel Prospero | | | | | | | | | |
| 198267 | | | | | 7/18/2018 | | 183 | | \$0.00 |
| Medium | Work In Progress | | | 7/18/2018 9:39:49 AM | | | | | |
| Prospero, Manuel | | Requested by Ms. Rebecca Rodriguez for All Buildings- Entrance doors to all buildings need to be repainted inside and out. | | | | | | | |
| Velia Alarcon | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|--|-------------|-----------------------|-----------------------------|--|-----------|-------------|-------------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 207660 | | | | | 12/18/2018 | | 30 | | \$0.00 |
| Medium | Work In Progress | | | 12/18/2018 12:23:55 | | | | | |
| Lara, Ralph | | Requested by Mrs. Danielle Rodriguez for Rm. 721 Admin. Building-Door is completely off its hinges and needs to be repaired as soon as possible. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 206741 | | | | | 11/30/2018 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2018 9:51:16 AM | | | | | |
| Villalobos, Jose | | Requested by Jorge Diaz-ARoyal vacuum needs parts. PLEASE SEE JORGE FOR VACCUM. | | | | Joe - no HC at this site, please let him know that serial & or tag # on all equipment needs to be provided upon repair, thank you! | | | |
| Velia Alarcon | | | | | | | | | |
| 199852 | | | | | 8/9/2018 | | 161 | | \$0.00 |
| Medium | Work In Progress | | | 8/9/2018 10:21:33 AM | | | | | |
| Escobar, David | | requesting filters list for GHS site. | | | | | | | |
| David Escobar | | | | | | | | | |
| 205335 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:10 AM | | | | | |
| Vallejo, Albert | | Monthly - Gadsden HS Fire Suppression Culinary - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207720 | | | | | 12/19/2018 | | 29 | | \$0.00 |
| Medium | Work In Progress | | | 12/19/2018 1:42:06 PM | | | | | |
| Vallejo, Albert | | Core and replace footing for for light pole base by main office. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| Count: 51 Work Orders | | Avg. Age of WO's | | 75 | Total for Gadsden HS | | | 25.5 | \$3,949.25 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden MS | | | | | | | | | |
| 206641 | | Custodial | | | 11/29/2018 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | 11/29/2018 10:14:28 | | | | | |
| Villalobos, Jose | | Requesting 13in shower scrubber for gym bleachers. Thank you | | | | | | | |
| Martin Soria | | | | | | | | | |
| 201662 | | Kitchen | | | 9/5/2018 | | 2 | 1 | \$25.00 |
| High | Work In Progress | | | 9/5/2018 8:56:59 AM | 9/7/2018 | | | | |
| Villalobos, David | | Replace burnt bulb in freezer SNP Mgr. Susana H. (575) 882-6724 | | | | replaced bulbs | | | |
| Dino Facio | | | | | | | | | |
| 205389 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:52 AM | | | | | |
| Facio, Dino | | Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 201999 | C-Wing | Portables | | | 9/10/2018 | | 129 | | \$0.00 |
| Medium | Work In Progress | | | 9/10/2018 3:20:11 PM | | | | | |
| Gonzalez, Salvador | | Wood planks on Computer portable ramp damaged and need to be replaced with metal plating. Thank you. | | | | | | | |
| Jesus Avila | | | | | | | | | |
| 205340 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:13 AM | | | | | |
| Facio, Dino | | Yearly - Gadsden MS - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205030 | | Custodial | | | 10/30/2018 | | 79 | | \$0.00 |
| Medium | Work In Progress | | | 10/30/2018 2:00:35 PM | | | | | |
| Gonzalez, Salvador | | broken bars on gators shade please weld asap. Thank you #GM-0908 | | | | | | | |
| Martin Soria | | | | | | | | | |
| 202261 | | Custodial | | | 9/13/2018 | | 126 | | \$6.99 |
| Medium | Work In Progress | | | 9/13/2018 9:35:35 AM | | | | | |
| Soria, Martin | | Requesting a can of OFF. Thank you | | | | | | | |
| Martin Soria | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| 012 Work Orders in Progress (Fiscal Year) | | | | | | | | | | Total Costs |
|---|------------------|--|-------------|-----------------------|-------------------|---|-----------|-------------|--|-------------|
| Selected Date Range for Request Dates:7/1/2018 - 12/31/2018 Order By Location, Status | | | | | | | | | | |
| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | | |
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | | |
| Assigned To | | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | | |
| Location: Gadsden MS | | | | | | | | | | |
| 207430 | C-Wing | Office | | | 12/12/2018 | | 36 | | | \$0.00 |
| Medium | Work In Progress | Nursing | | 12/12/2018 3:31:51 PM | | | | | | |
| Briones, Enrique | | Will you please send Warehouse personnel to Nursing Department Office to deliver some equipment to various campuses, please see below: Narcotics Cabinet to DVE-(Sherri Althouse-RN) LLE-(Jeanette Buckhalter-RN) Chrome Base Stool to SRE-(Martha Banning-RN) STE-(Nancy Bergman-RN) Kik Step to DVE-(Sherri Althouse-RN) STMS-(Bertha Valenzuela-RN) and SRE-(Martha Banning-RN) all this equipment should by signed off by the Registered Nurse listed above. Your assistance in this matter will be greatly appreciated. Thank you, Priscilla | | | | | | | | |
| Priscilla Martinez | | | | | | | | | | |
| 202894 | | Classroom | | | 9/25/2018 | | 114 | | | \$0.00 |
| Medium | Work In Progress | RM#415/Kuehn | | 9/25/2018 2:57:46 PM | | | | | | |
| Marquez, Gerardo | | My classroom door is acting up again, like last year. You need to push/pull on it in order for it to lock. Please fix, thank you. | | | | | | | | |
| Hilda Adler | | | | | | | | | | |
| 198515 | | | | | 7/23/2018 | | 14 | 1 | | \$25.00 |
| Medium | Work In Progress | Main doors to | | 7/23/2018 3:31:23 PM | | 8/6/2018 | | | | |
| Marquez, Gerardo | | Change setting on locking mechanism from 7 sec to 5 sec. (for new security camera & doorbell on main door) | | | | met w/ Plan B Tech Adrian to change setting | | | | |
| Hilda Adler | | | | | | | | | | |
| 207410 | C-Wing | Portables | | | 12/12/2018 | | 36 | | | \$0.00 |
| Medium | Work In Progress | Athletic | | 12/12/2018 11:06:16 | | | | | | |
| Marquez, Gerardo | | Exit Device needs to be replaced on one of the doors. | | | | | | | | |
| Thank you | | | | | | | | | | |
| Terry Alvarado | | | | | | | | | | |
| 207553 | | Library | | | 12/14/2018 | | 34 | | | \$14.08 |
| Medium | Work In Progress | Library doors | | 12/14/2018 11:19:58 | | | | | | |
| Marquez, Gerardo | | Library doors need permanent door holder openers. | | | | | | | | |
| Hilda Adler | | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|---------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden MS | | | | | | | | | |
| 202662 | | Parking Lot | | | 9/20/2018 | | 119 | | \$0.00 |
| Medium | Work In Progress | Front Parking | | 9/20/2018 1:52:31 PM | | | | | |
| Ontiveros, Guadalupe | | | | | | | | | |
| Please remove old speed bump by the north fence in the staff parking lot. See Connie for any questions. Per Mrs. Quiñonez | | | | | | | | | |
| Hilda Adler | | | | | | | | | |
| 206264 | Cafeteria | Cafeteria | | | 11/16/2018 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | 11/16/2018 12:10:40 | | | | | |
| Ambriz, Jose | | | | | | | | | |
| water fountain broken and needs to be replaced inside eating area. leaks water and pvc line coming out from wall is broken. | | | | | | | | | |
| Jesus Avila | | | | | | | | | |
| 206774 | | Gym | | | 11/30/2018 | | 48 | | \$120.75 |
| Medium | Work In Progress | | | 11/30/2018 3:40:46 PM | | | | | |
| Ambriz, Jose | | | | | | | | | |
| Need to fix scotsman ice machine. | | | | | | | | | |
| Jose Ambriz | | | | | | | | | |
| 202869 | | | | | 9/25/2018 | | 114 | | \$0.00 |
| Medium | Work In Progress | | | 9/25/2018 8:41:30 AM | | | | | |
| Ontiveros, Joe | | | | | | | | | |
| G. Sandoval Construction, Inc. (575) 524-6878 | | | | | | | | | |
| Please mark 100 feet on the East side of the Crosswalk (In front of Gadsden Middle School) and 100 feet on the west side of the crosswalk (in front of Gadsden Middle School) on both sides of Washington Street. Area marked in white. If you have any questions please call Joey at 575-649-8963, | | | | | | | | | |
| Jessica Herrera | | | | | | | | | |
| 206265 | Annex | Classroom | | | 11/16/2018 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | 11/16/2018 12:16:20 | | | | | |
| Chavez, Santos | | | | | | | | | |
| (2) safety lights not working and need to be replaced. One is in classroom 409 and the other is directly in front of the same classroom in the hallway. Thank you. | | | | | | | | | |
| Jesus Avila | | | | | | | | | |
| 201041 | Main Building | Classroom | | | 8/27/2018 | | 143 | | \$0.00 |
| Medium | Work In Progress | | | 8/27/2018 11:38:35 AM | | | | | |
| Chavez, Santos | | | | | | | | | |
| Outlet box needs to be rewired to new location. Room 181 (nurses office), thank you. | | | | | | | | | |
| Jesus Avila | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-----------------------------|------------------|------------------|-----------|-----------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden MS | | | | | | | | | |
| 202663 | | Parking Lot | | | 9/20/2018 | | 119 | | \$17.24 |
| Medium | Work In Progress | Staff Parking | | 9/20/2018 2:11:04 PM | | | | | |
| Avila, Jesus | | Paint Fire Zone Lane & label "No Parking" "Fire Lane" | | | | | | | |
| | | As Per Mrs. Quiñonez | | | | | | | |
| Hilda Adler | | | | | | | | | |
| 207402 | C-Wing | Office | | | 12/12/2018 | | 36 | | \$0.00 |
| Medium | Work In Progress | Nursing | | 12/12/2018 9:00:57 AM | | | | | |
| Chavez, Santos | | Send Electrician to cover some exposed outlets, and also check on why some outlets are not working. | | | | | | | |
| | | Thank you, Priscilla | | | | | | | |
| Priscilla Martinez | | | | | | | | | |
| 207060 | | | | | 12/6/2018 | | 42 | | \$112.53 |
| Medium | Work In Progress | | | 12/6/2018 9:21:06 AM | | | | | |
| Chavez, Santos | | Relocate outlet in nurse's portable. | | | | | | | |
| Santos Chavez | | | | | | | | | |
| 202959 | Annex | Mechanical | | | 9/26/2018 | | 113 | | \$47.81 |
| Medium | Work In Progress | | | 9/26/2018 10:41:45 AM | | | | | |
| Avila, Jesus | | Requesting Anchors for school use. thank you | | | | | | | |
| Jesus Avila | | | | | | | | | |
| 205907 | | | | | 11/9/2018 | | 69 | | \$327.15 |
| Medium | Work In Progress | | | 11/9/2018 11:09:57 AM | | | | | |
| Avila, Jesus | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| Count: 23 Work Orders | | Avg. Age of WO's 74 | | Total for Gadsden MS | | | 2 | \$696.55 | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| Selected Date Range for Request Dates:7/1/2018 - 12/31/2018 Order By Location, Status | | | | | | | | | | Total Costs |
|---|------------------|---|-------------|-----------------------|-------------------|------------------------|-----------|-------------|---------|-------------|
| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | | |
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | | |
| Assigned To | | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | | |
| Location: GSAC - Alamo | | | | | | | | | | |
| 205908 | | | | | 11/9/2018 | | 6 | 1 | \$60.89 | |
| Medium | Work In Progress | | | 11/9/2018 11:10:55 AM | | 11/15/2018 | | | | |
| Rincon, Jesus | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | done | | | | |
| | | (order thru warehouse) | | | | | | | | |
| Albert Vallejo | | | | | | | | | | |
| 204930 | | | | | 10/29/2018 | | 80 | | \$0.00 | |
| Medium | Work In Progress | | | 10/29/2018 10:31:05 | | | | | | |
| Chavez, Santos | | We need electrical outlets are needed in workstations in room 112. Please send a technician to help us out. Thank you. | | | | | | | | |
| Susie Ramos Lara | | | | | | | | | | |
| 205891 | | | | | 11/9/2018 | | 69 | | \$0.00 | |
| Medium | Work In Progress | | | 11/9/2018 8:05:40 AM | | | | | | |
| Lara, Ralph | | Please send a technician to check the door in the first office that belongs to the coordinator. We can not open the door. Thank you | | | | | | | | |
| Susie Ramos Lara | | | | | | | | | | |
| Count: 3 Work Orders | | Avg. Age of WO's | | | 52 | Total for GSAC - Alamo | | 1 | \$60.89 | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-----------------------|------------------|--|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: La Union ES | | | | | | | | | |
| 205652 | | Restroom | | | 11/6/2018 | | 72 | | \$186.17 |
| Medium | Work In Progress | | | 11/6/2018 12:13:59 PM | | | | | |
| Castillo, Carlos | | in the boy's restroom there is only one light that works but the other will not turn on and also has a missing light cover. If you have any questions contact the head custodian. | | | | | | | |
| Basilio Santillano | | | | | | | | | |
| 199650 | | Classroom | | | 8/7/2018 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | 8/7/2018 12:55:08 PM | 10/16/2018 | | | | |
| Santillano, Basilio | | There is mildew build up in the bottom of the sink in room 206. It is the art room. | | | | I sprayed clorox on the mildew and cleaned it as much as possible. | | | |
| Basilio Santillano | | | | | | | | | |
| 205390 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:53 AM | | | | | |
| Facio, Dino | | Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205342 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:16 AM | | | | | |
| Facio, Dino | | Yearly - La Union ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 206182 | | | | | 11/15/2018 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | 11/15/2018 9:11:07 AM | | | | | |
| Ambriz, Juan | | Respectfully requesting to replace lose tile next to the cafeteria. If you have any questions contact the head custodian. | | | | | | | |
| Basilio Santillano | | | | | | | | | |
| 207394 | | Kitchen | | | 12/12/2018 | | 36 | | \$0.00 |
| High | Work In Progress | | | 12/12/2018 8:01:26 AM | | | | | |
| Villalobos, David | | Check oven making loud noise | | | | | | | |
| Dino Facio | | | | | | | | | |
| 205909 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2018 11:11:42 AM | | | | | |
| Ambriz, Juan | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|------------------------------|------------------|------------------|-----------|-----------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: La Union ES | | | | | | | | | |
| 207609 | | | | | 12/17/2018 | | 31 | | \$0.00 |
| Medium | Work In Progress | | | 12/17/2018 10:54:08 | | | | | |
| Carbajal, Jimmy | | As per Mr. Sanchez, he is respectfully requesting to put new floor tile. This would be the hallway located in front of the office east side of the building. We have many tiles that are lose, cracked and coming apart. If you have any questions contact Mr. Sanchez or the Head Custodian. | | | | | | | |
| Basilio Santillano | | | | | | | | | |
| 198045 | | | | | 7/12/2018 | | 189 | | \$0.00 |
| Medium | Work In Progress | | | 7/12/2018 8:03:06 AM | | | | | |
| Escobar, David | | requesting lift for La Union site. Caff area for Emergency light battery replacement | | | | | | | |
| David Escobar | | | | | | | | | |
| 202786 | | | | | 9/24/2018 | | 115 | | \$0.00 |
| Medium | Work In Progress | | | 9/24/2018 9:03:32 AM | | | | | |
| Lara, Ralph | | In the female restroom of the upper grade hallway, one of the latches came off the door to lock. The bolts to secure the latch are not to be found. If you have any questions contact the head custodian. | | | | | | | |
| Basilio Santillano | | | | | | | | | |
| Count: 10 Work Orders | | Avg. Age of WO's 79 | | Total for La Union ES | | | 0 | \$186.17 | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------------|------------------|---|-------------|-----------------------|------------------|--|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Loma Linda ES | | | | | | | | | |
| 203772 | | | | | 10/9/2018 | | 100 | | \$0.00 |
| Medium | Work In Progress | | | 10/9/2018 3:31:14 PM | | | | | |
| Carrasco, Danny | | Need to borrow scissor lift to service F,C,U'S in cafeteria. | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| 206343 | | | | | 11/26/2018 | | 52 | | \$0.00 |
| Medium | Work In Progress | | | 11/26/2018 10:42:54 | | | | | |
| Villalobos, Jose | | respectfully requesting a new 13" shower scrubber | | | | | | | |
| Guadalupe Parada | | | | | | | | | |
| 204155 | | | | | 10/16/2018 | | 93 | | \$0.00 |
| Medium | Work In Progress | | | 10/16/2018 11:15:24 | | | | | |
| Nunez, Arturo | | Need some poles installed in parking to separate, student drop off area, and parking lot area. | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| 200147 | | | | | 8/13/2018 | | 81 | 1 | \$287.14 |
| Medium | Work In Progress | | | 8/13/2018 2:59:21 PM | 11/2/2018 | | | | |
| Nunez, Arturo | | On Play Ground Climbing Equipment, Where The Safety Bolts Go Into The Holes On The Plastic Sing. They Are Cracking Creating A Sharp Point Around The Safety Bolt. | | | | 11/15/18 Asp Albert, send back to Art, he will finish work order. Checked equipment and front panel cracked, need company to replace, Recreation Creation. Can you get company to replace part Route to Art Nunez as per new assignment on 9/24/18 | | | |
| Jesus Rincon | | | | | | | | | |
| 202157 | | Kitchen | | | 9/12/2018 | | 127 | | \$0.00 |
| High | Work In Progress | | | 9/12/2018 8:20:29 AM | | | | | |
| Medina, Eric | | Check disposal not working properly SNP Mgr. Dolores R. (575) 882-6725 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 207657 | | | | | 12/18/2018 | | 30 | | \$0.00 |
| Medium | Work In Progress | | | 12/18/2018 10:00:16 | | | | | |
| Medina, Eric | | OVEN OUT, TOP FACING DISHWASHER. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 205339 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:12 AM | | | | | |
| Facio, Dino | | Yearly - Loma Linda ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Loma Linda ES | | | | | | | | | |
| 205391 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | | 11/4/2018 12:48:53 AM | | | | |
| Facio, Dino | | Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205911 | | | | | 11/9/2018 | | 69 | | \$525.82 |
| Medium | Work In Progress | | | | 11/9/2018 11:13:13 AM | | | | |
| Nunez, Arturo | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 207269 | | | | | 12/10/2018 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 12/10/2018 2:19:42 PM | | | | |
| Nunez, Arturo | | Replace exhaust fan motors on classrooms and restrooms. | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| 203769 | | | | | 10/9/2018 | | 100 | | \$155.53 |
| Medium | Work In Progress | | | | 10/9/2018 3:28:44 PM | | | | |
| Nunez, Arturo | | Need the following filters. 20x36x2 3 EA. 24x36x2 3 EA. 16x25x1 8 EA. 10 1/2x27x1 9 EA. 10x27x1 2 EA. 15x20x1 4 EA. 16x30x1 4 EA. | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| 201773 | Main Building | Classroom | | | 9/6/2018 | | 133 | | \$18.90 |
| Medium | Work In Progress | | | | 9/6/2018 1:21:38 PM | | | | |
| Chavez, Santos | | 9/5/2018. Need A Power Outlet Install To Plug In Water Heater In New Nurse's Office | | | | | | | |
| Jesus Rincon | | | | | | | | | |
| 199879 | | Kitchen | | | 8/9/2018 | | 161 | | \$308.46 |
| High | Work In Progress | | | | 8/9/2018 2:36:44 PM | | | | |
| Chavez, Santos | | Check door bell to back door not working SNP Mgr. Dolores R. (575) 882-6725 | | | | | | | |
| Dino Facio | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------------|------------------|---|-------------|-----------------------|--------------------------------|---------------------------------------|-----------|-------------|-------------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Loma Linda ES | | | | | | | | | |
| 202972 | | | | | 9/26/2018 | | 113 | | \$0.00 |
| Medium | Work In Progress | | | 9/26/2018 2:24:26 PM | | | | | |
| Ontiveros, Joe | | Need a 6 in. floor drain cover for girls restroom upper grades. | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| 205228 | | | | | 11/1/2018 | | 77 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2018 3:05:17 PM | | | | | |
| Ontiveros, Joe | | Main drain pipe on fire riser needs to be replaced. line is rusted and leaking. | | | | 11/8/18 Asp Albert, route to plumber. | | | |
| Arturo Nunez | | | | | | | | | |
| 202164 | Main Building | Office | | | 9/12/2018 | | 127 | | \$0.00 |
| Medium | Work In Progress | Nurse Office | | 9/12/2018 10:07:23 AM | | | | | |
| Marquez, Gerardo | | Need an entire set of keys for nurse assistant. | | | | | | | |
| Crystalee Heredia | | | | | | | | | |
| 202973 | Main Building | | | | 9/26/2018 | | 113 | | \$2,583.66 |
| Medium | Work In Progress | | | 9/26/2018 2:26:59 PM | | | | | |
| Ambriz, Jose | | Need assistance on checking A.C. units, and heater in portable #7. Will be used as a classroom. | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| Count: 17 Work Orders | | Avg. Age of WO's | | 92 | Total for Loma Linda ES | | | 1 | \$3,879.51 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Mesquite ES | | | | | | | | | |
| 207467 | | | | | 12/13/2018 | | 35 | | \$110.95 |
| Medium | Work In Progress | | | 12/13/2018 7:32:57 AM | | | | | |
| Ambriz, Jose | | nurses heat/cooling unit not working | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 204846 | Main Building | Cafeteria | | | 10/26/2018 | | 83 | | \$0.00 |
| Medium | Work In Progress | | | 10/26/2018 10:13:50 | | | | | |
| Chavez, Santos | | Cafeteria dining area-Noticed a couple of fixtures not working. Try to upgrade to LED lighting (retrofit). Please get with Albert about this. thanks. | | | | | | | |
| Jessica Herrera | | | | | | | | | |
| 206430 | | | | | 11/27/2018 | | 51 | | \$0.00 |
| Medium | Work In Progress | | | 11/27/2018 12:34:26 | | | | | |
| Chavez, Santos | | need to replace 2 hand dryers boys bathroom | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 206431 | | | | | 11/27/2018 | | 51 | | \$0.00 |
| Medium | Work In Progress | | | 11/27/2018 12:35:18 | | | | | |
| Chavez, Santos | | need to replace 2 light switches | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 205103 | | Kitchen | | | 10/31/2018 | | 78 | | \$0.00 |
| High | Work In Progress | | | 10/31/2018 7:56:26 AM | | | | | |
| Chavez, Santos | | Two of the ceiling lights are out in the kitchen area | | | | | | | |
| Dino Facio | | | | | | | | | |
| 206976 | | | | | 12/5/2018 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/5/2018 8:56:28 AM | | | | | |
| Chavez, Santos | | need to replace emergency light ballast in staff bathroom | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 205392 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:54 AM | | | | | |
| Facio, Dino | | Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205351 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:23 AM | | | | | |
| Facio, Dino | | Yearly - Mesquite ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Mesquite ES | | | | | | | | | |
| 200002 | | Kitchen | | | 8/10/2018 | | 160 | | \$0.00 |
| High | Work In Progress | | | 8/10/2018 2:39:55 PM | | | | | |
| Villalobos, David | | Assessment on dish machine (leak on cooper line) SNP | | | | | | | |
| | | Mgr. Elizabeth M. (575) 882-6729 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 203755 | | Kitchen | | | 10/9/2018 | | 100 | | \$0.00 |
| High | Work In Progress | | | 10/9/2018 2:35:54 PM | | | | | |
| Villalobos, David | | Check disposal leaking water when in use SNP Mgr. | | | | | | | |
| | | Santa N. (575) 882-6729 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 203756 | | Kitchen | | | 10/9/2018 | | 100 | | \$0.00 |
| High | Work In Progress | | | 10/9/2018 2:38:28 PM | | | | | |
| Villalobos, David | | Assessment on dish machine leaking water cant pin | | | | | | | |
| | | point location of leak SNP Mgr. Santa N. (575) 882-6729 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 203983 | | Kitchen | | | 10/12/2018 | | 97 | | \$49.55 |
| High | Work In Progress | | | 10/12/2018 8:07:22 AM | | | | | |
| Villalobos, David | | Install T and Valve on water line to access water for | | | | | | | |
| | | skillet SNP Mgr. Santa N. (575) 882-6729 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 202207 | | | | | 9/12/2018 | | 0 | 7 | \$691.75 |
| Medium | Work In Progress | | | 9/12/2018 3:19:43 PM | 9/12/2018 | | | | |
| Ramirez, Joe | | need to replace several lightbulbs | | | 9/12/18 | | | | |
| Joe Ramirez | | | | | | | | | |
| 201775 | | | | | 9/6/2018 | | 133 | | \$123.99 |
| Medium | Work In Progress | | | 9/6/2018 1:36:24 PM | | | | | |
| Ramirez, Joe | | need to replace submersible drainage pump | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 197975 | | | | | 7/11/2018 | | 190 | | \$0.00 |
| Medium | Work In Progress | | | 7/11/2018 9:10:07 AM | | | | | |
| Ramirez, Joe | | need to replace filters on hvac units | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 207605 | | | | | 12/17/2018 | | 31 | | \$17.50 |
| Medium | Work In Progress | | | 12/17/2018 10:31:32 | | | | | |
| Ramirez, Joe | | need to install counselor parking sign | | | | | | | |
| Joe Ramirez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| Selected Date Range for Request Dates:7/1/2018 - 12/31/2018 Order By Location, Status | | | | | | | | | | Total Costs |
|---|------------------|---|------------------|-------|-----------------------|-----------------------|-----------|-------------|------------|-------------|
| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | | |
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | | |
| Assigned To | | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | | |
| Location: Mesquite ES | | | | | | | | | | |
| 207653 | Main Building | Custodial | | | 12/18/2018 | | 30 | | \$0.00 | |
| Medium | Work In Progress | | | | 12/18/2018 9:06:04 AM | | | | | |
| Villalobos, Jose | | I need to fix two vacuum 00089 5/8/12 and the next is01178 07/11/11 | | | | | | | | |
| Marco Fattorini | | | | | | | | | | |
| Count: 17 Work Orders | | | Avg. Age of WO's | | 78 | Total for Mesquite ES | | | 7 \$993.74 | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: North Valley ES | | | | | | | | | |
| 202279 | | Kitchen | | | 9/13/2018 | | 126 | | \$0.00 |
| High | Work In Progress | | | | 9/13/2018 1:17:07 PM | | | | |
| Villalobos, David | | The reach refrigerator needs a new light bulb SNP gr. Sandra H. (575) 882-6730 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 206984 | | Kitchen | | | 12/5/2018 | | 43 | | \$0.00 |
| High | Work In Progress | | | | 12/5/2018 9:52:01 AM | | | | |
| , | | Assessment on dish machine | | | | | | | |
| Dino Facio | | | | | | | | | |
| 205350 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | | 11/4/2018 12:48:22 AM | | | | |
| Facio, Dino | | Yearly - North Valley ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205403 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | | 11/4/2018 12:49:03 AM | | | | |
| Facio, Dino | | Monthly - North Valley ES - Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 206708 | | | | | 11/29/2018 | | 49 | | \$0.00 |
| Medium | Work In Progress | parking lot | | | 11/29/2018 4:11:56 PM | | | | |
| Chavez, Santos | | 4 of the parking lot lights do not turn on | | | | | | | |
| Ruth Gomez | | | | | | | | | |
| 203931 | | | | | 10/11/2018 | | 98 | | \$0.00 |
| Medium | Work In Progress | | | | 10/11/2018 3:01:31 PM | | | | |
| Chavez, Santos | | Need emergency ballast replaced in rooms 1o6,105.104,208 Thank you | | | | | | | |
| Joaquin Romero | | | | | | | | | |
| 206170 | | | | | 11/15/2018 | | 63 | | \$6.90 |
| Medium | Work In Progress | | | | 11/15/2018 8:13:27 AM | | | | |
| Chavez, Santos | | Need an outlet installed for a projector . Fire marshal said its a fire hazard because a extension cord is being used to power up the projector. Thank you | | | | | | | |
| Joaquin Romero | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|----------------------------|-------|-----------------------|----------------------------------|-----------|-------------|-----------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: North Valley ES | | | | | | | | | |
| 206245 | | | | | 11/16/2018 | | 62 | | \$125.45 |
| Medium | Work In Progress | | | | 11/16/2018 7:56:21 AM | | | | |
| Appelzoller, Fred | | Please relocate the ice machine from the kitchen to the lounge where they have one that isn't working very well. Thank you. | | | | | | | |
| 207258 | | | | | 12/10/2018 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 12/10/2018 11:53:56 | | | | |
| Vallejo, Albert | | Repair geothermal leak | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 205913 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | | 11/9/2018 11:16:45 AM | | | | |
| Romero, Joaquin | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 206011 | | | | | 11/13/2018 | | 65 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2018 9:49:50 AM | | | | |
| Ontiveros, Guadalupe | | Broken water line on back flow need your assistance . Thank You | | | | | | | |
| Joaquin Romero | | | | | | | | | |
| Count: 11 Work Orders | | | Avg. Age of WO's 69 | | | Total for North Valley ES | | 0 | \$132.35 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|---|-------------------------|-----------|---|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Northern On-Track Pre-K (LM) | | | | | | | | | |
| 205020 | Cafeteria | Exterior | | | 10/30/2018 | | 79 | | \$0.00 |
| Medium | Work In Progress | | | | 10/30/2018 12:37:45 | | | | |
| Romero, Joaquin | | Please replace the ceiling tiles in the storage room so that the Social Work Clothing Bank can move in there. Thank you | | | | | | | |
| Viola Ramos | | | | | | | | | |
| 198801 | | | | | 7/30/2018 | | 171 | | \$7.58 |
| Medium | Work In Progress | | | | 7/30/2018 7:41:20 AM | | | | |
| Ambriz, Jose | | The hydronic water line is leaking in room 102 . Can someone go check it out Thank you | | | | | | | |
| Joaquin Romero | | | | | | | | | |
| 207779 | | | | | 12/20/2018 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | | 12/20/2018 11:19:29 | | | | |
| Marquez, Gerardo | | The hinges on the custodian closet door need to be realigned . The door not closing right . Thank you | | | | | | | |
| Joaquin Romero | | | | | | | | | |
| Count: 3 Work Orders | | | Avg. Age of WO's | 93 | Total for Northern On-Track Pre-K (LM) | | | 0 | \$7.58 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 207762 | | | | | 12/20/2018 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | 12/20/2018 7:48:38 AM | | | | | |
| Marquez, Gerardo | | AS PER ALBERT VALLEJO. NEED A GATE KEY FOR A. PRE-K. AND A MASTER KEY FOR CHAPARRAL HIGH SCH. TO BE ISSUED TO SANDOVAL CONST. | | | | | | | |
| Gerardo Marquez | | | | | | | | | |
| 206167 | | | | | 11/15/2018 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | 11/15/2018 7:55:32 AM | | | | | |
| Marquez, Gerardo | | PLEASE ORDER SCREWS, BOLTS, TAPS AND BITS FOR USE DISTRICT WIDE. | | | | | | | |
| Gerardo Marquez | | | | | | | | | |
| 205642 | | | | | 11/6/2018 | | 72 | | \$0.00 |
| Medium | Work In Progress | | | 11/6/2018 7:51:45 AM | | | | | |
| Ontiveros, Joe | | Needed some Channellock, Screw Drivers and Crescent Wrench for services truck. | | | | | | | |
| Joe Ontiveros | | | | | | | | | |
| 197694 | | | | | 7/3/2018 | | 198 | | \$0.00 |
| Medium | Work In Progress | | | 7/3/2018 10:44:25 AM | | | | | |
| Chavez, Santos | | Need to replace worn, damaged or missing hand tools | | | | | | | |
| Santos Chavez | | | | | | | | | |
| 205890 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2018 7:58:46 AM | | | | | |
| Castillo, Carlos | | Organize and clean veh#152 | | | | | | | |
| Carlos Castillo | | | | | | | | | |
| 207385 | | | | | 12/11/2018 | | 37 | | \$0.00 |
| Medium | Work In Progress | | | 12/11/2018 4:20:23 PM | | | | | |
| Ronquillo, Ruben | | order light meter for albert | | | | | | | |
| Ruben Ronquillo | | | | | | | | | |
| 205633 | | | | | 11/6/2018 | | 72 | | \$0.00 |
| Medium | Work In Progress | | | 11/6/2018 12:28:13 AM | | | | | |
| Flores, Pete | | Monthly - PPD Dist Backhoe 0526 - Full Service -SP - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205524 | | | | | 11/5/2018 | | 73 | | \$0.00 |
| Medium | Work In Progress | | | 11/5/2018 12:43:24 AM | | | | | |
| Flores, Pete | | Monthly - PPD Backhoe T-PPD-0520 Full Service -SP - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 1/17/2019 11:56:48 AM | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 205525 | | | | | 11/5/2018 | | 73 | | \$0.00 |
| Medium | Work In Progress | | | 11/5/2018 12:43:25 AM | | | | | |
| Flores, Pete | | Monthly - PPD-T-0525 PM (Excavator) - by SP - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205559 | | Exterior | | | 11/5/2018 | | 73 | | \$0.00 |
| Medium | Work In Progress | Lt. O. Garcia | | 11/5/2018 11:13:28 AM | | | | | |
| Flores, Pete | | For vehicle #186, Ford Expedition, issued to Lt. Orlando Garcia. Driver side window regulator needs to be replaced. Not working. | | | | | | | |
| Maria Carbajal | | | | | | | | | |
| 202074 | | | | | 9/11/2018 | | 128 | | \$0.00 |
| High | Work In Progress | | | 9/11/2018 1:01:10 PM | | | | | |
| Flores, Pete | | SNP Freightliner #53 needs DEF fluid and reverse lightbulb replacements SNP WH Spvr. Antonio C. (575) 882-6927 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 203657 | | | | | 10/8/2018 | | 101 | | \$0.00 |
| Medium | Work In Progress | | | 10/8/2018 10:22:18 AM | | | | | |
| Flores, Pete | | PLEASE CHECK FRONT TIRES ON MAIL VEHICLE # 81 | | | | | | | |
| Enrique Briones | | | | | | | | | |
| 205588 | | | | | 11/5/2018 | | 73 | | \$0.00 |
| Medium | Work In Progress | | | 11/5/2018 2:58:33 PM | | | | | |
| Flores, Pete | | requesting lug nut wrenches for maintenance vehicles | | | | | | | |
| Pete Flores | | | | | | | | | |
| 205590 | | | | | 11/5/2018 | | 73 | | \$0.00 |
| Medium | Work In Progress | | | 11/5/2018 3:02:34 PM | | | | | |
| Flores, Pete | | jacks needed for maintenance trucks. no jacks available for changing flat tires | | | | | | | |
| Pete Flores | | | | | | | | | |
| 206966 | | | | | 12/5/2018 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/5/2018 7:50:27 AM | | | | | |
| Flores, Pete | | PETE, NEED TO HAVE INVERTER INSTALLED IN LOCKSMITH VAN # 17. THANKS. | | | | | | | |
| Gerardo Marquez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 206967 | | | | | 12/5/2018 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 12/5/2018 7:56:08 AM | | | | |
| Flores, Pete | | PETE, NEED TO HAVE A PARTICIAN GAURD INSTALLED IN VAN # 17. THIS IS THE PARTICIAN THAT PROTECTS THE DRIVERS AREA FROM THE WORK AREA. THANKS. | | | | | | | |
| Gerardo Marquez | | | | | | | | | |
| 207469 | | | | | 12/13/2018 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 12/13/2018 7:52:39 AM | | | | |
| Flores, Pete | | Veh.#152 needs service | | | | | | | |
| Carlos Castillo | | | | | | | | | |
| 206330 | | | | | 11/26/2018 | | 52 | | \$0.00 |
| Medium | Work In Progress | veh.#47 | | | 11/26/2018 8:08:12 AM | | | | |
| Flores, Pete | | service engine oil light is on | | | | | | | |
| Maria Ruiz | | | | | | | | | |
| 206267 | | | | | 11/16/2018 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | | 11/16/2018 12:50:11 | | | | |
| Flores, Pete | | Please affix chrome emblems back onto the Suburban. AVECHS personnel will deliver the Suburban to the lot today to be parked during the Thanksgiving Break. | | | | | | | |
| Melanie Beegle | | | | | | | | | |
| 206001 | | | | | 11/13/2018 | | 65 | | \$0.00 |
| Medium | Work In Progress | Vehicle #41 | | | 11/13/2018 7:46:27 AM | | | | |
| Flores, Pete | | needs oil change | | | | | | | |
| Maria Ruiz | | | | | | | | | |
| 205162 | | | | | 10/31/2018 | | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 10/31/2018 3:50:43 PM | | | | |
| Flores, Pete | | Need to have Vehicle #31. serviced for winter, radiator needs to be flushed water is all rusty. | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| 206420 | Main Warehouse | | | | 11/27/2018 | | 51 | | \$0.00 |
| Medium | Work In Progress | | | | 11/27/2018 11:06:01 | | | | |
| Carrasco, Danny | | REQUESTING NEW DOLLEY FOR WAREHOUSE USE. | | | | | | | |
| Danny Carrasco | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| Selected Date Range for Request Dates:7/1/2018 - 12/31/2018 Order By Location, Status | | | | | | | | | | Total Costs |
|---|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|--------|-------------|
| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | | |
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | | |
| Assigned To | | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | | |
| 207567 | | | | | 12/14/2018 | | 34 | | \$0.00 | |
| Medium | Work In Progress | | | | 12/14/2018 3:07:57 PM | | | | | |
| Flores, Pete | | Need two quarts of ATF for vehicle 31 | | | | | | | | |
| Arturo Nunez | | | | | | | | | | |
| 206555 | | | | | 11/28/2018 | | 50 | | \$0.00 | |
| High | Work In Progress | | | | 11/28/2018 9:38:12 AM | | | | | |
| Flores, Pete | | Need full service maintenance on SNP vehicle#63 | | | | | | | | |
| Dino Facio | | | | | | | | | | |
| 206588 | | | | | 11/28/2018 | | 50 | | \$0.00 | |
| Medium | Work In Progress | Vehicle #10 | | | 11/28/2018 3:26:08 PM | | | | | |
| Flores, Pete | | sliding door are hard to open and close both sides | | | | | | | | |
| Maria Ruiz | | | | | | | | | | |
| 206627 | | | | | 11/29/2018 | | 49 | | \$0.00 | |
| High | Work In Progress | | | | 11/29/2018 8:08:25 AM | | | | | |
| Flores, Pete | | Replace wipers on SNP Van#67 | | | | | | | | |
| Dino Facio | | | | | | | | | | |
| 206660 | | | | | 11/29/2018 | | 49 | | \$0.00 | |
| High | Work In Progress | | | | 11/29/2018 12:28:30 | | | | | |
| Flores, Pete | | SNP Freightliner#78 airbrake system leaking | | | | | | | | |
| Dino Facio | | | | | | | | | | |
| 206816 | | | | | 12/3/2018 | | 45 | | \$0.00 | |
| Medium | Work In Progress | Vehicle #27 | | | 12/3/2018 9:07:07 AM | | | | | |
| Flores, Pete | | crack on windshield | | | | | | | | |
| Maria Ruiz | | | | | | | | | | |
| 206817 | | | | | 12/3/2018 | | 45 | | \$0.00 | |
| Medium | Work In Progress | veh.#15 | | | 12/3/2018 9:09:20 AM | | | | | |
| Flores, Pete | | back door & handle dent on the on Lt side | | | | | | | | |
| Maria Ruiz | | | | | | | | | | |
| 207775 | | Parking Lot | | | 12/20/2018 | | 28 | | \$0.00 | |
| Medium | Work In Progress | | | | 12/20/2018 10:26:18 | | | | | |
| Flores, Pete | | Please service vehicle # 118 . Needs oil change. | | | | | | | | |
| THANKS | | | | | | | | | | |
| Larry Martinez | | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 203505 | | | | | 10/2/2018 | | 107 | | \$0.00 |
| High | Work In Progress | | | 10/2/2018 3:42:10 PM | | | | | |
| Tobias, Victor | | need to replace batteries | | | | | | | |
| Pete Flores | | | | | | | | | |
| 202876 | | | | | 9/25/2018 | | 114 | | \$15.98 |
| Medium | Work In Progress | | | 9/25/2018 10:32:33 AM | | | | | |
| Carrasco, Danny | | requesting spray nozzles for shop use | | | | | | | |
| Pete Flores | | | | | | | | | |
| 207571 | | | | | 12/14/2018 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | 12/14/2018 3:29:48 PM | | | | | |
| Briones, Enrique | | please pick printer; HP Laser Jet Pro400 M401n; not working | | | | | | | |
| Mary Sitters | | | | | | | | | |
| 198865 | Main Warehouse | Storage | | | 7/30/2018 | | 171 | | \$0.00 |
| Medium | Work In Progress | | | 7/30/2018 12:19:37 PM | | | | | |
| Gonzalez, Salvador | | remove wood planks on HVAC barrack steps and replace with metal plate, thank you. | | | | | | | |
| Jesus Avila | | | | | | | | | |
| 200003 | | | | | 8/10/2018 | | 160 | | \$0.00 |
| Medium | Work In Progress | | | 8/10/2018 2:44:40 PM | | | | | |
| Gonzalez, Salvador | | PPD/GMS wastewater effluent water weir need to be rebuilt out of stainless steel | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 200405 | | | | | 8/16/2018 | | 154 | | \$71.84 |
| Medium | Work In Progress | | | 8/16/2018 11:40:32 AM | | | | | |
| Apodaca, Mario | | button batteries for water booster pump control box district-wide use. | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 207821 | | | | | 12/31/2018 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | 12/31/2018 1:46:36 AM | | | | | |
| Apodaca, Mario | | Monthly - PPD/GHS - WW Monthly Sampling - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207354 | | | | | 12/11/2018 | | 37 | | \$0.00 |
| Medium | Work In Progress | | | 12/11/2018 3:18:03 PM | | | | | |
| Ortiz, Alfredo | | Need to Order Orange Cream and Disposable gloves for district wide use. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Physical Plant Complex

| | | | | | |
|-----------------------|------------------|----|----------------------------------|---|---------|
| Count: 38 Work Orders | Avg. Age of WO's | 71 | Total for Physical Plant Complex | 0 | \$87.82 |
|-----------------------|------------------|----|----------------------------------|---|---------|

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Riverside ES | | | | | | | | | |
| 207208 | | | | | 12/10/2018 | 12/26/2018 | 38 | | \$0.00 |
| Medium | Work In Progress | | | 12/10/2018 12:54:02 | | | | | |
| Hernandez, Javier | | Monthly - Riverside ES Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207764 | Main Building | Hallway/Corridor | | | 12/20/2018 | | 28 | | \$100.64 |
| Medium | Work In Progress | | | 12/20/2018 8:08:32 AM | | | | | |
| Hernandez, Javier | | replacing emergency exit lights | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 206985 | | Kitchen | | | 12/5/2018 | | 43 | | \$0.00 |
| High | Work In Progress | | | 12/5/2018 9:53:39 AM | | | | | |
| Villalobos, David | | Assessment on dish machine | | | | | | | |
| Dino Facio | | | | | | | | | |
| 202677 | | | | | 9/20/2018 | | 119 | | \$151.97 |
| Medium | Work In Progress | | | 9/20/2018 3:33:30 PM | | | | | |
| Carrasco, Danny | | requesting a saw saw and a grease gun | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 205347 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:20 AM | | | | | |
| Facio, Dino | | Yearly - Riverside ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205424 | | | | | 11/4/2018 | 11/10/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:49:20 AM | | | | | |
| Hernandez, Javier | | Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207097 | Main Building | Parking Lot | | | 12/6/2018 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2018 3:25:30 PM | | | | | |
| Hernandez, Javier | | need red paint for no parking zone curbs | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 205549 | | | | | 11/5/2018 | | 73 | | \$0.00 |
| Medium | Work In Progress | | | 11/5/2018 9:58:23 AM | | | | | |
| Hernandez, Javier | | needing 440 voltage detector item# 447115, model # 59110 | | | | | | | |
| Javier Hernandez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Riverside ES | | | | | | | | | |
| 204928 | | | | | 10/29/2018 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | | 10/29/2018 9:59:49 AM | | | | |
| Hernandez, Javier | | 100 ft utilitech extension cord item #59610 model# utp511735, fluke digital 600 volt voltage detector item #806177 model# 15-600 | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 203934 | | | | | 10/11/2018 | | 98 | | \$0.00 |
| Medium | Work In Progress | | | | 10/11/2018 3:26:17 PM | | | | |
| Hernandez, Javier | | need silicone gun to seal some leaks we have in window sills | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 204375 | Main Building | Office | | | 10/18/2018 | | 91 | | \$0.00 |
| Medium | Work In Progress | | | | 10/18/2018 3:58:54 PM | | | | |
| Hernandez, Javier | | flexible silicone weatherstrip part #DW34 | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 204302 | | | | | 10/18/2018 | | 91 | | \$0.00 |
| Medium | Work In Progress | | | | 10/18/2018 9:18:49 AM | | | | |
| Hernandez, Javier | | in need of a channel locks set, to utilize on repairing sprinkler system | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 207543 | New Wing 1/02 | Classroom | | | 12/14/2018 | | 34 | | \$99.00 |
| Medium | Work In Progress | | | | 12/14/2018 10:12:44 | | | | |
| Hernandez, Javier | | need 6 ballasts for the long 4 fluorescent light bulbs | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 207613 | Main Building | Exterior | | | 12/17/2018 | | 31 | | \$15.12 |
| Medium | Work In Progress | | | | 12/17/2018 2:42:45 PM | | | | |
| Hernandez, Javier | | need three forest green spray paint to cover up graffiti under canopy | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 206024 | Main Building | Cafeteria | | | 11/13/2018 | | 65 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2018 12:26:45 | | | | |
| Lara, Ralph | | doors are not shutting correctly from entrance or exit to or from cafeteria | | | | | | | |
| Javier Hernandez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-------|-----------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Riverside ES | | | | | | | | | |
| 204317 | | | | | 10/18/2018 | | 91 | | \$0.00 |
| Medium | Work In Progress | Tractor is at | | | 10/18/2018 11:25:37 | | | | |
| Flores, Pete | | The tractor T-RS-0532 needs to replace thee Tractor Seat Upholstery and Repair | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 204584 | | | | | 10/23/2018 | | 86 | | \$0.00 |
| Medium | Work In Progress | | | | 10/23/2018 2:37:12 PM | | | | |
| Flores, Pete | | borrowed john deere tractor #T-RS 0532 from sunland park elementary not working properly need checked please | | | | Unit was just checked by Victor on 10/17/18 see wo 203913 | | | |
| Javier Hernandez | | | | | | | | | |
| 206026 | | | | | 11/13/2018 | | 65 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2018 1:25:22 PM | | | | |
| Hernandez, Javier | | Please level sand and add concrete by the parent center. Will be installing a 10'ft x14' ft storage shed by the portable. (Mrs. Martine) | | | | | | | |
| Norma Martinez | | | | | | | | | |
| 205916 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | | 11/9/2018 11:19:14 AM | | | | |
| Hernandez, Javier | | ADACConcerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 207096 | Main Building | Parking Lot | | | 12/6/2018 | | 42 | | \$187.85 |
| Medium | Work In Progress | | | | 12/6/2018 3:23:48 PM | | | | |
| Hernandez, Javier | | parking lot no parking curbs need to be repainted red | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 205803 | New Wing 1/02 | Exterior | | | 11/8/2018 | | 70 | | \$8.16 |
| Medium | Work In Progress | | | | 11/8/2018 8:25:24 AM | | | | |
| Hernandez, Javier | | blower not functioning testing it | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 205825 | | | | | 11/8/2018 | | 70 | | \$0.00 |
| Medium | Work In Progress | Parent Center | | | 11/8/2018 12:35:11 PM | | | | |
| Hernandez, Javier | | Install TV in parent center. TV and mount are located in Mrs. Navarro's office. (Mrs. Martinez) | | | | | | | |
| Norma Martinez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Riverside ES | | | | | | | | | |
| 205826 | Main Building | Classroom | | | 11/8/2018 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | 11/8/2018 12:37:17 PM | | | | | |
| Hernandez, Javier | | need entry door-kick down stop,item #63770 mod# S837-617 | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 205725 | | | | | 11/7/2018 | | 71 | | \$0.00 |
| Medium | Work In Progress | | | 11/7/2018 11:11:28 AM | | | | | |
| Hernandez, Javier | | Install bird/pitchen traps around school. (Mr. Damian) | | | | | | | |
| Norma Martinez | | | | | | | | | |
| 205726 | | | | | 11/7/2018 | | 71 | | \$0.00 |
| Medium | Work In Progress | | | 11/7/2018 11:12:17 AM | | | | | |
| Hernandez, Javier | | replace ceiling tiles on main hallway by 2nd grade hallway. (Mr. Damian) | | | | | | | |
| Norma Martinez | | | | | | | | | |
| 205443 | | | | | 11/4/2018 | 11/12/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:49:40 AM | | | | | |
| Hernandez, Javier | | Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205454 | | | | | 11/4/2018 | 11/12/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:49:49 AM | | | | | |
| Hernandez, Javier | | Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 202197 | | | | | 9/12/2018 | | 127 | | \$0.00 |
| Medium | Work In Progress | | | 9/12/2018 2:28:06 PM | | | | | |
| Hernandez, Javier | | need Leatherman, 11 in 1 screw driver and air compressor | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 203814 | | | | | 10/10/2018 | | 99 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2018 8:53:15 AM | | | | | |
| Hernandez, Javier | | remove and clean up all weeds behind the school. (Mrs. Martinez) | | | | | | | |
| Norma Martinez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Riverside ES | | | | | | | | | |
| 203815 | | | | | 10/10/2018 | | 99 | | \$0.00 |
| Medium | Work In Progress | | | | 10/10/2018 8:53:59 AM | | | | |
| Hernandez, Javier | | Remove and clean up all weeds in front of the school. (Mrs. Martinez) | | | | | | | |
| Norma Martinez | | | | | | | | | |
| 203816 | | | | | 10/10/2018 | | 99 | | \$0.00 |
| Medium | Work In Progress | | | | 10/10/2018 8:55:57 AM | | | | |
| Hernandez, Javier | | Relocated all benches located under the canopy in the upper grades playground to the upper grades patio area by the trees. (Mrs. Martinez) | | | | | | | |
| Norma Martinez | | | | | | | | | |
| 203752 | | Classroom | | | 10/9/2018 | | 100 | | \$0.00 |
| Medium | Work In Progress | | | | 10/9/2018 1:31:48 PM | | | | |
| Hernandez, Javier | | need a few desks from san Miguel storage | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 202504 | Main Building | | | | 9/18/2018 | | 121 | | \$720.84 |
| Medium | Work In Progress | | | | 9/18/2018 10:51:42 AM | | | | |
| Hernandez, Javier | | 16x25x1=4pcs 14x25x1 item #hc-00370=4pcs 20x20x1-hc-00400=8pcs 20x22x1-hc-00403=32 16x20x1-hc-00377=4 16x25x2-hc-00382=112 20x20x2-hc-00408=24 20x25x2-hc-00406=32 20x30x2=12 | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 201588 | | | | | 9/4/2018 | | 135 | | \$59.94 |
| Medium | Work In Progress | 1st grade | | | 9/4/2018 11:46:56 AM | | | | |
| Hernandez, Javier | | Please paint to remove all the student hands and painting in the 1st grade hallway. (Mrs. Navarro) | | | | | | | |
| Norma Martinez | | | | | | | | | |
| 207086 | New Wing 1/02 | Restroom (Girls) | | | 12/6/2018 | | 42 | | \$180.00 |
| Medium | Work In Progress | | | | 12/6/2018 1:29:58 PM | | | | |
| Pacheco, Hector | | water faucet in girls restroom stuck on on tried cleaning it and addinf lubricunt but too worn, need to be replaced | | | | | | | |
| Javier Hernandez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|-------------------------------|-----------------------|------------------|-----------|-------------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Riverside ES | | | | | | | | | |
| 206996 | New Wing 1/02 | Restroom (Girls) | | | 12/5/2018 | | 43 | | \$6.49 |
| Medium | Work In Progress | | | | 12/5/2018 11:40:32 AM | | | | |
| Pacheco, Hector | | girls toilet keeps running | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 205169 | | | | | 10/31/2018 | | 78 | | \$0.00 |
| Medium | Work In Progress | Room 141 | | | 10/31/2018 4:02:23 PM | | | | |
| Lara, Ralph | | Unable to lock or unlock the classroom door. Please check cylinder> Mr. De Santiago | | | | | | | |
| Norma Martinez | | | | | | | | | |
| 202895 | Main Building | Athletic Field | | | 9/25/2018 | | 114 | | \$0.00 |
| Medium | Work In Progress | | | | 9/25/2018 2:59:37 PM | | | | |
| Ontiveros, Guadalupe | | area in sand box needs wood chips black cloth tearing apart tripping hazard | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 202897 | Main Building | Athletic Field | | | 9/25/2018 | | 114 | | \$0.00 |
| Medium | Work In Progress | | | | 9/25/2018 3:03:16 PM | | | | |
| Ontiveros, Guadalupe | | benches requested by principal Navarro to be relocated from playground area to grass area next to north side building | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| 207206 | | | | | 12/9/2018 | | 39 | | \$0.00 |
| Medium | Work In Progress | | | | 12/9/2018 12:59:50 AM | | | | |
| Hernandez, Javier | | Monthly - Riverside ES - Split System Filters - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207006 | New Wing 1/02 | Hallway/Corridor | | | 12/5/2018 | | 43 | | \$429.00 |
| Medium | Work In Progress | | | | 12/5/2018 1:49:44 PM | | | | |
| Hernandez, Guillermo | | water fountain in third grade hallway not working no water comes out | | | | | | | |
| Javier Hernandez | | | | | | | | | |
| Count: 41 Work Orders | | Avg. Age of WO's 75 | | Total for Riverside ES | | | 0 | \$1,959.01 | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------------|------------------|--|-------------|-----------------------|---------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: RTC - Alliance | | | | | | | | | |
| 201381 | | | | | 8/31/2018 | | 139 | | \$0.00 |
| Medium | Work In Progress | | | 8/31/2018 11:42:26 AM | | | | | |
| Gonzalez, Salvador | | We have placed several work orders on our ramps. Mr. Ortiz replaced the ones that were broken in front of the office. Unfortunately you have patched and patched our ramps. I believe we need aluminum. Mr. Rapanut and Superintendant Demsey visited our campus and noted we do need them. Thank you for attending to this concern, | | | | | | | |
| Gloria Delgado | | | | | | | | | |
| 200752 | | | | | 8/22/2018 | | 148 | | \$0.00 |
| Medium | Work In Progress | | | 8/22/2018 9:39:58 AM | | | | | |
| Gonzalez, Salvador | | The decomposed wooden staircase and ramp is corroded and needs to be replaced with a metal staircase and ramp in portable A | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 207713 | | | | | 12/19/2018 | | 29 | | \$0.00 |
| Medium | Work In Progress | | | 12/19/2018 10:54:18 | | | | | |
| Gonzalez, Salvador | | Can you please send your welder at the beginning of the year to see our rod iron safety windows. They always stay open the latches do not work. | | | | | | | |
| Gloria Delgado | | | | | | | | | |
| Count: 3 Work Orders | | Avg. Age of WO's | | 105 | Total for RTC - Alliance | | | 0 | \$0.00 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa ES | | | | | | | | | |
| 207275 | Main Building | Parking Lot | | | 12/10/2018 | | 38 | | \$105.40 |
| Medium | Work In Progress | | | 12/10/2018 3:12:09 PM | | | | | |
| Gonzalez, Salvador | | As per Mr. Smith need to weld chain in front to stop traffic flow (student and staff safety) | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 205343 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:17 AM | | | | | |
| Facio, Dino | | Yearly - Santa Teresa ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205394 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:55 AM | | | | | |
| Facio, Dino | | Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207767 | | | | | 12/20/2018 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | 12/20/2018 8:43:21 AM | | | | | |
| Villalobos, David | | OVENS NEED TO BE RE POSITIONED. THANK YOU. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 207768 | | | | | 12/20/2018 | | 28 | | \$12.95 |
| Medium | Work In Progress | | | 12/20/2018 8:44:41 AM | | | | | |
| Villalobos, David | | LEFT SIDE OF STAND (COLD SIDE) IS NOT WORKING. THANK YOU. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 204640 | | | | | 10/24/2018 | | 85 | | \$0.00 |
| Medium | Work In Progress | | | 10/24/2018 8:05:14 AM | | | | | |
| Ambriz, Juan | | need to order filters for establishing stock | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 204949 | | | | | 10/29/2018 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/29/2018 2:46:15 PM | | | | | |
| Ambriz, Juan | | Need to order filters to stablsh stock | | | | | | | |
| Juan Ambriz | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|----------------------------------|------------------|------------------|-----------|-------------|-----------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa ES | | | | | | | | | |
| 205910 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2018 11:12:26 AM | | | | | |
| Ambriz, Juan | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 207704 | Main Building | Computer Lab | | | 12/19/2018 | | 29 | | \$0.00 |
| Medium | Work In Progress | | | 12/19/2018 7:59:51 AM | | | | | |
| Ambriz, Juan | | Need to strap all headphone cables | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 205198 | Main Building | Office | | | 11/1/2018 | | 77 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2018 10:58:31 AM | | | | | |
| Carbajal, Jimmy | | Need carpet repair in main office has a small runner in carpet | | | | | | | |
| Maria Gabaldon | | | | | | | | | |
| 201977 | Main Building | Classroom | | | 9/10/2018 | | 129 | | \$0.00 |
| Medium | Work In Progress | | | 9/10/2018 10:51:34 AM | | | | | |
| Vallejo, Albert | | WE HAD A WATER LEAK IN A CLASSROOM. SOME OF THE CABINETS AND DRAWERS GOT SOAKED WITH WATER. NEED TO EVALUATE TO SEE IF IT NEEDS REPLACING. THANKS | | | | | | | |
| Rudy Ramos | | | | | | | | | |
| Count: 11 Work Orders | | Avg. Age of WO's 65 | | Total for Santa Teresa ES | | | | 0 | \$118.35 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 205917 | | | | | 11/9/2018 | | 69 | | \$619.26 |
| Medium | Work In Progress | | | | 11/9/2018 11:23:08 AM | | | | |
| Hernandez, Carlos | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 205926 | | | | | 11/9/2018 | | 69 | | \$345.04 |
| Medium | Work In Progress | | | | 11/9/2018 11:32:07 AM | | | | |
| Hernandez, Carlos | | Fields - Install Wheelchair Signs on all ADA spaces on bleachers. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 207403 | | | | | 12/12/2018 | | 36 | | \$0.00 |
| Medium | Work In Progress | #900 | | | 12/12/2018 9:07:02 AM | | | | |
| Flores, Pete | | Athletic Gator 900 - needs to be serviced | | | | | | | |
| Pete Flores | | | | | | | | | |
| 205105 | | | | | 10/31/2018 | | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 10/31/2018 8:26:26 AM | | | | |
| Vallejo, Albert | | Connect plumbing for booster pump. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 206962 | | Exterior | | | 12/5/2018 | | 43 | | \$0.00 |
| Medium | Work In Progress | Various Areas | | | 12/5/2018 7:02:45 AM | | | | |
| Ontiveros, Guadalupe | | Please provide Mr. Bustamante tractor, equipment and support to move dirt, add base course of gravel throughout campus. Grading and other work needed prior to start of spring field maintenance. Please see Mrs. Soriano and Mr. Wohlgemuth for details. | | | | | | | |
| Nicholas Wohlgemuth | | | | | | | | | |
| 207250 | | Athletic Field | | | 12/10/2018 | | 38 | | \$0.00 |
| Medium | Work In Progress | softball | | | 12/10/2018 10:29:27 | | | | |
| Ontiveros, Guadalupe | | Need completion of fence strips, infield dirt, backstop padding, movement of fence door see Bryan Chavez for further direction | | | | | | | |
| Lorraine Dominguez | | | | | | | | | |
| 205406 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | | 11/4/2018 12:49:05 AM | | | | |
| Flores, Pete | | Monthly - Santa Teresa HS- UV-STHS-0518 PM Service - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-----------------------|------------------|-------------------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 206163 | | | | | 11/15/2018 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | 11/15/2018 12:42:30 | | | | | |
| Flores, Pete | | Yearly - Santa Teresa HS - Mower 0425 - Grounds - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207825 | | | | | 12/31/2018 | | 17 | | \$0.00 |
| Medium | Work In Progress | | | 12/31/2018 1:46:38 AM | | | | | |
| Flores, Pete | | Monthly - District Tractors - Full Service PM - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 206672 | | | | | 11/29/2018 | | 49 | | \$503.72 |
| Medium | Work In Progress | | | 11/29/2018 3:03:41 PM | | | | | |
| Hernandez, Guillermo | | 200 hallway not cooling all classrooms getting to hot | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 206840 | | | | | 12/3/2018 | | 45 | | \$92.00 |
| Medium | Work In Progress | | | 12/3/2018 2:31:54 PM | | | | | |
| Hernandez, Guillermo | | need to replace belimo valves to air handler library and temp gauge. | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 207565 | | | | | 12/14/2018 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | 12/14/2018 2:19:12 PM | | | | | |
| Castillo, Carlos | | need to replace capacitors to basket ball backboards having trouble going up | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 202803 | | | | | 9/24/2018 | | 115 | | \$283.10 |
| Medium | Work In Progress | Entrance | | 9/24/2018 1:03:57 PM | | | | | |
| Hernandez, Carlos | | Stain the wooden planters along main entrance walkway. Need adequate amount of stain and rollers/brushes to complete project. | | | | waiting for stain was ordered | | | |
| Nicholas Wohlgemuth | | | | | | | | | |
| 207780 | Main Building | Classroom | | | 12/20/2018 | | 28 | | \$0.00 |
| Medium | Work In Progress | C-3 | | 12/20/2018 11:31:24 | | | | | |
| Lara, Ralph | | Need to create lock for door to store computer equipment | | | | | | | |
| Lorraine Dominguez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 207654 | Main Building | Classroom | | | 12/18/2018 | | 30 | | \$0.00 |
| Medium | Work In Progress | 801 | | 12/18/2018 9:38:58 AM | | | | | |
| Lara, Ralph | | Key lock is not working it is difficult to open | | | | | | | |
| Lorraine Dominguez | | | | | | | | | |
| 205209 | | | | | 11/1/2018 | | 77 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2018 11:43:55 AM | | | | | |
| Castillo, Carlos | | Please change lamps in fixtures in culinary area as needed. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 205284 | | | | | 11/2/2018 | | 76 | | \$0.00 |
| Medium | Work In Progress | | | 11/2/2018 10:53:15 AM | | | | | |
| Castillo, Carlos | | ballast in culinary need to be replaced | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 206184 | | | | | 11/15/2018 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | 11/15/2018 9:16:06 AM | | | | | |
| Castillo, Carlos | | several lights need replacing in parking lot and walkway to gym area getting to dark | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 206185 | | | | | 11/15/2018 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | 11/15/2018 9:17:08 AM | | | | | |
| Castillo, Carlos | | light fixture needs replacement in nurses office storage | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 197853 | | | | | 7/10/2018 | | 191 | | \$0.00 |
| Medium | Work In Progress | | | 7/10/2018 6:50:44 AM | | | | | |
| Vallejo, Albert | | Install rip-rap to stop erosion of east bleachers at football field | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 205336 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:10 AM | | | | | |
| Vallejo, Albert | | Monthly - Santa Teresa HS Fire Suppress Culinary - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207157 | | | | | 12/7/2018 | | 41 | | \$0.00 |
| Medium | Work In Progress | | | 12/7/2018 12:35:11 PM | | | | | |
| Villalobos, Jose | | the machine to wash the floors outside is not working well does not have much pressure. #1012151668 tank you. | | | | | | | |
| Juan Hernandez | | | | | | | | | |
| 1/17/2019 11:56:48 AM | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|---|-------------|-----------------------|----------------------------------|------------------|-----------|-------------|-------------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa HS | | | | | | | | | |
| 203843 | | | | | 10/10/2018 | | 99 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2018 2:11:21 PM | | | | | |
| Lara, Ralph | | Please fix ADA button coming in from North side of Band Room into Hallway. Picture has been sent to Margret via e-mail of button. Should you have any questions please see Mr. Gallegos in the Construction Office. Thank You | | | | | | | |
| 204132 | | Exterior | | | 10/15/2018 | | 94 | | \$0.00 |
| Medium | Work In Progress | Main Entrance | | 10/15/2018 6:51:28 PM | | | | | |
| Lara, Ralph | | Please ensure correct operation of automatic door opener on main doors by Library. Also requesting PPD evaluate an opener is needed on the second set of doors in the same area. (exiting vestibule and entering hallway) | | | | | | | |
| Nicholas Wohlgemuth | | | | | | | | | |
| 205930 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2018 11:36:38 AM | | | | | |
| Lara, Ralph | | Trades West Restroom - Install stall doors. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 205931 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2018 11:38:01 AM | | | | | |
| Lara, Ralph | | Bandroom Storage - Install double doors. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 205932 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2018 11:41:07 AM | | | | | |
| Lara, Ralph | | Bandroom Storage Doors - Install district lockset. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 205395 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:56 AM | | | | | |
| Facio, Dino | | Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205345 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:19 AM | | | | | |
| Facio, Dino | | Yearly - Santa Teresa HS - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 29 Work Orders | | Avg. Age of WO's | | 66 | Total for Santa Teresa HS | | | 0 | \$1,843.12 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-----------------------|------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa MS | | | | | | | | | |
| 205396 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:56 AM | | | | | |
| Facio, Dino | | Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205360 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:30 AM | | | | | |
| Facio, Dino | | Yearly - Santa Teresa MS - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207053 | | Kitchen | | | 12/6/2018 | | 42 | | \$0.00 |
| High | Work In Progress | | | 12/6/2018 7:29:13 AM | | | | | |
| Villalobos, David | | Ice machine leaking water from the bottom | | | | | | | |
| Dino Facio | | | | | | | | | |
| 204064 | | Kitchen | | | 10/15/2018 | | 94 | | \$0.00 |
| High | Work In Progress | | | 10/15/2018 8:13:26 AM | | | | | |
| Villalobos, David | | Assessment on warmer (electrical issues) SNP Mgr. Gessica B. (575) 882-6746 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 206192 | | Athletic Field | | | 11/15/2018 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | 11/15/2018 1:00:03 PM | | | | | |
| Villalobos, Jose | | 11/15/18. please service chain saw and replace or sharpen chain. | | | | | | | |
| Julio Alvarado | | | | | | | | | |
| 206834 | North Building | Classroom | | | 12/3/2018 | | 45 | | \$0.00 |
| Medium | Work In Progress | 35-B | | 12/3/2018 12:14:26 PM | | | | | |
| Lara, Ralph | | CHANGE LOCK SO THAT TEACHERS ARE ABLE TO UNLOCK COMPUTER LAB WITH CLASSROOM KEYS | | | | | | | |
| Laura Parra | | | | | | | | | |
| 201311 | | | | | 8/30/2018 | | 140 | | \$0.00 |
| Medium | Work In Progress | | | 8/30/2018 2:09:35 PM | | | | | |
| Ontiveros, Guadalupe | | Please remove dirt that has accumulated against the fence closest to the road. For questions please seem Ms. Lovelace at STMS or talk Mr. Gallegos in the construction office. Thank You | | | | Asp report 10/30/18, pending fence raised, ck w/Ms.Lovelace | | | |
| Dominique Esparza | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| Selected Date Range for Request Dates:7/1/2018 - 12/31/2018 Order By Location, Status | | | | | | | | | | Total Costs |
|---|------------------|---|-------------|-----------------------|-------------------|------------------|-----------|-------------|------------|-------------|
| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | | |
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | | |
| Assigned To | | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | | |
| Location: Santa Teresa MS | | | | | | | | | | |
| 207534 | | | | | 12/14/2018 | | 34 | | \$1,612.80 | |
| Medium | Work In Progress | | | 12/14/2018 7:51:13 AM | | | | | | |
| Hernandez, Guillermo | | Need to replace broken CO 2 sensors having problems with the economizer/fresh air vent. Also, T-stats/sensors. | | | | | | | | |
| Guillermo Hernandez | | | | | | | | | | |
| 207810 | | | | | 12/31/2018 | | 17 | | \$0.00 | |
| Medium | Work In Progress | | | 12/31/2018 1:46:24 AM | | | | | | |
| Soriano, David | | Yearly - Santa Teresa MS H6(Roof Furnace)(Yearly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | | |
| 203222 | | | | | 9/30/2018 | 10/16/2018 | 109 | | \$0.00 | |
| Medium | Work In Progress | | | 9/30/2018 2:10:42 AM | | | | | | |
| Soriano, David | | Monthly - Santa Teresa MS A1(Wall Refr.E/H)(Semi) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | | |
| 206162 | | | | | 11/15/2018 | | 63 | | \$0.00 | |
| Medium | Work In Progress | | | 11/15/2018 12:42:29 | | | | | | |
| Flores, Pete | | Yearly - Santa Teresa MS - Mower 0416 - Grounds - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | | |
| 205479 | | | | | 11/4/2018 | 12/5/2018 | 74 | | \$0.00 | |
| Medium | Work In Progress | | | 11/4/2018 12:50:11 AM | | | | | | |
| Soriano, David | | Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | | |
| 205918 | | | | | 11/9/2018 | | 69 | | \$417.30 | |
| Medium | Work In Progress | | | 11/9/2018 11:24:00 AM | | | | | | |
| Soriano, David | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | | |
| (order thru warehouse) | | | | | | | | | | |
| Albert Vallejo | | | | | | | | | | |
| 204858 | | | | | 10/26/2018 | | 83 | | \$165.00 | |
| Medium | Work In Progress | | | 10/26/2018 1:12:59 PM | | | | | | |
| Soriano, David | | 10/26/2018 Change ballasts in classrooms and hallways | | | | | | | | |
| David Soriano | | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|----------------------------------|------------------|---|-----------|-------------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa MS | | | | | | | | | |
| 203340 | | | | | 9/30/2018 | 10/8/2018 | 25 | 3 | \$240.00 |
| Medium | Work In Progress | | | 9/30/2018 2:12:53 AM | 10/25/2018 | | | | |
| Soriano, David | | Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details. | | | | done 10/29/18 Sent work order back, until batteries are received | | | |
| Margret Villalobos | | | | | | | | | |
| 204959 | South Building | Hallway/Corridor | | | 10/29/2018 | | 80 | | \$69.39 |
| Medium | Work In Progress | | | 10/29/2018 3:05:18 PM | | | | | |
| Soriano, David | | Replace 3 exit signs that are no longer working | | | | | | | |
| David Soriano | | | | | | | | | |
| 205033 | | Kitchen | | | 10/30/2018 | | 79 | | \$143.96 |
| High | Work In Progress | | | 10/30/2018 2:50:58 PM | | | | | |
| Soriano, David | | Need double doors next to chemical room painted front and back | | | | | | | |
| Dino Facio | | | | | | | | | |
| Count: 17 Work Orders | | Avg. Age of WO's 69 | | Total for Santa Teresa MS | | | 3 | \$2,648.45 | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|--|-------------|-----------|------------------------------|--|-----------|-------------|-----------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: SNP Complex | | | | | | | | | |
| 207058 | | | | | 12/6/2018 | | 42 | 1 | \$25.00 |
| High | Work In Progress | | | | 12/6/2018 8:39:27 AM | | | | |
| Facio, Dino | | Need entire SNP Complex outdoor lighting to functioning properly. all lights must work due to recent vandalism that occurred on site | | | | 12/14/18 reroute, need for site mechanic to replace light bulbs and contact me if needed - C. Castillo | | | |
| Dino Facio | | | | | | | | | |
| 205919 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | | 11/9/2018 11:24:53 AM | | | | |
| Diaz, David | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 201857 | | | | | 9/7/2018 | | 132 | | \$0.00 |
| High | Work In Progress | | | | 9/7/2018 10:02:22 AM | | | | |
| Lara, Ralph | | Need Keyless Door Locks installed to main building back door and door to lounge in main training room SNP Dir. Maria G. (575) 882-6773 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 204578 | | | | | 10/23/2018 | | 86 | | \$495.96 |
| High | Work In Progress | | | | 10/23/2018 2:01:25 PM | | | | |
| Diaz, David | | Checking and replacing filters for all units (heating/cooling) | | | | | | | |
| Dino Facio | | | | | | | | | |
| 202280 | | Storage | | | 9/13/2018 | | 126 | | \$0.00 |
| High | Work In Progress | | | | 9/13/2018 1:22:21 PM | | | | |
| Gonzalez, Salvador | | Need ramp to storage redone with metal plating SNP Dir. Maria G. (575) 882-6773 | | | | | | | |
| Dino Facio | | | | | | | | | |
| Count: 5 Work Orders | | Avg. Age of WO's | | 91 | Total for SNP Complex | | | 1 | \$520.96 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Sunland Park ES | | | | | | | | | |
| 205397 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:57 AM | | | | | |
| Facio, Dino | | Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205349 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:21 AM | | | | | |
| Facio, Dino | | Yearly - Sunland Park ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 202953 | | Kitchen | | | 9/26/2018 | | 113 | | \$0.00 |
| High | Work In Progress | | | 9/26/2018 8:56:45 AM | | | | | |
| Lara, Ralph | | Back door to kitchen still not closing properly SNP Mgr. Ignacia C. (575) 882-6734 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 207062 | | | | | 12/6/2018 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2018 9:27:38 AM | | | | | |
| Saucedo, Luis | | as per Ms, Romero need to replace all baseboards inside the offices | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 205527 | | | | | 11/5/2018 | | 73 | | \$0.00 |
| Medium | Work In Progress | | | 11/5/2018 7:08:59 AM | | | | | |
| Saucedo, Luis | | need to sandblaster portables, then Bondo, primer, and paint it, | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 204053 | | | | | 10/15/2018 | | 25 | 7 | \$600.59 |
| Medium | Work In Progress | | | 10/15/2018 7:21:12 AM | 11/9/2018 | | | | |
| Saucedo, Luis | | need to replace all air filters for the heating system start -up | | | | DONE | | | |
| Luis Saucedo | | | | | | | | | |
| 205300 | | | | | 11/2/2018 | | 76 | | \$0.00 |
| Medium | Work In Progress | | | 11/2/2018 3:35:33 PM | | | | | |
| Carrasco, Danny | | please I need to barrow the sandblaster machine | | | | | | | |
| Luis Saucedo | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Sunland Park ES | | | | | | | | | |
| 206408 | | | | | 11/27/2018 | | 51 | | \$288.50 |
| Medium | Work In Progress | | | 11/27/2018 7:50:07 AM | | | | | |
| Castillo, Carlos | | Need to relocate power supply for H/C unit at white portable # 54. | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 207227 | | | | | 12/10/2018 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | 12/10/2018 7:23:03 AM | | | | | |
| Castillo, Carlos | | please I need electrician to run 120vl cable on compt lab, to installed exit sign (Current cable is too short) | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 207465 | | | | | 12/13/2018 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | 12/13/2018 7:21:56 AM | | | | | |
| Castillo, Carlos | | I need to barrow the slab scissor lift to reach the support poles and paint | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 207414 | | | | | 12/12/2018 | | 36 | | \$0.00 |
| Medium | Work In Progress | | | 12/12/2018 11:54:26 | | | | | |
| Saucedo, Luis | | as per Romero paint blue the support poles inside the building | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 204456 | | | | | 10/21/2018 | | 17 | 2.5 | \$233.58 |
| Medium | Work In Progress | | | 10/21/2018 12:47:49 | 11/7/2018 | | | | |
| Saucedo, Luis | | Monthly - Sunland Park ES - Split System Filters - Refer to PM schedule details. | | | | done | | | |
| Margret Villalobos | | | | | | | | | |
| 204843 | | | | | 10/26/2018 | | 83 | | \$73.56 |
| Medium | Work In Progress | | | 10/26/2018 10:09:52 | | | | | |
| Pacheco, Hector | | Please relocate the ice machine from the kitchen to the lounge. If not feasible, please speak to Principal Barraza about alternate location. Thank you | | | | | | | |
| Jessica Herrera | | | | | | | | | |
| 206990 | | | | | 12/5/2018 | | 43 | | \$284.08 |
| Medium | Work In Progress | | | 12/5/2018 10:49:20 AM | | | | | |
| Pacheco, Hector | | please the drain is clogged (in the back of custodian office) where the water pump is | | | | | | | |
| Carlos Montes | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|-----------------------------|-------------|-------------------|----------------------------------|------------------|-----------|-------------|-------------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Location: | | Sunland Park ES | | | | | | | |
| 206995 | | Custodial | | | 12/5/2018 | | 43 | | \$64.77 |
| Medium | Work In Progress | | | | 12/5/2018 11:37:32 AM | | | | |
| Pacheco, Hector | | needs 3 toilet seat please. | | | | | | | |
| Carlos Montes | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Count: 15 Work Orders | | Avg. Age of WO's | | 55 | Total for Sunland Park ES | | | 9.5 | \$1,545.08 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Sunrise ES | | | | | | | | | |
| 204923 | | | | | 10/29/2018 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/29/2018 8:40:38 AM | | | | | |
| Tellez, Hector | | 5 fixtures out in SRE hallways. Need 5 two lamp ballast | | | | | | | |
| Hector Tellez | | | | | | | | | |
| 205195 | | | | | 11/1/2018 | | 77 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2018 10:20:06 AM | | | | | |
| Tellez, Hector | | There are two outside electrical poles with their luminaries or bulbs not functioning in the parking lot. One is located in main parking lot facing the portable entrance, and the other one is located outside in the kitchen workers parking space facing dumpsters alongside bus parking. All other light poles are lit except these two at 4:30 a.m. Thank you. | | | | | | | |
| Felipe Gallegos | | | | | | | | | |
| 202578 | | | | | 9/19/2018 | | 120 | | \$8.75 |
| Medium | Work In Progress | | | 9/19/2018 9:04:28 AM | | | | | |
| Tellez, Hector | | Need blanks for deadfront on electrical panel in 100 wing 4 blanks (GE) | | | | | | | |
| Hector Tellez | | | | | | | | | |
| 206789 | | | | | 12/2/2018 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2018 1:30:49 AM | | | | | |
| Tellez, Hector | | Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 206790 | | | | | 12/2/2018 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2018 1:30:50 AM | | | | | |
| Tellez, Hector | | Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205921 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2018 11:26:33 AM | | | | | |
| Tellez, Hector | | ADACConcerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Sunrise ES | | | | | | | | | |
| 205269 | | | | | 11/2/2018 | | 76 | | \$145.00 |
| Medium | Work In Progress | | | 11/2/2018 6:50:18 AM | | | | | |
| Tellez, Hector | | Please replace old worn out cotton rope to flag pole in front of main entrance to admin building. Thank you. | | | | | | | |
| Felipe Gallegos | | | | | | | | | |
| 202294 | | | | | 9/13/2018 | | 126 | | \$495.70 |
| Medium | Work In Progress | | | 9/13/2018 3:10:40 PM | | | | | |
| Tellez, Hector | | need paint for library | | | | | | | |
| Hector Tellez | | | | | | | | | |
| 204668 | | | | | 10/24/2018 | | 85 | | \$0.00 |
| Medium | Work In Progress | | | 10/24/2018 12:32:18 | | | | | |
| Vallejo, Albert | | Procure new Marquee | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 201753 | | | | | 9/6/2018 | | 133 | | \$0.00 |
| Medium | Work In Progress | | | 9/6/2018 9:49:31 AM | | | | | |
| Lara, Ralph | | Wooden door to staff restroom next to workroom in LUNA hallway drags on floor. Please repair. Thank you. | | | | | | | |
| Felipe Gallegos | | | | | | | | | |
| 205398 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:57 AM | | | | | |
| Facio, Dino | | Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205357 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:28 AM | | | | | |
| Facio, Dino | | Yearly - Sunrise ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 198130 | | | | | 7/16/2018 | | 185 | | \$0.00 |
| Medium | Work In Progress | | | 7/16/2018 12:03:29 PM | | | | | |
| Gonzalez, Salvador | | need to weld another rack for ladder and a 12 X 7 inches steel plate for pipe rack 3, 2 inch pieces if pipe for bender hangers a nd a metal hook for cords | | | | | | | |
| Hector Tellez | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| Selected Date Range for Request Dates:7/1/2018 - 12/31/2018 Order By Location, Status | | | | | | | | | Total Costs |
|---|------------------|---|------------------|-------|---------------------|----------------------|-----------|-------------|-------------|
| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | |
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Sunrise ES | | | | | | | |
| 207257 | Main Building | | | | 12/10/2018 | | 38 | | \$37.26 |
| Medium | Work In Progress | | | | 12/10/2018 11:49:21 | | | | |
| Tellez, Hector | | Please replace broken round plexi-glass to fire extinguisher in lobby area right outside cafeteria door. Thank you. | | | | | | | |
| Felipe Gallegos | | | | | | | | | |
| Count: 14 Work Orders | | | Avg. Age of WO's | | 88 | Total for Sunrise ES | | 0 | \$686.71 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------------|------------------|--|-------------|-----------|-----------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Support Services | | | | | | | | | |
| 205712 | | Portables | | | 11/7/2018 | | 71 | | \$0.00 |
| Medium | Work In Progress | | | | 11/7/2018 8:31:12 AM | | | | |
| Gonzalez, Salvador | | Requesting a small frame to be built around new AC unit installed in nurses portable, thank you. | | | | | | | |
| Jesus Avila | | | | | | | | | |
| 205922 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | | 11/9/2018 11:27:24 AM | | | | |
| Avila, Jesus | | ADAConcerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 206739 | | | | | 11/30/2018 | | 48 | | \$9.98 |
| Medium | Work In Progress | Maria's Office | | | 11/30/2018 9:44:03 AM | | | | |
| Avila, Jesus | | Please paint and repair wall and ceiling, where new cooling/heating unit is. | | | | | | | |
| Cynthia Maes | | | | | | | | | |
| 204220 | | | | | 10/17/2018 | | 92 | | \$0.00 |
| Medium | Work In Progress | | | | 10/17/2018 8:07:50 AM | | | | |
| Marquez, Gerardo | | Need name plate made, please see me first. | | | | | | | |
| Maria Ruiz | | | | | | | | | |
| Count: 4 Work Orders | | Avg. Age of WO's | | 70 | Total for Support Services | | | 0 | \$9.98 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------|------------------|---|-------------|-----------------------|------------------|--|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Vado ES | | | | | | | | | |
| 207550 | | | | | 12/14/2018 | | 20 | 0.5 | \$12.50 |
| Medium | Work In Progress | | | 12/14/2018 10:54:13 | 1/3/2019 | | | | |
| Ambriz, Jose | | need to ck. unit in room 201 will not reset only cold air coming out | | | | ck unit in Tracer, no alarm indicated, working fine. | | | |
| Danny Miranda | | | | | | | | | |
| 200486 | Main Building | Classroom | | | 8/17/2018 | | 153 | | \$0.00 |
| Medium | Work In Progress | | | 8/17/2018 9:42:37 AM | | | | | |
| Ambriz, Jose | | A C WATER LEAK ROOM 311 ! | | | | | | | |
| Armando Diaz | | | | | | | | | |
| 198859 | | | | | 7/30/2018 | | 171 | | \$0.00 |
| Medium | Work In Progress | | | 7/30/2018 11:15:55 AM | | | | | |
| Chavez, Santos | | need to ck. emer. lights in front lobby | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 203484 | | | | | 10/2/2018 | | 107 | | \$206.70 |
| Medium | Work In Progress | | | 10/2/2018 1:36:25 PM | | | | | |
| Miranda, Danny | | need to replace light bulbs in 100-wing back entrance | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 205923 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2018 11:28:14 AM | | | | | |
| Miranda, Danny | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 203476 | | | | | 10/2/2018 | | 0 | 4.5 | \$492.30 |
| Medium | Work In Progress | | | 10/2/2018 8:11:08 AM | 10/2/2018 | | | | |
| Miranda, Danny | | need to change air filters | | | | 10/2/18 | | | |
| Danny Miranda | | | | | | | | | |
| 205352 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:24 AM | | | | | |
| Facio, Dino | | Yearly - Vado ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-----------------------|--------------------------|------------------|-----------|-------------|-----------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Vado ES | | | | | | | | | |
| 205399 | | | | | 11/4/2018 | 11/25/2018 | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:48:58 AM | | | | | |
| Facio, Dino | | Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 205019 | | Kitchen | | | 10/30/2018 | | 79 | | \$0.00 |
| High | Work In Progress | | | 10/30/2018 12:33:41 | | | | | |
| Medina, Eric | | Disconnect and transfer ice machine to SP Elem. Lounge | | | | | | | |
| Dino Facio | | | | | | | | | |
| 206340 | | | | | 11/26/2018 | | 52 | | \$0.00 |
| Medium | Work In Progress | | | 11/26/2018 10:32:14 | | | | | |
| Carrasco, Danny | | need mini blinds for library 26 1/4" x 46" | | | | | | | |
| Danny Miranda | | | | | | | | | |
| Count: 10 Work Orders | | Avg. Age of WO's | | 80 | Total for Vado ES | | | 5 | \$711.50 |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Yucca Heights ES | | | | | | | | | |
| 206107 | | | | | 11/14/2018 | | 64 | | \$0.00 |
| Medium | Work In Progress | | | 11/14/2018 1:29:52 PM | | | | | |
| Medina, Eric | | I need to submit a work order for the dishwasher the inside rack continues to fall off. | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 207095 | | Lift Station | | | 12/6/2018 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2018 3:23:36 PM | | | | | |
| Apodaca, Mario | | Yucca H.E wastewater plant need to order chain link fence slats | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 205901 | | | | | 11/9/2018 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2018 11:05:06 AM | | | | | |
| Vargas, Juan | | ADA Concerns - Install interior pull on all ADA Stalls and install knee guard covers on exposed pipes underneath sinks. | | | | | | | |
| | | (order thru warehouse) | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 206463 | | | | | 11/27/2018 | | 51 | | \$0.00 |
| High | Work In Progress | | | 11/27/2018 2:34:26 PM | | | | | |
| Vargas, Juan | | Missing filter in room 113A, must complete within 7 days. | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 206482 | | | | | 11/27/2018 | | 51 | | \$0.00 |
| High | Work In Progress | | | 11/27/2018 3:30:05 PM | | | | | |
| Vargas, Juan | | Be sure that FDC is properly mark, must complete within 7 days. | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 207092 | | Custodial | | | 12/6/2018 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2018 2:29:39 PM | | | | | |
| Vargas, Juan | | there is a hole about 2" wide at the bottom of the wall where it meets the floor between rooms 318 and 320 | | | | | | | |
| Ernesto Diaz | | | | | | | | | |
| 205408 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2018 12:49:06 AM | | | | | |
| Facio, Dino | | Monthly - Yucca Heights ES - Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|----------------------|------------------|--|--|--|-----------------------|--|-----|--|----------|
| Location: | | Yucca Heights ES | | | | | | | |
| 205361 | | | | | 11/4/2018 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | | 11/4/2018 12:48:31 AM | | | | |
| Facio, Dino | | Yearly - Yucca Heights ES - Grease Trap - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 207012 | | Lift Station | | | 12/5/2018 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 12/5/2018 2:59:37 PM | | | | |
| Ontiveros, Guadalupe | | Attention to Grounds, Need accumulated dirt removed around the wastewater gravel filter and pumps. | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 202788 | | Kitchen | | | 9/24/2018 | | 115 | | \$0.00 |
| High | Work In Progress | | | | 9/24/2018 9:39:09 AM | | | | |
| Ontiveros, Joe | | Water is coming out green/yellow in the kitchen area sinks SNP Mgr. Arlene M. (575) 882-6748 | | | | | | | |
| Dino Facio | | | | | | | | | |
| 201030 | | | | | 8/27/2018 | | 143 | | \$0.00 |
| Medium | Work In Progress | | | | 8/27/2018 9:29:48 AM | | | | |
| Tellez, Hector | | in front area outside need fix two wall lights is blinking | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 201577 | | | | | 9/4/2018 | | 135 | | \$372.50 |
| Medium | Work In Progress | | | | 9/4/2018 9:51:08 AM | | | | |
| Tellez, Hector | | two lights at the front of the building of Y.H.E. are not working properly | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 206257 | | | | | 11/16/2018 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | | 11/16/2018 10:33:06 | | | | |
| Tellez, Hector | | need install new outlet in main office for printer machine | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 206900 | | Office | | | 12/4/2018 | | 44 | | \$0.00 |
| Medium | Work In Progress | Office | | | 12/4/2018 10:47:30 AM | | | | |
| Tellez, Hector | | Office- Need an outlet to connect the office printer | | | | | | | |
| Rocio Rodriguez | | | | | | | | | |
| 206112 | | | | | 11/14/2018 | | 64 | | \$0.00 |
| Medium | Work In Progress | | | | 11/14/2018 2:41:15 PM | | | | |
| Ambriz, Jose | | in rooms 173 and 113 need return air grille 31x32 and 8 /12x 8 | | | | | | | |
| Juan Vargas | | | | | | | | | |

512 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2018 - 12/31/2018 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|-------------------------|---|-------------|-------------------|-----------------------------------|------------------|-----------|-------------|--------------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | | Description | | | | | | | |
| Requester Name | | | | | | | | | |
| <hr/> | | | | | | | | | |
| Location: | Yucca Heights ES | | | | | | | | |
| 204850 | | | | | 10/26/2018 | | 83 | | \$0.00 |
| Medium | Work In Progress | | | | 10/26/2018 11:09:13 | | | | |
| Ambriz, Jose | | need check ERV UNITE IN B PENHOUSE NOT ON | | | | | | | |
| Juan Vargas | | | | | | | | | |
| 201783 | | Office | | | 9/6/2018 | | 133 | | \$0.00 |
| Medium | Work In Progress | | | | 9/6/2018 2:21:45 PM | | | | |
| Marquez, Gerardo | | Office- Door handle by receptionist is loose | | | | | | | |
| Rocio Rodriguez | | | | | | | | | |
| 203911 | | | | | 10/11/2018 | | 98 | | \$0.00 |
| Medium | Work In Progress | | | | 10/11/2018 9:49:19 AM | | | | |
| Marquez, Gerardo | | in front doors the handi cap button not working | | | | | | | |
| Juan Vargas | | | | | | | | | |
| Count: 18 Work Orders | | Avg. Age of WO's | | 77 | Total for Yucca Heights ES | | | 0 | \$372.50 |
| Count: 512 Work Orders | | Avg. Age of WO's | | 74 | Grand Total | | | 77.5 | \$27,970.25 |