

**PHYSICAL PLANT SPECIAL PROJECTS/REQUESTS**  
(Revised 7/12/2023)

<b>Site</b>	<b>WO#</b>	<b>Interior/Exterior</b>	<b>Description</b>	<b>Estimated</b>
AVEC	260161	Exterior	Paint and texturize all ramps	8/15/2023
DV	276774	Interior	Need to replace faulty valves, rusted water shutoff and gauges in boiler room.	Complete
DV	278949	Exterior	Relocate portable from Sunland Park to Desert View Elementary.	7/30/2023
GAC	278166	Exterior	Replacement of playground equipment 1.	8/15/2023
GE	278168	Exterior	Replacement of playground equipment (two total)	8/15/2023
GE	280361	Exterior	New Basketball Courts	Complete
GHS	267150	Exterior	Need to replace failing pump head to fire pump	7/25/2023
GHS	231178	Interior	Old Main Paint classrooms and hallways.	7/25/2023
LM PRE-K	261905	Interior	Floor tiles in Rm 114 (daycare) are lifting.	Complete
LM PRE-K	278167	Exterior	Replacement of playground equipment.	6/15/2023
LM PRE-K	280022	Interior	Paint classroom and Hallway	8/30/2023
LM PRE-K	281916	Interior	Replace VCT flooring in Social Services office and repair hallway	7/20/2023
NV	275995	Exterior	Removal and installation of new playgrounds 1 & 2.	9/15/2023
PPD	277307	Interior	Need to remove and replace the two windows facing west of the building.	Complete
PPD	278195	Exterior	PPD warehouse metal awning above main roll up deliver doors	7/30/2023
RE	275605	Exterior	Install front block wall and chain link fence.	8/1/2023
RE	275607	Exterior	Rockwall repair and privacy gates	Complete
RE	277677	Exterior	The rock walls along the walkway towards the school entrance need to be maintained and replaster with concrete.	Complete
RE	279391	Interior	Patch walls, paint and replace flooring in double portable P#1 & P#2	Complete
RE	279736	Interior	Portable 3 renovations - paint walls and remove carpet and replace with linoleum part of	7/30/2023
RS	251717	Interior	Patch and paint classrooms and paint all Pre K wing classroom and hallway	7/25/2023
RS,SP,AE,BE	278784	Exterior	Pune all palm trees at RS, SP, AE and BE	7/30/2023
SNP	278946	Exterior	Need to install chain link fence at SNP on the open area.	Complete
VE	258856	Interior	The laminate on the counter top in front office is peeling off and laminate is in a bad shape.	Complete
VE	278951	Exterior	Relocate portable from RTC to Vado Elementary.	8/1/2023