

PHYSICAL PLANT SPECIAL PROJECTS/REQUESTS
(Revised 11/28/2023)

Site	WO#	Interior/Exterior	Description	Estimated
AE	285247	Interior	Need to replace relays and connect the inside lighting controls to Trane	12/22/2023
AE	287040	Exterior	Painting all exterior walls	12/22/2023
AE	287041	Exterior	Sidewalk repairs	12/23/2023
AE	287041	Interior	Exterior sidewalk repair	12/22/2023
AE Alamo	287835	Exterior	Installation of Chain Link Fence and gate	12/22/2023
AE-PreK	288459	Exterior	Need to order primary screen to level the ground to be used for parking.	12/22/2023
BE	288700	Exterior	PSFA Need to install walking pads on the roof.	1/25/2024
CHHS	289302		Water heater replacement	1/25/2024
CHS	285948	Exterior	Need to repair the fence and replace the gate (Ms. Lopez)	12/22/2023
CHM	288536		Electrical Panels replacement for HVAC units	1/25/2024
DP	288466	Exterior	Fire Sprinkler Repairs.	12/22/2023
DT	287864	Interior	Need to check water heater in kitchen.	Complete
DV	287790	Exterior	Post Emergent Herbicide Application	12/8/2023
DV,RS,SP	286686	Exterior	Installation of Knox boxes for the south schools	Complete
GAC	278166	Exterior	Replacement of playground equipment 1.	Complete
GAC	285526	Interior	Removal of suppression system	1/25/2024
GE	278168	Exterior	Replacement of playground equipment (two total)	2/10/2024
GHS	287204	Exterior	Demo existing concrete sidewalks	12/22/2023
GHS	287377	Exterior	Need to repair fire hydrant.	Complete
GM	287836	Exterior	Repair of 8" backflow	Complete
LL	282919	Interior	There is tile lifting from the boys restrooms by the bus lobby.	Complete
LL	285621	Exterior	Mr. Cardona is requesting for the entire school, windows and doors to be mirror tinted.	Complete
LM PreK	278167	Exterior	Replacement of playground equipment.	2/10/2024
LU	285403	Interior	Remodeling boys restrooms in the upper grade hallway.	1/25/2024
LU	288900	Interior	Renovation of nurses office.	1/30/2024
ME	284349	Exterior	Replace chain link fence at Bus Drop Off	Complete
NV	288920	Exterior	Leveling the garss area	3/15/2024
NV	285914	Exterior	Small playground installation	3/20/2024
NV	285914	Interior	Install signs on playgrounds,	1/15/2024
PPD	285293	Exterior	Needs to repair leaking roof on welding/custodial equipment repair shop.	1/25/2024
RE	275605	Exterior	Install front block wall and chain link fence.	1/20/2024
SNP	280555	Exterior	Need section of sidewalk westside in front of main training room.	Complete
SR	283402	Exterior	Need to install gates to open areas at SR	12/22/2023
SR	288570	Exterior	Backflow is leaking and needs to be repaired.	12/5/2023
STE	288921	Exterior	Leveling the grass area	3/15/2024
STE	287524	Exterior	Need to check slides in the playground. (Replacing playground)	3/15/2024
STH	283247	Interior	Football shower heads need to be replaced	12/22/2023
STH	276608	Exterior	Tennis courts are cracked and in need of repair before an athlete gets injured.	2/25/2024
STM	287834	Interior	Toilet Partition Installation and Repairs	Complete
VE	278951	Exterior	Relocate portable from RTC to Vado Elementary.	1/25/2024