

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Alta Vista ECHS</b>									
289322					10/26/2023		83		\$489.00
Medium	Work In Progress	P22			10/26/2023 9:49:27 AM				
Tellez, Hector		The solar light on P22 is no longer working.							
Melanie Beegle									
291248					12/6/2023		42		\$0.00
Medium	Work In Progress	P1 & P10			12/6/2023 9:27:45 AM				
Ontiveros, Joe		There is no hot water in portables P1 & P10.							
Melanie Beegle									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>63</b>	<b>Total for Alta Vista ECHS</b>			<b>0</b>	<b>\$489.00</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony - On Track Pre-K (Village)</b>									
291124		Classroom			12/4/2023		44		\$0.00
Medium	Work In Progress	109			12/4/2023 2:26:31 PM				
Tellez, Hector	classroom needs more outlets. Please see teacher Ms. Daisy for more information								
Michelle Soto									
288459					10/10/2023		99		\$0.00
Medium	Work In Progress				10/10/2023 7:37:43 AM				
Duenas, Jose	Need to order primary screen to level the ground to be used for parking.								
Guillermo Hernandez									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>72</b>	<b>Total for Anthony - On Track Pre-K (Village)</b>				<b>0</b>	<b>\$0.00</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: Anthony ES</b>									
289219					10/24/2023		85		\$6,920.93
Medium	Work In Progress				10/24/2023 3:34:58 PM				
Tellez, Hector	Need to order solar lights for door entrances to building								
Hector Tellez									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>85</b>	<b>Total for Anthony ES</b>			<b>0</b>	<b>\$6,920.93</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Berino ES</b>										
288937					10/18/2023		91	\$8,588.84		
Medium	Work In Progress				10/18/2023 3:40:56 PM					
Tellez, Hector		need to order 10 solar kimberly lights								
Hector Tellez										
291304		Athletic Field			12/7/2023		41	\$8.58		
Medium	Work In Progress				12/7/2023 12:28:46 PM					
Ontiveros, Joe		I need to trench right next to the concret ( new metal shades) close to the pond, marking is in purple								
Jose Vasquez										
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>66</b>	<b>Total for Berino ES</b>			<b>0</b>	<b>\$8,597.42</b>	

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Chaparral ES</b>										
291412	Main Building	Classroom			12/11/2023		37		\$0.00	
Medium	Work In Progress	125			12/11/2023 7:08:49 AM					
Pacheco, Hector		The water or pipes in the sink sound like they are bubbling.								
Micaela Paniagua										
289310					10/26/2023		83		\$6.90	
Medium	Work In Progress				10/26/2023 8:19:26 AM					
Vela, Nancy		CE need fix roof for warranty. TPO on 321 room area								
Juan Vargas										
290586	Main Building	Classroom			11/27/2023		51		\$0.00	
Medium	Work In Progress	331			11/27/2023 7:56:45 AM					
Ambriz, Jose		The classroom is too hot.								
Micaela Paniagua										
<b>Count: 3 Work Orders</b>		<b>Avg. Age of WO's 57</b>		<b>Total for Chaparral ES</b>				<b>0</b>	<b>\$6.90</b>	

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Chaparral HS

290094		Exterior			11/8/2023		70		\$0.00
--------	--	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/8/2023 8:07:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duenas, Jose		Remove part of the dirt in the flower beds in front of the office and replace the dirt with baseball turf ( red dirt)				Asp Memo, route to J. Duenas			
--------------	--	---	--	--	--	------------------------------	--	--	--

Jose Vasquez

289680	Q-Wing	Classroom			11/2/2023		76		\$0.00
--------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Q-4			11/2/2023 11:51:08 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Pacheco, Hector		I need my compressor connected to the electrical panel since it's a 3 phase 320v and also the compressor needs to be plumb into the building and have some air lines that are connected to Ornelas and Acosta's shops. (Q-4)							
-----------------	--	--	--	--	--	--	--	--	--

Eli Barrios

289929					11/6/2023		72		\$394.32
--------	--	--	--	--	-----------	--	----	--	----------

Medium	Work In Progress				11/6/2023 8:19:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan		paint dugouts at soft /baseball and soccer fields							
--------------	--	---	--	--	--	--	--	--	--

Juan Vargas

290162	R-Wing	Classroom			11/9/2023		69		\$0.00
--------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	R-5			11/9/2023 9:22:32 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Pacheco, Hector		Kitchen smells like gas, 3rd sink in dish room slowly drains while closed and garbage disposal is not working. (Veronica Garcia,R-5)							
-----------------	--	--	--	--	--	--	--	--	--

Eli Barrios

290171	F-Wing	Classroom			11/9/2023		69		\$2,591.10
--------	--------	-----------	--	--	-----------	--	----	--	------------

Medium	Work In Progress	F-Lab			11/9/2023 12:27:04 PM				
--------	------------------	-------	--	--	-----------------------	--	--	--	--

Flores, Antonio		Repair the floor power sockets (Ray Murray, F-Lab)							
-----------------	--	--	--	--	--	--	--	--	--

Eli Barrios

289304					10/26/2023		83		\$0.00
--------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/26/2023 7:55:28 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Avila, Jesus		Need extended. Metal canopy nex to Morgan storage							
--------------	--	---	--	--	--	--	--	--	--

Juan Vargas

288305	F-Wing	Custodial			10/4/2023		105		\$0.00
--------	--------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/4/2023 12:48:02 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Flores, Pete		Good afternoon the blower # 91015 the string to pull to start is tearing. We can't pull it to start.							
--------------	--	--	--	--	--	--	--	--	--

Christina Nares

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Chaparral HS

283819	C-Wing	Classroom			7/26/2023		6		\$0.00
Medium	Work In Progress	C-7			7/26/2023 2:27:54 PM	8/1/2023			
Montoya, Federico		Rekey filing cabinet due to missing key. (Emily Williams, C-7)				Forward. To lock Smith			
Eli Barrios									

284427	B-Wing	Custodial			8/3/2023		167		\$309.90
Medium	Work In Progress				8/3/2023 2:55:34 PM				
Pacheco, Hector		If you can please check the water pressure, in the B wing custodial closet, the water splashes out when you close it.				Asp report 10/16/23 - Waiting for parts Forwarded to plumbing			
Christina Nares									

284788	Field House	Athletic Field			8/7/2023		163		\$0.00
Medium	Work In Progress	Baseball field			8/7/2023 9:52:49 AM				
Duenas, Jose		Baseball Field needs a flag pole and pitching mound needs dirt. (coach Soria)				Asp report 10/16/23 -Waiting on pole to arrive			
Mireya Meza									

286047		Office			8/25/2023		145		\$0.00
Medium	Work In Progress	Nursing Adm			8/25/2023 2:04:18 PM				
Pacheco, Hector		Please remove sink from the CHS Nurses Office that is located in the RN-desk area. Contact person is RN-Lisa Crawford or Vivica Carlos. Thank you,							
Priscilla Martinez									

291449	H-Wing	Gym			12/11/2023		37		\$0.00
Medium	Work In Progress	showers			12/11/2023 12:28:42				
Vargas, Juan		Shower in the Main Gym between Coach Y and Coach Rojas, the shower is spilling water threw the top of the shower rod. on the wall.				Forward. To plumbing capper shower head			
Christina Nares									

291490	F-Wing	Classroom			12/12/2023		36		\$0.00
Medium	Work In Progress	F-2			12/12/2023 8:11:50 AM				
Ambriz, Jose		The classroom is very cold. Please adjusted the temperature. (Michelle Ballard,F-2)							
Eli Barrios									

290713	B-Wing	Restroom			11/28/2023		50		\$0.00
Medium	Work In Progress	B-2			11/28/2023 2:13:01 PM				
Pacheco, Hector		The sped restroom's toilet it moves to the sides. Is not well fixed to the floor. (Perez, B-2)							
Eli Barrios									

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Chaparral HS</b>							
291596					12/14/2023		34		\$0.00
Medium	Work In Progress				12/14/2023 8:50:55 AM				
Ambriz, Jose		On fields hoses unites back the weight room 3/4 copper condenser water broken need replaced							
Juan Vargas									
<b>Count: 15 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>79</b>			<b>Total for Chaparral HS</b>	<b>0</b>	<b>\$3,295.32</b>	



# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Chaparral MS</b>										
291491					12/12/2023		36		\$0.00	
Medium	Work In Progress				12/12/2023 8:25:59 AM					
Pacheco, Hector		200 wing need Flx 3 in valve	water leak			on ciling roof				
		front boys rest room								
Juan Vargas										
288529		Classroom			10/10/2023		99		\$1,518.00	
Medium	Work In Progress	105			10/10/2023 4:08:14 PM					
Ambriz, Jose		Need to installed a 2 ton ductless.								
Jose Ambriz										
288530		Classroom			10/10/2023		99		\$1,560.24	
Medium	Work In Progress	100			10/10/2023 4:10:05 PM					
Ambriz, Jose		Need to installed a 2 ton ductless.								
Jose Ambriz										
288534		Classroom			10/11/2023		98		\$1,518.00	
Medium	Work In Progress	101			10/11/2023 7:33:47 AM					
Ambriz, Jose		Need to installed a 2 ton ductless.								
Jose Ambriz										
288535		Classroom			10/11/2023		98		\$1,518.00	
Medium	Work In Progress	102			10/11/2023 7:35:35 AM					
Ambriz, Jose		Need to installed a 2 ton ductless.								
Jose Ambriz										
288536		Classroom			10/11/2023		98		\$1,588.36	
Medium	Work In Progress	103			10/11/2023 7:38:39 AM					
Ambriz, Jose		Need to installed a 2 ton ductless.								
Jose Ambriz										
<b>Count: 6 Work Orders</b>		<b>Avg. Age of WO's 88</b>			<b>Total for Chaparral MS</b>			<b>0</b>	<b>\$7,702.60</b>	

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Trail ES</b>									
288616		Kitchen			10/12/2023		97		\$0.00
High	Work In Progress				10/12/2023 8:41:58 AM				
Pacheco, Hector		Hand peddle sink is leaking water (corroded water lines)							
Dino Facio									
291417	Main Building	Classroom			12/11/2023		37		\$211.99
Medium	Work In Progress	400			12/11/2023 7:57:58 AM				
Ambriz, Jose		In room 400 in the early childhood students classroom is very cold need assistant as soon as possible.							
Elizabeth Hernandez									
291421		Kitchen			12/11/2023		37		\$0.00
Medium	Work In Progress				12/11/2023 8:28:56 AM				
Pacheco, Hector		SINK WHERE FRUIT IS WASHED IS LEAKING.							
Maritza Gonzalez									
291276		Exterior			12/7/2023		41		\$0.00
Medium	Work In Progress				12/7/2023 5:44:17 AM				
Pacheco, Hector		There's a valve outside that has a leak (pool of water at bus drop off)							
Ernesto Diaz									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>53</b>	<b>Total for Desert Trail ES</b>			<b>0</b>	<b>\$211.99</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert View ES</b>									
289246					10/25/2023		84		\$0.00
Medium	Work In Progress	Playground			10/25/2023 9:14:08 AM				
Duenas, Jose		Add wood chips to the playground next to the water tank. Please call Mrs. Cadena with any questions. (575) 882-6949							
Cynthia Maes									
290098	Main Building	Classroom			11/8/2023		70		\$0.00
Medium	Work In Progress				11/8/2023 8:52:54 AM				
Chavez, Santos		Room 325 it smells like burned wire				Re-route to Santos Chavez he already took care of this work order.			
Israel Ortega									
290091		Exterior			11/8/2023		70		\$0.00
Medium	Work In Progress				11/8/2023 8:00:44 AM				
Vasquez, Jose		Need wood fiber for the playgrounds							
Jose Vasquez									
<b>Count: 3 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>75</b>	<b>Total for Desert View ES</b>			<b>0</b>	<b>\$0.00</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: GAC</b>										
285273	The Pointe	Office			8/14/2023		156		\$0.00	
Medium	Work In Progress				8/14/2023 9:58:59 AM					
Chavez, Santos		Room #312 we have an issue with the lights they went off and we need this office to be checked in Finance Department in Priscilla Escobar's room.								
Martha Ortega										
291355	The Pointe	Computer Lab			12/8/2023		40		\$500.55	
Medium	Work In Progress				12/8/2023 10:14:05 AM					
Ambriz, Jose		Spoke to Mr. Shane to send someone to check the thermostat and also on the top of the roof to check the heaters.								
Martha Ortega										
291423					12/11/2023		37		\$0.00	
Medium	Work In Progress				12/11/2023 8:43:37 AM					
Ambriz, Jose		Received call from Lucy Garcia, that the heater in Vanessa Garcia in HR office is not working, blowing cold air.								
Margret Villalobos										
291497					12/12/2023		36		\$0.00	
Medium	Work In Progress				12/12/2023 9:42:03 AM					
Ambriz, Jose		Sam Snoddy office, heater smells burnt.								
Cora Ramirez										
291589					12/14/2023		34		\$0.00	
High	Work In Progress				12/14/2023 8:19:07 AM					
Ambriz, Jose		Need to check for gas odor as per email from Memo.								
Guillermo Hernandez										
291479	The Pointe	Cafeteria			12/11/2023		37		\$0.00	
Medium	Work In Progress				12/11/2023 3:41:26 PM					
Ambriz, Jose		The icemaker is having dirt on the ice. The ice has dirt and is not coming out clean								
Martha Ortega										
<b>Count: 6 Work Orders</b>		<b>Avg. Age of WO's 57</b>			<b>Total for GAC</b>			<b>0</b>	<b>\$500.55</b>	

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Gadsden ES</b>							
291528		Classroom			12/13/2023		35		\$0.00
Medium	Work In Progress	207			12/13/2023 7:36:48 AM				
		Classroom 207 insects (roaches) in the classroom.							
Patty Madrid									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>35</b>	<b>Total for Gadsden ES</b>			<b>0</b>	<b>\$0.00</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

291592					12/14/2023		34	\$974.05
--------	--	--	--	--	------------	--	----	----------

Medium	Work In Progress	CT robotics			12/14/2023 8:40:16 AM			
--------	------------------	-------------	--	--	-----------------------	--	--	--

Ambriz, Jose      Need to replace blower motor.

Jose Ambriz

291559	North Building	Restroom			12/13/2023		35	\$49.39
--------	----------------	----------	--	--	------------	--	----	---------

Medium	Work In Progress	Boys and Girls			12/13/2023 3:00:47 PM			
--------	------------------	----------------	--	--	-----------------------	--	--	--

Ontiveros, Joe

1. In the NORTH BLDG., in the BOYS RESTROOM, the FIRST urinal has a broken handle and does not allow it to flush.  
 2. Also in the NORTH BLDG., in the GIRLS RESTROOM, one of the toilets has a broken handle and does not flush either.  
 Can both of these be looked at and repaired as soon as possible, thank you.

Laura Gomez

291603	North Building	Kitchen			12/14/2023		34	\$0.00
--------	----------------	---------	--	--	------------	--	----	--------

Medium	Work In Progress	207 and 208			12/14/2023 10:03:30			
--------	------------------	-------------	--	--	---------------------	--	--	--

Villalobos, Margret

Requested per Ms. Holguin and Ms. Aragon, we need pest (mice) traps replaced and any possible precautionary measures to be taken to prevent and to eliminate rodents and pests in STORAGE and KITCHEN CLASSROOM #207 and STORAGE and KITCHEN CLASSROOM #208 which both are located in the NORTH BLDG., an "Emergency Waiver for Schools" as already been approved by Admin. and attached to email to Margret Villalobos. Waiver attached to WO.

EM Bugout 12/14/23

Laura Gomez

291605					12/14/2023		34	\$0.00
--------	--	--	--	--	------------	--	----	--------

High	Work In Progress				12/14/2023 10:16:50			
------	------------------	--	--	--	---------------------	--	--	--

Ambriz, Jose      Gas odor between Theater and N. Bldg.      reroute to hvac - CH

Shane Smythe

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

291618	North Building	Restroom			12/14/2023		34		\$0.00
Medium	Work In Progress				12/14/2023 2:05:59 PM				

Ontiveros, Joe Requested per Custodian, BOYS BATHROOM in NORTH BLDG., in front of MR. LUGO'S office has two (2) urinals that are out of order. When being flushed they are over flowing with water and flooding the bathroom, the custodians having taken the necessary precautions so that students do not use urinals, but they continue to take off whatever custodians place to prevent them from using them. Can we get a plumber to come see what exactly the issue is with these urinals. In addition, the GIRLS BATHROOM in the NORTH BLDG., also located across from MR. LUGO'S office is also having the same problem when being flushed. If need be, please get with our campus custodians so they can show you what exactly is going on with them, thank you.

Laura Gomez

291620	Cafeteria (1998)	Cafeteria			12/14/2023		34		\$6.99
Medium	Work In Progress	Near "Its Italian"			12/14/2023 2:10:27 PM				

Ontiveros, Joe Requested per Frank Marin, the WATER FOUNTAIN located in the CAFETERIA near one of the serving areas called, "It's Italian" is clogged and needing to be drained manually on the daily. Can we please have someone look at this and repair, thank you.

Laura Gomez

291435		Restroom (Girls)			12/11/2023		37		\$0.00
Medium	Work In Progress	Annex			12/11/2023 9:30:00 AM				

Ontiveros, Joe Requested per Frank Marin, there are two (2) sinks in the GIRLS RESTROOM located in the ANNEX that are missing knobs. It looks likes the knobs were taken off by students. The sinks are not able to be used, sink knobs need to be repaired, thank you.

Laura Gomez

291496		Exterior			12/12/2023		36		\$0.00
Medium	Work In Progress	Various Areas			12/12/2023 9:36:19 AM				

Tellez, Hector Outside building lights need to be replaced in-between CTE and Admin building. Currently none of them are working. Large outdoor light just in front of the entrance to cafeteria is out, needs to be replaced. Lights on shed of the entrance to CTE building, some of the lights need to be replaced, thank you.

Laura Gomez

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									

Location: Gadsden HS

290679	Varsity Gym	Exterior			11/28/2023		50		\$2.25
--------	-------------	----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	Atrium			11/28/2023 9:42:33 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Tellez, Hector  
Requested per Mr. Velez, the lights that are located in the VARSITY GYM/ATRIUM do not turn on, it seems that this has been an issue in the past and still has not been corrected. The lights are facing and mounted high on the NORTH SIDE of the wall. Can this please be repaired/corrected, thank you.

Laura Gomez

291096	Vocational	Classroom			12/4/2023		44		\$0.00
--------	------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	504			12/4/2023 9:21:44 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Flores, Pete  
Requested per Ms. Perry, the compressor needs to be fixed it is located in CLASSROOM #504 in the CTE BLDG., if this can be taken care of as soon as possible it would be greatly appreciated, thank you. reroute to pete flores

Laura Gomez

290689	Library	Library			11/28/2023		50		\$0.00
--------	---------	---------	--	--	------------	--	----	--	--------

Medium	Work In Progress	LIGHTS			11/28/2023 10:32:11				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Tellez, Hector  
Requested per Mr. Quiroga, he was observant in noticing that the lights in the LIBRARY near the SKY LIGHT are not working and need to be replaced. Can this please be looked at and repaired, thank you.

Laura Gomez

285790					8/22/2023		148		\$528.84
--------	--	--	--	--	-----------	--	-----	--	----------

Medium	Work In Progress				8/22/2023 9:35:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Tellez, Hector  
Requested by Mr. Matt Grubaugh for Library-There are several lights in the library that come on only for a few seconds and then flicker out. He believes it is a wiring problem. This is the second request for help with this issue. Asp report 10/16/23 - material on order

Velia Alarcon

284811					8/7/2023		163		\$0.00
--------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/7/2023 12:45:48 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Flores, Pete  
need tillers repaired

Carlos Hernandez

284491		Football Field			8/4/2023		166		\$0.00
--------	--	----------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/4/2023 10:29:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lucero, Michael  
Need to remove dirt and grass in front of concession stand, and put crusher fine Asp report 10/16/23 -Waiting on materials

Jose Vasquez



# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Gadsden HS</b>							
288271		Football Field			10/3/2023		106	1	\$128.53
Medium	Work In Progress	Guest			10/3/2023 3:45:33 PM				
Ontiveros, Joe		Requested per Mr. Lugo, the water fountains near the FOOTBALL FIELD BATHROOM AREA are NOT working and need to be repaired. Please look into this, thank you. Photo attached.					Reroute to plumbing. ASP Jose A. Hvac Supervisor		
Laura Gomez									
288558					10/11/2023		98		\$0.00
Medium	Work In Progress				10/11/2023 11:28:14				
Hernandez, Guillermo		Roof repair kit for GHS, STH and CHHS.							
Guillermo Hernandez									
290238					11/13/2023		65		\$0.00
Medium	Work In Progress				11/13/2023 7:35:37 AM				
Tellez, Hector		pole was hit check for integrity							
Hector Tellez									
290331					11/14/2023		64		\$0.00
Medium	Work In Progress	Weight Room			11/14/2023 8:59:02 AM				
Ontiveros, Joe		Requested per Coach O'Neil, the water fountain located in the WEIGHT ROOM FACILITY had been leaking all weekend and created a minor flood. The water fountain continues to leak. If this can be looked at asap and repaired, thank you.							
Laura Gomez									
290340					11/14/2023		64		\$0.00
Medium	Work In Progress				11/14/2023 9:53:37 AM				
Flores, Pete		tiller for grounds needs repair							
Carlos Hernandez									
289255	Community	Restroom (Girls)			10/25/2023		84		\$0.00
Medium	Work In Progress	Weight Room			10/25/2023 10:14:29				
Ontiveros, Joe		Requested per Frank/Custodian, one of the sinks located in the GIRLS RESTROOM in the WEIGHT ROOM is leaking water, the custodians went ahead and turned off the water to that sink to avoid any further damage, thank you.							
Laura Gomez									

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Gadsden HS</b>							
289274	Business	Classroom			10/25/2023		84		\$0.00
Medium	Work In Progress	600			10/25/2023 1:27:41 PM				
Ontiveros, Joe		Requested per Ms. Favela, she has stated that there are several of the sinks in her classroom leaking along with some faucets. She is located in the SCIENCE BLDG (BUSINESS BLDG) ROOM #600. Can this please get repaired as soon as possible, thank you.							
Laura Gomez									
288899					10/18/2023		91		\$1,705.90
Medium	Work In Progress	Football field			10/18/2023 9:03:38 AM				
Ambriz, Jose		Need to replace evaporator to ice machine.							
Jose Ambriz									
<b>Count: 22 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>71</b>	<b>Total for Gadsden HS</b>			<b>1</b>	<b>\$3,395.95</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

290446	Annex	Classroom			11/15/2023		63		\$0.00
--------	-------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	RM 407 - Durr			11/15/2023 4:16:03 PM				
--------	------------------	---------------	--	--	-----------------------	--	--	--	--

Tellez, Hector  
I have another flickering light in my classroom please replace.  
Thank you 11/15/23

Hilda Adler

287918		Classroom			9/29/2023		110		\$217.50
--------	--	-----------	--	--	-----------	--	-----	--	----------

Medium	Work In Progress	RM 404 -			9/29/2023 1:53:33 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Tellez, Hector  
Light bulbs out, need them replaced. reroute electrician.  
Light by window  
Light in front of Newline Screen  
Light between vent and fire alarm

Hilda Adler

284301	C-Wing	Office			8/2/2023		168		\$2,038.58
--------	--------	--------	--	--	----------	--	-----	--	------------

Medium	Work In Progress	Nursing Dept			8/2/2023 8:53:29 AM				
--------	------------------	--------------	--	--	---------------------	--	--	--	--

Ambriz, Jose  
Please send plumber to change water filter in the fountain/refill station in the CHS Nurses Office. Reroute to HVAC - JO 10/31/23  
Thank you,  
Priscilla

Priscilla Martinez

287810		Classroom			9/27/2023		112		\$0.00
--------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	RM 163 -Mr.			9/27/2023 3:26:53 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Hernandez, Guillermo  
The wall that has the smartboard in front of it is showing signs of water intrusion. This is concerning from the standpoint that within the last week students have been commenting about a smell in the room. It could be related to this water intrusion. I am revising this order also to include browned tiles on the ceiling. There may be water intrusion that is making the insulation and other materials above the ceiling rot and mold. I have ran the air filter machine all last night, and have it on full blast this morning, but the kids have been complaining about the smell, and I am not sure if what we are breathing in is safe or the product of mold above the ceiling tiles. Pictures of the wall and ceiling tiles are submitted below. Reported on 9/27/23

Hilda Adler

291117	Main Building	Restroom (Girls)			12/4/2023		44		\$0.00
--------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/4/2023 12:39:33 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Joe  
leaking water from metal pipe of toilet when flushed in girls restroom in the mid corridor of main building rereoute to plumber

David Hinojosa

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Gadsden MS</b>							
291628					12/14/2023		34		\$0.00
Medium	Work In Progress	boys locker			12/14/2023 3:37:51 PM				
Ontiveros, Joe		Need to check water fountain in boys locker room.				Hvac tech clean p-trap and water is still backing up, clogged drain.			
Jose Ambriz									
291662	C-Wing	Office			12/15/2023		33		\$0.00
Medium	Work In Progress	Nursing Adm			12/15/2023 12:06:50				
Ontiveros, Joe		4th request, just running water in one of our toilets, please check before we leave for the holidays. Thank you, Priscilla							
Priscilla Martinez									
<b>Count: 7 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>81</b>	<b>Total for Gadsden MS</b>			<b>0</b>	<b>\$2,256.08</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location: La Union ES</b>									
290673	2000 Core	Classroom			11/28/2023		50		\$0.00
Medium	Work In Progress	MR.			11/28/2023 9:03:18 AM				
Hernandez, Guillermo		URGENT. PLEASE ASSESS CLASSROOM FOR MOLD. TEACHER IS CONCERNED ABOUT HAVING BREATHING ISSUES WHEN IN CLASS.							
Virginia Galindo									
290769	Main Building	Classroom			11/29/2023		49		\$0.00
Medium	Work In Progress	MS.			11/29/2023 11:47:26				
Ontiveros, Joe		REINSTALL TOILET & SINK THAT WE WERE REMOVED FROM RESTROOM IN CLASSROOM.							
Virginia Galindo									
290121		Kitchen			11/8/2023		70		\$0.00
High	Work In Progress				11/8/2023 1:36:21 PM				
Pacheco, Hector		In three compartment sink and sink at the front both faucets are leaking							
Dino Facio									
289995	Main Building				11/6/2023		72		\$0.00
Medium	Work In Progress	MS.			11/6/2023 3:08:11 PM				
Ontiveros, Joe		PLEASE ASSESS ROOM FOR INSTALLING A SINK AREA FOR STUDENTS TO WASH THEIR HANDS AND ASSESS TO ENSURE THAT SINK INCLUDES A PAINT TRAP.							
Virginia Galindo									
<b>Count: 4 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>60</b>	<b>Total for La Union ES</b>			<b>0</b>	<b>\$0.00</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
284297	Main Building	Classroom			8/2/2023		168		\$0.00
Medium	Work In Progress	212/Escobedo			8/2/2023 8:27:24 AM				
Tellez, Hector		Lights do not turn off with switch (need them incase of lockdown or shelter in place).				Asp report 10/16/23 - need to rewire light relay			
Crystalee Heredia									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>168</b>	<b>Total for Loma Linda ES</b>			<b>0</b>	<b>\$0.00</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: North Valley ES</b>										
288554					10/11/2023		98		\$0.00	
Medium	Work In Progress				10/11/2023 10:44:45					
Hernandez, Guillermo		Need install signs for the playgrounds (NV, RS and Sunrise)								
290909		Classroom			12/1/2023		47		\$2.25	
Medium	Work In Progress	103			12/1/2023 11:35:16 AM					
Tellez, Hector		Need to replace lights in room 103								
Gloria Reyes										
291551		Classroom			12/13/2023		35		\$0.00	
Medium	Work In Progress	401/Nurse's			12/13/2023 11:41:09					
Ambriz, Jose		The fan in the bathroom in the Nurse's office stopped working.								
Gloria Reyes										
<b>Count: 3 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>60</b>	<b>Total for North Valley ES</b>			<b>0</b>	<b>\$2.25</b>	

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Northern On-Track Pre-K (LM)</b>										
291661					12/15/2023		33		\$0.00	
Medium	Work In Progress				12/15/2023 12:01:12					
Ontiveros, Joe		Plummer has replace the water heater. Now I need someone to come look at the drawer under the water heater because it will not close. Same room #104. I do have a picture of it.				reroute to plumber he soldered valve close to door not letting door close				
Sandy Silvas										
286821					9/8/2023		131		\$0.00	
Medium	Work In Progress				9/8/2023 9:24:40 AM					
Ontiveros, Joe		Please check drainage in girls bathroom. Water not going down stay clogged up. Ask Ms. Lourdes.				Asp report 10/16/23 - Memo is going to talk to Russel - J. Ontiveros				
Sandy Silvas										
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>82</b>	<b>Total for Northern On-Track Pre-K (LM)</b>			<b>0</b>	<b>\$0.00</b>	



# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
287523	Purchasing	Athletic Field			9/21/2023		11	0.1	\$222.50
Medium	Work In Progress			9/21/2023 12:48:45 PM	10/2/2023				
Vasquez, Jose	Need black and dark garnet paint for STM, STH, GH, GM, CM, CH		Black paint was delivered to the warehouse Pioneer - 2,825.32 - PO232401899						
Jose Vasquez									
289421					10/30/2023		79		\$981.59
Medium	Work In Progress			10/30/2023 7:35:44 AM					
Tellez, Hector	Need two solar lights for PPD office and for new sign								
Hector Tellez									
290588					11/27/2023		51		\$0.00
Medium	Work In Progress			11/27/2023 8:30:35 AM					
Ontiveros, Joe	There is a water leak on the Northside of the Auto Shop bldg (outside).		Informed J. Ontiveros 8:30am - mkv 11/28/23 Pending - Water is off to A/C and some how when valve is opened it comes out of the relief drain pipe, need to break wall to follow pipe						
Jose Villalobos									
289314					10/26/2023		83		\$0.00
Medium	Work In Progress	hvac tech tools		10/26/2023 8:32:58 AM					
Ambriz, Jose	Need to replace charging hoses, burst out high side for Alfredo Ortiz.								
Jose Ambriz									
288972	Motor Vehicle				10/19/2023		90		\$0.00
Medium	Work In Progress			10/19/2023 9:43:35 AM					
Flores, Pete	requesting service on Stihl chainsaw #4 (Pete Flores)								
Danny Carrasco									
288676					10/13/2023		96		\$0.00
Medium	Work In Progress	hvac shop		10/13/2023 7:43:43 AM					
Ambriz, Jose	Need to provide a TU and Rover software.								
Jose Ambriz									
291623					12/14/2023		34		\$44.97
Medium	Work In Progress			12/14/2023 2:34:52 PM					
Avila, Jesus	Requesting to order welding gear for J. Velasco for shop use.								
Jesus Avila									

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location: Physical Plant Complex</b>									
291586					12/14/2023		34		\$0.00
Medium	Work In Progress				12/14/2023 7:52:16 AM				
Ontiveros, Joe		Need Cable Snake Cutting Tips for big Cable Services Sanke.							
Joe Ontiveros									
290797		Athletic Field			11/29/2023		49		\$0.00
Medium	Work In Progress				11/29/2023 3:57:04 PM				
Vasquez, Jose		Need to order baseball turf ( red dirt) for all the Middle Schools and High Schools.							
Jose Vasquez									
291456	Main Warehouse				12/11/2023		37		\$0.00
Medium	Work In Progress				12/11/2023 1:27:21 PM				
Hernandez, Carlos		Please fix holes on the floor on original metal storage conic at warehouse.							
Enrique Briones									
<b>Count: 10 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>56</b>	<b>Total for Physical Plant Complex</b>		<b>0.10000</b>	<b>\$1,249.06</b>	

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Riverside ES</b>									
290904	Main Building	Classroom			12/1/2023		47		\$0.00
Medium	Work In Progress	20		12/1/2023 10:59:54 AM					
Chavez, Santos	outlet is not producing power, please check with teacher								
Claudia Mendez									
290539	Main Building	Classroom			11/17/2023		61		\$0.00
Medium	Work In Progress			11/17/2023 1:18:34 PM					
Chavez, Santos	En el salon #76 checar 3 balastras.								
Norma Oate									
291598					12/14/2023		34		\$29.72
Medium	Work In Progress			12/14/2023 9:01:45 AM					
Ambriz, Jose	Start-up boiler system.								
Aaron Solis									
289131	Main Building				10/23/2023		86		\$0.00
Medium	Work In Progress			10/23/2023 1:39:10 PM					
Chavez, Santos	Checar los postes de luces 3 no prenden entrada de camiones y entrada principal X seguridad del staff.								
Norma Oate									
289458	Main Building	Restroom			10/30/2023		79		\$0.00
Medium	Work In Progress			10/30/2023 1:03:16 PM					
Pacheco, Hector	de el bano de 6th. tengo unos tubos de un urinal flojos. y despegado de la pared.								
Norma Oate									
288555	Main Building	Classroom			10/11/2023		98		\$0.00
Medium	Work In Progress	Multi Use Room		10/11/2023 10:47:13					
Herrera, Marin	We need three book shelves to be moved from the multi use room to classroom 16. The bookshelves are currently installed and attached to the wall		Waiting for Shane's approval						
Claudia Mendez									
<b>Count: 6 Work Orders</b>		<b>Avg. Age of WO's 68</b>		<b>Total for Riverside ES</b>		<b>0</b>		<b>\$29.72</b>	

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa ES</b>									
288655					10/12/2023		97		\$0.00
Medium	Work In Progress				10/12/2023 2:26:04 PM				
Herrera, Marin		As per Suncity Analytical Report, replace ceiling tiles and check for roof leaks - Main Bldg. & 800 Classroom Bldg.							
		*Map Provided and placed in your Maintenance Mailbox*							
Guillermo Hernandez									
286920					9/11/2023		128		\$0.00
Medium	Work In Progress	Potable E (Ms.			9/11/2023 11:17:08 AM				
Herrera, Marin		Please install a fiber optic corner shower in portable E with Ms. Diaz. Ms. Diaz has the optic just needs assistance to install it. (Ms. Diaz)				Still waiting on approval spoke with Memo 9/12/23, 10/31/23			
Norma Martinez									
290780					11/29/2023		49		\$0.00
Medium	Work In Progress				11/29/2023 3:15:13 PM				
Lara, Ralph		As per Mr. S. Smythe approval, please install an additional door to the nurse's office for safety purposes. The door will be installed next to the conference room. (Mrs. Word)							
Norma Martinez									
291145					12/4/2023		44		\$0.00
Medium	Work In Progress				12/4/2023 4:10:14 PM				
Lucero, Michael		Need wood chips in lower grade playground at STE thank you							
Marin Herrera									
<b>Count: 4 Work Orders</b>		<b>Avg. Age of WO's 80</b>			<b>Total for Santa Teresa ES</b>			<b>0</b>	<b>\$0.00</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

290866					11/30/2023		48		\$0.00
--------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/30/2023 2:03:34 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Duenas, Jose		Need clay mount for softball field thank you (2 bags)				re-route to grounds (Joe Duenas)			
--------------	--	---	--	--	--	----------------------------------	--	--	--

Marin Herrera

290683	Main Building	Classroom			11/28/2023		50		\$0.00
--------	---------------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	513			11/28/2023 9:58:10 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Pacheco, Hector		SINK IN FAR RIGHT SIDE OF CLASSROOM LEAKING							
-----------------	--	---	--	--	--	--	--	--	--

Ashley Villalobos-Trujillo

291286		Kitchen			12/7/2023		41		\$0.00
--------	--	---------	--	--	-----------	--	----	--	--------

High	Work In Progress				12/7/2023 8:21:03 AM				
------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Marin		Walls in mop room need to be fixed coming apart (possible mold)							
----------------	--	---	--	--	--	--	--	--	--

Dino Facio

291198	Main Building	Classroom			12/5/2023		43		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	501			12/5/2023 3:04:14 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Ruiz, Danny		Please install blinds in classroom				Re-route to Danny Ruiz thank you			
-------------	--	------------------------------------	--	--	--	----------------------------------	--	--	--

Ashley Villalobos-Trujillo

291349	Main Building	Classroom			12/8/2023		40		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	501			12/8/2023 9:38:34 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Chavez, Santos		4 lights are out, and some lights have some stains on them, please see Mr. Villagrana							
----------------	--	---	--	--	--	--	--	--	--

Ashley Villalobos-Trujillo

291499	Vocational	Classroom			12/12/2023		36		\$0.00
--------	------------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	803			12/12/2023 10:16:29				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Ambriz, Jose		The exhaust extractors for the welding fumes need to be looked at. I believe that one of the extractors is not working. They do need some maintenance done on them either way.							
--------------	--	--	--	--	--	--	--	--	--

Ashley Villalobos-Trujillo

287343		Mechanical			9/19/2023		120		\$5,560.02
--------	--	------------	--	--	-----------	--	-----	--	------------

Medium	Work In Progress	chiller			9/19/2023 7:43:01 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Ambriz, Jose		Need to check condenser inverter.				Order 2 condenser inverters for chiller as per parts trane will take 6 to 8 weeks for delivery			
--------------	--	-----------------------------------	--	--	--	--	--	--	--

Jose Ambriz

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Santa Teresa HS**

284068		Kitchen			7/31/2023		170		\$0.00
--------	--	---------	--	--	-----------	--	-----	--	--------

High	Work In Progress				7/31/2023 9:26:41 AM				
------	------------------	--	--	--	----------------------	--	--	--	--

Ruiz, Maria E		Need all ceiling vents and registers clean as per Health Insp.				Re-route to Custodians thank you			
---------------	--	--	--	--	--	----------------------------------	--	--	--

Dino Facio

290515	Main Building				11/17/2023		61		\$0.00
--------	---------------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	200			11/17/2023 9:00:20 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Chavez, Santos		Please install surge switch in room 200							
----------------	--	---	--	--	--	--	--	--	--

Ashley Villalobos-Trujillo

290415					11/15/2023		63		\$0.00
--------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	G.Soccer			11/15/2023 9:57:04 AM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Chavez, Santos		Need an electrical light switch fixed in the girls soccer storage room. Please see Ms. Gentzler or Coach Sanchez							
----------------	--	--	--	--	--	--	--	--	--

Ashley Villalobos-Trujillo

289209					10/24/2023		85		\$0.00
--------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/24/2023 1:21:09 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Pacheco, Hector		Need water supply outside maintenance shop to wash maintenance trucks							
-----------------	--	---	--	--	--	--	--	--	--

Marin Herrera

289127					10/23/2023		86		\$0.00
--------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	Band Room			10/23/2023 1:19:25 PM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Chavez, Santos		Change light switches in front entrance of band room (by outside doors).							
----------------	--	--	--	--	--	--	--	--	--

Ashley Villalobos-Trujillo

288692	Classroom				10/13/2023		96		\$3.79
--------	-----------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	Choir Room			10/13/2023 9:49:01 AM				
--------	------------------	------------	--	--	-----------------------	--	--	--	--

Chavez, Santos		Lights need to be replaced, on high ceiling in choir room and light switch does not work.-Mr. Soria							
----------------	--	---	--	--	--	--	--	--	--

Ashley Villalobos-Trujillo

288694	Hallway/Corridor				10/13/2023		96		\$0.00
--------	------------------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	Band/Choir			10/13/2023 9:53:32 AM				
--------	------------------	------------	--	--	-----------------------	--	--	--	--

Chavez, Santos		Lights are not working in the hallway between the Band Room and Choir Room. Where our Practice Rooms are located.-Mr. Allen (Band Director)							
----------------	--	---	--	--	--	--	--	--	--

Ashley Villalobos-Trujillo

<b>Count: 14 Work Orders</b>		<b>Avg. Age of WO's 74</b>			<b>Total for Santa Teresa HS</b>		<b>0</b>		<b>\$5,563.81</b>
------------------------------	--	----------------------------	--	--	----------------------------------	--	----------	--	-------------------

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa MS</b>									
288656					10/12/2023		97		\$0.00
Medium	Work In Progress				10/12/2023 2:27:09 PM				
Herrera, Marin		As per Suncity Analytical Report, replace ceiling tiles and check for roof leaks - North & South Lower/Upper Levels and Cafeteria							
		*Map Provided and placed in your Maintenance Mailbox*							
Guillermo Hernandez									
291504	North Building				12/12/2023		36		\$0.00
Medium	Work In Progress				12/12/2023 12:06:08				
Chavez, Santos		En el edificio Norte parte trasera del edificio por fuera una de las lamparas grandes en la puera no tiene foco							
Matilde Gonzalez									
291180	Gym (1997)	Gym			12/5/2023		43		\$0.00
Medium	Work In Progress	BLEACHERS			12/5/2023 12:36:59 PM				
Chavez, Santos		WOULD IT BE POSSIBLE TO CHANGE THE BLEACHERS SWITCH FROM A KEY SWITCH TO A TOGGLE SWITCH?							
Laura Parra									
290844					11/30/2023		48		\$0.00
Medium	Work In Progress				11/30/2023 11:02:45				
Herrera, Marin		asiendo peticion para la reparacion de las paredes de los banos abajo de los lavamanos donde an abierto para reparar alginos de ellos y hay hoyos o faltante de tile gracias							
Matilde Gonzalez									
<b>Count: 4 Work Orders</b>		<b>Avg. Age of WO's 56</b>			<b>Total for Santa Teresa MS</b>			<b>0</b>	<b>\$0.00</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>SNP Complex</b>							
287885					9/29/2023		110		\$563.00
High	Work In Progress				9/29/2023 6:53:02 AM				
Chavez, Santos		As per Santos need a solar light wall mount in front of main entrance							
Dino Facio									
287886					9/29/2023		110		\$0.00
High	Work In Progress				9/29/2023 6:54:33 AM				
Chavez, Santos		As per Santos need a solar light for front of SNP building							
Dino Facio									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>110</b>			<b>Total for SNP Complex</b>	<b>0</b>		<b>\$563.00</b>



# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
286166					8/29/2023		141		\$7.92
Medium	Work In Progress			8/29/2023 7:43:46 AM					
Lucero, Michael	SP need unclog the storm drainpipe by the marquee and clean the passage. While you are at SP level the front area and cover the exposed gas line by the Morgan building.		Asp report 10/16/23 -Equipment at location will be starting later this week						
Guillermo Hernandez									
286168					8/29/2023		141		\$77.47
Medium	Work In Progress			8/29/2023 7:46:07 AM					
Pacheco, Hector	Please generate a work order to close the gas line that was feeding the tenant at SP. Hector if you walk by the marquee and keep going north to the Morgan building you will see the gas line. Please close it from the main. Check to see if we need to remove it.		Asp report 10/16/23 - Pending						
Guillermo Hernandez									
291178		Kitchen			12/5/2023		43		\$0.00
High	Work In Progress			12/5/2023 12:25:26 PM					
Chavez, Santos	Hood lights are burnt out possible electrical issue								
Dino Facio									
<b>Count: 3 Work Orders</b>		<b>Avg. Age of WO's 108</b>		<b>Total for Sunland Park ES</b>			<b>0</b>	<b>\$85.39</b>	

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
291079		Kitchen			12/4/2023		44		\$121.54
High	Work In Progress				12/4/2023 7:47:06 AM				
Ontiveros, Joe		Need pressure regulator installed for dish machine							
Dino Facio									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>44</b>	<b>Total for Vado ES</b>			<b>0</b>	<b>\$121.54</b>

# 132 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 12/31/2023 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Yucca Heights ES</b>									
288397					10/9/2023		100		\$0.00
Medium	Work In Progress				10/9/2023 8:41:39 AM				
Lucero, Michael		Need woodchips for play grond							
Juan Vargas									
288794					10/16/2023		93		\$0.00
Medium	Work In Progress				10/16/2023 2:53:15 PM				
Duenas, Jose		Need wood ships for play grounds							
Juan Vargas									
290349					11/14/2023		64		\$0.00
Medium	Work In Progress				11/14/2023 11:02:11				
Pacheco, Hector		Need fix outside water valve on Eastside building closed to portables							
Juan Vargas									
290359					11/14/2023		64		\$0.00
Medium	Work In Progress				11/14/2023 1:04:29 PM				
Pacheco, Hector		Leak on the water valve outside the building.				Forward to plumbing			
Rocio Rodriguez									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's 80</b>			<b>Total for Yucca Heights ES</b>	<b>0</b>		<b>\$0.00</b>
<b>Count: 132 Work Orders</b>			<b>Avg. Age of WO's 72</b>			<b>Grand Total</b>	<b>1.10000000</b>		<b>\$40,991.51</b>