Selected Da WOID	ate Range for Request Building	Dates:7/1/2023-2 Area	2/29/2024 Order By Loc Deferred By	cation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Crea	ated Date/Time	Actual Comp Date	Aged	Hours	
Assigned [·]	То	Description				Action Taken			
Requester	Name								
Location:	Alta Vista	ECHS							
294430					2/16/2024		25		\$6.19
Medium	Work In Progress	P10		2/16/2	2024 9:54:21 AM	I			
Tellez, Heo	ctor	The plumber is plug in the hot	requesting an exten water heater.	ded electrica	l cord to				
Melanie B	eegle								
294498					2/19/2024		22		\$0.00
Medium	Work In Progress	P1		2/19/2	2024 9:19:57 AM	l			
Tellez, Heo	ctor		ter in Principal De La ossible to replace it?	Garza's offic	е	reroute to electrician			
Melanie B	eegle								
294903					2/27/2024		14		\$23.99
Medium	Work In Progress	P20		2/27/2	024 1:27:24 PM				
Ambriz, Jo	ise	work orders res ductwork to all classroom. Work can be do	still does not cool ade sulted in discussion o ow proper air flow thro one on Fridays or duri ssts that it be finished	f redoing the oughout the ing the summ	erbut				
Melanie B	eegle								
Count: 3 V	Vork Orders	A	vg. Age of WO's 20	0	٦	otal for Alta Vista E	CHS	0	\$30.18

200			1091033 (1	iscai	rcarj				Total
Selected Da	ate Range for Request Building	Dates:7/1/2023 - 2 Area	2/29/2024 Order By Loc Deferred By		Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Creat	ted Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Anthony -	On Track Pre-	K (Village)						
291124		Classroom			12/4/2023		99		\$0.00
Medium	Work In Progress	109		12/4/20)23 2:26:31 PN	1			
Tellez, He	ctor	classroom nee Daisy for more	ds more outlets. Plea information	se see teache	er Ms.				
Michelle S	Soto								
291369					12/8/2023		95		\$0.00
High	Work In Progress			12/8/20)23 3:23:02 PM	1			
Villalobos	, Margret	As per Mr. Hern gophers a/s/a/p	andez, please treat p	layground are	eafor	EM BugOut 12/8/23			
Guillermo	Hernandez								
Count: 2 V	Vork Orders	Δ	vg. Age of WO's 97	7 Total	for Anthony -	On Track Pre-K (Vil	age)	0	\$0.00

WOID Priority	Building Status	Dates:7/1/2023 - 2/29/2024 Order By L Area Deferred By Area Number Reason	ocation, Status Until Request Date Ta Created Date/Time Ac	tual Comp Date	Days Aged	C Labor Hours	Costs
Assigned		Description		Action Taken			
Requester							
Location:	Anthony I	ES					
285247			8/14/2023		211	\$	\$0.00
Medium	Work In Progress		8/14/2023 8:08:40 AM				
Hernande	z, Guillermo	Need to replace relays and conne controls to Trane.	ect the inside lighting				
Guillermo	Hernandez						
289219			10/24/2023		140	\$6,94	44.93
Medium	Work In Progress		10/24/2023 3:34:58 PM				
Tellez, Hee	ctor	Need to order solar lights for door	entrances to building				
Hector Tel	llez						
293322			1/29/2024		43	\$	\$0.00
Medium	Work In Progress		1/29/2024 2:39:29 PM				
Duenas, J	ose	Need to remove one foot of dirt fro Then bed vault with 6-10 inches or gravel to prevent condensation.					
Edward So	chneider						
294512			2/19/2024		22	\$5	58.25
Medium	Work In Progress		2/19/2024 11:27:03 AM				
Tellez, Heo	ctor	Building: Library Description: Please install 4 Elect the closet wall. (see Ms. Avalos for exact location) thank you					
Jessica Lo	opez						
294933			2/28/2024		13	\$	\$0.00
Medium	Work In Progress		2/28/2024 7:30:07 AM				
Tellez, Heo	ctor	Please replace fluorescent linear office thank you	bulbs in the front				
Jessica Lo	-						
Count: 5 V	Vork Orders	Avg. Age of WO's	86	Total for Anthon	y ES	0 \$7,00)3.18

WOID Priority	Building Status	Dates:7/1/2023 - 2/29/2024 Order By Loca Area Deferred By Area Number Reason		-	Days Aged	Labor Hours	Total Costs
Assigned Requester		Description		Action Taken			
Location:	Berino ES	3					
293825			2/6/2024		35		\$0.00
Medium	Work In Progress		2/6/2024 8:04:54 AM				
Hernande	z, Guillermo	Fire Sprinkler repairs identified durin inspection.	ig quarterly				
Guillermo	Hernandez						
288937			10/18/2023		146	\$8	8,588.84
Medium	Work In Progress		10/18/2023 3:40:56 PM				
Tellez, Heo	ctor	need to order 10 solar kimberly lights	3				
Hector Tel	llez						
289909			11/5/2023		128		\$0.00
Medium	Work In Progress		11/5/2023 12:49:03 AM				
Flores, Pe	te	Monthly - Berino ES - Mower M-040 schedule details.	01 - Refer to PM				
Margret Vil	llalobos						
288700			10/13/2023		151		\$0.00
Medium	Work In Progress		10/13/2023 10:35:42				
Hernande	z, Guillemo	PSFA Need to install walking pads on the ro	pof.				
Guillermo	Hernandez						
Count: 4 V	Vork Orders	Avg. Age of WO's 11	5	Total for Berin	o ES	0\$8	3,588.84

Selected D			2/29/2024 Order By Log		•				Total Costs
WOID	Building	Area	Deferred By	Until		Target Comp Date	Days	Labor	00313
Priority	Status	Area Number	Reason	Cr	eated Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Chaparra	al ES							
289310					10/26/2023		138		\$6.90
Medium	Work In Progress			10/26	6/2023 8:19:26 AM				
Vela, Nan	су	CE need fix roo	of for warranty. TPO o	n 321 room	area				
Juan Varg	as								
Count: 1 V	Nork Orders	A	vg. Age of WO's 1	38		Total for Chaparra	al ES	0	\$6.90

Priority Assigned Requeste		Area Number Description	Deferred By	Until Request Da	ite Target Comp Date ne Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	alHS						
289304				10/26/20	23	138		\$0.00
Medium	Work In Progress			10/26/20237:55:28	AM			
Avila, Jes	us	Need extende	d. Metal canopy ne	ex to Morgan storage				
Juan Varg	nas							
284788	Field House	Athletic Field		8/7/20	23	218		\$0.00
Medium	Work In Progress	Baseball field		8/7/2023 9:52:49	AM			
Duenas, J		Baseball Field needs dirt. (coa	needs a flag pole a Ich Soria)	nd pitching mound	Asp report 10/16/23 arrive	-Waiting	on pole to	
Mireya Me	za	0//:		0.05.00	200	0.00		<u> </u>
286047		Office		8/25/20	-	200		\$0.00
Medium	Work In Progress	Nursing Adm		8/25/2023 2:04:18	PM			
Hernande	ez, Guillemo		RN-desk area. Con	Nurses Office that is tact person is RN-Lisa				
Priscilla N	<i>l</i> artinez							
291221	A-Wing	Office		12/5/20	023	98		\$0.00
Medium	Work In Progress	Nurse office		12/5/2023 4:25:43	PM			
Villalobos	s, Margret	We have mice fumigate. (Ms.		. Please set traps or	EM Bugout - 12/6/23	8-mkv		
Mireya Me								\$0.00
Mireya Me 290246	R-Wing	Classroom		11/13/20	23	120		
-		Classroom R-4		11/13/20 11/13/2023 8:23:33	-	120		
290246	R-Wing Work In Progress	R-4	noved from R4 (Re		-	-	. Hernande	z
290246 Medium	R-Wing Work In Progress Jan	R-4	moved from R4 (Re	11/13/2023 8:23:33	AM	-	. Hernande	Z
290246 Medium Vargas, Ju	R-Wing Work In Progress Jan	R-4	noved from R4 (Re	11/13/2023 8:23:33	AM Forward. To Juan 3/	-		
290246 Medium Vargas, Ju Eli Barrios	R-Wing Work In Progress Jan	R-4 the lab table rei	noved from R4 (Re	11/13/2023 8:23:33 nne Longsdon, R-4)	AM Forward. To Juan 3/ 24	/7/24 - G		sz \$353.44
290246 Medium Vargas, Ju Eli Barrios 294056	R-Wing Work In Progress Jan s Work In Progress	R-4 the lab table ren Gym Axuliary Gym	moved from R4 (Re unit has a alarm.	11/13/2023 8:23:33 nne Longsdon, R-4) 2/9/20	AM Forward. To Juan 3/ 24	/7/24 - G		
290246 Medium Vargas, Ju Eli Barrios 294056 Medium	R-Wing Work In Progress Jan s Work In Progress	R-4 the lab table ren Gym Axuliary Gym		11/13/2023 8:23:33 nne Longsdon, R-4) 2/9/20	AM Forward. To Juan 3/ 24	/7/24 - G		
290246 Medium Vargas, Ju Eli Barrios 294056 Medium Ambriz, Jo	R-Wing Work In Progress Jan s Work In Progress	R-4 the lab table ren Gym Axuliary Gym		11/13/2023 8:23:33 nne Longsdon, R-4) 2/9/20	AM Forward. To Juan 3/ 24 AM	/7/24 - G		\$353.44
290246 Medium Vargas, Ju Eli Barrios 294056 Medium Ambriz, Jo Jose Amb	R-Wing Work In Progress Jan s Work In Progress	R-4 the lab table rep Gym Axuliary Gym Need to check to		11/13/2023 8:23:33 nne Longsdon, R-4) 2/9/20 2/9/2024 8:06:01	AM Forward. To Juan 3, 24 AM	7/24 - G		

WOID Priority Assigned 7 Requester	Building Status To	Dates:7/1/2023 - 2/29/2024 Order By Loca Area Deferred By Area Number Reason Description		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	alHS					
294121			2/11/2024		30		\$0.00
Medium	Work In Progress		2/11/2024 12:34:31 AM				
Gonzalez,	Javier	Monthly - CHS - Football Field Groom Refer to PM schedule details.	ning (Monthly) -				
Margret Vil	lalobos						
294411			2/16/2024		25		\$0.00
Medium	Work In Progress		2/16/2024 7:44:06 AM				
Flores, Pet	e	El gator se Salen los tornillos de una	llanta need fix				
Juan Varga	as						
293385			1/30/2024		42		\$0.00
Medium	Work In Progress		1/30/2024 3:45:24 PM				
Flores, Ant	onio	Light out in the girl's locker room (Al	JX) Gym)				
Antonio Flo	ores						
293438			1/31/2024		41		\$0.00
Medium	Work In Progress		1/31/2024 3:07:52 PM				
Pacheco, H	Hector	Need fix circulated water pomp and r boiler	notor on kitchen				
Juan Varga	as						
293813		Athletic Field	2/6/2024		35		\$2.44
Medium	Work In Progress		2/6/2024 7:21:17 AM				
Vasquez, J		There is a water leak right behind pite baseball field.	chers mound in the				
Jose Vasq 292724	uez		1/16/2024		56		\$0.00
Medium	Work In Progress		1/16/2024 2:54:54 PM		00		ψ0.00
		Flowerbeds to be cleaned and resurf				nmonttor	
Duenas, Jo		Flowerbeds to be cleaned and result		Re-route to Jose. He vill do the work.	avyequi	pmentiea	4111
Guillermo 292725	Hernandez		1/16/2024		56		\$0.00
Medium	Work In Progress		1/16/2024 2:56:30 PM		00		φ0.00
	-	Flastriant un ano de fas O min a	1/10/2024 2:30:301 W				
	z, Guillermo	Electrical upgrade for Q wing					
Guillermo 292827	Hernandez		1/17/2024		55		\$0.00
Medium	Work In Progress		1/17/2024 3:46:26 PM		00		ψ0.00
	-		1/17/2024 3.40.20 PW				
	z, Guillermo	Main Gym needs to be painted.					

Selected Da WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2023 - 2/29/2024 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Cost
Location:	Chaparra	alHS					
292864	A-Wing		1/18/2024		54		\$0.00
Medium	Work In Progress	Main Entry	1/18/2024 11:31:15 AN	1			
Ruiz, Danr Eli Barrios	-	Please install window tint on all the fint the main entry.(Ms. Lopez, Main Entr					
293026	Q-Wing	Restroom	1/23/2024		49	3	\$75.00
Medium	Work In Progress		1/23/2024 10:01:25 AN	1			
Pacheco, H		Q boys restroom is still clogged the w takes time to go down (to Flush). the work order # 290899 but the toilet is a	ere was another	2/29/24 Forward. To compressor gun and were not able to unc	snake:		nes
Christina N		Destroom	2/26/2024		15		<u>ቀ</u> ር ርር
294847	R-Wing	Restroom			15		\$0.00
Medium Pacheco, H	Work In Progress Hector	R-Building The boys restroom toilet is clogged.	2/26/2024 2:50:11 PM . (Ms. Norma, R-	I			
Eli Barrios		Building)					
294787	R-Wing		2/23/2024		18		\$0.0
Medium	Work In Progress	Bistro/R building	2/23/2024 2:24:45 PM	I			·
Ambriz, Jo	-	Cold air is being pumped into the roc Bistro R-Building)	om.(Ms. Garcia,				
Eli Barrios							
294798			2/23/2024		18		\$0.00
Medium	Work In Progress		2/23/2024 3:17:56 PM	I			
Hernande	z, Guillermo	Fire Sprinkler repairs identified durir inspection.	ng quarterly				
Guillermo	Hernandez						
294451			2/16/2024		25		\$0.0
Medium	Work In Progress		2/16/2024 12:49:54 PM	I			
Hernande	z, Guillermo	Install electrical power for portable re Field	estrooms - Baseball				
Guillermo	Hernandez						
295043	B-Wing	Classroom	2/29/2024		12		\$0.00
Medium	Work In Progress	B-	2/29/2024 8:41:09 AN	1			
Villalobos,	Margret	There are mice every where. (Ms.Lo Wing/Concession Stand/R-Wing)	pez, B-	2/29/24 Asp Mr. Sha Mikey - mkv	ine he w	ill contact	t
Eli Barrios							
Count: 22	Work Orders	Avg. Age of WO's 62	<u> </u>	Total for Chaparra	al HS	3	\$430.8

WOID Priority Assigned	Building Status To	Dates:7/1/2023 - 2/29/2024 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Cost: Labor Hours
Location:	Chaparra	MMS				
295107	Main Building	Classroom	2/29/2024		12	\$8,380.00
Medium	Work In Progress		2/29/2024 3:54:13 PM			
Ambriz, Jo	se	Need to installed mini ductless to c 355,200,206,405A,405B,102, Tea room				
Jose Amb	riz					
294868			2/27/2024		14	\$0.00
Medium	Work In Progress		2/27/2024 12:54:55 AM			
Flores, Pe	te	Monthly - Chaparral MS - Mower I PM schedule details.	M-CHS-0404 - Refer to			
Margret Vi			0///0004		- 10	.
293471	Main Building	Classroom	2/1/2024		40	\$0.00
Medium	Work In Progress		2/1/2024 9:37:25 AM			
Flores, Ant	tonio	Need to run electrical to the new 2 all classrooms for CMS, Thank you				
Jose Amb	riz		0/4/0004		40	\$ 0.00
293458			2/1/2024		40	\$0.00
Medium	Work In Progress		2/1/2024 7:51:15 AM			
Vasquez,	lose	Need paint softball. And baseball.	Fields			
Juan Varg	as					
294061			2/9/2024		32	\$0.00
Medium	Work In Progress		2/9/2024 8:32:53 AM			
Vasquez, J	lose	Need fix broken irrigation pvc pipe trees area	e on front palm s			
Juan Varg	as					
293824			2/6/2024		35	\$0.00
Medium	Work In Progress		2/6/2024 8:04:04 AM			
Hernande	z, Guillermo	Fire Sprinkler repairs identified du inspection.	ring quarterly			
	Hernandez					
288530		Classroom	10/10/2023		154	\$1,642.22
Medium	Work In Progress	100	10/10/2023 4:10:05 PM			
Ambriz, Jo	se	Need to installed a 2 ton ductless.	. f	projects installation 2	2 ton duc	tless
Jose Amb	riz					

Selected D	ate Range for Request		2/29/2024 Order By Log		,							
WOID	Building	Area	Deferred By	Until		Target Comp Date	Days	Labor	Costs			
Priority	Status	Area Number	Reason	Cr	eated Date/Time	Actual Comp Date	Aged	ed Hours				
Assigned	То	Description				Action Taken						
Requeste	r Name											
Location:	Desert P	ride HS										
293828					2/6/2024		35		\$0.00			
Medium	Work In Progress			2/6	/2024 8:09:15 AN	1						
Hernande	z, Guillemo	Fire Sprinkler reinspection - Bo	epairs identified duri xing	ng quarterly								
Guillermo	Hernandez											
Count: 1 V	Vork Orders	A	vg. Age of WO's 3	5	-	Total for Desert Prid	e HS	0	\$0.00			

WOID	ate Range for Request Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Costs
Priority	Status	Area Number	Reason	Cre	ated Date/Time	Actual Comp Date	Ageu	nou s	
Assigned Requester		Description				Action Taken			
•									
Location:	Desert Tr	ailES							
293473	Main Building	Hallway/Corrido	r		2/1/2024		40		\$0.00
Medium	Work In Progress	hallways		2/1/	2024 9:51:32 AM				
Villalobos	, Margret	We've been see	n a lot of large roach	nes in the ha	llways.				
Elizabeth I	Hernandez								
293822					2/6/2024		35		\$0.00
Medium	Work In Progress			2/6/	2024 8:01:48 AM				
Hernande	z, Guillermo	Fire Sprinkler re inspection.	pairs identified duri	ng quarterly					
Guillermo	Hernandez								
291663	Main Building	Classroom			12/15/2023		88		\$0.00
Medium	Work In Progress	416		12/15/	2023 1:10:28 PM				
Villalobos	, Margret	Treatmentneed	ed in portable 416 d	lue to mice.		EM Lorraine to servi	ce on 1/2	/24	
Elizabeth I	Hernandez								
295089					2/29/2024		12		\$0.00
Medium	Work In Progress			2/29/	2024 2:22:02 PM				
Vasquez, .	lose	Need fix 3 sta have 1 broken tr	tions irrigation. Lin eesbobbler	e not on an	d line 5				
Juan Varg	as								
Count: 4 V	Vork Orders	Α	vg. Age of WO's 4	4		Total for Desert Tra	il ES	0	\$0.00

Selected Da WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By	Until R	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Vi	ew ES							
294877	Main Building	Cafeteria			2/27/2024		14	2.5	\$62.50
Medium	Work In Progress			2/27/202	24 8:54:24 AN	I			
Herrera, M	larin	The 90 degree ramp came off.	angle trim that goes	on the side of th	e	As per Jesus, route	to Marin		
Israel Orte	ga								
294456					2/16/2024		25		\$0.00
Medium	Work In Progress			2/16/202	24 1:50:55 PM				
Hernande	z, Guillemo	Fire Sprinkler re	epairs identified duri	ing quarterly					
Guillermo	Hernandez								
291914					1/1/2024		71		\$0.00
Medium	Work In Progress			1/1/202	4 1:59:19 AM				
Flores, Pe	te	Monthly - Dese to PM schedule	ert View - UV-DV-051 e details.	6 PM Service -	Refer				
Margret Vil	lalobos								
289584					11/1/2023		0	0.5	\$12.50
Medium	Work In Progress			11/1/202	3 1:05:05 AM	11/1/2023			
Flores, Per Margret Vil		Monthly - Dese PM schedule d	ert View ES - Mower etails.	M-DV-0522 - Re	efer to	mower 0522 is d-13 mower identified in mower is a z-950.			
289240					10/25/2023		139		\$0.00
Medium	Work In Progress	All Exterior		10/25/202	23 8:55:46 AM	I			
Hernande	z, Guillermo		or doors beige. Plea ny questions (575) 88			Re-route to Memo.	thank you	l	
Cynthia Ma	aes								
292830					1/17/2024		38		\$962.70
Medium	Work In Progress			1/17/202	4 3:57:54 PM	2/24/2024			
Chavez, S	antos	Need to replace	e batteries in the inve	erter.					
Santos Ch	avez								
	Vork Orders	Δ	vg. Age of WO's 4	8		Total for Desert Vie		3 4	61,037.70

Selected Da	ate Range for Request Building	Dates:7/1/2023 - 2/29/2024 Order By Area Deferred By	Location, Status Until Request Date Targe	t Comp Date Days	Labor	Total Costs
Priority	Status	Area Number Reason	Created Date/Time Actua	A rin al	Hours	
Assigned		Description		Action Taken		
Requeste	r Name	·				
Location:	GAC					
285526			8/17/2023	208		\$0.00
Medium	Work In Progress		8/17/2023 8:15:53 AM			
Hernande	ez, Guillermo	GAC Kitchen Hood Demolition a Sandoval Construction	nd Improvements by			
Guillermo	Hernandez					
294796			2/23/2024	18		\$0.00
Medium	Work In Progress		2/23/2024 3:15:29 PM			
Hernande	z, Guillemo	Fire Sprinkler repairs identified d inspection.	luring quarterly			
Guillermo	Hernandez					
294738			2/22/2024	19		\$0.00
Medium	Work In Progress		2/22/2024 3:42:55 PM			
Flores, An	tonio	Check electrical outlets in the S Hernandez's office) at GAC for a large copiers from room 202. Ca have any questions.	possible transfer of			
Marisela C	Quezada					
Count: 3 V	Nork Orders	Avg. Age of WO's	82	Total for GAC	0	\$0.00

WOID Priority Assigned		Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Cost
Location:	Gadsden	ES						
294935		Office		2/28/2024		13		\$0.00
Medium	Work In Progress			2/28/2024 7:35:40 AN	Λ			
Tellez, Hec	ctor	Florescent ligh out. Please ass Thank you,	t bulb in front of the sist.	cafeteria doors are				
Patty Madr	id							
294951		Kitchen		2/28/2024		13		\$0.00
High	Work In Progress			2/28/2024 8:50:08 AN	Л			
Ontiveros,	Joe	Mop sink is crac	cked					
Dino Facio	0							
294564				2/20/2024		21		\$0.00
Medium	Work In Progress			2/20/2024 9:01:07 AN	Λ			
Villalobos,	, Margret	Please get top at Gadsden ES		to take care of gophers	2/20/24 Asp Mr. Shane, Mike	y will be	gintreatme	ent
Shane Sm	lythe				this weekend.			
294639		Classroom		2/21/2024		20		\$0.00
Medium	Work In Progress	206		2/21/2024 8:17:03 AN	Λ			
Tellez, Hec	ctor	in my classroor	e if I could place a v n. This particular lig others being on. roo					
Patty Madr	id							
295090		Office		2/29/2024		12		\$366.24
Medium	Work In Progress			2/29/2024 2:23:31 PM	1			
Tellez, Heo	ctor	Stage lights do	not work. Please a	assist Thank you,				
Patty Madr	id							
294898		Classroom		2/27/2024		14		\$0.00
Medium	Work In Progress	206		2/27/2024 12:27:49 PM	1			
Tellez, Hec	ctor	There is anothe is going out. room 206	er light in my classro	oom that seems like it				
Patty Madr	id							
291528		Classroom		12/13/2023		90		\$0.00
Medium	Work In Progress	207		12/13/2023 7:36:48 AN	Л			
Villalobos,	, Margret	Classroom 207	' insects (roaches) i	n the classroom.				
Patty Madr	id							
Count: 7 W	Vork Orders	A	vg. Age of WO's	26	Total for Gadsde	n ES	0	\$366.24

WOID Priority	ite Range for Request Building Status	Area Area Number	Deferred By		-	Days Aged	Labor Hours	Costs
Assigned 1		Description			Action Taken			
Requester								
Location:	Gadsden	HS						
291603	North Building	Kitchen		12/14/2023		89		\$0.00
Medium	Work In Progress	207 and 208		12/14/2023 10:03:30)			
Villalobos,	Margret	pest (mice) trap precautionary r eliminate rode CLASSROOM CLASSROOM NORTH BLDG already been a	es replaced and an neasures to be tak nts and pests in S #207 and STORA #208 which both a , an "Emergency V	en to prevent and to TORAGE and KITCHEN GE and KITCHEN are located in the Waiver for Schools" as and attached to email	EM Bugout 12/14/23			
Laura Gom	nez							
291904				12/31/2023		72		\$0.00
Medium	Work In Progress			12/31/2023 1:33:51 AM	1			
Flores, Pet	te	Yearly - Gadsd PM schedule d		GHS-0412 - Refer to				
Margret Vil	lalobos							
292164	Business	Classroom		1/5/2024		67		\$0.00
Medium	Work In Progress	619		1/5/2024 3:30:21 PN	1			
Hernandez	z, Carlos	CLASSROOM		rnandez, the blinds in e SCIENCE BLDG., ed, thank you.	ordered blind on 1/8/	24		
Laura Gom	nez							
290331				11/14/2023		119		\$0.00
Medium	Work In Progress	WeightRoom		11/14/2023 8:59:02 AM	1			
Ontiveros,	Joe	in the WEIGHT weekend and c	ROOM FACILITY reated a minor flo ak. If this can be lo	water fountain located had been leaking all od. The water fountain boked at asap and				
Laura Gom	nez							
290340				11/14/2023		119		\$0.00
Medium	Work In Progress			11/14/2023 9:53:37 AN	1			
Flores, Pet	te	tiller for ground	s needs repair					
Carlos He	rnandez							
290369		Cafeteria		11/14/2023		119		\$0.00
Medium	Work In Progress			11/14/2023 2:43:03 PM	1			
Smythe, Sł	hane	The cement lid	is deteriorating. No pvehicles off mea					
	chneider							

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	2/29/2024 Order By L Deferred By Reason	Until Request Dat	e Target Comp Date e Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS						
290689	Library	Library		11/28/202	23	105		\$0.00
Medium	Work In Progress	LIGHTS		11/28/2023 10:32:	11			
Tellez, Hec	-	noticing that th LIGHT are not v		ARY near the SKY be replaced. Can				
Laura Gon	nez							
291257				12/6/202	23	97		\$0.00
Medium	Work In Progress			12/6/2023 12:55:45 P	M			
Hernandez	z, Guillermo	Remove 4" altit	ude valve					
Edward So	hneider							
291496		Exterior		12/12/202	23	91		\$0.00
Medium	Work In Progress	Various Areas		12/12/2023 9:36:19 A	M			
Tellez, Hec		CTE and Admir working. Large outdoor cafeteria is out Lights on shed	n building. Currentl ight just infront of th needs to be replace	ed. CTE building, some of				
Laura Gon	nez							•
285790				8/22/202	23	203		\$528.84
Medium	Work In Progress			8/22/2023 9:35:27 A	M			
Tellez, Hec	tor	several lights ir seconds and th	the library that cor en flicker out. He b	for Library-There are ne on only for a few selieves it is a wiring st for help with this	Asp report 10/16/23	- materia	al on order	
Velia Alarc	on							
284811				8/7/202	23	218		\$0.00
Medium	Work In Progress			8/7/2023 12:45:48 P	M			
Flores, Pet	e	need tillers rep	aired					
Carlos He	rnandez							
289255	Community	Restroom (Girl	s)	10/25/202	23	139		\$0.00
Medium	Work In Progress	WeightRoom		10/25/2023 10:14:	29			
Ontiveros,	Joe	located in the OROOM is leaking	vater to that sink to	l in the WEIGHT dians went ahead and				
Laura Gon								

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2023 - 2/29/2024 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
289274	Business	Classroom	10/25/2023		139		\$0.00
Medium	Work In Progress	600	10/25/2023 1:27:41 PM				
Ontiveros,	Joe	Requested per Ms. Favela, she several of the sinks in her classro some faucets. She is located in th (BUSINESS BLDG) ROOM #600 repaired as soon as possible, that	oom leaking along with ne SCIENCE BLDG). Can this please get				
Laura Gon	nez						<u> </u>
288165			10/1/2023		163		\$0.00
Medium	Work In Progress		10/1/2023 1:50:54 AM				
Flores, Pet	te	Monthly - Gadsden HS - GHS-U Refer to PM schedule details.	V-0515 PM Service -				
Margret Vil	lalobos						
288271		Football Field	10/3/2023		161	1	\$128.53
Medium	Work In Progress	Guest	10/3/2023 3:45:33 PM				
Ontiveros,	Joe	Requested per Mr. Lugo, the wa FOOTBALL FIELD BATHROOM, and need to be repaired. Please you. Photo attached.	AREA are NOT working	Reroute to plumbing Supervisor	g. ASP Jo	ose A. Hva	с
Laura Gon	nez						
289167			10/24/2023		140		\$0.00
Medium	Work In Progress		10/24/2023 12:38:50				
Flores, Pet	le	Monthly - Gadsden HS - Mower PM schedule details.	M-GHS-0413 - Refer to				
Margret Vil	lalobos						
290238			11/13/2023		120		\$0.00
Medium	Work In Progress		11/13/2023 7:35:37 AM				
Tellez, Heo	ctor	pole was hit check for integrity					
Hector Tel	lez						
289920	-		11/6/2023		127		\$0.00
Medium	Work In Progress		11/6/2023 12:57:12 AM				
Flores, Pet	-	Monthly - Gadsden HS - GHS-U schedule details.	V-0927 - Refer to PM				
Margret Vil	lalobos	-					
292822			1/17/2024		55		\$0.00
Medium	Work In Progress		1/17/2024 3:34:29 PM				
Tellez, Heo	-	need t5 lamps for 2x2 fixtures in atrium	GHS varsity gym				
Hector Tel	107						

Location: Gadsden HS 292899 New Admin Bldg Restroom (Girls) 1/19/2024 8:25:33 AM 119/2024 8:25:33 AM The LIGHT on the LEFT HAND side above the sink seems to going out in the GRLS RESTROM in the NEW ADMIN BLDG, will flicker and go out, come back on and off, can it please be replaced, thank you. reroute to electrician. Laura Gomez 293010 New Admin Bldg Office 1/23/2024 49 Medium Work In Progress Attendance 1/23/2024 8:56:21 AM Approved EM Lorraine 1/24/24 Villalobos, Margret Requested per Hilda Hernandez, there was a rodent spotted but was not able to to be caught, we need traps set and any other precautionary measures that can be taken to precent any more pessivodents, LOCATED in the ADMIN BLDG./MTENDANCE OFFICE, COPY or SIGNED WAIVER is ATTACHED, thank you. Approved EM Lorraine 1/24/24 Laura Gomez 1/23/2024 3:09:41 PM 49 Medium Work In Progress 1/23/2024 3:09:41 PM De Leon, Clarissa Troubleshoot/Pull GHS Fire Protection well for a shortage 50-600000000000000000000000000000000000		•	Target Comp Date Days Actual Comp Date Aged Action Taken		2/29/2024 Order By Loc Deferred By Reason	Area Area Number Description	Building Status To	WOID Priority Assigned
Medium Work In Progress 1/19/2024 8:25:33 AM Tellez, Heck The LIGHT on the LEFT HAND side above the sink seems to going out in the GIRLS RESTROVM in the NEW ADMINI BLOG, will flicker and go out, come back on and off, can it please be replaced, thank you. reroute to electrician. Laura Gomez 293010 New Admin Bldg Office 1/23/2024 49 Medium Work In Progress Attendance 1/23/2024 8:56:21 AM Approved EM Lorraine 1/24/24 Villalobos, Margret Requested per Hilda Hernandez, there was a rodent spotted but was not able to to be caught, we need traps set and any other precentany more pest/fordents, LOCATED in the ADMIN BLDG., ATTENDANCE OFFICE, COPY of SIGNED WAIVER is ATTACHED, thank you. Approved EM Lorraine 1/24/24 Laura Gomez 1/23/2024 49 Medium Work In Progress 1/23/2024 3:09:41 PM De Leon, Clarissa Troubleshoot/Pull GHS Fire Protection well for a stortage Stortage Clarissa D Leon 1/24/2024 8:42:58 AM 48 Midj Work In Progress 3compartment sink drain leaking 1/24/2024 Din Facio 2/6/2024 35 3compartment sink drain leaking 3compartment sink drain leaking Din Facio 2/6/2024 8:03:08 AM Fire Sprinkler repairs identified during quarterly inspection.						HS	Gadsden	Location:
Tellez, Hector The LIGHT on the LEFT HAND side above the sink seems to going out in the GIRLS RESTROOM in the NEW ADMIN BLDG., will flicker and go out, come back on and off, can it please be replaced, thank you. reroute to electrician. Laura Gomez 233010 New Admin Bldg Office 1/23/2024 49 Medium Work In Progress Attendance 1/23/2024 S:56:21 AM Approved EM Lorraine 1/24/24 Villalobos, Margret Requested per Hilda Hernandez, there was a rodent spotted but was not able to to be caught, we need traps set and any other precautionary more pastryfordents, LOCATED in the ADMIN BLDG, /ATTENDANCE OFFICE, COPY of SIGNED WAIVER is ATTACHED, thank you. Approved EM Lorraine 1/24/24 Laura Gomez 1/23/2024 3:09:41 PM 49 Medium Work In Progress Troubleshoot/Pull GHS Fire Protection well for a shortage 49 De Leon, Clarissa Troubleshoot/Pull GHS Fire Protection well for a shortage 49 Clarissa De Leon 1/24/2024 8:42:58 AM 48 Migh Work In Progress 3-compartment sink drain leaking 5 Din Facio 2/6/2024 8:03:08 AM 5 5 23823 2/6/2024 8:03:08 AM 5 5 Medium Work In Progress 2/6/2024 8:03:08 AM 5 Medium	\$456.99	3	53	1/19/2024	s)	Restroom (Girl	New Admin Bldg	292899
seems to going out in the GIRLS RESTROOM in the NEW ADMIN BLDG, will flicker and go out, come back on and off, can it please be replaced, thank you.Laura Gomez1/23/202449MediumWork In ProgressAttendance1/23/2024 8:56:21 AMVillalobos, MargretRequested per Hilda Hernandez, there was a rodent spotted but was notable to to be cought, we need traps set and any other precautionary measures that can be taken to precent any more pests/rodents, LOCATED in the ADMIN BLDG, AITTENDANCE OFFICE, COPY of SIGNED WAIVER is ATTACHED, thank you.Approved EM Lorraine 1/24/24Laura Gomez1/23/202430:941 PM2930531/23/2024 3:09:41 PM49MediumWork In ProgressTroubleshoot/Pull GHS Fire Protection well for a shortage1/23/2024 3:09:41 PMDe Leon, ClarissaTroubleshoot/Pull GHS Fire Protection well for a shortage1/24/2024 8:42:58 AM48HighWork In ProgressGicture tisk drain leaking48Dino Facio2/6/2024 8:03:08 AM1/24/2024 8:42:58 AMDino Facio2/6/2024 8:03:08 AM1Earand Cuillermo2/6/2024 8:03:08 AM1Hernandez, GuillermoFire Sprinkler repairs identified during quarterly inspection.2/6/2024 8:03:08 AM1Earand De ternandezFire Sprinkler repairs identified during quarterly inspection.2/6/2024 8:03:08 AM1			1	1/19/2024 8:25:33 AM			Work In Progress	Medium
293010 New Admin Bidg Office 1/23/2024 49 Medium Work In Progress Attendance 1/23/2024 8:56:21 AM Villalobos, Margret Requested per Hilda Hernandez, there was a rodent spotted but was not able to to be caught, we need traps set and any other precautionary measures that can be taken to precent any more pest/srodents, LOCATED in the ADMIN BLDG./ATTENDANCE OFFICE, COPY of SIGNED WAIVER is ATTACHED, thank you. Approved EM Lorraine 1/24/24 Laura Gomez 1/23/2024 49 Medium Work In Progress 1/23/2024 3:09:41 PM De Leon, Clarissa Troubleshoot/Pull GHS Fire Protection well for a shortage 1/24/2024 Ontiveros, Joe 3-compartment sink drain leaking 1/24/2024 48 High Work In Progress 1/24/2024 8:42:58 AM 49 Ontiveros, Joe 3-compartment sink drain leaking 2/6/2024 35 Dino Facio 2/6/2024 8:03:08 AM 49 Hernandez, Guillermo Fire Sprinkler repairs identified during quarterly inspection. 35 Medium Work In Progress 2/6/2024 8:03:08 AM 48			reroute to electrician.	STROOM in the go out, come back	out in the GIRLS RELDG., will flicker and	seems to going NEW ADMIN B	ctor	Tellez, Heo
Medium Work In Progress Attendance 1/23/2024 8:56:21 AM Villalobos Margret Requested per Hilda Hernandez, there was a rodent softwarp recautionary measures that can be taken to precent any more pests/rodentis, LOCATED in the ADMIN BLDG, /ATTENDANCE OFFICE, COPY of SIGNED WAIVER is ATTACHED, thank you. Approved EM Lorraine 1/24/24 Laura Gomez 1/23/2024 3:09:41 PM 49 Medium Work In Progress Troubleshoot/Pull GHS Fire Protection well for a shortage 1/23/2024 3:09:41 PM De Leon Troubleshoot/Pull GHS Fire Protection well for a shortage 1/24/2024 4:42:58 AM 49 Ontiveros Stortage 2/6/2024 3:09:41 PM 1/24/2024 4:42:59 AM Ontiveros Troubleshoot/Pull GHS Fire Protection well for a shortage 1/24/2024 4:42:58 AM Ontiveros Gom partment sink drain leaking 1/24/2024 8:42:58 AM 1/23/2024 3:09:41 PM Ontiveros Stortage 2/6/2024 8:03:08 AM 1/23/2024 8:42:58 AM 1/23/2024 8:42:58 AM Ontiveros Stortage 2/6/2024 8:03:08 AM 1/23/2024 8:42:58 AM								Laura Gon
Villalobos, MargretRequested per Hilda Hernandez, there was a rodent spotted but was not able to to be caught, we need traps set and any other precautionary measures that can be taken to precent any more pests/rodents, LOCATED in 	\$0.00	19	49	1/23/2024		Office	New Admin Bldg	293010
spotted but was not able to to be caught, we need traps set and any other precautionary measures that can be taken to precent any more pests/rodents, LOCATED in the ADMIN BLDG.,/ATTENDANCE OFFICE, COPY of SIGNED WAIVER is ATTACHED, thank you.Laura Gomez1/23/2024492930531/23/2024 3:09:41 PMDe Leon, ClarissaTroubleshoot/Pull GHS Fire Protection well for a shortage1/24/2024Clarissa De LeonKitchen1/24/2024293101Kitchen1/24/2024 8:42:58 AMOntiveros, Joe3-compartment sink drain leakingDino Facio2/6/2024352938232/6/2024 8:03:08 AMHernandez, GuillermoFire Sprinkler repairs identified during quarterly inspection.35Guillermo Hernandez2/1/202440			1	1/23/2024 8:56:21 AM		Attendance	Work In Progress	Medium
2930531/23/202449MediumWork In Progress1/23/2024 3:09:41 PMDe Leon, ClarissaTroubleshoot/Pull GHS Fire Protection well for a shortageClarissa De Leonshortage293101Kitchen293101KitchenMediumNork In Progress3-compartment sink drain leakingDino Facio2938232/6/2024 8:03:08 AMHernandez, GuillermoFire Sprinkler repairs identified during quarterly inspection.Guillermo Hernandez2/1/2024293467Grounds ShopExterior2/1/202440		/24/24	Approved EM Lorraine 1/24/2	ught, we need traps asures that can be Jents, LOCATED in DFFICE, COPY of	s not able to to be ca er precautionary me nt any more pests/ro DG.,/ATTENDANCE	spotted but wa set and any oth taken to precer the ADMIN BL	Margret	Villalobos,
Medium Work In Progress 1/23/2024 3:09:41 PM De Leon, Clarissa Troubleshoot/Pull GHS Fire Protection well for a shortage Clarissa De Leon shortage 293101 Kitchen 1/24/2024 High Work In Progress 1/24/2024 8:42:58 AM Ontiveros, Joe 3-compartment sink drain leaking Dino Facio 2/6/2024 8:03:08 AM Yernandez, Guillermo Fire Sprinkler repairs identified during quarterly inspection. Guillermo Hernandez Fire Sprinkler repairs identified during quarterly inspection. 293467 Grounds Shop Exterior							nez	Laura Gon
De Leon, ClarissaTroubleshoot/Pull GHS Fire Protection well for a shortageClarissa De Leon293101Kitchen293101KitchenHighWork In ProgressOntiveros, Joe3-compartment sink drain leakingDino Facio2938232/6/2024MediumWork In ProgressMediumWork In ProgressFire Sprinkler repairs identified during quarterly inspection.Guillermo HernandezExterior293467Grounds ShopExterior2/1/20242010242/1/20242024440	\$0.00	19	49	1/23/2024				293053
Shortage Clarissa De Leon 293101 Kitchen High Work In Progress Ontiveros, Joe 3-compartment sink drain leaking Dino Facio 2/6/2024 293823 2/6/2024 8:03:08 AM Hernandez, Guillermo Fire Sprinkler repairs identified during quarterly inspection. Guillermo Hernandez 2/1/2024 293467 Grounds Shop			l	1/23/2024 3:09:41 PM			Work In Progress	Medium
293101Kitchen1/24/202448HighWork In Progress1/24/2024 8:42:58 AM48Ontiveros, Joe3-compartment sink drain leaking1/24/2024 8:42:58 AMDino Facio3-compartment sink drain leaking1/24/2024 8:42:58 AM2938232/6/202435MediumWork In Progress2/6/2024 8:03:08 AMHernandez, GuillermoFire Sprinkler repairs identified during quarterly inspection.1/24/2024 8:03:08 AMGuillermo Hernandez2/3467Grounds ShopExterior293467Grounds ShopExterior2/1/202440				on well for a	Pull GHS Fire Protecti		Clarissa	De Leon, C
HighWork In Progress1/24/2024 8:42:58 AMOntiveros, Joe3-compartment sink drain leakingDino Facio2938232/6/20242938232/6/2024 8:03:08 AMMediumWork In Progress2/6/2024 8:03:08 AMHernandez, GuillermoFire Sprinkler repairs identified during quarterly inspection.Guillermo Hernandez293467Grounds ShopExterior2/1/202440							e Leon	Clarissa D
Ontiveros, Joe3-compartment sink drain leakingDino Facio2/6/20242938232/6/2024 8:03:08 AMMediumWork In Progress2/6/2024 8:03:08 AM2/6/2024 8:03:08 AMHernandez, GuillermoFire Sprinkler repairs identified during quarterly inspection.Guillermo HernandezExterior293467Grounds ShopExterior2/1/20242/1/202440	\$0.00	18	48	1/24/2024		Kitchen		293101
Dino Facio 2/6/2024 35 293823 2/6/2024 8:03:08 AM 35 Medium Work In Progress 2/6/2024 8:03:08 AM Hernandez, Guillemo Fire Sprinkler repairs identified during quarterly inspection. 5 Guillermo Hernandez Exterior 2/1/2024 40			1	1/24/2024 8:42:58 AM			Work In Progress	High
2938232/6/202435MediumWork In Progress2/6/2024 8:03:08 AMHernandez, GuillermoFire Sprinkler repairs identified during quarterly inspection.1Guillermo Hernandez2/1/202440					tsink drain leaking	3-compartmen	Joe	Ontiveros,
Medium Work In Progress 2/6/2024 8:03:08 AM Hernandez, Guillermo Fire Sprinkler repairs identified during quarterly inspection. Guillermo Hernandez 293467 Grounds Shop Exterior)	Dino Facio
Hernandez, Guillemo Fire Sprinkler repairs identified during quarterly inspection. Guillermo Hernandez 2/1/2024 293467 Grounds Shop Exterior	\$0.00	35	35	2/6/2024				293823
inspection. Guillermo Hernandez 293467 Grounds Shop Exterior 2/1/2024 40			I	2/6/2024 8:03:08 AM			Work In Progress	Medium
293467 Grounds Shop Exterior 2/1/2024 40				ng quarterly	epairs identified duri	•	z, Guillermo	Hernande
							Hernandez	Guillermo
Medium Work In Progress 2/1/2024 9:28:24 AM	\$0.00	Ю	40	2/1/2024		Exterior	Grounds Shop	293467
5			ł	2/1/2024 9:28:24 AM			Work In Progress	Medium
Ontiveros, Joe Requesting line locate on West end and south end of Grounds shop for bollard installation. Post location and perimeter has been marked in white, thank you.				 Post location and 	or bollard installation	Grounds shop t	Joe	Ontiveros,
Jesus Avila							a	Jesus Avil

WOID Priority Assigned 1 Requester		Area Area Number Description	Deferred By	Until F	-	Target Comp Date Actual Comp Date Action Taken		Costs abor ours
Location:	Gadsden	HS						
293424					1/31/2024		41	\$38.04
Medium	Work In Progress			1/31/202	4 12:48:13 PM			
Avila, Jesu	IS	apart starting fr rear south east	blease install 3" pipe ont north west corne corner to fence line sk Clarissa or ED fo	er to fence line a at grounds sho	ınd p.			
Edward Sc	chneider							
293287		Exterior			1/29/2024		43	\$0.00
Medium	Work In Progress			1/29/20	24 8:12:25 AM	l		
Flores, Pet		The tractor 551 and bolts	0 T-GHS-#0507 r	eeds a new bl	ade			
Jose Vasq	uez				1/29/2024		43	
293288				4 /00 /00			43	\$0.00
Medium	Work In Progress				24 8:34:52 AM			
Villalobos,	Jose	The pull bening	scrapper GHS #07	'04 needs a bra	cket	Re-route Joe GH 3/	1/24	
Jose Vasq	uez							
293911		Athletic Field			2/7/2024		34	\$0.00
Medium	Work In Progress			2/7/20	24 8:40:06 AM			
Vasquez, J	lose	Need to replace	e the baseball bases	s in the basebal	lfield			
Jose Vasq	uez							
294055		Athletic Field			2/9/2024		32	\$0.00
Medium	Work In Progress			2/9/20	24 7:59:24 AM			
Hernandez	z, Carlos		fence in the empty ivacy slats, (new ba		ecurty	2/15/24 Slats will be Vasquez - mkv	ordered by J	эе
Jose Vasq	luez							
294374	New Admin Bldg	Restroom (Girl	s)		2/15/2024		26	\$0.00
Medium	Work In Progress			2/15/202	24 11:12:12 AM	l		
Tellez, Hec	ctor	ADMIN BLDG.,	GIRLS RESTROOM is flickering and ne ne RIGHT HAND SI	eds to be repla	aced. It	reroute to electriciar	1	
Laura Gom	-							
294386	Academic Bldg	Classroom			2/15/2024		26	\$496.13
Medium	Work In Progress	room 315		2/15/20	24 2:44:22 PM			
Ambriz, Jo	se	Need to relocat	e return duct in roor	n 315.				
	riz							

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2023 - 2/29/2024 Order By Area Deferred By Area Number Reason Description	Until Request D	ate Target Comp Date me Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
294120			2/11/2	024	30		\$0.00
Medium	Work In Progress		2/11/2024 12:34:30	AM			
Gonzalez,	Javier	Monthly - GHS - Football Field G Refer to PM schedule details.	rooming (Monthly) -				
Margret Vi	llalobos						
294169	Varsity Gym		2/12/2)24	29		\$4.30
Medium	Work In Progress	Boys Baseball	2/12/2024 8:59:46	AM			
Hernande	z, Carlos	Requested per Ms. Perry, the loc BASEBALL LOCKER RM located need to be repaired. Photos are a be broken and cannot be locked.	d in the VARSITY GYM attached. They seem to	ordered handles			
Laura Gor	nez						
295074			2/29/2	024	12		\$0.00
Medium	Work In Progress	Annex Washer	2/29/2024 11:51:37	AM			
Ontiveros,	Joe	Requested per Ms. Posada, the ANNEX is not working properly a and possibly repaired. It is not cyc items are staying wet, thank you	nd needs to be looked cling the water and	reroute to plumber			
Laura Gor	nez						
294450			2/16/2	024	25		\$0.00
Medium	Work In Progress		2/16/2024 12:48:57	PM			
Hernande	z, Guillermo	Install electrical power for portable Field	le restrooms - Baseball				
	Hernandez		- ((-				
294793			2/23/2	024	18		\$0.00
Medium	Work In Progress		2/23/2024 3:03:25	PM			
Hernande	z, Guillemo	Need to install a door to divide the grade in the hallway of the Old Ma					
	Hernandez		- ((-				
294704	Vocational		2/22/2		19		\$0.00
Medium	Work In Progress		2/22/2024 9:55:25	AM			
Flores, Pe	te	Requested per Ms. Perry, the CC the CTE/VOCATIONAL BLDG., is please be looked at and repaired unable to be repaired, please let	s not working. Can this I if possible if it is	reroute to pete autos	shop		
Laura Gor	nez						
Count: 38	Work Orders	Avg. Age of WO's	79	Total for Gadsde	n HS	1 \$´	1,652.83

Selected Da	ate Range for Request Building	Dates:7/1/2023 - 2	2/29/2024 Order By Lo Deferred By	cation, Status Until	Request Date	Target Comp Date	Davs	Labor	Total Costs
Priority	Status	Area Number	•		-	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Gadsden	MS							
294884					2/27/2024		14		\$0.00
Medium	Work In Progress	Athletic		2/27/20)24 10:15:13 AN	I			
Vasquez, .	Jose		tor and gas to be de e track meet at Gao		Sat/Mar	reroute to joe vasque generator.	ez he is g	jetting	
		Thank you							
Terry Alvar	rado								
293343		Cafeteria			1/30/2024		42		\$145.00
Medium	Work In Progress	Cafeteria		1/30/2	2024 8:05:38 AN	l			
Tellez, He	ctor	flickeringlighti	n the cafeteria, mak	kes your eyes h	nurt.				
Hilda Adle	er								
292091		Kitchen			1/4/2024		68		\$0.00
High	Work In Progress			1/4/2	024 2:47:52 PM				
Tellez, He	ctor	Ceiling light ou	t going into storage	room area					
Dino Facio	0								
292585		Athletic Field			1/11/2024		61		\$0.00
Medium	Work In Progress			1/11/2	024 3:46:17 PM				
Lucero, Mi	ichael		tice softball field in t that needs red dirt a						
Jose Vaso	•								
Count: 4 V	Nork Orders	Δ	vg. Age of WO's	46		Total for Gadsde	n MS	0	\$145.00

WOID	ate Range for Request Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Labor	Costs
Priority	Status	Area Number		Crea	ted Date/Time	Actual Comp Date	Aged Hours	
Assigned	То	Description				Action Taken		
Requeste	r Name							
Location:	La Union	ES						
290769	Main Building	Classroom			11/29/2023		104	\$0.00
Medium	Work In Progress	MS.		11/2	9/2023 11:47:26	6		
Ontiveros,	,Joe		DILET & SINK THAT OM RESTROOM IN		1.			
Virginia G	alindo							
289995	Main Building				11/6/2023		127	\$0.00
Medium	Work In Progress	MS.		11/6/2	023 3:08:11 PN	1		
Ontiveros,	, Joe	AREA FOR STL	SS ROOM FOR INS JDENTS TO WASH NSURE THAT SINK	I THEIR HAND	SAND			
Virginia G	alindo							
285403	Main Building	Restroom			8/15/2023		210	\$0.00
Medium	Work In Progress	MAIN		8/15/20	23 12:19:04 PN	1		
Hernande	z, Guillemo	UPPER GRADE MS. BARRAZA	DDEL BOYS RESTR E HALLWAY IN THE DISCUSSED WOR HE. THANK YOU.	E MAIN BUILD		Asp report 10/16/23	- Pending Quote	
Virginia G	alindo							
288900					10/18/2023		146	\$0.00
Medium	Work In Progress			10/18/2	2023 9:17:04 AM	1		
Smythe, S	Shane	Renovation of N	Nurses office.					
Shane Sm	nythe							
Count: 4 V	Nork Orders	Α	vg. Age of WO's	147		Total for La Unio	on ES 0	\$0.00

Selected Da	ate Range for Request Building		Deferred By Loc	Until	Request Date	Target Comp Date	Days	Labor	Cost
Priority	Status	Area Number	•	Crea	ated Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Loma Lin	da ES							
286729	Main Building	Exterior			9/6/2023		188		\$0.00
Medium	Work In Progress	Outside of main	I	9/6/20)23 12:57:35 PN	1			
Hernande	z, Guillemo	Mr. Cardona is be removed.	requesting for the 2	dead pine t	rees to	reroute to memo			
Crystalee	Heredia								
293302					1/29/2024		43		\$0.00
Medium	Work In Progress			1/29/20)24 10:05:41 AM	1			
Hernande	z, Guillemo	Removal and di whiteboards.	sposal of blackboard	ds and instal	lation of				
Guillermo	Hernandez								
293230					1/26/2024		46		\$0.00
Medium	Work In Progress			1/26/2	2024 8:56:47 AN	1			
Hernande	z, Guillemo	Mr. Cardona is r and doors to be	equesting for the ent mirror tinted.	ire school, w	indows				
Guillermo	Hernandez								
294111	Main Building	Classroom			2/9/2024		32		\$0.00
Medium	Work In Progress	104/Casiano		2/9/2	2024 3:48:34 PN	1			
Tellez, He	ctor	Lights don't turn lockdowns or ot	off. Concerned about her situations.	ut safety for					
Crystalee	Heredia								
293829					2/6/2024		35		\$0.00
Medium	Work In Progress			2/6/2	2024 8:10:12 AN	1			
Hernande	z, Guillemo	Fire Sprinkler re inspection.	pairs identified durir	ng quarterly					
Guillermo	Hernandez								
Count: 5 V	Nork Orders	A	vg. Age of WO's 69			Total for Loma Lind	a ES	0	\$0.00

WOID Priority Assigned	Building Status To	Dates:7/1/2023 - 2/29/2024 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ac	- · · ·	iys Labor Jed Hours	Costs
Location:	North Val	ley ES				
288920			10/18/2023	14	6	\$0.00
Medium	Work In Progress		10/18/2023 11:22:15			
Hernande	z, Guillermo	Need to level the grass area.				
Guillermo	Hernandez					
285914			8/23/2023	20)2	\$0.00
Medium	Work In Progress		8/23/2023 3:16:32 PM			
Hernande	z, Guillermo	Install playground ages 2-5.	As	sp report 10/16/23 - Pe	ending PO	
Guillermo	Hernandez					
290909		Classroom	12/1/2023	10)2	\$2.25
Medium	Work In Progress	103	12/1/2023 11:35:16 AM			
Tellez, Heo	ctor	Need to replace lights in room 103				
Gloria Rey	/es					
294967		Classroom	2/28/2024	1	3	\$260.46
Medium	Work In Progress	303 & 306	2/28/2024 11:53:06 AM			
Ambriz, Jo	se	Room 303 and 306 the air keeps r does not shut off.	unning cold air. It			
Gloria Rey	/es					
294763		Mechanical	2/23/2024	1	8	\$224.48
Medium	Work In Progress		2/23/2024 8:12:11 AM			
Tellez, Heo	ctor	Need to reconnect the power supp system condenser, and inside air ha phase need to converted it to single	andler is a three			
Jose Amb	riz					
294449			2/16/2024	2	25	\$0.00
Medium	Work In Progress		2/16/2024 12:47:22 PM			
Hernande	z, Guillermo	Fire Sprinkler repairs identified dur inspection.	ing quarterly			
	Hernandez					
294662			2/21/2024	2	20	\$0.00
Medium	Work In Progress		2/21/2024 1:46:35 PM			
Tellez, Heo	ctor	We need to add receptacles to the A office.	Assistant Principal's			
Gloria Rey	100					

200			1091000 (1	10001	icarj				Total
Selected Da	ate Range for Request Building	Dates:7/1/2023-2 Area	2/29/2024 Order By Loc Deferred By	ation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Crea	ated Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Northern	On-Track Pre-	((LM)						
294931					2/28/2024		13		\$0.00
Medium	Work In Progress			2/28/2	2024 7:20:22 AM	1			
Ontiveros	, Joe	0	in room #114. The rig sing is leaking. (Dayca		main				
Sandy Silv	vas								
286821					9/8/2023		186		\$0.00
Medium	Work In Progress			9/8/2	2023 9:24:40 AN	1			
Ontiveros	,Joe		Irainage in girls bathro ay clogged up. Ask Ms		not	Asp report 10/16/23 talk to Russel - J. Or		is going to	
Sandy Silv	vas								
Count: 2 \	Work Orders	A	vg. Age of WO's 10	00	Total for North	ern On-Track Pre-K	(LM)	0	\$0.00

Selected Da WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2023 - 2/29/2024 Order By I Area Deferred By Area Number Reason Description	Location, Status Until Request Date Tar Created Date/Time Act		Labor Hours	Costs
Location:	Physical	Plant Complex				
288972	Motor Vehicle		10/19/2023	145		\$0.00
Medium	Work In Progress		10/19/2023 9:43:35 AM			
Flores, Pet	e	requesting service on Stihl chains	saw #4 (Pete Flores)			
Danny Car	rasco					
290588			11/27/2023	106		\$0.00
Medium	Work In Progress		11/27/2023 8:30:35 AM			
Ontiveros, Jose Villal		There is a water leak on the Nort bldg (outside).	11/2 sor out	ormed J. Ontiveros 8:30ar 28/23 Pending - Water is ne how when valve is ope of the relief drain pipe, ne I to follow pipe	off to A/C ened it come	es
292583		Athletic Field	1/11/2024	61		\$0.00
Medium	Work In Progress		1/11/2024 3:39:25 PM			
Vasquez, J	ose	We need fertilizer for STM, STH,	GH,GM,VM,CH			
Jose Vasq	uez					
291905			12/31/2023	72		\$0.00
Medium	Work In Progress		12/31/2023 1:33:52 AM			
Flores, Pet	e	Monthly - PPD - Mower M-PPDL PM schedule details.	0417,0435 - Refer to			
Margret Vil	lalobos					
291586			12/14/2023	89		\$0.00
Medium	Work In Progress		12/14/2023 7:52:16 AM			
Ontiveros,	Joe	Need Cable Snake Cutting Tips for Sanke.	or big Cable Services			
Joe Ontive	ros		0/0/0004			
293831			2/6/2024	35		\$0.00
Medium	Work In Progress		2/6/2024 8:11:51 AM			
Hernandez	z, Guillermo	Fire Suppression repairs needed STH, GHS, LU, BE, NV, AE and L				
	Hernandez			-		A <i>c</i> -
294285	Main Warehouse	Athletic Field	2/13/2024	28		\$0.00
Medium	Work In Progress		2/13/2024 3:57:54 PM			
Vasquez, J	ose	We need lime (chalk) for STH, GH	l and CH			

WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2023 - 2/29/2024 Order By Loc Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ac	-		Costs
Location:	Physical	Plant Complex				
294388			2/15/2024	20	6	\$0.00
Medium	Work In Progress		2/15/2024 3:14:30 PM			
Hernande	z, Guillermo	Need to replace fire extinguishers for GHS.LL, NV, VE.GE, AE.LU.	or GHS, CHHS,			
Guillermo	Hernandez					
293762			2/5/2024	3	6	\$0.00
Medium	Work In Progress	hvac tech tools	2/5/2024 8:31:38 AM			
Ambriz, Jo	ose	Need to request tools for Aron Solis				
Jose Amb	oriz					
293134			1/24/2024	4	3	\$0.00
Medium	Work In Progress	hvac shop	1/24/2024 2:37:25 PM			
Avila, Jesu	us	NEED TO MAKE A DISPLAY FRAM MINI DUCTLESS. THANK YOU	E STAND FOR A			
Jose Amb						
293047	Motor Vehicle		1/23/2024	49	9	\$0.00
Medium	Work In Progress		1/23/2024 2:23:05 PM			
Villalobos	s, Jose	Need to up grade old air compresso air lines for auto shop. Too much wa air lines and air compressor.				
Jose Villa	lobos					
294596			2/20/2024	2	1	\$0.00
Medium	Work In Progress		2/20/2024 2:47:23 PM			
Avila, Jesu	us	Requesting to restock Lawson hard	ware box.			
Jesus Avil	la					
294590			2/20/2024	2	1	\$0.00
Medium	Work In Progress		2/20/2024 1:59:24 PM			
Avila, Jesu	us	Requesting to order parts for chain I	ink fence stock.			
Jesus Avil	la					
294819	Purchasing	Athletic Field	2/26/2024	1	5	\$0.00
Medium	Work In Progress		2/26/2024 8:34:07 AM			
Vasquez,	Jose	We need sprinklers for all Elementa	ary Schools			
Jose Vaso	quez					
	Work Orders	Avg. Age of WO's 5	4 Total for Ph	ysical Plant Complex	0	\$0.00

WOID Priority Assigned	Building Status To	Dates:7/1/2023 - 2/29/2024 Order B Area Deferred By Area Number Reason Description		•	Days Labor Aged Hours	Costs
Location:	Riverside	ES				
294591	New Wing 1/02	Exterior	2/20/2024		21	\$56.96
Medium	Work In Progress		2/20/2024 2:02:28 PN	1		
Herrera, M	larin	SOLICITO BIRD SPIKES PARA PUERTA DE KINDER Y PARA L CAFETERIA.				
Norma On						
295066	New Wing 1/02	Restroom (Girls)	2/29/2024		12	\$0.00
Medium	Work In Progress		2/29/2024 11:09:34 AN	1		
Flores, Ant	tonio	En el bano de las ninas en kin no funciona	der el (air dry for hands)			
Norma On						
295051	Main Building	Portables	2/29/2024		12	\$0.00
Medium	Work In Progress	STEM LAB	2/29/2024 9:33:41 AM	1		
Lara, Ralp	h	Cabinets need to be rekeyed				
Claudia M	endez					
295053	Main Building	Classroom	2/29/2024		12	\$9.00
Medium	Work In Progress	Multiple areas	2/29/2024 9:35:22 AM	1		
Herrera, M	larin	Please help move paper produ storage room to new storage po				
		Thank you				
Claudia M	endez					
292614			1/12/2024		60	\$0.00
Medium	Work In Progress		1/12/2024 10:33:02 AM	1		
Herrera, M	larin	The fire truck in lower grade pla cracked and need to be replace		Re-route to Marin GH ON ORDER	1/18/24	
Marin Herr	era					
290370		Cafeteria	11/14/2023		119	\$0.00
Medium	Work In Progress		11/14/2023 2:44:34 PN	1		
Smythe, S	hane	Kitchen grease trap needs to be	e replaced.			
Edward So	chneider					
289740	Main Building	Exterior	11/3/2023		130	\$0.00
Medium	Work In Progress	Playground	11/3/2023 9:20:38 AN	1		
Hernande	z, Guillermo	please remove mary-go-round parking lot to stop the sand fron sidewalk.				
Claudia M						
Count: 7 V	Vork Orders	Avg. Age of WO'	s 52	Total for Riverside	ES 0	\$65.96

	ate Range for Request		•	•	•				Total Costs
WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	
Priority	Status	Area Number	Reason	Cr	eated Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	San Migu	el Special Serv	ices						
293006	Classrooms	Exterior			1/23/2024		49		\$0.00
Medium	Work In Progress			1/23	0/2024 8:40:58 AN	1			
Pacheco,	Hector		to disconnect wate going to be moved		verat				
Hector Pa	icheco								
295075					2/29/2024		12		\$0.00
Medium	Work In Progress			2/29/	2024 11:53:17 AM	1			
Hernande	ez, Guillemo	room 118 beca the windows to	technician to meas luse they need refle block the sunlight aging the students	ective tape to coming in. Th	be put on e				
Susie Rai	mos Lara								
Count: 2 V	Nork Orders	Α	vg. Age of WO's	31	Total for San	Miguel Special Serv	/ices	0	\$0.00

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2023 - 2/29/2024 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Tei	resa ES					
294682			2/21/2024		20		\$0.00
Medium	Work In Progress	OFFICE	2/21/2024 4:02:15 PM	1			
Flores, Ant	tonio	The top portion of the marquee whi is displayed needs a light bulb repl message area is working perfectly electrician needs to replace the ligh area. (Mrs. Martinez)	acement. The digital but it seems like the	Re-route to electricia	an thank	you	
Norma Ma	irtinez		0/5/0004				* •••••
293770			2/5/2024		36		\$0.00
Medium	Work In Progress	Soccer Fields	2/5/2024 9:11:51 AN	1			
Duenas, Jo	ose	We need help leveling the field for Coach Vasquez in portable B for in exactly the field needs to be leveled Vasquez)	structions on where				
Norma Ma	irtinez						
293839			2/6/2024		35		\$0.00
Safety	Work In Progress	Casa Roja	2/6/2024 9:39:27 AN	1			
Herrera, M	larin	The fire extinguisher located by the needs a new cover, the cover is br replaced. (Mrs. Martinez)		ON ORDER			
Norma Ma	ırtinez						
286920			9/11/2023		183		\$0.00
Medium	Work In Progress	Potable E (Ms.	9/11/2023 11:17:08 AN	1			
Herrera, M	larin	Please install a fiber optic corner sl with Ms. Diaz. Ms. Diaz has the op assistance to install it. (Ms. Diaz)		Still waiting on appro 9/12/23, 10/31/23	oval społ	ke with Me	mo
Norma Ma	irtinez						<u> </u>
288921			10/18/2023		146		\$0.00
Medium	Work In Progress		10/18/2023 11:25:18	3			
Hernande	z, Guillermo	Need to level the grass area.					
Guillermo	Hernandez						
290780			11/29/2023		104		\$0.00
Medium	Work In Progress		11/29/2023 3:15:13 PN	1			
Lara, Ralpl	h	As per Mr. S. Smythe approval, ple additional door to the nurse's office The door will be installed next to the (Mrs. Word)	e for safety purposes.				
Norma Ma	Intinez						
Count: 6 W	Vork Orders	Avg. Age of WO's	87 T	otal for Santa Teres	a ES	0	\$0.00

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2023 - 2/29/2024 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ac		Days Aged	Labor Hours	Costs
Location:	Santa Ter	resa HS					
290389			11/15/2023		118		\$0.00
Medium	Work In Progress		11/15/2023 12:27:20				
Flores, Pet	e	Yearly - Santa Teresa HS - Mower to PM schedule details.	M-STHS-0425 - Refer				
Margret Vil							
291198	Main Building	Classroom	12/5/2023		98		\$0.00
Medium	Work In Progress	501	12/5/2023 3:04:14 PM				
Ruiz, Dann	У	Please install blinds in classroom	Re	e-route to Danny R	uiz thanł	k you	
Ashley Villa	alobos-Trujillo						
289087	-		10/23/2023		141		\$0.00
Medium	Work In Progress		10/23/2023 12:40:42				
Flores, Pet	e	Monthly - Santa Teresa HS - STHS PM schedule details.	-UV-0916 - Refer to				
Margret Vil	lalobos						
288472			10/10/2023		154		\$0.00
Medium	Work In Progress		10/10/2023 8:59:50 AM				
Hernandez	z, Guillermo	Fire Sprinkler Repairs					
Guillermo	Hernandez						
293913		Athletic Field	2/7/2024		34		\$0.00
Medium	Work In Progress		2/7/2024 8:42:22 AM				
Vasquez, J	ose	There are a couple of bases that r the baseball field	need to be replace in				
Jose Vasq	uez						
294122			2/11/2024		30		\$0.00
Medium	Work In Progress		2/11/2024 12:34:32 AM				
Gonzalez,	Javier	Monthly - STHS - Football Field Gro Refer to PM schedule details.	ooming (Monthly) -				
Margret Vil	lalobos						
293796		PumpHouse	2/5/2024		36		\$0.00
Medium	Work In Progress		2/5/2024 3:41:03 PM				
Hernandez	z, Guillermo	Woud please check the injections p pumping fertilizer into the irrigation					
Jose Vasq	uez						
292880			1/18/2024		54		\$0.00
Medium	Work In Progress		1/18/2024 3:23:55 PM				
Ruiz, Dann	У	Need 1 pair of blinds for room 704 [measurements thank you	Danny Ruiz has the				
Marin Herr	era						

WOID Priority Assigned Requeste		Area Area Number Description	Deferred By Reason	-	e Target Comp Date e Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Ter	resa HS						
292679				1/16/202	24	56		\$0.00
Medium	Work In Progress	Nurses Office		1/16/2024 9:08:04 A	M			
Villalobos	, Margret		ervice as soon as po Nurse Rivera if need	ssible (found spiders) ded.	EM Lorraine 1/24/24	ļ		
Ashley Vill	alobos-Trujillo							
293223				1/26/202	24	46		\$0.00
Medium	Work In Progress			1/26/2024 8:11:08 A	M			
Hernande	z, Guillermo	Fire Sprinkler ro	epairs identified dur	ing quarterly				
	Hernandez							
293225				1/26/202	24	46		\$0.00
Medium	Work In Progress			1/26/2024 8:12:41 A	M			
Duenas, J	ose	uneven spots.	soil for Softball field Also if possible to ov grass growing again	er seed the outfield				
Marin Her	rera							
293229				1/26/202	24	46		\$39.59
Medium	Work In Progress			1/26/2024 8:22:58 A	M			
Duenas, J	ose	spots and if po	or baseball field to fil ssible to over seed again thank you					
Marin Her	rera							
294690		Athletic Field		2/22/202	24	19		\$0.00
Medium	Work In Progress			2/22/20247:56:06A	M			
Vasquez,	Jose	There is a broke	en sprinkler in stator	1#3				
Jose Vaso	quez							
294651	Main Building	Stairway		2/21/202	24	20		\$0.00
Medium	Work In Progress	Stair Case		2/21/2024 11:02:20 A	M			
Villalobos	, Margret	Black Widow w	eb, Spider was kille	d.	2/22/24 Approved El	MLorrair	ne-mkv	
Ashley Vill	alobos-Trujillo							
294432	Library	Library		2/16/202	24	25		\$0.00
Medium	Work In Progress	Library		2/16/2024 10:05:00 A	M			
Wieddian								

Selected Da	ate Range for Request Building	Dates:7/1/2023 - 2 Area	2/29/2024 Order By Loc Deferred By	,	e Target Comp Date	Days	Labor	Tota Costs
Priority	Status	Area Number	Reason	Created Date/Time	e Actual Comp Date	Aged	Hours	
Assigned	То	Description			Action Taken			
Requeste	r Name							
Location:	Santa Ter	esa HS						
294448				2/16/2024	4	25		\$0.00
Medium	Work In Progress			2/16/2024 12:45:40 PI	M			
Hernande	z, Guillemo	Install electrica West Field	l power for portable r	estrooms - East &				
Guillermo	Hernandez							
295058	Main Building	Classroom		2/29/2024	4	12		\$0.00
Medium	Work In Progress	603		2/29/2024 10:48:47 A	Μ			
Herrera, N	larin	Chairs are mis on.	sing screws and bolts	that hold the seat				
Ashley Vill	lalobos-Trujillo							
295065	Main Building	Classroom		2/29/2024	4	12		\$11.60
Medium	Work In Progress	311		2/29/2024 11:07:01 A	M			
Flores, An	tonio		ge several outlets hav rings are not secured	•				
Ashley Vill	lalobos-Trujillo							
Count: 18	Work Orders	A	vg. Age of WO's 54	f	Total for Santa Teres	a HS	0	\$51.19

WOID Priority Assigned			Deferred By			get Comp Date ual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Ter	resa MS							
294380		Kitchen		2/15/2	024		26		\$0.00
High	Work In Progress			2/15/2024 1:11:23	3 PM				
Pacheco, I	Hector	Floor drain in sa	lad bar area clogg	ed					
Dino Facio)								
294417	North Building	Exterior		2/16/2	024		25		\$13.12
Medium	Work In Progress	MORGANS		2/16/2024 8:29:04	4 AM				
Flores, Ant	tonio	NEED LIGHTIN SECURITY PUF	GOUTSIDE THE	MORGANS FOR					
Laura Pari	ra								
294418	South Building	Classroom		2/16/2	024		25		\$0.00
Medium	Work In Progress	UPPER LEVEL		2/16/2024 8:31:32	2 AM				
Smythe, S			MOVE STUDENT I ND THE LOCKERS E AND TRIM.		Re-	route to Shane S	S. thank y	/ou	
Laura Pari				0.11.0.12					.
294419	North Building	Hallway/Corrido	or	2/16/2	-		25		\$0.00
Medium	Work In Progress	UPPER LEVEL		2/16/2024 8:32:29	9 AM				
Smythe, S	hane		MOVE STUDENT I ND THE LOCKERS E AND TRIM.		Re-	route to Shane S	S. thank y	/ou	
Laura Pari				- (- (-					
294003	North Building	Classroom		2/8/2	024		16		\$0.00
Medium	Work In Progress			2/8/2024 11:15:01	AM	2/24/2024			
Chavez, S				numero 6 la mitad de sta demaciado oscuro					
Matilde Go	onzalez			9/18/2	022		176		\$0.00
287245 Medium	Work In Progress			9/18/2023 12:45:4 ⁻			170		φ 0 .00
Flores, Pe	-	Monthly - Santa PM schedule de		S-UV-0907 - Refer to					
Margret Vil	lalobos								
291258				12/6/2	023		97		\$0.00
Medium	Work In Progress			12/6/2023 12:57:30) PM				
Hernande	z, Guillermo	Replace boiler	oump and piping						
	, -								

	ate Range for Request		•	cation, Status				Total Costs
WOID	Building	Area	Deferred By	-	Target Comp Date	Days	Labor	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned		Description			Action Taken			
Requeste	rName							
Location:	Santa Ter	esa MS						
290388				11/15/2023	5	118		\$0.00
Medium	Work In Progress			11/15/2023 12:27:1	9			
Flores, Pe	ete	Yearly - Santa to PM schedule		M-STM-0416 - Refer				
Margret Vi	illalobos							
291572				12/13/2023	5	90		\$0.00
Medium	Work In Progress			12/13/2023 3:57:37 PM	Λ			
Duenas, J	lose	Need to level th	e football fields.					
Jose Due	nas							
291928	South Building	Classroom		1/2/2024	ļ	70		\$432.63
Medium	Work In Progress	ENTIRE SOUT	Н	1/2/2024 8:22:55 AM	Λ			
Ambriz, Jo	ose	HEATERS ARE	NOT ON IN THE SO	OUTH BUILDING.				
Laura Par	rra							
Count: 10	Work Orders	Α	vg. Age of WO's 6	7 1	otal for Santa Teres	a MS	0	\$445.75

WOID	Building Status	Area Area Number	2/29/2024 Order By Lo Deferred By	Until	-	Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Priority Assigned		Description	Reason	Crea		Action Taken	J * *		
Requester		Description				Action laken			
Location:	Sunland	Park ES							
292209					1/7/2024		65		\$0.00
Medium	Work In Progress			1/7/20	24 12:36:13 AN	1			
Flores, Pe	te	Monthly - Sunlato PM schedule	and Park ES - Mow e details.	er 0437, 0523	- Refer				
Margret Vi	llalobos								
286166					8/29/2023		196		\$7.92
Medium	Work In Progress			8/29/2	0237:43:46 AN	1			
Medium Duenas, J	5	clean the pass	g the storm drainpip age. While you are the exposed gas lin	e by the marqu at SP level the	lee and front	Asp report 10/16/23 will be starting later			
Duenas, J	5	clean the pass area and cover	age. While you are	e by the marqu at SP level the	lee and front	Asp report 10/16/23			
Duenas, J	ose	clean the pass area and cover	age. While you are	e by the marqu at SP level the	lee and front	Asp report 10/16/23 will be starting later			ero
Duenas, J Guillermo	ose	clean the pass area and cover	age. While you are	e by the marqu at SP level the he by the Morga	lee and front in	Asp report 10/16/23 will be starting later	this wee		ero
Duenas, J Guillermo 286168	ose Hernandez Work In Progress	clean the pass area and cover building. Please genera was feeding th Hector if you wa to the Morgan b	age. While you are the exposed gas lin	be by the marqu at SP level the be by the Morga 8/29/2 close the gas lin and keep going the gas line. P	ee and front n 8/29/2023 023 7:46:07 AN ne that g north lease	Asp report 10/16/23 will be starting later	this wee	k - M. Luc	
Duenas, J Guillermo 286168 Medium Pacheco, I	ose Hernandez Work In Progress	clean the pass area and cover building. Please genera was feeding th Hector if you way to the Morgan b close it from th	age. While you are the exposed gas lin te a work order to c e tenant at SP. alk by the marquee building you will see	be by the marqu at SP level the be by the Morga 8/29/2 close the gas lin and keep going the gas line. P	ee and front n 8/29/2023 023 7:46:07 AN ne that g north lease	Asp report 10/16/23 will be starting later	this wee	k - M. Luc	ero

Selected D WOID Priority	ate Range for Request Building Status		Deferred By	ation, Status Until Request Date Ta Created Date/Time Ac		Days Aged	Labor Hours	Costs
Assigned To		Description	Reason		Action Taken			
Requester Name								
Location:	Sunrise I	ES						
291970				1/3/2024		69		\$0.00
Medium	Work In Progress			1/3/2024 12:41:25 AM				
Flores, Pe	ete	Monthly - Sunris schedule details		-0430 - Refer to PM				
Margret V	íllalobos							
294070				2/9/2024		32		\$0.00
Medium	Work In Progress			2/9/2024 9:50:11 AM				
Hernande	ez, Guillemo	Need to repair b	ackflow is leaking					
Hector Pa	acheco							
293942				2/7/2024		34		\$0.00
Medium	Work In Progress			2/7/2024 1:41:00 PM				
Vasquez,	Jose	Please see coad	ch scott for sprinkler of	check				
Joanna R	lodriguez							
294457				2/16/2024		25		\$0.00
Medium	Work In Progress			2/16/2024 1:51:53 PM				
Hernandez, Guillermo		Fire Sprinkler re inspection.	pairs identified durir	ng quarterly				
	Hernandez							
294835	Main Building	Football Field		2/26/2024		15		\$0.00
Medium	Work In Progress			2/26/2024 11:56:58 AM				
Vargas, Juan		kinder playgrou is missing	nd green four seats s	see saw orange cap				
Adrian Flo								
294848	Main Building	Exterior		2/26/2024		15		\$0.00
Medium	Work In Progress			2/26/2024 3:03:43 PM				
Vasquez,	Jose	We need 4 field	goals with nets pleas	se thank you				
Joanna R	lodriguez							
Count: 6 \	Work Orders	Av	g. Age of WO's 32		Total for Sunris	e ES	0	\$0.00

WOID Priority Assigned Requester		Area Area Number Description	Deferred By			Costs .abor lours
Location:	Vado ES					
294514	Main Building	Exterior		2/19/20	24 22	\$0.00
Medium	Work In Progress	Exterior Field		2/19/2024 12:21:51	PM	
Villalobos, Margret			or field due to too m	control to come and any spiders on the	Approved/EM Lorraine 2/19/24	
Sylvia Car	y					
294335				2/14/20	24 27	\$0.00
Medium	Work In Progress			2/14/2024 1:11:06	PM	
Tellez, Hector		In the boy's res lights is out.	troom on the 200's	hallway one of the	reroute to electrician.	
Guadalup						
293774	Main Building	Hallway/Corrid	or	2/5/20	24 36	\$0.00
Medium	Work In Progress	200 Hallway		2/5/2024 10:19:22	AM	
Villalobos	, Margret		students are saying y saw the rats movir	that there are rats on Ig along the ceiling.	Approved-EM Lorraine 2/5/24-n	nkv
Sylvia Car	y			2/2/20	04 00	\$0.00
293544				2/2/20		φ 0. 00
Medium	Work In Progress			2/2/2024 10:06:39	AM	
Tellez, Hee	ctor	In room 204 two	o lights panels are co	ompletely out.		
Guadalup	e Parada					
292324				1/9/20	24 63	\$0.00
Medium	Work In Progress			1/9/2024 12:34:08	AM	
Flores, Pe	te	Monthly - Vado schedule detai	ES - Mower M-VE- s.	0431 - Refer to PM		
Margret Vi						
292495	Main Building	Classroom		1/10/20	24 62	\$0.00
Medium	Work In Progress	Kinder		1/10/2024 2:20:54	PM	
Villalobos, Margret		classrooms#10	s are requesting for 05, 107 & 108 to be e nd cockroaches in th	xterminated due to a	Approved and EM Waiver to Lori 1/11/24	raine
Sylvia Car	у					
292621				1/12/20	24 60	\$0.00
Medium	Work In Progress			1/12/2024 11:28:34	AM	
Tellez, Hee	rtor	In room 211 on	e of the emergency	iahts is out.	reroute to electrician.	

203 - WOIK OIDEIS III FIOGIESS (FISCAI TEAL)								Total	
Selected Dates WOID	ate Range for Request Building	t Dates:7/1/2023 - 2 Area Area Number Description	2/29/2024 Order By Loo Deferred By	cation, Status Until		Target Comp Date	Days	Labor	Costs
Priority	Status		Reason	Created Dat	ated Date/Time	d Date/Time Actual Comp Date		Hours	
Assigned	Го					Action Taken			
Requeste	r Name								
Location:	Vado ES								
291079		Kitchen			12/4/2023		99		\$121.54
High	Work In Progress			12/4/	2023 7:47:06 AN	1			
Ontiveros	, Joe	Need pressure	regulator installed fo	or dish mach	ine				
Dino Faci	0								
Count: 8 Work Orders		A	vg. Age of WO's 5	1		Total for Vad	lo ES	0	\$121.54

ZU3 - WOIK OIGETS III FIOGRESS (FISCAL TEAL) Selected Date Range for Request Dates:7/1/2023 - 2/29/2024 Order By Location, Status WOID Building Area Deferred By Until Request Date Target Comp Date Days Labor							Labor	Total Costs	
Priority	Status	Area Number	•		-	Actual Comp Date	Aged	Hours	
Assigned		Description	Reason	0.04		Action Taken			
Requester									
Location:	Yucca He	eights ES							
294371					2/15/2024		26		\$0.00
Medium	Work In Progress			2/15/202	24 10:26:59 AN	1			
Villalobos	, Margret	Room#229-we	e found mice drop	pings in the class	sroom	2/15/24 EM Lorraine	e-mkv		
Rocio Roc	driguez								
293826					2/6/2024		35		\$0.00
Medium	Work In Progress			2/6/20)24 8:05:33 AM	I			
Hernande	z, Guillemo	Fire Sprinkler r inspection.	epairs identified d	uring quarterly					
Guillermo	Hernandez								
293941					2/7/2024		34		\$0.00
Medium	Work In Progress			2/7/20)24 1:37:43 PM	l			
Vargas, Ju	lan	Need 8 decals	signs for the entry	doors					
Rocio Roc	driguez								
294645		Kitchen			2/21/2024		20		\$0.00
High	Work In Progress			2/21/202	24 10:13:51 AN	1			
Pacheco, I	Hector	Water spigot rig wont close com	ght outside kitchen opletely	h back door leakir	ng				
Dino Facio	0								
Count: 4 V	Nork Orders	4	vg. Age of WO's	29	То	tal for Yucca Height	s ES	0	\$0.00
Count: 20	03 Work Orders	A	vg. Age of WO's	6 5		Grand Total		7 \$3	0,540.99