

618 - Work Orders In Progress (7/1/05 - 9/30/05)

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3982	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3981	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3960	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3211	Work In Progress Monthly - Alma Del Valle Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Alma Del Valle Daycare
3312	Work In Progress Yearly - Alma Del Valle Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3308	Work In Progress Yearly - Alma Del Valle Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3661	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Carlos Lujan		Anthony ES
5285	Work In Progress KNIFE BROKE ON MIXERS BLADE ASSEMBLY	9/6/2005 Medium	Danny Orozco Danny Orozco	Cafeteria	Anthony ES
5694	Work In Progress we need two extension cord some time they ask for them and we note have one	9/21/2005 Medium	Carlos Lujan Aida Salcedo		Anthony ES
3899	Work In Progress room 201 bad capert half is bad replace with tile	7/28/2005 Medium	Hector Villalobos Michael Munoz	Classroom	Anthony ES
4581	Work In Progress old main blg a/c motor burn out a 3 hp volts 230	8/15/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
4478	Work In Progress Chapter bg p.e room replace 3/4 motor with a 1hp motor	8/11/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
4479	Work In Progress Annex blg need two mirrors in gilrs bathroom	8/11/2005 Medium	Hector Villalobos Ruben Ronquillo		Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4255	Work In Progress room 109 needs carpet repair	8/8/2005 Medium	Hector Villalobos Michael Munoz	Classroom	Anthony ES
5802	Work In Progress 9/22/05 2. cutting weeds by football feild 5. monthly inspection 1. log on work order log 9/22 - 8	9/23/2005 Medium	Hector Villalobos Hector Villalobos		Anthony ES
5992	Work In Progress upper primary boiler is leaking replace	9/30/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
5944	Work In Progress Old main blg boiler room needs a thermocuple size 56 inch	9/29/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
5051	Work In Progress Nurse's office need a door for bathroom 28x 80	8/30/2005 Medium	Hector Villalobos Danny Miranda		Anthony ES
4705	Work In Progress upper primary room 321 will be come a work room need to replace bathroom door that has a half door	8/19/2005 Medium	Hector Villalobos Danny Miranda	Classroom	Anthony ES
4742	Work In Progress need a 3/4 hp motor cafeteira motor burn out old cafeteria	8/22/2005 Medium	Hector Villalobos Jaime Gomez	Cafeteria	Anthony ES
4743	Work In Progress mild cafeteria burn motor 3/4 hp with a belt 4-L 660 or 670	8/22/2005 Medium	Hector Villalobos Jaime Gomez	Cafeteria	Anthony ES
5093	Work In Progress Headstart pt 1 broken window double window 29 1/2 x 28	8/30/2005 Medium	Hector Villalobos Ruben Ronquillo	Classroom	Anthony ES
4861	Work In Progress Nurse office refrigerator is not working water is leaking from seal	8/24/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
4487	Work In Progress plese grade and add crusher fine for neww parking for parents and add parking curbs.	8/11/2005 Medium	Guadalupe Ontiveros		Anthony ES
4097	Work In Progress please scrape and add crusher fine along with parking curbs.see mike	8/2/2005 Medium	Guadalupe Ontiveros		Anthony ES
5090	Work In Progress new oven is completely down. Becky S. SNP Mgr 882-3507	8/30/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Anthony ES
5825	Work In Progress NEED KEY FOR OT/PT KA50	9/26/2005 Medium	Karla Quesada Manny Lozoya		Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4059	Work In Progress DAYCARE - NEED TO ISSUE KEYS TO CORINA VALDESPINO for (Krishna's Office). WILL BE HERE AT 8:00 AM TOMORROW.	8/1/2005 Medium	Margret Villalobos Manny Lozoya		Anthony ES
3434	Work In Progress WASHING MACHINE DOES NOT WORK ANY MORE. (IT GAVE UP) ELSA CHAIRZ - SNP MGR 882-2417	7/11/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Berino ES
5338	Work In Progress WALK - IN FREEZER IS LEAKING ALOT OF WATER BETWEEN THE FREEZER AND REFRIG. ELSA - 882-2417	9/8/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Berino ES
5800	Work In Progress 2 vaccums that need repair 1 has a short and ones missing a tire	9/23/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES
5898	Work In Progress Need 2 new keys for office gate and recut master key for Mr Silva THANKS OFFICE KEY IS ON YOUR KEY CHAIN ALREADY	9/28/2005 Medium	Jimmy Cortez Manny Lozoya		Berino ES
5585	Work In Progress need nemaster b key and 55key for new custodian thanks a.s. p	9/19/2005 Medium	Jimmy Cortez Manny Lozoya		Berino ES
4673	Work In Progress dolly has a flat needs to get fixed	8/18/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES
4055	Work In Progress please cut weeds and pick-up debre on east side of rockwall. (i.e weeds bottles cinder blocks.)	8/1/2005 Medium	Ramiro Holguin		Berino ES
4208	Work In Progress MOBILE HOME OCCUPANT WILL BE RECEIVING NEW MOBILE HOME ON APPROXIMATELY 8-29-05. PLEASE CONNECT ELECTRICAL. 28X54	8/4/2005 Medium	Enrique Sotelo		Berino ES
5318	Work In Progress I need a key to the monitoring wells	9/7/2005 Medium	Alfredo Holguin Manny Lozoya		Berino ES
4082	Work In Progress Monitoring Wells - I need a set of keys to the monitoring well caps	8/2/2005 Medium	Alfredo Holguin Manny Lozoya		Berino ES
4518	Work In Progress please replace urinal and commode in mens restrrom.	8/12/2005 Medium	Joe Ontiveros	Mechanical Room	Chaparral ES
5794	Work In Progress vaccum/cleaner/electrical/corde/no/good	9/23/2005 Medium	Daniel Ramirez Jimmy Carbajal		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5498	Work In Progress sweeper/blower/not/working/choke/broken	9/14/2005 Medium	Daniel Ramirez Jimmy Carbajal		Chaparral ES
5053	Work In Progress need to be replaced front area gate doors and chain link fence as mr. cardona	8/30/2005 Medium	Juan Vargas Michael Munoz		Chaparral ES
5704	Work In Progress many new doors need a 3 new locks	9/21/2005 Medium	Juan Vargas Manny Lozoya		Chaparral ES
5951	Work In Progress room 31 need change 8 fluorescent lighting troffer	9/29/2005 Medium	Juan Vargas Enrique Sotelo		Chaparral ES
3293	Work In Progress WWTP - The fence around plant needs wind screen replaced.	7/5/2005 Medium	Juan Vargas Ricardo Jacquez		Chaparral ES
3284	Work In Progress 07/05/05 mike munoz Mr. cardona quiere bertical blind en su oficina size 82 width and 80 length	7/5/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
4030	Work In Progress Room 47 need to instaled a/c ventilation	8/1/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
3868	Work In Progress ROOMS 83-82-81-80-72-96-70 NEED WINDOWS REPAIRED OR REPLACE 2-REPORT	7/27/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
3846	Work In Progress 07/26/05 j. gomes rooms 2 -20-21- 51-47-107-44- 55-46- need replace A/C 6500	7/26/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
3801	Work In Progress 5/25/05/ mike neseito que pongan sistema de riego para los arboles	7/25/2005 Medium	Juan Vargas Guadalupe Ontiveros		Chaparral ES
3800	Work In Progress 07/25/05 jaime gomes main office need new A/C two 4500 and one 6500	7/25/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
4213	Work In Progress Rooms 101-102-60-62-61-54-70-96-72-73-97 80-82-83 need carpet repace	8/4/2005 Medium	Juan Vargas Michael Munoz		Chaparral ES
4602	Work In Progress ruben ronquillo need 10 pvc 45 elbows 6 inches 10 square grate basin 6 inches and 200 ft. 6 inches pvc pipe	8/16/2005 Medium	Juan Vargas Joe Ontiveros		Chaparral ES
4797	Work In Progress repair storage, boy,s , girl,s r.r. @ chaparral elem	8/22/2005 Medium	Danny Miranda Danny Miranda		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3871	Work In Progress need an extra key for Even start classroom, Jeannette rm-118	7/27/2005 Medium	Jennifer Corral Manny Lozoya	Classroom	Chaparral ES
4110	Work In Progress Rm-72 Ms. Barret needs screens on her windows. Says they were suppose to be put in last year.	8/3/2005 Medium	Jennifer Corral Ruben Ronquillo	Classroom	Chaparral ES
3945	Work In Progress Air Conditioner smells like burn and is not cold in rm-128 for Ms. Word	7/29/2005 Medium	Jennifer Corral Jaime Gomez	Classroom	Chaparral ES
3946	Work In Progress Air Conditioner not working in rm-20 for Ms. Gary	7/29/2005 Medium	Jennifer Corral Jaime Gomez	Classroom	Chaparral ES
3785	Work In Progress NEED A KEY FOR ROOM 114,LEDESMA REPRINT FOR MANNY - REGARDING E-MAIL 7/27/05 - MKV	7/22/2005 Medium	Jennifer Corral Manny Lozoya	Classroom	Chaparral ES
3299	Work In Progress I need some keys for two of the new administrators who will be coming to this school. They have requested main keys to the gate that opens up the fence outside the school and also a set of main keys for the building. If you can please do as soon as possible. Keys for Chaparral Elementary.	7/5/2005 Medium	Jennifer Corral Manny Lozoya	Office	Chaparral ES
5726	Work In Progress Need cores on mulliums at 3 new entrance doors.	9/22/2005 Medium	Michael Munoz Manny Lozoya		Chaparral ES
5364	Work In Progress 9/9/05. need for DANNY M. to spray texture a couple of walls in rms. 405a & 405b. thanks.	9/9/2005 Medium	Joe Ramirez Danny Miranda		Chaparral MS
4993	Work In Progress 8/29/05. need new lock for one of the main gates the other lock was stolen asap. thanks.	8/29/2005 Medium	Joe Ramirez Manny Lozoya		Chaparral MS
4537	Work In Progress 8/12/05. 1.5 install shelves rm. 9. 2.5service a/c rm208, secure wiring underneath bleachers. 1.5 paint handrail rm. 12. 2.0 replace several lightbulbs rm 208. .5 install pencil sharpener rm.105 8/12 - 8	8/12/2005 Medium	Joe Ramirez Joe Ramirez		Chaparral MS
4042	Work In Progress Need sensor replaced in girls locker room lavatory.	8/1/2005 Medium	Joe Ramirez Joe Ontiveros		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3720	Work In Progress 7/12/05. need a/c replaced on portable 1 rm. 2 please.	7/20/2005 Medium	Joe Ramirez Jaime Gomez		Chaparral MS
4072	Work In Progress Room 208 - Mold on ceiling tiles. (Nancy, Nurse @ site called in) - mkv Margaret, Joe replied and said there where a couple of ceiling tiles with small mold droppings on them. He replaced them. However still go ahead and generate a w.o. for our records and have him fill it out. Mike	8/2/2005 Medium	Mary Garcia Joe Ramirez	Classroom	Chaparral MS
3499	Work In Progress We need locks to be installed on the center pole to the double doors in the front entrance,north east doors and south east doors. This is the oldest part of the school. the newer part of the school already have locks on the center poles. This old doors are the once that we use more often. This locks will make it so much faster and easier. THANK YOU ROBERT	7/13/2005 Medium	Robert Gonzalez Manny Lozoya		Chaparral MS
3682	Work In Progress WE HAVE AN OLDER MODEL SHOWER SCRUBBER THAT DOESN'T WORK THAT GOOD ONCE WE USE IT FOR A WHILE. THANK YOU ROBERT	7/19/2005 Medium	Robert Gonzalez Jimmy Carbajal		Chaparral MS
3793	Work In Progress ROOM 355 HAS A STORAGE ROOM THAT DOESN'T OPEN WITH THE SAME KEY THAT OPENS THE CLASS ROOM. NEED TO BE REKEYED. THANK YOU ROBERT	7/25/2005 Medium	Robert Gonzalez Manny Lozoya		Chaparral MS
5920	Work In Progress NEED 3 55 GALLON BARRELS TO USE AS TRASH CANS. THANK YOU	9/28/2005 Medium	Robert Gonzalez Sal Acuna		Chaparral MS
5563	Work In Progress STILL HAVING PROBLEMS WITH THE BURNISHER THAT JOSE USES. VERY HARD TO PUSH. THANK YOU	9/16/2005 Medium	Robert Gonzalez Jimmy Carbajal		Chaparral MS
5062	Work In Progress I NEED 1 MALE WATER HOSE CONNECTOR, 1 HX-1 VINYL ANCHOR KIT AND 1 WEJIT DRY WALL AUGER ANCHOR KIT SIZE 8. THANK YOU	8/30/2005 Medium	Robert Gonzalez Jimmy Carbajal		Chaparral MS
4060	Work In Progress NEED KEY TO OPEN 406	8/1/2005 Medium	Vickie Reed Manny Lozoya	Classroom	Chaparral MS 406
3855	Work In Progress NEED TO REKEY CABINET.	7/26/2005 Medium	Vickie Reed Manny Lozoya	Classroom	Chaparral MS 204

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3717	Work In Progress NEED BACKHOE TO CLEAN OUT POND AREA.	7/20/2005 Medium	Vickie Reed Lorenzo Hernandez		Chaparral MS POND
3481	Work In Progress need to rekey locks on cabinets in rm. 405a.	7/12/2005 Medium	Vickie Reed Manny Lozoya		Chaparral MS
3439	Work In Progress NEED KEYS FOR TWO NEW PORTABLES.	7/11/2005 Medium	Vickie Reed Manny Lozoya	Portables	Chaparral MS
4459	Work In Progress NEED COPIES OF KEYS FOR CHS DATA CLERK'S DESK AND FILE CABINET.	8/10/2005 Medium	Vickie Reed Manny Lozoya	Office	Chaparral MS SHIRLEY HEMPHILL
4509	Work In Progress need to rekey file cabinets. 2	8/12/2005 Medium	Vickie Reed Manny Lozoya	Classroom	Chaparral MS 104
4639	Work In Progress NEED 3 REPLACEMENT KEYS FOR 3 A-34'S THAT DO NOT WORK.	8/17/2005 Medium	Vickie Reed Manny Lozoya	Office	Chaparral MS VICKIE-KEY
4736	Work In Progress DOOR WILL NOT LOCK SOMETIMES AND GETS STUCK ALSO.	8/19/2005 Medium	Vickie Reed Manny Lozoya	Classroom	Chaparral MS P1
3314	Work In Progress Yearly - Chaparral MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3607	Work In Progress need to paint new door @ football storage rm.	7/18/2005 Medium	Danny Miranda Joe Ramirez		Chaparral MS
3608	Work In Progress need to paint new door @ rm. 86	7/18/2005 Medium	Danny Miranda Joe Ramirez		Chaparral MS
4586	Work In Progress garbage disposal is clogged up	8/16/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Chaparral MS
4772	Work In Progress walk-in refrigerator/fan is making alot of noise Sandra Diaz - SNP Manager 824-4376	8/22/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Chaparral MS
3307	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
4485	Work In Progress please take a load of crusher fine so sewer line. Ak David (plumbing) for the specifics.	8/11/2005 Medium	Guadalupe Ontiveros	Portables	Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3648	Work In Progress please get with speedy and have him train you on the sprikler system on football field and thru out campus. Identify all valves and repair what is needed. also ask him for a key for sprinkler box and have him teach you the programs.	7/19/2005 Medium	Joe Ramirez	Football Field	Chaparral MS
3649	Work In Progress need to cut weeds and grass behind library and courtyard and surrounding areas tru -out campus including pond. Also need to irrigate these areas also.	7/19/2005 High	Joe Ramirez		Chaparral MS
3650	Work In Progress please paint railing on new portables that where installed and modified and all railings that are in need.	7/19/2005 Medium	Joe Ramirez		Chaparral MS
3656	Work In Progress please put up fence where portables where installed even if its on a temp bases.	7/19/2005 Medium	Joe Ramirez	Football Field	Chaparral MS
4031	Work In Progress Please level around ponding and surronding areas. Check with Mr.Diggs	8/1/2005 Medium	Guadalupe Ontiveros		Chaparral MS
5463	Work In Progress need to pour landing and sidewalks to portables by football feild.	9/13/2005 Medium	Michael Munoz	Portables	Chaparral MS
5229	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
5227	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
5204	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3964	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3977	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3990	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3988	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3243	Work In Progress Monthly - Chaparral MS Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3241	Work In Progress Monthly - Chaparral MS Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3191	Work In Progress Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Chaparral MS
3148	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3336	Work In Progress Yearly - Chaparral MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3165	Work In Progress Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3185	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3248	Work In Progress Monthly - Desert Pride Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3244	Work In Progress Monthly - Desert Pride Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3995	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3991	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3979	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
5218	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
4992	Work In Progress please remove marquee sign from desertveiw and install at desert pride. please be careful when removing.see mike	8/29/2005 Medium	Guadalupe Ontiveros		Desert Pride

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5234	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
5230	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3337	Work In Progress Yearly - Desert Pride Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3315	Work In Progress Yearly - Desert Pride Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
5336	Work In Progress Principals requests: for dead bolt locks for last portable (where break-in occur)	9/8/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride #6,7.
5294	Work In Progress NEED OUTSIDE NIGHT LIGHT BETEWEW LAST PORTABLE AND END OF CAMPUS. ALSO NEED LIGHT BULK FOR NIGHT LIGHT BETEWEW 2ND BUILDING AND PUMP HOUSE	9/6/2005 Medium	David Acosta Carlos Castillo	Classroom	Desert Pride
5693	Work In Progress ATT: Mike Munoz-I was ask if the utilitie post that are lying on the ground by the portables can be remove for safety reasons 9/26 - Route to Lupe as per Mike.	9/21/2005 Medium	David Acosta Guadalupe Ontiveros	Portables	Desert Pride
5904	Work In Progress Having trouble unlocking door handle (cylinder won't turn).	9/28/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride #8
5959	Work In Progress need to ckeck a/c blower . It stops blowing	9/29/2005 Medium	David Acosta Jose Ambriz	Classroom	Desert Pride #1
4642	Work In Progress need one key for storage closet for teacher in room #3	8/17/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride 3
3942	Work In Progress need emergency light and exit signs check out.	7/29/2005 Medium	David Acosta Carlos Castillo	Office	Desert Pride
4304	Work In Progress need locks for two doors to the hall way, that needs to be use as storage for science rooms.	8/8/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride #3,4
3791	Work In Progress need plastic name plates(12)MS. S. VERLANDER, MS. I. RAMIREZ, MS. BACH-HAGUE, MS. B. COSTULIS, MS. C. MCDONALD, MR. C. VELA, MR. P. WYMAN, MS. G. PARKER, MS. S. GARCIA, MR. D. NEAL , MS. J. ZAPATA, MS. D. DEAN	7/25/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4460	Work In Progress I need an office key for Ms. Maes, Clerk at Desert Pride Academy	8/10/2005 Medium	Mary Telles Manny Lozoya	Office	Desert Pride
5171	Work In Progress Please check and replace lights on last row of portables. Thanks.	9/2/2005 Medium	Juliet Parra Carlos Castillo		Desert Pride
4799	Work In Progress (assistant principal's request) need to re-do cylinder on portable #405 main door to where teacher's have access to the room to enter at any time.	8/22/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
5426	Work In Progress need a replacement heating coil (Boiler System) in the Cafeteria/Gym. (Old one Leaks)	9/12/2005 Medium	Johnny Acuna Jaime Gomez		Desert Trail Intermediate
4115	Work In Progress Emergency: Please fix door knob to portable # 409. Door knob gets stuck open and need to have the door secured by the end of the day. Thank You !!!!!	8/3/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
4558	Work In Progress Mrs. Bonham (Asst. Principal) requesting concrete slab to be installed between portable #412 and #413 art studio.	8/15/2005 Medium	Johnny Acuna Michael Munoz		Desert Trail Intermediate
4561	Work In Progress need a heavy-duty doorknob for the inside door going to restrooms to portable #412.	8/15/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
4116	Work In Progress need a replacement single knob water faucet for room #112.	8/3/2005 Medium	Johnny Acuna Joe Ontiveros		Desert Trail Intermediate
3739	Work In Progress DIAG/PSYCH ROOM NEED (2) CLASSROOM KEYS MADE. CORE IS: J-53	7/21/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
3619	Work In Progress MENS RESTROOM (NW HALL) : PLEASE CHANGE DOOR CYLINDER WHERE KEY ENTERS TO OPEN UP DOOR. STUDENTS STUFFED IN CYLINDER WITH CLAY AND HARDENED. THANK YOU !!!!!	7/18/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
3620	Work In Progress NEED NAME PLATES TO BE MADE: (1) PRINCIPAL, (1) ASSISTANT PRINCIPAL, (1) COMPUTER LAB	7/18/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3375	Work In Progress (CHAPARRAL SUNRISE ELEMENTARY) CUSTODIAL REQUESTING FOR FLAG POLE ROPE TO BE RE-INSTALLED ON OUTDOOR FLAG POLE BEFORE SCHOOL STARTS. (VANDALS CUT OFF ROPE) THANK YOU...	7/7/2005 Medium	Johnny Acuna Ruben Ronquillo		Desert Trail Intermediate
4107	Work In Progress The door lock on portable 409 it doesn't work, so we can't lock it up (it's open)	8/3/2005 Medium	Salvador Gonzalez Manny Lozoya		Desert Trail Intermediate
5228	Work In Progress Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
5233	Work In Progress Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
5462	Work In Progress need to demo and repour concrete to sectioned area by cafeteria.	9/13/2005 Medium	Michael Munoz	Cafeteria	Desert Trail Intermediate
5205	Work In Progress Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
3166	Work In Progress Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
3339	Work In Progress Yearly - Desert View ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
4587	Work In Progress Bottom right blodgett oven is not working properly	8/16/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Desert View ES
4149	Work In Progress key cylinder to walk-in refrigerator doesn't lock, key continously goes round and round, please repair as soon as possible, groceries and commodities are stored in there.	8/3/2005 Medium	Alma Terrell Manny Lozoya	Cafeteria	Desert View ES
3317	Work In Progress Yearly - Desert View ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
5340	Work In Progress MOUSE PROBLEM. MOUSE GOT ON THE TABLE WHILE EATING MARTHA FLORES - 589-2425 HELP PLEASE	9/8/2005 Medium	Jacqueline Aguilar Margret Villalobos	Cafeteria	Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4781	Work In Progress pat aguilar rock wall (safety concern) 6 rock wall metal gates need to be replaced rusted throw	8/22/2005 Medium	Patricio Aguilar Michael Munoz		Desert View ES
5769	Work In Progress electrician teachers lounge need light ballast need 2 boxes light fluorescent lamps order code 26668	9/22/2005 Medium	Patricio Aguilar Carlos Castillo		Desert View ES
5616	Work In Progress REQUESTING (2) "R" KEYS, ONE FOR NEW COUNSELOR, Mr. David Gonzalez and the other one to replace Ms. Esther Maldonado's "R" key. (Bended Key) Please pick up bended key with Margarita Terrazas at the front office	9/19/2005 Medium	Margarita Terrazas Manny Lozoya		Desert View ES 5055891180
4083	Work In Progress TEACHER DESK WITH LOCKING DRAWER, DOES NOT LOCK. ROOM#19, LOWER GRADE SIDE. MRS. GRISWOLD	8/2/2005 Medium	Margarita Terrazas Manny Lozoya		Desert View ES
5145	Work In Progress Urgent: Need center pole repaired in exterior double door on east side of school repaired, pole fell and struck teacher. Door cannot be fully secured and will compromise security after school hours.	9/1/2005 Medium	Miguel Aguilar Manny Lozoya		Desert View ES
5146	Work In Progress Need copies (3) made of padlocks on hall doors, need for sub keys and replacement.	9/1/2005 Medium	Miguel Aguilar Manny Lozoya		Desert View ES
5833	Work In Progress Need scissor lift to reach top of flag pole to repair broken chain in order to raise New Mexico flag.	9/26/2005 Medium	Miguel Aguilar Ruben Ronquillo		Desert View ES
5836	Work In Progress Need Sprite wet/vac for hall shower scrubbing/cleaning. Do not have one here available.	9/26/2005 Medium	Miguel Aguilar Jimmy Carbajal		Desert View ES
3827	Work In Progress Requesting electrical setup for installation of garbage disposal inside teachers lounge.	7/26/2005 Medium	Miguel Aguilar Carlos Castillo		Desert View ES
3828	Work In Progress Requesting necessary setup of sink plumbing for installation of garbage disposal inside teachers lounge.	7/26/2005 Medium	Miguel Aguilar David Villalobos		Desert View ES
3567	Work In Progress Server Room - Breaker is tripping.	7/14/2005 Medium	Norma Alvarado Carlos Castillo		GAC

10/4/2005 8:37:57 AM

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4377	Work In Progress NEED NEW R. R. PARTITIONS IN "A" WING AS PER MENNY PROSPERO	8/9/2005 Medium	Manuel Prospero Danny Miranda		GAC
5557	Work In Progress THE A/C IN THE CAFETERIA IN PRE-K IN NOT WORKING AND IN ON WARRANTY. AS PER MR. DAVID BOYD.	9/15/2005 Medium	Manuel Prospero David Boyd		GAC
4182	Work In Progress B-Wing - Human Resources Dept Please spray Lucy Garcia's & Ms. Browder's office for bugs (crickets, centerpedes, etc.)	8/4/2005 Medium	Mary Garcia Margret Villalobos		GAC
4227	Work In Progress AS PER GINGER BERR-IF IT WOULD BE POSSIBLE TO HAVE TRAPS TO COVER THE WATERHOUSE AT THE PRE-K. (THIS WAY THEY DO NOT HAVE TO BE MOVING IT IN & OUT) 9/23 - Route to Manuel as per Mike.	8/5/2005 Medium	Mary Garcia Manuel Prospero		GAC PLAY GROUND AREA
4655	Work In Progress AS PER ANN STEINHOFF-NEEDS 1 MORE GRAND MASTER KEY FOR HER SECRETARY AT PRE-K	8/17/2005 Medium	Mary Garcia Manny Lozoya	Office	GAC WHOLE BUILDING
3545	Work In Progress AS PER ANN STEINHOFF-CHECK ELECTRICITY IN LAST OFFICE ON WEST SIDE OF C -WING MAYBE TRIPPED BREAKER.	7/14/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC C WING
3460	Work In Progress AS PER JULIE HERNANDEZ, NEED ELECTRICIAN TO CONNECT WIRES WITH AN END CONNECTION TO BE ABLE TO PLUG CONNECTION TO THE WALL. (CALL JULIE @ 6417 BEFORE COMING)	7/12/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC A WING
3432	Work In Progress AS PER LINDA REYES-NEED FURNITURE FROM 3 OFFICES & BOXES ALONG WITH THIS TO BE MOVED A.S.A.P. TO NEW AREA IN C-WING. STAFF WILL START WORKING IN THESE NEW OFFICES BY TOMORROW.	7/11/2005 Medium	Mary Garcia Manuel Prospero	Office	GAC C WING
3408	Work In Progress AS PER CARLOS VIGIL-NEEDS A GRAND MASTER 7, ASAP. (HIS BROKE IN HALF) ALREADY TALKED WITH MANNY LOZOYA	7/8/2005 Medium	Mary Garcia Manny Lozoya	Office	GAC ALL SCHOOLS
3579	Work In Progress AS PER JOSE HINOJOSA-NEEDS AN OUTLET TO BE REPLACED NEXT TO HIS COMPUTER DESK.	7/15/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC C WING
5796	Work In Progress AS PER CORA-NEEDS THE DOOR LOCK TO THE DATA CENTER SWITCHED OUT FROM SWIPE CARD TO A COMBINATION LOCK. (MANNY, PLEASE SEE CORA BEFORE CHANGING OUT)	9/23/2005 Medium	Mary Garcia Manny Lozoya	Computer Lab	GAC DATA CENTER- TECHNOLOGY

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5830	Work In Progress AS PER MS. CANTRELL NEED FOR MORGAN BLDG TO BE LEVELED. THE SIDES NEED MORE DIRT ADDED TO THEM, CUASE WHEN YOU STEP ON THE SIDES IT FOLDS IN. Route to Manuel as per Mike 9/30/05 -mkv	9/26/2005 Medium	Mary Garcia Manuel Prospero	Portables	GAC STORAGE BLDG.
5831	Work In Progress AS PER MS. CANTRELL NEEDS FOR THE MORGAN RAMP TO BE FLUSHED WITH THE BLDG. ALSO THE RAMP NEEDS TO BE LOWERED TO HIGH. Route to Manuel as per Mike 9/30/05 -mkv	9/26/2005 Medium	Mary Garcia Manuel Prospero	Portables	GAC STORAGE BLDG
5899	Work In Progress AS PER PHILLIP NEEDS HELP TO UNLOAD SHLEIVING FOR MORGAN AT ABOUT 10:45 AM	9/28/2005 Medium	Mary Garcia Manuel Prospero	Portables	GAC MORGAN
5900	Work In Progress AS PER PHILLIP NEEDS HELP TO ASSEMBLE SHELVES (5 UNITS) TO INSTALL IN THE MORGAN	9/28/2005 Medium	Mary Garcia Manuel Prospero	Portables	GAC MORGAN
5953	Work In Progress MIKE MUNOZ -AS PER OUR CONVERSATION ON 9/28/05 REGARDING THE THERMASTAT IN THE KITCHEN AREA AT THE GAC. SUGGESTIONS WERE THAT MAYBE TO PUT IN A PROGRAMABLE W/OVER RIGHT THERAMSTAT. REMINDER FOR MIKE MUNOZ	9/29/2005 Medium	Mary Garcia Michael Munoz	Office	GAC A WING
5967	Work In Progress AS PER PHILLIP NEEDS A DOOR STOPPER INSTALLED ON THE MORGAN BUILDING. AS PER MANNY'S REQUEST TO PUT IN WORK ORDER FOR DOOR STOPPER	9/29/2005 Medium	Mary Garcia Manuel Prospero	Portables	GAC MORGAN
4925	Work In Progress C Wing- Having problems with mice.	8/25/2005 Medium	Mary Garcia Margret Villalobos		GAC
3580	Work In Progress SWIMMING POOL AREA ELECTRICAL ROOM - NEED A KEY FOR THIS AREA.	7/15/2005 Medium	Lorenzo Hernandez Manny Lozoya		GAC
5824	Work In Progress NEED A WATERHOSE AND ALSO A HOSE ROLL A WAY.2 WATERHOSE ONE FOR THE PATIO AND ONE FOR THE PRE KINDER AREA I ONLY HAVE ONE AND I USE IT FOR THE FRONT AREA,THE HOSE ROLL A WAYS I NEED ONE FOR EACH HOSE THANK YOU FOR YOUR CONTINUED SUPPORT YOU ARE THE BEST!!!!	9/26/2005 Medium	Jimmy Carbajal Sal Acuna	Custodial	GAC
3282	Work In Progress C-WING - TAKE OFF TILE AND INSTALL NEW TILE (TILE HAS BEEN DELIVERED), ALSO FINISH PAINTING. WILL SEND GERRY MARQUEZ TO ASSIST.	7/5/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3195	Work In Progress Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5413	Work In Progress please cover hole where water fountain is when it is removed	9/12/2005 Medium	Manuel Prospero	Cafeteria	GAC
3546	Work In Progress Technology Server Room-Install Battery powered Emergency lighting in this room	7/14/2005 Medium	Carlos Castillo		GAC
4916	Work In Progress please check and repair leak & secure drop ceiling in rm 142. possible safety hazard.	8/25/2005 Medium	Danny Miranda		Gadsden HS
5464	Work In Progress Need to paint stripings for student parking lot and east of Auto Shop.	9/13/2005 Medium	Michael Munoz	Parking Lot	Gadsden HS
5458	Work In Progress need to restripe all parking lines ,handi-cap-arrowa etc.	9/13/2005 Medium	Michael Munoz	Parking Lot	Gadsden HS
5957	Work In Progress Please repair wall where existing plumbing was behind wall. counseling center.(old Miller house)	9/29/2005 Medium	Danny Miranda		Gadsden HS
5962	Work In Progress please install a couple of l-brackets to desk where new electrical was installed. see mr.carrasco in auto shop	9/29/2005 Medium	Fernando Moncayo		Gadsden HS
5845	Work In Progress please replace 2 locks to the storage area beneath the bleachers ASAP . Thanks	9/26/2005 High	Manny Lozoya	Football Field	Gadsden HS
4448	Work In Progress Telescope observatory locate on the west side of the baseball field - Installl fencing around it to prevent vandalism	8/10/2005 Medium	Michael Munoz		Gadsden HS
5922	Work In Progress Received a complaint from a Parent - Need to remove the Graffiti from the sign at the entrance to the parking that reads "Welcome to Gadsden" it has been this way for about three years. And also on the two pillars in front of the Old English Building, the graffiti was painted over but you can still see it.	9/28/2005 Medium	Alfredo Holguin Fernando Moncayo		Gadsden HS
3659	Work In Progress PLease install stair treads when they come in. Old english stair ways. I will order. See Mike INstall from main to old english stairs. FAXED PO 8/4/05 - MKV	7/19/2005 Medium	Mario Apodaca	Stairway	Gadsden HS
5237	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Fernando Moncayo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3168	Work In Progress Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS
3141	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
3998	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Fernando Moncayo		Gadsden HS
3319	Work In Progress Yearly - Gadsden HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
4212	Work In Progress need metal door @ frame for dugout storage	8/4/2005 Medium	Danny Miranda Danny Miranda		Gadsden HS
4612	Work In Progress Need a bucket operator and a bucket truck at GHS football field some time this week.	8/16/2005 Medium	Carlos Vigil Danny Orozco	Football Field	Gadsden HS
4902	Work In Progress AG BLDG entry door,won't open or lock key just turns;Also WOOD SHOP entry door new lock doesn't work	8/25/2005 Medium	Fernando Moncayo Manny Lozoya		Gadsden HS
4626	Work In Progress Attn. JOSE AMBRIZ; This w/o is for the pillow block bearings that I, called for.Need two more 1 3/16 THANK YOU!!!	8/17/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
5101	Work In Progress ATTN. JOSE AMBRIZ need about ten three pole contactors for the a/c's nighth set back system in the ACADEMIC BLDG. Some burned out by the power outage.Thank you!!	8/30/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
5943	Work In Progress Attn. MIKE MUNOZ need about ten parking stops[parking curb]on refrence from w/o# 5464 thank you!!	9/28/2005 Medium	Fernando Moncayo Michael Munoz		Gadsden HS
5767	Work In Progress As per MR. JOSE AMBRIZ the YORK a/c unit on top of gym need to disconnect the electrical power by the FALL BREAK [10/03/05]	9/22/2005 Medium	Fernando Moncayo Michael Mc Dermott	Gym	Gadsden HS
5622	Work In Progress Attn. MANNY LO TOYA , need four pad locks for new electrical panels at SWIMMING POOL and storages under bleachers ASAP please!! THANK YOU!!	9/19/2005 Medium	Fernando Moncayo Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5546	Work In Progress 09/14/05 1-4566 2.5-SOCIAL WORKER office assembled computer stand 3.5-3957-5197 1-Log on reports 9/14 - 3.5	9/15/2005 Medium	Fernando Moncayo Fernando Moncayo		Gadsden HS
4240	Work In Progress Need six wheels for large gates in NORTH parking lot THANK YOU!! 8/11 - Route to Ruben as per Mike	8/5/2005 Medium	Fernando Moncayo Ruben Ronquillo		Gadsden HS
4307	Work In Progress Room 244-245 HVAC unit not working properly too many problems. m#d136090g20025b- s#nls361523	8/8/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
4305	Work In Progress NORTH bus entrance gate keep falling, bottom rail all bend;Also needs new roller bearings for both gates thank you !!! [safety hazard]	8/8/2005 Medium	Fernando Moncayo Michael Munoz		Gadsden HS
4371	Work In Progress Broken windows in ACADEMIC BLDG rooms 309 and 320	8/9/2005 Medium	Fernando Moncayo Ruben Ronquillo		Gadsden HS
4311	Work In Progress PANTHER HUT porch entrance too dark security ligh doesn't work	8/8/2005 Medium	Fernando Moncayo Fernando Moncayo		Gadsden HS
3726	Work In Progress Attn electrician need a better security lighs by CONCESSION STAND to control vandalism	7/20/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
3593	Work In Progress Need to repair or replace electrical conduit outside of CONCESSION STAND by GIRL'S GYM	7/15/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
3479	Work In Progress All Campus - Need to replace old door knobs w/new levers.	7/12/2005 Medium	Hector Lozoya Manny Lozoya		Gadsden HS
3645	Work In Progress BOTH OVENS ARE DOWN. LYDIA M. SNP MGR 882-5522	7/19/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Gadsden HS
5915	Work In Progress Pressbox - There is a Bee Hive in pressbox. Having a game tomorrow. Please send someone out today. (Open PO) as per A. Holguin.	9/28/2005 Medium	Jesus Estrada Margret Villalobos	Football Field	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4726	Work In Progress Royal vacuum is missing bag and brush, belt serial No.H93266101B GISD tag 014131	8/19/2005 Medium	Jesus Estrada Jimmy Carbajal		Gadsden HS
5840	Work In Progress NEED A NEW CORE CYLINDER AND 4# LOCK FOR CONCESSION STAND AT FOOTBALL FIELD	9/26/2005 Medium	Mario Apodaca Manny Lozoya		Gadsden HS
5842	Work In Progress NEED A NEW GLASS PUT ON CONCESSION STAND WINDOW AT FOOTBALL FIELD (VANDALISM) 23X23 ASAP	9/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
5768	Work In Progress NEED A NEW FAUCET AT ROOM 229 FOR MR PALMER LAB SINK	9/22/2005 Medium	Mario Apodaca David Villalobos		Gadsden HS
5708	Work In Progress THE OUTSIDE OUTLET NEED TO BE FIX AT WEIGHT ROOM	9/21/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
5108	Work In Progress NEED TO PUT NEW BALLAST AT WOOD SHOP LAMPES	8/31/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
4849	Work In Progress NEED A NEW THERMOSTAT FOR BIG PAN	8/23/2005 Medium	Mario Apodaca Danny Orozco		Gadsden HS
4970	Work In Progress GLASS AT MAIN BLDG HALLWAY 40X18 NEED TOBE REPLACES VANDALISM	8/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
4976	Work In Progress NEED ALL WINDOW BLINDSON OLD ENGLISH BLDG 40 EA 40WX90L	8/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
4502	Work In Progress NEED TO LAMPES AT WOOD SHOP SAME ARE BURNED OUT	8/11/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
3917	Work In Progress 7-27-05 1-IN PUT TO SCHOOL DUDE 4-HELP CARLOS PUT NEW BOX FOR SCOREBOARD 3-ASSEMBLE DESK AT N-BLDG OFFICE 7/27 - 8	7/28/2005 Medium	Mario Apodaca Mario Apodaca		Gadsden HS
3524	Work In Progress NEED TO FIX FOOTBALL FIELD SCOREBOARD BREAKER BOX	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3525	Work In Progress NEED TO CK ALL FOOTBALL FIELD LAMPS	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
4658	Work In Progress 8/16 4-GHS-o&m of wwtp, filled up chlorinator at pool & added soda ash to pool water to boost PH 2.5-GHS-o& m of water supply system & main lift station, worked on DMR-QA25 study report .5-PPD-turned in DMR-QA25 info for faxing to ERA 1-GHS-added more soda ash to pool to raise PH 8/16 - 8	8/17/2005 Medium	Raul Sanchez Raul Sanchez		Gadsden HS
4811	Work In Progress Requested by Mr. Cordova Storage Room in Varsity Gym Stage-The door needs to be re-keyed to an off master key, light board room. 4 keys are needed.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4812	Work In Progress Requested by Lt. Dickerson Rm. 202 North Building-His HEM key has broken, 3 HEM keys are needed. One for him and two for the key box.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4815	Work In Progress Requested by Priscilla Martinez Rm. 605 Business Building-Two HJ masters are needed, one for Priscilla and one for key box.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4816	Work In Progress Requested by Ms. L. Melendrez Rm. 331 Academic Building-I have been having trouble opening my front door for over a year, and now I am having trouble opening the back door. It's not my key it's the door handle and deadbolts. Both back doors are very difficult to open.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4817	Work In Progress Requested by Mr. S. Perez Weight Room-Boys locker room door handle needs repair does not open. West side Weight Room door needs repairs does not lock.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4814	Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Air conditioner still does not work. No air is coming out of vents, very hot. Wires hanging into light fixture and a piece of ceiling tile (broken) is in one of the air conditioning vents. (room was damaged over summer)	8/23/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4819	Work In Progress Requested by Mr. S. Perez Weight Room-Water fountain does not give cold water.	8/23/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4810	Work In Progress Requested by Ms. L. Chavez Rm. 245 Classroom Over Varsity Gym-Re-place several burned out light bulbs. RE-ROUTE TO BUILDING MECHANIC as per Mike Mc Dermott 9/19/05	8/23/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4820	Work In Progress Requested by Luis Saucedo Rm. 507 & 509 Annex Building-Install door stops on each of these doors.	8/23/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4821	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- The boys bathroom door handle is very loose, needs to be tightened.	8/23/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4822	Work In Progress Requested by Ms. Zapien Rm. 154 Old English Building-The blinds are completely broken, the curtain is hanging.	8/23/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4905	Work In Progress Requested by Mr. Milligan Rm. 143 Old English Building-Four keys are needed of HX2. Three for the assistant coaches and one for key box.	8/25/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4908	Work In Progress Requested by Mr. Myers Rm. 506 Annex Building- Front door needs adjustment, it will not lock unless it is slammed.	8/25/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4915	Work In Progress Requested by Mr. Myers Rm. 506 Annex Building- The room needs more electrical outlets on the east and north walls. For computer setup-plugs on floor are a safety issue.	8/25/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4914	Work In Progress Requested by Mr. Myers Rm. 506 Annex Building- There is no air coming out of the vents of the A.C.	8/25/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4904	Work In Progress Requested by Mr. D. Gallegos Rm. 403-Please install water fountains with hose bibs, between soccer canopies for Athletic events and Gadsden High School P.E. classes.	8/25/2005 Medium	Velia Alarcon Guadalupe Ontiveros		Gadsden HS
4897	Work In Progress Requested by Velia Rm. 112 Front Office-Two HE27 are needed for key box.	8/25/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4631	Work In Progress Requested by Ms. M. Gonzalez Rm. 140 Old English Building-I would like to request a door stop for the new door and blinds fo one of my windows. The room gets "very" warm especially 4th period. Receive measurements from Bldg Mechanic and re-route to Ruben for ordering. 4 ea - 43" W x 90' L	8/17/2005 9/16/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
4633	Work In Progress Requested by ISS Rm. 800 Old Counseling Center-Door frame falling off portable door leading to the old counseling center.	8/17/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS
4627	Work In Progress Requested by Velia Rm. 112 Front Office-Work order #3911 was not asked to me made off master, also three keys were asked for not two. An additional 4 keys are needed as soon as possible.	8/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4629	Work In Progress Requested by Mr. Dixon Rm. 600 Business Building-Two keys of M114 for the Varsity Gym bathrooms. One for Mr. Dixon and one for key box.	8/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4630	Work In Progress Requested by Mr. Dixon Rm. 600 Business Building-Needs an F3 gate key.	8/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5076	Work In Progress Requested by Ms. Anderson Rm. 233 North Building (Panther Hut)-Pastry refrigerator has severe condensation dripping.	8/30/2005 Medium	Velia Alarcon Danny Orozco		Gadsden HS
4947	Work In Progress Old English Bldg - Heating is turning on and on the computer it states that it is off. Teachers have been complaining on a daily basis that it is too hot. Need your help!	8/26/2005 Medium	Velia Alarcon Margret Villalobos		Gadsden HS
5066	Work In Progress Requested by Ms. Anderson Rm. 233 North Building(Panther Hut)-Clothes Dryer takes several hours to dry clothes. Order new heating element or check and see if vent is clogged. 9/23 - Route to Mario as per Mike.	8/30/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
5068	Work In Progress Requested by Ms. Anderson Rm. 233 North Building (Panther Hut)-Replace circuit breakers with ones that can handle the load of appliances in the kitchen so we don't constantly trip them. Note from Mr. Chambers: Question? Check and see if appliances can be re-routed to another outlet? Too many appliances on one outlet will cause fire.	8/30/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5083	Work In Progress Requested by Mr. Martin Rm. 551 Wood Shop- Hall lock will no unlock, 2nd Notice.	8/30/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5084	Work In Progress Requested by Velia Press Box-Safety Hazard; need to re-duct and install new air conditioner were it can be serviced. FERNANDO, JOSE WILL LOOK INTO ORDERING UPDRAFT UNIT AND SHEETMETAL. AS PER OUR CONVERSATION YOU AND MARIO WILL FORM AND POUR CONCRETE FOR SMALL PAD FOR A/C STAND. IN THE MEAN TIME SERVICE WHAT IS THERE. - M. MUNOZ 9/1/05-MKV XC: WO TO FERNANDO	8/30/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS
5795	Work In Progress Requested by Josie Enriquez Rm. 107 Main Building- Work Order # 3920 entered on 7/28/05 has never been looked at or completed. The ladies who work in the Day Care classroom have now entered the 2nd work order, their having trouble with the lock on the door and the door needs to be in working order as soon as possible.	9/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5798	Work In Progress Requested by Mr. D. Gallegos Rm. 406 Boys Gyn- Roof leaks, air conditioner condensation.	9/23/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
5414	Work In Progress Requested by Mr. G. Holguin Rm. 342 Academic Building-Cabinets in room need to be stabilized.	9/12/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
5412	Work In Progress Requested by D. Gallegos Rm. 403 Boys Gym- Install threaded end on faucet or shower in volleyball and boys basketball lockers to allow for a water hose connection.	9/12/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
5416	Work In Progress Requested by Mrs. Klein Rm. 504 Annex Building- Roof is leaking, one spot has mold, and one panel is buldging down.	9/12/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
5405	Work In Progress Requested by Velia Rm. 112 Front Office-HG3 is needed for key box.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5406	Work In Progress Requested by Velia Rm. 112 Front Office-Two SA16 are needed, one for Ms. Dominguez and one for key box.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5407	Work In Progress Requested by Marie School Registrar Storage Room East Wing of the Cafeteria-The new vault needs to be re-keyed. The cylinder from the old vault can be placed on the door of the East Wing of the Cafeteria where her new vault is located now.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5409	Work In Progress Requested by Marie Storage Room in the East Wing of the Cafeteria-In the move from the old vault to the storage room one of the fire prove filing cabinet's locks broke. The filing cabinet remained locked, needs to be fixed as soon as possible as the Registrar needs access to these files on a daily basis.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5601	Work In Progress Requested by Ms. Thornley Rm. 660 Business Building-No heat/A.C. in lounge. Please attempt to tie into the ducting in my classroom (it has it's own system and is immediately adjacent) so that our lounge can be more comfortable.	9/19/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS
5597	Work In Progress Requested by Velia Rm. 112 Front Office-Two HE164 keys are needed, for room # 320.	9/19/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5598	Work In Progress Requested by Velia Rm. 112 Front Office-One HE119 key is needed for key box, for room # 315.	9/19/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4133	Work In Progress Requested by Velia Front Office-We need 2 additional keys made of HK15 as soon as possible.	8/3/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4166	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace ceiling tile in storeroom and office.	8/3/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4153	Work In Progress Requested by Mary Barreras Rm. 130 Old English Building-Need the new key to new lock to Sp. Ed. storage room for files and equipment. Key # M260	8/3/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4150	Work In Progress Requested by Velia Front Office-We need key # HJ7, for key box.	8/3/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4288	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-Lights are burned out in the shop.	8/8/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4282	Work In Progress Requested by Mr. Martinez Rm. 227 North Building-Replace carpet in Attendance Office area. One edge of the carpet is lifting, our concern is that a person may trip and fall.	8/8/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
4269	Work In Progress Requested by Ms. Jacquez Rm. 752 Barracks-Window is unhinged and needs to be repaired.	8/8/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
4199	Work In Progress Requested by Mr. Chambers Rm. 110 Front Office-Re-key doors, make cylinders off D Master, 4 keys will be needed. Have had several items stolen from office, please re-key as soon as possible.	8/4/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4222	Work In Progress Requested by Mr. Grubaugh Rm. 275C Library-The door to the video room has swollen and will not shut properly unless its slammed.	8/4/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS
4247	Work In Progress Requested by Mr. Grubaugh Rm. 275C Library-The door in the girl's bathroom sticks and is very difficult to open.	8/5/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4248	Work In Progress Requested by Ms. Gutierrez Rm. 823 Barracks-New cylinder is needed for new filing cabinet, 3 keys are needed.	8/5/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4243	Work In Progress Requested by Ms. Bradley Rm. 602 Business Building-Handle on window has broken off, needs to be replaced.	8/5/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4521	Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Need a lock and spare keys on the new filing cabinet.	8/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4519	Work In Progress Requested by Mr. Grace Rm. 603 Business Building-Electrical outlets by teacher's desk and west wall do not work. Also, need electrical outlets by television disconnected from light switch.	8/12/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4562	Work In Progress Requested by Ms. Klein Rm. 504 Annex Building-Air conditioner not working and appears to be leaking.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4564	Work In Progress Requested by Ms. Nanez Library-Install plywood baks to magazine shelves.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4566	Work In Progress Requested by Mr. E. Rios Boys Gym-Air conditioner leak, on to the floor.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4563	Work In Progress Requested by Ms. Moreno Rm. 126 Main Building-Install white board.	8/15/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4516	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-New water heater for kitchen area of Panther Hut. Route to Bldg Mechanic as per Mike 8/15/05 Check to see whats wrong with the H2o heater they have new one in small mech. room.	8/12/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4428	Work In Progress Requested by Velia Rm. 112 Front Office-Four additional keys are needed for HE200, for Weight Room.	8/10/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4429	Work In Progress Requested by Velia Rm. 112 Front Office-Three HE keys are needed for Key Box.	8/10/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4359	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional key are needed of HJ13, one for the floating teacher and one for the Key Box. For room number 609.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4360	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HJ7, one for the floating teacher and one for the Key Box. For room number 753.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4361	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK1, one for the floating teacher and one for the Key Box. For the Auto Shop.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4362	Work In Progress Requested by Velia Rm. 112 Front Office-We need 5 additional keys of HE1. For the Gyms.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4363	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK5, one for the I.A. in the classroom and one for the key box. For room number 569.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4365	Work In Progress Requested by Velia Rm. 112 Front Office-The HK key that was assigned to the custodian broke, 3 additional keys are needed.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4367	Work In Progress Requested by Velia Rm. 112 Front Office-One HE97 is needed for key box, for room number 307.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4368	Work In Progress Requested by Velia Rm. 112 Front Office-One HE104 is needed for Key Box, for room number 325.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4370	Work In Progress Requested by Velia Rm. 112 Front Office-Five additional keys are needed of HE200 for key box, for Weight Room.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4267	Work In Progress Requested by Ms. Hamilton Rm. 562 Ag. Shop- We need to have locks with keys put on the bathrooms again. Students are locking themselves in, we can't get in. Students are locking the doors and leaving. Security and ISS had trouble with students sneaking in and hiding.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4272	Work In Progress Requested by Ms. Klein Rm. 504 Annex Building- Having a hard time locking and opening door, appears to be locked but stays unlocked.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4279	Work In Progress Requested by Ms. Littlefield Rm. 226 North Building-The lock on my podium and one storage cabinet is brocken and lost.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4283	Work In Progress Requested by Mr. Myers Rm. 509 Annex Building- Key will not open storage door. HJ10 is the key that should open door.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4286	Work In Progress Requested by Mr. Villa Rm. 510 Band Room-Need two HK13 keys made.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4268	Work In Progress Requested by Ms. Hunt Rm. 105 Main Building- Roof leaks. 8/11 - Route to Fernie as per Mike	8/8/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4271	Work In Progress Requested by Ms. Kalkwarf Rm. 750 Barracks- Floor tiles are broken and coming off the floor.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4285	Work In Progress Requested by Mr. Villa Rm. 510 Band Room- Security light in the center of the room does not work.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4380	Work In Progress Requested by Velia Rm. 112 Front Office-Five D49 are needed, key to men's restroom in the Main Building.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4381	Work In Progress Requested by Velia Rm. 112 Front Office-Five DX are needed, key to women's restroom in the Main Building.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4384	Work In Progress Requested by Ms. Sanchez Rm. 122 Main Building-Door knobs are loose and needs to be tightened on both of them.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4385	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-Two large shop lights are burned out.	8/9/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4386	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-220 Volt Electric extension cord needed with a new female end, current ones puts people at risk of electrocution.	8/9/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4387	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-Need a new oil pressure gauge for air compressor. (0-30 PSI) Current gauge leaks compressor oil out of crankcase and on to the floor. Need a new air pressure gauge for air compressor, current gauge is to small. Need a 0-150PSI gauge.	8/9/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
3494	Work In Progress Requested by Marie New Counseling Center Portable-New portable needs to be keyed HE134. Change old cylinder to doors of new portable doors.	7/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3493	Work In Progress Requested by Pamela Holguin Rm. 228 North Building-A door frame is needed. Will have an old door installed, left over from doors that are being replaced in North Building. Also, a door knob that will not lock is needed.	7/12/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS
3774	Work In Progress Requested by Velia Rm. 112 Front Office- Key # HH7 is needed for the key box.	7/22/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3754	Work In Progress Requested by Velia Rm. 800 Old Counseling Center Portable-Doors need to be re-keyed as soon as possible. This portable will be used as the ISS classroom, 4 keys are needed.	7/21/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3755	Work In Progress Requested by Velia Rm. 112 Front Office-Key # HJ2 is needed for the key box.	7/21/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3715	Work In Progress Requested by Mr. Pawloski Rm. 109A Main Building (Sp.Ed. Office)-Please remove the lock in my file cabinet, replace, and re-key it with a new one.	7/20/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3716	Work In Progress ***URGENT***Requested by Velia Library-All the doors in the library need to be secured. They have changed all the door knobs and the cylinders need to be installed. URGENT library has alot of equipment that needs to me locked and secured!	7/20/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4204	Work In Progress Requested by Cathy Cano Parking Lot-Over Fall Break, have the lines in the North Parking Lot painted.	8/4/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
3910	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Bracket needed for N.M. Flag.	7/28/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
3902	Work In Progress Requested by Ms. Marquez New Counseling Portable-Two filing cabinets need to be keyed.	7/28/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3920	Work In Progress Requested by Velia Front Office-The cylinder for room #107 will not open with a D Master or key assigned to door. This classroom is the Day Care on our campus and the building custodian can not open the classroom to clean. Please fix as soon as possible.	7/28/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3908	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Dr. Pockets to be placed in Marie's copy to be placed on wall.	7/28/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
3909	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Install clock on wall.	7/28/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
3404	Work In Progress 7*07*05 .50 Picking up paint and tarps. 5.5 Replacing lamps that were burned out and starting doing cut in RM399 1.0 Moved new furniture to hallway. 1.0 Mr Q showing me the desks that needed to be repalced. 7/7 - 8	7/8/2005 Medium	Rudy Arreola Rudy Arreola		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4528	Work In Progress We need 2 water fountains replaced in cafeteria.	8/12/2005 Medium	Rudy Arreola Jaime Gomez		Gadsden MS
4218	Work In Progress Coil in not cooling cleaned out strainer and checked valve. RM 156	8/4/2005 Medium	Rudy Arreola Jaime Gomez	Classroom	Gadsden MS
4220	Work In Progress Rm 157/158 Unit is not cooling at all cleaned out strainer and checked valves.	8/4/2005 Medium	Rudy Arreola Jaime Gomez	Classroom	Gadsden MS
5793	Work In Progress {{{GYM LOBBY}}} Wall needs to be secured.	9/23/2005 Medium	Rudy Arreola Danny Miranda	Restroom (Boys)	Gadsden MS
5985	Work In Progress We can borrow the 935 to cut around bus turn around and behind annex and football field.	9/30/2005 Medium	Rudy Arreola Guadalupe Ontiveros		Gadsden MS
5919	Work In Progress {{{VOC BLDG}}} RM#300 We need new electric stove wired up.	9/28/2005 Medium	Rudy Arreola Enrique Sotelo	Classroom	Gadsden MS
5916	Work In Progress {{{ANNEXBLDG}}} Boys RR is just turning and cant be lock.	9/28/2005 Medium	Rudy Arreola Manny Lozoya		Gadsden MS
5918	Work In Progress Door handle is broken off boys lockerroom	9/28/2005 Medium	Rudy Arreola Manny Lozoya		Gadsden MS
5569	Work In Progress VOC BLDG RM#306 - Need some assistance changing out ballast already replaced lamps high ceiling.	9/16/2005 Medium	Rudy Arreola Enrique Sotelo	Classroom	Gadsden MS
5586	Work In Progress Handle was jammed in is hard to open and close.	9/19/2005 Medium	Rudy Arreola Manny Lozoya	Restroom (Boys)	Gadsden MS
5468	Work In Progress 9*09*05 .50 Ck in with office. 1.5 Chaning filters with Rick. 1.5 Unit in RM 209C not cooling power was off. .50 Water fountain was clogged. 1.0 .5256. 2.5 Cleaned units in RM 213C .50 Picking up tools and putting away. 9/9 - 7	9/13/2005 Medium	Rudy Arreola Rudy Arreola		Gadsden MS
5373	Work In Progress Door handle was pulled off weed need a new with a new plate.	9/9/2005 Medium	Rudy Arreola Manny Lozoya	Gym	Gadsden MS
5418	Work In Progress Rm #121 Door is hard to lock and unlock handle is loose also tighten up but still having problems with locking.	9/12/2005 Medium	Rudy Arreola Rudy Arreola	Classroom	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4725	Work In Progress Portable 500/501 really leak bad right in the center of the room.	8/19/2005 Medium	Rudy Arreola Rudy Arreola	Portables	Gadsden MS
5317	Work In Progress Need to cap of water lines and drain removed already removed sink and counters. RM#188.	9/7/2005 Medium	Rudy Arreola Joe Ontiveros	Classroom	Gadsden MS
3616	Work In Progress replace door at pump room	7/18/2005 Medium	Ricardo Jacquez Danny Miranda		Gadsden MS
4196	Work In Progress Small gate by canal road (gate used by BB players) is not secure. Padlock is locked and my key does not open it. Needs to be checked.	8/4/2005 Medium	Yolie Jacquez Manny Lozoya		Gadsden MS
4195	Work In Progress Gate by canal road still needs to be replaced. Gate not secure and needs to be replaced. (chain is not strong enough).	8/4/2005 Medium	Yolie Jacquez Michael Munoz		Gadsden MS
4404	Work In Progress C-WING CAREER CTR - SOMETHING IS STUCK IN CYLINDER.	8/9/2005 Medium	Michael Munoz Manny Lozoya		Gadsden MS
3582	Work In Progress IRRIGATION CTRL PANEL - IRRIGATION BOOSTER PUMP IS NOT WORKING. PLEASE TROUBLESHOOT BUS TURNAROUND AREA. ROUTED TO ENRIQUE AS PER RICK 8/2/05	7/15/2005 8/2/2005 Medium	Lorenzo Hernandez Enrique Sotelo		Gadsden MS
5119	Work In Progress Power Outage - El Paso Electric	8/29/2005 Medium	Margret Villalobos Enrique Sotelo		Gadsden MS
4867	Work In Progress THE PAD HOLDER IS WORN OUT AND WONT HOLD THE PAD AT ALL.	8/24/2005 Medium	Jimmy Carbajal Jimmy Carbajal	Hallway/Corridor	Gadsden MS
4778	Work In Progress 2nd request for an "A" master for GMS Campus	8/22/2005 Medium	Dana Hamel Manny Lozoya	Office	Gadsden MS
4777	Work In Progress The three locks on the office front window are broken, mostly poor design. The front office is wide open until these are repaired or replaced	8/22/2005 Medium	Dana Hamel Rudy Arreola	Office	Gadsden MS
4922	Work In Progress broken W-62 key please replace	8/25/2005 Medium	Dana Hamel Manny Lozoya	Gym	Gadsden MS
4863	Work In Progress Need extra keys to Key storage cabinet	8/24/2005 Medium	Dana Hamel Manny Lozoya	Office	Gadsden MS
5342	Work In Progress Install a new door in room 112, lock never installed	9/8/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5343	Work In Progress need to check lock and key rooms 300 and 301	9/8/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
5344	Work In Progress need lock and key for rooms # 122 and 157	9/8/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
5345	Work In Progress need new key for new teacher Key WA111	9/8/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
5347	Work In Progress Mr. Hamel needs an "A" master for GMS campus 3rd request	9/8/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
4982	Work In Progress Whole south side of annex does not have any air, class temperatures are above 95 degrees. The classes opposite hallway have conditioning, Please fix ASAP	8/26/2005 Medium	Dana Hamel Jaime Gomez	Classroom	Gadsden MS
5975	Work In Progress Need 1 each of the following keys for box, A88,A86,WA83, WA88,WA148, WA25, WA8 and three O2 keys (Mr. Hamel also)	9/29/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
5909	Work In Progress need a new WA 2 key for room 122	9/28/2005 Medium	Dana Hamel Manny Lozoya	Classroom	Gadsden MS
5832	Work In Progress Key both locks in registrar area (Gloria Hernandez) to the A 53 key	9/26/2005 Medium	Dana Hamel Manny Lozoya	Office	Gadsden MS
5850	Work In Progress repair valve in urinal of restroom across from nurse office	9/26/2005 Medium	Dana Hamel Rudy Arreola	Restroom (Boys)	Gadsden MS
5834	Work In Progress replace the stalls in restroom by nurses office (urinals)	9/26/2005 Medium	Dana Hamel Danny Miranda	Restroom (Boys)	Gadsden MS
5838	Work In Progress Electrical problems in front office , A wing teachers lounge and administrative offices. Causes computers to brown out or have no power, appears to be a problem with amperage.	9/26/2005 Medium	Dana Hamel Enrique Sotelo	Office	Gadsden MS
5779	Work In Progress clean the south wall of the Vocational building (Power scrub) all writing and tagging off walls	9/22/2005 Medium	Dana Hamel		Gadsden MS
5776	Work In Progress REPAIR OR REPLACE THE RAMP BETWEEN LOBBY AND ANNEX 9/23 - Route to Danny M. as per Mike.	9/22/2005 Medium	Dana Hamel Danny Miranda	Stairway	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5774	Work In Progress REMOVE ALL THE BENCHES FROM BOYS LOCKER ROOM THEY ARE GETTING OLD AND KEEP BREAKING OFF FROM WELDED PLATES OR BREAK IN HALF 9/23 - Route to Rudy as per Mike	9/22/2005 Medium	Dana Hamel Rudy Arreola		Gadsden MS
5777	Work In Progress PAINT CEILING IN BOYS RESTROOM ANNEX (BLACK)	9/22/2005 Medium	Dana Hamel Rudy Arreola	Restroom (Boys)	Gadsden MS
5624	Work In Progress Need extra key for Key Locker, Rooms 156/Wa33, Rm 169/WA44, rm161/WA38, rm165/wa109, rm 1151/WA02, rm 406 WA153, Rm 402 WA154, rm 108 WA151, rm 107 WA93, rm 307 WAv3, rm 308 WA95, rm 305 WAv4, rm 303 WA/96, rm 302 V6, rm 209 WA89, rm 207 WA148, rm 206 WA148, rm211 WA83, rm 214 WA111, rm 212 WA118, rm 203 A88, 204 A86, rm 205 WA116, Registration Office WA53 Attendance office WA120, Athletic Office WA152	9/19/2005 Medium	Dana Hamel Manny Lozoya	Classroom	Gadsden MS
5499	Work In Progress Change M4 key to a G key in all electrical room on campus, we have no "m" master	9/14/2005 Medium	Dana Hamel Manny Lozoya	Electrical Room	Gadsden MS
5500	Work In Progress change A3 key to a "g" key in storage room in annex	9/14/2005 Medium	Dana Hamel Manny Lozoya	Mechanical Room	Gadsden MS
5501	Work In Progress Repair the outside doors locks "w" master will not open doors to lobby	9/14/2005 Medium	Dana Hamel Manny Lozoya	Hallway/Corridor	Gadsden MS
5502	Work In Progress request 3 new "G" keys for principal and custodians	9/14/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
3651	Work In Progress Mice in Gloria Hernandez office in C Wing. Need control as soon as possible 1) HAD JUAN CHECK FOR ANY FOOD AROUND, 2) REQUESTED THAT THEY ASK R. RONQUILLO FOR MICE TRAPS (W/GLUE) 3) FAXED FOR PRICE QUOTE AS PER M. MUNOZ FOR THE WHOLE C-WING.	7/19/2005 Medium	Dana Hamel Margret Villalobos	Office	Gadsden MS
3652	Work In Progress Cockroach issues for the total school, need a monthly spraying Faxed PO - 8/4/05 -mkv	7/19/2005 Medium	Dana Hamel Margret Villalobos	Hallway/Corridor	Gadsden MS
3653	Work In Progress paint the columns on outside of gym	7/19/2005 Medium	Dana Hamel Rudy Arreola	Gym	Gadsden MS
3654	Work In Progress paint over the scratchouts in boys black restrooms	7/19/2005 Medium	Dana Hamel Rudy Arreola	Restroom (Boys)	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3655	Work In Progress paint the front columns of the school to remove tagging	7/19/2005 Medium	Dana Hamel Rudy Arreola		Gadsden MS
4643	Work In Progress Need a copy of fire alarm key (See Mr. Hamel for his key).	8/17/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
4522	Work In Progress Door broken in room 500, and window shattered	8/12/2005 Medium	Dana Hamel Danny Miranda	Portables	Gadsden MS
4524	Work In Progress add additional electrical strip for more computer usage, change circuit from 15 amp, room 161	8/12/2005 Medium	Dana Hamel Enrique Sotelo	Classroom	Gadsden MS
4095	Work In Progress please fill hole that is in front of entrance to band room. Will need a backing before gravel is applied. see mike	8/2/2005 High	Rudy Arreola		Gadsden MS
5958	Work In Progress b-wing by entrance to band room. gravel was layed down on existing hole. No backing was done as per our conversation. please put backing.	9/29/2005 Medium	Rudy Arreola		Gadsden MS
5961	Work In Progress please reomve and replaced stained ceiling tiles in Mr.Lowenburgs office.	9/29/2005 Medium	Rudy Arreola		Gadsden MS
5862	Work In Progress please look in to a possible short circuit to the microwave which might affect the alarm in the d-level.	9/27/2005 Medium	Enrique Sotelo		Gadsden MS
5309	Work In Progress Miik Cooler was at 60 degrees this morning 9/7/05	9/7/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	La Mesa ES
5116	Work In Progress cockroach problem Laura Benavidez - SNP Manager 233-2646	8/31/2005 Medium	Alma Terrell Margret Villalobos	Cafeteria	La Mesa ES
4446	Work In Progress DANNY NEED BUCKET TO BRING ROPE DOWN TO TIE OTHER END, CAME OF	8/10/2005 Medium	Frank Lara Danny Orozco		La Mesa ES
4378	Work In Progress locksmith need three keys for supply rm. key no F 49 8/23- Debra needs status on this work order submitted on 8/9/05 - mkv	8/9/2005 Medium	Frank Lara Manny Lozoya		La Mesa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4229	Work In Progress lupe ontiv. need helped to cut large branch by picnic table safety issue	8/5/2005 Medium	Frank Lara Guadalupe Ontiveros		La Mesa ES
4912	Work In Progress danny miranda need to replace counter top in boys restroom is is coming of	8/25/2005 Medium	Frank Lara Danny Miranda		La Mesa ES
5828	Work In Progress LIGHT IN WALK IN IS OFF. LAURA B. 233-2646	9/26/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	La Mesa ES
4357	Work In Progress BUTTON NOT MAKING CONTACT. TO GARBAGE DISPOSAL. LINDA Y. SNP MGR 589-2040	8/9/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	La Union ES
5447	Work In Progress Student Cross Walk - Path on the west side there is a tree that is in the way. Students have to scoot over onto the street.	9/12/2005 Medium	Margret Villalobos Alfredo Holguin		La Union ES
4864	Work In Progress JTP- Rosaro Ruedas needs a L201 key.	8/24/2005 Medium	Selma Nevarez Manny Lozoya		La Union ES JTP
3281	Work In Progress ice machine needs to be repired.	7/5/2005 Medium	Santos Galindo Danny Orozco		La Union ES
4356	Work In Progress in room 202 there is no outlet for refrigeration unit a.s.p.	8/9/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4408	Work In Progress a light next to my office need to be looked at cause it buzzes all day long.	8/10/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4410	Work In Progress They need to check lighting from building cause several lights are off. And some stay on 24 hrs out side.	8/10/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
3934	Work In Progress rotor needs repair; probably needs motor	7/29/2005 Medium	Santos Galindo Jimmy Carbajal		La Union ES
4223	Work In Progress need an electrical outlet by computer hookups room 203.	8/5/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4372	Work In Progress need a fan motor in electrical storage room.	8/9/2005 Medium	Santos Galindo Jose Ambriz		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4775	Work In Progress Parking lanes need to be repainted in yellow and bus lane also needs to be repainted but in red. Route to Sal Gonzalez as per Mike 9/13/05 -mkv	8/22/2005 Medium	Santos Galindo Salvador Gonzalez		La Union ES
4695	Work In Progress AUGUST 31 IS OPEN HOUSE WOULD LIKE ALL LIGHTS OUT SIDE TO BE CHECKED BEFORE THEN.	8/19/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4853	Work In Progress SINK AT CUSTODIAL CLOSET AT OLD BLDG. IS CLOGGED UP.	8/24/2005 Medium	Santos Galindo David Villalobos		La Union ES
4825	Work In Progress Need keys for room #100, #106, and room #108; plus keys for a file cabinet in the nurse's office.	8/23/2005 Medium	Santos Galindo Manny Lozoya		La Union ES
5312	Work In Progress After last night's rainfall, leaks were discovered in rooms #208, #209, and the library.	9/7/2005 Medium	Santos Galindo Lorenzo Solis		La Union ES
4956	Work In Progress NEED TO HAVE CHECK DRIVEWAY IN FRONT POSSIBLE WATER LINE BREAK. AREA HAS BEEN WET FOR TWO DAYS.	8/26/2005 Medium	Santos Galindo David Villalobos		La Union ES
5117	Work In Progress Lights in computer room keeps going out; breaker needs to be checked.	8/31/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
5371	Work In Progress In the women's restroom, in the southwing, the toilet is constantly flushy.	9/9/2005 Medium	Santos Galindo Salvador Gonzalez		La Union ES
5425	Work In Progress We need Vector Control to come in and spray.	9/12/2005 Medium	Santos Galindo Margret Villalobos		La Union ES
5503	Work In Progress Old emergency light fixtures (the complete system) are not working can you check them please. thank you	9/14/2005 Medium	Salvador Gonzalez Carlos Castillo		La Union ES
5849	Work In Progress 2.5 Assembly furniture - 2.0 Fix a door that did not locking 2.0 Service to an AC - 1.0 Change soap dispenser - .5 Change an outlet 9/26-8	9/26/2005 Medium	Salvador Gonzalez Salvador Gonzalez		La Union ES
5786	Work In Progress Upper hinge on door at JTP needs to be repaired. Might need to be welded	9/23/2005 Medium	Salvador Gonzalez Manny Lozoya		La Union ES
5949	Work In Progress Music Room needs a new circuit installation.	9/29/2005 Medium	Salvador Gonzalez Carlos Castillo		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3322	Work In Progress Yearly - La Union ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES
3572	Work In Progress NEED LIGHT BULBS FOR RECESSED LIGHTS AT LA UNION ELEM. THE MAJORITY ARE BURNED OUT. THANK YOU.	7/15/2005 Medium	Arturo Nunez Carlos Castillo		La Union ES
4917	Work In Progress please repair asphalt where other water line was repired.	8/25/2005 Medium	Michael Munoz		La Union ES
3344	Work In Progress Yearly - La Union ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES
3345	Work In Progress Yearly - Loma Linda ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
5568	Work In Progress As per Mike Munoz issue a 6 & 7 Grand Master keys to Mike Mc Dermott.	9/16/2005 Medium	Manny Lozoya		Loma Linda ES
3323	Work In Progress Yearly - Loma Linda ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
3829	Work In Progress MR. TRUJILLO IS WANTING NEW KEYS MADE FOR DESKS, CABINETTS AND FILE CABINETS. ALSO NEEDING NAME PLATE FOR NEW TEACHERS. MS. BERARD, CHAVEZ-FISHER, GRIEGO, DESANTIAGO, HUGHES, MARKHAM, MEDINA, MERRICK, MONTES, PINA, PRICE, RIOS- ALVILLAR,	7/26/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
4593	Work In Progress MIKE MUNOZ, REPLACE EAST FENCE	8/16/2005 Medium	Grace Alvarado Michael Munoz		Loma Linda ES
4330	Work In Progress NEEDING COAT RACK HOOKS IN ROOM #203 & 207& 201	8/8/2005 Medium	Grace Alvarado Ruben Ronquillo		Loma Linda ES
4315	Work In Progress MANNY LOZOYA, FIX LOCK IN 212	8/8/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
4316	Work In Progress MANNY LOZOYA: KEY MADE FOR PORTABLES WILL NOT OPEN STORAGE ROOM. MASTER WILL NOT OPEN STORAGE ROOM. NEEDING STORAGE ROOM OPENED AS SOON AS POSSIBLE.	8/8/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4317	Work In Progress MANNY LOZOYA: NEEDING KEYS FOR BOOK ROOM, ROOM #208, AND KEY #44	8/8/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
5965	Work In Progress RUBEN RONQUILLO REPAIR 3 BROKEN WINDOWS	9/29/2005 Medium	Grace Alvarado Ruben Ronquillo		Loma Linda ES
5311	Work In Progress A.S.A.P PLEASE NEED A CORD LESS DRILL , IF POSIBLE A TWO PACK BATTERIAS. (THANK YOU)	9/7/2005 Medium	Luis Solis Aida Salcedo		Loma Linda ES
5863	Work In Progress NEED SERVICE FOR THE VACUUM CLEANER.(THERE IS SOMETHING WRONG WITH THE PROPERLAR OR THE ENGINE., IT MAKES AN IRRITATING NOISE.) THANK YOU.	9/27/2005 Medium	Luis Solis Jimmy Carbajal		Loma Linda ES
5284	Work In Progress 9-6-5 TO MIKE MUNOZ. MR. T. NEEDS TO TALK WITH YOU ABOUT PUTTING A FENCE ALONG NORTH SIDE OF SCHOOL. K-3 KIDS ARE A CONCERN ABOUT GOING INTO VACANT AREA. THANK YOU.	9/6/2005 Medium	Michael Mc Dermott Michael Munoz	Athletic Field	Loma Linda ES
5283	Work In Progress 9-6-5 attn; lupe b. mr. truillo at loma linda would like to meet with you about moving play ground equpt. to grass area. thank you.	9/6/2005 Medium	Michael Mc Dermott Guadalupe Ontiveros	Athletic Field	Loma Linda ES
5466	Work In Progress attn; mike munoz- we need to have kitchen store room tiled with non slip tile like rest of kitchen. francis would really enjoy it. thank you.	9/13/2005 Medium	Michael Mc Dermott Michael Munoz	Cafeteria	Loma Linda ES store room
4618	Work In Progress replace pump at lift station #2	8/17/2005 Medium	Ricardo Jacquez Ricardo Jacquez		Mesquite ES
4699	Work In Progress manny need your assistance w/ doors that are hard to open and close. thanx.	8/19/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
5054	Work In Progress NEED NAME PLATES MADE PER MS. PHILLIPS.NAMES TO BE FAXED.	8/30/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
5730	Work In Progress RUBEN RONQUILLO,NEED 4 1X6X8FT. BOARDS FOR COAT HOOKS.NEED 40 COAT HOOKS.THANX.	9/22/2005 Medium	Romauldo Apodaca Ruben Ronquillo		Mesquite ES
5952	Work In Progress attention ruben ronquillo,need 6 tires for gates.thanx.	9/29/2005 Medium	Romauldo Apodaca Ruben Ronquillo		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3558	Work In Progress need compresor changed out on armstrong unit in rm. 608.thanx.	7/14/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES
3955	Work In Progress DINING AREA - NEED TO WELD HINGES ON DOOR FALLING DOWN.	7/29/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
4340	Work In Progress manny need to assist w/ 2 doors in porables having hard time tpo close safety issue. also need lever handle.	8/9/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
5525	Work In Progress VACCUM CLEANER NEEDS TO BE FIX	9/15/2005 Medium	Ruben Solis Jimmy Carbajal	Custodial	Mesquite ES
3324	Work In Progress Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3346	Work In Progress Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
4005	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3971	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
4015	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
4017	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
3461	Work In Progress Need a copy of control key (core) to keep here at the Maintenance Dept - as per A. Holguin.	7/12/2005 Medium	Alfredo Holguin Manny Lozoya		Physical Plant Complex
3186	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
5526	Work In Progress NEED A "CB4" KEY FOR GUILLERMO - TO HAVE ACCESS TO ENERGY OFFICE TO CLEAN.	9/15/2005 Medium	Manny Lozoya		Physical Plant Complex
3379	Work In Progress Mens Restroom in Custodial Warehouse -Install new privacy lockset	7/7/2005 Low			Physical Plant Complex Restroom (Boys)

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3380	Work In Progress Mens Restroom in Custodial Warehouse- Replace toilet tank cover with appropriate size for unit.	7/7/2005 Medium	Fred Appelzoller	Restroom (Boys)	Physical Plant Complex
4545	Work In Progress 8/12/05 (1)paper work @ call contractors (5)2998 (1.5)measure for cabinets @ chaparral elem. (.5)back tp shop 8/12 - 3	8/12/2005 Medium	Danny Miranda Danny Miranda		Physical Plant Complex
3770	Work In Progress need window locks at s.t. elem.	7/22/2005 Medium	Danny Miranda Danny Miranda		Physical Plant Complex
5432	Work In Progress Auto Shop - need to install new door knob to new door at Angel's Office.	9/12/2005 Medium	Danny Miranda Manny Lozoya		Physical Plant Complex
5917	Work In Progress need lorenzo to stain new doors @ auto shop	9/28/2005 Medium	Danny Miranda Lorenzo Solis		Physical Plant Complex
5981	Work In Progress need to patch wall were water lines were removed	9/30/2005 Medium	Danny Miranda Danny Miranda		Physical Plant Complex
4585	Work In Progress Need to replace water heater,its giving out an extremeley bad odor.Health issue.	8/16/2005 Medium	Carlos Castillo Joe Ontiveros	Electrical Room	Physical Plant Complex
4221	Work In Progress 08/04/05 4.0 La Union E. Applied roof cement around Master cool unit and replaced insulation on duck work and ceiling tiles in the library. Work Order # 4066. 1.5 Cheked and replaced flash valve diaphram for new one. Work Order# 4181. 1.5 Replaced blown 20 amp fuse for master cool. 1.0 Road. 8/4 - 5	8/4/2005 Medium	Lorenzo Solis Lorenzo Solis		Physical Plant Complex
3940	Work In Progress MARTA JACQUEZ - A/C UNIT IS NOT WORKING AT ALL.	7/29/2005 Medium	Marta Jacquez Jaime Gomez		Physical Plant Complex
5121	Work In Progress Power Outage - El Paso Electric	8/29/2005 Medium	Margret Villalobos Enrique Sotelo		Physical Plant Complex
5735	Work In Progress AS PER ALFREDO I NEED A COPY OF KEY TO CUSTODIAL OFFICE. THANK YOU.	9/22/2005 Medium	Maritza Gonzalez Manny Lozoya		Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5806	Work In Progress As per Alfredo, wants shelves built in Julie's storage closet.	9/23/2005 Medium	Juliet Parra Danny Miranda		Physical Plant Complex
5589	Work In Progress Mechanical room to stairway to heating units. please clean and remove boxes and desk in front of electrical panels.	9/19/2005 Medium	Michael Munoz Adan Duran	Cafeteria	Riverside ES
5590	Work In Progress Need to replace electrical cord to cooler on line of serving. 1st peice of equipment as you enter serving line.	9/19/2005 Medium	Michael Munoz Danny Orozco	Cafeteria	Riverside ES
5614	Work In Progress Carpet and plastic cover (edge) into Room 17 is picking-up and is coming loose and you please check it and repair it.	9/19/2005 Medium	Olga Arias Michael Munoz		Riverside ES
5605	Work In Progress Having problems with Ticks in the Kinder Portables need to have rooms extremitted Rooms 503 and 506 outside .	9/19/2005 Medium	Olga Arias Margret Villalobos		Riverside ES
5609	Work In Progress Having prolems with Roaches and Black insect (Ticks) in rooms and Hallways, Storage area etc.. could we have the Whole building extremitted during intersession. We have no students at this time.	9/19/2005 Medium	Olga Arias Margret Villalobos		Riverside ES
5058	Work In Progress Carpet (Doorway) to Data clerk office is coming loose. Plastic edge is picking-up.. Thanks	8/30/2005 Medium	Olga Arias Michael Munoz		Riverside ES
5057	Work In Progress We need a new Door Knob placed in the Data Clerk office. (office area) At this time the door doesn't lock.	8/30/2005 Medium	Olga Arias Manny Lozoya		Riverside ES
3768	Work In Progress NEED APPLIANCE TRUCK TO MOVE SOME FIREPROOF CABINETS.	7/22/2005 Medium	Raul Romero Jimmy Carbajal	Classroom	Riverside ES
4998	Work In Progress NEED TO ORDER 2 R.R. PARTITIONS FOR RIVERSIDE ELEM.	8/29/2005 Medium	Danny Miranda Danny Miranda		Riverside ES
3326	Work In Progress Yearly - Riverside ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3414	Work In Progress MR LOZOYA MRS ARIAS IS HAVING TROUBLE WITH THE STORAGE ROOM LOCK WOULD LIKE FOR YOU TO LOOK AT IT THANK YOU SIR	7/8/2005 Medium	Adan Duran Manny Lozoya		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3415	Work In Progress MR JOSE AMBRIZ THE LITTLE ROOM WHERE WATER HEATER IS IN THE NEW WING IS GETTING HOT SETTING OFF ALARM NEED EXHUST FAN TO DRAW HEAT OUT THANK YOU SIR	7/8/2005 Medium	Adan Duran Jose Ambriz		Riverside ES
3778	Work In Progress MR DAVID VILLALOBOS WE HAVE SOME LEAKING FUACTS NEW WING NEED REPAIR KIT OR REPLACEMENT THANK YOU SIR	7/22/2005 Medium	Adan Duran David Villalobos		Riverside ES
3690	Work In Progress MR MANNY LOZOYA FILE CABINET NEW PORTABLE RM B NEEDS REPAIR WILL NOT LOCK PARTS MISSING THANK YOU SIR	7/19/2005 Medium	Adan Duran Manny Lozoya		Riverside ES
4388	Work In Progress MR JOSE AMBRIZ SIR WE NEED TO HOOK BACK UP THE AIR IN WHAT USE TO BE MRS FLORES OFFICE IT WAS REMOVE AT HER REQUEST AND ITS KIND OF WARM IN THERE THANK YOU SIR	8/9/2005 Medium	Adan Duran Jose Ambriz		Riverside ES
4473	Work In Progress MR MANNY LOZOYA SIR THE DOOR ON NEW PORTABLE IS STUCK IN LOCK CAN NOT GET IT TO UNLOCK PORTABLE B IN BACK THANK YOU SIR	8/11/2005 Medium	Adan Duran Manny Lozoya	Portables	Riverside ES
4500	Work In Progress MR CARLOS CASTILLO SIR WE HAVE SEVERAL EMERGENCY LIGHTS THAT NEED TO BE CHECKED NOT TURING ON ALSO WILL NEED SOME LIGHT BULBS FOR LIGHTS IN HALL WAY THANK YOU SIR	8/11/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
4596	Work In Progress MR MANNY LOYZOA SIR NEED TO CHANGE OUT DOOR HANDLE BY MRS ARIAS OFFICE THE ONE THERE DO NOT LOCK NEED ONE THAT CAN BE LOCKED THANK YOU SIR	8/16/2005 Medium	Adan Duran Manny Lozoya		Riverside ES
5115	Work In Progress MR LUPE ONTIVEROS SIR WILL NEED THE USE OF THE BACKHOE TO MOVE SOCCOR GOAL POST AWAY FROM PARKING AREA UNSAFE FOR KIDS THANK YOU SIR	8/31/2005 Medium	Adan Duran Guadalupe Ontiveros		Riverside ES
5301	Work In Progress MR ANGEL GONZALES SIR MY MOWER NEEDS BEARINS BLADE WILL NOT TURN ALSO NEEDS NEW BLADES MAY NEED FEN BELT ALSO THANK YOU SIR	9/6/2005 Medium	Adan Duran Angel Gonzales		Riverside ES
5766	Work In Progress MR LORENZO SOLIS SIR WILL NEED TO REPLACE FLOOR TILE IN NEW OFFICE AND BASE BOARD THANK YOU SIR	9/22/2005 Medium	Adan Duran Lorenzo Solis		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5657	Work In Progress MR CARLOS CASTILLO SIR WILL NEED TO MOVE ELECTRICAL BOX HIGHER IN THE WAY OF FILING CABINETS THANK YOU SIR	9/20/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
5659	Work In Progress MR CARLOS CASTILLO SIR WILL NEED SOME LIGHT BULBS FOR INSIDE OF HALL ALSO SOME BOXS OF FLORCENT BULBS FOUR BOXS WILL DO ME FOR NOW THANK YOU SIR	9/20/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
5592	Work In Progress please see what can be done to repair or remove electrical outlet on floor on serving line. Outlet has a can over it and could be a trip hazard.	9/19/2005 Medium	Danny Orozco	Cafeteria	Riverside ES
5588	Work In Progress Please clean return grill to heating unit located in the dinining area.	9/19/2005 Medium	Adan Duran	Cafeteria	Riverside ES
5960	Work In Progress around campus where new electrical conduit is along walls 4to 5 ft high.there are some support brackets for conduit that have sharp corners. could be a possible safety hazard. please see what you can put so no one will hurt.	9/29/2005 High	Adan Duran		Riverside ES
5246	Work In Progress Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
5258	Work In Progress Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3348	Work In Progress Yearly - Riverside ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
5212	Work In Progress Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3175	Work In Progress Monthly - San Miguel ES Roof Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
4488	Work In Progress File cabinet has a lock which does not lock-- locking mechanism comes out. Also need locks for two file cabinets.	8/11/2005 Medium	Barbara Cardenas Manny Lozoya	Classroom	San Miguel ES 21
4489	Work In Progress Need an extra key for these rooms.	8/11/2005 Medium	Barbara Cardenas Manny Lozoya	Classroom	San Miguel ES 25, 49,50

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5750	Work In Progress need tractor&scraper to remove goat-head stickers by play ground area.weeds also by fence line	9/22/2005 Medium	Danny Vega Guadalupe Ontiveros		San Miguel ES
5718	Work In Progress need additional outlets rm30	9/21/2005 Medium	Danny Vega Enrique Sotelo		San Miguel ES
5964	Work In Progress rm#47-48 need door to lock from #47 /door knob is key-less asap.	9/29/2005 Medium	Danny Vega Manny Lozoya		San Miguel ES
5307	Work In Progress portable #28 refrig unit not cooling/please check it out asap	9/7/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
5315	Work In Progress need replacement faucets for double sinks /kitchen .please stop by asap/	9/7/2005 Medium	Danny Vega Danny Orozco	Cafeteria	San Miguel ES
5175	Work In Progress RM21 DOOR WILL NOT OPEN/KEY JAMS IN CORE	9/2/2005 Medium	Danny Vega Manny Lozoya		San Miguel ES
5177	Work In Progress NEED FILTERS 12X24X1	9/2/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
5176	Work In Progress CAFETERIA GIRLS RR/SINK FAUCET BROKEN - OFF /PLEASE REPLACE/HOT-COLD TYPE	9/2/2005 Medium	Danny Vega Joe Ontiveros		San Miguel ES
5270	Work In Progress NEED LDO 2QT/FLUSH VALVE KIT/DIAPRAHMS/TUB&SINK SEALER/ELONGATED TIOLET SEAT	9/6/2005 Medium	Danny Vega Joe Ontiveros		San Miguel ES
3834	Work In Progress A/C UNIT NOT WORKING IN HIGH SPEED PORTABLE#58	7/26/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
4051	Work In Progress portable #30/rheem a/c unit not woking.stop by asap	8/1/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
4445	Work In Progress Portable 29 - Needs to be secured by the end of the day.	8/10/2005 Medium	Danny Vega Manny Lozoya	Portables	San Miguel ES
4447	Work In Progress principals office door hard to open/door needs to be shaved.stop by asap	8/10/2005 Medium	Danny Vega Manny Lozoya		San Miguel ES
5337	Work In Progress DISHWASHER LEAKING WATER. EVA MIRANDA - 233-2860	9/8/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4713	Work In Progress NEED SEVERAL KEYS MADE FOR CLASSROOMS. PLEASE SEE RITA IN OFFICE. ALSO, A REMINDER THAT WE NEED A KEY FOR MAILBX. THANKS.	8/19/2005 Medium	Rita Mendez Manny Lozoya		Santa Teresa ES
5872	Work In Progress ATTN. DAVID VILLALOBOS; DAVE , NEED FOR YOU TO CHECK OUT TOILETS IN RM. 107, AND ALSO THE ONE IN THE MENS FACULTY RR. FLOATS ARE STICKING.	9/27/2005 Medium	Gerardo Marquez David Villalobos		Santa Teresa ES
5725	Work In Progress ATTN; CALICASTILLO CALI COULD YOU PLEASE ORDER ME FOUR BOXES OF 4 FOOT FLOURECENT LAMPS. THANKS.	9/22/2005 Medium	Gerardo Marquez Carlos Castillo		Santa Teresa ES
5873	Work In Progress ATTN. J.AMBRIZ. JOSE, NEED FOR YOU TO COME AND CHECK OUT EXAUST FAN TO CAFET. AREAS. BELTS KEEP BREAKING, AND WHOLE UNIT IS SHAKING .	9/27/2005 Medium	Gerardo Marquez Jose Ambriz		Santa Teresa ES
4152	Work In Progress ATTN MANNY. MANNY, WE STILL NEED FOR YOU TO MAKE US ANOTHER KEY TO THE MAIL BOX. THANKS.	8/3/2005 Medium	Gerardo Marquez Manny Lozoya		Santa Teresa ES
4154	Work In Progress ATTN LUPE, LUPE, WE STILL NEED THE COBBLESTONE TO KEEP CHECK THE RAIN ERROSION. ALSO NEED FOR BETO AND MANNY TO REDIG TRENCH AT BACK FENCE TO KEEP RAIN FROM FLOODING GROUNDS AND CLASS RMS.	8/3/2005 Medium	Gerardo Marquez Guadalupe Ontiveros		Santa Teresa ES
4572	Work In Progress 8/5/05 1-INSP. BLDG.AND GRNDS. PICKED UP TRASH. 1-INSP. VEHICLE AND COMM. EQUIP. 2-WENT TO PPD. TO TURN IN TIME AND PICK UP MATERIAL. 1-CHECKED OUT VAULT, AND TOOK MEASUREMENTS FOR SHELFs. 1-CHECKED OUT PORTABLE AIR UNIT IN TESTING RM. AND CLEANED UP WATER. 1-ADJ. ROLLERS ON GATES. 1-RECHECKED CAFET. FOR GAS SMELL. 8/5 - 8	8/15/2005 Medium	Gerardo Marquez Gerardo Marquez		Santa Teresa ES
3657	Work In Progress ATTN. Manny . NEED FOR YOU TO DUPLICATE A KEY TO THE MAIL BOX . THANKS .	7/19/2005 Medium	Gerardo Marquez Manny Lozoya		Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4021	Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
5198	Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
4009	Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
3958	Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
5260	Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
5248	Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
4636	Work In Progress EL Paso Disposal - Need a key to get into the second gate in order to pick up the trash.	8/17/2005 Medium	Manny Lozoya		Santa Teresa ES
5250	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
5261	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
4484	Work In Progress please install venting system and exhaust hood in the metal shop. See Joe Angelo.	8/11/2005 Medium	Jose Ambriz		Santa Teresa HS
5214	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3176	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3351	Work In Progress Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3329	Work In Progress Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3158	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
4613	Work In Progress Need a bucket operator and a bucket truck at STHS football field some time this week.	8/16/2005 Medium	Carlos Vigil Danny Orozco	Football Field	Santa Teresa HS
3630	Work In Progress NEED A MD 10 AND A #478 FOR GROUNDS AND FOOTBALL STORAGE	7/18/2005 Medium	Arturo Nunez Manny Lozoya		Santa Teresa HS
4476	Work In Progress NEED KEYS FOR TEACHERS MAILBOXES MADE OR LOCKS CHANGED. THANK YOU	8/11/2005 Medium	Arturo Nunez Manny Lozoya		Santa Teresa HS
4346	Work In Progress NEED TO FUMIGATE VOC. SHOPS TO MANNY CRIKETS, ANTS, ETC,ETC.	8/9/2005 Medium	Arturo Nunez Margret Villalobos		Santa Teresa HS
4465	Work In Progress NEED 1/4 INCH GAS VALVE TO PILOT , ON BOILER #1 ON NEW SYSTEM REPLACED, LEAKING REAL BAD,	8/11/2005 Medium	Arturo Nunez David Villalobos		Santa Teresa HS
3571	Work In Progress NEED CONDENSER MTR. FOR SNACK ROOM A.C. UNIT, MTR. IS FROZEN UNIT IS DOWN.	7/15/2005 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS
5903	Work In Progress Due to gas lines being broken yesterday-when Manager turned on Ovens this morning she is having problems (one oven is not heating up enough and the other one-- the blower is not working). Olga Bustamante - SNP Manager 589-5332	9/28/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Santa Teresa HS
5923	Work In Progress MIKE MUNOZ WE NEED BARRIER FENCE ON WEST SIDE AT SOCCER FIELD TO RETAIN BALLS OUT IT PLAY . ALSO NEED FENCE FROM 20 YARD LINE TO 20 YARD LINE IN FRONT OF FOOTBALL VISITORS SEATING AREA. SEE R GALLEGOS THANK YOU MIKE...	9/28/2005 Medium	Joel Herrera Michael Munoz		Santa Teresa HS
4966	Work In Progress RUBEN WE NEED REPAIR THE WINDOWS AT DAYCAREBUILDING IT DOESN'T OPEN THANK YOU Route to Joel as per Mike 9/12/05 - mkv	8/26/2005 Medium	Joel Herrera Joel Herrera		Santa Teresa HS
5102	Work In Progress WE NEED REPLACE MA 51 AND TREE LOCKS AT R.O.T.C CLASS ROOMS.	8/30/2005 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4857	Work In Progress MIKE, BLEACHERS RIGHTSIDE IT DOESN'T WORK WE NEED REPAIR AT G.Y.M AREA	8/24/2005 Medium	Joel Herrera Michael Munoz		Santa Teresa HS
4807	Work In Progress MANNY MY MASTER KEY IS BROKEN IT DOESN'T WORK NO MORE.	8/23/2005 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS
3452	Work In Progress 7-06-05 8.0 PAINTING CLASS ROOMS 7/6 - 8	7/11/2005 Medium	Joel Herrera Joel Herrera		Santa Teresa HS
4454	Work In Progress SMASHED WINDOW ON DOOR - STOLEN LARGE SCREEN TV. DISCOVERED BY MR. BUCKLEY	8/1/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
4463	Work In Progress SENER ON SINCK AT GIRLS REST ROOM IT DOESN'T WORK WE REPLACE IT .	8/11/2005 Medium	Joel Herrera David Villalobos		Santa Teresa HS
4306	Work In Progress 8-08-05 RUBEN RONQUILLO I NEED TWO BATTERYYS FOR MY CORDLESS SIZE 14.4 V MY BATTERYYS NOT GOOD NO MORE THANK YOU RUBEN	8/8/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
4186	Work In Progress Milk Cooler not cooling at all. Olga B. Snp Manager 589-5332	8/4/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Santa Teresa HS
5449	Work In Progress Kitchen - Check all door seals as per pest control company.	9/12/2005 Medium	Margret Villalobos Danny Orozco	Cafeteria	Santa Teresa HS
5450	Work In Progress Kitchen - Check all door seals as per pest control company.	9/12/2005 Medium	Margret Villalobos Danny Orozco	Cafeteria	Santa Teresa MS
5749	Work In Progress FILING CABINET IN PORTABLE 1-B NEEDS A KEY TO LOCK FILES	9/22/2005 Medium	Laura Parra Manny Lozoya		Santa Teresa MS
5113	Work In Progress AIR CONDITIONER DOES NOT TURN ON THE LEFT SIDE OF THE ROOM FACING CHALK BOARD ROOM 3 MR. DORANTES	8/31/2005 Medium	Laura Parra Jose Ambriz	Classroom	Santa Teresa MS
4720	Work In Progress POWER STRIP ON WEST SIDE OF ROOM IS NOT WORKING IN ROOM 52	8/19/2005 Medium	Laura Parra Jaime Mijarez	Classroom	Santa Teresa MS ROOM # 52

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4506	Work In Progress Need to replace all condensate pumps for all geothermo units, trough all school.	8/12/2005 Medium	Lorenzo Solis Jose Ambriz		Santa Teresa MS
3387	Work In Progress Rm 1. N. bldg lower level Removal of carpet is going to require tile installation. Alfredo H. requested a work order for contractor.	7/7/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
3412	Work In Progress S.bldg upper level. Because of the shortage of classrooms Mrs. williams has to move the teachers lounge to a storage rm. The floor has no tile, can you include this room with the area's that the contractor will be installing floor tile. Attn: Alfredo holguin.	7/8/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
3465	Work In Progress N.bldg home ec rm 10. Ruben Ronquillo I am going to need a Miter saw to cut legs on ten of the tables. please make sure it has a good blade. I am planning this project for next week (7/18/05.) The wood is oak.	7/12/2005 Medium	Jaime Mijarez Ruben Ronquillo		Santa Teresa MS
3364	Work In Progress S.bldg custodial storage. please make 2ea. A-7 keys for principal and building mechanic.	7/6/2005 Medium	Jaime Mijarez Manny Lozoya		Santa Teresa MS
4719	Work In Progress School planters. As per Mrs. williams she wants the planters to be filled with rocks. She already talked to Lupe ontiveros.	8/19/2005 Medium	Jaime Mijarez Guadalupe Ontiveros		Santa Teresa MS
4806	Work In Progress North and South bldgs. Condensation pumps are starting to give out. I am going to need help to start replacing them. I have been getting call after call of water spilling into classroom which requires changing damaged ceiling tiles. Attn: Joe A.	8/23/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
5149	Work In Progress N.bldg Rm 3. Mrs. williams would like to have a sidewalk that goes from Rm 3 exit door out to the fence. This way when there is a fire drill the special ed students on wheel chairs can be moved away from the building in case of an actual emergency.	9/1/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
5329	Work In Progress North & South - I lost communication to both buildings and i am getting constant calls of hot areas. I am getting a message of an error on the IP address.	9/8/2005 Medium	Jaime Mijarez Margret Villalobos		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5683	Work In Progress Rm 1. heat pump has a hole in condensate pan and causing water to drain on to ceiling tiles. Attn: joe ambriz.	9/21/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
5685	Work In Progress principals office. install a dead bolt lock on door. Need to see Mrs.williams on this work order. Attn: Manny I.	9/21/2005 Medium	Jaime Mijarez Manny Lozoya		Santa Teresa MS
5363	Work In Progress N.bldg maintenance and custodial. Would like a duct and register installed on heat pump.	9/9/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
5515	Work In Progress Gym. I need the scissor lift as soon as possible to check a suspended heating unit for any damage. Mike munoz is aware of this problem.	9/14/2005 Medium	Jaime Mijarez Ruben Ronquillo		Santa Teresa MS
4641	Work In Progress THERE A BOYS URINAL THAT IS CRACK FROM THE BOTTOM AND EVERY TIME THEY FLUSH IT WATER COMES OUT.SEE MR. RODRIGUEZ.	8/17/2005 Medium	Ismael Rodriguez David Villalobos	Restroom (Boys)	Santa Teresa MS
5308	Work In Progress I NEED A KEY A7 FOR THE PRINCIPAL TO HAVE ACCESS TO MY STORAGE ROOM. THANK YOU.SEE MR. RODRIGUEZ.	9/7/2005 Medium	Ismael Rodriguez Manny Lozoya	Custodial	Santa Teresa MS
5680	Work In Progress MANNY I NEED FOR YOU TO CHANGE A KEY CYLINDER FOR SEVENTH GRADE COUNSLER OFFICE.SEE MR. RODRIGUEZ THANK YOU.	9/21/2005 Medium	Ismael Rodriguez Manny Lozoya	Office	Santa Teresa MS
3118	Work In Progress I NEED FOR GYM KEY CYLINDERS TOO TO BE CHANGE BEFORE 7/13/05.CONT.MR.RODRIGUEZ.	7/1/2005 Medium	Ismael Rodriguez Manny Lozoya		Santa Teresa MS
3353	Work In Progress Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3330	Work In Progress Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
5215	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
4023	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
4013	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3975	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
5262	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
5252	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3423	Work In Progress Yearly - Sunland Park ES Emer. Light Test: Annual - Refer to PM schedule details.	7/10/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3160	Work In Progress Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3355	Work In Progress Yearly - Sunland Park ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3179	Work In Progress Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3278	Work In Progress Monthly - Sunland Park ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3268	Work In Progress Monthly - Sunland Park ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3875	Work In Progress NEED REPLACEMENT KEYS FOR NURSE'S OFFICE DORR AND FILE CABINET	7/27/2005 Medium	Irene Trujillo Manny Lozoya		Sunland Park ES
4171	Work In Progress ROOM #25 IIGHTS IN THE CLASSROOM DO NOT TURN OFF.	8/3/2005 Medium	Irene Trujillo Carlos Castillo		Sunland Park ES
5687	Work In Progress We have a mice problem throughout the school. Please help!	9/21/2005 Medium	Irene Trujillo Margret Villalobos		Sunland Park ES
5422	Work In Progress NEED TO REMOVED DEAD TREES.	9/12/2005 Medium	Irene Trujillo Guadalupe Ontiveros		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4868	Work In Progress BLACK WIDOW SPIDERS, SCORPIONS, ETC. HAVE BEEN FOUND INTHE CLASSROOMS, PLAYGROUND, AND HALLS OF THIS SCHOOL. PLEASE SEND SOMEONE TO SPRAY. FAXED PO 9/1/05	8/24/2005 Medium	Irene Trujillo Margret Villalobos		Sunland Park ES
4927	Work In Progress a sign is needed to read "Delivery Trucks Only"	8/25/2005 Medium	Irene Trujillo Ruben Ronquillo		Sunland Park ES
5474	Work In Progress Need to replace glass window 1=10"X10" 1/8 2=12 1/4X21 1/4 thank you	9/13/2005 Medium	Sebastian Diaz Ruben Ronquillo		Sunland Park ES
5888	Work In Progress 9/27/05 Need to fix water line sprinkler under the sidewalk in the new playground thank you	9/27/2005 9/28/2005 Medium	Sebastian Diaz Guadalupe Ontiveros		Sunland Park ES
5195	Work In Progress 9/2/05 Lupe Ontiveros Need the heavy tractor to remove the weeds around the school thank you	9/2/2005 Medium	Sebastian Diaz Guadalupe Ontiveros		Sunland Park ES
4732	Work In Progress 8/19/05 2-welding and install gate northwest entrance 4-cut grass with the tractor 2-went to main office to pick up materal 8/19 - 8	8/19/2005 Medium	Sebastian Diaz Sebastian Diaz		Sunland Park ES
3436	Work In Progress 7/11/05 need to replace door knob in main entrance northwest and check some doors need parts thank you	7/11/2005 Medium	Sebastian Diaz Manny Lozoya		Sunland Park ES
5190	Work In Progress As per Nurse Creegan & Mr. Chavez request would like the 2 rooms fumigated where they had the infestation. (Spoke to Daniel he said they could send someone out on Tuesday.	9/2/2005 Medium	Richard Chavez Margret Villalobos		Sunrise ES
3533	Work In Progress Could you turn the air conditioning on we have teachers coming in to get a head start on their rooms. It is very hot and we would greatly appreciate it. Since we are a year round school the teachers need to report on Monday. Thank-you	7/14/2005 Medium	Joanne Munoz Jaime Gomez	Classroom	Sunrise ES
3477	Work In Progress I NEED SAND FOR THE PLAY GROUNDS, THANKS.	7/12/2005 Medium	Paul Quinones Lorenzo Hernandez		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3469	Work In Progress FENCING AREA IN BACK OF SCHOOL NEAR LIFT STATION NEEDS TO BE REPAIRED,AND ROLL GATE.PROBABLE HIGH WINDS ON 7-11-05 CAUSED THE DAMAGE.NO SIGNS OF VANDILISM ON SCHOOL PROPERTY	7/12/2005 Medium	Paul Quinones Michael Munoz		Sunrise ES
3876	Work In Progress RM.307,BAD CIRCULATING PUMP NEED TO REPLACE	7/27/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
4920	Work In Progress Infestation of bug at school site office. (Health Issue)	8/25/2005 Medium	Alfredo Holguin Margret Villalobos		Sunrise ES
5199	Work In Progress Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
5255	Work In Progress Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
5331	Work In Progress Treat inside and outside of perimeter for insects. Note: Service setup w/principal on 9/9/05 at 3:00pm) - B. Watson Open Purchase Order!	9/8/2005 Medium	Alfredo Holguin Margret Villalobos		Sunrise ES
5264	Work In Progress Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
3629	Work In Progress please cut and weedeat in and aroud lift station. weeds are growing rapid and are going to end up on the playing fields.	7/18/2005 Medium	Paul Quinones		Sunrise ES
4628	Work In Progress Need to meet contractor on Monday - to rekey school site.	8/17/2005 Medium	David Boyd Manny Lozoya		Vado ES
4722	Work In Progress Needs 2 master keys for Vado Elementary.	8/19/2005 Medium	David Boyd Manny Lozoya		Vado ES