

# 1034 - Work Orders In Progress (7/1/05 - 11/30/05)

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7753	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
7774	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
7775	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3308	Work In Progress Yearly - Alma Del Valle Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3312	Work In Progress Yearly - Alma Del Valle Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3960	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3981	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3982	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
6221	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Jimmy Carbajal		Anthony ES
7776	Work In Progress Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
7778	Work In Progress Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
7754	Work In Progress Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6005	Work In Progress Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
1862	Work In Progress New unit that was installed in Nurces area is not sufficient. Need to provide more cooling. Please see Mike	5/11/2005 Medium	Jaime Gomez		Anthony ES
4097	Work In Progress please scrape and add crusher fine along with parking curbs.see mike	8/2/2005 Medium	Guadalupe Ontiveros		Anthony ES
4487	Work In Progress plese grade and add crusher fine for neww parking for parents and add parking curbs.	8/11/2005 Medium	Guadalupe Ontiveros		Anthony ES
6953	Work In Progress please cut a total of 3 gates that are to long. 1/2 swing, 1/2 roll. 1) on 4th st and 2 on church.	11/2/2005 Medium	Michael Munoz		Anthony ES
3661	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Carlos Lujan		Anthony ES
766	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Carlos Lujan		Anthony ES
2867	Work In Progress need four sinks Anthony elem girls r.r.`s	6/20/2005 Medium	Danny Miranda Fred Appelzoller		Anthony ES
3899	Work In Progress Room 201 - Half of the carpet is bad replace with tile. 11/29/05 - Teacher requesting status on this work order on 11/10/05 a student fell and hurt her leg. -mkv	7/28/2005 Medium	Hector Villalobos Michael Munoz	Classroom	Anthony ES
4255	Work In Progress room 109 needs carpet repair	8/8/2005 Medium	Hector Villalobos Michael Munoz	Classroom	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4581	Work In Progress old main bldg a/c motor burn out a 3 hp volts 230	8/15/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
4478	Work In Progress Chapter bg p.e room replace 3/4 motor with a 1hp motor	8/11/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
4742	Work In Progress need a 3/4 hp motor cafeteira motor burn out old cafeteria	8/22/2005 Medium	Hector Villalobos Jaime Gomez	Cafeteria	Anthony ES
4743	Work In Progress mild cafeteria burn motor 3/4 hp with a belt 4-L 660 or 670	8/22/2005 Medium	Hector Villalobos Jaime Gomez	Cafeteria	Anthony ES
4861	Work In Progress Nurse office refrigerator is not working water is leaking from seal	8/24/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
331	Work In Progress need 8 sheet metal plates 20x20	3/11/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
205	Work In Progress Annex Bldg Girls rr - Broken window 45 1/2 x 14 3/4.	3/9/2005 Medium	Hector Villalobos Ruben Ronquillo	Restroom (Girls)	Anthony ES Annex Bldg
102	Work In Progress need to remove dirt with tractor by dumpster	3/7/2005 Medium	Hector Villalobos Lorenzo Hernandez	Cafeteria	Anthony ES
103	Work In Progress boiler room we have a leak in pipe line	3/7/2005 Medium	Hector Villalobos Jaime Gomez	Mechanical Room	Anthony ES
228	Work In Progress pt 217 replace heating and cooling	3/10/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
1321	Work In Progress hook up electrial power to storage outside	4/21/2005 Medium	Hector Villalobos Enrique Sotelo	Athletic Field	Anthony ES
823	Work In Progress ALL windows in old primary bldg do not open Route to Danny Miranda as per Mike 9/12/05 - mkv	4/4/2005 Medium	Hector Villalobos Danny Miranda	Classroom	Anthony ES
623	Work In Progress 3/18/05 1. check boilers 1.5 go to shop put gas pick up supplies 5.5 pruning trees by football field	3/24/2005 Medium	Hector Villalobos Hector Villalobos		Anthony ES
764	Work In Progress rooms 3 4 5 6 7 8 emergency windows do not open Route to Danny Miranda as per Mike. 9/12/05 - mkv	4/1/2005 Medium	Hector Villalobos Danny Miranda	Classroom	Anthony ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
1038	Work In Progress replace a/c unit in cafeteria 63 a/c unit	4/11/2005 Medium	Hector Villalobos Jaime Gomez	Cafeteria	Anthony ES
1039	Work In Progress primary office to replace 45 sidedraft master cool	4/11/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
2629	Work In Progress On 5/11/05 they spray one room at daycace center they need to spray all daycare rooms FAXED PO# 4501399 6/16/05-MKV	6/8/2005 Medium	Hector Villalobos Margret Villalobos	Classroom	Anthony ES
2812	Work In Progress Mrs marquez is requesting that the old cabinets in the old main blg and mild blg lounge be replace	6/16/2005 Medium	Hector Villalobos Danny Miranda		Anthony ES
2390	Work In Progress room 207 door will not lock need to fix a.s. a. p. for today	5/31/2005 Medium	Hector Villalobos Manny Lozoya	Classroom	Anthony ES
7566	Work In Progress Bathroom dry walls need to be replace or panel	11/28/2005 Medium	Hector Villalobos Danny Miranda	Mechanical Room	Anthony ES
7610	Work In Progress Annex Bldg Room 201 - Need to spray for roaches.	11/29/2005 Medium	Hector Villalobos Margret Villalobos		Anthony ES
7339	Work In Progress Custodial storage faucet is leaking need to replace faucet	11/14/2005 Medium	Hector Villalobos Joe Ontiveros	Custodial	Anthony ES
7340	Work In Progress Hallway need to hook up wires for backup lights	11/14/2005 Medium	Hector Villalobos Enrique Sotelo	Hallway/Corridor	Anthony ES
5944	Work In Progress Old main blg boiler room needs a thermocuple size 56 inch	9/29/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
5992	Work In Progress upper primary boiler is leaking replace	9/30/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
6586	Work In Progress heater is not working need to replace parts	10/20/2005 Medium	Hector Villalobos Jose Ambriz	Cafeteria	Anthony ES
6587	Work In Progress Boiler needs parts valve is leaking	10/20/2005 Medium	Hector Villalobos Jaime Gomez	Mechanical Room	Anthony ES
6588	Work In Progress Chapter blg p.e room heater needs parts	10/20/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
5090	Work In Progress new oven is completely down.  Becky S. SNP Mgr 882-3507	8/30/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7188	Work In Progress ANTHONY 4-6 CAMPUS - ICE MACHINE NOT WORKING. NOTICED THIS MORNING THERE WAS NO ICE.  BECKY S. AE SNP MGR 882-3507	11/8/2005 Medium	Jacqueline Aguilar Danny Orozco	Computer Lab	Anthony ES
4059	Work In Progress DAYCARE - NEED TO ISSUE KEYS TO CORINA VALDESPINO for (Krishna's Office). WILL BE HERE AT 8:00 AM TOMORROW.	8/1/2005 Medium	Margret Villalobos Manny Lozoya		Anthony ES
7231	Work In Progress HEATER ON SOUTHWEST SIDE OF GYM NOT WORKING NEEDS TO BE CHECK OUT	11/9/2005 Medium	Ramiro Holguin Lorenzo Solis		Berino ES
6447	Work In Progress DISHWASHER CHEMICAL DISPENSERS NOT WORKING RIGHT HAS TO BE CHECK OUT	10/17/2005 Medium	Ramiro Holguin Danny Orozco		Berino ES
2551	Work In Progress 5/26/05 0.5 CHECK WITH JIMMY CLOSE GATES 1.0 CHECKING WITH TEACHERS ON ROOMS TO BE PAINTED 0.5 UNCLOG TOILET ROOM 100 2.0 HELP RAUL CHECK WELLS 1.0 CHANGE OUT ELECTRICAL BALLAST TEACHERS LOUNGE 0.5 REPAIR BROKEN ELECTRICAL OUTLET IN GYM 1.5 CHECK ALL SPRINKLERS IN PLAYGROUND CHANGE OUT THE ONES NOT WORKING FILL OUT DAILY WORK LOG  5/26 - 7	6/6/2005 Medium	Ramiro Holguin Ramiro Holguin		Berino ES
846	Work In Progress JAIME GOMEZ NEED TO REPLACE FOUR A/C UNITS WESTWING 131,128 ON EASTWING 103,107 ALL 6500	4/5/2005 Medium	Ramiro Holguin Jaime Gomez		Berino ES
203	Work In Progress NEED PLAYGROUND FERTELIZES	3/9/2005 Medium	Ramiro Holguin Lorenzo Hernandez		Berino ES
720	Work In Progress PLAYGROUND NEEDS TO BE AERATED	3/31/2005 Medium	Ramiro Holguin Lorenzo Hernandez		Berino ES
1977	Work In Progress 5/17/05 GROUNDS NEED TRACTOR TO REMOVE BROKEN CONCRETE AND CONCRETE SLAP TO RELOCATE SEE-SAW	5/17/2005 Medium	Ramiro Holguin Lorenzo Hernandez		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2247	Work In Progress MANNY LOZOYA PORTABLE 140 DOOR NEEDS CLOSURE AND PORTABLE 151 CORE IN HANDLE NEEDS TO BE CHECK OUT KEYS DO NOT WORK	5/24/2005 Medium	Ramiro Holguin Manny Lozoya		Berino ES
3434	Work In Progress WASHING MACHINE DOES NOT WORK ANY MORE. (IT GAVE UP)  ELSA CHAIRZ - SNP MGR 882-2417	7/11/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Berino ES
2480	Work In Progress CONNECT UTILITIES TO PORTABLES (4).	6/3/2005 Medium	Fred Appenzoller Fred Appenzoller		Berino ES PORTABLES
2222	Work In Progress Room 140 - Need to replace door closer.	5/23/2005 Medium	Hector Lozoya Danny Miranda		Berino ES
5338	Work In Progress WALK - IN FREEZER IS LEAKING ALOT OF WATER BETWEEN THE FREEZER AND REFRIG.  ELSA - 882-2417	9/8/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Berino ES
5585	Work In Progress need nemaster b key and 55key for new custodian thanks a.s. p	9/19/2005 Medium	Jimmy Cortez Manny Lozoya		Berino ES
2817	Work In Progress 1-6 TO 8FT DOOM SKYLIGHT BROKEN AND A/C UNIT CAVED IN. MIKE WILLIAMS-DEPUTY (Pending Skylight) WITNESSED 3 TEENAGERS WALKING INTO BLDG 2 JUMP ON TO WALK-IN FREEZER AND TO BLDG (CALLED SHERIFF) - JIMMY CORTEZ  SKYLIGHT WORK ORDER IS PENDING - A/C UNIT WAS PUSH UP (COVER) - 7/13 R. HOLGUIN	6/16/2005 Medium	Jimmy Cortez Ramiro Holguin		Berino ES
441	Work In Progress CHARGER NEEDS TO BE FIXED AGAIN	3/16/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES
5898	Work In Progress Need 2 new keys for office gate and recut master key for Mr Silva THANKS OFFICE KEY IS ON YOUR KEY CHAIN ALREADY	9/28/2005 Medium	Jimmy Cortez Manny Lozoya		Berino ES
7409	Work In Progress vaccum needs repair need s tire new handle	11/16/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES
7410	Work In Progress need new vaccum bag	11/16/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES
7406	Work In Progress need 4 new belts for vaccum thanks	11/16/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7664	Work In Progress vaccum needs to be worked on might need new case in thanks	11/30/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES
4208	Work In Progress MOBILE HOME OCCUPANT WILL BE RECEIVING NEW MOBILE HOME ON APPROXIMATELY 8-29- 05. PLEASE CONNECT ELECTRICAL. 28X54	8/4/2005 Medium	Enrique Sotelo		Berino ES
4055	Work In Progress please cut weeds and pick-up debre on east side of rockwall. (i.e weeds bottles cinder blocks.)	8/1/2005 Medium	Ramiro Holguin		Berino ES
2956	Work In Progress please check all portables and see if all blocking cinder blocks are placed properly and repair if neede.	6/23/2005 High	Ramiro Holguin	Parking Lot	Berino ES
7755	Work In Progress Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
7059	Work In Progress Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
7081	Work In Progress Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
7084	Work In Progress Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
7780	Work In Progress Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
7777	Work In Progress Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
6222	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Jimmy Cortez		Berino ES
4082	Work In Progress Monitoring Wells - I need a set of keys to the monitoring well caps	8/2/2005 Medium	Alfredo Holguin Manny Lozoya		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6123	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
7779	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
7820	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
7756	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
4518	Work In Progress please replace urinal and commode in mens restroom.	8/12/2005 Medium	Joe Ontiveros	Mechanical Room	Chaparral ES
7701	Work In Progress library. need install electrical outlets for the computers	12/1/2005 Medium	Juan Vargas Enrique Sotelo		Chaparral ES
7702	Work In Progress library need to install computers cables to 8-foot the wall	12/1/2005 Medium	Juan Vargas Enrique Sotelo		Chaparral ES
7829	Work In Progress cafeteria need move a/c duct more up	12/5/2005 Medium	Juan Vargas Lorenzo Solis		Chaparral ES
7830	Work In Progress room 46 and nurse is too cold need check heater	12/5/2005 Medium	Juan Vargas Lorenzo Solis		Chaparral ES
7376	Work In Progress portables and e. wing need doors replace	11/15/2005 Medium	Juan Vargas Danny Miranda		Chaparral ES
7378	Work In Progress music room and gym. need doors replace	11/15/2005 Medium	Juan Vargas Danny Miranda		Chaparral ES
7646	Work In Progress evenstar playgroun need water fouting fix	11/30/2005 Medium	Juan Vargas Joe Ontiveros		Chaparral ES
7357	Work In Progress LUPE . nesesito que quemen las ramas atras o aser el hoyo mas grande	11/15/2005 Medium	Juan Vargas Guadalupe Ontiveros		Chaparral ES
7359	Work In Progress 2 request e. wing rooms need to repair windows	11/15/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
7360	Work In Progress rooms 79 71 70 83 need 12 blinds size 33 width 58 length	11/15/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5951	Work In Progress room 31 need change 8 fluorescent lighting troffer	9/29/2005 Medium	Juan Vargas Enrique Sotelo		Chaparral ES
6728	Work In Progress ruben nesesito 4 metal signs 1-principal 1-secretary 2-assistant principal y tambien los tubos	10/25/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
6502	Work In Progress room 72 heating not work need help to fix	10/18/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
6343	Work In Progress las vanquetas need grabo a round	10/12/2005 Medium	Juan Vargas Guadalupe Ontiveros		Chaparral ES
6415	Work In Progress cafeteria exit sign need change	10/14/2005 Medium	Juan Vargas Enrique Sotelo		Chaparral ES
1422	Work In Progress 04/26/05/jaime gomes library need 3 new master cools	4/26/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
1871	Work In Progress 05/11/05/ jaime gomes cafeteria need new air conditioning	5/12/2005 Medium	Juan Vargas Jaime Gomez	Cafeteria	Chaparral ES
2121	Work In Progress Air condition on cosesion stand need new motor 2 peed	5/19/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
2314	Work In Progress 05/26/05 lorenzo nesesito ayada para ubicar los sprinklers	5/26/2005 Medium	Juan Vargas Lorenzo Hernandez		Chaparral ES
2738	Work In Progress 06/13/05 mike munos need to clean the parking	6/13/2005 Medium	Juan Vargas		Chaparral ES
2486	Work In Progress 05/31/05 2- put round up round the school 4- limpiar los techos 2- regar los arboles 5/31-8	6/3/2005 Medium	Juan Vargas Juan Vargas		Chaparral ES
3284	Work In Progress 07/05/05 mike munoz Mr. cardona quiere bertical blind en su oficina size 82 width and 80 length	7/5/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
2829	Work In Progress 06/16/05 rooms 81 82 and 72 need window repair	6/16/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
2760	Work In Progress SECURE STORAGE	6/14/2005 Medium	Juan Vargas Manny Lozoya		Chaparral ES
4602	Work In Progress ruben ronquillo need 10 pvc 45 elbows 6 inches 10 square grate basin 6 inches and 200 ft. 6 inches pvc pipe	8/16/2005 Medium	Juan Vargas Joe Ontiveros		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5053	Work In Progress need to be replaced front area gate doors and chain link fence as mr. cardona	8/30/2005 Medium	Juan Vargas Michael Munoz		Chaparral ES
3846	Work In Progress 07/26/05 j. gomes rooms 2 -20-21- 51-47-107-44- 55-46- need replace A/C 6500	7/26/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
3800	Work In Progress 07/25/05 jaime gomes main office need new A/C two 4500 and one 6500	7/25/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
3801	Work In Progress 5/25/05/ mike neseito que pongan sistema de riego para los arboles	7/25/2005 Medium	Juan Vargas Guadalupe Ontiveros		Chaparral ES
3868	Work In Progress ROOMS 83-82-81-80-72-96-70 NEED WINDOWS REPAIRED OR REPLACE 2-REPORT	7/27/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
4030	Work In Progress Room 47 need to instaled a/c ventilation	8/1/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
4213	Work In Progress Rooms 101-102-60-62-61-54-70-96-72-73-97 80-82-83 need carpet repace	8/4/2005 Medium	Juan Vargas Michael Munoz		Chaparral ES
7647	Work In Progress ONE OVEN IS TO HOT AND THE OTHER IS OVEN IS LOW HEAT. IF YOU HAVE ANY QUESTIONS CALL MARK KING - 346-9237. REQUESTED BY MR. G.	11/30/2005 Medium	Jacqueline Aguilar Danny Orozco	Computer Lab	Chaparral ES
3299	Work In Progress I need some keys for two of the new administators who will be coming to this school. They have requested main keys to the gate that opens up the fence outside the school and also a set of main keys for the building. If you can please do as soon as possible. Keys for Chaparral Elementary.	7/5/2005 Medium	Jennifer Corral Manny Lozoya	Office	Chaparral ES
2536	Work In Progress Meza lost keys:He did pay to replace the ones he lost. Meza is room # 130. Rosalinda Mendez would like keys to her filing cabinet. She never got any keys, she has been having to borrow the keys in the office. Mendez is in room #122. Manuela Ledesma needs keys for her room. She never received any. She is room # 114. 9/7 - Manny, Mr. Meza is requesting on status of key.- mkv ref wo 4337	6/6/2005 Medium	Jennifer Corral Manny Lozoya	Classroom	Chaparral ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
4110	Work In Progress Rm-72 Ms. Barret needs screens on her windows. Says they were suppose to be put in last year.	8/3/2005 Medium	Jennifer Corral Ruben Ronquillo	Classroom	Chaparral ES
3945	Work In Progress Air Conditioner smells like burn and is not cold in rm-128 for Ms. Word	7/29/2005 Medium	Jennifer Corral Jaime Gomez	Classroom	Chaparral ES
3946	Work In Progress Air Conditioner not working in rm-20 for Ms. Gary	7/29/2005 Medium	Jennifer Corral Jaime Gomez	Classroom	Chaparral ES
3871	Work In Progress need an extra key for Even start classroom, Jeannette rm-118	7/27/2005 Medium	Jennifer Corral Manny Lozoya	Classroom	Chaparral ES
3785	Work In Progress NEED A KEY FOR ROOM 114,LEDESMA REPRINT FOR MANNY - REGARDING E-MAIL 7/27/05 - MKV	7/22/2005 Medium	Jennifer Corral Manny Lozoya	Classroom	Chaparral ES
6913	Work In Progress needs electrical wiring for 4 center poles. Surge protectors are being overloaded, causing system to shut down. Printer in computer lab needs to be installed.A.S.A.P Rm- computer lab, Ms. Elkurdi	11/1/2005 Medium	Jennifer Corral Enrique Sotelo	Computer Lab	Chaparral ES
6529	Work In Progress Had done a work order before for Ms. Barrett about fixing her windows needs a screen.She says they still haven't done the work order. Thanks	10/18/2005 Medium	Jennifer Corral Ruben Ronquillo	Classroom	Chaparral ES
7710	Work In Progress Window in rm-72 is falling out. When opened it falls out. Doesn't stay up alone needs a stick to hold it up. See Ms. Barrett.	12/1/2005 Medium	Jennifer Corral Ruben Ronquillo		Chaparral ES
5498	Work In Progress sweeper/blower/not/working/choke/broken	9/14/2005 Medium	Daniel Ramirez Jimmy Carbajal		Chaparral ES
4797	Work In Progress repair storage, boy,s , girl,s r.r. @ chaparral elem	8/22/2005 Medium	Danny Miranda Danny Miranda		Chaparral ES
3607	Work In Progress need to paint new door @ football storage rm.	7/18/2005 Medium	Danny Miranda Joe Ramirez		Chaparral MS
3608	Work In Progress need to paint new door @ rm. 86	7/18/2005 Medium	Danny Miranda Joe Ramirez		Chaparral MS
7478	Work In Progress I need a A31 key for CMS for sound signal systems.	11/18/2005 Medium	Carlos Vigil Manny Lozoya		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3977	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7686	Work In Progress 1. Garbage Disposal is still out of order 2. Both sinks are dripping 3. Salad Sink is dripping from the faucet 4. Dishwasher sink drips from the pipe on the bottom  Sandra Diaz - SNP Manager - 824-4376	11/30/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Chaparral MS
7833	Work In Progress WARMER IS NOT WARMING UP. TAKING TO LONG TO HEAT UP.  SANDRA DIAZ SNP MGR 824-4376	12/5/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Chaparral MS
4485	Work In Progress please take a load of crusher fine so sewer line. Ak David (plumbing) for the specifics.	8/11/2005 Medium	Guadalupe Ontiveros	Portables	Chaparral MS
3648	Work In Progress please get with speedy and have him train you on the sprikler system on football field and thru out campus. Identify all valves and repair what is needed. also ask him for a key for sprinkler box and have him teach you the programs.	7/19/2005 Medium	Joe Ramirez	Football Field	Chaparral MS
3649	Work In Progress need to cut weeds and grass behind library and courtyard and surrounding areas tru -out campus including pond. Also need to irrigate these areas also.	7/19/2005 High	Joe Ramirez		Chaparral MS
3650	Work In Progress please paint railing on new portables that where installed and modified and all railings that are in need.	7/19/2005 Medium	Joe Ramirez		Chaparral MS
3656	Work In Progress please put up fence where portables where installed even if its on a temp bases.	7/19/2005 Medium	Joe Ramirez	Football Field	Chaparral MS
1854	Work In Progress Joe please order paint from Ruben so when portables arrive you can start painting them. Please call Mike	5/11/2005 Medium	Joe Ramirez	Portables	Chaparral MS
5463	Work In Progress need to pour landing and sidewalks to portables by football feild.	9/13/2005 Medium	Michael Munoz	Portables	Chaparral MS
7757	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
6008	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
6048	Work In Progress Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		Chaparral MS
6084	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
6086	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7085	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7087	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7074	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7061	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3148	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3241	Work In Progress Monthly - Chaparral MS Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3243	Work In Progress Monthly - Chaparral MS Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3307	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7781	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7783	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3988	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3990	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3964	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3314	Work In Progress Yearly - Chaparral MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3336	Work In Progress Yearly - Chaparral MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
5204	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
5227	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
5229	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
2818	Work In Progress WE NEED 3 CHAIR DOLLIES. WE HAVE ALOT OF SPECIAL EVENTS IN WHICH WE HAVE TO TAKE ANY WHERE FROM 200 TO 400 CHAIRS TO THE GYM FROM THE CAFETERIA AND CLASSROOMS. THIS YEAR WITH THE 9TH GRADERS WE"LL HAVE EVEN MORE SET UPS TO DO . WE NEED THE DOLLIES TO BE LIKE THE TWO THAT WE HAVE NOW, TALL WE CAN CARRY TEN CHAIRS AT A TIME. THANK YOU ROBERT	6/16/2005 Medium	Robert Gonzalez Aida Salcedo		Chaparral MS
2799	Work In Progress I NEED IF POSSIBLE 2 MORE 2 WHEEL DOLLIES. EVERY BREAK WE HAVE ESPECIALY THE SUMMER BREAK. WE HAVE TEACHERS MOVING FROM ONE ROOM TO ANOTHER AND SOME OF THEM BORROW THE DOLLIES. IT MAKES HARD FOR US BECAUSE WE"RE MOVING FURNITURE OR BOOKS AND OTHER THINGS. THANK YOU ROBERT	6/15/2005 Medium	Robert Gonzalez Aida Salcedo		Chaparral MS
5062	Work In Progress I NEED 1 MALE WATER HOSE CONNECTOR, 1 HX- 1 VINYL ANCHOR KIT AND 1 WEJIT DRY WALL AUGER ANCHOR KIT SIZE 8. THANK YOU	8/30/2005 Medium	Robert Gonzalez Jimmy Carbajal		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3499	Work In Progress We need locks to be installed on the center pole to the double doors in the front entrance,north east doors and south east doors. This is the oldest part of the school. the newer part of the school already have locks on the center poles. This old doors are the once that we use more often. This locks will make it so much faster and easier. THANK YOU ROBERT	7/13/2005 Medium	Robert Gonzalez Manny Lozoya		Chaparral MS
7525	Work In Progress MRS. ADAMS ROOM 203 HAS CABINETS AND DRAWERS THAT ARE LOCKED AND SHE DOESN'T HAVE A KEY TO UNLOCK THEM. SHE WOULD LIKE TO HAVE THEM UNLOCKED AS SOON AS POSSIBLE. THANK YOU	11/22/2005 Medium	Robert Gonzalez Manny Lozoya		Chaparral MS
1708	Work In Progress NEED TO CHANGE STORAGE ROOM LOCK TO OPEN WITH KEY A-82 ONLY. ALSO DOOR MUST REMAIN LOCKED AT ALL TIMES.	5/6/2005 Medium	Vickie Reed Manny Lozoya	Hallway/Corridor	Chaparral MS 100 STORAGE
2822	Work In Progress rekey file cabinets--about 8 or 9	6/16/2005 Medium	Vickie Reed Manny Lozoya	Custodial	Chaparral MS
2823	Work In Progress need to key stage cabinets to open w/ only one key.	6/16/2005 Medium	Vickie Reed Manny Lozoya		Chaparral MS
2487	Work In Progress need extra key for rm 405a	6/3/2005 Medium	Vickie Reed Manny Lozoya	Classroom	Chaparral MS 405a
2488	Work In Progress need extra key for rm 405b	6/3/2005 Medium	Vickie Reed Manny Lozoya	Classroom	Chaparral MS 405b
2489	Work In Progress need to rekey storage rm in 100 hall to open only w/ A82	6/3/2005 6/3/2005 Medium	Vickie Reed Manny Lozoya	Office	Chaparral MS storage rm
3439	Work In Progress NEED KEYS FOR TWO NEW PORTABLES.	7/11/2005 Medium	Vickie Reed Manny Lozoya	Portables	Chaparral MS
3855	Work In Progress NEED TO REKEY CABINET.	7/26/2005 Medium	Vickie Reed Manny Lozoya	Classroom	Chaparral MS 204
4509	Work In Progress need to rekey file cabinets. 2	8/12/2005 Medium	Vickie Reed Manny Lozoya	Classroom	Chaparral MS 104
4639	Work In Progress NEED 3 REPLACEMENT KEYS FOR 3 A-34'S THAT DO NOT WORK.	8/17/2005 Medium	Vickie Reed Manny Lozoya	Office	Chaparral MS VICKIE-KEY

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6558	Work In Progress 10/19/05. we need propane tank filled for portable housing rms. 1&2. ATTEN. RUBEN.	10/19/2005 10/21/2005 Medium	Joe Ramirez Ruben Ronquillo		Chaparral MS
6246	Work In Progress Need about 2 yards base coarse for use around pond area.	10/10/2005 Medium	Joe Ramirez Guadalupe Ontiveros		Chaparral MS
7324	Work In Progress 11/14/05. door closer on walk in freezer door needs to be replaced. thanks.	11/14/2005 Medium	Joe Ramirez Danny Orozco		Chaparral MS
4042	Work In Progress Need sensor replaced in girls locker room lavatory.	8/1/2005 Medium	Joe Ramirez Joe Ontiveros		Chaparral MS
3720	Work In Progress 7/12/05. need a/c replaced on portable 1 rm. 2 please.	7/20/2005 Medium	Joe Ramirez Jaime Gomez		Chaparral MS
2919	Work In Progress 6/21/05. need to replace s.e. corner a/c gym area.	6/21/2005 Medium	Joe Ramirez Jaime Gomez		Chaparral MS
4072	Work In Progress Room 208 - Mold on ceiling tiles. (Nancy, Nurse @ site called in) - mkv Margaret, Joe replied and said there where a couple of ceiling tiles with small mold droppings on them. He replaced them. However still go ahead and generate a w.o. for our records and have him fill it out.  Mike	8/2/2005 Medium	Mary Garcia Joe Ramirez	Classroom	Chaparral MS
4460	Work In Progress I need an office key for Ms. Maes, Clerk at Desert Pride Academy	8/10/2005 Medium	Mary Telles Manny Lozoya	Office	Desert Pride
6223	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo David Acosta		Desert Pride
7784	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin David Acosta		Desert Pride



<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
7771	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
7788	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
7076	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
7088	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
7092	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
6025	Work In Progress Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
4992	Work In Progress please remove marquee sign from desertveiw and install at desert pride. please be careful when removing.see mike	8/29/2005 Medium	Guadalupe Ontiveros		Desert Pride
6368	Work In Progress principal requests - to add crush fine to parking lot and bus turn around to help keep the dust down	10/13/2005 Medium	David Acosta Guadalupe Ontiveros	Parking Lot	Desert Pride
5959	Work In Progress need to cckek a/c blower . It stops blowing	9/29/2005 Medium	David Acosta Jose Ambriz	Classroom	Desert Pride #1
7665	Work In Progress need to service vacuum cleaner- very noisy and loose core from handle.	11/30/2005 Medium	David Acosta Jimmy Carbajal	Office	Desert Pride
7666	Work In Progress having trouble unlocking the westside door (cylinder).	11/30/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride #8
7187	Work In Progress need to remove receptacle from wall (once used for those big printers) for safety reasons. ( parents with small children in lobby area).	11/8/2005 Medium	David Acosta Carlos Castillo	Office	Desert Pride lobby
7284	Work In Progress need to service royal vacuum cleaner. (sparks coming out of motor housing)	11/11/2005 Medium	David Acosta Jimmy Carbajal	Custodial	Desert Pride

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
7731	Work In Progress need gate repairs-vehicles hit and run on gate (front entrance)	12/2/2005 Medium	David Acosta Ruben Ronquillo	Parking Lot	Desert Pride front entrance
4642	Work In Progress need one key for storage closet for teacher in room #3	8/17/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride 3
5336	Work In Progress Principals requests: for dead bolt locks for last portable (where break-in occur )	9/8/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride #6,7.
5294	Work In Progress NEED OUTSIDE NIGHT LIGHT BETEWE LAST PORTABLE AND END OF CAMPUS. ALSO NEED LIGHT BULK FOR NIGHT LIGHT BETEWE 2ND BUILDING AND PUMP HOUSE	9/6/2005 Medium	David Acosta Carlos Castillo	Classroom	Desert Pride
3942	Work In Progress need emergency light and exit signs check out.	7/29/2005 Medium	David Acosta Carlos Castillo	Office	Desert Pride
4304	Work In Progress need locks for two doors to the hall way, that needs to be use as storage for science rooms.	8/8/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride #3,4
3791	Work In Progress need plastic name plates(12)MS. S. VERLANDER, MS. I. RAMIREZ, MS. BACH-HAGUE, MS. B. COSTULIS, MS. C. MCDONALD, MR. C. VELA, MR. P. WYMAN, MS. G. PARKER, MS. S. GARCIA, MR. D. NEAL , MS. J. ZAPATA, MS. D. DEAN	7/25/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride
1410	Work In Progress need seven locks for doors to front offices. (in counslor, social workers area.)	4/25/2005 Medium	David Acosta Manny Lozoya	Office	Desert Pride
1834	Work In Progress need two plactic name plates for front office doors-( ALL VISITORS MUST SIGN IN AT FRONT OFFICE )	5/11/2005 Medium	David Acosta Manny Lozoya	Office	Desert Pride
2606	Work In Progress need one key for classroom for new teacher	6/7/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride 5
3064	Work In Progress Att: Sal Acuna-requesting for a desk mover and red flat truck.	6/29/2005 Medium	David Acosta Sal Acuna	Football Field	Desert Pride
2910	Work In Progress need two light switches installed for iep room and custodian office (no light switches in rooms.)	6/21/2005 Medium	David Acosta Carlos Castillo	Office	Desert Pride
1380	Work In Progress need to paint new frame @ varnish door to lounge	4/25/2005 Medium	Danny Miranda David Acosta		Desert Pride

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6266	Work In Progress RUSH ! or as soon as possible or Monday even. Could I get a line locate for Desert Trails Portables?	10/11/2005 Medium	Carlos Vigil Enrique Sotelo		Desert Trail Intermediate
7477	Work In Progress I need a Master Key for Desert Trails and an A31 key for CHap mid, for sound signal systems.	11/18/2005 Medium	Carlos Vigil Manny Lozoya		Desert Trail Intermediate
6170	Work In Progress please repair or replace door knob in the kitchen going outdoors in the back:(door jams and is hard to open) Thank You !!!!!!!!!!!!!!!!!!!!!	10/4/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
6883	Work In Progress need a lock (J-11) for new gate that was installed located in the fence between CH. ELEM and CH. DESERT TRAIL closest to Lisa ST. (To be locked during LOCK DOWN events). Thank You !!!!!!!	10/31/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
6884	Work In Progress Marquee Light not working properly. (vice- principal)	10/31/2005 Medium	Johnny Acuna Enrique Sotelo		Desert Trail Intermediate
7184	Work In Progress Please replace metal door (Back Door) from the kitchen. Door is corroded and getting worse. Thank You !!!	11/8/2005 Medium	Johnny Acuna Danny Miranda		Desert Trail Intermediate
7175	Work In Progress need 2 classroom faucets. (single handle "cold" water faucets). Thank You !!!!!!!!!!!!!	11/8/2005 Medium	Johnny Acuna Joe Ontiveros		Desert Trail Intermediate
6846	Work In Progress fire-proof filing cabinet inside vault: please fix or replace lock.	10/28/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
6910	Work In Progress need a replacement heating coil (boiler heating system) for cafeteria heater. Old heater leaks: Model # LHD103CH Serial #35C01059-06	11/1/2005 Medium	Johnny Acuna Jose Ambriz		Desert Trail Intermediate
7205	Work In Progress need to replace hydraulic door closure in the back kitchen door. (old door closure leaked oil out and doesn't work)	11/8/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
7366	Work In Progress need to replace door frame and door to portable #404.	11/15/2005 Medium	Johnny Acuna Danny Miranda		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7520	Work In Progress (Ruben Ronquillo) Need cement mixer for next week to do cement project in parking lot area. (ramp)	11/22/2005 Medium	Johnny Acuna Ruben Ronquillo		Desert Trail Intermediate
7408	Work In Progress NEED TO INSTALL FENCE AROUND FIRE HYDRANT. (SEE ATTACHED)	11/16/2005 Medium	Johnny Acuna Michael Munoz		Desert Trail Intermediate
7573	Work In Progress need a gas valve for reznor roof top heater. (valve doesn't close and leaks a little). HONEYWELL : VR8304M 2880 supplied Johnny w/gas valve and he will install.	11/28/2005 12/1/2005 Medium	Johnny Acuna Lorenzo Solis		Desert Trail Intermediate
7551	Work In Progress need ballasts (double) 277 V and light bulbs, to fix classroom light fixtures during intersession.	11/28/2005 Medium	Johnny Acuna Enrique Sotelo		Desert Trail Intermediate
7726	Work In Progress PRINCIPAL'S REQUEST: NEED TO ISSUE A DIFFERENT KEY AND CHANGE OUT THE CORE TO DOORKNOB. TEACHER IN PORTABLE #411 HAS THE SAME KEY TO OPEN UP GATES AND THE MAIN BUILDING. THANK YOU !!!!!!!	12/2/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
7728	Work In Progress need to replace refrigerated waterfountain located in the southwest hall. Old one leaks water from the evaporator coil section.	12/2/2005 Medium	Johnny Acuna Joe Ontiveros		Desert Trail Intermediate
7732	Work In Progress need a new classroom t-stat for boiler heating system to room #118.	12/2/2005 Medium	Johnny Acuna Lorenzo Solis		Desert Trail Intermediate
7688	Work In Progress need a 3-way switch for lights to kitchen. (regular type switch) Thank You !!!!!	12/1/2005 Medium	Johnny Acuna Enrique Sotelo		Desert Trail Intermediate
7699	Work In Progress SECURITY LIGHT IN PARKING LOT NOT WORKING.	12/1/2005 Medium	Johnny Acuna Enrique Sotelo		Desert Trail Intermediate
2425	Work In Progress NEED TO REPLACE A LOST KEY FOR ROOM #201: MARIA RONGEL	6/1/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
2322	Work In Progress PLEASE SEND EXTERMINATOR OR MOUSE TRAPS TO RM.#116(MRS. DOMINGUEZ) MOUSE INSIDE CLASSROOM.	5/26/2005 Medium	Johnny Acuna Johnny Acuna		Desert Trail Intermediate
2403	Work In Progress NEED A LOCK FOR SOUTHWEST GATE NEXT TO LISA ST.	6/1/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2376	Work In Progress NEED TO REPLACE DOOR FRAME TO PORTABLE #411. (MAIN DOOR).	5/31/2005 Medium	Johnny Acuna Danny Miranda		Desert Trail Intermediate
2585	Work In Progress (DANNY MIRANDA) NEED TO SEE IF FRAME AND DOOR COULD BE MOVED TO THE OTHER SIDE OF THE WALL TOWARDS HALLWAY AND CLOSE OFF WALL WHERE DOOR AND FRAME USED TO BE. *LOCATION: SPEECH ROOM*	6/7/2005 Medium	Johnny Acuna Danny Miranda		Desert Trail Intermediate
1192	Work In Progress RM. #112 GUTIERREZ . NEED TO FIX AND MAKE A KEY FOR FILING CABINET INSIDE CLASSROOM..THANK YOU.....	4/15/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
1211	Work In Progress need irrigation backflow preventer to be installed for irrigation to front trees. (irrigation line has been installed).	4/18/2005 Medium	Johnny Acuna Lorenzo Hernandez		Desert Trail Intermediate
2211	Work In Progress NEED A NEW REPLACEMENT HOLLOW DOOR FOR CLASSROOM # 411 GIRL'S RESTROOM. DOOR SIZE: 32 1/2" WIDE X 80" LONG. ALSO NEED (2) DOOR KNOBS. ONE (ROUND) FOR HALLWAY DOOR, AND ONE (LEVER) FOR BOY'S RESTROOM DOOR. THANK YOU !!!!!	5/23/2005 Medium	Johnny Acuna Danny Miranda		Desert Trail Intermediate
2212	Work In Progress (STUDENT RECORDS) NEED TO REPAIR BROKEN FILE CABINET LOCK, ALSO NEED A KEY TO BE ABLE TO LOCK CABINETS. BOTH STUDENT RECORD CABINETS ARE THE SAME KEY. (LOCATED INSIDE THE VAULT IN THE MAIN OFFICE)	5/23/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
2289	Work In Progress NEED A SCREW EXTRACTOR FOR CLASSROOM #112 SINK HANDLE. (VALVE)	5/25/2005 Medium	Johnny Acuna Fred Appenzoller		Desert Trail Intermediate
2290	Work In Progress NEED NEW LOCKS AND KEYS FOR CABINET/CLOSET AND THE TEACHER'S DESK. MAIN BLDG. RM. #115.	5/25/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
2298	Work In Progress 5/25/05 .5-CHECK LIFT STATION .5-REPLACE MISSING INTERCOM BUTTONS TO CLASSROOMS. 2.0-FIX LIGHT FIXTURES TO CLASSROOM RESTROOMS. .5-REPLACE PENCIL SHARPENERS TO ROOMS. #102 AND 406. 1.5-TROUBLESHOOT AND FIX A/C TO ROOM #209. 3.0-CUT WEEDS. 5/25 - 8	5/25/2005 Medium	Johnny Acuna Johnny Acuna		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2061	Work In Progress NEED TO REPLACE CONDENSATION PUMP TO THE REFRIGERATION UNIT LOCATED INSIDE THE SERVER ROOM.	5/18/2005 Medium	Johnny Acuna Jaime Gomez		Desert Trail Intermediate
1807	Work In Progress NEED SCRAPER TO CLEAN OUTSIDE AND INSIDE OF FENCE LINES. THANK YOU !!!!	5/10/2005 Medium	Johnny Acuna Lorenzo Hernandez		Desert Trail Intermediate
1556	Work In Progress PORTABLE #411: NEED A NEW DOORKNOB (LEVER TYPE) FOR BOYS RR, AND ALSO NEED TO RE-WELD DOOR HINGE TO MAIN CLASSROOM DOOR. FALLEN DOOR HARD TO CLOSE.	5/2/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
3739	Work In Progress DIAG/PSYCH ROOM NEED (2) CLASSROOM KEYS MADE. CORE IS: J-53	7/21/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
3619	Work In Progress MENS RESTROOM (NW HALL) : PLEASE CHANGE DOOR CYLINDER WHERE KEY ENTERS TO OPEN UP DOOR. STUDENTS STUFFED IN CYLINDER WITH CLAY AND HARDENED. THANK YOU !!!!!	7/18/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
3620	Work In Progress NEED NAME PLATES TO BE MADE: (1) PRINCIPAL, (1) ASSISTANT PRINCIPAL, (1) COMPUTER LAB	7/18/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
4116	Work In Progress need a replacement single knob water faucet for room #112.	8/3/2005 Medium	Johnny Acuna Joe Ontiveros		Desert Trail Intermediate
4558	Work In Progress Mrs. Bonham (Asst. Principal) requesting concrete slab to be installed between portable #412 and #413 art studio.	8/15/2005 Medium	Johnny Acuna Michael Munoz		Desert Trail Intermediate
5426	Work In Progress need a replacement heating coil (Boiler System) in the Cafeteria/Gym. (Old one Leaks)	9/12/2005 Medium	Johnny Acuna Jaime Gomez		Desert Trail Intermediate
5462	Work In Progress need to demo and repour concrete to sectioned area by cafeteria.	9/13/2005 Medium	Michael Munoz	Desert Trail Intermediate Cafeteria	
7758	Work In Progress Monthly - Desert Trail Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
7787	Work In Progress Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7782	Work In Progress Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
6224	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Guillermo Hernandez		Desert Trail Intermediate
6225	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Miguel Aguilar		Desert View ES
3339	Work In Progress Yearly - Desert View ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
3317	Work In Progress Yearly - Desert View ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
7785	Work In Progress Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
7789	Work In Progress Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
7759	Work In Progress Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
6977	Work In Progress NEED TO LINE LOCATE AT COURTYARD AREA TOMORROW OR MONDAY. (PLEASE CONTACT RICK MILLER W/ESA TO LET HIM KNOW WHEN YOU WILL BE LOCATING THE LINES @ 915-845- 4777)	11/3/2005 Medium	Alfredo Holguin David Villalobos		Desert View ES
7697	Work In Progress JIMMY & SAL - NEED TO RESTORE FLOORS AT DESERT VIEW ON WED, DEC 7 AFTER 4:00 PM.	12/1/2005 Medium	Jimmy Carbajal		Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7698	Work In Progress JIMMY & SAL & GUILLERMO, FOR BOARD MEETING SCHEDULED (DEC 8 @ 5:00 PM) NEED TO CLEAN ENTRANCE & GYM ARE VERY WELL. DEL BOARD TABLES AS WELL	12/1/2005 Medium			Desert View ES
5340	Work In Progress MOUSE PROBLEM. MOUSE GOT ON THE TABLE WHILE EATING  MARTHA FLORES - 589-2425 HELP PLEASE	9/8/2005 Medium	Jacqueline Aguilar Margret Villalobos	Cafeteria	Desert View ES
7518	Work In Progress Having problems turning ON Top Blodgett Oven  Martha Flores - SNP Manager 589-2425	11/22/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Desert View ES
4149	Work In Progress key cylinder to walk-in refrigerator doesn't lock, key continuously goes round and round, please repair as soon as possible, groceries and commodities are stored in there.	8/3/2005 Medium	Alma Terrell Manny Lozoya	Cafeteria	Desert View ES
1183	Work In Progress NEED TO REPLACE HOSE SPIGOTS IN PATIOS. LOOSING WATER PRESSURE AND HANDLES ARE BROKEN. NO HEAD CUSTODIAN AT SCHOOL SITE. IF YOU NEED ANY INFORMATION, CONTACT JIMMY CARBAJAL @ THE CUSTODIAL WAREHOUSE	4/15/2005 Medium	Aida Salcedo David Villalobos		Desert View ES
6455	Work In Progress Need heavy amounts of sand/dirt removed from road leading to backside of school parking lot, mud and debri causing a hazard. Hard rains exposed many water pipes and created many deep crevices, also a hazard for students.	10/17/2005 Medium	Miguel Aguilar Guadalupe Ontiveros		Desert View ES
7611	Work In Progress Request (3) bearings and caps for carpet brush on Royal vacuum. Have two vacuums nonworking due to broken bearings/caps.	11/29/2005 Medium	Miguel Aguilar Jimmy Carbajal		Desert View ES
7612	Work In Progress Request (1) complete roller brush for Royal vacuum.	11/29/2005 Medium	Miguel Aguilar Jimmy Carbajal		Desert View ES
7613	Work In Progress Have a nonfunctioning electrical outlet in gymnasium.	11/29/2005 Medium	Miguel Aguilar Carlos Castillo		Desert View ES
7614	Work In Progress Have a nonfunctional electrical outlet in cafeteria.	11/29/2005 Medium	Miguel Aguilar Carlos Castillo		Desert View ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7232	Work In Progress Trees in front courtyard unhealthy/dying, signs of infestation, requesting solution/insecticide to remedy problem.	11/9/2005 Medium	Miguel Aguilar Guadalupe Ontiveros		Desert View ES
7023	Work In Progress Light pole facing lower grade playground not turning on, may need bulb replaced, unlit playground receiving a lot of graffiti and other illegal activity a problem during evening and early morning hours.	11/4/2005 Medium	Miguel Aguilar Carlos Castillo		Desert View ES
5145	Work In Progress Urgent: Need center pole repaired in exterior double door on east side of school repaired, pole fell and struck teacher. Door cannot be fully secured and will compromise security after school hours.	9/1/2005 Medium	Miguel Aguilar Manny Lozoya		Desert View ES
5146	Work In Progress Need copies (3) made of padlocks on hall doors, need for sub keys and replacement.	9/1/2005 Medium	Miguel Aguilar Manny Lozoya		Desert View ES
5616	Work In Progress REQUESTING (2) "R" KEYS, ONE FOR NEW COUNSELOR, Mr. David Gonzalez and the other one to replace Ms. Esther Maldonado's "R" key. (Bended Key) Please pick up bended key with Margarita Terrazas at the front office	9/19/2005 Medium	Margarita Terrazas Manny Lozoya		Desert View ES 5055891180
4083	Work In Progress TEACHER DESK WITH LOCKING DRAWER, DOES NOT LOCK. ROOM#19, LOWER GRADE SIDE. MRS. GRISWOLD	8/2/2005 Medium	Margarita Terrazas Manny Lozoya		Desert View ES
2546	Work In Progress Faucets in both patio areas need repair. Note: Work order is for Desert View Elementary, not RS.	6/6/2005 Medium	Miguel Aguilar David Villalobos		Desert View ES
1968	Work In Progress pat aguilar - asper principal to replace ac in port #2 room 3&4 with refrigerated air conditioning	5/16/2005 Medium	Patricio Aguilar Jose Ambriz		Desert View ES
1969	Work In Progress pat aguilar move sand away from rock wall move sand back up hill	5/16/2005 Medium	Patricio Aguilar Lorenzo Hernandez		Desert View ES
2448	Work In Progress pat aguilar locksmith frount door to building need repair door closures need replacement door handdels need replacement	6/2/2005 Medium	Patricio Aguilar Manny Lozoya		Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4781	Work In Progress pat aguilar rock wall (safety concern) 6 rock wall metal gates need to be replaced rusted throw	8/22/2005 Medium	Patricio Aguilar Michael Munoz		Desert View ES
7045	Work In Progress belts for ac 4 each ax26 code 1 2401-285 4 each ax32 code 1 3602-385	11/4/2005 Medium	Patricio Aguilar Jose Ambriz		Desert View ES
6477	Work In Progress second requist on wo 123783 12/15/04 wo 115914 7/22/04 play grounds need 10 truck loads of play ground sand need 4 trucks of pressure crush need rain drains cleaned out need sand moved from rock wall need sand moved off drive way and back up hill	10/17/2005 Medium	Patricio Aguilar Guadalupe Ontiveros		Desert View ES
7407	Work In Progress RTC-SPED OFFICE - NEED OFFICE FURNITURE MOVED. JULIANA HINOJOSA/GLORIA SAENZ	11/16/2005 Medium	Margret Villalobos Ralph Lara		GAC
7235	Work In Progress SPED Portable - need ramp for portable located at GAC. (see Margaret Villalobos-SPED_ Route to Manuel Prospero as per Mike 11/9/05 - mkv	11/9/2005 12/1/2005 Medium	Margret Villalobos Manuel Prospero		GAC
6525	Work In Progress I NEED 3 EXOST MOTOR FOR C WING V 115 HZ 60 PH 1 HP 1/20 AO AMPS 1.7 NO.7108-5136 RPM 1500. AND AIR FILTERS 20X20XX2. 16X20X2. 16X20X1. 20X25X2. 16X25X2. AS PER JOSE AMBRIZ.	10/18/2005 Medium	Manuel Prospero Jose Ambriz		GAC
2163	Work In Progress 5/20/05 WE NEED TO CHANGED LOCKS AT NEW HANDICAP RESTROOMS. TO PRIMUS LOCKS. THIS IN FOR MANNY LOZOYA	5/20/2005 Medium	Manuel Prospero Manny Lozoya		GAC
1980	Work In Progress AS PER MANY LOZOYA WE NEED 4 KEY FOR RESETE FIRE ALARM.	5/17/2005 Medium	Manuel Prospero Manny Lozoya		GAC
4377	Work In Progress NEED NEW R. R. PARTITIONS IN "A" WING AS PER MENNY PROSPERO	8/9/2005 Medium	Manuel Prospero Danny Miranda		GAC
4182	Work In Progress B-Wing - Human Resources Dept Please spray Lucy Garcia's & Ms. Browder's office for bugs (crickets, centerpedes, etc.)	8/4/2005 Medium	Mary Garcia Margret Villalobos		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4655	Work In Progress AS PER ANN STEINHOFF-NEEDS 1 MORE GRAND MASTER KEY FOR HER SECRETARY AT PRE-K	8/17/2005 Medium	Mary Garcia Manny Lozoya	Office	GAC WHOLE BUILDING
4925	Work In Progress C Wing- Having problems with mice.	8/25/2005 Medium	Mary Garcia Margret Villalobos		GAC
144	Work In Progress IN A-WING SPECIAL ED, ACROSS COMPUTER LAB; ROOMS HAVE NO COOLING AND HEATING. NEED TO TALK W/SYLVIA MORENO.	3/8/2005 Medium	Mary Garcia Jose Ambriz	Office	GAC
850	Work In Progress As per Manny Prospero: Needs weeds to be cut if can have ground come out to help.	4/5/2005 Medium	Mary Garcia Lorenzo Hernandez		GAC
2909	Work In Progress AS PER TINA B-WING, OUTLET IN THE FILE ROOM DOES NOT WORK. (NEED TO PLUG A FAN IN ORDER TO WORK IN THAT ROOM TO HOT.) Need Electrician's assistance, checked for power, breaker and no power. routed to Cali 6/27/05.	6/21/2005 10/26/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC FILE ROOM
3408	Work In Progress AS PER CARLOS VIGIL-NEEDS A GRAND MASTER 7, ASAP. (HIS BROKE IN HALF) ALREADY TALKED WITH MANNY LOZOYA	7/8/2005 Medium	Mary Garcia Manny Lozoya	Office	GAC ALL SCHOOLS
3432	Work In Progress AS PER LINDA REYES-NEED FURNITURE FROM 3 OFFICES & BOXES ALONG WITH THIS TO BE MOVED A.S.A.P. TO NEW AREA IN C-WING. STAFF WILL START WORKING IN THESE NEW OFFICES BY TOMORROW.	7/11/2005 Medium	Mary Garcia Manuel Prospero	Office	GAC C WING
2658	Work In Progress RAY LARA-C WING; NEEDS FURNITURE TO BE MOVED FROM CORINA & DEBBIE'S OFFICE INTO THE CONFERENCE ROOM. (WIRE SHELVE WILL BE PLACED IN MR. LARA'S OFFICE). NOTE: THIS MUST BE DONE BY 6/15/05 AS PER MS. STEINHOFF.	6/9/2005 Medium	Mary Garcia Manuel Prospero	Office	GAC
2660	Work In Progress AS PER CARLOS VIGIL-NEEDS 6 PAD LOCKS FOR GHS MASTER. (FOR THIS TO OPEN WITH BEST LOCK MASTER KEY) APPROVED BY MR. CHAVEZ	6/9/2005 Medium	Mary Garcia Manny Lozoya	Classroom	GAC
2755	Work In Progress AS PER LAURA GARCIA-WOULD LIKE TO CLOSE OFF OFFICE DOOR TOTALLY & HAVE A DOOR MADE THROUGH ANNIE'S OFFICE, GOING INTO HER OFFICE. (PLEASE CHECK W/LAURA BEFORE DOING ANYTING.)	6/13/2005 Medium	Mary Garcia Danny Miranda	Office	GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2548	Work In Progress AS PER CORA W/TECHNOLOGY, SHE NEEDS A KEYS TO BE ISSUE TO LYNCO ELECTRIC AND SOUND & SINGNAL FOR GHS AND LU (FOR THE WHOLE SCHOOL)	6/6/2005 Medium	Mary Garcia Manny Lozoya	Classroom	GAC
7618	Work In Progress AS PER AMY RODRIGUEZ-LIGHTS ABOVE DESK ARE FLICKERING OFF AND ON. NEED BULBS TO BE REPLACED	11/29/2005 Medium	Mary Garcia Manuel Prospero	Office	GAC C-WING
5796	Work In Progress AS PER CORA-NEEDS THE DOOR LOCK TO THE DATA CENTER SWITCHED OUT FROM SWIPE CARD TO A COMBINATION LOCK. (MANNY, PLEASE SEE CORA BEFORE CHANGING OUT)	9/23/2005 Medium	Mary Garcia Manny Lozoya	Computer Lab	GAC DATA CENTER- TECHNOLOGY
6743	Work In Progress AS PER MS. BERRY-NEEDS 3 SIGNS THAT SAY SLOW CHILDREN TO PUT IN THE ENTRANCE AND PARKING AREA. TALKED WITH RUBEN RONQUILLO AND KNOW WHICH SIGNS TO ORDER	10/25/2005 Medium	Mary Garcia Ruben Ronquillo		GAC PARKING AREA
7747	Work In Progress AS PER ELISA SAENZ-NEEDS NAME PLATES FOR THE FOLLOWING NEW BOARD MEMBERS: 1.) Elsa Porras 2.) Charles Gonnell 3.) Daniel Castillo 4.) Jennifer Viramontes IF THIS CAN BE DONE ASAP, SO THEY CAN BE READY FOR THURSDAY'S BOARD MEETING.	12/2/2005 Medium	Mary Garcia Manny Lozoya	Office	GAC
5824	Work In Progress NEED A WATERHOSE AND ALSO A HOSE ROLL A WAY.2 WATERHOSE ONE FOR THE PATIO AND ONE FOR THE PRE KINDER AREA I ONLY HAVE ONE AND I USE IT FOR THE FRONT AREA,THE HOSE ROLL A WAYS I NEED ONE FOR EACH HOSE THANK YOU FOR YOUR CONTINUED SUPPORT YOU ARE THE BEST!!!!	9/26/2005 Medium	Jimmy Carbajal Sal Acuna	Custodial	GAC
1674	Work In Progress NEED 2FT.BY2FT. CONCRETE BASE TO INTALL LIGHT FIXTURES ON BOTH SIDES OF ENTRANCE SIGN TO THE GAC.	5/5/2005 Medium	Carlos Castillo Michael Munoz		GAC
6270	Work In Progress I would like to request a 120v outlet to be installed above kitchen (dock entrance side) door for door horn.	10/11/2005 Medium	Carlos Vigil Danny Orozco		GAC
7053	Work In Progress Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Manuel Prospero		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7094	Work In Progress Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
6050	Work In Progress Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		GAC
7749	Work In Progress Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3546	Work In Progress Technology Server Room-Install Battery powered Emergency lighting in this room	7/14/2005 Medium	Carlos Castillo		GAC
7790	Work In Progress Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
7786	Work In Progress Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3282	Work In Progress C-WING - TAKE OFF TILE AND INSTALL NEW TILE (TILE HAS BEEN DELIVERED), ALSO FINISH PAINTING. WILL SEND GERRY MARQUEZ TO ASSIST.	7/5/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3094	Work In Progress Install fencing on north property line for site security.	6/30/2005 6/30/2005 Medium	Alfredo Holguin Michael Munoz		GAC
6226	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Ralph Lara		GAC
6227	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Jesus Estrada		Gadsden HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
3319	Work In Progress Yearly - Gadsden HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
3141	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
7791	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Fernando Moncayo		Gadsden HS
7794	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS
4448	Work In Progress Telescope observatory locate on the west side of the baseball field - Install fencing around it to prevent vandalism	8/10/2005 Medium	Michael Munoz		Gadsden HS
5458	Work In Progress need to restripe all parking lines ,handi-cap- arrowa etc.	9/13/2005 Medium	Michael Munoz	Parking Lot	Gadsden HS
4916	Work In Progress please check and repair leak & secure drop ceiling in rm 142. possible safety hazard.	8/25/2005 Medium	Danny Miranda		Gadsden HS
2315	Work In Progress Please paint inside and out of both guard shack and repair what is damaged before school starts this year.	5/26/2005 Medium	Mario Apodaca		Gadsden HS
3659	Work In Progress Please install stair treads when they come in. Old english stair ways. I will order. See Mike Install from main to old english stairs. FAXED PO 8/4/05 - MKV	7/19/2005 Medium	Mario Apodaca	Stairway	Gadsden HS
5464	Work In Progress Need to paint stripings for student parking lot and east of Auto Shop.	9/13/2005 Medium	Michael Munoz	Parking Lot	Gadsden HS
6958	Work In Progress please provide a concrete landing and side walk to counselors portable.	11/2/2005 Medium	Michael Munoz	Portables	Gadsden HS
7750	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
6097	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
6001	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
7095	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Fernando Moncayo		Gadsden HS
7098	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS
7054	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
7499	Work In Progress please re-route conduit and repair where kids get on roof by panther hut. north bldg.	11/21/2005 Medium	Enrique Sotelo	Classroom	Gadsden HS
7500	Work In Progress please replace disconnect to heating unit on the - S- wing north bldg. blades do not work properly.	11/21/2005 Medium	Jose Ambriz	Classroom	Gadsden HS
7542	Work In Progress mario fernando could you schedule the new doors thru-out the campus that need painting and schedule around the x-mas break. please order your material. thanks	11/22/2005 Medium	Mario Apodaca		Gadsden HS
7544	Work In Progress please remove and relocate tree in front of electrical panel east of north bldg by hwy 28.Thanks	11/22/2005 Medium	Guadalupe Ontiveros		Gadsden HS
4212	Work In Progress need metal door @ frame for dugout storage	8/4/2005 Medium	Danny Miranda Danny Miranda		Gadsden HS
2762	Work In Progress need to varnish 15 new doors	6/14/2005 Medium	Danny Miranda Joe Ontiveros		Gadsden HS
7638	Work In Progress Girls BB Lockerroom - Connect Electric Water Heater.	11/29/2005 Medium	David Villalobos Michael Mc Dermott		Gadsden HS
7667	Work In Progress Need several lighth bulbs,for outside security lights;75-100-175-250w metal halide, 150w mercury vapor THANK YOU!!	11/30/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
7637	Work In Progress Attn. RUBEN RONQUIIIILLO;Broken window at BOY'S restrooms in MAIN bldg. Glass is +-15x39 privacy glass for restroom THANK YOU SIR!!!!	11/29/2005 Medium	Fernando Moncayo Ruben Ronquillo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7325	Work In Progress Attn. MR. AMBRIZ ;Need a combustion vent motor for VARSITY GYM reznor heaters.MTR. is 208/230 volts	11/14/2005 Medium	Fernando Moncayo Jose Ambriz	Gym	Gadsden HS
7301	Work In Progress BOY'S GYM SOUTH EAST exterior door need to be replace	11/11/2005 Medium	Fernando Moncayo Danny Miranda	Gym	Gadsden HS
6489	Work In Progress VARSITY GYM; girl's BASKETBALL locker room,water heater is leaking from bottom of tank	10/17/2005 Medium	Fernando Moncayo David Villalobos		Gadsden HS
6607	Work In Progress LIBRARY EAST wall;There is a wall keyed hose bib that is leaking	10/20/2005 Medium	Fernando Moncayo David Villalobos		Gadsden HS
6609	Work In Progress Need to install flouresent lighth lamps in ANNEX CORRIDOR, is too dark	10/20/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
5943	Work In Progress Attn. MIKE MUNOZ need about ten parking stops[parking curb]on refrence from w/o# 5464 thank you!!	9/28/2005 Medium	Fernando Moncayo Michael Munoz		Gadsden HS
7721	Work In Progress Attn. JOSE JO, JO AMRIZ need a blower motor for fresh air units on top of OLD ENGLISH asap please !! LORENZO took the old motor THANK YOU!!!	12/1/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
7725	Work In Progress Security lights on electrical poles in the SOUTHSIDE of school not working,*safety hazard, too dark for SCHOOL BAND students	12/1/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
4240	Work In Progress Need six wheels for large gates in NORTH parking lot THANK YOU!! 8/11 - Route to Ruben as per Mike	8/5/2005 Medium	Fernando Moncayo Ruben Ronquillo		Gadsden HS
4305	Work In Progress NORTH bus entrance gate keep falling, bottom rail all bend;Also needs new roller bearings for both gates thank you !!! [safety hazard]	8/8/2005 Medium	Fernando Moncayo Michael Munoz		Gadsden HS
4311	Work In Progress PANTHER HUT porch entrance too dark security lighth dosen't work	8/8/2005 Medium	Fernando Moncayo Fernando Moncayo		Gadsden HS
3726	Work In Progress Attn electrician need a better security lighths by CONCESSION STAND to control vandalism	7/20/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3593	Work In Progress Need to repair or replace electrical conduit outside of CONCESSION STAND by GIRL'S GYM	7/15/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
5101	Work In Progress ATTN. JOSE AMBRIZ need about ten three pole contactors for the a/c's nighth set back system in the ACADEMIC BLDG. Some burned out by the power outage.Thank you!!	8/30/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
4902	Work In Progress AG BLDG entry door,won't open or lock key just turns;Also WOOD SHOP entry door new lock dosn't work	8/25/2005 Medium	Fernando Moncayo Manny Lozoya		Gadsden HS
1973	Work In Progress Need to rerun conduit and wires to kitchen exhaust in PANTHER HUT HOMEC ROOM	5/16/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
2459	Work In Progress Attn. MANNY LOCKSMITH; Need to ck. storage cabinet in room 226 not locking	6/2/2005 Medium	Fernando Moncayo Manny Lozoya		Gadsden HS
2630	Work In Progress 06/08/05 Atrn;MANNY LATOYA , need to change the lock cilinders to restrict the access to the VARSITY GYM due to been paint thank you!	6/8/2005 Medium	Fernando Moncayo Manny Lozoya		Gadsden HS
3479	Work In Progress All Campus - Need to replace old door knobs w/new levers.	7/12/2005 Medium	Hector Lozoya Manny Lozoya		Gadsden HS
3645	Work In Progress BOTH OVENS ARE DOWN.  LYDIA M. SNP MGR 882-5522	7/19/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Gadsden HS
4726	Work In Progress Royal vacuum is missing bag and brush, belt serial No.H93266101B GISD tag 014131	8/19/2005 Medium	Jesus Estrada Jimmy Carbajal		Gadsden HS
1354	Work In Progress need casters on tables fixed. I counted 14 that need replacement.	4/22/2005 Medium	Jesus Estrada Guillermo Hernandez	Cafeteria	Gadsden HS
7010	Work In Progress I have two dolleys with flats.	11/4/2005 Medium	Jesus Estrada Jimmy Carbajal		Gadsden HS
5915	Work In Progress Pressbox - There is a Bee Hive in pressbox. Having a game tomorrow. Please send someone out today. (Open PO) as per A. Holguin.	9/28/2005 Medium	Jesus Estrada Margret Villalobos	Football Field	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7676	Work In Progress NEED A NEW 2 1/2 GAL WATER BOILER FOR ROOM 107	11/30/2005 Medium	Mario Apodaca David Villalobos	Classroom	Gadsden HS
6526	Work In Progress NEED TO RUN SEWER SNAKE AT WOOD SHOP BLDG unclog main sewer line to woodshop	10/18/2005 10/19/2005 Medium	Mario Apodaca David Villalobos		Gadsden HS
6595	Work In Progress OUTSIDE CONDUIT AT ROOM 233 NEED TO BEREPAIR SO IT CAN'T BE PULL OFF THE WALL ON MORE AND THE KID CAN'T USE THE CONDUIT AS A LADDER TO GATING UP TO THE ROOF TOP	10/20/2005 Medium	Mario Apodaca Michael Mc Dermott	Restroom (Boys)	Gadsden HS
6425	Work In Progress NEED TO REMOVE ALL OUTLET AT ROOM 126 AT ARE ON BOOK SHEVING FLOOR AND RELOCA OUTLETS	10/14/2005 Medium	Mario Apodaca Michael Mc Dermott	Custodial	Gadsden HS
5842	Work In Progress NEED A NEW GLASS PUT ON CONCESSION STAND WINDOW AT FOOTBALL FIELD (VANDALISM) 23X23 ASAP	9/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
7277	Work In Progress NEED TO PUT CRUSH ROCK ON ROAD BY THE WOOD SHOP , ANNEX BLDG AND POOL SO DUST WOOD NOT P-PU ASAP	11/10/2005 Medium	Mario Apodaca Guadalupe Ontiveros		Gadsden HS
7239	Work In Progress NEED KEY FOR TOW FILE CABINETS AT ROOM 223	11/9/2005 Medium	Mario Apodaca Manny Lozoya		Gadsden HS
7385	Work In Progress NEED SEWER SNAKE FOR SINK AT ROOM 124	11/15/2005 Medium	Mario Apodaca Joe Ontiveros		Gadsden HS
5708	Work In Progress THE OUTSIDE OUTLET NEED TO BE FIX AT WEIGHT ROOM	9/21/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
5768	Work In Progress NEED A NEW FAUCET AT ROOM 229 FOR MR PALMER LAB SINK	9/22/2005 Medium	Mario Apodaca David Villalobos		Gadsden HS
5108	Work In Progress NEED TO PUT NEW BALLAST AT WOOD SHOP LAMPES	8/31/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
4970	Work In Progress GLASS AT MAIN BLDG HALLWAY 40X18 NEED TOBE REPLACES VANDALISM	8/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4976	Work In Progress NEED ALL WINDOW BLINDSON OLD ENGLISH BLDG 40 EA 40WX90L	8/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
4502	Work In Progress NEED TO LAMPES AT WOOD SHOP SAME ARE BURNED OUT	8/11/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
3524	Work In Progress NEED TO FIX FOOTBALL FIELD SCOREBOARD BREAKER BOX	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
3525	Work In Progress NEED TO CK ALL FOOTBALL FIELD LAMPS	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
1393	Work In Progress BASEBALL & SOFTBALL DUGOUT AREA - NEED (3) HOLLOW METAL DOORS WITH HOLLOW METAL FRAMES (3'0" X 6'8") FOR STORAGE ROOMS.	4/25/2005 Medium	Lorenzo Hernandez Danny Miranda	Athletic Field	Gadsden HS
1394	Work In Progress GROUNDS SHOP - NEED TO RESTOCK FIRST AID KIT.	4/25/2005 Medium	Lorenzo Hernandez Ruben Ronquillo		Gadsden HS
7543	Work In Progress old english- could you remove the cobwebs off the wall in the east entrance to the bldg.Thanks	11/22/2005 Medium	Michael Munoz Jesus Estrada	Classroom	Gadsden HS
133	Work In Progress NEED NEW STAIR VINYL STRIP FOR MAIN GOING UP TO OLD/ENG	3/7/2005 Medium	Mario Apodaca Michael Munoz	Stairway	Gadsden HS
264	Work In Progress NEED A METAL DOOR FOR BOY RESTROOM AT N-BLDG - ONE DOOR	3/10/2005 Medium	Mario Apodaca Danny Miranda	Restroom (Boys)	Gadsden HS
333	Work In Progress NEED NEW DOOR AT MAIN BLDG GOING OUT TO COMPUTER LAB WEST WING	3/11/2005 Medium	Mario Apodaca Danny Miranda	Hallway/Corridor	Gadsden HS
4810	Work In Progress Requested by Ms. L. Chavez Rm. 245 Classroom Over Varsity Gym-Re-place several burned out light bulbs. RE-ROUTE TO BUILDING MECHANIC as per Mike Mc Dermott 9/19/05	8/23/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4811	Work In Progress Requested by Mr. Cordova Storage Room in Varsity Gym Stage-The door needs to be re- keyed to an off master key, light board room. 4 keys are needed.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4812	Work In Progress Requested by Lt. Dickerson Rm. 202 North Building-His HEM key has broken, 3 HEM keys are needed. One for him and two for the key box.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4814	Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Air conditioner still does not work. No air is coming out of vents, very hot. Wires hanging into light fixture and a piece of ceiling tile (broken) is in one of the air conditioning vents. (room was damaged over summer)	8/23/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4816	Work In Progress Requested by Ms. L. Melendrez Rm. 331 Academic Building-I have been having trouble opening my front door for over a year, and now I am having trouble opening the back door. It's not my key it's the door handle and deadbolts. Both back doors are very difficult to open.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4817	Work In Progress Requested by Mr. S. Perez Weight Room-Boys locker room door handle needs repair does not open. West side Weight Room door needs repairs does not lock.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4820	Work In Progress Requested by Luis Saucedo Rm. 507 & 509 Annex Building-Install door stops on each of these doors.	8/23/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4822	Work In Progress Requested by Ms. Zapien Rm. 154 Old English Building-The blinds are completely broken, the curtain is hanging.	8/23/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
5066	Work In Progress Requested by Ms. Anderson Rm. 233 North Building(Panther Hut)-Clothes Dryer takes several hours to dry clothes. Order new heating element or check and see if vent is clogged. 9/23 - Route to Mario as per Mike.	8/30/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
5068	Work In Progress Requested by Ms. Anderson Rm. 233 North Building (Panther Hut)-Replace circuit breakers with ones that can handle the load of appliances in the kitchen so we don't constantly trip them. Note from Mr. Chambers: Question? Check and see if appliances can be re-routed to another outlet? Too many appliances on one outlet will cause fire.	8/30/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
5076	Work In Progress Requested by Ms. Anderson Rm. 233 North Building (Panther Hut)-Pastry refrigerator has severe condensation dripping.	8/30/2005 Medium	Velia Alarcon Danny Orozco		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5083	Work In Progress Requested by Mr. Martin Rm. 551 Wood Shop-Hall lock will no unlock, 2nd Notice.	8/30/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5084	Work In Progress Requested by Velia Press Box-Safety Hazard; need to re-duct and install new air conditioner were it can be serviced. FERNANDO, JOSE WILL LOOK INTO ORDERING UPDRAFT UNIT AND SHEETMETAL. AS PER OUR CONVERSATION YOU AND MARIO WILL FORM AND POUR CONCRETE FOR SMALL PAD FOR A/C STAND. IN THE MEAN TIME SERVICE WHAT IS THERE. - M. MUNOZ 9/1/05-MKV XC: WO TO FERNANDO	8/30/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS
4947	Work In Progress Old English Bldg - Heating is turning on and on the computer it states that it is off. Teachers have been complaining on a daily basis that it is too hot. Need your help!	8/26/2005 Medium	Velia Alarcon Margret Villalobos		Gadsden HS
4897	Work In Progress Requested by Velia Rm. 112 Front Office-Two HE27 are needed for key box.	8/25/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4904	Work In Progress Requested by Mr. D. Gallegos Rm. 403-Please install water fountains with hose bibs, between soccer canopies for Athletic events and Gadsden High School P.E. classes.	8/25/2005 Medium	Velia Alarcon Guadalupe Ontiveros		Gadsden HS
4905	Work In Progress Requested by Mr. Milligan Rm. 143 Old English Building-Four keys are needed of HX2. Three for the assistant coaches and one for key box.	8/25/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4627	Work In Progress Requested by Velia Rm. 112 Front Office-Work order #3911 was not asked to me made off master, also three keys were asked for not two. An additional 4 keys are needed as soon as possible.	8/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4630	Work In Progress Requested by Mr. Dixon Rm. 600 Business Building-Needs an F3 gate key.	8/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4631	Work In Progress Requested by Ms. M. Gonzalez Rm. 140 Old English Building-I would like to request a door stop for the new door and blinds fo one of my windows. The room gets "very" warm especially 4th period. Receive measurements from Bldg Mechanic and re-route to Ruben for ordering. 4 ea - 43" W x 90' L	8/17/2005 9/16/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
4633	Work In Progress Requested by ISS Rm. 800 Old Counseling Center-Door frame falling off portable door leading to the old counseling center.	8/17/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS
4516	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-New water heater for kitchen area of Panther Hut. Route to Bldg Mechanic as per Mike 8/15/05 Check to see whats wrong with the H2o heater they have new one in small mech. room.	8/12/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4562	Work In Progress Requested by Ms. Klein Rm. 504 Annex Building-Air conditioner not working and appears to be leaking.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4563	Work In Progress Requested by Ms. Moreno Rm. 126 Main Building-Install white board.	8/15/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4564	Work In Progress Requested by Ms. Nanez Library-Install plywood baks to magazine shelves.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4521	Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Need a lock and spare keys on the new filing cabinet.	8/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5601	Work In Progress Requested by Ms. Thornley Rm. 660 Business Building-No heat/A.C. in lounge. Please attempt to tie into the ducting in my classroom (it has it's own system and is immediately adjacent) so that our lounge can be more comfortable.	9/19/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS
5405	Work In Progress Requested by Velia Rm. 112 Front Office-HG3 is needed for key box.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5406	Work In Progress Requested by Velia Rm. 112 Front Office-Two SA16 are needed, one for Ms. Dominguez and one for key box.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5407	Work In Progress Requested by Marie School Registrar Storage Room East Wing of the Cafeteria-The new vault needs to be re-keyed. The cylinder from the old vault can be placed on the door of the East Wing of the Cafeteria were her new vault is located now.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5409	Work In Progress Requested by Marie Storage Room in the East Wing of the Cafeteria-In the move from the old vault to the storage room one of the fire prove filing cabinet's locks broke. The filing cabinet remained locked, needs to be fixed as soon as possible as the Registrar needs access to these files on a daily basis.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5412	Work In Progress Requested by D. Gallegos Rm. 403 Boys Gym-Install threaded end on faucet or shower in volleyball and boys basketball lockers to allow for a water hose connection.	9/12/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
5414	Work In Progress Requested by Mr. G. Holguin Rm. 342 Academic Building-Cabinets in room need to be stabilized.	9/12/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
5416	Work In Progress Requested by Mrs. Klein Rm. 504 Annex Building-Roof is leaking, one spot has mold, and one panel is buldging down.	9/12/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4166	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace ceiling tile in storeroom and office.	8/3/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4243	Work In Progress Requested by Ms. Bradley Rm. 602 Business Building-Handle on window has broken off, needs to be replaced.	8/5/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4248	Work In Progress Requested by Ms. Gutierrez Rm. 823 Barracks-New cylinder is needed for new filing cabinet, 3 keys are needed.	8/5/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4222	Work In Progress Requested by Mr. Grubaugh Rm. 275C Library-The door to the video room has swollen and will not shut properly unless its slammed.	8/4/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS
4199	Work In Progress Requested by Mr. Chambers Rm. 110 Front Office-Re-key doors, make cylinders off D Master, 4 keys will be needed. Have had several items stolen from office, please re-key as soon as possible.	8/4/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4204	Work In Progress Requested by Cathy Cano Parking Lot-Over Fall Break, have the lines in the North Parking Lot painted.	8/4/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
4153	Work In Progress Requested by Mary Barreras Rm. 130 Old English Building-Need the new key to new lock to Sp. Ed. storage room for files and equipment. Key # M260	8/3/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4429	Work In Progress Requested by Velia Rm. 112 Front Office-Three HE keys are needed for Key Box.	8/10/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4385	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-Two large shop lights are burned out.	8/9/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4386	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-220 Volt Electric extension cord needed with a new female end, current ones puts people at risk of electrocution.	8/9/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4387	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-Need a new oil pressure gauge for air compressor. (0-30 PSI) Current gauge leaks compressor oil out of crankcase and on to the floor. Need a new air pressure gauge for air compressor, current gauge is to small. Need a 0-150PSI gauge.	8/9/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS
4360	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HJ7, one for the floating teacher and one for the Key Box. For room number 753.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4361	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK1, one for the floating teacher and one for the Key Box. For the Auto Shop.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4362	Work In Progress Requested by Velia Rm. 112 Front Office-We need 5 additional keys of HE1. For the Gyms.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4363	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK5, one for the I.A. in the classroom and one for the key box. For room number 569.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4269	Work In Progress Requested by Ms. Jacquez Rm. 752 Barracks-Window is unhinged and needs to be repaired.	8/8/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
4271	Work In Progress Requested by Ms. Kalkwarf Rm. 750 Barracks-Floor tiles are broken and coming off the floor.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS



<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
4272	Work In Progress Requested by Ms. Klein Rm. 504 Annex Building- Having a hard time locking and opening door, appears to be locked but stays unlocked.	8/8/2005  Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4279	Work In Progress Requested by Ms. Littlefield Rm. 226 North Building-The lock on my podium and one storage cabinet is brocken and lost.	8/8/2005  Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4282	Work In Progress Requested by Mr. Martinez Rm. 227 North Building-Replace carpet in Attendance Office area. One edge of the carpet is lifting, our concern is that a person may trip and fall.	8/8/2005  Medium	Velia Alarcon Michael Munoz		Gadsden HS
4283	Work In Progress Requested by Mr. Myers Rm. 509 Annex Building- Key will not open storage door. HJ10 is the key that should open door.	8/8/2005  Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4285	Work In Progress Requested by Mr. Villa Rm. 510 Band Room- Security light in the center of the room does not work.	8/8/2005  Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4286	Work In Progress Requested by Mr. Villa Rm. 510 Band Room-Need two HK13 keys made.	8/8/2005  Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4288	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- Lights are burned out in the shop.	8/8/2005  Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
3902	Work In Progress Requested by Ms. Marquez New Counseling Portable-Two filing cabinets need to be keyed.	7/28/2005  Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3908	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Dr. Pockets to be placed in Marie's copy to be placed on wall.	7/28/2005  Medium	Velia Alarcon Mario Apodaca		Gadsden HS
3909	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Install clock on wall.	7/28/2005  Medium	Velia Alarcon Mario Apodaca		Gadsden HS
3910	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Bracket needed for N.M. Flag.	7/28/2005  Medium	Velia Alarcon Fernando Moncayo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3920	Work In Progress Requested by Velia Front Office-The cylinder for room #107 will not open with a D Master or key assigned to door. This classroom is the Day Care on our campus and the building custodian can not open the classroom to clean. Please fix as soon as possible.	7/28/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3493	Work In Progress Requested by Pamela Holguin Rm. 228 North Building-A door frame is needed. Will have an old door installed, left over from doors that are being replaced in North Building. Also, a door knob that will not lock is needed.	7/12/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS
3494	Work In Progress Requested by Marie New Counseling Center Portable-New portable needs to be keyed HE134. Change old cylinder to doors of new portable doors.	7/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3715	Work In Progress Requested by Mr. Pawloski Rm. 109A Main Building (Sp.Ed. Office)-Please remove the lock in my file cabinet, replace, and re-key it with a new one.	7/20/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3716	Work In Progress ***URGENT***Requested by Velia Library-All the doors in the library need to be secured. They have changed all the door knobs and the cylinders need to be installed. URGENT library has alot of equipment that needs to me locked and secured!	7/20/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2471	Work In Progress Requested by Ms. Lopez Rm. 805 Counseling Center-Re-Key room 805 (both doors) to a D106, two keys are needed.	6/2/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2467	Work In Progress Requested by Velia Front Office-Five additional keys needed of the M master key.	6/2/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2469	Work In Progress Requested by Ms. Lopez Counseling Center-1. Re-key rooms 804, 806, 808, 809 (room 809 has two doors, both doors need to be re-keyed) to an off master key. Needed to store testing materials and is a security issue. Four keys are needed.	6/2/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2436	Work In Progress Requested by Maria Perez Rm. 228 North Building-Have the small brown filing cabinet re-keyed. 3 keys are needed.	6/2/2005 Medium	Velia Alarcon Manny Lozoya	Office	Gadsden HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
2437	Work In Progress Requested by Cathy Rm. 115 Front Office-Need 3 name plates with Cathryn Cano	6/2/2005 Medium	Velia Alarcon Manny Lozoya	Office	Gadsden HS
2441	Work In Progress Requested by Ms. Lopez Rooms 802-809 Counseling Center-Remove carpet from all rooms. As per Mike route to Bldg Mechanic 6/10/05 - mkv	6/2/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS
2442	Work In Progress Requested by Ms. Lopez Business Building- Remove bulletin board strips from hallway outside of room 611 and put them up in main building hallway outside of room 122.	6/2/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
2530	Work In Progress Requested by Mr. Chambers Rm. 110 Front Office-Need a 6 and 7 point keys to open classrooms, storerooms, etc. for construction people at G.H.S., one key of each.	6/6/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2745	Work In Progress Requested by Velia-In room 505 of the Annex Building there's a storage room that the contractors of Lynco Electric need access to. We do not have a key for the deadbolt on that door, needs to be opened as soon as possible for them.	6/13/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2698	Work In Progress Requested by Marie Acosta Rm. 803 Old Counseling Center-Re-key vault in Old Counseling Center. Needs to be off master, 5 keys are needed.	6/10/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2699	Work In Progress Requested by Velia Rm. 112 Front Office-Fix or re-place light bulbs on posts where Juan Diaz' mobile home is located. Where D.P.A. was located on our campus before, extremely dark at night.	6/10/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
2700	Work In Progress Requested by Velia Rm. 112 Front Office-Have one HE200 re-cut, key does not open room. (Weight Room)	6/10/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2701	Work In Progress Requested by Velia Rm. 112 Front Office-Have three HE87 re-cut, keys do not open room. (Training Room)	6/10/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2578	Work In Progress Requested by Velia Rm. 112 Front Office-We need two additional keys of HH6, downstairs Social Workers Office in Old English Building.	6/7/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2579	Work In Progress Requested by Velia Rm. 112 Front Office-We need three additional keys of HE200 (Weight Room).	6/7/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2580	Work In Progress Requested by Velia Rm. 112 Front Office-We need three additional keys of HE131 (my office).	6/7/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2581	Work In Progress Requested by Velia Rm. 112 Front Office-We need five additional keys of DC17 (Swimming Pool).	6/7/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2582	Work In Progress Requested by Velia Rm. 112 Front Office- We need two additional keys of HH9, upstairs Social Workers Office in Old English Building.	6/7/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2583	Work In Progress Requested by Velia Rm. 112 Front Office-We need one additional key of HH7, for I.A. in Ms. Axtell's classroom.	6/7/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
2584	Work In Progress Requested by Isela Rm. 800 Counseling Center- Paint office and doors.	6/7/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS
1638	Work In Progress Requested by Ms. Jordan Rm. 320 Academic Building-Lights blown out.	5/4/2005 Medium	Velia Alarcon Fernando Moncayo	Classroom	Gadsden HS
1640	Work In Progress Requested by Mr. Whitener Rm. 563 Ag. Shop- Needed: one 25 foot extension cord made for the arc welding machines.  Also, repair the female ends on 3 existing extension cords.	5/4/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
1641	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- The oil pressure gauge on the air compressor is broken and drips crankcase oil onto the floor. It also has an air leak on the small copper tubing on the compressor which causes it to turn on frequently.	5/4/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS
1642	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- The door lock on the south shop door (emergency exit) is very difficult to lock and unlock.	5/4/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
1527	Work In Progress Requested by Mr. A. Perez Rm. 550 Wood Shop Building-Paint entry door; in order to avoid tagging. Adjust gap between door.	4/29/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1569	Work In Progress Requested by Fernando Moncayo Varsity Gym- Broken glass in basketball locker room.	5/2/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
1680	Work In Progress Requested by Mr. Chambers Rm. 317 Academic Building-Install a combination lock in the mail room in the Academic Building.	5/5/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
727	Work In Progress Requested by Mr. Haack, Rm 127 Main Building- Window was broken on 3/30/05.	3/31/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
345	Work In Progress The gate on the south side of the school was hit over the weekend. We're unable to close gate, we need this repaired as soon as possible.	3/14/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS
447	Work In Progress Requested by Mr. D. Martinez Rm 227C North Building-Replace windows in the Assistant Principal's Office. The windows that are there currently are painted shut.	3/16/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
448	Work In Progress Requested by Mr. D. Martinez Outside of North Building-Have electrical outlets placed outside the North Building in the shaded area for the candy/snack machines. THIS WO WAS REROUTED TO MIKE MC DERMOTT AS PER MIKE MUNOZ - CC 9/21/05	3/16/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
450	Work In Progress Requested by Mr. D. Martinez main hallway in North Building-Move the snack machines from the main hallway to the shaded area outside, once the electrical outlets have been placed. Need to run new outlets for snack machines - reassign to Dist. Electrician - as per Mario Apodaca 8/23/05 - mkv	3/16/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
315	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop- Install exhaust system (hook up pipe, tubes, etc.) for Jointer/Planer Non-Electrical route to Bldg Mechanic as per C. Castillo 9/7/05 -mkv	3/11/2005 Medium	Velia Alarcon Mario Apodaca	Classroom	Gadsden HS
316	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop- 1. Install heavier electric circuit for operation of drum sander. 2. Re-route machine wiring (belt/disc., sander, etc.) through safety kill switch.	3/11/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
321	Work In Progress Requested by Mr. J. Gonzales Rm 300 Academic Building-No power on south wall of classroom. as per BM reset breaker after power outage.	3/11/2005 5/18/2005 Medium	Velia Alarcon Fernando Moncayo	Classroom	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
179	Work In Progress Requested by Ms. M. Gonzalez, Rm 140 Old English Building-Third Request-The blinds in my room are broken and do not work properly. This will help keep the sun out in the afternoon when the roon gets "very hot". Mario took a look at them, class will need 4 set of blinds measurements 44 X 90	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
185	Work In Progress Requested by Mr. Martin, Rm 551 Wood Shop-Broken Window	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
893	Work In Progress Requested by Mr. Contaldo Rm 103-Paint outside of observatory using white oil-based paint.	4/6/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS
1019	Work In Progress Requested by Ms. Moreno Rm. 126 Main Building-Put blinds on the windows.	4/11/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
1159	Work In Progress Requested by Ms. M. Garcia Rm 752 Barracks-Blinds needed on one window (45 x 60). Fire hazard, covered with paper. Special Ed. classroom	4/14/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
1179	Work In Progress Requested by Velia Rm 113 & 114 Main Building (Front Office)-We need the windows replaced in the men and women bathrooms, we're unable to open or close windows properly.	4/15/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS PATIO
1489	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace broken ceiling tile and install plank roof over office and storeroom.	4/28/2005 Medium	Velia Alarcon Joe Ontiveros	Classroom	Gadsden HS
6454	Work In Progress Requested by Mr. Chambers Football Restrooms-Paint large letters on restroom indicating men's and women's sides, or hang large signs indicating directions.	10/17/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6457	Work In Progress Requested by Ms. Littlefield Rm. 226 North Building-Sink faucet needs to be fixed. Faucet is leaking and she will be having labs soon.	10/17/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
6460	Work In Progress Requested by Mr. Whitener Rm. 563 Ag. Shop-Install a hydraulic door closer on the new front door to the building.	10/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
6704	Work In Progress Requested by Mr. Lawrence Rm. 402 Boys Gym (Offices)-Please fumigate, roach infestation.	10/25/2005 Medium	Velia Alarcon Margret Villalobos		Gadsden HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
6710	Work In Progress Requested Ms. Nanez Library-Backs to shelves need to be installed. Backs are in library, however, they need to be cut down to fit.	10/25/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
6713	Work In Progress Requested by Ms. Trich Library-Please replace blown light bulbs, especially in Librarian's office, room 275b.	10/25/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6830	Work In Progress Requested by Velia Rm. 127 Main Building-When the sound system contractors installed the wiring in Ms. Garcia's classroom. They placed it on a wall Ms. Garcia used for her projector. Once they removed the wiring and placed it on another wall, they left the wall scrated and paint peeled. Wall needs to be repaired and painted.	10/28/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6832	Work In Progress Requested by Ms. Pena Rm. 128 North Building-Plugged kitchen sink.	10/28/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
6833	Work In Progress Requesed by Luis Saucedo Main Building-East and west hallways the light switchs are broken. Having a problem turning on the lights every morning. Light switches on each corner.	10/28/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
6834	Work In Progress Requested by Luis Saucedo Rm. 502 Weight Room-2ND REQUEST Both sinks are loose from the base and the water drains to slow and the urinal has a leak in the base.	10/28/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
6272	Work In Progress Requested by Velia Rm. 112 Main Building-Sink is leaking, the base is warped and growing mold.	10/11/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
6273	Work In Progress Requested by Velia Rm. 100 Main Building-All of the doors and drawers need to be tightened, they're all off their tracks or broken.	10/11/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6274	Work In Progress Requested by Mr. Chambers Varsity Gym- Varsity Gym floor is showing large space and boards are coming loose, needs repair a.s.a.p. SAFETY ISSUE	10/11/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
6280	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop-Replace or repair ceiling tile in office. Second Request	10/11/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
6282	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Paint (or provide paint)for repainting the tool room and paint room. Second Request	10/11/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
6285	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Replace burned out lights in paint room.	10/11/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6286	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Install circuit with sufficient amperage to run Drum Sander. Second Request	10/11/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
6287	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Route stationery power tools through central emergency shut off. Second Request	10/11/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
6288	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Replace burned out transformer for overhead lights. Second Request	10/11/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
6289	Work In Progress Requested by Ms. Trich Rm. 275a Library-Please flush trap or pump sewage to eliminate the odor of raw sewage in the girl's bathroom.	10/11/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
7626	Work In Progress Requested by Mr. Foster and Mr. Chambers Varsity Gym-ATTN: Mike Munoz Replace heating units and duct work. *Girls team practiced in 23 degrees this morning in the gym. *Parents calling and complaining about conditions. *Parents calling Central Office.	11/29/2005 Medium	Velia Alarcon Jose Ambriz	Gym	Gadsden HS
7145	Work In Progress Requested by Ms. V. Lopez Old Counseling Center-Repair hole in ceiling near new ventilation work.	11/7/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
7370	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop- 2ND REQUEST Replace ceiling tile in office storeroom. Consider placing a plywood floor over unprotected tile.	11/15/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
7371	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop- 2ND REQUEST Replace damage ceiling tile in tool room of Wood Shop.	11/15/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7372	Work In Progress Requested by Mr. Contaldo Rm. 103 for Observatory-Re-install horizontal panel and sweep out or vaccum interior floor prior to November 28, 2005.	11/15/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
2385	Work In Progress SWIMMING POOL (PUMP ROOM) - AS PER NM ENVIRONMENT DEPT. POOL REGULATIONS, PUBLIC POOLS AND GENERAL USE POOLS WILL HAVE AN EMERGENCY SHUT OF SWITCH INSTALLED TO TURN OFF RECIRCULATING PUMP IN CASE OF AN EMERGENCY.	5/31/2005 Medium	Raul Sanchez Michael Mc Dermott		Gadsden HS
1499	Work In Progress Irrigation Wells - Need Grounds to pick up old well column piping and dispose of it properly.	4/28/2005 Medium	Raul Sanchez Lorenzo Hernandez		Gadsden HS
3616	Work In Progress replace door at pump room	7/18/2005 Medium	Ricardo Jacquez Danny Miranda		Gadsden MS
7202	Work In Progress Light on the southside of A-WING keeps blinking on and off.	11/8/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
7204	Work In Progress Broken light cover on security light on northside of gym.need to have cover repalced also new bulb.	11/8/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
5793	Work In Progress {{{GYM LOBBY}}} Wall needs to be secured.	9/23/2005 Medium	Rudy Arreola Danny Miranda	Restroom (Boys)	Gadsden MS
5918	Work In Progress Door handle is broken off boys lockerroom	9/28/2005 Medium	Rudy Arreola Manny Lozoya		Gadsden MS
6384	Work In Progress Light by main entrance is not working.	10/13/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
6386	Work In Progress Light on the westside of the bandroom doesnt turn on.	10/13/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
1101	Work In Progress We are going have a new student in a wheelchair the only concern is we need a walkway where the new fence was put up to connect to the side of the bandroom.	4/13/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
1102	Work In Progress Some of the doors to the main entance have a little step the wheelchair may not be able to go up (Concerned the student may flip forward).	4/13/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
851	Work In Progress Fence by the football feild is getting knocked down by students when they are running.	4/5/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
686	Work In Progress Some of the sprinklers in the front of campus are watering on to the street need to them adjusted or replaced.	3/30/2005 Medium	Rudy Arreola Lorenzo Hernandez		Gadsden MS
1465	Work In Progress We need metal frames around windows we several threw out the campus in main bldg. The moulding is missing.	4/27/2005 Medium	Rudy Arreola Ruben Ronquillo		Gadsden MS
1105	Work In Progress Sidewalk on eastside of annex bldg is to steep for wheelchair need sidewalk raised.	4/13/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
5119	Work In Progress Power Outage - El Paso Electric	8/29/2005 Medium	Margret Villalobos Enrique Sotelo		Gadsden MS
2470	Work In Progress GATE BY DITCH NEEDS TO BE REPLACED. IT'S ONLY LOCKED BY A SMALL CHAIN THAT CAN EASILY BE BROKEN (PER YOLIE JACQUEZ). ROUTE TO MANNY LOZOYA AS PER MIKE MUNOZ.	6/2/2005 Medium	Michael Munoz Manny Lozoya		Gadsden MS
2954	Work In Progress Please install new sprinkler by picnic area where sprinkler was broken and run a new line for additional sprinkler by the south east door by cafeteria for proper coverage of irrigation. As per Rudy need to route to Fred Appelzoller. - mkv	6/23/2005 Medium	Michael Munoz Fred Appelzoller		Gadsden MS GROUNDS
2221	Work In Progress Weeds are growing out on the new tennis courts. Please cut and apply a none coloring chemical to prevent weeds from coming out thru concrete and damaging the courts. Also please cut the weeds around tennis court. THanks	5/23/2005 Medium	Michael Munoz Lorenzo Hernandez	Athletic Field	Gadsden MS
354	Work In Progress Need to installing emerg. lights in hallways and restrooms girls and boys as per pm 125602.	3/14/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
326	Work In Progress We are having a problem with students in the cafeteria after hours we need to have dead bolts installed so we can secure cafeteria.	3/11/2005 Medium	Rudy Arreola Manny Lozoya	Cafeteria	Gadsden MS
2194	Work In Progress Need some help for knocking down some walls to make an extra classroom in C-WING old Calixto's office.	5/23/2005 Medium	Rudy Arreola Danny Miranda		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2242	Work In Progress MAIN BANDROOM. We need to remove 2 steps in bandroom to make more room.	5/24/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
2244	Work In Progress Room 140 handle was broken need to have it replaced.	5/24/2005 Medium	Rudy Arreola Manny Lozoya		Gadsden MS
2031	Work In Progress 2 A/C in main gym need to be replaced.	5/17/2005 Medium	Rudy Arreola Jaime Gomez		Gadsden MS
3000	Work In Progress We need change locks due to the floor getting a new coat of varnish and so one can go in.	6/27/2005 Medium	Rudy Arreola Manny Lozoya	Gym	Gadsden MS
2341	Work In Progress Light fixture on eastside of cafeteria was damaged and needs to be replaced.	5/27/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
2784	Work In Progress We need to have the sprinklers in front of school adjusted especially in the B-WING.	6/15/2005 Medium	Rudy Arreola Lorenzo Hernandez	Parking Lot	Gadsden MS
4218	Work In Progress Coil in not cooling cleaned out strainer and checked valve. RM 156	8/4/2005 Medium	Rudy Arreola Jaime Gomez	Classroom	Gadsden MS
4220	Work In Progress Rm 157/158 Unit is not cooling at all cleaned out strainer and checked valves.	8/4/2005 Medium	Rudy Arreola Jaime Gomez	Classroom	Gadsden MS
4725	Work In Progress Portable 500/501 really leak bad right in the center of the room.	8/19/2005 Medium	Rudy Arreola Rudy Arreola	Portables	Gadsden MS
4528	Work In Progress We need 2 water fountains replaced in cafeteria.	8/12/2005 Medium	Rudy Arreola Jaime Gomez		Gadsden MS
5569	Work In Progress VOC BLDG RM#306 - Need some assistance changing out ballast already replaced lamps high ceiling.	9/16/2005 Medium	Rudy Arreola Enrique Sotelo	Classroom	Gadsden MS
5317	Work In Progress Need to cap of water lines and drain removed already removed sink and counters. RM#188.	9/7/2005 Medium	Rudy Arreola Joe Ontiveros	Classroom	Gadsden MS
7621	Work In Progress Rockwall front the school needs to be repaired chunks missing and has sharp edges.	11/29/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
7379	Work In Progress Portable 501 Door was replaced but now the frame is loose and now the door is dragging and is hard to open or close.	11/15/2005 Medium	Rudy Arreola Manny Lozoya	Portables	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3582	Work In Progress IRRIGATION CTRL PANEL - IRRIGATION BOOSTER PUMP IS NOT WORKING. PLEASE TROUBLESHOOT BUS TURNAROUND AREA. ROUTED TO ENRIQUE AS PER RICK 8/2/05	7/15/2005 8/2/2005 Medium	Lorenzo Hernandez Enrique Sotelo		Gadsden MS
117	Work In Progress Softball Field Concession Stand need to run power to it.	3/7/2005 Medium	Mario Apodaca Carlos Castillo	Athletic Field	Gadsden MS
4867	Work In Progress THE PAD HOLDER IS WORN OUT AND WONT HOLD THE PAD AT ALL.	8/24/2005 Medium	Jimmy Carbajal Jimmy Carbajal	Hallway/Corridor	Gadsden MS
7824	Work In Progress JOHNNY'W WAREHOUSE: FREEZER #1 - ONE OF THE FAN MOTORES WENT OUT. SMELLS LIKE IT BURNED OUT.  JOHNNY LECHUGA - SNP WHSMGR 882-6927	12/5/2005 Medium	Jacqueline Aguilar Danny Orozco	Electrical Room	Gadsden MS
7479	Work In Progress Also at GMS Gym Bleachers They have a cheap extension for the score board, could we get a permanent 120v outlet fastened to front of bleachers? thanks , Carlos	11/18/2005 Medium	Carlos Vigil Enrique Sotelo		Gadsden MS
6241	Work In Progress The new roof on the vocational building leaked badly over vacation and the insulation in the old woodshop is falling. Serious problem with students returning tomorrow could fall at any time.	10/10/2005 Medium	Dana Hamel David Boyd	Classroom	Gadsden MS
4643	Work In Progress Need a copy of fire alarm key (See Mr. Hamel for his key).	8/17/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
4522	Work In Progress Door broken in room 500, and window shattered	8/12/2005 Medium	Dana Hamel Danny Miranda	Portables	Gadsden MS
4777	Work In Progress The three locks on the office front window are broken, mostly poor design. The front office is wide open until these are repaired or replaced	8/22/2005 Medium	Dana Hamel Rudy Arreola	Office	Gadsden MS
4778	Work In Progress 2nd request for an "A" master for GMS Campus	8/22/2005 Medium	Dana Hamel Manny Lozoya	Office	Gadsden MS
4982	Work In Progress Whole south side of annex does not have any air, class temperatures are above 95 degrees. The classes opposite hallway have conditioning, Please fix ASAP	8/26/2005 Medium	Dana Hamel Jaime Gomez	Classroom	Gadsden MS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
5499	Work In Progress Change M4 key to a G key in all electrical room on campus, we have no "m" master	9/14/2005 Medium	Dana Hamel Manny Lozoya	Electrical Room	Gadsden MS
5500	Work In Progress change A3 key to a "g" key in storage room in annex	9/14/2005 Medium	Dana Hamel Manny Lozoya	Mechanical Room	Gadsden MS
5501	Work In Progress Repair the outside doors locks "w" master will not open doors to lobby	9/14/2005 Medium	Dana Hamel Manny Lozoya	Hallway/Corridor	Gadsden MS
5502	Work In Progress request 3 new "G" keys for principal and custodians	9/14/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
3651	Work In Progress Mice in Gloria Hernandez office in C Wing. Need control as soon as possible 1) HAD JUAN CHECK FOR ANY FOOD AROUND, 2) REQUESTED THAT THEY ASK R. RONQUILLO FOR MICE TRAPS (W/GLUE) 3) FAXED FOR PRICE QUOTE AS PER M. MUNOZ FOR THE WHOLE C-WING.	7/19/2005 Medium	Dana Hamel Margret Villalobos	Office	Gadsden MS
3652	Work In Progress Cockroach issues for the total school, need a monthly spraying Faxed PO - 8/4/05 -mkv	7/19/2005 Medium	Dana Hamel Margret Villalobos	Hallway/Corridor	Gadsden MS
3653	Work In Progress paint the columns on outside of gym	7/19/2005 Medium	Dana Hamel Rudy Arreola	Gym	Gadsden MS
3654	Work In Progress paint over the scratchouts in boys black restrooms	7/19/2005 Medium	Dana Hamel Rudy Arreola	Restroom (Boys)	Gadsden MS
3655	Work In Progress paint the front columns of the school to remove tagging	7/19/2005 Medium	Dana Hamel Rudy Arreola		Gadsden MS
2789	Work In Progress check to ensure that the flushes are working in lobby bathroom. If they are, then request that custodial clean, clean, and clean again this area (stinks)	6/15/2005 Medium	Dana Hamel Fred Appelzoller	Restroom (Boys)	Gadsden MS
2881	Work In Progress fix exhaust fan in science room 150	6/20/2005 Medium	Dana Hamel Rudy Arreola	Classroom	Gadsden MS
2888	Work In Progress repair holes in ceiling by air conditioner, needs 4 new window blinds, secure fuse box, secure air conditioner switch, repair entry door to class and last can not use the high switch on air conditioner because it makes too much noise.	6/20/2005 Medium	Dana Hamel Rudy Arreola	Portables	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2889	Work In Progress repair all the interior doors, jams and latches. Outside doors are not closing unless lifted by handles	6/20/2005 Medium	Dana Hamel Danny Miranda	Gym	Gadsden MS
2929	Work In Progress Replace door into storage area and repair the frame to keep students from upstairs area	6/21/2005 Medium	Dana Hamel Danny Miranda	Stairway	Gadsden MS
2572	Work In Progress need locks on desk draws and other security measures to ensure that data is not compromised. Gloria Hernandez office and Terry Villalobos data entry clerks in C wing. ASAP	6/7/2005 Medium	Dana Hamel Manny Lozoya	Office	Gadsden MS
7760	Work In Progress Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola		Gadsden MS
5961	Work In Progress please reomve and replaced stained ceiling tiles in Mr.Lowenburgs office.	9/29/2005 Medium	Rudy Arreola		Gadsden MS
6424	Work In Progress WE NEED LIGHTS IN THE BOYS & GIRLS RR IN MAIN BLDG, ALSO WE NEED THE LIGHTS IN HALLWAYS AS PER PM 6095.	10/14/2005 Medium	Enrique Sotelo		Gadsden MS
2708	Work In Progress please repair and tighten existing fence behind mobile home occupant.	6/10/2005 Medium	Michael Munoz	Football Field	Gadsden MS
4095	Work In Progress please fiill hole that is in front of entrance to band room. Will need a backking before gravel is applied. see mike	8/2/2005 High	Rudy Arreola		Gadsden MS
7792	Work In Progress Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola		Gadsden MS
7797	Work In Progress Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola		Gadsden MS
6228	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Juan Acosta		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6229	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Armando Diaz		La Mesa ES
7799	Work In Progress Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Frank Lara		La Mesa ES
7793	Work In Progress Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Frank Lara		La Mesa ES
7716	Work In Progress Kitchen - Need to shutdown gas and water service on Friday, 12/16/05 @ 1:00 pm.	12/1/2005 Medium	Alfredo Holguin David Villalobos	Cafeteria	La Mesa ES
7761	Work In Progress Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Frank Lara		La Mesa ES
5116	Work In Progress cockroach problem  Laura Benavidez - SNP Manager 233-2646	8/31/2005 Medium	Alma Terrell Margret Villalobos	Cafeteria	La Mesa ES
5309	Work In Progress Milk Cooler was at 60 degrees this morning 9/7/05	9/7/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	La Mesa ES
1453	Work In Progress need to plow playground and seed	4/27/2005 Medium	Frank Lara Lorenzo Hernandez		La Mesa ES
4378	Work In Progress locksmith need three keys for supply rm. key no F 49 8/23- Debra needs status on this work order submitted on 8/9/05 - mkv	8/9/2005 Medium	Frank Lara Manny Lozoya		La Mesa ES
4229	Work In Progress lupe ontiv. need helped to cut large branch by picnic table safety issue	8/5/2005 Medium	Frank Lara Guadalupe Ontiveros		La Mesa ES
7526	Work In Progress HVAC, JOSE NEED TO REPLACE GAS VALVE FOR CAFT AREA	11/22/2005 Medium	Frank Lara Jose Ambriz		La Mesa ES
1932	Work In Progress A bubbler system is requested for the trees at the playground.	5/13/2005 Medium	Eddie Baeza Lorenzo Hernandez		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1748	Work In Progress A contactor is requested for a/c units.NEMA size 4. 8502SFO2S.Ser.460/575V 60hz.100HP. 3 phase	5/9/2005 Medium	Eddie Baeza Carlos Castillo		La Union ES
1613	Work In Progress Transformer for the high temp. alarm in the server rm. does not have 120v circuit only the 24v side was hooked up.	5/3/2005 Medium	Eddie Baeza Carlos Castillo		La Union ES
166	Work In Progress A motor starter coil is requested for the boiler pump at new addition	3/8/2005 Medium	Eddie Baeza Jose Ambriz		La Union ES
7832	Work In Progress ALARM TO WALK-IN KEEPS GOINT OFF.  LINDA YANAGA SNP MGR 589-2040	12/5/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	La Union ES
7762	Work In Progress Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Salvador Gonzalez		La Union ES
4917	Work In Progress please repair asphalt where other water line was repired.	8/25/2005 Medium	Michael Munoz		La Union ES
6476	Work In Progress LUJTP - INSTALL DRYER (NEED VENT DIRECTED OUT OF BLDG - OKAYED BY MR. ALVAREZ). PLEASE CALL MR. CASVANTES @ 589-3009 IF YOU NEED ANY INFORMATION.	10/17/2005 Medium	David Villalobos		La Union ES
7795	Work In Progress Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Salvador Gonzalez		La Union ES
7803	Work In Progress Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Salvador Gonzalez		La Union ES
6230	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Santos Galindo		La Union ES
3572	Work In Progress NEED LIGHT BULBS FOR RECESSED LIGHTS AT LA UNION ELEM. THE MAJORITY ARE BURNED OUT. THANK YOU.	7/15/2005 Medium	Arturo Nunez Carlos Castillo		La Union ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3322	Work In Progress Yearly - La Union ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES
3344	Work In Progress Yearly - La Union ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES
7673	Work In Progress LUJTP - Cut weeds around LUJTP Program Bldg in La Union.	11/30/2005 Medium	Margret Villalobos Salvador Gonzalez		La Union ES JTP - Daniel Casavantes
5447	Work In Progress Student Cross Walk - Path on the west side there is a tree that is in the way. Students have to scoot over onto the street.	9/12/2005 Medium	Margret Villalobos Alfredo Holguin		La Union ES
7234	Work In Progress LJTP - Requesting 2 fire extinguishers.	11/9/2005 Medium	Margret Villalobos Ruben Ronquillo		La Union ES
6403	Work In Progress NEED CORK STRIP INFRONT OF THE OFFICE IN HALLAWAY.	10/14/2005 Medium	Santos Galindo Ruben Ronquillo		La Union ES
6718	Work In Progress need electrical outlet on north wall	10/25/2005 10/26/2005 Medium	Santos Galindo Carlos Castillo	Office	La Union ES
6719	Work In Progress need floor tile in lounge	10/25/2005 Medium	Santos Galindo Michael Munoz	Office	La Union ES
7446	Work In Progress would like hallway in old wing painted and frames. and new base trimming.	11/18/2005 Medium	Santos Galindo Salvador Gonzalez		La Union ES
7549	Work In Progress I need a roto block for the advance 200HD PACESETTER.	11/28/2005 Medium	Santos Galindo Jimmy Carbajal		La Union ES
7550	Work In Progress The roto machine that was rebuild starting smoking and it was the belt need to be replace.	11/28/2005 Medium	Santos Galindo Jimmy Carbajal		La Union ES
5117	Work In Progress Lights in computer room keeps going out; breaker needs to be checked.	8/31/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
5371	Work In Progress In the women's restroom, in the southwing, the toilet is constantly flushy.	9/9/2005 Medium	Santos Galindo Salvador Gonzalez		La Union ES
5312	Work In Progress After last nights rainfall, leaks were discovered in rooms #208, #209, and the library.	9/7/2005 Medium	Santos Galindo Lorenzo Solis		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5425	Work In Progress We need Vector Control to come in and spray.	9/12/2005 Medium	Santos Galindo Margret Villalobos		La Union ES
4775	Work In Progress Parking lanes need to be repaint in yellow and bus lane also needs to be repaint but in red. Route to Sal Gonzalez as per Mike 9/13/05 -mkv	8/22/2005 Medium	Santos Galindo Salvador Gonzalez		La Union ES
4825	Work In Progress Need keys for room #100, #106, and room #108; plus keys for a file cabinet in the nurse's office.	8/23/2005 Medium	Santos Galindo Manny Lozoya		La Union ES
4853	Work In Progress SINK AT CUSTODIAL CLOSET AT OLD BLDG. IS CLOGGED UP.	8/24/2005 Medium	Santos Galindo David Villalobos		La Union ES
4695	Work In Progress AUGUST 31 IS OPEN HOUSE WOULD LIKE ALL LIGHTS OUT SIDE TO BE CHECKED BEFORE THEN.	8/19/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4356	Work In Progress in room 202 there is no outlet for refrigeration unit a.s.p.	8/9/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4372	Work In Progress need a fan motor in electrical storage room.	8/9/2005 Medium	Santos Galindo Jose Ambriz		La Union ES
4408	Work In Progress a light next to my office need to be looked at cause it buzzes all day long.	8/10/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4410	Work In Progress They need to check lighting from building cause several lights are off. And some stay on 24 hrs out side.	8/10/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4223	Work In Progress need an electrical outlet by computer hookups room 203.	8/5/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
5503	Work In Progress Old emergency light fixtures (the complete system) are not working can you check them please. thank you	9/14/2005 Medium	Salvador Gonzalez Carlos Castillo		La Union ES
5786	Work In Progress Upper hinge on door at JTP needs to be repair. Might need to be weld	9/23/2005 Medium	Salvador Gonzalez Manny Lozoya		La Union ES
7634	Work In Progress 11/29/05 A furnace roof is not working cold air coming out.	11/29/2005 Medium	Salvador Gonzalez Jose Ambriz		La Union ES
7391	Work In Progress 11/15/05 To Caly. Relocate electrical outlet.	11/15/2005 Medium	Salvador Gonzalez Carlos Castillo		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7393	Work In Progress 11/15/05 Replace bowl wax on man & woman restroom.	11/15/2005 Medium	Salvador Gonzalez Salvador Gonzalez		La Union ES
5949	Work In Progress Music Room needs a new circuit installation.	9/29/2005 Medium	Salvador Gonzalez Carlos Castillo		La Union ES
6418	Work In Progress Work Truck - need to repair broken tial-light.	10/14/2005 Medium	Salvador Gonzalez Angel Gonzales		La Union ES
4864	Work In Progress JTP- Rosaro Ruedas needs a L201 key.	8/24/2005 Medium	Selma Nevarez Manny Lozoya		La Union ES JTP
5466	Work In Progress attn; mike munoz- we need to have kitchen store room tiled with non slip tile like rest of kitchen. francis would really enjoy it. thank you.	9/13/2005 Medium	Michael Mc Dermott Michael Munoz	Cafeteria	Loma Linda ES store room
5283	Work In Progress 9-6-5 attn; lupe b. mr. truillo at loma linda would like to meet with you about moving play ground eqpt. to grass area. thank you.	9/6/2005 Medium	Michael Mc Dermott Guadalupe Ontiveros	Athletic Field	Loma Linda ES
5284	Work In Progress 9-6-5 TO MIKE MUNOZ. MR. T. NEEDS TO TALK WITH YOU ABOUT PUTTING A FENCE ALONG NORTH SIDE OF SCHOOL. K-3 KIDS ARE A CONCERN ABOUT GOING INTO VACANT AREA. THANK YOU.	9/6/2005 Medium	Michael Mc Dermott Michael Munoz	Athletic Field	Loma Linda ES
6217	Work In Progress NEED TO (PER ATTACHED DRAWING): 1. CUT CURB 2. DIG DIRT 4" 3. ADD CRUSH FINE / CEMENT 4. MOVE DUMPSTER INSIDE THE CURB	10/10/2005 Medium	Michael Munoz Guadalupe Ontiveros		Loma Linda ES
1676	Work In Progress NEED ANOTHER ROYAL BAG FOR THE VACUUM CLEANER. TO REPLACE TWO WITH SOME HOLES (DAMAGED). THANK YOU.	5/5/2005 Medium	Luis Solis Jimmy Carbajal		Loma Linda ES
5311	Work In Progress A.S.A.P PLEASE NEED A CORD LESS DRILL , IF POSIBLE A TWO PACK BATTERIAS. ( THANK YOU )	9/7/2005 Medium	Luis Solis Aida Salcedo		Loma Linda ES
7733	Work In Progress NEED SERVICE FOR THE BUFFER MACHINE (DO NOT TURN ON)DON'T START.,(THANK YOU).	12/2/2005 Medium	Luis Solis Jimmy Carbajal		Loma Linda ES
3345	Work In Progress Yearly - Loma Linda ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3323	Work In Progress Yearly - Loma Linda ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
6684	Work In Progress NEED BROKEN DOLLY WHEEL TO BE REPLACED A.S.A.P.	10/24/2005 Medium	Armando Diaz Aida Salcedo		Loma Linda ES
6231	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Luis Solis		Loma Linda ES
7796	Work In Progress Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
7805	Work In Progress Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
5568	Work In Progress As per Mike Munoz issue a 6 & 7 Grand Master keys to Mike Mc Dermott.	9/16/2005 Medium	Manny Lozoya		Loma Linda ES
7763	Work In Progress Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
2481	Work In Progress CONNECT UTILITIES TO PORTABLE.	6/3/2005 Medium	Fred Appelzoller Fred Appelzoller		Loma Linda ES PORTABLES
6538	Work In Progress Need Ditch Witch delivered to Loma Linda tomorrow.	10/18/2005 Medium	David Villalobos Angel Gonzales		Loma Linda ES
699	Work In Progress need window latches for rms 103-106-105-204 asap- need to secure windows at end of day- sent sample to ppd	3/30/2005 Medium	Danny Vega Danny Miranda	Classroom	Loma Linda ES
1761	Work In Progress Needing Speedy to fertilize within next 2 weeks, also needing dirt to build borders for trees	5/9/2005 Medium	Grace Alvarado Lorenzo Hernandez		Loma Linda ES
452	Work In Progress DISTRICT ART SHOW SETUP AT GADSDEN MIDDLE SCHOOL, PUT UP IS APRIL 14, 2005 AT 8:30 AM TAKE DOWN IS APRIL 18, 2005 AT 10:00 AM	3/16/2005 Medium	Grace Alvarado Danny Vega		Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
352	Work In Progress UNABLE TO LOCK ROOM	3/14/2005 Medium	Grace Alvarado Manny Lozoya	Classroom	Loma Linda ES 114
4593	Work In Progress MIKE MUNOZ, REPLACE EAST FENCE	8/16/2005 Medium	Grace Alvarado Michael Munoz		Loma Linda ES
4315	Work In Progress MANNY LOZOYA, FIX LOCK IN 212	8/8/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
4316	Work In Progress MANNY LOZOYA: KEY MADE FOR PORTABLES WILL NOT OPEN STORAGE ROOM. MASTER WILL NOT OPEN STORAGE ROOM. NEEDING STORAGE ROOM OPENED AS SOON AS POSSIBLE.	8/8/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
4317	Work In Progress MANNY LOZOYA: NEEDING KEYS FOR BOOK ROOM, ROOM #208, AND KEY #44	8/8/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
3829	Work In Progress MR. TRUJILLO IS WANTING NEW KEYS MADE FOR DESKS, CABINETTS AND FILE CABINETS. ALSO NEEDING NAME PLATE FOR NEW TEACHERS. MS. BERARD, CHAVEZ-FISHER, GRIEGO, DESANTIAGO, HUGHES, MARKHAM, MEDINA, MERRICK, MONTES, PINA, PRICE, RIOS- ALVILLAR,	7/26/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
7691	Work In Progress TO: JOE AMBRIZ, REPAIR BOILER LINE IN MAIN HALLWAY , LEAKING.	12/1/2005 Medium	Grace Alvarado Jose Ambriz		Loma Linda ES
6686	Work In Progress INSTALL ELECTRICAL CIRCUIT IN ROOM 208 FOR MICROWAVE AND FRIDGE.	10/24/2005 Medium	Grace Alvarado Enrique Sotelo		Loma Linda ES
6665	Work In Progress NEEDS TO REPAIR DUMPSTER PAD THAT WAS BUILT. REPLACE TWO BENCHES ON PLAYGROUND. AND LEVEL PLAYGROUND AREA WITH SCRAPER	10/24/2005 Medium	Grace Alvarado Guadalupe Ontiveros		Loma Linda ES
7361	Work In Progress REPLACE TIMER FOR BOILER	11/15/2005 Medium	Grace Alvarado Jose Ambriz		Loma Linda ES
7764	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
7527	Work In Progress could you please line locate on Monday 11-28- 05. If you have any questions call Carlos Vigil. Thanks	11/22/2005 Medium	Enrique Sotelo	Portables	Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7808	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
7798	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
6232	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Ruben Solis		Mesquite ES
3324	Work In Progress Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3346	Work In Progress Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3971	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
4005	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
4015	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
7190	Work In Progress FLOOR TO WALK- IN NEEDS TO BE REPAIR. SNP STAFF ARE STILL TRIPPING  ALICE F. SNP MGR 233-2341	11/8/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Mesquite ES
7214	Work In Progress 2 VACCUM CLEANERS NEED TO BE REPAIR. WE NEED A LOANER IF POSSIBLE	11/9/2005 Medium	Ruben Solis Jimmy Carbajal	Custodial	Mesquite ES
7624	Work In Progress need 8 sink faucets for restrms. in 2002 wing. defective.	11/29/2005 Medium	Romauldo Apodaca Joe Ontiveros		Mesquite ES
6783	Work In Progress NEED TO ORDER CLAMP FOR FILTERS TANK IN BOILER RM.BOLT IS STIPPED. THANX.	10/26/2005 Medium	Romauldo Apodaca Ricardo Jacquez		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6506	Work In Progress david boyd.need 2 sets of plans for the 1995 addition,per ms. phillips and all hazard team.thank you.	10/18/2005 Medium	Romauldo Apodaca David Boyd		Mesquite ES
6507	Work In Progress kiki, 5 rms w/ out lights need assistance.thanks. ARREGLAR PROBLEMA EN ALAMBRADO DE LUCES EN SALONES DE OLD WING.	10/18/2005 10/18/2005 Medium	Romauldo Apodaca Romauldo Apodaca		Mesquite ES
6508	Work In Progress jaime need to assist w/ boilers to change over to heating,also need gas valve for heater in old office.thanx.	10/18/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES
6509	Work In Progress lupe ontiveros.need play sand for play structures and alma del valle.thanx.	10/18/2005 Medium	Romauldo Apodaca Guadalupe Ontiveros		Mesquite ES
7825	Work In Progress NEED TO RUN ELECTRICAL LINES TO MAIN FIELD FOR RED RIBBON CUTTING CEROMONY ON 12/8/05 AT 6:AM FOR HEATERS AND LIGHTING,PER MS. PHILLIPS.	12/5/2005 Medium	Romauldo Apodaca Enrique Sotelo		Mesquite ES
3558	Work In Progress need compresor changed out on armstrong unit in rm. 608.thanx.	7/14/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES
3955	Work In Progress DINING AREA - NEED TO WELD HINGES ON DOOR FALLING DOWN.	7/29/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
4340	Work In Progress manny need to assist w/ 2 doors in porables having hard time tpo close safety issue. also need lever handle.	8/9/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
4699	Work In Progress manny need your assistance w/ doors that are hard to open and close. thanx.	8/19/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
1619	Work In Progress have leak between wall in rm. 401 rest rm.thanx.	5/3/2005 Medium	Romauldo Apodaca Fred Appelzoller		Mesquite ES
1621	Work In Progress need replacement of a/c side draft in portable 610.	5/3/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES
1622	Work In Progress need replacement of indusrial unit on barracks,per phillips and leyva.	5/3/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES
2152	Work In Progress PORTABLE 612 - DOOR HANDLE BROKEN.	5/20/2005 Medium	Romauldo Apodaca Manny Lozoya	Portables	Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
971	Work In Progress NEED FILING CABINETS CYLINDERS REPLACED.THANX.	4/8/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
2664	Work In Progress need tile replaced rm. 113,111,110. 602 carpet instead of tile.	6/9/2005 Medium	Romauldo Apodaca Michael Munoz	Classroom	Mesquite ES 602,113,111,110.
2116	Work In Progress BERNICE SAPIEN - ROOM 304 NEED A NEW LOCK FOR FILING CABINET - KEY BROKE INSIDE LOCK.	5/19/2005 Medium	Luz Griego Manny Lozoya	Classroom	Mesquite ES
7834	Work In Progress Need to make a key for D. Miranda's Office for Ruben.	12/5/2005 Medium	Ruben Ronquillo Manny Lozoya		Physical Plant Complex
353	Work In Progress Need to installing emerg. lights as per pm 125559.	3/14/2005 Medium	Rudy Arreola Enrique Sotelo		Physical Plant Complex
2997	Work In Progress TRANSP. OFFICE - NEED TO RELOCATE ELEC. OUTLETS A/S/A/P.	6/27/2005 Medium	Sitters Walter Enrique Sotelo		Physical Plant Complex
7524	Work In Progress NEED TWO WALL HANGING FILING CABINETS REINFORCED. THEY ARE CURRENTLY NOT VERY STURDY. (IN AIDAS OFFICE)	11/22/2005 Medium	Maria Sitters Danny Miranda		Physical Plant Complex
5121	Work In Progress Power Outage - El Paso Electric	8/29/2005 Medium	Margret Villalobos Enrique Sotelo		Physical Plant Complex
3940	Work In Progress MARTA JACQUEZ - A/C UNIT IS NOT WORKING AT ALL.	7/29/2005 Medium	Marta Jacquez Jaime Gomez		Physical Plant Complex
2657	Work In Progress LADIES RR - THE FAUCET SHOOTS THE WATER OUT IN UNEVEN SPURTS AND ON THE TOILET THE LINE CONNECTING TO THE WALL, MAKES A LOUD SOUND AND RATTLES AND THE WATER FILLING IN COMES IN DIRTY.	6/9/2005 Medium	Marta Jacquez Fred Appelzoller	Restroom (Girls)	Physical Plant Complex
2263	Work In Progress Maint. Office - Need to fix door closer to main door.	5/24/2005 Medium	Margret Villalobos Manny Lozoya		Physical Plant Complex
1673	Work In Progress Transporation Office - Need to install door w/window.	5/5/2005 Medium	Margret Villalobos Danny Miranda		Physical Plant Complex
5735	Work In Progress AS PER ALFREDO I NEED A COPY OF KEY TO CUSTODIAL OFFICE. THANK YOU.	9/22/2005 Medium	Maritza Gonzalez Manny Lozoya		Physical Plant Complex



<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
7377	Work In Progress Light by fueling station is missing cover needs to be repalced.	11/15/2005 Medium	Rudy Arreola Enrique Sotelo	Parking Lot	Physical Plant Complex
4017	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
2357	Work In Progress Custodial Office - Need to correct cooling in Mary and Aida's Office.	5/27/2005 Medium	Alfredo Holguin Jaime Gomez	Custodial	Physical Plant Complex
7772	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
7810	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
3092	Work In Progress Install Speed limit signs and speed bumps on access road. See me on specifics Faxed PO on 8/4/05 - mkv	6/30/2005 8/8/2005 Safety	Alfredo Holguin Michael Munoz		Physical Plant Complex
3186	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
3461	Work In Progress Need a copy of control key (core) to keep here at the Maintenance Dept - as per A. Holguin.	7/12/2005 Medium	Alfredo Holguin Manny Lozoya		Physical Plant Complex
7711	Work In Progress please order all material needed to paint barracks in the back and let me know what staff will be need to accomplish the project.	12/1/2005 Medium	Danny Miranda	Portables	Physical Plant Complex
7642	Work In Progress Auto Shop - Need to install 4 cylinders all the same but different from main entrance. Need 4 keys issued (see Angel).	11/30/2005 Medium	Angel Gonzales Manny Lozoya		Physical Plant Complex
5526	Work In Progress NEED A "CB4" KEY FOR GUILLERMO - TO HAVE ACCESS TO ENERGY OFFICE TO CLEAN.	9/15/2005 Medium	Manny Lozoya		Physical Plant Complex
2235	Work In Progress please order material for fill for disrict portable re-location. please include site and material that will be delivered on w.o . (per site)	5/24/2005 Medium	Lorenzo Hernandez		Physical Plant Complex
3379	Work In Progress Mens Restroom in Custodial Warehouse -Install new privacy lockset	7/7/2005 Low		Restroom (Boys)	Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3380	Work In Progress Mens Restroom in Custodial Warehouse- Replace toilet tank cover with appropriate size for unit.	7/7/2005 Medium	Fred Appelzoller	Restroom (Boys)	Physical Plant Complex
5432	Work In Progress Auto Shop - need to install new door knob to new door at Angel's Office.	9/12/2005 Medium	Danny Miranda Manny Lozoya		Physical Plant Complex
1309	Work In Progress Need to make material list and request for general maintenance duties	4/21/2005 Medium	Carlos Castillo Carlos Castillo	Electrical Room	Physical Plant Complex
4585	Work In Progress Need to replace water heater,its giving out an extremeley bad odor.Health issue.	8/16/2005 Medium	Carlos Castillo Joe Ontiveros	Electrical Room	Physical Plant Complex
7619	Work In Progress Jimmy I have a broken vacuume.	11/29/2005 Medium	Guillermo Hernandez Jimmy Carbajal		Physical Plant Complex
2631	Work In Progress Need to replace door knob to outside Double Doors.	6/8/2005 Medium	HECTOR LOZOYA Manny Lozoya		Physical Plant Complex
7659	Work In Progress VEGETABLE SINK IS CLOGGED AGAIN. AND THERE IS NO HOT WATER AGAIN.  NANCY ROLLIN RS SNP MGR 589-2550	11/30/2005 Medium	Jacqueline Aguilar Danny Orozco	Custodial	Riverside ES
7484	Work In Progress Need a master key for ESA Construction for Monday. (Please give key to Peggy Jo)	11/18/2005 Medium	David Boyd Manny Lozoya		Riverside ES
4998	Work In Progress NEED TO ORDER 2 R.R. PARTITIONS FOR RIVERSIDE ELEM. paint rr partitions and install	8/29/2005 Medium	Danny Miranda Danny Miranda		Riverside ES
2085	Work In Progress RM 39, PLEASE REMOVE OLD CAULK AND BLOW OUT WITH AIR. iNSTALLED NEW SEAL TO PREVENT AIR FROM ENTERING. ROOF TOP	5/18/2005 Medium	Adan Duran	Classroom	Riverside ES
2086	Work In Progress PLEASE INSTALL NEW WEATHER STRIPPING TO ALL DOORS AND WINDOWS TO PREVENT SAND FROM ENTERING ROOM.	5/18/2005 Medium	Adan Duran	Classroom	Riverside ES
2088	Work In Progress PLEASE REMOVE OLD SEAL, INSTALL NEW ONE WITH NEW CAULKING AND 45 CONCRETE AGAINST WALL AND FLOOR. OUTSIDE PATIO WHERE MAIN HALL WAY ENTERS TOWARDS CAFETERIA. THIS WILL PREVENT WATER FROM ENTERING TO BUILDING.	5/18/2005 Medium	Adan Duran	Cafeteria	Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5592	Work In Progress please see what can be done to repair or remove electrical outlet on floor on serving line. Outlet has a can over it and could be a trip hazard.	9/19/2005 Medium	Danny Orozco	Cafeteria	Riverside ES
6956	Work In Progress please provide sidewalk to portable that was moved in this summer.	11/2/2005 Medium	Michael Munoz		Riverside ES
7627	Work In Progress MR MIKE MUNOZ SIR WOULD LIKE TO USE BOBCAT HAVE A LOT OF SAND FROM WINDS AROUND ROCK WALL AND IN BACK BY DUMPSTERS THANK YOU SIR	11/29/2005 Medium	Adan Duran Guadalupe Ontiveros		Riverside ES
7505	Work In Progress MR CASTILLO SIR WILL NEED TO REPLACE BELAST BOYS BATH ROOM LOWER GRADE BY OFFICE THANK YOU SIR	11/21/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
7415	Work In Progress MR CARLOS CASTILLO SIR NEED LIGHT BULBS FOR BATHROOM THEN ARE U SHAPE 22" LONG BY 7" WIDE OUT SIDE TO OUT SIDE THANK YOU SIR	11/16/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
7156	Work In Progress 11/7/05 1/2 SIGN IN CHECK SCHOOL GROUNDS 2 1/2 MOWED GRASS 1 1/2 EDGE WITH TRIMER 1 CLEAN SIDEWALKS WITH BLOWER 1 REPAIR ENTRANCE DOOR WILL NOT CLOSE 1/2 CLOSE WEST AND DROP OFF GATES 1 FILE PAPER WORK AND SIGN OUT 11/7 - 8	11/7/2005 Medium	Adan Duran Adan Duran		Riverside ES
6854	Work In Progress MR DAVID VILLALOBOS SIR RELIEF VALUE BIG WATER HEATER IN NEW WING IS LEAK NEED TO REPLACE THANK YOU SIR	10/28/2005 Medium	Adan Duran David Villalobos		Riverside ES
6689	Work In Progress MR CARLOS CASTILLO CALLI MR LORENZO SPEEDY REPORTED SOME OF THE LIGHTS ON BACK POLE AND ONE ON NORTH SIDE PARKING POLE ARE NOT COMING ON WILL NEED THE HIGH LIFT TO CHANGE THANK YOU SIR	10/24/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
6559	Work In Progress MR CARLOS CASTILLO MR CASTILLO THE LIGHTS ON THE OUT SIDE NORTH EAST SIDE ARE OUT NEED TO REPLACE VERY DARK ON THAT SIDE THANK YOU SIR	10/19/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
5115	Work In Progress MR LUPE ONTIVEROS SIR WILL NEED THE USE OF THE BACKHOE TO MOVE SOCCOR GOAL POST AWAY FROM PARKING AREA UNSAFE FOR KIDS THANK YOU SIR	8/31/2005 Medium	Adan Duran Guadalupe Ontiveros		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4473	Work In Progress MR MANNY LOZOYA SIR THE DOOR ON NEW PORTABLE IS STUCK IN LOCK CAN NOT GET IT TO UNLOCK PORTABLE B IN BACK THANK YOU SIR	8/11/2005 Medium	Adan Duran Manny Lozoya	Portables	Riverside ES
4596	Work In Progress MR MANNY LOYZOA SIR NEED TO CHANGE OUT DOOR HANDLE BY MRS ARIAS OFFICE THE ONE THERE DO NOT LOCK NEED ONE THAT CAN BE LOCKED THANK YOU SIR	8/16/2005 Medium	Adan Duran Manny Lozoya		Riverside ES
4388	Work In Progress MR JOSE AMBRIZ SIR WE NEED TO HOOK BACK UP THE AIR IN WHAT USE TO BE MRS FLORES OFFICE IT WAS REMOVE AT HER REQUEST AND ITS KIND OF WARM IN THERE THANK YOU SIR	8/9/2005 Medium	Adan Duran Jose Ambriz		Riverside ES
3690	Work In Progress MR MANNY LOZOYA FILE CABINET NEW PORTABLE RM B NEEDS REPAIR WILL NOT LOCK PARTS MISSING THANK YOU SIR	7/19/2005 Medium	Adan Duran Manny Lozoya		Riverside ES
3778	Work In Progress MR DAVID VILLALOBOS WE HAVE SOME LEAKING FUACTS NEW WING NEED REPAIR KIT OR REPLACEMENT THANK YOU SIR	7/22/2005 Medium	Adan Duran David Villalobos		Riverside ES
3414	Work In Progress MR LOZOYA MRS ARIAS IS HAVING TROUBLE WITH THE STORAGE ROOM LOCK WOULD LIKE FOR YOU TO LOOK AT IT THANK YOU SIR	7/8/2005 Medium	Adan Duran Manny Lozoya		Riverside ES
3415	Work In Progress MR JOSE AMBRIZ THE LITTLE ROOM WHERE WATER HEATER IS IN THE NEW WING IS GETTING HOT SETTING OFF ALARM NEED EXHUST FAN TO DRAW HEAT OUT THANK YOU SIR	7/8/2005 Medium	Adan Duran Jose Ambriz		Riverside ES
2982	Work In Progress 6/24/05 MR JOSE AMBRIZ SIR THE HEATING COIL IN THE WOMANS BATHROOM NEW WING IS LEAKING ALONG THE WALL THANK YOU SIR	6/24/2005 Medium	Adan Duran Jose Ambriz		Riverside ES
7765	Work In Progress Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
7812	Work In Progress Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
7800	Work In Progress Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3348	Work In Progress Yearly - Riverside ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3326	Work In Progress Yearly - Riverside ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
6233	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Jimmy Carbajal		Riverside ES
2074	Work In Progress When fire alarm system replaced, ceiling light in upper grade library storage was removed and not placed back. Refrigeration air escaping and may cause overheating of unit and server located in room.	5/18/2005 Medium	Miguel Aguilar Adan Duran		Riverside ES
2540	Work In Progress Need copies (3) made of regular master padlocks located in halls used to secure exits with chain.	6/6/2005 Medium	Miguel Aguilar Manny Lozoya		Riverside ES
3768	Work In Progress NEED APPLIANCE TRUCK TO MOVE SOME FIREPROOF CABINETS.	7/22/2005 Medium	Raul Romero Jimmy Carbajal	Classroom	Riverside ES
5609	Work In Progress Having prolems with Roaches and Black insect (Ticks) in rooms and Hallways, Storage area etc.. could we have the Whole building extremitted during intersession. We have no students at this time. 10/11 - WAITING ON PURCHASE ORDER - MKV	9/19/2005 Medium	Olga Arias Margret Villalobos		Riverside ES
5057	Work In Progress We need a new Door Knob placed in the Data Clerk office. (office area) At this time the door doesn't lock.	8/30/2005 Medium	Olga Arias Manny Lozoya		Riverside ES
5058	Work In Progress Carpet (Doorway) to Data clerk office is coming loose. Plastic edge is picking-up.. Thanks	8/30/2005 Medium	Olga Arias Michael Munoz		Riverside ES
2241	Work In Progress Need to repair carpet. (edge) is picking-up within the office area. Doorway to the back copy room. Adan can you glue this down? - As per Mike.	5/24/2005 Medium	Olga Arias Adan Duran		Riverside ES
7015	Work In Progress Need backflow tested on irrigation system thanks	11/4/2005 Medium	Ricardo Jacquez Joe Ontiveros		San Miguel ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
214	Work In Progress Please replace nonlocking door knob with locking one. Mrs. Avalos portable#45.	3/9/2005 Medium	Lorenzo Solis Manny Lozoya		San Miguel ES
216	Work In Progress Replaced falling apart door knob with new one on entrance door in cafeteria.	3/9/2005 Medium	Lorenzo Solis Manny Lozoya		San Miguel ES
717	Work In Progress Boiler Room - relief valve drain is not properly supported. As per Boiler Inspector.	3/30/2005 Medium	Michael Munoz Jaime Gomez		San Miguel ES
6234	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Cervando Padilla		San Miguel ES
7801	Work In Progress Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
7813	Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
3087	Work In Progress Double portable relocated to site was labeled as SM17DM1R there is no portable with that ID. Re-label this and all portables correctly.	6/29/2005 Low	Alfredo Holguin Michael Munoz	Portables	San Miguel ES
3175	Work In Progress Monthly - San Miguel ES Roof Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
7766	Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
7117	Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
7105	Work In Progress Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7632	Work In Progress The backflow prevention device on the irrigation distribution system needs to have the annual inspection performed.	11/29/2005 Medium	Guadalupe Ontiveros		San Miguel ES
7070	Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
6954	Work In Progress please provide side walks to the last 2 portables that where moved in. rms 50&51	11/2/2005 Medium	Michael Munoz	Portables	San Miguel ES
6955	Work In Progress please provide concrete landing and sidewalk to portable 51	11/2/2005 Medium	Michael Munoz	Portables	San Miguel ES
1852	Work In Progress Please order paint so when portables arrive you can go ahead and paint. You site will be receiving one PLease see mike or call him for more info.	5/11/2005 Medium	Danny Vega	Portables	San Miguel ES
1766	Work In Progress KEY JAMMED IN CORE/CORE WILL NOT TURN - OVER	5/10/2005 Medium	Danny Vega Manny Lozoya	Classroom	San Miguel ES PORTABLE#37
1881	Work In Progress NEED TOP PIVOT LACTH HINGE/RIGHT SIDE FOR METAL DOOR IN LIBRARY ASAP	5/12/2005 Medium	Danny Vega Manny Lozoya	Classroom	San Miguel ES LIBRARY
1820	Work In Progress need filetrs for units 12ea) 20x20x1 pleated 12ea )12x25x1 pleated 12ea)12x25x1 pleated -asap	5/11/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
1821	Work In Progress ramp not level- door hits bottom platform -need to lift with chains asap	5/11/2005 5/12/2005 Medium	Danny Vega Danny Vega	Classroom	San Miguel ES #37
1826	Work In Progress NEED 14X30X1 PLEATED FILERS 8EA	5/11/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
1749	Work In Progress NEED TO REPLACE GUTTERS IN KITCHEN ROOF/NEED SCAFFOLDS/ D.MIRANDA NEED TO ORDERS GUTTERS.	5/9/2005 5/9/2005 Medium	Danny Vega Danny Miranda	Cafeteria	San Miguel ES
2103	Work In Progress need number (stick-on )plates for all class rm doors as per MRS DUNCAN (PRINCIPAL) 1 THRU 60	5/19/2005 Medium	Danny Vega Manny Lozoya		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2118	Work In Progress REFG. AIR UNIT PORTABLE#33/IS NOT WORKING/USED FOR SUMMER SCHOOL /NEED HVAC -TECH	5/19/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
2686	Work In Progress need bob-cat sweeper to clean staff parking & re-stripe	6/10/2005 Medium	Danny Vega Lorenzo Hernandez		San Miguel ES
2347	Work In Progress need to open & install door between rms 37 and 38	5/27/2005 Medium	Danny Vega Danny Miranda	Portables	San Miguel ES rm#37-38
6301	Work In Progress need additional ventilation in cafeteria/exhaust	10/11/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
6367	Work In Progress rm#32 day&night type furnance/pilot wont stay on-needs thermo-couple	10/13/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
6584	Work In Progress NEED LOCK-OUT DEVICE FOR DISCONNECT BOX/PORTABLE 28-29/POWER SHUT-OFF DAILY-ASAP	10/20/2005 Medium	Danny Vega Enrique Sotelo		San Miguel ES
6617	Work In Progress j.gomez/need to start and go thru check list on boiler unit/before 10-28-05 (.you can do it)	10/21/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
6618	Work In Progress need two loads playground sand asap	10/21/2005 Medium	Danny Vega Guadalupe Ontiveros		San Miguel ES
6785	Work In Progress boiler is not heating/please ck it out/class rooms are cold in the morning	10/26/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
7563	Work In Progress boys restroom heater coil leaks water/need replaced asap found leak and repaired it	11/28/2005 12/1/2005 Medium	Danny Vega Lorenzo Solis		San Miguel ES
7173	Work In Progress PARKING LOT SECURITY LIGHT IS ON DAY&NIGHT/SENSOR IS NOT WORKING/WEST PARKING LOT.	11/8/2005 Medium	Danny Vega Enrique Sotelo		San Miguel ES
5315	Work In Progress need replacement faucets for double sinks /kitchen .please stop by asap/	9/7/2005 Medium	Danny Vega Danny Orozco	Cafeteria	San Miguel ES
5176	Work In Progress CAFETERIA GIRLS RR/SINK FAUCET BROKEN - OFF /PLEASE REPLACE/HOT-COLD TYPE	9/2/2005 Medium	Danny Vega Joe Ontiveros		San Miguel ES
5177	Work In Progress NEED FILTERS 12X24X1	9/2/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5307	Work In Progress portable #28 refrig unit not cooling/please check it out asap	9/7/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
5270	Work In Progress NEED LDO 2QT/FLUSH VALVE KIT/DIAPRAHMS/TUB&SINK SEALER/ELONGATED TIOLET SEAT	9/6/2005 Medium	Danny Vega Joe Ontiveros		San Miguel ES
4051	Work In Progress portable #30/rheem a/c unit not woking.stop by asap	8/1/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
4445	Work In Progress Portable 29 - Needs to be secured by the end of the day.	8/10/2005 Medium	Danny Vega Manny Lozoya	Portables	San Miguel ES
4447	Work In Progress principals office door hard to open/door needs to be shaved.stop by asap	8/10/2005 Medium	Danny Vega Manny Lozoya		San Miguel ES
3834	Work In Progress A/C UNIT NOT WORKING IN HIGH SPEED PORTABLE#58	7/26/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
4489	Work In Progress Need an extra key for these rooms.	8/11/2005 Medium	Barbara Cardenas Manny Lozoya	Classroom	San Miguel ES 25, 49,50
1777	Work In Progress Need a lock installed in a filing cabinet in the Library.	5/10/2005 Medium	Barbara Cardenas Manny Lozoya		San Miguel ES
7561	Work In Progress need repairs on royal vacuum#co2a 00003445 asap.thank you	11/28/2005 Medium	Cervando Padilla Jimmy Carbajal		San Miguel ES
5337	Work In Progress DISHWASHER LEAKING WATER.  EVA MIRANDA - 233-2860	9/8/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	San Miguel ES
7323	Work In Progress Need to check Lounge and Admin. Office Units. Have to reset units manually everyday. (Jose Ambriz informed Renee of problem). Please send someone out to check these. - Thanks	11/14/2005 Medium	Jose Ambriz Margret Villalobos		Santa Teresa ES
7297	Work In Progress 11/8/05 8-ATTENDED LCN DOOR CLOSER WK. SHOP. 11/8 - 8	11/11/2005 Medium	Gerardo Marquez Gerardo Marquez		Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6450	Work In Progress 10/3/05 1-insp. bldg.and grnds. picked up trash. 1-tried to fix broken stop sign at bus pick up exit. 1-fixed bus exit gate. (was knocked down over the wk. end) 4-mowed grass. 10/3 - 7	10/17/2005 Medium	Gerardo Marquez Gerardo Marquez		Santa Teresa ES
5872	Work In Progress ATTN. DAVID VILLALOBOS; DAVE , NEED FOR YOU TO CHECK OUT TOILETS IN RM. 107, AND ALSO THE ONE IN THE MENS FACULTY RR. FLOATS ARE STICKING.	9/27/2005 Medium	Gerardo Marquez David Villalobos		Santa Teresa ES
4152	Work In Progress ATTN MANNY. MANNY, WE STILL NEED FOR YOU TO MAKE US ANOTHER KEY TO THE MAIL BOX. THANKS.	8/3/2005 Medium	Gerardo Marquez Manny Lozoya		Santa Teresa ES
4154	Work In Progress ATTN LUPE, LUPE, WE STILL NEED THE COBBLESTONE TO KEEP CHECK THE RAIN ERROSION. ALSO NEED FOR BETO AND MANNY TO REDIG TRENCH AT BACK FENCE TO KEEP RAIN FROM FLOODING GROUNDS AND CLASS RMS.	8/3/2005 Medium	Gerardo Marquez Guadalupe Ontiveros		Santa Teresa ES
3657	Work In Progress ATTN. Manny . NEED FOR YOU TO DUPLICATE A KEY TO THE MAIL BOX . THANKS .	7/19/2005 Medium	Gerardo Marquez Manny Lozoya		Santa Teresa ES
5725	Work In Progress ATTN; CALICASTILLO CALI COULD YOU PLEASE ORDER ME FOUR BOXES OF 4 FOOT FLOURECENT LAMPS. THANKS. supplied J.MARQUEZ WIHT LAMPS.	9/22/2005 10/26/2005 Medium	Gerardo Marquez Carlos Castillo		Santa Teresa ES
453	Work In Progress ATT. ANGEL GONZALEZ. ANGEL I NEED FOR YOU TO SERVICE TRUCK 107.WOULD YOU LET ME KNOW WHEN YOU CAN FIT IT IN TO YOUR SCHEDULE. THANKS.	3/16/2005 Medium	Gerardo Marquez Angel Gonzales		Santa Teresa ES
454	Work In Progress ATT. CALI CASTILLO. CALI, NEED FOR YOU TO FOLLOW UP ON WK. OR. 124323. THANKS. NEED FOR YOU TO COME CHECK A COUPLE OF LIGHT FIXTURES THAT I AM HAVING TROUBLE WITH.	3/16/2005 Medium	Gerardo Marquez Carlos Castillo		Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2432	Work In Progress ATTN. MARGRET; NEED FOR YOU TO CALL EXTERMINATOR TO SPRAY FOR FLYING ANTS. HAVE BEEN SPRAYING WITH THE DEAD-SURE, BUT I STILL CANT GET RID OF THEM. PARENTS HAVE BEEN COMPLAINING TO RITA. I TALKED TO MIKE, AND HE SAID TO SEND YOU A WK. ORDER. Faxed PO on 6/8/05 45013796	6/2/2005 Medium	Gerardo Marquez Margret Villalobos		Santa Teresa ES
2323	Work In Progress 5/26/05 MIKE; I NEED FOR YOU TO GET ME A COPY OF THE PAINT SCHEDULE. THANKS.	5/26/2005 Medium	Gerardo Marquez Michael Munoz		Santa Teresa ES
7751	Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
7814	Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
7802	Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
6235	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Pablo Diaz		Santa Teresa ES
3958	Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
4021	Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
4009	Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
7560	Work In Progress RISERS NEED TO BE PICKED UP FROM STHS (FOR OUR CHRISTMAS PROGRAM) ON 12/13/05 AND RETURNED BACK TO STHS ON 12/16/05.	11/28/2005 Medium	Rita Mendez Gerardo Marquez		Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
348	Work In Progress BOTH MIRROR FROM BOYS BATH ROOM ARE FADED THEY NEED TO BE REPLACE IN THE ENGLISH WING THANK YOU.	3/14/2005 Medium	Luis Murillo Ruben Ronquillo		Santa Teresa HS
6519	Work In Progress NEED 4-PAIRS OF BLACK RUBBER BOOTS FOR SCRUBBING FLOORS SIZES 11, 7, 7, N 9 THANK YOU GUILLERMO.	10/18/2005 Medium	Luis Murillo Guillermo Hernandez		Santa Teresa HS
923	Work In Progress WE NEED CHECK AND REPAIR DOOR LOCK NO WELDING CLASS ROOM AT V.O.C BUILDING	4/7/2005 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS
4966	Work In Progress RUBEN WE NEED REPAIR THE WINDOWS AT DAYCAREBUILDING IT DOESN'T OPEN THANK YOU Route to Joel as per Mike 9/12/05 - mkv	8/26/2005 Medium	Joel Herrera Joel Herrera		Santa Teresa HS
5102	Work In Progress WE NEED REPLACE MA 51 AND TREE LOCKS AT R.O.T.C CLASS ROOMS.	8/30/2005 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS
4807	Work In Progress MANNY MY MASTER KEY IS BROKEN IT DOESN'T WORK NO MORE.	8/23/2005 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS
4463	Work In Progress SENSOR ON SINK AT GIRLS REST ROOM IT DOESN'T WORK WE REPLACE IT .	8/11/2005 Medium	Joel Herrera David Villalobos		Santa Teresa HS
4454	Work In Progress SMASHED WINDOW ON DOOR - STOLEN LARGE SCREEN TV. DISCOVERED BY MR. BUCKLEY	8/1/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
7557	Work In Progress BROKEN DOOR'S WINDOW ON CLASS ROOM T- 100 AT V.O.C BUILDING SIZE 27 X 61 WIRE GLASS	11/28/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
5923	Work In Progress MIKE MUNOZ WE NEED BARRIER FENCE ON WEST SIDE AT SOCCER FIELD TO RETAIN BALLS OUT IT PLAY . ALSO NEED FENCE FROM 20 YARD LINE TO 20 YARD LINE IN FRONT OF FOOTBALL VISITORS SEATING AREA. SEE R GALLEGOS THANK YOU MIKE...	9/28/2005 Medium	Joel Herrera Michael Munoz		Santa Teresa HS
6567	Work In Progress BROKEN TOILER SET AT ISS CLASS ROOM AND WE NEED REPLACE IT	10/19/2005 Medium	Joel Herrera David Villalobos		Santa Teresa HS
7740	Work In Progress UNCLOG BOYS OLD LOCKER ROOM REST ROOMS AT G.Y. M AREA	12/2/2005 Medium	Joel Herrera David Villalobos		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3329	Work In Progress Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3351	Work In Progress Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
6236	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Luis Murillo		Santa Teresa HS
7159	Work In Progress NEED A FLORECENT LIGHT FIXTURE INSTALLED AT SECURITY GUARD SHACK.	11/7/2005 Medium	Arturo Nunez Carlos Castillo		Santa Teresa HS
7164	Work In Progress NEED SOME SOURCE OF HEAT FOR SECURITY GUARD SHACK, BEING PORTABLE, OR PERMANENTLY INSTALLED. THANK YOU.	11/7/2005 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS
7169	Work In Progress NEED FOUR (4) EA. ALLEN-BRADEY CONTROL RELAY BULLETIN 700, TYPE H, CAT #700- HHF73A1, SER A . HAVE SAMPLE WITH ME IF YOU NEED MORE INFO. THIS ARE GOING TO GYM BLEACHERS. THANK YOU.	11/7/2005 Medium	Arturo Nunez Carlos Castillo		Santa Teresa HS
6927	Work In Progress NEED A SET OF BROUNING GRIP NOTCH V BELTS. #5VX840, 358, FOR NEW AIR HANDLER UNIT AT LIBRARY.	11/1/2005 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS
7342	Work In Progress NEED A FIFTY (50) GALLON WATER HEATER, TO REPLACE THE ONE AT CUSTODIAL CLOSET, IT IS LEAKING REAL BAD, AND WE HAD TO SHUT DOWN, RED TAG. CUSTODIANS NEED THE HOT WATER.	11/14/2005 Medium	Arturo Nunez David Villalobos		Santa Teresa HS
7839	Work In Progress NEED FIVE (5) MB- 64 LOCKS FOR DRESSING ROOM AREA DOORS TO OUTSIDE. BUILDING SECURITY.	12/5/2005 Medium	Arturo Nunez Manny Lozoya		Santa Teresa HS
7840	Work In Progress NEED FIVE (5) LOCKS 6" SLIDE LOCKING HASP	12/5/2005 Medium	Arturo Nunez Manny Lozoya		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7841	Work In Progress MOTOR- GOULD CENTURY M/R PA/T 8-159589-01 R P.M. 1725 F / ANE LA 56H VOLTS 208-230/ 460 3PHASE CAT H 535 .	12/5/2005 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS
4465	Work In Progress NEED 1/4 INCH GAS VALVE TO PILOT , ON BOILER #1 ON NEW SYSTEM REPLACED, LEAKING REAL BAD,	8/11/2005 Medium	Arturo Nunez David Villalobos		Santa Teresa HS
4346	Work In Progress NEED TO FUMIGATE VOC. SHOPS TO MANNY CRIKETS, ANTS, ETC,ETC.	8/9/2005 Medium	Arturo Nunez Margret Villalobos		Santa Teresa HS
3571	Work In Progress NEED CONDENSER MTR. FOR SNACK ROOM A.C. UNIT, MTR. IS FROZEN UNIT IS DOWN.	7/15/2005 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS
1998	Work In Progress 03/23/05 3/23 8.0 - CONT. PAINTING DRESSING ROOM	5/17/2005 Medium	Arturo Nunez Arturo Nunez		Santa Teresa HS
695	Work In Progress NEED TILE INSTALLED AT TRAINERS WRAPPING AREA, REQUESTED BY MR. MUNOZ,FRANK.	3/30/2005 Medium	Arturo Nunez Michael Munoz		Santa Teresa HS
1011	Work In Progress NEED CYLINDER AT DRESSING ROOM HALLWAY CHECKED SOME ONE STUCK SOMETHING IN IT, CAN"T OPEN IT ,AFRAID SOMEONE WILL BREAK KEY.	4/11/2005 Medium	Arturo Nunez Manny Lozoya		Santa Teresa HS
5214	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
7804	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
7773	Work In Progress Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Danny Orozco		Santa Teresa HS
7815	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
3176	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3158	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
6107	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
6118	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
6018	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
6036	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
7767	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
7071	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
7696	Work In Progress NEED 5 KEYS MADE FOR THE TRASH COMPACTOR. MARY SITTERS HAS THE ORIGINAL ONE.	12/1/2005 Medium	Manny Lozoya		Santa Teresa HS
7108	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
7119	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
4484	Work In Progress please install venting system and exhaust hood in the metal shop. See Joe Angelo.	8/11/2005 Medium	Jose Ambriz		Santa Teresa HS
7181	Work In Progress NEED TO CREATE A WORK PLAN FOR 2 ADDITIONAL WORKERS AND BREAK DOWN OF MISCELLANEOUS DUTIES BETWEEN 1:30 - 3:30. AND AREA'S ASSIGNED.	11/8/2005 Medium	Luis Murillo		Santa Teresa HS
7330	Work In Progress NEED TO REPLACE MULTIFOLD DISPENSORS TO ROLL TOWEL DISPENSORS AND REG TOILET PAPER DISPENSOR TO JUMBO DISPENSORS ( IN KITCHEN BATHROOM, REPLACE WITH SINGLE JUMBO). LUIS TO CALL US BACK WITH AN ACCURATE COUNT.	11/14/2005 Medium	Aida Salcedo Guillermo Hernandez		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7194	Work In Progress ADULT RESTROOM IN OFFICE AREA NEEDS TO BE PAINTED.	11/8/2005 Medium	Aida Salcedo Arturo Nunez		Santa Teresa HS
7236	Work In Progress NEED HAVE LOCKER ROOM AND BLEACHERS CLEANED IN GYM AREA.	11/9/2005 Medium	Aida Salcedo		Santa Teresa HS
7172	Work In Progress ADULT RESTROOM IN OFFICE AREA. NEED TO CLEAN, DO FLOORS AND REPLACE SOAP DISPENSOR.	11/8/2005 Medium	Aida Salcedo Luis Murillo		Santa Teresa HS
1387	Work In Progress need to repair sheetrock in gym locker room	4/25/2005 Medium	Danny Miranda Danny Miranda	Auditorium	Santa Teresa HS
7465	Work In Progress NEED 2 SHARPS CONTAINERS TO BE PICKED UP. CALLED IN PER ROSA HIDALGO	11/18/2005 Medium	Dana Hamel Guillermo Hernandez		Santa Teresa MS
2728	Work In Progress need to replace doors @ 10x56 window kit	6/13/2005 Medium	Danny Miranda Danny Miranda		Santa Teresa MS
6218	Work In Progress DUE TO WATER OVER FLOW, GYM FLOOR HAS BUBBLED BY FLOODING. NEED VENDOR TO DO A RECOMMENDATION AND QUOTE US.	10/10/2005 Medium	Aida Salcedo Michael Munoz		Santa Teresa MS
2161	Work In Progress duplicate keys for new portables	5/20/2005 Medium	Jose Hinojosa Manny Lozoya	Portables	Santa Teresa MS
2204	Work In Progress 5 copies of cabinet key for North building kitchen cabinets	5/23/2005 Medium	Jose Hinojosa Manny Lozoya	Restroom (Boys)	Santa Teresa MS
2059	Work In Progress HINGES NEED TO BE REPLACED...DOOR NOT CLOSING IN UPPER LEVEL GIRLS BATHROOM	5/18/2005 Medium	Jose Hinojosa Danny Miranda	Restroom (Girls)	Santa Teresa MS
6314	Work In Progress Rms 43 and 38. Please order 2 ea. Bell & Gosset circulating pumps.	10/12/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
6321	Work In Progress Second Request. Mrs. Williams wants to know status on broken urinal at S.bldg lower level boys restroom by ramp.	10/12/2005 Medium	Jaime Mijarez David Villalobos		Santa Teresa MS
7657	Work In Progress Gym lobby entrance doors. Student broke glass on door and needs to be replaced as soon as posible.	11/30/2005 Medium	Jaime Mijarez Ruben Ronquillo		Santa Teresa MS



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7658	Work In Progress Gym basketball court. Cable rapped around spool and won't go up cause it got stuck. I need the lift if it is possible today. there is going to be a basketball game today.	11/30/2005 Medium	Jaime Mijarez Ruben Ronquillo		Santa Teresa MS
7470	Work In Progress Heat Pumps. Can you order ten time delay timers. ICM PART #ICM102 DELAY ON MAKE TIMER.	11/18/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
7471	Work In Progress Cafeteria. Need to replace all the light bulbs. Lighting is very dim and some are burned out.	11/18/2005 Medium	Jaime Mijarez Carlos Castillo		Santa Teresa MS
5149	Work In Progress N.bldg Rm 3. Mrs. williams would like to have a sidewalk that goes from Rm 3 exit door out to the fence. This way when there is a fire drill the special ed students on wheel chairs can be moved away from the building in case of an actual emergency.	9/1/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
5363	Work In Progress N.bldg maintenance and custodial. Would like a duct and register installed on heat pump.	9/9/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
2597	Work In Progress N.bldg. Handicap ramp side walk was repaired without expansion joint. Concrete slab cracked and needs to be repaired again. Heavy traffic area.	6/7/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
2957	Work In Progress N. Bldg upper level. Need Price Quote to correct communication problem on hps 17 thru 22, and 25. They go on failure and restore every few minutes.  Waiting on Vendor (ok) by Purchasing Agent. Will route to Alpine Electric. 10/05	6/23/2005 Medium	Jaime Mijarez Margret Villalobos		Santa Teresa MS
3412	Work In Progress S.bldg upper level. Because of the shortage of classrooms Mrs. williams has to move the teachers lounge to a storage rm. The floor has no tile, can you include this room with the area's that the contractor will be installing floor tile. Attn: Alfredo holguin.	7/8/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
3465	Work In Progress N.bldg home ec rm 10. Ruben Ronquillo I am going to need a Miter saw to cut legs on ten of the tables. please make sure it has a good blade. I am planning this project for next week ( 7/18/05.) The wood is oak.	7/12/2005 Medium	Jaime Mijarez Ruben Ronquillo		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3387	Work In Progress Rm 1. N. bldg lower level Removal of carpet is going to require tile installation. Alfredo H. requested a work order for contractor.	7/7/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
3364	Work In Progress S.bldg custodial storage. please make 2ea. A-7 keys for principal and building mechanic.	7/6/2005 Medium	Jaime Mijarez Manny Lozoya		Santa Teresa MS
1884	Work In Progress S.bldg rm36. Need to have a safety window with safety glass installed. Rm will be used for a special ed student. Requested by Ms Williams.	5/12/2005 Medium	Jaime Mijarez Danny Miranda	Classroom	Santa Teresa MS
542	Work In Progress Choir Rm . Outside metal door is damaged and old used to belong to the demolished mechanical rm. Door is to big and heavy for students to be opening every day. Would like to have it replaced to a new and smaller door. Approved by principal.	3/18/2005 Medium	Jaime Mijarez Danny Miranda		Santa Teresa MS
298	Work In Progress Gym - Replace westside doors.	3/11/2005 Medium	Jaime Mijarez Danny Miranda		Santa Teresa MS
7556	Work In Progress JIMMEY I NEED THREE ROLLER BRUSHES FOR THE ROYAL VACCUMS,AND ALSO THREE VACUUM BELTS.THANK YOU.	11/28/2005 Medium	Ismael Rodriguez Jimmy Carbajal	Custodial	Santa Teresa MS
7695	Work In Progress THANK YOU MR.SORIA FOR HELPING US REMOVE THE SAND FROM OUR CAMPUS ON 11/29/05 AND 11/30/05.GREAT TEAM WORK.	12/1/2005 Medium	Ismael Rodriguez Mike Soria	Parking Lot	Santa Teresa MS
2828	Work In Progress NEED TO REMOVE WEEDS ON OUR CAMPUS AREA AS PER. MISS WILLIAMS . NORTH AND SOUTH BUILDING AND GYM AREA.THANK YOU.	6/16/2005 Medium	Ismael Rodriguez Mike Soria		Santa Teresa MS
3118	Work In Progress I NEED FOR GYM KEY CYLINDERS TOO TO BE CHANGE BEFORE 7/13/05.CONT.MR.RODRIGUEZ.	7/1/2005 Medium	Ismael Rodriguez Manny Lozoya		Santa Teresa MS
1103	Work In Progress ATTN;RUBEN RONQUILLO. I NEED A TRAILER TOO TRANSPORT ART WORK FOR MR. SANCHEZ TO THE G.M.S 4/14/05. THANK YOU.	4/13/2005 Medium	Ismael Rodriguez Ruben Ronquillo		Santa Teresa MS
4641	Work In Progress THERE A BOYS URINAL THAT IS CRACK FROM THE BOTTOM AND EVERY TIME THEY FLUSH IT WATER COMES OUT.SEE MR. RODRIGUEZ.	8/17/2005 Medium	Ismael Rodriguez David Villalobos	Restroom (Boys)	Santa Teresa MS
5308	Work In Progress I NEED A KEY A7 FOR THE PRINCIPAL TO HAVE ACCESS TO MY STORAGE ROOM. THANK YOU.SEE MR. RODRIGUEZ.	9/7/2005 Medium	Ismael Rodriguez Manny Lozoya	Custodial	Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6957	Work In Progress please provide a landing and side walk to portable that was delivered this summer & also provide a sidewalk from bldg to existing side walk	11/2/2005 Medium	Michael Munoz		Santa Teresa MS
6437	Work In Progress please replace h20 fountain and unclog drain.	10/14/2005 Medium	David Villalobos	Office	Santa Teresa MS
2317	Work In Progress need to provide new side walks to new portable.	5/26/2005 Medium	Michael Munoz	Portables	Santa Teresa MS
7120	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
7110	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
7072	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
7768	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
7816	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
7806	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
6237	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Ismael Rodriguez		Santa Teresa MS
3353	Work In Progress Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3330	Work In Progress Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
4013	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3975	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
4023	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
5113	Work In Progress AIR CONDITIONER DOES NOT TURN ON THE LEFT SIDE OF THE ROOM FACING CHALK BOARD ROOM 3 MR. DORANTES	8/31/2005 Medium	Laura Parra Jose Ambriz	Classroom	Santa Teresa MS
6625	Work In Progress Need Heavy Duty Dolly for fire proof file cabinet on Monday October 24, 2005	10/21/2005 Medium	Larry Flores Margret Villalobos		Sunland Park ES
5195	Work In Progress 9/2/05 Lupe Ontiveros Need the heavy tractor to remove the weeds around the school thank you	9/2/2005 Medium	Sebastian Diaz Guadalupe Ontiveros		Sunland Park ES
7029	Work In Progress The sink in the room 41 is clog need to bring the snake also need to replace the fauset thank you	11/4/2005 Medium	Sebastian Diaz David Villalobos		Sunland Park ES
6692	Work In Progress Need 4 metal blinds for portable F 46"X 52" thank you.	10/24/2005 Medium	Sebastian Diaz Ruben Ronquillo		Sunland Park ES
7719	Work In Progress Need to replace broken window in portable A 30"X28"double glass thank you.	12/1/2005 Medium	Sebastian Diaz Ruben Ronquillo		Sunland Park ES
3355	Work In Progress Yearly - Sunland Park ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
6238	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Larry Flores		Sunland Park ES
7807	Work In Progress Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7817	Work In Progress Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3160	Work In Progress Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3179	Work In Progress Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3423	Work In Progress Yearly - Sunland Park ES Emer. Light Test: Annual - Refer to PM schedule details.	7/10/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3268	Work In Progress Monthly - Sunland Park ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3278	Work In Progress Monthly - Sunland Park ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
7769	Work In Progress Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
6975	Work In Progress NEED TO LINE LOCATE AT COURTYARD AREA TOMORROW OR MONDAY. (PLEASE CONTACT RICK MILLER W/ESA TO LET HIM KNOW WHEN YOU WILL BE LOCATING THE LINES @ 915-845- 4777)	11/3/2005 Medium	Alfredo Holguin David Villalobos		Sunland Park ES
2953	Work In Progress Please remove sand along fence line by houses. Also scrape playing area.	6/23/2005 Medium	Robert Sanchez		Sunland Park ES
5687	Work In Progress We have a mice problem throughout the school. Please help!	9/21/2005 Medium	Irene Trujillo Margret Villalobos		Sunland Park ES
5422	Work In Progress NEED TO REMOVED DEAD TREES.	9/12/2005 Medium	Irene Trujillo Guadalupe Ontiveros		Sunland Park ES
4868	Work In Progress BLACK WIDOW SPIDERS, SCORPIONS, ETC. HAVE BEEN FOUND INTHE CLASSROOMS, PLAYGROUND, AND HALLS OF THIS SCHOOL. PLEASE SEND SOMEONE TO SPRAY. FAXED PO 9/1/05	8/24/2005 Medium	Irene Trujillo Margret Villalobos		Sunland Park ES
4171	Work In Progress ROOM #25 IIGHTS IN THE CLASSROOM DO NOT TURN OFF.	8/3/2005 Medium	Irene Trujillo Carlos Castillo		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3875	Work In Progress NEED REPLACEMENT KEYS FOR NURSE'S OFFICE DORR AND FILE CABINET	7/27/2005 Medium	Irene Trujillo Manny Lozoya		Sunland Park ES
2321	Work In Progress THE GRASS SHOULD BE REPLACED ON THE CIRCLE ENTERING THE SCHOOL GROUNDS. WE NEED THE AREA SMOOTHED AND SOD PLACED. REQUESTED AS PER MS. LINDA PEREZ, ASST. PRINCIPAL.	5/26/2005 Medium	Irene Trujillo Lorenzo Hernandez		Sunland Park ES GROUNDS
2409	Work In Progress THIS IS A REQUEST FOR SAND TO BE PLACED UNDER SWING AREA AND MONKEY BAR PIT.	6/1/2005 Medium	Irene Trujillo Lorenzo Hernandez		Sunland Park ES
7837	Work In Progress ROOM 21 BACK DOOR DOESN'T CLOSE CORRECTLY. TEACHER HAS TO JIGGLE THE DOOR KNOB TO MAKE IT LOCK. SHE HAS TO DO THAT FROM THE INSIDE. DURING THE FILE DRILL DOOR KEPT OPENING UP.	12/5/2005 Medium	Irene Trujillo Manny Lozoya		Sunland Park ES
7615	Work In Progress NEED TO REPLACE 4 BROKER WINDOWS: 1. 10-1/4"X15" (GYM) 2. 63-5/8" X 23-1/2" (RM40) 3. 23-1/2"X40-1/2"X22-3/4"X 463/4" (RM24) 4. 23-1/2"X35X41-1/2"X22-3/4"(RM24)	11/29/2005 Medium	Irene Trujillo Ruben Ronquillo		Sunland Park ES
7669	Work In Progress CLASSROOM #10 - MICE DROPPINGS FOUND IN CLASSROOM!!!	11/30/2005 Medium	Irene Trujillo Ruben Ronquillo		Sunland Park ES
7522	Work In Progress A kitchen sink is needed in room 52. The new teacher's lounge.	11/22/2005 Medium	Irene Trujillo David Villalobos		Sunland Park ES
7523	Work In Progress Please remove carpet in room #52 and install floor tile.	11/22/2005 Medium	Irene Trujillo Michael Munoz		Sunland Park ES
7041	Work In Progress A door opening is needed from lounge to existing bathroom in nurse's office. Please send someone to check wiring.	11/4/2005 Medium	Irene Trujillo Carlos Castillo		Sunland Park ES
7042	Work In Progress A door opening is needed to connect lounge to existing bathroom in nurse's office. Please send someone to check the plumbing of sink, etc.	11/4/2005 Medium	Irene Trujillo David Villalobos		Sunland Park ES
7176	Work In Progress CLASSROOM 41 - THE SINK IS PLUGGED UP AND IT STINKS! THE STUDENTS AND TEACHER HAD TO BE MOVED INTO THE LIBRARY. PLEASE SEND SOMEONE RUSH1	11/8/2005 Medium	Irene Trujillo David Villalobos		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7182	Work In Progress CLASSROOM 40 - SINK IS PLUGGED UP AND IT STINKS!! PLEASE SEND SOMEONE RUSH.	11/8/2005 Medium	Irene Trujillo David Villalobos		Sunland Park ES
7183	Work In Progress CLASSROOM 25 - ROACHES HAVE BEEN SEEN IN THE ROOM AND IN THE CUBBIES. PLEASE SEND SOMEONE ASAP.	11/8/2005 Medium	Irene Trujillo Margret Villalobos		Sunland Park ES
6465	Work In Progress THE GROUNDS NEED TO BE SMOOTHED OUT AFTER THE RAIN. THE SAND WAS WASHED AWAY IN SOME AREAS.	10/17/2005 Medium	Irene Trujillo Guadalupe Ontiveros		Sunland Park ES
6727	Work In Progress Roaches in classroom #25.	10/25/2005 Medium	Irene Trujillo Margret Villalobos		Sunland Park ES
6878	Work In Progress ADD NEW ELECTRICAL OUTLET TO TEACHER'S LOUNGE.	10/31/2005 Medium	Irene Trujillo Carlos Castillo		Sunland Park ES
6279	Work In Progress I need to replace camode in room #25. It is broken.	10/11/2005 Medium	Irene Trujillo David Villalobos		Sunland Park ES
7262	Work In Progress Problems with bottom left Blodgett Oven  Serving Line - Left Side- Cold Area not cooling  Marina Ramirez - SNP Manager - 589-3439	11/10/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Sunland Park ES
3629	Work In Progress please cut and weedeat in and around lift station. weeds are growing rapid and are going to end up on the playing fields.	7/18/2005 Medium	Paul Quinones		Sunrise ES
7495	Work In Progress please order fill dirt for new arrivals of new portables. sunrise, che, desert-trail	11/21/2005 Medium	Guadalupe Ontiveros	Portables	Sunrise ES
6887	Work In Progress The Wastwater Flow Meter needs to be checked for proper calibration ASAP	10/31/2005 High	Ricardo Jacquez		Sunrise ES
7122	Work In Progress Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
7113	Work In Progress Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
7056	Work In Progress Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7752	Work In Progress Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
7818	Work In Progress Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
7809	Work In Progress Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
6239	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Ramon Dominguez		Sunrise ES
5331	Work In Progress Treat inside and outside of perimeter for insects. Note: Service setup w/principal on 9/9/05 at 3:00pm) - B. Watson Open Purchase Order!	9/8/2005 Medium	Alfredo Holguin Margret Villalobos		Sunrise ES
4920	Work In Progress Infestation of bug at school site office. (Health Issue)	8/25/2005 Medium	Alfredo Holguin Margret Villalobos		Sunrise ES
5190	Work In Progress As per Nurse Creegan & Mr. Chavez request would like the 2 rooms fumigated where they had the infestation. (Spoke to Daniel he said they could send someone out on Tuesday.	9/2/2005 Medium	Richard Chavez Margret Villalobos		Sunrise ES
3533	Work In Progress Could you turn the air conditioning on we have teachers coming in to get a head start on their rooms. It is very hot and we would greatly appreciate it. Since we are a year round school the teachers need to report on Monday. Thank-you	7/14/2005 Medium	Joanne Munoz Jaime Gomez	Classroom	Sunrise ES
6449	Work In Progress 10-14-05 2.0,REMOVE SAND GRAVEL FROM BACK SIDEWALK ENTRANCE 4.5,ASSIST ENRIQUE W/ELECTRICAL PROBLEM RM.201 1.5,VISUAL INSPECT PLAYGROUNDS 10/14 - 8	10/17/2005 Medium	Paul Quinones Paul Quinones		Sunrise ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6570	Work In Progress WATER LEAKING FROM PUMP SEAL,NEED TO REPLACE IN RM. 210. THANKS	10/19/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
6781	Work In Progress REQUESTING SEAL KITS ,AND GASKETS.FOR CIRCULATING PUMPS GEO THERMAL UNITS. UNIT LEAKING FROM SEAL RM.210	10/26/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
6782	Work In Progress STERLING HEATING UNIT IN KITCHEN AREA.WILL NOT TURN ON ,MIXED AIR CONTROL NOT WORKING PROPERLY	10/26/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
7334	Work In Progress REQUESTING SEAL KITS,AND PUMP GASKETS,FOR CIRCULATING PUMPS,FOR GEO THEMAL UNITS.	11/14/2005 Medium	Paul Quinones Jose Ambriz		Sunrise ES
7460	Work In Progress 11-09-05 4.0,WASH DOWN ROOFING AREA,MASTERCOOLS,EXHAUST FANS.PIGEON DROPPINGS 1.5,PICK UP OUTSIDE TRASH 2.5,CONTINUE TO TIE DOWN WIND SCREEN 11/9 - 8	11/18/2005 11/9/2005 Medium	Paul Quinones Margret Villalobos		Sunrise ES
7468	Work In Progress PEST CONROL OF PIGEONS.PIGEONS ARE NESTING ON THE ROOF,AND AROUND THE MECH. EQUIPMENT,AND DROPPINGS AS WELL.THANKS Need price quote!	11/18/2005 Medium	Paul Quinones Margret Villalobos		Sunrise ES
7576	Work In Progress REQUESTING FLUORESCENT LIGHT LAMPS T8/SP30	11/28/2005 Medium	Paul Quinones Enrique Sotelo		Sunrise ES
7582	Work In Progress PROBLEM IN DIAG. RM. NEED TO REPLACE HEATER ELEMENTS REQUESTING 3.0 HEATER ELEMENTS FOR 3 PHASE SHUT OFF SWITCH.	11/28/2005 Medium	Paul Quinones Enrique Sotelo		Sunrise ES
3876	Work In Progress RM.307,BAD CIRCULATING PUMP NEED TO REPLACE	7/27/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
2278	Work In Progress UNIT IN RM.308 NO CIRCULATING WATER.A SLEEVE IS NEEDED TRIPPING ON HIGH HEAD PRESSURE AS WELL	5/25/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
2407	Work In Progress 5-27-05 .5,CHECK IN WITH OFFICE 3.0,PICK UP MATERIALS,AND TURN IN TIME SHEET 2.5,REROUT 6 INCH FLEX MORE AIR FLOW NEEDED IN CAFET- ERIA MANAGERS OFFICE. 1.0,PICK UP TRASH,AND SWEEP GRAVEL FROM BASKETBALL COURTS 1.0,ASSIST RICK J. CLEAN LIFT STATION 5/27 - 8	6/1/2005 Medium	Paul Quinones Paul Quinones		Sunrise ES
2987	Work In Progress I NEED SLEEVES,AND ALSO GASKETS THAT CONNECT TO THE MOTOR,AND PUMP HOUSING. THANKS	6/24/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
3469	Work In Progress FENCING AREA IN BACK OF SCHOOL NEAR LIFT STATION NEEDS TO BE REPAIRED,AND ROLL GATE.PROBABLE HIGH WINDS ON 7-11-05 CAUSED THE DAMAGE.NO SIGNS OF VANDILISM ON SCHOOL PROPERTY	7/12/2005 Medium	Paul Quinones Michael Munoz		Sunrise ES
3477	Work In Progress I NEED SAND FOR THE PLAY GROUNDS,THANKS.	7/12/2005 Medium	Paul Quinones Lorenzo Hernandez		Sunrise ES
2113	Work In Progress I NEED A COUPLING THAT TURNS THE CIRCULATING PUMP WITH MOTOR SHAFT,TO CIRCULATE WATER TO UNIT IN OUT DOOR MECH. RM.	5/19/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
2208	Work In Progress MASTER COOL UNIT WILL NOT TURN ON AND THE EXHAUST FAN AS WELL,	5/23/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
2209	Work In Progress STERLING UNIT WET SECTION MIXED AIR CONTROL NOT WORKING PROPERLY DAMPER STAYS SHUT AT TIMES,AND HAS TO BE MOVED MANUALLY FOR COOLING,AND HEATING AS WELL.	5/23/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
946	Work In Progress I NEED SAND FOR BOTH PLAY GROUNDS	4/7/2005 Medium	Paul Quinones Lorenzo Hernandez		Sunrise ES
7811	Work In Progress Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Danny Miranda		Vado ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
7819	Work In Progress Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Danny Miranda		Vado ES
7715	Work In Progress Need to change cores back to the original cores a/s/a/p (Also you need to provide Mr. Giovas w/gate and bldg keys (kitchen) he will be working there during the holidays).	12/1/2005 Medium	Alfredo Holguin Manny Lozoya		Vado ES
7770	Work In Progress Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Danny Miranda		Vado ES
7713	Work In Progress please apply water to all roof top vents and also extend vents. please see mike. thanks	12/1/2005 Medium	Danny Miranda		Vado ES
4628	Work In Progress Need to meet contractor on Monday - to rekey school site.	8/17/2005 Medium	David Boyd Manny Lozoya		Vado ES