

696 - Work Orders In Progress (Fiscal Year 7/1/05 - 12/31/05)

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|-------------------------------------|-------------|-------------------------|
| 3982 | Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Romauldo Apodaca | | Alma Del Valle Daycare |
| 3981 | Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Romauldo Apodaca | | Alma Del Valle Daycare |
| 3960 | Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Romauldo Apodaca | | Alma Del Valle Daycare |
| 3312 | Work In Progress Yearly - Alma Del Valle Exit Sign Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Romauldo Apodaca | | Alma Del Valle Daycare |
| 3308 | Work In Progress Yearly - Alma Del Valle Emer. Light Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Romauldo Apodaca | | Alma Del Valle Daycare |
| 3661 | Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005. | 7/19/2005 4/26/2005 Medium | Aida Salcedo Carlos Lujan | | Anthony ES |
| 5173 | Work In Progress School campus needs to be fumigated due to poisonous critters found in classrooms. On hold for additional budget - as per A. Holguin 9/8/05 -mkv emailed - C. Lujan and L. Villalobos 9/20/05 9/20/05. rec call from Carla as per Ms. Marquez. Very concerned, spiders and centipedes in classrooms on a daily basis. | 9/2/2005 Medium | Carlos Lujan Margret Villalobos | | Anthony ES |
| 8201 | Work In Progress need to open classroom wall @ music rm. | 12/20/2005 Medium | Danny Miranda Danny Miranda | Classroom | Anthony ES |
| 8191 | Work In Progress please install an additional gate for in and out traffic. | 12/19/2005 Medium | Michael Munoz | Parking Lot | Anthony ES |
| 6953 | Work In Progress please cut a total of 3 gates that are to long. 1/2 swing, 1/2 roll. 1) on 4th st and 2 on church. | 11/2/2005 Medium | Michael Munoz | | Anthony ES |
| 4487 | Work In Progress please grade and add crusher fine for neww parking for parents and add parking curbs. | 8/11/2005 Medium | Guadalupe Ontiveros | | Anthony ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|--|--|---|------------------|---------------------------------|
| 4097 | Work In Progress please scrape and add crusher fine along with parking curbs.see mike | 8/2/2005 Medium | Guadalupe Ontiveros | | Anthony ES |
| 6005 | Work In Progress Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details. | 10/2/2005 Medium | Alfredo Holguin Hector Villalobos | | Anthony ES |
| 6586 | Work In Progress heater is not working need to replace parts | 10/20/2005 Medium | Hector Villalobos Jose Ambriz | Cafeteria | Anthony ES |
| 7340 | Work In Progress Hallway need to hook up wires for backup lights | 11/14/2005 Medium | Hector Villalobos Enrique Sotelo | Hallway/Corridor | Anthony ES |
| 7339 | Work In Progress Custodial storage faucet is leaking need to replace faucet | 11/14/2005 Medium | Hector Villalobos Joe Ontiveros | Custodial | Anthony ES |
| 7610 | Work In Progress Annex Bldg Room 201 - Need to spray for roaches. | 11/29/2005 Medium | Hector Villalobos Margret Villalobos | | Anthony ES |
| 7566 | Work In Progress Bathroom dry walls need to be replace or panel | 11/28/2005 Medium | Hector Villalobos Danny Miranda | Mechanical Room | Anthony ES |
| 8109 | Work In Progress Waste disposer valve will not turn off | 12/14/2005 Medium | Hector Villalobos Danny Orozco | Cafeteria | Anthony ES |
| 7938 | Work In Progress Mrs marquez office high pressure toilet needs bottom seal | 12/8/2005 Medium | Hector Villalobos Joe Ontiveros | Office | Anthony ES |
| 7937 | Work In Progress Boys bathroom replace emergency lighting | 12/8/2005 Medium | Hector Villalobos Enrique Sotelo | Restroom (Boys) | Anthony ES |
| 3899 | Work In Progress Room 201 - Half of the carpet is bad replace with tile. 11/29/05 - Teacher requesting status on this work order on 11/10/05 a student fell and hurt her leg. -mkv | 7/28/2005 Medium | Hector Villalobos Michael Munoz | Classroom | Anthony ES |
| 4581 | Work In Progress old main blg a/c motor burn out a 3 hp volts 230 | 8/15/2005 Medium | Hector Villalobos Jaime Gomez | Classroom | Anthony ES |
| 4861 | Work In Progress Nurse office refrigerator is not working water is leaking from seal | 8/24/2005 Medium | Hector Villalobos Jaime Gomez | | Anthony ES |
| 4255 | Work In Progress room 109 needs carpet repair | 8/8/2005 Medium | Hector Villalobos Michael Munoz | Classroom | Anthony ES |
| 4478 | Work In Progress Chapter bg p.e room replace 3/4 motor with a 1hp motor | 8/11/2005 Medium | Hector Villalobos Jaime Gomez | Classroom | Anthony ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|------------------------------------|--------------|-------------------------|
| 4742 | Work In Progress need a 3/4 hp motor cafeteira motor burn out old cafeteria | 8/22/2005 Medium | Hector Villalobos Jaime Gomez | Cafeteria | Anthony ES |
| 4743 | Work In Progress mild cafeteria burn motor 3/4 hp with a belt 4-L 660 or 670 | 8/22/2005 Medium | Hector Villalobos Jaime Gomez | Cafeteria | Anthony ES |
| 5944 | Work In Progress Old main blg boiler room needs a thermocuple size 56 inch | 9/29/2005 Medium | Hector Villalobos Jaime Gomez | | Anthony ES |
| 5992 | Work In Progress upper primary boiler is leaking replace | 9/30/2005 Medium | Hector Villalobos Jaime Gomez | | Anthony ES |
| 7188 | Work In Progress ANTHONY 4-6 CAMPUS - ICE MACHINE NOT WORKING. NOTICED THIS MORNING THERE WAS NO ICE. BECKY S. AE SNP MGR 882-3507 | 11/8/2005 Medium | Jacqueline Aguilar Danny Orozco | Computer Lab | Anthony ES |
| 5090 | Work In Progress new oven is completely down. Becky S. SNP Mgr 882-3507 | 8/30/2005 Medium | Jacqueline Aguilar Danny Orozco | Cafeteria | Anthony ES |
| 4059 | Work In Progress DAYCARE - NEED TO ISSUE KEYS TO CORINA VALDESPINO for (Krishna's Office). WILL BE HERE AT 8:00 AM TOMORROW. | 8/1/2005 Medium | Margret Villalobos Manny Lozoya | | Anthony ES |
| 5338 | Work In Progress WALK - IN FREEZER IS LEAKING ALOT OF WATER BETWEEN THE FREEZER AND REFRIG. ELSA - 882-2417 | 9/8/2005 Medium | Jacqueline Aguilar Danny Orozco | Cafeteria | Berino ES |
| 5585 | Work In Progress need nemaster b key and 55key for new custodian thanks a.s. p | 9/19/2005 Medium | Jimmy Cortez Manny Lozoya | | Berino ES |
| 5898 | Work In Progress Need 2 new keys for office gate and recut master key for Mr Silva THANKS OFFICE KEY IS ON YOUR KEY CHAIN ALREADY | 9/28/2005 Medium | Jimmy Cortez Manny Lozoya | | Berino ES |
| 3434 | Work In Progress WASHING MACHINE DOES NOT WORK ANY MORE. (IT GAVE UP) ELSA CHAIRZ - SNP MGR 882-2417 | 7/11/2005 Medium | Jacqueline Aguilar Danny Orozco | Cafeteria | Berino ES |
| 4082 | Work In Progress Monitoring Wells - I need a set of keys to the monitoring well caps | 8/2/2005 Medium | Alfredo Holguin Manny Lozoya | | Berino ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|------------------------------------|-----------------|-------------------------|
| 4055 | Work In Progress please cut weeds and pick-up debris on east side of rockwall. (i.e weeds bottles cinder blocks.) | 8/1/2005 Medium | Ramiro Holguin | | Berino ES |
| 4208 | Work In Progress MOBILE HOME OCCUPANT WILL BE RECEIVING NEW MOBILE HOME ON APPROXIMATELY 8-29-05. PLEASE CONNECT ELECTRICAL. 28X54 | 8/4/2005 Medium | Enrique Sotelo | | Berino ES |
| 6447 | Work In Progress DISHWASHER CHEMICAL DISPENSERS NOT WORKING RIGHT HAS TO BE CHECK OUT | 10/17/2005 Medium | Ramiro Holguin Danny Orozco | | Berino ES |
| 7907 | Work In Progress 12/06/05 TO MIKE PORTABLE 154 FLOOR TILES ARE COMING OFF IF POSSIBLE THIS CHRISTMAS BREAK YOU CAN SOME CARPET INSTALL ED | 12/7/2005 Medium | Ramiro Holguin Michael Munoz | | Berino ES |
| 7820 | Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Juan Vargas | | Chaparral ES |
| 4518 | Work In Progress please replace urinal and commode in mens restroom. | 8/12/2005 Medium | Joe Ontiveros | Mechanical Room | Chaparral ES |
| 6123 | Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details. | 10/2/2005 Medium | Alfredo Holguin Juan Vargas | | Chaparral ES |
| 7779 | Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Juan Vargas | | Chaparral ES |
| 7756 | Work In Progress Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Juan Vargas | | Chaparral ES |
| 5498 | Work In Progress sweeper/blower/not/working/choke/broken | 9/14/2005 Medium | Daniel Ramirez Jimmy Carbajal | | Chaparral ES |
| 4797 | Work In Progress repair storage, boy,s , girl,s r.r. @ chaparral elem | 8/22/2005 Medium | Danny Miranda Danny Miranda | | Chaparral ES |
| 7900 | Work In Progress THE TWO OVENS MOVED TO HER SCHOOL DO NOT WORK. ALICE E. SNP MGR 824-0048 | 12/7/2005 Medium | Jacqueline Aguilar Danny Orozco | Cafeteria | Chaparral ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|------------------------------------|--------------|-------------------------|
| 7901 | Work In Progress DISHWASHER IS MAKING ALOT OF NOISE. ALICE E. SNP MGR 824-0048 | 12/7/2005 Medium | Jacqueline Aguilar Danny Orozco | Cafeteria | Chaparral ES |
| 7647 | Work In Progress ONE OVEN IS TO HOT AND THE OTHER IS OVEN IS LOW HEAT. IF YOU HAVE ANY QUESTIONS CALL MARK KING - 346-9237. REQUESTED BY MR. G. | 11/30/2005 Medium | Jacqueline Aguilar Danny Orozco | Computer Lab | Chaparral ES |
| 6343 | Work In Progress las vanquetas need grabo a round | 10/12/2005 Medium | Juan Vargas Guadalupe Ontiveros | | Chaparral ES |
| 5053 | Work In Progress need to be replaced front area gate doors and chain link fence as mr. cardona | 8/30/2005 Medium | Juan Vargas Michael Munoz | | Chaparral ES |
| 3868 | Work In Progress ROOMS 83-82-81-80-72-96-70 NEED WINDOWS REPAIRED OR REPLACE 2-REPORT | 7/27/2005 Medium | Juan Vargas Ruben Ronquillo | | Chaparral ES |
| 3846 | Work In Progress 07/26/05 j. gomes rooms 2 -20-21- 51-47-107- 44- 55-46- need replace A/C 6500 | 7/26/2005 Medium | Juan Vargas Jaime Gomez | | Chaparral ES |
| 3801 | Work In Progress 5/25/05/ mike neseito que pongan sistema de riego para los arboles | 7/25/2005 Medium | Juan Vargas Guadalupe Ontiveros | | Chaparral ES |
| 3800 | Work In Progress 07/25/05 jaime gomes main office need new A/C two 4500 and one 6500 | 7/25/2005 Medium | Juan Vargas Jaime Gomez | | Chaparral ES |
| 4030 | Work In Progress Room 47 need to instaled a/c ventilation | 8/1/2005 Medium | Juan Vargas Jaime Gomez | | Chaparral ES |
| 4213 | Work In Progress Rooms 101-102-60-62-61-54-70-96-72-73-97 80- 82-83 need carpet repace | 8/4/2005 Medium | Juan Vargas Michael Munoz | | Chaparral ES |
| 4602 | Work In Progress ruben ronquillo need 10 pvc 45 elbows 6 inches 10 square grate basin 6 inches and 200 ft. 6 inches pvc pipe | 8/16/2005 Medium | Juan Vargas Joe Ontiveros | | Chaparral ES |
| 7359 | Work In Progress 2 request e. wing rooms need to repair windows | 11/15/2005 Medium | Juan Vargas Ruben Ronquillo | | Chaparral ES |
| 7360 | Work In Progress rooms 79 71 70 83 need 12 blinds size 33 width 58 length | 11/15/2005 Medium | Juan Vargas Ruben Ronquillo | | Chaparral ES |
| 7376 | Work In Progress portables and e. wing need doors replace | 11/15/2005 Medium | Juan Vargas Danny Miranda | | Chaparral ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|---|--|------------------------------------|------------------|---------------------------------|
| 7378 | Work In Progress music room and gym. need doors replace | 11/15/2005 Medium | Juan Vargas Danny Miranda | | Chaparral ES |
| 6502 | Work In Progress room 72 heating not work need help to fix | 10/18/2005 Medium | Juan Vargas Jaime Gomez | | Chaparral ES |
| 6415 | Work In Progress cafeteria exit sign need change | 10/14/2005 Medium | Juan Vargas Enrique Sotelo | | Chaparral ES |
| 7646 | Work In Progress evenstar playgroun need water fouting fix | 11/30/2005 Medium | Juan Vargas Joe Ontiveros | | Chaparral ES |
| 7865 | Work In Progress e. wing need fix main line water leak size pipe is 1-1/4 | 12/6/2005 Medium | Juan Vargas Joe Ontiveros | | Chaparral ES |
| 7863 | Work In Progress cafeteria need replace floor tile | 12/6/2005 Medium | Juan Vargas Michael Munoz | | Chaparral ES |
| 7953 | Work In Progress nesesito 6 donpes de arena para los colunpios y acuitment playground | 12/8/2005 Medium | Juan Vargas Guadalupe Ontiveros | | Chaparral ES |
| 7946 | Work In Progress cafeteria need replace two entry doors | 12/8/2005 Medium | Juan Vargas Danny Miranda | Cafeteria | Chaparral ES |
| 7947 | Work In Progress kitchen need replace entry door | 12/8/2005 Medium | Juan Vargas Danny Miranda | Cafeteria | Chaparral ES |
| 7949 | Work In Progress room 120 need fix bathroom door frame | 12/8/2005 Medium | Juan Vargas Danny Miranda | | Chaparral ES |
| 8009 | Work In Progress north playgroun need fix water founting | 12/12/2005 Medium | Juan Vargas Joe Ontiveros | | Chaparral ES |
| 8046 | Work In Progress Furnace for hallway on main building is not working properly, please check it out! | 12/12/2005 Medium | Juan Vargas Lorenzo Solis | | Chaparral ES |
| 3284 | Work In Progress 07/05/05 mike munoz Mr. cardona quiere bertical blind en su oficina size 82 width and 80 length | 7/5/2005 Medium | Juan Vargas Ruben Ronquillo | | Chaparral ES |
| 6913 | Work In Progress needs electrical wiring for 4 center poles. Surge protectors are being overloaded, causing system to shut down. Printer in computer lab needs to be installed.A.S.A.P Rm- computer lab, Ms. Elkurdi | 11/1/2005 Medium | Jennifer Corral Enrique Sotelo | Computer Lab | Chaparral ES |
| 7710 | Work In Progress Window in rm-72 is falling out. When opened it falls out. Doesn't stay up alone needs a stick to hold it up. See Ms. Barrett. | 12/1/2005 Medium | Jennifer Corral Ruben Ronquillo | | Chaparral ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|------------------------------------|-----------|-------------------------|
| 6529 | Work In Progress Had done a work order before for Ms. Barrett about fixing her windows needs a screen.She says they still haven't done the work order. Thanks | 10/18/2005 Medium | Jennifer Corral Ruben Ronquillo | Classroom | Chaparral ES |
| 4110 | Work In Progress Rm-72 Ms. Barret needs screens on her windows. Says they were suppose to be put in last year. | 8/3/2005 Medium | Jennifer Corral Ruben Ronquillo | Classroom | Chaparral ES |
| 3871 | Work In Progress need an extra key for Even start classroom, Jeannette rm-118 | 7/27/2005 Medium | Jennifer Corral Manny Lozoya | Classroom | Chaparral ES |
| 3945 | Work In Progress Air Conditioner smells like burn and is not cold in rm-128 for Ms. Word | 7/29/2005 Medium | Jennifer Corral Jaime Gomez | Classroom | Chaparral ES |
| 3946 | Work In Progress Air Conditioner not working in rm-20 for Ms. Gary | 7/29/2005 Medium | Jennifer Corral Jaime Gomez | Classroom | Chaparral ES |
| 3785 | Work In Progress NEED A KEY FOR ROOM 114,LEDESMA REPRINT FOR MANNY - REGARDING E-MAIL 7/27/05 - MKV | 7/22/2005 Medium | Jennifer Corral Manny Lozoya | Classroom | Chaparral ES |
| 3299 | Work In Progress I need some keys for two of the new administators who will be coming to this school. They have requested main keys to the gate that opens up the fence outside the school and also a set of main keys for the building. If you can please do as soon as possible. Keys for Chaparral Elementary. | 7/5/2005 Medium | Jennifer Corral Manny Lozoya | Office | Chaparral ES |
| 8071 | Work In Progress Need to cut, pickup weeds and cleanup debris around WWTP as per Mike Munoz. | 12/13/2005 Medium | Michael Munoz Ricardo Jacquez | | Chaparral ES |
| 8069 | Work In Progress Need to cleanout Mech, Bolier and Electrical Rooms as per Mike Munoz. | 12/13/2005 Medium | Michael Munoz Joe Ramirez | | Chaparral MS |
| 4072 | Work In Progress Room 208 - Mold on ceiling tiles. (Nancy, Nurse @ site called in) - mkv Margaret, Joe replied and said there where a couple of ceiling tiles with small mold droppings on them. He replaced them. However still go ahead and generate a w.o. for our records and have him fill it out. Mike | 8/2/2005 Medium | Mary Garcia Joe Ramirez | Classroom | Chaparral MS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|------------------------------------|-----------|-------------------------|
| 4042 | Work In Progress Need sensor replaced in girls locker room lavatory. | 8/1/2005 Medium | Joe Ramirez Joe Ontiveros | | Chaparral MS |
| 3720 | Work In Progress 7/12/05. need a/c replaced on portable 1 rm. 2 please. | 7/20/2005 Medium | Joe Ramirez Jaime Gomez | | Chaparral MS |
| 6246 | Work In Progress Need about 2 yards base coarse for use around pond area. | 10/10/2005 Medium | Joe Ramirez Guadalupe Ontiveros | | Chaparral MS |
| 7324 | Work In Progress 11/14/05. door closer on walk in freezer door needs to be replaced. thanks. | 11/14/2005 Medium | Joe Ramirez Danny Orozco | | Chaparral MS |
| 6558 | Work In Progress 10/19/05. we need propane tank filled for portable housing rms. 1&2. ATTEN. RUBEN. | 10/19/2005 10/21/2005 Medium | Joe Ramirez Ruben Ronquillo | | Chaparral MS |
| 7833 | Work In Progress WARMER IS NOT WARMING UP. TAKING TO LONG TO HEAT UP. SANDRA DIAZ SNP MGR 824-4376 | 12/5/2005 Medium | Jacqueline Aguilar Danny Orozco | Cafeteria | Chaparral MS |
| 3607 | Work In Progress need to paint new door @ football storage rm. | 7/18/2005 Medium | Danny Miranda Joe Ramirez | | Chaparral MS |
| 3608 | Work In Progress need to paint new door @ rm. 86 | 7/18/2005 Medium | Danny Miranda Joe Ramirez | | Chaparral MS |
| 3314 | Work In Progress Yearly - Chaparral MS Emer. Light Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 7686 | Work In Progress 1. Garbage Disposal is still out of order 2. Both sinks are dripping 3. Salad Sink is dripping from the faucet 4. Dishwasher sink drips from the pipe on the bottom Sandra Diaz - SNP Manager - 824-4376 | 11/30/2005 Medium | Alma Terrell Danny Orozco | Cafeteria | Chaparral MS |
| 3307 | Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 3964 | Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|--|--|----------------------------------|------------------|---------------------------------|
| 3977 | Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 3243 | Work In Progress Monthly - Chaparral MS Emergency Lighting Insp. - Refer to PM schedule details. | 7/3/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 3241 | Work In Progress Monthly - Chaparral MS Exit Sign Insp. - Refer to PM schedule details. | 7/3/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 3148 | Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details. | 7/3/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 3336 | Work In Progress Yearly - Chaparral MS Exit Sign Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 7757 | Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 7783 | Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 7781 | Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 6086 | Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details. | 10/2/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 6084 | Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details. | 10/2/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 7061 | Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 5229 | Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details. | 9/4/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 5227 | Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details. | 9/4/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 7087 | Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|--|--|----------------------------------|------------------|---------------------------------|
| 7085 | Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 7074 | Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 6048 | Work In Progress Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details. | 10/2/2005 Medium | Alfredo Holguin Danny Orozco | | Chaparral MS |
| 5204 | Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details. | 9/4/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 6008 | Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details. | 10/2/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 3990 | Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 3988 | Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Joe Ramirez | | Chaparral MS |
| 4485 | Work In Progress please take a load of crusher fine so sewer line. Ak David (plumbing) for the specifics. | 8/11/2005 Medium | Guadalupe Ontiveros | Portables | Chaparral MS |
| 5463 | Work In Progress need to pour landing and sidewalks to portables by football feild. | 9/13/2005 Medium | Michael Munoz | Portables | Chaparral MS |
| 3648 | Work In Progress please get with speedy and have him train you on the sprikler system on football field and thru out campus. Identify all valves and repair what is needed. also ask him for a key for sprinkler box and have him teach you the programs. | 7/19/2005 Medium | Joe Ramirez | Football Field | Chaparral MS |
| 3649 | Work In Progress need to cut weeds and grass behind library and courtyard and surrounding areas tru -out campus including pond. Also need to irrigate these areas also. | 7/19/2005 High | Joe Ramirez | | Chaparral MS |
| 3650 | Work In Progress please paint railing on new portables that where installed and modified and all railings that are in need. | 7/19/2005 Medium | Joe Ramirez | | Chaparral MS |
| 3656 | Work In Progress please put up fence where portables where installed even if its on a temp bases. | 7/19/2005 Medium | Joe Ramirez | Football Field | Chaparral MS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|-----------------------------------|-----------|----------------------------|
| 3439 | Work In Progress NEED KEYS FOR TWO NEW PORTABLES. | 7/11/2005 Medium | Vickie Reed Manny Lozoya | Portables | Chaparral MS |
| 3855 | Work In Progress NEED TO REKEY CABINET. | 7/26/2005 Medium | Vickie Reed Manny Lozoya | Classroom | Chaparral MS 204 |
| 4509 | Work In Progress need to rekey file cabinets. 2 | 8/12/2005 Medium | Vickie Reed Manny Lozoya | Classroom | Chaparral MS 104 |
| 4639 | Work In Progress NEED 3 REPLACEMENT KEYS FOR 3 A-34'S THAT DO NOT WORK. | 8/17/2005 Medium | Vickie Reed Manny Lozoya | Office | Chaparral MS VICKIE-KEY |
| 3499 | Work In Progress We need locks to be installed on the center pole to the double doors in the front entrance,north east doors and south east doors. This is the oldest part of the school. the newer part of the school already have locks on the center poles. This old doors are the once that we use more often. This locks will make it so much faster and easier. THANK YOU ROBERT | 7/13/2005 Medium | Robert Gonzalez Manny Lozoya | | Chaparral MS |
| 5062 | Work In Progress I NEED 1 MALE WATER HOSE CONNECTOR, 1 HX- 1 VINYL ANCHOR KIT AND 1 WEJIT DRY WALL AUGER ANCHOR KIT SIZE 8. THANK YOU | 8/30/2005 Medium | Robert Gonzalez Jimmy Carbajal | | Chaparral MS |
| 7525 | Work In Progress MRS. ADAMS ROOM 203 HAS CABINETS AND DRAWERS THAT ARE LOCKED AND SHE DOESN'T HAVE A KEY TO UNLOCK THEM. SHE WOULD LIKE TO HAVE THEM UNLOCKED AS SOON AS POSSIBLE. THANK YOU | 11/22/2005 Medium | Robert Gonzalez Manny Lozoya | | Chaparral MS |
| 8070 | Work In Progress Need to cut, pickup weeds and cleanup debris around WWTP as per Mike Munoz. | 12/13/2005 Medium | Michael Munoz Ricardo Jacquez | | Chaparral MS |
| 4992 | Work In Progress please remove marquee sign from desertveiw and install at desert pride. please be careful when removing.see mike | 8/29/2005 Medium | Guadalupe Ontiveros | | Desert Pride |
| 7784 | Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin David Acosta | | Desert Pride |
| 7771 | Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin David Acosta | | Desert Pride |
| 7788 | Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin David Acosta | | Desert Pride |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|-------------------------------------|-------------|-----------------------------|
| 6368 | Work In Progress principal requests - to add crush fine to parking lot and bus turn around to help keep the dust down | 10/13/2005 Medium | David Acosta Guadalupe Ontiveros | Parking Lot | Desert Pride |
| 5959 | Work In Progress need to ckeck a/c blower . It stops blowing | 9/29/2005 Medium | David Acosta Jose Ambriz | Classroom | Desert Pride #1 |
| 5336 | Work In Progress Principals requests: for dead bolt locks for last portable (where break-in occur) | 9/8/2005 Medium | David Acosta Manny Lozoya | Classroom | Desert Pride #6,7. |
| 5294 | Work In Progress NEED OUTSIDE NIGHT LIGHT BETEEW LAST PORTABLE AND END OF CAMPUS. ALSO NEED LIGHT BULK FOR NIGHT LIGHT BETEEW 2ND BUILDING AND PUMP HOUSE | 9/6/2005 Medium | David Acosta Carlos Castillo | Classroom | Desert Pride |
| 4642 | Work In Progress need one key for storage closet for teacher in room #3 | 8/17/2005 Medium | David Acosta Manny Lozoya | Classroom | Desert Pride 3 |
| 4304 | Work In Progress need locks for two doors to the hall way, that needs to be use as storage for science rooms. | 8/8/2005 Medium | David Acosta Manny Lozoya | Classroom | Desert Pride #3,4 |
| 3942 | Work In Progress need emergency light and exit signs check out. | 7/29/2005 Medium | David Acosta Carlos Castillo | Office | Desert Pride |
| 3791 | Work In Progress need plastic name plates(12)MS. S. VERLANDER, MS. I. RAMIREZ, MS. BACH-HAGUE, MS. B. COSTULIS, MS. C. MCDONALD, MR. C. VELA, MR. P. WYMAN, MS. G. PARKER, MS. S. GARCIA, MR. D. NEAL , MS. J. ZAPATA, MS. D. DEAN | 7/25/2005 Medium | David Acosta Manny Lozoya | Classroom | Desert Pride |
| 7731 | Work In Progress need gate repairs-vehicles hit and run on gate .(front entrance) | 12/2/2005 Medium | David Acosta Ruben Ronquillo | Parking Lot | Desert Pride front entrance |
| 7666 | Work In Progress having trouble unlocking the westside door (cylinder). | 11/30/2005 Medium | David Acosta Manny Lozoya | Classroom | Desert Pride #8 |
| 7665 | Work In Progress need to service vacuum cleaner- very noisy and loose core from handle. | 11/30/2005 Medium | David Acosta Jimmy Carbajal | Office | Desert Pride |
| 7955 | Work In Progress Vandalism - Damage to front entrance roll gate hit by vehicle. (Case# 2005-1037) Julio Ledesma #831 | 12/2/2005 Medium | David Acosta Michael Munoz | | Desert Pride |
| 4460 | Work In Progress I need an office key for Ms. Maes, Clerk at Desert Pride Academy | 8/10/2005 Medium | Mary Telles Manny Lozoya | Office | Desert Pride |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|--------------------------------|-----------|---------------------------|
| 5426 | Work In Progress need a replacement heating coil (Boiler System) in the Cafeteria/Gym. (Old one Leaks) | 9/12/2005 Medium | Johnny Acuna Jaime Gomez | | Desert Trail Intermediate |
| 6170 | Work In Progress please repair or replace door knob in the kitchen going outdoors in the back:(door jams and is hard to open) Thank You !!!!!!!!!!!!!!!! | 10/4/2005 Medium | Johnny Acuna Manny Lozoya | | Desert Trail Intermediate |
| 3739 | Work In Progress DIAG/PSYCH ROOM NEED (2) CLASSROOM KEYS MADE. CORE IS: J-53 | 7/21/2005 Medium | Johnny Acuna Manny Lozoya | | Desert Trail Intermediate |
| 4116 | Work In Progress need a replacement single knob water faucet for room #112. | 8/3/2005 Medium | Johnny Acuna Joe Ontiveros | | Desert Trail Intermediate |
| 4558 | Work In Progress Mrs. Bonham (Asst. Principal) requesting concrete slab to be installed between portable #412 and #413 art studio. | 8/15/2005 Medium | Johnny Acuna Michael Munoz | | Desert Trail Intermediate |
| 6884 | Work In Progress Marquee Light not working properly. (vice- principal) | 10/31/2005 Medium | Johnny Acuna Enrique Sotelo | | Desert Trail Intermediate |
| 6883 | Work In Progress need a lock (J-11) for new gate that was installed located in the fence between CH. ELEM and CH. DESERT TRAIL closest to Lisa ST. (To be locked during LOCK DOWN events). Thank You !!!!!!! | 10/31/2005 Medium | Johnny Acuna Manny Lozoya | | Desert Trail Intermediate |
| 6846 | Work In Progress fire-proof filing cabinet inside vault: please fix or replace lock. | 10/28/2005 Medium | Johnny Acuna Manny Lozoya | | Desert Trail Intermediate |
| 6910 | Work In Progress need a replacement heating coil (boiler heating system) for cafeteria heater. Old heater leaks: Model # LHD103CH Serial #35C01059-06 | 11/1/2005 Medium | Johnny Acuna Jose Ambriz | | Desert Trail Intermediate |
| 7205 | Work In Progress need to replace hydraulic door closure in the back kitchen door. (old door closure leaked oil out and doesn't work) | 11/8/2005 Medium | Johnny Acuna Manny Lozoya | | Desert Trail Intermediate |
| 7175 | Work In Progress need 2 classroom faucets. (single handle "cold" water faucets). Thank You !!!!!!!!!!!! | 11/8/2005 Medium | Johnny Acuna Joe Ontiveros | | Desert Trail Intermediate |
| 7184 | Work In Progress Please replace metal door (Back Door) from the kitchen. Door is corroded and getting worse. Thank You !!! | 11/8/2005 Medium | Johnny Acuna Danny Miranda | | Desert Trail Intermediate |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|-------------------------------------|-----------|---------------------------|
| 7520 | Work In Progress (Ruben Ronquillo) Need cement mixer for next week to do cement project in parking lot area. (ramp) | 11/22/2005 Medium | Johnny Acuna Ruben Ronquillo | | Desert Trail Intermediate |
| 7573 | Work In Progress need a gas valve for reznor roof top heater. (valve doesn't close and leaks a little). HONEYWELL : VR8304M 2880 supplied Johnny w/gas valve and he will install. | 11/28/2005 12/1/2005 Medium | Johnny Acuna Lorenzo Solis | | Desert Trail Intermediate |
| 7551 | Work In Progress need ballasts (double) 277 V and light bulbs, to fix classroom light fixtures during intersession. | 11/28/2005 Medium | Johnny Acuna Enrique Sotelo | | Desert Trail Intermediate |
| 7408 | Work In Progress NEED TO INSTALL FENCE AROUND FIRE HYDRANT. (SEE ATTACHED) | 11/16/2005 Medium | Johnny Acuna Michael Munoz | | Desert Trail Intermediate |
| 7366 | Work In Progress need to replace door frame and door to portable #404. | 11/15/2005 Medium | Johnny Acuna Danny Miranda | | Desert Trail Intermediate |
| 7699 | Work In Progress SECURITY LIGHT IN PARKING LOT NOT WORKING. | 12/1/2005 Medium | Johnny Acuna Enrique Sotelo | | Desert Trail Intermediate |
| 8166 | Work In Progress need to replace cracked window to portable #412. Have already placed glass patch on the window (both sides) | 12/16/2005 Medium | Johnny Acuna Ruben Ronquillo | | Desert Trail Intermediate |
| 7917 | Work In Progress Special ED Room - no electrical power to one side of room outlets. Have re-set breakers, but still no power. | 12/7/2005 Medium | Johnny Acuna Enrique Sotelo | | Desert Trail Intermediate |
| 7920 | Work In Progress need a new classroom water faucet for room #111. The old one is bent up, classroom cabinets fell on top of it. (single handle faucet) | 12/7/2005 Medium | Johnny Acuna Joe Ontiveros | | Desert Trail Intermediate |
| 8064 | Work In Progress Please fill in holes in playground area with top soil located in the side of the swings area. Thank You !!!!!!! | 12/13/2005 Medium | Johnny Acuna Guadalupe Ontiveros | | Desert Trail Intermediate |
| 3619 | Work In Progress MENS RESTROOM (NW HALL) : PLEASE CHANGE DOOR CYLINDER WHERE KEY ENTERS TO OPEN UP DOOR. STUDENTS STUFFED IN CYLINDER WITH CLAY AND HARDENED. THANK YOU !!!!!!! | 7/18/2005 Medium | Johnny Acuna Manny Lozoya | | Desert Trail Intermediate |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|-------------------------------------|--|---------------------------|
| 3620 | Work In Progress NEED NAME PLATES TO BE MADE: (1) PRINCIPAL, (1) ASSISTANT PRINCIPAL, (1) COMPUTER LAB | 7/18/2005 Medium | Johnny Acuna Manny Lozoya | | Desert Trail Intermediate |
| 6266 | Work In Progress RUSH ! or as soon as possible or Monday even. Could I get a line locate for Desert Trails Portables? | 10/11/2005 Medium | Carlos Vigil Enrique Sotelo | | Desert Trail Intermediate |
| 7787 | Work In Progress Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Johnny Acuna | | Desert Trail Intermediate |
| 7758 | Work In Progress Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Johnny Acuna | | Desert Trail Intermediate |
| 5462 | Work In Progress need to demo and repour concrete to sectioned area by cafeteria. | 9/13/2005 Medium | Michael Munoz | Desert Trail Intermediate Cafeteria | |
| 3339 | Work In Progress Yearly - Desert View ES Exit Sign Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Patricio Aguilar | | Desert View ES |
| 4149 | Work In Progress key cylinder to walk-in refrigerator doesn't lock, key continuously goes round and round, please repair as soon as possible, groceries and commodities are stored in there. | 8/3/2005 Medium | Alma Terrell Manny Lozoya | Cafeteria | Desert View ES |
| 7518 | Work In Progress Having problems turning ON Top Blodgett Oven Martha Flores - SNP Manager 589-2425 | 11/22/2005 Medium | Alma Terrell Danny Orozco | Cafeteria | Desert View ES |
| 6225 | Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005. | 10/10/2005 Medium | Aida Salcedo Miguel Aguilar | | Desert View ES |
| 3317 | Work In Progress Yearly - Desert View ES Emer. Light Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Patricio Aguilar | | Desert View ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|--|-----------|------------------------------|
| 5340 | Work In Progress MOUSE PROBLEM. MOUSE GOT ON THE TABLE WHILE EATING MARTHA FLORES - 589-2425 HELP PLEASE | 9/8/2005 Medium | Jacqueline Aguilar Margret Villalobos | Cafeteria | Desert View ES |
| 5616 | Work In Progress REQUESTING (2) "R" KEYS, ONE FOR NEW COUNSELOR, Mr. David Gonzalez and the other one to replace Ms. Esther Maldonado's "R" key. (Bended Key) Please pick up bended key with Margarita Terrazas at the front office | 9/19/2005 Medium | Margarita Terrazas Manny Lozoya | | Desert View ES 5055891180 |
| 4083 | Work In Progress TEACHER DESK WITH LOCKING DRAWER, DOES NOT LOCK. ROOM#19, LOWER GRADE SIDE. MRS. GRISWOLD | 8/2/2005 Medium | Margarita Terrazas Manny Lozoya | | Desert View ES |
| 8110 | Work In Progress MANNY, PLEASE MAKE TWO NAME PLAQUES FOR MINERVA SINGH, RN AND YOLANDA F. GOMEZ, CNA. THANK YOU, THANK YOU!! margarita :) | 12/14/2005 Medium | Margarita Terrazas Manny Lozoya | | Desert View ES |
| 5145 | Work In Progress Urgent: Need center pole repaired in exterior double door on east side of school repaired, pole fell and struck teacher. Door cannot be fully secured and will compromise security after school hours. | 9/1/2005 Medium | Miguel Aguilar Manny Lozoya | | Desert View ES |
| 5146 | Work In Progress Need copies (3) made of padlocks on hall doors, need for sub keys and replacement. | 9/1/2005 Medium | Miguel Aguilar Manny Lozoya | | Desert View ES |
| 7232 | Work In Progress Trees in front courtyard unhealthy/dying, signs of infestation, requesting solution/insecticide to remedy problem. | 11/9/2005 Medium | Miguel Aguilar Guadalupe Ontiveros | | Desert View ES |
| 8072 | Work In Progress Requesting wet vac for winter break projects. Will be shower scrubbing floors. | 12/13/2005 Medium | Miguel Aguilar Jimmy Carbajal | | Desert View ES |
| 7613 | Work In Progress Have a nonfunctioning electrical outlet in gymnasium. | 11/29/2005 Medium | Miguel Aguilar Carlos Castillo | | Desert View ES |
| 7614 | Work In Progress Have a nonfunctional electrical outlet in cafeteria. | 11/29/2005 Medium | Miguel Aguilar Carlos Castillo | | Desert View ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|---------------------------------------|------------------|-------------------------|
| 4781 | Work In Progress pat aguilar rock wall (safety concern) 6 rock wall metal gates need to be replaced rusted throw | 8/22/2005 Medium | Patricio Aguilar Michael Munoz | | Desert View ES |
| 7045 | Work In Progress belts for ac 4 each ax26 code 1 2401-285 4 each ax32 code 1 3602-385 | 11/4/2005 Medium | Patricio Aguilar Jose Ambriz | | Desert View ES |
| 7950 | Work In Progress 12/8/05.EXHAUST POWER IN RESTROOM AT C WING DOESN'T WORK. THIS WORK ORDER IN FOR CARLOS CASTILLO. 2ND REQUEST. FIRST WORK ORER #6990. 11/3/05. | 12/8/2005 Medium | Manuel Prospero Carlos Castillo | | GAC |
| 6525 | Work In Progress I NEED 3 EXOST MOTOR FOR C WING V 115 HZ 60 PH 1 HP 1/20 AO AMPS 1.7 NO.7108-5136 RPM 1500. AND AIR FILTERS 20X20XX2. 16X20X2. 16X20X1. 20X25X2. 16X25X2. AS PER JOSE AMBRIZ. | 10/18/2005 Medium | Manuel Prospero Jose Ambriz | | GAC |
| 4377 | Work In Progress NEED NEW R. R. PARTITIONS IN "A" WING AS PER MENNY PROSPERO | 8/9/2005 Medium | Manuel Prospero Danny Miranda | | GAC |
| 7235 | Work In Progress SPED Portable - need ramp for portable located at GAC. (see Margaret Villalobos-SPED_ Route to Manuel Prospero as per Mike 11/9/05 - mkv | 11/9/2005 12/1/2005 Medium | Margret Villalobos Manuel Prospero | | GAC |
| 5824 | Work In Progress NEED A WATERHOSE AND ALSO A HOSE ROLL A WAY.2 WATERHOSE ONE FOR THE PATIO AND ONE FOR THE PRE KINDER AREA I ONLY HAVE ONE AND I USE IT FOR THE FRONT AREA,THE HOSE ROLL A WAYS I NEED ONE FOR EACH HOSE THANK YOU FOR YOUR CONTINUED SUPPORT YOU ARE THE BEST!!!! | 9/26/2005 Medium | Jimmy Carbajal Sal Acuna | Custodial | GAC |
| 8115 | Work In Progress AS PER ELISA SAENZ-NEED FOR HALLWAY LIGHT TO BE CHANGED OUT. MANNY IS ALREADY AWARE AND HAS ALREADY BEEN TAKEN CARE OF | 12/14/2005 Medium | Mary Garcia Manuel Prospero | Hallway/Corridor | GAC A-WING |
| 8116 | Work In Progress AS PER ELISA SAENZ-NEEDS LIGHT BULBS CHANGED IN HER OFFICE. MANNY HAS ALREADY TAKEN CARE OF IT. | 12/14/2005 Medium | Mary Garcia Manuel Prospero | Office | GAC A WING |
| 6743 | Work In Progress AS PER MS. BERRY-NEEDS 3 SIGNS THAT SAY SLOW CHILDREN TO PUT IN THE ENTRANCE AND PARKING AREA. TALKED WITH RUBEN RONQUILLO AND KNOW WHICH SIGNS TO ORDER | 10/25/2005 Medium | Mary Garcia Ruben Ronquillo | | GAC PARKING AREA |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|------------------------------------|--------------|-----------------------------------|
| 4182 | Work In Progress B-Wing - Human Resources Dept Please spray Lucy Garcia's & Ms. Browder's office for bugs (crickets, centerpedes, etc.) | 8/4/2005 Medium | Mary Garcia Margret Villalobos | | GAC |
| 4655 | Work In Progress AS PER ANN STEINHOFF-NEEDS 1 MORE GRAND MASTER KEY FOR HER SECRETARY AT PRE-K | 8/17/2005 Medium | Mary Garcia Manny Lozoya | Office | GAC WHOLE BUILDING |
| 5796 | Work In Progress AS PER CORA-NEEDS THE DOOR LOCK TO THE DATA CENTER SWITCHED OUT FROM SWIPE CARD TO A COMBINATION LOCK. (MANNY, PLEASE SEE CORA BEFORE CHANGING OUT) | 9/23/2005 Medium | Mary Garcia Manny Lozoya | Computer Lab | GAC DATA CENTER- TECHNOLOGY |
| 4925 | Work In Progress C Wing- Having problems with mice. | 8/25/2005 Medium | Mary Garcia Margret Villalobos | | GAC |
| 3408 | Work In Progress AS PER CARLOS VIGIL-NEEDS A GRAND MASTER 7, ASAP. (HIS BROKE IN HALF) ALREADY TALKED WITH MANNY LOZOYA | 7/8/2005 Medium | Mary Garcia Manny Lozoya | Office | GAC ALL SCHOOLS |
| 3432 | Work In Progress AS PER LINDA REYES-NEED FURNITURE FROM 3 OFFICES & BOXES ALONG WITH THIS TO BE MOVED A.S.A.P. TO NEW AREA IN C-WING. STAFF WILL START WORKING IN THESE NEW OFFICES BY TOMORROW. | 7/11/2005 Medium | Mary Garcia Manuel Prospero | Office | GAC C WING |
| 8025 | Work In Progress Walk-In Freezer not freezing at all Gessica Blazquez - SNP Manager - 882-6784 | 12/12/2005 Medium | Alma Terrell Danny Orozco | Cafeteria | GAC |
| 3282 | Work In Progress C-WING - TAKE OFF TILE AND INSTALL NEW TILE (TILE HAS BEEN DELIVERED), ALSO FINISH PAINTING. WILL SEND GERRY MARQUEZ TO ASSIST. | 7/5/2005 Medium | Alfredo Holguin Manuel Prospero | | GAC |
| 6270 | Work In Progress I would like to request a 120v outlet to be installed above kitchen (dock entrance side) door for door horn. | 10/11/2005 Medium | Carlos Vigil Danny Orozco | | GAC |
| 3546 | Work In Progress Technology Server Room-Install Battery powered Emergency lighting in this room | 7/14/2005 Medium | Carlos Castillo | | GAC |
| 7749 | Work In Progress Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Manuel Prospero | | GAC |
| 7786 | Work In Progress Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Manuel Prospero | | GAC |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|-------------------------------------|-------------|-------------------------|
| 7790 | Work In Progress Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Manuel Prospero | | GAC |
| 6050 | Work In Progress Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details. | 10/2/2005 Medium | Alfredo Holguin Danny Orozco | | GAC |
| 7054 | Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Joe Ontiveros | | Gadsden HS |
| 7095 | Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Fernando Moncayo | | Gadsden HS |
| 6001 | Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details. | 10/2/2005 Medium | Alfredo Holguin Joe Ontiveros | | Gadsden HS |
| 7791 | Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Fernando Moncayo | | Gadsden HS |
| 7750 | Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Joe Ontiveros | | Gadsden HS |
| 3659 | Work In Progress PLease install stair treads when they come in. Old english stair ways. I will order. See Mike INstall from main to old english stairs. FAXED PO 8/4/05 - MKV | 7/19/2005 Medium | Mario Apodaca | Stairway | Gadsden HS |
| 4448 | Work In Progress Telescope observatory locate on the west side of the baseball field - Installl fencing around it to prevent vandalism | 8/10/2005 Medium | Michael Munoz | | Gadsden HS |
| 4916 | Work In Progress please check and repair leak & secure drop ceiling in rm 142. possible safety hazard. | 8/25/2005 Medium | Danny Miranda | | Gadsden HS |
| 5458 | Work In Progress need to restripe all parking lines ,handi-cap-arrows etc. | 9/13/2005 Medium | Michael Munoz | Parking Lot | Gadsden HS |
| 5464 | Work In Progress Need to paint stripings for student parking lot and east of Auto Shop. | 9/13/2005 Medium | Michael Munoz | Parking Lot | Gadsden HS |
| 6958 | Work In Progress please provide a concrete landing and side walk to counselors portable. | 11/2/2005 Medium | Michael Munoz | Portables | Gadsden HS |
| 8193 | Work In Progress please repair the goal on the northeast side. | 12/19/2005 Medium | Michael Munoz | Gym | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|--|-----------|-------------------------|
| 7499 | Work In Progress please re-route conduit and repair where kids get on roof by panther hut. north bldg. | 11/21/2005 Medium | Enrique Sotelo | Classroom | Gadsden HS |
| 7500 | Work In Progress please replace disconnect to heating unit on the - S- wing north bldg. blades do not work properly. | 11/21/2005 Medium | Jose Ambriz | Classroom | Gadsden HS |
| 7638 | Work In Progress Girls BB Lockerroom - Connect Electric Water Heater. | 11/29/2005 Medium | David Villalobos Michael Mc Dermott | | Gadsden HS |
| 4311 | Work In Progress PANTHER HUT porch entrance too dark security ligth dosen't work | 8/8/2005 Medium | Fernando Moncayo Fernando Moncayo | | Gadsden HS |
| 4305 | Work In Progress NORTH bus entrance gate keep falling, bottom rail all bend;Also needs new roller bearings for both gates thank you !!! [safety hazard] | 8/8/2005 Medium | Fernando Moncayo Michael Munoz | | Gadsden HS |
| 4240 | Work In Progress Need six wheels for large gates in NORTH parking lot THANK YOU!! 8/11 - Route to Ruben as per Mike | 8/5/2005 Medium | Fernando Moncayo Ruben Ronquillo | | Gadsden HS |
| 3726 | Work In Progress Attn electrician need a better security ligths by CONCESSION STAND to control vandalism | 7/20/2005 Medium | Fernando Moncayo Michael Mc Dermott | | Gadsden HS |
| 5101 | Work In Progress ATTN. JOSE AMBRIZ need about ten three pole contactors for the a/c's nighth set back system in the ACADEMIC BLDG. Some burned out by the power outage.Thank you!! | 8/30/2005 Medium | Fernando Moncayo Jose Ambriz | | Gadsden HS |
| 4902 | Work In Progress AG BLDG entry door,won't open or lock key just turns;Also WOOD SHOP entry door new lock dosen't work | 8/25/2005 Medium | Fernando Moncayo Manny Lozoya | | Gadsden HS |
| 7667 | Work In Progress Need several lighth bulbs,for outside security lights;75-100-175-250w metal halide, 150w mercury vapor THANK YOU!! | 11/30/2005 Medium | Fernando Moncayo Michael Mc Dermott | | Gadsden HS |
| 7721 | Work In Progress Attn. JOSE JO, JO AMRIZ need a blower motor for fresh air units on top of OLD ENGLISH asap please !! LORENZO took the old motor THANK YOU!!! | 12/1/2005 Medium | Fernando Moncayo Jose Ambriz | | Gadsden HS |
| 7725 | Work In Progress Security lights on electrical poles in the SOUTHSIDE of school not working,*safety hazard, too dark for SCHOOL BAND students | 12/1/2005 Medium | Fernando Moncayo Michael Mc Dermott | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|--|-----------|-------------------------|
| 7325 | Work In Progress Attn. MR. AMBRIZ ;Need a combustion vent motor for VARSITY GYM reznor heaters.MTR. is 208/230 volts | 11/14/2005 Medium | Fernando Moncayo Jose Ambriz | Gym | Gadsden HS |
| 7301 | Work In Progress BOY'S GYM SOUTH EAST exterior door need to be replace | 11/11/2005 Medium | Fernando Moncayo Danny Miranda | Gym | Gadsden HS |
| 6607 | Work In Progress LIBRARY EAST wall;There is a, wall keyed hose bib that is leaking | 10/20/2005 Medium | Fernando Moncayo David Villalobos | | Gadsden HS |
| 6609 | Work In Progress Need to install flouresent lighth lamps in ANNEX CORRIDOR, is too dark | 10/20/2005 Medium | Fernando Moncayo Michael Mc Dermott | | Gadsden HS |
| 6489 | Work In Progress VARSITY GYM; girl's BASKETBALL locker room,water heater is leaking from bottom of tank | 10/17/2005 Medium | Fernando Moncayo David Villalobos | | Gadsden HS |
| 3593 | Work In Progress Need to repair or replace electrical conduit outside of CONCESSION STAND by GIRL'S GYM | 7/15/2005 Medium | Fernando Moncayo Michael Mc Dermott | | Gadsden HS |
| 8017 | Work In Progress Need to replace several ballasts in woodshop | 12/12/2005 Medium | Carlos Castillo Carlos Castillo | Classroom | Gadsden HS |
| 8254 | Work In Progress Need to replace return unit's disconnect | 12/22/2005 Medium | Carlos Castillo Carlos Castillo | Cafeteria | Gadsden HS |
| 8145 | Work In Progress several light pole around cafeteria area are out.Already change lamps but still not working,need to change ballasts. | 12/15/2005 Medium | Carlos Castillo Carlos Castillo | | Gadsden HS |
| 3141 | Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details. | 7/3/2005 Medium | Alfredo Holguin Joe Ontiveros | | Gadsden HS |
| 3319 | Work In Progress Yearly - Gadsden HS Emer. Light Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Joe Ontiveros | | Gadsden HS |
| 4904 | Work In Progress Requested by Mr. D. Gallegos Rm. 403-Please install water fountains with hose bibs, between soccer canopies for Athletic events and Gadsden High School P.E. classes. | 8/25/2005 Medium | Velia Alarcon Guadalupe Ontiveros | | Gadsden HS |
| 4897 | Work In Progress Requested by Velia Rm. 112 Front Office-Two HE27 are needed for key box. | 8/25/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|-------------------------------------|-----------|-------------------------|
| 4947 | Work In Progress Old English Bldg - Heating is turning on and on the computer it states that it is off. Teachers have been complaining on a daily basis that it is too hot. Need your help! | 8/26/2005 Medium | Velia Alarcon Margret Villalobos | | Gadsden HS |
| 4810 | Work In Progress Requested by Ms. L. Chavez Rm. 245 Classroom Over Varsity Gym-Re-place several burned out light bulbs. RE-ROUTE TO BUILDING MECHANIC as per Mike Mc Dermott 9/19/05 | 8/23/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 4820 | Work In Progress Requested by Luis Saucedo Rm. 507 & 509 Annex Building-Install door stops on each of these doors. | 8/23/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 4822 | Work In Progress Requested by Ms. Zapien Rm. 154 Old English Building-The blinds are completely broken, the curtain is hanging. | 8/23/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 4811 | Work In Progress Requested by Mr. Cordova Storage Room in Varsity Gym Stage-The door needs to be re-keyed to an off master key, light board room. 4 keys are needed. | 8/23/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4812 | Work In Progress Requested by Lt. Dickerson Rm. 202 North Building-His HEM key has broken, 3 HEM keys are needed. One for him and two for the key box. | 8/23/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4816 | Work In Progress Requested by Ms. L. Melendrez Rm. 331 Academic Building-I have been having trouble opening my front door for over a year, and now I am having trouble opening the back door. It's not my key it's the door handle and deadbolts. Both back doors are very difficult to open. | 8/23/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4817 | Work In Progress Requested by Mr. S. Perez Weight Room-Boys locker room door handle needs repair does not open. West side Weight Room door needs repairs does not lock. | 8/23/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4905 | Work In Progress Requested by Mr. Milligan Rm. 143 Old English Building-Four keys are needed of HX2. Three for the assistant coaches and one for key box. | 8/25/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|-------------------------------------|-----------|-------------------------|
| 5068 | Work In Progress Requested by Ms. Anderson Rm. 233 North Building (Panther Hut)-Replace circuit breakers with ones that can handle the load of appliances in the kitchen so we don't constantly trip them. Note from Mr. Chambers: Question? Check and see if appliances can be re-routed to another outlet? Too many appliances on one outlet will cause fire. | 8/30/2005 Medium | Velia Alarcon Michael Mc Dermott | | Gadsden HS |
| 5084 | Work In Progress Requested by Velia Press Box-Safety Hazard; need to re-duct and install new air conditioner were it can be serviced. FERNANDO, JOSE WILL LOOK INTO ORDERING UPDRAFT UNIT AND SHEETMETAL. AS PER OUR CONVERSATION YOU AND MARIO WILL FORM AND POUR CONCRETE FOR SMALL PAD FOR A/C STAND. IN THE MEAN TIME SERVICE WHAT IS THERE. - M. MUNOZ 9/1/05-MKV XC: WO TO FERNANDO | 8/30/2005 Medium | Velia Alarcon Jose Ambriz | | Gadsden HS |
| 5083 | Work In Progress Requested by Mr. Martin Rm. 551 Wood Shop-Hall lock will no unlock, 2nd Notice. | 8/30/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 5076 | Work In Progress Requested by Ms. Anderson Rm. 233 North Building (Panther Hut)-Pastry refrigerator has severe condensation dripping. | 8/30/2005 Medium | Velia Alarcon Danny Orozco | | Gadsden HS |
| 6282 | Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop-Paint (or provide paint)for repainting the tool room and paint room. Second Request | 10/11/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 6286 | Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop-Install circuit with sufficient amperage to run Drum Sander. Second Request | 10/11/2005 Medium | Velia Alarcon Michael Mc Dermott | | Gadsden HS |
| 6287 | Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop-Route stationery power tools through central emergency shut off. Second Request | 10/11/2005 Medium | Velia Alarcon Michael Mc Dermott | | Gadsden HS |
| 6288 | Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop-Replace burned out transformer for overhead lights. Second Request | 10/11/2005 Medium | Velia Alarcon Michael Mc Dermott | | Gadsden HS |
| 6274 | Work In Progress Requested by Mr. Chambers Varsity Gym-Varsity Gym floor is showing large space and boards are coming loose, needs repair a.s.a.p. SAFETY ISSUE | 10/11/2005 Medium | Velia Alarcon Michael Munoz | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|---|--|-----------------------------------|------------------|---------------------------------|
| 6273 | Work In Progress Requested by Velia Rm. 100 Main Building-All of the doors and drawers need to be tightened, they're all off their tracks or broken. | 10/11/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |
| 6285 | Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop-Replace burned out lights in paint room. | 10/11/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |
| 5601 | Work In Progress Requested by Ms. Thornley Rm. 660 Business Building-No heat/A.C. in lounge. Please attempt to tie into the ducting in my classroom (it has it's own system and is immediately adjacent) so that our lounge can be more comfortable. | 9/19/2005 Medium | Velia Alarcon Jose Ambriz | | Gadsden HS |
| 5412 | Work In Progress Requested by D. Gallegos Rm. 403 Boys Gym-Install threaded end on faucet or shower in volleyball and boys basketball lockers to allow for a water hose connection. | 9/12/2005 Medium | Velia Alarcon David Villalobos | | Gadsden HS |
| 5416 | Work In Progress Requested by Mrs. Klein Rm. 504 Annex Building-Roof is leaking, one spot has mold, and one panel is buldging down. | 9/12/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 5405 | Work In Progress Requested by Velia Rm. 112 Front Office-HG3 is needed for key box. | 9/12/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 5406 | Work In Progress Requested by Velia Rm. 112 Front Office-Two SA16 are needed, one for Ms. Dominguez and one for key box. | 9/12/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 5407 | Work In Progress Requested by Marie School Registrar Storage Room East Wing of the Cafeteria-The new vault needs to be re-keyed. The cylinder from the old vault can be placed on the door of the East Wing of the Cafeteria were her new vault is located now. | 9/12/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 5409 | Work In Progress Requested by Marie Storage Room in the East Wing of the Cafeteria-In the move from the old vault to the storage room one of the fire prove filing cabinet's locks broke. The filing cabinet remained locked, needs to be fixed as soon as possible as the Registrar needs access to these files on a daily basis. | 9/12/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|-----------------------------------|-----------|-------------------------|
| 4814 | Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Air conditioner still does not work. No air is coming out of vents, very hot. Wires hanging into light fixture and a piece of ceiling tile (broken) is in one of the air conditioning vents. (room was damaged over summer) | 8/23/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |
| 4633 | Work In Progress Requested by ISS Rm. 800 Old Counseling Center-Door frame falling off portable door leading to the old counseling center. | 8/17/2005 Medium | Velia Alarcon Danny Miranda | | Gadsden HS |
| 4631 | Work In Progress Requested by Ms. M. Gonzalez Rm. 140 Old English Building-I would like to request a door stop for the new door and blinds fo one of my windows. The room gets "very" warm espcpecially 4th period. Receive measurements from Bldg Mechanic and re-route to Ruben for ordering. 4 ea - 43" W x 90' L | 8/17/2005 9/16/2005 Medium | Velia Alarcon Ruben Ronquillo | | Gadsden HS |
| 4627 | Work In Progress Requested by Velia Rm. 112 Front Office-Work order #3911 was not asked to me made off master, also three keys were asked for not two. An additional 4 keys are needed as soon as possible. | 8/17/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4630 | Work In Progress Requested by Mr. Dixon Rm. 600 Business Building-Needs an F3 gate key. | 8/17/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4521 | Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Need a lock and spare keys on the new filing cabinet. | 8/12/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4562 | Work In Progress Requested by Ms. Klein Rm. 504 Annex Building-Air conditioner not working and appears to be leaking. | 8/15/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |
| 4564 | Work In Progress Requested by Ms. Nanez Library-Install plywood baks to magazine shelves. | 8/15/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |
| 4516 | Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-New water heater for kitchen area of Panther Hut. Route to Bldg Mechanic as per Mike 8/15/05 Check to see whats wrong with the H2o heater they have new one in small mech. room. | 8/12/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |
| 4248 | Work In Progress Requested by Ms. Gutierrez Rm. 823 Barracks-New cylinder is needed for new filing cabinet, 3 keys are needed. | 8/5/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|---|--|-------------------------------------|------------------|---------------------------------|
| 4243 | Work In Progress Requested by Ms. Bradley Rm. 602 Business Building-Handle on window has broken off, needs to be replaced. | 8/5/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 4222 | Work In Progress Requested by Mr. Grubaugh Rm. 275C Library-The door to the video room has swollen and will not shut properly unless its slammed. | 8/4/2005 Medium | Velia Alarcon Danny Miranda | | Gadsden HS |
| 4282 | Work In Progress Requested by Mr. Martinez Rm. 227 North Building-Replace carpet in Attendance Office area. One edge of the carpet is lifting, our concern is that a person may trip and fall. | 8/8/2005 Medium | Velia Alarcon Michael Munoz | | Gadsden HS |
| 4269 | Work In Progress Requested by Ms. Jacquez Rm. 752 Barracks-Window is unhinged and needs to be repaired. | 8/8/2005 Medium | Velia Alarcon Ruben Ronquillo | | Gadsden HS |
| 4272 | Work In Progress Requested by Ms. Klein Rm. 504 Annex Building-Having a hard time locking and opening door, appears to be locked but stays unlocked. | 8/8/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4279 | Work In Progress Requested by Ms. Littlefield Rm. 226 North Building-The lock on my podium and one storage cabinet is brocken and lost. | 8/8/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4283 | Work In Progress Requested by Mr. Myers Rm. 509 Annex Building-Key will not open storage door. HJ10 is the key that should open door. | 8/8/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4286 | Work In Progress Requested by Mr. Villa Rm. 510 Band Room-Need two HK13 keys made. | 8/8/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4288 | Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-Lights are burned out in the shop. | 8/8/2005 Medium | Velia Alarcon Michael Mc Dermott | | Gadsden HS |
| 4271 | Work In Progress Requested by Ms. Kalkwarf Rm. 750 Barracks-Floor tiles are broken and coming off the floor. | 8/8/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |
| 4285 | Work In Progress Requested by Mr. Villa Rm. 510 Band Room-Security light in the center of the room does not work. | 8/8/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |
| 4429 | Work In Progress Requested by Velia Rm. 112 Front Office-Three HE keys are needed for Key Box. | 8/10/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|-------------------------------------|-----------|-------------------------|
| 4387 | Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- Need a new oil pressure gauge for air compressor. (0-30 PSI) Current gauge leaks compressor oil out of crankcase and on to the floor. Need a new air pressure gauge for air compressor, current gauge is to small. Need a 0- 150PSI gauge. | 8/9/2005 Medium | Velia Alarcon Jose Ambriz | | Gadsden HS |
| 4385 | Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- Two large shop lights are burned out. | 8/9/2005 Medium | Velia Alarcon Michael Mc Dermott | | Gadsden HS |
| 4386 | Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- 220 Volt Electric extension cord needed with a new female end, current ones puts people at risk of electrocution. | 8/9/2005 Medium | Velia Alarcon Michael Mc Dermott | | Gadsden HS |
| 4360 | Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HJ7, one for the floating teacher and one for the Key Box. For room number 753. | 8/9/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4361 | Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK1, one for the floating teacher and one for the Key Box. For the Auto Shop. | 8/9/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4362 | Work In Progress Requested by Velia Rm. 112 Front Office-We need 5 additional keys of HE1. For the Gyms. | 8/9/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4363 | Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK5, one for the I.A. in the classroom and one for the key box. For room number 569. | 8/9/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4204 | Work In Progress Requested by Cathy Cano Parking Lot-Over Fall Break, have the lines in the North Parking Lot painted. | 8/4/2005 Medium | Velia Alarcon Michael Munoz | | Gadsden HS |
| 4199 | Work In Progress Requested by Mr. Chambers Rm. 110 Front Office-Re-key doors, make cylinders off D Master, 4 keys will be needed. Have had several items stolen from office, please re-key as soon as possible. | 8/4/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 4166 | Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace ceiling tile in storeroom and office. | 8/3/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|-----------------------------------|-----------|-------------------------|
| 4153 | Work In Progress Requested by Mary Barreras Rm. 130 Old English Building-Need the new key to new lock to Sp. Ed. storage room for files and equipment. Key # M260 | 8/3/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 3910 | Work In Progress Requested by Isela Martinez New Counseling Center Portable-Bracket needed for N.M. Flag. | 7/28/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |
| 3902 | Work In Progress Requested by Ms. Marquez New Counseling Portable-Two filing cabinets need to be keyed. | 7/28/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 3920 | Work In Progress Requested by Velia Front Office-The cylinder for room #107 will not open with a D Master or key assigned to door. This classroom is the Day Care on our campus and the building custodian can not open the classroom to clean. Please fix as soon as possible. | 7/28/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 3908 | Work In Progress Requested by Isela Martinez New Counseling Center Portable-Dr. Pockets to be placed in Marie's copy to be placed on wall. | 7/28/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 3909 | Work In Progress Requested by Isela Martinez New Counseling Center Portable-Install clock on wall. | 7/28/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 3715 | Work In Progress Requested by Mr. Pawloski Rm. 109A Main Building (Sp.Ed. Office)-Please remove the lock in my file cabinet, replace, and re-key it with a new one. | 7/20/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 3716 | Work In Progress ***URGENT***Requested by Velia Library-All the doors in the library need to be secured. They have changed all the door knobs and the cylinders need to be installed. URGENT library has alot of equipment that needs to me locked and secured! | 7/20/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 7370 | Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop- 2ND REQUEST Replace ceiling tile in office storeroom. Consider placing a plywood floor over unprotected tile. | 11/15/2005 Medium | Velia Alarcon Michael Munoz | | Gadsden HS |
| 6454 | Work In Progress Requested by Mr. Chambers Football Restrooms-Paint large letters on restroom indicating men's and women's sides, or hang large signs indicating directions. | 10/17/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|-------------------------------------|-----------|-------------------------|
| 6460 | Work In Progress Requested by Mr. Whitener Rm. 563 Ag. Shop- Install a hydraulic door closer on the new front door to the building. | 10/17/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 6713 | Work In Progress Requested by Ms. Trich Library-Please replace blown light bulbs, especially in Librarian's office, room 275b. | 10/25/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |
| 6710 | Work In Progress Requested Ms. Nanez Library-Backs to shelves need to be installed. Backs are in library, however, they need to be cut down to fit. | 10/25/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 6833 | Work In Progress Requested by Luis Saucedo Main Building-East and west hallways the light switches are broken. Having a problem turning on the lights every morning. Light switches on each corner. | 10/28/2005 Medium | Velia Alarcon Michael Mc Dermott | | Gadsden HS |
| 6830 | Work In Progress Requested by Velia Rm. 127 Main Building-When the sound system contractors installed the wiring in Ms. Garcia's classroom. They placed it on a wall Ms. Garcia used for her projector. Once they removed the wiring and placed it on another wall, they left the wall scrated and paint peeled. Wall needs to be repaired and painted. | 10/28/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |
| 7145 | Work In Progress Requested by Ms. V. Lopez Old Counseling Center-Repair hole in ceiling near new ventilation work. | 11/7/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 7626 | Work In Progress Requested by Mr. Foster and Mr. Chambers Varsity Gym-ATTN: Mike Munoz Replace heating units and duct work. *Girls team practiced in 23 degrees this morning in the gym. *Parents calling and complaining about conditions. *Parents calling Central Office. | 11/29/2005 Medium | Velia Alarcon Jose Ambriz | Gym | Gadsden HS |
| 7910 | Work In Progress Requested by Mr. Carrasco Auto Shop-The spring which supports the lifting of the Nort Shop door has broken and needs repair. | 12/7/2005 Medium | Velia Alarcon Danny Miranda | | Gadsden HS |
| 7913 | Work In Progress Requested by Cathy Cano Concession Stand- Windows to concession stand need to be put back on. Reasons: cold, and too many flies and/or bees. Route to Bldg Mechanic as per Mike Munoz 12/16/05 - mkv | 12/7/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|-------------------------------------|-----------|-------------------------|
| 7914 | Work In Progress Requested by Ms. Hunt Rm. 105 Main Building- Cupboard door broke off, screws on my desk. | 12/7/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 7915 | Work In Progress Requested by Mr. Contaldo Campus Observatory- Close hatch door on observatory, check out electrical connection for motor drive and white overhead lights. route to Mike Mc Dermott - As per Mike Munoz 12/12/05 - mkv | 12/7/2005 Medium | Velia Alarcon Michael Mc Dermott | | Gadsden HS |
| 8068 | Work In Progress Requested by Mr. Chambers North Building Project-Temporarily remove cable from North Building Lockers by Saturday, Dec. 17. (For Columbia University Film Documentary) | 12/13/2005 Medium | Velia Alarcon Michael Munoz | | Gadsden HS |
| 8074 | Work In Progress Requested by Velia Rm. 112 Front Office-Four keys of 1HEM (old master key) are needed. Three keys have been broken and I need to replace the ones I had in the key box. | 12/13/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 8087 | Work In Progress Requested by Mr. Whitener Rm. 562 Ag. Shop- The exhaust fans in both restrooms have been disconnected, requesting that they both be reconnected. | 12/13/2005 Medium | Velia Alarcon Jose Ambriz | | Gadsden HS |
| 8088 | Work In Progress Requested by Mr. Whitener Rm. 564 Ag. Shop- One light in the office does not work. | 12/13/2005 Medium | Velia Alarcon Michael Mc Dermott | | Gadsden HS |
| 8089 | Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- One light in the Ag. Shop-front row is not working. | 12/13/2005 Medium | Velia Alarcon Michael Mc Dermott | | Gadsden HS |
| 8078 | Work In Progress Requested by Ms. Simmons Rm. 652 Business Building-I need a wall (no. end of my room) We, students and myself, would appreciate it. We have the materials already. Note: This request was ok'd last year, C. Chambers. | 12/13/2005 Medium | Velia Alarcon Danny Miranda | | Gadsden HS |
| 8081 | Work In Progress Requested by Ms. Trich Rm. 275 Library-Tops of the short book shelves are losing the laminate, which is peeling off. Please re-attach the laminate tops. Please check with either Bonnie or me. | 12/13/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|--------------------------------------|-----------|-------------------------|
| 8180 | Work In Progress Requested by Ms. R. Holguin Rm. 125 Main Building-Handicap railing in bathroom came off wall. There was no bracing behind it. We have two students using it. Note: PRIORITY (Mr. C. Chambers) | 12/16/2005 Medium | Velia Alarcon Fernando Moncayo | | Gadsden HS |
| 8179 | Work In Progress Requested by Mr. Contaldo Campus Observatory- Install 6' chain link fence around Observatory Deck with locking gate. Key problem: prevent future vandalism. 1/11 - Route to Lupe as per Mike. | 12/16/2005 Medium | Velia Alarcon Guadalupe Ontiveros | | Gadsden HS |
| 8172 | Work In Progress Requested by Velia Rm. 112 Front Office-Three keys of D41 are needed for key box, Girlsbathroom North Building. | 12/16/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 8174 | Work In Progress Requested by Velia Rm. 112 Front Office-Three keys of D111 are needed for key box, Boys Bathroom North Building. | 12/16/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 8175 | Work In Progress Requested by Velia Rm. 112 Front Office-Four keys of HEM (new master key) are needed, to be kept in key box and be distributed as needed. | 12/16/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 8182 | Work In Progress Requested by L. Melendrez Rm. 333 Academic Building-Classroom walls need to be repaired. There are holes in the walls and it needs to be repainted. | 12/16/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 8185 | Work In Progress Requested by Ms. Trich Library-The drawer slides for the cashbox are loose. They may be missing screws to attach them to the base. Might someone please assess the situation to determine if the present one can be repaired or if they need replacement? Please check with Leslie, this is a safety issue; the drawer may fall out of the base. | 12/16/2005 Medium | Velia Alarcon Mario Apodaca | | Gadsden HS |
| 8178 | Work In Progress Requested by Mr. Contaldo Campus Observatory- Fix or replace limiting switches on Observatory hatch. Existing switches may (?) be fixed by bending metal contact plates to correct position. Key problem: need to be able to open and close hatch. Replace or fix white light bulbs inside Observatory. | 12/16/2005 Medium | Velia Alarcon Michael Mc Dermott | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|-------------------------------------|-----------|-------------------------|
| 3493 | Work In Progress Requested by Pamela Holguin Rm. 228 North Building-A door frame is needed. Will have an old door installed, left over from doors that are being replaced in North Building. Also, a door knob that will not lock is needed. | 7/12/2005 Medium | Velia Alarcon Danny Miranda | | Gadsden HS |
| 3494 | Work In Progress Requested by Marie New Counseling Center Portable-New portable needs to be keyed HE134. Change old cylinder to doors of new portable doors. | 7/12/2005 Medium | Velia Alarcon Manny Lozoya | | Gadsden HS |
| 3479 | Work In Progress All Campus - Need to replace old door knobs w/new levers. | 7/12/2005 Medium | Hector Lozoya Manny Lozoya | | Gadsden HS |
| 3645 | Work In Progress BOTH OVENS ARE DOWN. LYDIA M. SNP MGR 882-5522 | 7/19/2005 Medium | Jacqueline Aguilar Danny Orozco | Cafeteria | Gadsden HS |
| 5108 | Work In Progress NEED TO PUT NEW BALLAST AT WOOD SHOP LAMPES | 8/31/2005 Medium | Mario Apodaca Michael Mc Dermott | | Gadsden HS |
| 4970 | Work In Progress GLASS AT MAIN BLDG HALLWAY 40X18 NEED TOBE REPLACES VANDALISM | 8/26/2005 Medium | Mario Apodaca Ruben Ronquillo | | Gadsden HS |
| 4976 | Work In Progress NEED ALL WINDOW BLINDSON OLD ENGLISH BLDG 40 EA 40WX90L | 8/26/2005 Medium | Mario Apodaca Ruben Ronquillo | | Gadsden HS |
| 5842 | Work In Progress NEED A NEW GLASS PUT ON CONCESSION STAND WINDOW AT FOOTBALL FIELD (VANDALISM) 23X23 ASAP | 9/26/2005 Medium | Mario Apodaca Ruben Ronquillo | | Gadsden HS |
| 5708 | Work In Progress THE OUTSIDE OUTLET NEED TO BE FIX AT WEIGHT ROOM | 9/21/2005 Medium | Mario Apodaca Michael Mc Dermott | | Gadsden HS |
| 4502 | Work In Progress NEED TO LAMPES AT WOOD SHOP SAME ARE BURNED OUT | 8/11/2005 Medium | Mario Apodaca Michael Mc Dermott | | Gadsden HS |
| 7886 | Work In Progress NEED TO REPAIR ALL DOOR FRAMS AT THE WEIGHT ROOM THE KID WILL PULL THE DOOR OPEN W/THE DOOR ARE LOCK | 12/6/2005 Medium | Mario Apodaca Danny Miranda | | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|--------------------------------------|-----------------|-------------------------|
| 7956 | Work In Progress Vandalism - Damage to south front entrance roll gate hit by vehicle. (Case# 2005-10383) Deputy Isidro Gonzalez #935 | 12/2/2005 Medium | Mario Apodaca Michael Munoz | | Gadsden HS |
| 7936 | Work In Progress NEED A NEW EXHAUST FAN MOTOR FOR N/BLDG HEATING UNIT MO JB1PO5ONS" O26-275OC 115V 60HZ 1.5A 3050 RPM | 12/7/2005 Medium | Mario Apodaca Jose Ambriz | | Gadsden HS |
| 8095 | Work In Progress NEED A NEW FLOODLIGHT FIXER FOR THE SCHOOL SIGN AT FRONT OF CAMPUS. | 12/13/2005 Medium | Mario Apodaca Michael Mc Dermott | | Gadsden HS |
| 6526 | Work In Progress NEED TOO RUN SEWER SNAKE AT WOOD SHOP BLDG unclog main sewer line to woodshop | 10/18/2005 10/19/2005 Medium | Mario Apodaca David Villalobos | | Gadsden HS |
| 6595 | Work In Progress OUTSIDE CONDUIT AT ROOM 233 NEED TO BEREPAIR SO IT CAN'T BE PULL OFF THE WALL ON MORE AND THE KID CAN'T USE THE CONDUIT AS A LADDER TO GATING UP TO THE ROOF TOP | 10/20/2005 Medium | Mario Apodaca Michael Mc Dermott | Restroom (Boys) | Gadsden HS |
| 6425 | Work In Progress NEED TO REMOVE ALL OUTLET AT ROOM 126 AT ARE ON BOOK SHEVING FLOOR AND RELOCA OUTLETS | 10/14/2005 Medium | Mario Apodaca Michael Mc Dermott | Custodial | Gadsden HS |
| 7277 | Work In Progress NEED TO PUT CRUSH ROCK ON ROAD BY THE WOOD SHOP , ANNEX BLDG AND POOL SO DUST WOOD NOT P-PU ASAP | 11/10/2005 Medium | Mario Apodaca Guadalupe Ontiveros | | Gadsden HS |
| 7239 | Work In Progress NEED KEY FOR TOW FILE CABINETS AT ROOM 223 | 11/9/2005 Medium | Mario Apodaca Manny Lozoya | | Gadsden HS |
| 3524 | Work In Progress NEED TO FIX FOOTBALL FIELD SCOREBOARD BREAKER BOX | 7/14/2005 Medium | Mario Apodaca Michael Mc Dermott | | Gadsden HS |
| 3525 | Work In Progress NEED TO CK ALL FOOTBALL FIELD LAMPS | 7/14/2005 Medium | Mario Apodaca Michael Mc Dermott | | Gadsden HS |
| 4726 | Work In Progress Royal vacuum is missing bag and brush, belt serial No.H93266101B GISD tag 014131 | 8/19/2005 Medium | Jesus Estrada Jimmy Carbajal | | Gadsden HS |
| 5915 | Work In Progress Pressbox - There is a Bee Hive in pressbox. Having a game tomorrow. Please send someone out today. (Open PO) as per A. Holguin. | 9/28/2005 Medium | Jesus Estrada Margret Villalobos | Football Field | Gadsden HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|--------------------------------------|------------------|-------------------------|
| 4867 | Work In Progress THE PAD HOLDER IS WORN OUT AND WONT HOLD THE PAD AT ALL. | 8/24/2005 Medium | Jimmy Carbajal Jimmy Carbajal | Hallway/Corridor | Gadsden MS |
| 3582 | Work In Progress IRRIGATION CTRL PANEL - IRRIGATION BOOSTER PUMP IS NOT WORKING. PLEASE TROUBLESHOOT BUS TURNAROUND AREA. ROUTED TO ENRIQUE AS PER RICK 8/2/05 | 7/15/2005 8/2/2005 Medium | Lorenzo Hernandez Enrique Sotelo | | Gadsden MS |
| 7824 | Work In Progress JOHNNY'W WAREHOUSE: FREEZER #1 - ONE OF THE FAN MOTORES WENT OUT. SMELLS LIKE IT BURNED OUT. JOHNNY LECHUGA - SNP WHSMGR 882-6927 | 12/5/2005 Medium | Jacqueline Aguilar Danny Orozco | Electrical Room | Gadsden MS |
| 5119 | Work In Progress Power Outage - El Paso Electric | 8/29/2005 Medium | Margret Villalobos Enrique Sotelo | | Gadsden MS |
| 3616 | Work In Progress replace door at pump room | 7/18/2005 Medium | Ricardo Jacquez Danny Miranda | | Gadsden MS |
| 4218 | Work In Progress Coil in not cooling cleaned out strainer and checked valve. RM 156 | 8/4/2005 Medium | Rudy Arreola Jaime Gomez | Classroom | Gadsden MS |
| 4220 | Work In Progress Rm 157/158 Unit is not cooling at all cleaned out strainer and checked valves. | 8/4/2005 Medium | Rudy Arreola Jaime Gomez | Classroom | Gadsden MS |
| 4725 | Work In Progress Portable 500/501 really leak bad right in the center of the room. | 8/19/2005 Medium | Rudy Arreola Rudy Arreola | Portables | Gadsden MS |
| 4528 | Work In Progress We need 2 water fountains replaced in cafeteria. | 8/12/2005 Medium | Rudy Arreola Jaime Gomez | | Gadsden MS |
| 5317 | Work In Progress Need to cap of water lines and drain removed already removed sink and counters. RM#188. | 9/7/2005 Medium | Rudy Arreola Joe Ontiveros | Classroom | Gadsden MS |
| 5569 | Work In Progress VOC BLDG RM#306 - Need some assistance changing out ballast already replaced lamps high ceiling. | 9/16/2005 Medium | Rudy Arreola Enrique Sotelo | Classroom | Gadsden MS |
| 5793 | Work In Progress {{{GYM LOBBY}}} Wall needs to be secured. | 9/23/2005 Medium | Rudy Arreola Danny Miranda | Restroom (Boys) | Gadsden MS |
| 5918 | Work In Progress Door handle is broken off boys lockerroom | 9/28/2005 Medium | Rudy Arreola Manny Lozoya | | Gadsden MS |
| 7621 | Work In Progress Rockwall front the school needs to be repaired chunks missing and has sharp edges. | 11/29/2005 Medium | Rudy Arreola Michael Munoz | | Gadsden MS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|------------------------------------|------------------|-------------------------|
| 6384 | Work In Progress Light by main entrance is not working. | 10/13/2005 Medium | Rudy Arreola Enrique Sotelo | | Gadsden MS |
| 6386 | Work In Progress Light on the westside of the bandroom doesnt turn on. | 10/13/2005 Medium | Rudy Arreola Enrique Sotelo | | Gadsden MS |
| 7202 | Work In Progress Light on the southside of A-WING keeps blinking on and off. | 11/8/2005 Medium | Rudy Arreola Enrique Sotelo | | Gadsden MS |
| 7204 | Work In Progress Broken light cover on security light on northside of gym.need to have cover repalced also new bulb. | 11/8/2005 Medium | Rudy Arreola Enrique Sotelo | | Gadsden MS |
| 7921 | Work In Progress We need a switch installed in the front office to turn on and off the unit. | 12/7/2005 Medium | Rudy Arreola Jose Ambriz | | Gadsden MS |
| 8107 | Work In Progress Heater is not working needs a new board. | 12/14/2005 Medium | Rudy Arreola Lorenzo Solis | Hallway/Corridor | Gadsden MS |
| 8121 | Work In Progress 12*08*05 .50 Ck in with office. 1.0 Ck boiler RMs. 2.0 Had to adjust temps in RMs main bldg. .50 Did paperwork. 1.0 Clogged toilet boys RR b-WING cleaned up water and toilet paper. 1.5 Heater not working RM 116. 1.5 Picking up trash by c-wing. .50 Did paperwork. 1.0 Clogged toilet Boys RR cleaned up water and toilet paper. 12/8 - 7 | 12/14/2005 Medium | Rudy Arreola Margret Villalobos | | Gadsden MS |
| 7908 | Work In Progress Sink Clogged Terry Portillo - SNP Manager - 882-2824 | 12/7/2005 Medium | Alma Terrell Danny Orozco | Cafeteria | Gadsden MS |
| 7479 | Work In Progress Also at GMS Gym Bleachers They have a cheap extension for the score board, could we get a permanent 120v outlet fastened to front of bleachers? thanks , Carlos | 11/18/2005 Medium | Carlos Vigil Enrique Sotelo | | Gadsden MS |
| 4643 | Work In Progress Need a copy of fire alarm key (See Mr. Hamel for his key). | 8/17/2005 Medium | Dana Hamel Manny Lozoya | | Gadsden MS |
| 4777 | Work In Progress The three locks on the office front window are broken, mostly poor design. The front office is wide open until these are repaired or replaced | 8/22/2005 Medium | Dana Hamel Rudy Arreola | Office | Gadsden MS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|---|--|----------------------------------|------------------|---------------------------------|
| 4522 | Work In Progress Door broken in room 500, and window shattered | 8/12/2005 Medium | Dana Hamel Danny Miranda | Portables | Gadsden MS |
| 4982 | Work In Progress Whole south side of annex does not have any air, class temperatures are above 95 degrees. The classes opposite hallway have conditioning, Please fix ASAP | 8/26/2005 Medium | Dana Hamel Jaime Gomez | Classroom | Gadsden MS |
| 4778 | Work In Progress 2nd request for an "A" master for GMS Campus | 8/22/2005 Medium | Dana Hamel Manny Lozoya | Office | Gadsden MS |
| 6241 | Work In Progress The new roof on the vocational building leaked badly over vacation and the insulation in the old woodshop is falling. Serious problem with students returning tomorrow could fall at any time. | 10/10/2005 Medium | Dana Hamel David Boyd | Classroom | Gadsden MS |
| 5499 | Work In Progress Change M4 key to a G key in all electrical room on campus, we have no "m" master | 9/14/2005 Medium | Dana Hamel Manny Lozoya | Electrical Room | Gadsden MS |
| 5500 | Work In Progress change A3 key to a "g" key in storage room in annex | 9/14/2005 Medium | Dana Hamel Manny Lozoya | Mechanical Room | Gadsden MS |
| 5501 | Work In Progress Repair the outside doors locks "w" master will not open doors to lobby | 9/14/2005 Medium | Dana Hamel Manny Lozoya | Hallway/Corridor | Gadsden MS |
| 5502 | Work In Progress request 3 new "G" keys for principal and custodians | 9/14/2005 Medium | Dana Hamel Manny Lozoya | | Gadsden MS |
| 3651 | Work In Progress Mice in Gloria Hernandez office in C Wing. Need control as soon as possible 1) HAD JUAN CHECK FOR ANY FOOD AROUND, 2) REQUESTED THAT THEY ASK R. RONQUILLO FOR MICE TRAPS (W/GLUE) 3) FAXED FOR PRICE QUOTE AS PER M. MUNOZ FOR THE WHOLE C-WING. | 7/19/2005 Medium | Dana Hamel Margret Villalobos | Office | Gadsden MS |
| 3652 | Work In Progress Cockroach issues for the total school, need a monthly spraying Faxed PO - 8/4/05 -mkv | 7/19/2005 Medium | Dana Hamel Margret Villalobos | Hallway/Corridor | Gadsden MS |
| 3653 | Work In Progress paint the columns on outside of gym | 7/19/2005 Medium | Dana Hamel Rudy Arreola | Gym | Gadsden MS |
| 3654 | Work In Progress paint over the scratchouts in boys black restrooms | 7/19/2005 Medium | Dana Hamel Rudy Arreola | Restroom (Boys) | Gadsden MS |
| 3655 | Work In Progress paint the front columns of the school to remove tagging | 7/19/2005 Medium | Dana Hamel Rudy Arreola | | Gadsden MS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|---------------------------------------|-----------|-------------------------|
| 6424 | Work In Progress WE NEED LIGHTS IN THE BOYS & GIRLS RR IN MAIN BLDG, ALSO WE NEED THE LIGHTS IN HALLWAYS AS PER PM 6095. | 10/14/2005 Medium | Enrique Sotelo | | Gadsden MS |
| 5961 | Work In Progress please reomve and replaced stained ceiling tiles in Mr.Lowenburgs office. | 9/29/2005 Medium | Rudy Arreola | | Gadsden MS |
| 4095 | Work In Progress please fiill hole that is in front of entrance to band room. Will need a backking before gravel is applied. see mike | 8/2/2005 High | Rudy Arreola | | Gadsden MS |
| 7760 | Work In Progress Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Rudy Arreola | | Gadsden MS |
| 7716 | Work In Progress Kitchen - Need to shutdown gas and water service on Friday, 12/16/05 @ 1:00 pm. Route to Pancho, Spoke to him today 12/15/05 and he can do this. - M. Munoz | 12/1/2005 Medium | Alfredo Holguin Frank Lara | Cafeteria | La Mesa ES |
| 7526 | Work In Progress HVAC, JOSE NEED TO REPLACE GAS VALVE FOR CAFT AREA | 11/22/2005 Medium | Frank Lara Jose Ambriz | | La Mesa ES |
| 5309 | Work In Progress Milk Cooler was at 60 degrees this morning 9/7/05 | 9/7/2005 Medium | Alma Terrell Danny Orozco | Cafeteria | La Mesa ES |
| 5116 | Work In Progress cockroach problem Laura Benavidez - SNP Manager 233-2646 | 8/31/2005 Medium | Alma Terrell Margret Villalobos | Cafeteria | La Mesa ES |
| 4378 | Work In Progress locksmith need three keys for supply rm. key no F 49 8/23- Debra needs status on this work order submitted on 8/9/05 - mkv | 8/9/2005 Medium | Frank Lara Manny Lozoya | | La Mesa ES |
| 7832 | Work In Progress ALARM TO WALK-IN KEEPS GOINT OFF. LINDA YANAGA SNP MGR 589-2040 | 12/5/2005 Medium | Jacqueline Aguilar Danny Orozco | Cafeteria | La Union ES |
| 5447 | Work In Progress Student Cross Walk - Path on the west side there is a tree that is in the way. Students have to scoot over onto the street. | 9/12/2005 Medium | Margret Villalobos Alfredo Holguin | | La Union ES |
| 7234 | Work In Progress LJTP - Requesting 2 fire extinguishers. | 11/9/2005 Medium | Margret Villalobos Ruben Ronquillo | | La Union ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|---|--|-------------------------------------|------------------|---------------------------------|
| 3322 | Work In Progress Yearly - La Union ES Emer. Light Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Eddie Baeza | | La Union ES |
| 3572 | Work In Progress NEED LIGHT BULBS FOR RECESSED LIGHTS AT LA UNION ELEM. THE MAJORITY ARE BURNED OUT. THANK YOU. | 7/15/2005 Medium | Arturo Nunez Carlos Castillo | | La Union ES |
| 3344 | Work In Progress Yearly - La Union ES Exit Sign Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Eddie Baeza | | La Union ES |
| 8256 | Work In Progress Alvarez Farms ,panel needs main lug kit replaced | 12/22/2005 Medium | Carlos Castillo Carlos Castillo | Classroom | La Union ES |
| 4917 | Work In Progress please repair asphalt where other water line was repaired. | 8/25/2005 Medium | Michael Munoz | | La Union ES |
| 5312 | Work In Progress After last nights rainfall, leaks were discovered in rooms #208, #209, and the library. | 9/7/2005 Medium | Santos Galindo Lorenzo Solis | | La Union ES |
| 5117 | Work In Progress Lights in computer room keeps going out; breaker needs to be checked. | 8/31/2005 Medium | Santos Galindo Carlos Castillo | | La Union ES |
| 4825 | Work In Progress Need keys for room #100, #106, and room #108; plus keys for a file cabinet in the nurse's office. | 8/23/2005 Medium | Santos Galindo Manny Lozoya | | La Union ES |
| 4853 | Work In Progress SINK AT CUSTODIAL CLOSET AT OLD BLDG. IS CLOGGED UP. | 8/24/2005 Medium | Santos Galindo David Villalobos | | La Union ES |
| 5371 | Work In Progress In the women's restroom, in the southwing, the toilet is constantly flushy. | 9/9/2005 Medium | Santos Galindo Salvador Gonzalez | | La Union ES |
| 4372 | Work In Progress need a fan motor in electrical storage room. | 8/9/2005 Medium | Santos Galindo Jose Ambriz | | La Union ES |
| 4356 | Work In Progress in room 202 there is no outlet for refrigeration unit a.s.p. | 8/9/2005 Medium | Santos Galindo Carlos Castillo | | La Union ES |
| 4408 | Work In Progress a light next to my office need to be looked at cause it buzzes all day long. | 8/10/2005 Medium | Santos Galindo Carlos Castillo | | La Union ES |
| 4410 | Work In Progress They need to check lighting from building cause several lights are off. And some stay on 24 hrs out side. | 8/10/2005 Medium | Santos Galindo Carlos Castillo | | La Union ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|--------------------------------------|-----------|-------------------------|
| 4223 | Work In Progress need an electrical outlet by computer hookups room 203. | 8/5/2005 Medium | Santos Galindo Carlos Castillo | | La Union ES |
| 4775 | Work In Progress Parking lanes need to be repaint in yellow and bus lane also needs to be repaint but in red. Route to Sal Gonzalez as per Mike 9/13/05 -mkv | 8/22/2005 Medium | Santos Galindo Salvador Gonzalez | | La Union ES |
| 4695 | Work In Progress AUGUST 31 IS OPEN HOUSE WOULD LIKE ALL LIGHTS OUT SIDE TO BE CHECKED BEFORE THEN. | 8/19/2005 Medium | Santos Galindo Carlos Castillo | | La Union ES |
| 7550 | Work In Progress The roto machine that was rebuild starting smoking and it was the belt need to be replace. | 11/28/2005 Medium | Santos Galindo Jimmy Carbajal | | La Union ES |
| 7446 | Work In Progress would like hallway in old wing painted and frames. and new base trimming. | 11/18/2005 Medium | Santos Galindo Salvador Gonzalez | | La Union ES |
| 6403 | Work In Progress NEED CORK STRIP INFRONT OF THE OFFICE IN HALLAWAY. | 10/14/2005 Medium | Santos Galindo Ruben Ronquillo | | La Union ES |
| 6719 | Work In Progress need floor tile in lounge | 10/25/2005 Medium | Santos Galindo Michael Munoz | Office | La Union ES |
| 6718 | Work In Progress need electrical outlet on north wall | 10/25/2005 10/26/2005 Medium | Santos Galindo Carlos Castillo | Office | La Union ES |
| 6418 | Work In Progress Work Truck - need to repair broken tial-light. | 10/14/2005 Medium | Salvador Gonzalez Angel Gonzales | | La Union ES |
| 7391 | Work In Progress 11/15/05 To Caly. Relocate electrical outlet. | 11/15/2005 Medium | Salvador Gonzalez Carlos Castillo | | La Union ES |
| 7634 | Work In Progress 11/29/05 A furnace roof is not working cold air coming out. | 11/29/2005 Medium | Salvador Gonzalez Jose Ambriz | | La Union ES |
| 5503 | Work In Progress Old emergency light fixtures (the complete system) are not working can you check them please. thank you | 9/14/2005 Medium | Salvador Gonzalez Carlos Castillo | | La Union ES |
| 5786 | Work In Progress Upper hinge on door at JTP needs to be repair. Might need to be weld | 9/23/2005 Medium | Salvador Gonzalez Manny Lozoya | | La Union ES |
| 5949 | Work In Progress Music Room needs a new circuit installation. | 9/29/2005 Medium | Salvador Gonzalez Carlos Castillo | | La Union ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|---------------------------------------|-----------|-------------------------|
| 4864 | Work In Progress JTP- Rosaro Ruedas needs a L201 key. | 8/24/2005 Medium | Selma Nevarez Manny Lozoya | | La Union ES JTP |
| 5568 | Work In Progress As per Mike Munoz issue a 6 & 7 Grand Master keys to Mike Mc Dermott. | 9/16/2005 Medium | Manny Lozoya | | Loma Linda ES |
| 7763 | Work In Progress Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Michael Mc Dermott | | Loma Linda ES |
| 7796 | Work In Progress Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Michael Mc Dermott | | Loma Linda ES |
| 7805 | Work In Progress Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Michael Mc Dermott | | Loma Linda ES |
| 6686 | Work In Progress INSTALL ELECTRICAL CIRCUIT IN ROOM 208 FOR MICROWAVE AND FRIDGE. | 10/24/2005 Medium | Grace Alvarado Enrique Sotelo | | Loma Linda ES |
| 7361 | Work In Progress REPLACE TIMER FOR BOILER | 11/15/2005 Medium | Grace Alvarado Jose Ambriz | | Loma Linda ES |
| 7691 | Work In Progress TO: JOE AMBRIZ, REPAIR BOILER LINE IN MAIN HALLWAY , LEAKING. | 12/1/2005 Medium | Grace Alvarado Jose Ambriz | | Loma Linda ES |
| 8090 | Work In Progress ATTN: MIKE MUNOZ POUR SLAB FOR GARBAGE BINS AS TALKED ABOUT. | 12/13/2005 Medium | Grace Alvarado Michael Munoz | | Loma Linda ES |
| 8143 | Work In Progress MIKE INSTALL OUTLET IN BOOKROOM | 12/15/2005 Medium | Grace Alvarado Michael Mc Dermott | | Loma Linda ES |
| 3829 | Work In Progress MR. TRUJILLO IS WANTING NEW KEYS MADE FOR DESKS, CABINETTS AND FILE CABINETS. ALSO NEEDING NAME PLATE FOR NEW TEACHERS. MS. BERARD, CHAVEZ-FISHER, GRIEGO, DESANTIAGO, HUGHES, MARKHAM, MEDINA, MERRICK, MONTES, PINA, PRICE, RIOS-ALVILLAR, | 7/26/2005 Medium | Grace Alvarado Manny Lozoya | | Loma Linda ES |
| 4593 | Work In Progress MIKE MUNOZ, REPLACE EAST FENCE | 8/16/2005 Medium | Grace Alvarado Michael Munoz | | Loma Linda ES |
| 3345 | Work In Progress Yearly - Loma Linda ES Exit Sign Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Michael Mc Dermott | | Loma Linda ES |
| 3323 | Work In Progress Yearly - Loma Linda ES Emer. Light Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Michael Mc Dermott | | Loma Linda ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|---|----------------|-----------------------------|
| 5466 | Work In Progress attn; mike munoz- we need to have kitchen store room tiled with non slip tile like rest of kitchen. francis would really enjoy it. thank you. | 9/13/2005 Medium | Michael Mc Dermott Michael Munoz | Cafeteria | Loma Linda ES store room |
| 5284 | Work In Progress 9-6-5 TO MIKE MUNOZ. MR. T. NEEDS TO TALK WITH YOU ABOUT PUTTING A FENCE ALONG NORTH SIDE OF SCHOOL. K-3 KIDS ARE A CONCERN ABOUT GOING INTO VACANT AREA. THANK YOU. | 9/6/2005 Medium | Michael Mc Dermott Michael Munoz | Athletic Field | Loma Linda ES |
| 5283 | Work In Progress 9-6-5 attn; lupe b. mr. truillo at loma linda would like to meet with you about moving play ground equpt. to grass area. thank you. | 9/6/2005 Medium | Michael Mc Dermott Guadalupe Ontiveros | Athletic Field | Loma Linda ES |
| 6217 | Work In Progress NEED TO (PER ATTACHED DRAWING): 1. CUT CURB 2. DIG DIRT 4" 3. ADD CRUSH FINE / CEMENT 4. MOVE DUMPSTER INSIDE THE CURB | 10/10/2005 Medium | Michael Munoz Guadalupe Ontiveros | | Loma Linda ES |
| 5311 | Work In Progress A.S.A.P PLEASE NEED A CORD LESS DRILL , IF POSIBLE A TWO PACK BATTERIAS. (THANK YOU) | 9/7/2005 Medium | Luis Solis Aida Salcedo | | Loma Linda ES |
| 6538 | Work In Progress Need Ditch Witch delivered to Loma Linda tomorrow. | 10/18/2005 Medium | David Villalobos Angel Gonzales | | Loma Linda ES |
| 7190 | Work In Progress FLOOR TO WALK- IN NEEDS TO BE REPAIR. SNP STAFF ARE STILL TRIPPING ALICE F. SNP MGR 233-2341 | 11/8/2005 Medium | Jacqueline Aguilar Danny Orozco | Cafeteria | Mesquite ES |
| 7624 | Work In Progress need 8 sink faucets for restrms. in 2002 wing. defective. | 11/29/2005 Medium | Romauldo Apodaca Joe Ontiveros | | Mesquite ES |
| 6508 | Work In Progress jaime need to assist w/ boilers to change over to heating,also need gas valve for heater in old office.thanx. | 10/18/2005 Medium | Romauldo Apodaca Jaime Gomez | | Mesquite ES |
| 6507 | Work In Progress kiki, 5 rms w/ out lights need assistance.thanks. ARREGLAR PROBLEMA EN ALAMBRADO DE LUCES EN SALONES DE OLD WING. | 10/18/2005 10/18/2005 Medium | Romauldo Apodaca Romauldo Apodaca | | Mesquite ES |
| 6506 | Work In Progress david boyd.need 2 sets of plans for the 1995 addition,per ms. phillips and all hazard team.thank you. | 10/18/2005 Medium | Romauldo Apodaca David Boyd | | Mesquite ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|---|--|---|------------------|---------------------------------|
| 6509 | Work In Progress lupe ontiveros.need play sand for play structures and alma del valle.thanx. | 10/18/2005 Medium | Romauldo Apodaca Guadalupe Ontiveros | | Mesquite ES |
| 7825 | Work In Progress NEED TO RUN ELECTRICAL LINES TO MAIN FIELD FOR RED RIBBON CUTTING CEROMONY ON 12/8/05 AT 6:AM FOR HEATERS AND LIGHTING,PER MS. PHILLIPS. | 12/5/2005 Medium | Romauldo Apodaca Enrique Sotelo | | Mesquite ES |
| 4699 | Work In Progress manny need your assistance w/ doors that are hard to open and close. thanx. | 8/19/2005 Medium | Romauldo Apodaca Manny Lozoya | | Mesquite ES |
| 4340 | Work In Progress manny need to assist w/ 2 doors in porables having hard time tpo close safety issue. also need lever handle. | 8/9/2005 Medium | Romauldo Apodaca Manny Lozoya | | Mesquite ES |
| 3955 | Work In Progress DINING AREA - NEED TO WELD HINGES ON DOOR FALLING DOWN. | 7/29/2005 Medium | Romauldo Apodaca Manny Lozoya | | Mesquite ES |
| 3558 | Work In Progress need compresor changed out on armstrong unit in rm. 608.thanx. | 7/14/2005 Medium | Romauldo Apodaca Jaime Gomez | | Mesquite ES |
| 3346 | Work In Progress Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Romauldo Apodaca | | Mesquite ES |
| 3324 | Work In Progress Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Romauldo Apodaca | | Mesquite ES |
| 3971 | Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Romauldo Apodaca | | Mesquite ES |
| 4005 | Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Romauldo Apodaca | | Mesquite ES |
| 4015 | Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Romauldo Apodaca | | Mesquite ES |
| 4017 | Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Rudy Arreola | | Physical Plant Complex |
| 7772 | Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Rudy Arreola | | Physical Plant Complex |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|------------------------------------|-----------------|-------------------------|
| 5526 | Work In Progress NEED A "CB4" KEY FOR GUILLERMO - TO HAVE ACCESS TO ENERGY OFFICE TO CLEAN. | 9/15/2005 Medium | Manny Lozoya | | Physical Plant Complex |
| 8192 | Work In Progress please repair the following exterior lites.autoshop,south and east custodial,technology by purchasing warehouse,food sevice northside,gms annex southside,gms band room | 12/19/2005 Medium | Enrique Sotelo | | Physical Plant Complex |
| 7711 | Work In Progress please order all material needed to paint barracks in the back and let me know what staff will be need to accomplish the project. | 12/1/2005 Medium | Danny Miranda | Portables | Physical Plant Complex |
| 7810 | Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Rudy Arreola | | Physical Plant Complex |
| 7642 | Work In Progress Auto Shop - Need to install 4 cylinders all the same but different from main entrance. Need 4 keys issued (see Angel). | 11/30/2005 Medium | Angel Gonzales Manny Lozoya | | Physical Plant Complex |
| 3379 | Work In Progress Mens Restroom in Custodial Warehouse -Install new privacy lockset | 7/7/2005 Low | | Restroom (Boys) | Physical Plant Complex |
| 3380 | Work In Progress Mens Restroom in Custodial Warehouse- Replace toilet tank cover with appropriate size for unit. | 7/7/2005 Medium | Fred Appelzoller | Restroom (Boys) | Physical Plant Complex |
| 3461 | Work In Progress Need a copy of control key (core) to keep here at the Maintenance Dept - as per A. Holguin. | 7/12/2005 Medium | Alfredo Holguin Manny Lozoya | | Physical Plant Complex |
| 3186 | Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details. | 7/3/2005 Medium | Alfredo Holguin Rudy Arreola | | Physical Plant Complex |
| 5432 | Work In Progress Auto Shop - need to install new door knob to new door at Angel's Office. | 9/12/2005 Medium | Danny Miranda Manny Lozoya | | Physical Plant Complex |
| 4585 | Work In Progress Need to replace water heater,its giving out an extremeley bad odor.Health issue. | 8/16/2005 Medium | Carlos Castillo Joe Ontiveros | Electrical Room | Physical Plant Complex |
| 7967 | Work In Progress 12-7-05 ppd- daily o&m on wwtp me-5.5 clean out lift station and septic tank ppd-.5 fill in daily log 12/7 - 8 | 12/8/2005 Medium | Ricardo Jacquez Ricardo Jacquez | | Physical Plant Complex |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|--------------------------------------|-----------|---------------------------------------|
| 7377 | Work In Progress Light by fueling station is missing cover needs to be repalced. | 11/15/2005 Medium | Rudy Arreola Enrique Sotelo | | Physical Plant Complex Parking Lot |
| 7524 | Work In Progress NEED TWO WALL HANGING FILING CABINETS REINFORCED. THEY ARE CURRENTLY NOT VERY STURDY. (IN AIDAS OFFICE) | 11/22/2005 Medium | Maria Sitters Danny Miranda | | Physical Plant Complex |
| 5121 | Work In Progress Power Outage - El Paso Electric | 8/29/2005 Medium | Margret Villalobos Enrique Sotelo | | Physical Plant Complex |
| 3940 | Work In Progress MARTA JACQUEZ - A/C UNIT IS NOT WORKING AT ALL. | 7/29/2005 Medium | Marta Jacquez Jaime Gomez | | Physical Plant Complex |
| 7994 | Work In Progress Need to issue a key for Mary and Julie/Alfredo's office to Maritza. | 12/9/2005 High | Maritza Gonzalez Manny Lozoya | | Physical Plant Complex |
| 5735 | Work In Progress AS PER ALFREDO I NEED A COPY OF KEY TO CUSTODIAL OFFICE. THANK YOU. | 9/22/2005 Medium | Maritza Gonzalez Manny Lozoya | | Physical Plant Complex |
| 7834 | Work In Progress Need to make a key for D. Miranda's Office for Ruben. | 12/5/2005 Medium | Ruben Ronquillo Manny Lozoya | | Physical Plant Complex |
| 7659 | Work In Progress VEGETABLE SINK IS CLOGGED AGAIN. AND THERE IS NO HOT WATER AGAIN. NANCY ROLLIN RS SNP MGR 589-2550 | 11/30/2005 Medium | Jacqueline Aguilar Danny Orozco | Custodial | Riverside ES |
| 5609 | Work In Progress Having prolems with Roaches and Black insect (Ticks) in rooms and Hallways, Storage area etc.. could we have the Whole building extremitted during intersession. We have no students at this time. 10/11 - WAITING ON PURCHASE ORDER - MKV | 9/19/2005 Medium | Olga Arias Margret Villalobos | | Riverside ES |
| 5057 | Work In Progress We need a new Door Knob placed in the Data Clerk office. (office area) At this time the door doesn't lock. | 8/30/2005 Medium | Olga Arias Manny Lozoya | | Riverside ES |
| 5058 | Work In Progress Carpet (Doorway) to Data clerk office is coming loose. Plastic edge is picking-up.. Thanks | 8/30/2005 Medium | Olga Arias Michael Munoz | | Riverside ES |
| 3326 | Work In Progress Yearly - Riverside ES Emer. Light Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Adan Duran | | Riverside ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|-----------------------------------|-----------|-------------------------|
| 3348 | Work In Progress Yearly - Riverside ES Exit Sign Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Adan Duran | | Riverside ES |
| 3414 | Work In Progress MR LOZOYA MRS ARIAS IS HAVING TROUBLE WITH THE STORAGE ROOM LOCK WOULD LIKE FOR YOU TO LOOK AT IT THANK YOU SIR | 7/8/2005 Medium | Adan Duran Manny Lozoya | | Riverside ES |
| 3415 | Work In Progress MR JOSE AMBRIZ THE LITTLE ROOM WHERE WATER HEATER IS IN THE NEW WING IS GETTING HOT SETTING OFF ALARM NEED EXHUST FAN TO DRAW HEAT OUT THANK YOU SIR | 7/8/2005 Medium | Adan Duran Jose Ambriz | | Riverside ES |
| 3690 | Work In Progress MR MANNY LOZOYA FILE CABINET NEW PORTABLE RM B NEEDS REPAIR WILL NOT LOCK PARTS MISSING THANK YOU SIR | 7/19/2005 Medium | Adan Duran Manny Lozoya | | Riverside ES |
| 3778 | Work In Progress MR DAVID VILLALOBOS WE HAVE SOME LEAKING FUACTS NEW WING NEED REPAIR KIT OR REPLACEMENT THANK YOU SIR | 7/22/2005 Medium | Adan Duran David Villalobos | | Riverside ES |
| 4388 | Work In Progress MR JOSE AMBRIZ SIR WE NEED TO HOOK BACK UP THE AIR IN WHAT USE TO BE MRS FLORES OFFICE IT WAS REMOVE AT HER REQUEST AND ITS KIND OF WARM IN THERE THANK YOU SIR | 8/9/2005 Medium | Adan Duran Jose Ambriz | | Riverside ES |
| 4473 | Work In Progress MR MANNY LOZOYA SIR THE DOOR ON NEW PORTABLE IS STUCK IN LOCK CAN NOT GET IT TO UNLOCK PORTABLE B IN BACK THANK YOU SIR | 8/11/2005 Medium | Adan Duran Manny Lozoya | Portables | Riverside ES |
| 4596 | Work In Progress MR MANNY LOYZOA SIR NEED TO CHANGE OUT DOOR HANDLE BY MRS ARIAS OFFICE THE ONE THERE DO NOT LOCK NEED ONE THAT CAN BE LOCKED THANK YOU SIR | 8/16/2005 Medium | Adan Duran Manny Lozoya | | Riverside ES |
| 5115 | Work In Progress MR LUPE ONTIVEROS SIR WILL NEED THE USE OF THE BACKHOE TO MOVE SOCCOR GOAL POST AWAY FROM PARKING AREA UNSAFE FOR KIDS THANK YOU SIR | 8/31/2005 Medium | Adan Duran Guadalupe Ontiveros | | Riverside ES |
| 6559 | Work In Progress MR CARLOS CASTILLO MR CASTILLO THE LIGHTS ON THE OUT SIDE NORTH EAST SIDE ARE OUT NEED TO REPLACE VERY DARK ON THAT SIDE THANK YOU SIR | 10/19/2005 Medium | Adan Duran Carlos Castillo | | Riverside ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|-------------------------------|-----------|-------------------------|
| 7156 | Work In Progress 11/7/05 1/2 SIGN IN CHECK SCHOOL GROUNDS 2 1/2 MOWED GRASS 1 1/2 EDGE WITH TRIMER 1 CLEAN SIDEWALKS WITH BLOWER 1 REPAIR ENTRANCE DOOR WILL NOT CLOSE 1/2 CLOSE WEST AND DROP OFF GATES 1 FILE PAPER WORK AND SIGN OUT 11/7 - 8 | 11/7/2005 Medium | Adan Duran Adan Duran | | Riverside ES |
| 7415 | Work In Progress MR CARLOS CASTILLO SIR NEED LIGHT BULBS FOR BATHROOM THEN ARE U SHAPE 22" LONG BY 7" WIDE OUT SIDE TO OUT SIDE THANK YOU SIR | 11/16/2005 Medium | Adan Duran Carlos Castillo | | Riverside ES |
| 7505 | Work In Progress MR CASTILLO SIR WILL NEED TO REPLACE BELAST BOYS BATH ROOM LOWER GRADE BY OFFICE THANK YOU SIR | 11/21/2005 Medium | Adan Duran Carlos Castillo | | Riverside ES |
| 8225 | Work In Progress 12/20/05 1/2 SIGN IN CHECK SCHOOL GROUNDS 6 PAINT BATHROOMS 1/2 WASH ROLLERS AND PAINT BRUSH AND PAN 1 FILE PAPER WORK AND SIGN OUT 12/20 - 8 | 12/20/2005 Medium | Adan Duran Adan Duran | | Riverside ES |
| 8056 | Work In Progress MR CARLOS CASTILLO SIR WILL NEED TO CHANGE BELAST BOYS BATHROOM ACROSS FROM OFFICE NO LIGHT THANK YOU SIR | 12/12/2005 Medium | Adan Duran Carlos Castillo | | Riverside ES |
| 5592 | Work In Progress please see what can be done to repair or remove electrical outlet on floor on serving line. Outlet has a can over it and could be a trip hazard. | 9/19/2005 Medium | Danny Orozco | Cafeteria | Riverside ES |
| 6956 | Work In Progress please provide sidewalk to portable that was moved in this summer. | 11/2/2005 Medium | Michael Munoz | | Riverside ES |
| 6954 | Work In Progress please provide side walks to the last 2 portables that where moved in. rms 50&51 | 11/2/2005 Medium | Michael Munoz | Portables | San Miguel ES |
| 6955 | Work In Progress please provide concrete landing and sidewalk to portable 51 | 11/2/2005 Medium | Michael Munoz | Portables | San Miguel ES |
| 7632 | Work In Progress The backflow prevention device on the irrigation distribution system needs to have the annual inspection performed. | 11/29/2005 Medium | Guadalupe Ontiveros | | San Miguel ES |
| 7813 | Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Danny Vega | | San Miguel ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|--|--|----------------------------------|------------------|---------------------------------|
| 7766 | Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Danny Vega | | San Miguel ES |
| 7117 | Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Danny Vega | | San Miguel ES |
| 7801 | Work In Progress Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Danny Vega | | San Miguel ES |
| 7070 | Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Danny Vega | | San Miguel ES |
| 7105 | Work In Progress Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Danny Vega | | San Miguel ES |
| 3175 | Work In Progress Monthly - San Miguel ES Roof Inpsection - Refer to PM schedule details. | 7/3/2005 Medium | Alfredo Holguin Danny Vega | | San Miguel ES |
| 4489 | Work In Progress Need an extra key for these rooms. | 8/11/2005 Medium | Barbara Cardenas Manny Lozoya | Classroom | San Miguel ES 25, 49,50 |
| 6301 | Work In Progress need additional ventilation in cafeteria/exhaust | 10/11/2005 Medium | Danny Vega Jaime Gomez | | San Miguel ES |
| 6367 | Work In Progress rm#32 day&night type furnance/pilot wont stay on-needs thermo-couple | 10/13/2005 Medium | Danny Vega Jaime Gomez | | San Miguel ES |
| 5270 | Work In Progress NEED LDO 2QT/FLUSH VALVE KIT/DIAPRAHMS/TUB&SINK SEALER/ELONGATED TIOLET SEAT | 9/6/2005 Medium | Danny Vega Joe Ontiveros | | San Miguel ES |
| 5315 | Work In Progress need replacement faucets for double sinks /kitchen .please stop by asap/ | 9/7/2005 Medium | Danny Vega Danny Orozco | Cafeteria | San Miguel ES |
| 5307 | Work In Progress portable #28 refrig unit not cooling/please check it out asap | 9/7/2005 Medium | Danny Vega Jaime Gomez | | San Miguel ES |
| 5177 | Work In Progress NEED FILTERS 12X24X1 | 9/2/2005 Medium | Danny Vega Jaime Gomez | | San Miguel ES |
| 5176 | Work In Progress CAFETERIA GIRLS RR/SINK FAUCET BROKEN - OFF /PLEASE REPLACE/HOT-COLD TYPE | 9/2/2005 Medium | Danny Vega Joe Ontiveros | | San Miguel ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|-----------------------------------|-----------|-------------------------|
| 4445 | Work In Progress Portable 29 - Needs to be secured by the end of the day. | 8/10/2005 Medium | Danny Vega Manny Lozoya | Portables | San Miguel ES |
| 4447 | Work In Progress principals office door hard to open/door needs to be shaved.stop by asap | 8/10/2005 Medium | Danny Vega Manny Lozoya | | San Miguel ES |
| 3834 | Work In Progress A/C UNIT NOT WORKING IN HIGH SPEED PORTABLE#58 | 7/26/2005 Medium | Danny Vega Jaime Gomez | | San Miguel ES |
| 4051 | Work In Progress portable #30/rheem a/c unit not woking.stop by asap | 8/1/2005 Medium | Danny Vega Jaime Gomez | | San Miguel ES |
| 8140 | Work In Progress need additional outlets rm#17 asap/computer rm | 12/15/2005 Medium | Danny Vega Enrique Sotelo | | San Miguel ES |
| 8082 | Work In Progress library toilet will not flush/we need to replace it | 12/13/2005 Medium | Danny Vega Joe Ontiveros | | San Miguel ES |
| 8007 | Work In Progress need one set gates wheels /west gate wheels damaged /asap(ruben ronquillo) | 12/12/2005 Medium | Danny Vega Ruben Ronquillo | | San Miguel ES |
| 7563 | Work In Progress boys restroom heater coil leaks water/need replaced asap found leak and repaired it | 11/28/2005 12/1/2005 Medium | Danny Vega Lorenzo Solis | | San Miguel ES |
| 7173 | Work In Progress PARKING LOT SECURITY LIGHT IS ON DAY&NIGHT/SENSOR IS NOT WORKING/WEST PARKING LOT. | 11/8/2005 Medium | Danny Vega Enrique Sotelo | | San Miguel ES |
| 6785 | Work In Progress boiler is not heating/please ck it out/class rooms are cold in the morning | 10/26/2005 Medium | Danny Vega Jaime Gomez | | San Miguel ES |
| 6618 | Work In Progress need two loads playground sand asap | 10/21/2005 Medium | Danny Vega Guadalupe Ontiveros | | San Miguel ES |
| 6617 | Work In Progress j.gomez/need to start and go thru check list on boiler unit/before 10-28-05 (.you can do it) | 10/21/2005 Medium | Danny Vega Jaime Gomez | | San Miguel ES |
| 6584 | Work In Progress NEED LOCK-OUT DEVICE FOR DISCONNECT BOX/PORTABLE 28-29/POWER SHUT-OFF DAILY-ASAP | 10/20/2005 Medium | Danny Vega Enrique Sotelo | | San Miguel ES |
| 7015 | Work In Progress Need backflow tested on irrigation system thanks | 11/4/2005 Medium | Ricardo Jacquez Joe Ontiveros | | San Miguel ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|--|-----------|-------------------------|
| 5337 | Work In Progress DISHWASHER LEAKING WATER. EVA MIRANDA - 233-2860 | 9/8/2005 Medium | Jacqueline Aguilar Danny Orozco | Cafeteria | San Miguel ES |
| 7951 | Work In Progress Wing A - Rooms 102, 105, 107, 108 and in Wing C - Conf. Room and Room 310 units are freezing up/low pressure. | 12/8/2005 Medium | Jose Ambriz Jose Ambriz | | Santa Teresa ES |
| 7323 | Work In Progress Need to check Lounge and Admin. Office Units. Have to reset units manually everyday. (Jose Ambriz informed Renee of problem). Please send someone out to check these. - Thanks | 11/14/2005 Medium | Jose Ambriz Margret Villalobos | | Santa Teresa ES |
| 7560 | Work In Progress RISERS NEED TO BE PICKED UP FROM STHS (FOR OUR CHRISTMAS PROGRAM) ON 12/13/05 AND RETURNED BACK TO STHS ON 12/16/05. | 11/28/2005 Medium | Rita Mendez Gerardo Marquez | | Santa Teresa ES |
| 3657 | Work In Progress ATTN. Manny . NEED FOR YOU TO DUPLICATE A KEY TO THE MAIL BOX . THANKS . | 7/19/2005 Medium | Gerardo Marquez Manny Lozoya | | Santa Teresa ES |
| 4152 | Work In Progress ATTN MANNY. MANNY, WE STILL NEED FOR YOU TO MAKE US ANOTHER KEY TO THE MAIL BOX. THANKS. | 8/3/2005 Medium | Gerardo Marquez Manny Lozoya | | Santa Teresa ES |
| 4154 | Work In Progress ATTN LUPE, LUPE, WE STILL NEED THE COBBLESTONE TO KEEP CHECK THE RAIN ERROSION. ALSO NEED FOR BETO AND MANNY TO REDIG TRENCH AT BACK FENCE TO KEEP RAIN FROM FLOODING GROUNDS AND CLASS RMS. | 8/3/2005 Medium | Gerardo Marquez Guadalupe Ontiveros | | Santa Teresa ES |
| 7297 | Work In Progress 11/8/05 8-ATTENDED LCN DOOR CLOSER WK. SHOP. 11/8 - 8 | 11/11/2005 Medium | Gerardo Marquez Gerardo Marquez | | Santa Teresa ES |
| 6450 | Work In Progress 10/3/05 1-insp. bldg.and grnds. picked up trash. 1-tried to fix broken stop sign at bus pick up exit. 1-fixed bus exit gate. (was knocked down over the wk. end) 4-mowed grass. 10/3 - 7 | 10/17/2005 Medium | Gerardo Marquez Gerardo Marquez | | Santa Teresa ES |
| 3958 | Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Gerardo Marquez | | Santa Teresa ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|---|--|------------------------------------|------------------|---------------------------------|
| 4021 | Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Gerardo Marquez | | Santa Teresa ES |
| 4009 | Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Gerardo Marquez | | Santa Teresa ES |
| 7802 | Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Gerardo Marquez | | Santa Teresa ES |
| 7751 | Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Gerardo Marquez | | Santa Teresa ES |
| 7814 | Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Gerardo Marquez | | Santa Teresa ES |
| 7815 | Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Joel Herrera | | Santa Teresa HS |
| 4484 | Work In Progress please install venting system and exhaust hood in the metal shop. See Joe Angelo. | 8/11/2005 Medium | Jose Ambriz | | Santa Teresa HS |
| 7119 | Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Joel Herrera | | Santa Teresa HS |
| 7767 | Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Arturo Nunez | | Santa Teresa HS |
| 7804 | Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Joel Herrera | | Santa Teresa HS |
| 7773 | Work In Progress Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Danny Orozco | | Santa Teresa HS |
| 6036 | Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details. | 10/2/2005 Medium | Alfredo Holguin Arturo Nunez | | Santa Teresa HS |
| 6018 | Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details. | 10/2/2005 Medium | Alfredo Holguin Arturo Nunez | | Santa Teresa HS |
| 7108 | Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Joel Herrera | | Santa Teresa HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|------------------------------------|-----------|-------------------------|
| 7071 | Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Arturo Nunez | | Santa Teresa HS |
| 5214 | Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details. | 9/4/2005 Medium | Alfredo Holguin Arturo Nunez | | Santa Teresa HS |
| 6118 | Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details. | 10/2/2005 Medium | Alfredo Holguin Joel Herrera | | Santa Teresa HS |
| 6107 | Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details. | 10/2/2005 Medium | Alfredo Holguin Joel Herrera | | Santa Teresa HS |
| 3176 | Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details. | 7/3/2005 Medium | Alfredo Holguin Arturo Nunez | | Santa Teresa HS |
| 3351 | Work In Progress Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Arturo Nunez | | Santa Teresa HS |
| 3158 | Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details. | 7/3/2005 Medium | Alfredo Holguin Arturo Nunez | | Santa Teresa HS |
| 3329 | Work In Progress Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Arturo Nunez | | Santa Teresa HS |
| 7991 | Work In Progress Student leaned against glass shield on serving line and glass broke. Needs to be replaced immediately. Olga Bustamante - SNP Manager (No Phone Service Yet) | 12/9/2005 Medium | Alma Terrell Danny Orozco | Cafeteria | Santa Teresa HS |
| 3571 | Work In Progress NEED CONDENSER MTR. FOR SNACK ROOM A.C. UNIT, MTR. IS FROZEN UNIT IS DOWN. | 7/15/2005 Medium | Arturo Nunez Jose Ambriz | | Santa Teresa HS |
| 4465 | Work In Progress NEED 1/4 INCH GAS VALVE TO PILOT , ON BOILER #1 ON NEW SYSTEM REPLACED, LEAKING REAL BAD, | 8/11/2005 Medium | Arturo Nunez David Villalobos | | Santa Teresa HS |
| 4346 | Work In Progress NEED TO FUMIGATE VOC. SHOPS TO MANNY CRIKETS, ANTS, ETC,ETC. | 8/9/2005 Medium | Arturo Nunez Margret Villalobos | | Santa Teresa HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|---------------------------------------|------------------|-------------------------|
| 7342 | Work In Progress NEED A FIFTY (50) GALLON WATER HEATER, TO REPLACE THE ONE AT CUSTODIAL CLOSET, IT IS LEAKING REAL BAD, AND WE HAD TO SHUT DOWN, RED TAG. CUSTODIANS NEED THE HOT WATER. | 11/14/2005 Medium | Arturo Nunez David Villalobos | | Santa Teresa HS |
| 7169 | Work In Progress NEED FOUR (4) EA. ALLEN-BRADEY CONTROL RELAY BULLETIN 700, TYPE H, CAT #700- HHF73A1, SER A . HAVE SAMPLE WITH ME IF YOU NEED MORE INFO. THIS ARE GOING TO GYM BLEACHERS. THANK YOU. | 11/7/2005 Medium | Arturo Nunez Carlos Castillo | | Santa Teresa HS |
| 7164 | Work In Progress NEED SOME SOURCE OF HEAT FOR SECURITY GUARD SHACK, BEING PORTABLE, OR PERMANENTLY INSTALLED. THANK YOU. | 11/7/2005 Medium | Arturo Nunez Jose Ambriz | | Santa Teresa HS |
| 6927 | Work In Progress NEED A SET OF BROUNING GRIP NOTCH V BELTS. #5VX840, 358, FOR NEW AIR HANDLER UNIT AT LIBRARY. | 11/1/2005 Medium | Arturo Nunez Jose Ambriz | | Santa Teresa HS |
| 7840 | Work In Progress NEED FIVE (5) LOCKS 6" SLIDE LOCKING HASP | 12/5/2005 Medium | Arturo Nunez Manny Lozoya | | Santa Teresa HS |
| 7841 | Work In Progress MOTOR- GOULD CENTURY M/R PA/T 8-159589- 01 R P.M. 1725 F / ANE LA 56H VOLTS 208- 230/ 460 3PHASE CAT H 535 . | 12/5/2005 Medium | Arturo Nunez Jose Ambriz | | Santa Teresa HS |
| 8013 | Work In Progress NEED ASSISTANCE ON REPLACING BROKEN LIGHT BULB BY FOOTBALL CONSESSION STAND, WILL NEED BUCKET TRUCK TO REPLACE LIGHT BULB. THANK YOU. | 12/12/2005 Medium | Arturo Nunez Carlos Castillo | | Santa Teresa HS |
| 7172 | Work In Progress ADULT RESTROOM IN OFFICE AREA. NEED TO CLEAN, DO FLOORS AND REPLACE SOAP DISPENSOR. | 11/8/2005 Medium | Aida Salcedo Luis Murillo | | Santa Teresa HS |
| 7194 | Work In Progress ADULT RESTROOM IN OFFICE AREA NEEDS TO BE PAINTED. | 11/8/2005 Medium | Aida Salcedo Arturo Nunez | | Santa Teresa HS |
| 8019 | Work In Progress Need to replace several locking switches | 12/12/2005 Medium | Carlos Castillo Carlos Castillo | Hallway/Corridor | Santa Teresa HS |
| 8147 | Work In Progress Softball coach requesting to check pitching machines | 12/15/2005 Medium | Carlos Castillo Margret Villalobos | Athletic Field | Santa Teresa HS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|-------------------------------------|-----------|-------------------------|
| 6519 | Work In Progress NEED 4-PR*S OF BLACK RUBBER BOOTS FOR SCRUBBING FLOORS SIZES 11, 7, 7, N 9 THANK YOU GUILLERMO. | 10/18/2005 Medium | Luis Murillo Guillermo Hernandez | | Santa Teresa HS |
| 7828 | Work In Progress ROYAL VACUUM CLEANER SERIAL *EOO6O00004074 IS MAKEING A REAL LAOUD NOISE WHEN TURN ON NEEDS TO BE CHECKED OUT THANK YOU. | 12/5/2005 Medium | Luis Murillo Jimmy Carbajal | | Santa Teresa HS |
| 5102 | Work In Progress WE NEED REPLACE MA 51 AND TREE LOCKS AT R.O.T.C CLASS ROOMS. | 8/30/2005 Medium | Joel Herrera Manny Lozoya | | Santa Teresa HS |
| 4807 | Work In Progress MANNY MY MASTER KEY IS BROKEN IT DOESN'T WORK NO MORE. | 8/23/2005 Medium | Joel Herrera Manny Lozoya | | Santa Teresa HS |
| 4966 | Work In Progress RUBEN WE NEED REPAIR THE WINDOWS AT DAYCAREBUILDING IT DOESN'T OPEN THANK YOU Route to Joel as per Mike 9/12/05 - mkv | 8/26/2005 Medium | Joel Herrera Joel Herrera | | Santa Teresa HS |
| 5923 | Work In Progress MIKE MUNOZ WE NEED BARRIER FENCE ON WEST SIDE AT SOCCER FIELD TO RETAIN BALLS OUT IT PLAY . ALSO NEED FENCE FROM 20 YARD LINE TO 20 YARD LINE IN FRONT OF FOOTBALL VISITORS SEATING AREA. SEE R GALLEGOS THANK YOU MIKE... | 9/28/2005 Medium | Joel Herrera Michael Munoz | | Santa Teresa HS |
| 4454 | Work In Progress SMASHED WINDOW ON DOOR - STOLEN LARGE SCREEN TV. DISCOVERED BY MR. BUCKLEY | 8/1/2005 Medium | Joel Herrera Ruben Ronquillo | | Santa Teresa HS |
| 4463 | Work In Progress SENER ON SINCK AT GIRLS REST ROOM IT DOESN'T WORK WE REPLACE IT . | 8/11/2005 Medium | Joel Herrera David Villalobos | | Santa Teresa HS |
| 5113 | Work In Progress AIR CONDITIONER DOES NOT TURN ON THE LEFT SIDE OF THE ROOM FACING CHALK BOARD ROOM 3 MR. DORANTES | 8/31/2005 Medium | Laura Parra Jose Ambriz | Classroom | Santa Teresa MS |
| 3412 | Work In Progress S.bldg upper level. Because of the shortage of classrooms Mrs. williams has to move the teachers lounge to a storage rm. The floor has no tile, can you include this room with the area's that the contractor will be installing floor tile. Attn: Alfredo holguin. | 7/8/2005 Medium | Jaime Mijarez Michael Munoz | | Santa Teresa MS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|--------------------------------------|-----------|-------------------------|
| 3387 | Work In Progress Rm 1. N. bldg lower level Removal of carpet is going to require tile installation. Alfredo H. requested a work order for contractor. | 7/7/2005 Medium | Jaime Mijarez Michael Munoz | | Santa Teresa MS |
| 3364 | Work In Progress S.bldg custodial storage. please make 2ea. A-7 keys for principal and building mechanic. | 7/6/2005 Medium | Jaime Mijarez Manny Lozoya | | Santa Teresa MS |
| 3465 | Work In Progress N.bldg home ec rm 10. Ruben Ronquillo I am going to need a Miter saw to cut legs on ten of the tables. please make sure it has a good blade. I am planning this project for next week (7/18/05.) The wood is oak. | 7/12/2005 Medium | Jaime Mijarez Ruben Ronquillo | | Santa Teresa MS |
| 6321 | Work In Progress Second Request. Mrs. williams wants to know status on broken urinal at S.bldg lower level boys restroom by ramp. | 10/12/2005 Medium | Jaime Mijarez David Villalobos | | Santa Teresa MS |
| 5363 | Work In Progress N.bldg maintenance and custodial. Would like a duct and register installed on heat pump. | 9/9/2005 Medium | Jaime Mijarez Jose Ambriz | | Santa Teresa MS |
| 5304 | Work In Progress School bldgs. Bldgs need to be fumigated for stink bugs, scorpions,and other insects. Also mice traps need to be placed cause mice are being seen just about everywhere. On hold for additional budget - as per A. Holguin 9/8/05 -mkv emailed - J. Mijarez | 9/6/2005 Medium | Jaime Mijarez Margret Villalobos | | Santa Teresa MS |
| 5149 | Work In Progress N.bldg Rm 3. Mrs. williams would like to have a sidewalk that goes from Rm 3 exit door out to the fence. This way when there is a fire drill the special ed students on wheel chairs can be moved away from the building in case of an actual emergency. | 9/1/2005 Medium | Jaime Mijarez Michael Munoz | | Santa Teresa MS |
| 8160 | Work In Progress Markee Sign. As per Mrs. Williams she would like to have the sign installed during the winter break. | 12/15/2005 Medium | Jaime Mijarez Guadalupe Ontiveros | | Santa Teresa MS |
| 8159 | Work In Progress Markee Sign. As per Mrs. Williams she would like to have the sign installed during winter break. | 12/15/2005 Medium | Jaime Mijarez Carlos Castillo | | Santa Teresa MS |
| 8161 | Work In Progress Principals office. Need a window installed on interior door. | 12/15/2005 Medium | Jaime Mijarez Danny Miranda | | Santa Teresa MS |
| 7470 | Work In Progress Heat Pumps. Can you order ten time delay timers. ICM PART #ICM102 DELAY ON MAKE TIMER. | 11/18/2005 Medium | Jaime Mijarez Jose Ambriz | | Santa Teresa MS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|--|---|--------------------------------------|-----------------|-------------------------|
| 7471 | Work In Progress Cafeteria. Need to replace all the light bulbs. Lighting is very dim and some are burned out. | 11/18/2005 Medium | Jaime Mijarez Carlos Castillo | | Santa Teresa MS |
| 7902 | Work In Progress WALK - IN IS NOT COOLING. PAULA S. SNP MGR 589-9836 | 12/7/2005 Medium | Jacqueline Aguilar Danny Orozco | Cafeteria | Santa Teresa MS |
| 5308 | Work In Progress I NEED A KEY A7 FOR THE PRINCIPAL TO HAVE ACCESS TO MY STORAGE ROOM. THANK YOU.SEE MR. RODRIGUEZ. | 9/7/2005 Medium | Ismael Rodriguez Manny Lozoya | Custodial | Santa Teresa MS |
| 4641 | Work In Progress THERE A BOYS URINAL THAT IS CRACK FROM THE BOTTOM AND EVERY TIME THEY FLUSH IT WATER COMES OUT.SEE MR. RODRIGUEZ. | 8/17/2005 Medium | Ismael Rodriguez David Villalobos | Restroom (Boys) | Santa Teresa MS |
| 8104 | Work In Progress JIMMEY I NEED 4 PAIRS OF LEATHER GLOVES FOR THE CUSTODIANS THE REASON IS WHEN WE DO WORK OUTSIDE THE BUILDINGS.THANK YOU. | 12/14/2005 Medium | Ismael Rodriguez Aida Salcedo | Custodial | Santa Teresa MS |
| 7823 | Work In Progress JIMMEY I AM GOING TO NEED THE EXTRACTER WITH THE WOND FOR THE CRISTMAS BREAK.THANK YOU. | 12/5/2005 Medium | Ismael Rodriguez Jimmy Carbajal | Office | Santa Teresa MS |
| 3118 | Work In Progress I NEED FOR GYM KEY CYLINDERS TOO TO BE CHANGE BEFORE 7/13/05.CONT.MR.RODRIGUEZ. | 7/1/2005 Medium | Ismael Rodriguez Manny Lozoya | | Santa Teresa MS |
| 6218 | Work In Progress DUE TO WATER OVER FLOW, GYM FLOOR HAS BUBBLED BY FLOODING. NEED VENDOR TO DO A RECOMMENDATION AND QUOTE US. | 10/10/2005 Medium | Aida Salcedo Michael Munoz | | Santa Teresa MS |
| 3330 | Work In Progress Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Jaime Mijarez | | Santa Teresa MS |
| 3353 | Work In Progress Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Jaime Mijarez | | Santa Teresa MS |
| 3975 | Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Jaime Mijarez | | Santa Teresa MS |
| 7072 | Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Jaime Mijarez | | Santa Teresa MS |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|---|--|-----------------------------------|------------------|---------------------------------|
| 4023 | Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Jaime Mijarez | | Santa Teresa MS |
| 4013 | Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details. | 7/31/2005 Medium | Alfredo Holguin Jaime Mijarez | | Santa Teresa MS |
| 7768 | Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Jaime Mijarez | | Santa Teresa MS |
| 7110 | Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Jaime Mijarez | | Santa Teresa MS |
| 7120 | Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details. | 11/6/2005 Medium | Alfredo Holguin Jaime Mijarez | | Santa Teresa MS |
| 6437 | Work In Progress please replace h20 fountain and unclog drain. | 10/14/2005 Medium | David Villalobos | Office | Santa Teresa MS |
| 6957 | Work In Progress please provide a landing and side walk to portable that was delivered this summer & also provide a sidewalk from bldg to existing side walk | 11/2/2005 Medium | Michael Munoz | | Santa Teresa MS |
| 7816 | Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Jaime Mijarez | | Santa Teresa MS |
| 7806 | Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Jaime Mijarez | | Santa Teresa MS |
| 3423 | Work In Progress Yearly - Sunland Park ES Emer. Light Test: Annual - Refer to PM schedule details. | 7/10/2005 Medium | Alfredo Holguin Sebastian Diaz | | Sunland Park ES |
| 3278 | Work In Progress Monthly - Sunland Park ES Exit Sign Insp. - Refer to PM schedule details. | 7/3/2005 Medium | Alfredo Holguin Sebastian Diaz | | Sunland Park ES |
| 3268 | Work In Progress Monthly - Sunland Park ES Emergency Lighting Insp. - Refer to PM schedule details. | 7/3/2005 Medium | Alfredo Holguin Sebastian Diaz | | Sunland Park ES |
| 3179 | Work In Progress Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details. | 7/3/2005 Medium | Alfredo Holguin Sebastian Diaz | | Sunland Park ES |
| 3160 | Work In Progress Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details. | 7/3/2005 Medium | Alfredo Holguin Sebastian Diaz | | Sunland Park ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|---------------------------------------|-----------|-------------------------|
| 3355 | Work In Progress Yearly - Sunland Park ES Exit Sign Test: Annual - Refer to PM schedule details. | 7/6/2005 Medium | Alfredo Holguin Sebastian Diaz | | Sunland Park ES |
| 7262 | Work In Progress Problems with bottom left Blodgett Oven Serving Line - Left Side- Cold Area not cooling Marina Ramirez - SNP Manager - 589-3439 | 11/10/2005 Medium | Alma Terrell Danny Orozco | Cafeteria | Sunland Park ES |
| 7523 | Work In Progress Please remove carpet in room #52 and install floor tile. | 11/22/2005 Medium | Irene Trujillo Michael Munoz | | Sunland Park ES |
| 7522 | Work In Progress A kitchen sink is needed in room 52. The new teacher's lounge. | 11/22/2005 Medium | Irene Trujillo David Villalobos | | Sunland Park ES |
| 7041 | Work In Progress A door opening is needed from lounge to existing bathroom in nurse's office. Please send someone to check wiring. | 11/4/2005 Medium | Irene Trujillo Carlos Castillo | | Sunland Park ES |
| 7042 | Work In Progress A door opening is needed to connect lounge to existing bathroom in nurse's office. Please send someone to check the plumbing of sink, etc. | 11/4/2005 Medium | Irene Trujillo David Villalobos | | Sunland Park ES |
| 6878 | Work In Progress ADD NEW ELECTRICAL OUTLET TO TEACHER'S LOUNGE. | 10/31/2005 Medium | Irene Trujillo Carlos Castillo | | Sunland Park ES |
| 6727 | Work In Progress Roaches in classroom #25. | 10/25/2005 Medium | Irene Trujillo Margret Villalobos | | Sunland Park ES |
| 6465 | Work In Progress THE GROUNDS NEED TO BE SMOOTHED OUT AFTER THE RAIN. THE SAND WAS WASHED AWAY IN SOME AREAS. | 10/17/2005 Medium | Irene Trujillo Guadalupe Ontiveros | | Sunland Park ES |
| 4868 | Work In Progress BLACK WIDOW SPIDERS, SCORPIONS, ETC. HAVE BEEN FOUND IN THE CLASSROOMS, PLAYGROUND, AND HALLS OF THIS SCHOOL. PLEASE SEND SOMEONE TO SPRAY. FAXED PO 9/1/05 | 8/24/2005 Medium | Irene Trujillo Margret Villalobos | | Sunland Park ES |
| 3875 | Work In Progress NEED REPLACEMENT KEYS FOR NURSE'S OFFICE DORR AND FILE CABINET | 7/27/2005 Medium | Irene Trujillo Manny Lozoya | | Sunland Park ES |
| 5687 | Work In Progress We have a mice problem throughout the school. Please help! | 9/21/2005 Medium | Irene Trujillo Margret Villalobos | | Sunland Park ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|---------------------------------------|-----------|-------------------------|
| 5422 | Work In Progress NEED TO REMOVED DEAD TREES. | 9/12/2005 Medium | Irene Trujillo Guadalupe Ontiveros | | Sunland Park ES |
| 7903 | Work In Progress WALK - IN TEMP. IS AT 45. MARINA R. SNP MGR 589-2545 | 12/7/2005 Medium | Jacqueline Aguilar Danny Orozco | Cafeteria | Sunland Park ES |
| 6625 | Work In Progress Need Heavy Duty Dolly for fire proof file cabinet on Monday October 24, 2005 | 10/21/2005 Medium | Larry Flores Maria Sitters | | Sunland Park ES |
| 8041 | Work In Progress Portable A - Broken window 30 x 28 Double Glass. Est. Damage 125.00 | 12/1/2005 Medium | Sebastian Diaz Ruben Ronquillo | Portables | Sunland Park ES |
| 6692 | Work In Progress Need 4 metal blinds for portable F 46"X 52" thank you. | 10/24/2005 Medium | Sebastian Diaz Ruben Ronquillo | | Sunland Park ES |
| 7029 | Work In Progress The sink in the room 41 is clog need to bring the snake also need to replace the fauset thank you | 11/4/2005 Medium | Sebastian Diaz David Villalobos | | Sunland Park ES |
| 5195 | Work In Progress 9/2/05 Lupe Ontiveros Need the heavy tractor to remove the weeds around the school thank you | 9/2/2005 Medium | Sebastian Diaz Guadalupe Ontiveros | | Sunland Park ES |
| 3533 | Work In Progress Could you turn the air conditioning on we have teachers coming in to get a head start on their rooms. It is very hot and we would greatly appreciate it. Since we are a year round school the teachers need to report on Monday. Thank-you | 7/14/2005 Medium | Joanne Munoz Jaime Gomez | Classroom | Sunrise ES |
| 6781 | Work In Progress REQUESTING SEAL KITS ,AND GASKETS.FOR CIRCULATING PUMPS GEO THERMAL UNITS. UNIT LEAKING FROM SEAL RM.210 | 10/26/2005 Medium | Paul Quinones Jaime Gomez | | Sunrise ES |
| 6782 | Work In Progress STERLING HEATING UNIT IN KITCHEN AREA.WILL NOT TURN ON ,MIXED AIR CONTROL NOT WORKING PROPERLY | 10/26/2005 Medium | Paul Quinones Jaime Gomez | | Sunrise ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|------|---|---|-------------------------------------|-----------|-------------------------|
| 6449 | Work In Progress 10-14-05 2.0,REMOVE SAND GRAVEL FROM BACK SIDEWALK ENTRANCE 4.5,ASSIST ENRIQUE W/ELECTRICAL PROBLEM RM.201 1.5,VISUAL INSPECT PLAYGROUNDS 10/14 - 8 | 10/17/2005 Medium | Paul Quinones Paul Quinones | | Sunrise ES |
| 6570 | Work In Progress WATER LEAKING FROM PUMP SEAL,NEED TO REPLACE IN RM. 210. THANKS | 10/19/2005 Medium | Paul Quinones Jaime Gomez | | Sunrise ES |
| 7576 | Work In Progress REQUESTING FLUORESCENT LIGHT LAMPS T8/SP30 | 11/28/2005 Medium | Paul Quinones Enrique Sotelo | | Sunrise ES |
| 7582 | Work In Progress PROBLEM IN DIAG. RM. NEED TO REPLACE HEATER ELEMENTS REQUESTING 3.0 HEATER ELEMENTS FOR 3 PHASE SHUT OFF SWITCH. | 11/28/2005 Medium | Paul Quinones Enrique Sotelo | | Sunrise ES |
| 7468 | Work In Progress PEST CONROL OF PIGEONS.PIGEONS ARE NESTING ON THE ROOF,AND AROUND THE MECH. EQUIPMENT,AND DROPPINGS AS WELL.THANKS Need price quote! | 11/18/2005 Medium | Paul Quinones Margret Villalobos | | Sunrise ES |
| 3876 | Work In Progress RM.307,BAD CIRCULATING PUMP NEED TO REPLACE | 7/27/2005 Medium | Paul Quinones Jaime Gomez | | Sunrise ES |
| 3477 | Work In Progress I NEED SAND FOR THE PLAY GROUNDS,THANKS. | 7/12/2005 Medium | Paul Quinones Lorenzo Hernandez | | Sunrise ES |
| 3469 | Work In Progress FENCING AREA IN BACK OF SCHOOL NEAR LIFT STATION NEEDS TO BE REPAIRED,AND ROLL GATE.PROBABLE HIGH WINDS ON 7-11-05 CAUSED THE DAMAGE.NO SIGNS OF VANDILISM ON SCHOOL PROPERTY | 7/12/2005 Medium | Paul Quinones Michael Munoz | | Sunrise ES |
| 7809 | Work In Progress Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Paul Quinones | | Sunrise ES |
| 7818 | Work In Progress Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Paul Quinones | | Sunrise ES |

| WOID | Status Description Action Taken | Request Date Completion Date Priority | Requester Assigned To | Area Type | Location Area Number |
|-------------|---|--|-----------------------------------|------------------|---------------------------------|
| 3629 | Work In Progress please cut and weedeat in and around lift station. weeds are growing rapid and are going to end up on the playing fields. | 7/18/2005 Medium | Paul Quinones | | Sunrise ES |
| 6887 | Work In Progress The Wastwater Flow Meter needs to be checked for proper calibration ASAP | 10/31/2005 High | Ricardo Jacquez | | Sunrise ES |
| 7495 | Work In Progress please order fill dirt for new arrivals of new portables. sunrise, che, desert-trail | 11/21/2005 Medium | Guadalupe Ontiveros | Portables | Sunrise ES |
| 7752 | Work In Progress Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details. | 12/4/2005 Medium | Alfredo Holguin Paul Quinones | | Sunrise ES |
| 4628 | Work In Progress Need to meet contractor on Monday - to rekey school site. | 8/17/2005 Medium | David Boyd Manny Lozoya | | Vado ES |
| 8045 | Work In Progress LUPE ONTIV. need backhoe at vado to spread sand for play ground equitement | 12/12/2005 Medium | Frank Lara Guadalupe Ontiveros | | Vado ES |