

# 963 - Work Orders In Progress (7/1/05 - 2/28/06 Fiscal Year)

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9356	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
9355	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
9334	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3982	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3981	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3960	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3312	Work In Progress Yearly - Alma Del Valle Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3308	Work In Progress Yearly - Alma Del Valle Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
8636	Work In Progress NEED TO COMPLETE BUILDING INSPECTION FOR ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOU OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED & SIGNED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JANUARY 27, 2006	1/11/2006 Medium	Aida Salcedo Carlos Lujan		Anthony ES
9570	Work In Progress ON FEB 28, '06 - NEED TO DELIVER 26 TABLES AND 40 CHAIRS TO AE - RIGHT AFTER 12:00 PM TO CLEAN & SET UP FOR "TEACHER OF THE YEAR AWARD CEREMONY". TABLES & CHAIRS NEED TO BE PICKED UP ON WEDNESDAY MORNING BY 9:00 A.M.	2/10/2006 Medium	Aida Salcedo Jimmy Carbajal		Anthony ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
8748	Work In Progress Ice Maker at Anthony Elementary 4-6 is not making ICE and Milk Cooler at Anthony Elementary k-1 is not working Rebecca Saenz - SNP Manager 882-3507 or 882-5607	1/13/2006 Medium	Alma Terrell Danny Orozco	Cafeteria	Anthony ES
6005	Work In Progress Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
9925	Work In Progress please provide carpet in music classrooms. (chapter bldg)	2/22/2006 Medium	Michael Munoz		Anthony ES
9549	Work In Progress please provide concrete for repair of sidewalk where mainsewer line was replaced. main bldg. contact person-Lucky	2/10/2006 Medium	Michael Munoz		Anthony ES
9133	Work In Progress main bldg behind annex. Please use backhoe for repair of sewer line.	1/30/2006 High	Guadalupe Ontiveros		Anthony ES
8736	Work In Progress please add additional sprinklers to existing sprinkler system in the corredore and between the primary and drug free. Also if h2o can be tied in to pine trees. Thanks	1/13/2006 Medium	Guadalupe Ontiveros		Anthony ES
4487	Work In Progress plese grade and add crusher fine for neww parking for parents and add parking curbs.	8/11/2005 Medium	Guadalupe Ontiveros		Anthony ES
4097	Work In Progress please scrape and add crusher fine along with parking curbs.see mike	8/2/2005 Medium	Guadalupe Ontiveros		Anthony ES
9303	Work In Progress I request a tool set for us we need some tools fore exsample a drill that has 18v we have a 9.6v and the batter is slow.and tools sets	2/3/2006 Medium	Carlos Lujan Sal Acuna		Anthony ES
9185	Work In Progress need metal frame for new opening @ music rm. anthony elem.	1/31/2006 Medium	Danny Miranda Danny Miranda		Anthony ES
3899	Work In Progress Room 201 - Half of the carpet is bad replace with tile. 11/29/05 - Teacher requesting status on this work order on 11/10/05 a student fell and hurt her leg. -mkv	7/28/2005 Medium	Hector Villalobos Michael Munoz	Classroom	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4255	Work In Progress room 109 needs carpet repair	8/8/2005 Medium	Hector Villalobos Michael Munoz	Classroom	Anthony ES
4478	Work In Progress Chapter bg p.e room replace 3/4 motor with a 1hp motor	8/11/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
4581	Work In Progress old main blg a/c motor burn out a 3 hp volts 230	8/15/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
4861	Work In Progress Nurse office refrigerator is not working water is leaking from seal	8/24/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
4742	Work In Progress need a 3/4 hp motor cafeteira motor burn out old cafeteria	8/22/2005 Medium	Hector Villalobos Jaime Gomez	Cafeteria	Anthony ES
4743	Work In Progress mild cafeteria burn motor 3/4 hp with a belt 4-L 660 or 670	8/22/2005 Medium	Hector Villalobos Jaime Gomez	Cafeteria	Anthony ES
5944	Work In Progress Old main blg boiler room needs a thermocuple size 56 inch	9/29/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
5992	Work In Progress upper primary boiler is leaking replace	9/30/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
8966	Work In Progress upper primary office needs two filing cabinet locks and two desk locks two cabinet locks	1/24/2006 Medium	Hector Villalobos Manny Lozoya	Office	Anthony ES
8967	Work In Progress Headstrat pt1 h 2 keys can not open lock on door	1/24/2006 Medium	Hector Villalobos Manny Lozoya	Portables	Anthony ES
8952	Work In Progress broken water line in ceiling cafeteria	1/23/2006 Medium	Hector Villalobos Joe Ontiveros	Cafeteria	Anthony ES
8540	Work In Progress order new toilet for bathroom	1/9/2006 Medium	Hector Villalobos Joe Ontiveros	Restroom (Girls)	Anthony ES
7566	Work In Progress Bathroom dry walls need to be replace or panel	11/28/2005 Medium	Hector Villalobos Danny Miranda	Mechanical Room	Anthony ES
7339	Work In Progress Custodial storage faucet is leaking need to replace faucet	11/14/2005 Medium	Hector Villalobos Joe Ontiveros	Custodial	Anthony ES
9595	Work In Progress replace water heater in leaning center 2. 5 gal.	2/10/2006 Medium	Hector Villalobos Joe Ontiveros		Anthony ES
9853	Work In Progress MISSING 1 FIRE EXTINGUISHER AT OLD MAIN HALLWAY AS PER PM 9335	2/17/2006 Medium	Hector Villalobos Ruben Ronquillo		Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
10014	Work In Progress Broken windows 2 19 1/4 by 14 1/2 one 19 1/4 x15 1/2 frost	2/27/2006 Medium	Hector Villalobos Ruben Ronquillo	Cafeteria	Anthony ES
10015	Work In Progress Need to replace pump seal	2/27/2006 Medium	Hector Villalobos Lorenzo Solis	Mechanical Room	Anthony ES
10012	Work In Progress Replace outside lighting fixture	2/27/2006 Medium	Hector Villalobos Enrique Sotelo	Cafeteria	Anthony ES
10013	Work In Progress Replace all 4 bathroom lighting	2/27/2006 Medium	Hector Villalobos Enrique Sotelo	Restroom (Boys)	Anthony ES
9437	Work In Progress Replace a/c unit with a 65 master cool cafeteria	2/7/2006 Medium	Hector Villalobos Lorenzo Solis	Cafeteria	Anthony ES
9440	Work In Progress Need a/c vents for two class rooms 201 202	2/7/2006 Medium	Hector Villalobos Lorenzo Solis	Classroom	Anthony ES
9250	Work In Progress Chapter blg p. e bathroom replace lock and straighten out door	2/2/2006 Medium	Hector Villalobos Manny Lozoya	Office	Anthony ES
9251	Work In Progress Social worker office needs to rekey cabinets	2/2/2006 Medium	Hector Villalobos Manny Lozoya	Office	Anthony ES
9065	Work In Progress Replace a/c 45 to a 65 master cool room 306	1/26/2006 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
9058	Work In Progress constant blockage of main sewer line coming out of cafeteria and linking portables&annex buildings.	1/26/2006 Medium	David Villalobos David Villalobos	Cafeteria	Anthony ES
9088	Work In Progress AE 4-6 CAMPUS. DISHWASHER HAS ALOT OF LIME BUILD-UP , MAY NEED NEW TIPS ON THE RINSE .  BECKY S. SNP MGR 882-3507	1/27/2006 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Anthony ES
4059	Work In Progress DAYCARE - NEED TO ISSUE KEYS TO CORINA VALDESPINO for (Krishna's Office). WILL BE HERE AT 8:00 AM TOMORROW.	8/1/2005 Medium	Margret Villalobos Manny Lozoya		Anthony ES
9884	Work In Progress NEED TO REPLACE DRAIN TRAP ON WATER FOUNTAIN IN GYM AND SOME OTHER PARTS	2/21/2006 Medium	Ramiro Holguin Joe Ontiveros		Berino ES
9885	Work In Progress NEED TO REPLACE DRAIN TRAP ON WATER FOUNTAIN IN GYM AND SOME OTHER PARTS	2/21/2006 Medium	Ramiro Holguin Joe Ontiveros		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9557	Work In Progress TOILET IN ROOM 100 IS LEAKING WATER FROM BOTTOM OF TANK NEEDS TO BE REPLACE	2/10/2006 Medium	Ramiro Holguin Joe Ontiveros		Berino ES
9644	Work In Progress 2/13/06 NEED FIVE 2X12X12	2/13/2006 Medium	Ramiro Holguin Ruben Ronquillo		Berino ES
9765	Work In Progress ROOMS 119,120 NEED A/C REPLACE TWO 6500 MIDDLE WESTWING NEEDS TWO WET SECTIONS 6500 NORTH WESTWING NEEDS ONE WET SECTION 4500 NORTH EASTWING NEEDS FOUR WET SECTIONS REPLACED 6500 AND ONE 4500 GYM NEEDS TWO 8500 A/C REPLACE	2/16/2006 Medium	Ramiro Holguin Lorenzo Solis		Berino ES
9404	Work In Progress 2/03/06 SECURITY LIGHT COVER ON CAFETERIA OUTSIDE WALL NEEDS TO BE REPLACE	2/6/2006 Medium	Ramiro Holguin Enrique Sotelo		Berino ES
7907	Work In Progress 12/06/05 TO MIKE PORTABLE 154 FLOOR TITLES ARE COMING OFF IF POSSIBLE THIS CHRISTMAS BREAK YOU CAN SOME CARPET INSTALL ED	12/7/2005 Medium	Ramiro Holguin Michael Munoz		Berino ES
8684	Work In Progress NEED TO REPLACE BROKEN BLINDS ROOM 108 NEEDS ONE 54" P.145 NEEDS 3 35" P. 147 3 45" P 156 2 47"	1/12/2006 Medium	Ramiro Holguin Ruben Ronquillo		Berino ES
8947	Work In Progress NEED TWO LOADS OF TOP RED SOIL FOR PLAYGROUND ON EASTSIDE	1/23/2006 Medium	Ramiro Holguin Guadalupe Ontiveros		Berino ES
8945	Work In Progress NEED TO REPLACE KEY FOR TV BROKEN ASAP	1/23/2006 Medium	Ramiro Holguin Manny Lozoya		Berino ES
8526	Work In Progress NEED TO REPLACE TWO SINGLE SINK FAUCETS IN CLASS ROOMS	1/9/2006 Medium	Ramiro Holguin Joe Ontiveros		Berino ES
8630	Work In Progress PORTABLE 154, NEEDS CARPET INSTALL FLOOR TILES ARE COMING OFF	1/11/2006 Medium	Ramiro Holguin Michael Munoz		Berino ES
8560	Work In Progress NEED TO RELACE SKY LIGHT WINDOW 6X6 FEET HAS A HOLE IN TOP CLASS	1/9/2006 Medium	Ramiro Holguin Ruben Ronquillo		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9455	Work In Progress Need another gate key for El Paso Disposal.	2/7/2006 Medium	Juliet Parra Manny Lozoya		Berino ES
9006	Work In Progress Need a gate key for El Paso Disposal.	1/24/2006 Medium	Juliet Parra Manny Lozoya		Berino ES
5338	Work In Progress WALK - IN FREEZER IS LEAKING ALOT OF WATER BETWEEN THE FREEZER AND REFRIG.  ELSA - 882-2417	9/8/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Berino ES
3434	Work In Progress WASHING MACHINE DOES NOT WORK ANY MORE. (IT GAVE UP)  ELSA CHAIRZ - SNP MGR 882-2417	7/11/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Berino ES
5898	Work In Progress Need 2 new keys for office gate and recut master key for Mr Silva THANKS OFFICE KEY IS ON YOUR KEY CHAIN ALREADY	9/28/2005 Medium	Jimmy Cortez Manny Lozoya		Berino ES
5585	Work In Progress need nemaster b key and 55key for new custodian thanks a.s. p	9/19/2005 Medium	Jimmy Cortez Manny Lozoya		Berino ES
4208	Work In Progress MOBILE HOME OCCUPANT WILL BE RECEIVING NEW MOBILE HOME ON APPROXIMATELY 8-29- 05. PLEASE CONNECT ELECTRICAL. 28X54	8/4/2005 Medium	Enrique Sotelo		Berino ES
4055	Work In Progress please cut weeds and pick-up debris on east side of rockwall. (i.e weeds bottles cinder blocks.)	8/1/2005 Medium	Ramiro Holguin		Berino ES
4082	Work In Progress Monitoring Wells - I need a set of keys to the monitoring well caps	8/2/2005 Medium	Alfredo Holguin Manny Lozoya		Berino ES
9336	Work In Progress Monthly - Berino ES Monthly FE Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
9358	Work In Progress Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
9361	Work In Progress Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
9360	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Juan Vargas		Chaparral ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
9337	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
6123	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
4518	Work In Progress please replace urinal and commode in mens restrrom.	8/12/2005 Medium	Joe Ontiveros	Mechanical Room	Chaparral ES
8428	Work In Progress please remove and remodel restrooms and custodial closet.	1/5/2006 Medium	Danny Miranda		Chaparral ES
8430	Work In Progress please remove and provide new electrical to e- wing restrooms as needed. i.e exhaust fan, electric heat. please discuss with hvac techs.	1/5/2006 Medium	Enrique Sotelo		Chaparral ES
8429	Work In Progress please remove all old fixtures and order new material for rough and top out. also order new fixures.	1/5/2006 Medium	Joe Ontiveros		Chaparral ES
7820	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
7779	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
7756	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
8408	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
8367	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
8312	Work In Progress Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
8295	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9401	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
6343	Work In Progress las vanquetas need grabo a round	10/12/2005 Medium	Juan Vargas Guadalupe Ontiveros		Chaparral ES
4602	Work In Progress ruben ronquillo need 10 pvc 45 elbows 6 inches 10 square grate basin 6 inches and 200 ft. 6 inches pvc pipe	8/16/2005 Medium	Juan Vargas Joe Ontiveros		Chaparral ES
3868	Work In Progress ROOMS 83-82-81-80-72-96-70 NEED WINDOWS REPAIRED OR REPLACE 2-REPORT	7/27/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
4030	Work In Progress Room 47 need to instaled a/c ventilation	8/1/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
3846	Work In Progress 07/26/05 j. gomes rooms 2 -20-21- 51-47-107- 44- 55-46- need replace A/C 6500	7/26/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
3801	Work In Progress 5/25/05/ mike neseito que pongan sistema de riego para los arboles	7/25/2005 Medium	Juan Vargas Guadalupe Ontiveros		Chaparral ES
3800	Work In Progress 07/25/05 jaime gomes main office need new A/C two 4500 and one 6500	7/25/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
4213	Work In Progress Rooms 101-102-60-62-61-54-70-96-72-73-97 80- 82-83 need carpet repace	8/4/2005 Medium	Juan Vargas Michael Munoz		Chaparral ES
3284	Work In Progress 07/05/05 mike munoz Mr. cardona quiere bertical blind en su oficina size 82 width and 80 length	7/5/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
9658	Work In Progress room 129need fix door not lock	2/13/2006 Medium	Juan Vargas Manny Lozoya		Chaparral ES
9107	Work In Progress need 200ft. swing chain and 10 swing hanger	1/27/2006 Medium	Juan Vargas Guadalupe Ontiveros		Chaparral ES
9199	Work In Progress need replce a/c rooms 20 -2-46-21-51- 47 and 3 more in library	1/31/2006 Medium	Juan Vargas Lorenzo Solis		Chaparral ES
9201	Work In Progress portables 63 -62 -and 54 need replace a/c master cool 3800	1/31/2006 Medium	Juan Vargas Lorenzo Solis		Chaparral ES
8841	Work In Progress cafeteria need replace duct and a/c	1/18/2006 Medium	Juan Vargas Lorenzo Solis		Chaparral ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
8842	Work In Progress portables 414/416/and 418 need ventilation duct	1/18/2006 Medium	Juan Vargas Lorenzo Solis		Chaparral ES
8718	Work In Progress NEED NEW NUMBERS FOR THE CLASSROOMS 0-1/0-2/0-3/0-4/0-5/0-7/101/102/103/104/105/106/107/108/109/201/202/203/204/205/206/207/208/209/210/211/212/213/214/215/216/217/218/219/220401/402/403/404/405/406/408/409/410/412/414/416/418301/302/303/304/305/306/307/308/309/310/311/312501/502/503/504/505506/507/508/510/509/511/5124-B.RESTROOMS 4-G.RESTROOMS 3-MANS3-WOMANS 1-T.L.ROOMS	1/12/2006 Medium	Juan Vargas Manny Lozoya		Chaparral ES
8523	Work In Progress room 20 need fix cabinets lock	1/9/2006 Medium	Juan Vargas Manny Lozoya		Chaparral ES
6415	Work In Progress cafeteria exit sign need change	10/14/2005 Medium	Juan Vargas Enrique Sotelo		Chaparral ES
6502	Work In Progress room 72 heating not work need help to fix	10/18/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
7863	Work In Progress cafeteria need replace floor tile	12/6/2005 Medium	Juan Vargas Michael Munoz		Chaparral ES
7946	Work In Progress cafeteria need replace two entry doors	12/8/2005 Medium	Juan Vargas Danny Miranda	Cafeteria	Chaparral ES
7947	Work In Progress kitchen need replace entry door	12/8/2005 Medium	Juan Vargas Danny Miranda	Cafeteria	Chaparral ES
7949	Work In Progress room 120 need fix bathroom door frame	12/8/2005 Medium	Juan Vargas Danny Miranda		Chaparral ES
7953	Work In Progress nesesito 6 donpes de arena para los colunpios y acuitment playground	12/8/2005 Medium	Juan Vargas Guadalupe Ontiveros		Chaparral ES
7646	Work In Progress evenstar playgroun need water fouting fix	11/30/2005 Medium	Juan Vargas Joe Ontiveros		Chaparral ES
7376	Work In Progress portables and e. wing need doors replace	11/15/2005 Medium	Juan Vargas Danny Miranda		Chaparral ES
7378	Work In Progress miusic room and gym. need doors replace	11/15/2005 Medium	Juan Vargas Danny Miranda		Chaparral ES
7359	Work In Progress 2 request e. wing rooms need to repair windows	11/15/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
7360	Work In Progress rooms 79 71 70 83 need 12 blinds size 33 width 58 length	11/15/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
9630	Work In Progress 2/13/06 need to replace r.r. partitions in boys @ girls r.r. E-eing	2/13/2006 Medium	Danny Miranda Danny Miranda		Chaparral ES
8834	Work In Progress THE TWO OVENS THAT WERE MOVED DO NOT WORK.  ALICE E. SNP MGR 824-0048	1/18/2006 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Chaparral ES
8891	Work In Progress Display case in the main hallway does not have a key, to open. Need someone to look into making another key.	1/19/2006 Medium	Jennifer Corral Manny Lozoya	Hallway/Corridor	Chaparral ES
6529	Work In Progress Had done a work order before for Ms. Barrett about fixing her windows needs a screen.She says they still haven't done the work order. Thanks	10/18/2005 Medium	Jennifer Corral Ruben Ronquillo	Classroom	Chaparral ES
7710	Work In Progress Window in rm-72 is falling out. When opened it falls out. Doesn't stay up alone needs a stick to hold it up. See Ms. Barrett.	12/1/2005 Medium	Jennifer Corral Ruben Ronquillo		Chaparral ES
10058	Work In Progress Doors need locks to be changed on the outside. Different knobs. will be done today 2/28/06. per request of Mr. Cardona	2/28/2006 Medium	Jennifer Corral Manny Lozoya	Classroom	Chaparral ES
10060	Work In Progress need to replace cylinder in hallway of office, masters not working.	2/28/2006 Medium	Jennifer Corral Manny Lozoya	Hallway/Corridor	Chaparral ES
10019	Work In Progress my box with keys for teachers was locked and I need it open, the keys to the box are in there. Have no way of giving teachers keys. Please do as soon as possible.	2/27/2006 Medium	Jennifer Corral Manny Lozoya	Office	Chaparral ES
4110	Work In Progress Rm-72 Ms. Barret needs screens on her windows. Says they were suppose to be put in last year.	8/3/2005 Medium	Jennifer Corral Ruben Ronquillo	Classroom	Chaparral ES
3785	Work In Progress NEED A KEY FOR ROOM 114,LEDESMA REPRINT FOR MANNY - REGARDING E-MAIL 7/27/05 - MKV	7/22/2005 Medium	Jennifer Corral Manny Lozoya	Classroom	Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3871	Work In Progress need an extra key for Even start classroom, Jeannette rm-118	7/27/2005 Medium	Jennifer Corral Manny Lozoya	Classroom	Chaparral ES
3945	Work In Progress Air Conditioner smells like burn and is not cold in rm-128 for Ms. Word	7/29/2005 Medium	Jennifer Corral Jaime Gomez	Classroom	Chaparral ES
3946	Work In Progress Air Conditioner not working in rm-20 for Ms. Gary	7/29/2005 Medium	Jennifer Corral Jaime Gomez	Classroom	Chaparral ES
3299	Work In Progress I need some keys for two of the new administrators who will be coming to this school. They have requested main keys to the gate that opens up the fence outside the school and also a set of main keys for the building. If you can please do as soon as possible. Keys for Chaparral Elementary.	7/5/2005 Medium	Jennifer Corral Manny Lozoya	Office	Chaparral ES
9980	Work In Progress Mr. Cardona is requesting verticle blinds for the front office. measurements are 48"x 84".	2/24/2006 Medium	Joe Ramirez Ruben Ronquillo		Chaparral ES
9991	Work In Progress Mr. Cardona is requesting that pine trees be planted all along the westside fence line.	2/24/2006 Medium	Joe Ramirez Guadalupe Ontiveros		Chaparral ES
4797	Work In Progress repair storage, boy,s , girl,s r.r. @ chaparral elem	8/22/2005 Medium	Danny Miranda Danny Miranda		Chaparral ES
5498	Work In Progress sweeper/blower/not/working/choke/broken	9/14/2005 Medium	Daniel Ramirez Jimmy Carbajal		Chaparral ES
9742	Work In Progress Could I get a key for Chap E for sound signal? Thanks, carlos	2/15/2006 Medium	Carlos Vigil Manny Lozoya		Chaparral ES
9053	Work In Progress E-Wing Barracks - Repair hole on eastside.	1/26/2006 Medium	Michael Munoz Juan Vargas		Chaparral ES
9054	Work In Progress E-Wing Barracks -Paint door on E-Wing Patio area and repair door (hole on wall E-Wing by Patio).	1/26/2006 Medium	Michael Munoz Juan Vargas		Chaparral ES
9052	Work In Progress Patio (Behind Library) Cut grass, weeds and trim edges of grass on sidewalk.	1/26/2006 Medium	Michael Munoz Joe Ramirez		Chaparral MS
8070	Work In Progress Need to cut, pickup weeds and cleanup debris around WWTP as per Mike Munoz.	12/13/2005 1/24/2006 Medium	Michael Munoz Ricardo Jacquez		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
8069	Work In Progress Need to cleanout Mech, Bolier and Electrical Rooms as per Mike Munoz.	12/13/2005 Medium	Michael Munoz Joe Ramirez		Chaparral MS
4072	Work In Progress Room 208 - Mold on ceiling tiles. (Nancy, Nurse @ site called in) - mkv Margaret, Joe replied and said there where a couple of ceiling tiles with small mold droppings on them. He replaced them. However still go ahead and generate a w.o. for our records and have him fill it out.  Mike	8/2/2005 Medium	Mary Garcia Joe Ramirez	Classroom	Chaparral MS
9486	Work In Progress need to replace cloged lines on top of rsf unit	2/8/2006 Medium	Ricardo Jacquez Ricardo Jacquez		Chaparral MS
5062	Work In Progress I NEED 1 MALE WATER HOSE CONNECTOR, 1 HX-1 VINYL ANCHOR KIT AND 1 WEJIT DRY WALL AUGER ANCHOR KIT SIZE 8. THANK YOU	8/30/2005 Medium	Robert Gonzalez Jimmy Carbajal		Chaparral MS
3499	Work In Progress We need locks to be installed on the center pole to the double doors in the front entrance,north east doors and south east doors. This is the oldest part of the school. the newer part of the school already have locks on the center poles. This old doors are the once that we use more often. This locks will make it so much faster and easier. THANK YOU ROBERT	7/13/2005 Medium	Robert Gonzalez Manny Lozoya		Chaparral MS
7525	Work In Progress MRS. ADAMS ROOM 203 HAS CABINETS AND DRAWERS THAT ARE LOCKED AND SHE DOESN'T HAVE A KEY TO UNLOCK THEM. SHE WOULD LIKE TO HAVE THEM UNLOCKED AS SOON AS POSSIBLE. THANK YOU	11/22/2005 Medium	Robert Gonzalez Manny Lozoya		Chaparral MS
9913	Work In Progress main door to main office does not unlock	2/22/2006 Medium	Robert Gonzalez Manny Lozoya		Chaparral MS
9914	Work In Progress main door to come in to main building can not be locked open	2/22/2006 Medium	Robert Gonzalez Manny Lozoya		Chaparral MS
3855	Work In Progress NEED TO REKEY CABINET.	7/26/2005 Medium	Vickie Reed Manny Lozoya	Classroom	Chaparral MS 204
3439	Work In Progress NEED KEYS FOR TWO NEW PORTABLES.	7/11/2005 Medium	Vickie Reed Manny Lozoya	Portables	Chaparral MS
4509	Work In Progress need to rekey file cabinets. 2	8/12/2005 Medium	Vickie Reed Manny Lozoya	Classroom	Chaparral MS 104

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4639	Work In Progress NEED 3 REPLACEMENT KEYS FOR 3 A-34'S THAT DO NOT WORK.	8/17/2005 Medium	Vickie Reed Manny Lozoya	Office	Chaparral MS VICKIE-KEY
9293	Work In Progress add micro switch to the suppression system	2/2/2006 Medium	Cora Ramirez Danny Orozco	Cafeteria	Chaparral MS
9728	Work In Progress Pushbar front door entrance needs to be replaced mechanism inside is all scattered.	2/15/2006 Medium	Joe Ramirez Manny Lozoya		Chaparral MS
9827	Work In Progress Coach Y. would like to have a plumber check out the shower system it is not functioning at full capacity.	2/17/2006 Medium	Joe Ramirez Joe Ontiveros		Chaparral MS
8490	Work In Progress 1/6/06. need a new lock for bus turnaround south gate, lock has been cut off.	1/6/2006 Medium	Joe Ramirez Manny Lozoya		Chaparral MS
6558	Work In Progress 10/19/05. we need propane tank filled for portable housing rms. 1&2. ATTEN. RUBEN.	10/19/2005 10/21/2005 Medium	Joe Ramirez Ruben Ronquillo		Chaparral MS
7324	Work In Progress 11/14/05. door closer on walk in freezer door needs to be replaced. thanks.	11/14/2005 Medium	Joe Ramirez Danny Orozco		Chaparral MS
3720	Work In Progress 7/12/05. need a/c replaced on portable 1 rm. 2 please.	7/20/2005 Medium	Joe Ramirez Jaime Gomez		Chaparral MS
6246	Work In Progress Need about 2 yards base coarse for use around pond area.	10/10/2005 Medium	Joe Ramirez Guadalupe Ontiveros		Chaparral MS
9445	Work In Progress Need to replace tumblers in office door lock, keys will not unlock door.	2/7/2006 Medium	Joe Ramirez Manny Lozoya		Chaparral MS
9447	Work In Progress Need wire glass pane replaced sizes are 30x20.	2/7/2006 Medium	Joe Ramirez Ruben Ronquillo		Chaparral MS
9531	Work In Progress 2/09/06. door handle to rm. 407 is broken needs to be replaced as soon as possible.	2/9/2006 Medium	Joe Ramirez Manny Lozoya		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9808	Work In Progress STOVE NOT HEATING VERY WELL/NOT ENOUGH  JUANA MONTELONGO ASSIST. MGR 824-4376	2/17/2006  Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Chaparral MS
9778	Work In Progress c.m.s. need to paint new doors around gym	2/16/2006  Medium	Danny Miranda Juan Vargas		Chaparral MS
3607	Work In Progress need to paint new door @ football storage rm.	7/18/2005  Medium	Danny Miranda Joe Ramirez		Chaparral MS
3608	Work In Progress need to paint new door @ rm. 86	7/18/2005  Medium	Danny Miranda Joe Ramirez		Chaparral MS
9110	Work In Progress Need a lock/key for a new file cabinet being set up in the teacher's lounge.	1/27/2006  Medium	Elena Palacios Manny Lozoya		Chaparral MS
9629	Work In Progress sink in womens bathroom in front office is leaking and splashes water everywhere from the sides when it is opened.	2/13/2006  Medium	Elena Palacios Joe Ontiveros		Chaparral MS
9627	Work In Progress Coach Yturralde needs to change a lock to one of his cabinets in the boys gym that doesn't have a key.	2/13/2006  Medium	Elena Palacios Manny Lozoya		Chaparral MS
9628	Work In Progress door to front office won't open with any key. Not even master key.	2/13/2006  Medium	Elena Palacios Manny Lozoya		Chaparral MS
9825	Work In Progress SHOWERS IN BOYS GYM NEED SERVICING ONLY SEVEN OUT OF TEN ARE WORKING. POSSIBLY INSTALL NEW SHOWER HEADS.	2/17/2006  Medium	Elena Palacios Joe Ontiveros	Gym	Chaparral MS BOYS GYM
8488	Work In Progress Need keys to be made/duplicated for various rooms.	1/6/2006 1/9/2006  Medium	Elena Palacios Manny Lozoya	Classroom	Chaparral MS
8702	Work In Progress needs copy of key A-24, needs to put new locks on two files cabinets in front office	1/12/2006  Medium	Elena Palacios Manny Lozoya		Chaparral MS Room 201
8949	Work In Progress Mr. Digg's door handle to his office is currently getting jammed. Also, one of the front doors keeps locking on it's own.	1/23/2006  Medium	Elena Palacios Manny Lozoya		Chaparral MS
8296	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	1/1/2006  Medium	Alfredo Holguin Joe Ramirez		Chaparral MS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
8371	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
8369	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7087	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7085	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7074	Work In Progress Monthly - Chaparral MS Roof Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7757	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7061	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7783	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
7781	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
5463	Work In Progress need to pour landing and sidewalks to portables by football feild.	9/13/2005 Medium	Michael Munoz	Portables	Chaparral MS
4485	Work In Progress please take a load of crusher fine so sewer line. Ak David (plumbing) for the specifics.	8/11/2005 Medium	Guadalupe Ontiveros	Portables	Chaparral MS
3648	Work In Progress please get with speedy and have him train you on the sprikler system on football field and thru out campus. Identify all valves and repair what is needed. also ask him for a key for sprinkler box and have him teach you the programs.	7/19/2005 Medium	Joe Ramirez	Football Field	Chaparral MS
3649	Work In Progress need to cut weeds and grass behind library and courtyard and surrounding areas tru -out campus including pond. Also need to irrigate these areas also.	7/19/2005 High	Joe Ramirez		Chaparral MS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
3650	Work In Progress please paint railing on new portables that where installed and modified and all railings that are in need.	7/19/2005 Medium	Joe Ramirez		Chaparral MS
3656	Work In Progress please put up fence where portables where installed even if its on a temp bases.	7/19/2005 Medium	Joe Ramirez	Football Field	Chaparral MS
5229	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
5227	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
6086	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
6084	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
6048	Work In Progress Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		Chaparral MS
5204	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
6008	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3990	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3988	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3964	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3977	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
9338	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS



<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
9351	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
9362	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
9364	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3314	Work In Progress Yearly - Chaparral MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3307	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3336	Work In Progress Yearly - Chaparral MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3243	Work In Progress Monthly - Chaparral MS Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3241	Work In Progress Monthly - Chaparral MS Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3148	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
9369	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin David Acosta		Desert Pride
9365	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin David Acosta		Desert Pride
9353	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin David Acosta		Desert Pride
4992	Work In Progress please remove marquee sign from desertveiw and install at desert pride. please be careful when removing.see mike	8/29/2005 Medium	Guadalupe Ontiveros		Desert Pride
8313	Work In Progress Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin David Acosta		Desert Pride

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9877	Work In Progress front office building - roof missing tile	2/21/2006 Medium	David Acosta Michael Munoz	Office	Desert Pride
9984	Work In Progress royal vacuum cleaner-crack around the handle by switch. (k96A 0001527 )	2/24/2006 Medium	David Acosta Jimmy Carbajal	Office	Desert Pride
9986	Work In Progress Hand dolly- wheels noisy and loose.	2/24/2006 Medium	David Acosta Jimmy Carbajal	Custodial	Desert Pride
7731	Work In Progress need gate repairs-vehicles hit and run on gate (front entrance)	12/2/2005 Medium	David Acosta Ruben Ronquillo	Parking Lot	Desert Pride front entrance
7666	Work In Progress having trouble unlocking the westside door (cylinder).	11/30/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride #8
7955	Work In Progress Vandalism - Damage to front entrance roll gate hit by vehicle. (Case# 2005-1037) Julio Ledesma #831	12/2/2005 Medium	David Acosta Michael Munoz		Desert Pride
8880	Work In Progress need to replace broken toilet seat	1/19/2006 Medium	David Acosta David Villalobos	Computer Lab	Desert Pride
8848	Work In Progress need help with tree pruning for bigger trees	1/18/2006 Medium	David Acosta Guadalupe Ontiveros		Desert Pride
4642	Work In Progress need one key for storage closet for teacher in room #3	8/17/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride 3
5959	Work In Progress need to ckeck a/c blower . It stops blowing	9/29/2005 Medium	David Acosta Jose Ambriz	Classroom	Desert Pride #1
6368	Work In Progress principal requests - to add crush fine to parking lot and bus turn around to help keep the dust down	10/13/2005 Medium	David Acosta Guadalupe Ontiveros	Parking Lot	Desert Pride
5336	Work In Progress Principals requests: for dead bolt locks for last portable (where break-in occur )	9/8/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride #6,7.
4304	Work In Progress need locks for two doors to the hall way, that needs to be use as storage for science rooms.	8/8/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride #3,4
3791	Work In Progress need plastic name plates(12)MS. S. VERLANDER, MS. I. RAMIREZ, MS. BACH-HAGUE, MS. B. COSTULIS, MS. C. MCDONALD, MR. C. VELA, MR. P. WYMAN, MS. G. PARKER, MS. S. GARCIA, MR. D. NEAL , MS. J. ZAPATA, MS. D. DEAN	7/25/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4460	Work In Progress I need an office key for Ms. Maes, Clerk at Desert Pride Academy	8/10/2005 Medium	Mary Telles Manny Lozoya	Office	Desert Pride
9144	Work In Progress NEED A KEY (CD-32) FOR KITCHEN DOORS. REQUESTED BY MRS. MARTINEZ: PRINCIPAL	1/30/2006 Medium	Marisela Torres Manny Lozoya		Desert Trail Intermediate
9944	Work In Progress BUFFER SP20H00051912 CADA VEZ QUE LA CONECTO HACE CORTO (NO TRABAJA) ME PODRIAN PRESTAR UNA POR MIENTRAS? GRACIAS.	2/23/2006 Medium	Marisela Torres Jimmy Carbajal		Desert Trail Intermediate
9055	Work In Progress Portables - Repair dangling water lines and secure properly.	1/26/2006 Medium	Michael Munoz Johnny Acuna	Portables	Desert Trail Intermediate
9292	Work In Progress add micro switch to the suppression system	2/2/2006 Medium	Cora Ramirez Danny Orozco	Cafeteria	Desert Trail Intermediate
6266	Work In Progress RUSH ! or as soon as possible or Monday even. Could I get a line locate for Desert Trails Portables?	10/11/2005 Medium	Carlos Vigil Enrique Sotelo		Desert Trail Intermediate
9830	Work In Progress Portable #412, need to replace cracked window glass.	2/17/2006 Medium	Johnny Acuna Ruben Ronquillo		Desert Trail Intermediate
9779	Work In Progress Need keys made for Portable #400 furniture: Teacher's desk (3) different locks, need to install a lock to filing cabinet (cabinet still has the knockout), and a key for storage cabinet.	2/16/2006 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
9614	Work In Progress Need a new key for room #212. Teacher lost key. (J-50) Sylvia Lorenzo.	2/13/2006 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
9062	Work In Progress need (2) flush valve kits for restroom comodotes. One for boy's RR in the NW hall (handicap), and the other for the girl's RR in front of the teacher's lounge (handicap).	1/26/2006 Medium	Johnny Acuna Joe Ontiveros		Desert Trail Intermediate
9048	Work In Progress need a J-11 lock for outdoor cage gate between the lift station and the baseball backstop in the playground area. Thank You !!!	1/25/2006 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
9430	Work In Progress (Danny Miranda) Portable #411, #412: Need to replace hallway and restroom doors. Thank You !!!!!	2/6/2006 Medium	Johnny Acuna Danny Miranda		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7520	Work In Progress (Ruben Ronquillo) Need cement mixer for next week to do cement project in parking lot area. (ramp)	11/22/2005 Medium	Johnny Acuna Ruben Ronquillo		Desert Trail Intermediate
7408	Work In Progress NEED TO INSTALL FENCE AROUND FIRE HYDRANT. (SEE ATTACHED)	11/16/2005 Medium	Johnny Acuna Michael Munoz		Desert Trail Intermediate
7366	Work In Progress need to replace door frame and door to portable #404.	11/15/2005 Medium	Johnny Acuna Danny Miranda		Desert Trail Intermediate
7551	Work In Progress need ballasts (double) 277 V and light bulbs, to fix classroom light fixtures during intersession.	11/28/2005 Medium	Johnny Acuna Enrique Sotelo		Desert Trail Intermediate
7573	Work In Progress need a gas valve for reznor roof top heater. (valve doesn't close and leaks a little). HONEYWELL : VR8304M 2880 supplied Johnny w/gas valve and he will install.	11/28/2005 12/1/2005 Medium	Johnny Acuna Lorenzo Solis		Desert Trail Intermediate
7920	Work In Progress need a new classroom water faucet for room #111. The old one is bent up, classroom cabinets fell on top of it. (single handle faucet)	12/7/2005 Medium	Johnny Acuna Joe Ontiveros		Desert Trail Intermediate
6846	Work In Progress fire-proof filing cabinet inside vault: please fix or replace lock.	10/28/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
6910	Work In Progress need a replacement heating coil (boiler heating system) for cafeteria heater. Old heater leaks: Model # LHD103CH Serial #35C01059-06	11/1/2005 Medium	Johnny Acuna Jose Ambriz		Desert Trail Intermediate
6884	Work In Progress Marquee Light not working properly. (vice-principal)	10/31/2005 Medium	Johnny Acuna Enrique Sotelo		Desert Trail Intermediate
6883	Work In Progress need a lock (J-11) for new gate that was installed located in the fence between CH. ELEM and CH. DESERT TRAIL closest to Lisa ST. (To be locked during LOCK DOWN events). Thank You !!!!!!!	10/31/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
7184	Work In Progress Please replace metal door (Back Door) from the kitchen. Door is corroded and getting worse. Thank You !!!	11/8/2005 Medium	Johnny Acuna Danny Miranda		Desert Trail Intermediate

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
7205	Work In Progress need to replace hydraulic door closure in the back kitchen door. (old door closure leaked oil out and doesn't work)	11/8/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
8166	Work In Progress need to replace cracked window to portable #412. Have already placed glass patch on the window (both sides)	12/16/2005 Medium	Johnny Acuna Ruben Ronquillo		Desert Trail Intermediate
8064	Work In Progress Please fill in holes in playground area with top soil located in the side of the swings area. Thank You !!!!!!!	12/13/2005 Medium	Johnny Acuna Guadalupe Ontiveros		Desert Trail Intermediate
9001	Work In Progress need a restroom partition installed in room #107. (handicapp room)	1/24/2006 Medium	Johnny Acuna Danny Miranda		Desert Trail Intermediate
8625	Work In Progress portable #407: need a lock with key installed to filing cabinet. cabinet has no lock installed. It still has an oval knockout hole to it. Also need a key made to teacher's desk. I have tried out all extra keys from the office.	1/11/2006 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
3619	Work In Progress MENS RESTROOM (NW HALL) : PLEASE CHANGE DOOR CYLINDER WHERE KEY ENTERS TO OPEN UP DOOR. STUDENTS STUFFED IN CYLINDER WITH CLAY AND HARDENED. THANK YOU !!!!!!!	7/18/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
3620	Work In Progress NEED NAME PLATES TO BE MADE: (1) PRINCIPAL, (1) ASSISTANT PRINCIPAL, (1) COMPUTER LAB	7/18/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
3739	Work In Progress DIAG/PSYCH ROOM NEED (2) CLASSROOM KEYS MADE. CORE IS: J-53	7/21/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
4116	Work In Progress need a replacement single knob water faucet for room #112.	8/3/2005 Medium	Johnny Acuna Joe Ontiveros		Desert Trail Intermediate
6170	Work In Progress please repair or replace door knob in the kitchen going outdoors in the back:(door jams and is hard to open) Thank You !!!!!!!!!!!!!!!!!!!!!!!	10/4/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
5426	Work In Progress need a replacement heating coil (Boiler System) in the Cafeteria/Gym. (Old one Leaks)	9/12/2005 Medium	Johnny Acuna Jaime Gomez		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4558	Work In Progress Mrs. Bonham (Asst. Principal) requesting concrete slab to be installed between portable #412 and #413 art studio.	8/15/2005 Medium	Johnny Acuna Michael Munoz		Desert Trail Intermediate
8314	Work In Progress Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
5462	Work In Progress need to demo and repour concrete to sectioned area by cafeteria.	9/13/2005 Medium	Michael Munoz	Desert Trail Intermediate Cafeteria	
9368	Work In Progress Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
9363	Work In Progress Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
8596	Work In Progress Dryer is out of order - Not working at all  Patricia Cisneros - SNP Manager - 824-3822	1/10/2006 Medium	Alma Terrell Danny Orozco	Desert Trail Intermediate Cafeteria	
6225	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Miguel Aguilar		Desert View ES
3339	Work In Progress Yearly - Desert View ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
3317	Work In Progress Yearly - Desert View ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
5340	Work In Progress MOUSE PROBLEM. MOUSE GOT ON THE TABLE WHILE EATING  MARTHA FLORES - 589-2425 HELP PLEASE	9/8/2005 Medium	Jacqueline Aguilar Margret Villalobos	Cafeteria	Desert View ES
4149	Work In Progress key cylinder to walk-in refrigerator doesn't lock, key continously goes round and round, please repair as soon as possible, groceries and commodities are stored in there.	8/3/2005 Medium	Alma Terrell Manny Lozoya	Cafeteria	Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
8110	Work In Progress MANNY, PLEASE MAKE TWO NAME PLAQUES FOR MINERVA SINGH, RN AND YOLANDA F. GOMEZ, CNA. THANK YOU, THANK YOU!!  margarita :)	12/14/2005  Medium	Margarita Terrazas Manny Lozoya		Desert View ES
4083	Work In Progress TEACHER DESK WITH LOCKING DRAWER, DOES NOT LOCK. ROOM#19, LOWER GRADE SIDE. MRS. GRISWOLD	8/2/2005  Medium	Margarita Terrazas Manny Lozoya		Desert View ES
9872	Work In Progress Electrical cord wiring on roto machine exposed, tank also may need to be fixed.	2/21/2006  Medium	Miguel Aguilar Jimmy Carbajal		Desert View ES
7232	Work In Progress Trees in front courtyard unhealthy/dying, signs of infestation, requesting solution/insecticide to remedy problem.	11/9/2005  Medium	Miguel Aguilar Guadalupe Ontiveros		Desert View ES
7613	Work In Progress Have a nonfunctioning electrical outlet in gymnasium.	11/29/2005  Medium	Miguel Aguilar Carlos Castillo		Desert View ES
7614	Work In Progress Have a nonfunctional electrical outlet in cafeteria.	11/29/2005  Medium	Miguel Aguilar Carlos Castillo		Desert View ES
5145	Work In Progress Urgent: Need center pole repaired in exterior double door on east side of school repaired, pole fell and struck teacher. Door cannot be fully secured and will compromise security after school hours.	9/1/2005  Medium	Miguel Aguilar Manny Lozoya		Desert View ES
5146	Work In Progress Need copies (3) made of padlocks on hall doors, need for sub keys and replacement.	9/1/2005  Medium	Miguel Aguilar Manny Lozoya		Desert View ES
4781	Work In Progress pat aguilar rock wall (safety concern) 6 rock wall metal gates need to be replaced rusted throw	8/22/2005  Medium	Patricio Aguilar Michael Munoz		Desert View ES
9994	Work In Progress pat aguilar need thermostat heating & cooling port 4	2/24/2006  Medium	Patricio Aguilar Jose Ambriz		Desert View ES
4377	Work In Progress NEED NEW R. R. PARTITIONS IN "A" WING AS PER MANNY PROSPERO	8/9/2005  Medium	Manuel Prospero Danny Miranda		GAC
9066	Work In Progress I AM REQUESTING A CHAIN AND LOCK TO TIE UP TWO PIC-NIC TABLES. THI W O AS PER MANNY LOZOYA.	1/26/2006  Medium	Manuel Prospero Manny Lozoya		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9832	Work In Progress NEED 20 LIGHTS BULBS 277V FOR A OUT SIDE BUILDING. THIS WO AS PER CARLOS CASTILLO.	2/17/2006 Medium	Manuel Prospero Carlos Castillo		GAC
7950	Work In Progress 12/8/05.EXHAUST POWER IN RESTROOM AT C WING DOESN'T WORK. THIS WORK ORDER IN FOR CARLOS CASTILLO. 2ND REQUEST. FIRST WORK ORER #6990. 11/3/05.	12/8/2005 Medium	Manuel Prospero Carlos Castillo		GAC
9067	Work In Progress Swimming Pool Area - Remove dangling wooden boards.	1/26/2006 Medium	Michael Munoz Gerardo Marquez		GAC
9320	Work In Progress THE BURNISHER HAS NO POWER TO SWITCH,1681715 THANK YOU	2/3/2006 Medium	Ralph Lara Jimmy Carbajal	Cafeteria	GAC
4182	Work In Progress B-Wing - Human Resources Dept Please spray Lucy Garcia's & Ms. Browder's office for bugs (crickets, centerpedes, etc.)	8/4/2005 Medium	Mary Garcia Margret Villalobos		GAC
3408	Work In Progress AS PER CARLOS VIGIL-NEEDS A GRAND MASTER 7, ASAP. (HIS BROKE IN HALF) ALREADY TALKED WITH MANNY LOZOYA	7/8/2005 Medium	Mary Garcia Manny Lozoya	Office	GAC ALL SCHOOLS
3432	Work In Progress AS PER LINDA REYES-NEED FURNITURE FROM 3 OFFICES & BOXES ALONG WITH THIS TO BE MOVED A.S.A.P. TO NEW AREA IN C-WING. STAFF WILL START WORKING IN THESE NEW OFFICES BY TOMORROW.	7/11/2005 Medium	Mary Garcia Manuel Prospero	Office	GAC C WING
5796	Work In Progress AS PER CORA-NEEDS THE DOOR LOCK TO THE DATA CENTER SWITCHED OUT FROM SWIPE CARD TO A COMBINATION LOCK. (MANNY, PLEASE SEE CORA BEFORE CHANGING OUT)	9/23/2005 Medium	Mary Garcia Manny Lozoya	Computer Lab	GAC DATA CENTER- TECHNOLOGY
4925	Work In Progress C Wing- Having problems with mice.	8/25/2005 Medium	Mary Garcia Margret Villalobos		GAC
4655	Work In Progress AS PER ANN STEINHOFF-NEEDS 1 MORE GRAND MASTER KEY FOR HER SECRETARY AT PRE-K	8/17/2005 Medium	Mary Garcia Manny Lozoya	Office	GAC WHOLE BUILDING
8924	Work In Progress AS PER ELISA SAENZ-NEEDS NAME PLATES DONE FOR OUR NEW BOARD MEMBERS, BEFORE NEXT WEDNESDAY. 1.) ANDREW MORALES 2.) MANUELA HUERTA	1/20/2006 Medium	Mary Garcia Manny Lozoya		GAC BOARD ROOM



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
8925	Work In Progress AS PER ELISA SAENZ-NEEDS NAME PLATES DONE FOR OUR STUDENT REPRESENTATIVES. FOR NAME PLATES TO ALSO SAY STUDENT REPRESENTATIVE BELOW THEIR NAME IF POSSIBLE. 1.) DELILAH APPELZOLLER 2.) JOSUE CASTREJON	1/20/2006 Medium	Mary Garcia Manny Lozoya		GAC STUDENT REPRESENTATIV E @ GAC
8635	Work In Progress SPED Office - Need to plaster holes in wall and replace ceiling tile.	1/11/2006 Medium	Margret Villalobos Manuel Prospero	Office	GAC
7235	Work In Progress SPED Portable - need ramp for portable located at GAC. (see Margaret Villalobos-SPED_ Route to Manuel Prospero as per Mike 11/9/05 - mkv	11/9/2005 12/1/2005 Medium	Margret Villalobos Manuel Prospero		GAC
6743	Work In Progress AS PER MS. BERRY-NEEDS 3 SIGNS THAT SAY SLOW CHILDREN TO PUT IN THE ENTRANCE AND PARKING AREA. TALKED WITH RUBEN RONQUILLO AND KNOW WHICH SIGNS TO ORDER	10/25/2005 Medium	Mary Garcia Ruben Ronquillo		GAC PARKING AREA
9275	Work In Progress AS PER MARY GARCIA-NEED SUPPLY CABINET LOCK TO BE REPLACED OR FIXED. DOES NOT LOCK. (MANNY P. HAS ALREADY TRIED TWICE AND LOCKS ONLY FOR 1 DAY AND BACK TO THE SAME THING.)	2/2/2006 Medium	Mary Garcia Manny Lozoya	Office	GAC FILE ROOM
9215	Work In Progress AS PER MIKE SORIA NEEDS A KEY TO THE PATIO LOCK. (WAS CHANGED BY MANNY L. TO OPEN W/GRAND MASTER) MIKE HAS AN OLD KEY.	2/1/2006 Medium	Mary Garcia Manny Lozoya		GAC PATIO AREA
9106	Work In Progress AS PER MIKE MUNOZ-PATIO AREA, TO REMOVE DEAD WEEDS, TRIM TREES AND CLEAN THE AREA. 2/2 - THIS WO WAS GIVEN TO MANNY P PERSONALLY FROM MIKE MUNOZ - M. GARCIA 2/3 - ROUTED TO M. PROSPERO	1/27/2006 Medium	Mary Garcia Manuel Prospero		GAC PATIO AREA
9166	Work In Progress AS PER MS. BERRY-ROOM 101 IN THE PRE-K FRONT DOOR NEEDS TO BE TINTED. IT FACES THE WEST SIDE OF THE BUILDING AND IS VERY HOT IN THE AFTERNOON.	1/30/2006 Medium	Mary Garcia Ruben Ronquillo	Classroom	GAC
9073	Work In Progress AS PER MANNY-NEEDS TO RE-KEY ELODIA'S OFFICE, KEY DID NOT WORK.	1/26/2006 Medium	Mary Garcia Manny Lozoya	Office	GAC C-WING
9529	Work In Progress AS PER MS. BERRY-NEEDS FOR RUGS TO BE SET UP IN EACH CLASSROOM. (SEE ATTACHED SHEET GIVEN TO MANNY P.)	2/9/2006 Medium	Mary Garcia Manuel Prospero	Classroom	GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9496	Work In Progress AS PER MARGARET V W/SPED-NEED AN ELECTRICAL OUTLET UNDER A DESK TO BE REMOVED. (SAM GALLEGOS OFFICE) IF POSSIBLE ASAP.	2/8/2006 Medium	Mary Garcia Carlos Castillo	Mechanical Room	GAC A WINT
9318	Work In Progress AS PER MS. CUBILETTE-NEED CEMENT SCREWS FOR PINIC TABLES. (IF POSSIBLE TO BE SENT TODAY, CAUSE MANNY P. ALREADY ASSEMBLED TABLES & ARE SET OUTSIDE WITHOUT BEING SECURED. TABLES ARE WORTH \$600.000 EACH & IS VERY CONCERNED THEY MIGHT WALK OFF OVER THE WEEKEND.) AS PER MANNY P. STATED HE WAS NOT GOING TO PUT TABLES OUTSIDE UNTIL CEMENT SCREWS WERE SENT (BY YET HE DID). MANNY P. STATED THEY WERE ALREADY ORDER BY WORK ORDER AND ALSO PLACE A PHONE CALL TO RUBEN R. SINCE A WEEK AGO. AS PER RUBEN NO WORK ORDER HAS BEEN DONE BY MANNY P. RUBEN R. WILL TRY TO SENT CEMENT SCREWS TODAY W/JIMMY.	2/3/2006 Medium	Mary Garcia Manuel Prospero		GAC PATIO
9880	Work In Progress AS PER JOSE AMBRIZ-NEEDS TO REPLACE THE WHOLE AIR CONDITING UNIT FOR A-WING. (WILL BE ORDERING PARTS TO HAVE READY)	2/21/2006 Medium	Mary Garcia Jose Ambriz		GAC A WING
9945	Work In Progress AS PER BLANCA RIVERA-LIGHT BULB IN PARTION UNDER THE CABINET WENT OUT. (THERE ARE BULBS FROM OTHER PARTIONS THAT WERE STORED AT THE WAREHOUSE) MANNY P. HAS ALREADY SEEN THE BULB NEEDED.	2/23/2006 Medium	Mary Garcia Manuel Prospero	Office	GAC C-WING
9947	Work In Progress AS PER MRS. RAIHL-NEEDS HELP TO SET UP SELVES AND UNLOAD BOXES ON 2/24/06 THEY HAVE ALREADY TALKED W/MANNY P.	2/23/2006 Medium	Mary Garcia Manuel Prospero	Office	GAC C-WING
9954	Work In Progress AS PER MR. GALLEGOS W/SPED-NEEDS BASE BOARDS TO BE INSTALLED IN HIS ROOM. MANNY P. IS ALREADY AWARE OF THIS	2/23/2006 Medium	Mary Garcia Manuel Prospero	Office	GAC A WING
9955	Work In Progress AS PER MR. GALLEGOS W/SPED-NEEDS 3 ELECTRICAL PLUGS TO BE INSTALLED. (LEVELED TO HIS DESK)	2/23/2006 Medium	Mary Garcia Carlos Castillo	Office	GAC A WING
9721	Work In Progress AS PER MR. HINOJOSA-NEEDS ASSISTANCE N HANGING PICUTRES THROUGHOUT GAC HALLWAYS. NEED HOOKS TO PLACE IN VARIOUS AREAS OF THE BUILDING. (MAP IS ATTACHED)	2/15/2006 Medium	Mary Garcia Manuel Prospero		GAC HALL WAYS @ GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9717	Work In Progress AS PER SAM GALLEGOS-OFFICE DOOR IS JAM AND KEY DOES NOT OPEN DOOR. (ALSO, THAT DOOR LOOKS LIKE IT HAS A CRACK) MANNY L. IS AWARE OF THIS 2/15- Lock was jammed open door but door needs to be replaced. As per Mike route to Danny Miranda 2/21/06 - mkv	2/15/2006 Medium	Mary Garcia Danny Miranda	Office	GAC A WING
9981	Work In Progress RTC Office - Transfer furniture to Portable 3 take computer from Margaret's Office to RTC Office.	2/24/2006 Medium	Selma Nevarez Ralph Lara		GAC
5824	Work In Progress NEED A WATERHOSE AND ALSO A HOSE ROLL A WAY.2 WATERHOSE ONE FOR THE PATIO AND ONE FOR THE PRE KINDER AREA I ONLY HAVE ONE AND I USE IT FOR THE FRONT AREA,THE HOSE ROLL A WAYS I NEED ONE FOR EACH HOSE THANK YOU FOR YOUR CONTINUED SUPPORT YOU ARE THE BEST!!!!	9/26/2005 Medium	Jimmy Carbajal Sal Acuna	Custodial	GAC
9281	Work In Progress NEED TO RE-KEY CUSTODIAL CLOSET IN "ON- TRACK" PRE-K BUILDING TO GAC BLDG MASTER.	2/2/2006 Medium	Aida Salcedo Manny Lozoya		GAC
3282	Work In Progress C-WING - TAKE OFF TILE AND INSTALL NEW TILE (TILE HAS BEEN DELIVERED), ALSO FINISH PAINTING. WILL SEND GERRY MARQUEZ TO ASSIST.	7/5/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
6050	Work In Progress Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		GAC
3546	Work In Progress Technology Server Room-Install Battery powered Emergency lighting in this room	7/14/2005 Medium	Carlos Castillo		GAC
9145	Work In Progress please install water line for misters on the east side of the pre-k. Plans are in your mail box.	1/30/2006 Medium	Guadalupe Ontiveros		GAC
9297	Work In Progress please cut weeds and rake in the entrance to the GAC and also do the same where new landscaping was done by the students. Please apply chemical if need be but be careful not to hurt the other plants.	2/3/2006 Medium	Manuel Prospero		GAC
9141	Work In Progress please do a line locate on the east side of the pre- k. Plans are in yor mail box	1/30/2006 Medium	David Villalobos		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9616	Work In Progress Install two electrical outlets in "new" office for Sam Gallegos, Diagnostician. (Please contact Margaret @ SPED for directions-Thanks)	2/13/2006 Medium	Carlos Castillo	Office	GAC
8338	Work In Progress Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Danny Orozco		GAC
8316	Work In Progress Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS
8382	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS
8379	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Fernando Moncayo		Gadsden HS
7095	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Fernando Moncayo		Gadsden HS
7791	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Fernando Moncayo		Gadsden HS
9546	Work In Progress please repair clean out that east of concession stand.	2/10/2006 Medium	David Villalobos	Football Field	Gadsden HS
10016	Work In Progress rm223 n.bldg,please remove electrical to unit and re-connect unit when installed.coordinate w/ Jose. Thanks	2/27/2006 Medium	Michael Mc Dermott	Classroom	Gadsden HS
5464	Work In Progress Need to paint stripings for student parking lot and east of Auto Shop.	9/13/2005 Medium	Michael Munoz	Parking Lot	Gadsden HS
7499	Work In Progress please re-route conduit and repair where kids get on roof by panther hut. north bldg.	11/21/2005 Medium	Enrique Sotelo	Classroom	Gadsden HS
7500	Work In Progress please replace disconnect to heating unit on the - S- wing north bldg. blades do not work properly.	11/21/2005 Medium	Jose Ambriz	Classroom	Gadsden HS
5458	Work In Progress need to restripe all parking lines ,handi-cap-arrowa etc.	9/13/2005 Medium	Michael Munoz	Parking Lot	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4916	Work In Progress please check and repair leak & secure drop ceiling in rm 142. possible safety hazard.	8/25/2005 Medium	Danny Miranda		Gadsden HS
3659	Work In Progress PLease install stair treads when they come in. Old english stair ways. I will order. See Mike INstall from main to old english stairs. FAXED PO 8/4/05 - MKV	7/19/2005 Medium	Mario Apodaca	Stairway	Gadsden HS
4448	Work In Progress Telescope observatory locate on the west side of the baseball field - Installl fencing around it to prevent vandalism	8/10/2005 Medium	Michael Munoz		Gadsden HS
6001	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
9375	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS
9372	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Fernando Moncayo		Gadsden HS
9331	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
3319	Work In Progress Yearly - Gadsden HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
3141	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
3479	Work In Progress All Campus - Need to replace old door knobs w/new levers.	7/12/2005 Medium	Hector Lozoya Manny Lozoya		Gadsden HS
7638	Work In Progress Girls BB Lockerroom - Connect Electric Water Heater.	11/29/2005 Medium	David Villalobos Michael Mc Dermott		Gadsden HS
4726	Work In Progress Royal vacuum is missing bag and brush, belt serial No.H93266101B GISD tag 014131	8/19/2005 Medium	Jesus Estrada Jimmy Carbajal		Gadsden HS
9596	Work In Progress PORTABLE NEXT TO NURSES OFFICE - NEED EMT PIPE AT CORNER OF BUILDING FOR COMPUTER DROPS. PLEASE CALL SILVER IN TECH FOR INFORMATION	2/10/2006 Medium	Cora Ramirez Michael Mc Dermott	Portables	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9432	Work In Progress need to replace key switches with regular two pole switches.	2/6/2006 Medium	Carlos Castillo Carlos Castillo	Classroom	Gadsden HS
8254	Work In Progress Need to replace return unit's disconnect	12/22/2005 Medium	Carlos Castillo Carlos Castillo	Cafeteria	Gadsden HS
8145	Work In Progress several light pole around cafeteria area are out. Already change lamps but still not working, need to change ballasts.	12/15/2005 Medium	Carlos Castillo Carlos Castillo		Gadsden HS
4311	Work In Progress PANTHER HUT porch entrance too dark security light doesn't work	8/8/2005 Medium	Fernando Moncayo Fernando Moncayo		Gadsden HS
4305	Work In Progress NORTH bus entrance gate keep falling, bottom rail all bent; Also needs new roller bearings for both gates thank you !!! [safety hazard]	8/8/2005 Medium	Fernando Moncayo Michael Munoz		Gadsden HS
4240	Work In Progress Need six wheels for large gates in NORTH parking lot THANK YOU!! 8/11 - Route to Ruben as per Mike	8/5/2005 Medium	Fernando Moncayo Ruben Ronquillo		Gadsden HS
3593	Work In Progress Need to repair or replace electrical conduit outside of CONCESSION STAND by GIRL'S GYM	7/15/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
4902	Work In Progress AG BLDG entry door, won't open or lock key just turns; Also WOOD SHOP entry door new lock doesn't work	8/25/2005 Medium	Fernando Moncayo Manny Lozoya		Gadsden HS
9147	Work In Progress Need a new metal door for BOY'S restroom in OLD ENGLISH 1st. floor. ASAP please, can't lock restroom to control vandalism THANK YOU!!	1/30/2006 Medium	Fernando Moncayo Danny Miranda	Restroom (Boys)	Gadsden HS
9672	Work In Progress Attn. MANNY LAZORDA; WEIGHT ROOM SOUTH door, has a broken panic bar locking mechanism THANK YOU!!!	2/13/2006 Medium	Fernando Moncayo Manny Lozoya		Gadsden HS
10081	Work In Progress PRESCHOOL sink is clogged up, run small cable through, but no luck, please assist THANK YOU!!	2/28/2006 Medium	Fernando Moncayo David Villalobos		Gadsden HS
9959	Work In Progress ATTN.MR.LAZOYA; Key stuck and almost broken in NORTH side door at WEIGHTROOM. Need you a.s.a.p THANK YOU!!!	2/23/2006 Medium	Fernando Moncayo Manny Lozoya		Gadsden HS
6609	Work In Progress Need to install fluorescent light lamps in ANNEX CORRIDOR, is too dark	10/20/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6607	Work In Progress LIBRARY EAST wall;There is a, wall keyed hose bib that is leaking	10/20/2005 Medium	Fernando Moncayo David Villalobos		Gadsden HS
7325	Work In Progress Attn. MR. AMBRIZ ;Need a combustion vent motor for VARSITY GYM reznor heaters.MTR. is 208/230 volts	11/14/2005 Medium	Fernando Moncayo Jose Ambriz	Gym	Gadsden HS
7301	Work In Progress BOY'S GYM SOUTH EAST exterior door need to be replace	11/11/2005 Medium	Fernando Moncayo Danny Miranda	Gym	Gadsden HS
8896	Work In Progress Attn. MR. JOJO AMBRIZ;Will need to replace a/c's in rooms 750,752and 753 MC-6500 side draft	1/19/2006 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
8932	Work In Progress MR.CASTILLO;When you have a chance please drop by ghs with two plug-in photocell 120v THANK YOU!!	1/20/2006 Medium	Fernando Moncayo Carlos Castillo		Gadsden HS
8629	Work In Progress Attn; MR. JO,JO AMBRIZ,need a vent motor for VARSITY GYM reznor heater unit	1/11/2006 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
8695	Work In Progress Requested by Ms. Li Rm. 339 Academic Building- Door does not lock.	1/12/2006 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
8687	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-Ovens not working at all. First and third ovens on the right side of kitchen, possibly a problem with the outlets.	1/12/2006 Medium	Velia Alarcon Danny Orozco		Gadsden HS
8688	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-Dishwasher not pulling cleaner or rinse products, only pulls sanitizer.	1/12/2006 Medium	Velia Alarcon Danny Orozco		Gadsden HS
8691	Work In Progress Requested by Chief Arms Rifle Range/Adjacent to Boys Gym-Rifle Range is coming loose in numerous panels and range is no longer secure. Recommend a permanent wall or welded metal plating. Kids are using basketballs to break the screens; also maintenance caught three kids in the rifle range before break.	1/12/2006 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
	Note from Mr. Foster: THIS IS IMPORTANT! Route to Bldg Mechanic as per Mike - 2/8/06 -mkv				

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
8693	Work In Progress Requested by Ms. Barreras Main Building Women's Faculty Restroom-Light switch cover in restroom has caused electrical shock with any kind of moisture when touched to be turned off. Is an endanerment to anyone who may touch it with any kind of moisture on their hands.	1/12/2006 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
8696	Work In Progress Requested by Mrs. Quinones Rm. 653 Busines Building-Replace florescent light bulbs.	1/12/2006 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
8689	Work In Progress Requested by Ms. Anderson Rm. 233 Panter Hut-Mice in Panther Hut.	1/12/2006 Medium	Velia Alarcon Margret Villalobos		Gadsden HS
8802	Work In Progress Requested by Velia Rm. 327 Academic Building-The handicap stall toilet leaks when flushed, not all the water goes down the drain. SAFETY HAZARD!	1/17/2006 Medium	Velia Alarcon David Villalobos		Gadsden HS
8803	Work In Progress Requested by Mr. Cordova Rm. 331 Academic Building-Light in middle of room, burned out or not working.	1/17/2006 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
8946	Work In Progress Requested by Ms. Lopez Rm. 605 Business Building-Replacement of school lock on the second floor of the Business Building elevator, due to it not being able to find an original key to open the Master Pad. Lock currently on the door.  Please contact Ms. Lopez for information regarding the type of lock to be placed on the door.	1/23/2006 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
8534	Work In Progress Requested by Velia Rm. 112 Front Office-One key of D47 is needed for key box, for room 125. Ms. Holguin's classroom.	1/9/2006 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
8179	Work In Progress Requested by Mr. Contaldo Campus Observatory- Install 6' chain link fence around Observatory Deck with locking gate. Key problem: prevent future vandalism. 1/11 - Route to Lupe as per Mike.	12/16/2005 Medium	Velia Alarcon Guadalupe Ontiveros		Gadsden HS
8182	Work In Progress Requested by L. Melendrez Rm. 333 Academic Building-Classroom walls need to be repaired. There are holes in the walls and it needs to be repainted.	12/16/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
8185	Work In Progress Requested by Ms. Trich Library-The drawer slides for the cashbox are loose. They may be missing screws to attach them to the base. Might someone please assess the situation to determine if the present one can be repaired or if they need replacement? Please check with Leslie, this is a safety issue; the drawer may fall out of the base.	12/16/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
8178	Work In Progress Requested by Mr. Contaldo Campus Observatory-Fix or replace limiting switches on Observatory hatch. Existing switches may (?) be fixed by bending metal contact plates to correct position. Key problem: need to be able to open and close hatch. Replace or fix white light bulbs inside Observatory.	12/16/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
8068	Work In Progress Requested by Mr. Chambers North Building Project-Temporarily remove cable from North Building Lockers by Saturday, Dec. 17. (For Columbia University Film Documentary)	12/13/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
8087	Work In Progress Requested by Mr. Whitener Rm. 562 Ag. Shop-The exhaust fans in both restrooms have been disconnected, requesting that they both be reconnected.	12/13/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS
8081	Work In Progress Requested by Ms. Trich Rm. 275 Library-Tops of the short book shelves are losing the laminate, which is peeling off. Please re-attach the laminate tops. Please check with either Bonnie or me.	12/13/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6273	Work In Progress Requested by Velia Rm. 100 Main Building-All of the doors and drawers need to be tightened, they're all off their tracks or broken.	10/11/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6282	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop-Paint (or provide paint)for repainting the tool room and paint room. Second Request	10/11/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
6274	Work In Progress Requested by Mr. Chambers Varsity Gym-Varsity Gym floor is showing large space and boards are coming loose, needs repair a.s.a.p. SAFETY ISSUE	10/11/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6454	Work In Progress Requested by Mr. Chambers Football Restrooms- Paint large letters on restroom indicating men's and women's sides, or hang large signs indicating directions.	10/17/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6460	Work In Progress Requested by Mr. Whitener Rm. 563 Ag. Shop- Install a hydraulic door closer on the new front door to the building.	10/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
6713	Work In Progress Requested by Ms. Trich Library-Please replace blown light bulbs, especially in Librarian's office, room 275b.	10/25/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6710	Work In Progress Requested Ms. Nanez Library-Backs to shelves need to be installed. Backs are in library, however, they need to be cut down to fit.	10/25/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
6830	Work In Progress Requested by Velia Rm. 127 Main Building-When the sound system contractors installed the wiring in Ms. Garcia's classroom. They placed it on a wall Ms. Garcia used for her projector. Once they removed the wiring and placed it on another wall, they left the wall scrated and paint peeled. Wall needs to be repaired and painted.	10/28/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6833	Work In Progress Requesed by Luis Saucedo Main Building-East and west hallways the light switchs are broken. Having a problem turning on the lights every morning. Light switches on each corner.	10/28/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
7145	Work In Progress Requested by Ms. V. Lopez Old Counseling Center-Repair hole in ceiling near new ventilation work.	11/7/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
7370	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop- 2ND REQUEST Replace ceiling tile in office storeroom. Consider placing a plywood floor over unprotected tile.	11/15/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
7626	Work In Progress Requested by Mr. Foster and Mr. Chambers Varsity Gym-ATTN: Mike Munoz Replace heating units and duct work. *Girls team practiced in 23 degrees this morning in the gym. *Parents calling and complaining about conditions. *Parents calling Central Office.	11/29/2005 Medium	Velia Alarcon Jose Ambriz	Gym	Gadsden HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
7914	Work In Progress Requested by Ms. Hunt Rm. 105 Main Building- Cupboard door broke off, screws on my desk.	12/7/2005  Medium	Velia Alarcon Mario Apodaca		Gadsden HS
7915	Work In Progress Requested by Mr. Contaldo Campus Observatory- Close hatch door on observatory, check out electrical connection for motor drive and white overhead lights. route to Mike Mc Dermott - As per Mike Munoz 12/12/05 - mkv	12/7/2005  Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
7913	Work In Progress Requested by Cathy Cano Concession Stand- Windows to concession stand need to be put back on. Reasons: cold, and too many flies and/or bees. Route to Bldg Mechanic as per Mike Munoz 12/16/05 - mkv	12/7/2005  Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
9972	Work In Progress Requested by Mr. D. Martinez North Building Main Hallway-Some tiles in the main hallway are damaged and are a hazard for parents, students, and teachers.	2/24/2006  Medium	Velia Alarcon Michael Munoz		Gadsden HS
9909	Work In Progress Requested by Dolores Nanez Library-Anchor wall (partition) has glass window and shelves, made of wood.	2/22/2006  Medium	Velia Alarcon Mario Apodaca		Gadsden HS
9905	Work In Progress Requested by Josie Enriquez Day Care Playgroun-Debris on playground needs to be removed, as per licensing. Playground needs to be maintained.	2/22/2006  Medium	Velia Alarcon Guadalupe Ontiveros		Gadsden HS
10034	Work In Progress Requested by Mr. Grubaugh Rm. 275C Library- Toilet in the boy's restroom won't quit flushing.	2/27/2006  Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
10031	Work In Progress Requested by Velia North Building-Door connecting Main North Building hallway and Varsity Gym does not want to open with the HE1 key, needs repair.	2/27/2006  Medium	Velia Alarcon Manny Lozoya		Gadsden HS
10033	Work In Progress Requested by Ms. Masters Rm. 121 Main Building- Classroom 121 has 2 doors. As you face the classroom from the outside in the hall, the on the right is broken. It will not lock. It will not catch the latch, anyone can push it open.	2/27/2006  Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
10035	Work In Progress Requested by Mr. Palmer Rm. 229 North Building- 1.) Remove permanent desks that stick out into room. (There's 7 of them.) 2.) Relocate the gas and electrical outlets to the side counters. *Call me before work begins so I can clean out stored items.	2/27/2006 Medium	Velia Alarcon Michael Munoz		Gadsden HS
9824	Work In Progress Requested by Mr. Chambers Weightroom-Need double doors at the Weightroom repaired to protect new equipment. Need dead bolts with keys installed on side doors (two way).	2/17/2006 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
9823	Work In Progress Requested by Mr. Chambers All G.H.S. Buildings- Paint all G.H.S. Buildings with maroon trim (outside)-doors, windows, and flashing etc.	2/17/2006 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
9819	Work In Progress Requested by Velia Old English Building (Lobby Area)-Replace light bulbs in Lobby Area between Social Worker's office and Speech Therapist's office.	2/17/2006 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
9681	Work In Progress Requested by Velia Light Room in Varsity Gym- The door that opens the storage room for our Light Switch Board in the Varsity Gym on the stage is not opening, might be the door handle. Also, the opposite doors on the stage do not want to open, the door knob is not working properly.	2/14/2006 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
9685	Work In Progress Requested by Ms. Foote Rm. 332 Academic Building-Replace ceiling light bulbs. ROUTE TO BM - AS PER MIKE 2/17/06	2/14/2006 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
9688	Work In Progress Requested by David Vega Rm. 243 Classroom Over Varsity Gym-Needs a few light bulbs replaced, on one of the lights. ROUTE TO BM - AS PER MIKE 2/17/06	2/14/2006 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
9686	Work In Progress Requested by David Vega Business Building- Light switch on north wall, bottom floor needs to be replace.	2/14/2006 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
9684	Work In Progress Requested by Mr. Carrasco Rm. 581 Auto Shop- Cieling lamps are out, they need new lamps. ROUTE TO BM - AS PER MIKE 2/17/06	2/14/2006 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
9451	Work In Progress Requested by Velia Rm. 112 Front Office-Two keys of HE25 are needed for Key Box; room 200, Ms. A. Torres' classroom.	2/7/2006 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9102	Work In Progress Requested by Ms. Nanez Library Girls Restroom-Toilet #2 leaks from top pipe when it is flushed.	1/27/2006 Medium	Velia Alarcon David Villalobos		Gadsden HS
9230	Work In Progress Requested by Velia Rm. 112 Front Office-Ms. Hamilton's classroom door does not want to lock, she's in room # 562.	2/1/2006 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
9232	Work In Progress Requested by Jenny Gonzalez Rm. 250 Computer Lab-Light bulb needs to be replaced in the Boys Restroom.	2/1/2006 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
9276	Work In Progress Requested by Velia Rm. 112 Front Office-Pad lock are needed to be placed on roll down metal shades in the Concession Stand at the Football Field and three sets of keys will be needed. Students have been raising the metal shades climbing into the Concession Stand and ditching for the day. The doors are also very easily kicked and forced open, please repair as soon as possible.	2/2/2006 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
9093	Work In Progress Requested by Velia Rm. 112 Front Office-Two keys of HE203 are needed for Key Box; for Concession Stand at Football Field.	1/27/2006 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
9094	Work In Progress Requested by Velia Rm. 112 Front Office-Key broke inside cylinder, we need lock fixed and also, please complete Work Order # 4362. Five keys are needed of HE1 (Gym Key), three keys are now broken and need replacing.	1/27/2006 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
9098	Work In Progress Requested by Mr. Contaldo Observatory-Close and lubricate observatory dome as soon as possible.	1/27/2006 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
9101	Work In Progress Requested by Ms. Jacquez Rm. 752 Barracks-Mount flags on wall.	1/27/2006 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
9111	Work In Progress Requested by Ms. Lam Women's Restroom Main Building-The door can not be locked, with the key given to us. Students are using the restroom.	1/27/2006 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
9096	Work In Progress Requested by Mr. Carrasco Rm. 581 Auto Shop-Mount strut press on wall.	1/27/2006 Medium	Velia Alarcon Mario Apodaca		Gadsden HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
9097	Work In Progress Requested by Mr. Carrasco Rm. 581 Auto Shop- Repair air leak on Hunter car lift. Routed to Mario as per Mike 1/30/06 - mkv	1/27/2006  Medium	Velia Alarcon Mario Apodaca		Gadsden HS
9099	Work In Progress Requested by Mr. Contaldo Observatory-Replace power cord going to white light bulbs on top, inside of dome.	1/27/2006  Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
9100	Work In Progress Requested by Mr. Contaldo Observatory-Replace acciator switches.	1/27/2006  Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4905	Work In Progress Requested by Mr. Milligan Rm. 143 Old English Building-Four keys are needed of HX2. Three for the assistant coaches and one for key box.	8/25/2005  Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4810	Work In Progress Requested by Ms. L. Chavez Rm. 245 Classroom Over Varsity Gym-Re-place several burned out light bulbs. RE-ROUTE TO BUILDING MECHANIC as per Mike Mc Dermott 9/19/05	8/23/2005  Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4820	Work In Progress Requested by Luis Saucedo Rm. 507 & 509 Annex Building-Install door stops on each of these doors.	8/23/2005  Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4822	Work In Progress Requested by Ms. Zapien Rm. 154 Old English Building-The blinds are completely broken, the curtain is hanging.	8/23/2005  Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4811	Work In Progress Requested by Mr. Cordova Storage Room in Varsity Gym Stage-The door needs to be re- keyed to an off master key, light board room. 4 keys are needed.	8/23/2005  Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4812	Work In Progress Requested by Lt. Dickerson Rm. 202 North Building-His HEM key has broken, 3 HEM keys are needed. One for him and two for the key box.	8/23/2005  Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4816	Work In Progress Requested by Ms. L. Melendrez Rm. 331 Academic Building-I have been having trouble opening my front door for over a year, and now I am having trouble opening the back door. It's not my key it's the door handle and deadbolts. Both back doors are very difficult to open.	8/23/2005  Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4817	Work In Progress Requested by Mr. S. Perez Weight Room-Boys locker room door handle needs repair does not open. West side Weight Room door needs repairs does not lock.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5084	Work In Progress Requested by Velia Press Box-Safety Hazard; need to re-duct and install new air conditioner were it can be serviced. FERNANDO, JOSE WILL LOOK INTO ORDERING UPDRAFT UNIT AND SHEETMETAL. AS PER OUR CONVERSATION YOU AND MARIO WILL FORM AND POUR CONCRETE FOR SMALL PAD FOR A/C STAND. IN THE MEAN TIME SERVICE WHAT IS THERE. - M. MUNOZ 9/1/05-MKV XC: WO TO FERNANDO	8/30/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS
5083	Work In Progress Requested by Mr. Martin Rm. 551 Wood Shop-Hall lock will no unlock, 2nd Notice.	8/30/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4904	Work In Progress Requested by Mr. D. Gallegos Rm. 403-Please install water fountains with hose bibs, between soccer canopies for Athletic events and Gadsden High School P.E. classes.	8/25/2005 Medium	Velia Alarcon Guadalupe Ontiveros		Gadsden HS
4897	Work In Progress Requested by Velia Rm. 112 Front Office-Two HE27 are needed for key box.	8/25/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4814	Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Air conditioner still does not work. No air is coming out of vents, very hot. Wires hanging into light fixture and a piece of ceiling tile (broken) is in one of the air conditioning vents. (room was damaged over summer)	8/23/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4630	Work In Progress Requested by Mr. Dixon Rm. 600 Business Building-Needs an F3 gate key.	8/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4633	Work In Progress Requested by ISS Rm. 800 Old Counseling Center-Door frame falling off portable door leading to the old counseling center.	8/17/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS
4627	Work In Progress Requested by Velia Rm. 112 Front Office-Work order #3911 was not asked to me made off master, also three keys were asked for not two. An additional 4 keys are needed as soon as possible.	8/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4521	Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Need a lock and spare keys on the new filing cabinet.	8/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4516	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-New water heater for kitchen area of Panther Hut. Route to Bldg Mechanic as per Mike 8/15/05 Check to see whats wrong with the H2o heater they have new one in small mech. room.	8/12/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4631	Work In Progress Requested by Ms. M. Gonzalez Rm. 140 Old English Building-I would like to request a door stop for the new door and blinds fo one of my windows. The room gets "very" warm especially 4th period. Receive measurements from Bldg Mechanic and re-route to Ruben for ordering. 4 ea - 43" W x 90' L	8/17/2005 9/16/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
4562	Work In Progress Requested by Ms. Klein Rm. 504 Annex Building-Air conditioner not working and appears to be leaking.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4564	Work In Progress Requested by Ms. Nanez Library-Install plywood baks to magazine shelves.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
5601	Work In Progress Requested by Ms. Thornley Rm. 660 Business Building-No heat/A.C. in lounge. Please attempt to tie into the ducting in my classroom (it has it's own system and is immediately adjacent) so that our lounge can be more comfortable.	9/19/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS
5412	Work In Progress Requested by D. Gallegos Rm. 403 Boys Gym-Install threaded end on faucet or shower in volleyball and boys basketball lockers to allow for a water hose connection.	9/12/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
5405	Work In Progress Requested by Velia Rm. 112 Front Office-HG3 is needed for key box.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5406	Work In Progress Requested by Velia Rm. 112 Front Office-Two SA16 are needed, one for Ms. Dominguez and one for key box.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5407	Work In Progress Requested by Marie School Registrar Storage Room East Wing of the Cafeteria-The new vault needs to be re-keyed. The cylinder from the old vault can be placed on the door of the East Wing of the Cafeteria were her new vault is located now.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5409	Work In Progress Requested by Marie Storage Room in the East Wing of the Cafeteria-In the move from the old vault to the storage room one of the fire prove filing cabinet's locks broke. The filing cabinet remained locked, needs to be fixed as soon as possible as the Registrar needs access to these files on a daily basis.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4386	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- 220 Volt Electric extension cord needed with a new female end, current ones puts people at risk of electrocution.	8/9/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4272	Work In Progress Requested by Ms. Klein Rm. 504 Annex Building- Having a hard time locking and opening door, appears to be locked but stays unlocked.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4279	Work In Progress Requested by Ms. Littlefield Rm. 226 North Building-The lock on my podium and one storage cabinet is brocken and lost.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4283	Work In Progress Requested by Mr. Myers Rm. 509 Annex Building- Key will not open storage door. HJ10 is the key that should open door.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4286	Work In Progress Requested by Mr. Villa Rm. 510 Band Room-Need two HK13 keys made.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4248	Work In Progress Requested by Ms. Gutierrez Rm. 823 Barracks- New cylinder is needed for new filing cabinet, 3 keys are needed.	8/5/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4243	Work In Progress Requested by Ms. Bradley Rm. 602 Business Building-Handle on window has broken off, needs to be replaced.	8/5/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4269	Work In Progress Requested by Ms. Jacquez Rm. 752 Barracks- Window is unhinged and needs to be repaired.	8/8/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4282	Work In Progress Requested by Mr. Martinez Rm. 227 North Building-Replace carpet in Attendance Office area. One edge of the carpet is lifting, our concern is that a person may trip and fall.	8/8/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
4271	Work In Progress Requested by Ms. Kalkwarf Rm. 750 Barracks-Floor tiles are broken and coming off the floor.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4285	Work In Progress Requested by Mr. Villa Rm. 510 Band Room-Security light in the center of the room does not work.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4429	Work In Progress Requested by Velia Rm. 112 Front Office-Three HE keys are needed for Key Box.	8/10/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4360	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HJ7, one for the floating teacher and one for the Key Box. For room number 753.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4361	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK1, one for the floating teacher and one for the Key Box. For the Auto Shop.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4362	Work In Progress Requested by Velia Rm. 112 Front Office-We need 5 additional keys of HE1. For the Gyms.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4363	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK5, one for the I.A. in the classroom and one for the key box. For room number 569.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4204	Work In Progress Requested by Cathy Cano Parking Lot-Over Fall Break, have the lines in the North Parking Lot painted.	8/4/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
4166	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace ceiling tile in storeroom and office.	8/3/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4222	Work In Progress Requested by Mr. Grubaugh Rm. 275C Library-The door to the video room has swollen and will not shut properly unless its slammed.	8/4/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4199	Work In Progress Requested by Mr. Chambers Rm. 110 Front Office-Re-key doors, make cylinders off D Master, 4 keys will be needed. Have had several items stolen from office, please re-key as soon as possible.	8/4/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4153	Work In Progress Requested by Mary Barreras Rm. 130 Old English Building-Need the new key to new lock to Sp. Ed. storage room for files and equipment. Key # M260	8/3/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3493	Work In Progress Requested by Pamela Holguin Rm. 228 North Building-A door frame is needed. Will have an old door installed, left over from doors that are being replaced in North Building. Also, a door knob that will not lock is needed.	7/12/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS
3494	Work In Progress Requested by Marie New Counseling Center Portable-New portable needs to be keyed HE134. Change old cylinder to doors of new portable doors.	7/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3715	Work In Progress Requested by Mr. Pawloski Rm. 109A Main Building (Sp.Ed. Office)-Please remove the lock in my file cabinet, replace, and re-key it with a new one.	7/20/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3716	Work In Progress ***URGENT***Requested by Velia Library-All the doors in the library need to be secured. They have changed all the door knobs and the cylinders need to be installed. URGENT library has alot of equipment that needs to me locked and secured!	7/20/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3910	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Bracket needed for N.M. Flag.	7/28/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
3902	Work In Progress Requested by Ms. Marquez New Counseling Portable-Two filing cabinets need to be keyed.	7/28/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3920	Work In Progress Requested by Velia Front Office-The cylinder for room #107 will not open with a D Master or key assigned to door. This classroom is the Day Care on our campus and the building custodian can not open the classroom to clean. Please fix as soon as possible.	7/28/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3908	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Dr. Pockets to be placed in Marie's copy to be placed on wall.	7/28/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
3909	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Install clock on wall.	7/28/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
9622	Work In Progress NEED LOCK BACK TOO A F3 KEY ON GUARD HOUSE ON NORTH SIED	2/13/2006 Medium	Mario Apodaca Manny Lozoya		Gadsden HS
9697	Work In Progress THE WATER BOILER AT CAFETERIA ARE RUSTING	2/14/2006 Medium	Mario Apodaca David Villalobos		Gadsden HS
9696	Work In Progress NEED #5 FIRE EXTINGUISHER CABINETS FOR THE N/BLDG 10 LB DRY CHEMICAL SURFACEMOUNT	2/14/2006 Medium	Mario Apodaca Danny Orozco		Gadsden HS
10003	Work In Progress MIRROR AT GIRLS GYM NEED TOBE REPLACES PRESCHOOL KIDS BROKIT	2/24/2006 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
9923	Work In Progress NEED NEW BEARINGS FOR FAN BLOWER AT ROOM 223 N-BLDG	2/22/2006 Medium	Mario Apodaca Jose Ambriz		Gadsden HS
10007	Work In Progress ROOF LEAK AT NEW RESTROOM BOY SIDE AT FOOTBALL FIELD	2/24/2006 Medium	Mario Apodaca David Boyd	Football Field	Gadsden HS Roof
10036	Work In Progress NEED A NEW DOOR AT OLD ENG BOY RESTROOM DO TOO VANDALISM	2/27/2006 Medium	Mario Apodaca Danny Miranda		Gadsden HS
9266	Work In Progress NEED TOW LACK FOR CONCESSION STAND AT FOOTBALL FIELD	2/2/2006 Medium	Mario Apodaca Manny Lozoya		Gadsden HS
8582	Work In Progress NEED NEW E/COOLER AND DUCTING FOR BOY GYM	1/9/2006 Medium	Mario Apodaca Jose Ambriz		Gadsden HS
8584	Work In Progress NEED NEW E/COOLER AT ROOM 506 ANNEX BLDG	1/9/2006 Medium	Mario Apodaca Jose Ambriz		Gadsden HS
8585	Work In Progress NEED NEW E/COOLER AT GIRLS LOCKROOM ROOM 237 V-GYM	1/9/2006 Medium	Mario Apodaca Jose Ambriz		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
8095	Work In Progress NEED A NEW FLOODLIGHT FIXER FOR THE SCHOOL SIGN AT FRONT OF CAMPUS.	12/13/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
8901	Work In Progress CAFETERIA KITCHEN - TOW FLOOR MOP SINK IS LEAKING NEEDS TO BE RESET TO P-TRAP.	1/20/2006 Medium	Mario Apodaca Danny Orozco	Cafeteria	Gadsden HS
8996	Work In Progress NEED TO CK ALL BREAKER AT ACADEMIC BLDG SAME AER LOSS AT ELECTRICAL ROOM 338 . MR CARLOS C	1/24/2006 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
8717	Work In Progress NEED TO REKEY RESTROOM AT MAIN BLDG FOR STAFF	1/12/2006 Medium	Mario Apodaca Manny Lozoya		Gadsden HS
8714	Work In Progress NEED A NEW E/COOLER AT FOOTBALL FIELD PRESS BOX	1/12/2006 Medium	Mario Apodaca Jose Ambriz	Football Field	Gadsden HS
6526	Work In Progress NEED TOO RUN SEWER SNAKE AT WOOD SHOP BLDG unclog main sewer line to woodshop	10/18/2005 10/19/2005 Medium	Mario Apodaca David Villalobos		Gadsden HS
6425	Work In Progress NEED TO REMOVE ALL OUTLET AT ROOM 126 AT ARE ON BOOK SHEVING FLOOR AND RELOCA OUTLETS	10/14/2005 Medium	Mario Apodaca Michael Mc Dermott	Custodial	Gadsden HS
7277	Work In Progress NEED TO PUT CRUSH ROCK ON ROAD BY THE WOOD SHOP , ANNEX BLDG AND POOL SO DUST WOOD NOT P-PU ASAP	11/10/2005 Medium	Mario Apodaca Guadalupe Ontiveros		Gadsden HS
7239	Work In Progress NEED KEY FOR TOW FILE CABINETS AT ROOM 223	11/9/2005 Medium	Mario Apodaca Manny Lozoya		Gadsden HS
7886	Work In Progress NEED TO REPAIR ALL DOOR FRAMS AT THE WEIGHT ROOM THE KID WILL PULL THE DOOR OPEN W/THE DOOR ARE LOCK	12/6/2005 Medium	Mario Apodaca Danny Miranda		Gadsden HS
7956	Work In Progress Vandalism - Damage to south front entrance roll gate hit by vehicle. (Case# 2005-10383) Deputy Isidro Gonzalez #935	12/2/2005 Medium	Mario Apodaca Michael Munoz		Gadsden HS
5108	Work In Progress NEED TO PUT NEW BALLAST AT WOOD SHOP LAMPES	8/31/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4970	Work In Progress GLASS AT MAIN BLDG HALLWAY 40X18 NEED TOBE REPLACES VANDALISM	8/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
4976	Work In Progress NEED ALL WINDOW BLINDSON OLD ENGLISH BLDG 40 EA 40WX90L	8/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
5842	Work In Progress NEED A NEW GLASS PUT ON CONCESSION STAND WINDOW AT FOOTBALL FIELD (VANDALISM) 23X23 ASAP	9/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
3524	Work In Progress NEED TO FIX FOOTBALL FIELD SCOREBOARD BREAKER BOX	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
3525	Work In Progress NEED TO CK ALL FOOTBALL FIELD LAMPS	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
4502	Work In Progress NEED TO LAMPES AT WOOD SHOP SAME ARE BURNED OUT	8/11/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
8193	Work In Progress please repair the goal on the northeat side.	12/19/2005 Medium	Michael Munoz Michael Munoz	Gym	Gadsden HS
8844	Work In Progress AS PER MR. CHAVEZ OVER AT THE GHS ACADEMIC BUILDING BOYS RESTROOM ON THE WEST SIDE NEEDS A PARTION BETWEEN HANDICAP & REGULAR TOILET.	1/18/2006 Medium	Mary Garcia Danny Miranda	Restroom (Boys)	Gadsden HS GHS ACADEMIC BLDG
9172	Work In Progress GHS pool needs an emergency cut-off switch for circulating pump installed outside of pump room as per pool inspection 2005 report	1/30/2006 Medium	Raul Sanchez Michael Mc Dermott	Parking Lot	Gadsden HS
9061	Work In Progress need to add another inline filter house for ARSENIC removal as per NMED.	1/26/2006 Medium	Ricardo Jacquez Ricardo Jacquez		Gadsden MS
8845	Work In Progress DOUBLE DOORS INSIDE BAND ROOM WHERE INSTRUMENTS ARE STORED DO NOT LOCK AND SECURE PROPERLY. EQUIPMENT SAFETY ISSUE.	1/18/2006 Medium	Maria Sitters Danny Miranda		Gadsden MS
9038	Work In Progress Main Gym - pulled handle and broken, tagging on door, mirror and baseball dugouts.	1/23/2006 Medium	Rudy Arreola Rudy Arreola		Gadsden MS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
9003	Work In Progress We need a new handle behind gym annex handle was pulled and broken off.	1/24/2006 Medium	Rudy Arreola Manny Lozoya		Gadsden MS
9004	Work In Progress Rm #114 cylinder is stuck and wont turn and door needs to be secured for the end of the day.	1/24/2006 Medium	Rudy Arreola Manny Lozoya		Gadsden MS
9002	Work In Progress Sink is clogged we need the snake. to run it threw the wall drain.	1/24/2006 Medium	Rudy Arreola Joe Ontiveros		Gadsden MS
8468	Work In Progress We need to have front office fumigated big and small roaches when you turn on the lights.	1/6/2006 Medium	Rudy Arreola Margret Villalobos		Gadsden MS
8471	Work In Progress Just a reminder on how the push lawn mower is coming along. for GMS.	1/6/2006 Medium	Rudy Arreola Angel Gonzales		Gadsden MS
8472	Work In Progress We have broken water line front of the school.	1/6/2006 Medium	Rudy Arreola Guadalupe Ontiveros		Gadsden MS
8603	Work In Progress Backflow in B-WING is leaking water.	1/10/2006 Medium	Rudy Arreola Guadalupe Ontiveros		Gadsden MS
8602	Work In Progress Back flow in A-WING is leaking water.	1/10/2006 Medium	Rudy Arreola Joe Ontiveros		Gadsden MS
6386	Work In Progress Light on the westside of the bandroom doesnt turn on.	10/13/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
9422	Work In Progress Need to replace water fountain all the front of the water is broken.	2/6/2006 Medium	Rudy Arreola Lorenzo Solis	Restroom (Boys)	Gadsden MS
9494	Work In Progress MAIN BLDG - NEED EMERGENCY LIGHTS IN HALLWAYS AND RESTROOMS AS PER PM 9373.	2/8/2006 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
9495	Work In Progress ANNEX GYM - ONE EXIT SIGN NOT WORKING DOOR LEADING TO BUS TURNAROUND. AS PER PM 9378.	2/8/2006 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
9590	Work In Progress Boiler RM in B-WING not heating B-WING area.  Called Control and Equipment	2/10/2006 Medium	Rudy Arreola Margret Villalobos		Gadsden MS
9031	Work In Progress We have water leak by nurses office. in the middle of the hallway.	1/25/2006 Medium	Rudy Arreola Rudy Arreola		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9032	Work In Progress We have a water leak in the hallway right outside RM#119 its also leaking onto the lights and lockers.	1/25/2006 Medium	Rudy Arreola Rudy Arreola		Gadsden MS
9033	Work In Progress We have water leak in RM 119 in the corner of the room.	1/25/2006 Medium	Rudy Arreola Rudy Arreola	Classroom	Gadsden MS
9150	Work In Progress We need 2 cylinders changed so they can match the WA-94 key to the classroom and storage RMS	1/30/2006 Medium	Rudy Arreola Manny Lozoya	Classroom	Gadsden MS
9940	Work In Progress Water fountain by cafeteria has being damaged this is happening afterschool all the pushbar has being kicked in .	2/23/2006 Medium	Rudy Arreola Lorenzo Solis		Gadsden MS
9939	Work In Progress Wall on the eastside of storage office is being pushed in and there is a crack all along edge.	2/23/2006 Medium	Rudy Arreola Michael Munoz	Library	Gadsden MS
10030	Work In Progress Rm 403 door cant be opened or locked.	2/27/2006 Medium	Rudy Arreola Manny Lozoya	Classroom	Gadsden MS
9591	Work In Progress Three way valve in unit is getting stuck needs to be replaced in RM 116	2/10/2006 Medium	Rudy Arreola Lorenzo Solis	Classroom	Gadsden MS
4218	Work In Progress Coil in not cooling cleaned out strainer and checked valve. RM 156	8/4/2005 Medium	Rudy Arreola Jaime Gomez	Classroom	Gadsden MS
4220	Work In Progress Rm 157/158 Unit is not cooling at all cleaned out strainer and checked valves.	8/4/2005 Medium	Rudy Arreola Jaime Gomez	Classroom	Gadsden MS
4725	Work In Progress Portable 500/501 really leak bad right in the center of the room.	8/19/2005 Medium	Rudy Arreola Rudy Arreola	Portables	Gadsden MS
4528	Work In Progress We need 2 water fountains replaced in cafeteria.	8/12/2005 Medium	Rudy Arreola Jaime Gomez		Gadsden MS
5793	Work In Progress {{{GYM LOBBY}}} Wall needs to be secured.	9/23/2005 Medium	Rudy Arreola Danny Miranda	Restroom (Boys)	Gadsden MS
5918	Work In Progress Door handle is broken off boys lockerroom	9/28/2005 Medium	Rudy Arreola Manny Lozoya		Gadsden MS
5317	Work In Progress Need to cap of water lines and drain removed already removed sink and counters. RM#188.	9/7/2005 Medium	Rudy Arreola Joe Ontiveros	Classroom	Gadsden MS



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5569	Work In Progress VOC BLDG RM#306 - Need some assistance changing out ballast already replaced lamps high ceiling.	9/16/2005 Medium	Rudy Arreola Enrique Sotelo	Classroom	Gadsden MS
5119	Work In Progress Power Outage - El Paso Electric	8/29/2005 Medium	Margret Villalobos Enrique Sotelo		Gadsden MS
3616	Work In Progress replace door at pump room	7/18/2005 Medium	Ricardo Jacquez Danny Miranda		Gadsden MS
9285	Work In Progress Small gate by the old Library Services Portable, needs to be fixed. It cannot be closed or locked.	2/2/2006 Medium	Yolie Jacquez Michael Munoz		Gadsden MS
7479	Work In Progress Also at GMS Gym Bleachers They have a cheap extension for the score board, could we get a permanent 120v outlet fastened to front of bleachers? thanks , Carlos	11/18/2005 Medium	Carlos Vigil Enrique Sotelo		Gadsden MS
4778	Work In Progress 2nd request for an "A" master for GMS Campus	8/22/2005 Medium	Dana Hamel Manny Lozoya	Office	Gadsden MS
4777	Work In Progress The three locks on the office front window are broken, mostly poor design. The front office is wide open until these are repaired or replaced	8/22/2005 Medium	Dana Hamel Rudy Arreola	Office	Gadsden MS
4643	Work In Progress Need a copy of fire alarm key (See Mr. Hamel for his key).	8/17/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
4522	Work In Progress Door broken in room 500, and window shattered	8/12/2005 Medium	Dana Hamel Danny Miranda	Portables	Gadsden MS
4982	Work In Progress Whole south side of annex does not have any air, class temperatures are above 95 degrees. The classes opposite hallway have conditioning, Please fix ASAP	8/26/2005 Medium	Dana Hamel Jaime Gomez	Classroom	Gadsden MS
6241	Work In Progress The new roof on the vocational building leaked badly over vacation and the insulation in the old woodshop is falling. Serious problem with students returning tomorrow could fall at any time.	10/10/2005 Medium	Dana Hamel David Boyd	Classroom	Gadsden MS
5499	Work In Progress Change M4 key to a G key in all electrical room on campus, we have no "m" master	9/14/2005 Medium	Dana Hamel Manny Lozoya	Electrical Room	Gadsden MS
5500	Work In Progress change A3 key to a "g" key in storage room in annex	9/14/2005 Medium	Dana Hamel Manny Lozoya	Mechanical Room	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5501	Work In Progress Repair the outside doors locks "w" master will not open doors to lobby	9/14/2005 Medium	Dana Hamel Manny Lozoya	Hallway/Corridor	Gadsden MS
5502	Work In Progress request 3 new "G" keys for principal and custodians	9/14/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
3651	Work In Progress Mice in Gloria Hernandez office in C Wing. Need control as soon as possible 1) HAD JUAN CHECK FOR ANY FOOD AROUND, 2) REQUESTED THAT THEY ASK R. RONQUILLO FOR MICE TRAPS (W/GLUE) 3) FAXED FOR PRICE QUOTE AS PER M. MUNOZ FOR THE WHOLE C-WING.	7/19/2005 Medium	Dana Hamel Margret Villalobos	Office	Gadsden MS
3653	Work In Progress paint the columns on outside of gym	7/19/2005 Medium	Dana Hamel Rudy Arreola	Gym	Gadsden MS
3654	Work In Progress paint over the scratchouts in boys black restrooms	7/19/2005 Medium	Dana Hamel Rudy Arreola	Restroom (Boys)	Gadsden MS
3655	Work In Progress paint the front columns of the school to remove tagging	7/19/2005 Medium	Dana Hamel Rudy Arreola		Gadsden MS
9148	Work In Progress Please repair the bleachers, the rollers are out of sync, and we have a tournament coming up	1/30/2006 Medium	Dana Hamel Michael Munoz	Gym	Gadsden MS
9149	Work In Progress Extend concrete eastward from doorway towards the gym, not enough room for a motorized wheelchair	1/30/2006 Medium	Dana Hamel Michael Munoz	Hallway/Corridor	Gadsden MS
9518	Work In Progress check out the recepticle on front wall room 121, teacher currently using a side outlet for 5 computers	2/9/2006 Medium	Dana Hamel Enrique Sotelo		Gadsden MS
9517	Work In Progress repair or replace the water fountains damaged after school in the boys locker room and lobby	2/9/2006 Medium	Dana Hamel Lorenzo Solis		Gadsden MS
9876	Work In Progress Dugouts - Need to be painted there is graffitti all over them.	2/21/2006 Medium	Guadalupe Ontiveros Rudy Arreola	Athletic Field	Gadsden MS
4867	Work In Progress THE PAD HOLDER IS WORN OUT AND WONT HOLD THE PAD AT ALL.	8/24/2005 Medium	Jimmy Carbajal Jimmy Carbajal	Hallway/Corridor	Gadsden MS
3582	Work In Progress IRRIGATION CTRL PANEL - IRRIGATION BOOSTER PUMP IS NOT WORKING. PLEASE TROUBLESHOOT BUS TURNAROUND AREA. ROUTED TO ENRIQUE AS PER RICK 8/2/05	7/15/2005 8/2/2005 Medium	Lorenzo Hernandez Enrique Sotelo		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9341	Work In Progress Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Rudy Arreola		Gadsden MS
4095	Work In Progress please fill hole that is in front of entrance to band room. Will need a backing before gravel is applied. see mike	8/2/2005 High	Rudy Arreola		Gadsden MS
8735	Work In Progress please install new sprinklers by picnic tables & where needed and level grounds around area. Thanks	1/13/2006 Medium	Guadalupe Ontiveros	Cafeteria	Gadsden MS
6424	Work In Progress WE NEED LIGHTS IN THE BOYS & GIRLS RR IN MAIN BLDG, ALSO WE NEED THE LIGHTS IN HALLWAYS AS PER PM 6095.	10/14/2005 Medium	Enrique Sotelo		Gadsden MS
5961	Work In Progress please reomve and replaced stained ceiling tiles in Mr.Lowenburgs office.	9/29/2005 Medium	Rudy Arreola		Gadsden MS
9295	Work In Progress please replaced stained ceiling tiles in Mr.Lowenburgs office and thru-out c-wing area thats needed. Thanks	2/3/2006 Medium	Rudy Arreola		Gadsden MS
8732	Work In Progress please build frames to pour concrete for clean- outs that where Identied on 1-12-06 for future use.	1/13/2006 Medium	Rudy Arreola	Cafeteria	Gadsden MS
7760	Work In Progress Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola		Gadsden MS
7716	Work In Progress Kitchen - Need to shutdown gas and water service on Friday, 12/16/05 @ 1:00 pm. Route to Pancho, Spoke to him today 12/15/05 and he can do this. - M. Munoz	12/1/2005 12/2/2005 Medium	Alfredo Holguin Frank Lara	Cafeteria	La Mesa ES
5116	Work In Progress cockroach problem  Laura Benavidez - SNP Manager 233-2646	8/31/2005 Medium	Alma Terrell Margret Villalobos	Cafeteria	La Mesa ES
4378	Work In Progress locksmith need three keys for supply rm. key no F 49 8/23- Debra needs status on this work order submitted on 8/9/05 - mkv	8/9/2005 Medium	Frank Lara Manny Lozoya		La Mesa ES
9899	Work In Progress MAIN BLDG - NEED TO REPLACE 2 BROKEN WINDOWS 26 1/2 W X 54 3/4 L	2/21/2006 Medium	Frank Lara Ruben Ronquillo		La Mesa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9715	Work In Progress MAIN BLDG - NEED TO REPLACE BROKEN WINDOWS 26 1/2 W X 54 5/8 L (WIRE GLASS)	2/15/2006 Medium	Frank Lara Ruben Ronquillo		La Mesa ES
9613	Work In Progress Need to remove A/C's on barracks that will be demolished as per Mike. A/C's will be reinstall at CHE for W/O #9201.	2/13/2006 Medium	Lorenzo Solis Lorenzo Solis	Portables	La Mesa ES
7234	Work In Progress LJTP - Requesting 2 fire extinguishers.	11/9/2005 Medium	Margret Villalobos Ruben Ronquillo		La Union ES
5447	Work In Progress Student Cross Walk - Path on the west side there is a tree that is in the way. Students have to scoot over onto the street.	9/12/2005 Medium	Margret Villalobos Alfredo Holguin		La Union ES
8846	Work In Progress LUJTP - ASSEMBLE GREEHOUSE. (COORDINATE WITH DANNY M. AND GERRY MARQUEZ)	1/18/2006 Medium	Selma Nevarez Salvador Gonzalez		La Union ES LUJTP
5312	Work In Progress After last nights rainfall, leaks were discovered in rooms #208, #209, and the library.	9/7/2005 Medium	Santos Galindo Lorenzo Solis		La Union ES
5117	Work In Progress Lights in computer room keeps going out; breaker needs to be checked.	8/31/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
5371	Work In Progress In the women's restroom, in the southwing, the toilet is constantly flushy.	9/9/2005 Medium	Santos Galindo Salvador Gonzalez		La Union ES
4853	Work In Progress SINK AT CUSTODIAL CLOSET AT OLD BLDG. IS CLOGGED UP.	8/24/2005 Medium	Santos Galindo David Villalobos		La Union ES
4825	Work In Progress Need keys for room #100, #106, and room #108; plus keys for a file cabinet in the nurse's office.	8/23/2005 Medium	Santos Galindo Manny Lozoya		La Union ES
4775	Work In Progress Parking lanes need to be repaint in yellow and bus lane also needs to be repaint but in red. Route to Sal Gonzalez as per Mike 9/13/05 -mkv	8/22/2005 Medium	Santos Galindo Salvador Gonzalez		La Union ES
4356	Work In Progress in room 202 there is no outlet for refrigeration unit a.s.p.	8/9/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4408	Work In Progress a light next to my office need to be looked at cause it buzzes all day long.	8/10/2005 Medium	Santos Galindo Carlos Castillo		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4410	Work In Progress They need to check lighting from building cause several lights are off. And some stay on 24 hrs out side.	8/10/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4223	Work In Progress need an electrical outlet by computer hookups room 203.	8/5/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4372	Work In Progress need a fan motor in electrical storage room.	8/9/2005 Medium	Santos Galindo Jose Ambriz		La Union ES
6718	Work In Progress need electrical outlet on north wall	10/25/2005 10/26/2005 Medium	Santos Galindo Carlos Castillo	Office	La Union ES
6719	Work In Progress need floor tile in lounge	10/25/2005 Medium	Santos Galindo Michael Munoz	Office	La Union ES
6403	Work In Progress NEED CORK STRIP INFRONT OF THE OFFICE IN HALLAWAY.	10/14/2005 Medium	Santos Galindo Ruben Ronquillo		La Union ES
7446	Work In Progress would like hallway in old wing painted and frames. and new base trimming.	11/18/2005 Medium	Santos Galindo Salvador Gonzalez		La Union ES
7391	Work In Progress 11/15/05 To Caly. Relocate electrical outlet.	11/15/2005 Medium	Salvador Gonzalez Carlos Castillo		La Union ES
6418	Work In Progress Work Truck - need to repair broken tial-light.	10/14/2005 Medium	Salvador Gonzalez Angel Gonzales		La Union ES
8982	Work In Progress David I need some PVC to make a drain fanel for boiler room please. Thank you.	1/24/2006 Medium	Salvador Gonzalez David Villalobos		La Union ES
8547	Work In Progress Take out grass at swings area with the back hoe and fill with sand ( has half of needed sand)	1/9/2006 Medium	Salvador Gonzalez Guadalupe Ontiveros		La Union ES
9768	Work In Progress To Mike Munoz Subject: I would like to install PVC watering system on side of the school and between buildings.	2/16/2006 Medium	Salvador Gonzalez Salvador Gonzalez		La Union ES
9769	Work In Progress Teacher in classroom 110 requires more power outlets because his room only has two.	2/16/2006 Medium	Salvador Gonzalez Carlos Castillo		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
10076	Work In Progress 2/28/06 To Jose Ambriz: I would like to replace some (4) old water cooler for master cool system.	2/28/2006 Medium	Salvador Gonzalez Jose Ambriz		La Union ES
9087	Work In Progress 1/27/06 To David Villalobos. There is a boiler back flow water valve leaking , on my opinion has to replaced.	1/27/2006 Medium	Salvador Gonzalez David Villalobos		La Union ES
5503	Work In Progress Old emergency light fixtures (the complete system) are not working can you check them please. thank you	9/14/2005 Medium	Salvador Gonzalez Carlos Castillo		La Union ES
5786	Work In Progress Upper hinge on door at JTP needs to be repair. Might need to be weld	9/23/2005 Medium	Salvador Gonzalez Manny Lozoya		La Union ES
5949	Work In Progress Music Room needs a new circuit installation.	9/29/2005 Medium	Salvador Gonzalez Carlos Castillo		La Union ES
4864	Work In Progress JTP- Rosaro Ruedas needs a L201 key.	8/24/2005 Medium	Selma Nevarez Manny Lozoya		La Union ES JTP
9571	Work In Progress LUJTP 1. REMOVE & DUMP ALL INDUSTRIAL METAL SHELVING 2. MOVE GROCERY SHELVING TO DESIGNATED AREA. (Please call when scheduled 355-2048 Diana De Vore)	2/10/2006 Medium	Selma Nevarez Salvador Gonzalez		La Union ES JTP
9025	Work In Progress Need to protect 3 phase systems from single phasing.	1/25/2006 Medium	Carlos Castillo Carlos Castillo	Electrical Room	La Union ES
8256	Work In Progress Alvarez Farms ,panel needs main lug kit replaced	12/22/2005 Medium	Carlos Castillo Carlos Castillo	Classroom	La Union ES
3572	Work In Progress NEED LIGHT BULBS FOR RECESSED LIGHTS AT LA UNION ELEM. THE MAJORITY ARE BURNED OUT. THANK YOU.	7/15/2005 Medium	Arturo Nunez Carlos Castillo		La Union ES
3322	Work In Progress Yearly - La Union ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES
3344	Work In Progress Yearly - La Union ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4917	Work In Progress please repair asphalt where other water line was repired.	8/25/2005 Medium	Michael Munoz		La Union ES
9548	Work In Progress please provide concrete for trash dumpsters.	2/10/2006 Medium	Michael Munoz	Cafeteria	Loma Linda ES
5568	Work In Progress As per Mike Munoz issue a 6 & 7 Grand Master keys to Mike Mc Dermott.	9/16/2005 Medium	Manny Lozoya		Loma Linda ES
7805	Work In Progress Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
7796	Work In Progress Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
7763	Work In Progress Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
3345	Work In Progress Yearly - Loma Linda ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
3323	Work In Progress Yearly - Loma Linda ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
8647	Work In Progress NEED TO COMPLETE BUILDING INSPECTION FOR ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOU OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED & SIGNED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JANUARY 27, 2006	1/11/2006 Medium	Aida Salcedo Luis Solis		Loma Linda ES
9386	Work In Progress Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
8607	Work In Progress NEEDING KEY FOR ROOM 119,	1/10/2006 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
8433	Work In Progress Mike Munoz - Repair East Fence facing Katie Rd. seems to have been hit by a car. Case# 200600164	1/5/2006 Medium	Grace Alvarado Michael Munoz		Loma Linda ES
8143	Work In Progress MIKE INSTALL OUTLET IN BOOKROOM	12/15/2005 Medium	Grace Alvarado Michael Mc Dermott		Loma Linda ES

3/1/2006 3:54:04 PM

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6686	Work In Progress INSTALL ELECTRICAL CIRCUIT IN ROOM 208 FOR MICROWAVE AND FRIDGE.	10/24/2005 Medium	Grace Alvarado Enrique Sotelo		Loma Linda ES
8090	Work In Progress ATTN: MIKE MUNOZ POUR SLAB FOR GARBAGE BINS AS TALKED ABOUT.	12/13/2005 Medium	Grace Alvarado Michael Munoz		Loma Linda ES
7361	Work In Progress REPLACE TIMER FOR BOILER	11/15/2005 Medium	Grace Alvarado Jose Ambriz		Loma Linda ES
10029	Work In Progress Manny Lozoya, Repair Push Bar, West Enterance	2/27/2006 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
9720	Work In Progress MIKE REPLACE LIGHT SWITCH ROOM 117. OLD ONE IS SHORTING OUT	2/15/2006 Medium	Grace Alvarado Michael Mc Dermott		Loma Linda ES
9831	Work In Progress ATTN: PLUMBERS NEED KIT INSTALLED TO BOLT TOILET TO FLOOR & NEW BOWLI WAY. BOYS R.R. NORTHWEST WING. NEED SENSOR SINKS REPAIRED. 2ND REQUEST LEAKING VERY BADLY. BOYS RR SOUTH WEST WING. NEED NEW HOSE BIB INSTALLED IN COURTYARD BEHIND LIBRARY. OLD ONE WILL NOT CLOSE.	2/17/2006 Medium	Grace Alvarado Joe Ontiveros		Loma Linda ES
9897	Work In Progress MIKE MCDERMOTT: REQUEST REPAIR OR REPLACEMENT OF VENETIAN BLINDS, PARTICULARLY WINDOW ON NORTH ISE OF EAST WALL ROOM 103 LET ME KNOW. AS PER MR. T.	2/21/2006 Medium	Grace Alvarado Ruben Ronquillo		Loma Linda ES
9219	Work In Progress MANNY. REPAIR NE GATE. LOCK IS BROKEN	2/1/2006 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
4593	Work In Progress MIKE MUNOZ, REPLACE EAST FENCE	8/16/2005 Medium	Grace Alvarado Michael Munoz		Loma Linda ES
3829	Work In Progress MR. TRUJILLO IS WANTING NEW KEYS MADE FOR DESKS, CABINETTS AND FILE CABINETS. ALSO NEEDING NAME PLATE FOR NEW TEACHERS. MS. BERARD, CHAVEZ-FISHER, GRIEGO, DESANTIAGO, HUGHES, MARKHAM, MEDINA, MERRICK, MONTES, PINA, PRICE, RIOS- ALVILLAR,	7/26/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
6538	Work In Progress Need Ditch Witch delivered to Loma Linda tomorrow.	10/18/2005 Medium	David Villalobos Angel Gonzales		Loma Linda ES
9454	Work In Progress Need a gate key for El Paso Disposal.	2/7/2006 Medium	Juliet Parra Manny Lozoya		Loma Linda ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6217	Work In Progress NEED TO (PER ATTACHED DRAWING): 1. CUT CURB 2. DIG DIRT 4" 3. ADD CRUSH FINE / CEMENT 4. MOVE DUMPSTER INSIDE THE CURB	10/10/2005 Medium	Michael Munoz Guadalupe Ontiveros		Loma Linda ES
9176	Work In Progress NEED TO ASSIT W/ BROKEN 1-1/4 INCH FEMALE ADDAPTER AS DISCUSSED.THANX.ALSO NEED 4 MORE 3500 HUNTER SPRINKLERS.	1/31/2006 Medium	Romauldo Apodaca Guadalupe Ontiveros		Mesquite ES
10061	Work In Progress broken master key need one right away,thanx.	2/28/2006 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
10073	Work In Progress replace broken plug on a/c.art rm.	2/28/2006 Medium	Romauldo Apodaca Enrique Sotelo		Mesquite ES
9937	Work In Progress DANNY MIRANDA, NEED DOOR HARDEWARE FOR CAFETERIA DOORS, AND MAIN DOORS. THANX.	2/23/2006 Medium	Romauldo Apodaca Danny Miranda		Mesquite ES
9935	Work In Progress MANNY, NEED TO HELP W/ OPENING STORAGE RM. TRIED TO OPEN BUT CAN,T. THANX.	2/23/2006 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
8677	Work In Progress Portable 602 - Need vinyl flooring replaced w/ carpet, floor in bad shape,safety issue, someone may trip.	1/12/2006 Medium	Romauldo Apodaca Michael Munoz	Portables	Mesquite ES
6508	Work In Progress jaime need to assist w/ boilers to change over to heating,also need gas valve for heater in old office.thanx.	10/18/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES
6507	Work In Progress kiki, 5 rms w/ out lights need assistance.thanks. ARREGLAR PROBLEMA EN ALAMBRADO DE LUCES EN SALONES DE OLD WING.	10/18/2005 10/18/2005 Medium	Romauldo Apodaca Romauldo Apodaca		Mesquite ES
6509	Work In Progress lupe ontiveros.need play sand for play structures and alma del valle.thanx.	10/18/2005 Medium	Romauldo Apodaca Guadalupe Ontiveros		Mesquite ES
7825	Work In Progress NEED TO RUN ELECTRICAL LINES TO MAIN FIELD FOR RED RIBBON CUTTING CEROMONY ON 12/8/05 AT 6:AM FOR HEATERS AND LIGHTING,PER MS. PHILLIPS.	12/5/2005 Medium	Romauldo Apodaca Enrique Sotelo		Mesquite ES
3558	Work In Progress need compresor changed out on armstrong unit in rm. 608.thanx.	7/14/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
3955	Work In Progress DINING AREA - NEED TO WELD HINGES ON DOOR FALLING DOWN.	7/29/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
4340	Work In Progress manny need to assist w/ 2 doors in porables having hard time tpo close safety issue. also need lever handle.	8/9/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
4699	Work In Progress manny need your assistance w/ doors that are hard to open and close. thanx.	8/19/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
9135	Work In Progress Barracks - Remove rocks from roof and repair and secure water lines (safety issue).	1/30/2006 Medium	Michael Munoz Romauldo Apodaca		Mesquite ES
9137	Work In Progress East of Library - Lots of weeds growing apply chemical, treat weeds ask for imput from Lupe so you wont kill trees.	1/30/2006 Medium	Michael Munoz Romauldo Apodaca		Mesquite ES
9138	Work In Progress Pecan Trees in back parking lot - Trim branches, cut weeds around and make new wells and water.	1/30/2006 Medium	Michael Munoz Romauldo Apodaca		Mesquite ES
9139	Work In Progress North Fence Line by Pine Trees - Cut weeds and pickup trash and treat fence line.	1/30/2006 Medium	Michael Munoz Romauldo Apodaca		Mesquite ES
9379	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
9345	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3971	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
4015	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
4005	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3324	Work In Progress Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
3346	Work In Progress Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
9389	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
9132	Work In Progress please remove grass and tiller ,then level on the enviromental park as per our discussion and reveiw of the plans.	1/30/2006 Medium	Guadalupe Ontiveros	Athletic Field	Mesquite ES
5526	Work In Progress NEED A "CB4" KEY FOR GUILLERMO - TO HAVE ACCESS TO ENERGY OFFICE TO CLEAN.	9/15/2005 Medium	Manny Lozoya		Physical Plant Complex
7711	Work In Progress please order all material needed to paint barracks in the back and let me know what staff will be need to accomplish the project.	12/1/2005 Medium	Danny Miranda	Portables	Physical Plant Complex
3379	Work In Progress Mens Restroom in Custodial Warehouse -Install new privacy lockset	7/7/2005 Low		Restroom (Boys)	Physical Plant Complex
3380	Work In Progress Mens Restroom in Custodial Warehouse- Replace toilet tank cover with appropriate size for unit.	7/7/2005 Medium	Fred Appelzoller	Restroom (Boys)	Physical Plant Complex
9391	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
7772	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
7810	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
7642	Work In Progress Auto Shop - Need to install 4 cylinders all the same but different from main entrance. Need 4 keys issued (see Angel).	11/30/2005 Medium	Angel Gonzales Manny Lozoya		Physical Plant Complex
8737	Work In Progress NEED SPARE KEY FOR AIDA (TRUCK) - P1106 BB6	1/13/2006 Medium	Aida Salcedo Manny Lozoya		Physical Plant Complex
9749	Work In Progress WILL NEED ELECTRICAL WORK DONE IN CUSTODIAL WAREHOUSE TO BE ABLE TO INSTALL NEW WASHER & DRYER - MUST BE DONE BY FEBUARY 24, 2005.	2/16/2006 Medium	Aida Salcedo Enrique Sotelo		Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9750	Work In Progress WILL NEED PLUMBING WORK DONE IN CUSTODIAL WAREHOUSE TO BE ABLE TO INSTALL NEW WASHER & DRYER - MUST BE DONE BY FEBUARY 24, 2005.	2/16/2006 Medium	Aida Salcedo Joe Ontiveros		Physical Plant Complex
3186	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
3461	Work In Progress Need a copy of control key (core) to keep here at the Maintenance Dept - as per A. Holguin.	7/12/2005 Medium	Alfredo Holguin Manny Lozoya		Physical Plant Complex
4017	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
9354	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
8634	Work In Progress As per Mike Vehicle # 23 (Manny Lozoya Van) needs new tires.	1/11/2006 Medium	Manny Lozoya Angel Gonzales		Physical Plant Complex
9950	Work In Progress 2/21/06 (2)7910 (4)unload materials for chaparral elen. @ san miguel elem. (1.5)exchange corner bead @ foxworth (.5)back to vado elem.  2/21-6	2/23/2006 Medium	Danny Miranda Danny Miranda		Physical Plant Complex
9114	Work In Progress need mail boxes 2 vado elem	1/27/2006 Medium	Danny Miranda Danny Miranda		Physical Plant Complex
5432	Work In Progress Auto Shop - need to install new door knob to new door at Angel's Office.	9/12/2005 Medium	Danny Miranda Manny Lozoya		Physical Plant Complex
4585	Work In Progress Need to replace water heater,its giving out an extremeley bad odor.Health issue.	8/16/2005 Medium	Carlos Castillo Joe Ontiveros	Electrical Room	Physical Plant Complex
9057	Work In Progress PPD Barracks - Need to run power to existing panel box. (Coordinate w/eachother Cali, Enrique and Mike Mc Dermott).	1/26/2006 Medium	Michael Munoz Enrique Sotelo		Physical Plant Complex
5121	Work In Progress Power Outage - El Paso Electric	8/29/2005 Medium	Margret Villalobos Enrique Sotelo		Physical Plant Complex
3940	Work In Progress MARTA JACQUEZ - A/C UNIT IS NOT WORKING AT ALL.	7/29/2005 Medium	Marta Jacquez Jaime Gomez		Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5735	Work In Progress AS PER ALFREDO I NEED A COPY OF KEY TO CUSTODIAL OFFICE. THANK YOU.	9/22/2005 Medium	Maritza Gonzalez Manny Lozoya		Physical Plant Complex
7994	Work In Progress Need to issue a key for Mary and Julie/Alfredo's office to Maritza.	12/9/2005 High	Maritza Gonzalez Manny Lozoya		Physical Plant Complex
8822	Work In Progress Front Entrance Blue Double Doors - Cylinders need to be cleaned.	1/18/2006 Medium	Peggy Jo Hernandez Manny Lozoya		Physical Plant Complex
7834	Work In Progress Need to make a key for D. Miranda's Office for Ruben.	12/5/2005 Medium	Ruben Ronquillo Manny Lozoya		Physical Plant Complex
8774	Work In Progress I would like to request the "Student Records Office" sign be moved from the north outside wall of the loading bay to the wall beside the Records Room door and also the door leading into the warehouse by the rec. room re-painted with "Student Records Office" Inside.	1/17/2006 Medium	Tracey Swinford Rudy Arreola		Physical Plant Complex
5057	Work In Progress We need a new Door Knob placed in the Data Clerk office. (office area) At this time the door doesn't lock.	8/30/2005 Medium	Olga Arias Manny Lozoya		Riverside ES
5058	Work In Progress Carpet (Doorway) to Data clerk office is coming loose. Plastic edge is picking-up.. Thanks	8/30/2005 Medium	Olga Arias Michael Munoz		Riverside ES
3348	Work In Progress Yearly - Riverside ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3326	Work In Progress Yearly - Riverside ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3690	Work In Progress MR MANNY LOZOYA FILE CABINET NEW PORTABLE RM B NEEDS REPAIR WILL NOT LOCK PARTS MISSING THANK YOU SIR	7/19/2005 Medium	Adan Duran Manny Lozoya		Riverside ES
3414	Work In Progress MR LOZOYA MRS ARIAS IS HAVING TROUBLE WITH THE STORAGE ROOM LOCK WOULD LIKE FOR YOU TO LOOK AT IT THANK YOU SIR	7/8/2005 Medium	Adan Duran Manny Lozoya		Riverside ES
3778	Work In Progress MR DAVID VILLALOBOS WE HAVE SOME LEAKING FUACTS NEW WING NEED REPAIR KIT OR REPLACEMENT THANK YOU SIR	7/22/2005 Medium	Adan Duran David Villalobos		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4473	Work In Progress MR MANNY LOZOYA SIR THE DOOR ON NEW PORTABLE IS STUCK IN LOCK CAN NOT GET IT TO UNLOCK PORTABLE B IN BACK THANK YOU SIR	8/11/2005 Medium	Adan Duran Manny Lozoya	Portables	Riverside ES
4388	Work In Progress MR JOSE AMBRIZ SIR WE NEED TO HOOK BACK UP THE AIR IN WHAT USE TO BE MRS FLORES OFFICE IT WAS REMOVE AT HER REQUEST AND ITS KIND OF WARM IN THERE THANK YOU SIR	8/9/2005 Medium	Adan Duran Jose Ambriz		Riverside ES
4596	Work In Progress MR MANNY LOYZOA SIR NEED TO CHANGE OUT DOOR HANDLE BY MRS ARIAS OFFICE THE ONE THERE DO NOT LOCK NEED ONE THAT CAN BE LOCKED THANK YOU SIR	8/16/2005 Medium	Adan Duran Manny Lozoya		Riverside ES
5115	Work In Progress MR LUPE ONTIVEROS SIR WILL NEED THE USE OF THE BACKHOE TO MOVE SOCCOR GOAL POST AWAY FROM PARKING AREA UNSAFE FOR KIDS THANK YOU SIR	8/31/2005 Medium	Adan Duran Guadalupe Ontiveros		Riverside ES
7156	Work In Progress 11/7/05 1/2 SIGN IN CHECK SCHOOL GROUNDS 2 1/2 MOWED GRASS 1 1/2 EDGE WITH TRIMER 1 CLEAN SIDEWALKS WITH BLOWER 1 REPAIR ENTRANCE DOOR WILL NOT CLOSE 1/2 CLOSE WEST AND DROP OFF GATES 1 FILE PAPER WORK AND SIGN OUT 11/7 - 8	11/7/2005 Medium	Adan Duran Adan Duran		Riverside ES
8225	Work In Progress 12/20/05 1/2 SIGN IN CHECK SCHOOL GROUNDS 6 PAINT BATHROOMS 1/2 WASH ROLLERS AND PAINT BRUSH AND PAN 1 FILE PAPER WORK AND SIGN OUT 12/20 - 8	12/20/2005 Medium	Adan Duran Adan Duran		Riverside ES
8611	Work In Progress MR JOSE AMBRIZ SIR WILL NEED A SWITCH FOR REZNOR HEATER ROOM 105 NEED TO KEEP RESTARTING NOT WORKING RIGHT THANK YOU SIR	1/10/2006 Medium	Adan Duran Jose Ambriz		Riverside ES
8661	Work In Progress MR CARLOS CASTILLO SIR WILL NEED SOME LAMPS SOME U LAMPS HALL WAY LAMPS SOME PL 13 SOME METAL HALIDE THANK YOU VERY MUCH SIR	1/11/2006 Medium	Adan Duran Carlos Castillo		Riverside ES
8807	Work In Progress MR JOSE AMBRIZ SIR RM 105 SWITCH IS NOT WORKING HAD TO BY PASS IN ORDER TO GET HEAT INTO ROOM VERY COLD REZNOR HEATER NEW WING WILL NEED TO CHANGE OUT THANK YOU SIR	1/17/2006 Medium	Adan Duran Jose Ambriz		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
8753	Work In Progress MR CARLOS CASTILLO SIR WE HAVE SOME LIGNTS THAT ARE OUT IN THE GYM AND DINNING AREA WILL NEED LIFT TO REACH THEM ARE PRETTY HIGH YOU NEED TO COME BY WHEN YOU HAVE A CHANCE TO SEE WHAT KIND THEY ARE THANK YOU SIR	1/13/2006 Medium	Adan Duran Carlos Castillo		Riverside ES
9839	Work In Progress MR CARLOS CASTILLO SIR THE HAND DRYER PUSH BUTTON IS BROKEN WILL NEED LOCK KEY TO HOLD IN PLACE ITS HANGING OUT THANK YOU SIR AND GOD BLESS	2/17/2006 Medium	Adan Duran Carlos Castillo		Riverside ES
9855	Work In Progress NEED 6 BATTERIES FOR EMER. LIGHTS AS PER PM 9381.	2/17/2006 Medium	Adan Duran Carlos Castillo		Riverside ES
9856	Work In Progress NEED TAGS TO TAG FIRE EXTINGUISHERS AS PER PM 9346.	2/17/2006 Medium	Adan Duran Ruben Ronquillo		Riverside ES
9734	Work In Progress MR CARLOS CASTILLO SIR WE HAVE SEVERAL EMERGENCY LIGHT THAT NEED BATTRIES WILL NEED 6 AT THIS TIME THANK YOU SIR	2/15/2006 Medium	Adan Duran Carlos Castillo		Riverside ES
9714	Work In Progress NORTH ENTRANCE DOUBLE DOORS - AUTOMATIC DOOR CLOSER IS LEAKING ALOT OF OIL AND DOOR IS CLOSING FAST.	2/15/2006 Medium	Adan Duran Manny Lozoya		Riverside ES
10068	Work In Progress MR ANGEL GONZALES SIR THE FUEL GLASS ON THE 455 JOHNDEERE IS LEAKING TRY TO TIE IT SOME BUT IT STILL LEAKS MAY NEED A NEW HOUSING ON TOP OF NUT THANK YOU SIR AND GOD BLESS	2/28/2006 Medium	Adan Duran Angel Gonzales		Riverside ES
5592	Work In Progress please see what can be done to repair or remove electrical outlet on floor on serving line. Outlet has a can over it and could be a trip hazard.	9/19/2005 Medium	Danny Orozco	Cafeteria	Riverside ES
7632	Work In Progress The backflow prevention device on the irrigation distribution system needs to have the annual inspection performed.	11/29/2005 Medium	Guadalupe Ontiveros		San Miguel ES
8666	Work In Progress please cut and trim evergreens and pines in front of campus	1/11/2006 Medium	Danny Vega		San Miguel ES
9394	Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Danny Vega		San Miguel ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
8305	Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Danny Vega		San Miguel ES
8401	Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Danny Vega		San Miguel ES
8323	Work In Progress Monthly - San Miguel ES Roof Inpsection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Danny Vega		San Miguel ES
8389	Work In Progress Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Danny Vega		San Miguel ES
3175	Work In Progress Monthly - San Miguel ES Roof Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
9347	Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Danny Vega		San Miguel ES
9382	Work In Progress Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Danny Vega		San Miguel ES
4489	Work In Progress Need an extra key for these rooms.	8/11/2005 Medium	Barbara Cardenas Manny Lozoya	Classroom	San Miguel ES 25, 49,50
9290	Work In Progress Room 26--Marcos Rivera Lost key to his room, B43 needs a replacement	2/2/2006 Medium	Barbara Cardenas Manny Lozoya	Classroom	San Miguel ES
6367	Work In Progress rm#32 day&night type furnance/pilot wont stay on-needs thermo-couple	10/13/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
5177	Work In Progress NEED FILTERS 12X24X1	9/2/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
5176	Work In Progress CAFETERIA GIRLS RR/SINK FAUCET BROKEN - OFF /PLEASE REPLACE/HOT-COLD TYPE	9/2/2005 Medium	Danny Vega Joe Ontiveros		San Miguel ES
5307	Work In Progress portable #28 refrig unit not cooling/please check it out asap	9/7/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
5270	Work In Progress NEED LDO 2QT/FLUSH VALVE KIT/DIAPRAHMS/TUB&SINK SEALER/ELONGATED TIOLET SEAT	9/6/2005 Medium	Danny Vega Joe Ontiveros		San Miguel ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3834	Work In Progress A/C UNIT NOT WORKING IN HIGH SPEED PORTABLE#58	7/26/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
4051	Work In Progress portable #30/rheem a/c unit not woking.stop by asap	8/1/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
4445	Work In Progress Portable 29 - Needs to be secured by the end of the day.	8/10/2005 Medium	Danny Vega Manny Lozoya	Portables	San Miguel ES
4447	Work In Progress principals office door hard to open/door needs to be shaved.stop by asap	8/10/2005 Medium	Danny Vega Manny Lozoya		San Miguel ES
10080	Work In Progress rm#19 door wont close/need to close testing matreial stored in this rm/key wont turn core.asap	2/28/2006 Medium	Danny Vega Manny Lozoya		San Miguel ES
10032	Work In Progress need flourescent lamps/40w2-boxes/32w 1-box	2/27/2006 Medium	Danny Vega Enrique Sotelo		San Miguel ES
9064	Work In Progress no hot water/womens restroom/main bldg.please stop by	1/26/2006 Medium	Danny Vega Joe Ontiveros		San Miguel ES
8847	Work In Progress need fertilizer spread on campus fields/front lawn 16-8-8	1/18/2006 Medium	Danny Vega Guadalupe Ontiveros	Athletic Field	San Miguel ES
8676	Work In Progress east exit door/main bldg/having trouble securing /panic bar stuck	1/12/2006 Medium	Danny Vega Manny Lozoya		San Miguel ES
8082	Work In Progress library toilet will not flush/we need to replace it	12/13/2005 Medium	Danny Vega Joe Ontiveros		San Miguel ES
8007	Work In Progress need one set gates wheels /west gate wheels damaged /asap(ruben ronquillo)	12/12/2005 Medium	Danny Vega Ruben Ronquillo		San Miguel ES
7563	Work In Progress boys restroom heater coil leaks water/need replaced asap found leak and repaired it	11/28/2005 12/1/2005 Medium	Danny Vega Lorenzo Solis		San Miguel ES
6785	Work In Progress boiler is not heating/please ck it out/class rooms are cold in the morning	10/26/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
6618	Work In Progress need two loads playground sand asap	10/21/2005 Medium	Danny Vega Guadalupe Ontiveros		San Miguel ES
6617	Work In Progress j.gomez/need to start and go thru check list on boiler unit/before 10-28-05 (.you can do it)	10/21/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6584	Work In Progress NEED LOCK-OUT DEVICE FOR DISCONNECT BOX/PORTABLE 28-29/POWER SHUT-OFF DAILY-ASAP	10/20/2005 Medium	Danny Vega Enrique Sotelo		San Miguel ES
9115	Work In Progress need to cover duct in cafeteria san miguel	1/27/2006 Medium	Danny Miranda Danny Miranda		San Miguel ES
5337	Work In Progress DISHWASHER LEAKING WATER.  EVA MIRANDA - 233-2860	9/8/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	San Miguel ES
9670	Work In Progress main building, please apply 10% bleach and scrub pillars on the north side of building as per work shop. Use your PPEs.	2/13/2006 High	Michael Munoz Danny Vega		San Miguel ES
7015	Work In Progress Need backflow tested on irrigation system thanks	11/4/2005 Medium	Ricardo Jacquez Ricardo Jacquez		San Miguel ES
8801	Work In Progress Lock is hard to open and lock on pump house. Please repare thank you.	1/17/2006 Medium	Ricardo Jacquez Manny Lozoya		San Miguel ES
7951	Work In Progress Wing A - Rooms 102, 105, 107, 108 and in Wing C - Conf. Room and Room 310 units are freezing up/low pressure.	12/8/2005 Medium	Jose Ambriz Jose Ambriz		Santa Teresa ES
7323	Work In Progress Need to check Lounge and Admin. Office Units. Have to reset units manually everyday. (Jose Ambriz informed Renee of problem). Please send someone out to check these. - Thanks	11/14/2005 Medium	Jose Ambriz Margret Villalobos		Santa Teresa ES
8761	Work In Progress Need to replace (2) Phase Monitors in Room 101 and Lounge/Library Office.  Waiting on invoice from Trane.	1/13/2006 Medium	Jose Ambriz Margret Villalobos		Santa Teresa ES
9005	Work In Progress Need a gate key for El Paso Disposal.	1/24/2006 Medium	Juliet Parra Manny Lozoya		Santa Teresa ES
4154	Work In Progress ATTN LUPE, LUPE, WE STILL NEED THE COBBLESTONE TO KEEP CHECK THE RAIN ERROSION. ALSO NEED FOR BETO AND MANNY TO REDIG TRENCH AT BACK FENCE TO KEEP RAIN FROM FLOODING GROUNDS AND CLASS RMS.	8/3/2005 Medium	Gerardo Marquez Guadalupe Ontiveros		Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3657	Work In Progress ATTN. Manny . NEED FOR YOU TO DUPLICATE A KEY TO THE MAIL BOX .  THANKS .	7/19/2005  Medium	Gerardo Marquez Manny Lozoya		Santa Teresa ES
4152	Work In Progress ATTN MANNY. MANNY, WE STILL NEED FOR YOU TO MAKE US ANOTHER KEY TO THE MAIL BOX. THANKS.	8/3/2005  Medium	Gerardo Marquez Manny Lozoya		Santa Teresa ES
9561	Work In Progress RITA HAS REQUESTED THAT WE HAVE THE EXTERMINATOR COME AND SPRAY THE BUILDING TO CONTROL AN INFESTATION OF BROWN SPIDERS. SHE IS REQUESTING THAT IT BE DONE AFTER CLASS HOURS. THANKS.	2/10/2006  Medium	Gerardo Marquez Margret Villalobos	Classroom	Santa Teresa ES
9562	Work In Progress MARGARET; RITA HAS REQUESTED THAT I PICK UP RISERS AR STMS. ON 2/14/06, AFTER 10:AM. AND RETURN THEM ON 2/17/06. THANKS JERRY.	2/10/2006  Medium	Gerardo Marquez Gerardo Marquez	Choral	Santa Teresa ES
9640	Work In Progress MIKE, MRS. VAN DYKE, THE SPECIAL ED. TEACHER IN RM. 107. IS REQUESTING THAT WE RIG A SUPPORT FOR THEIR PHYSICAL THERAPY SESSIONS SIMILAR TO THE ONES IN RM. 101.	2/13/2006  Medium	Gerardo Marquez Michael Munoz	Classroom	Santa Teresa ES
9995	Work In Progress DAVE, NEED FOR YOU TO GET ME A 1/2 INCH SHUT OFF VALVE FOR WALL HYDRANT THATS LEAKING.	2/24/2006  Medium	Gerardo Marquez David Villalobos		Santa Teresa ES
8731	Work In Progress DAVE; NEED FOR YOU TO COME AND CHECK OUT HOSE BIB AT S.END OF A-WING. I CAN'T GET IT TO STOP LEAKING. I TOOK APART THE FRONT COVER AND CLEANED OFF THE DIAPHRAM , BUT IT STILL LEAKS. THEHOSE BIBS HAVE NO SHUT OFF VALVES UNLESS WE SHUT OFF THE WATER TO THE RR. WATER.	1/13/2006  Medium	Gerardo Marquez David Villalobos		Santa Teresa ES
9383	Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.	2/5/2006  Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
9332	Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.	2/5/2006  Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
4021	Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005  Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
4009	Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005  Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
3958	Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
9395	Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
8306	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
8324	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
8403	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
8392	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
7804	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
7773	Work In Progress Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Danny Orozco		Santa Teresa HS
7815	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
7767	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
7119	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
7108	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
7071	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
9999	Work In Progress please repair the wood that is breaking off the dugouts. Thanks	2/24/2006 Medium	Guadalupe Ontiveros	Athletic Field	Santa Teresa HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
9990	Work In Progress bleachers do not go in or out. please repair.	2/24/2006 Medium	Michael Munoz	Gym	Santa Teresa HS ATHLETIC
4484	Work In Progress please install venting system and exhaust hood in the metal shop. See Joe Angelo.	8/11/2005 Medium	Jose Ambriz		Santa Teresa HS
6036	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
6018	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
5214	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
6118	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
6107	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
9348	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
9396	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
9385	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
3176	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3351	Work In Progress Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3158	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
9869	Work In Progress NEED ASSISTANT ON C.W. LINE AT A.H.U. AT LIBRARY, A SMALL SMALL LEAK HAS SPRUNG, NEED TO SEE IF WE CAN REPAIR.	2/21/2006 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
10017	Work In Progress Old Locker Room - Unclog drain.	2/24/2006 Medium	Arturo Nunez David Villalobos	Gym	Santa Teresa HS
9976	Work In Progress NEED ELECTRICAL RUN TO NEW EXHUAST FAN THAT WAS INSTALLED ON WELDING SHOP, FOR PLASMA CUTTER.	2/24/2006 Medium	Arturo Nunez Carlos Castillo		Santa Teresa HS
10055	Work In Progress NEED DOOR WINDOW ON GIRLS DRESSING ROOM REPLACED . IT WAS BROKEN. FOUND BROKEN THIS MORING. THE SIZE IS 5"X25 7/8 " WIRE SAFETY MESH. THANK YOU.	2/28/2006 Medium	Arturo Nunez Ruben Ronquillo		Santa Teresa HS
9785	Work In Progress NEED 12 EA. 2X4 277V. LAY IN LIGHTS WITH EMERGENCY BALAST. FOR 300 WING ROOMS, AND HALLWAYS.	2/16/2006 Medium	Arturo Nunez Carlos Castillo		Santa Teresa HS
9787	Work In Progress NEED 14 EA. OUSIDE SECURITY LIGHT FIXTURES TO REPLACE EXISTING ORIGINAL FIXTURES ON MAIN BUILDING, AND ANNEX. WILL ASISSIT ELECTRICAN ON REPLACING FIXTURES.	2/16/2006 Medium	Arturo Nunez Carlos Castillo		Santa Teresa HS
9623	Work In Progress DOOR KNOB IN COUSELORS OFFICE, SOUTH SIDE DOOR.CLINDER IS BROKEN THEY CAN'T OPEN DOOR WITH THEIR KEY. WOULD LIKE TO HAVE LOCKSMITH HELP US WITH THIS SITUATION. REPAIR CYLINDER AT COUNSELORS OFFICE	2/13/2006 1/16/2006 Medium	Arturo Nunez Manny Lozoya		Santa Teresa HS
9671	Work In Progress NEED THE FOLLOWING V BELTS. 4L 280 2 EA. , 4L 200, 4 EA. 4L 220. 4 EA.	2/13/2006 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS
9738	Work In Progress NEED A MARTHON MTR. MODEL #6QB48517D2055KP ,115V. FR.482 ROT. C.W. FOR BOYS DRESSING ROOM.	2/15/2006 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS
9737	Work In Progress NEED FIRE EXT. THAT WERE TOOK IN TO BE REFILLED , SERVICED, AND TESTED. BACK TO SCHOOL SITE. GOOD MORNING MARGRET, AS PER MIKE, WORK ORDER 9737 NEEDS TO GO TO RUBEN. THANKS, DANNY	2/15/2006 Medium	Arturo Nunez Ruben Ronquillo		Santa Teresa HS
9484	Work In Progress EXTERIOR POLE LIGHTS AT VOC. BLDG. NEED TO BE REPLACED, WE HAVE THREE THAT ARE OUT, WOULD LIKE TO HAVE ALL SIX REPLACED, AND TURNED AROUND TO WHERE THEY WERE ORIGINAL, SET TO LIGHT. CUSTODIANS CLAIM THAT IT IS TO DARK BY TRASH COMPACTOR. THANK YOU.	2/8/2006 Medium	Arturo Nunez Carlos Castillo		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
8571	Work In Progress NEED TO BORROW SCISSOR LIFT TO PUT UP BANNERS ON GYM RAFTERS. AND PUT UP SOME ACUSTIC PANELS THAT FELL . AND CHECK THEM ALL, FOR SAFETY PURPOSES.	1/9/2006 Medium	Arturo Nunez Ruben Ronquillo		Santa Teresa HS
8410	Work In Progress NEED DOOR WINDOW REPLACED ON ROOM #304 6 3/4X24 1/2 1/4" WIRE SAFETY GLASS. WILL NEED PRICE TO PUT ON VANDALISM REPORT. THANK YOU.....	1/4/2006 Medium	Arturo Nunez Ruben Ronquillo		Santa Teresa HS
8779	Work In Progress NEED TO HAVE BATTING CAGE FOR SOFTBALL FIELD FRAME PIPE REWELDED, WELD BROKE. WILL LIKE TO HAVE IT REWELD AS SOON AS POSSIBLE, BEFORE IT BECOMES A MAJOR PROBLEM. SAFETY ISSUE. THANK YOU.	1/17/2006 Medium	Arturo Nunez Guadalupe Ontiveros		Santa Teresa HS
8757	Work In Progress NEED TO HAVE OLD BAND ROOM FUMIGATED, AND MOUSE TRAP INSTALLED, MICE HAVE BEEN SIGHTED, DUE TO FOOD NOT PROPERLY STORED. A.S.AP. THANK YOU....	1/13/2006 Medium	Arturo Nunez Margret Villalobos		Santa Teresa HS
7342	Work In Progress NEED A FIFTY (50) GALLON WATER HEATER, TO REPLACE THE ONE AT CUSTODIAL CLOSET, IT IS LEAKING REAL BAD, AND WE HAD TO SHUT DOWN, RED TAG. CUSTODIANS NEED THE HOT WATER.	11/14/2005 Medium	Arturo Nunez David Villalobos		Santa Teresa HS
6927	Work In Progress NEED A SET OF BROUNING GRIP NOTCH V BELTS. #5VX840, 358, FOR NEW AIR HANDLER UNIT AT LIBRARY.	11/1/2005 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS
8013	Work In Progress NEED ASSISTANCE ON REPLACING BROKEN LIGHT BULB BY FOOTBALL CONSESSION STAND, WILL NEED BUCKET TRUCK TO REPLACE LIGHT BULB. THANK YOU.	12/12/2005 Medium	Arturo Nunez Carlos Castillo		Santa Teresa HS
7840	Work In Progress NEED FIVE (5) LOCKS 6" SLIDE LOCKING HASP	12/5/2005 Medium	Arturo Nunez Manny Lozoya		Santa Teresa HS
3571	Work In Progress NEED CONDENSER MTR. FOR SNACK ROOM A.C. UNIT, MTR. IS FROZEN UNIT IS DOWN.	7/15/2005 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS
3329	Work In Progress Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
4346	Work In Progress NEED TO FUMIGATE VOC. SHOPS TO MANNY CRIKETS, ANTS, ETC,ETC.	8/9/2005 Medium	Arturo Nunez Margret Villalobos		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7194	Work In Progress ADULT RESTROOM IN OFFICE AREA NEEDS TO BE PAINTED.	11/8/2005 Medium	Aida Salcedo Arturo Nunez		Santa Teresa HS
8157	Work In Progress MR. GALLEGOS WANTS DEADBOLT ON BOYS AND GIRLS DRESSING ROOMS 2- NEED TO CHANGE DOOR KNOBS TO BE ABLE TO LOCK THE WORK ROOM BETWEEN THE BAND AND CHORUS ROOM 3- AND NEED TO CHANGE ONE ENTRY KEY TO THE RESTROOMS FROM THE MEETINS ROOM. 12/15 - 5	12/15/2005 12/15/2005 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS
9773	Work In Progress RUBEN; I NEED THE WELDER MASHINE I NEED REPAIR SOMETHING THANK YOU....	2/16/2006 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
9723	Work In Progress Counselor Office - Need 6 mouse traps (old fashion ones) a/s/a/p - Glue Boards are not getting them.	2/15/2006 2/1/2006 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
9679	Work In Progress NEW CAFETERIA BOTH DRESSING ROOMS. 1.KEY FOR MAIN DOOR TO DRESSING ROOM BOTH BOYS AND GIRLS. 2 KEY FOR CLOSET DOOR BOTH BOYS AND GIRLS. 3 ADULT BATHROOMS NEED TO BE RE-CORE THE LOCKS 4.KEY FOR BATHROOOMS IN BOTH DRESSING ROOMS 5.MD-12 AND MD-2 KEYS NEED FOR MR. ANGELO AND MR. JEWETT. 6. LOCK FOR MS. FRANCIS SOCCER CABINET BY G.Y.M AREA.	2/14/2006 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS
10062	Work In Progress WE HAVE PROBLEMS WITH MAIN ENTRANCE DOOR SAMETIMES IT DOESN'T OPEN AT DAYCARE	2/28/2006 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS
9210	Work In Progress BROKENT COMMED FROM BOYS REST ROOMS AT THE NEW AREA WE NEED REPLACE	2/1/2006 Medium	Joel Herrera David Villalobos		Santa Teresa HS
9143	Work In Progress 1-27-06 2.0 RE-MOVE FLAIRS AT G.Y.M AREA. 1.0 CHECK HEATINGS UNITS 1.0 REPLACE ELECTRICAL SWITCH AT G.Y.M AREA 2.0 CHECK ELECTRICAL PROBLEM AT KITCHEN 2.0 CHECK AND REPAIR DOOR LOCK AT COACHES ROOM AT SOFBALL FIELD AREA. 1/27 - 8	1/30/2006 Medium	Joel Herrera Joel Herrera		Santa Teresa HS
9411	Work In Progress DOOR FROM MAINT ENTRANCE IT DOESN'T LOCKE MANNY WE NEED FIX IT.	2/6/2006 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5923	Work In Progress MIKE MUNOZ WE NEED BARRIER FENCE ON WEST SIDE AT SOCCER FIELD TO RETAIN BALLS OUT IT PLAY . ALSO NEED FENCE FROM 20 YARD LINE TO 20 YARD LINE IN FRONT OF FOOTBALL VISITORS SEATING AREA. SEE R GALLEGOS THANK YOU MIKE...	9/28/2005 Medium	Joel Herrera Michael Munoz		Santa Teresa HS
4463	Work In Progress SENER ON SINCK AT GIRLS REST ROOM IT DOESN'T WORK WE REPLACE IT .	8/11/2005 Medium	Joel Herrera David Villalobos		Santa Teresa HS
4807	Work In Progress MANNY MY MASTER KEY IS BROKEN IT DOESN'T WORK NO MORE.	8/23/2005 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS
5102	Work In Progress WE NEED REPLACE MA 51 AND TREE LOCKS AT R.O.T.C CLASS ROOMS.	8/30/2005 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS
4966	Work In Progress RUBEN WE NEED REPAIR THE WINDOWS AT DAYCAREBUILDING IT DOESN'T OPEN THANK YOU Route to Joel as per Mike 9/12/05 - mkv	8/26/2005 Medium	Joel Herrera Joel Herrera		Santa Teresa HS
4454	Work In Progress SMASHED WINDOW ON DOOR - STOLEN LARGE SCREEN TV. DISCOVERED BY MR. BUCKLEY	8/1/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
9213	Work In Progress ADVANCE BA/6124 NEW SCRUBBER NEEDS TO BE CHECKED OUT WATER NOT COMEING OUT THANK YOU .	2/1/2006 Medium	Luis Murillo Jimmy Carbajal		Santa Teresa HS
9948	Work In Progress Cafeteria - Green Hot Boxes need to remove mustache.	2/23/2006 Medium	Michael Munoz Arturo Nunez	Cafeteria	Santa Teresa HS
9146	Work In Progress South Bldg - Need to repair (outside) hosebibs.	1/30/2006 Medium	Mike Soria Jaime Mijarez		Santa Teresa MS
8556	Work In Progress Kitchen #1- Sink is clogged unable to use Kitchen #4- Pipes under sink leak	1/9/2006 Medium	Laura Parra David Villalobos	Classroom	Santa Teresa MS room 10
5113	Work In Progress AIR CONDITIONER DOES NOT TURN ON THE LEFT SIDE OF THE ROOM FACING CHALK BOARD ROOM 3 MR. DORANTES	8/31/2005 Medium	Laura Parra Jose Ambriz	Classroom	Santa Teresa MS
9776	Work In Progress s.t.m.s. need to paint new doors in front of gym	2/16/2006 Medium	Danny Miranda Jaime Mijarez		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9777	Work In Progress s.t.m.s. need to paint new door at music room	2/16/2006 Medium	Danny Miranda Jaime Mijarez		Santa Teresa MS
3387	Work In Progress Rm 1. N. bldg lower level Removal of carpet is going to require tile installation. Alfredo H. requested a work order for contractor.	7/7/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
3364	Work In Progress S.bldg custodial storage. please make 2ea. A-7 keys for principal and building mechanic.	7/6/2005 Medium	Jaime Mijarez Manny Lozoya		Santa Teresa MS
3465	Work In Progress N.bldg home ec rm 10. Ruben Ronquillo I am going to need a Miter saw to cut legs on ten of the tables. please make sure it has a good blade. I am planning this project for next week ( 7/18/05.) The wood is oak.	7/12/2005 Medium	Jaime Mijarez Ruben Ronquillo		Santa Teresa MS
3412	Work In Progress S.bldg upper level. Because of the shortage of classrooms Mrs. williams has to move the teachers lounge to a storage rm. The floor has no tile, can you include this room with the area's that the contractor will be installing floor tile. Attn: Alfredo holguin.	7/8/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
5149	Work In Progress N.bldg Rm 3. Mrs. williams would like to have a sidewalk that goes from Rm 3 exit door out to the fence. This way when there is a fire drill the special ed students on wheel chairs can be moved away from the building in case of an actual emergency.	9/1/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
5363	Work In Progress N.bldg maintenance and custodial. Would like a duct and register installed on heat pump.	9/9/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
10028	Work In Progress Locker key. PLease make a duplicate key for the locks. This key is the only master Margie or Mr. kamenski have.	2/27/2006 Medium	Jaime Mijarez Manny Lozoya		Santa Teresa MS
9910	Work In Progress Campus. Can you help us with a tracter to move all the sand that has accumulated by the walk ways and stairways to the gym. Requested by Mr. Mora.	2/22/2006 Medium	Jaime Mijarez Guadalupe Ontiveros		Santa Teresa MS
9911	Work In Progress Exhaust fans. I need for Joe A. to order some fan motors that I need to replace in S.bldg and N.bldg. I will E-mail you the motor info.	2/22/2006 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9828	Work In Progress Gym ceiling heaters not working.Need scissor lift to light up pilots.ASAP!!!!	2/17/2006 Medium	Jaime Mijarez Ruben Ronquillo		Santa Teresa MS
7470	Work In Progress Heat Pumps. Can you order ten time delay timers. ICM PART #ICM102 DELAY ON MAKE TIMER.	11/18/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
8159	Work In Progress Markee Sign. As per Mrs. Williams she would like to have the sign installed during winter break.	12/15/2005 Medium	Jaime Mijarez Carlos Castillo		Santa Teresa MS
8161	Work In Progress Principals office. Need a window installed on interior door.	12/15/2005 Medium	Jaime Mijarez Danny Miranda		Santa Teresa MS
8160	Work In Progress Markee Sign. As per Mrs. Williams she would like to have the sign installed during the winter break.	12/15/2005 Medium	Jaime Mijarez Guadalupe Ontiveros		Santa Teresa MS
9188	Work In Progress MANNY WE NEED FOR YOU TO CHANGE A KEY CYLINDER FROM Q TO P KEY.THIS IS A SCIENCE STORAGE ROOM.SEE MR. RODRIGUEZ.THANK YOU.	1/31/2006 Medium	Ismael Rodriguez Manny Lozoya	Classroom	Santa Teresa MS
9575	Work In Progress MR. SORIA PRUNE OUR CAMPUS TREES .THANK YOU.	2/10/2006 Medium	Ismael Rodriguez Mike Soria	Parking Lot	Santa Teresa MS
8104	Work In Progress JIMMEY I NEED 4 PAIRS OF LEATHER GLOVES FOR THE CUSTODIANS THE REASON IS WHEN WE DO WORK OUTSIDE THE BUILDINGS.THANK YOU. AS PER MIKE MUNOZ, WE WILL PURCHASING ON OUR OWN. WILL ISSUE TO CUSTODIANS AS SOON AS THEY ARE RECIEVED.	12/14/2005 1/17/2006 Medium	Ismael Rodriguez Aida Salcedo	Custodial	Santa Teresa MS
5308	Work In Progress I NEED A KEY A7 FOR THE PRINCIPAL TO HAVE ACCESS TO MY STORAGE ROOM. THANK YOU.SEE MR. RODRIGUEZ.	9/7/2005 Medium	Ismael Rodriguez Manny Lozoya	Custodial	Santa Teresa MS
3118	Work In Progress I NEED FOR GYM KEY CYLINDERS TOO TO BE CHANGE BEFORE 7/13/05.CONT.MR.RODRIGUEZ.	7/1/2005 Medium	Ismael Rodriguez Manny Lozoya		Santa Teresa MS
9184	Work In Progress Need to replace ballasts and lamp inside marquee	1/31/2006 Medium	Carlos Castillo Carlos Castillo	Parking Lot	Santa Teresa MS
10052	Work In Progress REINSTALLATION AND ELECTRICAL RECONNECTION OF MARQUEE	2/28/2006 Medium	Carlos Castillo Carlos Castillo		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6218	Work In Progress DUE TO WATER OVER FLOW, GYM FLOOR HAS BUBBLED BY FLOODING. NEED VENDOR TO DO A RECOMMENDATION AND QUOTE US.	10/10/2005 Medium	Aida Salcedo Michael Munoz		Santa Teresa MS
8653	Work In Progress NEED TO COMPLETE BUILDING INSPECTION FOR ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOU OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED & SIGNED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JANUARY 27, 2006	1/11/2006 Medium	Aida Salcedo Ismael Rodriguez		Santa Teresa MS
3330	Work In Progress Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3353	Work In Progress Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
9349	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
4023	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
4013	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3975	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
6437	Work In Progress please replace h20 fountain and unclog drain.	10/14/2005 Medium	David Villalobos	Office	Santa Teresa MS
7072	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
7110	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
7120	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
7768	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
7806	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
7816	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
8394	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
8404	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
8325	Work In Progress Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
8307	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
9397	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
9387	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
9514	Work In Progress AS PER MARY GARCIA, SUNLAND PARK IS REQUESTING 10 TABLES FOR SCIENCE FAIR STARTING AT 11:00 A.M. THIS MORNING THRU A USE OF BLDG (SHE RECEIVED IT ON 2/8/06 @ 4:00 P.M. -2 WK PRIOR NOTICE REQUESTED FOR USE OF BLDG). AS PER MIKE, CALLED SEBASTIAN AND HAD HIM PICK UP TABLES FROM GAC AND RETURN WHEN THEY ARE DONE USING THEM.	2/9/2006 Medium	Sebastian Diaz		Sunland Park ES
3423	Work In Progress Yearly - Sunland Park ES Emer. Light Test: Annual - Refer to PM schedule details.	7/10/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3278	Work In Progress Monthly - Sunland Park ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
3268	Work In Progress Monthly - Sunland Park ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3355	Work In Progress Yearly - Sunland Park ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3160	Work In Progress Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3179	Work In Progress Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
9120	Work In Progress 1.3 compartment sink is leaking 2. right side of serving line (cold unit) is not working. and 3. Blodgett Oven is still not heating properly  Marina Ramirez - SNP Manager 589-2545	1/27/2006 Medium	Alma Terrell Danny Orozco	Cafeteria	Sunland Park ES
9214	Work In Progress need borders for playground S.P.E.	2/1/2006 Medium	Danny Miranda Sebastian Diaz		Sunland Park ES
5422	Work In Progress NEED TO REMOVED DEAD TREES.	9/12/2005 Medium	Irene Trujillo Guadalupe Ontiveros		Sunland Park ES
5687	Work In Progress We have a mice problem throughout the school. Please help!	9/21/2005 Medium	Irene Trujillo Margret Villalobos		Sunland Park ES
3875	Work In Progress NEED REPLACEMENT KEYS FOR NURSE'S OFFICE DORR AND FILE CABINET	7/27/2005 Medium	Irene Trujillo Manny Lozoya		Sunland Park ES
7041	Work In Progress A door opening is needed from lounge to existing bathroom in nurse's office. Please send someone to check wiring. 1/25 - Faxed to Mr. Chavez for approval - mkv	11/4/2005 Medium	Irene Trujillo Carlos Castillo		Sunland Park ES
6878	Work In Progress ADD NEW ELECTRICAL OUTLET TO TEACHER'S LOUNGE.	10/31/2005 Medium	Irene Trujillo Carlos Castillo		Sunland Park ES
7042	Work In Progress A door opening is needed to connect lounge to existing bathroom in nurse's office. Please send someone to check the plumbing of sink, etc. 1/25 - Faxed to Mr. Chavez for approval - mkv	11/4/2005 Medium	Irene Trujillo David Villalobos		Sunland Park ES
6727	Work In Progress Roaches in classroom #25.	10/25/2005 Medium	Irene Trujillo Margret Villalobos		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6465	Work In Progress THE GROUNDS NEED TO BE SMOOTHED OUT AFTER THE RAIN. THE SAND WAS WASHED AWAY IN SOME AREAS.	10/17/2005 Medium	Irene Trujillo Guadalupe Ontiveros		Sunland Park ES
7522	Work In Progress A kitchen sink is needed in room 52. The new teacher's lounge.	11/22/2005 Medium	Irene Trujillo David Villalobos		Sunland Park ES
7523	Work In Progress Please remove carpet in room #52 and install floor tile.	11/22/2005 Medium	Irene Trujillo Michael Munoz		Sunland Park ES
9270	Work In Progress TA17 AND TA31 - PLEASE ADJUST SO THAT THE KEYS OPEN SIDE DOORS.	2/2/2006 Medium	Irene Trujillo Manny Lozoya		Sunland Park ES
9985	Work In Progress PORTABLE A & B NEED THE FLOOR TILE TO BE REPLACED.	2/24/2006 Medium	Irene Trujillo Michael Munoz		Sunland Park ES
6625	Work In Progress Need Heavy Duty Dolly for fire proof file cabinet on Monday October 24, 2005	10/21/2005 Medium	Larry Flores Maria Sitters		Sunland Park ES
9317	Work In Progress vac-needs repaier none	2/3/2006 Medium	Larry Flores Jimmy Carbajal	Elevator	Sunland Park ES
9319	Work In Progress vaccum needs repair	2/3/2006 Medium	Larry Flores Jimmy Carbajal	Custodial	Sunland Park ES
8041	Work In Progress Portable A - Broken window 30 x 28 Double Glass. Est. Damage 125.00	12/1/2005 Medium	Sebastian Diaz Ruben Ronquillo	Portables	Sunland Park ES
6692	Work In Progress Need 4 metal blinds for portable F 46"X 52" thank you.	10/24/2005 Medium	Sebastian Diaz Ruben Ronquillo		Sunland Park ES
7029	Work In Progress The sink in the room 41 is clog need to bring the snake also need to replace the fauset thank you	11/4/2005 Medium	Sebastian Diaz David Villalobos		Sunland Park ES
8879	Work In Progress Need to repair lock at cafeteria double doors. thank you.	1/19/2006 Medium	Sebastian Diaz Manny Lozoya		Sunland Park ES
8710	Work In Progress In the cafeteria the water heater need to replace the ingicion pilot. thank you	1/12/2006 Medium	Sebastian Diaz Jose Ambriz		Sunland Park ES
8712	Work In Progress need exhaust fan in boiler room smell bad thank you	1/12/2006 Medium	Sebastian Diaz Jose Ambriz		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9221	Work In Progress Need to replace door closer in front library. thank you	2/1/2006 Medium	Sebastian Diaz Manny Lozoya		Sunland Park ES
9082	Work In Progress Need to replace door knob portable E .Is broken is difficult to open from inside.thank you.	1/27/2006 Medium	Sebastian Diaz Manny Lozoya		Sunland Park ES
9834	Work In Progress Need to remove sand by the south area with the heavy tractor. thank you.	2/17/2006 Medium	Sebastian Diaz Guadalupe Ontiveros		Sunland Park ES
5195	Work In Progress 9/2/05 Lupe Ontiveros Need the heavy tractor to remove the weeds around the school thank you	9/2/2005 Medium	Sebastian Diaz Guadalupe Ontiveros		Sunland Park ES
9916	Work In Progress REQUESTING WIND SCREENING FOR BACK FENCING AREA LOCATED NEAR LIFT STATION AREA IS WHERE WIND SREENING NEEDS TO BE REPLACED	2/22/2006 Medium	Paul Quinones Ruben Ronquillo		Sunrise ES
9142	Work In Progress REQUESTING PEST CONTROL SPRAY FOR OAK TREES,PEST EATING LEAVES MAY LEAVE TREE DRY. THANKS Faxed PO o 2/10/06	1/30/2006 Medium	Paul Quinones Margret Villalobos		Sunrise ES
9257	Work In Progress REQUESTING 220V STEP DOWN TO 120V FOR OUTSIDE USE IN THE PATIO AREA FOR P.E.	2/2/2006 Medium	Paul Quinones Enrique Sotelo		Sunrise ES
8984	Work In Progress REQUESTING KEY CYLINDERS FOR ROOMS,205,AND 210 DOORS LOCATED IN BETWEEN CLASSROOMS REQUESTING ALSO A LOCK FOR THE FENCING AREA PROTECTING THE GAS METER ON SCHOOL GROUNDS	1/24/2006 Medium	Paul Quinones Manny Lozoya		Sunrise ES
6782	Work In Progress STERLING HEATING UNIT IN KITCHEN AREA.WILL NOT TURN ON ,MIXED AIR CONTROL NOT WORKING PROPERLY	10/26/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
3876	Work In Progress RM.307,BAD CIRCULATING PUMP NEED TO REPLACE	7/27/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3477	Work In Progress I NEED SAND FOR THE PLAY GROUNDS, THANKS.	7/12/2005 Medium	Paul Quinones Lorenzo Hernandez		Sunrise ES
3469	Work In Progress FENCING AREA IN BACK OF SCHOOL NEAR LIFT STATION NEEDS TO BE REPAIRED, AND ROLL GATE. PROBABLE HIGH WINDS ON 7-11-05 CAUSED THE DAMAGE. NO SIGNS OF VANDILISM ON SCHOOL PROPERTY	7/12/2005 Medium	Paul Quinones Michael Munoz		Sunrise ES
9294	Work In Progress both of my buffing machines are down need to be fixed	2/3/2006 Medium	Ramon Dominguez Jimmy Carbajal		Sunrise ES
9456	Work In Progress Need a gate key for El Paso Disposal.	2/7/2006 Medium	Juliet Parra Manny Lozoya		Sunrise ES
3533	Work In Progress Could you turn the air conditioning on we have teachers coming in to get a head start on their rooms. It is very hot and we would greatly appreciate it. Since we are a year round school the teachers need to report on Monday. Thank-you	7/14/2005 Medium	Joanne Munoz Jaime Gomez	Classroom	Sunrise ES
9333	Work In Progress Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
6887	Work In Progress The Wastewater Flow Meter needs to be checked for proper calibration ASAP	10/31/2005 High	Ricardo Jacquez		Sunrise ES
7495	Work In Progress please order fill dirt for new arrivals of new portables. sunrise, che, desert-trail	11/21/2005 Medium	Guadalupe Ontiveros	Portables	Sunrise ES
3629	Work In Progress please cut and weedeat in and around lift station. weeds are growing rapid and are going to end up on the playing fields.	7/18/2005 Medium	Paul Quinones		Sunrise ES
9390	Work In Progress Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
9399	Work In Progress Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
9028	Work In Progress please remove salt cedar trees that are at Valley Grove Baptist church. They are in the way for the bus drivers. W.O as per R.Chavez.	1/25/2006 High	Guadalupe Ontiveros	Parking Lot	Vado ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
9982	Work In Progress Outside electrical covers are being kicked off.	2/24/2006 Medium	Armando Diaz Danny Miranda		Vado ES
9983	Work In Progress Stove knobs were removed from stove.	2/24/2006 Medium	Armando Diaz Danny Orozco	Cafeteria	Vado ES
10051	Work In Progress 2/28/06 lupe need tiller to work dirt in playground	2/28/2006 Medium	Frank Lara Guadalupe Ontiveros		Vado ES
9113	Work In Progress Lupe Need to take out two tether balls poles out of la mesa and re-locate at vado	1/27/2006 Medium	Frank Lara Guadalupe Ontiveros		Vado ES
9641	Work In Progress Manny, having trouble with door on rm 310	2/13/2006 Medium	Frank Lara Frank Lara		Vado ES
8739	Work In Progress manny need to change lock p.e. office also re-key rm207 also duplicent keys for testing, counslor rm	1/13/2006 Medium	Frank Lara Frank Lara		Vado ES
8045	Work In Progress LUPE ONTIV. need backhoe at vado to spread sand for play ground equitement	12/12/2005 Medium	Frank Lara Guadalupe Ontiveros		Vado ES
4628	Work In Progress Need to meet contractor on Monday - to rekey school site.	8/17/2005 Medium	David Boyd Manny Lozoya		Vado ES