

# 375 - Work Orders In Progress

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13370	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Alma Del Valle Daycare
13440	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
13441	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
13410	Work In Progress Monthly - Alma Del Valle Roof Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Romauldo Apodaca Roof		Alma Del Valle Daycare
13489	Work In Progress Yearly - Alma Del Valle Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Alma Del Valle Daycare
13537	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Ruben Solis Custodial		Alma Del Valle Daycare
14117	Work In Progress two emergency lights not working.need to replace.also 2 exit signs.	7/26/2006 Medium	Romauldo Apodaca Enrique Sotelo Electrical		Alma Del Valle Daycare
14114	Work In Progress refrigeration unit is not working rooms 18 19 20	7/26/2006 Medium	Hector Villalobos Lorenzo Solis Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
14070	Work In Progress Refrigerated Unit is leaking a substancial amount of water it starting to ruin a bookcase. Please call and let us know when someone can come by so we can make arrangements to be here.	7/25/2006 Medium	Rosa Hidalgo Lorenzo Solis Heating/Ventilation /Air Conditioning	Office	Anthony ES Nurse's Office- at Old Anthony Primary
13933	Work In Progress need 12 2inch x 10 ft poles for football field	7/20/2006 Medium	Hector Villalobos Ruben Ronquillo General Maintenance	Football Field	Anthony ES
13927	Work In Progress NEED TO BORROW ANY GARDEN TOOLS, HOES, WEEEDEATER, RAKES,ETC.	7/20/2006 Medium	David Vega Jimmy Carbajal Custodial		Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13931	Work In Progress need to change lock to best lock new pt. upper primary	7/20/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Portables	Anthony ES
13992	Work In Progress FREEZER DID NOT HOLD ITS TEMPERATURE. (20 DEGREES)FOOD DEFROSTED  BECKY S. SNP MGR 882-3507	7/24/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES
13997	Work In Progress ECOLAB CHECKED DISHWASHER NOTICED 3 LEAKS: 1) ARMS / DISHMACHINE LEAKING 2) PUMP/GASKET LEANKING 3) VACUUM BREAKER/FINAL RINSE LEAKING (REPORT IN OFFICE FROM ECOLAB)	7/24/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES
13656	Work In Progress Nurse Coordinator Office - Need to replace valve on toilet (keeps running). As per Alfredo assign to David Villalobos he will be going out there in the morning.	7/10/2006 Medium	Alfredo Holguin David Villalobos Plumbing	Office	Anthony ES
13915	Work In Progress Freezer need parts - Becky says that she reported on 3/1/06 and it was worked on June 06, but it still needs parts  Rebecca Saenz - SNP Manager 882-3507	7/20/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Anthony ES
13917	Work In Progress Blade Cover to Slicer is Broken (reported on 5/02/06)  Rebecca Saenz - SNP Manager (old cafeteria) 882-3507	7/20/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Anthony ES
13918	Work In Progress Tilt Skillet has an electrical short - it turns on and off at will. (reported it in May, 2006)  Rebecca Saenz - SNP Manager 882-5607 (newer cafeteria)	7/20/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Anthony ES
13538	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo David Vega Custodial		Anthony ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To Craft</b>	<b>Area Type</b>	<b>Location Area Number</b>
13511	Work In Progress Yearly - Anthony ES Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Hector Villalobos Fire Protection		Anthony ES
13487	Work In Progress Yearly - Anthony ES Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Hector Villalobos Fire Protection		Anthony ES
13444	Work In Progress Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Hector Villalobos General Maintenance		Anthony ES
13442	Work In Progress Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Hector Villalobos General Maintenance		Anthony ES
13371	Work In Progress Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Hector Villalobos Fire Extinguishers		Anthony ES
13388	Work In Progress Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Hector Villalobos Roof		Anthony ES
13418	Work In Progress Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Anthony ES
14201	Work In Progress REFRIG. IS COMPLETELY DOWN THIS MORNING.  BECKY S. SNP MGR 882-3507	7/28/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES
13419	Work In Progress Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Berino ES
13389	Work In Progress Monthly - Berino ES Roof Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Ramiro Holguin Roof		Berino ES
13372	Work In Progress Monthly - Berino ES Monthly FE Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Ramiro Holguin Fire Extinguishers		Berino ES
13443	Work In Progress Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Ramiro Holguin General Maintenance		Berino ES
13413	Work In Progress Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Berino ES
13446	Work In Progress Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Ramiro Holguin General Maintenance		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13488	Work In Progress Yearly - Berino ES Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Ramiro Holguin Fire Protection		Berino ES
13512	Work In Progress Yearly - Berino ES Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Ramiro Holguin Fire Protection		Berino ES
13539	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Jimmy Cortez Custodial		Berino ES
13872	Work In Progress wheel keeps falling off need caps	7/19/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial Equipment Repair		Berino ES
13904	Work In Progress vaccum needs new handle	7/20/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial Equipment Repair		Berino ES
13905	Work In Progress need new vaccum bag for silva and 5 belts	7/20/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial Equipment Repair		Berino ES
13851	Work In Progress PORTABLE 156 KEY CORE IS HARD TO TURN NEEDS TO BE CHECK OUT OR REPLACE	7/18/2006 Medium	Ramiro Holguin Manny Lozoya Key and Lock		Berino ES
13995	Work In Progress 7/21/06 NEED NEW KEY MADE FOR LIBRARY TV ROOM THE OLD ONE DOESN'T WORK	7/24/2006 Medium	Ramiro Holguin Manny Lozoya Key and Lock		Berino ES
13998	Work In Progress 7/24/06. there is a leak at irrigation tank please send someone to repair it. thanks.	7/24/2006 Medium	Joe Ramirez Guadalupe Ontiveros Grounds		Chaparral ES
13950	Work In Progress 7/21/06. electric hand dryer in girls bathroom is not working properly it keeps running i need for enrique to check it out as soon as possible (2) request thanks.	7/21/2006 Medium	Joe Ramirez Enrique Sotelo Electrical		Chaparral ES
14147	Work In Progress 7/27/06. rms. 507,503 ,501 need door closers installed.	7/27/2006 Medium	Joe Ramirez Manny Lozoya Key and Lock		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
14148	Work In Progress 7/27/06. rm. 506 having trouble unlocking it have lubricated but still having problems.	7/27/2006 Medium	Joe Ramirez Manny Lozoya Key and Lock		Chaparral ES
13826	Work In Progress Need key for cabinet in rm-101. See Ms. Barrett never had a key tom cabinet	7/17/2006 Medium	Jennifer Corral Manny Lozoya Key and Lock	Classroom	Chaparral ES
13827	Work In Progress Need key for cabinet Ms. Yanez in rm-508	7/17/2006 Medium	Jennifer Corral Manny Lozoya Key and Lock	Dressing Room	Chaparral ES
13828	Work In Progress Need a key for Ms. Castaneda for her room, was never turned in Rm-p-2	7/17/2006 Medium	Jennifer Corral Manny Lozoya Key and Lock	Classroom	Chaparral ES
13693	Work In Progress Need for manny to make these additional name plates A.S.A.P RM# 514, 516, 518(2) CUSTodian (6) nurse(1), data entry, principal, assistant principal(2) secretary,conference room,concession as per mr cardona thank you.	7/12/2006 Medium	Joe Ramirez Manny Lozoya Key and Lock		Chaparral ES
13813	Work In Progress 7/17/06. sensor activated lavatory is not working in the 100 wing 3rd. request.	7/17/2006 Medium	Joe Ramirez Joe Ontiveros Plumbing		Chaparral ES
13814	Work In Progress 7/17/06. playground water fountain drain is clogged have tried to unclog it .	7/17/2006 Medium	Joe Ramirez Lorenzo Solis Plumbing		Chaparral ES
13816	Work In Progress Nurses Area - Need to install a power pole to new desk position. Pole needs to carry technology also.	7/17/2006 Medium	Alfredo Holguin Enrique Sotelo Electrical		Chaparral ES
13540	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Daniel Ramirez Custodial		Chaparral ES
13490	Work In Progress Yearly - Chaparral ES Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral ES
13513	Work In Progress Yearly - Chaparral ES Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To Craft</b>	<b>Area Type</b>	<b>Location Area Number</b>
13486	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral ES
13569	Work In Progress need to paint new door put in music rm.	7/6/2006 Medium	Danny Miranda Joe Ramirez Painting		Chaparral ES
13445	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral ES
13373	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral ES
13390	Work In Progress Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral ES
13420	Work In Progress Monthly - Chapparral ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Chaparral ES
13421	Work In Progress Monthly - Chapparral MS Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Chaparral MS
13414	Work In Progress Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Chaparral MS
13447	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral MS
13449	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral MS
13625	Work In Progress mike. portables 7-3and 4 need carpet replace	7/7/2006 Medium	Juan Vargas Michael Munoz Carpet Repair		Chaparral MS
13566	Work In Progress mike. new portable need put sidewalks	7/6/2006 Medium	Juan Vargas Michael Munoz Concrete		Chaparral MS
13650	Work In Progress storage and restroom on new portable need two lockset	7/10/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13545	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Robert Gonzalez Custodial		Chaparral MS
13805	Work In Progress NEED TO INSTALL SCORE BOARD.	7/17/2006 Medium	Michael Munoz Enrique Sotelo Electrical		Chaparral MS
13723	Work In Progress NEED TO USE THE APPLIANCE DOLLY TO MOVE THE FIRE PROVE FILING CABINETS IN THE NURSES OFFICE AGIAN. THANK YOU	7/13/2006 Medium	Robert Gonzalez Sal Acuna Custodial		Chaparral MS
13906	Work In Progress need to replace time delay relay on wwtp needed asap pumps will not work with out it thanks.	7/20/2006 Medium	Ricardo Jacquez Ricardo Jacquez Sewage/Water Treatment Plant		Chaparral MS
13910	Work In Progress need 4 scringrave dumps on nurse area	7/20/2006 Medium	Juan Vargas Guadalupe Ontiveros Grounds		Chaparral MS
14121	Work In Progress Need an extra A 29 and A31 key made. Also we need an additional key for room 102, we have multiple people in there now.	7/26/2006 Medium	Elena Palacios Manny Lozoya Key and Lock	Office	Chaparral MS
14012	Work In Progress need replace a/c master cool 6500 on stage area	7/24/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning		Chaparral MS
13698	Work In Progress GUILLERMO & GIMMY - ON MONDAY 7/24/06 - NEED TO HELP DAVID MOVE FURNITURE FROM 2 CLASS ROOMS. APPROX 2 HRS WORK.	7/12/2006 Medium	Aida Salcedo Jimmy Carbajal Custodial	Portables	Desert Pride
13546	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo David Acosta Custodial		Desert Pride
13492	Work In Progress Yearly - Desert Pride Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin David Acosta Fire Protection		Desert Pride

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To Craft</b>	<b>Area Type</b>	<b>Location Area Number</b>
13515	Work In Progress Yearly - Desert Pride Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin David Acosta Fire Protection		Desert Pride
13450	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
13454	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
13411	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin David Acosta Fire Extinguishers		Desert Pride
13422	Work In Progress Monthly - Desert Pride Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Desert Pride
13391	Work In Progress Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin David Acosta Roof		Desert Pride
13392	Work In Progress Monthly - Desert Trail Roof Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Johnny Acuna Roof		Desert Trail Intermediate
13375	Work In Progress Monthly - Desert Trail Monthly FE Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Johnny Acuna Fire Extinguishers		Desert Trail Intermediate
13423	Work In Progress Monthly - Desert Trail Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Desert Trail Intermediate
13415	Work In Progress Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Desert Trail Intermediate
13448	Work In Progress Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Johnny Acuna General Maintenance		Desert Trail Intermediate
13453	Work In Progress Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Johnny Acuna General Maintenance		Desert Trail Intermediate
13516	Work In Progress Yearly - Desert Trail Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Johnny Acuna Fire Protection		Desert Trail Intermediate
13571	Work In Progress need to paint new frame in rm. # 411	7/6/2006 Medium	Danny Miranda Johnny Acuna Painting		Desert Trail Intermediate
13572	Work In Progress need to paint new door in hallway	7/6/2006 Medium	Danny Miranda Johnny Acuna Painting		Desert Trail Intermediate



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13578	Work In Progress need to relocate fire ext. in hallway	7/6/2006 Medium	Danny Miranda Johnny Acuna General Maintenance	Hallway/Corridor	Desert Trail Intermediate
13493	Work In Progress Yearly - Desert Trail Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Johnny Acuna Fire Protection		Desert Trail Intermediate
13547	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Marisela Torres Custodial		Desert Trail Intermediate
13786	Work In Progress please provide landings and sidewalks to 1st new portable.	7/14/2006 Medium	Michael Munoz Michael Munoz Carpet Repair	Portables	Desert Trail Intermediate
13787	Work In Progress please provide landing and sidewalk to 2nd new portable.	7/14/2006 Medium	Michael Munoz Michael Munoz Carpet Repair	Portables	Desert Trail Intermediate
13788	Work In Progress please provide sidewalk to connect existing portables to new portables.	7/14/2006 Medium	Michael Munoz Michael Munoz Concrete	Portables	Desert Trail Intermediate
14006	Work In Progress need (2) keys made for room #206. J-42	7/24/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
14017	Work In Progress new custodial storage room: need to secure by the end of the day. Need to install 5 core locks.	7/24/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
13999	Work In Progress aspiradora #k 96A00001522 no esta haciendo contacto se apaga sola. gracias	7/24/2006 Medium	Marisela Torres Jimmy Carbajal Custodial Equipment Repair		Desert Trail Intermediate
14000	Work In Progress TENEMOS UNA EXTENCION ELECTRICA QUE LE FALTA UNA TERMINAL, NOS LA PODRIAN COMPONER POR FAVOR? GRACIAS.	7/24/2006 Medium	Marisela Torres Jimmy Carbajal Custodial Equipment Repair		Desert Trail Intermediate
13989	Work In Progress Left doorknob on portable door is loose and teacher has trouble locking and unlocking door. Please check out. Thank You.....	7/24/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock	Portables	Desert Trail Intermediate PORTABLE #402
13990	Work In Progress need keys made for large file cabinet. Thank You.....	7/24/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock	Portables	Desert Trail Intermediate Portable #408

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13991	Work In Progress Need keys made for Cabinet and File Cabinet. Thank You.....	7/24/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock	Desert Trail Intermediate Portables	Portable #405
13985	Work In Progress Portable #414: Teacher claiming that her door handle locks sometimes from the outside and students cannot open the door. Also, the door handle keeps falling off from the inside. PLEASE CHECK OR REPLACE A/S/A/P. THANK YOU.....	7/24/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock	Desert Trail Intermediate Portables	PORTABLE #414
14119	Work In Progress Please replace hand dryer to boys restroom in the nw hall. Does not work and is missing parts. Thank You.....	7/26/2006 Medium	Johnny Acuna Enrique Sotelo Electrical	Desert Trail Intermediate	
14120	Work In Progress Requesting a box of aerosol cans of Evaporator coil cleaner. Thank You....	7/26/2006 Medium	Johnny Acuna Lorenzo Solis Heating/Ventilation /Air Conditioning	Desert Trail Intermediate	
14182	Work In Progress Need a new door closure for kitchen main door going outdoors.	7/27/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock	Desert Trail Intermediate	
14138	Work In Progress Need help with some Emergency light fixtures.	7/26/2006 Medium	Johnny Acuna Enrique Sotelo Electrical	Desert Trail Intermediate	
14179	Work In Progress Need a replacement light fixture cover (panel) for the library. The old one is broken and is missing a piece. Thank You.....	7/27/2006 Medium	Johnny Acuna Enrique Sotelo Electrical	Desert Trail Intermediate	
14255	Work In Progress Need base and primary screening to spread in between portables. Thank You.....	7/31/2006 Medium	Johnny Acuna Robert Sanchez Grounds	Desert Trail Intermediate	
14267	Work In Progress 7/31/06 Need base and crusher fine to spread between new portable buildings. (When raining, it gets too muddy and slippery: Students cannot get out and go to their other classes). Principal's Request... Thank You.....	7/31/2006 Medium	Johnny Acuna Robert Sanchez Grounds	Desert Trail Intermediate	
14249	Work In Progress Continued raining adding to more erosion around ground area of school creating larger ditches and more safety hazards exposing underground lines, drainage areas filled with sand decreasing water run off.	7/31/2006 Medium	Miguel Aguilar Robert Sanchez Grounds	Desert View ES	

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
14250	Work In Progress Principal requesting master key set , having difficulty unlocking and locking doors, needs new copies.	7/31/2006 Medium	Miguel Aguilar Manny Lozoya Key and Lock		Desert View ES
14205	Work In Progress Heavy rain has eroded grounds around school, creating large ditches, exposing pvc water pipes, hazard to students, cafeteria staff vehicle stuck in mud which covered paved road around school, another hazard for school delivery vehicles.	7/28/2006 Medium	Miguel Aguilar Robert Sanchez Grounds		Desert View ES
14206	Work In Progress pat aguilar hall ways brock glass - windows 3-13 1/2" x 64" safty glass door 10-13"x15" glass windows 2-5 1/2"x 13 1/4" safty glass 1-46 1/2"x20 #/4" window port	7/28/2006 Medium	Patricio Aguilar Ruben Ronquillo Glass\Window Repairs		Desert View ES
13548	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Miguel Aguilar Custodial		Desert View ES
13494	Work In Progress Yearly - Desert View ES Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Patricio Aguilar Fire Protection		Desert View ES
13652	Work In Progress Broken royal vacuum #E00G00004092, handle completely broken off from base/engine of unit.	7/10/2006 Medium	Miguel Aguilar Jimmy Carbajal Custodial Equipment Repair		Desert View ES
13653	Work In Progress pat aguilar remove sand from wall remove sand rain drains move sand back up hill after rains	7/10/2006 Medium	Patricio Aguilar Guadalupe Ontiveros Grounds		Desert View ES
13517	Work In Progress Yearly - Desert View ES Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Patricio Aguilar Fire Protection		Desert View ES
13451	Work In Progress Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Patricio Aguilar General Maintenance		Desert View ES
13455	Work In Progress Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Patricio Aguilar General Maintenance		Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13424	Work In Progress Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Desert View ES
13456	Work In Progress Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Juan Ambriz General Maintenance		GAC
13452	Work In Progress Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Juan Ambriz General Maintenance		GAC
13439	Work In Progress Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		GAC
13416	Work In Progress Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		GAC
13643	Work In Progress C-Wing - Need a name plate for: Jessica C. Hernandez SPED Data Clerk	7/10/2006 Medium	Margret Villalobos Manny Lozoya Key and Lock	Office	GAC SPED Office
13549	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Ralph Lara Custodial		GAC
14134	Work In Progress AS PER ANNE-NEEDS A FILE HOLDER THAT IS ASSEMBLED TO THE WALL IN THE APPLICATION ROOM - NEEDS TO BE REMOVED FROM THERE AND RELOCATED IN THE FINANCE DEPT. (SEE ANNE BEFORE REMOVING IT)	7/26/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Office	GAC B-WING
14111	Work In Progress Light switch in Elisa office need's to be changed. Thank you.	7/26/2006 Medium	Ralph Lara Carlos Castillo Electrical		GAC A wing Elisa office.
14156	Work In Progress AS PER MS. BERRY-NEEDS ITEMS TO BE ASSEMBLED IN THE CAFETERIA FOR THE PRE-K (BASKETBALL HOOP, SAND & WATER TABLE & WOODWORKING BENCH)	7/27/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Cafeteria	GAC PRE-K
14157	Work In Progress SELMA SEPULVEDA'S OFFICE LIGHTING NEEDS TO BE CHANGED OUT. LIGHTS ARE FLICKERING OFF & ON	7/27/2006 Medium	Mary Garcia Carlos Castillo Electrical	Office	GAC B-WING

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
14158	Work In Progress AS PER LUCY GARCIA-NEED DESK DRAWERS TO BE FIXED. (DRAWERS DO NOT CLOSE- MAYBE OFF THE DRAWER TRACK)	7/27/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Office	GAC B-WING
14051	Work In Progress AS PER SALLY SEPULVEDA- THERE IS NO POWER ON THE ELECTRICAL OUTLETS IN THE FILE ROOM W/HR.	7/25/2006 Medium	Mary Garcia Carlos Castillo Electrical	Office	GAC B-WING
14052	Work In Progress AS PER YVONNE LOZANO-NEEDS A KEY MADE (#A4) WHICH IS OFF MASTER. USED FOR STORAGE OF TESTING MATERIALS.	7/25/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC C-WING
14053	Work In Progress AS PER GINGER BERRY- NEEDS 3 AV CARTS TO BE ASSEMBLED. (THEY ARE STORED IN THE CAFETERIA)	7/25/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Classroom	GAC
13955	Work In Progress As per Mr. Hougen at main lobby, sliding door on top right side, needs stucco patching.  Thank you;	7/21/2006 Medium	Ralph Lara Juan Ambriz General Maintenance	Office	GAC
13957	Work In Progress Jimmy my vacuum cleaner needs a new extension cord, and service.  Thank you;	7/21/2006 Medium	Ralph Lara Jimmy Carbajal Custodial Equipment Repair	Custodial	GAC A wing area
13993	Work In Progress AS PER MR. HAUGEN-ENTRANCE @ GAC NEEDS TO BE PAINTED. (STACCO IS BRAKING) JUAN IS ALREADY AWARE BUT NEEDS PAINT & STACCO TO REFILL HOLES. (COLOR IS LIKE AN IVRY)	7/24/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Office	GAC OUTSIDE ENTRANCE @ GAC
14004	Work In Progress AS PER NANCY -IF CUSTODIAL CAN MOVE ALL EXTRA HANDBOOKS FROM DIAG'S ROOM INTO SUPT'S FILING ROOM.	7/24/2006 Medium	Mary Garcia Custodial	Office	GAC A-WING
13921	Work In Progress AS PER GINGER BERRY - NONE OF THE CLASSROOMS WERE CLEANED NOR DUSTED. (THE ONLY THNING DONE WAS THE WAXING ON THE FLOORS IN THE PRE-K AREA)	7/20/2006 Medium	Mary Garcia Ralph Lara Custodial	Classroom	GAC ALL PRE-K
13862	Work In Progress AS PER LUCY MEZA-BATHROOM BEHIND RECEPTION AREA IS CLOGGED. NEEDS A PLUMBE MR. GUSTAVO SOLIS ALREADY TRIED UNCLOGGING IT BUT IT HAPPEN AGAIN	7/18/2006 Medium	Mary Garcia David Villalobos Plumbing	Restroom (Girls)	GAC C-WING

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13845	Work In Progress ICE MACHINE IS LEAKING ALOT OF WATER FROM THE LINE.	7/18/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	GAC
	GESSICA - SNP MGR 882-6784				
14237	Work In Progress AS PER LISA SANCHEZ-NEED STORAGE BOXES TO BE TAKEN FROM HER OFFICE INTO THE MORGAN FOR STORAGE.	7/28/2006 Medium	Mary Garcia Ralph Lara Custodial	Office	GAC C-WING
14271	Work In Progress AS PER MS. BERRY-NEED FOR WINDOW SEALS TO BE CLEANED OUT (DEAD BUGS/DIRT)	7/31/2006 Medium	Mary Garcia Juan Ambriz Custodial	Cafeteria	GAC CAFETERIA & CLASSROOMS
14272	Work In Progress AS PER MS. BERRY-NEED CAFETERIA BLINDS TO BE CLEANED. (FULL OF CHOCOLATE MILK)	7/31/2006 Medium	Mary Garcia Ralph Lara Custodial	Cafeteria	GAC CAFETERIA
14273	Work In Progress AS PER MS. BERRY- DOORS IN ALL CLASSROOMS NEED TO HAVE WEATHER STRIPS INSTALLED TO KEEP DIRT & WATER OUT.	7/31/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Classroom	GAC ALL CLASSROOMS
14275	Work In Progress AS PER MS. SALINAS-NEED TO INSTALL A CURTAIN ROD HOLDER. (CURTAINS/DRAPE FELL) WILL NEED ANCHERS FOR ROD HOLDER	7/31/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Office	GAC C-WING
14266	Work In Progress Requested by Ms. Gutierrez Rm. 823-Key cylinders are full of glue or silicone, please clean as soon as possible.	7/31/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
14248	Work In Progress Need an electrician to install an audible alarm on emergency pump shut-off system. Pool Inspector wants it installed before the season is over. Contact Raul for details	7/30/2006 Medium	Raul Sanchez Carlos Castillo Electrical	Pool	Gadsden HS
14218	Work In Progress GLASS AT ROOM 154 NEED TOBE REPLACE AT OLD ENG BLDG ROOM 154 40X39	7/28/2006 Medium	Mario Apodaca Ruben Ronquillo Glass\Window Repairs		Gadsden HS
14220	Work In Progress OUTLET AT V-GYM LOCK ROOM #339 OFFICE HAVE ON POWR	7/28/2006 Medium	Mario Apodaca Carlos Castillo Electrical		Gadsden HS
14202	Work In Progress Electrical needs to be connected to unit at Press Box.	7/28/2006 Medium	Jose Ambriz Michael Mc Dermott Heating/Ventilation /Air Conditioning		Gadsden HS
13822	Work In Progress academic bldg was broken in over the week end. please fix what was damaged. areas are on e-mail sent.	7/17/2006 Medium	Michael Munoz Manny Lozoya Key and Lock		Gadsden HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To Craft</b>	<b>Area Type</b>	<b>Location Area Number</b>
13868	Work In Progress NEED A 1 HP 2 SPEED E/COOLER MOTER W/ PULLEY FOR KITCHEN. ASAP	7/19/2006 Medium	Mario Apodaca Lorenzo Solis Heating/Ventilation /Air Conditioning		Gadsden HS
13697	Work In Progress NEED TO LIGH SHOWER SCRUB, SEAL & WAX NEW PORTABLE BEFORE PLACING ITEMS INSIDE.	7/12/2006 Medium	Aida Salcedo Jesus Estrada Custodial	Portables	Gadsden HS
14016	Work In Progress Need a truck load of crashfined rock;To be spread around new portable,to avoid skunks from nesting under it.THANK YOU!!	7/24/2006 Medium	Fernando Moncayo Robert Sanchez Grounds		Gadsden HS
13960	Work In Progress Requested by Velia Rm. 342 Academic Building- Four keys are needed of HF16 for room #342. Two Social Workers will share this office now.	7/21/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
14159	Work In Progress Requested by Isela Counseling Center-The toilet is clogged and does not allow water to drain properly, please fix as soon as possible.	7/27/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
14151	Work In Progress Requested by Erica Acosta Rm. 227 North Building-Needs a name plate with her name "Erica Acosta"	7/27/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
14152	Work In Progress Requested by L. Chavez V. Gym-Clock in Varsity Gym (south wall) is not working, it does have power. Lights on scoreboard don't work.	7/27/2006 Medium	Velia Alarcon Carlos Castillo Electrical		Gadsden HS
14153	Work In Progress Requested by Bill Dickson Rm. 109 Main Building- Special Ed. meeting office, place an air conditioner duct to control temperature in room.	7/27/2006 Medium	Velia Alarcon Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
14154	Work In Progress Requested by Velia Front Office-The ceiling is leaking above the receptionist desk. A couple of ceiling tiles need to be replaced.	7/27/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
14056	Work In Progress NEED TO RUN POWER TOO NEW E/COORER AT PRESS BOX.	7/25/2006 Medium	Mario Apodaca Enrique Sotelo Electrical	Football Field	Gadsden HS
14110	Work In Progress need to divide rm.#652 with new wall & door	7/26/2006 Medium	Danny Miranda Danny Miranda General Maintenance	Classroom	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13550	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Jesus Estrada Custodial		Gadsden HS
13496	Work In Progress Yearly - Gadsden HS Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Mario Apodaca Fire Protection		Gadsden HS
13638	Work In Progress AS PER BUILDING MECHANICS NEED 20 BOXES OF FLOURESCENT LAMPS	7/10/2006 Medium	Carlos Castillo Carlos Castillo Electrical		Gadsden HS
13581	Work In Progress Due to recent vandalism at the pool we need to re-key ASAP. Found no damage treated pool as a safety precaution. Chainlink fence needs minor repairs deck had human feces and was powerwashed and disinfected. Ben Casillas #944	7/3/2006 High	Alfredo Holguin Manny Lozoya Key and Lock	Pool	Gadsden HS
13519	Work In Progress Yearly - Gadsden HS Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Fernando Moncayo Fire Protection		Gadsden HS
13367	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Sebastian Diaz Fire Extinguishers		Gadsden HS
13457	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
13460	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Mario Apodaca General Maintenance		Gadsden HS
13425	Work In Progress Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Gadsden HS
13426	Work In Progress Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Gadsden MS
13463	Work In Progress Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Rudy Arreola General Maintenance		Gadsden MS



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13458	Work In Progress Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Rudy Arreola General Maintenance		Gadsden MS
13588	Work In Progress We need to have some fans installed in the cafeteria the boxes already there. just need the fans. Route to Rudy why can't you do this. If u need help I will send someone to help you - M. Munoz 7/12/06	7/6/2006 Medium	Rudy Arreola Rudy Arreola General Maintenance	Cafeteria	Gadsden MS
13589	Work In Progress Window is cracked need to have it replaced.	7/6/2006 Medium	Rudy Arreola Ruben Ronquillo Glass\Window Repairs	Hallway/Corridor	Gadsden MS
13551	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Juan Acosta Custodial		Gadsden MS
14048	Work In Progress repair the lock on room 156	7/25/2006 Medium	Dana Hamel Manny Lozoya Key and Lock	Classroom	Gadsden MS
14050	Work In Progress replace the hardware on outside doors a wing b wing	7/25/2006 Medium	Dana Hamel Manny Lozoya Key and Lock		Gadsden MS a wing
14096	Work In Progress As per Mike Munoz,need to order 3000 flourescent lamp for classroom replacement thruout the district and have some leftover for stock.G.H.S was selected as location for generating w.o. purposes.	7/26/2006 Medium	Carlos Castillo Carlos Castillo Electrical	Classroom	Gadsden MS
13962	Work In Progress ATHLETIC OFFICE - HAVING PROBLEMS W/CASH BOX KEY IS STUCK AND NOT ABLE TO TAKE OUT.	7/21/2006 Medium	Terry Alvarado Manny Lozoya Key and Lock		Gadsden MS
13986	Work In Progress VOCATIONAL BLDG, GRASS IS GROWING SOUTH OF BLDG IN FRONT OF CLASSROOMS.PLEASE CUT AND ALSO ALONG BLDG AND AROUND AND THEN APPLY ROUND-UP BEFORE SCHOOL STARTS.	7/24/2006 Medium	Michael Munoz Rudy Arreola Grounds		Gadsden MS
13778	Work In Progress please clean all debre in boiler room, chiller and gas fenced in lines area.	7/14/2006 Medium	Michael Munoz Rudy Arreola General Maintenance		Gadsden MS
13911	Work In Progress portable by gym. The roof was blown due to high winds. please repair roof with new one.	7/20/2006 Medium	Michael Munoz Danny Miranda Roof	Portables	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
14203	Work In Progress Bad water leak in bandroom corridor by tropy case.	7/28/2006 Medium	Rudy Arreola David Boyd Roof	Hallway/Corridor	Gadsden MS
14204	Work In Progress We had a bad leak in RM 130 this is the first time it leak in this area of bldg.	7/28/2006 Medium	Rudy Arreola David Boyd Roof	Classroom	Gadsden MS
14164	Work In Progress Rm 146 door is hard to open and to lock the key gets stuck <ALL READY TRIED SOME LUBRICATION SPRAY>	7/27/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock	Classroom	Gadsden MS
14254	Work In Progress Portable 500 suspened ceiling came down and lights Mike could you please send me some help so we can take of the problem. As per Mike Danny Miranda can assist. - 8/1/06 - mkv	7/31/2006 Medium	Rudy Arreola Danny Miranda Roof		Gadsden MS
14163	Work In Progress BUFFER MACHINE NOT WORKING GOOD- MACHINE OLD, CAN YOU PLEASE SERVICE AND POSSIBLE PROVIDE NEW PADS. THE ONE IT HAS IS GOOD BUT POSSIBLE COULD USE A NEW ONE.	7/27/2006 Medium	Maria Sitters Jimmy Carbajal Custodial Equipment Repair		La Mesa ES
14007	Work In Progress GUILLERMO & JIMMY - ON TUESDAY, JULY 25 - NEED TO PICK UP CABINETS FROM GLORIA GONZALES @ LM AND DELIVER TO ANTHONY ELEMENTARY (PRE-K PROGRAM, VILLAGE, NEW PORTABLE)	7/24/2006 Medium	Aida Salcedo Jimmy Carbajal Custodial		La Mesa ES
14054	Work In Progress enrique 1. need to replace light fixures outside for security 2. also need a case of lights for outside lighting	7/25/2006 Medium	Frank Lara Enrique Sotelo Electrical		La Mesa ES
14155	Work In Progress HAVING A MICE PROBLEM, NEED TO SCHEDULE SERVICE CALL A.S.A.P.	7/27/2006 Medium	Aida Salcedo Margret Villalobos Pest Control		La Mesa ES
13465	Work In Progress Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Frank Lara General Maintenance		La Mesa ES
13459	Work In Progress Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Frank Lara General Maintenance		La Mesa ES
13427	Work In Progress Monthly - La Mesa ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		La Mesa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13428	Work In Progress Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		La Union ES
13379	Work In Progress Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Salvador Gonzalez Fire Extinguishers		La Union ES
13397	Work In Progress Monthly - La Union ES Roof Inpsection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Salvador Gonzalez Roof		La Union ES
13461	Work In Progress Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Salvador Gonzalez General Maintenance		La Union ES
13469	Work In Progress Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Salvador Gonzalez General Maintenance		La Union ES
13499	Work In Progress Yearly - La Union ES Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Salvador Gonzalez Fire Protection		La Union ES
13553	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Santos Galindo Custodial		La Union ES
13522	Work In Progress Yearly - La Union ES Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Salvador Gonzalez Fire Protection		La Union ES
13932	Work In Progress 7/20/06 Underground leaking in restroom. May you come please.	7/20/2006 Medium	Salvador Gonzalez David Villalobos Plumbing		La Union ES
13912	Work In Progress Need service on 2 vaccums.	7/20/2006 Medium	Santos Galindo Jimmy Carbajal Custodial Equipment Repair		La Union ES
13923	Work In Progress MIKE, ROOM 206 NEEDING APPROX. 10 COAT HOOKS	7/20/2006 Medium	Grace Alvarado Michael Mc Dermott General Maintenance		Loma Linda ES
13819	Work In Progress Attn lupe we need some type of fill dirt put in where pine trees are located next to school . also we need to clean pathways for students befor school starts. thank you.	7/17/2006 Medium	Michael Mc Dermott Guadalupe Ontiveros Grounds	Athletic Field	Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13820	Work In Progress 7-17-6 attn joe we need to repair electronic sinks. they are leaking bad. please before school starts.	7/17/2006 Medium	Michael Mc Dermott Joe Ontiveros Plumbing	Restroom (Boys)	Loma Linda ES
13821	Work In Progress 7-17-6 attn lorenzo please repair drinking fountain before school starts.	7/17/2006 Medium	Michael Mc Dermott Lorenzo Solis Heating/Ventilation /Air Conditioning	Hallway/Corridor	Loma Linda ES
13908	Work In Progress Washing Machine is not spinning and it was leaking alot of water.  Frances Black - SNP Manager 882-4707	7/20/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Loma Linda ES
13954	Work In Progress MANY L, PLEASE, PLEASE, PLEASE. 2 ND REQUEST, I NEEDING KEY FOR BOOKROOM	7/21/2006 Medium	Grace Alvarado Manny Lozoya Key and Lock		Loma Linda ES
13554	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Luis Solis Custodial		Loma Linda ES
13462	Work In Progress Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Michael Mc Dermott General Maintenance		Loma Linda ES
13417	Work In Progress Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Loma Linda ES
13429	Work In Progress Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Loma Linda ES
14196	Work In Progress IN MS. DESANTIAGO'S ROOM THERE ARE SEVERAL DESKS THAT NEED ADJUSTMENTS AND THE TABLES ARE WOBBLY.	7/28/2006 Medium	Grace Alvarado Michael Mc Dermott General Maintenance		Loma Linda ES
14264	Work In Progress MIKE, NEEDING COAT RACK AND SMALL BULLETIN BOARD TO BE REMOVED FROM 202 AND PLACED IN ROOM 209	7/31/2006 Medium	Grace Alvarado Michael Mc Dermott General Maintenance		Loma Linda ES
14265	Work In Progress NEEDING FAUCET IN ROOM 209 REPAIRED. MAJOR LEAK	7/31/2006 Medium	Grace Alvarado Fred Appelzoller Plumbing		Loma Linda ES
14210	Work In Progress PORTABLE 611&612-INSTALL DOWN SPOUTS	7/28/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To Craft</b>	<b>Area Type</b>	<b>Location Area Number</b>
14211	Work In Progress PORTABLE 611&612-BUILD DIRT BORDERS AROUND PORTABLE (SAFETY HAZARD)	7/28/2006 Safety	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
14213	Work In Progress CUT WEEDS AT NEW PLAYGROUND	7/28/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
14214	Work In Progress NEW PLAYGROUND NEEDS MORE SAND. (SAFETY HAZARD)	7/28/2006 Safety	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
14181	Work In Progress CLEAN UNDER PORTABLE RAMPS	7/27/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
14168	Work In Progress Clean trash debri etc. around Morgan Building.	7/27/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
14174	Work In Progress Trim,dig well, cut weeds and water Pecan Trees.	7/27/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
14175	Work In Progress Cut grass around Mobile Home Occupant.	7/27/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
14177	Work In Progress CUT WEEDS AT BACK STOP.	7/27/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
14178	Work In Progress WATER PLAY FIELD MANUALLY.	7/27/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
14183	Work In Progress CUT GRASS AROUND BORDERS ON PLAYGROUND.	7/27/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
14189	Work In Progress BARRACKS-WATER LEAK ON ROOF.REMOVE MOLD ON WALL. (SAFETY HAZARD)	7/27/2006 Safety	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
14190	Work In Progress DISPOSE DOOR FRAME IN ROOM 612 (SAFETY HAZARD)	7/27/2006 Safety	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
14191	Work In Progress FILL DIRT WHERE TREE WAS REMOVED BY BARRACKS. (SAFETY HAZARD)	7/27/2006 Safety	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
13430	Work In Progress Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Mesquite ES
13399	Work In Progress Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Romauldo Apodaca Roof		Mesquite ES
13381	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13464	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
13555	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Ruben Solis Custodial		Mesquite ES
13501	Work In Progress Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Mesquite ES
13524	Work In Progress Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Mesquite ES
13474	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
13760	Work In Progress ON MONDAY, JULY 17 - NEED TO MOVE BOXES & BELONGONS FOR MS. RANKIN FROM STORAGE @ MQ TO LM. LIFT TRUCK WOULD BE RECOMMENDED. CALL ROMA OR RUBEN IF YOU HAVE ANY QUESTIONS.	7/14/2006 Medium	Aida Salcedo Guillermo Hernandez Custodial		Mesquite ES
13757	Work In Progress vaccum cleaner needs to be repair (broken shell)	7/14/2006 Medium	Ruben Solis Jimmy Carbajal Custodial Equipment Repair	Custodial	Mesquite ES
13758	Work In Progress vacuum cleaner needs to be replace with a new one. This vacuum cleaner has been fixed several times and still does not work efficiently	7/14/2006 Medium	Ruben Solis Jimmy Carbajal Custodial Equipment Repair	Custodial	Mesquite ES
14009	Work In Progress NEED TO DO A HIGH LOW DUSTING IN MS. PETERSON, ROOM # 22 - AS PER MR. SANCHEZ.	7/24/2006 Medium	Virginia Salazar Raul Romero Custodial		Riverside ES
14013	Work In Progress MR ANGEL GONZALES SIR WOULD LIKE THE USE OF THE BOBCAT HAVE SOME LARGE RUN OFF TO COVER BY THE PORTABLE AND REMOVE SAND FROM IN SIDE ROCK WALL LOWER GRADE PLAYGROUND THANK YOU SIR AND GOD BLESS	7/24/2006 Medium	Adan Duran Angel Gonzales Equipment		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13570	Work In Progress MANNY LOZOYA SIR NEED TO REPLACE 3 THREE MASTER KEYS THE OLD ONES ARE WORE OUT PLUS WE NEED TO REPLACE SOME LOCKS THANK YOU SIR	7/6/2006 Medium	Adan Duran Manny Lozoya Key and Lock		Riverside ES
13594	Work In Progress MR ALFREDO HOLGIN SIR THERE ARE ABOUT 13 EXIT DOORS WITH BROKEN GLASS SOME ARE BAD MR SANCHES AND MRS BELLINGER WOULD LIKE THEM REPLACE THANK YOU SIR AND GOD BLESS	7/6/2006 Medium	Adan Duran Ruben Ronquillo Glass\Window Repairs		Riverside ES
13612	Work In Progress I got a call from Mr. Sanchez and he indicates that they had several roof leaks during yesterday's rain. He says the leaks occurred in a lot of the same areas where repairs were made, along the hallway and one whole wing has classroom leaks. He is concerned that the painting of the hallways being done by the contractor will get ruined. Make arrangements to work on this again.  Margret, Please generate a work order for this and contact Adan need a site plan of the school indicating where the leaks are located. Also ask him if he already entered the work order to repair windows on classroom doors.	7/7/2006 Medium	Alfredo Holguin Adan Duran Roof		Riverside ES
13556	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Raul Romero Custodial		Riverside ES
13431	Work In Progress Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Riverside ES
13432	Work In Progress Monthly - San Miguel ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		San Miguel ES
13383	Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Vega Fire Extinguishers		San Miguel ES
13401	Work In Progress Monthly - San Miguel ES Roof Inpsection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Vega Roof		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13557	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Cervando Padilla Custodial		San Miguel ES
13504	Work In Progress Yearly - San Miguel ES Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Vega Fire Protection		San Miguel ES
13467	Work In Progress Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Vega General Maintenance		San Miguel ES
13479	Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Vega General Maintenance		San Miguel ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13621	<p>Work In Progress</p> <p>As we continued walking down the hall the following rooms had the same damage:</p> <p>Rm. 7---Lounge Rm. 9---Nurses Office Rm. 10—Administrative Intern Office Rm. 15—Office Rm. 20---Kindergarten Classroom</p> <p>We walked throughout the hallway checking the classroom and saw no sign of forced entry. I called Ms. Muela and indicated what we had discovered and she asked me to call the sheriff's department and make a police report. I spoke to Deputy Rosemary Zamora, case #20069-06254 and indicated that nothing seemed to be missing but that two doors where damaged and would need to be replaced the work room door Rm. 14, was forced open and broke from the lock, also our supply room door was broken but nothing seemed to be missing.</p> <p>Ms. Muela called the administration offices and spoke to Cindy Nava and informed her about the situation, Ms. Nava indicated she would inform Mr. Richard Chavez.</p> <p>Today July 6, 2006 two of our SPED teachers came by to pick up some of their belongings from classroom 33 and noticed that it had been broken into. The following items were missing:</p> <p>2 alpha smarts 5 cd players 8 mini recorders 1 case of hot chocolate 5 filing cabinets where forced open damaging all of them.</p> <p>They estimated all the items to be worth about\$1000.00. Deputy Zamora and I had previously estimated about \$800.00 worth of damage, but this was before today. I have called her and left a message to let her know about the items that where stolen. We have about three pairs of scissors that where found thrown in the hallway that where used as tools to do most of the damage. Mine where taken from my desk drawer.</p>	<p>7/7/2006</p> <p>Medium</p>	<p>Barbara Cardenas Manny Lozoya Key and Lock</p>		San Miguel ES
13527	<p>Work In Progress</p> <p>Yearly - San Miguel ES Exit Sign Test: Annual - Refer to PM schedule details.</p>	<p>7/2/2006</p> <p>Medium</p>	<p>Alfredo Holguin Danny Vega Fire Protection</p>		San Miguel ES
13952	<p>Work In Progress</p> <p>GARBAGE DISPOSAL HAS A LEAK.</p> <p>EVA MIRANDA SNP MGR 233-2860</p>	<p>7/21/2006</p> <p>Medium</p>	<p>Jacqueline Aguilar Danny Orozco Food Services</p>	Cafeteria	San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
14074	Work In Progress TOP OVEN IS NOT WORKING AT ALL. ONLY HAVE ONE OVEN  EVA MIRANDA - SNP MGR 233-2860	7/26/2006  Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	San Miguel ES
13658	Work In Progress door needs replacement rm14	7/10/2006  Medium	Danny Vega Danny Miranda Doors and Hardware		San Miguel ES
13659	Work In Progress door needs replacement rm18 storage	7/10/2006  Medium	Danny Vega Danny Miranda Doors and Hardware		San Miguel ES
13866	Work In Progress MILK COOLER NOT COOLING.  EVA MIRANDA - SNP MGR 233-2860	7/19/2006  Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	San Miguel ES
13823	Work In Progress need to re-route electrical power from floor to new power poles(safety hazard) in computer lab rm 17	7/17/2006  Medium	Danny Vega Enrique Sotelo Electrical		San Miguel ES
13825	Work In Progress commode leaks thru tank gasket rm 32 .please (repair asap)	7/17/2006  Medium	Fred Appelzoller Lorenzo Solis Plumbing		San Miguel ES
13919	Work In Progress rm33 needs door handle plate installed/this rm is vandalized very often.	7/20/2006  Medium	Danny Vega Manny Lozoya Key and Lock		San Miguel ES
13898	Work In Progress need two 115v a/c pumps-two 230v pumps if available	7/20/2006  Medium	Danny Vega Ruben Ronquillo General Maintenance		San Miguel ES
13901	Work In Progress need 230v -2 speed-s.f 1.25 a/c motor for front office-computer rm-vice principal office a/c unit - asap	7/20/2006  Medium	Danny Vega Ruben Ronquillo General Maintenance		San Miguel ES
13902	Work In Progress Computer lab needs electrical wiring outlets need to be removed from floor and re routed thru ceiling. Safety Hazard for students.	7/20/2006  Medium	Barbara Cardenas Enrique Sotelo Electrical	Classroom	San Miguel ES 17
14199	Work In Progress Ana O'Neill--Rm. 50  Needs a filing cabinet lock checked it will not lock.	7/28/2006  Medium	Barbara Cardenas Manny Lozoya Key and Lock		San Miguel ES
14209	Work In Progress john deere mower needs belt replaced.	7/28/2006  Medium	Danny Vega Angel Gonzales Vehicle Maintenance		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
14282	Work In Progress water leak in rm 32 a/c unit/please ck( before i add tar) 8/1 Route to Danny Vega - Please add tar and check unit and squirrel cage. If a/c pump is over rated (cfms) to much water is being dist., but tar should work.	7/31/2006 Medium	Danny Vega Danny Vega General Maintenance		San Miguel ES
14283	Work In Progress need status on wk od # 13919	7/31/2006 Medium	Danny Vega Manny Lozoya Key and Lock		San Miguel ES
14285	Work In Progress need status on wk od #13825	7/31/2006 Medium	Danny Vega Joe Ontiveros Plumbing		San Miguel ES
13907	Work In Progress NEED TO LIGH SHOWER SCRUB, SEAL & WAX NEW PORTABLE BEFORE PLACING ITEMS INSIDE.	7/20/2006 Medium	Aida Salcedo Pablo Diaz Custodial	Portables	Santa Teresa ES
13849	Work In Progress 3, 55 GAL. DRUMS FOR TRASH CANS	7/18/2006 Medium	Pablo Diaz Sal Acuna Custodial		Santa Teresa ES
14099	Work In Progress NEED TWO FIRE EXTINGUISHERS FOR NEW PORTABLE.	7/26/2006 Medium	Gerardo Marquez Ruben Ronquillo Fire Extinguishers		Santa Teresa ES
14100	Work In Progress MANNY, NEED FOR YOU TO KEY LOCKS TO NEW PORTABLE. PORTABLE HAS ALREADY BEEN DELIVERED. THANKS.	7/26/2006 Medium	Gerardo Marquez Manny Lozoya Key and Lock		Santa Teresa ES
14101	Work In Progress MANNY, STILL NEED REPLACEMENT KEY FOR RM. 301, RITA HAS BEEN ASKING ABOUT IT.	7/26/2006 Medium	Gerardo Marquez Manny Lozoya Key and Lock		Santa Teresa ES
13958	Work In Progress JOSE, NEED FOR YOU TO CHECK OUT UNITS IN ADMIN. OFFICE, AND ALSO RM. 102. UNITS ARE NOT COOLING. IM HAVING TO RESET THEM FREQUENTLY.	7/21/2006 Medium	Gerardo Marquez Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa ES
13528	Work In Progress Yearly - Santa Teresa ES Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Gerardo Marquez Fire Protection		Santa Teresa ES
13480	Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Gerardo Marquez General Maintenance		Santa Teresa ES
13468	Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Gerardo Marquez General Maintenance		Santa Teresa ES
13505	Work In Progress Yearly - Santa Teresa ES Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Gerardo Marquez Fire Protection		Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13559	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Pablo Diaz Custodial		Santa Teresa ES
13433	Work In Progress Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Santa Teresa ES
13368	Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Gerardo Marquez Fire Extinguishers		Santa Teresa ES
13404	Work In Progress Monthly - Santa Teresa ES Roof Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Gerardo Marquez Roof		Santa Teresa ES
13434	Work In Progress Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Santa Teresa HS
13402	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Arturo Nunez Roof		Santa Teresa HS
13384	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
13560	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Luis Murillo Custodial		Santa Teresa HS
13506	Work In Progress Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Arturo Nunez Fire Protection		Santa Teresa HS
13529	Work In Progress Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Arturo Nunez Fire Protection		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13536	Work In Progress NEED TO HAVE ROOF ON SECOND PHASE OF CONSTRUCTION CHECKED. BAND ROOM OFFICE HAS A PRETTY GOOD SIZE ROOF LEAK, ABOVE TEACHERS DESK. MIGHT STILL BE UNDER WARRANTY, COULD YOU PLEASE FORWARD TO DAVID BOYD. THANK YOU.	7/5/2006 Medium	Arturo Nunez David Boyd Construction		Santa Teresa HS Roof
14081	Work In Progress NEED TO HAVE WATER LEAK ON DRIVEWAY TO REAR PARKING LOT CHECKED. WATER IS SEEPING OUT INTO DRIVEWAY.	7/26/2006 Medium	Arturo Nunez David Villalobos Plumbing		Santa Teresa HS
14093	Work In Progress NEED TO HAVE LOCKSMITH CHECK DOOR ON VALT, HAVING TROUBLE OPENING, EMERGENCY, NEED TO GET IN TO PROCEED WITH DAILY BUSINESS THAN YOU.	7/26/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
14055	Work In Progress SCRUBING MACHINE WILL NOT TURN ON SERVICE MASTER SERIAL* 1000289	7/25/2006 Medium	Luis Murillo Jimmy Carbajal Custodial		Santa Teresa HS
14033	Work In Progress NEED ELECTRICAL ON SCIENCE TABLES IN ROOM #18 DISCONNECTED TO BE REPLACED, BY NEW TABLES. WILL NEED TO HOOK UP NEW SCIENCE TABLES WHEN INSTALLED.	7/25/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
14162	Work In Progress NEED TO PICK UP FURNITURE (SCIENCE TABLES) FROM STH AND DELIVER TO DESERT PRIDE.	7/27/2006 Medium	Aida Salcedo Jimmy Carbajal Custodial		Santa Teresa HS
13719	Work In Progress Lobby marquee not lihgtng up.	7/13/2006 Medium	Carlos Castillo Carlos Castillo Electrical	Hallway/Corridor	Santa Teresa HS
13834	Work In Progress DAVE, JUST LETTING YOU KNOW THAT B.RR AT ROTC. BUILDING IS READY FOR TOILET INSTALATION.	7/17/2006 Medium	Gerardo Marquez David Villalobos Plumbing		Santa Teresa HS
13884	Work In Progress NEED FOUR (4) WINDOWS REPLACED 2EA. 36 7/8 BY 29 3/8 , 2 EA.36 3/8 BY 21 3/8. VANDALISM.	7/19/2006 Medium	Arturo Nunez Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS
13759	Work In Progress NEED A WINDOW GLASS REPLACED. NOTIFIED BY GALLEGOS, ROOM # 8 , 31" X 36 1/8.	7/14/2006 Medium	Arturo Nunez Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS
13803	Work In Progress NEED TO HAVE WINDOW AT ROOM #8 REPLACED, BROKEN DURING THE WEEKEND, MEASUREMENTS ARE 36 1/8" BY 31". WOULD LIKE TO SEE IF IT CAN BE REPLACED WITH PLEXIGLASS AS PER MR. GALLEGOS. ( VANDALISM)	7/17/2006 Medium	Arturo Nunez Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13804	Work In Progress NEED WINDOW AT ROOM. #14 REPLACED MEASUREMENTS ARE 36 1/4" BY 25 3/8". SCIENCE WING. (VANDALISM)	7/17/2006 Medium	Arturo Nunez Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS
13806	Work In Progress School Grounds. Mrs. williams would like 6 dump trucks of landscape rock and spreaded in some areas of the school. She likes the rock that was used at the G.A.C offices.	7/17/2006 Medium	Jaime Mijarez Guadalupe Ontiveros Grounds		Santa Teresa MS
13809	Work In Progress School bldgs. Please order me 10 ea. toilet seats as soon as you can. David I need to replace some as per Mrs. williams, thank you.	7/17/2006 Medium	Jaime Mijarez David Villalobos Plumbing		Santa Teresa MS
13811	Work In Progress S.bldg attendance office. Please include with all the other sliding door openings that Mrs. williams wants covered with sheetrock. W/O # 12514	7/17/2006 Medium	Jaime Mijarez Danny Miranda Doors and Hardware		Santa Teresa MS
13662	Work In Progress JIMMY , I AM GOING TO NEED THE HEAVY DUTY DOLLEY ON 7/13/06 TO MOVE SOME FIRE PROOF CABNETS IN THE NORTH OFFICE.THANK YOU.	7/11/2006 Medium	Ismael Rodriguez Jimmy Carbajal Custodial	Office	Santa Teresa MS
13667	Work In Progress Library. Ms. Mays has requested to replace all for wooden doors going into library. They are old and in bad shape, please check with Jaime and Ms. Mays first. Thank you.	7/11/2006 Medium	Jaime Mijarez Danny Miranda Doors and Hardware		Santa Teresa MS
13730	Work In Progress Mouding around walls needs to be replaced  snp manager - paula Sanchez 589-9836	7/13/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Santa Teresa MS
13732	Work In Progress Fix wall panel under dishwasher  snp manager - paula sanchez - 589-9836	7/13/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Santa Teresa MS
13733	Work In Progress Finish replacing missing tiles  Paula Sanchez - SNP Manager 589-9836	7/13/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Santa Teresa MS
13734	Work In Progress Blodgett ovens - 2 of them are not working  Paula Sanchez - SNP Manager 589-9836	7/13/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Santa Teresa MS
13735	Work In Progress Steamtables some compartments are not warming up  Paula Sanchez - SNP Manager 589-9836	7/13/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13531	Work In Progress Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Jaime Mijarez Fire Protection		Santa Teresa MS
13641	Work In Progress CALI ,I DONT IF JAIME TOLD YOU THAT I NEEDED SOME LIGHT BULBS FOR THE NORTH BUILDING I RAN OUT.SO CAN YOU GET ME SOME A.S.A.P.THANK YOU.	7/10/2006 Medium	Ismael Rodriguez Carlos Castillo Electrical	Custodial	Santa Teresa MS
13575	Work In Progress need to paint new door girl's upper level	7/6/2006 Medium	Danny Miranda Jaime Mijarez Painting		Santa Teresa MS
13576	Work In Progress need new core lock girl's r.r. upper level	7/6/2006 Medium	Danny Miranda Manny Lozoya Key and Lock		Santa Teresa MS
13507	Work In Progress Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Jaime Mijarez Fire Protection		Santa Teresa MS
13472	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Jaime Mijarez General Maintenance		Santa Teresa MS
13482	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Jaime Mijarez General Maintenance		Santa Teresa MS
13561	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Ismael Rodriguez Custodial		Santa Teresa MS
13385	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Jaime Mijarez Fire Extinguishers		Santa Teresa MS
13403	Work In Progress Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Jaime Mijarez Roof		Santa Teresa MS
13435	Work In Progress Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Santa Teresa MS
14216	Work In Progress Door to counselor's office does not lock.	7/28/2006 Medium	Laura Parra Manny Lozoya Key and Lock	Office	Santa Teresa MS Counselors Office
14217	Work In Progress Need to key for Social Worker's Office	7/28/2006 Medium	Laura Parra Manny Lozoya Key and Lock	Office	Santa Teresa MS Social Worker

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
14226	Work In Progress a/c does not work.  Classroom key opens the deadbolt but not the handle	7/28/2006  Medium	Laura Parra Manny Lozoya  General Maintenance	Portables	Santa Teresa MS p 1-b
14194	Work In Progress Rain caused erosion and big water puddles on school campus. Can we have them covered up again and maybe before school starts, if it is possible. Thank you.	7/28/2006  Medium	Jaime Mijarez Robert Sanchez  Grounds		Santa Teresa MS
14262	Work In Progress NEED THE FOLLOWING KEYS MADE: TA8, TA2	7/31/2006  Medium	Irene Trujillo Manny Lozoya  Key and Lock		Sunland Park ES
14263	Work In Progress NEED THE FOLLOWING KEYS MADE: TA8, TA2	7/31/2006  Medium	Irene Trujillo Manny Lozoya  Key and Lock		Sunland Park ES
13436	Work In Progress Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006  Medium	Alfredo Holguin Danny Orozco  Kitchen Hood		Sunland Park ES
13405	Work In Progress Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.	7/2/2006  Medium	Alfredo Holguin Manuel Prospero  Roof		Sunland Park ES
13562	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006  Medium	Aida Salcedo Larry Flores  Custodial		Sunland Park ES
13609	Work In Progress Dr. Garcia, new principal for Sunland Park Elementary just now called to request his keys for that site. I spoke to Margret Villalobos this morning regarding this and she asked me to request this by e-mail. Ms. Villalobos also stated that Manny Lozoya is on vacation and won't be back until the 17th of July.	7/7/2006  Medium	Norma Alvarado Manny Lozoya  Key and Lock		Sunland Park ES
13700	Work In Progress 7/12/06. WE NEED TO COVER TOP MONTAIN AFTER RAINS STORM. AROUND SCHOOL. THES WORK ORDER IS FOR LUPE ONTIVEROS.	7/12/2006  Medium	Manuel Prospero Guadalupe Ontiveros  Grounds		Sunland Park ES
13946	Work In Progress DRAINS WERE INSTALLED BY 1ST GR. WIND AND KINDER WING BUT WERE LEFT UNCOVERED. ALSO, BY EARLY CHILDHOOD CLASSES A SQUARE OPENING WAS LEFT WITHOUT A COVER.	7/21/2006  Safety	Irene Trujillo David Boyd  Construction		Sunland Park ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13947	Work In Progress THE AREA BEHIND THE FIRST GRADE AND KINDER WINGS WERE LEFT UNEVEN. PLEASE HAVE THESE AREAS AND HOLES FILLED IN WITH DIRT. ALSO, THESE AREAS WERE LEFT WITH CONCRETE LITTERED THROUGHOUT.	7/21/2006 Medium	Irene Trujillo Guadalupe Ontiveros Grounds		Sunland Park ES
13949	Work In Progress THE AREA BEHIND THE SCHOOL BUILDING OUTSIDE THE ROCK WALL WAS LEFT LITTERED WITH CONCRETE AND PILES OF SAND. THIS ALSO NEED TO BE CLEANED.	7/21/2006 Safety	Irene Trujillo David Boyd Construction		Sunland Park ES
14137	Work In Progress REQUESTING NEW LOCK,AND MASTER KEYS FOR PORTABLE S.R.E	7/26/2006 Medium	Paul Quinones Manny Lozoya Key and Lock		Sunrise ES
13812	Work In Progress Cabinet in room 104 needs the latch repaired.	7/17/2006 Medium	Joanne Munoz Paul Quinones General Maintenance		Sunrise ES
13817	Work In Progress Soap Dispenser push button in student bathroom is broken please fix	7/17/2006 Medium	Joanne Munoz Jesus Urquidi Custodial		Sunrise ES
13754	Work In Progress NEED TO SHOWER SCRUB KITCHEN AREA ON 7/17/06.	7/14/2006 Medium	Aida Salcedo Jesus Urquidi Custodial		Sunrise ES
13725	Work In Progress Need key for room 206	7/13/2006 Medium	Joanne Munoz Manny Lozoya Key and Lock	Classroom	Sunrise ES
13726	Work In Progress I need a new master key for Maria Espinoza her key keeps getting stuck in the doors. Thanks	7/13/2006 Medium	Joanne Munoz Manny Lozoya Key and Lock		Sunrise ES
13727	Work In Progress Jessie Urquidi, head custodian needs a new master key it is getting stuck in all the doors.	7/13/2006 Medium	Joanne Munoz Manny Lozoya Key and Lock		Sunrise ES
13728	Work In Progress Adrian Flores, cutsodian, needs a new master key it is getting stuck in doors.	7/13/2006 Medium	Joanne Munoz Manny Lozoya Key and Lock		Sunrise ES
13729	Work In Progress I need a key for the El Sol work room office and closet.	7/13/2006 Medium	Joanne Munoz Manny Lozoya Key and Lock		Sunrise ES
13699	Work In Progress NEED TO LIGH SHOWER SCRUB, SEAL & WAX NEW PORTABLE BEFORE PLACING ITEMS INSIDE.	7/12/2006 Medium	Aida Salcedo Jesus Urquidi Custodial	Portables	Sunrise ES
13532	Work In Progress Yearly - Sunrise ES Exit Sign Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Paul Quinones Fire Protection		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13475	Work In Progress Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Paul Quinones General Maintenance		Sunrise ES
13563	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Jesus Urquidi Custodial		Sunrise ES
13484	Work In Progress Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Paul Quinones General Maintenance		Sunrise ES
13509	Work In Progress Yearly - Sunrise ES Emer. Light Test: Annual - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Paul Quinones Fire Protection		Sunrise ES
13407	Work In Progress Monthly - Sunrise ES Roof Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Paul Quinones Roof		Sunrise ES
13369	Work In Progress Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Paul Quinones Fire Extinguishers		Sunrise ES
13437	Work In Progress Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Sunrise ES
13438	Work In Progress Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.	7/2/2006 Medium	Alfredo Holguin Danny Orozco Kitchen Hood		Vado ES
13564	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JULY 21,2006	7/5/2006 Medium	Aida Salcedo Armando Diaz Custodial		Vado ES
13535	Work In Progress need to remove sand from walls see lupe ontveros	7/5/2006 Medium	Danny Miranda Guadalupe Ontiveros Grounds		Vado ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13717	Work In Progress 7/12/06 (1)put up tray's on wall nurse office (1.5)open doors &start ups at la mesa (5)13645 (.5)back to vado	7/13/2006 7/13/2006 Medium	Danny Miranda Danny Miranda General Maintenance		Vado ES
	7/12 -3				
14043	Work In Progress desk dolly	7/25/2006 Medium	Armando Diaz Sal Acuna Custodial Equipment Repair		Vado ES
14046	Work In Progress plastic brush for shower scrubber	7/25/2006 Medium	Armando Diaz Jimmy Carbajal Custodial		Vado ES
14018	Work In Progress david boyd need to replace facuett boys restroom not working	7/24/2006 Medium	Danny Miranda David Boyd Construction		Vado ES
14207	Work In Progress DOOR IS CRACKED OR SPLIT	7/28/2006 Medium	Danny Miranda David Boyd General Maintenance		Vado ES