

**366 - Work Orders In Progress (Fiscal Year)**

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Alma Del Valle Daycare</b>									
24560					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:52 AM				
Apodaca, Romauldo		Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.							
Alfredo Holguin									
24561					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:52 AM				
Apodaca, Romauldo		Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.							
Alfredo Holguin									
24559					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:51 AM				
Apodaca, Romauldo		Monthly - Alma Del Valle Roof Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24556					7/1/2007	7/7/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:50 AM				
Apodaca, Romauldo		Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24554					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:49 AM				
Apodaca, Romauldo		Yearly - Alma Del Valle Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
25187					7/30/2007		2		\$0.00
Medium	Work In Progress				7/30/2007 8:13:06 AM				
Saucedo, Luis		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
24600					7/6/2007		26		\$0.00
Medium	Work In Progress				7/6/2007 10:05:02 AM				
Apodaca, Romauldo		THE FENCE WAS CUT AT ALMA DE VALLE DUE TO A BREAK IN OVER THE WEEKEND				As per Mike. Re-routed to Roma to see if he can stitch or mend. If not Roma is to return to Mike for repair through Academy Fence.MG			
Luis Saucedo									
<b>Count: 7 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>26</b>		<b>Total for Alma Del Valle Daycare</b>	<b>0</b>		<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Anthony ES

25233					7/31/2007		1		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium Work In Progress

7/31/2007 7:58:33 AM

Vega, David

QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)

Jesus Estrada

24803		Cafeteria			7/16/2007		16		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium Work In Progress

7/16/2007 1:09:23 PM

Orozco, Danny

Reach - In Freezer - The breaking is going out. Will not stay on.

Becky S. SNP Mgr - 882-3507

Jacqueline Aguilar

24804		Cafeteria			7/16/2007		16		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium Work In Progress

7/16/2007 1:10:59 PM

Orozco, Danny

Reach - In Refrig. / Temp. is high this morning.

Becky S. - SNP MGR 882-3507

Jacqueline Aguilar

25193	Main Building	Restroom (Girls)			7/30/2007		2		\$0.00
-------	---------------	------------------	--	--	-----------	--	---	--	--------

Medium Work In Progress

7/30/2007 8:26:35 AM

Appelzoller, Fred

Need to order a new w all toilet in grils bathroom

Hector Villalobos

24810	Main Building	Hallw ay/Corridor			7/16/2007		16		\$0.00
-------	---------------	-------------------	--	--	-----------	--	----	--	--------

Medium Work In Progress

7/16/2007 3:26:13 PM

Villalobos, Hector

need to remove lockers from w all mild blg hallw ay

Hector Villalobos

24684	Drug Free Bldg.	Office			7/11/2007		21		\$0.00
-------	-----------------	--------	--	--	-----------	--	----	--	--------

Medium Work In Progress

7/11/2007 7:36:48 AM

Lozoya, Manny

Drug free need to replace door handle on two doors and it a off master

Hector Villalobos

24586	Dona Ana Branch	Cafeteria			7/2/2007		30		\$0.00
-------	-----------------	-----------	--	--	----------	--	----	--	--------

Medium Work In Progress

7/2/2007 9:40:03 AM

Orozco, Danny

REACH-IN REFRIGERATOR IS NOT WORKING-BECKY CHECKED BREAKER, BREAKER WAS IN THE OFF POSITION, WHEN SHE TRIED TO RESET BREAKER IT STILL WOULDN'T RESET. (CALLED DANNY ON 7/2/07 LEFT MESSAGE)

BECKY SAENZ - SNP MANAGER 882-3507

Alma Terrell

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
24442					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:02 AM				
Orozco, Danny		Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
24365					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:48 AM				
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24366					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:48 AM				
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24592					7/2/2007		30		\$0.00
Medium	Work In Progress				7/2/2007 2:21:51 PM				
Ambriz, Jose		Nursing Dept- Please check A/C. Very hot in office.							
Rosa Hidalgo									
<b>Count: 11 Work Orders</b>		<b>Avg. Age of WO's 20</b>		<b>Total for Anthony ES</b>		<b>0</b>	<b>0</b>	<b>\$0.00</b>	

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Berino ES</b>									
24624					7/9/2007		23		\$0.00
Medium	Work In Progress				7/9/2007 11:01:05 AM				
Lozoya, Manny		NEED A KEY MADE FOR PARENT ROOM MRS. DOMINGUEZ NEEDS A KEY							
Ramiro Holguin									
25015					7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 8:45:09 AM				
Ronquillo, Ruben		TINT FRONT OFFICE WINDOW!							
Ruben Ronquillo									
24367					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:48 AM				
Villalobos, David		Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24368					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:48 AM				
Villalobos, David		Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24369					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:49 AM				
Villalobos, David		Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24370					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:49 AM				
Villalobos, David		Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24437					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:00 AM				
Orozco, Danny		Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Alfredo Holguin									
24443					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:03 AM				
Orozco, Danny		Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
24544					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:46 AM				
Holguin, Ramiro		Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Alfredo Holguin									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Berino ES</b>									
24542					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:45 AM				
Holguin, Ramiro		Monthly - Berino ES Roof Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24543					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:45 AM				
Holguin, Ramiro		Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Alfredo Holguin									
24540					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:44 AM				
Holguin, Ramiro		Yearly - Berino ES Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
24541					7/1/2007	7/7/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:44 AM				
Holguin, Ramiro		Monthly - Berino ES Monthly FE Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24539					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:44 AM				
Holguin, Ramiro		Yearly - Berino ES Emer. Light Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
25029					7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 1:42:26 PM				
Ronquillo, Ruben		Broken window (Case# 07-06680)							
Jimmy Cortez									
25234					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 7:59:42 AM				
Cortez, Jimmy		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
<b>Count: 16 Work Orders</b>			<b>Avg. Age of WO's 26</b>		<b>Total for Berino ES</b>			<b>0</b>	<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral ES</b>									
24987					7/23/2007		9		\$0.00
Medium	Work In Progress			7/23/2007 11:07:47 AM					
Munoz, Michael	7/23/07. as per mr. cardona he is requesting that the carpet in the office be replaced as soon as possible.								
Joe Ramirez									
24935		Classroom			7/20/2007		12		\$0.00
Medium	Work In Progress	103		7/20/2007 8:00:42 AM					
Lozoya, Manny	Teacher lost her keys, will pay. needs key to be done. See Jennifer								
Jennifer Corral									
24960					7/20/2007		12		\$0.00
Medium	Work In Progress			7/20/2007 11:30:34 AM					
Ramirez, Joe	Trash out by fenceline (Lisa street) needs to be picked up it is the west corner of the campus								
24517					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress			7/1/2007 12:16:35 AM					
Ramirez, Joe	Yearly - Chaparral ES Exit Sign Test: Annual - Refer to PM schedule details.								
Alfredo Holguin									
25237					7/31/2007		1		\$0.00
Medium	Work In Progress			7/31/2007 8:00:20 AM					
Ramirez, Daniel	QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)								
Jesus Estrada									
24647		Custodial			7/9/2007		23		\$0.00
Medium	Work In Progress			7/9/2007 4:00:58 PM					
Carbajal, Jimmy	The furniture out in the open (Chaparral Elem.) goes to La Mesa Elem. for storage. (Route to Jimmy Carbajal)								
Jesus Estrada									
25071		Office			7/25/2007		7		\$0.00
Medium	Work In Progress	OFFICE		7/25/2007 11:28:57 AM					
Lozoya, Manny	REQUESTING 2 MASTER KEYS FOR THE PORTABLES AND 1 MASTER KEY FOR THE TWO FRONT GATES. WILL BE USED FOR OFF TRACK PRE-KINDER DIRECTOR								
Jennifer Corral									
24936		Classroom			7/20/2007		12		\$0.00
Medium	Work In Progress	510		7/20/2007 8:03:29 AM					
Lozoya, Manny	Need key for classroom. Music teacher that was there lost key and needs to be replaced.								
Jennifer Corral									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
24938		Classroom			7/20/2007		12		\$0.00
Medium	Work In Progress	502			7/20/2007 8:05:12 AM				
Lozoya, Manny		new counselor in room, has key to open office but needs locks replaced so she can open outside doors, they require master keys and Principal does not want her to have a master key.							
Jennifer Corral									
24940		Computer Lab			7/20/2007		12		\$0.00
Medium	Work In Progress	310			7/20/2007 8:06:56 AM				
Lozoya, Manny		computer teacher needs key for her desk. Cannot open her desk. Wants to know if it's able to be fixed. See Olivia							
Jennifer Corral									
24514					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:34 AM				
Ramirez, Joe		Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Alfredo Holguin									
24515					7/1/2007	7/7/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:34 AM				
Ramirez, Joe		Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24516					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:34 AM				
Ramirez, Joe		Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Alfredo Holguin									
24513					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:33 AM				
Ramirez, Joe		Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24444					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:06 AM				
Orozco, Danny		Monthly - Chapparral ES Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
24376					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:50 AM				
Villalobos, David		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24377					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:50 AM				
Villalobos, David		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

Count: 17 Work Orders      Avg. Age of WO's 20      Total for Chaparral ES      0      \$0.00



# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
24436					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:00 AM				
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24434					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:59 AM				
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24435					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:59 AM				
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24884					7/18/2007		14		\$0.00
Medium	Work In Progress				7/18/2007 3:38:37 PM				
Lozoya, Manny		PLEASE ISSUE A "B" KEY TO SERGIO SANDOVAL. (HEAD CUSTODIAN)							
Jesus Estrada									
25084		Cafeteria			7/25/2007		7		\$0.00
Medium	Work In Progress	CHAPARRAL			7/25/2007 3:56:01 PM				
Lozoya, Manny		AS PER MR. GIOVAS-NEEDS A TEMP LOCK ON THE CAFETERIA DOOR BEFORE MONDAY JULY 30TH. (DELIVERY OF FOOD WILL COME IN ON MONDAY & NEEDS TO HAVE A LOCK.)							
Mary Garcia									
24958					7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 10:31:07 AM				
Ontiveros, Guadalupe		NEED MATERIAL FOR BUS TURN AROUND FOR THE AMOUNT OF \$25,000.							
Guadalupe Ontiveros									
<b>Count: 6 Work Orders</b>		<b>Avg. Age of WO's 21</b>		<b>Total for Chaparral HS</b>		<b>0</b>		<b>\$0.00</b>	

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral MS</b>									
24955					7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 9:37:06 AM				
Lozoya, Manny		locker room door need fix not lock							
Juan Vargas									
24952					7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 8:51:48 AM				
Vargas, Juan		teacher longe door need fix							
Juan Vargas									
25238					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:00:58 AM				
Gonzalez, Robert		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
24707		Cafeteria			7/11/2007		21		\$0.00
Medium	Work In Progress				7/11/2007 2:27:07 PM				
Orozco, Danny		Walk-In Freezer was at 19 degrees (6:30 a.m.) and now it is at 30 degrees (9:30 a.m.) left message on Danny's cell phone							
		Paula Sanchez - SNP Manager 824-4376							
Alma Terrell									
25192		Cafeteria			7/30/2007		2		\$0.00
Medium	Work In Progress				7/30/2007 8:25:45 AM				
Orozco, Danny		Oven is not working properly, the oven only heats up for a couple of minutes, then it stops. Called Danny O. on 7/30/07 left message.							
		Sandra Diaz - SNP Manager 824-4376							
Alma Terrell									
24445					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:06 AM				
Orozco, Danny		Monthly - Chapparal MS Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
24438					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:00 AM				
Orozco, Danny		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Alfredo Holguin									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral MS</b>									
24411					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:56 AM				
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24412					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:56 AM				
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24413					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:56 AM				
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24518					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:35 AM				
Ramirez, Joe		Yearly - Chaparral MS Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
24970	Main Building	Gym			7/20/2007		12		\$0.00
High	Work In Progress				7/20/2007 2:55:21 PM				
Gonzalez, Robert		Cut out w wrinkles on floor and varnish those spots							
24959					7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 11:27:13 AM				
Vargas, Juan		Trash out by the fenceline needs to be picked up(Lisa street) corner (w est)							
24792	Main Building				7/16/2007		16		\$0.00
Medium	Work In Progress				7/16/2007 9:59:44 AM				
Villalobos, David		REPLACE WATER HEATERS							
Ruben Ronquillo									
<b>Count: 14 Work Orders</b>		<b>Avg. Age of WO's 20</b>		<b>Total for Chaparral MS</b>		<b>0</b>		<b>\$0.00</b>	

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Pride</b>									
24353					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:44 AM				
Acosta, David		Yearly - Desert Pride Emer. Light Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
24351					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:43 AM				
Acosta, David		Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24352					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:43 AM				
Acosta, David		Yearly - Desert Pride Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
25066		Classroom			7/25/2007		7		\$0.00
Medium	Work In Progress	5,6,8,11.			7/25/2007 10:43:54 AM				
Castillo, Carlos		rooms 5,6,8,11 some of the light fixtures ballast need replacing.							
David Acosta									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>25</b>	<b>Total for Desert Pride</b>			<b>0</b>	<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Trail Intermediate</b>									
24362					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:47 AM				
Villalobos, David		Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24363					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:47 AM				
Villalobos, David		Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
25133		Classroom			7/26/2007		6		\$0.00
Medium	Work In Progress				7/26/2007 3:58:52 PM				
Lozoya, Manny		Need keys made for (Portable #408, 409) and (classrooms #118, 212). Attn: Blanca (Front Office).							
Johnny Acuna									
24662					7/10/2007		22		\$0.00
Medium	Work In Progress				7/10/2007 12:42:45 PM				
Ontiveros, Joe		Need a 1" threaded female cap for pvc pipe in the playground area.							
Johnny Acuna									
25239					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:01:33 AM				
Torres, Marisela		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
24913		Classroom			7/19/2007		13		\$0.00
Medium	Work In Progress				7/19/2007 1:16:31 PM				
Lozoya, Manny		3 candados para gabinetes cuarto 113.							
Marisela Torres									
24900		Custodial			7/19/2007		13		\$0.00
Medium	Work In Progress				7/19/2007 9:01:32 AM				
Lozoya, Manny		Urgente. cambiar las chapas del cuarto 408. nueva chapa para cuarto 201. cambiar chapa de storage. Gracias							
Marisela Torres									
25017		Classroom			7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 9:05:54 AM				
Lozoya, Manny		una llave para el cuarto 408 la que tiene el maestro no habre .gracias.							
Marisela Torres									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Desert Trail Intermediate

24805	Main Building	Custodial			7/16/2007		16		\$0.00
Medium	Work In Progress				7/16/2007 2:34:30 PM				
Lozoya, Manny		Por favor. llaves para un escritorio . llaves para un gabinete.cuarto #113. Gracias.							
Marisela Torres									
24961		Custodial			7/20/2007		12		\$0.00
High	Work In Progress				7/20/2007 11:34:17 AM				
Acuna, Johnny		Dirt piled up in front of front office entrance curb needs to be removed							
24491					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:25 AM				
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.							
Alfredo Holguin									
24492					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:25 AM				
Acuna, Johnny		Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.							
Alfredo Holguin									
24493					7/1/2007	7/7/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:26 AM				
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.							
Alfredo Holguin									
24489					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:24 AM				
Acuna, Johnny		Yearly - Desert Trail Emer. Light Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
24490					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:24 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.							
Alfredo Holguin									
24488					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:23 AM				
Acuna, Johnny		Yearly - Desert Trail Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
24439					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:01 AM				
Orozco, Danny		Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.							
Alfredo Holguin									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
24446					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:07 AM				
Orozco, Danny		Monthly - Desert Trail Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
24364					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:48 AM				
Villalobos, David		Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
<b>Count: 19 Work Orders</b>		<b>Avg. Age of WO's 23</b>		<b>Total for Desert Trail Intermediate</b>				<b>0</b>	<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Desert View ES</b>							
24378					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24379					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24380					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24447					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:07 AM				
Orozco, Danny		Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
24533					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:41 AM				
Aguilar, Patricio		Monthly - Desert View ES Roof Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24534					7/1/2007	7/7/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:42 AM				
Aguilar, Patricio		Monthly - Desert View ES Monthly FE Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24535					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:42 AM				
Aguilar, Patricio		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Alfredo Holguin									
24536					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:42 AM				
Aguilar, Patricio		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Alfredo Holguin									
24537					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:43 AM				
Aguilar, Patricio		Yearly - Desert View ES Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									



# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert View ES</b>									
24538					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:43 AM				
Aguilar, Patricio		Yearly - Desert View ES Emer. Light Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
25062					7/25/2007		7		\$0.00
Medium	Work In Progress				7/25/2007 10:29:29 AM				
Holguin, Alfredo		Need a price quote for Pigeon Control.							
Alfredo Holguin									
25240					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:04:00 AM				
		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
25272					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 3:33:29 PM				
Ronquillo, Ruben		pat aguilar need w indow s sun city glass 1 - 15"x17" tow er right side 2 - 13 1/4"x63 3/4" door frount 1 - 10 1/2"x15" dinning room 1 - 10"x10" room #34							
Patricio Aguilar									
24963		Cafeteria			7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 11:50:39 AM				
Orozco, Danny		ALL DRAINS ARE BACKED-UP. (3 COMPARTMENT SINK)  MARTHA FLORES - 589-2425							
Jacqueline Aguilar									
25111		Cafeteria			7/26/2007		6		\$0.00
Medium	Work In Progress				7/26/2007 9:49:40 AM				
Villalobos, Margret		Mice problem - I called Margret at Maintenance on 7/26/07 at 9:00 a.m.  Martha Flores - SNP Manager							
Alma Terrell									
25196					7/30/2007		2		\$0.00
Medium	Work In Progress				7/30/2007 8:45:46 AM				
Lozoya, Manny		need a classroom key for the new portable.							
Diana Gonzalez									
<b>Count: 16 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>21</b>		<b>Total for Desert View ES</b>	<b>0</b>		<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>GAC</b>							
24679					7/10/2007		22		\$0.00
Medium	Work In Progress				7/10/2007 4:02:36 PM				
Miranda, Danny		Main Entry Reception Area- prepare cost estimat to install new counter. Check w with Elisa Saenz or Nancy Segura on specifics							
Alfredo Holguin									
25227		Restroom (Girls)			7/30/2007		2		\$0.00
Medium	Work In Progress	BEHIND			7/30/2007 4:42:38 PM				
Villalobos, David		AS PER YVONNE LOZANO-NEED TO PURCHASE A COMOTE FOR GIRLS BATHROOM IN C-WING. (TALL ONE, DUE TO ADA)				OKEYED AS PER MR. CHAVEZ			
Mary Garcia									
25031		Office			7/24/2007		8		\$0.00
Medium	Work In Progress	C-WING			7/24/2007 1:53:15 PM				
Lozoya, Manny		AS PER ESTHER NATERA-NEED A KEY MADE FOR HER OFFICE #A41							
Mary Garcia									
24899		Office			7/19/2007		13		\$0.00
Medium	Work In Progress	C-WING			7/19/2007 8:52:25 AM				
Lozoya, Manny		NEED A KEY #A25 FOR MANUEL LEYVA							
Mary Garcia									
24883	RTC	Portables			7/18/2007		14		\$0.00
Medium	Work In Progress	Across the street			7/18/2007 3:38:11 PM				
Villalobos, Margret		As Per Gloria Saenz need fumigation & mouse traps for classrooms							
Juan Ambriz									
25028		Office			7/24/2007		8		\$0.00
Medium	Work In Progress	C-WING			7/24/2007 1:40:04 PM				
Villalobos, David		AS PER ROBERTO-SINK IN THE CUSTODIAN ROOM IN C -WING IS NOT WORKING PROPERLY.							
Mary Garcia									
24902	Pre-K	Portables			7/19/2007		13		\$0.00
Medium	Work In Progress	CHAPARRAL			7/19/2007 9:29:27 AM				
Lozoya, Manny		AS PER LUCY MESA-NEED 3 GATE KEYS AND 3 GRAND MASTER KEYS FOR ALL DOORS AND AT CHAPARRAL ELEM. WHEN COMPLETED PLEASE TURN IN TO ANN STENOFF AS SHE WILL DISTRIBUTE. (IF YOU NEED MORE INFO. ON THIS CALL LUCY MESA @ FEDERAL PROGRAMS @ 882-6788				PERSON TO TALK W/TERESA RAMIREZ OR JUDY ATKINS			
Mary Garcia									
24918	RTC	Classroom			7/19/2007		13		\$0.00
Medium	Work In Progress	ACROSS THE			7/19/2007 2:34:45 PM				
Munoz, Michael		AS PER GLORIA SAENZ-IF A SIDE WALK CAN BE INSTALLED BEHIND THE PORTABLE. THERE IS TO MUCH SAND FOR STUDENT TO WALK IN.							
Mary Garcia									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: GAC</b>									
25151		Restroom (Girls)			7/27/2007		5		\$0.00
Medium	Work In Progress	C-WING			7/27/2007 8:10:34 AM				
Ambriz, Juan		AS PER LISA S-BATHROOM BEHIND RECEPTION AREA NEEDS TO BE PAINTED. (PAINT LOOKS OLD AND DIRTY)							
Mary Garcia									
25154		Restroom (Girls)			7/27/2007		5		\$0.00
Medium	Work In Progress	C-WING			7/27/2007 8:22:37 AM				
Ambriz, Juan		AS PER LISA S-BATHROOM BEHIND RECEPTION AREA, THE BASE BOARD LOOKS OLD DIRTY AND REALLY NEEDS TO BE REPLACED.				Route to Juan for color match - Mike 7/30			
Mary Garcia									
25153		Restroom (Girls)			7/27/2007		5		\$0.00
Medium	Work In Progress	C-WING			7/27/2007 8:14:51 AM				
Ambriz, Jose		AS PER LISA S.-BATHROOM BEHIND RECEPTION AREA, IF FLOOR TILES CAN BE CHANGED OUT. TILES ARE FADED AND OLD/SOME BROKEN & LOOKS BAD.)				Route to Juan for color match - Mike 7/30			
Mary Garcia									
25198	Pre-K	Classroom			7/30/2007		2		\$0.00
Medium	Work In Progress	ALL			7/30/2007 10:28:46 AM				
Hernandez, Guillermo		AS PER MS. BERRY-NEEDS FLOOR "WIPER" MATS FOR ALL DOORS GOING OUT TO THE PLAYGROUND AREA. TOTAL OF 6 MATS, SIZE 36 X 40							
Mary Garcia									
25197	RTC	Office			7/30/2007		2		\$0.00
Medium	Work In Progress	ACROSS THE			7/30/2007 10:22:03 AM				
Ambriz, Jose		AS PER MS. HINOJOS-AIR UNIT STILL HAVING PROBLEMS.							
Mary Garcia									
25226		Office			7/30/2007		2		\$0.00
Medium	Work In Progress	C-WING			7/30/2007 4:40:24 PM				
Ambriz, Juan		AS PER JOSIE-IF AIR VENT CAN BE RELOCATED, SO IT WON'T BE RIGHT OVER HER HEAD.							
Mary Garcia									
25139	RTC	Portables			7/26/2007		6		\$0.00
Medium	Work In Progress	ACROSS THE			7/26/2007 4:31:17 PM				
Ambriz, Jose		AS PER JONES JOHNSON-THE AIR UNIT (REGRIGERATION) DOES NOT WORK.							
Mary Garcia									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

25241					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:04:45 AM				
Lara, Ralph		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
24816	Pre-K	Office			7/16/2007		16		\$0.00
Medium	Work In Progress	PRE K			7/16/2007 4:24:46 PM				
Lozoya, Manny		AS PER YVONNE LOZANO-NEEDS A GRAND MASTER KEY FOR PRE-K CENTER.							
Mary Garcia									
24801	Pre-K	Office			7/16/2007		16		\$0.00
Medium	Work In Progress	ROOM 203			7/16/2007 12:58:23 PM				
Lara, Ralph		AS PER ESTRELL-NEED TO MOVE THE LOFT FROM ROOM 202 INTO ROOM 203.							
Mary Garcia									
24802	Pre-K	Office			7/16/2007		16		\$0.00
Medium	Work In Progress	PRE-K			7/16/2007 1:00:31 PM				
Lara, Ralph		AS PER ALICE-NEED TO HAVE AN OLD FILE CABINET OUT AND REPLACE WITH NEW ONE.							
Mary Garcia									
24815	Pre-K	Classroom			7/16/2007		16		\$0.00
Medium	Work In Progress	PRE-K			7/16/2007 4:18:02 PM				
Boyd, David		AS PER JUAN AMBRIZ-ROOF LEAKED IN 2 OF THE PRE-K CLASSROOMS.				ON HOLD UNTIL MR. BOYD LOOKS INTO THIS, TO MAKE SURE IT IS NOT UNDER WARRENTY.			
Mary Garcia									
24504					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:30 AM				
Ambriz, Juan		Yearly - GAC Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
24505					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:30 AM				
Ambriz, Juan		Yearly - GAC Emer. Light Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
24461					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:13 AM				
Orozco, Danny		Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC</b>							
24502					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:29 AM				
Ambriz, Juan		Monthly - GAC Roof Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24440					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:01 AM				
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Alfredo Holguin									
24381					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24382					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24383					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
<b>Count: 28 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>15</b>	<b>Total for GAC</b>			<b>0</b>	<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
24384					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24385					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24386					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24387					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24388					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24448					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:07 AM				
Orozco, Danny		Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
24519					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:36 AM				
Apodaca, Mario		Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Alfredo Holguin									
24474					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:18 AM				
Moncayo, Fernando		Yearly - Gladsgden HS Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
24475					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:18 AM				
Moncayo, Fernando		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Alfredo Holguin									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
24571					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:56 AM				
Arreola, Rudy	Yearly - Gadsden HS Emer. Light Test: Annual - Refer to PM schedule details.								
Alfredo Holguin									
24912	North Building	Custodial			7/19/2007		13		\$0.00
Medium	Work In Progress				7/19/2007 11:54:19 AM				
Munoz, Joe	The windows in the attendance office need to be washed.								
25243					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:05:19 AM				
Munoz, Joe	QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)								
Jesus Estrada									
25199					7/30/2007		2		\$0.00
Medium	Work In Progress				7/30/2007 10:56:31 AM				
Gonzales, Angel	I HAVE TWO GAS BLOWERS THAT NEED SERVICE								
Joe Munoz									
24746		Football Field			7/12/2007		20		\$0.00
Medium	Work In Progress				7/12/2007 3:34:03 PM				
Castillo, Carlos	NEED TO PUT NEW OUTLET AT FOOTBALL CONCESSION STAND AT THE BACK ROOM FOR THE REFRIGERATOR AND FREEZER								
Mario Apodaca									
25204	Boys Gym				7/30/2007		2		\$0.00
Medium	Work In Progress	Football Side			7/30/2007 2:49:17 PM				
Munoz, Michael	NEED A NEW DOOR FOR THE BOYS GYM FOOTBALL SIDE LOCKER ROOM DOTO VANDALISM								
Mario Apodaca									
24655		Football Field			7/10/2007		22		\$0.00
Medium	Work In Progress				7/10/2007 8:36:04 AM				
Castillo, Carlos	Need to check out football field.								
Michael Munoz									
25268	Cafeteria (1998)	Hallway/Corridor			7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 3:20:25 PM				
Ronquillo, Ruben	Window needs to be replaced 2 x2 main entrance to cafeteria.								
Rudy Arreola									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
24914	Cafeteria (1998)	Cafeteria			7/19/2007		13		\$0.00
Medium	Work In Progress				7/19/2007 1:19:31 PM				
Ronquillo, Ruben		NEED TO ORDER FLUORESCENT LAMPS MINI BIA X 20W -120/127 VOLTS FLE20TT3/827 NEED 60 E.A							
Mario Apodaca									
24839					7/17/2007		15		\$0.00
Medium	Work In Progress				7/17/2007 2:46:09 PM				
Mc Dermott, Michael		We need the sign in the cafeteria the ZIA symbol flourcens lamp to be checked for power contractor said no power going to it.							
Rudy Arreola									
25059	Pool Pump House	Pool			7/25/2007		7		\$0.00
Medium	Work In Progress				7/25/2007 8:10:17 AM				
Castillo, Carlos		AS PER RAUL SANCHEZ ;CIRCULATING PUMP NOT WORKING							
Carlos Castillo									
24862	Main Building	Gym			7/18/2007		14		\$0.00
Medium	Work In Progress				7/18/2007 7:57:29 AM				
Appelzoller, Fred		gas repair at main building to girls gym, auto shop and wood shop.							
Fred Appelzoller									
24852					7/17/2007		15		\$0.00
Medium	Work In Progress				7/17/2007 3:32:00 PM				
Villalobos, Margret		Need to spray HOME C ROOMS for brown cockroach, and apply mice poison, before school start THANKS!!							
Fernando Moncayo									
24836					7/17/2007		15		\$0.00
Medium	Work In Progress				7/17/2007 2:30:46 PM				
Lozoya, Manny		Requested by Velia-Four HK7 keys are needed for the Intervention Staff that will be in Rm. 554.							
Velia Alarcon									
24823					7/17/2007		15		\$0.00
Medium	Work In Progress				7/17/2007 9:44:36 AM				
Lozoya, Manny		Requested by Agustin Garcia Rm. 310A Academic Building- Door handle to Custodian's storage closet is broken and needs to be replaced before school begins.							
Velia Alarcon									
25113					7/26/2007		6		\$0.00
Medium	Work In Progress				7/26/2007 11:09:31 AM				
Arreola, Rudy		Requested by Mr. Burciaga Rm. 611 Business Building-Move projection screen from room 153 in Old English Building to room 611 in Business Building.							
Velia Alarcon									



# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
25208					7/30/2007		2		\$0.00
Medium	Work In Progress				7/30/2007 3:12:59 PM				
Lozoya, Manny		Requested by Velia for rm. 245 over Varsity Gym-Mr. Foster has placed the Parent Out-Reach Ambassador's in this classroom has their new office. Four HE38 keys are need to issue to the Ambassador's. They will be re-located once a space is found for them.							
Velia Alarcon									
25212					7/30/2007		2		\$0.00
Medium	Work In Progress				7/30/2007 3:25:27 PM				
Lozoya, Manny		Requested by Velia-Four HE1 (Gym Keys) are needed for the Parent Out-Reach Ambassador's to open small hallw ay over the Varsity Gym to access their new office/classroom.							
Velia Alarcon									
25221					7/30/2007		2		\$0.00
Medium	Work In Progress				7/30/2007 3:44:32 PM				
Lozoya, Manny		Requested by Velia for Rm. 126A Main Building-Four HH16 keys are needed to office.							
Velia Alarcon									
25225					7/30/2007		2		\$0.00
Medium	Work In Progress				7/30/2007 4:00:35 PM				
Lozoya, Manny		Requested by Velia for Rm. 554 Wood Shop-Four HK7 keys are needed for Intervention Staff.							
Velia Alarcon									
25263	Concession Stand				7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 1:36:15 PM				
Ronquillo, Ruben		Requested by Ms. I. Ramos Rm. 158 Concession Stand-Room # 158 (Concession Stand) by the Girl's Gym needs to have windows intalled. They need to be able to open and close. This will be used as a classroom lab area for the marketing program. It will be used as a store & inventory classroom, needs to be secure.							
Velia Alarcon									
25261					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 1:18:55 PM				
Arreola, Rudy		Requested by Ms. I. Ramos Rm. 158 Concession Stand-Request for paint, marble and maroon color paint, rollers, and brushes. To paint outside of concession stand and touch up the inside as well.							
Velia Alarcon									
25259					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 10:22:16 AM				
Lozoya, Manny		Requested by Oscar Menchaca Rm. 123 Custodial Storage Room in Main Building-Door lock does not work.							
Velia Alarcon									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Gadsden HS</b>							
25260					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 10:34:23 AM				
Lozoya, Manny		Requested by Debbie Costalez Rm. 118 Bookkeeper's Office in Main Building-The bookkeeping office in the same as the concession stand. The concession stand is going to be used as a Marketing classroom. The bookkeeping office needs to be off master and four keys are needed.							
Velia Alarcon									
<b>Count: 33 Work Orders</b>		<b>Avg. Age of WO's</b>			<b>15</b>	<b>Total for Gadsden HS</b>		<b>0</b>	<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
24392					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24393					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24394					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
25033					7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 3:29:03 PM				
Ronquillo, Ruben		7/24/07 Inthe Vicky Lopez office need blind 45 1/2 x 45 1/2 thank you							
Sebastian Diaz									
24670					7/10/2007		22		\$0.00
Medium	Work In Progress				7/10/2007 3:22:34 PM				
Sotelo, Enrique		7/10/07 Need three boxes of florescent lights tipo U thank you							
Sebastian Diaz									
24605	Cafeteria	Cafeteria			7/6/2007		26		\$0.00
Medium	Work In Progress				7/6/2007 11:24:48 AM				
Orozco, Danny		REACH-IN FREEZER IS NOT FREEZING (TERRY NOTICED THAT IT WAS 50 DEGREES ON 7/5/07, SHE HAD TO MOVE ALL PRODUCTS TO WALK-IN FREEZER, ON 7/6/07 IT WAS 95 DEGREES SO SHE DISCONNECTED IT)							
		TERRY PORTILLO - SNP MANAGER 882-2824							
Alma Terrell									
25125	Main Building Mid	Classroom			7/26/2007		6		\$0.00
Medium	Work In Progress	ROOM 169			7/26/2007 2:44:56 PM				
Diaz, Sebastian		LEAKING ROOF IN ROOM 169							
Juan Acosta									
25265					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 2:58:50 PM				
Diaz, Sebastian		AS PER SECURITY/DRUG FREE COORDINATOR JOE MENDEZ LOCKERS NEED TO BE SECURED WITH CABLE BEFORE MONDAY AUGUST 6, 2007.							
Juan Acosta									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

25082	Vocational				7/25/2007		7		\$0.00
Medium	Work In Progress	VOCATIONAL			7/25/2007 3:48:39 PM				
Diaz, Sebastian		OUTSIDE WALLS NEED PAINTING							
Juan Acosta									
25087	C-Wing (Old)	Restroom (Girls)			7/25/2007		7		\$0.00
Medium	Work In Progress				7/25/2007 3:58:17 PM				
Diaz, Sebastian		C WING RESTROOMS TILES NEED TO BE REPLACED WORN OUT							
Juan Acosta									
25116	C-Wing	Office			7/26/2007		6		\$0.00
Medium	Work In Progress	ATHLETIC DEPT.			7/26/2007 1:59:10 PM				
Lozoya, Manny		AS PER MR. LOWENBERG-NEEDS 3 KEYS TO THE PORTABLE BEHIND OLD CENTRAL OFFICE NEXT TO GMS. (PORTABLE WHERE PAM/PURCHASING OFFICE USED TO BE.)							
Mary Garcia									
25118	C-Wing	Office			7/26/2007		6		\$0.00
Medium	Work In Progress	ATHLETIC DEPT.			7/26/2007 2:00:32 PM				
Lozoya, Manny		AS PER MR. LOWENBERG-NEEDS 3 KEYS FOR THE FRONT GATE (1ST GATE ONLY) NEXT TO OLD CENTRAL OFFICE.							
Mary Garcia									
25244					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:13:51 AM				
Acosta, Juan		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
24956					7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 9:53:03 AM				
Acosta, Juan		NEED TO RELOCATE ATHLETICS TO OLD PURCHASING PORTABLE, PURCHASING ( ALLL EXCETP CONFERENCETABLE) TO GM NURSHING AND GM NURSING TO ATHLETICS. CONTACT PERSONS WOULD BE MR. LOWENBERG & DR GARCIA							
Alfredo Holguin									
24920					7/19/2007		13		\$0.00
Medium	Work In Progress				7/19/2007 3:01:05 PM				
Lozoya, Manny		AS PER ALFREDO YOU NEED TO PICK UP MASTER KEY 6&7 THAT WERE ISSUED TO MR. DANA HAMEL ASAP.							
Alfredo Holguin									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
25021					7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 11:02:26 AM				
Lozoya, Manny		Manny Lozoya to collect the 6 and 7 master keys that were issued to him. ASAP							
Alfredo Holguin									
24449					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:08 AM				
Orozco, Danny		Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
24389					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24390					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24391					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24395					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24396					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
<b>Count: 22 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>18</b>		<b>Total for Gadsden MS</b>	<b>0</b>		<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: La Union - JTP Alvarez Farms</b>									
24909					7/19/2007		13		\$0.00
Medium	Work In Progress				7/19/2007 10:26:14 AM				
Lozoya, Manny		Need Master key for Alvarez Farms issued to Hirri Bauman.							
25115					7/26/2007		6		\$0.00
Medium	Work In Progress				7/26/2007 1:46:13 PM				
Lozoya, Manny		Need (1) L200 Key for new teacher A. Franco.							
Margaret Villalobos									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>10</b>	<b>Total for La Union - JTP Alvarez Farms</b>			<b>0</b>	<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: La Union ES</b>									
24675	La Union JTP				7/10/2007		22		\$0.00
Medium	Work In Progress				7/10/2007 3:35:03 PM				
Castillo, Carlos		Cali can you come and check for new electric circuit powder for new refrigeration system on classroom 108 please. Thank you							
Salvador Gonzalez									
24719					7/11/2007		21		\$0.00
Medium	Work In Progress				7/11/2007 3:43:15 PM				
Lozoya, Manny		7/11/07 Manny Linda (cafeteria Manager) is requiring a new KEY because she is having problems with the she has. Thank you							
Salvador Gonzalez									
24879					7/18/2007		14		\$0.00
Medium	Work In Progress				7/18/2007 3:25:18 PM				
Castillo, Carlos		7/18/07 Cali can you check the metal gate of the office please, has an electric failure and it doesn't close. Thank you.							
Salvador Gonzalez									
25129					7/26/2007		6		\$0.00
Medium	Work In Progress				7/26/2007 3:49:29 PM				
Lozoya, Manny		7/26/07 Manny can you change door lock for classroom 210 (child safety). Thank you.							
Salvador Gonzalez									
25172					7/27/2007		5		\$0.00
Medium	Work In Progress				7/27/2007 3:42:58 PM				
Castillo, Carlos		7/27/07 Cali can you install new outlets for room 110 Requested by principal. Thank you.							
Salvador Gonzalez									
24402					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:54 AM				
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24403					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:54 AM				
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24404					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:54 AM				
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: La Union ES</b>									
24450					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:08 AM				
Orozco, Danny		Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
25245					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:14:30 AM				
Galindo, Santos		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
<b>Count: 10 Work Orders</b>		<b>Avg. Age of WO's 19</b>			<b>Total for La Union ES</b>			<b>0</b>	<b>\$0.00</b>



# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Loma Linda ES</b>									
24700					7/11/2007		21		\$0.00
Medium	Work In Progress	Playground			7/11/2007 10:01:41 AM				
Mc Dermott, Michael		As per Alfredo need to replace sprinklers and adjust.							
Alfredo Holguin									
25163					7/27/2007		5		\$0.00
Medium	Work In Progress				7/27/2007 10:06:44 AM				
Lozoya, Manny		MANNY THE DOOR IN ROOM 115 NOT WORKING PROPERLY, CATCH ON DOOR WILL NOT CATCH.							
Grace Alvarado									
24441					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:02 AM				
Orozco, Danny		Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Alfredo Holguin									
24397					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24398					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24399					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
25200					7/30/2007		2		\$0.00
Medium	Work In Progress				7/30/2007 11:47:38 AM				
Holguin, Ramiro		MIKE: AS PER MR. TRUJILLO'S REQUEST, WE ARE NEEDING IMMEDIATE ATTENTION REGARDING THE WEEDS THROUGHOUT THE GROUNDS. WE ARE NEEDING THIS DONE BEFORE SCHOOL STARTS. STUDENTS USE BACK ENTRANCE TO GET ONTO SCHOOL PREMISES.							
Grace Alvarado									
25061					7/25/2007		7		\$0.00
Medium	Work In Progress				7/25/2007 8:29:50 AM				
Ronquillo, Ruben		WE HAD ASKED MIKE MCDERMOTT TO REPLACE BLINDS IN ROOM 103. HE IS NO LONGER WITH THE DISTRICT AND BLINDS STILL HAVE NOT BEEN REPLACED.							
Grace Alvarado									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Loma Linda ES</b>									
25246					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:15:12 AM				
Solis, Luis	QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)								
Jesus Estrada									
24835		Custodial			7/17/2007		15		\$0.00
Medium	Work In Progress				7/17/2007 12:38:28 PM				
Villalobos, Margret	PLEASE, WE NEED SOME THING TO CATCH SOME MICE FROM THE CUSTODIAL (JANITOR ROOM.) THANKS.								
Luis Solis									
24400					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David	Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24451					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:09 AM				
Orozco, Danny	Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.								
Alfredo Holguin									
<b>Count: 12 Work Orders</b>		<b>Avg. Age of WO's 20</b>			<b>Total for Loma Linda ES</b>			<b>0</b>	<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Mesquite ES

24452					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:09 AM				
Orozco, Danny		Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
24551					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:48 AM				
Apodaca, Romauldo		Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
24857	Army Building	Custodial			7/17/2007		15		\$0.00
High	Work In Progress				7/17/2007 4:28:09 PM				
Lozoya, Manny		I need 2 keys (A6) for administrators at Mesquite Elem. Administration should have access to room 600 where custodial/maintenance have computers.							
24557					7/1/2007	7/7/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:51 AM				
Apodaca, Romauldo		Monthly - Mesquite ES Monthly FE Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24558					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:51 AM				
Apodaca, Romauldo		Monthly - Mesquite ES Roof Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24555					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:50 AM				
Apodaca, Romauldo		Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
24552					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:49 AM				
Apodaca, Romauldo		Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Alfredo Holguin									
24553					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:49 AM				
Apodaca, Romauldo		Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Alfredo Holguin									
24405					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Mesquite ES</b>									
24406					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24407					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24408					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24612		Classroom			7/6/2007		26		\$0.00
Medium	Work In Progress				7/6/2007 2:28:27 PM				
Apodaca, Romauldo		ROOM 402 TEACHER DESK NEED TO BE FIX ASK LUIS SAUCEDO							
Luis Saucedo									
24876		Dressing Room			7/18/2007		14		\$0.00
Medium	Work In Progress				7/18/2007 3:12:55 PM				
Carbajal, Jimmy		please i need a flat bed doolly w e are moving classrooms thank you luis							
Luis Saucedo									
25247					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:17:25 AM				
Saucedo, Luis		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
25019		Portables			7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 10:58:26 AM				
Lozoya, Manny		PT 611 - Need to change lever a/s/a/p.							
Romauldo Apodaca									
25072					7/25/2007		7		\$0.00
Medium	Work In Progress				7/25/2007 11:38:23 AM				
Lozoya, Manny		AS PER MS. PHILLIPS NEED THE FOLLOWING KEYS: 3 KEYS FOR RM 607 3 KEYS FOR RM 206							
Romauldo Apodaca									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
24630					7/9/2007		23		\$0.00
Medium	Work In Progress				7/9/2007 2:37:11 PM				
Lozoya, Manny	manny nedd 2 c-242								
Romauldo Apodaca									
<b>Count: 18 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>24</b>	<b>Total for Mesquite ES</b>				<b>0</b>	<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
25248					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:18:19 AM				
Trujillo, Gilbert	QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)								
Jesus Estrada									
25232					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 7:54:27 AM				
Hernandez, Guillermo	JIMMY NEED 8 TIRES FOR BUTCHER PAPER CARTS FOR GILBERT								
Frank Lara									
25203	Main Building				7/30/2007		2		\$0.00
Medium	Work In Progress				7/30/2007 2:26:51 PM				
Lara, Frank	Need to transport 5 filing cabinets to Chaparral On Track Pre-k and 3 filing cabinets to Anthony On Track Pre-K.								
Concepcion Montalvo									
24401					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:54 AM				
Villalobos, David	Yearly - Northern Pre-K (LM) Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>9</b>	<b>Total for Northern On-Track Pre-K (LM)</b>			<b>0</b>	<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
24409					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24410					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
25023	Purchasing				7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 11:04:34 AM				
Lozoya, Manny		I (Mary Murin) lost the key DC18 opened the one outside door....the same door the Marta and Yoli Jacquez go into the leads to their offices.							
Margret Villalobos									
24610					7/6/2007		26		\$0.00
Medium	Work In Progress				7/6/2007 1:54:54 PM				
Lozoya, Manny		Need a J3 (Gate Key) for Sebastian Diaz							
Michael Munoz									
25020	Maintenance				7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 11:00:39 AM				
Appelzoller, Fred		New Tech Office Restroom - is not flushing properly.							
Michael Munoz									
24827					7/17/2007		15		\$0.00
Medium	Work In Progress				7/17/2007 11:18:49 AM				
Lozoya, Manny		JULIE IS REQUESTING A J3 GATE KEY (ORIGINAL ONE WAS GIVEN TO VIKKI LOPEZ)							
Juliet Parra									
24589		Office			7/2/2007		30		\$0.00
Medium	Work In Progress	PPD			7/2/2007 11:03:22 AM				
Lozoya, Manny		AS PER SHIELA RHAIL-NEED A TOTAL OF 2 KEYS DC-18 FOR HERSELF AND VICKY LOPEZ.							
Mary Garcia									
24784					7/16/2007		16		\$0.00
Medium	Work In Progress				7/16/2007 8:03:38 AM				
Ronquillo, Ruben		FORKLIFT SHADE YELLOW CANVAS(MAINT.WHS-2, PUR.WHS-1, F.S. WHS.-1.							
Ruben Ronquillo									
24943					7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 8:39:09 AM				
Jacquez, Ricardo		7-16-07 ppd-2 daily o&m on w w tp ghs-2 daily o&m on w w tp sre-3.5 24570 ppd-.5 fill in daily log				7/16-4.5			
Ricardo Jacquez									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
24904	Purchasing				7/19/2007		13		\$0.00
Medium	Work In Progress				7/19/2007 9:42:45 AM				
Diaz, Sebastian		A/C NOT WORKING... THERE IS BARLEY AIR COMING OUT. (As per Ruben motor burned out informed Sebastian).							
Tracey Sw inford									
24590	Purchasing	Office			7/2/2007		30		\$0.00
Medium	Work In Progress	Inst/Materials			7/2/2007 2:08:06 PM				
Diaz, Sebastian		Need new blinds for this office.				Re-routed to Sebastian... Need sizes. MG			
Vicky Lopez									
<b>Count: 11 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>20</b>	<b>Total for Physical Plant Complex</b>			<b>0</b>	<b>\$0.00</b>



# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Riverside ES**

24374					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:50 AM				
Villalobos, David		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24375					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:50 AM				
Villalobos, David		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

25249					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:18:53 AM				
		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									

24373					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:49 AM				
Villalobos, David		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

25168					7/27/2007		5		\$0.00
Medium	Work In Progress				7/27/2007 3:01:02 PM				
Ambriz, Jose		MR JOSE AMBRIZ SIR WE HAVE AN AC UNIT IN BAD SHAPE WATER IS LEAKING FROM PAN TO WHERE SQUIRREL CAGE IS AND IS LEAKING IN TO ROOM IT A 6500 AC 12" PADS SIR WE NEED TO REPLACE ASAP THANK YOU SIR AND GOD BLESS							
Adan Duran									

24898					7/19/2007		13		\$0.00
Medium	Work In Progress				7/19/2007 8:51:46 AM				
Ambriz, Jose		MR JOSE AMBRIZ SIR WE HAVE AN AC UNIT IN BAD SHAPE BEARINGS BAD THE WATER PAN BAD MAKING ALOT OF NOSISE NEED TO REPLACE IT AND JUST TO LET YOU KNOW WE START SCHOOL MONDAY 23 THANK YOU SIR AND GOD BLESS							
Adan Duran									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
24848					7/17/2007		15		\$0.00
Medium	Work In Progress				7/17/2007 3:11:58 PM				
Duran, Adan		7/17/07	1/2 SIGN IN CHECK SCHOOL GROUNDS BUILDING FENCE 11/2 CLEAN SAND AROUND BIG CIRCLE AND CURBS 455 JOHN DEERE 5 PRUN MESQITE TREES NORTH AND SOUTH SIDE AND POT ASH TREE AND HAUL OFF BRANCHES 1 FILE DAILY LOG AND SIGN OUT			7/17-8			
Adan Duran									
24964					7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 12:11:45 PM				
Lozoya, Manny			MR MANNY LOZOYA SIR PER OFFICE THERE ARE TWO FILE CABINETS THAT NEED TO BE REPAIRED ONE IN CONFERENCE ROOM AND ONE IN ROOM 28 ASAP PLEASE THANK YOU SIR						
Adan Duran									
24971					7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 3:10:27 PM				
Lozoya, Manny			MR MANNY LOZOYA SIR WE HAVE TWO CABINET DOORS ROOM 116 THAT NEED THE DOOR LATCH REPLACE BROKE THE ONES THAT WHERE THERE THANK YOU SIR						
Adan Duran									
24453					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:10 AM				
Orozco, Danny			Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.						
Alfredo Holguin									
<b>Count: 10 Work Orders</b>		<b>Avg. Age of WO's 18</b>			<b>Total for Riverside ES</b>			<b>0</b>	<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** San Miguel ES

24454 7/1/2007 7/22/2007 31 \$0.00  
 Medium Work In Progress 7/1/2007 12:16:10 AM  
 Orozco, Danny Monthly - San Miguel ES Range Hood Cleaning - Refer to PM schedule details.

Alfredo Holguin

24462 7/1/2007 7/9/2007 31 \$0.00  
 Medium Work In Progress 7/1/2007 12:16:13 AM  
 Vega, Danny Monthly - San Miguel ES Roof Inpsection - Refer to PM schedule details.

Alfredo Holguin

24466 7/1/2007 7/9/2007 31 \$0.00  
 Medium Work In Progress 7/1/2007 12:16:15 AM  
 Vega, Danny Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details.

Alfredo Holguin

24467 7/1/2007 8/1/2007 31 \$0.00  
 Medium Work In Progress 7/1/2007 12:16:15 AM  
 Vega, Danny Yearly - San Miguel ES Exit Sign Test: Annual - Refer to PM schedule details.

Alfredo Holguin

24463 7/1/2007 7/7/2007 31 \$0.00  
 Medium Work In Progress 7/1/2007 12:16:14 AM  
 Vega, Danny Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.

Alfredo Holguin

24464 7/1/2007 8/1/2007 31 \$0.00  
 Medium Work In Progress 7/1/2007 12:16:14 AM  
 Vega, Danny Yearly - San Miguel ES Emer. Light Test: Annual - Refer to PM schedule details.

Alfredo Holguin

24465 7/1/2007 7/9/2007 31 \$0.00  
 Medium Work In Progress 7/1/2007 12:16:14 AM  
 Vega, Danny Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Alfredo Holguin

24371 7/1/2007 8/1/2007 31 \$0.00  
 Medium Work In Progress 7/1/2007 12:15:49 AM  
 Villalobos, David Yearly - San Miguel ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24372 7/1/2007 8/1/2007 31 \$0.00  
 Medium Work In Progress 7/1/2007 12:15:49 AM  
 Villalobos, David Yearly - San Miguel ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: San Miguel ES</b>									
25250					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:19:25 AM				
		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
24730					7/12/2007		20		\$0.00
Medium	Work In Progress	SERVER ROOM			7/12/2007 8:32:57 AM				
	Vega, Danny	there is water right behind the Compaq Rack it seems like it is coming from the AC unit. please check ASAP							
Cora Ramirez									
25103		Classroom			7/26/2007		6		\$0.00
Medium	Work In Progress	21			7/26/2007 8:19:00 AM				
	Lozoya, Manny	Rosie Castillo--Rm. 21 one of the doors does not lock w their key or the master key, safety issue we had a lock down the other day and we were not able to secure the room.							
		Safety Issue--ASAP							
Barbara Cardenas									
25065		Classroom			7/25/2007		7		\$0.00
Medium	Work In Progress	2,19,22,30,32,36,3			7/25/2007 10:39:20 AM				
	Lozoya, Manny	Need the following keys: One of each except B47 need to for that classroom. B7, B11, B22, B47-need two keys of this one, B51, B52, B55, B63, B64							
Barbara Cardenas									
24953					7/20/2007		0		\$0.00
Medium	Work In Progress				7/20/2007 9:08:53 AM	7/20/2007			
	Lozoya, Manny	new doors installed in boiler rm#16/need to recore locks on doors/secure before end of day /asap							
Danny Vega									
25075					7/25/2007		7		\$0.00
Medium	Work In Progress				7/25/2007 1:09:11 PM				
	Lozoya, Manny	keys made for fire alarm pull station boxes dont work /please pick-up keys in office.please correct or make new keys							
Danny Vega									
<b>Count: 15 Work Orders</b>			<b>Avg. Age of WO's 21</b>		<b>Total for San Miguel ES</b>			<b>0</b>	<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa ES</b>									
25067					7/25/2007		7		\$0.00
Medium	Work In Progress				7/25/2007 10:54:09 AM				
Ronquillo, Ruben		MIKE, I'LL NEED 30 BUNDLES OF CEILING TILES FOR THE OLD PORTABLE.							
Gerardo Marquez									
25064					7/25/2007		7		\$0.00
Medium	Work In Progress				7/25/2007 10:36:40 AM				
Munoz, Michael		MIKE, NEED TO HAVE CARPET INSTALLED AND COVE BASE REPLACED IN NORTHWEST CLASS RM. OF NEW PORTABLE.							
Gerardo Marquez									
25252					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:19:58 AM				
Diaz, Pablo		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
24432					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:59 AM				
Villalobos, David		Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24433					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:59 AM				
Villalobos, David		Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24455					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:10 AM				
Orozco, Danny		Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
<b>Count: 6 Work Orders</b>			<b>Avg. Age of WO's 18</b>			<b>Total for Santa Teresa ES</b>	<b>0</b>		<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
24456					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:11 AM				
Orozco, Danny		Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
24419					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:57 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24420					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24421					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24422					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24423					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24424					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24425					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24426					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
25253					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:20:30 AM				
Murillo, Luis		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
24908		Classroom			7/19/2007		13		\$0.00
Medium	Work In Progress	STHS			7/19/2007 10:00:20 AM				
Murillo, Luis		NEED TO PICK UP FROM STHS - CRYSTAL ARAGON/ COUNSELORS CENTER - 1) BLK STORAGE AND DELIVER TO LA MESA PRE-K. 2) COPIER, BOOKSHELF & FILE CABINET AND DELIVER TO ANTHONY PRE-K VILLAGE ROOM #308							
Mary Garcia									
24781					7/13/2007		19		\$0.00
Medium	Work In Progress				7/13/2007 4:10:46 PM				
Villalobos, David		As per David Munoz w ater leaking from job done by contractors.							
Margret Villalobos									
24348					7/1/2007	7/7/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:42 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24349					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:42 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24346					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:41 AM				
Nunez, Arturo		Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
24347					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:42 AM				
Nunez, Arturo		Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Santa Teresa HS</b>							
24733		Cafeteria			7/12/2007		20		\$0.00
Medium	Work In Progress				7/12/2007 2:13:37 PM				
Orozco, Danny		SLICER IS NOT WORKING CORRECTLY							
		OLGA B. SNP MGR 589-5332							
Jacqueline Aguilar									
24734		Cafeteria			7/12/2007		20		\$0.00
Medium	Work In Progress				7/12/2007 2:15:18 PM				
Orozco, Danny		NEEDS A WATER HOSE TO BE INSTALLED FROM THE DISHWASHER							
		OLGA B. SNP MGR 589-5332							
Jacqueline Aguilar									
<b>Count: 18 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>26</b>			<b>Total for Santa Teresa HS</b>	<b>0</b>		<b>\$0.00</b>



# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Santa Teresa MS**

24957	North Building	Custodial			7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 10:11:38 AM				
Villalobos, Margret		NEED TO FUMEGATE THE NORTH AND SOUTH BUILDING THERES ALL CLASSES OF INSECTS.AS PER THE PRINCIPALS.THANK YOU.							
Ismael Rodriguez									

25254					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:21:56 AM				
Rodriguez, Ismael		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									

25166	North Building	Parking Lot			7/27/2007		5		\$0.00
Medium	Work In Progress	Parking Lot			7/27/2007 2:37:02 PM				
Ronquillo, Ruben		Need sign to designate parent parking.							
Laura Parra									

25165					7/27/2007		5		\$0.00
Medium	Work In Progress				7/27/2007 2:34:47 PM				
Mijarez, Jaime		Request for sidew alk curb sides be painted yellow (are now red)							
Laura Parra									

24427					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24791					7/16/2007		16		\$0.00
Medium	Work In Progress				7/16/2007 8:34:47 AM				
Lozoya, Manny		S.bldg room 54 needs a new door handle and assembly w ith core. Can this be done before school starts.							
Jaime Mijarez									

24993	South	Portables			7/23/2007		9		\$0.00
Medium	Work In Progress	P 2 B and 3 B			7/23/2007 1:35:16 PM				
Lozoya, Manny		Please repair locks on Portables 2 B and 3B. Keys get stuck in key hole and are unable to remove.							
Laura Parra									

25164	North Building	Office			7/27/2007		5		\$0.00
Medium	Work In Progress	Round Room			7/27/2007 2:28:41 PM				
Lozoya, Manny		Need to install door lock in the round room. Room w ill become principals office and needs to be locked.							
Laura Parra									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Santa Teresa MS**

24686	North Building	Office			7/11/2007		21		\$0.00
Medium	Work In Progress	North and South			7/11/2007 7:47:03 AM				
Mijarez, Jaime		Request to paint offices located in the north and south building. As per Ms. Lovelace.							
		Principals offices	Assistant Principal						
		Reception Area	Counselor						
		Administrative Intern							
		Data Registrar							
		Secretary							
		Bathrooms							
Laura Parra									
24428					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24429					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24430					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24431					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:59 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24457					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:11 AM				
Orozco, Danny		Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
24498					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:27 AM				
Mijarez, Jaime		Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
24501					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:29 AM				
Mijarez, Jaime		Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									

**Count: 16 Work Orders      Avg. Age of WO's 20      Total for Santa Teresa MS      0      \$0.00**

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Sunland Park ES

24458					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:12 AM				
Orozco, Danny		Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									

24529					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:40 AM				
Prospero, Manuel		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.							
Alfredo Holguin									

24530					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:40 AM				
Prospero, Manuel		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Alfredo Holguin									

24531					7/1/2007	7/7/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:40 AM				
Prospero, Manuel		Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24527					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:39 AM				
Prospero, Manuel		Yearly - Sunland Park ES Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									

24528					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:39 AM				
Prospero, Manuel		Yearly - Sunland Park ES Emer. Light Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									

24532					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:41 AM				
Prospero, Manuel		Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24416					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:57 AM				
Villalobos, David		Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24417					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:57 AM				
Villalobos, David		Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
24418					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:57 AM				
Villalobos, David		Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
25255					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:22:28 AM				
Flores, Larry		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Jesus Estrada									
24671					7/10/2007		22		\$0.00
Medium	Work In Progress				7/10/2007 3:25:01 PM				
Villalobos, David		7/10/07. WATER FOUNTAIN ON PLAY GROUN WAS BROKE. THIS WORK ORDER IS FOR DAVID VILLALOBOS.							
Manuel Prospero									
24962					7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 11:45:33 AM				
Lozoya, Manny		Please help open two filing cabinets that were accidentally locked during the summer break.							
Irene Trujillo									
25022					7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 11:02:33 AM				
Lozoya, Manny		INSTALL A LOCK ON FILING CABINET IN ROOM 10.							
Irene Trujillo									
25025					7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 11:50:25 AM				
Prospero, Manuel		TEACHER'S DESK IN ROOM 10 - THE LEG ON DESK IS FALLING OFF PLEASE REPAIR.							
Irene Trujillo									
25068					7/25/2007		7		\$0.00
Medium	Work In Progress				7/25/2007 11:03:48 AM				
Prospero, Manuel		SWINGS ON PLAYGROUND NEED TO BE REPAIRED. SOME OF THE SWINGS ARE BROKEN AT THE SEAT.							
Irene Trujillo									
25069					7/25/2007		7		\$0.00
Medium	Work In Progress				7/25/2007 11:05:34 AM				
Prospero, Manuel		ON THE KINDER PLAYGROUND - THE SANDS NEEDS TO BE LEVELED AND WEEDS REMOVED.							
Irene Trujillo						Route to Manny, material was selivered and as per Lupe grounds Manuel will spread. Wheel barrow will take care of pile of sand. 7/30 - Mike			

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location: Sunland Park ES</b>									
25070					7/25/2007		7		\$0.00
Medium	Work In Progress				7/25/2007 11:22:01 AM				
Prospero, Manuel		SECURE ALL BULLETIN BOARDS IN THE CLASSROOMS AND HALLWAYS.							
Irene Trujillo									
25018					7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 9:25:34 AM				
Castillo, Carlos		INSTALLATION OF ENFOCUS PROJECTOR IN THE NEW CONFERENCE ROOM. THIS WILL BE MOUNTED FROM CEILING. WE HAVE THE HARDWARE TO DO THIS PROJECT.							
Irene Trujillo									
25038		Restroom (Boys)			7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 3:39:38 PM				
Villalobos, David		PLUMBER NEEDED TO UNPLUG RESTROOM OUTSIDE OF BLDG BY PORTABLE. THIS IS A SECOND REQUEST.							
Irene Trujillo									
25039		Athletic Field			7/24/2007		8		\$0.00
Medium	Work In Progress				7/24/2007 3:41:45 PM				
Villalobos, David		THE DRINKING FOUNTAIN ON PLAYGROUND HAS BEEN BROKEN. NEEDS REPAIR. SECOND REQUEST							
Irene Trujillo									
25235					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:00:09 AM				
Ronquillo, Ruben		A SIGN IS NEEDED TO POST ON SCHOOL RESIDENT'S GATE. THE SIGN IS TO HAVE THE DISTRICT INSIGNIA AND READ PRIVATE PROPERTY - NO TRESPASSING.							
Irene Trujillo									
25127	Main Building				7/26/2007		6		\$0.00
Medium	Work In Progress				7/26/2007 3:24:02 PM				
Munoz, Michael		2nd request - Tile in nurse's office is not level. Safety hazard concern, as student/staff may possibly trip and be injured.							
Irene Trujillo									
<b>Count: 23 Work Orders</b>		<b>Avg. Age of WO's 18</b>			<b>Total for Sunland Park ES</b>			<b>0</b>	<b>\$0.00</b>

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunrise ES</b>									
25055		Athletic Field			7/24/2007		8		\$0.00
Medium	Work In Progress	outside			7/24/2007 4:44:23 PM				
Quinones, Paul		Need to secure the two trash cans on field so they do not blow over.							
Joanne Munoz									
25054		Office			7/24/2007		8		\$0.00
Medium	Work In Progress	supply closet			7/24/2007 4:42:31 PM				
Lozoya, Manny		Supply Closet door near the the cafeteria is not closing check this out							
Joanne Munoz									
25073					7/25/2007		7		\$0.00
Medium	Work In Progress				7/25/2007 12:34:44 PM				
Quinones, Paul		REPLACE CIRCULATING MOTOR TO UNIT IN CLASS RM.309 AND 4-J SLEEVE.							
Paul Quinones									
24875					7/18/2007		14		\$0.00
Medium	Work In Progress				7/18/2007 2:30:27 PM				
Ontiveros, Guadalupe		REQUESTING TO SCRAPE DIRT, AND SCREENING WERE PORTABLE WAS REMOVED ALONG FENCE LINE.							
Paul Quinones									
24830		Portables			7/17/2007		15		\$0.00
Medium	Work In Progress	Portables 5 & 7			7/17/2007 11:47:42 AM				
Quinones, Paul		Need to put up new bulletin board in the portables next to windows facing playground. Need done before students arrive.							
Joanne Munoz									
24832		Cafeteria			7/17/2007		15		\$0.00
Medium	Work In Progress	stage area			7/17/2007 12:07:26 PM				
Quinones, Paul		Need the cork board that was put on the stage wall to be put up a little higher where the blue line ends							
Joanne Munoz									
24667		Classroom			7/10/2007		22		\$0.00
Medium	Work In Progress	sever classrooms			7/10/2007 3:12:28 PM				
Quinones, Paul		Classrooms need to have dispensers replaced. Jesse head custodian has the list ready need for maint. to pick up list. and install.							
Joanne Munoz									
24666		Office			7/10/2007		22		\$0.00
Medium	Work In Progress	front handicap door			7/10/2007 3:10:07 PM				
Lozoya, Manny		Front door to school needs to be serviced door is jamming. This door is the one located entering the door for handicap entrance.							
Joanne Munoz									
24736					7/12/2007		20		\$0.00
Medium	Work In Progress				7/12/2007 3:02:48 PM				
Quinones, Paul		painting parking lanes speed bumps parking lot areas							
Paul Quinones									

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Sunrise ES</b>									
25256					7/31/2007		1		\$0.00
Medium	Work In Progress			7/31/2007 8:23:19 AM					
Flores, Larry	QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)								
Jesus Urquidi									
24414					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress			7/1/2007 12:15:56 AM					
Villalobos, David	Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24415					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress			7/1/2007 12:15:56 AM					
Villalobos, David	Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24549					7/1/2007	7/9/2007	31		\$0.00
Medium	Work In Progress			7/1/2007 12:16:48 AM					
Quinones, Paul	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Alfredo Holguin									
24550					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress			7/1/2007 12:16:48 AM					
Quinones, Paul	Yearly - Sunrise ES Exit Sign Test: Annual - Refer to PM schedule details.								
Alfredo Holguin									
24459					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress			7/1/2007 12:16:12 AM					
Orozco, Danny	Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details.								
Alfredo Holguin									
<b>Count: 15 Work Orders</b>		<b>Avg. Age of WO's 19</b>		<b>Total for Sunrise ES</b>			<b>0</b>	<b>\$0.00</b>	

# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Vado ES</b>									
24460					7/1/2007	7/22/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:16:12 AM				
Orozco, Danny		Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.							
Alfredo Holguin									
25257					7/31/2007		1		\$0.00
Medium	Work In Progress				7/31/2007 8:24:01 AM				
Flores, Larry		QUARTERLY BUILDING INSPECTION REPORT - NEED TO COMPLETE PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOUR OWN WORK AREA. INSPECTION REPORTS ALONG WITH THIS COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 15, 2007 (OR SOONER)							
Armando Diaz									
24360					7/1/2007	7/7/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:47 AM				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24361					7/1/2007	8/1/2007	31		\$0.00
Medium	Work In Progress				7/1/2007 12:15:47 AM				
Miranda, Danny		Yearly - Vado ES Exit Sign Test: Annual - Refer to PM schedule details.							
Alfredo Holguin									
25112		Cafeteria			7/26/2007		6		\$0.00
Medium	Work In Progress				7/26/2007 9:51:36 AM				
Orozco, Danny		Exhaust Fan is not working - (called Danny O. left msg. 7/26/07 at 9:50 a.m.)							
		Laura Benavidez - SNP Manager							
Alma Terrell									
24910					7/19/2007		13		\$0.00
Medium	Work In Progress				7/19/2007 10:46:46 AM				
Villalobos, Margret		PLEASE SPRAY FOR SPINDERS AND CRICKETS							
Frank Lara									
24972					7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 3:13:10 PM				
Lozoya, Manny		NEED 5 SETS OF EACH KEY (M4 AND 2) FOR FLASHING LIGHTS IN VADO. M4 IS DANNY MIRANDA ORIGINAL AND KEY 2 IS COUNTY.							
Carlos Vigil									
24634		Office			7/9/2007		23		\$0.00
Medium	Work In Progress				7/9/2007 3:02:27 PM				
Lozoya, Manny		NEED TO HAVE 2 KEYS MADE ONE FOR ROOM 205 AND 207							
Debra Facio									



# 366 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 7/31/2007 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Vado ES</b>									
25202					7/30/2007		2		\$0.00
Medium	Work In Progress				7/30/2007 1:05:48 PM				
Lozoya, Manny		RM. 202 SP. ED. NEED TO PUT SPECIAL TYPE OF DOOR KNOBE SO THREE YEAR OLD CHILD WILL NOT GET OUT							
Danny Miranda									
25130					7/26/2007		6		\$0.00
Medium	Work In Progress				7/26/2007 3:51:20 PM				
Gonzalez, Salvador		need to weld new brackets & rollers on front gates (see chava)							
Danny Miranda									
25167					7/27/2007		5		\$0.00
Medium	Work In Progress				7/27/2007 2:39:04 PM				
Ronquillo, Ruben		NEED TO REPAIR WINDOW ON FRONT LOBBY (LAM/TINTED)							
Danny Miranda									
25155					7/27/2007		5		\$0.00
Medium	Work In Progress				7/27/2007 8:23:24 AM				
Lozoya, Manny		NURSE OFFICE RESTROOM DOOR WILL NOT OPEN							
Danny Miranda									
24951					7/20/2007		12		\$0.00
Medium	Work In Progress				7/20/2007 8:49:03 AM				
Sotelo, Enrique		need weatherproof electrical covers for recepticals around out side of building							
Danny Miranda									
<b>Count: 13 Work Orders</b>			<b>Avg. Age of WO's 14</b>				<b>Total for Vado ES</b>	<b>0</b>	<b>\$0.00</b>
<b>Count: 366 Work Orders</b>			<b>Avg. Age of WO's 20</b>				<b>Grand Total</b>	<b>0</b>	<b>\$0.00</b>