

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Alma Del Valle Daycare

32043					2/29/2008		32		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/29/2008 2:31:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe joe as per our conversation, please move washer and drier and also stove and store at Lamesa.

Michael Munoz

32724					3/26/2008		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/26/2008 7:43:09 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny NEED TO PUT NEW DOOR KNOB ON DOOR TO INFANT ROOM WASHER AND DRYER AREA

Danny Miranda

32725					3/26/2008		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/26/2008 7:45:24 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Miranda, Danny NEED TO VARNISH NEW DOOR IN INFANTS WASHER AND DRYER AREA

Danny Miranda

Count: 3 Work Orders			Avg. Age of WO's	15		Total for Alma Del Valle Daycare	0		\$0.00
-----------------------------	--	--	-------------------------	-----------	--	---	----------	--	---------------

Location: Anthony ES

24365					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24366					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

25385	Main Building	Custodial			8/3/2007		242		\$0.00
-------	---------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/3/2007 11:57:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel repair weed eater

David Vega

26332	Main Building				8/28/2007		217		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/28/2007 7:45:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael Mild blg lounge replace counter top and make door for cabinet

Hector Villalobos

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Anthony ES
------------------	-------------------

26750	Cafeteria	Cafeteria			9/6/2007		208		\$0.00
-------	-----------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2007 12:38:20 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
As per Mr. Giovas, he was there at Anthony Elementary, water is leaking from the top and bottom pipes to the dishwashing machine.

Rebecca Saenz - SNP Manager 882-3507

Alma Terrell

27868	Main Building	Office			10/4/2007		180		\$0.00
-------	---------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/4/2007 11:04:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
WE WILL BE NEEDING TO CHANGE THE LOCK FOR THE SUPPLY ROOM IN THE MAIN AND PRIMARY BUILDING. WE WILL BE NEEDING 9 ADDITIONAL KEYS. IF YOU HAVE ANY QUESTIONS PLEASE FREE TO CONTACT ME.

Loraine Gandara

28350					10/19/2007		165		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress	Anthony On Track			10/19/2007 4:48:27 PM				
--------	------------------	------------------	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben
Blinds for windows (6) in office portable and in two classrooms.
4- 47 x 37
2- 33 x 62

Lucy Meza

28492	Dona Ana	Office			10/24/2007		160		\$0.00
-------	----------	--------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2007 3:14:21 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
Hector Villalobos
Need to charge locks for p.e and office

28563		Classroom			10/25/2007		159		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	Pre - K			10/25/2007 3:46:59 PM				
--------	------------------	---------	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben
Hector Villalobos
P.R.E.K headstart rooms 306 307 blinds 12 63x54

29108					11/9/2007		144		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/9/2007 11:14:13 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenz
Michael Munoz
Nurse Station - Install a package unit.

29151	Original Main	Classroom			11/13/2007		140		\$0.00
-------	---------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2007 9:07:01 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Loraine Gandara
WE NEED AN KEYS FOR ROOM 206 SPEECH ROOM...

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

29390	Chapter I	Classroom			11/26/2007		127		\$0.00
-------	-----------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/26/2007 8:21:25 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Chapter blg music room borken lock can not open							
Hector Villalobos									

29811		Portables			12/4/2007		119		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 3:02:11 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		PT219 need a key made for filing cabinet							
Hector Villalobos									

29812		Portables			12/4/2007		119		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 3:04:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Headstrat pt 1 need a keymade for filing cabinet							
Hector Villalobos									

29900					11/26/2007		127		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/7/2007 9:33:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael		NEW PLAYGROUND SHATE WAS CUT 3 TIMES.							
Hector Villalobos									

29903	Original Main	Office			12/7/2007		116		\$0.00
-------	---------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/7/2007 9:39:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Old main blg new office cabinet and filing cabinet need keys made							
---------------	--	---	--	--	--	--	--	--	--

Hector Villalobos									
-------------------	--	--	--	--	--	--	--	--	--

29930		Portables			12/10/2007		113		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/10/2007 10:27:27				
--------	------------------	--	--	--	---------------------	--	--	--	--

Solis, Lorenzø		pt 221 replace heater.							
Hector Villalobos									

30908					1/24/2008		68		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/24/2008 11:02:52 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Provide me with a list of individuals who have keys to the gates on this campus							
---------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

31029	Main Building	Classroom			1/29/2008		63		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/29/2008 2:32:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique		Replace brun out lamps and ballast in milg blg							
-----------------	--	--	--	--	--	--	--	--	--

Hector Villalobos									
-------------------	--	--	--	--	--	--	--	--	--

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

31463		Athletic Field			2/11/2008		50		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

High	Work In Progress				2/11/2008 11:27:42 AM				
------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Hector
Barbwire supports for fencing will be ordered (35).
Please install when they are in. Norht fence by
apartments.
thxs

Michael Munoz

31465					2/11/2008		50		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				2/11/2008 11:35:19 AM				
------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Hector
warehouse will be purchasing no trespassing signs(15)
please install on north of campus by apt.
thxs

Michael Munoz

31589		Portables			2/14/2008		47		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/14/2008 9:10:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben
Broken windows portable (221 & 203) Parenting Lab
Headstart size 42 3/4 x14 1/2
(PT 3 & \$ Stolen computer, radio, 3 box of meat)
(Parenting Lab- Computer)
CASE# 2008-01608 Ben Casillas

Hector Villalobos

31650	Main Building	Hallway/Corridor			2/19/2008		42		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/19/2008 7:18:12 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Hector Villalobos
break in milg blg need to order new panic bars 6

31976		Classroom			2/28/2008		33		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/28/2008 8:22:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Margret
rooms 306,307,308,309,310 need to be sprayed for
bugs at request of pre k ,coordinator

David Vega

32408	Nurse Building	Office			3/10/2008		22		\$0.00
-------	----------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 7:53:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Enrique Sotelo
Need to connect refrigeration unit.

32432					3/10/2008		22		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 1:35:08 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Hector
Upper primary P.K.E morgan blg made a ramp for
storage

Hector Villalobos

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Anthony ES							
32700	Drug Free Bldg.				3/25/2008		7		\$0.00
Medium	Work In Progress				3/25/2008 2:52:32 PM				
Sotelo, Enrique		Only half of the bldg has power.							
David Vega									
32702	Original Main	Classroom			3/25/2008		7		\$0.00
Medium	Work In Progress				3/25/2008 3:07:32 PM				
Lozoya, Manny		NEED TWO ADDITIONAL KEYS FOR RM 201.. KEY H14...							
Loraine Gandara									
32773	Office	Custodial			3/27/2008		5		\$0.00
Medium	Work In Progress				3/27/2008 10:02:53 AM				
Lozoya, Manny		NEED A SET OF KA KEYS FOR CUSTODIANS...							
Loraine Gandara									
32839	Original Main	Hallway/Corridor			3/31/2008		1		\$0.00
Medium	Work In Progress				3/31/2008 9:16:27 AM				
Appelzoller, Fred		old main hallway water fountain is leaking inside wall							
Hector Villalobos									
32840	Annex Building	Office			3/31/2008		1		\$0.00
Medium	Work In Progress				3/31/2008 9:18:37 AM				
Lozoya, Manny		room 206 needs 3 keys k47							
Hector Villalobos									
32869		Portables			4/1/2008		0		\$0.00
Medium	Work In Progress				4/1/2008 9:00:52 AM				
Ronquillo, Ruben		Pt 1 broken window 22 1/2 X 34 1/3 (DEP. S. BAYLES 649 CASE# 2008-02673)							
Hector Villalobos									
Count: 32 Work Orders		Avg. Age of WO's		103	Total for Anthony ES			0	\$0.00

Location:		Berino ES							
24367					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:48 AM				
Villalobos, David		Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24368					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:48 AM				
Villalobos, David		Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

24369					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24370					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

26824	Main Building	Gym			9/10/2007		204		\$0.00
-------	---------------	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	5058822242			9/10/2007 6:54:35 AM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Lozoya, Manny LOCK TO HATCH TO ROOF WAS BROKEN OFF DURING THE BREAK IN NEEDS TO BE REPLACED

Jimmy Cortez

28572		Cafeteria			10/26/2007		158		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/26/2007 8:57:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny Having problems with Dishwasher - Tom/Ecolab checked the DW-his recommendation: repair or replace the vacuum breaker and repair or replace the solenoid valve for the final rinse.

Aida Salcedo - SNP Coord. 882-6772 and Elsa Chairez - SNP Manager 882-2417

Alma Terrell

29029					11/7/2007		146		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/7/2007 9:26:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny BROKEN FLOOR TILES THROUGHOUT FACILITY - REPEAT VIOLATION FROM ENVIRONMENT INSPECTION DEPARTMENT.

AIDA SALCEDO - SNP COMPLIANCE COORDINATOR
882-6772
ELSA CHAIREZ - SNP MANAGER - 882-2417

Alma Terrell

30165					12/18/2007		105		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/18/2007 7:53:56 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenzo ONE OF THE BOILERS NEEDS TO BE CHECK OUT NOT WORKING

Ramiro Holguin

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

30295					1/6/2008	1/27/2008	86		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

30670					1/16/2008		76		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/16/2008 7:23:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenz BOILERS NOT WORKING RIGHT TEMPEURE IN WATER TO LOW NEEDS TO BE CHECK OUT. CLASS ROOMS ARE COLD

Ramiro Holguin

30777	Main Building	Hallway/Corridor			1/18/2008		74		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/18/2008 9:17:54 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan TILES NEED TO BE EXCHANGED CRACKED IN MAIN HALL AND ENTRANCE AS PER JESUS ESTRADA - ROUTE TO BUILDING MECHANIC

Jimmy Cortez

30778		Restroom (Boys)			1/18/2008		74		\$0.00
-------	--	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/18/2008 9:29:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan BASEBOARDS NEEDS TO BE REPLACED IN ALL 8 SMALL RESTROOMS BOYS AND GIRLS IN CLASSROOMS 100 101 105 104 AS PER JESUS ESTRADA - ROUTE TO BLDG MECH.

Jimmy Cortez

30827					1/22/2008		70		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/22/2008 10:01:06 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Holguin, Ramiro Portable 157 - Window was left open and they went in and stole the overhead projector. (Case# 2008-00879) est loss 150.00

Maribel Chavez

31053	Main Building	Library			1/30/2008		62		\$0.00
-------	---------------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/30/2008 10:40:38 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Library - Door knob is coming loose.

Adan Duran

31054		Portables			1/30/2008		62		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/30/2008 10:41:13 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Portable 158- Door knob is coming loose.

Adan Duran

31055	Main Building	Restroom (Boys)			1/30/2008		62		\$0.00
-------	---------------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/30/2008 10:42:13 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Joe Kinder Classroom (Boys RR) - Need a bowl wax.

Adan Duran

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

31607					2/14/2008		47		\$0.00
Medium	Work In Progress				2/14/2008 3:20:46 PM				
Moncayo, Fernando		MR JOSE AMBRIZ SIR THE EXHUAST FAN UPPER GRADE BATHROOM HAS A BURN OUT MORTOR WE NEED TO REPLACE IT 1/4 HP THANK YOU SIR AND GOD BLESS							

Adan Duran

31633					2/15/2008		46		\$0.00
Medium	Work In Progress				2/15/2008 2:59:37 PM				
Moncayo, Fernando		MR JOSE AMBRIZ SIR EXHUAST FAN ROOM 100 MOTOR IS NOT WORKING NEED TO REPLACE THANK YOU SIR AND GOD BLESS							

Adan Duran

31706					2/20/2008		41		\$0.00
Medium	Work In Progress				2/20/2008 3:12:15 PM				
Ontiveros, Guadalupe		MR LUPE ONTIVEROS SIR THE IRRIGATION TIMER IN FRONT IS NOT WORKING ALL IRRIGATION HAS TO BE DONE BY HAND THE IRRIGATION BOX NAME IS IRRI-TROL HAVE BEEN TOLD BY MR HOLGIN THAT IT HAS NOT WORKED OVER A YEAR WOULD YOU HAVE SOME ONE LOOK AT IT PLEASE THANK YOU SIR AND GOD BLESS							

Adan Duran

31709					2/20/2008		41		\$0.00
Medium	Work In Progress				2/20/2008 3:20:49 PM				
Ontiveros, Guadalupe		MR LUPE ONTIVEROS SIR WE HAVE A LOT OF ROCK ON THE PLAYGROUND THAT WAS PUT ON WITH SOME FILL DIRT MR VALTIERRA WOULD LIKE ALL THAT ROCK REMOVE AND SOME CLEAN FILL DIRT SPREAD ON FIELD THANK YOU SIR AND GOD BLESS							

Adan Duran

31940					2/27/2008		34		\$0.00
Medium	Work In Progress				2/27/2008 3:09:06 PM				
Lozoya, Manny		MR MANNY LOZOYA SIR THE DOOR HANDLE IN THE LIBRARY IS VERY LOSE THE TUMBLER IS ALSO LOSE ALSO PORTABLE 158 THE HANDLE IS ALSO LOSE THEY NEED TO BE LOOK AT THANK YOU SIR AND GOD BLESS							

Adan Duran

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

31970	Main Building	Classroom			2/28/2008		33		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Special ED Room			2/28/2008 8:05:37 AM				
--------	------------------	-----------------	--	--	----------------------	--	--	--	--

Villalobos, Margret
 MR MIKE MUNOZ THE HAVE INFORM ME THAT
 THERE IS A BUG PROBLEM IN ROOM 113 I WENT
 TO CHECK IT OUT AND THERE A LOT OF ROCHES
 IN THE BATHROOM ON THE TOOTH BRUSHES ECT
 ALONG THE BASE BOARD THIS IS THE SPECIAL ED
 ROOM COULD YOU SENT SOME TO SPRAY THANK
 YOU SIR AND GOD BLESS

Adan Duran

31972					2/28/2008		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/28/2008 8:10:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
 MR ENRIQUE SOLTERO MI BROTHER KIKI EL
 SWITCH EN EL QUARTO 115 ESTA QUEBRDO ES EL
 SWITCH DEL EXHUAST Y EL SWITCH DEL EXHUST
 EN EL TECHO TABIEN GRACIAS Y DIOS LO
 VENDIGA

Adan Duran

32003					2/28/2008		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/28/2008 3:12:46 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose
 MR JOSE AMBRIZ SIR THE BOILER ON THE RIGHT
 SIDE THE ONE MR SOLIS CHANGE THE CONTROL
 IS MAKING A LOT OF NOISE BAD ITS HAMMERING
 SOMETHING IS NOT RIGHT WILL NEED TO CHECK
 OUT THANK YOU SIR AND GOD BLESS

Adan Duran

32396					3/7/2008		25		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/7/2008 3:32:19 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Sotelo, Enrique
 MR ENRIQUE SOTELO LAS EMERGENCE LIGHT EN
 EL WEST SIDE GIRLS BATHROOM Y LOS MEN
 NESISITAN BATTERIES Y EL STORAGE EN LA
 CAFETERIA THANK YOU SIR

Adan Duran

32400					3/7/2008		25		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/7/2008 3:39:28 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Sotelo, Enrique
 MR ENREQUE SOTELO EL SWITCH EN EL TECHO
 DEL EXHUAST FAN NESESTE COMBIER NO GOOD
 DEL BANO WEST SIDE THANK YOU SIR

Adan Duran

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

32483 3/11/2008 21 \$0.00

Medium Work In Progress 3/11/2008 3:32:51 PM

Sotelo, Enrique MR SOTELO MR CORTEZ ME INFORMO QUE LOS PORTABLES PA EL EAST SON 5 LAS LUZES NO ESTAN PRENDIDO ESTA MUY ESCUQURO DARK EN LAS NOCHES THANK YOU SIR

Adan Duran

32523 3/12/2008 20 \$0.00

Medium Work In Progress 3/12/2008 3:25:02 PM

Castillo, Carlos MR ENREQUE SOTELO SENOR SOTELO LA LUZ EN EL POSTE ESTA QUEBRIDA EL PLASTIC COVER TAMBIEN POR FAVOR QUENDO PUEDA CHECK IT PLEASE ESTA EN LOS PORTABLES THANK YOU SIR

Adan Duran

32668 3/19/2008 13 \$0.00

Medium Work In Progress 3/19/2008 2:03:07 PM

Sanchez, Raul MR RAUL SANCHEZ SIR THE ELBOW UNDER FILTER IS LEAKING NEED TO CHANGE OUT ASAP CLOSE MAIN VALVE OPEN BY PASS THANK YOU SIR AND GOD BLESS

Adan Duran

32720 Main Building 3/25/2008 7 \$0.00

Medium Work In Progress 3/25/2008 3:59:56 PM

Sotelo, Enrique Need batteries (Emer. Lights asp PM32088) for Westside Girls RR, Mens RR and Storage Room Restroom.

Adan Duran

32898 Portables 3/31/2008 1 \$0.00

Medium Work In Progress 4/1/2008 4:09:33 PM

Ontiveros, Guadalupe BROKEN SPRINKLERS ABOUT 12 HEADS ALL BROKEN. (OFFICER APODACA 880 CASE# 2008-03-124)

Adan Duran

Count: 31 Work Orders Avg. Age of WO's 87 Total for Berino ES 0 \$0.00

Location: Chaparral ES

24376 7/1/2007 8/1/2007 275 \$0.00

Medium Work In Progress 7/1/2007 12:15:50 AM

Villalobos, David Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

24377					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:50 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

26649		Portables			9/4/2007		210		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	p-3			9/4/2007 8:25:13 AM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Lozoya, Manny need another key to portable 3 for pre kinder classes for new clerk. See Judy Atkins

Jennifer Corral

26931		Classroom			9/12/2007		202		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	512			9/12/2007 10:40:56 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lozoya, Manny teacher is requesting another key for room. There are now two teachers in that room. See Ms. Adina

Jennifer Corral

26976					9/13/2007		201		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/13/2007 6:57:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny 9/13/07 fire proof file cabinet in principals' office needs to be re-keyed.

Joe Ramirez

27215					9/20/2007		194		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/20/2007 8:32:42 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Briones, Enrique 9/20/07.
we need discarded furn. and equip. to be picked up by the purch. wrhse. turn in sheets are available.

Joe Ramirez

28241					10/17/2007		167		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/17/2007 3:45:12 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny (Chaparral Elementary): (Ms. Vasquez, Room #414):
Door to classroom is fallen. Door is hard to close. Need to re-weld top hinge of frame. Also, need to weld door closure to top of metal frame.

Johnny Acuna

28503					10/24/2007		160		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2007 3:51:34 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Michael Mike Muñoz: Need a double gate installed on the east side of fence area (Where the Trees are). Pre-K portable at Chaparral Elementary.

Johnny Acuna

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

29796					12/4/2007		119		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 10:54:27 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Joe
Chaparral Elementary: Portable 2 / Pre-K. Water faucet to sink is leaking. Need a new gasket in the cold water side of the valve.

Johnny Acuna

29828					12/4/2007		119		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 4:00:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Need a pad lock for Blue box inside the irrigation system area.
Pad Lock (N-53)

Johnny Acuna

29916					12/7/2007		116		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/7/2007 2:39:27 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Need to re-weld rebar back on to the Roof top Ladder and re-enforce all other bars. Main building: Metal Ladder on top of Roof: Cafeteria Section.

Johnny Acuna

29917					12/7/2007		116		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/7/2007 2:42:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Chaparral Elementary Rooftop: Need to Make and install Metal ladder and frame to main building wall to be able to go up from the kitchen rooftop to cafeteria rooftop.

Johnny Acuna

30154					12/17/2007		106		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/17/2007 3:36:14 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Chaparral Elementary School Principal: Mrs. Ballard is requesting a lock for the Fire Proof Filing Cabinet.

Johnny Acuna

30577		Classroom			1/14/2008		78		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	101			1/14/2008 7:51:37 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny
need key for cabinet, teacher misplaced cabinet key and cannot open it. See Ms. Ledesma

Jennifer Corral

30721	2001 Classroom	Classroom			1/17/2008		75		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	220			1/17/2008 9:19:23 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny
Chaparral Elementary: (Emergency Health Issue)- Need to replace Restroom Door Knob to Room #220 in the New Wing Area. Students remove loose handle and dump it in the toilet.

Johnny Acuna

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

30897					1/24/2008		68		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/24/2008 8:22:20 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Sink to kitchen area is cracked. (Where pots and pans are washed)

Johnny Acuna

30977		Custodial			1/28/2008		64		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	office			1/28/2008 1:48:11 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Lozoya, Manny need extra master keys for head custodian/ please see front office. as soon as possible

Jennifer Corral

31652					2/19/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/19/2008 8:43:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny need replace doors on barracas 416 414-412- 410 408 406 506 501

Juan Vargas

31736					2/21/2008		40		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/21/2008 10:18:41 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Gonzales, Angel need replace star switch the kaybroke inside swich truck # 155

Juan Vargas

32038					2/29/2008		32		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/29/2008 12:53:16 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Joe need fix 3/4 copper pipe is broken on behind barrack 416

Juan Vargas

32127					3/2/2008	3/10/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:14 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

32130					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan Monthly - Chaparral ES A-1 Semiannual EVD - Refer to PM schedule details.

Margret Villalobos

32131					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan Monthly - Chaparral ES A-1 Semiannual EVD - Refer to PM schedule details.

Margret Villalobos

4/1/2008 6:24:36 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

32132					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan		Monthly - Chaparral ES A-1 Semiannual EVD - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32133					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan		Monthly - Chaparral ES A-1 Semiannual EVD - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32134					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:16 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan		Monthly - Chaparral ES C-6 Quarterly HP - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32135					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:16 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan		Monthly - Chaparral ES A-8 Quarterly HPW Unit - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32136					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:16 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan		Monthly - Chaparral ES A-2 Quarterly H/C IREH - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32137					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan		Monthly - Chaparral ES A-1 Semiannual MCD - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32138					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan		Monthly - Chaparral ES A-5 Quarterly SS - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32170					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:31 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan		Monthly - Chaparral ES A-1 Semiannual EVS - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

32184					3/2/2008		30		\$0.00
Medium	Work In Progress				3/2/2008 12:33:37 AM				
Jacquez, Ricardo		Monthly - Chaparral ES-Wastewater Weed Control - Refer to PMSchedule details.							
Margret Villalobos									

32750					3/26/2008		6		\$0.00
Medium	Work In Progress				3/26/2008 3:45:03 PM				
Ambriz, Jose		need replace water fonting on lobby area have leck water tank							
Juan Vargas									

Count: 33 Work Orders Avg. Age of WO's 92 Total for Chaparral ES 0 \$0.00

Location: Chaparral HS

24434					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:59 AM				
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PMSchedule details.							
Alfredo Holguin									

24435					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:59 AM				
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PMSchedule details.							
Alfredo Holguin									

24436					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:16:00 AM				
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PMSchedule details.							
Alfredo Holguin									

26036					8/20/2007		225		\$0.00
Medium	Work In Progress				8/20/2007 1:18:09 PM				
Boyd, David		WARRANTY WO. D-WING COMPUTER RM. CHANGE STORE RM. LOCK TO CLASS RM.LOCK							
Eddie Baeza									

26038					8/20/2007		225		\$0.00
Medium	Work In Progress				8/20/2007 1:24:09 PM				
Boyd, David		WARRANTY WO. (7) MULLENS ON EXTERIOR DOORS MISSING PLATES,ADJUST CYL. SO CORE CAN BE IN LOCKED POSITION.							
Eddie Baeza									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

26039					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:26:06 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		WARRANTY WO. NEED CRANK FOR ROLL UP CURTAIN AT THE CONCESSION STAND.							
-------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

26040					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:29:14 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		WARRANTY WO. TRANSITION STRIPS IN KITCHEN FLOORS ARE COMING LOOSE.							
-------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

26041					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:32:07 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		WARRANTY WO. E-WING COMPUTER LAB HOLE IN WALL UNDER BULLETIN BOARD.							
-------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

26043					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:36:10 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		WARRANTY WO. VENT UNCOVERED IN CEILING. UNFINISHED HOLE IN WALL COUNCELORS OFFICE. (BARNETT)							
-------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

26045					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:38:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		WARRANTY WO PAPER LEFT IN LIGHT FIXTURE IN COUNCELORS OFFICE.							
-------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

26046					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:45:56 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		WARRANTY WO. F-WING COMPUTER LAB 2 HOLES IN WALL NEXT TO TV STAND, HOLES NEAR OUTLETS, MISSING PAINT BETWEEN GLASS BLOCKS, CEILING TILES MISSING.							
-------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

26047					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:49:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		WARRANTY WO. RM. D-1 WALL OUTLET NOT COMPLETED, STAIN ON CEILING TILE, CEILING TILES MISSING.							
-------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

26048					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:51:57 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. BAND RM. OUTLETS HAVE NOT BEEN COVERED AND WIRES ARE STICKING OUT.

Eddie Baeza

26049					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:54:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. CEILING TILES MISSING THRU OUT CAMPUS.

Eddie Baeza

26050					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:56:27 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRAFNTY WO. RMB-6 CHIPPED PAINT ON A/C VENT.

Eddie Baeza

26051					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:59:36 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. RM. C-3 DOOR ON STORAGE CABINET CANNOT OPEN ALL THE WAY DUE TO T-STAT COVER.

Eddie Baeza

26052					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 2:04:24 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. RM. F-7 WATER STAINS ON CEILING TILES.

Eddie Baeza

26053					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 2:07:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. LIBRARY CONFERENCE RM. JHOLE IN NORTH WALL. ELECTRICAL OUTLETS DO NOT WORK.

Eddie Baeza

26054					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 2:11:34 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. B-SPED NEED HOOK UP FOR WASHER, NEED HOOK UP DRIER.NEED HOOKUP FOR STOVE. HOOK UP FOR DISHWASHER.

Eddie Baeza

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

26055					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 2:13:14 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		WARRANTY WO. WEST SCORE BOARD IN GYM NOT WORKING.							
-------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

26056					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 2:16:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		WARRANTY WO. BLEACHERS IN GYM NEED TO HAVE 120 VOLT, AND PARARECEPTALS AT THE BLEACHERS							
-------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

26057					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 2:22:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		WARRANTY WO FIRE PUMP NEEDS TO BE PROGRAMMED SO THAT IT WILL SHUT OFF AUTOMATICALLY. ALSO EVERY TIME IT STARTS IT CALLS THE FIRE DEPT.							
-------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

26821					9/7/2007		207		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress	BAND ROOM			9/7/2007 4:31:33 PM				
--------	------------------	-----------	--	--	---------------------	--	--	--	--

Lozoya, Manny		RESTROOMS - LOCKS SHOULD BE CHANGED BECAUSE STUDENTS CAN LOCK THE DOOR FROM THE INSIDE AND IT SHOULDN'T BE THE CASE. GIRLS DOOR WON'T LOCK EITHER. ALSO, THE BATHROOM NEEDS BOYS AND GIRLS SIGNS POSTED ONT THE DOORS							
---------------	--	---	--	--	--	--	--	--	--

Rosa Quezada

26822					9/7/2007		207		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress	OUTSIDE HOSE			9/7/2007 4:33:14 PM				
--------	------------------	--------------	--	--	---------------------	--	--	--	--

Lozoya, Manny		NEED 8 KEYS FOR OUTSIDE HOSE BIBS, AS PER EDDIE BAEZA							
---------------	--	---	--	--	--	--	--	--	--

Rosa Quezada

26941					9/12/2007		202		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	gym			9/12/2007 2:15:46 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny		please rekey the ch1 key to a ch86 to fit the custodial door on the northwest end of the gym.							
---------------	--	---	--	--	--	--	--	--	--

Rosa Quezada

26943	B-Wing				9/12/2007		202		\$0.00
-------	--------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	B-2			9/12/2007 2:26:44 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny		COACH YTURRALDE NEEDS A KEY (CH32) TO ACCESS WASHER AND DRYER FOR FOOTBALL							
---------------	--	--	--	--	--	--	--	--	--

Rosa Quezada

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

26964	C-Wing				9/12/2007		202		\$0.00
-------	--------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	sped room			9/12/2007 3:55:48 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Lozoya, Manny
need ch32 to open door - need two keys - one for teacher and one for spare

Rosa Quezada

26965		Gym			9/12/2007		202		\$0.00
-------	--	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	gym			9/12/2007 3:57:05 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny
need 4 keys off the GM1 master for coaches, Nougues, Yturralde, and Ulibarri and one for spare

Rosa Quezada

26967	C-Wing	Classroom			9/12/2007		202		\$0.00
-------	--------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	sped - c wing			9/12/2007 3:59:24 PM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
please change order # 26964 previously entered to ch45 (2 keys) instead of ch32 - my mistake

Rosa Quezada

27410					9/25/2007		189		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/25/2007 2:10:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
Chaparral High School: Requesting Lobo Lane Fenceline be treated with arsenal and round up. Need motorized sprayer to spray on fenceline. All weeds are cut and raked. Thank You...

Johnny Acuna

28047					10/11/2007		173		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/11/2007 9:53:40 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Margret
AN EXTERMINATOR IS REQUESTED FOR PEST IN ROOM C-6.

Eddie Baeza

28146		Custodial			10/15/2007		169		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/15/2007 3:16:11 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Need a set of tools and drill motor for various jobs that
pop up ON HOLD AS PER CHUY

Arthur Contreras

28271					10/18/2007		166		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/18/2007 1:50:07 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Margret
AN EXTERMINATOR IS REQUESTED TO GET RID OF RODENTS.

Eddie Baeza

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Chaparral HS

28641					10/30/2007		154		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/30/2007 7:46:46 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Boyd, David		#1 UNIT IN THE CAFETERIA IS TRIPPING THE CONTROL TRANSFORMER SEEMS LIKE A DIRECT SHORT							
-------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

28837	C-Wing				11/2/2007		151		\$0.00
-------	--------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	c-4			11/2/2007 2:27:46 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny		NEED A SET OF D156AR KEYS (CABINET) FOR HALLEY WOODS AT C-4							
---------------	--	---	--	--	--	--	--	--	--

Rosa Quezada

29166		Cafeteria			11/13/2007		140		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2007 1:26:01 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Margret		BAD ANT PROBLEM BY THE TRAY ROOM JUANA MONTELONGO - SNP MANAGER 824-4461							
---------------------	--	---	--	--	--	--	--	--	--

Alma Terrell

29213					11/14/2007		139		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/14/2007 11:07:12				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny		STORAGE RM IN THE CAREER CENTER NEEDS TO BE REKEYED OFF MASTER, AND 4 KEYS ARE NEEDED							
---------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

29691					12/2/2007	12/23/2007	121		\$0.00
-------	--	--	--	--	-----------	------------	-----	--	--------

Medium	Work In Progress				12/2/2007 12:30:23 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny		Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

29748					12/3/2007		120		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/3/2007 2:28:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		POWER NEEDS TO BE SUPPLIED TO BLEACHERS, AND PA SYSTEM							
-------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

29749					12/3/2007		120		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/3/2007 2:30:00 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		FIRE BLOCK DOORS IN THE MAIN CORRIDOR NEEDS LOCKSETS INSTALLED							
---------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

29806					12/4/2007		119		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 2:47:41 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny (1) CH-7 AND (1) CH-3 KEYS ARE REQUESTED FOR NURSE HIGGS IN THE HEALTH CENTER

Eddie Baeza

29858					12/6/2007		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				12/6/2007 7:52:44 AM	12/6/2007			
--------	------------------	--	--	--	----------------------	-----------	--	--	--

Lozoya, Manny Can we get a key to the gate for the compactor at Chaparral High School. Please let me know when the key is ready and I will go by and pick it up.

Juliet Parra

29953		Gym			12/10/2007		113		\$0.00
-------	--	-----	--	--	------------	--	-----	--	--------

Medium	Work In Progress	GYM			12/10/2007 3:38:16 PM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lozoya, Manny NEED A KEY TO RETRACT THE SIDE BASKETS IN THE GYM (F.SANCHEZ)

Rosa Quezada

29954		Classroom			12/10/2007		113		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	SECRETARY			12/10/2007 3:39:28 PM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Lozoya, Manny NEED A WA (LIFT STATION GATE KEY)

Rosa Quezada

30137	A-Wing				12/17/2007		106		\$0.00
-------	--------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress	RECEPTIONIST			12/17/2007 10:23:58				
--------	------------------	--------------	--	--	---------------------	--	--	--	--

Lozoya, Manny NEED COPIES OF D-264AR FOR CABINETS BEHIND RECEPTIONIST DESK (M.MEZA)

Rosa Quezada

30138		Gym			12/17/2007		106		\$0.00
-------	--	-----	--	--	------------	--	-----	--	--------

Medium	Work In Progress	OFFICE			12/17/2007 10:25:42				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Lozoya, Manny NEED A KEY FOR CABINET IN P.E. OFFICE FOR COACH YTURRALDE A.S.A.P.

Rosa Quezada

30485		Office			1/10/2008		82		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	MAINTENANCE			1/10/2008 2:19:49 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Lozoya, Manny NEED A C-T KEY FOR EDDIE BAEZA (MAINTENANCE) TO ACCESS ROOF HATCH AND A/C UNITS

Rosa Quezada

30728	E-Wing	Classroom			1/17/2008		75		\$0.00
-------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	E-7			1/17/2008 10:48:11 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lozoya, Manny LOCK ON TALL CABINET IN BACK OF CLASSROOM FELL OUT. NEEDS TO BE REPAIRED (SAVOIE)

Rosa Quezada

4/1/2008 6:24:36 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

30729	D-Wing	Classroom			1/17/2008		75		\$0.00
-------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	D-4			1/17/2008 10:50:47 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lozoya, Manny		CABINET KEYS GET STUCK - UNABLE TO LOCK)							
---------------	--	--	--	--	--	--	--	--	--

Rosa Quezada									
--------------	--	--	--	--	--	--	--	--	--

30732		Classroom			1/17/2008		75		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	E-7			1/17/2008 10:54:33 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lozoya, Manny		NEED KEY# RD025 TO OPEN CABINETS (SAVOIE)							
---------------	--	---	--	--	--	--	--	--	--

Rosa Quezada									
--------------	--	--	--	--	--	--	--	--	--

30805		Gym			1/18/2008		74		\$0.00
-------	--	-----	--	--	-----------	--	----	--	--------

High	Work In Progress				1/18/2008 3:26:09 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Baeza, Eddie		6 breakaway goals where purchasaed for courts. 2 have been installed, please install the remaining 4 and return to the physical plant. THXS							
--------------	--	--	--	--	--	--	--	--	--

Michael Munoz									
---------------	--	--	--	--	--	--	--	--	--

31011	E-Wing	Classroom			1/29/2008		63		\$0.00
-------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	E-3			1/29/2008 9:17:45 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny		NEED A CH-12 TO OPEN THE WEIGHTLIFTING ROOM FOR HIS CLASS (DIOSDADO)							
---------------	--	--	--	--	--	--	--	--	--

Rosa Quezada									
--------------	--	--	--	--	--	--	--	--	--

31050		Cafeteria			1/30/2008		62		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Kitchen			1/30/2008 8:50:54 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Baeza, Eddie		As per Pest Control need to redo door kitchen entry from exterior 1/2 - 1in cap under door.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

31167					2/1/2008		60		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/1/2008 10:18:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		A CH-1 CORE IS REQUESTED FOR THE ROOF HATCH AAT THE B-WING.							
---------------	--	---	--	--	--	--	--	--	--

Eddie Baeza									
-------------	--	--	--	--	--	--	--	--	--

31417		Office			2/7/2008		54		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	TROPHY CASES			2/7/2008 6:50:49 PM				
--------	------------------	--------------	--	--	---------------------	--	--	--	--

Lozoya, Manny		NEED SIX LOCKS FOR TROPHY CASES AND TWO LOCKS FOR DISPLAY CASES (QUEZADA)							
---------------	--	---	--	--	--	--	--	--	--

Rosa Quezada									
--------------	--	--	--	--	--	--	--	--	--

31459					2/11/2008		50		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/11/2008 10:52:30 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		42 FLOOR DOOR STOPS ARE REQUESTED FOR CLASS RM. DOORS.(PURCHASE THROUGH RAWSON)							
---------------	--	--	--	--	--	--	--	--	--

Eddie Baeza									
-------------	--	--	--	--	--	--	--	--	--

4/1/2008 6:24:36 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

31540					2/12/2008		49		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/12/2008 3:47:46 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Baeza, Eddie		2-7-08				2/7 - 8			
--------------	--	--------	--	--	--	---------	--	--	--

2 HRS CHECK SYSTEMS
4 HRS INSTALL BULLETIN BOARDS IN CONF. RM.
2 HRS ASSIST CONTRACTORS

Eddie Baeza

31686					2/20/2008		41		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/20/2008 9:53:02 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		A DOOR BELL IS REQUESTED FOR THE RECEIVING DOOR AT THE KITCHEN.							
---------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

31858					2/26/2008		35		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/26/2008 7:50:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		STORAGE DOOR AT THE GIRLS LOCKER RM. CANNOT BE OPENED. SEEMS LIKE LATCH IS NOT ENGAGING.							
---------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

31973		Classroom			2/28/2008		33		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C WING			2/28/2008 8:15:46 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Lozoya, Manny		lock on the bathroom door keeps getting stuck. the lock turns, but the handle doesn't move. (fernandez)							
---------------	--	---	--	--	--	--	--	--	--

Rosa Quezada

31975					2/28/2008		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	GIRLS LOCKER			2/28/2008 8:20:15 AM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Lozoya, Manny		PLEASE RE-KEY DOOR THAT SEPARATES DOORS BETWEEN GIRLS LOCKER ROOM. NEEDS TO BE KEY ENTRY ON BOTH SIDES. (NOUGUES)							
---------------	--	---	--	--	--	--	--	--	--

Rosa Quezada

31984	E-Wing	Classroom			2/28/2008		33		\$0.00
-------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	E-7			2/28/2008 8:34:23 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny		NEED KEYS TO LOCK AND UNLOCK CABINETS IN SOTRE ROOM. THE STAMP CODE IS RD025. (SAVOIE) 2ND REQUEST							
---------------	--	--	--	--	--	--	--	--	--

Rosa Quezada

31999					2/28/2008		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/28/2008 2:05:36 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		LOCKSETS ARE REQUESTED FOR THE GREENHOUSES. CONTRACTORS WILL NOT BE CHANGING THEM OUT.							
---------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

32032		Custodial			2/29/2008		32		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/29/2008 11:11:36 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Estrada, Jesus
Arthur Contreras
I need 4 gallons of vinegar for the tile floors

32189					3/2/2008	3/23/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:39 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
Margret Villalobos
Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details.

32191					3/2/2008	3/23/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:40 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
Margret Villalobos
Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.

32316					3/5/2008		27		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/5/2008 3:55:03 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny
Eddie Baeza
TEACHERS ARE HAVING PROBLEMS UNLOCKING AND LOCKING STAFF RESTROOMS IN THE C & E WINGS. MS BALLARD WANTS ALL STAFF REST RMS CHECKED

32384					3/7/2008		25		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

High	Work In Progress				3/7/2008 1:12:14 PM				
------	------------------	--	--	--	---------------------	--	--	--	--

Contreras, Arthur
Jesus Estrada
Pick up trash around fence line and entrance east side is the worst.

32440					3/10/2008		22		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 3:02:25 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Eddie Baeza
ELECTRICAL CIRCUITS ARE REQUESTED FOR THE GAURD SHACK AT MAIN ENTRANCE

32493	C-Wing				3/11/2008		21		\$0.00
-------	--------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-COMPUTER			3/11/2008 3:47:14 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Rosa Quezada
NEED SIX COPIES OF PORT A POTTY KEY #3172 (ROSA HAS A KEY)

32537					3/13/2008		19		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/13/2008 8:54:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David
Eddie Baeza
LOCHINVAR BOILERS ARE KICKING OFF ON LOW AIR PRESSURE

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
32538					3/13/2008		19		\$0.00
Medium	Work In Progress				3/13/2008 9:02:26 AM				
Boyd, David		DOMESTIC WATER PUMPS ARE GOING INTO ALARM ON HIGH DISCHARGE PRESSURE							
Eddie Baeza									
32540					3/13/2008		19		\$0.00
Medium	Work In Progress				3/13/2008 9:04:40 AM				
Boyd, David		DOOR CLOSER IN THE CONCESSION STAND HAS FALLEN OFF.							
Eddie Baeza									
32541					3/13/2008		19		\$0.00
Medium	Work In Progress				3/13/2008 9:06:13 AM				
Boyd, David		START UP OF HEATING AND COOLING UNITS AT THE GREENHOUSES, NEEDS TO BE PERFORMED AND CHECKED FOR PROPER PERFORMANCE.							
Eddie Baeza									
32542					3/13/2008		19		\$0.00
Medium	Work In Progress				3/13/2008 9:07:31 AM				
Boyd, David		CIRCULATING PUMP IN THE CUSTODIAL CLOSET IN THE C-WING IS MAKING NOISE.							
Eddie Baeza									
32547					3/13/2008		19		\$0.00
Medium	Work In Progress				3/13/2008 10:02:50 AM				
Lozoya, Manny		Need a gate key for El Paso Disposal.							
Juliet Parra									
32703					3/25/2008		7		\$0.00
Medium	Work In Progress				3/25/2008 3:08:05 PM				
Carbajal, Jimmy		wet/vac is not picking up water 06203							
Arthur Contreras									
32747					3/26/2008		6		\$0.00
Medium	Work In Progress				3/26/2008 1:58:24 PM				
Lozoya, Manny		MS HARDY'S KEY IN ROOM B-5 WILL NOT OPEN THE STAFF REST RM. SINCE HER CORE HAS BEEN CHANGED							
Eddie Baeza									
Count: 78 Work Orders		Avg. Age of WO's		128	Total for Chaparral HS			0	\$0.00

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

24411					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24412					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24413					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

26037					8/20/2007		225		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:20:23 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. DEADBOLTS NEED TO BE REPLACED IN ALL REST RMS.

Eddie Baeza

27127					9/18/2007		196		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/18/2007 11:19:23 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny we need to change the lock from 405A to 405B and 405B TO 405A. we have computers in room 405A and we do not want people with the A master key to be able to go in there.

Robert Gonzalez

27255					9/21/2007		193		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/21/2007 7:27:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny girls locker room door that leads to the back girls sports locker room is hard to open and lock. choach ramos would like a dead bolt put on there if possible.

Robert Gonzalez

29159		Cafeteria			11/13/2007		140		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2007 10:39:04				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny BOTTOM BLODGETT OVEN IS STILL NOT WORKING (NEED TO COOK TURKEY ASAP - PLEASE)

SANDRA DIAZ - SNP MANAGER 824-4379

Alma Terrell

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

29167		Cafeteria			11/13/2007		140		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2007 1:47:21 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny the floor peddle to the sink broke off. (unable to use at all)

Sandra Diaz -SNP Mgr 824-4376

Jacqueline Aguilar

30023		Classroom			12/12/2007		111		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	ROOM 205			12/12/2007 10:15:38				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Lozoya, Manny MR. ALVA NEEDS HIS LOCK BACK ON HIS CABINET. LOCKS WERE TAKEN TO MAKE KEYS AND NEVER PUT BACK ON.

Elena Palacios

30024		Classroom			12/12/2007		111		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	ROOM 106			12/12/2007 10:17:12				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Lozoya, Manny MR. RAMOS NEEDS HIS FILE CABINETS (2) REKEYED THEY'RE LOCKED NOW.

Elena Palacios

30028		Classroom			12/12/2007		111		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	ROOM 305			12/12/2007 10:22:55				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Lozoya, Manny MRS. KROL NEEDS A CABINET REKEYED. CANNOT CLOSE OR LOCK IT AT THE TIME

Elena Palacios

30296					1/6/2008	1/27/2008	86		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

30645					1/15/2008		77		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Lounge			1/15/2008 1:47:47 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Estrada, Jesus Re-carpet lounge during Spring Break.

Michael Munoz

31064					1/30/2008		62		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/30/2008 11:15:47 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenz Need a coupling connector for Boiler system water pump in the mechanical Room.

Johnny Acuna

31295		Gym			2/5/2008		-60		\$0.00
-------	--	-----	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/5/2008 9:00:35 AM	12/7/2007			
--------	------------------	--	--	--	---------------------	-----------	--	--	--

Lozoya, Manny boys and grls. lockers rooms need replace partitions.

Juan Vargas

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

31598		Portables			2/14/2008		47		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/14/2008 1:19:14 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Portable #14 has two file cabinets that need keys and the building mechanic needs locks and keys for his desk

Eric Medina

31601					2/14/2008		47		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/14/2008 2:26:42 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe
4 custodial closets have leaks at faucet

Eric Medina

32025		Portables			2/29/2008		32		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	P-10			2/29/2008 8:35:00 AM				
--------	------------------	------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Need file cabinet re-keyed for Ms. Smith in portable 10 needs to file important confidential papers.

Elena Palacios

32305					3/5/2008		27		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/5/2008 3:16:24 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Joe
3/5
need to replace valve under portable #2

Eric Medina

32329					3/6/2008		26		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/6/2008 8:06:40 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Gonzales, Angel
Myblower's throttle is stuck on fast and the weed eater's string housing is broken

Eric Medina

32354					3/6/2008		26		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

High	Work In Progress				3/6/2008 3:03:01 PM				
------	------------------	--	--	--	---------------------	--	--	--	--

Gonzalez, Robert
Shampoo and extract carpet in band room. As per Ms. Muela the carpet is making the band director sick. (assign to R. Gonzalez)

Jesus Estrada

32418					3/10/2008		22		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				3/10/2008 9:39:00 AM				
------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
We need all the locks that were taken off the file cabinets re-installed. We have been waiting since SEPTEMBER!!!

Elena Palacios

32426					3/10/2008		22		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 11:14:51 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
classroom 204 lock will not stay unlocked

Robert Gonzalez

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

32429					3/10/2008		22		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 11:22:23 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny outside door to boys locker rooms westside is very hard to unlock. then it's very hard to lock again. door handle is loose.

Robert Gonzalez

Count: 24 Work Orders		Avg. Age of WO's 104				Total for Chaparral MS	0		\$0.00
------------------------------	--	-----------------------------	--	--	--	-------------------------------	----------	--	---------------

Location: Desert Pride

26455					8/30/2007		215		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	storage building			8/30/2007 12:55:10 PM				
--------	------------------	------------------	--	--	-----------------------	--	--	--	--

Miranda, Danny storage building- a good size of the ceiling (sheetrock) came down and a light fixture is hanging loose toward the back end of building Routed to Danny asp Mike 8/31 -mkv

David Acosta

28788		Restroom (Girls)			11/1/2007		152		\$0.00
-------	--	------------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	front office			11/1/2007 10:12:05 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Appelzoller, Fred Need an ADA toilet installed in the restroom in the front office.

Mary Telles

30920		Portables			1/24/2008		68		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	6 & 7			1/24/2008 2:00:01 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Castillo, Carlos ROOMS 6 & 7 NEEDS INDIVIDUAL LIGHT SWITCH TO TURN ON LIGHTS TO THEIR ROOMS. (LAST PORTABLE)

David Acosta

31595		Office			2/14/2008		47		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/14/2008 10:38:39 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph SOCIAL WORKER (MRS. ZAPATA) REQUESTING THE DOOR KNOB TO BE REPLACE BACK ON HER DOOR. THAT WAS REMOVE ONCE FROM HER OFFICE DOOR & INSTALL ON OTHER DOOR WHERE TESTING MATERIEL WHERE STORED.

David Acosta

32870					4/1/2008		0		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				4/1/2008 9:01:45 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose THE A/C UNIT BLOWING HOT AIR - PLEASE CHECK ASAP

Cora Ramirez

32873		Portables			4/1/2008		0		\$0.00
-------	--	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	6 , 7 & 8			4/1/2008 10:44:19 AM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Castillo, Carlos OUTSIDE NIGHTLIGHTS NOT TURNING ON AT NITE

David Acosta

4/1/2008 6:24:36 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Pride							
32874		Office			4/1/2008		0		\$0.00
Medium	Work In Progress				4/1/2008 10:50:50 AM				
Castillo, Carlos		SECURITY NIGHTLIGHT NEEDED ON NORTH SIDE OF FRONT OFFICE BUILDING. THAT AREA VERY DARK.							
David Acosta									

Count: 7 Work Orders	Avg. Age of WO's 69	Total for Desert Pride	0	\$0.00
-----------------------------	----------------------------	-------------------------------	----------	---------------

Location:		Desert Trail Intermediate							
24362					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:47 AM				
Villalobos, David		Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24363					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:47 AM				
Villalobos, David		Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24364					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:48 AM				
Villalobos, David		Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

25347		Cafeteria			8/2/2007		243		\$0.00
Medium	Work In Progress				8/2/2007 1:47:59 PM				
Orozco, Danny		Kitchen: Washroom Door Frame needs to be replaced. Door Frame is corroded on the bottom.							
Johnny Acuna									

26689					9/5/2007		209		\$0.00
Medium	Work In Progress				9/5/2007 1:18:39 PM				
Lozoya, Manny		Need to check Custodial J-Master Key. Key does not open doorknob lock to portable #415 for her to clean classroom during her working hours.							
Johnny Acuna									

26782					9/7/2007		207		\$0.00
Medium	Work In Progress				9/7/2007 8:57:11 AM				
Lozoya, Manny		Custodial Dept. requesting a lock for filing cabinet in the custodial / maintenance office.							
Johnny Acuna									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Desert Trail Intermediate

26788					9/7/2007		207		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/7/2007 10:28:19 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Need to replace (2) Ballasts for Outdoor security light poles. *-light next to storage shed. *-Light in back of portables closest to grass area:Also for this light pole need to replace broken light cover.

Johnny Acuna

27020					9/14/2007		200		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/14/2007 10:48:38 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Michael
Need to replace VCT in the kitchen laundry room. VCT is cracked and faded out. If possible, replace with skid resistant type. Thank You.

Johnny Acuna

28406					10/23/2007		161		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 11:10:46				
--------	------------------	--	--	--	---------------------	--	--	--	--

Acuna, Johnny
Please connect existing sidewalk to playground ramp approx. 3 x 5 section after grounds does backfill of dirt.

Michael Munoz

28408					10/23/2007		161		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 11:13:37				
--------	------------------	--	--	--	---------------------	--	--	--	--

Acuna, Johnny
Michael Munoz
Digout grass around wells in trees.

28536					10/25/2007		159		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/25/2007 1:01:41 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Acuna, Johnny
Michael Munoz
PLAYGROUND ARE-NEED CONNECTION FROM SIDEWALK TO SURFACING FOR ADA.

28537					10/25/2007		159		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/25/2007 1:05:49 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Acuna, Johnny
Michael Munoz
NOT GOOD FOR 5 YEAR OLD.- NEED SIGN FOR 6YRS AND OLDER.

30297					1/6/2008	1/27/2008	86		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
Margret Villalobos
Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail Intermediate

30396		Cafeteria			1/8/2008		84		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/8/2008 2:05:00 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny		Garbage Disposal is Not Working Again							
---------------	--	---------------------------------------	--	--	--	--	--	--	--

		Patricia Cisneros - SNP Manager 824-3822							
--	--	--	--	--	--	--	--	--	--

Alma Terrell

31003					1/29/2008		63		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/29/2008 7:22:07 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo		Replacement a/c's for portable 403/404.							
----------------	--	---	--	--	--	--	--	--	--

Johnny Acuna

31052		Cafeteria			1/30/2008		62		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/30/2008 9:42:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		SLICER IS MAKING WEIRD NOISES WHEN BLADE IS ROTATING							
---------------	--	--	--	--	--	--	--	--	--

		PATRICIA CISNEROS - SNP MANAGER 824-3822							
--	--	--	--	--	--	--	--	--	--

Alma Terrell

31197					2/3/2008	2/11/2008	58		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				2/3/2008 12:30:34 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

31202					2/3/2008	2/11/2008	58		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				2/3/2008 12:30:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

31855					2/25/2008		36		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 4:03:54 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Need 3 Muliums installed in our main building main entry door areas. (1)-Front office area, main doors. (1)-Bus area main doors. (1)-Middle main door going to portable area.							
---------------	--	---	--	--	--	--	--	--	--

Johnny Acuna

31892					2/26/2008		35		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/26/2008 2:52:35 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe		Room #208. Need to replace classroom waterfountain. Leaking.							
----------------	--	--	--	--	--	--	--	--	--

Johnny Acuna

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail Intermediate

32251					3/4/2008		28		\$0.00
Medium	Work In Progress				3/4/2008 11:11:58 AM				
Ontiveros, Joe		Need to unclog urinal in the 2nd grade boys restroom.							
Johnny Acuna									
32300					3/5/2008		27		\$0.00
Medium	Work In Progress				3/5/2008 12:16:32 PM				
Lozoya, Manny		Need (2) replacement pad locks for outdoor gates on the west side of the main building.							
Johnny Acuna									
32337					3/6/2008		26		\$0.00
Medium	Work In Progress				3/6/2008 8:54:02 AM				
Hernandez, Guillermo		Need to borrow appliance dolly to move heavy stuff.							
Marisela Torres									
32768		Cafeteria			3/27/2008		5		\$0.00
Medium	Work In Progress				3/27/2008 8:34:39 AM				
Orozco, Danny		Food slicer motor very loud needs new bearings, thanks!							
Fernando Moncayo									
32857					3/31/2008		1		\$0.00
Medium	Work In Progress				3/31/2008 3:34:42 PM				
Ontiveros, Guadalupe		Broken Main Irrigation water line inside the Water pressure tank area at Chaparral Elementary. Need Parts for PVC line (6").							
Johnny Acuna									
32860					3/31/2008		1		\$0.00
Medium	Work In Progress				3/31/2008 3:42:29 PM				
Orozco, Danny		Ice-Machine in kitchen not working.							
Johnny Acuna									
Count: 26 Work Orders			Avg. Age of WO's 119			Total for Desert Trail Intermediate	0		\$0.00

Location: Desert View ES

24378					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24379					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

4/1/2008 6:24:36 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

24380					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

25693					8/9/2007		236		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/9/2007 3:49:24 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose pat aguilar
a/c port 1 not working properly not cold - has new filter

Patricio Aguilar

26461	Main Building	Portables			8/30/2007		215	1	\$25.00
-------	---------------	-----------	--	--	-----------	--	-----	---	---------

High	Work In Progress				8/30/2007 2:24:40 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Cylinders in portables 1 - 5 are getting stuck so are the main entrances (outer) 3 doors are hard to open. Completed asp report 1/23/08.

Jesus Estrada

27635					9/30/2007	10/21/2007	184		\$0.00
-------	--	--	--	--	-----------	------------	-----	--	--------

Medium	Work In Progress				9/30/2007 12:17:39 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

29032		Cafeteria			11/7/2007		146		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/7/2007 9:44:32 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny AS PER HEALTH INSPECTION ON 10/29/07 -- BACK DOOR MISSING A GOOD SEAL TO PREVENT THE ENTRY OF INSECTS AND VERMIN.

AIDA SALCEDO - SNP COMPLIANCE COORDINATOR
882-6772
MARTHA FLORES - SNP MANAGER 589-2425

Alma Terrell

30305					1/6/2008	1/27/2008	86		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:28:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

30613					1/14/2008		78		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				1/14/2008 4:18:52 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph need locks installed on new gates on new buss turn around. THXS

Michael Munoz

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

31681		Portables			2/20/2008		41		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/20/2008 7:34:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Aguilar, Patricio portable # 6, as per our conversation, please extend sidewalk to asphalt. concrete or asphalt.

Michael Munoz

31725		Cafeteria			2/20/2008		41		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/20/2008 4:02:08 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando DOOR OPENS TO MIXER

AIDA SALCEDO - SNP COORD.

Alma Terrell

31757					2/21/2008		40		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/21/2008 3:12:03 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel pat aguilar
lawnmower need service - blades - battey
need my weed eater repaired - thank you

Patricio Aguilar

31806					2/22/2008		39		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/22/2008 3:26:23 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos paguilar
need lights - philips fc8t9/cw 22watt - philips fc6t9/cw
20watt

Patricio Aguilar

31868					2/26/2008		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				2/26/2008 10:14:40 AM	2/26/2008			
--------	------------------	--	--	--	-----------------------	-----------	--	--	--

Munoz, Michael Need to pour new sidewalk to connect existing sidewalk on east side of building to new playground equipment

Alfredo Holguin

31904		Cafeteria			2/26/2008		35		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/26/2008 3:57:08 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph NEED KEYS TO BE MADE FOR 1) REACH IN FREEZER 2) WALK - IN REFRIG. & 3) STORAGE ROOM

AIDA SALCEDO - SNP COORDINATOR 882-6772

Jacqueline Aguilar

32000					2/28/2008		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/28/2008 3:05:48 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe paguilar
need help in moving sand. thank you

Patricio Aguilar

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

32141					3/2/2008		30	1	\$25.00
Medium	Work In Progress				3/2/2008 12:33:18 AM				
Aguilar, Patricio		Monthly - Desert View ES A-1 Semiannual MCS & MCS2 - Refer to PM schedule details.				Test			
Margret Villalobos									

32397					3/7/2008		25		\$0.00
Medium	Work In Progress				3/7/2008 3:33:31 PM				
Castillo, Carlos		pat aguilar need 4 emer light replaced							
Patricio Aguilar									

Count: 18 Work Orders Avg. Age of WO's 114 Total for Desert View ES 2 \$50.00

Location: GAC

24381					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24382					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24383					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24815	Pre-K	Classroom			7/16/2007		260		\$0.00
Medium	Work In Progress	PRE-K			7/16/2007 4:18:02 PM				
Boyd, David		AS PER JUAN AMBRIZ-ROOF LEAKED IN 2 OF THE PRE-K CLASSROOMS.				ON HOLD UNITL MR. BOYD LOOKS INTO THIS, TO MAKE SURE IT IS NOT UNDER WARRENTY.			
Mary Garcia									

24918	RTC	Classroom			7/19/2007		257		\$0.00
Medium	Work In Progress	ACROSS THE			7/19/2007 2:34:45 PM				
Ontiveros, Guadalupe		AS PER GLORIA SAENZ-IF A SIDE WALK CAN BE INSTALLED BEHIND THE PORTABLE. THERE IS TO MUCH SAND FOR STUDENT TO WALK IN.				1/14 - Asp Mike route to Lupe			
Mary Garcia									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC
------------------	------------

26441		Cafeteria			8/30/2007		215		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/30/2007 9:55:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Water leaking from garbage disposal water line area.							
---------------	--	--	--	--	--	--	--	--	--

		Gessica Blazquez - SNP Manager 882-6784							
--	--	---	--	--	--	--	--	--	--

Alma Terrell									
--------------	--	--	--	--	--	--	--	--	--

26842		Portables			9/10/2007		204		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	STORAGE-MS.			9/10/2007 1:33:27 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Ambriz, Juan		AS PER MS. SALINAS-THE STORAGE UNIT NEEDS				9/19 - Asp Mike route to Juan Ambriz			
--------------	--	---	--	--	--	--------------------------------------	--	--	--

		ADDITIONAL SHELVING AND WOULD LIKE TO HAVE SOME INSTALLED. BILINGUAL DEPT. HAS NO MATERIALS FOR THIS, AND WOULD LIKE TO KNOW IF MAINTENANCE WOULD BE ABLE TO SUPPLY THEM WITH THE MATERIALS NEEDED.							
--	--	---	--	--	--	--	--	--	--

Mary Garcia									
-------------	--	--	--	--	--	--	--	--	--

28141		Office			10/15/2007		169		\$0.00
-------	--	--------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	C-WING			10/15/2007 3:07:50 PM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Miranda, Danny		AS PER SHEILA RAIHL-NEED TO REMOVE OBSERVATION WINDOW IN HER OFFICE.				ASP Mike route to Danny 10/25			
----------------	--	--	--	--	--	-------------------------------	--	--	--

Mary Garcia									
-------------	--	--	--	--	--	--	--	--	--

28143		Office			10/15/2007		169		\$0.00
-------	--	--------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	C-WING			10/15/2007 3:09:23 PM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Miranda, Danny		AS PER MS. RAIHL-AFTER REMOVING THE WINDOW, THE WALL NEEDS TO BE				10/25 - ASP Mike route to Danny M.			
----------------	--	--	--	--	--	------------------------------------	--	--	--

		TAPED/TEXTURED AND PAINTED.							
--	--	-----------------------------	--	--	--	--	--	--	--

Mary Garcia									
-------------	--	--	--	--	--	--	--	--	--

29377	RTC	Stairway			11/20/2007		133		\$0.00
-------	-----	----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	Portable ramps			11/20/2007 3:23:11 PM				
--------	------------------	----------------	--	--	-----------------------	--	--	--	--

Ambriz, Juan		As per Ms. Julie Hinojosa Ramp boards are worpped and seperated. Students tripping need to be replaced as sson as possible for Staff and Student safety							
--------------	--	---	--	--	--	--	--	--	--

Juan Ambriz									
-------------	--	--	--	--	--	--	--	--	--

29423	RTC	Portables			11/26/2007		127		\$0.00
-------	-----	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	ACROSS THE			11/26/2007 3:52:43 PM				
--------	------------------	------------	--	--	-----------------------	--	--	--	--

Villalobos, David		AS PER GLORIA SAENZ-THERE'S NO HOT WATER IN THE CHILDREN'S PORTABLES.							
-------------------	--	---	--	--	--	--	--	--	--

Mary Garcia									
-------------	--	--	--	--	--	--	--	--	--

29511		Office			11/28/2007		125		\$0.00
-------	--	--------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	Front lobby			11/28/2007 3:21:38 PM				
--------	------------------	-------------	--	--	-----------------------	--	--	--	--

Lara, Ralph		As Per Ms. Nava need to install a door with window in front lobby with Ms. Nancy Segura							
-------------	--	---	--	--	--	--	--	--	--

Juan Ambriz									
-------------	--	--	--	--	--	--	--	--	--

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
29535		Parking Lot			11/29/2007		124		\$0.00
Medium	Work In Progress	NEAR FRONT			11/29/2007 9:02:05 AM				
Castillo, Carlos		AS PER SELMA NEVAREZ-NIGHT LIGHTS NEAR FRONT OFFICE NEXT TO SIDE WALK ARE NOT WORKING. (AS PER SELMA THIS A SAFETY ISSUE)							
Mary Garcia									
29783					12/4/2007		119		\$0.00
Medium	Work In Progress				12/4/2007 9:36:05 AM				
Ambriz, Jose		Receptionist Area - Need to check for additional Heating and Cooling (see Mike)							
Michael Munoz									
29785					12/4/2007		119		\$0.00
Medium	Work In Progress				12/4/2007 9:43:26 AM				
Castillo, Carlos		Receptionist Area - Need additional lighting (see Mike)							
Michael Munoz									
30298					1/6/2008	1/27/2008	86		\$0.00
Medium	Work In Progress				1/6/2008 12:28:56 AM				
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
30319					1/6/2008	1/27/2008	86		\$0.00
Medium	Work In Progress				1/6/2008 12:29:05 AM				
Orozco, Danny		Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
30698		Computer Lab			1/16/2008		76		\$0.00
Medium	Work In Progress				1/16/2008 3:30:49 PM				
Ronquillo, Ruben		As per Ms. Socorro need to tint windows in computer lab							
Juan Ambriz									
30739		Office			1/17/2008		75		\$0.00
Medium	Work In Progress				1/17/2008 11:26:45 AM				
Estrada, Jesus		The carpet in Richard Chavez office needs to be replaced. We will schedule this for spring break.							
Jesus Estrada									
30766		Cafeteria			1/17/2008		75		\$0.00
Medium	Work In Progress	Cafeteria Heating			1/17/2008 3:44:54 PM				
Ambriz, Jose		Need to repair heating unit in cafeteria not working properly							
Juan Ambriz									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC
------------------	------------

30848					1/22/2008		70		\$0.00
Medium	Work In Progress				1/22/2008 3:20:21 PM				
Ambriz, Juan		AS PER IRMA TRUJILLO-SOME OF THE LIGHTS IN CONFERENCE ROOM #2 ARE OUT AND NEED TO BE REPLACED.							

Mary Garcia

31857					2/25/2008		36		\$0.00
Medium	Work In Progress				2/25/2008 4:36:40 PM				
Castillo, Carlos		Ms. Sheila Raihl would like an outlet installed outside of Conference Room # 2. It would be greatly appreciated if it is done by this week. Thank You!							

Sheila Raihl

31869		Office			2/26/2008		35		\$0.00
Medium	Work In Progress				2/26/2008 10:19:59 AM				
Ambriz, Jose		Gloria Lopez - This office is getting to hot. need to balance system or provide her with a supply diffuser with a damper so she can limit the supply air if necessary.							

Alfredo Holguin

32027					2/29/2008		32		\$0.00
Medium	Work In Progress				2/29/2008 8:43:11 AM				
Castillo, Carlos		As per Mike generate work order for installation of emergency lighting at the Gac.							

Michael Munoz

32207		Office			3/3/2008		29		\$0.00
Medium	Work In Progress	C-WING			3/3/2008 11:17:12 AM				
Ambriz, Juan		AS PER LINDA REYES-NEED TO HAVE DESK LIGHT BULBS REPLACED.							

Mary Garcia

32478		Office			3/11/2008		21		\$0.00
Medium	Work In Progress	B-WING			3/11/2008 3:18:31 PM				
Ambriz, Juan		AS PER ANNE-NEED TO HAVE FILE FRAME INSTALLED IN A CABINET IN MS. GARCIA'S OFFICE.							

Mary Garcia

32512		Office			3/12/2008		20		\$0.00
Medium	Work In Progress	B-WING			3/12/2008 10:18:58 AM				
Lara, Ralph		AS PER MS. BROWDER-NEED AN OFFICE KEY A24 FOR MR. SUTTMILLER.							

Mary Garcia

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC
------------------	------------

32567		Office			3/13/2008		19		\$0.00
Medium	Work In Progress	A WING			3/13/2008 4:47:47 PM				
Ambriz, Juan		AS PER JULIE-NEED TO HAVE DOOR WINDOW TINTED.							

Mary Garcia

32569		Office			3/13/2008		19		\$0.00
Medium	Work In Progress	A WING			3/13/2008 4:53:24 PM				
Lara, Ralph		NEED TO HAVE KEY CORE SWITCHED FROM JULIE'S OLD OFFICE TO NEW OFFICE AND DIAG'S OFFICE TO JULIE'S OLD OFFICE AND SANDRA'S OFFICE .				SEE MARY GARCIA BEFORE DOING THIS JOB. WILL EXPLAIN			

Mary Garcia

32656		Office			3/19/2008		13		\$0.00
Medium	Work In Progress	C-WING			3/19/2008 10:29:55 AM				
Ambriz, Juan		AS PER SALLY-NEEDS A PENCIL DRAWER INSTALLED IN HER OFFICE.							

Mary Garcia

32811		Pool			3/28/2008		4		\$0.00
Medium	Work In Progress	POOL AREA			3/28/2008 10:04:47 AM				
Castillo, Carlos		AS PER MIKE SORIA-ELECTRICAL BOX (SPRINKLER SYSTEM) IN THE POOL AREA IS SHORTING OUT.							

Mary Garcia

32812		Office			3/28/2008		4		\$0.00
Medium	Work In Progress	A-WING			3/28/2008 10:13:37 AM				
Morales, Ramon		AS PER ANNA-NEED TO HAVE THEIR OFFICE WAXED				TALKED W/RAMON & WILL BE DONE NEXT FRIDAY.			

Mary Garcia

32836		Custodial			3/31/2008		1		\$0.00
Medium	Work In Progress	gas blower			3/31/2008 8:10:40 AM				
Gonzales, Angel		The blower keeps choking. I need it asap.							

Ramon Morales

32837					3/31/2008		1		\$0.00
Medium	Work In Progress				3/31/2008 8:16:46 AM				
Munoz, Michael		need to build a counter for the mail area							

Alfredo Holguin

32884		Classroom			4/1/2008		0		\$0.00
Medium	Work In Progress	LM FURNITURE			4/1/2008 3:32:33 PM				
Lara, Ralph		AS PER MR. RICHARD G. CHAVEZ-NEED A "B" KEY FOR LM/SM FURNITURE STORAGE ROOM.				RAFA CALL IF YOU HAVE QUESTIONS ON THIS KEY			

Mary Garcia

Count: 35 Work Orders		Avg. Age of WO's 101				Total for GAC	0		\$0.00
------------------------------	--	-----------------------------	--	--	--	----------------------	----------	--	---------------

4/1/2008 6:24:37 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		GAC - Pre-K							
32472		Classroom			3/11/2008		21		\$0.00
Medium	Work In Progress	Room 102			3/11/2008 1:46:09 PM				
Castillo, Carlos		Need to replace light switch in Pre-K room 102 not working prorerly ASAP							
Juan Ambriz									
Count: 1 Work Orders		Avg. Age of WO's		21	Total for GAC - Pre-K			0	\$0.00

Location:		Gadsden HS							
24384					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24385					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24386					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24387					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24388					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24823					7/17/2007		259		\$0.00
Medium	Work In Progress				7/17/2007 9:44:36 AM				
Lozoya, Manny		Requested by Agustin Garcia Rm. 310A Academic Building-Door handle to Custodian's storage doiset is broken and needs to be replaced before school begins.							
Velia Alarcon									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

24836					7/17/2007		259		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/17/2007 2:30:46 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Velia-Four HK7 keys are needed for the Intervention Staff that will be in Rm. 554.

Velia Alarcon

24912	North Building	Custodial			7/19/2007		257		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/19/2007 11:54:19 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Joe The windows in the attendance office need to be washed.

25204	Boys Gym				7/30/2007		246		\$0.00
-------	----------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Football Side			7/30/2007 2:49:17 PM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Lara, Ralph NEED A NEW DOOR FOR THE BOYS GYM FOOTBALL SIDE LOCKER ROOM DO TO VANDALISM

Mario Apodaca

25208					7/30/2007		246		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/30/2007 3:12:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Velia for rm. 245 over Varsity Gym-Mr. Foster has placed the Parent Out-Reach Ambassador's in this classroom has their new office. Four HE38 keys are need to issue to the Ambassador's. They will be re-located once a space is found for them.

Velia Alarcon

25212					7/30/2007		246		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/30/2007 3:25:27 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Velia-Four HE1 (Gym Keys) are needed for the Parent Out-Reach Ambassador's to open small hallway over the Varsity Gym to access their new office/classroom.

Velia Alarcon

25221					7/30/2007		246		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/30/2007 3:44:32 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Velia for Rm. 126A Main Building-Four HH16 keys are needed to office.

Velia Alarcon

25225					7/30/2007		246		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/30/2007 4:00:35 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Velia for Rm. 554 Wood Shop-Four HK7 keys are needed for Intervention Staff.

Velia Alarcon

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

25259					7/31/2007		245		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/31/2007 10:22:16 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Requested by Oscar Menchaca Rm. 123 Custodial Storage Room in Main Building-Door lock does not work.

Velia Alarcon

25260					7/31/2007		245		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/31/2007 10:34:23 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Requested by Debbie Costalez Rm. 118 Bookkeeper's Office in Main Building-The bookkeeping office in the same as the concession stand. The concession stand is going to be used as a Marketing classroom. The bookkeeping office needs to be off master and four keys are needed.

Velia Alarcon

25342	Boys Gym	Dressing Room			8/2/2007		243		\$0.00
-------	----------	---------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/2/2007 1:24:08 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny NEED A NEW DOOR CYLINDER AT THE GIRLS LOCKER ROOM AT BOYS GYM ROOM 404

Mario Apodaca

25343	Cafeteria (1998)	Restroom (Boys)			8/2/2007		243		\$0.00
-------	------------------	-----------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/2/2007 1:26:39 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny BOYS RESTROOM NEED A NEW LEVER LOCKSET FOR THE DOOR

Mario Apodaca

25344	Academic Bldg				8/2/2007		243		\$0.00
-------	---------------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/2/2007 1:30:21 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny A KEY IS BROKEN IN A DOOR CYLINDER AT ACADEMIC BLDG ON THE N-SIDE OF THE BLDG

Mario Apodaca

25682	Old English Bldg	Restroom (Boys)			8/9/2007		236		\$0.00
-------	------------------	-----------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/9/2007 2:51:13 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny BOYS RESTROOM AT THE TOP FLOOR NEED A NEW KEY CYLINDER

Mario Apodaca

25689					8/9/2007		236		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/9/2007 3:38:10 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny Attn;MR. LATOYA my key is about to break, need one asap THANK YOU!!

Fernando Moncayo

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

25690					8/9/2007		236		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/9/2007 3:40:46 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny		CAFETERIA WEST wing door lock has something inside the cylinder							
---------------	--	---	--	--	--	--	--	--	--

Fernando Moncayo

25691	Varsity Gym	Gym			8/9/2007		236		\$0.00
-------	-------------	-----	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/9/2007 3:43:17 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny		GIRL'S dressing rooms in VARSITY gym, has a broken lock handle							
---------------	--	--	--	--	--	--	--	--	--

Fernando Moncayo

25726	Concession	Football Field			8/10/2007		235		\$0.00
-------	------------	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/10/2007 3:12:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		CONCESSION STAND AT FOOTBALL NEED A NEW DOOR LEVER FOR BACK ROOM							
---------------	--	--	--	--	--	--	--	--	--

Mario Apodaca

25743					8/10/2007		235		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/10/2007 4:11:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Requested by Ms. Jaraba Rm. 124 Main Building-Rekey desk and three keys will be needed.							
---------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

25760					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 9:52:12 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Requested by Ms. Jaraba Rm. 124 Main Building-Replace missing cylinder in closet and three keys will be needed.							
---------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

25763					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 9:57:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Requested by Velia for Cafeteria-A dead bolt lock needs to be installed on both doors that connect the Conference rooms to the kitchen area of the Cafeteria and five keys are needed.							
---------------	--	--	--	--	--	--	--	--	--

Velia Alarcon

25767					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 11:07:57 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Requested by Velia for Main Building and Academic Building Mail Rooms-Combination locks into mail rooms need to be changed, several students have figured out combination. Also, WO# 17300 has not been completed, please review.							
---------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

25771					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 11:37:05 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Requested by Ms. Lam Rm. 104 Main Building-Lock of the North door can no be locked.							
---------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

25774					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 12:04:00 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Requested by Chief Arms Rm. 203 North Building-Key does not want to open classroom.							
---------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

25782					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 1:01:42 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Requested by Velia-Five HJ2 keys are needed for room 801.							
---------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

25783		Gym			8/13/2007		232		\$0.00
-------	--	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 1:08:57 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Requested by Velia-Three HG3 keys are needed (Girl's Gym Office.)							
---------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

25786					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 1:35:55 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Requested by Velia Rm. 153 Old English Building-Room # 153 needs to have the door knob replaced and re-keyed, four keys will be needed.							
---------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

25788					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 1:47:30 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Requested by Velia-Four D Master keys are needed.							
---------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

25790					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 1:55:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Requested by Velia-Five HEM1 Master keys are needed.							
---------------	--	--	--	--	--	--	--	--	--

Velia Alarcon

25791					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 1:59:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Requested by Velia-Two M251 keys are needed for the new Cross Country Coach for restrooms at Football Field.							
---------------	--	--	--	--	--	--	--	--	--

Velia Alarcon

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

25894					8/15/2007		230		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	GATE			8/15/2007 2:32:57 PM				
--------	------------------	------	--	--	----------------------	--	--	--	--

Lozoya, Manny

Mr. Joe S. Mendez, would like to request a key for the gate in the back of Gadsden High School by the alfalfa field in the back of schools ground. That he is requesting is (GM-7) master key to lock. If any questions you may reach me at (505) 882-3364.

Joe Mendez

25933					8/16/2007		229		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/16/2007 2:24:53 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos

Emerg. Light not working as per PM24571
Comp. Lab Southside Entrance
Comp. Lab. Storage
Boys Locker Rm
West Wing Panther Hut

Rudy Arreola

25977	Cafeteria (1998)	Restroom (Boys)			8/17/2007		228		\$0.00
-------	------------------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/17/2007 3:20:32 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred

the water fountain by the boys restroom is leaking

Joe Munoz

26031	Counselors				8/20/2007		225		\$0.00
-------	------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 10:30:31 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny

NEED LOCK FOR COUNSELING CENTER. PLEASE
SEE LUPE ONTIVEROS FOR DETAILS. THANKS.

Guadalupe Ontiveros

26099					8/21/2007		224		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 2:10:31 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny

NEED SIX NEW LOCK FOR THE NEW POWER
PLANT

Mario Apodaca

26102	Cafeteria (1998)	Restroom (Boys)			8/21/2007		224		\$0.00
-------	------------------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 2:32:13 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny

Requested by Velia for Cafeteria-Door knob for the
Boy's Restroom does not lock properly, needs to be
repaired.

Velia Alarcon

26105	Main Building				8/21/2007		224		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 2:42:35 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny

Requested by Ms. Moreno Rm. 126 Main Building-Lock
for classroom sticks, can't get in or get out.

Velia Alarcon

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

26106	Main Building				8/21/2007		224		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 2:50:45 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Ms. Moreno for Women's Faculty Restroom in Main Building-Keydoes not open restroom.

Velia Alarcon

26109	Old English Bldg				8/21/2007		224		\$0.00
-------	------------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 3:09:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Ms. Spivey Rm. 134 Old English Building-Tighten door knob on room 134-keysticks in lock.

Velia Alarcon

26110	Old English Bldg				8/21/2007		224		\$0.00
-------	------------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 3:12:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Ms. Spivey Rm. 134A Old English Building-Fix door frame on bathroom.

Velia Alarcon

26114	Old English Bldg				8/21/2007		224		\$0.00
-------	------------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 3:32:49 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Ms. Zapien Rm. 154 Old English Building-Request to have name plate made to be placed over door.

Velia Alarcon

26444					8/30/2007		215		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/30/2007 10:45:01 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Requested by Linda Solis Rm. 801 Parent Center-The door between room 801 and 800 won't close, latch is stuck.

Velia Alarcon

26656	Concession	Football Field			9/4/2007		210		\$0.00
-------	------------	----------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/4/2007 11:09:22 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny THE LOCK SET AT CONCESSION STAD NEED WORK

Mario Apodaca

26853	Academic Bldg	Restroom (Boys)			9/10/2007		204		\$0.00
-------	---------------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/10/2007 3:44:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael THE PARTITONS AT ACADIMIC BLDG AT THE BOY'S RESTROOM ARE VANDALIS ON THE E/SIDE WING

Mario Apodaca

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
26892	Counselors	Portables			9/11/2007		203		\$0.00
Medium	Work In Progress				9/11/2007 1:01:38 PM				
Lara, Ralph		We need the door that seperates RM 823 and 822 to lock students are trying to open the door from the other side.							
Rudy Arreola									
27104	North Building				9/18/2007		196		\$0.00
Medium	Work In Progress				9/18/2007 7:50:53 AM				
Castillo, Carlos		NEED A NEW OUTLET RUN TO A COPY AT THE ATTENDNCE OFFICE				COPIER			
Mario Apodaca									
27346	Counselors				9/24/2007		190		\$0.00
Medium	Work In Progress				9/24/2007 8:18:44 AM				
Moncayo, Fernando		Requested by Marie for Counseling Center-Thermostat does not work and it is very hot in Counseling Center.							
Velia Alarcon									
27519					9/27/2007		187		\$0.00
Medium	Work In Progress				9/27/2007 3:45:50 PM				
Lara, Ralph		Requested by Velia for Rm. 109D Main Building Men's Faculty Restroom-The cylinder lock is missing out of the door knob, please replace.							
Velia Alarcon									
27637					9/30/2007	10/21/2007	184		\$0.00
Medium	Work In Progress				9/30/2007 12:17:40 AM				
Orozco, Danny		Monthly- Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
27752					10/1/2007		183		\$0.00
Medium	Work In Progress				10/1/2007 9:22:49 PM				
Villalobos, Margret		Need mice pellets [poison] to control mice in storages THANKS!!							
Fernando Moncayo									
27764	Business	Restroom (Boys)			10/2/2007		182		\$0.00
Medium	Work In Progress				10/2/2007 2:58:22 PM				
Appelzoller, Fred		THE URINAL AT THE BUS BLDG NEED TO BE REPLACE DOTO WATER LEAKING AT THE TOP FLOOR							
Mario Apodaca									
27909					10/5/2007		179		\$0.00
Medium	Work In Progress				10/5/2007 2:51:11 PM				
Carrasco, Danny		Greenhouse cooling pads; 4"w x36"h need 20 feet							
Fernando Moncayo									
4/1/2008 6:24:37 PM									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

28064		Electrical Room			10/11/2007		173		\$0.00
Medium	Work In Progress				10/11/2007 1:26:26 PM				
Apodaca, Mario		All numbers in electrical panels need to be updated.							
Jesus Estrada									
28138	Business	Hallway/Corridor			10/15/2007		169		\$0.00
Medium	Work In Progress				10/15/2007 3:00:58 PM				
Lara, Ralph		NEED TO WELD A DOOR HING AT THE BUS BLDG ON THE N-END BOTT FLOOR							
Mario Apodaca									
28235	Agricultural				10/17/2007		167		\$0.00
Medium	Work In Progress				10/17/2007 2:55:30 PM				
Appelzoller, Fred		THE GAS REGULATOR AT THE AG BLDG IS LEAKING NEED FIXING							
Mario Apodaca									
28307	North Building				10/19/2007		165		\$0.00
Medium	Work In Progress				10/19/2007 8:03:48 AM				
Vallejo, Albert		Shingles in North bldg(G wing)are coming off from roof				Pending from Fernando			
Fernando Moncayo									
28317		Electrical Room			10/19/2007		165		\$0.00
Medium	Work In Progress				10/19/2007 8:39:04 AM				
Castillo, Carlos		NEED THE ASSIST OF THE ELECTRICAN TOO HELP OUT ON NUMBERING THE BREAKER W/O 28064							
Mario Apodaca									
28397	Cafeteria (1998)				10/23/2007		161		\$0.00
Medium	Work In Progress				10/23/2007 10:56:32				
Vallejo, Albert		Please paint patio frames around canopy area.				Pending from Fernando			
Michael Munoz									
28398	Varsity Gym				10/23/2007		161		\$0.00
Medium	Work In Progress				10/23/2007 10:59:51				
Ambriz, Jose		Please order parts to repair water fountain in lobby area.				Pending from Fernando			
Michael Munoz									
28401	Academic Bldg				10/23/2007		161		\$0.00
Medium	Work In Progress				10/23/2007 11:02:57				
Ontiveros, Guadalupe		Please install irr. watering system to all trees and shurbs around bldg.							
Michael Munoz									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

28437	North Building				10/23/2007		161		\$0.00
-------	----------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 3:45:44 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Mr. Belle Rm 213 North Building-Lock on file cabinet is broken-comes out completely.

Velia Alarcon

28442	Main Building				10/23/2007		161		\$0.00
-------	---------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 3:49:53 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Velia for Rm. 109d Main Building Men's Faculty Restroom-Lock cylinder has being missing for several months. Students are getting in and ditching, needs to be replaced as soon as possible.

Velia Alarcon

28480	Agricultural				10/24/2007		160		\$0.00
-------	--------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2007 11:28:25				
--------	------------------	--	--	--	---------------------	--	--	--	--

Appelzoller, Fred REPLACE GAS REGULATORS IN AG BLDG.

Michael Munoz

28642	Academic Bldg	Restroom (Boys)			10/30/2007		154		\$0.00
-------	---------------	-----------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/30/2007 7:47:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Appelzoller, Fred NEED 8 NEW SINK SET FAUCET FOR ALL RESTROOMS IN THE ACADEMIC BLDG

Mario Apodaca

28707					10/30/2007		154		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/30/2007 4:06:05 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Gonzales, Angel Truck #166 driver's side door won't close, safety issue

Fernando Moncayo

28790	Academic Bldg				11/1/2007		152		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/1/2007 11:33:00 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Ms. Kalkwarf for the Faculty Restrooms (both North and South Restroom) in the Academic Building-Door locks do not open at times, difficult to turn key.

Velia Alarcon

28792	North Building				11/1/2007		152		\$0.00
-------	----------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/1/2007 12:56:25 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Ms. Leahy Rm. 215 North Building-Replace door stopper on the south side door.

Velia Alarcon

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

28794	Concession				11/1/2007		152		\$0.00
-------	------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/1/2007 1:00:55 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos Requested by Ms. I. Ramos for Panther Paw/Concession Stand-Need to have a power outlet put in the backroom of the Concession Stand.

Velia Alarcon

28819	North Building				11/1/2007		152		\$0.00
-------	----------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/1/2007 4:13:16 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Margret North bldg room 202 is infested with mice. Also requesting mouse, poison pellets or blocks for storages and plumbing chases. Thanks!!

Fernando Moncayo

28978	Old English Bldg	Classroom			11/6/2007		147		\$0.00
-------	------------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/6/2007 8:07:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph OLd English room 148 door is badly broken complete coming apart, need to be replaced ASAP. Thanks!!

Fernando Moncayo

29036					11/7/2007		146		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/7/2007 10:24:39 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Mr. Contaldo Rm. 103 Main Building- Make key for drawer locks. I already gave our Locksmith one of the locks which are all keyed alike.

Velia Alarcon

29164	North Building	Hallway/Corridor			11/13/2007		140		\$0.00
-------	----------------	------------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2007 12:52:11				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph A SET OF DOOR HINGES ARE BROKEN AT N-BLDG BY THE OFFICE AT G -WING NEED TO BE REWELDED

Mario Apodaca

29201					11/14/2007		139		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/14/2007 9:26:12 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Bonnie Sloan for Library-Has a key to a desk that used to work, but they put a new key lock and now it doesn't work, please repair.

Velia Alarcon

29202	Library				11/14/2007		139		\$0.00
-------	---------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/14/2007 9:29:18 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Mr. Grubaugh for Library-The lock is failing on the south emergency exit in the Library. If the lock can not be repaired, the door needs to be chained at night.

Velia Alarcon

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

29336					11/19/2007		134		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/19/2007 1:21:16 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph		Requested by Mr. McNiece Rm. 213 North Building-2nd door does not shut/lock. (North door)							
-------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

29337					11/19/2007		134		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/19/2007 1:21:28 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph		Requested by Mr. McNiece Rm. 213 North Building-2nd door does not shut/lock. (North door)							
-------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

29467					11/27/2007		126		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 4:02:20 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph		Requested by Oscar Menchaca for Rm. 109d Men's Faculty Restroom in Main Building-WORK ORDER # 28442 HAS NOT BEEN COMPLETED. Lock cylinder has being missing for several months. Students are getting in and ditching, needs to be replaced as soon as possible.							
-------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

29469	North Building				11/27/2007		126		\$0.00
-------	----------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 4:04:53 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph		Requested by Velia for Rm. 217 Men's Faculty Restroom in North Building-Teacher and custodian keys do not open door, something is wrong with cylinder.							
-------------	--	--	--	--	--	--	--	--	--

Velia Alarcon

29797					12/4/2007		119		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 11:06:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Requested by Ms. I. Ramos for Panter Paw/Concession Stand-Check or replace locks, door knob not closing properly.							
---------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

29798					12/4/2007		119		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 11:08:16 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos		Requested by Ms. I. Ramos Panther Paw/Concession Stand-Need additional outlets with more power added in Concession Stand.							
------------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

29799					12/4/2007		119		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 11:10:24 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos		Requested by Ms. I. Ramos for Computer Lab (Lab A)- Need an outlet with more power in Lab A for a laminating machine.							
------------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

4/1/2008 6:24:37 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

29820	Boys Gym				12/4/2007		119		\$0.00
-------	----------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 3:27:24 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		Securitylights around Boy's gym not working,night Custodians complaining of being too dark							
------------------	--	---	--	--	--	--	--	--	--

Fernando Moncayo									
------------------	--	--	--	--	--	--	--	--	--

29871		Athletic Field			12/6/2007		117		\$0.00
-------	--	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/6/2007 1:57:16 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		please relocate electrical breaker panel boxfrom back of boys home dug out to the north wall.							
------------------	--	--	--	--	--	--	--	--	--

Michael Munoz									
---------------	--	--	--	--	--	--	--	--	--

29939					12/10/2007		113		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/10/2007 11:29:34				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph		Requested byMr. Belle Rm. 315 Academic Building- Lock on file cabinet needs to be replaced.							
-------------	--	--	--	--	--	--	--	--	--

Velia Alarcon									
---------------	--	--	--	--	--	--	--	--	--

29980					12/11/2007		112		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/11/2007 9:26:32 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose		Computer Lab - Leaking water.							
--------------	--	-------------------------------	--	--	--	--	--	--	--

Fernando Moncayo									
------------------	--	--	--	--	--	--	--	--	--

30140					12/17/2007		106		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/17/2007 2:02:11 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario		Requested byMrs. B-Holzhausen Rm. 226 North Building-Replace damaged lab tables.							
----------------	--	---	--	--	--	--	--	--	--

Velia Alarcon									
---------------	--	--	--	--	--	--	--	--	--

30141					12/17/2007		106		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/17/2007 2:04:04 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Appelzoller, Fred		Requested byMrs. B-Holzhausen Rm. 226 North Building-Replace sink with deep tub lab sink and drying board.							
-------------------	--	--	--	--	--	--	--	--	--

Velia Alarcon									
---------------	--	--	--	--	--	--	--	--	--

30142					12/17/2007		106		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/17/2007 2:05:58 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando		Requested byMrs. B-Holzhausen Rm. 226 North Building-Repair or replace broken floor tiles.							
-------------------	--	---	--	--	--	--	--	--	--

Velia Alarcon									
---------------	--	--	--	--	--	--	--	--	--

30143					12/17/2007		106		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/17/2007 2:09:49 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe		Requested by Mr. A. Lopez for Varsity Softball Field-Sprinkler installed on varsity in-field/wet down dirt.							
----------------------	--	--	--	--	--	--	--	--	--

Velia Alarcon									
---------------	--	--	--	--	--	--	--	--	--

4/1/2008 6:24:37 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

30145					12/17/2007		106		\$0.00
Medium	Work In Progress				12/17/2007 2:13:33 PM				
Ontiveros, Guadalupe		Requested by Mr. A. Lopez for JV Softball Field-Dug out shade for JV field.				1/8 - Route to Lupe asp Mike			

Velia Alarcon

30151	North Building	Office			12/17/2007		106		\$0.00
Medium	Work In Progress				12/17/2007 3:16:51 PM				
Lozoya, Manny		THE DOOR LOCKSET AT THE N-BLDG OFFICE IS NOT LACKING W/KEY							

Mario Apodaca

30249					1/6/2008	1/12/2008	86		\$0.00
Medium	Work In Progress				1/6/2008 12:28:37 AM				
Moncayo, Fernando		Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.							

Margret Villalobos

30306					1/6/2008	1/27/2008	86		\$0.00
Medium	Work In Progress				1/6/2008 12:29:00 AM				
Orozco, Danny		Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.							

Margret Villalobos

30383					1/8/2008		84	2	\$50.00
Medium	Work In Progress				1/8/2008 8:22:40 AM				
Moncayo, Fernando		NEED TO CHECK ALL WATER FOUNTAINS. ORDER MATERIALS & PARTS TO HAVE THEM ALL WORKING AND FUNCTIONING PROPERLY.				Asp report 1/23/08 partially complete waiting on parts.			

Michael Munoz

30493		Athletic Field			1/10/2008		82		\$0.00
Medium	Work In Progress				1/10/2008 3:07:55 PM				
Ontiveros, Guadalupe		Need Storage by home dug -out to be build of cinder block. As per Coach Yanes.							

Guadalupe Ontiveros

30612					1/14/2008		78		\$0.00
Medium	Work In Progress				1/14/2008 4:18:05 PM				
Lara, Ralph		Requested by Velia for Panther Paw (Concession Stand)-WORK ORDER #29797 HAS NOT BEEN COMPLETED-Ms. I. Ramos is concerned that the Panther Paw door is not locking properly.							

Velia Alarcon

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

30629					1/15/2008		77		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/15/2008 10:06:31 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Commander Snarr Rm. 203 North Building-Room door is broken at hinges and swings open freely.

Velia Alarcon

30631		Stairway			1/15/2008		77		\$0.00
-------	--	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/15/2008 10:10:33 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Julio Alcantar (SO1) for Softball Field-West fence by softball fields need repair for safety reasons. 1/16/08 - asp Mike route to Lupe

Velia Alarcon

30648	Main Building				1/15/2008		77		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/15/2008 2:46:56 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Apodaca, Mario Requested by Al Marmolejo (SO6) for outside of Main Building North East corner-Guard rail on north side entrance to Main Building is loose, needs to be fastened.

Velia Alarcon

30690	Agricultural				1/16/2008		76		\$0.00
-------	--------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/16/2008 2:47:00 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos THE GREENHOUSE BREAKER BOX NEED TO BE SERVICE

Mario Apodaca

30724	Library	Restroom (Boys)			1/17/2008		75		\$0.00
-------	---------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2008 9:26:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred Requested by Charlie Jacquez for Boy's Restroom in the Library-One of the urinal won't flush.

Velia Alarcon

30738		Athletic Field			1/17/2008		75		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2008 11:13:34 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe THE TRACK COACH NEED TOW CONCRETE SLABS (7X7) & (7X28) BY THE SOCCER FIELD

Mario Apodaca

30752					1/17/2008		75		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2008 2:49:53 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Velia-Two HJ11 keys are needed for, one for floating teacher and one for key box (room 660).

Velia Alarcon

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

30753					1/17/2008		75		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2008 2:53:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Velia-Three F3 keys are needed, one for Security Officer and two for key box.

Velia Alarcon

30755					1/17/2008		75		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2008 3:10:41 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Velia-Two 1HE25 keys are needed, one for I.A. an one for key box (room 200).

Velia Alarcon

30756					1/17/2008		75		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2008 3:12:10 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Velia-Five L Wrenches are needed for classrooms with panic bars.

Velia Alarcon

30792	North Building	Classroom			1/18/2008		74		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/18/2008 1:05:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph NEED TO REPLALE A DOOR AT ROOM 202 AT THE N-BLDG

Mario Apodaca

30793	North Building	Classroom			1/18/2008		74		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/18/2008 1:07:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph NEED TO REPLACE A DOOR AT ROOM 203 AT THE N-BLDG

Mario Apodaca

30795	Old English Bldg	Gym			1/18/2008		74		\$0.00
-------	------------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/18/2008 1:14:35 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos THE GIRLS GYM THE LAMPS NEED TOBE SERVICE BULBS NEED CHANGE-OUT

Mario Apodaca

30796	Computer	Computer Lab			1/18/2008		74		\$0.00
-------	----------	--------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/18/2008 1:15:53 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos OUTSIDE LAMPS NEED TOBE SERVICE

Mario Apodaca

30929	Main Building	Restroom (Boys)			1/24/2008		68		\$0.00
-------	---------------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/24/2008 3:04:11 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph MENS RESTROOM AT THE MAIN BLDG NEED TOBE REKEY TO (H-E RO D) KEY

Mario Apodaca

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

30960	Main Building	Classroom			1/25/2008		67		\$0.00
Medium	Work In Progress				1/25/2008 2:47:06 PM				
Villalobos, Margret		need pest control - roaches reported in restroom behind towel dispenser. m 106							

Mario Apodaca

30998	Cafeteria (1998)	Cafeteria			1/28/2008		64		\$0.00
Medium	Work In Progress				1/28/2008 3:46:49 PM				
Lara, Ralph		Requested by Marie for entrance to West Conference room in the Cafeteria-Her HE1 key does not open the door. She needs to access her Cum Files located in the West Conference storage room. Please repair as soon as possible.							

Velia Alarcon

31035		Dressing Room			1/29/2008		63		\$0.00
Medium	Work In Progress				1/29/2008 3:18:16 PM				
Lara, Ralph		Wrestling room (507) - Keycylinder spins but does not engage lock							

Albert Vallejo

31036	North Building	Restroom (Boys)			1/29/2008		63		\$0.00
Medium	Work In Progress				1/29/2008 3:20:45 PM				
Lara, Ralph		North building (217) - Key will not unlock door (it IS the proper key)							

Albert Vallejo

31174	Cafeteria (1998)	Cafeteria			2/1/2008		60		\$0.00
Medium	Work In Progress				2/1/2008 3:03:38 PM				
Moncayo, Fernando		NEED NEW BULBS SOCKET FOR THE COOLER AT THE SERVING LINE							

Mario Apodaca

31318	Auto Shop				2/5/2008		56		\$0.00
Medium	Work In Progress				2/5/2008 3:15:37 PM				
Castillo, Carlos		Requested by Mr. Carrasco Rm. 580 Auto Shop-Repair ceiling lights.							

Velia Alarcon

31319					2/5/2008		56		\$0.00
Medium	Work In Progress				2/5/2008 3:19:20 PM				
Lara, Ralph		Requested by Coach R. Yanez for Baseball Field-Extra keys to storage shed lock made for Assistant Coaches or format shed lock and office key to be the same for both. Shed lock key # CG2 (3 extra) Office key # HE43.							

Velia Alarcon

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

31322	Library	Library			2/5/2008		56		\$0.00
Medium	Work In Progress				2/5/2008 3:23:48 PM				
Lara, Ralph		Requested by Mr. Grubaugh Rm. 275 Library-The front door to the Library is becoming very hard to open. It sticks even when it's unlocked.							

Velia Alarcon

31337	Main Building	Classroom			2/5/2008		56		\$0.00
Medium	Work In Progress				2/5/2008 4:01:52 PM				
Villalobos, Margret		Requested by Cathy Cano for Rm. 106 Main Building-Roach and mouse problem.							

Velia Alarcon

31339		Portables			2/5/2008		56		\$0.00
Medium	Work In Progress				2/5/2008 4:11:38 PM				
Apodaca, Mario		Requested by Coach A. Lawrence for Rm. 822 Portables-Both ramps need to be fixed.							

Velia Alarcon

32848	Old English Bldg				3/31/2008		1		\$0.00
Medium	Work In Progress				3/31/2008 2:31:12 PM				
Villalobos, Margret		Need to check all A/C with Tracer Summit.							
Jose Ambriz									

31340					2/5/2008		56		\$0.00
Medium	Work In Progress				2/5/2008 4:27:04 PM				
Lara, Ralph		Requested by Mr. Belle Rm. 315 Academic Building-WORK ORDER #29939 HAS NOT BEEN COMPLETED -Lock on file cabinet needs to be replaced. It is totally broken and it pulls out of the socket.							

Velia Alarcon

31356	Pool Dressing	Pool			2/6/2008		55		\$0.00
Medium	Work In Progress				2/6/2008 10:29:10 AM				
Estrada, Jesus		Change the vinyl cove base in the swimming pool locker/shower area to ceramic.							

Alfredo Holguin

31357					2/6/2008		55		\$0.00
Medium	Work In Progress				2/6/2008 10:32:04 AM				
Lara, Ralph		Requested by Mr. Belle Rm. 200 North Building-The lock on the classroom door needs to be fixed, keys do not lock the door.							

Velia Alarcon

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

31358	North Building				2/6/2008		55		\$0.00
-------	----------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/6/2008 10:34:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Velia for Rm. 217 Men's Faculty Restroom in North Building-WORK ORDER #29469 HAS NOT BEEN COMPLETED-Teacher and custodian keys do not open door, something is wrong with cylinder.

Velia Alarcon

31360	Boys Gym				2/6/2008		55		\$0.00
-------	----------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/6/2008 10:39:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Mr. Mora Rm. 403 Boys Gym-Athletic training room door broke again, request a door that latches.

Velia Alarcon

31369					2/6/2008		55		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/6/2008 1:46:46 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph Requested by Coach Maxey for Intervention Room in the Barracks-Door knobs put on doors of both rooms in Intervention, have cylinder match the building key HJ1 as soon as possible.

Velia Alarcon

31386	Grounds Shop	Athletic Field			2/7/2008		54		\$0.00
-------	--------------	----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/7/2008 7:38:00 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos As per Raul Sanchez disconnect irrigation pump to be pulled out by Anthony P ump. Will need to return and reconnect

Carlos Castillo

31394	Academic Bldg	Restroom (Boys)			2/7/2008		54		\$0.00
-------	---------------	-----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/7/2008 2:36:51 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Juan NEED NEW EXHAUST FAN FOR THE #4 RESTROOM AT THE ACADEMIC BLDG

Mario Apodaca

31419	Library	Library			2/8/2008		53		\$0.00
-------	---------	---------	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/8/2008 10:39:52 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos the outside lights are not working safety hazard

Joe Munoz

31470	North Building	Classroom			2/11/2008		50		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	221			2/11/2008 3:07:48 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lara, Ralph The teachers key will not work on her classroom door.

Albert Vallejo

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

31471					2/11/2008		50		\$0.00
Medium	Work In Progress				2/11/2008 3:10:59 PM				
Ronquillo, Ruben		I am missing Eighteen (18) ABC Fire extinguishers							
Albert Vallejo									
31561	Boys Gym	Mechanical Room			2/13/2008		48		\$0.00
Medium	Work In Progress				2/13/2008 12:23:30 PM				
Lara, Ralph		THE DOOR AT THE BOYS GYM AT BOILER ROOM NEED TOBE REPLACES							
Mario Apodaca									
31600	Varsity Gym	Classroom			2/14/2008		47		\$0.00
Medium	Work In Progress	Room #245			2/14/2008 1:59:28 PM				
Castillo, Carlos		Electricity to entire back wall has been shut off, I would like to find out why before reconnecting it. Teachers have requested power to the outlets for thier computers							
Albert Vallejo									
31631					2/15/2008		46		\$0.00
Medium	Work In Progress				2/15/2008 1:50:31 PM				
Ronquillo, Ruben		Need to install a rack on Albert Vallejo truck.							
Albert Vallejo									
31684		Athletic Field			2/20/2008		41		\$0.00
Medium	Work In Progress				2/20/2008 8:07:30 AM				
Castillo, Carlos		As per Raul SanchezNeed to disconnect irrigation pump,will need to return to reconnect.							
Carlos Castillo									
31833					2/25/2008		36		\$0.00
Medium	Work In Progress				2/25/2008 2:58:02 PM				
Lara, Ralph		Requested byMs. Hamilton Rm. 562 Ag. Shop- Classroom door is sticking and can not be opened with key.							
Velia Alarcon									
31837					2/25/2008		36		\$0.00
Medium	Work In Progress				2/25/2008 3:05:19 PM				
Lara, Ralph		Requested by Velia for key box-Two M114 keys are needed (key to restrooms in Varsity Gym)							
Velia Alarcon									
31840	Auto Shop				2/25/2008		36		\$0.00
Medium	Work In Progress				2/25/2008 3:12:05 PM				
Castillo, Carlos		Requested by Mr. Carrasco Rm. 580 A Auto Shop-Need 10 rough service gowah bulbs.							
Velia Alarcon									

4/1/2008 6:24:37 PM

Page 60 of 126

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

31844	Cafeteria (1998)	Cafeteria			2/25/2008		36		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 3:30:51 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
NEED TO DO A GENERAL CLEANING-UP OUTSIDE THE CAFE BLDG FOR THE BOARD METING ON THE 2-28-08

Mario Apodaca

31849	North Building	Classroom			2/25/2008		36		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 3:40:08 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
NEED NEW OUTLET FOR THE TOW NEW COMMERCIAL MICROWAVE AT THE N-BLDG TO ROOM 233 FOR NEXT SCHOOL YEAR

Mario Apodaca

31919	Cafeteria (1998)	Cafeteria			2/27/2008		34		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2008 8:41:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Mr Castillo need to check the Zia neon sign, it not getting power. We checked all breakers, but no luck Thanks!!

Fernando Moncayo

31933					2/27/2008		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2008 11:35:58 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Joe
NEED TO CLEAN UP AREA (TRASH, OLD ENTRANCE MAT, CANS) WEST SIDE WALK BY GIRLS GYM NEXT TO BOILER ROOM AND ALSO LIFT STATION AREA BY BUS TURN AROUND NEXT TO ACADEMIC BUILDING.

Michael Munoz

31934					2/27/2008		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2008 11:46:45 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vallejo, Albert
NEED TO REPAIR SOFFITT ??? (OVERHANG) BY MAIN BUILDING ON SOUTH SIDE OF BLDG.

Michael Munoz

31941	Grounds Shop				2/27/2008		34		\$0.00
-------	--------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2008 3:09:18 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
As per Coach Lopez, They want an electrical outlet installed at the field to accomodate a pitching machine.

Albert Vallejo

31942	Counselors	Classroom			2/27/2008		34		\$0.00
-------	------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	822			2/27/2008 3:11:39 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Villalobos, Margret
There is a wasp nest somewhere in the space between the cieling and roof or in the north wall.

Albert Vallejo

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

31944	Academic Bldg	Hallway/Corridor			2/27/2008		34		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2008 3:17:31 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Only about 20% of the emergency lights in the hallways are functioning.

Albert Vallejo

32218					3/3/2008		29		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

High	Work In Progress				3/3/2008 2:40:40 PM				
------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
Requested by Mr. Grubaugh for Library-The emergency exit by the boy's bathroom has a broken lock. It needs to be chained nightly for security purposes. Please fix as soon as possible.

Velia Alarcon

32220					3/3/2008		29		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/3/2008 2:46:43 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos
the outside lights of the annex, weight room, boys need to be service

Mario Apodaca

32222					3/3/2008		29		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/3/2008 2:58:22 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David
Requested by Mr. Grubaugh for Boy's Restroom in Library-There is a urinal in the boy's restroom that has not worked in some time. The water in it is stagnant and foul smelling.

Velia Alarcon

32227		Athletic Field			3/3/2008		29		\$0.00
-------	--	----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/3/2008 3:10:22 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos
Requested by Coach A. Lopez for J.V. Softball-J.V.- electrical box behind basket for pitching machine.

Velia Alarcon

32289	Grounds Shop				3/5/2008		27		\$0.00
-------	--------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/5/2008 8:12:31 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos
Needs outlets installed outside Grounds Shop.

Guadalupe Ontiveros

32338					3/6/2008		26		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/6/2008 9:19:28 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos
Please check switch at irrigation well.

Guadalupe Ontiveros

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

32481	Concession	Auditorium			3/11/2008		21		\$0.00
Medium	Work In Progress				3/11/2008 3:30:38 PM				
Castillo, Carlos		NEED #2 NEW OUTLET FOR THE NEW COMMERCIAL MICROWAVE OVENS AT THE OLD ENG CONCESSION STAND							

Mario Apodaca

32583	Boys Gym				3/14/2008		18		\$0.00
High	Work In Progress				3/14/2008 10:12:27 AM				
Castillo, Carlos		We need lighting on south side of boys gym.							

Jesus Estrada

32584	Varsity Gym				3/14/2008		18		\$0.00
High	Work In Progress				3/14/2008 10:15:22 AM				
Castillo, Carlos		We need lighting on south side of Varsity gym.							

Jesus Estrada

32697		Gym			3/25/2008		7		\$0.00
Medium	Work In Progress				3/25/2008 1:42:41 PM				
Ontiveros, Guadalupe		Need to landscape Area and install irrigation system. area to incould plants & trees.							

Guadalupe Ontiveros

32826	Boys Gym	Dressing Room			3/28/2008		4		\$0.00
Medium	Work In Progress				3/28/2008 3:29:00 PM				
Ronquillo, Ruben		need two 16" x 48" x 1/4" wired glass.							

Albert Vallejo

32851	Academic Bldg	Classroom			3/31/2008		1		\$0.00
Medium	Work In Progress				3/31/2008 3:13:27 PM				
Castillo, Carlos		NEED NEW OUTLES FOR THE COMPUTERI AT ROOM 306							

Mario Apodaca

Count: 165 Work Orders		Avg. Age of WO's 134				Total for Gadsden HS	2		\$50.00
-------------------------------	--	-----------------------------	--	--	--	-----------------------------	----------	--	----------------

Location: Gadsden MS

24389					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							

Alfredo Holguin

24390					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							

Alfredo Holguin

4/1/2008 6:24:38 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

24391 7/1/2007 8/1/2007 275 \$0.00

Medium Work In Progress 7/1/2007 12:15:53 AM

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24392 7/1/2007 8/1/2007 275 \$0.00

Medium Work In Progress 7/1/2007 12:15:53 AM

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24393 7/1/2007 8/1/2007 275 \$0.00

Medium Work In Progress 7/1/2007 12:15:53 AM

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24394 7/1/2007 8/1/2007 275 \$0.00

Medium Work In Progress 7/1/2007 12:15:53 AM

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24395 7/1/2007 8/1/2007 275 \$0.00

Medium Work In Progress 7/1/2007 12:15:53 AM

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24396 7/1/2007 8/1/2007 275 \$0.00

Medium Work In Progress 7/1/2007 12:15:53 AM

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24956 7/20/2007 256 \$0.00

Medium Work In Progress 7/20/2007 9:53:03 AM

Acosta, Juan
NEED TO RELOCATE ATHLETICS TO OLD
PURCHASING PORTABLE, PURCHASING (ALLL
EXCETP CONFERENCETABLE) TO GM NURSHING
AND GM NURSING TO ATHLETICS. CONTACT
PERSONS WOULD BE MR. LOWENBERG & DR
GARCIA

Alfredo Holguin

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

25755	Main Building	Hallway/Corridor			8/13/2007		232		\$0.00
Medium	Work In Progress	A.B WING			8/13/2007 8:23:16 AM				
Diaz, Sebastian		MAROON TILE IN HALLWAY WALLS ARE BROKEN OFF IN THE A.B WING AND CAFEARIA				Route to BM asp Mike- 8/13			

Juan Acosta

25950		Classroom			8/17/2007		-1	1	\$25.00
Medium	Work In Progress	Annex/400			8/16/2007 10:57:39 PM	8/16/2007			
Lozoya, Manny		Mr. Martinez's door to storage closet has a lock. Request that door has same lock as room door.				Completed asp Report 9/4/07			

Maricruz Carrasco

26297					8/27/2007		218		\$0.00
Medium	Work In Progress				8/27/2007 1:23:52 PM				
Sotelo, Enrique		please provide power to sebastians morgan bldg. THXS							

Michael Munoz

26752	Cafeteria				9/6/2007		208		\$0.00
Medium	Work In Progress				9/6/2007 2:03:39 PM				
Diaz, Sebastian		Replace the original tile on the walls by serving doors of cafeteria. (Asp Mike route to Sebastian 123086-Act)-mkv							

Michael Munoz

26791					9/7/2007		207		\$0.00
Medium	Work In Progress	Mobile Home			9/7/2007 1:08:36 PM				
Ontiveros, Guadalupe		Would it be possible for the groundsman, who cuts the grass/weeds, to cut/mow the weeds that are growing underneath the trees in front of my mobile home, and also the ones that are growing underneath the trees by my storage shed.							

Thank you.

Yolie Jacquez

26830	C-Wing	Portables			9/10/2007		204		\$0.00
Medium	Work In Progress	Athletic Office			9/10/2007 8:37:49 AM				
Lozoya, Manny		Repair cash boc barrel for key has broken and needs to be replaced.							

Terry Alvarado

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

26981					9/13/2007		201		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/13/2007 7:48:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
9/13/07
Need to fix all main entrance doors thank you

Sebastian Diaz

27253		Gym			9/20/2007		194		\$0.00
-------	--	-----	--	--	-----------	--	-----	--	--------

High	Work In Progress	Gym/Lockerroom			9/20/2007 4:00:58 PM				
------	------------------	----------------	--	--	----------------------	--	--	--	--

Diaz, Sebastian
Benches need to be replaced in boys lockerroom.

Maricruz Carrasco

27385		Office			9/24/2007		190		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Front Office			9/24/2007 9:48:29 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Keys needed:
(4) V8 for Gym (Outside doors)
(1) A3 for Custodial Storage Room

Maricruz Carrasco

27917					10/5/2007		179		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/5/2007 3:26:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred
10/5/07
Need to replace two urinal in annex boys rest. thank you

Sebastian Diaz

28081	Main Building	Restroom (Boys)			10/12/2007		172		\$0.00
-------	---------------	-----------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/12/2007 7:15:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Diaz, Sebastian
NEED REPLACE NEW MIRRORS IN BOYS
RESTROOMS A.B WING

Juan Acosta

28830	Cafeteria				11/2/2007		151		\$0.00
-------	-----------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/2/2007 1:20:40 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben
NEED A DOOR COVER FOR FIRE EXTINGUISHER
ASP PM 27589.

Sebastian Diaz

29306					11/16/2007		137		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress	GMS Campus			11/16/2007 12:47:39				
--------	------------------	------------	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe
Set up outside tables on GMS Campus. 11/27 Asp Mike route to Lupe.

Maricruz Carrasco

29876					12/6/2007		117		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/6/2007 3:06:03 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred
12/6/07
In room 140 need to replace water faucet sink thank you

Sebastian Diaz

4/1/2008 6:24:38 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

29927	Gym	Gym			12/8/2007		115		\$0.00
-------	-----	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Storage area			12/8/2007 11:56:48 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Doors and hindges need to be replace and installed in the storage are located in the gym.

Veronica Quinonez

29945					12/10/2007		113		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/10/2007 1:14:49 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
12/10/07
Need to fix door knob in couchers storage in the gym
thank you

Sebastian Diaz

30001					12/11/2007		112		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/11/2007 3:48:25 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique
12/11/07
In band room need relocaed switches in the heaters
thank you

Sebastian Diaz

30307					1/6/2008	1/27/2008	86		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:00 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

30391					1/8/2008		84		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/8/2008 12:03:19 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
1/8/08
Need glass window in class door's three doors thank you

Sebastian Diaz

30415	Gym	Dressing Room			1/9/2008		83		\$0.00
-------	-----	---------------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Gym/Official's			1/9/2008 8:56:40 AM				
--------	------------------	----------------	--	--	---------------------	--	--	--	--

Lozoya, Manny
Replace cylinder in Official's dressing room. Hard to open.

Maricruz Carrasco

30682		Office			1/16/2008		76		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Awing/SRO Office			1/16/2008 10:58:43 AM				
--------	------------------	------------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Need 3 keys to SRO Office- F3 as soon as possible.
Thank you!

Maricruz Carrasco

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

30734					1/17/2008		75		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2008 10:58:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
1/17/08
Need fix main entrance doors not closing right thank you

Sebastian Diaz

30740	C-Wing	Portables			1/17/2008		75		\$0.00
-------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2008 11:29:50 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Estrada, Jesus
The carpets in the Athletics portables need to be replaced. We will schedule this during spring break.

Jesus Estrada

30741					1/17/2008		75		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	All GMS Lockers			1/17/2008 11:51:19 AM				
--------	------------------	-----------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
All lockers should have a screw on door so that students don't hide anything in there. To avoid students access to lockers.

Maricruz Carrasco

30817		Office			1/18/2008		74		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	399/100/Secretary			1/18/2008 5:25:38 PM				
--------	------------------	-------------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Glass doors needed for room 399, 100-Chacon's Lounge, Secretary's office, and SRO Office as soon as possible.

Maricruz Carrasco

31301					2/5/2008		56		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/5/2008 9:22:03 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Joe
2/5/08
Need fix toilet tank is broken in hall boys gym thank you

Sebastian Diaz

31361	C-Wing	Classroom			2/6/2008		55		\$0.00
-------	--------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Cwing/C-204/MS.			2/6/2008 10:46:20 AM				
--------	------------------	-----------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Door does not lock. Tried to fix once but still does not lock.

Maricruz Carrasco

31385	Main Building	Cafeteria			2/7/2008		54		\$0.00
-------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/7/2008 4:41:34 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Diaz, Sebastian
CAFETERIA ENTRANCE DOORS FLOOR TILES
NEED REPLACING

Juan Acosta

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

31653	C-Wing				2/19/2008		0		\$0.00
-------	--------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	C-Wing			2/19/2008 9:26:22 AM	2/19/2008			
--------	------------------	--------	--	--	----------------------	-----------	--	--	--

Sotelo, Enrique
Need to replace 2 emerg. lights and 1 exit sign asp PM
31207, 31212

Sebastian Diaz

31829					2/25/2008		36		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 12:16:19 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
Need to fix irrigation waters pipes in front main office
thank you

Sebastian Diaz

32129					3/2/2008	3/18/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:14 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Margret
Yearly - Gadsden MS March Chiller Insp. - Refer to PM
Faxed to Johnson Controls 3/3 mkv
schedule details.

Margret Villalobos

32208		Cafeteria			3/3/2008		29		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/3/2008 11:21:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
TOP RIGHT OVEN. TEMP. WILL HEAT UP GOOD
AND THEN GOES BACK DOWN AND SHUTS OFF.

TERRY PORTILLO GMS SNP MGR 882-2824

Jacqueline Aguilar

32254		Office			3/4/2008		28		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	GMS Front Office			3/4/2008 1:15:32 PM				
--------	------------------	------------------	--	--	---------------------	--	--	--	--

Lozoya, Manny
Cabinet needs lock, same as others in front office.

Maricruz Carrasco

32320	Band Room	Parking Lot			3/6/2008		26		\$0.00
-------	-----------	-------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/6/2008 5:30:58 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe
IN FRONT OF CAFETERIA AND BAND ROOM
SIDEWALKS THERE ARE SINK HOLES

Juan Acosta

32364					3/6/2008		0		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Low	Work In Progress				3/6/2008 3:37:03 PM	3/6/2008			
-----	------------------	--	--	--	---------------------	----------	--	--	--

Lozoya, Manny
Need to meet w/Mike Hogan w/Gencon at 1:00pm on 3-
07-08 to make him keys where needed.

Michael Munoz

32421	C-Wing				3/10/2008		22		\$0.00
-------	--------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 9:54:25 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Need to replace light on light post in front of Old Central
Office (C-Wing)

Yolie Jacques

4/1/2008 6:24:38 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

32500					3/12/2008		20		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	All Automatic			3/11/2008 11:08:33 PM				
--------	------------------	---------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Need to make doors automatic for a student that needs easy access from Portable 501 to Awing to classrooms inside. All doors that are automatic need to be connected at all times for student to use.

Maricruz Carrasco

32502		Office			3/12/2008		20		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Awing/134/A.			3/11/2008 11:18:57 PM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Please install locks on Mr. Salas' black filing cabinet and tan storage cabinet as well.

Maricruz Carrasco

32513	Main Building	Library			3/12/2008		20		\$0.00
-------	---------------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/12/2008 11:06:39 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Briones, Enrique
WE NEED TO HAVE OLD EQUIPMENT THAT IS IN THE LIBRARY PICKED UP FOR DISCARD. THE LIBRARIAN ALREADY HAS THE PAPERWORK WITH TAG AND SERIAL NUMBERS.

Phillip Medina

32553	Gym	Athletic Field			3/13/2008		19		\$0.00
-------	-----	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	BUS TURN			3/13/2008 2:58:50 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Munoz, Michael
HIGH PRIORITY WORK ORDER DUE TO LIFE SAFETY CONCERNS; INSTALL A GATE TO ACCOMODATE A SAFETY ROUTE FOR STUDENTS LOADING ON BUS TURN AROUND. LOCATED BY BASEBALL DUG OUT BY THE SOUTHSIDE. REQUEST BY DR. GARCIA.

Veronica Quinonez

32698	Vocational	Classroom			3/25/2008		7		\$0.00
-------	------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/25/2008 2:15:25 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Vocational Bldg - Mr. Carsizgas Room - Need to install electrical to Kiln.

Michael Munoz

32763	C-Wing	Classroom			3/27/2008		5		\$0.00
-------	--------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Cwing/204			3/26/2008 11:36:05 PM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Need new door knob. It does not lock. Maintenance already tried to fix once.

Maricruz Carrasco

32766	Vocational	Library			3/27/2008		5		\$0.00
-------	------------	---------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Vocational/306/Te			3/27/2008 8:12:19 AM				
--------	------------------	-------------------	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Plug (electrical outlet) needs to be replaced on North side next to cage.

Maricruz Carrasco

4/1/2008 6:24:38 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden MS

32849					3/31/2008		1		\$0.00
Medium	Work In Progress				3/31/2008 2:47:35 PM				
Sotelo, Enrique	electrical short-burned out outlets-no power.								
Rosa Hidalgo									

Count: 53 Work Orders **Avg. Age of WO's 118** **Total for Gadsden MS 1 \$25.00**

Location: La Union ES

24402					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:54 AM				
Villalobos, David	Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									

24403					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:54 AM				
Villalobos, David	Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									

24404					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:54 AM				
Villalobos, David	Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									

25129					7/26/2007		250		\$0.00
Medium	Work In Progress				7/26/2007 3:49:29 PM				
Lozoya, Manny	7/26/07 Manny can you change door lock for classroom 210 (child safety). Thank you.								
Salvador Gonzalez									

25962					8/17/2007		228		\$0.00
Medium	Work In Progress	Playground/Leach			8/17/2007 10:36:16 AM				
Ontiveros, Guadalupe	Need to remove fence between playground and leach fields, level and plant grass.								
Alfredo Holguin									

26704					9/5/2007		209		\$0.00
Medium	Work In Progress				9/5/2007 3:26:36 PM				
Lozoya, Manny	9/5/07 Door knob in classroom is not opening, something inside the cilinder is wrong.								
Salvador Gonzalez									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		La Union ES							
26916					9/11/2007		203		\$0.00
Medium	Work In Progress				9/11/2007 3:45:29 PM				
Castillo, Carlos		9/11/07 Cali I need assistance to replace lidth bulbs and ballasts in old bldg., ceiling is high and it's hard to get up and down. Can you help me? Thanks.							
Salvador Gonzalez									
27262		Cafeteria			9/21/2007		193		\$0.00
Medium	Work In Progress				9/21/2007 7:48:54 AM				
Orozco, Danny		NEED TEMP. CONTROL FOR OVEN. NOT WORKING LINDA YANAGA SNP MGR 589-2040							
Jacqueline Aguilar									
27864					10/4/2007		180		\$0.00
Medium	Work In Progress				10/4/2007 8:57:15 AM				
Villalobos, David		Need Electrician and Plumber to La Union for locates or can it be scheduled for today or tomorrow?							
Cora Ramirez									
27889					10/5/2007		179		\$0.00
Medium	Work In Progress				10/5/2007 8:00:33 AM				
Villalobos, David		10/5/07 David can you check comode in annex building is not flushing righ.							
Salvador Gonzalez									
30015	2000 Core	Hallway/Corridor			12/12/2007		111		\$0.00
Medium	Work In Progress				12/12/2007 9:35:10 AM				
Castillo, Carlos		New hallway in front of boys and girls restrooms bulbs need to be replaced.							
Santos Galindo									
30016	Main Building	Hallway/Corridor			12/12/2007		111		\$0.00
Medium	Work In Progress				12/12/2007 9:41:17 AM				
Castillo, Carlos		Switch right in front of computer lab in hallway needs to be replace.							
Santos Galindo									
30052	Main Building	Classroom			12/13/2007		110		\$0.00
Medium	Work In Progress				12/13/2007 7:53:39 AM				
Castillo, Carlos		Same light bulb's need to be replaced in room 107.							
Santos Galindo									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

30308					1/6/2008	1/27/2008	86		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:01 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

30859					1/23/2008		69		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	DP 544			1/23/2008 9:20:21 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Sanchez, Raul

I talked to Melanie Sanchez regarding the Closure monitoring requirements for the La Union and I agreed to do two additional samplings of the monitoring reports on a quarterly basis. The first sampling needs to be accomplished in January 2008 and the next will be in April 2008.

Alfredo Holguin

30980		Parking Lot			1/28/2008		64		\$0.00
-------	--	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/28/2008 2:21:51 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		Relocate Marquee to area on right hand side of parent entrance where light pole small chinese elm is located. Power for lighting not required				2/4/08 - Asp Mike route to Lupe.			
----------------------	--	---	--	--	--	----------------------------------	--	--	--

Richard Chavez

32147					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador		Monthly - La Union ES A-1 Semiannual EVS - Refer to PM schedule details.							
--------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

32148					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador		Monthly - La Union ES A-8 Quarterly HPW - Refer to PM schedule details.							
--------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32149					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:22 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador		Monthly - La Union ES A-1 Semiannual MCD - Refer to PM schedule details.							
--------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

32153					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador		Monthly - La Union ES A-10 Semiannual HPWC - Refer to PM schedule details.							
--------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

32154					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:24 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador		Monthly - La Union ES C-4 Quarterly MSS - Refer to PM schedule details.							
--------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32463					3/11/2008		21		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2008 8:18:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador		back area(leach lines)where the disc was done, there are alot of rocks, concrete and so on.please pick-up with truck and dispose off. Also with the truck you can start dragging it to help w/ the leveling. THXS							
--------------------	--	--	--	--	--	--	--	--	--

Michael Munoz

Count: 22 Work Orders		Avg. Age of WO's 136				Total for La Union ES	0		\$0.00
------------------------------	--	-----------------------------	--	--	--	------------------------------	----------	--	---------------

Location: Loma Linda ES

24397					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

24398					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

24399					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

24400					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

24441					7/1/2007	7/22/2007	275		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:02 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

25780					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 12:37:30 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Michael
SIDEWALK IN FRONT OF BUILDING. SIDEWALK IS LIFTED. WANTING TO PREVENT ACCIDENT.

Grace Alvarado

26188					8/23/2007		222		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/23/2007 11:27:05 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
LANDSCAPE/PLANT GRASS AND INSTALL A SPRINKLER SYSTEM BETWEEN WINGS.

Alfredo Holguin

27964					10/8/2007		176		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/8/2007 1:16:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sanchez, Raul
We need the filters changed for the domestic water.

Rudy Arreola

28187					10/16/2007		168		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/16/2007 1:37:35 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Margret
We have alot of roaches around entire school need to have it fumigated.

Rudy Arreola

28459					10/24/2007		160		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2007 8:40:57 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
The door is hard to open have to push to lock and unlock and the key is hard to turn already tried some silicone spray but its still hard. Mens RR across mr Ramirez RM.

Rudy Arreola

29225					11/14/2007		139		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/14/2007 2:18:38 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Margret
We are have alot of roaches and spiders in side school.

Rudy Arreola

29728					12/3/2007		120		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/3/2007 8:58:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
Aprox 50-FT of fence was damaged poles were bent and fence was torn that was struck by a vehicle over the weekend. 12/4 - Route to Lupe asp Mike

Rudy Arreola

29787					12/4/2007		119		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 10:29:53 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben
We need a total of 17 blinds replaced through out the school Mr. Ronquillo already has a sample of the blind.

Rudy Arreola

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

29788					12/4/2007		119		\$0.00
Medium	Work In Progress				12/4/2007 10:30:33 AM				
Lozoya, Manny		RM106 Door handle is broken.							
Rudy Arreola									
29789					12/4/2007		119		\$0.00
Medium	Work In Progress				12/4/2007 10:31:11 AM				
Lozoya, Manny		Rm 204 Door is hard to close is hitting the frame of the door.							
Rudy Arreola									
30186					12/18/2007		105		\$0.00
Medium	Work In Progress				12/18/2007 1:34:10 PM				
Sotelo, Enrique		Emergency Light at Mens rr and hallway in front of Rm 109 not working asp PM29659.							
Rudy Arreola									
30299					1/6/2008	1/27/2008	86		\$0.00
Medium	Work In Progress				1/6/2008 12:28:57 AM				
Orozco, Danny		Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
30748					1/17/2008		75		\$0.00
Medium	Work In Progress				1/17/2008 2:07:18 PM				
Sotelo, Enrique		Emerg. Lights asp PM30342 - Mens RR front lobby and hallway not working.							
Rudy Arreola									
31935					2/27/2008		34		\$0.00
Medium	Work In Progress				2/27/2008 1:43:57 PM				
Ontiveros, Joe		We need a water line installed to tap in for irrigation line on the southside of campus.							
Rudy Arreola									
32271					3/4/2008		28		\$0.00
Medium	Work In Progress				3/4/2008 3:17:43 PM				
Lozoya, Manny		MANNY LOZOYA, REPLACE DOOR CLOSURE IN MAIN ENTRANCE FOYER.							
Grace Alvarado									
32298					3/5/2008		27		\$0.00
High	Work In Progress				3/5/2008 10:03:28 AM				
Ontiveros, Guadalupe		start on new landscaping project for pto.							
Joe Munoz									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Loma Linda ES							
32464					3/11/2008		21		\$0.00
Medium	Work In Progress				3/11/2008 8:29:28 AM				
Ontiveros, Joe		We have a water hose spicket that is stripped and leaking water on the southside of kitchen wall. needs to be replaced.							
Rudy Arreola									

Count: 22 Work Orders Avg. Age of WO's 151 Total for Loma Linda ES 0 \$0.00

Location:		Mesquite ES							
24405					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24406					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24407					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24408					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

26748					9/6/2007		208		\$0.00
Medium	Work In Progress				9/6/2007 12:07:58 PM				
Lozoya, Manny		mannyneed new lock for filing cabinet,mis sing key.							
Romauldo Apodaca									

26940		Portables			9/12/2007		202		\$0.00
Medium	Work In Progress	room 601			9/12/2007 1:45:43 PM				
Lozoya, Manny		Change lock on closet in Portable room 601.							
Priscilla Martinez									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

27986					10/9/2007		175		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/9/2007 7:50:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe NEEDS TO REPLACED 10 TILES ON ROOM #111
THANK YOU LUIS

Luis Saucedo

27987					10/9/2007		175		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/9/2007 7:52:37 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe ON PORTABLE #229 GIRLS RESTROOMS NEEDS TO
REPLACED 9 TILES THANK YOU LUIS

Luis Saucedo

28019					10/10/2007		174		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/10/2007 10:35:17				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny Need three doors in the barracks to be replace, they are
in very bad shape.

Joe Ramirez

28065					10/11/2007		173		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/11/2007 2:16:24 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe NEED TO REPLEACE (10) TILES ON ROOM #110
THANK YOU LUIS, ANY QUESTIONS ASK LUIS.

Luis Saucedo

28477					10/24/2007		160		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2007 10:14:02				
--------	------------------	--	--	--	---------------------	--	--	--	--

Solis, Lorenzo Review all Air Condensers. Order parts as need or
replace.

Michael Munoz

29133					11/13/2007		140		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2007 6:44:17 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny need to make a keyfor file cabinet please ask luis.

thank you.
luis

Luis Saucedo

29340		Parking Lot			11/19/2007		134		\$0.00
-------	--	-------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	gate key			11/19/2007 2:16:04 PM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Lozoya, Manny Texas Migrant Council needs a gate key for the north
entrance. Will Mr. Munoz or Mr. Holguin please approve
this request, and direct me as to how the keys should be
handed over. The director for the Texas Migrant Council
is Olivia Hinojosa.

Priscilla Martinez

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

29683					12/2/2007	12/3/2007	121		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium	Work In Progress				12/2/2007 12:30:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

29684					12/2/2007	12/3/2007	121		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium	Work In Progress				12/2/2007 12:30:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

29697					12/2/2007	12/3/2007	121		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium	Work In Progress				12/2/2007 12:30:25 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.							
--------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

29719					12/2/2007	12/3/2007	121		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium	Work In Progress				12/2/2007 12:30:34 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

30574					1/14/2008		78		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/14/2008 6:39:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		the teacher staff bathroom in the 2nd grade wing door lock is not working. thank you luis							
---------------	--	---	--	--	--	--	--	--	--

Luis Saucedo

30575					1/14/2008		78		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/14/2008 6:46:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		need to make a key for file cabinet for room 204 sedillo class room thank you. luis							
---------------	--	---	--	--	--	--	--	--	--

Luis Saucedo

30576					1/14/2008		78		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/14/2008 7:40:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		need to replaced latched on girls & boys restrooms on north side of blg. thank you luis							
---------------	--	---	--	--	--	--	--	--	--

Luis Saucedo

30679	Main Building	Office			1/16/2008		76		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	front office			1/16/2008 10:19:41 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Will you please make a door plaque for our new AP.							
---------------	--	--	--	--	--	--	--	--	--

		Jacob Montano Assistant Principal							
--	--	--------------------------------------	--	--	--	--	--	--	--

Priscilla Martinez

4/1/2008 6:24:38 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
30826		Classroom			1/22/2008		70		\$0.00
Medium	Work In Progress				1/22/2008 9:46:55 AM				
Estrada, Jesus		Need tile replaced in Rooms 113,111,110 w/carpet instead of tile.							
Michael Munoz									
31213					2/3/2008	2/11/2008	58		\$0.00
Medium	Work In Progress				2/3/2008 12:30:42 AM				
Ramirez, Joe		Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
31223					2/3/2008	2/11/2008	58		\$0.00
Medium	Work In Progress				2/3/2008 12:30:46 AM				
Ramirez, Joe		Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
31249					2/3/2008	2/9/2008	58		\$0.00
Medium	Work In Progress				2/3/2008 12:30:55 AM				
Ramirez, Joe		Monthly - Mesquite ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
31260					2/4/2008		57		\$0.00
Medium	Work In Progress				2/4/2008 7:05:29 AM				
Ramirez, Joe		on south hallway under water fountain needs 10 tiles thank you luis							
Luis Saucedo									
31303					2/5/2008		56		\$0.00
Medium	Work In Progress				2/5/2008 9:54:13 AM				
Lozoya, Manny		needs to fix door lock inside of cafeteria by laundry room please thank you luis							
Luis Saucedo									
31341					2/6/2008		55		\$0.00
Medium	Work In Progress				2/6/2008 7:22:50 AM				
Ramirez, Joe		wall on north & SOUTH BOYS & girls restrooms entrance needs to be painted							
Luis Saucedo									
31422		Cafeteria			2/8/2008		53		\$0.00
Medium	Work In Progress				2/8/2008 11:05:21 AM				
Sotelo, Enrique		please, needs to replace (9) lamps on cafeteria is to dark thank you.luis							
Luis Saucedo									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

31496					2/12/2008		49		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/12/2008 8:44:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Rooms 111,110,113 tiles need to be replaced they are the old 6x6 or 8x8 they keep coming off and i believe they are asbestos type.

Joe Ramirez

31499					2/12/2008		49		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/12/2008 8:49:12 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben As per Mr. Montano he is requesting replacement letters for front of school letters missing are H & L. Ruben is working on sending the Marquee co. to several sites and Mq is one of them. When they are there they can go ahead and give us a quote for letters also. If the site needs them ASAP, then they need to purchasing them w/ there funding.

Joe Ramirez

Mike
2/12/08

31596					2/14/2008		47		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/14/2008 12:02:20 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe I need some assistance with the sprinkler system timer and stations.

Joe Ramirez

31698					2/20/2008		41		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/20/2008 1:57:54 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Foot activated lavatory keeps running (slow) hot water side. 2/21/08 - Asp Joe O. route to SNP Tech.

Joe Ramirez

32116					3/2/2008	3/10/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:09 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

32150					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:22 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES A-1 Semiannual EVS - Refer to PM schedule details.

Margret Villalobos

32152					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.

Margret Villalobos

4/1/2008 6:24:38 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

32155					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:24 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.							
--------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

32156					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:25 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-1 Semiannual MCD - Refer to PM schedule details.							
--------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

32157					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:25 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32158					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-1 Semiannual UCD - Refer to PM schedule details.							
--------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

32159					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-1 Semiannual UCS2 - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32160					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32192		Cafeteria			3/3/2008		29		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

High	Work In Progress				3/3/2008 7:35:40 AM				
------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny		A VERY STRONG ELE. BURNING SMELL COMING FROM THE WALK-IN AND THE RIGHT SIDE OF THE CAFET.							
---------------	--	---	--	--	--	--	--	--	--

		ALICE FLOURNOY SNP MGR 233-2341							
--	--	---------------------------------	--	--	--	--	--	--	--

Jacqueline Aguilar

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Mesquite ES							
32504	Main Building	Classroom			3/12/2008		20		\$0.00
Medium	Work In Progress	room 605			3/12/2008 9:00:13 AM				
Ramirez, Joe		this room has been cleared of old equipment, and we would like for it to be restored so that we may create a classroom environment for testing, our campus needs an area for bi-lingual testing and this is the only room available							
Priscilla Martinez									
32549					3/13/2008		19		\$0.00
Medium	Work In Progress				3/13/2008 12:40:01 PM				
Ontiveros, Guadalupe		Requesting tractor with scraper to level out one of the courtyards might need to disc it up first.							
Joe Ramirez									
32559					3/13/2008		19		\$0.00
Medium	Work In Progress				3/13/2008 3:37:43 PM				
Lozoya, Manny		Need 2 locks for the sand seperater gates.							
Joe Ramirez									
32796					3/27/2008		5		\$0.00
Medium	Work In Progress				3/27/2008 3:41:59 PM				
Lozoya, Manny		on room #111 they put a new carpet but the door needs to be fix up to lock up to long thank you. luis							
Luis Saucedo									
32805					3/27/2008		5		\$0.00
Medium	Work In Progress				3/27/2008 7:52:52 PM				
Carbajal, Jimmy		WET&DRY (VIPER S718WD MODEL) DO NOT PICK UP THE WATER THANK YOU. LUIS							
Luis Saucedo									
Count: 48 Work Orders		Avg. Age of WO's		93	Total for Mesquite ES			0	\$0.00

Location:		North Valley Elementary							
31986					2/28/2008		33		\$0.00
Medium	Work In Progress				2/28/2008 8:48:10 AM				
Villalobos, Margret		(New School) Need to spray the whole building on The week of April 1 thru April 4. Before school starts on April 7th.							
Danny Vega									
32548					3/13/2008		19		\$0.00
Medium	Work In Progress				3/13/2008 10:03:23 AM				
Lozoya, Manny		Need a gate key for El Paso Disposal.							
Juliet Parra									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: North Valley Elementary

32693					3/25/2008		7		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/25/2008 10:50:56 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe As per Ms. Bonham, please move bleachers from SMto NV.

Danny Vega

32813					3/28/2008		4		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/28/2008 10:41:44 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vega, Danny Need to install & re-locate white boards in RPT/MPT room and patch and paint when completed.

Michael Munoz

Count: 4 Work Orders			Avg. Age of WO's 16			Total for North Valley Elementary	0		\$0.00
-----------------------------	--	--	----------------------------	--	--	--	----------	--	---------------

Location: Northern On-Track Pre-K (LM)

24401					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:54 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Northern Pre-K (LM) Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

26803					9/7/2007		207		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/7/2007 3:00:03 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe Need to level area north of main bldg (Any ?'s call Alfredo)

Alfredo Holguin

26877	Main Building	Office			9/11/2007		203		\$0.00
-------	---------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/11/2007 10:49:41 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Re-key lock for social workers filing cabinet.

Concepcion Montalvo

28578	Main Building				10/26/2007		158		\$0.00
-------	---------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress	Wilma Martinez			10/26/2007 10:14:50				
--------	------------------	----------------	--	--	---------------------	--	--	--	--

Lozoya, Manny Need locks with keys installed onto 2 (two) cabinets that hold Migrant supplies. Please contact Wilma Martinez @ 575-649-4800.

Lucy Meza

29464					11/27/2007		126		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 3:54:41 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Please have Manny reinstall the key cores in the new hardware sets at La Mesa. He removed the entire cores during const. and needs to be reinstalled. Thanks David

David Boyd

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

30449	Main Building	Office			1/10/2008		82		\$0.00
Medium	Work In Progress				1/10/2008 9:25:14 AM				
Lozoya, Manny		Second request - Please, re-keylock for social worker's filling cabinet							

Concepcion Montalvo

31479					2/11/2008		50		\$0.00
Medium	Work In Progress				2/11/2008 3:32:43 PM				
Vega, Danny		Need to rake leaves in front of campus, and trim tree behind backstop.							

Alfredo Holguin

31480					2/11/2008		50		\$0.00
Medium	Work In Progress				2/11/2008 3:33:28 PM				
Vega, Danny		Need to irrigate.							

Michael Munoz

31512					2/12/2008		49		\$0.00
Medium	Work In Progress				2/12/2008 1:50:47 PM				
Vega, Danny		N. Side of Main Bldg need to cut mustard weed and grass.							

Michael Munoz

31747	Main Building	Office			2/21/2008		40		\$0.00
Medium	Work In Progress				2/21/2008 12:56:18 PM				
Vega, Danny		We have some furniture that needs to be assembled: 2 desks, 1 book shelf, 2 lateral files, and 2 hutches.							

Gilbert Trujillo

31748	Main Building				2/21/2008		40		\$0.00
Medium	Work In Progress				2/21/2008 1:04:59 PM				
Vega, Danny		Trim hedges and spray for bees at entrance to school. (An adult with severe allergies to bees was stung by a bee on 2/20/08.)							

Gilbert Trujillo

32071					3/2/2008	3/8/2008	30		\$0.00
Medium	Work In Progress				3/2/2008 12:32:50 AM				
Vega, Danny		Monthly - La Mesa ES Monthly FE Inspection - Refer to PM schedule details.							

Margret Villalobos

32101					3/2/2008	3/10/2008	30		\$0.00
Medium	Work In Progress				3/2/2008 12:33:03 AM				
Vega, Danny		Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.							

Margret Villalobos

4/1/2008 6:24:38 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

32107					3/2/2008	3/10/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

32256	Main Building	Athletic Field			3/4/2008		28		\$0.00
-------	---------------	----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Playground			3/4/2008 1:19:19 PM				
--------	------------------	------------	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe Refill two sand boxes.

Concepcion Montalvo

32416	Cafeteria	Cafeteria			3/10/2008		17	1	\$25.00
-------	-----------	-----------	--	--	-----------	--	----	---	---------

High	Work In Progress				3/10/2008 9:18:23 AM	3/27/2008			
------	------------------	--	--	--	----------------------	-----------	--	--	--

Trujillo, Gilbert Cafeteria along with storage rooms need a wash down of all walls and windows. WASHED DOEN WITH STRIDE

Jesus Estrada

32603					3/14/2008		18		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/14/2008 3:31:40 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny as per our conversation, need irriagation system installed behind main bldg. contact Rosie Reyes for details. trees to be planted by grounds.

Michael Munoz

32606					3/14/2008		18		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/14/2008 3:34:17 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe please install trees as needed behind main bldg.see Rosie reyes for locations and details. Also Danny Vega will be installing irrigation system. same location. get w/ him so that trees can be on system.

Michael Munoz

32654					3/19/2008		13		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/19/2008 8:10:54 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe BOILER NEEDS TO BE CHECKED. WATER LEVEL WAS VERY LOW AND HAD SPILLED OVER THIS MORNING. DANNY VEGA WAS NOTIFIED BY CHUY. FYI - 3/25/08

Jesus Estrada

Called Danny Vega this morning to see if he had responded to work order and he said he did not have a chance. As per Gilbert had to come in every day (during the holiday), because water was leaking. (Informed Joe Ontiveros this morning to check on this) 3/25/08 -mkv

32730					3/26/2008		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/26/2008 9:06:01 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny NEED TO HAVE KEYS MADE FOR TWO STORAGE CABINETS (PLEASE CONTACT CONCHA MONTALVO)

Cora Ramirez

4/1/2008 6:24:38 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)									
32734		Athletic Field			3/26/2008		6		\$0.00
Medium	Work In Progress				3/26/2008 10:47:53 AM				
Ontiveros, Guadalupe		need a hose adapter with 2 female ends for hose and sprinkler							
Gilbert Trujillo									
32753					3/26/2008		6		\$0.00
Medium	Work In Progress				3/26/2008 3:51:13 PM				
Ontiveros, Joe		Need to check irrigation pump. (Asp Mike ck w/Gilbert).							
Michael Munoz									
32843	Concession	Office			3/31/2008		1		\$0.00
Medium	Work In Progress				3/31/2008 12:46:57 PM				
Lozoya, Manny		unable to unlock 2 doors							
Gilbert Trujillo									
Count: 23 Work Orders			Avg. Age of WO's 64		Total for Northern On-Track Pre-K (LM)			1	\$25.00

Location: Physical Plant Complex									
24409					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24410					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24784					7/16/2007		260		\$0.00
Medium	Work In Progress				7/16/2007 8:03:38 AM				
Ronquillo, Ruben		FORKLIFT SHADE YELLOW CANVAS(MAINT.WHS-2, PUR.WHS-1, F.S. WHS.-1.							
Ruben Ronquillo									
24827					7/17/2007		0	1	\$25.00
Medium	Work In Progress				7/17/2007 11:18:49 AM	7/17/2007			
Lozoya, Manny		JULIE IS REQUESTING A J3 GATE KEY (ORIGINAL ONE WAS GIVEN TO VIKKI LOPEZ)				Completed asp Report 9/4/07			
Juliet Parra									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

27500	Motor Vehicle				9/27/2007		187		\$0.00
Medium	Work In Progress				9/27/2007 9:30:33 AM				
Gonzales, Angel		PLEASE CHECK WATER PUMP ENGINE, NOT STARTING. THANKS RUBEN							

Ruben Ronquillo

27501	Motor Vehicle				9/27/2007		187		\$0.00
Medium	Work In Progress				9/27/2007 9:33:12 AM				
Gonzales, Angel		PLEASE CHECK YELLOW DOUBLE AIR TANK COMPRESSOR, IDLE IS NOT WORKING, IT WILL NOT IDLE DOWN WHEN TANKS ARE FULL. THANKS RUBEN							

Ruben Ronquillo

27765					10/2/2007		182		\$0.00
Medium	Work In Progress				10/2/2007 3:03:33 PM				
Lara, Ralph		RELOCATE DOUBLE DOORS ON BARRACK #1.							

Ruben Ronquillo

28418	Motor Vehicle				10/23/2007		161		\$0.00
Medium	Work In Progress				10/23/2007 2:10:41 PM				
Lozoya, Manny		Transp Office - Install a door stop.							

Norma Alvarado

28986					11/6/2007		147		\$0.00
Medium	Work In Progress				11/6/2007 10:37:20 AM				
Villalobos, Margret		Need Price Quote for Pigeon Control at Barracks.							

Alfredo Holguin

28990					11/6/2007		147		\$0.00
Medium	Work In Progress				11/6/2007 11:58:09 AM				

Hernandez, Guillermo

Michael Munoz		NEED TO COORDINATE AND SCHEDULE WITH VICKI LOPEZ FOR A HIGH/LOW CLEANING				1/11/08 - REQUESTED STATUS FROM GUILLERMO AS OF 2/25/08 - STILL PENDING AS PER GUILLERMO			
---------------	--	--	--	--	--	--	--	--	--

29073					11/8/2007		145		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Custodial Office			11/8/2007 2:31:43 PM				
--------	------------------	------------------	--	--	----------------------	--	--	--	--

Solis, Lorenzo
Removal of the split system and replace w/a package unit in Mary Sitters Office.

Michael Munoz

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

30228	Maintenance	Custodial			12/19/2007		104		\$0.00
-------	-------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/19/2007 9:53:10 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Gonzales, Angel
ANGEL THE BIG TRUCK #82 IS MAKING A LOT OF NOISE SAL WAS PULLED OVER BY THE POLICE AND WAS TOLD NOT TO USE IT UNTILL IT GETS FIXED.THANK YOU

Jimmy Carbajal

30529		Gym			1/11/2008		81		\$0.00
-------	--	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/11/2008 11:20:49 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Michael
need recommendations for the following site (gms, chm, ghs, sths and stms) on bleachers for a preventive plan to see what needs to be done to them so they can operate/function properly.(pm) norcon/ces

Michael Munoz

31068	Purchasing	Office			1/30/2008		62		\$0.00
-------	------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Inst. Materials			1/30/2008 12:51:43 PM				
--------	------------------	-----------------	--	--	-----------------------	--	--	--	--

Estrada, Jesus
Remove carpet from Office #2 (bigger office) and replace with tile.

Vicky Lopez

31380					2/6/2008		55		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/6/2008 3:50:47 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose
Need to recover the units pt from the GAC.

Guillermo Hernandez

31629					2/15/2008		46		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/15/2008 1:10:46 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
ESA Construction needs the following Site Keys: CMS, CHE and LU (Need by the end of the day)

Peggy Jo Hernandez

31931	Maintenance				2/27/2008		34		\$0.00
-------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	HVAC Shop			2/27/2008 10:42:18 AM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Ontiveros, Joe
Former Hvac Shop restroom . please remove toilet, sand sink, but leave a drain and h2o supply for the office for futhure sink install.please see me.
thxs

Michael Munoz

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

32021					2/28/2008		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/28/2008 4:20:32 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
I need the following plates:
Yolanda Jacquez
Michelle Tellez
Mark Rios
RudyCastro
Victoria T. Lopez

I would also like to get a couple of room number plaques made for the office doors:
Office 1
Office 2

Vicky Lopez

32026	Maintenance				2/29/2008		32		\$0.00
-------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/29/2008 8:40:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael
NEED 4' FENCE GATE EAST OF PPD PARK. WO FOR MIKE MUNOZ. THANK YOU!

Ruben Ronquillo

32409		Office			3/10/2008		22		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Mary Sitters			3/10/2008 7:54:53 AM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Enrique Sotelo
Need to connect refrigeration unit in Custodial Office.

32622	Food Services	Cafeteria			3/17/2008		15		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/17/2008 9:10:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando
Food Service Warehouse - Walk-In Freezer # 1 is at 16 degrees.

JohnnyLechuga - SNP Warehouse 882-6927

Alma Terrell

32627					3/17/2008		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/17/2008 2:01:03 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Diaz, Sebastian
NEED TO PAINT FRAMES, WALLS AND VARNISH DOORS IN CUSTODIAL OFFICE

Danny Miranda

32761	Purchasing				3/26/2008		6		\$0.00
-------	------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/26/2008 4:08:04 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Diaz, Sebastian
Mail Room - Paint Exterior Door and install Sign "Mail Room" on door

Alfredo Holguin

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
32808	Food Services	Parking Lot			3/28/2008		4		\$0.00
Medium	Work In Progress				3/28/2008 8:22:47 AM				
Appelzoller, Fred		please raise man hole where it was dug out for clogged sewer for future use.thxs							
Michael Munoz									
32815	Purchasing				3/28/2008		4		\$0.00
Medium	Work In Progress				3/28/2008 11:11:12 AM				
Diaz, Sebastian		Drywall on interior wall south side needs to be replaced with plywood and painted							
Alfredo Holguin									
32816	Purchasing				3/28/2008		4		\$0.00
Medium	Work In Progress				3/28/2008 11:14:18 AM				
Munoz, Michael		Build a new counter for recieving area.							
Alfredo Holguin									
32817	Purchasing				3/28/2008		4		\$0.00
Medium	Work In Progress				3/28/2008 11:18:06 AM				
Gonzales, Angel		The diliveryvan needs the walls repaired priferable with some type of metal and also install new metal flooring. This needs to be accomplished as soon as possible.							
Alfredo Holguin									
32841					3/31/2008		1		\$0.00
Medium	Work In Progress				3/31/2008 12:06:54 PM				
Appelzoller, Fred		CUSTODIAL WAREHOUSE - URINAL IN MENS RESTROOM IS CLOGGED							
Michael Munoz									
32868					4/1/2008		0		\$0.00
Medium	Work In Progress				4/1/2008 8:27:53 AM				
Jacquez, Ricardo		need to fix broken sewer line at lift station							
Ricardo Jacquez									
32876	Purchasing				4/1/2008		0		\$0.00
Medium	Work In Progress				4/1/2008 1:17:58 PM				
Diaz, Sebastian		<ol style="list-style-type: none"> Cover the exposed insulation on the west wall above the garage door. Seal the openings around the garage door Seal the gaps along the west wall Repair holes in northeast wall Repair, replace, or adjust ceiling covering along the southwest wall so that the covering and insulation doesn't hang down from the ceiling. 							
Vicky Lopez									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

32877	Purchasing				4/1/2008		0		\$0.00
Medium	Work In Progress				4/1/2008 2:07:03 PM				
Carrasco, Danny		Need Scissor Lift for Saturday, April 19th at Purchasing Warehouse.							
Jesus Estrada									

Count: 31 Work Orders Avg. Age of WO's 80 Total for Physical Plant Complex 1 \$25.00

Location: Riverside ES

24373					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:49 AM				
Villalobos, David		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24374					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:50 AM				
Villalobos, David		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24375					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:50 AM				
Villalobos, David		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

26653					9/4/2007		210		\$0.00
Medium	Work In Progress				9/4/2007 10:32:36 AM				
Holguin, Alfredo		Provide services and materials for installation of new controller to control existing lighting.				Joe V. picked up PO on 9/4-mkv			
Alfredo Holguin									

28486		Cafeteria			10/24/2007		160		\$0.00
Medium	Work In Progress				10/24/2007 2:34:48 PM				
Orozco, Danny		Shelves need to be removed on next session (March, 2008) As per Environment Department - they inspected Riverside on 10/23/07 and their comments were that: Wood shelving in dry storage must be coated with paint or replaced - Repeat violation. Must be corrected within 60 days. Need to inform Maria Nevarez - Inspector, when corrected.							
Alma Terrell		Aida Salcedo, SNP Coordinator 882-6772 & Emilia Carrillo, SNP Manager 589-2550							

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
28720					10/31/2007		153		\$0.00
Medium	Work In Progress				10/31/2007 9:23:23 AM				
Castillo, Carlos		AS PER OUR CONVERSATION, PLEASE PROVIDE A 120 OUTLET FOR THE ENVIRONMENT DEPT.							
Michael Munoz									
30226					12/19/2007		104		\$0.00
Medium	Work In Progress				12/19/2007 9:04:29 AM				
Lozoya, Manny		MR MANNY LOZOYA SIR WE NEED TO REPLACE 3 THREE OUTSIDE LOCK FOR GATES ONE WAS BROKEN AND THE TWO OTHERS WERE STOLEN THEY ARE FOR OUT SIDE GATES THANK YOU SIR							
Adan Duran									
30311					1/6/2008	1/27/2008	86		\$0.00
Medium	Work In Progress				1/6/2008 12:29:02 AM				
Orozco, Danny		Monthly - Riverside ES Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									
30851					1/22/2008		70		\$0.00
Medium	Work In Progress				1/22/2008 3:35:20 PM				
Ambriz, Jose		MR JOSE AMBRIZ SIR THE RELIEF VALUE ON THE BOILER ON NORTH WING IS STAYING OPEN NEED TO REPLACE WAS ABLE TO GET IT TO STOP FOR NOW THANK YOU SIR AND GOD BLESS							
Adan Duran									
31668					2/19/2008		42		\$0.00
Medium	Work In Progress				2/19/2008 3:30:58 PM				
Gonzales, Angel		jhon deer tractor 455 stopped and won't start							
Carlos Hernandez									
31715					2/20/2008		41		\$0.00
Medium	Work In Progress				2/20/2008 3:49:15 PM				
Castillo, Carlos		Need to replace light bulbs on marque(3light bulbs f2t1 2cwho 800), also need light bulbs for outside lights hps-35w) 08-04							
Carlos Hernandez									
31859	Main Building				2/26/2008		35		\$0.00
Medium	Work In Progress				2/26/2008 8:08:03 AM				
Villalobos, Margret		Theres mice in main office							
Carlos Hernandez									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
32164					3/2/2008		1		\$0.00
Medium	Work In Progress				3/2/2008 12:33:28 AM	3/3/2008			
Hernandez, Carlos		Monthly - Riverside ES A-1 Semiannual MCD - Refer to PM schedule details.							
Margret Villalobos									
32343					3/6/2008		26		\$0.00
Medium	Work In Progress				3/6/2008 11:02:33 AM				
Ronquillo, Ruben		Draper 5-loop surface mount bike racks. 2ea							
Ruben Ronquillo									
32410		Portables			3/10/2008		22		\$0.00
Medium	Work In Progress				3/10/2008 7:58:40 AM				
Castillo, Carlos		Need to connect portable (relocated from GMS).							
Michael Munoz									
32411		Portables			3/10/2008		22		\$0.00
Medium	Work In Progress				3/10/2008 7:59:38 AM				
Villalobos, David		Need to connect portable (relocated from GMS).							
Michael Munoz									
32420		Portables			3/10/2008		22		\$0.00
Medium	Work In Progress				3/10/2008 9:45:24 AM				
Munoz, Michael		Need to connect sidewalk to new relocated portable.							
Michael Munoz									
32423		Portables			3/10/2008		22		\$0.00
Medium	Work In Progress				3/10/2008 10:54:58 AM				
Estrada, Jesus		Need to re-carpet (relocated) portable.							
Michael Munoz									
32611	New Wing 1/02	Classroom			3/14/2008		18		\$0.00
Medium	Work In Progress				3/14/2008 3:40:45 PM				
Villalobos, David		need to replace faucet							
Carlos Hernandez									
32707	New Wing 1/02	Hallway/Corridor			3/25/2008		7		\$0.00
Medium	Work In Progress				3/25/2008 3:26:50 PM				
Ronquillo, Ruben		Skylight was broken and sspd was notified made report case#sp2008000390 need to be replaced							
Carlos Hernandez									
32713	New Wing 1/02	Classroom			3/25/2008		7		\$0.00
Medium	Work In Progress				3/25/2008 3:36:44 PM				
Villalobos, David		Need to replace faucet room 126							
Carlos Hernandez									
Count: 21 Work Orders			Avg. Age of WO's	89			Total for Riverside ES	0	\$0.00

4/1/2008 6:24:39 PM

Page 94 of 126

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: San Miguel ES

24371 7/1/2007 8/1/2007 275 \$0.00

Medium Work In Progress 7/1/2007 12:15:49 AM

Villalobos, David Yearly - San Miguel ES Backflow Inspection - Refer to PMschedule details.

Alfredo Holguin

24372 7/1/2007 8/1/2007 275 \$0.00

Medium Work In Progress 7/1/2007 12:15:49 AM

Villalobos, David Yearly - San Miguel ES Backflow Inspection - Refer to PMschedule details.

Alfredo Holguin

25336 Classroom 8/2/2007 243 \$0.00

Medium Work In Progress all classrooms 8/2/2007 10:56:11 AM

Lozoya, Manny Need Name Plates and numbers for the following staff

- members:
- L. Shoemaker
- K. Andrews
- J. Padilla
- D. Gurrola
- R. Rodriguez
- R. Rhodes
- V. Uranga
- J. Gibbs
- G. Cabral
- J. Llañez
- A. Nuñez
- G. Armendariz-Chavez
- V. Henderson
- M. Lugo
- J. Sachs
- S. Vasquez
- P. Gosnell
- A. Avalos
- M. Gaber
- S. Najera
- D. Sanchez
- R. Gose
- And the following numbers:28,29,30,31,32,33,36,37,38,39,40,42,43,44,45,46,47,48,49,50,51,

Barbara Cardenas

29866 12/6/2007 117 \$0.00

Medium Work In Progress 12/6/2007 1:27:24 PM

Jacquez, Ricardo pump house main shut-off valve (gate valve 2 in.) wont close to main bldg.need to replace .ck annexvalves also 2/20/08 - Route to Rick asp Joe Ontiveros

Danny Vega

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: San Miguel ES

30925					1/24/2008		68		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/24/2008 2:56:17 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
 rm#10 needs to be re-cored off key/this is assitant principals office/high priority test papers are to be kept in this office. please re-core asap

Danny Vega

30931					1/24/2008		68		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/24/2008 3:05:52 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
 rm32 restroom door needs keyed door knob placed thru outside-only to be opened by teacher when needed- thanks please stop by asap

Danny Vega

30997	Classrooms	Portables			1/28/2008		64		\$0.00
-------	------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	36			1/28/2008 3:45:35 PM				
--------	------------------	----	--	--	----------------------	--	--	--	--

Lozoya, Manny
 Sylvia Najera--Rm. 36
 Lost her classroom key needs a replacement

Barbara Cardenas

31509					2/12/2008		49		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/12/2008 1:46:12 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny
 Michael Munoz
 Need to rake and clean under pine trees.

31510					2/12/2008		49		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/12/2008 1:48:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny
 Michael Munoz
 Bus Turnaround - Need to clean up sand around area and also from curbs.

Michael Munoz

31511					2/12/2008		49		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/12/2008 1:49:39 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny
 Michael Munoz
 Need to start irrigating.

31659					2/19/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/19/2008 1:08:13 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
 Danny Vega
 john deere mower needs repaired/deck is loose

32044		Cafeteria			2/29/2008		32		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

High	Work In Progress				2/29/2008 2:33:50 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny
 Michael Munoz
 need remove and dispose all desk, and unused furniture that is on southside. received complaint from community member.

Michael Munoz

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: San Miguel ES

32120					3/2/2008	3/10/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:11 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

32470		Gym			3/11/2008		21		\$0.00
-------	--	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2008 12:51:43 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vega, Danny Ms. Vasquez and Ms. Sanchez are requesting to have Mesh Art Display Boards set up for the District Art Show on Thursday April 17, 2008 at STMS, if they could please be set up by 8:00 a.m. If you have any questions please call them at San Miguel / North Valley. Thank you

Cristina Arevalo

32814					3/28/2008		4		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/28/2008 10:44:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Estrada, Jesus need to inventory all furniture and equipment left at san miguel.

Michael Munoz

32866					4/1/2008		0		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				4/1/2008 5:55:49 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ronquillo, Ruben 54 1/2 x 26 1/4 window broken by vandals in hallway east exit doors (safety wire glass) case#2008-03130

Danny Vega

Count: 16 Work Orders			Avg. Age of WO's 87			Total for San Miguel ES	0		\$0.00
------------------------------	--	--	----------------------------	--	--	--------------------------------	----------	--	---------------

Location: Santa Teresa ES

24432					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24433					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

26342					8/28/2007		217		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/28/2007 8:17:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose STERLING UNIT TO CAFET. PREP AREA IS NOT WORKING. ACTUATOR TO THE LOUVERS IS STUCK.

Gerardo Marquez

4/1/2008 6:24:39 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

26772					9/6/2007		208		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2007 3:52:06 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David DAVID, NEED TO CHECK OUT MOP SINK IN C-WING (CASA ROJA) STILL LEAKING.

Gerardo Marquez

27366					9/24/2007		190		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/24/2007 11:10:28 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos NEED TO CHECK OUT EXIT SIGNS THAT FAILED DURING M. INSP. THEY ARE AT RM. 211, LIBRARY MAIN ENTRANCE, & HALLWAY BY FACULTY RRMS.

Gerardo Marquez

29023					11/7/2007		146		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/7/2007 8:46:04 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David STUCCO IS STARTING TO CRACK AND CHIP AT PARAPETS. BLOCK WORK IS ALSO STARTING TO SEPARATE AT MORTAR JOINTS. SHEETROCK IS ALSO BREAKING ABOVE DOORS, AND AROUND DR. JAMBS. EXPANSION JOINTS IN FLOORS SEEM TO BE SEPARATING , THUS CAUSING VCT. TO CRACK.

Gerardo Marquez

29027					11/7/2007		146		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/7/2007 9:19:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe LUPE; COULD YOU DELIVER A COUPLE OF LOADS OF THE BROWN SCREENING . I NEED TO SPREAD SOME AROUND BY THE PORTABLES AND FRONT AREAS, WHERE THE RAINS HAVE WASHED IT AWAY. THANKS.

Gerardo Marquez

30313					1/6/2008	1/27/2008	86		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:02 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly- Santa Teresa ES Range Hood Cleaning - Refer to PMs schedule details.

Margret Villalobos

30644					1/15/2008		77		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/15/2008 1:26:14 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael ATTN. MIKE. THE SLAB FOR THE DUMPSTERS HAS ALREADY BEEN POURED. NEED TO HAVE FENCE CONTRACTOR BUILD FENCE , AND GATES LIKE THE ONE IN THE PICTURE YOU SENT US. PLEASE BE SURE THEY INCLUDE THE SLATS.

Gerardo Marquez

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

31269					2/4/2008		57		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/4/2008 2:05:25 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose
 JOSE; THE HVAC PUMP IN RM. 203 IS MAKING A LOUD NOISE. IT SEEMS TO BE THE IMPELLER. WOULD YOU CHECK IT OUT?

Gerardo Marquez

31647	Main Building	Classroom			2/15/2008		46		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	RM 108			2/15/2008 4:23:53 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Marquez, Gerardo
 RM 108 HAS A WIDE CRACK ON TOP OF THE ENTRY DOOR. PLEASE CHECK. THANKS.

Rita Mendez

31791					2/22/2008		39		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/22/2008 11:22:39 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose
 JOSE, HVAC IN ART RM. NOT WORKING , PLEASE CHECK OUT.

Gerardo Marquez

31826					2/25/2008		36		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 9:44:30 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben
 ATTN. RUBEN RONQUILLO
 RUBEN, I NEED FOR YOU TO ORDER WINDOW SCREENS FOR PORTABLES E & F. WHEN DELIVERED THEY WERE MISSING THE SCREENS. HERE ARE THE SIZES AND QUANTITIES NEEDED. 2-- 27 5/8"X 28", 4--43 5/8"X16 1/8" THE FRAMES NEED TO BE BRONZE FINISH. THANKS.

Gerardo Marquez

31847					2/25/2008		36		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 3:37:27 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
 ANGEL; AS PER MIKE MUNOZ HE WANTS US TO LET YOU KNOW THAT OUR MOWERS NEED TO BE SERVICED , SO THAT THELL BE READY FOR THE CUTTING SEASON. YOU CAN PICK IT UP AT YOUR EARLIEST CONVENIENCE. THANKS.

Gerardo Marquez

31848					2/25/2008		36		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 3:39:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
 ANGEL, WE HAVE TWO BLOWERS THAT NEED TO BE SERVICED.

Gerardo Marquez

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

31907		Auditorium			2/26/2008		35		\$0.00
-------	--	------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	MUSIC AND ART			2/26/2008 4:10:35 PM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Marquez, Gerardo ASSISTANCE NEEDED WITH SET UP OF ART SHOW ON APRIL 17, 2008 AND ALSO TO TAKE DOWN MATERIALS ON APRIL 21, 2008. THANK YOU.

Rita Mendez

32023					2/29/2008		32		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/29/2008 8:27:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Margret Need someone to come out and check Rooms 210 & 102 Nueron ID #'s are crossing. Technician will be coming out on 3/5 between 9:00 -9:15
Jose Ambriz 3/26/08 - Work completed on 3/18 (E7517 103) J. Villalobos/waiting on invoice.

32029					2/29/2008		32		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/29/2008 8:52:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe ATTN. MIKE MUNOZ. MIKE, AS PER OUR CONVERSATION 2/27/08, THE SAND DRIFTS ALONG THE BACK FENCE AREA ARE GOING TO BE AGAINST THE BACK FENCE SOON. 2/29/08 Asp Mike, hold off until further notice.

Gerardo Marquez

32165					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:29 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo Monthly - Santa Teresa ES A-11 Quarterly ERV - Refer to PMschedule details.

Margret Villalobos

32166					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:29 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo Monthly - Santa Teresa ES C-6 Quarterly HP - Refer to PMschedule details.

Margret Villalobos

32167					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:30 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo Monthly - Santa Teresa ES A-1 Semiannual MCS - Refer to PMschedule details.

Margret Villalobos

32168					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:30 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PMschedule details.

Margret Villalobos

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

32169					3/2/2008		30		\$0.00
Medium	Work In Progress				3/2/2008 12:33:30 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES A-6 Quarterly PUG - Refer to PMschedule details.							

Margret Villalobos

32415					3/10/2008		22		\$0.00
Medium	Work In Progress				3/10/2008 8:58:30 AM				
Gonzales, Angel		ANGEL;TRUCK 107 NEEDS TO HAVE THE OIL CHANGED, AND AND A TUNE UP . PLEASE LET ME KNOW WHEN TO TAKE IT IN. ALSO TRANSMISION SHIFTING REAL HARD.							

Gerardo Marquez

32466	Main Building	Classroom			3/11/2008		21		\$0.00
Medium	Work In Progress	MR. PEREZ'S			3/11/2008 8:43:09 AM				
Marquez, Gerardo		WE NEED FOR BLDG. MECHANIC TO PICK UP A CABINET FROM SAN MIGUEL AND TRANSPORT IT TO OUR SCHOOL.							

Rita Mendez

32704	Main Building	Mechanical Room			3/25/2008		7		\$0.00
Medium	Work In Progress				3/25/2008 3:08:55 PM				
Castillo, Carlos		Water Heater need to install relay to pump.							

David Villalobos

32739		Classroom			3/26/2008		6		\$0.00
Medium	Work In Progress	SPEECH ROOM			3/26/2008 12:54:58 PM				
Marquez, Gerardo		SPEECH DEPT. NEEDS A LARGE HEAVY BOX TRANSPORTED FROM OUR SCHOOL TO SANTA TERESA MIDDLE SCHOOL (TRUCK IS NEEDED TO TRANSPORT-IT DOESN'T FIT IN A CAR). THANKS.							

Rita Mendez

Count: 27 Work Orders			Avg. Age of WO's 81			Total for Santa Teresa ES	0		\$0.00
------------------------------	--	--	----------------------------	--	--	----------------------------------	----------	--	---------------

Location: Santa Teresa HS

24419					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:57 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							

Alfredo Holguin

24420					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							

Alfredo Holguin

4/1/2008 6:24:39 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
24421					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24422					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24423					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24424					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24425					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24426					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
25499		Cafeteria			8/6/2007		239		\$0.00
Medium	Work In Progress				8/6/2007 10:44:10 AM				
Orozco, Danny		NEEDS WATER HOSE FOR USE NEAR DISHMACHINE (DANNY IS AWARE OF THIS REQUEST)							
		OLGA BUSTAMANTE - SNP MANAGER 589-5332							
Alma Terrell									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

25748					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 8:12:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose
NEED SOME ASSISTANCE ON A.C. UNITS ON 600'S WING. BREAKERS #90 FOR EF-17, AND #94 FOR EC -2, WILL NOT STAY ON, NEED TO TROUBLE SHOOT.

Arturo Nunez

27496					9/27/2007		187		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/27/2007 8:31:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
NEED THREE (3) EA. HON LOCKS FOR FILING CABINETS, OVAL AND, ROUND.

Arturo Nunez

29156	Cafeteria (2005)	Cafeteria			11/13/2007		140		\$0.00
-------	------------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2007 9:44:53 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny
WASHING MACHINE THROWING ALOT OF WATER FROM BEHIND THE MACHINE - THEY HAVE TO MOP IT UP CONSTANTLY.

OLGA BUSTAMANTE - SNP MANAGER 589-5332

Alma Terrell

29446					11/27/2007		126		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 10:23:34				
--------	------------------	--	--	--	---------------------	--	--	--	--

Gonzales, Angel
MOFFLER NEEDS TO BE REPLACE FROM TRUCK #8 THANK YOU

Joel Herrera

29451	Gymnasium				11/27/2007		126		\$0.00
-------	-----------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 12:41:32				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David
WE NEED REPLACE SINCK'S FAUCETS AND REPAIR URINAL'S LEACK AT NEW BOYS LOCKER ROOM AT G.Y.M AREA

Joel Herrera

30171					12/18/2007		105		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/18/2007 9:40:57 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Margret
NEED TO HAVE WORK STATION UP GRADE, CAN'T GET TEMP, DIANOSTICS, ETC. TO FAN COIL UNITS, AND AIR HANDLER UNITS.

Arturo Nunez

30314					1/6/2008	1/27/2008	86		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
30936		Classroom			1/24/2008		68		\$0.00
Medium	Work In Progress	SPED classroom			1/24/2008 3:24:59 PM				
Castillo, Carlos		Need electrical outlets installed near cabinet at STHS special ed classroom (please call Silver for questions)							
Cora Ramirez									
31121					1/31/2008		61		\$0.00
Medium	Work In Progress				1/31/2008 9:13:36 AM				
Lara, Ralph		MR. WAGNER HE NEEDS TWO KEYS FROM HIS CLASS ROOM							
Joel Herrera									
31135	Cafeteria (2005)	Cafeteria			1/31/2008		61		\$0.00
Medium	Work In Progress				1/31/2008 2:44:30 PM				
Moncayo, Fernando		WATER IS LEAKING FROM DISHMACHING - IGNACIA RELAYED MESSAGE TO SNP DEPT.							
		OLGA BUSTAMANTE - SNP MANAGER 589-5332							
Alma Terrell									
31252					2/3/2008	2/9/2008	58		\$0.00
Medium	Work In Progress				2/3/2008 12:30:56 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PMSchedule details.							
Margret Villalobos									
31423	Gymnasium				2/8/2008		53		\$0.00
High	Work In Progress				2/8/2008 1:17:21 PM				
Nunez, Arturo		West side of porch, the sheetrock is missing. Please replace and tape and texture (paint). thxs							
Michael Munoz									
31461		Athletic Field			2/11/2008		50		\$0.00
Medium	Work In Progress				2/11/2008 11:04:25 AM				
Ontiveros, Guadalupe		Softball Field - Replace irrigation controls.							
Guadalupe Ontiveros									
31867					2/26/2008		35		\$0.00
Medium	Work In Progress				2/26/2008 9:03:23 AM				
Villalobos, David		NEED A BELL AND GOSSET WATER CIRCULATING PUMP FOR WATER HEATER ON GIRLS RESSROOM.							
Arturo Nunez									
31870					2/26/2008		35		\$0.00
Medium	Work In Progress				2/26/2008 10:37:38 AM				
Ontiveros, Guadalupe		West of Bus Drop off Area- This area is apparently turing into the site dump. dispose of all trash and bring all salvagale itmes to the Physical plant yard.							
Alfredo Holguin									
4/1/2008 6:24:39 PM									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

32008					2/28/2008		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/28/2008 3:35:42 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo		02/27/08 1.0 - CHECKED CHILLER, BOILERS. 1.0 - CHECKED LIGHT ON CAGE HALLWAY REPLACED LIGHT BULBS 2 T/8 @ \$ 1.20 1.0 - REPAIRED DOOR CLOSER ON DRESSING ROOM HALLWAY. 1.0 - EQUIP. DATA REPORT.			2/27 - 4 Material - 2.40				
---------------	--	--	--	--	-----------------------------	--	--	--	--

Arturo Nunez

32122					3/2/2008	3/10/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:12 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32310		Classroom			3/5/2008		27		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	MS.			3/5/2008 3:36:25 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Castillo, Carlos		INSTALL 2 VIDEO PROJECTORS IN CEILING-ELECTRICIAN WORK							
------------------	--	--	--	--	--	--	--	--	--

Marylou Jimenez

32339		Athletic Field			3/6/2008		26		\$0.00
-------	--	----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/6/2008 9:21:05 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe		Need to fix 3 inch water line at Football Field.							
----------------------	--	--	--	--	--	--	--	--	--

Guadalupe Ontiveros

32465					3/11/2008		21		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2008 8:30:22 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph		3/11/08. WE NEED TO REPLACEMENT OF DOOR HANDLE. KEY AREA DOSE NOT WORK IS CONSTANTLY JAMMING. (THIS WORK ORDER IS FOR MANY LOZOYA.)							
-------------	--	--	--	--	--	--	--	--	--

Manuel Prospero

32499					3/11/2008		21		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2008 4:20:10 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		LINE LOCATE AROUND ECONOMICS BUILDING AND NURSE BUILDING - PLEASE CALL SILVER FOR EXACT LOCATION - PLAN B WILL BE DIGGING ON MARCH 17.							
-------------------	--	--	--	--	--	--	--	--	--

Cora Ramirez

32520					3/12/2008		20		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/12/2008 2:07:55 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph		NEED SIX SLIDE LOCKS FOR TROPHY CASES.							
-------------	--	--	--	--	--	--	--	--	--

Arturo Nunez

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

32525					3/12/2008		20		\$0.00
Medium	Work In Progress				3/12/2008 3:34:13 PM				
Ronquillo, Ruben		NEED A WINDOW REPLACED AT ROOM # 40 R.O.T.C. 30X28X 1/8 INSULATED GLASS.							
Arturo Nunez									

32527					3/12/2008		20		\$0.00
Medium	Work In Progress				3/12/2008 3:38:48 PM				
Ambriz, Jose		NEED A MARTHON EHAUST FAN MOTOR. PART # 6311R , MODEL # B.W.H. 48A1703220 , 1/2 H.P, FOR BOYS RESTROOM.							
Arturo Nunez									

32536					3/13/2008		19		\$0.00
Medium	Work In Progress				3/13/2008 8:27:44 AM				
Castillo, Carlos		NEED TO LOCATE UTILITY LINES ON GYM. AREA FOR NEW GYM CONST. AS PER DAVID BOYD.							
Arturo Nunez									

32585					3/14/2008		18		\$0.00
Medium	Work In Progress	Line Locate			3/14/2008 11:53:58 AM				
Castillo, Carlos		Need to line locate on Monday 3/17 @ 8:00am for Plan B (Between Nurse Bldg & ROTC). Any?'s please call Richard w/Plan B @ 915-222-1163.							
Michael Munoz									

32658					3/19/2008		13		\$0.00
Medium	Work In Progress				3/19/2008 10:39:14 AM				
Villalobos, David		NEED SOME ASSISTANCE ON BROKEN AND CRACKED CAST IRON VENT PIPES ON BOYS AND GIRLS RESTROOM ON 300'S WING. EMITTING FOUL SMELL INTO HALLWAY,AND CLASSROOMS.							
Arturo Nunez									

32736					3/26/2008		6		\$0.00
Medium	Work In Progress				3/26/2008 11:14:50 AM				
Castillo, Carlos		Asp PM 32122 Gym Area - Missing 2 Emer. Lights Main Lobby - Missing 2 Emer. Lights Athletic Hall - Missing 1 Emer. Lights							
Manuel Prospero									

Count: 37 Work Orders		Avg. Age of WO's 112			Total for Santa Teresa HS		0		\$0.00
------------------------------	--	-----------------------------	--	--	----------------------------------	--	----------	--	---------------

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

24427					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24428					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24429					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24430					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24431					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24498					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime		Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PMschedule details.							
----------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

24501					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:29 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime		Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PMschedule details.							
----------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

25722	South	Classroom			8/10/2007		235		\$0.00
-------	-------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	ROOM 35			8/10/2007 2:28:12 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Lozoya, Manny		Need key for filing cabinet							
Laura Parra									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

25723	South	Classroom			8/10/2007		235		\$0.00
-------	-------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	36 B			8/10/2007 2:33:23 PM				
--------	------------------	------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Laura Parra
Need key for filing cabinet

25837					8/14/2007		231		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/14/2007 10:09:09 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose
Please order for condensate pump replacement. 35 ea. little giant pumps cat#554200, vcc- 20uls or 2ouls, 35 ea. 1/2" 90 deg. ells. SlipxTHD, 35 ea. SPRTB-6 24x24 metal grilles, 35 ft 3/4" OD x 5/8" ID clear vinyl tube, box of 3 amp fuses, box of 1 amp fuses, box of orange electrical wire nuts, and box of insulated female and male solderless terminals.

Jaime Mijarez

25886	South Building	Classroom			8/15/2007		230		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	room 47			8/15/2007 11:06:16 AM				
--------	------------------	---------	--	--	-----------------------	--	--	--	--

Mijarez, Jaime
Dana Hamel
Install a new pencil sharpener in room 47

26272					8/27/2007		218		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/27/2007 8:51:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
Storm drain in back of S.bldg has a section that is bent inward and sand is caving in through a hole. I showed Alfredo Holguin, please give the work order to Alfredo. ROUTE TO LUPE ASP MIKE 8/30

Jaime Mijarez

28417	North Building	Cafeteria			10/23/2007		161		\$0.00
-------	----------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 12:28:57				
--------	------------------	--	--	--	---------------------	--	--	--	--

Mijarez, Jaime
Baseboard and walls in kitchen by sinks and dishwashing area need to be replaced. This is by order of the NM Environmental Department and the report and the repair must be completed in 60 days. According to ED this is not the first warning about the repairs in an inspection report
Assign to Jaime and Gerry will assist asp Mike 11/13/07 -mkv

Dana Hamel

28722					10/31/2007		153		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/31/2007 9:24:59 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
AS PER OUR CONVERSATION, PLEASE PROVIDE A 120 OUTLET FOR THE ENVIRONMENT DEPT.

Michael Munoz

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

29454	North Building	Office			11/27/2007		126		\$0.00
-------	----------------	--------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 1:54:25 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
 many, i need for you to make a key for some kitchen cabnits in the north office as per ms parra. And also check a panic bar ,see mr rodriguez on this one . thank you.

Ismael Rodriguez

30315					1/6/2008	1/27/2008	86		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/6/2008 12:29:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
 Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

30823	Gym (1997)	Parking Lot			1/22/2008		70		\$0.00
-------	------------	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/22/2008 9:03:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
 Repair the dripping faucet that continues to cause freezing ice and dangerous conditions

Dana Hamel

30838	North Building	Restroom (Girls)			1/22/2008		70		\$0.00
-------	----------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/22/2008 2:09:24 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
 Unisex restroom top floor north building need to have a key CYLINDER THAT ANY KEY WILL OPEN, currently any coin will do and we have found students ditching there.

Dana Hamel

30843	South	Choral			1/22/2008		70		\$0.00
-------	-------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Choir			1/22/2008 2:48:03 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Lara, Ralph
 Need signs over both doors that say "Choir Room"

Laura Parra

30935	South Building				1/24/2008		68		\$0.00
-------	----------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/24/2008 3:22:30 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
 We are going to need electrical outlets installed at Santa Teresa Middle South Bld IDF. We have currently extended electrical using 15' power strips, but need the outlets relocated closer to the cabinets contact Silver.

Cora Ramirez

31013					1/29/2008		63		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/29/2008 9:36:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
 S.bldg water heater room. Need to replace water shut-off valves for irrigation and regulator.

Jaime Mijarez

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

31309	Gym (1997)	Athletic Field			2/5/2008		56		\$0.00
High	Work In Progress				2/5/2008 12:52:31 PM				
Munoz, Michael		LOTS OF CRACKS ON OUTSIDE BASKETBALL COURT. NEED TO REPIAR THEM. STUDENTS CAN TRIP.							

Jaime Mijarez

31624					2/15/2008		46		\$0.00
Medium	Work In Progress				2/15/2008 9:47:53 AM				
Gonzales, Angel		Truck 121, starter might be giving out, more and more I am having trouble getting the truck to start.							

Jaime Mijarez

31803	South Building				2/22/2008		39		\$0.00
Medium	Work In Progress				2/22/2008 3:20:24 PM				
Castillo, Carlos		Santa Teresa Middle South Bld IDF, We have currently extended electrical using 15' power strips, but need the outlets relocated closer to the cabinets.							

Cora Ramirez

32247	North Building	Custodial			3/4/2008		28		\$0.00
Medium	Work In Progress				3/4/2008 9:05:20 AM				
Lara, Ralph		as,per ms .casillas we need to change the door handles in the boys and girls restrooms in the cafeteria for safety reasons.also mr.lara i will be needing 3 L wrenches for the panic bars.thank you see mr rodriguez.							

Ismael Rodriguez

32248	North Building	Cafeteria			3/4/2008		28		\$0.00
Medium	Work In Progress				3/4/2008 9:12:29 AM				
Castillo, Carlos		Need to provide electrical connectors at STMS Kitchen,for service line relocation.Need to be done during Spring break Thanks!!							

Fernando Moncayo

32325	South	Classroom			3/6/2008		26		\$0.00
Medium	Work In Progress	Room 49			3/6/2008 7:56:39 AM				
Lara, Ralph		Key will not open door. Cylinder was changed but does not match key							

Laura Parra

32326	South	Classroom			3/6/2008		26		\$0.00
Medium	Work In Progress	Room 51			3/6/2008 7:57:31 AM				
Lara, Ralph		Key will not open door. Cylinder was changed and key does not match							

Laura Parra

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

32406	North Building	Gym			3/10/2008		22		\$0.00
-------	----------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 7:25:02 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Ismael Rodriguez
the lights in the front porch of the gym are not working.

32407	North Building	Custodial			3/10/2008		22		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 7:30:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Ismael Rodriguez
also,the exterior lights in the front of the north lobby porch are also not working.

32417	South	Electrical Room			3/10/2008		22		\$0.00
-------	-------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Old Teachers			3/10/2008 9:37:41 AM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Lara, Ralph
Laura Parra
Please re-key old teachers lounge. It will be used as an office for Speech Therapist.--- South Building Upstairs

32471	South Building				3/11/2008		21		\$0.00
-------	----------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2008 1:28:07 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Ismael Rodriguez
need to replace two exterior water faucets in order to irrigate the front campus trees there in bad shape.thank you.

32587	Gym (1997)	Gym			3/14/2008		18		\$0.00
-------	------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/14/2008 1:48:26 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael
Michael Munoz
gym floor bubble up due to water leak. need to repair gym floor.

32633	North Building	Custodial			3/18/2008		14		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/18/2008 7:37:39 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
Ismael Rodriguez
manny,i need for you to change the key cylinders for both north and south principals offices in order to go in there and clean.thank you.

32692					3/25/2008		7		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/25/2008 10:39:32 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Estrada, Jesus
Jaime Mijarez
A section of the floor in front of the custodial closet has been lifting up and seems to be getting worst. I have tried to dry it up and to put it back in place but had no luck. Could you send somebody please? Request was sent thru e-mail on Thursday 1/10/2008 10:05 am. Mike Munoz requested work order. Thank you.
Asp Mike assign to Chuy.

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

32733	South	Office			3/26/2008		6		\$0.00
-------	-------	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Assistant			3/26/2008 10:02:58 AM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Lara, Ralph
Laura Parra
Please place lock in refrigerator

32810					2/26/2008		31		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/28/2008 9:25:48 AM	3/28/2008			
--------	------------------	--	--	--	----------------------	-----------	--	--	--

Gonzales, Angel
Gooseneck Trailer lights were broken need to be replaced.

Manuel Barrientos

32818	North Building	Gym			3/28/2008		4		\$0.00
-------	----------------	-----	--	--	-----------	--	---	--	--------

Medium	Work In Progress				3/28/2008 12:38:21 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Soria, Mike
need the tractor to remove sand from behind the gym and also in front of the north office as per pricipal ms casillas .thank you.

Ismael Rodriguez

Count: 38 Work Orders			Avg. Age of WO's 115			Total for Santa Teresa MS	0		\$0.00
------------------------------	--	--	-----------------------------	--	--	----------------------------------	----------	--	---------------

Location: Sunland Park ES

24416					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Yearly - Sunland Park ES Backflow Inspection - Refer to PMschedule details.

Alfredo Holguin

24417					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Yearly - Sunland Park ES Backflow Inspection - Refer to PMschedule details.

Alfredo Holguin

24418					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Yearly - Sunland Park ES Backflow Inspection - Refer to PMschedule details.

Alfredo Holguin

24527					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:39 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel
Yearly - Sunland Park ES Exit Sign Test: Annual - Refer to PMschedule details.

Alfredo Holguin

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

24528					7/1/2007	8/1/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:39 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Yearly - Sunland Park ES Emer. Light Test: Annual - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24529					7/1/2007	7/9/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:40 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.							
------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

24530					7/1/2007	7/9/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:40 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24531					7/1/2007	7/7/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:40 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24532					7/1/2007	7/9/2007	275		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:41 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

24962					7/20/2007		256		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/20/2007 11:45:33 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Please help open two filing cabinets that were accidentally locked during the summer break.							
---------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

25127	Main Building				7/26/2007		250		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/26/2007 3:24:02 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		2nd request - Tile in nurse's office is not level. Safety hazard concern, as student/staff may possibly trip and be injured.				8/2 - Route to M. Prospero. This issue was discussed w/him last year. Mike.			
------------------	--	--	--	--	--	---	--	--	--

Irene Trujillo

25395		Cafeteria			8/3/2007		242		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/3/2007 2:20:24 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny		COLD UNIT TO SERVING LINE IS NOT COLD							
---------------	--	---------------------------------------	--	--	--	--	--	--	--

		MARINA RAMIREZ - SNP MANAGER 589-2524							
--	--	---------------------------------------	--	--	--	--	--	--	--

Alma Terrell

4/1/2008 6:24:39 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

25405					8/3/2007		242		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/3/2007 3:33:00 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny		CLASSROOM 28 - PLEASE INSTALL A DOOR KNOB WITH A LOCK IN THE RESTROOM.							
---------------	--	--	--	--	--	--	--	--	--

Irene Trujillo

25804					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 3:24:36 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		PORTABLE D - NEED A SMALL BOARD SCREWED TO WALL. ALSO, NEED A BACKPACK RACK FIXED.							
------------------	--	--	--	--	--	--	--	--	--

Irene Trujillo

25805					8/13/2007		232		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 3:25:32 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		PORTABLE D - PLEASE INSTALL NEW PENCIL SHARPENER.							
------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

25848					8/14/2007		231		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/14/2007 2:01:40 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		LIBRARY - NEED TO HAVE HOOKS PLACED INSIDE STORAGE ROOM FOR BOOK PUPPETS. ALSO NEED NAILS TO HANG CHARTS.							
------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

25891					8/15/2007		230		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/15/2007 12:33:38 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel		SET UP SCREEN IN THE COMPUTER LAB.							
------------------	--	------------------------------------	--	--	--	--	--	--	--

Irene Trujillo

26135					8/22/2007		223		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/22/2007 9:00:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		PLEASE INSTALL A MARKER BOARD ON THE WALL IN THE LIBRARY.							
------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

26232					8/24/2007		221		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/24/2007 1:20:27 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		2ND REQUEST - PORTABLES NEED PAINTING.							
------------------	--	--	--	--	--	--	--	--	--

Irene Trujillo

26236					8/24/2007		221		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/24/2007 1:31:54 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		CLASSROOM 25 - WATER FLUSING (IT IS STUCK) IN COMMUNE. WATER RUNS FOR 15-20 MINS. THEN STOPS.							
-------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

26344					8/28/2007		217		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/28/2007 8:31:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Holguin, Alfredo		Provide services and materials for installation of new controller to control existing lighting.				Joe V. picked up PO on 9/4-mkv			
------------------	--	---	--	--	--	--------------------------------	--	--	--

Alfredo Holguin

26623					9/2/2007	9/3/2007	212		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-1 Semiannual EVS - Refer to PM schedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

26624					9/2/2007	9/3/2007	212		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-8 Quarterly HPW Unit - Refer to PM schedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

26625					9/2/2007	9/3/2007	212		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-2 Quarterly H/C IREH - Refer to PM schedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

26626					9/2/2007	9/3/2007	212		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-1 Semiannual MCD - Refer to PM schedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

26627					9/2/2007	9/3/2007	212		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-1 Semiannual MCS2 - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

26628					9/2/2007	9/3/2007	212		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-6 Quarterly PUG - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

26629					9/2/2007	9/3/2007	212		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-5 Quarterly SS - Refer to PM schedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

26630					9/2/2007	9/3/2007	212		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				9/2/2007 12:16:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Monthly - Sunland Park ES A-13 Quarterly WREH - Refer to PM schedule details.							
------------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

26843					9/10/2007		204		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/10/2007 2:14:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		PLEASE ASSEMBLE KIDNEY TABLE AND PLACE IN ROOM 12 (MS. C. GARCIA.) THANKS							
------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

26874					9/11/2007		203		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/11/2007 10:10:09 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David		9/11/07. WE HAVE A WATER LEAK ON MECHANICAL ROOM.(IS A WATER VALVE). THIS WORK ORDER IS FOR DAVID VILLALOBOS.							
-------------------	--	---	--	--	--	--	--	--	--

Manuel Prospero

27066					9/17/2007		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/17/2007 8:45:39 AM	9/17/2007			
--------	------------------	--	--	--	----------------------	-----------	--	--	--

Prospero, Manuel		PIGEON PROBLEM IS GETTING WORSE. MANY DROPPINGS AND FEATHERS IN THE FRONT ENTRANCE AND BACK ENTRANCE.				Watson Pest Control was out there on Saturday 9/15. They will be treating this site once a month. Manny Needs to be cleaning up areas as needed.			
------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

27507					9/27/2007		187		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/27/2007 12:32:18 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David		classroom #41 - Toilet needs to be repaired. Do not have enough pressure.							
-------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

27508					9/27/2007		187		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/27/2007 12:37:37 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel		CLASSROOM #12 - BROKEN DESK - PLEASE FIX IT.							
------------------	--	--	--	--	--	--	--	--	--

Irene Trujillo

27509					9/27/2007		187		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/27/2007 12:42:38 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel		PLEASE INSTALL BULLETIN BOARDS. ONE IN ROOM 41 (T. PEREZ) AND THE OTHER IN THE COUNSELOR'S OFFICE.							
------------------	--	--	--	--	--	--	--	--	--

Irene Trujillo

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

27903					10/5/2007		179		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Room 20			10/5/2007 1:34:38 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Villalobos, Margret
 CLASSROOM #20 - PLEASE FUMIGATE! THERE ARE ROACHES OF ALL SIZES AS WELL AS SOME OTHER BLACK BUGS.

Irene Trujillo

28127					10/15/2007		169		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/15/2007 10:16:34				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, Margret
 NEED HELP! THERE IS A HUGE RAT IN THE CUSTODIAN'S ROOM. THE CUSTODIAN SAW IT CRAWL FROM THE ROOM UP TO THE ROOF AREA. Need price quote!

Irene Trujillo

28178					10/16/2007		168		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/16/2007 10:01:32				
--------	------------------	--	--	--	---------------------	--	--	--	--

Prospero, Manuel
 The ramps on portables need to be painted. Also, this is a reminder portables have not been painted (previously submitted request)

Irene Trujillo

28192					10/16/2007		168		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/16/2007 3:07:59 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel
 2ND REQUEST TO HAVE THE PORTABLES PAINTED.

Irene Trujillo

28273					10/18/2007		166		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/18/2007 1:55:04 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
 CLASSROOM 25 - THE DOOR WHICH LEADS TO THE OUTSIDE NEEDS TO BE REPLACED.

Irene Trujillo

28542					10/25/2007		159		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/25/2007 1:24:32 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David
 CLASSROOM #24 - UNCLOG SINK

Irene Trujillo

28721					10/31/2007		153		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/31/2007 9:24:25 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
 AS PER OUR CONVERSATION, PLEASE PROVIDE A 120 OUTLET FOR THE ENVIRONMENT DEPT.

Michael Munoz

29221					11/14/2007		139		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/14/2007 1:49:39 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel
 PLEASE HANG 10 FRAMED POSTERS THROUGHOUT THE SCHOOL BUILDING.

Irene Trujillo

4/1/2008 6:24:39 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

29692					12/2/2007	12/3/2007	121		\$0.00
Medium	Work In Progress				12/2/2007 12:30:23 AM				
Prospero, Manuel		Monthly - Sunland Park ES A-13 Quarterly WREH - Refer to PM schedule details.							
Margret Villalobos									
29698					12/2/2007	12/3/2007	121		\$0.00
Medium	Work In Progress				12/2/2007 12:30:26 AM				
Prospero, Manuel		Monthly - Sunland Park ES A-2 Quarterly H/C IREH - Refer to PM schedule details.							
Margret Villalobos									
29699					12/2/2007	12/3/2007	121		\$0.00
Medium	Work In Progress				12/2/2007 12:30:26 AM				
Prospero, Manuel		Monthly - Sunland Park ES A-6 Quarterly PUG - Refer to PM schedule details.							
Margret Villalobos									
29720					12/2/2007	12/3/2007	121		\$0.00
Medium	Work In Progress				12/2/2007 12:30:34 AM				
Prospero, Manuel		Monthly - Sunland Park ES A-8 Quarterly HPW Unit - Refer to PM schedule details.							
Margret Villalobos									
29723					12/2/2007	12/3/2007	121		\$0.00
Medium	Work In Progress				12/2/2007 12:30:35 AM				
Prospero, Manuel		Monthly - Sunland Park ES A-5 Quarterly SS - Refer to PM schedule details.							
Margret Villalobos									
30316					1/6/2008	1/27/2008	86		\$0.00
Medium	Work In Progress				1/6/2008 12:29:04 AM				
Orozco, Danny		Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
30712	Main Building	Athletic Field			1/16/2008		76		\$0.00
Medium	Work In Progress				1/16/2008 4:17:40 PM				
Ontiveros, Guadalupe		Clean out drains at main entrance. Also cut weeds around back stop and playarea							
Guadalupe Ontiveros									
30957					1/25/2008		67		\$0.00
Medium	Work In Progress				1/25/2008 1:32:50 PM				
Villalobos, Margret		MICE DROPPINGS IN THE TEACHER'S LOUNGE AND OFFICE STORAGE ROOM.							
Irene Trujillo									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

31661					2/19/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/19/2008 1:36:47 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		WE HAVE PROBLEMS WITH WATER HEATING AT KITCHEN							
-------------------	--	--	--	--	--	--	--	--	--

Joel Herrera

31830					2/25/2008		36		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 1:29:12 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		WE NEED TO REPLACE THE RELIEF VALVE ON THE BOILER.							
--------------	--	--	--	--	--	--	--	--	--

Joel Herrera

31861		Electrical Room			2/26/2008		35		\$0.00
-------	--	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/26/2008 8:18:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		Southern schools several outside electrical boxes need to be painted over to stop severe corrosion. Need to do this as soon as possible!!							
------------------	--	---	--	--	--	--	--	--	--

Carlos Castillo

31958					2/27/2008		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2008 3:47:51 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Joel		2-27-08 8.0 HELP TO MANNY BARRIENTOS AND RAMIRO TO CLEAN UP OUTSIDE OF SCHOOL IS TOO MUCH SAND			2/27-8				
---------------	--	--	--	--	--------	--	--	--	--

Joel Herrera

32115					3/2/2008	3/10/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:09 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Joel		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

32124					3/2/2008	3/10/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:12 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Joel		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32171					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:31 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Joel		Monthly - Sunland Park ES A-1 Semiannual EVS - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

32172					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:32 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Joel		Monthly - Sunland Park ES A-8 Quarterly HPW Unit - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

4/1/2008 6:24:39 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

32173					3/2/2008		30		\$0.00
Medium	Work In Progress				3/2/2008 12:33:32 AM				
Herrera, Joel		Monthly - Sunland Park ES A-2 Quarterly H/C IREH - Refer to PM schedule details.							
Margret Villalobos									

32174					3/2/2008		30		\$0.00
Medium	Work In Progress				3/2/2008 12:33:32 AM				
Herrera, Joel		Monthly - Sunland Park ES A-1 Semiannual MCD - Refer to PM schedule details.							
Margret Villalobos									

32175					3/2/2008		30		\$0.00
Medium	Work In Progress				3/2/2008 12:33:33 AM				
Herrera, Joel		Monthly - Sunland Park ES A-1 Semiannual MCS2 - Refer to PM schedule details.							
Margret Villalobos									

32176					3/2/2008		30		\$0.00
Medium	Work In Progress				3/2/2008 12:33:33 AM				
Herrera, Joel		Monthly - Sunland Park ES A-6 Quarterly PUG - Refer to PM schedule details.							
Margret Villalobos									

32177					3/2/2008		30		\$0.00
Medium	Work In Progress				3/2/2008 12:33:34 AM				
Herrera, Joel		Monthly - Sunland Park ES A-5 Quarterly SS - Refer to PM schedule details.							
Margret Villalobos									

32178					3/2/2008		30		\$0.00
Medium	Work In Progress				3/2/2008 12:33:34 AM				
Herrera, Joel		Monthly - Sunland Park ES A-13 Quarterly WREH - Refer to PM schedule details.							
Margret Villalobos									

32349					3/6/2008		26		\$0.00
Medium	Work In Progress				3/6/2008 1:00:50 PM				
Villalobos, David		I NEED REPLACE MOPSINK FAUCET AT CUSTODIANS CLOSET							
Joel Herrera									

32731					3/26/2008		6		\$0.00
Medium	Work In Progress				3/26/2008 9:12:48 AM				
Ontiveros, Guadalupe		WE NEED THE TRACKTOR TO CLEANUP AND REMOVED SAND AT SCH00L FRONT AREA							
Joel Herrera									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

32775					3/27/2008		5		\$0.00
Medium	Work In Progress				3/27/2008 11:06:53 AM				
Villalobos, David		WE NEED TO REPLACE WATER FAUNTAIN FAUCETE ITS LEAKING AGAIN AT ROOM 38							
Joel Herrera									

32820					3/28/2008		4		\$0.00
Medium	Work In Progress				3/28/2008 2:44:04 PM				
Lara, Ralph		WE NEED 12 PADLOCKS AND 10' FEET OF CHAIN TO SECURE ALL DOORS							
Joel Herrera									

32838					3/31/2008		1		\$0.00
Medium	Work In Progress				3/31/2008 8:29:22 AM				
Lara, Ralph		MS. GOMEZ BROKEN HER POTABLE'S KEY AND WE NEED REPLACE IT							
Joel Herrera									

32863					3/31/2008		1		\$0.00
Medium	Work In Progress				3/31/2008 4:05:10 PM				
Villalobos, Margret		WE HAVE CUCARACHAS AND ASQUELES AT CLASS ROOMS #37, 38 AND 41							
Joel Herrera									

Count: 71 Work Orders Avg. Age of WO's 149 Total for Sunland Park ES 0 \$0.00

Location: Sunrise ES

32180					3/2/2008		30		\$0.00
Medium	Work In Progress				3/2/2008 12:33:35 AM				
Quinones, Paul		Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM schedule details.							
Margret Villalobos									

24414					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:56 AM				
Villalobos, David		Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

24415					7/1/2007	8/1/2007	275		\$0.00
Medium	Work In Progress				7/1/2007 12:15:56 AM				
Villalobos, David		Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunrise ES

29471					11/27/2007		126		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 4:20:26 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
REQUESTING RED COLORD SCREENING FOR SIDEWALKS NEXT TO THE PORTABLES,AND BACK OF PRIMARY PLAY GROUND AREAS

Paul Quinones

30685		Classroom			1/16/2008		76		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	p-8			1/16/2008 12:56:03 PM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lozoya, Manny
I need to have an extra key for portable 8 We will be having detention in this portable and our Coach will need access key# 1c88.

Joanne Munoz

31156					2/1/2008		60		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/1/2008 7:56:27 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Jacquez, Ricardo
BACK FENCE LINE,REQUESTING WIND SCREEN ESTIMATE LENGTH OF APPROX. 250'. THANKS

Paul Quinones

31451					2/11/2008		50		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/11/2008 7:40:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben
ROOMS 201, 208, 209, 212, OFFICE (5 1/2 X 38 WIRE MESH ON DOOR) WINDOWS BROKEN DURING WEEKEND, DUE TO BREAK IN. NEED TO REPLACE AS SOON AS POSSIBLE. THANKS (CASE#200801467)
OTHER ITEMS MISSING: 1 BAGGY W/4-5 MEMORY STICKS, 1 LEAP PAD, LABLE MAKER.

Paul Quinones

31962					2/27/2008		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2008 3:57:37 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
NEED TO REPLACE BROKEN LAMP COVERS IN NURSES STATION,STAFFS REST RM. IN WING B,AND STAFFS REST RM.IN WING C. AS WELL.THANKS

Paul Quinones

32117					3/2/2008	3/10/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:09 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul
Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PMschedule details.

Margret Villalobos

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunrise ES

32125					3/2/2008	3/10/2008	30		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:13 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

32179					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:34 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul		Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM schedule details.							
----------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32181					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul		Monthly - Sunrise ES A-1 Semiannual MCS - Refer to PM schedule details.							
----------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32182					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul		Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details.							
----------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

32183					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul		Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.							
----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

32185					3/2/2008		30		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:37 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Jacquez, Ricardo		Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

32670					3/19/2008		13		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/19/2008 2:07:10 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		REQUESTING 4 PAD LOCKS FOR BACK FIELD ENTRANCES THANKS							
---------------	--	--	--	--	--	--	--	--	--

Paul Quinones

32778	Main Building	Portables			3/27/2008		5		\$0.00
-------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	P-6 AND P-5			3/27/2008 1:49:42 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Quinones, Paul		Need wheels on portable cabinets to be replaced or fixed one in each portable.							
----------------	--	--	--	--	--	--	--	--	--

Joanne Munoz

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunrise ES

32881					4/1/2008		0		\$0.00
Medium	Work In Progress				4/1/2008 3:08:51 PM				
Ontiveros, Guadalupe		REQUESTING AERATE BACK GRASS FIELD							
Paul Quinones									

Count: 18 Work Orders Avg. Age of WO's 64 Total for Sunrise ES 0 \$0.00

Location: Vado ES

27650					9/30/2007	10/21/2007	184		\$0.00
Medium	Work In Progress				9/30/2007 12:17:45 AM				
Orozco, Danny		Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									

29332					11/19/2007		134		\$0.00
Medium	Work In Progress				11/19/2007 9:17:26 AM				
Sotelo, Enrique		need light covers for lights in restroom 100-wing							
Danny Miranda									

29940					12/10/2007		113		\$0.00
Medium	Work In Progress				12/10/2007 11:33:33				
Villalobos, Margret		RMS 211 & 212 WIRES ARE CROSSED AND 210 & 211 ARE ON THE SAME WIRES THIS HAPPENED ON THE INITIAL SETUP A LONG TIME NOW (JUST FIGURED IT OUT NOW) There should be no charge for this - should be under warranty.							
Danny Miranda									

30436					1/9/2008		83		\$0.00
Medium	Work In Progress				1/9/2008 3:02:16 PM				
Lozoya, Manny		need to repair teachers restroom door knob door can't be opened from inside teachers are locking themselves inside							
Danny Miranda									

30680					1/16/2008		76		\$0.00
Medium	Work In Progress				1/16/2008 10:34:24 AM				
Villalobos, Margret		NEED SOMEONE TO CK. TRACER SUMMIT CLASSROOM'S MUST BE RESET EVERY MORNING AND AGAIN DURING THE DAY SEVERAL TIMES				1/17 - Eddie came out today to check on problem			
Danny Miranda									

30943					1/24/2008		68		\$0.00
Medium	Work In Progress				1/24/2008 3:54:33 PM				
Villalobos, Margret		Asp Jose Ambriz the need to replace board on BCU. Unable to communicate w/site. (Please advise when someone will be coming out so we can send one of our Technicians) Thanks.							
Jose Ambriz									

4/1/2008 6:24:40 PM

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
30956					1/25/2008		67		\$0.00
Medium	Work In Progress				1/25/2008 1:06:11 PM				
Sotelo, Enrique		A-Wing - no power to several several classrooms.							
Enrique Sotelo									
31188					2/3/2008	2/9/2008	58		\$0.00
Medium	Work In Progress				2/3/2008 12:30:30 AM				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
31225					2/3/2008	2/11/2008	58		\$0.00
Medium	Work In Progress				2/3/2008 12:30:46 AM				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
31233					2/3/2008	2/11/2008	58		\$0.00
Medium	Work In Progress				2/3/2008 12:30:49 AM				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
31310	Main Building	Classroom			2/5/2008		56		\$0.00
Medium	Work In Progress				2/5/2008 1:02:35 PM				
Miranda, Danny		RAISE HANDICAP BAR IN SPECIAL NEEDS ROOM 101							
Debra Facio									
31467					2/11/2008		50		\$0.00
Medium	Work In Progress				2/11/2008 1:10:09 PM				
Villalobos, Margret		need to spray classroom's for spiders & bugs							
Danny Miranda									
31592					2/14/2008		47		\$0.00
Medium	Work In Progress				2/14/2008 10:08:00 AM				
Lozoya, Manny		NEED TO REPLACE DOOR KNOB IN CUSTODIAL RM. 100-WING HANDLE WILL NOT STAY ON							
Danny Miranda									
31593					2/14/2008		47		\$0.00
Medium	Work In Progress				2/14/2008 10:10:09 AM				
Sotelo, Enrique		NEED 5 BATTERY PACKS FOR EXIT SIGNS							
Danny Miranda									

901 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Vado ES							
31745					2/21/2008		40		\$0.00
Medium	Work In Progress				2/21/2008 12:23:59 PM				
Sotelo, Enrique		need to put in two lights in r.r. in rm. 103							
Danny Miranda									
31746					2/21/2008		40		\$0.00
Medium	Work In Progress				2/21/2008 12:25:04 PM				
Miranda, Danny		need to put in curtin divider in r.r. to rm. 103							
Danny Miranda									
31793					2/22/2008		39		\$0.00
Medium	Work In Progress				2/22/2008 1:52:35 PM				
Sotelo, Enrique		need to check electric heater in sp. ed. room 103 will not turn off							
Danny Miranda									
Count: 17 Work Orders		Avg. Age of WO's		72	Total for Vado ES			0	\$0.00
Count: 901 Work Orders		Avg. Age of WO's		112	Grand Total			7	\$175.00