

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Alma Del Valle Daycare

32043					2/29/2008		89		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/29/2008 2:31:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe joe as per our conversation, please move washer and drier and also stove and store at Lamesa.

Michael Munoz

32725					3/26/2008		63		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/26/2008 7:45:24 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Miranda, Danny NEED TO VARNISH NEW DOOR IN INFANTS WASHER AND DRYER AREA

Danny Miranda

Count: 2 Work Orders			Avg. Age of WO's 76			Total for Alma Del Valle Daycare	0		\$0.00
-----------------------------	--	--	----------------------------	--	--	---	----------	--	---------------

Location: Anthony ES

24366					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

25385	Main Building	Custodial			8/3/2007		299		\$0.00
-------	---------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/3/2007 11:57:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel repair weed eater

David Vega

26750	Cafeteria	Cafeteria			9/6/2007		265		\$0.00
-------	-----------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2007 12:38:20 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny As per Mr. Giovas, he was there at Anthony Elementary, water is leaking from the top and bottom pipes to the dishwashing machine.

Rebecca Saenz - SNP Manager 882-3507

Alma Terrell

27868	Main Building	Office			10/4/2007		237		\$0.00
-------	---------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/4/2007 11:04:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny WE WILL BE NEEDING TO CHANGE THE LOCK FOR THE SUPPLY ROOM IN THE MAIN AND PRIMARY BUILDING. WE WILL BE NEEDING 9 ADDITIONAL KEYS. IF YOU HAVE ANY QUESTIONS PLEASE FREE TO CONTACT ME.

Loraine Gandara

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
28350					10/19/2007		222		\$0.00
Medium	Work In Progress	Anthony On Track			10/19/2007 4:48:27 PM				
Ronquillo, Ruben		Blinds for windows (6) in office portable and in two classrooms. 4- 47 x 37 2- 33 x 62							
Lucy Meza									
28492	Dona Ana	Office			10/24/2007		217		\$0.00
Medium	Work In Progress				10/24/2007 3:14:21 PM				
Lara, Ralph		Need to charge locks for p.e and office							
Hector Villalobos									
28563		Classroom			10/25/2007		216		\$0.00
Medium	Work In Progress	Pre - K			10/25/2007 3:46:59 PM				
Ronquillo, Ruben		P.R.E.K headstart rooms 306 307 blinds 12 63x54							
Hector Villalobos									
29151	Original Main	Classroom			11/13/2007		197		\$0.00
Medium	Work In Progress				11/13/2007 9:07:01 AM				
Lozoya, Manny		WE NEED AN KEYS FOR ROOM 206 SPEECH ROOM...							
Loraine Gandara									
29390	Chapter I	Classroom			11/26/2007		184		\$0.00
Medium	Work In Progress				11/26/2007 8:21:25 AM				
Lozoya, Manny		Chapter blg music room borken lock can not open							
Hector Villalobos									
29811		Portables			12/4/2007		176		\$0.00
Medium	Work In Progress				12/4/2007 3:02:11 PM				
Lozoya, Manny		PT219 need a key made for filing cabinet							
Hector Villalobos									
29812		Portables			12/4/2007		176		\$0.00
Medium	Work In Progress				12/4/2007 3:04:29 PM				
Lozoya, Manny		Headstrat pt 1 need a keymade for filing cabinet							
Hector Villalobos									
29900					11/26/2007		184		\$0.00
Medium	Work In Progress				12/7/2007 9:33:21 AM				
Villalobos, Hector		NEW PLAYGROUND SHATE WAS CUT 3 TIMES.				4/23 As per Mike, please remove.			
Hector Villalobos									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

29903	Original Main	Office			12/7/2007		173		\$0.00
Medium	Work In Progress				12/7/2007 9:39:26 AM				
Lozoya, Manny		Old main blg new office cabinet and filing cabinet need keys made							

Hector Villalobos

29930		Portables			12/10/2007		170		\$0.00
Medium	Work In Progress				12/10/2007 10:27:27				
Solis, Lorenzø		pt 221 replace heater.							

Hector Villalobos

30908					1/24/2008		125		\$0.00
Medium	Work In Progress				1/24/2008 11:02:52 AM				
Lozoya, Manny		Provide me with a list of individuals who have keys to the gates on this campus							

Alfredo Holguin

31029	Main Building	Classroom			1/29/2008		120		\$0.00
Medium	Work In Progress				1/29/2008 2:32:28 PM				
Sotelo, Enrique		Replace brun out lamps and ballast in milg blg							

Hector Villalobos

31463		Athletic Field			2/11/2008		107		\$0.00
High	Work In Progress				2/11/2008 11:27:42 AM				
Villalobos, Hector		Barbwire supports for fencing will be ordered (35). Please install when they are in. Norht fence by apartments.							

thxs

Michael Munoz

31465					2/11/2008		107		\$0.00
High	Work In Progress				2/11/2008 11:35:19 AM				
Villalobos, Hector		warehouse will be purchasing no trespassing signs(15) please install on north of campus by apt.							

thxs

Michael Munoz

31589		Portables			2/14/2008		104		\$0.00
Medium	Work In Progress				2/14/2008 9:10:45 AM				
Ronquillo, Ruben		Broken windows portable (221 & 203) Parenting Lab							

Headstart size 42 3/4 x14 1/2
(PT 3 & \$ Stolen computer, radio, 3 box of meat)
(Parenting Lab- Computer)
CASE# 2008-01608 Ben Casillas

Hector Villalobos

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
31650	Main Building	Hallway/Corridor			2/19/2008		99		\$0.00
Medium	Work In Progress				2/19/2008 7:18:12 AM				
Lozoya, Manny Hector Villalobos break in milg blg need to order new panic bars 6									
32869		Portables			4/1/2008		57		\$0.00
Medium	Work In Progress				4/1/2008 9:00:52 AM				
Ronquillo, Ruben Hector Villalobos Pt 1 broken window 22 1/2 X 34 1/3 (DEP. S. BAYLES 649 CASE# 2008-02673)									
32960	Annex Building	Classroom			4/4/2008		54		\$0.00
Medium	Work In Progress				4/4/2008 7:26:24 AM				
Lozoya, Manny Hector Villalobos need locks for cabinet and desk a.s.a.p. room 201									
32961		Parking Lot			4/4/2008		54		\$0.00
Medium	Work In Progress				4/4/2008 7:33:04 AM				
Lozoya, Manny Hector Villalobos parking lot need a new lock mild bld									
33049					4/6/2008	4/27/2008	52		\$0.00
Medium	Work In Progress				4/6/2008 12:18:18 AM				
Orozco, Danny Margret Villalobos Monthly - Anthony ES Fire Suppression Insp. - Refer to PM schedule details.									
33211	Dona Ana	Office			4/9/2008		49		\$0.00
Medium	Work In Progress				4/9/2008 7:26:16 AM				
Lozoya, Manny Hector Villalobos need to charge lock on door									
33334	Annex Building	Classroom			4/11/2008		47		\$0.00
Medium	Work In Progress				4/11/2008 1:43:24 PM				
Ronquillo, Ruben Hector Villalobos broken window 37x14 wire glass room 204									
33579	Original Main	Classroom			4/21/2008		37		\$0.00
Medium	Work In Progress				4/21/2008 1:18:06 PM				
Lozoya, Manny Loraine Gandara POA NEEDS KEYS FOR CABINETS...									
33659	Original Main	Classroom			4/23/2008		35		\$0.00
Medium	Work In Progress				4/23/2008 8:37:59 AM				
Ronquillo, Ruben Hector Villalobos Room 101 broken window 12x18									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

33660	Cafeteria				4/23/2008		35		\$0.00
Medium	Work In Progress				4/23/2008 8:40:37 AM				
Ronquillo, Ruben		Old cafeteria broken window 19 1/2 x15 3/4							
Hector Villalobos									
33939	Cafeteria				5/2/2008		26		\$0.00
Medium	Work In Progress				5/2/2008 7:21:54 AM				
Ronquillo, Ruben		borken widow 19 1/2 x153/4							
Hector Villalobos									
33941	Chapter I	Classroom			5/2/2008		26		\$0.00
Medium	Work In Progress				5/2/2008 8:06:44 AM				
Lozoya, Manny		Music room wind blow door off hinges							
Hector Villalobos									
33942	Main Building	Office			5/2/2008		26		\$0.00
Medium	Work In Progress				5/2/2008 8:12:28 AM				
Lozoya, Manny		OFFICE WILL NEED NEW LOCK AND NEW KEYS...							
Loraine Gandara									
33973					5/4/2008	5/10/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:18:57 AM				
Villalobos, Hector		Monthly - Anthony ES Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
33993					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:04 AM				
Villalobos, Hector		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
33995					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:04 AM				
Villalobos, Hector		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
34081	Cafeteria	Cafeteria			5/6/2008		22		\$0.00
Medium	Work In Progress				5/6/2008 8:59:13 AM				
Orozco, Danny		REACH IN FREEZER IS AT 20 DEGREES - IT'S COLD BUT FOOD IS NOT FROZEN							
		REBECCA SAENZ - SNP MANAGER 882-3507							
Alma Terrell									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
34266	Main Building	Classroom			5/13/2008		15		\$0.00
Medium	Work In Progress				5/13/2008 1:34:30 PM				
Ronquillo, Ruben		Mid Bldg - Room 23 broken window size 22x58 1/2 wire glass							
Hector Villalobos									
34442	Cafeteria				5/20/2008		8		\$0.00
Medium	Work In Progress				5/20/2008 1:24:02 PM				
Villalobos, Hector		need two a/c pumps mild blg cafetria							
Hector Villalobos									
34452	Main Building	Classroom			5/20/2008		8		\$0.00
Medium	Work In Progress				5/20/2008 3:17:53 PM				
Villalobos, Hector		room 12 install locks on wall cabinet							
Hector Villalobos									
34454	Main Building	Classroom			5/20/2008		8		\$0.00
Medium	Work In Progress				5/20/2008 3:19:58 PM				
Villalobos, Hector		room 13 install locks on wall cabinets							
Hector Villalobos									
34457	Main Building	Office			5/20/2008		8		\$0.00
Medium	Work In Progress				5/20/2008 3:24:35 PM				
Villalobos, Hector		mild blg Ms Dominguez office install locks on cabinet							
Hector Villalobos									
34490		Classroom			5/21/2008		7		\$0.00
Medium	Work In Progress	ANTHONY			5/21/2008 2:04:40 PM				
Lozoya, Manny		AS PER ANN S. - TO PLEASE PUT A DOOR BETWEEN THE TWO CLASSROOMS. (LIZ RUIZ AND MARCIA BENTO)							
Mary Garcia									
34558					5/23/2008		5		\$0.00
Medium	Work In Progress				5/23/2008 8:36:27 AM				
Villalobos, Hector		Supplies used to start a/c units							
Hector Villalobos									
34559		Football Field			5/23/2008		5		\$0.00
Medium	Work In Progress				5/23/2008 8:41:15 AM				
Villalobos, Hector		Repair bronken sprinklers chapter scooer field							
Hector Villalobos									
34593	Main Building				5/27/2008		1		\$0.00
Medium	Work In Progress	LINE LOCATE			5/27/2008 7:46:38 AM				
Villalobos, David		Need to line locate by boiler room.							
Michael Munoz									
Count: 45 Work Orders			Avg. Age of WO's	97		Total for Anthony ES	0	\$0.00	

5/28/2008 3:23:46 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

26824	Main Building	Gym			9/10/2007		261		\$0.00
-------	---------------	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	5058822242			9/10/2007 6:54:35 AM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
LOCK TO HATCH TO ROOF WAS BROKEN OFF
DURING THE BREAK IN NEEDS TO BE REPLACED

Jimmy Cortez

28572		Cafeteria			10/26/2007		215		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/26/2007 8:57:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny
Having problems with Dishwasher - Tom/Ecolab
checked the DW-his recommendation: repair or replace
the vacuum breaker and repair or replace the solenoid
valve for the final rinse.

Aida Salcedo - SNP Coord. 882-6772 and Elsa Chairez
- SNP Manager 882-2417

Alma Terrell

29029					11/7/2007		203		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/7/2007 9:26:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
BROKEN FLOOR TILES THROUGHOUT FACILITY -
REPEAT VIOLATION FROM ENVIRONMENT
INSPECTION DEPARTMENT.

AIDA SALCEDO - SNP COMPLIANCE COORDINATOR
882-6772
ELSA CHAIREZ - SNP MANAGER - 882-2417

Alma Terrell

30777	Main Building	Hallway/Corridor			1/18/2008		131		\$0.00
-------	---------------	------------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/18/2008 9:17:54 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan
TILES NEED TO BE EXCHANGED CRACKED IN MAIN
HALL AND ENTRANCE AS PER JESUS ESTRADA - ROUTE TO
BUILDING MECHANIC

Jimmy Cortez

30778		Restroom (Boys)			1/18/2008		131		\$0.00
-------	--	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/18/2008 9:29:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan
BASEBOARDS NEEDS TO BE REPLACED IN ALL 8
SMALL RESTROOMS BOYS AND GIRLS IN
CLASSROOMS 100 101 105 104 AS PER JESUS ESTRADA - ROUTE TO
BLDG MECH.

Jimmy Cortez

30827					1/22/2008		127		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/22/2008 10:01:06 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Holguin, Ramiro
Portable 157 - Window was left open and they went in
and stole the overhead projector.
(Case# 2008-00879) est loss 150.00

Maribel Chavez

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

31053	Main Building	Library			1/30/2008		119		\$0.00
-------	---------------	---------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			1/30/2008 10:40:38 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lozoya, Manny
Adan Duran
Library - Door knob is coming loose.

31054		Portables			1/30/2008		119		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			1/30/2008 10:41:13 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lozoya, Manny
Adan Duran
Portable 158- Door knob is coming loose.

31055	Main Building	Restroom (Boys)			1/30/2008		119		\$0.00
-------	---------------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			1/30/2008 10:42:13 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ontiveros, Joe
Adan Duran
Kinder Classroom (Boys RR) - Need a bowl wax.

31633					2/15/2008		103		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			2/15/2008 2:59:37 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Moncayo, Fernando
Adan Duran
MR JOSE AMBRIZ SIR EXHUAST FAN ROOM 100
MOTOR IS NOT WORKING NEED TO REPLACE
THANK YOU SIR AND GOD BLESS

31706					2/20/2008		98		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/20/2008 3:12:15 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe
Adan Duran
MR LUPE ONTIVEROS SIR THE IRRIGATION TIMER
IN FRONT IS NOT WORKING ALL IRRIGATION HAS
TO BE DONE BY HAND THE IRRIGATION BOX
NAME IS IRRI-TROL HAVE BEEN TOLD BY MR
HOLGIN THAT IT HAS NOT WORKED OVER A YEAR
WOULD YOU HAVE SOME ONE LOOK AT IT PLEASE
THANK YOU SIR AND GOD BLESS

32003					2/28/2008		90		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/28/2008 3:12:46 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose
Adan Duran
MR JOSE AMBRIZ SIR THE BOILER ON THE RIGHT
SIDE THE ONE MR SOLIS CHANGE THE CONTROL
IS MAKING A LOT OF NOISE BAD ITS HAMMERING
SOMETHING IS NOT RIGHT WILL NEED TO CHECK
OUT THANK YOU SIR AND GOD BLESS

32396					3/7/2008		82		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			3/7/2008 3:32:19 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Sotelo, Enrique
Adan Duran
MR ENRIQUE SOTELO LAS EMERGENCE LIGHT EN
EL WEST SIDE GIRLS BATHROOM Y LOS MEN
NESISITAN BATTERIES Y EL STORAGE EN LA
CAFETERIA THANK YOU SIR

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

32523					3/12/2008		77		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/12/2008 3:25:02 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
MR ENRIQUE SOTELO SENOR SOTELO LA LUZ EN EL POSTE ESTA QUEBRIDA EL PLASTIC COVER TAMBIEN POR FAVOR QUENDO PUEDA CHECK IT PLEASE ESTA EN LOS PORTABLES THANK YOU SIR

Adan Duran

32898					3/31/2008		58		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/1/2008 4:09:33 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Duran, Adan
Torn Screens (OFFICER APODACA 880 CASE# 2008-03132)

Jimmy Cortez

33004					4/6/2008	4/12/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan
Monthly - Berino ES Monthly FE Inpsection - Refer to PMschedule details.

Margret Villalobos

33021					4/6/2008	4/14/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:09 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan
Monthly - Berino ES Roof Inspection - Refer to PM schedule details.

Margret Villalobos

33044					4/6/2008	4/27/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:16 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

33050					4/6/2008	4/27/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:18 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
Monthly - Berino ES Fire Suppression Insp. - Refer to PMschedule details.

Margret Villalobos

33071					4/6/2008	4/14/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:25 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan
Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PMschedule details.

Margret Villalobos

33074					4/6/2008	4/14/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan
Monthly - Berino ES Emer. Light Test: Monthly - Refer to PMschedule details.

Margret Villalobos

5/28/2008 3:23:46 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

33189 Cafeteria 4/8/2008 50 \$0.00
 Medium Work In Progress 4/8/2008 1:17:04 PM
 Sanchez, Raul FILTER NEEDS TO BE CHANGED TO THE WATER.
 ITS COMING OUT YELLOW.
 ELSA CHAIREZ - 882-2417

Jacqueline Aguilar
 33623 Cafeteria 4/22/2008 36 \$0.00
 Medium Work In Progress 4/22/2008 8:41:19 AM
 Orozco, Danny WALK-IN REFRIG. TEMP. STAYS AROUND 45 AND
 UP. RIGHT NOW IT IS AT 48.
 ELSA CHAIREZ - SNP MGER 882-2417

Jacqueline Aguilar
 33770 Classroom 4/28/2008 30 \$0.00
 Medium Work In Progress 4/28/2008 1:18:34 PM
 Ronquillo, Ruben A BROKEN WINDOW THIS MORNING IN
 CLASSROOM 117 NOTHING APPEARS MISSING
 THANKS
 (Case # 08-0-4111 E. Parra)

Jimmy Cortez
 33823 4/29/2008 29 \$0.00
 Medium Work In Progress 4/29/2008 3:42:49 PM
 Ontiveros, Guadalupe MR LUPE ONTIVEROS SIR THE IRRIGATION
 CONTROL FOR THE NORTH PLAYGROUND HAS
 GONE HAYWIRE CANNOT CONTROL IT START AT
 ODD HOURS WILL TURN OFF FOR NOW WE"LL
 NEED TO REPLACE IT THANK YOU SIR AND GOD
 BLESS

Adan Duran
 34059 5/5/2008 23 \$0.00
 Medium Work In Progress 5/5/2008 3:22:48 PM
 Appelzoller, Fred MR FRED APPELZOLLER SIR THE CIRCULATION
 PUMP ON WATER HEATER IS NOT WORKING HAS A
 SHORT KEEPS KICKING THE BREAKER OUT MAY
 NEED TO REPLACE THANK YOU SIR AND GOD
 BLESS

Adan Duran
 34060 5/5/2008 23 \$0.00
 Medium Work In Progress 5/5/2008 3:26:11 PM
 Lozoya, Manny MR MANNY LOZOYA SIR NEED A NAME TAG FOR
 CAFETERIA MANAGER MRS ELSA ORTEGA THANK
 YOU SIR

Adan Duran

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Berino ES

34206 5/9/2008 19 \$0.00

Medium Work In Progress 5/9/2008 3:08:22 PM

Lozoya, Manny MR MANNY LOZOYA SIR PER MR VALTIERRA
THERE ARE ABOUT 3 CABINET FILES WITH OUT
LOCKS NEED TO REPAIR NEED TO LOCK
IMPORTANT PAPERS AND TEST THANK YOU SIR

Adan Duran

34343 Main Building Portables 5/15/2008 13 \$0.00

Medium Work In Progress 5/15/2008 8:15:12 AM

Appelzoller, Fred broken drinking fountain bubblers need to replace
Fred Appelzoller

34500 5/21/2008 7 \$0.00

Medium Work In Progress 5/21/2008 3:20:31 PM

Sanchez, Raul MR RAUL SANCHES SIR THE IRRGATION PUMP
FOR BERINO IS BURNED OUT WILL NEED TO
REPLACE AS SOON AS WE CAN GET A
REPLACEMENT THE PLAYGOUNDS ARE VERY DRY
THANK YOU SIR AND GOD BLESS

Adan Duran

34581 5/23/2008 5 \$0.00

Medium Work In Progress 5/23/2008 3:12:18 PM

Sotelo, Enrique MR ENRIQUE SOLTERO KIKI LAS LUCES EN EL
BANO DE LAS MUJERES ENFRENTE DE LA
ESCUELA NO PRENDEN SWITCH NO GOOD
NESITAMOS CABIER GRACIAS Y DIOS LO
VENDIGA DES CULPE EL ESPANISH

Adan Duran

34616 5/27/2008 1 \$0.00

Medium Work In Progress 5/27/2008 3:10:58 PM

Appelzoller, Fred MR FRED APPELZOLLER SIR THE WATER HEATER
IN PORTABLE 157 IS LEAKING BAD NEED TO
REPLACE ITS THE SMALL ONE THAT GOES ON
WALL UNDER SINK 220 V THANK YOU SIR AND
GOD BLESS

Adan Duran

Count: 32 Work Orders Avg. Age of WO's 78 Total for Berino ES 0 \$0.00

Location: Chaparral ES

30897 1/24/2008 125 \$0.00

Medium Work In Progress 1/24/2008 8:22:20 AM

Orozco, Danny Sink to kitchen area is cracked. (Where pots and pans
are washed)

Johnny Acuna

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

26649		Portables			9/4/2007		267		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	p-3			9/4/2007 8:25:13 AM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Lozoya, Manny
need another key to portable 3 for pre kinder classes for new clerk. See Judy Atkins

Jennifer Corral

26931		Classroom			9/12/2007		259		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	512			9/12/2007 10:40:56 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lozoya, Manny
teacher is requesting another key for room. There are now two teachers in that room. See Ms. Adina

Jennifer Corral

26976					9/13/2007		258		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/13/2007 6:57:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
9/13/07 fire proof file cabinet in principals' office needs to be re-keyed.

Joe Ramirez

27215					9/20/2007		251		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/20/2007 8:32:42 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Briones, Enrique
9/20/07.
we need discarded furn. and equip. to be picked up by the purch. whse. turn in sheets are available.

Joe Ramirez

28241					10/17/2007		224		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/17/2007 3:45:12 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
(Chaparral Elementary): (Ms. Vasquez, Room #414):
Door to classroom is fallen. Door is hard to close. Need to re-weld top hinge of frame. Also, need to weld door closure to top of metal frame.

Johnny Acuna

28503					10/24/2007		217		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2007 3:51:34 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Michael
Mike Muñoz: Need a double gate installed on the east side of fence area (Where the Trees are). Pre-K portable at Chaparral Elementary.

(4/29/08 Asp Juan has not been done)

Johnny Acuna

29796					12/4/2007		176		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 10:54:27 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Joe
Chaparral Elementary: Portable 2 / Pre-K. Water faucet to sink is leaking. Need a new gasket in the cold water side of the valve.

Johnny Acuna

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral ES							
29828					12/4/2007		176		\$0.00
Medium	Work In Progress				12/4/2007 4:00:15 PM				
Lozoya, Manny		Need a pad lock for Blue box inside the irrigation system area. Pad Lock (N-53)							
Johnny Acuna									
29916					12/7/2007		173		\$0.00
Medium	Work In Progress				12/7/2007 2:39:27 PM				
Lozoya, Manny		Need to re-weld rebar back on to the Roof top Ladder and re-enforce all other bars. Main building: Metal Ladder on top of Roof: Cafeteria Section.							
Johnny Acuna									
29917					12/7/2007		173		\$0.00
Medium	Work In Progress				12/7/2007 2:42:29 PM				
Lozoya, Manny		Chaparral Elementary Rooftop: Need to Make and install Metal ladder and frame to main building wall to be able to go up from the kitchen rooftop to cafeteria rooftop.							
Johnny Acuna									
30154					12/17/2007		163		\$0.00
Medium	Work In Progress				12/17/2007 3:36:14 PM				
Lozoya, Manny		Chaparral Elementary School Principal: Mrs. Ballard is requesting a lock for the Fire Proof Filing Cabinet.							
Johnny Acuna									
30577		Classroom			1/14/2008		135		\$0.00
Medium	Work In Progress	101			1/14/2008 7:51:37 AM				
Lozoya, Manny		need key for cabinet, teacher misplaced cabinet key and cannot open it. See Ms. Ledesma							
Jennifer Corral									
30721	2001 Classroom	Classroom			1/17/2008		132		\$0.00
Medium	Work In Progress	220			1/17/2008 9:19:23 AM				
Lozoya, Manny		Chaparral Elementary: (Emergency Health Issue)- Need to replace Restroom Door Knob to Room #220 in the New Wing Area. Students remove loose handle and dump it in the toilet.							
Johnny Acuna									
30977		Custodial			1/28/2008		121		\$0.00
Medium	Work In Progress	office			1/28/2008 1:48:11 PM				
Lozoya, Manny		need extra master keys for head custodian/ please see front office. as soon as possible							
Jennifer Corral									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

31652					2/19/2008		99		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/19/2008 8:43:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny need replace doors on barracas 416 414-412- 410 408
406 506 501

Juan Vargas

33051					4/6/2008	4/27/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:19 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly - Chaparral ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

33114					4/6/2008		52		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:40 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Jacquez, Ricardo Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.

Margret Villalobos

33505					4/17/2008		41		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/17/2008 3:31:43 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe water founting on main hall next to nurse have leak
need replace lines

Juan Vargas

33671					4/23/2008		35		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/23/2008 2:10:34 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vargas, Juan Storn Drains between the new classroom wing and existing wing need to be cleaned out.

Alfredo Holguin

33717					4/24/2008		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/24/2008 2:03:53 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny e wing doors portables need replace closers hiwges
water stripers seeps adjment of door and reweld same
hingereinfo
rcement # 501 502 503 505 506 507 508 509 510 512

Juan Vargas

33832					4/30/2008		28		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/30/2008 12:20:03 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Jacquez, Ricardo Monthly - Chaparral ES DP-91 - Refer to PM schedule details.

Margret Villalobos

34037					5/4/2008		24		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/4/2008 12:19:19 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Jacquez, Ricardo Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.

Margret Villalobos

5/28/2008 3:23:46 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

34404					5/19/2008		9		\$0.00
Medium	Work In Progress				5/19/2008 8:03:47 AM				
Lozoya, Manny		room 408 need fixlock not closed							
Juan Vargas									
34405					5/19/2008		9		\$0.00
Medium	Work In Progress				5/19/2008 8:06:16 AM				
Lozoya, Manny		room 408 need fixlock not closed							
Juan Vargas									
34406					5/19/2008		9		\$0.00
Medium	Work In Progress				5/19/2008 8:06:35 AM				
Lozoya, Manny		room 408 need fixlock not closed							
Juan Vargas									
34476					5/21/2008		7		\$0.00
Medium	Work In Progress				5/21/2008 7:54:31 AM				
Ronquillo, Ruben		room 406 need replace window glass zise 16 w.24l. 1/8 regular glass							
Juan Vargas									
34561		Cafeteria			5/23/2008		5		\$0.00
Medium	Work In Progress				5/23/2008 10:28:21 AM				
Moncayo, Fernando		MILK COOLER IS DOWN.							
		ESTHER CISNEROS SNP MGR 824-0048							
Jacqueline Aguilar									
34613		Custodial			5/27/2008		1		\$0.00
Medium	Work In Progress				5/27/2008 1:43:55 PM				
Hernandez, Guillermo		need/to/borrow/three/dollies/to/move/furniture/one/big/dollie							
Daniel Ramirez									
34634					5/28/2008		0		\$0.00
Medium	Work In Progress				5/28/2008 8:33:06 AM				
Solis, Lorenzo		need fix water founting next to nurse							
Juan Vargas									
34635					5/28/2008		0		\$0.00
Medium	Work In Progress				5/28/2008 8:40:12 AM				
Ontiveros, Joe		main drain next to portable #1 need 3 in. tapa							
Juan Vargas									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

Location:		Chaparral ES							
34638					5/28/2008		0		\$0.00
Medium	Work In Progress				5/28/2008 8:51:04 AM				
Vargas, Juan		05-21-08 8-	paint halls on main building			5/21 - 8			
Juan Vargas									
Count: 32 Work Orders		Avg. Age of WO's 102		Total for Chaparral ES		0		\$0.00	

Location:		Chaparral HS							
26036					8/20/2007		282		\$0.00
Medium	Work In Progress				8/20/2007 1:18:09 PM				
Boyd, David			WARRANTY WO. D-WING COMPUTER RM. CHANGE STORE RM. LOCK TO CLASS RM.LOCK						
Eddie Baeza									
26038					8/20/2007		282		\$0.00
Medium	Work In Progress				8/20/2007 1:24:09 PM				
Boyd, David			WARRANTY WO. (7) MULLENS ON EXTERIOR DOORS MISSING PLATES,ADJUST CYL. SO CORE CAN BE IN LOCKED POSITION.						
Eddie Baeza									
26039					8/20/2007		282		\$0.00
Medium	Work In Progress				8/20/2007 1:26:06 PM				
Boyd, David			WARRANTY WO. NEED CRANK FOR ROLL UP CURTAIN AT THE CONCESSION STAND.						
Eddie Baeza									
26040					8/20/2007		282		\$0.00
Medium	Work In Progress				8/20/2007 1:29:14 PM				
Boyd, David			WARRANTY WO. TRANSITION STRIPS IN KITCHEN FLOORS ARE COMING LOOSE.						
Eddie Baeza									
26041					8/20/2007		282		\$0.00
Medium	Work In Progress				8/20/2007 1:32:07 PM				
Boyd, David			WARRANTY WO. E-WING COMPUTER LAB HOLE IN WALL UNDER BULLETIN BOARD.						
Eddie Baeza									
26043					8/20/2007		282		\$0.00
Medium	Work In Progress				8/20/2007 1:36:10 PM				
Boyd, David			WARRANTY WO. VENT UNCOVERED IN CEILING. UNFINISHED HOLE IN WALL COUNCELORS OFFICE. (BARNETT)						
Eddie Baeza									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

26045					8/20/2007		282		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:38:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO PAPER LEFT IN LIGHT FIXTURE
IN COUNCELORS OFFICE.

Eddie Baeza

26046					8/20/2007		282		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:45:56 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. F-WING COMPUTER LAB 2
HOLES IN WALL NEXT TO TV STAND, HOLES NEAR
OUTLETS, MISSING PAINT BETWEEN GLASS
BLOCKS, CEILING TILES MISSING.

Eddie Baeza

26047					8/20/2007		282		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:49:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. RM. D-1 WALL OUTLET NOT
COMPLETED, STAIN ON CEILING TILE, CEILING
TILES MISSING.

Eddie Baeza

26048					8/20/2007		282		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:51:57 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. BAND RM. OUTLETS HAVE NOT
BEEN COVERED AND WIRES ARE STICKING OUT.

Eddie Baeza

26049					8/20/2007		282		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:54:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. CEILING TILES MISSING THRU
OUT CAMPUS.

Eddie Baeza

26050					8/20/2007		282		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:56:27 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRAFNTY WO. RMB-6 CHIPPED PAINT ON
A/C VENT.

Eddie Baeza

26051					8/20/2007		282		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:59:36 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. RM. C-3 DOOR ON STORAGE
CABINET CANNOT OPEN ALL THE WAY DUE TO T-
STAT COVER.

Eddie Baeza

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
26052					8/20/2007		282		\$0.00
Medium	Work In Progress				8/20/2007 2:04:24 PM				
Boyd, David		WARRANTY WO. RM. F-7 WATER STAINS ON CEILING TILES.							
Eddie Baeza									
26053					8/20/2007		282		\$0.00
Medium	Work In Progress				8/20/2007 2:07:05 PM				
Boyd, David		WARRANTY WO. LIBRARY CONFERENCE RM. JHOLE IN NORTH WALL. ELECTRICAL OUTLETS DO NOT WORK.							
Eddie Baeza									
26054					8/20/2007		282		\$0.00
Medium	Work In Progress				8/20/2007 2:11:34 PM				
Boyd, David		WARRANTY WO. B-SPED NEED HOOK UP FOR WASHER, NEED HOOK UP DRIER.NEED HOOKUP FOR STOVE. HOOK UP FOR DISHWASHER.							
Eddie Baeza									
26055					8/20/2007		282		\$0.00
Medium	Work In Progress				8/20/2007 2:13:14 PM				
Boyd, David		WARRANTY WO. WEST SCORE BOARD IN GYM NOT WORKING.							
Eddie Baeza									
26056					8/20/2007		282		\$0.00
Medium	Work In Progress				8/20/2007 2:16:29 PM				
Boyd, David		WARRANTY WO. BLEACHERS IN GYM NEED TO HAVE 120 VOLT, AND PA RECEPTALS AT THE BLEACHERS							
Eddie Baeza									
26057					8/20/2007		282		\$0.00
Medium	Work In Progress				8/20/2007 2:22:33 PM				
Boyd, David		WARRANTY WO FIRE PUMP NEEDS TO BE PROGRAMMED SO THAT IT WILL SHUT OFF AUTOMATICALLY. ALSO EVERY TIME IT STARTS IT CALLS THE FIRE DEPT.							
Eddie Baeza									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

26821 9/7/2007 264 \$0.00

Medium Work In Progress BAND ROOM 9/7/2007 4:31:33 PM

Lozoya, Manny RESTROOMS - LOCKS SHOULD BE CHANGED BECAUSE STUDENTS CAN LOCK THE DOOR FROM THE INSIDE AND IT SHOULDN'T BE THE CASE. GIRLS DOOR WON'T LOCK EITHER. ALSO, THE BATHROOM NEEDS BOYS AND GIRLS SIGNS POSTED ONT THE DOORS

Rosa Quezada

26822 9/7/2007 264 \$0.00

Medium Work In Progress OUTSIDE HOSE 9/7/2007 4:33:14 PM

Lozoya, Manny NEED 8 KEYS FOR OUTSIDE HOSE BIBS, AS PER EDDIE BAEZA

Rosa Quezada

26941 9/12/2007 259 \$0.00

Medium Work In Progress gym 9/12/2007 2:15:46 PM

Lozoya, Manny please rekey the ch1 key to a ch86 to fit the custodial door on the northwest end of the gym.

Rosa Quezada

26943 B-Wing 9/12/2007 259 \$0.00

Medium Work In Progress B-2 9/12/2007 2:26:44 PM

Lozoya, Manny COACH YTURRALDE NEEDS A KEY (CH32) TO ACCESS WASHER AND DRYER FOR FOOTBALL

Rosa Quezada

26964 C-Wing 9/12/2007 259 \$0.00

Medium Work In Progress sped room 9/12/2007 3:55:48 PM

Lozoya, Manny need ch32 to open door - need two keys - one for teacher and one for spare

Rosa Quezada

26965 Gym 9/12/2007 259 \$0.00

Medium Work In Progress gym 9/12/2007 3:57:05 PM

Lozoya, Manny need 4 keys off the GM1 master for coaches, Nougues, Yturralde, and Ulibarri and one for spare

Rosa Quezada

26967 C-Wing Classroom 9/12/2007 259 \$0.00

Medium Work In Progress sped - c wing 9/12/2007 3:59:24 PM

Lozoya, Manny please change order # 26964 previously entered to ch45 (2 keys) instead of ch32 - mymistake

Rosa Quezada

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

27410					9/25/2007		246		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/25/2007 2:10:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
Chaparral High School: Requesting Lobo Lane Fenceline be treated with arsenal and round up. Need motorized sprayer to spray on fenceline. All weeds are cut and raked. Thank You...

Johnny Acuna

28146		Custodial			10/15/2007		226		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/15/2007 3:16:11 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Need a set of tools and drill motor for various jobs that pop up ON HOLD AS PER CHUY

Arthur Contreras

28641					10/30/2007		211		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/30/2007 7:46:46 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Boyd, David
#1 UNIT IN THE CAFETERIA IS TRIPPING THE CONTROL TRANSFORMER SEEMS LIKE A DIRECT SHORT

Eddie Baeza

28837	C-Wing				11/2/2007		208		\$0.00
-------	--------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	c-4			11/2/2007 2:27:46 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lozoya, Manny
NEED A SET OF D156AR KEYS (CABINET) FOR HALLEY WOODS AT C-4

Rosa Quezada

29213					11/14/2007		196		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/14/2007 11:07:12				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny
STORAGE RM IN THE CAREER CENTER NEEDS TO BE REKEYED OFF MASTER, AND 4 KEYS ARE NEEDED

Eddie Baeza

29691					12/2/2007	12/23/2007	178		\$0.00
-------	--	--	--	--	-----------	------------	-----	--	--------

Medium	Work In Progress				12/2/2007 12:30:23 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny
Monthly- Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

29748					12/3/2007		177		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/3/2007 2:28:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David
POWER NEEDS TO BE SUPPLIED TO BLEACHERS, AND PA SYSTEM

Eddie Baeza

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

29749					12/3/2007		177		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/3/2007 2:30:00 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		FIRE BLOCK DOORS IN THE MAIN CORRIDOR NEEDS LOCKSETS INSTALLED							
---------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

29806					12/4/2007		176		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 2:47:41 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		(1) CH-7 AND (1) CH-3 KEYS ARE REQUESTED FOR NURSE HIGGS IN THE HEALTH CENTER							
---------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

29858					12/6/2007		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				12/6/2007 7:52:44 AM	12/6/2007			
--------	------------------	--	--	--	----------------------	-----------	--	--	--

Lozoya, Manny		Can we get a key to the gate for the compactor at Chaparral High School. Please let me know when the key is ready and I will go by and pick it up.							
---------------	--	--	--	--	--	--	--	--	--

Juliet Parra

29953		Gym			12/10/2007		170		\$0.00
-------	--	-----	--	--	------------	--	-----	--	--------

Medium	Work In Progress	GYM			12/10/2007 3:38:16 PM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lozoya, Manny		NEED A KEY TO RETRACT THE SIDE BASKETS IN THE GYM (F.SANCHEZ)							
---------------	--	--	--	--	--	--	--	--	--

Rosa Quezada

29954		Classroom			12/10/2007		170		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	SECRETARY			12/10/2007 3:39:28 PM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Lozoya, Manny		NEED A WA (LIFT STATION GATE KEY)							
---------------	--	-----------------------------------	--	--	--	--	--	--	--

Rosa Quezada

30137	A-Wing				12/17/2007		163		\$0.00
-------	--------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress	RECEPTIONIST			12/17/2007 10:23:58				
--------	------------------	--------------	--	--	---------------------	--	--	--	--

Lozoya, Manny		NEED COPIES OF D-264AR FOR CABINETS BEHIND RECEPTIONIST DESK (M.MEZA)							
---------------	--	--	--	--	--	--	--	--	--

Rosa Quezada

30138		Gym			12/17/2007		163		\$0.00
-------	--	-----	--	--	------------	--	-----	--	--------

Medium	Work In Progress	OFFICE			12/17/2007 10:25:42				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Lozoya, Manny		NEED A KEY FOR CABINET IN P.E. OFFICE FOR COACH YTURREALDE A.S.A.P.							
---------------	--	--	--	--	--	--	--	--	--

Rosa Quezada

30485		Office			1/10/2008		139		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	MAINTENANCE			1/10/2008 2:19:49 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Lozoya, Manny		NEED A C-T KEY FOR EDDIE BAEZA (MAINTENANCE) TO ACCESS ROOF HATCH AND AC UNITS							
---------------	--	--	--	--	--	--	--	--	--

Rosa Quezada

5/28/2008 3:23:46 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

30728	E-Wing	Classroom			1/17/2008		132		\$0.00
Medium	Work In Progress	E-7			1/17/2008 10:48:11 AM				
Lozoya, Manny		LOCK ON TALL CABINET IN BACK OF CLASSROOM FELL OUT. NEEDS TO BE REPAIRED (SAVOIE)							

Rosa Quezada

30729	D-Wing	Classroom			1/17/2008		132		\$0.00
Medium	Work In Progress	D-4			1/17/2008 10:50:47 AM				
Lozoya, Manny		CABINET KEYS GET STUCK - UNABLE TO LOCK)							
Rosa Quezada									

30732		Classroom			1/17/2008		132		\$0.00
Medium	Work In Progress	E-7			1/17/2008 10:54:33 AM				
Lozoya, Manny		NEED KEY# RD025 TO OPEN CABINETS (SAVOIE)							
Rosa Quezada									

30805		Gym			1/18/2008		131		\$0.00
High	Work In Progress				1/18/2008 3:26:09 PM				
Baeza, Eddie		6 breakaway goals where purchaed for courts. 2 have been installed, please install the remaining 4 and return to the physical plant. THXS							

Michael Munoz

31011	E-Wing	Classroom			1/29/2008		120		\$0.00
Medium	Work In Progress	E-3			1/29/2008 9:17:45 AM				
Lozoya, Manny		NEED A CH-12 TO OPEN THE WEIGHTLIFTING ROOM FOR HIS CLASS (DIOSDADO)							

Rosa Quezada

31050		Cafeteria			1/30/2008		119		\$0.00
Medium	Work In Progress	Kitchen			1/30/2008 8:50:54 AM				
Baeza, Eddie		As per Pest Control need to redo door kitchen entry from exterior 1/2 - 1in cap under door.							

Margret Villalobos

31167					2/1/2008		117		\$0.00
Medium	Work In Progress				2/1/2008 10:18:36 AM				
Lozoya, Manny		A CH-1 CORE IS REQUESTED FOR THE ROOF HATCH AAT THE B-WING.							

Eddie Baeza

31417		Office			2/7/2008		111		\$0.00
Medium	Work In Progress	TROPHY CASES			2/7/2008 6:50:49 PM				
Lozoya, Manny		NEED SIX LOCKS FOR TROPHY CASES AND TWO LOCKS FOR DISPLAY CASES (QUEZADA)							

Rosa Quezada

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
31459					2/11/2008		107		\$0.00
Medium	Work In Progress				2/11/2008 10:52:30 AM				
Lozoya, Manny		42 FLOOR DOOR STOPS ARE REQUESTED FOR CLASS RM. DOORS.(PURCHASE THROUGH RAWSON)							
Eddie Baeza									
31686					2/20/2008		98		\$0.00
Medium	Work In Progress				2/20/2008 9:53:02 AM				
Orozco, Danny		A DOOR BELL IS REQUESTED FOR THE RECEIVING DOOR AT THE KITCHEN.							
Eddie Baeza									
31858					2/26/2008		92		\$0.00
Medium	Work In Progress				2/26/2008 7:50:53 AM				
Lozoya, Manny		STORAGE DOOR AT THE GIRLS LOCKER RM. CANNOT BE OPENED. SEEMS LIKE LATCH IS NOT ENGAGING.							
Eddie Baeza									
31975					2/28/2008		90		\$0.00
Medium	Work In Progress	GIRLS LOCKER			2/28/2008 8:20:15 AM				
Lozoya, Manny		PLEASE RE-KEY DOOR THAT SEPARATES DOORS BETWEEN GIRLS LOCKER ROOM. NEEDS TO BE KEY ENTRY ON BOTH SIDES. (NOUGUES)							
Rosa Quezada									
31984	E-Wing	Classroom			2/28/2008		90		\$0.00
Medium	Work In Progress	E-7			2/28/2008 8:34:23 AM				
Lozoya, Manny		NEED KEYS TO LOCK AND UNLOCK CABINETS IN SOTRE ROOM. THE STAMP CODE IS RD025. (SAVOIE) 2ND REQUEST							
Rosa Quezada									
32032		Custodial			2/29/2008		89		\$0.00
Medium	Work In Progress				2/29/2008 11:11:36 AM				
Estrada, Jesus		I need 4 gallons of vinegar for the tile floors							
Arthur Contreras									
32384					3/7/2008		82		\$0.00
High	Work In Progress				3/7/2008 1:12:14 PM				
Contreras, Arthur		Pick up trash around fence line and entrance east side is the worst.							
Jesus Estrada									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

32440					3/10/2008		79		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 3:02:25 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique		ELECTRICAL CIRCUITS ARE REQUESTED FOR THE GAURD SHACK AT MAIN ENTRANCE							
-----------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

32493	C-Wing				3/11/2008		78		\$0.00
-------	--------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-COMPUTER			3/11/2008 3:47:14 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Lozoya, Manny		NEED SIX COPIES OF PORT A POTTY KEY #3172 (ROSA HAS A KEY)							
---------------	--	--	--	--	--	--	--	--	--

Rosa Quezada

32537					3/13/2008		76		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/13/2008 8:54:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		LOCHINVAR BOILERS ARE KICKING OFF ON LOW AIR PRESSURE							
-------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

32538					3/13/2008		76		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/13/2008 9:02:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		DOMESTIC WATER PUMPS ARE GOING INTO ALARM ON HIGH DISCHARGE PRESSURE							
-------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

32540					3/13/2008		76		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/13/2008 9:04:40 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		DOOR CLOSER IN THE CONCESSION STAND HAS FALLEN OFF.							
-------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

32541					3/13/2008		76		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/13/2008 9:06:13 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		START UP OF HEATING AND COOLING UNITS AT THE GREENHOUSES, NEEDS TO BE PERFORMED AND CHECKED FOR PROPER PERFORMANCE.							
-------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

32542					3/13/2008		76		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/13/2008 9:07:31 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David		CIRCULATING PUMP IN THE CUSTODIAL CLOSET IN THE C-WING IS MAKING NOISE.							
-------------	--	---	--	--	--	--	--	--	--

Eddie Baeza

32978					4/4/2008		54		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/4/2008 1:22:10 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny		N.W. DOOR AT THE GYM WILL NOT UNLOCK							
---------------	--	--------------------------------------	--	--	--	--	--	--	--

Eddie Baeza

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

33136		Office			4/7/2008		51		\$0.00
Medium	Work In Progress	secretary			4/7/2008 12:09:53 PM				
Lozoya, Manny		I NEED TWO E-158 KEYS FOR THE TRASH COMPACTOR							
Rosa Quezada									

33246					4/9/2008		49		\$0.00
Medium	Work In Progress				4/9/2008 2:41:22 PM				
Ontiveros, Guadalupe		ARSONEL AND A SPRAYER ARE REQUESTED TO SPRAY FENCE LINES.							
Eddie Baeza									

33252					4/9/2008		49		\$0.00
Medium	Work In Progress				4/9/2008 2:50:44 PM				
Ontiveros, Joe		(5) HOSE BIBS ARE REQUESTED FOR THE MASTERCOOLS AT THE GYM.							
Eddie Baeza									

33253					4/9/2008		49		\$0.00
Medium	Work In Progress				4/9/2008 2:52:29 PM				
Boyd, David		DOMESTIC WATER PUMPS ARE GOING INTO ALARM AND SHUTTING DOWN ON HI SYSTEM PRESSURE.							
Eddie Baeza									

33298					4/10/2008		48		\$0.00
Medium	Work In Progress				4/10/2008 12:10:01 PM				
Lozoya, Manny		(60) DOOR LATCH PROTECTORS AND (60) FLOOR DOOR STOPS ARE REQUESTED FOR CLASSROOM DOORS.							
Eddie Baeza									

33652					4/22/2008		36		\$0.00
Medium	Work In Progress				4/22/2008 3:52:55 PM				
Lozoya, Manny		(2) DISPLAY CASE LOCKS ARE REQUESTED FOR THE LIBRARY. KEYED TO # 998 IF POSSIBLE							
Eddie Baeza									

33714	E-Wing	Classroom			4/24/2008		34		\$0.00
Medium	Work In Progress	E-7			4/24/2008 12:11:24 PM				
Baeza, Eddie		INSTALL TWO PAPERTOWEL DISPENSERS. ONE BY THE SINK IN THE CLASSROOM AND THE OTHER BY THE SINK IN THE STOREROOM. (SAVOIE)							
Rosa Quezada									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
34039					5/4/2008		24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:20 AM				
Baeza, Eddie		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
34040					5/4/2008		24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:20 AM				
Baeza, Eddie		Monthly - Chaparral HS Monthly FE Inspection - Refer to PMSchedule details.							
Margret Villalobos									
34041					5/4/2008		24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:21 AM				
Baeza, Eddie		Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
34263		Football Field			5/13/2008		15		\$0.00
Medium	Work In Progress	FOOTBALL -			5/13/2008 12:41:50 PM				
Ontiveros, Guadalupe		NEED TO MARK THE PRACTICE FIELD WITH FOOTBALL AND SOCCER LINES (YTURRALDE)							
Rosa Quezada									
34475					5/21/2008		7		\$0.00
Medium	Work In Progress				5/21/2008 7:33:08 AM				
Hernandez, Guillermo		need vinegar to clean ceramic floors. 12 gallons							
Arthur Contreras									
34539		Athletic Field			5/22/2008		6		\$0.00
Medium	Work In Progress				5/22/2008 3:05:46 PM				
Estrada, Jesus		Need pitchfork for tumble weeds that accumulate on the perimeter of the facility. The fence line							
Arthur Contreras									
34645					5/28/2008		0		\$0.00
Medium	Work In Progress				5/28/2008 9:23:18 AM				
Lozoya, Manny		We need Manny to change the keys in the IDF server rooms to be a master key of that school site							
Cora Ramirez									
Count: 78 Work Orders			Avg. Age of WO's	159		Total for Chaparral HS	0		\$0.00

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

24411					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24412					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24413					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

26037					8/20/2007		282		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 1:20:23 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David WARRANTY WO. DEADBOLTS NEED TO BE REPLACED IN ALL REST RMS.

Eddie Baeza

27127					9/18/2007		253		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/18/2007 11:19:23 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny we need to change the lock from 405A to 405B and 405B TO 405A. we have computers in room 405A and we do not want people with the A master key to be able to go in there.

Robert Gonzalez

27255					9/21/2007		250		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/21/2007 7:27:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny girls locker room door that leads to the back girls sports locker room is hard to open and lock. choach ramos would like a dead bolt put on there if possible.

Robert Gonzalez

29159		Cafeteria			11/13/2007		197		\$0.00
-------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2007 10:39:04				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny BOTTOM BLODGETT OVEN IS STILL NOT WORKING (NEED TO COOK TURKEY ASAP - PLEASE)

SANDRA DIAZ - SNP MANAGER 824-4379

Alma Terrell

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

31064					1/30/2008		119		\$0.00
Medium	Work In Progress				1/30/2008 11:15:47 AM				
Solis, Lorenzo		Need a coupling connector for Boiler system water pump in the mechanical Room.							
Johnny Acuna									
31295		Gym			2/5/2008		-60		\$0.00
Medium	Work In Progress				2/5/2008 9:00:35 AM	12/7/2007			
Lozoya, Manny		boys and grls. lockers rooms need replace partitions.							
Juan Vargas									
31598		Portables			2/14/2008		104		\$0.00
Medium	Work In Progress				2/14/2008 1:19:14 PM				
Lozoya, Manny		Portable #14 has two file cabinets that need keys and the building mechanic needs locks and keys for his desk							
Eric Medina									
31601					2/14/2008		104		\$0.00
Medium	Work In Progress				2/14/2008 2:26:42 PM				
Ontiveros, Joe		4 custodial closets have leaks at faucet							
Eric Medina									
32025		Portables			2/29/2008		89		\$0.00
Medium	Work In Progress	P-10			2/29/2008 8:35:00 AM				
Lozoya, Manny		Need file cabinet re-keyed for Ms. Smith in portable 10 needs to file important confidential papers.							
Elena Palacios									
32305					3/5/2008		84		\$0.00
Medium	Work In Progress				3/5/2008 3:16:24 PM				
Ontiveros, Joe		3/5 need to replace valve under portable #2							
Eric Medina									
32329					3/6/2008		83		\$0.00
Medium	Work In Progress				3/6/2008 8:06:40 AM				
Gonzales, Angel		Myblower's throttle is stuck on fast and the weed eater's string houing is broken							
Eric Medina									
32354					3/6/2008		83		\$0.00
High	Work In Progress				3/6/2008 3:03:01 PM				
Gonzalez, Robert		Shampoo and extract carpet in band room. As per Ms. Muela the carpet is making the band director sick. (assign to R. Gonzalez)							
Jesus Estrada									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

32418					3/10/2008		79		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				3/10/2008 9:39:00 AM				
------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny We need all the locks that were taken off the file cabinets re-installed. We have been waiting since SEPTEMBER!!!

Elena Palacios

32429					3/10/2008		79		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 11:22:23 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny outside door to boys locker rooms westside is very hard to unlock. then it's very hard to lock again. door handle is loose.

Robert Gonzalez

33045					4/6/2008	4/27/2008	-11		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress				4/6/2008 12:18:17 AM	3/26/2008			
--------	------------------	--	--	--	----------------------	-----------	--	--	--

Orozco, Danny Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PMschedule details.

Margret Villalobos

33350					4/11/2008		47		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/11/2008 3:50:10 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Room 206 need lock on file cabinet replaced

Eric Medina

33389					4/14/2008		44		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/14/2008 12:33:51 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny THE DOOR HANDLE IN ROOM 450 (BAND ROOM) LOCKS BUT IF YOU JIGGLE IT IT UNLOCKS.

Robert Gonzalez

33549					4/18/2008		40		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	DP-781			4/18/2008 2:21:11 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Jacquez, Ricardo As per DP-781 Closure Plan: Needs to be done before July 11, 2008. (Please inform Alfredo when complete).
1. Remove or plug all lines conveying wastewater to the septic tank/leachfield system (s) so that a discharge can no longer occur.

2. Pump the grease interceptor and septic tanks and dispose of pumpings in accordance with all local, state and federal regulations.

Alfredo Holguin

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

33552					4/18/2008		40		\$0.00
Medium	Work In Progress	DP-781			4/18/2008 2:24:24 PM				
Ontiveros, Guadalupe		As per DP-781 Closure Plan: Needs to be done before July 11, 2008. (Please inform Alfredo when complete).							
		Backfill the tanks with clean fill or sand or remove from site.							
		(Lupe ck w/Rick Jacquez to see if he is done w/his part first). Thanks							

Alfredo Holguin

33989					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:02 AM				
Medina, Eric		Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.							

Margret Villalobos

34225					5/12/2008		16		\$0.00
Medium	Work In Progress				5/12/2008 9:03:47 AM				
Sotelo, Enrique		Smelling burnt wires in room 304 requesting electrician to come inspect room							

Eric Medina

Count: 24 Work Orders		Avg. Age of WO's	123			Total for Chaparral MS	0		\$0.00
------------------------------	--	-------------------------	------------	--	--	-------------------------------	----------	--	---------------

Location: Desert Pride

26455					8/30/2007		272		\$0.00
Medium	Work In Progress	storage building			8/30/2007 12:55:10 PM				
Miranda, Danny		storage building- a good size of the ceiling (sheetrock) came down and a light fixture is hanging lose toward the back end of building				Routed to Danny asp Mike 8/31 -mkv			

David Acosta

28788		Restroom (Girls)			11/1/2007		209		\$0.00
Medium	Work In Progress	front office			11/1/2007 10:12:05 AM				
Appelzoller, Fred		Need an ADA toilet installed in the restroom in the front office.							

Mary Telles

30920		Portables			1/24/2008		125		\$0.00
Medium	Work In Progress	6 & 7			1/24/2008 2:00:01 PM				
Castillo, Carlos		ROOMS 6 & 7 NEEDS INDIVIDUAL LIGHT SWITCH TO TURN ON LIGHTS TO THEIR ROOMS. (LAST PORTABLE)							

David Acosta

5/28/2008 3:23:46 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Pride									
32873		Portables			4/1/2008		57		\$0.00
Medium	Work In Progress	6 , 7 & 8			4/1/2008 10:44:19 AM				
Castillo, Carlos		OUTSIDE NIGHTLIGHTS NOT TURNING ON AT NITE							
David Acosta									
32874		Office			4/1/2008		57		\$0.00
Medium	Work In Progress				4/1/2008 10:50:50 AM				
Castillo, Carlos		SECURITY NIGHTLIGHT NEEDED ON NORTH SIDE OF FRONT OFFICE BUILDING. THAT AREA VERY DARK.							
David Acosta									
33581					4/21/2008		37		\$0.00
High	Work In Progress				4/21/2008 2:26:39 PM				
Miranda, Danny		1st bldg, need to repair restroom floors. repair 2nd restroom 1st and 1st restroom 2nd when abated.thxs							
Michael Munoz									
33605	Storage A	Pump House			4/21/2008		37		\$0.00
Medium	Work In Progress				4/21/2008 3:37:05 PM				
Castillo, Carlos		I need an electrician to check flourescent fixture in pump house.It may need to be replaced or repaired. Thanks ,Raul							
Raul Sanchez									
33664		Classroom			4/23/2008		35		\$0.00
Medium	Work In Progress	9,10,11			4/23/2008 10:41:27 AM				
Estrada, Jesus		NEED TO REPAIR CARPET IN CLASSROOMS.				5/9 - AS PER MICHEAL - CARPET IS BEYOIND REPAIR UNLESS IT IS REPAIRED WITH DIFFERENT COLOR OF CARPET THAT WON'T MATCH EXACTLY OR DO WE WANT QUOTE TO REPLACE? WILL STOP BY LATER TODAY AND TALK TO CHUY			
David Acosta									
33670		Portables			4/23/2008		35		\$0.00
Medium	Work In Progress	ROOM 7			4/23/2008 1:59:16 PM				
Castillo, Carlos		NEED TO REPLACE BALLAST IN ONE LIGHT FIXTURE							
David Acosta									
33777					4/28/2008		30		\$0.00
Medium	Work In Progress				4/28/2008 2:53:48 PM				
Holguin, Alfredo		Provide Electrical power to new marquee							
Alfredo Holguin									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Pride

33893		Portables			5/1/2008		27		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/1/2008 9:27:53 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe		Portable 5/9SM - Need to make sure area is ready for portable. (entrance, fencing, blocks, cookies, leveled, etc.)							
----------------------	--	---	--	--	--	--	--	--	--

Michael Munoz

33894		Portables			5/1/2008		27		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/1/2008 9:29:28 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos		Portable 5/9SM - Need to connect utilities.							
------------------	--	---	--	--	--	--	--	--	--

Michael Munoz

33895		Portables			5/1/2008		27		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/1/2008 9:30:47 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Appelzoller, Fred		Portable 5/9SM - Need to connect utilities (if any).							
-------------------	--	--	--	--	--	--	--	--	--

Michael Munoz

33896		Portables			5/1/2008		27		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/1/2008 9:32:10 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose		Portable 5/9SM - Need to connect HVAC.							
--------------	--	--	--	--	--	--	--	--	--

Michael Munoz

33897					5/1/2008		27		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	Barrack			5/1/2008 9:36:59 AM				
--------	------------------	---------	--	--	---------------------	--	--	--	--

Miranda, Danny		Need to make a partition in the middle of Barrack with door. (by Julie's Trailer).							
----------------	--	--	--	--	--	--	--	--	--

Michael Munoz

33898					5/1/2008		27		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	Barrack			5/1/2008 9:42:20 AM				
--------	------------------	---------	--	--	---------------------	--	--	--	--

Ambriz, Jose		Need to install (2) Bards for Barrack will be divided in the middle, ck amp w/Electrician. (by Julie's Trailer).							
--------------	--	--	--	--	--	--	--	--	--

Michael Munoz

33899					5/1/2008		27		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	Barrack			5/1/2008 10:49:24 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Estrada, Jesus		Need to install VCT in Barrack (by Julie's Mobile Home) partition will be installed 2 classrooms.							
----------------	--	---	--	--	--	--	--	--	--

Michael Munoz

33901					5/1/2008		27		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	Barrack			5/1/2008 10:53:14 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Gonzalez, Salvador		Need to install ramp at barrack (by Julie's Mobile Home). See Mike							
--------------------	--	---	--	--	--	--	--	--	--

Michael Munoz

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Pride

33902					5/1/2008		27		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	Barrack			5/1/2008 10:54:30 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Lara, Ralph
Need to install door and window at barrack (by Julie's Mobile Home).
See Mike

Michael Munoz

34234		Office			5/12/2008		16		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

High	Work In Progress				5/12/2008 2:45:54 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael
Need to abate asbestos in 1st bldg, 1st restroom, so floor and plumbing can be repaired.

Michael Munoz

34275		Portables			5/13/2008		15		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/13/2008 3:27:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Carbajal, Jimmy
Need to take out furniture in storage portable. Furniture that is in good shape you can bring out to our barracks. This should take place on 5/21 so maintenance can help you out.
(Assign to Jimmy Carbajal)

5/14/08 - AS PER MIKE THIS NEEDS TO BE TAKEN CARE OF A.S.A.P. SO THAT THEY CAN START WORKING ON PORTABLE. AS PER CHUY - THEY CAN START ON FRIDAY (5/16/08).

Jesus Estrada

34304					5/14/2008		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Barrack			5/14/2008 8:18:23 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Castillo, Carlos
Need to install lighting and electrical outlets to barrack will be divided into 2 classrooms. (by Julie's Mobile Home).
See Mike

Michael Munoz

34445					5/20/2008		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/20/2008 2:36:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred
1st bldg (1st Restroom) - Need to remove comode and water heater (See Mike before you start).

Michael Munoz

34484					5/21/2008		7		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/21/2008 11:07:11 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Estrada, Jesus
NEED TO INSTALL VCT IN 2 RESTROOMS IN THE FIRST BUILDING (AFTER IT IS ABATED/SCHEDULED FOR THIS FRIDAY -5/23)

Michael Munoz

34560		Library			5/23/2008		5		\$0.00
-------	--	---------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/23/2008 8:46:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
the two loads of dirt by library bldg. need to have it spread out.

David Acosta

5/28/2008 3:23:47 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Pride							
34601		Portables			5/27/2008		1		\$0.00
Medium	Work In Progress	8			5/27/2008 10:46:16 AM				
Ronquillo, Ruben		ATT: RUBEN R.- NEED TO REPLACE TWO WINDOWS TO PORTABLE [AS PER MIKE]							
David Acosta									
Count: 26 Work Orders		Avg. Age of WO's		46	Total for Desert Pride			0	\$0.00

Location:		Desert Trail Intermediate							
25347		Cafeteria			8/2/2007		300		\$0.00
Medium	Work In Progress				8/2/2007 1:47:59 PM				
Orozco, Danny		Kitchen: Washroom Door Frame needs to be replaced. Door Frame is corroded on the bottom.							
Johnny Acuna									
26689					9/5/2007		266		\$0.00
Medium	Work In Progress				9/5/2007 1:18:39 PM				
Lozoya, Manny		Need to check Custodial J-Master Key. Key does not open doorknob lock to portable #415 for her to clean classroom during her working hours.							
Johnny Acuna									
26782					9/7/2007		264		\$0.00
Medium	Work In Progress				9/7/2007 8:57:11 AM				
Lozoya, Manny		Custodial Dept. requesting a lock for filing cabinet in the custodial / maintenance office.							
Johnny Acuna									
26788					9/7/2007		264		\$0.00
Medium	Work In Progress				9/7/2007 10:28:19 AM				
Sotelo, Enrique		Need to replace (2) Ballasts for Outdoor security light poles. *-light next to storage shed. *-Light in back of portables closest to grass area:Also for this light pole need to replace broken light cover.							
Johnny Acuna									
27020					9/14/2007		257		\$0.00
Medium	Work In Progress				9/14/2007 10:48:38 AM				
Estrada, Jesus		Need to replace VCT in the kitchen laundry room. VCT is cracked and faded out. If possible, replace with skid resistant type. Thank You.				4/23 - Asp Mike route to Chuy			
Johnny Acuna									
28406					10/23/2007		218		\$0.00
Medium	Work In Progress				10/23/2007 11:10:46				
Acuna, Johnny		Please connect existing sidewalk to playground ramp approx. 3 x 5 section after grounds does backfill of dirt.							
Michael Munoz									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail Intermediate

28408					10/23/2007		218		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 11:13:37				
--------	------------------	--	--	--	---------------------	--	--	--	--

Acuna, Johnny		Digout grass around wells in trees.							
Michael Munoz									

28536					10/25/2007		216		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/25/2007 1:01:41 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Acuna, Johnny		PLAYGROUND ARE-NEED CONNECTION FROM SIDEWALK TO SURFACING FOR ADA.							
---------------	--	--	--	--	--	--	--	--	--

Michael Munoz									
---------------	--	--	--	--	--	--	--	--	--

28537					10/25/2007		216		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/25/2007 1:05:49 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Acuna, Johnny		NOT GOOD FOR 5 YEAR OLD.- NEED SIGN FOR 6YRS AND OLDER.							
---------------	--	---	--	--	--	--	--	--	--

Michael Munoz									
---------------	--	--	--	--	--	--	--	--	--

30396		Cafeteria			1/8/2008		141		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				1/8/2008 2:05:00 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny		Garbage Disposal is Not Working Again							
---------------	--	---------------------------------------	--	--	--	--	--	--	--

		Patricia Cisneros - SNP Manager 824-3822							
--	--	--	--	--	--	--	--	--	--

Alma Terrell									
--------------	--	--	--	--	--	--	--	--	--

31003					1/29/2008		120		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/29/2008 7:22:07 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo		Replacement a/c's for portable 403/404.							
----------------	--	---	--	--	--	--	--	--	--

Johnny Acuna									
--------------	--	--	--	--	--	--	--	--	--

31197					2/3/2008	2/11/2008	115		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress				2/3/2008 12:30:34 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PMschedule details.							
---------------	--	---	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

31202					2/3/2008	2/11/2008	115		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress				2/3/2008 12:30:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PMschedule details.							
---------------	--	---	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

31855					2/25/2008		93		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 4:03:54 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Need 3 Muliums installed in our main building main entry door areas. (1)-Front office area, main doors. (1)-Bus area main doors. (1)-Middle main door going to portable area.							
---------------	--	---	--	--	--	--	--	--	--

Johnny Acuna									
--------------	--	--	--	--	--	--	--	--	--

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Desert Trail Intermediate							
32068					3/2/2008	3/8/2008	87		\$0.00
Medium	Work In Progress				3/2/2008 12:32:49 AM				
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
32090					3/2/2008	3/10/2008	87		\$0.00
Medium	Work In Progress				3/2/2008 12:32:58 AM				
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
32095					3/2/2008	3/10/2008	87		\$0.00
Medium	Work In Progress				3/2/2008 12:33:00 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
32251					3/4/2008		85		\$0.00
Medium	Work In Progress				3/4/2008 11:11:58 AM				
Ontiveros, Joe		Need to unclogg urinal in the 2nd grade boys restroom.							
Johnny Acuna									
32909	Main Building	Library			4/2/2008		56		\$0.00
Medium	Work In Progress				4/2/2008 10:11:14 AM				
Estrada, Jesus		Carpet in Library needs to be replaced.							
Jesus Estrada									
33007					4/6/2008	4/12/2008	52		\$0.00
Medium	Work In Progress				4/6/2008 12:18:04 AM				
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
33024					4/6/2008	4/14/2008	52		\$0.00
Medium	Work In Progress				4/6/2008 12:18:10 AM				
Acuna, Johnny		Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
33046					4/6/2008	4/27/2008	-11		\$0.00
Medium	Work In Progress				4/6/2008 12:18:17 AM	3/26/2008			
Orozco, Danny		Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail Intermediate

33076					4/6/2008	4/14/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acuna, Johnny Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

33081					4/6/2008	4/14/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:28 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acuna, Johnny Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

33173					4/8/2008		50		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/8/2008 7:55:57 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Jacquez, Ricardo Rick Jaquez: Please pick up your trash and debris from when you cleaned the inside of the lift station and was left outside the lift station.

Johnny Acuna

33662					4/23/2008		35		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/23/2008 10:36:24 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Need to install a lock for new filing cabinet to classroom #398.

Johnny Acuna

33710		Cafeteria			4/24/2008		34		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/24/2008 9:44:18 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny NAME PLATE FOR CAFETERIA CLERK. (AMANDA MEDRANO)

Marisela Torres

33774	Main Building	Library			4/28/2008		30		\$0.00
-------	---------------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/28/2008 2:09:50 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Torres, Marisela The furniture in the library needs to be taken out before May 27th which is when new rug will be installed.

Jesus Estrada

33833					4/30/2008		28		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/30/2008 12:20:03 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Jacquez, Ricardo Monthly - Desert Trail - Refer to PM schedule details.

Margret Villalobos

33917					5/1/2008		27		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/1/2008 3:23:47 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny (Desert Trail) The Front Main doors going inside the main building: The door all the way to the left has mechanical parts broken inside the panic bar. Please fix A/S/AP.

Johnny Acuna

5/28/2008 3:23:47 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail Intermediate							
33977					5/4/2008	5/10/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:18:58 AM				
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
33999					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:06 AM				
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
34004					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:08 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
34261		Custodial			5/13/2008		15		\$0.00
Medium	Work In Progress				5/13/2008 10:45:35 AM				
Estrada, Jesus		ME PODRIA FACILITAR LA SIGUIENTE HERRAMIENTA? drill bit extension- #2 phillip drill bits- 1/4 " nut driver drill bit- 5/16"nut driver drill bit- #3 phillip drill bits. GRACIAS.							
Marisela Torres									
34305					5/14/2008		14		\$0.00
Medium	Work In Progress				5/14/2008 8:43:07 AM				
Sotelo, Enrique		Need additional electrical outlets installed in the cafeteria room.							
Johnny Acuna									
Count: 35 Work Orders			Avg. Age of WO's	106		Total for Desert Trail Intermediate	0		\$0.00

Location:		Desert View ES							
24378					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									
24379					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:51 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Desert View ES
------------------	-----------------------

24380					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

25693					8/9/2007		293		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/9/2007 3:49:24 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose		pat aguilar a/c port 1 not working properly not cold - has new filter							
--------------	--	--	--	--	--	--	--	--	--

Patricio Aguilar									
------------------	--	--	--	--	--	--	--	--	--

27635					9/30/2007	10/21/2007	241		\$0.00
-------	--	--	--	--	-----------	------------	-----	--	--------

Medium	Work In Progress				9/30/2007 12:17:39 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny		Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

29032		Cafeteria			11/7/2007		203		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/7/2007 9:44:32 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		AS PER HEALTH INSPECTION ON 10/29/07 -- BACK DOOR MISSING A GOOD SEAL TO PREVENT THE ENTRY OF INSECTS AND VERMIN.							
---------------	--	---	--	--	--	--	--	--	--

		AIDA SALCEDO - SNP COMPLIANCE COORDINATOR 882-6772 MARTHA FLORES - SNP MANAGER 589-2425							
--	--	---	--	--	--	--	--	--	--

Alma Terrell									
--------------	--	--	--	--	--	--	--	--	--

30613					1/14/2008		135		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

High	Work In Progress				1/14/2008 4:18:52 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph		need locks installed on new gates on new buss turn around. THXS							
-------------	--	---	--	--	--	--	--	--	--

Michael Munoz									
---------------	--	--	--	--	--	--	--	--	--

31725		Cafeteria			2/20/2008		98		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/20/2008 4:02:08 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando		DOOR OPENS TO MIXER							
-------------------	--	---------------------	--	--	--	--	--	--	--

		AIDA SALCEDO - SNP COORD.							
--	--	---------------------------	--	--	--	--	--	--	--

Alma Terrell									
--------------	--	--	--	--	--	--	--	--	--

31757					2/21/2008		97		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/21/2008 3:12:03 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel		pat aguilar lawnmower need service - blades - battey need my weed eater repaired - thank you							
-----------------	--	--	--	--	--	--	--	--	--

Patricio Aguilar									
------------------	--	--	--	--	--	--	--	--	--

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

31806					2/22/2008		96		\$0.00
Medium	Work In Progress				2/22/2008 3:26:23 PM				
Castillo, Carlos		paguilar need lights - philips fc8t9/cw 22watt - philips fc6t9/cw 20watt							

Patricio Aguilar

31868					2/26/2008		0		\$0.00
Medium	Work In Progress				2/26/2008 10:14:40 AM	2/26/2008			
Munoz, Michael		Need to pour new sidewalke to connect existing sidewalk on east side of building to new playground equipment							

Alfredo Holguin

32397					3/7/2008		82		\$0.00
Medium	Work In Progress				3/7/2008 3:33:31 PM				
Castillo, Carlos		pat aguilar need 4 emer light replaced							

Patricio Aguilar

32944					4/3/2008		55		\$0.00
Medium	Work In Progress				4/3/2008 3:09:10 PM				
Castillo, Carlos		No power to ac lower grade wing.							

Patricio Aguilar

33138		Cafeteria			4/7/2008		51		\$0.00
Medium	Work In Progress				4/7/2008 1:09:59 PM				
Moncayo, Fernando		SCREEN DOOR TO KITCHEN NEEDS TO BE REPLACED.							
		DIANA LAZARIN - SNP MGR 589-2425							

Jacqueline Aguilar

33381					4/14/2008		44		\$0.00
Medium	Work In Progress				4/14/2008 7:25:28 AM				
Munoz, Michael		Shed in back of the cafeteria needs to be moved to the other side of the parking lot in the back. (See Diana)							

Diana Gonzalez

33573	Main Building				4/21/2008		37		\$0.00
Medium	Work In Progress				4/21/2008 8:48:06 AM				
Appelzoller, Fred		This work order is for a broken waterline that is on the front sidewalk and we used to water the grass that is in the main entrance so will you please come and fixed for us. THANK YOU.							

Hector Rivera

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
33918					5/1/2008		27		\$0.00
Medium	Work In Progress				5/1/2008 3:24:59 PM				
Lara, Ralph		pat aguilar							
		the hinge is broken off the door frame - need weldding #12							
Patricio Aguilar									
33978					5/4/2008	5/10/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:18:59 AM				
Aguilar, Patricio		Monthly - Desert View ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
34002					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:07 AM				
Aguilar, Patricio		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
34006					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:08 AM				
Aguilar, Patricio		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
34083		Custodial			5/6/2008		22		\$0.00
Medium	Work In Progress				5/6/2008 9:30:37 AM				
Acuna, Sal		This work order is for a wheelbarrow and 3 angle brums I spoke to chuyestrada and he said it was ok so THANK YOU for everiting.				ANGLE BROOMS NEED TO BE ORDERED THRU INVENTORY DIRECT.			
Hector Rivera									
34133					5/8/2008		20		\$0.00
Medium	Work In Progress	Morgan Bldg			5/8/2008 8:42:37 AM				
Aguilar, Patricio		D.V- clean out Morgan Bldg for up coming projects. Hector will support Pat. (any ?'s call Mike)							
Michael Munoz									
34250					5/12/2008		16		\$0.00
High	Work In Progress				5/12/2008 4:19:20 PM				
Aguilar, Patricio		there is sprinkler that is broken south of the cafeteria as you go towards the dumpsters on the hill where used to be. please repair for proper irrigation.							
Michael Munoz									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
34251					5/12/2008		16		\$0.00
High	Work In Progress				5/12/2008 4:21:27 PM				
Aguilar, Patricio		there are red tiles around the campus on the sidewalks that are missing. this is a trip hazard. either order the material to repair the tile or fill w/ concrete.							
Michael Munoz									
34385		Office			5/15/2008		13		\$0.00
Medium	Work In Progress	OFFICE			5/15/2008 3:54:58 PM				
Lara, Ralph		SECRETARY'S DESK NEED A NEW LOCK OR HAVE THE LOCK FIXED.							
Diana Gonzalez									
34419					5/19/2008		9		\$0.00
Medium	Work In Progress				5/19/2008 3:16:50 PM				
Gonzales, Angel		pat aguilar the starter on my loaner truck went out - starter will not turn truck #95							
Patricio Aguilar									
34523	Main Building	Custodial			5/22/2008		6		\$0.00
Medium	Work In Progress				5/22/2008 8:45:17 AM				
Briones, Enrique		This work order is for warehouse will you please come and pickup the computers that are in the storage they are already checked and ready to go we need to clean the storage so they can moved. THANK YOU IN ADVANCED.							
Hector Rivera									
34583					5/23/2008		5		\$0.00
Medium	Work In Progress				5/23/2008 3:23:15 PM				
Castillo, Carlos		paguilar need 3 emer lights replaced dinning room = gym - left frount hall way							
Patricio Aguilar									
34621		Custodial			5/27/2008		1		\$0.00
Medium	Work In Progress				5/27/2008 3:39:47 PM				
Carbajal, Jimmy		This work order is for a broken vacum cleaner something is wrong with the motor it makes alot of noise will you please come and picked up so you can fixed for me.THANK YOU IN ADVANCE.							
Hector Rivera									
Count: 29 Work Orders		Avg. Age of WO's 91		Total for Desert View ES		0		\$0.00	

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC
------------------	------------

24381					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24382					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24383					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin									
-----------------	--	--	--	--	--	--	--	--	--

24815	Pre-K	Classroom			7/16/2007		317		\$0.00
-------	-------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	PRE-K			7/16/2007 4:18:02 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Boyd, David		AS PER JUAN AMBRIZ-ROOF LEAKED IN 2 OF THE PRE-K CLASSROOMS.				ON HOLD UNITL MR. BOYD LOOKS INTO THIS, TO MAKE SURE IT IS NOT UNDER WARRENTY.			
-------------	--	--	--	--	--	--	--	--	--

Mary Garcia									
-------------	--	--	--	--	--	--	--	--	--

24918	RTC	Classroom			7/19/2007		314		\$0.00
-------	-----	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	ACROSS THE			7/19/2007 2:34:45 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		AS PER GLORIA SAENZ-IF A SIDE WALK CAN BE INSTALLED BEHIND THE PORTABLE. THERE IS TO MUCH SAND FOR STUDENT TO WALK IN.				1/14 - Asp Mike route to Lupe			
----------------------	--	--	--	--	--	-------------------------------	--	--	--

Mary Garcia									
-------------	--	--	--	--	--	--	--	--	--

26441		Cafeteria			8/30/2007		272		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/30/2007 9:55:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Water leaking from garbage disposal water line area.							
---------------	--	--	--	--	--	--	--	--	--

		Gessica Blazquez- SNP Manager 882-6784							
--	--	--	--	--	--	--	--	--	--

Alma Terrell									
--------------	--	--	--	--	--	--	--	--	--

26842		Portables			9/10/2007		261		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	STORAGE-MS.			9/10/2007 1:33:27 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Ambriz, Juan		AS PER MS. SALINAS-THE STORAGE UNIT NEEDS ADDITIONAL SHELIVING AND WOULD LIKE TO HAVE SOME INSTALLED. BILINGUAL DEPT. HAS NO MATERIALS FOR THIS, AND WOULD LIKE TO KNOW IF MAINTENANCE WOULD BE ABLE TO SUPPLY THEM WITH THE MATERIALS NEEDED.				9/19 - Asp Mike route to Juan Ambriz			
--------------	--	--	--	--	--	--------------------------------------	--	--	--

Mary Garcia									
-------------	--	--	--	--	--	--	--	--	--

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC
------------------	------------

28141		Office			10/15/2007		226		\$0.00
Medium	Work In Progress	C-WING			10/15/2007 3:07:50 PM				
Miranda, Danny		AS PER SHEILA RAIHL-NEED TO REMOVE OBSERVATION WINDOW IN HER OFFICE.				ASP Mike route to Danny 10/25			

Mary Garcia

28143		Office			10/15/2007		226		\$0.00
Medium	Work In Progress	C-WING			10/15/2007 3:09:23 PM				
Miranda, Danny		AS PER MS. RAIHL-AFTER REMOVING THE WINDOW, THE WALL NEEDS TO BE TAPED/TEXTURED AND PAINTED.				10/25 - ASP Mike route to Danny M.			

Mary Garcia

29377	RTC	Stairway			11/20/2007		190		\$0.00
Medium	Work In Progress	Portable ramps			11/20/2007 3:23:11 PM				
Ambriz, Juan		As per Ms. Julie Hinojosa Ramp boards are warped and separated. Students tripping need to be replaced as soon as possible for Staff and Student safety							

Juan Ambriz

29423	RTC	Portables			11/26/2007		184		\$0.00
Medium	Work In Progress	ACROSS THE			11/26/2007 3:52:43 PM				
Villalobos, David		AS PER GLORIA SAENZ-THERE'S NO HOT WATER IN THE CHILDREN'S PORTABLES.							

Mary Garcia

29783					12/4/2007		176		\$0.00
Medium	Work In Progress				12/4/2007 9:36:05 AM				
Ambriz, Jose		Receptionist Area - Need to check for additional Heating and Cooling (see Mike)							

Michael Munoz

30298					1/6/2008	1/27/2008	143		\$0.00
Medium	Work In Progress				1/6/2008 12:28:56 AM				
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							

Margret Villalobos

30698		Computer Lab			1/16/2008		133		\$0.00
Medium	Work In Progress				1/16/2008 3:30:49 PM				
Ronquillo, Ruben		As per Ms. Socorro need to tint windows in computer lab							

Juan Ambriz

30766		Cafeteria			1/17/2008		132		\$0.00
Medium	Work In Progress	Cafeteria Heating			1/17/2008 3:44:54 PM				
Ambriz, Jose		Need to repair heating unit in cafeteria not working properly							

Juan Ambriz

5/28/2008 3:23:47 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC
------------------	------------

30848					1/22/2008		127		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/22/2008 3:20:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Juan		AS PER IRMA TRUJILLO-SOME OF THE LIGHTS IN CONFERENCE ROOM #2 ARE OUT AND NEED TO BE REPLACED.							
--------------	--	--	--	--	--	--	--	--	--

Mary Garcia

31869		Office			2/26/2008		92		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/26/2008 10:19:59 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose		Gloria Lopez - This office is getting to hot. need to balance system or provide her with a supply diffuser with a damper so she can limit the supply air if necessary.							
--------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

32027					2/29/2008		89		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/29/2008 8:43:11 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		As per Mike generate work order for installation of emergency lighting at the Gac.							
------------------	--	--	--	--	--	--	--	--	--

Michael Munoz

32207		Office			3/3/2008		86		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	C-WING			3/3/2008 11:17:12 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan		AS PER LINDA REYES-NEED TO HAVE DESK LIGHT BULBS REPLACED.							
--------------	--	--	--	--	--	--	--	--	--

Mary Garcia

32512		Office			3/12/2008		77		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	B-WING			3/12/2008 10:18:58 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Lara, Ralph		AS PER MS. BROWDER-NEED AN OFFICE KEY A24 FOR MR. SUTTMILLER.							
-------------	--	---	--	--	--	--	--	--	--

Mary Garcia

32567		Office			3/13/2008		76		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	A WING			3/13/2008 4:47:47 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan		AS PER JULIE-NEED TO HAVE DOOR WINDOW TINTED.							
--------------	--	---	--	--	--	--	--	--	--

Mary Garcia

32656		Office			3/19/2008		70		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-WING			3/19/2008 10:29:55 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Ambriz, Juan		AS PER SALLY-NEEDS A PENCIL DRAWER INSTALLED IN HER OFFICE.							
--------------	--	---	--	--	--	--	--	--	--

Mary Garcia

32837					3/31/2008		58		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/31/2008 8:16:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael		need to build a counter for the mail area							
----------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

5/28/2008 3:23:47 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC
------------------	------------

32919		Mechanical Room			4/2/2008		56		\$0.00
-------	--	-----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress	A-Wing			4/2/2008 3:22:26 PM				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Villalobos, David		Need the gasket for the circulating pump							
Juan Ambriz									

33047					4/6/2008	4/27/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

33055					4/6/2008	4/27/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:20 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos									
--------------------	--	--	--	--	--	--	--	--	--

33218		Hallway/Corridor			4/9/2008		49		\$0.00
-------	--	------------------	--	--	----------	--	----	--	--------

Medium	Work In Progress	A-WING			4/9/2008 8:32:32 AM				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Estrada, Jesus		AS PER JUAN AMBRIZ-NEED TO RETILE THE HALLWAY NEXT TO MAINTENANCE AND CUSTODIAL OFFICES.							
----------------	--	--	--	--	--	--	--	--	--

Mary Garcia									
-------------	--	--	--	--	--	--	--	--	--

33223		Office			4/9/2008		49		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	C-WING			4/9/2008 10:24:19 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Lara, Ralph		AS PER WILMA MARTINEZ-NEED TO HAVE A STORAGE CABINET KEYED. (ITEMS ARE DUE TO COME IN & MUST HAVE THEM LOCKED UP.)							
-------------	--	--	--	--	--	--	--	--	--

Mary Garcia									
-------------	--	--	--	--	--	--	--	--	--

33241		Hallway/Corridor			4/9/2008		49		\$0.00
-------	--	------------------	--	--	----------	--	----	--	--------

Medium	Work In Progress	A-Wing Exit door			4/9/2008 1:15:03 PM				
--------	------------------	------------------	--	--	---------------------	--	--	--	--

Ambriz, Juan		Need to replace door closure on door							
--------------	--	--------------------------------------	--	--	--	--	--	--	--

Juan Ambriz									
-------------	--	--	--	--	--	--	--	--	--

33256		Restroom (Boys)			4/9/2008		49		\$0.00
-------	--	-----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress	A-Wing			4/9/2008 3:16:16 PM				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Castillo, Carlos		Need to replace the whole light in A-Wing restroom							
------------------	--	--	--	--	--	--	--	--	--

Juan Ambriz									
-------------	--	--	--	--	--	--	--	--	--

33422					4/15/2008		43		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	PATIO AREA			4/15/2008 9:42:48 AM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Villalobos, David		AS PER MIKE SORIA-NEED TO REPAIR A BROKEN DRIP LINE TO THE SPRINKLER SYSTEM.							
-------------------	--	--	--	--	--	--	--	--	--

Mary Garcia									
-------------	--	--	--	--	--	--	--	--	--

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

33437		Office			4/16/2008		42		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-WING			4/16/2008 10:53:53 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Lara, Ralph		AS PER OFELIA-NEED TO HAVE ALL HER OFFICE DRAWERS TO BE REKEYED INTO ONE KEY. THIS WAY SHE HAS ONE KEY THAT OPENS AND LOCKS ALL DRAWERS IN THE OFFICE.				RAFA IS AWARE OF THIS			
-------------	--	--	--	--	--	-----------------------	--	--	--

Mary Garcia

33438		Office			4/16/2008		42		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-WING			4/16/2008 10:57:27 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Lara, Ralph		AS PER SALLY S. - NEED TO HAVE ALL HER OFFICE DRAWERS TO BE REKEYED INTO ONE KEY. THIS WAY SHE HAS ONE KEY THAT OPENS AND LOCKS ALL DRAWERS IN THE OFFICE.				RAFA IS AWARE OF THIS			
-------------	--	--	--	--	--	-----------------------	--	--	--

Mary Garcia

33439		Office			4/16/2008		42		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-WING			4/16/2008 11:00:33 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Lara, Ralph		AS PER DORA-NEED TO HAVE ALL HER OFFICE DRAWERS REKEYED INOT ONE KEY. THIS WAY SHE HAS ONE KEY THAT OPENS AND LOCKS ALL DRAWERS IN THE OFFICE				RAFA IS AWARE OF THIS			
-------------	--	---	--	--	--	-----------------------	--	--	--

Mary Garcia

33656	Pre-K				4/23/2008		35		\$0.00
-------	-------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	PLAY GROUND			4/23/2008 7:54:46 AM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Soria, Mike		AS PER MS. BERRY-NEED TO HAVE 2 PLANTERS IN THE BACK OF PRE-K FILLED UP WITH SAND.				OKAY AS PER MR. CHAVEZ			
-------------	--	--	--	--	--	------------------------	--	--	--

Mary Garcia

33672		Office			4/23/2008		35		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	STM POA			4/23/2008 2:24:21 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Castillo, Carlos		AS PER JUANA ESPINOZA-NEED AN ELECTRICAL OUTLET IN THE POA OFFICE/PARENT CENTER.							
------------------	--	--	--	--	--	--	--	--	--

Mary Garcia

33740		Office			4/24/2008		34		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	A-WING			4/24/2008 5:04:54 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Castillo, Carlos		AS PER JUAN A. - NEED TO HAVE AN ELECTRICAL OUTLET MOVED OVER SOME WHAT WITH IN THE SAME WALL IN OREDER TO HAVE EXTRA ROOM FOR SOME CABINETS.							
------------------	--	---	--	--	--	--	--	--	--

Mary Garcia

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC
------------------	------------

33772					4/28/2008		30		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	CHAPARRAL			4/28/2008 1:35:12 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Lozoya, Manny
 NEED TO CHANGE THE KEYS AT THE IDF ROOMS
 @ CHAPARRAL HIGH SCHOOL - PLEASE CALL
 CALIXTO IN THE TECHNOLOGY DEPT. EXT 6274
 FOR INSTRUCTIONS. THANK YOU

Cora Ramirez

33813		Cafeteria			4/29/2008		29		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/29/2008 12:00:38 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando
 WARMER FOR THE PRE-K JUST DIED. (NEEDS IT
 TO TRANSPORT THE FOOD.)

GESSICA B. SNP MGR 882-6784

Jacqueline Aguilar

33905		Hallway/Corridor			5/1/2008		27		\$0.00
-------	--	------------------	--	--	----------	--	----	--	--------

Medium	Work In Progress	FRONT OFFICE			5/1/2008 11:14:15 AM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Castillo, Carlos
 AS PER ART-NEEDS AN ELECTRICAL OUTLET
 INSTALLED. (FOR A NEW TV MONITOR)

Mary Garcia

33945					5/2/2008		26		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	Reception Area			5/2/2008 10:53:10 AM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Castillo, Carlos
 New refreg package unit will be installed @ GAC
 (Reception Area).

Michael Munoz

33946					5/2/2008		26		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	Reception Area			5/2/2008 10:57:36 AM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Ambriz, Jose
 New refreg package unit will be installed @ GAC
 (Reception Area).

Michael Munoz

33949		Office			5/2/2008		26		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	A-WING			5/2/2008 1:42:23 PM				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Lara, Ralph
 AS PER CORA-NEED TO HAVE AN AB36 KEY MADE
 FOR MARCO PERALES W/TECHNOLOGY.

Mary Garcia

34082		Cafeteria			5/6/2008		22		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/6/2008 9:19:08 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Moncayo, Fernando
 BRAKE WHEEL TO STOVE IS BROKEN.

GESSICA B. SNP MGR 882-6784

Jacqueline Aguilar

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC
------------------	------------

34205		Office			5/9/2008		19		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	A-WING			5/9/2008 3:04:11 PM				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Ronquillo, Ruben
AS PER ART R.-IF COULD HAVE HIS OFFICE WINDOW REMOVED WHICH HAPPENS TO BE A SLIDE WINDOW AND INSTALL 1 SOLID PIECE WINDOW. (DUE TO TOO MUCH EQUIPMENT IN HIS OFFICE DIRT KEEPS COMING IN)

Mary Garcia

34238					5/12/2008		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/12/2008 3:03:11 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael
Need to abate tile and have an air clearance,so work order 33218 can be completed.

Michael Munoz

34264		Office			5/13/2008		15		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-WING			5/13/2008 12:58:51 PM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Ambriz, Juan
AS PER SALLY-NEED A BULLETIN BOARD INSTALLED IN HER OFFICE.

Mary Garcia

34265		Office			5/13/2008		15		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-WING			5/13/2008 1:02:38 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan
AS PER LEZIE LEYVA-NEED TO HAVE A KEYBOARD INSTALLED.

Mary Garcia

34310		Cafeteria			5/14/2008		14		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/14/2008 10:54:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
Fernando needs keys for GAC Kitchen and Electric/Mechanical Room

Demetrious P. Giovas - SNP Director

Alma Terrell

34318					5/14/2008		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Board Room			5/14/2008 3:05:18 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Castillo, Carlos
Need to replace 4 Emergency Lights in the board room not working

Juan Ambriz

34320		Parking Lot			5/14/2008		14		\$0.00
-------	--	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Flag pole			5/14/2008 3:23:22 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Orozco, Danny
Need to replace the rope and hooks on the flag pole

Juan Ambriz

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
34345					5/15/2008		13		\$0.00
High	Work In Progress				5/15/2008 10:34:59 AM				
Ambriz, Jose		Need to replace server room a/c unit.							
Juan Ambriz									
34424					5/19/2008		9		\$0.00
Medium	Work In Progress	Front lobby			5/19/2008 3:27:45 PM				
Ambriz, Juan		As Per Art Rulioba need to Install TV stand and TV in front lobby							
Juan Ambriz									
34443		Office			5/20/2008		8		\$0.00
Medium	Work In Progress	C-WING			5/20/2008 2:13:34 PM				
Ambriz, Juan		AS PER IRMA SUAREZ-NEED TO HAVE A CART ASSEMBLED.							
Mary Garcia									
34524					5/22/2008		6		\$0.00
Medium	Work In Progress	Front lobby			5/22/2008 8:59:01 AM				
Castillo, Carlos		Need to install power/outlet to TV in front lobby.							
Art Ruiloba									
34547		Hallway/Corridor			5/22/2008		6		\$0.00
Medium	Work In Progress	A-Wing Unit			5/22/2008 3:35:23 PM				
Ambriz, Jose		A-Wing Unit not working properly							
Juan Ambriz									
34590					5/23/2008		5		\$0.00
High	Work In Progress				5/23/2008 4:09:28 PM				
Castillo, Carlos		power went out to entire bldg. please look into problem							
Michael Munoz									
34591					5/23/2008		5		\$0.00
High	Work In Progress				5/23/2008 4:11:17 PM				
Ambriz, Jose		power went out to bldg an blew fuses to a/c units . need to replace and check units when operating.							
Michael Munoz									
34596		Office			5/27/2008		1		\$0.00
Medium	Work In Progress	A-WING			5/27/2008 9:55:26 AM				
Ambriz, Jose		AS PER MARY G. - NEED TO HAVE THE BALLAST REPLACED.							
Mary Garcia									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

34597		Hallway/Corridor			5/27/2008		1		\$0.00
Medium	Work In Progress	A-WING			5/27/2008 9:56:25 AM				
Ambriz, Juan		AS PER ELISA S. -NEED TO HAVE THE BALLAST REPLACED							

Mary Garcia

34599		Office			5/27/2008		1		\$0.00
Medium	Work In Progress	A-WING			5/27/2008 9:59:17 AM				
Ambriz, Juan		AS PER ART R.-NEED TO HAVE A FILING CABINET HUNG IN HIS OFFICE.							

Mary Garcia

34619		Electrical Room			5/27/2008		1		\$0.00
Medium	Work In Progress	A-wing Main			5/27/2008 3:31:31 PM				
Castillo, Carlos Juan Ambriz		Need to install conduit in electrical wiring in motor							

Count: 62 Work Orders		Avg. Age of WO's 84					Total for GAC	0	\$0.00
------------------------------	--	----------------------------	--	--	--	--	----------------------	----------	---------------

Location: Gadsden HS

24386					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							

Alfredo Holguin

24823					7/17/2007		316		\$0.00
Medium	Work In Progress				7/17/2007 9:44:36 AM				
Lozoya, Manny		Requested by Agustin Garcia Rm. 310A Academic Building-Door handle to Custodian's storage closet is broken and needs to be replaced before school begins.							

Velia Alarcon

24836					7/17/2007		316		\$0.00
Medium	Work In Progress				7/17/2007 2:30:46 PM				
Lozoya, Manny		Requested by Velia-Four HK7 keys are needed for the Intervention Staff that will be in Rm. 554.							

Velia Alarcon

24912	North Building	Custodial			7/19/2007		314		\$0.00
Medium	Work In Progress				7/19/2007 11:54:19 AM				
Munoz, Joe		The windows in the attendance office need to be washed.							

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

25204	Boys Gym				7/30/2007		303		\$0.00
Medium	Work In Progress	Football Side			7/30/2007 2:49:17 PM				
Lara, Ralph		NEED A NEW DOOR FOR THE BOYS GYM FOOTBALL SIDE LOCKER ROOM DO TO VANDALISM							

Mario Apodaca

25208					7/30/2007		303		\$0.00
Medium	Work In Progress				7/30/2007 3:12:59 PM				
Lozoya, Manny		Requested by Velia for rm. 245 over Varsity Gym-Mr. Foster has placed the Parent Out-Reach Ambassador's in this classroom has their new office. Four HE38 keys are need to issue to the Ambassador's. They will be re-located once a space is found for them.							

Velia Alarcon

25212					7/30/2007		303		\$0.00
Medium	Work In Progress				7/30/2007 3:25:27 PM				
Lozoya, Manny		Requested by Velia-Four HE1 (Gym Keys) are needed for the Parent Out-Reach Ambassador's to open small hallway over the Varsity Gym to access their new office/classroom.							

Velia Alarcon

25221					7/30/2007		303		\$0.00
Medium	Work In Progress				7/30/2007 3:44:32 PM				
Lozoya, Manny		Requested by Velia for Rm. 126A Main Building-Four HH16 keys are needed to office.							

Velia Alarcon

25225					7/30/2007		303		\$0.00
Medium	Work In Progress				7/30/2007 4:00:35 PM				
Lozoya, Manny		Requested by Velia for Rm. 554 Wood Shop-Four HK7 keys are needed for Intervention Staff.							

Velia Alarcon

25259					7/31/2007		302		\$0.00
Medium	Work In Progress				7/31/2007 10:22:16 AM				
Lozoya, Manny		Requested by Oscar Menchaca Rm. 123 Custodial Storage Room in Main Building-Door lock does not work.							

Velia Alarcon

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

25260 7/31/2007 302 \$0.00

Medium Work In Progress 7/31/2007 10:34:23 AM

Lozoya, Manny Requested byDebbie CostalezRm. 118 Bookkeeper's Office in Main Building-The bookkeeping office in the same as the concession stand. The concession stand is going to be used as a Marketing classroom. The bookkeeping office needs to be off master and four keys are needed.

Velia Alarcon

25342 Boys Gym Dressing Room 8/2/2007 300 \$0.00

Medium Work In Progress 8/2/2007 1:24:08 PM

Lozoya, Manny NEED A NEW DOOR CYLINDER AT THE GIRLS LOCKEROOM AT BOYS GYM ROOM 404

Mario Apodaca

25343 Cafeteria (1998) Restroom (Boys) 8/2/2007 300 \$0.00

Medium Work In Progress 8/2/2007 1:26:39 PM

Lozoya, Manny BOYS RESTROOM NEED A NEW LEVER LOCKSET FOR THE DOOR

Mario Apodaca

25344 Academic Bldg 8/2/2007 300 \$0.00

Medium Work In Progress 8/2/2007 1:30:21 PM

Lozoya, Manny A KEY IS BROKEN IN A DOOR CYLINDER AT ACADEMIC BLDG ON THE N-SIDE OF TNE BLDG

Mario Apodaca

25682 Old English Bldg Restroom (Boys) 8/9/2007 293 \$0.00

Medium Work In Progress 8/9/2007 2:51:13 PM

Lozoya, Manny BOYS RESTROOM AT THE TOP FLOOR NEED A NEW KEY CYLINDER

Mario Apodaca

25689 8/9/2007 293 \$0.00

Medium Work In Progress 8/9/2007 3:38:10 PM

Lozoya, Manny Attn;MR. LATOYA my key is about to break,need one asap THANK YOU!!

Fernando Moncayo

25690 8/9/2007 293 \$0.00

Medium Work In Progress 8/9/2007 3:40:46 PM

Lozoya, Manny CAFETERIA WEST wing door lock has something inside the cylinder

Fernando Moncayo

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

25691	Varsity Gym	Gym			8/9/2007		293		\$0.00
-------	-------------	-----	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/9/2007 3:43:17 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny
GIRL'S dressing rooms in VARSITY gym, has a broken lock handle

Fernando Moncayo

25726	Concession	Football Field			8/10/2007		292		\$0.00
-------	------------	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/10/2007 3:12:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
CONCESSION STAND AT FOOTBALL NEED A NEW DOOR LEVER FOR BACK ROOM

Mario Apodaca

25743					8/10/2007		292		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/10/2007 4:11:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Requested by Ms. Jaraba Rm. 124 Main Building-Rekey desk and three keys will be needed.

Velia Alarcon

25760					8/13/2007		289		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 9:52:12 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Requested by Ms. Jaraba Rm. 124 Main Building-Replace missing cylinder in closet and three keys will be needed.

Velia Alarcon

25763					8/13/2007		289		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 9:57:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Requested by Velia for Cafeteria-A dead bolt lock needs to be installed on both doors that connect the Conference rooms to the kitchen area of the Cafeteria and five keys are needed.

Velia Alarcon

25767					8/13/2007		289		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 11:07:57 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Requested by Velia for Main Building and Academic Building Mail Rooms-Combination locks into mail rooms need to be changed, several students have figured out combination. Also, WO# 17300 has not been completed, please review.

Velia Alarcon

25771					8/13/2007		289		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 11:37:05 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Requested by Ms. Lam Rm. 104 Main Building-Lock of the North door can no be locked.

Velia Alarcon

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
25774					8/13/2007		289		\$0.00
Medium	Work In Progress				8/13/2007 12:04:00 PM				
Lozoya, Manny		Requested by Chief Arms Rm. 203 North Building-Key does not want to open classroom.							
Velia Alarcon									
25782					8/13/2007		289		\$0.00
Medium	Work In Progress				8/13/2007 1:01:42 PM				
Lozoya, Manny		Requested by Velia-Five HJ2 keys are needed for room 801.							
Velia Alarcon									
25783		Gym			8/13/2007		289		\$0.00
Medium	Work In Progress				8/13/2007 1:08:57 PM				
Lozoya, Manny		Requested by Velia-Three HG3 keys are needed (Girl's Gym Office.)							
Velia Alarcon									
25786					8/13/2007		289		\$0.00
Medium	Work In Progress				8/13/2007 1:35:55 PM				
Lozoya, Manny		Requested by Velia Rm. 153 Old English Building-Room # 153 needs to have the door knob replaced and re-keyed, four keys will be needed.							
Velia Alarcon									
25788					8/13/2007		289		\$0.00
Medium	Work In Progress				8/13/2007 1:47:30 PM				
Lozoya, Manny		Requested by Velia-Four D Master keys are needed.							
Velia Alarcon									
25790					8/13/2007		289		\$0.00
Medium	Work In Progress				8/13/2007 1:55:05 PM				
Lozoya, Manny		Requested by Velia-Five HEM1 Master keys are needed.							
Velia Alarcon									
25791					8/13/2007		289		\$0.00
Medium	Work In Progress				8/13/2007 1:59:05 PM				
Lozoya, Manny		Requested by Velia-Two M251 keys are needed for the new Cross Country Coach for restrooms at Football Field.							
Velia Alarcon									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

25894					8/15/2007		287		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	GATE			8/15/2007 2:32:57 PM				
--------	------------------	------	--	--	----------------------	--	--	--	--

Lozoya, Manny

Mr. Joe S. Mendez, would like to request a key for the gate in the back of Gadsden High School by the alfalfa field in the back of schools ground. That he is requesting is (GM-7) master key to lock. If any questions you may reach me at (505) 882-3364.

Joe Mendez

25933					8/16/2007		286		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/16/2007 2:24:53 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos

Emerg. Light not working as per PM24571
Comp. Lab Southside Entrance
Comp. Lab. Storage
Boys Locker Rm
West Wing Panther Hut

Rudy Arreola

25977	Cafeteria (1998)	Restroom (Boys)			8/17/2007		285		\$0.00
-------	------------------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/17/2007 3:20:32 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred

the water fountain by the boys restroom is leaking

Joe Munoz

26031	Counselors				8/20/2007		282		\$0.00
-------	------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2007 10:30:31 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny

NEED LOCK FOR COUNSELING CENTER. PLEASE
SEE LUPE ONTIVEROS FOR DETAILS. THANKS.

Guadalupe Ontiveros

26099					8/21/2007		281		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 2:10:31 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny

NEED SIX NEW LOCK FOR THE NEW POWER
PLANT

Mario Apodaca

26102	Cafeteria (1998)	Restroom (Boys)			8/21/2007		281		\$0.00
-------	------------------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 2:32:13 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny

Requested by Velia for Cafeteria-Door knob for the
Boy's Restroom does not lock properly, needs to be
repaired.

Velia Alarcon

26105	Main Building				8/21/2007		281		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 2:42:35 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny

Requested by Ms. Moreno Rm. 126 Main Building-Lock
for classroom sticks, can't get in or get out.

Velia Alarcon

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

26106	Main Building				8/21/2007		281		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 2:50:45 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Ms. Moreno for Women's Faculty Restroom in Main Building-Keydoes not open restroom.

Velia Alarcon

26109	Old English Bldg				8/21/2007		281		\$0.00
-------	------------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 3:09:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Ms. Spivey Rm. 134 Old English Building-Tighten door knob on room 134-keysticks in lock.

Velia Alarcon

26110	Old English Bldg				8/21/2007		281		\$0.00
-------	------------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 3:12:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Ms. Spivey Rm. 134A Old English Building-Fix door frame on bathroom.

Velia Alarcon

26114	Old English Bldg				8/21/2007		281		\$0.00
-------	------------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2007 3:32:49 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Requested by Ms. Zapien Rm. 154 Old English Building-Request to have name plate made to be placed over door.

Velia Alarcon

26444					8/30/2007		272		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/30/2007 10:45:01 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Requested by Linda Solis Rm. 801 Parent Center-The door between room 801 and 800 won't close, latch is stuck.

Velia Alarcon

26656	Concession	Football Field			9/4/2007		267		\$0.00
-------	------------	----------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/4/2007 11:09:22 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny THE LOCK SET AT CONCESSION STAD NEED WORK

Mario Apodaca

26853	Academic Bldg	Restroom (Boys)			9/10/2007		261		\$0.00
-------	---------------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/10/2007 3:44:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael THE PARTITONS AT ACADIMIC BLDG AT THE BOY'S RESTROOM ARE VANDALIS ON THE E/SIDE WING (4/28/08 Asp Mario has not been done)

Mario Apodaca

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

26892	Counselors	Portables			9/11/2007		260		\$0.00
-------	------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/11/2007 1:01:38 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
We need the door that seperates RM 823 and 822 to lock students are trying to open the door from the other side.

Rudy Arreola

27346	Counselors				9/24/2007		247		\$0.00
-------	------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/24/2007 8:18:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando
Requested by Marie for Counseling Center-Thermostat does not work and it is very hot in Counseling Center.

Velia Alarcon

27519					9/27/2007		244		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/27/2007 3:45:50 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
Requested by Velia for Rm. 109D Main Building Men's Faculty Restroom-The cylinder lock is missing out of the door knob, please replace.

Velia Alarcon

27637					9/30/2007	10/21/2007	241		\$0.00
-------	--	--	--	--	-----------	------------	-----	--	--------

Medium	Work In Progress				9/30/2007 12:17:40 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny
Monthly- Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

27764	Business	Restroom (Boys)			10/2/2007		239		\$0.00
-------	----------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/2/2007 2:58:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred
THE URINAL AT THE BUS BLDG NEED TO BE REPLACE DOTO WATER LEAKING AT THE TOP FLOOR

Mario Apodaca

28064		Electrical Room			10/11/2007		230		\$0.00
-------	--	-----------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/11/2007 1:26:26 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario
All numbers in electrical panels need to be updated.

Jesus Estrada

28138	Business	Hallway/Corridor			10/15/2007		226		\$0.00
-------	----------	------------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/15/2007 3:00:58 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
NEED TO WELD A DOOR HING AT THE BUS BLDG ON THE N-END BOTT FLOOR

Mario Apodaca

28235	Agricultural				10/17/2007		224		\$0.00
-------	--------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/17/2007 2:55:30 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Appelzoller, Fred
THE GAS REGULATOR AT THE AG BLDG IS LEAKING NEED FIXING

Mario Apodaca

5/28/2008 3:23:47 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
28307	North Building				10/19/2007		222		\$0.00
Medium	Work In Progress				10/19/2007 8:03:48 AM				
Vallejo, Albert		Shingles in North bldg(G wing)are coming off from roof				Pending from Fernando			
Fernando Moncayo									
28317		Electrical Room			10/19/2007		222		\$0.00
Medium	Work In Progress				10/19/2007 8:39:04 AM				
Castillo, Carlos		NEED THE ASSIST OF THE ELECTRICAN TOO HELP OUT ON NUMBERING THE BREAKER W/O 28064							
Mario Apodaca									
28397	Cafeteria (1998)				10/23/2007		218		\$0.00
Medium	Work In Progress				10/23/2007 10:56:32				
Vallejo, Albert		Please paint patio frames around canopy area.				Pending from Fernando			
Michael Munoz									
28398	Varsity Gym				10/23/2007		218		\$0.00
Medium	Work In Progress				10/23/2007 10:59:51				
Ambriz, Jose		Please order parts to repair water fountain in lobby area.				Pending from Fernando			
Michael Munoz									
28401	Academic Bldg				10/23/2007		218		\$0.00
Medium	Work In Progress				10/23/2007 11:02:57				
Ontiveros, Guadalupe		Please install irr. watering system to all trees and shurbs around bldg.							
Michael Munoz									
28437	North Building				10/23/2007		218		\$0.00
Medium	Work In Progress				10/23/2007 3:45:44 PM				
Lara, Ralph		Requested by Mr. Belle Rm 213 North Building-Lock on file cabinet is broken-comes out completely.							
Velia Alarcon									
28442	Main Building				10/23/2007		218		\$0.00
Medium	Work In Progress				10/23/2007 3:49:53 PM				
Lara, Ralph		Requested by Velia for Rm. 109d Main Building Men's Faculty Restroom-Lock cylinder has being missing for several months. Students are getting in and ditching, needs to be replaced as soon as possible.							
Velia Alarcon									
28480	Agricultural				10/24/2007		217		\$0.00
Medium	Work In Progress				10/24/2007 11:28:25				
Appelzoller, Fred		REPLACE GAS REGULATORS IN AG BLDG.							
Michael Munoz									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

28707					10/30/2007		211		\$0.00
Medium	Work In Progress				10/30/2007 4:06:05 PM				
Gonzales, Angel		Truck #166 driver's side door won't close,safety issue							
Fernando Moncayo									
28790	Academic Bldg				11/1/2007		209		\$0.00
Medium	Work In Progress				11/1/2007 11:33:00 AM				
Lara, Ralph		Requested by Ms. Kalkwarf for the Faculty Restrooms (both North and South Restroom) in the Academic Building-Door locks do not open at times, difficult to turn key.							
Velia Alarcon									
28792	North Building				11/1/2007		209		\$0.00
Medium	Work In Progress				11/1/2007 12:56:25 PM				
Lara, Ralph		Requested by Ms. Leahy Rm. 215 North Building- Replace door stopper on the south side door.							
Velia Alarcon									
28794	Concession				11/1/2007		209		\$0.00
Medium	Work In Progress				11/1/2007 1:00:55 PM				
Castillo, Carlos		Requested by Ms. I. Ramos for Panther Paw/Concession Stand-Need to have a power outlet put in the backroom of the Concession Stand.							
Velia Alarcon									
28978	Old English Bldg	Classroom			11/6/2007		204		\$0.00
Medium	Work In Progress				11/6/2007 8:07:59 AM				
Lara, Ralph		Old English room 148 door is badly broken complete coming apart, need to be replaced ASAP. Thanks!!							
Fernando Moncayo									
29036					11/7/2007		203		\$0.00
Medium	Work In Progress				11/7/2007 10:24:39 AM				
Lara, Ralph		Requested by Mr. Contaldo Rm. 103 Main Building- Make key for drawer locks. I already gave our Locksmith one of the locks which are all keyed alike.							
Velia Alarcon									
29164	North Building	Hallway/Corridor			11/13/2007		197		\$0.00
Medium	Work In Progress				11/13/2007 12:52:11				
Lara, Ralph		A SET OF DOOR HINGES ARE BROKEN AT N-BLDG BY THE OFFICE AT G -WING NEED TO BE REWELDED							
Mario Apodaca									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

29201					11/14/2007		196		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/14/2007 9:26:12 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Bonnie Sloan for Library-Has a key to a desk that used to work, but they put a new key lock and now it doesn't work, please repair.

Velia Alarcon

29202	Library				11/14/2007		196		\$0.00
-------	---------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/14/2007 9:29:18 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Mr. Grubaugh for Library-The lock is failing on the south emergency exit in the Library. If the lock can not be repaired, the door needs to be chained at night.

Velia Alarcon

29336					11/19/2007		191		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/19/2007 1:21:16 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Mr. McNiece Rm. 213 North Building-2nd door does not shut/lock. (North door)

Velia Alarcon

29337					11/19/2007		191		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/19/2007 1:21:28 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Mr. McNiece Rm. 213 North Building-2nd door does not shut/lock. (North door)

Velia Alarcon

29467					11/27/2007		183		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 4:02:20 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Oscar Menchaca for Rm. 109d Men's Faculty Restroom in Main Building-WORK ORDER # 28442 HAS NOT BEEN COMPLETED. Lock cylinder has been missing for several months. Students are getting in and ditching, needs to be replaced as soon as possible.

Velia Alarcon

29469	North Building				11/27/2007		183		\$0.00
-------	----------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 4:04:53 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Velia for Rm. 217 Men's Faculty Restroom in North Building-Teacher and custodian keys do not open door, something is wrong with cylinder.

Velia Alarcon

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

29797					12/4/2007		176		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 11:06:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Requested by Ms. I. Ramos for Panter Paw/Concession Stand-Check or replace locks, door knob not closing properly.

Velia Alarcon

29798					12/4/2007		176		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 11:08:16 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos Requested by Ms. I. Ramos Panther Paw/Concession Stand-Need additional outlets with more power added in Concession Stand.

Velia Alarcon

29871		Athletic Field			12/6/2007		174		\$0.00
-------	--	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/6/2007 1:57:16 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos please relocate electrical breaker panel box from back of boys home dug out to the north wall.

Michael Munoz

29939					12/10/2007		170		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/10/2007 11:29:34				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph Requested by Mr. Belle Rm. 315 Academic Building-Lock on file cabinet needs to be replaced.

Velia Alarcon

29980					12/11/2007		169		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/11/2007 9:26:32 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose Computer Lab - Leaking water.

Fernando Moncayo

30140					12/17/2007		163		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/17/2007 2:02:11 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario Requested by Mrs. B-Holzhausen Rm. 226 North Building-Replace damaged lab tables.

Velia Alarcon

30141					12/17/2007		163		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/17/2007 2:04:04 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Appelzoller, Fred Requested by Mrs. B-Holzhausen Rm. 226 North Building-Replace sink with deep tub lab sink and drying board.

Velia Alarcon

30142					12/17/2007		163		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/17/2007 2:05:58 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando Requested by Mrs. B-Holzhausen Rm. 226 North Building-Repair or replace broken floor tiles.

Velia Alarcon

5/28/2008 3:23:47 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

30143					12/17/2007		163		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/17/2007 2:09:49 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Mr. A. Lopez for Varsity Softball Field-Sprinkler installed on varsity in-field/wet down dirt.

Velia Alarcon

30145					12/17/2007		163		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/17/2007 2:13:33 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Mr. A. Lopez for JV Softball Field-Dug out 1/8 - Route to Lupe asp Mike shade for JV field.

Velia Alarcon

30151	North Building	Office			12/17/2007		163		\$0.00
-------	----------------	--------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/17/2007 3:16:51 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny THE DOOR LOCKSET AT THE N-BLDG OFFICE IS NOT LACKING W/KEY

Mario Apodaca

30493		Athletic Field			1/10/2008		139		\$0.00
-------	--	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/10/2008 3:07:55 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Need Storage by home dug -out to be build of cinder block.As per Coach Yanes.

Guadalupe Ontiveros

30629					1/15/2008		134		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/15/2008 10:06:31 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Commander Snarr Rm. 203 North Building-Room door is broken at hinges and swings open freely.

Velia Alarcon

30631		Stairway			1/15/2008		134		\$0.00
-------	--	----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/15/2008 10:10:33 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Julio Alcantar (SO1) for Softball Field-West fence by softball fields need repair for safety reasons.

Velia Alarcon

30690	Agricultural				1/16/2008		133		\$0.00
-------	--------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/16/2008 2:47:00 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos THE GREENHOUSE BREAKER BOX NEED TO BE SERVICE

Mario Apodaca

30738		Athletic Field			1/17/2008		132		\$0.00
-------	--	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/17/2008 11:13:34 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe THE TRACK COACH NEED TOW CONCRETE SLABS (7X7) & (7X28) BY THE SOCCER FIELD

Mario Apodaca

5/28/2008 3:23:47 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

30752					1/17/2008		132		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/17/2008 2:49:53 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Velia-Two HJ11 keys are needed for, one for floating teacher and one for key box (room 660).

Velia Alarcon

30753					1/17/2008		132		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/17/2008 2:53:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Velia-Three F3 keys are needed, one for Security Officer and two for key box.

Velia Alarcon

30755					1/17/2008		132		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/17/2008 3:10:41 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Velia-Two 1HE25 keys are needed, one for I.A. an one for key box (room 200).

Velia Alarcon

30756					1/17/2008		132		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/17/2008 3:12:10 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Velia-Five L Wrenches are needed for classrooms with panic bars.

Velia Alarcon

30792	North Building	Classroom			1/18/2008		131		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/18/2008 1:05:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph NEED TO REPLALE A DOOR AT ROOM 202 AT THE N-BLDG

Mario Apodaca

30793	North Building	Classroom			1/18/2008		131		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/18/2008 1:07:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph NEED TO REPLACE A DOOR AT ROOM 203 AT THE N-BLDG

Mario Apodaca

30795	Old English Bldg	Gym			1/18/2008		131		\$0.00
-------	------------------	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/18/2008 1:14:35 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos THE GIRLS GYM THE LAMPS NEED TOBE SERVICE BULBS NEED CHANGE-OUT

Mario Apodaca

30796	Computer	Computer Lab			1/18/2008		131		\$0.00
-------	----------	--------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/18/2008 1:15:53 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos OUTSIDE LAMPS NEED TOBE SERVICE

Mario Apodaca

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

30929	Main Building	Restroom (Boys)			1/24/2008		125		\$0.00
-------	---------------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/24/2008 3:04:11 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
MENS RESTROOM AT THE MAIN BLDG NEED TOBE REKEY TO (H-E RO D) KEY

Mario Apodaca

30998	Cafeteria (1998)	Cafeteria			1/28/2008		121		\$0.00
-------	------------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/28/2008 3:46:49 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
Requested by Marie for entrance to West Conference room in the Cafeteria-Her HE1 key does not open the door. She needs to access her Cum Files located in the West Conference storage room. Please repair as soon as possible.

Velia Alarcon

31035		Dressing Room			1/29/2008		120		\$0.00
-------	--	---------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/29/2008 3:18:16 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
Wrestling room (507) - Keycylinder spins but does not engage lock

Albert Vallejo

31036	North Building	Restroom (Boys)			1/29/2008		120		\$0.00
-------	----------------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/29/2008 3:20:45 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
North building (217) - Key will not unlock door (it IS the proper key)

Albert Vallejo

31174	Cafeteria (1998)	Cafeteria			2/1/2008		117		\$0.00
-------	------------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/1/2008 3:03:38 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Moncayo, Fernando
NEED NEW BULBS SOCKET FOR THE COOLER AT THE SERVING LINE

Mario Apodaca

31319					2/5/2008		113		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/5/2008 3:19:20 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
Requested by Coach R. Yanez for Baseball Field-Extra keys to storage shed lock made for Assistant Coaches or format shed lock and office key to be the same for both. Shed lock key # CG2 (3 extra) Office key # HE43.

Velia Alarcon

31322	Library	Library			2/5/2008		113		\$0.00
-------	---------	---------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/5/2008 3:23:48 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
Requested by Mr. Grubaugh Rm. 275 Library-The front door to the Library is becoming very hard to open. It sticks even when it's unlocked.

Velia Alarcon

5/28/2008 3:23:48 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden HS

31340					2/5/2008		113		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/5/2008 4:27:04 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph Requested by Mr. Belle Rm. 315 Academic Building-
WORK ORDER #29939 HAS NOT BEEN COMPLETED
-Lock on file cabinet needs to be replaced. It is totally
broken and it pulls out of the socket.

Velia Alarcon

31357					2/6/2008		112		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/6/2008 10:32:04 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Mr. Belle Rm. 200 North Building-The
lock on the classroom door needs to be fixed, keys do
not lock the door.

Velia Alarcon

31358	North Building				2/6/2008		112		\$0.00
-------	----------------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/6/2008 10:34:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Velia for Rm. 217 Men's Faculty
Restroom in North Building-WORK ORDER #29469
HAS NOT BEEN COMPLETED-Teacher and custodian
keys do not open door, something is wrong with
cylinder.

Velia Alarcon

31360	Boys Gym				2/6/2008		112		\$0.00
-------	----------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/6/2008 10:39:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Mr. Mora Rm. 403 Boys Gym-Athletic
training room door broke again, request a door that
latches.

Velia Alarcon

31386	Grounds Shop	Athletic Field			2/7/2008		111		\$0.00
-------	--------------	----------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/7/2008 7:38:00 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos As per Raul Sanchez disconnect irrigation pump to be
pulled out by Anthony P ump. Will need to return and
reconnect

Carlos Castillo

31470	North Building	Classroom			2/11/2008		107		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	221			2/11/2008 3:07:48 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lara, Ralph The teachers key will not work on her classroom door.

Albert Vallejo

31471					2/11/2008		107		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/11/2008 3:10:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben I am missing Eighteen (18) ABC Fire extinguishers

Albert Vallejo

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

31631					2/15/2008		103		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/15/2008 1:50:31 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben
Albert Vallejo
Need to install a rack on Albert Vallejo truck.

31833					2/25/2008		93		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 2:58:02 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
Requested by Ms. Hamilton Rm. 562 Ag. Shop-
Classroom door is sticking and can not be opened with
key.

Velia Alarcon

31837					2/25/2008		93		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 3:05:19 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
Requested by Velia for key box-Two M114 keys are
needed (key to restrooms in Varsity Gym)

Velia Alarcon

31840	Auto Shop				2/25/2008		93		\$0.00
-------	-----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 3:12:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Requested by Mr. Carrasco Rm. 580 A Auto Shop-Need
10 rough service gowah bulbs.

Velia Alarcon

31844	Cafeteria (1998)	Cafeteria			2/25/2008		93		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 3:30:51 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
NEED TO DO A GENERAL CLEANING-UP OUTSIDE
THE CAFE BLDG FOR THE BOARD METING ON THE
2-28-08

Mario Apodaca

31849	North Building	Classroom			2/25/2008		93		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 3:40:08 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
NEED NEW OUTLET FOR THE TOW NEW
COMMERCIAL MICROWAVE AT THE N-BLDG TO
ROOM 233 FOR NEXT SCHOOL YEAR

Mario Apodaca

31933					2/27/2008		91		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2008 11:35:58 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Joe
NEED TO CLEAN UP AREA (TRASH, OLD
ENTRANCE MAT,CANS) WEST SIDE WALK BY
GIRLS GYM NEXT TO BOILER ROOM AND ALSO
LIFT STATION AREA BY BUS TURN AROUND NEXT
TO ACADEMIC BUILDING.

Michael Munoz

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

31934					2/27/2008		91		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2008 11:46:45 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vallejo, Albert
NEED TO REPAIR SOFFITT ??? (OVERHANG) BY
MAIN BUILDING ON SOUTH SIDE OF BLDG.

Michael Munoz

31941	Grounds Shop				2/27/2008		91		\$0.00
-------	--------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2008 3:09:18 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
As per Coach Lopez, They want an electrical outlet
installed at the field to accomodate a pitching machine.

Albert Vallejo

31944	Academic Bldg	Hallway/Corridor			2/27/2008		91		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/27/2008 3:17:31 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Only about 20% of the emergency lights in the hallways
are functioning.

Albert Vallejo

32218					3/3/2008		86		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

High	Work In Progress				3/3/2008 2:40:40 PM				
------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
Requested by Mr. Grubaugh for Library-The emergency
exit by the boy's bathroom has a broken lock. It needs to
be chained nightly for security purposes. Please fix as
soon as possible.

Velia Alarcon

32220					3/3/2008		86		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/3/2008 2:46:43 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos
the outside lights of the annex, weight room, boys need to
be service

Mario Apodaca

32222					3/3/2008		86		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/3/2008 2:58:22 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David
Requested by Mr. Grubaugh for Boy's Restroom in
Library-There is a urinal in the boy's restroom that has
not worked in some time. The water in it is stagnant and
foul smelling.

Velia Alarcon

32227		Athletic Field			3/3/2008		86		\$0.00
-------	--	----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/3/2008 3:10:22 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos
Requested by Coach A. Lopez for J.V. Softball-J.V.-
electrical box behind basketop for pitching machine.

Velia Alarcon

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
32289	Grounds Shop				3/5/2008		84		\$0.00
Medium	Work In Progress				3/5/2008 8:12:31 AM				
Castillo, Carlos Guadalupe Ontiveros Needs outlets installed outside Grounds Shop.									
32338					3/6/2008		83		\$0.00
Medium	Work In Progress				3/6/2008 9:19:28 AM				
Castillo, Carlos Guadalupe Ontiveros Please check switch at irrigation well.									
32481	Concession	Auditorium			3/11/2008		78		\$0.00
Medium	Work In Progress				3/11/2008 3:30:38 PM				
Castillo, Carlos NEED #2 NEW OUTLET FOR THE NEW COMMERCIAL MICROWAVE OVENS AT THE OLD ENG CONCESSION STAND									
Mario Apodaca									
32697		Gym			3/25/2008		64		\$0.00
Medium	Work In Progress				3/25/2008 1:42:41 PM				
Ontiveros, Guadalupe Need to landscape Area and install irrigation system. area to incould plants & trees.									
Guadalupe Ontiveros									
32826	Boys Gym	Dressing Room			3/28/2008		61		\$0.00
Medium	Work In Progress				3/28/2008 3:29:00 PM				
Ronquillo, Ruben Albert Vallejo need two 16" x 48" x 1/4" wired glass.									
32848	Old English Bldg				3/31/2008		58		\$0.00
Medium	Work In Progress				3/31/2008 2:31:12 PM				
Villalobos, Margret Jose Ambriz Need to check all A/C with Tracer Summit.									
32851	Academic Bldg	Classroom			3/31/2008		58		\$0.00
Medium	Work In Progress				3/31/2008 3:13:27 PM				
Castillo, Carlos NEED NEW OUTLES FOR THE COMPUTERI AT ROOM 306									
Mario Apodaca									
32940					4/3/2008		55		\$0.00
Medium	Work In Progress				4/3/2008 11:40:07 AM				
Ronquillo, Ruben Requested by Coach Hite for J.V. Locker Room-Fix broken benches, new legs are needed. Safetyhazard.									
Velia Alarcon									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

32981	Business				4/4/2008		54		\$0.00
-------	----------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/4/2008 2:45:29 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Munoz, Michael Rm 610, all sewing machines need to be serviced for up-coming year. Thanks

Carey Chambers

33026					4/6/2008	4/14/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:11 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Apodaca, Mario Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.

Margret Villalobos

33088					4/6/2008	4/14/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:31 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Apodaca, Mario Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

33125					4/7/2008		51		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/7/2008 10:12:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert Requested by Coach Hite for Football Fieldhouse and Hallway in the Boys Gym - Remove carpet in hall and Varsity Locker Room. Carpet is rolled up and a safety hazard and a health hazard.

Velia Alarcon

33129					4/7/2008		51		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/7/2008 10:30:33 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred Requested by Coach Hite for Boiler Room in Football Fieldhouse in the Boys Gym - Hot water heater has smelly water. Drain and clean hot water tank, water was black the first time I used it.

Velia Alarcon

33131					4/7/2008		51		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/7/2008 11:04:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert Requested by Coach Hite for Boys Gym (Outside Building) - Paint fieldhouse and restore Panther Pride logo. Speak to Coach Hite first, before starting on this job.

Velia Alarcon

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

33137					4/7/2008		51		\$0.00
Medium	Work In Progress				4/7/2008 12:34:30 PM				
Lara, Ralph		Requested by Mr. Chambers Assistant Principal for Joe Munoz Head Custodian-Two Grand Masters with digits 6 & 7 for the entire school at G.H.S. Mr. Chambers had requested these keys over two years ago. These keys will be assigned to Mr. Chamber and Joe Munoz for those days that we might have emergencies on our campus.							

Velia Alarcon

33184	Main Building	Classroom			4/8/2008		50		\$0.00
Medium	Work In Progress				4/8/2008 11:26:32 AM				
Appelzoller, Fred		Requested by Ms. Lam Rm. 104 Main Building-Faucet (on the south side of the room) has sulfur bacteria growing both in cold and hot water lines.							

Velia Alarcon

33187	Academic Bldg	Classroom			4/8/2008		50		\$0.00
Medium	Work In Progress				4/8/2008 11:44:00 AM				
Castillo, Carlos		Requested by Mr. S. Hernandez Rm. 306 Academic Building (Journalism/Yearbook Classroom)-Need the data and electric outlets re-done. We are currently running computer (19) on 4 outlets. Re-wire classroom--4-5 columns in the back would be great.							

Velia Alarcon

33365					4/13/2008	4/29/2008	45		\$0.00
Medium	Work In Progress				4/13/2008 12:17:02 AM				
Munoz, Joe		Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.							

Jesus Estrada

33398	Main Building	Classroom			4/14/2008		44		\$0.00
Medium	Work In Progress				4/14/2008 3:20:17 PM				
Ronquillo, Ruben		BROKEN WONDOW AT ROOM 126 (30X18) MAIN BLDG							

Mario Apodaca

33627					4/22/2008		36		\$0.00
Medium	Work In Progress				4/22/2008 11:56:40 AM				
Vallejo, Albert		Requested by Coach Hite for Field House (Boy's Gym-Football Locker Rooms)-Paint all lockers in football dressing room areas (maroon).							

Velia Alarcon

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

33629	Academic Bldg	Classroom			4/22/2008		36		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/22/2008 1:25:34 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Apodaca, Mario
Requested by Ms. Foote Rm. 332 Academic Building-
One of the panels covering a ceiling light is falling off
(1/2 way). I'm afraid it will fall completely off and hit a
student. I need someone to come and push it up and in
place.

Velia Alarcon

33630	Varsity Gym	Classroom			4/22/2008		36		\$0.00
-------	-------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/22/2008 1:27:58 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Requested by Ms. Howard Rm. 245 Over Varsity Gym-
Outlet on wall keeps tripping.

Velia Alarcon

33632	North Building	Classroom			4/22/2008		36		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/22/2008 1:35:03 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
Requested by Ms. Anderson Rm. 233 North Building-
Door knob to classroom is loose.

Velia Alarcon

33633					4/22/2008		36		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/22/2008 1:38:24 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
Requested by Mr. Villa Rm. 510 Annex Building (Band
Room)-Double door on south side-door prop mount
came off from the top-inside of the door.

Velia Alarcon

33634	Cafeteria (1998)				4/22/2008		36		\$0.00
-------	------------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/22/2008 1:43:23 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
NEED TOW NEW LAMP FIXTURES FOR THE CAFE
BLDG CUSTODIAN ROOMS (277V)

Mario Apodaca

33635	Football Stadium	Athletic Field			4/22/2008		36		\$0.00
-------	------------------	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/22/2008 1:51:17 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
NEED A NEW DOOR SET FOR THE TRACK ROOM
AT BY THE BLEACHERS

Mario Apodaca

33817	Academic Bldg	Classroom			4/29/2008		29		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/29/2008 2:05:46 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert
Requested by Mr. Cordova Rm. 331 Academic Building-
The wall on the back of the stage needs to be finished
color being black. The light reflects off the white wall and
makes teaching lighting to students impossible.

Velia Alarcon

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden HS

33820					4/29/2008		29		\$0.00
Medium	Work In Progress				4/29/2008 2:55:45 PM				
Ontiveros, Guadalupe	Requested by Coach Hite for Varsity Game Field-Field has grubworms, spray insecticide to kill them.								
Velia Alarcon									

33822					4/29/2008		29		\$0.00
Medium	Work In Progress				4/29/2008 3:08:28 PM				
Apodaca, Mario	4-28-08	1-ASSIST CARLOS C. ON FIXING OUTSIDE LAMPS 1-WORK ON E/COOLER UNIT AT ROOM 569 WATER PUMP 1-TURN-ON AND OFF THE E/COOLER UNIT TO THE OLD ENG BLDG 4-CUT WOOD TO FIX TABLES W/O 301410 1-IN PUT TO SCHOOL DUDE				4/28 - 4			
Mario Apodaca									

33911	North Building	Classroom			5/1/2008		27		\$0.00
Medium	Work In Progress	228			5/1/2008 3:15:21 PM				
Lara, Ralph	Mr. Palmers key broke off inside the cabinet lock (same as 15 other cabinets) I have the pieces of the key that needs to be made.								
Albert Vallejo									

33923					5/1/2008		27		\$0.00
Medium	Work In Progress				5/1/2008 3:33:07 PM				
Ronquillo, Ruben	GLASS AT THE ANNEX BLDG DOORS ON THE EASTSIDE OF BLDG (28X28) X2 ARE BROKEN DO TO VANDALISM								
Mario Apodaca									

34008					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:09 AM				
Vallejo, Albert	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

34011					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:10 AM				
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

34084					5/6/2008		22		\$0.00
High	Work In Progress	Wastewater			5/6/2008 10:08:38 AM				
Sanchez, Raul	BDP-GHS-0002 - Broken line to Back Flow Preventor needs to be fixed, in order to test (asp PM 24385) 4/9/08								
Margret Villalobos									

5/28/2008 3:23:48 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

34088	Agricultural				5/6/2008		22		\$0.00
Medium	Work In Progress				5/6/2008 11:58:49 AM				
Ronquillo, Ruben		NEED TO ORDER SUPPLY TOO FIX THE GREENHOUSE .							

Mario Apodaca

34107	Academic Bldg	Classroom			5/6/2008		22		\$0.00
Medium	Work In Progress	344			5/6/2008 3:38:09 PM				
Lara, Ralph		The lever in Room #344 is broken and in need of replacement							

Albert Vallejo

34144	Varsity Gym				5/8/2008		20		\$0.00
Medium	Work In Progress				5/8/2008 1:55:50 PM				
Lara, Ralph		the key cylinder at locker room 238 not working w/the key							

Mario Apodaca

34146	North Building	Classroom			5/8/2008		20		\$0.00
Medium	Work In Progress				5/8/2008 2:16:27 PM				
Moncayo, Fernando		the food deli cart cooler unit at room 233 is not working good							

Mario Apodaca

34268	North Building	Choral			5/13/2008		15		\$0.00
Medium	Work In Progress				5/13/2008 3:00:46 PM				
Ronquillo, Ruben		A BROKEN GLASS WINDOW AT THE N-BLDG (20"X60") BY THE OFFICE DO TO VANDALISM.							

Mario Apodaca

34315					5/14/2008		14		\$0.00
Medium	Work In Progress				5/14/2008 2:07:40 PM				
Vallejo, Albert		Requested by Ms. Miller Rm. 344 Academic Building- Room number (and in Braille) fell, please put back up.							

Velia Alarcon

34316					5/14/2008		14		\$0.00
Medium	Work In Progress				5/14/2008 2:52:41 PM				
Lara, Ralph		Requested by Velia-Three HK3 keys are needed. One was broken and I need two to keep in the key box.							

Velia Alarcon

34356	Old English Bldg				5/15/2008		13		\$0.00
Medium	Work In Progress				5/15/2008 2:57:45 PM				
Ambriz, Jose		The evaporative cooler on the northwest side of the Old English Building needs to be replaced.							

Albert Vallejo

5/28/2008 3:23:48 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS									
34417	Old English Bldg	Classroom			5/19/2008		9		\$0.00
Medium	Work In Progress	154			5/19/2008 3:00:08 PM				
Lara, Ralph Lock on door has something inside that keeps a key from being inserted and needs to be drilled out									
Albert Vallejo									
34436	North Building	Classroom			5/20/2008		8		\$0.00
Medium	Work In Progress				5/20/2008 9:10:25 AM				
Vallejo, Albert Requested by Ms. Pena for rooms 208 and 209 North Building-Paint classrooms, including kitchen cabinets. New paint is very needed.									
Velia Alarcon									
34437	Business	Classroom			5/20/2008		8		\$0.00
Medium	Work In Progress				5/20/2008 9:18:58 AM				
Castillo, Carlos Requested by Ms. Munoz Rm. 610 Business Building- Electric outlets for sewing machines need to be repaired. Each table has three outlets, one under each sewing machine and one under table.									
Velia Alarcon									
34485					5/21/2008		7		\$0.00
Medium	Work In Progress				5/21/2008 12:08:51 PM				
Lara, Ralph Requested by Coach Hite for Football Field House (Boy's Gym)-We are having a tough time keeping doors locked after hours. All doors need to be re-keyed going into the Football areas. See Coach Hite for type of key (if he wants it off master or not) and key number. Please complete as soon as possible.									
Velia Alarcon									
34543	Main Building	Hallway/Corridor			5/22/2008		6		\$0.00
Medium	Work In Progress				5/22/2008 3:20:11 PM				
Lara, Ralph There is a foreign object inserted into both entry doors making it impossible to lock or unlock either door.									
Albert Vallejo									
34557	Academic Bldg	Classroom			5/23/2008		5		\$0.00
Medium	Work In Progress				5/23/2008 8:32:46 AM				
Apodaca, Mario Requested by Mrs. Gage Rm. 330 Academic Building- Paint classroom walls.									
Velia Alarcon									
Count: 174 Work Orders			Avg. Age of WO's 158		Total for Gadsden HS			0	\$0.00

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

24394					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24395					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24956					7/20/2007		313		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/20/2007 9:53:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acosta, Juan NEED TO RELOCATE ATHLETICS TO OLD PURCHASING PORTABLE, PURCHASING (ALLL EXCETP CONFERENCETABLE) TO GM NURSHING AND GM NURSING TO ATHLETICS. CONTACT PERSONS WOULD BE MR. LOWENBERG & DR GARCIA

Alfredo Holguin

25755	Main Building	Hallway/Corridor			8/13/2007		289		\$0.00
-------	---------------	------------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	A.B WING			8/13/2007 8:23:16 AM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Diaz, Sebastian MAROON TILE IN HALLWAY WALLS ARE BROKEN OFF IN THE A.B WING AND CAFEARIA Route to BM asp Mike- 8/13

Juan Acosta

26297					8/27/2007		275		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/27/2007 1:23:52 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique please provide power to sebastians morgan bldg. THXS

Michael Munoz

26752	Cafeteria				9/6/2007		265		\$0.00
-------	-----------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2007 2:03:39 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Diaz, Sebastian Replace the original tile on the walls by serving doors of cafeteria. (Asp Mike route to Sebastian 123086-Act)-mkv

Michael Munoz

26830	C-Wing	Portables			9/10/2007		261		\$0.00
-------	--------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Athletic Office			9/10/2007 8:37:49 AM				
--------	------------------	-----------------	--	--	----------------------	--	--	--	--

Lozoya, Manny Repair cash boc barrel for keyhas broken and needs to be replaced.

Terry Alvarado

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

26981					9/13/2007		258		\$0.00
Medium	Work In Progress				9/13/2007 7:48:15 AM				
Lozoya, Manny		9/13/07							
		Need to fix all main entrance doors thank you							
Sebastian Diaz									
27253		Gym			9/20/2007		251		\$0.00
High	Work In Progress	Gym/Lockerroom			9/20/2007 4:00:58 PM				
Diaz, Sebastian		Benches need to be replaced in boys lockerroom.							
Maricruz Carrasco									
27385		Office			9/24/2007		247		\$0.00
Medium	Work In Progress	Front Office			9/24/2007 9:48:29 PM				
Lozoya, Manny		Keys needed:							
		(4) V8 for Gym (Outside doors)							
		(1) A3 for Custodial Storage Room							
Maricruz Carrasco									
28830	Cafeteria				11/2/2007		208		\$0.00
Medium	Work In Progress				11/2/2007 1:20:40 PM				
Ronquillo, Ruben		NEED A DOOR COVER FOR FIRE EXTINGUISHER							
		ASP PM 27589.							
Sebastian Diaz									
29876					12/6/2007		174		\$0.00
Medium	Work In Progress				12/6/2007 3:06:03 PM				
Appelzoller, Fred		2nd Request 4/8/08				4/8 - Need to replace a/s/a/p 2nd Request			
		In room 140 need to relpace water fauset sink thank you.							
Sebastian Diaz									
29927	Gym	Gym			12/8/2007		172		\$0.00
Medium	Work In Progress	Storage area			12/8/2007 11:56:48 AM				
Lozoya, Manny		Doors and hindges need to be replace and installed in the storage are located in the gym.							
Veronica Quinonez									
29945					12/10/2007		170		\$0.00
Medium	Work In Progress				12/10/2007 1:14:49 PM				
Lara, Ralph		12/10/07							
		Need to fix door knob in couchers storage in the gym thank you							
Sebastian Diaz									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

30391					1/8/2008		141		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				1/8/2008 12:03:19 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
1/8/08
Need glass window in class door's three doors thank you

Sebastian Diaz

30415	Gym	Dressing Room			1/9/2008		140		\$0.00
-------	-----	---------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	Gym/Official's			1/9/2008 8:56:40 AM				
--------	------------------	----------------	--	--	---------------------	--	--	--	--

Lozoya, Manny
Replace cylinder in Official's dressing room. Hard to open.

Maricruz Carrasco

30682		Office			1/16/2008		133		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Awing/SRO Office			1/16/2008 10:58:43 AM				
--------	------------------	------------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Need 3 keys to SRO Office- F3 as soon as possible. Thank you!

Maricruz Carrasco

30734					1/17/2008		132		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/17/2008 10:58:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
1/17/08
Need fix main entrance doors not closing rights thank you

Sebastian Diaz

30741					1/17/2008		132		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	All GMS Lockers			1/17/2008 11:51:19 AM				
--------	------------------	-----------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
All lockers should have a screw on door so that students don't hide anything in there. To avoid students access to lockers.

Maricruz Carrasco

30817		Office			1/18/2008		131		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	399/100/Secretar			1/18/2008 5:25:38 PM				
--------	------------------	------------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Glass doors needed for room 399, 100-Chacon's Lounge, Secretary's office, and SRO Office as soon as possible.

Maricruz Carrasco

31361	C-Wing	Classroom			2/6/2008		112		\$0.00
-------	--------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	Cwing/C-204/Ms.			2/6/2008 10:46:20 AM				
--------	------------------	-----------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Door does not lock. Tried to fix once but still does not lock.

Maricruz Carrasco

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

31385	Main Building	Cafeteria			2/7/2008		111		\$0.00
Medium	Work In Progress				2/7/2008 4:41:34 AM				
Diaz, Sebastian		CAFETERIA ENTRANCE DOORS FLOOR TILES NEED REPLACING							

Juan Acosta

31653	C-Wing				2/19/2008		0		\$0.00
Medium	Work In Progress	C-Wing			2/19/2008 9:26:22 AM	2/19/2008			
Sotelo, Enrique		Need to replace 2 emerg. lights and 1 exit sign asp PM 31207, 31212							

Sebastian Diaz

31829					2/25/2008		93		\$0.00
Medium	Work In Progress				2/25/2008 12:16:19 PM				
Ontiveros, Guadalupe		Need to fix irrigation waters pipes in front main office thank you							

Sebastian Diaz

32208		Cafeteria			3/3/2008		86		\$0.00
Medium	Work In Progress				3/3/2008 11:21:38 AM				
Orozco, Danny		TOP RIGHT OVEN. TEMP. WILL HEAT UP GOOD AND THEN GOES BACK DOWN AND SHUTS OFF.							

TERRY PORTILLO GMS SNP MGR 882-2824

Jacqueline Aguilar

32254		Office			3/4/2008		85		\$0.00
Medium	Work In Progress	GMS Front Office			3/4/2008 1:15:32 PM				
Lozoya, Manny		Cabinet needs lock, same as others in front office.							

Maricruz Carrasco

32320	Band Room	Parking Lot			3/6/2008		83		\$0.00
Medium	Work In Progress				3/6/2008 5:30:58 AM				
Ontiveros, Guadalupe		IN FRONT OF CAFETERIA AND BAND ROOM SIDEWALKS THERE ARE SINK HOLES							

Juan Acosta

32364					3/6/2008		0		\$0.00
Low	Work In Progress				3/6/2008 3:37:03 PM	3/6/2008			
Lozoya, Manny		Need to meet w/Mike Hogan w/Gencon at 1:00pm on 3- 07-08 to make him keys where needed.							

Michael Munoz

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

32500					3/12/2008		77		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	All Automatic			3/11/2008 11:08:33 PM				
--------	------------------	---------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
 Need to make doors automatic for a student that needs easy access from Portable 501 to Awing to classrooms inside. All doors that are automatic need to be connected at all times for student to use.

Maricruz Carrasco

32502		Office			3/12/2008		77		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Awing/134/A.			3/11/2008 11:18:57 PM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
 Please install locks on Mr. Salas' black filing cabinet and tan storage cabinet as well.

Maricruz Carrasco

32513	Main Building	Library			3/12/2008		77		\$0.00
-------	---------------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/12/2008 11:06:39 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Briones, Enrique
 WE NEED TO HAVE OLD EQUIPMENT THAT IS IN THE LIBRARY PICKED UP FOR DISCARD. THE LIBRARIAN ALREADY HAS THE PAPERWORK WITH TAG AND SERIAL NUMBERS.

Phillip Medina

32763	C-Wing	Classroom			3/27/2008		62		\$0.00
-------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Cwing/204			3/26/2008 11:36:05 PM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Lozoya, Manny
 Need new door knob. It does not lock. Maintenance already tried to fix once.

Maricruz Carrasco

33309					4/10/2008		48		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/10/2008 3:36:14 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
 4/10/08
 Need new locks for extinguisher boxes in AB wing thank you

Sebastian Diaz

33460	Vocational	Classroom			4/17/2008		41		\$0.00
-------	------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Vocational/301			4/17/2008 9:53:49 AM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
 Door lock will not close or sometimes opening is very hard. Door knob lock needs changing out or replaced "V" key.

Maricruz Carrasco

33468					4/17/2008		41		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Moblle Home			4/17/2008 10:46:13 AM				
--------	------------------	-------------	--	--	-----------------------	--	--	--	--

Jacquez, Ricardo
 Please have one of the district plumbers replace the outside water filter at the mobile home.

Yolie Jacquez

5/28/2008 3:23:48 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden MS							
33618		Athletic Field			4/22/2008		36		\$0.00
High	Work In Progress				4/22/2008 7:46:45 AM				
Appelzoller, Fred		1st valve to backflow in fenced tank area is broken. need to replace ASAP. fields are not getting watered.thxs							
Michael Munoz									
33658	Cafeteria				4/23/2008		35		\$0.00
Medium	Work In Progress				4/23/2008 8:24:29 AM				
Miranda, Danny		as per our conversation, please fur-out ducting to cafeteria kitchen.thxs							
Michael Munoz									
33711					4/24/2008		34		\$0.00
Medium	Work In Progress				4/24/2008 10:16:24 AM				
Ontiveros, Guadalupe		NEED TO REPLACE VACUUM BREAKER AND INSTALL HOT BOX BY WATER TANKS.							
Guadalupe Ontiveros									
33907		Office			5/1/2008		27		\$0.00
High	Work In Progress	Front			5/1/2008 12:40:40 PM				
Lozoya, Manny		*Change lock and key to Dr. Garcia, Principal's office and to Maricruz, School Secretary's office. *Change combination to Big Vault in Front office and to smaller vault located inside Big Vault. As soon as possible.							
Maricruz Carrasco									
33922					5/1/2008		27		\$0.00
Medium	Work In Progress				5/1/2008 3:32:10 PM				
Ambriz, Jose		5/1/08 Need to replace water fiuntain in B wing thank you							
Sebastian Diaz									
33979					5/4/2008	5/10/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:18:59 AM				
Diaz, Sebastian		Monthly - Gadsden MS Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
34009					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:09 AM				
Diaz, Sebastian		Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

34014					5/4/2008	5/12/2008	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				5/4/2008 12:19:11 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Diaz, Sebastian Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

34186	Cafeteria	Cafeteria			5/9/2008		19		\$0.00
-------	-----------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/9/2008 9:11:20 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Moncayo, Fernando CONDENCER AT GMS WALK-IN REFRIG. NEEDS TO BE REPLACE.

TERRY PORTILLO SNP MGR 882-2824

Jacqueline Aguilar

34262	Main Building	Mechanical Room			5/13/2008		15		\$0.00
-------	---------------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/13/2008 11:09:14 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose Replace 10 isolation valves on the hot and chilled water piping and replace the evaporator gaskets.

Alfredo Holguin

34322	Main Building				5/14/2008		14		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	B-Wing			5/14/2008 3:35:30 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Lozoya, Manny Need fix main entrance door in B-Wing asap thank you

Sebastian Diaz

34349	Main Building	Custodial			5/15/2008		13		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/15/2008 2:41:36 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acuna, Sal CAN I GET 2 HARDWOOD DOLLIES FOR GMS

Juan Acosta

34387		Office			5/15/2008		13		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

High	Work In Progress	Awing/IEP			5/15/2008 5:52:34 PM				
------	------------------	-----------	--	--	----------------------	--	--	--	--

Solis, Lorenzo Fan in IEP room not working properly. Please fix.

Maricruz Carrasco

34388	Cafeteria	Office			5/15/2008		13		\$0.00
-------	-----------	--------	--	--	-----------	--	----	--	--------

High	Work In Progress	Cafeteria/WAR			5/15/2008 5:56:59 PM				
------	------------------	---------------	--	--	----------------------	--	--	--	--

Diaz, Sebastian As per Dr. Garcia, please install equipment for Enfocus in WAR Room.

Maricruz Carrasco

34391	C-Wing	Portables			5/16/2008		12		\$0.00
-------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/16/2008 5:11:00 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Diaz, Sebastian PORTABLES C-208 CAREER CENTER NEED TO REPLACE WOOD ON RAMPA

Juan Acosta

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden MS

34414	Main Building				5/19/2008		9		\$0.00
Medium	Work In Progress	B-Wing			5/19/2008 10:42:09 AM				
Sotelo, Enrique	Rm 137 (Old Teachers Lounge)- Remove light next to comm. box.								

34446					5/20/2008		8		\$0.00
Medium	Work In Progress	LINE LOCATE			5/20/2008 2:42:39 PM				
Appelzoller, Fred	Need to line locate at Track Field on Thursday, June 5th (See Mike Munoz).								

Michael Munoz

34486					5/21/2008		7		\$0.00
Medium	Work In Progress				5/21/2008 12:32:15 PM				
Diaz, Sebastian	5/21/08 Need to replace A/C motor in warehouse bldg thank you								

Sebastian Diaz

34644					5/28/2008		0		\$0.00
Medium	Work In Progress				5/28/2008 9:18:33 AM				
Diaz, Sebastian	Need to move Office to AE on Thursday, May 29th at 8:00am, also will need the big truck. (Coordinate w/ Sebastian) (Sal Gonzalez, George, Custodial Support will assist).								

Michael Munoz

Count: 54 Work Orders	Avg. Age of WO's 106	Total for Gadsden MS	0	\$0.00
------------------------------	-----------------------------	-----------------------------	----------	---------------

Location: La Union - JTP Alvarez Farms

34489					5/21/2008		7		\$0.00
Medium	Work In Progress				5/21/2008 1:41:05 PM				
Ambriz, Jose	AS PER GLORIA SAENZ-THE AIR UNIT IS NOT WORKING								

Mary Garcia

Count: 1 Work Orders	Avg. Age of WO's 7	Total for La Union - JTP Alvarez Farms	0	\$0.00
-----------------------------	---------------------------	---	----------	---------------

Location: La Union ES

25129					7/26/2007		307		\$0.00
Medium	Work In Progress				7/26/2007 3:49:29 PM				
Lozoya, Manny	7/26/07 Manny can you change door lock for classroom 210 (child safety). Thank you.								

Salvador Gonzalez

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

25962					8/17/2007		285		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Playground/Leach			8/17/2007 10:36:16 AM				
--------	------------------	------------------	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
Need to remove fence between playground and leach fields, level and plant grass.

Alfredo Holguin

26704					9/5/2007		266		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/5/2007 3:26:36 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny
9/5/07
Door knob in classroom is not opening, something inside the cilinder is wrong.

Salvador Gonzalez

26916					9/11/2007		260		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/11/2007 3:45:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
9/11/07
Cali I need assistance to replace lidth bulbs and ballasts in old bldg., ceiling is high and it's hard to get up and down.
Can you help me? Thanks.

Salvador Gonzalez

27864					10/4/2007		237		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/4/2007 8:57:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Need Electrician and Plumber to La Union for locates or can it be s scheduled for today or tomorrow?

Cora Ramirez

27889					10/5/2007		236		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/5/2007 8:00:33 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
10/5/07
David can you check comode in annex building is not flushing righ.

Salvador Gonzalez

30015	2000 Core	Hallway/Corridor			12/12/2007		168		\$0.00
-------	-----------	------------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/12/2007 9:35:10 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
New hallway in front of boys and girls restrooms bulbs need to be replaced.

Santos Galindo

30052	Main Building	Classroom			12/13/2007		167		\$0.00
-------	---------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/13/2007 7:53:39 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
Same light bulb's need to be replaced in room 107.

Santos Galindo

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

30980		Parking Lot			1/28/2008		121		\$0.00
-------	--	-------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/28/2008 2:21:51 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		Relocate Marquee to area on right hand side of parent entrance where light pole small chinese elm is located. Power for lighting not required				2/4/08 - Asp Mike route to Lupe.			
----------------------	--	---	--	--	--	----------------------------------	--	--	--

Richard Chavez

33119					4/7/2008		51		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/7/2008 7:59:56 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David		Install water Fountains for playground area. Install in area between bulding and playground.							
-------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

33619					4/22/2008		36		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/22/2008 7:56:18 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		4-22-08 Can you help replacing burned out outdoor lighth bulbs in parking lot. Thanks.							
------------------	--	---	--	--	--	--	--	--	--

Salvador Gonzalez

33903	Main Building	Classroom			5/1/2008		27		\$0.00
-------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/1/2008 10:55:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Estrada, Jesus		The carpet in rooms 104 and 106 needs to be replaced with tile.							
----------------	--	---	--	--	--	--	--	--	--

Jesus Estrada

33904	Main Building	Classroom			5/1/2008		27		\$0.00
-------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/1/2008 11:09:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Estrada, Jesus		We need half of the carpet removed in room 210(kitchen area East) and tiled.							
----------------	--	--	--	--	--	--	--	--	--

Jesus Estrada

34244					5/12/2008		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/12/2008 3:57:09 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		5-12-08 Cali we need temporary electrical panel to be installed for mercado day(5-16-08). Thanks.							
------------------	--	---	--	--	--	--	--	--	--

Salvador Gonzalez

34334					5/14/2008		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/14/2008 4:17:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		there is a water leak in front of the campus.the plumbers will be working there on the 5/27. will need backhoe for support.contact person d.villalobos. thxs							
----------------------	--	---	--	--	--	--	--	--	--

Michael Munoz

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

34335					5/14/2008		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				5/14/2008 4:23:12 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
 there is a water leak in front of the campus driveway. as per our conversation the backhoe is scheduled for 5/27 for the repair.contact person Lupe.
 thxs

Michael Munoz

34471					5/20/2008		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	LINE LOCATE			5/20/2008 4:14:44 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Castillo, Carlos
 Need to line locate at the west entrance driveway going towards the mobile home by Friday, May 23rd contact Mike Munoz if you have any questions.

Michael Munoz

34472					5/20/2008		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	LINE LOCATE			5/20/2008 4:15:38 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Villalobos, David
 Need to line locate at the west entrance driveway going towards the mobile home by Friday, May 23rd contact Mike Munoz if you have any questions.

Michael Munoz

Count: 18 Work Orders			Avg. Age of WO's 125			Total for La Union ES	0		\$0.00
------------------------------	--	--	-----------------------------	--	--	------------------------------	----------	--	---------------

Location: Loma Linda ES

26188					8/23/2007		279		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/23/2007 11:27:05 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
 LANDSCAPE/PLANT GRASS AND INSTALL A SPRINKLER SYSTEM BETWEEN WINGS.

Alfredo Holguin

27964					10/8/2007		178		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/8/2007 1:16:59 PM	4/3/2008			
--------	------------------	--	--	--	----------------------	----------	--	--	--

Sanchez, Raul
 We need the filters changed for the domestic water.

Rudy Arreola

28459					10/24/2007		217		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/24/2007 8:40:57 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
 The door is hard to open have to push to lock and unlock and the key is hard to turn already tried some silicone spray but its still hard. Mens RR across mr Ramirez RM.

Rudy Arreola

29787					12/4/2007		176		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				12/4/2007 10:29:53 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben
 We need a total of 17 blinds replaced through out the school Mr.Ronquillo allready has a sample of the blind.

Rudy Arreola

5/28/2008 3:23:48 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

29788					12/4/2007		176		\$0.00
Medium	Work In Progress				12/4/2007 10:30:33 AM				
Lozoya, Manny		RM 106 Door handle is broken.							
Rudy Arreola									
29789					12/4/2007		176		\$0.00
Medium	Work In Progress				12/4/2007 10:31:11 AM				
Lozoya, Manny		Rm 204 Door is hard to close is hitting the frame of the door.							
Rudy Arreola									
30186					12/18/2007		162		\$0.00
Medium	Work In Progress				12/18/2007 1:34:10 PM				
Sotelo, Enrique		Emergency Light at Mens rr and hallway in front of Rm 109 not working asp PM29659.							
Rudy Arreola									
30748					1/17/2008		132		\$0.00
Medium	Work In Progress				1/17/2008 2:07:18 PM				
Sotelo, Enrique		Emerg. Lights asp PM 30342 - Mens RR front lobby and hallway not working.							
Rudy Arreola									
31935					2/27/2008		91		\$0.00
Medium	Work In Progress				2/27/2008 1:43:57 PM				
Ontiveros, Joe		We need a water line installed to tap in for irrigation line on the southside of campus.							
Rudy Arreola									
32298					3/5/2008		84		\$0.00
High	Work In Progress				3/5/2008 10:03:28 AM				
Ontiveros, Guadalupe		start on new landscaping project for pto.							
Joe Munoz									
32464					3/11/2008		78		\$0.00
Medium	Work In Progress				3/11/2008 8:29:28 AM				
Ontiveros, Joe		We have a water hose spicket that is stripped and leaking water on the southside of kitchen wall. needs to be replaced.							
Rudy Arreola									
33048					4/6/2008	4/27/2008	-10		\$0.00
Medium	Work In Progress				4/6/2008 12:18:18 AM	3/27/2008			
Orozco, Danny		Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Loma Linda ES							
33744		Custodial			4/25/2008		33		\$0.00
Medium	Work In Progress				4/25/2008 9:56:54 AM				
Estrada, Jesus		THE CARPET IN RM 114 NEEDS TO BE REPLACE. IT HAS ABOUT 6 FEET TORN . (THANKS).							
Luis Solis									
33775					4/28/2008		30		\$0.00
Medium	Work In Progress				4/28/2008 2:29:48 PM				
Holguin, Alfredo		Pour new sidewalks for ADA access to new shade strutures and playground equipment							
Alfredo Holguin									
33982					5/4/2008	5/10/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:00 AM				
Arreola, Rudy		Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
34091		Parking Lot			5/6/2008		22		\$0.00
Safety	Work In Progress				5/6/2008 1:58:44 PM				
Holguin, Alfredo		Provide ADA access (sidewalks) to new playground equipment and metal canopies.							
Alfredo Holguin									
34155					5/8/2008		20		\$0.00
Medium	Work In Progress				5/8/2008 3:10:43 PM				
Lozoya, Manny		Manny Lozoya, Jose Vasquez's key needs replacing. key is very worn out							
Grace Alvarado									
34199					5/9/2008		19		\$0.00
Medium	Work In Progress				5/9/2008 12:14:09 PM				
Lozoya, Manny		Manny, west side door hinge is broken, needs rewelding.							
Grace Alvarado									
34307					5/14/2008		14		\$0.00
Medium	Work In Progress				5/14/2008 9:20:54 AM				
Ontiveros, Guadalupe		AS PER ALFREDO H. DELIVER SAND TO NEW PLAYGROUND EQUIPMENT AREA.							
Alfredo Holguin									
34487					5/21/2008		7		\$0.00
Medium	Work In Progress				5/21/2008 12:44:57 PM				
Lozoya, Manny		Manny, file cabinet in Ms. Blancas needs to be looked at, file cabinet lost its means to be locked.							
Grace Alvarado									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

34488					5/21/2008		7		\$0.00
Medium	Work In Progress				5/21/2008 12:48:42 PM				
Ontiveros, Guadalupe		needing 2 1 inch soleloid valves to replace broken ones in grass area							
Grace Alvarado									
34535					5/22/2008		6		\$0.00
Medium	Work In Progress				5/22/2008 2:05:30 PM				
Solis, Lorenz		We need a new fountain old one busted resovoir tank.							
Rudy Arreola									
34536					5/22/2008		6		\$0.00
Medium	Work In Progress				5/22/2008 2:06:25 PM				
Lozoya, Manny		We need to have the 2 locks on the southside of campus fixed so we can lock the walk in gates.							
Rudy Arreola									
34565					5/23/2008		5		\$0.00
Medium	Work In Progress				5/23/2008 1:43:23 PM				
Ambriz, Jose		Joe, needing new air system placed in PE room							
Grace Alvarado									

Count: 24 Work Orders Avg. Age of WO's 81 Total for Loma Linda ES 0 \$0.00

Location: Mesquite ES

26748					9/6/2007		265		\$0.00
Medium	Work In Progress				9/6/2007 12:07:58 PM				
Lozoya, Manny		manny need new lock for filing cabinet,missing key.							
Romauldo Apodaca									
26940		Portables			9/12/2007		259		\$0.00
Medium	Work In Progress	room 601			9/12/2007 1:45:43 PM				
Lozoya, Manny		Change lock on closet in Portable room 601.							
Priscilla Martinez									
27986					10/9/2007		232		\$0.00
Medium	Work In Progress				10/9/2007 7:50:27 AM				
Ramirez, Joe		NEEDS TO REPLACED 10 TILES ON ROOM #111 THANK YOU LUIS							
Luis Saucedo									
27987					10/9/2007		232		\$0.00
Medium	Work In Progress				10/9/2007 7:52:37 AM				
Ramirez, Joe		ON PORTABLE #229 GIRLS RESTROOMS NEEDS TO REPLACED 9 TILES THANK YOU LUIS							
Luis Saucedo									

5/28/2008 3:23:48 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

28019					10/10/2007		231		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/10/2007 10:35:17				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny Need three doors in the barracks to be replace, they are in very bad shape.

Joe Ramirez

28065					10/11/2007		230		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/11/2007 2:16:24 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe NEED TO REPLEACE (10) TILES ON ROOM #110
THANK YOU LUIS, ANY QUESTIONS ASK LUIS.

Luis Saucedo

29133					11/13/2007		197		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2007 6:44:17 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny need to make a keyfor file cabinet please ask luis.

thank you.
luis

Luis Saucedo

29340		Parking Lot			11/19/2007		191		\$0.00
-------	--	-------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	gate key			11/19/2007 2:16:04 PM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Lozoya, Manny Texas Migrant Council needs a gate key for the north entrance. Will Mr. Munoz or Mr. Holguin please approve this request, and direct me as to how the keys should be handed over. The director for the Texas Migrant Council is Olivia Hinojosa.

Priscilla Martinez

29683					12/2/2007	12/3/2007	178		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium	Work In Progress				12/2/2007 12:30:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.

Margret Villalobos

29684					12/2/2007	12/3/2007	178		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium	Work In Progress				12/2/2007 12:30:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.

Margret Villalobos

29697					12/2/2007	12/3/2007	178		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium	Work In Progress				12/2/2007 12:30:25 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.

Margret Villalobos

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

29719					12/2/2007	12/3/2007	178		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium	Work In Progress				12/2/2007 12:30:34 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.

Margret Villalobos

30574					1/14/2008		135		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/14/2008 6:39:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny the teacher staff bathroom in the 2nd grade wing door lock is not working. thank you luis

Luis Saucedo

30575					1/14/2008		135		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/14/2008 6:46:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny need to make a key for file cabinet for room 204 sedillo class room thank you. luis

Luis Saucedo

30576					1/14/2008		135		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/14/2008 7:40:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny need to replaced latched on girls & boys restrooms on north side of blg. thank you luis

Luis Saucedo

30679	Main Building	Office			1/16/2008		133		\$0.00
-------	---------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	front office			1/16/2008 10:19:41 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny Will you please make a door plaque for our new AP.

Jacob Montano
Assistant Principal

Priscilla Martinez

31213					2/3/2008	2/11/2008	115		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress				2/3/2008 12:30:42 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

31223					2/3/2008	2/11/2008	115		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress				2/3/2008 12:30:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

31249					2/3/2008	2/9/2008	115		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				2/3/2008 12:30:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

5/28/2008 3:23:48 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

31260					2/4/2008		114		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/4/2008 7:05:29 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ramirez, Joe on south hallway under water fountain needs 10 tiles
thank you luis

Luis Saucedo

31303					2/5/2008		113		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/5/2008 9:54:13 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny needs to fix door lock inside of cafeteria by laundry room
please thank you luis

Luis Saucedo

31341					2/6/2008		112		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/6/2008 7:22:50 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ramirez, Joe wall on north & SOUTH BOYS & girls restrooms
entrance needs to be painted

Luis Saucedo

31496					2/12/2008		106		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/12/2008 8:44:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Rooms 111,110,113 tiles need to be replaced they are
the old 6x6 or 8x8 they keep coming off and i believe
they are asbestos type.

Joe Ramirez

31596					2/14/2008		104		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/14/2008 12:02:20 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe I need some assistance with the sprinkler system timer
and stations.

Joe Ramirez

32074					3/2/2008	3/8/2008	87		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:32:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES Monthly FE Inpsection - Refer to
PM schedule details.

Margret Villalobos

32106					3/2/2008	3/10/2008	87		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES Emer. Light Test: Monthly - Refer
to PM schedule details.

Margret Villalobos

32116					3/2/2008	3/10/2008	87		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:09 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to
PM schedule details.

Margret Villalobos

5/28/2008 3:23:48 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Mesquite ES							
32150					3/2/2008		87		\$0.00
Medium	Work In Progress				3/2/2008 12:33:22 AM				
Ramirez, Joe		Monthly - Mesquite ES A-1 Semiannual EVS - Refer to PM schedule details.							
Margret Villalobos									
32152					3/2/2008		87		\$0.00
Medium	Work In Progress				3/2/2008 12:33:23 AM				
Ramirez, Joe		Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.							
Margret Villalobos									
32155					3/2/2008		87		\$0.00
Medium	Work In Progress				3/2/2008 12:33:24 AM				
Ramirez, Joe		Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.							
Margret Villalobos									
32156					3/2/2008		87		\$0.00
Medium	Work In Progress				3/2/2008 12:33:25 AM				
Ramirez, Joe		Monthly - Mesquite ES A-1 Semiannual MCD - Refer to PM schedule details.							
Margret Villalobos									
32157					3/2/2008		87		\$0.00
Medium	Work In Progress				3/2/2008 12:33:25 AM				
Ramirez, Joe		Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.							
Margret Villalobos									
32158					3/2/2008		87		\$0.00
Medium	Work In Progress				3/2/2008 12:33:26 AM				
Ramirez, Joe		Monthly - Mesquite ES A-1 Semiannual UCD - Refer to PM schedule details.							
Margret Villalobos									
32159					3/2/2008		87		\$0.00
Medium	Work In Progress				3/2/2008 12:33:26 AM				
Ramirez, Joe		Monthly - Mesquite ES A-1 Semiannual UCS2 - Refer to PM schedule details.							
Margret Villalobos									
32160					3/2/2008		87		\$0.00
Medium	Work In Progress				3/2/2008 12:33:26 AM				
Ramirez, Joe		Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.							
Margret Villalobos									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

32504	Main Building	Classroom			3/12/2008		77		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	room 605			3/12/2008 9:00:13 AM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Ramirez, Joe
this room has been cleared of old equipment, and we would like for it to be restored so that we may create a classroom environment for testing, our campus needs an area for bi-lingual testing and this is the only room available

Priscilla Martinez

32559					3/13/2008		76		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/13/2008 3:37:43 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Need 2 locks for the sand seperater gates.

Joe Ramirez

32970					4/4/2008		54		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/4/2008 9:48:39 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe
need all grass areas fertilized

Joe Ramirez

32971					4/4/2008		54		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/4/2008 9:50:42 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe
need large pile of dirt removed from north end of playground

Joe Ramirez

33013					4/6/2008	4/12/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:06 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe
Monthly - Mesquite ES Monthly FE Inpsection - Refer to PMs schedule details.

Margret Villalobos

33031					4/6/2008	4/14/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:12 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe
Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.

Margret Villalobos

33092					4/6/2008	4/14/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:33 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe
Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PMs schedule details.

Margret Villalobos

33102					4/6/2008	4/14/2008	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2008 12:18:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe
Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PMs schedule details.

Margret Villalobos

5/28/2008 3:23:49 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

33431					4/15/2008		43		\$0.00
Medium	Work In Progress				4/15/2008 2:43:47 PM				
Ontiveros, Joe		needs to replaced a hose bid is located on (b wing) out side of the blg. thank you.luis							
Luis Saucedo									
33617					4/21/2008		37		\$0.00
Medium	Work In Progress				4/21/2008 6:17:32 PM				
Lozoya, Manny		MASTER KEY HAVE TROUBLE TO OPEN ALL CLASS ROOM PLEASE NEED A NEW ONE, KEY TO ALL. THANK YOU. LUIS							
Luis Saucedo									
33940					5/2/2008		26		\$0.00
Medium	Work In Progress				5/2/2008 7:33:46 AM				
Lozoya, Manny		please on room # 605 need to change door clyinder off master to regular keytheyare using for class room thank you.luis							
Luis Saucedo									
33983					5/4/2008	5/10/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:00 AM				
Ramirez, Joe		Monthly - Mesquite ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
34015					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:11 AM				
Ramirez, Joe		Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
34025					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:15 AM				
Ramirez, Joe		Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
34180					5/9/2008		19		\$0.00
Medium	Work In Progress				5/9/2008 8:08:08 AM				
Estrada, Jesus		rm. 109 several tiles are missing mr. montano is requesting for tile replacement or carpet to be installed.							
Joe Ramirez									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

34181					5/9/2008		19		\$0.00
Medium	Work In Progress				5/9/2008 8:09:28 AM				
Estrada, Jesus		The newly installed carpet in rm. 111 is coming apart at the seams.				5/8/08 - AS PER CHUY, CARPET WILL BE RE-DONE. 5/9- AS PER MICHAEL, IT WILL BE TAKEN CARE OF AFTER SCHOOL IS OUT. INSTALLERS DID NOT TAKE PRECAUTIONS AND IF HE WAS AWARE OF PROBLEM RIGHT AWAY, HE COULD HAVE REPAIRED. CARPET WAS GLUED - FLOOR CONTAINS ASBESTOS, WHICH HE USE PADDING UNDER CARPET. WILL CONTACT CHUY			
Joe Ramirez									

34441 5/20/2008 8 5/20/2008 1:23:35 PM \$0.00

Medium	Work In Progress				5/20/2008 1:23:35 PM				
Carbajal, Jimmy		please the vaccum is broken fro the handle thank you.							
Luis Saucedo		luis							

Count: 52 Work Orders Avg. Age of WO's 108 Total for Mesquite ES 0 \$0.00

Location: North Valley Elementary

33063					4/6/2008	4/27/2008	52		\$0.00
Medium	Work In Progress				4/6/2008 12:18:23 AM				
Orozco, Danny		Monthly - North Valley ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									

33124 4/7/2008 51 4/7/2008 9:30:32 AM \$0.00

Medium	Work In Progress				4/7/2008 9:30:32 AM				
Ontiveros, Joe		requesting special tool for diaphram nut removal (flush valve) to prevent damage to fixtures .asap							
Danny Vega									

33394 4/14/2008 44 4/14/2008 2:21:11 PM \$0.00

Medium	Work In Progress				4/14/2008 2:21:11 PM				
Lozoya, Manny		rm 105-door exterior door doesnt lock-keys jammed in cylinder.help							
Danny Vega									

33395 4/14/2008 44 4/14/2008 2:26:06 PM \$0.00

Medium	Work In Progress				4/14/2008 2:26:06 PM				
Lozoya, Manny		womens restroom in rio grande wing next to 311 wont close /dead-bolt wont turn							
Danny Vega									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: North Valley Elementary

33706					4/24/2008		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/24/2008 8:48:11 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny have one ice maker that needs to be transported-by foods dept asap-

Danny Vega

33709					4/24/2008		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/24/2008 8:57:16 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique rm 100 has one 4ft lamp only-this is used for testing- need additional lighting.

Danny Vega

33766					4/28/2008		30		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/28/2008 11:00:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Boyd, David bad sewer oder in bldg over weekends-spoke to lenny hernandez with county.need to install ckeck valve on our end of line.had same problem at vado(is this warranty wk) this smell stays in bldg most of the day.

Danny Vega

33943					5/2/2008		26		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/2/2008 8:44:47 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny rm211 door will not open/this a safety hazard/student are using 209-exit door .please ck asap

Danny Vega

33985					5/4/2008	5/10/2008	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				5/4/2008 12:19:01 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny Monthly - North Valley ES Monthly FE Inpsection - Refer to PMschedule details.

Margret Villalobos

34018					5/4/2008	5/12/2008	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				5/4/2008 12:19:12 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny Monthly - North Valley ES Emer Light Test: Monthly - Refer to PMschedule details.

Margret Villalobos

34029					5/4/2008	5/12/2008	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				5/4/2008 12:19:16 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PMschedule details.

Margret Villalobos

34044					5/5/2008		23		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	Basketball Courts			5/5/2008 10:07:03 AM				
--------	------------------	-------------------	--	--	----------------------	--	--	--	--

Vega, Danny Need #'s painted for students accountability and organization. (see attachment)

Victor Prieto

5/28/2008 3:23:49 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: North Valley Elementary

34138					5/8/2008		20		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/8/2008 12:51:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
Javier Parra
gas blower needs repair pullstringh recoil

34300		Classroom			5/13/2008		15		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	SPED Classroom			5/13/2008 4:18:52 PM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Selma Nevarez
SPED Room - Please change type of light fixture (too bright) due to student's reaction to light.

34516					5/22/2008		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/22/2008 7:43:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Priscilla Martinez
We need an electrical outlet and cable port installed in our front office so that a VIZIO flat screen may be installed.

Priscilla Martinez

34517					5/22/2008		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/22/2008 7:45:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David
Priscilla Martinez
We also need to have someone check out a main doorway magnet unit that is falling off the wall and the magnet chain has extended too much.

Priscilla Martinez

34525		Library			5/22/2008		6		\$0.00
-------	--	---------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	room 200			5/22/2008 9:40:43 AM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Priscilla Martinez
cable drop in the library for the installation of the flat screen tv. Please visit with Ms. Lucero (Librarian), for this request.

34631		Computer Lab			5/28/2008		0		\$0.00
-------	--	--------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	room 404			5/28/2008 8:22:04 AM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Priscilla Martinez
Computer lab IA needs an old key for a cabinet that was transferred here from the old school.

Priscilla Martinez

Count: 18 Work Orders			Avg. Age of WO's	26		Total for North Valley Elementary	0		\$0.00
------------------------------	--	--	-------------------------	-----------	--	--	----------	--	---------------

Location: Northern On-Track Pre-K (LM)

24401					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:54 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Alfredo Holguin
Yearly - Northern Pre-K (LM) Backflow Inspection - Refer to PM schedule details.

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

26803					9/7/2007		264		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/7/2007 3:00:03 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe		Need to level area north of main bldg (Any ?'s call Alfredo)							
----------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

26877	Main Building	Office			9/11/2007		260		\$0.00
-------	---------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/11/2007 10:49:41 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Re-keylock for social workers filing cabinet.							
---------------	--	---	--	--	--	--	--	--	--

Concepcion Montalvo

28578	Main Building				10/26/2007		215		\$0.00
-------	---------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress	Wilma Martinez			10/26/2007 10:14:50				
--------	------------------	----------------	--	--	---------------------	--	--	--	--

Lozoya, Manny		Need locks with keys installed onto 2 (two) cabinets that hold Migrant supplies. Please contact Wilma Martinez @ 575-649-4800.							
---------------	--	--	--	--	--	--	--	--	--

Lucy Meza

29464					11/27/2007		183		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 3:54:41 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Please have Manny reinstall the key cores in the new hardware sets at La Mesa. He removed the entire cores during const. and needs to be reinstalled. Thanks David							
---------------	--	--	--	--	--	--	--	--	--

David Boyd

30449	Main Building	Office			1/10/2008		139		\$0.00
-------	---------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/10/2008 9:25:14 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Second request - Please, re-keylock for social worker's filling cabinet							
---------------	--	---	--	--	--	--	--	--	--

Concepcion Montalvo

31479					2/11/2008		107		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/11/2008 3:32:43 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny		Need to rake leaves in front of campus, and trim tree behind backstop.							
-------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

31480					2/11/2008		107		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/11/2008 3:33:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny		Need to irrigate.							
-------------	--	-------------------	--	--	--	--	--	--	--

Michael Munoz

31512					2/12/2008		106		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/12/2008 1:50:47 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny		N. Side of Main Bldg need to cut mustard weed and grass.							
-------------	--	--	--	--	--	--	--	--	--

Michael Munoz

5/28/2008 3:23:49 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

31747	Main Building	Office			2/21/2008		97		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/21/2008 12:56:18 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vega, Danny We have some furniture that needs to be assembled: 2 desks, 1 book shelf, 2 lateral files, and 2 hutches.

Gilbert Trujillo

31748	Main Building				2/21/2008		97		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/21/2008 1:04:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny Trim hedges and spray for bees at entrance to school. (An adult with severe allergies to bees was stung by a bee on 2/20/08.)

Gilbert Trujillo

32256	Main Building	Athletic Field			3/4/2008		85		\$0.00
-------	---------------	----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Playground			3/4/2008 1:19:19 PM				
--------	------------------	------------	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe Refill two sand boxes.
Concepcion Montalvo

32603					3/14/2008		75		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/14/2008 3:31:40 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vega, Danny as per our conversation, need irrigation system installed behind main bldg. contact Rosie Reyes for details. trees to be planted by grounds.

Michael Munoz

32606					3/14/2008		75		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/14/2008 3:34:17 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe please install trees as needed behind main bldg. see Rosie Reyes for locations and details. Also Danny Vega will be installing irrigation system. same location. get w/ him so that trees can be on system.

Michael Munoz

32730					3/26/2008		63		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/26/2008 9:06:01 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny NEED TO HAVE KEYS MADE FOR TWO STORAGE CABINETS (PLEASE CONTACT CONCHA MONTALVO)

Cora Ramirez

32734		Athletic Field			3/26/2008		63		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/26/2008 10:47:53 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe need a hose adapter with 2 female ends for hose and sprinkler

Gilbert Trujillo

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)									
32843	Concession	Office			3/31/2008		58		\$0.00
Medium	Work In Progress				3/31/2008 12:46:57 PM				
Lozoya, Manny Gilbert Trujillo unable to unlock 2 doors									
33058					4/6/2008	4/27/2008	52		\$0.00
Medium	Work In Progress				4/6/2008 12:18:21 AM				
Orozco, Danny Margret Villalobos Monthly - La Mesa ES Fire Suppression Insp. - Refer to PM schedule details.									
33580					4/21/2008		37		\$0.00
Medium	Work In Progress				4/21/2008 2:03:03 PM				
Vega, Danny Gilbert Trujillo Need to get a/c's ready.									
33980					5/4/2008	5/10/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:18:59 AM				
Vega, Danny Margret Villalobos Monthly - La Mesa ES Monthly FE Inspection - Refer to PM schedule details.									
34010					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:10 AM				
Vega, Danny Margret Villalobos Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.									
34016					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:12 AM				
Vega, Danny Margret Villalobos Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
34198					5/9/2008		19		\$0.00
Medium	Work In Progress				5/9/2008 11:55:56 AM				
Sotelo, Enrique Gilbert Trujillo east exit door emergency lighting is out. i need one box ballast & wire nuts so i can replace hallway lamp ballast. thanks Danny V.									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

34534					5/22/2008		6		\$0.00
Medium	Work In Progress	LMPRE-K-			5/22/2008 1:52:33 PM				
Ontiveros, Guadalupe		AS PER ANN S./ROSIE REYES-NEED TO HAVE A PLAY HOUSE ASSEMBLED AND SECURED TO THE GROUND OUTSIDE IN THE PLAYGROUND. (TALK W/ROSIE REYES BEFORE SECURING TO GROUND TO MAKE SURE WHERE IT'S GOING TO BE PLACED.)							
Mary Garcia									

Count: 24 Work Orders **Avg. Age of WO's 105** **Total for Northern On-Track Pre-K (LM)** **0** **\$0.00**

Location: Physical Plant Complex

24409					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									

24410					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									

24784					7/16/2007		317		\$0.00
Medium	Work In Progress				7/16/2007 8:03:38 AM				
Ronquillo, Ruben		FORKLIFT SHADE YELLOW CANVAS(MAINT.WHS-2, PUR.WHS-1, F.S. WHS.-1.							
Ruben Ronquillo									

27500	Motor Vehicle				9/27/2007		244		\$0.00
Medium	Work In Progress				9/27/2007 9:30:33 AM				
Gonzales, Angel		PLEASE CHECK WATER PUMP ENGINE, NOT STARTING. THANKS RUBEN							
Ruben Ronquillo									

27501	Motor Vehicle				9/27/2007		244		\$0.00
Medium	Work In Progress				9/27/2007 9:33:12 AM				
Gonzales, Angel		PLEASE CHECK YELLOW DOUBLE AIR TANK COMPRESSOR, IDLE IS NOT WORKING, IT WILL NOT IDLE DOWN WHEN TANKS ARE FULL. THANKS RUBEN							
Ruben Ronquillo									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

27765					10/2/2007		239		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/2/2007 3:03:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
 Ruben Ronquillo
 RELOCATE DOUBLE DOORS ON BARRACK #1.

28418	Motor Vehicle				10/23/2007		218		\$0.00
-------	---------------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 2:10:41 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
 Norma Alvarado
 Transp Office - Install a door stop.

30228	Maintenance	Custodial			12/19/2007		161		\$0.00
-------	-------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/19/2007 9:53:10 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Gonzales, Angel
 ANGEL THE BIG TRUCK #82 IS MAKING A LOT OF NOISE SAL WAS PULLED OVER BY THE POLICE AND WAS TOLD NOT TO USE IT UNTILL IT GETS FIXED.THANK YOU

Jimmy Carbajal

31380					2/6/2008		112		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/6/2008 3:50:47 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose
 Guillermo Hernandez
 Need to recover the units pt from the GAC.

31629					2/15/2008		103		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/15/2008 1:10:46 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
 Peggy Jo Hernandez
 ESA Construction needs the following Site Keys:
 CMS, CHE and LU
 (Need by the end of the day)

31931	Maintenance				2/27/2008		91		\$0.00
-------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	HVAC Shop			2/27/2008 10:42:18 AM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Ontiveros, Joe
 Former Hvac Shop restroom . please remove toilet, sand sink, but leave a drain and h2o supply for the office for futhure sink install.please see me.
 thxs

Michael Munoz

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

32021 2/28/2008 90 \$0.00

Medium Work In Progress 2/28/2008 4:20:32 PM

Lozoya, Manny I need the following plates:
 Yolanda Jacquez
 Michelle Tellez
 Mark Rios
 RudyCastro
 Victoria T. Lopez

I would also like to get a couple of room number plaques made for the office doors:
 Office 1
 Office 2

Vicky Lopez

32026 Maintenance 2/29/2008 89 \$0.00

Medium Work In Progress 2/29/2008 8:40:43 AM

Munoz, Michael NEED 4' FENCE GATE EAST OF PPD PARK. WO FOR MIKE MUNOZ. THANK YOU!

Ruben Ronquillo

32816 Purchasing 3/28/2008 61 \$0.00

Medium Work In Progress 3/28/2008 11:14:18 AM

Munoz, Michael Build a new counter for recieving area.
 Alfredo Holguin

32817 Purchasing 3/28/2008 61 \$0.00

Medium Work In Progress 3/28/2008 11:18:06 AM

Gonzales, Angel The dilivery van needs the walls repaired priferable with some type of metal and also install new metal flooring. This needs to be accomplished as soon as possible.

Alfredo Holguin

32876 Purchasing 4/1/2008 57 \$0.00

Medium Work In Progress 4/1/2008 1:17:58 PM

- Diaz, Sebastian
1. Cover the exposed insulation on the west wall above the garage door.
 2. Seal the openings around the garage door
 3. Seal the gaps along the west wall
 4. Repair holes in northeast wall
 5. Repair, replace, or adjust ceiling covering along the southwest wall so that the covering and insulation doesn't hang down from the ceiling.

Vicky Lopez

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

33224					4/9/2008		49		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/9/2008 10:52:29 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Miranda, Danny
NEED A SHELF PUT IN NEW WINDOW MARY'S OFFICE

Danny Miranda

33328	Maintenance				4/11/2008		47		\$0.00
-------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	HVAC Shop			4/11/2008 8:38:06 AM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Appelzoller, Fred
Need a to connect water to ice machine.

Michael Munoz

33625	Food Services	Cafeteria			4/22/2008		36		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/22/2008 8:43:04 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred
SNP WAREHOUSE - TOLIET HANDLE BROKE OFF

JOHNNY LECHUGA SNP WHSE MGR 882-6927

Jacqueline Aguilar

33831	Maintenance				4/29/2008		29		\$0.00
-------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/29/2008 4:07:14 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
#99 (Mike's Blazer)
Fan is not working and there is water in the condensor.

Michael Munoz

33992					5/4/2008	5/10/2008	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				5/4/2008 12:19:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Diaz, Sebastian
Monthly - Physical Plant FE Inspection - Refer to PM schedule details.

Margret Villalobos

34195	Motor Vehicle				5/9/2008		19		\$0.00
-------	---------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/9/2008 10:37:54 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
AS PER ALFREDO ORDER AND INSTALL A LOCKING GAS CAP FOR CHS BAND TRUCK.

Alfredo Holguin

34196	Maintenance				5/9/2008		19		\$0.00
-------	-------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/9/2008 10:55:18 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Need to switch doors from old HVAC Shop (Double Doors w/Old Elec. Shop (Single Door).
Any questions see Mike

Michael Munoz

34197	Maintenance				5/9/2008		19		\$0.00
-------	-------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/9/2008 10:57:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Miranda, Danny
Need to extend old HVAC office (into new lounge).

Michael Munoz

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
34257	Purchasing	Restroom (Boys)			5/13/2008		15		\$0.00
Medium	Work In Progress				5/13/2008 9:04:01 AM				
Diaz, Sebastian		Sebastian would you please check the exhaust fan in the men's restroom and the toilet, the toilet is loose. Purchasing warehouse Thank you							
Guillermo Hernandez									
34348	Motor Vehicle				5/15/2008		13		\$0.00
Medium	Work In Progress	Transp. Office			5/15/2008 1:55:46 PM				
Diaz, Sebastian		Please install two key cabinets and a drywall board.							
Norma Alvarado									
34407	Purchasing				5/19/2008		9		\$0.00
Medium	Work In Progress				5/19/2008 8:08:33 AM				
Diaz, Sebastian		DISASSEMBLE OLD WOODEN SHELVES AND ASSEMBLE NEW ONES. (Sebastian coordinate w/Rudy and Sal they can support asp Mike).							
Larry Martinez									
Count: 27 Work Orders		Avg. Age of WO's		112	Total for Physical Plant Complex			0	\$0.00

Location:		Riverside ES							
26653					9/4/2007		267		\$0.00
Medium	Work In Progress				9/4/2007 10:32:36 AM				
Holguin, Alfredo		Provide services and materials for installation of new controller to control existing lighting.				Joe V. picked up PO on 9/4-mkv			
Alfredo Holguin									
28486		Cafeteria			10/24/2007		217		\$0.00
Medium	Work In Progress				10/24/2007 2:34:48 PM				
Orozco, Danny		Shelves need to be removed on next session (March, 2008) As per Environment Department - they inspected Riverside on 10/23/07 and their comments were that: Wood shelving in dry storage must be coated with paint or replaced - Repeat violation. Must be corrected within 60 days. Need to inform Maria Nevarez - Inspector, when corrected.							
Alma Terrell		Aida Salcedo, SNP Coordinator 882-6772 & Emilia Carrillo, SNP Manager 589-2550							
28720					10/31/2007		210		\$0.00
Medium	Work In Progress				10/31/2007 9:23:23 AM				
Castillo, Carlos		AS PER OUR CONVERSATION, PLEASE PROVIDE A 120 OUTLET FOR THE ENVIRONMENT DEPT.							
Michael Munoz									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

30226					12/19/2007		161		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/19/2007 9:04:29 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny MR MANNY LOZOYA SIR WE NEED TO REPLACE 3 THREE OUTSIDE LOCK FOR GATES ONE WAS BROKEN AND THE TWO OTHERS WERE STOLEN THEY ARE FOR OUT SIDE GATES THANK YOU SIR

Adan Duran

30851					1/22/2008		127		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/22/2008 3:35:20 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose MR JOSE AMBRIZ SIR THE RELIEF VALUE ON THE BOILER ON NORTH WING IS STAYING OPEN NEED TO REPLACE WAS ABLE TO GET IT TO STOP FOR NOW THANK YOU SIR AND GOD BLESS

Adan Duran

32411		Portables			3/10/2008		79		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 7:59:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Need to connect portable (relocated from GMS).
Michael Munoz

32611	New Wing 1/02	Classroom			3/14/2008		75		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/14/2008 3:40:45 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David need to replace faucet
Carlos Hernandez

32707	New Wing 1/02	Hallway/Corridor			3/25/2008		64		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/25/2008 3:26:50 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben Skylight was broken and sppd was notified made report case#sp2008000390 need to be replaced

Carlos Hernandez

32713	New Wing 1/02	Classroom			3/25/2008		64		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/25/2008 3:36:44 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Need to replace faucet room 126
Carlos Hernandez

33263		Classroom			4/9/2008		0		\$0.00
-------	--	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress				4/9/2008 3:31:09 PM	4/9/2008			
--------	------------------	--	--	--	---------------------	----------	--	--	--

Castillo, Carlos 2 lights are out need ballest and 8 lights in hallway are out need lightbulbs

Carlos Hernandez

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

33559					4/18/2008		40		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/18/2008 3:24:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel		4-18-08							
		need to repair flat tire lawn mower front tire							

Carlos Hernandez

34228					5/12/2008		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/12/2008 10:03:52 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos		Emergency Lights. - 1 light in kictchen and 3 in hallway not working asp PM34017.							
------------------	--	---	--	--	--	--	--	--	--

Carlos Hernandez

34229					5/12/2008		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/12/2008 10:04:51 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos		Exit Sign - 1 in kictchen not working asp PM 34028.							
------------------	--	---	--	--	--	--	--	--	--

Carlos Hernandez

34285					5/13/2008		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/13/2008 3:37:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel		Pickup truck - starter slipping having hard time starting							
-----------------	--	---	--	--	--	--	--	--	--

Carlos Hernandez

34376	New Wing 1/02	Hallway/Corridor			5/15/2008		13		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/15/2008 3:45:32 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben		5-15-08							
		second request as of 3-25-08 skylight was broken due to vandlism need to be replaced							

Carlos Hernandez

34545		Portables			5/22/2008		6		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/22/2008 3:32:45 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		5-22-08							
		a/c unit portable #503 not cooling at times needs therma state							

Carlos Hernandez

34562					5/23/2008		5		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/23/2008 1:04:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		5-23-08							
		refregated air unit not working teachers lounge							

Carlos Hernandez

34620	New Wing 1/02	Classroom			5/27/2008		1		\$0.00
-------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/27/2008 3:38:01 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		5-27-08							
		need to install emergcy light in bathroom in room 121							

Carlos Hernandez

5/28/2008 3:23:49 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

Count: 18 Work Orders Avg. Age of WO's 76 Total for Riverside ES 0 \$0.00

Location: San Miguel ES

31511 2/12/2008 106 \$0.00

Medium Work In Progress 2/12/2008 1:49:39 PM

Vega, Danny Need to start irrigating.

Michael Munoz

32044 Cafeteria 2/29/2008 89 \$0.00

High Work In Progress 2/29/2008 2:33:50 PM

Vega, Danny need remove and dispose all desk, and unused furniture that is on southside. received complaint from community member.

Michael Munoz

32965 4/4/2008 54 \$0.00

Medium Work In Progress 4/4/2008 7:55:33 AM

Lozoya, Manny AS PER ALFREDO, PICK UP KEY FROM MRS. BONHAM. (SAN MIGUEL). FIRST THING MONDAY 4/7/08 MORNING.

Alfredo Holguin

33294 4/10/2008 48 \$0.00

High Work In Progress 4/10/2008 11:36:55 AM

Vega, Danny need to move all tools, equipment, material etc to new location @ north valley asap. morgan bldg to be re-located. let me know when complete. there are plenty of shelves @ san miguel to use for proper storage in new area.

Michael Munoz

33467 4/17/2008 41 \$0.00

Medium Work In Progress 4/17/2008 10:44:25 AM

Ramirez, Joe Please paint portable 5/9SM.

Michael Munoz

33892 Portables 5/1/2008 27 \$0.00

Medium Work In Progress 5/1/2008 9:22:32 AM

Ontiveros, Guadalupe Portable 5/9SM- Need to remove ramps and prepare portable for relocation.

Michael Munoz

33909 Portables 5/1/2008 27 \$0.00

Medium Work In Progress 5/1/2008 2:56:20 PM

Holguin, Alfredo Need to move Portable 5/9SM to Desert Pride Academy.

Alfredo Holguin

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: San Miguel ES

34043					5/5/2008		23		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/5/2008 7:59:45 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Estrada, Jesus
NEED TO REPLACE VCT WITH CARPET IN PORTABLE #5-SM9. THIS PORTABLE WILL BE RELOCATED TO DP. (NOTE: JOE RAMIREZ NEEDS TO PAINT BEFORE CARPET IS INSTALLED)

Michael Munoz

34231					5/12/2008		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				5/12/2008 11:29:22 AM				
------	------------------	--	--	--	-----------------------	--	--	--	--

Vega, Danny
remove weeds from fence lines and treat.

Michael Munoz

34470					5/20/2008		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/20/2008 3:51:32 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael
need to relocate morgan bldg from san miguel to desert pride.

Michael Munoz

34600		Hallway/Corridor			5/27/2008		1		\$0.00
-------	--	------------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	SAN MIGUEL			5/27/2008 10:05:08 AM				
--------	------------------	------------	--	--	-----------------------	--	--	--	--

Ramirez, Joe
AS PER RICHARD G. CHAVEZ-TO HAVE AIR UNIT TURNED ON IN THE SAN MIGUEL ELEM. SCHOOL WERE THE ELECTIONS ARE GOING TO BE HELD. (MY GUESS IN THE ENTRANCE AREA OF THE SCHOOL)

Mary Garcia

AS PER MR. CHAVEZ, TO CHECK W/MIKE AND CHUY ESTRADA IF IT WOULD NOT TAKE TO MUCH TIME IN HAVING SOMEONE CHECK OUT THE AIR UNITS TO BE TURNED ON FOR THIS FUNCTION AND IF SO, THEN GO WITH PORTABLE AIR UNITS. (THIS IS ONLY A ONE DAY FUNTION).

Count: 11 Work Orders			Avg. Age of WO's 40			Total for San Miguel ES	0		\$0.00
------------------------------	--	--	----------------------------	--	--	--------------------------------	----------	--	---------------

Location: Santa Teresa ES

24432					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Yearly - Santa Teresa ES Backflow Inspection - Refer to PMschedule details.

Alfredo Holguin

24433					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Yearly - Santa Teresa ES Backflow Inspection - Refer to PMschedule details.

Alfredo Holguin

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

26342					8/28/2007		274		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/28/2007 8:17:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose
STERLING UNIT TO CAFET. PREP AREA IS NOT WORKING. ACTUATOR TO THE LOUVERS IS STUCK.

Gerardo Marquez

26772					9/6/2007		265		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2007 3:52:06 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David
DAVID, NEED TO CHECK OUT MOP SINK IN C-WING (CASA ROJA) STILL LEAKING.

Gerardo Marquez

27366					9/24/2007		247		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/24/2007 11:10:28 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
NEED TO CHECK OUT EXIT SIGNS THAT FAILED DURING M. INSP. THEY ARE AT RM. 211, LIBRARY MAIN ENTRANCE, & HALLWAY BY FACULTY RRMS.

Gerardo Marquez

29023					11/7/2007		203		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/7/2007 8:46:04 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Boyd, David
STUCCO IS STARTING TO CRACK AND CHIP AT PARAPETS. BLOCK WORK IS ALSO STARTING TO SEPARATE AT MORTAR JOINTS. SHEETROCK IS ALSO BREAKING ABOVE DOORS, AND AROUND DR. JAMBS. EXPANSION JOINTS IN FLOORS SEEM TO BE SEPARATING, THUS CAUSING VCT. TO CRACK.

Gerardo Marquez

30644					1/15/2008		134		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/15/2008 1:26:14 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael
ATTN. MIKE. THE SLAB FOR THE DUMPSTERS HAS ALREADY BEEN POURED. NEED TO HAVE FENCE CONTRACTOR BUILD FENCE, AND GATES LIKE THE ONE IN THE PICTURE YOU SENT US. PLEASE BE SURE THEY INCLUDE THE SLATS.

Pending SB-9 Funding 4/23/08 - mm

Gerardo Marquez

31647	Main Building	Classroom			2/15/2008		103		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	RM 108			2/15/2008 4:23:53 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Marquez, Gerardo
RM 108 HAS A WIDE CRACK ON TOP OF THE ENTRY DOOR. PLEASE CHECK. THANKS.

Rita Mendez

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

31826					2/25/2008		93		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 9:44:30 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben
ATTN. RUBEN RONQUILLO
RUBEN, I NEED FOR YOU TO ORDER WINDOW SCREENS FOR PORTABLES E & F. WHEN DELIVERED THEY WERE MISSING THE SCREENS. HERE ARE THE SIZES AND QUANTITIES NEEDED. 2-- 27 5/8"X 28", 4--43 5/8"X16 1/8" THE FRAMES NEED TO BE BRONZE FINISH. THANKS.

Gerardo Marquez

31847					2/25/2008		93		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 3:37:27 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
ANGEL; AS PER MIKE MUNOZ HE WANTS US TO LET YOU KNOW THAT OUR MOWERS NEED TO BE SERVICED , SO THAT THELL BE READY FOR THE CUTTING SEASON. YOU CAN PICK IT UP AT YOUR EARLIEST CONVENIENCE. THANKS.

Gerardo Marquez

31848					2/25/2008		93		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/25/2008 3:39:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
ANGEL, WE HAVE TWO BLOWERS THAT NEED TO BE SERVICED.

Gerardo Marquez

32415					3/10/2008		79		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 8:58:30 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
ANGEL;TRUCK 107 NEEDS TO HAVE THE OIL CHANGED, AND AND A TUNE UP . PLEASE LET ME KNOW WHEN TO TAKE IT IN. ALSO TRANSMISION SHIFTING REAL HARD.

Gerardo Marquez

32907					4/2/2008		56		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/2/2008 9:23:16 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David
DAVID, THE FAUCET IN THE CONFERENCE RM HAS A CONSTANT DRIP JUST LIKE THE NURSE OFFICE. NEED FOR YOU TO REPLACE IT. THANKS.

Gerardo Marquez

33333		Portables			4/11/2008		47		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	ART PORTABLE			4/11/2008 1:39:17 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Villalobos, David
PLEASE INSTALL SINK IN CLASSROOM. NEEDED FOR ART CLASSES. THANK YOU.

Rita Mendez

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

33684		Athletic Field			4/23/2008		35		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/23/2008 3:30:42 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe LUPE, COULD YOU SCHEDULE SOMEBODY TO AIREATE & FERTILIZE THE GRASS. THANKS.

Gerardo Marquez

33809		Classroom			4/29/2008		29		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/29/2008 10:13:11 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo WE RECEIVED FURNITURE THAT NEEDS TO BE PUT TOGETHER (SHELVES, CARTS ETC.). THANK YOU.

Rita Mendez

33810		Classroom			4/29/2008		29		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	ALL			4/29/2008 10:21:51 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Marquez, Gerardo NEW TELEVISION SETS NEED TO BE SET UP IN THE CLASSROOMS ON HIGH STANDS. ASSISTANCE (AT LEAST 2 PEOPLE) NEEDED TO SET THEM UP. THANK YOU.

Rita Mendez

33971					5/4/2008	5/10/2008	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				5/4/2008 12:18:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

34019					5/4/2008	5/12/2008	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				5/4/2008 12:19:13 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

34030					5/4/2008	5/12/2008	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				5/4/2008 12:19:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

34226					5/12/2008		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/12/2008 9:15:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben MARGARET; THE UPPER WINDOW IN WORK RM. A-WING WAS BROKEN OVER THE WEEKEND. NEED TO HAVE GLASS REPLACED. THANKS.

Gerardo Marquez

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

34288					5/13/2008		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/13/2008 3:42:27 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
CALI; NEED FOR YOU TO CHECK OUT THE GFCI OUTLETS AT P.G CANOPIES. (THEY KEEP POPPING THE BREAKERS.)

Gerardo Marquez

34332		Classroom			5/14/2008		14		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	all areas			5/14/2008 3:59:09 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Lara, Ralph
WE NEED 7 KEYS FOR THE FIRE ALARM BOXES (PULL BOXES). THANK YOU.

Rita Mendez

34333		Restroom (Girls)			5/14/2008		14		\$0.00
-------	--	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	ADULT			5/14/2008 4:05:10 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Marquez, Gerardo
TOILET SEAT COVER DISPENSERS NEED TO BE INSTALLED IN THE RESTROOMS. THANKS.

Rita Mendez

34563					5/23/2008		5		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/23/2008 1:23:49 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
WE ARE UNABLE TO SHUT OFF THE WATER TO THE WASHER IN RM. 101.WE HAVE TURNED OFF ALL THE SHUT OFF VALVES IN THAT AREA, BUT NONE SHUT OFF THE WATER TO THE WASHER.

Gerardo Marquez

34598		Electrical Room			5/27/2008		1		\$0.00
-------	--	-----------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/27/2008 9:57:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose
SERVER ROOM TOO HOT - PATRICK OPENED THE DOORS PLEASE CHECK ASAP

Cora Ramirez

34646		Athletic Field			5/28/2008		0		\$0.00
-------	--	----------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	outside			5/28/2008 9:43:56 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Acuna, Sal
WE ARE REQUESTING 6 55 GALLON DRUM TRASH CANS FOR THE OUTSIDE GROUNDS (IF POSSIBLE WITH LIDS TO KEEP THE TRASH FROM FLYING OUT). THANK YOU.

Rita Mendez

34647		Classroom			5/28/2008		0		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	ROOM 301			5/28/2008 9:47:26 AM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Lara, Ralph
OUR TEACHER, MR. WADE CORNELIUS, LOST THE CLASSROOM KEY. PLEASE CHANGE THE DRUM IN THE DOOR.
LOST KEY #1S19. THANK YOU.

Rita Mendez

5/28/2008 3:23:49 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa ES							
34648		Cafeteria			5/28/2008		0		\$0.00
Medium	Work In Progress				5/28/2008 10:26:42 AM				
Orozco, Danny		KITCHEN AND WASH ROOM SMELLS LIKE A SEWER. (BAD)							
		PATRICIA SANCHEZ SNP MGR 589-3439							

Jacqueline Aguilar

Count: 29 Work Orders	Avg. Age of WO's	89	Total for Santa Teresa ES	0	\$0.00
------------------------------	-------------------------	-----------	----------------------------------	----------	---------------

Location:		Santa Teresa HS							
24419					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:57 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24420					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24421					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24422					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24423					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									
24424					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Alfredo Holguin									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

24425					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24426					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

25499		Cafeteria			8/6/2007		296		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/6/2007 10:44:10 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny NEEDS WATER HOSE FOR USE NEAR DISHMACHINE (DANNY IS AWARE OF THIS REQUEST)

OLGA BUSTAMANTE - SNP MANAGER 589-5332

Alma Terrell

25748					8/13/2007		289		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 8:12:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose NEED SOME ASSISTANCE ON A.C. UNITS ON 600'S WING. BREAKERS #90 FOR EF-17, AND #94 FOR EC -2, WILL NOT STAY ON, NEED TO TROUBLE SHOOT.

Arturo Nunez

27496					9/27/2007		244		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/27/2007 8:31:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph NEED THREE (3) EA. HON LOCKS FOR FILING CABINETS, OVAL AND, ROUND.

Arturo Nunez

29446					11/27/2007		183		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 10:23:34				
--------	------------------	--	--	--	---------------------	--	--	--	--

Gonzales, Angel MOFFLER NEEDS TO BE REPLACE FROM TRUCK #8 THANK YOU

Joel Herrera

29451	Gymnasium				11/27/2007		183		\$0.00
-------	-----------	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 12:41:32				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David WE NEED REPLACE SINCK'S FAUCETS AND REPAIR URINAL'S LEACK AT NEW BOYS LOCKER ROOM AT G.Y.M AREA

Joel Herrera

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

30171 12/18/2007 162 \$0.00
 Medium Work In Progress 12/18/2007 9:40:57 AM
 Villalobos, Margret NEED TO HAVE WORK STATION UP GRADE, CAN'T GET TEMP, DIANOSTICS, ETC. TO FAN COIL UNITS, AND AIR HANDLER UNITS.

Arturo Nunez

31121 1/31/2008 118 \$0.00
 Medium Work In Progress 1/31/2008 9:13:36 AM
 Lara, Ralph MR. WAGNER HE NEEDS TWO KEYS FROM HIS CLASS ROOM

Joel Herrera

31135 Cafeteria (2005) Cafeteria 1/31/2008 118 \$0.00
 Medium Work In Progress 1/31/2008 2:44:30 PM
 Moncayo, Fernando WATER IS LEAKING FROM DISHMACHING - IGNACIA RELAYED MESSAGE TO SNP DEPT.
 OLGA BUSTAMANTE - SNP MANAGER 589-5332

Alma Terrell

31252 2/3/2008 2/9/2008 115 \$0.00
 Medium Work In Progress 2/3/2008 12:30:56 AM
 Nunez, Arturo Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PMSchedule details.

Margret Villalobos

31423 Gymnasium 2/8/2008 110 \$0.00
 High Work In Progress 2/8/2008 1:17:21 PM
 Nunez, Arturo West side of porch, the sheetrock is missing. Please replace and tape and texture (paint). thxs

Michael Munoz

31867 2/26/2008 92 \$0.00
 Medium Work In Progress 2/26/2008 9:03:23 AM
 Villalobos, David NEED A BELL AND GOSSET WATER CIRCULATING PUMP FOR WATER HEATER ON GIRLS RESSROOM.

Arturo Nunez

31870 2/26/2008 92 \$0.00
 Medium Work In Progress 2/26/2008 10:37:38 AM
 Ontiveros, Guadalupe West of Bus Drop off Area- This area is apparently turing into the site dump. dispose of all trash and bring all salvagale itmes to the Physical plant yard.

Alfredo Holguin

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

32077					3/2/2008	3/8/2008	87		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:32:52 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PMSchedule details.

Margret Villalobos

32083					3/2/2008	3/23/2008	87		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:32:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PMSchedule details.

Margret Villalobos

32122					3/2/2008	3/10/2008	87		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/2/2008 12:33:12 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PMSchedule details.

Margret Villalobos

32310		Classroom			3/5/2008		84		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	MS.			3/5/2008 3:36:25 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Castillo, Carlos INSTALL 2 VIDEO PROJECTORS IN CEILING-ELECTRICIAN WORK

Marylou Jimenez

32465					3/11/2008		78		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2008 8:30:22 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph 3/11/08. WE NEED TO REPLACEMENT OF DOOR HANDLE. KEY AREA DOSE NOT WORK IS CONSTANTLY JAMMING. (THIS WORK ORDER IS FOR MANY LOZOYA.)

Manuel Prospero

32499					3/11/2008		78		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2008 4:20:10 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David LINE LOCATE AROUND ECONOMICS BUILDING AND NURSE BUILDING - PLEASE CALL SILVER FOR EXACT LOCATION - PLAN B WILL BE DIGGING ON MARCH 17.

Cora Ramirez

32520					3/12/2008		77		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/12/2008 2:07:55 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph NEED SIX SLIDE LOCKS FOR TROPHY CASES.

Arturo Nunez

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

32525					3/12/2008		77		\$0.00
Medium	Work In Progress				3/12/2008 3:34:13 PM				
Ronquillo, Ruben		NEED A WINDOW REPLACED AT ROOM # 40 R.O.T.C. 30X28X 1/8 INSULATED GLASS.							

Arturo Nunez

32658					3/19/2008		70		\$0.00
Medium	Work In Progress				3/19/2008 10:39:14 AM				
Villalobos, David		NEED SOME ASSISTANCE ON BROKEN AND CRACKED CAST IRON VENT PIPES ON BOYS AND GIRLS RESTROOM ON 300'S WING. EMITTING FOUL SMELL INTO HALLWAY, AND CLASSROOMS.							

Arturo Nunez

32736					3/26/2008		63		\$0.00
Medium	Work In Progress				3/26/2008 11:14:50 AM				
Castillo, Carlos		Asp PM 32122 Gym Area - Missing 2 Emer. Lights Main Lobby - Missing 2 Emer. Lights Athletic Hall - Missing 1 Emer. Lights							

Manuel Prospero

33065					4/6/2008	4/27/2008	52		\$0.00
Medium	Work In Progress				4/6/2008 12:18:23 AM				
Orozco, Danny		Monthly - Santa Teresa HS Fire Suppression Insp. - Refer to PMs schedule details.							

Margret Villalobos

33489					4/17/2008		41		\$0.00
Medium	Work In Progress				4/17/2008 3:02:40 PM				
Castillo, Carlos		NEED TO REPLACE 10 (TEN) DROP LIGHT LAMP HOLERS AND REPLACE WITH CORD CONNECTOR IN WELDING SHOP, LAMP HOLDERS ARE SHORTING OUT.							

Arturo Nunez

33609					4/21/2008		37		\$0.00
Medium	Work In Progress				4/21/2008 3:43:30 PM				
Lara, Ralph		NEED TO HAVE DOOR KNOB IN ROOM #309, REPLACED IT IS GETTING STUCK AND STUDENTS ARE GETTING LOCKED IN CLASS ROOM							

Arturo Nunez

33869					4/30/2008		28		\$0.00
Medium	Work In Progress				4/30/2008 2:58:20 PM				
Lara, Ralph		NEED SIX (6) EA. LOCKS FOR CABINETS FOR ROOM #3. KEYED ALIKE. TO STORE EQUIPMENT.							

Arturo Nunez

5/28/2008 3:23:49 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

33986					5/4/2008	5/10/2008	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				5/4/2008 12:19:01 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

34073					5/5/2008		23		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/5/2008 3:52:26 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos We have 4 Emergency Lights broken (asp PM33098)
2 - Lobby Area and 2- Gym Area

Manuel Prospero

34077					5/5/2008		23		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/5/2008 4:05:06 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos We have 3 exit signs broken on gym area and 1 in Locker Room (asp PM33108)

Manuel Prospero

34209					5/9/2008		19		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/9/2008 3:19:45 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph NEED SOME ASSISTANCE FROM LOCK SMITH, CYLINDERS TO OUSIDE DOORS HAVE BEEN FILLED WITH SILICONE

Arturo Nunez

34230	Cafeteria (2005)	Custodial			5/12/2008		16		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/12/2008 11:00:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe LUPE TALKED TO MIKE ABOUT BUYING A FAN PALM/ AND HE TOLD ME TO SEND YOU A WORK ORDER TO PURCHASE IT THANKS.

Luis Murillo

34247					5/12/2008		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				5/12/2008 4:09:46 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel please clean around maintmorgan bldg. throw away what needs to go and bring back what is good to maint warehouse..

Michael Munoz

34353	Annex Building	Custodial			5/15/2008		13		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/15/2008 2:53:04 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph DOOR FROM GIRLS BATHROOM WILL NOT LOCK / AREA FROM DOOR IS BROKEN/ WHERE DEAD BOLT IS LOCATED ANNEX BUILDING THANK YOU.

Luis Murillo

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

34481					5/21/2008		0		\$0.00
Medium	Work In Progress				5/21/2008 9:28:45 AM	5/21/2008			
Nunez, Arturo		Hector Rodriguez (915) 603-0198 w/A & A Fire Systems backed up and knocked down sign by guard shack.							
Arturo Nunez									

34527					5/22/2008		6		\$0.00
Medium	Work In Progress	LOST KEYS			5/22/2008 10:35:36 AM				
Lara, Ralph		Mr. Harold Wagner lost the following keys; 64, 10, 4, 250, 60, 7 6 and the mailbox key what process do you suggest to replace needed cores and set up financial responsibility? (Rafa need cost)							
Ralph Gallegos									

34573					5/23/2008		5		\$0.00
Medium	Work In Progress				5/23/2008 2:41:29 PM				
Ambriz, Jose		5/23/08. WE NEED TO REPLACE A/C MASTER COOL 65 ON ROOM 13. IS ON VERY BAD CONDITIONS. THIS WORK ORDER IS FOR JOSE AMBRIZ.							
Manuel Prospero									

Count: 44 Work Orders Avg. Age of WO's 131 Total for Santa Teresa HS 0 \$0.00

Location: Santa Teresa MS

24427					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									

24428					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									

24429					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									

24430					7/1/2007	8/1/2007	332		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PMschedule details.							
Alfredo Holguin									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

24431					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24498					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details.

Alfredo Holguin

24501					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:16:29 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details.

Alfredo Holguin

25722	South Building	Classroom			8/10/2007		292		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	ROOM 35			8/10/2007 2:28:12 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Lozoya, Manny Need key for filing cabinet

Laura Parra

25723	South Building	Classroom			8/10/2007		292		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	36 B			8/10/2007 2:33:23 PM				
--------	------------------	------	--	--	----------------------	--	--	--	--

Lozoya, Manny Need key for filing cabinet

Laura Parra

25837					8/14/2007		288		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/14/2007 10:09:09 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose Please order for condensate pump replacement. 35 ea. little giant pumps cat#554200, vcc- 20u/s or 2ou/s, 35 ea. 1/2" 90 deg. ells. SlipxTHD, 35 ea. SPRTB-6 24x24 metal grilles, 35 ft 3/4"OD x 5/8" ID clear vinyl tube, box of 3 amp fuses, box of 1 amp fuses, box of orange electrical wire nuts, and box of insulated female and male solderless terminals.

Jaime Mijarez

25886	South Building	Classroom			8/15/2007		287		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	room 47			8/15/2007 11:06:16 AM				
--------	------------------	---------	--	--	-----------------------	--	--	--	--

Mijarez, Jaime Install a new pencil sharpener in room 47

Dana Hamel

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

26272					8/27/2007		275		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/27/2007 8:51:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		Storm drain in back of S.bldg has a section that is bent inward and sand is caving in through a hole. I showed Alfredo Holguin, please give the work order to Alfredo.				ROUTE TO LUPE ASP MIKE 8/30			
----------------------	--	--	--	--	--	-----------------------------	--	--	--

Jaime Mijarez

28417	North Building	Cafeteria			10/23/2007		218		\$0.00
-------	----------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/23/2007 12:28:57				
--------	------------------	--	--	--	---------------------	--	--	--	--

Mijarez, Jaime		Baseboard and walls in kitchen by sinks and dishwashing area need to be replaced. This is by order of the NM Environmental Department and the report and the repair must be completed in 60 days. According to ED this is not the first warning about the repairs in an inspection report				Assign to Jaime and Gerry will assist asp Mike 11/13/07 -mkv			
----------------	--	---	--	--	--	--	--	--	--

Dana Hamel

28722					10/31/2007		210		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/31/2007 9:24:59 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos		AS PER OUR CONVERSATION, PLEASE PROVIDE A 120 OUTLET FOR THE ENVIRONMENT DEPT.							
------------------	--	--	--	--	--	--	--	--	--

Michael Munoz

29454	North Building	Office			11/27/2007		183		\$0.00
-------	----------------	--------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/27/2007 1:54:25 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph		manny, i need for you to make a key for some kitchen cabnits in the north office as per ms parra. And also check a panic bar ,see mr rodriguez on this one . thank you.							
-------------	--	---	--	--	--	--	--	--	--

Ismael Rodriguez

30823	Gym (1997)	Parking Lot			1/22/2008		127		\$0.00
-------	------------	-------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/22/2008 9:03:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Repair the dripping faucet that continues to cause freezing ice and dangerous conditions							
-------------------	--	--	--	--	--	--	--	--	--

Dana Hamel

30838	North Building	Restroom (Girls)			1/22/2008		127		\$0.00
-------	----------------	------------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/22/2008 2:09:24 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph		Unisex restroom top floor north building need to have a key CYLINDER THAT ANY KEY WILL OPEN, currently any coin will do and we have found students ditching there.							
-------------	--	--	--	--	--	--	--	--	--

Dana Hamel

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

30843	South Building	Choral			1/22/2008		127		\$0.00
-------	----------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Choir			1/22/2008 2:48:03 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Lara, Ralph Need signs over both doors that say "Choir Room"

Laura Parra

30935	South Building				1/24/2008		125		\$0.00
-------	----------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/24/2008 3:22:30 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos We are going to need electrical outlets installed at Santa Teresa Middle South Bld IDF. We have currently extended electrical using 15' power strips, but need the outlets relocated closer to the cabinets contact Silver.

Cora Ramirez

31013					1/29/2008		120		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/29/2008 9:36:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David S.bldg water heater room. Need to replace water shut-off valves for irrigation and regulator.

Jaime Mijarez

31803	South Building				2/22/2008		96		\$0.00
-------	----------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/22/2008 3:20:24 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos Santa Teresa Middle South Bld IDF, We have currently extended electrical using 15' power strips, but need the outlets relocated closer to the cabinets.

Cora Ramirez

32247	North Building	Custodial			3/4/2008		85		\$0.00
-------	----------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/4/2008 9:05:20 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph as,per ms .casillas we need to change the door handles in the boys and girls restrooms in the cafeteria for safety reasons.also mr.lara i will be needing 3 L wrenches for the panic bars.thank you see mr rodriguez.

Ismael Rodriguez

32406	North Building	Gym			3/10/2008		79		\$0.00
-------	----------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 7:25:02 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos the lights in the front porch of the gym are not working.

Ismael Rodriguez

32407	North Building	Custodial			3/10/2008		79		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2008 7:30:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos also,the exterior lights in the front of the north lobby porch are also not working.

Ismael Rodriguez

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

32471	South Building				3/11/2008		78		\$0.00
-------	----------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2008 1:28:07 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
need to replace two exterior water faucets in order to irrigate the front campus trees there in bad shape.thank you.

Ismael Rodriguez

32587	Gym (1997)	Gym			3/14/2008		75		\$0.00
-------	------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/14/2008 1:48:26 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Estrada, Jesus
Gym floor bubble up due to water leak. need to repair gym floor.

Michael Munoz

32692					3/25/2008		64		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/25/2008 10:39:32 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Mijarez, Jaime
A section of the floor in front of the custodial closet has been lifting up and seems to be getting worst. I have tried to dry it up and to put it back in place but had no luck. Could you send somebody please? Request was sent thru e-mail on Thursday 1/10/2008 10:05 am. Mike Munoz requested work order. Thank you.

Asp Mike assign to Chuy.
4-2-08 - REROUTED TO JAIME MINJAREZ AS PER CHUY, HE HAS TALKED TO HIM.

Jaime Mijarez

32733	South Building	Office			3/26/2008		63		\$0.00
-------	----------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Assistant			3/26/2008 10:02:58 AM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Lara, Ralph
Laura Parra
Please place lock in refrigerator

32810					2/26/2008		31		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/28/2008 9:25:48 AM	3/28/2008			
--------	------------------	--	--	--	----------------------	-----------	--	--	--

Gonzales, Angel
Gooseneck Trailer lights were broken need to be replaced.

Manuel Barrientos

32936					4/3/2008		55		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/3/2008 9:11:38 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Mijarez, Jaime
Need 12 stage pieces from S.T.H.S, by April 28,08 for concert on May 1,08.

Jaime Mijarez

33229		Office			4/9/2008		49		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/9/2008 11:17:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
N.bldg principals office. Need to relocate the light switch so that the lights can be turned on as the principal enters her office.

Jaime Mijarez

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

33232	South Building	Restroom (Girls)			4/9/2008		49		\$0.00
-------	----------------	------------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/9/2008 11:52:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos I need help with a emergency light fixture. I installed a new ballast, but can't get it to turn on.

Jaime Mijarez

33331	North Building	Cafeteria			4/11/2008		47		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/11/2008 11:24:44 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando Kitchen walk-in refrigerator, Troubleshoot condensing unit. Contactor needs to be changed. Due to power outage.

Jaime Mijarez

33699	North Building	Stairway			4/24/2008		34		\$0.00
-------	----------------	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/24/2008 8:07:33 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe lupe, i was talking to mr.soria about putting some windscreen along the stairway going from northbuilding to gym ,this will keep the sand out of the stairway,so faculty and students have a better access .thank you.see mr. rodriguez.

Ismael Rodriguez

33855	Gym (1997)	Gym			4/30/2008		28		\$0.00
-------	------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/30/2008 1:46:00 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Manny, i need for you to change the gym cylinders on MAY -27-08.thank you.

Ismael Rodriguez

33873	South Building	Office			4/30/2008		28		\$0.00
-------	----------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Assistant			4/30/2008 3:08:48 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Lara, Ralph Ms. Casillas-Assistant Principal needs keys for filing cabinets and desk

Laura Parra

33944					5/2/2008		26		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/2/2008 8:56:15 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ronquillo, Ruben Studen broke a window in lower level S.bldg hallway. Window is double pane insulated.

Jaime Mijarez

33953		Cafeteria			5/2/2008		26		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/2/2008 3:32:52 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Moncayo, Fernando Need Freezer Outlet in the storage room

Paula Sanchez- SNP Manager 589-9836

Alma Terrell

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

33954		Cafeteria			5/2/2008		26		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/2/2008 3:33:54 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Moncayo, Fernando		Garbage disposal is still out of order							
-------------------	--	--	--	--	--	--	--	--	--

		Paula Sanchez - SNP Manager 589-9836							
--	--	--------------------------------------	--	--	--	--	--	--	--

Alma Terrell

33955		Cafeteria			5/2/2008		26		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/2/2008 3:35:14 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph		Replace wooden door with metal door (door is all busted)							
-------------	--	--	--	--	--	--	--	--	--

		Paula Sanchez - SNP Manager 589-9836							
--	--	--------------------------------------	--	--	--	--	--	--	--

Alma Terrell

33967					5/2/2008		26		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	LINE LOCATE			5/2/2008 4:15:11 PM				
--------	------------------	-------------	--	--	---------------------	--	--	--	--

Villalobos, David		Need to line locate for new landscape area. This needs to be done on May 22nd. The construction will start on Monday the 26th. (See Mike Munoz for more Direction).							
-------------------	--	---	--	--	--	--	--	--	--

Michael Munoz

33987					5/4/2008	5/10/2008	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				5/4/2008 12:19:02 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.							
----------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

34023					5/4/2008	5/12/2008	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				5/4/2008 12:19:14 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime		Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.							
----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

34032					5/4/2008	5/12/2008	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				5/4/2008 12:19:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
----------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

34086		Cafeteria			5/6/2008		22		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/6/2008 10:52:58 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		NEED ELECTRICAL OUTLETS FOR REACH-IN FREEZERS IN THE STORAGE ROOM.							
------------------	--	--	--	--	--	--	--	--	--

Alma Terrell

5/28/2008 3:23:50 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

34131		Cafeteria			5/8/2008		20		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/8/2008 8:31:10 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Moncayo, Fernando Weather Stripping to Door needs to be replaced

Paula Sanchez - SNP Manager 589-9836

Alma Terrell

34132		Cafeteria			5/8/2008		20		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/8/2008 8:34:31 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Moncayo, Fernando Kitchen needs to be repainted (new colors) Black on Doors and Gold on Walls and Ceiling (as per Principal's Request)

Paula Sanchez - 589-9836

Alma Terrell

34347	North Building	Portables			5/15/2008		13		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Portable 3B			5/15/2008 12:02:59 PM				
--------	------------------	-------------	--	--	-----------------------	--	--	--	--

Lara, Ralph Need lock on door to adjoining classroom

Laura Parra

34589	South Building	Office			5/23/2008		5		\$0.00
-------	----------------	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/23/2008 4:01:24 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Estrada, Jesus Requested by Yvonne Casillas assistant principal. Remove carpet south bldg office area, except Assistant Principals office, and is requesting tile.

Jaime Mijarez

Count: 49 Work Orders		Avg. Age of WO's 127				Total for Santa Teresa MS	0		\$0.00
------------------------------	--	-----------------------------	--	--	--	----------------------------------	----------	--	---------------

Location: Sunland Park ES

24416					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24417					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

24418					7/1/2007	8/1/2007	332		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/1/2007 12:15:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.

Alfredo Holguin

5/28/2008 3:23:50 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

24962					7/20/2007		313		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/20/2007 11:45:33 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Please help open two filing cabinets that were accidentally locked during the summer break.

Irene Trujillo

25127	Main Building				7/26/2007		307		\$0.00
-------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/26/2007 3:24:02 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel 2nd request - Tile in nurse's office is not level. Safety hazard concern, as student/staff may possibly trip and be injured. 8/2 - Route to M. Prospero. This issue was discussed w/him last year. Mike.

Irene Trujillo

25405					8/3/2007		299		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/3/2007 3:33:00 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny CLASSROOM 28 - PLEASE INSTALL A DOOR KNOB WITH A LOCK IN THE RESTROOM.

Irene Trujillo

25804					8/13/2007		289		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 3:24:36 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel PORTABLE D - NEED A SMALL BOARD SCREWED TO WALL. ALSO, NEED A BACKPACK RACK FIXED.

Irene Trujillo

25805					8/13/2007		289		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/13/2007 3:25:32 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel PORTABLE D - PLEASE INSTALL NEW PENCIL SHARPENER.

Irene Trujillo

25848					8/14/2007		288		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/14/2007 2:01:40 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel LIBRARY - NEED TO HAVE HOOKS PLACED INSIDE STORAGE ROOM FOR BOOK PUPPETS. ALSO NEED NAILS TO HANG CHARTS.

Irene Trujillo

25891					8/15/2007		287		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/15/2007 12:33:38 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel SET UP SCREEN IN THE COMPUTER LAB.

Irene Trujillo

26135					8/22/2007		280		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/22/2007 9:00:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel PLEASE INSTALL A MARKER BOARD ON THE WALL IN THE LIBRARY.

Irene Trujillo

5/28/2008 3:23:50 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

26232					8/24/2007		278		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/24/2007 1:20:27 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Prospero, Manuel		2ND REQUEST - PORTABLES NEED PAINTING.							
Irene Trujillo									

26236					8/24/2007		278		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/24/2007 1:31:54 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David		CLASSROOM 25 - WATER FLUSING (IT IS STUCK) IN COMMODE. WATER RUNS FOR 15-20 MINS. THEN STOPS.							
-------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

26344					8/28/2007		274		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/28/2007 8:31:05 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Holguin, Alfredo		Provide services and materials for installation of new controller to control existing lighting.				Joe V. picked up PO on 9/4-mkv			
------------------	--	---	--	--	--	--------------------------------	--	--	--

Alfredo Holguin

26843					9/10/2007		261		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/10/2007 2:14:29 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Prospero, Manuel		PLEASE ASSEMBLE KIDNEY TABLE AND PLACE IN ROOM 12 (MS. C. GARCIA.) THANKS							
------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

26874					9/11/2007		260		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/11/2007 10:10:09 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Villalobos, David		9/11/07. WE HAVE A WATER LEAK ON MECHANICAL ROOM.(IS A WATER VALVE). THIS WORK ORDER IS FOR DAVID VILLALOBOS.							
-------------------	--	---	--	--	--	--	--	--	--

Manuel Prospero

27507					9/27/2007		244		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/27/2007 12:32:18 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Villalobos, David		classroom #41 - Toilet needs to be repaired. Do not have enough pressure.							
-------------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

27508					9/27/2007		244		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/27/2007 12:37:37 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Prospero, Manuel		CLASSROOM #12 - BROKEN DESK - PLEASE FIX IT.							
------------------	--	--	--	--	--	--	--	--	--

Irene Trujillo

27509					9/27/2007		244		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/27/2007 12:42:38 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Prospero, Manuel		PLEASE INSTALL BULLETIN BOARDS. ONE IN ROOM 41 (T. PEREZ) AND THE OTHER IN THE COUNSELOR'S OFFICE.							
------------------	--	--	--	--	--	--	--	--	--

Irene Trujillo

5/28/2008 3:23:50 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

28178 10/16/2007 225 \$0.00

Medium Work In Progress 10/16/2007 10:01:32

Prospero, Manuel The ramps on portables need to be painted. Also, this is a reminder portables have not been painted (previously submitted request)

Irene Trujillo

28192 10/16/2007 225 \$0.00

Medium Work In Progress 10/16/2007 3:07:59 PM

Prospero, Manuel 2ND REQUEST TO HAVE THE PORTABLES PAINTED.

Irene Trujillo

28273 10/18/2007 223 \$0.00

Medium Work In Progress 10/18/2007 1:55:04 PM

Lara, Ralph CLASSROOM 25 - THE DOOR WHICH LEADS TO THE OUTSIDE NEEDS TO BE REPLACED.

Irene Trujillo

28542 10/25/2007 216 \$0.00

Medium Work In Progress 10/25/2007 1:24:32 PM

Villalobos, David CLASSROOM #24 - UNCLOG SINK

Irene Trujillo

28721 10/31/2007 210 \$0.00

Medium Work In Progress 10/31/2007 9:24:25 AM

Castillo, Carlos AS PER OUR CONVERSATION, PLEASE PROVIDE A 120 OUTLET FOR THE ENVIRONMENT DEPT.

Michael Munoz

29221 11/14/2007 196 \$0.00

Medium Work In Progress 11/14/2007 1:49:39 PM

Prospero, Manuel PLEASE HANG 10 FRAMED POSTERS THROUGHOUT THE SCHOOL BUILDING.

Irene Trujillo

30712 Main Building Athletic Field 1/16/2008 133 \$0.00

Medium Work In Progress 1/16/2008 4:17:40 PM

Ontiveros, Guadalupe Clean out drains at main entrance. Also cut weeds around back stop and playarea

Guadalupe Ontiveros

31830 2/25/2008 93 \$0.00

Medium Work In Progress 2/25/2008 1:29:12 PM

Ambriz, Jose WE NEED TO REPLACE THE RELIEF VALVE ON THE BOILER.

Joel Herrera

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

32349					3/6/2008		83		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/6/2008 1:00:50 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David		I NEED REPLACE MOPSINK FAUCET AT CUSTODIANS CLOSET							
-------------------	--	--	--	--	--	--	--	--	--

Joel Herrera

32904					4/2/2008		56		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/2/2008 8:12:41 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph		KEY #TJ1 FOR ROOM 19 - PLEASE CHECK THE (3) KEYS WE HAVE. THESE DO NOT OPEN THE DOOR WITH THE NEW DOOR KNOB.							
-------------	--	--	--	--	--	--	--	--	--

Irene Trujillo

32966					4/4/2008		54		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/4/2008 8:11:29 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph		WE NEED REPLACE KEYS FROM CLASS ROOMS #35 AND 38							
-------------	--	--	--	--	--	--	--	--	--

Joel Herrera

32969					4/4/2008		54		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/4/2008 9:28:57 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph		CLASSROOM #35 - PLEASE CHECK DOOR KNOB AND KEYS. THE KEY WILL OPEN THE DOOR BUT WILL NOT LOCK IT.							
-------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

33156					4/7/2008		51		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/7/2008 3:26:24 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph		PLEASE CHECK CLASSROOM KEY FOR ROOM #12 - HAVING A DIFFICULT TIME OPENING AND CLOSING THE DOOR. KEY GETS STUCK.							
-------------	--	---	--	--	--	--	--	--	--

Irene Trujillo

33157					4/7/2008		51		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/7/2008 3:27:15 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph		PLEASE CHECK KEY FOR THE SUPPLY ROOM. KEY IS GETTING STUCK AND WE HAVE TO FORCE IT TO UNLOCK THE DOOR.							
-------------	--	--	--	--	--	--	--	--	--

Irene Trujillo

33244		Classroom			4/9/2008		20	1	\$25.00
-------	--	-----------	--	--	----------	--	----	---	---------

Medium	Work In Progress				4/9/2008 1:49:14 PM	4/29/2008			
--------	------------------	--	--	--	---------------------	-----------	--	--	--

Estrada, Jesus		REMOVE CARPET IN THE PRINCIPAL'S OFFICE AND CONFERENCE ROOM; TO BE REPLACED WITH FLOOR TILE.				4/29/08 - AS PER CHUY, THIS CAN WAIT UNTIL FURTHER NOTICE 5/9/08 - REOPENED - REQUESTED QUOTE			
----------------	--	--	--	--	--	--	--	--	--

Irene Trujillo

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

33824					4/29/2008		29		\$0.00
Medium	Work In Progress				4/29/2008 3:47:44 PM				
Ontiveros, Guadalupe		WE NEED TO RE-MOVED MONKEY BARS AND DEAD TREES THANK YOU LUPE.....							

Joel Herrera

34049					5/5/2008		23		\$0.00
Medium	Work In Progress				5/5/2008 2:42:43 PM				
Lara, Ralph		MANNY AND RAFA I NEED TWO SIGNS FROM ADULTS REST ROOMS WOMANS AND MANS							

Joel Herrera

34448					5/20/2008		8		\$0.00
Medium	Work In Progress				5/20/2008 2:52:51 PM				
Estrada, Jesus		WE NEED TO REPLACE FLOOR TILE AT PORTABLE P-C THANK YOU MR. ESTRADA							

Joel Herrera

34526					5/22/2008		6		\$0.00
Medium	Work In Progress				5/22/2008 10:29:27 AM				
Lara, Ralph		PORT. F - PLEASE INSTALL WEATHER STRIPPING ON BOTH DOORS. DUST SEEPS THRU AND DAMAGES INSTRUMENTS.							

Irene Trujillo

34533					5/22/2008		6		\$0.00
Medium	Work In Progress				5/22/2008 1:43:31 PM				
Villalobos, David		BOYS REST ROOMS URINAL STILL CLAGGED THANK YOU DAVID....							

Joel Herrera

Count: 39 Work Orders			Avg. Age of WO's 190			Total for Sunland Park ES	1		\$25.00
------------------------------	--	--	-----------------------------	--	--	----------------------------------	----------	--	----------------

Location: Sunrise ES

30685		Classroom			1/16/2008		133		\$0.00
Medium	Work In Progress	p-8			1/16/2008 12:56:03 PM				
Lozoya, Manny		I need to have an extra key for portable 8 We will be having detention in this portable and our Coach will need access key# 1c88.							

Joanne Munoz

31156					2/1/2008		117		\$0.00
Medium	Work In Progress				2/1/2008 7:56:27 AM				
Jacquez, Ricardo		BACK FENCE LINE,REQUESTING WIND SCREEN ESTIMATE LENGTH OF APPROX. 250'. THANKS							

Paul Quinones

5/28/2008 3:23:50 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
31451					2/11/2008		107		\$0.00
Medium	Work In Progress				2/11/2008 7:40:59 AM				
Ronquillo, Ruben		ROOMS 201, 208, 209, 212, OFFICE (5 1/2 X 38 WIRE MESH ON DOOR) WINDOWS BROKEN DURING WEEKEND, DUE TO BREAK IN. NEED TO REPLACE AS SOON AS POSSIBLE. THANKS (CASE#200801467) OTHER ITEMS MISSING: 1 BAGGY W/4-5 MEMORY STICKS, 1 LEAP PAD, LABEL MAKER.							
Paul Quinones									
31962					2/27/2008		91		\$0.00
Medium	Work In Progress				2/27/2008 3:57:37 PM				
Sotelo, Enrique		NEED TO REPLACE BROKEN LAMP COVERS IN NURSES STATION, STAFFS REST RM. IN WING B, AND STAFFS REST RM. IN WING C. AS WELL. THANKS							
Paul Quinones									
32117					3/2/2008	3/10/2008	87		\$0.00
Medium	Work In Progress				3/2/2008 12:33:09 AM				
Quinones, Paul		Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
32778	Main Building	Portables			3/27/2008		62		\$0.00
Medium	Work In Progress	P-6 AND P-5			3/27/2008 1:49:42 PM				
Quinones, Paul		Need wheels on portable cabinets to be replaced or fixed one in each portable.							
Joanne Munoz									
32881					4/1/2008		57		\$0.00
Medium	Work In Progress				4/1/2008 3:08:51 PM				
Ontiveros, Guadalupe		REQUESTING AERATE BACK GRASS FIELD							
Paul Quinones									
33380	Main Building	Cafeteria			4/13/2008		45		\$0.00
Medium	Work In Progress	CAFETERIA			4/13/2008 6:47:06 PM				
Orozco, Danny		TORN WATER HOSE IN UTILITY ROOM							
Joanne Munoz									
33776					4/28/2008		30		\$0.00
Medium	Work In Progress				4/28/2008 2:47:31 PM				
Holguin, Alfredo		Run Electrical power to the new marquee							
Alfredo Holguin									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
33972					5/4/2008	5/10/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:18:57 AM				
Quinones, Paul		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
34026					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:15 AM				
Quinones, Paul		Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
34034					5/4/2008	5/12/2008	24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:18 AM				
Quinones, Paul		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
34038					5/4/2008		24		\$0.00
Medium	Work In Progress				5/4/2008 12:19:19 AM				
Jacquez, Ricardo		Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.							
Margret Villalobos									
34188					5/9/2008		19		\$0.00
Medium	Work In Progress				5/9/2008 9:47:29 AM				
Ronquillo, Ruben		ATTN: RUBEN RON. BROKEN PLAY GROUND EQUIPMENT AS PER RUBEN REQUEST W/O IS NEEDED FOR P/O #.							
Paul Quinones									
34413	Main Building	Football Field			5/19/2008		9		\$0.00
Medium	Work In Progress				5/19/2008 9:53:25 AM				
Carbajal, Jimmy		need to order four 55 gallon outside trash cans.							
Jesus Urquidi									
34530	Main Building	Athletic Field			5/22/2008		6		\$0.00
Medium	Work In Progress	basketball courts			5/22/2008 1:08:05 PM				
Ontiveros, Guadalupe		Need line up spots and circle on Basketball courts. See Coach Roger for further details.							
Joanne Munoz									
Count: 16 Work Orders			Avg. Age of WO's	54	Total for Sunrise ES			0	\$0.00

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Vado ES

27650					9/30/2007	10/21/2007	241		\$0.00
-------	--	--	--	--	-----------	------------	-----	--	--------

Medium	Work In Progress				9/30/2007 12:17:45 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

29332					11/19/2007		191		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/19/2007 9:17:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique need light covers for lights in restroom 100-wing

Danny Miranda

30436					1/9/2008		140		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				1/9/2008 3:02:16 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny need to repair teachers restroom door knob door can't be opened from inside teachers are locking themselves inside

Danny Miranda

30943					1/24/2008		125		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/24/2008 3:54:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Margret Asp Jose Ambriz the need to replace board on BCU. Unable to communicate w/site. (Please advise when someone will be coming out so we can send one of our Technicians) Thanks.

Jose Ambriz

30956					1/25/2008		124		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/25/2008 1:06:11 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique A-Wing - no power to several several classrooms.

Enrique Sotelo

31310	Main Building	Classroom			2/5/2008		113		\$0.00
-------	---------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				2/5/2008 1:02:35 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Miranda, Danny RAISE HANDICAP BAR IN SPECIAL NEEDS ROOM 101

Debra Facio

31592					2/14/2008		104		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/14/2008 10:08:00 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny NEED TO REPLACE DOOR KNOB IN CUSTODIAL RM. 100-WING HANDLE WILL NOT STAY ON

Danny Miranda

31745					2/21/2008		97		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/21/2008 12:23:59 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique need to put in two lights in r.r. in rm. 103

Danny Miranda

5/28/2008 3:23:50 PM

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Vado ES							
31746					2/21/2008		97		\$0.00
Medium	Work In Progress				2/21/2008 12:25:04 PM				
Miranda, Danny		need to put in curtin divider in r.r. to rm. 103							
Danny Miranda									
33069					4/6/2008	4/27/2008	52		\$0.00
Medium	Work In Progress				4/6/2008 12:18:24 AM				
Orozco, Danny		Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
33215					4/9/2008		49		\$0.00
Medium	Work In Progress				4/9/2008 8:01:59 AM				
Lozoya, Manny		NEED TO CK. DEAD BOLT IN RM. 305							
Danny Miranda									
33217	Main Building	Hallway/Corridor			4/9/2008		49		\$0.00
Medium	Work In Progress				4/9/2008 8:16:48 AM				
Ronquillo, Ruben		NEED BLINDS FOR TWO WINDOWS IN PARENT EMASSADOR ROOM-JOHANNA MORA 74X20 NEED SIX TOTAL, (74X32) NEED TWO TOTAL							
Debra Facio									
33393					4/14/2008		44		\$0.00
Medium	Work In Progress				4/14/2008 2:08:56 PM				
Ronquillo, Ruben		NEED BALLAST FOR EMERGENCY LAMPS							
Danny Miranda									
34227					5/12/2008		16		\$0.00
Medium	Work In Progress				5/12/2008 9:23:47 AM				
Gonzales, Angel		need bobcat for grounds back of school, and to remove sand around campus							
Danny Miranda									
34344	Main Building	Dressing Room			5/15/2008		13		\$0.00
Medium	Work In Progress				5/15/2008 10:24:37 AM				
Carbajal, Jimmy		NEED TO REPLACE EXTENSION PLUG ON BUFFER ASAP THANK YOU .							
Armando Diaz									
34393					5/16/2008		12		\$0.00
Medium	Work In Progress				5/16/2008 1:17:10 PM				
Solis, Lorenzo		NEED THREE MOTORS FOR COMM. & ELEC. RM'S							
Danny Miranda									

981 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Vado ES							
34528					5/22/2008		6		\$0.00
Medium	Work In Progress				5/22/2008 10:36:32 AM				
Lozoya, Manny		NEED TO RETIME AND ADJUST ALL DEAD BOLTS BETWEEN CLASSROOMS							
Danny Miranda									
34614					5/27/2008		1		\$0.00
Medium	Work In Progress				5/27/2008 2:52:36 PM				
Ontiveros, Guadalupe		NEED FILL DIRT TO REDO WHAT WIND HAS BLOWN AWAY							
Danny Miranda									
Count: 18 Work Orders		Avg. Age of WO's		82	Total for Vado ES			0	\$0.00
Count: 981 Work Orders		Avg. Age of WO's		116	Grand Total			1	\$25.00