

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
35584					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:31 AM					
Orozco, Danny		Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
35695					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:06 AM					
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
35986	Chapter I	Office			7/16/2008		48		\$0.00
Medium	Work In Progress			7/16/2008 9:38:50 AM					
Lozoya, Manny		chapter blg repair pannic bar a.s.a.p							
<u>Hector Villalobos</u>									
36176	Cafeteria	Cafeteria			7/24/2008		40		\$0.00
Medium	Work In Progress			7/24/2008 11:26:39 AM					
Ontiveros, Guadalupe		remove old tree next to cafeteria,health issue as per ms.marquez							
<u>David Vega</u>									
36223	Chapter I				7/25/2008		39		\$0.00
Medium	Work In Progress			7/25/2008 1:32:17 PM					
Carbajal, Jimmy		Storage room in Chapter 1 building will be cleaned out by custodial crew at Anthony Elem. Take broken furniture that does not fit in site dumpsters to other site dumpsters. This will take place on 7/29/08 at 10:00 am. (Assign to Jimmy Carbajal)							
<u>Jesus Estrada</u>									
36228	Drug Free Bldg.				7/25/2008		39		\$0.00
Medium	Work In Progress			7/25/2008 2:12:37 PM					
Appelzoller, Fred		please remove sink, commode etc for remodeling of 1 restroom and when remodeling is complete start on the other. thxs							
<u>Michael Munoz</u>									
36229	Drug Free Bldg.				7/25/2008		39		\$0.00
Medium	Work In Progress			7/25/2008 2:15:04 PM					
Miranda, Danny		all plumbing will be removed in 1 restroom. please repair floor as needed and walls, once 1st r/r is completed please start on the next one please see mike. thxs							
<u>Michael Munoz</u>									
36311	Chapter I	Office			7/29/2008		35		\$0.00
Medium	Work In Progress			7/29/2008 8:10:42 AM					
Estrada, Jesus		chapter blg o.t.p. room carpet need to be replace .glue on carpet from vandalism				QUOTE REQUESTED PER CHUY 8/1/08			
<u>Hector Villalobos</u>									
9/2/2008 11:25:20 AM									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
36497					8/3/2008	8/9/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:11 AM					
Villalobos, Hector		Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
36517					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:19 AM					
Villalobos, Hector		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
36519					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:19 AM					
Villalobos, Hector		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
36641	Drug Free Bldg.				8/5/2008		28		\$0.00
Medium	Work In Progress			8/5/2008 10:48:59 AM					
Sotelo, Enrique		please install a power strip for radios. please see irene for location.thxs							
<u>Michael Munoz</u>									
36671	Main Building	Classroom			8/6/2008		27		\$0.00
Medium	Work In Progress			8/6/2008 8:43:57 AM					
Lozoya, Manny		room 14 lock will not open							
<u>Hector Villalobos</u>									
36672					8/6/2008		27		\$0.00
Medium	Work In Progress			8/6/2008 8:48:17 AM					
Lozoya, Manny		Primary blg storage need to charge lock							
<u>Hector Villalobos</u>									
36679	Annex Building	Classroom			8/6/2008		27		\$0.00
Medium	Work In Progress			8/6/2008 11:11:09 AM					
Estrada, Jesus		remove or install new carpet, carpet is tearing up as per teacher, potable 218							
<u>David Vega</u>									
36849					8/10/2008	8/26/2008	23		\$0.00
Medium	Work In Progress			8/10/2008 12:19:42 AM					
Villalobos, Hector		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
36867	Chapter I				8/11/2008		22		\$0.00
Medium	Work In Progress			8/11/2008 7:36:10 AM					
Sotelo, Enrique		Out side of chapter need to order new light fixture							
<u>Hector Villalobos</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
36933					8/12/2008		21		\$0.00
Medium	Work In Progress	Anthony Pre-K		8/12/2008 8:14:23 AM					
Ontiveros, Guadalupe New playground equip installed in the pre-k (village). Asp Donnie recommendation need 30 tons of masonry sand (wash sand). Also need 10 tons of sand for existing playground equipment.									
Nancy Bellagamba									
37078	Cafeteria				8/14/2008		19		\$0.00
Medium	Work In Progress			8/14/2008 2:47:20 PM					
Villalobos, Hector old cafeteria replace a/c pumps complete on 7/16/08									
Hector Villalobos									
37105	Chapter I	Office			8/15/2008		18		\$0.00
Medium	Work In Progress			8/15/2008 8:46:10 AM					
Lozoya, Manny chapter blg o.t.p room needs 4 keys k50									
Hector Villalobos									
37112					8/15/2008		18		\$0.00
Medium	Work In Progress			8/15/2008 11:23:07 AM					
Estrada, Jesus NEED TO REPLACE CARPET IN "SECURITY - DRUG FREE BARRACK.									
Michael Munoz									
37170	Nurse Building				8/19/2008		14		\$0.00
Medium	Work In Progress			8/19/2008 7:36:40 AM					
Lozoya, Manny need to replace exit door									
Hector Villalobos									
37171		Classroom			8/19/2008		14		\$0.00
Medium	Work In Progress			8/19/2008 7:41:19 AM					
Solis, Lorenzo room 310 , 307,306 expend duct vent longer inside rooms									
Hector Villalobos									
37287	Cafeteria	Cafeteria			8/21/2008		12		\$0.00
Medium	Work In Progress			8/21/2008 11:49:08 AM					
Orozco, Danny SEAL TO WALK-IN REFRIGERATOR IS ALL TORN AND MOLDY, SEAL NEEDS TO BE REPLACED									
BECKY SAENZ - 882-3507 (K-3 CAFETERIA)									
Alma Terrell									
37450	Original Main	Classroom			8/27/2008		6		\$0.00
Medium	Work In Progress	201		8/27/2008 12:39:44 PM					
Lozoya, Manny Need an additional key.....									
Loraine Gandara									
37451	Original Main	Classroom			8/27/2008		6		\$0.00
Medium	Work In Progress	201		8/27/2008 12:40:05 PM					
Lozoya, Manny Need an additional key.....									
Loraine Gandara									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
37452	Original Main	Classroom			8/27/2008		6		\$0.00
Medium	Work In Progress	202		8/27/2008 12:41:04 PM					
Lozoya, Manny		Need an additional key.....							
Loraine Gandara									
37455	Chapter I	Classroom			8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 2:24:38 PM					
Lozoya, Manny		chapter blg deadbolt cylinder fall apart music room							
Hector Villalobos									
37456	Nurse Building				8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 2:28:35 PM					
Appelzoller, Fred		Need part to fix leaking tub shower faucet . need to close main valve							
Hector Villalobos									
37516	Original Main	Classroom			8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 7:42:33 AM					
Carrasco, Danny		room 112 broken widows 12x 18 two							
Hector Villalobos									
37521	Cafeteria	Cafeteria			8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 8:39:59 AM					
Gonzalez, Salvador		(ANTHONY ELEMENTARY K-1 - OLD CAFETERIA) TWO EXIT DOORS NEED TO HAVE WIDER RAMPS. COMPLAINT OF FALLING CARTS WITH FOOD. PLEASE HELP. TERRY PORTILLO - SNP MANAGER 885-3507							
Alma Terrell									
37525	Annex Building	Classroom			8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 10:42:03 AM					
Villalobos, Hector		Damage to a/c vent in room 206. (Case# 08-08052) D. Allen #133							
David Vega									
37583					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:24 AM					
Villalobos, Hector		Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
37584					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:25 AM					
Villalobos, Hector		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Anthony ES							
37585					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:25 AM				
Villalobos, Hector	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
Count: 35 Work Orders		Avg. Age of WO's	22			Total for Anthony ES	0	0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
35557					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:23 AM					
Duran, Adan	Monthly - Berino ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
35579					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:29 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
35585					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:31 AM					
Orozco, Danny	Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
35696					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:06 AM					
Villalobos, David	Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35767					7/7/2008		57		\$0.00
High	Work In Progress			7/8/2008 3:20:01 PM					
Duran, Adan	Tag graffiti all over campus. Dep. LGarcia 114 Case# 2008-06493								
Jimmy Cortez									
35892					7/13/2008	7/29/2008	51		\$0.00
Medium	Work In Progress			7/13/2008 12:18:01 AM					
Cortez, Jimmy	Monthly - QRTLY BLDG INSP REPORTS (BE) - Refer to PM schedule details.								
Jesus Estrada									
35915					7/13/2008	7/29/2008	51		\$0.00
Medium	Work In Progress			7/13/2008 12:18:09 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
35982	Main Building	Cafeteria			7/16/2008		5	3	\$80.00
Medium	Work In Progress			7/16/2008 6:53:46 AM	7/21/2008				
Carbajal, Jimmy	VACCUM NEEDS NEW CORD						REPAIRED (REPLACED REAR WHEEL AXLE ASSEM W/USED ONE) AND ALDO DID PM		
Jimmy Cortez									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
36296					7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 3:37:40 PM					
Lozoya, Manny	MR MANNY LOZOYA SIR IN PORTABLE 148 THE FILE CABINET GOT LOCK BY MASTAKE AND THEY DONT HAVE A KEY NEED TO REMOVE CYLINDER AND REPLACE WITH NEW ONE THAT HAS A KEY THANK YOU SIR AND GOD BLESS								
Adan Duran									
36376					7/30/2008		34		\$0.00
Medium	Work In Progress			7/30/2008 4:04:04 PM					
Appelzoller, Fred	MR FRED APPELZOLLER SIR WE HAVE A LEAKING FAUCTET THE SEATS ARE SHOT NEED TO REPLACE RM 144 PORTABLE ALSO ROOM 105 HAS A LEAK UNTER COMODE HELP ! THANK YOU SIR AND GOD BLESS								
Adan Duran									
36707					8/6/2008		27		\$0.00
Medium	Work In Progress			8/6/2008 3:31:30 PM					
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR WE HAVE ABOUT 8 GALVNIZE PIPES 21 FT LOG THAT NEED TO BE PICKED UP AND HAUL OFF TO PPD YARD ALSO BIG BLOCKS OF CONCRETE THANK YOU SIR AND GOD BLESS								
Adan Duran									
36843					8/8/2008		25		\$0.00
Medium	Work In Progress	Mobile Home		8/8/2008 3:52:16 PM					
Appelzoller, Fred	Solicit quote for utility hook-up.								
Michael Munoz									
36845					8/8/2008		25		\$0.00
Medium	Work In Progress	Mobile Home		8/8/2008 3:52:51 PM					
Sotelo, Enrique	Solicit quote for utility hook-up.								
Michael Munoz									
36850					8/10/2008	8/26/2008	23		\$0.00
Medium	Work In Progress			8/10/2008 12:19:42 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
36879					8/11/2008		22		\$0.00
Medium	Work In Progress			8/11/2008 9:01:25 AM					
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR PER MR VALTIERRA HE WOULD LIKE THE SCHOOL CLEAN TO MANNY WEEDS PONDING AREA NEEDS CLEAN IN FRONT AND BACK AROUND PORTABLES ALONE FENCE IN FRONT OUTSIDE AND IN SIDE THANK YOU SIR								
Adan Duran									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

37051					8/14/2008		19	\$0.00	
Medium	Work In Progress			8/14/2008 8:43:38 AM					
Sanchez, Raul	INSTALL RELIEF VALVE ON IRRIGATION WELL.								
Raul Sanchez									
37156					8/18/2008		15	\$0.00	
Medium	Work In Progress			8/18/2008 3:39:48 PM					
Sanchez, Raul	MR RAUL SANCHEZ SIR THE FILTER FOR THE IRRIGATION PUMP BLEW A HOLE LEAKING BAD NEED TO REPLACE THANK YOU SIR AND GOD BLESS								
Adan Duran									
37159					8/18/2008		15	\$0.00	
Medium	Work In Progress			8/18/2008 3:43:40 PM					
Solis, Lorenzo	MR LORENZO SOLIS SIR THE AC UNIT TEACHERS LOUNGE IS REAL BAD THE SQUIRREL CAGE IS BAD MAY LAST THE YEAR MAY NOT COME LOOK AT IT WHEN YOU CAN THANK YOU SIR AND GOD BLESS								
Adan Duran									
37206					8/19/2008		14	\$0.00	
Medium	Work In Progress			8/19/2008 3:24:48 PM					
Solis, Lorenzo	MR LORENZO SOLIS SIR THE SQUIRREL CAGE IS LOSE AC CAFETERIA NEEDS TO BE REPLACE ITS A 6500 8" PADS ITS IN BAD SHAPE THANK YOU SIR AND GOD BLESS								
Adan Duran									
37210					8/19/2008		14	\$0.00	
Medium	Work In Progress			8/19/2008 3:32:05 PM					
Solis, Lorenzo	MR LORENZO SOLIS SIR PORTABLE 139 HAS TWO AC WINDOW TYPE THE CLAM IS THAT ITS NOT COOLING ENOUGH IT USE TO BE MUSIC ROOM BUT ITS A CLASS ROOM NOW WOULD LIKE A BIGGER UNIT THANK YOU SIR AND GOD BLESS								
Adan Duran									
37370					8/25/2008		8	\$0.00	
Medium	Work In Progress			8/25/2008 3:29:44 PM					
Sanchez, Raul	MR RAUL SANCHEZ SIR THE IRRIGATION PUMP IS NOT WORKING STARTED UP ON WED WORKED GOOD TILL FRIDAY IT QUIT ABOUT 1100 OCLOCK BLEW A FUSE THANK YOU SIR AND GOD BLESS								
Adan Duran									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
37529					8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 12:49:08 PM					
Orozco, Danny	MR DANNY OROZCO SIR THE SMALL TARP NORTH PLAYGROUND WAS TORN BY VANDALS AND ARE CLAMING UP THROUGH THE HOLE TO THE TOP AND SOME ONE MAY FALL ITS NEEDS TO BE REMOVE WITH BOOM TRUCK ITS HIGH THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
37539					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:10 AM					
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37540					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:10 AM					
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37541					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:11 AM					
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37672					9/2/2008		0		\$0.00
Medium	Work In Progress			9/2/2008 8:37:37 AM					
Lozoya, Manny	Asp Mike, please issue Sebastian Diaz, keys for this site.								
<u>Michael Munoz</u>									
37674		Mechanical Room			9/2/2008		0		\$0.00
Medium	Work In Progress			9/2/2008 8:57:00 AM					
Solis, Lorenzo	Replacement of hydronic boiler system, Remove old Bryan boilers and install new Raypacks.								
<u>Lorenzo Solis</u>									
Count: 27 Work Orders		Avg. Age of WO's 25			Total for Berino ES			3	\$80.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
35517					7/2/2008		62		\$0.00
Medium	Work In Progress			7/2/2008 7:52:46 AM					
Villalobos, Margret	Chaparral Elementary: Need an exterminator for mice in Classrooms #312 (Sink area) and #302 in the main building.		7/1 - Faxed to Watson						
Johnny Acuna									
35541					7/6/2008	7/12/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:17 AM					
Vargas, Juan	Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
35558					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:23 AM					
Vargas, Juan	Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
35586					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:32 AM					
Orozco, Danny	Monthly - Chapparral ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
35607					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:38 AM					
Vargas, Juan	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35647					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:50 AM					
Vargas, Juan	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35650					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:51 AM					
Vargas, Juan	Yearly - Chaparral ES Emer. Light Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
35673					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:59 AM					
Vargas, Juan	Yearly - Chaparral ES Exit Sign Test: Annual - Refer to PM schedule details.								
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral ES								
35694					7/6/2008	8/6/2008	58		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:05 AM						
Villalobos, David		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
35916					7/13/2008	7/29/2008	51		\$0.00	
Medium	Work In Progress			7/13/2008 12:18:09 AM						
Vargas, Juan		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos										
35944		Classroom			7/14/2008		50		\$0.00	
Medium	Work In Progress	506		7/14/2008 10:05:07 AM						
Estrada, Jesus		carpet needs to be removed from this classroom and linoleum was going to be installed. Work order is for Jesus Estrada per Administrators and Mike Munoz request. Please call school if you have any questions speak to Ms. Beckford, Ms. Ballard, or Mr. Gardea				AS OF 7/14/08 - OH HOLD PER CHUY				
Jennifer Corral										
36011					7/17/2008		47		\$0.00	
Medium	Work In Progress			7/17/2008 7:43:13 AM						
Vargas, Juan		07-10-08 2-check school fecelines and play ground 6-paint and instaled big tv on library wall				7/10-8				
Juan Vargas										
36075		Office			7/18/2008		46		\$0.00	
Medium	Work In Progress	PRE-K		7/18/2008 4:55:16 PM						
Vargas, Juan		AS PER ANN STEINHOFF-THERE IS MOLD ON THE CEILING IN THE WORK ROOM AT THE PRE-K								
Mary Garcia										
36214		Classroom			7/25/2008		39		\$0.00	
Medium	Work In Progress			7/25/2008 10:15:35 AM						
Lozoya, Manny		need,to,check,all,doors,locks,keys,do,not,open,doors,locks.								
Daniel Ramirez										
36314					7/29/2008		35		\$0.00	
Medium	Work In Progress	Room#208-		7/29/2008 10:16:15 AM						
Lozoya, Manny		Please install new locks to file cabinet -social worker will leave a sticky on the file cabinet								
Lucia Almeraz										
36387					7/31/2008		33		\$0.00	
Medium	Work In Progress			7/31/2008 9:44:58 AM						
Ontiveros, Joe		water heater on new bldg. not work								
Juan Vargas										

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
36499					8/3/2008	8/9/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:12 AM					
Vargas, Juan	Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
36520					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:20 AM					
Vargas, Juan	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36560					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:32 AM					
Vargas, Juan	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36581					8/4/2008		29		\$0.00
Medium	Work In Progress			8/4/2008 8:49:37 AM					
Vargas, Juan	barracas 406-408-410-412-414-416-418 need change master cools now have 3800 is to small need replace for 4500		Routed 8/11 - Assign to JC asp our conversation he needs to give units a good PM, where installed last year. Humidity is @ 70 and m/c swamps do not work well. m.munoz						
Juan Vargas									
36582					8/4/2008		29		\$0.00
Medium	Work In Progress			8/4/2008 8:51:58 AM					
Vargas, Juan	cafeteria roof need fix leaks		Route back to JC asp Mike 8/4						
Juan Vargas									
36584					8/4/2008		29		\$0.00
Medium	Work In Progress			8/4/2008 8:54:36 AM					
Vargas, Juan	303 room need fix roof leak		Route back to JC asp Mike 8/4						
Juan Vargas									
36675		Office			8/6/2008		27		\$0.00
Medium	Work In Progress			8/6/2008 9:42:24 AM					
Lozoya, Manny	need,to,fix,door,lock,mrs,baderd,officef								
Daniel Ramirez									
36737		Office			8/7/2008		26		\$0.00
Medium	Work In Progress	front office		8/7/2008 7:51:44 AM					
Lozoya, Manny	secretary's door locks and can't open, need door to be able to lock only when used with the key stays locked and when there is a fire drill door needs to be closed but not locked and locks automatically. Administrative Intern's room also having trouble with lock door cannot open very hard custodians are having a difficult time opening. Please see front office								
Jennifer Corral									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
36738					8/7/2008		26		\$0.00
Medium	Work In Progress			8/7/2008 7:59:01 AM					
Lozoya, Manny		chuy y mando nesecitan que les cambies las llaves por que batallan para abrir las puertas							
Juan Vargas									
36764		Cafeteria			8/7/2008		26		\$0.00
Medium	Work In Progress			8/7/2008 10:43:19 AM					
Orozco, Danny		MILK COOLER IS OUT OF ORDER							
Alma Terrell		ESTHER CISNEROS - SNP MANAGER 824-0048							
36773					8/7/2008		26		\$0.00
Medium	Work In Progress			8/7/2008 1:07:27 PM					
Ontiveros, Joe		kitchen r.room need replace toilet is broke							
Juan Vargas									
36851					8/10/2008	8/26/2008	23		\$0.00
Medium	Work In Progress			8/10/2008 12:19:43 AM					
Vargas, Juan		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
36956		Office			8/12/2008		21		\$0.00
Medium	Work In Progress	Office		8/12/2008 2:24:27 PM					
Lozoya, Manny		Wasn't sure if this was the one or if it was door but door knobs in office are very hard to open and always close. They were looked at by Manny and said these were storage locks. Principal would like these replaced with right door knobs. The door closes as we walk out for a fire drill and doors lock Doors shouldn't be locking while a drill is in session, need new locks.							
Jennifer Corral									
37005		Classroom			8/13/2008		20		\$0.00
Medium	Work In Progress	whole school		8/13/2008 10:45:16 AM					
Lozoya, Manny		work order to redo keys for custodians, can't open the doors to the classrooms. As per Manny Request.							
Jennifer Corral									
37055	2001 Classroom				8/14/2008		19		\$0.00
Medium	Work In Progress			8/14/2008 10:11:15 AM					
Vargas, Juan		need to add large rocks or cobblestones in areas where roof gutters are causing erosion							
Alfredo Holguin									
37056					8/14/2008		19		\$0.00
Medium	Work In Progress			8/14/2008 10:14:39 AM					
Vargas, Juan		All sidewalks with more than 4" drop need to have fill dirt added - Call Mike or Alfredo when work is complete							
Alfredo Holguin									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
37057					8/14/2008		19		\$0.00
Medium	Work In Progress			8/14/2008 10:17:19 AM					
Vargas, Juan	Sand need to be leveled in fall areas of all plaground structures on site.								
Alfredo Holguin									
37135	West Central				8/18/2008		15		\$0.00
Medium	Work In Progress			8/18/2008 9:11:53 AM					
Vargas, Juan	new doors are being installed in the esat and west barrack. please order paint so you can paint doors. thxs								
Michael Munoz									
37222		Custodial			8/20/2008		13		\$0.00
Medium	Work In Progress	master		8/20/2008 9:40:22 AM					
Lozoya, Manny	need another key to be done for substitute custodian. One of the keys did not open the doors. Please see Danny head custodian for more explanation								
Jennifer Corral									
37226		Classroom			8/20/2008		13		\$0.00
Medium	Work In Progress	103		8/20/2008 1:04:04 PM					
Sotelo, Enrique	need electrical setup to plug in computers and maybe move some to another location in the room. See Ms. Aguayo/Gary or Portillo								
Jennifer Corral									
37357		Classroom			8/25/2008		8		\$0.00
Medium	Work In Progress			8/25/2008 12:22:31 PM					
	need,to,borrow,big,dolley,to,move,fire,proof,cabinets.								
Daniel Ramirez									
37392		Custodial			8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 9:26:19 AM					
Carbajal, Jimmy	need,to,fix,vaccum,wheels,broken.								
Daniel Ramirez									
37393		Custodial			8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 9:28:36 AM					
Carbajal, Jimmy	need,to,fix,vaccum,makes,to,much,loud,noise.								
Daniel Ramirez									
37607					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:32 AM					
Vargas, Juan	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
37608					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:32 AM					
Vargas, Juan	Monthly - Chaparral ES A-1 Semiannual EVD - Refer to PM schedule details.								
Margret Villalobos									
37609					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:33 AM					
Vargas, Juan	Monthly - Chaparral ES C-6 Quarterly HP - Refer to PM schedule details.								
Margret Villalobos									
37610					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:33 AM					
Vargas, Juan	Monthly - Chaparral ES A-8 Quarterly HPW Unit - Refer to PM schedule details.								
Margret Villalobos									
37611					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:33 AM					
Vargas, Juan	Monthly - Chaparral ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
Margret Villalobos									
37612					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:34 AM					
Vargas, Juan	Monthly - Chaparral ES A-1 Semiannual MCD - Refer to PM schedule details.								
Margret Villalobos									
37613					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:34 AM					
Vargas, Juan	Monthly - Chaparral ES A-5 Quarterly SS - Refer to PM schedule details.								
Margret Villalobos									
37614					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:34 AM					
Vargas, Juan	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
37615					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:34 AM					
Vargas, Juan	Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Chaparral ES							
37616					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:35 AM				
Vargas, Juan	Monthly - Chaparral ES A-1 Semiannual EVS - Refer to PM schedule details.								
Margret Villalobos									
37654					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:47 AM				
Jacquez, Ricardo	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									
Count: 50 Work Orders			Avg. Age of WO's	27		Total for Chaparral ES	0	0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
35714					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:12 AM					
Villalobos, David	Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35869					7/11/2008		53		\$0.00
Medium	Work In Progress			7/11/2008 9:39:33 AM					
Lozoya, Manny	RE-KEY LEFT UPPER AND LOWER CABINETS FOR STORAGE LOCATED BEHIND THE RECEPTIONST FOR THE REGISTRAR (HEMPHILL)								
Rosa Quezada									
35870		Office			7/11/2008		53		\$0.00
Medium	Work In Progress	FRONT OFFICE		7/11/2008 9:41:05 AM					
Lozoya, Manny	RE-KEY RIGHT UPPER AND LOWER CABINETS FOR STORAGE LOCATED BEHIND THE RECEPTIONIST (GARCIA)								
Rosa Quezada									
35970					7/15/2008		49		\$0.00
Medium	Work In Progress	Mobile Home		7/15/2008 2:56:29 PM					
Ontiveros, Joe	SEPTIC AND WATER SYSTEMS NEED TO BE TIED IN FOR AN ON SITE MOBILE HOME.								
Eddie Baeza									
36093		Classroom			7/21/2008		43		\$0.00
Medium	Work In Progress	D-7		7/21/2008 3:47:12 PM					
Lozoya, Manny	NEED 1G032 SPARE KEY FOR FLAMABLE CABINET IN D-7(QUEZADA)								
Rosa Quezada									
36565					8/3/2008		30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:34 AM					
Baeza, Eddie	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36566					8/3/2008		30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:34 AM					
Baeza, Eddie	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
36567					8/3/2008		30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:35 AM					
Baeza, Eddie	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
36569					8/3/2008	9/3/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:35 AM					
Baeza, Eddie		Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
36579		Classroom			8/4/2008		29		\$0.00
Medium	Work In Progress	F Wing - Rm. 5		8/4/2008 8:18:45 AM					
Lozoya, Manny		Need a CH73 key for classroom F-5. (Paul H. Geiger)							
<u>Guadalupe Gonzalez</u>									
36593		Classroom			8/4/2008		29		\$0.00
Medium	Work In Progress	R Wing - Rm. 1		8/4/2008 1:55:06 PM					
Lozoya, Manny		Due to high security requirements, the control room door key must be cored the same as the storage room door. It is to be "off master" like the storage room.							
<u>Guadalupe Gonzalez</u>									
36606	B-Wing	Classroom			8/4/2008		29		\$0.00
Medium	Work In Progress	Rm B-3		8/4/2008 3:13:25 PM					
Lozoya, Manny		Need keys D274AR & D273AR. (Emmanuel Okefor)							
<u>Guadalupe Gonzalez</u>									
36768					8/7/2008		26		\$0.00
Medium	Work In Progress			8/7/2008 12:14:33 PM					
Villalobos, Margret		AN EXTERMINATOR IS REQUESTED TO SPRAY FOR BUGS AT Q @ R WINGS.				Faxed for Quote.			
<u>Eddie Baeza</u>									
36888					8/11/2008		22		\$0.00
Medium	Work In Progress			8/11/2008 1:32:00 PM					
Ontiveros, Joe		FAUCETS IN D-WING SCIENCE LABS NEED REPAIR AND REPLACEMENT.							
<u>Eddie Baeza</u>									
36959	A-Wing	Office			8/12/2008		21		\$0.00
Medium	Work In Progress			8/12/2008 3:11:57 PM					
Lozoya, Manny		Need to re-key mailroom to fit GM3 key.							
<u>Guadalupe Gonzalez</u>									
37134		Library			8/18/2008		15		\$0.00
Medium	Work In Progress			8/18/2008 9:05:08 AM					
Sotelo, Enrique		Run electricity from Production Room to Library side for flat screen TV. Need to put in outlet. Check wall for support. Install 52" flat screen.							
<u>Guadalupe Gonzalez</u>									
37177					8/19/2008		14		\$0.00
Medium	Work In Progress	Concession		8/19/2008 7:55:32 AM					
Lozoya, Manny		Need key to concession stand. (Mr. Sanchez)							
<u>Guadalupe Gonzalez</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
37220					8/20/2008		13		\$0.00
Medium	Work In Progress			8/20/2008 8:34:48 AM					
Lozoya, Manny		Need a CH73 key for classroom for F Wing - Rm. 5. (Paul H. Geiger)							
Guadalupe Gonzalez									
37394		Classroom			8/26/2008		7		\$0.00
Medium	Work In Progress	Nurse		8/26/2008 11:42:37 AM					
Lozoya, Manny		Need keys CH6 for Nurse's office and CH5 for the storage room in the Health Center. (Ana Castro)							
Guadalupe Gonzalez									
37432					8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 8:12:23 AM					
Gonzalez, Salvador		WELD GOOSENECK TO FOOTBALL GOAL POST.							
Guadalupe Ontiveros									
37435		Gym			8/27/2008		6		\$0.00
Medium	Work In Progress	P.E. Storage Rm.		8/27/2008 8:53:56 AM					
Lozoya, Manny		Need two GM1 keys for the P.E. storage room in the gym. (Rosa Quezada)							
Guadalupe Gonzalez									
37526					8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 12:31:07 PM					
Carrasco, Danny		20 70 WATT METAL HALIDE BULBS ARE REQUESTED. MEDIUM BASE.							
Eddie Baeza									
37527					8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 12:32:25 PM					
Ontiveros, Joe		A CLOSET AUGER IS REQUESTED TO UNPLUG CAMODES AT TEACHERS LOUNGE AND BOYS REST RM. G-WING.							
Eddie Baeza									
37528					8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 12:34:48 PM					
Sotelo, Enrique		THERE ARE 7 EXTERIOR POLE LIGHTS OUT AT PARKING LOTS							
Eddie Baeza									
37560					8/31/2008	9/21/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:17 AM					
Orozco, Danny		Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
37561					8/31/2008	9/21/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:17 AM					
Orozco, Danny	Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37569					8/31/2008	10/1/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:20 AM					
Baeza, Eddie	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37570					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:20 AM					
Baeza, Eddie	Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37571					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:20 AM					
Baeza, Eddie	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37572					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:21 AM					
Baeza, Eddie	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37573					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:21 AM					
Baeza, Eddie	Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37671		Cafeteria			9/2/2008		0		\$0.00
Medium	Work In Progress			9/2/2008 8:18:16 AM					
Orozco, Danny	Sprayer was replaced (dishwashing area)								
	Juana Montelongo - SNP Manager 824-4461								
<u>Alma Terrell</u>									
Count: 32 Work Orders		Avg. Age of WO's 19			Total for Chaparral HS			0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
35580					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:30 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
35587					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:32 AM					
Orozco, Danny	Monthly - Chapparal MS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
35697					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:06 AM					
Villalobos, David	Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35893					7/13/2008	7/29/2008	51		\$0.00
Medium	Work In Progress			7/13/2008 12:18:02 AM					
Gonzalez, Robert	Monthly - QRTLY BLDG INSP REPORTS (CE) - Refer to PM schedule details.								
Jesus Estrada									
36115		Cafeteria			7/22/2008		42		\$0.00
Medium	Work In Progress			7/22/2008 12:04:07 PM					
Orozco, Danny	Oven only warms up, (NO High Heat)								
Sandra Diaz SNP Mgr 824-4376									
Jacqueline Aguilar									
36145	Main Building	Classroom			7/23/2008		41		\$0.00
Medium	Work In Progress	Room 207		7/23/2008 11:09:15 AM					
Lozoya, Manny	**URGENT** THIRD REQUEST FOR NEW KEY FOR ROOM 207 OLD KEY BENT AND BROKE								
Elena Palacios									
36315					7/29/2008		35		\$0.00
High	Work In Progress			7/29/2008 10:57:48 AM					
Lozoya, Manny	***URGENT*** NEED KEY LOCKS THAT WERE LOST AND ORDERED ACCORDING TO RAFA AND MANNY BACK IN SEPTEMBER OF 07, LOCKS AND KEYS STILL HAVE NOT BEEN REPLACED IN THEIR ENTIRETY								
Elena Palacios									
36316		Computer Lab			7/29/2008		35		\$0.00
High	Work In Progress	ROOM 207		7/29/2008 11:01:56 AM					
Lozoya, Manny	NEED NEW KEY MADE FOR ROOM 207								
Elena Palacios									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
36767	Main Building	Classroom			8/7/2008		26		\$0.00
Medium	Work In Progress	ROOM 201		8/7/2008 12:10:58 PM					
Lozoya, Manny		NEEDS KEYS TO LOCK CABINETS							
Elena Palacios									
37050					8/14/2008		19		\$0.00
Medium	Work In Progress			8/14/2008 8:28:32 AM					
Ontiveros, Joe		need to replace shower columns in boys and girls reast rooms. Thxs							
Marti Muela									
37052		Athletic Field			8/14/2008		19		\$0.00
Medium	Work In Progress			8/14/2008 9:37:16 AM					
Ontiveros, Guadalupe		Purchase and Install new baseball backstop							
Richard Chavez									
37190					8/19/2008		14		\$0.00
Medium	Work In Progress			8/19/2008 10:46:23 AM					
Sotelo, Enrique		all exit outside building lights are not working. also two of the light pole lights, one in the pond area and one on the front fence.							
Robert Gonzalez									
37191					8/19/2008		14		\$0.00
Medium	Work In Progress			8/19/2008 10:54:48 AM					
Lozoya, Manny		eight security window rod irons can not be locked in the 300 & 400 hallway. very easy to break into. those rooms are to the back and can not be seen from the street.							
Robert Gonzalez									
37404	Main Building	Classroom			8/26/2008		7		\$0.00
Medium	Work In Progress	ROOM 406		8/26/2008 3:43:07 PM					
Lozoya, Manny		NEED CABINET LOCKS							
Elena Palacios									
37520	Main Building	Cafeteria			8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 8:15:59 AM					
Medina, Eric		Replace stained ceiling tiles							
Alfredo Holguin									
37574					8/31/2008	10/1/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:21 AM					
Medina, Eric		Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
37575					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:22 AM					
Medina, Eric		Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									

9/2/2008 11:25:21 AM

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Chaparral MS							
37576					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:22 AM				
Medina, Eric	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
37577					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:22 AM				
Medina, Eric	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
Count: 19 Work Orders		Avg. Age of WO's		26	Total for Chaparral MS			0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Pride

35559					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:19:23 AM				
Acosta, David		Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
35577					7/6/2008	7/12/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:19:29 AM				
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
35839	Storage A	Mechanical Room			7/10/2008		54		\$0.00
Medium	Work In Progress				7/10/2008 12:44:57 PM				
Castillo, Carlos		NEED TO MOVE RECEPTACLES LOWER OR INSTALL NEW ONE TO STORAGE ROOM TO PUMP HOUSE (WILL BE USING AS CUSTODIAL OFFICE)							
David Acosta									
35840	Storage A	Pump House			7/10/2008		54		\$0.00
Medium	Work In Progress	STORAGE			7/10/2008 12:50:41 PM				
Ambriz, Jose		NEED HEATING & COOLING FOR STORAGE ROOM. WILL BE USING AS CUSTODIAL OFFICE.							
David Acosta									
36010					7/17/2008		47		\$0.00
Medium	Work In Progress	MORGAN			7/17/2008 7:41:48 AM				
Ambriz, Jose		NEED HEATING & COOLING FOR MORGAN BLDG.							
David Acosta									
36027					7/17/2008		47		\$0.00
Medium	Work In Progress	MORGAN BLDG.			7/17/2008 11:08:09 AM				
Castillo, Carlos		NEED POWER TO RUN HEATING/COOLING & OUTLETS IN MORGAN BLDG.							
David Acosta									
36338		Portables			7/30/2008		34		\$0.00
Medium	Work In Progress	LAST			7/30/2008 6:52:59 AM				
Ontiveros, Guadalupe		NEED TO ADD MORE CRUSHERFINE TO EDGE OF NEW SIDEWALK.							
David Acosta									
36356		Classroom			7/30/2008		34		\$0.00
Medium	Work In Progress	11			7/30/2008 12:37:03 PM				
Castillo, Carlos		ONE LIGHT FIXTURE OUT NEED TO REPLACE BALLAST.							
David Acosta									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
36450		Parking Lot			8/1/2008		32		\$0.00
Medium	Work In Progress			8/1/2008 6:46:37 AM					
Ontiveros, Guadalupe	NEED HELP WITH LARGE ROCKS & CONCRETE PIECES BY MARQUEE SIGN. NEED TO BE HAUL AWAY.								
<u>David Acosta</u>									
36451		Classroom			8/1/2008		32		\$0.00
Medium	Work In Progress	14,15		8/1/2008 7:22:52 AM					
Castillo, Carlos	EMER. LIGHT DO NOT TURN ON IN BOTH ROOMS WHEN TURNING OFF BREAKER SWITCH FOR TESTING.								
<u>David Acosta</u>									
36452		Library			8/1/2008		32		\$0.00
Medium	Work In Progress			8/1/2008 7:26:27 AM					
Castillo, Carlos	EMER LIGHT WON'T STAY ON VERY LONG WHEN DOING ANNUAL TEST.								
<u>David Acosta</u>									
36515					8/3/2008	8/9/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:18 AM					
Acosta, David	Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36525					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:21 AM					
Acosta, David	Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36529					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:23 AM					
Acosta, David	Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36894					8/11/2008		22		\$0.00
Medium	Work In Progress			8/11/2008 2:51:43 PM					
Munoz, Michael	Purchase and install a Morgan Storage for the Avance program.								
<u>Richard Chavez</u>									
37554					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:15 AM					
Acosta, David	Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Desert Pride							
37555					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:15 AM				
Acosta, David	Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
37556					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:16 AM				
Acosta, David	Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 18 Work Orders			Avg. Age of WO's	33		Total for Desert Pride	0	0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
35560					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:23 AM					
Acuna, Johnny	Monthly - Desert Trail Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35581					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:30 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35588					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:32 AM					
Orozco, Danny	Monthly - Desert Trail Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35698					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:07 AM					
Villalobos, David	Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35728					7/7/2008		57		\$0.00
Medium	Work In Progress			7/7/2008 9:25:36 AM					
Lozoya, Manny	Please change core to doorknob in maintenance office to A-32.								
<u>Johnny Acuna</u>									
35816					7/10/2008		54		\$0.00
Medium	Work In Progress			7/10/2008 7:55:15 AM					
Ronquillo, Ruben	Need an awning installed outdoors on top of the back door to the library. When it rains, water comes through the door wetting the new carpet.								
<u>Johnny Acuna</u>									
35917					7/13/2008	7/29/2008	51		\$0.00
Medium	Work In Progress			7/13/2008 12:18:09 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36381					7/30/2008		34		\$0.00
Medium	Work In Progress			7/30/2008 9:32:01 PM					
Ontiveros, Guadalupe	Springkler system is down on the westside, it has been uncovered for a couple of weeks. Please advise as to covering the system or will it be fixed before August 1, 2008. School starts on the 4th.								
<u>Ruben Ortiz</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
36462		Cafeteria			8/1/2008		32		\$0.00
Medium	Work In Progress			8/1/2008 11:10:43 AM					
Orozco, Danny	Garbage Disposal is Still Out of Order								
	Pat Cisneros - SNP Manager 824-3822								
Alma Terrell									
36473					8/1/2008		32		\$0.00
Medium	Work In Progress			8/1/2008 12:38:15 PM					
Ontiveros, Joe	Need to replace broken handicap comode in the Nurse's office Restroom.								
Johnny Acuna									
36501					8/3/2008	8/9/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:12 AM					
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
36523					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:21 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36528					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:22 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36612					8/4/2008		29		\$0.00
Medium	Work In Progress			8/4/2008 3:41:11 PM					
Lozoya, Manny	Room #109. North Door Slips when trying to open.								
Johnny Acuna									
36625					8/4/2008		29		\$0.00
Medium	Work In Progress			8/4/2008 4:14:22 PM					
Jacquez, Ricardo	Replace lift station sewage pump.								
Ricardo Jacquez									
36656					8/6/2008		0		\$0.00
Medium	Work In Progress			8/6/2008 7:39:00 AM	8/6/2008				
Villalobos, Margret	Need to spray for ants inside and out of Portable Classrooms.		Faxed for Price Quote						
Johnny Acuna									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
36822					8/8/2008		25		\$0.00
Medium	Work In Progress				8/8/2008 9:41:58 AM				
Lozoya, Manny		Need 3 key cores to be installed in the new mulliums for the doors.							
Johnny Acuna									
36823					8/8/2008		25		\$0.00
Medium	Work In Progress				8/8/2008 9:43:14 AM				
Lozoya, Manny		Need a lock installed in the new filing cabinet to room #398. Mr. Varela.							
Johnny Acuna									
36852					8/10/2008	8/26/2008	23		\$0.00
Medium	Work In Progress				8/10/2008 12:19:43 AM				
Acuna, Johnny		Monthly - Desert Trail Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
36887					8/11/2008		22		\$0.00
Medium	Work In Progress	110			8/11/2008 11:51:39 AM				
Lozoya, Manny		Marisela front office receptionist needs replacement of lost key for room #110 (J66) and also need one extra (J2) key.							
Elizabeth Hernandez									
36895					8/11/2008		22		\$0.00
Medium	Work In Progress				8/11/2008 2:53:14 PM				
Ontiveros, Guadalupe		Baseball backstop- Install a new one or renistall the one moved the CHS.							
Richard Chavez									
37007	Main Building	Classroom			8/13/2008		20		\$0.00
Medium	Work In Progress				8/13/2008 11:46:28 AM				
Lozoya, Manny		Room 109 no se puede habrir. ---- J master esta doblada--- room 403 necesita llave---- banos 411 necesitan cambiar chapas---- puertas principales se atora la llave- GRACIAS							
Marisela Torres									
37034					8/13/2008		20		\$0.00
Medium	Work In Progress				8/13/2008 3:46:59 PM				
Lozoya, Manny		Portable #408 Mr. West is having trouble unlocking door knob key cylinder. Please send me some Graffite.							
Johnny Acuna									
37193	Main Building	Restroom (Boys)			8/19/2008		14		\$0.00
Medium	Work In Progress				8/19/2008 11:20:15 AM				
Ontiveros, Joe		Need to fix urinal . don't stop running at 4 grade wing.							
Marisela Torres									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
37197					8/19/2008		14		\$0.00
Medium	Work In Progress			8/19/2008 2:56:15 PM					
Acuna, Johnny	.5-check lift station 7.5-Transport Bobcat tractor to Chaparral High and Help Eddie cut weeds around the back of the main building.		8/19 - 8						
Johnny Acuna									
37281	Main Building	Classroom			8/21/2008		12		\$0.00
Medium	Work In Progress			8/21/2008 9:34:34 AM					
Lozoya, Manny	Room # 409 la puerta tiene una parte quebrada y no se puede cerrar. Gracias.								
Marisela Torres									
37286	Main Building	Office			8/21/2008		12		\$0.00
Medium	Work In Progress			8/21/2008 11:32:48 AM					
Lozoya, Manny	Escritorio de enfermeria necesita candado de seguridad. Gracias.								
Marisela Torres									
37523					8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 9:16:56 AM					
Ontiveros, Joe	(Johnny Acuña-Desert Trail Elem.) Need 2 replacement gooseneck sink faucets. Cold Only. to classrooms # Kinder wing.								
Eddie Baeza									
37586					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:25 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
37587					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:25 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
37588					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:26 AM					
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
Count: 31 Work Orders		Avg. Age of WO's	28	Total for Desert Trail Intermediate			0	\$0.00	

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
35589					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:33 AM					
Orozco, Danny	Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35613					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:40 AM					
Aguilar, Patricio	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35617					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:41 AM					
Aguilar, Patricio	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35699					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:07 AM					
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35898					7/13/2008	7/29/2008	51		\$0.00
Medium	Work In Progress			7/13/2008 12:18:03 AM					
Rivera, Hector	Monthly - QRTLY BLDG INSP REPORT (DV) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
35961		Cafeteria			7/15/2008		49		\$0.00
Medium	Work In Progress			7/15/2008 7:33:37 AM					
Moncayo, Fernando	MILK COOLER IS NOT WORKING AT ALL.								
	DIANA LAZARIN SNP MGR 589-2425								
<u>Jacqueline Aguilar</u>									
36006	Main Building				7/16/2008		48		\$0.00
Medium	Work In Progress			7/16/2008 3:40:41 PM					
Villalobos, Margret	Ant problem at Desert View classrooms and hallways.		Faxed for price quote.						
<u>Jesus Estrada</u>									
36098					7/21/2008		43		\$0.00
Medium	Work In Progress			7/21/2008 3:58:36 PM					
Ontiveros, Guadalupe	REPAIR WATER LEAK IN IRRIGATION LINE.								
<u>Guadalupe Ontiveros</u>									
36198					7/25/2008		39		\$0.00
Medium	Work In Progress			7/25/2008 7:12:16 AM					
Ontiveros, Guadalupe	Perimeter Fence - clear trash and sand build up along fenceline.								
<u>Alfredo Holguin</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Desert View ES									
36382					7/30/2008		34		\$0.00
Medium	Work In Progress			7/30/2008 9:39:07 PM					
Ontiveros, Guadalupe	Revised correction it's at Desert View not Desert Trail Intermediate; Sprinkler system is down on the westside, it has been uncovered for a couple of weeks. Please advise as to covering the system or will it be fixed before August 1, 2008. School starts on the 4th.								
Ruben Ortiz									
36674					8/6/2008		27		\$0.00
Medium	Work In Progress	Mobile Home		8/6/2008 9:34:01 AM					
Castillo, Carlos	Back of school bldg 1 light on post is out. A large part of the bldg is in the dark, grafitti may occur (see attached).								
Miquel Aguilar									
36727					8/6/2008		27		\$0.00
Medium	Work In Progress			8/6/2008 5:25:58 PM					
Lara, Ralph	I would like to get new keys, having trouble with the ones I have they are to worn out. I need keys for alarm, lights need key for alarm system before Saturday August 9th.								
Ruben Ortiz									
36762	Main Building				8/7/2008		26		\$0.00
High	Work In Progress			8/7/2008 10:29:45 AM					
Lara, Ralph	Need a key made for the locks on the chains.								
Jesus Estrada									
36883					8/11/2008		22		\$0.00
Medium	Work In Progress	Hallways		8/11/2008 10:24:06 AM					
Castillo, Carlos	2 Emergency Lights not working in Middle and East Hallway asp PM 36530.								
Ruben Ortiz									
36939	Main Building				8/12/2008		21		\$0.00
Medium	Work In Progress			8/12/2008 8:37:50 AM					
Castillo, Carlos	Tested exit signs (4) are not working 2 in Gym and Cafeteria asp PM 36526.								
Ruben Ortiz									
36988					8/12/2008		21		\$0.00
Medium	Work In Progress			8/12/2008 4:20:26 PM					
Castillo, Carlos	Repair the security light on post located in the southwest corner of the building.								
Alfredo Holguin									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert View ES

37045 8/13/2008 20 \$0.00

Medium Work In Progress 8/13/2008 8:46:58 PM

Ontiveros, Guadalupe

08/13/08

To: Lupe Ontiveros

I am requesting to have the arroyo run off filled in and weeds scrapped. If possible with the tractors that are on the south schools area. Before the tractors are taken out.

Ruben Ortiz

37166 8/18/2008 15 \$0.00

Medium Work In Progress 8/18/2008 5:24:18 PM

Ortiz, Ruben

08/18/08

Called Danny Carrasco from warehouse for parts on the motor for the master cooler in room 32. Danny sent me a new motor and brace. Jose Ambriz took off a bracket from an old master cooler and brought to me to fix the master cooler in room 32. Both responded promptly. Thank you.

Ruben Ortiz

37479 Cafeteria 8/28/2008 5 \$0.00

Medium Work In Progress 8/28/2008 8:31:04 AM

Moncayo, Fernando

Since she is the first one to arrive - every morning the cafeteria smells like gas - has to turn on the air conditioner to take the smell away.

Diana Lazarin - SNP Manager 589-2425

Alma Terrell

37480 Cafeteria 8/28/2008 5 \$0.00

Medium Work In Progress 8/28/2008 8:32:32 AM

Moncayo, Fernando

It takes a couple of hours for the two bottom blodgett ovens to heat up.

Diana Lazarin - SNP Manager 589-2425

Alma Terrell

37481 Cafeteria 8/28/2008 5 \$0.00

Medium Work In Progress 8/28/2008 8:34:01 AM

Moncayo, Fernando

Reach-In Refrigerator was at 43 degrees this morning - it's at 39 degrees right now.

Diana Lazarin - SNP Manager 589-2425

Alma Terrell

37634 8/31/2008 2 \$0.00

Medium Work In Progress 8/31/2008 12:25:41 AM

Aguilar, Patricio

Monthly - Desert View ES A-2 Quarterly H/C IREH - Refer to PM schedule details.

Margret Villalobos

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
37635					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:41 AM					
Aguilar, Patricio	Monthly - Desert View ES A-1 Semiannual MCD - Refer to PM schedule details.								
Margret Villalobos									
37636					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:41 AM					
Aguilar, Patricio	Monthly - Desert View ES A-1 Semiannual MCS & MCS2 - Refer to PM schedule details.								
Margret Villalobos									
37637					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:42 AM					
Aguilar, Patricio	Monthly - Desert View ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos									
37638					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:42 AM					
Aguilar, Patricio	Monthly - Desert View ES A-6 Quarterly PUG - Refer to PM schedule details.								
Margret Villalobos									
37639					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:42 AM					
Aguilar, Patricio	Monthly - Desert View ES A-5 Quarterly SS - Refer to PM schedule details.								
Margret Villalobos									
37640					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:43 AM					
Aguilar, Patricio	Monthly - Desert View ES A-13 Quarterly WREH - Refer to PM schedule details.								
Margret Villalobos									
37641					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:43 AM					
Aguilar, Patricio	Monthly - Desert View ES A-13 Quarterly WREH - Refer to PM schedule details.								
Margret Villalobos									
37656					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:48 AM					
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Desert View ES							
37657					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:48 AM				
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
37658					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:49 AM				
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
Count: 32 Work Orders		Avg. Age of WO's 22		Total for Desert View ES				0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
35582					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:19:30 AM				
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
35603					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:19:37 AM				
Orozco, Danny		Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
35700					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:20:07 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
35729					7/7/2008		57		\$0.00
Medium	Work In Progress	C - WING			7/7/2008 9:56:07 AM				
Castillo, Carlos		ELECTRICAL OUTLET NEEDS TO BE MOVED OR ADDED TO ANOTHER OFFICE - WILL BE MOVING PRINTER THAT IS CURRENTLY IN KARLA QUESADA'S OFFICE (PLEASE SEE LULU ESPARZA FOR DETAILS) THANK YOU							
<u>Cora Ramirez</u>									
35802	RTC	Office			7/9/2008		55		\$0.00
Medium	Work In Progress	RTC ACROSS			7/9/2008 3:07:58 PM				
Ambriz, Jose		AS PER GLORIA SAENZ-NEED TO HAVE THE AIR CONDITIONER UNIT CHECKED. SETTINGS ARE NOT WORKING PROPERLY.							
<u>Mary Garcia</u>									
35983					7/16/2008		48		\$0.00
Medium	Work In Progress				7/16/2008 7:38:01 AM				
Ontiveros, Guadalupe		Pick up old mobile home hitches haul to metal recycling facility.							
<u>Alfredo Holguin</u>									
36049		Office			7/18/2008		46		\$0.00
Medium	Work In Progress	C-WING			7/18/2008 11:22:29 AM				
Ambriz, Juan		AS PER MS. STEINHOFF-NEED TO HAVE A FILING CABINET MOVED FROM DAVID AVILA'S OFFICE INTO MS. LUZ MARIA AVILA							
<u>Mary Garcia</u>									
36143		Office			7/23/2008		41		\$0.00
Medium	Work In Progress	Mr. Ituralde's			7/23/2008 9:03:25 AM				
Ambriz, Jose		Need to replace Mr. Ituralde's A/C unit compressor not working properly							
Juan Ambriz									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
36277		Office			7/28/2008		36		\$0.00
Medium	Work In Progress	STM-JUANA		7/28/2008 10:49:25 AM					
Castillo, Carlos	AS PER JUANA ESPINOZA-NEED SEVERAL ELECTRICAL OUTLETS IN THE PARENT CENTER, SOUTH BUILDING. (FOR COMPUTERS AND ETC.) PLEASE SEE ME BEFORE INSTALLING ANY OUTLETS.								
Mary Garcia									
36280					7/28/2008		36		\$0.00
Medium	Work In Progress	Back bottom road		7/28/2008 12:11:48 PM					
Ontiveros, Guadalupe	need to apply dirt and crusherfine in back road due to running water after haevy rain.								
Juan Ambriz									
36281		Hallway/Corridor			7/28/2008		36		\$0.00
Medium	Work In Progress	C-Wing A/C unit		7/28/2008 12:13:33 PM					
Ambriz, Jose	Need to raplace relays in C-Wing unit not working properly								
Juan Ambriz									
36322		Office			7/29/2008		35		\$0.00
Medium	Work In Progress	C-WING		7/29/2008 2:53:41 PM					
Castillo, Carlos	AS PER ANN S.-WHEN A FAX COMES IN OR SENDING A FAX THE LIGHTS FLICKER AND STAY FLICKERING FOR ABOUT 30 MINUTES IN THE OFFICE OF LUCY MESA AND DAVID AVILA.								
Mary Garcia									
36334		Parking Lot			7/29/2008		35		\$0.00
Medium	Work In Progress	bottom dirt		7/29/2008 3:47:57 PM					
Ontiveros, Guadalupe	Need to apply more crusherfine in bottom dirt parking lot accumulating water after rain								
Juan Ambriz									
36360					7/30/2008		34		\$0.00
Medium	Work In Progress			7/30/2008 3:14:05 PM					
Castillo, Carlos	Need to order new emergency lights for the server room not working total of two								
Juan Ambriz									
36379		Office			7/30/2008		34		\$0.00
Medium	Work In Progress	A-WING		7/30/2008 4:38:24 PM					
Estrada, Jesus	AS PER ANGIE SANCHEZ-WOULD LIKE TO HAVE HER OFFICE RETILED. FLOOR TILE IS REALLY WORN OUT.								
Mary Garcia									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
36947	Pre-K	Parking Lot			8/12/2008		21		\$0.00
Medium	Work In Progress	PRE-K		8/12/2008 10:33:17 AM					
Carrasco, Danny	AS PER MS. BERRY-WOULD LIKE TO HAVE A PORTABLE SIGN THAT SAYS "DROP OFF / PICK UP" ZONE. THEY ARE CURRENTLY USING 3 CONES & A SIGN THAT WAS MADE.								
Mary Garcia									
36949		Office			8/12/2008		21		\$0.00
Medium	Work In Progress	A-WING		8/12/2008 10:35:44 AM					
Ambriz, Juan	IF IT WOULD BE POSSIBLE TO HAVE THE AIR VENTS IN JESUS REYE'S OFFICE ADJUSTED. NOT ENOUGH AIR COMES THROUGH.								
Mary Garcia									
36962		Office			8/12/2008		21		\$0.00
Medium	Work In Progress	C-WING		8/12/2008 3:29:08 PM					
Ambriz, Juan	AS PER MS. AVILA-TO PLEASE HANG TWO PICTURES ON THE WALL BRHIND THE COMPUTER. PICTURES TO HANG SIDE BY SIDE ABOVE DESK AT EYE LEVEL. (PLEASE SEE MS. AVILA BEFORE HANGING)								
Mary Garcia									
37189		Office			8/19/2008		14		\$0.00
Medium	Work In Progress	B-WING		8/19/2008 10:23:04 AM					
Castillo, Carlos	AS PER ANNE- IN LUDYM'S OFFICE (NEW FINANCE DIRECTOR) ONE OF THE FLUORESCENT LIGHT FIXTURES DOES NOT HAVE A COVERING AND NEEDS ONE PLEASE.								
Mary Garcia									
37396		Office			8/26/2008		7		\$0.00
Medium	Work In Progress	C-WING		8/26/2008 2:55:56 PM					
Lara, Ralph	AS PER MS. RAIHL-REQUESTING FOR AN OFFICE DOOR WITH A WINDOW.								
Mary Garcia									
37504	Pre-K	Office			8/28/2008		5		\$0.00
Medium	Work In Progress	PER-K OFFICE		8/28/2008 4:07:30 PM					
Ambriz, Juan	AS PER ALICE-HAS A CHAIR THAT NEEDS 4 BOLTS. (NOTE: SHE DOES NOT HAVE BOLTS FOR THIS CHAIR, THEY WERE LOST)								
Mary Garcia									
37505	Pre-K	Hallway/Corridor			8/28/2008		5		\$0.00
Medium	Work In Progress	PER-K MAIN		8/28/2008 4:08:51 PM					
Lara, Ralph	AS PER ALICE-MAIN FRONT DOOR TO PRE-K DOES NOT CLOSE.								
Mary Garcia									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
37604					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:31 AM				
Ambriz, Juan		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
37605					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:31 AM				
Ambriz, Juan		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
37606					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:32 AM				
Ambriz, Juan		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
Count: 25 Work Orders		Avg. Age of WO's	31			Total for GAC	0	0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
35479	Football Stadium	Football Field			7/1/2008		63		\$0.00
Medium	Work In Progress				7/1/2008 8:20:32 AM				
Ontiveros, Guadalupe	The chain link fence by the guest bleachers need to be repaired at the football field.								
Mario Apodaca									
35522	Boys Gym	Gym			7/2/2008		62		\$0.00
Medium	Work In Progress				7/2/2008 8:46:13 AM				
Villalobos, Margret	NEED TO SPRAY ALL THE BOYS GYM FOR VEGETATION					E-mailed			
Mario Apodaca									
35590					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:19:33 AM				
Orozco, Danny	Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
35701					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:20:08 AM				
Villalobos, David	Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35757		Athletic Field			7/8/2008		56		\$0.00
Medium	Work In Progress				7/8/2008 11:04:03 AM				
Ontiveros, Guadalupe	Remove goal post and install at GMS.								
Terry Alvarado									
35873	Main Building	Office			7/11/2008		53		\$0.00
Medium	Work In Progress				7/11/2008 2:16:35 PM				
Lara, Ralph	NEW NAME PLATES (3) MR. CAREY L. CHAMBERS								
Mario Apodaca									
35876	Main Building	Office			7/11/2008		53		\$0.00
Medium	Work In Progress				7/11/2008 2:28:45 PM				
Carrasco, Danny	NEED NEW BLINDS FOR PRINCIPAL CHAMBERS OFFICE 1. 40" X 5' 2. 7' X 5'								
Mario Apodaca									
35877	Main Building	Office			7/11/2008		53		\$0.00
Medium	Work In Progress				7/11/2008 2:32:00 PM				
Ambriz, Jose	NEW WINDOW AC UNIT FOR PRINCIPAL CHAMBERS								
Mario Apodaca									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
35899					7/13/2008	7/29/2008	51		\$0.00
Medium	Work In Progress			7/13/2008 12:18:04 AM					
Munoz, Joe	Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
35993	Boys Gym	Office			7/16/2008		48		\$0.00
Medium	Work In Progress			7/16/2008 2:28:31 PM					
Ambriz, Jose	Requested by Coach Lawrence Rm. 401 Office in Boy's Gym-Room 401 does not have any air conditioning, would like to have a unit installed this summer of 2008, to review videos and to watch films for Soccer.								
<u>Velia Alarcon</u>									
35998	Business	Stairway			7/16/2008		48		\$0.00
Medium	Work In Progress			7/16/2008 3:14:33 PM					
Ontiveros, Guadalupe	The tree near the south entrance is very close to dead and should be removed								
<u>Albert Vallejo</u>									
35999	Varsity Gym				7/16/2008		48		\$0.00
Medium	Work In Progress			7/16/2008 3:16:52 PM					
Ambriz, Jose	Two water coolers need to be ordered to replace the existing ones that are beyond repair.								
<u>Albert Vallejo</u>									
36000	Library	Library			7/16/2008		48		\$0.00
Medium	Work In Progress			7/16/2008 3:18:40 PM					
Ontiveros, Guadalupe	An irrigation control box has a water leak underneath the asphalt outside the southwest exit.								
<u>Albert Vallejo</u>									
36066	North Building	Classroom			7/18/2008		46		\$0.00
Medium	Work In Progress			7/18/2008 3:19:18 PM					
Ronquillo, Ruben	NEED NEW WINDOW BLINDS (35"WX56"L) FOR ROOM 207 NEED 11 EA								
<u>Mario Apodaca</u>									
36067	Old English Bldg	Classroom			7/18/2008		46		\$0.00
Medium	Work In Progress			7/18/2008 3:21:06 PM					
Ambriz, Jose	NEED A NEW HEATING CONDESER AT ROOM 141 DO TO VANDALISM								
<u>Mario Apodaca</u>									
36157	Vocational				7/23/2008		41		\$0.00
Medium	Work In Progress			7/23/2008 3:12:06 PM					
Ontiveros, Guadalupe	Due to heavy rain, there is a large amount of vegetation growing between each of the individual buildings that needs to be removed.								
<u>Albert Vallejo</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
36186	Cafeteria (1998)	Cafeteria			7/24/2008		40		\$0.00
Medium	Work In Progress				7/24/2008 3:18:50 PM				
Moncayo, Fernando		WALK - IN FREEZER DOWN.							
Jacqueline Aguilar		GHS SNP 882-5522							
36204	Football Stadium	Athletic Field			7/25/2008		39		\$0.00
Medium	Work In Progress				7/25/2008 7:47:13 AM				
Castillo, Carlos		Need to check all electrical at football field ,press box,scoarboard,stadium lighting,etc.							
Carlos Castillo									
36231					7/25/2008		39		\$0.00
Medium	Work In Progress				7/25/2008 3:04:45 PM				
Ontiveros, Guadalupe		Requested by Coach Hite for Football Field-Football field is very uneven. Please level as it is very dangerous.							
Velia Alarcon									
36233					7/25/2008		39		\$0.00
Medium	Work In Progress				7/25/2008 3:06:46 PM				
Lozoya, Manny		Requested by Coach Hite for Varsity Locker Room-Remove handle and replace with metal plate, door should not open from outside.							
Velia Alarcon									
36260	Academic Bldg	Hallway/Corridor			7/28/2008		36		\$0.00
Medium	Work In Progress				7/28/2008 8:59:44 AM				
Munoz, Michael		ROOF ARE LEAKING AT THE ACADEMIC BLDG NEED A NEW ROOF							
Mario Apodaca									
36261	Boys Gym				7/28/2008		36		\$0.00
Medium	Work In Progress				7/28/2008 9:04:42 AM				
Munoz, Michael		ROOF ARE LEAKING AT THE BOYS GYM AT THE GYM ,ROOM 404,403 NEED A NEW ROOF							
Mario Apodaca									
36263	Business	Classroom			7/28/2008		36		\$0.00
Medium	Work In Progress				7/28/2008 9:10:25 AM				
Munoz, Michael		ROOF LEAKING AT THE BUSINESS BLDG ROOM 653,660 NEED A NEW ROOF							
Mario Apodaca									
36264	Cafeteria (1998)	Cafeteria			7/28/2008		36		\$0.00
Medium	Work In Progress				7/28/2008 9:16:45 AM				
Munoz, Michael		ROOF LEAKING AT THE CAFE BLDG NEED WORK							
Mario Apodaca									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
36265	Community				7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 9:21:07 AM					
Munoz, Michael	THE WEIGHT ROOM HAS SAME ROOF LEAKS NEED WORK								
Mario Apodaca									
36266	Computer	Computer Lab			7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 9:24:04 AM					
Munoz, Michael	ROOF LEAK AT THE COMP LAB NEED A NEW ROOF								
Mario Apodaca									
36267	Concession				7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 9:27:17 AM					
Munoz, Michael	THE TOW CONCESSION STAN LEAK NEED NEW ROOF								
Mario Apodaca									
36268	Library				7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 9:29:49 AM					
Munoz, Michael	NEED NEW ROOF AT THE LIBRARY DO TO ROOF LEAKS								
Mario Apodaca									
36269	Main Building	Office			7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 9:35:20 AM					
Munoz, Michael	NEED A NEW ROOF AT THE MAIN , OFFICE AND ROOM 104,105,100,HALLWAY								
Mario Apodaca									
36270	New Vocational	Classroom			7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 9:37:27 AM					
Munoz, Michael	THE ANNEX BLDG ROOMS LEAKING 506,505								
Mario Apodaca									
36271	North Building	Classroom			7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 9:44:48 AM					
Munoz, Michael	ALL BLDG NEED A NEW ROOF JOB AT THE N-BLDG ROOMS 222,223,224,221,220,228,229,216,231,232,223,204,237, ,236,245,243 AND HALLWAYS								
Mario Apodaca									
36272	Nursing Center				7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 9:47:30 AM					
Munoz, Michael	THE NURSE BLDG HAS ROOF LEAKS NEED WORK								
Mario Apodaca									
36273	Old English Bldg	Classroom			7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 9:52:10 AM					
Munoz, Michael	THE OLD ENG BLDG NEED A NEW ROOF THE GYM, 142,HALLWAY								
Mario Apodaca									

9/2/2008 11:25:22 AM

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
36274	Vocational				7/28/2008		36		\$0.00
Medium	Work In Progress				7/28/2008 9:56:02 AM				
Munoz, Michael	NEED A NEW ROOF AT THE WOOD SHOP BLDG AND AT THE AG SHOP BLDG SAME LEAK								
Mario Apodaca									
36284	Agricultural				7/28/2008		36		\$0.00
Medium	Work In Progress				7/28/2008 2:52:32 PM				
Appelzoller, Fred	NEED A NEW ELECTRIC WATER HEATER AT THE ART ROOM 568 BY AG BLDG								
Mario Apodaca									
36288	Vocational	Classroom			7/28/2008		36		\$0.00
Medium	Work In Progress	568			7/28/2008 3:08:02 PM				
Carrasco, Danny	Window frames in front of classroom are in bad repair and need to be completely replaced. Large amounts of water get through during rainstorms.								
Albert Vallejo									
36310	Cafeteria (1998)	Cafeteria			7/29/2008		35		\$0.00
Medium	Work In Progress				7/29/2008 8:10:33 AM				
Castillo, Carlos	NEED A SAFETY POWER DISCONNECT TO THE GHS WALK-IN'S (BOTH) ON THE CONDENSER UNITS ON THE ROOF								
MR. DEMETRIIOUS GIOVAS									
Jacqueline Aguilar									
36359		Cafeteria			7/30/2008		34		\$0.00
Medium	Work In Progress				7/30/2008 3:02:54 PM				
Moncayo, Fernando	need to ck the ice maker compressors at the cafe it is tipping the circuit breaker								
Mario Apodaca									
36386	Main Building	Classroom			7/31/2008		33		\$0.00
Medium	Work In Progress	127			7/31/2008 8:53:23 AM				
Lara, Ralph	The double doors on room 127 need to be replaced. When closed, they are hard to open due to swelling. When closed, they are hard to close because the hinges no longer take firm purchase on the door or jamb.								
Albert Vallejo									
36403	Academic Bldg				7/31/2008		33		\$0.00
Medium	Work In Progress				7/31/2008 1:52:38 PM				
Lara, Ralph	Requested by Ms. Leahy Rm. 328 Academic Building- Put a lock on the left-hand built-in cabinet.								
Velia Alarcon									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
36404	Boys Gym				7/31/2008		33		\$0.00
Medium	Work In Progress			7/31/2008 2:09:10 PM					
Vallejo, Albert	Requested by Coach Hite for J.V. Football Locker Room in Boy's Gym-Gray paint J.V. Football locker room floor around toilet/urinal area and sink area.								
<u>Velia Alarcon</u>									
36406					7/31/2008		33		\$0.00
Medium	Work In Progress			7/31/2008 2:22:56 PM					
Vallejo, Albert	Requested by Coach Hite for Panther Stadium Storage Area-Paint over graffiti on storage room under home stadium seats.								
<u>Velia Alarcon</u>									
36415					7/31/2008		33		\$0.00
Medium	Work In Progress			7/31/2008 2:44:16 PM					
Villalobos, Margret	Requested by Coach Hite for J.V. and Varsity Football Locker Rooms-Spray for insects.		Faxed for Price Quote						
<u>Velia Alarcon</u>									
36419					7/31/2008		33		\$0.00
Medium	Work In Progress			7/31/2008 2:47:06 PM					
Estrada, Jesus	Requested by Coach Hite for J.V. Football Locker Room -Replace wall molding under urinal in J.V. locker room. Level broken floor areas for installation of new floor tile.		8/20/08 - MICHAEL THE DRYWALL HAS BEEN REPAIRED , PLEASE GO AHEAD AND QUOTE.						
<u>Velia Alarcon</u>									
36423	Old English Bldg	Custodial			7/31/2008		33		\$0.00
Medium	Work In Progress			7/31/2008 2:51:55 PM					
Lara, Ralph	i need a doorknob with a lock installed its missing and custodial supplies get stolen								
<u>Joe Munoz</u>									
36444					7/31/2008		33		\$0.00
Medium	Work In Progress			7/31/2008 3:47:42 PM					
Lara, Ralph	Requested by Julio Alcantar SO1-A pad lock with an F3 cylinder is requested to secure the golf cart assigned to Security.								
<u>Velia Alarcon</u>									
36622					8/4/2008		29		\$0.00
Medium	Work In Progress	WWT		8/4/2008 4:10:54 PM					
Sanchez, Raul	Replace motor for Wastewater Treatment Plant Blowers.								
<u>Raul Sanchez</u>									
36740					8/7/2008		26		\$0.00
Medium	Work In Progress			8/7/2008 8:07:37 AM					
Lara, Ralph	David Martinez, broken key.								
<u>Mary Garcia</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
36774	Academic Bldg				8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 1:58:16 PM				
Lara, Ralph	Requested by Ms. Howard Rm. 307 Academic Building- A cylinder with two keys are needed for file cabinet in classroom. Cabinet has not cylinder.								
<u>Velia Alarcon</u>									
36775					8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 2:15:59 PM				
Lara, Ralph	Requested by Ms. Arredondo Rm. 552 Wood Shop- Bathroom door off it's hinges. Unusable, please fix as soon as possible.								
<u>Velia Alarcon</u>									
36776	Old English Bldg				8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 2:19:22 PM				
Lara, Ralph	Requested by Mr. Stemsrud Rm. 154 Old English Building-Need two keys made for file cabinet in classroom.								
<u>Velia Alarcon</u>									
36779	North Building				8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 2:39:56 PM				
Lara, Ralph	Requested by Ms. Roth Rm. 213 North Building-The interior handle of the north door is missing and the door won't lock, please repair.								
<u>Velia Alarcon</u>									
36780	Gym				8/7/2008		26	1	\$25.00
Medium	Work In Progress				8/7/2008 2:51:17 PM				
Ambriz, Jose	Requested by Ms. Letz Rm. 155 Girl's Gym Locker Room-Air conditioner in locker room is not working.		adj float						
<u>Velia Alarcon</u>									
36782					8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 2:57:07 PM				
Ontiveros, Guadalupe	Requested by Coach Hite-Please mow grass outside Coach Hite's Office. Mosquitoes are about to take Coach away. Cut weeds around the stadium. Clean out grass in planter around cactus sculpture on south west corner of Academic Building.								
<u>Velia Alarcon</u>									
36783	Academic Bldg				8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 2:58:49 PM				
Apodaca, Mario	Requested by Coach Hite-Paint Cactus Sculpture on south west corner of academic building.								
<u>Velia Alarcon</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
36787	Old English Bldg				8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 3:10:19 PM				
Lara, Ralph	Requested by Ms. Spivey Rm. 134 Old English Building- Lock seems to be striping, key doesn't work right.								
<u>Velia Alarcon</u>									
36801	North Building				8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 3:54:07 PM				
Lara, Ralph	Requested by Mr. Palmer Rm. 205 North Building- Teacher's keys do not open Teacher Lounge in North Building. Please repair as soon as possible.								
<u>Velia Alarcon</u>									
36802					8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 3:55:26 PM				
Lara, Ralph	Requested by Velia-The key HE89 does not open classroom, please repair and make one more for key box.								
<u>Velia Alarcon</u>									
36805					8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 4:00:15 PM				
Lara, Ralph	Requested by Velia-The key HE122 does not open classroom, please repair and make one more for key box.								
<u>Velia Alarcon</u>									
36807					8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 4:15:59 PM				
Lara, Ralph	Requested by Velia-Three A53 keys are needed for new Football Coaching Staff.								
<u>Velia Alarcon</u>									
36878	Boys Gym				8/11/2008		22		\$0.00
Medium	Work In Progress				8/11/2008 8:35:04 AM				
Marquez, Gerardo	new shower column was installed in girls dressing room. need to install tile to complete project.see mike. thxs								
<u>Michael Munoz</u>									
36896	Boys Gym	Gym			8/11/2008		22		\$0.00
Medium	Work In Progress				8/11/2008 2:55:29 PM				
Castillo, Carlos	NEED A NEW SWITCH FOR THE E/COOER UNIT AT THE BOYS GYM								
<u>Mario Apodaca</u>									
36897	Football Stadium	Athletic Field			8/11/2008		22		\$0.00
Medium	Work In Progress				8/11/2008 3:02:38 PM				
Castillo, Carlos Mario Apodaca	NEED TO CK ALL OF THE FOOTBALL FIELD LIGHT								

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
36913	Old English Bldg				8/11/2008		22		\$0.00
Medium	Work In Progress			8/11/2008 3:29:50 PM					
Lara, Ralph	Requested by Mr. Van Dam Rm. 153 Old English Building-Teacher is having problems with door knob, he's afraid he'll break the key. This door knob is an old round door knob and I (Velia) also placed a Work Order to have this door knob changed to a Best cylinder with three keys, a year ago.								
<u>Velia Alarcon</u>									
36924	Varsity Gym				8/11/2008		22		\$0.00
Medium	Work In Progress			8/11/2008 4:40:45 PM					
Vallejo, Albert	Requested by Coach S. Perez Rm. 239 Varsity Gym Boy's Basketball Locker Room-Ceiling tiles in varsity gym need to be replaced.								
<u>Velia Alarcon</u>									
36925	Old English Bldg				8/11/2008		22		\$0.00
Medium	Work In Progress			8/11/2008 4:42:18 PM					
Lara, Ralph	Requested by Ms. Goodman Rm. 129 Old English Building-Key not working, getting stuck, won't turn.								
<u>Velia Alarcon</u>									
36926					8/11/2008		22		\$0.00
Medium	Work In Progress			8/11/2008 4:43:46 PM					
Ambriz, Jose	Requested by Dolores Nanez Library-Girl's Restroom is extremely hot, it's a warehouse for germs.								
<u>Velia Alarcon</u>									
36999	Auto Shop	Classroom			8/13/2008		20		\$0.00
Medium	Work In Progress			8/13/2008 8:46:42 AM					
Ambriz, Jose	need to put new t-bar diffusers (24"x24") - 6ea at room 569								
<u>Mario Apodaca</u>									
37049	Football Stadium	Football Field			8/14/2008		19		\$0.00
Medium	Work In Progress			8/14/2008 8:14:03 AM					
Munoz, Michael	Some of the concrete piers that support the bleachers are cracked and need to be repaired.								
<u>Albert Vallejo</u>									
37084	Library	Restroom (Girls)			8/14/2008		19		\$0.00
Medium	Work In Progress			8/14/2008 2:57:29 PM					
Ambriz, Jose	The restrooms in the library east wall have no circulation. An extractor fan on the rooftop needs to be replaced.								
<u>Albert Vallejo</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
37094	Cafeteria (1998)	Cafeteria			8/14/2008		19		\$0.00
Medium	Work In Progress				8/14/2008 3:40:19 PM				
Ambriz, Jose	ALL OUTSIDE DUCTS OF THE CAFE BLDG NEED TO BE RESEAL DOTO SUN AND WATER DAMAGE. ASAP								
Mario Apodaca									
37099	Boys Gym	Gym			8/15/2008		18		\$0.00
Medium	Work In Progress				8/15/2008 7:44:21 AM				
Appelzoller, Fred	install collars to cover vents and water to showers in boys gym as per mike.								
Fred Appelzoller									
37143	New Vocational	Hallway/Corridor			8/18/2008		15		\$0.00
Medium	Work In Progress				8/18/2008 2:43:34 PM				
Ronquillo, Ruben	Need window glass replaced, Approximately 24" x 30" in size. (wired glass)								
Albert Vallejo									
37144	Computer	Electrical Room			8/18/2008		15		\$0.00
Medium	Work In Progress				8/18/2008 2:46:26 PM				
Castillo, Carlos	Contactor for computer outlets intermitently makes more noise than normal.								
Albert Vallejo									
37145					8/18/2008		15		\$0.00
Medium	Work In Progress				8/18/2008 2:48:35 PM				
Gonzalez, Salvador	The chain link fence directly south of the band room has been hit by a vehicle, one post is down and the mesh has been torn								
Albert Vallejo									
37231					8/20/2008		13		\$0.00
Medium	Work In Progress				8/20/2008 1:59:08 PM				
Gonzalez, Salvador	NEED TO WELD A NEW PADLOCK TOO THE S/GATE . ASAP.								
Mario Apodaca									
37232	Old English Bldg	Classroom			8/20/2008		13		\$0.00
Medium	Work In Progress				8/20/2008 2:03:04 PM				
Carrasco, Danny	NEED NEW WINDOW MINI BLINDS DOTO VANDALISM (W43 1/2"X L90") NEED #4								
Mario Apodaca									
37233	Academic Bldg				8/20/2008		13		\$0.00
Medium	Work In Progress				8/20/2008 2:15:18 PM				
Ambriz, Jose	AT THE ACADEMIC BLDG NEED NEW E/COOLER STANDS								
Mario Apodaca									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
37234	Cafeteria (1998)				8/20/2008		13		\$0.00
Medium	Work In Progress			8/20/2008 2:17:31 PM					
Ambriz, Jose	AT THE CAFE BLDG NEED NEW E/COOER STANDS								
Mario Apodaca									
37235	Cafeteria (1998)	Restroom (Boys)			8/20/2008		13		\$0.00
Medium	Work In Progress			8/20/2008 2:25:19 PM					
Lara, Ralph	NEED TO PUT A NEW DEADBOLTS ON THE TOW RESTROOMS DOORS .ASAP								
Mario Apodaca									
37284					8/21/2008		12		\$0.00
Medium	Work In Progress			8/21/2008 11:13:30 AM					
Ronquillo, Ruben	8 SIGNS (24 X 18) THAT READ THE FOLLOWING: GHS IS A DRUG FREE CAMPUS NO SMOKING NO ALCOHOL NO WEAPONS NO PETS								
Mario Apodaca									
37295	Agricultural	Classroom			8/21/2008		12		\$0.00
Medium	Work In Progress			8/21/2008 2:52:32 PM					
Appelzoller, Fred	need a new sink and faucet set put-in at room 569								
Mario Apodaca									
37297	Agricultural	Classroom			8/21/2008		12		\$0.00
Medium	Work In Progress			8/21/2008 2:54:06 PM					
Appelzoller, Fred	need a new water boiler put in at room 569								
Mario Apodaca									
37299					8/21/2008		12		\$0.00
Medium	Work In Progress			8/21/2008 2:59:39 PM					
Apodaca, Mario	8-20-08				8/20-8				
	6-painting a class room at the a.g bldg room 569 1-t/shoot a/c unit at the n-bldg too room 202 1-in put to school dude								
Mario Apodaca									
37306					8/21/2008		12		\$0.00
Medium	Work In Progress			8/21/2008 3:20:25 PM					
Vallejo, Albert	(8-21-08) 2 hrs - Troubleshoot and repair A/C unit on top of varsity gym; 2 hrs - Finish restroom wall and install urinal in boys gym; 3 hrs - repair partitions in boys restroom in cafeteria; 1 hr - Fire extinguisher inspections (work order #36494)				8/21-7				
Albert Vallejo									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
37339					8/22/2008		11		\$0.00
Medium	Work In Progress			8/22/2008 12:57:34 PM					
Gonzalez, Salvador		WELD GOOSENECK TO FOOTBAL GOAL POST.							
Guadalupe Ontiveros									
37360	Grounds Shop				8/25/2008		8		\$0.00
Medium	Work In Progress			8/25/2008 12:51:17 PM					
Castillo, Carlos		I need an electrician to disconnect power to burned-out motor at wwtp and assist me in installing a new blower motor. We may need a small crane to lift new motor up to wwtp platform. Thanks, Raul							
Raul Sanchez									
37388	Auto Shop				8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 8:18:28 AM					
Lara, Ralph		Lock on the southside door will not release the key in the locked position.							
Albert Vallejo									
37398					8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 3:27:40 PM					
Apodaca, Mario		Requested by Mrs. Smith Rm. 127 Main Building- Need the overhead screen placed above chalkboard.							
Velia Alarcon									
37400					8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 3:35:15 PM					
Castillo, Carlos		Requested by Mr. Roberson for Rm. 127 Main Building- Install on/off switch for lights in room #127. When room was divided switch was left in room #128.							
Velia Alarcon									
37401					8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 3:38:09 PM					
Castillo, Carlos		Requested by Dolores Nanez for Video Room in Library- One electric outlet in video room to plug fan, room gets too hot.							
Velia Alarcon									
37402					8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 3:40:08 PM					
Vallejo, Albert		Requested by Mr. Marquez Rm. 143 Old English Building- Install a screen for infocus machine, the screen is in the classroom.							
Velia Alarcon									
37411					8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 3:52:41 PM					
Orozco, Danny		bucket truck for wed, thurs, friday or asap for pa GHS and pa STHS (please call Carlos Vigil for information)							
Cora Ramirez									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

37421					8/26/2008		7		\$0.00
Medium	Work In Progress				8/26/2008 4:18:55 PM				
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Remove frame from North Batting Cage and deliver to Softball Field.								
	See Coach Bones and Coach Lopez before beginning work.								
Velia Alarcon									
37423					8/26/2008		7		\$0.00
Medium	Work In Progress				8/26/2008 4:21:08 PM				
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Take nets off of north batting cage and place them on the south east batting cage.								
	See Coach Bones before beginning work.								
Velia Alarcon									
37426					8/26/2008		7		\$0.00
Medium	Work In Progress				8/26/2008 4:28:51 PM				
Lara, Ralph	Requested by Mrs. Smith Rm. 127 Main Building-Can not lock or unlock door from the inside. This is a hazard during fire drills such as freezes or lock downs. This is an old door handle that should be replaced.								
Velia Alarcon									
37431					8/27/2008		6		\$0.00
Medium	Work In Progress				8/27/2008 8:10:43 AM				
Gonzalez, Salvador	NEED TO CONSTRUCT SHADE AT GROUNDS DEPT. TO PROTECT IMPLEMENT.								
Guadalupe Ontiveros									
37441					8/27/2008		6		\$0.00
Medium	Work In Progress				8/27/2008 10:45:18 AM				
Vallejo, Albert	Requested by Mr. Contaldo Rm. 103 Main Building-Glue flooring strips back onto floor, Mr. Contaldo removed strips.								
Velia Alarcon									
37442					8/27/2008		6		\$0.00
Medium	Work In Progress				8/27/2008 10:51:46 AM				
Ontiveros, Guadalupe	Requested by Coach Hite for Football Field-Sod bare areas on Football Field before first home game on September 12th.								
Velia Alarcon									
37443					8/27/2008		6		\$0.00
Medium	Work In Progress				8/27/2008 11:25:08 AM				
Ontiveros, Guadalupe	Requested by Coach Hite for Football Field-White line game field before first home game on September 12th.								
Velia Alarcon									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
37444	Old English Bldg				8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 11:31:54 AM					
Apodaca, Mario	Requested by Mr. Stemsrud Rm. 154 Old English Building- Hang maps.								
<u>Velia Alarcon</u>									
37445					8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 11:33:57 AM					
Lara, Ralph	Requested by Mr. Mora Rm. 403 Boys Gym (Training Room)-Athletic training room door broke again, hinges need to be replaced.								
<u>Velia Alarcon</u>									
37446	Auto Shop				8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 11:38:46 AM					
Vallejo, Albert	Requested by Mr. Enriquez Rm. 580 Auto Shop-The class of the auto shop needs some paint to the windows.								
<u>Velia Alarcon</u>									
37448	Auto Shop				8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 11:41:06 AM					
Appelzoller, Fred	Requested by Mr. Enriquez Rm. 580 Auto Shop-Need an airline to the south wall of the shop. Also a fresh water tap to the north wall of the Auto Shop.								
<u>Velia Alarcon</u>									
37449	Boys Gym				8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 11:44:27 AM					
Appelzoller, Fred	Requested by Coach Lawrence Boy's Gym P.E. Side of Gym-Men's restroom as a urinal that has not worked since the summer and it really stinks.								
<u>Velia Alarcon</u>									
37487	Cafeteria (1998)	Cafeteria			8/28/2008		5		\$0.00
Medium	Work In Progress			8/28/2008 11:05:01 AM					
Sitters, Mary	i need one gallon of degreaser for the spills at the trash compactor								
<u>Joe Munoz</u>									
37542					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:11 AM					
Vallejo, Albert	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37543					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:11 AM					
Vallejo, Albert	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
37544					8/31/2008	10/1/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:12 AM				
Vallejo, Albert		Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
37628					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:39 AM				
Apodaca, Mario		Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
Count: 110 Work Orders			Avg. Age of WO's	26		Total for Gadsden HS	1	\$25.00	

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
35591					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:33 AM					
Orozco, Danny		Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
35702					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:08 AM					
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
35828	Annex	Classroom			7/10/2008		54		\$0.00
Medium	Work In Progress	Annex/Room 400		7/10/2008 10:15:00 AM					
Estrada, Jesus		Replace carpet in Room 400.							
<u>Maricruz Carrasco</u>									
35829	C-Wing	Classroom			7/10/2008		54		\$0.00
Medium	Work In Progress	Cwing/C-206		7/10/2008 10:16:48 AM					
Estrada, Jesus		Replace carpet in Room C-206.							
<u>Maricruz Carrasco</u>									
35900					7/13/2008	7/29/2008	51		\$0.00
Medium	Work In Progress			7/13/2008 12:18:04 AM					
Acosta, Juan		Monthly - QRTLY BLDG INSP REPORT (GM) - Refer to PM schedule details.							
<u>Jesus Estrada</u>									
35947		Office			7/14/2008		50		\$0.00
High	Work In Progress	Awing/T. Urbina's		7/14/2008 11:29:19 AM					
Jacquez, Ricardo		Manhole located in T. Urbina's office needs to be sealed. The metal lid that is currently on that manhole is too small and is permitting vapors and putrid odors from the crawl space. We need a larger metal lid and to make sure that the access door is sealed in a manner that prohibits those odors into the room. This manhole poses a safety issue in that someone could fall into the access door and the odors can be a health risk to the person who is occupying the room. Please take care of this as soon as possible.							
<u>Maricruz Carrasco</u>									
35955					7/14/2008		50		\$0.00
Medium	Work In Progress			7/14/2008 3:35:17 PM					
Lozoya, Manny		Need fix main entrance doors the punish bar not work properly thank you							
<u>Sebastian Diaz</u>									
35991					7/16/2008		48		\$0.00
Medium	Work In Progress	GMS Campus		7/16/2008 11:16:19 AM					
Diaz, Sebastian		Door stops are needed on every door on campus.							
<u>Maricruz Carrasco</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
36131					7/23/2008		41		\$0.00
Medium	Work In Progress			7/23/2008 7:50:13 AM					
Solis, Lorenzo	7/23/08 A/C not working in C wing thank you								
Sebastian Diaz									
36196		Office			7/24/2008		40		\$0.00
Medium	Work In Progress	Awing/Dr.		7/24/2008 4:10:24 PM					
Sotelo, Enrique	Need more outlets in Dr. Garcia's office in order to connect printers, copiers, etc. as soon as possible.								
Maricruz Carrasco									
36222		Office			7/25/2008		39		\$0.00
Medium	Work In Progress	Awing/GMS Front		7/25/2008 11:40:57 AM					
Lozoya, Manny	Need to set up A57 key lock on new door in Ms. Quinonez's office as soon as possible.								
Maricruz Carrasco									
36627		Office			8/5/2008		28		\$0.00
Medium	Work In Progress	GMS Front		8/5/2008 5:44:35 AM					
Lozoya, Manny	Need A53 door lock on Nancy's door as soon as possible.								
Maricruz Carrasco									
36628		Office			8/5/2008		28		\$0.00
Medium	Work In Progress	Awing/155/Dr.		8/5/2008 5:47:23 AM					
Lozoya, Manny	Door lock in Dr. Garcia's office supposed to be opened by M36 key only. W key can be used to open the door. Please check door lock.								
Maricruz Carrasco									
36629		Classroom			8/5/2008		28		\$0.00
Medium	Work In Progress	Bwing/141/G.		8/5/2008 5:53:14 AM					
Diaz, Sebastian	Room needs a paint job. It has grafitti all over. Paint bookshelf the same color of room.								
Maricruz Carrasco									
36630		Parking Lot			8/5/2008		28		\$0.00
Medium	Work In Progress	Parking		8/5/2008 5:56:11 AM					
Ronquillo, Ruben	Need two windows in security shed.								
Maricruz Carrasco									
36632		Parking Lot			8/5/2008		28		\$0.00
Medium	Work In Progress	Parking		8/5/2008 5:59:53 AM					
Lozoya, Manny	Need metal door installed in Security shed.								
Maricruz Carrasco									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
36733	Cafeteria	Cafeteria			8/6/2008		27		\$0.00
Medium	Work In Progress	Outside cafeteria			8/6/2008 6:36:10 PM				
Gonzalez, Salvador		Walking gate on right corner of the cafeteria needs to be extended for easy access for GMS golf cart to travel between Main Campus and Bus Turnaround.							
<u>Maricruz Carrasco</u>									
36994	Cafeteria	Cafeteria			8/13/2008		20		\$0.00
Medium	Work In Progress				8/13/2008 8:10:48 AM				
Moncayo, Fernando		SNP WAREHOUSE A/C SOUTHSIDE HAS NO WATER. HOT AIR BLOWING.							
		JOHNNY LECHUGS SNP MGR WHSE 882-6927							
<u>Jacqueline Aguilar</u>									
36995	Cafeteria	Cafeteria			8/13/2008		20		\$0.00
Medium	Work In Progress				8/13/2008 8:12:29 AM				
Moncayo, Fernando		SNP WAREHOUSE: WALK IN REFRIG. NEEDS TO BE RECHECK TEMP. THIS MORNING WAS AT 42.							
		JOHNNY LECHUGA SNP MGR 882-6927							
<u>Jacqueline Aguilar</u>									
37002	Cafeteria	Cafeteria			8/13/2008		20		\$0.00
Medium	Work In Progress				8/13/2008 9:07:14 AM				
Orozco, Danny		SNP WAREHOUSE: FREEZER #2 NEEDS THE DOOR RUBBER SEALS TO BE REPLACED.							
		JOHNNY LECHUGA SNP MGR 882-6927							
<u>Jacqueline Aguilar</u>									
37014	C-Wing	Computer Lab			8/13/2008		20		\$0.00
Medium	Work In Progress	Cwing/C-			8/13/2008 12:26:49 PM				
Gonzalez, Salvador		Replace or fix the ramp to Career Center for safety purposes.							
<u>Maricruz Carrasco</u>									
37027		Parking Lot			8/13/2008		20		\$0.00
Medium	Work In Progress	Parking lot by C-			8/13/2008 3:10:30 PM				
Ronquillo, Ruben		Need to replace sign "Reserved for Visitor sign" with "Judge Schultz"							
<u>Maricruz Carrasco</u>									
37035					8/13/2008		20		\$0.00
Medium	Work In Progress				8/13/2008 3:47:01 PM				
Appelzoller, Fred		8/13/08 need to replace water fauset in sink C wing girl rest thank you							
Sebastian Diaz									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
37266	Cafeteria	Cafeteria			8/21/2008		12		\$0.00
Medium	Work In Progress	Cafeteria/WAR		8/20/2008 10:00:14 PM					
Diaz, Sebastian		We have 2 ping-pong tables and one other game table that needs to be assembled.							
<u>Maricruz Carrasco</u>									
37267		Office			8/21/2008		12		\$0.00
Medium	Work In Progress	Awing/162/Securit		8/20/2008 10:01:58 PM					
Lozoya, Manny		"W" key is getting jammed.							
<u>Maricruz Carrasco</u>									
37270		Classroom			8/21/2008		12		\$0.00
Medium	Work In Progress	Awing/159/E.		8/20/2008 10:06:16 PM					
Lozoya, Manny		Door does not close and lock.							
<u>Maricruz Carrasco</u>									
37336	Cafeteria	Office			8/22/2008		11		\$0.00
Medium	Work In Progress	Cafeteria/333/Vigi		8/22/2008 10:14:45 AM					
Lozoya, Manny		Move F3 core from Attendance office to Room 333 for Miguel Vigil and Juan Acosta's office.							
<u>Maricruz Carrasco</u>									
37337		Office			8/22/2008		11		\$0.00
Medium	Work In Progress	Awing/Attendance		8/22/2008 10:16:58 AM					
Lozoya, Manny		Rekey core on Attendance Office door to be off master.							
<u>Maricruz Carrasco</u>									
37358		Portables			8/25/2008		8		\$0.00
Medium	Work In Progress	Double Portable		8/25/2008 12:42:33 PM					
Solis, Lorenzo		Double Portable - Need to cover all registers properly.							
<u>Michael Munoz</u>									
37530	Cafeteria				8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 1:53:08 PM					
Orozco, Danny		please repiar ice machine. thxs							
<u>Michael Munoz</u>									
37531					8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 1:54:43 PM					
Ontiveros, Guadalupe		need to apply crusher fine gravel to where students exit bldg to the buses by portables. thxs							
<u>Michael Munoz</u>									
37660					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:49 AM					
Diaz, Sebastian		Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Gadsden MS							
37661					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:50 AM				
Diaz, Sebastian	Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
37662					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:50 AM				
Diaz, Sebastian	Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
Count: 34 Work Orders			Avg. Age of WO's	27		Total for Gadsden MS	0	0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: La Union - JTP Alvarez Farms									
37476					8/28/2008		5		\$0.00
Medium	Work In Progress				8/28/2008 7:46:35 AM				
Castillo, Carlos	Asp e-mail w/o for the replacement of the outside lights.								
Selma Nevarez									
Count: 1	Work Orders		Avg. Age of WO's	5	Total for La Union - JTP Alvarez Farms			0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
35592					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:33 AM					
Orozco, Danny	Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
35705					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:09 AM					
Villalobos, David	Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35791		Cafeteria			7/9/2008		55		\$0.00
Medium	Work In Progress			7/9/2008 1:48:49 PM					
Moncayo, Fernando	OVENS NEED TO BE CHECKED. SOMETIMES THEY WILL HEAT UP AND THEN STOP HEATING ALL OF A SUDDEN.								
	LINDA YANAGA SNP MGR 589-2040								
Jacqueline Aguilar									
35792		Cafeteria			7/9/2008		55		\$0.00
Medium	Work In Progress			7/9/2008 1:49:55 PM					
Moncayo, Fernando	PASS THRU REFRIG. IS FREEZING UP.								
	LINDA YANAGA LU SNP MGR 589-2040								
Jacqueline Aguilar									
35921					7/13/2008	7/29/2008	51		\$0.00
Medium	Work In Progress			7/13/2008 12:18:11 AM					
Gonzalez, Salvador	Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
36505					8/3/2008	8/9/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:15 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
36536					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:25 AM					
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36544					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:27 AM					
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
36588					8/4/2008		29		\$0.00
Medium	Work In Progress			8/4/2008 10:23:03 AM					
Castillo, Carlos	pat aguilar need help with the light in the office safe - trasformer sp1400								
Patricio Aguilar									
36590					8/4/2008		29		\$0.00
Medium	Work In Progress			8/4/2008 10:36:40 AM					
Castillo, Carlos	Run elect. to morgom maint storage - would be nice to use fan								
Patricio Aguilar									
36624					8/4/2008		29		\$0.00
Medium	Work In Progress	WWT		8/4/2008 4:12:49 PM					
Sanchez, Raul	Plug Monitoring Wells as per State NMED Regulations.								
Raul Sanchez									
36856					8/10/2008	8/26/2008	23		\$0.00
Medium	Work In Progress			8/10/2008 12:19:44 AM					
Aguilar, Patricio	Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
36891		Athletic Field			8/11/2008		22		\$0.00
Medium	Work In Progress			8/11/2008 2:47:10 PM					
Aguilar, Patricio	Provide backfill around new concret under new canopy- build a gradual slope from the concrete to the grass.								
Alfredo Holguin									
36892	Main Building				8/11/2008		22		\$0.00
Medium	Work In Progress			8/11/2008 2:48:41 PM					
Aguilar, Patricio	Check all evap AC's and verify that they are working correctly.								
Alfredo Holguin									
36893	Annex Building				8/11/2008		22		\$0.00
Medium	Work In Progress			8/11/2008 2:49:52 PM					
Aguilar, Patricio	Install kiln in the middle of annex bldg where boiler used to be. Santos knows where and custodial can support w/placement.								
Michael Munoz									
36996		Cafeteria			8/13/2008		20		\$0.00
Medium	Work In Progress			8/13/2008 8:23:00 AM					
Moncayo, Fernando	REACH THRU REFRIG. DOES NOT COOL TEMP IS AT 50								
Jacqueline Aguilar	LINDA YANAGA SNP MGR 589-2040								

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
37040	Annex Building				8/13/2008		20		\$0.00
Medium	Work In Progress			8/13/2008 4:17:56 PM					
Castillo, Carlos		Install electrical for kiln in room # 203							
Alfredo Holguin									
37041	Annex Building				8/13/2008		20		\$0.00
Medium	Work In Progress			8/13/2008 4:18:39 PM					
Ambriz, Jose		Install venting for kiln in room # 203							
Alfredo Holguin									
37120					8/15/2008		18		\$0.00
Medium	Work In Progress			8/15/2008 3:17:51 PM					
Castillo, Carlos		pat aguilar need 3 gfi elect out lets #202							
Patricio Aguilar									
37489	Annex Building				8/28/2008		5		\$0.00
Medium	Work In Progress			8/28/2008 1:15:53 PM					
Aguilar, Patricio		Pick up kiln from SM and coordinate w/Danny Vega so he can open and assist w/loading kiln.							
Michael Munoz									
37632					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:40 AM					
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
37633					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:40 AM					
Aguilar, Patricio		Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
37642					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:43 AM					
Aguilar, Patricio		Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
37663					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:50 AM					
Gonzalez, Salvador		Monthly - La Union ES A-1 Semiannual EVS - Refer to PM schedule details.							
Margret Villalobos									
37664					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:50 AM					
Gonzalez, Salvador		Monthly - La Union ES A-8 Quarterly HPW - Refer to PM schedule details.							
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		La Union ES							
37665					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:51 AM				
Gonzalez, Salvador	Monthly - La Union ES A-1 Semiannual MCD - Refer to PM schedule details.								
Margret Villalobos									
37666					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:51 AM				
Gonzalez, Salvador	Monthly - La Union ES A-10 Semiannual HPWC - Refer to PM schedule details.								
Margret Villalobos									
37667					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:51 AM				
Gonzalez, Salvador	Monthly - La Union ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos									
Count: 28 Work Orders		Avg. Age of WO's	23	Total for La Union ES				0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
35583					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:31 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
35593					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:34 AM					
Orozco, Danny	Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
35703					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:08 AM					
Villalobos, David	Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36116					7/22/2008		42		\$0.00
Medium	Work In Progress			7/22/2008 12:27:51 PM					
Lozoya, Manny	Manny, needing door in room 212 repaired								
Grace Alvarado									
36408					7/31/2008		33		\$0.00
Medium	Work In Progress			7/31/2008 2:26:46 PM					
Ronquillo, Ruben	Need to replace 10 more blinds.								
Rudy Arreola									
36409		Parking Lot			7/31/2008		33		\$0.00
Medium	Work In Progress			7/31/2008 2:27:51 PM					
Sotelo, Enrique	Need to install 2 more security lights on the bus turnaround area.								
Rudy Arreola									
36411		Parking Lot			7/31/2008		33		\$0.00
Medium	Work In Progress			7/31/2008 2:29:13 PM					
Sotelo, Enrique	Need to install a GCFI outlet so when we have to pump out the water in bus turn around we have access.								
Rudy Arreola									
36686					8/6/2008		27		\$0.00
Medium	Work In Progress			8/6/2008 3:03:22 PM					
Lozoya, Manny	Rm 111 needs to have lock installed in her filing cabinet.								
Rudy Arreola									
36898					8/11/2008		22		\$0.00
Medium	Work In Progress			8/11/2008 3:03:50 PM					
Lozoya, Manny	We need a lock installed in a filing cabinet in RM 201								
Rudy Arreola									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
36958					8/12/2008		21		\$0.00
Medium	Work In Progress			8/12/2008 3:06:06 PM					
Ontiveros, Guadalupe		We need to have some areas leveled off where rain has washed away dirt.							
Rudy Arreola									
37058		Portables			8/14/2008		19		\$0.00
Medium	Work In Progress			8/14/2008 10:22:44 AM					
Arreola, Rudy		Complete skirting installation on double portable							
Alfredo Holguin									
37172		Custodial			8/19/2008		14		\$0.00
Medium	Work In Progress			8/19/2008 7:44:41 AM					
Sotelo, Enrique		We need an extra outlet in luis office.							
Rudy Arreola									
37174		Classroom			8/19/2008		14		\$0.00
Medium	Work In Progress			8/19/2008 7:48:48 AM					
Sotelo, Enrique		Rm 111 the emergency light is out not working at all.							
Rudy Arreola									
37438		Custodial			8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 9:25:44 AM					
Carbajal, Jimmy		WE NEED SERVICE FOR THE BUFFER MACHINE. (FIRE ON THE ELECTRICO CORD) THANKS.							
Luis Solis									
37465					8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 3:44:41 PM					
Arreola, Rudy		CUT WEEDS AND CLEAN UP NEW LANDSCAPING IN FRONT AND SIDE.							
Michael Munoz									
37651					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:46 AM					
Arreola, Rudy		Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
37652					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:46 AM					
Arreola, Rudy		Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
37653					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:47 AM					
Arreola, Rudy		Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Loma Linda ES							
37669					9/2/2008		0		\$0.00
Medium	Work In Progress				9/2/2008 8:12:59 AM				
Appelzoller, Fred	Toilet is leaking in the boys RRs in cafeteria lobby from the bottom.								
Rudy Arreola									
Count: 19 Work Orders		Avg. Age of WO's	24	Total for Loma Linda ES				0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
35549					7/6/2008	7/12/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:20 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
35567					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:26 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
35594					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:34 AM					
Orozco, Danny	Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
35626					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:44 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35636					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:47 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35661					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:55 AM					
Ramirez, Joe	Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
35684					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:02 AM					
Ramirez, Joe	Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
35706					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:09 AM					
Villalobos, David	Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
36109					7/22/2008		42		\$0.00
Medium	Work In Progress			7/22/2008 10:11:48 AM					
Lozoya, Manny	on (work room) needs a cylinder with a key they have school files need to be lock all the time as per montano principal asap. thank you. luis								
<u>Luis Saucedo</u>									
36147	Main Building	Office			7/23/2008		41		\$0.00
Medium	Work In Progress	Main office area		7/23/2008 12:29:38 PM					
Lozoya, Manny	Main office need's (4) engraved plaque's for front office door. Name and Title (Jacob Montano, Principal), (Sandra Mora, Secretary), (Dora Lerma, Data-Entry Clerk), (Maribel Villela, Receptionist-Clerk) for Manny Lozoya.								
<u>Sandra Mora</u>									
36149	Main Building				7/23/2008		41		\$0.00
Medium	Work In Progress	3rd grade		7/23/2008 12:35:49 PM					
Ontiveros, Joe	Mrs. Hernandez, room # 112 need's washer/dryer outlets installed in room.								
<u>Sandra Mora</u>									
36227		Portables			7/25/2008		39		\$0.00
Medium	Work In Progress			7/25/2008 2:11:53 PM					
Lozoya, Manny	Ms. Flores room # 801 has filing cabinet that doesn't have a key, need's to be re-key.								
<u>Sandra Mora</u>									
36245					7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 7:44:32 AM					
Ramirez, Joe	please need to check water pump we have flood on barracks on 7/29/08 between the blds. thank you.								
<u>Luis Saucedo</u>									
36256	2003 Classroom	Classroom			7/28/2008		36		\$0.00
Medium	Work In Progress	Portable room #		7/28/2008 8:30:02 AM					
Lozoya, Manny	Ms. Jimenez, portable room # 506 she has a storage cabinet needs to be re-key.								
<u>Sandra Mora</u>									
36259	2003 Classroom	Classroom			7/28/2008		36		\$0.00
Medium	Work In Progress	Kinder hallway,		7/28/2008 8:58:17 AM					
Lozoya, Manny	Need a master for that room # 405 for our inventory, and key # 305.								
<u>Sandra Mora</u>									
36278					7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 11:12:36 AM					
Carbajal, Jimmy	PLEASE, I NEED A HURRICANE BLOWER(I HAVE ONE BUT A NEED ONE MORE) THANK YOU. LUIS								
<u>Luis Saucedo</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
36507					8/3/2008	8/9/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:15 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
36539					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:26 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36549					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:29 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36577					8/4/2008		29		\$0.00
Medium	Work In Progress			8/4/2008 5:44:47 AM					
Ramirez, Joe	please need to chek the roof this mornig we got a few big leak in the cafeteeria from the rain.thank you luis.								
Luis Saucedo									
36885	Main Building	Office			8/11/2008		22		\$0.00
Medium	Work In Progress	Office area		8/11/2008 11:09:39 AM					
Lozoya, Manny	(1) engraved plaque for front office door. Name and Title (Norma Sierra, Assistant Principal) for Manny Lozoya								
Sandra Mora									
37225					8/20/2008		13		\$0.00
Medium	Work In Progress			8/20/2008 12:43:56 PM					
Ontiveros, Joe	sink faucet in south lounge needs to be replaced.								
Joe Ramirez									
37330		Classroom			8/22/2008		11		\$0.00
Medium	Work In Progress			8/22/2008 9:53:47 AM					
Lozoya, Manny	Need to check lock on filing cabinet room 110.								
Michael Munoz									
37331					8/22/2008		11		\$0.00
Medium	Work In Progress	LINE LOCATE		8/22/2008 9:55:06 AM					
Castillo, Carlos	Need to line locate for Env. Park (Greenhouse) contact J. Perez.								
Michael Munoz									
37428					8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 5:27:42 AM					
Ramirez, Joe	this morning we have a few leaks in the cafeteria by south side corner. thank you luis								
Luis Saucedo									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
37490					8/28/2008		5		\$0.00
Medium	Work In Progress			8/28/2008 3:06:30 PM					
Ramirez, Joe	continue the condensation line to a proper area for drainage.								
Michael Munoz									
37617					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:35 AM					
Ramirez, Joe	Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
Margret Villalobos									
37618					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:35 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual MCD - Refer to PM schedule details.								
Margret Villalobos									
37619					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos									
37620					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual UCD - Refer to PM schedule details.								
Margret Villalobos									
37621					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual UCS2 - Refer to PM schedule details.								
Margret Villalobos									
37622					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.								
Margret Villalobos									
37623					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
37624					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.								
Margret Villalobos									
37625					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual EVS - Refer to PM schedule details.								
Margret Villalobos									
37626					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
37627					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
Count: 37 Work Orders			Avg. Age of WO's	26	Total for Mesquite ES			0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
35551					7/6/2008	7/12/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:21 AM					
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
35629					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:45 AM					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35640					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:48 AM					
Vega, Danny	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35721					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:14 AM					
Vega, Danny	Monthly - North Valley ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
36158					7/23/2008		41		\$0.00
Medium	Work In Progress			7/23/2008 3:13:20 PM					
Carrasco, Danny	need two portable a/c units to cover rms#207 and 181 wk rm at end of organ trail-have one in rm201 already -if you have them bring them please.thanks								
Danny Vega									
36463		Office			8/1/2008		32		\$0.00
Medium	Work In Progress	room 400		8/1/2008 11:44:39 AM					
Lozoya, Manny	Hello Manny, The alarm box key was broken off, please replace.								
Priscilla Martinez									
36509					8/3/2008	8/9/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:16 AM					
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
36542					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:27 AM					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
36553					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:30 AM					
Vega, Danny		Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
36643					8/5/2008		28		\$0.00
Medium	Work In Progress			8/5/2008 11:59:27 AM					
Ontiveros, Guadalupe		need to level -off rain erosion by plgrd with tractor and scraper (most off erosion by run-offs)asap							
Danny Vega									
37136		Office			8/18/2008		15		\$0.00
Medium	Work In Progress	video		8/18/2008 10:18:19 AM					
Lozoya, Manny		could not locate a key				Need a black box located in our office to be opened, could not locate the correct key in our vault			
Priscilla Martinez									
37188		Cafeteria			8/19/2008		14		\$0.00
Medium	Work In Progress			8/19/2008 9:58:55 AM					
Orozco, Danny		DOOR FELL OFF TO REACH-IN WARMER							
		EVA MIRANDA - SNP MANAGER 233-3658							
Alma Terrell									
37221		Classroom			8/20/2008		13		\$0.00
Medium	Work In Progress	various		8/20/2008 9:15:00 AM					
Lozoya, Manny		Send Lozoya to make various keys for various classrooms, desks, cabinets, filing cabinets, storage closets,				please visit the front office for this list of keys that are needed, thanks Priscilla			
Priscilla Martinez									
37310					8/21/2008		12		\$0.00
Medium	Work In Progress			8/21/2008 3:30:27 PM					
Lozoya, Manny		stage area in gym supply rm door core will not turn-need to open for pa system controls.please ck asap							
Danny Vega									
37326					8/22/2008		11		\$0.00
Medium	Work In Progress			8/22/2008 7:29:45 AM					
Munoz, Michael		need cement slab at marquee sign 12x12 very harzardous to place ladder on dirt uneven grd due to rain erosion on ponding area							
Danny Vega									
37563					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:18 AM					
Vega, Danny		Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
37566					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:19 AM					
Vega, Danny		Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
37567					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:19 AM					
Vega, Danny		Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
37673					9/2/2008		0		\$0.00
Medium	Work In Progress			9/2/2008 8:56:44 AM					
Munoz, Michael		230ft x5ft sidewalk by rm 306 for ADA evacuation safety plus a 6ft by 6ft landing(this is on west side of bldg)							
Danny Vega									
37675					9/2/2008		0		\$0.00
Medium	Work In Progress			9/2/2008 9:01:54 AM					
Munoz, Michael		need a 4ft gate door by marquee by 12ft by 12ft slab (facing north) spoke to jaun v. on this							
Danny Vega									
Count: 20 Work Orders		Avg. Age of WO's		25	Total for North Valley ES			0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Northern On-Track Pre-K (LM)							
35546					7/6/2008	7/12/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:19 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
35564					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:25 AM					
Vega, Danny	Monthly - La Mesa ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
35621					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:42 AM					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35627					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:44 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35658					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:54 AM					
Vega, Danny	Yearly - La Mesa ES Emer. Light Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
35681					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:01 AM					
Vega, Danny	Yearly - La Mesa ES Exit Sign Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
35704					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:09 AM					
Villalobos, David	Yearly - Northern Pre-K (LM) Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36220	Main Building				7/25/2008		39		\$0.00
Medium	Work In Progress			7/25/2008 11:25:22 AM					
Vega, Danny	Hedge in front of Main Entrance - needs to be trimmed also a sprout in the Planter on the west side of the entrance needs to be removed and the hedge growing against the building directly next to it also.								
Alfredo Holguin									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
36481					8/1/2008		32		\$0.00
Medium	Work In Progress				8/1/2008 3:30:32 PM				
Ontiveros, Guadalupe		need to level-off with kabota and small scraper/by north fence line and ply grd							
Danny Vega									
36483					8/1/2008		32		\$0.00
Medium	Work In Progress				8/1/2008 3:34:14 PM				
Sotelo, Enrique		need to install control panels in pump house and main bldg for new electric valves /wire is runnig in trench already							
Danny Vega									
36504					8/3/2008	8/9/2008	30		\$0.00
Medium	Work In Progress				8/3/2008 12:20:14 AM				
Vega, Danny		Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
36534					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress				8/3/2008 12:20:24 AM				
Vega, Danny		Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
36540					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress				8/3/2008 12:20:26 AM				
Vega, Danny		Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
36680					8/6/2008		27		\$0.00
Medium	Work In Progress	Playground			8/6/2008 11:23:04 AM				
Vega, Danny		New playground structure is complete. We need plastic lining and Round-up applied so that area can be filled in with sand. We also need a sand box moved, enlarged and filled with sand.				8/11 - Asp Lupe route to D. Vega			
Gilbert Trujillo									
36858					8/10/2008	8/26/2008	23		\$0.00
Medium	Work In Progress				8/10/2008 12:19:45 AM				
Vega, Danny		Monthly - Northern On-Track Pre-K Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
36884	Cafeteria	Custodial			8/11/2008		22		\$0.00
Medium	Work In Progress	room 16			8/11/2008 10:49:59 AM				
Vega, Danny		roof is leaking, ceiling fell off.							
Gilbert Trujillo									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
36943		Parking Lot			8/12/2008		21		\$0.00
Medium	Work In Progress			8/12/2008 9:47:15 AM					
Sotelo, Enrique		street lamp bulb needs to be replaced							
Gilbert Trujillo									
37110	Main Building	Athletic Field			8/15/2008		18		\$0.00
Medium	Work In Progress			8/15/2008 11:15:46 AM					
Ontiveros, Guadalupe		Requesting tree bark for new playground structure, as per Ann Steinhoff.							
Concepcion Montalvo									
37300					8/21/2008		12		\$0.00
Medium	Work In Progress			8/21/2008 3:03:06 PM					
Vega, Danny		8-18-08 .5-ck wk ods in office nve 2.5-ck and clean a/c unit distributors la mesa pre-k 5-cut weeds and spray round-up at la mesa							
Danny Vega									
37454		Pool			8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 1:49:31 PM					
Ontiveros, Joe		need to replace urinal p traps							
Gilbert Trujillo									
37564					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:18 AM					
Vega, Danny		Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
37565					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:18 AM					
Vega, Danny		Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
37568					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:19 AM					
Vega, Danny		Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
Count: 23 Work Orders		Avg. Age of WO's 32		Total for Northern On-Track Pre-K (LM)			0	\$0.00	

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Physical Plant Complex								
35707					7/6/2008	8/6/2008	58		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:10 AM						
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
35751	Food Services	Restroom (Boys)			7/8/2008		56		\$0.00	
Medium	Work In Progress			7/8/2008 8:32:14 AM						
Diaz, Sebastian		Walls in the restroom at food service (warehouse) needs to be painted. Thank you								
Guillermo Hernandez										
35864					7/11/2008		53		\$0.00	
Medium	Work In Progress			7/11/2008 8:59:27 AM						
Jacquez, Ricardo		7-9-08 ppd-1.5 ck wwtp cms-6 wo# 33549 ppd-.5 daily o&m on wwtp								
Ricardo Jacquez										
36213	Maintenance				7/25/2008		39		\$0.00	
Medium	Work In Progress			7/25/2008 10:15:21 AM						
Sotelo, Enrique		please install electrical outlet to cooling duct fan and pilot switch. Thxs								
Michael Munoz										
36291					7/28/2008		36		\$0.00	
Medium	Work In Progress			7/28/2008 3:26:53 PM						
Ronquillo, Ruben		Purchase a new water tank								
Alfredo Holguin										
36355	Food Services	Parking Lot			7/30/2008		34		\$0.00	
Medium	Work In Progress	SNP		7/30/2008 12:01:33 PM						
Ontiveros, Guadalupe		AS PER MR. GIOVAS-IF NEAR THE WAREHOUSE GOING FROM THE SHADED AREA TO THE STAIR WAY INTO THE WAREHOUSE IF THEY CAN LEVEL OUT THE PATH WAY. (PLEASE SEE JOHNNY L. IF NEED DIRECTION.)								
Mary Garcia										
36576					8/4/2008		29		\$0.00	
Medium	Work In Progress			8/4/2008 12:19:31 AM						
Villalobos, Margret		Monthly - PPD - Quarterly Meeting - Refer to PM schedule details.								
Margret Villalobos										
36755					8/7/2008		26		\$0.00	
Medium	Work In Progress			8/7/2008 9:00:09 AM						
Gonzalez, Salvador		as per our discussion, please cut and weld gates so that SNP will have access early in the morning.								
Michael Munoz										

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
36758	Maintenance				8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 9:51:53 AM				
Munoz, Michael	Need price quote to build 10 shelves for desktops at Tech's Office.								
<u>Michael Munoz</u>									
36759	Maintenance				8/7/2008		26		\$0.00
Medium	Work In Progress				8/7/2008 9:53:28 AM				
Munoz, Michael	Need price quote to build an architect table for Tech's Office.								
<u>Michael Munoz</u>									
37066					8/14/2008		19		\$0.00
Medium	Work In Progress				8/14/2008 11:15:18 AM				
Ronquillo, Ruben	Purchase new individual signs to go above doors outside Bldg. indicating as follows: -Purchasing Warehouse -Instructional Materials -Physical Plant Dept./ Construction Dept./Custodial Dept. -Custodial Shipping/Receiving Also 1 sign for Main Entrance by Nurse Complex indicating as follows: Construction Dept. Instructional Materials Student Nutrition Warehouse Student Records Transportation Physical Plant Department Custodial Dept. Maintenance Dept. Motor Pool Purchasing Warehouse SEE ALFREDO IF ANY QUESTIONS.								
<u>Alfredo Holguin</u>									
37074	Food Services				8/14/2008		19		\$0.00
Medium	Work In Progress				8/14/2008 2:23:06 PM				
Lara, Ralph	As per Mike, remove doubled doors and replace with a rolling door. Please see Mike if you have any questions.								
<u>Michael Munoz</u>									
37659					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:49 AM				
Diaz, Sebastian	Monthly - Physical Plant FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 13 Work Orders			Avg. Age of WO's	33	Total for Physical Plant Complex			0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
35595					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:34 AM					
Orozco, Danny	Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35708					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:10 AM					
Villalobos, David	Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35753	New Wing 1/02				7/8/2008		56		\$0.00
Medium	Work In Progress			7/8/2008 10:29:47 AM					
Ronquillo, Ruben	Need window repaired room 137 due to break in 20x21 Add two more broken windows custodian found windows in corrdor by cafe.								
<u>Carlos Hernandez</u>									
35834					7/10/2008		0	3	\$277.59
Medium	Work In Progress			7/10/2008 11:08:20 AM	7/10/2008				
Carbajal, Jimmy	Mr. carbajal , the aqua clean machine is leaking water,can you fix it please thank you.		repaired (replaced used valve) and did pm						
<u>Daniel Mata</u>									
36235					7/25/2008		39		\$0.00
Medium	Work In Progress			7/25/2008 3:25:32 PM					
Ontiveros, Guadalupe	need 5 loads sand for play grounds								
<u>Carlos Hernandez</u>									
36292	Main Building				7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 3:27:42 PM					
Ambriz, Jose	a/c unit main office ducting leaking after rain needs to be sealed								
<u>Carlos Hernandez</u>									
36366					7/30/2008		34		\$0.00
Medium	Work In Progress			7/30/2008 3:47:39 PM					
Villalobos, Margret	upper wing needs to be fumagated lots of ants in classrooms								
<u>Carlos Hernandez</u>									
36377					7/30/2008		34	24	\$600.00
Medium	Work In Progress			7/30/2008 4:14:57 PM					
Estrada, Jesus	NEED TO REPLACE CARPET IN ROOM #15 AND ALSO FRON ENTRANCE TO LIBRARY DUE TO BREAK IN / VANDALISM.		reference w.o. #36601 for vandalism charges.Andres Alvarez, Valeria Castillo, Jesus Lerma, Daniel Mata, Hector Rivera, and Gabriel Mejia all worked 4 hrs in helping move furniture for carpet installation.						
<u>Jesus Estrada</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
36586		Cafeteria			8/4/2008		29		\$0.00
Medium	Work In Progress			8/4/2008 9:53:07 AM					
Moncayo, Fernando		Oven with Grill is not working/heating up at all.							
Alma Terrell		Emilia Carrillo - SNP Manager 589-2550							
36587		Cafeteria			8/4/2008		29		\$0.00
Medium	Work In Progress			8/4/2008 9:54:27 AM					
Moncayo, Fernando		Walk-In Refrigerator is leaking alot of water							
Alma Terrell		Emilia Carrillo - SNP Manager 589-2550							
36669					8/6/2008		27		\$0.00
Medium	Work In Progress			8/6/2008 8:39:54 AM					
Carrasco, Danny		need fuses for a/c units							
Carlos Hernandez									
36987					8/12/2008		21		\$0.00
Medium	Work In Progress			8/12/2008 4:12:40 PM					
Hernandez, Carlos		weeds are taking over along all fence lines and in parking area. please address. once cut.treat fence lines to prevent growth. call mike if you have questions. thxs							
Michael Munoz									
37148	New Wing 1/02				8/18/2008		15		\$0.00
Medium	Work In Progress			8/18/2008 3:12:30 PM					
Lara, Ralph		need to change door locks on classrooms outter door (princapal dosn't want door handles on on outside doors)							
Carlos Hernandez									
37255	Main Building				8/20/2008		13		\$0.00
Medium	Work In Progress			8/20/2008 3:43:37 PM					
Castillo, Carlos		need electrical outlet in storage room							
Carlos Hernandez									
37259	Main Building				8/20/2008		13		\$0.00
Medium	Work In Progress			8/20/2008 3:45:59 PM					
Castillo, Carlos		need to install light fixture in nurses office (bathroom) and need light switch for middle wing bathroom							
Carlos Hernandez									
37260	Main Building	Library			8/20/2008		13		\$0.00
Medium	Work In Progress			8/20/2008 3:46:58 PM					
Castillo, Carlos		need to install electrical outlet							
Carlos Hernandez									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
37439					8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 9:28:58 AM					
Gonzales, Angel		need tire fixed on tractor at sunland park es (front tire) thank u							
<u>Carlos Hernandez</u>									
37440		Portables			8/27/2008		6		\$0.00
Medium	Work In Progress			8/27/2008 9:30:51 AM					
Ronquillo, Ruben		broken window on new portable due to vandalism (Case# 2008-1239)							
<u>Carlos Hernandez</u>									
37493		Cafeteria			8/28/2008		5		\$0.00
Medium	Work In Progress			8/28/2008 3:24:24 PM					
Moncayo, Fernando		Seal to Walk-In needs to be replaced - it accumulates alot of ice							
		Emilia Carrillo - SNP Manager - 589-2550							
<u>Alma Terrell</u>									
37494		Cafeteria			8/28/2008		5		\$0.00
Medium	Work In Progress			8/28/2008 3:26:02 PM					
Moncayo, Fernando		Switch to 6 burner stove doesn't work							
		Emilia Carrillo - SNP Manager 589-2550							
<u>Alma Terrell</u>									
37546					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:12 AM					
Hernandez, Carlos		Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
37547					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:13 AM					
Hernandez, Carlos		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
37548					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:13 AM					
Hernandez, Carlos		Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
37549					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:13 AM					
Hernandez, Carlos		Monthly - Riverside ES A-6 Quarterly PUG - Refer to PM schedule details.							
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
37550					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:14 AM					
Hernandez, Carlos	Monthly - Riverside ES A-8 Quarterly HPW Unit - Refer to PM schedule details.								
Margret Villalobos									
37551					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:14 AM					
Hernandez, Carlos	Monthly - Riverside ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
Margret Villalobos									
37552					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:14 AM					
Hernandez, Carlos	Monthly - Riverside ES A-1 Semiannual MCD2 - Refer to PM schedule details.								
Margret Villalobos									
37553					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:15 AM					
Hernandez, Carlos	Monthly - Riverside ES A-1 Semiannual MCD - Refer to PM schedule details.								
Margret Villalobos									
Count: 28 Work Orders			Avg. Age of WO's	18		Total for Riverside ES	27	\$877.59	

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		San Miguel ES							
35596					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:19:35 AM				
Orozco, Danny	Monthly - San Miguel ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
35664					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:19:56 AM				
Vega, Danny	Yearly - San Miguel ES Emer. Light Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
35687					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:20:03 AM				
Vega, Danny	Yearly - San Miguel ES Exit Sign Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
36623					8/4/2008		29		\$0.00
Medium	Work In Progress	WWT			8/4/2008 4:12:10 PM				
Sanchez, Raul	Plug Monitoring Wells (3) as per State NMED Regulations.								
Raul Sanchez									
37343					8/22/2008		11		\$0.00
Medium	Work In Progress				8/22/2008 3:24:23 PM				
Lozoya, Manny	Asp Mike, please core back to GM 6 or 7 pin.								
Count: 5 Work Orders		Avg. Age of WO's		43	Total for San Miguel ES			0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
35597					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:35 AM					
Orozco, Danny	Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
35630					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:45 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35641					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:48 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35713					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:12 AM					
Villalobos, David	Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36262					7/28/2008		36		\$0.00
Medium	Work In Progress			7/28/2008 9:05:56 AM					
Gonzales, Angel	ATTN. MIKE MUNOZ MIKE AS PER OUR PHONE CONVERSATION OUR SCHOOL SITE INCURRED RAIN DAMAGE TO THE FRONT WALK IN GATE PATH. WE ALSO HAVE THE WASH OUT @ THE BACK FENCE AREA. I WILL NEED TO HAVE THE BOBCAT TO CLEAN UP THESE AREAS.					8/26 - Asp Lupe route to Auto Shop.			
Gerardo Marquez									
36676					8/6/2008		27		\$0.00
Medium	Work In Progress			8/6/2008 9:53:35 AM					
Lara, Ralph	MANNY; THE BOTTOM LOCKING PIN TO THE DR. AT THE MAINT. STORAGE RM. BROKE. WOULD YOU CHECK IT OUT SO WE CAN SECURE THIS RM. THANKS.								
Gerardo Marquez									
36941					8/12/2008		21		\$0.00
Medium	Work In Progress			8/12/2008 9:37:51 AM					
Flores, Pete	ANGEL; WOULD YOU SCHEDULE STE. FOR THE BOBCAT & SWEEPER. I STILL NEED TO FINISH FIXING THE WASHED OUT AREAS.								
Gerardo Marquez									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
37054	Main Building	Classroom			8/14/2008		19		\$0.00
Medium	Work In Progress	202		8/14/2008 10:07:05 AM					
Marquez, Gerardo		SOME FURNITURE NEEDS TO BE ASSEMBLED FOR CLASSROOMS. THANK YOU.							
Rita Mendez									
37063	Main Building	Classroom			8/14/2008		19		\$0.00
Medium	Work In Progress	CASA AZUL		8/14/2008 11:10:59 AM					
Marquez, Gerardo		PE COACH NEEDS A PEGBOARD CONSTRUCTED AND SET UP (FOR PE EQUIP.) THANKS.							
Rita Mendez									
37138					8/18/2008		15		\$0.00
Medium	Work In Progress			8/18/2008 11:30:28 AM					
Ambriz, Jose		JOSE; ART TEACHER @ PORTABLE -F STILL SAYING THAT HVAC. IS NOT COLD ENOUGH. WOULD YOU PLEASE CHECK IT OUT. I HAVE CHECKED IT OUT , AND IT SEEMS THAT ITS NOT BLOWING ENOUGH AIR OUT. THANKS.							
Gerardo Marquez									
37139					8/18/2008		15		\$0.00
Medium	Work In Progress			8/18/2008 11:44:10 AM					
Castillo, Carlos		CALI; HAND DRYER IN BOYS RRM. DOES NOT SHUT OFF AT TIMES, AND SOMETIMES STARTS BY ITSELF. NEED FOR YOU TO CHECK IT OUT. I TURNED THE BREAKER OFF , BECAUSE A STUDENT BURNED HIMSELF ON IT AND REPORTED IT TO THE OFFICE.							
Gerardo Marquez									
37447	Main Building	Classroom			8/27/2008		6		\$0.00
Medium	Work In Progress	RM 304		8/27/2008 11:39:51 AM					
Marquez, Gerardo		MS. FIELDS NEEDS AN AV CART TO BE PUT TOGETHER. THANK YOU.							
Rita Mendez									
37453	Main Building	Classroom			8/27/2008		6		\$0.00
Medium	Work In Progress	RM 304		8/27/2008 1:46:55 PM					
Marquez, Gerardo		TELEVISION SET NEEDS TO BE MOUNTED. THANK YOU.							
Rita Mendez									
37578					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:23 AM					
Marquez, Gerardo		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
37579					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:23 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
37580					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:23 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
37581					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:24 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.							
Margret Villalobos									
37582					8/31/2008	9/21/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:24 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES C-12 Chemical Feeder-SA - Refer to PM schedule details.							
Margret Villalobos									
Count: 18 Work Orders			Avg. Age of WO's	23		Total for Santa Teresa ES	0		\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
35520		Football Field			7/2/2008		62		\$0.00
Medium	Work In Progress			7/2/2008 8:03:34 AM					
Castillo, Carlos	NEED TO HAVE ONE LIGHT AT FOOTBALL FIELD CHECKED, NOT LIGHTING, WESTSIDE OF FIELD, BEHIND PRESSBOX.								
<u>Arturo Nunez</u>									
35552					7/6/2008	7/12/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:21 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35569					7/6/2008	7/14/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:26 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35598					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:35 AM					
Orozco, Danny	Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35666					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:56 AM					
Nunez, Arturo	Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35689					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:04 AM					
Nunez, Arturo	Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35711					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:11 AM					
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35756		Athletic Field			7/8/2008		56		\$0.00
Medium	Work In Progress			7/8/2008 11:03:17 AM					
Ontiveros, Guadalupe Terry Alvarado	Remove goal post and install at CMS.								

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
36225	Gymnasium				7/25/2008		39		\$0.00
Medium	Work In Progress				7/25/2008 2:08:58 PM				
Gonzalez, Salvador	please enlarge opening to pipe chase between water fountains in the hall by the gym. please see mike. thxs								
<u>Michael Munoz</u>									
36329	Gymnasium				7/29/2008		35		\$0.00
Medium	Work In Progress				7/29/2008 3:45:02 PM				
Boyd, David	Locker Room and Offices water leak on the roof.								
<u>Manuel Prospero</u>									
36384					7/31/2008		33		\$0.00
Medium	Work In Progress				7/31/2008 8:05:50 AM				
Prospero, Manuel	7/30/08. 8 HRS	FINISH PAINTING 300'S HALLWAY.			7/30 - 8				
<u>Manuel Prospero</u>									
36510					8/3/2008	8/9/2008	30		\$0.00
Medium	Work In Progress				8/3/2008 12:20:16 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36545					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress				8/3/2008 12:20:28 AM				
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36555					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress				8/3/2008 12:20:31 AM				
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36645	Cafeteria (2005)	Cafeteria			8/5/2008		28		\$0.00
Medium	Work In Progress				8/5/2008 1:01:49 PM				
Moncayo, Fernando	WATER IS LEAKING FROM UNDERNEATH THE DISHWASHING MACHINE								
	OLGA BUSTAMANTE - SNP MANAGER 589-9836								
<u>Alma Terrell</u>									
36811	Classroom				8/7/2008		26		\$0.00
Medium	Work In Progress	COACH			8/7/2008 4:37:21 PM				
Castillo, Carlos	INSTALL PORTABLE SCOREBOARD OUTSIDE OF BASEBALL FIELD.								
<u>Marylou Jimenez</u>									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
37137	Cafeteria (2005)	Cafeteria			8/18/2008		15		\$0.00
Medium	Work In Progress			8/18/2008 11:08:29 AM					
Moncayo, Fernando		Washing Machine is leaking water (underneath machine) - Left message with Fernando							
Alma Terrell		Olga Bustamante - SNP Manager 589-5332							
37180		Football Field			8/19/2008		14		\$0.00
Medium	Work In Progress			8/19/2008 8:13:59 AM					
Castillo, Carlos		As per Art Nunez ,one light is out at foot ball field.l							
Carlos Castillo									
37181		Hallway/Corridor			8/19/2008		14		\$0.00
Medium	Work In Progress			8/19/2008 8:22:54 AM					
Lara, Ralph		HAVEING PROBLEMS LOCKING -N- OPENING DOOR / MISSING PARTS DOOR BY COUNSELORS HALLWAY S.A.S.P. THANK YOU.							
Luis Murillo									
37228	Concession	Restroom (Boys)			8/20/2008		13		\$0.00
Medium	Work In Progress			8/20/2008 1:51:50 PM					
Villalobos, David		HANDI/CAP COMMODE WILL NOT FLUSH NEEDS TO BE REPAIR / FOOTBALL GAMES OBUT TO START A.S.P. THANKS.							
Luis Murillo									
37329					8/22/2008		11		\$0.00
Medium	Work In Progress			8/22/2008 9:21:24 AM					
Lara, Ralph		8/21/08. WE NEED TO FIX THE CABINET AND CLOSET IN ROOM 31 AND 9 (WE NEED KEYS). THI WORK ORDER IS FOR RAFAEL LARA.							
Manuel Prospero									
37338					8/22/2008		11		\$0.00
Medium	Work In Progress			8/22/2008 12:14:16 PM					
Ontiveros, Guadalupe		Remove the hanging fence pole by the wash out next to the soccer field. Extremely dangerous.							
Manuel Prospero									
37359	Applied Science				8/25/2008		8		\$0.00
Medium	Work In Progress			8/25/2008 12:49:37 PM					
Ontiveros, Guadalupe		backfill against perimeter sidewalks so that there is less than a 4" drop.							
Alfredo Holguin									
37386					8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 7:30:49 AM					
Ontiveros, Guadalupe		Pedestrian Gate on South side that goes to the Bluffs. - Install taller gate to prevent access through bottom of gate.							
Alfredo Holguin									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
37410					8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 3:52:14 PM					
Orozco, Danny	bucket truck for wed, thurs, friday or asap for pa GHS and pa STHS (please call Carlos Vigil for information)								
<u>Cora Ramirez</u>									
37518					8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 8:07:38 AM					
Ontiveros, Guadalupe	Install Signs in Area where the arroyo has eroded the banks and the fence has been damaged to read "Danger Keep Out"								
<u>Alfredo Holguin</u>									
37545					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:12 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37562					8/31/2008	9/21/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:18 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37629					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:39 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37630					8/31/2008	10/1/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:39 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37631					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:40 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 31 Work Orders			Avg. Age of WO's	27	Total for Santa Teresa HS			0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
35513	Library	Classroom			7/1/2008		63		\$0.00
Medium	Work In Progress				7/1/2008 3:55:25 PM				
Castillo, Carlos		cali, also mr.sanchez the art teacher wants a electrical panel on the wall for his computers.thank you.room #1							
Ismael Rodriguez									
35553					7/6/2008	7/12/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:19:21 AM				
Mijarez, Jaime		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
35599					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:19:35 AM				
Orozco, Danny		Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
35712					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress				7/6/2008 12:20:11 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36170	North Building	Custodial			7/24/2008		40		\$0.00
Medium	Work In Progress				7/24/2008 7:42:22 AM				
Gonzales, Angel		pete,the truck 39 needs a complete tune up i need to have it ready for the school year.thank you.							
Ismael Rodriguez									
36283					7/28/2008		36		\$0.00
Medium	Work In Progress				7/28/2008 1:30:00 PM				
Ambriz, Jose		I am going to need Joe Ambriz help to work on heat pump failures before school starts.							
Jaime Mijarez									
36313	South Building				7/29/2008		35		\$0.00
Medium	Work In Progress	office-Ricardo			7/29/2008 9:57:57 AM				
Lara, Ralph		Please replace desk drawers locks							
Lucia Almeraz									
36385	North Building				7/31/2008		33		\$0.00
Medium	Work In Progress				7/31/2008 8:30:11 AM				
Villalobos, David		Mech Room in N. Bldg - Insulation of new water heaters by contractors.							
David Villalobos									
36511					8/3/2008	8/9/2008	30		\$0.00
Medium	Work In Progress				8/3/2008 12:20:17 AM				
Mijarez, Jaime		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
36547					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:28 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36556					8/3/2008	8/11/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:31 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36572					8/3/2008	9/3/2008	30		\$0.00
Medium	Work In Progress			8/3/2008 12:20:36 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
36618	South Building	Classroom			8/4/2008		29		\$0.00
Medium	Work In Progress	Room 49		8/4/2008 3:44:35 PM					
Lara, Ralph	Key does not open main door. Need to come in through main door to access light switch								
Laura Parra									
36620	North Building	Office			8/4/2008		29		\$0.00
Medium	Work In Progress	Principals Office		8/4/2008 3:55:07 PM					
Castillo, Carlos	Please move light switch next to the door. In order to turn lights on Ms. Lovelace needs to walk around her desk								
Laura Parra									
36647	Gym (1997)	Gym			8/5/2008		28		\$0.00
Medium	Work In Progress	Girls Locker		8/5/2008 2:01:22 PM					
Mijarez, Jaime	Please replace lightbulb in girls locker room entrance								
Laura Parra									
36735	North Building	Classroom			8/7/2008		26		\$0.00
Medium	Work In Progress	Room 18		8/7/2008 7:46:29 AM					
Ambriz, Jose	Air conditioner not working								
Laura Parra									
36736	North Building	Classroom			8/7/2008		26		\$0.00
Medium	Work In Progress	Room 17		8/7/2008 7:48:16 AM					
Ambriz, Jose	Air conditioner blower is non stop-- it keeps blowing at all times								
Laura Parra									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
36757					8/7/2008		26		\$0.00
Medium	Work In Progress			8/7/2008 9:33:54 AM					
Ambriz, Jose	Please order condensation pump replacement. 40 ea. little giant low rise pumps cat#554200, vcc-20ul or 2ouls, 40 ea. 1/2" 90 deg. ells. Slipxthd fmle, 40 ea. SPRTB-6 24x24 metal grilles, 40 ft. 3/4"ODx 5/8"ID clear vinyl tube, 60 ea. 3 amp fuses, box of orange electrical wire nuts, and box of insulated female and male solderless terminals. I need this asap when old condensate pumps stop working i can't repair them anymore.								
Jaime Mijarez									
36769	North Building	Computer Lab			8/7/2008		26		\$0.00
Medium	Work In Progress	Room 48B		8/7/2008 12:28:10 PM					
Ambriz, Jose	Air Conditioner does not come on.								
Laura Parra									
36770	North Building	Classroom			8/7/2008		26		\$0.00
Medium	Work In Progress	Portable 2 B		8/7/2008 12:30:56 PM					
Castillo, Carlos	Flourescent lights need to be replaced- 8								
Laura Parra									
36882	North Building	Classroom			8/11/2008		22		\$0.00
Medium	Work In Progress	Room 32		8/11/2008 10:14:05 AM					
Lara, Ralph	Door key cylinder is damaged. Unable to open door								
Laura Parra									
36903	North Building	Classroom			8/11/2008		22		\$0.00
Medium	Work In Progress	Room 3A		8/11/2008 3:12:40 PM					
Mijarez, Jaime	1. Portable leaks when it rains.								
Laura Parra									
36914	North Building	Classroom			8/11/2008		22		\$0.00
Medium	Work In Progress	Room 9		8/11/2008 3:31:00 PM					
Lara, Ralph	Lock on closet cabinet is broken								
Laura Parra									
36984	South Building				8/12/2008		21		\$0.00
Medium	Work In Progress			8/12/2008 4:07:35 PM					
Mijarez, Jaime	Assistant Principal office - Paint before new VCT is installed - Check with Jesus Estrada.								
Alfredo Holguin									
37004	North Building	Classroom			8/13/2008		20		\$0.00
Medium	Work In Progress	Room 14		8/13/2008 9:27:04 AM					
Mijarez, Jaime	1. Multiple desks need to be adjusted.								
	2. Air conditioner not working set at 75 room is at 85								
Laura Parra									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
37140	South Building	Classroom			8/18/2008		15		\$0.00
Medium	Work In Progress	Room 37		8/18/2008 11:52:49 AM					
Mijarez, Jaime	1. Replace ceiling panels due to leak.								
	2. Water leaking from AC								
Laura Parra									
37161	North Building	Classroom			8/18/2008		15		\$0.00
Medium	Work In Progress	Room 23		8/18/2008 3:44:01 PM					
Ambriz, Jose	Air conditioner not working								
Laura Parra									
37276	Library	Library			8/21/2008		12		\$0.00
Medium	Work In Progress	library		8/21/2008 9:01:58 AM					
Castillo, Carlos	10 Lights are out.								
Laura Parra									
37278	Gym (1997)	Gym			8/21/2008		12		\$0.00
Medium	Work In Progress			8/21/2008 9:08:41 AM					
Munoz, Michael	Attn. Mike Munoz and Alfredo Holguin. Stout hardwood floor co. cut a hole on gym floor to dry up with a blower, but it is only getting worst. The gym floor is still lifting up.								
Jaime Mijarez									
37280					8/21/2008		12		\$0.00
Medium	Work In Progress			8/21/2008 9:19:49 AM					
Gonzales, Angel	Golf cart. Battery charger is not charging the batteries.								
Jaime Mijarez									
37290	North Building	Classroom			8/21/2008		12		\$0.00
Medium	Work In Progress	room 1		8/21/2008 1:17:47 PM					
Castillo, Carlos	Please install electrical outlet to connect all computers and printers.								
Laura Parra									
37395		Pump House			8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 2:54:40 PM					
Gonzales, Angel	Golf Cart - Does not hold charge. please repair								
Alfredo Holguin									
37477	South Building				8/28/2008		5		\$0.00
Medium	Work In Progress			8/28/2008 7:57:47 AM					
Ambriz, Jose	The entire South Bldg lost communication, showing critical link error in BCU. Need someone to come out a/s/a/p.								
Jose Ambriz									
37600					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:30 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

9/2/2008 11:25:24 AM

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Santa Teresa MS							
37601					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:30 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
37602					8/31/2008	10/1/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:30 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
37603					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:31 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 37 Work Orders		Avg. Age of WO's	25	Total for Santa Teresa MS				0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
35600					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:36 AM					
Orozco, Danny	Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
35710					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:11 AM					
Villalobos, David	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35734					7/7/2008		57		\$0.00
Medium	Work In Progress			7/7/2008 3:30:23 PM					
Lara, Ralph	WE NEED EXTRA KEY FROM LIBRARY								
Joel Herrera									
36955					8/12/2008		21		\$0.00
Medium	Work In Progress			8/12/2008 1:39:59 PM					
Lara, Ralph	MAIN ENTRANCE'S DOOR IT DOESN'T LOCK								
Joel Herrera									
36976					8/12/2008		21		\$0.00
Medium	Work In Progress			8/12/2008 3:50:10 PM					
Ontiveros, Guadalupe	WE NEED TO CLEANUP WEEDS AND TORITOS AT OUTSIDE SCHOOL AREA								
Joel Herrera									
37073					8/14/2008		19		\$0.00
Medium	Work In Progress			8/14/2008 2:22:33 PM					
Villalobos, David	WE NEED TO REPLACE WATER FAUCET AT CLASS ROOM #38								
Joel Herrera									
37075					8/14/2008		19		\$0.00
Medium	Work In Progress			8/14/2008 2:27:07 PM					
Castillo, Carlos	WE NEED TO REPLACE ALL LAMP ON GIRLS REST ROOM AT PORTABLE= A								
Joel Herrera									
37107					8/15/2008		18		\$0.00
Medium	Work In Progress	office, Room #31		8/15/2008 9:33:32 AM					
Lara, Ralph	Office needs a master key. Sped. teachers need keys for their file cabinets: Mrs. Holguin room #31 and Ms. Claudia Perez room #22 (IEP information)								
Jessica Lopez									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
37362					8/25/2008		8		\$0.00
Medium	Work In Progress			8/25/2008 2:14:46 PM					
Lara, Ralph	WE NEED REPLACE CLASS ROOMS DOORS THEY ARE TO RUSTING								
Joel Herrera									
37387					8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 8:08:25 AM					
Ontiveros, Guadalupe	LUPE WE NEED TO MOVE TWO SOCCER GOALS FROM THE U.E.S THANK YOU LUPE								
Joel Herrera									
37488	Main Building	Classroom			8/28/2008		5		\$0.00
Medium	Work In Progress	Room 28		8/28/2008 11:43:54 AM					
Lara, Ralph	Read 180 teacher (Ms. Gonzales) is requesting a key for the read 180 room TA20.								
Jessica Lopez									
37522					8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 9:04:07 AM					
Lara, Ralph	MS. ALCANTAR SHE NEEDS NEW KEY HER KEY BROKEN AT LIBRARY THANKYOU MANNY AND RAFA								
Joel Herrera									
37532					8/29/2008		4		\$0.00
Medium	Work In Progress			8/29/2008 3:04:00 PM					
Villalobos, David	TOILET IS LIKING AND THE WALL IS WET AT CLASS ROOM # 21								
Joel Herrera									
37589					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:26 AM					
Herrera, Joel	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
37590					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:26 AM					
Herrera, Joel	Monthly - Sunland Park ES A-1 Semiannual EVS - Refer to PM schedule details.								
Margret Villalobos									
37591					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:27 AM					
Herrera, Joel	Monthly - Sunland Park ES A-8 Quarterly HPW Unit - Refer to PM schedule details.								
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
37592					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:27 AM				
Herrera, Joel		Monthly - Sunland Park ES A-2 Quarterly H/C IREH - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
37593					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:27 AM				
Herrera, Joel		Monthly - Sunland Park ES A-1 Semiannual MCD - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
37594					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:28 AM				
Herrera, Joel		Monthly - Sunland Park ES A-1 Semiannual MCS2 - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
37595					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:28 AM				
Herrera, Joel		Monthly - Sunland Park ES A-6 Quarterly PUG - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
37596					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:28 AM				
Herrera, Joel		Monthly - Sunland Park ES A-5 Quarterly SS - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
37597					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:29 AM				
Herrera, Joel		Monthly - Sunland Park ES A-13 Quarterly WREH - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
37598					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:29 AM				
Herrera, Joel		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
37599					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:29 AM				
Herrera, Joel		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
Count: 24 Work Orders			Avg. Age of WO's 13			Total for Sunland Park ES	0		\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
37649					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:46 AM					
Quinones, Paul	Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details.								
Margret Villalobos									
37650					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:46 AM					
Quinones, Paul	Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.								
Margret Villalobos									
35601					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:36 AM					
Orozco, Danny	Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
35709					7/6/2008	8/6/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:20:10 AM					
Villalobos, David	Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36205					7/25/2008		39		\$0.00
Medium	Work In Progress			7/25/2008 8:27:04 AM					
Lozoya, Manny	CLASSS RM. 207 DOOR HANDLE,AND LOCK CYLINDER NOT OPENING DOOR PROPERLY. THANKS								
Paul Quinones									
36206					7/25/2008		39		\$0.00
Medium	Work In Progress			7/25/2008 8:37:07 AM					
Ontiveros, Guadalupe	REQUESTING PLAY GROUND SAND FOR BOTH PLAYGROUNDS UPPER LEVEL,AND PRE-K THANKS								
Paul Quinones									
36336					7/29/2008		35		\$0.00
Medium	Work In Progress			7/29/2008 3:57:08 PM					
Ronquillo, Ruben	BROKEN WALL WINDOW IN WING 1, LOCATION RM.107 WINDOW SIZE 2'X2' DOUBLE PANE GLASS WINDOW W/ TINT. THANKS								
Paul Quinones									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
36378					7/30/2008		34		\$0.00
Medium	Work In Progress			7/30/2008 4:19:55 PM					
Lozoya, Manny	DOOR IN WING B ELSOL HALL WAY.DURING FIRE DRILL IN THE MORNING 7-30-08.RIGHT SIDE DOOR WOULD NOT CLOSE DURING DRILL.								
Paul Quinones									
37422					8/26/2008		7		\$0.00
Medium	Work In Progress			8/26/2008 4:19:28 PM					
Ontiveros, Joe	HOSE BIBB ON WALL NEXT TO UPPER PLAY GROUND WATER LEAKING,BROKEN HANDLE.								
Paul Quinones									
37643					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:44 AM					
Quinones, Paul	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
37644					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:44 AM					
Quinones, Paul	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
37645					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:44 AM					
Quinones, Paul	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
37646					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:45 AM					
Quinones, Paul	Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM schedule details.								
Margret Villalobos									
37647					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:45 AM					
Quinones, Paul	Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM schedule details.								
Margret Villalobos									
37648					8/31/2008		2		\$0.00
Medium	Work In Progress			8/31/2008 12:25:45 AM					
Quinones, Paul	Monthly - Sunrise ES A-1 Semiannual MCS - Refer to PM schedule details.								
Margret Villalobos									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Sunrise ES							
37655					8/31/2008		2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:47 AM				
Jacquez, Ricardo	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									
Count: 16 Work Orders		Avg. Age of WO's 18		Total for Sunrise ES				0	\$0.00

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
35602					7/6/2008	7/27/2008	58		\$0.00
Medium	Work In Progress			7/6/2008 12:19:36 AM					
Orozco, Danny	Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
36103					7/22/2008		42		\$0.00
Medium	Work In Progress			7/22/2008 8:39:31 AM					
Sotelo, Enrique	NEED TO REPLACE 4 EXIT SIGNS								
Danny Miranda									
36104					7/22/2008		42		\$0.00
Medium	Work In Progress			7/22/2008 8:40:50 AM					
Sotelo, Enrique	NEED TO REPLACE 6 EMER. LIGHTS								
Danny Miranda									
36175	Main Building	Classroom			7/24/2008		40		\$0.00
Medium	Work In Progress			7/24/2008 11:22:30 AM					
Ronquillo, Ruben	NEED TO HAVE A COVER PUT OVER THE FIRE ALARM IN THE SPECIAL NEEDS CLASSROOM. ROOM101- PER DANNY MIRANDA								
Debra Facio									
36221					7/25/2008		39		\$0.00
Medium	Work In Progress			7/25/2008 11:32:11 AM					
Lozoya, Manny	NEED A NEW DOOR CLOSER IN RM. 308, (LCN 4041)								
Danny Miranda									
36771		Cafeteria			8/7/2008		26		\$0.00
Medium	Work In Progress			8/7/2008 12:50:26 PM					
Orozco, Danny	WASHING MACHINE IS OUT OF ORDER								
	LAURA BENAVIDEZ - SNP MANAGER 2332945								
Alma Terrell									
36772		Cafeteria			8/7/2008		26		\$0.00
Medium	Work In Progress			8/7/2008 12:51:55 PM					
Orozco, Danny	NEEDS A DOOR BELL TO BE INSTALLED TO BACK DOOR								
	LAURA BENAVIDEZ - SNP MANAGER 233-2945								
Alma Terrell									
37195					8/19/2008		14		\$0.00
Medium	Work In Progress			8/19/2008 1:25:18 PM					
Gonzales, Angel	NEED A LAWNMOWER FOR VADO ELEM. (THIS WEEK)								
Danny Miranda									

725 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
37434					8/27/2008		6		\$0.00
Medium	Work In Progress				8/27/2008 8:53:14 AM				
Gonzales, Angel		NEED TRACTOR MOWER TO CUT WEEDS ALONG OUTSIDE ROAD SIDE FENCE LINE (LUPE SEE MIKE)							
Danny Miranda									
37557					8/31/2008	9/6/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:16 AM				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
37558					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:16 AM				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
37559					8/31/2008	9/8/2008	2		\$0.00
Medium	Work In Progress				8/31/2008 12:25:17 AM				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
Count: 12 Work Orders			Avg. Age of WO's 25			Total for Vado ES	0		\$0.00
Count: 725 Work Orders			Avg. Age of WO's 25			Grand Total	31		\$982.59