

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Alma Del Valle Daycare							
41338					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:16 AM				
Trujillo, Gilbert	Monthly - QRTLY BLDG INSP REPORTS (ADV) - Refer to PM schedule details.								
Jesus Estrada									
Count: 1 Work Orders		Avg. Age of WO's	3		Total for Alma Del Valle Daycare			0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
35695					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress				7/6/2008 12:20:06 AM				
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
35986	Chapter I	Office			7/16/2008		182		\$0.00
Medium	Work In Progress				7/16/2008 9:38:50 AM				
Lozoya, Manny		chapter blg repair pannic bar a.s.a.p							
Hector Villalobos									
36176	Cafeteria	Cafeteria			7/24/2008		174		\$0.00
Medium	Work In Progress				7/24/2008 11:26:39 AM				
Ontiveros, Guadalupe		remove old tree next to cafeteria,health issue as per ms.marquez							
David Vega									
36641	Drug Free Bldg.				8/5/2008		162		\$0.00
Medium	Work In Progress				8/5/2008 10:48:59 AM				
Sotelo, Enrique		please install a power strip for radios. please see irene for location.thxs							
Michael Munoz									
36672					8/6/2008		161		\$0.00
Medium	Work In Progress				8/6/2008 8:48:17 AM				
Lozoya, Manny		Primary blg storage need to charge lock							
Hector Villalobos									
37105	Chapter I	Office			8/15/2008		152		\$0.00
Medium	Work In Progress				8/15/2008 8:46:10 AM				
Lozoya, Manny		chapter blg o.t.p room needs 4 keys k50							
Hector Villalobos									
37170	Nurse Building				8/19/2008		148		\$0.00
Medium	Work In Progress				8/19/2008 7:36:40 AM				
Lozoya, Manny		need to replace exit door							
Hector Villalobos									
37287	Cafeteria	Cafeteria			8/21/2008		146		\$0.00
Medium	Work In Progress				8/21/2008 11:49:08 AM				
Orozco, Danny		SEAL TO WALK-IN REFRIGERATOR IS ALL TORN AND MOLDY, SEAL NEEDS TO BE REPLACED							
		BECKY SAENZ - 882-3507 (K-3 CAFETERIA)							
Alma Terrell									
37450	Original Main	Classroom			8/27/2008		140		\$0.00
Medium	Work In Progress	201			8/27/2008 12:39:44 PM				
Lozoya, Manny		Need an additional key.....							
Loraine Gandara									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
37451	Original Main	Classroom			8/27/2008		140		\$0.00
Medium	Work In Progress	201		8/27/2008 12:40:05 PM					
Lozoya, Manny		Need an additional key.....							
Loraine Gandara									
37452	Original Main	Classroom			8/27/2008		140		\$0.00
Medium	Work In Progress	202		8/27/2008 12:41:04 PM					
Lozoya, Manny		Need an additional key.....							
Loraine Gandara									
37942					9/9/2008		127		\$0.00
Medium	Work In Progress			9/9/2008 10:36:36 AM					
Lozoya, Manny		NEED 2 ADDITIONAL "H" KEY.....							
Loraine Gandara									
37962	Original Main				9/9/2008		127		\$0.00
Medium	Work In Progress	110		9/9/2008 2:44:04 PM					
Lozoya, Manny		NEED AN ADDITIONAL KEY FOR RM 110 KEY H11							
Loraine Gandara									
37994	Original Main	Office			9/10/2008		126		\$0.00
Medium	Work In Progress			9/10/2008 2:17:01 PM					
Gonzalez, Salvador		old main bld room 112 p.t.o needs window gurad							
Hector Villalobos									
38031	Original Main				9/11/2008		125		\$0.00
Medium	Work In Progress	POA OFFICE		9/11/2008 3:06:22 PM					
Lozoya, Manny		NEED A LOCK AND KEY FOR CABINETS.....							
Loraine Gandara									
38157	Original Main	Hallway/Corridor			9/17/2008		119		\$0.00
Medium	Work In Progress			9/17/2008 7:36:41 AM					
Lozoya, Manny		old main blg exit door hallway pannic bar will not lock .replace with new pannic bar. A.S.A.P							
Hector Villalobos									
38270					9/19/2008		117		\$0.00
Medium	Work In Progress	Corina		9/19/2008 4:08:26 PM					
Lozoya, Manny		Please install new locks on 2 file cabinets Tag# F00742 and the other one doesn't have a label. In Corina Valdespino's officce she is at the Village							
Lucia Almeraz									
38320	Main Building	Library			9/22/2008		114		\$0.00
Medium	Work In Progress			9/22/2008 2:54:34 PM					
Carrasco, Danny		need 5 boxes of u-bent fluorescent lamps. for library							
Hector Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
39028		Athletic Field			10/8/2008		98		\$0.00
Medium	Work In Progress			10/8/2008 10:07:55 AM					
Appelzoller, Fred		Outside water fountains mounted on concrete block columns located east of the Old Main Cafeteria are not working. REPAIR							
Alfredo Holguin									
39172	Chapter I	Classroom			10/13/2008		93		\$0.00
Medium	Work In Progress			10/13/2008 9:04:29 AM					
Lozoya, Manny		Chapter blg music room needs deadbolts on two doors							
Hector Villalobos									
39407					10/23/2008		83		\$0.00
Medium	Work In Progress			10/23/2008 8:36:43 AM					
Gonzales, Angel		truck 153 thermostat is not working on heater							
Hector Villalobos									
39592					10/30/2008		76		\$0.00
Medium	Work In Progress			10/30/2008 7:34:13 AM					
Lozoya, Manny		old cafeteria gate and drug free gate need a pad lock H1							
Hector Villalobos									
39847	Main Building	Custodial			11/5/2008		70		\$0.00
Medium	Work In Progress			11/5/2008 9:38:37 AM					
Lozoya, Manny		custodial office does not lock							
David Vega									
39848	Main Building	Custodial			11/5/2008		70		\$0.00
Medium	Work In Progress			11/5/2008 9:40:28 AM					
Lozoya, Manny		need to replace k master key							
David Vega									
39957					11/9/2008	11/25/2008	66		\$0.00
Medium	Work In Progress			11/9/2008 12:28:34 AM					
Villalobos, Hector		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									
39973					11/10/2008	11/16/2008	65		\$0.00
Medium	Work In Progress			11/10/2008 12:19:34					
Villalobos, Hector		Monthly - Anthony ES A7 (Rooftop Unit)(Monthly) - Refer to PM schedule details.							
Margret Villalobos									
40015	Office				11/12/2008		63		\$0.00
Medium	Work In Progress			11/12/2008 7:22:02 AM					
Lozoya, Manny		On track Pre-k code came out of lock eixt door . secure door by today							
Hector Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
40016	Cafeteria	Cafeteria			11/12/2008		63		\$0.00
Medium	Work In Progress				11/12/2008 7:52:56 AM				
Sotelo, Enrique		please install light fixture in bathroom, old main cafeteria where remodeling is being done. thxs							
Michael Munoz									
40021	Original Main	Classroom			11/12/2008		63		\$0.00
Medium	Work In Progress				11/12/2008 9:29:47 AM				
Lozoya, Manny		old main blg room 101 door will not lock							
Hector Villalobos									
40041	Office	Portables			11/13/2008		62		\$0.00
Medium	Work In Progress				11/13/2008 7:36:52 AM				
Lozoya, Manny		Pt on track -Prek eixt door will not lock							
Hector Villalobos									
40083		Portables			11/14/2008		61		\$0.00
Medium	Work In Progress				11/14/2008 8:43:39 AM				
Appelzoller, Fred		pt 219 and 220 water heater is leaking							
Hector Villalobos									
40310					11/24/2008		51		\$0.00
Medium	Work In Progress				11/24/2008 10:29:21				
Lozoya, Manny		NEED TO PUT IN NEW DOOR & FRAME IN R.R. ANTHONY ELEM. CAFETERIA							
Danny Miranda									
40328	Main Building	Cafeteria			11/25/2008		50		\$0.00
Medium	Work In Progress				11/25/2008 7:32:53 AM				
Orozco, Danny		Mid cafettria water heater is not working							
Hector Villalobos									
40616	Main Building	Classroom			12/5/2008		40		\$0.00
Medium	Work In Progress				12/5/2008 12:36:05 PM				
Ronquillo, Ruben		missing 2 10 lbs and 9 5lbs fire extinguishers							
Hector Villalobos									
41029					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:31 AM				
Villalobos, Hector		Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
41046					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:40 AM				
Villalobos, Hector		Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
41093					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:57 AM					
Villalobos, Hector		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
41095					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:58 AM					
Villalobos, Hector		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
41163	Original Main	Athletic Field			1/5/2009		9		\$0.00
Medium	Work In Progress			1/5/2009 2:35:27 PM					
Holguin, Alfredo		Canopy tore in pieces by wind need to replace old main blg side palyground equipment							
Hector Villalobos									
41265		Athletic Field			1/8/2009		6		\$0.00
Medium	Work In Progress			1/8/2009 9:09:39 AM					
Ronquillo, Ruben		mild blg playground equipment slide needs to be replaced. Before someone cut themselves.							
Hector Villalobos									
41339					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:17 AM					
Vega, David		Monthly - QRTLY BLDG INSP REPORT (AE) - Refer to PM schedule details.							
Jesus Estrada									
41362					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:25 AM					
Villalobos, Hector		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									
41387					1/12/2009	1/18/2009	2		\$0.00
Medium	Work In Progress			1/12/2009 12:17:46 AM					
Villalobos, Hector		Monthly - Anthony ES A7 (Rooftop Unit)(Monthly) - Refer to PM schedule details.							
Margret Villalobos									
41473	Main Building	Custodial			1/14/2009		0		\$0.00
Medium	Work In Progress			1/14/2009 7:10:53 AM					
Carbajal, Jimmy		vaccum cleaner needs repair							
David Vega									
Count: 44 Work Orders		Avg. Age of WO's 85		Total for Anthony ES				0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Berino ES								
35696					7/6/2008	8/6/2008	192		\$0.00	
Medium	Work In Progress				7/6/2008 12:20:06 AM					
Villalobos, David		Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
35767					7/7/2008		191		\$0.00	
High	Work In Progress				7/8/2008 3:20:01 PM					
Duran, Adan		Tag graffiti all over campus. Dep. LGarcia 114 Case# 2008-06493								
Jimmy Cortez										
35915					7/13/2008	7/29/2008	185		\$0.00	
Medium	Work In Progress				7/13/2008 12:18:09 AM					
Duran, Adan		Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos										
36296					7/28/2008		170		\$0.00	
Medium	Work In Progress				7/28/2008 3:37:40 PM					
Lozoya, Manny		MR MANNY LOZOYA SIR IN PORTABLE 148 THE FILE CABINET GOT LOCK BY MASTAKE AND THEY DONT HAVE A KEY NEED TO REMOVE CYLINDER AND REPLACE WITH NEW ONE THAT HAS A KEY THANK YOU SIR AND GOD BLESS								
Adan Duran										
36707					8/6/2008		161		\$0.00	
Medium	Work In Progress				8/6/2008 3:31:30 PM					
Ontiveros, Guadalupe		MR LUPE ONTIVEROS SIR WE HAVE ABOUT 8 GALVNIZE PIPES 21 FT LOG THAT NEED TO BE PICKED UP AND HAUL OFF TO PPD YARD ALSO BIG BLOCKS OF CONCRETE THANK YOU SIR AND GOD BLESS								
Adan Duran										
36845					8/8/2008		159		\$0.00	
Medium	Work In Progress	Mobile Home			8/8/2008 3:52:51 PM					
Sotelo, Enrique		Need to install utility hook-up for mobile home.								
Michael Munoz										
36850					8/10/2008	8/26/2008	157		\$0.00	
Medium	Work In Progress				8/10/2008 12:19:42 AM					
Duran, Adan		Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos										

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
36879					8/11/2008		156		\$0.00
Medium	Work In Progress			8/11/2008 9:01:25 AM					
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR PER MR VALTIERRA HE WOULD LIKE THE SCHOOL CLEAN TO MANNY WEEDS PONDING AREA NEEDS CLEAN IN FRONT AND BACK AROUND PORTABLES ALONE FENCE IN FRONT OUTSIDE AND IN SIDE THANK YOU SIR								
Adan Duran									
37210					8/19/2008		148		\$0.00
Medium	Work In Progress			8/19/2008 3:32:05 PM					
Solis, Lorenzo	MR LORENZO SOLIS SIR PORTABLE 139 HAS TWO AC WINDOW TYPE THE CLAM IS THAT ITS NOT COOLING ENOUGH IT USE TO BE MUSIC ROOM BUT ITS A CLASS ROOM NOW WOULD LIKE A BIGGER UNIT THANK YOU SIR AND GOD BLESS								
Adan Duran									
37769		Portables			9/4/2008		132		\$0.00
Medium	Work In Progress			9/4/2008 8:09:26 AM					
Sotelo, Enrique Lorenzo Solis	Please provide electrical connection to 3 Ton Bard unit.								
37866					9/7/2008	9/23/2008	129		\$0.00
Medium	Work In Progress			9/7/2008 12:27:28 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
38004					9/10/2008		126		\$0.00
Medium	Work In Progress			9/10/2008 3:33:58 PM					
Lozoya, Manny	MR MANNY LOZOYA SIR WE ARE HAVE PROBLEMS WITH DOOR PORTABLE 135 OLD DOOR WILL NEED SOME HAREWARE WILL NOT LOCK KEEPS BLOWING OPEN WHEN WINDY THANK YOU SIR GOD BLESS								
Adan Duran									
38128					9/16/2008		120		\$0.00
Medium	Work In Progress			9/16/2008 10:30:21 AM					
Sotelo, Enrique	Emer. Light need replacing at west entrance and Custodial room.								
Adan Duran									
38159					9/17/2008		119		\$0.00
Medium	Work In Progress			9/17/2008 7:52:03 AM					
Lozoya, Manny	MR MANNY LOZOYA SIR WE NEED TO CHANGE OUTSIDE GATE PAD LOCKS SOMEONE IS OPENING OUR GATES CHANGE LOCKS AS SAME AS ENTRANCE DOOR THANK YOU SIR								
Adan Duran									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
38442	Main Building				9/25/2008		111		\$0.00
Medium	Work In Progress			9/25/2008 3:59:37 PM					
Duran, Adan	Restrooms next to multipurpose room- sand entrance doors and reseal								
<u>Alfredo Holguin</u>									
38444	Portables				9/25/2008		111		\$0.00
Medium	Work In Progress			9/25/2008 4:06:10 PM					
Duran, Adan	Last two Portables on south row east side - re-install blocks under beams.								
<u>Alfredo Holguin</u>									
38502					9/29/2008		107		\$0.00
Medium	Work In Progress	Mobile Home		9/29/2008 1:34:42 PM					
Duran, Adan	Need to remove fence on October 4, 2008 1st thing in the morning.								
<u>Michael Munoz</u>									
38529					9/30/2008		106		\$0.00
Medium	Work In Progress			9/30/2008 12:25:59 AM					
Duran, Adan	Monthly - Berino ES A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38699					10/3/2008		103		\$0.00
Medium	Work In Progress	Mobile Home		10/3/2008 10:42:41 AM					
Lozoya, Manny	As per Alfredo, need a gate key for Guadalupe Quinones the new mobile home occupant at Berino. The mobile home will be placed at the school this weekend.								
<u>Alfredo Holguin</u>									
38737					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:47 AM					
Duran, Adan	Yearly - Berino ES I4 (Fan Coil)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38738					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:48 AM					
Duran, Adan	Yearly - Berino ES R9 (Radiator Hot)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38739					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:48 AM					
Duran, Adan	Yearly - Berino ES H6 (Furnace Gas)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
38740					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:48 AM					
Duran, Adan	Yearly - Berino ES U2 (Heat Gas)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
38778					10/5/2008	10/26/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:02 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
39148					10/12/2008	10/28/2008	94		\$0.00
Medium	Work In Progress			10/12/2008 12:20:57					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
39479					10/24/2008		82		\$0.00
Medium	Work In Progress			10/24/2008 3:26:04 PM					
Sotelo, Enrique	MR ENRIQUE SOTELO SIR EMERGENCY LIGHT FALL OFF WALL IN CAFETERIA NEED TO REPLACE BROKEN BURN ELEMENTS THE ONE IN CUSTODIAL ROOM ALSO THANK YOU SIR								
Adan Duran									
39958					11/9/2008	11/25/2008	66		\$0.00
Medium	Work In Progress			11/9/2008 12:28:34 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
40073					11/13/2008		62		\$0.00
Medium	Work In Progress			11/13/2008 4:10:00 PM					
Lozoya, Manny	MR MANNY LOZOYA SIR WE NEED TO REPLACEMENT KEY THE TRASH MAN HAS B KEY BUT WE CHANGE GATE LOCKS TO B-1 HE COULD NOT GET IN MONDAY MUNCHO TRASH THANK YOU SIR								
Adan Duran									
40137					11/17/2008		58		\$0.00
High	Work In Progress			11/17/2008 11:07:56					
Lozoya, Manny	manny, you changed the core to the gates from a b to a b-1. the thrash guy does not have access. please make a new key for them and give to adan. he has the b for you.								
Michael Munoz									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
40359					11/30/2008	12/6/2008	45		\$0.00
Medium	Work In Progress			11/30/2008 12:23:27					
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
George ZZ Gabaldon									
40360					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress			11/30/2008 12:23:28					
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40361					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress			11/30/2008 12:23:28					
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40507					12/2/2008		43		\$0.00
Medium	Work In Progress			12/2/2008 4:09:15 PM					
Ontiveros, Guadalupe	Need to top dress playing field.								
Michael Munoz									
40565	Main Building				12/3/2008		42		\$0.00
Medium	Work In Progress			12/3/2008 4:55:34 PM					
Duran, Adan	Courtyard area between classroom wings - Cut and remove weeds and trim trees to allow cameras to view windows								
Alfredo Holguin									
40642					12/7/2008	12/23/2008	38		\$0.00
Medium	Work In Progress			12/7/2008 12:16:12 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
George ZZ Gabaldon									
40921					12/16/2008		29		\$0.00
Medium	Work In Progress			12/16/2008 3:45:59 PM					
Solis, Lorenzo	MR LORENZO SOLIS SIR THE HEATING UNIT IN THE GYM WILL NOT KICK ON NEED TO CHECK THANK YOU AND GOD BLESS								
Adan Duran									
40997					12/18/2008		27		\$0.00
High	Work In Progress			12/18/2008 4:24:02 PM					
Miranda, Danny	as epr our conversation, the wall to the entrance of the boys restroom on the east wing has been kicked in. please replace w/ durock as discussed. if other areas at site need the same please take of them. Thxs								
Michael Munoz									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
41030					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:32 AM					
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
41047					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:40 AM					
Duran, Adan	Monthly - Berino ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
41069					1/4/2009	1/25/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:49 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
41094					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:58 AM					
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41097					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:59 AM					
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41153					1/5/2009		9		\$0.00
Medium	Work In Progress			1/5/2009 8:18:40 AM					
Lozoya, Manny	MR MANNY LOZOYA HAPPY NEW YEAR AND GOD BLESS MR LOZOYS SIR WE HAVE A BROKEN KEY IN GATE LOCK WEST GATE NEED TO REPLACE WILL NEED TO LOCK TO NIGHT THANK YOU SIR								
Adan Duran									
41286					1/8/2009		6		\$0.00
Medium	Work In Progress			1/8/2009 3:43:24 PM					
Appelzoller, Fred	MR FRED APPELOZLLER SIR THE REST ROOM PORTABLE 153 IS PLUG TRIED THE OGER BUT DID NOT WORK WILL NEED THE LONG CABLE THANK YOU SIR								
Adan Duran									
41340					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:17 AM					
Cortez, Jimmy	Monthly - QRTLY BLDG INSP REPORTS (BE) - Refer to PM schedule details.								
Jesus Estrada									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Berino ES							
41363					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress		1/11/2009 12:17:26 AM						
Duran, Adan		Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									
Count: 46 Work Orders		Avg. Age of WO's		86	Total for Berino ES			0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral ES								
35694					7/6/2008	8/6/2008	192		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:05 AM						
Villalobos, David		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
36075		Office			7/18/2008		180		\$0.00	
Medium	Work In Progress	PRE-K		7/18/2008 4:55:16 PM						
Vargas, Juan		AS PER ANN STEINHOFF-THERE IS MOLD ON THE CEILING IN THE WORK ROOM AT THE PRE-K								
Mary Garcia										
36214		Classroom			7/25/2008		173		\$0.00	
Medium	Work In Progress			7/25/2008 10:15:35 AM						
Lozoya, Manny		need,to,check,all,doors,locks,keys,do,not,open,doors,locks.								
Daniel Ramirez										
36314					7/29/2008		169		\$0.00	
Medium	Work In Progress	Room#208-		7/29/2008 10:16:15 AM						
Lozoya, Manny		Please install new locks to file cabinet -social worker will leave a sticky on the file cabinet								
Lucia Almeraz										
36581					8/4/2008		163		\$0.00	
Medium	Work In Progress			8/4/2008 8:49:37 AM						
Vargas, Juan		barracas 406-408-410-412-414-416-418 need change master cools now have 3800 is to small need replace for 4500				Routed 8/11 - Assign to JC asp our conversation he needs to give units a good PM, where installed last year. Humidity is @ 70 and m/c swamps do not work well. m.munoz				
Juan Vargas										
36675		Office			8/6/2008		161		\$0.00	
Medium	Work In Progress			8/6/2008 9:42:24 AM						
Lozoya, Manny		need,to,fix,door,lock,mrs,baderd,officef								
Daniel Ramirez										
36737		Office			8/7/2008		160		\$0.00	
Medium	Work In Progress	front office		8/7/2008 7:51:44 AM						
Lozoya, Manny		secretary's door locks and can't open, need door to be able to lock only when used with the key stays locked and when there is a fire drill door needs to be closed but not locked and locks automatically.Administrative Intern's room also having trouble with lock door cannot open very hard custodians are having a difficult time opening. Please see front office								
Jennifer Corral										
36738					8/7/2008		160		\$0.00	
Medium	Work In Progress			8/7/2008 7:59:01 AM						
Lozoya, Manny		chuy y mando nesecitan que les cambies las llaves por que batallan para abrir las puertas								
Juan Vargas										
1/14/2009 11:38:12 AM										

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
36773					8/7/2008		160		\$0.00
Medium	Work In Progress			8/7/2008 1:07:27 PM					
Ontiveros, Joe	kitchen r.room need replace toilet is broke								
Juan Vargas									
37005		Classroom			8/13/2008		154		\$0.00
Medium	Work In Progress	whole school		8/13/2008 10:45:16 AM					
Lozoya, Manny	work order to redo keys for custodians, can't open the doors to the classrooms. As per Manny Request.								
Jennifer Corral									
37055	2001 Classroom				8/14/2008		153		\$0.00
Medium	Work In Progress			8/14/2008 10:11:15 AM					
Vargas, Juan	need to add large rocks or cobblestones in areas where roof gutters are causing erosion								
Alfredo Holguin									
37056					8/14/2008		153		\$0.00
Medium	Work In Progress			8/14/2008 10:14:39 AM					
Vargas, Juan	All sidewalks with more than 4" drop need to have fill dirt added - Call Mike or Alfredo when work is complete								
Alfredo Holguin									
37057					8/14/2008		153		\$0.00
Medium	Work In Progress			8/14/2008 10:17:19 AM					
Vargas, Juan	Sand need to be leveled in fall areas of all playground structures on site.								
Alfredo Holguin									
37135	West Central				8/18/2008		149		\$0.00
Medium	Work In Progress			8/18/2008 9:11:53 AM					
Vargas, Juan	new doors are being installed in the esat and west barrack. please order paint so you can paint doors. thxs								
Michael Munoz									
37222		Custodial			8/20/2008		147		\$0.00
Medium	Work In Progress	master		8/20/2008 9:40:22 AM					
Lozoya, Manny	need another key to be done for substitute custodian. One of the keys did not open the doors. Please see Danny head custodian for more explanation								
Jennifer Corral									
37990		Cafeteria			9/10/2008		126		\$0.00
Medium	Work In Progress			9/10/2008 1:49:03 PM					
Orozco, Danny	Side of grease trap caving in.								
Michael Munoz									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
37993					9/10/2008		126		\$0.00
Medium	Work In Progress			9/10/2008 2:16:48 PM					
Lozoya, Manny	Monday, September 15, 2008 @ 10:00, need to inventory J. Vargas keys to be transferred to Guillermo Hernandez.								
<u>Michael Munoz</u>									
38027		Athletic Field			9/11/2008		125		\$0.00
Medium	Work In Progress			9/11/2008 2:05:24 PM					
Ontiveros, Guadalupe	Lower Grades playground equipment located between classroom wings - Re layout plastic borders so they are around the remaining playground (slide) structure.								
<u>Alfredo Holguin</u>									
38240					9/18/2008		118		\$0.00
Medium	Work In Progress			9/18/2008 3:45:24 PM					
Lozoya, Manny	Would you please issue a key for me to use on the gate next to Chap Midd, they use the gate for the fire drill and the keys that I got dont have one. thank you								
<u>Guillermo Hernandez</u>									
38785					10/5/2008	10/26/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:05 AM					
Orozco, Danny	Monthly - Chaparral ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39939	E. Building	Classroom			11/7/2008		68		\$0.00
Medium	Work In Progress	509		11/7/2008 10:55:11 AM					
Lozoya, Manny	need cabinet to be relocked. Need new lock for it and key. Teacher for Visually impaired will be storing important and expensive merchandise in there and needs for it to be safe. See Ms. Kayce speech Teacher								
<u>Jennifer Corral</u>									
40051		Classroom			11/13/2008		62		\$0.00
Medium	Work In Progress	512		11/13/2008 12:36:13					
Lozoya, Manny	need cabinet in rm to place belongings very expensive but does not have a key. So would like it to be redone and get a key for it. See Ms. Kayce SLP Speech Teacher. As soon as possible								
<u>Jennifer Corral</u>									
40238					11/19/2008		56		\$0.00
Medium	Work In Progress			11/19/2008 3:45:57 PM					
Ontiveros, Joe	would you please replace lavatory faucets in the girls restroom on the north hallway. Thank you								
<u>Guillermo Hernandez</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
40239					11/19/2008		56		\$0.00
Medium	Work In Progress			11/19/2008 3:48:17 PM					
Lozoya, Manny		would you please check the automatic door opener for handicap on the norh side of the main hallway. Thank you							
Guillermo Hernandez									
40441					11/30/2008		45		\$0.00
Medium	Work In Progress			11/30/2008 12:23:55					
Jacquez, Ricardo		Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.							
George ZZ Gabaldon									
40450		Classroom			12/1/2008		44		\$0.00
Medium	Work In Progress	403		12/1/2008 8:05:14 AM					
Lozoya, Manny		Teacher lost key and needs a replacement. See Ms. DeGeeter							
Jennifer Corral									
40604					12/4/2008		41		\$0.00
Medium	Work In Progress			12/4/2008 4:46:38 PM					
Sotelo, Enrique		Need assistance to replace two outside light fixtures of portable 34DW (#402 and #404)							
Guillermo Hernandez									
40796		Cafeteria			12/11/2008		34		\$0.00
Medium	Work In Progress			12/11/2008 1:44:34 PM					
Orozco, Danny		IT'S LEAKING ALOT OF WATER FROM CEILING (INSIDE WALK-IN REFRIGERATOR)							
		ESTHER CISNEROS - SNP MANAGER 824-0048							
Alma Terrell									
41048					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:40 AM					
Hernandez, Guillermo		Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
41096					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:59 AM					
Hernandez, Guillermo		Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
41136					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:17 AM					
Hernandez, Guillermo		Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
41137					1/4/2009		10		\$0.00
Medium	Work In Progress				1/4/2009 12:19:17 AM				
Jacquez, Ricardo		Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.							
Margret Villalobos									
41343					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:18 AM				
Ramirez, Daniel		Monthly - QRTLY BLDG INSP REPORT (CM) - Refer to PM schedule details.							
Jesus Estrada									
41364					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:26 AM				
Hernandez, Guillermo		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
41418		Custodial			1/13/2009		1		\$0.00
Medium	Work In Progress				1/13/2009 7:28:20 AM				
Carbajal, Jimmy		NEED,TO,FIX,VACCUM,CLEANER,BROKEN							
Daniel Ramirez									
41467					1/13/2009		1		\$0.00
Medium	Work In Progress				1/13/2009 4:03:57 PM				
Solis, Lorenzo		Need assistance to replace an exhaust fan in the Boy's restroom by the nurse office. Thank you							
Guillermo Hernandez									
Count: 36 Work Orders		Avg. Age of WO's 97		Total for Chaparral ES				0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral HS								
35714					7/6/2008	8/6/2008	192		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:12 AM						
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
35869					7/11/2008		187		\$0.00	
Medium	Work In Progress			7/11/2008 9:39:33 AM						
Lozoya, Manny		RE-KEY LEFT UPPER AND LOWER CABINETS FOR STORAGE LOCATED BEHIND THE RECEPTIONST FOR THE REGISTRAR (HEMPHILL)								
Rosa Quezada										
35870		Office			7/11/2008		187		\$0.00	
Medium	Work In Progress	FRONT OFFICE		7/11/2008 9:41:05 AM						
Lozoya, Manny		RE-KEY RIGHT UPPER AND LOWER CABINETS FOR STORAGE LOCATED BEHIND THE RECEPTIONIST (GARCIA)								
Rosa Quezada										
35970					7/15/2008		183		\$0.00	
Medium	Work In Progress	Mobile Home		7/15/2008 2:56:29 PM						
Ontiveros, Joe		SEPTIC AND WATER SYSTEMS NEED TO BE TIED IN FOR AN ON SITE MOBILE HOME.								
Eddie Baeza										
36093		Classroom			7/21/2008		177		\$0.00	
Medium	Work In Progress	D-7		7/21/2008 3:47:12 PM						
Lozoya, Manny		NEED 1G032 SPARE KEY FOR FLAMABLE CABINET IN D-7(QUEZADA)								
Rosa Quezada										
36579		Classroom			8/4/2008		163		\$0.00	
Medium	Work In Progress	F Wing - Rm. 5		8/4/2008 8:18:45 AM						
Lozoya, Manny		Need a CH73 key for classroom F-5. (Paul H. Geiger)								
Guadalupe Gonzalez										
36593		Classroom			8/4/2008		163		\$0.00	
Medium	Work In Progress	R Wing - Rm. 1		8/4/2008 1:55:06 PM						
Lozoya, Manny		Due to high security requirements, the control room door key must be cored the same as the storage room door. It is to be "off master" like the storage room.								
Guadalupe Gonzalez										
36606	B-Wing	Classroom			8/4/2008		163		\$0.00	
Medium	Work In Progress	Rm B-3		8/4/2008 3:13:25 PM						
Lozoya, Manny		Need keys D274AR & D273AR. (Emmanuel Okefor)								
Guadalupe Gonzalez										

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
36888					8/11/2008		156		\$0.00
Medium	Work In Progress			8/11/2008 1:32:00 PM					
Ontiveros, Joe		FAUCETS IN D-WING SCIENCE LABS NEED REPAIR AND REPLACEMENT.							
Eddie Baeza									
36959	A-Wing	Office			8/12/2008		155		\$0.00
Medium	Work In Progress			8/12/2008 3:11:57 PM					
Lozoya, Manny		Need to re-key mailroom to fit GM3 key.							
Guadalupe Gonzalez									
37177					8/19/2008		148		\$0.00
Medium	Work In Progress	Concession		8/19/2008 7:55:32 AM					
Lozoya, Manny		Need key to concession stand. (Mr. Sanchez)							
Guadalupe Gonzalez									
37220					8/20/2008		147		\$0.00
Medium	Work In Progress			8/20/2008 8:34:48 AM					
Lozoya, Manny		Need a CH73 key for classroom for F Wing - Rm. 5. (Paul H. Geiger)							
Guadalupe Gonzalez									
37394		Classroom			8/26/2008		141		\$0.00
Medium	Work In Progress	Nurse		8/26/2008 11:42:37 AM					
Lozoya, Manny		Need keys CH6 for Nurse's office and CH5 for the storage room in the Health Center. (Ana Castro)							
Guadalupe Gonzalez									
37432					8/27/2008		140		\$0.00
Medium	Work In Progress			8/27/2008 8:12:23 AM					
Gonzalez, Salvador		WELD GOOSENECK TO FOOTBALL GOAL POST.							
Guadalupe Ontiveros									
37783					9/4/2008		132		\$0.00
Medium	Work In Progress			9/4/2008 10:52:49 AM					
Lozoya, Manny		(65) LATCH PROTECTORS ARE REQUESTED FOR CLASS RMS AND OFFICE DOORS							
Eddie Baeza									
37893					9/8/2008		128		\$0.00
Medium	Work In Progress	q-4		9/8/2008 10:21:54 AM					
Lozoya, Manny		need a CH-1 for auto construction labs.							
Rosa Quezada									
38072					9/14/2008		122		\$0.00
Medium	Work In Progress			9/14/2008 12:23:08 AM					
Ontiveros, Guadalupe		Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.							
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
38307		Classroom			9/22/2008		114		\$0.00
Medium	Work In Progress	Q-7		9/22/2008 1:13:03 PM					
Lozoya, Manny	NEED CH-94 (2) FOR Q-2 FOR LAB AND CAGES ONE & TWO NEED CH-96 (2) FOR Q-6 FOR LAB AND CAGE KEYS (FOR PETE GALVAN)								
<u>Rosa Quezada</u>									
38324					9/22/2008		114		\$0.00
Medium	Work In Progress			9/22/2008 3:28:35 PM					
Lozoya, Manny	THERE ARE SEVERAL PANIC BARS AND LOCK-SETS THAT ARE NOT WORKING PROPERLY ON CAMPUS.								
<u>Eddie Baeza</u>									
38577					9/30/2008		106		\$0.00
Medium	Work In Progress			9/30/2008 3:53:50 PM					
Lozoya, Manny	CHANGE THE LOCK ON THE TRAINERS ROOM OFF OF CH-86								
<u>Eddie Baeza</u>									
38578					9/30/2008		106		\$0.00
Medium	Work In Progress			9/30/2008 3:56:13 PM					
Lozoya, Manny	(4) DOORS IN THE LOCKER ROOMS NEED TO BE DOUBLE KEYED. (4) DOORS NEED TO BE CHANGED TO LATCH FOR SAFETY AND SECURITY REASONS								
<u>Eddie Baeza</u>									
38742					10/5/2008		101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:49 AM					
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.				10/6/08	- Emailed to Ricky Borrego			
<u>Margret Villalobos</u>									
38989					10/7/2008		99		\$0.00
Medium	Work In Progress			10/7/2008 8:47:09 AM					
Lozoya, Manny	PAD LOCKS AT THE ATHLETIC FEILDS NEED TO BE SECURED SO THEY WILL NOT BE LOST.								
<u>Eddie Baeza</u>									
38995					10/7/2008		99		\$0.00
Medium	Work In Progress			10/7/2008 11:12:22 AM					
Lozoya, Manny	Need a Master Key for Trane Company. They will be working during Fall Break. (approved by A. Holguin)								
Alfredo Holguin									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
39019					10/7/2008		99		\$0.00
Medium	Work In Progress			10/7/2008 3:55:21 PM					
Lozoya, Manny	Greenhouses attached to building - Change door hardware between building and greenhouse to appropriate type.								
Alfredo Holguin									
39021		Athletic Field			10/7/2008		99		\$0.00
Medium	Work In Progress			10/7/2008 3:58:09 PM					
Jacquez, Ricardo	Install fencing around lift station with gates as needed for the service.		11/18 - Asp Mike route to Rick						
Alfredo Holguin									
39194					10/13/2008		93		\$0.00
Medium	Work In Progress	workroom Q & R		10/13/2008 3:43:04 PM					
Lozoya, Manny	NEED TO KEY Q & R WING WORKROOMS SO THAT ALL TEACHERS HAVE ACCESS TO COPIER (QUEZADA)								
Rosa Quezada									
39303	A-Wing	Custodial			10/20/2008		86		\$0.00
Medium	Work In Progress			10/20/2008 2:42:25 PM					
Lozoya, Manny	NEED 4 COPIES OF THE TRASH COMPACTOR KEY FOR HEAD CUSTODIAN ARMANDO RIVERA (QUEZADA)								
Rosa Quezada									
39306					10/20/2008		86		\$0.00
Medium	Work In Progress	SOCCER		10/20/2008 2:44:56 PM					
Lozoya, Manny	NEED 3 COPIES OF CH-86 KEYS FOR SOCCER COACHES								
Rosa Quezada									
39328					10/21/2008		85		\$0.00
Medium	Work In Progress			10/21/2008 8:25:53 AM					
Lozoya, Manny	(10) BEST PADLOCKS WITH LONG SHANKS ARE REQUESTED FOR EQUIPMENT IN NEW WEIGHT ROOM.								
Eddie Baeza									
39337					10/21/2008		85		\$0.00
Medium	Work In Progress			10/21/2008 1:12:48 PM					
Lozoya, Manny	WE ARE UNABLE TO OPEN VAULT AT MAIN OFFICE, AND KEY JUST KEEPS TURNING.								
Eddie Baeza									
39363	A-Wing	Classroom			10/22/2008		84		\$0.00
Medium	Work In Progress	storage room		10/22/2008 9:20:35 AM					
Lozoya, Manny	NEED TO CHANGE CORE IN MAIN STORAGE ROOM IN FRONT OFFICE TO FIT TO KEY GM3 (QUEZADA)								
Rosa Quezada									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral HS									
39393					10/22/2008		84		\$0.00
Medium	Work In Progress				10/22/2008 3:50:18 PM				
Ontiveros, Guadalupe	(4) BATTING CAGES ARE REQUESTED FOR THE BASEBALL FIELDS.								
Eddie Baeza									
39551					10/28/2008		78		\$0.00
Medium	Work In Progress				10/28/2008 3:39:58 PM				
Carrasco, Danny	(10)BALLAST ARE REQUESTED FOR 70 WATT METAL HALIDE BULBS FOR EXTERIOR LIGHTS, AT WINGS.								
Eddie Baeza									
39768					11/3/2008		0		\$0.00
Medium	Work In Progress				11/3/2008 9:22:51 AM	11/3/2008			
Quinones, Paul	Asp Mike, please assist at CHS in cutting weeds starting today. Thanks								
Michael Munoz									
39771					11/3/2008		72		\$0.00
Medium	Work In Progress				11/3/2008 9:54:06 AM				
Parra, Juliet	A TRASH DUMPSTER IS REQUESTED FOR THE Q-WING								
Eddie Baeza									
39780		Cafeteria			11/3/2008		72		\$0.00
Medium	Work In Progress				11/3/2008 1:29:12 PM				
Orozco, Danny	OLD FAVORITE LINE - 2 OF THE 4 LIGHTS ARE OUT								
	JUANA MONTELONGO - SNP MANAGER 824-4461								
Alma Terrell									
39983	A-Wing	Office			11/11/2008		64		\$0.00
Medium	Work In Progress	front main door			11/11/2008 9:09:53 AM				
Lozoya, Manny	NEED TO REKEY FRONT MAIN DOOR TO CH-86 (DIGGS)								
Rosa Quezada									
39984					11/11/2008		64		\$0.00
Medium	Work In Progress	CONCESSION			11/11/2008 9:10:50 AM				
Lozoya, Manny	NEED TO RE-KEY CONCESSION ROOM TO OPEN ON MASTER								
Rosa Quezada									
40133					11/17/2008		58		\$0.00
Medium	Work In Progress	Storage Area			11/17/2008 10:18:06				
Lozoya, Manny	The storage for the building mechanic at CHS needs to be keyed so Mike and I have access to it. When we were there last week our key would not work. please correct this.								

Alfredo Holguin

1/14/2009 11:38:13 AM

Page 23 of 138

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral HS								
40350	A-Wing	Office			11/25/2008		50		\$0.00	
Medium	Work In Progress	TESTING			11/25/2008 3:46:50 PM					
Lozoya, Manny		NEED TO REKEY TESTING STORAGE ROOM LOCATED IN THE MAIN OFFICE.								
Rosa Quezada										
40485	A-Wing	Classroom			12/2/2008		43		\$0.00	
Medium	Work In Progress	A Wing - Rm. 106			12/2/2008 10:03:48 AM					
Quinones, Paul		The platform on which the piano sits is not holding together when the piano is moved. It keeps separating and the piano falls. (Gonzalez)				12/2/08 - Asp David this would be under the furniture manuf. and installer, not construction.				
Guadalupe Gonzalez						12/3 - Routed to Paul to see if it is warranty. - mkv				
40562					12/3/2008		42		\$0.00	
Medium	Work In Progress				12/3/2008 3:52:43 PM					
Lozoya, Manny		Check w/Paul to see if there is any other keys he needs for this site. He already has a GM.								
Michael Munoz										
40701	E-Wing	Classroom			12/9/2008		36		\$0.00	
Medium	Work In Progress	E Wing - Rm. 7			12/9/2008 12:45:14 PM					
Sotelo, Enrique		No electricity on side walls and no cold water. Earlier this year this happened and a make shift fuse was placed in the "utility controller". (Mr. Turner)								
Guadalupe Gonzalez										
40705		Gym			12/9/2008		36		\$0.00	
Medium	Work In Progress	Gym			12/9/2008 2:10:35 PM					
Lozoya, Manny		Left gym door does not lock. (Mr. Sanchez)								
Guadalupe Gonzalez										
40735		Classroom			12/10/2008		35		\$0.00	
Medium	Work In Progress	F Wing -			12/10/2008 10:10:47					
Lozoya, Manny		Replace lock in Teacher's Lounge, it doesn't lock.								
Guadalupe Gonzalez										
40736		Office			12/10/2008		35		\$0.00	
Medium	Work In Progress	Office			12/10/2008 10:12:29					
Lozoya, Manny		Replace the lock to the door in the west side of the front office. It doesn't lock.								
Guadalupe Gonzalez										
40738	D-Wing	Classroom			12/10/2008		35		\$0.00	
Medium	Work In Progress	D Wing - Rm. 7			12/10/2008 10:26:04					
Sotelo, Enrique		No Electricity in classroom. (Ms. Selwyn)								
Guadalupe Gonzalez										
40739	D-Wing	Classroom			12/10/2008		35		\$0.00	
Medium	Work In Progress	Rm.7			12/10/2008 10:51:44					
Ontiveros, Joe		No Water in classroom. (Ms. Selwyn)								
Guadalupe Gonzalez										

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
40740	D-Wing	Classroom			12/10/2008		35		\$0.00
Medium	Work In Progress	Rm.7			12/10/2008 10:52:49				
Ontiveros, Joe		No gas in classroom. (Ms. Selwyn)							
Guadalupe Gonzalez									
40782	A-Wing				12/11/2008		34		\$0.00
Medium	Work In Progress				12/11/2008 9:11:02 AM				
Quinones, Paul		Need to install pencil sharpeners in the A Wing. (Ms. Ballard)							
Guadalupe Gonzalez									
40783		Classroom			12/11/2008		34		\$0.00
Medium	Work In Progress	R Wing - Rm. 1			12/11/2008 9:15:05 AM				
Lozoya, Manny		Plate needs to be installed over door latch/jamb to prevent unauthorized entry into the studio facility. As soon as possible. (Mr. Gabaldon)							
Guadalupe Gonzalez									
40824					12/12/2008		33		\$0.00
Medium	Work In Progress				12/12/2008 8:53:14 AM				
Lozoya, Manny		Need to issue a key to J. Acuna for Paul Quinones office.							
Michael Munoz									
40851					12/14/2008		31		\$0.00
Medium	Work In Progress				12/14/2008 12:16:33				
Ontiveros, Guadalupe		Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.							
George ZZ Gabaldon									
40870		Classroom			12/15/2008		30		\$0.00
Medium	Work In Progress	R Wing - Rm. 2			12/15/2008 2:29:31 PM				
Lozoya, Manny		Door will not lock properly in R Wing - Rm. 2 (Mr. Aguilar)							
Guadalupe Gonzalez									
40904					12/16/2008		29		\$0.00
Medium	Work In Progress				12/16/2008 11:12:15				
Lozoya, Manny		Paper Recycle Bins - Install regular master padlocks on them. (Any ?'s see Alfredo) - Please let him know when it is complete.							
Alfredo Holguin									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
40973					12/18/2008		27		\$0.00
Medium	Work In Progress			12/18/2008 11:05:11					
Lozoya, Manny	PROTECTOR LATCHES,AND DOOR STOPS ARE NEEDED TO ALL CLASS RM. DOORS,AND OTHER DOORS REQUESTED BY CHS PRINCAPLE.ADDITIONAL HELP WILL HELP AS PROJECT STARTS.THANKS MANNY								
Paul Quinones									
41139					1/4/2009		10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:18 AM					
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41140					1/4/2009		10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:19 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
41141					1/4/2009		10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:19 AM					
Quinones, Paul	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41142					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:20 AM					
Quinones, Paul	Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
41144					1/4/2009	2/4/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:21 AM					
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
41150					1/4/2009		10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:23 AM					
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.					1/6/09 e-mailed to ricky.borrego@cummins.com - mkv			
Margret Villalobos									
41178					1/5/2009		9		\$0.00
Medium	Work In Progress	R-Bldg		1/5/2009 3:59:51 PM					
Lozoya, Manny	DOOR IN R-2 BUILDING DOOR DOESNT LOCK DOOR ENTRANCE.								
Paul Quinones									

1/14/2009 11:38:13 AM

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
41180					1/5/2009		9		\$0.00
Medium	Work In Progress				1/5/2009 4:02:23 PM				
Lozoya, Manny		DOOR NEXT TO FRONT ENTRANCE WILL NOT LOCK WITH KEY.ON THE LEFT SIDE OF DOOR.							
Paul Quinones									
41342					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:18 AM				
Rivera, Armando		Monthly - QRTLY BLDG INSP REPORT (CH) - Refer to PM schedule details.							
Jesus Estrada									
41479					1/14/2009		0		\$0.00
Medium	Work In Progress	SECURITY			1/14/2009 9:12:39 AM				
Lozoya, Manny		RE-KEY SECURITY SHACK WHEN COMPLETED WITH A CH-1 KEY. (DE SANTIAGO)							
Rosa Quezada									
Count: 67 Work Orders		Avg. Age of WO's 79			Total for Chaparral HS			0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral MS								
35697					7/6/2008	8/6/2008	192		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:06 AM						
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
36145	Main Building	Classroom			7/23/2008		175		\$0.00	
Medium	Work In Progress	Room 207		7/23/2008 11:09:15 AM						
Lozoya, Manny		**URGENT** THIRD REQUEST FOR NEW KEY FOR ROOM 207 OLD KEY BENT AND BROKE								
Elena Palacios										
36315					7/29/2008		169		\$0.00	
High	Work In Progress			7/29/2008 10:57:48 AM						
Lozoya, Manny		***URGENT*** NEED KEY LOCKS THAT WERE LOST AND ORDERED ACCORDING TO RAFA AND MANNY BACK IN SEPTEMBER OF 07, LOCKS AND KEYS STILL HAVE NOT BEEN REPLACED IN THEIR ENTIRETY								
Elena Palacios										
36316		Computer Lab			7/29/2008		169		\$0.00	
High	Work In Progress	ROOM 207		7/29/2008 11:01:56 AM						
Lozoya, Manny		NEED NEW KEY MADE FOR ROOM 207								
Elena Palacios										
36767	Main Building	Classroom			8/7/2008		160		\$0.00	
Medium	Work In Progress	ROOM 201		8/7/2008 12:10:58 PM						
Lozoya, Manny		NEEDS KEYS TO LOCK CABINETS								
Elena Palacios										
37050					8/14/2008		153		\$0.00	
Medium	Work In Progress			8/14/2008 8:28:32 AM						
Ontiveros, Joe		need to replace shower columns in boys and girls reast rooms. Thxs								
Marti Muela										
37191					8/19/2008		148		\$0.00	
Medium	Work In Progress			8/19/2008 10:54:48 AM						
Lozoya, Manny		eight security window rod irons can not be locked in the 300 & 400 hallway. very easy to break into. those rooms are to the back and can not be seen from the street.								
Robert Gonzalez										
37404	Main Building	Classroom			8/26/2008		141		\$0.00	
Medium	Work In Progress	ROOM 406		8/26/2008 3:43:07 PM						
Lozoya, Manny		NEED CABINET LOCKS								
Elena Palacios										

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
37822	Main Building	Portables			9/5/2008		131		\$0.00
High	Work In Progress	P-9		9/5/2008 9:09:01 AM					
Lozoya, Manny		Social Worker Berenice Holguin needs her file cabinet locked for very confidential paperwork. Her lock was taken by Manny but never replaced.							
Elena Palacios									
37823	Main Building	Classroom			9/5/2008		131		\$0.00
High	Work In Progress	Room 206		9/5/2008 9:10:55 AM					
Lozoya, Manny		Counselor James Wolf needs file cabinet lock back, to secure confidential paperwork. Was taken last year by Manny and not yet replaced.							
Elena Palacios									
37824	Main Building	Classroom			9/5/2008		131		\$0.00
High	Work In Progress	Room 404		9/5/2008 9:14:56 AM					
Lozoya, Manny		NEED CABINETS KEYED FOR MR. MORALES IN ROOM 406							
Elena Palacios									
38127		Gym			9/16/2008		120		\$0.00
Medium	Work In Progress			9/16/2008 10:22:53 AM					
Ronquillo, Ruben		Asp PM 37575 FXT-CHM -017 Need plexiglass cover. FXT-CHM-018 Need plexiglass cover.							
Eric Medina									
38437					9/25/2008		111		\$0.00
Medium	Work In Progress			9/25/2008 3:39:35 PM					
Sotelo, Enrique		need light covers plastic							
Eric Medina									
38633					10/1/2008		105		\$0.00
Medium	Work In Progress			10/1/2008 4:12:11 PM					
Gonzalez, Salvador		need to fix square tubing around 8 windows on the west and north side of building							
Eric Medina									
38779					10/5/2008	10/26/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:03 AM					
Orozco, Danny		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
39188					10/13/2008		93		\$0.00
Medium	Work In Progress			10/13/2008 3:24:04 PM					
Ronquillo, Ruben		large square glass partition in cafeteria was broken over weekend							
Eric Medina									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
39496	Main Building	Classroom			10/27/2008		79		\$0.00
Medium	Work In Progress	ROOM 203		10/27/2008 8:38:48 AM					
Lozoya, Manny		NEED EXTRA KEY MADE FOR ROOM 203 KEY 78 THANKS							
<u>Elena Palacios</u>									
39611					10/30/2008		76		\$0.00
Medium	Work In Progress			10/30/2008 12:30:11					
Lozoya, Manny		room 312 teacher complains door knob is loose							
<u>Eric Medina</u>									
39912		Parking Lot			11/6/2008		69		\$0.00
High	Work In Progress			11/6/2008 2:51:44 PM					
Medina, Eric		need to cut weeds along the east fence line, bus turn around, cove area behind library. also along west fence behind building along pine trees. i have asked you verbally to complete these task and i have not seen progress. call me when complete so i can inspect areas.							
<u>Michael Munoz</u>									
39938	Main Building	Gym			11/7/2008		68		\$0.00
Medium	Work In Progress			11/7/2008 9:41:00 AM					
Lozoya, Manny		Need to replace panic bar in boys locker room due to vandalism.							
<u>Manny Lozoya</u>									
40024					11/12/2008		63		\$0.00
Medium	Work In Progress			11/12/2008 10:54:32					
Ontiveros, Guadalupe		need to order a couple of loads of gravel or base for exposed plumbing in nurses portable							
<u>Eric Medina</u>									
40703					12/9/2008		36		\$0.00
Medium	Work In Progress			12/9/2008 1:44:35 PM					
Ontiveros, Joe		need to order new water heater for nurses portable # 5							
<u>Eric Medina</u>									
40741					12/10/2008		35		\$0.00
Medium	Work In Progress			12/10/2008 11:12:20					
Medina, Eric		About 8 of the exhaust fans in the restrooms or the custodial closets have not been working for a while.				12/16 - Asp Mike route to Eric.			
<u>Robert Gonzalez</u>									
40744					12/10/2008		35		\$0.00
Medium	Work In Progress			12/10/2008 11:20:18					
Medina, Eric		The floors in the boys and girls locker rooms need painting . They look very bad. Mike painted them about five years ago.							
<u>Robert Gonzalez</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
40837		Cafeteria			12/12/2008		33		\$0.00
Medium	Work In Progress			12/12/2008 3:24:23 PM					
Orozco, Danny	DRYER NOT DRYING PROPERLY - TAKES AT LEAST 3 TO 4 CYCLES TO DRY								
Alma Terrell	SANDRA DIAZ - SNP MANAGER 824-4376								
41032					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:33 AM					
Medina, Eric	Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
41070					1/4/2009	1/25/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:49 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
41098					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:00 AM					
Medina, Eric	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41100					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:01 AM					
Medina, Eric	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41146					1/4/2009	2/4/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:22 AM					
Medina, Eric	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
41229					1/7/2009		7		\$0.00
Medium	Work In Progress			1/7/2009 9:19:22 AM					
Solis, Lorenzo	need to replace water fountain in main hallway near 200 entrance								
Eric Medina									
41253	Main Building	Classroom			1/7/2009		7		\$0.00
Medium	Work In Progress	Room 303, 406,		1/7/2009 3:55:06 PM					
Lozoya, Manny	***URGENT THIRD REQUEST*** NEED KEYS FOR THEIR FILING CABINET HAVE VERY PRIVATE SPED INFO THAT NEEDS TO BE LOCKED UP								
Elena Palacios									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Chaparral MS							
41341					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:17 AM				
Gonzalez, Robert	Monthly - QRTLY BLDG INSP REPORTS (CE) - Refer to PM schedule details.								
Jesus Estrada									
Count: 33 Work Orders		Avg. Age of WO's	85	Total for Chaparral MS				0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Pride

35839	Storage A	Mechanical Room			7/10/2008		188		\$0.00
Medium	Work In Progress				7/10/2008 12:44:57 PM				
Castillo, Carlos	NEED TO MOVE RECEPTACLES LOWER OR INSTALL NEW ONE TO STORAGE ROOM TO PUMP HOUSE (WILL BE USING AS CUSTODIAL OFFICE)								

David Acosta					7/17/2008		181		\$0.00
36027					7/17/2008 11:08:09 AM				
Medium	Work In Progress	MORGAN BLDG.							
Castillo, Carlos	NEED POWER TO RUN HEATING/COOLING & OUTLETS IN MORGAN BLDG.								

David Acosta					7/30/2008		168		\$0.00
36356		Classroom			7/30/2008 12:37:03 PM				
Medium	Work In Progress	11							
Castillo, Carlos	ONE LIGHT FIXTURE OUT NEED TO REPLACE BALLAST.								

David Acosta					8/1/2008		166		\$0.00
36451		Classroom			8/1/2008 7:22:52 AM				
Medium	Work In Progress	14,15							
Castillo, Carlos	EMER. LIGHT DO NOT TURN ON IN BOTH ROOMS WHEN TURNING OFF BREAKER SWITCH FOR TESTING.								

David Acosta					8/1/2008		166		\$0.00
36452		Library			8/1/2008 7:26:27 AM				
Medium	Work In Progress								
Castillo, Carlos	EMER LIGHT WON'T STAY ON VERY LONG WHEN DOING ANNUAL TEST.								

David Acosta					9/2/2008		134		\$0.00
37699		Classroom			9/2/2008 2:08:10 PM				
Medium	Work In Progress	1,2							
Castillo, Carlos	NEED MORE EMERG. EXIT SIGNS. (ASK BY STATE FIREMARSHAL TO REQUEST).								

David Acosta					9/2/2008		134		\$0.00
37701		Portables			9/2/2008 2:13:46 PM				
Medium	Work In Progress	ROOM #16							
Castillo, Carlos	NEED SECURITY NITE LIGHT FOR LAST PORTABLE.								

David Acosta					10/1/2008		105		\$0.00
38592		Hallway/Corridor			10/1/2008 11:52:55 AM				
Medium	Work In Progress	2ND BLDG.							
Castillo, Carlos	NEED TO INSTALL RECEPTACLE FOR CANDY MACH. WALL AS NO RECEPTACLE								

David Acosta

1/14/2009 11:38:13 AM

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
39333		Portables			10/21/2008		85		\$0.00
Medium	Work In Progress	16		10/21/2008 11:07:07					
Castillo, Carlos		NEED EXIT SIGN AND EMER. LIGHT FOR LAST PORTABLE (ROOM 16).							
David Acosta									
39845					11/5/2008		70		\$0.00
Medium	Work In Progress			11/5/2008 8:44:00 AM					
Apodaca, Mario		Need to dispose of skunk							
David Acosta									
40488		Office			12/2/2008		43		\$0.00
Medium	Work In Progress			12/2/2008 10:34:07 AM					
Castillo, Carlos		NEED TO REPLACE BURN OUT LIGHT BULB TO OUTSIDE OFFICE BLDG.							
David Acosta									
40669		Portables			12/8/2008		37		\$0.00
Medium	Work In Progress	room 1		12/8/2008 11:46:00 AM					
Estrada, Jesus		ATT: MIKE MUNOZ-ROOM 1 (PORTABLE) NEEDS TO REPLACE SOME FLOOR TILE BUT MAY NEED TO REPLACE A SECTION OF FLOOR BY DOOR ENTRANCE.							
David Acosta									
41049					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:41 AM					
Acosta, David		Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
41067					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:48 AM					
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
41101					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:01 AM					
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
41105					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:03 AM					
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
41209					1/6/2009		8		\$0.00
Medium	Work In Progress				1/6/2009 3:43:53 PM				
Gonzalez, Salvador	please install ballards on the sidewalk from the 3rd bldg to the barrack.please see mike.thxs								
Michael Munoz									
41344					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:19 AM				
Acosta, David	Monthly - QRTLY BLDG INSP REPORT (DP) - Refer to PM schedule details.								
Jesus Estrada									
Count: 18 Work Orders		Avg. Age of WO's 85		Total for Desert Pride			0	\$0.00	

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
35728					7/7/2008		191		\$0.00
Medium	Work In Progress				7/7/2008 9:25:36 AM				
Lozoya, Manny	Please change core to doorknob in maintenance office to A-32.								
Johnny Acuna									
35698					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress				7/6/2008 12:20:07 AM				
Villalobos, David	Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35816					7/10/2008		188		\$0.00
Medium	Work In Progress				7/10/2008 7:55:15 AM				
Ronquillo, Ruben	Need an awning installed outdoors on top of the back door to the library. When it rains, water comes through the door wetting the new carpet.								
Johnny Acuna									
36381					7/30/2008		168		\$0.00
Medium	Work In Progress				7/30/2008 9:32:01 PM				
Ontiveros, Guadalupe	Springkler system is down on the westside, it has been uncovered for a couple of weeks. Please advise as to covering the system or will it be fixed before August 1, 2008. School starts on the 4th.								
Ruben Ortiz									
36822					8/8/2008		159		\$0.00
Medium	Work In Progress				8/8/2008 9:41:58 AM				
Lozoya, Manny	Need 3 key cores to be installed in the new mulliums for the doors.								
Johnny Acuna									
36823					8/8/2008		159		\$0.00
Medium	Work In Progress				8/8/2008 9:43:14 AM				
Lozoya, Manny	Need a lock installed in the new filing cabinet to room #398. Mr. Varela.								
Johnny Acuna									
36887					8/11/2008		156		\$0.00
Medium	Work In Progress	110			8/11/2008 11:51:39 AM				
Lozoya, Manny	Marisela front office receptionist needs replacement of lost key for room #110 (J66) and also need one extra (J2) key.								
Elizabeth Hernandez									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
37007	Main Building	Classroom			8/13/2008		154		\$0.00
Medium	Work In Progress			8/13/2008 11:46:28 AM					
Lozoya, Manny	Room 109 no se puede habrir. ---- J master esta doblada--- room 403 necesita llave---- banos 411 necesitan cambiar chapas---- puertas principales se atora la llave- GRACIAS								
<u>Marisela Torres</u>									
37034					8/13/2008		154		\$0.00
Medium	Work In Progress			8/13/2008 3:46:59 PM					
Lozoya, Manny	Portable #408 Mr. West is having trouble unlocking door knob key cylinder. Please send me some Graffite.								
<u>Johnny Acuna</u>									
37197					8/19/2008		148		\$0.00
Medium	Work In Progress			8/19/2008 2:56:15 PM					
Acuna, Johnny	.5-check lift station 7.5-Transport Bobcat tractor to Chaparral High and Help Eddie cut weeds around the back of the main building.								
<u>Johnny Acuna</u>									
37281	Main Building	Classroom			8/21/2008		146		\$0.00
Medium	Work In Progress			8/21/2008 9:34:34 AM					
Lozoya, Manny	Room # 409 la puerta tiene una parte quebrada y no se puede cerrar. Gracias.								
<u>Marisela Torres</u>									
37286	Main Building	Office			8/21/2008		146		\$0.00
Medium	Work In Progress			8/21/2008 11:32:48 AM					
Lozoya, Manny	Escritorio de enfermeria necesita candado de seguridad.Gracias.								
<u>Marisela Torres</u>									
37831	Main Building	Restroom (Boys)			9/5/2008		131		\$0.00
Medium	Work In Progress			9/5/2008 11:30:06 AM					
Lozoya, Manny	Puerta bano maestros esta caida no cierra. puerta portable 404 esta caida no cierra. puerta principal se atora la llave. Gracias.								
<u>Marisela Torres</u>									
38075	Main Building	Cafeteria			9/15/2008		121		\$0.00
Medium	Work In Progress			9/15/2008 8:14:18 AM					
Lozoya, Manny	LA CHAPA DE LA PUERTA SE QUEBRO Y NO SE PUEDE CERRAR.								
<u>Marisela Torres</u>									
38213					9/18/2008		118		\$0.00
Medium	Work In Progress			9/18/2008 12:09:20 PM					
Gonzalez, Salvador	Please weld extra metal to the top of the metal scraper to add on a little more weight to it. Thank You....								
<u>Johnny Acuna</u>									
1/14/2009 11:38:13 AM									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
38214					9/18/2008		118		\$0.00
Medium	Work In Progress			9/18/2008 12:11:28 PM					
Lozoya, Manny	Please install Lock to new filing cabinet in room #399 inside the main building.								
<u>Johnny Acuna</u>									
38277	Main Building	Computer Lab			9/22/2008		114		\$0.00
Medium	Work In Progress			9/22/2008 8:00:19 AM					
Sotelo, Enrique	Provide electrical supply to 5 ton unit, cooling only.								
<u>Lorenzo Solis</u>									
38553		Classroom			9/30/2008		106		\$0.00
Medium	Work In Progress			9/30/2008 9:21:04 AM					
Lozoya, Manny	se necesita recortar e instalar 2 puertas en cuarto 407 (fueron removidas porque instalaron alfombra) gracias.								
<u>Marisela Torres</u>									
38554	Main Building	Custodial			9/30/2008		106		\$0.00
Medium	Work In Progress			9/30/2008 9:24:04 AM					
Lozoya, Manny	se necesitan 2 name plates--- JAIME GUTIERREZ--- CUSTODIAL OFFICE . Gracias.								
<u>Marisela Torres</u>									
40644					12/7/2008	12/23/2008	38		\$0.00
Medium	Work In Progress			12/7/2008 12:16:13 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>George ZZ_Gabaldon</u>									
38634					10/1/2008		105		\$0.00
Medium	Work In Progress			10/1/2008 4:14:26 PM					
Lozoya, Manny	Physical Education Coach (Mrs. Murphy) has trouble opening her classroom door with her key. Portable #404								
<u>Johnny Acuna</u>									
38701	Main Building	Restroom (Girls)			10/3/2008		103		\$0.00
Medium	Work In Progress			10/3/2008 11:41:44 AM					
Lozoya, Manny	URGENTE, CAMBIAR LA CHAPA DE UN BANO DE OFICINA, SE QUEDA CERRADA. CUARTO #413 LA PUERTA ESTA CAIDA , NO CIERRA.								
<u>Marisela Torres</u>									
38780					10/5/2008	10/26/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:03 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
39012					10/7/2008		99		\$0.00
Medium	Work In Progress			10/7/2008 3:30:52 PM					
Lozoya, Manny	Need a replacement Door and Door Frame for Portable #413 inside Restroom Door.								
Johnny Acuna									
39014					10/7/2008		99		\$0.00
Medium	Work In Progress			10/7/2008 3:33:24 PM					
Lozoya, Manny	Portable #410: Need a Replacement Metal Door.								
Johnny Acuna									
39122					10/10/2008		96		\$0.00
Medium	Work In Progress			10/10/2008 4:10:15 PM					
Ontiveros, Guadalupe	(Irrigation water pressure tank: Chaparral Elementary) Water leak next to the water pressure tank area.								
Johnny Acuna									
39413					10/23/2008		83		\$0.00
Medium	Work In Progress			10/23/2008 12:20:38					
Ronquillo, Ruben	Asp PM 38534 Exhaust Fan, need to replace motor on the following: FED-001, FED-003, FED-017, FED-019, FED-023, FED-036. FED-039, FED-049, FED-077.								
Johnny Acuna									
39492					10/27/2008		79		\$0.00
Medium	Work In Progress			10/27/2008 8:10:22 AM					
Ontiveros, Joe	Portable # 412. Restroom sink faucet needs to be replaced.								
Johnny Acuna									
39643					10/31/2008		75		\$0.00
Medium	Work In Progress			10/31/2008 7:36:22 AM					
Lozoya, Manny	Need a Name Plate for Portable #411 that says: (Parent Center).								
Johnny Acuna									
39677					10/31/2008		75		\$0.00
Medium	Work In Progress			10/31/2008 4:09:15 PM					
Gonzalez, Salvador	Need to re-weld stainless sheetmetal sheet together that came apart in the kitchen sink area.								
Johnny Acuna									
39759		Athletic Field			11/3/2008		72		\$0.00
Medium	Work In Progress			11/3/2008 7:38:23 AM					
Acuna, Johnny	Basketball Courts in the outdoor playground are badly cracked and separating.		Asp Mike, route back to Johnny, to order joint and filler thru Maint. Warehouse.						
Johnny Acuna		11/5/08							

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
39760					11/3/2008		72		\$0.00
Medium	Work In Progress			11/3/2008 7:40:41 AM					
Ronquillo, Ruben	Window frames in the side of the main doors in the NW hall needs to be replaced or repaired. There is too much corrosion.								
Johnny Acuna									
39852	Main Building	Office			11/5/2008		70		\$0.00
Medium	Work In Progress			11/5/2008 11:52:46 AM					
Lozoya, Manny	PUERTA ENTRADA PRINCIPAL, NO SE PUEDE CERRAR. GR								
Marisela Torres									
40131					11/17/2008		58		\$0.00
Medium	Work In Progress			11/17/2008 10:01:30					
Lozoya, Manny	Need to install Locks in Filing cabinets to room # 212 and Portable #412.								
Johnny Acuna									
40135					11/17/2008		58		\$0.00
Medium	Work In Progress			11/17/2008 10:49:05					
Lozoya, Manny	Need (1) key for Rm. #511 that also opens staff Restrooms. And (1) Key for Rm. #304 that also opens staff Restrooms.								
Johnny Acuna									
40174					11/18/2008		57		\$0.00
Medium	Work In Progress			11/18/2008 10:30:37					
Ontiveros, Joe	Need to replace urinal in the Southwest hall Boy's Restroom.								
Johnny Acuna									
40307					11/24/2008		51		\$0.00
Medium	Work In Progress			11/24/2008 7:46:01 AM					
Lozoya, Manny	Portable #403 (Mrs. Rios) Needing a cabinet lock for wood storage cabinet. (Same as the ones installed in the workroom and Old nurse's office cabinets).								
Johnny Acuna									
40410					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress			11/30/2008 12:23:44					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
George ZZ_Gabaldon									
40946					12/17/2008		28		\$0.00
Medium	Work In Progress			12/17/2008 9:39:09 AM					
Lozoya, Manny	Portable #403. Doorknob sometimes gets stuck through tthe inside. In case of an Emergency, Teacher and students would not be able to Exit their classroom. It is the only door for the classroom. Thank You.....								
Johnny Acuna									
1/14/2009 11:38:13 AM									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Desert Trail Intermediate							
41033					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:33 AM				
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41050					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:41 AM				
Acuna, Johnny	Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41071					1/4/2009	1/25/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:50 AM				
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41099					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:19:00 AM				
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41104					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:19:02 AM				
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41192					1/6/2009		8		\$0.00
Medium	Work In Progress				1/6/2009 12:08:50 PM				
Lozoya, Manny	Room #117: need assistance in adjusting door frame and door.								
<u>Johnny Acuna</u>									
41193					1/6/2009		8		\$0.00
Medium	Work In Progress				1/6/2009 12:10:21 PM				
Lozoya, Manny	Portable #412: Door knob is very loose and teacher has problems opening door.								
<u>Johnny Acuna</u>									
41199	Main Building	Classroom			1/6/2009		8		\$0.00
Medium	Work In Progress				1/6/2009 2:18:47 PM				
Lozoya, Manny	Urgente. Cuarto 410 la chapa se quebro, y no se puede cerrar. gracias								
<u>Marisela Torres</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Desert Trail Intermediate							
41345					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:19 AM				
Torres, Marisela		Monthly - QRTL Y BLDG INSP REPORTS (DT) - Refer to PM schedule details.							
Jesus Estrada									
41365					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:27 AM				
Acuna, Johnny		Monthly - Desert Trail Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
41414					1/12/2009		2		\$0.00
Medium	Work In Progress				1/12/2009 4:08:44 PM				
Lozoya, Manny		Portable #403: (Mrs. Rios): Need to install a new door knob to Portable #403. Has been repaired several times. Door knob gets stuck and the teacher and student's sometimes cannot come out of the classroom. It's the only door to their classroom. (Safety Issue in case of an Emergency).							
Johnny Acuna									
Count: 50 Work Orders		Avg. Age of WO's		86	Total for Desert Trail Intermediate			0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
35613					7/6/2008	7/14/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:40 AM					
Aguilar, Patricio	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35617					7/6/2008	7/14/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:41 AM					
Aguilar, Patricio	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35699					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:20:07 AM					
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35961		Cafeteria			7/15/2008		183		\$0.00
Medium	Work In Progress			7/15/2008 7:33:37 AM					
Moncayo, Fernando	MILK COOLER IS NOT WORKING AT ALL.								
	DIANA LAZARIN SNP MGR 589-2425								
Jacqueline Aguilar									
36198					7/25/2008		173		\$0.00
Medium	Work In Progress			7/25/2008 7:12:16 AM					
Ortiz, Ruben	Perimeter Fence - clear trash and sand build up along fenceline.		Asp Lupe, route back to Ruben 9/19						
Alfredo Holguin									
36883					8/11/2008		156		\$0.00
Medium	Work In Progress	Hallways		8/11/2008 10:24:06 AM					
Ortiz, Ruben	2 Emergency Lights not working in Middle and East Hallway asp PM 36530.		Need to order thru material request and complete wo once they are replaced.						
Ruben Ortiz									
36939	Main Building				8/12/2008		155		\$0.00
Medium	Work In Progress			8/12/2008 8:37:50 AM					
Ortiz, Ruben	Tested exit signs (4) are not working 2 in Gym and Cafeteria asp PM 36526.		Need to order thru material request and complete wo once they are replaced.						
Ruben Ortiz									
37045					8/13/2008		154		\$0.00
Medium	Work In Progress			8/13/2008 8:46:58 PM					
Ortiz, Ruben	08/13/08 To: Lupe Ontiveros I am requesting to have the arroyo run off filled in and weeds scrapped. If possible with the tractors that are on the south schools area. Before the tractors are taken out.		Asp Lupe, route back to Ruben 9/19						
Ruben Ortiz									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
37634					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:41 AM					
Aguilar, Patricio	Monthly - Desert View ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
Margret Villalobos									
37635					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:41 AM					
Aguilar, Patricio	Monthly - Desert View ES A-1 Semiannual MCD - Refer to PM schedule details.								
Margret Villalobos									
37636					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:41 AM					
Aguilar, Patricio	Monthly - Desert View ES A-1 Semiannual MCS & MCS2 - Refer to PM schedule details.								
Margret Villalobos									
37637					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:42 AM					
Aguilar, Patricio	Monthly - Desert View ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos									
37639					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:42 AM					
Aguilar, Patricio	Monthly - Desert View ES A-5 Quarterly SS - Refer to PM schedule details.								
Margret Villalobos									
37641					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:43 AM					
Aguilar, Patricio	Monthly - Desert View ES A-13 Quarterly WREH - Refer to PM schedule details.								
Margret Villalobos									
38108					9/15/2008		121		\$0.00
Medium	Work In Progress			9/15/2008 7:13:21 PM					
Villalobos, David	Requesting for plumber to check if two water faucets can be installed for cleaning purposes								
Ruben Ortiz									
38928					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:57 AM					
Ortiz, Ruben	Yearly - Desert View ES U-2 Unit Heat Gas Yearly - Refer to PM schedule details.								
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Desert View ES									
39053					10/8/2008		98		\$0.00
Medium	Work In Progress			10/8/2008 5:07:00 PM					
Villalobos, David	To Mike Munoz I was asked by Mr. Carrasco that he needs hot water and more water pressure for the shower in the Special Ed room. There is a child that needs to be bathed often and the water is too cold. He asked for an urgent work order. Mr. Carrasco asked for this work order to be sent directly to you because he wants it ASAP 10/08/08. Child is being bathed in cold water. Thank you.								
Ruben Ortiz									
39404					10/22/2008		84		\$0.00
Medium	Work In Progress			10/22/2008 9:10:57 PM					
Lara, Ralph	Carlos Castillo The button for the handicap door is not working on the southside of the building exit.								
Ruben Ortiz									
40528		Gym			12/3/2008		42		\$0.00
Medium	Work In Progress			12/3/2008 12:28:54 PM					
Briones, Enrique	This work order is for warehouse we need from you guys to come for some furniture and some chairs because the principal wants the gym all clear for the spelling b next week and for christmas dance. THANK YOU IN ADVANCED.								
Hector Rivera									
40871		Cafeteria			12/15/2008		30		\$0.00
Medium	Work In Progress			12/15/2008 2:35:04 PM					
Moncayo, Fernando	AS PER DIMAR SYSTEM, RANGE HOOD SYSTEMS REPORT DATED 12/15/08, EXHAUST FAN IS NOT OPERATING. DIANA LAZARIN SNP MGR 589-2425								
Jacqueline Aguilar									
41034					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:34 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
41051					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:42 AM					
Ortiz, Ruben	Monthly - Desert View ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Desert View ES								
41102					1/4/2009	1/12/2009	10		\$0.00	
Medium	Work In Progress			1/4/2009 12:19:01 AM						
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
41106					1/4/2009	1/12/2009	10		\$0.00	
Medium	Work In Progress			1/4/2009 12:19:03 AM						
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
41155					1/5/2009		9		\$0.00	
Medium	Work In Progress			1/5/2009 8:57:57 AM						
Carrasco, Danny	1 broken window in portable 1, it measures 43x15 inches, it's a double window 2 Broken windows in hallway above principles office, they measures 13x23 inches 1 broken window in the westside hallway, it measures 13 by 23 inches Thank you for your immediate response, Ruben Ortiz									
<u>Ruben Ortiz</u>										
41185					1/5/2009		9		\$0.00	
Medium	Work In Progress			1/5/2009 9:21:52 PM						
Villalobos, David	leaking valves in the pump room, need plumber. Thank you, Ruben									
<u>Ruben Ortiz</u>										
41346					1/11/2009	1/27/2009	3		\$0.00	
Medium	Work In Progress			1/11/2009 12:17:19 AM						
Rivera, Hector	Monthly - QRTLY BLDG INSP REPORT (DV) - Refer to PM schedule details.									
<u>Jesus Estrada</u>										
41366					1/11/2009	1/27/2009	3		\$0.00	
Medium	Work In Progress			1/11/2009 12:17:27 AM						
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
Count: 28 Work Orders			Avg. Age of WO's	98	Total for Desert View ES			0	\$0.00	

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		GAC								
35700					7/6/2008	8/6/2008	192		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:07 AM						
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
35802	RTC	Office			7/9/2008		189		\$0.00	
Medium	Work In Progress	RTC ACROSS		7/9/2008 3:07:58 PM						
Ambriz, Jose		AS PER GLORIA SAENZ-NEED TO HAVE THE AIR CONDITIONER UNIT CHECKED. SETTINGS ARE NOT WORKING PROPERLY.								
Mary Garcia										
36280					7/28/2008		170		\$0.00	
Medium	Work In Progress	Back bottom road		7/28/2008 12:11:48 PM						
Ontiveros, Guadalupe		need to apply dirt and crusherfine in back road due to running water after haevy rain.								
Juan Ambriz										
36281		Hallway/Corridor			7/28/2008		170		\$0.00	
Medium	Work In Progress	C-Wing A/C unit		7/28/2008 12:13:33 PM						
Ambriz, Jose		Need to raplace relays in C-Wing unit not working properly								
Juan Ambriz										
36334		Parking Lot			7/29/2008		169		\$0.00	
Medium	Work In Progress	bottom dirt		7/29/2008 3:47:57 PM						
Ontiveros, Guadalupe		Need to apply more crusherfine in bottom dirt parking lot accumulating water after rain								
Juan Ambriz										
36360					7/30/2008		168		\$0.00	
Medium	Work In Progress			7/30/2008 3:14:05 PM						
Castillo, Carlos		Need to order new emergency lights for the server room not working total of two								
Juan Ambriz										
36949		Office			8/12/2008		155		\$0.00	
Medium	Work In Progress	A-WING		8/12/2008 10:35:44 AM						
Ambriz, Juan		IF IT WOULD BE POSSIBLE TO HAVE THE AIR VENTS IN JESUS REYE'S OFFICE ADJUSTED. NOT ENOUGH AIR COMES THROUGH.								
Mary Garcia										
37189		Office			8/19/2008		148		\$0.00	
Medium	Work In Progress	B-WING		8/19/2008 10:23:04 AM						
Castillo, Carlos		AS PER ANNE- IN LUDYM'S OFFICE (NEW FINANCE DIRECTOR) ONE OF THE FLUORESCENT LIGHT FIXTURES DOES NOT HAVE A COVERING AND NEEDS ONE PLEASE.								
Mary Garcia										

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
37828		Office			9/5/2008		131		\$0.00
Medium	Work In Progress	B-WING		9/5/2008 11:13:08 AM					
Ambriz, Juan	AS PER MS. BROWDER-WOULD LIKE TO HAVE HER WHOLE OFFICE PAINTED. IF IT WOULD BE POSSIBLE FOR THE DATES OF 9/16 OR 9/17TH, BEFORE FURNITURE COMES IN ON 9/18/08.		APPROVED BY MR. RICHARD G. CHAVEZ. AS PER JUAN, HE HAS ENOUGH PAINT.						
Mary Garcia									
37829		Office			9/5/2008		131		\$0.00
Medium	Work In Progress	B-WING		9/5/2008 11:15:03 AM					
Rodriguez, Arturo	AS PER MS. BROWDER-WOULD LIKE TO HAVE HER OFFICED WAXED, DUE TO GETTING NEW FURNITURE ON 9/18/09. IF THIS CAN BE DONE ON THE FOLLOWING DATES: 9/16 OR 9/1708.		12/03/08 - REFAXED TO ARTURO 12/17/08 - MAILED AGAIN TO ARTURO 1/8/09 - refaxed to arturo						
Mary Garcia									
37844		Office			9/5/2008		131		\$0.00
Medium	Work In Progress	Districts vehicle		9/5/2008 3:13:38 PM					
Gonzales, Angel	Need to do tune-up to maintenance vehicle # 140								
Juan Ambriz									
37912		Parking Lot			9/8/2008		128		\$0.00
Medium	Work In Progress	bottom dirt		9/8/2008 3:39:17 PM					
Ontiveros, Guadalupe	Need to level bottom parking lot with crusher fine to avoid accumulated water after rains								
Juan Ambriz									
37939		Office			9/9/2008		127		\$0.00
Medium	Work In Progress	Back dirt road		9/9/2008 8:25:56 AM					
Ontiveros, Guadalupe	need to add dirt to back dirt road due to running water after rains. If possible add crusher fine.								
Juan Ambriz									
37978		Office			9/9/2008		127		\$0.00
Medium	Work In Progress	A-WING		9/9/2008 4:42:49 PM					
Castillo, Carlos	AS PER ELISA-NEED AN ELECTRICAL OUTLET TO BE INSTALLED IN THE SUPT. CONFERENCE CLOSET.								
Mary Garcia									
37979		Office			9/9/2008		127		\$0.00
Medium	Work In Progress	A-WING		9/9/2008 4:44:25 PM					
Castillo, Carlos	AS PER ELISA-NEED TO HAVE AN ELECTRICAL OUTLET IN HER OFFICE REMOVED.								
Mary Garcia									
37984		Office			9/10/2008		126		\$0.00
Medium	Work In Progress	C-WING		9/10/2008 10:29:18 AM					
Ambriz, Juan	AS PER MS. PHILLIPS-NEED TO HAVE A TV & DVD PLAYER STRAPPED DOWN TO THE CART THAT WAS PURCHASED.								
Mary Garcia									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
38423		Cafeteria			9/25/2008		111		\$0.00
Medium	Work In Progress			9/25/2008 8:29:48 AM					
Moncayo, Fernando	DELI COOLER - CONDENSING UNIT ON ROOF NEEDS A POWER DISCONNECT FOR SAFETY -- TOP PRIORITY		10/27 - Asp Mike, route to Cali 11/18 - Route back to Fernie asp Mike						
Alma Terrell	AIDA SALCEDO - SNP COORDINATOR 882-6772								
38646					10/2/2008		104		\$0.00
Medium	Work In Progress			10/2/2008 2:30:47 PM					
Castillo, Carlos	Asp PM 37606, still waiting on Emerg. Light for Board Rm and Sever Rm not working.								
Juan Ambriz									
38781					10/5/2008	10/26/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:03 AM					
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
38879					10/5/2008	10/21/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:39 AM					
Ambriz, Juan	Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.								
Margret Villalobos									
39066		Office			10/9/2008		97		\$0.00
Medium	Work In Progress	C-WING		10/9/2008 9:56:10 AM					
Ambriz, Juan	AS PER MS. NORMA DURAN-NEED TO HAVE SOME HOLES PATCHED UP, DUE TO REMOVAL OF SOME FILING CABINETS IN THE BILINGUAL OFFICE.								
Mary Garcia									
39366		Office			10/22/2008		84		\$0.00
Medium	Work In Progress	C-WING		10/22/2008 9:54:03 AM					
Ambriz, Juan	AS PER ALFREDO-GO AHEAD AND SEAL OFF THE WALL WHERE THE AIR UNIT WAS IN OFELIA'S OFFICE.		APPROVED BY ALFREDO						
Mary Garcia									
40020		Cafeteria			11/12/2008		63		\$0.00
Medium	Work In Progress			11/12/2008 9:26:48 AM					
Moncayo, Fernando	DELI UNIT IS NOT WORKING - COOLING								
Alma Terrell	GESSICA BLAZQUEZ - SNP MANAGER 882-6784								

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:	GAC								
40223		Office			11/19/2008		56		\$0.00
Medium	Work In Progress	B-WING			11/19/2008 2:24:32 PM				
Villalobos, David		AS PER MR. CHAVEZ-NEED TO HAVE THE PLUMBER COME IN AND CHECK OUT THE SINK BEHIND RECEPTIONIST AREA IN B WING, OVER WITH VANESSA. THERE IS A REAL BAD SEWER SMELL.				JUAN HAS ALREADY TAKEN A LOOK AT THIS AND SMELL STILL CONTINUES.			
Mary Garcia									
40275		Office			11/20/2008		55		\$0.00
Medium	Work In Progress	A-WING			11/20/2008 3:59:32 PM				
Carrasco, Danny		AS PER JULIE & ANN-NEED TO BORROW A PORTABLE HEATER FOR FIRST THING TOMORROW MORNING. (APPROVED BY MR. RICHARD G. CHAVEZ)							
Mary Garcia									
40588		Office			12/4/2008		41		\$0.00
Medium	Work In Progress	A-WING			12/4/2008 3:00:15 PM				
Ambriz, Juan		AS PER MARGARET V.-NEED A BOARD INSTALLED IN HER OFFICE.							
Mary Garcia									
40589		Office			12/4/2008		41		\$0.00
Medium	Work In Progress	C-WING			12/4/2008 3:02:00 PM				
Ambriz, Juan		AS PER MS. YTURRALDE-REQUESTING TO HAVE EXCESS RAILING REMOVED FROM THE WALL.							
Mary Garcia									
40590		Office			12/4/2008		41		\$0.00
Medium	Work In Progress	C-WING			12/4/2008 3:04:11 PM				
Ambriz, Juan		AS PER MS. YTURRALDE-NEED TO HAVE EXCESS RAILING MOVED AND INSTALLED UNDER DATA CLERK'S FLIPPER CABINET.							
Mary Garcia									
40591		Office			12/4/2008		41		\$0.00
Medium	Work In Progress	C-WING			12/4/2008 3:04:50 PM				
Ambriz, Juan		AS PER MS. YTURRALDE-NEED TO HAVE HOLES IN WALL FILLED.							
Mary Garcia									
40605	RTC	Office			12/4/2008		41		\$0.00
Medium	Work In Progress	RTC ACROSS			12/4/2008 5:01:11 PM				
Ambriz, Juan		AS PER GLORIA SAENZ-NEED TO FIX DOOR STOPPER							
Mary Garcia									
40646					12/7/2008	12/23/2008	38		\$0.00
Medium	Work In Progress				12/7/2008 12:16:14 AM				
Ambriz, Juan		Monthly - GAC Playground Insp - Refer to PM schedule details.							
George ZZ_Gabaldon									
1/14/2009 11:38:14 AM									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									
Location: GAC									
40674	RTC	Parking Lot			12/8/2008		37		\$0.00
Medium	Work In Progress	RTC ACROSS		12/8/2008 2:30:07 PM					
Ontiveros, Guadalupe		AS PER GLORIA SAENZ-NEED TO HAVE THE DIRT REMOVED FROM THE PARKING LOT.							
<u>Mary Garcia</u>									
40699		Restroom (Girls)			12/9/2008		36		\$0.00
Medium	Work In Progress	B-Wing		12/9/2008 12:36:49 PM					
Ambriz, Juan		Need to replace Sink faucets in B-Wing restroom							
<u>Juan Ambriz</u>									
40706		Office			12/9/2008		36		\$0.00
Medium	Work In Progress	B-Wing file room		12/9/2008 2:55:57 PM					
Ambriz, Juan		Need to replace light switch causing short							
<u>Juan Ambriz</u>									
40806		Parking Lot			12/11/2008		34		\$0.00
Medium	Work In Progress			12/11/2008 2:43:32 PM					
Munoz, Michael		Pour concret pad for trash dumpsters							
<u>Alfredo Holguin</u>									
40892	RTC	Office			12/16/2008		29		\$0.00
Medium	Work In Progress	RTC ACROSS		12/16/2008 9:19:21 AM					
Ambriz, Juan		AS PER GLORIA-DOOR LOCKS ARE FULL OF DIRT AND WILL NOT TURN THE KEY TO OPEN OR CLOSE				JUAN IS ALREADY LOOKING INTO THIS			
<u>Mary Garcia</u>									
40914		Cafeteria			12/16/2008		29		\$0.00
Medium	Work In Progress	kitchen		12/16/2008 3:17:47 PM					
Ambriz, Juan		Need to repair or replace exhaust fan in kitchen							
<u>Juan Ambriz</u>									
40994		Cafeteria			12/18/2008		27		\$0.00
Medium	Work In Progress			12/18/2008 3:50:21 PM					
Ambriz, Jose		AS PER OUR CONVERSATION (MIKE MUNOZ) ON 12/18/08 PLEASE ORDER BUTTERFLY VENTS FOR DINING ROOM AND KITCHEN				1/6/09 - Route to Jose asp Mike.			
		SNP 882-6772							
<u>Alma Terrell</u>									
41025					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:29 AM					
Ambriz, Juan		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
41063					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:46 AM					
Ambriz, Juan		Monthly - GAC Roof Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
41072					1/4/2009	1/25/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:50 AM					
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
41103					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:02 AM					
Ambriz, Juan	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41107					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:04 AM					
Ambriz, Juan	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41187		Office			1/6/2009		8		\$0.00
Medium	Work In Progress	C-WING		1/6/2009 9:53:19 AM					
Ambriz, Juan	AS PER MS. SHIELA RAIHL-FLOOR TILE IS LIFTING UP AND THE SHOES ARE GETTING STUCK ON THE TILE, NEEDS TO BE REPLACED OR REPAIRED.								
Mary Garcia									
41203		Hallway/Corridor			1/6/2009		8		\$0.00
Medium	Work In Progress	B-WING		1/6/2009 2:57:15 PM					
Estrada, Jesus	AS PER MR. SUTTMILLER-THE FLOOR TILE ENTERING B-WING NEEDS TO BE REPLACED OR REPAIRED, IT IS LIFTING.								
Mary Garcia									
41217					1/6/2009		8		\$0.00
Medium	Work In Progress			1/6/2009 4:27:32 PM					
Ambriz, Juan	please cut weeds and pick up tree branches where trash bins are going to go. please call mike if you have any questions								
Michael Munoz									
41284		Hallway/Corridor			1/8/2009		6		\$0.00
Medium	Work In Progress	loading dock back		1/8/2009 3:39:42 PM					
Lara, Ralph	Need to clean or repair back door key core not turning properly.								
Juan Ambriz									
41322		Office			1/9/2009		5		\$0.00
Medium	Work In Progress	B-WING		1/9/2009 3:13:41 PM					
Ambriz, Juan	AS PER ANNE-NEED TO HAVE A CEILING LIGHT TURNED OFF AND HAVE ANOTHER ONE TURNED ON IN MR. SUGGS OFFICE.								
Mary Garcia									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: GAC									
41361					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:25 AM					
Rodriguez, Arturo	Monthly - QRTL BLDG INSP REPORT (GAC) - Refer to PM schedule details.								
Jesus Estrada									
41367					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:28 AM					
Ambriz, Juan	Monthly - GAC Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
41406	RTC	Office			1/12/2009		2		\$0.00
Medium	Work In Progress	RTC ACROSS		1/12/2009 3:40:26 PM					
Ambriz, Juan	AS PER GLORIA SAENZ-WALING RAMP TO CLASSROOM BOARD IS MISSING AND HAS BROKEN BOARDS.								
Mary Garcia									
41407		Office			1/12/2009		2		\$0.00
Medium	Work In Progress	C-WING		1/12/2009 3:42:24 PM					
Lara, Ralph	AS PER KARLA QUESADA-NEED TO HAVE ONE OF THE VAULTS RE-KEYED WITH A DIFFERENT LOCK AND ALSO GET 2 NEW KEYS FOR THAT LOCK ON THE VAULT. (WHERE TESTING MATERIALS ARE LOCATED)								
Mary Garcia									
41408					1/12/2009		2		\$0.00
Medium	Work In Progress			1/12/2009 3:45:54 PM					
Ambriz, Juan	Need to assist Arturo Ruiloba on Wednesday at 10:00am to load equipment and move to the New Tech Office @ PPD. (Danny Carrasco will assist)								
Alfredo Holguin									
41471		Hallway/Corridor			1/13/2009		1		\$0.00
Medium	Work In Progress	A-WING SUPT'S		1/13/2009 4:47:38 PM					
Lara, Ralph	AS PER MR. YTURREALDE-NEED TO HAVE THE DOOR LOCK GOING INTO THE SUPT'S HALLWAY CHANGED TO A PAD LOCK COMBINATION OR PUSH BUTTON LOCK. (WHERE IT OPENS THROUGH A ONE WAY ONLY.) SEE MR. YTURREALDE OR MARY GARCIA BEFORE INSTALLING.								
Mary Garcia									
Count: 54 Work Orders			Avg. Age of WO's 69				Total for GAC	0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Gadsden HS								
41052					1/4/2009	1/12/2009	10		\$0.00	
Medium	Work In Progress			1/4/2009 12:18:42 AM						
Apodaca, Mario		Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
35479	Football Stadium	Football Field			7/1/2008		197		\$0.00	
Medium	Work In Progress			7/1/2008 8:20:32 AM						
Ontiveros, Guadalupe		The chain link fence by the guest bleachers need to be repaired at the football field.								
<u>Mario Apodaca</u>										
35701					7/6/2008	8/6/2008	192		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:08 AM						
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
35873	Main Building	Office			7/11/2008		187		\$0.00	
Medium	Work In Progress			7/11/2008 2:16:35 PM						
Lara, Ralph		NEW NAME PLATES (3) MR. CAREY L. CHAMBERS								
<u>Mario Apodaca</u>										
35876	Main Building	Office			7/11/2008		187		\$0.00	
Medium	Work In Progress			7/11/2008 2:28:45 PM						
Carrasco, Danny		NEED NEW BLINDS FOR PRINCIPAL CHAMBERS OFFICE 1. 40" X 5' 2. 7' X 5'								
<u>Mario Apodaca</u>										
35877	Main Building	Office			7/11/2008		187		\$0.00	
Medium	Work In Progress			7/11/2008 2:32:00 PM						
Ambriz, Jose		NEW WINDOW AC UNIT FOR PRINCIPAL CHAMBERS								
<u>Mario Apodaca</u>										
35993	Boys Gym	Office			7/16/2008		182		\$0.00	
Medium	Work In Progress			7/16/2008 2:28:31 PM						
Ambriz, Jose		Requested by Coach Lawrence Rm. 401 Office in Boy's Gym-Room 401 does not have any air conditioning, would like to have a unit installed this summer of 2008, to review videos and to watch films for Soccer.								
<u>Velia Alarcon</u>										
36000	Library	Library			7/16/2008		182		\$0.00	
Medium	Work In Progress			7/16/2008 3:18:40 PM						
Ontiveros, Guadalupe		An irrigation control box has a water leak underneath the asphalt outside the southwest exit.								
Albert Vallejo										

1/14/2009 11:38:14 AM

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
36066	North Building	Classroom			7/18/2008		180		\$0.00
Medium	Work In Progress				7/18/2008 3:19:18 PM				
Ronquillo, Ruben	NEED NEW WINDOW BLINDS (35"WX56"L) FOR ROOM 207 NEED 11 EA								
Mario Apodaca									
36067	Old English Bldg	Classroom			7/18/2008		180		\$0.00
Medium	Work In Progress				7/18/2008 3:21:06 PM				
Ambriz, Jose	NEED A NEW HEATING CONDESER AT ROOM 141 DO TO VANDALISM								
Mario Apodaca									
36186	Cafeteria (1998)	Cafeteria			7/24/2008		174		\$0.00
Medium	Work In Progress				7/24/2008 3:18:50 PM				
Moncayo, Fernando	WALK - IN FREEZER DOWN. GHS SNP 882-5522								
Jacqueline Aguilar									
36231					7/25/2008		173		\$0.00
Medium	Work In Progress				7/25/2008 3:04:45 PM				
Ontiveros, Guadalupe	Requested by Coach Hite for Football Field-Football field is very uneven. Please level as it is very dangerous.								
Velia Alarcon									
36288	Vocational	Classroom			7/28/2008		170		\$0.00
Medium	Work In Progress	568			7/28/2008 3:08:02 PM				
Carrasco, Danny	Window frames in front of classroom are in bad repair and need to be completely replaced. Large amounts of water get through during rainstorms.								
Albert Vallejo									
36310	Cafeteria (1998)	Cafeteria			7/29/2008		169		\$0.00
Medium	Work In Progress				7/29/2008 8:10:33 AM				
Moncayo, Fernando	NEED A SAFETY POWER DISCONNECT TO THE GHS WALK-IN'S (BOTH) ON THE CONDENSER UNITS ON THE ROOF						11/18 - Asp Mike route to Fernie		
MR. DEMETRIIOUS GIOVAS									
Jacqueline Aguilar									
36359		Cafeteria			7/30/2008		168		\$0.00
Medium	Work In Progress				7/30/2008 3:02:54 PM				
Moncayo, Fernando	need to ck the ice maker compressors at the cafe it is tipping the circuit breaker								
Mario Apodaca									
36622					8/4/2008		163		\$0.00
Medium	Work In Progress	WWT			8/4/2008 4:10:54 PM				
Sanchez, Raul	Replace motor for Wastewater Treatment Plant Blowers.								
Raul Sanchez									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
36783	Academic Bldg				8/7/2008		160		\$0.00
Medium	Work In Progress				8/7/2008 2:58:49 PM				
Apodaca, Mario	Requested by Coach Hite-Paint Cactus Sculpture on south west corner of academic building.								
<u>Velia Alarcon</u>									
36878	Boys Gym				8/11/2008		156		\$0.00
Medium	Work In Progress				8/11/2008 8:35:04 AM				
Marquez, Gerardo	new shower column was installed in girls dressing room. need to install tile to complete project. see mike. thxs								
<u>Michael Munoz</u>									
36896	Boys Gym	Gym			8/11/2008		156		\$0.00
Medium	Work In Progress				8/11/2008 2:55:29 PM				
Castillo, Carlos	NEED A NEW SWITCH FOR THE E/COOER UNIT AT THE BOYS GYM								
<u>Mario Apodaca</u>									
37049	Football Stadium	Football Field			8/14/2008		153		\$0.00
Medium	Work In Progress				8/14/2008 8:14:03 AM				
Munoz, Michael	Some of the concrete piers that support the bleachers are cracked and need to be repaired.								
<u>Albert Vallejo</u>									
37094	Cafeteria (1998)	Cafeteria			8/14/2008		153		\$0.00
Medium	Work In Progress				8/14/2008 3:40:19 PM				
Ambriz, Jose	ALL OUTSIDE DUCTS OF THE CAFE BLDG NEED TO BE RESEAL DOTO SUN AND WATER DAMAGE. ASAP								
<u>Mario Apodaca</u>									
37099	Boys Gym	Gym			8/15/2008		152		\$0.00
Medium	Work In Progress				8/15/2008 7:44:21 AM				
Appelzoller, Fred	install collars to cover vents and water to showers in boys gym as per mike.								
<u>Fred Appelzoller</u>									
37143	New Vocational	Hallway/Corridor			8/18/2008		149		\$0.00
Medium	Work In Progress				8/18/2008 2:43:34 PM				
Ronquillo, Ruben	Need window glass replaced, Approximately 24" x 30" in size. (wired glass)								
<u>Albert Vallejo</u>									
37145					8/18/2008		149		\$0.00
Medium	Work In Progress				8/18/2008 2:48:35 PM				
Gonzalez, Salvador	The chain link fence directly south of the band room has been hit by a vehicle, one post is down and the mesh has been torn								
<u>Albert Vallejo</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
37232	Old English Bldg	Classroom			8/20/2008		147		\$0.00
Medium	Work In Progress			8/20/2008 2:03:04 PM					
Carrasco, Danny	NEED NEW WINDOW MINI BLINDS DOTO VANDALISM (W43 1/2"X L90") NEED #4								
Mario Apodaca									
37233	Academic Bldg				8/20/2008		147		\$0.00
Medium	Work In Progress			8/20/2008 2:15:18 PM					
Ambriz, Jose	AT THE ACADEMIC BLDG NEED NEW E/COOLER STANDS								
Mario Apodaca									
37234	Cafeteria (1998)				8/20/2008		147		\$0.00
Medium	Work In Progress			8/20/2008 2:17:31 PM					
Ambriz, Jose	AT THE CAFE BLDG NEED NEED NEW E/COOER STANDS								
Mario Apodaca									
37284					8/21/2008		146		\$0.00
Medium	Work In Progress			8/21/2008 11:13:30 AM					
Ronquillo, Ruben	8 SIGNS (24 X 18) THAT READ THE FOLLOWING: GHS IS A DRUG FREE CAMPUS NO SMOKING NO ALCOHOL NO WEAPONS NO PETS								
Mario Apodaca									
37295	Agricultural	Classroom			8/21/2008		146		\$0.00
Medium	Work In Progress			8/21/2008 2:52:32 PM					
Appelzoller, Fred	need a new sink and faucet set put-in at room 569								
Mario Apodaca									
37299					8/21/2008		146		\$0.00
Medium	Work In Progress			8/21/2008 2:59:39 PM					
Apodaca, Mario	8-20-08				8/20-8				
	6-painting a class room at the a.g bldg room 569 1-t/shoot a/c unit at the n-bldg too room 202 1-in put to school dude								
Mario Apodaca									
37306					8/21/2008		146		\$0.00
Medium	Work In Progress			8/21/2008 3:20:25 PM					
Vallejo, Albert	(8-21-08) 2 hrs - Troubleshoot and repair A/C unit on top of varsity gym; 2 hrs - Finish restroom wall and install urinal in boys gym; 3 hrs - repair partitions in boys restroom in cafeteria; 1 hr - Fire extinguisher inspections (work order #36494)				8/21-7				
Albert Vallejo									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
37360	Grounds Shop				8/25/2008		142		\$0.00
Medium	Work In Progress			8/25/2008 12:51:17 PM					
Castillo, Carlos	I need an electrician to disconnect power to burned-out motor at wwtp and assist me in installing a new blower motor. We may need a small crane to lift new motor up to wwtp platform. Thanks, Raul								
Raul Sanchez									
37400					8/26/2008		141		\$0.00
Medium	Work In Progress			8/26/2008 3:35:15 PM					
Castillo, Carlos	Requested by Mr. Roberson for Rm. 127 Main Building- Install on/off switch for lights in room #127. When room was divided switch was left in room #128.								
Velia Alarcon									
37421					8/26/2008		141		\$0.00
Medium	Work In Progress			8/26/2008 4:18:55 PM					
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Remove frame from North Batting Cage and deliver to Softball Field.								
	See Coach Bones and Coach Lopez before beginning work.								
Velia Alarcon									
37423					8/26/2008		141		\$0.00
Medium	Work In Progress			8/26/2008 4:21:08 PM					
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Take nets off of north batting cage and place them on the south east batting cage.								
	See Coach Bones before beginning work.								
Velia Alarcon									
37431					8/27/2008		140		\$0.00
Medium	Work In Progress			8/27/2008 8:10:43 AM					
Gonzalez, Salvador	NEED TO CONSTRUCT SHADE AT GROUNDS DEPT. TO PROTECT IMPLEMENT.								
Guadalupe Ontiveros									
37442					8/27/2008		140		\$0.00
Medium	Work In Progress			8/27/2008 10:51:46 AM					
Ontiveros, Guadalupe	Requested by Coach Hite for Football Field-Sod bare areas on Football Field before first home game on September 12th.								
Velia Alarcon									
37444	Old English Bldg				8/27/2008		140		\$0.00
Medium	Work In Progress			8/27/2008 11:31:54 AM					
Apodaca, Mario	Requested by Mr. Stemsrud Rm. 154 Old English Building-Hang maps.								
Velia Alarcon									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
37691	Academic Bldg				9/2/2008		134		\$0.00
Medium	Work In Progress				9/2/2008 11:42:35 AM				
Apodaca, Mario	Requested by Ms. Luna Rm. 318 Academic Building- Paint the office.								
<u>Velia Alarcon</u>									
37708	Cafeteria (1998)	Custodial			9/2/2008		134		\$0.00
Medium	Work In Progress				9/2/2008 2:46:32 PM				
Gonzales, Angel	i have a preasure washer that will start but has very little water preasure when operating								
<u>Joe Munoz</u>									
37996	Agricultural	Classroom			9/10/2008		126		\$0.00
Medium	Work In Progress				9/10/2008 3:10:19 PM				
Ronquillo, Ruben	need new window blinds for room 568.ea 2 (60 1/2"x45")								
<u>Mario Apodaca</u>									
38074					9/14/2008		122		\$0.00
Medium	Work In Progress				9/14/2008 12:23:09 AM				
Ontiveros, Guadalupe	Monthly - Gadsden HS Soil Sampling - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38165	Cafeteria (1998)	Restroom (Boys)			9/17/2008		119		\$0.00
Medium	Work In Progress				9/17/2008 8:25:05 AM				
Ronquillo, Ruben	a cafe window need to be repairs at the boys restroom do to vandalism (20"x20")								
<u>Mario Apodaca</u>									
38284					9/22/2008		114		\$0.00
Medium	Work In Progress				9/22/2008 9:40:57 AM				
Vallejo, Albert	Requested by Mr. Roberson for Campus-Paint all paintable surfaces on campus restrooms white.								
<u>Velia Alarcon</u>									
38286					9/22/2008		114		\$0.00
Medium	Work In Progress				9/22/2008 10:13:18 AM				
Apodaca, Mario	Requested by Ms. Lam Rm. 104 Main Building-Holder of the glass door of the south book shelf is broken.								
<u>Velia Alarcon</u>									
38287					9/22/2008		114		\$0.00
Medium	Work In Progress				9/22/2008 10:30:07 AM				
Villalobos, David	Requested by Ms. Lam Rm. 104 Main Building-Both cold and hot water of the faucet on the south side have sulfur smell.								
<u>Velia Alarcon</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
38288					9/22/2008		114	1	\$25.00
Medium	Work In Progress			9/22/2008 10:35:59 AM					
Briones, Enrique	Requested by Coach Hite and Coach Maxey Football Laundry Room-Remove old dryer and metal objects from laundry room. Also, tables and chairs that are broken and stored in there. Remove refrigerator from Football locker room.		11/17/08 Items are on inventory, forwarded to purchasing warehouse for pickup.						
Velia Alarcon									
38292					9/22/2008		114		\$0.00
Medium	Work In Progress			9/22/2008 10:58:14 AM					
Apodaca, Mario	Requested by Ms. Aguilar Rm. 236 North Building- Replace burned out light bulbs.								
Velia Alarcon									
38293					9/22/2008		114		\$0.00
Medium	Work In Progress			9/22/2008 10:59:47 AM					
Apodaca, Mario	Requested by Ms. Leahy Rm. 328 Academic Building- Window does not have screen, please install one.								
Velia Alarcon									
38294					9/22/2008		114		\$0.00
Medium	Work In Progress			9/22/2008 11:05:39 AM					
Lara, Ralph	Requested by Ms. Moreno Rm. 126 Main Building-The door is fallen and hard to close. The key is very hard to get out of the lock and the door sometimes gets stuck and students can not get out. This could be a problem during fire drills.								
Velia Alarcon									
38296					9/22/2008		114		\$0.00
Medium	Work In Progress			9/22/2008 11:16:00 AM					
Vallejo, Albert	Requested by Ms. Roth Rm. 213 North Building-Legs are loose on various HEAVY lab tables and need to be tightened and possibly secured. Table tops are not attached to certain tables and also pose a safety hazard and noise maker.								
Velia Alarcon									
38303	Main Building	Custodial			9/22/2008		114		\$0.00
Medium	Work In Progress			9/22/2008 11:49:06 AM					
Gonzales, Angel	i have two weeders that will not start and needs maintnence								
Joe Munoz									
38305					9/22/2008		114		\$0.00
Medium	Work In Progress			9/22/2008 12:04:36 PM					
Briones, Enrique	Requested by Coach Hite for Football Fieldhouse (Boy's Gym)-Please remove refrigerator, does not work.		11/17/08 Items are on inventory, forwarded to purchasing warehouse for pickup.						
Velia Alarcon									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
38429	Academic Bldg	Classroom			9/25/2008		111		\$0.00
Medium	Work In Progress			9/25/2008 2:39:13 PM					
Carrasco, Danny		need windos blinds (46 3/4" x 62") for the academic bldg need 10							
Mario Apodaca									
38465					9/26/2008		110		\$0.00
Medium	Work In Progress			9/26/2008 12:29:32 PM					
Lozoya, Manny		Mr. Chacon, Band Director needs a gate key.							
Michael Munoz									
38493					9/29/2008		107		\$0.00
Medium	Work In Progress			9/29/2008 10:43:07 AM					
Ontiveros, Guadalupe		Requested by Coach A. Lopez for Softball Field Varsity Batting Cage-Patio, cement inside of batting cage.							
Velia Alarcon									
38497					9/29/2008		107		\$0.00
Medium	Work In Progress			9/29/2008 10:57:19 AM					
Carrasco, Danny		Requested by Julio Alcantar for Student Parking Lot- Need more electrical poles to help mark the parking spaces in the student parking lot.							
Velia Alarcon									
38538					9/30/2008		106		\$0.00
Medium	Work In Progress			9/30/2008 12:26:03 AM					
Apodaca, Mario		Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
38604					10/1/2008		105		\$0.00
Medium	Work In Progress			10/1/2008 2:02:50 PM					
Ambriz, Jose		Requested by Ms. Hartmann Rm. 568 Classroom between Ag. Shop and Wood Shop-Install an extracting fan to remove fumes coming into room 568, created by Auto and Ag engines. There's currently no way for fumes to exit from classroom. Fumes giving teacher and students headaches.							
Velia Alarcon									
38744					10/5/2008		101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:50 AM					
Holguin, Alfredo		Monthly - Gadsden HS Generator PM (Quarterly) - Refer				10/6/08 - Emailed to Ricky Borrego to PM schedule details.			
Margret Villalobos									
38746					10/5/2008	10/26/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:51 AM					
Vallejo, Albert		Monthly - Gadsden HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
38747					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:51 AM					
Vallejo, Albert	Yearly - Gadsden HS H6 (Furnace)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
38748					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:51 AM					
Vallejo, Albert	Yearly - Gadsden HS R9 (H.W.Radiator)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
38790					10/5/2008	10/26/2008	99		\$0.00
Medium	Work In Progress			10/5/2008 12:24:06 AM		1/12/2009			
Orozco, Danny	Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38893					10/5/2008	10/13/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:44 AM					
Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
38954	Cafeteria (1998)	Cafeteria			10/6/2008		100		\$0.00
Medium	Work In Progress			10/6/2008 10:39:01 AM					
Moncayo, Fernando	ICE MACHINE IS DOWN AGAIN - FERNANDO WAS AT GAC ON 10/3/08, I (ALMA) TOLD HIM OF THE PROBLEM.								
SARA GARCIA - SNP ASST. MANAGER 882-5522									
Alma Terrell									
38974	Academic Bldg	Classroom			10/6/2008		100		\$0.00
Medium	Work In Progress			10/6/2008 3:03:50 PM					
Ambriz, Jose	need new e/cooler unit at the academic bldg need 20 e.a								
Mario Apodaca									
38997	Main Building				10/7/2008		99		\$0.00
Medium	Work In Progress			10/7/2008 11:33:11 AM					
Munoz, Joe	Requested by Velia for Front Office in Main Building- Since air quality and mold are a concern today. There are several spots in the Front Office that have leaked when it rains and dark spots have started to grow in these areas. Please test areas for mold and clean them. Although this problem won't be resolved until the roof is either repaired or re-roofed. Main Building has several leaks through out the building.				10/7 - Asp Mike, rout to Custodial FAX W.O. TO JOE 12/03- REFAXED TO JOE 12/17- REFAXED TO JOE. 1/8/09 - REFAXED TO JOE.				

Velia Alarcon

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
39073	Agricultural	Classroom			10/9/2008		97		\$0.00
Medium	Work In Progress				10/9/2008 3:15:51 PM				
Ronquillo, Ruben	need a window blind for room 569 (60"x48")								
Mario Apodaca									
39097					10/10/2008		96		\$0.00
Medium	Work In Progress				10/10/2008 11:31:16				
Lara, Ralph	Requested by Coach Letz for Storage Room in Girl's Gym-The door bolt came off the door knob, the loose bolt is in Velia's Office. Please pick it up when the door knob will be fixed.								
Velia Alarcon									
39132					10/12/2008	10/28/2008	58	6	\$150.00
Medium	Work In Progress				10/12/2008 12:20:51	12/9/2008			
Munoz, Joe	Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.					COMPLETED			
Jesus Estrada									
39252	Old English Bldg	Classroom			10/15/2008		91		\$0.00
Medium	Work In Progress				10/15/2008 12:27:17				
Ambriz, Jose	need a new damper motor for the heating unit at the old eng bldg								
Mario Apodaca									
39300	North Building	Classroom			10/20/2008		86		\$0.00
Medium	Work In Progress				10/20/2008 2:38:24 PM				
Moncayo, Fernando	the deli cart cooer is not working need to be fix ASAP.at room 233 n-bldg.								
Mario Apodaca									
39506	Academic Bldg				10/27/2008		79		\$0.00
High	Work In Progress				10/27/2008 10:25:31				
Castillo, Carlos	as per mr.chambers, the north end of the outside of the building is lacking lighting. this is a pick-up area and is safety issue.please see if exterior lighting can be placed. presently there is 1 exterior light. would like more lights that would illuminte more.								
thxs									
Carey Chambers									
39510					10/27/2008		79		\$0.00
Medium	Work In Progress				10/27/2008 10:59:35				
Lara, Ralph	Requested by Mr. Enriquez Rm. 580 Auto Shop-Repair damaged doors to storage room and office.								
Velia Alarcon									
39621	New Vocational	Classroom			10/30/2008		76		\$0.00
High	Work In Progress				10/30/2008 2:08:48 PM				
Ambriz, Jose	the heating unit at rom 551 has a carbon monoxide of 5ppm need a new heating unit asap								
Mario Apodaca									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
39823	Auto Shop	Classroom			11/4/2008		71		\$0.00
Medium	Work In Progress				11/4/2008 3:05:39 PM				
Lara, Ralph	need 2 new doors at the auto shop the doors are broken do to vandalism								
<u>Mario Apodaca</u>									
40007					11/11/2008		64		\$0.00
Medium	Work In Progress				11/11/2008 3:32:35 PM				
Orozco, Danny	I need to have someone operate a bucket truck or a small crane to remove a bad motor and blower from atop of wastewater plant. The person operating then has to put in place a new motor and blower that I have in stock. Thanks, Raul Sanchez								
<u>Raul Sanchez</u>									
40054	Old English Bldg	Gym			11/13/2008		62		\$0.00
Medium	Work In Progress				11/13/2008 3:05:05 PM				
Munoz, Michael	the girls gym need work on the gym floor do to roof leaks . A.S.A.P								
<u>Mario Apodaca</u>									
40142					11/17/2008		58		\$0.00
Medium	Work In Progress				11/17/2008 12:26:28				
Apodaca, Mario	11-14-08					11/14-8			
	1.5-went to the p.p.d for supplies and gas-up 1.5-ck water boiler unit at bldg 2-t/shoot heating unit at the n-bldg at the annex bldg 1-fix a door lever set at the academic bldg to room 331 1-went to put new traps at camp lab 1-ck the electrical heater unit at the main bldg								
<u>Mario Apodaca</u>									
40177					11/18/2008		57		\$0.00
Medium	Work In Progress				11/18/2008 12:10:04				
Lara, Ralph	Requested by Mr. Villa Rm. 510 Band Room-Double door on south side, door drop mount came off from the top inside of the door.								
<u>Velia Alarcon</u>									
40182	Auto Shop	Classroom			11/18/2008		57		\$0.00
Medium	Work In Progress				11/18/2008 1:01:06 PM				
Moncayo, Fernando	NEED TO REMOVE THE OLD WASHER AT STORED IN THE AUTO SHOP. AT WAS IN THE KITCHEN ASAP.								
<u>Mario Apodaca</u>									
40362					11/30/2008	12/6/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:28				
Vallejo, Albert	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
<u>George ZZ_Gabaldon</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
40363					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:29				
Vallejo, Albert	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40424					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:49				
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40517	Main Building				12/3/2008		42		\$0.00
Medium	Work In Progress				12/3/2008 8:08:17 AM				
Castillo, Carlos	Run new electrical for new units installed.								
<u>Michael Munoz</u>									
40525	Cafeteria (1998)	Cafeteria			12/3/2008		42		\$0.00
Medium	Work In Progress				12/3/2008 11:34:13 AM				
Moncayo, Fernando	Bottom Blodgett Oven is not working								
	Sara Garcia - Asst. Manager 882-5522								
<u>Alma Terrell</u>									
40526	Cafeteria (1998)	Cafeteria			12/3/2008		42		\$0.00
Medium	Work In Progress				12/3/2008 11:35:42 AM				
Moncayo, Fernando	The pilot to one of the Ovens is not working								
	Sara Garcia - SNP Asst. Manager 882-5522								
<u>Alma Terrell</u>									
40542	Old English Bldg	Restroom (Girls)			12/3/2008		42		\$0.00
Medium	Work In Progress				12/3/2008 2:51:58 PM				
Lara, Ralph	need a new door for the girls restroom at the old eng bldg at the top floor. asap.								
<u>Mario Apodaca</u>									
40647					12/7/2008	12/23/2008	38		\$0.00
Medium	Work In Progress				12/7/2008 12:16:14 AM				
Vallejo, Albert	Monthly - Gadsden HS Playground Insp - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40677	Varsity Gym	Dressing Room			12/8/2008		37		\$0.00
Medium	Work In Progress				12/8/2008 3:22:27 PM				
Gonzalez, Salvador	NEED TO REWELD THE SCREEN AT THE GIRLS LOCKEROOM 237 AT THE V-GYM								
<u>Mario Apodaca</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
40695	Old English Bldg				12/9/2008		36		\$0.00
Medium	Work In Progress				12/9/2008 12:33:28 PM				
Ambriz, Jose	Girls Gym - Need to check heating and control dampers in gym.								
Michael Munoz									
40700					12/9/2008		36		\$0.00
Medium	Work In Progress				12/9/2008 12:41:33 PM				
Estrada, Jesus	NEED TO LOOK @ INTERLOCKING TILE IN BOYS GYM (SOUTH SIDE), MEASURE AND ORDER SAME MATERIAL FOR GIRLS VARSITY GYM. ALSO NEED TO ORDER SAME SHOWER MATTING THAT IS IN THE BOYS GYM FOR GIRLS GYMS.		12/10/08 - MICHAEL TO GO OUT TO GH AND QUOTE ON SAME FLOORING PRODUCT (WHICH HE DOES NOT RECOMMEND) AND QUOTE ON WHAT HE DOES RECOMMEND. WILL PRICE QUOTE MATTING FROM FLOORSURFAES.COM / MILO CRIPPS 805-275-4087 1/12/09 - PENDING PURCHASE ORDER						
Michael Munoz									
40707	Library	Library			12/9/2008		36		\$0.00
Medium	Work In Progress				12/9/2008 2:59:42 PM				
Ambriz, Jose	NEED A NEW GAS VALVE FOR A HEATING UNIT AT THE LIBRARY								
Mario Apodaca									
40747	Varsity Gym				12/10/2008		35		\$0.00
Medium	Work In Progress				12/10/2008 1:46:03 PM				
Apodaca, Mario	V.Gym Girls locker room- Paint and remove tiles. (Danny C. and Sal G. will assist)								
Michael Munoz									
40771	Main Building				12/11/2008		34		\$0.00
Medium	Work In Progress				12/11/2008 8:20:02 AM				
Ambriz, Jose	the a/c unit at the network room it not working at the main bldg								
Mario Apodaca									
40834	Varsity Gym				12/12/2008		33		\$0.00
Medium	Work In Progress				12/12/2008 2:43:02 PM				
Vallejo, Albert	V.GYM GIRLS LOCKER ROOM-NEED TO INSTALL KEM LIGHTING ON WALL		12/16 - Asp Mike route to Albert.						
Michael Munoz									
40853					12/14/2008		31		\$0.00
Medium	Work In Progress				12/14/2008 12:16:34				
Ontiveros, Guadalupe	Monthly - Gadsden HS Soil Sampling - Refer to PM schedule details.								
George ZZ Gabaldon									
40893		Athletic Field			12/16/2008		29		\$0.00
Medium	Work In Progress				12/16/2008 9:23:01 AM				
Ontiveros, Guadalupe	Requested by Mr. Lawrence for Soccer Field-Over seed soccer field, top soil for soccer field.								
Velia Alarcon									
1/14/2009 11:38:14 AM									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
40895					12/16/2008		29		\$0.00
Medium	Work In Progress			12/16/2008 9:33:11 AM					
Vallejo, Albert	Requested by Maria Rm. 657A Faculty Lounge Restroom in Business Building-Light bulb needs to be replaced.								
<u>Velia Alarcon</u>									
40897	Boys Gym				12/16/2008		29		\$0.00
Medium	Work In Progress			12/16/2008 9:50:42 AM					
Lara, Ralph	Requested by Coach Hite for Boy's Gym-Repair or replace the plate damaged on the outside south east door of the football field house.								
<u>Velia Alarcon</u>									
40898					12/16/2008		29		\$0.00
Medium	Work In Progress			12/16/2008 10:00:05					
Ronquillo, Ruben	Requested by Coach Hite Football J.V. Locker Room in Boy's Gym-Install a mirror in J.V. locker room. Please make mirror as large as possible, alot of students need to use it at the same time.								
<u>Velia Alarcon</u>									
40899	Boys Gym				12/16/2008		29		\$0.00
Medium	Work In Progress			12/16/2008 10:02:41					
Apodaca, Mario	Requested by Coach Hite for Football Locker Room in Boy's Gym-Repair all lockers in the varsity locker room.								
<u>Velia Alarcon</u>									
40900	Auto Shop				12/16/2008		29		\$0.00
Medium	Work In Progress			12/16/2008 10:08:04					
Appelzoller, Fred	Requested by Mr. Enriquez Rm. 580 Auto Shop-Pressure washer hose ruptured.								
<u>Velia Alarcon</u>									
41026					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:30 AM					
Vallejo, Albert	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41108					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:04 AM					
Vallejo, Albert	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41111					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:05 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1/14/2009 11:38:14 AM

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
41145					1/4/2009	2/4/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:21 AM					
Vallejo, Albert	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41149					1/4/2009		10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:23 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.		1/6/09 - E-mailed to ricky.borrego@cummins.com'						
<u>Margret Villalobos</u>									
41205	Academic Bldg				1/6/2009		8		\$0.00
Medium	Work In Progress			1/6/2009 3:21:19 PM					
Ambriz, Jose	the heating unit at the greenhouse need a new fan moter								
<u>Mario Apodaca</u>									
41211	North Building				1/6/2009		8		\$0.00
High	Work In Progress			1/6/2009 3:45:35 PM					
Vallejo, Albert	please replace broken glass blocks on the west side of the n.bldg. Thanks								
<u>Michael Munoz</u>									
41242	Vocational	Classroom			1/7/2009		7		\$0.00
Medium	Work In Progress			1/7/2009 2:52:33 PM					
Ambriz, Jose	nedd a new heating unit for classroom 550 at the wood shop bldg								
<u>Mario Apodaca</u>									
41259					1/7/2009		7		\$0.00
Medium	Work In Progress			1/7/2009 4:28:40 PM					
Ronquillo, Ruben	Requested by Mr. Cordova for Stage Curtains in Varsity Gym-Repair the stage curtains in the Varsity Gym, curtains were made by Rodriguez Upholstery.								
<u>Velia Alarcon</u>									
41270	Agricultural	Classroom			1/8/2009		6		\$0.00
Medium	Work In Progress			1/8/2009 2:29:39 PM					
Appelzoller, Fred	NEED TO FIX A COPPER WATER LINE IN THE GREENHOUSE								
<u>Mario Apodaca</u>									
41271	North Building	Gym			1/8/2009		6		\$0.00
Medium	Work In Progress			1/8/2009 2:36:51 PM					
Ronquillo, Ruben	NEED A NEW GLASS SHELV PUT IN AT THE DLSPLAY CASES(76"X12"1/4")								
<u>Mario Apodaca</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
41279	North Building				1/8/2009		6		\$0.00
Medium	Work In Progress			1/8/2009 3:19:24 PM					
Lara, Ralph	Need to change cores in room #236 in the North Building so that teachers will have keys that correspond with the rest of the building, allowing them access to the lounge. Will require six (6) keys.								
<u>Albert Vallejo</u>									
41301	Nursing Center	Office			1/8/2009		6		\$0.00
Medium	Work In Progress	900		1/8/2009 4:37:19 PM					
Sotelo, Enrique	Jan.16 the RN office is receiving a sleep pod for students. It requires electricity, so we will need an electrical outlet on the East wall, on the boys side. Thanks, Colleen								
<u>Colleen Runyan</u>									
41347					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:20 AM					
Munoz, Joe	Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
41368					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:28 AM					
Vallejo, Albert	Monthly - Gadsden HS Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41399	Academic Bldg	Classroom			1/12/2009		2		\$0.00
Medium	Work In Progress			1/12/2009 12:46:15 PM					
Lara, Ralph	THE DOOR LOCK SET ROOM 562 NEED WORK ON AT AG SHOP BLDG								
<u>Mario Apodaca</u>									
41445	Football Stadium	Athletic Field			1/13/2009		1		\$0.00
Medium	Work In Progress			1/13/2009 3:08:56 PM					
Castillo, Carlos	Need to line locate where the power to the football light post for new fence is going-up.								
<u>Mario Apodaca</u>									
41446	Football Stadium	Athletic Field			1/13/2009		1		\$0.00
Medium	Work In Progress			1/13/2009 3:12:12 PM					
Munoz, Michael	need new fence for football on the s-side								
<u>Mario Apodaca</u>									
Count: 122 Work Orders		Avg. Age of WO's 92		Total for Gadsden HS			7	\$175.00	

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
35702					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:20:08 AM					
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
35955					7/14/2008		184		\$0.00
Medium	Work In Progress			7/14/2008 3:35:17 PM					
Lozoya, Manny		Need fix main entrance doors the punish bar not work properly thank you							
Sebastian Diaz									
36222		Office			7/25/2008		173		\$0.00
Medium	Work In Progress	Awing/GMS Front		7/25/2008 11:40:57 AM					
Lozoya, Manny		Need to set up A57 key lock on new door in Ms. Quinonez's office as soon as possible.							
Maricruz Carrasco									
36627		Office			8/5/2008		162		\$0.00
Medium	Work In Progress	GMS Front		8/5/2008 5:44:35 AM					
Lozoya, Manny		Need A53 door lock on Nancy's door as soon as possible.							
Maricruz Carrasco									
36628		Office			8/5/2008		162		\$0.00
Medium	Work In Progress	Awing/155/Dr.		8/5/2008 5:47:23 AM					
Lozoya, Manny		Door lock in Dr. Garcia's office supposed to be opened by M36 key only. W key can be used to open the door. Please check door lock.							
Maricruz Carrasco									
36630		Parking Lot			8/5/2008		162		\$0.00
Medium	Work In Progress	Parking		8/5/2008 5:56:11 AM					
Ronquillo, Ruben		Need two windows in security shed.							
Maricruz Carrasco									
36632		Parking Lot			8/5/2008		162		\$0.00
Medium	Work In Progress	Parking		8/5/2008 5:59:53 AM					
Lozoya, Manny		Need metal door installed in Security shed.							
Maricruz Carrasco									
36994	Cafeteria	Cafeteria			8/13/2008		154		\$0.00
Medium	Work In Progress			8/13/2008 8:10:48 AM					
Moncayo, Fernando		SNP WAREHOUSE A/C SOUTHSIDE HAS NO WATER. HOT AIR BLOWING.							
Jacqueline Aguilar		JOHNNY LECHUGS SNP MGR WHSE 882-6927							

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
36995	Cafeteria	Cafeteria			8/13/2008		154		\$0.00
Medium	Work In Progress				8/13/2008 8:12:29 AM				
Moncayo, Fernando		SNP WAREHOUSE: WALK IN REFRIG. NEEDS TO BE RECHECK TEMP. THIS MORNING WAS AT 42.							
Jacqueline Aguilar		JOHNNY LECHUGA SNP MGR 882-6927							
37267	Office				8/21/2008		146		\$0.00
Medium	Work In Progress	Awing/162/Securit			8/20/2008 10:01:58 PM				
Lozoya, Manny		"W" key is getting jammed.							
Maricruz Carrasco									
37270	Classroom				8/21/2008		146		\$0.00
Medium	Work In Progress	Awing/159/E.			8/20/2008 10:06:16 PM				
Lozoya, Manny		Door does not close and lock.							
Maricruz Carrasco									
37358	Portables				8/25/2008		142		\$0.00
Medium	Work In Progress	Double Portable			8/25/2008 12:42:33 PM				
Solis, Lorenzo		Double Portable - Need to cover all registers properly.							
Michael Munoz									
37763	C-Wing	Classroom			9/3/2008		133		\$0.00
Medium	Work In Progress	Cwing/C-			9/3/2008 9:29:19 PM				
Lozoya, Manny		Door does not lock. Safety issue.							
Maricruz Carrasco									
37764	C-Wing	Office			9/3/2008		133		\$0.00
Medium	Work In Progress	Cwing/Dr. Montes			9/3/2008 9:30:21 PM				
Lozoya, Manny		Door does not lock.							
Maricruz Carrasco									
37770	Portables				9/4/2008		132		\$0.00
Medium	Work In Progress				9/4/2008 8:13:40 AM				
Sotelo, Enrique		Please provide electrical connection to 2 Bard units.							
Lorenzo Solis									
38384	Gym	Gym			9/24/2008		112		\$0.00
Medium	Work In Progress	Gym/Lockerroom			9/23/2008 10:02:16 PM				
Diaz, Sebastian		Lockers need to get fixed. Please check with Dr. Garcia for specific instructions.							
Maricruz Carrasco									
38385					9/24/2008		112		\$0.00
Medium	Work In Progress	All GMS Staff			9/23/2008 10:06:29 PM				
Lozoya, Manny		All staff restrooms to have latch placed on door for privacy reasons.							
Maricruz Carrasco									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
38417	C-Wing				9/24/2008		112		\$0.00
Medium	Work In Progress			9/24/2008 3:44:29 PM					
Lozoya, Manny	New Portable - 1st thing tomorrow need to recore like GMS (see Mike if u have any questions).								
Michael Munoz									
38464	C-Wing				9/26/2008		110		\$0.00
Medium	Work In Progress			9/26/2008 12:26:38 PM					
Lozoya, Manny	Mr. Chacon, Band Director needs a gate key for gate by C-Wing.								
Michael Munoz									
38485					9/26/2008		110		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:32:43 PM					
Lozoya, Manny	Need three WA-83 keys. Need two V-3 keys.								
Maricruz Carrasco									
38486					9/26/2008		110		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:34:17 PM					
Lozoya, Manny	Need two keys made for golf cart.								
Maricruz Carrasco									
38487	C-Wing	Portables			9/26/2008		110		\$0.00
Medium	Work In Progress	C-wing/New		9/26/2008 4:35:35 PM					
Lozoya, Manny	Fix lock to main entrance on new portable-Health Center								
Maricruz Carrasco									
38651	Annex				10/2/2008		104		\$0.00
Medium	Work In Progress			10/2/2008 3:20:00 PM					
Lozoya, Manny	Need fix handi cup door in annex bldg thank you								
Sebastian Diaz									
39040					10/8/2008		98		\$0.00
Medium	Work In Progress			10/8/2008 3:45:14 PM					
Ronquillo, Ruben	Need 4 window blinds for new portable 30"X60 thank you								
Sebastian Diaz									
39212	Gym	Gym			10/14/2008		92		\$0.00
Medium	Work In Progress	Gym/Boys Locker		10/14/2008 9:44:16 AM					
Diaz, Sebastian	Lockers need to be reinforced with plywood. Please see Mr. Mitchell for more information.								
Maricruz Carrasco									
39213		Office			10/14/2008		92		\$0.00
Medium	Work In Progress	Dr. Garcia's		10/14/2008 9:56:39 AM					
Lozoya, Manny	Install lock on black storage cabinet for Maricruz.								
Maricruz Carrasco									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
39603					10/30/2008		76		\$0.00
Medium	Work In Progress	GMS		10/30/2008 12:02:54					
Diaz, Sebastian		Remove light bulbs from specific areas. See Nancy for a list.							
Maricruz Carrasco									
39856					11/5/2008		70		\$0.00
Medium	Work In Progress			11/5/2008 2:20:53 PM					
Lozoya, Manny		Controls contractor (Trane) Needs keys to access building on Monday Nov. 10							
Alfredo Holguin									
39910	C-Wing	Portables			11/6/2008		69		\$0.00
Medium	Work In Progress			11/6/2008 2:25:24 PM					
Holguin, Alfredo		Connect Electrical service to new portable for School Based Health Clinic							
Alfredo Holguin									
40147	C-Wing				11/17/2008		58		\$0.00
Medium	Work In Progress			11/17/2008 2:29:35 PM					
Lozoya, Manny		Nursing Coordinator Offices - Rekey - check with Ms. Cregan on keying							
Alfredo Holguin									
40601		Cafeteria			12/4/2008		41		\$0.00
Medium	Work In Progress			12/4/2008 4:02:49 PM					
Moncayo, Fernando		SNP Warehouse - Some windows are broken and seals are poor in existing windows allowing a large amount of dust to come in where food is being stored. Good lighting is available therefore, we are requesting that the windows be covered with plywood and sealed to prevent contamination of food items.							
		Johnny Lechuga - SNP Warehouse							
Alma Terrell									
40612	Cafeteria	Cafeteria			12/5/2008		40		\$0.00
Medium	Work In Progress			12/5/2008 8:16:38 AM					
Ontiveros, Guadalupe		SNP Warehouse: The SNP Warehouse docking area ground has become unlevelled creating pot holes that hold water and dirt is very loose. Please level and install gravel/crusher fine to eliminate the loose dust.							
Jacqueline Aguilar									
40785					12/11/2008		34		\$0.00
Medium	Work In Progress	A wing / Sped		12/11/2008 10:29:02					
Lozoya, Manny		Re-Key File Cabinet							
Maricruz Carrasco									
40786		Classroom			12/11/2008		34		\$0.00
Medium	Work In Progress	A wing / 178		12/11/2008 10:30:20					
Lozoya, Manny		Repair Lock to File Cabinet							
Maricruz Carrasco									
1/14/2009 11:38:14 AM									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
40787					12/11/2008		34		\$0.00
Medium	Work In Progress	B Wing / New		12/11/2008 10:31:39					
Lozoya, Manny	Re-Key to A53								
Maricruz Carrasco									
40788					12/11/2008		34		\$0.00
Medium	Work In Progress	C wing/ 211		12/11/2008 10:33:38					
Lozoya, Manny	Re-key off Master- for JPO office-see Connie-ok'd by Dr. Garcia								
Maricruz Carrasco									
41035					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:34 AM					
Diaz, Sebastian	Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
41053					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:42 AM					
Diaz, Sebastian	Monthly - Gadsden MS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
41109					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:04 AM					
Diaz, Sebastian	Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41114					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:07 AM					
Diaz, Sebastian	Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41220	Annex				1/6/2009		8		\$0.00
Medium	Work In Progress	GMS		1/6/2009 4:52:10 PM					
Ontiveros, Guadalupe	Two large holes between Annex and portable need to be filled with dirt. Please see Dr. Garcia for more information.								
Maricruz Carrasco									
41221					1/6/2009		8		\$0.00
Medium	Work In Progress	GMS Campus		1/6/2009 4:53:38 PM					
Ontiveros, Guadalupe	Uprooted tree needs to be covered with dirt. Please see Dr. Garcia for more information.								
Maricruz Carrasco									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
41222					1/6/2009		8		\$0.00
Medium	Work In Progress	GMS Campus		1/6/2009 4:56:28 PM					
Ontiveros, Guadalupe		GMS tables/benches stored in warehouse need to be set up on GMS Campus. Please see Dr. Garcia for more information.							
Maricruz Carrasco									
41266					1/8/2009		6		\$0.00
Medium	Work In Progress			1/8/2009 10:14:34 AM					
Lozoya, Manny		NEED TO INSTALL CORES IN NEW ANNEX BUILDING.							
41314					1/9/2009		5		\$0.00
Medium	Work In Progress			1/9/2009 11:35:55 AM					
Gonzalez, Salvador		Eastside Double Gate (by canal) Broken. Gate totally off hinges.							
Yolie Jacquez									
41348					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:20 AM					
Acosta, Juan		Monthly - QRTLY BLDG INSP REPORT (GM) - Refer to PM schedule details.							
Margret Villalobos									
41379	Band Room	Portables			1/11/2009		3		\$0.00
Safety	Work In Progress	C-213 and Band		1/11/2009 12:27:24 AM					
Munoz, Michael		Fence needs to be placed to close the campus by C-213, Mr. Martinez's classroom and the Band room. This will help stop the ditching in that area and also stop any vandalism to the vehicles							
Maricruz Carrasco									
41380	C-Wing	Office			1/11/2009		3		\$0.00
Medium	Work In Progress	Cwing/Big		1/11/2009 12:29:27 AM					
Diaz, Sebastian		Heater does not work.							
Maricruz Carrasco									
41381		Classroom			1/11/2009		3		\$0.00
Medium	Work In Progress	Bwing/140/G.		1/11/2009 12:32:19 AM					
Diaz, Sebastian		White board on north wall not cleanable. Can't use it. Please remove in order for teacher to use chalkboard							
Maricruz Carrasco									
41382	Gym	Gym			1/11/2009		3		\$0.00
Medium	Work In Progress	Gym/Boys and		1/11/2009 12:34:27 AM					
Appelzoller, Fred		Toilets in both coaches offices restrooms leak when flushed.							
Maricruz Carrasco									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Gadsden MS							
41386		Library			1/11/2009		3		\$0.00
Medium	Work In Progress	Awing/GMS New			1/11/2009 12:52:18 AM				
Acosta, Juan		Clean shelves to be placed in New Library.							
Maricruz Carrasco									
41393	C-Wing	Office			1/12/2009		2		\$0.00
Medium	Work In Progress	201			1/12/2009 10:26:12 AM				
Diaz, Sebastian		Heater in Irene Ortiz's room does not work							
Colleen Runyan									
41395	Cafeteria	Cafeteria			1/12/2009		2		\$0.00
Medium	Work In Progress				1/12/2009 10:40:33 AM				
Orozco, Danny		SNP Warehouse Freezer #3: Timer needs to be replaced							
		Johnny R. Lechuga SNP WHSE MGR 882-6927							
Jacqueline Aguilar									
Count: 53 Work Orders		Avg. Age of WO's 77			Total for Gadsden MS			0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
Location:		La Union - JTP Alvarez Farms							
41420		Restroom (Girls)			1/13/2009		1		\$0.00
Medium	Work In Progress				1/13/2009 8:03:50 AM				
Villalobos, Margret		CONTACT: SAM AVALOS 580-3008				1/13 - Emailed Watson for Price Quote.			
		PLEASE SPRAY FOR COCKROACHES IN THE BUILDING							
Margaret Villalobos									
Count: 1 Work Orders		Avg. Age of WO's 1		Total for La Union - JTP Alvarez Farms				0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		La Union ES								
35705					7/6/2008	8/6/2008	192		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:09 AM						
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
35791		Cafeteria			7/9/2008		189		\$0.00	
Medium	Work In Progress			7/9/2008 1:48:49 PM						
Moncayo, Fernando		OVENS NEED TO BE CHECKED. SOMETIMES THEY WILL HEAT UP AND THEN STOP HEATING ALL OF A SUDDEN.								
		LINDA YANAGA SNP MGR 589-2040								
Jacqueline Aguilar										
35792		Cafeteria			7/9/2008		189		\$0.00	
Medium	Work In Progress			7/9/2008 1:49:55 PM						
Moncayo, Fernando		PASS THRU REFRIG. IS FREEZING UP.								
		LINDA YANAGA LU SNP MGR 589-2040								
Jacqueline Aguilar										
35921					7/13/2008	7/29/2008	185		\$0.00	
Medium	Work In Progress			7/13/2008 12:18:11 AM						
Gonzalez, Salvador		Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos										
36544					8/3/2008	8/11/2008	164		\$0.00	
Medium	Work In Progress			8/3/2008 12:20:27 AM						
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos										
36590					8/4/2008		163		\$0.00	
Medium	Work In Progress			8/4/2008 10:36:40 AM						
Castillo, Carlos		Run elect. to morgom maint storage - would be nice to use fan								
Patricio Aguilar										
36996		Cafeteria			8/13/2008		154		\$0.00	
Medium	Work In Progress			8/13/2008 8:23:00 AM						
Moncayo, Fernando		REACH THRU REFRIG. DOES NOT COOL TEMP IS AT 50								
		LINDA YANAGA SNP MGR 589-2040								
Jacqueline Aguilar										
37040	Annex Building				8/13/2008		154		\$0.00	
Medium	Work In Progress			8/13/2008 4:17:56 PM						
Castillo, Carlos		Install electrical for kiln in room # 203								
Alfredo Holguin										
1/14/2009 11:38:15 AM										

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
37120					8/15/2008		152		\$0.00
Medium	Work In Progress			8/15/2008 3:17:51 PM					
Carrasco, Danny	Need 3 gfi elect out lets #202								
Patricio Aguilar									
37960					9/9/2008		127		\$0.00
Medium	Work In Progress			9/9/2008 2:37:27 PM					
Castillo, Carlos	NEED TO HAVE LIGHT POLES, AND LIGHTS ON WEST PARKING LOT CHECKED THEY ARE OFF, ONLY A FEW LIGHTS COME ON, POSSIBLE LIGHTING DAMAGE.								
Arturo Nunez									
38034					9/11/2008		125		\$0.00
Medium	Work In Progress			9/11/2008 3:14:33 PM					
Villalobos, David	pat aguilar need rubber bushing for water faucet - thank you								
Patricio Aguilar									
38036					9/11/2008		125		\$0.00
Medium	Work In Progress			9/11/2008 3:22:31 PM					
Ambriz, Jose	pat aguilar wants her refrigerated ac replaced - that it is to loud								
Patricio Aguilar									
38186		Restroom (Girls)			9/17/2008		119		\$0.00
Medium	Work In Progress			9/17/2008 3:28:46 PM					
Lara, Ralph	The door knob for female rest room will not lock - thank you								
Patricio Aguilar									
40988					12/18/2008		27		\$0.00
Medium	Work In Progress			12/18/2008 3:20:23 PM					
Ambriz, Jose	pat aguilar the thermostat not working right - dayton electric heater model 2e441 ser 143933 volts 240/208 wats 4800/2500 60 hz 13tu 16382/11946								
Patricio Aguilar									
41037					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:35 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
41055					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:43 AM					
Aguilar, Patricio	Monthly - La Union ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
41112					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:06 AM					
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41120					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:09 AM					
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41167					1/5/2009		9		\$0.00
Medium	Work In Progress			1/5/2009 3:33:50 PM					
Ambriz, Jose	pat aguilar heater boiler pump taco model fm1207 has a bad bearing								
Patricio Aguilar									
41244					1/7/2009		7		\$0.00
Medium	Work In Progress			1/7/2009 3:11:39 PM					
Lara, Ralph	pat aguilar need a new frame & door for rest room r210								
Patricio Aguilar									
41245					1/7/2009		7		\$0.00
Medium	Work In Progress			1/7/2009 3:14:33 PM					
Lara, Ralph	pat aguilar need same kind of lock on door to keep children in								
Patricio Aguilar									
41349					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:21 AM					
Galindo, Santos	Monthly - QRTLY BLDG INSP REPORT (LU) - Refer to PM schedule details.								
Jesus Estrada									
41369					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:28 AM					
Aguilar, Patricio	Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
Count: 23 Work Orders			Avg. Age of WO's	93	Total for La Union ES			0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
35703					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:20:08 AM					
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36116					7/22/2008		176		\$0.00
Medium	Work In Progress			7/22/2008 12:27:51 PM					
Lozoya, Manny		Manny, needing door in room 212 repaired							
Grace Alvarado									
36408					7/31/2008		167		\$0.00
Medium	Work In Progress			7/31/2008 2:26:46 PM					
Ronquillo, Ruben		Need to replace 10 more blinds.							
Rudy Arreola									
36686					8/6/2008		161		\$0.00
Medium	Work In Progress			8/6/2008 3:03:22 PM					
Lozoya, Manny		Rm 111 needs to have lock installed in her filing cabinet.							
Rudy Arreola									
36898					8/11/2008		156		\$0.00
Medium	Work In Progress			8/11/2008 3:03:50 PM					
Lozoya, Manny		We need a lock installed in a filing cabinet in RM 201							
Rudy Arreola									
37058		Portables			8/14/2008		153		\$0.00
Medium	Work In Progress			8/14/2008 10:22:44 AM					
Arreola, Rudy		Complete skirting installation on double portable							
Alfredo Holguin									
37174		Classroom			8/19/2008		148		\$0.00
Medium	Work In Progress			8/19/2008 7:48:48 AM					
Sotelo, Enrique		Rm 111 the emergency light is out not working at all.							
Rudy Arreola									
37711		Athletic Field			9/2/2008		134		\$0.00
Medium	Work In Progress			9/2/2008 3:15:39 PM					
Ontiveros, Guadalupe		Water leak from one of the irrigation line its coming from under the cement. by the basketball courts area.							
Rudy Arreola									
38220		Classroom			9/18/2008		118		\$0.00
Medium	Work In Progress			9/18/2008 2:36:13 PM					
Ronquillo, Ruben		Windows in RM 205 are hard to open and wont stay up.TOTAL of 3							
Rudy Arreola									
38221		Classroom			9/18/2008		118		\$0.00
Medium	Work In Progress			9/18/2008 2:37:10 PM					
Ronquillo, Ruben		Windows in RM 201 is very hard to open TOTAL of 2.							
Rudy Arreola									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
38222					9/18/2008		118		\$0.00
Medium	Work In Progress			9/18/2008 2:37:50 PM					
Ronquillo, Ruben	Window in RM 204 wont stay up TOTAL of 1.								
Rudy Arreola									
38782					10/5/2008	10/26/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:04 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
38964					10/6/2008		100		\$0.00
Medium	Work In Progress			10/6/2008 1:40:46 PM					
Carrasco, Danny	Need pressure washer and hose to wash off wall of the east side of main bldg.								
Rudy Arreola									
38973					10/6/2008		100		\$0.00
Medium	Work In Progress			10/6/2008 2:55:14 PM					
Sotelo, Enrique	We need more outlets in coaches office.								
Rudy Arreola									
39414					10/23/2008		83		\$0.00
Medium	Work In Progress			10/23/2008 12:22:29					
Sotelo, Enrique	Asp PM 38922 Emerg. Light not workin in boys rr and entrance. (ck w/Rudy for location)								
Rudy Arreola									
39613					10/30/2008		76		\$0.00
Medium	Work In Progress			10/30/2008 1:29:28 PM					
Lozoya, Manny	Need new lock for popcorn machine.								
Rudy Arreola									
39614					10/30/2008		76		\$0.00
Medium	Work In Progress			10/30/2008 1:30:36 PM					
Lozoya, Manny	Door handle is broken in RM 212								
Rudy Arreola									
39615					10/30/2008		76		\$0.00
Medium	Work In Progress			10/30/2008 1:32:10 PM					
Lozoya, Manny	Library door is getting stuck.								
Rudy Arreola									
39616					10/30/2008		76		\$0.00
Medium	Work In Progress			10/30/2008 1:34:22 PM					
Lozoya, Manny	Door handle is getting stuck in womens rr.								
Rudy Arreola									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
39762					11/3/2008		72		\$0.00
Medium	Work In Progress			11/3/2008 7:52:22 AM					
Ronquillo, Ruben			Need 6 signs that say NO PARKING 7.AM. TO 4P.M. MOM THRU FRIDAY						
Rudy Arreola									
40091					11/14/2008		61		\$0.00
Medium	Work In Progress			11/14/2008 1:23:35 PM					
Arreola, Rudy			Need a plate for bottom of poles to relocate handicapp spaces total of 4.			11/21/08			
Rudy Arreola						Asp Sal route to Rudy, plates will not hold sign. Asphalt will break and is weak. Rudy needs to break asphalt w/Hilti make hole w/post hole dig and pour concrete. Thanks Mike			
40216	Main Building	Restroom (Boys)			11/19/2008		56		\$0.00
Medium	Work In Progress			11/19/2008 11:20:53					
Arreola, Rudy			Boys RR Eastside by cafe -Check and reappear Exhaust Fan, smells like urine. (When complete, please contact M.Munoz for inspection)						
Michael Munoz									
40530					12/3/2008		42		\$0.00
Medium	Work In Progress			12/3/2008 12:58:09 PM					
Arreola, Rudy			*11*14*08* 2.0 Removed handicapp signs. 1.5 Went to shop. 4.0 Painting handicapp signs. 1.0 Doing paperwork.			11/14 - 8			
Rudy Arreola									
40649					12/7/2008	12/23/2008	38		\$0.00
Medium	Work In Progress			12/7/2008 12:16:15 AM					
Arreola, Rudy			Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.						
George ZZ Gabaldon									
40791					12/11/2008		34		\$0.00
Medium	Work In Progress			12/11/2008 12:35:13					
Lozoya, Manny			We need a new lock for new gate that was installed						
Rudy Arreola									
40792					12/11/2008		34		\$0.00
Medium	Work In Progress			12/11/2008 12:37:00					
Lozoya, Manny			Overhead file cabinet does not lock need a new lock installed.						
Rudy Arreola									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
40793					12/11/2008		34		\$0.00
Medium	Work In Progress				12/11/2008 12:38:32				
Carrasco, Danny	Total of 180 ceiling tiles that were damaged on 12/9/09-12/10/08.								
Rudy Arreola									
41038					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:36 AM				
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
41056					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:44 AM				
Arreola, Rudy	Monthly - Loma Linda ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
41073					1/4/2009	1/25/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:50 AM				
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
41113					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:19:06 AM				
Arreola, Rudy	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41122					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:19:10 AM				
Arreola, Rudy	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41263	Main Building	Library			1/8/2009		6		\$0.00
Medium	Work In Progress				1/8/2009 8:30:20 AM				
Solis, Luis	Shampoo and extract carpet, coordinate with your building mechanic. The carpet cleaning will take place after the walls are painted. If you have any questions call me.								
Jesus Estrada									
41264	Main Building	Library			1/8/2009		6		\$0.00
Medium	Work In Progress				1/8/2009 8:33:48 AM				
Acuna, Sal	(For Jimmy and Sal) Help custodial crew at Loma Linda shampoo and extract carpet in library. Date still pending.								
Jesus Estrada									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Loma Linda ES										
41323		Library			1/9/2009		5		\$0.00	
Medium	Work In Progress				1/9/2009 3:19:20 PM					
Arreola, Rudy		please paint library before shelving is installed. thxs								
Michael Munoz										
41350					1/11/2009	1/27/2009	3		\$0.00	
Medium	Work In Progress				1/11/2009 12:17:21 AM					
Solis, Luis		Monthly - QRTLY BLDG INSP REPORT (LL) - Refer to PM schedule details.								
Jesus Estrada										
41370					1/11/2009	1/27/2009	3		\$0.00	
Medium	Work In Progress				1/11/2009 12:17:29 AM					
Arreola, Rudy		Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos										
Count: 37 Work Orders		Avg. Age of WO's 75		Total for Loma Linda ES			0	\$0.00		

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
35549					7/6/2008	7/12/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:20 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35567					7/6/2008	7/14/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:26 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35626					7/6/2008	7/14/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:44 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35636					7/6/2008	7/14/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:47 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35661					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:55 AM					
Ramirez, Joe	Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35684					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:20:02 AM					
Ramirez, Joe	Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35706					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:20:09 AM					
Villalobos, David	Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36109					7/22/2008		176		\$0.00
Medium	Work In Progress			7/22/2008 10:11:48 AM					
Lozoya, Manny	on (work room) needs a cylinder with a key they have school files need to be lock all the time as per montano principal asap. thank you. luis								
<u>Luis Saucedo</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
36147	Main Building	Office			7/23/2008		175		\$0.00
Medium	Work In Progress	Main office area		7/23/2008 12:29:38 PM					
Lozoya, Manny	Main office need's (4) engraved plaque's for front office door. Name and Title (Jacob Montano, Principal), (Sandra Mora, Secretary), (Dora Lerma, Data-Entry Clerk), (Maribel Villela, Receptionist-Clerk) for Manny Lozoya.								
Sandra Mora									
36227		Portables			7/25/2008		173		\$0.00
Medium	Work In Progress			7/25/2008 2:11:53 PM					
Lozoya, Manny	Ms. Flores room # 801 has filing cabinet that doesn't have a key, need's to be re-key.								
Sandra Mora									
36245					7/28/2008		170		\$0.00
Medium	Work In Progress			7/28/2008 7:44:32 AM					
Ramirez, Joe	please need to check water pump we have flood on barracks on 7/29/08 between the blds. thank you.								
Luis Saucedo									
36256	2003 Classroom	Classroom			7/28/2008		170		\$0.00
Medium	Work In Progress	Portable room #		7/28/2008 8:30:02 AM					
Lozoya, Manny	Ms. Jimenez, portable room # 506 she has a storage cabinet needs to be re-key.								
Sandra Mora									
36259	2003 Classroom	Classroom			7/28/2008		170		\$0.00
Medium	Work In Progress	Kinder hallway,		7/28/2008 8:58:17 AM					
Lozoya, Manny	Need a master for that room # 405 for our inventory, and key # 305.								
Sandra Mora									
36507					8/3/2008	8/9/2008	164		\$0.00
Medium	Work In Progress			8/3/2008 12:20:15 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
36539					8/3/2008	8/11/2008	164		\$0.00
Medium	Work In Progress			8/3/2008 12:20:26 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36549					8/3/2008	8/11/2008	164		\$0.00
Medium	Work In Progress			8/3/2008 12:20:29 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
36577					8/4/2008		163		\$0.00
Medium	Work In Progress			8/4/2008 5:44:47 AM					
Ramirez, Joe	please need to chek the roof this mornig we got a few big leak in the cafeteeria from the rain.thank you luis.								
<u>Luis Saucedo</u>									
36885	Main Building	Office			8/11/2008		156		\$0.00
Medium	Work In Progress	Office area		8/11/2008 11:09:39 AM					
Lozoya, Manny	(1) engraved plaque for front office door. Name and Title (Norma Sierra, Assistant Principal) for Manny Lozoya								
<u>Sandra Mora</u>									
37428					8/27/2008		140		\$0.00
Medium	Work In Progress			8/27/2008 5:27:42 AM					
Ramirez, Joe	this morning we have a few leaks in the cafeteria by south side corner. thank you luis								
<u>Luis Saucedo</u>									
37490					8/28/2008		139		\$0.00
Medium	Work In Progress			8/28/2008 3:06:30 PM					
Ramirez, Joe	continue the condensation line to a proper area for drainage.								
<u>Michael Munoz</u>									
37617					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:35 AM					
Ramirez, Joe	Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37618					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:35 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual MCD - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37619					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37620					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual UCD - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
37621					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual UCS2 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37622					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37623					8/31/2008	9/8/2008	136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37624					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37625					8/31/2008		136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual EVS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37626					8/31/2008	9/6/2008	136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37627					8/31/2008	9/8/2008	136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38209					9/18/2008		118		\$0.00
Medium	Work In Progress			9/18/2008 9:17:37 AM					
Sotelo, Enrique	pole lights on the eastside of campus not working.								
<u>Joe Ramirez</u>									
38210					9/18/2008		118		\$0.00
Medium	Work In Progress			9/18/2008 9:18:18 AM					
Sotelo, Enrique	marquee lights not working.								
<u>Joe Ramirez</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
38537					9/30/2008		106		\$0.00
Medium	Work In Progress			9/30/2008 12:26:03 AM					
Ramirez, Joe	Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38589					10/1/2008		105		\$0.00
Medium	Work In Progress			10/1/2008 9:13:56 AM					
Sotelo, Enrique	front porch entrance lights not working need to replace ballasts.								
<u>Joe Ramirez</u>									
38663	Pump House				10/2/2008		104		\$0.00
Medium	Work In Progress			10/2/2008 3:36:10 PM					
Ramirez, Joe	Remove all materials equipment and other supplies stored in this area. This is not a storeroom.		e- mailed 11/5/08 - Please resubmit the work orders to clean out the pump rooms at La Mesa, San Miguel, and Mesquite with notes on them to notify me when they are complete.						
<u>Alfredo Holguin</u>									
38881					10/5/2008	10/11/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:40 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38882					10/5/2008	10/13/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:41 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38883					10/5/2008	10/13/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:41 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38884					10/5/2008	10/13/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:41 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38885					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:42 AM					
Ramirez, Joe	Yearly - Mesquite ES I-4 Fan Coil Unit Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
38886					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:42 AM					
Ramirez, Joe	Yearly - Mesquite ES H-6 Rooftop Furnance Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38887					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:42 AM					
Ramirez, Joe	Yearly - Mesquite ES R-9 Rad Hot Water 2 years - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38888					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:43 AM					
Ramirez, Joe	Yearly - Mesquite ES U-2 Unit Heater Gas Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38889					10/5/2008	10/21/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:43 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39516					10/27/2008		79		\$0.00
Medium	Work In Progress			10/27/2008 3:08:58 PM					
Ramirez, Joe	CLEAN AND SERVICE ALL HEATERS AS PER OUR CONVERSATION. POSSIBLE SAFETY AND FIRE HAZARD. WILL BE INSPECTED.		10/27 - AS PER MIKE, ONCE W.O. 39516 FOR MQ IS COMPLETED, PLEASE GIVE TO MIKE FOR HIS REVIEW. THANKS MG						
<u>Michael Munoz</u>									
39517					10/27/2008		79		\$0.00
Medium	Work In Progress			10/27/2008 3:09:56 PM					
Ramirez, Joe	WEED EAT AROUND CAMPUS (AROUND PICNIC TABLES, TREES ETC.)								
<u>Michael Munoz</u>									
39518					10/27/2008		79		\$0.00
Medium	Work In Progress			10/27/2008 3:10:45 PM					
Ramirez, Joe	REPAIR HOLE IN SHEET ROCK AND INSTALL DOOR STOP BY LARRY SEDILLO'S ROOM.								
<u>Michael Munoz</u>									
39519					10/27/2008		79		\$0.00
Medium	Work In Progress			10/27/2008 3:11:39 PM					
Ramirez, Joe	GRASS IS GROWING IN DRAIN GRID BY BUS TURN AROUND.								
<u>Michael Munoz</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
39692					11/2/2008	11/8/2008	73		\$0.00
Medium	Work In Progress			11/2/2008 12:24:35 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39724					11/2/2008	11/10/2008	73		\$0.00
Medium	Work In Progress			11/2/2008 12:24:47 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39734					11/2/2008	11/10/2008	73		\$0.00
Medium	Work In Progress			11/2/2008 12:24:50 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39854	Pump House				11/5/2008		70		\$0.00
Medium	Work In Progress			11/5/2008 2:17:45 PM					
Ramirez, Joe	Remove roof turbin/ventilator and patch roof.								
<u>Alfredo Holguin</u>									
40256					11/20/2008		55		\$0.00
Medium	Work In Progress			11/20/2008 9:34:58 AM					
Lozoya, Manny	file cabinet in rm 405 needs a new lock installed the other was damaged.								
<u>Joe Ramirez</u>									
40421					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress			11/30/2008 12:23:48					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40422					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress			11/30/2008 12:23:48					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40423					11/30/2008	12/6/2008	45		\$0.00
Medium	Work In Progress			11/30/2008 12:23:49					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
41039					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:36 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1/14/2009 11:38:15 AM

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
41057					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:44 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41115					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:07 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41125					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:12 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41227	Main Building	Classroom			1/7/2009		7		\$0.00
Medium	Work In Progress	Room # 203		1/7/2009 8:59:31 AM					
Lozoya, Manny	Key is needed for Pamela Uribe IA to that classroom.								
<u>Sandra Mora</u>									
41305		Classroom			1/9/2009		5		\$0.00
Medium	Work In Progress			1/9/2009 8:12:50 AM					
Lozoya, Manny	Rm 608 (Wendy Tow) - Door continues to stick, even after it has been fixed.								
<u>Joe Ramirez</u>									
41351					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:21 AM					
Saucedo, Luis	Monthly - QRTLY BLDG INSP REPORT (MQ) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
Count: 64	Work Orders		Avg. Age of WO's	114		Total for Mesquite ES	0		\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
36463		Office			8/1/2008		166		\$0.00
Medium	Work In Progress	room 400		8/1/2008 11:44:39 AM					
Lozoya, Manny		Hello Manny, The alarm box key was broken off, please replace.							
<u>Priscilla Martinez</u>									
37136		Office			8/18/2008		149		\$0.00
Medium	Work In Progress	video		8/18/2008 10:18:19 AM					
Lozoya, Manny		could not locate a key							
Priscilla Martinez		Need a black box located in our office to be opened, could not locate the correct key in our vault							
37221		Classroom			8/20/2008		147		\$0.00
Medium	Work In Progress	various		8/20/2008 9:15:00 AM					
Lozoya, Manny		Send Lozoya to make various keys for various classrooms, desks, cabinets, filing cabinets, storage closets,							
Priscilla Martinez		please visit the front office for this list of keys that are needed, thanks Priscilla							
<u>Priscilla Martinez</u>									
38084		Classroom			9/15/2008		121		\$0.00
Medium	Work In Progress			9/15/2008 1:35:12 PM					
Lozoya, Manny		need a key made for Larry Roybal (Deputy Dona Ana County Sheriff) for the gates at North Valley Elementary							
<u>Priscilla Martinez</u>									
38743					10/5/2008		101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:50 AM					
Holguin, Alfredo		Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos		10/6/08 - Emailed to Ricky Borrego							
39280					10/20/2008		86		\$0.00
Medium	Work In Progress			10/20/2008 9:11:35 AM					
Lozoya, Manny		need new pad lock for bus exit gate/had to cut old lock this morning-key didnt turn core							
<u>Danny Vega</u>									
39383					10/22/2008		84		\$0.00
Medium	Work In Progress			10/22/2008 1:41:03 PM					
Lozoya, Manny		p.e coaches office door will not open -core will not turn with key-please ck out asap							
<u>Danny Vega</u>									
39456		Classroom			10/24/2008		82		\$0.00
Medium	Work In Progress	room 210		10/24/2008 12:13:11					
Lozoya, Manny		black file cabinet w/blue sticker does not lock.							
Priscilla Martinez									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
39804					11/4/2008		71		\$0.00
Medium	Work In Progress			11/4/2008 9:20:53 AM					
Lozoya, Manny	need key made for rm 304 art rm/cabinet key broke in core-need to lock-up supplies asap								
<u>Danny Vega</u>									
40731					12/10/2008		35		\$0.00
Medium	Work In Progress			12/10/2008 7:40:36 AM					
Sotelo, Enrique	need 24 ea blue flourescent lamp covers /same as syle as before.rm 213 speech rm								
<u>Danny Vega</u>									
40742					12/10/2008		35		\$0.00
Medium	Work In Progress			12/10/2008 11:12:53					
Vega, Danny	Please pick up easel from room 210 Deanna Gurrola and bring back to GAC/SPED Office. Julie/Anna								
<u>Anna Alvarez</u>									
40891					12/16/2008		29		\$0.00
Medium	Work In Progress			12/16/2008 8:10:47 AM					
Lozoya, Manny	need duplicate from rm 306/cabinet keys- parent center (402) has 01 and 06 key locks-need to give rm 402 a 06 key								
<u>Danny Vega</u>									
41041					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:37 AM					
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41118					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:09 AM					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41129					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:14 AM					
Vega, Danny	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41143					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:20 AM					
Vega, Danny	Monthly - North Valley ES Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
Location:		North Valley ES							
41151					1/4/2009		10		\$0.00
Medium	Work In Progress				1/4/2009 12:19:23 AM				
Holguin, Alfredo		Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.			1/6/09 - E-mailed to ricky.borrego@cummins.com'				
Margret Villalobos									
41354					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:22 AM				
Parra, Javier		Monthly - QRTLY BLDG INSP REPORT (SM) - Refer to PM schedule details.							
Jesus Estrada									
41378					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:32 AM				
Vega, Danny		Monthly - North Valley ES Playground Inspection - Refer to PM schedule details.							
Margret Villalobos									
41436					1/13/2009		1		\$0.00
Medium	Work In Progress				1/13/2009 12:15:10 PM				
Carbajal, Jimmy		back wheels on vacuum broke							
Javier Parra									
Count: 20 Work Orders		Avg. Age of WO's		58	Total for North Valley ES			0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
35704					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:20:09 AM					
Villalobos, David	Yearly - Northern Pre-K (LM) Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36680					8/6/2008		161		\$0.00
Medium	Work In Progress	Playground		8/6/2008 11:23:04 AM					
Vega, Danny	New playground structure is complete. We need plastice lining and Round-up applied so that area can be filled in with sand. We also need a sand box moved, enlarged and filled with sand.		8/11 - Asp Lupe route to D. Vega						
Gilbert Trujillo									
37300					8/21/2008		146		\$0.00
Medium	Work In Progress			8/21/2008 3:03:06 PM					
Vega, Danny	8-18-08				8/18-8				
	.5-ck wk ods in office nve								
	2.5-ck and clean a/c unit distributors la mesa pre-k								
	5-cut weeds and spray round-up at la mesa								
Danny Vega									
37774		Athletic Field			9/4/2008		132		\$0.00
Medium	Work In Progress			9/4/2008 8:52:16 AM					
Lozoya, Manny	send us the lock and chain to secure the west gate								
Gilbert Trujillo									
37775	Main Building	Restroom (Girls)			9/4/2008		132		\$0.00
Medium	Work In Progress	classroom 114		9/4/2008 9:33:49 AM					
Lozoya, Manny	Bathroom door in the baby room won't close.								
Concepcion Montalvo									
39602	Pump House	Pump House			10/30/2008		76		\$0.00
Medium	Work In Progress			10/30/2008 9:07:18 AM					
Lozoya, Manny	please change lock back to original lock on irrigation well thanks								
Ricardo Jacquez									
39905		Restroom (Boys)			11/6/2008		69		\$0.00
Medium	Work In Progress			11/6/2008 10:29:38 AM					
Lozoya, Manny	alma de valle restroom door need to be worked on.								
Gilbert Trujillo									
40019	Main Building	Classroom			11/12/2008		63		\$0.00
Medium	Work In Progress			11/12/2008 8:35:22 AM					
Sotelo, Enrique	classroom plug switch is shorted out.room 112								
Gilbert Trujillo									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
40149		Athletic Field			11/17/2008		58		\$0.00
Medium	Work In Progress			11/17/2008 2:34:09 PM					
Ontiveros, Guadalupe	Remove concret rock from sand box								
Alfredo Holguin									
41036					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:35 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
41054					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:43 AM					
Vega, Danny	Monthly - La Mesa ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
41110					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:05 AM					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41116					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:08 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41304	Main Building				1/9/2009		5		\$0.00
Medium	Work In Progress			1/9/2009 8:07:06 AM					
Ontiveros, Guadalupe	please remove evergreens, chineseelms and trim other bushes and hedges on entrance as per our conversation. thxs								
Michael Munoz									
41352					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:22 AM					
Trujillo, Gilbert	Monthly - QRTLY BLDG INSP REPORT (LM/PRE-K) - Refer to PM schedule details.								
Jesus Estrada									
41371					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:29 AM					
Vega, Danny	Monthly - Northern On-Track Pre-K Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
Count: 16 Work Orders			Avg. Age of WO's	68		Total for Northern On-Track Pre-K (LM)	0		\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

35707					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress				7/6/2008 12:20:10 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36213	Maintenance				7/25/2008		173		\$0.00
Medium	Work In Progress				7/25/2008 10:15:21 AM				
Sotelo, Enrique		please install electrical outlet to cooling duct fan and pilot switch. Thxs							
Michael Munoz									
36291					7/28/2008		170		\$0.00
Medium	Work In Progress				7/28/2008 3:26:53 PM				
Ronquillo, Ruben		Purchase a new water tank							
Alfredo Holguin									
36355	Food Services	Parking Lot			7/30/2008		168		\$0.00
Medium	Work In Progress	SNP			7/30/2008 12:01:33 PM				
Ontiveros, Guadalupe		AS PER MR. GIOVAS-IF NEAR THE WAREHOUSE GOING FROM THE SHADED AREA TO THE STAIR WAY INTO THE WAREHOUSE IF THEY CAN LEVEL OUT THE PATH WAY. (PLEASE SEE JOHNNY L. IF NEED DIRECTION.)							
Mary Garcia									
36759	Maintenance				8/7/2008		160		\$0.00
Medium	Work In Progress				8/7/2008 9:53:28 AM				
Munoz, Michael		Need price quote to build an architect table for Tech's Office.							
Michael Munoz									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
37066					8/14/2008		153		\$0.00
Medium	Work In Progress			8/14/2008 11:15:18 AM					
Ronquillo, Ruben	Purchase new individual signs to go above doors outside Bldg. indicating as follows: -Purchasing Warehouse -Instructional Materials -Physical Plant Dept./ Construction Dept./Custodial Dept. -Custodial Shipping/Receiving Also 1 sign for Main Entrance by Nurse Complex indicating as follows: Construction Dept. Instructional Materials Student Nutrition Warehouse Student Records Transportation Physical Plant Department Custodial Dept. Maintenance Dept. Motor Pool Purchasing Warehouse SEE ALFREDO IF ANY QUESTIONS.								
<u>Alfredo Holguin</u>									
37074	Food Services				8/14/2008		153		\$0.00
Medium	Work In Progress			8/14/2008 2:23:06 PM					
Lara, Ralph	As per Mike, remove doubled doors and replace with a rolling door. Please see Mike if you have any questions.								
<u>Michael Munoz</u>									
37767					9/4/2008		132		\$0.00
Medium	Work In Progress			9/4/2008 8:02:44 AM					
Lozoya, Manny	need to replace door lock on water department office does not lock thanks								
<u>Ricardo Jacquez</u>									
37791	Purchasing				9/4/2008		132		\$0.00
Medium	Work In Progress			9/4/2008 2:35:30 PM					
Sotelo, Enrique	I would like to have a light switch in my office to control the lights. Currently the switch is in the hall and the one switch controls my office and hallway.								
<u>Vicky Lopez</u>									
37882	Food Services				9/8/2008		128		\$0.00
Medium	Work In Progress			9/8/2008 8:10:34 AM					
Ontiveros, Guadalupe	Need to add Crusher fines to dock area.								
Alfredo Holguin									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
37888		Parking Lot			9/8/2008		128		\$0.00
Medium	Work In Progress			9/8/2008 8:19:17 AM					
Ronquillo, Ruben		Desigate Handicap Parking for Building and Install signage			9/29 - asp Mike route to Ruben				
Alfredo Holguin									
37889		Parking Lot			9/8/2008		128		\$0.00
Medium	Work In Progress			9/8/2008 8:23:48 AM					
Ronquillo, Ruben		Purchase and Install Parking Signs for the entire PPD Complex. (Vistiors Parking, Employee Parking, No Parking- Loading Zone)							
Alfredo Holguin									
37944					9/9/2008		127		\$0.00
Medium	Work In Progress			9/9/2008 12:13:23 PM					
Gonzalez, Salvador		PLEASE MAKE SCRAPERS/DRAGERS. PLEASE SEE MIKE.							
Michael Munoz									
38130		Parking Lot			9/16/2008		120		\$0.00
Medium	Work In Progress			9/16/2008 11:39:13 AM					
Ronquillo, Ruben		Purchase Sign for Physical Plant Parking Plan as per the layout provided. Signs need to be larger than the standard size.							
Alfredo Holguin									
38639	Maintenance	Office			10/2/2008		104		\$0.00
Medium	Work In Progress			10/2/2008 9:08:26 AM					
Ronquillo, Ruben		SERVICE FOR ASBESTOS ABATEMENT AND CUT OPENING TO BE DONE IN BETWEEN THE PLUMBING AND THE MAINT. WHS.							
Ruben Ronquillo									
39757					11/3/2008		72		\$0.00
Medium	Work In Progress			11/3/2008 12:24:08 AM					
Villalobos, Margret		Monthly - PPD - Quarterly Meeting - Refer to PM schedule details.							
Margret Villalobos									
39941					11/7/2008		68		\$0.00
Medium	Work In Progress			11/7/2008 1:06:01 PM					
Ontiveros, Guadalupe		Gooseneck Trailers 2 ea. - Replace damaged floor boards							
Alfredo Holguin									
39986		Pump House			11/11/2008		64		\$0.00
Medium	Work In Progress			11/11/2008 9:16:37 AM					
Jacquez, Ricardo		need to calibrate flow meters at GMS,GHS,CMS & SRE thanks							
Ricardo Jacquez									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
40909	Motor Vehicle				12/16/2008		29		\$0.00
Medium	Work In Progress				12/16/2008 1:12:43 PM				
Diaz, Sebastian	TUMBLE WEEDS NEED TO BE REMOVED FROM TRANSPORTATION ENTRANCE. THANK YOU.								
Norma Alvarado									
41045					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:39 AM				
Diaz, Sebastian	Monthly - Physical Plant Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
41068					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:48 AM				
Diaz, Sebastian	Monthly - Physical Plant FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
41474	Maintenance				1/14/2009		0		\$0.00
Medium	Work In Progress				1/14/2009 8:35:53 AM				
Lara, Ralph	Need to install a new door 46" for new lounge.								
Michael Munoz									
Count: 22 Work Orders			Avg. Age of WO's	110		Total for Physical Plant Complex	0		\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Riverside ES								
35708					7/6/2008	8/6/2008	192		\$0.00	
Medium	Work In Progress				7/6/2008 12:20:10 AM					
Villalobos, David		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
35753	New Wing 1/02				7/8/2008		190		\$0.00	
Medium	Work In Progress				7/8/2008 10:29:47 AM					
Ronquillo, Ruben		Need window repaired room 137 due to break in 20x21 Add two more broken windows custodian found windows in corrdor by cafe.								
Carlos Hernandez										
36586		Cafeteria			8/4/2008		163		\$0.00	
Medium	Work In Progress				8/4/2008 9:53:07 AM					
Moncayo, Fernando		Oven with Grill is not working/heating up at all. Emilia Carrillo - SNP Manager 589-2550								
Alma Terrell										
36587		Cafeteria			8/4/2008		163		\$0.00	
Medium	Work In Progress				8/4/2008 9:54:27 AM					
Moncayo, Fernando		Walk-In Refrigerator is leaking alot of water Emilia Carrillo - SNP Manager 589-2550								
Alma Terrell										
36669					8/6/2008		161		\$0.00	
Medium	Work In Progress				8/6/2008 8:39:54 AM					
Carrasco, Danny		need fuses for a/c units								
Carlos Hernandez										
37440		Portables			8/27/2008		140		\$0.00	
Medium	Work In Progress				8/27/2008 9:30:51 AM					
Ronquillo, Ruben		broken window on new portable due to vandalism (Case# 2008-1239)								
Carlos Hernandez										
37732		Portables			9/3/2008		133		\$0.00	
Medium	Work In Progress				9/3/2008 8:16:37 AM					
Ronquillo, Ruben		need glass repaired new portable rear glass 40 3/4 by 12 1/2 thanks								
Carlos Hernandez										
37820					9/5/2008		131		\$0.00	
Medium	Work In Progress				9/5/2008 8:39:36 AM					
Gonzalez, Salvador		Need to make a canopy for behind of cafeteria.								
Michael Munoz										

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
39543					10/28/2008		78		\$0.00
Medium	Work In Progress			10/28/2008 1:28:41 PM					
Lozoya, Manny		remove lock from the flashing lights -							
Cora Ramirez									
39660					10/31/2008		75		\$0.00
Medium	Work In Progress			10/31/2008 3:06:06 PM					
Lara, Ralph		needs parts for handicap automatic door opener westside door							
Carlos Hernandez									
40264					11/20/2008		55		\$0.00
Medium	Work In Progress			11/20/2008 3:11:28 PM					
Gonzales, Angel		truck seat needs repair truck #21							
Carlos Hernandez									
40877		Cafeteria			12/15/2008		2	1	\$25.00
Medium	Work In Progress			12/15/2008 3:27:13 PM	12/17/2008				
Moncayo, Fernando		alarm showing dirty duct in cafeteria and dirty 2, 16				12/17/08 ck Dimar Report was showing exhaust fan in kitchen alarm. Ck inside and it reflects to kitchen equip, route to Fernie. - J. Ambriz			
Carlos Hernandez									
40950					12/17/2008		28		\$0.00
Medium	Work In Progress			12/17/2008 3:08:54 PM					
Moncayo, Fernando		range hood systems exhaust fan not operating							
Carlos Hernandez									
41324					1/9/2009		5		\$0.00
Medium	Work In Progress			1/9/2009 3:20:51 PM					
Castillo, Carlos		need to check for short in teachers lounge tripping breaker							
Carlos Hernandez									
41353					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:22 AM					
Mata, Daniel		Monthly - QRTLY BLDG INSP REPORT (RS) - Refer to PM schedule details.							
Jesus Estrada									
41372					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:29 AM					
Hernandez, Carlos		Monthly - Riverside ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
Count: 16 Work Orders		Avg. Age of WO's 95		Total for Riverside ES				1	\$25.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		San Miguel ES							
35664					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:56 AM					
Vega, Danny		Yearly - San Miguel ES Emer. Light Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35687					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:20:03 AM					
Vega, Danny		Yearly - San Miguel ES Exit Sign Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
37343					8/22/2008		145		\$0.00
Medium	Work In Progress			8/22/2008 3:24:23 PM					
Lozoya, Manny		Asp Mike, please core back to GM 6 or 7 pin.							
39334		Portables			10/21/2008		85		\$0.00
Medium	Work In Progress			10/21/2008 11:17:54					
Estrada, Jesus		Please re-carpet dbl portable northwest corner mescalero.Thxs(#42/goose)				1/12/09 - PENDING AS OF TODAY PER CHUY			
Michael Munoz									
39565	Main Building				10/29/2008		77		\$0.00
Medium	Work In Progress			10/29/2008 7:32:46 AM					
Lozoya, Manny		please change cores to where the techs can have access to the back door of the boiler room so they can service equipment.							
Michael Munoz									
Count: 5 Work Orders		Avg. Age of WO's		138	Total for San Miguel ES			0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
35630					7/6/2008	7/14/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:45 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35641					7/6/2008	7/14/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:48 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35713					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:20:12 AM					
Villalobos, David	Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37139					8/18/2008		149		\$0.00
Medium	Work In Progress			8/18/2008 11:44:10 AM					
Castillo, Carlos	CALI; HAND DRYER IN BOYS RRM. DOES NOT SHUT OFF AT TIMES, AND SOMETIMES STARTS BY ITSELF. NEED FOR YOU TO CHECK IT OUT. I TURNED THE BREAKER OFF , BECAUSE A STUDENT BURNED HIMSELF ON IT AND REPORTED IT TO THE OFFICE.								
<u>Gerardo Marquez</u>									
37687	Classroom				9/2/2008		134		\$0.00
Medium	Work In Progress			9/2/2008 11:24:37 AM					
Ronquillo, Ruben	One window on Portable is jammed intruder tried to get in thru window on east portable, also middle hallway workroom broken (window) cracked -B-Wing. (Case# 2008-08926)								
<u>Pablo Diaz</u>									
37927					9/8/2008		128		\$0.00
Medium	Work In Progress			9/8/2008 3:57:59 PM					
Marquez, Gerardo	9/4/08					9/4-8			
	1-INSP. BLDG. & GRNDS. PICKED UP TRASH. 2-CLEANED OFF ENTRANCES & SIDEWALKS. 1-CLEANED & IJNSP. P.G. AREAS. 2-ADJ. LOCKSETS, & DR. CLOSERS @ PORTABLES A, & B. 2-CLEANED & INSP. MECH. RMS.								
<u>Gerardo Marquez</u>									
39449	Main Building	Portables			10/24/2008		82		\$0.00
Medium	Work In Progress	ART PORTABLE		10/24/2008 9:06:50 AM					
Marquez, Gerardo	A PAPER RACK IS NEEDED TO BE SET UP IN THE CLASSROOM. THANKS.								
<u>Rita Mendez</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
39454	Main Building	Portables			10/24/2008		82		\$0.00
Medium	Work In Progress	ART PORTABLE			10/24/2008 10:59:50				
Marquez, Gerardo		BRACKETS AND SHELF NEED TO BE SET UP IN CLASSROOM. THANKS.							
Rita Mendez									
39918	Main Building	Restroom (Girls)			11/6/2008		69		\$0.00
Medium	Work In Progress	ladies restroom			11/6/2008 3:11:24 PM				
Marquez, Gerardo		Large spacing in between the wall and other toilet partition needs to be covered. The gap is large enough to see other people inside the stall. Thank you.							
Rita Mendez									
40401					11/30/2008		45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:41				
Marquez, Gerardo		Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.							
George ZZ Gabaldon									
40402					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:42				
Marquez, Gerardo		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40403					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:42				
Marquez, Gerardo		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40404					11/30/2008	12/6/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:42				
Marquez, Gerardo		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.							
George ZZ Gabaldon									
40652					12/7/2008	12/23/2008	38		\$0.00
Medium	Work In Progress				12/7/2008 12:16:16 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.							
George ZZ Gabaldon									
40673					12/8/2008		37		\$0.00
Medium	Work In Progress				12/8/2008 2:29:44 PM				
Ronquillo, Ruben		RUBEN, ONE WINDOW PAYNE @ FRONT FOYER NEEDS TO BE REPLACED DUE TO CONDENSATION. THANKS.							
Gerardo Marquez									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
40868		Cafeteria			12/15/2008		30		\$0.00
Medium	Work In Progress			12/15/2008 1:33:12 PM					
Moncayo, Fernando	OVEN NOT WARMING UP ENOUGH. (NOT GETTING HOT)								
	PAT SANCHEZ SNP MGR 589-3439								
Jacqueline Aguilar									
41012					12/19/2008		26		\$0.00
Medium	Work In Progress			12/19/2008 11:55:39					
Gallegos, Ralph	JOSE AMBRIZ/MARGRET VILLALOBOS; HVAC UNITS NEED TO BE SHUT DOWN THROUGH TRACER SUMMIT FOR HOLIDAYS. NEED TO BE BACK ON FOR JAN. 5TH. THANKS.								
Gerardo Marquez									
41027					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:30 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
41061					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:45 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
41119					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:09 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41130					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:14 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41235		Cafeteria			1/7/2009		7		\$0.00
Medium	Work In Progress			1/7/2009 10:45:02 AM					
Moncayo, Fernando	NEED DOOR BELL FOR BACK DOO (DELIVERY)								
	PAT SANCHEZ STE SNP MGR 589-3439								
Jacqueline Aguilar									
41278		Classroom			1/8/2009		6		\$0.00
Medium	Work In Progress	RM 102		1/8/2009 3:18:53 PM					
Marquez, Gerardo	NEED RACK FOR JACKETS TO SET UP IN CLASSROOM 102								
Rita Mendez									
1/14/2009 11:38:16 AM									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Santa Teresa ES							
41355					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:23 AM				
Diaz, Pablo		Monthly - QRTL Y BLDG INSP REPORT (STE) - Refer to PM schedule details.							
<u>Jesus Estrada</u>									
41373					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:30 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
41431					1/13/2009		1		\$0.00
Medium	Work In Progress				1/13/2009 10:52:36 AM				
Villalobos, David		DAVID, FAUCET @ SINK IN TEACHERS LOUNGE NEEDS TO BE REPLACED. (FAUCET HAS BEEN LEAKING, AND IS GETTING WORSE.) THANKS.							
<u>Gerardo Marquez</u>									
41432					1/13/2009		1		\$0.00
Medium	Work In Progress				1/13/2009 10:54:08 AM				
Villalobos, David		DAVID, FAUCET TO SINK IN B. RRM. NEEDS TO BE REPLACED. (FAUCET WILL NOT SHUT OFF.)							
<u>Gerardo Marquez</u>									
41433					1/13/2009		1		\$0.00
Medium	Work In Progress				1/13/2009 10:57:59 AM				
Villalobos, David		DAVID, FLUSH LEVERS IN TEACHERS RRMS. IN B, & C WING NEED TO BE REPLACED. HANDLES ARE BROKEN.							
<u>Gerardo Marquez</u>									
Count: 28 Work Orders		Avg. Age of WO's 57			Total for Santa Teresa ES			0	\$0.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
35520		Football Field			7/2/2008		196		\$0.00
Medium	Work In Progress			7/2/2008 8:03:34 AM					
Castillo, Carlos	NEED TO HAVE ONE LIGHT AT FOOTBALL FIELD CHECKED, NOT LIGHTING, WESTSIDE OF FIELD, BEHIND PRESSBOX.								
Arturo Nunez									
35552					7/6/2008	7/12/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:21 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
35569					7/6/2008	7/14/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:26 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
35666					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:19:56 AM					
Nunez, Arturo	Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
35689					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:20:04 AM					
Nunez, Arturo	Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
35711					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress			7/6/2008 12:20:11 AM					
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35756		Athletic Field			7/8/2008		190		\$0.00
Medium	Work In Progress			7/8/2008 11:03:17 AM					
Ontiveros, Guadalupe	Remove goal post and install at CMS.								
Terry Alvarado									
36510					8/3/2008	8/9/2008	164		\$0.00
Medium	Work In Progress			8/3/2008 12:20:16 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
36645	Cafeteria (2005)	Cafeteria			8/5/2008		162		\$0.00
Medium	Work In Progress			8/5/2008 1:01:49 PM					
Moncayo, Fernando		WATER IS LEAKING FROM UNDERNEATH THE DISHWASHING MACHINE							
Alma Terrell		OLGA BUSTAMANTE - SNP MANAGER 589-9836							
37137	Cafeteria (2005)	Cafeteria			8/18/2008		149		\$0.00
Medium	Work In Progress			8/18/2008 11:08:29 AM					
Moncayo, Fernando		Washing Machine is leaking water (underneath machine) - Left message with Fernando							
Alma Terrell		Olga Bustamante - SNP Manager 589-5332							
37386					8/26/2008		141		\$0.00
Medium	Work In Progress			8/26/2008 7:30:49 AM					
Ontiveros, Guadalupe		Pedestrian Gate on South side that goes to the Bluffs. - Install taller gate to prevent access through bottom of gate.							
Alfredo Holguin									
37545					8/31/2008	9/6/2008	136		\$0.00
Medium	Work In Progress			8/31/2008 12:25:12 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
37958					9/9/2008		127		\$0.00
Medium	Work In Progress			9/9/2008 2:33:14 PM					
Castillo, Carlos		NEED SOME ASSISTANCE ON CHECKING OUTSIDE LIGHTING ON CAF. NEW BUILDING, VOC. BUILDING, AND MAIN BUILDING.							
Arturo Nunez									
38073					9/14/2008		122		\$0.00
Medium	Work In Progress			9/14/2008 12:23:08 AM					
Ontiveros, Guadalupe		Monthly - Santa Teresa HS Soil Sampling - Refer to PM schedule details.							
Margret Villalobos									
38255		Classroom			9/19/2008		117		\$0.00
Medium	Work In Progress	RM 207		9/19/2008 12:14:53 PM					
Villalobos, Margret		Unit is working fine, problem with comm link, need to contact Trane.				Asp Jose Ambriz, need to schedule, when there is no students.			
Jose Ambriz		E-mailed to J. Velasquez 9/19/08							
38257					9/19/2008		117		\$0.00
Medium	Work In Progress			9/19/2008 2:26:25 PM					
Ambriz, Jose		WE NEED SOME INSULATION FOR DUCTWORK IN ROOM 12.							
Manuel Prospero									
1/14/2009 11:38:16 AM									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
38346					9/23/2008		113		\$0.00
Medium	Work In Progress			9/23/2008 9:02:34 AM					
Ambriz, Jose	THE FOLLOWING F.C.U.'S HAVE A COMMUNICATION PROBLEM BETWEEN MASTER AND SLAVE, 207M SCC IS OF LINE, 205M SCC IS OFF LINE, AND 203 SCC IS IF LINE. CAN WE PLEASE HAVE THEN CHECKED. THANK YOU.								
<u>Arturo Nunez</u>									
38539					9/30/2008		106		\$0.00
Medium	Work In Progress			9/30/2008 12:26:04 AM					
Prospero, Manuel	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38544	Cafeteria (2005)	Cafeteria			9/30/2008		106		\$0.00
Medium	Work In Progress			9/30/2008 8:10:55 AM					
Moncayo, Fernando	Comments from Ecolab Report: Dishwasher is not filling up. Pre-spray hose id damaged & should be replaced. Olga Bustamante SNP MANAGER 58905332								
<u>Jacqueline Aguilar</u>									
38595	Gymnasium				10/1/2008		105		\$0.00
Medium	Work In Progress			10/1/2008 12:31:34 PM					
Nunez, Arturo	REPLACE STAINED AND BROKEN CIELING TILES								
<u>Michael Munoz</u>									
38691					10/3/2008		103		\$0.00
Medium	Work In Progress			10/3/2008 7:59:21 AM					
Gonzalez, Salvador	FRONT GATE NEEDS A GATE STOPER 6 GATE HINGES POLE IS 7 INCH WIDE 1 GATESTOPPER 1 POLE FOR GATE STOPPER.					12/17 - Asp Mike route to Sal.			
<u>Manuel Prospero</u>									
38753					10/5/2008	10/11/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:53 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38754					10/5/2008	10/13/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:53 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38755					10/5/2008	10/26/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1/14/2009 11:38:16 AM

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
38756					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Yearly - Santa Teresa HS H-6 Rftop Furn Yearly - Refer to PM schedule details.								
Margret Villalobos									
38757					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Yearly - Santa Teresa HS R-9 Radiator Ht Wtr 2yr - Refer to PM schedule details.								
Margret Villalobos									
38758					10/5/2008	10/21/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:23:55 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
Margret Villalobos									
38897					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:46 AM					
Prospero, Manuel	Yearly - Santa Teresa HS I-4 Fan Coil Unit Yearly - Refer to PM schedule details.								
Margret Villalobos									
38898					10/5/2008	10/26/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:46 AM					
Prospero, Manuel	Monthly - Santa Teresa HS C-12 Chm Feeder Semimtlly - Refer to PM schedule details.								
Margret Villalobos									
38899					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:47 AM					
Prospero, Manuel	Yearly - Santa Teresa HS U-2 Unit Ht Gas Yearly - Refer to PM schedule details.								
Margret Villalobos									
38992	Library				10/7/2008		99		\$0.00
Medium	Work In Progress			10/7/2008 9:54:07 AM					
Lara, Ralph	LIBRARY CONFERENCE ROOM LOCK ON DOOR TO HALLWAY IS BROCK								
Manuel Prospero									
39059	Library	Library			10/9/2008		97		\$0.00
Medium	Work In Progress			10/9/2008 9:00:13 AM					
Lara, Ralph	Key tumblers have fallen out on two doors Multi media and lib conf room								
Rosa Hood									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
39164					10/12/2008	10/28/2008	94		\$0.00
Medium	Work In Progress				10/12/2008 12:21:05				
Nunez, Arturo		Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
39344					10/21/2008		85		\$0.00
Medium	Work In Progress				10/21/2008 3:13:05 PM				
Villalobos, David		NEED SOME ASSISTANCE ON LEAK TEST GAS LINES ON WELDING BOTHS, THERE SEEMS TO BE A GAS LEAK, BUT CAN'T LOCATE.							
<u>Arturo Nunez</u>									
39396	Main Building	Choral			10/22/2008		84		\$0.00
Medium	Work In Progress				10/22/2008 3:57:04 PM				
Lara, Ralph		Door from Band Room Top Corner broken, needs to be replaced Thank you, Rosa							
<u>Rosa Hood</u>									
39398	Main Building	Hallway/Corridor			10/22/2008		84		\$0.00
Medium	Work In Progress				10/22/2008 3:59:35 PM				
Prospero, Manuel		Remove lockers in hallway near counseling area and across from Main office Thank you, Rosa							
<u>Rosa Hood</u>									
39412	Dressing Rooms				10/23/2008		83		\$0.00
Medium	Work In Progress				10/23/2008 11:11:35				
Lara, Ralph		NEED TO HAVE A RESTROOM PILLASTER REPLACED FOR BOYS FOOTBALL DRESSING RESTROOM , TO INSTALL DOOR AT H.C. COMMODE. SIZES WERE FAXED TO MR. RONQUILLO THANK YOU.							
<u>Arturo Nunez</u>									
39542	Main Building	Office			10/28/2008		78		\$0.00
Medium	Work In Progress				10/28/2008 1:18:25 PM				
Ronquillo, Ruben		We need signs to indicate what building is what since we do not have a front entrance. Please feel free to call me or Art Nunez so that we can be more specific Thank you, Rosa							
<u>Rosa Hood</u>									
39648					10/31/2008		75		\$0.00
Medium	Work In Progress				10/31/2008 9:49:48 AM				
Castillo, Carlos		NEED SOME ASSISTANCE WITH A WALL PLUG, AND PIG TAIL FOR KILN IN ROOM # 601. THEY ARE FRIED, NEED TO BE REPLACED.							
<u>Arturo Nunez</u>									

1/14/2009 11:38:16 AM

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
39695					11/2/2008	11/8/2008	73		\$0.00
Medium	Work In Progress			11/2/2008 12:24:36 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
39730					11/2/2008	11/10/2008	73		\$0.00
Medium	Work In Progress			11/2/2008 12:24:49 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
39740					11/2/2008	11/10/2008	73		\$0.00
Medium	Work In Progress			11/2/2008 12:24:53 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
39756					11/2/2008	12/3/2008	73		\$0.00
Medium	Work In Progress			11/2/2008 12:24:59 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
40146					11/6/2008		69		\$0.00
Medium	Work In Progress			11/17/2008 2:07:57 PM					
Ronquillo, Ruben		BROKEN WINDOW IN SHOP 2.							
<u>Jose Angelo</u>									
40365					11/30/2008	12/6/2008	45		\$0.00
Medium	Work In Progress			11/30/2008 12:23:29					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
<u>George ZZ_Gabaldon</u>									
40376					11/30/2008	12/21/2008	45		\$0.00
Medium	Work In Progress			11/30/2008 12:23:33					
Orozco, Danny		Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.							
<u>George ZZ_Gabaldon</u>									
40425					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress			11/30/2008 12:23:49					
Prospero, Manuel		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
<u>George ZZ_Gabaldon</u>									
40426					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress			11/30/2008 12:23:50					
Prospero, Manuel		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>George ZZ_Gabaldon</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
40427					11/30/2008	12/31/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:50				
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40483		Cafeteria			12/2/2008		43		\$0.00
Medium	Work In Progress				12/2/2008 9:05:35 AM				
Moncayo, Fernando	MILK COOLER TO HER RED & GREEN CHILE IS NOT WORKING AT ALL.								
	OLGA B. 589-5332								
<u>Jacqueline Aguilar</u>									
40653					12/7/2008	12/23/2008	38		\$0.00
Medium	Work In Progress				12/7/2008 12:16:16 AM				
Prospero, Manuel	Monthly - Santa Teresa HS Playground Insp - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40852					12/14/2008		31		\$0.00
Medium	Work In Progress				12/14/2008 12:16:33				
Ontiveros, Guadalupe	Monthly - Santa Teresa HS Soil Sampling - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40873					12/15/2008		30		\$0.00
Medium	Work In Progress				12/15/2008 2:57:45 PM				
Castillo, Carlos	NEED A 115V ELEC. OUTLET INSTALLED ON CONFERENCE ROOM IN LIBRARY, FOR POWER POINT PROJECTOR.								
<u>Arturo Nunez</u>									
40964					12/17/2008		28		\$0.00
Medium	Work In Progress				12/17/2008 4:02:37 PM				
Ontiveros, Guadalupe	Recycle Dumpster - Relocate next to trash compactor								
<u>Alfredo Holguin</u>									
41042					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:38 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41059					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:45 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
41121					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:10 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41131					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:14 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41148					1/4/2009	2/4/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:22 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41154					1/5/2009		9		\$0.00
Medium	Work In Progress			1/5/2009 8:52:07 AM					
Villalobos, David	NEED SOME ASSISTANCE ON CHECKING MANHOLE BY GAS METER, ON EAST SIDE. METHANE GAS LEVEL READING IS A 8 , AS PER P.N.M. TECH. WOULD LIKE TO HAVE IT CHECKED OUT.								
<u>Arturo Nunez</u>									
41237					1/7/2009		7		\$0.00
Medium	Work In Progress			1/7/2009 12:48:37 PM					
Ronquillo, Ruben	NEED THE FOLLOWING WINDOW GLASS REPLACED 1 , 53 3/4 X24 5/8, 1 -24 7/8 X6 7/8, 1- 60 7/8 X26 7/8. ALL WIRE MESH GLASS.								
<u>Arturo Nunez</u>									
41307	Dressing Rooms	Dressing Room			1/9/2009		5		\$0.00
Medium	Work In Progress			1/9/2009 8:54:39 AM					
Munoz, Michael	Boys athletic lockers need to be bolted down for safety reasons This is the second request Someone is going to get hurt with a falling bank of lockers				Art Nunez had previously submitted a work order and has spokent to someone at the GAC/Warehouse regarding this situation				
<u>Rosa Hood</u>									
41316	Main Building	Office			1/9/2009		5		\$0.00
Medium	Work In Progress			1/9/2009 12:47:04 PM					
Estrada, Jesus	Main Office carpet needs to be replaced Carpet is at least 15 years old It is a safety issue - duct tape is holding it together at door entrances Mr. Kelch and Mrs. Hood				Was measured picked color				
<u>Rosa Hood</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
41337		Athletic Field			1/10/2009		4		\$0.00
Medium	Work In Progress			1/10/2009 9:40:16 AM					
Ontiveros, Guadalupe		Track was damaged last year when work was being done on irrigation system. The track has not been repaired and this is a safety issue for all our students for this Track season. Please see coach Solis or Mrs. Hood							
Rosa Hood									
41356					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:23 AM					
Murillo, Luis		Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.							
Jesus Estrada									
41374					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:30 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
41394					1/12/2009		2		\$0.00
Medium	Work In Progress			1/12/2009 10:29:54 AM					
Carrasco, Danny		WE NEED THE SCISSOR LIFT TO CHANGE OVER HEAD LIGHTS ON T-300.							
Manuel Prospero									
41453					1/13/2009		1		\$0.00
Medium	Work In Progress			1/13/2009 3:27:58 PM					
Carrasco, Danny		WE NEED TO REPLACE (3) WINDOWS 2-WIREGLASS IN ROOM T400. 36X36. 1-SINGLE GLASS IN ROOM 7 26X29.							
Manuel Prospero									
Count: 68 Work Orders		Avg. Age of WO's 83		Total for Santa Teresa HS			0	\$0.00	

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Santa Teresa MS								
35712					7/6/2008	8/6/2008	192		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:11 AM						
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
36170	North Building	Custodial			7/24/2008		174		\$0.00	
Medium	Work In Progress			7/24/2008 7:42:22 AM						
Gonzales, Angel		pete,the truck 39 needs a complete tune up i need to have it ready for the school year.thank you.								
Ismael Rodriguez										
36511					8/3/2008	8/9/2008	164		\$0.00	
Medium	Work In Progress			8/3/2008 12:20:17 AM						
Mijarez, Jaime		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos										
36903	North Building	Classroom			8/11/2008		156		\$0.00	
Medium	Work In Progress	Room 3A			8/11/2008 3:12:40 PM					
Mijarez, Jaime		1. Portable leaks when it rains.								
Laura Parra										
37603					8/31/2008	9/6/2008	136		\$0.00	
Medium	Work In Progress			8/31/2008 12:25:31 AM						
Mijarez, Jaime		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos										
37771	Gym (1997)				9/4/2008		132		\$0.00	
High	Work In Progress			9/4/2008 8:21:25 AM						
Mijarez, Jaime		please reroute overflow lines from a/c. do not drain into mop sink and install strainer also. this will prevent from sink overflowing and damaging gym floor. (2nd time)								
Michael Munoz										
37808					9/4/2008		132		\$0.00	
Medium	Work In Progress			9/4/2008 4:13:04 PM						
Munoz, Michael		North Bldg. - Build concrete Pad for dumpsters.								
Alfredo Holguin										
38251	Library	Library			9/19/2008		117		\$0.00	
Medium	Work In Progress	Ms. Swaim-			9/19/2008 10:10:45 AM					
Castillo, Carlos		Need power strip for the wall. The outlets are overloaded. Wires and cords need to be contained.								
Parra, Laura										

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
38505					9/29/2008		107		\$0.00
Medium	Work In Progress			9/29/2008 1:43:22 PM					
Mijarez, Jaime	Need to install signs. Below is the recommendaton, but please ck w/site administrator first on location.								
<u>Daniel Rosales</u>									
38535					9/30/2008		106		\$0.00
Medium	Work In Progress			9/30/2008 12:26:01 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38596					10/1/2008		105		\$0.00
Medium	Work In Progress			10/1/2008 12:33:20 PM					
Soria, Mike	CUT WEEDS AT NEW LANDSCAPING IN FRONT OF SOUTH BUILDING.								
<u>Michael Munoz</u>									
38597					10/1/2008		105		\$0.00
Medium	Work In Progress			10/1/2008 12:34:21 PM					
Soria, Mike	OPEN DRAIN BY MORGAN BUILDING. CUT WEEDS AND BARRICADE. SAFETY HAZARD.								
<u>Michael Munoz</u>									
38869					10/5/2008	11/5/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:36 AM					
Mijarez, Jaime	Yearly - Santa Teresa MS U2 (Heat Gas)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39102	North Building	Classroom			10/10/2008		96		\$0.00
Medium	Work In Progress	Room 1		10/10/2008 2:36:56 PM					
Mijarez, Jaime	Hand made wooden case in recognition hall needs to be installed on the wall. The case will need a 2x6 wooden base, plexiglass doors and mounting hardware								
<u>Laura Parra</u>									
39103	South Building	Office			10/10/2008		96		\$0.00
Medium	Work In Progress	Social Worker-		10/10/2008 2:38:07 PM					
Mijarez, Jaime	Ceiling is leaking next to the window								
<u>Laura Parra</u>									
39113	South Building	Office			10/10/2008		96		\$0.00
Medium	Work In Progress	Assistant		10/10/2008 3:39:59 PM					
Castillo, Carlos	Need computer outlet and phone outlet to be placed on the opposite wall as to where its actually at								
<u>Laura Parra</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
39335					10/21/2008		85		\$0.00
Medium	Work In Progress				10/21/2008 12:48:47				
Ambriz, Jose	N.bldg Hp 36 lobby has a bad motor that is making a loud noise.								
<u>Jaime Mijarez</u>									
39406					10/23/2008		83		\$0.00
Medium	Work In Progress				10/23/2008 7:58:22 AM				
Castillo, Carlos	See if we can repair the timers and order additional triggers. (see Jaime if you have any questions).								
<u>Michael Munoz</u>									
39696					11/2/2008	11/8/2008	73		\$0.00
Medium	Work In Progress				11/2/2008 12:24:36 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39873	Gym (1997)				11/5/2008		70		\$0.00
Medium	Work In Progress				11/5/2008 3:41:57 PM				
Marquez, Gerardo	as per our meeting, please cut edges of gym floor for expansion. Thankyou								
<u>Michael Munoz</u>									
40169					11/18/2008		57		\$0.00
Medium	Work In Progress				11/18/2008 9:33:58 AM				
Ronquillo, Ruben	N.bldg office exterior windows. Replace 2nd glass window with new aluminum molding. Existing molding is to corroded. Replace aluminum molding around glass window that was replaced for W/O #39295. I checked molding around window and it is too damaged.								
<u>Jaime Mijarez</u>									
40414					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:46				
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>George ZZ_Gabaldon</u>									
40415					11/30/2008	12/31/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:46				
Mijarez, Jaime	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
<u>George ZZ_Gabaldon</u>									
40416					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:46				
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>George ZZ_Gabaldon</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
40417					11/30/2008	12/6/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:47				
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40475	South Building	Choral			12/2/2008		43		\$0.00
Medium	Work In Progress	Outside Choir			12/2/2008 8:05:57 AM				
Gonzalez, Salvador	Replace the old worn out gate behind the south building and relocate by the corner of the south building with a new one. (A safety measure)								
<u>Laura Parra</u>									
40476	North Building	Portables			12/2/2008		43		\$0.00
Medium	Work In Progress	Outside by			12/2/2008 8:09:53 AM				
Gonzalez, Salvador	North building by the portable-- Place a gate by the portables so we could keep people from driving their cars around the north building to get to the gym. (A SAFETY MEASURE)								
<u>Laura Parra</u>									
40584	North Building	Custodial			12/4/2008		41		\$0.00
Medium	Work In Progress				12/4/2008 1:30:18 PM				
Ontiveros, Guadalupe	Lupe i will be needing a trailer on 12/18/08 to 12/19/08 reason for delivering of lunches to south building								
<u>Ismael Rodriguez</u>									
40781	North Building	Parking Lot			12/11/2008		34		\$0.00
Medium	Work In Progress				12/11/2008 9:06:49 AM				
Lara, Ralph	rafa, need to place a master lock where the main gas shut off valve is we need to have access in case off emergency.thank you.mr.rodriguez.								
<u>Ismael Rodriguez</u>									
40825	Gym (1997)				12/12/2008		33		\$0.00
Medium	Work In Progress				12/12/2008 9:11:23 AM				
Mijarez, Jaime	Gym lobby floor vinyl tile is lifting up in big sections. I checked it and had to remove some of it. As per Mrs. Casillas can it be repaired or replaced before the basketball season. I was looking in to repairing but more tiles are coming loose.					1/9/09 - Assign to Jaime asp coversation with him. mmunoz			
<u>Jaime Mijarez</u>									
40826					12/12/2008		33		\$0.00
Medium	Work In Progress				12/12/2008 9:18:30 AM				
Castillo, Carlos	Nurses office. I am loosing power to recepticles on one section of walls. I am going to need your help on this one, I am having a hard time pin pointing the problem.								
<u>Jaime Mijarez</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
41024					12/31/2008		14		\$0.00
Medium	Work In Progress				12/31/2008 12:18:22				
Mijarez, Jaime	Yearly - Santa Teresa MS H6(Roof Furnace)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
41043					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:38 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
41060					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:45 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
41123					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:19:11 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41132					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:19:15 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41147					1/4/2009	2/4/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:19:22 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
41216	South Building				1/6/2009		8		\$0.00
Medium	Work In Progress				1/6/2009 4:25:30 PM				
Soria, Mike	please cut weeds in culvert by ground morgan bldg.								
Michael Munoz									
41218					1/6/2009		8		\$0.00
Medium	Work In Progress	LINE LOCATE			1/6/2009 4:28:20 PM				
Villalobos, David	Need to line locate by Grounds Morgan Bldg 1st thing tomorrow morning - septic tank leak.								
David Villalobos									
41219					1/6/2009		8		\$0.00
Medium	Work In Progress	LINE LOCATE			1/6/2009 4:28:49 PM				
Castillo, Carlos	Need to line locate by Grounds Morgan Bldg 1st thing tomorrow morning - septic tank leak.								
David Villalobos									

1/14/2009 11:38:16 AM

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Santa Teresa MS								
41268					1/8/2009		6		\$0.00	
Medium	Work In Progress				1/8/2009 2:04:38 PM					
Villalobos, David	Please ck septic tank it might be full, if so please have it cleaned.									
<u>Michael Munoz</u>										
41357					1/11/2009	1/27/2009	3		\$0.00	
Medium	Work In Progress				1/11/2009 12:17:24 AM					
Rodriguez, Ismael	Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PM schedule details.									
<u>Jesus Estrada</u>										
41440	South Building	Restroom (Girls)			1/13/2009		1		\$0.00	
Medium	Work In Progress				1/13/2009 1:48:17 PM					
Lara, Ralph	rafa theres a restroom that it locks by it self, i think you need to check the cylinder or the doornob some teachers already advise me about it.thank you.see mr.rodriquez									
<u>Ismael Rodriguez</u>										
41443	South Building	Restroom (Boys)			1/13/2009		1		\$0.00	
Medium	Work In Progress	Restroom Boys			1/13/2009 2:54:16 PM					
Lara, Ralph	Boys and girls restroom south bld lower level--- students are having trouble opening the door, at times students are locked inside and cant get out.									
<u>Laura Parra</u>										
Count: 44 Work Orders		Avg. Age of WO's 66		Total for Santa Teresa MS			0	\$0.00		

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
35710					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress				7/6/2008 12:20:11 AM				
Villalobos, David	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35734					7/7/2008		191		\$0.00
Medium	Work In Progress				7/7/2008 3:30:23 PM				
Lara, Ralph	WE NEED EXTRA KEY FROM LIBRARY								
Joel Herrera									
37362					8/25/2008		142		\$0.00
Medium	Work In Progress				8/25/2008 2:14:46 PM				
Lara, Ralph	WE NEED REPLACE CLASS ROOMS DOORS THEY ARE TO RUSTING								
Joel Herrera									
37891	Main Building				9/8/2008		128		\$0.00
Medium	Work In Progress				9/8/2008 9:02:24 AM				
Ronquillo, Ruben	FXT-SP-030 - Missing Boiler Room (S) asp PM 37589								
Joel Herrera									
38310					9/22/2008		114		\$0.00
Medium	Work In Progress	outside			9/22/2008 2:14:13 PM				
Herrera, Joel	Please replace broken tiles located by the main entrance.								
Jessica Lopez									
38468					9/26/2008		110		\$0.00
Medium	Work In Progress				9/26/2008 1:25:56 PM				
Castillo, Carlos	MS. PEREZ WANTS TWO OUTLETS AT PLAYGROUNDS AREA IF WE CAN DO POSSIBLE. THANK YOU CALI								
Joel Herrera									
38567					9/30/2008		106		\$0.00
Medium	Work In Progress				9/30/2008 2:42:50 PM				
Lara, Ralph	DOOR'S KNOB HAS A PIECE OF PENCIL LEAD STUCK IN KEY OPENING AND DOOR CAN'T BE UNLOCKED AT CLASS ROOM #28								
Joel Herrera									
38568					9/30/2008		106		\$0.00
Medium	Work In Progress				9/30/2008 3:01:23 PM				
Lara, Ralph	NEED TO FIXED HALL WAY DOOR IN SOUTH SIDE ALSO G.Y.M DOOR IS NOT WORKING								
Joel Herrera									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
38801					10/5/2008	10/26/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:11 AM					
Orozco, Danny	Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38865					10/5/2008	10/13/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:34 AM					
Herrera, Joel	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38958					10/6/2008		100	1	\$25.00
Medium	Work In Progress	library		10/6/2008 12:29:14 PM					
Herrera, Joel	Attach electrical strip to new computer cart.						10/24 -NON ELECTRICAL, NEED BM TO OBTAIN A POWER SURGE STRIP AND INSTALL HIMSELF. C. CASTILLO.		
Jessica Lopez							Route to Joel 11/3/08		
39810	Main Building	Library			11/4/2008		71		\$0.00
Medium	Work In Progress			11/4/2008 1:13:33 PM					
Herrera, Joel	Mr. Herrera please assemble tv cart. Location-Library								
<u>Jessica Lopez</u>									
39811	Main Building	Classroom			11/4/2008		71		\$0.00
Medium	Work In Progress	Room #39		11/4/2008 1:22:08 PM					
Villalobos, David	Both sinks are not working correctly. They seem to be clogged. Location Room #39								
<u>Jessica Lopez</u>									
39888					11/6/2008		69		\$0.00
Medium	Work In Progress			11/6/2008 8:12:18 AM					
Gonzalez, Salvador	WE NEED REPLACE CONCRET WALL AND STEEL GATE AT OUTSIDE AREA								
<u>Joel Herrera</u>									
40052					11/13/2008		62		\$0.00
Medium	Work In Progress	Room # 41		11/13/2008 1:19:38 PM					
Herrera, Joel	Mr. Herrera, Ms. Cordero needs a new sharpener. Room # 41								
<u>Jessica Lopez</u>									
40113					11/14/2008		0		\$0.00
Medium	Work In Progress			11/14/2008 3:14:33 PM	11/14/2008				
Rivera, Hector	Pick up trash all along the north side fence.						12/3/08 REFAXED TO HECTOR		
<u>Jesus Estrada</u>									
40288					11/21/2008		54		\$0.00
Medium	Work In Progress			11/21/2008 9:15:30 AM					
Herrera, Joel	Mr. Herrera please paint the red emergency lines located in front of the school.								
<u>Jessica Lopez</u>									

1/14/2009 11:38:16 AM

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
40654					12/7/2008	12/23/2008	38		\$0.00
Medium	Work In Progress			12/7/2008 12:16:17 AM					
Herrera, Joel	Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40679		Cafeteria			12/8/2008		37		\$0.00
Medium	Work In Progress			12/8/2008 3:30:26 PM					
Moncayo, Fernando	DISHWASHER NEEDS TO BE REPAIRED. NOT WORKING AT ALL.								
	MARINA RAMIREZ SNP MGR 589-2545								
<u>Jacqueline Aguilar</u>									
40949					12/17/2008		28		\$0.00
Medium	Work In Progress			12/17/2008 2:00:31 PM					
De Santiago, Baudelio	Mr. De Santiago please mop all classrooms & wax and buff hall ways.								
<u>Jessica Lopez</u>									
40983					12/18/2008		27		\$0.00
Medium	Work In Progress			12/18/2008 2:52:52 PM					
Villalobos, David	WE NEED REPLACE MOP SINK FAUCET W/VACUUM BREAKER AT CUSTODIANS CLOSET								
<u>Joel Herrera</u>									
41044					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:39 AM					
Herrera, Joel	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41062					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:46 AM					
Herrera, Joel	Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41124					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:11 AM					
Herrera, Joel	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41133					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:15 AM					
Herrera, Joel	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
41298		Cafeteria			1/8/2009		6		\$0.00
Medium	Work In Progress				1/8/2009 4:07:16 PM				
Moncayo, Fernando	2 Blodgett Ovens are down - not heating up at all								
Alma Terrell	Marina Ramirez - SNP Manager 589-2545								
41299		Cafeteria			1/8/2009		6		\$0.00
Medium	Work In Progress				1/8/2009 4:08:12 PM				
Moncayo, Fernando	Dishwasher is down - System corroded - Not working at all								
Alma Terrell	Marina Ramirez - SNP Manager 589-2545								
41300		Cafeteria			1/8/2009		6		\$0.00
Medium	Work In Progress				1/8/2009 4:09:11 PM				
Moncayo, Fernando	Hobart Mixer - Dropping oil and making a grinding sound								
Alma Terrell	Marina Ramirez - SNP Manager 589-2545								
41358					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:24 AM				
De Santiago, Baudelio	Monthly - QRTLY BDLG INSP REPORT (SP) - Refer to PM schedule details.								
Jesus Estrada									
41375					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:31 AM				
Herrera, Joel	Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
Count: 30 Work Orders		Avg. Age of WO's	64	Total for Sunland Park ES				1	\$25.00

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
40433					11/30/2008		45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:52				
Quinones, Paul	Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM schedule details.								
George ZZ Gabaldon									
35709					7/6/2008	8/6/2008	192		\$0.00
Medium	Work In Progress				7/6/2008 12:20:10 AM				
Villalobos, David	Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36205					7/25/2008		173		\$0.00
Medium	Work In Progress				7/25/2008 8:27:04 AM				
Lozoya, Manny	CLASSS RM. 207 DOOR HANDLE,AND LOCK CYLINDER NOT OPENING DOOR PROPERLY. THANKS								
Paul Quinones									
36336					7/29/2008		169		\$0.00
Medium	Work In Progress				7/29/2008 3:57:08 PM				
Ronquillo, Ruben	BROKEN WALL WINDOW IN WING 1,LOCATION RM.107 WINDOW SIZE 2'X2' DOUBLE PANE GLASS WINDOW W/ TINT. THANKS								
Paul Quinones									
36378					7/30/2008		168		\$0.00
Medium	Work In Progress				7/30/2008 4:19:55 PM				
Lozoya, Manny	DOOR IN WING B ELSOL HALL WAY.DURING FIRE DRILL IN THE MORNING 7-30-08.RIGHT SIDE DOOR WOULD NOT CLOSE DURING DRILL.								
Paul Quinones									
37422					8/26/2008		141		\$0.00
Medium	Work In Progress				8/26/2008 4:19:28 PM				
Ontiveros, Joe	HOSE BIBB ON WALL NEXT TO UPPER PLAY GROUND WATER LEAKING,BROKEN HANDLE.								
Paul Quinones									
38008	Main Building	Classroom			9/10/2008		126		\$0.00
Medium	Work In Progress				9/10/2008 4:02:35 PM				
Lozoya, Manny	Need key # for room 206 1c 32. The key is bent								
Joanne Munoz									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
38009	Main Building	Classroom			9/10/2008		126		\$0.00
Medium	Work In Progress	Estrellita work		9/10/2008 4:18:59 PM					
Lozoya, Manny		Alma Castillo, testing room estrellita hallway, has a filing cabinet in her room that is locked and we do not have a key for it. CAN a new key be made or reinstall a new lock? Thank you.							
Joanne Munoz									
38329					9/22/2008		114		\$0.00
Medium	Work In Progress			9/22/2008 3:45:45 PM					
Quinones, Paul		9-17-08 .5,CHECK IN W/OFFICE FOR PLAN OF THE DAY 7.5,REMOVE BLEACHERS FROM CHAP MID.TO C.H.S FOOT BALL STADIUM,AND RELOCATE SOCCER BLEACHERS TO FOOTBALL STADIUM AS WELL							
Paul Quinones									
38425	Main Building	Hallway/Corridor			9/25/2008		111		\$0.00
Safety	Work In Progress	sol		9/25/2008 10:54:05 AM					
Lozoya, Manny		The 1st door in el sol hallway is not releasing during fire drill. Needs to be checked out.							
Joanne Munoz									
39161					10/12/2008	10/28/2008	94		\$0.00
Medium	Work In Progress			10/12/2008 12:21:04					
Quinones, Paul		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
39588					10/29/2008		77		\$0.00
Medium	Work In Progress			10/29/2008 4:11:14 PM					
Lozoya, Manny		HANDI CAP DOOR CLOSER NOT WORKING PROPERLY,DOOR STAYS OPEN.FRONT ENTRANCE AREA.							
Paul Quinones									
39681					11/2/2008	11/8/2008	73		\$0.00
Medium	Work In Progress			11/2/2008 12:24:30 AM					
Quinones, Paul		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
39735					11/2/2008	11/10/2008	73		\$0.00
Medium	Work In Progress			11/2/2008 12:24:51 AM					
Quinones, Paul		Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
39743					11/2/2008	11/10/2008	73		\$0.00
Medium	Work In Progress			11/2/2008 12:24:54 AM					
Quinones, Paul	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39872					11/5/2008		70		\$0.00
Medium	Work In Progress			11/5/2008 3:35:43 PM					
Jacquez, Ricardo	REQUESTING WIND SCREEN FOR BACK CHAIN LINK FENCING AREA,LIFT STATION AREAS. BALL PARK FIGURE 200' WILL BE NEEDED @ 4' HIGH THANK YOU VERY MUCH								
Paul Quinones									
39895					11/6/2008		69		\$0.00
Medium	Work In Progress			11/6/2008 9:05:37 AM					
Sotelo, Enrique	LIGHTING PROBLEM IN REAR ENTRANCE OF SCHOOL,BURNED ELECTRICAL WIRING FROM INSIDE LIGHTING FIXTURE.								
Paul Quinones									
39971					11/9/2008	11/25/2008	66		\$0.00
Medium	Work In Progress			11/9/2008 12:28:38 AM					
Quinones, Paul	Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
40017	Main Building	Hallway/Corridor			11/12/2008		63		\$0.00
Medium	Work In Progress	VARIOUS		11/12/2008 8:05:43 AM					
Quinones, Paul	Need to have selected bulbs removed in the hallway.								
Joanne Munoz									
40018		Classroom			11/12/2008		63		\$0.00
Medium	Work In Progress	Parent Room		11/12/2008 8:11:32 AM					
Sotelo, Enrique	Check outlet with built in breaker, in Parent Room, by office, it keeps tripping.								
Joanne Munoz									
40050		Classroom			11/13/2008		62		\$0.00
Medium	Work In Progress	various		11/13/2008 11:30:13					
Quinones, Paul	Need to have a tv and/ or vcr and/or dvd in the following rooms:304,305,309,310,301,portables 3,4,5,6 and POA room See Mr. Wiggs for exact rooms and items								
Joanne Munoz									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
40168					11/18/2008		57		\$0.00
Medium	Work In Progress				11/18/2008 9:12:56 AM				
Lozoya, Manny	DOOR HANDLE IN SPEECH THERAPIST DOOR ENTRANCE STICKING, AND WILL NOT CLOSE DOOR PROPERLY.								
Paul Quinones									
40236					11/19/2008		56		\$0.00
Medium	Work In Progress				11/19/2008 3:44:08 PM				
Ontiveros, Joe	WATER LINE ON ROOF LEAKING WATER, VALVE INSIDE HALL WAY THAT SHUTS OFF WATER LINE IS SHUT OFF FROM INSIDE BUILDING NEXT TO THE ADMIN. OFFICE								
Paul Quinones									
40289		Classroom			11/21/2008		54		\$0.00
Medium	Work In Progress	VARIOUS			11/21/2008 9:41:43 AM				
Quinones, Paul	PLEASE INSTALL PENCIL SHARPENERS IN THE FOLLOWING ROOMS 310, P-4, AND 302 WE HAVE THE SHARPENERS HERE AND READY TO BE INSTALLED								
Joanne Munoz									
40431					11/30/2008	12/6/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:51				
Quinones, Paul	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
George ZZ Gabaldon									
40432					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:52				
Quinones, Paul	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40434					11/30/2008		45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:52				
Quinones, Paul	Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM schedule details.								
George ZZ Gabaldon									
40435					11/30/2008		45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:53				
Quinones, Paul	Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details.								
George ZZ Gabaldon									
40436					11/30/2008		45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:53				
Quinones, Paul	Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.								
George ZZ Gabaldon									
1/14/2009 11:38:17 AM									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
40437					11/30/2008	12/8/2008	45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:53				
Quinones, Paul	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
George ZZ_Gabaldon									
40442					11/30/2008		45		\$0.00
Medium	Work In Progress				11/30/2008 12:23:55				
Jacquez, Ricardo	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
George ZZ_Gabaldon									
40519					12/3/2008		42		\$0.00
Medium	Work In Progress				12/3/2008 9:23:21 AM				
Lozoya, Manny	automatic door closer not working,handicap door front entrance.								
Paul Quinones									
40522		Cafeteria			12/3/2008		42		\$0.00
Medium	Work In Progress				12/3/2008 10:00:31 AM				
Orozco, Danny	INSIDE THE WALK-IN REFRIGERATOR FLOOR, THERE IS A PIECE OF METAL THAT IS LIFTING UP.								
VIRGINIA PRUIT - SNP MANAGER 824-3194									
Alma Terrell									
40523	Main Building	Classroom			12/3/2008		42		\$0.00
Medium	Work In Progress	310			12/3/2008 10:24:17 AM				
Lozoya, Manny	Mrs. White's, room 310, key is not working well can not open or lock door. key # 1c13								
Joanne Munoz									
40561					12/3/2008		42		\$0.00
Medium	Work In Progress				12/3/2008 3:51:04 PM				
Lozoya, Manny	Need to issue keys for site to Juan Carlos Vargas before Monday 12/8/08. (Paul will keep his set for Sunrise)								
Michael Munoz									
40581		Cafeteria			12/4/2008		41		\$0.00
Medium	Work In Progress				12/4/2008 1:19:39 PM				
Orozco, Danny	REAR DOOR NEEDS A BETTER SEAL. SEE ATTACHED INSPECTION SHEET FROM THE NM ENVIR. DEPT.								
VIRGINIA PRUIT SNP MGR 824-3194									
Jacqueline Aguilar									
40655					12/7/2008	12/23/2008	38		\$0.00
Medium	Work In Progress				12/7/2008 12:16:17 AM				
Quinones, Paul	Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.								
George ZZ_Gabaldon									
								1/14/2009 11:38:17 AM	

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
41028					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:31 AM					
Quinones, Paul	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
41064					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:18:47 AM					
Quinones, Paul	Monthly - Sunrise ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
41126					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:12 AM					
Quinones, Paul	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41134					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:16 AM					
Quinones, Paul	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41138					1/4/2009		10		\$0.00
Medium	Work In Progress			1/4/2009 12:19:18 AM					
Jacquez, Ricardo	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									
41164		Classroom			1/5/2009		9		\$0.00
Medium	Work In Progress	102		1/5/2009 2:51:54 PM					
Lara, Ralph	I will need a extra key for our RPT key # 1c38								
Joanne Munoz									
41359					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:24 AM					
Urquidi, Jesus	Monthly - QRTLY BLDG INSP REPORT (SR) - Refer to PM schedule details.								
Jesus Estrada									
41376					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress			1/11/2009 12:17:31 AM					
Vargas, Juan	Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
41441	Main Building				1/13/2009		1		\$0.00
Medium	Work In Progress			1/13/2009 1:49:07 PM					
Carbajal, Jimmy	VACUM DOES NOT WORK CO2A 00003435								
Jesus Urquidi									
Count: 46 Work Orders			Avg. Age of WO's	64		Total for Sunrise ES	0	\$0.00	

1/14/2009 11:38:17 AM

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
36103					7/22/2008		176		\$0.00
Medium	Work In Progress			7/22/2008 8:39:31 AM					
Sotelo, Enrique		NEED TO REPLACE 4 EXIT SIGNS							
Danny Miranda									
36104					7/22/2008		176		\$0.00
Medium	Work In Progress			7/22/2008 8:40:50 AM					
Sotelo, Enrique		NEED TO REPLACE 6 EMER. LIGHTS							
Danny Miranda									
36175	Main Building	Classroom			7/24/2008		174		\$0.00
Medium	Work In Progress			7/24/2008 11:22:30 AM					
Ronquillo, Ruben		NEED TO HAVE A COVER PUT OVER THE FIRE ALARM IN THE SPECIAL NEEDS CLASSROOM. ROOM101- PER DANNNY MIRANDA							
Debra Facio									
36221					7/25/2008		173		\$0.00
Medium	Work In Progress			7/25/2008 11:32:11 AM					
Lozoya, Manny		NEED A NEW DOOR CLOSER IN RM. 308, (LCN 4041)							
Danny Miranda									
37940					9/9/2008		127		\$0.00
Medium	Work In Progress			9/9/2008 10:02:37 AM					
Lozoya, Manny		need locks with long shank for outside gates custodians have trouble locking the ones that are there total of six gates							
Danny Miranda									
38100		Classroom			9/15/2008		121		\$0.00
High	Work In Progress			9/15/2008 3:46:51 PM					
Ronquillo, Ruben		Broken window in room 203. (CASE# 2008-08888) Est. Damage 255.00							
Alfredo Holguin									
38773					10/5/2008	10/26/2008	101		\$0.00
Medium	Work In Progress			10/5/2008 12:24:00 AM					
Orozco, Danny		Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.							
Margret Villalobos									
39777					11/3/2008		72		\$0.00
Medium	Work In Progress			11/3/2008 12:27:44 PM					
Ontiveros, Joe		NEED TO REPAIR SINK IN GIRLS R.R. 200-WING							
Danny Miranda									
39782					11/3/2008		72		\$0.00
Medium	Work In Progress			11/3/2008 3:03:07 PM					
Ontiveros, Joe		NEED TO REPAIR WATER LEAK IN 2" LINE IN 200-WING HALLWAY							
Danny Miranda									

1/14/2009 11:38:17 AM

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
40046					11/13/2008		62		\$0.00
Medium	Work In Progress				11/13/2008 9:12:21 AM				
Miranda, Danny		NEED NEW EXIT SIGN IN GYM & 200-WING HALLWAY				Request thru Material Request Form. (e-mailed) mkv			
<u>Danny Miranda</u>									
40047					11/13/2008		62		\$0.00
Medium	Work In Progress				11/13/2008 9:13:38 AM				
Sotelo, Enrique		NEED TO CK. LIGHT IN 100-WING R.R. STAFF							
<u>Danny Miranda</u>									
40048	Main Building	Restroom (Boys)			11/13/2008		62		\$0.00
Medium	Work In Progress				11/13/2008 9:15:32 AM				
Sotelo, Enrique		NEED TO CK. LIGHT IN BOYS R.R. EMERGENCY LIGHT NOTCOMMING ON							
<u>Danny Miranda</u>									
40049					11/13/2008		62		\$0.00
Medium	Work In Progress				11/13/2008 10:49:45				
Miranda, Danny		NEED SOME BATTERIES FOR EXIT SIGNES # NICO148 80AAS 1.2 V							
<u>Danny Miranda</u>									
40212	Main Building				11/19/2008		56		\$0.00
Medium	Work In Progress	PSFA Site Visit			11/19/2008 9:44:32 AM				
Miranda, Danny		Roof top (Center) Recovery wheel is squeaking, please look into it and see what needs to be done.							
<u>Michael Munoz</u>									
40481					12/2/2008		43		\$0.00
Medium	Work In Progress				12/2/2008 8:31:54 AM				
Gonzalez, Salvador		Need 5 metal covers.							
<u>Enrique Sotelo</u>									
40656					12/7/2008	12/23/2008	38		\$0.00
Medium	Work In Progress				12/7/2008 12:16:18 AM				
Miranda, Danny		Monthly - Vado ES Playground Insp - Refer to PM schedule details.							
<u>George ZZ Gabaldon</u>									
40760					12/10/2008		35		\$0.00
Medium	Work In Progress				12/10/2008 3:40:45 PM				
Miranda, Danny		Casa Verde Wing, Boys RR Exhaust Fan vibrating and making loud noise. Please Check.							
<u>Michael Munoz</u>									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
40869					12/15/2008		30		\$0.00
Medium	Work In Progress				12/15/2008 2:18:32 PM				
Solis, Lorenzo		NEED TO REPAIR EXHAUST FAN AND KNOBS ON STOVE IN TEACHERS LOUNGE							
Danny Miranda									
41065					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:47 AM				
Miranda, Danny		Monthly - Vado ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
41066					1/4/2009	1/10/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:18:47 AM				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
41127					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:19:13 AM				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
41135					1/4/2009	1/12/2009	10		\$0.00
Medium	Work In Progress				1/4/2009 12:19:16 AM				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
41189					1/6/2009		8		\$0.00
Medium	Work In Progress				1/6/2009 10:43:25 AM				
Sotelo, Enrique		NEED TO REPAIR THREE POWER POLES IN KITCHEN							
Danny Miranda									
41360					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:25 AM				
Diaz, Armando		Monthly - QRTL BLDG INSP REPORT (VE) - Refer to PM schedule details.							
Jesus Estrada									
41377					1/11/2009	1/27/2009	3		\$0.00
Medium	Work In Progress				1/11/2009 12:17:31 AM				
Miranda, Danny		Monthly - Vado ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									

998 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Vado ES							
41428		Cafeteria			1/13/2009		1		\$0.00
Medium	Work In Progress				1/13/2009 10:07:49 AM				
Orozco, Danny	3-COMPARTMENT SINK IS LEAKING.								
	LAURA B. SNP MGR 233-2945								
Jacqueline Aguilar									
Count: 26 Work Orders		Avg. Age of WO's		65	Total for Vado ES			0	\$0.00
Count: 998 Work Orders		Avg. Age of WO's		83	Grand Total			9	\$225.00