

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Anthony ES								
35695					7/6/2008	8/6/2008	240		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:06 AM						
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
36176	Cafeteria	Cafeteria			7/24/2008		222		\$0.00	
Medium	Work In Progress			7/24/2008 11:26:39 AM						
Ontiveros, Guadalupe		remove old tree next to cafeteria, health issue as per ms.marquez								
David Vega										
36641	Drug Free Bldg.				8/5/2008		210		\$0.00	
Medium	Work In Progress			8/5/2008 10:48:59 AM						
Sotelo, Enrique		please install a power strip for radios. please see irene for location.thxs								
Michael Munoz										
37287	Cafeteria	Cafeteria			8/21/2008		194		\$0.00	
Medium	Work In Progress			8/21/2008 11:49:08 AM						
Orozco, Danny		SEAL TO WALK-IN REFRIGERATOR IS ALL TORN AND MOLDY, SEAL NEEDS TO BE REPLACED								
		BECKY SAENZ - 882-3507 (K-3 CAFETERIA)								
Alma Terrell										
39028		Athletic Field			10/8/2008		146		\$0.00	
Medium	Work In Progress			10/8/2008 10:07:55 AM						
Appelzoller, Fred		Outside water fountains mounted on concrete block columns located east of the Old Main Cafeteria are not working. REPAIR								
Alfredo Holguin										
40016	Cafeteria	Cafeteria			11/12/2008		111		\$0.00	
Medium	Work In Progress			11/12/2008 7:52:56 AM						
Sotelo, Enrique		please install light fixture in bathroom, old main cafeteria where remodeling is being done. thxs								
Michael Munoz										
41163	Original Main	Athletic Field			1/5/2009		57		\$0.00	
Medium	Work In Progress			1/5/2009 2:35:27 PM						
Holguin, Alfredo		Canopy tore in pieces by wind need to replace old main blg side palyground equipment								
Hector Villalobos										
41265		Athletic Field			1/8/2009		54		\$0.00	
Medium	Work In Progress			1/8/2009 9:09:39 AM						
Ronquillo, Ruben		mild blg playground equipment slide needs to be replaced. Before someone cut themselves.								
Hector Villalobos										

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
41625	Main Building	Classroom			1/20/2009		42		\$0.00
Medium	Work In Progress			1/20/2009 7:23:55 AM					
Lozoya, Manny		room 16 needs keys made for cabinet							
Hector Villalobos									
41626	Original Main	Office			1/20/2009		42		\$0.00
Medium	Work In Progress			1/20/2009 7:28:24 AM					
Lozoya, Manny		Room 112 needs adoor guard for door lock handle							
Hector Villalobos									
41627		Electrical Room			1/20/2009		42		\$0.00
Medium	Work In Progress			1/20/2009 7:39:20 AM					
Solis, Lorenzo		Mild blg collaborative room need to order a new remoto contoller for unit							
Hector Villalobos									
41846	Original Main	Classroom			1/26/2009		36		\$0.00
Medium	Work In Progress	214 H5		1/26/2009 12:43:46 PM					
Lozoya, Manny		NEED AN ADDITIONAL KEY TO ROOM 214				WOULD GREATLY APPRECIATE IF THIS CAN BE DONE ASAP			
Loraine Gandara									
41944	Original Main				1/28/2009		34		\$0.00
Medium	Work In Progress			1/28/2009 1:26:53 PM					
Lozoya, Manny		old main blg stoage supplie room needs door handle lock guard							
Hector Villalobos									
42372					2/9/2009		22		\$0.00
Medium	Work In Progress			2/9/2009 12:43:22 PM					
Lozoya, Manny		Need to ck padlock or issue a new key for the gate on church street, where the NM Environment Dept goes in. She said her key does not open that lock.							
Margret Villalobos									
42376	Cafeteria				2/9/2009		22		\$0.00
Medium	Work In Progress			2/9/2009 1:30:16 PM					
		Cafeteria - Light fixture covers need to be removed and cleaned immediately (bugs and debris could contaminate food) asp AE Health Inspection. Terry Portillo				2/20/09 - E-MAILED DAVID ON STATUS			
Aida Salcedo									
42600	Original Main	Mechanical Room			2/17/2009		14		\$0.00
Medium	Work In Progress			2/17/2009 9:14:54 AM					
Solis, Lorenzo		old main blg boilers room pump is leaking							
Hector Villalobos									
42622	Main Building	Custodial			2/17/2009		14		\$0.00
Medium	Work In Progress			2/17/2009 1:12:42 PM					
Carbajal, Jimmy		repair wet vac							
David Vega									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
42826	Main Building	Restroom (Boys)			2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 7:53:02 AM				
Appelzoller, Fred		lav's in boys r-rms need replacement from 8" c-set to 4" c-set for better maintenance and up keep.							
Fred Appelzoller									
42859					2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 3:37:33 PM				
Carrasco, Danny		Danny need to conduct inventory of all Bldg Mechanic tools and equipment. Ask Ruben for present inventory list to match up.				Previos wo 23739 - 6/07			
Michael Munoz									
42895		Parking Lot			2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 8:28:10 AM				
Villalobos, David		Have contractor(s) see about installation of Backflow preventer for the school site to be located at far northwest end of campus next to main water meter							
David Villalobos									
42912		Classroom			2/25/2009		6		\$0.00
Medium	Work In Progress	ON TRACK PRE			2/25/2009 11:11:40 AM				
Ronquillo, Ruben		SCREENS & BLINDS FOR 4 CLASSROOMS * SCREENS FOR 20 WINDOWS 31 1/2 " H X 4 FT 11" W * BLINDS FOR 20 WINDOWS 54" H X 63" W BLINDS FOR OFFICE * 2 WINDOWS 38" H X 95" W * 2 WINDOWS 62" H X 34" W							
Lucy Meza									
42913					2/25/2009		6		\$0.00
Medium	Work In Progress	Anthony On Track			2/25/2009 11:12:28 AM				
Ronquillo, Ruben		Blinds for windows (6) in office portable and in two classrooms. 4- 47 x 37 2- 33 x 62							
Lucy Meza									
42914		Classroom			2/25/2009		6		\$0.00
Medium	Work In Progress	Pre - K			2/25/2009 11:13:20 AM				
Ronquillo, Ruben		P.R.E.K headstart rooms 306 307 blinds 12 63x54							
Hector Villalobos									
42964					2/26/2009		5		\$0.00
Medium	Work In Progress				2/26/2009 8:23:36 AM				
Appelzoller, Fred		Upper Primary - Need to relocate spikett.							
Michael Munoz									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
42971	Main Building	Custodial			2/26/2009		5		\$0.00
Medium	Work In Progress				2/26/2009 10:32:48 AM				
Carbajal, Jimmy		vaccum cleaner needs repair							
David Vega									
43105					3/1/2009		2		\$0.00
Medium	Work In Progress				3/1/2009 12:22:56 AM				
Orozco, Danny		Yearly - Anthony ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
43152					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:12 AM				
Villalobos, Hector		Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
43153					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:13 AM				
Villalobos, Hector		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
43154					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:13 AM				
Villalobos, Hector		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
43155					3/1/2009		2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:13 AM				
Villalobos, Hector		Yearly - Anthony ES A10(Heat Pumps)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
43156					3/1/2009	4/1/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:14 AM				
Villalobos, Hector		Yearly - Anthony ES R3 (Ref. Unit)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
43231	Annex Building	Office			3/2/2009		1		\$0.00
Medium	Work In Progress				3/2/2009 12:56:02 PM				
Lozoya, Manny		room 212 door lock handle broken off need to replace it annex blg							
Hector Villalobos									
Count: 32 Work Orders		Avg. Age of WO's 49		Total for Anthony ES				0	\$0.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
43085					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:22:48 AM				
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35696					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress				7/6/2008 12:20:06 AM				
Villalobos, David	Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36845					8/8/2008		207		\$0.00
Medium	Work In Progress	Mobile Home			8/8/2008 3:52:51 PM				
Sotelo, Enrique	Need to install utility hook-up for mobile home.								
<u>Michael Munoz</u>									
36879					8/11/2008		204		\$0.00
Medium	Work In Progress				8/11/2008 9:01:25 AM				
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR PER MR VALTIERRA HE WOULD LIKE THE SCHOOL CLEAN TO MANNY WEEDS PONDING AREA NEEDS CLEAN IN FRONT AND BACK AROUND PORTABLES ALONE FENCE IN FRONT OUTSIDE AND IN SIDE THANK YOU SIR								
<u>Adan Duran</u>									
38128					9/16/2008		168		\$0.00
Medium	Work In Progress				9/16/2008 10:30:21 AM				
Sotelo, Enrique	Emer. Light need replacing at west entrance and Custodial room.								
<u>Adan Duran</u>									
38159					9/17/2008		167		\$0.00
Medium	Work In Progress				9/17/2008 7:52:03 AM				
Lozoya, Manny	MR MANNY LOZOYA SIR WE NEED TO CHANGE OUTSIDE GATE PAD LOCKS SOMEONE IS OPENING OUR GATES CHANGE LOCKS AS SAME AS ENTRANCE DOOR THANK YOU SIR								
<u>Adan Duran</u>									
38442	Main Building				9/25/2008		159		\$0.00
Medium	Work In Progress				9/25/2008 3:59:37 PM				
Duran, Adan	Restrooms nest to multipurpose room- sand entrance doors and reseal								
<u>Alfredo Holguin</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
38699					10/3/2008		151		\$0.00
Medium	Work In Progress	Mobile Home		10/3/2008 10:42:41 AM					
Lozoya, Manny	As per Alfredo, need a gate key for Guadalupe Quinones the new mobile home occupant at Berino. The mobile home will be placed at the school this weekend.								
Alfredo Holguin									
38778					10/5/2008	10/26/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:02 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
39479					10/24/2008		130		\$0.00
Medium	Work In Progress			10/24/2008 3:26:04 PM					
Sotelo, Enrique	MR ENRIQUE SOTELO SIR EMERGENCY LIGHT FALL OFF WALL IN CAFETERIA NEED TO REPLACE BROKEN BURN ELEMENTS THE ONE IN CUSTODIAL ROOM ALSO THANK YOU SIR								
Adan Duran									
40073					11/13/2008		110		\$0.00
Medium	Work In Progress			11/13/2008 4:10:00 PM					
Lozoya, Manny	MR MANNY LOZOYA SIR WE NEED TO REPLACEMENT KEY THE TRASH MAN HAS B KEY BUT WE CHANGE GATE LOCKS TO B-1 HE COULD NOT GET IN MONDAY MUNCHO TRASH THANK YOU SIR								
Adan Duran									
40137					11/17/2008		106		\$0.00
High	Work In Progress			11/17/2008 11:07:56					
Lozoya, Manny	manny, you changed the core to the gates from a b to a b-1. the thrash guy does not have access. please make a new key for them and give to adan. he has the b for you.								
Michael Munoz									
40921					12/16/2008		77		\$0.00
Medium	Work In Progress			12/16/2008 3:45:59 PM					
Solis, Lorenzo	MR LORENZO SOLIS SIR THE HEATING UNIT IN THE GYM WILL NOT KICK ON NEED TO CHECK THANK YOU AND GOD BLESS								
Adan Duran									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
40997					12/18/2008		75		\$0.00
High	Work In Progress			12/18/2008 4:24:02 PM					
Miranda, Danny	as epr our conversation, the wall to the entrance of the boys restroom on the east wing has been kicked in. please replace w/ durock as discussed. if other areas at site need the same please take of them. Thxs								
<u>Michael Munoz</u>									
41069					1/4/2009	1/25/2009	58		\$0.00
Medium	Work In Progress			1/4/2009 12:18:49 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41153					1/5/2009		57		\$0.00
Medium	Work In Progress			1/5/2009 8:18:40 AM					
Lozoya, Manny	MR MANNY LOZOYA HAPPY NEW YEAR AND GOD BLESS MR LOZOYS SIR WE HAVE A BROKEN KEY IN GATE LOCK WEST GATE NEED TO REPLACE WILL NEED TO LOCK TO NIGHT THANK YOU SIR								
<u>Adan Duran</u>									
41506					1/14/2009		48		\$0.00
Medium	Work In Progress			1/14/2009 3:48:50 PM					
Gonzalez, Salvador	MR SAL GONZALEZ SIR THE SWING SET PLAY GROUND HAS A BENT PIPE NEED TO CUT REWELD OR REPLACE NEED TO LOOK AT IT THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
41707					1/21/2009		41		\$0.00
Medium	Work In Progress			1/21/2009 3:39:44 PM					
Gonzalez, Salvador	MR SAL GONZALES SIR THE BLEACHERS IN OUR PLAYGROUND HAVE BEEN VANDALISE TWO STEPS WHERE STOLEN NEED TO REPLACE 27 FEET LONG AND 9" WIDE I THINK 1/8 CHANNEL WILL DO NEED TO WELD ON ANGLE THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
41940					1/28/2009		34		\$0.00
Medium	Work In Progress	LINE LOCATE		1/28/2009 11:32:17 AM					
Ontiveros, Joe	Need to line locate by Palm Tree loacted on southwest area, where camera is located.								
Guadalupe Ontiveros									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
42002					1/29/2009		33		\$0.00
Medium	Work In Progress			1/29/2009 3:19:45 PM					
Sotelo, Enrique	MR ENRIQUE SOTELO SIR NEED TO CHECK MOTOR ON EXHUAST FAN ROOMS 105 AND 106 ALSO CHECK SWITCHS FANS NOT WORKING THANK YOU AND GOD BLESS								
Adan Duran									
42731					2/20/2009		11		\$0.00
Medium	Work In Progress			2/20/2009 7:31:46 AM					
Carbajal, Jimmy	HURICANE BLOWER NEEDS NEW PLUG								
Jimmy Cortez									
43055					2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 3:22:22 PM					
Sotelo, Enrique	MR ENRIQUE SOTELO PER MR VALTIERRA NEED TO REPLACE LIGHT BULBS GYM STAGE SOME ARE COLORED THANK YOU SIR AND GOD BLESS								
Adan Duran									
43083					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:47 AM					
Duran, Adan	Yearly - Berino ES A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43084					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:48 AM					
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
43086					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:49 AM					
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43106					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:57 AM					
Orozco, Danny	Yearly - Berino ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43239					3/2/2009		1		\$0.00
Medium	Work In Progress			3/2/2009 3:36:14 PM					
Castillo, Carlos	MR ENRIQUE SOTELO SIR THE POST LIGHTS OUT SIDE ARE NOT WORKING VERY DARK IN THE MORNING ALL AROUND THE PLAYGROUND FRONT AND SIDES NEED TO CHECK PLEASE THANK YOU SIR AND GOD BLESS								
Adan Duran									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

Count: 27 Work Orders	Avg. Age of WO's	83	Total for Berino ES	0	\$0.00
-----------------------	------------------	----	---------------------	---	--------

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral ES								
35694					7/6/2008	8/6/2008	240		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:05 AM						
Villalobos, David		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
36075		Office			7/18/2008		228		\$0.00	
Medium	Work In Progress	PRE-K		7/18/2008 4:55:16 PM						
Vargas, Juan		AS PER ANN STEINHOFF-THERE IS MOLD ON THE CEILING IN THE WORK ROOM AT THE PRE-K								
Mary Garcia										
36581					8/4/2008		211		\$0.00	
Medium	Work In Progress			8/4/2008 8:49:37 AM						
Vargas, Juan		barracas 406-408-410-412-414-416-418 need change master cools now have 3800 is to small need replace for 4500				Routed 8/11 - Assign to JC asp our conversation he needs to give units a good PM, where installed last year. Humidity is @ 70 and m/c swamps do not work well. m.munoz				
Juan Vargas										
37055	2001 Classroom				8/14/2008		201		\$0.00	
Medium	Work In Progress			8/14/2008 10:11:15 AM						
Vargas, Juan		need to add large rocks or cobblestones in areas where roof gutters are causing erosion								
Alfredo Holguin										
37056					8/14/2008		201		\$0.00	
Medium	Work In Progress			8/14/2008 10:14:39 AM						
Vargas, Juan		All sidewalks with more than 4" drop need to have fill dirt added - Call Mike or Alfredo when work is complete								
Alfredo Holguin										
37057					8/14/2008		201		\$0.00	
Medium	Work In Progress			8/14/2008 10:17:19 AM						
Vargas, Juan		Sand need to be leveled in fall areas of all playground structures on site.								
Alfredo Holguin										
37135	West Central				8/18/2008		197		\$0.00	
Medium	Work In Progress			8/18/2008 9:11:53 AM						
Vargas, Juan		new doors are being installed in the esat and west barrack. please order paint so you can paint doors. thxs								
Michael Munoz										
37990		Cafeteria			9/10/2008		174		\$0.00	
Medium	Work In Progress			9/10/2008 1:49:03 PM						
Orozco, Danny		Side of grease trap caving in.								
Michael Munoz										

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
38027		Athletic Field			9/11/2008		173		\$0.00
Medium	Work In Progress			9/11/2008 2:05:24 PM					
Ontiveros, Guadalupe	Lower Grades playground equipment located between classroom wings - Re layout plastic borders so they are around the remaining playground (slide) structure.								
Alfredo Holguin									
39939	E.Building	Classroom			11/7/2008		116		\$0.00
Medium	Work In Progress	509		11/7/2008 10:55:11 AM					
Lozoya, Manny	need cabinet to be relocked. Need new lock for it and key. Teacher for Visually impaired will be storing important and expensive merchandise in there and needs for it to be safe. See Ms. Kayce speech Teacher								
Jennifer Corral									
40051		Classroom			11/13/2008		110		\$0.00
Medium	Work In Progress	512		11/13/2008 12:36:13					
Lozoya, Manny	need cabinet in rm to place belongings very expensive but does not have a key. So would like it to be redone and get a key for it. See Ms. Kayce SLP Speech Teacher. As soon as possible								
Jennifer Corral									
40239					11/19/2008		104		\$0.00
Medium	Work In Progress			11/19/2008 3:48:17 PM					
Lozoya, Manny	would you please check the automatic door opener for handicap on the north side of the main hallway. Thank you								
Guillermo Hernandez									
40604					12/4/2008		89		\$0.00
Medium	Work In Progress			12/4/2008 4:46:38 PM					
Sotelo, Enrique	Need assistance to replace two outside light fixtures of portable 34DW (#402 and #404)								
Guillermo Hernandez									
40796		Cafeteria			12/11/2008		82		\$0.00
Medium	Work In Progress			12/11/2008 1:44:34 PM					
Orozco, Danny	IT'S LEAKING ALOT OF WATER FROM CEILING (INSIDE WALK-IN REFRIGERATOR)								
	ESTHER CISNEROS - SNP MANAGER 824-0048								
Alma Terrell									
41137					1/4/2009		58		\$0.00
Medium	Work In Progress			1/4/2009 12:19:17 AM					
Jacquez, Ricardo	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
41968					1/28/2009		34		\$0.00
Medium	Work In Progress			1/28/2009 3:46:13 PM					
Ontiveros, Joe	Need to replace two bubblers on the water fountain by the field and one by E wing. Thank you.								
<u>Guillermo Hernandez</u>									
41982					1/29/2009		33		\$0.00
Medium	Work In Progress			1/29/2009 9:19:23 AM					
Hernandez, Guillermo	Please install gutters on portable 34DW.								
<u>Guillermo Hernandez</u>									
42180					2/3/2009		28		\$0.00
Medium	Work In Progress			2/3/2009 11:54:25 AM					
Estrada, Jesus	ROOM 504 - SEAM COMING UNDONE CARPET WAS INSTALLED APPROX. MARCH/APRIL OF 2007, REF W.O. #19573								
<u>Jesus Estrada</u>									
42286					2/5/2009		26		\$0.00
Medium	Work In Progress			2/5/2009 3:39:10 PM					
Sotelo, Enrique	Need assistance to replace ballasts in Portable #P-1 & #P-2 (2 lamp ballast) Thank you								
<u>Guillermo Hernandez</u>									
42288					2/5/2009		26		\$0.00
Medium	Work In Progress			2/5/2009 3:41:08 PM					
Sotelo, Enrique	Need assistance to replace ballasts in # P-7 Pre-K (4 lamp ballast) Thank you.								
<u>Guillermo Hernandez</u>									
42423		Cafeteria			2/10/2009		21		\$0.00
Medium	Work In Progress			2/10/2009 1:45:42 PM					
Orozco, Danny	HOSE ON SERVING LINE IS LEAKING ESTHER CISNEROS - SNP MANAGER 824-0048								
<u>Alma Terrell</u>									
42473		Cafeteria			2/11/2009		20		\$0.00
Medium	Work In Progress			2/11/2009 8:55:37 AM					
Orozco, Danny	CHECKED WITH ESTHER THIS MORNING 2/11/09 - OVENS STILL DO NOT HEAT UP - SHE HAS TO CHANGE FROM ONE OVEN TO ANOTHER ESTHER CISNEROS - SNP MANAGER								
<u>Alma Terrell</u>									
42714					2/19/2009		12		\$0.00
Medium	Work In Progress			2/19/2009 2:07:11 PM					
Castillo, Carlos	Please check electrical components in the electrical panel inside the Irrigation pressure tank area. (Booster Pump does not work to the Irrigation Pressure Tank)				2/20 - route to Cali asp Mike				
<u>Johnny Acuna</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
42880					2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 7:43:36 AM				
Hernandez, Guillermo	Need to install missing sheet metal A/C covers to the units. 16pcs=26X42 and 6pcs=24X36		2/27 - asp Mike route to Memo						
Guillermo Hernandez									
42953					2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 3:57:41 PM				
Lozoya, Manny	Having hard time to lock door on classroom #408, key just turn around.								
Guillermo Hernandez									
42960					2/26/2009		5		\$0.00
Medium	Work In Progress				2/26/2009 7:44:24 AM				
Lozoya, Manny	Room # 202 (New Wing Area): Doorknob to classroom does not unlock. Teachers have to enter through the room next door to be able to enter their classroom.								
Johnny Acuna									
42962					2/26/2009		5		\$0.00
Medium	Work In Progress				2/26/2009 7:47:42 AM				
Munoz, Michael	Need assistance to check light on the parking lot. Requesting bucket truck. Thank you								
Guillermo Hernandez									
42963					2/26/2009		5		\$0.00
Medium	Work In Progress				2/26/2009 7:51:14 AM				
Gonzales, Angel	Need to use Bobcat to remove sand againsts the fence that it is piling up. Thank you								
Guillermo Hernandez									
43027		Custodial			2/27/2009		4		\$0.00
Medium	Work In Progress				2/27/2009 10:09:48 AM				
Carbajal, Jimmy	need, to, fix, vaccum, cleaner, broken								
Daniel Ramirez									
43069					2/27/2009		4		\$0.00
Medium	Work In Progress				2/27/2009 3:58:35 PM				
Ontiveros, Joe	Would you please replace the flushing valves to the comodes in the boy's and girl's restrooms. Thank you								
Guillermo Hernandez									
43079					2/28/2009		3		\$0.00
Medium	Work In Progress				2/28/2009 12:19:59 AM				
Hernandez, Guillermo	Monthly - Chaparral ES A-16 Exh Fan (Semi Annual) - Refer to PM schedule details.								
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral ES								
43107					3/1/2009		2		\$0.00	
Medium	Work In Progress			3/1/2009 12:22:57 AM						
Orozco, Danny	Yearly - Chaparral ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43141					3/1/2009	3/9/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:08 AM						
Hernandez, Guillermo	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43142					3/1/2009	3/7/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:09 AM						
Hernandez, Guillermo	Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43143					3/1/2009	3/9/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:09 AM						
Hernandez, Guillermo	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43144					3/1/2009	3/22/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:10 AM						
Hernandez, Guillermo	Monthly - Chaparral ES H-11 Unit Heater Semiannual - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43145					3/1/2009		2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:10 AM						
Hernandez, Guillermo	Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43146					3/1/2009		2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:10 AM						
Hernandez, Guillermo	Yearly - Chaparral ES A-10 HP Rooftop Yearly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43208					3/1/2009		2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:31 AM						
Jacquez, Ricardo	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
Count: 39 Work Orders	Avg. Age of WO's 68		Total for Chaparral ES				0	\$0.00		

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral HS								
35714					7/6/2008	8/6/2008	240		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:12 AM						
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
35869					7/11/2008		235		\$0.00	
Medium	Work In Progress			7/11/2008 9:39:33 AM						
Lozoya, Manny		RE-KEY LEFT UPPER AND LOWER CABINETS FOR STORAGE LOCATED BEHIND THE RECEPTIONST FOR THE REGISTRAR (HEMPHILL)								
Rosa Quezada										
35870		Office			7/11/2008		235		\$0.00	
Medium	Work In Progress	FRONT OFFICE		7/11/2008 9:41:05 AM						
Lozoya, Manny		RE-KEY RIGHT UPPER AND LOWER CABINETS FOR STORAGE LOCATED BEHIND THE RECEPTIONIST (GARCIA)								
Rosa Quezada										
36093		Classroom			7/21/2008		225		\$0.00	
Medium	Work In Progress	D-7		7/21/2008 3:47:12 PM						
Lozoya, Manny		NEED 1G032 SPARE KEY FOR FLAMABLE CABINET IN D-7(QUEZADA)								
Rosa Quezada										
36579		Classroom			8/4/2008		211		\$0.00	
Medium	Work In Progress	F Wing - Rm. 5		8/4/2008 8:18:45 AM						
Lozoya, Manny		Need a CH73 key for classroom F-5. (Paul H. Geiger)								
Guadalupe Gonzalez										
36593		Classroom			8/4/2008		211		\$0.00	
Medium	Work In Progress	R Wing - Rm. 1		8/4/2008 1:55:06 PM						
Lozoya, Manny		Due to high security requirements, the control room door key must be cored the same as the storage room door. It is to be "off master" like the storage room.								
Guadalupe Gonzalez										
36606	B-Wing	Classroom			8/4/2008		211		\$0.00	
Medium	Work In Progress	Rm B-3		8/4/2008 3:13:25 PM						
Lozoya, Manny		Need keys D274AR & D273AR. (Emmanuel Okeafor)								
Guadalupe Gonzalez										
36959	A-Wing	Office			8/12/2008		203		\$0.00	
Medium	Work In Progress			8/12/2008 3:11:57 PM						
Lozoya, Manny		Need to re-key mailroom to fit GM3 key.								
Guadalupe Gonzalez										
37177					8/19/2008		196		\$0.00	
Medium	Work In Progress	Concession		8/19/2008 7:55:32 AM						
Lozoya, Manny		Need key to concession stand. (Mr. Sanchez)								
Guadalupe Gonzalez										

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral HS								
37220					8/20/2008		195		\$0.00	
Medium	Work In Progress			8/20/2008 8:34:48 AM						
Lozoya, Manny		Need a CH73 key for classroom for F Wing - Rm. 5. (Paul H. Geiger)								
Guadalupe Gonzalez										
37394		Classroom			8/26/2008		189		\$0.00	
Medium	Work In Progress	Nurse		8/26/2008 11:42:37 AM						
Lozoya, Manny		Need keys CH6 for Nurse's office and CH5 for the storage room in the Health Center. (Ana Castro)								
Guadalupe Gonzalez										
37783					9/4/2008		180		\$0.00	
Medium	Work In Progress			9/4/2008 10:52:49 AM						
Lozoya, Manny		(65) LATCH PROTECTORS ARE REQUESTED FOR CLASS RMS AND OFFICE DOORS								
Eddie Baeza										
37893					9/8/2008		176		\$0.00	
Medium	Work In Progress	q-4		9/8/2008 10:21:54 AM						
Lozoya, Manny		need a CH-1 for auto construction labs.								
Rosa Quezada										
38307		Classroom			9/22/2008		162		\$0.00	
Medium	Work In Progress	Q-7		9/22/2008 1:13:03 PM						
Lozoya, Manny		NEED CH-94 (2) FOR Q-2 FOR LAB AND CAGES ONE & TWO NEED CH-96 (2) FOR Q-6 FOR LAB AND CAGE KEYS (FOR PETE GALVAN)								
Rosa Quezada										
38324					9/22/2008		162		\$0.00	
Medium	Work In Progress			9/22/2008 3:28:35 PM						
Lozoya, Manny		THERE ARE SEVERAL PANIC BARS AND LOCK-SETS THAT ARE NOT WORKING PROPERLY ON CAMPUS.								
Eddie Baeza										
38577					9/30/2008		154		\$0.00	
Medium	Work In Progress			9/30/2008 3:53:50 PM						
Lozoya, Manny		CHANGE THE LOCK ON THE TRAINERS ROOM OFF OF CH-86								
Eddie Baeza										
38578					9/30/2008		154		\$0.00	
Medium	Work In Progress			9/30/2008 3:56:13 PM						
Lozoya, Manny		(4) DOORS IN THE LOCKER ROOMS NEED TO BE DOUBLE KEYED. (4) DOORS NEED TO BE CHANGED TO LATCH FOR SAFETY AND SECURITY REASONS								
Eddie Baeza										

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral HS

38742					10/5/2008		149		\$0.00
Medium	Work In Progress			10/5/2008 12:23:49 AM					
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.		10/6/08 - Emailed to Ricky Borrego						
<u>Margret Villalobos</u>									
38989					10/7/2008		147		\$0.00
Medium	Work In Progress			10/7/2008 8:47:09 AM					
Lozoya, Manny	PAD LOCKS AT THE ATHLETIC FEILDS NEED TO BE SECURED SO THEY WILL NOT BE LOST.								
<u>Eddie Baeza</u>									
38995					10/7/2008		147		\$0.00
Medium	Work In Progress			10/7/2008 11:12:22 AM					
Lozoya, Manny	Need a Master Key for Trane Company. They will be working during Fall Break. (approved by A. Holguin)								
<u>Alfredo Holguin</u>									
39019					10/7/2008		147		\$0.00
Medium	Work In Progress			10/7/2008 3:55:21 PM					
Lozoya, Manny	Greenhouses attached to building - Change door hardware between building and greenhouse to appropriate type.								
<u>Alfredo Holguin</u>									
39194					10/13/2008		141		\$0.00
Medium	Work In Progress	workroom Q & R		10/13/2008 3:43:04 PM					
Lozoya, Manny	NEED TO KEY Q & R WING WORKROOMS SO THAT ALL TEACHERS HAVE ACCESS TO COPIER (QUEZADA)								
<u>Rosa Quezada</u>									
39303	A-Wing	Custodial			10/20/2008		134		\$0.00
Medium	Work In Progress			10/20/2008 2:42:25 PM					
Lozoya, Manny	NEED 4 COPIES OF THE TRASH COMPACTOR KEY FOR HEAD CUSTODIAN ARMANDO RIVERA (QUEZADA)								
<u>Rosa Quezada</u>									
39306					10/20/2008		134		\$0.00
Medium	Work In Progress	SOCCER		10/20/2008 2:44:56 PM					
Lozoya, Manny	NEED 3 COPIES OF CH-86 KEYS FOR SOCCER COACHES								
<u>Rosa Quezada</u>									
39328					10/21/2008		133		\$0.00
Medium	Work In Progress			10/21/2008 8:25:53 AM					
Lozoya, Manny	(10) BEST PADLOCKS WITH LONG SHANKS ARE REQUESTED FOR EQUIPMENT IN NEW WEIGHT ROOM.								
<u>Eddie Baeza</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
39337					10/21/2008		133		\$0.00
Medium	Work In Progress			10/21/2008 1:12:48 PM					
Lozoya, Manny		WE ARE UNABLE TO OPEN VAULT AT MAIN OFFICE, AND KEY JUST KEEPS TURNING.							
<u>Eddie Baeza</u>									
39363	A-Wing	Classroom			10/22/2008		132		\$0.00
Medium	Work In Progress	storage room		10/22/2008 9:20:35 AM					
Lozoya, Manny		NEED TO CHANGE CORE IN MAIN STORAGE ROOM IN FRONT OFFICE TO FIT TO KEY GM3 (QUEZADA)							
<u>Rosa Quezada</u>									
39393					10/22/2008		132		\$0.00
Medium	Work In Progress			10/22/2008 3:50:18 PM					
Ontiveros, Guadalupe		(4) BATTING CAGES ARE REQUESTED FOR THE BASEBALL FIELDS.							
<u>Eddie Baeza</u>									
39983	A-Wing	Office			11/11/2008		112		\$0.00
Medium	Work In Progress	front main door		11/11/2008 9:09:53 AM					
Lozoya, Manny		NEED TO REKEY FRONT MAIN DOOR TO CH-86 (DIGGS)							
<u>Rosa Quezada</u>									
39984					11/11/2008		112		\$0.00
Medium	Work In Progress	CONCESSION		11/11/2008 9:10:50 AM					
Lozoya, Manny		NEED TO RE-KEY CONCESSION ROOM TO OPEN ON MASTER							
<u>Rosa Quezada</u>									
40133					11/17/2008		106		\$0.00
Medium	Work In Progress	Storage Area		11/17/2008 10:18:06					
Lozoya, Manny		The storage for the building mechanic at CHS needs to be keyed so Mike and I have access to it. When we were there last week our key would not work. please correct this.							
<u>Alfredo Holguin</u>									
40350	A-Wing	Office			11/25/2008		98		\$0.00
Medium	Work In Progress	TESTING		11/25/2008 3:46:50 PM					
Lozoya, Manny		NEED TO REKEY TESTING STORAGE ROOM LOCATED IN THE MAIN OFFICE.							
<u>Rosa Quezada</u>									
40562					12/3/2008		90		\$0.00
Medium	Work In Progress			12/3/2008 3:52:43 PM					
Lozoya, Manny		Check w/Paul to see if there is any other keys he needs for this site. He already has a GM.							
Michael Munoz									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
40705		Gym			12/9/2008		84		\$0.00
Medium	Work In Progress	Gym		12/9/2008 2:10:35 PM					
Lozoya, Manny		Left gym door does not lock. (Mr. Sanchez)							
Guadalupe Gonzalez									
40735		Classroom			12/10/2008		83		\$0.00
Medium	Work In Progress	F Wing -		12/10/2008 10:10:47					
Lozoya, Manny		Replace lock in Teacher's Lounge, it doesn't lock.							
Guadalupe Gonzalez									
40736		Office			12/10/2008		83		\$0.00
Medium	Work In Progress	Office		12/10/2008 10:12:29					
Lozoya, Manny		Replace the lock to the door in the west side of the front office. It doesn't lock.							
Guadalupe Gonzalez									
40782	A-Wing				12/11/2008		82		\$0.00
Medium	Work In Progress			12/11/2008 9:11:02 AM					
Quinones, Paul		Need to install pencil sharpeners in the A Wing. (Ms. Ballard)							
Guadalupe Gonzalez									
40783		Classroom			12/11/2008		82		\$0.00
Medium	Work In Progress	R Wing - Rm. 1		12/11/2008 9:15:05 AM					
Lozoya, Manny		Plate needs to be installed over door latch/jamb to prevent unauthorized entry into the studio facility. As soon as possible. (Mr. Gabaldon)							
Guadalupe Gonzalez									
40824					12/12/2008		81		\$0.00
Medium	Work In Progress			12/12/2008 8:53:14 AM					
Lozoya, Manny		Need to issue a key to J. Acuna for Paul Quinones office.							
Michael Munoz									
40870		Classroom			12/15/2008		78		\$0.00
Medium	Work In Progress	R Wing - Rm. 2		12/15/2008 2:29:31 PM					
Lozoya, Manny		Door will not lock properly in R Wing - Rm. 2 (Mr. Aguilar)							
Guadalupe Gonzalez									
40904					12/16/2008		77		\$0.00
Medium	Work In Progress			12/16/2008 11:12:15					
Lozoya, Manny		Paper Recycle Bins - Install regular master padlocks on them. (Any ?'s see Alfredo) - Please let him know when it is complete.							
Alfredo Holguin									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
40973					12/18/2008		75		\$0.00
Medium	Work In Progress				12/18/2008 11:05:11				
Lozoya, Manny	PROTECTOR LATCHES,AND DOOR STOPS ARE NEEDED TO ALL CLASS RM. DOORS,AND OTHER DOORS REQUESTED BY CHS PRINCAPLE.ADDITIONAL HELP WILL HELP AS PROJECT STARTS.THANKS MANNY								
Paul Quinones									
41139					1/4/2009		58		\$0.00
Medium	Work In Progress				1/4/2009 12:19:18 AM				
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41140					1/4/2009		58		\$0.00
Medium	Work In Progress				1/4/2009 12:19:19 AM				
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
41141					1/4/2009		58		\$0.00
Medium	Work In Progress				1/4/2009 12:19:19 AM				
Quinones, Paul	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41142					1/4/2009	1/12/2009	58		\$0.00
Medium	Work In Progress				1/4/2009 12:19:20 AM				
Quinones, Paul	Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
41144					1/4/2009	2/4/2009	58		\$0.00
Medium	Work In Progress				1/4/2009 12:19:21 AM				
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
41150					1/4/2009		58		\$0.00
Medium	Work In Progress				1/4/2009 12:19:23 AM				
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.					1/6/09 e-mailed to ricky.borrego@cummins.com - mkv			
Margret Villalobos									
41178					1/5/2009		57		\$0.00
Medium	Work In Progress	R-Bldg			1/5/2009 3:59:51 PM				
Lozoya, Manny	DOOR IN R-2 BUILDING DOOR DOESNT LOCK DOOR ENTRANCE.								
Paul Quinones									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
41180					1/5/2009		57		\$0.00
Medium	Work In Progress				1/5/2009 4:02:23 PM				
Lozoya, Manny	DOOR NEXT TO FRONT ENTRANCE WILL NOT LOCK WITH KEY.ON THE LEFT SIDE OF DOOR.								
Paul Quinones									
41479					1/14/2009		48		\$0.00
Medium	Work In Progress	SECURITY			1/14/2009 9:12:39 AM				
Lozoya, Manny	RE-KEY SECURITY SHACK WHEN COMPLETED WITH A CH-1 KEY. (DE SANTIAGO)								
Rosa Quezada									
41529		Computer Lab			1/15/2009		47		\$0.00
Medium	Work In Progress	B Wing -			1/15/2009 2:15:39 PM				
Lozoya, Manny	Right entrance door to the classroom can not be unlocked with the key. Please check. (Ms. Duran-Campbell)								
Guadalupe Gonzalez									
41607					1/16/2009		46		\$0.00
Medium	Work In Progress				1/16/2009 3:12:37 PM				
Lozoya, Manny	FIELD HOUSE BUILDING,BOYS WEIGHT RM.DOOR ENTRANCE KEY CYLINDERS DEED TO BE REPLACED FROM MULLEN TO BEST 2 DOORS.GIRLS LOCKER RM.3 CYLINDERS WILL BE NEEDED,AND BOYS LOCKER RM.4 CYLINDERS WILL BE NEEDED TO PANIC BARS THANKS								
Paul Quinones									
41608					1/16/2009		46		\$0.00
Medium	Work In Progress				1/16/2009 3:18:26 PM				
Sotelo, Enrique	Q,AND R BUILDING BUILDING ELECTRICAL KEY SWITCHES NEED TO BE REPLACED IN RES RMS.,AND HALL WAYS. CUSTODIANS HAVIING PROBLEMS TURNING OFF LIGHTS. MUCHOS GRACIAS HENRY.								
Paul Quinones									
41610					1/16/2009		46		\$0.00
Medium	Work In Progress				1/16/2009 3:23:48 PM				
Lozoya, Manny	REAR GATE TO KITCHEN REAR ENTRANCE.HOLES ARE NEEDED TO BE PLACED ON FLOOR TO SECURE GATE LATCHES								
Paul Quinones									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
41612					1/16/2009		46		\$0.00
Medium	Work In Progress			1/16/2009 3:28:00 PM					
Lozoya, Manny	GYM ENTRANCE DOORS HOLES NEED TO BE PLACED TO SECURE DOOR LATCHES								
Paul Quinones									
41787					1/23/2009		39		\$0.00
Medium	Work In Progress			1/23/2009 9:47:49 AM					
Quinones, Paul	AS PER MIKE WEEDS NEED TO BE CUT AND CLEANED. FOCUS ON FRONT OF SCHOOL, ISLANDS, COVES AND FENCE LINES.								
Michael Munoz									
41896		Mechanical Room			1/27/2009		35		\$0.00
Medium	Work In Progress	field house by		1/27/2009 2:15:28 PM					
Lozoya, Manny	change keys to field house by football field to CH-Master (jdiggs)								
Rosa Quezada									
41973					1/28/2009		0		\$0.00
High	Work In Progress			1/28/2009 4:21:00 PM	1/28/2009				
Lozoya, Manny	Head Custodian Armando Rivera needs his desk to lock so he can keep documents locked up.								
Jesus Estrada									
42027					1/30/2009		32		\$0.00
Medium	Work In Progress			1/30/2009 12:56:48 PM					
Lozoya, Manny	NEED TO REPLACE LOCKS IN HOT BOX FENCE AREA NORTH END FENCE LINE.								
Paul Quinones									
42113					2/1/2009		30		\$0.00
Medium	Work In Progress			2/1/2009 12:24:48 AM					
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42114					2/1/2009		30		\$0.00
Medium	Work In Progress			2/1/2009 12:24:49 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
42115					2/1/2009		30		\$0.00
Medium	Work In Progress			2/1/2009 12:24:49 AM					
Quinones, Paul	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
42116					2/1/2009	3/4/2009	30		\$0.00
Medium	Work In Progress			2/1/2009 12:24:49 AM					
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
42182					2/3/2009		28		\$0.00
Medium	Work In Progress			2/3/2009 12:59:06 PM					
Lozoya, Manny	PANIC BAR IN REAR ENTRANCE KITCHEN NEEDS TO BE SECURED TO DOOR FOR SAFETY PURPOSES, AND TO LOCCK DOOR								
Paul Quinones									
42183					2/3/2009		28		\$0.00
Medium	Work In Progress			2/3/2009 1:04:18 PM					
Lozoya, Manny	ADMIN.OFFICE NEEDS CAM LOCK TO SECURE PARTITION IN OFFICE AREA NEXT TO MR.DIGGS OFFICE								
Paul Quinones									
42184					2/3/2009		28		\$0.00
Medium	Work In Progress			2/3/2009 1:07:28 PM					
Ontiveros, Joe	ARMSTRONG CIRCULATING PUMP SEAL LEAKING, SECURE RETURN HOT WATER DOMESTIC WATER LINE TO BOILER								
Paul Quinones									
42197					2/3/2009		28		\$0.00
Medium	Work In Progress			2/3/2009 3:32:47 PM					
Lozoya, Manny	OUTSIDE DOOR HEALTHCENTER AREA DOOR WILL NOT CLOSE DOOR FROM CYLINDER, AND THE PANIC BAR KEY CYLINDER AS WELL.								
Paul Quinones									
42403					2/10/2009		21		\$0.00
Medium	Work In Progress			2/10/2009 8:31:08 AM					
Sotelo, Enrique	NEED TO INSTALL OUTLETS IN NEW GROUNDS STORAGE.								
Guadalupe Ontiveros									
42463					2/11/2009		20	5.5	\$137.50
Medium	Work In Progress			2/11/2009 7:55:45 AM					
Solis, Lorenzo	COMPUTER RM. UNITS 1, AND 2 IN C WING WILL NOT RESET								
Paul Quinones			2/12 - Ck'd and Troubleshoot unit, with Rover and Tracer Summit, could not reset possible problem with Trane Controls. Please have Trane Rep, take a look at this rooms. Thanks, Lorenzo Solis						

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
42464					2/11/2009		20	5.5	\$137.50
Medium	Work In Progress			2/11/2009 7:57:28 AM					
Solis, Lorenzo		UNIT IN WING G WILL NOT RESET UNIT 2 IN COMPUTER LAB				2/12 - Ck'd and Troubleshoot unit, with Rover and Tracer Summit, could not reset possible problem with Trane Controls. Please have Trane Rep, take a look at this rooms. Thanks, Lorenzo Solis			
Paul Quinones									
42479	A-Wing	Library			2/11/2009		20		\$0.00
Medium	Work In Progress	trophy case		2/11/2009 11:14:25 AM					
Lozoya, Manny		replace lock on display case (middle one) for the library							
Rosa Quezada									
42480					2/11/2009		20		\$0.00
Medium	Work In Progress	whole school		2/11/2009 11:18:00 AM					
Lozoya, Manny		NEED A CH-1 FOR JOHNNY VALLES (GROUNDSMAN) QUEZADA							
Rosa Quezada									
42740		Athletic Field			2/20/2009		11		\$0.00
Medium	Work In Progress			2/20/2009 9:20:13 AM					
Villalobos, David		leaking domestic Backflow Preventer needs to be repaired							
David Villalobos									
43104					3/1/2009	3/22/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:56 AM					
Orozco, Danny		Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
43122					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:02 AM					
Orozco, Danny		Yearly - Chaparral HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
43199					3/1/2009	4/1/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:28 AM					
Quinones, Paul		Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
43200					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:29 AM					
Quinones, Paul		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral HS									
43201					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:29 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
43202					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:29 AM					
Quinones, Paul	Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43203					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:30 AM					
Quinones, Paul	Yearly - Chaparral HS A10 (Heat Pump)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43227		Cafeteria			3/2/2009		1		\$0.00
Medium	Work In Progress			3/2/2009 9:26:05 AM					
Carbajal, Jimmy	scrubber-auto bearings from motor making to much noise droning battery								
Armando Rivera									
43253		Athletic Field			3/3/2009		0		\$0.00
High	Work In Progress			3/3/2009 8:21:36 AM					
Valles, Johnny	need to install gates behind home site blachers.Also need gate by grounds storage to secure area.								
Guadalupe Ontiveros									
Count: 83 Work Orders			Avg. Age of WO's 88			Total for Chaparral HS	11		\$275.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral MS								
35697					7/6/2008	8/6/2008	240		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:06 AM						
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
36145	Main Building	Classroom			7/23/2008		223		\$0.00	
Medium	Work In Progress	Room 207		7/23/2008 11:09:15 AM						
Lozoya, Manny		**URGENT** THIRD REQUEST FOR NEW KEY FOR ROOM 207 OLD KEY BENT AND BROKE								
Elena Palacios										
36315					7/29/2008		217		\$0.00	
High	Work In Progress			7/29/2008 10:57:48 AM						
Lozoya, Manny		***URGENT*** NEED KEY LOCKS THAT WERE LOST AND ORDERED ACCORDING TO RAFA AND MANNY BACK IN SEPTEMBER OF 07, LOCKS AND KEYS STILL HAVE NOT BEEN REPLACED IN THEIR ENTIRETY								
Elena Palacios										
36316		Computer Lab			7/29/2008		217		\$0.00	
High	Work In Progress	ROOM 207		7/29/2008 11:01:56 AM						
Lozoya, Manny		NEED NEW KEY MADE FOR ROOM 207								
Elena Palacios										
36767	Main Building	Classroom			8/7/2008		208		\$0.00	
Medium	Work In Progress	ROOM 201		8/7/2008 12:10:58 PM						
Lozoya, Manny		NEEDS KEYS TO LOCK CABINETS								
Elena Palacios										
37050					8/14/2008		201		\$0.00	
Medium	Work In Progress			8/14/2008 8:28:32 AM						
Ontiveros, Joe		need to replace shower columns in boys and girls reast rooms. Thxs								
Marti Muela										
37191					8/19/2008		196		\$0.00	
Medium	Work In Progress			8/19/2008 10:54:48 AM						
Lozoya, Manny		eight security window rod irons can not be locked in the 300 & 400 hallway. very easy to break into. those rooms are to the back and can not be seen from the street.								
Robert Gonzalez										
37404	Main Building	Classroom			8/26/2008		189		\$0.00	
Medium	Work In Progress	ROOM 406		8/26/2008 3:43:07 PM						
Lozoya, Manny		NEED CABINET LOCKS								
Elena Palacios										

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral MS									
37822	Main Building	Portables			9/5/2008		179		\$0.00
High	Work In Progress	P-9		9/5/2008 9:09:01 AM					
Lozoya, Manny	Social Worker Berenice Holguin needs her file cabinet locked for very confidential paperwork. Her lock was taken by Manny but never replaced.								
Elena Palacios									
37823	Main Building	Classroom			9/5/2008		179		\$0.00
High	Work In Progress	Room 206		9/5/2008 9:10:55 AM					
Lozoya, Manny	Counselor James Wolf needs file cabinet lock back, to secure confidential paperwork. Was taken last year by Manny and not yet replaced.								
Elena Palacios									
37824	Main Building	Classroom			9/5/2008		179		\$0.00
High	Work In Progress	Room 404		9/5/2008 9:14:56 AM					
Lozoya, Manny	NEED CABINETS KEYED FOR MR. MORALES IN ROOM 406								
Elena Palacios									
38127		Gym			9/16/2008		168		\$0.00
Medium	Work In Progress			9/16/2008 10:22:53 AM					
Ronquillo, Ruben	Asp PM 37575 FXT-CHM -017 Need plexiglass cover. FXT-CHM-018 Need plexiglass cover.								
Eric Medina									
38437					9/25/2008		159		\$0.00
Medium	Work In Progress			9/25/2008 3:39:35 PM					
Sotelo, Enrique	need light covers plastic								
Eric Medina									
38779					10/5/2008	10/26/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:03 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
39496	Main Building	Classroom			10/27/2008		127		\$0.00
Medium	Work In Progress	ROOM 203		10/27/2008 8:38:48 AM					
Lozoya, Manny	NEED EXTRA KEY MADE FOR ROOM 203 KEY 78 THANKS								
Elena Palacios									
39611					10/30/2008		124		\$0.00
Medium	Work In Progress			10/30/2008 12:30:11					
Lozoya, Manny	room 312 teacher complains door knob is loose								
Eric Medina									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
39938	Main Building	Gym			11/7/2008		116		\$0.00
Medium	Work In Progress				11/7/2008 9:41:00 AM				
Lozoya, Manny		Need to replace panic bar in boys locker room due to vandalism.							
Manny Lozoya									
40703					12/9/2008		84		\$0.00
Medium	Work In Progress				12/9/2008 1:44:35 PM				
Ontiveros, Joe		need to order new water heater for nurses portable # 5							
Eric Medina									
40741					12/10/2008		83		\$0.00
Medium	Work In Progress				12/10/2008 11:12:20				
Medina, Eric		About 8 of the exhaust fans in the restrooms or the custodial closets have not been working for a while.				12/16 - Asp Mike route to Eric.			
Robert Gonzalez									
40744					12/10/2008		83		\$0.00
Medium	Work In Progress				12/10/2008 11:20:18				
Medina, Eric		The floors in the boys and girls locker rooms need painting . They look very bad. Mike painted them about five years ago.							
Robert Gonzalez									
40837		Cafeteria			12/12/2008		81		\$0.00
Medium	Work In Progress				12/12/2008 3:24:23 PM				
Orozco, Danny		DRYER NOT DRYING PROPERLY - TAKES AT LEAST 3 TO 4 CYCLES TO DRY							
		SANDRA DIAZ - SNP MANAGER 824-4376							
Alma Terrell									
41070					1/4/2009	1/25/2009	58		\$0.00
Medium	Work In Progress				1/4/2009 12:18:49 AM				
Orozco, Danny		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
41253	Main Building	Classroom			1/7/2009		55		\$0.00
Medium	Work In Progress	Room 303, 406,			1/7/2009 3:55:06 PM				
Lozoya, Manny		***URGENT THIRD REQUEST*** NEED KEYS FOR THEIR FILING CABINET HAVE VERY PRIVATE SPED INFO THAT NEEDS TO BE LOCKED UP							
Elena Palacios									
41651		Classroom			1/20/2009		42		\$0.00
Medium	Work In Progress	ROOM 203			1/20/2009 2:34:58 PM				
Lozoya, Manny		DRAWERS IN HOME EC ROOM DO NOT OPEN NEED TO HAVE THE KEY LOCKS REMOVED							
Elena Palacios									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
41653					1/20/2009		42		\$0.00
Medium	Work In Progress			1/20/2009 2:56:17 PM					
Lozoya, Manny		manny need to fix loose door handle in portable 14 and straightend the door for room 312							
Eric Medina									
41877					1/27/2009		35		\$0.00
Medium	Work In Progress	OUTSIDE AND		1/27/2009 9:57:18 AM					
Orozco, Danny		NEED FOR DIMAR TO COME AND CK LEAKING SPRINKLER HEAD.							
Eric Medina									
41954					1/28/2009		34		\$0.00
Medium	Work In Progress			1/28/2009 3:14:33 PM					
Estrada, Jesus		NEED CARPET REPLACED IN BAND ROOM.				1/28/09 - FAXED TO MICHAEL @ AZTEC			
Jesus Estrada									
41979					1/29/2009		33		\$0.00
Medium	Work In Progress			1/29/2009 8:16:06 AM					
Gonzalez, Salvador		new tables for outside canopies need to be installed and assemble.eric will support.							
Michael Munoz									
41980					1/29/2009		33		\$0.00
Medium	Work In Progress			1/29/2009 8:17:34 AM					
Medina, Eric		please order and replace all window screens that are damaged. thxs							
Michael Munoz									
42032					1/30/2009		32		\$0.00
Medium	Work In Progress			1/30/2009 3:03:37 PM					
Ontiveros, Joe		joe i need you to look at the toilet in the womens faculty rr							
Eric Medina									
42073					2/1/2009	2/7/2009	30		\$0.00
Medium	Work In Progress			2/1/2009 12:24:34 AM					
Medina, Eric		Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
42142					2/2/2009		29		\$0.00
Medium	Work In Progress			2/2/2009 9:50:09 AM					
Lozoya, Manny		I NEED TWO XX2 KEYS ONE FOR CARMEN THE CUSTODIAN THAT CLEANS THAT ROOM 405A AND ONE FOR MYSELF. I LOAN MINE TO THE COMPUTOR TECH THATS IN THAT ROOM							
Robert Gonzalez									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
42320		Cafeteria			2/6/2009		25		\$0.00
Medium	Work In Progress			2/6/2009 11:05:24 AM					
Orozco, Danny	FIX OR INSTALL BELL (DELIVERY DOOR)								
Alma Terrell	DEMETRIOS P. GIOVAS - SNP DIRECTOR		882-6771						
42486					2/11/2009		20		\$0.00
Medium	Work In Progress			2/11/2009 2:18:56 PM					
Solis, Lorenzo	secondary boiler system needs new gas valve								
Eric Medina									
42703	Main Building	Portables			2/19/2009		12		\$0.00
Medium	Work In Progress	PORTABLE 14		2/19/2009 11:19:25 AM					
Lozoya, Manny	REKEY THE BATHROOM DOOR WE CAN THEN USE THE ROOM FOR STORAGE.								
Elena Palacios									
42992					2/26/2009		5		\$0.00
Medium	Work In Progress			2/26/2009 3:17:49 PM					
Jacquez, Ricardo	need to upgrade filtration system, too small, and also need to up size pumps								
Eric Medina									
42994	Main Building	Restroom (Girls)			2/26/2009		5		\$0.00
Medium	Work In Progress			2/26/2009 3:18:47 PM					
Ontiveros, Joe	need to replace flush valve in three toilets								
Eric Medina									
43121					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:02 AM					
Orozco, Danny	Yearly - Chaparral MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43136					3/1/2009	4/1/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:07 AM					
Medina, Eric	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
43137					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:07 AM					
Medina, Eric	Yearly - Chaparral MS A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43138					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:07 AM					
Medina, Eric	Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Chaparral MS							
43139					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:08 AM				
Medina, Eric	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43140					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:08 AM				
Medina, Eric	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
Count: 43 Work Orders		Avg. Age of WO's 91		Total for Chaparral MS				0	\$0.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
36027					7/17/2008		229		\$0.00
Medium	Work In Progress	MORGAN BLDG.		7/17/2008 11:08:09 AM					
Castillo, Carlos		NEED POWER TO RUN HEATING/COOLING & OUTLETS IN MORGAN BLDG.							
David Acosta									
36451		Classroom			8/1/2008		214		\$0.00
Medium	Work In Progress	14,15		8/1/2008 7:22:52 AM					
Castillo, Carlos		EMER. LIGHT DO NOT TURN ON IN BOTH ROOMS WHEN TURNING OFF BREAKER SWITCH FOR TESTING.							
David Acosta									
36452		Library			8/1/2008		214		\$0.00
Medium	Work In Progress			8/1/2008 7:26:27 AM					
Castillo, Carlos		EMER LIGHT WON'T STAY ON VERY LONG WHEN DOING ANNUAL TEST.							
David Acosta									
37699		Classroom			9/2/2008		182		\$0.00
Medium	Work In Progress	1,2		9/2/2008 2:08:10 PM					
Castillo, Carlos		NEED MORE EMERG. EXIT SIGNS. (ASK BY STATE FIREMARSHAL TO REQUEST).							
David Acosta									
38592		Hallway/Corridor			10/1/2008		153		\$0.00
Medium	Work In Progress	2ND BLDG.		10/1/2008 11:52:55 AM					
Castillo, Carlos		NEED TO INSTALL RECEPTACLE FOR CANDY MACH. WALL AS NO RECEPTACLE							
David Acosta									
39333		Portables			10/21/2008		133		\$0.00
Medium	Work In Progress	16		10/21/2008 11:07:07					
Castillo, Carlos		NEED EXIT SIGN AND EMER. LIGHT FOR LAST PORTABLE (ROOM 16).							
David Acosta									
40669		Portables			12/8/2008		85		\$0.00
Medium	Work In Progress	room 1		12/8/2008 11:46:00 AM					
Estrada, Jesus		ATT: MIKE MUNOZ-ROOM 1 (PORTABLE) NEEDS TO REPLACE SOME FLOOR TILE BUT MAY NEED TO REPLACE A SECTION OF FLOOR BY DOOR ENTRANCE.				1/12/09 - PENDING AS PER CHUY			
David Acosta									
41209					1/6/2009		56		\$0.00
Medium	Work In Progress			1/6/2009 3:43:53 PM					
Gonzalez, Salvador		please install ballards on the sidewalk from the 3rd bldg to the barrack.please see mike.thxs							
Michael Munoz									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Desert Pride								
42224		Portables			2/4/2009		27		\$0.00	
Medium	Work In Progress	6		2/4/2009 11:22:54 AM						
Castillo, Carlos		BALLAST TO LIGHT FIXTURE NEEDS TO BE REPLACES								
David Acosta										
42847		Parking Lot			2/24/2009		7		\$0.00	
Medium	Work In Progress			2/24/2009 2:01:57 PM						
Munoz, Michael		NEED CONCRETE RAMP ASSESSABLE TO OFFICE FOR HANDICAP AND TRUNK DELIVERY								
David Acosta										
43095					3/1/2009		2		\$0.00	
Medium	Work In Progress			3/1/2009 12:22:52 AM						
Aguilar, Patricio		Yearly - Deset Pride HS A10(Heat Pumps)(Yearly) - Refer to PM schedule details.								
Margret Villalobos										
43096					3/1/2009	3/9/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:22:53 AM						
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos										
43097					3/1/2009	3/9/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:22:53 AM						
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos										
43098					3/1/2009	3/7/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:22:53 AM						
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos										
43124					3/1/2009		2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:03 AM						
Orozco, Danny		Yearly - Desert Pride HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos										
43228		Restroom (Boys)			3/2/2009		1		\$0.00	
Medium	Work In Progress	2ND BLDG, 1&2,		3/2/2009 12:13:26 PM						
Lara, Ralph		PRINCIPLE REQUEST TO HAVE LOCK ON RESTROOM DOORS.								
David Acosta										

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Desert Pride							
43229					3/2/2009		1		\$0.00
Medium	Work In Progress	2ND BLDG			3/2/2009 12:19:32 PM				
Lara, Ralph	NURSE NEEDS KEYS FOR FILING CABINET & MEDICAL SUPPLIES CABINET.								
David Acosta									
43230	Storage A				3/2/2009		1		\$0.00
Medium	Work In Progress				3/2/2009 12:27:02 PM				
Ontiveros, Guadalupe	NEED A COUPLE OF LOADS OF DIRT TO FILL IN AROUND LUNCH AREA.								
David Acosta									
Count: 18 Work Orders		Avg. Age of WO's 73			Total for Desert Pride			0	\$0.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Desert Trail Intermediate								
35698					7/6/2008	8/6/2008	240		\$0.00	
Medium	Work In Progress				7/6/2008 12:20:07 AM					
Villalobos, David		Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
38213					9/18/2008		166		\$0.00	
Medium	Work In Progress				9/18/2008 12:09:20 PM					
Gonzalez, Salvador		Please weld extra metal to the top of the metal scraper to add on a little more weight to it. Thank You....								
Johnny Acuna										
38277	Main Building	Computer Lab			9/22/2008		162		\$0.00	
Medium	Work In Progress				9/22/2008 8:00:19 AM					
Sotelo, Enrique		Provide electrical supply to 5 ton unit, cooling only.								
Lorenzo Solis										
38780					10/5/2008	10/26/2008	149		\$0.00	
Medium	Work In Progress				10/5/2008 12:24:03 AM					
Orozco, Danny		Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos										
39012					10/7/2008		147		\$0.00	
Medium	Work In Progress				10/7/2008 3:30:52 PM					
Lozoya, Manny		Need a replacement Door and Door Frame for Portable #413 inside Restroom Door.								
Johnny Acuna										
39014					10/7/2008		147		\$0.00	
Medium	Work In Progress				10/7/2008 3:33:24 PM					
Lozoya, Manny		Portable #410: Need a Replacement Metal Door.								
Johnny Acuna										
39677					10/31/2008		123		\$0.00	
Medium	Work In Progress				10/31/2008 4:09:15 PM					
Gonzalez, Salvador		Need to re-weld stainless sheetmetal sheet together that came apart in the kitchen sink area.								
Johnny Acuna										
39759		Athletic Field			11/3/2008		120		\$0.00	
Medium	Work In Progress				11/3/2008 7:38:23 AM					
Acuna, Johnny		Basketball Courts in the outdoor playground are badly cracked and separating.				Asp Mike, route back to Johnny, to order joint and filler thru Maint. Warehouse. 11/5/08				
Johnny Acuna										

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
39760					11/3/2008		120		\$0.00
Medium	Work In Progress				11/3/2008 7:40:41 AM				
Ronquillo, Ruben	Window frames in the side of the main doors in the NW hall needs to be replaced or repaired. There is too much corrosion.								
Johnny Acuna									
41071					1/4/2009	1/25/2009	58		\$0.00
Medium	Work In Progress				1/4/2009 12:18:50 AM				
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
41192					1/6/2009		56		\$0.00
Medium	Work In Progress				1/6/2009 12:08:50 PM				
Lozoya, Manny	Room #117: need assistance in adjusting door frame and door.								
Johnny Acuna									
41193					1/6/2009		56		\$0.00
Medium	Work In Progress				1/6/2009 12:10:21 PM				
Lozoya, Manny	Portable #412: Door knob is very loose and teacher has problems opening door.								
Johnny Acuna									
41199	Main Building	Classroom			1/6/2009		56		\$0.00
Medium	Work In Progress				1/6/2009 2:18:47 PM				
Lozoya, Manny	Urgente. Cuarto 410 la chapa se quebro, y no se puede cerrar. gracias								
Marisela Torres									
41414					1/12/2009		50		\$0.00
Medium	Work In Progress				1/12/2009 4:08:44 PM				
Lozoya, Manny	Portable #403: (Mrs. Rios): Need to install a new door knob to Portable #403. Has been repaired several times. Door knob gets stuck and the teacher and student's sometimes cannot come out of the classroom. It's the only door to their classroom. (Safety Issue in case of an Emergency).								
Johnny Acuna									
41494					1/14/2009		48		\$0.00
Medium	Work In Progress				1/14/2009 1:33:10 PM				
Ontiveros, Guadalupe	(Need Assistance): Need tractor to dig up 6'ft. in all directions around 2 sets of swings in the playground area and fill in with playground sand. Thank You.....								
Johnny Acuna									
41496					1/14/2009		48		\$0.00
Medium	Work In Progress				1/14/2009 1:45:26 PM				
Lozoya, Manny	Need an oval lock for filing cabinet to the nurse's office. (Student Records).								
Johnny Acuna									
3/3/2009 12:02:20 PM									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
41594		Cafeteria			1/16/2009		46		\$0.00
Medium	Work In Progress			1/16/2009 11:58:05 AM					
Orozco, Danny	Plastic Handle fell off to Sprayer in Dishwashing Area								
Alma Terrell	Pat Cisneros - SNP Manager 824-3822								
41790	Main Building	Custodial			1/23/2009		39		\$0.00
Medium	Work In Progress			1/23/2009 11:10:22 AM					
Carbajal, Jimmy	Podria prestarme el extractor de 2 galones?. Gracias.								
Marisela Torres									
41985					1/29/2009		33		\$0.00
Medium	Work In Progress			1/29/2009 10:16:23 AM					
Gonzalez, Salvador	Please re-weld stainless steel sink that came apart in the left corner of the sink tub. (kitchen) (South sink)								
Johnny Acuna									
41986					1/29/2009		33		\$0.00
Medium	Work In Progress			1/29/2009 10:21:43 AM					
Gonzalez, Salvador	Please re-weld hood vent cover to exhaust fans inside the kitchen. (Hood System)								
Johnny Acuna									
42029	Main Building	Hallway/Corridor			1/30/2009		32		\$0.00
Medium	Work In Progress			1/30/2009 1:01:18 PM					
Lozoya, Manny	Puerta principal (pasillo kinder) esta caida,								
Marisela Torres									
42089					2/1/2009	2/9/2009	30		\$0.00
Medium	Work In Progress			2/1/2009 12:24:40 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42144					2/2/2009		29		\$0.00
Medium	Work In Progress			2/2/2009 12:12:43 PM					
Gonzales, Angel	Please repair Echo Blower. (Desert Trail) Got sent over to Auto shop by Memo on Payday. (1/30/09)								
Johnny Acuna									
42555	Main Building	Portables			2/13/2009		18		\$0.00
Medium	Work In Progress			2/13/2009 11:25:12 AM					
Ontiveros, Joe	Broken water line in portable #413								
Marisela Torres									
42594					2/17/2009		14		\$0.00
Medium	Work In Progress			2/17/2009 8:07:41 AM					
Lozoya, Manny	Need a key made for storage cabinet lock in room #204 (Mrs. Stewart). (Will send out core by Mail to Locksmith)								
Johnny Acuna									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
42620	Main Building	Custodial			2/17/2009		14		\$0.00
Medium	Work In Progress				2/17/2009 12:43:48 PM				
Carbajal, Jimmy		Aspiradora #Lo6000000048 se quebro de una rueda.							
Marisela Torres									
42824	Main Building	Custodial			2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 7:29:02 AM				
Carbajal, Jimmy		wet n dry (esprite) #1382814 no levanta el agua.							
Marisela Torres									
42825	Main Building	Custodial			2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 7:31:44 AM				
Carbajal, Jimmy		agua clean (extractor) #1291647 tiene la tapadera quebrada.							
Marisela Torres									
42955					2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 4:02:18 PM				
Ronquillo, Ruben		Need Mastercool A/c Covers: (3): 48" x 48" (3): 42" (W) x 32" (Long) (2): 42" (W) x 27" (Long)							
Johnny Acuna									
43108					3/1/2009		2		\$0.00
Medium	Work In Progress				3/1/2009 12:22:57 AM				
Orozco, Danny		Yearly - Desert Trail ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
43157					3/1/2009		2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:14 AM				
Acuna, Johnny		Yearly - Desert Trail ES A10 (Heat Pump)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
43158					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:15 AM				
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
43159					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:15 AM				
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Desert Trail Intermediate							
43160					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:15 AM				
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43234					3/2/2009		1		\$0.00
Medium	Work In Progress				3/2/2009 2:29:47 PM				
Lozoya, Manny	Please change out core to confrence room doorknob in the office area. (Needs to be restricted due to the Testing Materials put away in that room).								
Johnny Acuna									
Count: 35 Work Orders			Avg. Age of WO's	59	Total for Desert Trail Intermediate			0	\$0.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert View ES

35699					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress				7/6/2008 12:20:07 AM				
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36939	Main Building				8/12/2008		203		\$0.00
Medium	Work In Progress				8/12/2008 8:37:50 AM				
Ortiz, Ruben	Tested exit signs (4) are not working 2 in Gym and Cafeteria asp PM 36526.		Need to order thru material request and complete wo once they are replaced.						
Ruben Ortiz									
38108					9/15/2008		169		\$0.00
Medium	Work In Progress				9/15/2008 7:13:21 PM				
Villalobos, David	Requesting for plumber to check if two water faucets can be installed for cleaning purposes								
Ruben Ortiz									
39053					10/8/2008		146		\$0.00
Medium	Work In Progress				10/8/2008 5:07:00 PM				
Villalobos, David	To Mike Munoz I was asked by Mr. Carrasco that he needs hot water and more water pressure for the shower in the Special Ed room. There is a child that needs to be bathed often and the water is too cold. He asked for an urgent work order. Mr. Carrasco asked for this work order to be sent directly to you because he wants it ASAP 10/08/08. Child is being bathed in cold water. Thank you.								
Ruben Ortiz									
39404					10/22/2008		132		\$0.00
Medium	Work In Progress				10/22/2008 9:10:57 PM				
Lara, Ralph	Carlos Castillo The button for the handicap door is not working on the southside of the building exit.								
Ruben Ortiz									
40871	Cafeteria				12/15/2008		78		\$0.00
Medium	Work In Progress				12/15/2008 2:35:04 PM				
Moncayo, Fernando	AS PER DIMAR SYSTEM, RANGE HOOD SYSTEMS REPORT DATED 12/15/08, EXHAUST FAN IS NOT OPERATING. DIANA LAZARIN SNP MGR 589-2425								
Jacqueline Aguilar									
41887					1/27/2009		35		\$0.00
Medium	Work In Progress				1/27/2009 12:56:50 PM				
Lara, Ralph	please replace exterior door to rm 25. thxs								
Michael Munoz									

3/3/2009 12:02:20 PM

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
41888					1/27/2009		35		\$0.00
Medium	Work In Progress			1/27/2009 12:58:48 PM					
Ortiz, Ruben	please schedule the aerator order seed and fertilizer for the areas on campus that do no have grass in the circle. thxs								
Michael Munoz									
41921					1/28/2009		34		\$0.00
Medium	Work In Progress			1/28/2009 6:49:22 AM					
Moncayo, Fernando	Ladies in cafeteria need a lock for their file cabinet. Hinges on the walk in refrigerator are broken having trouble locking it. Thank you.								
Ruben Ortiz									
41975					1/28/2009		34		\$0.00
Medium	Work In Progress			1/28/2009 8:34:35 PM					
Carrasco, Danny	Requesting a small chainsaw to cut thick branches and a pull saw for pruning. Thank you.								
Ruben Ortiz									
42165					2/2/2009		29		\$0.00
Medium	Work In Progress			2/2/2009 9:33:14 PM					
Lara, Ralph	Need a door replaced in room 25; 2 inches from the bottom of the door is rusted through; the replacement has been request by Principal Carrasco. Thank you, Ruben								
Ruben Ortiz									
42230		Portables			2/4/2009		27		\$0.00
Medium	Work In Progress			2/4/2009 2:49:07 PM					
Gonzalez, Salvador	Need to install ramps to portable (see Mike).								
Michael Munoz									
42298					2/5/2009		26		\$0.00
Medium	Work In Progress			2/5/2009 8:59:12 PM					
Gonzalez, Salvador	Need parking poles welded back up, have been a tripping hazard. Thank you, Ruben								
Ruben Ortiz									
42420		Cafeteria			2/10/2009		21		\$0.00
Medium	Work In Progress			2/10/2009 1:40:20 PM					
Moncayo, Fernando	SLICER JUMPED SIZE WHEN SLICING, PLEASE ADJUST								
	DIANA LAZARIN -SNP MANAGER 589-2425								
Alma Terrell									
42425		Cafeteria			2/10/2009		21		\$0.00
Medium	Work In Progress			2/10/2009 1:50:57 PM					
Moncayo, Fernando	EXHAUST FAN DOES NOT TURN ON								
	DIANA LAZARIN - SNP MANGER 589-2425								
Alma Terrell									

3/3/2009 12:02:20 PM

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
42581		Portables			2/13/2009		18		\$0.00
Medium	Work In Progress			2/13/2009 3:57:16 PM					
Ortiz, Ruben		Order material to do skirting on portable.							
Michael Munoz									
42582		Portables			2/13/2009		18		\$0.00
Medium	Work In Progress			2/13/2009 3:59:12 PM					
Ontiveros, Guadalupe		Reconnect ramps to portable, once skirting is complete.							
Michael Munoz									
42588					2/13/2009		18		\$0.00
Medium	Work In Progress			2/13/2009 8:18:55 PM					
Villalobos, David		Need wall faucets outside replaced due to leaking. Thank you.							
Ruben Ortiz									
42615		Cafeteria			2/17/2009		14		\$0.00
Medium	Work In Progress			2/17/2009 11:19:55 AM					
Moncayo, Fernando		OUT SIDE LIGHT TO REACH-IN FREEZER KEEPS ON BLINKING							
		DIANA LAZARIN - SNP MANAGER 589-2425							
Alma Terrell									
42616		Cafeteria			2/17/2009		14		\$0.00
Medium	Work In Progress			2/17/2009 11:21:14 AM					
Moncayo, Fernando		WHEELS TO STAINLESS STEEL WORK TABLE NEEDS TO BE REPLACED (WHEELS ARE ROTTED OUT)							
		DIANA LAZARIN - SNP MANAGER 589-2425							
Alma Terrell									
43026		Custodial			2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 10:09:38 AM					
Carbajal, Jimmy		This work order is for a vaccum cleaner needs to be checked it doesnt clean very good on the carpets .I DONT NEED A LOANER.THANK YOU IN ADVANCED.							
Hector Rivera									
43076					2/28/2009		3		\$0.00
Medium	Work In Progress			2/28/2009 12:19:57 AM					
Ortiz, Ruben		Monthly - Desert View ES A-16 Fan Exhaust (Semi) - Refer to PM schedule details.							
Margret Villalobos									
43109					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:58 AM					
Orozco, Danny		Yearly - Desert View ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Desert View ES								
43210					3/1/2009		2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:32 AM						
Ortiz, Ruben	Yearly - Desert View ES A-10 HP Rooftop Yearly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43211					3/1/2009	3/22/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:32 AM						
Ortiz, Ruben	Monthly - Desert View ES C-12 Chem. Feeder (Semi) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43212					3/1/2009	3/9/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:33 AM						
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43213					3/1/2009	3/7/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:33 AM						
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43214					3/1/2009	3/9/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:33 AM						
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43233		Portables			3/2/2009		1		\$0.00	
Medium	Work In Progress			3/2/2009 1:31:11 PM						
Ortiz, Ruben	PLEASE INSTALL ANCHOR SUPPORTS TO NEW PORTABLE.									
<u>Michael Munoz</u>										
Count: 29 Work Orders		Avg. Age of WO's 46		Total for Desert View ES			0	\$0.00		

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
35700					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:07 AM					
Villalobos, David	Yearly - GAC Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36280					7/28/2008		218		\$0.00
Medium	Work In Progress	Back bottom road		7/28/2008 12:11:48 PM					
Ontiveros, Guadalupe	need to apply dirt and crusherfine in back road due to running water after haevy rain.								
Juan Ambriz									
36334		Parking Lot			7/29/2008		217		\$0.00
Medium	Work In Progress	bottom dirt		7/29/2008 3:47:57 PM					
Ontiveros, Guadalupe	Need to apply more crusherfine in bottom dirt parking lot accumulating water after rain								
Juan Ambriz									
36949		Office			8/12/2008		203		\$0.00
Medium	Work In Progress	A-WING		8/12/2008 10:35:44 AM					
Ambriz, Juan	IF IT WOULD BE POSSIBLE TO HAVE THE AIR VENTS IN JESUS REYE'S OFFICE ADJUSTED. NOT ENOUGH AIR COMES THROUGH.								
Mary Garcia									
37912		Parking Lot			9/8/2008		176		\$0.00
Medium	Work In Progress	bottom dirt		9/8/2008 3:39:17 PM					
Ontiveros, Guadalupe	Need to level bottom parking lot with crusher fine to avoid accumulated water after rains								
Juan Ambriz									
37939					9/9/2008		175		\$0.00
Medium	Work In Progress	Back dirt road		9/9/2008 8:25:56 AM					
Ontiveros, Guadalupe	need to add dirt to back dirt road due to running water after rains. If possible add crusher fine.								
Juan Ambriz									
37978		Office			9/9/2008		175		\$0.00
Medium	Work In Progress	A-WING		9/9/2008 4:42:49 PM					
Castillo, Carlos	AS PER ELISA-NEED AN ELECTRICAL OUTLET TO BE INSTALLED IN THE SUPT. CONFERENCE CLOSET.								
Mary Garcia									
38646					10/2/2008		152		\$0.00
Medium	Work In Progress			10/2/2008 2:30:47 PM					
Castillo, Carlos	Asp PM 37606, still waiting on Emerg. Light for Board Rm and Sever Rm not working.								
Juan Ambriz									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
38781					10/5/2008	10/26/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:03 AM					
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
39366		Office			10/22/2008		132		\$0.00
Medium	Work In Progress	C-WING		10/22/2008 9:54:03 AM					
Ambriz, Juan		AS PER ALFREDO-GO AHEAD AND SEAL OFF THE WALL WHERE THE AIR UNIT WAS IN OFELIA'S OFFICE.				APPROVED BY ALFREDO			
Mary Garcia									
40223		Office			11/19/2008		104		\$0.00
Medium	Work In Progress	B-WING		11/19/2008 2:24:32 PM					
Villalobos, David		AS PER MR. CHAVEZ-NEED TO HAVE THE PLUMBER COME IN AND CHECK OUT THE SINK BEHIND RECEPTIONIST AREA IN B WING, OVER WITH VANESSA. THERE IS A REAL BAD SEWER SMELL.				JUAN HAS ALREADY TAKEN A LOOK AT THIS AND SMELL STILL CONTINUES.			
Mary Garcia									
40674	RTC	Parking Lot			12/8/2008		32	1	\$25.00
Medium	Work In Progress	RTC ACROSS		12/8/2008 2:30:07 PM		1/9/2009			
Soria, Mike		AS PER GLORIA SAENZ-NEED TO HAVE THE DIRT REMOVED FROM THE PARKING LOT.				Completed asp report 1/9/09			
Mary Garcia									
40994		Cafeteria			12/18/2008		75		\$0.00
Medium	Work In Progress			12/18/2008 3:50:21 PM					
Ambriz, Jose		AS PER OUR CONVERSATION (MIKE MUNOZ) ON 12/18/08 PLEASE ORDER BUTTERFLY VENTS FOR DINING ROOM AND KITCHEN				1/6/09 - Route to Jose asp Mike.			
		SNP 882-6772							
Alma Terrell									
41072					1/4/2009	1/25/2009	58		\$0.00
Medium	Work In Progress			1/4/2009 12:18:50 AM					
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
41203		Hallway/Corridor			1/6/2009		56		\$0.00
Medium	Work In Progress	B-WING		1/6/2009 2:57:15 PM					
Estrada, Jesus		AS PER MR. SUTTMILLER-THE FLOOR TILE ENTERING B-WING NEEDS TO BE REPLACED OR REPAIRED, IT IS LIFTING.							
Mary Garcia									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
41521	RTC	Portables			1/15/2009		47		\$0.00
Medium	Work In Progress	RTC-ACROSS			1/15/2009 9:40:00 AM				
Ambriz, Juan		AS PER MS. SAENZ-THEY HAVE A BROKEN WINDOW THAT DOES NOT LOCK.				1/26 - Route to Juan asp Ruben			
Mary Garcia									
41669		Office			1/20/2009		42		\$0.00
Medium	Work In Progress	C-WING			1/20/2009 3:50:11 PM				
Ambriz, Juan		AS PER DAVID AVILA-LIGHT FIXTURES NEED TO BE CHECKED IN ANN STEINHOFF'S OFFICE. LIGHTS KEEP ON FLICKERING.							
Mary Garcia									
41722					1/22/2009		40		\$0.00
Medium	Work In Progress				1/22/2009 8:46:30 AM				
Castillo, Carlos		IT Room - Remove unused conduit and electrical outlet next to new chiller. Check with Calixo or contractor on specifics.							
Alfredo Holguin									
41865					1/26/2009		36		\$0.00
Medium	Work In Progress	OUTSIDE AND			1/26/2009 4:09:18 PM				
Orozco, Danny		AS PER JUAN AMBRIZ-NEED FOR DIMAR TO COME IN AN RECAP A PIPE THAT IS LEAKING WATER. (TO ASK FOR JUAN WHEN DIMAR COMES IN)				DAVID VILLALOBOS ALREADY LOOKING INTO THIS SITUATION AND SUGGESTED FOR JUAN TO PUT IN A WORK ORDER FOR DIMAR TO TAKE CARE OF THIS.			
Mary Garcia									
41937	RTC	Portables			1/28/2009		34		\$0.00
Medium	Work In Progress	RTC ACROSS			1/28/2009 10:42:26 AM				
Ambriz, Juan		AS PER GLORIA SAENZ-KEYS UNABLE TO OPEN CLASSROOM-MS. MORALES, MAYBE DUE TO DUST.							
Mary Garcia									
42414	Pre-K	Cafeteria			2/10/2009		21		\$0.00
Medium	Work In Progress	PRE-K			2/10/2009 11:21:26 AM				
Ambriz, Juan		AS PER MS. BERRY- NEED HELP W/ 2 WALL HANINGS IN THE CAFETERIA.							
Mary Garcia									
42453	RTC	Portables			2/10/2009		21		\$0.00
Medium	Work In Progress	RTC ACROSS			2/10/2009 3:53:38 PM				
Ambriz, Juan		AS PER GLORIA SAENZ-NEED TO HAVE THE RAMP BOARDS REPLACED. (THERE IN REAL BAD SHAPE DUE TO RAIN)				2/29/09 - Have you ck'd w/Warehouse on the status of supplies? - mkv			
Mary Garcia									
42466		Computer Lab			2/11/2009		20		\$0.00
Medium	Work In Progress				2/11/2009 8:01:44 AM				
Ambriz, Jose		Heating unit in Computer Lab not working.							
Juan Ambriz									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
42522		Cafeteria			2/12/2009		19		\$0.00
Medium	Work In Progress			2/12/2009 11:44:29 AM					
Moncayo, Fernando	SPRAYER HANDLE TO SPRAYER KEEPS ON GETTING STUCK, ALSO THE SPRAYER HOSE NEEDS TO BE REPLACED (HOSE LEAKS ALOT)								
	GESSICA BLAZQUEZ - SNP MANAGER - 882-6784								
Alma Terrell									
42611					2/17/2009		14		\$0.00
High	Work In Progress			2/17/2009 10:20:06 AM					
Castillo, Carlos	tech room project is coming up for inspection.as per alfredo, could you go remove un-used conduit from tech,boiler,electrical room.contact person on site is pablo rojo. thanks								
Michael Munoz									
42625		Parking Lot			2/17/2009		14		\$0.00
Medium	Work In Progress	bottom dirt		2/17/2009 2:13:55 PM					
Ontiveros, Guadalupe	Need to level and add crusher fine both west and east ends to add more parking spaces.								
Juan Ambriz									
42659		Office			2/18/2009		13		\$0.00
Medium	Work In Progress	B-WING		2/18/2009 9:44:47 AM					
Ambriz, Juan	AS PER ANNE-NEEDS A DESK DRAWER TO BE FIXED, KEEPS OPEINING AND DOES NOT CLOSE.								
Mary Garcia									
42739		Parking Lot			2/20/2009		11		\$0.00
Medium	Work In Progress			2/20/2009 9:01:30 AM					
Villalobos, David	repair needed for domestic backflow preventer								
David Villalobos									
42748	Pre-K	Classroom			2/20/2009		11		\$0.00
Medium	Work In Progress	Room 201		2/20/2009 2:46:32 PM					
Ambriz, Juan	Need to replace toilet floater not working properly								
Juan Ambriz									
42797		Restroom (Girls)			2/23/2009		8		\$0.00
Medium	Work In Progress	A-Wing handicap		2/23/2009 12:45:43 PM					
Ambriz, Juan	Need to repair exhaust fan in restroom								
Juan Ambriz									
42864					2/24/2009		7		\$0.00
Medium	Work In Progress			2/24/2009 3:47:42 PM					
Carrasco, Danny	Danny need to conduct inventory of all Bldg Mechanic tools and equipment. Ask Ruben for present inventory list to match up.					Previous wo 23745			
Michael Munoz									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
43031		Office			2/27/2009		4		\$0.00
Medium	Work In Progress	A-WING		2/27/2009 10:29:17 AM					
Ambriz, Juan	AS PER CALIXTO-NEED MAINTENANCE (JUAN) TO INSTALL BASE BOARDS AROUND THE AREA WHERE FURNITURE WAS REMOVED, DUE TO THE REMODELING OF THERE OFFICE.		2/29/09 - Juan have you ck'd w/warehouse for staus? - mkv						
Mary Garcia									
43054		Office			2/27/2009		4		\$0.00
Medium	Work In Progress	C-WING		2/27/2009 3:20:45 PM					
Ambriz, Juan	AS PER LUCIA-NEED TO HAVE HER LIGHTS REPLACED, BECAUSE THEY ARE FLICKERING								
Mary Garcia									
43056		Office			2/27/2009		4		\$0.00
Medium	Work In Progress	C-WING		2/27/2009 3:22:42 PM					
Ambriz, Juan	AS PER LUCIA-NEED TO HAVE DESK LIGHTS ON, BUT ONLY IN HER AREA, AND NOT ALL THE WAY AROUND HER COUNTER.								
Mary Garcia									
43126					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:03 AM					
Orozco, Danny	Yearly - GAC Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43172					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:19 AM					
Ambriz, Juan	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43173					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:20 AM					
Ambriz, Juan	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
43174					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:20 AM					
Ambriz, Juan	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43175					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:20 AM					
Ambriz, Juan	Yearly - GAC A-10 Heat Pump Cooling Only Yearly - Refer to PM schedule details.								
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
43251		Electrical Room			3/3/2009		0		\$0.00
Medium	Work In Progress				3/3/2009 8:05:13 AM				
Castillo, Carlos		Checked main electrical service after the weekend's outage.							
Carlos Castillo									
Count: 40 Work Orders		Avg. Age of WO's 64		Total for GAC				1	\$25.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
35701					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress				7/6/2008 12:20:08 AM				
Villalobos, David	Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35876	Main Building	Office			7/11/2008		235		\$0.00
Medium	Work In Progress				7/11/2008 2:28:45 PM				
Carrasco, Danny	NEED NEW BLINDS FOR PRINCIPAL CHAMBERS OFFICE								
		1. 40" X 5'							
		2. 7' X 5'							
<u>Mario Apodaca</u>									
35993	Boys Gym	Office			7/16/2008		230		\$0.00
Medium	Work In Progress				7/16/2008 2:28:31 PM				
Ambriz, Jose	Requested by Coach Lawrence Rm. 401 Office in Boy's Gym-Room 401 does not have any air conditioning, would like to have a unit installed this summer of 2008, to review videos and to watch films for Soccer.								
<u>Velia Alarcon</u>									
36000	Library	Library			7/16/2008		230		\$0.00
Medium	Work In Progress				7/16/2008 3:18:40 PM				
Ontiveros, Guadalupe	An irrigation control box has a water leak underneath the asphalt outside the southwest exit.								
<u>Albert Vallejo</u>									
36066	North Building	Classroom			7/18/2008		228		\$0.00
Medium	Work In Progress				7/18/2008 3:19:18 PM				
Ronquillo, Ruben	NEED NEW WINDOW BLINDS (35"WX56"L) FOR ROOM 207 NEED 11 EA								
<u>Mario Apodaca</u>									
36067	Old English Bldg	Classroom			7/18/2008		228		\$0.00
Medium	Work In Progress				7/18/2008 3:21:06 PM				
Ambriz, Jose	NEED A NEW HEATING CONDESER AT ROOM 141 DO TO VANDALISM								
<u>Mario Apodaca</u>									
36310	Cafeteria (1998)	Cafeteria			7/29/2008		217		\$0.00
Medium	Work In Progress				7/29/2008 8:10:33 AM				
Moncayo, Fernando	NEED A SAFETY POWER DISCONNECT TO THE GHS WALK-IN'S (BOTH) ON THE CONDENSER UNITS ON THE ROOF						11/18 - Asp Mike route to Fernie		
	MR. DEMETRIIOUS GIOVAS								
<u>Jacqueline Aguilar</u>									
36622					8/4/2008		211		\$0.00
Medium	Work In Progress	WWT			8/4/2008 4:10:54 PM				
Sanchez, Raul	Replace motor for Wastewater Treatment Plant Blowers.								
<u>Raul Sanchez</u>									

3/3/2009 12:02:21 PM

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
36878	Boys Gym				8/11/2008		204		\$0.00
Medium	Work In Progress				8/11/2008 8:35:04 AM				
Marquez, Gerardo	new shower column was installed in girls dressing room. need to install tile to complete project. see mike. thxs								
<u>Michael Munoz</u>									
36896	Boys Gym	Gym			8/11/2008		204		\$0.00
Medium	Work In Progress				8/11/2008 2:55:29 PM				
Castillo, Carlos	NEED A NEW SWITCH FOR THE E/COOLER UNIT AT THE BOYS GYM								
<u>Mario Apodaca</u>									
37049	Football Stadium	Football Field			8/14/2008		201		\$0.00
Medium	Work In Progress				8/14/2008 8:14:03 AM				
Munoz, Michael	Some of the concrete piers that support the bleachers are cracked and need to be repaired.								
<u>Albert Vallejo</u>									
37094	Cafeteria (1998)	Cafeteria			8/14/2008		201		\$0.00
Medium	Work In Progress				8/14/2008 3:40:19 PM				
Ambriz, Jose	ALL OUTSIDE DUCTS OF THE CAFE BLDG NEED TO BE RESEAL DOTO SUN AND WATER DAMAGE. ASAP								
<u>Mario Apodaca</u>									
37232	Old English Bldg	Classroom			8/20/2008		195		\$0.00
Medium	Work In Progress				8/20/2008 2:03:04 PM				
Carrasco, Danny	NEED NEW WINDOW MINI BLINDS DOTO VANDALISM (W43 1/2" X L90") NEED #4								
<u>Mario Apodaca</u>									
37233	Academic Bldg				8/20/2008		195		\$0.00
Medium	Work In Progress				8/20/2008 2:15:18 PM				
Ambriz, Jose	AT THE ACADEMIC BLDG NEED NEW E/COOLER STANDS								
<u>Mario Apodaca</u>									
37234	Cafeteria (1998)				8/20/2008		195		\$0.00
Medium	Work In Progress				8/20/2008 2:17:31 PM				
Ambriz, Jose	AT THE CAFE BLDG NEED NEED NEW E/COOLER STANDS								
<u>Mario Apodaca</u>									
37295	Agricultural	Classroom			8/21/2008		194		\$0.00
Medium	Work In Progress				8/21/2008 2:52:32 PM				
Appelzoller, Fred	need a new sink and faucet set put-in at room 569								
<u>Mario Apodaca</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
37400					8/26/2008		189		\$0.00
Medium	Work In Progress			8/26/2008 3:35:15 PM					
Castillo, Carlos	Requested by Mr. Roberson for Rm. 127 Main Building- Install on/off switch for lights in room #127. When room was divided switch was left in room #128.								
<u>Velia Alarcon</u>									
37431					8/27/2008		188		\$0.00
Medium	Work In Progress			8/27/2008 8:10:43 AM					
Gonzalez, Salvador	NEED TO CONSTRUCT SHADE AT GROUNDS DEPT. TO PROTECT IMPLEMENT.								
<u>Guadalupe Ontiveros</u>									
37442					8/27/2008		188		\$0.00
Medium	Work In Progress			8/27/2008 10:51:46 AM					
Ontiveros, Guadalupe	Requested by Coach Hite for Football Field-Sod bare areas on Football Field before first home game on September 12th.								
<u>Velia Alarcon</u>									
37996	Agricultural	Classroom			9/10/2008		174		\$0.00
Medium	Work In Progress			9/10/2008 3:10:19 PM					
Ronquillo, Ruben	need new window blinds for room 568.ea 2 (60 1/2"x45")								
<u>Mario Apodaca</u>									
38286					9/22/2008		162		\$0.00
Medium	Work In Progress			9/22/2008 10:13:18 AM					
Apodaca, Mario	Requested by Ms. Lam Rm. 104 Main Building-Holder of the glass door of the south book shelf is broken.								
<u>Velia Alarcon</u>									
38287					9/22/2008		162		\$0.00
Medium	Work In Progress			9/22/2008 10:30:07 AM					
Villalobos, David	Requested by Ms. Lam Rm. 104 Main Building-Both cold and hot water of the faucet on the south side have sulfur smell.								
<u>Velia Alarcon</u>									
38296					9/22/2008		162		\$0.00
Medium	Work In Progress			9/22/2008 11:16:00 AM					
Vallejo, Albert	Requested by Ms. Roth Rm. 213 North Building-Legs are loose on various HEAVY lab tables and need to be tightened and possibly secured. Table tops are not attached to certain tables and also pose a safety hazard and noise maker.								
<u>Velia Alarcon</u>									
38429	Academic Bldg	Classroom			9/25/2008		159		\$0.00
Medium	Work In Progress			9/25/2008 2:39:13 PM					
Carrasco, Danny	need windos blinds (46 3/4" x 62") for the academic bldg need 10								
<u>Mario Apodaca</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
38465					9/26/2008		158		\$0.00
Medium	Work In Progress			9/26/2008 12:29:32 PM					
Lozoya, Manny	Mr. Chacon, Band Director needs a gate key.								
Michael Munoz									
38497					9/29/2008		155		\$0.00
Medium	Work In Progress			9/29/2008 10:57:19 AM					
Ontiveros, Guadalupe	Requested by Julio Alcantar for Student Parking Lot- Need more electrical poles to help mark the parking spaces in the student parking lot.		2/17/09 - Asp Mike, route to Lupe. Danny C.						
Velia Alarcon									
38538					9/30/2008		154		\$0.00
Medium	Work In Progress			9/30/2008 12:26:03 AM					
Apodaca, Mario	Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
38604					10/1/2008		153		\$0.00
Medium	Work In Progress			10/1/2008 2:02:50 PM					
Ambriz, Jose	Requested by Ms. Hartmann Rm. 568 Classroom between Ag. Shop and Wood Shop-Install an extracting fan to remove fumes coming into room 568, created by Auto and Ag engines. There's currently no way for fumes to exit from classroom. Fumes giving teacher and students headaches.								
Velia Alarcon									
38744					10/5/2008		149		\$0.00
Medium	Work In Progress			10/5/2008 12:23:50 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.		10/6/08 - Emailed to Ricky Borrego						
Margret Villalobos									
38790					10/5/2008	10/26/2008	99		\$0.00
Medium	Work In Progress			10/5/2008 12:24:06 AM		1/12/2009			
Orozco, Danny	Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38893					10/5/2008	10/13/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:44 AM					
Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
38974	Academic Bldg	Classroom			10/6/2008		148		\$0.00
Medium	Work In Progress			10/6/2008 3:03:50 PM					
Ambriz, Jose	need new e/cooler unit at the academic bldg need 20 e.a								
Mario Apodaca									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
38997	Main Building				10/7/2008		147		\$0.00
Medium	Work In Progress				10/7/2008 11:33:11 AM				
Apodaca, Mario	Requested by Velia for Front Office in Main Building- Since air quality and mold are a concern today. There are several spots in the Front Office that have leaked when it rains and dark spots have started to grow in these areas. Please test areas for mold and clean them. Although this problem won't be resolved until the roof is either repaired or re-roofed. Main Building has several leaks through out the building.		2/26/09 - Route to Mario to replaced stained tiles, no mold only water stains. - Joe Munoz 10/7 - Asp Mike, rout to Custodial FAX W.O. TO JOE 12/03- REFAXED TO JOE 12/17- REFAXED TO JOE. 1/8/09 - REFAXED TO JOE.						
<u>Velia Alarcon</u>									
39073	Agricultural	Classroom			10/9/2008		145		\$0.00
Medium	Work In Progress				10/9/2008 3:15:51 PM				
Ronquillo, Ruben	need a window blind for room 569 (60"x48")								
<u>Mario Apodaca</u>									
39823	Auto Shop	Classroom			11/4/2008		119		\$0.00
Medium	Work In Progress				11/4/2008 3:05:39 PM				
Lara, Ralph	need 2 new doors at the auto shop the doors are broken do to vandalism								
<u>Mario Apodaca</u>									
40054	Old English Bldg	Gym			11/13/2008		110		\$0.00
Medium	Work In Progress				11/13/2008 3:05:05 PM				
Munoz, Michael	the girls gym need work on the gym floor do to roof leaks . A.S.A.P								
<u>Mario Apodaca</u>									
40182	Auto Shop	Classroom			11/18/2008		105		\$0.00
Medium	Work In Progress				11/18/2008 1:01:06 PM				
Moncayo, Fernando	NEED TO REMOVE THE OLD WASHER AT STORED IN THE AUTO SHOP. AT WAS IN THE KITCHEN ASAP.								
<u>Mario Apodaca</u>									
40542	Old English Bldg	Restroom (Girls)			12/3/2008		90		\$0.00
Medium	Work In Progress				12/3/2008 2:51:58 PM				
Lara, Ralph	need a new door for the girls restroom at the old eng bldg at the top floor. asap.								
<u>Mario Apodaca</u>									
40695	Old English Bldg				12/9/2008		84		\$0.00
Medium	Work In Progress				12/9/2008 12:33:28 PM				
Ambriz, Jose	Girls Gym - Need to check heating and control dampers in gym.								
<u>Michael Munoz</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
40700					12/9/2008		84		\$0.00
Medium	Work In Progress			12/9/2008 12:41:33 PM					
Estrada, Jesus	NEED TO LOOK @ INTERLOCKING TILE IN BOYS GYM (SOUTH SIDE), MEASURE AND ORDER SAME MATERIAL FOR GIRLS VARSITY GYM. ALSO NEED TO ORDER SAME SHOWER MATTING THAT IS IN THE BOYS GYM FOR GIRLS GYMS.		12/10/08 - MICHAEL TO GO OUT TO GH AND QUOTE ON SAME FLOORING PRODUCT (WHICH HE DOES NOT RECOMMEND) AND QUOTE ON WHAT HE DOES RECOMMEND. WILL PRICE QUOTE MATTING FROM FLOORSURFAES.COM / MILO CRIPPS 805-275-4087						
Michael Munoz	1/12/09 - PENDING PURCHASE ORDER								
40707	Library	Library			12/9/2008		84		\$0.00
Medium	Work In Progress			12/9/2008 2:59:42 PM					
Ambriz, Jose	NEED A NEW GAS VALVE FOR A HEATING UNIT AT THE LIBRARY								
Mario Apodaca									
40893		Athletic Field			12/16/2008		77		\$0.00
Medium	Work In Progress			12/16/2008 9:23:01 AM					
Ontiveros, Guadalupe	Requested by Mr. Lawrence for Soccer Field-Over seed soccer field, top soil for soccer field.								
Velia Alarcon									
40898					12/16/2008		77		\$0.00
Medium	Work In Progress			12/16/2008 10:00:05					
Ronquillo, Ruben	Requested by Coach Hite Football J.V. Locker Room in Boy's Gym-Install a mirror in J.V. locker room. Please make mirror as large as possible, alot of students need to use it at the same time.								
Velia Alarcon									
41052					1/4/2009	1/12/2009	58		\$0.00
Medium	Work In Progress			1/4/2009 12:18:42 AM					
Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
41111					1/4/2009	1/12/2009	58		\$0.00
Medium	Work In Progress			1/4/2009 12:19:05 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41149					1/4/2009		58		\$0.00
Medium	Work In Progress			1/4/2009 12:19:23 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.		1/6/09 - E-mailed to ricky.borrego@cummins.com'						
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
41205	Academic Bldg				1/6/2009		56		\$0.00
Medium	Work In Progress				1/6/2009 3:21:19 PM				
Ambriz, Jose	the heating unit at the greenhous need a new fan moter								
Mario Apodaca									
41271	North Building	Gym			1/8/2009		54		\$0.00
Medium	Work In Progress				1/8/2009 2:36:51 PM				
Ronquillo, Ruben	NEED A NEW GLASS SHELVE PUT IN AT THE DLSPLAY CASES(76"X12"1/4")								
Mario Apodaca									
41484		Athletic Field			1/14/2009		48		\$0.00
Medium	Work In Progress				1/14/2009 12:25:58 PM				
Ontiveros, Guadalupe	Requested by Coach Maxey for Track Field-Clean up the track area and blow the track of debris. Please do this the week before the meet which is March 7, 2009. FOR FURTHER INSTRUCTION SEE COACH MAXEY.								
Velia Alarcon									
41485	Concession				1/14/2009		48		\$0.00
Medium	Work In Progress				1/14/2009 12:28:25 PM				
Apodaca, Mario	Requested by Coach Maxey For Football Concession Stand-Turn on ice machine on March 5th so we can use it for the meet which will be held on March 7, 2009.								
Velia Alarcon									
41560		Gym			1/16/2009		46		\$0.00
Medium	Work In Progress				1/16/2009 8:36:45 AM				
Gonzalez, Salvador	windows need to be covered with mesh.								
Salvador Gonzalez									
41633	Old English Bldg	Classroom			1/20/2009		42		\$0.00
High	Work In Progress				1/20/2009 8:52:37 AM				
Vallejo, Albert	as per conversation please look into repairing leak in girls gym. get back to me.thxs								
Michael Munoz									
41640					1/20/2009		42		\$0.00
Medium	Work In Progress				1/20/2009 10:53:12 AM				
Jacquez, Ricardo	CHECK BOOSTER PUMP								
Guadalupe Ontiveros									
41678					1/21/2009		41		\$0.00
Medium	Work In Progress				1/21/2009 7:53:21 AM				
Appelzoller, Fred	NEED TO REPLACE ALL LEAKING FAUCETS AT ALL BOYS AND GIRLS RESTROOM AT CONTRACTOR PUT ON DO TOO THE METERING FAUCETS ARE NOT CLOSING								
Mario Apodaca									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
41732	Cafeteria (1998)	Cafeteria			1/22/2009		40		\$0.00
Medium	Work In Progress			1/22/2009 12:38:06 PM					
Moncayo, Fernando	THE WHEELS ON THE CAFE TABLES NEED TO BE ADJUST ON ALL TABLES. A.S.A.P!!!!!!								
Mario Apodaca									
41733	Cafeteria (1998)	Cafeteria			1/22/2009		40		\$0.00
Medium	Work In Progress			1/22/2009 12:44:35 PM					
Moncayo, Fernando	A FLUORESCENT FIXTURES IS OUT AT THE KITCHEN NEED TO BE FIX								
Mario Apodaca									
41798	North Building	Classroom			1/23/2009		39		\$0.00
Medium	Work In Progress			1/23/2009 2:36:08 PM					
Ambriz, Jose	NEED NEW EXH FAN MOTER FOR THE N-BLDG (5 e.a)								
Mario Apodaca									
41799	Main Building	Office			1/23/2009		39		\$0.00
Medium	Work In Progress			1/23/2009 2:38:36 PM					
Lara, Ralph	NEED A NEW DOOR FOR MR. CHEMBERS OFFICE. A.S.A.P								
Mario Apodaca									
41834	North Building	Classroom			1/26/2009		36		\$0.00
Medium	Work In Progress			1/26/2009 8:45:35 AM					
Castillo, Carlos	Need to ck breakers in N. Bldg, that feed rooms 220,222,223 (Science)								
Mario Apodaca									
41904	Old English Bldg	Classroom			1/27/2009		35		\$0.00
Medium	Work In Progress			1/27/2009 3:35:33 PM					
Ambriz, Jose	NEED TO SET-UP A NEW E/COOLER UNIT ON THE ROOF TOP AT THE OLD ENG BLDGING FOR THE CLASSROOMS								
Mario Apodaca									
42049	Academic Bldg	Classroom			1/30/2009		32		\$0.00
Medium	Work In Progress	Academic 306		1/30/2009 4:00:26 PM					
Castillo, Carlos	I'm also running 10 computers off of 3 power outlets. I have talked to Victor and he agrees that the wiring in my room is a problem. I did ask for this last year and I was told that it would be taken care of but I have not been told when that will happen.								
Erica Acosta									
42105					2/1/2009	2/9/2009	30		\$0.00
Medium	Work In Progress			2/1/2009 12:24:45 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

42214	North Building	Classroom			2/4/2009		27		\$0.00
Medium	Work In Progress	209			2/4/2009 8:42:05 AM				
Munoz, Michael	The cabinets in the home economics room are in need of being replaced. They are not functional and look very bad.								
Albert Vallejo									
42301	New Vocational				2/6/2009		25		\$0.00
Medium	Work In Progress				2/6/2009 8:27:10 AM				
Lara, Ralph	need new restroom toilet partitons at the boys restroom. do to vandalism								
Mario Apodaca									
42319	Cafeteria (1998)	Cafeteria			2/6/2009		25		\$0.00
Medium	Work In Progress				2/6/2009 11:04:33 AM				
Moncayo, Fernando	FIX OR INSTALL BELL (DELIVERY DOOR)								
	DEMETRIOUS P. GIOVAS - SNP DIRECTOR 882-6771								
Alma Terrell									
42337	Business				2/6/2009		25		\$0.00
Medium	Work In Progress				2/6/2009 4:36:55 PM				
Munoz, Michael	need to purchase 24 bobbin case cb hook for sewing machines								
Velia Alarcon									
42363	Business				2/9/2009		22		\$0.00
Medium	Work In Progress				2/9/2009 8:48:22 AM				
Apodaca, Mario	Requested by Mr. Gomez Rm. 602 Business Building- Put up a white board.								
Velia Alarcon									
42389					2/9/2009		22		\$0.00
Medium	Work In Progress				2/9/2009 3:26:54 PM				
Moncayo, Fernando	THE DELI CART AT ROOM 233 IS AT 49 NEED TO BE AT 38 OR LOWER. ASAP.								
Mario Apodaca									
42422	Cafeteria (1998)	Cafeteria			2/10/2009		21		\$0.00
Medium	Work In Progress				2/10/2009 1:44:44 PM				
Moncayo, Fernando	POTATO MIXER, START BUTTON GETS STUCK								
	LYDIA MONTOYA - SNP MANAGER - 882-5522								
Alma Terrell									
42429	Cafeteria (1998)	Cafeteria			2/10/2009		21		\$0.00
Medium	Work In Progress				2/10/2009 2:07:12 PM				
Moncayo, Fernando	PUSH CART NEEDS NEW WHEELS								
	LYDIA MONTOYA - SNP MANAGER -882-5522								
Alma Terrell									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
42433	North Building	Classroom			2/10/2009		21		\$0.00
Medium	Work In Progress				2/10/2009 3:05:50 PM				
Ambriz, Jose	NEED TO T/SHOOT A HEATING UNIT AT THE N-BLDG TO ROOM 215								
Mario Apodaca									
42546	Academic Bldg	Classroom			2/13/2009		18		\$0.00
Medium	Work In Progress				2/13/2009 8:10:20 AM				
Lara, Ralph	NEED A NEW DOOR CLOSER FOR CLASSROOM AT THE ACADEMIC BLDG TO ROOM 333								
Mario Apodaca									
42551	Cafeteria (1998)				2/13/2009		18		\$0.00
Medium	Work In Progress				2/13/2009 9:24:33 AM				
Garcia, Jose	please clean area around cafeteria. please use the power washer. coordinate w/ joey custodial so when you do the windows they can dry and clean them. Thanks								
Michael Munoz									
42589					2/14/2009		17		\$0.00
Medium	Work In Progress				2/14/2009 12:17:35 AM				
Jacquez, Ricardo	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
42598					2/17/2009		14		\$0.00
Medium	Work In Progress				2/17/2009 8:58:46 AM				
Appelzoller, Fred	Please check all metering faucets throughout campus. They are not turning off by themselves. (See Mike Munoz)								
Michael Munoz									
42606	Main Building				2/17/2009		14		\$0.00
Medium	Work In Progress				2/17/2009 9:53:50 AM				
Apodaca, Mario	Requested by Ms. R. Holguin Rm. 125 Main Building- Need to replace bulb in storage room 125a, no light.								
Velia Alarcon									
42608	Main Building				2/17/2009		14		\$0.00
Medium	Work In Progress				2/17/2009 10:03:56 AM				
Apodaca, Mario	Requested by Ms. Lam Rm. 104 Main Building-The screen for the overhead projector does no roll-up.								
Velia Alarcon									
42613					2/17/2009		14		\$0.00
Medium	Work In Progress				2/17/2009 10:39:57 AM				
Lara, Ralph	Requested by Velia-Please stop by to speak to me regarding WORK ORDER # 42220, there are some concerns.								
Velia Alarcon									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
42627	Cafeteria (1998)				2/17/2009		14		\$0.00
Medium	Work In Progress				2/17/2009 2:36:05 PM				
Moncayo, Fernando	NEED TO SERVICE ALL EVAPOATIVE COOLER UNIT AT COOL DOWN THE KITCHEN FOR START-UP IN THE SPRING								
<u>Mario Apodaca</u>									
42662	Cafeteria (1998)	Cafeteria			2/18/2009		13		\$0.00
Medium	Work In Progress				2/18/2009 10:46:23 AM				
Moncayo, Fernando	REACH- IN REFRIG. (ITALIAN LINE) TEMP AT 60								
	LYDIA MONTOYA SNP MGR 882-5522								
<u>Jacqueline Aguilar</u>									
42664	Cafeteria (1998)	Cafeteria			2/18/2009		13		\$0.00
Medium	Work In Progress				2/18/2009 10:50:30 AM				
Moncayo, Fernando	REACH IN - REFRIG. (ON A BUN LINE) TEMP AT 55 - 60								
	LYDIA MONTOYA - SNP MGR 882-5522								
<u>Jacqueline Aguilar</u>									
42711					2/19/2009		12		\$0.00
Medium	Work In Progress				2/19/2009 1:52:27 PM				
Ontiveros, Guadalupe	Requested by Coach Maxey for Track Fields-Patch the high jump runway at the south end of the track. Cover the existing high jump area that is in concrete with tar to expand the area.								
<u>Velia Alarcon</u>									
42783	Pool Pump	Pool			2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 8:00:42 AM				
Villalobos, David	need to install backflow preventer that was taken out								
<u>David Villalobos</u>									
42799	Football Stadium				2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 2:54:56 PM				
Lara, Ralph	need a new lock set for the football shack								
<u>Mario Apodaca</u>									
42800	Football Stadium				2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 2:56:39 PM				
Ronquillo, Ruben	need a new window at the football shack								
<u>Mario Apodaca</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
42819	North Building				2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 4:19:30 PM				
Castillo, Carlos	Requested by Mr. J. Gonzales Rm. 206 North Building- No power on all wall outlets, breaker form Teacher's Lounge possibly needs to be reset. POSSIBLE FIRE HAZARD with refrigerator, Coke Machine, microwave and all my outlets drawing power from the same wire.								
Velia Alarcon									
42820					2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 4:21:03 PM				
Vallejo, Albert	Requested by Isela Martinez for Counseling Center- Need 8 chairs assembled and Brochure Display roto rack.								
Velia Alarcon									
42821					2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 4:24:00 PM				
Vallejo, Albert	Requested by Mr. R. Grace for Facility Goal Team-Move lockers from hallway in Business Building to P.E. Locker rooms and Weight rooms. SEE MR. GRACE FOR FURTHER INSTRUCTIONS.								
Velia Alarcon									
42848	Cafeteria (1998)	Cafeteria			2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 2:30:17 PM				
Munoz, Joe	Strip floor in kitchen during the week of March, 23-27. (Assign to J. Munoz)								
Jesus Estrada									
42890					2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 8:03:27 AM				
Lara, Ralph	Need a lock and chain for North Gate at Agricultural Farm.								
Albert Vallejo									
42918					2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 11:27:29 AM				
Carrasco, Danny	Danny need to conduct inventory of all Building Mechanic tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									
42927					2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 12:30:55 PM				
Carrasco, Danny	Danny need to conduct inventory of all Bldg Mechanic tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
42942	Auto Shop	Classroom			2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 3:36:20 PM					
Moncayo, Fernando		REQUEST # 2 W/O 40182 NEED TO REMOVE THE OLD WASHER AT STORED IN THE AUTO SHOP AT WAS IN THE KITCHEN A.S.A.P							
Mario Apodaca									
42968		Lift Station			2/26/2009		5		\$0.00
Medium	Work In Progress			2/26/2009 9:20:48 AM					
Jacquez, Ricardo		please replace starter on lift station for pump #1							
Ricardo Jacquez									
42975	Counselors	Restroom (Girls)			2/26/2009		5		\$0.00
Medium	Work In Progress			2/26/2009 11:42:26 AM					
Ambriz, Jose		the exhaust fan at the restroom does turn on but will not withdraw air or odors							
Joe Munoz									
43021	Grounds Shop	Athletic Field			2/27/2009		4		\$0.00
High	Work In Progress			2/27/2009 8:49:52 AM					
Gonzalez, Salvador		Need to secure breakers for safety, at bus trun-around by pump.							
Guadalupe Ontiveros									
43032	Cafeteria (1998)	Cafeteria			2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 11:00:38 AM					
Moncayo, Fernando		Reach In Refrig. (Italian Side) temp is at 60 Lydia M. SNP MGR 882-5522							
Jacqueline Aguilar									
43036	Academic Bldg	Restroom (Boys)			2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 12:45:08 PM					
Munoz, Michael		THE PARTITONS AT ACADIMIC BLDG AT THE BOY'S RESTROOM ARE VANDALIS ON THE E/SIDE WING (4/28/08 Asp Mario has not been done)							
Mario Apodaca									
43057					2/27/2009		4		\$0.00
High	Work In Progress			2/27/2009 3:26:44 PM					
Carbajal, Jimmy		We need 6 trash barrels for Gadsden High School. (Assign to Jimmy)							
Jesus Estrada									
43087					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:49 AM					
Vallejo, Albert		Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
43088					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:50 AM					
Vallejo, Albert		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
43089					3/1/2009	4/1/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:50 AM					
Vallejo, Albert		Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
43123					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:02 AM					
Orozco, Danny		Yearly - Gadsden HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
43189					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:25 AM					
Apodaca, Mario		Yearly - Gadsden HS A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
43190					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:25 AM					
Apodaca, Mario		Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
43226					3/2/2009		1		\$0.00
Medium	Work In Progress			3/2/2009 9:24:39 AM					
Apodaca, Mario		NEED TO MOVE E/COOLER AT ROOM 107 AND THE OLD COUNS BLDG TO THE LIBRARY							
Mario Apodaca									
43255	Agricultural	Athletic Field			3/3/2009		0		\$0.00
Medium	Work In Progress			3/3/2009 8:32:15 AM					
Lara, Ralph		Need pad lock to secure breakers at bus-turn around to be keyed HE-163							
Guadalupe Ontiveros									
43256	Grounds Shop				3/3/2009		0		\$0.00
Medium	Work In Progress			3/3/2009 8:38:57 AM					
Lara, Ralph		In the water/wastewater office,located in the Grounds Shop building,one of my filing cabinets will not open.The key turns the lock but will not open the drawers.I can not access the important reports that I need for my job. Thanks,Raul Sanchez							

Raul Sanchez

3/3/2009 12:02:21 PM

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

Count: 108 Work Orders	Avg. Age of WO's 78	Total for Gadsden HS	0	\$0.00
------------------------	---------------------	----------------------	---	--------

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
37770		Portables			9/4/2008		180		\$0.00
Medium	Work In Progress			9/4/2008 8:13:40 AM					
Sotelo, Enrique		Please provide electrical connection to 2 Bard units.							
Lorenzo Solis									
35702					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:08 AM					
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
35955					7/14/2008		232		\$0.00
Medium	Work In Progress			7/14/2008 3:35:17 PM					
Lozoya, Manny		Need fix main entrance doors the punish bar not work properly thank you							
Sebastian Diaz									
36222		Office			7/25/2008		221		\$0.00
Medium	Work In Progress	Awing/GMS Front		7/25/2008 11:40:57 AM					
Lozoya, Manny		Need to set up A57 key lock on new door in Ms. Quinonez's office as soon as possible.							
Maricruz Carrasco									
36627		Office			8/5/2008		210		\$0.00
Medium	Work In Progress	GMS Front		8/5/2008 5:44:35 AM					
Lozoya, Manny		Need A53 door lock on Nancy's door as soon as possible.							
Maricruz Carrasco									
36628		Office			8/5/2008		210		\$0.00
Medium	Work In Progress	Awing/155/Dr.		8/5/2008 5:47:23 AM					
Lozoya, Manny		Door lock in Dr. Garcia's office supposed to be opened by M36 key only. W key can be used to open the door. Please check door lock.							
Maricruz Carrasco									
36632		Parking Lot			8/5/2008		210		\$0.00
Medium	Work In Progress	Parking		8/5/2008 5:59:53 AM					
Lozoya, Manny		Need metal door installed in Security shed.							
Maricruz Carrasco									
37267		Office			8/21/2008		194		\$0.00
Medium	Work In Progress	Awing/162/Securit		8/20/2008 10:01:58 PM					
Lozoya, Manny		"W" key is getting jammed.							
Maricruz Carrasco									
37270		Classroom			8/21/2008		194		\$0.00
Medium	Work In Progress	Awing/159/E.		8/20/2008 10:06:16 PM					
Lozoya, Manny		Door does not close and lock.							
Maricruz Carrasco									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
37763	C-Wing	Classroom			9/3/2008		181		\$0.00
Medium	Work In Progress	Cwing/C-		9/3/2008 9:29:19 PM					
Lozoya, Manny Maricruz Carrasco Door does not lock. Safety issue.									
37764	C-Wing	Office			9/3/2008		181		\$0.00
Medium	Work In Progress	Cwing/Dr. Montes		9/3/2008 9:30:21 PM					
Lozoya, Manny Maricruz Carrasco Door does not lock.									
38385					9/24/2008		160		\$0.00
Medium	Work In Progress	All GMS Staff		9/23/2008 10:06:29 PM					
Lozoya, Manny Maricruz Carrasco All staff restrooms to have latch placed on door for privacy reasons.									
38417	C-Wing				9/24/2008		160		\$0.00
Medium	Work In Progress			9/24/2008 3:44:29 PM					
Lozoya, Manny Michael Munoz New Portable - 1st thing tomorrow need to recore like GMS (see Mike if u have any questions).									
38464	C-Wing				9/26/2008		158		\$0.00
Medium	Work In Progress			9/26/2008 12:26:38 PM					
Lozoya, Manny Michael Munoz Mr. Chacon, Band Director needs a gate key for gate by C-Wing.									
38485					9/26/2008		158		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:32:43 PM					
Lozoya, Manny Maricruz Carrasco Need three WA-83 keys. Need two V-3 keys.									
38486					9/26/2008		158		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:34:17 PM					
Lozoya, Manny Maricruz Carrasco Need two keys made for golf cart.									
38487	C-Wing	Portables			9/26/2008		158		\$0.00
Medium	Work In Progress	C-wing/New		9/26/2008 4:35:35 PM					
Lozoya, Manny Maricruz Carrasco Fix lock to main entrance on new portable-Health Center									
38651	Annex				10/2/2008		152		\$0.00
Medium	Work In Progress			10/2/2008 3:20:00 PM					
Lozoya, Manny Sebastian Diaz Need fix handi cup door in annex bldg thank you									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
39213		Office			10/14/2008		140		\$0.00
Medium	Work In Progress	Dr. Garcia's		10/14/2008 9:56:39 AM					
Lozoya, Manny		Install lock on black storage cabinet for Maricruz.							
Maricruz Carrasco									
39856					11/5/2008		118		\$0.00
Medium	Work In Progress			11/5/2008 2:20:53 PM					
Lozoya, Manny		Controls contractor (Trane) Needs keys to acces building on Monday Nov. 10							
Alfredo Holguin									
39910	C-Wing	Portables			11/6/2008		117		\$0.00
Medium	Work In Progress			11/6/2008 2:25:24 PM					
Holguin, Alfredo		Connect Electrical service to new portable for School Based Health Clinic							
Alfredo Holguin									
40147	C-Wing				11/17/2008		106		\$0.00
Medium	Work In Progress			11/17/2008 2:29:35 PM					
Lozoya, Manny		Nursing Coordinator Offices - Rekey - check with Ms. Cregan on keying							
Alfredo Holguin									
40601		Cafeteria			12/4/2008		89		\$0.00
Medium	Work In Progress			12/4/2008 4:02:49 PM					
Moncayo, Fernando		SNP Warehouse - Some windows are broken and seals are poor in existing windows allowing a large amount of dust to come in where food is being stored. Good lighting is available therefore, we are requesting that the windows be covered with plywood and sealed to prevent contamination of food items.							
		Johnny Lechuga - SNP Warehouse							
Alma Terrell									
40785					12/11/2008		82		\$0.00
Medium	Work In Progress	A wing / Sped		12/11/2008 10:29:02					
Lozoya, Manny		Re-Key File Cabinet							
Maricruz Carrasco									
40786		Classroom			12/11/2008		82		\$0.00
Medium	Work In Progress	A wing / 178		12/11/2008 10:30:20					
Lozoya, Manny		Repair Lock to File Cabinet							
Maricruz Carrasco									
40787					12/11/2008		82		\$0.00
Medium	Work In Progress	B Wing / New		12/11/2008 10:31:39					
Lozoya, Manny		Re-Key to A53							
Maricruz Carrasco									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
41220	Annex				1/6/2009		56		\$0.00
Medium	Work In Progress	GMS		1/6/2009 4:52:10 PM					
Ontiveros, Guadalupe	Two large holes between Annex and portable need to be filled with dirt. Please see Dr. Garcia for more information.								
<u>Maricruz Carrasco</u>									
41221					1/6/2009		56		\$0.00
Medium	Work In Progress	GMS Campus		1/6/2009 4:53:38 PM					
Ontiveros, Guadalupe	Uprooted tree needs to be covered with dirt. Please see Dr. Garcia for more information.								
<u>Maricruz Carrasco</u>									
41222					1/6/2009		56		\$0.00
Medium	Work In Progress	GMS Campus		1/6/2009 4:56:28 PM					
Ontiveros, Guadalupe	GMS tables/benches stored in warehouse need to be set up on GMS Campus. Please see Dr. Garcia for more information.								
<u>Maricruz Carrasco</u>									
41266					1/8/2009		54		\$0.00
Medium	Work In Progress			1/8/2009 10:14:34 AM					
Lozoya, Manny	NEED TO INSTALL CORES IN NEW ANNEX BUILDING.								
<u>Maritza Gonzalez</u>									
41379	Band Room	Portables			1/11/2009		51		\$0.00
Safety	Work In Progress	C-213 and Band		1/11/2009 12:27:24 AM					
Munoz, Michael	Fence needs to be placed to close the campus by C-213, Mr. Martinez's classroom and the Band room. This will help stop the ditching in that area and also stop any vandalism to the vehicles								
<u>Maricruz Carrasco</u>									
41382	Gym	Gym			1/11/2009		51		\$0.00
Medium	Work In Progress	Gym/Boys and		1/11/2009 12:34:27 AM					
Appelzoller, Fred	Toilets in both coaches offices restrooms leak when flushed.								
<u>Maricruz Carrasco</u>									
41469	Annex	Classroom			1/13/2009		49		\$0.00
High	Work In Progress			1/13/2009 4:42:58 PM					
Acosta, Juan	Furniture needs to be moved into classrooms in Annex 400-410.								
<u>Jesus Estrada</u>									
41573					1/16/2009		46		\$0.00
Medium	Work In Progress	War room in		1/16/2009 10:54:08 AM					
Lozoya, Manny	Secure storage cabinet with clasp in WAR Room								
<u>Maricruz Carrasco</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
41575	C-Wing				1/16/2009		46		\$0.00
Medium	Work In Progress	C wing/ Elev. 8		1/16/2009 10:57:09 AM					
Lozoya, Manny		Lock change for storage room in the Elev. 8 room. (See Shirley Baca)							
<u>Maricruz Carrasco</u>									
41578		Cafeteria			1/16/2009		46		\$0.00
Medium	Work In Progress	War room		1/16/2009 11:04:53 AM					
Lozoya, Manny		Re-key off Master to M36, same as Dr. Garcia's office							
<u>Maricruz Carrasco</u>									
41588		Computer Lab			1/16/2009		46		\$0.00
Medium	Work In Progress	rooms next to		1/16/2009 11:25:41 AM					
Lozoya, Manny		Need construction Core removed from computer labs next to library and Keyed to GISD Key Core. ASAP							
<u>Maricruz Carrasco</u>									
41590					1/16/2009		46		\$0.00
Medium	Work In Progress			1/16/2009 11:30:43 AM					
Lozoya, Manny		Need extra copy of key 56 for boiler room for Dr. Garcia							
<u>Maricruz Carrasco</u>									
41788		Classroom			1/23/2009		39		\$0.00
Medium	Work In Progress	B wing/ room 109		1/23/2009 10:56:22 AM					
Lozoya, Manny		Need two new locks for cabinets							
<u>Maricruz Carrasco</u>									
41792	Annex				1/23/2009		39		\$0.00
Medium	Work In Progress	Home Ec/ room		1/23/2009 11:54:39 AM					
Lozoya, Manny		Lock to storage cabinet (see mr. kohl)							
<u>Maricruz Carrasco</u>									
41853					1/26/2009		36		\$0.00
Medium	Work In Progress	A Wing/ Front		1/26/2009 3:37:20 PM					
Lozoya, Manny		8 keys to Basketball goals (Connie) 3 set's of keys to Partition Doors in Multipurpose rooms (Connie) Change Lock in Multipurpose Room (Mrs. Williams)							
<u>Maricruz Carrasco</u>									
41903					1/27/2009		35		\$0.00
Medium	Work In Progress			1/27/2009 3:34:39 PM					
Diaz, Sebastian		Need to install rain gutters in B wig entrances thank you							
<u>Sebastian Diaz</u>									
41905	C-Wing				1/27/2009		35		\$0.00
Medium	Work In Progress			1/27/2009 3:35:53 PM					
Diaz, Sebastian		Need to intall rain gutters in C wing area thank you							
<u>Sebastian Diaz</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
41924					1/28/2009		34		\$0.00
Medium	Work In Progress			1/28/2009 8:15:30 AM					
Lozoya, Manny	Need to fix door handal in room 303 vocatinal bldg thank you								
Sebastian Diaz									
41932					1/28/2009		34		\$0.00
Medium	Work In Progress	room 146 and		1/28/2009 10:15:28 AM					
Lozoya, Manny	Key new computer labs, rooms 146 and 148.								
	Need 5 keys of the V8 (Connie)								
Maricruz Carrasco									
41938					1/28/2009		34		\$0.00
Medium	Work In Progress	Library		1/28/2009 11:19:35 AM					
Lozoya, Manny	Rekey inside new library								
Maricruz Carrasco									
41988					1/29/2009		33		\$0.00
Medium	Work In Progress			1/29/2009 11:28:47 AM					
Ontiveros, Guadalupe	could you please support w/ the irrigation system in the front of the campus to include the backflow preventer. no water thxs								
Michael Munoz									
41989					1/29/2009		33		\$0.00
Medium	Work In Progress			1/29/2009 11:32:40 AM					
Appelzoller, Fred	please provide and check all hose bibbs around campus for water hose hook ups. thxs								
Michael Munoz									
42020					1/30/2009		32		\$0.00
Medium	Work In Progress			1/30/2009 11:37:16 AM					
Lozoya, Manny	Need to check key and lock in computer lab thank you								
Sebastian Diaz									
42021					1/30/2009		32		\$0.00
Medium	Work In Progress			1/30/2009 11:39:56 AM					
Lozoya, Manny	Need to change lock in new annex bldg electrical room thank you								
Sebastian Diaz									
42317	C-Wing	Custodial			2/6/2009		25		\$0.00
Medium	Work In Progress			2/6/2009 10:48:40 AM					
Estrada, Jesus	LIKE TO ORDER 2 AIR BLOWERS AND 1 WEED EATER								
Juan Acosta									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
42398	Gym	Gym			2/9/2009		22		\$0.00
Medium	Work In Progress	Gym/Boys			2/9/2009 4:15:46 PM				
Lozoya, Manny		New lock needed for Boys Basketball Storage. See Connie for more information.							
<u>Maricruz Carrasco</u>									
42427	Cafeteria	Cafeteria			2/10/2009		21		\$0.00
Medium	Work In Progress				2/10/2009 2:04:08 PM				
Lozoya, Manny		REPLACE LOCK/DOOR KNOB TO LADIES RESTROOM (SOMEONE TRASHED IT PRETTY BAD - TOLIET PAPER ALL OVER THE PLACE AND FECES)							
		TERRY PORTILLO - SNP MANGER 882-3507 OR 882-2824							
<u>Alma Terrell</u>									
42590					2/14/2009		17		\$0.00
Medium	Work In Progress				2/14/2009 12:17:36 AM				
Jacquez, Ricardo		Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
42619	Main Building				2/17/2009		14		\$0.00
Medium	Work In Progress	B- Wing			2/17/2009 12:06:39 PM				
Sotelo, Enrique		Asp PM 42129, Need power in Main Entrance for emerg.lights. (see Sebastian for further info).							
<u>Sebastian Diaz</u>									
42691		Classroom			2/19/2009		12		\$0.00
Medium	Work In Progress	Bwing/140/G.Riva			2/19/2009 12:20:14 AM				
Lozoya, Manny		Filing cabinet lock needs to be replaced.							
<u>Maricruz Carrasco</u>									
42741		Athletic Field			2/20/2009		11		\$0.00
Medium	Work In Progress				2/20/2009 9:21:56 AM				
Villalobos, David		leaking irrigation backflow preventer needs to be repaired							
<u>David Villalobos</u>									
42928					2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 12:31:58 PM				
Carrasco, Danny		Danny need to conduct inventory of all Bldg Mechanic tools and equipment. Ask Ruben for present inventory list to match up.							
<u>Michael Munoz</u>									
42965					2/26/2009		5		\$0.00
Medium	Work In Progress				2/26/2009 8:25:09 AM				
Appelzoller, Fred		Isolate water valves for all new bldg, water valves.				Need Ditch Witch for digging french drain for drinking fountain. asp report 2/24/09			
Michael Munoz									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
42976	Gym				2/26/2009		5		\$0.00
Medium	Work In Progress				2/26/2009 12:38:53 PM				
Solis, Lorenzo Need to fix broken outside light behind the gym thank you									
Sebastian Diaz									
43010	Classroom				2/27/2009		4		\$0.00
Medium	Work In Progress	Awing/157/Peters			2/27/2009 5:54:17 AM				
Diaz, Sebastian Thermostat needs closure and a cover for protection.									
Maricruz Carrasco									
43082					3/1/2009	3/17/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:22:47 AM				
Villalobos, Margret Yearly - Gadsden MS March Chiller Insp. - Refer to PM schedule details.									
Margret Villalobos									
43119					3/1/2009		2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:01 AM				
Orozco, Danny Yearly - Gadsden MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.									
Margret Villalobos									
43216					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:34 AM				
Diaz, Sebastian Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.									
Margret Villalobos									
43217					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:34 AM				
Diaz, Sebastian Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.									
Margret Villalobos									
43218					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:35 AM				
Diaz, Sebastian Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.									
Margret Villalobos									
43219					3/1/2009		2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:35 AM				
Diaz, Sebastian Yearly - Gadsden MS A-10 HP Rooftop Yearly - Refer to PM schedule details.									
Margret Villalobos									
43243					3/2/2009		1		\$0.00
Medium	Work In Progress				3/2/2009 3:46:57 PM				
Gonzalez, Salvador Need to weld gate wheels and roolling wheel in south gate thank you									
Sebastian Diaz									

3/3/2009 12:02:22 PM

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

Count: 68 Work Orders Avg. Age of WO's 79 Total for Gadsden MS 0 \$0.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
Location:		La Union - JTP Alvarez Farms							
41895					1/27/2009		35		\$0.00
Medium	Work In Progress	ENTIRE			1/27/2009 2:12:34 PM				
Villalobos, Margret		PLEASE spray for bugs inside and outside of the building.				2/23 Price Quote 100.00 - waiting on approval.			
Margaret Villalobos									
Count: 1	Work Orders		Avg. Age of WO's	35	Total for La Union - JTP Alvarez Farms			0	\$0.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
35705					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:09 AM					
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36590					8/4/2008		211		\$0.00
Medium	Work In Progress			8/4/2008 10:36:40 AM					
Castillo, Carlos		Run elect. to morgom maint storage - would be nice to use fan							
Patricio Aguilar									
37120					8/15/2008		200		\$0.00
Medium	Work In Progress			8/15/2008 3:17:51 PM					
Carrasco, Danny		Need 3 gfi elect out lets #202							
Patricio Aguilar									
38034					9/11/2008		173		\$0.00
Medium	Work In Progress			9/11/2008 3:14:33 PM					
Villalobos, David		pat aguilar need rubber bushing for water faucet - thank you							
Patricio Aguilar									
38036					9/11/2008		173		\$0.00
Medium	Work In Progress			9/11/2008 3:22:31 PM					
Ambriz, Jose		pat aguilar wants her refrigerated ac replaced - that it is to loud							
Patricio Aguilar									
40988					12/18/2008		75		\$0.00
Medium	Work In Progress			12/18/2008 3:20:23 PM					
Ambriz, Jose		pat aguilar the thermostat not working right - dayton electric heater model 2e441 ser 143933 volts 240/208 wats 4800/2500 60 hz 13tu 16382/11946							
Patricio Aguilar									
41167					1/5/2009		57		\$0.00
Medium	Work In Progress			1/5/2009 3:33:50 PM					
Ambriz, Jose		pat aguilar heater boiler pump taco model fm1207 has a bad bearing							
Patricio Aguilar									
41244					1/7/2009		55		\$0.00
Medium	Work In Progress			1/7/2009 3:11:39 PM					
Lara, Ralph		pat aguilar need a new frame & door for rest room r210							
Patricio Aguilar									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
41883		Classroom			1/27/2009		35		\$0.00
Medium	Work In Progress			1/27/2009 10:12:35 AM					
Ambriz, Jose	The thermostat not working will not cut off set tempiter rm 303								
Patricio Aguilar									
41999					1/29/2009		33		\$0.00
Medium	Work In Progress			1/29/2009 3:09:17 PM					
Ambriz, Jose	pat aguilar need to replace a 1/2" ball vale on heater pump								
Patricio Aguilar									
42202					2/3/2009		28		\$0.00
Medium	Work In Progress			2/3/2009 3:44:11 PM					
Gonzales, Angel	Need to use sweeper for drive ways								
Patricio Aguilar									
42256		Cafeteria			2/5/2009		26		\$0.00
Medium	Work In Progress			2/5/2009 8:20:41 AM					
Moncayo, Fernando	WALK - IN FREEZER TEMP AT 33.								
	LINDA YANAGA SNP MGR 589-2040								
Jacqueline Aguilar									
42632					2/17/2009		14		\$0.00
Medium	Work In Progress			2/17/2009 3:11:32 PM					
Gonzales, Angel	need stop light assembly replaced truck #106 dodge left side								
Patricio Aguilar									
43019		Cafeteria			2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 8:10:37 AM					
Moncayo, Fernando	FREEZER TEMP. AT 57 THIS MORNING.								
	LINDA YANAGA SNP MGR 589-2040								
Jacqueline Aguilar									
43052					2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 3:20:31 PM					
Carrasco, Danny	need use of the lift to hang one banner in gym								
Patricio Aguilar									
43077					2/28/2009		3		\$0.00
Medium	Work In Progress			2/28/2009 12:19:58 AM					
Aguilar, Patricio	Monthly - La Union ES A-16 Fan Exhaust Semimonthly - Refer to PM schedule details.								
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
43110					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:58 AM					
Orozco, Danny	Yearly - La Union ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43195					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:27 AM					
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43196					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:27 AM					
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43197					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:28 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
Count: 20 Work Orders			Avg. Age of WO's	67		Total for La Union ES	0		\$0.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
35703					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:08 AM					
Villalobos, David	Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
37711		Athletic Field			9/2/2008		182		\$0.00
Medium	Work In Progress			9/2/2008 3:15:39 PM					
Ontiveros, Guadalupe	Water leak from one of the irrigation line its coming from under the cement. by the basketball courts area.								
Rudy Arreola									
38782					10/5/2008	10/26/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:04 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
38964					10/6/2008		148		\$0.00
Medium	Work In Progress			10/6/2008 1:40:46 PM					
Carrasco, Danny	Need pressure washer and hose to wash off wall of the east side of main bldg.								
Rudy Arreola									
40791					12/11/2008		82		\$0.00
Medium	Work In Progress			12/11/2008 12:35:13					
Lozoya, Manny	We need a new lock for new gate that was installed								
Rudy Arreola									
40792					12/11/2008		82		\$0.00
Medium	Work In Progress			12/11/2008 12:37:00					
Lozoya, Manny	Overhead file cabinet does not lock need a new lock installed.								
Rudy Arreola									
40793					12/11/2008		82		\$0.00
Medium	Work In Progress			12/11/2008 12:38:32					
Arreola, Rudy	Total of 180 ceiling tiles that were damaged on 12/9/09-12/10/08.					2/17/09 - Reroute to Rudy asp Mike - Danny Carrasco			
Rudy Arreola									
41073					1/4/2009	1/25/2009	58		\$0.00
Medium	Work In Progress			1/4/2009 12:18:50 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
41323		Library			1/9/2009		27		\$0.00
Medium	Work In Progress			1/9/2009 3:19:20 PM		2/5/2009			
Arreola, Rudy	please paint library before shelving is installed. thxs								
Michael Munoz									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Loma Linda ES								
41564					1/16/2009		46		\$0.00	
Medium	Work In Progress			1/16/2009 9:16:24 AM						
Arreola, Rudy		Need to replace a total of 180 ceiling tiles that were damaged on 12/9/09-12/10/08.								
Michael Munoz										
42146					2/2/2009		29		\$0.00	
Medium	Work In Progress			2/2/2009 2:22:39 PM						
Gonzales, Angel		Riding mower needs service and new blades also back tires are low.								
Rudy Arreola										
42147					2/2/2009		29		\$0.00	
Medium	Work In Progress			2/2/2009 2:23:29 PM						
Lozoya, Manny		Lock in room 107 was getting stuck and hard to lock.								
Rudy Arreola										
42148					2/2/2009		29		\$0.00	
Medium	Work In Progress			2/2/2009 2:25:08 PM						
Lozoya, Manny		Door closure came off door in RM 211								
Rudy Arreola										
42259	Main Building	Classroom			2/5/2009		26		\$0.00	
Medium	Work In Progress			2/5/2009 8:53:21 AM						
Lozoya, Manny		RM 317 Music Room - Having trouble opening door.								
Luis Solis										
42276					2/5/2009		26		\$0.00	
Medium	Work In Progress			2/5/2009 2:03:22 PM						
Lozoya, Manny		We need to have 2 sets of RR have the door handle changed so we can lock the RR One is front lobby and the other is cafeteria lobby. BOYS AND GIRLS								
Rudy Arreola										
42524					2/12/2009		19		\$0.00	
Medium	Work In Progress			2/12/2009 12:54:24 PM						
Sotelo, Enrique		We need an outlet relocated for tv.								
Rudy Arreola										
42525					2/12/2009		19		\$0.00	
Medium	Work In Progress			2/12/2009 12:55:10 PM						
Sotelo, Enrique		We need to have 2 more outlets in installed in server RM.								
Rudy Arreola										
42745		Portables			2/20/2009		11		\$0.00	
Medium	Work In Progress			2/20/2009 11:38:44 AM						
Castillo, Carlos		Asp Rudy, single portable is having power failure.								
Rudy Arreola										

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: Loma Linda ES										
43111					3/1/2009		2		\$0.00	
Medium	Work In Progress			3/1/2009 12:22:58 AM						
Orozco, Danny	Yearly - Loma Linda ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.									
Margret Villalobos										
43204					3/1/2009		2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:30 AM						
Arreola, Rudy	Yearly - Loma Linda ES A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.									
Margret Villalobos										
43205					3/1/2009	3/7/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:30 AM						
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.									
Margret Villalobos										
43206					3/1/2009	3/9/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:31 AM						
Arreola, Rudy	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.									
Margret Villalobos										
43207					3/1/2009	3/9/2009	2		\$0.00	
Medium	Work In Progress			3/1/2009 12:23:31 AM						
Arreola, Rudy	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
Margret Villalobos										
Count: 23 Work Orders	Avg. Age of WO's 56		Total for Loma Linda ES				0	\$0.00		

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
35549					7/6/2008	7/12/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:19:20 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
35567					7/6/2008	7/14/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:19:26 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
35626					7/6/2008	7/14/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:19:44 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35636					7/6/2008	7/14/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:19:47 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35661					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:19:55 AM					
Ramirez, Joe	Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
35684					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:02 AM					
Ramirez, Joe	Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
35706					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:09 AM					
Villalobos, David	Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36109					7/22/2008		224		\$0.00
Medium	Work In Progress			7/22/2008 10:11:48 AM					
Lozoya, Manny	on (work room) needs a cylinder with a key they have school files need to be lock all the time as per montano principal asap. thank you. luis								
Luis Saucedo									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
36147	Main Building	Office			7/23/2008		223		\$0.00
Medium	Work In Progress	Main office area		7/23/2008 12:29:38 PM					
Lozoya, Manny	Main office need's (4) engraved plaque's for front office door. Name and Title (Jacob Montano, Principal), (Sandra Mora, Secretary), (Dora Lerma, Data-Entry Clerk), (Maribel Villela, Receptionist-Clerk) for Manny Lozoya.								
Sandra Mora									
36227		Portables			7/25/2008		221		\$0.00
Medium	Work In Progress			7/25/2008 2:11:53 PM					
Lozoya, Manny	Ms. Flores room # 801 has filing cabinet that doesn't have a key, need's to be re-key.								
Sandra Mora									
36256	2003 Classroom	Classroom			7/28/2008		218		\$0.00
Medium	Work In Progress	Portable room #		7/28/2008 8:30:02 AM					
Lozoya, Manny	Ms. Jimenez, portable room # 506 she has a storage cabinet needs to be re-key.								
Sandra Mora									
36259	2003 Classroom	Classroom			7/28/2008		218		\$0.00
Medium	Work In Progress	Kinder hallway,		7/28/2008 8:58:17 AM					
Lozoya, Manny	Need a master for that room # 405 for our inventory, and key # 305.								
Sandra Mora									
36507					8/3/2008	8/9/2008	212		\$0.00
Medium	Work In Progress			8/3/2008 12:20:15 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
36539					8/3/2008	8/11/2008	212		\$0.00
Medium	Work In Progress			8/3/2008 12:20:26 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36549					8/3/2008	8/11/2008	212		\$0.00
Medium	Work In Progress			8/3/2008 12:20:29 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36885	Main Building	Office			8/11/2008		204		\$0.00
Medium	Work In Progress	Office area		8/11/2008 11:09:39 AM					
Lozoya, Manny	(1) engraved plaque for front office door. Name and Title (Norma Sierra, Assistant Principal) for Manny Lozoya								
Sandra Mora									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
37617					8/31/2008		184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:35 AM					
Ramirez, Joe	Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
Margret Villalobos									
37618					8/31/2008		184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:35 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual MCD - Refer to PM schedule details.								
Margret Villalobos									
37619					8/31/2008		184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos									
37620					8/31/2008		184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual UCD - Refer to PM schedule details.								
Margret Villalobos									
37621					8/31/2008		184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual UCS2 - Refer to PM schedule details.								
Margret Villalobos									
37622					8/31/2008		184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.								
Margret Villalobos									
37623					8/31/2008	9/8/2008	184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
37624					8/31/2008		184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.								
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
37625					8/31/2008		184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual EVS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37626					8/31/2008	9/6/2008	184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37627					8/31/2008	9/8/2008	184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38210					9/18/2008		166		\$0.00
Medium	Work In Progress			9/18/2008 9:18:18 AM					
Sotelo, Enrique	marquee lights not working.								
<u>Joe Ramirez</u>									
38537					9/30/2008		154		\$0.00
Medium	Work In Progress			9/30/2008 12:26:03 AM					
Ramirez, Joe	Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38881					10/5/2008	10/11/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:40 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38882					10/5/2008	10/13/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:41 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38883					10/5/2008	10/13/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:41 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38884					10/5/2008	10/13/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:41 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
38885					10/5/2008	11/5/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:42 AM					
Ramirez, Joe	Yearly - Mesquite ES I-4 Fan Coil Unit Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38886					10/5/2008	11/5/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:42 AM					
Ramirez, Joe	Yearly - Mesquite ES H-6 Rooftop Furnance Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38887					10/5/2008	11/5/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:42 AM					
Ramirez, Joe	Yearly - Mesquite ES R-9 Rad Hot Water 2 years - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38888					10/5/2008	11/5/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:43 AM					
Ramirez, Joe	Yearly - Mesquite ES U-2 Unit Heater Gas Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38889					10/5/2008	10/21/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:43 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39519					10/27/2008		127		\$0.00
Medium	Work In Progress			10/27/2008 3:11:39 PM					
Ramirez, Joe	GRASS IS GROWING IN DRAIN GRID BY BUS TURN AROUND.								
<u>Michael Munoz</u>									
39692					11/2/2008	11/8/2008	121		\$0.00
Medium	Work In Progress			11/2/2008 12:24:35 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39724					11/2/2008	11/10/2008	121		\$0.00
Medium	Work In Progress			11/2/2008 12:24:47 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
39734					11/2/2008	11/10/2008	121		\$0.00
Medium	Work In Progress			11/2/2008 12:24:50 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
40256					11/20/2008		103		\$0.00
Medium	Work In Progress			11/20/2008 9:34:58 AM					
Lozoya, Manny	file cabinet in rm 405 needs a new lock installed the other was damaged.								
<u>Joe Ramirez</u>									
41227	Main Building	Classroom			1/7/2009		55		\$0.00
Medium	Work In Progress	Room # 203		1/7/2009 8:59:31 AM					
Lozoya, Manny	Key is needed for Pamela Uribe IA to that classroom.								
<u>Sandra Mora</u>									
41305		Classroom			1/9/2009		53		\$0.00
Medium	Work In Progress			1/9/2009 8:12:50 AM					
Lozoya, Manny	Rm 608 (Wendy Tow) - Door continues to stick, even after it has been fixed.								
<u>Joe Ramirez</u>									
41567					1/16/2009		46		\$0.00
Medium	Work In Progress			1/16/2009 9:32:05 AM					
Ontiveros, Joe	outside drinking fountain one bubbler missing the other one doesn't work need to be replaced.								
<u>Joe Ramirez</u>									
41690	Main Building	Classroom			1/21/2009		41		\$0.00
Medium	Work In Progress	Room # 203		1/21/2009 10:37:15 AM					
Lozoya, Manny	Pamela Uribe IA needs key we don't have another in key box for that room.								
<u>Sandra Mora</u>									
41977					1/29/2009		33		\$0.00
High	Work In Progress			1/29/2009 8:14:01 AM					
Gonzalez, Salvador	covers to lift station are rusty and old and need replacement ASAP. safty thxs								
<u>Michael Munoz</u>									
42308					2/6/2009		25		\$0.00
Medium	Work In Progress			2/6/2009 9:31:18 AM					
Ontiveros, Guadalupe	trees in front of school need to be pruned. mr. sedillo talked to mike about this.								
<u>Joe Ramirez</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
43112					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:59 AM					
Orozco, Danny	Yearly - Mesquite ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43184					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:23 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43185					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:24 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43186					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:24 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
43187					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:24 AM					
Ramirez, Joe	Yearly - Mesquite ES A-10 HP Rooftop Yearly - Refer to PM schedule details.								
Margret Villalobos									
43188					3/1/2009	3/22/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:25 AM					
Ramirez, Joe	Monthly - Mesquite ES C-12 Chem Feeder Semimonthly - Refer to PM schedule details.								
Margret Villalobos									
Count: 55 Work Orders		Avg. Age of WO's	148	Total for Mesquite ES				0	\$0.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
43113					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:59 AM					
Orozco, Danny	Yearly - North Valley ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36463		Office			8/1/2008		214		\$0.00
Medium	Work In Progress	room 400		8/1/2008 11:44:39 AM					
Lozoya, Manny	Hello Manny,								
	The alarm box key was broken off, please replace.								
<u>Priscilla Martinez</u>									
37136		Office			8/18/2008		197		\$0.00
Medium	Work In Progress	video		8/18/2008 10:18:19 AM					
Lozoya, Manny	could not locate a key					Need a black box located in our office to be opened, could not locate the correct key in our vault			
Priscilla Martinez									
37221		Classroom			8/20/2008		195		\$0.00
Medium	Work In Progress	various		8/20/2008 9:15:00 AM					
Lozoya, Manny	Send Lozoya to make various keys for various classrooms, desks, cabinets, filing cabinets, storage closets,					please visit the front office for this list of keys that are needed, thanks Priscilla			
<u>Priscilla Martinez</u>									
38084		Classroom			9/15/2008		169		\$0.00
Medium	Work In Progress			9/15/2008 1:35:12 PM					
Lozoya, Manny	need a key made for Larry Roybal (Deputy Dona Ana County Sheriff) for the gates at North Valley Elementary								
<u>Priscilla Martinez</u>									
38743					10/5/2008		149		\$0.00
Medium	Work In Progress			10/5/2008 12:23:50 AM					
Holguin, Alfredo	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.					10/6/08 - Emailed to Ricky Borrego			
<u>Margret Villalobos</u>									
39280					10/20/2008		134		\$0.00
Medium	Work In Progress			10/20/2008 9:11:35 AM					
Lozoya, Manny	need new pad lock for bus exit gate/had to cut old lock this morning-key didnt turn core								
<u>Danny Vega</u>									
39383					10/22/2008		132		\$0.00
Medium	Work In Progress			10/22/2008 1:41:03 PM					
Lozoya, Manny	p.e coaches office door will not open -core will not turn with key-please ck out asap								
<u>Danny Vega</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
39456		Classroom			10/24/2008		130		\$0.00
Medium	Work In Progress	room 210			10/24/2008 12:13:11				
Lozoya, Manny		black file cabinet w/blue sticker does not lock.							
Priscilla Martinez									
39804					11/4/2008		119		\$0.00
Medium	Work In Progress				11/4/2008 9:20:53 AM				
Lozoya, Manny		need key made for rm 304 art rm/cabinet key broke in core-need to lock-up supplys asap							
Danny Vega									
40891					12/16/2008		77		\$0.00
Medium	Work In Progress				12/16/2008 8:10:47 AM				
Lozoya, Manny		need duplicate from rm 306/cabinet keys- parent center (402) has 01 and 06 key locks-need to give rm 402 a 06 key							
Danny Vega									
41151					1/4/2009		58		\$0.00
Medium	Work In Progress				1/4/2009 12:19:23 AM				
Holguin, Alfredo		Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.				1/6/09 - E-mailed to ricky.borrego@cummins.com'			
Margret Villalobos									
42695					2/19/2009		12		\$0.00
Medium	Work In Progress				2/19/2009 8:14:21 AM				
Holguin, Alfredo		Rm 201 - Unit was changed out and is still going out on Hi/low pressure cutout.				This work order is for Trane.			
Lorenzo Solis									
42737					2/20/2009		11		\$0.00
Medium	Work In Progress				2/20/2009 8:28:56 AM				
Holguin, Alfredo		Rm 101 - Unit going out on Hi/low pressure cutout.							
Lorenzo Solis									
42746					2/20/2009		11		\$0.00
Medium	Work In Progress				2/20/2009 11:58:00 AM				
Estrada, Jesus		need a new gas blower							
Javier Parra									
42919					2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 11:28:26 AM				
Carrasco, Danny		Danny need to conduct inventory of all Building Mechanic tools and equipment. Ask Ruben for present inventory list to match up.							
Michael Munoz									
42926					2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 12:11:06 PM				
Carbajal, Jimmy		vacum cleaner making a really loud noise							
Javier Parra									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
42940		Cafeteria			2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 3:22:04 PM					
Orozco, Danny	Walk-In Freezer is at 25 degrees - I called Danny at 1:13 to inform him of work order								
	Eva Miranda - SNP Manager 233-3658								
Alma Terrell									
43129					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:04 AM					
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
43131					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:05 AM					
Vega, Danny	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43133					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:06 AM					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43135					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:06 AM					
Vega, Danny	Yearly - North Valley ES A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
Count: 22 Work Orders			Avg. Age of WO's	74	Total for North Valley ES			0	\$0.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Northern On-Track Pre-K (LM)							
35704					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:09 AM					
Villalobos, David		Yearly - Northern Pre-K (LM) Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
37774		Athletic Field			9/4/2008		180		\$0.00
Medium	Work In Progress			9/4/2008 8:52:16 AM					
Lozoya, Manny		send us the lock and chain to secure the west gate							
Gilbert Trujillo									
37775	Main Building	Restroom (Girls)			9/4/2008		180		\$0.00
Medium	Work In Progress	classroom 114		9/4/2008 9:33:49 AM					
Lozoya, Manny		Bathroom door in the baby room won't close.							
Concepcion Montalvo									
39602	Pump House	Pump House			10/30/2008		124		\$0.00
Medium	Work In Progress			10/30/2008 9:07:18 AM					
Lozoya, Manny		please change lock back to original lock on irrigation well thanks							
Ricardo Jacquez									
39905		Restroom (Boys)			11/6/2008		117		\$0.00
Medium	Work In Progress			11/6/2008 10:29:38 AM					
Lozoya, Manny		alma de valle restroom door need to be worked on.							
Gilbert Trujillo									
40019	Main Building	Classroom			11/12/2008		111		\$0.00
Medium	Work In Progress			11/12/2008 8:35:22 AM					
Sotelo, Enrique		classroom plug switch is shorted out.room 112							
Gilbert Trujillo									
41981	Cafeteria				1/29/2009		33		\$0.00
Medium	Work In Progress			1/29/2009 8:40:25 AM					
Carrasco, Danny		please pick-up shelving that belongs to gms and deliver to sunland carpentry, so they can make adjustments for installation at loma linda. as per ida garcia and phillip medina							
Michael Munoz									
42261	Main Building				2/5/2009		26		\$0.00
Medium	Work In Progress			2/5/2009 8:58:11 AM					
Ontiveros, Guadalupe		we have 3 broken sprinklers in the soccer field.							
Gilbert Trujillo									
42663		Football Field			2/18/2009		13		\$0.00
Medium	Work In Progress			2/18/2009 10:49:42 AM					
Ontiveros, Guadalupe		drip sprinkler pipe top is broken new tree area.							
Gilbert Trujillo									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
42974	Main Building	Elevator			2/26/2009		5		\$0.00
Medium	Work In Progress				2/26/2009 11:30:06 AM				
Lozoya, Manny		we need 1 master key for alma del valle day care							
Gilbert Trujillo									
43130					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:05 AM				
Vega, Danny		Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
43132					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:05 AM				
Vega, Danny		Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
43134					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:06 AM				
Vega, Danny		Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
Count: 13 Work Orders		Avg. Age of WO's	80		Total for Northern On-Track Pre-K (LM)		0		\$0.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
35707					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:10 AM					
Villalobos, David	Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36213	Maintenance				7/25/2008		221		\$0.00
Medium	Work In Progress			7/25/2008 10:15:21 AM					
Sotelo, Enrique	please install electrical outlet to cooling duct fan and pilot switch. Thxs								
<u>Michael Munoz</u>									
36291					7/28/2008		218		\$0.00
Medium	Work In Progress			7/28/2008 3:26:53 PM					
Ronquillo, Ruben	Purchase a new water tank								
<u>Alfredo Holguin</u>									
36355	Food Services	Parking Lot			7/30/2008		216		\$0.00
Medium	Work In Progress	SNP		7/30/2008 12:01:33 PM					
Ontiveros, Guadalupe	AS PER MR. GIOVAS-IF NEAR THE WAREHOUSE GOING FROM THE SHADED AREA TO THE STAIR WAY INTO THE WAREHOUSE IF THEY CAN LEVEL OUT THE PATH WAY. (PLEASE SEE JOHNNY L. IF NEED DIRECTION.)								
<u>Mary Garcia</u>									
36759	Maintenance				8/7/2008		208		\$0.00
Medium	Work In Progress			8/7/2008 9:53:28 AM					
Munoz, Michael	Need price quote to build an architect table for Tech's Office.								
<u>Michael Munoz</u>									
37767					9/4/2008		180		\$0.00
Medium	Work In Progress			9/4/2008 8:02:44 AM					
Lozoya, Manny	need to replace door lock on water department office does not lock thanks								
<u>Ricardo Jacquez</u>									
37791	Purchasing				9/4/2008		180		\$0.00
Medium	Work In Progress			9/4/2008 2:35:30 PM					
Sotelo, Enrique	I would like to have a light switch in my office to control the lights. Currently the switch is in the hall and the one switch controls my office and hallway.								
<u>Vicky Lopez</u>									
37882	Food Services				9/8/2008		176		\$0.00
Medium	Work In Progress			9/8/2008 8:10:34 AM					
Ontiveros, Guadalupe	Need to add Crusher fines to dock area.								
<u>Alfredo Holguin</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
37944					9/9/2008		175		\$0.00
Medium	Work In Progress			9/9/2008 12:13:23 PM					
Gonzalez, Salvador		PLEASE MAKE SCRAPERS/DRAGERS. PLEASE SEE MIKE.							
Michael Munoz									
39941					11/7/2008		116		\$0.00
Medium	Work In Progress			11/7/2008 1:06:01 PM					
Ontiveros, Guadalupe		Gooseneck Trailers 2 ea. - Replace damaged floor boards							
Alfredo Holguin									
39986		Pump House			11/11/2008		112		\$0.00
Medium	Work In Progress			11/11/2008 9:16:37 AM					
Jacquez, Ricardo		need to calibrate flow meters at GMS,GHS,CMS & SRE thanks							
Ricardo Jacquez									
41518	Food Services	Cafeteria			1/15/2009		47		\$0.00
Medium	Work In Progress			1/15/2009 9:29:05 AM					
Moncayo, Fernando		WORK ORDER FOR GADSDEN STUDENT NUTRITION PROGRAM WAREHOUSE - -- MOTOR WENT OUT TO THE FURNACE							
		JOHNNY LECHUGA - SNP WAREHOUSE MGR 882-6927							
Alma Terrell									
41915					1/27/2009		35		\$0.00
Medium	Work In Progress			1/27/2009 4:07:07 PM					
Gonzales, Angel		Mail Van - driver side seat needs additional padding call Alfredo Holguin if you have questions							
Alfredo Holguin									
42175		Pump House			2/3/2009		28		\$0.00
Medium	Work In Progress			2/3/2009 8:55:23 AM					
Jacquez, Ricardo		please order water filters for water treatment @ GHS & GMS Thanks							
Ricardo Jacquez									
42215	Maintenance				2/4/2009		27		\$0.00
Medium	Work In Progress			2/4/2009 8:52:47 AM					
Sotelo, Enrique		Need to remove electrical from old HVAC Shop.							
Manny Lozoya									
42228	Maintenance				2/4/2009		27		\$0.00
Medium	Work In Progress			2/4/2009 1:23:11 PM					
Miranda, Danny		FRAME AND FURR MAINT.WHS. OPENING TO PLUMBING DANNY MIRANDA							
Danny Carrasco									

3/3/2009 12:02:23 PM

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
42234	Maintenance				2/4/2009		27		\$0.00
Medium	Work In Progress				2/4/2009 3:22:07 PM				
Lozoya, Manny	NEED TO INSTALL BARREL BOLT ON PLUMB. EXIT DOUBLE DOOR								
Ruben Ronquillo									
42264	Maintenance				2/5/2009		26		\$0.00
Medium	Work In Progress				2/5/2009 10:40:01 AM				
Sotelo, Enrique	Need to change bulbs in my office.								
Margret Villalobos									
42336					2/6/2009		25		\$0.00
Medium	Work In Progress				2/6/2009 4:25:43 PM				
Munoz, Michael	need drafting table for tech room.								
Michael Munoz									
42359	Food Services	Electrical Room			2/9/2009		22		\$0.00
Medium	Work In Progress				2/9/2009 8:24:32 AM				
Sotelo, Enrique	need to Relocated swich box where they installed the new door frame. thank you								
Ralph Lara									
42417	Purchasing				2/10/2009		21		\$0.00
Medium	Work In Progress				2/10/2009 11:57:17 AM				
Munoz, Michael	Paper Shredder - Shredder gets jamed when more that one sheet of paper is feed into it.								
Alfredo Holguin									
42670		Custodial			2/18/2009		13		\$0.00
Medium	Work In Progress				2/18/2009 1:13:19 PM				
Carbajal, Jimmy	I need a custodial equipment inventory of all sites.								
Jesus Estrada									
42671		Custodial			2/18/2009		13		\$0.00
Medium	Work In Progress				2/18/2009 1:18:52 PM				
Acuna, Sal	I need a gym supply inventory for Chaparral Middle, Santa Teresa High, Santa Teresa Middle, Gadsden High and Gadsden Middle.								
Jesus Estrada									
42718	Maintenance				2/19/2009		12		\$0.00
Medium	Work In Progress				2/19/2009 3:23:41 PM				
Ronquillo, Ruben	INSTALL PLYWOOD RACK SUPPORTS AT MAINT. WHS. RACKS.								
Ruben Ronquillo									
42911	Purchasing				2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 10:52:35 AM				
Solis, Lorenzo	Need to replace A/C in warehouse thank you								
Sebastian Diaz									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
42915					2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 11:25:40 AM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									
42917					2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 11:26:42 AM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									
42929					2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 12:32:49 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians c tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									
42930					2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 12:35:59 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians c tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									
42931					2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 12:36:53 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									
42932					2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 12:37:43 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									
42933					2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 12:39:11 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: Physical Plant Complex										
43022					2/27/2009		4		\$0.00	
Medium	Work In Progress	Construction			2/27/2009 8:51:56 AM					
Lara, Ralph	Need to issue Ralph Gallegos a key for the Construction Office.									
<u>Juliet Parra</u>										
43053	Purchasing				2/27/2009		4		\$0.00	
High	Work In Progress				2/27/2009 3:20:43 PM					
Carbajal, Jimmy	Jimmy/Sal as per Ms. Browder, she needs the storage where records are stored (ask Tracy Swinford) dusted and swept because GAC personel will be working in there March 6th.									
<u>Jesus Estrada</u>										
43127					3/1/2009		2		\$0.00	
Medium	Work In Progress				3/1/2009 12:23:04 AM					
Orozco, Danny	Yearly - Physical Plant Fire Ext. Insp. (Yearly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43215					3/1/2009	3/7/2009	2		\$0.00	
Medium	Work In Progress				3/1/2009 12:23:34 AM					
Diaz, Sebastian	Monthly - Physical Plant FE Inspection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
43238	Purchasing				3/2/2009		1		\$0.00	
Medium	Work In Progress				3/2/2009 3:34:25 PM					
Acuna, Sal	DURING SPRING BREAK NEED TO: (1) STRIP & WAX ALL AREAS INCLUDING THE RESTROOM. (2) VACUUM & SHAMPOO ALL OFFICE & ENTRY WAY CARPETS.									
<u>Vicky Lopez</u>										
Count: 37 Work Orders		Avg. Age of WO's 66		Total for Physical Plant Complex				0	\$0.00	

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
35708					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:10 AM					
Villalobos, David		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
37820					9/5/2008		179		\$0.00
Medium	Work In Progress			9/5/2008 8:39:36 AM					
Gonzalez, Salvador		Need to make a canopy for behind of cafeteria.							
Michael Munoz									
39543					10/28/2008		126		\$0.00
Medium	Work In Progress			10/28/2008 1:28:41 PM					
Lozoya, Manny		remove lock from the flashing lights -							
Cora Ramirez									
39660					10/31/2008		123		\$0.00
Medium	Work In Progress			10/31/2008 3:06:06 PM					
Lara, Ralph		needs parts for handicap automatic door opener westside door							
Carlos Hernandez									
40264					11/20/2008		103		\$0.00
Medium	Work In Progress			11/20/2008 3:11:28 PM					
Gonzales, Angel		truck seat needs repair truck #21							
Carlos Hernandez									
40877		Cafeteria			12/15/2008		2	1	\$25.00
Medium	Work In Progress			12/15/2008 3:27:13 PM		12/17/2008			
Moncayo, Fernando		alarm showing dirty duct in cafeteria and dirty 2, 16				12/17/08 ck Dimar Report was showing exhaust fan in kitchen alarm. Ck inside and it reflects to kitchen equip, route to Fernie.			
Carlos Hernandez		- J. Ambriz							
40950					12/17/2008		76		\$0.00
Medium	Work In Progress			12/17/2008 3:08:54 PM					
Moncayo, Fernando		range hood systems exhaust fan not operating							
Carlos Hernandez									
42669					2/18/2009		13		\$0.00
Medium	Work In Progress			2/18/2009 1:11:51 PM					
Villalobos, David		need 7 new water fountain heads for water fountains outside need to be replaced							
Carlos Hernandez									
42704					2/19/2009		12		\$0.00
Medium	Work In Progress			2/19/2009 11:44:21 AM					
Carbajal, Jimmy		vaccum not working , needs service							
Jesus Estrada									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
42801	New Wing 1/02				2/23/2009		8		\$0.00
Medium	Work In Progress			2/23/2009 2:58:23 PM					
Castillo, Carlos		need new switch for heater room 104							
Carlos Hernandez									
42910		Cafeteria			2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 10:52:33 AM					
Moncayo, Fernando		Milk Cooler needs a Longer Hose							
Emilia Carrillo		- SNP Manager 589-2550							
Alma Terrell									
43025		Cafeteria			2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 9:53:45 AM					
Moncayo, Fernando		VEGETABLE SINK CLOGGED UP							
EMILIA C. SNP MGR		589-2550							
Jacqueline Aguilar									
43046					2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 3:11:22 PM					
Orozco, Danny		NEED LIFT TO RESTRING FLAGPOLE							
Carlos Hernandez									
43078					2/28/2009		3		\$0.00
Medium	Work In Progress			2/28/2009 12:19:58 AM					
Hernandez, Carlos		Monthly - Riverside ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.							
Margret Villalobos									
43091					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:51 AM					
Hernandez, Carlos		Monthly - Riverside ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
43092					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:51 AM					
Hernandez, Carlos		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
43093					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:52 AM					
Hernandez, Carlos		Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Riverside ES							
43094					3/1/2009		2		\$0.00
Medium	Work In Progress				3/1/2009 12:22:52 AM				
Hernandez, Carlos	Yearly - Riverside ES A-10 HP Rooftop Yearly - Refer to PM schedule details.								
Margret Villalobos									
43114					3/1/2009		2		\$0.00
Medium	Work In Progress				3/1/2009 12:22:59 AM				
Orozco, Danny	Yearly - Riverside ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
Count: 19 Work Orders			Avg. Age of WO's	48		Total for Riverside ES	1	\$25.00	

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		San Miguel ES								
37343					8/22/2008		193		\$0.00	
Medium	Work In Progress			8/22/2008 3:24:23 PM						
Lozoya, Manny	Asp Mike, please core back to GM 6 or 7 pin.									
Michael Munoz										
39334		Portables			10/21/2008		133		\$0.00	
Medium	Work In Progress			10/21/2008 11:17:54						
Estrada, Jesus	Please re-carpet dbl portable northwest corner mescalero.Thxs(#42/goose)		1/12/09 - PENDING AS OF TODAY PER CHUY							
Michael Munoz										
39565	Main Building				10/29/2008		125		\$0.00	
Medium	Work In Progress			10/29/2008 7:32:46 AM						
Lozoya, Manny	please change cores to where the techs can have access to the back door of the boiler room so they can service equipment.									
Michael Munoz										
42935					2/25/2009		6		\$0.00	
Medium	Work In Progress			2/25/2009 1:18:24 PM						
Vega, Danny	Just to let you know that Mr. Sanjay Mathur with Avance, wants to schedule to go to San Miguel School on Friday (2/27/09) @ 11:30am. Can you please have someone open for him.									
	Note: Okay as per Mr. Richard G. Chavez									
Mary Garcia										
Count: 4 Work Orders	Avg. Age of WO's 114		Total for San Miguel ES				0	\$0.00		

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
35713					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:12 AM					
Villalobos, David	Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
37139					8/18/2008		197		\$0.00
Medium	Work In Progress			8/18/2008 11:44:10 AM					
Castillo, Carlos	CALI; HAND DRYER IN BOYS RRM. DOES NOT SHUT OFF AT TIMES, AND SOMETIMES STARTS BY ITSELF. NEED FOR YOU TO CHECK IT OUT. I TURNED THE BREAKER OFF , BECAUSE A STUDENT BURNED HIMSELF ON IT AND REPORTED IT TO THE OFFICE.								
Gerardo Marquez									
39918	Main Building	Restroom (Girls)			11/6/2008		117		\$0.00
Medium	Work In Progress	ladies restroom		11/6/2008 3:11:24 PM					
Marquez, Gerardo	Large spacing in between the wall and other toilet partition needs to be covered. The gap is large enough to see other people inside the stall. Thank you.								
Rita Mendez									
41235		Cafeteria			1/7/2009		55		\$0.00
Medium	Work In Progress			1/7/2009 10:45:02 AM					
Moncayo, Fernando	NEED DOOR BELL FOR BACK DOO (DELIVERY) PAT SANCHEZ STE SNP MGR 589-3439								
Jacqueline Aguilar									
41278		Classroom			1/8/2009		54		\$0.00
Medium	Work In Progress	RM 102		1/8/2009 3:18:53 PM					
Marquez, Gerardo	NEED RACK FOR JACKETS TO SET UP IN CLASSROOM 102								
Rita Mendez									
41990					1/29/2009		33		\$0.00
Medium	Work In Progress			1/29/2009 1:38:38 PM					
Moncayo, Fernando	FERNIE; THE HANDWASHING STATIONS IN THE CAFET. PREP AREA ARE BOTH RUNNING CONTINUOUSLY. WOULD YOU PLEASE CORRECT THE PROBLEM.								
Gerardo Marquez									
42406	Main Building	Hallway/Corridor			2/10/2009		21		\$0.00
Medium	Work In Progress	hallway		2/10/2009 9:38:34 AM					
Marquez, Gerardo	4 large bulleting boards need to be set up in the hallways. need assistance in setting them up due to the size of board. thanks.								
Rita Mendez									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
42521					2/12/2009		19		\$0.00
Medium	Work In Progress			2/12/2009 11:03:36 AM					
Ontiveros, Guadalupe		LUPE, AS PER OUR CONVERSATION ON 2/12/09. WE NEED TO HAVE THE S. W. CORNER OF THE FENCE THAT THE CONTRACTOR STATED TO REMOVE PUT BACK UP.							
Gerardo Marquez									
42554	Main Building	Classroom			2/13/2009		18		\$0.00
Medium	Work In Progress	CASA AZUL		2/13/2009 11:09:02 AM					
Ronquillo, Ruben Rita Mendez		FIRE ALARM PULLS NEED COVERS. THANKS.				MARGRET; THE PORTABLES HAVE THIS TYPE OF COVER. I THINK THAT THE SAME KIND WILL WORK FOR THE CLASSROOMS.			
						THIS IS THE INFO. ON THOSE COVERS. STOPPER 11			
						PULL STATION PROTECTION			
						MODEL ST 11100			
						MFG. BY SAFETY TECHNOLOGY			
						2306 AIRPORT RD.			
						WATERFORD MICH. 48327.			
42558	Main Building	Classroom			2/13/2009		18		\$0.00
Medium	Work In Progress	RM 201		2/13/2009 11:42:55 AM					
Ronquillo, Ruben		RM 201 NEEDS A COVER FOR FIRE ALARM PULL. THANKS							
Rita Mendez									
42672	Main Building	Parking Lot			2/18/2009		13		\$0.00
Medium	Work In Progress	FENCE		2/18/2009 1:21:13 PM					
Ronquillo, Ruben		NEED 2 SIGNS TO SAY: NOT A STUDENT DROP OFF. THESE SIGNS NEED TO BE POSTED AT FACULTY PARKING LOT ENTRANCE. NEED SIGNS TO BE BIG ENOUGH TO BE VISIBLE. THANKS.							
Rita Mendez									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
42920		Cafeteria			2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 11:29:20 AM					
Carbajal, Jimmy		Vacuum needs handle and a tune up.							
Pablo Diaz									
42921					2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 11:29:28 AM					
Carrasco, Danny		Danny need to conduct inventory of all Building Mechanic tools and equipment. Ask Ruben for present inventory list to match up.							
Michael Munoz									
42966		Cafeteria			2/26/2009		5		\$0.00
Medium	Work In Progress			2/26/2009 9:00:34 AM					
Carbajal, Jimmy		Vacuum needs tune up and a handle.							
Pablo Diaz									
43034		Cafeteria			2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 11:34:10 AM					
Moncayo, Fernando		OVEN NOT HEATING.							
		PAT SANCHEZ STE MGR 589-3439							
Jacqueline Aguilar									
43115					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:00 AM					
Orozco, Danny		Yearly - Santa Teresa ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
43147					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:11 AM					
Marquez, Gerardo		Yearly - Santa Teresa ES A-10 HEAT PUMPS (ANNUAL) - Refer to PM schedule details.							
Margret Villalobos									
43148					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:11 AM					
Marquez, Gerardo		Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.							
Margret Villalobos									
43149					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:11 AM					
Marquez, Gerardo		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Santa Teresa ES							
43150					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:12 AM				
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43151					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:12 AM				
Marquez, Gerardo	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 21 Work Orders		Avg. Age of WO's	39	Total for Santa Teresa ES				0	\$0.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
35552					7/6/2008	7/12/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:19:21 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
35569					7/6/2008	7/14/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:19:26 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
35666					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:19:56 AM					
Nunez, Arturo		Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35689					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:04 AM					
Nunez, Arturo		Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35711					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:11 AM					
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36510					8/3/2008	8/9/2008	212		\$0.00
Medium	Work In Progress			8/3/2008 12:20:16 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
37386					8/26/2008		189		\$0.00
Medium	Work In Progress			8/26/2008 7:30:49 AM					
Ontiveros, Guadalupe		Pedestrian Gate on South side that goes to the Bluffs. - Install taller gate to prevent access through bottom of gate.							
Alfredo Holguin									
37545					8/31/2008	9/6/2008	184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:12 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
37958					9/9/2008		175		\$0.00
Medium	Work In Progress			9/9/2008 2:33:14 PM					
Castillo, Carlos	NEED SOME ASSISTANCE ON CHECKING OUTSIDE LIGHTING ON CAF. NEW BUILDING, VOC. BUILDING, AND MAIN BUILDING.								
Arturo Nunez									
38255		Classroom			9/19/2008		165		\$0.00
Medium	Work In Progress	RM 207		9/19/2008 12:14:53 PM					
Ambriz, Jose	Unit is working fine, problem with comm link, need to contact Trane.		Asp Jose Ambriz, need to schedule, when there is no students.						
Jose Ambriz			E-mailed to J. Velasquez 9/19/08						
			Asp Jose, he is going to fix problem. - mkv 2/4/09						
38346					9/23/2008		161		\$0.00
Medium	Work In Progress			9/23/2008 9:02:34 AM					
Ambriz, Jose	THE FOLLOWING F.C.U.'S HAVE A COMMUNICATION PROBLEM BETWEEN MASTER AND SLAVE, 207M SCC IS OF LINE, 205M SCC IS OFF LINE, AND 203 SCC IS IF LINE. CAN WE PLEASE HAVE THEN CHECKED. THANK YOU.								
Arturo Nunez									
38539					9/30/2008		154		\$0.00
Medium	Work In Progress			9/30/2008 12:26:04 AM					
Prospero, Manuel	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								
Margret Villalobos									
38544	Cafeteria (2005)	Cafeteria			9/30/2008		154		\$0.00
Medium	Work In Progress			9/30/2008 8:10:55 AM					
Moncayo, Fernando	Comments from Ecolab Report: Dishwasher is not filling up. Pre-spray hose id damaged & should be replaced. Olga Bustamante SNP MANAGER 58905332								
Jacqueline Aguilar									
38595	Gymnasium				10/1/2008		153		\$0.00
Medium	Work In Progress			10/1/2008 12:31:34 PM					
Nunez, Arturo	REPLACE STAINED AND BROKEN CIELING TILES								
Michael Munoz									
38753					10/5/2008	10/11/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:23:53 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
38754					10/5/2008	10/13/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:23:53 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38755					10/5/2008	10/26/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38756					10/5/2008	11/5/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Yearly - Santa Teresa HS H-6 Rftop Furn Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38757					10/5/2008	11/5/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Yearly - Santa Teresa HS R-9 Radiator Ht Wtr 2yr - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38758					10/5/2008	10/21/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:23:55 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39164					10/12/2008	10/28/2008	142		\$0.00
Medium	Work In Progress			10/12/2008 12:21:05					
Nunez, Arturo	Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39344					10/21/2008		133		\$0.00
Medium	Work In Progress			10/21/2008 3:13:05 PM					
Villalobos, David	NEED SOME ASSISTANCE ON LEAK TEST GAS LINES ON WELDING BOTHS, THERE SEEMS TO BE A GAS LEAK, BUT CAN'T LOCATE.								
<u>Arturo Nunez</u>									
39396	Main Building	Choral			10/22/2008		132		\$0.00
Medium	Work In Progress			10/22/2008 3:57:04 PM					
Lara, Ralph	Door from Band Room Top Corner broken, needs to be replaced Thank you, Rosa								
Rosa Hood									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
39398	Main Building	Hallway/Corridor			10/22/2008		132		\$0.00
Medium	Work In Progress			10/22/2008 3:59:35 PM					
Prospero, Manuel		Remove lockers in hallway near counseling area and across from Main office Thank you, Rosa							
Rosa Hood									
39542	Main Building	Office			10/28/2008		126		\$0.00
Medium	Work In Progress			10/28/2008 1:18:25 PM					
Nunez, Arturo		We need signs to indicate what building is what since we do not have a front entrance. Please feel free to call me or Art Nunez so that we can be more specific Thank you, Rosa				1/23/09 - Art asp our conversation you would take care of it and asp Mike please submit request for signs. - Thank You Ruben			
Rosa Hood									
39695					11/2/2008	11/8/2008	121		\$0.00
Medium	Work In Progress			11/2/2008 12:24:36 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
39730					11/2/2008	11/10/2008	121		\$0.00
Medium	Work In Progress			11/2/2008 12:24:49 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
40365					11/30/2008	12/6/2008	93		\$0.00
Medium	Work In Progress			11/30/2008 12:23:29					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
PSFA View Only									
40425					11/30/2008	12/8/2008	93		\$0.00
Medium	Work In Progress			11/30/2008 12:23:49					
Prospero, Manuel		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
PSFA View Only									
40873					12/15/2008		78		\$0.00
Medium	Work In Progress			12/15/2008 2:57:45 PM					
Castillo, Carlos		NEED A 115V ELEC. OUTLET INSTALLED ON CONFERENCE ROOM IN LIBRARY, FOR POWER POINT PROJECTOR.							
Arturo Nunez									
41042					1/4/2009	1/10/2009	58		\$0.00
Medium	Work In Progress			1/4/2009 12:18:38 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
3/3/2009 12:02:23 PM									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
41059					1/4/2009	1/12/2009	58		\$0.00
Medium	Work In Progress			1/4/2009 12:18:45 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41154					1/5/2009		57		\$0.00
Medium	Work In Progress			1/5/2009 8:52:07 AM					
Villalobos, David	NEED SOME ASSISTANCE ON CHECKING MANHOLE BY GAS METER, ON EAST SIDE. METHANE GAS LEVEL READING IS A 8 , AS PER P.N.M. TECH. WOULD LIKE TO HAVE IT CHECKED OUT.								
<u>Arturo Nunez</u>									
41307	Dressing Rooms	Dressing Room			1/9/2009		53		\$0.00
Medium	Work In Progress			1/9/2009 8:54:39 AM					
Nunez, Arturo	Boys athletic lockers need to be bolted down for safety reasons This is the second request Someone is going to get hurt with a falling bank of lockers		Art Nunez had previously submitted a work order and has spokent to someone at the GAC/Warehouse regarding this situation 1/15 - Route to Art asp Mike						
<u>Rosa Hood</u>									
41316	Main Building	Office			1/9/2009		53		\$0.00
Medium	Work In Progress			1/9/2009 12:47:04 PM					
Estrada, Jesus	Main Office carpet needs to be replaced Carpet is at least 15 years old It is a safety issue - duct tape is holding it together at door entrances Mr. Kelch and Mrs. Hood		Was measured picked color						
<u>Rosa Hood</u>									
41538					1/15/2009		47		\$0.00
Medium	Work In Progress			1/15/2009 3:24:46 PM					
Ambriz, Jose	NEED SOME ASSISTANCE ON CHECKING F.C.U. ON NEW ROOMS MASTER AND SLAVES ARE NOT COMMUNICATING WITH EACH OTHER AND ARE DOING THEIR OWN THING.								
<u>Arturo Nunez</u>									
41629					1/20/2009		42		\$0.00
Medium	Work In Progress			1/20/2009 8:21:41 AM					
Ontiveros, Guadalupe Michael Munoz	Remove equipment asp attached pictures and e-mail.								

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
41699	Gymnasium	Hallway/Corridor			1/21/2009		41		\$0.00
Medium	Work In Progress				1/21/2009 2:21:21 PM				
Prospero, Manuel	Mr. Kelch has asked that we retile the hallway between the old and new gym. He spoke with Manuel Prospero about the tiles (they need to be the same color and pattern) Thank you, Rosa		Mr. Kelch has spoken with Manny Prospero regarding tiles that need to be ordered and changed throughout the building Thank you, Rosa						
<u>Rosa Hood</u>									
41751	Annex Building	Classroom			1/22/2009		40		\$0.00
Medium	Work In Progress				1/22/2009 3:19:52 PM				
Nunez, Arturo	Anchor the serving sets to the ground and need to make a safety zone under the servings Thank you		License inspection 1-15-09 2/9 - Mailed to Art asp Mike						
<u>Rosa Hood</u>									
41752	Annex Building	Classroom			1/22/2009		40		\$0.00
Medium	Work In Progress	DAYCARE			1/22/2009 3:21:49 PM				
Nunez, Arturo	Replace all stained ceiling tiles Thank you, Rosa		License inspection 1-15-09						
<u>Rosa Hood</u>									
41753	Annex Building	Classroom			1/22/2009		40		\$0.00
Medium	Work In Progress				1/22/2009 3:23:59 PM				
Estrada, Jesus	Linolium in both bathrms need to be replaced and floor tiles at each exit need to be replace and any around the day care center Thank you, Rosa		License inspection 1-15-09						
<u>Rosa Hood</u>									
41929		Classroom			1/28/2009		34		\$0.00
Medium	Work In Progress	MR.			1/28/2009 9:21:25 AM				
Nunez, Arturo	NEED TO INSTALL PROJECTION TV-DIGITAL RECORDING SYSTEM-PROJECTION SCREEN-AND TIE IN HD DVD-MULTI CHANNEL AV RECEIVER-STEREO CASSETTE DECK-BBE PROCESSOR. PLEASE VISIT WITH MR. RIVERA ON THESE INSTALLATIONS.								
<u>Jimenez, Marylou</u>									
42057					2/1/2009	2/7/2009	30		\$0.00
Medium	Work In Progress				2/1/2009 12:24:28 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
42262	Main Building	Office			2/5/2009		26		\$0.00
Medium	Work In Progress				2/5/2009 9:16:53 AM				
Lara, Ralph	We need to repair locks on fire proof cabinets in the counseling office that house student records Make an extra set of keys for all cabinet in the counseling center Thank you, Rosa		We have spoken with Rafa (Mr. Lara and Art Nunez)						
Rosa Hood									
42379					2/9/2009		22		\$0.00
Medium	Work In Progress				2/9/2009 1:51:03 PM				
Ambriz, Jose	Need to check chiller, EP Electric did their part already.								
Michael Munoz									
42416	Applied Science	Classroom			2/10/2009		21		\$0.00
Medium	Work In Progress				2/10/2009 11:50:45 AM				
Lara, Ralph	Room 14 Mrs. Hyde needs to be re keyed please Thank you, Rosa		Cleared with Mr. Phelps						
Rosa Hood									
42485	Cafeteria (2005)				2/11/2009		20		\$0.00
Medium	Work In Progress				2/11/2009 2:17:51 PM				
Villalobos, David	need to send Horizon Mechanical to repair backlow preventer for irrigation, located next to cafetorium,								
David Villalobos									
42595	Main Building	Classroom			2/17/2009		14		\$0.00
Medium	Work In Progress				2/17/2009 8:08:27 AM				
Nunez, Arturo	Room 200 has a leak The ceiling tile has already caved in Thanks, Rosa		Art and Prospero have been made aware according to teacher Ms. Rios on Friday Thanks, Rosa						
Rosa Hood									
42596	Gymnasium	Hallway/Corridor			2/17/2009		14		\$0.00
Medium	Work In Progress				2/17/2009 8:11:02 AM				
Ronquillo, Ruben	Glass was broken side panels of door by ramp They were replaced with plexi glass instead of glass Thank you, Rosa		Mr. Kelch wants all windows replaced with glass instead of plexi glass						
Rosa Hood									
42698	Vocational	Classroom			2/19/2009		12		\$0.00
Medium	Work In Progress				2/19/2009 8:41:00 AM				
Castillo, Carlos	Mr. Angelo needs -install powere cords on 2 new machines with correct plugs-change to 208 voltage from previous setting new thermo 251 new thermo 52 plasma ...								
Rosa Hood									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
42747	Gymnasium	Athletic Field			2/20/2009		11		\$0.00
Medium	Work In Progress				2/20/2009 1:37:36 PM				
Ontiveros, Guadalupe	A batting cage has been donated by Franklin High School I have emailed Mr. Munoz, Mr. Ontiveros, and Mr. Holguin The contace person at STHS is coach Gilbert Bailon Thank you, Rosa								
Rosa Hood									
42793	Main Building	Classroom			2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 11:33:13 AM				
Nunez, Arturo	Mr. Portillo's room needs door stops for bathroom and air freshner dispensers need to be mounted Thank you, Rosa								
Rosa Hood									
42794	Main Building	Restroom (Girls)			2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 11:35:20 AM				
Nunez, Arturo	Air freshners need to be mounted in the women restroom in the main office Next to Receptionist Ana Perez Thank you, Rosa								
Rosa Hood									
42795	Main Building	Restroom (Girls)			2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 11:36:51 AM				
Prospero, Manuel	All boys and girls restrooms need to be painted. They are now black and we need the natural color (white, beige, whatever you have in stock) Thank you, Rosa								
Rosa Hood									
42796	Main Building	Hallway/Corridor			2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 11:38:36 AM				
Nunez, Arturo	All entry ways, door frames, window frames need to be painted black per Mr. Kelch our principal Mr. Munoz, Art Nunez, and Manuel Prospero are aware Thank you, Rosa								
Rosa Hood									
42807					2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 3:41:55 PM				
Castillo, Carlos Arturo Nunez	NEED SIX (6) FNR-50 FUSES FOR KILN.								

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

42810					2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 3:47:24 PM				
Ambriz, Jose	NEED A L.C.D. PAD FOR CHILLER CIRCULATING PUMP, THE ON THERE IS BLANK, I ALREADY REPLACED BATTERY. INFO : ABB OY , ACH-CP-B , SN 417CO271.								
Arturo Nunez									
42811					2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 3:48:44 PM				
Lara, Ralph	NEED A DOOR CLOSER FOR NURSES STATION PORTABLE.								
Arturo Nunez									
42839	Main Building	Classroom			2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 1:42:45 PM				
Nunez, Arturo	ceiling tiles need to be replace in room 200 Ms. Rios								
	Thanks, Rosa								
Rosa Hood									
42841	Main Building	Classroom			2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 1:47:07 PM				
Nunez, Arturo	Ms McConnell a few tiles need to be replaced								
	Thanks, Rosa								
Rosa Hood									
42843	Main Building	Office			2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 1:52:40 PM				
Nunez, Arturo	Leak in counseling office and rusted vents need to be replaced								
	Thank you, Rosa								
Rosa Hood									
42844	Main Building	Office			2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 1:53:40 PM				
Nunez, Arturo	Counseling offices and lobby area need to be painted								
	Thank you, Rosa								
Rosa Hood									
42845	Main Building	Office			2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 1:54:50 PM				
Castillo, Carlos	Counseling offices need more outlets								
	Thank you, Rosa								
Rosa Hood									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
42846	Main Building	Office			2/24/2009		7	1	\$25.00
Medium	Work In Progress				2/24/2009 1:56:20 PM				
Estrada, Jesus		Counseling Center needs carpet replaced in lobby and in offices. (dirty and safety issue)				2/26/08 NO TEAR OR STAIN, ON HOLD AS PER CHUY			
Rosa Hood		Thanks, Rosa							
42869	Cafeteria (2005)	Choral			2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 4:01:56 PM				
Prospero, Manuel		Wall closet has hole in it since last year that needs to be repaired							
Rosa Hood		Thanks, rosa							
42870	Main Building	Classroom			2/24/2009		7		\$0.00
Medium	Work In Progress	Daycare			2/24/2009 4:04:50 PM				
Villalobos, Margret		Daycare center needs to be fumigated .construciton of parking lot has caused with black widow and otehr insects							
Rosa Hood		Thanks, Rosa							
42874	Applied Science	Classroom			2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 6:02:00 PM				
Nunez, Arturo		L 1 needs some ceiling tiles replaced							
Rosa Hood		Thank you, Rosa							
42875	Applied Science	Classroom			2/24/2009		7		\$0.00
Medium	Work In Progress				2/24/2009 6:03:23 PM				
Nunez, Arturo		L1 needs screens on windows replaced							
Rosa Hood		Ms McKnight Thanks, Rosa							
42897	Gymnasium	Dressing Room			2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 8:45:54 AM				
Lara, Ralph		Ms. Valdez needs 10 copies of key MD 10 and Mr. Phelps approved the order of the keys							
Rosa Hood		Thanks, Rosa							
42900		Classroom			2/25/2009		6		\$0.00
Medium	Work In Progress	MR. RAY/ROOM			2/25/2009 9:12:29 AM				
Nunez, Arturo		PLEASE REPLACE TV IN MY ROOM. MARYLOU HAS TV'S AVAILABLE.							
Marylou Jimenez									

3/3/2009 12:02:24 PM

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
42901	Applied Science	Classroom			2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 9:26:06 AM					
Ronquillo, Ruben	Plexiglass in room 14 at the back of room needs to be replaced If it is an outside window it needs to be glass Thank you, Rosa								
Rosa Hood									
42902	Applied Science	Classroom			2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 9:27:31 AM					
Nunez, Arturo	Room 14 molding around desk needs to be glued								
Rosa Hood									
42903	Main Building	Classroom			2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 9:39:24 AM					
Nunez, Arturo	Room 308 screens for windows								
Rosa Hood									
42904	Main Building	Classroom			2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 9:40:53 AM					
Prospero, Manuel	Room 308 ceiling tiles need to be replaced -two								
Rosa Hood									
42905	Main Building	Classroom			2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 9:42:00 AM					
Nunez, Arturo	Room 308 needs to be painted during Spring Break or Summer schedule								
Rosa Hood									
42906	Main Building	Restroom (Girls)			2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 9:57:52 AM					
Nunez, Arturo	Handcap bathroom in 300 hall needs to be tightend								
Rosa Hood									
42907	Annex Building	Classroom			2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 10:14:34 AM					
Prospero, Manuel	ceiling tiles need to be replace in the ROTC room before April 2nd for inspection from Milington, TN 5 in room 40 8 in room 41 2 in room 42								
Rosa Hood									
42908		Custodial			2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 10:38:07 AM					
Carbajal, Jimmy	WATER FROM EXTRACTOR WILL NOT SHUT OFF / ADVANCE EXTRACTOR THANKS.								
Luis Murillo									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
42916					2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 11:26:08 AM					
Murillo, Luis	Shampoo and extract carpet in lobby and offices in counseling center. To be done in week of March 23-27. (Assign to L. Murillo)								
Jesus Estrada									
42922					2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 11:30:45 AM					
Carrasco, Danny	Danny need to conduct inventory of all Building Mechanic tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									
42972	Gymnasium	Hallway/Corridor			2/26/2009		5		\$0.00
Medium	Work In Progress			2/26/2009 11:13:17 AM					
Lara, Ralph	The gate located in the gym hallway by the athletic training room will not lock, it is not secure.								
Rosa Hood									
42984	Main Building	Classroom			2/26/2009		5		\$0.00
Medium	Work In Progress			2/26/2009 2:25:07 PM					
Lara, Ralph	213 needs locks replaced on cabinets to secure materials								
Rosa Hood									
43023	Main Building	Classroom			2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 9:11:22 AM					
Nunez, Arturo	I really do not know who this goes to... we are donating four Art racks to different schools we need them moved to those schools Desert View E (2) and STMS (2) Thank you, Rosa								
Rosa Hood									
43033					2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 11:03:22 AM					
Ambriz, Jose	NEED A PUSH BAR FOR AN ELKAY WATER FOUNTAIN AT CAFETERIA LOBBY. HERE IS THE INFO.; MODEL # EZFSTL8 1B, SERIAL # 050614348 , PART # EZSTL8LC.								
Arturo Nunez									
43037	Main Building	Restroom (Girls)			2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 12:59:16 PM					
Lara, Ralph	Office bathrooms men and women Hallway mens need to be keyed so that only faculty can use Hallway womens is already keyed Thank you, Rosa								
Rosa Hood									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
43038	Main Building	Hallway/Corridor			2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 1:01:01 PM					
Ronquillo, Ruben		Fire ex glass is broken New hallway near bookroom							
Rosa Hood									
43040	Main Building	Classroom			2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 2:14:19 PM					
Prospero, Manuel		Tiles need to be repalced room 200 Thank you, Rosa							
Rosa Hood									
43081					3/1/2009	3/17/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:46 AM					
Villalobos, Margret		Yearly - Santa Teresa HS March Chiller Insp. - Refer to PM schedule details.							
Margret Villalobos									
43090					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:51 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
43125					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:03 AM					
Orozco, Danny		Yearly - Santa Teresa HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
43128					3/1/2009	3/22/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:04 AM					
Orozco, Danny		Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
43191					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:26 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
43192					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:26 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Santa Teresa HS										
43193					3/1/2009	4/1/2009	2		\$0.00	
Medium	Work In Progress				3/1/2009 12:23:26 AM					
Prospero, Manuel		Yearly - Santa Teresa HS A-10 HP Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
43194					3/1/2009	4/1/2009	2		\$0.00	
Medium	Work In Progress				3/1/2009 12:23:27 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
43252	Main Building	Hallway/Corridor			3/3/2009		0		\$0.00	
Medium	Work In Progress				3/3/2009 8:07:26 AM					
Lara, Ralph		Mr. Kelch would like the rooms re-numbered for next school year (summer project) Thank you, Rosa								
<u>Rosa Hood</u>										
Count: 96 Work Orders		Avg. Age of WO's 60		Total for Santa Teresa HS				1	\$25.00	

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
35712					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress			7/6/2008 12:20:11 AM					
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36170	North Building	Custodial			7/24/2008		222		\$0.00
Medium	Work In Progress			7/24/2008 7:42:22 AM					
Gonzales, Angel		pete, the truck 39 needs a complete tune up i need to have it ready for the school year. thank you.							
Ismael Rodriguez									
36903	North Building	Classroom			8/11/2008		204		\$0.00
Medium	Work In Progress	Room 3A		8/11/2008 3:12:40 PM					
Mijarez, Jaime		1. Portable leaks when it rains.							
Laura Parra									
37603					8/31/2008	9/6/2008	184		\$0.00
Medium	Work In Progress			8/31/2008 12:25:31 AM					
Mijarez, Jaime		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
37808					9/4/2008		180		\$0.00
Medium	Work In Progress			9/4/2008 4:13:04 PM					
Munoz, Michael		North Bldg. - Build concrete Pad for dumpsters.							
Alfredo Holguin									
38251	Library	Library			9/19/2008		165		\$0.00
Medium	Work In Progress	Ms. Swaim-		9/19/2008 10:10:45 AM					
Castillo, Carlos		Need power strip for the wall. The outlets are overloaded. Wires and cords need to be contained.							
Parra, Laura									
38535					9/30/2008		154		\$0.00
Medium	Work In Progress			9/30/2008 12:26:01 AM					
Mijarez, Jaime		Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.							
Margret Villalobos									
38596					10/1/2008		153		\$0.00
Medium	Work In Progress			10/1/2008 12:33:20 PM					
Soria, Mike		CUT WEEDS AT NEW LANDSCAPING IN FRONT OF SOUTH BUILDING.							
Michael Munoz									
38597					10/1/2008		153		\$0.00
Medium	Work In Progress			10/1/2008 12:34:21 PM					
Soria, Mike		OPEN DRAIN BY MORGAN BUILDING. CUT WEEDS AND BARRICADE. SAFETY HAZARD.							
Michael Munoz									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
38869					10/5/2008	11/5/2008	149		\$0.00
Medium	Work In Progress			10/5/2008 12:24:36 AM					
Mijarez, Jaime	Yearly - Santa Teresa MS U2 (Heat Gas)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39102	North Building	Classroom			10/10/2008		144		\$0.00
Medium	Work In Progress	Room 1		10/10/2008 2:36:56 PM					
Mijarez, Jaime	Hand made wooden case in recognition hall needs to be installed on the wall. The case will need a 2x6 wooden base, plexiglass doors and mounting hardware								
<u>Laura Parra</u>									
39335					10/21/2008		133		\$0.00
Medium	Work In Progress			10/21/2008 12:48:47					
Ambriz, Jose	N.bldg Hp 36 lobby has a bad motor that is making a loud noise.								
<u>Jaime Mijarez</u>									
39406					10/23/2008		131		\$0.00
Medium	Work In Progress			10/23/2008 7:58:22 AM					
Castillo, Carlos	See if we can repair the timers and order additional triggers. (see Jaime if you have any questions).								
<u>Michael Munoz</u>									
40169					11/18/2008		105		\$1,400.00
Medium	Work In Progress			11/18/2008 9:33:58 AM					
Ronquillo, Ruben	N.bldg office exterior windows. Replace 2nd glass window with new aluminum molding. Existing molding is to corroded. Replace aluminum molding around glass window that was replaced for W/O #39295. I checked molding around window and it is too damaged.								
<u>Jaime Mijarez</u>									
40475	South Building	Choral			12/2/2008		91		\$0.00
Medium	Work In Progress	Outside Choir		12/2/2008 8:05:57 AM					
Gonzalez, Salvador	Replace the old worn out gate behind the south building and relocate by the corner of the south building with a new one. (A safety measure)								
<u>Laura Parra</u>									
40476	North Building	Portables			12/2/2008		91		\$0.00
Medium	Work In Progress	Outside by		12/2/2008 8:09:53 AM					
Gonzalez, Salvador	North building by the portable-- Place a gate by the portables so we could keep people from driving their cars around the north building to get to the gym. (A SAFETY MEASURE)								
<u>Laura Parra</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
41024					12/31/2008		62		\$0.00
Medium	Work In Progress				12/31/2008 12:18:22				
Mijarez, Jaime	Yearly - Santa Teresa MS H6(Roof Furnace)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41216	South Building				1/6/2009		56		\$0.00
Medium	Work In Progress				1/6/2009 4:25:30 PM				
Soria, Mike	please cut weeds in culvert by ground morgan bldg.								
<u>Michael Munoz</u>									
41530					1/15/2009		47		\$0.00
Medium	Work In Progress				1/15/2009 2:58:36 PM				
Villalobos, David	Install new septic tank.								
<u>Michael Munoz</u>									
41632	North Building	Custodial			1/20/2009		42		\$0.00
Medium	Work In Progress				1/20/2009 8:39:52 AM				
Gonzales, Angel	pete, the truck 39 needs the the oil change i will be taking it in during this week thank you.								
<u>Ismael Rodriguez</u>									
42093					2/1/2009	3/4/2009	30		\$0.00
Medium	Work In Progress				2/1/2009 12:24:41 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42094					2/1/2009	2/7/2009	30		\$0.00
Medium	Work In Progress				2/1/2009 12:24:42 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42095					2/1/2009	2/9/2009	30		\$0.00
Medium	Work In Progress				2/1/2009 12:24:42 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42096					2/1/2009	2/9/2009	30		\$0.00
Medium	Work In Progress				2/1/2009 12:24:42 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42186	Gym (1997)	Gym			2/3/2009		28		\$0.00
Medium	Work In Progress				2/3/2009 1:28:34 PM				
Villalobos, David	theres a urinal that is overflowing in the boys dressing room . i tried it with a plunger but the problem doesnt seem to work.thank you.								
<u>Ismael Rodriguez</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
42210	North Building	Portables			2/4/2009		27		\$0.00
Medium	Work In Progress				2/4/2009 7:52:53 AM				
Ontiveros, Guadalupe		Lupe can you send a small tractor to clear the sand that is build up around the ramps and stairways of the portables.so can you let us borrow a small tractor and i will help mr. soria. And also along the sidewalks of the northbuilding thank you.							
Ismael Rodriguez									
42477					2/11/2009		20		\$0.00
Medium	Work In Progress	Grounds Truck			2/11/2009 9:23:05 AM				
Gonzales, Angel		Need to repair door to truck #17 Mike Soria.							
Mike Soria									
42478	South Building	Mechanical Room			2/11/2009		20		\$0.00
Medium	Work In Progress				2/11/2009 9:25:27 AM				
Ontiveros, Guadalupe		Need to repair irrigation valve in Mechanical Room.				2/17/09 - Grounds works w/irrigation they need to repair their valves. D. Villalobos			
Mike Soria									
42488		Cafeteria			2/11/2009		20		\$0.00
Medium	Work In Progress				2/11/2009 2:53:01 PM				
Moncayo, Fernando		TOP LEFT HAND BLODGETT OVEN IS NOT HEATING UP							
		PAULA SANCHEZ - SNP MANAGER 589-9836							
Alma Terrell									
42511	South Building	Classroom			2/12/2009		19		\$0.00
Medium	Work In Progress	Choir			2/12/2009 9:06:38 AM				
Lara, Ralph		Door hinge is broken.							
Laura Parra									
42923					2/25/2009		6		\$0.00
Medium	Work In Progress				2/25/2009 11:32:07 AM				
Carrasco, Danny		Danny need to conduct inventory of all Building Mechanic tools and equipment. Ask Ruben for present inventory list to match up.							
Michael Munoz									
42937	North Building	Office			2/25/2009		6		\$0.00
Medium	Work In Progress	Fence Around			2/25/2009 1:45:56 PM				
Ontiveros, Guadalupe		MS. LOVELACE WOULD LIKE TO REQUEST FOR THE SAND TO BE REMOVED AWAY FROM THE FENCE AROUND THE SCHOOL. SAND IS SO HIGH THAT YOU CAN WALK OVER THE FENCE.							
Laura Parra									
43020	Gym (1997)	Athletic Field			2/27/2009		0		\$0.00
High	Work In Progress				2/27/2009 8:40:07 AM	2/27/2009			
Soria, Mike		Replace sprinklers that are not working at playing fields.							
Guadalupe Ontiveros									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
43035					2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 12:41:47 PM					
Estrada, Jesus	North bldg Requested by Philip Dorantes. Special Ed room needs new carpeting due to the constant wear and tear of daily activity, and also due to the foul odor of the constant urination of the students with severe disabilities. The odor has been very noticeable to visiting teachers and administration visits for observation. (5/2/08 Asp Jaime still pending)		2/29/09 - ROUTE TO CHUY ASP MIKE						
Jaime Mijarez									
43120					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:01 AM					
Orozco, Danny	Yearly - Santa Teresa MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43167					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:18 AM					
Mijarez, Jaime	Yearly - Santa Teresa MS A10 (Heat Pump)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43168					3/1/2009	4/1/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:18 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
43169					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:18 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
43170					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:19 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43171					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:19 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43254		Gym			3/3/2009		0		\$0.00
Medium	Work In Progress			3/3/2009 8:26:41 AM					
Soria, Mike	Replace broken hot box to protect reduce pressure assembly.								
Guadalupe Ontiveros									

3/3/2009 12:02:24 PM

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

Count: 41 Work Orders Avg. Age of WO's 73 Total for Santa Teresa MS 0 \$1,400.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Sunland Park ES

35710					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress				7/6/2008 12:20:11 AM				
Villalobos, David	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
37362					8/25/2008		190		\$0.00
Medium	Work In Progress				8/25/2008 2:14:46 PM				
Lara, Ralph	WE NEED REPLACE CLASS ROOMS DOORS THEY ARE TO RUSTING								
Joel Herrera									
38310					9/22/2008		162		\$0.00
Medium	Work In Progress	outside			9/22/2008 2:14:13 PM				
Herrera, Joel	Please replace broken tiles located by the main entrance.								
Jessica Lopez									
38468					9/26/2008		158		\$0.00
Medium	Work In Progress				9/26/2008 1:25:56 PM				
Castillo, Carlos	MS. PEREZ WANTS TWO OUTLETS AT PLAYGROUNDS AREA IF WE CAN DO POSSIBLE. THANK YOU CALI								
Joel Herrera									
38801					10/5/2008	10/26/2008	149		\$0.00
Medium	Work In Progress				10/5/2008 12:24:11 AM				
Orozco, Danny	Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38958					10/6/2008		148	1	\$25.00
Medium	Work In Progress	library			10/6/2008 12:29:14 PM				
Herrera, Joel	Attach electrical strip to new computer cart.				10/24 -NON ELECTRICAL, NEED BM TO OBTAIN A POWER SURGE STRIP AND INSTALL HIMSELF. C. CASTILLO.				
Jessica Lopez					Route to Joel 11/3/08				
39888					11/6/2008		117		\$0.00
Medium	Work In Progress				11/6/2008 8:12:18 AM				
Gonzalez, Salvador	WE NEED REPLACE CONCRET WALL AND STEEL GATE AT OUTSIDE AREA								
Joel Herrera									
40679					12/8/2008		85		\$0.00
Medium	Work In Progress	Cafeteria			12/8/2008 3:30:26 PM				
Moncayo, Fernando	DISHWASHER NEEDS TO BE REPAIRED. NOT WORKING AT ALL.								
Jacqueline Aguilar	MARINA RAMIREZ SNP MGR 589-2545								

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
41299		Cafeteria			1/8/2009		54		\$0.00
Medium	Work In Progress			1/8/2009 4:08:12 PM					
Moncayo, Fernando	Dishwasher is down - System corroded - Not working at all								
	Marina Ramirez - SNP Manager 589-2545								
Alma Terrell									
41300		Cafeteria			1/8/2009		54		\$0.00
Medium	Work In Progress			1/8/2009 4:09:11 PM					
Moncayo, Fernando	Hobart Mixer - Dropping oil and making a grinding sound								
	Marina Ramirez - SNP Manager 589-2545								
Alma Terrell									
41497		Cafeteria			1/14/2009		48		\$0.00
Medium	Work In Progress			1/14/2009 2:24:17 PM					
Moncayo, Fernando	Hose to dishwashing area is all cracked - leaking water everywhere								
	Marina Ramirez - SNP Manager 589-2545								
Alma Terrell									
41960					1/28/2009		34		\$0.00
Medium	Work In Progress			1/28/2009 3:28:44 PM					
Ambriz, Jose	MR. AMBRIZ WE NEED TO REPLACE MASTERCOOLS 65S AT CLASS ROOMS 10, 11, 17 AND 23 THANK YOU JOSE								
Joel Herrera									
42161		Cafeteria			2/2/2009		29		\$0.00
Medium	Work In Progress			2/2/2009 4:00:22 PM					
Moncayo, Fernando	2-compartment Veg. Sink is leaking.								
	Marina Ramirez SNP Mgr 589-2545								
Jacqueline Aguilar									
42235					2/4/2009		27		\$0.00
Medium	Work In Progress			2/4/2009 3:26:24 PM					
Lara, Ralph	WE NEED TO SECURED MALLEN ON SOUTH SIDE EXIT DOOR'S A.S.P THANK YOU RAFA								
Joel Herrera									
42260					2/5/2009		26		\$0.00
Medium	Work In Progress			2/5/2009 8:57:09 AM					
Ontiveros, Guadalupe	LUPE WE NEED TO REPLACE SPRINKLES TIMER IT DOESNT WORK THANK YOU								
Joel Herrera									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
42540		Cafeteria			2/12/2009		19		\$0.00
Medium	Work In Progress			2/12/2009 3:51:46 PM					
Moncayo, Fernando	RECEIVED CALL AT 3:50 PM (HOBART MIXER IS NOT WORKING AT ALL - FERNANDO WENT OVER TODAY TO PUT OIL IN MACHINE AND MARINA SAYS THAT THE MACHINE DOES NOT WORK ANYMORE)								
	MARINA RAMIREZ - SNP MANAGER 589-2545								
<u>Alma Terrell</u>									
42626	Main Building				2/17/2009		14		\$0.00
Medium	Work In Progress	LIBRARY		2/17/2009 2:16:43 PM					
Herrera, Joel	MR. HERRERA PLEASE REMOVE ENFOCUS AND PLACE ON CEILING BRACKET. LOCATION: LIBRARY								
<u>Jessica Lopez</u>									
42827					2/24/2009		7		\$0.00
Medium	Work In Progress	NURSE'S		2/24/2009 8:27:14 AM					
Estrada, Jesus	MR. HERRERA/MIKE MUNOZ LOCATION: NURSE'S OFFICE RESTROOM NEEDS TILE								
<u>Jessica Lopez</u>									
42828					2/24/2009		7		\$0.00
Medium	Work In Progress	PORTABLE A &		2/24/2009 8:34:47 AM					
Estrada, Jesus	MIKE MUNOZ/MR. HERRERA LOCATION: RESTROOM ENTRANCE (PORTABLE A & B) TILES ARE LIFTED DANGEROUS SITUATION								
<u>Jessica Lopez</u>									
42967					2/26/2009		5		\$0.00
Medium	Work In Progress	1		2/26/2009 9:15:01 AM					
Herrera, Joel	PLEASE FIX BOOK SHELF LOCATION: ROOM # 10								
<u>Jessica Lopez</u>									
43015					2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 7:58:21 AM					
Herrera, Joel	I NEED PAINT TO PAINTING G.Y.M AREA AND I NEED PAINT TO PAINTING OUTSIDE CONCRET WALL								
<u>Joel Herrera</u>									
43028					2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 10:18:35 AM					
Herrera, Joel	TILES ON THE FRONT ENTRANCE - MANY ARE BROKEN AND NEED REPLACEMENT.								
Irene Trujillo									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Sunland Park ES									
43029					2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 10:19:54 AM					
Herrera, Joel	THE PLANTERS ON THE FRONT ENTRANCE NEED TO BE PAINTED.								
Irene Trujillo									
43030	Main Building				2/27/2009		4		\$0.00
Medium	Work In Progress			2/27/2009 10:22:10 AM					
Herrera, Joel	2nd request - Tile in nurse's office is not level. Safety hazard concern, as student/staff may possibly trip and be injured.								
Irene Trujillo									
43080					2/28/2009		3		\$0.00
Medium	Work In Progress			2/28/2009 12:19:59 AM					
Herrera, Joel	Monthly - Sunland Park ES A-16 Fan Exh Semiannual - Refer to PM schedule details.								
Margret Villalobos									
43116					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:00 AM					
Orozco, Danny	Yearly - Santa Teresa ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43161					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:16 AM					
Herrera, Joel	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43162					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:16 AM					
Herrera, Joel	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43163					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:16 AM					
Herrera, Joel	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
43164					3/1/2009	3/17/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:17 AM					
Herrera, Joel	Monthly - Sunland Park ES A-1 Wall Ref Semiannual - Refer to PM schedule details.								
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
43165					3/1/2009	3/22/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:17 AM				
Herrera, Joel		Monthly - Sunland Park ES C-12 Chem. Feeder (SA) - Refer to PM schedule details.							
Margret Villalobos									
43166					3/1/2009		2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:17 AM				
Herrera, Joel		Yearly - Sunland Park ES A-10 HP Rooftop Yearly - Refer to PM schedule details.							
Margret Villalobos									
43240					3/2/2009		1		\$0.00
Medium	Work In Progress				3/2/2009 3:42:53 PM				
Gonzalez, Salvador		WE NEED WELD FLAG POST'S HANGER AT MAIN ENTRANCE POSTS							
Joel Herrera									
Count: 33 Work Orders			Avg. Age of WO's	49		Total for Sunland Park ES	1		\$25.00

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
35709					7/6/2008	8/6/2008	240		\$0.00
Medium	Work In Progress				7/6/2008 12:20:10 AM				
Villalobos, David		Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36205					7/25/2008		221		\$0.00
Medium	Work In Progress				7/25/2008 8:27:04 AM				
Lozoya, Manny		CLASSSS RM. 207 DOOR HANDLE,AND LOCK CYLINDER NOT OPENING DOOR PROPERLY. THANKS							
Paul Quinones									
36378					7/30/2008		216		\$0.00
Medium	Work In Progress				7/30/2008 4:19:55 PM				
Lozoya, Manny		DOOR IN WING B ELSOL HALL WAY.DURING FIRE DRILL IN THE MORNING 7-30-08.RIGHT SIDE DOOR WOULD NOT CLOSE DURING DRILL.							
Paul Quinones									
37422					8/26/2008		189		\$0.00
Medium	Work In Progress				8/26/2008 4:19:28 PM				
Ontiveros, Joe		HOSE BIBB ON WALL NEXT TO UPPER PLAY GROUND WATER LEAKING,BROKEN HANDLE.							
Paul Quinones									
38008	Main Building	Classroom			9/10/2008		174		\$0.00
Medium	Work In Progress				9/10/2008 4:02:35 PM				
Lozoya, Manny		Need key # for room 206 1c 32. The key is bent							
Joanne Munoz									
38009	Main Building	Classroom			9/10/2008		174		\$0.00
Medium	Work In Progress				9/10/2008 4:18:59 PM				
Lozoya, Manny		Alma Castillo, testing room estrellita hallway, has a filing cabinet in her room that is locked and we do not have a key for it. CAN a new key be made or reinstall a new lock? Thank you.							
Joanne Munoz									
39872					11/5/2008		118		\$0.00
Medium	Work In Progress				11/5/2008 3:35:43 PM				
Jacquez, Ricardo		REQUESTING WIND SCREEN FOR BACK CHAIN LINK FENCING AREA,LIFT STATION AREAS. BALL PARK FIGURE 200' WILL BE NEEDED @ 4' HIGH THANK YOU VERY MUCH							
Paul Quinones									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
40018		Classroom			11/12/2008		111		\$0.00
Medium	Work In Progress	Parent Room			11/12/2008 8:11:32 AM				
Sotelo, Enrique		Check outlet with built in breaker, in Parent Room, by office, it keeps tripping.							
<u>Joanne Munoz</u>									
40522		Cafeteria			12/3/2008		90		\$0.00
Medium	Work In Progress				12/3/2008 10:00:31 AM				
Orozco, Danny		INSIDE THE WALK-IN REFRIGERATOR FLOOR, THERE IS A PIECE OF METAL THAT IS LIFTING UP.							
		VIRGINIA PRUIT - SNP MANAGER 824-3194							
<u>Alma Terrell</u>									
41164		Classroom			1/5/2009		57		\$0.00
Medium	Work In Progress	102			1/5/2009 2:51:54 PM				
Lara, Ralph		I will need a extra key for our RPT key # 1c38							
<u>Joanne Munoz</u>									
41559					1/16/2009		46		\$0.00
Medium	Work In Progress				1/16/2009 8:17:12 AM				
Sotelo, Enrique		DRYER HANDS BOYS AND GRLS. NEED REPLCE SENSOR NOT WORK							
<u>Juan Vargas</u>									
41786		Lift Station			1/23/2009		39		\$0.00
Medium	Work In Progress				1/23/2009 9:31:44 AM				
Jacquez, Ricardo		please installe air valve on lift station							
<u>Ricardo Jacquez</u>									
42483					2/11/2009		20		\$0.00
Medium	Work In Progress				2/11/2009 1:29:26 PM				
Solis, Lorenzo		need fix cafeteria heating fan not on							
<u>Juan Vargas</u>									
42708					2/19/2009		12		\$0.00
Medium	Work In Progress				2/19/2009 12:58:11 PM				
Lozoya, Manny		room 303 back door need fix lock							
<u>Juan Vargas</u>									
42709					2/19/2009		12		\$0.00
Medium	Work In Progress				2/19/2009 1:02:20 PM				
Lozoya, Manny		entry main need fix handy cop door							
<u>Juan Vargas</u>									
42785		Cafeteria			2/23/2009		8		\$0.00
Medium	Work In Progress				2/23/2009 9:33:26 AM				
Orozco, Danny		kitcken heating need check have problem to star							
<u>Juan Vargas</u>									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
43117					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:00 AM					
Orozco, Danny	Yearly - Sunrise ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43176					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:21 AM					
Vargas, Juan	Yearly - Sunrise ES A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43177					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:21 AM					
Vargas, Juan	Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM schedule details.								
Margret Villalobos									
43178					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:21 AM					
Vargas, Juan	Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM schedule details.								
Margret Villalobos									
43179					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:22 AM					
Vargas, Juan	Monthly - Sunrise ES A-1 Semiannual MCS - Refer to PM schedule details.								
Margret Villalobos									
43180					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:22 AM					
Vargas, Juan	Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details.								
Margret Villalobos									
43181					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:22 AM					
Vargas, Juan	Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.								
Margret Villalobos									
43182					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:23:23 AM					
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Sunrise ES							
43183					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:23 AM				
Vargas, Juan		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
43198					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:28 AM				
Vargas, Juan		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
43209					3/1/2009		2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:32 AM				
Jacquez, Ricardo		Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.							
Margret Villalobos									
Count: 27 Work Orders		Avg. Age of WO's 65		Total for Sunrise ES		0		\$0.00	

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
36103					7/22/2008		224		\$0.00
Medium	Work In Progress			7/22/2008 8:39:31 AM					
Sotelo, Enrique		NEED TO REPLACE 4 EXIT SIGNS							
Danny Miranda									
36104					7/22/2008		224		\$0.00
Medium	Work In Progress			7/22/2008 8:40:50 AM					
Sotelo, Enrique		NEED TO REPLACE 6 EMER. LIGHTS							
Danny Miranda									
41189					1/6/2009		56		\$0.00
Medium	Work In Progress			1/6/2009 10:43:25 AM					
Sotelo, Enrique		NEED TO REPAIR THREE POWER POLES IN KITCHEN							
Danny Miranda									
41569					1/16/2009		46		\$0.00
Medium	Work In Progress			1/16/2009 9:52:29 AM					
Lozoya, Manny		NEED TOCK. DOOR KNOB IN CUSTODIAL ROOM AT 300-WING HANDLE CAME OUT							
Danny Miranda									
41848	Main Building	Classroom			1/26/2009		36		\$0.00
Medium	Work In Progress			1/26/2009 2:01:36 PM					
Lozoya, Manny		NEED A KEY FOR ROOM 101 CLOSET DOOR FOR P.E. TEACHER MR. GONZALES							
Debra Facio									
41880					1/27/2009		35		\$0.00
Medium	Work In Progress			1/27/2009 10:03:30 AM					
Lozoya, Manny		NEED TO PUT CHANGE DOOR KNOB AND TWO KEYS TO BEST IN NEW CLASSROOM AT LIBUERY							
Danny Miranda									
41947					1/28/2009		34		\$0.00
Medium	Work In Progress			1/28/2009 2:23:55 PM					
Lozoya, Manny		NEED TO CK. CORE ON DOOR KNOB TO BACK ELECTRICAL ROOM KEY WILL NOT LOCK							
Danny Miranda									
42134	Main Building	Athletic Field			2/2/2009		29		\$0.00
Medium	Work In Progress			2/2/2009 7:58:56 AM					
Ontiveros, Guadalupe		NEED DIRT DUG UP 6 INCHES OUTSIDE ON PATIO WINDOWS							
Debra Facio									
42360	Main Building	Parking Lot			2/9/2009		22		\$0.00
Medium	Work In Progress			2/9/2009 8:37:01 AM					
Miranda, Danny		START UP OF RAYS GARDENS FOR OUTSIDE PATIO							
Debra Facio									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
42362	Main Building	Parking Lot			2/9/2009		22		\$0.00
Medium	Work In Progress			2/9/2009 8:39:43 AM					
Miranda, Danny	NEE TO HAVE RED PAINT IN THE EMERGENCY LANES								
Debra Facio									
42470	Main Building				2/11/2009		14		\$0.00
Medium	Work In Progress			2/11/2009 8:30:49 AM	2/25/2009				
Villalobos, Margret	BCU needs to be checked, keeps going off and on.								
Lorenzo Solis									
42924					2/25/2009		6		\$0.00
Medium	Work In Progress			2/25/2009 11:33:25 AM					
Carrasco, Danny	Danny need to conduct inventory of all Building Mechanic tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									
43099					3/1/2009	3/7/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:54 AM					
Miranda, Danny	Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
43100					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:54 AM					
Miranda, Danny	Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43101					3/1/2009	3/9/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:55 AM					
Miranda, Danny	Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
43102					3/1/2009		2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:55 AM					
Miranda, Danny	Yearly - Vado ES A-10 Heat Pump Yearly - Refer to PM schedule details.								
Margret Villalobos									
43103					3/1/2009	4/1/2009	2		\$0.00
Medium	Work In Progress			3/1/2009 12:22:55 AM					
Miranda, Danny	Yearly - Vado ES R-3 Ref. Unit Yearly - Refer to PM schedule details.								
Margret Villalobos									

952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Vado ES							
43118					3/1/2009		2		\$0.00
Medium	Work In Progress				3/1/2009 12:23:00 AM				
Orozco, Danny	Yearly - Vado ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
Count: 18 Work Orders		Avg. Age of WO's 42		Total for Vado ES				0	\$0.00
Count: 952 Work Orders		Avg. Age of WO's 73		Grand Total				15	\$1,775.00