

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Anthony ES

47382	Cafeteria	Cafeteria			7/9/2009		83		\$0.00
-------	-----------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			7/9/2009 11:19:24 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

AE 3-6 CAMPUS: HAS A ROACH PROBLEM. FOUND A NEST OF ROACHES BY THE DISHWASHER. 7/9/09 - spoke to Mikey, this routine service and he will look in to this. FAXED TO SUSAN PER MIKEY.

CUCA PEREZ SNP MGR 882-5607

Jacqueline Aguilar

47851		Classroom			7/27/2009		65		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/27/2009 10:17:28 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lozoya, Manny upper primary room 305 made key for cabinet

Hector Villalobos

47859	Annex Building				7/27/2009		65		\$0.00
-------	----------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/27/2009 12:56:13 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ontiveros, Joe Annex grils bathroom 2 toilet need closet flange replace

Hector Villalobos

47860	Dona Ana	Restroom (Girls)			7/27/2009		65		\$0.00
-------	----------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/27/2009 1:09:34 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Joe chapter blg grils bathroom toilet needs pipe valve and closet flanges

Hector Villalobos

48263		Classroom			8/3/2009		58		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/3/2009 3:49:37 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lozoya, Manny Room 320 door lock will not open

Hector Villalobos

48399		Athletic Field			8/5/2009		56		\$0.00
-------	--	----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/5/2009 2:28:12 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ontiveros, Guadalupe Need two box of I-25 full and half for main scooer field and chapter scooer field

Hector Villalobos

48634	Cafeteria	Cafeteria			8/11/2009		50		\$0.00
-------	-----------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/11/2009 10:28:30 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Orozco, Danny LOCK NEEDS TO BE FIXED TO REACH IN REFRIG. WILL NOT LOCK

BECKY S. 882-3507

Jacqueline Aguilar

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

48938	Original Main				8/18/2009		43		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	POA ROOM			8/18/2009 10:24:43 AM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Lozoya, Manny PLEASE IF POSSIBLE TO CHANGE LOCK AND NEW KEY....

Loraine Gandara

49050		Portables			8/20/2009		41		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/20/2009 7:00:06 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny PT 4 door handle is broken need to secure door

Hector Villalobos

49463	Annex Building	Office			8/31/2009		30		\$0.00
-------	----------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/31/2009 7:28:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny room 212 broken door handle outside door

Hector Villalobos

49940	Cafeteria				9/10/2009		20		\$0.00
-------	-----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/10/2009 3:22:31 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Hector mild cafeteria need 4 pillow blocks high raise for a/c unit 3/4

Hector Villalobos

50222	Main Building				9/17/2009		13		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/17/2009 2:27:38 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben need 11 5 lbs fire extinguisher that are out date

Hector Villalobos

50223	Main Building				9/17/2009		13		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/17/2009 2:31:00 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Hector Book room 21 order 2 backing for book case 4x8 1x1x8 3

Hector Villalobos

50224	Main Building	Office			9/17/2009		13		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/17/2009 2:33:16 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Hector Front office out side paint letters yellow paint 1 qt

Hector Villalobos

50225	Main Building	Cafeteria			9/17/2009		13		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/17/2009 2:35:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Hector mild cafeteria paint walls rosarian sp 4013 5 gals

Hector Villalobos

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Anthony ES

50226	Annex Building	Classroom			9/17/2009		13		\$0.00
Medium	Work In Progress			9/17/2009 2:39:05 PM					
Sotelo, Enrique	Room 213 needs receptacle locking devices for machine								
<u>Hector Villalobos</u>									
50352	Main Building	Classroom			9/22/2009		8		\$0.00
Medium	Work In Progress			9/22/2009 7:38:26 AM					
Lozoya, Manny	room 16 mild blg new key will not unlock door								
<u>Hector Villalobos</u>									
50353		Parking Lot			9/22/2009		8		\$0.00
Medium	Work In Progress			9/22/2009 7:42:25 AM					
Ontiveros, Guadalupe	need a load of cruiser fine for parking lot								
<u>Hector Villalobos</u>									
50527		Athletic Field			9/25/2009		5		\$0.00
Medium	Work In Progress			9/25/2009 2:58:37 PM					
Ontiveros, Guadalupe	Need a tractor to help cover sink holes on playground and church street with a load of cruiser fine								
<u>Hector Villalobos</u>									
50564					9/28/2009		2		\$0.00
Medium	Work In Progress			9/28/2009 8:51:21 AM					
Briones, Enrique	Deliver to AE PO #91001488 One box Katrina Garza								
<u>Margaret Villalobos</u>									
50674	Main Building	Custodial			9/30/2009		0		\$0.00
Medium	Work In Progress			9/30/2009 6:13:13 AM					
Carbajal, Jimmy	repair vaccum cleaner								
<u>David Vega</u>									
50675		Custodial			9/30/2009		0		\$0.00
Medium	Work In Progress			9/30/2009 7:47:50 AM					
Ronquillo, Ruben	room 307 and office next door broken window 2 19 3/4x15 3/4 , 191/2 x 161/2								
<u>Hector Villalobos</u>									
Count: 22 Work Orders			Avg. Age of WO's	30			Total for Anthony ES	0	\$0.00

Location: Berino ES

47149					7/5/2009	7/26/2009	87		\$0.00
Medium	Work In Progress			7/5/2009 12:21:20 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
9/30/2009 6:01:20 PM									

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

49319					8/26/2009		35		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/26/2009 3:17:26 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny
MR ADAN DURAN NEED DOOR LATCH TO PLACE ON DOOR BETWEEN PORTABLES AND DOOR KNOB ON THE OTHER SIDE

Adan Duran

49366					8/27/2009		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/27/2009 12:40:12 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Duran, Adan
MR ADAN DURAN PER MR ALFEDO HOLGIN NEED TO PAINT WEST ENTRANCE GATES

Adan Duran

49403					8/28/2009		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/28/2009 7:43:18 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Joe
upper primary is requesting a water fountain by playground

Hector Villalobos

49418					8/28/2009		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/28/2009 9:57:53 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Joe
WATER VALVE COMING OUT OF SCHOOL BUILDING ON EAST SIDE IS STUCK WILL NOT CLOSE NEED TO REPAIR OR REPLACE THANK YOU AND GOD BLESS

Adan Duran

49443					8/28/2009		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/28/2009 3:35:23 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David
Need to coordinate w/Bldg Mechanic and Joe Ontiveros on proper training for newer water heaters.

Michael Munoz

49889					9/9/2009		21		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/9/2009 2:54:30 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lozoya, Manny
MR MANNY LOZOYA MR MANNY I HAVE TWO GATE LOCKS THAT WILL NOT OPEN NEED TO REPAIR OR REPLACE THANK YOU SIR AND GOD BLESS

Adan Duran

50186					9/16/2009		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/16/2009 3:06:14 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Duran, Adan
MR ADAN DURAN THE EXHUAST FAN IN ROOM 100 AND 101 ARE NOT WORKING WILL NEED TO REPLACE MOTORS

Adan Duran

9/30/2009 6:01:20 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

50659					9/30/2009		0		\$0.00
Medium	Work In Progress				9/30/2009 12:22:59 AM				
Duran, Adan	Monthly - Berino ES A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								

Margret Villalobos

Count: 9 Work Orders	Avg. Age of WO's 32	Total for Berino ES	0	\$0.00
-----------------------------	----------------------------	----------------------------	----------	---------------

Location: Chaparral Elem East Pre-K

47602		Portables			7/16/2009		76		\$0.00
Medium	Work In Progress	CE-ON TRACK			7/16/2009 5:54:15 PM				
Lozoya, Manny	AS PER MS. ANN STEINHOFF-NEED TO HAVE TWO KEYS MADE FOR THE 2 PORTABLES LOCATED AT CHAPARRAL ELEMENTARY ON TRACK PRE-K W/JUDY ATKINS		APPROVED BY RICHARD G. CHAVEZ						

Mary Garcia

Count: 1 Work Orders	Avg. Age of WO's 76	Total for Chaparral Elem East Pre-K	0	\$0.00
-----------------------------	----------------------------	--	----------	---------------

Location: Chaparral ES

47603		Parking Lot			7/16/2009		76		\$0.00
Medium	Work In Progress	CE-SIDE GATE			7/16/2009 5:56:16 PM				
Lozoya, Manny	AS PER ANN STEINHOFF-NEED TO HAVE A KEY MADE FOR THE SIDE GATE OF CHAPARRAL ELEMENTARY MADE FOR JUDY ATKINS. (SEE JUDY ATKINS TO CK EXACTLY WHICH GATE).		APPROVED BY RICHARD G. CHAVEZ						

Mary Garcia

48077					7/30/2009		62		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/30/2009 4:07:23 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo	Need to replace rusted distribution duct in the cafeteria. Thank you								
----------------	--	--	--	--	--	--	--	--	--

Guillermo Hernandez

49057					8/20/2009		41		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/20/2009 8:25:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny	Would you please check door closer for handicap door by the Nurse, also need to replace remote wireless switch. Thank you								
---------------	---	--	--	--	--	--	--	--	--

Guillermo Hernandez

49072					8/20/2009		41		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/20/2009 10:55:32 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny	FIRE EXTINGUISHERS NEED SERVICE								
---------------	---------------------------------	--	--	--	--	--	--	--	--

Danny Orozco

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral ES

49338					8/26/2009		35		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/26/2009 3:57:27 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe Need to use Bobcat to fill water run out erosion spots.
Thank you.

Guillermo Hernandez

49813					9/6/2009		24		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:54 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Jacquez, Ricardo Monthly - Chaparral ES-Wastewater Weed Control -
Refer to PM schedule details.

Margret Villalobos

50028					9/13/2009	9/29/2009	17		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress			9/13/2009 12:33:17 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Hernandez, Guillermo Monthly - Chaparral ES Playground Insp - Refer to PM
schedule details.

Margret Villalobos

50056					9/14/2009		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/14/2009 1:15:32 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe water leak on irrigation system by irrigation tank (shut off
water). Thank you.

Guillermo Hernandez

50138					9/15/2009		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/15/2009 3:03:22 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Jacquez, Ricardo Please check stuck motor for Irrigation pressure tank
Booster pump.

U.S. Electrical Motors (MOTOR)
Model #E684A, HP 15, 3-PHASE, 60 HZ, RPM-1745,
FL. AMPS 43.6-40.0 / 20.0, 440 VOLTS

(BOOSTER PUMP) PEERLESS PUMP CO.
MODEL #C1220AMBF

Johnny Acuna

50413					9/22/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/22/2009 3:55:13 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Joe Need to replace flush valves in the boy's restroom Main
lobby. Thank you

Guillermo Hernandez

50498					9/24/2009		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/24/2009 3:40:44 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben Need to replace support legs to a swing set. Thank you

Guillermo Hernandez

9/30/2009 6:01:20 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

50513					9/25/2009		5		\$0.00
Medium	Work In Progress				9/25/2009 8:46:06 AM				

Carrasco, Danny Need to use scissor lift on the week of October 12 to replace ducting. thank you

Guillermo Hernandez

50575					9/28/2009		2		\$0.00
Medium	Work In Progress				9/28/2009 11:15:12 AM				

Ontiveros, Guadalupe Would you please bring one load of sand for the playground, Thankyou.

Guillermo Hernandez

Count: 13 Work Orders			Avg. Age of WO's 27				Total for Chaparral ES	0	\$0.00
------------------------------	--	--	----------------------------	--	--	--	-------------------------------	----------	---------------

Location: Chaparral HS

47098					7/5/2009		87		\$0.00
Medium	Work In Progress				7/5/2009 12:21:00 AM				

Holguin, Alfredo Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details. 8/27/09 - Emailed to Rick

Margret Villalobos

47967	Field House				7/29/2009		63		\$0.00
Medium	Work In Progress	Field House			7/29/2009 8:36:27 AM				

Quinones, Paul Place door stops in certain doors in Field House (10) (Coach Y)

Guadalupe Gonzalez

47970	R-Wing	Classroom			7/29/2009		63		\$0.00
Medium	Work In Progress	R Wing - Rm. 1			7/29/2009 8:41:46 AM				

Quinones, Paul 1) Mount dry erase whiteboard for student instruction, 2) Mount projection screen for student instruction, 3) Mount sound panels on wall over control room & office, 4) Install hasp (finsish installation) on cabinet, 5) Cut access holes in countertop for cable passage - control room. (Mr. Gabaldon)

Guadalupe Gonzalez

48088	C-Wing	Classroom			7/31/2009		61		\$0.00
Medium	Work In Progress	Rm. 1			7/31/2009 8:39:41 AM				

Quinones, Paul I need some shelves assembled. Thank you. (Ms. Fernandez)

Guadalupe Gonzalez

48110					7/31/2009		61		\$0.00
Medium	Work In Progress				7/31/2009 2:09:52 PM				

Quinones, Paul NEED TO REPLACE MOTOR MASTERCOOL BOYS LOCKER EAST 8/6 - Asp Lorenzo, completed by Paul.

Paul Quinones

9/30/2009 6:01:20 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral HS

48111					7/31/2009		61		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/31/2009 2:12:25 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Quinones, Paul		NEED MASTERCOOL MOTOR FOR SCIENCE CLASS RM. AND WATER PUMP		8/6 - Asp Lorenzo, completed by Paul.					
----------------	--	--	--	---------------------------------------	--	--	--	--	--

Paul Quinones

48121	F-Wing	Classroom			7/31/2009		61		\$0.00
-------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Rm. 4		7/31/2009 3:13:30 PM					
--------	------------------	-------	--	----------------------	--	--	--	--	--

Quinones, Paul		Need a bracket to hold the pull down maps. (Mr. Hubble)		ROUTED TO PAUL, AS PER MIKE NEED MORE INFORMATION					
----------------	--	---	--	---	--	--	--	--	--

Guadalupe Gonzalez

48200					8/2/2009		59		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/2/2009 12:21:21 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Quinones, Paul		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

48201					8/2/2009		59		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/2/2009 12:21:22 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Quinones, Paul		Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.							
----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

48229		Athletic Field			8/3/2009		58		\$0.00
-------	--	----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/3/2009 9:51:50 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ontiveros, Guadalupe		Lupe I need the total amount of landscaped areas at this site.							
----------------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

48251					8/3/2009		58		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/3/2009 2:15:11 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Gonzales, Angel		REQUESTING BOBCAT LOADER TO CLEAN OPEN AREAS AROUND C.H.S.							
-----------------	--	--	--	--	--	--	--	--	--

Paul Quinones

48445					8/6/2009		55		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/6/2009 12:37:42 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Orozco, Danny		NEED TO HAVE FIRE EXTINGUISHERS SERVICED							
---------------	--	--	--	--	--	--	--	--	--

Danny Orozco

48579					8/10/2009		51		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Gym		8/10/2009 11:24:42 AM					
--------	------------------	-----	--	-----------------------	--	--	--	--	--

Quinones, Paul		I want the whiteboard in the P.E. Locker moved to the Basketball Lockerroom to be located between my office door and the window. (Mr. Heredia)							
----------------	--	--	--	--	--	--	--	--	--

Guadalupe Gonzalez

9/30/2009 6:01:20 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

48581		Classroom			8/10/2009		51		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	E Wing - Rm. 6			8/10/2009 12:45:39 PM				
--------	------------------	----------------	--	--	-----------------------	--	--	--	--

Quinones, Paul		Television needs to be turned. (Ms. Pranses)							
----------------	--	--	--	--	--	--	--	--	--

Guadalupe Gonzalez

48712	C-Wing	Computer Lab			8/12/2009		49		\$0.00
-------	--------	--------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/12/2009 10:36:27 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenzo		ONE OF THE UNITS IS NOT FOUND AT ALL THRU TRACER SUMMIT, NEED TO LOCATE UNIT.				8/12 - Emailed Trane -mkv			
----------------	--	---	--	--	--	---------------------------	--	--	--

Lorenzo Solis

48779	D-Wing	Classroom			8/13/2009		48		\$0.00
-------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Rm. 6			8/13/2009 1:14:56 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Quinones, Paul		Remove and replace broken desk (leg fell off) (Ms. Lopez)							
----------------	--	---	--	--	--	--	--	--	--

Guadalupe Gonzalez

48781					8/13/2009		48		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Gates			8/13/2009 1:18:57 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Gonzalez, Salvador		Weld the locks to chains and chains to gates. Locks keep getting moved preventing security to secure the gates. Safety Issue. (Frank De Santiago)							
--------------------	--	---	--	--	--	--	--	--	--

Guadalupe Gonzalez

48950		Office			8/18/2009		43		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/18/2009 1:27:55 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul		Need "Smart Board" installed in the following classrooms: Mr. Ubinger - D-1 and Ms. Fernandez - C-1. (Smart boards are in Ms. Hardy's classroom (B-5) (Ms. Ballard)							
----------------	--	---	--	--	--	--	--	--	--

Guadalupe Gonzalez

49023					8/19/2009		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/19/2009 1:30:45 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		PROBLEM WITH DOOR CLOSER, AND DOOR HARDWARE IN KITCHEN REAR ENTRANCE DOOR.							
---------------	--	--	--	--	--	--	--	--	--

Paul Quinones

49364		Classroom			8/27/2009		34		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	TRAINING			8/27/2009 11:56:21 AM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Solis, Lorenzo		NEED TO INSTALL ICE MACHINE IN THE GYM TRAINING ROOM - STORAGE AREA- SEE MR. HANSON FOR EXACT LOCATION (QUEZADA)							
----------------	--	--	--	--	--	--	--	--	--

Rosa Quezada

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
49415					8/28/2009		33		\$0.00
Medium	Work In Progress				8/28/2009 9:25:58 AM				
Quinones, Paul		Please check a/c in gym							
<u>Michael Munoz</u>									
49502					8/31/2009		30		\$0.00
Medium	Work In Progress	BOYS LOCKER			8/31/2009 3:32:43 PM				
Lozoya, Manny		CHANGE LOCK ON BOYS LOCKER ROOM STORAGE. (HEREDIA)							
<u>Rosa Quezada</u>									
49504	E-Wing	Classroom			8/31/2009		30		\$0.00
Medium	Work In Progress	E-4			8/31/2009 3:41:08 PM				
Lozoya, Manny		REPLACE CH-60 (KEY BENT WHILE OPENING CLASSROOM) (RACETTE)							
<u>Rosa Quezada</u>									
49523	Field House	Gym			9/1/2009		29		\$0.00
Medium	Work In Progress				9/1/2009 7:42:27 AM				
Ontiveros, Joe		please provide water supply to new ice machine.							
<u>Lorenzo Solis</u>									
49525	Field House	Gym			9/1/2009		29		\$0.00
Medium	Work In Progress				9/1/2009 7:44:00 AM				
Sotelo, Enrique		please run electrical supply to new ice machine need 120volt outlet. thank you!							
<u>Lorenzo Solis</u>									
49539					9/1/2009		29		\$0.00
Medium	Work In Progress				9/1/2009 2:08:24 PM				
Orozco, Danny		Annual Operational Inspection of Fire Pump.							
<u>Danny Orozco</u>									
49575					9/2/2009		28		\$0.00
Medium	Work In Progress				9/2/2009 8:59:01 AM				
Ontiveros, Joe		WATER LEAKING FROM PUMP SEAL FROM #1 BOILER CIRCULATING PUMP IN BACK MECHANICAL RM. NEXT TO KITCHEN.NEED TO REPLACE PUMP.							
<u>Paul Quinones</u>									
49806					9/6/2009		24		\$0.00
Medium	Work In Progress				9/6/2009 12:22:52 AM				
Quinones, Paul		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral HS

49807					9/6/2009		24		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:52 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Quinones, Paul Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

49808					9/6/2009		24		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:53 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Quinones, Paul Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

49809					9/6/2009	10/7/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:53 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Quinones, Paul Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

49903		Cafeteria			9/9/2009		21		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/9/2009 3:39:46 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Orozco, Danny there is no hot water in the kitchen area. please check boilers for proper operation. t loernzo will assist. thanks

Michael Munoz

50077		Classroom			9/14/2009		16		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	D Wing - Rm. 5		9/14/2009 2:55:05 PM					
--------	------------------	----------------	--	----------------------	--	--	--	--	--

Quinones, Paul Install two bulletin boards. (3rd Request) (Ms. Holguin)

Guadalupe Gonzalez

50090	E-Wing	Restroom (Boys)			9/14/2009		16		\$0.00
-------	--------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	E WING		9/14/2009 3:45:06 PM					
--------	------------------	--------	--	----------------------	--	--	--	--	--

Ontiveros, Joe BOYS SINK - NO WATER (DIGGS)

Rosa Quezada

50112	B-Wing	Hallway/Corridor			9/15/2009		15		\$0.00
-------	--------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	WING B		9/15/2009 9:14:46 AM					
--------	------------------	--------	--	----------------------	--	--	--	--	--

Vargas, Juan
 1. COMPUTER LAB ROOF HAS WATER STAINS (15)
 2. FIRE EXTINGUISHER HAS CAP BROKEN.
 3. MAIN HALLWAY ENTERING BUILDING HAS WATER STAIN

Rosa Quezada

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

50113	C-Wing				9/15/2009		15		\$0.00
Medium	Work In Progress	MISCELLANEO			9/15/2009 9:18:33 AM				
Ontiveros, Joe		WING "C" PROBLEMS; 1. BOYS RESTROOM - 4 SINKS ARE LOOSE 2. GIRLS RESTROOM - SOAP DISPENSER BROKEN 3. WATER FOUNTAIN BUTTON IS LOOSE 4. ROOF BETWEEN C & D HALLWAY HAS A WATER STAIN							

Rosa Quezada

50114	D-Wing				9/15/2009		15		\$0.00
Medium	Work In Progress				9/15/2009 9:23:18 AM				
Ontiveros, Joe		WING "D" PROBLEMS; 1. BOYS RESTROOM - 3 SINKS ARE LOOSE 2. TWO SINKS DON'T HAVE WATER 3. HALLWAY CLOCK IS BROKEN 4. WATER FOUNTAIN BUTTON IS LOOSE 5. COMPUTER LAB HAS THREE STAINED CEILING TILES							

Rosa Quezada

50116	E-Wing				9/15/2009		15		\$0.00
Medium	Work In Progress				9/15/2009 9:44:59 AM				
Vargas, Juan		WING "E" PROBLEMS; 1. E-7 ENTRANCE IS MISSING THE LIGHT COVER 2. WATER FOUNTAIN BUTTON IS LOOSE 3. WATER FOUNTAIN IN MAIN HALLWAY BETWEEN E & F WING HAS A LOOSE PUSH BAR							

Rosa Quezada

50117	F-Wing				9/15/2009		15		\$0.00
Medium	Work In Progress				9/15/2009 9:52:20 AM				
Vargas, Juan		WING "F" PROBLEMS; 1. WATER FOUNTAINS PUSH BARS ARE LOOSE 2. COMPUTER LAB HAS NINE CEILING TILES WITH STAINS 3. MISSING A CEILING TILE IN COMPUTER LAB 4. FIRE EXTINGUISHER CAP IS BROKEN 5. MAIN HALLWAY BETWEEN F & G HAS STAINED CEILING TILES							

Rosa Quezada

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

50118	G-Wing				9/15/2009		15		\$0.00
-------	--------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	WING			9/15/2009 9:55:59 AM				
--------	------------------	------	--	--	----------------------	--	--	--	--

Vargas, Juan

WING "G" PROBLEMS;
 1. HALLWAY COMPUTER LAB HAS ONE STAINED CEILING TILE
 2. COMPUTER LAB IS MISSING A CEILING TILE
 3. FIRE EXTINGUISHER IN MAIN HALLWAY BETWEEN G AND GYM HAS A BROKEN COVER

Rosa Quezada

50119		Gym			9/15/2009		15		\$0.00
-------	--	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress	GYM			9/15/2009 9:57:57 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Vargas, Juan

GYM PROBLEMS:
 1. FOUR FIRE EXTINGUISHERS HAVE BROKEN COVERS
 2. BOYS LOCKER ROOM URINAL DOESN'T FLUSH

Rosa Quezada

50120		Cafeteria			9/15/2009		15		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	CAFETERIA			9/15/2009 9:59:21 AM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Vargas, Juan

FIRE EXTINGUISHER HAS A BROKEN COVER

Rosa Quezada

50125		Gym			9/15/2009		15		\$0.00
-------	--	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Gym			9/15/2009 11:51:20 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Gonzalez, Salvador

We are requesting that Metal Beams be purchased to be cut to size to hang the glass backboards at Chaparral High School. Salvador came and took measurements so he knows how much is needed. (Steve Heredia)

Guadalupe Gonzalez

50176	B-Wing	Hallway/Corridor			9/16/2009		14		\$0.00
-------	--------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	WING B			9/16/2009 1:59:42 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Vargas, Juan

1. WATER FOUNTAIN BUTTEN IS LOOSE
 2. WATER FOUNTAIN BUTTON LOOSE BETWEEN B & C WING

Rosa Quezada

50177	E-Wing				9/16/2009		14		\$0.00
-------	--------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/16/2009 2:02:54 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe

WING "E" PROBLEMS;
 1. BOYS RESTROOM SINK IS LOOSE
 2. 4 SINKS DON'T RELEASE WATER

Rosa Quezada

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral HS

50178	B-Wing	Hallway/Corridor			9/16/2009		14		\$0.00
Medium	Work In Progress	WING B			9/16/2009 2:07:29 PM				
Ontiveros, Joe	BOYS RESTROOM URINALS DON'T FLUSH								

Rosa Quezada

50179	F-Wing				9/16/2009		14		\$0.00
Medium	Work In Progress				9/16/2009 2:09:20 PM				
Ontiveros, Joe	WING "F" PROBLEMS;								
	1. GIRLS RESTROOM - TWO SINKS DON'T RELEASE WATER								
	2. BOYS RESTROOM - 3 SINKS ARE LOOSE								
	3. ONE SINK DOESN'T RELEASE WATER								
	4. URINAL IN BOYS RESTROOM DOESN'T FLUSH								

Rosa Quezada

50181	G-Wing				9/16/2009		14		\$0.00
Medium	Work In Progress	WING			9/16/2009 2:12:58 PM				
Ontiveros, Joe	WING "G" PROBLEMS;								
	BOYS RESTROOM - 5 SINKS ARE LOOSE								

Rosa Quezada

50279					9/20/2009		10		\$0.00
Medium	Work In Progress				9/20/2009 12:18:48 AM				
Ontiveros, Guadalupe	Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.								

Margret Villalobos

50463	Field House	Restroom (Girls)			9/24/2009		6		\$0.00
Medium	Work In Progress				9/24/2009 7:17:11 AM				
Rivera, Armando	field house rest rooms boys rest room set up 10 toilet roll paper dispensers girls frst room set up 21 toilet roll paper dispensers								
	9/24(Asp Mike/Alfredo, Custodial needs to install)mkv								

Armando Rivera

50522					9/25/2009		5		\$0.00
Medium	Work In Progress	Security			9/25/2009 10:40:34 AM				
Lozoya, Manny	Put locks and chains on interior fence for security reasons. Several locks have been taken and we are not able to secure gates. Weld gates to the gate and the locks to the chains to keep people from taking locks. (Frank De Santiago)								

Guadalupe Gonzalez

50523		Library			9/25/2009		5		\$0.00
Medium	Work In Progress				9/25/2009 11:08:45 AM				
Quinones, Paul	Repair wheel roller on periodical shelving. Please ask librarian Marty Mayes for specific location.								

Phillip Medina

9/30/2009 6:01:20 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral HS

50554	A-Wing	Hallway/Corridor			9/28/2009		2		\$0.00
Medium	Work In Progress				9/28/2009 8:18:44 AM				
Gonzalez, Salvador	re-weld 3 phase motor plate.								

Lorenzo Solis

50559					9/28/2009		2		\$0.00
Medium	Work In Progress				9/28/2009 8:34:21 AM				
Briones, Enrique	PO# 91000531 Three boxes to Jeanette Edwards--Chaparral HS								

Margaret Villalobos

50576					9/28/2009		2		\$0.00
Medium	Work In Progress				9/28/2009 11:46:48 AM				
Gonzales, Angel	ANGEL PLEASE DELIVER SCOOTER TO KAREN NOUGES (ASST. PRINCIPAL) AS PER LUPITA CHAVEZ IN HUMAN RESOURCES								

Cora Ramirez

50580	Field House	Restroom (Boys)			9/28/2009		2		\$0.00
Medium	Work In Progress				9/28/2009 1:42:19 PM				
Rivera, Armando	set up 12 soap dispensers boy and girls rest rooms and concession stand								

Armando Rivera

50652	A-Wing				9/29/2009		1		\$0.00
Medium	Work In Progress	STORAGE			9/29/2009 3:52:32 PM				
Lozoya, Manny	NEED TO REKEY STORAGE ROOM BY FRONT OFFICE								

Rosa Quezada

50657					9/29/2009		1		\$0.00
Medium	Work In Progress				9/29/2009 4:26:07 PM				
Lozoya, Manny	Please meet w/David Ortega, regarding door issues on Thursday, Oct 1, 2009 at 8:15am.								

Margret Villalobos

50671					9/30/2009		0		\$0.00
Medium	Work In Progress				9/30/2009 12:23:03 AM				
Quinones, Paul	Monthly - Chaparral HS A16 (Fan Exhst.)(S.Annual) - Refer to PM schedule details.								

Margret Villalobos

50689					9/30/2009		0		\$0.00
Medium	Work In Progress				9/30/2009 2:13:30 PM				
Lozoya, Manny	#'s ARE NEEDED TO ALL DOORS IN A-WING 101,102,103 104,105,106,107,108,109,110,111,112.THANKS								

Paul Quinones

9/30/2009 6:01:21 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral HS

Count: 60 Work Orders	Avg. Age of WO's 29	Total for Chaparral HS	0	\$0.00
------------------------------	----------------------------	-------------------------------	----------	---------------

Location: Chaparral MS

47150					7/5/2009	7/26/2009	87		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			7/5/2009 12:21:20 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Orozco, Danny Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

47470					7/13/2009		79		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	pond		7/13/2009 11:06:23 AM					
--------	------------------	------	--	-----------------------	--	--	--	--	--

Jacquez, Ricardo Rick need to see if you can replace apump for the pond it is the filtration pump

Eric Medina

48224	Main Building	Classroom			8/3/2009		58		\$0.00
-------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	ROOM 307		8/3/2009 9:13:24 AM					
--------	------------------	----------	--	---------------------	--	--	--	--	--

Lozoya, Manny NEED KEYS MADE TO SCIENCE LAB CABINETS HAVE NEVER BEEN ABLE TO LOCK. NEED THEM TO LOCK SCIENCE EQUIPMENT

Elena Palacios

48227					8/3/2009		58		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/3/2009 9:38:42 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lozoya, Manny I WOULD LIKE A KEY MADE FOR A FILING CABINET

Elena Palacios

48693		Athletic Field			8/12/2009		49		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

Safety	Work In Progress			8/12/2009 8:14:17 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Garcia, Jose need to replace sprinklers on football field that are not working.

Guadalupe Ontiveros

48717		Classroom			8/12/2009		49		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	ROOM 201		8/12/2009 10:56:31 AM					
--------	------------------	----------	--	-----------------------	--	--	--	--	--

Lozoya, Manny TERESA ORTEGA : ROOM DOOR STAYS LOCKED, WILL NOT UNLOCK ANYMORE

Elena Palacios

48881					8/17/2009		44		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/17/2009 11:03:59 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lozoya, Manny we have an office in the main offices that we can not unlock so if you could fix asap that would really help alot. thanks

Robert Gonzalez

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

49028	Main Building	Classroom			8/19/2009		42		\$0.00
Medium	Work In Progress	ROOM 406		8/19/2009 2:23:09 PM					
Lozoya, Manny		RAMON RUEDA - CABINET DOORS NEED LOCKS RUEDA HAS THE LOCKS JUST NEEDS THEM INSTALLED							
<u>Elena Palacios</u>									
49071					8/20/2009		41		\$0.00
Medium	Work In Progress			8/20/2009 10:54:07 AM					
Orozco, Danny		FIRE EXTINGUISHERS NEED SERVICE							
<u>Danny Orozco</u>									
49114					8/21/2009		40		\$0.00
Medium	Work In Progress			8/21/2009 11:03:52 AM					
Lozoya, Manny		door to room 309 is very hard to unlock							
<u>Robert Gonzalez</u>									
49115					8/21/2009		40		\$0.00
Medium	Work In Progress			8/21/2009 11:11:24 AM					
Lozoya, Manny		door to room 302 is very hard to unlock							
<u>Robert Gonzalez</u>									
49116					8/21/2009		40		\$0.00
Medium	Work In Progress			8/21/2009 11:15:32 AM					
Lozoya, Manny		first exit doors in the front main entrance doors can only be locked or unlocked from one side							
<u>Robert Gonzalez</u>									
49439					8/28/2009		33		\$0.00
Medium	Work In Progress			8/28/2009 3:33:52 PM					
Villalobos, David		Need to coordinate w/Bldg Mechanic and Joe Ontiveros on proper training for newer water heaters.							
<u>Michael Munoz</u>									
49540					9/1/2009		29		\$0.00
Medium	Work In Progress			9/1/2009 2:09:07 PM					
Orozco, Danny		Annual Operational Inspection of Fire Pump.							
<u>Danny Orozco</u>									
50240					9/18/2009		12		\$0.00
Medium	Work In Progress			9/18/2009 9:55:11 AM					
Ontiveros, Joe		we need a new faucet in the custodial closet in the gym it leaks real bad. Thank You							
<u>Robert Gonzalez</u>									

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

50363					9/22/2009		8		\$0.00
Medium	Work In Progress			9/22/2009 8:45:53 AM					

Ontiveros, Joe Joe I have a mop closet in the gym that needs a new faucet

Eric Medina

50395					9/22/2009		8		\$0.00
Medium	Work In Progress			9/22/2009 2:59:24 PM					

Ontiveros, Joe Joe I have garbage disposal in home ec. rm 203 that is stuck, need to order another one

Eric Medina

50514					9/25/2009		5		\$0.00
Medium	Work In Progress			9/25/2009 9:04:45 AM					

Briones, Enrique On September 30, 2009, please deliver one (1) box of English Material to Chaparral Middle School.

Yolie Jacquez

50543		Classroom			9/25/2009		5		\$0.00
Medium	Work In Progress	ROOM 407		9/25/2009 3:46:48 PM					

Lozoya, Manny ROSA MARISCAL - NEEDS WALL CABINETS RE-KEYED KEY HOLE IS BROKEN

Elena Palacios

50662					9/30/2009		0		\$0.00
Medium	Work In Progress			9/30/2009 12:23:00 AM					

Medina, Eric Monthly - Chaparral MS A16 (Fan Exh.)(S. Annual) - Refer to PM schedule details.

Margret Villalobos

Count: 20 Work Orders			Avg. Age of WO's 36			Total for Chaparral MS	0		\$0.00
------------------------------	--	--	----------------------------	--	--	-------------------------------	----------	--	---------------

Location: Charter School

47478					7/13/2009		7		\$0.00
Medium	Work In Progress			7/13/2009 2:54:32 PM		7/20/2009			

Munoz, Michael Portables # 2 DW, 80 DW and 32 SW located in San Miguel Elem. recarpet, paint and get ready for Charter School at GHS old DACC location 7/15/09 - FAX TO MICHAEL/AZTEC FOR QUOTE ON CARPET

Alfredo Holguin

50452					9/23/2009		7		\$0.00
Medium	Work In Progress			9/23/2009 3:38:15 PM					

Munoz, Michael Driveway entrance to PPD- need to designate both sides of entrance as No- Parking area install signs and paint curbs on both sides with No-Parking designation.

Alfredo Holguin

Count: 2 Work Orders			Avg. Age of WO's 7			Total for Charter School	0		\$0.00
-----------------------------	--	--	---------------------------	--	--	---------------------------------	----------	--	---------------

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Pride

47114					7/5/2009	7/13/2009	87		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				7/5/2009 12:21:07 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acosta, David		Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

47115					7/5/2009	7/13/2009	87		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				7/5/2009 12:21:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

47116					7/5/2009	7/13/2009	87		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				7/5/2009 12:21:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

47117					7/5/2009	7/11/2009	87		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				7/5/2009 12:21:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

47118					7/5/2009	8/5/2009	87		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				7/5/2009 12:21:09 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acosta, David		Yearly - Desert Pride Emer. Light Test: Annual - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

47119					7/5/2009	8/5/2009	87		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				7/5/2009 12:21:09 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acosta, David		Yearly - Desert Pride Exit Sign Test: Annual - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

47637					7/20/2009		72		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/20/2009 3:59:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Aguilar, Patricio		Need to assemble desk.							
-------------------	--	------------------------	--	--	--	--	--	--	--

Irene Herrera

48146					8/2/2009	8/10/2009	59		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				8/2/2009 12:21:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Pride

48147					8/2/2009	8/10/2009	59		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			8/2/2009 12:21:03 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Acosta, David Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

48148					8/2/2009	8/8/2009	59		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress			8/2/2009 12:21:04 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Acosta, David Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

48620	Curriculum and	Classroom			8/11/2009		50		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	room 7		8/11/2009 7:46:35 AM					
--------	------------------	--------	--	----------------------	--	--	--	--	--

Lara, Ralph Teacher Kelley Scott needs keys made for file cabinets in SPED room. Thank you

Mary Telles

48969					8/18/2009		43		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress			8/18/2009 3:22:08 PM					
------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David 2nd bldg, please check to see if gas regulator if functioning properly. thanks

Michael Munoz

49745					9/6/2009	9/14/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:32 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Acosta, David Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

49746					9/6/2009	9/14/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:32 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Acosta, David Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

49747					9/6/2009	9/12/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:32 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Acosta, David Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

50124		Office			9/15/2009		15		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	BACK DOOR		9/15/2009 11:20:48 AM					
--------	------------------	-----------	--	-----------------------	--	--	--	--	--

Lara, Ralph REQUESTING FOR A SMALL WINDOW TO BE INSTALL ON BACK DOOR ENTRANCE.

David Acosta

9/30/2009 6:01:21 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Pride

50244		Library			9/18/2009		12		\$0.00
-------	--	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	SECURITY			9/18/2009 11:14:11 AM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Castillo, Carlos		SECURITY OFFICE NEEDS OWN LIGHT SWITCH.							
------------------	--	---	--	--	--	--	--	--	--

David Acosta

50660					9/30/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/30/2009 12:22:59 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Aguilar, Patricio		Monthly - Desert Pride HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

50683	Storage A	Pump House			9/30/2009		0		\$0.00
-------	-----------	------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/30/2009 8:48:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sanchez, Raul		9/30/09 Remove old storage tanks (2) from pump house and install 2 new ones.Replumb and test ssystem for leaks as per State regulations.							
---------------	--	---	--	--	--	--	--	--	--

Raul Sanchez

Count: 19 Work Orders		Avg. Age of WO's 51				Total for Desert Pride	0		\$0.00
------------------------------	--	----------------------------	--	--	--	-------------------------------	----------	--	---------------

Location: Desert Trail Intermediate

47151					7/5/2009	7/26/2009	87		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				7/5/2009 12:21:20 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

47596					7/16/2009		76		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/16/2009 4:17:50 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

		NEED TO REPLACE CARPETS IN ROOMS 202, 212 & 100.				7/16/09 - FAXED - MIKE, PLEASE QUOTE EACH ROOM SEPERATELY.			
--	--	--	--	--	--	--	--	--	--

Jesus Estrada

47932					7/28/2009		64		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/28/2009 2:32:25 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel		Need to borrow 'Bobcat for Desert Trail Elementary.							
-----------------	--	---	--	--	--	--	--	--	--

Johnny Acuna

48705	Main Building	Hallway/Corridor			8/12/2009		49		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/12/2009 9:50:20 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		Puertas principales, salida portables, no se pueden cerrar.							
---------------	--	---	--	--	--	--	--	--	--

Marisela Torres

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail Intermediate									
48707	Main Building	Office			8/12/2009		49		\$0.00
Medium	Work In Progress				8/12/2009 10:07:30 AM				
Lozoya, Manny		Urgente, llave (J 7) para oficina.							
<u>Marisela Torres</u>									
48725					8/12/2009		49		\$0.00
Medium	Work In Progress	office			8/12/2009 12:56:34 PM				
Lozoya, Manny		Office needs requesting J-7 key.							
<u>Elizabeth Hernandez</u>									
49069					8/20/2009		41		\$0.00
Medium	Work In Progress				8/20/2009 10:52:21 AM				
Orozco, Danny		FIRE EXTINGUISHERS NEED SERVICE							
<u>Danny Orozco</u>									
49082	Main Building				8/21/2009		40		\$0.00
Medium	Work In Progress				8/21/2009 7:10:00 AM				
Lozoya, Manny		Puertas principales(bus lobby) se queda la llave atorada.							
<u>Marisela Torres</u>									
49533	Main Building	Custodial			9/1/2009		29		\$0.00
Medium	Work In Progress				9/1/2009 9:21:47 AM				
Lozoya, Manny		8/31/09 Urgente, Mi llave (j master) se enchueco y no la puedo usar.							
<u>Marisela Torres</u>									
49730					9/4/2009		26		\$0.00
Medium	Work In Progress				9/4/2009 3:54:37 PM				
Jacquez, Ricardo		Need to fix leaking backflow that is in-line with the water supply.							
<u>Johnny Acuna</u>									
50031					9/13/2009	9/29/2009	17		\$0.00
Medium	Work In Progress				9/13/2009 12:33:18 AM				
Acuna, Johnny		Monthly - Desert Trail Playground Insp - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
50218					9/17/2009		13	12	\$447.00
Medium	Work In Progress				9/17/2009 9:40:50 AM				
Ontiveros, Guadalupe		Need Base course and dirt to fill in holes in front of parking lot area. (Errosion from Rain water)							
Johnny Acuna						TOOK 2 LOADS OF BASE COARSE FOR ERROISE AND SPREAD OUT AND LEVEL OUT IN FRNT OF PARKING LOT.			

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Trail Intermediate

50405					9/22/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/22/2009 3:50:12 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny
Need a master lock for worktruck toolbox that will open with Master key #1.

Johnny Acuna

50520					9/25/2009		5		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/25/2009 10:31:09 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ontiveros, Joe
Need replace all water faucet (custodial clossets) for all the building.

Marisela Torres

50561		Cafeteria			9/28/2009		2		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/28/2009 8:36:15 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Orozco, Danny
HAS ONE OVEN DOWN. NOT WORKING AT ALL

PAT CISNEROS SNP MGR 824-3822

Jacqueline Aguilar

50664					9/30/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/30/2009 12:23:01 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Acuna, Johnny
Monthly - Desert Trail ES A16(Exhst Fan)(S.Annual) - Refer to PM schedule details.

Margret Villalobos

Count: 16 Work Orders	Avg. Age of WO's 35	Total for Desert Trail Intermediate	12	\$447.00
------------------------------	----------------------------	--	-----------	-----------------

Location: Desert View ES

47234					7/5/2009	8/5/2009	87		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress			7/5/2009 12:21:50 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ortiz, Ruben
Yearly - Desert View ES Exit Sign Test: Annual - Refer to PM schedule details.

Margret Villalobos

47311					7/7/2009		85		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			7/7/2009 6:10:59 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Villalobos, David
Three water fountains in the lower level are not functioning, have tried to repair but unable to do so. Thank you, Ruben

Ruben Ortiz

48953		Cafeteria			8/18/2009		43		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/18/2009 2:07:02 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Moncayo, Fernando
DISHWASHER: 1) COLD WATER ONLY, 2) RINSE SPRAYER NOT WORKING

DIANNA L. SNP MGR 589-2425

Jacqueline Aguilar

9/30/2009 6:01:21 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert View ES

49220					8/24/2009		37		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/24/2009 9:06:42 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David
Are the faucets in the faculty room under warranty, because they continue to leak and need to be replaced.
Thank you, Ruben

 Ruben Ortiz

49274	Main Building	Classroom			8/25/2009		36		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

High	Work In Progress	RM# 24		8/25/2009 4:26:51 PM					
------	------------------	--------	--	----------------------	--	--	--	--	--

Villalobos, David
Please fix shower in SPED room. The work order had been placed since last year and has not been fixed yet.

It is imperative to have this shower fixed as soon as possible. This room pertains to the Basic Life Skills Classroom.

Thank you,

Fernando Carrasco

 Judy Garibay

49371					8/27/2009		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/27/2009 2:14:07 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ortiz, Ruben
INSTALL BASKETBALL NETS. 2EA.

 Ruben Ronquillo

49965					9/11/2009		19		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress			9/11/2009 8:31:22 AM					
------	------------------	--	--	----------------------	--	--	--	--	--

Marquez, Gerardo
need to build a fur-out for shower to accompany work order # 49274.

50495	Main Building	Cafeteria			9/24/2009		6		\$0.00
-------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/24/2009 3:15:20 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Orozco, Danny
Top oven on one of the old ovens is not working.

SNP Manager Diana Lazarin 589-2425

 Maritza Gonzalez

50511					9/25/2009		5		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/25/2009 8:34:14 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben
Vandalism; broken double window 28x28; portable 5 room 8; need it replaced today. Thank you, Ruben

Ruben Ortiz

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert View ES

50521	Main Building				9/25/2009		5		\$0.00
Medium	Work In Progress				9/25/2009 10:39:06 AM				
Briones, Enrique	Pick up boxes from Desert View Elementary in the front office and deliver to North Valley Elementary in care of Criselda Lopez. For questions or concerns please contact Rosa Hidalgo at 882-6737								

Phillip Medina

50608					9/28/2009		2		\$0.00
Medium	Work In Progress				9/28/2009 7:48:51 PM				
Lara, Ralph	Westside wing room 34; hinges broken; the door is hard to open. Thank you, Ruben								

Ruben Ortiz

Count: 11 Work Orders			Avg. Age of WO's	33		Total for Desert View ES	0		\$0.00
------------------------------	--	--	-------------------------	-----------	--	---------------------------------	----------	--	---------------

Location: GAC

47152					7/5/2009	7/26/2009	87		\$0.00
Medium	Work In Progress				7/5/2009 12:21:21 AM				
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								

Margret Villalobos

47462	RTC	Office			7/13/2009		79		\$0.00
Medium	Work In Progress	RTC ACROSS			7/13/2009 9:33:01 AM				
Ambriz, Juan	AS PER GLORIA SAENZ-NEED TO HAVE SOME FILING CABINETS MOVED AROUND WITHIN HER OFFICE.								

Mary Garcia

47533	Pre-K	Classroom			7/14/2009		78		\$0.00
Medium	Work In Progress	GAC-PRE K-			7/14/2009 4:41:13 PM				
Ambriz, Juan	AS PER MS. BERRY-NEED TO ASSEMBLE A METAL SHELF IN ROOM 201 PRE-K @ GAC								

Mary Garcia

47578	Pre-K	Classroom			7/16/2009		76		\$0.00
Medium	Work In Progress	GAC PREK-			7/16/2009 11:58:36 AM				
Ambriz, Juan	AS PER MS. BERRY-NEED TO MOVE A COAT/BACKPACK HOOKS TO BATHROOM FOYER. (SEE ANGELIC OR CECI BEFORE REMOVING.)								

Mary Garcia

47579	Pre-K	Classroom			7/16/2009		76		\$0.00
Medium	Work In Progress	GAC PRE-K			7/16/2009 11:59:47 AM				
Ambriz, Juan	AS PER MS. BERRY-NEED TO HAVE A TV STAND AND DIAPER CHANGER FROM THE BATHROOM.								

Mary Garcia

9/30/2009 6:01:21 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

48249		Office			8/3/2009		58		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	GAC-C-WING			8/3/2009 1:50:07 PM				
--------	------------------	------------	--	--	---------------------	--	--	--	--

Ambriz, Juan AS PR KARLA-NEED TO HAVE A PARTITION IN ROOM #210 REMOVED. (MARTHA'S OFFICE)

Mary Garcia

48250		Office			8/3/2009		58		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	GAC C-WING			8/3/2009 1:51:32 PM				
--------	------------------	------------	--	--	---------------------	--	--	--	--

Ambriz, Juan AS PER KARLA-NEED TO HAVE A PICTURE FRAM HUNG WITHIN MATHA'S OFFICE.

Mary Garcia

48447					8/6/2009		55		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/6/2009 12:45:53 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny NEED TO HAVE THE FIRE EXTINGUISHERS SERVICED

Danny Orozco

48540					8/9/2009	9/9/2009	52		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				8/9/2009 1:23:47 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Juan Yearly - GAC A-9 Air Cooled Condensor Yearly - Refer to PM schedule details.

Margret Villalobos

48730	Pre-K	Classroom			8/12/2009		49		\$0.00
-------	-------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	GAC PRE-K			8/12/2009 2:19:44 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Ambriz, Juan AS PER MS. BERRY-NEED TO HAVE METAL BOXES HUNG UP IN ROOM 201.

Mary Garcia

48871					8/17/2009		44		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				8/17/2009 10:01:17 AM				
------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos need to connect 12 heaters for testing of new refrigeration units in the I. T room as per contractor and alfredo. thanks

Alfredo Holguin

48925	Pre-K	Classroom			8/17/2009		44		\$0.00
-------	-------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	GAC PRE-K			8/17/2009 3:54:32 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Ambriz, Juan AS PER MS. BERRY- NEED TO HAVE AS CUPBOARD DOOR UNSTUCK. THE UPPER LEFT HAND SIDE IS GETTING STUCK AND HARD TO OPEN.

Mary Garcia

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: GAC

48926		Parking Lot			8/17/2009		44		\$0.00
-------	--	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	GAC PARKING		8/17/2009 3:57:48 PM					
--------	------------------	-------------	--	----------------------	--	--	--	--	--

Ambriz, Juan AS PER JUAN - NEED PAINT FOR THE PAINTING OF THE PARKING LOT LINES AT GAC.

Mary Garcia

49254	RTC	Office			8/25/2009		36		\$0.00
-------	-----	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	RTC-ACROSS		8/25/2009 1:52:07 PM					
--------	------------------	------------	--	----------------------	--	--	--	--	--

Ambriz, Juan AS PER GLORIA SAENZ-NEED TO HAVE BOXES BROUGHT FROM RTC TO GAC W/ANGIE SANCHEZ.

Mary Garcia

49335	RTC	Portables			8/26/2009		35		\$0.00
-------	-----	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	RTC ACROSS		8/26/2009 3:47:24 PM					
--------	------------------	------------	--	----------------------	--	--	--	--	--

Ambriz, Juan AS PER GLORIA SAENZ-NEED TO HAVE SOME BOARDS MOVED AND SOME PICTURE FRAMES HUNG.

Mary Garcia

49434					8/28/2009		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/28/2009 3:23:09 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Gonzales, Angel Need to repair blower

Juan Ambriz

49637		Office			9/3/2009		27		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	C-WING		9/3/2009 11:42:37 AM					
--------	------------------	--------	--	----------------------	--	--	--	--	--

Ambriz, Juan AS PER KARLA-NEED TO HAVE A PLAQUE HUNG UP IN MS. YTURRALDE'S OFFICE.

Mary Garcia

50169					9/16/2009		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/16/2009 10:29:54 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ambriz, Jose please replace heating/cooling unit in the board room.thanks (existing unit is old and needs replacement)

Michael Munoz

50254					9/18/2009		12		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	vehicle #140		9/18/2009 2:31:10 PM					
--------	------------------	--------------	--	----------------------	--	--	--	--	--

Gonzales, Angel Vehicle needs tune-up also transmission 4th gear not kicking in

Juan Ambriz

50412					9/22/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	A/C units		9/22/2009 3:54:41 PM					
--------	------------------	-----------	--	----------------------	--	--	--	--	--

Ambriz, Juan As per juan Need to Install p-traps for condensation in all units

Juan Ambriz

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

50562					9/28/2009		2		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/28/2009 8:44:10 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Briones, Enrique

Deliver to GAC
 PO #91001717 One box Selma Nevarez
 PO #91001686 One Box Rachel Rivera
 PO #91001485 Three boxes Sam Avalos
 PO # 91001491 One Box Sam Avalos
 PO #91000508 One Box Rachel Rivera
 PO # 91001484 One Box Selma Nevarez
 PO #91001486 One Box Rachel Rivera
 PO #91001157 One box to Lisa McCuller
 PO #91001741 Three boxes to Sam Gallegos
 PO #91001489 One box to Teresa Allen
 PO #91001158 One box to Lisa McCuller
 PO #91001545 Two boxes to Lesli Leyva
 PO # 91001156 On box to Julie Hernandez

Margaret Villalobos

50563	RTC				9/28/2009		2		\$0.00
-------	-----	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/28/2009 8:48:34 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Briones, Enrique

Deliver to RTC
 PO #91001251 (27) boxed to Julie Hinojosa--RTC

Margaret Villalobos

50569		Office			9/28/2009		2		\$0.00
-------	--	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	GAC A WING			9/28/2009 9:40:44 AM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Rodriguez, Arturo

AS PER ANNA - NEED TO HAVE SEVERAL BOXES
 TAKEN FROM HER OFFICE AND TO BE STORED IN
 THE SPECIAL ED SHED AT GAC.

Mary Garcia

50570		Office			9/28/2009		2		\$0.00
-------	--	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	GAC A WING			9/28/2009 9:41:51 AM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Ambriz, Juan

AS PER ANNA-NEED TO HAVE A DOLLING
 ASSEMBLED. (IT'S IN HER OFFICE)

Mary Garcia

50571	RTC	Office			9/28/2009		2		\$0.00
-------	-----	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	RTC ACROSS			9/28/2009 9:43:03 AM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Ambriz, Juan

AS PER GLORIA-NEED TO HAVE A CART
 ASSEMBLED. (IT'S IN HER OFFICE)

Mary Garcia

50666					9/30/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/30/2009 12:23:01 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Juan

Monthly - GAC A-16 Fan Exh Roof Semimonthly - Refer
 to PM schedule details.

Margret Villalobos

9/30/2009 6:01:21 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: GAC

50676		Office			9/30/2009		0		\$0.00
-------	--	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/30/2009 7:56:05 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Briones, Enrique

Pick up 4 boxes from the office of Vicki Lopez (at GAC) room 210, and deliver them to the office of Vicki Lopez at PPD.
Boxes include: 1 unopened case of paper, 2 small file boxes and 1 large file box all located near the AC unit in office at GAC.

Vicky Lopez

Count: 27 Work Orders		Avg. Age of WO's 36				Total for GAC	0		\$0.00
------------------------------	--	----------------------------	--	--	--	----------------------	----------	--	---------------

Location: Gadsden ES

49424					8/28/2009		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/28/2009 1:06:04 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos

when possible, please go ahead and do a walk thru off the new gadsden elementary and write down any deficiencies found or that need to be addressed on the work order so that construction can take care off before completion.

Michael Munoz

Count: 1 Work Orders		Avg. Age of WO's 33				Total for Gadsden ES	0		\$0.00
-----------------------------	--	----------------------------	--	--	--	-----------------------------	----------	--	---------------

Location: Gadsden HS

47097					7/5/2009		87		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			7/5/2009 12:20:59 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Holguin, Alfredo

Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.

Margret Villalobos

47387	Boys Gym	Gym			7/9/2009		83		\$0.00
-------	----------	-----	--	--	----------	--	----	--	--------

Medium	Work In Progress			7/9/2009 3:14:42 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ambriz, Jose

NEED TOW NEW HEATING UNIT AT THE BOYS GYM

Mario Apodaca

47398					7/9/2009		83		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			7/9/2009 3:46:30 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Castillo, Carlos

NEED TO SERVICE ALL OUTSIDE AND PARKING LOT LAMPS

Mario Apodaca

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

47466	Pool Dressing				7/13/2009		79		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/13/2009 10:50:25 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Villalobos, David Requested by Velia for Girl's Restroom at the Swimming Pool-Water faucet for the sink is leaking water and causing it to pool at the bottom of the sink. Potential hazard.

Velia Alarcon

47556					7/15/2009		77		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/15/2009 3:09:05 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe Requested by Velia for G.H.S. Campus-All grass needs to be mowed and weeds pulled from entire campus. Weeds are growing along side the edges of sidewalks and between cracks in sidewalks. Please complete before Wed., July 29, 2009. Freshman Orientation will take place this day and many parents and students will be on our campus.

Velia Alarcon

47816					7/24/2009		68		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/24/2009 2:49:12 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe Requested by Mr. Chambers for All G.H.S. Grounds-2ND REQUEST-All grass needs to be mowed and weeds pulled from entire campus. Some weeds are almost 5 feet tall in areas. Please complete before Wed., July 29, 2009. Freshman Orientation will take place this day and many parents and students will be on our campus.

Velia Alarcon

47903	Main Building	Office			7/28/2009		64		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/28/2009 7:58:49 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos Various fixtures in Main Building office area are in bad repair and need to be replaced. (2'x 4' lay-in style)

Albert Vallejo

47926					7/28/2009		64		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/28/2009 12:53:48 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Villalobos, David the weight room shower cabinet in the boys restroom is on good need to be replaces

Mario Apodaca

47937	New Vocational	Hallway/Corridor			7/28/2009		64		\$0.00
-------	----------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/28/2009 3:15:27 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben need a new glass door at the annex bldg do to vandalism (28x38) wire glass

Mario Apodaca

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

48433	Academic Bldg				8/6/2009		55		\$0.00
-------	---------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/6/2009 11:42:54 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph Requested by Ms. Howard Rm. 307 Academic Building-
Key isn't working to open classroom door.

Velia Alarcon

48436	Main Building				8/6/2009		55		\$0.00
-------	---------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/6/2009 11:52:46 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos Requested by Mr. Marquez Rm. 240 Main Building-An
electrical outlet is not working by teacher desk (counter).

Velia Alarcon

48438					8/6/2009		55		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/6/2009 12:01:38 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe Requested by Coach Yanez for Baseball Field-Extend
home dugout with a 4' fence. Already spoke with Lupe
Ontiveros who said materials are in the Grounds
Storage Facilities.

Velia Alarcon

48439					8/6/2009		55		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/6/2009 12:05:41 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Aldaz, Bobby Requested by Coach Yanez for Baseball Field-Cut out a
new warning track along 3rd base side and 1st base
side of the baseball field. Already spoke with Bob Aldaz
about the cut and he requested I put in a work order.

Velia Alarcon

48638	Old English Bldg				8/11/2009		50		\$0.00
-------	------------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/11/2009 10:35:20 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Apodaca, Mario Requested by Ms. Letz Rm. 155 Old English Building-
Please hang the bulletin strips in the gym. Please see
Ms. Letz for more instruction.

Velia Alarcon

48639	Old English Bldg				8/11/2009		50		\$0.00
-------	------------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/11/2009 10:36:58 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lara, Ralph Requested by Ms. Letz Rm. 155 Old English Building-
The equipment room door needs to be fixed in the locker
room.

Velia Alarcon

48640	Old English Bldg				8/11/2009		50		\$0.00
-------	------------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/11/2009 10:38:12 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lara, Ralph Requested by Ms. Letz Rm. 155 Old English Building-
The door between locker room and gym will not lock
properly, needs to be secured.

Velia Alarcon

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

48645		Athletic Field			8/11/2009		50		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/11/2009 11:21:53 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Aldaz, Bobby Need to replace front tires on Kubota Tractor

Guadalupe Ontiveros

48672	Boys Gym	Office			8/11/2009		50		\$0.00
-------	----------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/11/2009 3:30:19 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose need a new a/c window unit for the boys gym office 400

Mario Apodaca

48677	Vocational	Hallway/Corridor			8/11/2009		50		\$0.00
-------	------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/11/2009 3:43:45 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph need a exterior door hinge

Mario Apodaca

48739	North Building	Classroom			8/12/2009		49		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/12/2009 3:14:47 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David need a new faucets for room 222 n-bldg 4"spreader unit

Mario Apodaca

48741		Restroom (Girls)			8/12/2009		49		\$0.00
-------	--	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/12/2009 3:23:50 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David need new sink faucets put new in all of the restroom boys,girls and locker rooms

Mario Apodaca

48763	Academic Bldg				8/13/2009		48		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/13/2009 10:22:19 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Mr. Morales Rm. 337 Academic Building- It is very difficult to lock and unlock classroom door.

Velia Alarcon

48768	Business				8/13/2009		48		\$0.00
-------	----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/13/2009 10:42:45 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Ms. Thornley Rm. 660 Business Building- Need new lock or clean out the cylinder for north classroom door, was superglued! If cylinder needs to be replaced both north and south doors need to open with one same key. If new key is required three keys will be needed.

Velia Alarcon

48772	Old English Bldg	Classroom			8/13/2009		48		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/13/2009 12:26:20 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose A E/COOLER UNIT AT THE OLD ENG BLDG IS NOT WORK DO TO THE CONTROLS

Mario Apodaca

9/30/2009 6:01:21 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

48945	Old English Bldg	Dressing Room			8/18/2009		43		\$0.00
-------	------------------	---------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/18/2009 12:18:04 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
NEED TWO NEW DOOR FOR THE DRESSING ROOM AND LOCK SET.

Mario Apodaca

48982	Main Building				8/18/2009		43		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Computer Lab			8/18/2009 4:39:59 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Castillo, Carlos
Requested by Mr. Chambers for Rm. 121 Main Building- More power amperage is needed in room # 121. Breakers are tripping due to overload. A computer lab is being operated in this classroom.

Velia Alarcon

48983					8/18/2009		43		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/18/2009 4:43:08 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Requested by Velia for All Light Fixture Around the Boy's Gym-All light fixtures or light bulbs need to be checked, repaired, or replaced. Very dark especially on the west side of the gym where the Football players exist to go home after games.

Velia Alarcon

48985					8/18/2009		43		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/18/2009 4:47:56 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben
Requested by Ms. Leahy Rm. 127 Main Building-Please install mini-blinds in my classroom. Need (2) 106' W X 35' L

Velia Alarcon

49154					8/21/2009		40		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/21/2009 3:57:52 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Requested by Velia for Bus Turn Around-Replace all the light bulbs on the bus turn around. It is very dark in the evening when parents or students are walking the student parking lot where their vehicles are parked. Very dark and could be a safety issue. If possible install light posts on the west side of the bus turn around. This will help parents drive in through the bus turn around to pick up their child(ren) after an athletic event or field trip late at night.

Velia Alarcon

49173					8/24/2009		37		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/24/2009 9:44:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert
Requested by Velia for Lab A in the Computer Lab- Please replace several light bulbs that are burned out in Lab A.

Velia Alarcon

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

49225					8/25/2009		36		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/25/2009 8:16:03 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Briones, Enrique
On August 31, 2009, please pick-up obsolete technology items (Computer Towers and Monitors) from Gadsden High School)

Yolie Jacquez

49631	North Building				9/3/2009		27		\$0.00
-------	----------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/3/2009 8:55:42 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Villalobos, David
Requested by Ms. Aguilar Rm. 236 North Building-Water faucet in girl's dressing room stays on and leaks. When the water is enough it flows under the wall and puddles in the middle of the floor. Blind students are assigned to this classroom and is a safety issue.

Velia Alarcon

49632	Business				9/3/2009		27		\$0.00
-------	----------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/3/2009 9:35:31 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Vallejo, Albert
Requested by Mr. Grace on behalf of the Facilities Goal Team for the Business Building-Lockers located in the hallway of the Business Building need to be removed and placed in the P.E. locker room.

Velia Alarcon

49799					9/6/2009	9/14/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:50 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Apodaca, Mario
Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

49928					9/10/2009		20		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/10/2009 12:29:10 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Villalobos, David
NEED TO PUT A NEW HOSEBIB OUTSIDE THE ANNEX BLDG

Mario Apodaca

50011					9/11/2009		19		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/11/2009 3:41:53 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph
Requested by Ms. Moreno Rm. 126 Main Building-WORK ORDER # 38294 HAS NOT BEEN COMPLETED-SECOND WORK ORDER-The door has fallen and hard to close. The door also gets stuck and students can not get exit classroom. This is a problem during fire drills.

Velia Alarcon

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

50039					9/14/2009		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/14/2009 12:20:05 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Jacquez, Ricardo Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.

Margret Villalobos

50273	Business	Classroom			9/18/2009		12		\$0.00
-------	----------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/18/2009 3:54:13 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos in rm 603, mr grace, the light swich controls the outlet to the computer and shuts off computer when switch is turned off, also the outlets on the north and west wall do not work. could you please check and correct. thanks

Michael Munoz

50281					9/20/2009		10		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/20/2009 12:18:49 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ontiveros, Guadalupe Monthly - Gadsden HS Soil Sampling - Refer to PM schedule details.

Margret Villalobos

50317					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/21/2009 11:29:58 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Munoz, Michael need to pour new side walk for student in wheel chair between concession stand and old english.

Joe Munoz

50320	Business	Hallway/Corridor			9/21/2009		9		\$0.00
-------	----------	------------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/21/2009 12:43:20 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Gonzalez, Salvador NEED TO WELD THE DOOR HINGE TO A DOOR FRAME AT THE BUS BLDG BOT FLOOR S/SIDE

Mario Apodaca

50323	North Building				9/21/2009		9		\$0.00
-------	----------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/21/2009 1:18:38 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe THE RAIN WATER IS STANDING ON THE SIDEWAIK OUTSIDE WEST SIDE ENTER OF THE N-BLDG NEED A NEW RAIN PIT . A.S.A.P DO TO THE A.D.A

Mario Apodaca

50324					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/21/2009 1:50:22 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Vallejo, Albert NEED TO REPAIR SOFFITT ??? (OVERHANG) BY MAIN BUILDING ON SOUTH SIDE OF BLDG.

Michael Munoz

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

50365					9/22/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/22/2009 9:19:30 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Apodaca, Mario Requested by Mr. Grace on behalf of the Facilities Goal Team for the Entire Campus-Metal doors, rails, and poles need to be painted maroon.

Velia Alarcon

50392					9/22/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/22/2009 2:47:00 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Coach A. Lopez for Varsity Softball Field- Replace/fit/adjust back stalk fence. Top and bottom sections bent - open.

Velia Alarcon

50393	Main Building				9/22/2009		8		\$0.00
-------	---------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/22/2009 2:47:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Apodaca, Mario Requested by Ms. Jaraba Rm. 124 Main Building- Screen placed in front of room.

Velia Alarcon

50493	North Building	Classroom			9/24/2009		6		\$0.00
-------	----------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	228			9/24/2009 3:08:49 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Villalobos, David 2 gal. water heater needs to be replaced

Albert Vallejo

50494					9/24/2009		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/24/2009 3:11:36 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael Fence in north field has been knocked down and stretched to the point that it will no longer be tall enough to be refastened. Needs to be replaced. Approximately 6' x 120' chain link.

Albert Vallejo

50526	North Building	Custodial			9/25/2009		5		\$0.00
-------	----------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/25/2009 2:53:41 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David THE MOP SINK IN THE COUSTODIAL ROOM 212 AT THE N-BLDG IS BACKING -UP

Mario Apodaca

50583	North Building				9/28/2009		2		\$0.00
-------	----------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/28/2009 2:27:16 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Requested by Mr. Palmer Rm. 229 North Building- Replace water heater under sink.

Velia Alarcon

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

50637					9/29/2009		1		\$0.00
Medium	Work In Progress	Grounds Shop		9/29/2009 1:15:04 PM					
Villalobos, Margret		A swarm of Bees going into Grounds Shop.				9/29 1:24pm - Called Susan w/PC and they will send someone out this afternoon to check it out.			
Albert Vallejo									
50639	Vocational	Classroom			9/29/2009		1		\$0.00
Medium	Work In Progress			9/29/2009 2:15:40 PM					
Castillo, Carlos		As per M.Munoz ,several receptacles in room 603 are not working.Need to corrcet situation.							
Carlos Castillo									
50669					9/30/2009		0		\$0.00
Medium	Work In Progress			9/30/2009 12:23:03 AM					
Apodaca, Mario		Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
50681		Athletic Field			9/30/2009		0		\$0.00
Medium	Work In Progress	Grounds Truck		9/30/2009 8:37:59 AM					
Gonzales, Angel		Truck #122 needs battery to be replaced							
Guadalupe Ontiveros									
50682		Athletic Field			9/30/2009		0		\$0.00
Medium	Work In Progress	Grounds Truck		9/30/2009 8:41:15 AM					
Gonzales, Angel		Truck #137 battery needs to be replaced.							
Guadalupe Ontiveros									
50686	Varsity Gym				9/30/2009		0		\$0.00
Medium	Work In Progress			9/30/2009 10:24:09 AM					
Lara, Ralph		Need to replace panic bars at Varsity Gym.							
Albert Vallejo									
Count: 56 Work Orders		Avg. Age of WO's 35		Total for Gadsden HS			0	\$0.00	

Location: Gadsden MS

47300	C-Wing				7/6/2009		86		\$0.00
Medium	Work In Progress	Athletic Portable		7/6/2009 3:25:05 PM					
Lozoya, Manny		Please issue keys for Athletic Portable as follows: Norma Alvarado - WA88, V3 Terry Alvarado - WA88 Also please core doors the same - WA88							
Terry Alvarado									

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

47542	C-Wing	Portables			7/15/2009		77		\$0.00
-------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/15/2009 7:05:10 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Athletic Portable - Need to install a mail slot for vehicle packets to be dropped.

Priscilla Guterrez

47892					7/27/2009		65		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	GMS Campus			7/27/2009 4:49:37 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Diaz, Sebastian
Replace tile throughout hallways as needed.

Maricruz Carrasco

47893					7/27/2009		65		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Staff			7/27/2009 4:56:25 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Set up doors in Staff Restrooms. See Mrs. Williams for more information.

Maricruz Carrasco

47996	Cafeteria	Cafeteria			7/29/2009		63		\$0.00
-------	-----------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/29/2009 1:55:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Diaz, Sebastian
MAINTENANCE: REPAIR CRACKS TO 1) DRY STORAGE AREA, 2) DOORS TO SERVING LINE.

(AS PER STATE ENVIRONMENT DEPT. INSPECTOR)

Jacqueline Aguilar

48042					7/30/2009		62		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/30/2009 12:46:38 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Estrada, Jesus
ROOM 156 (CONTAINS ASBESTOS) NEEDS VCT REPLACED - PRIORITY FAXED TO MICHAEL - 7/30/09

Richard Chavez

48135					8/2/2009	8/18/2009	59		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				8/2/2009 12:20:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Margret
Yearly - Gadsden MS August Chiller Insp. - Refer to PM schedule details.

Margret Villalobos

48336	Cafeteria	Cafeteria			8/4/2009		57		\$0.00
-------	-----------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/4/2009 3:23:04 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Moncayo, Fernando
NEED MOP SINK

TERRY PORTILLO SNP MGR 882-2824

Jacqueline Aguilar

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

48345		Classroom			8/4/2009		57		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Awing/148/Baca			8/4/2009 3:45:52 PM				
--------	------------------	----------------	--	--	---------------------	--	--	--	--

Lozoya, Manny		Fix handle on door.							
---------------	--	---------------------	--	--	--	--	--	--	--

Maricruz Carrasco

48347	C-Wing	Office			8/4/2009		57		\$0.00
-------	--------	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Cwing/JPO			8/4/2009 3:47:13 PM				
--------	------------------	-----------	--	--	---------------------	--	--	--	--

Lozoya, Manny		Change lock on JPO Office in Cwing.							
---------------	--	-------------------------------------	--	--	--	--	--	--	--

Maricruz Carrasco

48349		Classroom			8/4/2009		57		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Awing/180			8/4/2009 3:48:18 PM				
--------	------------------	-----------	--	--	---------------------	--	--	--	--

Lozoya, Manny		Need a lock on door, has temporary lock WA-52							
---------------	--	---	--	--	--	--	--	--	--

Maricruz Carrasco

48431		Office			8/6/2009		55		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Vocational/304/3			8/6/2009 11:32:06 AM				
--------	------------------	------------------	--	--	----------------------	--	--	--	--

Lozoya, Manny		Make the same key for both rooms							
---------------	--	----------------------------------	--	--	--	--	--	--	--

Maricruz Carrasco

48448					8/6/2009		55		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/6/2009 1:17:08 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny		NEED TO HAVE FIRE EXTINGUISHERS SERVICED							
---------------	--	--	--	--	--	--	--	--	--

Danny Orozco

48464		Office			8/6/2009		55		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Counselor's			8/6/2009 3:46:53 PM				
--------	------------------	-------------	--	--	---------------------	--	--	--	--

Lozoya, Manny		Need to change lock on filing cabinet.							
---------------	--	--	--	--	--	--	--	--	--

Maricruz Carrasco

48465		Library			8/6/2009		55		\$0.00
-------	--	---------	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/6/2009 3:47:43 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny		Library front doors not locking.							
---------------	--	----------------------------------	--	--	--	--	--	--	--

Maricruz Carrasco

48483	C-Wing	Office			8/7/2009		54		\$0.00
-------	--------	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	GMS Portable			8/7/2009 9:28:58 AM				
--------	------------------	--------------	--	--	---------------------	--	--	--	--

Lozoya, Manny		AS PER MR. CHAVEZ-HAS APPROVED TO ISSUE OUT A GATE KEY TO NORMA ALVARADO FOR NOW.							
Mary Garcia						REMINDER - NORMA WILL RETURN KEY WHEN NEW GATE GETS INSTALLED BY PHYSICAL PLANT. SHE WILL HAVE NO NEED FOR A GATE KEY THEN.			

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

48498	C-Wing	Portables			8/7/2009		54		\$0.00
-------	--------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/7/2009 12:01:25 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny I need J3 - 8 keys for the side gate that leads to the transportation department for access to the vehicles

Terry Alvarado

48901	Gym	Gym			8/17/2009		44		\$0.00
-------	-----	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Gym			8/17/2009 12:55:31 PM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lozoya, Manny

1. Core missing-WA62
2. Gym door striker is missing.
3. Gym storage core is missing.
4. Core missng in Dr. Garcia's office-M36

Maricruz Carrasco

49011	C-Wing				8/19/2009		0		\$0.00
-------	--------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				8/19/2009 11:35:15 AM	8/19/2009			
--------	------------------	--	--	--	-----------------------	-----------	--	--	--

Sotelo, Enrique Need to check all lighting exit/emergency lighting throughout bldg a/s/a/p.

Michael Munoz

49060	C-Wing				8/20/2009		41		\$0.00
-------	--------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/20/2009 8:43:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Between C-Wing and GMS West Parking Lot need to level out with gravel. (See Mike)

Michael Munoz

49127					8/21/2009		40		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				8/21/2009 2:10:22 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael please paint cross walk in front of main entrance where new fence will be installed.

Ralph Gallegos

49130					8/21/2009		40		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Staff Parking Lot			8/21/2009 2:18:21 PM				
--------	------------------	-------------------	--	--	----------------------	--	--	--	--

Diaz, Sebastian Need parking spaces in GMS Staff parking to be labeled.

Maricruz Carrasco

49199					8/24/2009		37		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/24/2009 3:40:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo having problems changing filters to units around A and B wings. They get stuck when pulling them out. please have HVAC tech take a look at it.

Sebastian Diaz

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden MS

49428	Cafeteria	Cafeteria			8/28/2009		33		\$0.00
-------	-----------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/28/2009 2:21:08 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Sotelo, Enrique INSTALL A CEILING FAN IN THE STORAGE ROOM.

DEMETRIOUS P. GIOVAS SNP DIRECTOR 882-6771

Jacqueline Aguilar

49482	C-Wing	Portables			8/31/2009		30		\$0.00
-------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/31/2009 10:55:19 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lozoya, Manny The outside door handle is broken. Can't unlock it .
Thanks Colleen

Colleen Runyan

49537	Cafeteria	Cafeteria			9/1/2009		29		\$0.00
-------	-----------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/1/2009 1:13:50 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Orozco, Danny REACH IN FREEZER DOWN

TERRY PORTILLO SNP MGR 882-2824

Jacqueline Aguilar

49826					9/8/2009		22		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/8/2009 7:39:52 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ontiveros, Joe please check for water supply inside cinder block area
between metal canopies.thanks

Michael Munoz

49918		Pump House			9/10/2009		20		\$0.00
-------	--	------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/10/2009 8:19:52 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Jacquez, Ricardo need to have water tank level sing fixed does not go
back up on its own. thanks

Ricardo Jacquez

49950	Vocational				9/10/2009		20		\$0.00
-------	------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/10/2009 3:46:09 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny need 2 fence keys for elevate program.thanks(jacob
sanchez,irene najera) j-3

Michael Munoz

50040					9/14/2009		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/14/2009 12:20:06 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Jacquez, Ricardo Monthly - Gadsden MS-WWTP Chemical Order
(Monthly) - Refer to PM schedule details.

Margret Villalobos

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

50043					9/14/2009		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/14/2009 8:14:36 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Jacquez, Ricardo		need to fix leak at flush hydrant at bus trun around thanks							
------------------	--	---	--	--	--	--	--	--	--

Ricardo Jacquez

50110					9/15/2009		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/15/2009 8:36:10 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Barrientos, Manuel		please assit w/ removal of concrete curb on the buss turn around.thankyou							
--------------------	--	---	--	--	--	--	--	--	--

Michael Munoz

50142		Office			9/15/2009		15		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Attendance/roo			9/15/2009 3:36:37 PM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Solis, Lorenzo		Air conditioner not working.							
----------------	--	------------------------------	--	--	--	--	--	--	--

Maricruz Carrasco

50160					9/16/2009		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/16/2009 8:47:30 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Jacquez, Ricardo		please ck irrigation system for proper operation and please ck back flow thanks.							
------------------	--	--	--	--	--	--	--	--	--

Ricardo Jacquez

50213					9/16/2009		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Cafeteria and			9/16/2009 4:16:31 PM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Lozoya, Manny		Please check doors (outside) to Bwing and Cafeteria. Very hard to open (keep gettings stuck.) Not a key problem but a door problem. Thank you!							
---------------	--	--	--	--	--	--	--	--	--

Maricruz Carrasco

50269					9/18/2009		12		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/18/2009 3:44:36 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique		Need to replace out side lights by the gym thank you							
-----------------	--	--	--	--	--	--	--	--	--

Sebastian Diaz

50277		Office			9/18/2009		12		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Annex/399/Secu			9/18/2009 4:41:52 PM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Lozoya, Manny		Need a lock on the door between Security office and Ms. Rasura's classroom (400). Door needs to be secured. No teachers or students should have access to Security office.							
---------------	--	--	--	--	--	--	--	--	--

Maricruz Carrasco

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

50278		Portables			9/18/2009		12		\$0.00
Medium	Work In Progress	Portable/C-			9/18/2009 4:43:43 PM				
Lozoya, Manny		1. POA office change lock on door to match other door-WA-98. 2. Put locks on 2 filing cabinets.							
<u>Maricruz Carrasco</u>									
50377	Gym	Office			9/22/2009		8		\$0.00
Medium	Work In Progress	Boys lockerroom			9/22/2009 12:46:51 PM				
Lozoya, Manny		Change lock in PE equipment room to be able to open with master.							
<u>Maricruz Carrasco</u>									
50397	C-Wing	Portables			9/22/2009		8		\$0.00
Medium	Work In Progress	ATHLETICS			9/22/2009 3:10:55 PM				
Lara, Ralph		TO FIX INSIDE HINGE FOR SAFE IN ATHLETIC OFFICE. NEED TO SECURE VEHICLE KEYS AND OTHER ITEMS.							
<u>Terry Alvarado</u>									
50439					9/23/2009		7		\$0.00
Medium	Work In Progress				9/23/2009 1:06:17 PM				
Villalobos, David		As per Mike, Line locate next to Sebastians Morgan Bldg. Eastside of fence.							
<u>Michael Munoz</u>									
50440					9/23/2009		7		\$0.00
Medium	Work In Progress				9/23/2009 1:30:03 PM				
Ontiveros, Joe		please provide water source by morgan bldg. need a hose bibb and a valve for point of coneectuion.please see mike.thanks							
<u>Michael Munoz</u>									
50530					9/25/2009		5		\$0.00
Medium	Work In Progress				9/25/2009 3:02:05 PM				
Diaz, Sebastian		Need two conectors 3/4 and wet dry # 725							
<u>Sebastian Diaz</u>									
50548	Vocational				9/25/2009		5		\$0.00
Medium	Work In Progress	Vocational/304/3			9/25/2009 4:44:46 PM				
Lozoya, Manny		Fix locks in 304 and 305. Having problems with them.							
<u>Maricruz Carrasco</u>									

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden MS

50560	Cafeteria	Cafeteria			9/28/2009		2		\$0.00
Medium	Work In Progress				9/28/2009 8:34:50 AM				
Orozco, Danny	BOTH TOP OVENS ARE NOT WORKING								

TERESA PORTILLO SNP MGR 882-2824

Jacqueline Aguilar

50645	C-Wing	Office			9/29/2009		1		\$0.00
Medium	Work In Progress	207-c			9/29/2009 3:14:48 PM				
Solis, Lorenzo	We are burning up! Thermostat doesn't display a temp. We turned it off for 5 min then back on and it still doesn't work...blows hot air! Thanks, Colleen								

Colleen Runyan

50673					9/30/2009		0		\$0.00
Medium	Work In Progress				9/30/2009 12:23:04 AM				
Diaz, Sebastian	Monthly - Gadsden MS A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								

Margret Villalobos

50684	West	Mechanical			9/30/2009		0		\$0.00
Medium	Work In Progress				9/30/2009 9:37:03 AM				
Solis, Lorenzo	loosing pressure on chiller, please check asap.								

Sebastian Diaz

50690					9/30/2009		0		\$0.00
Medium	Work In Progress				9/30/2009 2:37:21 PM				
Ontiveros, Guadalupe	Asp conversation this morning, please deliver 2 buckets of compost and 2 of sand for the Elevate Program, by Sebas Morgan.								

Michael Munoz

Count: 49 Work Orders	Avg. Age of WO's	32	Total for Gadsden MS	0	\$0.00
------------------------------	-------------------------	-----------	-----------------------------	----------	---------------

Location: La Union - JTP Alvarez Farms

47763		Restroom (Girls)			7/23/2009		69		\$0.00
Medium	Work In Progress				7/23/2009 9:39:55 AM				
Lara, Ralph	Fix door to girls bathroom at LUJTP Contact Person Sam Avalos or Margaret S. Villalobos								

Margaret Villalobos

Count: 1 Work Orders	Avg. Age of WO's	69	Total for La Union - JTP Alvarez Farms	0	\$0.00
-----------------------------	-------------------------	-----------	---	----------	---------------

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: La Union ES

48670					8/11/2009		50		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/11/2009 3:27:43 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Aguilar, Patricio need to replace faucet in kids rest room ec#210 - assign to me

Patricio Aguilar

50442					9/23/2009		7		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/23/2009 1:53:41 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Aguilar, Patricio w.o. for myself - need covers for a/c winter close down

Patricio Aguilar

50685					9/30/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/30/2009 9:57:27 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Sotelo, Enrique please replace broken cover on ground for technology j-box, for safety. close to portable 500. thank you.

Sebastian Diaz

Count: 3 Work Orders	Avg. Age of WO's 19	Total for La Union ES	0	\$0.00
-----------------------------	----------------------------	------------------------------	----------	---------------

Location: Loma Linda ES

47153					7/5/2009	7/26/2009	87		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			7/5/2009 12:21:21 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Orozco, Danny Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

47608		Custodial			7/20/2009		72		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/20/2009 8:08:16 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Joe We have a water leak coming from the wall in custodial office.

Rudy Arreola

47847		Classroom			7/27/2009		65		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/27/2009 9:59:33 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny Door in Rm 208 is hard to lock need to have cylinder checked out.

Rudy Arreola

47980		Cafeteria			7/29/2009		63		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/29/2009 10:28:15 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Orozco, Danny FLOOR TILES NEED TO BE REPLACED.

FRANCES B. SNP MGR 882-4707

Jacqueline Aguilar

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Loma Linda ES

48869	Main Building	Classroom			8/17/2009		44		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/17/2009 9:37:50 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Arreola, Rudy
Please replace light bulbs in RM 327, teacher is Ms. Blancas she states bulbs are out.

Claudia Rodriguez

49095	Main Building	Office			8/21/2009		40		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/21/2009 8:16:59 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Arreola, Rudy
Counter gate in front office does not close. It is stuck. Please check. Thank you.

Claudia Rodriguez

49285	Main Building	Classroom			8/26/2009		35		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/26/2009 9:03:35 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Estrada, Jesus
Please replace carpet edge strip in RM 330. Teacher is Ms. Evans. Thank you. 9/3/09 - FAXED TO MICHAEL

Claudia Rodriguez

49293	Main Building	Classroom			8/26/2009		35		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/26/2009 12:09:20 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lozoya, Manny
Need a key for filing cabinet in RM 317. Teacher is Ms. Gutierrez.

Claudia Rodriguez

49441					8/28/2009		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/28/2009 3:34:44 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David
Need to coordinate w/Bldg Mechanic and Joe Ontiveros on proper training for newer water heaters.

Michael Munoz

49521					9/1/2009		29		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/1/2009 7:40:27 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Briones, Enrique
On September 2, 2009, please pick-up two (2) boxes of old, out-of-adoption textbooks.

Yolie Jacquez

49873	Main Building	Classroom			9/9/2009		21		\$0.00
-------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/9/2009 9:44:43 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lozoya, Manny
We have 4 classrooms that the door is hard to close due to the fact that it hits the frame when you try to close it. Please check RM's 206(Berard), 208 (Smith), 211 (Armendariz), 201 (Mr. Arreola's office). Thank you

Claudia Rodriguez

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Loma Linda ES

49874	Main Building	Classroom			9/9/2009		21		\$0.00
-------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/9/2009 9:48:49 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lozoya, Manny
Please check and replace door handle in RM 207. The teacher is Ms. Medina and she states the door handle is broken. Thank you.

Claudia Rodriguez

50072					9/14/2009		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/14/2009 1:55:23 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Sotelo, Enrique
Emergency light not working in boys rr. 2nd grade wing.

Rudy Arreola

50074	Main Building	Restroom (Girls)			9/14/2009		16		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/14/2009 1:57:06 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Sotelo, Enrique
Emergency light not working in bathroom.

Rudy Arreola

50099	Main Building	Classroom			9/14/2009		16		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/14/2009 3:57:01 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Arreola, Rudy
Please check backpack hooks and reinstall if necessary. Teacher is Ms. Medina RM 207. Thank you.

Claudia Rodriguez

50111	Main Building	Library			9/15/2009		15		\$0.00
-------	---------------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/15/2009 8:43:20 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Arreola, Rudy
Please check the rubber strip between carpet and tile (in the library). The strip is lifting and needs to be glued down. Thank you.

Claudia Rodriguez

50291					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/21/2009 8:10:15 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Solis, Lorenzo
Please ck unit in server room.

Richard Santillano

50390	Main Building				9/22/2009		8		\$0.00
-------	---------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/22/2009 2:27:30 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben
Broke plastic slide guard. Donnie is aware and is looking for one.

Rudy Arreola

50610	Main Building	Classroom			9/29/2009		1		\$0.00
-------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/29/2009 7:57:29 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben
Broken window in rm 213. Size is 28-3/4X 28-3/4. single pane window.

Rudy Arreola

9/30/2009 6:01:22 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Loma Linda ES

50623	Main Building	Hallway/Corridor			9/29/2009		1		\$0.00
Medium	Work In Progress			9/29/2009 8:45:31 AM					
Ronquillo, Ruben	Broken window 30X47 3/4 single pane window.								

Rudy Arreola

50672					9/30/2009		0		\$0.00
Medium	Work In Progress			9/30/2009 12:23:04 AM					

Arreola, Rudy Monthly - Loma Linda ES A16(Fan Exh.)(S.Anual) - Refer to PM schedule details.

Margret Villalobos

Count: 21 Work Orders	Avg. Age of WO's 30	Total for Loma Linda ES	0	\$0.00						
------------------------------	----------------------------	--------------------------------	----------	---------------	--	--	--	--	--	--

Location: Mesquite ES

47219					7/5/2009	7/13/2009	87		\$0.00
Medium	Work In Progress			7/5/2009 12:21:45 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								

Margret Villalobos

47220					7/5/2009	7/11/2009	87		\$0.00
Medium	Work In Progress			7/5/2009 12:21:45 AM					

Ramirez, Joe Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.

Margret Villalobos

47221					7/5/2009	7/13/2009	87		\$0.00
Medium	Work In Progress			7/5/2009 12:21:45 AM					

Ramirez, Joe Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

47222					7/5/2009	7/13/2009	87		\$0.00
Medium	Work In Progress			7/5/2009 12:21:46 AM					

Ramirez, Joe Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

47223					7/5/2009	8/5/2009	87		\$0.00
Medium	Work In Progress			7/5/2009 12:21:46 AM					

Ramirez, Joe Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.

Margret Villalobos

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

47224					7/5/2009	8/5/2009	87		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				7/5/2009 12:21:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe		Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

49374	2003 Classroom				8/27/2009		34		\$0.00
-------	----------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room # 305			8/27/2009 2:56:42 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Estrada, Jesus		Larry Sedillo, needs floor tiles replaced stained by urine.							
----------------	--	---	--	--	--	--	--	--	--

Sandra Mora

49635		Cafeteria			9/3/2009		27		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/3/2009 10:14:42 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		BATHROOM EXHAUST FAN NOT WORKING							
---------------	--	----------------------------------	--	--	--	--	--	--	--

Danny Orozco

49796					9/6/2009	9/14/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				9/6/2009 12:22:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

49797					9/6/2009	9/14/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				9/6/2009 12:22:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

49843		Library			9/8/2009		22		\$0.00
-------	--	---------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Library			9/8/2009 1:45:21 PM				
--------	------------------	---------	--	--	---------------------	--	--	--	--

Ramirez, Joe		Library to be painted during Fall Break. Color Chart will be picked up by Phillip so that the school can make a choice.							
--------------	--	---	--	--	--	--	--	--	--

Phillip Medina

50042					9/14/2009		16		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/14/2009 7:56:28 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo		water leak in the water supply line from the furnace to the heater needs to be repaired it is damageing the ceiling tiles.							
----------------	--	--	--	--	--	--	--	--	--

Joe Ramirez

50170		Library			9/16/2009		14		\$0.00
-------	--	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/16/2009 10:33:06 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		as per our meeting today, lets proceed w/ painting of the library during fall break.thanks							
--------------	--	--	--	--	--	--	--	--	--

 Joe Munoz

9/30/2009 6:01:22 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Mesquite ES

50215					9/17/2009		13		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/17/2009 7:53:55 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben we have a cracked tubular slide that needs to be replaced a.s.a.p. as per mr. montano it is a safety hazard.

Joe Ramirez

50288					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/21/2009 7:51:43 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben As per Montano, he would like the window to be replaced for the safety of the students. Portable # 610, stolen radio J. Ramirez,Bldg Mechanic.. (case# 2009-0925) Juan Flores Est Damage 1000.00

Luis Saucedo

50315		Library			9/21/2009		9		\$0.00
-------	--	---------	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/21/2009 11:26:39 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Sotelo, Enrique please install 3 electrical plugs on the north wall of library.please see mike.thanks

Michael Munoz

50622					9/29/2009		1		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/29/2009 8:29:43 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Martinez, Larry On October 5, 2009, please pick-up a number of obsolete, broken, computers from Mesquite Elementary. Location: Hallway Storage.

Yolie Jacquez

50668					9/30/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/30/2009 12:23:02 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.

Margret Villalobos

Count: 18 Work Orders			Avg. Age of WO's 40			Total for Mesquite ES	0		\$0.00
------------------------------	--	--	----------------------------	--	--	------------------------------	----------	--	---------------

Location: North Valley ES

47099					7/5/2009		87		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			7/5/2009 12:21:00 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Holguin, Alfredo Monthly - North Valley ES-Fire Pump PM (Quarterly) - 8/27/09 - e-mailed to Rick Refer to PM schedule details.

Margret Villalobos

47963					7/29/2009		63		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/29/2009 8:06:58 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny library door will not lock (west side)please ck out

Danny Vega

9/30/2009 6:01:22 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: North Valley ES

47968		Classroom			7/29/2009		63		\$0.00
Medium	Work In Progress	room 210		7/29/2009 8:39:11 AM					
Lozoya, Manny		Broken file cabinet lock.							
Priscilla Martinez									
48061					7/30/2009		62		\$0.00
Medium	Work In Progress			7/30/2009 3:33:30 PM					
Solis, Lorenzo		ROOF-TOP ERV UNIT MAKING LOUD NOISE- PLEASE RE -CK FOR SOURCE OF NOISE .ALL LOOKS WELL ON UNIT-BEARING AND BELT OK							
Danny Vega									
48986					8/19/2009		42		\$0.00
Medium	Work In Progress			8/19/2009 7:31:35 AM					
Gonzalez, Salvador		need to weld chains on parent-drop-off gates /weld chain to gate/need to bring chain with you.have bus drop -off gates also.asap							
Danny Vega									
49108					8/21/2009		40		\$0.00
Medium	Work In Progress			8/21/2009 10:03:54 AM					
Gonzalez, Salvador		need to install gate wheels on parent drop off and main entrance gates. swing out type gates.							
Javier Parra									
49195		Mechanical			8/24/2009		37		\$0.00
High	Work In Progress			8/24/2009 3:31:11 PM					
Sotelo, Enrique		as per boiler inspector need to install manual shut-offs inside boiler rooms close to the door, cover guards and identification tag for boilers serial #s K07h00203547 and k07h00203548							
Michael Munoz									
49197					8/24/2009		37		\$0.00
High	Work In Progress			8/24/2009 3:34:19 PM					
Sotelo, Enrique		(boiler room) as per bolier inspector, boiler needs to be hardwired to a junction box. (boiler serail # k07h00203547. thankyou							
Michael Munoz									
49465					8/31/2009		30		\$0.00
Medium	Work In Progress			8/31/2009 7:47:03 AM					
Lozoya, Manny		library door will not secure-core is turning all the way (west side by conf. rm)							
Danny Vega									

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: North Valley ES

49538					9/1/2009		29		\$0.00
Medium	Work In Progress				9/1/2009 1:52:44 PM				
Orozco, Danny		Annual Operational Inspection of Fire Pump.							
<u>Danny Orozco</u>									
49633		Parking Lot			9/3/2009		27		\$0.00
Medium	Work In Progress				9/3/2009 9:41:03 AM				
Vega, Danny		Need red paint to paint fire lanes and also signs regarding fire lanes.							
<u>Priscilla Martinez</u>									
50591					9/28/2009		2		\$0.00
Medium	Work In Progress				9/28/2009 3:32:22 PM				
Lozoya, Manny		door closure in organ trail wing /leaked oil out /has no adjustments/need new door closure installed							
<u>Danny Vega</u>									
Count: 12 Work Orders		Avg. Age of WO's 43				Total for North Valley ES	0		\$0.00

Location: Northern On-Track Pre-K (LM)

49170					8/24/2009		37		\$0.00
Medium	Work In Progress				8/24/2009 9:42:11 AM				
Sotelo, Enrique		girls restrooms on east hallway-emergency ballast is burnt-need to replace .has old sytle lamps on it .							
<u>Danny Vega</u>									
49578					9/2/2009		28		\$0.00
Medium	Work In Progress				9/2/2009 9:45:42 AM				
Ontiveros, Joe		LENCO ELECTRIC BUSTED SPRINKLER MAINS, NEEDS TO BE REPAIRED.							
<u>Adam Montoya</u>									
49636					9/3/2009		27		\$0.00
Medium	Work In Progress				9/3/2009 10:53:20 AM				
Vega, Danny		CEILING TILE FELL OFF 12 X 12, SOME ARE LOOSE							
<u>Adam Montoya</u>									
50389					9/22/2009		8		\$0.00
Medium	Work In Progress				9/22/2009 2:19:40 PM				
Lozoya, Manny		newly installed bus turn around gates /need chains and locks on them to secure school campus.drop of with adam or pando total of 3ea							
<u>Danny Vega</u>									

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Northern On-Track Pre-K (LM)

50415		Parking Lot			9/22/2009		8		\$0.00
Medium	Work In Progress	LA MESA PRE-			9/22/2009 3:59:42 PM				
Ronquillo, Ruben	AS PER ROSIE REYES-NEED TO HAVE TWO SIGNS MAKED "NO PARKING IN THIS AREA" PLEASE CALL HER BEFORE MAKING SIGNS TO MAKE SURE THAT'S WHAT SHE NEEDS TO BE SAID ON THOSE SIGNS @ 233-3475.		APPROVED BY MR. RICHARD G. CHAVEZ.						

Mary Garcia

50432					9/23/2009		7		\$0.00
Medium	Work In Progress				9/23/2009 10:46:07 AM				
Ronquillo, Ruben	RUBEN RONQUILLO PLEASE PICK UP WATER DISPENSERS								

Adam Montoya

50632					9/29/2009		1		\$0.00
Medium	Work In Progress				9/29/2009 10:03:37 AM				
Solis, Lorenzo	REMOTE BURNED OUT IN SERVER ROOM								

Adam Montoya

Count: 7 Work Orders	Avg. Age of WO's 17	Total for Northern On-Track Pre-K (LM)	0	\$0.00
-----------------------------	----------------------------	---	----------	---------------

Location: Physical Plant Complex

47290	Purchasing				7/6/2009		86		\$0.00
Medium	Work In Progress				7/6/2009 10:27:57 AM				
Munoz, Michael	PPD Main Entrance - Build designate Handicap Parking area and no parking area								

Alfredo Holguin

47292	Maintenance				7/6/2009		86		\$0.00
Medium	Work In Progress				7/6/2009 10:30:38 AM				
Munoz, Michael	Designate build handicap and visitors parking in front of Maint Bldg.								

Alfredo Holguin

47320					7/7/2009		85		\$0.00
Medium	Work In Progress				7/7/2009 10:07:11 AM				
Munoz, Michael	Relocate Food Service Morgan building to area between SNP warehouse and Maintenance shops								

Alfredo Holguin

48275					8/4/2009		57		\$0.00
Medium	Work In Progress				8/4/2009 8:52:13 AM				
Lozoya, Manny	As Per Alfredo, Need to make a gate key (J3) for Terry Portillo Gadsden Middle School SNP Manager.								

Alfredo Holguin

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

48795	Food Services				8/14/2009		47		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

High	Work In Progress				8/14/2009 8:06:35 AM				
------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando could you please repair or replace existing gutters. when it rains it is very hard to load trucks.thankyou

Michael Munoz

48809	Maintenance				8/14/2009		47		\$0.00
-------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/14/2009 11:34:28 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose Need to fixed vibration from ref. unit.

Margret Villalobos

49128	Maintenance				8/21/2009		40		\$0.00
-------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/21/2009 2:12:01 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael please paint for maintence parking area only.

Alfredo Holguin

49172	Cafeteria				8/24/2009		37		\$0.00
-------	-----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/24/2009 9:43:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando LOADING DOCK ROOF IS LEAKING. HOLES NEED TO BE SEALED OR PATCHED UP.

JOHNNY LECHUGA SNP WAREHOUSE MGR 882-6927

Jacqueline Aguilar

49174	Food Services	Cafeteria			8/24/2009		37		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/24/2009 9:56:39 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando SNP WAREHOUSE: 2ND REQUEST - RAIN GUTTER WAS NEVER REPAIRED AT LOADING DOCK. WATER LEADING ALL OVER DOCK. 1ST W/O # 43492
JOHNNY LECHUGA SNP MGR 882-6927

Jacqueline Aguilar

49290	Maintenance				8/26/2009		35		\$0.00
-------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Technology			8/26/2009 11:29:48 AM				
--------	------------------	------------	--	--	-----------------------	--	--	--	--

Gonzales, Angel Regular oil change for Richard Santillano's van #157.

Thank you!

Sandra Almeraz

49358					8/27/2009		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	DIST WIDE			8/27/2009 9:19:50 AM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Gonzales, Angel FOR REPAIR OF TIRE MOUNT AND BALANCE ON ALL DISTRICT VEHICLES

Angel Gonzales

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

49359					8/27/2009		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	DIST WIDE			8/27/2009 9:21:57 AM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Gonzales, Angel		FOR TIRE REPAIR ON ALL DISTRICT VEHICLES							
-----------------	--	--	--	--	--	--	--	--	--

Angel Gonzales

49421					8/28/2009		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	AG SHOP			8/28/2009 10:48:00 AM				
--------	------------------	---------	--	--	-----------------------	--	--	--	--

Gonzales, Angel		Vehicle#120 AG Truck							
		Angel, go ahead and work on scheduling the work for next week if possible.							

Armando Montoya

49536					9/1/2009		29		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/1/2009 1:05:29 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Jacquez, Ricardo		Water pressure is low.							
------------------	--	------------------------	--	--	--	--	--	--	--

Margret Villalobos

49645					9/3/2009		27		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	Mike Munoz			9/3/2009 2:02:14 PM				
--------	------------------	------------	--	--	---------------------	--	--	--	--

Gonzales, Angel		Vehicle 99 - Has and odor of anti-freeze inside.							
-----------------	--	--	--	--	--	--	--	--	--

Michael Munoz

49698					9/4/2009		26		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/4/2009 8:56:16 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Gonzales, Angel		Complete service on bobcat loader.							
-----------------	--	------------------------------------	--	--	--	--	--	--	--

Angel Gonzales

50115	Purchasing	Office			9/15/2009		15		\$0.00
-------	------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Instructional			9/15/2009 9:23:59 AM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Lara, Ralph		Due to it being a fire hazard, we need a key/lock to be made for the wrought-iron bars that are on the window in the Instructional Materials Department. Work order placed as per Alfredo Holguin.							
-------------	--	--	--	--	--	--	--	--	--

Yolie Jacquez

50151					9/15/2009		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/15/2009 4:13:43 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel		PLEASE REPLACE WIPER MOTOR FOR VEHICLE #32.							
		THANK YOU RUBEN							

Ruben Ronquillo

50171					9/16/2009		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/16/2009 12:14:00 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		Need to install a lock and chain on new entrance gate.							
---------------	--	--	--	--	--	--	--	--	--

Michael Munoz

9/30/2009 6:01:22 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Physical Plant Complex

50216	Maintenance				9/17/2009		13		\$0.00
-------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/17/2009 8:23:14 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben	PURCHASE NEW NEW MEXICO FLAG. OLD ONE WORN OUT.								
------------------	---	--	--	--	--	--	--	--	--

Ruben Ronquillo

50242					9/18/2009		12		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/18/2009 11:02:09 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Flores, Pete	Forklift needs service								
--------------	------------------------	--	--	--	--	--	--	--	--

Danny Carrasco

50311					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/21/2009 11:12:23 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lara, Ralph	please install lock on new gate behind custodial warehouse(where a/c units are at).thanks								
-------------	---	--	--	--	--	--	--	--	--

Michael Munoz

50381					9/22/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/22/2009 1:47:18 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Gonzales, Angel	VEHICLE 97 - COMPLETE ENGINE SERVICE.								
-----------------	---------------------------------------	--	--	--	--	--	--	--	--

Angel Gonzales

50382					9/22/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/22/2009 1:48:21 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Gonzales, Angel	VEHICLE 135 - COMPLETE ENGINE SERVICE.								
-----------------	--	--	--	--	--	--	--	--	--

Angel Gonzales

50383					9/22/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/22/2009 1:49:21 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Gonzales, Angel	VEHICLE 104 - SPARK PLUGS								
-----------------	---------------------------	--	--	--	--	--	--	--	--

Angel Gonzales

50384					9/22/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/22/2009 1:50:16 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Gonzales, Angel	VEHICLE 100- SERVICE ON A/C								
-----------------	-----------------------------	--	--	--	--	--	--	--	--

Angel Gonzales

50385					9/22/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/22/2009 1:51:20 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Gonzales, Angel	VEHICLE 157 - SERVICE ON ENGINE								
-----------------	---------------------------------	--	--	--	--	--	--	--	--

Angel Gonzales

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

50386					9/22/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/22/2009 1:52:10 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel		VEHICLE 02 - WINDOW REGULATOR							
-----------------	--	-------------------------------	--	--	--	--	--	--	--

Angel Gonzales

50401	Purchasing	Custodial			9/22/2009		8		\$0.00
-------	------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/22/2009 3:28:14 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe		THE LINT TRAP FROM THE WASHER BEHIND THE CUSTODIAL WHSE IS FULL AND NEEDS TO BE CLEANED OUT PLEASE AND THANK YOU							
----------------	--	--	--	--	--	--	--	--	--

Jimmy Carbajal

50482	Maintenance				9/24/2009		6		\$0.00
-------	-------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/24/2009 1:13:48 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Miranda, Danny		Need to extend old HVAC office (into new lounge).							
----------------	--	---	--	--	--	--	--	--	--

Michael Munoz

50484					9/24/2009		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/24/2009 1:54:08 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel		Vehicle#149 - Repair damaged right rear fender.							
-----------------	--	---	--	--	--	--	--	--	--

Angel Gonzales

50485					9/24/2009		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/24/2009 1:56:02 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel		Vehicle#137 - Needs new tires.							
-----------------	--	--------------------------------	--	--	--	--	--	--	--

Angel Gonzales

50507					9/25/2009		5		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/25/2009 7:53:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador		Need to make partitions in rack to stack different kind, and sizes of metal pieces.							
--------------------	--	---	--	--	--	--	--	--	--

Salvador Gonzalez

50519					9/25/2009		5		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/25/2009 9:48:11 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben		NEED TO ORDER NEW 3' HANDICAP STENCIL.							
------------------	--	--	--	--	--	--	--	--	--

 Ruben Ronquillo

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

50574					9/28/2009		2		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/28/2009 11:00:12 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
 Yoli called from the warehouse she said she spoke to Manny regarding the locks to the new gate installed by the middle school, she hasn't been able to lock them because they are stuck, Manny told her he would work on them but to inform you.

 Yolie Jacquez

50589					9/28/2009		2		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/28/2009 3:23:18 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Diaz, Sebastian
 Hallway between Const. office and PPD office - Repair ceiling tile grid damaged by RC on Sunday

 Alfredo Holguin

50691					9/30/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/30/2009 2:38:42 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
 Please level and apply roadbase w/crusher fine where salt cedars were removed, please see Mike.

 Michael Munoz

50693					9/30/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/30/2009 3:02:11 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo
 Please install ice machine in warehouse.

 Michael Munoz

50695					9/30/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/30/2009 3:05:49 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo
 Need to replace contactor to ref. unit in PPD Office.

 Michael Munoz

Count: 39 Work Orders			Avg. Age of WO's 23			Total for Physical Plant Complex	0		\$0.00
------------------------------	--	--	----------------------------	--	--	---	----------	--	---------------

Location: Riverside ES

48455		Cafeteria			8/6/2009		55		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/6/2009 3:01:56 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Moncayo, Fernando
 CART FOR REGISTER NEED WHEELS TO BE REPLACED.

EMILLA C SNP MGR 589-2550

Jacqueline Aguilar

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Riverside ES

48933					8/18/2009		43		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/18/2009 8:25:41 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David Plumbing problem in the Teachers lounge drain is not working.

Olga Arias

49126	Main Building				8/21/2009		40		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/21/2009 2:07:00 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph Door in the Sixth Grade Wing is not locking correctly.

Olga Arias

49425					8/28/2009		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/28/2009 1:23:09 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Gonzales, Angel tractor 970 has a slow leak on front right tire

Carlos Hernandez

49528					9/1/2009		29		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/1/2009 8:06:54 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Orozco, Danny need lift to restring flagpole

Carlos Hernandez

49579	Portables				9/2/2009		28		\$0.00
-------	-----------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/2/2009 10:06:08 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David last portable to be installed does not have gas run to it for heating. this portable is being occupied. please connect for heater to be used. thanks

Michael Munoz

50214	Classroom				9/16/2009		14		\$0.00
-------	-----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/16/2009 4:17:03 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Hernandez, Carlos 2" x 8' cork railings will be ordered. please install when you receive them. thank you

Michael Munoz

50330					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/21/2009 3:15:52 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose need new a/c unit room 37

Carlos Hernandez

50331					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/21/2009 3:16:41 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose need new a/c unit room 36

Carlos Hernandez

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

50332					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/21/2009 3:17:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		need new a/c unit room 30							
--------------	--	---------------------------	--	--	--	--	--	--	--

Carlos Hernandez									
------------------	--	--	--	--	--	--	--	--	--

50333					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/21/2009 3:18:23 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		need new a/c unit room 26							
--------------	--	---------------------------	--	--	--	--	--	--	--

Carlos Hernandez									
------------------	--	--	--	--	--	--	--	--	--

50334					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/21/2009 3:19:17 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		need new a/c unit room 25							
--------------	--	---------------------------	--	--	--	--	--	--	--

Carlos Hernandez									
------------------	--	--	--	--	--	--	--	--	--

50335					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/21/2009 3:20:06 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		need new a/c unit room 17							
--------------	--	---------------------------	--	--	--	--	--	--	--

Carlos Hernandez									
------------------	--	--	--	--	--	--	--	--	--

50336					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/21/2009 3:20:54 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		need new a/c unit room 27							
--------------	--	---------------------------	--	--	--	--	--	--	--

Carlos Hernandez									
------------------	--	--	--	--	--	--	--	--	--

50338					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/21/2009 3:21:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		need new a/c unit room 29							
--------------	--	---------------------------	--	--	--	--	--	--	--

Carlos Hernandez									
------------------	--	--	--	--	--	--	--	--	--

50339					9/21/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/21/2009 3:22:18 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		need new a/c unit room 35							
--------------	--	---------------------------	--	--	--	--	--	--	--

Carlos Hernandez									
------------------	--	--	--	--	--	--	--	--	--

50380					9/18/2009		12		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/22/2009 1:45:19 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		RIPPED OUT POLE AND SIGN, ALSO PULLED OUT AND BROKE 8 SPRINKLERS. (CASE#SP009001453) EST DAMAGE 800.00							
----------------------	--	--	--	--	--	--	--	--	--

Carlos Hernandez									
------------------	--	--	--	--	--	--	--	--	--

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

50606		Classroom			9/28/2009		2		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	New ART			9/28/2009 4:56:04 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Castillo, Carlos		Need connect electrical power to switch.							
------------------	--	--	--	--	--	--	--	--	--

Parra, Robert

50627		Cafeteria			9/29/2009		1		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/29/2009 9:40:33 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		FAN TO WALK - IN FREEZER NEEDS TO BE CLEANED OUT							
---------------	--	--	--	--	--	--	--	--	--

EMILIA CARILLO SNP MGR 589-2550

Jacqueline Aguilar

50628		Cafeteria			9/29/2009		1		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/29/2009 9:41:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		BACK OF REACH IN REFRIG. NEEDS TO BE CLEANED OUT. (FAN)							
---------------	--	---	--	--	--	--	--	--	--

EMILIA CARRILLO SNP MGR 589-2550

Jacqueline Aguilar

50629		Cafeteria			9/29/2009		1		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/29/2009 9:43:01 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		SERVING LINE (SINK) WILL NOT DRAIN							
---------------	--	------------------------------------	--	--	--	--	--	--	--

EMILIA CARRILLO SNP MGR 589-2550

Jacqueline Aguilar

50688					9/30/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/30/2009 1:11:38 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		need bearing for a/c unit in library							
--------------	--	--------------------------------------	--	--	--	--	--	--	--

Carlos Hernandez

50698					9/30/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/30/2009 3:24:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		need a/c unit room 16							
--------------	--	-----------------------	--	--	--	--	--	--	--

Carlos Hernandez

Count: 23 Work Orders			Avg. Age of WO's	15		Total for Riverside ES	0		\$0.00
------------------------------	--	--	-------------------------	-----------	--	-------------------------------	----------	--	---------------

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: RTC - Alliance

50604					9/28/2009		2		\$0.00
Medium	Work In Progress				9/28/2009 4:33:20 PM				
Briones, Enrique		On October 1, 2009, please pick-up six (6) boxes of out-of-adoption Science books.							

Yolie Jacquez

Count: 1 Work Orders		Avg. Age of WO's 2				Total for RTC - Alliance	0		\$0.00
-----------------------------	--	---------------------------	--	--	--	---------------------------------	----------	--	---------------

Location: San Miguel ES

49386		Office			8/27/2009		34		\$0.00
Medium	Work In Progress	PPD AUTO			8/27/2009 3:57:30 PM				
Martinez, Larry		AS PER MARIA-NEED TO HAVE SOMEONE PICK UP A PLASTIC FLOOR MAT FROM SAN MIGUEL ELEMENTARY AND TO DELIVER IT TO HER OFFICE AT PPD - AUTO SHOP.				APPROVED BY MR. RICHARD G. CHAVEZ			

Mary Garcia

Count: 1 Work Orders		Avg. Age of WO's 34				Total for San Miguel ES	0		\$0.00
-----------------------------	--	----------------------------	--	--	--	--------------------------------	----------	--	---------------

Location: Santa Teresa ES

47180					7/5/2009		87		\$0.00
Medium	Work In Progress				7/5/2009 12:21:31 AM				
Marquez, Gerardo		Yearly - Santa Teresa ES - ERV (Yearly) - Refer to PM schedule details.							

Margret Villalobos

47581					7/16/2009		76		\$0.00
Medium	Work In Progress				7/16/2009 12:54:46 PM				
Estrada, Jesus		NEED TO REPLACE VCT WITH CARPET IN PORTABLE A & B.							

Jesus Estrada

47803	Main Building	Classroom			7/24/2009		68		\$0.00
Medium	Work In Progress	102			7/24/2009 9:46:06 AM				
Lara, Ralph		LATCHES IN THE BUILT IN TALL CABINETS ARE BROKEN. NEED REPLACEMENT.							

Rita Mendez

47804	Main Building	Classroom			7/24/2009		68		\$0.00
Medium	Work In Progress	104			7/24/2009 9:48:47 AM				
Lara, Ralph		LATCHES IN BUILT IN CABINETS ARE BROKEN. NEED REPLACEMENT. THANK YOU.							

Rita Mendez

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

47805	Main Building	Classroom			7/24/2009		68		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	309			7/24/2009 9:51:33 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lara, Ralph LATCHES IN BUILT IN CABINETS ARE BROKEN. NEED REPLACEMENT. THANK YOU.

Rita Mendez

48310					8/4/2009		57		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/4/2009 2:05:04 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Gonzales, Angel 2nd Request 9/28/09
NEED BOBCAT DELIVERED TO SITE TO CLEAN UP
RAIN WASHOUTS AGAIN.

Gerardo Marquez

48532					8/9/2009	8/25/2009	52		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				8/9/2009 1:23:44 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo Monthly - Santa Teresa ES Playground Insp - Refer to
PM schedule details.

Margret Villalobos

48991					8/19/2009		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/19/2009 8:35:20 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David DAVID; TWO METERED FAUCETS NEED TO BE
REPLACED IN BOY'S BATHROOM. THEY ARE
SINGLE HOLE HOT & COLD TYPE. THANKS.

Gerardo Marquez

48994					8/19/2009		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/19/2009 8:39:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny AS OF 3/09 DIMAR POSTED THAT A 6 YEAR INSP.
ON ALL THE FIRE EXTINGUISHERS IS DUE.

Gerardo Marquez

49044	Main Building	Classroom			8/19/2009		42		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	RM 302			8/19/2009 5:09:14 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Lara, Ralph MR. ACKERMAN, RM 302, NEEDS A LOCK IN THE
LONG WALL CABINET IN HIS CLASSROOM. THANK
YOU.

Rita Mendez

49045	Main Building	Office			8/19/2009		42		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	NURSE'S			8/19/2009 5:11:14 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Lara, Ralph MEDICINE CABINET IN NURSE'S OFFICE NEEDS A
LOCK. THANK YOU.

Rita Mendez

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa ES

49046		Office			8/19/2009		42		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	OFFICE		8/19/2009 5:14:50 PM					
--------	------------------	--------	--	----------------------	--	--	--	--	--

Lara, Ralph
WE NEED L WRENCHES FOR OUR DOORS TO BUILDING. (AROUND 8 IF POSSIBLE). THANKS.

Rita Mendez

49161	Main Building	Classroom			8/24/2009		37		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	RM 201		8/24/2009 8:38:13 AM					
--------	------------------	--------	--	----------------------	--	--	--	--	--

Marquez, Gerardo
PAPERTOWEL DISPENSER NEEDS TO BE INSTALLED IN CLASSROOM 201. THANKS.

Rita Mendez

49767					9/6/2009	9/14/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:39 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Marquez, Gerardo
Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

49768					9/6/2009	9/14/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:39 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Marquez, Gerardo
Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

49769					9/6/2009	9/12/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:40 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Marquez, Gerardo
Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

49770					9/6/2009		24		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:40 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Marquez, Gerardo
Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.

Margret Villalobos

49906					9/9/2009		21		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/9/2009 3:46:52 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Marquez, Gerardo
NEED TO REPLACE HVAC FILTERS FOR HEATING SEASON START-UP.

Gerardo Marquez

49992					9/11/2009		19		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/11/2009 2:59:46 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David
ART TEACHER IS REQUESTING A SINK BE INSTALLED IN ART RM. THANKS.

Gerardo Marquez

9/30/2009 6:01:22 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa ES

50029					9/13/2009	9/29/2009	17		\$0.00
Medium	Work In Progress			9/13/2009 12:33:17 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								

Margret Villalobos

50487					9/24/2009		6		\$0.00
Medium	Work In Progress			9/24/2009 2:13:35 PM					

Marquez, Gerardo	9/14/09			9/14-8					
1-INSP. BLDG. & GRNDS. (CHECKED FOR VANDALISM & GRAFITTI.)									
1-PICKED UP TRASH.									
2-CLEANED OFF ENTRYWAYS & SIDEWALKS.									
1-CLEANED & INSP. P.G. EQUIP.									
2-CLEANED UP PAINT SPILL ON SIDEWALK OUTSIDE RM. 306. (KIDS SPILLED PAINT WHILE WORKING ON A PROJECT.)									
1-UNCLOGGED URINAL IN BOYS R.RM. B-WING.									

Gerardo Marquez

50663					9/30/2009		0		\$0.00
Medium	Work In Progress			9/30/2009 12:23:00 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES-A-16 Fan Exhaust (SemiA) - Refer to PM schedule details.								

Margret Villalobos

Count: 22 Work Orders	Avg. Age of WO's 40	Total for Santa Teresa ES					0	\$0.00		
------------------------------	----------------------------	----------------------------------	--	--	--	--	----------	---------------	--	--

Location: Santa Teresa HS

47104					7/5/2009	7/11/2009	87		\$0.00
Medium	Work In Progress			7/5/2009 12:21:02 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								

Margret Villalobos

47105					7/5/2009	7/13/2009	87		\$0.00
Medium	Work In Progress			7/5/2009 12:21:02 AM					

Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
---------------	---	--	--	--	--	--	--	--	--

Margret Villalobos

47106					7/5/2009	8/5/2009	87		\$0.00
Medium	Work In Progress			7/5/2009 12:21:03 AM					

Nunez, Arturo	Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.								
---------------	---	--	--	--	--	--	--	--	--

Margret Villalobos

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

47107					7/5/2009	8/5/2009	87		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress			7/5/2009 12:21:03 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.

Margret Villalobos

47324					7/7/2009		85		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			7/7/2009 12:49:16 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos Need to connect the new score boards at STHS. Code requires connection by an electrician...Thanks

Ralph Gallegos

47409					7/12/2009	8/12/2009	80		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress			7/12/2009 12:18:09 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Nunez, Arturo Yearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.

Margret Villalobos

47564					7/15/2009		77		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/15/2009 4:20:42 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose NEED FOUR (4) EA. T' STATS TRANE # X13510933-02 , 0607, REV. A

Arturo Nunez

47720					7/22/2009		70		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/22/2009 3:15:40 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph Need 10 keys for light switches.

Arturo Nunez

47782					7/23/2009		69		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/23/2009 3:29:47 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph NEED TO HAVE METAL DOORS , AND HARDWARE ON COUNSELORS OFFICE REPLACED HINDGES ARE BROKEN, SECURITY ISSUE. THANK YOU.

Arturo Nunez

47783					7/23/2009		69		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/23/2009 3:32:26 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph NEED DOUBLE DOORS IN BAND ROOM REPLACED OR REPAIRED , TOP LOCK ON DOOR IS BROKEN BEYOUND REPAIR, SECURITY ISSUE.

Arturo Nunez

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
47784					7/23/2009		69		\$0.00
Medium	Work In Progress				7/23/2009 3:35:04 PM				
Munoz, Michael	NEED TO REPLACE FORMICA ON FRONT OFFICE COUNTER, EXISTING IS ALL CHIPPED, AND IN BAD SHAPE.								
Arturo Nunez									
47786					7/23/2009		69		\$0.00
Medium	Work In Progress				7/23/2009 3:38:07 PM				
Ambriz, Jose	NEED FOUR (4) EA. 7"X23" GRILLS, AND FOUR (4) EA. 7"X13" GRILLS FOR BAND ROOM.								
Arturo Nunez									
47787					7/23/2009		69		\$0.00
Medium	Work In Progress				7/23/2009 3:40:11 PM				
Lara, Ralph	NEED TO REPLACE DOOR IN FRONT OFFICE, 1/2 DOOR WITH COUNTER								
Arturo Nunez									
47956		Custodial			7/28/2009		64		\$0.00
Medium	Work In Progress				7/28/2009 4:04:42 PM				
Carbajal, Jimmy	MR. JIMMY THE WRANGLER 20-B IS NOT TAKING THE CHARGE NEEDS TO BE CHECKED OUT THANK YOU.					9/25/09 - NO PARTS			
Luis Murillo									
48090					7/31/2009		61		\$0.00
Medium	Work In Progress				7/31/2009 9:05:27 AM				
Castillo, Carlos	GUARD SHACK WAS RELOCATED, NEED ELECTRICAL CONNECTION COMPLETED.								
Michael Munoz									
48102					7/31/2009		61		\$0.00
Medium	Work In Progress				7/31/2009 10:51:42 AM				
	NEED TO SPRAY FOOTBALL & SOCCER FIELDS FOR MOSQUITOS.					FAXED TO WATSON 7/31/09			
Michael Munoz									
48134					8/2/2009	8/18/2009	59		\$0.00
Medium	Work In Progress				8/2/2009 12:20:58 AM				
Villalobos, Margret	Yearly - Santa Teresa HS August Chiller Insp. - Refer to PM schedule details.								
Margret Villalobos									
48142					8/2/2009	8/8/2009	59		\$0.00
Medium	Work In Progress				8/2/2009 12:21:02 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
9/30/2009 6:01:22 PM									

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

48246					8/3/2009		58		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/3/2009 1:07:31 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Briones, Enrique
 On August 4, 2009:
 Please pick-up, from Santa Teresa High School, one full
 gaylord box and drop-off two empty gaylord boxes.

Yolie Jacquez

48365					8/5/2009		56		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/5/2009 8:16:06 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
 8/5/09. ON ROOM 23 FRONT DOOR LOCK WILL NOT
 WORK.

Manuel Prospero

48446					8/6/2009		55		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/6/2009 12:42:14 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
 NEED TO HAVE FIRE EXTINGUISHERS SERVICED

Danny Orozco

48657		Classroom			8/11/2009		50		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	MR.			8/11/2009 2:34:31 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Lara, Ralph
 ENTRY DOORS TO BANDROOM TO INSTALL METAL
 DOORS.

Marylou Jimenez

48689	Main Building	Athletic Field			8/12/2009		49		\$0.00
-------	---------------	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/12/2009 7:58:04 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Valdez, Pedro
 Soccer Field: Install and adjust retaining nets behind
 North and South Goals.

Luis Calleros

48690	Gymnasium				8/12/2009		49		\$0.00
-------	-----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	new gym			8/12/2009 8:02:27 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Lara, Ralph
 Door from storage room inside the new gym cannot be
 locked, door broken from the top.

Luis Calleros

48691	Main Building	Hallway/Corridor			8/12/2009		49		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	room 18			8/12/2009 8:05:59 AM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Castillo, Carlos
 Need additional electrical outlets for science room. Need
 approximately 8 more.

Luis Calleros

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

48796	Gymnasium				8/14/2009		47		\$0.00
-------	-----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/14/2009 8:12:04 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo please replace broken switch on red whirl- pool motor
thankyou

Michael Munoz

48848	Main Building	Classroom			8/15/2009		46		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	room 208		8/15/2009 11:08:27 AM					
--------	------------------	----------	--	-----------------------	--	--	--	--	--

Nunez, Arturo Switch position of pencil sharpener.

Luis Calleros

49013		Classroom			8/19/2009		42		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	MR.		8/19/2009 11:55:39 AM					
--------	------------------	-----	--	-----------------------	--	--	--	--	--

Nunez, Arturo PLEASE ASSEMBLE EXECUTIVE CHAIR FOR MR.
PHELPS.

Marylou Jimenez

49068	Main Building	Gym			8/20/2009		41		\$0.00
-------	---------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress	new gate by		8/20/2009 10:47:02 AM					
--------	------------------	-------------	--	-----------------------	--	--	--	--	--

Nunez, Arturo Need to paint in yellow the sidewalk / curb next to the
"new gate" by the new gym

Luis Calleros

49076	Main Building	Classroom			8/20/2009		41		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room 14		8/20/2009 5:18:33 PM					
--------	------------------	---------	--	----------------------	--	--	--	--	--

Lara, Ralph re-key two file desk cabinets and a desk

Luis Calleros

49078	Main Building	Classroom			8/20/2009		41		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	room 213		8/20/2009 5:23:47 PM					
--------	------------------	----------	--	----------------------	--	--	--	--	--

Lara, Ralph Replace broken door latches on storage cabinets.

Luis Calleros

49079	Main Building	Classroom			8/20/2009		41		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	room 213		8/20/2009 5:26:03 PM					
--------	------------------	----------	--	----------------------	--	--	--	--	--

Lara, Ralph change door mechanism to a door handle with manual
lock on top to the bathroom door

Luis Calleros

49169	Gymnasium				8/24/2009		37		\$0.00
-------	-----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/24/2009 9:02:34 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David please relocate ice machine to new traing room and
connect. contact person would be Frank Munoz

Joe Munoz

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

49188	Main Building	Classroom			8/24/2009		37		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room # 607			8/24/2009 2:10:11 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Nunez, Arturo A/C not working.

Luis Calleros

49192		Cafeteria			8/24/2009		37		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

High	Work In Progress				8/24/2009 3:09:28 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose as per boiler inspector a low water cut off such as a flow switch and a high limit temp control w/a manual reset button needs to be installed on the following boilers (serail #s 0501230507 and 050123506). thanks

Michael Munoz

49193		Cafeteria			8/24/2009		37		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

High	Work In Progress				8/24/2009 3:13:34 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos As per boiler inspector a manually operated remote shut down safety device needs to be installed inside boiler rooms by the door w/ cover guard and identification tag. (boilers serail #s 0501230507 and 0501230506) thank you

Michael Munoz

49216		Cafeteria			8/24/2009		37		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

High	Work In Progress				8/24/2009 4:22:42 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo As per boiler inspector need to post Certificates in a visable area.

Michael Munoz

49289	Cafeteria (2005)	Cafeteria			8/26/2009		35		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/26/2009 10:18:57 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph HANDI CAP DOOR NOT OPENING WHEN BOX IS PUSHED TO OPEN NEEDS TO BE CHECKED OUT THANK YOU.

Luis Murillo

49295	GYM (2009)				8/26/2009		35		\$0.00
-------	------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/26/2009 12:44:41 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Nunez, Arturo Tilley from GenCon gave Art Nunez a new cord. An STHS Coach cut the cord, so I asked Art to replace with the one Tilley provided.

Ralph Gallegos

49328					8/26/2009		35		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/26/2009 3:33:37 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos NEED ELEC. CIRCUITS ON ROOM # 14 CHECKED, SOME WILL NOT STAY ON, AT BREAKER PANEL, NEED SOME ASSISTANCE. THANK YOU.

Arturo Nunez

9/30/2009 6:01:22 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

49392	Annex Building	Portables			8/27/2009		34		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Flag Pole		8/27/2009 4:57:44 PM					
--------	------------------	-----------	--	----------------------	--	--	--	--	--

Nunez, Arturo The flag pole needs to be restrung.

Luis Calleros

49395	Main Building	Athletic Field			8/27/2009		34		\$0.00
-------	---------------	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Baseball field		8/27/2009 5:07:41 PM					
--------	------------------	----------------	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe Nee the following paint and paint supplies as needed:
5 gal. black paint
5 gal. whit paint
5 gal. turquoise paint as discussed with Mr. Lupe
Ontiveros and Mr. Pedro Valdez

Luis Calleros

49420	Vocational	Classroom			8/28/2009		33		\$0.00
-------	------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room T-300		8/28/2009 10:29:16 AM					
--------	------------------	------------	--	-----------------------	--	--	--	--	--

Castillo, Carlos Row of electrical drops do not work

Luis Calleros

49517		Football Field			8/31/2009		30		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/31/2009 3:54:50 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Valdez, Pedro Need to clear high grass around south west light to clear base, to avoid further corrosion of pole.

Carlos Castillo

49564		Cafeteria			9/2/2009		28		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/2/2009 7:06:02 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Nunez, Arturo WE HAVE TWO FIRE EXTINGUISHERS COVERS THAT ARE BROKEN ONE IN THE CAFETERIA AND ANOTHER IN THE NEW GYM THEY NEED TO BE REPLACE THANK YOU. 9/2 - Asp Ruben, needs to go thru BM for measurements. - mkv

Luis Murillo

49565	Cafeteria (2005)	Choral			9/2/2009		28		\$0.00
-------	------------------	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/2/2009 7:12:32 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lara, Ralph DOOR CLYINDER LEAKING OIL STAINING THE DOOR WINDOW / NEEDS TO BE REPAIR THANK YOU.

Luis Murillo

49585	Annex Building	Portables			9/2/2009		28		\$0.00
-------	----------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Flag Pole by		9/2/2009 11:04:37 AM					
--------	------------------	--------------	--	----------------------	--	--	--	--	--

Orozco, Danny Need the "lift" to resrtng flag pole to complete WO# 49329

Luis Calleros

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

49639	Main Building				9/3/2009		27		\$0.00
-------	---------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/3/2009 12:39:54 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo
WATER FOUNTAIN IN THE ENGLISH WING IS
PLUGGED UP NEEDS TO BE UNPLUG THANK YOU.

Luis Murillo

49741					9/6/2009	9/12/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:30 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo
Monthly - Santa Teresa HS Monthly FE Inspection -
Refer to PM schedule details.

Margret Villalobos

49751					9/6/2009	9/27/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:34 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Orozco, Danny
Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer
to PM schedule details.

Margret Villalobos

49800					9/6/2009	9/14/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:50 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Prospero, Manuel
Monthly - Santa Teresa HS Emer Light Test: Monthly -
Refer to PM schedule details.

Margret Villalobos

49801					9/6/2009	9/14/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:50 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Prospero, Manuel
Monthly - Santa Teresa HS Exit Sign Insp: Monthly -
Refer to PM schedule details.

Margret Villalobos

49802					9/6/2009	10/7/2009	24		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			9/6/2009 12:22:51 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Prospero, Manuel
Monthly - Santa Teresa HS Bleacher Inspection - Refer
to PM schedule details.

Margret Villalobos

49884	Gymnasium	Gym			9/9/2009		21		\$0.00
-------	-----------	-----	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/9/2009 12:25:28 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David
FASUET FROM SINK WILL NOT SHUT OFF FROM
GIRLS BATHROOM IN NEW GYM AREA THANK YOU.

Luis Murillo

50035					9/13/2009	9/29/2009	17		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress			9/13/2009 12:33:19 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Prospero, Manuel
Monthly - Santa Teresa HS Playground Insp - Refer to
PM schedule details.

Margret Villalobos

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

50152	Annex Building	Portables			9/15/2009		15		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Day Care Center			9/15/2009 5:00:15 PM				
--------	------------------	-----------------	--	--	----------------------	--	--	--	--

Nunez, Arturo Replace gutters, (two sets), outside of front doors

Luis Calleros

50154	Annex Building	Portables			9/15/2009		15		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Day care center			9/15/2009 5:04:57 PM				
--------	------------------	-----------------	--	--	----------------------	--	--	--	--

Nunez, Arturo replace floor tiles by doors

Luis Calleros

50280					9/20/2009		10		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/20/2009 12:18:49 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe Monthly - Santa Teresa HS Soil Sampling - Refer to PM schedule details.

Margret Villalobos

50378	Vocational	Cafeteria			9/22/2009		8		\$0.00
-------	------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/22/2009 1:17:16 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos LIGHTS BEHIND CAFETERIA ARE NOT COMEING ON / THE ONES THAT ARE BY THE TRASH COMPACTER / CUSTODIANS CAN NOT SEE WHEN THROWING TRASH THANK YOU.

Luis Murillo

50428					9/23/2009		7		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/23/2009 9:06:29 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben NEED TO HAVE GLASS ON WINDOW IN ROOM # 18 REPLACED THE MEASUREMENTS ARE 37 1/4 " X 26" SINGLE PANE GLASS

Arturo Nunez

50441		Athletic Field			9/23/2009		7		\$0.00
-------	--	----------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/23/2009 1:53:28 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Valdez, Pedro 997 Mower needs Battery replaced.

Guadalupe Ontiveros

50462	Main Building	Athletic Field			9/23/2009		7		\$0.00
-------	---------------	----------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Soccer Field			9/23/2009 4:26:27 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Replace North / South retaining nylon nets behind the goals with chain link fence or other weather erosion proof material

Luis Calleros

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

50471	Vocational	Classroom			9/24/2009		6		\$0.00
-------	------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Shop 2 Angelos'			9/24/2009 9:01:28 AM				
--------	------------------	-----------------	--	--	----------------------	--	--	--	--

Ambriz, Jose
Replace referigerated water fountain. Water fountain is over 15 years old.

Luis Calleros

50510		Football Field			9/25/2009		5		\$0.00
-------	--	----------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/25/2009 8:21:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Need to remove rust from sw light pole at Sta.Teresa Hi football stadium.

Carlos Castillo

50512					9/25/2009		5		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/25/2009 8:39:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Margret
WE HAVE A PROBLEM, IN ROOM # 611, HOME CE. WE SEEM TO HAVE MICE , WE HAVE INSTALLED GLUE BOARDS, AND MOUSE BAIT, BUT WE STILL FIND EVIDENCE OF THEIR PRESENCE. THAN YOU.

Arturo Nunez

50525	GYM (2009)	Gym			9/25/2009		5		\$0.00
-------	------------	-----	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/25/2009 12:29:03 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
Please provide the power when we move the boards. Thanks. They should be installing the new score board and moving the other one up on Friday, September 25h around 9 am.

Ralph Gallegos

50577					9/28/2009		2		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/28/2009 12:08:25 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Carrasco, Danny
NEED TO BORROW SISSOR LIFT SO THAT MR. CASTILLO CAN HOOK UP ELEELECTRICTY TO SCORE BOARDS THAT WERE RELOCATED IN NEW GYM.. COACH WOULD LIKE TO HAVE READY FOR NEXT GAME WHICH IS 10/03/09. THANK YOU.

Arturo Nunez

50636	Cafeteria (2005)	Cafeteria			9/29/2009		1		\$0.00
-------	------------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/29/2009 11:34:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny
SALAD LINE: SWITCH TO THE NEON LIGHTS BROKE

OLGA B. SNP MGR 589-5332

Jacqueline Aguilar

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

50670					9/30/2009		0		\$0.00
Medium	Work In Progress				9/30/2009 12:23:03 AM				
Prospero, Manuel	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								

Margret Villalobos

Count: 69 Work Orders	Avg. Age of WO's 40	Total for Santa Teresa HS	0	\$0.00
------------------------------	----------------------------	----------------------------------	----------	---------------

Location: Santa Teresa MS

47070					7/1/2009		91		\$0.00
Medium	Work In Progress				7/1/2009 7:23:52 AM				
Mijarez, Jaime	6/18/09 .50 Sign in and fill out paper work. 1.0 Troubleshoot thru tracer summit. 4.5 S.bldg office heat pump 74. 3.0 w/o 46585 N.bldg electrical room mini split system. .50 Fillout paper work. .50 lockup buildings.		6/18-6						

Jaime Mijarez

47553					7/15/2009		77		\$0.00
Medium	Work In Progress				7/15/2009 1:29:49 PM				
Ambriz, Jose	Storage Room - Asp Mike Soria need some kind of ventilation in this area, it is extremely hot in there.								

Mike Soria

47820					7/24/2009		68		\$0.00
Medium	Work In Progress				7/24/2009 3:16:14 PM				
Gonzales, Angel	Truck 121. The brakes need to be worked on they are sounding real bad. Thank you.								

Jaime Mijarez

48425	North Building				8/6/2009		55		\$0.00
Medium	Work In Progress	AREA			8/6/2009 10:06:23 AM				
Soria, Mike	AREA BETWEEN TWO BUILDINGS HAS WEEDS THAT NEED TO BE REMOVED.								

Laura Parra

48426	North Building	Custodial			8/6/2009		55		\$0.00
Medium	Work In Progress				8/6/2009 10:36:16 AM				
Flores, Pete	Pete one of the gas blowers is not working the string got of the rail. And i needed for the southbuilding thank you.								

Ismael Rodriguez

48761	Gym (1997)	Gym			8/13/2009		48		\$0.00
Medium	Work In Progress				8/13/2009 10:09:34 AM				
Lara, Ralph	As per Mr. Tony Enciso is requesting handi-cap devices on all doors in the gym.								

Jaime Mijarez

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

49033	South Building	Computer Lab			8/19/2009		42		\$0.00
-------	----------------	--------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/19/2009 3:19:50 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
S.bldg lower level rooms S-36-A and S-36-B. Circuit is tripping because there is too many computers in room S-36-A and causing to lose power in room S-36-B.

Jaime Mijarez

49120	North Building				8/21/2009		40		\$0.00
-------	----------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/21/2009 1:30:26 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
N.bldg upper and lower level staff restrooms. Having problems with the metering faucets.

Jaime Mijarez

49316	South Building	Restroom (Boys)			8/26/2009		35		\$0.00
-------	----------------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/26/2009 2:59:02 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
REPLACE BROKEN SINK IN BOYS RESTROOM

Laura Parra

49445					8/28/2009		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/28/2009 3:36:39 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Need to coordinate w/Bldg Mechanic on proper training for newer water heaters.

Michael Munoz

49487	North Building	Classroom			8/31/2009		30		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	ROOM 7			8/31/2009 2:45:16 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Villalobos, David
PLEASE REMOVE SMALL SINK FROM ROOM. SINK IS TOO CLOSE TO COMPUTERS.

Laura Parra

49634		Cafeteria			9/3/2009		27		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/3/2009 10:13:22 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
DRY STORAGE EXHAUST FAN NOT WORKING

Danny Orozco

49682					9/3/2009		27		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	SANTA			9/3/2009 4:58:50 PM				
--------	------------------	-------	--	--	---------------------	--	--	--	--

Martinez, Larry
DELIVERY OF 1 BOX FOR SANTA TERESA MIDDLE

Mary Garcia

49835	North Building	Custodial			9/8/2009		22		\$0.00
-------	----------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/8/2009 11:48:07 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
The truck bed needs to be welded or be replace it is loose and unsafe th truck number is #39.

Ismael Rodriguez

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

49859		Cafeteria			9/8/2009		22		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/8/2009 3:49:19 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Orozco, Danny freezer down need to order defrost heater

Danny Orozco

49925	North Building	Cafeteria			9/10/2009		20		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/10/2009 10:20:01 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lara, Ralph Cafeteria exterior exit door. As per Mrs. Yvonne Casillas she want's a dead bolt lock installed on door. Joe Laguna from architectural products recommends a Schlage Mortise Indecader Lock instead of the dead bolt. Mike it is an exit door and there are exit signs indicating that there is and exit.

Jaime Mijarez

50483		Parking Lot			9/24/2009		6		\$0.00
-------	--	-------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/24/2009 1:40:21 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Mijarez, Jaime Parking lot. Install no pets allowed signs.

Jaime Mijarez

50516					9/25/2009		5		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/25/2009 9:08:45 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Briones, Enrique On October 1, 2009, please deliver one (1) box of English Material to Santa Teresa Middle School.

Yolie Jacquez

50524	North Building	Classroom			9/25/2009		5		\$0.00
-------	----------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/25/2009 11:10:32 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Soria, Mike Mr.Soria the nurse wants for you to clear the weeds behind her office for safety precautions insects are crawling in.

Ismael Rodriguez

50567					9/28/2009		2		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/28/2009 8:53:33 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Briones, Enrique Deliver to STMS
PO #91001488 two boxes to Ms. Casillas Rm #3

Margaret Villalobos

50581	Gym (1997)				9/28/2009		2		\$0.00
-------	------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			9/28/2009 2:00:08 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos Gym light. One of the plastic light covers is broken.

Jaime Mijarez

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

50582	Gym (1997)				9/28/2009		2		\$0.00
Medium	Work In Progress				9/28/2009 2:05:35 PM				
Castillo, Carlos		Gym outside pole lights. They are controlled by a photocell and are not turning off.							

Jaime Mijarez

50640	North Building	Office			9/29/2009		1		\$0.00
Medium	Work In Progress				9/29/2009 2:15:49 PM				
Lara, Ralph		Principals key does not open exterior entrance doors to bldg. Check with her to see if key needs to be re-cut or replaced asap.							

Jaime Mijarez

50665					9/30/2009		0		\$0.00
Medium	Work In Progress				9/30/2009 12:23:01 AM				
Mijarez, Jaime		Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.							

Margret Villalobos

Count: 24 Work Orders		Avg. Age of WO's 30				Total for Santa Teresa MS	0		\$0.00
------------------------------	--	----------------------------	--	--	--	----------------------------------	----------	--	---------------

Location: Sunland Park ES

47646					7/21/2009		71		\$0.00
Medium	Work In Progress				7/21/2009 8:06:31 AM				
Herrera, Joel		MR. HERRERA OUTSIDE GRASS INCLUDING SOCCER FIELD IS DRY. PLEASE CHECK SPRINKLER SYSTEM. RUN MANUALLY IS NEEDED.							

Jessica Lopez

47647					7/21/2009		71		\$0.00
Medium	Work In Progress				7/21/2009 8:08:04 AM				
Herrera, Joel		MR. HERRERA PLEASE PAINT CUSTODIAN'S STORAGE ROOMS.							

Jessica Lopez

47648					7/21/2009		71		\$0.00
Medium	Work In Progress				7/21/2009 8:10:09 AM				
Herrera, Joel		MR. HERRERA PLEASE REPLACE ALL OUTSIDE BROKEN TILES. 3RD REQUEST. SAFETY HAZARD							

Jessica Lopez

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Sunland Park ES

47649					7/21/2009		71		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/21/2009 8:16:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Joel
 MR. HERRERA PLEASE PAINT OUTSIDE PORTABLES.
 4TH YEAR REQUEST.
 LAST REQUEST WAS ENTERED ON 3/18.09

Jessica Lopez

47650					7/21/2009		71		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/21/2009 8:17:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Joel
 MR. HERRERA PLEASE PAINT PLANTERS LOCATED AT THE MAIN ENTRANCE.
 2ND REQUEST

Jessica Lopez

47815					7/24/2009		68		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/24/2009 2:45:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Estrada, Jesus
 REPLACE VCT IN A.P. COUNSELOR'S OFFICE FAXED TO AZTEC 7/24/09

Jesus Estrada

47871					7/27/2009		65		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	NURSE'S			7/27/2009 3:03:43 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Lara, Ralph
 THE NURSE NEEDS TO LOCK 4 DIFFERENT CABINETS.
 NEED TO INSTALL LOCK AND WILL BE NEEDING KEYS.
 LOCATION: NURSE'S OFFICE

Jessica Lopez

47874					7/27/2009		65		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	PORTABLE C			7/27/2009 3:12:44 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Lara, Ralph
 LOCATION: PORTABLE C
 CABINET: GISD TAG # 98-2328
 WE NEED A KEY TO LOCK THE CABINET.

Jessica Lopez

47931					7/28/2009		64		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	ROOM # 40			7/28/2009 2:26:02 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Lara, Ralph
 MS. ALARCON NEEDS A KEY TO LOCK HER CABINET.
 TAG # N/A
 DOUBLE DOOR CABINET
 LOCATION: ROOM # 40

Jessica Lopez

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

48292					8/4/2009		57		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/4/2009 11:32:30 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph		MS. HOLGUIN ROOM # 31 NEEDS A KEY TO HER CABINET CYLINDER # 135E							
-------------	--	--	--	--	--	--	--	--	--

 Jessica Lopez

48419					8/6/2009		55		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	ROOM 33			8/6/2009 9:07:01 AM				
--------	------------------	---------	--	--	---------------------	--	--	--	--

Lara, Ralph		PLEASE FIX CABINET IN ROOM # 33. ENTIRE CYLINDER CAME OFF. IMPORTANT SPECIAL ED. INFORMATION.							
-------------	--	---	--	--	--	--	--	--	--

 Jessica Lopez

48819					8/14/2009		47		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	39			8/14/2009 2:11:34 PM				
--------	------------------	----	--	--	----------------------	--	--	--	--

Herrera, Joel		MR. HERRERA PLEASE REPLACE TILES BY THE BACK EXIT ROOM # 39							
---------------	--	---	--	--	--	--	--	--	--

 Jessica Lopez

49343					8/26/2009		35		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/26/2009 7:50:47 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel		I HAVE PROBLEMS WITH MY WEEDEATER IT DOESNT WORK							
-----------------	--	--	--	--	--	--	--	--	--

 Joel Herrera

49580					9/2/2009		28		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

High	Work In Progress				9/2/2009 10:08:28 AM				
------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Joel		as per our discussion, please remve cattails and repair water leak. if assistance is needed for the repair please call me (mike) so i may support. thanks							
---------------	--	---	--	--	--	--	--	--	--

 Michael Munoz

50195					9/16/2009		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/16/2009 3:25:30 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Joel		MR. HERRERA PLEASE CHECK MS. GAMBOA'S ROOM IT LEAKS WHEN IT RAINS.							
---------------	--	--	--	--	--	--	--	--	--

 Jessica Lopez

50198					9/16/2009		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	32			9/16/2009 3:28:58 PM				
--------	------------------	----	--	--	----------------------	--	--	--	--

Herrera, Joel		MR. HERRERA ROOM # 32 BATHROOM SINK IS FALLING							
---------------	--	--	--	--	--	--	--	--	--

 Jessica Lopez

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Sunland Park ES

50257					9/18/2009		12		\$0.00
Medium	Work In Progress			9/18/2009 2:47:01 PM					
Villalobos, David	please help repair the water leak where the cat tails used to be. i will generate a w/o for angel to deliver the ditch witch,thanks								

Michael Munoz

50258					9/18/2009		12		\$0.00
Medium	Work In Progress			9/18/2009 2:48:53 PM					
Gonzales, Angel	please get w/ david for delivery of ditch witch for repair of water line next week. thanks								

Michael Munoz

50535					9/25/2009		5		\$0.00
Medium	Work In Progress			9/25/2009 3:27:12 PM					
Villalobos, David	KITCHEN'S SINK IS CLOGGED								

Joel Herrera

50687					9/30/2009		0		\$0.00
Medium	Work In Progress			9/30/2009 11:11:18 AM					
Herrera, Joel	MR. HERRERA PLEASE PICK UP ALL PINE CONES LOCATION: KINDER PLAYGROUND								

Jessica Lopez

Count: 20 Work Orders	Avg. Age of WO's	45	Total for Sunland Park ES				0	\$0.00
------------------------------	-------------------------	-----------	----------------------------------	--	--	--	----------	---------------

Location: Sunrise ES

47297					7/6/2009		86		\$0.00
Medium	Work In Progress			7/6/2009 3:02:54 PM					
Lozoya, Manny	need open tool box								

Juan Vargas

47348					7/8/2009		84		\$0.00
Medium	Work In Progress			7/8/2009 8:32:43 AM					
Vargas, Juan	07-01-09 1-check school 9-replace bulbs lights use 5 box cost \$ 170. 00				7/1-10	Material 170.00			

Juan Vargas

47549	Main Building				7/15/2009		77		\$0.00
Medium	Work In Progress			7/15/2009 10:03:47 AM					
Carbajal, Jimmy	Burnisher sr 162634 keeps on turning off while running				9/25/09 - WAITING FOR MOTOR				
Jesus Urquidi									

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunrise ES

47944					7/28/2009		64		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/28/2009 3:42:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		marqui need replace locks							
---------------	--	---------------------------	--	--	--	--	--	--	--

Juan Vargas

47946					7/28/2009		64		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/28/2009 3:44:54 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		door on estrellas hall need fix frame							
---------------	--	---------------------------------------	--	--	--	--	--	--	--

Juan Vargas

48118		Office			7/31/2009		61		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	NURSE OFFICE			7/31/2009 2:59:13 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Lozoya, Manny		NURSE NEEDS TO HAVE TWO LOCKS ADDED TO CABINETS							
---------------	--	---	--	--	--	--	--	--	--

Joanne Munoz

49070					8/20/2009		41		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/20/2009 10:53:21 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny		FIRE EXTINGUISHERS NEED SERVICE							
---------------	--	---------------------------------	--	--	--	--	--	--	--

Danny Orozco

49814					9/6/2009		24		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/6/2009 12:22:55 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Jacquez, Ricardo		Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.							
------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

50054		Cafeteria			9/14/2009		16		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/14/2009 12:10:28 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny		KEY TO THE WALK - IN FREEZER BROKE. NEEDS A NEW ONE.							
---------------	--	--	--	--	--	--	--	--	--

		VIRGINIA PRUIT SNP MGR 824-3194							
--	--	---------------------------------	--	--	--	--	--	--	--

Jacqueline Aguilar

50566					9/28/2009		2		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/28/2009 8:52:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Briones, Enrique		Deliver to SRE PO #91001488 One box to Edna Clary							
------------------	--	--	--	--	--	--	--	--	--

Margaret Villalobos

50605					9/28/2009		2		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				9/28/2009 4:36:09 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Briones, Enrique		On September 30, 2009, please deliver one (1) box of Math Materials (2nd Grade Cards Package) to Sunrise Elementary.							
------------------	--	--	--	--	--	--	--	--	--

Yolie Jacquez

9/30/2009 6:01:23 PM

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Sunrise ES

50667					9/30/2009		0		\$0.00
Medium	Work In Progress				9/30/2009 12:23:02 AM				
Vargas, Juan	Monthly - Sunrise ES A16 (Fan Exh.)(S. Annual) - Refer to PM schedule details.								

Margret Villalobos

Count: 12 Work Orders	Avg. Age of WO's 43	Total for Sunrise ES	0	\$0.00
------------------------------	----------------------------	-----------------------------	----------	---------------

Location: Vado ES

47808					7/24/2009		68		\$0.00
Medium	Work In Progress				7/24/2009 11:16:09 AM				
Lozoya, Manny	rm 107 class rm door will not open /safety hazard -fire drill exit-please ck out asap								

Danny Vega

48098					7/31/2009		61		\$0.00
Medium	Work In Progress				7/31/2009 10:23:46 AM				

Ontiveros, Guadalupe NEED TRACTOR AND DISKS FOR BACK PONDING AREA

Danny Miranda

49012					8/19/2009		42		\$0.00
Medium	Work In Progress				8/19/2009 11:52:30 AM				

Miranda, Danny need two wood 4"x4"x8' to build ramp for mower

Danny Miranda

49014					8/19/2009		42		\$0.00
Medium	Work In Progress				8/19/2009 11:56:27 AM				

Miranda, Danny need two bundles of 2'x4' ceiling tile (56090A)

Danny Miranda

49015					8/19/2009		42		\$0.00
Medium	Work In Progress				8/19/2009 11:59:24 AM				

Miranda, Danny need 5 gal. wt. paint for (classroom's and hallways (DUNN-EDWARDS HAS COLOR ON FILE)

Danny Miranda

49016					8/19/2009		42		\$0.00
Medium	Work In Progress				8/19/2009 11:59:38 AM				

Miranda, Danny need 5 gal. wt. paint for (classroom's and hallways (DUNN-EDWARDS HAS COLOR ON FILE)

Danny Miranda

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
49245					8/25/2009		36		\$0.00
Medium	Work In Progress			8/25/2009 12:28:14 PM					
Miranda, Danny	NEED A PLASTIC LIGHT COVER 2X4 IN LIBRARY								
<u>Danny Miranda</u>									
49842					9/8/2009		22		\$0.00
Medium	Work In Progress			9/8/2009 1:41:20 PM					
Miranda, Danny	NEED 6"X24" STICK ON SIGNS VERTICAL (NO PARKING) (FIRE LANE) THREE EA.								
<u>Danny Miranda</u>									
49932					9/10/2009		20		\$0.00
Medium	Work In Progress			9/10/2009 1:12:43 PM					
Ontiveros, Joe	need to ck. boiler to kitchen no hot water		AS PER DANNY, TAKEN CARE OF BY JOE						
<u>Danny Miranda</u>									
50316					9/21/2009		9		\$0.00
Medium	Work In Progress			9/21/2009 11:28:15 AM					
Ontiveros, Guadalupe	please get quote to bore ponds for water to flow in the front campus.please see mike.thanks								
<u>Michael Munoz</u>									
50552					9/28/2009		2		\$0.00
Medium	Work In Progress			9/28/2009 8:07:44 AM					
Carrasco, Danny	NEED SPRAYER AND PAINT TO SPRAY LINES ON SOCCER FIELD								
<u>Danny Miranda</u>									
50565					9/28/2009		2		\$0.00
Medium	Work In Progress			9/28/2009 8:52:07 AM					
Gonzales, Angel	NEED MOWER TO CUT GRASS								
<u>Danny Miranda</u>									
50590					9/28/2009		2		\$0.00
Medium	Work In Progress			9/28/2009 3:25:58 PM					
Gonzales, Angel	International Tractor with Mower - Repair and deliver to Danny Miranda for use at Vado Elem.								
<u>Alfredo Holguin</u>									
50609					9/29/2009		1		\$0.00
Medium	Work In Progress			9/29/2009 7:51:07 AM					
Sotelo, Enrique	NEED NEW HAND DRYER IN GIRLS R.R. 300-WING								
<u>Danny Miranda</u>									

595- Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 6/30/2010 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Vado ES							
50661					9/30/2009		0		\$0.00
Medium	Work In Progress				9/30/2009 12:23:00 AM				
Miranda, Danny		Monthly - Vado ES A-16 - Fan Exhaust Semiannual - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
50692					9/30/2009		0		\$0.00
Medium	Work In Progress				9/30/2009 2:40:26 PM				
Miranda, Danny		Need to cut grass and weeds around campus.							
<u>Michael Munoz</u>									
Count: 16 Work Orders		Avg. Age of WO's 24			Total for Vado ES			0	\$0.00
Count: 595 Work Orders		Avg. Age of WO's 33			Grand Total			12	\$447.00