

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Alma Del Valle Daycare</b>							
71874					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress		4/10/2011 12:14:20 AM						
Montoya, Adam		Monthly - QRTLY BLDG INSP REPORTS (ADV) - Refer to PM schedule details.							
Jesus Estrada									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>10</b>	<b>Total for Alma Del Valle Daycare</b>			<b>0</b>	<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
<b>Location: Anthony - On Track Pre-K</b>									
66798					11/18/2010		153		\$0.00
Medium	Work In Progress				11/18/2010 7:39:17 AM				
Ronquillo, Ruben	Playground equipment install upper primary ,slide is broken bottom edge				12/3 - Asp Mike route to Ruben				
Hector Villalobos									
71992					4/11/2011		9		\$0.00
Medium	Work In Progress				4/11/2011 4:08:07 PM				
Estrada, Jesus	Pre-K offices need tile to be replaced by carpet. bathroom and storage need tile replaced with new tile.								
Jesus Estrada									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>81</b>	<b>Total for Anthony - On Track Pre-K</b>		<b>0</b>		<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Anthony ES</b>								
62752					8/20/2010		243		\$0.00	
Medium	Work In Progress	SPECIAL		8/20/2010 3:26:11 PM						
Lozoya, Manny		EXCHANGE DOORS BETWEEN ANGIE SANCHEZ AND MARGARET VILLALOBOS/ HALF DOOR TO ANGIE'S OFFICE FULL DOOR TO MARGARET'S OFFICE								
Margaret Villalobos										
65000		Portables			10/6/2010		196		\$0.00	
Medium	Work In Progress			10/6/2010 7:51:35 AM						
Villalobos, Hector		I need materials for pt 220 2x4x10 and 4x8 siding skiting pt								
Hector Villalobos										
66080					10/31/2010	11/21/2010	171		\$0.00	
Medium	Work In Progress			10/31/2010 12:36:20						
Orozco, Danny		Monthly - Anthony ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos										
66799					11/18/2010		153		\$0.00	
Medium	Work In Progress			11/18/2010 7:44:52 AM						
Ronquillo, Ruben		Upper primary playground equipment needs rubber mat for steps				12/3 - Asp Mike route to Ruben				
Hector Villalobos										
67131					12/3/2010		138		\$0.00	
Medium	Work In Progress			12/3/2010 1:25:25 PM						
Flores, Pete		truck will not start. Will need a starter # 153								
Hector Villalobos										
67266					12/5/2010		136		\$0.00	
Medium	Work In Progress			12/5/2010 12:27:27 AM						
Sanchez, Raul		Monthly - Anthony ES - Monthly Meter Readings - Refer to PM schedule details.								
Margret Villalobos										
67602		Mechanical			12/14/2010		127		\$0.00	
Medium	Work In Progress			12/14/2010 11:00:40						
Villalobos, David		For David V upper primary boilers back flow valve is leaking								
Hector Villalobos										
67816					1/2/2011	2/2/2011	108		\$0.00	
Medium	Work In Progress			1/2/2011 12:28:36 AM						
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
67868					1/2/2011	1/10/2011	108		\$0.00
Medium	Work In Progress				1/2/2011 12:29:01 AM				
Villalobos, Hector	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67869					1/2/2011	1/10/2011	108		\$0.00
Medium	Work In Progress				1/2/2011 12:29:01 AM				
Villalobos, Hector	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67870					1/2/2011	1/8/2011	108		\$0.00
Medium	Work In Progress				1/2/2011 12:29:02 AM				
Villalobos, Hector	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67871					1/2/2011	1/10/2011	108		\$0.00
Medium	Work In Progress				1/2/2011 12:29:02 AM				
Villalobos, Hector	Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68387					1/13/2011		97		\$0.00
Medium	Work In Progress	1			1/13/2011 4:05:10 PM				
Lozoya, Manny	PLEASE CHECK KEY HAVING EXTREME DIFFICULTY OPENING DOOR LOCATION PORTABLE 1								
<u>Jessica Lopez</u>									
68524					1/19/2011		91		\$0.00
Medium	Work In Progress	PORTABLE 5 &			1/19/2011 8:08:13 AM				
Appelzoller, Fred	NO WATER IN PORTABLES 5 AND 6 (PRE/K STUDENTS) PLEASE CHECK PLUMBING								
<u>Jessica Lopez</u>									
69051					2/6/2011	2/12/2011	73		\$0.00
Medium	Work In Progress				2/6/2011 12:33:45 AM				
Villalobos, Hector	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69052					2/6/2011	2/14/2011	73		\$0.00
Medium	Work In Progress				2/6/2011 12:33:46 AM				
Villalobos, Hector	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
69053					2/6/2011	2/14/2011	73		\$0.00
Medium	Work In Progress			2/6/2011 12:33:46 AM					
Villalobos, Hector	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69175					2/8/2011		71		\$0.00
Medium	Work In Progress			2/8/2011 8:41:41 AM					
Moncayo, Fernando	ADULT BATHROOM CEILING COLLAPSED PLEASE REPAIR								
<u>Jessica Lopez</u>									
69202					2/8/2011		71		\$0.00
Medium	Work In Progress			2/8/2011 12:16:37 PM					
Estrada, Jesus	NEED TO REPLACE CARPET & VCT IN PORTABLE #117 (NOT A CLASSROOM)								
<u>Jesus Estrada</u>									
69445	Main Building				2/14/2011		65		\$0.00
Medium	Work In Progress			2/14/2011 12:24:54 PM					
Appelzoller, Fred	repair or replace water faucet near entrance to main building								
<u>David Vega</u>									
69494	Main Building	Classroom			2/15/2011		64		\$0.00
High	Work In Progress			2/15/2011 9:08:42 AM					
Solis, Lorenzo	coil in rm 102 burst due to weather, please replace and install when it purchased and start-up.thankyou								
<u>Michael Munoz</u>									
69497		Portables			2/15/2011		64		\$0.00
High	Work In Progress			2/15/2011 9:30:27 AM					
Appelzoller, Fred	portables 217, 218,220 and wooden portable on east side end water burst due to storm. please repair lines and bring portables back to service.thank you								
<u>Michael Munoz</u>									
69768	Cafeteria				2/22/2011		57		\$0.00
Medium	Work In Progress			2/22/2011 1:49:09 PM					
Orozco, Danny	OVEN IS NOT HEATING UP AT ALL. SNP MANAGER BECKY S. 882.3507								
<u>Maritza Gonzalez</u>									
69985					2/28/2011		51		\$0.00
Medium	Work In Progress	SPED		2/28/2011 9:22:20 AM					
Moncayo, Fernando	SECOND REQUEST TO HAVE WINDOWS SEALED AND NOW TO HAVE THE WINDOW SILLS DUSTED (THERE IS A LOT OF DIRT)								
<u>Margaret Villalobos</u>									
4/20/2011 11:58:47 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
70000	Main Building	Classroom			2/28/2011		51		\$0.00
Medium	Work In Progress			2/28/2011 11:22:09 AM					
Moncayo, Fernando	all rooms in upper primary (VILLAGE) need door sweeps some have them and need to be lowered and some dont have them at all teachers are complaining that alot of dirt and dust is coming in and children are snizzing and coughing,especially ones with azthma								
<u>David Vega</u>									
70086	Main Building				3/2/2011		49		\$0.00
Medium	Work In Progress			3/2/2011 9:19:50 AM					
Appelzoller, Fred	repair or replace water faucet near entrane to main building								
<u>David Vega</u>									
70123	Main Building				3/3/2011		48		\$0.00
Medium	Work In Progress			3/3/2011 8:16:52 AM					
Lozoya, Manny	having trouble opening door main entrance to primary bldg(alamo)								
<u>David Vega</u>									
70153					3/3/2011		48		\$0.00
Medium	Work In Progress	SPED OFFICE		3/3/2011 2:30:52 PM					
Lozoya, Manny	CHANGE DOOR KNOB IN ROOM 111 @ THE ALAMO IT DOES NOT LOCK ANYMORE THE TOP LOCK DOES WORK (COMPUTERS SET UP IN THAT ROOM FOR TRAININGS)								
<u>Margaret Villalobos</u>									
70236					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:36 AM					
Orozco, Danny	Yearly - Anthony ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70494	Main Building	Restroom (Boys)			3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 11:16:14 AM					
Appelzoller, Fred	boys restroom (6th grade) flushes real slow,last stall towards wall								
<u>David Vega</u>									
70567					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 8:02:56 AM					
Estrada, Jesus	NEED CARPET REPLACED IN PORTABLE #217								
Jesus Estrada									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
70593					3/10/2011		41		\$0.00
Medium	Work In Progress	SPED OFFICE		3/10/2011 9:56:47 AM					
Moncayo, Fernando		MOVE FAMILY INTERVENTION SPECIALIST CABINETS FROM HALLWAY INTO ROOM 112							
Margaret Villalobos									
70776	Main Building				3/15/2011		36		\$0.00
Medium	Work In Progress			3/15/2011 10:22:52 AM					
Flores, Pete		weed eater serai#272031758 needs minor repair, weed eater string spool broken							
David Vega									
70777	Main Building				3/15/2011		36		\$0.00
Medium	Work In Progress			3/15/2011 10:25:03 AM					
Flores, Pete		weedeater serial #272031746 needs minor repair, weedeater string spool is broken							
David Vega									
71197					3/29/2011		22		\$0.00
Medium	Work In Progress	PORTABLE 1		3/29/2011 9:49:44 AM					
Lozoya, Manny		ANN MITCHELL LOST HER KEY (KA51) PORTABLE 1 NEEDS TO PAY AND GET KEY REPLACED \$21.50							
Jessica Lopez									
71201					3/29/2011		22		\$0.00
Medium	Work In Progress			3/29/2011 10:27:04 AM					
Orozco, Danny		REACH IN IS AT 80 DEGREES. SNP MANAGER BECKY S. 882.3507.							
Maritza Gonzalez									
71252					3/30/2011		21		\$0.00
Medium	Work In Progress	SPED		3/30/2011 2:03:20 PM					
Vega, David		REMOVE BROKEN FURNITURE AND OLD FILE CABINETS FROM THE HALL @ THE ALAMO IN ANTHONY ELEMENTARY (ASK MARGARET)							
Margaret Villalobos									
71428					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:50 AM					
Orozco, Danny		Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
71481					4/3/2011	5/4/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:14 AM					
Villalobos, Hector		Monthly - Anthony ES A16 (Fan Exhst.)(Semi. Ann.) - Refer to PM schedule details.							
Margret Villalobos									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
71482					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:15 AM					
Villalobos, Hector	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71483					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:15 AM					
Villalobos, Hector	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71484					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:16 AM					
Villalobos, Hector	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71587	Main Building				4/4/2011		16		\$0.00
Medium	Work In Progress			4/4/2011 8:10:52 AM					
Villalobos, Hector	need paint for out side walls inside walls								
<u>Hector Villalobos</u>									
71691		Portables			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 7:29:31 AM					
Lozoya, Manny	pt 221 need to be secure for music instruments. dead bolt key								
<u>Hector Villalobos</u>									
71885					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:26 AM					
Vega, David	Monthly - QRTLY BLDG INSP REPORT (AE) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
71917		Portables			4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 7:40:02 AM					
Solis, Lorenzo	pt 3 refrigeration unit not working								
<u>Hector Villalobos</u>									
71946					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 10:50:16 AM					
Villalobos, Hector	A VAULT IS REQUIRED IN THE SUPPLY ROOM AND THE RESTROOM LOCATED NEXT TO IT								
<u>Jessica Lopez</u>									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
71957	Office				4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 11:30:18 AM					
Ronquillo, Ruben	Upper primary rooms 110, 111. bronken windows 3 19 1/4x 14 1/4 wire glass								
<u>Hector Villalobos</u>									
72007	Classroom				4/12/2011		8		\$0.00
Medium	Work In Progress			4/12/2011 2:02:52 PM					
Villalobos, Hector	upper primary need door sweeps 36 inch . need 20								
<u>Hector Villalobos</u>									
72008	Classroom				4/12/2011		8		\$0.00
Medium	Work In Progress			4/12/2011 2:04:36 PM					
Villalobos, Hector	room 111 need motor for a/c 3/4								
<u>Hector Villalobos</u>									
72033	Portables				4/13/2011		7		\$0.00
High	Work In Progress			4/13/2011 8:22:58 AM					
Villalobos, Hector	Please repair the wall in Ms. Butlers portable with drywall and cemplite so the Fred can finish installing comodes and sinks. Let Fred know when complete. Thanks								
<u>Michael Munoz</u>									
72048					4/13/2011		7		\$0.00
Medium	Work In Progress			4/13/2011 12:45:40 PM					
Lozoya, Manny	CARPET WAS REPLACED IN PORTABLE 220 (WO #69204), DOOR NEEDS TO BE SHAVED DOWN IN ORDER TO OPEN/CLOSE PROPERLY								
<u>Jesus Estrada</u>									
72081					4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 8:20:55 AM					
Villalobos, Hector	Need to move out furniture in the following areas. (See attached e-mail)								
<u>Michael Munoz</u>									
72139	Nurse Building				4/15/2011		5		\$0.00
Medium	Work In Progress			4/15/2011 1:12:45 PM					
Ronquillo, Ruben	broken window 19 1/4 x15 1/4 nurse office 1								
<u>Hector Villalobos</u>									
72144	Main Building				4/15/2011		5		\$0.00
Medium	Work In Progress			4/15/2011 2:48:20 PM					
Villalobos, Hector	mild blg outside south of blg hose bibbs valve water will not close. needs kit								
<u>Hector Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
72173					4/18/2011		2		\$0.00
Medium	Work In Progress	6TH GRADE		4/18/2011 12:02:34 PM					
Briones, Enrique	WAREHOUSE PICKUP: 19 CHAIRS, GISD 99-0189 CABINET, 96-5237- CABINET, 96-5261-BOOK SHELF, BOOKSHELF, 96-5216-BOOK SHELF, WHITE SHELF, GISD 00-6088 TEACHER DESK, 96-1879 SHELF, GISD 01-09430 SAND BOX, BROWN SHELF, TEACHER DESK, GISD TAG 96-1778 KIDNEY TABLE, KIDNEY TABLE, GISD 96-1980 BLACK CABINET, BLUE SHELF, GISD 96-1875 SHELF, CABINET, 104 STUDENT DESKS, KIDNEY TABLE, SHELF, GISD 96-5272 CABINET, BOOK SHELF, TABLE, BOOK SHELF 00-0169, BOOK SHELF, GISD 96-1956 YELLOW CABINET, GISD 96-5260 CABINET, GISD 96-1984 CABINET, 96-4986 BOOK SHELF, 2 BOOK SHELVES, GISD 96-5242 YELLOW CABINET, KIDNEY TALBLE, WHITE SHELF, KIDNEY TABLE, 96-1994 CABINET, 96 -1950 YELLOW CABINET, 2 CABINETS, 1 KIDNEY TABLE, YELLOW SHELF, 96-5261 BROWN SHELF, 96 -5237 CABINET, 96-5239 CABINET, BOOK RACK, TABLE, SHELF								
Jessica Lopez									
72218					4/19/2011		1		\$0.00
Medium	Work In Progress	6TH GRADE		4/19/2011 8:43:11 AM					
Briones, Enrique	WAREHOUSE PICK UP: BOOK SHELF, GISD 96-1961 CABINET AND GISD 96-5290 CABINET								
Jessica Lopez									
72274					4/20/2011		0		\$0.00
Medium	Work In Progress	SPED OFFICE		4/20/2011 7:32:16 AM					
Villalobos, Hector	TURN ON AIR CONDITIONERS IN THE ALAMO SPED OFFICES								
Margaret Villalobos									
72281	Office				4/20/2011		0		\$0.00
Medium	Work In Progress			4/20/2011 8:04:12 AM					
Appelzoller, Fred	upper primary office main line clog restroom , needs cable								
Hector Villalobos									
<b>Count: 59 Work Orders</b>			<b>Avg. Age of WO's 55</b>			<b>Total for Anthony ES</b>	<b>0</b>		<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
60598					7/4/2010	7/25/2010	290		\$0.00
Medium	Work In Progress			7/4/2010 12:23:43 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
64739					10/3/2010	10/24/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:58 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
66081					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:20					
Orozco, Danny	Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
66431		Cafeteria			11/8/2010		163		\$0.00
Medium	Work In Progress			11/8/2010 9:40:42 AM					
Orozco, Danny	REACH IN FREEZER TEMP AT 58								
ELSA ORTEGA SNP MGR 882-2417									
Jacqueline Aguilar									
66601					11/15/2010		156		\$0.00
Medium	Work In Progress			11/15/2010 8:09:27 AM					
Solis, Lorenzo	MR LORENZO SOLIS SIR THE CIRCULATING PUMP IN THE BOILER ROOM IS LEAKING BLEW A GASKET NEED GO FIX THANK YOU SIR AND GOD BLESS								
Adan Duran									
66713					11/16/2010		155		\$0.00
Medium	Work In Progress			11/16/2010 11:06:12					
Flores, Pete	MR PETE FLORES SIR MY JOHN DEERE MOWER NEEDS BLADES NEED TO BE SERVICE IT HAS NOT BEEN SERVICE FOR TWO YEARS THANK YOU SIR AND GOD BLESS								
Adan Duran									
67267					12/5/2010		136		\$0.00
Medium	Work In Progress			12/5/2010 12:27:28 AM					
Sanchez, Raul	Monthly - Berino ES - Monthly Meter Readings - Refer to PM schedule details.								
Margret Villalobos									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Berino ES</b>									
67435					12/9/2010		132		\$0.00
Medium	Work In Progress			12/9/2010 12:20:33 PM					
Appelzoller, Fred	MR FRED APPELL SIR THE CIRCULATION PUMP FOR THE HOT WATER NOT WORKING NOT GETTING HOT WATER TO OFFICE MAY NEED TO REPLACE THANK YOU SIR AND GOD BLESS								
Adan Duran									
67436					12/9/2010		132		\$0.00
Medium	Work In Progress			12/9/2010 12:23:08 PM					
Villalobos, David	MR DAVID VILLALOBOS SIR THE BACK FLOW VALUE IS LEAKING NEED TO CHECK THANK YOU SIR AND GOD BLESS								
Adan Duran									
67817					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:36 AM					
Villalobos, David	Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
67836					1/2/2011	1/23/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:44 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
68675					1/24/2011		86		\$0.00
Medium	Work In Progress			1/24/2011 8:52:16 AM					
Lozoya, Manny	MR MANNY LOZOYA SIR THE FILE CABINET ROOM 118 THE CINDYLER CAME OUT IS ALL BROKEN NEED TO REPLACE THEY ARE TESTING AND NEED TO GET INTO CABINET THANK YOU SIR AND GOD BLESS								
Adan Duran									
68688					1/24/2011		86		\$0.00
Medium	Work In Progress			1/24/2011 12:36:15 PM					
Lozoya, Manny	MR MANNY LOZOYA SIR NEED TO CHANGE DOOR LOCK WEST WING WHERE CONSTRUCTION WORKER HAVE THEIR DOOR SO THAT IT WILL NOT OPEN FROM THEIR SIDE THANK YOU SIR AND GOD BLESS								
Adan Duran									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
68936					1/31/2011		79		\$0.00
Medium	Work In Progress			1/31/2011 3:11:05 PM					
Ontiveros, Guadalupe	MR LUPE ONTIVEOS SIR AS PER MR MUNOZ NEED THE USE OF ONE OF YOUR TRATORS TO SPEAD DIRT ON PLAYGROUND THANK SIR AND GOOD BLESS								
Adan Duran									
69313		Mechanical			2/10/2011		69		\$0.00
Medium	Work In Progress			2/10/2011 8:24:01 AM					
Lozoya, Manny	STORM LOCK PROBLEM SOMTHING STUCK INSIDE ON LOCK SET								
Manny Lozoya									
69346					2/10/2011		69		\$0.00
Medium	Work In Progress			2/10/2011 3:33:06 PM					
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR THE ELETRIC LINES TO IRRGATION VALVES WHERE CUT NEED TO BE RESPLICE NEED TO KNOW WHICH GOES WHERE THANK YOU								
Adan Duran									
70194					3/4/2011		47		\$0.00
Medium	Work In Progress			3/4/2011 2:33:42 PM					
Appelzoller, Fred	MR FRED APPELOZLLER THE FUACETS IN ROOM 133 NEED TO BE REPLACE WILL NOT SHUT OFF OLD AND RUSTY THANK YOU SIR AND GOD BLESS								
Adan Duran									
70195					3/4/2011		47		\$0.00
Medium	Work In Progress			3/4/2011 2:39:32 PM					
Appelzoller, Fred	MR FRED APPELOZLLER SIR THE HEATING UNIT ON BOTTOM THAT HEATS WATER FOR KITCHEN HAS A CRACK ON MONIFOLD NEED REPLACING THANK YOU SIR AND GOD BLESS YOU								
Adan Duran									
70237					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:37 AM					
Orozco, Danny	Yearly - Berino ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
70607					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 2:43:43 PM					
Villalobos, David	MR DAVID VILLALOBOS SIR THE BACK FLOW PREVENTOR IS LEAKING PRETTY BAD NEEDS REPAIR THANK YOU SIR AND GOD BLESS								
Adan Duran									
4/20/2011 11:58:48 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
70914					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 9:39:47 AM					
Appelzoller, Fred	MR FRED APPELLOZLLER SIR THE COMODE IN WOMENS RESTROOM FRONT LOBBY IS BROKEN NEEDS TO BE REPLACE THE TOP RIM IS MISSING A BIG CHUNK THANK YOU SIR AND GOD BLESS								
Adan Duran									
71110		Athletic Field			3/28/2011		23		\$0.00
Medium	Work In Progress			3/28/2011 7:36:58 AM					
Ontiveros, Guadalupe	please remove 4 adjustable basketball courts /goals and set in at berino.adan is aware of the locations.sal g will support with this project. see mike for details.thank you								
Joe Munoz									
71237					3/30/2011		21		\$0.00
Medium	Work In Progress			3/30/2011 10:02:41 AM					
Sanchez, Raul	MR RAUL SANCHEZ SIR I'M HAVING TROUBLE WITH COMPRESSER WILL NOT SHUT OFF AT 120 KEEPS GOING TILL RELEF VALUE POPS OPEN THE CUT OF SWITCH MAY BE BAD PLEASE CHECK THANK YOU AND GOD BLESS								
Adan Duran									
71422					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:48 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
71429					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:51 AM					
Orozco, Danny	Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71768		Athletic Field			4/7/2011		13		\$0.00
Medium	Work In Progress			4/7/2011 8:02:54 AM					
Ontiveros, Guadalupe	please assist adan with a row of sprinklers that is not working.thank you								
Michael Munoz									
71896					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:30 AM					
Cortez, Jimmy	Monthly - QRTLY BLDG INSP REPORTS (BE) - Refer to PM schedule details.								
Jesus Estrada									
4/20/2011 11:58:48 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Berino ES</b>									
72176					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 12:48:11 PM					
Appelzoller, Fred	MR FRED APPELLOZER SIR THE SINK ROOM 117 DRAIN PIPE HAS A HOLE ITS 2" GALVANIZE PIPE NEED TO REPLACE THANK YOU SIR AND GOD BLESS								
Adan Duran									
72180					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 2:43:34 PM					
Duran, Adan	MR ADURAN SIR THERE ARE SEVERAL BROKEN SPRINKLER NORTH PLAYGROUND AND SOME DO NOT WORK NEED TO REPLACE								
Adan Duran									
72243					4/19/2011		1		\$0.00
Medium	Work In Progress			4/19/2011 2:43:33 PM					
Sotelo, Enrique	MR ENRIQUE SOTELO SIR THE BALLEST WEST HALL WAY IN FRONT OF NURSE OFFICE NEEDS REPLACING THANK YOU AND GOD BLESS								
Adan Duran									
<b>Count: 30 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>82</b>		<b>Total for Berino ES</b>	<b>0</b>		<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Chaparral Elem East Pre-K</b>							
71758					4/6/2011		14		\$0.00
Medium	Work In Progress	CES PreK			4/6/2011 3:57:51 PM				
Briones, Enrique	Please pick up a black office chair (broken) from Chaparral Prek T-I 104866		Thank you						
Lucia Almeraz									
<b>Count: 1 Work Orders</b>	<b>Avg. Age of WO's</b>		<b>14</b>	<b>Total for Chaparral Elem East Pre-K</b>				<b>0</b>	<b>\$0.00</b>



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
61455					7/28/2010		266		\$0.00
Medium	Work In Progress			7/28/2010 3:35:20 PM					
Ontiveros, Joe	Need to replace leaking faucets in new wing classrooms. Thank you								
<u>Guillermo Hernandez</u>									
66082					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:20					
Orozco, Danny	Monthly - Chaparral ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66172					10/31/2010		171		\$0.00
Medium	Work In Progress			10/31/2010 12:37:03					
Sanchez, Raul	Monthly - Chaparral ES DP-91 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67256					12/5/2010		136		\$0.00
Medium	Work In Progress			12/5/2010 12:27:24 AM					
Sanchez, Raul	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67815					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:36 AM					
Villalobos, David	Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68417					1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 8:33:22 AM					
Gonzalez, Salvador	Need to replace and reinforce bend pole to the canopy on main playground and need to sew tarp or patch a hole made by rubbing on a lower pole. Thank you								
<u>Guillermo Hernandez</u>									
68667					1/21/2011		89		\$0.00
Medium	Work In Progress			1/21/2011 3:58:12 PM					
Ontiveros, Joe	Need to replace broken toilet tank lid in mes restroom front lobby. Thank you.								
<u>Guillermo Hernandez</u>									
68836					1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 11:16:47 AM					
Hernandez, Guillermo	Need to replace exhaust fan motors in classrooms #201 and #212. Thank you								
<u>Guillermo Hernandez</u>									
4/20/2011 11:58:48 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral ES</b>									
68841	Main Building				1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 2:03:29 PM					
Solis, Lorenzo	Need to replace A/C unit Principals office, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68842	Main Building				1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 2:04:55 PM					
Solis, Lorenzo	Need to replace A/C unit Assistant Principals office, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68843	Main Building				1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 2:06:27 PM					
Solis, Lorenzo	Need to replace A/C unit Room #101, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68844	Main Building				1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 2:07:07 PM					
Solis, Lorenzo	Need to replace A/C unit Room #103, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68845	Main Building				1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 2:07:48 PM					
Solis, Lorenzo	Need to replace A/C unit Room #104, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68846	Main Building				1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 2:08:54 PM					
Solis, Lorenzo	Need to replace A/C unit Library office, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68847	Main Building				1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 2:10:15 PM					
Solis, Lorenzo	Need to replace A/C unit in the Library, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68848	Main Building				1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 2:11:24 PM					
Solis, Lorenzo	Need to replace A/C unit Lobby front office, side draft. Thank you.								
<u>Guillermo Hernandez</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral ES</b>									
68849	Main Building				1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 2:12:12 PM					
Solis, Lorenzo		Need to replace A/C unit Room #302, side draft. Thank you.							
<u>Guillermo Hernandez</u>									
68932	Main Building	Hallway/Corridor			1/31/2011		79		\$0.00
Medium	Work In Progress	School		1/31/2011 2:44:44 PM					
Hernandez, Guillermo		Memo please install map rails							
<u>Jennifer Corral</u>									
69100					2/6/2011		73		\$0.00
Medium	Work In Progress			2/6/2011 12:34:05 AM					
Sanchez, Raul		Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
69939					2/25/2011		54		\$0.00
Medium	Work In Progress			2/25/2011 2:54:32 PM					
Estrada, Jesus		NEED TO REPLACE VCT IN BOYS & GIRLS BATHROOMS / E. WING				W.O. #72378 SUBMITTED FOR TOILET REMOVAL ON 4/27/11			
<u>Jesus Estrada</u>									
70149					3/3/2011		48		\$0.00
Medium	Work In Progress			3/3/2011 12:31:54 PM					
Ontiveros, Guadalupe		Lupe would you please stop by to check the irrigation tank there is a small water leak on the compressor and on the gauge meter. Thank you							
<u>Guillermo Hernandez</u>									
70238					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:37 AM					
Orozco, Danny		Yearly - Chaparral ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
70756		Lift Station			3/14/2011		37		\$0.00
Medium	Work In Progress			3/14/2011 3:57:35 PM					
Sanchez, Raul		Need to contract services with lift station contractor; Cubic Water Construction, Inc. and repair broken pipe in north pump column & replace other pump piping with sch 80 PVC. Contractor has all the safety equipment needed to do the job. We do not.							
Raul Sanchez									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
70850					3/16/2011		35		\$0.00
Medium	Work In Progress			3/16/2011 3:53:25 PM					
Ontiveros, Guadalupe		Lupe can you stop by to check the covers for the main valves for irrigation on the field (time's = 3). They need to be replaced safety issue. Thank you							
Guillermo Hernandez									
71430					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:51 AM					
Orozco, Danny		Monthly - Chapparral ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
71471					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:10 AM					
Hernandez, Guillermo		Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
71568					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:51 AM					
Sanchez, Raul		Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.							
Margret Villalobos									
71884					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:25 AM					
Ramirez, Daniel		Monthly - QRTLY BLDG INSP REPORT (CE) - Refer to PM schedule details.							
Jesus Estrada									
71890					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:28 AM					
Hernandez, Guillermo		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
71967	Main Building	Portables			4/11/2011		9		\$0.00
Medium	Work In Progress	P-2			4/11/2011 2:31:52 PM				
Hernandez, Guillermo		Transport Display Panels(for Memo). see Ms. Ballard or Ms. Marquis							
Jennifer Corral									
72044					4/13/2011		7		\$0.00
Medium	Work In Progress			4/13/2011 11:00:56 AM					
Gonzalez, Salvador		Need to weld broken pipe on sign by busses turn around and cut metal plate by E wing rain run out. Thank you							
Guillermo Hernandez									
4/20/2011 11:58:48 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
72045					4/13/2011		7		\$0.00
Medium	Work In Progress			4/13/2011 11:03:21 AM					
Flores, Pete	Need to use Bobcat to add sand to playground and add crusher fine to side salks. Thank you.								
Guillermo Hernandez									
72046					4/13/2011		7		\$0.00
Medium	Work In Progress			4/13/2011 11:05:13 AM					
Ontiveros, Guadalupe	Need 2 loads of playground sand and 2 loads of crusher fine. thank you.								
Guillermo Hernandez									
72161					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 8:12:54 AM					
Lozoya, Manny	Please generate a work order for the locksmith to Determine the Replacement Cost for gate key, She will need to pay for any rekeying cost. (Cynthia Linck-Mobile Home Occupant)								
Alfredo Holguin									
72179					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 2:29:57 PM					
Ontiveros, Joe	Need to unclog water fountains in the 3rd grade hallway. Thank you								
Guillermo Hernandez									
72278					4/20/2011		0		\$0.00
Medium	Work In Progress			4/20/2011 7:55:11 AM					
Hernandez, Guillermo	NEED TO REMOVE TOILETS IN BOYS AND GIRLS RESTROOMS ON WEDNESDAY, APRIL 27. RODRIGUEZ UPHOLSTERY WILL BE REPLACE VCT (W.O. #69939) ON THURSDAY, FRIDAY & SATURDAY. TOILETS NEED TO BE REPLACED ON MONDAY, MAY 2 OR AFTER.								
Jesus Estrada									
<b>Count: 36 Work Orders</b>		<b>Avg. Age of WO's 65</b>			<b>Total for Chaparral ES</b>			<b>0</b>	<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
60938		Custodial			7/13/2010		281		\$0.00
Medium	Work In Progress			7/13/2010 6:39:07 AM					
Carbajal, Jimmy		SWEEPER SN# 072820509 ESTA QUEBRADO DE LOS CEPILLOS Y NO FUNCIONA EL FRENO.				1/31/10 - ASP JIMMY, NO PARTS; STILL PENDING REPAIR			
Marisela Torres									
61938					8/5/2010		258		\$0.00
Medium	Work In Progress			8/5/2010 10:28:48 AM					
Lozoya, Manny		REQUESTING DOOR BETWEEN GIRLS LOCKER EAST,AND WEST.DOOR WAS REMOVED AND NEVER INSTALLED BACK. ACCORDING TO STAFF NOBODY KNOWS ABOUT THIS DOOR.							
Paul Quinones									
61990					8/6/2010		257		\$0.00
Medium	Work In Progress			8/6/2010 8:27:56 AM					
Ontiveros, Joe		NO HOT WATER IN SHOWERS,AND COACH SMITHS SHOWER STALL AS WELL.							
Paul Quinones									
63670					9/9/2010		223		\$0.00
Medium	Work In Progress			9/9/2010 8:49:24 AM					
Ontiveros, Joe		WATER FOUNTAIN NEXT TO THE OUTSIDE BASKETBALL COURTS,WATER IS LEAKING UNDER THE WATER FOUNTAIN							
Paul Quinones									
64475					9/28/2010		204		\$0.00
Medium	Work In Progress			9/28/2010 1:06:08 PM					
Flores, Pete		FLOAT SWITCH NOT WORKING PROPERLY REMOVE WIRING SETS OFF NOTIFIER IN MAIN BUILDING,REMOVE WIRING FROM TERMINAL.FUEL TANKS SIGHT GLASS DOESNT SHOW FUEL LEVELS.							
Paul Quinones									
65240					10/11/2010		191		\$0.00
Medium	Work In Progress			10/11/2010 2:33:23 PM					
Lozoya, Manny		REQUESTING BOYS,AND GIRLS SIGNS W/BRAIL FOR REST ROOMS IN B THROUGH G.AND Q,AND R AS WELL. TOTAL BOYS 8 SIGNS,AND 8 GIRLS. COLOR BLUE W/ WHITE LETTERS							
Paul Quinones									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
65356		Athletic Field			10/13/2010		189		\$0.00
High	Work In Progress			10/13/2010 12:56:47					
Ontiveros, Joe	need to run water line to storage.								
<u>Guadalupe Ontiveros</u>									
65357		Athletic Field			10/13/2010		189		\$0.00
Medium	Work In Progress			10/13/2010 1:00:34 PM					
Gonzalez, Salvador	need shade to protect sweeper and tractors from elements.								
<u>Jose Garcia</u>									
66076					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:18					
Orozco, Danny	Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66734					11/16/2010		155		\$0.00
Medium	Work In Progress			11/16/2010 3:53:57 PM					
Ontiveros, Joe	REQUESTING TO CHECK WASHING MACHINE,AND DRYER IN GIRLS LOCKER NORTH IN GYM.								
<u>Paul Quinones</u>									
67067					12/2/2010		139		\$0.00
Medium	Work In Progress			12/2/2010 9:23:29 AM					
Lozoya, Manny	REQUESTING PROTECTIVE LATCHES TO ALL DOORS IN CYBER CAFE,DUE TO VANDILISM IN SCIENCE CLASS RMS. AND COMPUTER LABS.								
<u>Paul Quinones</u>									
67120					12/3/2010		138		\$0.00
Medium	Work In Progress			12/3/2010 8:20:52 AM					
Estrada, Jesus	(PROJECT)	GYM - Need to re-stripe and refinish floor.				Leadership Request			
						Re-routed to J. Estrada on 4/11/11 - mkv			
<u>Paul Quinones</u>									
67835					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:43 AM					
Villalobos, David	Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67968	G-Wing	Gym			1/5/2011		105		\$0.00
Medium	Work In Progress	coach		1/5/2011 11:32:03 AM					
Lozoya, Manny	needs to secure the door in coach "Y" 's office by the boys locker room.								
<u>Rosa Quezada</u>									
4/20/2011 11:58:48 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
68085		Athletic Field			1/7/2011		103		\$0.00
Medium	Work In Progress			1/7/2011 1:20:32 PM					
Aldaz, Bobby	need to fertlize with 16-8-8. football,soccer,baseball,softball,P.E play areas.								
<u>Guadalupe Ontiveros</u>									
68227					1/11/2011		99		\$0.00
Medium	Work In Progress			1/11/2011 10:56:28 AM					
Lozoya, Manny	REQUESTING NEW LOCK FOR DOOR TO CLASS RM. B-6,AND NEW KEY.THANKS								
<u>Paul Quinones</u>									
68449		Gym			1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 2:36:03 PM					
Quinones, Paul	Remove sand buildup at or near entrances		Leadership Request						
<u>Alfredo Holguin</u>									
68529					1/19/2011		30		\$0.00
Medium	Work In Progress			1/19/2011 8:22:07 AM	2/18/2011				
Quinones, Paul	REQUESTING PLEADED AIR FILTERS FOR FIELD HOUSE UNITS 16"X24"								
<u>Paul Quinones</u>									
68636	G-Wing	Classroom			1/21/2011		89		\$0.00
Medium	Work In Progress	G-5		1/21/2011 11:22:50 AM					
Lozoya, Manny	NEED TWO PLATES TO SECURE GAPS IN STORAGE CABINETS IN G-5. (JAYME)								
<u>Rosa Quezada</u>									
68738	R-Wing	Classroom			1/25/2011		85		\$0.00
Medium	Work In Progress	R-4		1/25/2011 12:26:04 PM					
Lozoya, Manny	need a lock installed in bathroom in R-4 (Rueda)								
<u>Rosa Quezada</u>									
68795					1/26/2011		84		\$0.00
Medium	Work In Progress			1/26/2011 1:34:15 PM					
Lozoya, Manny	LOCKS TO CARD BOARD BINS KITCHEN STAFF HAVING A HARD TIME OPENING LOCK W/ KEY.LOCKS ARE BENDED. REQUESTING NEW LOCKS.								
<u>Paul Quinones</u>									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
68796					1/26/2011		84		\$0.00
Medium	Work In Progress			1/26/2011 1:36:35 PM					
Lozoya, Manny	HEAD CUSTODIAN REQUESTING MASTER KEY,KEY BROKE OPENING DOOR IN COURT YARD DOOR								
Paul Quinones									
68797					1/26/2011		84		\$0.00
Medium	Work In Progress			1/26/2011 1:39:53 PM					
Lozoya, Manny	DOOR IN A-WING WILL NOT OPEN W/KEY,REQUESTING NEW CYLINDER.								
Paul Quinones									
68824					1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 9:04:15 AM					
Lozoya, Manny	REQUESTING LOCK TO SECURE ELECTRIC DISCONNECT TO THE FOOTBALL SCORE BOARD.								
Paul Quinones									
69328	F-Wing	Office			2/10/2011		69		\$0.00
Medium	Work In Progress			2/10/2011 10:20:01 AM					
Lozoya, Manny	change lock back to on master instead of M200 (urquidi)								
Rosa Quezada									
69441					2/14/2011		65		\$0.00
Medium	Work In Progress			2/14/2011 10:55:25 AM					
Solis, Lorenzo	REPLACE CHK VALVES TO UNITS IN C D,AND E WINGS,VALVES RUPTURED DURING FREEZE CYBER CAFES								
Paul Quinones									
69563	A-Wing	Office			2/15/2011		64		\$0.00
Medium	Work In Progress	RECEPTIONIST		2/15/2011 4:01:09 PM					
Lozoya, Manny	LOCK FROM THE DESK/CABINET DOESN'T LOCK. MIGHT HAVE TO BE REPLACED (ORTIZ)								
Rosa Quezada									
69898		Football Field			2/24/2011		55		\$0.00
Medium	Work In Progress	softball practice		2/24/2011 2:42:08 PM					
Garcia, Jose	please relocate softball backstop practice field. please contact Ms. Nougues for exact location. (Nougues)								
Rosa Quezada									
69922					2/24/2011		55		\$0.00
Medium	Work In Progress			2/24/2011 4:30:59 PM					
Quinones, Paul	CIELING TILES NEED TO BE REPLACED DUE TO WINTER STORM DAMAGE THROUGH OUT SCHOOL.								
Paul Quinones									
4/20/2011 11:58:48 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
70001					2/28/2011		51		\$0.00
Medium	Work In Progress			2/28/2011 12:40:36 PM					
Quinones, Paul	NEED TO REPLACE CIELING TILES IN CLASS RMS.,AND CYBER CAFES DUE TO WINTER STORM.REQUESTING NEW TILES.								
Paul Quinones									
70038					3/1/2011		50		\$0.00
Medium	Work In Progress			3/1/2011 8:29:16 AM					
Quinones, Paul	ICE MACHINE WATER FILTERS IN FIELD HOUSE CONESSION NEED TO BE REPLACED,FILTERS RUPTURED DURING FREEZE REQUESTING 4 FILTERS								
Paul Quinones									
70108					3/2/2011		49		\$0.00
Medium	Work In Progress			3/2/2011 3:38:47 PM					
Carrasco, Danny	requesting 15 gal.of gasoline for work truck #139								
Paul Quinones									
70113					3/2/2011		49		\$0.00
Medium	Work In Progress			3/2/2011 3:59:01 PM					
Lozoya, Manny	DOOR TO MECH. RM.KEY WILL NOT OPEN DOOR,REQUESTING TO REPLACE KEY CYLINDER.MUCHOS GRACIAS.								
Paul Quinones									
70144					3/3/2011		48		\$0.00
Medium	Work In Progress			3/3/2011 11:00:08 AM					
Quinones, Paul	NEED TO PAINT DOUBLE DOORS TO BOTH ENTRANCES IN GYM NEXT TO CAFETERIA.REQUESTING 2 GAL.OF PAINT								
Paul Quinones									
70185					3/4/2011		47		\$0.00
Medium	Work In Progress			3/4/2011 10:23:29 AM					
Lozoya, Manny	EXIT DOOR IN B-SPED.TEACHER REQUESTING DOOR HANDLE FROM THE INSIDE.DOOR HARD TO CLOSE,AND LOCK. THANKS.								
Paul Quinones									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
70253					3/6/2011		45		\$0.00
Medium	Work In Progress				3/6/2011 12:17:45 AM				
Orozco, Danny	Yearly - Chaparral HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
70415					3/7/2011		44		\$0.00
Medium	Work In Progress				3/7/2011 2:51:01 PM				
Quinones, Paul	ELECTRIC FIRE PUMP CONTROLLER,ELECTRICAL FROM INSIDE ELECTRICAL PANEL SHORTED OUT. PACKING GLANDS LEAKING TO PUMP.DUE TO SPRINKLER LEAK FROM INSIDE								
Paul Quinones									
70416					3/7/2011		44		\$0.00
Medium	Work In Progress				3/7/2011 2:55:03 PM				
Quinones, Paul	DIESEL FIRE PUMP STATION LEAKING WATER FROM PACKING GLAND NEED TO REPLACE.								
Paul Quinones									
70480					3/9/2011		42		\$0.00
Medium	Work In Progress				3/9/2011 8:07:26 AM				
Solis, Lorenzo	GEO THERMAL PUMP LEAKING FROM SEAL,NEED TO BE REPLACED.MECH.RM. NEXT TO KITCHEN								
Paul Quinones									
70507	E-Wing	Classroom			3/9/2011		42		\$0.00
Medium	Work In Progress	e-4			3/9/2011 12:16:39 PM				
Lozoya, Manny	lock on fle cabinet doesn't work. (godin)								
Rosa Quezada									
70574					3/10/2011		41		\$0.00
Medium	Work In Progress				3/10/2011 8:20:26 AM				
Ontiveros, Joe	D-WING SCIENCE CLASS RM. DUE TO WINTER STORM FREEZE,WE NEED TO FIND WATER LEAKS BEHIND TABLES,AND LAVATORY COUNTER TOPS WILL TAKE LONGER THAN OTHER CLASS RMS..								
Paul Quinones									
70575					3/10/2011		41		\$0.00
Medium	Work In Progress				3/10/2011 8:22:19 AM				
Ontiveros, Joe	E-WING SCIENCE CLASS RM. NEED TO FIND WATER LEEAKS BEHIND WALLS.DUE TO FREEZE								
Paul Quinones									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
70659					3/11/2011		40		\$0.00
Medium	Work In Progress			3/11/2011 8:28:30 AM					
Ontiveros, Joe	SHOWER STALL IN BOYS FOOTBALL LOCKER FIELD HOUSE LEAKING WATER								
Paul Quinones									
70682					3/11/2011		40		\$0.00
Medium	Work In Progress			3/11/2011 3:33:19 PM					
Lozoya, Manny	CONSESSION DOOR IN THE FIELD HOUSE CORE FELL FROM DOOR.								
Paul Quinones									
70746					3/14/2011		37		\$0.00
Medium	Work In Progress			3/14/2011 3:34:13 PM					
Lozoya, Manny	NEED NEW LOCK BEHIND CARPENTRY SHOP TO SECURE COMPRESSOR INSIDE FENCE LINE.FOR INSTRUCTERS								
Paul Quinones									
70761					3/14/2011		37		\$0.00
Medium	Work In Progress			3/14/2011 4:31:56 PM					
Ontiveros, Joe	NO HOT WATER IN F-WING BAD IGNITOR								
Paul Quinones									
70813					3/16/2011		35		\$0.00
Medium	Work In Progress			3/16/2011 9:32:45 AM					
Quinones, Paul	NEED TO REPLACE ALL BROKEN T-STAT COVERS IN ALL AREAS,REQUESTING 24.								
Paul Quinones									
70833		Computer Lab			3/16/2011		35		\$0.00
Medium	Work In Progress	COMPUTER		3/16/2011 2:38:23 PM					
Lozoya, Manny	INSTALL DOOR GUARDS TO PREVENT STUDENTS FROM OPENING LOCKED DOORS TO ALL COMPUTER LABS IN EACH WING								
Rosa Quezada									
70858					3/17/2011		34		\$0.00
Medium	Work In Progress			3/17/2011 9:00:34 AM					
Gonzalez, Salvador	FENCE CHAIN LINK TYPE NEEDS TO BE REPLACED W/POLE AND POLE ALONG PRESSCOTT ANTHONY								
Paul Quinones									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
70876					3/17/2011		34		\$0.00
Medium	Work In Progress			3/17/2011 1:23:05 PM					
Castillo, Carlos		REINSTALL LIGHTING IN GIRLS REST RM.							
Paul Quinones									
70878	Field House	Athletic Field			3/17/2011		34		\$0.00
Medium	Work In Progress			3/17/2011 2:32:11 PM					
Quinones, Paul		the tape and texture has been completed. please paint. thank you							
Michael Munoz									
70909					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 9:17:05 AM					
Solis, Lorenzo		GYM A/C'S I NEED SOME SHEETMETAL, MEASUREMENTS ARE 30"X94'1/2".24 GAUGE.							
Paul Quinones									
70968					3/20/2011		31		\$0.00
Medium	Work In Progress			3/20/2011 12:12:34 AM					
Ontiveros, Guadalupe		Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.							
Margret Villalobos									
71020					3/23/2011		28		\$0.00
Medium	Work In Progress			3/23/2011 10:39:40 AM					
Ontiveros, Joe		GIRLS, AND BOYS REST RM. TOILETS NEED TO BE REPLACED TOILETS ARE CRACKED DUE TO WINTER FREEZE. IN THE NORTH END FIELD HOUSE							
Paul Quinones									
71291					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 12:17:36 AM					
Quinones, Paul		Monthly - Chaparral HS A16 (Fan Exhst.)(S. Annual) - Refer to PM schedule details.							
Margret Villalobos									
71393					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:32 AM					
Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									
71447					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:59 AM					
Orozco, Danny		Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
4/20/2011 11:58:48 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
71541					4/3/2011	4/6/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:40 AM					
Quinones, Paul	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
71542					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:41 AM					
Quinones, Paul	Monthly - Chaparral HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
71543					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:41 AM					
Quinones, Paul	Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
71544					4/3/2011	5/4/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:41 AM					
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
71545					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:42 AM					
Quinones, Paul	Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
71546					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:42 AM					
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
71547					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:43 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
71548					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:43 AM					
Quinones, Paul	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
71604					4/4/2011		16		\$0.00
Medium	Work In Progress			4/4/2011 11:22:39 AM					
Lozoya, Manny	DOOR IN BAND RM. DOESNT CLOSE WITH KEY, DOOR IS ALSO NOT ALIGNED WITH DOOR FRAME. DOOR WAS OPENED FORCED OPEN WITH HIGH WINDS.								
Paul Quinones									
71718		Classroom			4/6/2011		14		\$0.00
Medium	Work In Progress	q-3		4/6/2011 12:39:03 PM					
Quinones, Paul	install ceiling mounted projector. need installed by april 14, 2011. see Ms. Duran-Campbell before installing..								
Rosa Quezada									
71854					4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 3:32:39 PM					
Lozoya, Manny	DOUBLE DOORS NEXT TO CAFETERIA DOORS ARE HARD TO OPEN W/ KEY								
Paul Quinones									
71909					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:38 AM					
Urquidi, Jesus	Monthly - QRTLTY BLDG INSP REPORT (CH) - Refer to PM schedule details.								
Jesus Estrada									
71948					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 11:01:54 AM					
Quinones, Paul	Remove leak stains on inside walls throughout building. (Need to complete within 30 days)				Leadership Request				
Alfredo Holguin									
71960					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 12:06:35 PM					
Ontiveros, Joe	C-WING HOT WATER HEATER PUMP LEAKING WATER NEED TO REPLACE. CIRCULATING PUMP								
Paul Quinones									
71961					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 12:08:04 PM					
Ontiveros, Joe	B-WING TOILETS CLOGGED GIRLS REST RM.								
Paul Quinones									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Chaparral HS</b>								
72047		Classroom			4/13/2011		7		\$0.00	
Medium	Work In Progress	book room by		4/13/2011 12:40:47 PM						
Lozoya, Manny		NEED TO REKEY TO GM3 THE MAIN ENTRANCE TO THE BOOK ROOM BY THE CAFETERIA A.S.A.P. (NOUGUES)								
Rosa Quezada										
72049		Custodial			4/13/2011		7		\$0.00	
High	Work In Progress			4/13/2011 12:54:30 PM						
Urquidi, Jesus		Custodian have to stop using pipe chases and electrical rooms as custodial closets. There should be no paper products or chemicals in the pipe chases. Check all pipe chases and electrical rooms.								
Jesus Estrada										
72050		Restroom (Boys)			4/13/2011		7		\$0.00	
Medium	Work In Progress			4/13/2011 12:57:11 PM						
Urquidi, Jesus		All urinals need to have a deodorant screen. Some of the screens need to be refilled with a new block.								
Jesus Estrada										
72101	Q-Wing	Classroom			4/14/2011		6		\$0.00	
Medium	Work In Progress	Q-4		4/14/2011 2:48:58 PM						
Lozoya, Manny		need to re-key welding room in q-4 (nougues)								
Rosa Quezada										
72277					4/20/2011		0		\$0.00	
Medium	Work In Progress			4/20/2011 7:51:11 AM						
Briones, Enrique		On April 20, 2011, please deliver 4 boxes to Chaparral High School. Reference P.O. # 101107270.								
Yolie Jacquez										
72289		Athletic Field			4/20/2011		0		\$0.00	
Medium	Work In Progress			4/20/2011 8:31:44 AM						
Sotelo, Enrique		need to run electric line to grounds storage from lift station about 300'								
Guadalupe Ontiveros										
<b>Count: 78 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>65</b>		<b>Total for Chaparral HS</b>		<b>0</b>		<b>\$0.00</b>



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
60599					7/4/2010	7/25/2010	290		\$0.00
Medium	Work In Progress			7/4/2010 12:23:43 AM					
Orozco, Danny		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
62838					8/24/2010		239		\$0.00
Medium	Work In Progress			8/24/2010 9:45:04 AM					
Vallejo, Albert		Need to reinforce shelves in book room							
Albert Vallejo									
64740					10/3/2010	10/24/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:59 AM					
Orozco, Danny		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
65077		Dressing Room			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 9:28:04 AM					
Ontiveros, Joe		Motion activated sink in girls P.E. locker room has two broken solenoids which need to be replaced.							
Albert Vallejo									
65458		Cafeteria			10/15/2010		187		\$0.00
Medium	Work In Progress			10/15/2010 8:50:44 AM					
Vallejo, Albert		ENVIRONMENT DEPT. INSPECTION: 1- LOW RISK VIOLATION: MISSING 1 BROKEN FLOOR TILE UNDER THE DISH SINK. STATE INSPECTOR - SANDRA DIAZ SNP MGR 824-4376				Asp Mike, route to A. Vallejo - D. Orozco 1/26/11			
Jacqueline Aguilar									
66083					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:21					
Orozco, Danny		Monthly - Chaparral MS Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
66176					10/31/2010		171		\$0.00
Medium	Work In Progress			10/31/2010 12:37:05					
Sanchez, Raul		Monthly - Chaparral MS - DP-781 - Refer to PM schedule details.							
Margret Villalobos									
67347	Phase II New	Hallway/Corridor			12/7/2010		134		\$0.00
Medium	Work In Progress			12/7/2010 8:02:33 AM					
Ronquillo, Ruben		Need to replace transom glass above door in main hallway. 24" x 60" x 1/4" wired glass.							
Albert Vallejo									
4/20/2011 11:58:48 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
67542					12/13/2010		128		\$0.00
Medium	Work In Progress			12/13/2010 9:02:23 AM					
Vallejo, Albert		Need to install Handrail in restroom between I.S.S. room and room #107.							
Albert Vallejo									
67818					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:37 AM					
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
67837					1/2/2011	1/23/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:44 AM					
Orozco, Danny		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
67969					1/5/2011		105		\$0.00
Medium	Work In Progress			1/5/2011 2:30:29 PM					
Vallejo, Albert		Repair front entrance canopy up-lighting fixtures							
Albert Vallejo									
68086		Athletic Field			1/7/2011		103		\$0.00
Medium	Work In Progress			1/7/2011 1:49:10 PM					
Aldaz, Bobby		Football and soccer field need to be fertilize with 16-8-8.							
Guadalupe Ontiveros									
68337		Classroom			1/13/2011		97		\$0.00
High	Work In Progress	ROOM 308		1/13/2011 10:16:15 AM					
Lozoya, Manny		COMPUTER LAB DOOR IS NOT LOCKING THERE ARE A LOT OF COMPUTERS AND SOFTWARE EXPOSED							
Elena Palacios									
68442					1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 2:21:27 PM					
Ontiveros, Joe		Install refrigerated water fountains on exterior of building south side facing playfields				Leadership Request			
Alfredo Holguin									
68446					1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 2:30:03 PM					
Vallejo, Albert		(PROJECT) Both courtyards - remove all trash and relevel area. Install raised planters (Vado Elem) and cover other areas with crusher fines.				Leadership Request			
Alfredo Holguin									
4/20/2011 11:58:48 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
68581		Office			1/19/2011		91		\$0.00
Medium	Work In Progress	CONCESSION		1/19/2011 3:53:51 PM					
Lozoya, Manny		WE NEED AN EXTRA KEY (A82) FOR THE CONCESSION STAND							
Elena Palacios									
69104					2/6/2011		73		\$0.00
Medium	Work In Progress			2/6/2011 12:34:07 AM					
Sanchez, Raul		Monthly - Chaparral MS - DP-781 - Refer to PM schedule details.							
Margret Villalobos									
69207					2/8/2011		71		\$0.00
Medium	Work In Progress			2/8/2011 12:43:29 PM					
Orozco, Danny		BOTH PASS THROUGH WARMERS ARE NOT WORKING, PLEASE CHECK. SNP MANAGER SANDRA D. 824-4376.							
Maritza Gonzalez									
69252					2/9/2011		70		\$0.00
Medium	Work In Progress			2/9/2011 8:59:08 AM					
Orozco, Danny		I will need the bucket truck to obtain specifics of pole lighting for donated fixture.							
Albert Vallejo									
69763					2/22/2011		57		\$0.00
Medium	Work In Progress			2/22/2011 12:46:02 PM					
Orozco, Danny		WASHER NOT DRAINING ALL WATER DRYER NOT DRYING.(TOWELS HAVE BEEN IN THERE FROM 6:30 -12:38 AND STILL NOT DRY) THANK YOU SNP MANAGER SANDRA D. 824.4376.							
Maritza Gonzalez									
69813					2/23/2011		56		\$0.00
Medium	Work In Progress			2/23/2011 9:20:27 AM					
Ontiveros, Joe		Automatic lavatory faucets throughout campus need to be replaced or repaired.							
Albert Vallejo									
70252					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:44 AM					
Orozco, Danny		Yearly - Chaparral MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
70271					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:54 AM					
Medina, Eric		Yearly - Chaparral MS A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
70908	Main Building	Office			3/18/2011		33		\$0.00
Medium	Work In Progress	OFFICE		3/18/2011 9:12:35 AM					
Lozoya, Manny		MENS RESTROOM DOOR IS DIFFICULT TO OPEN TUMBLER NOT WORKING							
<u>Elena Palacios</u>									
70912	Phase III New	Classroom			3/18/2011		33		\$0.00
Medium	Work In Progress	ROOM 450		3/18/2011 9:30:23 AM					
Lozoya, Manny		HANDICAP DOOR IS STUCK OPEN WILL NOT CLOSE							
<u>Elena Palacios</u>									
71260	Main Building	Mechanical			3/30/2011		21		\$0.00
Medium	Work In Progress			3/30/2011 3:24:20 PM					
Ontiveros, Joe		Fire sprinkler pump system needs to be checked. Main pump periodically comes on before the jockey pump, setting off the alarm.							
<u>Albert Vallejo</u>									
71275					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 12:17:27 AM					
Vallejo, Albert		Monthly - Chaparral MS A16 (Fan Exh.)(S. Annual) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
71396					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:34 AM					
Vallejo, Albert		Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
71397					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:34 AM					
Vallejo, Albert		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
71398					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:35 AM					
Vallejo, Albert		Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
71423					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:48 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71431					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:52 AM					
Orozco, Danny	Monthly - Chapparal MS Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71461					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:06 AM					
Vallejo, Albert	Yearly - Chaparral MS A13(AC Wall)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71462					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:06 AM					
Vallejo, Albert	Monthly - Chaparral MS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71641					4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 9:07:59 AM					
Ontiveros, Joe	Please remove non-functioning solenoid valves and install ball valves so that trees can be irrigated properly.								
<u>Albert Vallejo</u>									
71672					4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 3:22:29 PM					
Orozco, Danny	SEVERAL TILES MISSING IN KITCHEN AREA. SNP MANAGER SANDRA D. 824-4376								
<u>Maria Gonzalez</u>									
71817	Main Building	Library			4/8/2011		12		\$0.00
Medium	Work In Progress	LIBRARY		4/8/2011 9:08:07 AM					
Martinez, Larry	PLEASE PICK UP 16 LIBRARY EQUIPMENT ITEMS THAT ARE NO LONGER WORKING								
<u>Elena Palacios</u>									
71911					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:39 AM					
Gonzalez, Robert	Monthly - QRTLY BLDG INSP REPORTS (CM) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
71949					4/11/2011		9		\$0.00
Medium	Work In Progress	Leadership		4/11/2011 11:06:11 AM					
Ontiveros, Joe		Soutside of Bldg (west) need to repair exterior water fountain - pipe base is leaning. (Needs to be complete within 30 days)				Leadership Request			
<u>Alfredo Holguin</u>									
71968	Phase III New	Electrical Room			4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 3:07:26 PM					
Vallejo, Albert		Repair or replace exterior lighting timer for west side lights.							
<u>Albert Vallejo</u>									
72098	Main Building	Hallway/Corridor			4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 2:42:13 PM					
Ronquillo, Ruben		Please repair glass on display case. Administration requests tempered glass. The panel that broke was not tempered and jagged pieces of glass pose a risk to students.							
<u>Albert Vallejo</u>									
72099					4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 2:44:20 PM					
Ronquillo, Ruben		Replace door side-light on ADA ramp behind stage. Approximately 2'x 3' x 1/4" wired glass.							
<u>Albert Vallejo</u>									
72132	Main Building				4/15/2011		5		\$0.00
Medium	Work In Progress			4/15/2011 9:12:06 AM					
Lozoya, Manny		Please repair or replace door handle in room #402							
<u>Albert Vallejo</u>									
72236		Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress	ROOM 310		4/19/2011 1:01:17 PM					
Lozoya, Manny		RICKY CHAVEZ - KEY IS GETTING STUCK IN DOOR WAS AN EMERGENCY HAZARD DURING A FIRE DRILL							
<u>Elena Palacios</u>									
<b>Count: 45 Work Orders</b>		<b>Avg. Age of WO's 72</b>			<b>Total for Chaparral MS</b>			<b>0</b>	<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Pride</b>							
65860		Office			10/26/2010		176		\$0.00
Medium	Work In Progress			10/26/2010 10:28:42					
Lara, Ralph	NEED TO REPLACE TO OLD DOORS FOR ADMINIST. ASSIST. AND TO COUNSELOR OFFICE.								
<u>David Acosta</u>									
67264					12/5/2010		136		\$0.00
Medium	Work In Progress			12/5/2010 12:27:27 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68420		Portables			1/14/2011		96		\$0.00
Medium	Work In Progress	BOXING		1/14/2011 9:24:06 AM					
Ronquillo, Ruben	NEED 23'X23' WEATHER PROOF CANVAS TO COVER BOXING RING.								
<u>David Acosta</u>									
68494		Library			1/18/2011		92		\$0.00
Medium	Work In Progress	READING/LAD		1/18/2011 1:09:34 PM					
Castillo, Carlos	EMER. LIGHT NOT WORKING								
<u>David Acosta</u>									
69526		Portables			2/15/2011		64		\$0.00
Medium	Work In Progress	BOXING		2/15/2011 12:10:20 PM					
Munoz, Michael	NEED TO PUT UP FENCE ALONG THE EDGE AND END OF SIDE WALK AND RUN IT TO FENCE LINE TO SECURE BOXING RING REQUESTED BY BOXING COACH.								
<u>David Acosta</u>									
70255					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:46 AM					
Orozco, Danny	Yearly - Desert Pride HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70599		Classroom			3/10/2011		41		\$0.00
Medium	Work In Progress	BOXING		3/10/2011 11:30:00 AM					
Carrasco, Danny	TEACHER MR. FERNANDEZ STATES THAT MAINTENANCE ON THE TREADMILLS FOR THE BOXING CLASS NEEDS TO BE TAKEN CARE OF BY WESTSIDE FITNESS.								
Mary Telles									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Pride</b>							
71245		Parking Lot			3/30/2011		21		\$0.00
Medium	Work In Progress	BUS		3/30/2011 12:04:08 PM					
Ontiveros, Guadalupe		NEED TO LEVEL UNEVEN GROUND AT BUS ENTRANCE AND FRONT ENTRANCE.							
David Acosta									
71289					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 12:17:35 AM					
Aguilar, Patricio		Monthly - Desert Pride HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
71413					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:43 AM					
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
71414					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:44 AM					
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
71415					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:44 AM					
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
71536					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:38 AM					
Aguilar, Patricio		Monthly - Desert Pride HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
71538					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:39 AM					
Aguilar, Patricio		Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
71561					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:48 AM					
Sanchez, Raul		Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Pride</b>							
71872					4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 4:16:26 PM					
Ronquillo, Ruben	Leadership Request Boxing (some) treadmills don't work. Needs to be completed within 30 days.		Leadership Request						
Richard Chavez									
71882					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:24 AM					
Acosta, David	Monthly - QRTL BLDG INSP REPORT (DP) - Refer to PM schedule details.								
Jesus Estrada									
72092		Portables			4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 11:48:12 AM					
Castillo, Carlos	NEED TO CHECK NIGHT LIGHTS ON ALL PORTABLES AND BLDG.								
David Acosta									
72160					4/18/2011		2		\$0.00
Safety	Work In Progress			4/18/2011 7:54:34 AM					
Miranda, Danny	PLASTER IS FALLING ON DROP CEILING AND HAS COLLAPSE IN MAIN BUILDING (SAFETY ISSUE)								
Mary Telles									
72266					4/19/2011		1		\$0.00
Medium	Work In Progress			4/19/2011 3:57:08 PM					
Appelzoller, Fred	Nurse Office - Toilet is not working properly, needs a handle								
Margret Villalobos									
<b>Count: 20 Work Orders</b>		<b>Avg. Age of WO's 41</b>			<b>Total for Desert Pride</b>			<b>0</b>	<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
60600					7/4/2010	7/25/2010	290		\$0.00
Medium	Work In Progress			7/4/2010 12:23:43 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
63218					8/31/2010		232		\$0.00
Medium	Work In Progress			8/31/2010 12:25:01 AM					
Sanchez, Raul	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.								
Margret Villalobos									
63407					9/3/2010		229		\$0.00
Medium	Work In Progress			9/3/2010 2:30:57 PM					
Flores, Pete	Please check red stiner tractor and deliver to Desert Trail to be used with only the front bucket. Thanks								
Johnny Acuna									
64741					10/3/2010	10/24/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:59 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
65716		Cafeteria			10/21/2010		181		\$0.00
Medium	Work In Progress			10/21/2010 9:38:23 AM					
Orozco, Danny	FRONT SLIDING DOOR IS HARD TO OPEN AND CLOSE.								
PAT CISNEROS SNP MGR 824-3822									
Jacqueline Aguilar									
66084					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:21					
Orozco, Danny	Monthly - Desert Trail Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
66173					10/31/2010		171		\$0.00
Medium	Work In Progress			10/31/2010 12:37:03					
Sanchez, Raul	Monthly - Desert Trail - Refer to PM schedule details.								
Margret Villalobos									
66228					11/2/2010		169		\$0.00
Medium	Work In Progress			11/2/2010 12:22:21 AM					
Sanchez, Raul	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.								
Margret Villalobos									
4/20/2011 11:58:48 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
67819					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:37 AM					
Villalobos, David	Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
67838					1/2/2011	1/23/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:44 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
67872					1/2/2011	1/10/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:29:03 AM					
Acuna, Johnny	Monthly - Desert Trail Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
67957					1/4/2011		106		\$0.00
Medium	Work In Progress			1/4/2011 12:24:41 AM					
Sanchez, Raul	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.								
Margret Villalobos									
68325					1/12/2011		98		\$0.00
Medium	Work In Progress			1/12/2011 3:54:50 PM					
Lozoya, Manny	Need (2) locks for new gates installed. *New Double gates between Ch. Elem. / Desert Trail *New Double gates in Bus Turnaround area. (Ponding Area)								
Johnny Acuna									
68623					1/21/2011		89		\$0.00
Medium	Work In Progress			1/21/2011 8:03:36 AM					
Solis, Lorenzo	Need parts for heating system pump in the mechanical room.								
Johnny Acuna									
68914					1/31/2011		79		\$0.00
Medium	Work In Progress			1/31/2011 7:32:37 AM					
Lozoya, Manny	EMERGENCY WORK ORDER: Doorknob lock does not open to Library door. Have also tried the GM key. Need to open A/S/A/P for classes this morning.								
Johnny Acuna									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
69415					2/13/2011	3/1/2011	66		\$0.00
Medium	Work In Progress			2/13/2011 12:23:12 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69986					2/28/2011		51		\$0.00
Medium	Work In Progress			2/28/2011 9:55:12 AM					
Sanchez, Raul	Need a replacement broken pump for the one next to the working one inside the sewer tank, and need to fix or replace check valve: Sewage water keeps backing up from the other tank through the pump.								
<u>Johnny Acuna</u>									
70024					3/1/2011		50		\$0.00
Medium	Work In Progress			3/1/2011 12:18:22 AM					
Sanchez, Raul	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70239					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:38 AM					
Orozco, Danny	Yearly - Desert Trail ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70297					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:18:07 AM					
Acuna, Johnny	Yearly - Desert Trail ES A10 (Heat Pump)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70563					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 5:35:50 PM					
Gonzalez, Salvador	Need 2 posts and chain installed for parking lot area entry to front of Main Building.								
<u>Johnny Acuna</u>									
70606					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 2:21:27 PM					
Ontiveros, Joe	Two backflow preventers inside mechanical room are leaking(Domestic). One backflow preventer from heating system is leaking (Mechanical Room).								
<u>Johnny Acuna</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
70705					3/13/2011	3/29/2011	38		\$0.00
Medium	Work In Progress			3/13/2011 12:13:04 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
71281					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 12:17:30 AM					
Acuna, Johnny	Monthly - Desert Trail ES A16(Exhst Fan)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
71424					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:48 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
71432					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:52 AM					
Orozco, Danny	Monthly - Desert Trail Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71486					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:17 AM					
Acuna, Johnny	Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
71487					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:17 AM					
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
71488					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:18 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
71489					4/3/2011	4/19/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:18 AM					
Acuna, Johnny	Monthly - Desert Trail ES A1 (Air Dryer)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
71490					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:18 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71491					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:19 AM					
Acuna, Johnny	Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71895					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:30 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71902					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:34 AM					
Sandoval, Laura	Monthly - QRTLY BLDG INSP REPORTS (DT) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
72003					4/12/2011		8		\$0.00
Medium	Work In Progress			4/12/2011 12:46:47 PM					
Lozoya, Manny	Computer Room: South Door. Doorknob is not working properly. Doorknob lever through the inside stays down not allowing the door to close properly. Please fix or replace. Thank You.....								
<u>Johnny Acuna</u>									
72006					4/12/2011		8		\$0.00
Medium	Work In Progress			4/12/2011 1:23:24 PM					
Estrada, Jesus	Warranty WorkOrder: (Chuy Estrada) Some pieces of newly installed Baseboard on wall to the cafeteria has fallen off wall. (W.O. 69129) (Stage Ramp Area)					FAXED TO RODRIGUEZ 3/13/11. 4/17/11 - ASP EVA, BASEBOARD HAS BEEN REPAIRED			
<u>Johnny Acuna</u>									
72028					4/12/2011		8		\$0.00
Medium	Work In Progress			4/12/2011 3:59:30 PM					
Orozco, Danny	sink faucets and sliding door are loose. snp manager Pat C. 824.3822								
Maritza Gonzalez									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
72034					4/13/2011		7		\$0.00
Medium	Work In Progress			4/13/2011 8:29:17 AM					
Carrasco, Danny	(Danny Carrasco) Need scissor lift for use in painting cafeteria upper part of walls. (Needed for June 2, 2011)								
<u>Johnny Acuna</u>									
72091					4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 11:16:13 AM					
Ontiveros, Joe	water backing up in laundry room when washing machine drains water. Also, need a 2 1/2" brass cap for cleanout.								
<u>Johnny Acuna</u>									
72169					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 10:23:29 AM					
Lozoya, Manny	Need to remove stuck key in storage shed lock.								
<u>Johnny Acuna</u>									
72175					4/18/2011		2		\$0.00
Medium	Work In Progress	402		4/18/2011 12:27:05 PM					
Lozoya, Manny	Mrs. Poet in room #402 door handle came off.								
<u>Elizabeth Hernandez</u>									
72194					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 3:51:51 PM					
Lozoya, Manny	Portable #402: Need to check doorknob, Handle when opened through the inside comes off the door. Have tried to lock it in place, but still comes off.								
<u>Johnny Acuna</u>									
72202					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 4:40:47 PM					
Orozco, Danny	one of the hose from the washer is throwing water it has a small hole. thank you snp manager Pat C. 824.3822.								
<u>Maritza Gonzalez</u>									
72210	Main Building	Mechanical			4/19/2011		1		\$0.00
Medium	Work In Progress			4/19/2011 7:35:27 AM					
Gonzalez, Salvador	please cut and weld fitting flange for hydronic system piping. thanxs.								
<u>Lorenzo Solis</u>									
72223					4/19/2011		1		\$0.00
Medium	Work In Progress			4/19/2011 10:05:03 AM					
Lozoya, Manny	Need 2 keys made for a storage unit.								
<u>Johnny Acuna</u>									
4/20/2011 11:58:48 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail Intermediate

Count: 45 Work Orders      Avg. Age of WO's 65      Total for Desert Trail Intermediate      0      \$0.00



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
61164					7/20/2010		274		\$0.00
Medium	Work In Progress				7/20/2010 3:53:44 PM				
Ortiz, Ruben	Asp PSFA - Replace or fill red clay pavers on sidewalk. This is a trip hazard.								
<u>Michael Munoz</u>									
61509		Cafeteria			7/29/2010		265		\$0.00
Medium	Work In Progress				7/29/2010 2:48:16 PM				
Moncayo, Fernando	BATHROOM SINK IS LEAKING ALOT OF WATER. (WATER FORMING UNDER SINK).								
	DIANNE L. SNP MGR 580-2425								
<u>Jacqueline Aguilar</u>									
62214					8/10/2010		253		\$0.00
Medium	Work In Progress				8/10/2010 8:51:23 AM				
Orozco, Danny	NEED TO HAVE FIRE EXTINGUISHERS SERVICED AS PER YEARLY INSPECTION								
<u>Danny Orozco</u>									
62218					8/10/2010		253		\$0.00
Safety	Work In Progress				8/10/2010 8:55:30 AM				
Ortiz, Ruben	Check all wall cabinets throughout your site and make sure they are secure to wall and remind teachers not to overload with books. If you should have any questions, call Alfredo or Mike.								
<u>Alfredo Holguin</u>									
63208					8/30/2010		1		\$0.00
Medium	Work In Progress				8/30/2010 5:19:53 PM	8/31/2010			
Ortiz, Ruben	Bathroom doors needs new hinges replaced								
<u>Ruben Ortiz</u>									
66085					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress				10/31/2010 12:36:22				
Orozco, Danny	Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66790					11/17/2010		154		\$0.00
Medium	Work In Progress				11/17/2010 8:03:48 PM				
Lara, Ralph	Requesting two dead bolt locks for portable 6 room A & B. Thank you, Ruben								
Ruben Ortiz									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Desert View ES</b>									
66792					11/17/2010		154		\$0.00
Medium	Work In Progress			11/17/2010 8:33:41 PM					
Ortiz, Ruben	Requesting 6 window screens 20x21 to be replaced due to the vandalism. Thank you, Ruben								
<u>Ruben Ortiz</u>									
67014	Main Building	Classroom			12/1/2010		140		\$0.00
Medium	Work In Progress			12/1/2010 10:54:03 AM					
Lara, Ralph	Keys are not opening the door to room 22 storage on the west and need key replace. Thank you Ruben								
<u>Ruben Ortiz</u>									
67381					12/7/2010		134		\$0.00
Medium	Work In Progress			12/7/2010 9:08:28 PM					
Lara, Ralph	Assistant Principal would like all the deadbolts in the portables worked on, in case of a lock down. Thank you, Ruben								
<u>Ruben Ortiz</u>									
67527					12/12/2010	12/28/2010	129		\$0.00
Medium	Work In Progress			12/12/2010 12:25:24					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67563		Athletic Field			12/13/2010		128		\$0.00
Medium	Work In Progress			12/13/2010 3:13:46 PM					
Ortiz, Ruben	Remove graffiti from playgrounds								
<u>Ruben Ortiz</u>									
67649					12/15/2010		126		\$0.00
Medium	Work In Progress			12/15/2010 11:10:42					
Estrada, Jesus	NEED CARPET REPLACE IN PORTABLE 6. PLEASE QUOTE					w.o. # 72170 submitted to have door shaved down.			
<u>Jesus Estrada</u>									
67820					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:38 AM					
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67962	Main Building	Custodial			1/5/2011		105		\$0.00
Medium	Work In Progress			1/5/2011 8:21:11 AM					
Villalobos, David	East side Custodial room water heater has to be replace. Thank you Ruben								
<u>Ruben Ortiz</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
69823					2/23/2011		56		\$0.00
Medium	Work In Progress			2/23/2011 11:03:40 AM					
Ortiz, Ruben	Broken chain on the flag pole, needs to be replaced. Thank you, Ruben								
Ruben Ortiz									
70240					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:38 AM					
Orozco, Danny	Yearly - Desert View ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
70495					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 11:46:55 AM					
Ambriz, Jose	Rm 27 MCD 004 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70497					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 11:48:40 AM					
Ambriz, Jose	Rm 29 MCD 003 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70498					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 11:50:24 AM					
Ambriz, Jose	Rm 31 MCD 002 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70499					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 11:52:19 AM					
Ambriz, Jose	Rm 33 MCD 001 Size 43; need 1 cover and 1 base								
Ruben Ortiz									
70500					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 11:54:06 AM					
Ambriz, Jose	Rm 24 MCD 005 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70501					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 11:55:48 AM					
Ambriz, Jose	Rm 26 MCD 006 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70502					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 11:57:18 AM					
Ambriz, Jose	Rm 28 MCD 007 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
4/20/2011 11:58:48 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
70503					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:07:34 PM					
Ambriz, Jose	Rm 30 MCD 008 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70508					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:21:02 PM					
Ambriz, Jose	Rm 35 MCD 009 Size 43; need 1 cover and 1 base								
Ruben Ortiz									
70510					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:22:24 PM					
Ambriz, Jose	Rm 37 MCD 010 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70511					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:25:25 PM					
Ambriz, Jose	Rm 39 MCD 011 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70512					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:28:21 PM					
Ambriz, Jose	Rm 41 MCD 012 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70513					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:29:46 PM					
Ambriz, Jose	Rm 32 MCD 015 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70514					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:31:14 PM					
Ambriz, Jose	Rm 34 MCD 014 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70515					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:32:39 PM					
Ambriz, Jose	Rm 36 MCD 013 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70516					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:34:13 PM					
Ambriz, Jose	Rm 10 MCD 021 Size 68; need 1 cover and 1 base								
Ruben Ortiz									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
70517					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:35:58 PM					
Ambriz, Jose	Rm 12 MCD 022 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70518					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:37:14 PM					
Ambriz, Jose	Rm 14 MCD 023 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70519					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:38:49 PM					
Ambriz, Jose	Rm 16 MCD 024 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70520					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:40:09 PM					
Ambriz, Jose	Rm 11 MCD 020 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70521					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:41:37 PM					
Ambriz, Jose	Rm 13 MCD 019 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70522					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:43:13 PM					
Ambriz, Jose	Rm 15A MCD 018 Size 43; need 1 cover and 1 base								
Ruben Ortiz									
70523					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:45:31 PM					
Ambriz, Jose	Rm 15B MCD 017 Size 43; need 1 cover and 1 base								
Ruben Ortiz									
70524					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:46:57 PM					
Ambriz, Jose	Rm 17 MCD 016 Size 43; need 1 cover and 1 base								
Ruben Ortiz									
70525					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:48:14 PM					
Ambriz, Jose	Rm 18 MCD 032 Size 68; need 1 cover and 1 base								
Ruben Ortiz									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
70526					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:49:30 PM					
Ambriz, Jose	Rm 20 MCD 031 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70527					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:50:48 PM					
Ambriz, Jose	Rm 22 MCD 030 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70528					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:52:14 PM					
Ambriz, Jose	Rm 19 MCD 029 Size 43; need 1 cover and 1 base								
Ruben Ortiz									
70529					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:53:34 PM					
Ambriz, Jose	Rm 21A MCD 028 Size 43; need 1 cover and 1 base								
Ruben Ortiz									
70530					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:54:56 PM					
Ambriz, Jose	Rm 21B MCD 027 Size 43; need 1 cover and 1 base								
Ruben Ortiz									
70531					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:56:14 PM					
Ambriz, Jose	Rm 23 MCD 026 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70532					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 12:57:49 PM					
Ambriz, Jose	Rm 25 MCD 025 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70726					3/14/2011		37		\$0.00
Medium	Work In Progress			3/14/2011 12:15:21 AM					
Ortiz, Ruben	Monthly - Desert View ES - Grease Trap (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
71261		Custodial			3/30/2011		21		\$0.00
Medium	Work In Progress			3/30/2011 3:25:01 PM					
Carbajal, Jimmy	Wet-n-dry needs a new squeegee.								
Jesus Estrada									
4/20/2011 11:58:49 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Desert View ES</b>									
71433					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:53 AM					
Orozco, Danny	Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71570					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:52 AM					
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71571					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:53 AM					
Ortiz, Ruben	Monthly - Desert View ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71573					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:53 AM					
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71674					4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 3:28:08 PM					
Ortiz, Ruben	Need to replace water faucet outdoors.								
<u>Ruben Ortiz</u>									
71906					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:37 AM					
Rivera, Hector	Monthly - QRTLY BLDG INSP REPORT (DV) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
71913					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:40 AM					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71984					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 3:44:44 PM					
Ortiz, Ruben	Need to replace 10 swings on the eastside playground								
<u>Ruben Ortiz</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Desert View ES</b>								
72170		Portables			4/18/2011		2		\$0.00	
Medium	Work In Progress			4/18/2011 10:38:00 AM						
Lara, Ralph	carpet was installed in portable#6 (w.o. #67649). door needs to be shaved down so that it opens/closes properly									
Jesus Estrada										
72172		Custodial			4/18/2011		2		\$0.00	
Medium	Work In Progress			4/18/2011 11:13:46 AM						
Lara, Ralph	Need a new lock for the front entrance.THANK YOU IN ADVANCED.									
Hector Rivera										
72272					4/19/2011		1		\$0.00	
Medium	Work In Progress			4/19/2011 9:30:45 PM						
Ortiz, Ruben	Need to replace 6 water faucets in the restrooms both boys/girls									
Ruben Ortiz										
<b>Count: 62 Work Orders</b>		<b>Avg. Age of WO's 65</b>		<b>Total for Desert View ES</b>			<b>0</b>	<b>\$0.00</b>		



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
60601					7/4/2010	7/25/2010	290		\$0.00
Medium	Work In Progress			7/4/2010 12:23:44 AM					
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
62207					8/10/2010		253		\$0.00
Medium	Work In Progress			8/10/2010 8:44:53 AM					
Orozco, Danny	NEED TO HAVE FIRE EXTINGUISHERS SERVICED AS PER YEARLY INSPECTION								
<u>Danny Orozco</u>									
63425					9/3/2010		229		\$0.00
Medium	Work In Progress			9/3/2010 4:26:13 PM					
Holguin, Alfredo	AS PER JUAN A., GENERATOR DID NOT GO ON TUESDAY AS SCHEDULED.								
<u>Maritza Gonzalez</u>									
64742					10/3/2010	10/24/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:59 AM					
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
65962					10/28/2010		174		\$0.00
Medium	Work In Progress			10/28/2010 10:25:54					
Castillo, Carlos	BREAKER IN RECEPTIONIST AREA AND LOUNGE KEEPS JUMPING.								
<u>Maritza Gonzalez</u>									
66086					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:22					
Orozco, Danny	Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67821					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:38 AM					
Villalobos, David	Yearly - GAC Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67839					1/2/2011	1/23/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:45 AM					
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
68249					1/11/2011		99		\$0.00
Medium	Work In Progress			1/11/2011 3:13:39 PM					
Ambriz, Jose	TECHNOLOGY SERVER ROOM- UNIT IS NOT WORKING PROPERLY.								
<u>Maritza Gonzalez</u>									
68250					1/11/2011		99		\$0.00
Medium	Work In Progress			1/11/2011 3:17:23 PM					
Villalobos, David	FLOOR DRAIN CLOGGED- MENS RESTROOM A-WING								
<u>Maritza Gonzalez</u>									
68461					1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 3:11:10 PM					
Miranda, Danny	as per our meeting, please build 4 offices in the dining area. thank you								
<u>Richard Chavez</u>									
68594					1/20/2011		90		\$0.00
Medium	Work In Progress			1/20/2011 9:46:48 AM					
Orozco, Danny	PILOT TO GRILL IS NOT GOIN ON, GENTLEMEN FROM HYDRO CLEAN CAME TO SERVICE/CLEAN HOODS THEY REMOVED APPLIANCES WHEN PUT BACK PILOT DID NOT WORK. APPLIANCES WERE WORKING FINE BEFORE THEY WERE REMOVED. SNP MANAGER GESSICA M.882-6784.								
<u>Maritza Gonzalez</u>									
68999					2/1/2011		78		\$0.00
Medium	Work In Progress			2/1/2011 4:04:12 PM					
Ambriz, Juan	AS PER MR. CHAVEZ, PATCH UP HOLES AND PAINT OFFICES/ROOMS IN C WING. (PLEASE SEE MARITZA)								
<u>Maritza Gonzalez</u>									
69816					2/23/2011		56		\$0.00
Medium	Work In Progress			2/23/2011 9:56:10 AM					
Ambriz, Juan	TILES ARE LIFTING AND NEED TO BE REPLACED IN DINO FACIO OFFICE.								
<u>Maritza Gonzalez</u>									
70132		Parking Lot			3/3/2011		48		\$0.00
Medium	Work In Progress			3/3/2011 9:04:28 AM					
Ontiveros, Guadalupe	need repair with aspalt where leak was.								
<u>Guadalupe Ontiveros</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
70175		Parking Lot			3/4/2011		47		\$0.00
Medium	Work In Progress				3/4/2011 8:18:36 AM				
Ambriz, Juan	Need to Install parking stoppers to avoid sprinkler head damage.								
Juan Ambriz									
70199					3/4/2011		47		\$0.00
Medium	Work In Progress	Northside main			3/4/2011 3:40:56 PM				
Ambriz, Jose	Need to repair sprinklers leaking water								
Juan Ambriz									
70257					3/6/2011		45		\$0.00
Medium	Work In Progress				3/6/2011 12:17:47 AM				
Orozco, Danny	Yearly - GAC Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
70312					3/6/2011		45		\$0.00
Medium	Work In Progress				3/6/2011 12:18:14 AM				
Ambriz, Juan	Yearly - GAC A-10 Heat Pump Cooling Only Yearly - Refer to PM schedule details.								
Margret Villalobos									
70398					3/7/2011		44		\$0.00
Medium	Work In Progress				3/7/2011 9:29:16 AM				
Ambriz, Jose	COOLING UNIT IS NOT WORKING PROPERLY IN SERVER ROOM.								
Juan Ambriz									
71192					3/29/2011		22		\$0.00
Medium	Work In Progress				3/29/2011 8:22:49 AM				
Ambriz, Juan	TILES ARE LIFTING AND NEED TO BE REPLACED IN FRONT OF MR. YTURRALDE.								
Maritza Gonzalez									
71283					3/31/2011		20		\$0.00
Medium	Work In Progress				3/31/2011 12:17:32 AM				
Ambriz, Juan	Monthly - GAC A-16 Fan Exh Roof Semimonthly - Refer to PM schedule details.								
Margret Villalobos									
71425					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress				4/3/2011 12:19:49 AM				
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
71446					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:59 AM					
Orozco, Danny	Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71505					4/3/2011	4/19/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:25 AM					
Ambriz, Juan	Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71506					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:25 AM					
Ambriz, Juan	Monthly - GAC F-39 Kitch Exh Makeup Ut Semimonthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71508					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:26 AM					
Ambriz, Juan	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71510					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:27 AM					
Ambriz, Juan	Monthly - GAC Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71644					4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 9:14:44 AM					
Ambriz, Juan	TILES NEED TO BE REPLACED IN CONFERENCE ROOM 2.								
<u>Maritza Gonzalez</u>									
71709					4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 9:49:30 AM					
Ambriz, Juan	LIGHT UNDER CABINET IN LUCY GARCIAS OFFICE NEEDS TO BE REPLACED.								
<u>Maritza Gonzalez</u>									
71806					4/7/2011		13		\$0.00
Medium	Work In Progress			4/7/2011 4:28:49 PM					
Lara, Ralph	PANIC BAR GETS STUCK ON SIDE ENTRANCE DOOR IN A-WING.								
<u>Maritza Gonzalez</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
71879					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:23 AM					
Rodriguez, Arturo	Monthly - QRTLY BLDG INSP REPORT (GAC) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
71900					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:32 AM					
Ambriz, Juan	Monthly - GAC Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71997					4/12/2011		8		\$0.00
Medium	Work In Progress			4/12/2011 8:26:23 AM					
Ronquillo, Ruben	BROKEN WINDOW IN RAY LARA'S AREA. 59x60 DOUBLE WINDOW.								
<u>Juan Ambriz</u>									
72094		Electrical Room			4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 1:08:54 PM					
Castillo, Carlos	need to run electrical to sprinkler system alarm								
<u>Danny Orozco</u>									
72201					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 4:39:09 PM					
Briones, Enrique	As per Bertha Ruiz six small and one large banker's boxes need to go to the warehouse.								
<u>Maritza Gonzalez</u>									
72222					4/19/2011		1		\$0.00
Medium	Work In Progress			4/19/2011 9:52:57 AM					
Lara, Ralph	2 FILE CABINETS IN SNP OFFICE NEED GET UNLOCKED AND NEW KEYS OR LOCK NEED TO MADE. PLEASE SEE JACKIE AGUILAR.								
<u>Jacqueline Aguilar</u>									
72293					4/20/2011		0		\$0.00
Medium	Work In Progress			4/20/2011 9:17:23 AM					
Ambriz, Juan	LIGHT WENT OUT IN UNISEX RESTROOM IN FRONT OF RECEPTIONIST AREA.								
<u>Maritza Gonzalez</u>									
<b>Count: 38 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>67</b>		<b>Total for GAC</b>	<b>0</b>		<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden ES</b>									
61541					7/30/2010		264		\$0.00
Medium	Work In Progress			7/30/2010 11:21:54 AM					
Moncayo, Fernando	Mini blinds need to be replaced where the windows were broken.								
	1. Washington wing workroom 1 blind broken. 2. Jefferson wing Room 202 blinds are broken.								
<u>Fernando Moncayo</u>									
63295		Classroom			9/1/2010		231		\$0.00
Medium	Work In Progress			9/1/2010 12:52:01 PM					
Moncayo, Fernando	MOVE EIGHT SHELVING UNITS FROM GADSDEN ELEMENTARY TO LA UNION JTP FOR ROBERT SAAVEDRA CHECK WITH GRACE MARQUEZ @ GE REGARDING UNITS								
<u>Margaret Villalobos</u>									
66078					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:19					
Orozco, Danny	Monthly - Gadsden ES Fire Sprinkler Insp -Qrtly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66079					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:19					
Orozco, Danny	Monthly - Gadsden ES - Fire Suppression Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67395		Cafeteria			12/8/2010		133		\$0.00
Medium	Work In Progress			12/8/2010 10:58:12 AM					
Moncayo, Fernando	As per Mr. Gallegos reroute and redo serving lines drain plumbing								
<u>Fernando Moncayo</u>									
68176					1/10/2011		100		\$0.00
Medium	Work In Progress			1/10/2011 1:32:21 PM					
Ontiveros, Guadalupe	Please schedule Spring Season fertilaizer for Gadsden Elementary								
<u>Fernando Moncayo</u>									
68721					1/25/2011		85		\$0.00
Medium	Work In Progress			1/25/2011 8:11:58 AM					
Lozoya, Manny	Have a broken key that needs to be replace Thanks!!								
<u>Fernando Moncayo</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
68903					1/28/2011		82		\$0.00
Medium	Work In Progress			1/28/2011 3:42:34 PM					
Munoz, Michael	need to purchase morgan for site.								
<u>Michael Munoz</u>									
68906					1/28/2011		82		\$0.00
Medium	Work In Progress			1/28/2011 3:54:21 PM					
Gallegos, Rafael	Warranty w/o heat pump filters are petty bad(clogged)								
<u>Fernando Moncayo</u>									
69028					2/6/2011	2/27/2011	73		\$0.00
Medium	Work In Progress			2/6/2011 12:33:36 AM					
Orozco, Danny	Monthly - Gadsden ES Fire Sprinkler Insp -Qrtly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69133					2/7/2011		72		\$0.00
Medium	Work In Progress			2/7/2011 10:20:38 AM					
Lozoya, Manny	AS PER MR. CHAVEZ, PLEASE ISSUE GATE KEY TO YMCA OF EL PASO FOR SOCCER LEAGUE.								
<u>Maritza Gonzalez</u>									
69866					2/24/2011		55		\$0.00
Medium	Work In Progress			2/24/2011 9:26:18 AM					
Appelzoller, Fred	room 101; Ecoflush toilet won't flush,cleaned strainer,ckd water lines no luck. Also no hot water on shower all valves are open please assist ASAP thanks!!								
<u>Fernando Moncayo</u>									
70143		Library			3/3/2011		48		\$0.00
Medium	Work In Progress			3/3/2011 10:38:12 AM					
Appelzoller, Fred	A horrible smell coming from( the sewer trap?) in or by the Library-Please speak to Mrs. Ida Garcia. Please send a plumber to come fix.								
<u>Rosa Hidalgo</u>									
70702					3/13/2011	3/29/2011	38		\$0.00
Medium	Work In Progress			3/13/2011 12:13:02 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70719					3/14/2011		37		\$0.00
Medium	Work In Progress			3/14/2011 12:15:18 AM					
Villalobos, Hector	Monthly - Gadsden ES - Grease Trap (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
4/20/2011 11:58:49 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden ES</b>									
70733					3/14/2011		37		\$0.00
Medium	Work In Progress			3/14/2011 10:12:49 AM					
Moncayo, Fernando	Need a carpet roto block jose pinon								
<u>Fernando Moncayo</u>									
70856					3/17/2011		34		\$0.00
Medium	Work In Progress			3/17/2011 8:50:13 AM					
Lozoya, Manny	NEED TO ISSUE A GATE KEY TO EL PASO DISPOSAL FOR USE ON TRASH PICK UP WHEN NO ONE IS THERE. o.k. AS PER ALFREDO								
<u>Mary Sitters</u>									
70885					3/17/2011		34		\$0.00
Medium	Work In Progress			3/17/2011 3:24:06 PM					
Moncayo, Fernando	filters on units need to be changed ASAP, we will start to loose compressors if not changed soon. let me know when complete.thank you								
<u>Michael Munoz</u>									
71367					4/1/2011		19		\$0.00
Medium	Work In Progress			4/1/2011 11:32:39 AM					
Ronquillo, Ruben	I am requesting two signs that say "Pick up and drop off area". I would like for them to be permanent standing. Plus, if possible you could supply as with 8 orange cones to assist us with the flow.								
<u>Grace Marquez</u>									
71648					4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 9:46:56 AM					
Flores, Pete	Mr. Flores, can I borrow the bobcat,for one day, maybe half day will do.Thanks!								
<u>Fernando Moncayo</u>									
71654		Cafeteria			4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 11:12:35 AM					
Moncayo, Fernando	please assist Cuca in cafeteria... ovens are not working properly... thank you								
<u>Loraine Gandara</u>									
71655					4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 11:20:17 AM					
Moncayo, Fernando	As per Mr. Gallegos need to turn off some of the hallways lights								
<u>Fernando Moncayo</u>									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden ES</b>									
71899					4/10/2011		10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:32 AM					
Pinon, Jose	Monthly - PM Schedule created on 1/20/2011 - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
71921					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:07:05 AM					
Moncayo, Fernando	Need to paint fire lane curb and no parking zone								
<u>Fernando Moncayo</u>									
71927		Gym			4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:29:08 AM					
Moncayo, Fernando	Need to install a "cosmopolitan electrol" motorized large projection screen								
<u>Fernando Moncayo</u>									
71970					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 3:23:48 PM					
Ontiveros, Guadalupe	Need a load of top soil								
<u>Fernando Moncayo</u>									
72087					4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 10:01:38 AM					
Moncayo, Fernando	Need to treat and clean the holding ponds area, fencelines and the westside of fence next to Hwy 78.								
<u>Michael Munoz</u>									
72158					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 7:39:06 AM					
Sotelo, Enrique	Need to run electrical power to new motorized projection screen.Thanks!								
<u>Fernando Moncayo</u>									
72212		Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress			4/19/2011 8:10:07 AM					
Moncayo, Fernando	received carts for ELMOS... need for them to be put together and installed in the classrooms... thank you								
<u>Loraine Gandara</u>									
72241		Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress			4/19/2011 2:26:28 PM					
Moncayo, Fernando	please build AV carts located in Ms. Garcia office needed them ASAP.... greatly appreciate your assistance in this urgent matter.....								
<u>Loraine Gandara</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
72242		Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress			4/19/2011 2:34:03 PM					
Moncayo, Fernando	loud sounds were coming out of air vents in rm 101....once looked at noticed that there was no filters went to verify other rooms and also were missing filters...some of them were very filthy... please assist in this matter... greatly appreciate your assistance ....								
<u>Loraine Gandara</u>									
72296		Restroom (Girls)			4/20/2011		0		\$0.00
Medium	Work In Progress			4/20/2011 9:49:13 AM					
Moncayo, Fernando	the water in the girls bathroom as well as in classroom 202 is coming out very hott.. please assist in this matter thank you								
<u>Loraine Gandara</u>									
<b>Count: 32 Work Orders</b>		<b>Avg. Age of WO's 58</b>			<b>Total for Gadsden ES</b>			<b>0</b>	<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
61798					8/3/2010		260		\$0.00
Medium	Work In Progress			8/3/2010 11:00:19 AM					
Lara, Ralph	Requested by Mr. Chambers for Entire Campus-Name plates w/room numbers for entire campus-all teachers, offices, etc.								
<u>Velia Alarcon</u>									
62248					8/10/2010		253		\$0.00
Medium	Work In Progress			8/10/2010 10:55:42 AM					
Herrera, Joel	Requested by Coach Lawrence for Main Soccer Field- Paint both awnings on Main Soccer Field.								
<u>Velia Alarcon</u>									
62314	Boys Gym				8/11/2010		252		\$0.00
Medium	Work In Progress			8/11/2010 11:13:51 AM					
Ambriz, Jose	Requested by Coach Lawrence for Rm. 408 Boy's Gym- The new Boy's Soccer Locker Room needs air conditioning of some type. It's very hot in there.								
<u>Velia Alarcon</u>									
62985					8/26/2010		237		\$0.00
Medium	Work In Progress			8/26/2010 12:38:44 PM					
Castillo, Carlos	Requested by Ms. Leahy Rm. 127 Main Building-The electricity keeps going out in my room. Please check on this since it is effecting my computer.								
<u>Velia Alarcon</u>									
63373					9/2/2010		230		\$0.00
Medium	Work In Progress			9/2/2010 3:07:40 PM					
Apodaca, Mario	Requested by Coach Hite for Press Box at Football Field -If we provide paint, can you paint press box.				Assign to Mario asp Mike. The paint is not the problem is the labor, If Mario/Joel can squeeze this in, if it's not possible stay on priority wo's and pms.				
<u>Velia Alarcon</u>									
63613					9/8/2010		224		\$0.00
Medium	Work In Progress			9/8/2010 9:42:08 AM					
Lara, Ralph	Need to install locks between wood shop and art class.								
<u>Michael Munoz</u>									
63766					9/10/2010		222		\$0.00
Medium	Work In Progress			9/10/2010 2:58:55 PM					
Apodaca, Mario	Requested by Ms. Simmons Rm. 324 Enlgish Book Room in Academic Building-Need shelves for back wall in English book room. This would help immensely.								
<u>Velia Alarcon</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
64440					9/28/2010		204		\$0.00
Medium	Work In Progress			9/28/2010 7:59:08 AM					
Castillo, Carlos	CALI WE NEED TO REPLACE TWO BULBS LIGHTS AT G.Y.M THANK YOU CALI								
Joel Herrera									
64598					9/30/2010		202		\$0.00
Medium	Work In Progress			9/30/2010 11:04:24 AM					
Castillo, Carlos	Requested by Mr. Pokluda for Tennis Courts-Re-wire electrical outlet on south side of Tennis Courts. Outlet is needed for tennis ball machine during practice.								
Velia Alarcon									
64707					10/3/2010	11/3/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:46 AM					
Herrera, Joel	Yearly - Gadsden HS U2 (Heater)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
65724					10/21/2010		181		\$0.00
Medium	Work In Progress			10/21/2010 2:23:13 PM					
Castillo, Carlos	10/21/10 I need an electrician to disconnect swimming pool pump and reconnect a new pump in place of the old one. The old pump needs to be rebuilt as it is not pumping to full capacity Thanks, Raul								
Raul Sanchez									
65815					10/25/2010		177		\$0.00
Medium	Work In Progress			10/25/2010 1:25:16 PM					
Sanchez, Raul	10/25/10 I need a w.o. for the purchase of a replacement clear effluent pump that I will be installing at the GHS wwtp. We are presently working on only one pump as the other one overheated & burnt out. I will use work order for the initial installation as well. Thanks, Raul								
Raul Sanchez									
65866	North Building	Classroom			10/26/2010		176		\$0.00
Medium	Work In Progress			10/26/2010 2:18:58 PM					
Appelzoller, Fred	As per Ms. Romero, she would like to have the gas jets on the science workbenches repaired in room 222, north building.								
Mario Apodaca									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

65974 10/28/2010 174 \$0.00

Medium Work In Progress 10/28/2010 3:03:22 PM

Castillo, Carlos CALI WE HAVE PROBLEM WITH THE LIGHT BEHIND TO ACADEMIC BUILDING IT DOESNT TURON

Joel Herrera

66087 10/31/2010 11/21/2010 171 \$0.00

Medium Work In Progress 10/31/2010 12:36:23

Orozco, Danny Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

66483 11/9/2010 162 \$0.00

Medium Work In Progress 11/9/2010 9:07:47 AM

Castillo, Carlos please check lighting around buss turn- around and repair as need be. thanks

Michael Munoz

66488 11/9/2010 162 \$0.00

Medium Work In Progress 11/9/2010 9:50:24 AM

Appelzoller, Fred FRED WE NEED TO RE PLACE SINCK ON GIRLS REST ROOMS AT NORTH BUILDING

Joel Herrera

66843 Cafeteria (1998) Cafeteria 11/19/2010 152 \$0.00

Medium Work In Progress 11/19/2010 10:34:10

Apodaca, Mario As per Mr. Pokluda he wants the floor tiles that were broken during basketball practice inside the cafeteria repaired.

Joe Munoz

Mary,  
I went to GHS and there are not enough broken tiles in the cafeteria to make it worth their while. Go ahead and forward that work order to the building mechanic. Thanks.

66919 11/29/2010 142 \$0.00

Medium Work In Progress 11/29/2010 2:50:42 PM

Apodaca, Mario Requested by Coach Greenwald Rm. 651 Business Building-Need new blind and need window latch fixed.

Velia Alarcon

67138 12/3/2010 138 \$0.00

Medium Work In Progress 12/3/2010 3:08:33 PM

Castillo, Carlos Requested by Velia for Lights on the West Side of the Academic Building Facing Bus Turn Around-The two west lights are burned out and is very dark when students arrive from Athletic Events or late field trips.

Velia Alarcon

4/20/2011 11:58:49 AM

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
67140					12/3/2010		138		\$0.00
Medium	Work In Progress			12/3/2010 3:09:49 PM					
Castillo, Carlos	Requested by Velia for Marquee in Front of the School- South side light is burned out, please replace.								
Velia Alarcon									
67213					12/5/2010	1/5/2011	136		\$0.00
Medium	Work In Progress			12/5/2010 12:27:06 AM					
Herrera, Joel	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
67312		Athletic Field			12/6/2010		135		\$0.00
Medium	Work In Progress			12/6/2010 2:12:53 PM					
Ontiveros, Guadalupe	Truck#122 needs module lite protector replaced.								
Guadalupe Ontiveros									
67421					12/8/2010		133		\$0.00
Medium	Work In Progress			12/8/2010 3:50:47 PM					
Castillo, Carlos	CALI LIGHTS TO CAFETERIA OUTSIDE NOT WORKING THANK YOU CALI								
Joel Herrera									
67609					12/14/2010		127		\$0.00
Medium	Work In Progress			12/14/2010 12:25:29					
Castillo, Carlos	Requested by Velia for Academic Building-All outside lights around the building need to be checked, many students walk around or between buildings to get to the Bus Turn Around afterschool. Extremely dark at night and a possible safety issue with the construction fence between the North and Academic Buildings.								
Velia Alarcon									
67822					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:38 AM					
Villalobos, David	Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
67905					1/2/2011	1/10/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:29:20 AM					
Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
68083		Athletic Field			1/7/2011		103		\$0.00
Medium	Work In Progress			1/7/2011 1:05:58 PM					
Ontiveros, Guadalupe	Gator 4x2 needs steering gear replaced and hood to be replaced. also battery.								
<u>Guadalupe Ontiveros</u>									
68084		Athletic Field			1/7/2011		103		\$0.00
Medium	Work In Progress			1/7/2011 1:13:33 PM					
Ontiveros, Guadalupe	735 mower leaking from crank shaft and intake valve needs to be replaced. Also cylinder block needs replacement.								
<u>Guadalupe Ontiveros</u>									
68088		Athletic Field			1/7/2011		103		\$0.00
Medium	Work In Progress			1/7/2011 1:57:04 PM					
Aldaz, Bobby	baseball, softball varsity, jv softball, soccer field and all pe fields need to be fertilize with 16-8-8.								
<u>Guadalupe Ontiveros</u>									
68272	Cafeteria (1998)				1/12/2011		98		\$0.00
High	Work In Progress			1/12/2011 7:34:58 AM					
Munoz, Joe	please sweep and power wash patio in front of cafeteria and surrounding areas. Thank you					3/2/11 - remailed to joe 4/5/11 - REMAILED TO JOE			
<u>Michael Munoz</u>									
68333	Auto Shop	Classroom			1/13/2011		97		\$0.00
Medium	Work In Progress			1/13/2011 8:08:45 AM					
Castillo, Carlos	need assist on put new ballast for the lamps at the auto shop								
<u>Mario Apodaca</u>									
68406					1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 12:23:45 AM					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68451	Old English Bldg				1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 2:41:54 PM					
Munoz, Michael	(PROJECT) Sidewalk in front is trip hazard. - repair / replace					Leadership Request			
<u>Alfredo Holguin</u>									
68453	Computer				1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 2:45:23 PM					
Herrera, Joel	Patch roof leaks					Leadership Request			
<u>Alfredo Holguin</u>									
4/20/2011 11:58:49 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
68457					1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 2:50:01 PM					
Munoz, Michael		(PROJECT)				Leadership Request			
		Purchase and install new marquee.							
<u>Alfredo Holguin</u>									
68535					1/19/2011		91		\$0.00
Medium	Work In Progress			1/19/2011 8:55:23 AM					
Apodaca, Mario		Requested by Ms. Roth Rm. 328 Academic Building- Shelves in storage cabinets need to be re-enforced so they don't break holding the stored science equipment and materials.							
<u>Velia Alarcon</u>									
69082					2/6/2011	2/12/2011	73		\$0.00
Medium	Work In Progress			2/6/2011 12:33:58 AM					
Apodaca, Mario		Monthly - Gadsden HS - Elevator (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
69166	Pool Pump	Pump House			2/8/2011		71		\$0.00
Medium	Work In Progress			2/8/2011 8:18:45 AM					
Appelzoller, Fred		the pipe in pool pump room need to be repair do to water freezing water in the pipe							
<u>Mario Apodaca</u>									
69168	Pool Dressing	Dressing Room			2/8/2011		71		\$0.00
Medium	Work In Progress			2/8/2011 8:24:29 AM					
Appelzoller, Fred		the pool dressing room need new sink faucet and shower faucet do to freezing water in pipe							
<u>Mario Apodaca</u>									
69177	North Building	Hallway/Corridor			2/8/2011		71		\$0.00
Medium	Work In Progress			2/8/2011 8:49:40 AM					
Appelzoller, Fred		outside hosebib at the n-bldg by room 221 a copper pipe need to be repair							
<u>Mario Apodaca</u>									
69330					2/10/2011		69		\$0.00
Medium	Work In Progress			2/10/2011 10:33:45 AM					
Ontiveros, Guadalupe		Requested by Coach Lawrence for Soccer Fields-Over seed, top soil, and fertalize main soccer field.							
<u>Velia Alarcon</u>									
69422					2/14/2011		65		\$0.00
Medium	Work In Progress			2/14/2011 12:26:03 AM					
Sanchez, Raul		Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
4/20/2011 11:58:49 AM									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
69591	North Building	Parking Lot			2/16/2011		63		\$0.00
Medium	Work In Progress			2/16/2011 11:13:36 AM					
Apodaca, Mario	the n/side parking lot need to be restrip and handicap repait for the new office								
<u>Mario Apodaca</u>									
69593					2/16/2011		63		\$0.00
Medium	Work In Progress			2/16/2011 11:26:37 AM					
Gonzalez, Salvador	need to put up new steel pipe post by the flag post n-side parking lot for traffic can't get on the sidewalk								
<u>Mario Apodaca</u>									
69819					2/23/2011		56		\$0.00
Medium	Work In Progress			2/23/2011 10:32:30 AM					
Ontiveros, Guadalupe	Requested by Coach Lawrence for Main Soccer Field- Paint lines on Main Soccer Field.								
<u>Velia Alarcon</u>									
70254					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:45 AM					
Orozco, Danny	Yearly - Gadsden HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70331					3/6/2011	3/14/2011	45		\$0.00
Medium	Work In Progress			3/6/2011 12:18:24 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70332					3/6/2011	3/12/2011	45		\$0.00
Medium	Work In Progress			3/6/2011 12:18:24 AM					
Apodaca, Mario	Monthly - Gadsden HS - Elevator (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70333					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:18:25 AM					
Apodaca, Mario	Yearly - Gadsden HS A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70445					3/8/2011		43		\$0.00
Medium	Work In Progress			3/8/2011 9:24:16 AM					
Castillo, Carlos	Requested by Ms. Moreno Rm. 126 Main Building- Electricity on for wall shorted out, no electricity to the computer and printer.								
<u>Velia Alarcon</u>									
4/20/2011 11:58:49 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
70446					3/8/2011		43		\$0.00
Medium	Work In Progress			3/8/2011 9:27:02 AM					
Gonzalez, Salvador	Requested by Al Marmolejo for Bus Turn Around Gate- North Bus Turn Around Gate is not working properly, does not open or close correctly.								
<u>Velia Alarcon</u>									
70447					3/8/2011		43		\$0.00
Medium	Work In Progress			3/8/2011 9:28:32 AM					
Herrera, Joel	Requested by Velia for Marque in Front of School-Both lights on the marquee are burned out, they need to be replaced.								
<u>Velia Alarcon</u>									
70490	North Building				3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 10:22:49 AM					
Lara, Ralph	Requested by Commander Dixon for Room #'s 201, 202, 203 in the North Building-Repair or replace wooden doors on all three classrooms.								
<u>Velia Alarcon</u>									
70492					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 10:25:10 AM					
Apodaca, Mario	Requested by Mr. Pokluda for Cafeteria-Repair or replace burned out lights or damaged covers in the Cafeteria. A scissor lift will be needed.								
<u>Velia Alarcon</u>									
70708					3/13/2011		38		\$0.00
Medium	Work In Progress			3/13/2011 12:13:05 AM					
Apodaca, Mario	Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70724					3/14/2011		37		\$0.00
Medium	Work In Progress			3/14/2011 12:15:20 AM					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70781	Concession	Football Field			3/15/2011		36		\$0.00
Medium	Work In Progress			3/15/2011 12:45:03 PM					
Ambriz, Jose	need a new ice machine for the concession stand at the football field								
Mario Apodaca									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
72191					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 3:43:50 PM					
Lara, Ralph	NEED GATE KEY FOR EL PASO DISPOSAL. LORENA WILL PICK UP AND TURN IN OLD ONE								
<u>Mary Sitters</u>									
70883					3/17/2011		34		\$0.00
Medium	Work In Progress			3/17/2011 3:19:35 PM					
Ontiveros, Guadalupe	Requested by Coach Letz for Tennis Courts-WORK ORDER # 69374 HAS NOT BEEN COMPLETED. Please clean and blow off sand from Tennis Courts, 2nd Notice.								
<u>Velia Alarcon</u>									
70921	Library	Custodial			3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 11:10:17 AM					
Carbajal, Jimmy	we have an extractor that will not pick up water.								
<u>Joe Munoz</u>									
70933	Varsity Gym				3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:14:15 PM					
Ronquillo, Ruben	need 8 signs for the gym. NOTICE : NO FOOD OR DRINK IN THE GYM. 12"X18"								
<u>Mario Apodaca</u>									
70979		Classroom			3/21/2011		30		\$0.00
Medium	Work In Progress			3/21/2011 12:36:15 PM					
Castillo, Carlos	need to put new outlet at od to a shot. room 126								
<u>Mario Apodaca</u>									
71028	Main Building	Classroom			3/23/2011		28		\$0.00
Medium	Work In Progress			3/23/2011 3:24:20 PM					
Lara, Ralph	The door lock at classroom 121 will lock but when you pull on it the door will open because it will not secure.								
<u>Joe Munoz</u>									
71048	Boys Gym	Dressing Room			3/24/2011		27		\$0.00
Medium	Work In Progress			3/24/2011 12:30:35 PM					
Castillo, Carlos	a lamp at the boys gym w3as pull down off the ceiling need to be repair. do to vandalism. A.S.A.P								
<u>Mario Apodaca</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

71049	Boys Gym	Dressing Room			3/24/2011		27		\$0.00
-------	----------	---------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/24/2011 12:34:36 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario  
 THE CEILING IN THE BOYS DRESSING ROOM WAS PULL DOWN NEED TO BE REPAIR DO TO VANDALISM. A.S.A.P

Mario Apodaca

71127	Pool Pump	Pool			3/28/2011		23		\$0.00
-------	-----------	------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/28/2011 8:57:01 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sanchez, Raul  
 3/28/11  
 need a work order to purchase a cast iron hair & lint strainer for the swimming pool. The one in place now is leaking & is corroded. I have the quote for a new one. Thanks, Raul

Raul Sanchez

71142	Pool Dressing				3/28/2011		23		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Changing Room			3/28/2011 10:58:45 AM				
--------	------------------	---------------	--	--	-----------------------	--	--	--	--

Sanchez, Raul  
 Need the following completed by April 29th. (Asp Mike, Fred will assist)  
 -4 shower Heads popped out  
 -4 shower valves popped out  
 -2 sink faucets broke  
 -1 sink feeder line broke  
 -2 sink traps leaking  
 -Janitor Sink faucet not working

Alfredo Holguin

71143	Pool Dressing				3/28/2011		23		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Changing Room			3/28/2011 11:03:19 AM				
--------	------------------	---------------	--	--	-----------------------	--	--	--	--

Apodaca, Mario  
 Need the following completed by April 29th. (Mario & Joel)  
 -A/C line burst  
 -Heavy water leak from ceiling ( office area )  
 -Broken tiles alone edges ( safety hazard )  
 -Broken benches ( both dressing areas )

Alfredo Holguin

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

71145	Pool Pump				3/28/2011		23		\$0.00
-------	-----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/28/2011 11:13:13 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Sanchez, Raul Need the following completed by April 29th.

- Pump room main line broke
- Switch out pump
- Backflow valve leaks
- Clean Diodes
- Check System lines for leaks
- Flush Chlorinator
- Repair lifeguard Chairs
- Repair Handicap lift
- Repair steps to water slide
- Repair water lines on slide
- Overall clean up

Alfredo Holguin

71146	Pool Pump				3/28/2011		23		\$0.00
-------	-----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/28/2011 11:14:58 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Apodaca, Mario Need the following completed by April 29th. (Mario &amp; Joel)

- Install signs
- Install picnic shade

Alfredo Holguin

71287					3/31/2011	5/1/2011	20		\$0.00
-------	--	--	--	--	-----------	----------	----	--	--------

Medium	Work In Progress			3/31/2011 12:17:34 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Apodaca, Mario Yearly - Gadsden HS A8 (Window Unit)(Yearly) - Refer to PM schedule details.

Margret Villalobos

71304					3/31/2011		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			3/31/2011 9:11:38 AM		3/31/2011			
--------	------------------	--	--	----------------------	--	-----------	--	--	--

Flores, Pete Truck #137 needs oil change.

Guadalupe Ontiveros

71318	Main Building				3/31/2011		20		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/31/2011 2:17:31 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben need a glass repair at the main bldg room 100 (20"x20")

Mario Apodaca

71319	Cafeteria (1998)	Restroom (Girls)			3/31/2011		20		\$0.00
-------	------------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/31/2011 2:20:38 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben need a glass repair at the cafe bldg to staff restroom (20"x38")

Mario Apodaca

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
71327	Main Building	Classroom			3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 2:49:07 PM					
Castillo, Carlos	the outlet at room126 are not working (wo#70979)								
Mario Apodaca									
71362					4/1/2011		19		\$0.00
Medium	Work In Progress			4/1/2011 10:43:38 AM					
Ontiveros, Guadalupe	Requested by Coach Hite for Practice Football Field-We want the practice Football Field (dirt field) marked, lined, as soon as possible.								
Velia Alarcon									
71363					4/1/2011		19		\$0.00
Medium	Work In Progress			4/1/2011 10:46:13 AM					
Appelzoller, Fred	Requested by Oscar Menchaca for Boy's & Girl's Dressing Rooms in the Boy's Gym-Water fountain is broken and a sink keep leaking.								
Velia Alarcon									
71392					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:32 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.								
Margret Villalobos									
71400					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:36 AM					
Vallejo, Albert	Monthly - Gadsden HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
71434					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:53 AM					
Orozco, Danny	Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71524					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:33 AM					
Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
71525					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:33 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
4/20/2011 11:58:49 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
71526					4/3/2011	4/19/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:34 AM					
Apodaca, Mario	Monthly - Gadsden HS A1 (Air Dryer)(S.Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71527					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:34 AM					
Apodaca, Mario	Yearly - Gadsden HS A13 (Ceil/Wall Unit)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71528					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:35 AM					
Apodaca, Mario	Monthly - Gadsden HS - Elevator (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71555					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:46 AM					
Sanchez, Raul	Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71592					4/4/2011		16		\$0.00
Medium	Work In Progress			4/4/2011 8:59:20 AM					
Briones, Enrique	On April 4, 2011, please deliver 75 boxes to Gadsden High School. Reference P.O. # 101105339.								
<u>Yolie Jacquez</u>									
71649	Library	Library			4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 10:05:51 AM					
Flores, Pete	As per Mr. Grubaugh, the library would like to borrow one or more pickup trucks next week to help with moving into the new library building. They will need them 4/11 - 4/15.								
<u>Mario Apodaca</u>									
71695		Athletic Field			4/6/2011		14		\$0.00
High	Work In Progress			4/6/2011 8:34:52 AM					
Sanchez, Raul	need to locate sewer line for tarp by tennis courts.								
<u>Guadalupe Ontiveros</u>									
71741	Cafeteria (1998)	Cafeteria			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 3:02:22 PM					
Ambriz, Jose	need a new e/cooler moter for a unit at the cafe bldg 3 hp								
<u>Mario Apodaca</u>									
4/20/2011 11:58:49 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
71751		Football Field			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 3:35:57 PM					
Ontiveros, Guadalupe		need to move the old electrical post and put on the n-side of the athletic fields							
Mario Apodaca									
71793					4/7/2011		13		\$0.00
Medium	Work In Progress			4/7/2011 3:25:02 PM					
Ontiveros, Guadalupe		need to cover/remove lose dirt in areas between new addition to varsit gym and new admin. add pea gravel							
Alfredo Holguin									
71795	Varsity Gym	Dressing Room			4/7/2011		13		\$0.00
Medium	Work In Progress			4/7/2011 3:28:07 PM					
Herrera, Joel		Girl locker room on northwest corner of gym- repair and paint ceiling and walls remove tile and paint with epoxy paint							
Alfredo Holguin									
71798	Pool Pump	Pump House			4/7/2011		13		\$0.00
Medium	Work In Progress			4/7/2011 3:39:50 PM					
Castillo, Carlos		Need to meet with general contractors regarding undersized electrical system for irrigation and fire suppression system.							
Carlos Castillo									
71808	Academic Bldg				4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 7:39:25 AM					
Gonzalez, Salvador		please set up a chain between the academic and buissness building. the sidewalk has become a road and safety hazard.thank you							
Michael Munoz									
71824	Academic Bldg	Mechanical			4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 10:45:38 AM					
Appelzoller, Fred		need a new pvc female adapter and plug outside the academic bldg by the mech/room							
Mario Apodaca									
71826	North Building	Parking Lot			4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 10:55:39 AM					
Apodaca, Mario		need a to put a chain by the flagpoles							
Mario Apodaca									
71827	Library	Office			4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 11:03:21 AM					
Apodaca, Mario		need to put -up poles by the new fire hydrant							
Mario Apodaca									
4/20/2011 11:58:49 AM									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
71846	Football Stadium	Athletic Field			4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 2:53:11 PM					
Ontiveros, Guadalupe	As per Mr. Chambers, please sweep the football field on a weekly basis.								
<b>Cathy Ramos</b>									
71871					4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 4:15:18 PM					
Herrera, Joel	Leadership Request Baseball & Softball dugouts graffiti - please paint. Needs to be completed within 30 days.		Leadership Request						
<b>Richard Chavez</b>									
71898					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:31 AM					
Munoz, Joe	Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.								
<b>Jesus Estrada</b>									
71916	Academic Bldg				4/11/2011		9		\$0.00
High	Work In Progress			4/11/2011 7:30:37 AM					
Villalobos, David	clean out is missing a plug, need to install one for a 4" dwv pipe. area is just south of the mechanical room in the academic building, thank you								
<b>Michael Munoz</b>									
71918	Cafeteria (1998)				4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 7:49:31 AM					
Ontiveros, Guadalupe	entrance and canopy area , the leaves need to be raked and picked-up. also could the shrubs,trees be trimmed as well. power wash. please see mike for details.thankyou								
<b>Michael Munoz</b>									
71926	Academic Bldg				4/11/2011		9		\$0.00
High	Work In Progress			4/11/2011 8:29:00 AM					
Ontiveros, Joe	sewer bcked up this weekend 4-09-11 on the academic building. thank you fo r responding.								
<b>Joe Munoz</b>									
71932	Pool Pump	Pool			4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:37:35 AM					
Sanchez, Raul	4/11/11 Pool Start-up Project,to be done by water/wastwater tech,helpers & plumber								
<b>Raul Sanchez</b>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
72001	Vocational	Classroom			4/12/2011		8		\$0.00
Medium	Work In Progress			4/12/2011 12:17:12 PM					
Apodaca, Mario		need to pick-up and delivered tables to santa teresa m.s for the art exhibit . set-up 4/28/11 and pick-up 5/02/11							
<u>Mario Apodaca</u>									
72072					4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 12:14:19 AM					
Sanchez, Raul		Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
72129	North Building				4/15/2011		5		\$0.00
Medium	Work In Progress			4/15/2011 7:34:03 AM					
Castillo, Carlos		in the entrances to the G,H,S wings there is a recessed light. if they are not needed please remove and cap off , if not please repair.thank you							
<u>Michael Munoz</u>									
72166	North Building	Office			4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 9:28:30 AM					
Ambriz, Jose		need a new a/c unit for the n-bldg office							
<u>Mario Apodaca</u>									
72174	Agricultural	Office			4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 12:02:50 PM					
Lara, Ralph		the key to office was left inside and lock-up need to unlock the office at academic bldg							
<u>Mario Apodaca</u>									
72184					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 3:20:52 PM					
Ambriz, Jose		FLOWERS SHOP - UNIT IS NOT WORKING GOOD							
<u>Joel Herrera</u>									
72286		Athletic Field			4/20/2011		0		\$0.00
Medium	Work In Progress			4/20/2011 8:27:45 AM					
Gonzalez, Salvador		we need two ranchers gates at baseball and softball fields to control traffic.							
<u>Guadalupe Ontiveros</u>									
<b>Count: 113 Work Orders</b>		<b>Avg. Age of WO's 69</b>		<b>Total for Gadsden HS</b>			<b>0</b>	<b>\$0.00</b>	

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
70250					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:43 AM					
Orozco, Danny	Yearly - Gadsden MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66088					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:23					
Orozco, Danny	Monthly - Gadsden MS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67265					12/5/2010		136		\$0.00
Medium	Work In Progress			12/5/2010 12:27:27 AM					
Sanchez, Raul	Monthly - Gadsden MS - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67823					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:39 AM					
Villalobos, David	Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68224		Classroom			1/11/2011		91		\$0.00
Medium	Work In Progress	B		1/11/2011 10:27:04 AM		4/12/2011			
Lozoya, Manny	Need spare key WA-15 for room 121 ok'd by Dr. G								
<u>Maricruz Carrasco</u>									
68407					1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 12:23:45 AM					
Sanchez, Raul	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68430	Gym	Gym			1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 10:48:50 AM					
Estrada, Jesus	(PROJECT) Paint mascot on Gym floor							Leadership Request	
<u>Alfredo Holguin</u>									
68432					1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 10:58:30 AM					
Ontiveros, Guadalupe	Entire Campus around and in between all buildings. - level all ruts and bumps - backfill against sidewalks - clean out all storm drains.							Leadership Request	
Alfredo Holguin									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden MS</b>							
68435					1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 11:07:31 AM					
Munoz, Michael		Tree Memorial for Benegas - Install plague - check with site leadership council for wording				Leadership Request			
<u>Alfredo Holguin</u>									
68436		Football Field			1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 11:08:44 AM					
Munoz, Michael		(PROJECT)				Leadership Request			
		Purchase and install scoreboard							
<u>Alfredo Holguin</u>									
68943	Annex	Classroom			1/31/2011		79		\$0.00
Medium	Work In Progress	Annex/408/D.		1/31/2011 3:40:51 PM					
Lozoya, Manny		DOOR LOCK WILL NOT LOCK PROPERLY, CANNOT SECURE ROOM.							
<u>Maricruz Carrasco</u>									
68964		Classroom			2/1/2011		78		\$0.00
Medium	Work In Progress	BWING/121/VAL		2/1/2011 8:29:04 AM					
Lozoya, Manny		DOOR WILL NOT UNLOCK - NEED CORE REMOVED AND FIX. EMERGENCY							
<u>Maricruz Carrasco</u>									
68977					2/1/2011		78		\$0.00
Medium	Work In Progress			2/1/2011 1:18:51 PM					
Ontiveros, Guadalupe		Lupe as per our discussion, please remove 2 trees mentioned in the front of the building. Dr.G has given us the green light to do so.thanks							
<u>Michael Munoz</u>									
69164					2/8/2011		71		\$0.00
Medium	Work In Progress			2/8/2011 8:12:11 AM					
Orozco, Danny		Reach-in freezer is down again. The temp. is at 50°.SNP Manager Terry P. 882.2824							
<u>Maritza Gonzalez</u>									
69423					2/14/2011		65		\$0.00
Medium	Work In Progress			2/14/2011 12:26:04 AM					
Sanchez, Raul		Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
69539		Classroom			2/15/2011		64		\$0.00
Medium	Work In Progress	A		2/15/2011 2:54:19 PM					
Lozoya, Manny		DOOR HAS FALLEN AT HINGES NEEDS TO BE REPAIRED. DOOR WILL NOT CLOSE PROPERLY.							
<u>Maricruz Carrasco</u>									
4/20/2011 11:58:49 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
69762	Vocational	Classroom			2/22/2011		57		\$0.00
Medium	Work In Progress	vocational/302,3		2/22/2011 11:29:16 AM					
Lozoya, Manny	PLEASE CLEAN AND SPRAY CORE (KEY LOCK CORE) HARD TO UNLOCK AND LOCK. VOCATIONAL ROOMS 302, 303, 304, & 305.								
<u>Maricruz Carrasco</u>									
69863		Custodial			2/24/2011		55		\$0.00
Medium	Work In Progress	Awing Custodial		2/24/2011 8:50:44 AM					
Lozoya, Manny	Lock on door hard to open. Please fix.								
<u>Maricruz Carrasco</u>									
69910					2/24/2011		55		\$0.00
Medium	Work In Progress			2/24/2011 3:47:34 PM					
Solis, Lorenzo	In Cafeteria water fountain not work need to check thank you								
<u>Sebastian Diaz</u>									
70458	Gymnasium	Gym			3/8/2011		43		\$0.00
Medium	Work In Progress	GYM LOBBY		3/8/2011 2:07:50 PM					
Lozoya, Manny	NEED TO REPLACE/REPAIR DOOR HINGES ON DOORS BROKEN.								
<u>Maricruz Carrasco</u>									
70541	Gym	Gym			3/9/2011		42		\$0.00
Medium	Work In Progress	GYM FLOOR		3/9/2011 2:41:12 PM					
Diaz, Sebastian	BOTTOM OF THE DOOR NEEDS FLAP TO KEEP DIRT OUT (DOOR LEAD TO FOOTBALL FIELD FROM GYM).								
<u>Maricruz Carrasco</u>									
70725					3/14/2011		37		\$0.00
Medium	Work In Progress			3/14/2011 12:15:21 AM					
Sanchez, Raul	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70799					3/16/2011		35		\$0.00
Medium	Work In Progress			3/16/2011 7:42:01 AM					
Solis, Lorenzo	Need to fix water fountain in cafeteria thank you								
<u>Sebastian Diaz</u>									
71018		Athletic Field			3/23/2011		28		\$0.00
Medium	Work In Progress			3/23/2011 10:00:17 AM					
Gonzalez, Salvador	new scoreboard is in for the football field. need to install.see mike for location, thank you								
Michael Munoz									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
71019		Athletic Field			3/23/2011		28		\$0.00
Medium	Work In Progress			3/23/2011 10:21:29 AM					
Sotelo, Enrique	need to provide power to scoreboard when installed in football field.thank you								
<u>Michael Munoz</u>									
71199	Gym				3/29/2011		22		\$0.00
Medium	Work In Progress			3/29/2011 10:11:47 AM					
Solis, Lorenzo	new ice machine will coming in . could you please install when it does.thank you								
<u>Michael Munoz</u>									
71231					3/30/2011		21		\$0.00
Medium	Work In Progress			3/30/2011 8:07:10 AM					
Appelzoller, Fred	Need to check water leak in front annex bldg thank you								
<u>Sebastian Diaz</u>									
71316					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 1:24:36 PM					
Ronquillo, Ruben		Filters 8x39=75 9x39=25	for Ruben						
<u>Sebastian Diaz</u>									
71435					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:54 AM					
Orozco, Danny	Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71556					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:46 AM					
Sanchez, Raul	Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71619					4/4/2011		16		\$0.00
Medium	Work In Progress			4/4/2011 3:35:09 PM					
Appelzoller, Fred	Need to check bad olor in closer B wing thank you								
<u>Sebastian Diaz</u>									
71683					4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 3:47:28 PM					
Gonzalez, Salvador	Need cover plate in A/C in some places thank you								
<u>Sebastian Diaz</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden MS</b>							
71716					4/6/2011		14		\$0.00
Medium	Work In Progress	SANTA		4/6/2011 11:54:15 AM					
Diaz, Sebastian	NEED SEBASTIAN DIAZ-MAINTENANCE TO SET-UP ART DISPLAY (FRAMES) AT SANTA TERESA MIDDLE SCHOOL ON APRIL 28, 2011 (THURSDAY) IN THE MORNING (FIRST THING). SEE MS. JACOBI FOR DETAILS.								
<u>Maricruz Carrasco</u>									
71743					4/6/2011		14		\$0.00
Medium	Work In Progress	SANTA		4/6/2011 3:11:24 PM					
Diaz, Sebastian	NEED SABASTIAN DIAZ(MAINTENANCE) TO TAKE DOWN ART DISPLAYS (FRAMES) AT SANTA TERESA MIDDLE SCHOOL ON MONDAY, MAY 2, 2011. FIRST THING IN THE MORNINING. SEE MS. JACOBI FOR DETAILS.								
<u>Maricruz Carrasco</u>									
71769		Athletic Field			4/7/2011		13		\$0.00
Medium	Work In Progress			4/7/2011 8:04:19 AM					
Ontiveros, Guadalupe	please adjust sprinklers on the football field, the track is getting watered as well. thank you								
<u>Guadalupe Ontiveros</u>									
71828					4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 11:32:51 AM					
Diaz, Sebastian	Need 10 plastic cover in annex lights thank you								
<u>Sebastian Diaz</u>									
71945	Gym	Gym			4/11/2011		9		\$0.00
Medium	Work In Progress	Gym Basketball		4/11/2011 10:24:14 AM					
Gonzalez, Salvador	Basketball storage cage needs to be welded. Bar on basket is missing.								
<u>Maricruz Carrasco</u>									
71947	Annex				4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 10:53:17 AM					
Solis, Lorenzo	Need part for Trane Unit in annex bldg thank you								
<u>Sebastian Diaz</u>									
71953	Main Building	Hallway/Corridor			4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 11:19:12 AM					
Lozoya, Manny	B.WING WEST OUTSIDE EXIT DOORS RIM CYLINDER NEED CLEANING								
<u>Juan Acosta</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
71954	Annex				4/11/2011		9		\$0.00
Medium	Work In Progress	Annex building		4/11/2011 11:21:38 AM					
Lozoya, Manny Annex building outside emergency door button not working for disabled students. Please fix as soon as possible for our disabled students.									
<u>Maricruz Carrasco</u>									
71955	Gymnasium	Hallway/Corridor			4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 11:23:54 AM					
Lozoya, Manny GYM LOBBY OUTSIDE EXIT DOORS RIM CYLINDER NEED CLEANING									
<u>Juan Acosta</u>									
72073					4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 12:14:20 AM					
Sanchez, Raul Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>									
72145	C-Wing	Portables			4/15/2011		5		\$0.00
Medium	Work In Progress	TRANSPORTAT		4/15/2011 2:52:38 PM					
Diaz, Sebastian AS PER MARY GARCIA-AIR UNIT IN THE TRANSPORTATION OFFICE IS MAKING A LOUD NOISE. (AS IF IT'S GOING TO FLY AWAY, WHEN TURNING IT ON)									
<u>Mary Garcia</u>									
72150					4/15/2011		5		\$0.00
Medium	Work In Progress			4/15/2011 3:37:12 PM					
Appelzoller, Fred In B wing rest urinal water not stop water thank you									
<u>Sebastian Diaz</u>									
72167	C-Wing				4/18/2011		2		\$0.00
Medium	Work In Progress	CHARTER		4/18/2011 9:49:07 AM					
Lozoya, Manny Charter School - We had a break-in the building. Can we please have the front entry door and the Director's door locks changed. Can you also provide 3 keys to these new locks.									
<u>Melenie Beegle</u>									
72168	C-Wing				4/18/2011		2		\$0.00
Medium	Work In Progress	CHARTER		4/18/2011 9:53:23 AM					
Diaz, Sebastian Charter School - Two conditioners in the left back classroom need cleaned and to fix the vibration									
Melenie Beegle									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location: Gadsden MS</b>										
72182	Band Room				4/18/2011		2		\$0.00	
Medium	Work In Progress	Band		4/18/2011 3:07:46 PM						
Lozoya, Manny	NEED EXTRA BIN KEY (2) FOR BAND ROOM EQUIPMENT. SEE MR. CHACON FOR KEY.									
<b>Maricruz Carrasco</b>										
72200	Annex	Restroom (Girls)			4/18/2011		2		\$0.00	
Medium	Work In Progress	Annex/Girls		4/18/2011 4:21:37 PM						
Appelzoller, Fred	Commode is leaking a lot of water at the flushing valve every time it is flushed. Needs to be repaired ASAP. Thank you!									
<b>Maricruz Carrasco</b>										
72217	C-Wing				4/19/2011		1		\$0.00	
Medium	Work In Progress	CHARTER		4/19/2011 8:42:55 AM						
Lozoya, Manny	CHARTER SCHOOL 1. Change the 2 back exit door locks to match the new entry door lock. 2. A replacement lock for the exterior gate with a key that matches the classroom keys.									
<b>Melenie Beegle</b>										
<b>Count: 49 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>43</b>	<b>Total for Gadsden MS</b>			<b>0</b>	<b>\$0.00</b>	

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>La Union - JTP Alvarez Farms</b>							
72273					4/20/2011		0		\$0.00
Medium	Work In Progress				4/20/2011 7:30:33 AM				
Aguilar, Patricio	PLEASE CHECK AIR CONDITIONER AT LA UNTION JTP SEE ROBERT SAAVEDRA								
Margaret Villalobos									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>			<b>Total for La Union - JTP Alvarez Farms</b>		<b>0</b>		<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>La Union ES</b>							
60989					7/14/2010		280		\$0.00
Medium	Work In Progress			7/14/2010 1:44:37 PM					
Ontiveros, Guadalupe	canal levee brock - now walking path is under 4" of dirt - need to have tracker dig it out - thank you								
Patricio Aguilar									
62217					8/10/2010		253		\$0.00
Medium	Work In Progress			8/10/2010 8:54:51 AM					
Sanchez, Raul	the air pump to the well tank is not working - dead								
Patricio Aguilar									
64314					9/23/2010		209		\$0.00
Medium	Work In Progress			9/23/2010 3:13:04 PM					
Flores, Pete	the differential is making a bad noise - need repair or replace allso need wipers - oil change								
Patricio Aguilar									
65723					10/21/2010		181		\$0.00
Medium	Work In Progress			10/21/2010 1:31:55 PM					
Castillo, Carlos	need 2 wall mounted multiple elect outlets bar r100								
Patricio Aguilar									
66089					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:24					
Orozco, Danny	Monthly - La Union ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
66525	Main Building	Classroom			11/10/2010		161		\$0.00
Medium	Work In Progress			11/10/2010 6:48:52 AM					
Villalobos, David	Talked to Mr. Rapanut about a sink in the parenty room 104, they would like to have one there. the hook ups are there, all it needs is the sink and faucet.								
Santos Galindo									
66626					11/15/2010		156		\$0.00
Medium	Work In Progress			11/15/2010 3:12:17 PM					
Villalobos, David	need a p-trap replaced water founten old hall way								
Patricio Aguilar									
67826					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:40 AM					
Villalobos, David	Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
4/20/2011 11:58:49 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>La Union ES</b>							
68969		Cafeteria			2/1/2011		78		\$0.00
Medium	Work In Progress			2/1/2011 8:46:16 AM					
Orozco, Danny	ONE OF THE OVENS IS DOWN. SNP MANAGER LINDA Y. 589.2040								
<u>Maritza Gonzalez</u>									
69977					2/28/2011		51		\$0.00
Medium	Work In Progress			2/28/2011 12:25:17 AM					
Aguilar, Patricio	Monthly - La Union ES A-16 Fan Exhaust Semimonthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70241					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:39 AM					
Orozco, Danny	Yearly - La Union ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70603					3/10/2011		1	10	\$400.00
Medium	Work In Progress			3/10/2011 12:57:27 PM		3/11/2011			
Villalobos, David	winter storm repair 3 copper lines out to building faucets need repair - copper line to play ground water fountner need repair		Work Still Pending will need to reconnect piping to outside hosebibbs, find exact cutoff locations and leaks.						
<u>Patricio Aguilar</u>									
71436					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:54 AM					
Orozco, Danny	Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71735		Athletic Field			4/6/2011		14		\$0.00
High	Work In Progress			4/6/2011 2:34:38 PM					
Villalobos, David	please provide water to the fields in the back with irrigation system.please see mike ion this work order.thank you								
<u>Alfredo Holguin</u>									
71914					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:40 AM					
Galindo, Santos	Monthly - QRTLY BLDG INSP REPORT (LU) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
72209	Main Building	Parking Lot			4/19/2011		1		\$0.00
Medium	Work In Progress			4/19/2011 7:25:57 AM					
Carbajal, Jimmy	Requesting blower because mine is giving out I asked Mr. Estrada and he oked it.								
<u>Santos Galindo</u>									
4/20/2011 11:58:49 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

Count: 16 Work Orders	Avg. Age of WO's	109	Total for La Union ES	10	\$400.00
-----------------------	------------------	-----	-----------------------	----	----------

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Loma Linda ES</b>									
60602					7/4/2010	7/25/2010	290		\$0.00
Medium	Work In Progress			7/4/2010 12:23:44 AM					
Orozco, Danny			Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.						
<u>Margret Villalobos</u>									
60892					7/12/2010		282		\$0.00
Medium	Work In Progress			7/12/2010 6:13:58 AM					
Flores, Pete			Need tractor to clean pathways and washed out rain paths.						
<u>Rudy Arreola</u>									
62846		Athletic Field			8/24/2010		239		\$0.00
High	Work In Progress			8/24/2010 10:53:22 AM					
Munoz, Michael			please install a fence on the north end of campus where desert begins. this is a safty issue as per mr.lawler.						
<u>Alfredo Holguin</u>									
63055	Main Building	Athletic Field			8/27/2010		236		\$0.00
Medium	Work In Progress			8/27/2010 1:02:33 PM					
Ontiveros, Guadalupe			Possible to reseed area that was torn up by by the installation of new sidewalks.						
<u>Rudy Arreola</u>									
63296	Main Building	Classroom			9/1/2010		231		\$0.00
Medium	Work In Progress	101		9/1/2010 1:00:28 PM					
Arreola, Rudy			Blinds behind teachers desk not working. The cords are frayed and the blinds wont go up or down.						
<u>Gidget Mora</u>									
64208	Main Building				9/21/2010		211		\$0.00
Medium	Work In Progress			9/21/2010 3:05:39 PM					
Sanchez, Raul			Grease trap is caving in and has broken parts where filters go.						
<u>Rudy Arreola</u>									
64743					10/3/2010	10/24/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:27:00 AM					
Orozco, Danny			Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.						
<u>Margret Villalobos</u>									
65095	Main Building	Classroom			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 2:41:32 PM					
Solis, Lorenzo			A/C needs to be replaced rusted out really bad.RM 101						
<u>Rudy Arreola</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
65096	Main Building	Classroom			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 2:42:17 PM					
Solis, Lorenzo		A/C needs to be replaced rusted out. RM 103							
Rudy Arreola									
65097	Main Building	Classroom			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 2:43:18 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced. RM 108							
Rudy Arreola									
65098	Main Building	Classroom			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 2:44:03 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced. RM 110							
Rudy Arreola									
65099	Main Building	Classroom			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 2:45:02 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced. RM 111							
Rudy Arreola									
65100	Main Building	Classroom			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 2:45:45 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced. RM 112							
Rudy Arreola									
65101	Main Building	Classroom			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 2:46:40 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced. RM 118							
Rudy Arreola									
65102	Main Building	Classroom			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 2:47:39 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced. RM 201							
Rudy Arreola									
65103	Main Building	Classroom			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 2:48:34 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced. Rm 206							
Rudy Arreola									
65104	Main Building	Classroom			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 2:49:16 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced. RM 212							
Rudy Arreola									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
65105	Main Building	Office			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 2:56:25 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced. Teachers lounge 308							
Rudy Arreola									
65106	Main Building	Office			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 3:01:05 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced RM 312							
Rudy Arreola									
65107	Main Building	Classroom			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 3:02:13 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced NURSES OFFICE. 313							
Rudy Arreola									
65108	Main Building	Office			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 3:03:40 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced front office.							
Rudy Arreola									
65110	Main Building	Office			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 3:07:08 PM					
Solis, Lorenzo		A/C is rusted out needs to be replaced principals offices							
Rudy Arreola									
65346	Main Building	Classroom			10/13/2010		189		\$0.00
Medium	Work In Progress	109		10/13/2010 8:59:54 AM					
Arreola, Rudy		Window blinds not working in room 109							
Gidget Mora									
66090					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:24					
Orozco, Danny		Monthly - Loma Linda ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
67824					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:39 AM					
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
67840					1/2/2011	1/23/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:45 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68072	Main Building	Classroom			1/7/2011		103		\$0.00
Medium	Work In Progress	212		1/7/2011 10:37:56 AM					
Arreola, Rudy	BLINDS IN CLASSROOM NEED TO BE FIXED								
<u>Gidget Mora</u>									
68463	Main Building	Restroom (Girls)			1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 3:16:53 PM					
Appelzoller, Fred	TOILET IS LEAKING WATER FROM ANGLE STOP AND FLUSHVALVE. WOMENS RESTROOM RIGHT ACROSS TEACHERS LOUNGE. CLOSED WATER SUPPLY								
<u>Rudy Arreola</u>									
68700	Main Building	Classroom			1/24/2011		86		\$0.00
Medium	Work In Progress			1/24/2011 3:17:29 PM					
Appelzoller, Fred	NEED TO REPLACED WATER HEATER IN ROOM 208 SLOW LEAK.								
<u>Rudy Arreola</u>									
68820	Main Building	Portables			1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 8:28:00 AM					
Lozoya, Manny	DOOR IS DRAGGING AND IS NOT LATCHING HARD TO CLOSE. PORTABLE #3								
<u>Rudy Arreola</u>									
69314	Main Building	Mechanical			2/10/2011		69		\$0.00
Medium	Work In Progress			2/10/2011 8:29:55 AM					
Appelzoller, Fred	MAIN WATER SUPPLY IS LEAKING FROM ELBOW.								
<u>Rudy Arreola</u>									
69316	Main Building	Mechanical			2/10/2011		69		\$0.00
Medium	Work In Progress			2/10/2011 8:31:19 AM					
Appelzoller, Fred	WATER LEAK BACKFLOW IS CRACKED.								
<u>Rudy Arreola</u>									
69318	Main Building	Mechanical			2/10/2011		69		\$0.00
Medium	Work In Progress			2/10/2011 8:34:18 AM					
Appelzoller, Fred	WATER HEATER IN MECHANICAL ROOM IS LEAKING.								
<u>Rudy Arreola</u>									
4/20/2011 11:58:49 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
69319	Main Building	Cafeteria			2/10/2011		69		\$0.00
Medium	Work In Progress			2/10/2011 8:35:29 AM					
Solis, Lorenzo		HEATING COIL IS LEAKING WATER,							
Rudy Arreola									
69322	Main Building	Portables			2/10/2011		69		\$0.00
Medium	Work In Progress			2/10/2011 8:39:00 AM					
Appelzoller, Fred		WATER LEAK IN WALL IN DOUBLE PORTABLE BATHROOM							
Rudy Arreola									
69341	Main Building	Mechanical			2/10/2011		69		\$0.00
Medium	Work In Progress			2/10/2011 3:01:58 PM					
Sanchez, Raul		WATER FILTERING SYSTEM ALSO HAS A WATER LEAK.							
Rudy Arreola									
69582	Main Building	Cafeteria			2/16/2011		63		\$0.00
Medium	Work In Progress			2/16/2011 9:36:51 AM					
Estrada, Jesus		TILES ARE LIFTING AND NEED TO BE REPLACED IN KITCHEN & LAUNDRY AREA. SAFETY ISSUE SNP MANAGER FRANCES B.882-4707.				P.O. RECIEVED. SUBMITTED REVISED REQUEST AS OF 3/30/11			
Jesus Estrada		AS OF 3/30/11 - REVISED / NEED TO ADD RESTROOM AND MANGAGERS OFFICE BUT DO NOT INCLUDE DISHWASHING AREA .							
69617					2/16/2011		63		\$0.00
Medium	Work In Progress			2/16/2011 4:03:24 PM					
Appelzoller, Fred		please replace backflow we have in stock in the mechanical room for irrigation.thank you							
Joe Munoz									
69636	Main Building	Restroom (Boys)			2/17/2011		62		\$0.00
Medium	Work In Progress			2/17/2011 9:06:15 AM					
Solis, Lorenzo		NEED TO REPLACE ENTIRE EXHAUST FAN COVER HAS HOLES SIZE IS 22X22 DUCT COVER.							
Rudy Arreola									
69881	Main Building	Classroom			2/24/2011		55		\$0.00
Medium	Work In Progress	201		2/24/2011 10:37:47 AM					
Arreola, Rudy		Repair or replace blinds							
Gidget Mora									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
70242					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:39 AM					
Orozco, Danny	Yearly - Loma Linda ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70626	Main Building	Classroom			3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:25:51 PM					
Arreola, Rudy	Need to paint old conference room								
<u>Rudy Arreola</u>									
70828	Main Building				3/16/2011		35		\$0.00
Medium	Work In Progress			3/16/2011 2:04:03 PM					
Arreola, Rudy	NEED TO FERTILIZE GRASS AREA. WITH WALK ALONG SPREADER.								
<u>Rudy Arreola</u>									
71151					3/28/2011		23		\$0.00
Medium	Work In Progress			3/28/2011 12:21:38 PM					
Arreola, Rudy	NEED TO DISASSEMBLE FUNITURE IN PORTABLE #1 & 2 BY TOMORROW MORNING. RODRIGUEZ UPHOLSTERY WILL BE THERE TO INSTALL CARPET. O.K. ASP MIKE AND RUDY IS AWARE.								
<u>Jesus Estrada</u>									
71426					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:49 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71437					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:55 AM					
Orozco, Danny	Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71552					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:45 AM					
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71553					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:45 AM					
Arreola, Rudy	Monthly - Loma Linda ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
4/20/2011 11:58:50 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Loma Linda ES

71839	Main Building	Athletic Field			4/8/2011		12		\$0.00
Medium	Work In Progress				4/8/2011 2:28:50 PM				
Ontiveros, Guadalupe	SOLENOID VALVE NEEDS TO BE REPLACED STILL GETTING STUCK.								

Rudy Arreola

71861	Main Building	Mechanical			4/8/2011		12		\$0.00
Medium	Work In Progress				4/8/2011 3:39:45 PM				

Villalobos, David replaced backflow preventer (3/4") to boiler broken during freeze

David Villalobos

71904					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress				4/10/2011 12:14:36 AM				

Solis, Luis Monthly - QRTLY BLDG INSP REPORT (LL) - Refer to PM schedule details.

Jesus Estrada

72013		Cafeteria			4/12/2011		8		\$0.00
Medium	Work In Progress				4/12/2011 2:56:35 PM				

Arreola, Rudy as per our converstaion, please paint the cafeteria kitchen, office, restroom and laundryroom. Thank you

Michael Munoz

72032	Main Building	Auditorium			4/13/2011		7		\$0.00
Medium	Work In Progress				4/13/2011 8:10:38 AM				

Estrada, Jesus WARRANTY. CARPET NEEDS TO BE REPAIRED COMING UNDONE ALONG FRONT OF STAGE BEFORE IT GETS WORST AND RIPS MORE. CARPET WAS JUST INSTALLED ABOUT JAN.WARRANTY.

Rudy Arreola

72089					4/14/2011		6		\$0.00
Medium	Work In Progress				4/14/2011 11:07:19 AM				

Briones, Enrique On April 20, 2011, please deliver 4 boxes to Loma Linda Elementary. Reference P.O. # 101106804.

Yolie Jacquez

72135		Hallway/Corridor			4/15/2011		5		\$0.00
Medium	Work In Progress				4/15/2011 12:24:57 PM				

Estrada, Jesus TILE IN HALLS UNDER THE DOUBLE WATER FOUNTAINS NEEDS TO BE REPLACED. 3 SECTIONS.

Rudy Arreola

4/20/2011 11:58:50 AM

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Loma Linda ES

72136	Main Building	Office			4/15/2011		5		\$0.00
Medium	Work In Progress				4/15/2011 12:26:23 PM				

Estrada, Jesus  
CARPET IN THE MAIN ENTRANCE TO OFFICE  
NEEDS TO BE REPAIRED OR GLUED.

Rudy Arreola

72137	Main Building	Classroom			4/15/2011		5		\$0.00
Medium	Work In Progress				4/15/2011 12:29:00 PM				

Estrada, Jesus  
CARPET IN ROOM 220 THE SEAM THAT SEPARTES  
CARPET AND TILE IS DAMAGED.

Rudy Arreola

72141	Main Building	Athletic Field			4/15/2011		5		\$0.00
Medium	Work In Progress				4/15/2011 2:19:57 PM				

Munoz, Michael  
NEED FENCE INSTALLED ON THE NORTHSIDE OF  
CAMPUS THAT SEPARTES CAMPUS FROM  
DESSERT AREA IT EXTENDS FROM EAST TO  
WEST.

Rudy Arreola

72149	Main Building	Classroom			4/15/2011		5		\$0.00
Medium	Work In Progress				4/15/2011 3:29:34 PM				

Ronquillo, Ruben  
Window needs to be replaced in room 114. BREAK IN.  
(Computers were stolen)  
Case# 201103981

Rudy Arreola

72224	Main Building	Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress	213			4/19/2011 10:13:31 AM				

Arreola, Rudy  
Air conditioner is not blowing out any cool air

Gidget Mora

72225	Main Building	Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress	107			4/19/2011 10:15:58 AM				

Arreola, Rudy  
Air conditioner is not blowing cool air

Gidget Mora

72226	Main Building	Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress	213			4/19/2011 10:17:57 AM				

Arreola, Rudy  
2-3 lights out

Gidget Mora

72227	Main Building	Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress	220			4/19/2011 10:19:42 AM				

Arreola, Rudy  
A/C not working

Gidget Mora

4/20/2011 11:58:50 AM

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
72228	Main Building	Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress	220		4/19/2011 10:20:40 AM					
Arreola, Rudy		Black carpet strip coming off							
Gidget Mora									
72229	Main Building	Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress	201		4/19/2011 10:22:07 AM					
Arreola, Rudy		Air conditioner is not cooling. Blowing hot air.							
Gidget Mora									
72230	Main Building	Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress	202		4/19/2011 10:26:49 AM					
Arreola, Rudy		Air conditioner is not cooling. Blowing hot air.							
Gidget Mora									
72231	Main Building	Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress	203		4/19/2011 10:27:33 AM					
Arreola, Rudy		Air conditioner is not cooling. Blowing hot air.							
Gidget Mora									
<b>Count: 67 Work Orders</b>		<b>Avg. Age of WO's 97</b>		<b>Total for Loma Linda ES</b>				<b>0</b>	<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Mesquite ES</b>									
61265					7/23/2010		271		\$0.00
Medium	Work In Progress			7/23/2010 8:42:38 AM					
Lozoya, Manny	principal is requesting that locks be installed on southside staff bathrooms.								
<u>Joe Ramirez</u>									
61764					8/3/2010		260		\$0.00
Medium	Work In Progress			8/3/2010 12:34:24 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
65094		Athletic Field			10/7/2010		195		\$0.00
Medium	Work In Progress			10/7/2010 1:42:39 PM					
Ramirez, Joe	please clean up along fence line on the back parking lot to include the pile of dirt by handi cap parking as well. also cut weeds and grass along sidewalk around enviromental park.thank you								
<u>Michael Munoz</u>									
65221					10/11/2010		191		\$0.00
Medium	Work In Progress			10/11/2010 11:32:16					
Ramirez, Joe	please trim grass and cut weeds along sidewalk on the exterior of enviromental park.thanks								
<u>Michael Munoz</u>									
65455	Main Building				10/15/2010		187		\$0.00
Medium	Work In Progress	Staff Bathroom		10/15/2010 8:27:22 AM					
Lozoya, Manny	Mr. Van Nosdale/Principal needs dead bolt lock place on Men/Women Bathroom located in main hallway next to lounge, for staff privacy when using bathrooms.								
<u>Sandra Mora</u>									
66091					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:24					
Orozco, Danny	Monthly - Mesquite ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66943					11/30/2010		141		\$0.00
Medium	Work In Progress			11/30/2010 12:25:58					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Mesquite ES</b>									
67269					12/5/2010		136		\$0.00
Medium	Work In Progress			12/5/2010 12:27:29 AM					
Sanchez, Raul	Monthly - Mesquite ES - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67433					12/9/2010		132		\$0.00
Medium	Work In Progress			12/9/2010 9:55:49 AM					
Gonzalez, Salvador	as per mr. moreno,asst principal eastside entrance gate needs to be repaired or replaced.								
<u>Joe Ramirez</u>									
67827					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:40 AM					
Villalobos, David	Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67903					1/2/2011	1/10/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:29:18 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67956					1/4/2011		106		\$0.00
Medium	Work In Progress			1/4/2011 12:24:41 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68000					1/6/2011		104		\$0.00
Medium	Work In Progress			1/6/2011 9:21:44 AM					
Orozco, Danny	TOP OVEN ON RIGHT SIDE OF CAFETERIA NOT HEATING. SNP MANAGER ALICE F.233.2341								
<u>Maritza Gonzalez</u>									
69754	Main Building				2/22/2011		57		\$0.00
Medium	Work In Progress			2/22/2011 9:50:06 AM					
Lozoya, Manny	Book room needs to have a file cabinet re key.								
<u>Sandra Mora</u>									
70023					3/1/2011		50		\$0.00
Medium	Work In Progress			3/1/2011 12:18:21 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

4/20/2011 11:58:50 AM



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
70243					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:40 AM					
Orozco, Danny	Yearly - Mesquite ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70391	Restrooms				3/7/2011		44		\$0.00
Medium	Work In Progress			3/7/2011 7:51:02 AM					
Ontiveros, Joe	please replace wash basin in restrooms in the corridore between office area and caferteis								
<u>Michael Munoz</u>									
70392	Restrooms				3/7/2011		44		\$0.00
Medium	Work In Progress			3/7/2011 7:52:51 AM					
Lozoya, Manny	please replace partitions in restrooms in corridore between office area and administration								
<u>Michael Munoz</u>									
70728					3/14/2011		37		\$0.00
Medium	Work In Progress			3/14/2011 7:43:50 AM					
Villalobos, David	back flow preventor by the pump house has a busted union needs to be replaced								
<u>Joe Ramirez</u>									
71238	Main Building	Office			3/30/2011		21		\$0.00
Medium	Work In Progress	Nurses Office		3/30/2011 10:08:59 AM					
Lozoya, Manny	Linda Contreras/Nurse needs to have her front door of office re key and lock.								
<u>Sandra Mora</u>									
71239	Main Building	Office			3/30/2011		21		\$0.00
Medium	Work In Progress	Main Office		3/30/2011 10:10:28 AM					
Lozoya, Manny	As per Mr. Moreno/Assistant Principal please have office front door re key and lock.								
<u>Sandra Mora</u>									
71285					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 12:17:33 AM					
Ramirez, Joe	Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71286					3/31/2011	5/1/2011	20		\$0.00
Medium	Work In Progress			3/31/2011 12:17:33 AM					
Ramirez, Joe	Yearly - Mesquite ES A-8 A/C Window Unit Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

4/20/2011 11:58:50 AM

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
71438					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:55 AM					
Orozco, Danny	Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71516					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:29 AM					
Ramirez, Joe	Monthly - Mesquite ES - Barrack Drainage (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71517					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:30 AM					
Ramirez, Joe	Monthly - Mesquite ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71518					4/3/2011	4/19/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:30 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71519					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:31 AM					
Ramirez, Joe	Yearly - Mesquite ES A-13 A/C Wall Mount Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71520					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:31 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71521					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:32 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71522					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:32 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

4/20/2011 11:58:50 AM

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
71523					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:32 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71632					4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 12:15:00 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71912					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:39 AM					
Saucedo, Luis	Monthly - QRTLY BLDG INSP REPORT (MQ) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
71924					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:27:56 AM					
Gonzalez, Salvador	need to install security bars on windows in rm.505 front and back.								
<u>Joe Ramirez</u>									
71925					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:28:51 AM					
Gonzalez, Salvador	need to install security bars on windows in rm.506								
<u>Joe Ramirez</u>									
71928					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:29:44 AM					
Gonzalez, Salvador	need to install security bars on windows in rm.602.								
<u>Joe Ramirez</u>									
71929					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:31:01 AM					
Gonzalez, Salvador	need to install security bars on windows in rm.606. front and back								
<u>Joe Ramirez</u>									
71930					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:33:18 AM					
Gonzalez, Salvador	need to install security bars on windows in rm.606 front and back.								
<u>Joe Ramirez</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Mesquite ES</b>									
71931					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:34:31 AM					
Gonzalez, Salvador	need to install security bars on windows in rm.607 front and back.								
Joe Ramirez									
71933					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:38:22 AM					
Lozoya, Manny	door lock in rm.506 not working needs to be repaired.								
Joe Ramirez									
71935					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:42:00 AM					
Lozoya, Manny	need to install safety door latch guard in rm.602.								
Joe Ramirez									
72051					4/13/2011		7		\$0.00
Medium	Work In Progress			4/13/2011 2:27:01 PM					
Ontiveros, Joe	need to isolate broken water lines inside the wall due to winter freeze								
Joe Ramirez									
72117					4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 3:49:50 PM					
Gonzalez, Salvador	need a ladder from the main roof to the library roof								
Joe Ramirez									
72138					4/15/2011		5		\$0.00
Medium	Work In Progress			4/15/2011 12:52:50 PM					
Estrada, Jesus	rm. 300 whole floor needs to be retiled.								
Joe Ramirez									
72178					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 1:55:52 PM					
Ronquillo, Ruben	skylight in cafe. dining area needs to be replaced								
Joe Ramirez									
72233	Main Building				4/19/2011		1		\$0.00
Medium	Work In Progress	Main Office		4/19/2011 11:13:05 AM					
Lozoya, Manny	Principal Mr. Van Nosedale request that lock in storage room be change to new key and lock and valt needs to be changes to different number also.								
Sandra Mora									
<b>Count: 47 Work Orders</b>			<b>Avg. Age of WO's 58</b>				<b>Total for Mesquite ES</b>	<b>0</b>	<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>North Valley ES</b>							
66093					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:25					
Orozco, Danny	Monthly - North Valley ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67075					12/2/2010		139		\$0.00
Medium	Work In Progress			12/2/2010 10:39:18 AM					
Ronquillo, Ruben	NEED A HAMMER DRILL /so i can make holes in pavement for some sign post/ attention ruben ronquillo								
<u>Danny Vega</u>									
67080					12/2/2010		139		\$0.00
Medium	Work In Progress			12/2/2010 10:56:08 AM					
Sotelo, Enrique	need replacement lamp cover for dome type exterior lamps/12 in. diamiter(round cover)								
<u>Danny Vega</u>									
67813					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:35 AM					
Villalobos, David	Yearly - North Valley ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68784					1/26/2011		84		\$0.00
Medium	Work In Progress			1/26/2011 9:45:52 AM					
Ontiveros, Joe	need angle stops replaced in mens /ladies restrooms /rio grand wing								
<u>Danny Vega</u>									
69215					2/8/2011		71		\$0.00
Medium	Work In Progress			2/8/2011 3:52:41 PM					
Solis, Lorenzo	rtu south side busted 1 1/2 water line /water turned off								
<u>Danny Vega</u>									
69267					2/9/2011		70		\$0.00
Medium	Work In Progress			2/9/2011 12:34:29 PM					
Orozco, Danny	Washing machine main water line broke. SNP Manager Laura B.								
<u>Maritza Gonzalez</u>									
69519		Parking Lot			2/15/2011		64		\$0.00
Medium	Work In Progress			2/15/2011 11:07:53 AM					
Villalobos, David	broken bypass on backflow preventer				Asp Mike, route to David 4/14/11				
Fred Appelzoller									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>North Valley ES</b>							
69857					2/24/2011		55		\$0.00
Medium	Work In Progress			2/24/2011 8:08:53 AM					
Ontiveros, Joe	pecan valley wing bys restrooms /sink faucet needs replaced /plus angle stops and supply lines /no more adjustments on this - water will not stop								
<u>Danny Vega</u>									
70147					3/3/2011		48		\$0.00
Medium	Work In Progress			3/3/2011 11:58:52 AM					
Ontiveros, Joe	exterior water fountains/need to replace screen cartrige as it cracked during winter freeze/3/8 copper line to 1/4 poly.please repair these are the only two outside fountains we have(storm day)								
<u>Danny Vega</u>									
70244					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:40 AM					
Orozco, Danny	Yearly - North Valley ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70632					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:29:48 PM					
Villalobos, David	(back -flow preventer) by -pass wilkins zurn type 180f 175psi 3/4 in. model 975xl needs replaced								
<u>Danny Vega</u>									
70993					3/22/2011		29		\$0.00
Medium	Work In Progress			3/22/2011 7:51:34 AM					
Carrasco, Danny	need 16-8-8 fertilizer 30 sacks for entire campus lawn								
<u>Danny Vega</u>									
71186					3/29/2011		22		\$0.00
Medium	Work In Progress			3/29/2011 7:43:08 AM					
Sotelo, Enrique	need the door buzzerd hooked up in the kithchen door/buzzerd is on door								
<u>Danny Vega</u>									
71202					3/29/2011		22		\$0.00
Medium	Work In Progress			3/29/2011 10:28:18 AM					
Orozco, Danny	BUZZARD TO DOOR NEEDS TO BE FIXED. SNP LAURA B. 233.3658								
<u>Maritza Gonzalez</u>									
71295					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 7:49:15 AM					
Ontiveros, Joe	girls restrms (pecan valley wng)have two sink faucets broken need replaced /supply lines and angle stop also								
<u>Danny Vega</u>									
4/20/2011 11:58:50 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: North Valley ES</b>									
71394					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:33 AM					
Holguin, Alfredo	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71421					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:47 AM					
Orozco, Danny	Monthly - North Valley ES - Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71454					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:02 AM					
Vega, Danny	Monthly - North Valley ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71732					4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 1:25:09 PM					
Vega, Danny	NEED SPRINKLERS REPLACED.								
<u>Adam Montoya</u>									
71777					4/7/2011		13		\$0.00
Medium	Work In Progress			4/7/2011 10:40:21 AM					
Ontiveros, Joe	2 faucets in organ trail wont stop running and 1 in pecan valley wont turn on...								
<u>Javier Parra</u>									
71787					4/7/2011		13		\$0.00
Medium	Work In Progress			4/7/2011 1:01:07 PM					
Munoz, Michael	NEED TWO (2) 3FT X 6 FT GATES DOORS FOR CAMPUS EVACUATION ROUTES ONE AT SOUTH WEST CORNER OF PONDING AREA/THEY OTHER IS BY MARQUEE SIGN								
<u>Danny Vega</u>									
71825					4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 10:47:52 AM					
Vega, Danny	need barricades for traffic control in parent drop -off and front entrance								
<u>Danny Vega</u>									
71881					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:24 AM					
Parra, Javier	Monthly - QRTLY BLDG INSP REPORT (NV) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
4/20/2011 11:58:50 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: North Valley ES</b>									
71950					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 11:08:14 AM					
Ontiveros, Joe	sink faucet in bys rr broken /need replaced /no water in this sink had to shut -off./please replace (organ trail wing)								
<u>Danny Vega</u>									
72021					4/12/2011		8		\$0.00
Medium	Work In Progress			4/12/2011 3:34:14 PM					
Villalobos, David	need to check water pressure at backflow test ports with gauges								
<u>Danny Vega</u>									
72177		Classroom			4/18/2011		2		\$0.00
Medium	Work In Progress	District Art Show		4/18/2011 1:35:44 PM					
Vega, Danny	Need to send personnel to set up District Art Show on 4/28 and take down of District Art Show on 5/2.								
<u>Priscilla Martinez</u>									
72276					4/20/2011		0		\$0.00
Medium	Work In Progress			4/20/2011 7:51:10 AM					
Ontiveros, Guadalupe	NEED KABOTA TRACTOR TO REMOVE SAND BLOWN OVER BY WINDS ONTO GRASS/MOST OF SAND IS FROM PLYGRD SAND BOXES AND IS ON GRASS								
<u>Danny Vega</u>									
<b>Count: 28 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>45</b>		<b>Total for North Valley ES</b>	<b>0</b>		<b>\$0.00</b>



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
63741					9/10/2010		222		\$0.00
Medium	Work In Progress			9/10/2010 10:28:46 AM					
Ontiveros, Guadalupe	as per conversation, please remove front hedges and design a small landscaping sceem.thank you								
<u>Michael Munoz</u>									
67268					12/5/2010		136		\$0.00
Medium	Work In Progress			12/5/2010 12:27:28 AM					
Sanchez, Raul	Monthly - Northern Pre-K - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67825					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:39 AM					
Villalobos, David	Yearly - Northern Pre-K Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68782					1/26/2011		84		\$0.00
Medium	Work In Progress			1/26/2011 9:41:38 AM					
Flores, Pete	john deere 125 mower will need new belt and blades at lm pre-k/service for summer use .please thanks								
<u>Danny Vega</u>									
69113					2/6/2011		73		\$0.00
Medium	Work In Progress			2/6/2011 12:34:10 AM					
Sanchez, Raul	Monthly - Northern Pre-K - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69965					2/28/2011	3/11/2011	51		\$0.00
Medium	Work In Progress			2/28/2011 12:25:14 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69966					2/28/2011	3/11/2011	51		\$0.00
Medium	Work In Progress			2/28/2011 12:25:14 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69967					2/28/2011	3/11/2011	51		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Northern On-Track Pre-K (LM)</b>							
69968					2/28/2011	3/11/2011	51		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69969					2/28/2011	3/11/2011	51		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69970					2/28/2011	3/11/2011	51		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69971					2/28/2011	3/11/2011	51		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69972					2/28/2011	3/11/2011	51		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69973					2/28/2011	3/11/2011	51		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70146	Main Building	Classroom			3/3/2011		48		\$0.00
Medium	Work In Progress	101		3/3/2011 11:32:55 AM					
Ontiveros, Joe	Room 101 repair lavatory faucet								
<u>Alfredo Holguin</u>									
70595	Main Building	Office			3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 10:23:30 AM					
Ontiveros, Guadalupe	Remove old shrubs from front of building. Last person that came in to see shrubs said this was a winter project. Currently not done yet.								
<u>Concepcion Montalvo</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
71240					3/30/2011		21		\$0.00
Medium	Work In Progress			3/30/2011 10:53:45 AM					
Estrada, Jesus	ROOM #114 - UNEVEN TILES ARE A TRIP HAZARD. PLEASE MAKE RECOMMENDATION.								
Jesus Estrada									
71324					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 2:36:49 PM					
Munoz, Michael	NEED TO INSTALL 3' WALK THRU GATE BY THE BASKETBALL COURTS								
Michael Munoz									
71354					4/1/2011		19		\$0.00
Medium	Work In Progress			4/1/2011 7:36:32 AM					
Flores, Pete	need diesel fuel for fire protection pump/need to top it off /showing 3/4 full(pump house)								
Danny Vega									
71455					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:03 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
71631					4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 12:14:59 AM					
Sanchez, Raul	Monthly - Northern Pre-K- Domestic Water Filters - Refer to PM schedule details.								
Margret Villalobos									
71715					4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 11:34:26 AM					
Gonzalez, Salvador	build ramp for new morgan bldg/diamond plated								
Danny Vega									
71739					4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 2:51:02 PM					
Lozoya, Manny	NEED NEW LOCK FOR MORGAN BUILDING, NEED CORED TO MASTER KEY.								
Adam Montoya									
71748		Athletic Field			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 3:31:22 PM					
Munoz, Michael	need a gate on northwest corner of campus so children can play on basketball concrete pads. thank you								
Michael Munoz									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
71875					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:21 AM					
Montoya, Adam	Monthly - QRTL Y BLDG INSP REPORT (LM/PRE-K) - Refer to PM schedule details.								
Jesus Estrada									
72070					4/13/2011		7		\$0.00
Medium	Work In Progress			4/13/2011 4:17:23 PM					
Lozoya, Manny	NEED LOCK FOR NEW GATE NEXT TO MORGAN BUILDING.								
Adam Montoya									
<b>Count: 26 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>51</b>	<b>Total for Northern On-Track Pre-K (LM)</b>			<b>0</b>	<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
60767	Maintenance				7/7/2010		287		\$0.00
Medium	Work In Progress				7/7/2010 6:40:24 AM				
Ambriz, Jose	The unit here at the Maintenance Office keeps freezing up and it seems to happen mid day when it's really hot. We had this problem last summer too. Do you think we could have the unit replaced with a Heating/Cooling Unit?								
	PS....It also vibrates a lot.								
<hr/>									
Margret Villalobos					8/13/2010		250		\$0.00
62486					8/13/2010 3:50:09 PM				
Medium	Work In Progress								
Flores, Pete	NEED TO FIX FRONT PASSAGER TIRE IS LOCKOUT AND MAKING KNOCKING BADLY SOUND.								
<hr/>									
Joe Ontiveros					9/22/2010		210		\$0.00
64249					9/22/2010 8:33:53 AM				
Medium	Work In Progress								
Flores, Pete	our ditch with backhoe attachment needs repair the chain drive on it: the chain on it or the gears are wore and the chain is jumping when you select to move it forward or in reverse. we need it fixed asap. need it for some jobs at some school sites. if we continue to use as is we will run into higher repairs on the machine. thank Fred								
<hr/>									
Fred Appelzoller					9/22/2010		210		\$0.00
64255	Food Services				9/22/2010 11:30:35 AM				
Medium	Work In Progress								
Orozco, Danny	FREEZER #3 AND #5: DOOR SEALS NEED TO BE REPLACED. DOORS DON'T SHUT RIGHT. TORN DOOR SEALS.								
	JOHNNY LECHUGA SNP MGR 882-6927								
<hr/>									
Jacqueline Aguilar					10/6/2010		196		\$0.00
65010	Motor Vehicle				10/6/2010 9:46:33 AM				
Medium	Work In Progress								
Appelzoller, Fred	please remove existing compressor and replace with new one. location will change and install will be outside in the metal building.thanks								
Michael Munoz									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Physical Plant Complex</b>							
65725					10/21/2010		181		\$0.00
Medium	Work In Progress			10/21/2010 2:31:05 PM					
Gonzalez, Salvador		10/21/10	Need a welder to install an iron bracket at the wastewater plant to secure the pipe that connects to the static screen. This pipe vibrates too much when the pumps turn off. It may break if it is not supported						
<u>Raul Sanchez</u>									
66231	Maintenance				11/2/2010		169		\$0.00
Medium	Work In Progress			11/2/2010 8:00:06 AM					
Sotelo, Enrique			please provide power to the new compressor to be installed. thank you						
<u>Michael Munoz</u>									
66998					11/30/2010		141		\$0.00
Medium	Work In Progress			11/30/2010 4:11:27 PM					
Perez, Raul			Mail Van # 11 - Seats need to be upholstered. Remove and do the passenger side first. then remove driver side and replace with passenger side and do the driver side and install on passenger side if necessary.						
<u>Alfredo Holguin</u>									
66999					11/30/2010		141		\$0.00
Medium	Work In Progress			11/30/2010 4:16:27 PM					
Flores, Pete			Van # 23 - Needs to be serviced.						
<u>Manny Lozoya</u>									
67015					12/1/2010		140		\$0.00
Low	Work In Progress			12/1/2010 11:54:46 AM					
Perez, Raul			wash car #33						
67062	Motor Vehicle				12/2/2010		139		\$0.00
Medium	Work In Progress	vehicles-183		12/2/2010 8:32:28 AM					
Flores, Pete			athletic's ford expeditions require wiper blade refills.						
<u>Pete Flores</u>									
67705	Motor Vehicle				12/16/2010		125		\$0.00
Medium	Work In Progress	vehicle#116		12/16/2010 10:13:43					
Flores, Pete			left rear tire flat.						
<u>Pete Flores</u>									
67706	Motor Vehicle				12/16/2010		125		\$0.00
Medium	Work In Progress	vehicle#161		12/16/2010 10:16:11					
Flores, Pete			flat tire on vehicle's left front.						
<u>Pete Flores</u>									
4/20/2011 11:58:50 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Physical Plant Complex</b>							
67828					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:41 AM					
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
68082	Motor Vehicle				1/7/2011		103		\$0.00
Medium	Work In Progress	vehicle#92		1/7/2011 1:03:42 PM					
Flores, Pete		vehicle#92 is scheduled for routine service.							
Pete Flores									
68682					1/24/2011		86		\$0.00
Medium	Work In Progress			1/24/2011 10:11:33 AM					
Carrasco, Danny		please texture, paint and install vct in room next to techs.thank you							
Michael Munoz									
68683					1/24/2011		86		\$0.00
Medium	Work In Progress			1/24/2011 10:13:34 AM					
Carrasco, Danny		as per our conversation we had, please dispose of any material outdated and cut and clean in fenced area.thank you							
Michael Munoz									
68685					1/24/2011		86		\$0.00
Medium	Work In Progress			1/24/2011 10:45:44 AM					
Ronquillo, Ruben		as per meeting held, please dispose of any unused material and clean and organize barracks. thank you.							
Michael Munoz									
68801					1/26/2011		84		\$0.00
Medium	Work In Progress			1/26/2011 3:08:04 PM					
Ronquillo, Ruben		Need to refill First Aide Boxes at Maint. Warehouse and Maint Lobby. Asp Alfredo now is the time...							
Margret Villalobos									
68850	Maintenance				1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 2:48:35 PM					
Ronquillo, Ruben		PURCHASE INDOOR AND OUTDOOR LIGHTING FOR WAREHOUSE.							
Ruben Ronquillo									
69148	Motor Vehicle				2/7/2011		72		\$0.00
Medium	Work In Progress	vehicle #128		2/7/2011 3:16:36 PM					
Flores, Pete		vehicle sluggish at highway speeds and clutch is very difficult to engage.							
Pete Flores									
4/20/2011 11:58:50 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location: Physical Plant Complex</b>										
69276					2/9/2011		70		\$0.00	
Medium	Work In Progress			2/9/2011 2:05:42 PM						
Estrada, Jesus	NEED FOR CARPET IN JULIES OFFICE TO BE REPLACED.									
<u>Jesus Estrada</u>										
69797					2/22/2011		57		\$0.00	
Medium	Work In Progress			2/22/2011 4:17:36 PM						
Ronquillo, Ruben	PURCHASE DEEP CYCLE BATTERIES FOR SCISSOR LIFT. FOR RUBEN THANK YOU									
<u>Ruben Ronquillo</u>										
70122	Maintenance				3/3/2011		48		\$0.00	
Medium	Work In Progress			3/3/2011 8:12:40 AM						
Gonzalez, Salvador	build an iron frame cart with wheels to be used at work shop.									
<u>Lorenzo Solis</u>										
70135		Athletic Field			3/3/2011		48		\$0.00	
Medium	Work In Progress			3/3/2011 9:16:15 AM						
Flores, Pete	dump truck #96 needs new tarp to transport material as per D.P.S									
<u>Guadalupe Ontiveros</u>										
70258					3/6/2011		45		\$0.00	
Medium	Work In Progress			3/6/2011 12:17:47 AM						
Orozco, Danny	Yearly - Physical Plant Fire Ext. Insp. (Yearly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
70596					3/10/2011		41		\$0.00	
Medium	Work In Progress			3/10/2011 10:29:23 AM						
Ronquillo, Ruben	NEED TO PURCHASE NEW FAX MACHINE, OLD ONE IS JAMMING PAPERS. FOR RUBEN THANK YOU									
<u>Ruben Ronquillo</u>										
70687					3/11/2011		40		\$0.00	
Medium	Work In Progress			3/11/2011 3:44:00 PM						
Flores, Pete	Truck #16 dies at the stops. Loud pop when in reverse, when traveling at 15 mph the front wheels pull to the sides. The A/C does not work.									
<u>Jesus Estrada</u>										
70800	Motor Vehicle				3/16/2011		35		\$0.00	
Medium	Work In Progress			3/16/2011 7:49:49 AM						
Gonzalez, Salvador	need to upgrade a new frame stand for new a/c									
<u>Jose Ambriz</u>										
4/20/2011 11:58:50 AM										



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
70869	Motor Vehicle				3/17/2011		34		\$0.00
Medium	Work In Progress	vehicle#104-			3/17/2011 11:01:37 AM				
Flores, Pete	vehicle stalls intermittently.check and advise								
Pete Flores									
70898	Maintenance	Mechanical			3/18/2011		33		\$0.00
Medium	Work In Progress				3/18/2011 7:49:30 AM				
Gonzalez, Salvador	please weld a 3 tank rack for compay truck to carry freon. safety								
Lorenzo Solis									
70899	Motor Vehicle				3/18/2011		33		\$0.00
Medium	Work In Progress				3/18/2011 8:40:45 AM				
Solis, Lorenzo	Need to repair water fountain in Auto Shop hallway.								
Alfredo Holguin									
71132	Motor Vehicle				3/28/2011		23		\$0.00
Medium	Work In Progress	vehicle#120			3/28/2011 9:06:52 AM				
Flores, Pete	vehicle is in need of tires								
Pete Flores									
71586					4/4/2011		16		\$0.00
Medium	Work In Progress				4/4/2011 7:27:39 AM				
Flores, Pete	Vehicle # 23, please replace front windshield and repair side one as well.thank you(locksmith manny)								
Michael Munoz									
71602	Motor Vehicle				4/4/2011		16		\$0.00
Medium	Work In Progress	vehicle#44			4/4/2011 9:57:28 AM				
Flores, Pete	vehicle leaking engine coolant.check&advise								
Pete Flores									
71608	Food Services				4/4/2011		16		\$0.00
Medium	Work In Progress				4/4/2011 1:55:33 PM				
Orozco, Danny	One of the ref. units (outside) is making a loud noise.								
Michael Munoz									
71618	Motor Vehicle				4/4/2011		16		\$0.00
Medium	Work In Progress	vehicle#160			4/4/2011 3:34:07 PM				
Flores, Pete	vehicle requires maintenance								
Pete Flores									
71697		Athletic Field			4/6/2011		14		\$0.00
Medium	Work In Progress				4/6/2011 8:49:47 AM				
Flores, Pete	back hoe is leaking from hydraulic fitting.								
Guadalupe Ontiveros									
4/20/2011 11:58:50 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Physical Plant Complex</b>							
71699		Athletic Field			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 8:56:55 AM					
Flores, Pete	dump truck #96 needs windshield replaced.hydraulic tank needs to be weld, leaking oil. left front signal broken. as per d.o.t.								
<u>Guadalupe Ontiveros</u>									
71729	Maintenance	Custodial			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 12:57:33 PM					
Flores, Pete	VAN #29 STALLED AT MESQUITE ELEM I BELIVE IT MAY BE THE FUEL PUMP THIS IS THE VAN WE USE AT THE PPD FOR THE CUSTODIAL DUTIES I HAVE BEEN USING MY PERSONNAL VEHICLE TO PERFORM THE CUSTODIAL DUTIES WHICH I BELIVE TO BE UNETHICAL WE ALSO USE THIS VAN FOR MISCELLANEOUS RUNS WE ONLY HAVE THIS ONE.								
<u>Jimmy Carbajal</u>									
71813					4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 8:41:02 AM					
Ronquillo, Ruben	OREDER NEW US/NM NYLON FLAGS. FOR RUBEN THANK YOU								
<u>Ruben Ronquillo</u>									
72077					4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 8:04:16 AM					
Diaz, Sebastian	please repair the water leak on the east side of the maint / cust warehouse. the line leaking is for the a/c.thank you								
<u>Michael Munoz</u>									
72088	Motor Vehicle				4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 11:02:31 AM					
Lara, Ralph	Maria's Door is scraping at the bottom and the Door to lobby area at Auto Shop is hard to unlock.								
<u>Maria Ruiz</u>									
72165					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 8:51:58 AM					
Sotelo, Enrique	attention Enrique can you install electrical outlet in work table please. Thank you.								
<u>Salvador Gonzalez</u>									
72221	Food Services				4/19/2011		1		\$0.00
Medium	Work In Progress			4/19/2011 9:50:30 AM					
Orozco, Danny	FREEZER #4 FROZEN COIL.								
<u>Maritza Gonzalez</u>									
<b>Count: 45 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>81</b>		<b>Total for Physical Plant Complex</b>	<b>0</b>		<b>\$0.00</b>

4/20/2011 11:58:50 AM

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
62586		Cafeteria			8/17/2010		246		\$0.00
Medium	Work In Progress			8/17/2010 11:24:47 AM					
Orozco, Danny	GARBAGE DISPOSAL: NEED TO REPLACE THE START AND STOP SWITCH.								
	DANNY O SNP TECH.								
<u>Jacqueline Aguilar</u>									
64030					9/16/2010		216		\$0.00
Medium	Work In Progress			9/16/2010 3:38:00 PM					
Perez, Raul	need 10gal desil and 5gal gas								
<u>Carlos Hernandez</u>									
65568					10/18/2010		184		\$0.00
Medium	Work In Progress			10/18/2010 3:26:52 PM					
Gonzalez, Salvador	need to make metal frame cover for outside water fountains								
<u>Carlos Hernandez</u>									
66092					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:25					
Orozco, Danny	Monthly - Riverside ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67139					12/3/2010		138		\$0.00
Medium	Work In Progress			12/3/2010 3:08:38 PM					
Flores, Pete	need to replace broken pin on scraper to 970								
<u>Carlos Hernandez</u>									
67829					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:41 AM					
Villalobos, David	Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68190					1/10/2011		100		\$0.00
Medium	Work In Progress			1/10/2011 3:36:33 PM					
Lara, Ralph	need replacement padlock for back gates old one missing and a spare one								
<u>Carlos Hernandez</u>									
68498					1/18/2011		92		\$0.00
Medium	Work In Progress			1/18/2011 2:11:20 PM					
Villalobos, David	need to replace koler seat need special part to install new one								
Carlos Hernandez									

4/20/2011 11:58:50 AM

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
68725					1/25/2011		85		\$0.00
Medium	Work In Progress			1/25/2011 9:09:10 AM					
Castillo, Carlos	need to replace covers and light bulbs on light poles outside new wing								
Carlos Hernandez									
68958					2/1/2011		78		\$0.00
Medium	Work In Progress			2/1/2011 8:20:29 AM					
Carrasco, Danny	need 15 gallon gas for truck								
Carlos Hernandez									
70245					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:41 AM					
Orozco, Danny	Yearly - Riverside ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
70572		Cafeteria			3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 8:16:48 AM					
Orozco, Danny	WALK IN DOOR STOPPER NOT WORKING.								
	EMILIA SNP MGR 589-2550								
Jacqueline Aguilar									
70837					3/16/2011		35		\$0.00
Medium	Work In Progress			3/16/2011 3:03:25 PM					
Hernandez, Carlos	need to install green machine pump on new a/c units that were installed								
Carlos Hernandez									
71168					3/28/2011		23		\$0.00
Medium	Work In Progress	Landscaping		3/28/2011 3:42:10 PM					
Villalobos, David	Need line locate for landscaping project. For location, please coordinate with Contractor - Joe Garcia/ESA Construction - (915)549-4582.								
Peggy Jo Hernandez									
71271					3/30/2011		21		\$0.00
Medium	Work In Progress			3/30/2011 4:31:54 PM					
Orozco, Danny	SPRING NEEDS TO BE REPLACED ON DISHWASHER. SNP MANAGER EMILIA C. 589.2550								
Maritza Gonzalez									
71439					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:55 AM					
Orozco, Danny	Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
4/20/2011 11:58:50 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Riverside ES</b>									
71897					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:31 AM					
Romero, Raul	Monthly - QRTL Y BLDG INSP REPORT (RS) - Refer to PM schedule details.								
Jesus Estrada									
71923					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:24:51 AM					
Ronquillo, Ruben	need to replace to broken windows north entrance and westside entrance middle wing 15 x 15 single pane due to vandlism								
Carlos Hernandez									
71974					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 3:33:19 PM					
Villalobos, David	need replace faucet in room 117 leaking								
Carlos Hernandez									
71975					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 3:34:15 PM					
Villalobos, David	need to replace faucet in roomn 126 keeps running								
Carlos Hernandez									
72018					4/12/2011		8		\$0.00
Medium	Work In Progress			4/12/2011 3:21:26 PM					
Carrasco, Danny	need 15 gallons fuel for truck								
Carlos Hernandez									
<b>Count: 21 Work Orders</b>			<b>Avg. Age of WO's 78</b>			<b>Total for Riverside ES</b>	<b>0</b>	<b>\$0.00</b>	

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>RTC - Alliance</b>							
70128		Stairway			3/3/2011		48		\$0.00
Medium	Work In Progress				3/3/2011 8:43:55 AM				
Ambriz, Juan	need to repair ramp that are warped safety precautions								
Gloria Delgado									
70130		Office			3/3/2011		48		\$0.00
Medium	Work In Progress				3/3/2011 8:46:06 AM				
Ambriz, Juan	would like my office painted in the summer								
Gloria Delgado									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>48</b>		<b>Total for RTC - Alliance</b>	<b>0</b>		<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: San Miguel ES</b>									
62911		Pump House			8/25/2010		238		\$0.00
Medium	Work In Progress				8/25/2010 11:04:05 AM				
Sanchez, Raul		Plug well LRG 7618 as per Satate Engineer Requierments and have Contractor provide a Plugging Report							
Alfredo Holguin									
70749					3/14/2011		37		\$0.00
Medium	Work In Progress				3/14/2011 3:43:01 PM				
Solis, Lorenzo		as per mike need to repair hvac water lines at sme boiler circulating pumps and damage to lines in hallways (winter storm)							
Danny Vega									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>138</b>		<b>Total for San Miguel ES</b>	<b>0</b>		<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa ES</b>									
61467	Main Building	Cafeteria			7/28/2010		266		\$0.00
Medium	Work In Progress	cafeteria			7/28/2010 4:00:25 PM				
Moncayo, Fernando	CEILING TILES AND HVAC REGISTERS NEED TO BE CLEANED. PLEASE ASSIT CAFETERIA STAFF WITH THIS MATTER. THANKS.								
<u>Rita Mendez</u>									
63124					8/30/2010		233		\$0.00
Medium	Work In Progress				8/30/2010 9:22:32 AM				
Marquez, Gerardo	MR. Y. IS REQUESTING 3-SECRETARY PARKING SIGNS BE INSTALLED @ FACULTY PARKING LOT.								
<u>Gerardo Marquez</u>									
65678					10/20/2010		182		\$0.00
Medium	Work In Progress				10/20/2010 9:47:18 AM				
Ambriz, Jose	JOSE; HVAC IN PORTABLE-E (THE MUSIC RM. NEEDS UPGRADING. ) THANKS.								
<u>Gerardo Marquez</u>									
66094					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress				10/31/2010 12:36:26				
Orozco, Danny	Monthly - Santa Teresa ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67834					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress				1/2/2011 12:28:43 AM				
Villalobos, David	Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68588	Main Building	Classroom			1/19/2011		91		\$0.00
Medium	Work In Progress	ROOM 309			1/19/2011 4:33:34 PM				
Marquez, Gerardo	MRS. TELLES'S WORLD MAP IS NOT ROLLING DOWN. IT NEEDS TO BE CHECKED. THANKS.								
<u>Rita Mendez</u>									
68593					1/20/2011		90		\$0.00
Medium	Work In Progress				1/20/2011 8:32:32 AM				
Marquez, Gerardo	NEED TO ORDER FERTILIZER & WEED & FEED FOR PLAYGROUND. THANKS.								
<u>Gerardo Marquez</u>									
69185					2/8/2011		71		\$0.00
Medium	Work In Progress				2/8/2011 9:42:03 AM				
Villalobos, David	WATER COMING OUT OF WALL IN CAFET. PREP AREA UNDER DISHWASHER PLEASE CHECK IT OUT. THANKS.								
<u>Gerardo Marquez</u>									
4/20/2011 11:58:50 AM									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
70246					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:41 AM					
Orozco, Danny	Yearly - Santa Teresa ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70286					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:18:01 AM					
Marquez, Gerardo	Yearly - Santa Teresa ES A-10 HEAT PUMPS (ANNUAL) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70287					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:18:02 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70413					3/7/2011		44		\$0.00
Medium	Work In Progress			3/7/2011 2:47:15 PM					
Ambriz, Jose	3/7/11 JOSE, WE NEED TO REPLACE THE STERLING UNIT @ CAFET. PREP. AREA.								
<u>Gerardo Marquez</u>									
70778					3/15/2011		36		\$0.00
Medium	Work In Progress			3/15/2011 12:13:18 PM					
Orozco, Danny	WASHER (CLOTHES) IS NOT DRAINING WATER. LEAK ON WALL NEAR DISHWASHER SNP MANAGER PAT S. 589.3439.								
<u>Maritza Gonzalez</u>									
70970		Cafeteria			3/21/2011		30		\$0.00
Medium	Work In Progress			3/21/2011 7:59:15 AM					
Gonzalez, Salvador	need to make a frame stand or adapter. Thank you								
<u>Jose Ambriz</u>									
71017		Cafeteria			3/23/2011		28		\$0.00
Medium	Work In Progress			3/23/2011 9:58:38 AM					
Castillo, Carlos	new package unit will be installed.unit will need power run to it.please meet with Jose(HVAC) for installation date.thankyou								
<u>Michael Munoz</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
71278					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 12:17:29 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES-A-16 Fan Exhaust (SemiA) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71440					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:56 AM					
Orozco, Danny	Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71475					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:12 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71476					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:12 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71477					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:13 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71637					4/5/2011		15		\$0.00
Medium	Work In Progress	custodian Pablo		4/5/2011 8:43:26 AM					
Carbajal, Jimmy	wheels are broken on tilt truck that is used for transporting trash and breakfast. Thank you.								
<u>Rosie Diaz</u>									
71704					4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 9:16:10 AM					
Marquez, Gerardo	MIKE. BASKETBALL GOAL POLE PADS NEED TO BE INSTALLED ON ALL 8 GOALS. THANKS.								
<u>Gerardo Marquez</u>									
71705					4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 9:19:55 AM					
Villalobos, David	A SHUT OFF VALVE NEEDS TO BE INSTALLED OUTSIDE OF CAFET. ON THE WATER SUPPLY LINE THAT GOES TO PORTABLE C & D, & MOBILE HOME. THANKS.								
<u>Gerardo Marquez</u>									
4/20/2011 11:58:50 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
71708					4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 9:43:49 AM					
Marquez, Gerardo	NEED TO REPLACE CONCRETE THAT WAS REMOVED TO FIX WATER LEAK @ BACK OF CAFETERIA. WILL NEED 15 BAGS OF CONCRETE MIX. THANKS.								
<u>Gerardo Marquez</u>									
71891					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:28 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71908					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:37 AM					
Diaz, Pablo	Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
71943	Main Building	Library			4/11/2011		9		\$0.00
Medium	Work In Progress	Mrs.Harmon		4/11/2011 9:11:13 AM					
Marquez, Gerardo	Please paint and install letters above library door								
<u>Rosie Diaz</u>									
71999					4/12/2011		8		\$0.00
Medium	Work In Progress			4/12/2011 10:19:09 AM					
Marquez, Gerardo	NEED TO REPLACE SUPPLY LINES TO MASTER COOLS & STERLING UNITS. BALL VALVES ALSO NEED TO BE REPLACES. (NOT SHUTTING OFF.)								
<u>Gerardo Marquez</u>									
72232	Main Building	Restroom (Boys)			4/19/2011		1		\$0.00
Medium	Work In Progress	CASA BLANCA		4/19/2011 10:54:34 AM					
Marquez, Gerardo	URINAL IS PLUGGED AND IS OVERFLOWING.								
<u>Rita Mendez</u>									
72234	Main Building	Library			4/19/2011		1		\$0.00
Medium	Work In Progress	LIBRARY AND		4/19/2011 12:33:36 PM					
Lara, Ralph	THE LOCK ON THE DOOR BETWEEN THE LIBRARY AND THE COMPUTER LAB NEEDS TO BE CHANGED TO A NON LOCKING DOORKNOB (IN CASE OF EVACUATION AS PER FIRE DEPARTMENT).								
<u>Rita Mendez</u>									
<b>Count: 30 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>56</b>	<b>Total for Santa Teresa ES</b>		<b>0</b>	<b>\$0.00</b>	

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
60574					7/4/2010	7/10/2010	290		\$0.00
Medium	Work In Progress			7/4/2010 12:23:35 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60575					7/4/2010	7/12/2010	290		\$0.00
Medium	Work In Progress			7/4/2010 12:23:35 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60576					7/4/2010	8/4/2010	290		\$0.00
Medium	Work In Progress			7/4/2010 12:23:35 AM					
Nunez, Arturo	Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60577					7/4/2010	8/4/2010	290		\$0.00
Medium	Work In Progress			7/4/2010 12:23:36 AM					
Nunez, Arturo	Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60578					7/4/2010		290		\$0.00
Medium	Work In Progress			7/4/2010 12:23:36 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60579					7/4/2010	7/7/2010	290		\$0.00
Medium	Work In Progress			7/4/2010 12:23:36 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60603					7/4/2010	7/25/2010	290		\$0.00
Medium	Work In Progress			7/4/2010 12:23:44 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60853					7/11/2010	8/11/2010	283		\$0.00
Medium	Work In Progress			7/11/2010 12:20:25 AM					
Nunez, Arturo	Yearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
60968					7/14/2010		280		\$0.00
Medium	Work In Progress			7/14/2010 12:20:23 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Grease Trap (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
61359		Classroom			7/27/2010		267		\$0.00
Medium	Work In Progress	MRS.		7/27/2010 10:07:32 AM					
Nunez, Arturo	1. CEILING TILES NEED TO BE REPLACED. 2. NEED OVERHEAD SCREEN ATTACHED TO CEILING OVER CHALK BOARD.								
<u>Marylou Jimenez</u>									
61530					7/30/2010		264		\$0.00
Medium	Work In Progress			7/30/2010 8:26:29 AM					
Perez, Raul	NEED TO HAVE WINDSHIELD ,PASSENGERS WINDOW , AND BAND TRUCK REARVIEW MIRRORS REPLACED. VANDALISM. Case#2010-07139								
<u>Arturo Nunez</u>									
61606					8/1/2010	8/4/2010	262		\$0.00
Medium	Work In Progress			8/1/2010 12:47:39 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
61607					8/1/2010		262		\$0.00
Medium	Work In Progress			8/1/2010 12:47:39 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
61608					8/1/2010	8/7/2010	262		\$0.00
Medium	Work In Progress			8/1/2010 12:47:40 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
62106					8/8/2010	9/8/2010	255		\$0.00
Medium	Work In Progress			8/8/2010 12:38:55 AM					
Prospero, Manuel	Yearly - Santa Teresa HS A-9 Air Cooled Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
62237					8/10/2010		253		\$0.00
Safety	Work In Progress			8/10/2010 9:13:08 AM					
Nunez, Arturo	Check all wall cabinets throughout your site and make sure they are secure to wall and remind teachers not to overload with books. If you should have any questions, call Alfredo or Mike.								
<u>Alfredo Holguin</u>									
62250		Classroom			8/10/2010		253		\$0.00
Medium	Work In Progress	Room # 17		8/10/2010 11:32:44 AM					
Nunez, Arturo	Replace some ceiling tiles. Walls need to be painted Remount bulletin board once painting is completed Door needs to be put in place.								
<u>Luis Calleros</u>									
62305	GYM (2009)	Gym			8/11/2010		252		\$0.00
Medium	Work In Progress	New Gym -		8/11/2010 10:23:33 AM					
Mijarez, Jaime	Need to hang up large posters in the new gym. See Coach Dotson								
<u>Luis Calleros</u>									
62331		Classroom			8/11/2010		252		\$0.00
Medium	Work In Progress	MR.		8/11/2010 1:16:10 PM					
Nunez, Arturo	I NEED OVERHEAD PROJECTOR SCREEN PUT BACK UP ON MY WALL. IT FELL DOWN IN APRIL AND HASN'T BEEN REINSTALLED YET.								
<u>Marylou Jimenez</u>									
62333					8/11/2010		252		\$0.00
Medium	Work In Progress	COACH		8/11/2010 1:21:00 PM					
Nunez, Arturo	AC IS NOT WORKING IN THE FOOTBALL COACHES OFFICE.								
<u>Marylou Jimenez</u>									
62577		Classroom			8/17/2010		246		\$0.00
Medium	Work In Progress	Room L3		8/17/2010 9:40:49 AM					
Nunez, Arturo	Need projector screen installed								
<u>Luis Calleros</u>									
62609	Main Building	Classroom			8/17/2010		246		\$0.00
Medium	Work In Progress	Room 12		8/17/2010 5:11:54 PM					
Prospero, Manuel	Refrigerated air unit not working in the "Career Lab". Ceiling tiles need to be replaced.				8/23 - Route to Manuel asp Mike.				
<u>Luis Calleros</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Santa Teresa HS

62712		Classroom			8/19/2010		244		\$0.00
Medium	Work In Progress	Room L2			8/19/2010 5:04:49 PM				
Prospero, Manuel	Water leak in room L2. Ceiling tiles collapsed. Need to respond asap.		8/23 - Route to Manuel asp Mike.						

Luis Calleros

62713		Gym			8/19/2010		244		\$0.00
Medium	Work In Progress	new gym area			8/19/2010 5:19:38 PM				
Prospero, Manuel	The ice machine in the new gym is not producing ice. Request fixing asap please, since our athletic trainer uses it daily to treat athletes.		8/23 - Route to Manuel asp Mike.						

Luis Calleros

62775		Classroom			8/21/2010		242		\$0.00
Medium	Work In Progress	Room C2			8/21/2010 3:31:12 PM				
Nunez, Arturo	Request wood dividers be built for middle desk area. See Ms. Armida Vasquez		Tury, please ck on this, any ?'s call Mike.						

Luis Calleros

62789		Classroom			8/23/2010		240		\$0.00
Medium	Work In Progress	Room 5 Ms.			8/23/2010 9:56:24 AM				
Nunez, Arturo	Rm 5 -Need ceiling tiles and replace floor board trimmings that are missing.								

Luis Calleros

62905		Classroom			8/25/2010		238		\$0.00
Medium	Work In Progress	cafeteria hallway			8/25/2010 10:29:39 AM				
Nunez, Arturo	Need to repair hole in the cafeteria hallway next to band room.								

Luis Calleros

62909		Classroom			8/25/2010		238		\$0.00
Medium	Work In Progress	Room 15			8/25/2010 10:56:14 AM				
Prospero, Manuel	Install pencil sharpener								

Luis Calleros

62943		Classroom			8/25/2010		238		\$0.00
Medium	Work In Progress	C 2			8/25/2010 5:23:41 PM				
Nunez, Arturo	Install a middle wooden divider between computers in middle island								

Luis Calleros

62976		Classroom			8/26/2010		237		\$0.00
Medium	Work In Progress	Room 19			8/26/2010 10:20:43 AM				
Nunez, Arturo	A/C blowing hot air.								

Luis Calleros

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
63054					8/27/2010		236		\$0.00
Medium	Work In Progress	Counseling		8/27/2010 12:57:45 PM					
Nunez, Arturo	Replace water damaged ceiling tiles								
<u>Luis Calleros</u>									
63203					8/30/2010		1		\$0.00
Medium	Work In Progress	Room 20 See		8/30/2010 4:29:24 PM	8/31/2010				
Nunez, Arturo	Need to replace three vent covers that are missing for the air conditioning ducts. The air is blowing directly on the students.								
<u>Luis Calleros</u>									
63204					8/30/2010		233		\$0.00
Medium	Work In Progress	Room 20 See		8/30/2010 4:33:07 PM					
Nunez, Arturo	Replace the handles on the cabinets in the room. 3rd requests (Jan, March) The handles are with the teacher. We need the screws.								
<u>Luis Calleros</u>									
63224					8/31/2010		232		\$0.00
Medium	Work In Progress	Vocational T-		8/31/2010 8:54:30 AM					
Nunez, Arturo	1 .Broken outlet needs to be replaced/repaired								
<u>Luis Calleros</u>									
63226					8/31/2010		232		\$0.00
Medium	Work In Progress	Vocational T-		8/31/2010 10:15:02 AM					
Prospero, Manuel	Table saw needs to be repaired								
<u>Luis Calleros</u>									
63229					8/31/2010		232		\$0.00
Medium	Work In Progress	Restroom (Boys)		8/31/2010 11:49:08 AM					
Prospero, Manuel	Boys restroom near counselors office has white paint spots that need to be painted black. The frames in the administrative areas need to be touched up.								
<u>Luis Calleros</u>									
63366					9/2/2010		230		\$0.00
Medium	Work In Progress	L 3 See Mrs.		9/2/2010 2:50:19 PM					
Nunez, Arturo	A/C is blowing hot air								
<u>Luis Calleros</u>									
63438					9/5/2010		227		\$0.00
Medium	Work In Progress			9/5/2010 12:41:44 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

4/20/2011 11:58:50 AM



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
63439					9/5/2010	9/8/2010	227		\$0.00
Medium	Work In Progress			9/5/2010 12:41:45 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
63440					9/5/2010	9/11/2010	227		\$0.00
Medium	Work In Progress			9/5/2010 12:41:45 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
63745					9/10/2010		222		\$0.00
Medium	Work In Progress	Room 307		9/10/2010 12:08:12 PM					
Nunez, Arturo	Need to have new projector mounted on wall								
<u>Luis Calleros</u>									
64286					9/22/2010		210		\$0.00
Medium	Work In Progress	Room 16		9/22/2010 5:00:22 PM					
Nunez, Arturo	Need to have bulletin boards attached to the wall. Boards are loose. Need and additional board.								
<u>Luis Calleros</u>									
64298					9/23/2010		209		\$0.00
Medium	Work In Progress	Room 22		9/23/2010 11:11:13 AM					
Nunez, Arturo	Ceiling tiles: 8 tiles are out of place and need to be properly set.								
<u>Luis Calleros</u>									
64574					9/30/2010		202		\$0.00
Medium	Work In Progress			9/30/2010 12:24:00 AM					
Prospero, Manuel	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64713					10/3/2010	10/9/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:48 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64714					10/3/2010	10/11/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:49 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
64715					10/3/2010	10/6/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:49 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64716					10/3/2010	10/24/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:50 AM					
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64717					10/3/2010	11/3/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:50 AM					
Nunez, Arturo	Yearly - Santa Teresa HS H-6 Rftop Furn Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64718					10/3/2010	11/3/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:50 AM					
Nunez, Arturo	Yearly - Santa Teresa HS R-9 Radiator Ht Wtr 2yr - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64719					10/3/2010		199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:51 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64720					10/3/2010	10/19/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:26:51 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64744					10/3/2010	10/24/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:27:00 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64865					10/3/2010	11/3/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:27:48 AM					
Prospero, Manuel	Yearly - Santa Teresa HS I-4 Fan Coil Unit Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
64866					10/3/2010	10/24/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:27:48 AM					
Prospero, Manuel	Monthly - Santa Teresa HS C-12 Chm Feeder Semimntly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64868					10/3/2010	10/11/2010	199		\$0.00
Medium	Work In Progress			10/3/2010 12:27:49 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64967					10/5/2010		197		\$0.00
Medium	Work In Progress			10/5/2010 2:39:03 PM					
Nunez, Arturo	PLAYGROUND AREA NEXT TO DAYCARE, WATER LEAK, SOUTH END ON BUILDING / STORAGE AREA								
<u>Michael Munoz</u>									
65127					10/7/2010		195		\$0.00
Medium	Work In Progress	Football		10/7/2010 4:52:21 PM					
Nunez, Arturo	Water backed up in football coaches office								
<u>Luis Calleros</u>									
65163					10/10/2010	10/26/2010	192		\$0.00
Medium	Work In Progress			10/10/2010 12:23:11					
Nunez, Arturo	Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
65282					10/12/2010		190		\$0.00
Medium	Work In Progress			10/12/2010 8:04:07 AM					
Villalobos, David	Urinal on restroom in vocational building, needs to be replaced it is broken.								
<u>Arturo Nunez</u>									
65919					10/27/2010		175		\$0.00
Medium	Work In Progress			10/27/2010 8:21:26 AM					
Ambriz, Jose	HEATER R.T.F. S.T.H.S. O13 , NEEDS TO BE REPLACED, FOUND HEAT EXCHANGER CRACKED. WILL PUT OUT OF SERVICE. MODINE SERIAL # 2060693, MODEL#WDG 2005F , 115V., BTU. INPUT 200,000. OUTPUT 160,000								
<u>Arturo Nunez</u>									
66063					10/31/2010		171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:11					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
4/20/2011 11:58:50 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
66064					10/31/2010	11/3/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:12					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66065					10/31/2010	11/6/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:12					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66095					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:26					
Orozco, Danny	Monthly - Santa Teresa HS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67798					1/2/2011	1/5/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:27 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66485	Main Building	Restroom (Girls)			11/9/2010		162		\$0.00
Medium	Work In Progress			11/9/2010 9:37:52 AM					
Nunez, Arturo	NEW JUMBO BATHROOM DISPENSERS NEED TO BE INSTALL IN THE MENS AND LADYS BATHROOMS BY ANNAS OFFICE THANK YOU.								
<u>Luis Murillo</u>									
66535					11/10/2010		161		\$0.00
Medium	Work In Progress			11/10/2010 8:54:55 AM					
Villalobos, David	NEED TO HAVE GAS SHUT VALVE, OFF FOR ANNEX HEATERS RELOCATED FROM ROOF, TO WALL. EASY EXCESS IN CASE OF AN EMERGENCY.								
<u>Arturo Nunez</u>									
66586					11/14/2010		157		\$0.00
Medium	Work In Progress			11/14/2010 12:24:37					
Nunez, Arturo	Monthly - Santa Teresa HS - Grease Trap (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66747	Vocational				11/17/2010		154		\$0.00
Medium	Work In Progress	T - 300		11/17/2010 9:44:51 AM					
Nunez, Arturo	Heater not working								
<u>Luis Calleros</u>									
4/20/2011 11:58:51 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
66846					11/19/2010		152		\$0.00
Medium	Work In Progress				11/19/2010 11:51:35				
Nunez, Arturo	NEED TO HAVE SPRINKLERS ON SOFTBALL FIELD CHECKED SOME ARE MISSING HEADS WATER JUST SHOOTING UP INTO THE AIR. GOT A CALL FROM MR. CALLERO ON 11/19/10 AT 9.00P.M TO COME AND CHECK OUT SITUATION. WRONG INFO. WAS GIVEN TO ME. THE INFO. I GOT WAS THAT, AN A.C. LINE WAS BUSTED, AFTER CHECKING SITUATION, IT CAME OU TO BE A B MISSING SPRINKLER HEAD.								
<u>Arturo Nunez</u>									
66898					11/29/2010		142		\$0.00
Medium	Work In Progress				11/29/2010 11:03:37				
Villalobos, David	NEED SOME ASSITANCE ON WATER HEATER IN CAFETERIA, WATER COIL SEEMS TO BE BUSTED ,LEAKING WATER								
<u>Arturo Nunez</u>									
67007	Main Building	Hallway/Corridor			12/1/2010		140		\$0.00
Medium	Work In Progress	Hallway by			12/1/2010 8:20:16 AM				
Nunez, Arturo	Please check bad odor that is coming out of the main hallway by the science, math and counseling wing. It has been smelling really bad for the last 2 days.					Leadership Request			
<u>Peggy Jo Hernandez</u>									
67126					12/3/2010		138		\$0.00
Medium	Work In Progress				12/3/2010 8:59:20 AM				
Nunez, Arturo	Hole in wall on warroir room in caferteria needs to be repaired, due to Vandalism								
<u>Arturo Nunez</u>									
67165					12/5/2010	12/8/2010	136		\$0.00
Medium	Work In Progress				12/5/2010 12:26:47 AM				
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67166					12/5/2010		136		\$0.00
Medium	Work In Progress				12/5/2010 12:26:48 AM				
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67167					12/5/2010	12/11/2010	136		\$0.00
Medium	Work In Progress				12/5/2010 12:26:48 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
4/20/2011 11:58:51 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
67376					12/7/2010		134		\$0.00
Medium	Work In Progress	Girls locker		12/7/2010 5:40:09 PM					
Villalobos, David	Clogged toilet in girls locker room, athletic side, middle one								
<u>Luis Calleros</u>									
67479					12/10/2010		131		\$0.00
Medium	Work In Progress	Attendance		12/10/2010 2:10:50 PM					
Prospero, Manuel	Paint old cabinets in attendance office the same color as the newly insatlld cabinets. Please match the same counter top as the new ones installed.								
<u>Luis Calleros</u>									
67524					12/12/2010	12/28/2010	129		\$0.00
Medium	Work In Progress			12/12/2010 12:25:23					
Prospero, Manuel	Monthly - Santa Teresa HS Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67631	Main Building	Restroom (Girls)			12/15/2010		126		\$0.00
Medium	Work In Progress			12/15/2010 7:54:45 AM					
Villalobos, David	12/15/10. WE NEED TO REPLACE ALL LAVATORY FAUCETS ON MAIN ENTRANCE GIRLS RESTROOMS.								
<u>Manuel Prospero</u>									
67638	Cafeteria (2005)	Cafeteria			12/15/2010		126		\$0.00
Medium	Work In Progress			12/15/2010 8:17:54 AM					
Nunez, Arturo	no gas to cafeteria.Please check .thank you								
<u>Michael Munoz</u>									
67651					12/15/2010		126		\$0.00
Medium	Work In Progress	new restrooms		12/15/2010 11:15:06					
Lara, Ralph	Need to install lock / key to be able to lock the new restrooms by the math wing.								
<u>Luis Calleros</u>									
67797					1/2/2011		108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:26 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67799					1/2/2011	1/8/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:28 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
4/20/2011 11:58:51 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
67800					1/2/2011	1/10/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:28 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67832					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:42 AM					
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67841					1/2/2011	1/23/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:46 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67906					1/2/2011	1/10/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:29:21 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67907					1/2/2011	1/10/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:29:21 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67908					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:29:22 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67958					1/4/2011		106		\$0.00
Medium	Work In Progress	Old Gym		1/4/2011 1:25:13 PM					
Murillo, Luis	Lights in old gym need to be replaced. There are about 4-5 lights out.								
<u>Luis Calleros</u>									
67960					1/4/2011		106		\$0.00
Medium	Work In Progress	Vocational		1/4/2011 1:33:14 PM					
Nunez, Arturo	Service air compressor								
<u>Luis Calleros</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
67985					1/5/2011		105		\$0.00
Medium	Work In Progress			1/5/2011 3:55:07 PM					
Nunez, Arturo		NEED TO REPAIR WATER LEAK FOR PORTABLE BUILDINGS, NEAR DAY CARE PLAY GROUND.							
Arturo Nunez									
68115		Classroom			1/8/2011		102		\$0.00
Medium	Work In Progress	Room 307		1/8/2011 1:09:58 PM					
Nunez, Arturo		Exhaust fan does not work. See Mrs. Ochoa							
Luis Calleros									
68149					1/9/2011	1/25/2011	101		\$0.00
Medium	Work In Progress			1/9/2011 12:25:29 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
68169					1/10/2011		100		\$0.00
Medium	Work In Progress	Hallway by		1/10/2011 10:42:16 AM					
Prospero, Manuel		Hallway by the old gym needs to be painted							
Luis Calleros									
68240					1/11/2011		99		\$0.00
Medium	Work In Progress	Room 208		1/11/2011 1:51:27 PM					
Nunez, Arturo		Venatlation blinds are broken and need to be replaced. See Mr. Gannon							
Luis Calleros									
68340		Library			1/13/2011		97		\$0.00
Medium	Work In Progress	MARY		1/13/2011 11:20:13 AM					
Nunez, Arturo		ART NUNEZ-PLEASE MOUNT SIMULATED SECURITY CAMERAS (3) IN LIBRARY: ONE IN BACK OF LIBRARY; ONE IN REFERENCE ROOM; AND ONE IN COMPUTER LAB.							
Marylou Jimenez									
68342					1/13/2011		97		\$0.00
Medium	Work In Progress			1/13/2011 12:37:41 PM					
Nunez, Arturo		NEED TO HAVE WALL ON SOFTBALL FIELD PAINTED TO COVER UP GRAFFITI,							
Arturo Nunez									
68363		Classroom			1/13/2011		97		\$0.00
Medium	Work In Progress	MRS.		1/13/2011 3:37:40 PM					
Nunez, Arturo		ART NUNEZ OR MANNY PROSPERO-I NEED A CART ASSEMBLED FOR MY "ELMO".							
Marylou Jimenez									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
68472					1/14/2011		96		\$0.00
Medium	Work In Progress			1/14/2011 3:52:28 PM					
Flores, Pete	NEED TO HAVE GAS PEDAL ON VECHILE #70 REPLACED, LINKAGE IS BROKEN FROM GAS PEDAL								
<u>Arturo Nunez</u>									
68485	Cafeteria (2005)	Custodial			1/18/2011		92		\$0.00
Medium	Work In Progress			1/18/2011 10:53:30 AM					
Villalobos, David	need work done on irrigation backflow preventer constantly leaking								
<u>David Villalobos</u>									
68511					1/13/2011		97		\$0.00
Medium	Work In Progress			1/18/2011 3:50:38 PM					
Nunez, Arturo	Graffiti on softball field wall. (Case# 11-00359) R. Tellez								
<u>Luis Calleros</u>									
68541		Classroom			1/19/2011		91		\$0.00
Medium	Work In Progress	MRS.		1/19/2011 11:09:06 AM					
Nunez, Arturo	ART NUNEZ-PLEASE INSTALL TV IN ROOM #300								
<u>Marylou Jimenez</u>									
68542					1/19/2011		91		\$0.00
Medium	Work In Progress	MARYLOU		1/19/2011 11:10:36 AM					
Nunez, Arturo	ART NUNEZ-PLEASE INSTALL 2 BOARDS 1-ON WALL NEXT TO PRINCIPALS OFFICE 1-TEACHERS LOUNGE PLEASE SEE ME TO GIVE INSTRUCTIONS WHICH WALL TO BE MOUNTED.								
<u>Marylou Jimenez</u>									
68573					1/19/2011		91		\$0.00
Medium	Work In Progress			1/19/2011 3:44:25 PM					
Lara, Ralph	NEED GATE KEY FOR EL PASO DISPOSAL AS PER MIKE/ALFREDO. OLD KEY TO BE TURNED IN WHEN THIS ONE IS PICKED UP								
<u>Michael Munoz</u>									
68664					1/21/2011		89		\$0.00
Medium	Work In Progress			1/21/2011 3:44:10 PM					
Nunez, Arturo	Need 20 - 25 light bulbs in welding classroom / office. See Mr. Angelo								
Luis Calleros									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
68916					1/31/2011		79		\$0.00
Medium	Work In Progress			1/31/2011 8:04:26 AM					
Nunez, Arturo	NEED A 4L 380 FAN BELT FOR A.H.U. FOR COMPUTER LAB # 4 .,								
<u>Arturo Nunez</u>									
68968					2/1/2011		78		\$0.00
Medium	Work In Progress	West side of		2/1/2011 8:33:52 AM					
Villalobos, David	Need Utility Line Locate on the west side of Annex Bldg. - width of building to sidewalk. Please mark on Monday 2/7/11. If you have any questions, please contact Mr. Ralph Gallegos at 882-6921 or (575) 650-9095 / cell.								
<u>Peggy Jo Hernandez</u>									
68971					2/1/2011		78		\$0.00
Medium	Work In Progress	New Boy's		2/1/2011 9:15:00 AM					
Nunez, Arturo	Basketball: New Boy's Locker Room: Replace bench seat on to the support. Has been repaired before at least twice.		3/9 - Asp Mike, route to Art.						
<u>Luis Calleros</u>									
69015					2/6/2011	2/12/2011	73		\$0.00
Medium	Work In Progress			2/6/2011 12:33:31 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69016					2/6/2011		73		\$0.00
Medium	Work In Progress			2/6/2011 12:33:31 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69017					2/6/2011	2/9/2011	73		\$0.00
Medium	Work In Progress			2/6/2011 12:33:32 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69153					2/7/2011		72		\$0.00
Medium	Work In Progress	Annex Bldg.		2/7/2011 3:27:48 PM					
Villalobos, David	Need line locate - North & South Sides of Annex Bldg. all the way to Chiller. If you have any questions, please call Mr. Ralph Gallegos (575) 650-9095								
<u>Peggy Jo Hernandez</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
69742					2/21/2011		58		\$0.00
Medium	Work In Progress	Baseball Field		2/21/2011 1:20:35 PM					
Valdez, Pedro	Back Stop, 3rd base, and behind home plate: By 3rd base the fence has been cut. A board has been temporarily placed, but a player can get hurt if he runs into the board or hole while trying to catch a ball. The fence will come apart. A player can be seriously hurt if he slides inot the fence that is sticking up.								
Luis Calleros									
69758					2/22/2011		57		\$0.00
Medium	Work In Progress			2/22/2011 10:18:43 AM					
Ronquillo, Ruben	GLAAS ON DOOR AT DRESSING ROOM EAST ENTRANCE NEEDS TO BE REPLACED, MEASUREMENTS ARE , 25 1/4 X 36 1/4 SAFETY WIRE MESH. 1 EA.								
Arturo Nunez									
69761					2/22/2011		57		\$0.00
Medium	Work In Progress			2/22/2011 10:27:07 AM					
Villalobos, David	NEED TO HAVE BACK FLOW RISER FOR IRRIGATION, CHECKED LEAKING WATER THROUGH VENT RELIEF,								
Arturo Nunez									
69786	Concession	Football Field			2/22/2011		21	47	\$1,341.00
Medium	Work In Progress			2/22/2011 3:34:03 PM	3/15/2011				
Villalobos, David	WE HAVE WATER LEAK ON CONSESSION STAND BOYS RESTROOM WALL.					Work Still Pending			
Manuel Prospero						Worked on broken water lines from freeze in cinder bolkd, sheetrock, fiberglass capped off lines got water going in concession stand.			
69788	Annex Building	Mechanical			2/22/2011		3	3	\$125.00
Medium	Work In Progress			2/22/2011 3:36:47 PM	2/25/2011				
Villalobos, David	WE HAVE A WATER LEAK ON WATER HEATER ( OLD R.O.T.C.).					Work still pending			
Manuel Prospero						need to replace cutoff flex connectors			
69794					2/22/2011		3	11	\$475.00
Medium	Work In Progress			2/22/2011 3:44:55 PM	2/25/2011				
Villalobos, David	WE AHVE A BIG WATER LEAK ON ANNEX BUILDING ( OLD KITCHEN) IN TE WALL.					Work still pending			
Manuel Prospero						seek where water leaking from will have to reroute most lines.			

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
69818					2/23/2011		56		\$0.00
Medium	Work In Progress	Vocational area		2/23/2011 10:24:34 AM					
Prospero, Manuel		Need to remove old furniture/junk that has been outside the vocational area. There is also a lot of junk that is in the portable that needs to be removed. We will be having the team from HSTW TAV visit in March. Please remove before March 4, 2011							
Luis Calleros									
69844					2/23/2011		56		\$0.00
Medium	Work In Progress	Warrior Ropom		2/23/2011 3:40:59 PM					
Nunez, Arturo		Need to have a television mounted in the Warrior Room by the cafeteria by next week please							
Luis Calleros									
69851					2/23/2011		56		\$0.00
Safety	Work In Progress	Room 16		2/23/2011 4:37:52 PM					
Nunez, Arturo		2nd request. Secure / hang a white objective board. Safety issue as it might fall on students. and very important before the TAV visit.							
Luis Calleros									
69852					2/23/2011		56		\$0.00
Medium	Work In Progress	Room 16		2/23/2011 4:39:48 PM					
Nunez, Arturo		Need to acquire bulletin board from storage and attach in room 16.							
Luis Calleros									
69960					2/26/2011		53		\$0.00
Medium	Work In Progress	Wall [panel next		2/26/2011 11:02:23 AM					
Nunez, Arturo		There is a hole the size of a big fist, and getting bigger, on the wall next to the band room. Maintenance attempted to fix on a separate occassion. However, the material used to cover the hole, keeps on falling out. Suggest replacing the entire panel. The problem needs to be properly addressed.							
Luis Calleros									
70027					3/1/2011		50		\$0.00
Medium	Work In Progress	Room 301		3/1/2011 7:51:00 AM					
Nunez, Arturo		Teacher needs an overhead projector screen hung up in room 301. Screen is in portable #2, which will have to be moved from the portable to room 301.							
Luis Calleros									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
70033					3/1/2011		50		\$0.00
Medium	Work In Progress	Baseball		3/1/2011 8:18:52 AM					
Castillo, Carlos		Need to have electricity to the baseball concession stand. Request work done asap please since the season has already started and the concession stand is needed.							
Luis Calleros									
70148					3/3/2011		48		\$0.00
Medium	Work In Progress	Science Room		3/3/2011 12:15:58 PM					
Nunez, Arturo		Asp Mr. Gallegos this needs to be check by the maintenance its not something the contractor did. Please ck on the exhaust fan in Ms. Stevens' Science classroom is not working. Please coordinate with teacher.							
Peggy Jo Hernandez									
70220					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:28 AM					
Nunez, Arturo		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
70221					3/6/2011	3/9/2011	45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:29 AM					
Nunez, Arturo		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.							
Margret Villalobos									
70222					3/6/2011	3/12/2011	45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:29 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
70256					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:46 AM					
Orozco, Danny		Yearly - Santa Teresa HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
70334					3/6/2011	4/6/2011	45		\$0.00
Medium	Work In Progress			3/6/2011 12:18:25 AM					
Prospero, Manuel		Yearly - Santa Teresa HS A-10 HP Yearly - Refer to PM schedule details.							
Margret Villalobos									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
70557					3/9/2011		42		\$0.00
Medium	Work In Progress			3/9/2011 3:48:00 PM					
Nunez, Arturo	NEED TO HAVE MAIN GATE VALVE FOR FIRE SPRINKLER SYSTEM ON VOCATIOAL BUILDING CHECKED, AND REPAIRED, LEAKING WATER PRETTY BAD.								
Arturo Nunez									
70679					3/11/2011		40		\$0.00
Medium	Work In Progress			3/11/2011 3:16:35 PM					
Munoz, Michael	Need to install two gates by old gym area. One gate would be installed immediately by one of the dressing rooms and the other needs to be installed next to the old gym.								
Luis Calleros									
70713					3/13/2011		38		\$0.00
Medium	Work In Progress	New gym area		3/13/2011 3:54:05 PM					
Lara, Ralph	Would like to chagne the locks to the new gym entry and exit area. See Mr.Calleros.								
Luis Calleros									
70774					3/15/2011		36		\$0.00
Medium	Work In Progress			3/15/2011 10:14:25 AM					
Prospero, Manuel	DOOR STOP NEEDS TO BE INSTALLED IN BACK DOOR TO CAFETERIA. SNP MANAGER OLGA B. 589.5332.								
Maritza Gonzalez									
70904					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 9:07:34 AM					
Lara, Ralph	Need door hooks / latches to keep Handicapp doors open.								
Luis Calleros									
70927					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 1:28:37 PM					
Ambriz, Jose	HEATERS ON CLASS ROOM # 807, NEED TO BE REPLACED, CLASSROOM CRPB 175, OFFICE CRPB 125.								
Arturo Nunez									
70928					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 1:31:13 PM					
Ambriz, Jose	HEATERS ON CLASSROOM # 805 NEED TO BE REPLACED, CLASSROOM CRPB 175, OFFICE CRPB 125.								
Arturo Nunez									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
70929					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 1:34:22 PM					
Ambriz, Jose	HEATERS ON CLASSROOM # 803 NEED TO BE REPLACED CLASSROOM CRPB 300, OFFICE CRPB 125.								
Arturo Nunez									
70930					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 1:36:05 PM					
Ambriz, Jose	HEATERS ON CLASSROOM # 801 NEED TO BE REPLACED, CLASSROOM CRPB 175, OFFICE CRPB 125.								
Arturo Nunez									
70935					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:23:33 PM					
Ambriz, Jose	CLASSROOM # 507 A.C. NEEDS TO BE REPLACED, 6500 C.F.M. S.D.								
Arturo Nunez									
70937					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:24:57 PM					
Ambriz, Jose	CLASSROOM # 509 NEED TO REPLACE A.C. UNIT, 6500 C.F.M. S.D.								
Arturo Nunez									
70938					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:26:15 PM					
Ambriz, Jose	CLASSROOM # 504 A.C. UNIT NEEDS TO BE REPLACED 6500 C.F.M. S.D.								
Arturo Nunez									
70939					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:31:48 PM					
Ambriz, Jose	A.C. UNIT ON COUNSELORS OFFICE NEED TO BE REPLACED. TWO AIR FLOW ENTRY, D.D.								
Arturo Nunez									
70940					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:33:45 PM					
Ambriz, Jose	NEED TO REPLACE A.C. UNIT ON ROOM # 501, 6500 C.F.M. S.D.								
Arturo Nunez									
70941					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:35:41 PM					
Ambriz, Jose	A.C. ON CLASSROOM # 400 NEEDS TO BE REPLACED, 6500 C.F.M. S.D.								
Arturo Nunez									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
70942					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:39:04 PM					
Ambriz, Jose	A.C. ON CLASSROOM # 403 NEEDS TO BE REPLACED, 6500 C.F.M. S.D.								
Arturo Nunez									
70943					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:41:21 PM					
Ambriz, Jose	A.C. ON CLASSROOM # 404 NEEDS TO BE REPLACED 6500 C.F.M. S.D.								
Arturo Nunez									
70944					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:42:48 PM					
Ambriz, Jose	A.C. ON ATTENDENCE OFFICE NEEDS TO BE REPLACED, 6500 C.F.M. D.D.								
Arturo Nunez									
70945					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:44:27 PM					
Ambriz, Jose	A.C. ON CLASSROOM # 612, NEEDS TO BE REPLACED 6500 C.F.M. D.D.								
Arturo Nunez									
70946					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:46:25 PM					
Ambriz, Jose	A.C. INCLASSROOM # 616, NEEDS TO BE REPLACED 6500 C.F.M. D.D.								
Arturo Nunez									
70948					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:48:16 PM					
Ambriz, Jose	A.C. ON CLASSROOM # 300 , NEEDS TO BE REPLACED 6500C.F.M. D.D.								
Arturo Nunez									
70949					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:51:45 PM					
Ambriz, Jose	A.C. ON ROOM # 302 NEEDS TO BE REPLACED , 6500 C.F.M. D.D.								
Arturo Nunez									
70950					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:53:36 PM					
Ambriz, Jose	A.C. ONCLASSROOM # 303 NEEDS TO BE REPLACED. 6500 C.F.M. D.D.								
Arturo Nunez									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
70951					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 2:57:46 PM					
Ambriz, Jose	A.C. UNIT ON CLASSROOM # 614 NEEDS TO BE REPLACED 6500 C.F.M. D.D.								
<u>Arturo Nunez</u>									
71200					3/29/2011		22		\$0.00
Medium	Work In Progress	Locker Room		3/29/2011 10:13:12 AM					
Prospero, Manuel	Broken faucet on athletic side. Once faucet is turned on, the water will not shut off for about an hopur. See Coach Francis.								
<u>Luis Calleros</u>									
71243					3/30/2011		21		\$0.00
Medium	Work In Progress			3/30/2011 11:48:34 AM					
Nunez, Arturo	AS PER MR. RALPH GALLEGOS, CEILING TILES NEED TO BE REPLACED IN OFFICE ARE AND MATH WING BETWEEN ROOM # 8 & 9.								
<u>Marylou Jimenez</u>									
71247	GYM (2009)	Custodial			3/30/2011		21		\$0.00
Medium	Work In Progress			3/30/2011 1:03:44 PM					
Carbajal, Jimmy	The court clean at this site is pulled by two jump ropes. We need to replace the rope on it.								
<u>Jesus Estrada</u>									
71288					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 12:17:34 AM					
Prospero, Manuel	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71384					4/1/2011		19		\$0.00
Medium	Work In Progress	Turf Field		4/1/2011 4:54:46 PM					
Valdez, Pedro	Please re-distribute the black rubber pellets on the Turf field								
<u>Luis Calleros</u>									
71402					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:37 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71403					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:38 AM					
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
4/20/2011 11:58:51 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
71404					4/3/2011	4/6/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:38 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71405					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:39 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71406					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:39 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71407					4/3/2011	4/19/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:40 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71427					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:50 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71441					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:56 AM					
Orozco, Danny	Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71529					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:35 AM					
Prospero, Manuel	Monthly - Santa Teresa HS C-12 Chm Feeder Semimntly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71530					4/3/2011	5/4/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:35 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
71531					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:36 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
71532					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:36 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
71676	Main Building				4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 3:35:21 PM					
Prospero, Manuel	4/4/11. 8HRS CLEANING AND STARTED A/C ON 300;S AREA.		4/4- 8						
Manuel Prospero									
71680	Main Building	Restroom (Boys)			4/5/2011		15		\$0.00
Medium	Work In Progress			4/5/2011 3:43:55 PM					
Villalobos, David	WE NEED SOME ASSINSTING. ON CLOGGED UNRINAL BOYS BATRROMS 300;S WENG.								
Manuel Prospero									
71722	Main Building	Classroom			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 12:45:11 PM					
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 304, IS ON BAD CONDITION.								
Manuel Prospero									
71723	Main Building	Classroom			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 12:46:47 PM					
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 306 IS ON BAD CONDITION.								
Manuel Prospero									
71724	Main Building	Classroom			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 12:48:17 PM					
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 308 IS ON BAD CONDITONE.								
Manuel Prospero									
71725	Main Building	Classroom			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 12:50:32 PM					
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 301 6500 CFM MC DOUN DRAFT.								
Manuel Prospero									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Santa Teresa HS

71726	Main Building	Classroom			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 12:52:35 PM					
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 305 6500 CFM MC DOUN DRAFT								

Manuel Prospero

71728	Main Building	Classroom			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 12:56:40 PM					
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 307 6500 CFM MC DOUN DRAFT.								

Manuel Prospero

71730		Classroom			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 12:58:23 PM					
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 309 6500 CFM MC DOUN DRAFT.								

Manuel Prospero

71773	Concession	Gym			4/7/2011		13		\$0.00
Medium	Work In Progress			4/7/2011 8:47:07 AM					
Villalobos, David	WE NEED ASSISTIN FOR FIX WATER FOUNTAIN ON CONCESSION STAND OUT SIDE ON GYM.								

Manuel Prospero

71774	Main Building	Restroom (Boys)			4/7/2011		13		\$0.00
Medium	Work In Progress			4/7/2011 8:50:03 AM					
Villalobos, David	WE NEED SOME ASSISTIN TO UNCLOGG URINAL ON 300; BOYS RESTROOMS.								

Manuel Prospero

71835		Athletic Field			4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 1:02:18 PM					
Flores, Pete	truck #17 needs oil and filter changed, also sparkplugs.								

Guadalupe Ontiveros

71877					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:22 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.								

Margret Villalobos

71903					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:35 AM					
Murillo, Luis	Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.								

Jesus Estrada

4/20/2011 11:58:51 AM

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Santa Teresa HS

71922	Main Building				4/11/2011		9		\$0.00
Medium	Work In Progress	Restroom 530			4/11/2011 8:23:59 AM				
Ambriz, Jose	Install new exhaust fan in Restroom 530 (ISS Restroom).								

Peggy Jo Hernandez

71951					4/11/2011		9		\$0.00
Medium	Work In Progress	Leadership			4/11/2011 11:13:03 AM				
Prospero, Manuel	Science Room 508 - Need to secure all table tops to base. (Needs to be completed within 30 days).					Leadership Request			

Alfredo Holguin

72030					4/12/2011		8		\$0.00
Medium	Work In Progress	MARY			4/12/2011 4:46:44 PM				
Lara, Ralph	FRONT DOOR STICKS OPEN-HAVE DIFFICULTY KEEPING IT LOCKED WHEN NECESSARY.								

Marylou Jimenez

72235					4/19/2011		1		\$0.00
Medium	Work In Progress				4/19/2011 12:59:23 PM				
Lara, Ralph	NEED REPLACEMENT OF M-7 FOR FOOTBALL FEILD BOX								

Manuel Prospero

72237	Main Building				4/19/2011		1		\$0.00
Medium	Work In Progress				4/19/2011 1:02:25 PM				
Lara, Ralph	NEED FOR YOU TO REKEYED ONE CLASSROOM TO THE SAME KEY TEACHER HAS RIGH NOW.								

Manuel Prospero

72238	Main Building				4/19/2011		1		\$0.00
Medium	Work In Progress				4/19/2011 1:04:43 PM				
Lara, Ralph	NEED TWO PADLOCKS FOR STORAGE ROOMS OUT SIDE DAYCARE CENTER.								

Manuel Prospero

72239	Annex Building	Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress				4/19/2011 1:07:02 PM				
Lara, Ralph	NEED TO INSTALLED ONE LOCK ON FILE CABINET IN THE ROTC BUILDING,								

Manuel Prospero

72240	Concession	Gym			4/19/2011		1		\$0.00
Medium	Work In Progress				4/19/2011 1:10:06 PM				
Lara, Ralph	NEED FOR YOU TO AJUSTED DOOR IN CONSSION STAND INSIDE LOBBY AREA ON NEW GYM.								

Manuel Prospero

4/20/2011 11:58:51 AM

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
72251					4/19/2011		1		\$0.00
Medium	Work In Progress				4/19/2011 3:29:26 PM				
Villalobos, David	NEED SOME ASSITANCE ON KITCHEN RAYPACK WATER HEATER, HOT WATER COILS ARE BUSTED.								
Arturo Nunez									
72254					4/19/2011		1		\$0.00
Medium	Work In Progress				4/19/2011 3:32:40 PM				
Ambriz, Jose	NEED SOME ASSITANCE ON CHECKING ICE MACHINE IN CAFETERIA, NEED AN ICE THICKNESS PROBE FOR MANITOWAC.								
Arturo Nunez									
<b>Count: 199 Work Orders</b>		<b>Avg. Age of WO's 113</b>			<b>Total for Santa Teresa HS</b>			<b>61</b>	<b>\$1,941.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
64597		Athletic Field			9/30/2010		202		\$0.00
Medium	Work In Progress			9/30/2010 11:02:20 AM					
Gonzalez, Salvador	SOCCER GOALS NEED TO BE WELDED AT BOTTOM AND TOP.								
<u>Guadalupe Ontiveros</u>									
65670					10/20/2010		182		\$0.00
Medium	Work In Progress			10/20/2010 8:33:05 AM					
Castillo, Carlos	I have to 2 classrooms that emergency lights are not working. This are the fluorescent type I need help to either replace emergency ballast or install the frog eyed emergency light fixtures.								
<u>Jaime Mijarez</u>									
66096					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:27					
Orozco, Danny	Monthly - Santa Teresa MS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66498	Gym (1997)	Gym			11/9/2010		162		\$0.00
Medium	Work In Progress			11/9/2010 11:34:13 AM					
Mijarez, Jaime	MIDDLE DRY ERASE BOARD IS COMING OFF THE WALL FROM BOTH SIDES								
<u>Laura Parra</u>									
67038					12/1/2010		140		\$0.00
Medium	Work In Progress			12/1/2010 3:35:59 PM					
Flores, Pete	The golf cart needs service it is not holding the charge.								
<u>Jaime Mijarez</u>									
67459					12/10/2010		131		\$0.00
Medium	Work In Progress			12/10/2010 7:58:51 AM					
Villalobos, David	Councilors office sink. I need help with the sink it is plugged up and p-trap is cracked we will need the snake.								
<u>Jaime Mijarez</u>									
67552	Gym (1997)	Parking Lot			12/13/2010		128		\$0.00
Medium	Work In Progress			12/13/2010 2:00:19 PM					
Castillo, Carlos	PLACE NEW LIGHTS GOING TOWARDS THE GYM FROM THE PARKING LOT- FROM THE N BUILDIND AND FROM THE S BUILDING. SAFETY ISSUE-- IT GETS TOO DARK WHEN GOING TOWARD THE GYM AT NIGHT								
<u>Laura Parra</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
67553	North Building	Parking Lot			12/13/2010		128		\$0.00
Medium	Work In Progress				12/13/2010 2:01:40 PM				
Castillo, Carlos	REPAIR ALL OUTSIDE LIGHTS- PARKING LOT- S BUILDING-N BUILDING- AND GYM AREA								
<u>Laura Parra</u>									
67833					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress				1/2/2011 12:28:42 AM				
Villalobos, David	Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68090		Athletic Field			1/7/2011		103		\$0.00
Medium	Work In Progress				1/7/2011 2:03:02 PM				
Valdez, Pedro	football, soccer, upper field and new soded are need to be fertilize with 16-8-8.								
<u>Guadalupe Ontiveros</u>									
68423	South Building	Classroom			1/14/2011		96		\$0.00
Medium	Work In Progress	Room 39			1/14/2011 9:47:04 AM				
Castillo, Carlos	Repair lights								
<u>Laura Parra</u>									
68425					1/14/2011		96		\$0.00
Medium	Work In Progress				1/14/2011 10:27:28 AM				
Mijarez, Jaime	Rockwall planters - repair broken sections				Noted on Leadership Meeting Asp Mike, route to Jaime 4/14/11-mkv				
<u>Alfredo Holguin</u>									
68427					1/14/2011		96		\$0.00
Medium	Work In Progress				1/14/2011 10:35:43 AM				
Mijarez, Jaime	(PROJECT) Repaint Flashing/cap on parapet wall both north and south buildings.				Leadership Request				
<u>Alfredo Holguin</u>									
68781					1/26/2011		84		\$0.00
Medium	Work In Progress				1/26/2011 9:36:56 AM				
Carrasco, Danny	As per Ace Sanchez. Deliver scissor lift to Stms before or by 9:00 am Monday May 2, 2011 or earlier. Will be use for Cinco De Mayo Concert setup.								
Jaime Mijarez									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
68783					1/26/2011		84		\$0.00
Medium	Work In Progress			1/26/2011 9:42:58 AM					
Mijarez, Jaime	As per Ace Sanchez. Pickup 12 pieces of stage from Sths and have them on campus by or before April 28, 2011 or earlier. Will be used for the Cinco de Mayo Concert.								
<u>Jaime Mijarez</u>									
68934	Gym (1997)	Gym			1/31/2011		79		\$0.00
Medium	Work In Progress	Ms. Snyder		1/31/2011 3:01:55 PM					
Mijarez, Jaime	Dry erase board (center) is falling off the wall. Safety Hazard Please repair								
<u>Laura Parra</u>									
69508	South Building	Mechanical			2/15/2011		17	17	\$519.75
Medium	Work In Progress			2/15/2011 9:56:07 AM		3/4/2011			
Villalobos, David	repaired broken copper water lines at south mechanical room to geothermal heating system					Work still pending replace broken 3/4 bfp and water meter re-routed water lines.			
<u>David Villalobos</u>									
69511	Gym (1997)				2/15/2011		64		\$0.00
Medium	Work In Progress			2/15/2011 10:03:41 AM					
Castillo, Carlos	receiver and antennas came in for scoreboards that were at sths, now at stms. please check to see if they work and if so please install in gym. thank you								
<u>Michael Munoz</u>									
69817	South Building	Restroom (Boys)			2/23/2011		56		\$0.00
Medium	Work In Progress			2/23/2011 9:57:12 AM					
Lara, Ralph	Rafa, the bottom southbuilding restrooms needs replacement of doors and hardware.								
<u>Ismael Rodriguez</u>									
70092		Custodial			3/2/2011		49		\$0.00
Medium	Work In Progress			3/2/2011 12:02:39 PM					
Ronquillo, Ruben	Ruben i need 10 rolls of duct tape for the gym floor tarp for the art show, chuy estrada has been notify thanks. Mr. Rodriguez								
<u>Ismael Rodriguez</u>									
70251					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:44 AM					
Orozco, Danny	Yearly - Santa Teresa MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa MS</b>									
70581					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 8:44:31 AM					
Ambriz, Jose	Joe can you order me 6 PL-36 Bell & Goss circulating pumps. I have used all the ones I had in stock.								
Jaime Mijarez									
70773					3/15/2011		36		\$0.00
Medium	Work In Progress			3/15/2011 10:09:22 AM					
Castillo, Carlos	N.bldg 2 exterior lights on eastside upper level exterior wall are broken.								
Jaime Mijarez									
70861					3/17/2011		34		\$0.00
Medium	Work In Progress			3/17/2011 9:47:56 AM					
Villalobos, David	w/o for winter storm emergency. South bldg administration area mechanical room had ruptured make water line, water meter, backflow preventer and no water in geothermal administration heat pump area.								
Jaime Mijarez									
71074					3/25/2011		26		\$0.00
Medium	Work In Progress			3/25/2011 8:33:50 AM					
Ontiveros, Guadalupe	S.bldg there is an area on the road behind the building along side the fire hydrant and transformer that the dirt is real loose and vehicals are getting stuck. As per Security Frank Medina the road should be accesible for ambulance and fire truck.								
Jaime Mijarez									
71315					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 1:19:33 PM					
Mijarez, Jaime	Repace broken VCT tiles throughout building-trip hazards per Leadership Council - Jaime Minjarez. knows what areas.								
Alfredo Holguin									
71442					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:57 AM					
Orozco, Danny	Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71498					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:22 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
71499					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:22 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71500					4/3/2011	4/19/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:23 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS A1(Wall Refr.E/H)(Semi) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71501					4/3/2011	5/4/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:23 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71502					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:24 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71503					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:24 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71504					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:24 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71594	North Building				4/4/2011		16		\$0.00
Medium	Work In Progress			4/4/2011 9:25:18 AM					
Estrada, Jesus	NEED TO REPLACE VCT IN HALLWAY, LOWER LEVEL OF NORHT BUILDING.								
<u>Jesus Estrada</u>									
71595		Cafeteria			4/4/2011		16		\$0.00
Medium	Work In Progress			4/4/2011 9:27:00 AM					
Estrada, Jesus	NEED TO REPLACE BASEBOARD IN CAFETERIA								
<u>Jesus Estrada</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
71816					4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 8:50:13 AM					
Mijarez, Jaime	Stage lights set-up for Cinco de Mayo concert requires scissor lift.								
<u>Jaime Mijarez</u>									
71837	South Building				4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 1:44:00 PM					
Valles, Johnny	Need to treat planter and till dirt by next Thursday.								
<u>Michael Munoz</u>									
71838					4/8/2011		12		\$0.00
Medium	Work In Progress			4/8/2011 1:45:59 PM					
Ronquillo, Ruben	Need to purchase flowers for Leadership Council. Make PO for 500.00 (see Mike Munoz)								
<u>Michael Munoz</u>									
71952					4/11/2011		9		\$0.00
Medium	Work In Progress	Leadership		4/11/2011 11:18:08 AM					
Estrada, Jesus	North/South Bldgs - Need tile replaced in various areas.		Leadership Request		ASP ALFREDO NORTH BLDG O.K. / SOUTH BLDG PENDING EXCEPT FOR 2 RESTROOM AREAS/LOWER LEVEL.				
Alfredo Holguin									
72042	Gym (1997)	Gym			4/13/2011		7		\$0.00
Medium	Work In Progress	GYM		4/13/2011 10:17:41 AM					
Mijarez, Jaime	HANGING OF SUSPENSION LIGHTS IN GYM ON WEDNESDAY APRIL 27TH.								
<u>Laura Parra</u>									
72057					4/13/2011		7		\$0.00
Medium	Work In Progress			4/13/2011 3:24:36 PM					
Mijarez, Jaime	School campus install No Trespassing signs along fence line and Reserved parking for assistant principal signs.								
<u>Jaime Mijarez</u>									
72079	North Building	Custodial			4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 8:07:31 AM					
Carrasco, Danny	Need three gallons of fuel for our equipment...pressure washer , gas blowers and weed edgers.								
<u>Ismael Rodriguez</u>									
72215	North Building	Parking Lot			4/19/2011		1		\$0.00
Medium	Work In Progress			4/19/2011 8:31:02 AM					
Ontiveros, Guadalupe	Lupe we need to borrow the small tracter from riverside so we can remove the sand from the parking lot.								
Ismael Rodriguez									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
72216	Gym (1997)	Custodial			4/19/2011		1		\$0.00
Medium	Work In Progress				4/19/2011 8:35:45 AM				
Flores, Pete	Pete i need to borrow a truck for the coming event art show iam going to move chairs and tables to the gym unless you have ready truck 121 by 4-27-11 thanks.								
Ismael Rodriguez									
72292	North Building	Office			4/20/2011		0		\$0.00
Medium	Work In Progress				4/20/2011 9:07:45 AM				
Lara, Ralph	Rafa, office personal is asking for you to put alock in the front the window office, see Mr.Rodriguez....								
Ismael Rodriguez									
<b>Count: 46 Work Orders</b>		<b>Avg. Age of WO's 57</b>			<b>Total for Santa Teresa MS</b>			<b>17</b>	<b>\$519.75</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
64465	Main Building	Classroom			9/28/2010		204		\$0.00
Medium	Work In Progress			9/28/2010 11:55:05 AM					
Ambriz, Jose	Air conditioning has leaked into classroom and caused several areas to rust, including light fixtures.								
Yvette Cortez									
64493	Main Building	Restroom (Girls)			9/28/2010		204		\$0.00
Medium	Work In Progress			9/28/2010 3:53:31 PM					
Medina, Eric	Floors paint is chipping.		(Summer Job)						
Yvette Cortez									
65051		Cafeteria			10/6/2010		196		\$0.00
Medium	Work In Progress			10/6/2010 3:28:36 PM					
Orozco, Danny	SCREEN DOOR TO THE KITCHEN NEEDS TO BE REPAIRED.								
AS PER STATE INSPECTOR									
Jacqueline Aguilar									
65249					10/11/2010		191		\$0.00
Medium	Work In Progress			10/11/2010 3:26:51 PM					
Orozco, Danny	HAND SINK IS LEAKING SNP MANAGER MARINA R. 589-2545.								
Maritza Gonzalez									
65553		Athletic Field			10/18/2010		184		\$0.00
Medium	Work In Progress			10/18/2010 2:05:51 PM					
Ontiveros, Guadalupe	please cut weeds that are growing on the sloped area of the field. thank you								
Michael Munoz									
65586					10/18/2010		184		\$0.00
Medium	Work In Progress			10/18/2010 3:53:46 PM					
Flores, Pete	Lupe I would like to request that you send someone with backhoe to dig hole to deposit all the weeds that were cut								
Eric Medina									
66097					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:27					
Orozco, Danny	Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
66285					11/3/2010		168		\$0.00
Medium	Work In Progress			11/3/2010 2:16:14 PM					
Orozco, Danny	LEFT SIDE OF SERVING LANE IS NOT COOLING. MARINA R. SNP MANAGER 589-2545.								
<u>Maritza Gonzalez</u>									
67831					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:42 AM					
Villalobos, David	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68601	Main Building	Gym			1/20/2011		90		\$0.00
Medium	Work In Progress			1/20/2011 3:16:09 PM					
Medina, Eric	Eric, Mrs. Villa has requested for a screen to be installed in the gym. Meanwhile, screen has been placed in the shed for storage.								
<u>Yvette Cortez</u>									
68743	Main Building				1/25/2011		85		\$0.00
Medium	Work In Progress			1/25/2011 2:35:30 PM					
Medina, Eric	pto will paint boys & girls rr with maintainence supervision								
<u>Eric Medina</u>									
69288	Main Building	Hallway/Corridor			2/9/2011		70		\$0.00
Medium	Work In Progress			2/9/2011 3:41:20 PM					
Medina, Eric	Sidewalk on southside of the building is raised by 1/2 inch. Please add cement to even level.								
<u>Yvette Cortez</u>									
69604	Main Building	Classroom			2/16/2011		63		\$0.00
Medium	Work In Progress	38 & 40		2/16/2011 3:12:26 PM					
Castillo, Carlos	Eric, Ms. Gardea and Ms. Cordero both need new light bulbs in theri restrooms. Thanks!								
<u>Yvette Cortez</u>									
70019		Auditorium			2/28/2011		51		\$0.00
Medium	Work In Progress			2/28/2011 3:56:15 PM					
Medina, Eric	2 turbines on the auditorium and 1 on dining area are not working. please check and repiar.thanks								
<u>Michael Munoz</u>									
70247					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:42 AM					
Orozco, Danny	Yearly - Sunland Park ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
70302					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:18:09 AM					
Herrera, Joel	Yearly - Sunland Park ES A-10 HP Rooftop Yearly - Refer to PM schedule details.								
Margret Villalobos									
70610					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:06:00 PM					
Ambriz, Jose	need to replace a/c in room 29 size 68								
Eric Medina									
70612					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:10:25 PM					
Ambriz, Jose	need to replace a/c in rm 31 size 45								
Eric Medina									
70614					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:11:47 PM					
Ambriz, Jose	need to replace a/c in sped office size 45								
Eric Medina									
70616					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:12:59 PM					
Ambriz, Jose	need to replace a/c in speech office size 45								
Eric Medina									
70617					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:14:05 PM					
Ambriz, Jose	need to replace a/c in rm 37 size 45								
Eric Medina									
70618					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:17:44 PM					
Ambriz, Jose	need to replace a/c in room 39 size 68								
Eric Medina									
70619					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:18:25 PM					
Ambriz, Jose	need to replace a/c in room 41 size 68								
Eric Medina									
70620					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:19:48 PM					
Ambriz, Jose	need to replace a/c in room 40 size 68								
Eric Medina									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
70621					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:22:05 PM					
Ambriz, Jose	need to replace a/c in room 38 size 68								
Eric Medina									
70622					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:23:24 PM					
Ambriz, Jose	need to replace a/c in room 36 size 68								
Eric Medina									
70623					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:24:05 PM					
Ambriz, Jose	need to replace a/c in room 32 size 68								
Eric Medina									
70624					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:24:48 PM					
Ambriz, Jose	need to replace a/c in room 30 size 68								
Eric Medina									
70625					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:25:30 PM					
Ambriz, Jose	need to replace a/c in room 26 size 68								
Eric Medina									
70627					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:26:45 PM					
Ambriz, Jose	need to replace a/c in room 24 size 68								
Eric Medina									
70629					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:27:39 PM					
Ambriz, Jose	need to replace a/c in room 22 size 45								
Eric Medina									
70630					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:28:24 PM					
Ambriz, Jose	need to replace a/c in staff development room size 45								
Eric Medina									
70631					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:29:23 PM					
Ambriz, Jose	need to replace a/c in room 16 size 68								
Eric Medina									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
70633					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:30:15 PM					
Ambriz, Jose	need to replace a/c in room 14 size 68								
Eric Medina									
70634					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:31:53 PM					
Ambriz, Jose	need to replace a/c in room 12 size 68								
Eric Medina									
70636					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:32:30 PM					
Ambriz, Jose	need to replace a/c in room 10 size 68								
Eric Medina									
70638					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:33:26 PM					
Ambriz, Jose	need to replace a/c in room 13 size 68								
Eric Medina									
70639					3/10/2011		41		\$0.00
Medium	Work In Progress			3/10/2011 3:34:08 PM					
Ambriz, Jose	need to replace a/c in room 11 size 68								
Eric Medina									
71007					3/22/2011		29		\$0.00
Medium	Work In Progress			3/22/2011 3:33:21 PM					
Medina, Eric	need to weed and feed all lawns								
Eric Medina									
71205					3/29/2011		22		\$0.00
Medium	Work In Progress			3/29/2011 2:40:36 PM					
Medina, Eric	need to replace motor belts on a/c units 5 ton and 7								
Eric Medina									
71443					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:57 AM					
Orozco, Danny	Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
71710	Main Building	Parking Lot			4/6/2011		14		\$0.00
Safety	Work In Progress			4/6/2011 9:59:17 AM					
Medina, Eric	Eric, we need noth bus turn around and main drive way to be cleaned of dirt/sand piles. Need thsi done as soon as possible, already had three incidents.								
Yvette Cortez									
71733	Main Building				4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 1:57:35 PM					
Medina, Eric	Eric, please take the art show display and assemble it at STMS on April 28th. Also, please take down the art display and bring it back here at SPE on May 2nd. You will need to check the display with Ms. Powell and practice assembling it prior to the display.								
Yvette Cortez									
71789					4/7/2011		13		\$0.00
Medium	Work In Progress			4/7/2011 2:16:14 PM					
Medina, Eric	danny need to replace ip 1/2 " ball valves with 1/2" male couplings and 1/2" female couplings								
Eric Medina									
71888					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:27 AM					
Medina, Eric	Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
72203					4/18/2011		2		\$0.00
Medium	Work In Progress			4/18/2011 4:41:35 PM					
Orozco, Danny	Filter under dishwasher is leaking. snp manager Marina R. 589.2545								
Maritza Gonzalez									
72213	Main Building	Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress	39		4/19/2011 8:19:29 AM					
Medina, Eric	Eric, may you please check the AC in Ms. Calderon's classroom. It's blowing hot air. Thanks								
Yvette Cortez									
72214	Main Building	Classroom			4/19/2011		1		\$0.00
Medium	Work In Progress	29		4/19/2011 8:22:55 AM					
Medina, Eric	Eric, please check in the sink in room 29 with Ms. Rubio. It's draining very slow.								
Yvette Cortez									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
72250					4/19/2011		1		\$0.00
Medium	Work In Progress				4/19/2011 3:28:21 PM				
Carrasco, Danny		need fuel for truck 105 and equipment 619							
<u>Eric Medina</u>									
72279	Main Building	Classroom			4/20/2011		0		\$0.00
Medium	Work In Progress	27			4/20/2011 7:55:57 AM				
Medina, Eric		Eric, I know we discussed about the AC in Ms. Terrazas room. I believe the heater turns on when she turns on the AC or its blowing out hot air.							
<u>Yvette Cortez</u>									
<b>Count: 50 Work Orders</b>			<b>Avg. Age of WO's 62</b>			<b>Total for Sunland Park ES</b>	<b>0</b>		<b>\$0.00</b>

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
60719					7/4/2010		290		\$0.00
Medium	Work In Progress			7/4/2010 12:24:23 AM					
Sanchez, Raul	Monthly - Sunrise ES - DP-1421 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64571					9/30/2010		202		\$0.00
Medium	Work In Progress			9/30/2010 12:23:59 AM					
Vargas, Juan	Monthly - Sunrise ES A16 (Fan Exh.)(S. Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64903					10/3/2010		199		\$0.00
Medium	Work In Progress			10/3/2010 12:28:02 AM					
Sanchez, Raul	Monthly - Sunrise ES - DP-1421 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66098					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:28					
Orozco, Danny	Monthly - Sunrise ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66371					11/5/2010		166		\$0.00
Medium	Work In Progress			11/5/2010 8:13:50 AM					
Ontiveros, Guadalupe	NEED 20 TONS RED SCRINIG								
<u>Juan Vargas</u>									
67830					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:41 AM					
Villalobos, David	Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67929					1/2/2011		108		\$0.00
Medium	Work In Progress			1/2/2011 12:29:32 AM					
Sanchez, Raul	Monthly - Sunrise ES - DP-1421 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68838					1/27/2011		83		\$0.00
Medium	Work In Progress			1/27/2011 11:28:22 AM					
Lozoya, Manny	Replace GM -7pin for Alfredo Holguin and replace lock where key broke at Lift Station.								
<u>Michael Munoz</u>									
4/20/2011 11:58:51 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
69463					2/14/2011		65		\$0.00
Medium	Work In Progress			2/14/2011 3:17:14 PM					
Carrasco, Danny	i need 10 gallons gas for 155 truck and 620- 2 blower								
<u>Juan Vargas</u>									
69785					2/22/2011		57		\$0.00
Medium	Work In Progress			2/22/2011 3:32:55 PM					
Ontiveros, Joe	outside water fonting neen fix broken copper line								
<u>Juan Vargas</u>									
70248					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:42 AM					
Orozco, Danny	Yearly - Sunrise ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70316					3/6/2011	3/14/2011	45		\$0.00
Medium	Work In Progress			3/6/2011 12:18:16 AM					
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70317					3/6/2011	3/14/2011	45		\$0.00
Medium	Work In Progress			3/6/2011 12:18:17 AM					
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70318					3/6/2011	3/12/2011	45		\$0.00
Medium	Work In Progress			3/6/2011 12:18:17 AM					
Vargas, Juan	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70356					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:18:37 AM					
Sanchez, Raul	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70707					3/13/2011	3/29/2011	38		\$0.00
Medium	Work In Progress			3/13/2011 12:13:04 AM					
Vargas, Juan	Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
71115					3/28/2011		23		\$0.00
Medium	Work In Progress			3/28/2011 7:52:34 AM					
Orozco, Danny	MOTOR TO GARBAGE DISPOSAL IS NOT WORKING. SNP MANAGER VIRGINIA P. 824.3194.								
Maritza Gonzalez									
71182					3/29/2011		22		\$0.00
Medium	Work In Progress			3/29/2011 12:20:58 AM					
Vargas, Juan	Monthly - Sunrise ES - Grease Trap (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
71185					3/29/2011		22		\$0.00
Medium	Work In Progress			3/29/2011 7:40:33 AM					
Flores, Pete	Need backhoe remove arena on playground areas								
Juan Vargas									
71284					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 12:17:32 AM					
Vargas, Juan	Monthly - Sunrise ES A16 (Fan Exh.)(S. Annual) - Refer to PM schedule details.								
Margret Villalobos									
71444					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:58 AM					
Orozco, Danny	Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71511					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:27 AM					
Vargas, Juan	Monthly - Sunrise ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
71512					4/3/2011	4/9/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:28 AM					
Vargas, Juan	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
71513					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:28 AM					
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
71514					4/3/2011	4/11/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:29 AM					
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71557					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:47 AM					
Sanchez, Raul	Monthly - Sunrise ES - DP-1421 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71569					4/3/2011		17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:52 AM					
Sanchez, Raul	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71663	Main Building	Cafeteria			4/5/2011		15		\$0.00
Medium	Work In Progress	CAFETERIA		4/5/2011 12:54:59 PM					
Vargas, Juan	VIRGINIA PRUIT, CAFETERIA MANAGER, THE PANEL FO RTHE AIR CONDITIONER WENT OUT. IT IS VERY HOT IN CAGETERIA POSSIBLY THE ELECTRICAL PUMP								
<u>Joanne Munoz</u>									
71711	Main Building	Restroom (Boys)			4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 11:01:47 AM					
Torres, Marisela	You need to place a screen in all the urinals. Some of the screens that are already in place need the deodorant puck replaced.								
<u>Jesus Estrada</u>									
71712					4/6/2011		14		\$0.00
High	Work In Progress			4/6/2011 11:05:00 AM					
Torres, Marisela	You have one unlabeled bottle in the custodial closet in "sol" hallway. Check all custodial closets and make sure all spray bottles are labeled.								
<u>Jesus Estrada</u>									
71901					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:33 AM					
Vargas, Juan	Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									



# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
71905					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:36 AM					
Torres, Marisela	Monthly - QRTL Y BLDG INSP REPORT (SR) - Refer to PM schedule details.								
Jesus Estrada									
71934					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:39:04 AM					
Vargas, Juan	cafeteria mater cools need replace peds								
Juan Vargas									
71936					4/11/2011		9		\$0.00
Medium	Work In Progress			4/11/2011 8:43:07 AM					
Carrasco, Danny	need sidewalks concrete cut machine								
Juan Vargas									
72076					4/14/2011		6		\$0.00
Medium	Work In Progress			4/14/2011 7:58:57 AM					
Orozco, Danny	Pass-Thru Refrigerators it is not working. SNP Manager Virginia P. 824-3194								
Maritza Gonzalez									
<b>Count: 35 Work Orders</b>		<b>Avg. Age of WO's 57</b>		<b>Total for Sunrise ES</b>			<b>0</b>	<b>\$0.00</b>	

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
63081		Cafeteria			8/27/2010		236		\$0.00
Medium	Work In Progress			8/27/2010 3:06:37 PM					
Orozco, Danny	NEED TO REPLACE THE WHEELS TO THE PREP TABLE. WHEELS THAT LOCK, THE TABLE MOVES.								
	EVA MIRANDA SNP MGR 233-2945								
<u>Jacqueline Aguilar</u>									
63621					9/8/2010		224		\$0.00
Medium	Work In Progress			9/8/2010 10:23:00 AM					
Ontiveros, Guadalupe	NEED TO PUT IN SPRINKLER SYSTEM TO RAISED GARDENS NOW THAT CONTRACTOR HAS PUT IN WATER SUPPLY LINE								
<u>Danny Miranda</u>									
65171					10/10/2010	10/26/2010	192		\$0.00
Medium	Work In Progress			10/10/2010 12:23:15					
Miranda, Danny	Monthly - Vado ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66099					10/31/2010	11/21/2010	171		\$0.00
Medium	Work In Progress			10/31/2010 12:36:28					
Orozco, Danny	Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67814					1/2/2011	2/2/2011	108		\$0.00
Medium	Work In Progress			1/2/2011 12:28:35 AM					
Villalobos, David	Yearly - Vado ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68920					1/31/2011		79		\$0.00
Medium	Work In Progress			1/31/2011 8:55:45 AM					
Ontiveros, Joe	NEED TO CK. CIRCULATING PUMP NOISE								
<u>Danny Miranda</u>									
70249					3/6/2011		45		\$0.00
Medium	Work In Progress			3/6/2011 12:17:43 AM					
Orozco, Danny	Yearly - Vado ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70757					3/14/2011		37		\$0.00
Medium	Work In Progress			3/14/2011 4:27:35 PM					
Miranda, Danny	need 12 emitter tips for drip system								
<u>Danny Miranda</u>									
4/20/2011 11:58:51 AM									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
70917					3/18/2011		33		\$0.00
Medium	Work In Progress			3/18/2011 10:23:11 AM					
Miranda, Danny	NEED TO CHANGE AIR FILTERS TO UNITS								
Danny Miranda									
71178					3/29/2011		22		\$0.00
Medium	Work In Progress			3/29/2011 12:20:56 AM					
Miranda, Danny	Monthly - Vado ES - Grease Trap (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
71337					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 3:35:35 PM					
Miranda, Danny	SPRAY ROUNDUP								
Danny Miranda									
71338					3/31/2011		20		\$0.00
Medium	Work In Progress			3/31/2011 3:37:14 PM					
Ontiveros, Guadalupe	NEED TO MARK SOCCER FIELD								
Danny Miranda									
71445					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:19:58 AM					
Orozco, Danny	Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71448					4/3/2011	4/24/2011	17		\$0.00
Medium	Work In Progress			4/3/2011 12:20:00 AM					
Orozco, Danny	Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.								
Margret Villalobos									
71746					4/6/2011		14		\$0.00
Medium	Work In Progress			4/6/2011 3:25:10 PM					
Ontiveros, Joe	CK. TWO FAUCETS IN 300-WING BOYS R.R.								
Danny Miranda									
71878					4/10/2011	4/26/2011	10		\$0.00
Medium	Work In Progress			4/10/2011 12:14:22 AM					
Diaz, Armando	Monthly - QRTL BLDG INSP REPORT (VE) - Refer to PM schedule details.								
Jesus Estrada									

# 1244 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
72054					4/13/2011		7		\$0.00
Medium	Work In Progress				4/13/2011 3:15:54 PM				
Miranda, Danny		NEED TO PUT FERTILIZER ON TREES AND PLANTS							
Danny Miranda									
72294					4/20/2011		0		\$0.00
Medium	Work In Progress				4/20/2011 9:25:25 AM				
Solis, Lorenzo		need to ck. unit in work rm 300-wing it will not stay on							
Danny Miranda									
<b>Count: 18 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>70</b>	<b>Total for Vado ES</b>			<b>0</b>	<b>\$0.00</b>
<b>Count: 1244 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>73</b>	<b>Grand Total</b>			<b>88</b>	<b>\$2,860.75</b>