

Work Order ID 73234

Location Desert View ES

Request Information

Request Description Vandalism
 13 broken square glasses
 12; 10 by 10 single glass
 1; 13 by 15 single glass
 7; 20 by 21 window screen

Requested By Ruben Ortiz
 Location Desert View ES
 Building

Requester Email rortiz@gisd.k12.nm.us
 Emergency? No

Submittal Date 5/16/2011 12:00:00AM
 Created On 5/16/2011 9:15:23AM

Req. Completion 5/16/2011 12:00:00AM
 Deferred Until
 Deferred By

Area Description
 Area Number

Created By Ruben Ortiz
 Craft Glass\Window Repairs

Custom Category

Budget/Code Assignment Information

Project Code
 Project Description
 Status Complete
 Status Last Change 5/19/2011 11:38:29AM
 Budget Code
 Budget Description
 Purpose Description Vandalism
 Priority Description Medium
 Group
 Classification
 Type

Number of File 0
 Attachments

Equipment Item No.
 Equipment Name
 Assignment To Ronquillo, Ruben
 Action Taken Purchased and del

Costs Information (Actual vs. Estimate)

Estimated Costs	\$0.00	Actual Costs	\$442.50
Estimated Hours	0	Actual Hours	0.50
Estimated Start Date	5/16/2011	Actual Completion Date	5/16/2011
Est. Completion Date		Total Costs	\$442.50

Work Order ID 73234

Labor Transactions

Date	Description	Hours	Rate	Total
5/16/2011	Ruben Ronquillo	0.50	\$25.00	\$12.50
				\$12.50

Material Transactions

Date	Item Number	Trns Type	Qty	Each	Sales	Total
Pool	Item Desc	Inv/ Ref. No.			Tax	
Budget Code	Description	SupplierName			Shipping	
Budget Code Desc					Other	
					Charges	
5/16/2011		Materials	1.00	\$430.00	\$0.00	\$430.00
		3388			\$0.00	
	GLASS	SUNCITY GLASS			\$0.00	
						\$430.00

Email Sent
Message