

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony - On Track Pre-K</b>									
81192					11/17/2011		83		\$0.00
Medium	Work In Progress	playground			11/17/2011 11:46:51				
Ontiveros, Guadalupe		The playground at Anthony PreK the sand to be level out.							
<u>Lucia Almeraz</u>									
83019					1/20/2012		19		\$0.00
Medium	Work In Progress				1/20/2012 2:21:17 PM				
Ronquillo, Ruben		Marquee has been vandalized, has a hole in it. - We need to replace and correct the wording. Check with Ann Steinhoff. I believe it should read "Anthony On-Track Pre-K Center"							
<u>Alfredo Holguin</u>									
82889		Athletic Field			1/18/2012		21		\$0.00
High	Work In Progress				1/18/2012 8:24:00 AM				
Ontiveros, Guadalupe		storage needs ramp, plywood is broken-safety.							
<u>Guadalupe Ontiveros</u>									
<b>Count: 3 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>41</b>		<b>Total for Anthony - On Track Pre-K</b>	<b>0</b>		<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
83656					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:02 AM					
Villalobos, Hector	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83657					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:02 AM					
Villalobos, Hector	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83231					1/26/2012		13		\$0.00
Medium	Work In Progress			1/26/2012 10:30:55 AM					
Villalobos, Hector	No parking Sign on North Street has been graffitied and torn down. Replace ASAP								
<u>Alfredo Holguin</u>									
83152					1/25/2012		14		\$0.00
Medium	Work In Progress	SPED OFFICE		1/25/2012 7:37:59 AM					
Villalobos, Hector	INSTALL WHITE BOARD IN CAFETERIA (SEE MARGARET)								
<u>Margaret Villalobos</u>									
83575					2/3/2012		5		\$0.00
Medium	Work In Progress	SPED		2/3/2012 1:58:51 PM					
Villalobos, Hector	OUTSIDE THE BACK DOOR IS A LONG BLACK CORD THAT NEEDS TO BE REMOVED (HAZARD)								
<u>Margaret Villalobos</u>									
82136		Classroom			12/15/2011		55		\$0.00
Medium	Work In Progress			12/15/2011 8:40:00 AM					
Carrasco, Danny	I need to order filters upper primary heater fan coils 9x33, 9x31, 9x19								
<u>Hector Villalobos</u>									
81831		Athletic Field			12/7/2011		63		\$0.00
Medium	Work In Progress			12/7/2011 8:06:28 AM					
Aldaz, Bobby	need to over seed soccer field for spring. as per mr.munoz								
<u>Guadalupe Ontiveros</u>									
81861					12/7/2011		63		\$0.00
Medium	Work In Progress			12/7/2011 3:13:42 PM					
Lozoya, Manny	Need to change lock on mail box .Not working with new key								
<u>Hector Villalobos</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
83425					1/31/2012		8		\$0.00
Medium	Work In Progress	SPED OFFICE		1/31/2012 9:49:45 AM					
Flores, Pete	CHANGE WIPER BLADES ON SPED CAR #104 (BARNEY)								
<u>Margaret Villalobos</u>									
82257					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:19 AM					
Villalobos, David	Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83154		Portables			1/25/2012		14		\$0.00
Medium	Work In Progress			1/25/2012 7:50:50 AM					
Appelzoller, Fred	upper primary pts 3,4 need water heater for bathrooms								
<u>Hector Villalobos</u>									
82456		Restroom (Girls)			1/6/2012		33		\$0.00
Medium	Work In Progress	SPED OFFICE		1/6/2012 10:25:36 AM					
Appelzoller, Fred	LAST SINK IN THE WOMEN'S BATHROOM IN THE SPED OFFICE BUILDING IS LEAKING I HAVE PLACED A DO NOT USE SIGN ON IT FOR NOW								
<u>Margaret Villalobos</u>									
82399		Pump House			1/5/2012		34		\$0.00
Medium	Work In Progress			1/5/2012 9:31:02 AM					
Appelzoller, Fred	Remove cutoff that are not be used, that the pump house, old main								
<u>Hector Villalobos</u>									
82099		Portables			12/14/2011		56		\$0.00
Medium	Work In Progress			12/14/2011 1:29:53 PM					
Sotelo, Enrique	PTS 1to 4 need to replace out side light fixture								
<u>Hector Villalobos</u>									
82665					1/11/2012		28		\$0.00
Medium	Work In Progress			1/11/2012 8:25:29 AM					
Sotelo, Enrique	NEEDS BUZZARD INSTALL OUTSIDE IF BACK DOOR. SNP MANAGER BECKY A. 882.3507								
<u>Maritza Gonzalez</u>									
81902					12/8/2011		62		\$0.00
Medium	Work In Progress			12/8/2011 2:24:10 PM					
Lozoya, Manny	Upper primary Teachers lounge need to change lock on door								
<u>Hector Villalobos</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
82052					12/13/2011		57		\$0.00
Medium	Work In Progress			12/13/2011 11:42:53					
Lozoya, Manny	WE ENTERED A WORK ORDER (81785) ON 12/5/11 REQUESTING A KEY FOR OUR MAIL BOX, THE KEY WAS PICKED UP BUT HAVE HAS NOT YET BEEN RETURNED								
Jessica Lopez									
75596					7/20/2011		203		\$0.00
Medium	Work In Progress	PRE-K		7/20/2011 3:39:41 PM					
Lozoya, Manny	PLEASE CHANGE ALL PRE-K DOORS TO H AND PORTABLES 1-8								
Jessica Lopez									
75321					7/12/2011		211		\$0.00
Medium	Work In Progress	New Classroom		7/12/2011 9:06:21 AM					
Lozoya, Manny	New cores (with new keys) need to be installed at the new classroom building. Please coordinate with contractor - Kerry Smith / Wooten Construction (575) 650-7779.								
Peggy Jo Hernandez									
77219					8/22/2011		170		\$0.00
Medium	Work In Progress	78 Building		8/22/2011 12:19:39 PM					
Lozoya, Manny	Cores need to be installed in the AE 78 building. Please coordinate with Contractor - Kerry Smith / Wooten Construction (575) 650-7779								
Peggy Jo Hernandez									
82674					1/11/2012		28		\$0.00
Medium	Work In Progress			1/11/2012 11:48:23 AM					
Lozoya, Manny	KA31 KEY NEEDED FOR MELISSA FLAVIAN SPEECH THERAPIST (LUCKY'S OFFICE- VILLAGE)								
Jessica Lopez									
83687					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:14 AM					
Apodaca, Mario	Monthly - Anthony ES - Monthly Meter Readings - Refer to PM schedule details.								
Margret Villalobos									
81936		Classroom			12/9/2011		61		\$0.00
Medium	Work In Progress			12/9/2011 11:48:42 AM					
Gonzalez, Salvador	need some rods made to lock TVs in every class room								
Hector Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
83490					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 1:18:20 PM					
Ambriz, Juan	On February 8, 2012, please pick-up 5-12 boxes of Science Adoption material from Anthony Elementary.								
<u>Yolie Jacquez</u>									
82666					1/11/2012		28		\$0.00
Medium	Work In Progress			1/11/2012 8:29:51 AM					
Lozoya, Manny	RESTROOM IN KITCHEN AREA NEEDS A DOOR KNOB THAT CAN BE LOCKED/UNLOCKED FROM BOTH SIDES . SNP MANAGER BECKY A. 882.3507								
<u>Maritza Gonzalez</u>									
83574					2/3/2012		5		\$0.00
Medium	Work In Progress	SPED OFFICES		2/3/2012 1:56:58 PM					
Lara, Ralph	DOOR STOPS NEED TO BE REPLACED IN BOTH BATHROOMS IN THE SPED BUILDING								
<u>Margaret Villalobos</u>									
83655					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:01 AM					
Villalobos, Hector	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
80274	Pump House				10/27/2011		104		\$0.00
Medium	Work In Progress			10/27/2011 7:50:19 AM					
Lozoya, Manny	Pump house needs a door with door jamb								
<u>Hector Villalobos</u>									
75357	Main Building				7/13/2011		210		\$0.00
Medium	Work In Progress			7/13/2011 6:29:09 AM					
Lozoya, Manny	mld blg remove all hardware from doors								
<u>Hector Villalobos</u>									
81393	Main Building				11/28/2011		72		\$0.00
Medium	Work In Progress			11/28/2011 12:32:46					
Sotelo, Enrique	need more lighting in upper primary area (village) talked to ralph gallegos advise to send work oder								
<u>David Vega</u>									
80000	Main Building				10/20/2011		111		\$0.00
Medium	Work In Progress			10/20/2011 8:52:59 AM					
Lozoya, Manny	need lock for drive in gate at upper primary gate (village)								
<u>David Vega</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
80001	Main Building				10/20/2011		111		\$0.00
Medium	Work In Progress				10/20/2011 8:54:38 AM				
Lozoya, Manny		need 2 12" chains for new walk through gates							
David Vega									
83742	Main Building				2/6/2012		2		\$0.00
Medium	Work In Progress				2/6/2012 3:29:37 PM				
Ontiveros, Guadalupe		please remove canopy frames and re-locate benches. thank you							
Michael Munoz									
82402	Main Building				1/5/2012		34		\$0.00
Medium	Work In Progress				1/5/2012 10:56:37 AM				
Flores, Pete		need fuel for truck 79							
David Vega									
77061	Cafeteria				8/17/2011		175		\$0.00
Medium	Work In Progress				8/17/2011 1:56:21 PM				
Lozoya, Manny		New cafeteria pad lock chargelock from CD 30 to CD5							
Hector Villalobos									
83004	Original Main	Office			1/20/2012		19		\$0.00
Medium	Work In Progress				1/20/2012 10:12:53 AM				
Solis, Lorenzo		Sped office need two ventilation vents 18x12							
Hector Villalobos									
83748	Original Main				2/6/2012		2		\$0.00
High	Work In Progress				2/6/2012 3:33:03 PM				
Solis, Lorenzo		staff is complaining that the rooms are to cold. that boiler shuts off to soon but fans continue to throw cold air.please check. thanks							
Michael Munoz									
83270	Original Main	Restroom (Girls)			1/27/2012		12		\$0.00
Medium	Work In Progress				1/27/2012 7:51:16 AM				
Appelzoller, Fred		old main grils bathroom sink is clog need cable to uncolg sink							
Hector Villalobos									
82737	Main Building	Hallway/Corridor			1/12/2012		27		\$0.00
Medium	Work In Progress				1/12/2012 3:29:20 PM				
Lozoya, Manny		need to change new locks on storage to best locks							
Hector Villalobos									
<b>Count: 39 Work Orders</b>		<b>Avg. Age of WO's 55</b>		<b>Total for Anthony ES</b>			<b>0</b>	<b>\$0.00</b>	

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Berino ES</b>									
78960	Main Building	Portables			9/29/2011		132		\$0.00
Medium	Work In Progress			9/29/2011 7:48:50 AM					
Sotelo, Enrique	Run power supply to portable, a new refrigeration unit will be install. 208/230 1 phase.								
<u>Lorenzo Solis</u>									
83834	Main Building				2/8/2012		0		\$0.00
Medium	Work In Progress			2/8/2012 10:02:03 AM					
Sanchez, Raul	Need a work order to request parts for water filtration units at BE & GHS mechanical rooms. Thanks, Raul								
<u>Raul Sanchez</u>									
83775	Classroom				2/7/2012		1		\$0.00
Medium	Work In Progress	147		2/7/2012 10:34:50 AM					
Gonzalez, Salvador	RM#147-SALLY DEZTEL-2 BOARDS IN THE RAMP ARE FALLING APART NEED TO BE REPLACED SOON.								
<u>Maribel Chavez</u>									
83475					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 9:06:34 AM					
Miranda, Danny	FENCE HAS A BIG HOLE NEEDS TO GET FIXED								
<u>Jimmy Cortez</u>									
82277					1/1/2012	1/22/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:27 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83606					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:42 AM					
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82218					1/1/2012	1/7/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:00 AM					
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

---

**Location: Berino ES**


---

81080					11/15/2011		85		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/15/2011 3:36:49 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny	MR MANNY LOZOYA SIR PER MR VALTIERRA NEED TO REMOVE ALL HARDWARE FROM OUTSIDE DOOR LIBRARY ALSO NEED TO INSTALL DOOR HANDAL RESTROOM EAST WING THANK YOU SIR AND GOD BLESS								
---------------	--	--	--	--	--	--	--	--	--

Adan Duran

---

83730					2/6/2012		2		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/6/2012 9:49:36 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Juan	pick up gatorbox it is full								
--------------	-----------------------------	--	--	--	--	--	--	--	--

Jimmy Cortez

---

81184					11/17/2011		83		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/17/2011 9:13:51 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny	MR MANNY LOZOYA SIR NEED TO REPAIR THE BACK STORAGE ROOM DOOR NUB PART OF IT WAS REMOVED THANK YOU SIR AND GOD BLESS								
---------------	--	--	--	--	--	--	--	--	--

Adan Duran

---

83773					2/7/2012		1		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/7/2012 9:11:47 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Danny	MOISTURE LEAKING FROM FREEZER IS LEAKING. SNP MANAGER ELSA C. 882.2417								
---------------	--	--	--	--	--	--	--	--	--

Maritza Gonzalez

---

80376					10/31/2011		100		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/31/2011 8:45:44 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben	RUBEN RONQUILLO SIR HAD A BREAK IN NEED SOME GLASS REPLACED LIBRARY 371/4"x471/4x1/4" one 71/4"x25"x1/4" need five ROOM 120-124-126-128-AND WORK ROOM THANK YOU SIR AND GOD BLESS CASE NO 2011-11656								
------------------	--	--	--	--	--	--	--	--	--

Adan Duran

---

83707					2/5/2012		3		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/5/2012 12:18:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sanchez, Raul	Monthly - Berino ES - Monthly Meter Readings - Refer to PM schedule details.								
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

---

80766					11/7/2011		93		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/7/2011 10:51:24 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny	MR MANNY LOZOYA SIR NEED A KEY FOR CABINET IN THE LIBRARY FOR MRS SANCHEZ GOT MISSED PLACED THANK YOU SIR AND GOD BLESS								
---------------	---	--	--	--	--	--	--	--	--

Adan Duran

2/8/2012 1:26:25 PM



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Berino ES</b>									
81313					11/22/2011		78		\$0.00
Medium	Work In Progress			11/22/2011 8:14:22 AM					
Lozoya, Manny	MR MANNY LOZOYA SIR MR VALTIERRA WOULD LIKE TWO LOCKS TO LOCK EARLY CHILDHOOD PLAYGROUND FENCE IN BACK OF LIBRARY THANK YOU SIR AND GOD BLESS								
Adan Duran									
83234					1/26/2012		13		\$0.00
Medium	Work In Progress	Northeast		1/26/2012 11:48:54 AM					
Lozoya, Manny	Need to install 2 cores in Northeast Hallway - Staff Restroom please coordinate with contractor - ESA Construction/ Roy Hargrove (915) 549-4614 or Eric Clifton (915) 549-4886								
Peggy Jo Hernandez									
81351					11/22/2011		78		\$0.00
Medium	Work In Progress			11/22/2011 3:32:35 PM					
Sotelo, Enrique	MR ENRIQUE SOTELO SIR NEED TO INSTALL OUTSIDE LIGHTS EASTSIDE BY BUS TURN AROUND BETWEEN CAMERA AND EAST ENTRANCE TO DARK AT NIGHT THANK YOU SIR AND GOD BLESS								
Adan Duran									
82957					1/19/2012		20		\$0.00
Medium	Work In Progress			1/19/2012 1:56:51 PM					
Sotelo, Enrique	OFFICE- ELECTRICAL OUTLET IN THE BACK ROOM OR THE OFFICE IS NOT WORKING.								
Maribel Chavez									
78760		Classroom			9/26/2011		135		\$0.00
Medium	Work In Progress	118		9/26/2011 10:27:16 AM					
Sotelo, Enrique	RM#118 - MYRA LAWRENCE- NEEDS TO HAVE THE REST OF WIRING /CABLING DONE								
Maribel Chavez									
78761		Classroom			9/26/2011		135		\$0.00
Medium	Work In Progress	143		9/26/2011 10:27:41 AM					
Sotelo, Enrique	RM#143- MARTHA FRANCO-NEEDS TO HAVE THE REST OF WIRING /CABLING DONE								
Maribel Chavez									
78762		Classroom			9/26/2011		135		\$0.00
Medium	Work In Progress	113		9/26/2011 10:28:06 AM					
Sotelo, Enrique	RM#113- SHAUNA TORRES- NEEDS TO HAVE THE REST OF WIRING /CABLING DONE								
Maribel Chavez									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Berino ES</b>								
78763		Classroom			9/26/2011		135		\$0.00	
Medium	Work In Progress	127		9/26/2011 10:28:57 AM						
Sotelo, Enrique		RM#127- SANDI HINOJOS-NEEDS TO HAVE THE REST OF WIRING /CABLING DONE								
Maribel Chavez										
78764		Classroom			9/26/2011		135		\$0.00	
Medium	Work In Progress	142		9/26/2011 10:29:24 AM						
Sotelo, Enrique		RM#142- VERONICA BAUTISTA-NEEDS TO HAVE THE REST OF WIRING /CABLING DONE								
Maribel Chavez										
78765		Classroom			9/26/2011		135		\$0.00	
Medium	Work In Progress	106		9/26/2011 10:32:27 AM						
Sotelo, Enrique		RM#106 - IRMA SANCHEZ - NEEDS TO HAVE THE REST OF WIRING /CABLING DONE								
Maribel Chavez										
83431					1/31/2012		8		\$0.00	
Medium	Work In Progress			1/31/2012 11:07:33 AM						
Appelzoller, Fred		Need to repair four outside drinking fountains, cut off valves and spiketts.								
Danny Miranda										
82142					12/15/2011		55		\$0.00	
Medium	Work In Progress			12/15/2011 1:11:48 PM						
Appelzoller, Fred		DRAINS ARE STILL BACKING UP IN KITCHEN AREA. AS PER SNP MANAGER BLDG. MECHANIC TOOK A LOOK AT IT.								
Maritza Gonzalez										
82258					1/1/2012	2/1/2012	38		\$0.00	
Medium	Work In Progress			1/1/2012 12:44:19 AM						
Villalobos, David		Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
82217					1/1/2012	1/9/2012	38		\$0.00	
Medium	Work In Progress			1/1/2012 12:44:00 AM						
Duran, Adan		Monthly - Berino ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos										
81599					12/2/2011		68		\$0.00	
Medium	Work In Progress			12/2/2011 8:51:04 AM						
Lozoya, Manny		Northeast Wing is ready for cores to be installed. Please coordinate with Contractor - ESA / Roy Hargrove 915.549.4614								
Peggy Jo Hernandez										

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location: Berino ES</b>										
83474					2/1/2012		7		\$0.00	
Medium	Work In Progress				2/1/2012 9:01:00 AM					
Miranda, Danny	Transport two cafeteria tables from San Miguel to Berino.									
<u>Jimmy Cortez</u>										
82219					1/1/2012	1/9/2012	38		\$0.00	
Medium	Work In Progress				1/1/2012 12:44:01 AM					
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
82220					1/1/2012	1/9/2012	38		\$0.00	
Medium	Work In Progress				1/1/2012 12:44:01 AM					
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
83607					2/5/2012	2/13/2012	3		\$0.00	
Medium	Work In Progress				2/5/2012 12:17:43 AM					
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
83608					2/5/2012	2/13/2012	3		\$0.00	
Medium	Work In Progress				2/5/2012 12:17:43 AM					
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
83605					2/5/2012		3		\$0.00	
Medium	Work In Progress				2/5/2012 12:17:42 AM					
Duran, Adan	Monthly - Berino ES - Clothes Dryer (Monthly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
82221					1/1/2012		38		\$0.00	
Medium	Work In Progress				1/1/2012 12:44:02 AM					
Duran, Adan	Monthly - Berino ES - Clothes Dryer (Monthly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
<b>Count: 36 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>53</b>				<b>Total for Berino ES</b>	<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral Elem East Pre-K</b>							
81276		Classroom			11/21/2011		79		\$0.00
Medium	Work In Progress				11/21/2011 8:07:28 AM				
Gallegos, Rafael	Warranty WO Room 103 window is loose needs double sided tape.								
Alfredo Ortiz									
75619					7/21/2011		202		\$0.00
Medium	Work In Progress				7/21/2011 8:09:39 AM				
Estrada, Jesus	VCT tile needs to be replaced, loose tiles double portable (68 DMIR) Classroom P #1 and P #2. Thank you					2/1/12 - WILL BE TAKEN CARE OF DURING SUMMER BREAK			
Guillermo Hernandez									
75620					7/21/2011		202		\$0.00
Medium	Work In Progress				7/21/2011 8:16:14 AM				
Estrada, Jesus	VCT tile needs to be replaced, loose and univen floor tiles. Double portable (69 DM1R) Classrooms P #3 and P #4. Thank you.					2/1/12 - WILL BE TAKEN CARE OF DURING SUMMER BREAK			
Guillermo Hernandez									
<b>Count: 3 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>161</b>		<b>Total for Chaparral Elem East Pre-K</b>	<b>0</b>		<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
83821					2/8/2012		0		\$0.00
Medium	Work In Progress				2/8/2012 8:10:23 AM				
Carrasco, Danny	REQUESTING GASOLINE FOR WORK TRUCK 10 GAL.THANKS								
Paul Quinones									
81290					11/21/2011		79		\$0.00
Medium	Work In Progress				11/21/2011 2:41:48 PM				
Estrada, Jesus	FLOOR TILE IN PORTABLE #1 NEEDS TO BE REPLACED, TILES ARE COMING UP FROM THE FLOOR. REQUESTING 12 BOXES OF 12"X12" CERAMIC TILES								
Paul Quinones									
83700					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:19 AM				
Quinones, Paul	Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
81750					12/4/2011	12/10/2011	66		\$0.00
Medium	Work In Progress				12/4/2011 12:16:58 AM				
Quinones, Paul	Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
80792					11/7/2011		93		\$0.00
Medium	Work In Progress				11/7/2011 3:46:35 PM				
Lara, Ralph	MECHANICAL RM. INSIDE KITCHEN METAL DOOR FRAME IS RUSTED FROM THE BOTTOM AND WOODEN DOOR NEEDS TO BE REPLACED. DOOR IS CRACKED REQUESTING DOOR AND FRAME TO BE REPLACED								
Paul Quinones									
81752					12/4/2011	12/12/2011	66		\$0.00
Medium	Work In Progress				12/4/2011 12:16:59 AM				
Quinones, Paul	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
83699					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:18 AM				
Quinones, Paul	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
81987					12/11/2011	12/27/2011	59		\$0.00
Medium	Work In Progress			12/11/2011 12:14:24					
Quinones, Paul	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83002					1/20/2012		19		\$0.00
Medium	Work In Progress			1/20/2012 9:36:10 AM					
Quinones, Paul	BROKEN EQUIPMENT MAIN PLAYGROUND SAFETY HAZARD								
<u>Paul Quinones</u>									
82896					1/18/2012		21		\$0.00
Medium	Work In Progress			1/18/2012 10:11:53 AM					
Orozco, Danny	Kitchen faucet and steam line leaking.								
<u>Maritza Gonzalez</u>									
80543					11/4/2011		96		\$0.00
Medium	Work In Progress			11/4/2011 8:20:04 AM					
Orozco, Danny	Serving line is leaking water. SNP Manager Esther C. 824.0048.								
<u>Maritza Gonzalez</u>									
75779					7/25/2011		198		\$0.00
Medium	Work In Progress			7/25/2011 1:21:24 PM					
Orozco, Danny	Chemical room wall needs to be replace with RFP, it is falling apart. . SNP Manager Esther C. 824.0048								
<u>Maritza Gonzalez</u>									
80790					11/7/2011		93		\$0.00
Medium	Work In Progress			11/7/2011 3:42:36 PM					
Lozoya, Manny	DOOR CLOSER IN KITCHEN REAR ENTRANCE WILL NOT CLOSE SCREEN DOOR FROM INSIDE.KITCHEN.								
<u>Paul Quinones</u>									
82033					12/12/2011		58		\$0.00
Medium	Work In Progress			12/12/2011 3:49:56 PM					
Lozoya, Manny	DOOR IN CAFETERIA WONT OPEN WITH KEY NEXT TO THE FRONT ENTRANCE PLEASE CHK THANKS								
<u>Paul Quinones</u>									
79608					10/11/2011		120		\$0.00
Medium	Work In Progress			10/11/2011 8:34:58 AM					
Quinones, Paul	REQUESTING 15 GALLON SPRAYER, FOR WEED CONTROL FOR ALL 3 SCHOOLS CH E, CH.M, AND D.T.								
<u>Paul Quinones</u>									
2/8/2012 1:26:25 PM									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
76918	Main Building	Classroom			8/15/2011		177		\$0.00
Medium	Work In Progress	107		8/15/2011 9:32:45 AM					
Lozoya, Manny		need extra key for room 107. see front office							
Jennifer Corral									
76920	Main Building	Office			8/15/2011		177		\$0.00
Medium	Work In Progress	office		8/15/2011 9:34:06 AM					
Lozoya, Manny		need extra N key for front office for Administrative Intern. See Front office							
Jennifer Corral									
81456					11/29/2011		71		\$0.00
Medium	Work In Progress			11/29/2011 1:42:12 PM					
Lozoya, Manny		LOCK TO FRONT ROLL GATE, LOCK IS HARD TO OPEN WITH KEY. REQUESTING NEW LOCK							
Paul Quinones									
80488					11/2/2011		98		\$0.00
Medium	Work In Progress			11/2/2011 3:52:49 PM					
Ontiveros, Guadalupe		REQUESTING PRIMARY FILL IN DIRT NEXT TO THE MAIN ENTRANCE DOUBLE DOOR CHAIN LINK FENCE AREAS.							
Paul Quinones									
77180					8/19/2011		173		\$0.00
Medium	Work In Progress			8/19/2011 3:41:04 PM					
Flores, Pete		Need to replace front tires to mower #0403. Tires are dry and cracked. Size 23 x 10.50 - 12 NHS. Thank you							
Guillermo Hernandez									
82850					1/17/2012		22		\$0.00
Medium	Work In Progress			1/17/2012 3:03:16 PM					
Quinones, Paul		REQUESTING TRIM SIDING FOR 400 WING 6"X16' 14 TOTAL							
Paul Quinones									
82439					1/6/2012		33		\$0.00
Medium	Work In Progress			1/6/2012 7:40:57 AM					
Quinones, Paul		no heat 416							
Paul Quinones									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
83274					1/27/2012		12		\$0.00
Medium	Work In Progress				1/27/2012 9:34:21 AM				
Quinones, Paul	REQUESTING SPRAY WASHER TO CHIP PAINT FROM TRIM IN E-WING.TO START PAINTING TRIM								
<u>Paul Quinones</u>									
83698					2/5/2012		3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:18 AM				
Quinones, Paul	Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83701					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:19 AM				
Quinones, Paul	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83770					2/7/2012		1		\$0.00
Medium	Work In Progress				2/7/2012 8:42:40 AM				
Quinones, Paul	REQUESTING FILTERS FOR HEATERS RESTOCK								
<u>Paul Quinones</u>									
83771					2/7/2012		1		\$0.00
Medium	Work In Progress				2/7/2012 8:45:20 AM				
Quinones, Paul	REQUESTING HEATING ONLY BI-METAL T-STATS HORIZONTAL TYPE. REQUESTING 10								
<u>Paul Quinones</u>									
81751					12/4/2011	12/12/2011	66		\$0.00
Medium	Work In Progress				12/4/2011 12:16:58 AM				
Quinones, Paul	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81749					12/4/2011		66		\$0.00
Medium	Work In Progress				12/4/2011 12:16:57 AM				
Quinones, Paul	Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81273					11/21/2011		79		\$0.00
Medium	Work In Progress				11/21/2011 7:58:57 AM				
Quinones, Paul	treatment plant is no longer in use. please remove tarps on fence and dispose of. thank you								
<u>Michael Munoz</u>									

2/8/2012 1:26:25 PM



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
82256					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress				1/1/2012 12:44:19 AM				
Villalobos, David	Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
83410					1/30/2012		9		\$0.00
Medium	Work In Progress				1/30/2012 4:03:00 PM				
Ontiveros, Joe	WATER LEAKING BEHIND WALL IN RM.210.UNDERNETH SINK								
Paul Quinones									
83132					1/24/2012		15		\$0.00
Medium	Work In Progress				1/24/2012 3:44:20 PM				
Ontiveros, Joe	CHK WATER HEATER NO HOT WATER IN CLASS RMS. CIRCULATING PUMP IS OUT,AND THE IGNITER. WATER HEATER LOCATED IN THE 200 WING								
Paul Quinones									
83447					1/31/2012		8		\$0.00
Medium	Work In Progress				1/31/2012 3:27:13 PM				
Ontiveros, Joe	FLOOR DRAIN CLOGGED AND SMELLS OF ALOT OF SEWER IN STAFFS REST RM. FRONT OFFICE.								
Paul Quinones									
77520					8/29/2011		163		\$0.00
Medium	Work In Progress				8/29/2011 1:54:15 PM				
Ontiveros, Joe	Need to replace rusted plugs on the sinks in kinder hallway. Thank yuo								
Guillermo Hernandez									
83772					2/7/2012		1		\$0.00
Medium	Work In Progress				2/7/2012 8:52:34 AM				
Sotelo, Enrique	5BX'S OF 25 LIGHTS F32 T-8'S RM.211 ELECTRICAL OUTLET IS CONTROLLED BY WALL SWITCH.OUTLET IS USED FOR THE NEW PROJECTOR SCREEN THAT WAS INSTALLED BY TECHNOLOGY.NEED NEW POWER SOURCE								
Paul Quinones									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
83167					1/25/2012		14		\$0.00
Medium	Work In Progress			1/25/2012 1:07:39 PM					
Solis, Lorenzo	REQUESTING SHEETMETAL RUNNERS FOR FRESH AIR HOODS 22 @ 48" LONG. DAMPER FOR DUCTING FOR HEATING AND COOLING SEASONS 1 @ 32"X 32"								
Paul Quinones									
83278					1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 11:11:24 AM					
Lozoya, Manny	REQUESTING NEW LOCK FOR BACK GATES NORTH END.								
Paul Quinones									
80339					10/28/2011		103		\$0.00
Medium	Work In Progress			10/28/2011 2:43:43 PM					
Lozoya, Manny	REQUESTING CAM LOCKS FOR SECRETARYS OFFICES,AND CABINETS								
Paul Quinones									
81011					11/14/2011		86		\$0.00
Medium	Work In Progress			11/14/2011 11:45:05					
Lozoya, Manny	NEED TO SECURE DOOR TO CLASS RM.106 TEACHERS REQUESTING NEW KEY.THANKS								
Paul Quinones									
80222					10/26/2011		105		\$0.00
Medium	Work In Progress			10/26/2011 8:40:31 AM					
Quinones, Paul	PAINTING IS NEEDED EXTERIOR WALLS,AND TRIM.E-WING REQUESTING PAINT FOR THIS PROJECT.								
Paul Quinones									
81753					12/4/2011		66		\$0.00
Medium	Work In Progress			12/4/2011 12:16:59 AM					
Quinones, Paul	Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.								
Margret Villalobos									
82401					1/5/2012		34		\$0.00
Medium	Work In Progress			1/5/2012 9:53:19 AM					
Solis, Lorenzo	NEED SPACE HEATER IN LAUNDRY RM CIELING TYPE PRE HUNG W/ALLTHREAD								
Paul Quinones									
<b>Count: 43 Work Orders</b>			<b>Avg. Age of WO's 61</b>			<b>Total for Chaparral ES</b>	<b>0</b>		<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
80270					10/26/2011		105		\$0.00
Medium	Work In Progress			10/26/2011 4:19:13 PM					
Solis, Lorenzo	please install exhaust on laser machine in computer lab. thankyou								
Michael Munoz									
75288					7/11/2011		212		\$0.00
Medium	Work In Progress			7/11/2011 11:37:19 AM					
Ontiveros, Joe	SCIENCE CLASS RM. D-7 WATER FAUCETS IN CLASS RM. NEED TO BE REPLACED.IF YOU CAN BEFORE SCHOOL STARTS ON AUG.4								
Paul Quinones									
75289					7/11/2011		212		\$0.00
Medium	Work In Progress			7/11/2011 11:43:22 AM					
Ontiveros, Joe	WE NEED TO CHK ISIMET CONTROLS IN ALL SCIENCE CLASS RMS SO THAT THE SOLINOID VALVES CAN BE REPLACED. AND CHK ALL SCIENCE CLASS RMS. THAT DO NOT HAVE HOT ,AND COLD DOMESTIC WATER IN CLASS RM.								
Paul Quinones									
83621					2/5/2012	2/8/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:48 AM					
Ortiz, Alfredo	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
83749		Athletic Field			2/6/2012		2		\$0.00
Medium	Work In Progress			2/6/2012 3:41:44 PM					
Ontiveros, Joe	Need to re-ancor water fountain and re-pipe water lines. Fountain tipped over. Out-side basket-ball court.								
Alfredo Ortiz									
82276					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:27 AM					
Villalobos, David	Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
79543					10/10/2011		121		\$0.00
Medium	Work In Progress			10/10/2011 6:20:46 AM					
Flores, Pete	CHARGER SR 09-89 TO GOLF CART NOT WORKING								
Jesus Urquidi									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
83014					1/20/2012		19		\$0.00
Medium	Work In Progress			1/20/2012 12:14:32 PM					
Ortiz, Alfredo	need to remove trash and sand from roof through out school.								
<u>Alfredo Ortiz</u>									
78472					9/18/2011		143		\$0.00
Medium	Work In Progress			9/18/2011 12:16:58 AM					
Ontiveros, Guadalupe	Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82189					12/18/2011		52		\$0.00
Medium	Work In Progress			12/18/2011 12:16:25					
Garcia, Jose	Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83768		Athletic Field			2/7/2012		1		\$0.00
Medium	Work In Progress			2/7/2012 8:19:34 AM					
Garcia, Jose	need to replaced sprinklers on fields that are not working.								
<u>Guadalupe Ontiveros</u>									
82138		Classroom			12/15/2011		55		\$0.00
Medium	Work In Progress	sports field			12/15/2011 11:01:48				
Garcia, Jose	overseed the softball, baseball, p.e. (practice) and soccer fields with winter rye grass (sanchez)								
<u>Rosa Quezada</u>									
83435		Hallway/Corridor			1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 12:13:08 PM					
Ortiz, Alfredo	Replace filter on roof-top heaters.								
<u>Alfredo Ortiz</u>									
82223					1/1/2012		38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:03 AM					
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83616					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:46 AM					
Ortiz, Alfredo	Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral HS</b>									
83620					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:48 AM					
Ortiz, Alfredo	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83617					2/5/2012	3/7/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:47 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82935					1/19/2012		20		\$0.00
Medium	Work In Progress			1/19/2012 7:46:31 AM					
Ortiz, Alfredo	Need to remove sand around curbs throught school.								
<u>Alfredo Ortiz</u>									
83737	A-Wing	Mechanical			2/6/2012		2		\$0.00
Medium	Work In Progress			2/6/2012 1:52:43 PM					
Ortiz, Alfredo	Need to replace thermastats at the Geothermal pumps to see the temperature of water supply and return.								
<u>Alfredo Ortiz</u>									
75964	A-Wing	Classroom			7/28/2011		195		\$0.00
Medium	Work In Progress	A-107		7/28/2011 11:58:57 AM					
Lozoya, Manny	key doesn't open door in A-107 - it opens after several attempts but doesn't close door with key (henry)								
<u>Rosa Quezada</u>									
78091	A-Wing	Hallway/Corridor			9/8/2011		153		\$0.00
Medium	Work In Progress	by attendence		9/8/2011 3:32:11 PM					
Lozoya, Manny	panic bar is loose outside door next to attendance office by cafeteria (urquidi)								
<u>Rosa Quezada</u>									
75470	A-Wing	Office			7/14/2011		209		\$0.00
Medium	Work In Progress	rosa's office		7/14/2011 1:55:14 PM					
Lozoya, Manny	cannot open front main door with ch86 -								
<u>Rosa Quezada</u>									
80130	A-Wing	Office			10/24/2011		107		\$0.00
Medium	Work In Progress			10/24/2011 2:51:23 PM					
Lozoya, Manny	need 5 chm keys. they break easily and i need them as needed for custodial, maintence, security, etc...								
<u>Rosa Quezada</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
79723	A-Wing	Auditorium			10/13/2011		118		\$0.00
Medium	Work In Progress			10/13/2011 8:51:33 AM					
Ontiveros, Joe	need to install water valve for a weter hose infront of office								
Alfredo Ortiz									
83800	A-Wing				2/7/2012		1		\$0.00
Medium	Work In Progress			2/7/2012 3:49:57 PM					
Ortiz, Alfredo	Need to seal several duct joints on the roof.								
Alfredo Ortiz									
82581	C-Wing	Classroom			1/9/2012		30		\$0.00
Medium	Work In Progress	C7		1/9/2012 3:25:43 PM					
Ortiz, Alfredo	There us a crack on the window...water comes in when it rains.(Velarde)		Asp Ruben, completed by Alfredo						
Diana Mendoza									
83498	E-Wing	Hallway/Corridor			2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 3:03:05 PM					
Ronquillo, Ruben	E-wing cyber-cafe window broken 57 in.x 35 3/4 in. 1/4in thick double pain window. approximate.								
Alfredo Ortiz									
82413	E-Wing				1/5/2012		34		\$0.00
Safety	Work In Progress	e- computer lab		1/5/2012 2:58:40 PM					
Solis, Lorenzo	need a vent installed a.s.a.p. in computer lab. this vent is needed to prevent the exhaust and machine fumes from "project lead the way equipment" from causing injury to students. this is the third request. the men come out to look at it but nothing else has been done. (steinert)								
Rosa Quezada									
83013	F-Wing	Restroom (Boys)			1/20/2012		19		\$0.00
Medium	Work In Progress			1/20/2012 12:07:24 PM					
Ortiz, Alfredo	Paint over graffity in boys rest-rooms F and G-wing								
Alfredo Ortiz									
83736	F-Wing	Classroom			2/6/2012		2		\$0.00
Medium	Work In Progress			2/6/2012 1:10:00 PM					
Ontiveros, Joe	Need to rerout water line for Green-house, A/C broken water line in wall.								
Alfredo Ortiz									
76218	F-Wing	Classroom			8/1/2011		191		\$0.00
Medium	Work In Progress			8/1/2011 3:58:42 PM					
Lozoya, Manny	Closets do not lock (montoya)								
Diana Mendoza									
2/8/2012 1:26:25 PM									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
83345	G-Wing	Classroom			1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 3:49:06 PM					
Ortiz, Alfredo	Need to replace Soap dispensers soap has become contaminated, could be a health hazard.								
<u>Alfredo Ortiz</u>									
76301	G-Wing	Classroom			8/2/2011		190		\$0.00
Medium	Work In Progress			8/2/2011 9:41:51 AM					
Quinones, Paul	support bar on teacher, teacher desk broken.								
<u>Diana Mendoza</u>									
82947	Q-Wing	Classroom			1/19/2012		20		\$0.00
Medium	Work In Progress	Construction		1/19/2012 10:56:27 AM					
Ronquillo, Ruben	Please repair 2 Hitachi saws on the construction lab. (Vicki Lopez)								
<u>Diana Mendoza</u>									
83727	Q-Wing	Mechanical			2/6/2012		2		\$0.00
Medium	Work In Progress			2/6/2012 8:31:12 AM					
Solis, Lorenzo	In Q-build. mechanical room a Geothermal pump is leaking water needs seal replaced.								
<u>Alfredo Ortiz</u>									
80239	Q-Wing	Classroom			10/26/2011		105		\$0.00
Medium	Work In Progress			10/26/2011 3:00:26 PM					
Solis, Lorenzo	Freezer in home economic not working True Freezer MO# T-49F Ser# 5043109 Thermostat not good								
<u>Alfredo Ortiz</u>									
81801	R-Wing	Classroom			12/5/2011		65		\$0.00
Medium	Work In Progress			12/5/2011 2:35:30 PM					
Solis, Lorenzo	Need to repair refrigerator at R-5 Home-economice Ms. Adams.								
<u>Alfredo Ortiz</u>									
83315	R-Wing	Classroom			1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 3:13:45 PM					
Solis, Lorenzo	need to recharge heating unit with refrigerant room R-3.								
<u>Alfredo Ortiz</u>									
83499	R-Wing	Mechanical			2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 3:05:41 PM					
Solis, Lorenzo	need to replace air vent at the GEO Thermal tank.								
<u>Alfredo Ortiz</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral HS</b>									
80259	R-Wing				10/26/2011		105		\$0.00
Medium	Work In Progress			10/26/2011 3:48:29 PM					
Sotelo, Enrique	an auto visual production will be held on march 8th, 2012. they will need and electrical distribution panel with 100 amps at the minimum. please purchase material for this work order and leave at site when complete for next years show. contact person on site will be teacher stephen galbadron room r-1. thank you								
<u>Michael Munoz</u>									
81846	R-Wing	Classroom			12/7/2011		63		\$0.00
Medium	Work In Progress	r4		12/7/2011 10:08:19 AM					
Munoz, Michael	needs acoustical pads around on the wall in r4. like the ones in the bad room. needed to eliminate some of the noise to other classrooms...(rueda)				2/7/12 - Mike will look into this work order - A. Ortiz				
<u>Rosa Quezada</u>									
76302	R-Wing	Classroom			8/2/2011		190		\$0.00
Medium	Work In Progress	kitchen		8/2/2011 9:46:01 AM					
Quinones, Paul	Need TV installed(Adams)								
<u>Diana Mendoza</u>									
82948	R-Wing	Classroom			1/19/2012		20		\$0.00
Medium	Work In Progress	R 3		1/19/2012 10:58:54 AM					
Ortiz, Alfredo	please install showcase cabinet in R building entrance hall. Also my room needs paint touch-ups.(Michelle Padget)								
<u>Diana Mendoza</u>									
78663	Field House				9/22/2011		139		\$0.00
Medium	Work In Progress			9/22/2011 10:26:46 AM					
Holguin, Alfredo	Collect Equipment data and inventory per PFSA requirements.								
<u>Alfredo Holguin</u>									
80115	Field House	Mechanical			10/24/2011		107		\$0.00
Medium	Work In Progress			10/24/2011 10:34:26					
Solis, Lorenzo	board on heater bad Train MO# TUX1D120A9601AB SER# 8124PTC7G								
<u>Alfredo Ortiz</u>									
81782	H-Wing	Gym			12/5/2011		65		\$0.00
Medium	Work In Progress			12/5/2011 8:37:05 AM					
Solis, Lorenzo	Ice maching not working in trainers room								
Alfredo Ortiz									



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
82839	H-Wing	Restroom (Boys)			1/17/2012		22		\$0.00
Medium	Work In Progress			1/17/2012 1:29:53 PM					
Ontiveros, Joe	Need to replace two urinla flush-valves not working properly								
<u>Alfredo Ortiz</u>									
83544	H-Wing	Gym			2/2/2012		6		\$0.00
Medium	Work In Progress			2/2/2012 3:25:12 PM					
Ortiz, Alfredo	Need to anchor benches in locker rooms								
<u>Alfredo Ortiz</u>									
82084	H-Wing	Gym			12/14/2011		56		\$0.00
Medium	Work In Progress			12/14/2011 9:33:49 AM					
Munoz, Michael	Need to re-locate cable from basket-ball back-board					2/7/12 - Mike will look into this work order - A. Ortiz			
<u>Alfredo Ortiz</u>									
83831	H-Wing	Library			2/8/2012		0		\$0.00
Medium	Work In Progress			2/8/2012 9:31:04 AM					
Carbajal, Jimmy	I NEED VACCUM BAGS FOR LARGE VACCUMS 32-9 -082-1								
<u>Jesus Urquidi</u>									
83618					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:47 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83434	Pre-K				1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 12:03:55 PM					
Ortiz, Alfredo	Need to sweep sand from side-walk around playground and front of office.								
<u>Alfredo Ortiz</u>									
82589	Pre-K	Restroom (Girls)			1/9/2012		30		\$0.00
Medium	Work In Progress			1/9/2012 3:38:21 PM					
Gallegos, Rafael	Warranty work order Ladies restroom no heat.								
<u>Alfredo Ortiz</u>									
81803	Pre-K	Electrical Room			12/5/2011		65		\$0.00
Medium	Work In Progress			12/5/2011 2:42:41 PM					
Lozoya, Manny	Warranty WO the door coved was broken off need to install The cover is to prevent vandalism.								
<u>Alfredo Ortiz</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
83545	Pre-K	Hallway/Corridor			2/2/2012		6		\$0.00
Medium	Work In Progress				2/2/2012 3:28:07 PM				
Ortiz, Alfredo	Need to weather strip doors sand comes in.								
<u>Alfredo Ortiz</u>									
83223					1/26/2012		13		\$0.00
Medium	Work In Progress				1/26/2012 8:25:56 AM				
Ronquillo, Ruben	Need Acetylene tank and accessories for cooling season								
<u>Alfredo Ortiz</u>									
83619					2/5/2012		3		\$0.00
Medium	Work In Progress				2/5/2012 12:17:47 AM				
Ortiz, Alfredo	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75963					7/28/2011		195		\$0.00
Medium	Work In Progress	all school doors			7/28/2011 11:57:34 AM				
Lozoya, Manny	check all doors - some need adjustments - specially "A" wing courtyard - it stays open (paul)								
<u>Rosa Quezada</u>									
83564					2/3/2012		5		\$0.00
Medium	Work In Progress				2/3/2012 7:58:43 AM				
Gonzalez, Salvador	need to fabricate a stand for the electrical distribution panels for steve galbadron (teacher) this work ord will accompany work order 80259.please makeit with wheels for transporting purposes.thank you								
<u>Enrique Sotelo</u>									
83818		Cafeteria			2/8/2012		0		\$0.00
Medium	Work In Progress				2/8/2012 7:35:28 AM				
Orozco, Danny	was called out to check walk in freezer (not working)								
<u>Danny Orozco</u>									
83302					1/27/2012		12		\$0.00
Medium	Work In Progress				1/27/2012 2:54:32 PM				
Orozco, Danny	DISHWASHER MADE A LOUD NOISE AND STOPPED WORKING, TURNED OFF BUT WILL NOT TURN BACK ON. SNP MANAGER JUANITA M. 824.4461								
<u>Maritza Gonzalez</u>									
79964		Pump House			10/19/2011		112		\$0.00
Medium	Work In Progress				10/19/2011 2:52:08 PM				
Munoz, Michael	At the fire-pump, and at the main panal it reads Controller Trouble ZONE 30 Dis fire pump RM								
<u>Alfredo Ortiz</u>									
2/8/2012 1:26:26 PM									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
78181					9/12/2011		149		\$0.00
Medium	Work In Progress				9/12/2011 9:28:11 AM				
Orozco, Danny	FIRE PUMP STATION IN MAIN BUILDING,CONTROL PANEL NEEDS TO BE REPLACED.DUE TO SPRINKLER LEAK FROM ROOF IN MECHANICAL RM.BEHIND KITCHEN								
Paul Quinones									
<b>Count: 63 Work Orders</b>	<b>Avg. Age of WO's</b>		<b>62</b>	<b>Total for Chaparral HS</b>				<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
82278					1/1/2012	1/22/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:27 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76143					7/31/2011		192		\$0.00
Medium	Work In Progress			7/31/2011 9:25:23 AM					
Sanchez, Raul	Monthly - Chaparral MS - DP-781 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76354					8/3/2011		189		\$0.00
Medium	Work In Progress			8/3/2011 10:27:46 AM					
Gonzalez, Salvador	Please fabricate expanded metal guard around exterior water fountain, located outside the gym door.								
<u>Albert Vallejo</u>									
81563					12/1/2011		69		\$0.00
Medium	Work In Progress			12/1/2011 9:34:35 AM					
Lozoya, Manny	Room 203 - Can not open classroom door.								
<u>Marti Muela</u>									
80800					11/7/2011		93		\$0.00
Medium	Work In Progress			11/7/2011 4:16:38 PM					
Lozoya, Manny	(Chaparral Middle School) Please check and replace missing bolts to door closure to main building door. Teacher's lounge hallway.								
<u>Johnny Acuna</u>									
81660					12/4/2011	12/10/2011	66		\$0.00
Medium	Work In Progress			12/4/2011 12:16:24 AM					
Vallejo, Albert	Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83611					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:44 AM					
Vallejo, Albert	Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81308	Main Building	Classroom			11/21/2011		79		\$0.00
Medium	Work In Progress	ROOM 403		11/21/2011 3:56:44 PM					
Lozoya, Manny	DOOR IS LOCKING TEACHER INSIDE CLASSROOM CANNOT CLOSE DOOR OR ELSE IT WILL LOCK FROM THE INSIDE								
Elena Palacios									

2/8/2012 1:26:26 PM

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
83373	Main Building	Gym			1/30/2012		9		\$0.00
Medium	Work In Progress	locker room			1/30/2012 12:41:42 PM				
Lozoya, Manny		need Key for girls locker room.							
<u>Gidget Mora</u>									
83536	Main Building	Classroom			2/2/2012		6		\$0.00
Medium	Work In Progress	203			2/2/2012 1:22:52 PM				
Lozoya, Manny		Room door lock is not working.							
<u>Gidget Mora</u>									
83374	Main Building	Portables			1/30/2012		9		\$0.00
Medium	Work In Progress	P2			1/30/2012 12:51:09 PM				
Lozoya, Manny		need a key for portable 2							
<u>Gidget Mora</u>									
83778	Main Building	Restroom (Girls)			2/7/2012		1		\$0.00
Medium	Work In Progress				2/7/2012 12:57:35 PM				
Ontiveros, Joe		Restroom lavatory is leaking from Solenoid/ valve. Needs to be replaced.							
<u>Albert Vallejo</u>									
83284	Main Building				1/27/2012		12		\$0.00
Medium	Work In Progress				1/27/2012 1:54:10 PM				
Lozoya, Manny		Please adjust locking mechanism on cafeteria door							
<u>Gidget Mora</u>									
78830	Main Building	Gym			9/27/2011		134		\$0.00
Medium	Work In Progress				9/27/2011 9:43:32 AM				
Vallejo, Albert		please repaint gym.							
<u>Albert Vallejo</u>									
82227					1/1/2012	1/9/2012	38		\$0.00
Medium	Work In Progress				1/1/2012 12:44:05 AM				
Vallejo, Albert		Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
81658					12/4/2011	12/12/2011	66		\$0.00
Medium	Work In Progress				12/4/2011 12:16:23 AM				
Vallejo, Albert		Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
81659					12/4/2011	12/12/2011	66		\$0.00
Medium	Work In Progress			12/4/2011 12:16:23 AM					
Vallejo, Albert	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81655					12/4/2011	1/4/2012	66		\$0.00
Medium	Work In Progress			12/4/2011 12:16:22 AM					
Vallejo, Albert	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81656					12/4/2011		66		\$0.00
Medium	Work In Progress			12/4/2011 12:16:22 AM					
Vallejo, Albert	Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83614					2/5/2012	3/7/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:45 AM					
Vallejo, Albert	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83609					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:44 AM					
Vallejo, Albert	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83610					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:44 AM					
Vallejo, Albert	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
80183					10/25/2011		106		\$0.00
Medium	Work In Progress			10/25/2011 11:09:55					
Vallejo, Albert	Replace exhaust fan motors in 100 hall men's restroom, 200 hallway men's restroom, 200 hallway women's restroom, 300 hallway women's restroom, 300 hallway custodial closet. 5 Total.								
<u>Albert Vallejo</u>									
79845					10/17/2011		114		\$0.00
Medium	Work In Progress			10/17/2011 12:46:00					
Vallejo, Albert	INSTALL BASE IN DRY STORAGE. AS PER HEALTH INSPECTION.								
<u>Maritza Gonzalez</u>									

2/8/2012 1:26:26 PM

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
79941					10/19/2011		112		\$0.00
Medium	Work In Progress			10/19/2011 7:43:23 AM					
Vallejo, Albert		Replace exterior lights on south end of building.							
Albert Vallejo									
80177		Cafeteria			10/25/2011		106		\$0.00
Medium	Work In Progress			10/25/2011 10:23:20					
Vallejo, Albert		MISSING TILE BY THE STOVE (AS PER MR. BAKER).							
Maritza Gonzalez									
83615					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:46 AM					
Vallejo, Albert		Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
83483					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 10:21:04 AM					
Vallejo, Albert		Change lamps in lobby recessed fixtures.							
Albert Vallejo									
83148					1/24/2012		15		\$0.00
Medium	Work In Progress			1/24/2012 4:13:29 PM					
Carrasco, Danny		Need 14.4v battery; screwdriver set (see Danny Carrasco)							
Albert Vallejo									
76355					8/3/2011		189		\$0.00
Medium	Work In Progress			8/3/2011 10:31:21 AM					
Ontiveros, Guadalupe		Please replace valves for tree line bubblers. Some do not open.							
Albert Vallejo									
83827					2/8/2012		0		\$0.00
Medium	Work In Progress			2/8/2012 8:53:25 AM					
Ontiveros, Guadalupe		Need to repair 2" irrigation line that was damaged by vandalism.							
Albert Vallejo									
83612					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:45 AM					
Vallejo, Albert		Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
81277					11/21/2011		79		\$0.00
High	Work In Progress			11/21/2011 8:08:55 AM					
Quinones, Paul		please paint all fire lanes and handi cap ramps. thank you							
<u>Michael Munoz</u>									
82259					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:20 AM					
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
82545					1/9/2012		30		\$0.00
Medium	Work In Progress			1/9/2012 9:28:52 AM					
Ontiveros, Joe		Please install valve from riser to fill boiler system.							
<u>Albert Vallejo</u>									
82546					1/9/2012		30		\$0.00
Medium	Work In Progress			1/9/2012 9:35:39 AM					
Ontiveros, Joe		Please check into installing a new washing machine in the home economics room #203. The machine has been purchased, but there is no water supply or drain.							
<u>Albert Vallejo</u>									
81657					12/4/2011	12/7/2011	66		\$0.00
Medium	Work In Progress			12/4/2011 12:16:23 AM					
Vallejo, Albert		Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
83613					2/5/2012	2/8/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:45 AM					
Vallejo, Albert		Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
83538		Portables			2/2/2012		6		\$0.00
Medium	Work In Progress	p2		2/2/2012 1:55:16 PM					
Lozoya, Manny		Please fix or replace 2 panic bars on portable 2							
<u>Gidget Mora</u>									
<b>Count: 39 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>54</b>			<b>Total for Chaparral MS</b>	<b>0</b>	<b>\$0.00</b>	



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
<b>Location:</b>		<b>Charter School</b>							
83724					2/6/2012		2		\$0.00
High	Work In Progress				2/6/2012 7:41:54 AM				
Diaz, Sebastian	water is entering building thru several area, need to scrape bottom 2' of east wall, apply coating and paint, also caulk all window, walls, pipes and frame out gutters and seal as well. please see mike for details. thank you								
Michael Munoz									
<b>Count: 1 Work Orders</b>	<b>Avg. Age of WO's</b>		<b>2</b>		<b>Total for Charter School</b>		<b>0</b>	<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Pride</b>							
82941		Portables			1/19/2012		20		\$0.00
Medium	Work In Progress	ROOM 1		1/19/2012 9:27:58 AM					
Estrada, Jesus	CARPET STARTING TO SMELL DUE WATER HEATER LEAK.								
<u>David Acosta</u>									
83378		Classroom			1/30/2012		9		\$0.00
Medium	Work In Progress	9		1/30/2012 1:57:15 PM					
Lara, Ralph	HAVING TROUBLE WITH PANIC BAR. SLOT FOR ALLEN WRENCH IS WORN OUT.								
<u>David Acosta</u>									
78010		Classroom			9/7/2011		154		\$0.00
Medium	Work In Progress	Boxing room		9/7/2011 10:25:23 AM					
Ronquillo, Ruben	JC Fernandez, Boxing coach,needs to transfer 5 punching bags at the warehouse.								
<u>Mary Telles</u>									
83628					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:51 AM					
Acosta, David	Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83629					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:51 AM					
Acosta, David	Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82145					12/15/2011		55		\$0.00
Medium	Work In Progress			12/15/2011 1:50:19 PM					
Lara, Ralph	AS PER MR CHAVEZ PLEASE ISSUE GATE KEYS TO ORLANDO GARCIA (SECURITY) THE FOLLOWING SCHOOLS VADO(A-1), NORTH VALLEY(CN-1), MESQUITE (C1).								
<u>Maritza Gonzalez</u>									
79568		Library			10/10/2011		121		\$0.00
Medium	Work In Progress	READING/LAB		10/10/2011 1:50:21 PM					
Castillo, Carlos	NEED TO INSTALL ELECTRICAL OUTLET ON CEILING FOR PROJECTOR								
<u>David Acosta</u>									
82552		Portables			1/9/2012		30		\$0.00
Medium	Work In Progress			1/9/2012 10:45:10 AM					
Appelzoller, Fred	please replace leaking water heater in portable #1, thank you								
<u>Michael Munoz</u>									

2/8/2012 1:26:26 PM

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Pride</b>							
82553		Portables			1/9/2012		30		\$0.00
Medium	Work In Progress			1/9/2012 10:46:41 AM					
Appelzoller, Fred	please repair or replce isolating water valves to portables. thank you								
<u>Michael Munoz</u>									
82894					1/18/2012		21		\$0.00
Medium	Work In Progress	BOXING AREA		1/18/2012 9:48:12 AM					
Castillo, Carlos	PER MR. FOSTER, WE NEED TO HAVE LIGHTING INSTALLED AROUND OUR BOXING RING AND BOXING AREA FOR DISTRICT BOXING FOR AFTER SCHOOL HOURS AT DESERT PRIDE ACADEMY.								
<u>Mary Telles</u>									
83226	Curriculum and				1/26/2012		13		\$0.00
Medium	Work In Progress	Boxing area		1/26/2012 9:00:36 AM					
Ronquillo, Ruben	Boxing Coach, Mr. Fernandez states that he needs to have 2 heavy bag stands transferred and assembled; transfer 12 heavy bags; delivery of 1 case of hand wraps; delivery of 1 dolley, and 1 6 ft. folding ladder.								
<u>Mary Telles</u>									
79250					10/2/2011		129		\$0.00
Medium	Work In Progress			10/2/2011 12:28:02 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83710					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:22 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83711					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:23 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83630					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:52 AM					
Acosta, David	Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
<b>Count: 15 Work Orders</b>		<b>Avg. Age of WO's 40</b>		<b>Total for Desert Pride</b>			<b>0</b>	<b>\$0.00</b>	

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
82279					1/1/2012	1/22/2012	17	0.5	\$12.50
Medium	Work In Progress				1/1/2012 12:44:28 AM	1/18/2012			
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
80861					11/9/2011		91		\$0.00
Medium	Work In Progress				11/9/2011 7:24:35 AM				
Estrada, Jesus	Need to replace carpets in front office. (Tear)					2/1/12 - WILL BE TAKEN CARE OF DURING SUMMER BREAK - PENDING PURCHASE ORDER			
<u>Johnny Acuna</u>									
83815					2/7/2012		1		\$0.00
Medium	Work In Progress				2/7/2012 4:05:20 PM				
Carrasco, Danny	Please fuel up Steiner Tractor and some on Work Truck #192. Unleaded Gasoline								
<u>Johnny Acuna</u>									
82783					1/13/2012		26		\$0.00
Medium	Work In Progress				1/13/2012 1:46:26 PM				
Estrada, Jesus	Need carpets replaced in Portable #400 and Portable #406								
<u>Johnny Acuna</u>									
77938					9/6/2011		155		\$0.00
Medium	Work In Progress				9/6/2011 12:20:02 AM				
Sanchez, Raul	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83769					2/7/2012		1		\$0.00
Medium	Work In Progress				2/7/2012 8:22:59 AM				
Apodaca, Mario	Please fix water leak to water filter system in mechanical room. I Need to water front trees. (Irrigation connected to same system) Thank You....								
<u>Johnny Acuna</u>									
75105					7/5/2011		218		\$0.00
Medium	Work In Progress				7/5/2011 12:16:34 AM				
Sanchez, Raul	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
83279					1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 11:11:35 AM					
Orozco, Danny	The outside metal cover from the walk-in refrigerator door is coming apart and doesn't close right. Also, the metal cover from the walk-in Freezer Wall is also coming apart. Thank You... SNP Manager Pat C. 824.3822								
Maritza Gonzalez									
82670					1/11/2012		28		\$0.00
Medium	Work In Progress			1/11/2012 9:31:35 AM					
Orozco, Danny	temperature for the walk in was 39 then at 8:00 it was 45 and now is 50.thank you. snp manager pat c. 824.3822								
Maritza Gonzalez									
82683					1/11/2012		28		\$0.00
Medium	Work In Progress			1/11/2012 3:22:22 PM					
Orozco, Danny	dish washer it throws hot water from the side snp manager Pat C. 824.3822								
Maritza Gonzalez									
76883					8/12/2011		180		\$0.00
Medium	Work In Progress			8/12/2011 11:50:32 AM					
Orozco, Danny	1) SNEEZE SHIELD ON ASSEMBLY LINE WERE BROKEN BY STUDENTS. 2) LADIES ARE HAVING A HARD TIME WITH RAILS/COVERS IN OVEN IS, GETTING STUCK. SNP MANAGER PAT C. 824.3822								
Maritza Gonzalez									
79609					10/11/2011		120		\$0.00
Medium	Work In Progress			10/11/2011 9:07:53 AM					
Orozco, Danny	Skillet it doesn't work and I need to use it Thursday and Friday.SNP Manager Pat C. 824.3822								
Maritza Gonzalez									
83832					2/8/2012		0		\$0.00
Medium	Work In Progress			2/8/2012 9:52:09 AM					
Orozco, Danny	the fans from the walk-in they have a lot of ice. SNP Manager Pat C. 824.3822								
Maritza Gonzalez									
83660					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:03 AM					
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
83816					2/7/2012		1		\$0.00
Medium	Work In Progress				2/7/2012 4:07:40 PM				
Carrasco, Danny	Need to borrow Sprayer Machine for enamel paint and a compressor. Thank You...								
Johnny Acuna									
82895					1/18/2012		21		\$0.00
Medium	Work In Progress				1/18/2012 9:57:21 AM				
Lozoya, Manny	Portable #409: Need to replace door as soon as possible, Badly damaged: Welds have come undone and door is wobly.								
Johnny Acuna									
82725					1/12/2012		27		\$0.00
Medium	Work In Progress				1/12/2012 12:38:26 PM				
Lozoya, Manny	Portable #400 south door is too flimsy and needs replacing.								
Johnny Acuna									
82676					1/11/2012		28		\$0.00
Medium	Work In Progress	410			1/11/2012 1:42:15 PM				
Lozoya, Manny	Ms. Manzanares in portable 410 the door not closing properly								
Elizabeth Hernandez									
82671					1/11/2012		28		\$0.00
Medium	Work In Progress				1/11/2012 10:48:57 AM				
Lozoya, Manny	Portable #410: Door to classroom does not close properly. Door is too flimsy and probably needs replacing.								
Johnny Acuna									
83491					2/1/2012		7		\$0.00
Medium	Work In Progress				2/1/2012 1:19:49 PM				
Ambriz, Juan	On February 8, 2012, please pick-up a full Gaylord from Desert Trail Elementary. Contact Person: Tori Gilpin								
Yolie Jacquez									
75597					7/20/2011		203		\$0.00
Medium	Work In Progress				7/20/2011 3:39:53 PM				
Gonzalez, Salvador	Please make (2) ramps for steiner tractor to be used to go in and out of concrete swell in the back and west side of school grounds.								
Johnny Acuna									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Desert Trail Intermediate

83581					2/3/2012		5		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/3/2012 3:11:24 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Gonzalez, Salvador      Need to weld metal coupling in mechanical room for Heating system water pump.

Johnny Acuna

83582					2/3/2012		5		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/3/2012 3:14:28 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Gonzalez, Salvador      Please re-weld broken screws to Soccer goals anchors.

Johnny Acuna

81778					12/5/2011		65		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/5/2011 8:17:42 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique      Need (1) 70W HPS Wall Light Fixture for Portable #415. Also, (2) 70W HPS Light Bulbs. Thank You.....

Johnny Acuna

83210					1/25/2012		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/25/2012 3:55:43 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique      Need assistance in Replacing Emergency Battery packs to light fixtures in rooms #304, 115, 119.

Johnny Acuna

83212					1/25/2012		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/25/2012 3:57:19 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique      Need assistance in Repairing noise in lighting to Staff Women's Restroom and light to hall Girl's Restroom.

Johnny Acuna

83214					1/25/2012		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/25/2012 3:58:50 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique      Need 4 boxes of T8 bulbs

Johnny Acuna

83380					1/30/2012		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/30/2012 2:07:02 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique      Need a replacement Hand Dryer for Girl's Restroom in the Bus Lobby Area. Make: World Dryer, Serial: B35755, 60 HZ, 120v, 17A.

Johnny Acuna

78758					9/26/2011		135		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/26/2011 10:10:54 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique      Need electrical wiring for Bard Heating/Cooling unit to portable #409.

Johnny Acuna

2/8/2012 1:26:26 PM

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
81938					12/9/2011		61		\$0.00
Medium	Work In Progress			12/9/2011 12:46:04 PM					
Ontiveros, Joe	Need assistance in repairing busted waterline between cinder block. Waterline in line with portables.								
Johnny Acuna									
83125					1/24/2012		15		\$0.00
Medium	Work In Progress			1/24/2012 3:21:41 PM					
Ontiveros, Joe	Need assistance in repairing leak to Cafeteria waterfountain. (Need gasket parts for Drain line)								
Johnny Acuna									
83833					2/8/2012		0		\$0.00
Medium	Work In Progress			2/8/2012 9:59:15 AM					
Ontiveros, Joe	Please repair comode in girl's restroom NW Hall. Keeps flushing.								
Johnny Acuna									
82260					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:20 AM					
Villalobos, David	Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
80224					10/26/2011		105		\$0.00
Medium	Work In Progress			10/26/2011 10:01:09					
Villalobos, David	David: Please fix leaking backflow to Boiler heating system.								
Johnny Acuna									
82943					1/19/2012		20		\$0.00
Medium	Work In Progress			1/19/2012 10:00:20 AM					
Acuna, Johnny	Need Paint for curbs, Panels, and Portables.								
Johnny Acuna									
82540					1/9/2012		30		\$0.00
Medium	Work In Progress			1/9/2012 9:07:09 AM					
Solis, Lorenzo	Need assistance in repairing water leak to heating system circulating pump in the mechanical room. (Old Pump section: Leaking from bottom of Check valve. Possibly need new gaskets) Heating system operating with only 1 pump.								
Johnny Acuna									
82629					1/10/2012		29		\$0.00
Medium	Work In Progress			1/10/2012 3:01:34 PM					
Solis, Lorenzo	Need assistance in troubleshooting heating unit to portable #410.								
Johnny Acuna									
2/8/2012 1:26:26 PM									



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Desert Trail Intermediate</b>								
82616					1/10/2012		29		\$0.00	
Medium	Work In Progress	406		1/10/2012 10:18:21 AM						
Lozoya, Manny		Mrs. Falin in room 406 needs key for file cabinet some one locked it and is unable to open filing cabinet.								
Elizabeth Hernandez										
83100		Portables			1/23/2012		16		\$0.00	
Medium	Work In Progress			1/23/2012 4:02:14 PM						
Lozoya, Manny		Need locks to be installed on all Electrical Disconnect Boxes around all portables. (Safety Issue)								
Johnny Acuna										
83166					1/25/2012		14		\$0.00	
Medium	Work In Progress			1/25/2012 12:54:59 PM						
Lozoya, Manny		Need an Isolated Core and 3 keys only that opens up that lock to be installed in the Intern Administrative office. (Security Purpose for Tests).								
Johnny Acuna										
83126					1/24/2012		15		\$0.00	
Medium	Work In Progress			1/24/2012 3:24:39 PM						
Lozoya, Manny		Need assistance with information on Door knob locks to be purchased for the front office. (Please see Elizabeth in the Front Office). Thank You.....								
Johnny Acuna										
83227					1/26/2012		13		\$0.00	
Medium	Work In Progress			1/26/2012 9:05:10 AM						
Lozoya, Manny		Need to re-make keys to Intern Administration office.								
Johnny Acuna										
80016					10/20/2011		111		\$0.00	
Medium	Work In Progress			10/20/2011 2:32:33 PM						
Acuna, Johnny		Need Aluminum window blinds for Portable # 400/401. (2) 94 1/2" Wide X 36" Long  (2) 47" Wide X 36" Long								
Johnny Acuna										
81612					12/2/2011		68		\$0.00	
Medium	Work In Progress			12/2/2011 12:13:03 PM						
Acuna, Johnny		Need cement runner for new exit gate wheels.				12/5 - Asp Mike route to Johnny				
Johnny Acuna										

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
81252					11/18/2011		82	1	\$175.44
Medium	Work In Progress				11/18/2011 3:35:11 PM				
Acuna, Johnny			Need 2 replacement Rooftop Exhaust fan motors with pulleys and with brackets attached to motors.			PURCHASED AND DEL TO J. ACUNA HE WILL INSTALL.			
Johnny Acuna									
83661					2/5/2012		3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:04 AM				
Acuna, Johnny			Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.						
Margret Villalobos									
82547					1/9/2012		30		\$0.00
Medium	Work In Progress				1/9/2012 9:41:07 AM				
Acuna, Johnny			Need (4) Aluminum window blinds for Portable #413. 46 1/2" Wide X 48" Long.						
Johnny Acuna									
82548					1/9/2012		30		\$0.00
Medium	Work In Progress				1/9/2012 9:46:29 AM				
Acuna, Johnny			Need (1) Aluminum Window Blind for Room #113. 62 1/2" Wide X 63" Long						
Johnny Acuna									
83658					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:02 AM				
Acuna, Johnny			Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.						
Margret Villalobos									
83659					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:03 AM				
Acuna, Johnny			Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.						
Margret Villalobos									
83725					2/6/2012		2		\$0.00
Medium	Work In Progress				2/6/2012 7:50:08 AM				
Carrasco, Danny			Need 3 boxes of Classroom light bulbs: F40 CW/RS/EW 34W						
Johnny Acuna									
75912					7/27/2011		196		\$0.00
Medium	Work In Progress				7/27/2011 3:45:58 PM				
Lozoya, Manny			Need a key issued to open up new covers for irrigation valves underground.						
Johnny Acuna									
<b>Count: 52 Work Orders</b>			<b>Avg. Age of WO's 46</b>			<b>Total for Desert Trail Intermediate</b>	<b>1.5</b>	<b>\$187.94</b>	

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
83160					1/25/2012		14		\$0.00
Medium	Work In Progress			1/25/2012 9:47:46 AM					
Ruben Ortiz	Ontiveros, Guadalupe	01/25/12	Vandalism; sprinkler control pulled pipe and wire out that was connected to the portable; Officer E. Salazar case no. SPPD 201200125						
83576					2/3/2012		5		\$0.00
Medium	Work In Progress			2/3/2012 2:04:04 PM					
Ruben Ortiz	Ontiveros, Guadalupe		Need two Flag poles replace and a new base for the new flag poles. Thank you Ruben						
83224		Custodial			1/26/2012		13		\$0.00
Medium	Work In Progress			1/26/2012 8:36:58 AM					
Ruben Ortiz	Estrada, Jesus		This work order is for the instalation of new carpets on rooms #35 AND #37 CARPETS ON THIS ROOMS ARE REAL BAD.THANK YOU IN ADVANCED.						
82954					1/19/2012		20		\$0.00
Medium	Work In Progress			1/19/2012 12:54:31 PM					
Ruben Ortiz	Flores, Pete		The battery of the John deer 970 tracter is not holding the chager. Thank you Ruben						
83572					2/3/2012		5		\$0.00
Medium	Work In Progress			2/3/2012 1:41:55 PM					
Ruben Ortiz	Flores, Pete		Tire is flat. Front passenger side. Truck 95 Thank you Ruben						
83713					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:24 AM					
Ruben Ortiz	Ortiz, Ruben		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.						
83714					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:24 AM					
Ruben Ortiz	Ortiz, Ruben		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.						
Margret Villalobos	Margret Villalobos								

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

---

**Location: Desert View ES**


---

83715					2/5/2012		3		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress			2/5/2012 12:18:24 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ortiz, Ruben	Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
--------------	--	--	--	--	--	--	--	--	--

---

Margret Villalobos

81766					12/4/2011	12/12/2011	66		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress			12/4/2011 12:17:04 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
--------------	--	--	--	--	--	--	--	--	--

---

Margret Villalobos

77531		Office			8/29/2011		163		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Office		8/29/2011 3:18:32 PM					
--------	------------------	--------	--	----------------------	--	--	--	--	--

Munoz, Michael	Move the existing counter towards the window located in the Office and move the Handicap table towards the door. (Gonzalez)								
----------------	---	--	--	--	--	--	--	--	--

---

Guadalupe Gonzalez

81788		Office			12/5/2011		65		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Office		12/5/2011 11:28:16 AM					
--------	------------------	--------	--	-----------------------	--	--	--	--	--

Ortiz, Ruben	Please assemble a projector cart for Ms. Autry. (Gonzalez)								
--------------	--	--	--	--	--	--	--	--	--

---

Guadalupe Gonzalez

76003					7/29/2011		194		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			7/29/2011 9:00:38 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ortiz, Ruben	Need to replace 16 120 sprinklers and blubbers								
--------------	--	--	--	--	--	--	--	--	--

---

Ruben Ortiz

78230					9/12/2011		149		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/12/2011 4:48:33 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ortiz, Ruben	Replace parking signs for staff								
--------------	---------------------------------	--	--	--	--	--	--	--	--

---

Ruben Ortiz

78231					9/12/2011		149		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/12/2011 4:55:28 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ortiz, Ruben	09/12/11 Put up No Trespassing sign between the hours of 9 p.m. to 5 a.m.								
--------------	--	--	--	--	--	--	--	--	--

---

Ruben Ortiz

81989					12/11/2011	12/27/2011	59		\$0.00
-------	--	--	--	--	------------	------------	----	--	--------

Medium	Work In Progress			12/11/2011 12:14:25					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
--------------	--	--	--	--	--	--	--	--	--

---

Margret Villalobos

2/8/2012 1:26:26 PM

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
82789					1/13/2012		26		\$0.00
Medium	Work In Progress			1/13/2012 3:26:42 PM					
Ambriz, Jose	Heater in the Cafeteria is not working. Thank you Ruben								
Ruben Ortiz									
78232					9/12/2011		149		\$0.00
Medium	Work In Progress			9/12/2011 4:59:30 PM					
Ortiz, Ruben	Paint lower level bathroom floors gray								
Ruben Ortiz									
82668		Portables			1/11/2012		28		\$0.00
Medium	Work In Progress			1/11/2012 9:12:36 AM					
Castillo, Carlos	Portable 4 room 6B a light is not woking. Thank you Ruben								
Ruben Ortiz									
82261					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:21 AM					
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
78832					9/27/2011		134		\$0.00
Medium	Work In Progress			9/27/2011 9:47:24 AM					
Villalobos, David	Install a deep sink and counter top for the art room								
Ruben Ortiz									
78834					9/27/2011		134		\$0.00
Medium	Work In Progress			9/27/2011 9:51:10 AM					
Villalobos, David	Install a sink and garbage disposal in the teacher's lounge								
Ruben Ortiz									
77701					9/1/2011		160		\$0.00
Medium	Work In Progress			9/1/2011 11:08:36 AM					
Ortiz, Ruben	please purchase new D130 john deere lawn mower to replace existing one.								
Michael Munoz									
81404					11/28/2011		72		\$0.00
Medium	Work In Progress			11/28/2011 3:31:22 PM					
Orozco, Danny	EXHAUST FAN IS NOT WORKING. SNP MANAGER DIANA L. 589.2425								
Maritza Gonzalez									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
76430					8/4/2011		188		\$0.00
Medium	Work In Progress			8/4/2011 10:19:15 AM					
Orozco, Danny	SCREEN DOOR NEEDS TO BE REPLACED IN KITCHEN. SNP MANAGER EMILIA C. 589.2550								
<u>Maritza Gonzalez</u>									
75780					7/25/2011		198		\$0.00
Medium	Work In Progress			7/25/2011 1:22:23 PM					
Orozco, Danny	3-Compartment sink leaking—gaskets need to be replaced per construction manager. They are not responsible for this.								
<u>Aida Salcedo</u>									
79717		Custodial			10/13/2011		118		\$0.00
Medium	Work In Progress			10/13/2011 7:52:31 AM					
Estrada, Jesus	This work order is to repair the carpet of rooms 16,20,and 22 the crpets are new but is coming apart from the middle of the rooms .THANK YOU IN ADVANCED.					1/30/12 - P.O. RECEIVED / FAXED TO RODRIGUEZ, WILL BE TAKEN CARE OF DURING SUMMER BREAK			
<u>Hector Rivera</u>									
82412					1/5/2012		34		\$0.00
Medium	Work In Progress			1/5/2012 2:48:21 PM					
Munoz, Michael	Need to Repair front Fence. Asap Thank you Ruben								
<u>Ruben Ortiz</u>									
83449					1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 3:31:51 PM					
Lara, Ralph	The handle on west wing door was broken needs to be fix asap Thank you Ruben								
<u>Ruben Ortiz</u>									
83573					2/3/2012		5		\$0.00
Medium	Work In Progress			2/3/2012 1:53:15 PM					
Munoz, Michael	Need a fence for the new watering control. For portection of vandalism. Thank you Ruben								
<u>Ruben Ortiz</u>									
83712					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:23 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78124					9/9/2011		152		\$0.00
Medium	Work In Progress			9/9/2011 2:44:06 PM					
Munoz, Michael	need to construct concret pad for trash dumpsters								
<u>Alfredo Holguin</u>									
2/8/2012 1:26:26 PM									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert View ES</b>									
81518	Main Building	Classroom			11/30/2011		70		\$0.00
Medium	Work In Progress				11/30/2011 1:43:22 PM				
Ambriz, Jose		Heater in room 39 is not working. Thank you Ruben							
Ruben Ortiz									
82669	Main Building				1/11/2012		28		\$0.00
Medium	Work In Progress				1/11/2012 9:16:10 AM				
Castillo, Carlos		Portable 2 room 4 a light is not working. Thank you Ruben							
Ruben Ortiz									
<b>Count: 33 Work Orders</b>		<b>Avg. Age of WO's 74</b>			<b>Total for Desert View ES</b>			<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
82328					1/1/2012	1/7/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:52 AM					
Ambriz, Juan	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81722					12/4/2011	12/10/2011	66		\$0.00
Medium	Work In Progress			12/4/2011 12:16:47 AM					
Ambriz, Juan	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83673					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:08 AM					
Ambriz, Juan	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
79062					9/30/2011		131		\$0.00
Medium	Work In Progress			9/30/2011 4:29:51 PM					
Lara, Ralph	Entrance door on south side currently used to accecs GAC offices - install automatic door opener or door bell/buzzer that can be used by individuals with disabilities of open the door or get assistance to open the door								
<u>Alfredo Holguin</u>									
82280					1/1/2012	1/22/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:28 AM					
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81462					11/29/2011		71		\$0.00
Medium	Work In Progress			11/29/2011 2:48:33 PM					
Orozco, Danny	SEAL TO SINK IS BROKEN, WATER WILL NOT HOLD. SNP MANAGER GESSICA M. 882.6784								
<u>Maritza Gonzalez</u>									
83828					2/8/2012		0		\$0.00
Medium	Work In Progress			2/8/2012 8:58:22 AM					
Gonzalez, Salvador	NEED TO HAVE HANDICAP SIGN WELDED TO BOLLARD BY PRE-K. HANDICAP RAMP. THANKS. (Please assist Gerry w/this work orders asp Mike)								
<u>Gerardo Marquez</u>									



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
83577					2/3/2012		5		\$0.00
Medium	Work In Progress			2/3/2012 2:31:50 PM					
Ambriz, Juan	7 boxes which contain federal fund folders ready to be picked up and taken to the warehouse to Tracey Swinford for storage. They are located in my (Bertha Ruiz) office in Finance.								
<u>Maritza Gonzalez</u>									
82012					12/12/2011		58		\$0.00
Medium	Work In Progress			12/12/2011 1:55:47 PM					
Castillo, Carlos	OUTLET (MICROWAVE) IN LOUNGE BEHIND RECEPTIONIST AREA IN B WING KEEPS JUMPING.								
<u>Maritza Gonzalez</u>									
82262					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:21 AM					
Villalobos, David	Yearly - GAC Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83398					1/30/2012		9		\$0.00
Medium	Work In Progress			1/30/2012 3:45:35 PM					
Villalobos, David	TOILET SEAT IN WOMENS (HANDICAP) RESTROOM A-WING NEEDS TO BE ADJUSTED OR REPLACED.								
<u>Maritza Gonzalez</u>									
81338					11/22/2011		78		\$0.00
High	Work In Progress			11/22/2011 1:36:13 PM					
Villalobos, David	temperature and pressure gauge cannot be read unless on a ladder. please re-install to be read from ground level. also relief valve on storage tank is missing tag. please replace t/p valve as per boiler inspectors site visit boiler sn 0410227096								
<u>Michael Munoz</u>									
83424					1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 9:21:37 AM					
Castillo, Carlos	Please check generator for proper operation.								
<u>Michael Munoz</u>									
81339					11/22/2011		78		\$0.00
High	Work In Progress			11/22/2011 1:59:42 PM					
Castillo, Carlos	boiler does not have an emergency shut off switch. please install one as per boiler inspectors site visit.thank you								
<u>Michael Munoz</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
83537					2/2/2012		6		\$0.00
Medium	Work In Progress			2/2/2012 1:29:19 PM					
Castillo, Carlos	Power Generator does a self check test every Tuesday morning. Has been two weeks and has not done this test								
Cora Ramirez									
83526		Office			2/2/2012		6		\$0.00
Medium	Work In Progress	SPED OFFICE		2/2/2012 9:15:19 AM					
Villalobos, Hector	AS PER MARGARET V. WITH SPECIAL ED @ ANTHONY ELEM-NEED TO HAVE SOMEONE GO CHECK JULIE HINOJOSA'S OFFICE HEATER CHECKED. NOT WORKIING.					QUESTIONS CALL MARGARET @ 882-6221. NOTAIFIED LUCKY THRU DAVID VEGA			
Mary Garcia									
83731					2/6/2012		2		\$0.00
Medium	Work In Progress			2/6/2012 10:02:04 AM					
Lara, Ralph	AUTOMATIC DOOR CLOSURE TO FRONT DOOR GETTING STUCK.								
Maritza Gonzalez									
82518					1/8/2012	1/24/2012	31		\$0.00
Medium	Work In Progress			1/8/2012 12:16:01 AM					
Ambriz, Juan	Monthly - GAC Playground Insp - Refer to PM schedule details.								
Jesus Estrada									
81984					12/11/2011	12/27/2011	59		\$0.00
Medium	Work In Progress			12/11/2011 12:14:23					
Ambriz, Juan	Monthly - GAC Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
81525					11/30/2011		70		\$0.00
Medium	Work In Progress			11/30/2011 3:11:39 PM					
Mijarez, Jaime	FILTERS ON FURNACES NEED TO BE CHANGED OUT THROUGH OUT BLDG.								
Maritza Gonzalez									
81626					12/2/2011		68		\$0.00
Medium	Work In Progress			12/2/2011 2:58:39 PM					
Mijarez, Jaime	WINDOW UNIT IN BARBARA C. AND ROSA A. OFFICE IN B-WING NEEDS TO BE CLEANED OUT, LOTS OF SAND.								
Maritza Gonzalez									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: GAC</b>									
82329					1/1/2012	1/9/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:53 AM					
Ambriz, Juan	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
82330					1/1/2012	1/9/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:53 AM					
Ambriz, Juan	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
83105					1/24/2012		15		\$0.00
Medium	Work In Progress			1/24/2012 8:08:16 AM					
Mijarez, Jaime	Directory Holder needs to be mounted on Priscilla Escobar office wall.								
Maritza Gonzalez									
81720					12/4/2011	12/12/2011	66		\$0.00
Medium	Work In Progress			12/4/2011 12:16:47 AM					
Ambriz, Juan	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
81721					12/4/2011	12/12/2011	66		\$0.00
Medium	Work In Progress			12/4/2011 12:16:47 AM					
Ambriz, Juan	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
83674					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:09 AM					
Ambriz, Juan	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
83675					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:09 AM					
Ambriz, Juan	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
82327					1/1/2012	1/9/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:52 AM					
Ambriz, Juan	Monthly - GAC Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: GAC</b>									
83429					1/31/2012		8		\$0.00
Medium	Work In Progress				1/31/2012 10:55:45 AM				
Rodriguez, Arturo		MR. YTURRALDE NEEDS PLAQUE HUNG ON WALL.							
Maritza Gonzalez									
83430					1/31/2012		8		\$0.00
Medium	Work In Progress				1/31/2012 10:57:02 AM				
Rodriguez, Arturo		CATHY PHILLIPS REQUESTING BLUE LIGHT COVERS INSTALLED ON LIGHTS.							
Maritza Gonzalez									
83562					2/2/2012		6		\$0.00
Medium	Work In Progress				2/2/2012 4:08:33 PM				
Rodriguez, Arturo		FURNITURE AND BOXES NEED TO BE MOVED FROM DINO FACIO'S OFFICE.							
Maritza Gonzalez									
<b>Count: 32 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>36</b>			<b>Total for GAC</b>	<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
<b>Location:</b>		<b>GAC - Pre-K</b>							
83054					1/23/2012		16		\$0.00
Medium	Work In Progress	playground			1/23/2012 9:36:58 AM				
Mijarez, Jaime	Please blow off blue area on PreK playground around toyboxes & sidewalks								
Lucia Almeraz									
83055					1/23/2012		16		\$0.00
Medium	Work In Progress	PreK			1/23/2012 9:50:39 AM				
Marquez, Gerardo	Please repair toybox in front of room 203								
Lucia Almeraz									
83058					1/23/2012		16		\$0.00
Medium	Work In Progress	PreK			1/23/2012 10:02:37 AM				
Villalobos, David	Please check sinks in all Pre K classrooms particle board is caving in because they are wet (soaked)								
Lucia Almeraz									
<b>Count: 3 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>16</b>			<b>Total for GAC - Pre-K</b>	<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden ES</b>									
83069					1/23/2012		16		\$0.00
Medium	Work In Progress	room 107		1/23/2012 1:01:05 PM					
Ontiveros, Joe	water in sink does not stop running.. greatly appreciate your assistance in this matter....								
Loraine Gandara									
83565					2/3/2012		5		\$0.00
Medium	Work In Progress	PTO		2/3/2012 8:06:17 AM					
Sotelo, Enrique	need assistance with the electrical cord from the laminator....								
Loraine Gandara									
82054		Restroom (Girls)			12/13/2011		57		\$0.00
Medium	Work In Progress	Jefferson Wing		12/13/2011 12:42:58					
Appelzoller, Fred	two sinks in the girls restroom in the Jefferson Wing are not functioning... when the button is pressed down in the sink the button stays stuck... greatly appreciate your assistance in this matter...								
Loraine Gandara									
83819		Classroom			2/8/2012		0		\$0.00
Medium	Work In Progress	101		2/8/2012 8:00:04 AM					
Appelzoller, Fred	per Ms. Nevarez.... need assistance asap in her classroom.... with her shower.... there is no hot water....								
Loraine Gandara									
82393		Athletic Field			1/5/2012		34		\$0.00
Medium	Work In Progress			1/5/2012 8:38:44 AM					
Sotelo, Enrique	need to line locate electric and gas and sewer for irrigation on plants. for info contact lupe								
Guadalupe Ontiveros									
81519					11/30/2011		70		\$0.00
Medium	Work In Progress			11/30/2011 1:46:01 PM					
Sotelo, Enrique	light bulbs on the outside corridors are not working... light bulbs need to be replaced... if you have any questions please free to ask Loraine Or Eric.. thank you...								
Loraine Gandara									
79853		Office			10/17/2011		114		\$0.00
Medium	Work In Progress			10/17/2011 2:47:07 PM					
Lozoya, Manny	need three padlocks for weekend games... greatly appreciate your assistance in this matter...								
Loraine Gandara									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
79856		Office			10/17/2011		114		\$0.00
Medium	Work In Progress			10/17/2011 2:56:03 PM					
Lozoya, Manny		padlocks need to be accompanied by 18 inch chains... greatly appreciate your assistance							
Loraine Gandara									
83726					2/6/2012		2		\$0.00
Medium	Work In Progress			2/6/2012 8:02:34 AM					
Lozoya, Manny		need a master key for our new custodian... greatly appreciate your assistance							
Loraine Gandara									
78166					9/11/2011	9/27/2011	150		\$0.00
Medium	Work In Progress			9/11/2011 12:20:44 AM					
Moncayo, Fernando		Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
79517					10/9/2011	10/25/2011	122		\$0.00
Medium	Work In Progress			10/9/2011 12:16:34 AM					
Moncayo, Fernando		Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
77578					8/30/2011		162		\$0.00
Medium	Work In Progress			8/30/2011 11:21:44 AM					
Marquez, Gerardo		please repair cracks walls, texture and paint thru-out site.thank you							
Michael Munoz									
78065		Computer Lab			9/8/2011		153		\$0.00
Medium	Work In Progress	201		9/8/2011 10:26:56 AM					
Moncayo, Fernando		needs assistance with the vent in room 201 bathroom... greatly appreciate your assistance.							
Loraine Gandara									
78093		Classroom			9/8/2011		153		\$0.00
Medium	Work In Progress	204		9/8/2011 3:39:22 PM					
Moncayo, Fernando		please check air vents... rattling and loud noise greatly appreciate your assistance							
Loraine Gandara									
78372		Hallway/Corridor			9/15/2011		146		\$0.00
Medium	Work In Progress			9/15/2011 7:53:01 AM					
Moncayo, Fernando		outside corridors need to be raked and dead weeds need to be removed... greatly appreciate your assistance in this matter...							
Loraine Gandara									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden ES</b>									
77844					9/4/2011		157		\$0.00
Medium	Work In Progress			9/4/2011 12:24:16 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83646					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:58 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83647					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:58 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83648					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:59 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77297					8/23/2011		169		\$0.00
Medium	Work In Progress			8/23/2011 3:51:26 PM					
Moncayo, Fernando	need the trenching machine and the line locate for GES								
<u>Fernando Moncayo</u>									
79222					10/2/2011		129		\$0.00
Medium	Work In Progress			10/2/2011 12:27:45 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
79220					10/2/2011	10/10/2011	129		\$0.00
Medium	Work In Progress			10/2/2011 12:27:44 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
79219					10/2/2011	10/10/2011	129		\$0.00
Medium	Work In Progress			10/2/2011 12:27:44 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
76334					8/2/2011		190		\$0.00
Medium	Work In Progress	nurses office		8/2/2011 4:03:53 PM					
Moncayo, Fernando		nurses needs assistance in putting up boards in her office							
Loraine Gandara									
76933					8/15/2011		177		\$0.00
Medium	Work In Progress			8/15/2011 1:34:16 PM					
Moncayo, Fernando		please set up irrigation system for new plants in front of the school... greatly appreciate your assistance in this matter...							
Loraine Gandara									
77320					8/24/2011		168		\$0.00
Medium	Work In Progress			8/24/2011 8:18:18 AM					
Moncayo, Fernando		water daily in the morning planters in front of building until irrigation system is in place.. greatly appreciate your assistance in this matter....							
Loraine Gandara									
78664					9/22/2011		139		\$0.00
Medium	Work In Progress			9/22/2011 10:27:24 AM					
Holguin, Alfredo		Collect Equipment data and inventory per PFSA requirements.							
Alfredo Holguin									
80226		Athletic Field			10/26/2011		105		\$0.00
High	Work In Progress			10/26/2011 10:14:52					
Soria, Mike		need to install irrigation system with control and P.V.B							
Guadalupe Ontiveros									
83649					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:59 AM					
Moncayo, Fernando		Monthly - Gadsden ES - Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
83416					1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 7:44:23 AM					
Arreola, Rudy		need assistance in assembling a grill that we purchased for the school... greatly appreciate your assistance in this matter....							
Loraine Gandara									
81050		Restroom (Boys)			11/15/2011		85		\$0.00
Medium	Work In Progress	Lincoln Wing		11/15/2011 9:56:46 AM					
Lozoya, Manny		Hinges on bathroom door is broken... greatly need your assistance in this matter...							
Loraine Gandara									
2/8/2012 1:26:26 PM									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Gadsden ES</b>								
83635					2/5/2012	2/26/2012	3		\$0.00	
Medium	Work In Progress			2/5/2012 12:17:54 AM						
Orozco, Danny	Monthly - Gadsden ES Fire Sprinkler Insp -Qrtly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
77845					9/4/2011	9/15/2011	157		\$0.00	
Medium	Work In Progress			9/4/2011 12:24:17 AM						
Moncayo, Fernando	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
83645					2/5/2012	2/16/2012	3		\$0.00	
Medium	Work In Progress			2/5/2012 12:17:57 AM						
Moncayo, Fernando	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
79273					10/2/2011	10/13/2011	129		\$0.00	
Medium	Work In Progress			10/2/2011 12:28:16 AM						
Moncayo, Fernando	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
82295					1/1/2012	1/12/2012	38		\$0.00	
Medium	Work In Progress			1/1/2012 12:44:35 AM						
Moncayo, Fernando	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
<b>Count: 36 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>90</b>				<b>Total for Gadsden ES</b>	<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
83665					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:05 AM				
Herrera, Joel	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83480					2/1/2012		7		\$0.00
Medium	Work In Progress				2/1/2012 9:43:28 AM				
Lara, Ralph	Requested by Coach Banister for Varsity Football Lockerroom-Repair Fire Exit door and latch on eastside door of Varsity Football lockerroom.								
<u>Velia Alarcon</u>									
78153		Football Field			9/9/2011		152		\$0.00
Medium	Work In Progress				9/9/2011 3:55:16 PM				
Holguin, Alfredo	Running Track- needs the ruberized surface repaired at various places and lines repaitted. the long jumb runway also needs repairs.								
<u>Guadalupe Ontiveros</u>									
83810					2/7/2012		1		\$0.00
Medium	Work In Progress				2/7/2012 3:59:49 PM				
Lara, Ralph	Requested by Mr. Martin Rm. 506 Annex Building-Need to have a door closer body installed into back door kitchen area. SEE MR. MARTIN FOR FURTHER INSTRUCTIONS.								
<u>Velia Alarcon</u>									
83811					2/7/2012		1		\$0.00
Medium	Work In Progress				2/7/2012 4:01:44 PM				
Lara, Ralph	Requested by Mr. Martin Rm. 506 Annex Building-Need to have a dead bolt installed into the restroom door for privacy. SEE MR. MARTIN FOR FURTHER INSTRUCTIONS.								
<u>Velia Alarcon</u>									
81182					11/17/2011		83		\$0.00
Medium	Work In Progress				11/17/2011 9:07:32 AM				
Lara, Ralph	Requested by Ms. Miller Rm. 344 Academic Building-Door broken.								
<u>Velia Alarcon</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
76503					8/5/2011		0		\$0.00
Medium	Work In Progress			8/5/2011 11:12:06 AM		8/5/2011			
Gonzalez, Salvador	Requested by Lupe Quinones for Faculty Parking Lot- Install a cement ramp at the left far end by the "G" hall of the North Building. This ramp will serve as a come and go with the Security Golf Cart as well as for Maintenance Cart. By placing this ramp there well be two parking spaced eliminated. For further instruction please see Lupe Quinones.		8/5/11 - This needs to be approved by new administration. M. Munoz						
<u>Velia Alarcon</u>									
78823	Business	Restroom (Boys)			9/27/2011		134		\$0.00
High	Work In Progress			9/27/2011 8:25:44 AM					
Munoz, Joe	Detail all bathrooms in businesss building floors, stalls, walls and fixtures. Strip down floors corners and edges.		10/31/11 REMAILED TO JOE 11/22/11 E-MAILED TO JOE 12/15/11 - 3rd request, re-mailed						
<u>Jesus Estrada</u>									
79780	Business	Restroom (Boys)			10/14/2011		117		\$0.00
Medium	Work In Progress			10/14/2011 3:28:11 PM					
Appelzoller, Fred	Need to replace faucet on the sink in the mens restroom second floor. Thank you								
<u>Guillermo Hernandez</u>									
81340	Old English Bldg				11/22/2011		78		\$0.00
High	Work In Progress			11/22/2011 2:01:38 PM					
Castillo, Carlos	please install lighting in boiler room as per boiler inspectors site visit sn 9510126802								
<u>Michael Munoz</u>									
75453	Old English Bldg				7/14/2011		209		\$0.00
Medium	Work In Progress			7/14/2011 7:39:52 AM					
Herrera, Joel	Roof leaks Old english Building hallway. Classroom gym								
<u>Mario Apodaca</u>									
81053	Old English Bldg	Classroom			11/15/2011		85		\$0.00
Medium	Work In Progress			11/15/2011 11:31:05					
Ronquillo, Ruben	Broken window Old english building classroom #147, Double pane 42 5/8 x 38 3/4. Thank you								
<u>Guillermo Hernandez</u>									
83569	Academic Bldg	Classroom			2/3/2012		5		\$0.00
Medium	Work In Progress	GHS N. MAIN			2/3/2012 10:17:57 AM				
Lara, Ralph	AS PER MR. CHAVEZ-THE DOORS TO THE NORTH MAIN ACADEMIC BUILDING DOES NOT CLOSE CORRECTLY. (YOU PULL DOORS AND THEY JUST OPEN WHEN LOCKED)								
<u>Mary Garcia</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
75587	Academic Bldg	Office			7/20/2011		203		\$0.00
Medium	Work In Progress				7/20/2011 3:03:42 PM				
Lozoya, Manny	Need to put a new lock set at the academic blde lunch room 317								
<u>Mario Apodaca</u>									
80283	Academic Bldg				10/27/2011		104		\$0.00
Medium	Work In Progress				10/27/2011 9:40:48 AM				
Hernandez, Guillermo	Requested by Bea Marquez Rm. 319 Academic Building -Paint the office white.								
<u>Velia Alarcon</u>									
83567	Boys Gym	Gym			2/3/2012		5		\$0.00
Medium	Work In Progress				2/3/2012 8:19:11 AM				
Gonzalez, Salvador	need a screen made for dryer outlet so kids will not throw stuff in the pipe								
<u>Fred Appenzoller</u>									
78031	Boys Gym				9/7/2011		154		\$0.00
High	Work In Progress				9/7/2011 3:03:27 PM				
Herrera, Joel	please check all dressing rooms,. bathrooms and shower to see if any painting needs done, all stalls are functional etc. this is a priority.thank you								
<u>Michael Munoz</u>									
75461	Boys Gym	Dressing Room			7/14/2011		209		\$0.00
Medium	Work In Progress				7/14/2011 11:18:26 AM				
Herrera, Joel	All Boys gym roof is leaking needs a new roof								
<u>Mario Apodaca</u>									
76489	Boys Gym	Office			8/5/2011		187		\$0.00
Medium	Work In Progress				8/5/2011 9:19:08 AM				
Ambriz, Jose	Boys gymnasium split system short it out I need to replace condenser office 400								
<u>Mario Apodaca</u>									
81522	Boys Gym				11/30/2011		70		\$0.00
Medium	Work In Progress				11/30/2011 2:20:29 PM				
Ambriz, Jose	Requested by Coach Rosen for Coach's Office in the Boy's Gym-The heating/cooling unit has been broken since the start of the year, needs replacements. Office is extremely cold now.								
<u>Velia Alarcon</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
78030	Boys Gym				9/7/2011		154		\$0.00
High	Work In Progress				9/7/2011 3:01:45 PM				
Castillo, Carlos	please check all light fixtures, swithces etc for proper operation and repair if need be. this is a priority. thankyou								
<u>Michael Munoz</u>									
81335	Cafeteria (1998)				11/22/2011		78		\$0.00
High	Work In Progress				11/22/2011 1:21:53 PM				
Castillo, Carlos	boiler to kitchen area needs an emergency shut-off switch as per boiler inspectors visit. boiler sn 1006310963								
<u>Michael Munoz</u>									
83162	Cafeteria (1998)	Restroom (Boys)			1/25/2012		14		\$0.00
Medium	Work In Progress				1/25/2012 9:53:46 AM				
Lara, Ralph	The door does not unlock for public use								
<u>Joe Munoz</u>									
81329	Cafeteria (1998)				11/22/2011		78		\$0.00
Medium	Work In Progress				11/22/2011 12:53:45				
Orozco, Danny	as per psfa site visit. need to replace ceiling tiles in kitchen area and replacement of stained ones or dirty ones as well. thank you								
<u>Michael Munoz</u>									
76982	Varsity Gym	Gym			8/16/2011		176		\$0.00
Medium	Work In Progress				8/16/2011 8:57:46 AM				
Ronquillo, Ruben	Central court varsity gym Volleyball post sleeve is coming loose								
<u>Mario Apodaca</u>									
83481					2/1/2012		7		\$0.00
Medium	Work In Progress				2/1/2012 9:46:47 AM				
Gonzalez, Salvador	Requested by Coach Banister for Varsity Football Lockerroom-Need cage type door for shower room #2. See equipment room door as example. See Coach Banister for any questions.								
<u>Velia Alarcon</u>									
75465					7/14/2011		209		\$0.00
Medium	Work In Progress	Weight Room			7/14/2011 1:13:44 PM				
Gonzalez, Salvador	Need to re-install punching bag in weight room.								
<u>Michael Munoz</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
82937					1/19/2012		20		\$0.00
Medium	Work In Progress			1/19/2012 8:05:26 AM					
Gonzalez, Salvador	Need to weld door on the west side entrance door of the North Bulding by classroom #200. Thank you								
<u>Guillermo Hernandez</u>									
79902					10/18/2011		113		\$0.00
Medium	Work In Progress			10/18/2011 12:52:25					
Gonzalez, Salvador	NEED TO CONSTRUCT SHADE AT GROUNDS DEPT. TO PROTECT IMPLEMENT.								
<u>Guadalupe Ontiveros</u>									
83298					1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 2:45:25 PM					
Sanchez, Raul	Requested by Alex Vargas for Swimming Pool-Repair handcap lift. Pressure hoses are dry rotted. Operating valve is frozen.								
<u>Velia Alarcon</u>									
80114					10/24/2011		107		\$0.00
Medium	Work In Progress			10/24/2011 9:46:42 AM					
Orozco, Danny	TILT SKILLET STOPPED WORKING. SNP MANAGER LYDIA M. 882.5522								
<u>Maritza Gonzalez</u>									
83709					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:22 AM					
Sanchez, Raul	Monthly - Gadsden HS - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76903					8/14/2011		178		\$0.00
Medium	Work In Progress			8/14/2011 12:18:19 AM					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82078					12/14/2011		56		\$0.00
Medium	Work In Progress			12/14/2011 12:14:07					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75447					7/14/2011		209		\$0.00
Medium	Work In Progress			7/14/2011 12:16:25 AM					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
75625					7/21/2011		202		\$0.00
Medium	Work In Progress			7/21/2011 10:20:47 AM					
Sanchez, Raul	Domestic Water Storage Tank- Perform cleaning and inspections of interior of tank including the one at GMSI Inspection needs to be performed according to AWWA D101-53 Standard.								
Alfredo Holguin									
75626					7/21/2011		202		\$0.00
Medium	Work In Progress			7/21/2011 10:24:57 AM					
Sanchez, Raul	Domestic Water Storage Tank- install a 24" mesh wire screen or flapper valve on the overflow pipe. Do the same to the tank at GMS								
Alfredo Holguin									
80998					11/14/2011		86		\$0.00
Medium	Work In Progress			11/14/2011 12:17:28					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
83706					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:21 AM					
Sanchez, Raul	Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.								
Margret Villalobos									
82813					1/14/2012		25		\$0.00
Medium	Work In Progress			1/14/2012 12:18:18 AM					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
78665	New Admin Bldg				9/22/2011		139		\$0.00
Medium	Work In Progress			9/22/2011 10:28:44 AM					
Holguin, Alfredo	Collect Equipment data and inventory per PFSA requirements. - New Admin, New Library. and Varsity Gym Addition								
Alfredo Holguin									
81057	North Building				11/15/2011		85		\$0.00
Medium	Work In Progress			11/15/2011 11:37:36					
Ronquillo, Ruben	Glass wall by ROTC hallway needs new seating blocks, there is a opening of about 1/2 inch between glass and frame. Frame 72 inch high x 21 3/8 wide. thank you								
Guillermo Hernandez									



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
75781	Main Building	Classroom			7/25/2011		198		\$0.00
Medium	Work In Progress				7/25/2011 2:01:50 PM				
Ambriz, Jose	Need to put new vents for ac units In class room to balance out air on the east side of building								
<u>Mario Apodaca</u>									
77060	Auto Shop	Auditorium			8/17/2011		175		\$0.00
Medium	Work In Progress				8/17/2011 1:34:45 PM				
Castillo, Carlos	Due to the removal of the telephone poles On the south side of campus Need to put lights on the outside of the building Annex and auto shop								
<u>Mario Apodaca</u>									
78518	Pool Dressing				9/19/2011		142		\$0.00
Medium	Work In Progress				9/19/2011 3:44:40 PM				
Lara, Ralph	Need to repair window (?s please ask Mike)								
<u>Michael Munoz</u>									
83372	Pool Dressing	Pool			1/30/2012		9		\$0.00
Medium	Work In Progress				1/30/2012 11:30:58 AM				
Ronquillo, Ruben	Need to replace broken risers on windows. Thank you								
<u>Guillermo Hernandez</u>									
80377	Pool Dressing				10/31/2011		100		\$0.00
Medium	Work In Progress				10/31/2011 9:25:37 AM				
Ronquillo, Ruben	Need to replace broken privacy glass 27 1/2 X 15 inch boy's dressing room in the swimming pool. Thank you								
<u>Guillermo Hernandez</u>									
80887	Pool Pump	Pool			11/9/2011		91		\$0.00
Medium	Work In Progress				11/9/2011 2:20:32 PM				
Sanchez, Raul	I need a work order to change out filters at GHS pool Thanks Raul								
<u>Raul Sanchez</u>									
79836	Concession				10/17/2011		114		\$0.00
Medium	Work In Progress				10/17/2011 10:53:40				
Appelzoller, Fred	Requested by Ms. Servin for Football Concession Stand -Replace small sink with a large stainless steel sink. Also, up grade faucet fixtures.								
<u>Velia Alarcon</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
83528	Main Building				2/2/2012		6		\$0.00
Medium	Work In Progress				2/2/2012 9:32:34 AM				
Castillo, Carlos	2/2/12 We need for Carlos Castillo to help in adjusting the main water tank levels in order to keep enough head pressure for the new booster pump system to function properly. Thanks, Raul								
<u>Raul Sanchez</u>									
78123	Football Stadium	Football Field			9/9/2011		152		\$0.00
Medium	Work In Progress				9/9/2011 2:39:05 PM				
Ontiveros, Guadalupe	1 more section of fence needs to be replaced at the football field on the north end of campus								
<u>Mario Apodaca</u>									
83318					1/27/2012		12		\$0.00
Medium	Work In Progress				1/27/2012 3:19:09 PM				
Herrera, Joel	Requested by Alex Vargas for Swimming Pool-Replace broken ceramic tile along wall and shower edges in changing rooms.								
<u>Velia Alarcon</u>									
83319					1/27/2012		12		\$0.00
Medium	Work In Progress				1/27/2012 3:22:00 PM				
Herrera, Joel	Requested by Alex Vargas for Swimming Pool-Replace burned out lights (interior and exterior). Set timer for "on" at 7:30 p.m. and "off" at 5:00 a.m.								
<u>Velia Alarcon</u>									
83663					2/5/2012		3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:04 AM				
Herrera, Joel	Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83667					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:06 AM				
Herrera, Joel	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83664					2/5/2012	3/7/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:05 AM				
Herrera, Joel	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
82859					1/17/2012		22		\$0.00
Medium	Work In Progress			1/17/2012 3:21:35 PM					
Herrera, Joel	Requested by Mr. Pokluda for Rm. 153 in the Old English Building-SEE MR. ZEMEK FIRST-Teacher is requesting mailboxes from old mail room moved to his classroom. SEE TEACHER FIRST.								
<u>Velia Alarcon</u>									
82440					1/6/2012		33		\$0.00
Medium	Work In Progress			1/6/2012 7:48:57 AM					
Ronquillo, Ruben	Ruben, Requesting: 1- dry wall pan; 1-10 inch taper knife; 1-acetylen gauge; 1- acetylen wrench. Thank you								
<u>Guillermo Hernandez</u>									
82299					1/1/2012	1/9/2012	32		\$0.00
Medium	Work In Progress			1/1/2012 12:44:37 AM		2/2/2012			
Hernandez, Guillermo	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78269		Athletic Field			9/13/2011		148		\$0.00
Medium	Work In Progress			9/13/2011 3:25:00 PM					
Flores, Pete	Truck # 137 needs transmission oil and filter changed. Also motor oil and filter.								
<u>Guadalupe Ontiveros</u>									
83309					1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 3:03:59 PM					
Sanchez, Raul	Requested by Alex Vargas for Swimming Pool-Repair pool deck, several areas around the deck have become unglued and could be a tripping hazard.								
<u>Velia Alarcon</u>									
83767		Athletic Field			2/7/2012		1		\$0.00
Medium	Work In Progress			2/7/2012 8:14:22 AM					
Holguin, Ramiro	replace sprinklers that are not working on baseball field and softball.								
<u>Guadalupe Ontiveros</u>									
83443		Athletic Field			1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 1:51:47 PM					
Lara, Ralph	new storage at grounds dept needs pad lock, to open with HE-163.								
<u>Guadalupe Ontiveros</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
80284					10/27/2011		104		\$0.00
Medium	Work In Progress			10/27/2011 9:48:00 AM					
Lara, Ralph	Requested by Coach Rios for Soccer Goal Posts in the Stadium-Six keys are needed to unlock the goal post for practice. One for each soccer and for key box.								
Velia Alarcon									
81236					11/18/2011		82		\$0.00
Medium	Work In Progress			11/18/2011 8:58:07 AM					
Lara, Ralph	Requested by Ms. Armendariz for all of the Counselors Offices in the New Admin. Building-Change all locks to the same key for the Counseling Center Staff, office room numbers 710, 712, 713, 714, 715.								
Velia Alarcon									
78599					9/21/2011		140		\$0.00
Medium	Work In Progress			9/21/2011 9:16:30 AM					
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Plant seed (grass) to fill first base and third base lines with grass instead fo dirt for the infield.								
Velia Alarcon									
82677					1/11/2012		28		\$0.00
High	Work In Progress			1/11/2012 1:58:51 PM					
Ontiveros, Guadalupe	need booster cables to carry in trucks in case we would have to jump start tractors.								
Guadalupe Ontiveros									
79573					10/10/2011		121		\$0.00
Medium	Work In Progress			10/10/2011 2:17:26 PM					
Ontiveros, Guadalupe	Requested by Coach Yanez-Set up batting cage with older brackets/poles. Add new cage set up next to the longer cage already in place to make it a double cage.								
Velia Alarcon									
83807		Athletic Field			2/7/2012		1		\$0.00
Medium	Work In Progress			2/7/2012 3:57:01 PM					
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Set up frame poles to add another batting cage. Poles have already been placed in batting cage area. They only need to be set in the ground (3 frames).								
Velia Alarcon									
76762					8/10/2011		182		\$0.00
Medium	Work In Progress			8/10/2011 9:12:44 AM					
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Move baseball storage shed directly behind dugout and surround it with a fence and gate to prevent any more thefts of our equipment.								
Velia Alarcon									
2/8/2012 1:26:27 PM									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
82899					1/18/2012		21		\$0.00
Medium	Work In Progress			1/18/2012 10:52:47 AM					
Munoz, Michael	refurbish exisiting wall shelve and instal new shelving 8 with support for storage and security of art supplies.								
<u>Michael Munoz</u>									
83437					1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 12:38:58 PM					
Herrera, Joel	Requested by Mrs. King Rm. 334 Academic Building- Florescent light cover panel is falling down from one corner. Also, replace burned out light bulbs above teacher's desk.								
<u>Velia Alarcon</u>									
83087					1/23/2012		16		\$0.00
Medium	Work In Progress			1/23/2012 3:46:48 PM					
Herrera, Joel	1-23-12 1.0 CHECK WATER HEATER AT CAFETERIA 2.0 CHECK HEATERS UNITS 2.0 REPLACE LIGHTS BALLAST AT NURSE OFFICE COST \$ 25.00 EACH. ONE 2.0 REPAIR GIRLS REST ROOMS AT FLOWER SHOP 1.0 INSTALL PACTURES AT LIBRARY								
<u>Joel Herrera</u>									
83111					1/24/2012		15		\$0.00
Medium	Work In Progress			1/24/2012 10:46:00 AM					
Herrera, Joel	Requested by Counseling Department-Assemble table.								
<u>Velia Alarcon</u>									
82222					1/1/2012		38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:02 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83436					1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 12:36:16 PM					
Hernandez, Guillermo	Requested by Mr. V. Hernandez Rm. 200 Norht Building -Dismount the in-focus from the ceiling and assemble video cart to place in-focus on cart.								
<u>Velia Alarcon</u>									
83438					1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 12:40:31 PM					
Hernandez, Guillermo	Requested by Mrs. King for Rm. 334 Academic Building- Ceiling tiles in three corners needs to be placed over opening.								
<u>Velia Alarcon</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
82657					1/11/2012		28		\$0.00
Medium	Work In Progress			1/11/2012 7:43:36 AM					
Hernandez, Guillermo	Please check classroom for installation of exhaust fan for lasser engraver in Ms. Romero Classroom. Thank you								
<u>Guillermo Hernandez</u>									
80754					11/7/2011		93		\$0.00
Medium	Work In Progress			11/7/2011 8:25:33 AM					
Hernandez, Guillermo	Requested by Velia for Weight Room-There are several broken ceiling tiles that are broken and need to be replaced.		Asp report 1/19/12 Wo to be completed with welding work order						
<u>Velia Alarcon</u>									
83650					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:59 AM					
Hernandez, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83814					2/7/2012		1		\$0.00
Medium	Work In Progress			2/7/2012 4:04:38 PM					
Hernandez, Guillermo	Requested by Mr. Martin Rm. 506 Annex Building-Need to have a privacy screen installed around the commode in restroom for privacy.								
<u>Velia Alarcon</u>									
82809					1/13/2012		26		\$0.00
Medium	Work In Progress			1/13/2012 4:07:35 PM					
Ronquillo, Ruben	Need to replace broken window glass on the security shack. size 16 1/8 x 32 1/2 double side window. Thank you								
<u>Guillermo Hernandez</u>									
83830					2/8/2012		0		\$0.00
Medium	Work In Progress			2/8/2012 9:17:21 AM					
Ronquillo, Ruben	BROKEN DOOR'S WINDOW AT GIRLS G.Y.M WIRE GLASS								
<u>Joel Herrera</u>									
81794					12/5/2011		65		\$0.00
Medium	Work In Progress			12/5/2011 12:47:37 PM					
Ronquillo, Ruben	Please replace broken mesh glass in the Girls Gym north side exit door. Thank you 27 3/4 x 24 inch.								
<u>Guillermo Hernandez</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

81514					11/30/2011		70		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/30/2011 12:10:28				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose Requested by Ms. Hartmann Rm. 107 Main Building- Room 107 is very very cold, while the attached rooms (106, 105, etc.) on the same system are hot. It is difficult for the students to paint with jackets on and cold hands.

Velia Alarcon

83222					1/26/2012		13		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/26/2012 7:59:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph BROKEN DOOR'S HANDLE AT COMP. LAB.

Joel Herrera

82938					1/19/2012		20		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/19/2012 8:08:00 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Need to replace door lock boys restroom in the cafeteria. Thank you

Guillermo Hernandez

82903					1/18/2012		21		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/18/2012 12:14:59 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Mr. Pokluda for Rm. 329 in Academic Building-Office door needs to be changed to a X38 and two extra keys are needed.

Office will be used to store testing materials. This work order needs to be completed as soon as possible since the testing time is here.

Velia Alarcon

81818					12/5/2011		65		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/5/2011 3:41:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose Need to replace T-stats in Old English ( T-sat # trane X13510933-02) Thank you

Guillermo Hernandez

82656					1/11/2012		28		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/11/2012 7:41:40 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose Need to replace water filter for ice maker in Panther Hood. (Filter R53-590). Thank you

Guillermo Hernandez

82852					1/17/2012		22		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/17/2012 3:14:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose Requested by Ms. Hamilton Rm. 562 Ag. Shop-Please fix freon to the cooler. Needs to fund sales and Valentine's Day is approaching quickly.

Velia Alarcon

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
82936					1/19/2012		20		\$0.00
Medium	Work In Progress			1/19/2012 8:02:08 AM					
Ambriz, Jose	Need to replace cicuit board on a York unit in the kitchen. Model #P-WHD12L060A SERIAL #WNFP033645 (BOARD #6302-318/1012-952) 97310. Thank you								
Guillermo Hernandez									
83471					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 8:36:56 AM					
Castillo, Carlos	Need to install GFI electric outlets and covers in Science classroom at North building X's 5. Thank you								
Guillermo Hernandez									
83482					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 9:49:18 AM					
Castillo, Carlos	Requested by Coach Banister for Varsity Football Lockerroom-Repair light switch and light for fire exit on eastside entrance of Varsity Football lockerroom.								
Velia Alarcon									
83235					1/26/2012		13		\$0.00
Medium	Work In Progress			1/26/2012 11:57:05 AM					
Castillo, Carlos	Requested by Mr. Andersen Rm. 226 in North Building-Cover bare electrical wires that are exposed on the lab tables or possibley cut off the power.								
Velia Alarcon									
76692					8/9/2011		183		\$0.00
Medium	Work In Progress			8/9/2011 10:00:29 AM					
Castillo, Carlos	Requested by Mr. Myers for East Wing of Cafeteria-Need electric outlet for new computers and solder stations.								
Velia Alarcon									
83527		Lift Station			2/2/2012		6		\$0.00
Medium	Work In Progress			2/2/2012 9:26:05 AM					
Castillo, Carlos	2/2/12 I need for an electrician to check north campus lift station electrical panel.I cleaned the floats but there seems to be another problem with them. Thanks, Raul								
Raul Sanchez									
78771					9/26/2011		135		\$0.00
Medium	Work In Progress			9/26/2011 11:08:07 AM					
Hernandez, Guillermo	Requested by Mr. D. Martinez for Cafeteria Entrance-Requesting to have the awnings located outside the entrances of the cafeteria painted the same color as the cafeteria doors.								
Velia Alarcon									
2/8/2012 1:26:27 PM									



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
78772					9/26/2011		135		\$0.00
Medium	Work In Progress			9/26/2011 11:13:48 AM					
Hernandez, Guillermo	Requested by Mr. D. Martinez for Cafeteria-Requesting that the window frames inside and outside of the cafeteria be painted the same color as the cafeteria doors. -The color for the cafeteria doors was chosen the week of 09/19/11. We would like to match the color requested to the color on the window frames of the New Administrative/Library Building.								
Velia Alarcon									
83296					1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 2:41:33 PM					
Hernandez, Guillermo	Requested by Alex Vargas for Swimming Pool (Pool Side)-Clean and paint rust. Repair worn-out steps. Repair and reseal slides.								
Velia Alarcon									
83300					1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 2:48:44 PM					
Hernandez, Guillermo	Requested by Alex Vargas for Swimming Pool-Repair exterior walls on building and surrounding walls. Several cracks and fallen grout in various areas. Paint as well.								
Velia Alarcon									
83303					1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 2:54:51 PM					
Hernandez, Guillermo	Requested by Alex Vargas for Swimming Pool-Tighten benches in dressing rooms and paint.								
Velia Alarcon									
83321					1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 3:24:22 PM					
Hernandez, Guillermo	Requested by Alex Vargas for Swimming Pool-Repaint and seal floor, must be anti-skid.								
Velia Alarcon									
83145					1/24/2012		15		\$0.00
Medium	Work In Progress			1/24/2012 4:01:39 PM					
Herrera, Joel	Requested by Oscar Menchaca for Boy's Restroom in Main Building-Needs to be painted.								
Velia Alarcon									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
78777					9/26/2011		135		\$0.00
Medium	Work In Progress			9/26/2011 11:48:49 AM					
Herrera, Joel	Requested by Mr. D. Martinez-After WORK ORDER # 78775 is completed. The short blue/gray wall in front of the Cafeteria needs to be painted.								
<u>Velia Alarcon</u>									
76747					8/10/2011		182		\$0.00
High	Work In Progress			8/10/2011 8:05:35 AM					
Ambriz, Jose	Ice Machine not working at grounds shop								
<u>Guadalupe Ontiveros</u>									
77046					8/17/2011		175		\$0.00
Medium	Work In Progress			8/17/2011 9:30:10 AM					
Holguin, Alfredo	Requested by Ms. Seiler for Rm. 134 Old English Building-Room has become increasing in mold and is causing allergic reactions in me and may very possibly in students whom I serve here at GHS. Administration has indicated to me that they are looking for another room to move me to, until they can. Please provide me with an air purifier to purify the air and minimize the health effects of the poor air quality in room 134.								
<u>Velia Alarcon</u>									
83228					1/26/2012		13		\$0.00
Medium	Work In Progress			1/26/2012 9:29:20 AM					
Appelzoller, Fred	Requested by Ms. Nevarez Rm. 125 Main Building-The small water heater is leaking all over the floor in the class restroom.								
<u>Velia Alarcon</u>									
83306					1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 2:57:01 PM					
Appelzoller, Fred	Requested by Alex Vargas for Swimming Pool-Leak in janitor's sink (cold water valve).								
<u>Velia Alarcon</u>									
83381					1/30/2012		9		\$0.00
Medium	Work In Progress	LINE LOCATE		1/30/2012 2:30:17 PM					
Appelzoller, Fred	NM One Call Need to line locate for Caliper Construction contact Ron Davis @ 575-524-3924 if you should have any questions.								
Michael Munoz									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
82460					1/6/2012		33		\$0.00
Medium	Work In Progress			1/6/2012 11:28:36 AM					
Appelzoller, Fred	Would you please check water heater in the kitchen, I reseted and keeps on shutting off. Thank you								
<u>Guillermo Hernandez</u>									
80212					10/25/2011		106		\$0.00
Medium	Work In Progress			10/25/2011 4:05:58 PM					
Appelzoller, Fred	Requested by Cathy for Boy's Gym-Install new washers and Dryers.								
<u>Velia Alarcon</u>									
79839					10/17/2011		114		\$0.00
Medium	Work In Progress			10/17/2011 11:10:53					
Appelzoller, Fred	Requested by Ms. Sevin for Football Concession Stand-Replace sink in the back of Football Concession Stand with a large stainless steel sink.								
<u>Velia Alarcon</u>									
83541					2/2/2012		6		\$0.00
Medium	Work In Progress			2/2/2012 3:18:36 PM					
Appelzoller, Fred	FRED WE NEED TO REPLACE ANGLE STOP ON TWO W/C IN NORTH BUILDING AT GIRLS REST ROOMS								
<u>Joel Herrera</u>									
82659					1/11/2012		28		\$0.00
Medium	Work In Progress			1/11/2012 7:45:10 AM					
Castillo, Carlos	Need assistance trouble shooting electric outlet in the V. Gym bleachers. Thank you								
<u>Guillermo Hernandez</u>									
83829					2/8/2012		0		\$0.00
Medium	Work In Progress			2/8/2012 9:13:14 AM					
Castillo, Carlos	CALI WE HAVE ELECTRICAL PROBLEM ON LAMP AT CLASS ROOM # 334 AT ACADEMIC BUILDING								
<u>Joel Herrera</u>									
81933					12/9/2011		61		\$0.00
Medium	Work In Progress			12/9/2011 10:08:47 AM					
Castillo, Carlos	Requested by Velia for Boy's Gym-Install new electrical outlets in the Boy's Gym to install new washer and dryer.								
<u>Velia Alarcon</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location: Gadsden HS</b>										
82851					1/17/2012		22		\$0.00	
Medium	Work In Progress			1/17/2012 3:11:09 PM						
Sanchez, Raul	need to reset the floats on the domestice water storage tank so it starts the pump at 17 ft instead of the curent 13 ft.									
<b>Alfredo Holguin</b>										
83666					2/5/2012	2/8/2012	3		\$0.00	
Medium	Work In Progress			2/5/2012 12:18:05 AM						
Herrera, Joel	Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.									
<b>Margret Villalobos</b>										
82263					1/1/2012	2/1/2012	38		\$0.00	
Medium	Work In Progress			1/1/2012 12:44:22 AM						
Villalobos, David	Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.									
<b>Margret Villalobos</b>										
<b>Count: 120 Work Orders</b>		<b>Avg. Age of WO's 66</b>		<b>Total for Gadsden HS</b>			<b>0</b>	<b>\$0.00</b>		

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
82264					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:22 AM					
Villalobos, David	Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
83721					2/5/2012	2/8/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:26 AM					
Diaz, Sebastian	Monthly - Gadsden MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
83534					2/2/2012		6		\$0.00
Medium	Work In Progress			2/2/2012 11:58:48 AM					
Sotelo, Enrique	Need to check motor in bleaches thank you								
Sebastian Diaz									
83195					1/25/2012		14		\$0.00
Medium	Work In Progress			1/25/2012 3:33:19 PM					
Appelzoller, Fred	Need to check circulate pump in boiler cafeteria thank you								
Sebastian Diaz									
82566					1/9/2012		30		\$0.00
Medium	Work In Progress			1/9/2012 1:32:53 PM					
Appelzoller, Fred	Need to fix broken water pipe in roof gym thank you								
Sebastian Diaz									
83015					1/20/2012		19		\$0.00
Medium	Work In Progress			1/20/2012 12:33:54 PM					
Appelzoller, Fred	Need to replace mop sinks in rooms 307,306 thank you								
Sebastian Diaz									
83825					2/8/2012		0		\$0.00
Medium	Work In Progress			2/8/2012 8:39:39 AM					
Appelzoller, Fred	Need to fix water fountain in playground thank you								
Sebastian Diaz									
81257					11/18/2011		82		\$0.00
Medium	Work In Progress			11/18/2011 3:41:38 PM					
Appelzoller, Fred	Need to unclog water fountain drain in A wing thank you								
Sebastian Diaz									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden MS</b>							
76367		Cafeteria			8/3/2011		189		\$0.00
Medium	Work In Progress				8/3/2011 1:35:38 PM				
Sotelo, Enrique	please install ceiling fans in kitchen area. see mike.thanks								
Michael Munoz									
83826					2/8/2012		0		\$0.00
Medium	Work In Progress				2/8/2012 8:41:24 AM				
Solis, Lorenzo	Need to fix broken water line in heater in B wing hall thank you								
Sebastian Diaz									
81621		Parking Lot			12/2/2011		68		\$0.00
Medium	Work In Progress	GMS Parking lot			12/2/2011 2:39:34 PM				
Diaz, Sebastian	Paint GMS Parking lot.								
Maricruz Carrasco									
83823					2/8/2012		0		\$0.00
Medium	Work In Progress				2/8/2012 8:33:55 AM				
Lozoya, Manny	Need to fix broken door in room 115 thank you								
Sebastian Diaz									
83824					2/8/2012		0		\$0.00
Medium	Work In Progress				2/8/2012 8:38:34 AM				
Lozoya, Manny	Need to fix door cilinder in concetion stand and rest boy's thank you								
Sebastian Diaz									
83341		Classroom			1/27/2012		12		\$0.00
Medium	Work In Progress	Bwing/121/A.			1/27/2012 3:46:25 PM				
Solis, Lorenzo	One of my heaters sounds and feels like it is on when the switch is off. It gets extremely hot in the afternoons.								
Maricruz Carrasco									
83533					2/2/2012		6		\$0.00
Medium	Work In Progress				2/2/2012 11:56:39 AM				
Lozoya, Manny	Need tto fix door in room 115 thank you								
Sebastian Diaz									
82735					1/12/2012		27		\$0.00
Medium	Work In Progress				1/12/2012 3:28:48 PM				
Lozoya, Manny	Need to fix door in vocational closer thank you								
Sebastian Diaz									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
82738					1/12/2012		27		\$0.00
Medium	Work In Progress			1/12/2012 3:31:28 PM					
Lozoya, Manny	Need to fix door cilindrer in hall gym boy's rest thank you								
Sebastian Diaz									
82741					1/12/2012		27		\$0.00
Medium	Work In Progress			1/12/2012 3:35:35 PM					
Lozoya, Manny	Need to fix main entrances doors some not open with the key								
Sebastian Diaz									
82826		Office			1/17/2012		22		\$0.00
Medium	Work In Progress	Front		1/17/2012 10:11:24 AM					
Lozoya, Manny	Need new key for desk cabinet. See Connie for more information.								
Maricruz Carrasco									
77103		Classroom			8/18/2011		174		\$0.00
Medium	Work In Progress	108/A. Franco		8/18/2011 12:44:26 PM					
Lozoya, Manny	Need lock on cabinet in room 108 as soon as possible.								
Maricruz Carrasco									
75914		Office			7/27/2011		196		\$0.00
Medium	Work In Progress	Bwing/124/Diag		7/27/2011 3:47:50 PM					
Lozoya, Manny	Replace lock in cabint in room 124								
Maricruz Carrasco									
75722		Office			7/22/2011		201		\$0.00
Medium	Work In Progress	Administrator		7/22/2011 3:26:19 PM					
Lozoya, Manny	Need locks on four filing cabinets in Administrator's office. Please see Mr. Calleros for more information.								
Maricruz Carrasco									
83168					1/25/2012		14		\$0.00
Medium	Work In Progress			1/25/2012 1:51:06 PM					
Diaz, Sebastian	Need 10 door stops for handi cup doors thank you								
Sebastian Diaz									
83719					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:26 AM					
Diaz, Sebastian	Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
83718					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:25 AM					
Diaz, Sebastian	Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83716					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:25 AM					
Diaz, Sebastian	Monthly - Gadsden MS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82617		Parking Lot			1/10/2012		29		\$0.00
Medium	Work In Progress			1/10/2012 11:29:26 AM					
Diaz, Sebastian	as per mr. chavez and our discussion, please paint loading and unloading zones on the west parking lot by vocational building and order and install large loading and unloading only sign on fence. thank you								
<u>Michael Munoz</u>									
83120	Vocational	Classroom			1/24/2012		15		\$0.00
Medium	Work In Progress	Vocational/307/		1/24/2012 3:11:59 PM					
Appelzoller, Fred	Replace sink in room 307 as per Mrs. Quinonez.								
<u>Maricruz Carrasco</u>									
77691					9/1/2011		160		\$0.00
Medium	Work In Progress			9/1/2011 8:37:00 AM					
Sanchez, Raul	9/01/11 I need a work order for the purchasing of plotter paper for the wwtp flowmeter at GMS & GHS;thanks Raul								
<u>Raul Sanchez</u>									
83685					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:13 AM					
Apodaca, Mario	Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83686					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:13 AM					
Apodaca, Mario	Monthly - Gadsden MS - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83540		Cafeteria			2/2/2012		6		\$0.00
Medium	Work In Progress			2/2/2012 3:10:56 PM					
Orozco, Danny	need to move kitchen equipment from anthony elem kitchen to different locations								
<u>Danny Orozco</u>									
2/8/2012 1:26:27 PM									



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
83114	C-Wing				1/24/2012		15		\$0.00
Medium	Work In Progress	C		1/24/2012 12:22:05 PM					
Diaz, Sebastian	Both of the student toilets have been backing up. Can you please send someone to fix them.								
82711	C-Wing				1/12/2012		27		\$0.00
Medium	Work In Progress	CHARTER		1/12/2012 9:27:38 AM					
Diaz, Sebastian	Charter School- Whenever it rains water leaks into the far east two classrooms causing puddles on the floor next electrical equipment.								
<u>Melenie Beegle</u>									
83495	C-Wing	Portables			2/1/2012		7		\$0.00
Medium	Work In Progress	Gate		2/1/2012 2:26:13 PM					
Lara, Ralph	AS PER MARY GARCIA-SOUTH GATE, NEXT TO PARKIING LOT, THE KEY CORE ON THE LOCK CAME OUT. (MARY GARCIA HAS KEY CORE IN OFFICE.)								
<u>Mary Garcia</u>									
83059	Gym				1/23/2012		16		\$0.00
Medium	Work In Progress			1/23/2012 10:42:37 AM					
Carbajal, Jimmy	I AN REQUESTING FOR NEW ELECTRIC BLOWER FOR THE GYM								
<u>Juan Acosta</u>									
83336	Gym				1/27/2012		12		\$0.00
Medium	Work In Progress	Gym/Boys		1/27/2012 3:44:55 PM					
Diaz, Sebastian	Holes in sheet rock.								
<u>Maricruz Carrasco</u>									
81934	Gym				12/9/2011		61		\$0.00
Medium	Work In Progress	Gym		12/9/2011 10:34:37 AM					
Lozoya, Manny	Repair handle on outside door in gym.								
<u>Maricruz Carrasco</u>									
81052	Cafeteria	Cafeteria			11/15/2011		85		\$0.00
Medium	Work In Progress	Cafeteria		11/15/2011 11:26:14					
Lozoya, Manny	Fix door stops in cafeteria.								
<u>Maricruz Carrasco</u>									
83276	Cafeteria				1/27/2012		12		\$0.00
Medium	Work In Progress	Kitchen		1/27/2012 11:08:30 AM					
Diaz, Sebastian	SEVERAL TILES ARE LIFTING IN KITCHEN AREA.								
<u>Maritza Gonzalez</u>									

2/8/2012 1:26:27 PM

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Gadsden MS</b>							
83720					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:26 AM				
Diaz, Sebastian		Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 41 Work Orders</b>		<b>Avg. Age of WO's 39</b>			<b>Total for Gadsden MS</b>			<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: La Union ES</b>									
83696					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:17 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
80343					10/28/2011		103		\$0.00
Medium	Work In Progress			10/28/2011 3:07:12 PM					
Lara, Ralph	need door sweeps for hall wall doors to playground - need weather streep for doors old wing out side doors								
Patricio Aguilar									
81986					12/11/2011	12/27/2011	59		\$0.00
Medium	Work In Progress			12/11/2011 12:14:23					
Aguilar, Patricio	Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
83708					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:22 AM					
Sanchez, Raul	Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details.								
Margret Villalobos									
83728	Main Building	Office			2/6/2012		2		\$0.00
Medium	Work In Progress			2/6/2012 9:13:51 AM					
Estrada, Jesus	Carpet in the office secretary,councilor needs to be replaced.								
Santos Galindo									
83694					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:16 AM					
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
83697					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:18 AM					
Aguilar, Patricio	Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
83695					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:17 AM					
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>La Union ES</b>							
81639					12/2/2011		68		\$0.00
Medium	Work In Progress			12/2/2011 3:41:47 PM					
Aguilar, Patricio	w.o. to myself replace mini-blinds r300								
Patricio Aguilar									
82533					1/8/2012	1/24/2012	31		\$0.00
Medium	Work In Progress			1/8/2012 12:16:09 AM					
Galindo, Santos	Monthly - QRTLY BLDG INSP REPORT (LU) - Refer to PM schedule details.								
Jesus Estrada									
83784					2/7/2012		1		\$0.00
Medium	Work In Progress			2/7/2012 3:16:45 PM					
Ambriz, Jose	heater valave is not closing room getting hot - we replaced valave 2 years ago r311 - thank you for your help								
Patricio Aguilar									
81336		Cafeteria			11/22/2011		78		\$0.00
High	Work In Progress			11/22/2011 1:24:10 PM					
Castillo, Carlos	boiler to kitchen does not have an emergency shut off switch. please install one as per boiler inspectors site visit boiler sn 9209102691								
Michael Munoz									
83248					1/26/2012		13		\$0.00
Medium	Work In Progress			1/26/2012 3:08:45 PM					
Castillo, Carlos	need new light fixer for rest room r309 the ballast is bad - thank you for your help								
Patricio Aguilar									
80155		Classroom			10/24/2011		107		\$0.00
Medium	Work In Progress	MR.		10/24/2011 4:01:22 PM					
Castillo, Carlos	WIRING/CABLING FOR WHITE BOARDS/PROJECTORS.								
Virginia Galindo									
79421					10/5/2011		126		\$0.00
Medium	Work In Progress			10/5/2011 1:52:11 PM					
Castillo, Carlos	need to relocate elect outlet from wall to above counter may need to use gfi - thank you								
Patricio Aguilar									
79695					10/12/2011		119		\$0.00
Medium	Work In Progress			10/12/2011 2:46:16 PM					
Castillo, Carlos	need ballast for light fixer with emer light in it - need new emer light fixer set up								
Patricio Aguilar									

2/8/2012 1:26:27 PM

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>La Union ES</b>							
80091					10/21/2011		110		\$0.00
Medium	Work In Progress			10/21/2011 3:43:54 PM					
Castillo, Carlos	need 2 light fixer for build out side wall new wing cort yard - thank you - go cowboys								
Patricio Aguilar									
82845					1/17/2012		22		\$0.00
Medium	Work In Progress			1/17/2012 2:28:31 PM					
Castillo, Carlos	wiring for white board projecors r207 thank you for your help								
Patricio Aguilar									
80774					11/7/2011		93		\$0.00
Medium	Work In Progress			11/7/2011 2:32:07 PM					
Villalobos, David	HOT HOT WATER IN KITCHEN.SNP MANAGER LINDA Y.589.2040								
Maritza Gonzalez									
82267					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:23 AM					
Villalobos, David	Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
78717					9/23/2011		138		\$0.00
Medium	Work In Progress			9/23/2011 10:13:59 AM					
Villalobos, David	need a new water line for new refrigerator ice maker in the new wing teachers lounge								
Patricio Aguilar									
76712					8/9/2011		183		\$0.00
Medium	Work In Progress			8/9/2011 2:54:02 PM					
Villalobos, David	need faucet for hand sink in women rest room new wing - also need the two cut off valves under sink								
Patricio Aguilar									
<b>Count: 22 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>59</b>	<b>Total for La Union ES</b>		<b>0</b>	<b>\$0.00</b>	

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
82265					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress				1/1/2012 12:44:22 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
82857		Parking Lot			1/17/2012		22		\$0.00
Medium	Work In Progress	Main Parking Lot			1/17/2012 3:19:22 PM				
Arreola, Rudy		Repaint the fire lane in the main parking lot.							
Angie Flores									
82827		Classroom			1/17/2012		22		\$0.00
Medium	Work In Progress				1/17/2012 10:23:43 AM				
Lozoya, Manny		please on room # 205 i have trouble to open the door this morning the cylinder is the working from the door, thank you							
Luis Saucedo									
81923					12/8/2011		62		\$0.00
Medium	Work In Progress				12/8/2011 4:02:45 PM				
Ronquillo, Ruben		please replace laminated covers on marquee. please see mike for details, thank you							
Michael Munoz									
83705					2/5/2012		3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:21 AM				
Arreola, Rudy		Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
83702					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:19 AM				
Arreola, Rudy		Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
83703					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:20 AM				
Arreola, Rudy		Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
81310		Portables			11/21/2011		79		\$0.00
High	Work In Progress				11/21/2011 3:58:41 PM				
Arreola, Rudy		please skirt double portable and also insulate water line .thank you							
Michael Munoz									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
81988					12/11/2011	12/27/2011	59		\$0.00
Medium	Work In Progress			12/11/2011 12:14:24					
Arreola, Rudy	Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81909	Main Building	Hallway/Corridor			12/8/2011		62		\$0.00
Medium	Work In Progress			12/8/2011 3:03:54 PM					
Estrada, Jesus	ABOUT 800 LINEAR FT OF BASE BOARD NEEDS TO BE REPLACED TRIED GLUEING AND GLUE STRIPS.								
<u>Rudy Arreola</u>									
78264	Main Building	Classroom			9/13/2011		148		\$0.00
Medium	Work In Progress			9/13/2011 2:30:13 PM					
Estrada, Jesus	need moulding in room 222		1/30/12 - PENDING FROM RODRIGUEZ						
<u>Rudy Arreola</u>									
81928	Main Building	Mechanical			12/9/2011		61		\$0.00
Medium	Work In Progress			12/9/2011 7:47:57 AM					
Solis, Lorenzo	NEED TO HAVE BOTH PUMPS FOR BOILER SYSTEM REPLACED.								
<u>Rudy Arreola</u>									
80328	Main Building	Hallway/Corridor			10/28/2011		103		\$0.00
Medium	Work In Progress			10/28/2011 10:43:28					
Lozoya, Manny	Please replace key for dsplay case.								
<u>Gidget Mora</u>									
81929	Main Building	Parking Lot			12/9/2011		61		\$0.00
Medium	Work In Progress			12/9/2011 7:48:59 AM					
Gonzalez, Salvador	NEED TO REPAIR MARQUEE DUE TO HIGH WINDS.								
<u>Rudy Arreola</u>									
81613	Main Building	Restroom (Boys)			12/2/2011		68		\$0.00
Medium	Work In Progress	boys and girls		12/2/2011 12:50:25 PM					
Arreola, Rudy	The exhaust fan from boys and girls restrooms across teacher lounge, the man and woman (teachers) restrooms on the third grade wing and the girls restroom from the lobby next to the cafeteria eastside, women (teacher) restroom on the 5,6,7 grade wing are not working.								
<u>Gidget Mora</u>									
82571	Main Building	Choral			1/9/2012		30		\$0.00
Medium	Work In Progress			1/9/2012 3:09:16 PM					
Arreola, Rudy	NEED BLINDS REPLACED 62x68. ALMOND COLOR TOTAL OF 40								
<u>Rudy Arreola</u>									
2/8/2012 1:26:27 PM									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Loma Linda ES</b>									
80110	Main Building	Cafeteria			10/24/2011		107		\$0.00
Medium	Work In Progress				10/24/2011 9:12:19 AM				
Sotelo, Enrique	NEED COVER FOR LIGHT FIXTURE IN CAFETERIA.								
Rudy Arreola									
83384	Main Building	Restroom (Girls)			1/30/2012		9		\$0.00
Medium	Work In Progress				1/30/2012 2:54:32 PM				
Sotelo, Enrique	bROKEN LIGHT FIXTURE COVER IN GIRLS RESTROOM IN FRONT OF TEACHERS LOUNGE. NEED NEW ONE.								
Rudy Arreola									
77512	Main Building	Athletic Field			8/29/2011		163		\$0.00
Medium	Work In Progress				8/29/2011 10:47:46 AM				
Appelzoller, Fred	WATER FOUNTAIN BEHIND LIBRARY NEEDS TO BE REPLACED.								
Rudy Arreola									
83020	Main Building	Classroom			1/20/2012		19		\$0.00
Medium	Work In Progress				1/20/2012 2:54:27 PM				
Sotelo, Enrique	BROKEN COVER FOR LIGHT FIXTURE. IN ROOM 106								
Rudy Arreola									
83738	Main Building				2/6/2012		2		\$0.00
Medium	Work In Progress				2/6/2012 2:49:10 PM				
Appelzoller, Fred	NEW UNRINAL THAT WAS JUST REPLACED CLOGGED AGAIN TRIED TO UNCLOGGED BUT DIIDNT WORK. URINAL STILL CLOGGED.								
Rudy Arreola									
81806	Main Building	Office			12/5/2011		65		\$0.00
Medium	Work In Progress				12/5/2011 3:18:57 PM				
Solis, Lorenzo	NEED MOTOR FOR FAN COIL IN FRONT OFFICE ALSO NEED SUPPORT FOR INSTALLATION.								
Rudy Arreola									
82940	Main Building	Mechanical			1/19/2012		20		\$0.00
Medium	Work In Progress				1/19/2012 8:21:22 AM				
Solis, Lorenzo	BOILER IS DOWN AGAIN. 1-19-2012								
Rudy Arreola									
80288	Main Building	Parking Lot			10/27/2011		104		\$0.00
Medium	Work In Progress				10/27/2011 10:04:45				
Arreola, Rudy	Re-paint the firelane in teacher parking lot.								
Gidget Mora									



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Loma Linda ES</b>								
82854	Main Building				1/17/2012		22		\$0.00	
Medium	Work In Progress	Hallway		1/17/2012 3:18:08 PM						
Arreola, Rudy	Repaint door frames in nurse, counselor and coaches office where they are chipped.									
<u>Angie Flores</u>										
83440					1/31/2012		8		\$0.00	
Medium	Work In Progress			1/31/2012 1:36:57 PM						
Orozco, Danny	washing machine, it is leaking water from the bottom. SNP Manager Frances B. 882.4707									
<u>Maritza Gonzalez</u>										
83566					2/3/2012		5		\$0.00	
Medium	Work In Progress			2/3/2012 8:17:00 AM						
Gonzalez, Salvador	need a stand for drinking fountain made 10 inches wide by 60 inches long with 48 inch of 1 by 1 inch square tubing for the legs									
<u>Fred Appelzoller</u>										
83704					2/5/2012	2/11/2012	3		\$0.00	
Medium	Work In Progress			2/5/2012 12:18:20 AM						
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
82281					1/1/2012	1/22/2012	38		\$0.00	
Medium	Work In Progress			1/1/2012 12:44:29 AM						
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
81325		Cafeteria			11/22/2011		78		\$0.00	
Medium	Work In Progress			11/22/2011 12:03:47						
Orozco, Danny	need to have hood suppression system serviced and repaired as per last inspection									
<u>Danny Orozco</u>										
<b>Count: 30 Work Orders</b>		<b>Avg. Age of WO's 49</b>		<b>Total for Loma Linda ES</b>			<b>0</b>	<b>\$0.00</b>		

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
81326		Cafeteria			11/22/2011		78		\$0.00
Medium	Work In Progress				11/22/2011 12:05:08				
Orozco, Danny	need to have hood suppression system serviced and repaired as per last inspection								
<u>Danny Orozco</u>									
83681					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:11 AM				
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82557		Cafeteria			1/9/2012		30		\$0.00
High	Work In Progress				1/9/2012 11:14:35 AM				
Munoz, Michael	type k extinguisher is leaking. please replace.								
<u>Michael Munoz</u>									
81425					11/29/2011		71		\$0.00
Medium	Work In Progress				11/29/2011 7:39:32 AM				
Gonzalez, Salvador	need security bars installed in rms. 505,506. 2nd request								
<u>Joe Ramirez</u>									
83414					1/31/2012		8		\$0.00
Medium	Work In Progress				1/31/2012 12:18:15 AM				
Apodaca, Mario	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77100					8/18/2011		174		\$0.00
Medium	Work In Progress				8/18/2011 9:22:00 AM				
Gonzalez, Salvador	8/18/11 I need welder to fabricate an aluminum cover for the sewage pumps at Mesquite Elementary wwtp ASAP,thanks Raul								
<u>Raul Sanchez</u>									
83375					1/30/2012		9		\$0.00
Medium	Work In Progress				1/30/2012 1:33:50 PM				
Lozoya, Manny	rm.203 door handle needs to be repaired or replaced.								
<u>Joe Ramirez</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
77716					9/1/2011		160		\$0.00
Medium	Work In Progress			9/1/2011 2:11:09 PM					
Moncayo, Fernando	NO HOT WATER IN HAND SINKS IN KITCHEN CITED BY HEALTH DEPT., THEY WILL NEED PROOF THAT ISSUE HAS BEEN RESOLVED. SNP MANAGER ALICE F. 233-2341								
<u>Maritza Gonzalez</u>									
76232					8/2/2011		190		\$0.00
Medium	Work In Progress			8/2/2011 12:17:00 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75104					7/5/2011		218		\$0.00
Medium	Work In Progress			7/5/2011 12:16:34 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83689					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:15 AM					
Apodaca, Mario	Monthly - Mesquite ES - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
80806	Main Building				11/8/2011		92		\$0.00
Medium	Work In Progress			11/8/2011 7:58:39 AM					
Ramirez, Joe	Original Bldg. - Exterior wall on westside has two areas that were painted to cover graffiti. Tha paint does not match. Order matching paint and repaint with even edges								
<u>Alfredo Holguin</u>									
83740	Main Building				2/6/2012		2		\$0.00
Medium	Work In Progress	Main Office		2/6/2012 3:19:07 PM					
Ambriz, Juan	Dora Lerma/Data Entry needs (2) boxes picked up and delivered to warehouse (Tracey Swinford approval) thank you.								
<u>Sandra Mora</u>									
82611					1/10/2012		29		\$0.00
Medium	Work In Progress			1/10/2012 8:42:23 AM					
Ramirez, Joe	need to paint 2 walls in rm.204								
Joe Ramirez									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Mesquite ES</b>									
79890					10/18/2011		113		\$0.00
High	Work In Progress			10/18/2011 8:52:04 AM					
Ramirez, Joe	nned to hook up to the existing irrigation system on the playing fields to irragate when ebid does not provide water.								
<u>Michael Munoz</u>									
83680					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:11 AM					
Ramirez, Joe	Monthly - Mesquite ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83683					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:12 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83684					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:13 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83012					1/12/2012		27		\$0.00
Medium	Work In Progress			1/20/2012 11:50:02 AM					
Ronquillo, Ruben	Stolen cordless dewalt drill and hammer. (Case# 2012-445 Holguin 1113)								
<u>Joe Ramirez</u>									
81238		Custodial			11/18/2011		82		\$0.00
Medium	Work In Progress			11/18/2011 10:30:42					
Lozoya, Manny	PLEASE THE CYLINDER IS BROKEN FROM CUSTODIAN STORGE THE DOOR DO NOT OPEN I NEED TO GET IN THANK YOU								
<u>Luis Saucedo</u>									
80160					10/25/2011		106		\$0.00
High	Work In Progress			10/25/2011 7:33:13 AM					
Sotelo, Enrique	please remove dangling wires(parqagon cable) that are laying on the ground. this could become a safety issue. thank you								
<u>Michael Munoz</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
80080		Parking Lot			10/21/2011		110	1	\$25.00
Medium	Work In Progress			10/21/2011 3:21:52 PM					
Ramirez, Joe	Parking Lot - Need to paint all fire lanes, parking lines and hadicap areas.		Asp report 1/19/12 fire lane complete						
Michael Munoz									
81856					12/7/2011		63		\$0.00
Medium	Work In Progress			12/7/2011 2:24:18 PM					
Ramirez, Joe	need to paint 2 walls in rm.301								
Joe Ramirez									
82268					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:24 AM					
Villalobos, David	Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
83682					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:12 AM					
Ramirez, Joe	Monthly - Mesquite ES - Barrack Drainage (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
83493					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 2:23:29 PM					
Ontiveros, Joe	boys bathroom by the south lounge continues to clog up need to remove toilet and auger the drain								
Joe Ramirez									
83494					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 2:25:45 PM					
Ontiveros, Joe	need to replace zurn mop sink fixture custodial closet by the south lounge								
Joe Ramirez									
81369					11/28/2011		72		\$0.00
Medium	Work In Progress			11/28/2011 7:11:09 AM					
Sotelo, Enrique	i need the electricians help with 3 light fixtures so that i can close out my ceiling tile installation w.o.								
Joe Ramirez									
78369					9/15/2011		146		\$0.00
Medium	Work In Progress			9/15/2011 7:12:39 AM					
Sotelo, Enrique	i have 3 parking lot lights that are out need new bulbs 1 will need a ballast								
Joe Ramirez									
<b>Count: 29 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>64</b>	<b>Total for Mesquite ES</b>			<b>1</b>	<b>\$25.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>North Valley ES</b>							
82821					1/17/2012		22		\$0.00
Medium	Work In Progress			1/17/2012 9:27:31 AM					
Sotelo, Enrique	ladies rr by lounge /emergency lamp is out/have replaced lamps will not lite								
Danny Vega									
82109					12/14/2011		56		\$0.00
Medium	Work In Progress			12/14/2011 3:28:31 PM					
Sotelo, Enrique	pecan valley wing -have 3 emergency lamp ballast burnt								
Danny Vega									
82110					12/14/2011		56		\$0.00
Medium	Work In Progress			12/14/2011 3:29:28 PM					
Sotelo, Enrique	rio grande wing have two emergency lamp ballast out								
Danny Vega									
83489					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 12:04:37 PM					
Ontiveros, Joe	sink in teacher's bathroom is clogged								
Javier Parra									
83238					1/26/2012		13		\$0.00
Medium	Work In Progress			1/26/2012 12:08:18 PM					
Ontiveros, Joe	urinal clogged up in bys rr east exit doors by buses and pecan valley wing bys rr.								
Danny Vega									
82254					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:18 AM					
Villalobos, David	Yearly - North Valley ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
76189					8/1/2011		191		\$0.00
Medium	Work In Progress			8/1/2011 1:13:59 PM					
Lozoya, Manny	need to repair door handle plus core in heat pumps mechanical rm organ trail(exterior)and give a key to joe trane rep								
Danny Vega									
83496					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 2:38:30 PM					
Solis, Lorenzo	rm 303 heating unit is making loud noises/teacher says she has to talk over noise-i have checked it out/cant trace source/it is loud.plz ck asap.seems its louder on cooling cycle								
Danny Vega									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>North Valley ES</b>							
83820					2/8/2012		0		\$0.00
Medium	Work In Progress				2/8/2012 8:09:49 AM				
Ontiveros, Guadalupe		need campus grass field fertilized (apprx 35 bags 16-8-8)							
Danny Vega									
82224					1/1/2012		38		\$0.00
Medium	Work In Progress				1/1/2012 12:44:03 AM				
Holguin, Alfredo		Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									
83338					1/27/2012		12		\$0.00
Medium	Work In Progress				1/27/2012 3:45:15 PM				
Vega, Danny		need belts to replaced on erv units b-72 & b74							
Danny Vega									
83636					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:17:54 AM				
Vega, Danny		Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
83637					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:17:54 AM				
Vega, Danny		Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
81274					11/21/2011		79		\$0.00
High	Work In Progress				11/21/2011 8:00:11 AM				
Vega, Danny		fire lanes and handi -cap areas need to be re-painted. thank you							
Michael Munoz									
83282					1/27/2012		12		\$0.00
Medium	Work In Progress				1/27/2012 1:29:10 PM				
Orozco, Danny		NEED NEW EXTENSION CORD FOR CASH REGISTER. SNP MANAGER LAURA B. 233-3658							
Maritza Gonzalez									
83488					2/1/2012		7		\$0.00
Medium	Work In Progress				2/1/2012 12:02:14 PM				
Carbajal, Jimmy		vacum handle does not stay in place and vacum wont turn on.							
Javier Parra									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>North Valley ES</b>							
83159					1/25/2012		14		\$0.00
Medium	Work In Progress				1/25/2012 8:34:19 AM				
Flores, Pete	need to use bob-cat /have two loads crusher fines need to spread and level off		Asp Lupe, reroute to Pete						
Danny Vega									
82542					1/9/2012		30		\$0.00
Medium	Work In Progress				1/9/2012 9:16:56 AM				
Flores, Pete	need kabota tractor to clean out and repair erosion on run-off ponds west and east plus level off north side by entrance gates								
Danny Vega									
83640					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:17:55 AM				
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 19 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>31</b>	<b>Total for North Valley ES</b>			<b>0</b>	<b>\$0.00</b>



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
83641					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:56 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83413					1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 12:18:15 AM					
Apodaca, Mario	Monthly - Northern Pre-K- Domestic Water Filters - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83688					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:14 AM					
Apodaca, Mario	Monthly - Northern Pre-K - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82959					1/19/2012		20		\$0.00
Medium	Work In Progress			1/19/2012 2:22:55 PM					
Carbajal, Jimmy	NEED BURNISHER FIXED. (WILL NOT TURN ON) GISD #00-00061.								
<u>Adam Montoya</u>									
75818					7/26/2011		197		\$0.00
Medium	Work In Progress			7/26/2011 9:59:35 AM					
Estrada, Jesus	ROOM #108 - UNEVEN TILES ARE A TRIP HAZARD. PLEASE MAKE RECOMMENDATION.					1/30/12 - NEEDS TO BE TAKEN CARE OF ON A WEEKEND/BREAK			
<u>Jesus Estrada</u>									
78806	Main Building				9/26/2011		135		\$0.00
Medium	Work In Progress			9/26/2011 4:06:11 PM					
Ontiveros, Joe	NEED WATER HEATER CHECKED IN CUSTODIAL CLOSET (KEEPS TRIPPING GFCI).								
<u>Adam Montoya</u>									
81428	Main Building				11/29/2011		71		\$0.00
Medium	Work In Progress			11/29/2011 8:04:05 AM					
Lozoya, Manny	NEED LOCKS CHECKED IN ROOM 110 CLOSETS. (DAYCARE AREA)								
<u>Adam Montoya</u>									
81931	Main Building				12/9/2011		61		\$0.00
Medium	Work In Progress			12/9/2011 8:33:05 AM					
Ronquillo, Ruben	NEED EXIT SIGNS (4) FOR DAYCARE CLASSROOMS. 12 X 9 6IN LETTERS.								
<u>Adam Montoya</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
83602	Main Building	Classroom			2/3/2012		5		\$0.00
Medium	Work In Progress	Room 18			2/3/2012 4:10:37 PM				
Vega, Danny	Remove panels from room 18 to old cafeteria. Bring from old cafeteria, Chaparral Pre-k furniture to room 18.								
<u>Concepcion Montalvo</u>									
83638					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:17:55 AM				
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83639					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:17:55 AM				
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83822					2/8/2012		0		\$0.00
Medium	Work In Progress				2/8/2012 8:11:48 AM				
Ontiveros, Guadalupe	need grass field fertilized (approx. 25 bags 16-8-8)								
<u>Danny Vega</u>									
83571					2/3/2012		5		\$0.00
Medium	Work In Progress				2/3/2012 11:09:18 AM				
Estrada, Jesus	ATTENTION CHUY ESTRADA as per mike m. alma del valle daycare tile repair in rm 114/tile is lifting in section done by contractors.please see mrs laura ybarra								
<u>Danny Vega</u>									
82820					1/17/2012		22		\$0.00
Medium	Work In Progress				1/17/2012 9:25:59 AM				
Lozoya, Manny	rms 114 and 108 /key will not turn cylinder/custodian cant open these door in the morning								
<u>Danny Vega</u>									
83835					2/8/2012		0		\$0.00
Medium	Work In Progress				2/8/2012 10:49:23 AM				
Solis, Lorenzo	Please check boiler its leaking.								
<u>Danny Vega</u>									
82266					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress				1/1/2012 12:44:23 AM				
Villalobos, David	Yearly - Northern Pre-K Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
82819					1/17/2012		22		\$0.00
Medium	Work In Progress				1/17/2012 9:23:58 AM				
Sotelo, Enrique	exterior security lights are out /breaker is ok /please ck custodians say it dark when they open at 5am								
Danny Vega									
<b>Count: 17 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>35</b>	<b>Total for Northern On-Track Pre-K (LM)</b>			<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Physical Plant Complex</b>								
82269					1/1/2012	2/1/2012	38		\$0.00	
Medium	Work In Progress			1/1/2012 12:44:24 AM						
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
79038		Parking Lot			9/30/2011		131		\$0.00	
Medium	Work In Progress			9/30/2011 12:31:17 PM						
Villalobos, David		ASP Mike remove upright connections to sewer, gas, and water								
David Villalobos										
83484					2/1/2012		7		\$0.00	
Medium	Work In Progress			2/1/2012 10:51:35 AM						
Ronquillo, Ruben		REPAIR INNER TOP LINER FOR TRUCK #32 THANK YOU!								
Ruben Ronquillo										
83106		Athletic Field			1/24/2012		15		\$0.00	
High	Work In Progress			1/24/2012 8:20:05 AM						
Ontiveros, Guadalupe		walk-behind trencher needs chain replaced.								
78847										
Medium	Work In Progress			9/27/2011 1:14:25 PM			134		\$0.00	
Ontiveros, Guadalupe		please order new 8' disc, 3 point hitch for district projects. thanks								
Michael Munoz										
78848					9/27/2011		134		\$0.00	
Medium	Work In Progress			9/27/2011 1:15:56 PM						
Ontiveros, Guadalupe		need new z-trac mower to cut new landscaping in the southern schools.thanks								
Michael Munoz										
83722					2/6/2012		2		\$0.00	
Medium	Work In Progress			2/6/2012 12:16:16 AM						
Villalobos, Margret		Monthly - PPD - Quarterly Meeting - Refer to PM schedule details.				Tenative for Thursday, 2/16/12				
Margret Villalobos										
83580					2/3/2012		5		\$0.00	
Medium	Work In Progress			2/3/2012 3:10:33 PM						
Apodaca, Mario		Need to order Water filter container parts for school site at Desert trails elementary, mesquite elementary, loma linda elementary, g m s								
Mario Apodaca										

2/8/2012 1:26:27 PM

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
83662					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:04 AM					
Carbajal, Jimmy	Monthly - Physical Plant - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
80886					11/9/2011		91		\$0.00
Medium	Work In Progress			11/9/2011 2:06:38 PM					
Miranda, Danny	please continue with the remodeling of the training room.thank you								
<u>Michael Munoz</u>									
83717					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:25 AM					
Diaz, Sebastian	Monthly - Physical Plant FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81560	Food Services				12/1/2011		69		\$0.00
Medium	Work In Progress			12/1/2011 8:35:22 AM					
Moncayo, Fernando	LIGHT IS FLICKERING IN JOHNNY LECHUGA OFFICE.								
<u>Maritza Gonzalez</u>									
83277	Food Services				1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 11:09:37 AM					
Orozco, Danny	Water leak in bathroom wall, left puddle on floor								
<u>Maritza Gonzalez</u>									
81109	Motor Vehicle				11/16/2011		84		\$0.00
Medium	Work In Progress			11/16/2011 11:31:34					
Lozoya, Manny	Need 5 gate J3(label them 21 thru 25) keys to issue with vehicle keys								
<u>Maria Ruiz</u>									
82009	Motor Vehicle				12/12/2011		58		\$0.00
Medium	Work In Progress	vehicle#52		12/12/2011 1:17:01 PM					
Flores, Pete	compressor to a/c is damaged & is requiring replacement								
<u>Pete Flores</u>									
83525	Motor Vehicle				2/2/2012		6		\$0.00
Medium	Work In Progress	vehicle#54		2/2/2012 8:35:00 AM					
Flores, Pete	vehicle running rough & stalling. check & advise								
<u>Pete Flores</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
81561	Motor Vehicle				12/1/2011		69		\$0.00
Medium	Work In Progress	vehicle#122		12/1/2011 8:43:36 AM					
Flores, Pete	engine idle fluctuating erratically-check & advise								
<u>Pete Flores</u>									
81562	Motor Vehicle				12/1/2011		69		\$0.00
Medium	Work In Progress	band truck#127		12/1/2011 8:47:19 AM					
Flores, Pete	scheduled for routine maintenance								
<u>Pete Flores</u>									
81169	Motor Vehicle				11/17/2011		83		\$0.00
Medium	Work In Progress	fleet vehicles		11/17/2011 8:19:04 AM					
Flores, Pete	check on chipped windshields & advise on which are repairable and what the cost will be.								
<u>Pete Flores</u>									
79372	Motor Vehicle				10/4/2011		127		\$0.00
Medium	Work In Progress			10/4/2011 2:33:58 PM					
Flores, Pete	truck needs oil change.								
<u>Lorenzo Solis</u>									
79481	Motor Vehicle				10/7/2011		124		\$0.00
Medium	Work In Progress	vehicle#110		10/7/2011 10:30:00 AM					
Flores, Pete	van leaking coolant & is requiring routine service.								
<u>Pete Flores</u>									
79768	Motor Vehicle				10/14/2011		117		\$0.00
Medium	Work In Progress			10/14/2011 10:21:06					
Flores, Pete	bucket truck is leaking hydraulic oil. please repair. if truck needs to be taken to private contractor for other services, please do so.thank you								
<u>Michael Munoz</u>									
78650	Motor Vehicle	Parking Lot			9/22/2011		139		\$0.00
Medium	Work In Progress			9/22/2011 7:56:36 AM					
Ontiveros, Guadalupe	re layout complete parking lot to add additional row and install signage.								
<u>Alfredo Holguin</u>									
81852	Purchasing				12/7/2011		63		\$0.00
Medium	Work In Progress			12/7/2011 11:10:29 AM					
Lozoya, Manny	Custodial Warehouse - back door needs to have core checked to work properly and door between warehouse and hallway to PPD office needs to have core installed. Check wiht Alfredo Holguin.								
<u>Alfredo Holguin</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
80331	Maintenance	Restroom (Boys)			10/28/2011		103		\$0.00
Medium	Work In Progress				10/28/2011 11:35:35				
Appelzoller, Fred	Please install hot water heater in Mens Restroom.								
<u>Michael Munoz</u>									
80931	Maintenance				11/10/2011		90		\$0.00
Medium	Work In Progress				11/10/2011 11:20:48				
Appelzoller, Fred	Training Room - Need to hookup sink. (See Mike)								
<u>Michael Munoz</u>									
80917	Maintenance				11/9/2011		91		\$0.00
Medium	Work In Progress				11/9/2011 4:07:55 PM				
Sotelo, Enrique	Training Room - Need to upgrade electrical. (See Mike)								
<u>Michael Munoz</u>									
80916	Maintenance				11/9/2011		91		\$0.00
Medium	Work In Progress				11/9/2011 4:06:25 PM				
Solis, Lorenzo	Training Room - Need to install a new refrigeration unit. (See Mike)								
<u>Michael Munoz</u>									
83163	Maintenance				1/25/2012		14		\$0.00
Medium	Work In Progress				1/25/2012 11:16:17 AM				
Carrasco, Danny	Requesting canvas top and plexiglass windshield for polaris UV-GM-0516 for Maint. Whs.								
<u>Danny Carrasco</u>									
83146	Maintenance				1/24/2012		15		\$0.00
Medium	Work In Progress				1/24/2012 4:11:43 PM				
Gonzalez, Salvador	Weld ADA handicap grab bars to accomodate from wall to floor.								
<u>Danny Carrasco</u>									
80237					10/26/2011		105		\$0.00
Medium	Work In Progress				10/26/2011 2:59:17 PM				
Apodaca, Mario	need to order water filter for all school sites								
<u>Mario Apodaca</u>									
83156					1/25/2012		14		\$0.00
Medium	Work In Progress				1/25/2012 8:06:24 AM				
Gonzalez, Salvador	1-25-12 I need welding material and supplies for welding shop, from southwest welding supplies.								
<u>Salvador Gonzalez</u>									
<b>Count: 32 Work Orders</b>		<b>Avg. Age of WO's 66</b>		<b>Total for Physical Plant Complex</b>				<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
83420					1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 8:32:06 AM					
Briones, Enrique	On February 2, 2012, please pick-up 5-12 boxes of Science Adoption material from Riverside Elementary. Contact Person: Maria Hernandez								
<u>Yolie Jacquez</u>									
83485					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 11:19:40 AM					
Gonzalez, Salvador	need to replace cover plate on sidewalk to north entrance rotting out tripping hazzard 30x96								
<u>Carlos Hernandez</u>									
83626					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:50 AM					
Hernandez, Carlos	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77702					9/1/2011		160		\$0.00
Medium	Work In Progress			9/1/2011 11:10:02 AM					
Hernandez, Carlos	please purchase new D130 john deere lawn mower to replace existing one.								
<u>Michael Munoz</u>									
83390					1/30/2012		9		\$0.00
Medium	Work In Progress			1/30/2012 3:20:06 PM					
Orozco, Danny	TEMPERATURE NEEDS TO BE CHECKED IN SERVING LINE. AS PER HEALTH DEPT. IT IS ABOVE 40 DEGREES.								
<u>Maritza Gonzalez</u>									
83422					1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 9:17:16 AM					
Orozco, Danny	OVEN DOWN. SNP MANAGER EMILIA C. 589.2550								
<u>Maritza Gonzalez</u>									
83423					1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 9:18:50 AM					
Orozco, Danny	ONE OF THE OUTLETS WHERE MILK COOLER CONNECTS IS OUT. SNP MANAGER EMILIA C. 589.2550								
<u>Maritza Gonzalez</u>									
80282					10/27/2011		104		\$0.00
Medium	Work In Progress			10/27/2011 9:27:09 AM					
Orozco, Danny	DISHWASHER IS NOT WORKING, RUSTED INSIDE. SNP MANAGER EMILIA C. 589.2550								
<u>Maritza Gonzalez</u>									
2/8/2012 1:26:27 PM									



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Riverside ES</b>									
80231					10/26/2011		105		\$0.00
Medium	Work In Progress			10/26/2011 11:28:21					
Orozco, Danny	SCREEN DOOR NEEDS TO BE FIXED. SNP MANAGER EMILIA C. 589.2550								
Maritza Gonzalez									
79323					10/3/2011		128		\$0.00
Medium	Work In Progress			10/3/2011 10:42:10 AM					
Orozco, Danny	HAND SINK LEAKING. SNP MANAGER EMILIA C. 589.2550								
Maritza Gonzalez									
78125					9/9/2011		152		\$0.00
Medium	Work In Progress			9/9/2011 2:44:31 PM					
Munoz, Michael	need to construct concret pad for trash dumpsters								
Alfredo Holguin									
82861					1/17/2012		22		\$0.00
Medium	Work In Progress			1/17/2012 3:22:25 PM					
Gonzalez, Salvador	missing gate to north drop off area sidewalk gate case #2012-00087								
Carlos Hernandez									
81483					11/29/2011		71		\$0.00
Medium	Work In Progress			11/29/2011 3:45:51 PM					
Munoz, Michael	need to replace concrete sidewalk outside back door to main office sidewalk coming up								
Carlos Hernandez									
83394					1/30/2012		9		\$0.00
Medium	Work In Progress			1/30/2012 3:28:46 PM					
Carrasco, Danny	need 10gal gas for truck and 5 for tractor								
Carlos Hernandez									
83627					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:50 AM					
Hernandez, Carlos	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
80505					11/3/2011		97		\$0.00
Medium	Work In Progress			11/3/2011 9:55:26 AM					
Hernandez, Carlos	need these tools weed eater 1" scraper tree pruners hoe 5 gallon compressor 50ft air hose tool pouch knee pads fin comb bits 5/16 and 1/4 and phillips								
Carlos Hernandez									
83625					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:50 AM					
Hernandez, Carlos	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
81849					12/7/2011		63		\$0.00
Medium	Work In Progress			12/7/2011 10:38:55 AM					
Ontiveros, Guadalupe	need to move pile of sand and rocks next to kinder portable								
Carlos Hernandez									
77117					8/18/2011		174		\$0.00
Medium	Work In Progress			8/18/2011 3:43:03 PM					
Lara, Ralph	need pad locks for small get and water control box and one for trash cans								
Carlos Hernandez									
81953					12/9/2011		61		\$0.00
Medium	Work In Progress			12/9/2011 3:37:49 PM					
Flores, Pete	truck #21 not running right making noise								
Carlos Hernandez									
82270					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:24 AM					
Villalobos, David	Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
80843					11/8/2011		92		\$0.00
Medium	Work In Progress			11/8/2011 3:28:34 PM					
Castillo, Carlos	need to line locate high voltage line in back to bus turn around caution tape is uncovered								
Carlos Hernandez									

2/8/2012 1:26:28 PM

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Riverside ES</b>									
83741					2/6/2012		2		\$0.00
Medium	Work In Progress				2/6/2012 3:22:27 PM				
Castillo, Carlos	electrical outlets in hallway in middle wing trip out								
Carlos Hernandez									
77677					8/31/2011		161		\$0.00
Medium	Work In Progress				8/31/2011 3:57:52 PM				
Ambriz, Jose	need elbow "5 gooseneck and 16x16 register for a/c storage								
Carlos Hernandez									
80335		Custodial			10/28/2011		103		\$0.00
Medium	Work In Progress				10/28/2011 2:24:40 PM				
Lara, Ralph	rafa. necesito 1 candado con 3 llaves para el morga. gracias r.r.								
Raul Romero									
80474					11/2/2011		98		\$0.00
Medium	Work In Progress				11/2/2011 3:27:19 PM				
Ambriz, Jose	need to remove old a/c unit and cover vent art portable								
Carlos Hernandez									
82731					1/12/2012		27		\$0.00
Medium	Work In Progress				1/12/2012 3:21:54 PM				
Ambriz, Jose	fan won't turn on to heater in room 104 needs new fan limit control module								
Carlos Hernandez									
<b>Count: 27 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>64</b>		<b>Total for Riverside ES</b>	<b>0</b>		<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: RTC - Alliance</b>									
79345					10/3/2011		128		\$0.00
Medium	Work In Progress				10/3/2011 4:29:40 PM				
Castillo, Carlos	AS PER GLORIA, WOULD LIKE TO SEE IF THEY CAN HAVE ELECTRICAL OUTLETS INSTALLED IN CLASSROOM. THERE ARE 15 NEW COMPUTERS THAT ARE BEING SET UP.								
<u>Maritza Gonzalez</u>									
83151					1/25/2012		14		\$0.00
Medium	Work In Progress				1/25/2012 7:30:22 AM				
Lara, Ralph	Mrs. Goodman classroom (Please see Gloria Delgado) door lock loose								
<u>Maritza Gonzalez</u>									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's 71</b>			<b>Total for RTC - Alliance</b>			<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
82275					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:26 AM					
Villalobos, David	Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81372					11/28/2011		72		\$0.00
High	Work In Progress			11/28/2011 7:58:20 AM					
Ambriz, Jose	please install temp gauge on lockinvar boiler as per boiler inspectors inspection.thank you								
<u>Michael Munoz</u>									
81373					11/28/2011		72		\$0.00
High	Work In Progress			11/28/2011 8:03:11 AM					
Ambriz, Jose	please install temp gauge on boiler as per boiler inspectors inspection, boiler sn # c03h00152877								
<u>Michael Munoz</u>									
77855					9/4/2011		157		\$0.00
Medium	Work In Progress			9/4/2011 12:24:21 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82653		Classroom			1/10/2012		29		\$0.00
Medium	Work In Progress	ROO 101		1/10/2012 4:31:27 PM					
Castillo, Carlos	NEED POWER SUPPLY NEEDS TO BE PROVIDED FOR SMART SCREEN PROJECTOR. THANKS.								
<u>Rita Mendez</u>									
83293					1/27/2012		12		\$0.00
Medium	Work In Progress			1/27/2012 2:33:25 PM					
Castillo, Carlos	WALL OUTLETS IN WK. RM. CASA AZUL ARE NOT WORKING. I CHECKED BREAKERS , LOOKED OK. NEED TO BE CHECKED OUT THANKS.								
<u>Gerardo Marquez</u>									
76757					8/10/2011		182		\$0.00
Medium	Work In Progress			8/10/2011 8:58:12 AM					
Castillo, Carlos	HAND DRYER @ BOYS RRM. IN CASA BLANCA NEEDS REPLACING. NOT WORKING. THANKS.								
<u>Gerardo Marquez</u>									
83377					1/30/2012		9		\$0.00
Medium	Work In Progress			1/30/2012 1:49:33 PM					
Flores, Pete	PETE, COULD YOU BRING BOBCAT TO MOVE DIRT. THANKS.								
<u>Gerardo Marquez</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
82303					1/1/2012	1/9/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:39 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82305					1/1/2012		38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:41 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83651					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:00 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83653					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:01 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83654					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:01 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82301					1/1/2012	1/9/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:38 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82651					1/10/2012		29		\$0.00
Medium	Work In Progress	ROOM 308		1/10/2012 4:07:48 PM					
Marquez, Gerardo	PLEASE CONSTRUCT AND SET UP EASEL FOR MS. NUNEZ. THANKS.								
<u>Rita Mendez</u>									
83455					1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 3:44:41 PM					
Nunez, Arturo	NEED TO CLEAN UP OR PAINT REAR WALL AT FOOTBALL CONSESSION STAND. CASE # 2012-01193 D.A.SO. BADGE # 880								
<u>Arturo Nunez</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
77359					8/24/2011		168		\$0.00
Medium	Work In Progress			8/24/2011 3:33:48 PM					
Marquez, Gerardo	NEED TO CHECK OUT HVAC IN RM. 307. NOT COOLING & MOTOR MAKING A LOUD NOISE. THANKS.								
<u>Gerardo Marquez</u>									
82302					1/1/2012	1/9/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:39 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82304					1/1/2012	1/7/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:40 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83652					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:00 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82842					1/17/2012		22		\$0.00
Medium	Work In Progress			1/17/2012 2:21:30 PM					
Orozco, Danny	replace push cart wheels								
<u>Maritza Gonzalez</u>									
82017					12/12/2011		58		\$0.00
Medium	Work In Progress			12/12/2011 2:45:16 PM					
Orozco, Danny	MILK COOLER IS NOT COOLING. SNP MANAGER PAT S. 589.3439								
<u>Maritza Gonzalez</u>									
80247	Main Building	Classroom			10/26/2011		105		\$0.00
Medium	Work In Progress			10/26/2011 3:38:41 PM					
Lara, Ralph	I need to request key # 1S38. Thank You.								
<u>Rosie Diaz</u>									
82131	Main Building	Classroom			12/14/2011		56		\$0.00
Medium	Work In Progress	conference room		12/14/2011 4:14:08 PM					
Castillo, Carlos	POWER SUPPLY NEEDS TO BE PROVIDED FOR SMART SCREEN PROJECTOR. THANKS.								
<u>Rita Mendez</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
82132	Main Building	Classroom			12/14/2011		56		\$0.00
Medium	Work In Progress	ROOM 201			12/14/2011 4:15:28 PM				
Castillo, Carlos	MR. CASTANEDAS ROOM. POWER SUPPLY NEEDS TO BE PROVIDED FOR SMART SCREEN PROJECTORS. THANKS.								
Rita Mendez									
82763	Main Building	Hallway/Corridor			1/13/2012		26		\$0.00
Medium	Work In Progress	MRS. URREA			1/13/2012 9:34:04 AM				
Marquez, Gerardo	PLEASE SET UP BULLETING BOARD IN HALLWAY. PLEASE SEE MRS. URREA ON AREA WHERE IT NEEDS TO BE HUNG. THANKS.								
Rita Mendez									
81328	Main Building	Classroom			11/22/2011		78		\$0.00
Medium	Work In Progress	NUNEZ ROOM			11/22/2011 12:15:05				
Marquez, Gerardo	EASEL NEEDS TO BE PUT TOGETHER FOR MRS. NUNEZ, ROOM 308. THANKS.								
Rita Mendez									
80770	Main Building	Classroom			11/7/2011		93		\$0.00
Medium	Work In Progress	Conference/Tea			11/7/2011 2:00:36 PM				
Marquez, Gerardo	WE NEED DOOR STOPPERS INSTALLED ON THE CONFERENCE AND TEACHER'S LOUNGE DOORS. THANKS.								
Rita Mendez									
80530	Main Building	Classroom			11/3/2011		97		\$0.00
Medium	Work In Progress	all classrooms			11/3/2011 3:49:31 PM				
Marquez, Gerardo	ALL OLD PAPERTOWEL DISPENSERS NEED TO BE REMOVED. 38 NEW PAPERTOWEL DISPENSERS NEED TO BE INSTALLED. THANKS.								
Rita Mendez									
80773	Main Building	Library			11/7/2011		93		\$0.00
Medium	Work In Progress	LIBRARY			11/7/2011 2:20:37 PM				
Marquez, Gerardo	SHELVING NEEDS TO BE CONSTRUCTED. DONNY GONZALEZ WITH RECREATION CREATIONS WILL BE ASSISTING GERRY WITH THE SET UP. THANKS.								
Rita Mendez									
82953	Main Building	Cafeteria			1/19/2012		20		\$0.00
Medium	Work In Progress	cafeteria			1/19/2012 12:04:50 PM				
Marquez, Gerardo	PLEASE ASSEMBLE 4 FOOD CARTS FOR CAFETERIA. THANKS.								
Rita Mendez									



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: Santa Teresa ES</b>									
82654	Main Building	Portables			1/10/2012		29		\$0.00
Medium	Work In Progress	ART			1/10/2012 5:25:15 PM				
Marquez, Gerardo		PLEASE INSTALL BACK SPLASH TO SINK IN ART PORTABLE. THANKS.							
Rita Mendez									
<b>Count: 32 Work Orders</b>		<b>Avg. Age of WO's 53</b>			<b>Total for Santa Teresa ES</b>			<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
82905	Main Building	Stairway			1/18/2012		21		\$0.00
Medium	Work In Progress			1/18/2012 1:55:13 PM					
Villalobos, David		Need to replace tempature relief valve to hot water heater at culinary building							
David Villalobos									
82990	Main Building	Classroom			1/20/2012		19		\$0.00
Medium	Work In Progress			1/20/2012 7:45:04 AM					
Castillo, Carlos		IN ROOM 404 LIHT SWITSH IS BROCK WE NEED TO CHANGED.							
Manuel Prospero									
78512	Main Building	Hallway/Corridor			9/19/2011		142		\$0.00
Medium	Work In Progress			9/19/2011 3:37:15 PM					
Prospero, Manuel		ON 9/16/11 JUAN TELLEZ THE HEAD SECURITY CALL ME AT 6:30 PM FOR WATER LEA ON SCIENCE HALLWAY ON ROOF.							
Manuel Prospero									
78471	Main Building	Classroom			9/16/2011		145		\$0.00
Medium	Work In Progress			9/16/2011 11:15:48 PM					
Prospero, Manuel		Gloria Goodman needs round table and computer desk repaired. Also check A/C that is not working.							
William Dickson									
77008	Main Building	Classroom			8/16/2011		176		\$0.00
Medium	Work In Progress			8/16/2011 2:28:54 PM					
Nunez, Arturo		Room 511 cabinet handles need to be replaced, teacher has handles needs screws Lab table doors stick and graffitti needs to be removed							
Rosalinda Rodriguez									
76874	Main Building	Classroom			8/12/2011		180		\$0.00
Medium	Work In Progress			8/12/2011 9:52:08 AM					
Lara, Ralph		Door in counseling center is off balance and very difficult to open and close							
Rosalinda Rodriguez									
78491	Gymnasium	Dressing Room			9/19/2011		142		\$0.00
Medium	Work In Progress			9/19/2011 9:28:15 AM					
Estrada, Jesus		Replace the carpet in football locker room with anti slip tile.				1/30/12 - P.O. RECEIVED/FAXED TO RODRIGUEZ, NEEDS TO BE TAKEN CARE OF DURING SUMMER BREAK			
Jesus Estrada									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
79039	Gymnasium	Dressing Room			9/30/2011		131		\$0.00
Medium	Work In Progress			9/30/2011 1:14:44 PM					
Prospero, Manuel		Need to replace Delaney flushvalves throughout dressing rooms, asp per David, Zurn or Sloan flushvalves should be installed							
<u>Manuel Prospero</u>									
80126	Vocational				10/24/2011		107		\$0.00
Medium	Work In Progress			10/24/2011 12:52:20					
Prospero, Manuel		Pickup all furniture from Voc Bldg and bring to PPD. (Art and Danny C. will assist)							
<u>Richard Chavez</u>									
81478	Vocational				11/29/2011		71		\$0.00
Medium	Work In Progress			11/29/2011 3:37:51 PM					
Prospero, Manuel		11/29/11. WE NEED 5 24V.HEATER ONLY FOR CHAGED ON BOCATIONAL BUILDING.							
<u>Manuel Prospero</u>									
83107	Vocational				1/24/2012		15		\$0.00
Medium	Work In Progress			1/24/2012 8:22:01 AM					
Villalobos, David		Re-hook gas to rooftop heating units at vocational building							
<u>David Villalobos</u>									
76877	Vocational	Classroom			8/12/2011		180		\$0.00
Medium	Work In Progress			8/12/2011 10:07:05 AM					
Nunez, Arturo		Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805							
<u>Rosalinda Rodriguez</u>									
82906	Cafeteria (2005)	Restroom (Girls)			1/18/2012		21		\$0.00
Medium	Work In Progress			1/18/2012 1:57:51 PM					
Villalobos, David		Not enough hot water temperature to low							
<u>David Villalobos</u>									
82140	Cafeteria (2005)	Cafeteria			12/15/2011		55		\$0.00
Medium	Work In Progress			12/15/2011 12:46:00					
Prospero, Manuel		12/15/11. WE NEED TO CHANGED A LOT LIHTS BULBS ON CAFETERIA.							
<u>Manuel Prospero</u>									
77090	GYM (2009)	Dressing Room			8/17/2011		175		\$0.00
Medium	Work In Progress			8/17/2011 4:11:16 PM					
Lara, Ralph		broken lockers need latches installed, coach will purchase latches							
<u>Rosalinda Rodriguez</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
75589					7/20/2011		203		\$0.00
Medium	Work In Progress			7/20/2011 3:07:28 PM					
Orozco, Danny	the Molino is broken and one of the ovens is not heating. SNP Manager Olga B. 589.5332								
<u>Maritza Gonzalez</u>									
82724					1/12/2012		27		\$0.00
Medium	Work In Progress			1/12/2012 12:33:30 PM					
Gonzalez, Salvador	BACK FENCE COMING IN FROM THE ARROYO NEEDS TO BE REINFORCED, FOR SECURITY PURPOSES.								
<u>Manuel Prospero</u>									
77206					8/22/2011		170		\$0.00
Medium	Work In Progress	MARYLOU		8/22/2011 10:15:41 AM					
Ronquillo, Ruben	CAN STHS BORROW A FORK LIFT TO TRANSPORT A PRINTER FROM FRONT OFFICE STORAGE TO DRAFTING CLASSROOM OUT IN THE VOCATIONAL BLDG.								
<u>Marylou Jimenez</u>									
83776					2/7/2012		1		\$0.00
Medium	Work In Progress			2/7/2012 11:09:29 AM					
Carbajal, Jimmy	need to replace 5 vaccum cleaner belts.								
<u>Jorge Perez</u>									
83623					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:49 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81669					12/4/2011	12/10/2011	66		\$0.00
Medium	Work In Progress			12/4/2011 12:16:27 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
79271					10/2/2011	10/8/2011	129		\$0.00
Medium	Work In Progress			10/2/2011 12:28:15 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
80619					11/6/2011	11/12/2011	94		\$0.00
Medium	Work In Progress			11/6/2011 12:21:38 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
2/8/2012 1:26:28 PM									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
77820					9/4/2011	9/10/2011	157		\$0.00
Medium	Work In Progress			9/4/2011 12:24:06 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
74926					7/4/2011	7/9/2011	219		\$0.00
Medium	Work In Progress			7/4/2011 12:21:35 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76057					7/31/2011	8/6/2011	192		\$0.00
Medium	Work In Progress			7/31/2011 9:24:46 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83805					2/7/2012		1		\$0.00
Medium	Work In Progress			2/7/2012 3:55:30 PM					
Gonzalez, Salvador	HAND RAILS FOR FOOTBALL EXIT STAIRS NEED TO BE SECURED, THEY ARE PRETTY LOOSE, AND DANGEROUS.								
<u>Arturo Nunez</u>									
78155		Football Field			9/9/2011		152		\$0.00
Medium	Work In Progress			9/9/2011 3:56:27 PM					
Holguin, Alfredo	Running Track- needs the rubberized surface repaired at various places and lines repainted.								
<u>Guadalupe Ontiveros</u>									
83062					1/23/2012		16		\$0.00
Medium	Work In Progress			1/23/2012 10:59:12 AM					
Nunez, Arturo	NEED 8 (EIGHT) EA. 4.10/3.50-4 WHEELS TO REPLACED THE EXISTING , THE ONES ON ARE ALL SHOT, COACHES CAN'T MOVE AROUND. AS PER MR. DIXON. THANK YOU.								
<u>Arturo Nunez</u>									
74924					7/4/2011	8/3/2011	219		\$0.00
Medium	Work In Progress			7/4/2011 12:21:34 AM					
Nunez, Arturo	Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
74925					7/4/2011	8/3/2011	219		\$0.00
Medium	Work In Progress			7/4/2011 12:21:35 AM					
Nunez, Arturo	Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82282					1/1/2012	1/22/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:29 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78364					9/14/2011		147		\$0.00
Medium	Work In Progress			9/14/2011 6:16:41 PM					
Marquez, Gerardo	Bench inside the showers in gym need to be replaced both boy and girls they've been ripped of the wall								
<u>Jorge Perez</u>									
83486					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 11:33:00 AM					
Villalobos, David	Two urinals located in the cafeteria lobby are constantly clogging, We have tried plugers, adjusting the water level and it still remains over filling.								
<u>Jorge Perez</u>									
76056					7/31/2011		192		\$0.00
Medium	Work In Progress			7/31/2011 9:24:45 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
74929					7/4/2011		219		\$0.00
Medium	Work In Progress			7/4/2011 12:21:37 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82427					1/5/2012		34		\$0.00
Medium	Work In Progress			1/5/2012 3:49:27 PM					
Ronquillo, Ruben	NEED TO HAVE TWO (2) 25 X23 1/2 WIRE MESH GLASS REPLACED IN VOC. BLDG. CASE # 21113664								
<u>Arturo Nunez</u>									
78666					9/22/2011		139		\$0.00
Medium	Work In Progress			9/22/2011 10:29:40 AM					
Holguin, Alfredo	Collect Equipment data and inventory per PFSA requirements. - new Gym								
<u>Alfredo Holguin</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
83532					2/2/2012		6		\$0.00
Medium	Work In Progress			2/2/2012 10:14:11 AM					
Villalobos, David	2 toilets located in the old gym locker rooms (coach Frances) need to be serviced water pressure is very slow and wont flush waste.								
<u>Jorge Perez</u>									
79228					10/2/2011		129		\$0.00
Medium	Work In Progress			10/2/2011 12:27:48 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82143					12/15/2011		55		\$0.00
Safety	Work In Progress			12/15/2011 1:30:45 PM					
Nunez, Arturo	Please check on gas leak that was reported.								
<u>Michael Munoz</u>									
77822					9/4/2011		157		\$0.00
Medium	Work In Progress			9/4/2011 12:24:07 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82837					1/17/2012		22		\$0.00
Medium	Work In Progress			1/17/2012 12:43:02 PM					
Nunez, Arturo	Need to replace light located on daycare building. Does not turn on,								
<u>Jorge Perez</u>									
82913					1/18/2012		21		\$0.00
Medium	Work In Progress			1/18/2012 3:22:21 PM					
Nunez, Arturo	NEED A BELIMO H.W.V. FOR A.H.U. IN LIBRARY, VALVE IS DAMAGED, AND CLIMATE CAN'T BE CONTROLLED AUTO. IN FO ; G332 + NVF 24 - MFT - E US, G3NV0050, 00413-200030- 130-47, 39716DNV24- MFT 2								
<u>Arturo Nunez</u>									
81963					12/9/2011		61		\$0.00
Medium	Work In Progress			12/9/2011 3:48:25 PM					
Nunez, Arturo	NEED 2 EA. GLOW PLUG FOR YORK UNITS, MODEL #271N, 025-32625-000								
Arturo Nunez									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
80618					11/6/2011		94		\$0.00
Medium	Work In Progress			11/6/2011 12:21:37 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81000					11/14/2011		86		\$0.00
Medium	Work In Progress			11/14/2011 8:08:32 AM					
Nunez, Arturo	NEED TO CHECKED FIRE ALARM PANEL FOR BUILDING, IT IS ACTIVATED								
<u>Arturo Nunez</u>									
81600					12/2/2011		68		\$0.00
Medium	Work In Progress	New Culinary		12/2/2011 8:56:35 AM					
Nunez, Arturo	Fix fan rubbing on cage in freezer. Please coordinate with Teacher / Mrs. Lusk (915) 630-6942.								
<u>Peggy Jo Hernandez</u>									
81668					12/4/2011		66		\$0.00
Medium	Work In Progress			12/4/2011 12:16:27 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81172					11/17/2011		83		\$0.00
Medium	Work In Progress			11/17/2011 8:26:30 AM					
Nunez, Arturo	RESTROOM IN KITCHEN AREA HAS NO WATER. SNP MANAGER OLGA B. 589.5332								
<u>Maritza Gonzalez</u>									
83624					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:49 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
79151					10/2/2011	10/10/2011	129		\$0.00
Medium	Work In Progress			10/2/2011 12:27:03 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82240					1/1/2012	1/9/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:11 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
74927					7/4/2011	7/11/2011	219		\$0.00
Medium	Work In Progress			7/4/2011 12:21:36 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
77299					8/23/2011		169		\$0.00
Medium	Work In Progress			8/23/2011 3:52:36 PM					
Lara, Ralph		CYLINDERS ON OLD D.O.L. PORTABLE NEED TO BE CHANGED TEACHER HAVING A HARD TIME OPENING .							
<u>Arturo Nunez</u>									
79946					10/19/2011		112		\$0.00
Medium	Work In Progress			10/19/2011 7:55:19 AM					
Flores, Pete		NEED TO HAVE VECHILE # 70 CHECKED , FUEL LEAK.							
<u>Arturo Nunez</u>									
83531					2/2/2012		6		\$0.00
Medium	Work In Progress			2/2/2012 10:11:27 AM					
Lara, Ralph		Need a Master Key and a 113 key for custodian. cant get in to the classes or doors.							
<u>Jorge Perez</u>									
83743		Athletic Field			2/6/2012		2		\$0.00
Medium	Work In Progress			2/6/2012 3:30:26 PM					
Valdez, Pedro		tires for new soccer goals are broken.							
<u>Guadalupe Ontiveros</u>									
83752		Athletic Field			2/6/2012		2		\$0.00
Medium	Work In Progress			2/6/2012 3:43:20 PM					
Valdez, Pedro		need to check and replaced sprinklers on baseball field and softball.							
<u>Guadalupe Ontiveros</u>									
82951					1/19/2012		20		\$0.00
Medium	Work In Progress			1/19/2012 11:16:20 AM					
Prospero, Manuel		Heater in custodial offices is not working, need one of the maintanace to service it please.							
<u>Jorge Perez</u>									
81617					12/2/2011		68		\$0.00
High	Work In Progress			12/2/2011 1:39:02 PM					
Prospero, Manuel		all boiler rooms need to be cleaned as per inspectors site visit and cleaned on a schedule.call mike for inspection so that he may forward to boiler inspector. thank you							
<u>Michael Munoz</u>									
2/8/2012 1:26:28 PM									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
80199					10/25/2011		106		\$0.00
Medium	Work In Progress			10/25/2011 3:39:09 PM					
Prospero, Manuel		10/25/11. 8HRS WO 78262.				10/25 - SEE WO ABOVE			
<u>Manuel Prospero</u>									
83369					1/30/2012		9		\$0.00
Medium	Work In Progress			1/30/2012 10:28:11 AM					
Prospero, Manuel		Need to replace all 4 wheels on the chair/cart located in the new gym area, tires are bent and dont wheel out properly, and its leaving marks on the gym floor.							
<u>Jorge Perez</u>									
83691					2/5/2012	3/7/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:15 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
83692					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:16 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
83693					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:16 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
82673		Library			1/11/2012		28		\$0.00
Medium	Work In Progress	MARY ALBERT		1/11/2012 11:08:44 AM					
Prospero, Manuel		WORN-OUT BATTERIES IN LIBRARY EMERGENCY EXIT DOOR. MAKES A "CHIRPING" SOUND. PLEASE REPLACE BATTERIES. ALSO BATTERIES NEED REPLACING IN SECURITY CAMERA IN REFERENCE ROOM.							
<u>Marylou Jimenez</u>									
78414		Classroom			9/16/2011		145		\$0.00
Medium	Work In Progress			9/16/2011 7:38:49 AM					
Prospero, Manuel		please remove all ceiling tiles and doors that were removed from the cullinary art room remodel project. only store what is good.dispose of the rest.							
<u>Michael Munoz</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
78116					9/9/2011		152		\$0.00
Medium	Work In Progress			9/9/2011 11:25:30 AM					
Prospero, Manuel	Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign								
<u>Alfredo Holguin</u>									
75044					7/4/2011	7/11/2011	219		\$0.00
Medium	Work In Progress			7/4/2011 12:22:29 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75042					7/4/2011	8/3/2011	219		\$0.00
Medium	Work In Progress			7/4/2011 12:22:28 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75043					7/4/2011	7/11/2011	219		\$0.00
Medium	Work In Progress			7/4/2011 12:22:28 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75464					7/14/2011		209		\$0.00
Medium	Work In Progress			7/14/2011 1:12:03 PM					
Mijarez, Jaime	Need to fix leak in classroom.								
<u>Michael Munoz</u>									
83570		Library			2/3/2012		5		\$0.00
Medium	Work In Progress	MRS. RIOS		2/3/2012 11:00:25 AM					
Castillo, Carlos	THE HITACHI PROJECTOR IS MOUNTED ON THE SOUTH WALL-ONCE A POWER OUTLET IS MOUNTED AT THE CEILING WALL-ALL THE TECHNOLOGY NEEDED TO THE PROJECTOR NEEDS TO BE INSTALLED. THERE ARE SEVERAL BOXES IN THE CONFERENCE ROOM WITH TECHNOLOGY.								
<u>Marylou Jimenez</u>									
78367					9/14/2011		147		\$0.00
Medium	Work In Progress			9/14/2011 6:24:35 PM					
Castillo, Carlos	hand dryers need to be fixed in locker rooms and in outside concession stand								
<u>Jorge Perez</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
83221					1/26/2012		13		\$0.00
Medium	Work In Progress			1/26/2012 7:51:52 AM					
Castillo, Carlos	A POWER OUTLET NEEDS TO BE INSTALLED ON CIELING FOR HITACHI PROJECTOR IN LIBRARY CONFERNCE ROOM.								
Arturo Nunez									
83432					1/31/2012		8		\$0.00
Medium	Work In Progress			1/31/2012 11:11:11 AM					
Castillo, Carlos	electrical outlet located on the bleacher of the New gym need to be replaced. Theirs no power and its been pulled and its haggng by the wires.								
Jorge Perez									
80869					11/9/2011		91		\$0.00
Medium	Work In Progress			11/9/2011 9:45:27 AM					
Nunez, Arturo	Boy restroom in the 600 halway needs to be painted due to graffiti, as well as the boy Restroom located outside in the consseion stand out side. already removed with graffiti remover but not graffiti came off.								
Jorge Perez									
83505					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 3:28:54 PM					
Nunez, Arturo	NEED TO PAINT WALL AT SOFTBALL, GRAFFITI. CASE # 2012-01219								
Arturo Nunez									
78375					9/15/2011		146		\$0.00
Medium	Work In Progress			9/15/2011 8:14:09 AM					
Ambriz, Jose	NEED A 125,000 BTU HEATER FOR OFFICE IN SHOP, ROOM # 801.								
Arturo Nunez									
78376					9/15/2011		146		\$0.00
Medium	Work In Progress			9/15/2011 8:15:55 AM					
Ambriz, Jose	NEED A 200,00 BTU HEATER FOR SHOP # 801.								
Arturo Nunez									
78377					9/15/2011		146		\$0.00
Medium	Work In Progress			9/15/2011 8:18:20 AM					
Ambriz, Jose	NEED A 125,000 BTU HEATER FOR FOR OFFICE IN SHOP # 803.								
Arturo Nunez									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
78378					9/15/2011		146		\$0.00
Medium	Work In Progress			9/15/2011 8:19:30 AM					
Ambriz, Jose	NEED A 300,000 B.T.U HEATER FOR SHOP # 803.								
Arturo Nunez									
78379					9/15/2011		146		\$0.00
Medium	Work In Progress			9/15/2011 8:24:15 AM					
Ambriz, Jose	NEED A 125,000 BTU HEATER FOR OFFICE IN SHOP # 805.								
Arturo Nunez									
78380					9/15/2011		146		\$0.00
Medium	Work In Progress			9/15/2011 8:25:20 AM					
Ambriz, Jose	NEED A 300,00 BTU HEATER FOR SHOP # 805.								
Arturo Nunez									
78381					9/15/2011		146		\$0.00
Medium	Work In Progress			9/15/2011 8:26:26 AM					
Ambriz, Jose	NEED A 125,000 HEATER FOR OFFICE IN SHOP # 807.								
Arturo Nunez									
78382					9/15/2011		146		\$0.00
Medium	Work In Progress			9/15/2011 8:27:35 AM					
Ambriz, Jose	NEED A 200,000 BTU HEATER FOR SHOP # 807								
Arturo Nunez									
75239					7/10/2011	8/10/2011	213		\$0.00
Medium	Work In Progress			7/10/2011 12:15:53 AM					
Nunez, Arturo	Yearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.								
Margret Villalobos									
79131					10/2/2011	10/18/2011	129		\$0.00
Medium	Work In Progress			10/2/2011 12:26:52 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
Margret Villalobos									
79129					10/2/2011	10/23/2011	129		\$0.00
Medium	Work In Progress			10/2/2011 12:26:51 AM					
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
79130					10/2/2011	11/2/2011	129		\$0.00
Medium	Work In Progress			10/2/2011 12:26:51 AM					
Nunez, Arturo	Yearly - Santa Teresa HS H-6 Rftop Furn Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81374					11/28/2011		72		\$0.00
High	Work In Progress			11/28/2011 8:07:08 AM					
Nunez, Arturo	boiler sn # 040157084, as per boiler inspectors inspection, wires need to be in electrical panel and not hanging out and electrical panel needs to be closed and secured. thank you								
<u>Michael Munoz</u>									
81962					12/9/2011		61		\$0.00
Medium	Work In Progress			12/9/2011 3:46:28 PM					
Nunez, Arturo	NEED A GAS VALVE FOR A YORK UNIT FOR FOOTBALL LOCKER ROOM. MODEL # G8C1252000DL11 ,SERAIL # WKHP327946, # ON VALV E36E29, 025-32794-000. EZ9926								
<u>Arturo Nunez</u>									
79505					10/9/2011	10/25/2011	122		\$0.00
Medium	Work In Progress			10/9/2011 12:16:28 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82980					1/19/2012		20		\$0.00
Medium	Work In Progress			1/19/2012 3:47:56 PM					
Nunez, Arturo	NEED 3EA. 4L 400 V BELTS FOR COM. LABS. A.H.U.'S								
<u>Arturo Nunez</u>									
79018					9/30/2011		131		\$0.00
Medium	Work In Progress			9/30/2011 12:22:34 AM					
Prospero, Manuel	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
79086					10/2/2011	11/2/2011	129		\$0.00
Medium	Work In Progress			10/2/2011 12:26:28 AM					
Prospero, Manuel	Yearly - Santa Teresa HS U-2 Unit Ht Gas Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
79085					10/2/2011	11/2/2011	129		\$0.00
Medium	Work In Progress				10/2/2011 12:26:27 AM				
Prospero, Manuel		Yearly - Santa Teresa HS I-4 Fan Coil Unit Yearly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
76015					7/29/2011		194		\$0.00
Medium	Work In Progress	MRS.			7/29/2011 1:53:52 PM				
Prospero, Manuel		MAINTENANCE PLEASE CHECK ON HVAC UNITS LOCATED BETWEEN MAIN BUILDING AND CAFETERIA-EXCESSIVE NOISE WHILE RUNNING AND LOUD BANGING WHEN AT LEAST 1 UNIT SHUTS DOWN.							
<u>Marylou Jimenez</u>									
79871					10/17/2011		114		\$0.00
Medium	Work In Progress				10/17/2011 3:51:16 PM				
Ambriz, Jose		NEED TO INSTALL VENT PIPE AND MOTOR FOR NEW PLASMA ZING MACHINE CUTTER IN ROOM # 602							
<u>Arturo Nunez</u>									
80525					11/3/2011		97		\$0.00
Medium	Work In Progress				11/3/2011 3:44:07 PM				
Ambriz, Jose		NEED SOME ASSITANCE ON GETTING HEATER ON ROOM # 402 STARTED.							
<u>Arturo Nunez</u>									
80384					10/31/2011		100		\$0.00
Medium	Work In Progress				10/31/2011 1:46:01 PM				
Ambriz, Jose		NEED SOME ASSITANCE ON CHECKING HEATER FOR ROOM # 407, 409.							
<u>Arturo Nunez</u>									
80386					10/31/2011		100		\$0.00
Medium	Work In Progress				10/31/2011 1:49:12 PM				
Ambriz, Jose		NEED A HIGH DELTA WATER HEATER, COIL FOR KITHEN WATER HEATER, AND NEED TO ASSEMBLE UNIT.							
<u>Arturo Nunez</u>									
80851					11/8/2011		92		\$0.00
Medium	Work In Progress				11/8/2011 3:46:59 PM				
Ambriz, Jose		Need some assitance on trouble shooting heater for lobby main building.							
<u>Arturo Nunez</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Santa Teresa HS

83804					2/7/2012		1		\$0.00
Medium	Work In Progress				2/7/2012 3:52:16 PM				
Ambriz, Jose	NEED SOME ASSITANCE ON REPARING WATER LEAK ON CIRCULATING PUMP 1, FOR 300'S WING.								

Arturo Nunez									
83512					2/1/2012		7		\$0.00
Medium	Work In Progress				2/1/2012 3:44:20 PM				
Lara, Ralph	NEED THREE EA. MAIL BOXES MADE FOR OUT SIDE MAIL BOX.								

Arturo Nunez									
83513					2/1/2012		7		\$0.00
Medium	Work In Progress				2/1/2012 3:45:32 PM				
Lara, Ralph	NEED 2 PAD LOCKS MADE TO SECURE AREA BEHIND CONSESSION STAND.								

Arturo Nunez									
82121					12/14/2011		56		\$0.00
Medium	Work In Progress				12/14/2011 3:42:44 PM				
Villalobos, David	NEED A SET OF WASHER HOSES FOR CULINARY KIT WASHER.								

Arturo Nunez									
82273					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress				1/1/2012 12:44:25 AM				
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								

Margret Villalobos									
82564					1/9/2012		30		\$0.00
Medium	Work In Progress				1/9/2012 1:18:42 PM				
Villalobos, David	NEED TO ADDRESS SEVERAL GAS LEAKS IN THE GAS METER LOOP								

Manuel Prospero									
83370					1/30/2012		9		\$0.00
Medium	Work In Progress				1/30/2012 10:34:06 AM				
Villalobos, David	Need to replace all Faucets(4) located in the old lockers. Water doesn't come out. and are really old and may need to replace the whole thing. on all 4 faucets/sinks								

Jorge Perez									
78366					9/14/2011		147		\$0.00
Medium	Work In Progress				9/14/2011 6:22:42 PM				
Villalobos, David	sinks in locker rooms need to be replaced water doesnt come out in some								

Jorge Perez

2/8/2012 1:26:28 PM



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
76055					7/31/2011	8/3/2011	192		\$0.00
Medium	Work In Progress			7/31/2011 9:24:45 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
74928					7/4/2011	7/6/2011	219		\$0.00
Medium	Work In Progress			7/4/2011 12:21:36 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
77821					9/4/2011	9/7/2011	157		\$0.00
Medium	Work In Progress			9/4/2011 12:24:06 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
79066					10/2/2011	10/5/2011	129		\$0.00
Medium	Work In Progress			10/2/2011 12:26:16 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
80617					11/6/2011	11/9/2011	94		\$0.00
Medium	Work In Progress			11/6/2011 12:21:37 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81667					12/4/2011	12/7/2011	66		\$0.00
Medium	Work In Progress			12/4/2011 12:16:26 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83622					2/5/2012	2/8/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:48 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
80260					10/26/2011		105		\$0.00
Medium	Work In Progress			10/26/2011 3:49:13 PM					
Castillo, Carlos	NEED TO REPLACE LAY IN LIGHT IN CLOSET BY ROOM # 600 115V.								
Arturo Nunez									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa HS</b>									
81376					11/28/2011		72		\$0.00
High	Work In Progress			11/28/2011 8:30:26 AM					
Castillo, Carlos	boiler lockinvar sn # D04H00002833 in custodial closet does not have an emergency shutoff switch. please install as per boilers inspectors inspection. thank you								
Michael Munoz									
82123					12/14/2011		56		\$0.00
Medium	Work In Progress			12/14/2011 3:44:30 PM					
Castillo, Carlos	NEED A PIG TAIL FOR WASHER IN CULNINARY KIT, PLUG DOES NOT MATCH OUTLET.								
Arturo Nunez									
83516					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 3:50:43 PM					
Villalobos, David	NEED SOME ASSITANCE ON RUNNING WATER TO CAPPAUCINO MACHINE,AND COFFE MAKER IN NEW CULINARY KITCHEN.								
Arturo Nunez									
<b>Count: 123 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>97</b>		<b>Total for Santa Teresa HS</b>	<b>0</b>		<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
83418					1/31/2012		8		\$0.00
Medium	Work In Progress	LINE LOCATE		1/31/2012 8:16:29 AM					
Castillo, Carlos		Need to line locate on North Bldg by portables and S. Bldg by entrance (See Mike for details).							
Michael Munoz									
76500					8/5/2011		187		\$0.00
Medium	Work In Progress			8/5/2011 10:29:52 AM					
Ontiveros, Guadalupe		please assist with an operator for ditchwitch to excavate 2- 240' trenches for electrical power.thank you							
Michael Munoz									
78511					9/19/2011		142		\$0.00
Medium	Work In Progress			9/19/2011 3:35:42 PM					
Villalobos, David		N.bldg, S.bldg, and Gym. I need help with several urinals that are leaking from the back seal, several toilets that are leaking from wax ring and loose because of rusted toilet bolts, also several flush valves that need new plumbing parts. David might need to order some of the materials if we don't have them.							
Jaime Mijarez									
83417					1/31/2012		8		\$0.00
Medium	Work In Progress	LINE LOCATE		1/31/2012 8:15:50 AM					
Villalobos, David		Need to line locate on North Bldg by portables and S. Bldg by entrance (See Mike for details).							
Michael Munoz									
82274					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:26 AM					
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
83529					2/2/2012		6		\$0.00
Medium	Work In Progress			2/2/2012 9:51:51 AM					
Lara, Ralph		N.bldg upper level teachers restroom. Principal and Teacher Mr. Ball are requesting a dead bolt lock on door for more privacy. Please get with the principal and see what they need.							
Jaime Mijarez									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
79364					10/4/2011		127		\$0.00
Medium	Work In Progress			10/4/2011 9:36:11 AM					
Lara, Ralph	Principal is requesting Door Mullians with key core on cafeteria doors and lobby doors. Existing mullians are screwed on frame with brackets and makes it a hassle when they have to be removed when cafeteria furniture has to be taken out or when deliveries on pallets are moved into the lobby. The south buliding will require some mullians with key too but first check with the Principal.								
Jaime Mijarez									
78670					9/22/2011		139		\$0.00
High	Work In Progress			9/22/2011 12:32:04 PM					
Mijarez, Jaime	fire lines are in need of painting. please remove sand and paint curbs red to include fire lanes wording on curbs.thank you								
Michael Munoz									
81069		Parking Lot			11/15/2011		85		\$0.00
Medium	Work In Progress			11/15/2011 2:50:13 PM					
Castillo, Carlos	5 parking lot light poles are out.								
Carlos Castillo									
81071		Parking Lot			11/15/2011		85		\$0.00
Medium	Work In Progress			11/15/2011 2:53:11 PM					
Castillo, Carlos	5 parking lot light poles are out as per Ms.Lovelace.Need to repair.								
Carlos Castillo									
76423					8/4/2011		188		\$0.00
Medium	Work In Progress			8/4/2011 9:10:56 AM					
Mijarez, Jaime	S.bldg upper level mechanical room heat pump is not changing to cooling it stays in heating mode. I already did some troubleshooting on tracer summit and it looks ok.								
Jaime Mijarez									
82326					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:51 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
83671					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:08 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa MS</b>									
83672					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:08 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83669					2/5/2012	3/7/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:07 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83670					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:07 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
78278		Gym			9/13/2011		148		\$0.00
Medium	Work In Progress			9/13/2011 3:50:39 PM					
Valles, Johnny	please order and replace hot box for irrigation back flow on the northeast side of gym.thank you								
<u>Michael Munoz</u>									
75770					7/25/2011		198		\$0.00
Medium	Work In Progress			7/25/2011 9:37:48 AM					
Lara, Ralph	Metal portable room 3-a, 3-a doors need to be secure please check with principal Montano to see if they want dead bolt locks on both room entrance doors. As per Mrs. Lovelace portable rooms will be used for Orchestra music and they will be having expensive music instruments. A.S.A.P								
<u>Jaime Mijarez</u>									
83158					1/25/2012		14		\$0.00
High	Work In Progress			1/25/2012 8:31:42 AM					
Marquez, Gerardo	need to install some supports for some hand rails in the south building in the mens restrooms in main office. thank you								
<u>Michael Munoz</u>									
81327		Cafeteria			11/22/2011		78		\$0.00
Medium	Work In Progress			11/22/2011 12:06:28					
Orozco, Danny	need to have hood suppression system serviced and repaired as per last inspection								
<u>Danny Orozco</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Santa Teresa MS

76499 8/5/2011 187 \$0.00

Medium Work In Progress 8/5/2011 10:27:29 AM

Gonzalez, Salvador as per our conversation, please order material for light poles that are to be installed. thank you

(concrete)

Michael Munoz

83108 Athletic Field 1/24/2012 15 \$0.00

Medium Work In Progress 1/24/2012 8:24:26 AM

Ontiveros, Guadalupe need concrete slab for R.P.A hot box 8'x 10' will take about two yards.

Guadalupe Ontiveros

82321 1/1/2012 1/7/2012 38 \$0.00

Medium Work In Progress 1/1/2012 12:44:49 AM

Mijarez, Jaime Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

83668 2/5/2012 2/11/2012 3 \$0.00

Medium Work In Progress 2/5/2012 12:18:06 AM

Mijarez, Jaime Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

81967 Library 12/9/2011 61 \$0.00

Medium Work In Progress Library 12/9/2011 3:56:15 PM

Mijarez, Jaime Can we please have someone from maintenance tighten tables and chairs they are loose. There are some shelves that need brackets replaced with permanent bracket. These need to be done as soon as possible - this is a safety issue - we had 1 incident already.

Rosa Hidalgo

83781 North Building Classroom 2/7/2012 1 \$0.00

Medium Work In Progress ROOM 1 2/7/2012 2:31:41 PM

Mijarez, Jaime ASSEMBLE 10 RACKS FOR ART ROOM. RACKS WILL BE PLACED IN ART ROOM TO SERVE AS STORAGE AND DISPLAY RACKS

Laura Parra

80956 North Building 11/10/2011 90 \$0.00

Medium Work In Progress 11/10/2011 3:26:47 PM

Munoz, Michael need a fence between the west portable and the edge of the hill with 2 8 ft gates to prevent vehicles from entering to the bottom of the gym.

Alfredo Holguin

2/8/2012 1:26:28 PM

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
75542	North Building	Hallway/Corridor			7/19/2011		204		\$0.00
Medium	Work In Progress			7/19/2011 12:54:49 PM					
Estrada, Jesus	Lobby tile needs to be replaced north building.		2/1/12 - WILL BE TAKEN CARE OF DURING SUMMER BREAK						
Jesus Estrada									
83164	North Building	Dressing Room			1/25/2012		14		\$0.00
Medium	Work In Progress			1/25/2012 11:17:47 AM					
Lara, Ralph	The exit back door to boys dressing room the baseboard came off it needs to be paste to the wall.Thanks								
Ismael Rodriguez									
80181	North Building	Parking Lot			10/25/2011		106		\$0.00
Medium	Work In Progress			10/25/2011 10:58:43					
Mijarez, Jaime	Add two more ADA parking spaces in parking area in center of lot between Mobile Home and North Bldg use parking spaces close to blds- intall post signs and mark pavement with stencil								
Alfredo Holguin									
76756	North Building	Custodial			8/10/2011		182		\$0.00
Medium	Work In Progress			8/10/2011 8:57:39 AM					
Flores, Pete	Pete, the small tracter #455 needs tires and the oil to be change.								
Ismael Rodriguez									
82891	North Building	Parking Lot			1/18/2012		21		\$0.00
Medium	Work In Progress			1/18/2012 8:46:10 AM					
Flores, Pete	Lupe I need to borrow the small tracter from riverside to clear sand from parking lot and portables.		Reroute to Pete asp Lupe 1/26/12						
Ismael Rodriguez									
78658	North Building				9/22/2011		139		\$0.00
High	Work In Progress			9/22/2011 8:42:12 AM					
Villalobos, David	as per our conversation, please identify location for new cleanout, this will require cutting concrete, excavating and installing material.thank you								
Michael Munoz									
82997	North Building	Classroom			1/20/2012		19		\$0.00
Medium	Work In Progress	ROOM 3		1/20/2012 8:56:12 AM					
Castillo, Carlos	Needs 2 electrical outlets: 1 in restroom for High Low Table 2- Infocuse								
Laura Parra									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
77317	South Building	Restroom (Girls)			8/24/2011		168		\$0.00
Medium	Work In Progress				8/24/2011 7:48:12 AM				
Lara, Ralph	REplacement of bathroom panel in south upper girls restroom as per Mr. Montano.								
<u>Ismael Rodriguez</u>									
83421	South Building	Custodial			1/31/2012		8		\$0.00
Medium	Work In Progress				1/31/2012 8:52:45 AM				
Lara, Ralph	Rafa i need replacement for of key for Mr.Grier P-key.								
<u>Ismael Rodriguez</u>									
80182	South Building	Parking Lot			10/25/2011		106		\$0.00
Medium	Work In Progress				10/25/2011 11:05:34				
Mijarez, Jaime	Add three more ADA parking spaces next to existion ADA parking space- intall post signs and mark pavement with stencil								
<u>Alfredo Holguin</u>									
79733	South Building	Parking Lot			10/13/2011		118		\$0.00
Medium	Work In Progress	NORTH AND			10/13/2011 2:46:54 PM				
Mijarez, Jaime	NEED AT LEAST 2 ADDITIONAL HANDI CAP PARKING SPACES FOR THE SOUTH AND NORTH BUILDINGS.								
<u>Laura Parra</u>									
80957	South Building				11/10/2011		90		\$0.00
Medium	Work In Progress				11/10/2011 3:28:24 PM				
Munoz, Michael	need fence from entrance gate to bottom of parking lot where curb begins.								
<u>Alfredo Holguin</u>									
80008	South Building	Football Field			10/20/2011		111		\$0.00
Medium	Work In Progress				10/20/2011 11:33:14				
Ontiveros, Guadalupe	The fence coming down the hill from south building that connects to atheletic field needs repair to keep intruders out.								
<u>Ismael Rodriguez</u>									
80179	South Building	Restroom (Boys)			10/25/2011		106		\$0.00
Medium	Work In Progress				10/25/2011 10:54:23				
Lara, Ralph	Admin Area Mens RR - install additional grab bar (retractable if possible) on opposite side of existing. Also replace existing nurses couch with a adult size retractable changing table if available to allow door to open completely.								
<u>Alfredo Holguin</u>									



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
79607	South Building	Parking Lot			10/11/2011		120		\$0.00
Medium	Work In Progress	SOUTH FENCE			10/11/2011 8:25:10 AM				
Gonzalez, Salvador		FENCE NEEDS TO BE REPAIRED. FENCE IS CUT AND IS BEING HELD TOGETHER WITH A WIRE.							
Laura Parra									
83236	Gym (1997)	Dressing Room			1/26/2012		13		\$0.00
Medium	Work In Progress				1/26/2012 11:59:07 AM				
Mijarez, Jaime		Boys and Girls Locker Rooms. - Build and install benches in the Shower areas. If you have questions on specifics check with Ms. Lovelace or Mr. Montano							
Alfredo Holguin									
83165	Gym (1997)	Restroom (Girls)			1/25/2012		14		\$0.00
Medium	Work In Progress				1/25/2012 11:22:39 AM				
Lara, Ralph		Rafa in the gym lobby area girls restroom needs the door handle.							
Ismael Rodriguez									
75618	Gym (1997)	Restroom (Boys)			7/21/2011		202		\$0.00
Medium	Work In Progress				7/21/2011 7:11:51 AM				
Villalobos, David		Two urinals are leaking water ever time you flush them the floor get puddles of water and smells bad i would like for the plumber to fix them before students return .thanks							
Ismael Rodriguez									
75769					7/25/2011		198		\$0.00
Medium	Work In Progress				7/25/2011 9:28:54 AM				
Gonzalez, Salvador		Metal portable rooms 3-a, 3-b need window guards installed on all windows. As per Mrs. Lovelace portables rooms will be used for Orchestra music and they will be having expensive music instruments. A.S.A.P							
Jaime Mijarez									
78912					9/28/2011		133		\$0.00
Medium	Work In Progress				9/28/2011 11:19:14 AM				
Gonzalez, Salvador		please install railing by the parking lot / sidewalk to continue with the design of existing. please see me for details. thank you							
Michael Munoz									
77770					9/2/2011		159		\$0.00
Medium	Work In Progress				9/2/2011 11:53:44 AM				
Orozco, Danny		REACH IN FREEZER IS NOT FREEZING PROPERLY. SNP MANAGER PAULA S. 589.9836							
Maritza Gonzalez									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
83386					1/30/2012		9		\$0.00
Medium	Work In Progress				1/30/2012 3:07:40 PM				
Orozco, Danny	GARBAGE DISPOSAL IS CLOGGED. SNP MANAGER PAULA S. 589.9836								
Maritza Gonzalez									
78907					9/28/2011		133		\$0.00
Medium	Work In Progress				9/28/2011 10:20:54 AM				
Munoz, Michael	Gym parking. Principal is requesting a handicap cement ramp by the boys dressing room asphalt parking lot.								
Jaime Mijarez									
<b>Count: 50 Work Orders</b>	<b>Avg. Age of WO's</b>		<b>85</b>	<b>Total for Santa Teresa MS</b>				<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Sunland Park ES

83735 Parking Lot 2/6/2012 2 \$0.00

Medium Work In Progress 2/6/2012 1:04:56 PM

Munoz, Michael need a sidewalk from east parking lot to asphalt that goes around school. teachers have to walk into on coming traffic.

David Avila

79599 Main Building 10/11/2011 120 \$0.00

Medium Work In Progress PLAYGROUND 10/11/2011 7:20:40 AM

Medina, Eric AS PER MS. GUTIERREZ, PLAYGROUND HAS A BIG HOLE - NEEDS REPAIR. LAST YEAR A FIRST GRADER BROKE HER HAND WHEN SHE TRIPPED. PLEASE SEE MS. GUTIERREZ FOR QUESTIONS.

David Avila

76419 Main Building Parking Lot 8/4/2011 161 \$0.00

Medium Work In Progress 8/4/2011 8:42:20 AM 1/12/2012

Medina, Eric Eric, the trees out in the parking lot need to be trimmed. We've had several complaints about trees scratching the cars that pass by.

Yvette Cortez

76493 Main Building Parking Lot 8/5/2011 187 \$0.00

Medium Work In Progress 8/5/2011 9:40:34 AM

Medina, Eric Eric, as per Mrs. Ramirez we need four baracades. Please place an order for them.

Yvette Cortez

83745 Main Building Parking Lot 2/6/2012 2 \$0.00

Medium Work In Progress OFFICE- 2/6/2012 3:31:19 PM

Medina, Eric AS PER MS. DUQUE - WOULD LIKE TO SEE IF SIGNS CAN BE MADE TO PUT IN THE PARKING LOT/TURNABOUT. "NO PARKING"; "KEEP PULLING FORWARD". ALSO WOULD LIKE TO SEE IF WE CAN PUT SIGNS ON THE ROAD TO SEPERATE LANES; ARROWS AND NO PARKING SIGNS.

David Avila

83746 Main Building Parking Lot 2/6/2012 2 \$0.00

Medium Work In Progress PARKING LOT 2/6/2012 3:32:35 PM

Medina, Eric AS PER MS. RAMIREZ - ERIC, PLEASE CLEAN TURNABOUT AND PARKING LOT OF DIRT. PARENTS HAVE EXPRESSED THEIR CONCERNS WITH ALL THE DIRT AROUND THE PARKING LOT AND TURNABOUT.

David Avila

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Sunland Park ES

78326	Main Building	Classroom			9/14/2011		147		\$0.00
Medium	Work In Progress	BRIONES			9/14/2011 10:55:45 AM				
Medina, Eric	ERICK, WE NEED A PENCIL SHARPNER INSTALLED IN MRS. BRIONES CLASSROOM RM#11. THANK YOU								

David Avila

82817	Main Building				1/17/2012		22		\$0.00
Medium	Work In Progress	PARENT			1/17/2012 8:30:08 AM				
Munoz, Michael	AS PER MS. RAMIREZ - WOULD LIKE TO REQUEST IF A SIDEWALK CAN BE MADE LEADING FROM THE PARKING LOT TO THE MAIN ROAD. MANY PARENTS AND TEACHERS ARE WALKING THROUGH THE DIRT, THEY HAVE EXPRESSED THEIR CONCERN ON THIS. FOR QUESTIONS PLEASE SEE THE OFFICE. THANK YOU.								

David Avila

83244	Main Building	Classroom			1/26/2012		13		\$0.00
Medium	Work In Progress	CLASSROOM			1/26/2012 2:28:47 PM				
Castillo, Carlos	AS PER MS. VENEGAS - WE NEED TO RUN ELECTRICITY TO THE OVERHEAD PROJECTOR LOCATED AT THE CIELING OF THE CLASSROOM. THE PROJECTOR IS INSTALLED BUT CANNOT BE USED DUE TO THE FACT THAT THERE IS NO OUTLET TO CONNECT IT TO.								

David Avila

78817	Main Building	Portables			9/27/2011		134		\$0.00
Medium	Work In Progress	PORTABLE E			9/27/2011 8:16:17 AM				
Medina, Eric	WOULD LIKE TO HAVE PORTABLE E PAINTED AS IT IS SERVING AS THE OFFICE FOR THE SCHOOL COUNSELOR, PARENT AMBASSADOR AND SPEECH THERAPIST.								

David Avila

76545	Main Building	Classroom			8/5/2011		187		\$0.00
Medium	Work In Progress	25			8/5/2011 3:22:25 PM				
Medina, Eric	Eric, the bathroom in room 25 needs to be painted. Room was painted but bathroom needs to be painted as well.								

Yvette Cortez

77338	Main Building	Library			8/24/2011		168		\$0.00
Medium	Work In Progress	C. MORENO			8/24/2011 12:18:43 PM				
Medina, Eric	NEED MAIN LIBRARY DOORS AND AUDIO VISUAL DOORS RE-PAINTED.								

David Avila

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Sunland Park ES

81793	Main Building	Portables			12/5/2011		65		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Portable B (Mr.		12/5/2011 12:28:24 PM					
--------	------------------	-----------------	--	-----------------------	--	--	--	--	--

Ambriz, Jose

AS PER MR. MENDEZ- HIS HEATER IS NOT WORKING. DISTRICT TECHNICIAN CAME TO SEE, HE WILL BE ABLE TO FIX IT WITHIN THE NEXT COUPLE OF DAYS. WE ARE REQUESTING SOME SPACE HEATERS TO PUT IN THE CLASSROOM UNTIL THE HEATER IS FIXED. IF YOU HAVE ANY QUESTIONS PLEASE FEEL FREE TO LET ME KNOW. DAVID AVIL AT 575-589-1114. THANK YOU!

David Avila

78324	Main Building	Classroom			9/14/2011		147		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/14/2011 10:39:24 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Villalobos, David

David need for you to come and see what we need to install washer and dryer in room 20

Eric Medina

83010	Main Building				1/20/2012		19		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	FRONT		1/20/2012 11:41:38 AM					
--------	------------------	-------	--	-----------------------	--	--	--	--	--

Medina, Eric

AS PER MS. RAMIREZ/MS. DUQUE- ERIC, PLEASE CLEAN FRONT COURTYARD AND RID OF ALL PIGEON DROPPINGS. WE HAVE HAD SEVERAL PARENTS CALLING AND STOPPING BY TO COMPLAIN ABOUT THIS. MANY PARENTS ARE GROSSED OUT AND ARE SCARED OF BACTERIA OR OTHER THINGS FORMING FROM IT, GETTING A CHILD SICK. IF YOU HAVE ANY QUESTIONS PLEASE SEE THE FRONT OFFICE.

same request as 82816

David Avila

83774					2/7/2012		1		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress			2/7/2012 9:14:09 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Orozco, Danny

MANAGER HAVING TROUBLE WITH OVEN ONCE AGAIN, WHEN SHE OPENS OVEN TO CHECK ON FOOD, OVEN TURNS OFF COMPLETELY. SNP MARINA R. 589.2545

Maritza Gonzalez

83170		Athletic Field			1/25/2012		14		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/25/2012 2:32:55 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Medina, Eric

please check if pine trees on soccer fields are getting watered. also remove the dead pine tree and replace with new one. thank you

Michael Munoz

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
77700					9/1/2011		160		\$0.00
Medium	Work In Progress			9/1/2011 11:06:45 AM					
Medina, Eric	purchase new D130 john deere lawn mower for site to replace existing one.								
Michael Munoz									
82801					1/13/2012		26		\$0.00
Medium	Work In Progress			1/13/2012 3:46:15 PM					
Flores, Pete	Pete need to request bobcat for sunland park								
Eric Medina									
83643					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress			2/5/2012 12:17:57 AM					
Medina, Eric	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
78126					9/9/2011		152		\$0.00
Medium	Work In Progress			9/9/2011 2:44:46 PM					
Munoz, Michael	need to construct concret pad for trash dumpsters								
Alfredo Holguin									
83788					2/7/2012		1		\$0.00
Medium	Work In Progress			2/7/2012 3:39:00 PM					
Lara, Ralph	Rafa mechanical room door does not close								
Eric Medina									
80986					11/13/2011	11/29/2011	87		\$0.00
Medium	Work In Progress			11/13/2011 12:15:30					
Medina, Eric	Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
83157					1/25/2012		14		\$0.00
High	Work In Progress			1/25/2012 8:29:17 AM					
Marquez, Gerardo	storage room next to restroom in room # 20 needs a 6" fur-out wall on the south wall. this needs to be done before spring break please call mike for details.thank you								
Michael Munoz									
82614		Mechanical			1/10/2012		29		\$0.00
High	Work In Progress			1/10/2012 9:50:25 AM					
Medina, Eric	as per site inspection by boiler inspector, mechanical rooms are not to be used for storage. rooms need to be clean and maintained. thank you								
Michael Munoz									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Sunland Park ES

82576					1/9/2012		30		\$0.00
Medium	Work In Progress				1/9/2012 3:14:20 PM				
Carrasco, Danny	Danny need small sissor lift for pigeon nest removal								

<u>Eric Medina</u>									
83185					1/25/2012		14		\$0.00
Medium	Work In Progress				1/25/2012 3:16:41 PM				
Medina, Eric	please repair and sraighten rails on portable e, thank you								

<u>Michael Munoz</u>									
83644					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:17:57 AM				
Medina, Eric	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								

<u>Margret Villalobos</u>									
83188					1/25/2012		14		\$0.00
High	Work In Progress				1/25/2012 3:20:25 PM				
Medina, Eric	gutter on classroom # 24 needs to be secured and gutter on room 20 needs to be replaced. please check other gutters as well .thank you								

<u>Michael Munoz</u>									
83189					1/25/2012		14		\$0.00
Medium	Work In Progress				1/25/2012 3:22:10 PM				
Medina, Eric	please adjust door to boiler mechanical room by cafeteria. thank you								

<u>Michael Munoz</u>									
83190					1/25/2012		14		\$0.00
Medium	Work In Progress				1/25/2012 3:24:28 PM				
Medina, Eric	electrical room where stairs are to roof above cafeteria kithcen needs to be cleaned. thankyou								

<u>Michael Munoz</u>									
83642					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:17:56 AM				
Medina, Eric	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								

<u>Margret Villalobos</u>									
83171					1/25/2012		14		\$0.00
Medium	Work In Progress				1/25/2012 2:34:50 PM				
Medina, Eric	please remove sand build up along fence line on the east side of the soccer filed, also on curb and sidewalk on bus turn around.								

Michael Munoz

2/8/2012 1:26:28 PM

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Sunland Park ES

83172					1/25/2012		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/25/2012 2:36:43 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Medina, Eric leaves need to be raked and picked-up on inner rock wall.

Michael Munoz

83173					1/25/2012		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/25/2012 2:38:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Medina, Eric please remove pine needles from gutters around campus. this is part of the roof Pms.thanks you

Michael Munoz

83174					1/25/2012		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/25/2012 2:40:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Medina, Eric please remove mistle toe from tree on the north east side of campus and other trees if they also have it. thank you

Michael Munoz

83175					1/25/2012		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				1/25/2012 2:42:23 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Medina, Eric please paint over graffitti on wall on the north east side of building as per our conversation on 1-17-12. thank you

Michael Munoz

83176					1/25/2012		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/25/2012 2:44:19 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Medina, Eric please rake and reove fruit from mesquite tree next to classroom on the eastside in front of campus. thank you.

Michael Munoz

83177					1/25/2012		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress				1/25/2012 2:46:24 PM				
------	------------------	--	--	--	----------------------	--	--	--	--

Medina, Eric coves in front of campus needs to be raked and debre needs to be picked up. especially in front of pricipals office. also please remove shrubs there as well as per conversation held with you. thank you

Michael Munoz

83179					1/25/2012		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/25/2012 2:49:06 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Medina, Eric on front entrance pole lights. the pole cover on the bottom needs to be replaced on several poles and painted to match. rusted out.thank you

Michael Munoz



# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
83180					1/25/2012		14		\$0.00
High	Work In Progress			1/25/2012 2:50:48 PM					
Medina, Eric	peigon droppings need to be removed and watered down daily, especially on the entrance.thank you								
<u>Michael Munoz</u>									
83181					1/25/2012		14		\$0.00
High	Work In Progress			1/25/2012 2:52:42 PM					
Medina, Eric	more piegon spikes need to be installed around, especially in the front entrance campus and nest and eggs need to be removed daily. thank you								
<u>Michael Munoz</u>									
83184		Portables			1/25/2012		14		\$0.00
High	Work In Progress			1/25/2012 3:15:18 PM					
Medina, Eric	please replace skirting on portable d. this is a safety issue and has been addressed before. thank you								
<u>Michael Munoz</u>									
83169		Portables			1/25/2012		14		\$0.00
Medium	Work In Progress			1/25/2012 2:30:58 PM					
Medina, Eric	please clean around portable f. thank you								
<u>Michael Munoz</u>									
79959					10/19/2011		112		\$0.00
Medium	Work In Progress			10/19/2011 12:05:31					
Medina, Eric	AS PER MS. SMITH, ONE OF HER WALLS IS ALWAYS WET, AS IF THERE IS A LEAK. WOULD LIKE TO SEE IF ERICK CAN LOOK AT IT.								
<u>David Avila</u>									
80558					11/4/2011		96		\$0.00
High	Work In Progress			11/4/2011 1:33:26 PM					
Medina, Eric	as per our conversation please install bird spikes in areas where needed and continue to install as need be.thank you								
<u>Michael Munoz</u>									
80419					11/1/2011		99		\$0.00
Medium	Work In Progress	OFFICE		11/1/2011 10:59:09 AM					
Medina, Eric	ERIC, DOOR STOPPER IN MAIN OFFICE DOOR NEEDS TO BE INSTALLED. THANK YOU.								
<u>David Avila</u>									
82963					1/19/2012		20		\$0.00
Medium	Work In Progress			1/19/2012 3:23:24 PM					
Medina, Eric	need new toilet for bathroom outside on north campus, toilet is cracked								
<u>Eric Medina</u>									
2/8/2012 1:26:29 PM									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
82291					1/1/2012	1/9/2012	38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:33 AM					
Medina, Eric	Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82534					1/8/2012	1/24/2012	31		\$0.00
Medium	Work In Progress			1/8/2012 12:16:09 AM					
Castillo, Valeria	Monthly - QRTLY BDLG INSP REPORT (SP) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
78325		Classroom			9/14/2011		147		\$0.00
Medium	Work In Progress			9/14/2011 10:41:03 AM					
Castillo, Carlos	Cali need for you to come and see what we need to install washer and dryer in room 20								
<u>Eric Medina</u>									
78786					9/26/2011		135		\$0.00
Medium	Work In Progress			9/26/2011 2:29:22 PM					
Medina, Eric	Need paint for graffitti and hand rails								
<u>Eric Medina</u>									
76704		Restroom (Girls)			8/9/2011		183		\$0.00
Medium	Work In Progress			8/9/2011 1:14:03 PM					
Medina, Eric	Eric, girls bathroom floor needs t be painted.								
<u>Yvette Cortez</u>									
83186					1/25/2012		14		\$0.00
High	Work In Progress			1/25/2012 3:18:25 PM					
Medina, Eric	please paint on asphalt loading and unloading only on cafeteria parking lot for vendors.thank you								
<u>Michael Munoz</u>									
83183					1/25/2012		14		\$0.00
Medium	Work In Progress			1/25/2012 3:13:41 PM					
Medina, Eric	concrete on poarch colums around campus need to painted. thank you								
<u>Michael Munoz</u>									
77043					8/17/2011		175		\$0.00
Medium	Work In Progress			8/17/2011 8:23:35 AM					
Ambriz, Jose	Jose need to order frames also for the new a/c's at sunland park if possible								
<u>Eric Medina</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Sunland Park ES</b>								
82272					1/1/2012	2/1/2012	38		\$0.00	
Medium	Work In Progress			1/1/2012 12:44:25 AM						
Villalobos, David		Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
83068		Classroom			1/23/2012		16		\$0.00	
Medium	Work In Progress	CLASSROOM		1/23/2012 11:37:16 AM						
Medina, Eric		AS PER MS. DUQUE- NEED TO HAVE SCREEN PROJECTOR INSTALLED IN NEW IEP ROOM. MS. DUQUE IS REQUESTING IF THIS CAN BE DONE AS SOON AS POSSIBLE. FOR QUESTIONS PLEASE CALL MS. DUQUE AT 575-589-1114.								
Avila, David										
83789					2/7/2012		1		\$0.00	
Medium	Work In Progress			2/7/2012 3:41:54 PM						
Castillo, Carlos		Cali outlets in rm 23 are not working								
Eric Medina										
<b>Count: 59 Work Orders</b>		<b>Avg. Age of WO's 55</b>		<b>Total for Sunland Park ES</b>				<b>0</b>	<b>\$0.00</b>	

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
82271					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress				1/1/2012 12:44:25 AM				
Villalobos, David	Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
77467					8/26/2011		166		\$0.00
Medium	Work In Progress				8/26/2011 8:35:55 AM				
Lozoya, Manny	need fix gabinete lock not open on parent room								
Juan Vargas									
78619					9/21/2011		140		\$0.00
Medium	Work In Progress				9/21/2011 11:04:59 AM				
Ontiveros, Guadalupe	nesesito un pino de 8 ft. para ponerlo donde el aire tunbo un pino								
Juan Vargas									
83677					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:10 AM				
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
83678					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:10 AM				
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
83679					2/5/2012		3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:11 AM				
Vargas, Juan	Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
83122					1/24/2012		15		\$0.00
Medium	Work In Progress				1/24/2012 3:18:48 PM				
Carrasco, Danny	need thermosta guards covers								
Juan Vargas									
83676					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:18:09 AM				
Vargas, Juan	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
81163		Cafeteria			11/17/2011		83		\$0.00
Medium	Work In Progress			11/17/2011 7:54:52 AM					
Orozco, Danny	need to have hood serviced and repaired as per last hood suppression system inspection								
<u>Danny Orozco</u>									
80885					11/9/2011		91		\$0.00
Medium	Work In Progress			11/9/2011 1:58:39 PM					
Lozoya, Manny	need 6 replace cast buper/ holder on entry doors								
<u>Juan Vargas</u>									
83469					2/1/2012		7		\$0.00
Medium	Work In Progress			2/1/2012 8:10:56 AM					
Orozco, Danny	Ice machine in leaking water on the floor, which ruins the tile. It Appears to be the copper line. SNP Manager Virginia P. 824.3194								
<u>Maritza Gonzalez</u>									
82342					1/1/2012		38		\$0.00
Medium	Work In Progress			1/1/2012 12:44:59 AM					
Apodaca, Mario	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
83690					2/5/2012		3		\$0.00
Medium	Work In Progress			2/5/2012 12:18:15 AM					
Apodaca, Mario	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
75071					7/4/2011		219		\$0.00
Medium	Work In Progress			7/4/2011 12:22:39 AM					
Sanchez, Raul	Monthly - Sunrise ES - DP-1421 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82367					1/1/2012		38		\$0.00
Medium	Work In Progress			1/1/2012 12:45:16 AM					
Sanchez, Raul	Monthly - Sunrise ES - DP-1421 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82675	Main Building	Classroom			1/11/2012		28		\$0.00
Medium	Work In Progress	308		1/11/2012 1:16:24 PM					
Lozoya, Manny	TERRY SHELDON, 308, NEEDS HER CABINET KEY REPLACED TS105 IT BROKE IN HALF.								
<u>Joanne Munoz</u>									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
83048	Main Building	Classroom			1/20/2012		19		\$0.00
Medium	Work In Progress	P-4			1/20/2012 4:09:43 PM				
Lozoya, Manny		ANGIE VALENCIA, P-4, NEEDS REPLACEMENT KEY FOR HER CABINET SLC02 IT BROKE IN HALF							
Joanne Munoz									
83723	Main Building	Library			2/6/2012		2		\$0.00
High	Work In Progress				2/6/2012 7:35:37 AM				
Gallegos, Felipe		Make sure the shelves, tables and window sills are dusted at least once a week. Library office should also be serviced on a daily basis.							
Jesus Estrada									
82469	Main Building	Cafeteria			1/6/2012		33		\$0.00
Medium	Work In Progress				1/6/2012 1:17:13 PM				
Carbajal, Jimmy		Minuteman floor shower scrubber Ser # bfr 2001150943 flops down after clutch disk is installed. Can't move scrubber from point A to point B without it flopping down at all. Unable to move.							
Felipe Gallegos									
<b>Count: 19 Work Orders</b>		<b>Avg. Age of WO's 49</b>			<b>Total for Sunrise ES</b>			<b>0</b>	<b>\$0.00</b>

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
83631					2/5/2012	2/11/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:17:52 AM				
Miranda, Danny	Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
83468					2/1/2012		7		\$0.00
Medium	Work In Progress				2/1/2012 7:55:08 AM				
Flores, Pete	NEED BOBCAT TO WORK GROUNDS AND PONDS								
Danny Miranda									
83225					1/26/2012		13		\$0.00
Medium	Work In Progress				1/26/2012 8:52:55 AM				
Miranda, Danny	NEED TO PUT PROTECTIVE COVER ON FIRE ALARM PULL STATION IN NEW SP/ED ROOM 103								
Danny Miranda									
80058					10/21/2011		110		\$0.00
Medium	Work In Progress				10/21/2011 12:26:23				
Estrada, Jesus	NEED TO REMOVE CARPET ON STAGE AND PUT IN WOOD FLOOR					1/30/12 - PENDING QUOTE FROM RODRIGUEZ			
Danny Miranda									
83053					1/23/2012		16		\$0.00
Medium	Work In Progress				1/23/2012 9:04:48 AM				
Miranda, Danny	NEED TO ORDER FILTERS FOR UNITS								
Danny Miranda									
81898					12/8/2011		62		\$0.00
Medium	Work In Progress				12/8/2011 1:41:19 PM				
Miranda, Danny	NEED BLINDS FOR FRONT OFFICE AND FRONT ENTRANCE								
Danny Miranda									
83632					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:17:52 AM				
Miranda, Danny	Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
83633					2/5/2012	2/13/2012	3		\$0.00
Medium	Work In Progress				2/5/2012 12:17:53 AM				
Miranda, Danny	Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 1035 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
83634					2/5/2012		3		\$0.00
Medium	Work In Progress				2/5/2012 12:17:53 AM				
Miranda, Danny	Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
77005					8/16/2011		176		\$0.00
Medium	Work In Progress				8/16/2011 2:05:23 PM				
Ontiveros, Guadalupe	NEED TO REPLACE DEAD PINE TREE WITH NEW ONE BY BUSS TURN AROUND								
Danny Miranda									
80838					11/8/2011		92		\$0.00
Medium	Work In Progress				11/8/2011 3:19:35 PM				
Flores, Pete	NEED TO SERVICE RIDING MOWER AND REPLACE BLADES								
Danny Miranda									
80277					10/27/2011		104		\$0.00
Medium	Work In Progress				10/27/2011 8:44:08 AM				
Lozoya, Manny	NEED TO CK. KEY TO RM. #100 KEY WILL NOT TURN CYLINDER								
Danny Miranda									
83271					1/27/2012		12		\$0.00
Medium	Work In Progress				1/27/2012 8:39:10 AM				
Solis, Lorenzo	NEED TO CK UNIT IN ROOM 105 WHEN IT TURNS OFF IT WILL NOT AUTO RESTART HAVE TO RESET ON T/S EVERY TIME								
Danny Miranda									
81802					12/5/2011		65		\$0.00
Medium	Work In Progress				12/5/2011 2:38:58 PM				
Solis, Lorenzo	NEED TO CK WATER LEAK TO BOOSTER PUMP IN 300-WING BOILER ROOM								
Danny Miranda									
82255					1/1/2012	2/1/2012	38		\$0.00
Medium	Work In Progress				1/1/2012 12:44:18 AM				
Villalobos, David	Yearly - Vado ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 15 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>47</b>	<b>Total for Vado ES</b>			<b>0</b>	<b>\$0.00</b>	
<b>Count: 1035 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>63</b>	<b>Grand Total</b>			<b>2.5</b>	<b>\$212.94</b>	