

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To	Description		Action Taken							
Requester Name										
<b>Location:</b>		<b>Alma Del Valle Daycare</b>								
98506					2/14/2013		0		\$0.00	
Medium	Work In Progress				2/14/2013 7:04:32 AM					
Ontiveros, Guadalupe	NEED SAND FOR DAYCARE SANDBOX. (FRONT OF BUILDING). 5 1/2 FT X 5 1/2 FT WIDE, 1 FT DEEP.									
Adam Montoya										
<b>Count: 1 Work Orders</b>	<b>Avg. Age of WO's</b>		<b>Total for Alma Del Valle Daycare</b>				<b>0</b>	<b>\$0.00</b>		

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony - On Track Pre-K (Village)</b>									
96401		Classroom			12/7/2012		69		\$0.00
Medium	Work In Progress				12/7/2012 5:01:38 PM				
Vega, David		Please empty and clean rooms 108, 110 and 111 at the Anthony Pre-K building. AVANCE and a SPED Diagnostician will be moving into them around December 12, 2012. For details or questions call Ralph Gallegos at 882-6921. Thanks.							
Rafael Gallegos									
95797					11/26/2012		80		\$0.00
Medium	Work In Progress				11/26/2012 3:48:45 PM				
Nunez, Arturo		CANOPY AT PRE K PLAY AREA NEEDS TO BE REPAIRED OR REPLACED, HAS A PRETTY GOOD SIZE TEAR ON TOP.							
Arturo Nunez									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>75</b>	<b>Total for Anthony - On Track Pre-K (Village)</b>			<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
95549					11/14/2012		92		\$0.00
Medium	Work In Progress			11/14/2012 3:48:20 PM					
Apodaca, Mario		AS PER MS. PEREZ , REQUESTING FOR WTAER FILTER BE INSTALLED FOR DOMESTIC WATER LINE.							
Arturo Nunez									
92466					9/6/2012		161		\$0.00
Medium	Work In Progress			9/6/2012 1:00:10 PM					
Orozco, Daniel		DISHWASHER WASH IN WASH MODE AND STOPPED WORKING. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									
92595					9/10/2012		157		\$0.00
Medium	Work In Progress			9/10/2012 8:13:09 AM					
Flores, Pete		400 A-E need oil, oil filter for 935							
Hector Villalobos									
95023					11/4/2012	11/12/2012	102		\$0.00
Medium	Work In Progress			11/4/2012 12:19:13 AM					
Nunez, Arturo		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
94354					10/19/2012		118		\$0.00
Medium	Work In Progress	SPED OFFICE		10/19/2012 9:00:43 AM					
Nunez, Arturo		MOVE OFFICE DESK FROM J. HERNANDEZ OFFICE TO DIAGNOSTICIANS OFFICE/MOVE DESK FROM DIAGNOSTICIAN OFFICE TO JULIE HERNANDEZ OFFICE (SEE JULIE HERNANDEZ OR MARGARET)							
Margaret Villalobos									
98302					2/7/2013		7		\$0.00
Medium	Work In Progress			2/7/2013 3:40:46 PM					
Nunez, Arturo		NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING.							
Arturo Nunez									
98210					2/5/2013		9		\$0.00
Medium	Work In Progress	SPED OFFICE		2/5/2013 3:02:42 PM					
Nunez, Arturo		MOVE FURNITURE IN DIAGNOSTICIAN OFFICE AS INSTRUCTED BY JULIE HERNANDEZ (DR. BLANCA ROLLE)							
Margaret Villalobos									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
98211					2/5/2013		9		\$0.00
Medium	Work In Progress	SPED OFFICE			2/5/2013 3:03:21 PM				
Nunez, Arturo	MOVE FILE CABINETS INTO DIAGNOSTICIAN ROOM (SEE JULIE HERNANDEZ)								
<u>Margaret Villalobos</u>									
98213					2/5/2013		9		\$0.00
Medium	Work In Progress	SPED OFFICE			2/5/2013 3:04:01 PM				
Nunez, Arturo	REMOVE OLD SHELVES FROM DIAGNOSTICIAN OFFICE (SEE JULIE HERNANDEZ)								
<u>Margaret Villalobos</u>									
98042					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:20 AM				
Nunez, Arturo	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98044					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:21 AM				
Nunez, Arturo	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96741					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:26 AM				
Nunez, Arturo	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96740					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:25 AM				
Nunez, Arturo	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96328					12/6/2012		70		\$0.00
Medium	Work In Progress	SPED OFFICE			12/6/2012 3:22:16 PM				
Nunez, Arturo	FINISH REMOVING CHALK BOARDS IN ROOM 120 (DISPOSE OF CHALKBOARDS) AND PAINT ROOM 120								
<u>Margaret Villalobos</u>									
96059					12/2/2012	12/10/2012	74		\$0.00
Medium	Work In Progress				12/2/2012 12:22:50 AM				
Nunez, Arturo	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
96999					1/8/2013		37		\$0.00
Medium	Work In Progress	SPED OFFICE		1/8/2013 8:58:52 AM					
Nunez, Arturo		PLEASE HAVE MAINTENANCE FINISH ROOM 120 REMOVE ALL CHALKBOARDS FROM THE HALL AND DISPOSE OF, PAINTING STILL NEEDS TO COMPLETED IN ORDER TO SET UP OFFICE SPACE FOR DIAGNOSTICIAN							
<u>Margaret Villalobos</u>									
98424					2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 3:55:09 PM					
Ontiveros, Guadalupe		NEED SOME ASSITANCE ON REPAIRING WATER LEAK ON PONDING AREA.							
<u>Arturo Nunez</u>									
93782					10/3/2012		134		\$0.00
Medium	Work In Progress	SPED OFFICE		10/3/2012 9:31:24 AM					
Lozoya, Manny		NEED TWO (2) KEYS FOR ROOM 120 (CANNOT READ NUMBER ON DOORKNOB)							
<u>Margaret Villalobos</u>									
94859					10/31/2012		106		\$0.00
Medium	Work In Progress			10/31/2012 3:38:26 PM					
Solis, Lorenzo		NEED SOME ASSITANCE ON TROUBLE SHOOTING HIGH DELTA WATER FOR KITCHEN, BURNED DOS NOT COME ON.							
<u>Arturo Nunez</u>									
98468					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 2:11:21 PM					
Lozoya, Manny		Asp Mr. Giovas, please issue a key to Rebecca, AE Manager for Old Cafeteria 1st thing tomorrow morning and she will open for mover.							
<u>Demetrious Giovas</u>									
96759					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:35 AM					
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
94458					10/22/2012		115		\$0.00
Medium	Work In Progress			10/22/2012 3:51:07 PM					
Appelzoller, Fred		NEED SOME ASSITANCE ON HOT WATER LINE LEAK INTO F.C.U. # 22.							
<u>Arturo Nunez</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
94680					10/26/2012		111		\$0.00
Medium	Work In Progress			10/26/2012 3:48:12 PM					
Sotelo, Enrique	NEED SOME ASSITANCE ON TROUBLE SHOOTING LIGHT FIXTURES ON PRE K. WORK ROOM, HALF OF THE IN ROOM ARE TURNED OFF								
<u>Arturo Nunez</u>									
97928					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 11:24:40 AM					
Sotelo, Enrique	Please install door bell check with site administration for location.								
<u>Richard Chavez</u>									
94404					10/22/2012		115		\$0.00
Medium	Work In Progress	SPED OFFICE		10/22/2012 7:33:07 AM					
Nunez, Arturo	REMOVE ALL CHALKBOARDS FROM DIAGNOSTICIAN ROOM AND PAINT								
<u>Margaret Villalobos</u>									
98510					2/14/2013		0		\$0.00
Medium	Work In Progress			2/14/2013 8:56:05 AM					
Lozoya, Manny	THE RIGHT DOOR THAT IS LOCATED NEXT TO THE NURSE'S OFFICE IS NOT CLOSING PROPERLY PLEASE CHECK (PLEASE SEE JESSICA IF YOU HAVE QUESTIONS)								
<u>Jessica Lopez</u>									
98043					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:21 AM					
Nunez, Arturo	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96779					1/6/2013		39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:43 AM					
Orozco, Daniel	Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97705	Main Building	Office			1/25/2013		20		\$0.00
Medium	Work In Progress			1/25/2013 2:27:32 PM					
Briones, Enrique	Please pick up 21 boxes of Math Adoption Samples.								
<u>Larry Martinez</u>									
97004	Main Building				1/8/2013		37		\$0.00
Medium	Work In Progress			1/8/2013 9:34:08 AM					
Appelzoller, Fred	water fountain on eastside of new addition does not turn off, keeps running								
<u>David Vega</u>									
							2/14/2013 11:25:49 AM		

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
96992	Main Building				1/8/2013		37		\$0.00
Medium	Work In Progress				1/8/2013 8:22:43 AM				
Sotelo, Enrique	some outside lights are not turning on in main building, and new addition, also street light coming in school entry not turning on								
<u>David Vega</u>									
96989	Main Building	Classroom			1/8/2013		37		\$0.00
Medium	Work In Progress				1/8/2013 8:19:24 AM				
Solis, Lorenzo	no heat in rooms 103, 104, 108, 111, speech therapy, and pre k office, upper primary (village)								
<u>David Vega</u>									
96354	Original Main				12/7/2012		69		\$0.00
Medium	Work In Progress				12/7/2012 8:31:03 AM				
Sotelo, Enrique	outside lights in old primary building and old cafeteria not turning on at night need to be checked out								
<u>David Vega</u>									
91739	Pump House				8/23/2012		175		\$0.00
Medium	Work In Progress				8/23/2012 9:52:41 AM				
Gonzalez, Salvador	upper primary pump house tank is leaking								
<u>Hector Villalobos</u>									
<b>Count: 34 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>59</b>			<b>Total for Anthony ES</b>	<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
96785					1/6/2013	1/27/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:46 AM					
Orozco, Daniel	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
94887					11/1/2012		105		\$0.00
Medium	Work In Progress			11/1/2012 10:52:35 AM					
Lozoya, Manny	put 2 key cores on muntin in the 2 lobbys								
<u>Jimmy Cortez</u>									
97927					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 10:17:48 AM					
Lozoya, Manny	MR MANNY LOZOYA SIR NEED THE KEY CORE INSTALL DOOR ROOM 138 IT IS MISSING THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
95266					11/7/2012		99		\$0.00
Medium	Work In Progress			11/7/2012 10:51:05 AM					
Briones, Enrique	PICK UP EMPTY BOXES THAT WERE USED TO STORE THE LIBRARY BOOKS								
<u>Jimmy Cortez</u>									
97929					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 11:26:29 AM					
Sotelo, Enrique	Please install door bell check with site administration for location.								
<u>Richard Chavez</u>									
96600					12/13/2012		63		\$0.00
Medium	Work In Progress			12/13/2012 3:03:45 PM					
Ontiveros, Joe	MR FRED APPELLOZER SIR THE WATER HEATER PORTABLE 155&156 SMALL WATER HEATER IS TO HOT NEED TO ADJUST HOT WATER HEADSTART KIDS THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
96760					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:36 AM					
Villalobos, David	Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
94300		Office			10/18/2012		119		\$0.00
Medium	Work In Progress	OFFICE		10/18/2012 9:41:51 AM					
Lozoya, Manny	OFFICE- FOR MANNY LOZOYA- I NEED A NEW NAME PLATE MARIBEL GAMBOA. THANK YOU								
<u>Maribel Chavez</u>									
2/14/2013 11:25:49 AM									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
95215					11/6/2012		100		\$0.00
Medium	Work In Progress				11/6/2012 8:20:10 AM				
Lozoya, Manny	MANNY LOZOYA PER MR VALTIERRA MANNY NEED TO INSTALL A DEAD-BOLT MAIN ENTRANCE TO LIBRARY FOR BETTER SECURITY THANK YOU SIR AND GOD BLESS								
Adan Duran									
95628					11/16/2012		90		\$0.00
Medium	Work In Progress				11/16/2012 2:06:10 PM				
Lozoya, Manny	NEED A LOCK AND KEY FOR THE GATE DRAINAGE POND AREA.								
Maribel Chavez									
96217					12/4/2012		72		\$0.00
Medium	Work In Progress				12/4/2012 8:19:14 AM				
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR NEED TO CLEAN AND DRESS UP PONDING AREA EAST SIDE BOTTOM FULL OF DIRT THANK YOU SIR AND GOD BLESS								
Adan Duran									
97940					1/31/2013		14		\$0.00
Medium	Work In Progress				1/31/2013 1:10:58 PM				
Duran, Adan	MR A-DURAN AS PER MR VALTIERRA NEED TO MAKE SIGNS FOR ALL ENTRANCE FOR PARENTS TO REPORT TO FRONT OFFICE 10 EA ALSO NEED TWO SIGNS NO PARKING ANY TIME THANK YOU SIR								
Adan Duran									
98321					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress				2/10/2013 12:20:31 AM				
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 13 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>59</b>		<b>Total for Berino ES</b>	<b>0</b>		<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
97331					1/15/2013		30		\$0.00
Medium	Work In Progress			1/15/2013 1:10:41 PM					
Ronquillo, Ruben	ATTN RUBEN RONQUILLO NEED NEW WINDOW FOR RM.509 CYLIDERS ARE BROKEN WINDOW WILL NOT LOCK OR STAY OPEN.								
Paul Quinones									
98332					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress			2/10/2013 12:20:37 AM					
Quinones, Paul	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
97218					1/13/2013	1/29/2013	32		\$0.00
Medium	Work In Progress			1/13/2013 12:16:09 AM					
Quinones, Paul	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
97904					1/30/2013		15		\$0.00
Medium	Work In Progress			1/30/2013 4:01:51 PM					
Quinones, Paul	play ground canvas ripped in half during wind storm								
Paul Quinones									
95651					11/16/2012		90		\$0.00
Medium	Work In Progress			11/16/2012 4:32:03 PM					
Martinez, Larry	relocate furniture from che to san miguel for storage.								
Paul Quinones									
95567					11/15/2012		91		\$0.00
Scheduled	Work In Progress			11/15/2012 10:34:17					
Quinones, Paul	Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You								
96359					12/7/2012		69		\$0.00
Medium	Work In Progress			12/7/2012 8:44:00 AM					
Quinones, Paul	reorder control ignitor for roof top heaters for restock.								
Paul Quinones									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
96360					12/7/2012		69		\$0.00
Medium	Work In Progress			12/7/2012 8:48:11 AM					
Quinones, Paul	requesting a spool of 3/8"rope								
Paul Quinones									
95472					11/13/2012		93		\$0.00
Medium	Work In Progress			11/13/2012 3:37:29 PM					
Quinones, Paul	BAD GAS VALVE IN ONE OF THE HEATERS IN 200 WING RM. 205,REQUESTING A COUPLE OF VALVES 1 FOR SPARE.								
Paul Quinones									
91935					8/28/2012		170		\$0.00
Medium	Work In Progress			8/28/2012 8:14:56 AM					
Quinones, Paul	INSTALL DRIP SECTION FOR PINE TREES IN BETWEEN E-WING AND THE 400 WING FOR WATERING.WATERING HAS BEEN W/ THE WATER HOSE.								
Paul Quinones									
98342					2/11/2013		3		\$0.00
Medium	Work In Progress			2/11/2013 8:45:59 AM					
Quinones, Paul	REQUESTING PVC PIPE,AND 1/2" PVC FITTINGS FOR A/C WATER LINE FOR WINGS 400,AND E-WING								
Paul Quinones									
98343					2/11/2013		3		\$0.00
Medium	Work In Progress			2/11/2013 8:51:10 AM					
Quinones, Paul	TRAILER LOADED WITH UNWANTED FURNITURE,AND TRASH UNLOAD P/P DUMPSTER.								
Paul Quinones									
98111					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:49 AM					
Quinones, Paul	Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
98113					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:50 AM					
Quinones, Paul	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
94038					10/11/2012		126		\$0.00
High	Work In Progress			10/11/2012 7:27:40 AM					
Quinones, Paul	new furniture came in and needs to be assembled. thank you								
Michael Munoz									
97589					1/23/2013		22		\$0.00
Medium	Work In Progress			1/23/2013 11:13:35 AM					
Quinones, Paul	REQUESTING REPAIR KITS TANK TO BOWL KIT FLUID MASTER PRO 45 FILL VALVES WAX RING FOR RESTOCK @ CHE								
Paul Quinones									
98340					2/11/2013		3		\$0.00
Medium	Work In Progress			2/11/2013 8:40:26 AM					
Carrasco, Danny	ATTN;DANNY CARRASCO 500'VYNAL BASE BOARD STORED BEHIND AUTO SHOP ON A PALLET.								
Paul Quinones									
94552					10/24/2012		113		\$0.00
Medium	Work In Progress			10/24/2012 3:47:10 PM					
Ontiveros, Guadalupe	requesting dump truck to remove dirt pile mixed with trash on the north west fence line.i have the skid loader to load into dump truck.as per mrs.pargas request the principle.								
Paul Quinones									
96863					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:24 AM					
Quinones, Paul	Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
98508					2/14/2013		0		\$0.00
Medium	Work In Progress			2/14/2013 7:56:03 AM					
Ontiveros, Guadalupe	water valves leaking shut off both water valves in front of school in hot box								
Paul Quinones									
98339					2/11/2013		3		\$0.00
Medium	Work In Progress			2/11/2013 8:30:32 AM					
Quinones, Paul	REQUESTING PAINT PRINCIPLE REQUESTING HALLWAY,AND BATHROOMS TO BE PAINTED.								
Paul Quinones									
2/14/2013 11:25:49 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
95597					11/15/2012		91		\$0.00
Medium	Work In Progress			11/15/2012 3:35:10 PM					
Quinones, Paul	need to paint yellow markings on front of school and fire hydrant no parking lane,requesting oilbase paint.								
Paul Quinones									
95831					11/27/2012		79		\$0.00
Medium	Work In Progress			11/27/2012 3:17:14 PM					
Quinones, Paul	need to paint behind e-wing requesting paint								
Paul Quinones									
92134					8/31/2012		167		\$0.00
Medium	Work In Progress			8/31/2012 12:24:24 AM					
Quinones, Paul	Monthly - Chaparral ES A-16 Exh Fan (Semi Annual) - Refer to PM schedule details.								
Margret Villalobos									
95739					11/20/2012		86		\$0.00
Medium	Work In Progress			11/20/2012 3:50:37 PM					
Solis, Lorenzo	REQUESTING LIMIT SWITCHES FOR WALL HEATERS								
Paul Quinones									
96758					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:35 AM					
Villalobos, David	Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
95374					11/9/2012		97		\$0.00
Medium	Work In Progress			11/9/2012 2:19:25 PM					
Ontiveros, Joe	requesting new valves for a/c water shut off for winter shut down in wing 400.thanks								
Paul Quinones									
95830					11/27/2012		79		\$0.00
Medium	Work In Progress			11/27/2012 3:15:19 PM					
Ontiveros, Joe	outside water fountain leaking from behind wall in front of e-wing.								
Paul Quinones									
98019					2/1/2013		13		\$0.00
Medium	Work In Progress			2/1/2013 4:06:51 PM					
Ontiveros, Joe	need to cap off 1/2" copper water line,and replace water valve will not shut off water.in wing 100								
Paul Quinones									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
94654					10/26/2012		111		\$0.00
Medium	Work In Progress			10/26/2012 2:50:41 PM					
Sotelo, Enrique	no power to heating units in main wing,chk breakers all are on checked for loose wires.								
Paul Quinones									
97936					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 11:59:08 AM					
Vallejo, Albert	Please install door bell, check with site administration for location.								
Richard Chavez									
97957					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 3:50:28 PM					
Gonzalez, Salvador	NEED METAL FRAME TO REPLACE THE WOOD FRAME,AND A 1/16 DIAMOND PLATE TO COVER THE WATER SUPPLY AND PLUMBING TO THE WATER FOUNTAIN FOR PROTECTION.								
Paul Quinones									
98472					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 2:23:16 PM					
Lozoya, Manny	REQUESTING DOOR AND DOOR FRAME TO SECURE SCHOOL SUPPLIES AND FOR STORAGE USE.								
Paul Quinones									
98112					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:49 AM					
Quinones, Paul	Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
91936					8/28/2012		170		\$0.00
Medium	Work In Progress			8/28/2012 8:33:17 AM					
Munoz, Michael	REQUESTING NEW ROLL GATES FOR FRONT ENTRANCES								
Paul Quinones									
98507					2/14/2013		0		\$0.00
Medium	Work In Progress			2/14/2013 7:49:59 AM					
Ronquillo, Ruben	need gasoline for work truck #123 fill tank								
Paul Quinones									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
96356					12/7/2012		69		\$0.00
Medium	Work In Progress			12/7/2012 8:40:15 AM					
Quinones, Paul	requesting transition strip to repair carpet to tile edges in class rooms.								
<u>Paul Quinones</u>									
97638					1/24/2013		21		\$0.00
Medium	Work In Progress			1/24/2013 10:29:42 AM					
,	NEED TO REPLACE COVEBASE IN (2) HALLWAYS - LABOR ONLY, WE HAVE THE MATERIAL.								
<u>Jesus Estrada</u>									
96926					1/7/2013		38		\$0.00
Medium	Work In Progress			1/7/2013 11:46:06 AM					
Estrada, Jesus	CARPET NEEDS TO BE REPLACED IN PORTABLE #572								
<u>Jesus Estrada</u>									
98114					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:50 AM					
Quinones, Paul	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96861					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:23 AM					
Quinones, Paul	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96945	Main Building	Classroom			1/7/2013		38		\$0.00
Medium	Work In Progress	gym		1/7/2013 2:33:45 PM					
Lozoya, Manny	need keys for coaches N69 please see Nava and Flores								
<u>Jennifer Corral</u>									
97031	Main Building	Hallway/Corridor			1/8/2013		37		\$0.00
Medium	Work In Progress	whole school		1/8/2013 2:14:58 PM					
Lozoya, Manny	main doors going to protables need to be rekeyed so teachers may open with their keys. See Administration								
<u>Jennifer Corral</u>									
98186	Main Building				2/5/2013		9		\$0.00
Medium	Work In Progress			2/5/2013 9:59:10 AM					
Quinones, Paul	1st sink in the boys restroom is loose. needs to be re-secure and re-caulk. could you re-caulk the rest as needed. thank you								
<u>Michael Munoz</u>									

2/14/2013 11:25:50 AM

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

Count: 44 Work Orders      Avg. Age of WO's 51      Total for Chaparral ES      0      \$0.00



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
96784					1/6/2013		39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:45 AM					
Orozco, Daniel	Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97305	A-Wing	Classroom			1/15/2013		30		\$0.00
Medium	Work In Progress			1/15/2013 8:54:25 AM					
Lozoya, Manny	Mrs. Vega's door is hard to open with key. She is located in the counselors area in front office.								
<u>Mireya Meza</u>									
98410	A-Wing	Hallway/Corridor			2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 3:38:58 PM					
Ortiz, Alfredo	Need to replace 2 Exit sign, someone hit them and broke them.								
<u>Alfredo Ortiz</u>									
97472	A-Wing	Office			1/17/2013		28		\$0.00
Medium	Work In Progress			1/17/2013 3:52:19 PM					
Lozoya, Manny	We need a CHS key for our permanent security guard. (Mireya Meza)					1/23/13 - ASP CHUY, CHECK STATUS ON KEY. ASP JESSIE/CHUY, NEED 2 KEYS, ASP MIREYA - MANNY ISSUED 2 KEYS TO HER.			
<u>Mireya Meza</u>									
96529	A-Wing	Hallway/Corridor			12/12/2012		64		\$0.00
Medium	Work In Progress			12/12/2012 8:57:47 AM					
Lozoya, Manny	Outer door lock will not open with key. Door is 3rd outer door from nurse's office, between CAP class and ISS class. (Ms. Lopez)								
<u>Mireya Meza</u>									
96907	A-Wing	Cafeteria			1/7/2013		38		\$0.00
Medium	Work In Progress			1/7/2013 8:42:27 AM					
Lozoya, Manny	Cafeteria doors lach don't work 3 doors.								
<u>Alfredo Ortiz</u>									
98262	A-Wing				2/6/2013		8		\$0.00
Medium	Work In Progress			2/6/2013 12:34:08 PM					
Lara, Ralph	Need to fix or replace door lock can't open with key.								
<u>Alfredo Ortiz</u>									
98146	A-Wing	Athletic Field			2/4/2013		10		\$0.00
Medium	Work In Progress			2/4/2013 10:24:11 AM					
Valdez, Pedro	Will you please move the softball storage shed to the left field side. (Coach E. Guerrero)								
<u>Mireya Meza</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
98147	A-Wing	Athletic Field			2/4/2013		10		\$0.00
Medium	Work In Progress			2/4/2013 10:26:26 AM					
Valdez, Pedro	The softball outfield fence on the left side needs to be fixed. It is lifted and balls go right under it. (Coach E. Guerrero)								
<u>Mireya Meza</u>									
97658	A-Wing				1/24/2013		21		\$0.00
Medium	Work In Progress			1/24/2013 3:22:34 PM					
Ortiz, Alfredo	Need to replace filters and clean units. A-wing roof top.								
<u>Alfredo Ortiz</u>									
98261	D-Wing	Classroom			2/6/2013		8		\$0.00
Medium	Work In Progress			2/6/2013 12:29:43 PM					
Lara, Ralph	Need to make a set of keys for teacher in science room for emergency shut-off panel. To reset gas valves.								
<u>Alfredo Ortiz</u>									
96585	D-Wing	Classroom			12/13/2012		63		\$0.00
Medium	Work In Progress			12/13/2012 11:39:45					
Solis, Lorenzo	Having problem with D-Sped heater								
<u>Alfredo Ortiz</u>									
98287	D-Wing	Classroom			2/7/2013		7		\$0.00
Medium	Work In Progress			2/7/2013 12:56:47 PM					
Ortiz, Alfredo	Need to unclog all gas valves and tighten all faucets in science room students work staitons.								
<u>Alfredo Ortiz</u>									
97529	E-Wing	Classroom			1/22/2013		23		\$0.00
Medium	Work In Progress			1/22/2013 8:55:00 AM					
Ortiz, Alfredo	Need to order and replace round electrical cover and base, it is broken and a trip hazard.								
<u>Alfredo Ortiz</u>									
91888	G-Wing	Restroom (Boys)			8/27/2012		171		\$0.00
Medium	Work In Progress			8/27/2012 11:27:10 AM					
Sotelo, Enrique	hand dryer broke								
<u>Jesus Urquidi</u>									
97692	Q-Wing	Classroom			1/25/2013		20		\$0.00
Medium	Work In Progress			1/25/2013 8:25:37 AM					
Ortiz, Alfredo	Requesting the interance to the shop be painted.								
<u>Alfredo Ortiz</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
96530	Q-Wing	Classroom			12/12/2012		64		\$0.00
Medium	Work In Progress				12/12/2012 9:36:37 AM				
Solis, Lorenzo		In Q-7 having problem with heaters							
<u>Alfredo Ortiz</u>									
98144	Q-Wing	Mechanical			2/4/2013		10		\$0.00
Medium	Work In Progress				2/4/2013 9:51:40 AM				
Ontiveros, Joe		need to repair or replace circulateing hot water pump not working.							
<u>Alfredo Ortiz</u>									
98453	Q-Wing	Classroom			2/13/2013		1		\$0.00
Medium	Work In Progress				2/13/2013 12:09:49 PM				
Sotelo, Enrique		Need to install new air compresor for mechanic shop. Need new electrical set up.							
<u>Alfredo Ortiz</u>									
98199	Q-Wing	Classroom			2/5/2013		9		\$0.00
Medium	Work In Progress				2/5/2013 12:36:11 PM				
Ortiz, Alfredo		Need to replace filters in Q, and R-buildings.							
<u>Alfredo Ortiz</u>									
97691	Q-Wing	Classroom			1/25/2013		20		\$0.00
Medium	Work In Progress				1/25/2013 8:17:46 AM				
Ortiz, Alfredo		Need to order and repair air compresor in Q-2 Construction room.							
<u>Alfredo Ortiz</u>									
94898	R-Wing	Classroom			11/1/2012		105		\$0.00
Medium	Work In Progress				11/1/2012 11:59:27 AM				
Lozoya, Manny		Door handle to storeroom in R1 has broken. Needs to be replaced. (Mr. Gabaldon)							
<u>Mireya Meza</u>									
97434	R-Wing	Classroom			1/16/2013		29		\$0.00
Medium	Work In Progress				1/16/2013 4:07:43 PM				
Sotelo, Enrique		Room R1 needs to have lights replaced. (Mr. Gabaldon)							
<u>Mireya Meza</u>									
95765	R-Wing	Restroom (Boys)			11/26/2012		80		\$0.00
Medium	Work In Progress				11/26/2012 12:19:37				
Ontiveros, Joe		nEED TO REPLACE 1 FAUSET IN BOYSRESTROOM.							
<u>Alfredo Ortiz</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
97478	Field House	Mechanical			1/18/2013		27		\$0.00
Medium	Work In Progress				1/18/2013 9:07:17 AM				
Solis, Lorenzo		Need to replace Presure switch and Hot Surfase Igniter. also order extra parts to have in stock.							
<u>Alfredo Ortiz</u>									
98458	Field House				2/13/2013		1		\$0.00
Medium	Work In Progress				2/13/2013 12:39:16 PM				
Ortiz, Alfredo		Need to order filters and replace on A/C units in field house and Q, and R-wing also repair drain lines.							
<u>Alfredo Ortiz</u>									
89726	Field House	Athletic Field			7/10/2012		219		\$0.00
Medium	Work In Progress				7/10/2012 4:23:59 PM				
Valdez, Pedro		We need 8 sets of tires attached to the soccer goals to make them mobile.							
<u>Mireya Meza</u>									
93777	Field House	Athletic Field			10/3/2012		134		\$0.00
Medium	Work In Progress				10/3/2012 7:29:03 AM				
Gonzalez, Salvador		Please put permanent shade in socccer fields. (Arnold Orozco)							
<u>Mireya Meza</u>									
96443	Pre-K				12/10/2012		66		\$0.00
Medium	Work In Progress				12/10/2012 3:07:05 PM				
Gonzalez, Salvador		Need to repaid gate door, lach broken.							
<u>Alfredo Ortiz</u>									
96780					1/6/2013		39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:43 AM				
Orozco, Daniel		Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
98038					2/3/2013		11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:18 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
96352		Pump House			12/7/2012		69		\$0.00
Medium	Work In Progress				12/7/2012 7:58:18 AM				
Munoz, Michael		Having problom with the fire pump							
<u>Alfredo Ortiz</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
97357		Parking Lot			1/15/2013		30		\$0.00
Medium	Work In Progress			1/15/2013 3:43:06 PM					
Munoz, Michael	Need to install new gates with signs for traffic controll exiting noth parking lot.								
Alfredo Ortiz									
97252					1/14/2013		31		\$0.00
Medium	Work In Progress			1/14/2013 12:40:24 PM					
Munoz, Michael	Need to send someone to build a wall to keep sand from collecting in front of healthroom.								
Alfredo Ortiz									
93161					9/24/2012		143		\$0.00
Medium	Work In Progress			9/24/2012 9:14:21 AM					
Carbajal, Jimmy	auto scrubber sn 8000062994 scrub brush does not turn also loosing power very quickly.					11/30/12 - ASP JIMMY, NEEDS TO SCHEDULE AND PICK UP FOR SERVICE			
Jesus Urquidi									
98039					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:19 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
89952					7/18/2012		211		\$0.00
Medium	Work In Progress			7/18/2012 10:01:25 AM					
Carbajal, Jimmy	auto scrubber nss SR. 232312A 36169435 does not pick up water.					11/30/12 - JIMMY, NEEDS TO SCHEDULE AND PICK UP MACHINE.			
Jesus Urquidi									
98246		Athletic Field			2/6/2013		8		\$0.00
High	Work In Progress			2/6/2013 8:47:00 AM					
Valdez, Pedro	need to fix 4" water line at baseball field.								
Guadalupe Ontiveros									
96587		Parking Lot			12/13/2012		63		\$0.00
Medium	Work In Progress			12/13/2012 11:46:18					
Gonzalez, Salvador	I also need a metal stop bar that comes from the end of the fence that also includes a seperate pole so that driving access can be denied because the students and parents are cutting off the busses as they are driving off. Please see Lupe Quinones for location.								
Mireya Meza									
90833					8/6/2012		192		\$0.00
Medium	Work In Progress			8/6/2012 10:03:59 AM					
Gonzalez, Salvador	Need to weld Soccer Goals								
Guadalupe Ontiveros									
2/14/2013 11:25:50 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
92673		Cafeteria			9/11/2012		156		\$0.00
Medium	Work In Progress			9/11/2012 11:14:39 AM					
Gonzalez, Salvador	Need to create some kind of shade for the students at the sitting area. (Lupe Quinones)								
<u>Mireya Meza</u>									
96024		Athletic Field			11/30/2012		76		\$0.00
Medium	Work In Progress			11/30/2012 3:38:16 PM					
Gonzalez, Salvador	please order material for install of new scoreboards .baseball / softball.thank you								
<u>Michael Munoz</u>									
96183		Hallway/Corridor			12/3/2012		73		\$0.00
Medium	Work In Progress			12/3/2012 2:40:58 PM					
Sotelo, Enrique	Need to replace 10 BALLAST Magnetic 70w Metal Halide.								
<u>Alfredo Ortiz</u>									
97348		Parking Lot			1/15/2013		30		\$0.00
Medium	Work In Progress			1/15/2013 3:10:32 PM					
Sotelo, Enrique	Need to replace light bulbs on parking lot. MH400/U/ED28 and ballast								
<u>Alfredo Ortiz</u>									
98358		Gym			2/11/2013		3		\$0.00
Medium	Work In Progress			2/11/2013 2:55:57 PM					
Sotelo, Enrique	Need to replace Ballast and light bulbs ing GYM. Magnetic Ballast 277 V M 750/Multi-PS Bulbs:MS750BU/PS Metal Halide.								
<u>Alfredo Ortiz</u>									
98435					2/13/2013		1		\$0.00
Medium	Work In Progress	LINE LOCATE		2/13/2013 8:32:23 AM					
Sotelo, Enrique	Need to line locate around baseball fields area marked in white paint for Lynco Electric. Contact: Raylin Wilcox 575-523-9066								
<u>Alfredo Holguin</u>									
97035		Athletic Field			1/8/2013		37		\$0.00
Medium	Work In Progress			1/8/2013 3:23:26 PM					
Castillo, Carlos	Requesting power to center area of Chaparral baseball fields for outdoor events.								
<u>Carlos Castillo</u>									
96016		Athletic Field			11/30/2012		76		\$0.00
Medium	Work In Progress			11/30/2012 3:23:44 PM					
Castillo, Carlos	power will be needed for new scoreboards for base ball/softball. Please contact lynco for quote. thank you								
<u>Michael Munoz</u>									

2/14/2013 11:25:50 AM

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
97888		Cafeteria			1/30/2013		15		\$0.00
Medium	Work In Progress			1/30/2013 3:26:03 PM					
Ontiveros, Joe	Need to replace circulating pump in Kitchen mech. room. Domestic Hot water.								
<u>Alfredo Ortiz</u>									
92674		Cafeteria			9/11/2012		156		\$0.00
Medium	Work In Progress			9/11/2012 11:15:45 AM					
Ontiveros, Joe	Need a water fountain for the students in the same area where tables are needed. (Lupe Quinones)								
<u>Mireya Meza</u>									
98436					2/13/2013		1		\$0.00
Medium	Work In Progress	LINE LOCATE		2/13/2013 8:33:39 AM					
Ontiveros, Joe	Need to line locate around baseball fields area marked in white paint for Lynco Electric. Contact: Raylin Wilcox 575-523-9066								
<u>Alfredo Holguin</u>									
98037					2/3/2013	2/6/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:18 AM					
Ortiz, Alfredo	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98438		Parking Lot			2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 8:35:29 AM					
Villalobos, David	The domestic, irrigation , and fire protection backflow preventers all were discharging lots of water through the relief valves back in mid December, Horizon mech. was sent to correct the problem and finished in February (2/7/2013).								
<u>David Villalobos</u>									
90843					8/6/2012		192		\$0.00
Medium	Work In Progress			8/6/2012 11:26:25 AM					
Lozoya, Manny	We need the following keys made for CHS. Room A-108, #86 (6), light keys (10), key to staff room in library, key for trophy case in cafeteria and overhead in Q building.								
<u>Mireya Meza</u>									
96629		Classroom			12/14/2012		62		\$0.00
Medium	Work In Progress			12/14/2012 10:02:17					
Lozoya, Manny	We need a new master key for our custodian. He is having trouble opening some doors. The key might be worn out or bent. Please replace. (Mireya Meza)								
<u>Mireya Meza</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
96668					12/16/2012		60		\$0.00
Medium	Work In Progress				12/16/2012 12:16:10				
Valdez, Pedro		Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
98360		Cafeteria			2/11/2013		3		\$0.00
Medium	Work In Progress				2/11/2013 2:59:34 PM				
Ortiz, Alfredo		Need to replace light bulbs in Cafeteria. Also order Bulbs.							
<u>Alfredo Ortiz</u>									
96723					1/6/2013		39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:16 AM				
Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump Eng (Quarterly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
98041					2/3/2013	3/6/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:20 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
98040					2/3/2013		11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:19 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
98036					2/3/2013		11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:17 AM				
Ortiz, Alfredo		Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
93934					10/9/2012		128		\$0.00
Medium	Work In Progress				10/9/2012 10:33:13 AM				
Flores, Pete		Truck is trembling alot and have a hard time starting it.							
<u>Jesus Urquidi</u>									
92677					9/11/2012		156		\$0.00
Medium	Work In Progress				9/11/2012 11:25:49 AM				
Apodaca, Mario		Need to install base to mount pump hoist in amphitheater lift station.							
Albert Vallejo									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
98100					2/3/2013		11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:44 AM				
Apodaca, Mario		Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
96586		Parking Lot			12/13/2012		63		\$0.00
Medium	Work In Progress				12/13/2012 11:43:18				
Ortiz, Alfredo		We need several signs to be placed at different locations of the school. Please see Lupe Quinones for signs.							
Mireya Meza									
<b>Count: 65 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>54</b>	<b>Total for Chaparral HS</b>			<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
92678					9/11/2012		156		\$0.00
Medium	Work In Progress			9/11/2012 11:27:08 AM					
Apodaca, Mario	I would like to have Mario come out to help me work on the irrigation booster pump.								
<u>Albert Vallejo</u>									
93936					10/9/2012		128		\$0.00
Medium	Work In Progress			10/9/2012 10:43:47 AM					
Flores, Pete	as per our meeting , please assign vehicle # 121 to albert. thank you								
<u>Michael Munoz</u>									
98029					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:14 AM					
Vallejo, Albert	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98034					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:17 AM					
Vallejo, Albert	Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98033					2/3/2013	3/6/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:16 AM					
Vallejo, Albert	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98030					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:15 AM					
Vallejo, Albert	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95569					11/15/2012		91		\$0.00
Scheduled	Work In Progress			11/15/2012 10:37:08					
Vallejo, Albert	Ms. Sherri with CLEARresult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You								

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
96729					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:20 AM					
Vallejo, Albert		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
94910		Athletic Field			11/1/2012		105		\$0.00
Medium	Work In Progress			11/1/2012 3:17:23 PM					
Ontiveros, Guadalupe		need two backstops to be built and installed for baseball.							
Guadalupe Ontiveros									
96486					12/11/2012		65		\$0.00
Medium	Work In Progress			12/11/2012 3:21:43 PM					
Lozoya, Manny		Key to room 106 is not working properly							
Albert Vallejo									
98031					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:15 AM					
Vallejo, Albert		Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
97223					1/13/2013	1/29/2013	32		\$0.00
Medium	Work In Progress			1/13/2013 12:16:12 AM					
Gonzalez, Robert		Monthly - QRTLY BLDG INSP REPORTS (CM) - Refer to PM schedule details.							
Margret Villalobos									
89871					7/16/2012		213		\$0.00
Medium	Work In Progress			7/16/2012 4:19:52 PM					
Vallejo, Albert		Re-paint Fire lanes with red GLOSS paint.							
Albert Vallejo									
98035					2/3/2013	2/6/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:17 AM					
Vallejo, Albert		Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
96771					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:40 AM					
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral MS</b>									
95176					11/5/2012		101		\$0.00
Medium	Work In Progress				11/5/2012 2:14:02 PM				
Gonzalez, Salvador	Please fabricate ice machine stand in Athletics locker room.								
<u>Albert Vallejo</u>									
98032					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:16 AM				
Vallejo, Albert	Monthly - Chaparral MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98355					2/11/2013		3		\$0.00
Medium	Work In Progress				2/11/2013 2:34:47 PM				
Ronquillo, Ruben	Please deliver unleaded fuel for vehicle #81.								
<u>Albert Vallejo</u>									
96786					1/6/2013	1/27/2013	39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:46 AM				
Orozco, Daniel	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93237	Main Building	Classroom			9/25/2012		142		\$0.00
Medium	Work In Progress	308			9/25/2012 3:11:29 PM				
Lozoya, Manny	Teacher would like locks put on cabinets								
<u>Gidget Mora</u>									
97923	Main Building	Classroom			1/31/2013		14		\$0.00
Medium	Work In Progress	p-4			1/31/2013 9:41:00 AM				
Vallejo, Albert	A set of wires has come loose behind teachers desk. They need to be secured.								
<u>Gidget Mora</u>									
96007	Main Building	Office			11/30/2012		76		\$0.00
Medium	Work In Progress				11/30/2012 2:39:01 PM				
Vallejo, Albert	Please replace a file that is smashed in pieces at the nurse's office.								
<u>Gidget Mora</u>									
93243	Main Building	Restroom (Boys)			9/25/2012		142		\$0.00
Medium	Work In Progress				9/25/2012 3:21:37 PM				
Vallejo, Albert	Please repair the hole in the boys restroom.								
<u>Gidget Mora</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
97637	Main Building	Classroom			1/24/2013		21		\$0.00
Medium	Work In Progress			1/24/2013 10:18:53 AM					
Vallejo, Albert	weather stripping needed around doors in kiln room								
<u>Gidget Mora</u>									
96911	Main Building	Classroom			1/7/2013		38		\$0.00
Medium	Work In Progress	104		1/7/2013 8:47:55 AM					
Vallejo, Albert	Window shades no longer functional. Please Replace								
<u>Gidget Mora</u>									
98399	Main Building	Classroom			2/12/2013		2		\$0.00
Medium	Work In Progress	100		2/12/2013 11:05:37 AM					
Vallejo, Albert	Please set up smartboard								
<u>Gidget Mora</u>									
98345	Main Building	Classroom			2/11/2013		3		\$0.00
Medium	Work In Progress	208		2/11/2013 9:56:13 AM					
Vallejo, Albert	Air conditioner/heater filter needs replacing								
<u>Gidget Mora</u>									
98354	Main Building	Classroom			2/11/2013		3		\$0.00
Medium	Work In Progress	309		2/11/2013 2:31:39 PM					
Vallejo, Albert	Please install smartboard								
<u>Gidget Mora</u>									
<b>Count: 28 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>55</b>	<b>Total for Chaparral MS</b>			<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
<b>Location:</b>		<b>Charter School</b>							
96216		Parking Lot			12/4/2012		72		\$0.00
Medium	Work In Progress				12/4/2012 8:04:07 AM				
Villalobos, David	Constant drip on 8" fire protection bfp need to replace check valves								
David Villalobos									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>72</b>	<b>Total for Charter School</b>		<b>0</b>	<b>\$0.00</b>	

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Pride</b>							
95455		Office			11/13/2012		93		\$0.00
Medium	Work In Progress	RESTROOM			11/13/2012 1:10:10 PM				
Appelzoller, Fred	WHEN TOILET IS FLUSHED WATER COMES OR BUBBLES BACK UP. SEPTIC TANK WAS CLEAN OUT 10/26/12								
<u>David Acosta</u>									
97976		Pump House			2/1/2013		13		\$0.00
Medium	Work In Progress	CUST. OFFICE			2/1/2013 8:25:36 AM				
Castillo, Carlos	NEED TO REPLACE LIGHT SWITCH NOT WORKING RROPERLY								
<u>David Acosta</u>									
97975		Portables			2/1/2013		13		\$0.00
Medium	Work In Progress	ROOM 7			2/1/2013 8:22:36 AM				
Castillo, Carlos	NEED TO REPLACE THE CLASSROOM LIGHT SWITCH.								
<u>David Acosta</u>									
97762		Portables			1/28/2013		17		\$0.00
Medium	Work In Progress	ROOM 5			1/28/2013 10:54:32 AM				
Castillo, Carlos	TWO LIGHT FIXTURES BALLAST NEED TO BE REPLACE.								
<u>David Acosta</u>									
97594		Parking Lot			1/23/2013		22		\$0.00
Medium	Work In Progress				1/23/2013 1:50:43 PM				
Castillo, Carlos	ONE POLE NIGHT LIGHT BY THE LUNCH TABLES IS BURN OUT. NEED LIGHT BULB REPLACED								
<u>David Acosta</u>									
93272		Portables			9/26/2012		141		\$0.00
Medium	Work In Progress				9/26/2012 9:14:50 AM				
Ontiveros, Guadalupe	please assit with the trenching for a new electrical line to the portable this friday 9-28-12.thank you								
<u>Michael Munoz</u>									
98450					2/13/2013		1		\$0.00
Medium	Work In Progress				2/13/2013 11:20:01 AM				
Diaz, Sebastian	Sanchez Portable - touch up painting and caulking of baseboard.								
Michael Munoz									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Pride</b>							
92503		Portables			9/6/2012		161		\$0.00
Medium	Work In Progress			9/6/2012 4:08:35 PM					
Ambriz, Jose	desert pride will be recieve a portable on 9-07-12. please provide a new window evaporative cooler and a new wall heater w/ fan. thank you								
<u>Michael Munoz</u>									
96856					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:20 AM					
Aguilar, Patricio	Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98252					2/6/2013		8		\$0.00
Medium	Work In Progress			2/6/2013 10:21:35 AM					
Acosta, David	NEED TO CLEAN WINDOWS AND WINDOW SEALS IN MR. SANCHEZ NEW PORTABLE								
<u>Jesus Estrada</u>									
98463		Portables			2/13/2013		1		\$0.00
Medium	Work In Progress	ART ROOM		2/13/2013 1:38:23 PM					
Lara, Ralph	NEED ONE KEY TO DOOR FOR TEACHER.								
<u>David Acosta</u>									
97760		Portables			1/28/2013		17		\$0.00
Medium	Work In Progress	1,2,3,4,6.		1/28/2013 10:35:12 AM					
Gonzalez, Salvador	THE STEPS & RAMPS TOO PORTABLES (ROOM 1,2,3,4,6) NEEDS TO BE SAND BLASTED OR SOME METHOD OF REMOVING RUST AND OLD CHIPPING PAINT BEFORE REPAINTING								
<u>David Acosta</u>									
98049					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:23 AM					
Acosta, David	Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98050					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:24 AM					
Acosta, David	Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Pride</b>							
98505					2/14/2013		0		\$0.00
Medium	Work In Progress			2/14/2013 12:21:41 AM					
Sanchez, Raul	Monthly - Desert Pride - Water Filters - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98124					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:54 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92513					9/7/2012		160		\$0.00
Medium	Work In Progress			9/7/2012 9:19:09 AM					
Estrada, Jesus	PORTABLE FROM SAN MIGUEL WILL BE RELOCATED TO DESERT PRIDE. NEED TO HAVE CARPET REPLACED.								
	9/7/12 REVISED - NEED TO REPLACE CARPET WITH LINOLEUM AND 4" COVE BASE								
<u>Michael Munoz</u>									
98048					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:23 AM					
Acosta, David	Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97646		Gym			1/24/2013		21		\$0.00
Medium	Work In Progress	Boxing Gym		1/24/2013 2:03:46 PM					
Ronquillo, Ruben	The following gym equipment needs repair: Sports Art Elliptical- shrouds, cup holder and extension cords need to be replaced.								
	Treadmill Endurance-site rails, cover/motor needs to be replaced.								
	Precor Treadmill-motor belt needs to be replaced								
	Serial #'s 0068567/006344								
<u>Yvette Cortez</u>									
96477		Classroom			12/11/2012		65		\$0.00
Medium	Work In Progress	ROOM 9		12/11/2012 12:15:40					
Lara, Ralph	MAY NEED TO REPLACE WOOD DOOR FRAME. (AS SPLITS OR CRACKS) AND SCREWS TO HINGES KEEP COMING LOOSE.								
<u>David Acosta</u>									
<b>Count: 20 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>41</b>	<b>Total for Desert Pride</b>		<b>0</b>	<b>\$0.00</b>	

2/14/2013 11:25:50 AM

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
98285					2/7/2013		7		\$0.00
Medium	Work In Progress				2/7/2013 8:35:55 AM				
Gonzalez, Salvador	Need to replace or repair bowed metal diamond plate to bus turnaround, and also grind sharp edges to all diamond plates in the bus turnaround.								
Johnny Acuna									
98072					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:33 AM				
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
98240		Custodial			2/6/2013		8		\$0.00
Medium	Work In Progress				2/6/2013 8:12:17 AM				
Carbajal, Jimmy	Jimmy buenos dias necesito 3 bolsas de aspiradora por favor gracias								
Laura Sandoval									
96267					12/5/2012		71		\$0.00
Medium	Work In Progress				12/5/2012 8:31:37 AM				
Carrasco, Danny	Need to borrow scissor lift to grease and service heating units to Cafeteria.								
Johnny Acuna									
94101					10/12/2012		125		\$0.00
Medium	Work In Progress				10/12/2012 11:06:14				
Carrasco, Danny	Need to borrow scissor lift to service cafeteria heating units and replace batteries to cafeteria emergency light kits.								
Johnny Acuna									
95306		Custodial			11/8/2012		98		\$0.00
Medium	Work In Progress				11/8/2012 7:10:35 AM				
Estrada, Jesus	Chuy buenos dias si puede revisar por favor los portables Num.405 y 406 pues la alfombra que pusieron se esta desilando gracias								
Laura Sandoval									
95308		Custodial			11/8/2012		98		\$0.00
Medium	Work In Progress				11/8/2012 7:28:35 AM				
Estrada, Jesus	Chuy por favor puede revisar el piso de los portables Num. 414 y 415 el tile se esta quebrando en pedasitos , Jhonny ya los a remplasado y se buelben a quebrar muchas gracias que tenga buen dia								
Laura Sandoval									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
96787					1/6/2013	1/27/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:46 AM					
Orozco, Daniel	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97978					2/1/2013		13		\$0.00
Medium	Work In Progress			2/1/2013 8:48:42 AM					
Villalobos, Margret	Principal requesting for Exterminator to spray whole kindergarten classrooms for cocharoaches.		Waiting on price quote						
<u>Johnny Acuna</u>									
92723					9/12/2012		155		\$0.00
Medium	Work In Progress			9/12/2012 8:26:47 AM					
Orozco, Daniel	Threshold to walk-in cooler came loose again. Also, please replace thermocouple to stove's oven. (Pilot keeps turning off) thank you. SNP Manager Pat C. 824.3822								
<u>Maritza Gonzalez</u>									
98073					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:34 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98074					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:34 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98075					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:34 AM					
Acuna, Johnny	Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98449					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 11:04:34 AM					
Acuna, Johnny	Need to assemble (2) A/V Carts with Flat screen Tv's mounted on them for the Library.								
<u>Johnny Acuna</u>									
96089					12/2/2012	12/10/2012	74		\$0.00
Medium	Work In Progress			12/2/2012 12:23:03 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
2/14/2013 11:25:50 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
98328					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress			2/10/2013 12:20:35 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96410					12/9/2012	12/25/2012	67		\$0.00
Medium	Work In Progress			12/9/2012 12:16:25 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98253					2/6/2013		8		\$0.00
Medium	Work In Progress			2/6/2013 10:26:10 AM					
Briones, Enrique	Need to deliver 214 student desks to San Miguel Elem.								
<u>Johnny Acuna</u>									
98404					2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 1:41:18 PM					
Lozoya, Manny	Please check Fix/Replace door handle to portable #403. (Handle on the outside only opens the door when pulling handle upward)								
<u>Johnny Acuna</u>									
98403					2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 1:39:14 PM					
Ontiveros, Guadalupe	Need assistance with backhoe in removing tree stump in the playground.								
<u>Johnny Acuna</u>									
98455					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 12:30:26 PM					
Ontiveros, Guadalupe	Coaches requesting to re-locate Baseball Backstop to a different location of the field.								
<u>Johnny Acuna</u>									
94274					10/17/2012		120		\$0.00
Medium	Work In Progress			10/17/2012 3:41:51 PM					
Ontiveros, Guadalupe	Coaches requesting to move baseball backstop to another location in same playground area. It is in the way. (Currently Located inside of the soccer playing area)								
<u>Johnny Acuna</u>									
96990					1/8/2013		37		\$0.00
Medium	Work In Progress			1/8/2013 8:19:24 AM					
Ontiveros, Guadalupe	Need Top Soil to fill in holes in playground grass area. (Safety Issue)								
<u>Johnny Acuna</u>									
2/14/2013 11:25:50 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
95920					11/29/2012		77		\$0.00
Medium	Work In Progress				11/29/2012 8:18:57 AM				
Lozoya, Manny		Need to secure electrical boxes to outdoor portables.							
Johnny Acuna									
97351					1/15/2013		30		\$0.00
Medium	Work In Progress				1/15/2013 3:23:41 PM				
Vallejo, Albert		As per Administration, please install dual light fixture to illuminate drive entrance. (Dual fixture will replace damaged single fixture)							
Albert Vallejo									
97935					1/31/2013		14		\$0.00
Medium	Work In Progress				1/31/2013 11:58:31 AM				
Vallejo, Albert		Please install door bell, check with site administration for location.							
Richard Chavez									
94098					10/12/2012		125		\$0.00
Medium	Work In Progress				10/12/2012 10:11:07				
Ontiveros, Joe		Need to replace all student restroom wash basins (Sinks) (Qty. 6)							
Johnny Acuna									
98509					2/14/2013		0		\$0.00
Medium	Work In Progress				2/14/2013 7:57:25 AM				
Ontiveros, Joe		Need to replace drinking water bubbler in sink to classroom #206.							
Johnny Acuna									
96756					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:34 AM				
Villalobos, David		Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 29 Work Orders</b>		<b>Avg. Age of WO's 43</b>		<b>Total for Desert Trail Intermediate</b>				<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
96762					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:37 AM					
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97747					1/28/2013		17		\$0.00
Medium	Work In Progress	Whole Campus		1/28/2013 8:55:43 AM					
Villalobos, David	There is a gas smell throughout the school campus. The odor is very strong in the cafeteria and the office. If we can have it check as soon as possible. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
97988					2/1/2013		13		\$0.00
Medium	Work In Progress			2/1/2013 12:49:01 PM					
Villalobos, David	Boys upper level urinal is clogged; tried everything but it's still clog								
<u>Ruben Ortiz</u>									
94995					11/2/2012		104		\$0.00
Medium	Work In Progress			11/2/2012 3:52:29 PM					
Villalobos, David	Need broken sink replaced in the upper level girl's bathroom Thank you, Ruben								
<u>Ruben Ortiz</u>									
96939		Restroom (Girls)			1/7/2013		38		\$0.00
Medium	Work In Progress	Lower Grade		1/7/2013 2:12:25 PM					
Villalobos, David	Broken toilet needs replacement. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
96317		Classroom			12/6/2012		70		\$0.00
Medium	Work In Progress	Portable #8		12/6/2012 11:51:11 AM					
Villalobos, David	Install sink in the classroom. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
96572		Office			12/13/2012		63		\$0.00
Medium	Work In Progress	Office		12/13/2012 8:21:53 AM					
Villalobos, David	There is a strong odor in the office due to the sewer drainage. If we can have it checked out as soon as possible. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
98409		Office			2/12/2013		2		\$0.00
Medium	Work In Progress	Office		2/12/2013 3:17:50 PM					
Castillo, Carlos	Install a 20 amp outlet for copier. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
2/14/2013 11:25:51 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
98001					2/1/2013		13		\$0.00
Medium	Work In Progress				2/1/2013 3:32:40 PM				
Ortiz, Ruben	Paint the base and little library								
<u>Ruben Ortiz</u>									
95917		Gym			11/29/2012		77		\$0.00
Medium	Work In Progress				11/29/2012 8:04:06 AM				
Ortega, Israel	Set up the stage in the gym for the Spelling Bee. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
97202					1/13/2013	1/29/2013	32		\$0.00
Medium	Work In Progress				1/13/2013 12:16:01 AM				
Ortega, Israel	Monthly - QRTLY BLDG INSP REPORT (DV) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96235					12/4/2012		72		\$0.00
Medium	Work In Progress				12/4/2012 2:26:39 PM				
Lara, Ralph	SCREEN DOOR IN KITCHEN AREA IS BROKEN, NEEDS TO BE LOOKED AT AND FIXED. SNP MANAGER DIANA L. 589.2425								
<u>Maritza Gonzalez</u>									
95514		Classroom			11/14/2012		92		\$0.00
Medium	Work In Progress	Rm. 24			11/14/2012 1:11:25 PM				
Lara, Ralph	Install locks in the classroom for the safety of the students.(Ms. Garcia)								
<u>Guadalupe Gonzalez</u>									
97855					1/30/2013		15		\$0.00
Medium	Work In Progress	Front Gate to			1/30/2013 8:31:52 AM				
Ortiz, Ruben	The Front Gate is difficult to open. It's heavy and doesn't roll as smooth. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
96982					1/7/2013		38		\$0.00
Medium	Work In Progress				1/7/2013 4:57:10 PM				
Ortiz, Ruben	Received a/c cover and base covers; need to install them.								
<u>Ruben Ortiz</u>									
96179					12/3/2012		73		\$0.00
Medium	Work In Progress				12/3/2012 1:05:26 PM				
Ortiz, Ruben	Need to change light blubs in the hallway. Thank you, Ruben								
<u>Ruben Ortiz</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
92736					9/12/2012		155		\$0.00
Medium	Work In Progress			9/12/2012 10:18:19 AM					
Ortiz, Ruben	Pick up Donation. (R. Ortiz)								
<u>Guadalupe Gonzalez</u>									
98131					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:57 AM					
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98132					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:57 AM					
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98129					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:56 AM					
Ortiz, Ruben	Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96588		Restroom (Boys)			12/13/2012		63		\$0.00
Medium	Work In Progress	Upper Grade		12/13/2012 1:05:29 PM					
Ortiz, Ruben	Replace light bulbs in the upper grade boys bathroom. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
96921		Restroom (Boys)			1/7/2013		38		\$0.00
Medium	Work In Progress			1/7/2013 10:29:22 AM					
Ortiz, Ruben	The paper towel dispenser in the Lower Grade Boy's Bathroom is broken.								
<u>Guadalupe Gonzalez</u>									
96940		Restroom (Boys)			1/7/2013		38		\$0.00
Medium	Work In Progress	Lower Grade		1/7/2013 2:13:53 PM					
Ortiz, Ruben	Sink fixtures need replacement. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
96941		Restroom (Boys)			1/7/2013		38		\$0.00
Medium	Work In Progress	Lower Grade		1/7/2013 2:16:15 PM					
Ortiz, Ruben	Toilet seat doesn't fit. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
92512		Classroom			9/7/2012		160		\$0.00
Medium	Work In Progress	Classroom		9/7/2012 9:05:01 AM					
Ortiz, Ruben	Install Marker Boards in the classrooms. (Gonzalez)								
Guadalupe Gonzalez									
96536		Office			12/12/2012		64		\$0.00
Medium	Work In Progress	Principal's Office		12/12/2012 11:40:29					
Ortiz, Ruben	Replace light bulbs in the Principal's office. (Gonzalez)								
Guadalupe Gonzalez									
96537		Office			12/12/2012		64		\$0.00
Medium	Work In Progress	Asst. Principal		12/12/2012 11:41:35					
Ortiz, Ruben	Sink in the Asst. Principal's Office is not working. (Gonzalez)								
Guadalupe Gonzalez									
98335					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress			2/10/2013 12:20:38 AM					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
97746					1/28/2013		17		\$0.00
Medium	Work In Progress			1/28/2013 8:35:06 AM					
Moncayo, Fernando	3 COMPARTMENT SINK BACKING UP WATER EVERYWHERE SMELLS LIKE SEWER. SNP MANAGER DIANA L. 589.2425								
Maritza Gonzalez									
97860		Cafeteria			1/30/2013		15		\$0.00
High	Work In Progress			1/30/2013 10:38:45 AM					
Orozco, Daniel	as per mr. giovas need to replace lavatory faucet in restroom to foot pedal type or existing faucet has to be on for 18 seconds or more as per health inspector. please see mike for details if need be. thank you								
Demetrious Giovas									
97861		Cafeteria			1/30/2013		15		\$0.00
High	Work In Progress			1/30/2013 10:42:11 AM					
Orozco, Daniel	need to relace small stainless steal sink. chemical was used to unclog drain and as per health inspector it needs to be cleaned or relaced.								
Demetrious Giovas									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Desert View ES</b>								
98145	Main Building	Custodial			2/4/2013		10		\$0.00	
Medium	Work In Progress			2/4/2013 10:00:39 AM						
Carbajal, Jimmy	Hi Jimmy, Mr. Aguirre our custodian had problems with one of vaccum cleaners he says it smelled like something was burning and its also going to need the rear wheels. If you could help us out with that. Thank you									
<u>Israel Ortega</u>										
98130					2/3/2013	2/9/2013	11		\$0.00	
Medium	Work In Progress			2/3/2013 12:22:56 AM						
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
98471		Cafeteria			2/13/2013		1		\$0.00	
Medium	Work In Progress	Cafeteria		2/13/2013 2:17:02 PM						
Lara, Ralph	2nd Request: The screen door the the Cafeteria is broken and needs repair. (D. Lazarin)									
<u>Guadalupe Gonzalez</u>										
98469		Cafeteria			2/13/2013		1		\$0.00	
Medium	Work In Progress	Cafeteria		2/13/2013 2:13:03 PM						
Lara, Ralph	The door to the Cafeteria has a broken square and needs repair. (Gonzalez)									
<u>Guadalupe Gonzalez</u>										
90992					8/8/2012		190		\$0.00	
Medium	Work In Progress			8/8/2012 10:33:59 AM						
Gonzalez, Salvador	Need a 2 by 6 dragger out of iron angle. Thank you, Ruben									
<u>Ruben Ortiz</u>										
97708					1/25/2013		20		\$0.00	
Medium	Work In Progress			1/25/2013 2:32:56 PM						
Gonzalez, Salvador	Welding Need a base built for little free library program height 30 inches; width 16 by 23									
<u>Ruben Ortiz</u>										
<b>Count: 37 Work Orders</b>		<b>Avg. Age of WO's 46</b>		<b>Total for Desert View ES</b>			<b>0</b>	<b>\$0.00</b>		

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
98061					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:29 AM					
Moncayo, Fernando	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91474					8/17/2012		181		\$0.00
Medium	Work In Progress			8/17/2012 9:09:56 AM					
Estrada, Jesus	Technology Office - need to have carpet removed in Calixto and Cora office.								
<u>Cora Ramirez</u>									
96788					1/6/2013	1/27/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:47 AM					
Orozco, Daniel	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95572					11/15/2012		91		\$0.00
Scheduled	Work In Progress			11/15/2012 10:40:26					
Ambriz, Juan	Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You								
95108					11/4/2012	11/12/2012	102		\$0.00
Medium	Work In Progress			11/4/2012 12:19:45 AM					
Ambriz, Juan	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92964					9/18/2012		149		\$0.00
Medium	Work In Progress	Lucia Almeraz		9/18/2012 3:45:13 PM					
Ambriz, Juan	ATTN: JUAN AMBRIZ PLEASE INSTALL A REGISTER IN OFFICE								
<u>Lucia Almeraz</u>									
96412					12/9/2012	12/25/2012	67		\$0.00
Medium	Work In Progress			12/9/2012 12:16:26 AM					
Ambriz, Juan	Monthly - GAC Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
97211					1/13/2013	1/29/2013	32		\$0.00
Medium	Work In Progress			1/13/2013 12:16:06 AM					
Moncayo, Fernando	Monthly - GAC Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98327					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress			2/10/2013 12:20:34 AM					
Moncayo, Fernando	Monthly - GAC Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97697					1/25/2013		20		\$0.00
Medium	Work In Progress			1/25/2013 10:01:30 AM					
Moncayo, Fernando	SEVERAL TILES NEED TO BE CHANGED IN B-WING HALLWAYS.								
<u>Maritza Gonzalez</u>									
93982					10/10/2012		127		\$0.00
Medium	Work In Progress			10/10/2012 8:40:49 AM					
Flores, Pete	Frank's Balderrama suburban stopped on Mercantile Road.								
<u>Cora Ramirez</u>									
93983					10/10/2012		127		\$0.00
Medium	Work In Progress			10/10/2012 8:44:59 AM					
Flores, Pete	David Hinojosa's van is not starting. Will drop off tomorrow morning to have it checked out.								
<u>Cora Ramirez</u>									
97391					1/16/2013		29		\$0.00
Medium	Work In Progress			1/16/2013 10:58:19 AM					
Flores, Pete	SNP VAN NUMBER 131(ADELE) NEEDS TO BE SERVICED. SQUEKING NOISE.								
<u>Maritza Gonzalez</u>									
98202					2/5/2013		9		\$0.00
Medium	Work In Progress			2/5/2013 12:57:55 PM					
Flores, Pete	SNP LOANER VAN THAT WAS ISSUED OUT TO ADELE NEEDS TO BE PICKED UP AT GAC. IT WILL NOT START.								
<u>Maritza Gonzalez</u>									
96721					1/6/2013		39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:15 AM					
Holguin, Alfredo	Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

2/14/2013 11:25:51 AM

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
98152					2/4/2013		10		\$0.00
Medium	Work In Progress				2/4/2013 3:35:52 PM				
Moncayo, Fernando	2/4/13-1-ckd blds,1-97780,2-97802,2-97968,1-98151,1-daily work log		2/4						
Fernando Moncayo									
98064					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:30 AM				
Moncayo, Fernando	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
97100					1/10/2013		35		\$0.00
Medium	Work In Progress				1/10/2013 8:41:28 AM				
Moncayo, Fernando	Need to hang 22 teachers of the year under the sign in the board room.								
Maritza Gonzalez									
98063					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:29 AM				
Moncayo, Fernando	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
97872					1/30/2013		15		\$0.00
Medium	Work In Progress				1/30/2013 1:39:46 PM				
Moncayo, Fernando	BUSHES NEED TO BE TRIMMED IN PARKING LOT AREA.								
Maritza Gonzalez									
94698					10/29/2012		108		\$0.00
Medium	Work In Progress				10/29/2012 9:26:05 AM				
Rodriguez, Arturo	TOILET IN RR IN FRONT OF RECEPTIONIST AREA WILL NOT FLUSH.								
Maritza Gonzalez									
96829					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress				1/6/2013 12:24:07 AM				
Moncayo, Fernando	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
98318					2/8/2013		6		\$0.00
Medium	Work In Progress				2/8/2013 1:56:07 PM				
Moncayo, Fernando	Need more light in computer tech office						2/11 - route to Fernando asp Mike		
Cora Ramirez									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
93781					10/3/2012		134		\$0.00
Medium	Work In Progress			10/3/2012 8:34:00 AM					
Lara, Ralph	AS PER MR. YTURRALDE, DOUBLED DOORS ENTERING HUMAN RESOURCES NEED LOCK/NUMBER LOCK INSTALLED FOR SECURITY PURPOSES. PLEASE SEE ARTURO.								
<u>Maritza Gonzalez</u>									
96832					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:08 AM					
Moncayo, Fernando	Monthly - GAC Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98504					2/14/2013		0		\$0.00
Medium	Work In Progress			2/14/2013 12:21:41 AM					
Ambriz, Jose	Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97228					1/14/2013		31		\$0.00
Medium	Work In Progress			1/14/2013 12:18:44 AM					
Ambriz, Jose	Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97780					1/28/2013		17		\$0.00
Medium	Work In Progress			1/28/2013 3:18:01 PM					
Ambriz, Jose	"C" wing restroom exhaust fan needs a new motor								
<u>Fernando Moncayo</u>									
95653					11/19/2012		87		\$0.00
High	Work In Progress			11/19/2012 7:30:10 AM					
Ambriz, Jose	need to rewire liebert cooling system in tech room to have only 2 compressors functioning, install 4 contactors, new switches, intelligent board, programming etc . this system is oversized for room and is causing problems as designed.								
<u>Michael Munoz</u>									
95358					11/9/2012		97		\$0.00
Medium	Work In Progress			11/9/2012 9:36:29 AM					
Ambriz, Jose	AS PER MR. Y. WALL UNIT IS NOT WORKING PROPERLY MAY NEED TO BE REPLACED.								
<u>Maritza Gonzalez</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: GAC</b>									
96623					12/14/2012		62		\$0.00
Medium	Work In Progress				12/14/2012 12:16:36				
Ambriz, Jose	Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96987					1/8/2013		37		\$0.00
Medium	Work In Progress				1/8/2013 8:12:56 AM				
Ambriz, Jose	Server Room - Unit is down								
<u>Michael Munoz</u>									
96315					12/6/2012		70		\$0.00
Medium	Work In Progress				12/6/2012 10:37:09 AM				
Castillo, Carlos	C-WING, NEED POWER TO CLOSET IN KARLA QUESADAS OFFICE.								
<u>Maritza Gonzalez</u>									
92932					9/18/2012		149		\$0.00
Medium	Work In Progress				9/18/2012 12:44:19 PM				
Villalobos, David	MAIN WATER LINE LEAKING IN C-WING.								
<u>Maritza Gonzalez</u>									
96763					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:37 AM				
Villalobos, David	Yearly - GAC Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
<b>Count: 35 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>58</b>			<b>Total for GAC</b>	<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
<b>Location: GAC - Pre-K</b>									
98151					2/4/2013		10		\$0.00
Medium	Work In Progress				2/4/2013 3:21:14 PM				
Moncayo, Fernando	assemble new student's furniture								
Fernando Moncayo									
97586					1/23/2013		22		\$0.00
Medium	Work In Progress				1/23/2013 9:23:08 AM				
Moncayo, Fernando	MIDDLE DRAWER TO PRE K SECRETARY DESK NEEDS TO BE ADJUSTED.								
Maritza Gonzalez									
97856					1/30/2013		15		\$0.00
Medium	Work In Progress				1/30/2013 8:51:17 AM				
Moncayo, Fernando	HANDICAP BUTTON TO PRE-K ENTRANCE IS NOT WORKING, PLEASE CHECK OUT.								
Maritza Gonzalez									
<b>Count: 3 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>16</b>			<b>Total for GAC - Pre-K</b>	<b>0</b>	<b>\$0.00</b>



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden ES</b>									
96894					1/7/2013		38		\$0.00
High	Work In Progress				1/7/2013 7:48:53 AM				
Gonzalez, Salvador	please repair broken window. vandalism								
<u>Michael Munoz</u>									
98334					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress				2/10/2013 12:20:38 AM				
Arreola, Rudy	Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91738		Football Field			8/23/2012		175		\$0.00
Medium	Work In Progress				8/23/2012 9:43:56 AM				
Arreola, Rudy	need assistance with the volleyball net... need to install them greatly appreciate your assistance..								
<u>Loraine Gandara</u>									
97221					1/13/2013	1/29/2013	32		\$0.00
Medium	Work In Progress				1/13/2013 12:16:11 AM				
Arreola, Rudy	Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98119					2/3/2013		11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:52 AM				
Arreola, Rudy	Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98121					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:53 AM				
Arreola, Rudy	Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98122					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:53 AM				
Arreola, Rudy	Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97922		Parking Lot			1/31/2013		14		\$0.00
Medium	Work In Progress				1/31/2013 9:34:36 AM				
Arreola, Rudy	need assistance our stop sign that belongs in the bus drop off area fell....greatly appreciate your assistance in this matter... thank you....								
<u>Loraine Gandara</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
96872					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:29 AM					
Arreola, Rudy	Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.								
Margret Villalobos									
96873					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:29 AM					
Arreola, Rudy	Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.								
Margret Villalobos									
94633					10/26/2012		111		\$0.00
Medium	Work In Progress	outside area		10/26/2012 10:31:19					
Appelzoller, Fred	need immediate assistance... outside where you hook up the water hoses... there seems to be alot of water drainage... water seems to be coming out even if the faucets are closed... please would greatly appreciate your assistance in this matter...								
Loraine Gandara									
97930					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 11:27:12 AM					
Sotelo, Enrique	Please install door bell check with site administration for location.								
Richard Chavez									
95947					11/29/2012		77		\$0.00
Medium	Work In Progress			11/29/2012 2:23:14 PM					
Lozoya, Manny	Need 2 gate keys. Need to check the keys out to either Hector Torres or Hector Gutierrez For more information contact Ralph Gallegos at 882-6921. Thank You.								
97402					1/16/2013		29		\$0.00
Medium	Work In Progress	Morgan Building		1/16/2013 1:57:34 PM					
Lozoya, Manny	Asp Mike, need to key new Morgan Building the same as school site is keyed for admin to have access to it.								
Michael Munoz									
98123					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:54 AM					
Arreola, Rudy	Monthly - Gadsden ES - Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden ES</b>									
97209					1/13/2013	1/29/2013	32		\$0.00
Medium	Work In Progress			1/13/2013 12:16:05 AM					
Pinon, Jose	Monthly - QRTL BLDG INSP REPORT (GES) - Refer to PM schedule details.								
Margret Villalobos									
96778					1/6/2013	1/27/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:43 AM					
Orozco, Daniel	Monthly - Gadsden ES - Fire Sprinkler Insp - Refer to PM schedule details.								
Margret Villalobos									
98120					2/3/2013	2/14/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:52 AM					
Arreola, Rudy	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.								
Margret Villalobos									
96143					12/2/2012	12/13/2012	74		\$0.00
Medium	Work In Progress			12/2/2012 12:23:25 AM					
Arreola, Rudy	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 19 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>41</b>		<b>Total for Gadsden ES</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
98079					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:36 AM					
Herrera, Joel	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96026		Athletic Field			11/30/2012		76		\$0.00
Medium	Work In Progress			11/30/2012 3:39:43 PM					
Gonzalez, Salvador	please order material for new scoreboards. baseball softball.thank you								
<u>Joe Munoz</u>									
94778					10/30/2012		107		\$0.00
Medium	Work In Progress			10/30/2012 1:39:44 PM					
Martinez, Larry	Please pick up Obsolete Technology items located in the Old Library								
<u>Michelle Tellez</u>									
98239					2/6/2013		8		\$0.00
Medium	Work In Progress			2/6/2013 7:41:14 AM					
Gallegos, Rafael	Warranty W/O for fresh air units for the Old English, after re-roofing was done and unit installed we could not start the units.								
<u>Guillermo Hernandez</u>									
91114		Athletic Field			8/10/2012		188		\$0.00
Medium	Work In Progress	Softball Fields		8/10/2012 10:10:53 AM					
Ontiveros, Guadalupe	Requested by Coach L. Chavez for Softball Fields-fencing 6' perimeter and 3-2x6 door chain link fence								
<u>Velia Alarcon</u>									
91115		Athletic Field			8/10/2012		188		\$0.00
Medium	Work In Progress	Softball Fields		8/10/2012 10:12:25 AM					
Ontiveros, Guadalupe	Requested by Coach L. Chavez for Softball Fields-wood fastener--raise fencing around bull pen								
<u>Velia Alarcon</u>									
91116		Athletic Field			8/10/2012		188		\$0.00
Medium	Work In Progress	Softball Fields		8/10/2012 10:14:38 AM					
Ontiveros, Guadalupe	Requested by Coach L. Chavez for Softball Fields-Perimeter fence needs to be pulled & anchored down w/hog ties.								
<u>Velia Alarcon</u>									
96167		Athletic Field			12/3/2012		73		\$0.00
High	Work In Progress			12/3/2012 9:10:56 AM					
Ontiveros, Guadalupe	need to install chian linkfence on infield for offical games. As per coach.								
Guadalupe Ontiveros									
2/14/2013 11:25:51 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
97776		Athletic Field			1/28/2013		17		\$0.00
Medium	Work In Progress			1/28/2013 1:59:54 PM					
Ontiveros, Guadalupe	dump trailer is needed to transport material.								
<u>Guadalupe Ontiveros</u>									
98466	Boys Gym				2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 2:04:50 PM					
Villalobos, Margret	Please spray boys locker room #100 for roaches and foot ball locker room for spiders at the Boys Gym.		This area was serviced on 1/31/13						
<u>Guillermo Hernandez</u>									
98433	Library				2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 8:23:19 AM					
Ronquillo, Ruben	as per conversation could you please deliver the scissor lift today before 130 to the old library for mr.alley to check ceiling.thank you								
<u>Alfredo Holguin</u>									
97699	Varsity Gym				1/25/2013		20		\$0.00
Medium	Work In Progress			1/25/2013 10:47:58 AM					
Castillo, Carlos	Please check score boards in the V. Gym, scoreboard is turning off and on. Previously W/O #96524, did not had a location...								
<u>Guillermo Hernandez</u>									
97804	Varsity Gym	Gym			1/29/2013		16		\$0.00
Medium	Work In Progress			1/29/2013 7:30:44 AM					
Carrasco, Danny	Need scissor lift to be delivered to GHS varsity gym by PPD warehousemen.								
<u>Carlos Castillo</u>									
92340	North Building				9/4/2012		163		\$0.00
Medium	Work In Progress			9/4/2012 11:39:43 AM					
Appelzoller, Fred	Requested by Ms. Romero Rm. 223 North Building- Need to remove water and gas outlets, in additon to bench tables. Laser engraver and mill need to be properly instaleld and the room is needed to properly install the equipment.								
<u>Velia Alarcon</u>									
96230	Auto Shop				12/4/2012		72		\$0.00
Medium	Work In Progress			12/4/2012 1:14:52 PM					
Appelzoller, Fred	Please install correct clean out fixture for the clean out located east of the electrical setup in the ponding area south of the Auto Shop. This is an existing clean out that the pond was designed around. For more details see Allan Jurney or call Rafael Gallegos at 882-6921. Thanks.								
<u>Rafael Gallegos</u>									
2/14/2013 11:25:51 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

97713	Pool Pump				1/25/2013		20		\$0.00
Medium	Work In Progress				1/25/2013 3:00:31 PM				
Lara, Ralph	Replace roll-up door with new motorized unit								

Alfredo Holguin

97715	Pool Pump				1/25/2013		20		\$0.00
Medium	Work In Progress				1/25/2013 3:02:00 PM				
Lara, Ralph	Replace door leading from pool area to pump house								

Alfredo Holguin

96781					1/6/2013		39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:44 AM				
Orozco, Daniel	Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PM schedule details.								

Margret Villalobos

95625	Old English Bldg				11/16/2012		90		\$0.00
High	Work In Progress				11/16/2012 10:46:22				
Lozoya, Manny	Need to replace door in Old English #141, door is hanging it is being hold by the door closer, secured door from falling down, but room needs to be secured..								

Guillermo Hernandez

97207					1/13/2013	1/29/2013	32		\$0.00
Medium	Work In Progress				1/13/2013 12:16:04 AM				
Munoz, Joe	Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.								

Margret Villalobos

96804					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:54 AM				
Hernandez, Guillermo	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								

Margret Villalobos

91592					8/20/2012		178		\$0.00
Medium	Work In Progress				8/20/2012 3:55:01 PM				
Gonzalez, Salvador	Requested by Coach L. Chavez for Softball Field- Replace roofs on both dugouts.								

Velia Alarcon

97547					1/22/2013		23		\$0.00
Medium	Work In Progress				1/22/2013 2:18:07 PM				
Lara, Ralph	Requested by Ms. M. Sanchez Rm. 122 Main Building- Southern door handle is loose, it needs to be tighten so that door can be locked.								

Velia Alarcon

2/14/2013 11:25:51 AM

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
97961					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 3:54:42 PM					
Lara, Ralph	Need to replace broken door knob to door on the stage storage room in V. Gym.								
<u>Guillermo Hernandez</u>									
95618					11/16/2012		90		\$0.00
Medium	Work In Progress			11/16/2012 9:02:24 AM					
Lara, Ralph	Requested by Coach Lawrence Rm 341 Academic Building-Lock on door does not lock. Please repair as soon as possible, since Coach Lawrence has his Sp. Ed. lab top out and is afraid it might get stolen.		11/26 - Need status on work order asp email.						
<u>Velia Alarcon</u>									
93980					10/10/2012		127		\$0.00
Medium	Work In Progress			10/10/2012 8:31:32 AM					
Lara, Ralph	Need to replace cores in two storage's room for maintenance to have access for plumbing... ( Academic and Annex building)								
<u>Guillermo Hernandez</u>									
96599					12/13/2012		63		\$0.00
Medium	Work In Progress			12/13/2012 2:58:12 PM					
Lara, Ralph	Need to replace broken keys. for Maintenance 6 and 7 pin..								
<u>Guillermo Hernandez</u>									
97880					1/30/2013		15		\$0.00
Medium	Work In Progress			1/30/2013 2:19:36 PM					
Ontiveros, Guadalupe	Need to remove or cover exposed tree roots on the south side of the Old English building. The root are creating a trip hazard.								
<u>Guillermo Hernandez</u>									
91588					8/20/2012		178		\$0.00
Medium	Work In Progress			8/20/2012 3:50:03 PM					
Ontiveros, Guadalupe	Requested by L. Chavez for Softball Field-Relocate tee's to the area where previous batting cage was located. SEE DIAGRAM								
<u>Velia Alarcon</u>									
91590					8/20/2012		178		\$0.00
Medium	Work In Progress			8/20/2012 3:52:01 PM					
Ontiveros, Guadalupe	Requested by Ms. L. Chavez for Softball Field-Batting cage needs to be moved next to other batting cage behind scoreboard. SEE DIAGRAM								
<u>Velia Alarcon</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
91453					8/16/2012		182		\$0.00
Medium	Work In Progress			8/16/2012 4:19:55 PM					
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Set up brackets for a batting cage to be placed behind "visitors" dugout on mini-base infield. Dimensions asking for L 55' x H 12'.								
<u>Velia Alarcon</u>									
96021		Athletic Field			11/30/2012		76		\$0.00
Medium	Work In Progress			11/30/2012 3:36:57 PM					
Ontiveros, Guadalupe	please reomve existing scoreboards to baseball / softball for new scoreboards. thank you								
<u>Michael Munoz</u>									
97772		Athletic Field			1/28/2013		17		\$0.00
Medium	Work In Progress			1/28/2013 1:49:34 PM					
Ontiveros, Guadalupe	need blade spade for three point hitch. J.D 4440								
<u>Guadalupe Ontiveros</u>									
97775		Athletic Field			1/28/2013		17		\$0.00
Medium	Work In Progress			1/28/2013 1:56:36 PM					
Ontiveros, Guadalupe	box-in scraper is needed for kubota tractor								
<u>Guadalupe Ontiveros</u>									
96339					12/6/2012		70		\$0.00
Medium	Work In Progress			12/6/2012 3:48:09 PM					
Ambriz, Jose	Need to replace gasket to pump in the boiler room for the Old English....								
<u>Guillermo Hernandez</u>									
97135					1/10/2013		35		\$0.00
Medium	Work In Progress			1/10/2013 3:37:55 PM					
Ambriz, Jose	Need to replace fan motor to furnace in the wrestling room.								
<u>Guillermo Hernandez</u>									
94185					10/15/2012		122		\$0.00
Medium	Work In Progress			10/15/2012 3:54:24 PM					
Ambriz, Jose	Need to replace 6 A/C commercial units for the cafeteria....								
<u>Guillermo Hernandez</u>									
94829					10/31/2012		106		\$0.00
Medium	Work In Progress			10/31/2012 9:33:08 AM					
Ambriz, Jose	HEATER UNIT IN BAND ROOM IT DOESNT WORKING AT ANNEX BUILDING								
Joel Herrera									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
93992					10/10/2012		127		\$0.00
Medium	Work In Progress			10/10/2012 11:27:53					
Ambriz, Jose	Need assistance to remove old furnace from the Boys Gym...								
Guillermo Hernandez									
94019					10/10/2012		127		\$0.00
Medium	Work In Progress			10/10/2012 3:43:56 PM					
Ambriz, Jose	Need to replace broken contactor to A/C #6. cafeteria roof.								
Guillermo Hernandez									
95309					11/8/2012		98		\$0.00
Medium	Work In Progress			11/8/2012 7:37:54 AM					
Ambriz, Jose	Need to replace T-stat and check leaks on gaskets on boiler for heating system on the Old English...								
Guillermo Hernandez									
98219					2/5/2013		9		\$0.00
Medium	Work In Progress			2/5/2013 3:30:43 PM					
Ambriz, Jose	Need assistance trouble shooting H/C units in Old English..								
Guillermo Hernandez									
98154					2/4/2013		10		\$0.00
Medium	Work In Progress			2/4/2013 3:38:46 PM					
Ambriz, Jose	Need assistance trouble shooting H/C unit for Admin. #715. dirt still coming in with new filters.								
Guillermo Hernandez									
98156					2/4/2013		10		\$0.00
Medium	Work In Progress			2/4/2013 3:40:18 PM					
Ambriz, Jose	Need assistance trouble shooting North H/C unit in the Library..								
Guillermo Hernandez									
98366					2/11/2013		3		\$0.00
Medium	Work In Progress			2/11/2013 3:26:32 PM					
Ambriz, Jose	Need to replace circuit board to H/ C unit for classroom #651 in Business building.								
Guillermo Hernandez									
95667					11/19/2012		87		\$0.00
High	Work In Progress			11/19/2012 10:06:13					
Hernandez, Guillermo	please paint all ADA logos, ramps and curbs etc to meet code requirements.thankyou								
Joe Munoz									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
92328					9/4/2012		163		\$0.00
Medium	Work In Progress			9/4/2012 10:17:12 AM					
Appelzoller, Fred	Requested by Ms. Lerma Rm. 105 Main Building-One of the ovens needs calibrating. SEE MS. LERMA FOR LOCATION OF OVEN.								
<u>Velia Alarcon</u>									
98420					2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 3:49:12 PM					
Appelzoller, Fred	Need to replace heating element (120v) to water heater in Ms. Lerma classroom.								
<u>Guillermo Hernandez</u>									
98421					2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 3:50:13 PM					
Appelzoller, Fred	Need assistance to unclog urinal in boys restroom at wrestling room..								
<u>Guillermo Hernandez</u>									
92272					9/2/2012		165		\$0.00
Medium	Work In Progress			9/2/2012 12:21:46 AM					
Munoz, Michael	Monthly - Gadsden HS - Grease Trap (Culinary/Auto) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92752		Pump House			9/12/2012		155		\$0.00
Medium	Work In Progress			9/12/2012 3:26:17 PM					
Appelzoller, Fred	the new domestic water filter housing has been order need to order fitting and parts for installation								
<u>Mario Apodaca</u>									
96524					12/12/2012		64		\$0.00
Medium	Work In Progress			12/12/2012 7:57:38 AM					
Sotelo, Enrique	Please check score board, having problems with the lights...								
<u>Guillermo Hernandez</u>									
96545					12/12/2012		64		\$0.00
High	Work In Progress			12/12/2012 3:03:54 PM					
Sotelo, Enrique	Need locates. Please do electrical on the south west corner of property from new light poles on south side of lift station. South of current fence 5' span of current fence. For information see Allan Journey (575-644-0810) or call Ralph Gallegos 882-6921. Thank You								

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
96358					12/7/2012		69		\$0.00
Medium	Work In Progress			12/7/2012 8:42:48 AM					
Castillo, Carlos	Please remove all electric wiring for the Science tables in classroom #223, North building. Tables to be removed....								
Guillermo Hernandez									
96598					12/13/2012		63		\$0.00
High	Work In Progress			12/13/2012 2:56:47 PM					
Castillo, Carlos	Please check east side bleachers motor in the V. Gym, bleachers stock open. Need to be closed for practices...								
Guillermo Hernandez									
91596					8/20/2012		178		\$0.00
Medium	Work In Progress			8/20/2012 3:59:41 PM					
Castillo, Carlos	Requested by Coach L. Chavez for Softball Field-Run electrical outlet to batting cage that will be moved behind scoreboard. SEE DIAGRAM								
Velia Alarcon									
98289					2/7/2013		7		\$0.00
Medium	Work In Progress	LINE LOCATE		2/7/2013 1:25:05 PM					
Castillo, Carlos	We will need locates to be done at Gadsden High School. See attached drawing for area, between the computer lab and the old library. For questions please contact Allan Journey at 575-644-0810, Cuco at 575-649-3178 or Ralph Gallegos at 882-6921. Work orders have been submitted. Thanks.								
Rafael Gallegos									
98460					2/13/2013		1		\$0.00
Medium	Work In Progress	LINE LOCATE		2/13/2013 1:17:36 PM					
Castillo, Carlos	Contact Annette Granado, Triple J Excavation 575-527-1763 Need to line locate from Anthony at Main St on Farm to Market 1905 2.91Mi to NM 28 - N 0.3MI to Haasville Rd - W 0.19MI to power line on L Side of Road. (Spot 50FT- Wide path on E and W Sides of power line from N. Side of Hassville RD S toward								
Alfredo Holguin									
97769					1/28/2013		17		\$0.00
Medium	Work In Progress			1/28/2013 12:45:56 PM					
Castillo, Carlos	Requested by Velia for Faculty Parking Lot-The light closest to the Bus Turnaround is burned out. Please replace as soon as possible.								
Velia Alarcon									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
91113		Athletic Field			8/10/2012		188		\$0.00
Medium	Work In Progress	Softball Fields		8/10/2012 10:08:48 AM					
Castillo, Carlos		Requested by Coach L. Chavez for Softball Fields- electrical boxes/in storage/dugout on both sides and Electrical box installed at score board							
Velia Alarcon									
94830					10/31/2012		106		\$0.00
Medium	Work In Progress			10/31/2012 10:03:50					
Castillo, Carlos		Requested by Mrs. Munoz Rm. 208 (Store Room) North Building-Need an electrical outlet on the west wall of store room.							
Velia Alarcon									
96525		Athletic Field			12/12/2012		64		\$0.00
Medium	Work In Progress			12/12/2012 8:10:53 AM					
Castillo, Carlos		GHS-Boys' baseball scoreboard electrical service needs to be upgraded to support new scoreboard.							
Carlos Castillo									
96526		Athletic Field			12/12/2012		64		\$0.00
Medium	Work In Progress			12/12/2012 8:15:30 AM					
Castillo, Carlos		GHS-softball field scoreboard electcal service needs to be upgraded to support new scoreboard.							
Carlos Castillo									
96543		Athletic Field			12/12/2012		64		\$0.00
Medium	Work In Progress			12/12/2012 2:12:30 PM					
Castillo, Carlos		electrical for new scoreboards needs to be up-gtraded. thank you							
Michael Munoz									
96764					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:37 AM					
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
98077					2/3/2013	2/6/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:35 AM					
Herrera, Joel		Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
97659					1/24/2013		21		\$0.00
Medium	Work In Progress			1/24/2013 3:24:56 PM					
Appelzoller, Fred		Please check for gas smell outside of the boiler room for the cafeteria..							
Guillermo Hernandez									
2/14/2013 11:25:51 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
97980					2/1/2013		13		\$0.00
Medium	Work In Progress	LINE LOCATE		2/1/2013 9:03:24 AM					
Appelzoller, Fred	We will need locates to be done at Gadsden High School by February 4, 2013. See attached drawing for area, from Hass Rd going along the west side of the bus drop off to where the new portables are being installed. For questions please contact Allan Jurney at 575-644-0810 or Ralph Gallegos at 882-6921. Work orders have been submitted. Thanks.								
Rafael Gallegos									
98150					2/4/2013		10		\$0.00
Medium	Work In Progress			2/4/2013 1:38:42 PM					
Appelzoller, Fred	Requested by Teaching Staff for Rm. 317 Academic Building-Sink is clogged with coffee and grinds in Teacher's Lounge.								
Velia Alarcon									
98461					2/13/2013		1		\$0.00
Medium	Work In Progress	LINE LOCATE		2/13/2013 1:18:24 PM					
Appelzoller, Fred	Contact Annette Granado, Triple J Excavation 575-527-1763 Need to line locate from Anthony at Main St on Farm to Market 1905 2.91Mi to NM 28 - N 0.3MI to Haasville Rd - W 0.19MI to power line on L Side of Road. (Spot 50FT- Wide path on E and W Sides of power line from N. Side of Haasville RD S toward								
Alfredo Holguin									
98480					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 3:34:29 PM					
Appelzoller, Fred	N. Bldg - Contractor broke a water line.								
Michael Munoz									
94661		Athletic Field			10/26/2012		111		\$0.00
Medium	Work In Progress			10/26/2012 3:01:38 PM					
Holguin, Ramiro	sprinklers at softball and baseball need to be replace to be able for over seeding.								
Guadalupe Ontiveros									
95620					11/16/2012		90		\$0.00
Medium	Work In Progress			11/16/2012 9:05:57 AM					
Hernandez, Guillermo	Requested by Coach Lawrence Rm. 341 Academic Building-Need two sets of blinds for window.								
Velia Alarcon									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
98067					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:31 AM				
Hernandez, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98068					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:31 AM				
Hernandez, Guillermo	Monthly - Gadsden HS - Elevator (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98011					2/1/2013		13		\$0.00
Medium	Work In Progress				2/1/2013 3:48:04 PM				
Hernandez, Guillermo	Please replace lights out side of the restrooms by the concession stand on the foot ball field.								
<u>Guillermo Hernandez</u>									
98465					2/13/2013		1		\$0.00
Medium	Work In Progress				2/13/2013 2:01:56 PM				
Hernandez, Guillermo	Please put partitions back together in the Nurses station after VCT tile is installed on the northwest side.								
<u>Guillermo Hernandez</u>									
93612					9/30/2012		137		\$0.00
Medium	Work In Progress				9/30/2012 12:31:20 AM				
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
89302					7/1/2012		228		\$0.00
Medium	Work In Progress				7/1/2012 12:30:01 AM				
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96720					1/6/2013		39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:15 AM				
Holguin, Alfredo	Monthly - Gadsden HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96722					1/6/2013		39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:16 AM				
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
96148					12/2/2012		74		\$0.00
Medium	Work In Progress			12/2/2012 12:23:27 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96877					1/6/2013		39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:32 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
94821					10/31/2012		106		\$0.00
Medium	Work In Progress			10/31/2012 12:26:40					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95150					11/4/2012		102		\$0.00
Medium	Work In Progress			11/4/2012 12:20:01 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93642					9/30/2012		137		\$0.00
Medium	Work In Progress			9/30/2012 12:31:33 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92301					9/2/2012		165		\$0.00
Medium	Work In Progress			9/2/2012 12:21:58 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97801					1/28/2013		17		\$0.00
Medium	Work In Progress			1/28/2013 4:09:27 PM					
Carrasco, Danny	Need to replace privacy glass in boys restroom in the cafeteria 20 3/4 x 20 3/4; and safety glass on the northeast entrance door to the cafeteria 22 1/2 x 55 3/8...								
Guillermo Hernandez									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
93092					9/20/2012		147		\$0.00
Medium	Work In Progress			9/20/2012 3:51:26 PM					
Carrasco, Danny	BROKEN WINDOW ON ROOM #341 SINGLE GLASS ZISE 44 1/2 X 29 1/2 AT ACADEMIC BUILDING								
Joel Herrera									
90166					7/25/2012		204		\$0.00
Medium	Work In Progress			7/25/2012 9:33:19 AM					
Estrada, Jesus	Requested by Mr. Pokluda for Rm. 300 in Academic Building-Replace or repair broken floor tiles at entry to classroom.								
Velia Alarcon									
98078					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:35 AM					
Herrera, Joel	Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
94870					10/31/2012		106		\$0.00
Medium	Work In Progress			10/31/2012 3:53:14 PM					
Herrera, Joel	10-31-12 3.0 CHECK HEATER AND REPLCE THERMOCOUPLE AT BAND ROOM 2.0 WORK ORDER # 91952 3.0 CLEANUP GRAFFITIS AT BOYS REST ROOMS AT THE NEW BUILDING				10/31-6				
Joel Herrera									
98081					2/3/2013	3/6/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:37 AM					
Herrera, Joel	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
98080					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:36 AM					
Herrera, Joel	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
97916					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 12:25:34 AM					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
Margret Villalobos									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location: Gadsden HS</b>										
97883					1/30/2013		15		\$0.00	
Medium	Work In Progress			1/30/2013 3:07:52 PM						
Sanchez, Raul	Asp Alfredo, install 2 pump and install valves to isolate pumps.									
<u>Alfredo Holguin</u>										
98451					2/13/2013		1		\$0.00	
Medium	Work In Progress	LINE LOCATE		2/13/2013 11:24:43 AM						
Sanchez, Raul	Need to line locate (See attached) Contact: Annette Grandao, Triple J Excavation 575-527-1763									
<u>Alfredo Holguin</u>										
98126					2/3/2013		11		\$0.00	
Medium	Work In Progress			2/3/2013 12:22:55 AM						
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
98127					2/3/2013		11		\$0.00	
Medium	Work In Progress			2/3/2013 12:22:55 AM						
Sanchez, Raul	Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
98259					2/6/2013		8		\$0.00	
Medium	Work In Progress			2/6/2013 12:10:30 PM						
Orozco, Daniel	TEMP ON REACH IN REFRIGERATION IS AT 43. SNP MANAGER LYDIA M. 882.5522									
<u>Maritza Gonzalez</u>										
93070					9/20/2012		147		\$0.00	
Medium	Work In Progress			9/20/2012 12:14:27 PM						
Gonzalez, Salvador	Need to weld brackets on windows of classroom #106. Main building....									
<u>Guillermo Hernandez</u>										
93175					9/24/2012		143		\$0.00	
Medium	Work In Progress			9/24/2012 2:18:30 PM						
Gonzalez, Salvador	Requested by Coach Letz for Tennis Court-Please repair two of the benches on the Tennis Courts.									
<u>Velia Alarcon</u>										
<b>Count: 102 Work Orders</b>	<b>Avg. Age of WO's 69</b>		<b>Total for Gadsden HS</b>				<b>0</b>	<b>\$0.00</b>		

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden MS</b>							
97907					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 12:25:28 AM					
Apodaca, Mario		Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
98098					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:44 AM					
Apodaca, Mario		Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
98099					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:44 AM					
Apodaca, Mario		Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
97977					2/1/2013		13		\$0.00
Medium	Work In Progress			2/1/2013 8:31:55 AM					
Orozco, Daniel		REFRIGERATION UNIT ON SERVING LINE IS RATTLING. SNP MANAGER TERRY P.882.2824							
Maritza Gonzalez									
98467					2/13/2013		1		\$0.00
Medium	Work In Progress	A wing Testing		2/13/2013 2:07:51 PM					
Diaz, Sebastian		Replace all light bulbs in testing room.							
Nancy Tinajero									
97417					1/16/2013		29		\$0.00
Medium	Work In Progress			1/16/2013 3:34:22 PM					
Diaz, Sebastian		Need to replace ballasts in main office thank you							
Sebastian Diaz									
98440					2/13/2013		1		\$0.00
High	Work In Progress			2/13/2013 9:06:45 AM					
Diaz, Sebastian		please order signs and install on gates. signs are to read. gates to be closed and locked at all times. see mike for details							
Alfredo Holguin									
98499					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 4:36:12 PM					
Appelzoller, Fred		Girls Restroom by cafeteria - water coming up from the floor drain.							
Connie Avalos									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Gadsden MS</b>								
96765					1/6/2013	2/6/2013	39		\$0.00	
Medium	Work In Progress				1/6/2013 12:23:38 AM					
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
96902		Football Field			1/7/2013		38		\$0.00	
Medium	Work In Progress				1/7/2013 8:18:11 AM					
Sotelo, Enrique		Enrique can you help disconnecting power on scoreboard please so we can work on it, thank you.								
Salvador Gonzalez										
98350					2/11/2013		3		\$0.00	
Medium	Work In Progress				2/11/2013 12:15:15 PM					
Solis, Lorenzo		Need to check pump on boiler room westside thank you								
Sebastian Diaz										
93734					10/1/2012		136		\$0.00	
Medium	Work In Progress				10/1/2012 3:42:45 PM					
Solis, Lorenzo		Need to check boiler pump in westside thank you								
Sebastian Diaz										
93735					10/1/2012		136		\$0.00	
Medium	Work In Progress				10/1/2012 3:44:34 PM					
Solis, Lorenzo		Need to check boiler in west side thank you								
Sebastian Diaz										
98007					2/1/2013		13		\$0.00	
Medium	Work In Progress				2/1/2013 3:43:43 PM					
Solis, Lorenzo		Need to replace A/C on locker rooms thank you								
Sebastian Diaz										
98008					2/1/2013		13		\$0.00	
Medium	Work In Progress				2/1/2013 3:44:34 PM					
Solis, Lorenzo		Need to check hater on gym thank you								
Sebastian Diaz										
97663					1/24/2013		21		\$0.00	
Medium	Work In Progress				1/24/2013 3:35:09 PM					
Lozoya, Manny		Need to fix door knob on cafeteria southeast thank you								
Sebastian Diaz										

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
95451					11/13/2012		93		\$0.00
Medium	Work In Progress				11/13/2012 11:21:58				
Ontiveros, Guadalupe	Please move guard shed to the back of the school. Set it up on the 6X6 concrete slab. Please see Mr. Calleros for details.								
<u>Nancy Tinajero</u>									
94655		Athletic Field			10/26/2012		111		\$0.00
Medium	Work In Progress				10/26/2012 2:51:10 PM				
Vasquez, Jose	need to replace solenoids on electric valves. sprinklers are not working.								
<u>Guadalupe Ontiveros</u>									
94874	Main Building				11/1/2012		105		\$0.00
Medium	Work In Progress				11/1/2012 7:48:39 AM				
Lozoya, Manny	B.WING EXIT DOOR NEXT TO ROOM 113 CANNOT UNLOCK WHTH KEY								
<u>Juan Acosta</u>									
94764	Annex				10/30/2012		107		\$0.00
Medium	Work In Progress	Annex/ old hall			10/30/2012 11:47:30				
Solis, Lorenzo	Water fountain does not work. It has low water pressure at drinking spout.								
<u>Nancy Tinajero</u>									
94878	Annex	Hallway/Corridor			11/1/2012		105		\$0.00
Medium	Work In Progress				11/1/2012 8:00:53 AM				
Lozoya, Manny	ANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOOR								
<u>Juan Acosta</u>									
94880	Gymnasium	Hallway/Corridor			11/1/2012		105		\$0.00
Medium	Work In Progress				11/1/2012 8:14:11 AM				
Lozoya, Manny	LOBBY EXIT DOOR GOING IN GYM FLOOR NEXT TO BLEACHERS THE MULLION IS LOOSE								
<u>Juan Acosta</u>									
97292	East Mechanical	Mechanical			1/15/2013		30		\$0.00
Medium	Work In Progress				1/15/2013 7:52:09 AM				
Appelzoller, Fred	need to replace return line on boiler system.								
<u>Fred Appelzoller</u>									
95623	Cafeteria	Custodial			11/16/2012		90		\$0.00
Medium	Work In Progress				11/16/2012 10:32:52				
Carbajal, Jimmy	THE DRIVABLE BURNISHERS BATTERY CABLE IS MELTED PLEASE CHECK FOR A SHORTAGE								
<u>Juan Acosta</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location: Gadsden MS</b>										
93405	C-Wing				9/28/2012		139		\$0.00	
Medium	Work In Progress			9/28/2012 2:33:04 PM						
Castillo, Carlos	Check Transformer by Support Services/Athletic Portable.									
<u>Michael Munoz</u>										
95951	Gym				11/29/2012		77		\$0.00	
Medium	Work In Progress	Gym Storage		11/29/2012 3:23:49 PM						
Gonzalez, Salvador	Please build new loft in storage room in gymnasium. See Mr. Calleros for more details.									
<u>Nancy Tinajero</u>										
94701					10/29/2012		1		\$0.00	
Medium	Work In Progress			10/29/2012 10:54:39		10/30/2012				
Martinez, Larry	Please pick up obsolete technology items									
<u>Michelle Tellez</u>										
98442					2/13/2013		1		\$0.00	
High	Work In Progress			2/13/2013 9:08:22 AM						
Gonzalez, Salvador	please install chain and lock on open space of fence by bus turn around for security puposes. please see mike for details.									
<u>Alfredo Holguin</u>										
89884					7/17/2012		212		\$0.00	
Medium	Work In Progress			7/17/2012 7:12:12 AM						
Lozoya, Manny	ALL CORES TO EXIT DOORS OUTSIDE NEEDS CLEANING									
<u>Juan Acosta</u>										
<b>Count: 29 Work Orders</b>		<b>Avg. Age of WO's 57</b>		<b>Total for Gadsden MS</b>			<b>0</b>	<b>\$0.00</b>		

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: La Union ES</b>									
93326					9/27/2012		140		\$0.00
Medium	Work In Progress			9/27/2012 9:57:08 AM					
Lara, Ralph	DOOR BY WATER HEATER NEEDS TO BE SHAVED - CARPET WAS REPLACED IN BARRACK CHILD CARE CLASS (WORK ORDER #92350), .								
<u>Jesus Estrada</u>									
96854					1/6/2013	1/12/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:19 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98109					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:48 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96398	Main Building	Classroom			12/7/2012		69		\$0.00
Medium	Work In Progress			12/7/2012 4:19:00 PM					
Villalobos, David	Please fix the leaking toilet and replace the lavatory faucet in room 111 at La Union. For details visit with Pat Aguilar or call Ralph Gallegos at 882-6921. Thanks.								
<u>Rafael Gallegos</u>									
96855					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:20 AM					
Aguilar, Patricio	Monthly - La Union ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97224					1/13/2013	1/29/2013	32		\$0.00
Medium	Work In Progress			1/13/2013 12:16:12 AM					
Ramos, Rudy	Monthly - QRTLY BLDG INSP REPORT (LU) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98431					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 7:56:40 AM					
Lara, Ralph	need to rekey one exit hall way door to p.e. teachers key - playground								
<u>Patricio Aguilar</u>									
98430					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 7:52:24 AM					
Aguilar, Patricio	wo to myself - need to install basebpard molding office old wing								
<u>Patricio Aguilar</u>									
2/14/2013 11:25:51 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>La Union ES</b>								
94907					11/1/2012		105		\$0.00	
Medium	Work In Progress				11/1/2012 2:43:15 PM					
Aguilar, Patricio	wo to my self - paint class rooms - hall way old wing									
Patricio Aguilar										
94427					10/22/2012		115		\$0.00	
Medium	Work In Progress				10/22/2012 11:28:37					
Aguilar, Patricio	need p trap for urinal restroom b build									
Patricio Aguilar										
96768					1/6/2013	2/6/2013	39		\$0.00	
Medium	Work In Progress				1/6/2013 12:23:39 AM					
Villalobos, David	Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.									
Margret Villalobos										
94429					10/22/2012		115		\$0.00	
Medium	Work In Progress				10/22/2012 11:31:40					
Villalobos, David	need wax donut - floor bracket for toilet r207									
Patricio Aguilar										
98110					2/3/2013		11		\$0.00	
Medium	Work In Progress				2/3/2013 12:22:48 AM					
Aguilar, Patricio	Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.									
Margret Villalobos										
98107					2/3/2013	2/11/2013	11		\$0.00	
Medium	Work In Progress				2/3/2013 12:22:47 AM					
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.									
Margret Villalobos										
98108					2/3/2013	2/11/2013	11		\$0.00	
Medium	Work In Progress				2/3/2013 12:22:48 AM					
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
Margret Villalobos										
98331					2/10/2013	2/26/2013	4		\$0.00	
Medium	Work In Progress				2/10/2013 12:20:36 AM					
Aguilar, Patricio	Monthly - La Union ES Playground Insp - Refer to PM schedule details.									
Margret Villalobos										
<b>Count: 16 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>46</b>				<b>Total for La Union ES</b>	<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
98333					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress			2/10/2013 12:20:37 AM					
Arreola, Rudy	Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97061					1/9/2013		36		\$0.00
Medium	Work In Progress			1/9/2013 12:34:57 PM					
Orozco, Daniel	HAND SINK NEXT TO 3 COMPARTMENT SINK IS LEAKING. SNP MANAGER FRANCES B. 882.4707								
<u>Maritza Gonzalez</u>									
97647					1/24/2013		21		\$0.00
Medium	Work In Progress			1/24/2013 2:04:25 PM					
Orozco, Daniel	WASHING MACHINE MAKING A LOUD NOISE. SNP MANAGER FRANCES B. 882.4707								
<u>Maritza Gonzalez</u>									
97686					1/24/2013		21		\$0.00
Medium	Work In Progress			1/24/2013 4:22:18 PM					
Orozco, Daniel	EXHAUST FAN AND LIGHT WENT OUT ON HOOD. SNP MANAGER FRANCES B. 882.4707								
<u>Maritza Gonzalez</u>									
98118					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:52 AM					
Arreola, Rudy	Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98115					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:50 AM					
Arreola, Rudy	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98116					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:51 AM					
Arreola, Rudy	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98454		Portables			2/13/2013		1		\$0.00
Medium	Work In Progress	7/8th Grade		2/13/2013 12:26:29 PM					
Arreola, Rudy	On each side of the portable there are 3 banks of lights that dont work. The tubes need replacing in each room.								
Angie Flores									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
97871		Classroom			1/30/2013		15		\$0.00
Medium	Work In Progress	112		1/30/2013 1:28:31 PM					
Arreola, Rudy		Need one of my round tables to be dropped down, too high for students.							
Angie Flores									
96766					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:38 AM					
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
97624		Restroom (Boys)			1/24/2013		21		\$0.00
Medium	Work In Progress			1/24/2013 7:51:32 AM					
Appelzoller, Fred		please replace all granite wash basins in restrooms with stainless steal basins. the existing ones are in poor conditions. thankyou							
Michael Munoz									
98184					2/5/2013		9		\$0.00
High	Work In Progress			2/5/2013 8:41:40 AM					
Appelzoller, Fred		need to run snake, jetter and camera to all sewer lines from point a to z.							
Alfredo Holguin									
91008					8/8/2012		190		\$0.00
Medium	Work In Progress			8/8/2012 2:00:00 PM					
Sotelo, Enrique		Emerg lights (8) in Boys & Girls Restrooms not working asp PM 90795.							
Rudy Arreola									
97931					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 11:54:47 AM					
Sotelo, Enrique		Please install door bell, check with site administration for location.							
Richard Chavez									
97214					1/13/2013	1/29/2013	32		\$0.00
Medium	Work In Progress			1/13/2013 12:16:07 AM					
Solis, Luis		Monthly - QRTLY BLDG INSP REPORT (LL) - Refer to PM schedule details.							
Margret Villalobos									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
96483	Main Building	Classroom			12/11/2012		65		\$0.00
Medium	Work In Progress	112			12/11/2012 3:07:37 PM				
Appelzoller, Fred	Two weeiks ago "snake" was used to declog toilet. It has been 2 years of the toilet not flushing properly. I dont believe it is an issue of two much toilet paper. I dont know if the whole toilet bowl needs to be replaced. On a daily baisis I have to pause Instruction to hold the lever down so that it flushes. There are water stains on floor from water leaking.								
Angie Flores									
98362	Main Building	Athletic Field			2/11/2013		3		\$0.00
Medium	Work In Progress				2/11/2013 3:01:31 PM				
Appelzoller, Fred	SUPPLY WATER LINE FOR WATER FOUNTAIN THAT WAS JUST INSTALLED OUTSIDE WAS BROKEN NEEDS TO BE REPLACED.								
Rudy Arreola									
98177	Main Building	Mechanical			2/5/2013		9		\$0.00
Medium	Work In Progress				2/5/2013 7:51:21 AM				
Appelzoller, Fred	THERE A VALVE ON BOTTOM OF THE TANK WHERE FILTERS ARE LOCATED THAT IS LEAKING TRYED TO TIGHTEN BUT ITS STILL LEAKING.								
Rudy Arreola									
95663	Main Building	Hallway/Corridor			11/19/2012		87		\$0.00
Medium	Work In Progress				11/19/2012 9:43:03 AM				
Sotelo, Enrique	THE SECURITY LIGHT OUTSIDE ENTRANCE AND EXIT DOORS NORTH EAST SIDE IS OFF, WE NEED IT ON FOR THE SECURITY CAMARAS., THANKS.								
Luis Solis									
92940	Main Building	Cafeteria			9/18/2012		149		\$0.00
Medium	Work In Progress				9/18/2012 2:52:51 PM				
Sotelo, Enrique	NEED TO HAVE EXIT SIGN REPLACED BACK DOOR IN KITHECN AREA.								
Rudy Arreola									
97008	Main Building	Classroom			1/8/2013		37		\$0.00
Medium	Work In Progress				1/8/2013 10:10:55 AM				
Lozoya, Manny	As per our principal we need 6 keys to open the back door to the main building. Keys are for Morris, Martinez, Quintero, Gonzalez, Luna and Steinert. Keys will be able to only open one of the back main doors. Not a master key!								
Angie Flores									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
95918	Main Building	Mechanical			11/29/2012		77		\$0.00
Medium	Work In Progress				11/29/2012 8:05:08 AM				
Solis, Lorenzo		PUMP IN MECHANICAL ROOM IS MAKING NOISE THAN NORMAL PUMP WAS GREASED WHEN BOILER WAS STARTED UP. NEEDS TO BE CHECKED.							
Rudy Arreola									
98179	Main Building	Athletic Field			2/5/2013		9		\$0.00
Medium	Work In Progress				2/5/2013 7:55:33 AM				
Ontiveros, Guadalupe		WE HAVE 2 MORE VAVLES STUCK IN GRASS AREA WAS GOING TO START WATERING GRASS ON WEEKENDS BUT THESE VALVES NOT WORKING. THIS MAKES A TOTAL OF 5 VALVES.							
Rudy Arreola									
96001	Main Building	Parking Lot			11/30/2012		76		\$0.00
Medium	Work In Progress				11/30/2012 11:37:03				
Arreola, Rudy		As per Mr. Lawler please repaint the fire lanes.							
Angie Flores									
97625	Main Building				1/24/2013		21		\$0.00
Medium	Work In Progress				1/24/2013 8:11:06 AM				
Arreola, Rudy		AS PER MY CONVERSATION WITH MIKE MUNOZ NEED TO CHANGE OUT FILTERS AT GES CAMPUS.							
Rudy Arreola									
95660	Main Building	Office			11/19/2012		87		\$0.00
Medium	Work In Progress				11/19/2012 9:27:33 AM				
Arreola, Rudy		PRINCIPAL OFFICE HAS SOME LIGHTS OFF. THANKS				11/20/12 - Asp Mike, route to Rudy.			
Luis Solis									
95770	Main Building	Hallway/Corridor			11/26/2012		80		\$0.00
Medium	Work In Progress				11/26/2012 12:45:44				
Arreola, Rudy		Water fountain needed to be turned off water kept running solenoid needs to be replaced.							
Rudy Arreola									
98191	Main Building	Classroom			2/5/2013		9		\$0.00
Medium	Work In Progress	220			2/5/2013 11:54:14 AM				
Arreola, Rudy		Vent fell of ceiling, please replace.							
Angie Flores									
98192	Main Building	Portables			2/5/2013		9		\$0.00
Medium	Work In Progress	Gonzalez			2/5/2013 11:55:01 AM				
Arreola, Rudy		One of the lights is out.							
Angie Flores									
2/14/2013 11:25:51 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Loma Linda ES</b>									
96008	Main Building	Athletic Field			11/30/2012		76		\$0.00
Medium	Work In Progress				11/30/2012 2:49:28 PM				
	Ontiveros, Guadalupe	ANOTHER VALVE IS STUCK SPRINKLERS KEEP RUNNING. BY PLAYGROUND AREA.							
Rudy Arreola									
96789					1/6/2013	1/27/2013	39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:47 AM				
	Orozco, Daniel	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
98117					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:51 AM				
	Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 32 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>40</b>		<b>Total for Loma Linda ES</b>	<b>0</b>		<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
98097					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:43 AM				
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97634		Custodial			1/24/2013		21		\$0.00
Medium	Work In Progress				1/24/2013 9:12:26 AM				
Carbajal, Jimmy	please vaccum #1168 the motor is not working making a lot of noise thank you								
<u>Luis Saucedo</u>									
97808					1/29/2013		16		\$0.00
Medium	Work In Progress				1/29/2013 8:06:10 AM				
Lozoya, Manny	bathroom partitions north and south ,boys' and girls' bathrooms need to be replaced								
<u>Joe Ramirez</u>									
97920		Custodial			1/31/2013		14		\$0.00
Medium	Work In Progress				1/31/2013 8:13:17 AM				
Carbajal, Jimmy	please #1166 vaccum no power at all thank you								
<u>Luis Saucedo</u>									
97385					1/16/2013		29		\$0.00
Medium	Work In Progress				1/16/2013 8:51:53 AM				
Lozoya, Manny	door handle rm.229 not working properly neds to be replaced								
<u>Joe Ramirez</u>									
95365					11/9/2012		97		\$0.00
Medium	Work In Progress				11/9/2012 1:09:02 PM				
Lozoya, Manny	sothside boys and girls bathroom stalls need to be replaced the floor securing brackets are either broken or rusted through and also most of the stalls are very rusted								
<u>Joe Ramirez</u>									
96318					12/6/2012		70		\$0.00
Medium	Work In Progress				12/6/2012 1:02:43 PM				
Briones, Enrique	please Warehouse ATT: LARRY MARTINES we have broken computer desk, old furniture, student desk broken, etc. thank you								
<u>Luis Saucedo</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Mesquite ES</b>									
91491					8/17/2012		181		\$0.00
Medium	Work In Progress			8/17/2012 12:42:10 PM					
Estrada, Jesus	ATTEN. ALFREDO, RMS.201,202,203,204,205. CARPET NEEDS TO BE REPLACED WITH FLOOR TILE.								
<b>Joe Ramirez</b>									
94625		Custodial			10/26/2012		111		\$0.00
Medium	Work In Progress			10/26/2012 6:55:00 AM					
Estrada, Jesus	Mr. Estrada, On portables #602 the carpet is torn out and need new carpet. If you have a chance, could you please stop by and see it. Thank you								
<b>Luis Saucedo</b>									
90983		Portables			8/8/2012		190		\$0.00
Medium	Work In Progress			8/8/2012 9:32:51 AM					
Estrada, Jesus	Mr. Estrada,  On portables #801 and #802 the carpet is torn out and both rooms need new carpet. If you have a chance, could you please stop by and see it.  Thank you								
<b>Luis Saucedo</b>									
89435					7/1/2012	8/1/2012	228		\$0.00
Medium	Work In Progress			7/1/2012 12:30:58 AM					
Ramirez, Joe	Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.								
<b>Margret Villalobos</b>									
89436					7/1/2012	8/1/2012	228		\$0.00
Medium	Work In Progress			7/1/2012 12:30:58 AM					
Ramirez, Joe	Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.								
<b>Margret Villalobos</b>									
95182		Athletic Field			11/5/2012		101		\$0.00
Medium	Work In Progress			11/5/2012 3:27:39 PM					
Ramirez, Joe	As per mr. Mike need to in stall irrigation system on playing fields.								
Guadalupe Ontiveros									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
98511					2/14/2013		0		\$0.00
Medium	Work In Progress			2/14/2013 9:17:23 AM					
Lozoya, Manny	AS PER MR. BAKER, HIS MASTER KEY TO KITCHEN (BACKDOOR) DID NOT WORK AT MESQUITE ELEM. HIS UNDERSTANDING WAS THAT HIS MASTER SHOULD BE ABLE TO OPEN ALL KITCHENS. PLEASE ADVISE.								
<u>Maritza Gonzalez</u>									
95919					11/29/2012		77		\$0.00
Medium	Work In Progress			11/29/2012 8:12:40 AM					
Solis, Lorenzo	heater coil unit rm. 402 not working								
<u>Joe Ramirez</u>									
97179					1/11/2013		34		\$0.00
Medium	Work In Progress			1/11/2013 3:47:35 PM					
Ramirez, Joe	please paint doors to portable 611 & 612. thank you								
<u>Selma Nevarez</u>									
97882					1/30/2013		15		\$0.00
Medium	Work In Progress			1/30/2013 2:25:48 PM					
Ramirez, Joe	interior doors need to be painted. please order paint. thank you								
<u>Michael Munoz</u>									
97874		Parking Lot			1/30/2013		15		\$0.00
High	Work In Progress			1/30/2013 1:59:05 PM					
Ramirez, Joe	as per conversation, all ada parking spaces need to be re-painted as well as fire lanes and parking stripes. not all paking spaces are used nor the ada parking so this project can be done during hours of operation.								
<u>Michael Munoz</u>									
97630					1/24/2013		21		\$0.00
Medium	Work In Progress			1/24/2013 8:50:56 AM					
Lozoya, Manny	i need 4 padlocks for the new gates that are being installed								
<u>Joe Ramirez</u>									
93466					9/30/2012	10/31/2012	137		\$0.00
Medium	Work In Progress			9/30/2012 12:30:15 AM					
Ramirez, Joe	Yearly - Mesquite ES I-4 Fan Coil Unit Yearly - Refer to PM schedule details.								
Margret Villalobos									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Mesquite ES</b>									
97932					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 11:55:20 AM					
Sotelo, Enrique	Please install door bell, check with site administration for location.								
Richard Chavez									
98406					2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 3:01:08 PM					
Ontiveros, Joe	toilet in boys' bathroom continues to clog up even after numerous augering								
Joe Ramirez									
98407					2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 3:01:55 PM					
Ontiveros, Joe	toilet in boys' bathroom continues to clog up even after numerous augering								
Joe Ramirez									
96769					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:39 AM					
Villalobos, David	Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
97059					1/9/2013		36		\$0.00
Medium	Work In Progress			1/9/2013 12:30:39 PM					
Orozco, Daniel	WALK IN FREEZER IS AT 32 DEGREES.SNP MANAGER VIRGINIA P. 233.2341								
Maritza Gonzalez									
98128					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:56 AM					
Sanchez, Raul	Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
91551					8/20/2012		178		\$0.00
Medium	Work In Progress			8/20/2012 12:50:51 PM					
Ramirez, Joe	need to install frp panel in rms. 801,802.								
Joe Ramirez									
97166					1/11/2013		34		\$0.00
Medium	Work In Progress			1/11/2013 3:18:00 PM					
Ramirez, Joe	please check all restrooms and replace partitions that are rusted. thank you								
Michael Munoz									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
98096					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:43 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97875		Athletic Field			1/30/2013		15		\$0.00
Medium	Work In Progress			1/30/2013 2:00:55 PM					
Ramirez, Joe	please repair backstop, chain link fence needs to be secured, also attach fence bracket on top.								
<u>Michael Munoz</u>									
97869					1/30/2013		15		\$0.00
High	Work In Progress			1/30/2013 1:23:23 PM					
Ramirez, Joe	need to clean in back and around morgan building, (ie commodes, pipes, pipe needles. the pbranches need to be trimmed this is a fire hazard.								
<u>Michael Munoz</u>									
97877					1/30/2013		15		\$0.00
Medium	Work In Progress			1/30/2013 2:02:30 PM					
Ramirez, Joe	please clean along fence and between community baseball park and playground.								
<u>Michael Munoz</u>									
97878					1/30/2013		15		\$0.00
Medium	Work In Progress			1/30/2013 2:05:19 PM					
Ramirez, Joe	please make wells to trees on the south play structures next to community baseball park. the grass is up against the trunk therefore choking th tree. also check all irrigation and bubblers to all trees and playing fields.								
<u>Michael Munoz</u>									
<b>Count:</b>	<b>33 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>60</b>		<b>Total for Mesquite ES</b>	<b>0</b>		<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** North Valley ES

98291					2/7/2013		7		\$0.00
Medium	Work In Progress			2/7/2013 1:51:55 PM					
Villalobos, Margret	need interior and exterior sprayed for spiders.they are all over campus		Waiting on price quote						

<u>Danny Vega</u>									
97987					2/1/2013		-9		\$0.00
Medium	Work In Progress			2/1/2013 11:08:00 AM		1/23/2013			
Orozco, Daniel	MILK COOLER IS FREEZING MILK SNP MANAGER LAURA B. 233.3658								

<u>Maritza Gonzalez</u>									
96175					12/3/2012		73		\$0.00
Medium	Work In Progress			12/3/2012 11:14:46 AM					
Munoz, Michael	attention (MMUNOZ)need 1 set of soccer goals (additional)6 ft x 12ft (same as vado)for our lower grades-thanks								

<u>Danny Vega</u>									
98324					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress			2/10/2013 12:20:33 AM					
Vega, Danny	Monthly - North Valley ES Playground Inspection - Refer to PM schedule details.								

<u>Margret Villalobos</u>									
98057					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:26 AM					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								

<u>Margret Villalobos</u>									
97757		Library			1/28/2013		17		\$0.00
Medium	Work In Progress			1/28/2013 10:05:50 AM					
Vega, Danny	please set up new laminator for Ms. Lucero in the library.								

<u>Priscilla Martinez</u>									
97534		Classroom			1/22/2013		23		\$0.00
Medium	Work In Progress	9 classrooms		1/22/2013 10:04:15 AM					
Vega, Danny	Please install projection screens in the following classrooms 102, 103, 104, 105, 106, 107, 108, 205, 207. Thank you,								
Priscilla Martinez									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>North Valley ES</b>							
93977					10/10/2012		127		\$0.00
Medium	Work In Progress			10/10/2012 7:41:20 AM					
Flores, Pete	truck #76 needs brakes checked-also it stulls on the road it just dies and leaks water thru water pump.plz ck anti freeze.my tool box is loose and will not close .plz remove								
<u>Danny Vega</u>									
96724					1/6/2013		39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:17 AM					
Holguin, Alfredo	Monthly - North Valley ES-Fire Pump Engine-Quartly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98160					2/4/2013		10		\$0.00
Medium	Work In Progress			2/4/2013 3:47:20 PM					
Vega, Danny	need six (6ea) liquid drain openers to use at nve classrm sinks								
<u>Danny Vega</u>									
98162					2/4/2013		10		\$0.00
Medium	Work In Progress			2/4/2013 3:48:40 PM					
Vega, Danny	need 6 replacement basket ball nets								
<u>Danny Vega</u>									
98055					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:25 AM					
Vega, Danny	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96754					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:33 AM					
Villalobos, David	Yearly - North Valley ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97484					1/18/2013		27		\$0.00
Medium	Work In Progress			1/18/2013 10:55:30 AM					
Ontiveros, Joe	exterior water fountain broken /missing drinking spigot/middle wing.please repair or order parts								
<u>Danny Vega</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>North Valley ES</b>							
97578					1/23/2013		22		\$0.00
Medium	Work In Progress			1/23/2013 8:30:33 AM					
Ontiveros, Joe	need small 3gal water heater installed in teachers lounge/it takes 10 minutes or more for luke warm water to pour out /MR T is asking to look into installing one for staff								
Danny Vega									
98402					2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 11:36:50 AM					
Vega, Danny	toilet in room 107 keeps getting clogged.								
Javier Parra									
97394					1/16/2013		29		\$0.00
Medium	Work In Progress			1/16/2013 12:18:39 PM					
Sotelo, Enrique	emergency lamp ballast burnt out boys restrms/rio grande wing								
Danny Vega									
94004					10/10/2012		127		\$0.00
Medium	Work In Progress			10/10/2012 3:11:28 PM					
Sotelo, Enrique	mechanical rms by rms 301-304-303-309-300-203208-210-102and by lounge lites are out bad emergency ballast								
Danny Vega									
97989					2/1/2013		13		\$0.00
Medium	Work In Progress			2/1/2013 12:50:37 PM					
Sotelo, Enrique	emergency lamp ballast in burnt out rio grande wing by rms 301-304. please replace								
Danny Vega									
89953					7/18/2012		211		\$0.00
Medium	Work In Progress			7/18/2012 10:38:49 AM					
Lozoya, Manny	need exterior security door handle plates installed in rm 107-108-211-212-309-310 doors to keep vandals from prying doors open as per MR. T								
Danny Vega									
91740		Classroom			8/23/2012		175		\$0.00
Medium	Work In Progress	various		8/23/2012 10:11:46 AM					
Lozoya, Manny	Need to obtain additional cabinet keys for certain classrooms.								
Priscilla Martinez									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: North Valley ES</b>									
94886					11/1/2012		105		\$0.00
Medium	Work In Progress			11/1/2012 10:47:05 AM					
Lozoya, Manny	door in between techers lounge and hallway wont close.								
Javier Parra									
97366					1/15/2013		30		\$0.00
Medium	Work In Progress			1/15/2013 3:53:46 PM					
Lozoya, Manny	need help to secure front entance door/divider bar core jammed /will not lock plz help								
Danny Vega									
96782					1/6/2013		39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:44 AM					
Orozco, Daniel	Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
98434					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 8:28:56 AM					
Ronquillo, Ruben	nv422-nv616 Impre-k418-Impre-k612 need gas								
Danny Vega									
98059					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:28 AM					
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 26 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>44</b>		<b>Total for North Valley ES</b>	<b>0</b>		<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
98060					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:28 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98244	Main Building				2/6/2013		8		\$0.00
Medium	Work In Progress			2/6/2013 8:44:05 AM					
Sotelo, Enrique	BREAKER FOR LOUNGE KEEPS TRIPPING.								
<u>Adam Montoya</u>									
98393		Mechanical			2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 9:15:11 AM					
Solis, Lorenzo	Pump is making noise,								
<u>Concepcion Montalvo</u>									
96767					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:38 AM					
Villalobos, David	Yearly - Northern Pre-K Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98058					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:27 AM					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98056					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:26 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98325					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress			2/10/2013 12:20:33 AM					
Vega, Danny	Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
<b>Count: 7 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>12</b>	<b>Total for Northern On-Track Pre-K (LM)</b>			<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Physical Plant Complex</b>							
93023					9/19/2012		148		\$0.00
Medium	Work In Progress			9/19/2012 3:17:08 PM					
Apodaca, Mario	need to place order for domestic water filters for several school sites								
Mario Apodaca									
95524					11/14/2012		92		\$0.00
Medium	Work In Progress			11/14/2012 2:45:56 PM					
Apodaca, Mario	PPD Sewage treatment plant The expansion joints At the aeration basin are expanding and contracting due to cold weather loosing some product need to be repaired. As soon as possible								
Mario Apodaca									
93067					9/20/2012		147		\$0.00
Medium	Work In Progress			9/20/2012 10:51:22 AM					
Ronquillo, Ruben	as per meeting held, please dispose of any unused material and clean and organize barracks. thank you.		Continuing from 68685						
Michael Munoz									
98286					2/7/2013		7		\$0.00
Medium	Work In Progress			2/7/2013 9:07:18 AM					
Flores, Pete	Vehicle # 44 - repair replace power steering pump - Very noisy								
Alfredo Holguin									
96035					11/30/2012		76		\$0.00
Medium	Work In Progress			11/30/2012 3:53:59 PM					
Flores, Pete	vehicle 99 is leaking oil and shocks sounds like if it is loose. please check. thank you								
Michael Munoz									
98139					2/4/2013		10		\$0.00
Medium	Work In Progress			2/4/2013 12:21:26 AM					
Villalobos, Margret	Monthly - PPD - Quarterly Meeting - Refer to PM schedule details.								
Margret Villalobos									
96770					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:40 AM					
Villalobos, David	Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Physical Plant Complex</b>							
92274					9/2/2012		165		\$0.00
Medium	Work In Progress			9/2/2012 12:21:47 AM					
Munoz, Michael	Monthly - Physical Plant - Grease Trap (Custodial) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97438					1/17/2013		28		\$0.00
High	Work In Progress			1/17/2013 6:56:41 AM					
Sotelo, Enrique	please check lighting on all buildings at ppd, there are alot of lights that are out. also please install another light on the pole int the auto shop parking lot thank you								
<u>Michael Munoz</u>									
95523		Parking Lot			11/14/2012		92		\$0.00
Medium	Work In Progress			11/14/2012 2:39:27 PM					
Ontiveros, Guadalupe	Parking Area on south side of fence between warehouse and GMS Annex - Install parking stops along fence and around fire hydrant to provide enough clearance around hydrant and next to fence.								
<u>Alfredo Holguin</u>									
97897		Athletic Field			1/30/2013		15		\$0.00
Medium	Work In Progress			1/30/2013 3:48:20 PM					
Ontiveros, Guadalupe	warehouse personal need storage 8'x 40'								
<u>Guadalupe Ontiveros</u>									
98242					2/6/2013		8		\$0.00
High	Work In Progress			2/6/2013 8:40:45 AM					
Flores, Pete	truck #137 needs to be service oil change. breaks need to be change.								
<u>Guadalupe Ontiveros</u>									
97770					1/28/2013		17		\$0.00
Medium	Work In Progress			1/28/2013 12:50:38 PM					
Flores, Pete	Vehicle 99 - Battery light has turned on.								
<u>Michael Munoz</u>									
98304					2/7/2013		7		\$0.00
Medium	Work In Progress			2/7/2013 3:42:10 PM					
Carrasco, Danny	REQUESTING COVERS FOR ALL (3) SCISSOR LIFTS								
Danny Carrasco									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Physical Plant Complex</b>							
98457	Food Services				2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 12:35:47 PM					
Lozoya, Manny	LOADING DOCK DOUBLE DOOR CYLINDER GETS STUCK.								
	JOHNNY LECHUGA SNP WHS MGR. 882-6927								
<u>Jacqueline Aguilar</u>									
93208	Food Services				9/25/2012		142		\$0.00
Medium	Work In Progress			9/25/2012 8:32:47 AM					
Orozco, Daniel	The walk-in refrigerator door has a piece of metal And rubber molding coming off that needs to be fixed								
<u>Maritza Gonzalez</u>									
96596	Motor Vehicle				12/13/2012		63		\$0.00
Medium	Work In Progress	vehicle#143		12/13/2012 2:36:26 PM					
Flores, Pete	check for leaks at fuel injection pump.								
<u>Pete Flores</u>									
98203	Motor Vehicle				2/5/2013		9		\$0.00
Medium	Work In Progress	vehicles178,179		2/5/2013 1:17:35 PM					
Flores, Pete	please clean & wash as required by daily trip schedule.also please refuel.								
<u>Pete Flores</u>									
98204	Motor Vehicle				2/5/2013		9		\$0.00
Medium	Work In Progress	vehicles 08,12		2/5/2013 1:20:34 PM					
Perez, Raul	please refuel,clean & wash listed vehicles as requested by trip schedule.								
<u>Pete Flores</u>									
98205	Motor Vehicle				2/5/2013		9		\$0.00
Medium	Work In Progress	vehicles 184,185		2/5/2013 1:24:27 PM					
Perez, Raul	please perform scheduled maintenance as required.also please refuel,clean and wash.								
<u>Pete Flores</u>									
94667	Motor Vehicle				10/26/2012		111		\$0.00
Medium	Work In Progress	vehicles 188,161		10/26/2012 3:24:12 PM					
Perez, Raul	please wash,clean,& re-fuel as required by daily trip schedule.								
<u>Pete Flores</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
96593	Motor Vehicle				12/13/2012		63		\$0.00
Medium	Work In Progress	vehicles-		12/13/2012 2:27:15 PM					
Perez, Raul	please refuel, clean & wash as required by daily trip schedule.								
Pete Flores									
96594	Motor Vehicle				12/13/2012		63		\$0.00
Medium	Work In Progress	vehicles-		12/13/2012 2:31:49 PM					
Perez, Raul	please check and prepare listed vehicles for daily trip schedules.								
Pete Flores									
96595	Motor Vehicle				12/13/2012		63		\$0.00
Medium	Work In Progress	vehicles-		12/13/2012 2:34:33 PM					
Perez, Raul	please clean, wash, and prepare for daily trip schedule.								
Pete Flores									
98446	Motor Vehicle				2/13/2013		1		\$0.00
Medium	Work In Progress	vehicles 15,27		2/13/2013 10:02:48 AM					
Flores, Pete	please prepare new vehicles for introduction to fleet.								
Pete Flores									
98447	Motor Vehicle				2/13/2013		1		\$0.00
Medium	Work In Progress	vehicle#135		2/13/2013 10:04:24 AM					
Flores, Pete	check brakes-trembling when applied								
Pete Flores									
98448	Motor Vehicle				2/13/2013		1		\$0.00
Medium	Work In Progress	band truck#128		2/13/2013 10:05:50 AM					
Flores, Pete	batteries weak-difficulty starting								
Pete Flores									
95928	Motor Vehicle				11/29/2012		77		\$0.00
Medium	Work In Progress	vehicle#86		11/29/2012 9:53:45 AM					
Flores, Pete	van is running rough and engine is misfiring during normal operation.								
Pete Flores									
97243	Motor Vehicle				1/14/2013		31		\$0.00
Medium	Work In Progress	vehicle#18		1/14/2013 9:43:00 AM					
Flores, Pete	shocks worn and need replacement, also alternator charging excessively causing electrical concerns. engine leaking oil.								
Pete Flores									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
97157	Motor Vehicle				1/11/2013		34		\$0.00
Medium	Work In Progress	vehicle#153		1/11/2013 9:00:45 AM					
Flores, Pete	bench seat torn and metal is exposed.								
Pete Flores									
97158	Motor Vehicle				1/11/2013		34		\$0.00
Medium	Work In Progress	vehicles 147,187		1/11/2013 9:11:54 AM					
Flores, Pete	please repair windshields on vehicles as needed								
Pete Flores									
91931	Motor Vehicle				8/28/2012		170		\$0.00
Medium	Work In Progress			8/28/2012 7:52:34 AM					
Flores, Pete	driver seat is tearing on unit 170, request seat covers for it and a step to get on the truck to avoid any more damage to seats and steering wheel while getting into the truck. even a dash mat for the dashboard to avoid sun damage to it . thank u !!								
Fred Appelzoller									
94039	Motor Vehicle				10/11/2012		126		\$0.00
Medium	Work In Progress	gms-golf cart		10/11/2012 7:47:47 AM					
Flores, Pete	golf cart will not travel in forward direction.								
Pete Flores									
94420	Motor Vehicle				10/22/2012		115		\$0.00
Medium	Work In Progress	vehicle#101		10/22/2012 11:16:35					
Flores, Pete	truck has difficulty achieving highway speed,possibly a fuel concern. check and advise.								
Pete Flores									
94426	Motor Vehicle				10/22/2012		115		\$0.00
Medium	Work In Progress	vehicle#126		10/22/2012 11:27:16					
Flores, Pete	water pump losing coolant and runs very rough intermittently.please check								
Pete Flores									
97392	Motor Vehicle				1/16/2013		29		\$0.00
Medium	Work In Progress	vehicle#135		1/16/2013 11:19:11 AM					
Flores, Pete	vehicle scheduled for routine maintenance								
Pete Flores									
97623	Motor Vehicle				1/24/2013		21		\$0.00
Medium	Work In Progress	vehicle#114		1/24/2013 7:51:18 AM					
Flores, Pete	please repair sun damage to rear speaker deck and torn headliner.								
Pete Flores									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
97812	Motor Vehicle				1/29/2013		16		\$0.00
Medium	Work In Progress	vehicles#124,49,			1/29/2013 9:59:04 AM				
Flores, Pete	tires worn beyond limits and in need of replacement.								
<u>Pete Flores</u>									
97825	Motor Vehicle				1/29/2013		16		\$0.00
Medium	Work In Progress	vehicle#184			1/29/2013 2:33:31 PM				
Flores, Pete	please check and service accordingly								
<u>Pete Flores</u>									
97853	Motor Vehicle				1/30/2013		15		\$0.00
Medium	Work In Progress	vehicle#182			1/30/2013 8:15:41 AM				
Flores, Pete	brakes losing air pressure, need to be looked at by border int.								
<u>Pete Flores</u>									
94890	Purchasing				11/1/2012		105		\$0.00
Medium	Work In Progress				11/1/2012 11:12:31 AM				
Lozoya, Manny	Main Entry Lock to PPD-Construction Offices - core is sticking and hard to unlock								
<u>Alfredo Holguin</u>									
95859	Purchasing	Office			11/27/2012		79		\$0.00
Medium	Work In Progress				11/27/2012 4:14:46 PM				
Lozoya, Manny	Please make a key for IM office 2. For larry								
<u>Larry Martinez</u>									
97246	Maintenance				1/14/2013		31		\$0.00
Medium	Work In Progress				1/14/2013 9:53:38 AM				
Lozoya, Manny	NEED THREE DC1 LOCKS FOR NEW FENCED AREA AT BARRACKS THANK YOU								
<u>Ruben Ronquillo</u>									
91801	Maintenance				8/24/2012		174		\$0.00
Medium	Work In Progress				8/24/2012 7:25:21 AM				
Munoz, Michael	please clean-out lint tank for custodial washing machine. the offices and warehouse smell like sewer.								
<u>Alfredo Holguin</u>									
97103	Maintenance				1/10/2013		35		\$0.00
Medium	Work In Progress				1/10/2013 9:58:53 AM				
Ronquillo, Ruben	PURCHASE NEW TIRES FOR JLG1935 SCISSOR LIFT, AND INSTALL								
<u>Ruben Ronquillo</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
98369	Maintenance				2/11/2013		3		\$0.00
Medium	Work In Progress				2/11/2013 3:39:26 PM				
Apodaca, Mario	Water from sink is coming out cloudy.								
<u>Margret Villalobos</u>									
95647					11/16/2012		90		\$0.00
High	Work In Progress				11/16/2012 3:52:03 PM				
Munoz, Michael	this is to provide service or replace fire extinguisher (out-dated codes) at the following sites gac,ae,br,che,chs,cms,dp,dt,dv,ge,ghs,gms,northern pre -k,lu,ll,mq,nv,ppd,re,ste,sths,sp,sr,vado.								
<u>Michael Munoz</u>									
98389					2/12/2013		2		\$0.00
Medium	Work In Progress				2/12/2013 7:54:56 AM				
Gonzalez, Salvador	I need to fabricate a holder to install and remove scoreboards and A/Cs from roof.								
<u>Salvador Gonzalez</u>									
93179		Lift Station			9/24/2012		143		\$0.00
Medium	Work In Progress				9/24/2012 2:41:20 PM				
Gonzalez, Salvador	Meet to manufacture A base for the domestic tablet container for the waste water treatment plant								
<u>Mario Apodaca</u>									
97854					1/30/2013		15		\$0.00
Medium	Work In Progress				1/30/2013 8:20:56 AM				
Gonzalez, Salvador	Need gas welder machine to replace small one installed on truck.								
<u>Salvador Gonzalez</u>									
<b>Count: 50 Work Orders</b>		<b>Avg. Age of WO's 57</b>		<b>Total for Physical Plant Complex</b>				<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Riverside ES</b>									
97838					1/29/2013		16		\$0.00
Medium	Work In Progress			1/29/2013 3:33:37 PM					
Gonzalez, Salvador	need to build frame of metal for outside water fountain								
<u>Carlos Hernandez</u>									
98062					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:29 AM					
Moncayo, Fernando	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90107					7/24/2012		205		\$0.00
Medium	Work In Progress			7/24/2012 11:06:46 AM					
Estrada, Jesus	NEED TO REPLACE CARPET TO VCT IN BACK STORAGE OFFICE AREA. SEE RAUL ROMOER (HC).								
<u>Jesus Estrada</u>									
97774		Athletic Field			1/28/2013		17		\$0.00
Medium	Work In Progress			1/28/2013 1:53:46 PM					
Ontiveros, Guadalupe	need wide trailer for transportation of z-track 997 mowers.								
<u>Guadalupe Ontiveros</u>									
93203					9/25/2012		142		\$0.00
Medium	Work In Progress			9/25/2012 7:35:15 AM					
Munoz, Michael	need to install new fence w/ gates where mobil home occupant used to be. security for tractors and morgan.								
<u>Alfredo Holguin</u>									
98260	Main Building	Restroom (Boys)			2/6/2013		8		\$0.00
Medium	Work In Progress			2/6/2013 12:11:41 PM					
Ambriz, Juan	Problems with the New toilet seat that was replace, as per custodian, Munoz.								
<u>Olga Arias</u>									
92671	Main Building	Parking Lot			9/11/2012		156		\$0.00
Medium	Work In Progress			9/11/2012 11:07:54 AM					
Moncayo, Fernando	Paint back parking lot with the assigned titles for Administration office/cafeateria, handicapped parkings, ect.								
<u>Olga Arias</u>									
97653	Main Building	Restroom (Girls)			1/24/2013		21		\$0.00
Medium	Work In Progress	front of office			1/24/2013 2:59:49 PM				
Villalobos, David	Girls restroom last stable missing missing toilet seat								
<u>Juan Ambriz</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
98258	Main Building				2/6/2013		8		\$0.00
Medium	Work In Progress				2/6/2013 12:06:58 PM				
Villalobos, David	Problems in the girl restroom with toilet leaking as per custodian								
<u>Olga Arias</u>									
98395	Main Building	Office			2/12/2013		2		\$0.00
Medium	Work In Progress				2/12/2013 10:15:38 AM				
Briones, Enrique	Please pick up 27 boxes of Math adoption materials & 4 boxes of Math materials.								
<u>Larry Martinez</u>									
97947	Main Building	Classroom			1/31/2013		14		\$0.00
Medium	Work In Progress	Room#39			1/31/2013 3:04:51 PM				
Ambriz, Juan	Need to Install white board								
<u>Juan Ambriz</u>									
97407	New Wing 1/02	Classroom			1/16/2013		29		\$0.00
Medium	Work In Progress				1/16/2013 3:07:49 PM				
Villalobos, David	need new toilet room 144								
<u>Carlos Hernandez</u>									
91078	New Wing 1/02				8/9/2012		189		\$0.00
Medium	Work In Progress				8/9/2012 3:29:12 PM				
Villalobos, David	need to replace toilet room 117 broken								
<u>Carlos Hernandez</u>									
98341	New Wing 1/02	Classroom			2/11/2013		3		\$0.00
Medium	Work In Progress				2/11/2013 8:43:01 AM				
Ambriz, Jose	Heating system in the room 101 is not working.								
<u>Olga Arias</u>									
95930					11/29/2012		77		\$0.00
Medium	Work In Progress				11/29/2012 10:09:16				
Moncayo, Fernando	roof top furnace (reznor) in room 141 blower motor burn out								
<u>Fernando Moncayo</u>									
97477					1/18/2013		27		\$0.00
Medium	Work In Progress				1/18/2013 9:05:34 AM				
Ambriz, Jose	need to replace pressure relief valve on both boilers leaking								
<u>Carlos Hernandez</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
90853					8/6/2012		192		\$0.00
Medium	Work In Progress			8/6/2012 2:19:16 PM					
Castillo, Carlos	need to replace 4 perimeter lights in patio areas that were broken due to vandalism case # sppd 20120-1174								
Carlos Hernandez									
97941		Parking Lot			1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 1:17:05 PM					
Castillo, Carlos	Please check all exterior lights at Riverside Elementary. The Tracer ES schedule has them going on at 5:00 pm and off at 7:00 am. As per report from custodian the lights are not coming on. For questions call Ralph Gallegos at 882-6921.								
Rafael Gallegos									
89669					7/9/2012		220		\$0.00
Medium	Work In Progress			7/9/2012 4:06:07 PM					
Castillo, Carlos	need tp replace two outside light fixtures torn off in patio area case # sppd201201011								
Carlos Hernandez									
96757					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:34 AM					
Villalobos, David	Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
97406					1/16/2013		29		\$0.00
Medium	Work In Progress			1/16/2013 3:05:38 PM					
Villalobos, David	need new toilet room 148								
Carlos Hernandez									
94470					10/23/2012		114		\$0.00
Medium	Work In Progress			10/23/2012 8:38:46 AM					
Villalobos, David	need round toilet seats for "kohler" one piece small toilet								
Fernando Moncayo									
89794					7/3/2012		226		\$0.00
Medium	Work In Progress			7/12/2012 10:22:48 AM					
Villalobos, David	Outside water fountain vandalized.								
Carlos Hernandez									
97539		Restroom (Boys)			1/22/2013		23		\$0.00
High	Work In Progress			1/22/2013 11:40:53 AM					
Villalobos, David	please unclog drains in rest rooms and remove temporary drain line. thank you								
Michael Munoz									
2/14/2013 11:25:52 AM									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
90202					7/25/2012		204		\$0.00
Medium	Work In Progress			7/25/2012 3:44:33 PM					
Villalobos, David	need new toilet in outside teacher bathroom upper wing								
Carlos Hernandez									
98348					2/11/2013		3		\$0.00
Medium	Work In Progress			2/11/2013 11:44:04 AM					
Flores, Pete	NEED GASOLINE AND 2 CYCLE OIL								
Jesus Estrada									
98066					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:31 AM					
Moncayo, Fernando	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
96802					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:53 AM					
Moncayo, Fernando	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
98065					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:30 AM					
Moncayo, Fernando	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
95579					11/15/2012		91		\$0.00
Scheduled	Work In Progress			11/15/2012 10:48:21					
Moncayo, Fernando	Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You								
93729					10/1/2012		136		\$0.00
Medium	Work In Progress			10/1/2012 3:14:30 PM					
Moncayo, Fernando	cleaned and serviced heating equipment								
Fernando Moncayo									
97111					1/10/2013		35		\$0.00
Medium	Work In Progress			1/10/2013 11:50:47 AM					
Ambriz, Juan	Asp walk-thru on 1/7/13 West Electrical Room is being used as storage blocking panels - code violation.								
Carlos Castillo									
2/14/2013 11:25:52 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
97057					1/9/2013		36		\$0.00
Medium	Work In Progress			1/9/2013 12:26:08 PM					
Orozco, Daniel	LIGHT ON DISHWASHER IS OUT. SNP MANAGER EMILIA C. 589.2550								
Maritza Gonzalez									
97058					1/9/2013		36		\$0.00
Medium	Work In Progress			1/9/2013 12:27:17 PM					
Orozco, Daniel	OVEN ON STOVE IS NOT HEATING. SNP MANAGER EMILIA C. 589.2550								
Maritza Gonzalez									
98456					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 12:32:15 PM					
Orozco, Daniel	OVEN LOSSES ITS PRESSURE AFTER IT HAS BEEN ON FOR A WHILE.  EMILIA C. SNP MGR 589-2550								
Jacqueline Aguilar									
93082					9/20/2012		147		\$0.00
Medium	Work In Progress			9/20/2012 3:22:08 PM					
Gonzalez, Salvador	need to make a metal box (plumbing protection) for outside drinking fountains,plywood won't stop vandals								
Fernando Moncayo									
97201					1/13/2013	1/29/2013	32		\$0.00
Medium	Work In Progress			1/13/2013 12:16:01 AM					
Moncayo, Fernando	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
96409					12/9/2012	12/25/2012	67		\$0.00
Medium	Work In Progress			12/9/2012 12:16:24 AM					
Moncayo, Fernando	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
98326					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress			2/10/2013 12:20:34 AM					
Moncayo, Fernando	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 39 Work Orders</b>			<b>Avg. Age of WO's 68</b>				<b>Total for Riverside ES</b>	<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
<b>Location:</b>		<b>RTC - Alliance</b>							
97802					1/28/2013		17		\$0.00
Medium	Work In Progress				1/28/2013 4:24:40 PM				
Moncayo, Fernando	replace air/heating filter and replace door stop								
Gloria Delgado									
97968		Portables			1/31/2013		14		\$0.00
Medium	Work In Progress				1/31/2013 4:50:38 PM				
Moncayo, Fernando	sweep sidewalks students and staff unable to walk								
Gloria Delgado									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>16</b>		<b>Total for RTC - Alliance</b>	<b>0</b>		<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>San Miguel ES</b>							
98125					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:55 AM					
Sanchez, Raul		Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
96761					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:36 AM					
Villalobos, David		Yearly - San Miguel ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>25</b>	<b>Total for San Miguel ES</b>			<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
96776					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:42 AM					
Villalobos, David		Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
97939					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 12:04:35 PM					
Castillo, Carlos		Please install door bell check with site administration for location.							
Richard Chavez									
96101					12/2/2012		74		\$0.00
Medium	Work In Progress			12/2/2012 12:23:08 AM					
Ambriz, Juan		Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.							
Margret Villalobos									
97216					1/13/2013	1/29/2013	30		\$0.00
Medium	Work In Progress			1/13/2013 12:16:08 AM		2/12/2013			
Diaz, Pablo		Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.				inspections completed			
Jesus Estrada									
93845					10/7/2012	10/23/2012	130		\$0.00
Medium	Work In Progress			10/7/2012 12:16:24 AM					
Diaz, Pablo		Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.							
Margret Villalobos									
94165		Athletic Field			10/15/2012		122		\$0.00
Medium	Work In Progress	BACK FIELD		10/15/2012 3:28:57 PM					
Ontiveros, Guadalupe		PLEASE FILL OUT ALL HOLES WITH DIRT IN THE BACK FIELDS. THANKS.							
Rita Mendez									
96825					1/6/2013		39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:05 AM					
Ambriz, Juan		Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
96831					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:08 AM					
Ambriz, Juan		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
95581					11/15/2012		91		\$0.00
Scheduled	Work In Progress				11/15/2012 10:49:42				
Ambriz, Juan	Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You								
98201					2/5/2013		9		\$0.00
Medium	Work In Progress				2/5/2013 12:53:31 PM				
Orozco, Daniel	GAS SMELL IN KITCHEN AREA.								
Maritza Gonzalez									
97255					1/14/2013		31		\$0.00
Medium	Work In Progress				1/14/2013 12:59:56 PM				
Orozco, Daniel	AS PER INSPECTION PIPES ON DISHWASHER AND STAND NEEDS TO BE FIXED.SNP MANAGER MARINA R. 589.3439								
Maritza Gonzalez									
98329					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress				2/10/2013 12:20:35 AM				
Ambriz, Juan	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
97210					1/13/2013	1/29/2013	32		\$0.00
Medium	Work In Progress				1/13/2013 12:16:05 AM				
Ambriz, Juan	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
98086					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:39 AM				
Ambriz, Juan	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
98087					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:39 AM				
Ambriz, Juan	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
98085					2/3/2013		11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:38 AM				
Ambriz, Juan	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95724		Restroom (Boys)			11/20/2012		86		\$0.00
Medium	Work In Progress	CASA AZUL			11/20/2012 3:14:15 PM				
Marquez, Gerardo	OUR NEW HAND DRYER IS NOT WORKING PROPERLY. IT WAS TURNING ON AND STAYING ON BY ITSELF. IT WAS TURNED OFF COMPLETELY. PLEASE CHECK. THANKS.								
<u>Rita Mendez</u>									
98418					2/12/2013		2		\$0.00
Medium	Work In Progress				2/12/2013 3:47:58 PM				
Vallejo, Albert	(2-12-13) 3 hrs—(97939) Install doorbell at North Valley Elementary; 4 hrs—(97933) Install doorbell at Santa Teresa Elementary; 1 hr—Gather materials and travel to sites.					2/12-1			
<u>Albert Vallejo</u>									
96581	Main Building	Portables			12/13/2012		63		\$0.00
Medium	Work In Progress	Portable B			12/13/2012 10:57:58				
Castillo, Carlos	Please replace 2 ceiling lights that are out in Portable B.								
<u>Melynda Menchaca</u>									
96473	Main Building	Cafeteria			12/11/2012		65		\$0.00
Medium	Work In Progress	CAFETERIA			12/11/2012 11:24:42				
Castillo, Carlos	A NEW LIGHT FIXTURE IS NEEDED IN THE CAFETERIA. THE OTHER WAS BROKEN AND HAD TO BE REMOVED. THANKS.								
<u>Rita Mendez</u>									
96474	Main Building	Cafeteria			12/11/2012		65		\$0.00
Medium	Work In Progress	CAFETERIA			12/11/2012 11:27:48				
Castillo, Carlos	THE LIGHTS IN THE CAFETERIA NEED TO BE CHECKED. NOT ALL OF THEM ARE WORKING. THANKS.								
<u>Rita Mendez</u>									
97399	Main Building	Cafeteria			1/16/2013		29		\$0.00
Medium	Work In Progress	cafeteria			1/16/2013 1:25:53 PM				
Castillo, Carlos	PLEASE CHECK THE LIGHTS IN THE CAFETERIA. THERE ARE 3 LIGHTS THAT DO NOT WORK. PLEASE CHECK FOR MISSING LIGHTS ALSO, (WERE SUPPOSED TO BE REPLACED LAST SCHOOL YEAR). SECOND REQUEST. THANKS								
<u>Rita Mendez</u>									

2/14/2013 11:25:52 AM

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa ES</b>									
97536	Main Building	Athletic Field			1/22/2013		23		\$0.00
Medium	Work In Progress	OUTSIDE CASA		1/22/2013 10:24:14 AM					
Villalobos, David	WATER FOUNTAIN IS LEAKING. PLEASE CHECK. THANKS.								
<u>Rita Mendez</u>									
98214	Main Building	Cafeteria			2/5/2013		9		\$0.00
Medium	Work In Progress	Kitchen		2/5/2013 3:18:42 PM					
Villalobos, David	Need to replace faucets in kitchen								
<u>Juan Ambriz</u>									
97994	Main Building	Restroom (Boys)			2/1/2013		13		\$0.00
Medium	Work In Progress	100 Hallway		2/1/2013 2:58:15 PM					
Ambriz, Juan	Need to replace sink faucet in boys restroom								
<u>Juan Ambriz</u>									
97297	Main Building	Portables			1/15/2013		30		\$0.00
Medium	Work In Progress	Portable B		1/15/2013 8:10:58 AM					
Ambriz, Juan	Need to check lights in portable B								
<u>Juan Ambriz</u>									
94161	Main Building	Portables			10/15/2012		122		\$0.00
Medium	Work In Progress	PORTABLE A.		10/15/2012 2:43:09 PM					
Ambriz, Juan	WE NEED MINI BLINDS IN PORTABLE A (CASTANEDAS PORTABLE). THANKS.								
<u>Rita Mendez</u>									
91681	Main Building	Portables			8/22/2012		176		\$0.00
Medium	Work In Progress	BILINGUAL		8/22/2012 10:10:45 AM					
Ambriz, Juan	WE NEED MINI BLINDS IN BILINGUAL PORTABLE. ALSO IN MS. BARRAZA'S (VICE PRINCIPAL) OFFICE. PLEASE SEE RITA ON THIS. THANKS.								
<u>Rita Mendez</u>									
92408	Main Building	Portables			9/5/2012		162		\$0.00
Medium	Work In Progress	FIRST		9/5/2012 9:52:41 AM					
Ambriz, Juan	PLEASE SET UP HOOKS FOR COATS AND BACKPACKS IN BILINGUAL PORTABLE. THANKS.								
<u>Rita Mendez</u>									
97298	Main Building	Restroom (Girls)			1/15/2013		30		\$0.00
Medium	Work In Progress	200 hallway		1/15/2013 8:12:56 AM					
Ambriz, Juan	Restroom in girls 200 hallway is not working properly								
<u>Juan Ambriz</u>									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa ES

97299	Main Building	Restroom (Girls)			1/15/2013		30		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	300 Hallway			1/15/2013 8:14:28 AM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Ambriz, Juan Girls restroom in 300 hallway is not working properly

Juan Ambriz

97295	Main Building	Classroom			1/15/2013		30		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room 308			1/15/2013 8:09:26 AM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Ambriz, Juan Ned to check lights in Room #308

Juan Ambriz

97293	Main Building	Classroom			1/15/2013		30		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	room #104			1/15/2013 8:06:56 AM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Ambriz, Juan Need to replace soap dispenser in room #104

Juan Ambriz

97409	Main Building	Classroom			1/16/2013		29		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room #205			1/16/2013 3:12:28 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Ambriz, Juan Need to hang up maps on wall in room # 205

Juan Ambriz

97294	Main Building	Restroom (Boys)			1/15/2013		30		\$0.00
-------	---------------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	200 hallway			1/15/2013 8:08:13 AM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Ambriz, Juan Urinal in boys 200 hallway is not working properly

Juan Ambriz

97636	Main Building	Portables			1/24/2013		21		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	FRONT AREA			1/24/2013 9:28:16 AM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Munoz, Michael PLEASE SET UP MORGAN BUILDING ACROSS THE ART PORTABLE. THIS BUILDING WILL BE USED AS STORAGE FOR ART SUPPLIES. ALSO, PLEASE INSTALL ELECTRICITY IN THE BLDG. THANK YOU.

Rita Mendez

97635	Main Building	Stairway			1/24/2013		21		\$0.00
-------	---------------	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Art portable			1/24/2013 9:12:56 AM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Gonzalez, Salvador A ramp is needed at the entrance of the Art portable. Thank you.

Rita Mendez

93012		Portables			9/19/2012		148		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	portable B			9/19/2012 2:33:09 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Estrada, Jesus Floor Tile in portable B is coming off needs to be replaced with tile or carpet. Tripping hazard for students and staff

Juan Ambriz

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
98088					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:40 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
96826					1/6/2013	1/12/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:05 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 40 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>49</b>	<b>Total for Santa Teresa ES</b>			<b>0</b>	<b>\$0.00</b>	

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
98071					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:33 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97918					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 8:07:27 AM					
Marquez, Gerardo	NEED TO REPLACE 13 BROKEN/MISSING PLASTIC COVERS @ FIRE EXTINGUISHER STATIONS. ALSO NEED TO REPLACE TAGS. 36 TOTAL. THANKS								
<u>Gerardo Marquez</u>									
96226					12/4/2012		72		\$0.00
Medium	Work In Progress			12/4/2012 10:18:50 AM					
Marquez, Gerardo	NEED TO REPLACE FIRE EXTINGUISHERS THAT HAVE BEEN DISCHARGED.								
<u>Gerardo Marquez</u>									
93667					9/30/2012	10/6/2012	137		\$0.00
Medium	Work In Progress			9/30/2012 12:31:44 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96083					12/2/2012	12/8/2012	74		\$0.00
Medium	Work In Progress			12/2/2012 12:23:00 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96809					1/6/2013	1/12/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:57 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
94523					10/24/2012		113		\$0.00
Medium	Work In Progress			10/24/2012 9:52:53 AM					
Carbajal, Jimmy	vacuum cleaner #4088 doesn't turn on.						ASP JIMMY, SCHEDULED TO PICK AND AND SERVICE ON 9/29/12		
<u>Jorge Perez</u>									
96027		Athletic Field			11/30/2012		76		\$0.00
Medium	Work In Progress			11/30/2012 3:41:07 PM					
Gonzalez, Salvador	pleaase order material for new scoreboards. baseball / softball. thank you								
<u>Michael Munoz</u>									

2/14/2013 11:25:52 AM

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
97397					1/16/2013		29		\$0.00
Medium	Work In Progress			1/16/2013 12:52:36 PM					
Lara, Ralph	1/16/13 DRS. TO PERCUSSION STORAGE RM. NEED TO BE REPLACED WITH NEW METAL DRS. EXISTING WOOD DRS. HAVE BEEN FORCED OPEN BREAKING DOORS AT TOP VERTICAL LATCHES.								
<u>Gerardo Marquez</u>									
94151					10/15/2012		122		\$0.00
Medium	Work In Progress			10/15/2012 11:32:27					
Lara, Ralph	The electeic stops that hold the doors open in the gym area needs extensive repair before some gets hurt. The holders are falling off the wall.								
<u>William Dickson</u>									
95999					11/30/2012		76		\$0.00
Medium	Work In Progress			11/30/2012 10:57:11					
Lara, Ralph	Need to replace the band percussion storage with metal doors. It currently has wood doors and can easy be broken in to. He is receiving a lot of new equipment and will need for it to be secured.								
<u>William Dickson</u>									
98245		Athletic Field			2/6/2013		8		\$0.00
High	Work In Progress			2/6/2013 8:44:22 AM					
Garcia, Jose	need to fix broken water lines that were broken by contractors at baseball and softball.								
<u>Guadalupe Ontiveros</u>									
97866					1/30/2013		15		\$0.00
Medium	Work In Progress			1/30/2013 1:06:53 PM					
Munoz, Michael	WHILE DOING FIRE SPRINKLER SYSTEM INSP. WITH DIMAR REPS. FOUND THAT ENTIRE FIRE SPRINKLER SYSTEM TO VOCATIONAL BLDG. HAS NOT BEEN OPERATIONAL SINCE 2011, DUE TO BUSTED WATER LINES. NEEDS TO BE CHECKED OUT. THANKS. CHECKED OUT. THANKS.								
<u>Gerardo Marquez</u>									
96790					1/6/2013	1/27/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:48 AM					
Orozco, Daniel	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
98241					2/6/2013		8		\$0.00
Medium	Work In Progress				2/6/2013 8:24:30 AM				
Flores, Pete	Need fuel on truck #17								
<u>Jorge Perez</u>									
98502					2/13/2013		1		\$0.00
Medium	Work In Progress				2/13/2013 10:13:02 PM				
Munoz, Michael	Annex electrical and boiler room. 11'6"x 5'3" was never filled with concrete when new construction was done. Section of dirt is causing a problem to these two rooms and culinary entrance.								
<u>Jaime Mijarez</u>									
98501					2/13/2013		1		\$0.00
Medium	Work In Progress				2/13/2013 9:47:13 PM				
Mijarez, Jaime	Outside walkway between nurse portable and Morgan storages. Reported by Mr.Dickson a 28'x 4' section of concrete has cracks and a piece missing. Mr.Dickson wants it repaired before some one gets hurt.								
<u>Jaime Mijarez</u>									
96533		Classroom			12/12/2012		64		\$0.00
Medium	Work In Progress	SCIENCE			12/12/2012 10:22:59				
Marquez, Gerardo	55 GAL. WORTH OF DISSECTING PIG PARTS NEED TO BE DISPOSED. NO PLACE TO STORE OVER HOLIDAY. PLEASE PICK UP ASAP. MRS. RODRIGUEZ SPOKE TO MR. CHAVE ABOUT THIS MATTER.								
<u>Marylou Jimenez</u>									
94656		Athletic Field			10/26/2012		111		\$0.00
Medium	Work In Progress				10/26/2012 2:55:46 PM				
Ontiveros, Guadalupe	JD 997 Mower will not start.								
<u>Guadalupe Ontiveros</u>									
94657		Athletic Field			10/26/2012		111		\$0.00
High	Work In Progress				10/26/2012 2:57:54 PM				
Garcia, Jose	JD Tractor is leaking from front axle.								
<u>Guadalupe Ontiveros</u>									
94897					11/1/2012		105		\$0.00
Medium	Work In Progress				11/1/2012 11:54:26 AM				
Munoz, Michael	GATES & FENCE @ VOCATIONAL BLDG. ARE VERY RAGGED LOOOKING. POSTS HAVE BEEN BENT. MESH HAS BEEN RUN INTO IN VARIOUS PLACES. PROBABLY NEEDS TO BE REPLACED.								
<u>Gerardo Marquez</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
98386					2/11/2013		3		\$0.00
Medium	Work In Progress			2/11/2013 6:36:12 PM					
Ronquillo, Ruben	New gym. We will be needing the scissor lift to repair side basketball court. I will get with electrician and Mr. Dodson to see when we can go into gym and perform work.								
<u>Jaime Mijarez</u>									
95746					11/21/2012		85		\$0.00
Medium	Work In Progress			11/21/2012 9:09:49 PM					
Estrada, Jesus	The carpet in the weight room needs repairing. It is coming and posing a unsafe setting.								
<u>William Dickson</u>									
97488	Main Building	Office			1/18/2013		27		\$0.00
Medium	Work In Progress			1/18/2013 11:39:50 AM					
Marquez, Gerardo	Need to get the Social Workers office painted								
<u>William Dickson</u>									
97489	Main Building	Office			1/18/2013		27		\$0.00
Medium	Work In Progress			1/18/2013 11:43:03 AM					
Mijarez, Jaime	Replace all the light bulbs in room 515								
<u>William Dickson</u>									
97550	Main Building	Hallway/Corridor			1/22/2013		23		\$0.00
Medium	Work In Progress			1/22/2013 2:34:13 PM					
Lara, Ralph	The double doors leading out of the 600 hallway need to be repaced. they do not lock well and with a pull can be opened.								
<u>William Dickson</u>									
98398	Main Building	Office			2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 10:47:20 AM					
Briones, Enrique	Please deliver 8 Gaylords & pallets to Emma at STHS.								
<u>Larry Martinez</u>									
98400	Main Building	Office			2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 11:15:30 AM					
Briones, Enrique	Please deliver 3 boxes of Sports Medicine & athletic training Books.								
Larry Martinez									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Santa Teresa HS

98352	Main Building	Office			2/11/2013		3		\$0.00
Medium	Work In Progress	MARYLOU			2/11/2013 1:46:02 PM				
Briones, Enrique	PLEASE DELIVER THE FOLLOWING ITEMS TO: MARYLOU								
	PO #121304020 - 17 BOXES (HURDLES) - STHS TRACK								

Terry Alvarado

93402	Main Building	Classroom			9/28/2012		139		\$0.00
Medium	Work In Progress				9/28/2012 2:23:27 PM				
Marquez, Gerardo	There was an announcement made by Mr. Gallegos in reference to some tables and chairs. We would like to get a few of them. We would like to get 4 rectangular and 4 round tables.								

William Dickson

94756	Vocational	Football Field			10/30/2012		107		\$0.00
Medium	Work In Progress				10/30/2012 8:52:33 AM				
Ontiveros, Guadalupe	We need a new fence for the softball field to be set up before the season starts.								

William Dickson

97544	Library	Library			1/22/2013		23		\$0.00
Medium	Work In Progress				1/22/2013 1:20:44 PM				
Lara, Ralph	Replace the library door so it can be locked everyday. Does not lock and it has been worked on several times.								

William Dickson

95226	Library	Hallway/Corridor			11/6/2012		100		\$0.00
Medium	Work In Progress				11/6/2012 10:12:45 AM				
Lara, Ralph	There is a open space in the Library that needs a drop down locking metal screen to keep equipment safe. There are two sections in the Library that are about 11 feet long. This was suppose to enclosed years ago but the job was never completed.								

William Dickson

95227	Library				11/6/2012		100		\$0.00
Medium	Work In Progress				11/6/2012 10:17:04 AM				
Lara, Ralph	The front door of the Library can not be locked properly. It may need to be replaced. They have tried to fix it on several occassions but no luck. Can we please replace so the Library will be secure.								

William Dickson

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
95225	Library	Classroom			11/6/2012		100		\$0.00
Medium	Work In Progress				11/6/2012 9:54:33 AM				
Estrada, Jesus	The library has carpet that has been there for about 12 years. It has stains, gum, and other ugly looking marks on it. Even after shampooing the carpet it doesn't change the look. We need to exchange that carpet for a new one since we have dignitaries come in quite often.								
<u>William Dickson</u>									
97545	Main Building	Athletic Field			1/22/2013		23		\$0.00
Medium	Work In Progress				1/22/2013 1:30:09 PM				
Lara, Ralph	Need to replace the outside door leading to ther football field. It does not lock.								
<u>William Dickson</u>									
94785	Locker Room				10/30/2012		107		\$0.00
Medium	Work In Progress				10/30/2012 3:14:53 PM				
Marquez, Gerardo	Need paint for the dugouts for both the boys and the girls. The players will paint both dugouts.								
<u>William Dickson</u>									
97972	Cafeteria (2005)	Cafeteria			2/1/2013		13		\$0.00
Medium	Work In Progress				2/1/2013 8:13:50 AM				
Castillo, Carlos	The electical plugs in the kitchen does not have any power. Need fixed ASAP. Thanks!								
<u>William Dickson</u>									
97974	Cafeteria (2005)	Cafeteria			2/1/2013		13		\$0.00
Medium	Work In Progress				2/1/2013 8:22:23 AM				
Marquez, Gerardo	The culinary Kitchen wants two metal shelves installed								
<u>William Dickson</u>									
98444	Cafeteria (2005)	Gym			2/13/2013		1		\$0.00
Medium	Work In Progress				2/13/2013 9:44:08 AM				
Ronquillo, Ruben	Need lift to rearrange the banners in the gym and to check the lights in the cafeteria.								
<u>William Dickson</u>									
96807					1/6/2013		39		\$0.00
Medium	Work In Progress				1/6/2013 12:23:56 AM				
Marquez, Gerardo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98069					2/3/2013		11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:32 AM				
Marquez, Gerardo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
2/14/2013 11:25:52 AM									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
96085					12/2/2012		74		\$0.00
Medium	Work In Progress			12/2/2012 12:23:01 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92657					9/11/2012		156		\$0.00
Medium	Work In Progress			9/11/2012 8:11:10 AM					
Marquez, Gerardo	need to replace 2 ceiling tiles in the main lobby. as well in room 403. No ceiling tiles are in place due to the rain over the weekend.								
<u>Jorge Perez</u>									
92204					9/2/2012		165		\$0.00
Medium	Work In Progress			9/2/2012 12:21:19 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96225					12/4/2012		72		\$0.00
Medium	Work In Progress			12/4/2012 9:24:33 AM					
Marquez, Gerardo	NEED TO REPLACE BURNT OUT LIGHT BULBS IN CUSTODIAL CLOSET 300 WING.								
<u>Gerardo Marquez</u>									
94761					10/30/2012		107		\$0.00
Medium	Work In Progress	WARRIOR		10/30/2012 11:17:32					
Marquez, Gerardo	MOUNT 3 BULLETIN BOARDS IN WARRIOR ROOM.								
<u>Marylou Jimenez</u>									
93068					9/20/2012		147		\$0.00
Medium	Work In Progress	BAND TRUCK		9/20/2012 11:19:31 AM					
Flores, Pete	BAND TRUCK NEEDS MAINTENANCE-CHECK FOR ANY MECHANICAL PROBLEMS ETC.								
<u>Marylou Jimenez</u>									
93404		Choral			9/28/2012		139		\$0.00
Medium	Work In Progress			9/28/2012 2:31:45 PM					
Flores, Pete	We are wanting to remodel the band truck but we need help inpreparing it to be remodeled. the paint is popping off the truck and it may need engine work. Will or can you help us.								
<u>William Dickson</u>									
93586					9/30/2012	10/8/2012	137		\$0.00
Medium	Work In Progress			9/30/2012 12:31:09 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
2/14/2013 11:25:52 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
93587					9/30/2012	10/8/2012	137		\$0.00
Medium	Work In Progress			9/30/2012 12:31:09 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93588					9/30/2012	10/31/2012	137		\$0.00
Medium	Work In Progress			9/30/2012 12:31:09 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96311					12/6/2012		70		\$0.00
Medium	Work In Progress			12/6/2012 8:46:00 AM					
Mijarez, Jaime	Need to install power vent to Laser Machine.								
<u>Michael Munoz</u>									
96096					12/2/2012	12/10/2012	74		\$0.00
Medium	Work In Progress			12/2/2012 12:23:06 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96097					12/2/2012	12/10/2012	74		\$0.00
Medium	Work In Progress			12/2/2012 12:23:06 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96098					12/2/2012	1/2/2013	74		\$0.00
Medium	Work In Progress			12/2/2012 12:23:06 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96823					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:04 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96821					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:03 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

96822					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress				1/6/2013 12:24:03 AM				

Mijarez, Jaime Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

97814					1/29/2013		16		\$0.00
Medium	Work In Progress				1/29/2013 10:04:07 AM				

Marquez, Gerardo NEED TO REPLACE LIGHT FIXTURE IN STORAGE RM. @ GIRLS SOFTBALLFIELD DUGOUT. THANKS.

Gerardo Marquez

93178		Classroom			9/24/2012		143		\$0.00
Medium	Work In Progress	VARIETY OF			9/24/2012 2:38:32 PM				

Marquez, Gerardo SEVERAL ROOM NEED BRACKETS TO BE MOUNTED ON WALL FOR CLASSROOM FLAGS:  
MR. RINCON ROOM #801 2 BRACKETS  
MR. FELIX ROOM #505 2 BRACKETS  
MR. STOUT ROOM #509 2 BRACKETS  
RECEPTIONIST AREA NEEDS 2 BRACKETS  
MR. BAILEY ROOM #406 NEEDS 2 BRACKETS  
MR. CHAMPAGNE WELDING PORTABLE NEEDS 2 BRACKETS  
ROOM #301 NEEDS 2 BRACKETS

Marylou Jimenez

91609					8/21/2012		177		\$0.00
Medium	Work In Progress				8/21/2012 9:55:17 AM				

Marquez, Gerardo NEED TO REPLACE WINDOW BLINDS IN 300 WING.

Gerardo Marquez

91619					8/21/2012		177		\$0.00
Medium	Work In Progress	MARY			8/21/2012 12:09:36 PM				

Marquez, Gerardo NEED TO HAVE 2 SECURITY MIRRORS HUNG IN BACK OF LIBRARY.

Marylou Jimenez

92398					9/5/2012		162		\$0.00
Medium	Work In Progress				9/5/2012 7:39:21 AM				

Marquez, Gerardo 3 urinals in the outside concession stand are leaking water when flushed.

Jorge Perez

98082					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:37 AM				

Mijarez, Jaime Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

2/14/2013 11:25:52 AM

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
98083					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:38 AM				
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98084					2/3/2013	3/6/2013	11		\$0.00
Medium	Work In Progress				2/3/2013 12:22:38 AM				
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97486					1/18/2013		27		\$0.00
Medium	Work In Progress				1/18/2013 11:29:17 AM				
Mijarez, Jaime	Weight Room. Heating unit fan motor gave out, please order fan motor with housing if possible. I will take care of installing the new one.								
<u>Jaime Mijarez</u>									
98283					2/6/2013		8		\$0.00
Medium	Work In Progress				2/6/2013 7:15:43 PM				
Mijarez, Jaime	200 wing photo cell needs to be replaced. lights are staying on too long.								
<u>Jaime Mijarez</u>									
92249					9/2/2012	9/10/2012	165		\$0.00
Medium	Work In Progress				9/2/2012 12:21:37 AM				
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91802					8/24/2012		174		\$0.00
Medium	Work In Progress				8/24/2012 7:27:50 AM				
Mijarez, Jaime	Water fountain located at the end of the 300 hallways is not working. And the water fountain in the back hall way that connects to the 300 is just stays running when power cord is connected.								
<u>Jorge Perez</u>									
90185					7/25/2012		204		\$0.00
Medium	Work In Progress				7/25/2012 1:25:35 PM				
Mijarez, Jaime	need to install vent motor to laser machine when it comes in. thank you								
<u>Michael Munoz</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
90764					8/5/2012	8/13/2012	193		\$0.00
Medium	Work In Progress			8/5/2012 12:17:59 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90782					8/5/2012	9/5/2012	193		\$0.00
Medium	Work In Progress			8/5/2012 12:18:06 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90765					8/5/2012	8/13/2012	193		\$0.00
Medium	Work In Progress			8/5/2012 12:18:00 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93073					9/20/2012		147		\$0.00
Medium	Work In Progress			9/20/2012 12:56:13 PM					
Orozco, Daniel	SANIZER ON DISHWASHER NOT WORKING, AS PER ECO LAB IT HAS TO DO WITH THE WATER PRESSURE.SNP MANAGER OLGA B. 589.5332								
<u>Maritza Gonzalez</u>									
92782					9/13/2012		154		\$0.00
Medium	Work In Progress			9/13/2012 8:41:58 AM					
Gonzalez, Salvador	We need to have a chain welded or hooks welded to extend a chain that will keep people from driving onto side walk along tree line. Rafa Lara will be providing the chain and locks. Mr. Dickson would like to have this done before the game on Friday. Please check with me.								
<u>Jaime Mijarez</u>									
97001					1/8/2013		37		\$0.00
Medium	Work In Progress			1/8/2013 9:18:30 AM					
Gonzalez, Salvador	Railling to exterior stairway going from athletic dressing rooms to concession stand was damaged. We had to remove it, might need to fabricate a new one or repair if possible.								
<u>Jaime Mijarez</u>									
96362					12/7/2012		69		\$0.00
Medium	Work In Progress			12/7/2012 9:21:25 AM					
Lara, Ralph	Culinary Arts Kitchen- Rework door key cores to proper working configuration.								
<u>Jaime Mijarez</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
94150					10/15/2012		122		\$0.00
Medium	Work In Progress			10/15/2012 10:14:42					
Lara, Ralph	Culinary Arts- Rework door key to proper working configuration.								
<u>Jaime Mijarez</u>									
96808					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:56 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98503					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 10:25:08 PM					
Garcia, Jose	Walkway between nurses portable and Morgan storages. Mr. Dickson is requesting more dirt to level all sides of these walk way								
<u>Jaime Mijarez</u>									
97314		Athletic Field			1/15/2013		30		\$0.00
High	Work In Progress			1/15/2013 10:53:18 AM					
Garcia, Jose	wind screen for baseball field was order with out grommets. need to install grommets before we hang on fence.								
<u>Guadalupe Ontiveros</u>									
96565					12/12/2012		64		\$0.00
Medium	Work In Progress			12/12/2012 4:18:54 PM					
Perez, Jorge	AS PER SNP MANAGER, PLEASE CLEAN KITCHEN FLOORS JANUARY 3, 2012 IF POSSIBLE. THANK YOU. SNP MANAGER OLGA B. 589.5332				2/6/13 - ASP JORGE HE WILL TALK TO OLGA AND SCHEDULE TO TAKE CARE OF THIS DURING SPRING BREAK.				
<u>Maritza Gonzalez</u>									
97208					1/13/2013	1/29/2013	32		\$0.00
Medium	Work In Progress			1/13/2013 12:16:04 AM					
Perez, Jorge	Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93008					9/19/2012		148		\$0.00
High	Work In Progress			9/19/2012 1:23:35 PM					
Mijarez, Jaime	gnats are back, please check above ceiling tiles, ducting in ms. panthers classroom and surrounding classrooms for any signs of population. thank you								
<u>Michael Munoz</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
97485					1/18/2013		27		\$0.00
Medium	Work In Progress			1/18/2013 11:24:53 AM					
Ambriz, Jose	Room 210. Both fan coil units are not working on the heating mode. Need to replace the 3 way valves and the actuator valves.								
Jaime Mijarez									
96169					12/3/2012		73		\$0.00
Medium	Work In Progress			12/3/2012 9:26:07 AM					
Ambriz, Jose	Mr.Ukestad wood shop teacher would like electrical wood machinery connected to saw dust exhaust collector. Joe will have to order and install the exhaust vent piping and other parts needed.								
Jaime Mijarez									
98284					2/6/2013		8		\$0.00
Medium	Work In Progress			2/6/2013 7:23:09 PM					
Ambriz, Jose	Library air-handler. Need to replace hot water side belimo valve. The stayed stuck in the open position.								
Jaime Mijarez									
90222					7/26/2012		203		\$0.00
Medium	Work In Progress			7/26/2012 7:54:01 AM					
Ambriz, Jose	Room 513 with Mrs. Hope. Classroom airconditioner is old and has corrosion on one of the corners of the water pan. A/C will need to be changed out. Check with Jaime or Art.								
Jaime Mijarez									
96017		Athletic Field			11/30/2012		76		\$0.00
Medium	Work In Progress			11/30/2012 3:25:22 PM					
Castillo, Carlos	power will be needed for new scoreboards, baseball/softball please contact lynco for quote. thank you								
Michael Munoz									
93291		Football Field			9/26/2012		141		\$0.00
Medium	Work In Progress			9/26/2012 3:02:39 PM					
Castillo, Carlos	Need permanent electrical set-up or better and safer temporary for half-time music.								
Carlos Castillo									
92161		Parking Lot			8/31/2012		167		\$0.00
Medium	Work In Progress	MR.		8/31/2012 1:15:00 PM					
Marquez, Gerardo	PAINT THE 45, 35, 25 YARD LINE ON THE PARKING LOT. BAND NEEDS IT FOR AFTER SCHOOL REHEARSAL. ANYWAY IF IT COULD BE DONE ASAP.								
Marylou Jimenez									

2/14/2013 11:25:52 AM

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
98346		Parking Lot			2/11/2013		3		\$0.00
Medium	Work In Progress			2/11/2013 11:07:12 AM					
Marquez, Gerardo	Need to get some white paint to mark off a no parking area.								
<u>William Dickson</u>									
98443		Athletic Field			2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 9:41:00 AM					
Castillo, Carlos	For the track meet on March 2nd we need to run a electrical line from the score board to the finish line on the south side of the track. Needs to be place above the track not to impede runners while competing. Prior High!								
<u>William Dickson</u>									
97816					1/29/2013		16		\$0.00
Medium	Work In Progress			1/29/2013 10:09:05 AM					
Castillo, Carlos	1/28/13 NEED TO INSTALL AN ELECTRICAL OUTLET IN DUGS OUTS @ GIRLS SOFTBALL FIELD. CURRENTLY AN EXTENSION CORD FED THROUGH A HOLE MADE IN THE CINDERBLOCK IS BEING USED AND ISNT SAFE. THANKS.								
<u>Gerardo Marquez</u>									
98385					2/11/2013		3		\$0.00
Medium	Work In Progress			2/11/2013 6:28:00 PM					
Castillo, Carlos	New gym. One of the side basketball courts is not working please repair.								
<u>Jaime Mijarez</u>									
92273					9/2/2012		165		\$0.00
Medium	Work In Progress			9/2/2012 12:21:46 AM					
Munoz, Michael	Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96774					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:41 AM					
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93711					10/1/2012		136		\$0.00
Medium	Work In Progress			10/1/2012 12:03:32 PM					
Villalobos, David	Restrooms in the main hallway Boy and girls need to adjust or replace toilet seats as well as the restroom in the 300 hallway those need to be replaced.								
<u>Jorge Perez</u>									



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
93789					10/3/2012		134		\$0.00
Medium	Work In Progress			10/3/2012 12:40:25 PM					
Villalobos, David	boys and girls restroom in the 300 hallway need new toilet seats as well as the girls restrooms in the main hallway.								
Jorge Perez									
92523					9/7/2012		160		\$0.00
Medium	Work In Progress			9/7/2012 11:28:42 AM					
Villalobos, David	Coach Dotson and Coach Bennet gym area showers have no water. Please check with Gerry.								
Jaime Mijarez									
93984					10/10/2012		127		\$0.00
Medium	Work In Progress			10/10/2012 9:16:18 AM					
Villalobos, David	URINAL IN BOYS RRM. CONTINUES TO LEAK UNDERNEATH @ WALL. NEEDS TO BE CHECKED OUT BY PLUMBER. THANKS.								
Gerardo Marquez									
97572					1/22/2013		23		\$0.00
Medium	Work In Progress			1/22/2013 3:52:53 PM					
Villalobos, David	Old gym a/c water supply. Locate water supply line to install a new shutoff valve. The existing valve is old and won't shutoff completely.								
Jaime Mijarez									
98495					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 4:00:53 PM					
Villalobos, David	Football concession stand. There was no water shutoff valve or drain line installed for selling area a/c. Had to find a way to close the water. Will need to install a shutoff valve and drain line.								
Jaime Mijarez									
98497					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 4:04:01 PM					
Villalobos, David	Gas main meter line by new gym. Repair gas leak and check all fittings and valves.								
Jaime Mijarez									
98498					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 4:05:57 PM					
Villalobos, David	Inspect man hole that caved in by baseball field and report to water utilities company.								
Jaime Mijarez									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Santa Teresa HS</b>										
92205					9/2/2012	9/5/2012	165		\$0.00	
Medium	Work In Progress				9/2/2012 12:21:20 AM					
Marquez, Gerardo		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
96084					12/2/2012	12/5/2012	74		\$0.00	
Medium	Work In Progress				12/2/2012 12:23:01 AM					
Marquez, Gerardo		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
96806					1/6/2013	1/9/2013	39		\$0.00	
Medium	Work In Progress				1/6/2013 12:23:55 AM					
Marquez, Gerardo		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
98070					2/3/2013	2/6/2013	11		\$0.00	
Medium	Work In Progress				2/3/2013 12:22:32 AM					
Marquez, Gerardo		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
<b>Count: 111 Work Orders</b>		<b>Avg. Age of WO's 75</b>		<b>Total for Santa Teresa HS</b>			<b>0</b>	<b>\$0.00</b>		

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
96775					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:42 AM					
Villalobos, David	Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98143					2/4/2013		10		\$0.00
Medium	Work In Progress			2/4/2013 8:18:34 AM					
Castillo, Carlos	Need to replace light fixture lenses -8ea.								
<u>Carlos Castillo</u>									
98194					2/5/2013		9		\$0.00
Medium	Work In Progress			2/5/2013 12:08:49 PM					
Ambriz, Jose	Thermostat broken								
<u>Laura Parra</u>									
96672					12/31/2012		45		\$0.00
Medium	Work In Progress			12/31/2012 12:27:05					
Mijarez, Jaime	Yearly - Santa Teresa MS H6(Roof Furnace)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90766					8/5/2012	9/5/2012	193		\$0.00
Medium	Work In Progress			8/5/2012 12:18:00 AM					
Prospero, Manuel	Yearly - Santa Teresa MS C-11(Evap.Down)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93542					9/30/2012	10/8/2012	137		\$0.00
Medium	Work In Progress			9/30/2012 12:30:48 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96852					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:18 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98470		Electrical Room			2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 2:14:51 PM					
Lara, Ralph	Need a key for the electrical room for Santa Teresa Middle School. Need to have key by February 14, 2013. Key will be checked out to Lee Eggleston (575-312-0023). For More information please contact Mr. Ralph Gallegos at 882-6921.								

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
98102					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:45 AM					
Prospero, Manuel	Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98106					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:47 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98103					2/3/2013	3/6/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:46 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97745					1/28/2013		17		\$0.00
High	Work In Progress			1/28/2013 8:34:35 AM					
Soria, Mike	GATOR NEEDS NEW TIRES FRONT AND BACK. ALSO GATOR AT S.T.H.S NEEDS FRONT AND BACK.								
<u>Guadalupe Ontiveros</u>									
90780					8/5/2012		193		\$0.00
Medium	Work In Progress			8/5/2012 12:18:06 AM					
Prospero, Manuel	Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90784					8/5/2012	8/13/2012	193		\$0.00
Medium	Work In Progress			8/5/2012 12:18:07 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90785					8/5/2012	8/13/2012	193		\$0.00
Medium	Work In Progress			8/5/2012 12:18:07 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96849					1/6/2013	1/14/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:24:17 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
96127					12/2/2012	12/10/2012	74		\$0.00
Medium	Work In Progress			12/2/2012 12:23:18 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96006					11/30/2012		76		\$0.00
Medium	Work In Progress			11/30/2012 2:34:29 PM					
Prospero, Manuel	11/30/12. 3HRS TROBLE SHUTER ON SOUTH BUILDING (NO COMUNICACION ON HEATERS). 3HRS TROBLE SHUTER ON FIRE ALARM (NO COMUNICACION SOUTH BUILDING.). 1HR PAPER WORK.		11/30-7						
<u>Manuel Prospero</u>									
98105					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:46 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96128					12/2/2012	12/10/2012	74		\$0.00
Medium	Work In Progress			12/2/2012 12:23:19 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95127					11/4/2012	11/12/2012	102		\$0.00
Medium	Work In Progress			11/4/2012 12:19:53 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91549		Classroom			8/20/2012		178		\$0.00
Medium	Work In Progress	ROOM 1		8/20/2012 12:21:59 PM					
Prospero, Manuel	1. PAPER TOWEL DISPENSER ABOVE SINKS 2. PLACE TILES ON BARE CONCRETE FLOOR.								
<u>Laura Parra</u>									
90174					7/25/2012		204		\$0.00
Medium	Work In Progress			7/25/2012 11:23:39 AM					
Prospero, Manuel	WE NEED SOME GASOLINE POR CUSTODIAN TRUAK AN POLARIS.								
<u>Manuel Prospero</u>									
98142		Parking Lot			2/4/2013		10		\$0.00
Medium	Work In Progress			2/4/2013 8:15:10 AM					
Carrasco, Danny	Need to fuel up united rental lift before pick-up.								
<u>Carlos Castillo</u>									
2/14/2013 11:25:53 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
98392	North Building	Cafeteria			2/12/2013		2		\$0.00
Medium	Work In Progress				2/12/2013 8:37:14 AM				
Ronquillo, Ruben	I need some glue traps.								
<u>Ismael Rodriguez</u>									
97710	North Building	Office			1/25/2013		20		\$0.00
Medium	Work In Progress				1/25/2013 2:40:20 PM				
Briones, Enrique	Please pick up boxes of Math adoption samples.								
<u>Larry Martinez</u>									
97445	North Building	Classroom			1/17/2013		28		\$0.00
Medium	Work In Progress	BAND ROOM			1/17/2013 8:41:54 AM				
Gonzalez, Salvador	REQUESTING ROD IRON GATE OUTSIDE BAND ROOM. SAFETY ISSUE.								
<u>Laura Parra</u>									
92934	North Building	Gym			9/18/2012		149		\$0.00
Medium	Work In Progress				9/18/2012 1:07:55 PM				
Lara, Ralph	As per Mr.Montano Principal the door to the concession stand needs to be replace with a ventilated door it gets super hot inside the concession stand and trips the ice makerand fridge Mr.Lara is aware of this work order thanks..								
<u>Ismael Rodriguez</u>									
93976	North Building	Hallway/Corridor			10/10/2012		127		\$0.00
Medium	Work In Progress				10/10/2012 7:29:44 AM				
Castillo, Carlos	Replace electrical outlet where the water fountains connect in the north upper level wires expose thanks..								
<u>Ismael Rodriguez</u>									
90641	North Building	Office			8/3/2012		195		\$0.00
Medium	Work In Progress	REGISTAR			8/3/2012 8:33:52 AM				
Castillo, Carlos	NEED ELECTRICAL OUTLET IN RESTROOM-- AS PER MS LOVELACE'S REQUEST								
<u>Laura Parra</u>									
90913	North Building	Restroom (Girls)			8/7/2012		191		\$0.00
Medium	Work In Progress				8/7/2012 8:41:12 AM				
Castillo, Carlos	Need a electrical outlet in private restroom in north office see Mr.Rodriguez.								
<u>Ismael Rodriguez</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
91364	North Building	Office			8/15/2012		183		\$0.00
Medium	Work In Progress	RECEPTIONIST		8/15/2012 11:34:06 AM					
Prospero, Manuel		1. REMOVE BLIND ATTACHEMENTS 2. PAINT WINDOW FRAMES BLACK 3. PAINT OFFICE							
<u>Laura Parra</u>									
97493	North Building	Office			1/18/2013		27		\$0.00
Medium	Work In Progress			1/18/2013 2:57:59 PM					
Prospero, Manuel		Paint -- Door frame, window frames-black Mens restroom- Light brown Main entrance doors- black							
<u>Laura Parra</u>									
90600	North Building	Cafeteria			8/2/2012		196		\$0.00
Medium	Work In Progress			8/2/2012 1:41:31 PM					
Prospero, Manuel		KITCHEN A/C UNID NEED TO CHANGED CIRCULATION PUMP. IS NOT WORKING.							
<u>Manuel Prospero</u>									
97153	North Building	Parking Lot			1/11/2013		34		\$0.00
Medium	Work In Progress			1/11/2013 7:42:26 AM					
Ontiveros, Guadalupe		Remove dirt with tracter dirt build up by portable ramps and also in North main entrance patio.							
<u>Ismael Rodriguez</u>									
98391	North Building	Classroom			2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 8:34:40 AM					
Ambriz, Jose		The refrigerter in rm #3 in special ed, it is not working need to be check on thanks.							
<u>Ismael Rodriguez</u>									
98401	North Building	Classroom			2/12/2013		2		\$0.00
Medium	Work In Progress	ROOM 3		2/12/2013 11:24:07 AM					
Ambriz, Jose		REFRIGERATOR NOT WORKING							
<u>Laura Parra</u>									
98338	North Building	Hallway/Corridor			2/11/2013		3		\$0.00
Medium	Work In Progress			2/11/2013 8:19:42 AM					
Ambriz, Jose		Replace by-level water fountains in upper and lower level north building hallway.							
<u>Ismael Rodriguez</u>									
95495	North Building	Gym			11/14/2012		92		\$0.00
Medium	Work In Progress			11/14/2012 7:54:10 AM					
Villalobos, David		5 Gallons of cherry mat for drains in the gym and 5 for north and south building thanks..							
<u>Ismael Rodriguez</u>									
2/14/2013 11:25:53 AM									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
98441	North Building	Restroom (Boys)			2/13/2013		1		\$0.00
Medium	Work In Progress				2/13/2013 9:07:02 AM				
Villalobos, David		Five gallons of cherry mat for drains.							
<u>Ismael Rodriguez</u>									
98140	North Building	Parking Lot			2/4/2013		10		\$0.00
Medium	Work In Progress				2/4/2013 7:33:02 AM				
Prospero, Manuel		Remove sand from cafeteria patio.							
<u>Ismael Rodriguez</u>									
98243	North Building	Classroom			2/6/2013		8		\$0.00
Medium	Work In Progress				2/6/2013 8:43:24 AM				
Prospero, Manuel		Rm#16 has wires expose need a cover for fire alarm a.s.a.p.thanks.							
<u>Ismael Rodriguez</u>									
98459	North Building	Cafeteria			2/13/2013		1		\$0.00
Medium	Work In Progress				2/13/2013 12:47:16 PM				
Prospero, Manuel		Put two shelves together for cafeteria manager.							
<u>Ismael Rodriguez</u>									
91685	South Building	Restroom (Boys)			8/22/2012		176		\$0.00
Medium	Work In Progress				8/22/2012 10:58:29 AM				
Prospero, Manuel		Broken water valve to flushvalve needs to be replaced							
<u>Manuel Prospero</u>									
97451	South Building	Classroom			1/17/2013		28		\$0.00
Medium	Work In Progress	ROOM 45			1/17/2013 11:26:33 AM				
Prospero, Manuel		MOUNT SMART BOARD ON THE EAST WALL.							
<u>Laura Parra</u>									
97453	South Building	Classroom			1/17/2013		28		\$0.00
Medium	Work In Progress	ROOM 44			1/17/2013 11:35:39 AM				
Prospero, Manuel		MOUNT SMART BOARD ON EAST WALL							
<u>Laura Parra</u>									
97456	South Building	Classroom			1/17/2013		28		\$0.00
Medium	Work In Progress	ROOM 42			1/17/2013 1:37:57 PM				
Prospero, Manuel		PLEASE MOUNT DUAL BOARD TO WALL							
<u>Parra, Laura</u>									
97580	South Building	Classroom			1/23/2013		22		\$0.00
Medium	Work In Progress	CHOIR ROOM			1/23/2013 8:47:01 AM				
Prospero, Manuel		BROKEN FLOURECENT LIGHT COVER				1/28 - Route to BM asp Cali			
<u>Laura Parra</u>									

2/14/2013 11:25:53 AM



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa MS

95704	South Building	Stairway			11/20/2012		86		\$0.00
Medium	Work In Progress				11/20/2012 12:34:22				

Castillo, Carlos  
The stairway in the South Building going up to the second floor the light is not working as per Manny theres a electrical problem we need the light for safety reasons.

Ismael Rodriguez

97984	South Building	Library			2/1/2013		13		\$0.00
Medium	Work In Progress				2/1/2013 10:06:33 AM				

Castillo, Carlos  
NEED TO REPLACE 4 LIGHTS ON LIBRARY. 250 W. METAL HALIDE.

Manuel Prospero

98337	South Building	Hallway/Corridor			2/11/2013		3		\$0.00
Medium	Work In Progress				2/11/2013 8:15:48 AM				

Ambriz, Jose  
Replacement of water fountain in south building lower level it is in bad condition.

Ismael Rodriguez

97029	South Building	Library			1/8/2013		37		\$0.00
Medium	Work In Progress				1/8/2013 1:12:45 PM				

Carrasco, Danny  
WE NEED LIFT TO FIX HEATERS ON LIBRERIA .

Manuel Prospero

98206	South Building	Office			2/5/2013		9		\$0.00
Medium	Work In Progress	Mr. Medina			2/5/2013 2:14:15 PM				

Lara, Ralph  
The following doors do not close:  
1. Choir room  
2. Lobby doors facing north from the library  
3. Lobby doors office area handicap doors  
4. Lower level emergency stairs  
5. Lower level east end by Ms. Cumplido  
6. Lower level across from Mr. Hernandez  
7. Upper level east end stairway by Mr. Winters

Laura Parra

97526	Gym (1997)				1/22/2013		23		\$0.00
Medium	Work In Progress				1/22/2013 7:56:32 AM				

Prospero, Manuel  
please replace missing hvac louvers and clean the remaining ones. will need to replace the small rectangular and clean the larger 24 x 24. thank you

Michael Munoz

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Santa Teresa MS

98439 Gym (1997) 2/13/2013 1 \$0.00

Medium Work In Progress 2/13/2013 8:40:17 AM

Lara, Ralph  
Need gate key and key for mechanical room on the north east side of the gym for Santa Teresa Middle School. There will be work there starting on Monday, February 18, 2013. Need to check the key out to Justin Armendariz (575-635-7988) or David Hernandez (575-649-6202) with C. D. General For more information contact Ralph Gallegos at 882-6921. Need key by February 14, 2013. Thanks

Rafael Gallegos

93323 Gym (1997) Gym 9/27/2012 140 \$0.00

Medium Work In Progress 9/27/2012 9:15:33 AM

Lara, Ralph  
Rafa the exit door behind the boys dressing room gym area is not handicapp accessabel for the student thats riding a wheel chair, he had a hard time opening the door is there any way you can install a push button door as per administration.

Ismael Rodriguez

97716 Gym (1997) Gym 1/25/2013 20 \$0.00

Medium Work In Progress CONCESSION 1/25/2013 3:21:30 PM

Castillo, Carlos  
CARLOS CASTILLO--  
NEW ELECTRICAL LINE FOR ICE MAKER.  
AS PER MR. JACOBO

Laura Parra

97437 Gym (1997) 1/17/2013 28 \$0.00

High Work In Progress 1/17/2013 6:40:48 AM

Soria, Mike  
please remove sand along curb in the parking lot and remove weeds and sand that are around light poles in the the parking lot as well, also please remove sand on side walk that leads from the parking lot to the gym and clean debre ie soda cans, weeds, rocks etc along this areas well and cleand sidewalk to entrance to gym and surrounding areas.  
thank you

Michael Munoz

98104 2/3/2013 2/9/2013 11 \$0.00

Medium Work In Progress 2/3/2013 12:22:46 AM

Prospero, Manuel  
Monthly - Santa Teresa MS Monthly FE Inspection -  
Refer to PM schedule details.

Margret Villalobos

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
96126					12/2/2012	12/8/2012	74		\$0.00
Medium	Work In Progress				12/2/2012 12:23:18 AM				
Prospero, Manuel	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
96853					1/6/2013	1/12/2013	39		\$0.00
Medium	Work In Progress				1/6/2013 12:24:19 AM				
Prospero, Manuel	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 61 Work Orders</b>		<b>Avg. Age of WO's 64</b>		<b>Total for Santa Teresa MS</b>				<b>0</b>	<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Sunland Park ES

98045					2/3/2013	2/9/2013	11		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress			2/3/2013 12:22:21 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Hernandez, Carlos	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
-------------------	---	--	--	--	--	--	--	--	--

Margret Villalobos

97120					1/10/2013		35		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/10/2013 3:06:08 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Flores, Pete	starter on truck 191 having trouble starter daraging								
--------------	--	--	--	--	--	--	--	--	--

Carlos Hernandez

94495					10/23/2012		114		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress			10/23/2012 3:40:31 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Flores, Pete	need new tires for 970 john deere tractor								
--------------	---	--	--	--	--	--	--	--	--

Carlos Hernandez

98046					2/3/2013	2/11/2013	11		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			2/3/2013 12:22:22 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Hernandez, Carlos	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								
-------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

98047					2/3/2013	2/11/2013	11		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			2/3/2013 12:22:22 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Hernandez, Carlos	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
-------------------	---	--	--	--	--	--	--	--	--

Margret Villalobos

97892					1/30/2013		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/30/2013 3:34:23 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Hernandez, Carlos	need new dewalt hammer drill and battiers also need new acceline touch								
-------------------	--	--	--	--	--	--	--	--	--

Carlos Hernandez

98255					2/6/2013		8		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress	MS.		2/6/2013 10:40:51 AM					
--------	------------------	-----	--	----------------------	--	--	--	--	--

Hernandez, Carlos	CARLOS, CAN YOU PLEASE MOVE THE TELEVISION THAT IS IN MS. GUTIERREZ'S ROOM (20A) AND PLEASE RELOCATE IT TO MS. KENNONS ROOM (11). IF YOU HAVE ANY QUESTIONS, PLEASE LET ME KNOW. THANK YOU, DAVID AVILA								
-------------------	---	--	--	--	--	--	--	--	--

David Avila

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Sunland Park ES

98256					2/6/2013		8		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress	IEP ROOM		2/6/2013 10:43:40 AM					
--------	------------------	----------	--	----------------------	--	--	--	--	--

Hernandez, Carlos AS PER MR. VAN NOSADLE - PLEASE INSTALL A WHITEBOARD IN THE IEP BOARD FOR THE USE OF THE INFOCUS. PLEASE SEE DAVID AVILA FOR DETAILS. THANK YOU.

David Avila

96426					12/10/2012		66		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress			12/10/2012 10:09:35					
--------	------------------	--	--	---------------------	--	--	--	--	--

Orozco, Daniel VEGETABLE SINK IS LEAKING. SNP MANAGER IGNACIA C. 589.2545

Maritza Gonzalez

98170					2/4/2013		10		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			2/4/2013 4:14:08 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Orozco, Daniel DISHWASHER IS NOT RINSING DISHES. SNP MANAGER IGNACIA C. 589.2545

Maritza Gonzalez

98171					2/4/2013		10		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			2/4/2013 4:17:09 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Orozco, Daniel PLEASE CHECK STAND PIECE OF METAL IS MISSING. SNP MANAGER IGNACIA C. 589.2545

Maritza Gonzalez

98172					2/4/2013		10		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			2/4/2013 4:17:37 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Orozco, Daniel OVENS NEED TO BE CHECKED, NOT HOLDING TEMPERATURE. SNP MANAGER IGNACIA C. 589.2545

Maritza Gonzalez

98322					2/10/2013	2/26/2013	4		\$0.00
-------	--	--	--	--	-----------	-----------	---	--	--------

Medium	Work In Progress			2/10/2013 12:20:32 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Hernandez, Carlos Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.

Margret Villalobos

96589		Parking Lot			12/13/2012		63		\$0.00
-------	--	-------------	--	--	------------	--	----	--	--------

Medium	Work In Progress			12/13/2012 1:31:50 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lara, Ralph Need gate key for Sunland Park Elementary. There will be work there over the break. Need to check the key out to Justin Armendariz with C. D. General (575-635-7988). For more information contact Ralph Gallegos at 882-6921. Need key by December 14, 2012. Thanks.

Rafael Gallegos

2/14/2013 11:25:53 AM

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
98474					2/13/2013		1		\$0.00
Medium	Work In Progress				2/13/2013 3:09:52 PM				
Ontiveros, Guadalupe		need fertilizer spreader							
Carlos Hernandez									
97123					1/10/2013		35		\$0.00
Medium	Work In Progress				1/10/2013 3:12:12 PM				
Ontiveros, Guadalupe		need new covers for irrigation valves to soccer field 10 were broken due to vandalism							
Carlos Hernandez									
97742					1/28/2013		17		\$0.00
Medium	Work In Progress				1/28/2013 7:54:20 AM				
Flores, Pete		tire needs repair getting flat drivers side rear tire							
Carlos Hernandez									
97039					1/8/2013		37		\$0.00
Medium	Work In Progress				1/8/2013 3:40:58 PM				
Ambriz, Jose		need new a/c unit 43 area cool contractors replaced roof and unit was no good							
Carlos Hernandez									
98270					2/6/2013		8		\$0.00
Medium	Work In Progress	-BETWEEN			2/6/2013 3:43:48 PM				
Castillo, Carlos		-AS PER MR. MONTES - NEEDS OUTLET TO BE REPAIRED. HE IS UNABLE TO USE THE OUTLET BETWEEN CLASSROOM 38-39-40-41. HE HAS TO RUN EXTENSION CORDS IN ORDER TO GET HIS DAILY WORK DONE. HAS BECOME A SAFETY ISSUE. PLEASE SEE VALERIA OR CARLOS MONTES FOR MORE INFORMATION. THANK YOU.							
David Avila									
98299					2/7/2013		7		\$0.00
Medium	Work In Progress				2/7/2013 3:34:39 PM				
Castillo, Carlos		need to replace outlets don't work in hallway next to room 39 and 41							
Carlos Hernandez									
97836					1/29/2013		16		\$0.00
Medium	Work In Progress				1/29/2013 3:32:32 PM				
Castillo, Carlos		need to replace outlet in hallway north wing not working							
Carlos Hernandez									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
96773					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:41 AM					
Villalobos, David	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
96590					12/13/2012		63		\$0.00
Medium	Work In Progress	CLASSROOM		12/13/2012 1:40:56 PM					
Villalobos, David	AS PER MS. HERRERA - TOILET LEAKING FROM FLUSHING KNOW AND EVERYTIME ONE FLUSHES EVERYTHING COMES BACK AND IT OVERFLOWS. PLEASE CHECK. THANK YOU.								
David Avila									
<b>Count: 23 Work Orders</b>		<b>Avg. Age of WO's 26</b>		<b>Total for Sunland Park ES</b>			<b>0</b>	<b>\$0.00</b>	

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
97065					1/9/2013		36		\$0.00
Medium	Work In Progress			1/9/2013 2:48:30 PM					
Ontiveros, Joe	need replace map sink fouset in kitchen								
<u>Juan Vargas</u>									
93999					10/10/2012		127		\$0.00
Medium	Work In Progress			10/10/2012 2:36:23 PM					
Vargas, Juan	need 10 gls oil paint to painting entry and portables doors								
<u>Juan Vargas</u>									
97496					1/18/2013		27		\$0.00
Medium	Work In Progress			1/18/2013 3:11:50 PM					
Sotelo, Enrique	need fix lights out side round the school								
<u>Juan Vargas</u>									
97937					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 11:59:37 AM					
Vallejo, Albert	Please install door bell, check with site administration for location.								
<u>Richard Chavez</u>									
98330					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress			2/10/2013 12:20:36 AM					
Vargas, Juan	Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98101					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:45 AM					
Apodaca, Mario	Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98479					2/13/2013		1		\$0.00
Medium	Work In Progress			2/13/2013 3:32:52 PM					
Vargas, Juan	need fix water founting								
<u>Juan Vargas</u>									
95584					11/15/2012		91		\$0.00
Scheduled	Work In Progress			11/15/2012 10:53:04					
Vargas, Juan	Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You								



# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
98090					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:40 AM					
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
98091					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:41 AM					
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
98092					2/3/2013		11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:41 AM					
Vargas, Juan	Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
98187					2/5/2013		9		\$0.00
Medium	Work In Progress			2/5/2013 10:00:57 AM					
Vargas, Juan	trees in the bus turn a round need to be trimmed and area needs to be raked. also please trim and rake other areas as needed. thank you								
Michael Munoz									
98089					2/3/2013	2/9/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:40 AM					
Vargas, Juan	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 13 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>28</b>		<b>Total for Sunrise ES</b>	<b>0</b>		<b>\$0.00</b>

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
96783					1/6/2013		39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:45 AM					
Orozco, Daniel	Monthly - Vado ES - Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98251	Main Building	Custodial			2/6/2013		8		\$0.00
Medium	Work In Progress			2/6/2013 10:04:16 AM					
Carbajal, Jimmy	Need vacuum cleaner switch replace serial # 1174 Thank u !								
<u>Armando Diaz</u>									
97527	Main Building	Office			1/22/2013		23		\$0.00
Medium	Work In Progress			1/22/2013 8:30:35 AM					
Lozoya, Manny	NEED 3 F1 KEYS AND 1 STORAGE DOOR KEY								
<u>Debra Facio</u>									
94699					10/29/2012		108		\$0.00
Medium	Work In Progress			10/29/2012 9:58:15 AM					
Orozco, Daniel	EXHAUST FAN OVER OVENS IS NOT WORKING.SNP MANAGER EVA M. 233.2945								
<u>Maritza Gonzalez</u>									
93941					10/9/2012		128		\$0.00
Medium	Work In Progress			10/9/2012 2:31:56 PM					
Miranda, Danny	please install new soccer goals when purchased. thank you								
<u>Michael Munoz</u>									
98323					2/10/2013	2/26/2013	4		\$0.00
Medium	Work In Progress			2/10/2013 12:20:32 AM					
Miranda, Danny	Monthly - Vado ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98396					2/12/2013		2		\$0.00
Medium	Work In Progress			2/12/2013 10:34:37 AM					
Miranda, Danny	need to replace flush valve in 200-wing boys r.r.								
<u>Danny Miranda</u>									
98053					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:25 AM					
Miranda, Danny	Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
98052					2/3/2013	2/11/2013	11		\$0.00
Medium	Work In Progress			2/3/2013 12:22:24 AM					
Miranda, Danny	Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97306					1/15/2013		30		\$0.00
Medium	Work In Progress			1/15/2013 9:14:04 AM					
Miranda, Danny	need saw horses for front parking lot								
<u>Danny Miranda</u>									
93866					10/8/2012		129		\$0.00
Medium	Work In Progress			10/8/2012 8:46:35 AM					
Flores, Pete	TRUCK # NEED TO CK FRONT RIGHT SIDE NOISE, DRIVERS SIDE DOOR' TRANSMISION LEVER' WINDSHEALD, CATALYTIC CONVERTER								
<u>Danny Miranda</u>									
97934					1/31/2013		14		\$0.00
Medium	Work In Progress			1/31/2013 11:56:14 AM					
Sotelo, Enrique	Please install door bell, check with site administration for location.								
<u>Richard Chavez</u>									
96755					1/6/2013	2/6/2013	39		\$0.00
Medium	Work In Progress			1/6/2013 12:23:33 AM					
Villalobos, David	Yearly - Vado ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93491					9/30/2012	10/21/2012	137		\$0.00
Medium	Work In Progress			9/30/2012 12:30:26 AM					
Orozco, Daniel	Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97079		Office			1/9/2013		36		\$0.00
Medium	Work In Progress			1/9/2013 4:02:57 PM					
Lozoya, Manny	need doors from main lobby to corridors and cafeteria to have locks installed that can be operated from office area. Check with Alfredo Holguin if you have questions								
<u>Alfredo Holguin</u>									
97761					1/28/2013		17		\$0.00
Medium	Work In Progress			1/28/2013 10:37:09 AM					
Lozoya, Manny	NEED A KEY MADE FOR ROOM 205 AND 207								
<u>Debra Facio</u>									

2/14/2013 11:25:53 AM

# 936 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
97344					1/15/2013		30		\$0.00
Medium	Work In Progress				1/15/2013 2:54:22 PM				
Lozoya, Manny	NEED NEW KEYS FOR FRONT DOORS AND OUTSIDE DOORS								
Danny Miranda									
98445					2/13/2013		1		\$0.00
Medium	Work In Progress				2/13/2013 9:51:46 AM				
Solis, Lorenzo	NEED TO REPAIR UNIT IN ROOM 105 UNIT NEEDS TO BE RESET EVERY MORNING AND DURING THE DAY								
Danny Miranda									
97925					1/31/2013		14		\$0.00
Medium	Work In Progress				1/31/2013 9:47:23 AM				
Flores, Pete	NEED TO SERVICE MOWER SHARPEN BLADES AND CHANGE OIL								
Danny Miranda									
<b>Count: 19 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>41</b>				<b>Total for Vado ES</b>	<b>0</b>	<b>\$0.00</b>
<b>Count: 936 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>56</b>				<b>Grand Total</b>	<b>0</b>	<b>\$0.00</b>