

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: Alma Del Valle Daycare										
98506					2/14/2013		20		\$0.00	
Medium	Work In Progress			2/14/2013 7:04:32 AM						
Ontiveros, Guadalupe	NEED SAND FOR DAYCARE SANDBOX. (FRONT OF BUILDING). 5 1/2 FT X 5 1/2 FT WIDE, 1 FT DEEP.									
<u>Adam Montoya</u>										
99310		Classroom			3/4/2013		2		\$0.00	
Medium	Work In Progress			3/4/2013 1:43:31 PM						
Lozoya, Manny	DAYCARE RESTROOM DOOR (RM 108) TOP HINGE IS DAMAGED AND DOOR IS NOT SHUTTING PROPERLY.									
<u>Adam Montoya</u>										
Count: 2 Work Orders		Avg. Age of WO's	11	Total for Alma Del Valle Daycare			0	\$0.00		

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
96401		Classroom			12/7/2012		89		\$0.00
Medium	Work In Progress				12/7/2012 5:01:38 PM				
Vega, David	Please empty and clean rooms 108, 110 and 111 at the Anthony Pre-K building. AVANCE and a SPED Diagnostician will be moving into them around December 12, 2012. For details or questions call Ralph Gallegos at 882-6921. Thanks.								
Rafael Gallegos									
95797					11/26/2012		100		\$0.00
Medium	Work In Progress				11/26/2012 3:48:45 PM				
Nunez, Arturo	CANOPY AT PRE K PLAY AREA NEEDS TO BE REPAIRED OR REPLACED, HAS A PRETTY GOOD SIZE TEAR ON TOP.								
Arturo Nunez									
98657					2/20/2013		14		\$0.00
Medium	Work In Progress				2/20/2013 8:29:05 AM				
Sotelo, Enrique	Please install door bell, check with site administration for location.								
Richard Chavez									
Count: 3 Work Orders			Avg. Age of WO's	68	Total for Anthony - On Track Pre-K (Village)		0		\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
94680					10/26/2012		131		\$0.00
Medium	Work In Progress			10/26/2012 3:48:12 PM					
Sotelo, Enrique	NEED SOME ASSITANCE ON TROUBLE SHOOTING LIGHT FIXTURES ON PRE K. WORK ROOM, HALF OF THE IN ROOM ARE TURNED OFF								
<u>Arturo Nunez</u>									
99340					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 8:21:09 AM					
Sotelo, Enrique	Need some assitance on water fountains elec. g.f.c.i. otulets are tripping often. Main building hallways.								
<u>Arturo Nunez</u>									
99373					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 3:42:46 PM					
Sotelo, Enrique	Need some assitance on trouble shooting emergency lay in lights in alamo building.								
<u>Arturo Nunez</u>									
96759					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:35 AM					
Villalobos, David	Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99094					3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 3:31:58 PM					
Appelzoller, Fred	Need some assitance on repairing exterior water fountains								
<u>Arturo Nunez</u>									
94458					10/22/2012		135		\$0.00
Medium	Work In Progress			10/22/2012 3:51:07 PM					
Appelzoller, Fred	NEED SOME ASSITANCE ON HOT WATER LINE LEAK INTO F.C.U. # 22.								
<u>Arturo Nunez</u>									
99169					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:37 AM					
Villalobos, Hector	Yearly - Anthony ES A10(Heat Pumps)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99170					3/3/2013	4/3/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:37 AM					
Villalobos, Hector	Yearly - Anthony ES R3 (Ref. Unit)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
98993					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:23 AM					
Nunez, Arturo	Yearly - Anthony ES C-11 (Evap.Down)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99024					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 8:18:36 AM					
Lozoya, Manny	Here is a list of names for the Social Workers whom will be needing a gate key. If you have any questions please feel free to contact our office. Thank you, Luz Garcia 575-882-6788								
	ARAGON, CRYSTAL MARIE BACA, MARIBEL HOLGUIN, DEBORAH ANN JACQUEZ-GUILLEN, ERNESTINA MARQUEZ, ANAHI LORENA MARTINEZ, WILMA PORRAS, GEORGINA ELIZABETH RANGEL, VERONICA ROBERTS, RICARDO								
99036					2/28/2013		6		\$0.00
Medium	Work In Progress	SPED OFFICE		2/28/2013 1:36:14 PM					
Solis, Lorenzo	HEATER UNIT IN DATA CLERKS OFFICE IS LEAKING PLEASE CHECK AS SOON AS POSSIBLE.								
<u>Margaret Villalobos</u>									
94859					10/31/2012		126		\$0.00
Medium	Work In Progress			10/31/2012 3:38:26 PM					
Solis, Lorenzo	NEED SOME ASSITANCE ON TROUBLE SHOOTING HIGH DELTA WATER FOR KITCHEN, BURNED DOS NOT COME ON.								
<u>Arturo Nunez</u>									
93782					10/3/2012		154		\$0.00
Medium	Work In Progress	SPED OFFICE		10/3/2012 9:31:24 AM					
Lozoya, Manny	NEED TWO (2) KEYS FOR ROOM 120 (CANNOT READ NUMBER ON DOORKNOB)								
<u>Margaret Villalobos</u>									
98210					2/5/2013		29		\$0.00
Medium	Work In Progress	SPED OFFICE		2/5/2013 3:02:42 PM					
Nunez, Arturo	MOVE FURNITURE IN DIAGNOSTICIAN OFFICE AS INSTRUCTED BY JULIE HERNANDEZ (DR. BLANCA ROLLE)								
<u>Margaret Villalobos</u>									

3/6/2013 4:22:56 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
98211					2/5/2013		29		\$0.00
Medium	Work In Progress	SPED OFFICE			2/5/2013 3:03:21 PM				
Nunez, Arturo		MOVE FILE CABINETS INTO DIAGNOSTICIAN ROOM (SEE JULIE HERNANDEZ)							
Margaret Villalobos									
98213					2/5/2013		29		\$0.00
Medium	Work In Progress	SPED OFFICE			2/5/2013 3:04:01 PM				
Nunez, Arturo		REMOVE OLD SHELVES FROM DIAGNOSTICIAN OFFICE (SEE JULIE HERNANDEZ)							
Margaret Villalobos									
98302					2/7/2013		27		\$0.00
Medium	Work In Progress				2/7/2013 3:40:46 PM				
Nunez, Arturo		NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING.							
Arturo Nunez									
98593					2/19/2013		15		\$0.00
Medium	Work In Progress				2/19/2013 7:57:13 AM				
Nunez, Arturo		A.C.U'S NEED TO BE SERVICED FOR CHANGE OVER FROM HTGING. TO COOLING FOR SEASON.				3/1 - Reroute to BM			
Arturo Nunez									
98611					2/19/2013		15		\$0.00
Medium	Work In Progress				2/19/2013 2:52:10 PM				
Nunez, Arturo		WATER SUPPLY LINES TO A.C. UNITS IN OLD CAF. BUILDING NEED TO BE REPLACED.							
Arturo Nunez									
96999					1/8/2013		57		\$0.00
Medium	Work In Progress	SPED OFFICE			1/8/2013 8:58:52 AM				
Nunez, Arturo		PLEASE HAVE MAINTENANCE FINISH ROOM 120 REMOVE ALL CHALKBOARDS FROM THE HALL AND DISPOSE OF, PAINTING STILL NEEDS TO COMPLETED IN ORDER TO SET UP OFFICE SPACE FOR DIAGNOSTICIAN							
Margaret Villalobos									
96741					1/6/2013	1/14/2013	59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:26 AM				
Nunez, Arturo		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
96740					1/6/2013	1/14/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:25 AM					
Nunez, Arturo	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96328					12/6/2012		90		\$0.00
Medium	Work In Progress	SPED OFFICE		12/6/2012 3:22:16 PM					
Nunez, Arturo	FINISH REMOVING CHALK BOARDS IN ROOM 120 (DISPOSE OF CHALKBOARDS) AND PAINT ROOM 120								
<u>Margaret Villalobos</u>									
96059					12/2/2012	12/10/2012	94		\$0.00
Medium	Work In Progress			12/2/2012 12:22:50 AM					
Nunez, Arturo	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99132					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:21 AM					
Nunez, Arturo	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99131					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:20 AM					
Nunez, Arturo	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95023					11/4/2012	11/12/2012	122		\$0.00
Medium	Work In Progress			11/4/2012 12:19:13 AM					
Nunez, Arturo	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
94354					10/19/2012		138		\$0.00
Medium	Work In Progress	SPED OFFICE		10/19/2012 9:00:43 AM					
Nunez, Arturo	MOVE OFFICE DESK FROM J. HERNANDEZ OFFICE TO DIAGNOSTICIANS OFFICE/MOVE DESK FROM DIAGNOSTICIAN OFFICE TO JULIE HERNANDEZ OFFICE (SEE JULIE HERNANDEZ OR MARGARET)								
<u>Margaret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
98807					2/25/2013		9		\$0.00
Medium	Work In Progress	SPED OFFICE		2/25/2013 10:34:38 AM					
Nunez, Arturo	REMOVE CHALKBOARD IN DIAGNOSTICIANS ROOM ON THE FAR LEFT SIDE WALL								
Margaret Villalobos									
98808					2/25/2013		9		\$0.00
Medium	Work In Progress	SPED OFFICE		2/25/2013 10:35:26 AM					
Nunez, Arturo	MOVE BLANCA ROLLE'S DESK IN DIAGNOSTIANS OFFICE TO THE RIGHT CORNER BY THE DOOR								
Margaret Villalobos									
98809					2/25/2013		9		\$0.00
Medium	Work In Progress	SPED OFFICE		2/25/2013 10:36:15 AM					
Nunez, Arturo	REMOVE STORAGE CABINETS IN A. SANCHEZ OFFICE AND MOVE TO DIAGNOSTICIAN OFFICE								
Margaret Villalobos									
98810					2/25/2013		9		\$0.00
Medium	Work In Progress	SPED OFFICE		2/25/2013 10:39:37 AM					
Nunez, Arturo	REMOVE CABINETS FROM STORAGE ROOM AND INSTALL IN DIAGNOSTICIANS ROOM								
Margaret Villalobos									
98846					2/25/2013		9		\$0.00
Medium	Work In Progress			2/25/2013 3:51:48 PM					
Nunez, Arturo	02/25/13 1.0 SIGN IN PAPER WORK. 1.0 CHECKED BOILERS. 1.30 CHECKED A.C.U. 3 FOR ROOMS # 262,284. ROOMS TO COLD. TROUBLE SHOOT UNIT, R/R V BELT. AX 63 1 EA. @ \$10.99. .30 EVALUATION W/ MIKE MUNOZ. 3.0 W.O. # 94404. 1.0 W.O. # 98761.								
Arturo Nunez									
98756					2/22/2013		12		\$0.00
Medium	Work In Progress			2/22/2013 11:35:07 AM					
Vega, David	please deliver TE 4x2 electric gator UV-AE-0903 and charging cord. david please review manual and cd as well as your staff and turn in w/o when done thank you								
Michael Munoz									
98963					2/27/2013		7		\$0.00
Medium	Work In Progress			2/27/2013 3:45:06 PM					
Ontiveros, Guadalupe	Need two loads of crusher fine for pre k student pick up area, and have parking log dragged.								
Arturo Nunez									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
92595					9/10/2012		177		\$0.00
Medium	Work In Progress			9/10/2012 8:13:09 AM					
Flores, Pete	400 A-E need oil, oil filter for 935								
<u>Hector Villalobos</u>									
98668					2/20/2013		14		\$0.00
Medium	Work In Progress			2/20/2013 2:07:37 PM					
Lozoya, Manny	Asp Giovas, need to open Old Cafe for Danny & Fernando.								
<u>Demetrious Giovas</u>									
99215					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:57 AM					
Munoz, Michael	Yearly - Anthony ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95549					11/14/2012		112		\$0.00
Medium	Work In Progress			11/14/2012 3:48:20 PM					
Apodaca, Mario	AS PER MS. PEREZ , REQUESTING FOR WTAER FILTER BE INSTALLED FOR DOMESTIC WATER LINE.								
<u>Arturo Nunez</u>									
98870					2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 10:23:03 AM					
Orozco, Daniel	SLICER IS NOT WORKING, TURNS ON BUT DOES NOT SLICE. SNP MANAGER BECKY S. 882.3507								
<u>Maritza Gonzalez</u>									
92466					9/6/2012		181		\$0.00
Medium	Work In Progress			9/6/2012 1:00:10 PM					
Orozco, Daniel	DISHWASHER WASH IN WASH MODE AND STOPPED WORKING. SNP MANAGER BECKY S. 882.3507								
<u>Maritza Gonzalez</u>									
99130					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:20 AM					
Nunez, Arturo	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96779					1/6/2013		59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:43 AM					
Orozco, Daniel	Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
98561	Main Building				2/15/2013		19		\$0.00
Medium	Work In Progress				2/15/2013 11:16:22 AM				
Carbajal, Jimmy	vacuum cleaner serial # 00053 ex cord needs repair								
<u>David Vega</u>									
99306	Main Building				3/4/2013		2		\$0.00
Medium	Work In Progress				3/4/2013 12:46:43 PM				
Carbajal, Jimmy	need vacuum cleaner bag								
<u>David Vega</u>									
96992	Main Building				1/8/2013		57		\$0.00
Medium	Work In Progress				1/8/2013 8:22:43 AM				
Sotelo, Enrique	some outside lights are not turning on in main building, and new addition, also street light coming in school entry not turning on								
<u>David Vega</u>									
97004	Main Building				1/8/2013		57		\$0.00
Medium	Work In Progress				1/8/2013 9:34:08 AM				
Appelzoller, Fred	water fountain on eastside of new addition does not turn off, keeps running								
<u>David Vega</u>									
98852	Main Building				2/26/2013		8		\$0.00
Medium	Work In Progress				2/26/2013 5:05:41 AM				
Lozoya, Manny	change core in morgan storage to k or h master so that custodians can have access to gator								
<u>David Vega</u>									
96989	Main Building	Classroom			1/8/2013		57		\$0.00
Medium	Work In Progress				1/8/2013 8:19:24 AM				
Solis, Lorenzo	no heat in rooms 103, 104, 108, 111, speech therapy, and pre k office, upper primary (village)								
<u>David Vega</u>									
98791	Main Building				2/25/2013		9		\$0.00
Medium	Work In Progress				2/25/2013 7:59:55 AM				
Sotelo, Enrique	need electrical outlet installed in morgan building, so gator can be charged								
<u>David Vega</u>									
98761	Cafeteria	Cafeteria			2/22/2013		12		\$0.00
Medium	Work In Progress				2/22/2013 1:39:15 PM				
Nunez, Arturo	please paint cafeteria as per our meeting. this has to be done before spring break. thank you								
Michael Munoz									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
96354	Original Main				12/7/2012		89		\$0.00
Medium	Work In Progress				12/7/2012 8:31:03 AM				
Sotelo, Enrique	outside lights in old primary building and old cafeteria not turning on at night need to be checked out								
<u>David Vega</u>									
99002					2/28/2013		6		\$0.00
Medium	Work In Progress				2/28/2013 12:28:27 AM				
Munoz, Michael	Yearly - Anthony ES - Fire Pump Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91739	Pump House				8/23/2012		195		\$0.00
Medium	Work In Progress				8/23/2012 9:52:41 AM				
Gonzalez, Salvador	upper primary pump house tank is leaking								
<u>Hector Villalobos</u>									
Count: 54 Work Orders		Avg. Age of WO's 47		Total for Anthony ES			0	\$0.00	

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
99003					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:28 AM					
Munoz, Michael	Yearly - Berino ES - Fire Pump Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98592					2/15/2013		19		\$0.00
Medium	Work In Progress			2/15/2013 4:05:21 PM					
Ronquillo, Ruben	Fire Pump - Need quote to replace batteries asp last PM 96719 Service.		2/19 - Email Cummins Rocky Mountain for Quote						
<u>Adan Duran</u>									
96785					1/6/2013	1/27/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:46 AM					
Orozco, Daniel	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99112					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:11 AM					
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99074					3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 11:11:00 AM					
Orozco, Daniel	GARBAGE DISPOSAL IS CLOGGED. SNP MANAGER ELSA C. 882.2417								
<u>Maritza Gonzalez</u>									
98759		Cafeteria			2/22/2013		12		\$0.00
Medium	Work In Progress			2/22/2013 1:36:47 PM					
Gonzalez, Salvador	please wled west window on door as per our conversation. this has to be done before spring break thank you								
<u>Michael Munoz</u>									
97927					1/31/2013		34		\$0.00
Medium	Work In Progress			1/31/2013 10:17:48 AM					
Lozoya, Manny	MR MANNY LOZOYA SIR NEED THE KEY CORE INSTALL DOOR ROOM 138 IT IS MISSING THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
99216					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:58 AM					
Munoz, Michael	Yearly - Berino ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
3/6/2013 4:22:56 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
94887					11/1/2012		125		\$0.00
Medium	Work In Progress			11/1/2012 10:52:35 AM					
Lozoya, Manny	put 2 key cores on muntin in the 2 lobbys								
Jimmy Cortez									
96217					12/4/2012		92		\$0.00
Medium	Work In Progress			12/4/2012 8:19:14 AM					
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR NEED TO CLEAN AND DRESS UP PONDING AREA EAST SIDE BOTTOM FULL OF DIRT THANK YOU SIR AND GOD BLESS								
Adan Duran									
99017					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:34 AM					
Sanchez, Raul	Monthly - Berino ES - Monthly Meter Readings - Refer to PM schedule details.								
Margret Villalobos									
97940					1/31/2013		34		\$0.00
Medium	Work In Progress			1/31/2013 1:10:58 PM					
Duran, Adan	MR A-DURAN AS PER MR VALTIERRA NEED TO MAKE SIGNS FOR ALL ENTRANCE FOR PARENTS TO REPORT TO FRONT OFFICE 10 EA ALSO NEED TWO SIGNS NO PARKING ANY TIME THANK YOU SIR								
Adan Duran									
99116					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:13 AM					
Duran, Adan	Monthly - Berino ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
99113					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:12 AM					
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
99114					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:12 AM					
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
95215					11/6/2012		120		\$0.00
Medium	Work In Progress			11/6/2012 8:20:10 AM					
Lozoya, Manny	MANNY LOZOYA PER MR VALTIERRA MANNY NEED TO INSTALL A DEAD-BOLT MAIN ENTRANCE TO LIBRARY FOR BETTER SECURITY THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
95628					11/16/2012		110		\$0.00
Medium	Work In Progress			11/16/2012 2:06:10 PM					
Lozoya, Manny	NEED A LOCK AND KEY FOR THE GATE DRAINAGE POND AREA.								
<u>Maribel Chavez</u>									
94300		Office			10/18/2012		139		\$0.00
Medium	Work In Progress	OFFICE		10/18/2012 9:41:51 AM					
Lozoya, Manny	OFFICE- FOR MANNY LOZOYA- I NEED A NEW NAME PLATE MARIBEL GAMBOA. THANK YOU								
<u>Maribel Chavez</u>									
99115					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:12 AM					
Duran, Adan	Yearly - Berino ES A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98983					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:18 AM					
Duran, Adan	Yearly - Berino ES C-11 (Evap.Down)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96600					12/13/2012		83		\$0.00
Medium	Work In Progress			12/13/2012 3:03:45 PM					
Ontiveros, Joe	MR FRED APPELLOZER SIR THE WATER HEATER PORTABLE 155&156 SMALL WATER HEATER IS TO HOT NEED TO ADJUST HOT WATER HEADSTART KIDS THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
98891					2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 2:46:15 PM					
Appelzoller, Fred	MR FRED APPELZOLLAR SIR THE LITTLE WATER HEATER IN PORTABLE 155&156 IS NOT WORKING NEED TO BE REPLACE ALSO THE WATER FACET IS LEAKING NEED REPLACING								
<u>Adan Duran</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
98898					2/26/2013		8		\$0.00
Medium	Work In Progress				2/26/2013 2:56:19 PM				
Appelzoller, Fred	FRED APPELLZOLLAR THE FAUCET IN GIRLS GANG RESTROOM ARE LOSE THE NUT THAT HOLD THE FAUCET DOWN IS MISSING NEED TO REPLACE THANK YOU SIR AND GOD BLESS								
Adan Duran									
96760					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:36 AM				
Villalobos, David	Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
98617					2/19/2013		15		\$0.00
Medium	Work In Progress				2/19/2013 3:16:39 PM				
Sotelo, Enrique	MR ENRIQUE SOTELO SIR THE OUT SIDE LIGHTS ARE NOT WORKING PORTABLE 155&156 CHANGE OUT LIGHT BUBLS ALSO MORGAN BUILDING MAY BE SENCOR THANK YOU SIR AND GOD BLESS								
Adan Duran									
Count: 25 Work Orders		Avg. Age of WO's 38			Total for Berino ES			0	\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
94654					10/26/2012		131		\$0.00
Medium	Work In Progress				10/26/2012 2:50:41 PM				
Sotelo, Enrique	no power to heating units in main wing,chk breakers all are on checked for loose wires.								
Paul Quinones									
96758					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:35 AM				
Villalobos, David	Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
95830					11/27/2012		99		\$0.00
Medium	Work In Progress				11/27/2012 3:15:19 PM				
Ontiveros, Joe	outside water fountain leaking from behind wall in front of e-wing.								
Paul Quinones									
95374					11/9/2012		117		\$0.00
Medium	Work In Progress				11/9/2012 2:19:25 PM				
Ontiveros, Joe	requesting new valves for a/c water shut off for winter shut down in wing 4oo.thanks								
Paul Quinones									
99396					3/6/2013		0		\$0.00
Medium	Work In Progress				3/6/2013 9:20:13 AM				
Ontiveros, Joe	floor drain clogged in kitchen								
Paul Quinones									
95739					11/20/2012		106		\$0.00
Medium	Work In Progress				11/20/2012 3:50:37 PM				
Solis, Lorenzo	REQUESTING LIMIT SWITCHES FOR WALL HEATERS								
Paul Quinones									
98902					2/26/2013		8		\$0.00
Medium	Work In Progress				2/26/2013 3:08:13 PM				
Lozoya, Manny	2-26-13 COULD YOU PLEASE RECUT SOME KEYS,SO TEACHERS COULD OPEN AND SECURE DOORS.THANKS								
Paul Quinones									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
99068					3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 8:02:53 AM					
Lozoya, Manny	need cam locks to secure file cabinets for teachers in rm.207 requesting 3 cam locks thank you very much have a good day.								
Paul Quinones									
98818					2/25/2013		9		\$0.00
Medium	Work In Progress			2/25/2013 1:25:31 PM					
Quinones, Paul	TOUCH UP OUTSIDEWALL NEW WINDOW WAS INSTALLED BY CONTRACTOR IN RM.509.WILL USE UNICOAT STUCCO								
Paul Quinones									
99342					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 8:54:48 AM					
Quinones, Paul	NEED OIL BASE PAINT TO PAINT DOOR FRAMES FRONT OFFICE HALLWAY								
Paul Quinones									
98339					2/11/2013		23		\$0.00
Medium	Work In Progress			2/11/2013 8:30:32 AM					
Quinones, Paul	REQUESTING PAINT PRINCIPLE REQUESTING HALLWAY,AND BATHROOMS TO BE PAINTED.								
Paul Quinones									
99011					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:31 AM					
Quinones, Paul	Yearly - Chaparral ES C-11 Evap (Annual) - Refer to PM schedule details.								
Margret Villalobos									
99012					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:31 AM					
Quinones, Paul	Monthly - Chaparral ES A-16 Exh Fan (Semi Annual) - Refer to PM schedule details.								
Margret Villalobos									
99254					3/3/2013	3/24/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:15 AM					
Quinones, Paul	Monthly - Chaparral ES H-11 Unit Heater Semiannual - Refer to PM schedule details.								
Margret Villalobos									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral ES									
99255					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:15 AM					
Quinones, Paul	Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99256					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:16 AM					
Quinones, Paul	Yearly - Chaparral ES A-10 HP Rooftop Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92134					8/31/2012		187		\$0.00
Medium	Work In Progress			8/31/2012 12:24:24 AM					
Quinones, Paul	Monthly - Chaparral ES A-16 Exh Fan (Semi Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95651					11/16/2012		110		\$0.00
Medium	Work In Progress			11/16/2012 4:32:03 PM					
Martinez, Larry	relocate furniture from che to san miguel for storage.								
<u>Paul Quinones</u>									
98332					2/10/2013	2/26/2013	24		\$0.00
Medium	Work In Progress			2/10/2013 12:20:37 AM					
Quinones, Paul	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98508					2/14/2013		20		\$0.00
Medium	Work In Progress			2/14/2013 7:56:03 AM					
Ontiveros, Guadalupe	water valves leaking shut off both water valves in front of school in hot box								
<u>Paul Quinones</u>									
98706					2/21/2013		13		\$0.00
Medium	Work In Progress			2/21/2013 8:09:12 AM					
Ontiveros, Guadalupe	please airate soccer field, and fertilize as well thank you								
<u>Paul Quinones</u>									
98708					2/21/2013		13		\$0.00
Medium	Work In Progress			2/21/2013 8:11:03 AM					
Ontiveros, Guadalupe	irrigation booster pump motor burned shorted out								
<u>Paul Quinones</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
98887					2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 1:51:12 PM					
Flores, Pete	REQUESTING WEED WACKER OVERHAUL THANKS!								
Paul Quinones									
91935					8/28/2012		190		\$0.00
Medium	Work In Progress			8/28/2012 8:14:56 AM					
Quinones, Paul	INSTALL DRIP SECTION FOR PINE TREES IN BETWEEN E-WING AND THE 400 WING FOR WATERING. WATERING HAS BEEN W/ THE WATER HOSE.								
Paul Quinones									
94038					10/11/2012		146		\$0.00
High	Work In Progress			10/11/2012 7:27:40 AM					
Quinones, Paul	new furniture came in and needs to be assembled. thank you								
Michael Munoz									
98817					2/25/2013		9		\$0.00
Medium	Work In Progress			2/25/2013 1:13:12 PM					
Quinones, Paul	SECTION OF EXTERIOR WALL NEEDED FOR NEW DOOR IN THE CONSESSION ENTRANCE								
Paul Quinones									
97589					1/23/2013		42		\$0.00
Medium	Work In Progress			1/23/2013 11:13:35 AM					
Quinones, Paul	REQUESTING REPAIR KITS TANK TO BOWL KIT FLUID MASTER PRO 45 FILL VALVES WAX RING FOR RESTOCK @ CHE								
Paul Quinones									
99250					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:13 AM					
Quinones, Paul	Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
98342					2/11/2013		23		\$0.00
Medium	Work In Progress			2/11/2013 8:45:59 AM					
Quinones, Paul	REQUESTING PVC PIPE, AND 1/2" PVC FITTINGS FOR A/C WATER LINE FOR WINGS 400, AND E-WING								
Paul Quinones									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
96360					12/7/2012		89		\$0.00
Medium	Work In Progress			12/7/2012 8:48:11 AM					
Quinones, Paul	requesting a spool of 3/8"rope								
Paul Quinones									
95472					11/13/2012		113		\$0.00
Medium	Work In Progress			11/13/2012 3:37:29 PM					
Quinones, Paul	BAD GAS VALVE IN ONE OF THE HEATERS IN 200 WING RM. 205,REQUESTING A COUPLE OF VALVES 1 FOR SPARE.								
Paul Quinones									
95567					11/15/2012		111		\$0.00
Scheduled	Work In Progress			11/15/2012 10:34:17					
Quinones, Paul	Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You								
99252					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:14 AM					
Quinones, Paul	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
98886					2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 1:46:18 PM					
Lozoya, Manny	DOUBLE DOORS,DOOR FRAME BEND AND DOOR IS RIPPED ON THE UPPER LEFT SIDE OF THE DOOR LOCATED NEXT TO THE CAFETERIA.								
Paul Quinones									
99321					3/4/2013		2		\$0.00
Medium	Work In Progress			3/4/2013 3:40:16 PM					
Lozoya, Manny	door in rm.512 door needs to be forced open and shut								
Paul Quinones									
98472					2/13/2013		21		\$0.00
Medium	Work In Progress			2/13/2013 2:23:16 PM					
Lozoya, Manny	REQUESTING DOOR AND DOOR FRAME TO SECURE SCHOOL SUPPLIES AND FOR STORAGE USE.								
Paul Quinones									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
99029		Custodial			2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 10:04:13 AM					
Carbajal, Jimmy		need;to;fix;water;vac;advance;a;w;d;1320;number;1024 128942;							
Daniel Ramirez									
99217					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:58 AM					
Munoz, Michael		Yearly - Chaparral ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
99251					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:14 AM					
Quinones, Paul		Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
97957					1/31/2013		34		\$0.00
Medium	Work In Progress			1/31/2013 3:50:28 PM					
Gonzalez, Salvador		NEED METAL FRAME TO REPLACE THE WOOD FRAME,AND A 1/16 DIAMOND PLATE TO COVER THE WATER SUPPLY AND PLUMBING TO THE WATER FOUNTAIN FOR PROTECTION.							
Paul Quinones									
97638					1/24/2013		41		\$0.00
Medium	Work In Progress			1/24/2013 10:29:42 AM					
,		NEED TO REPLACE COVEBASE IN (2) HALLWAYS - LABOR ONLY, WE HAVE THE MATERIAL.							
Jesus Estrada									
96356					12/7/2012		89		\$0.00
Medium	Work In Progress			12/7/2012 8:40:15 AM					
Quinones, Paul		requesting transition strip to repair carpet to tile edges in class rooms.							
Paul Quinones									
96926					1/7/2013		58		\$0.00
Medium	Work In Progress			1/7/2013 11:46:06 AM					
Estrada, Jesus		CARPET NEEDS TO BE REPLACED IN PORTABLE #572							
Jesus Estrada									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral ES									
96945	Main Building	Classroom			1/7/2013		58		\$0.00
Medium	Work In Progress	gym			1/7/2013 2:33:45 PM				
Lozoya, Manny need keys for coaches N69 please see Nava and Flores									
Jennifer Corral									
97031	Main Building	Hallway/Corridor			1/8/2013		57		\$0.00
Medium	Work In Progress	whole school			1/8/2013 2:14:58 PM				
Lozoya, Manny main doors going to protables need to be rekeyed so teachers may open with their keys. See Administration									
Jennifer Corral									
99304	Main Building	Classroom			3/4/2013		2		\$0.00
High	Work In Progress	WHOLE			3/4/2013 12:23:55 PM				
Villalobos, Margret need school especially main office fumigated. restrooms as well little bugs are back. See Administration									
Jennifer Corral									
99253					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:26:15 AM				
Quinones, Paul Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.									
Margret Villalobos									
Count: 47 Work Orders		Avg. Age of WO's 44			Total for Chaparral ES			0	\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
99004					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:28 AM					
Munoz, Michael	Yearly - Chaparral HS - Fire Pump Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99034	Pre-K	Classroom			2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 11:27:30 AM					
Ortiz, Alfredo	Need to clean return air vents in classroom floors and replace air filters in units.								
<u>Alfredo Ortiz</u>									
98864	Pre-K	Hallway/Corridor			2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 9:30:49 AM					
Ortiz, Alfredo	Need to seal all around building sand coming in.								
<u>Alfredo Ortiz</u>									
96443	Pre-K				12/10/2012		86		\$0.00
Medium	Work In Progress			12/10/2012 3:07:05 PM					
Gonzalez, Salvador	Need to repaid gate door, lach broken.								
<u>Alfredo Ortiz</u>									
98748	A-Wing	Hallway/Corridor			2/22/2013		12		\$0.00
Medium	Work In Progress			2/22/2013 9:18:13 AM					
Ortiz, Alfredo	Need to install trim between Main hallway and wings trip hazard.								
<u>Alfredo Ortiz</u>									
97305	A-Wing	Classroom			1/15/2013		50		\$0.00
Medium	Work In Progress			1/15/2013 8:54:25 AM					
Lozoya, Manny	Mrs. Vega's door is hard to open with key. She is located in the counselors area in front office.								
<u>Mireya Meza</u>									
98979	A-Wing	Classroom			2/27/2013		7		\$0.00
Medium	Work In Progress			2/27/2013 4:40:56 PM					
Lozoya, Manny	Replace metal shelves with cabinets like in athletic training room in field house with locks. (Mr. Beets)								
<u>Mireya Meza</u>									
99032	A-Wing	Cafeteria			2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 11:23:39 AM					
Ontiveros, Joe	Need to replace cracked toilet in kitchen.								
<u>Alfredo Ortiz</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral HS								
99400	A-Wing	Library			3/6/2013		0		\$0.00	
Medium	Work In Progress			3/6/2013 10:59:01 AM						
Lozoya, Manny		Need key for the security bar in main library door. (Ms. Mays)								
Mireya Meza										
96907	A-Wing	Cafeteria			1/7/2013		58		\$0.00	
Medium	Work In Progress			1/7/2013 8:42:27 AM						
Lozoya, Manny		Cafeteria doors lach don't work 3 doors.								
Alfredo Ortiz										
96529	A-Wing	Hallway/Corridor			12/12/2012		84		\$0.00	
Medium	Work In Progress			12/12/2012 8:57:47 AM						
Lozoya, Manny		Outer door lock will not open with key. Door is 3rd outer door from nurse's office, between CAP class and ISS class. (Ms. Lopez)								
Mireya Meza										
98943	A-Wing	Hallway/Corridor			2/27/2013		7		\$0.00	
Medium	Work In Progress			2/27/2013 1:37:32 PM						
Lozoya, Manny		Need to replace door exit device, Won't open with key. Exit door A-wing between A105 and A106. Also one in Cafeteria.								
Alfredo Ortiz										
97472	A-Wing	Office			1/17/2013		48		\$0.00	
Medium	Work In Progress			1/17/2013 3:52:19 PM						
Lozoya, Manny		We need a CHS key for our permanent security guard. (Mireya Meza)				1/23/13 - ASP CHUY, CHECK STATUS ON KEY. ASP JESSIE/CHUY, NEED 2 KEYS, ASP MIREYA - MANNY ISSUED 2 KEYS TO HER.				
Mireya Meza										
98147	A-Wing	Athletic Field			2/4/2013		30		\$0.00	
Medium	Work In Progress			2/4/2013 10:26:26 AM						
Valdez, Pedro		The softball outfield fence on the left side needs to be fixed. It is lifted and balls go right under it. (Coach E. Guerrero)								
Mireya Meza										
98262	A-Wing				2/6/2013		28		\$0.00	
Medium	Work In Progress			2/6/2013 12:34:08 PM						
Lara, Ralph		Need to fix or replace door lock can't open with key.								
Alfredo Ortiz										
96585	D-Wing	Classroom			12/13/2012		83		\$0.00	
Medium	Work In Progress			12/13/2012 11:39:45						
Solis, Lorenzo		Having problem with D-Sped heater								
Alfredo Ortiz										
3/6/2013 4:22:56 PM										

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
97692	Q-Wing	Classroom			1/25/2013		40		\$0.00
Medium	Work In Progress			1/25/2013 8:25:37 AM					
Ortiz, Alfredo	Requesting the interance to the shop be painted.								
<u>Alfredo Ortiz</u>									
99405	Q-Wing	Classroom			3/6/2013		0		\$0.00
Medium	Work In Progress			3/6/2013 1:09:40 PM					
Ortiz, Alfredo	Need to paint and seal Q-4 welding shop Floor. Coaches use that room. to much dust.								
<u>Alfredo Ortiz</u>									
98453	Q-Wing	Classroom			2/13/2013		21		\$0.00
Medium	Work In Progress			2/13/2013 12:09:49 PM					
Sotelo, Enrique	Need to install new air compresor for mechanic shop. Need new electrical set up.								
<u>Alfredo Ortiz</u>									
97691	Q-Wing	Classroom			1/25/2013		40		\$0.00
Medium	Work In Progress			1/25/2013 8:17:46 AM					
Ortiz, Alfredo	Need to order and repair air compresor in Q-2 Construction room.								
<u>Alfredo Ortiz</u>									
98715	Q-Wing	Classroom			2/21/2013		13		\$0.00
Medium	Work In Progress			2/21/2013 11:53:11 AM					
Ortiz, Alfredo	Room Q4 has a leak from the ceiling. This is the room where wrestling practice takes place.								
<u>Mireya Meza</u>									
98933	R-Wing	Classroom			2/27/2013		7		\$0.00
Medium	Work In Progress			2/27/2013 9:10:34 AM					
Ortiz, Alfredo	Need to replace ceiling tiles and light bulbs in Q and R-building								
<u>Alfredo Ortiz</u>									
94898	R-Wing	Classroom			11/1/2012		125		\$0.00
Medium	Work In Progress			11/1/2012 11:59:27 AM					
Lozoya, Manny	Door handle to storeroom in R1 has broken. Needs to be replaced. (Mr. Gabaldon)								
<u>Mireya Meza</u>									
93777	Field House	Athletic Field			10/3/2012		154		\$0.00
Medium	Work In Progress			10/3/2012 7:29:03 AM					
Gonzalez, Salvador	Please put permanent shade in socccer fields. (Arnold Orozco)								
<u>Mireya Meza</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
89726	Field House	Athletic Field			7/10/2012		239		\$0.00
Medium	Work In Progress				7/10/2012 4:23:59 PM				
Valdez, Pedro	We need 8 sets of tires attached to the soccer goals to make them mobile.								
<u>Mireya Meza</u>									
98978	Field House	Athletic Field			2/27/2013		7		\$0.00
Medium	Work In Progress				2/27/2013 4:36:22 PM				
Flores, Pete	Need 2 batteries for the athletic training gator. Might need 8 now since other 6 do not charge at all. (Mr. Beets)								
<u>Mireya Meza</u>									
98458	Field House				2/13/2013		21		\$0.00
Medium	Work In Progress				2/13/2013 12:39:16 PM				
Ortiz, Alfredo	Need to order filters and replace on A/C units in field house and Q, and R-wing also repair drain lines.								
<u>Alfredo Ortiz</u>									
98980	H-Wing	Classroom			2/27/2013		7		\$0.00
Medium	Work In Progress				2/27/2013 4:42:47 PM				
Munoz, Michael	Expand athletic training room in gym by knocking down north wall and building larger athletic training room. Unable to do complete therapies on injured athletes. (Mr. Beets)								
<u>Mireya Meza</u>									
99123					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:16 AM				
Ortiz, Alfredo	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96780					1/6/2013		59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:43 AM				
Orozco, Daniel	Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96352		Pump House			12/7/2012		89		\$0.00
Medium	Work In Progress				12/7/2012 7:58:18 AM				
Munoz, Michael	Having problem with the fire pump								
<u>Alfredo Ortiz</u>									
96784					1/6/2013		59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:45 AM				
Orozco, Daniel	Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
3/6/2013 4:22:56 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
99124					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:17 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97357		Parking Lot			1/15/2013		50		\$0.00
Medium	Work In Progress			1/15/2013 3:43:06 PM					
Munoz, Michael	Need to install new gates with signs for traffic controll exiting noth parking lot.								
<u>Alfredo Ortiz</u>									
97252					1/14/2013		51		\$0.00
Medium	Work In Progress			1/14/2013 12:40:24 PM					
Munoz, Michael	Need to send someone to build a wall to keep sand from collecting in front of healthroom.								
<u>Alfredo Ortiz</u>									
92673		Cafeteria			9/11/2012		176		\$0.00
Medium	Work In Progress			9/11/2012 11:14:39 AM					
Gonzalez, Salvador	Need to create some kind of shade for the students at the sitting area. (Lupe Quinones)								
<u>Mireya Meza</u>									
98689		Hallway/Corridor			2/20/2013		14		\$0.00
Medium	Work In Progress			2/20/2013 3:49:51 PM					
Ortiz, Alfredo	Need to replace door sweeps around school campus.								
<u>Alfredo Ortiz</u>									
90833					8/6/2012		212		\$0.00
Medium	Work In Progress			8/6/2012 10:03:59 AM					
Gonzalez, Salvador	Need to weld Soccer Goals								
<u>Guadalupe Ontiveros</u>									
96024		Athletic Field			11/30/2012		96		\$0.00
Medium	Work In Progress			11/30/2012 3:38:16 PM					
Gonzalez, Salvador	please order material for install of new scoreboards .baseball / softball.thank you								
<u>Michael Munoz</u>									
96587		Parking Lot			12/13/2012		83		\$0.00
Medium	Work In Progress			12/13/2012 11:46:18					
Gonzalez, Salvador	I also need a metal stop bar that comes from the end of the fence that also includes a seperate pole so that driving access can be denied because the students and parents are cutting off the busses as they are driving off. Please see Lupe Quinones for location.								
<u>Mireya Meza</u>									

3/6/2013 4:22:56 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
98100					2/3/2013		31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:44 AM					
Apodaca, Mario	Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99209					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:55 AM					
Apodaca, Mario	Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92677					9/11/2012		176		\$0.00
Medium	Work In Progress			9/11/2012 11:25:49 AM					
Apodaca, Mario	Need to install base to mount pump hoist in amphitheater lift station.								
<u>Albert Vallejo</u>									
99232					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:05 AM					
Munoz, Michael	Yearly - Chaparral HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99080					3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 12:24:47 PM					
Carbajal, Jimmy	Advance terra 3700b auto sweeper batteries do not take charge.								
<u>Jesus Urquidi</u>									
93161					9/24/2012		163		\$0.00
Medium	Work In Progress			9/24/2012 9:14:21 AM					
Carbajal, Jimmy	auto scrubber sn 8000062994 scrub brush does not turn also loosing power very quickly.					11/30/12 - ASP JIMMY, NEEDS TO SCHEDULE AND PICK UP FOR SERVICE			
<u>Jesus Urquidi</u>									
89952					7/18/2012		231		\$0.00
Medium	Work In Progress			7/18/2012 10:01:25 AM					
Carbajal, Jimmy	auto scrubber nss SR. 232312A 36169435 does not pick up water.					11/30/12 - JIMMY, NEEDS TO SCHEDULE AND PICK UP MACHINE.			
<u>Jesus Urquidi</u>									
93934					10/9/2012		148		\$0.00
Medium	Work In Progress			10/9/2012 10:33:13 AM					
Flores, Pete	Truck is trembling alot and have a hard time starting it.								
<u>Jesus Urquidi</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
96668					12/16/2012		80		\$0.00
Medium	Work In Progress				12/16/2012 12:16:10				
Valdez, Pedro	Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98589					2/15/2013		19		\$0.00
Medium	Work In Progress				2/15/2013 3:59:52 PM				
Valdez, Pedro	Sofia Payan is requesting dead plants be removed and plant differant plants infront of health Building.								
<u>Alfredo Ortiz</u>									
96586		Parking Lot			12/13/2012		83		\$0.00
Medium	Work In Progress				12/13/2012 11:43:18				
Ortiz, Alfredo	We need several signs to be placed at different locations of the school. Please see Lupe Quinones for signs.								
<u>Mireya Meza</u>									
98953		Mechanical			2/27/2013		7		\$0.00
Medium	Work In Progress				2/27/2013 3:34:21 PM				
Ortiz, Alfredo	Need to clean and sweep sand from all Mechanical rooms.								
<u>Alfredo Ortiz</u>									
99125					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:17 AM				
Ortiz, Alfredo	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99126					3/3/2013	4/3/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:17 AM				
Ortiz, Alfredo	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99129					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:19 AM				
Ortiz, Alfredo	Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96723					1/6/2013		59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:16 AM				
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump Eng (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
99127					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:18 AM					
Ortiz, Alfredo	Yearly - Chaparral HS A10 (Heat Pump)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90843					8/6/2012		212		\$0.00
Medium	Work In Progress			8/6/2012 11:26:25 AM					
Lozoya, Manny	We need the following keys made for CHS. Room A-108, #86 (6), light keys (10), key to staff room in library, key for trophy case in cafeteria and overhead in Q building.								
<u>Mireya Meza</u>									
96629		Classroom			12/14/2012		82		\$0.00
Medium	Work In Progress			12/14/2012 10:02:17					
Lozoya, Manny	We need a new master key for our custodian. He is having trouble opening some doors. The key might be worn out or bent. Please replace. (Mireya Meza)								
<u>Mireya Meza</u>									
98985					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:19 AM					
Ortiz, Alfredo	Yearly - Chaparral HS C11 (Evaporative)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98981					2/27/2013		7		\$0.00
Medium	Work In Progress			2/27/2013 4:44:17 PM					
Ontiveros, Joe	Install utility sink in athletic training room in gym so that we are compliant with health department. (Mr. Beets)								
<u>Mireya Meza</u>									
92674		Cafeteria			9/11/2012		176		\$0.00
Medium	Work In Progress			9/11/2012 11:15:45 AM					
Ontiveros, Joe	Need a water fountain for the students in the same area where tables are needed. (Lupe Quinones)								
<u>Mireya Meza</u>									
99128					3/3/2013	3/6/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:18 AM					
Ortiz, Alfredo	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
99025					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 8:39:02 AM					
Sotelo, Enrique		I need 3 GFI outlets installed in athletic training room in gym. (Mr. Beets)							
<u>Mireya Meza</u>									
97888		Cafeteria			1/30/2013		35		\$0.00
Medium	Work In Progress			1/30/2013 3:26:03 PM					
Ontiveros, Joe		Need to replace circulating pump in Kitchen mech. room. Domestic Hot water.							
<u>Alfredo Ortiz</u>									
96183		Hallway/Corridor			12/3/2012		93		\$0.00
Medium	Work In Progress			12/3/2012 2:40:58 PM					
Sotelo, Enrique		Need to replace 10 BALLAST Magnetic 70w Metal Halide.							
<u>Alfredo Ortiz</u>									
98358		Gym			2/11/2013		23		\$0.00
Medium	Work In Progress			2/11/2013 2:55:57 PM					
Sotelo, Enrique		Need to replace Ballast and light bulbs ing GYM. Magnetic Ballast 277 V M 750/Multi-PS Bulbs:MS750BU/PS Metal Halide.							
<u>Alfredo Ortiz</u>									
97348		Parking Lot			1/15/2013		50		\$0.00
Medium	Work In Progress			1/15/2013 3:10:32 PM					
Sotelo, Enrique		Need to replace light bulbs on parking lot. MH400/U/ED28 and ballast							
<u>Alfredo Ortiz</u>									
96016		Athletic Field			11/30/2012		96		\$0.00
Medium	Work In Progress			11/30/2012 3:23:44 PM					
Castillo, Carlos		power will be needed for new scoreboards for base ball/softball. Please contact lynco for quote. thank you							
<u>Michael Munoz</u>									
97035		Athletic Field			1/8/2013		57		\$0.00
Medium	Work In Progress			1/8/2013 3:23:26 PM					
Castillo, Carlos		Requesting power to center area of Chaparral baseball fields for outdoor events.							
<u>Carlos Castillo</u>									
Count: 70 Work Orders		Avg. Age of WO's 56		Total for Chaparral HS				0	\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
99393					3/6/2013		0		\$0.00
Medium	Work In Progress				3/6/2013 8:14:58 AM				
Vallejo, Albert		Replace HID fixtures for parking lot.							
Albert Vallejo									
89871					7/16/2012		233		\$0.00
Medium	Work In Progress				7/16/2012 4:19:52 PM				
Vallejo, Albert		Re-paint Fire lanes with red GLOSS paint.							
Albert Vallejo									
99118					3/3/2013	3/6/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:14 AM				
Vallejo, Albert		Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
98929					2/27/2013		7		\$0.00
Medium	Work In Progress				2/27/2013 7:50:55 AM				
Ontiveros, Joe		Please repair supply lines for sinks in room 307.							
Albert Vallejo									
96771					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:40 AM				
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
98984					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress				2/28/2013 12:28:19 AM				
Vallejo, Albert		Yearly - Chaparral MS C-11 (Swamp Coolers)Yearly) - Refer to PM schedule details.							
Margret Villalobos									
99154					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:30 AM				
Vallejo, Albert		Yearly - Chaparral MS A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
96486					12/11/2012		85		\$0.00
Medium	Work In Progress				12/11/2012 3:21:43 PM				
Lozoya, Manny		Key to room 106 is not working properly							
Albert Vallejo									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
99119					3/3/2013	4/3/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:14 AM					
Vallejo, Albert	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
99117					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:13 AM					
Vallejo, Albert	Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
99120					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:15 AM					
Vallejo, Albert	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
99121					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:15 AM					
Vallejo, Albert	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
94910		Athletic Field			11/1/2012		125		\$0.00
Medium	Work In Progress			11/1/2012 3:17:23 PM					
Ontiveros, Guadalupe	need two backstops to be built and installed for baseball.								
Guadalupe Ontiveros									
99392					3/6/2013		0		\$0.00
Medium	Work In Progress			3/6/2013 8:03:40 AM					
Ontiveros, Guadalupe	Please install bubblers for two new trees in front of school.								
Albert Vallejo									
97223					1/13/2013	1/29/2013	52		\$0.00
Medium	Work In Progress			1/13/2013 12:16:12 AM					
Gonzalez, Robert	Monthly - QRTLY BLDG INSP REPORTS (CM) - Refer to PM schedule details.								
Margret Villalobos									
98031					2/3/2013	2/11/2013	31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:15 AM					
Vallejo, Albert	Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
93936					10/9/2012		148		\$0.00
Medium	Work In Progress			10/9/2012 10:43:47 AM					
Flores, Pete	as per our meeting , please assign vehicle # 121 to albert. thank you								
<u>Michael Munoz</u>									
99231					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:05 AM					
Munoz, Michael	Yearly - Chaparral MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92678					9/11/2012		176		\$0.00
Medium	Work In Progress			9/11/2012 11:27:08 AM					
Apodaca, Mario	I would like to have Mario come out to help me work on the irrigation booster pump.								
<u>Albert Vallejo</u>									
95176					11/5/2012		121		\$0.00
Medium	Work In Progress			11/5/2012 2:14:02 PM					
Gonzalez, Salvador	Please fabricate ice machine stand in Athletics locker room.								
<u>Albert Vallejo</u>									
98559		Restroom (Boys)			2/15/2013		19		\$0.00
Medium	Work In Progress			2/15/2013 10:11:25 AM					
Lozoya, Manny	senesecita poner /2 puertas que quitaron los chabalos delos banos de los boys del #300 hallway de las particiones GRACIAS								
<u>M. Carmen Perez</u>									
99122					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:16 AM					
Vallejo, Albert	Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96786					1/6/2013	1/27/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:46 AM					
Orozco, Daniel	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99091					3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 3:18:36 PM					
Estrada, Jesus	NEED TO INSTALL COVE BASE IN CAFETERIA								
Jesus Estrada									

3/6/2013 4:22:56 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral MS									
93237	Main Building	Classroom			9/25/2012		162		\$0.00
Medium	Work In Progress	308		9/25/2012 3:11:29 PM					
Lozoya, Manny	Teacher would like locks put on cabinets								
<u>Gidget Mora</u>									
99397	Main Building	Classroom			3/6/2013		0		\$0.00
Medium	Work In Progress	303		3/6/2013 9:40:28 AM					
Vallejo, Albert	Respectfully requesting maintenance Dept. to pick-up Art stools from GES and bring to CMS as per Mr. Hinojosa. Please pick up as many as he has to offer								
<u>Gidget Mora</u>									
96911	Main Building	Classroom			1/7/2013		58		\$0.00
Medium	Work In Progress	104		1/7/2013 8:47:55 AM					
Vallejo, Albert	Window shades no longer functional. Please Replace								
<u>Gidget Mora</u>									
99028	Main Building				2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 10:03:07 AM					
Lozoya, Manny	please make key for 405B								
<u>Gidget Mora</u>									
99030	Main Building				2/28/2013		6		\$0.00
Medium	Work In Progress	Security		2/28/2013 10:04:31 AM					
Lozoya, Manny	Please fix lock on security door								
<u>Gidget Mora</u>									
99007					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:29 AM					
Munoz, Michael	Yearly - Chaparral MS - Fire Pump Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 30 Work Orders			Avg. Age of WO's 46				Total for Chaparral MS	0	\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
Location:		Charter School							
96216		Parking Lot			12/4/2012		92		\$0.00
Medium	Work In Progress				12/4/2012 8:04:07 AM				
Villalobos, David	Constant drip on 8" fire protection bfp need to replace check valves								
David Villalobos									
Count: 1 Work Orders		Avg. Age of WO's		92	Total for Charter School		0	\$0.00	

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
99031		Portables			2/28/2013		6		\$0.00
Medium	Work In Progress	ROOM 1 & 2		2/28/2013 11:07:06 AM					
Appelzoller, Fred	CLOGGED SINK IN RESTROOM. USED PLUNGER AND REMOVE TRAP TO CLEAN AND REMOVE OBJECTS. STILL CLOGGED.								
David Acosta									
95455		Office			11/13/2012		113		\$0.00
Medium	Work In Progress	RESTROOM		11/13/2012 1:10:10 PM					
Appelzoller, Fred	WHEN TOILET IS FLUSHED WATER COMES OR BUBBLES BACK UP. SEPTIC TANK WAS CLEAN OUT 10/26/12								
David Acosta									
93272		Portables			9/26/2012		161		\$0.00
Medium	Work In Progress			9/26/2012 9:14:50 AM					
Ontiveros, Guadalupe	please assist with the trenching for a new electrical line to the portable this friday 9-28-12.thank you								
Michael Munoz									
92503		Portables			9/6/2012		181		\$0.00
Medium	Work In Progress			9/6/2012 4:08:35 PM					
Ambriz, Jose	desert pride will be receive a portable on 9-07-12. please provide a new window evaporative cooler and a new wall heater w/ fan. thank you								
Michael Munoz									
99248					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:12 AM					
Aguilar, Patricio	Yearly - Desert Pride HS A10(Heat Pumps)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
99008					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:30 AM					
Aguilar, Patricio	Yearly - Desert Pride HS C11 (Evap.)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
98252					2/6/2013		28		\$0.00
Medium	Work In Progress			2/6/2013 10:21:35 AM					
Acosta, David	NEED TO CLEAN WINDOWS AND WINDOW SEALS IN MR. SANCHEZ NEW PORTABLE								
Jesus Estrada									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
98551		Custodial			2/15/2013		19		\$0.00
Medium	Work In Progress				2/15/2013 6:58:21 AM				
Carbajal, Jimmy		NEED 3 FILTER BAGS FOR RAVEN BACKPACK							
David Acosta									
97760		Portables			1/28/2013		37		\$0.00
Medium	Work In Progress	1,2,3,4,6.			1/28/2013 10:35:12 AM				
Gonzalez, Salvador		THE STEPS & RAMPS TOO PORTABLES (ROOM 1,2,3,4,6) NEEDS TO BE SAND BLASTED OR SOME METHOD OF REMOVING RUST AND OLD CHIPPING PAINT BEFORE REPAINTING							
David Acosta									
99138					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:23 AM				
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
99139					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:24 AM				
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
98049					2/3/2013	2/11/2013	31		\$0.00
Medium	Work In Progress				2/3/2013 12:22:23 AM				
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
98050					2/3/2013	2/11/2013	31		\$0.00
Medium	Work In Progress				2/3/2013 12:22:24 AM				
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
98505					2/14/2013		20		\$0.00
Medium	Work In Progress				2/14/2013 12:21:41 AM				
Sanchez, Raul		Monthly - Desert Pride - Water Filters - Refer to PM schedule details.							
Margret Villalobos									
99266					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:26:20 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									

3/6/2013 4:22:56 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
98124					2/3/2013		31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:54 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92513					9/7/2012		180		\$0.00
Medium	Work In Progress			9/7/2012 9:19:09 AM					
Estrada, Jesus	PORTABLE FROM SAN MIGUEL WILL BE RELOCATED TO DESERT PRIDE. NEED TO HAVE CARPET REPLACED.								
	9/7/12 REVISED - NEED TO REPLACE CARPET WITH LINOLEUM AND 4" COVE BASE								
<u>Michael Munoz</u>									
99137					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:23 AM					
Acosta, David	Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98048					2/3/2013	2/9/2013	31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:23 AM					
Acosta, David	Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96477		Classroom			12/11/2012		85		\$0.00
Medium	Work In Progress	ROOM 9		12/11/2012 12:15:40					
Lara, Ralph	MAY NEED TO REPLACE WOOD DOOR FRAME. (AS SPLITS OR CRACKS) AND SCREWS TO HINGES KEEP COMING LOOSE.								
<u>David Acosta</u>									
99016					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:33 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99234					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:06 AM					
Munoz, Michael	Yearly - Desert Pride HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Desert Pride							
97646		Gym			1/24/2013		41		\$0.00
Medium	Work In Progress	Boxing Gym			1/24/2013 2:03:46 PM				
Ronquillo, Ruben		The following gym equipment needs repair: Sports Art Eliptical- shrouds, cup holder and extension cords need to be replaced. Treadmill Endurance-site rails, cover/motor needs to be replaced. Precor Treadmill-motor belt needs to be replaced Serial #'s 0068567/006344							
Yvette Cortez									
Count: 23 Work Orders		Avg. Age of WO's 45			Total for Desert Pride			0	\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Desert Trail Intermediate									
99218					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:59 AM				
Munoz, Michael	Yearly - Desert Trail ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98888					2/26/2013		8		\$0.00
Medium	Work In Progress				2/26/2013 1:57:19 PM				
Orozco, Daniel	DRAINS ARE CLOGGING UP. IN FRONT OF WASH ROOM, IN FRONT OF SKILLET AND WHEN YOU LET GO OF THE WATER IN THE 3 COMPARTMENT SINK.SNP MANAGER PAT C. 824.3822								
<u>Maritza Gonzalez</u>									
92723					9/12/2012		175		\$0.00
Medium	Work In Progress				9/12/2012 8:26:47 AM				
Orozco, Daniel	Threshold to walk-in cooler came loose again. Also, please replace thermocouple to stove's oven. (Pilot keeps turning off) thank you. SNP Manager Pat C. 824.3822								
<u>Maritza Gonzalez</u>									
98240		Custodial			2/6/2013		28		\$0.00
Medium	Work In Progress				2/6/2013 8:12:17 AM				
Carbajal, Jimmy	Jimmy buenos dias necesito 3 bolsas de aspiradora por favor gracias								
<u>Laura Sandoval</u>									
99173					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:39 AM				
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95306		Custodial			11/8/2012		118		\$0.00
Medium	Work In Progress				11/8/2012 7:10:35 AM				
Estrada, Jesus	Chuy buenos dias si puede revisar por favor los portables Num.405 y 406 pues la alfombra que pusieron se esta desilando gracias								
<u>Laura Sandoval</u>									
95308		Custodial			11/8/2012		118		\$0.00
Medium	Work In Progress				11/8/2012 7:28:35 AM				
Estrada, Jesus	Chuy por favor puede revisar el piso de los portables Num. 414 y 415 el tile se esta quebrando en pedasitos , Jhonny ya los a remplasado y se buelben a quebrar muchas gracias que tenga buen dia								
<u>Laura Sandoval</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
96787					1/6/2013	1/27/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:46 AM					
Orozco, Daniel	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96410					12/9/2012	12/25/2012	87		\$0.00
Medium	Work In Progress			12/9/2012 12:16:25 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99174					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:39 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98455					2/13/2013		21		\$0.00
Medium	Work In Progress			2/13/2013 12:30:26 PM					
Ontiveros, Guadalupe	Coaches requesting to re-locate Baseball Backstop to a different location of the field.								
<u>Johnny Acuna</u>									
96990					1/8/2013		57		\$0.00
Medium	Work In Progress			1/8/2013 8:19:24 AM					
Ontiveros, Guadalupe	Need Top Soil to fill in holes in playground grass area. (Safety Issue)								
<u>Johnny Acuna</u>									
94274					10/17/2012		140		\$0.00
Medium	Work In Progress			10/17/2012 3:41:51 PM					
Ontiveros, Guadalupe	Coaches requesting to move baseball backstop to another location in same playground area. It is in the way. (Currently Located inside of the soccer playing area)								
<u>Johnny Acuna</u>									
99172					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:38 AM					
Acuna, Johnny	Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96089					12/2/2012	12/10/2012	94		\$0.00
Medium	Work In Progress			12/2/2012 12:23:03 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
3/6/2013 4:22:57 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
99175					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:40 AM				
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99171					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:38 AM				
Acuna, Johnny	Yearly - Desert Trail ES A10 (Heat Pump)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98994					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress				2/28/2013 12:28:24 AM				
Acuna, Johnny	Yearly - Desert Trail ES C-11 (Evap.Cool)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98806					2/25/2013		9		\$0.00
Medium	Work In Progress				2/25/2013 9:33:17 AM				
Lozoya, Manny	Need to change cylinder core to principal's office to secure Testing Material.								
<u>Johnny Acuna</u>									
99021					2/28/2013		6		\$0.00
Medium	Work In Progress				2/28/2013 7:48:11 AM				
Solis, Lorenzo	Need a replacement heating/cooling window unit for portable #409.								
<u>Johnny Acuna</u>									
98712					2/21/2013		13		\$0.00
Medium	Work In Progress				2/21/2013 10:23:49 AM				
Solis, Lorenzo	Need a combustion exhaust blower motor for portable #411 heating unit. Fasco, Model #7021-8935, 115v, Type U21B, A 1.1, Cust. P/N 2702-32								
<u>Johnny Acuna</u>									
99343					3/5/2013		1		\$0.00
Medium	Work In Progress				3/5/2013 9:01:19 AM				
Solis, Lorenzo	Please deliver the 3 Mastercool units behing the Auto shop to Desert Trail Elementary.								
<u>Johnny Acuna</u>									
94098					10/12/2012		145		\$0.00
Medium	Work In Progress				10/12/2012 10:11:07				
Ontiveros, Joe	Need to replace all student restroom wash basins (Sinks) (Qty. 6)								
<u>Johnny Acuna</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
97351					1/15/2013		50		\$0.00
Medium	Work In Progress			1/15/2013 3:23:41 PM					
Vallejo, Albert	As per Administration, please install dual light fixture to illuminate drive entrance. (Dual fixture will replace damaged single fixture)								
Albert Vallejo									
99408					3/6/2013		0		\$0.00
Medium	Work In Progress			3/6/2013 2:01:07 PM					
Ontiveros, Joe	Need assistance with P-trap to outdoor waterfountains.								
Johnny Acuna									
98509					2/14/2013		20		\$0.00
Medium	Work In Progress			2/14/2013 7:57:25 AM					
Ontiveros, Joe	Need to replace drinking water bubbler in sink to classroom #206.								
Johnny Acuna									
98528					2/14/2013		20		\$0.00
Medium	Work In Progress			2/14/2013 3:35:57 PM					
Ontiveros, Joe	Please Fix/Replace waterfountain Bubbler in sink to classroom #104.								
Johnny Acuna									
96756					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:34 AM					
Villalobos, David	Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 28 Work Orders		Avg. Age of WO's	45	Total for Desert Trail Intermediate			0	\$0.00	

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
96317		Classroom			12/6/2012		90		\$0.00
Medium	Work In Progress	Portable #8			12/6/2012 11:51:11 AM				
Villalobos, David Install sink in the classroom. (Gonzalez)									
Guadalupe Gonzalez									
96572		Office			12/13/2012		83		\$0.00
Medium	Work In Progress	Office			12/13/2012 8:21:53 AM				
Villalobos, David There is a strong odor in the office due to the sewer drainage. If we can have it checked out as soon as possible. (Gonzalez)									
Guadalupe Gonzalez									
94995					11/2/2012		124		\$0.00
Medium	Work In Progress				11/2/2012 3:52:29 PM				
Villalobos, David Need broken sink replaced in the upper level girl's bathroom Thank you, Ruben									
Ruben Ortiz									
96762					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:37 AM				
Villalobos, David Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.									
Margret Villalobos									
97747					1/28/2013		37		\$0.00
Medium	Work In Progress	Whole Campus			1/28/2013 8:55:43 AM				
Villalobos, David There is a gas smell throughout the school campus. The odor is very strong in the cafeteria and the office. If we can have it check as soon as possible. (Gonzalez)									
Guadalupe Gonzalez									
96939		Restroom (Girls)			1/7/2013		58		\$0.00
Medium	Work In Progress	Lower Grade			1/7/2013 2:12:25 PM				
Villalobos, David Broken toilet needs replacement. (Gonzalez)									
Guadalupe Gonzalez									
98409		Office			2/12/2013		22		\$0.00
Medium	Work In Progress	Office			2/12/2013 3:17:50 PM				
Castillo, Carlos Install a 20 amp outlet for copier. (Gonzalez)									
Guadalupe Gonzalez									
99048		Classroom			2/28/2013		6		\$0.00
Medium	Work In Progress	Portable 7			2/28/2013 3:37:08 PM				
Castillo, Carlos Lights in the Restroom aren't working. Light bulbs changed but its electrical problem. (Mrs. Ortiz)									
Guadalupe Gonzalez									

3/6/2013 4:22:57 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Desert View ES									
99359					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 11:22:00 AM					
Ambriz, Jose	Heater in portable 5 is not working; need it repaired; ASAP. Thank you, Ruben								
Ruben Ortiz									
99323					3/4/2013		2		\$0.00
Medium	Work In Progress			3/4/2013 3:43:51 PM					
Ambriz, Jose	Heater in room 27 is not working; need it repaired.								
Ruben Ortiz									
99275					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:24 AM					
Ortiz, Ruben	Yearly - Desert View ES A-10 HP Rooftop Yearly - Refer to PM schedule details.								
Margret Villalobos									
98001					2/1/2013		33		\$0.00
Medium	Work In Progress			2/1/2013 3:32:40 PM					
Ortiz, Ruben	Paint the base and little library								
Ruben Ortiz									
99018					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:34 AM					
Ortiz, Ruben	Yearly - Desert View ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									
99019					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:35 AM					
Ortiz, Ruben	Monthly - Desert View ES A-16 Fan Exhaust (Semi) - Refer to PM schedule details.								
Margret Villalobos									
99273					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:23 AM					
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
92736					9/12/2012		175		\$0.00
Medium	Work In Progress			9/12/2012 10:18:19 AM					
Ortiz, Ruben	Pick up Donation. (R. Ortiz)								
Guadalupe Gonzalez									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
96536		Office			12/12/2012		84		\$0.00
Medium	Work In Progress	Principal's Office			12/12/2012 11:40:29				
Ortiz, Ruben	Replace light bulbs in the Principal's office. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
92512		Classroom			9/7/2012		180		\$0.00
Medium	Work In Progress	Classroom			9/7/2012 9:05:01 AM				
Ortiz, Ruben	Install Marker Boards in the classrooms. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
96921		Restroom (Boys)			1/7/2013		58		\$0.00
Medium	Work In Progress				1/7/2013 10:29:22 AM				
Ortiz, Ruben	The paper towel dispenser in the Lower Grade Boy's Bathroom is broken.								
<u>Guadalupe Gonzalez</u>									
96941		Restroom (Boys)			1/7/2013		58		\$0.00
Medium	Work In Progress	Lower Grade			1/7/2013 2:16:15 PM				
Ortiz, Ruben	Toilet seat doesn't fit. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
96588		Restroom (Boys)			12/13/2012		83		\$0.00
Medium	Work In Progress	Upper Grade			12/13/2012 1:05:29 PM				
Ortiz, Ruben	Replace light bulbs in the upper grade boys bathroom. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
96982					1/7/2013		58		\$0.00
Medium	Work In Progress				1/7/2013 4:57:10 PM				
Ortiz, Ruben	Received a/c cover and base covers; need to install them.								
<u>Ruben Ortiz</u>									
97855					1/30/2013		35		\$0.00
Medium	Work In Progress	Front Gate to			1/30/2013 8:31:52 AM				
Ortiz, Ruben	The Front Gate is difficult to open. It's heavy and doesn't roll as smooth. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
99271					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:26:22 AM				
Ortiz, Ruben	Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
99274					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:24 AM					
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98867		Office			2/26/2013		8		\$0.00
Medium	Work In Progress	Front Office		2/26/2013 10:19:51 AM					
Lara, Ralph	For Security Safety....install an automatic door opener. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
98868		Office			2/26/2013		8		\$0.00
Medium	Work In Progress	Front Office		2/26/2013 10:21:42 AM					
Lara, Ralph	Security Safety.....check the locks on all doors throughout school campus to make sure that they lock. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
95514		Classroom			11/14/2012		112		\$0.00
Medium	Work In Progress	Rm. 24		11/14/2012 1:11:25 PM					
Lara, Ralph	Install locks in the classroom for the safety of the students.(Ms. Garcia)								
<u>Guadalupe Gonzalez</u>									
96235					12/4/2012		92		\$0.00
Medium	Work In Progress			12/4/2012 2:26:39 PM					
Lara, Ralph	SCREEN DOOR IN KITCHEN AREA IS BROKEN, NEEDS TO BE LOOKED AT AND FIXED. SNP MANAGER DIANA L. 589.2425								
<u>Maritza Gonzalez</u>									
97202					1/13/2013	1/29/2013	52		\$0.00
Medium	Work In Progress			1/13/2013 12:16:01 AM					
Ortega, Israel	Monthly - QRTLY BLDG INSP REPORT (DV) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95917		Gym			11/29/2012		97		\$0.00
Medium	Work In Progress			11/29/2012 8:04:06 AM					
Ortega, Israel	Set up the stage in the gym for the Spelling Bee. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
98335					2/10/2013	2/26/2013	24		\$0.00
Medium	Work In Progress			2/10/2013 12:20:38 AM					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
3/6/2013 4:22:57 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
99325					3/4/2013		2		\$0.00
Medium	Work In Progress			3/4/2013 3:46:49 PM					
Ronquillo, Ruben	Broken window due to the hard winds; on the Westside south entrance. 14x18; need it replaced.								
<u>Ruben Ortiz</u>									
98558		Office			2/15/2013		19		\$0.00
Medium	Work In Progress	Principal's Office		2/15/2013 9:02:00 AM					
Estrada, Jesus	The transition from carpet to floor needs repair. It has lifted and makes people trip over. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
98145	Main Building	Custodial			2/4/2013		30		\$0.00
Medium	Work In Progress			2/4/2013 10:00:39 AM					
Carbajal, Jimmy	Hi Jimmy, Mr. Aguirre our custodian had problems with one of vaccum cleaners he says it smelled like something was burning and its also going to need the rear wheels. If you could help us out with that. Thank you								
<u>Israel Ortega</u>									
98865	Main Building	Hallway/Corridor			2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 9:43:56 AM					
Lara, Ralph	Hi Rafa: We need a couple of things done now that we need to have the school locked. In the two hallways the doors that are at the end of the hallway facing the deserts we are having trouble locking them with the key through the outside. Also the school front doors one of them is having trouble closing all the way in and it stays open. Thank you								
<u>Israel Ortega</u>									
97708					1/25/2013		40		\$0.00
Medium	Work In Progress			1/25/2013 2:32:56 PM					
Gonzalez, Salvador	Welding Need a base built for little free library program height 30 inches; width 16 by 23								
<u>Ruben Ortiz</u>									
97861		Cafeteria			1/30/2013		35		\$0.00
High	Work In Progress			1/30/2013 10:42:11 AM					
Orozco, Daniel	need to relace small stainless steal sink. chemical was used to unclog drain and as per health inspector it needs to be cleaned or relaced.								
<u>Demetrious Giovas</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
90992					8/8/2012		210		\$0.00
Medium	Work In Progress			8/8/2012 10:33:59 AM					
Gonzalez, Salvador	Need a 2 by 6 dragger out of iron angle. Thank you, Ruben								
Ruben Ortiz									
99219					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:59 AM					
Munoz, Michael	Yearly - Desert View ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
99272					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:23 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
98866		Custodial			2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 10:16:37 AM					
Carbajal, Jimmy	Hi Jimmy: I got two vaccum cleaners down one of the smelled like it was burig and it stopped working and the other one just stopped working. We tried them in different outlets but they still don't work. Thank you								
Israel Ortega									
98469		Cafeteria			2/13/2013		21		\$0.00
Medium	Work In Progress	Cafeteria		2/13/2013 2:13:03 PM					
Lara, Ralph	The door to the Cafeteria has a broken square and needs repair. (Gonzalez)								
Guadalupe Gonzalez									
98471		Cafeteria			2/13/2013		21		\$0.00
Medium	Work In Progress	Cafeteria		2/13/2013 2:17:02 PM					
Lara, Ralph	2nd Request: The screen door the the Cafeteria is broken and needs repair. (D. Lazarin)								
Guadalupe Gonzalez									
Count: 44 Work Orders		Avg. Age of WO's 47		Total for Desert View ES			0	\$0.00	

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
99236					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:07 AM					
Munoz, Michael	Yearly - GAC Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99089		Office			3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 3:13:43 PM					
Briones, Enrique	Please deliver 10 boxes for Tech on PO 121304339.								
<u>Larry Martinez</u>									
99294		Office			3/4/2013		2		\$0.00
Medium	Work In Progress			3/4/2013 10:36:07 AM					
Briones, Enrique	Pleae deliver 1 box to SNP for PO 121304637.								
<u>Larry Martinez</u>									
99289					3/4/2013		2		\$0.00
Medium	Work In Progress			3/4/2013 9:42:34 AM					
Orozco, Daniel	WALK IN REFRIGERATOR IS AT 60 DEGREES. SNP MANAGER IRMA V. 882.6275								
<u>Maritza Gonzalez</u>									
91474					8/17/2012		201		\$0.00
Medium	Work In Progress			8/17/2012 9:09:56 AM					
Estrada, Jesus	Technology Office - need to have carpet removed in Calixto and Cora office.								
<u>Cora Ramirez</u>									
96788					1/6/2013	1/27/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:47 AM					
Orozco, Daniel	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99157					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:32 AM					
Moncayo, Fernando	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
94698					10/29/2012		128		\$0.00
Medium	Work In Progress			10/29/2012 9:26:05 AM					
Rodriguez, Arturo	TOILET IN RR IN FRONT OF RECEPTIONIST AREA WILL NOT FLUSH.								
<u>Maritza Gonzalez</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
99159					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:32 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
92964					9/18/2012		169		\$0.00
Medium	Work In Progress	Lucia Almeraz			9/18/2012 3:45:13 PM				
Moncayo, Fernando		ATTN: JUAN AMBRIZ PLEASE INSTALL A REGISTER IN OFFICE				2/26 -Routed to Fernando			
<u>Lucia Almeraz</u>									
96721					1/6/2013		59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:15 AM				
Holguin, Alfredo		Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
99161					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:33 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
96829					1/6/2013	1/14/2013	59		\$0.00
Medium	Work In Progress				1/6/2013 12:24:07 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
93781					10/3/2012		154		\$0.00
Medium	Work In Progress				10/3/2012 8:34:00 AM				
Lara, Ralph		AS PER MR. YTURREALDE, DOUBLED DOORS ENTERING HUMAN RESOURCES NEED LOCK/NUMBER LOCK INSTALLED FOR SECURITY PURPOSES. PLEASE SEE ARTURO.							
<u>Maritza Gonzalez</u>									
99394					3/6/2013		0		\$0.00
Medium	Work In Progress				3/6/2013 8:30:45 AM				
Lara, Ralph		FRONT AUTOMATIC DOOR IS STUCK , MOTOR IS NOT WORKING.							
<u>Maritza Gonzalez</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
99399					3/6/2013		0		\$0.00
Medium	Work In Progress			3/6/2013 10:57:36 AM					
Lara, Ralph	AS PER MR. YTURRALDE NEED CODE PAD LOCK INSTALLED ON DOOR ENTERING BUILDING IN FRONT RECEPTIONIST AREA								
Maritza Gonzalez									
99347					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 9:47:42 AM					
Lara, Ralph	DOOR WHERE COMBINATION LOCK WAS INSTALLED IN FRONT RECEPTION AREA IS GETING STUCK.								
Maritza Gonzalez									
99071					3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 9:43:58 AM					
Lara, Ralph	FRONT DOOR WITH CRRUA NEEDS TO BE LOOKED. WHEN IT OPENS IT HITS ON THE GLASS.								
Maritza Gonzalez									
98644					2/19/2013		15		\$0.00
Medium	Work In Progress			2/19/2013 4:03:31 PM					
Flores, Pete	please replace wiper blades on car#30 ricardo roberts								
Lucia Almeraz									
99341					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 8:43:00 AM					
Flores, Pete	vehicle #159 will not start. Parked at the bottom by Manny trailer house								
Cora Ramirez									
93982					10/10/2012		147		\$0.00
Medium	Work In Progress			10/10/2012 8:40:49 AM					
Flores, Pete	Frank's Balderrama suburban stopped on Mercantile Road.								
Cora Ramirez									
93983					10/10/2012		147		\$0.00
Medium	Work In Progress			10/10/2012 8:44:59 AM					
Flores, Pete	David Hinojosa's van is not starting. Will drop off tomorrow morning to have it checked out.								
Cora Ramirez									
95358					11/9/2012		117		\$0.00
Medium	Work In Progress			11/9/2012 9:36:29 AM					
Ambriz, Jose	AS PER MR. Y. WALL UNIT IS NOT WORKING PROPERLY MAY NEED TO BE REPLACED.								
Maritza Gonzalez									

3/6/2013 4:22:57 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
99395					3/6/2013		0		\$0.00
Medium	Work In Progress				3/6/2013 8:34:07 AM				
Ambriz, Jose	AIR IS COMING IN FROM VENT IN MS. BROWDER OFFICE, THAT VENT CAN NOT BE CLOSED.								
<u>Maritza Gonzalez</u>									
95653					11/19/2012		107		\$0.00
High	Work In Progress				11/19/2012 7:30:10 AM				
Ambriz, Jose	need to rewire liebert cooling system in tech room to have only 2 compressors functioning, install 4 contactors, new switches, intelligent board, programming etc. this system is oversized for room and is causing problems as designed.								
<u>Michael Munoz</u>									
96623					12/14/2012		82		\$0.00
Medium	Work In Progress				12/14/2012 12:16:36				
Ambriz, Jose	Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97228					1/14/2013		51		\$0.00
Medium	Work In Progress				1/14/2013 12:18:44 AM				
Ambriz, Jose	Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96987					1/8/2013		57		\$0.00
Medium	Work In Progress				1/8/2013 8:12:56 AM				
Ambriz, Jose	Server Room - Unit is down								
<u>Michael Munoz</u>									
97780					1/28/2013		37		\$0.00
Medium	Work In Progress				1/28/2013 3:18:01 PM				
Ambriz, Jose	"C" wing restroom exhaust fan needs a new motor								
<u>Fernando Moncayo</u>									
98504					2/14/2013		20		\$0.00
Medium	Work In Progress				2/14/2013 12:21:41 AM				
Ambriz, Jose	Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99188					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:45 AM				
Moncayo, Fernando	Yearly - GAC A-10 Heat Pump Cooling Only Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
3/6/2013 4:22:57 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
96315					12/6/2012		90		\$0.00
Medium	Work In Progress			12/6/2012 10:37:09 AM					
Castillo, Carlos	C-WING, NEED POWER TO CLOSET IN KARLA QUESADAS OFFICE.								
<u>Maritza Gonzalez</u>									
96763					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:37 AM					
Villalobos, David	Yearly - GAC Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92932					9/18/2012		169		\$0.00
Medium	Work In Progress			9/18/2012 12:44:19 PM					
Villalobos, David	MAIN WATER LINE LEAKING IN C-WING.								
<u>Maritza Gonzalez</u>									
99346					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 9:40:25 AM					
Villalobos, David	THERE IS A WATER LINE THAT IS LEAKING OUTSIDE OF MR. YTURRALDE OFFICE. MOISTURE IS GOING IN TO OFFICE.								
<u>Maritza Gonzalez</u>									
Count: 35 Work Orders			Avg. Age of WO's	56		Total for GAC	0		\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location:		GAC - Pre-K							
98516					2/14/2013		20		\$0.00
Medium	Work In Progress				2/14/2013 11:34:39 AM				
Ontiveros, Guadalupe	As per our conversation, please meet with Ms. Belegama for location and types of shade trees that are in need. Thank you								
Michael Munoz									
Count: 1 Work Orders		Avg. Age of WO's	20			Total for GAC - Pre-K	0		\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden ES

98795					2/25/2013		9		\$0.00
Medium	Work In Progress				2/25/2013 8:21:24 AM				
Pinion, Jose	please remove spider webs from around the school outside we started an abundant of black spiders.....								
Loraine Gandara									
97209					1/13/2013	1/29/2013	52		\$0.00
Medium	Work In Progress				1/13/2013 12:16:05 AM				
Pinon, Jose	Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PM schedule details.								
Margret Villalobos									
99265					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:26:20 AM				
Arreola, Rudy	Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.								
Margret Villalobos									
99262					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:26:19 AM				
Arreola, Rudy	Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
98794					2/25/2013		9		\$0.00
Medium	Work In Progress				2/25/2013 8:18:57 AM				
Arreola, Rudy	check exhaust fans in restrooms they are clogged up.... greatly appreciate your assistance in this matter....								
Loraine Gandara									
98797					2/25/2013		9		\$0.00
Medium	Work In Progress				2/25/2013 8:23:38 AM				
Arreola, Rudy	check and change filters for central air systems... greatly appreciate your assistance in this matter.....								
Loraine Gandara									
99264					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:26:19 AM				
Arreola, Rudy	Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.								
Margret Villalobos									
98796					2/25/2013		9		\$0.00
Medium	Work In Progress				2/25/2013 8:22:35 AM				
Villalobos, Margret	call the exterminator we have alot of black spiders on the outside walls....								
Loraine Gandara									

3/6/2013 4:22:57 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden ES									
91738		Football Field			8/23/2012		195		\$0.00
Medium	Work In Progress			8/23/2012 9:43:56 AM					
Arreola, Rudy	need assistance with the volleyball net... need to install them greatly appreciate your assistance..								
Loraine Gandara									
96894					1/7/2013		58		\$0.00
High	Work In Progress			1/7/2013 7:48:53 AM					
Gonzalez, Salvador	please repair broken window. vandalism								
Michael Munoz									
98802		Parking Lot			2/25/2013		9		\$0.00
Medium	Work In Progress			2/25/2013 8:26:03 AM					
Carrasco, Danny	put a stop sign in the bus drop off area... greatly appreciate your assistance in this matter...								
Loraine Gandara									
94633					10/26/2012		131		\$0.00
Medium	Work In Progress	outside area		10/26/2012 10:31:19					
Appelzoller, Fred	need immediate assistance... outside where you hook up the water hoses... there seems to be a lot of water drainage... water seems to be coming out even if the faucets are closed... please would greatly appreciate your assistance in this matter...								
Loraine Gandara									
97402					1/16/2013		49		\$0.00
Medium	Work In Progress	Morgan Building		1/16/2013 1:57:34 PM					
Lozoya, Manny	Asp Mike, need to key new Morgan Building the same as school site is keyed for admin to have access to it.								
Michael Munoz									
95947					11/29/2012		97		\$0.00
Medium	Work In Progress			11/29/2012 2:23:14 PM					
Lozoya, Manny	Need 2 gate keys. Need to check the keys out to either Hector Torres or Hector Gutierrez For more information contact Ralph Gallegos at 882-6921. Thank You.								
99349		Cafeteria			3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 10:51:05 AM					
Lozoya, Manny	need immediate assistance.... doors in middle hallway and in cafeteria dont close due to the door stopper being broken... greatly appreciate your assistance....								
Loraine Gandara									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden ES									
96778					1/6/2013	1/27/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:43 AM					
Orozco, Daniel	Monthly - Gadsden ES - Fire Sprinkler Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98889					2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 2:00:35 PM					
Orozco, Daniel	LEFT STEAM LINE, DRAIN PIPE IS BROKEN. SNP MANAGER CUCA P. 882.3410								
<u>Maritza Gonzalez</u>									
99263					3/3/2013	3/14/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:19 AM					
Arreola, Rudy	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96143					12/2/2012	12/13/2012	94		\$0.00
Medium	Work In Progress			12/2/2012 12:23:25 AM					
Arreola, Rudy	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98120					2/3/2013	2/14/2013	31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:52 AM					
Arreola, Rudy	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99214					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:57 AM					
Munoz, Michael	Yearly - Gadsden ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98872		Custodial			2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 10:23:15 AM					
Carbajal, Jimmy	vacuum has no power co8cooooo1o3								
<u>Jose Pinion</u>									
98873		Custodial			2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 10:27:09 AM					
Carbajal, Jimmy	need four vacuum belts								
<u>Jose Pinion</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Gadsden ES							
98799					2/25/2013		9		\$0.00
Medium	Work In Progress	Jefferson Wing			2/25/2013 8:24:37 AM				
Lozoya, Manny	main door from Jefferson wing hold up is broken... greatly appreciate your assistance in this matter... thank you.....								
Loraine Gandara									
Count: 24 Work Orders		Avg. Age of WO's	36	Total for Gadsden ES				0	\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
98602					2/19/2013		15		\$0.00
Medium	Work In Progress			2/19/2013 10:24:10 AM					
Lara, Ralph	Requested by Mr. Villa Rm. 510 Annex Building-Some kind of barriers are need to be put at the bottom of the west door and the bottom of all the south facing doors. Too much dust is coming in and can cause serious damage to electrical equipment as well as all acoustical equipment.								
<hr/>									
Velia Alarcon									
99233					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:06 AM					
Munoz, Michael	Yearly - Gadsden HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<hr/>									
Margret Villalobos									
96026		Athletic Field			11/30/2012		96		\$0.00
Medium	Work In Progress			11/30/2012 3:39:43 PM					
Gonzalez, Salvador	please order material for new scoreboards. baseball softball.thank you								
<hr/>									
Joe Munoz									
93175					9/24/2012		163		\$0.00
Medium	Work In Progress			9/24/2012 2:18:30 PM					
Gonzalez, Salvador	Requested by Coach Letz for Tennis Court-Please repair two of the benches on the Tennis Courts.								
<hr/>									
Velia Alarcon									
93070					9/20/2012		167		\$0.00
Medium	Work In Progress			9/20/2012 12:14:27 PM					
Gonzalez, Salvador	Need to weld brackets on windows of classroom #106. Main building....								
<hr/>									
Guillermo Hernandez									
99005					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:29 AM					
Munoz, Michael	Yearly - Gadsden HS - Fire Pump Inspection - Refer to PM schedule details.								
<hr/>									
Margret Villalobos									
96781					1/6/2013		59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:44 AM					
Orozco, Daniel	Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
98239					2/6/2013		28		\$0.00
Medium	Work In Progress				2/6/2013 7:41:14 AM				
Gallegos, Rafael	Warranty W/O for fresh air units for the Old English, after re-roofing was done and unit installed we could not start the units.								
<u>Guillermo Hernandez</u>									
99180					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:42 AM				
Herrera, Joel	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96167		Athletic Field			12/3/2012		93		\$0.00
High	Work In Progress				12/3/2012 9:10:56 AM				
Ontiveros, Guadalupe	need to install chian linkfence on infield for offical games. As per coach.								
<u>Guadalupe Ontiveros</u>									
91114		Athletic Field			8/10/2012		208		\$0.00
Medium	Work In Progress	Softball Fields			8/10/2012 10:10:53 AM				
Ontiveros, Guadalupe	Requested by Coach L. Chavez for Softball Fields-fencing 6' perimeter and 3-2x6 door chain link fence								
<u>Velia Alarcon</u>									
91115		Athletic Field			8/10/2012		208		\$0.00
Medium	Work In Progress	Softball Fields			8/10/2012 10:12:25 AM				
Ontiveros, Guadalupe	Requested by Coach L. Chavez for Softball Fields-wood fasterner--raise fencing around bull pen								
<u>Velia Alarcon</u>									
91116		Athletic Field			8/10/2012		208		\$0.00
Medium	Work In Progress	Softball Fields			8/10/2012 10:14:38 AM				
Ontiveros, Guadalupe	Requested by Coach L. Chavez for Softball Fields-Perimeter fence needs to be pulled & anchored down w/hog ties.								
<u>Velia Alarcon</u>									
98513	Boys Gym	Custodial			2/14/2013		20		\$0.00
Medium	Work In Progress				2/14/2013 10:52:05 AM				
Lara, Ralph	At the boys gym at the girls locker room, the door for the custodial closet has been damaged and the latch has also been ripped off.								
Joe Munoz									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

98514	Boys Gym	Custodial			2/14/2013		20		\$0.00
-------	----------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/14/2013 10:55:24 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lara, Ralph
At the boys gym at the football locker room, the door to the custodial closet has been kicked in and now does not secure.

Joe Munoz

98466	Boys Gym				2/13/2013		21		\$0.00
-------	----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/13/2013 2:04:50 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, Margret
Please spray boys locker room #100 for roaches and foot ball locker room for spiders at the Boys Gym. Asp Alfredo, wait until Custodial cleans area.

Guillermo Hernandez

97804	Varsity Gym	Gym			1/29/2013		36		\$0.00
-------	-------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/29/2013 7:30:44 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Carrasco, Danny
Need scissor lift to be delivered to GHS varsity gym by PPD warehousemen.

Carlos Castillo

97699	Varsity Gym				1/25/2013		40		\$0.00
-------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/25/2013 10:47:58 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Castillo, Carlos
Please check score boards in the V. Gym, scoreboard is turning off and on. Previously W/O #96524, did not had a location...

Guillermo Hernandez

95625	Old English Bldg				11/16/2012		110		\$0.00
-------	------------------	--	--	--	------------	--	-----	--	--------

High	Work In Progress			11/16/2012 10:46:22					
------	------------------	--	--	---------------------	--	--	--	--	--

Lozoya, Manny
Need to replace door in Old English #141, door is hanging it is being hold by the door closer, secured door from falling down, but room needs to be secured..

Guillermo Hernandez

92340	North Building				9/4/2012		183		\$0.00
-------	----------------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress			9/4/2012 11:39:43 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Appelzoller, Fred
Requested by Ms. Romero Rm. 223 North Building- Need to remove water and gas outlets, in additon to bench tables. Laser ingraver and mill need to be properly instaleld and the room is needed to properly install the equipment.

Velia Alarcon

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
98890	Main Building				2/26/2013		8		\$0.00
Medium	Work In Progress	OLD		2/26/2013 2:01:44 PM					
Castillo, Carlos	COPY MACHINE IN ROOM 100 IS SIGNALING POWER OUTAGES IN THE OUTLET CAUSING THE MACHINE TO STOP WORKING AND RE-SET ITSELF. WE CURRENTLY HAVE 2 OTHER COPY MACHINES IN THAT BUILDING WITH NO PROBLEMS...WE ARE ASSUMING IT IS THE OUTLET								
Cathy Ramos									
96230	Auto Shop				12/4/2012		92		\$0.00
Medium	Work In Progress			12/4/2012 1:14:52 PM					
Appelzoller, Fred	Please install correct clean out fixture for the clean out located east of the electrical setup in the ponding area south of the Auto Shop. This is an existing clean out that the pond was designed around. For more details see Allan Journey or call Rafael Gallegos at 882-6921. Thanks.								
Rafael Gallegos									
97713	Pool Pump				1/25/2013		40		\$0.00
Medium	Work In Progress			1/25/2013 3:00:31 PM					
Lara, Ralph	Replace roll-up door with new motorized unit								
Alfredo Holguin									
97715	Pool Pump				1/25/2013		40		\$0.00
Medium	Work In Progress			1/25/2013 3:02:00 PM					
Lara, Ralph	Replace door leading from pool area to pump house								
Alfredo Holguin									
98607	Pool Pump				2/19/2013		15		\$0.00
Medium	Work In Progress			2/19/2013 10:42:58 AM					
Sanchez, Raul	Remove and store all equipment around pool deck (slide, life guard chairs, etc). Will need to remove and store all supplies, equipment etc. from pool pump house before pool deck replacement and pump electrical remodel takes place.								
99164					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:35 AM					
Hernandez, Guillermo	Yearly - Gadsden HS A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
94829					10/31/2012		126		\$0.00
Medium	Work In Progress			10/31/2012 9:33:08 AM					
Ambriz, Jose	HEATER UNIT IN BAND ROOM IT DOESNT WORKING AT ANNEX BUILDING								
Joel Herrera									
93992					10/10/2012		147		\$0.00
Medium	Work In Progress			10/10/2012 11:27:53					
Ambriz, Jose	Need assistance to remove old furnace from the Boys Gym...								
Guillermo Hernandez									
94019					10/10/2012		147		\$0.00
Medium	Work In Progress			10/10/2012 3:43:56 PM					
Ambriz, Jose	Need to replace broken contactor to A/C #6. cafeteria roof.								
Guillermo Hernandez									
94185					10/15/2012		142		\$0.00
Medium	Work In Progress			10/15/2012 3:54:24 PM					
Ambriz, Jose	Need to replace 6 A/C commercial units for the cafeteria....								
Guillermo Hernandez									
98992					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:23 AM					
Hernandez, Guillermo	Yearly - Gadsden HS C-11 (Evap.Condnser)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
98934					2/27/2013		7		\$0.00
Medium	Work In Progress			2/27/2013 9:25:15 AM					
Ambriz, Jose	Requested by Velia-An ice machine is need to for the Band Room.								
Velia Alarcon									
97135					1/10/2013		55		\$0.00
Medium	Work In Progress			1/10/2013 3:37:55 PM					
Ambriz, Jose	Need to replace fan motor to furnace in the wrestling room.								
Guillermo Hernandez									
96339					12/6/2012		90		\$0.00
Medium	Work In Progress			12/6/2012 3:48:09 PM					
Ambriz, Jose	Need to replace gasket to pump in the boiler room for the Old English....								
Guillermo Hernandez									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
95309					11/8/2012		118		\$0.00
Medium	Work In Progress			11/8/2012 7:37:54 AM					
Ambriz, Jose	Need to replace T-stat and check leaks on gaskets on boiler for heating system on the Old English...								
Guillermo Hernandez									
99388					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 4:12:52 PM					
Ambriz, Jose	Need to check fan blower on North H/C unit in the Library.								
Guillermo Hernandez									
99389					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 4:14:29 PM					
Ambriz, Jose	Need to replace remote control to split unit in the server room in Old Main building. unit not cooling.								
Guillermo Hernandez									
92328					9/4/2012		183		\$0.00
Medium	Work In Progress			9/4/2012 10:17:12 AM					
Appelzoller, Fred	Requested by Ms. Lerma Rm. 105 Main Building-One of the ovens needs callobrating. SEE MS. LERMA FOR LOCATION OF OVEN.								
Velia Alarcon									
99177					3/3/2013	3/6/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:40 AM					
Herrera, Joel	Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
97659					1/24/2013		41		\$0.00
Medium	Work In Progress			1/24/2013 3:24:56 PM					
Appelzoller, Fred	Please check for gas smell outside of the boiler room for the cafeteria..								
Guillermo Hernandez									
99387					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 4:11:53 PM					
Appelzoller, Fred	Need to unclog sewer line for room#125 SPED classroom in Old Main building.								
Guillermo Hernandez									
98847					2/25/2013		9		\$0.00
Medium	Work In Progress			2/25/2013 3:51:56 PM					
Appelzoller, Fred	Need to replace broken toilet in the restrooms by the bus turn around.								
Guillermo Hernandez									

3/6/2013 4:22:57 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
98848					2/25/2013		9		\$0.00
Medium	Work In Progress	LINE LOCATE		2/25/2013 3:52:44 PM					
Appelzoller, Fred	Need to do locates a second time in the yellow area (attachment) at GHS. On the soccer field locate the whole area of 150 feet by 180 feet, starting at the south east corner by the Academic Building. Then do locates on the passage between the Academic Building and the Boys Gym all the way to the cafeteria. For details see Allan Journey (575-644-0810) or call Ralph Gallegos 882-6921. Thanks.								
Rafael Gallegos									
96764					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:37 AM					
Villalobos, David	Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
96358					12/7/2012		89		\$0.00
Medium	Work In Progress			12/7/2012 8:42:48 AM					
Castillo, Carlos	Please remove all electric wiring for the Science tables in classroom #223, North building. Tables to be removed....								
Guillermo Hernandez									
96598					12/13/2012		83		\$0.00
High	Work In Progress			12/13/2012 2:56:47 PM					
Castillo, Carlos	Please check east side bleachers motor in the V. Gym, bleachers stock open. Need to be closed for practices...								
Guillermo Hernandez									
99301					3/4/2013		2		\$0.00
Medium	Work In Progress			3/4/2013 12:08:06 PM					
Castillo, Carlos	Need assistance to replace ballast in hallway of the North building.								
Guillermo Hernandez									
97769					1/28/2013		37		\$0.00
Medium	Work In Progress			1/28/2013 12:45:56 PM					
Castillo, Carlos	Requested by Velia for Faculty Parking Lot-The light closest to the Bus Turnaround is burned out. Please replace as soon as possible.								
Velia Alarcon									
91113		Athletic Field			8/10/2012		208		\$0.00
Medium	Work In Progress	Softball Fields		8/10/2012 10:08:48 AM					
Castillo, Carlos	Requested by Coach L. Chavez for Softball Fields- electrical boxes/in storage/dugout on both sides and Electrical box installed at score board								
Velia Alarcon									
3/6/2013 4:22:57 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
96525		Athletic Field			12/12/2012		84		\$0.00
Medium	Work In Progress			12/12/2012 8:10:53 AM					
Castillo, Carlos	GHS-Boys' baseball scoreboard electrical service needs to be upgraded to support new scoreboard.								
Carlos Castillo									
96526		Athletic Field			12/12/2012		84		\$0.00
Medium	Work In Progress			12/12/2012 8:15:30 AM					
Castillo, Carlos	GHS-softball field scoreboard electrical service needs to be upgraded to support new scoreboard.								
Carlos Castillo									
96543		Athletic Field			12/12/2012		84		\$0.00
Medium	Work In Progress			12/12/2012 2:12:30 PM					
Castillo, Carlos	electrical for new scoreboards needs to be up-graded. thank you								
Michael Munoz									
94830					10/31/2012		126		\$0.00
Medium	Work In Progress			10/31/2012 10:03:50					
Castillo, Carlos	Requested by Mrs. Munoz Rm. 208 (Store Room) North Building-Need an electrical outlet on the west wall of store room.								
Velia Alarcon									
98860					2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 9:08:00 AM					
Castillo, Carlos	Requested by Mr. Myers in East Wing of Cafeteria-Move electrical/tables to room 514.								
Velia Alarcon									
91596					8/20/2012		198		\$0.00
Medium	Work In Progress			8/20/2012 3:59:41 PM					
Castillo, Carlos	Requested by Coach L. Chavez for Softball Field-Run electrical outlet to batting cage that will be moved behind scoreboard. SEE DIAGRAM								
Velia Alarcon									
98744					2/22/2013		12		\$0.00
Medium	Work In Progress			2/22/2013 8:50:05 AM					
Hernandez, Guillermo	Requested by Coach J. Vasquez for Football Lockerroom-Need white paint 10 gallons as many that can be supplied. Painting will be done by us.					2/26 - Route to Memo			
Velia Alarcon									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
95667					11/19/2012		107		\$0.00
High	Work In Progress			11/19/2012 10:06:13					
Hernandez, Guillermo	please paint all ADA logos, ramps and curbs etc to meet code requirements.thankyou								
Joe Munoz									
99079					3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 12:05:19 PM					
Herrera, Joel	Joel, need to paint all outside door of the Academic building and around the flower beds.								
Guillermo Hernandez									
92272					9/2/2012		185		\$0.00
Medium	Work In Progress			9/2/2012 12:21:46 AM					
Munoz, Michael	Monthly - Gadsden HS - Grease Trap (Culinary/Auto) - Refer to PM schedule details.								
Margret Villalobos									
99211					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:56 AM					
Munoz, Michael	Monthly - Gadsden HS - Grease Trap (Culinary/Auto) - Refer to PM schedule details.								
Margret Villalobos									
96524					12/12/2012		84		\$0.00
Medium	Work In Progress			12/12/2012 7:57:38 AM					
Sotelo, Enrique	Please check score board, having problems with the lights...								
Guillermo Hernandez									
96545					12/12/2012		84		\$0.00
High	Work In Progress			12/12/2012 3:03:54 PM					
Sotelo, Enrique	Need locates. Please do electrical on the south west corner of property from new light poles on south side of lift station. South of current fence 5' span of current fence. For information see Allan Journey (575-644-0810) or call Ralph Gallegos 882-6921. Thank You								
93092					9/20/2012		167		\$0.00
Medium	Work In Progress			9/20/2012 3:51:26 PM					
Carrasco, Danny	BROKEN WINDOW ON ROOM #341 SINGLE GLASS ZISE 44 1/2 X 29 1/2 AT ACADEMIC BUILDING								
Joel Herrera									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
98745					2/22/2013		12		\$0.00
Medium	Work In Progress			2/22/2013 8:51:55 AM					
Hernandez, Guillermo	Requested by Mrs. King Rm. 334 Academic Building- Replace two sets of burned out ceiling lights.								
<u>Velia Alarcon</u>									
98067					2/3/2013	2/11/2013	31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:31 AM					
Hernandez, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95620					11/16/2012		110		\$0.00
Medium	Work In Progress			11/16/2012 9:05:57 AM					
Hernandez, Guillermo	Requested by Coach Lawrence Rm. 341 Academic Building-Need two sets of blinds for window.								
<u>Velia Alarcon</u>									
98940		Pool			2/27/2013		7		\$0.00
Medium	Work In Progress			2/27/2013 12:33:24 PM					
Sanchez, Raul	We need to contract the service of Anthony Pump & Drilling to provide a crane to remove the pool slide from existing deck & reinstall after renovation of deck								
<u>Raul Sanchez</u>									
92301					9/2/2012		185		\$0.00
Medium	Work In Progress			9/2/2012 12:21:58 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
94821					10/31/2012		126		\$0.00
Medium	Work In Progress			10/31/2012 12:26:40					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93642					9/30/2012		157		\$0.00
Medium	Work In Progress			9/30/2012 12:31:33 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97883					1/30/2013		35		\$0.00
Medium	Work In Progress			1/30/2013 3:07:52 PM					
Sanchez, Raul	Asp Alfredo, install 2 pump and install valves to isolate pumps.								
Alfredo Holguin									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
97916					1/31/2013		34		\$0.00
Medium	Work In Progress			1/31/2013 12:25:34 AM					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98931					2/27/2013		7		\$0.00
Medium	Work In Progress			2/27/2013 8:38:09 AM					
Sanchez, Raul	Need to have Anthony Pump & Drilling check irrigation pump #1. Pumping gpm has gone done quite alot, casing screen may be clogged								
<u>Raul Sanchez</u>									
98451					2/13/2013		21		\$0.00
Medium	Work In Progress	LINE LOCATE		2/13/2013 11:24:43 AM					
Sanchez, Raul	Need to line locate (See attached) Contact: Annette Grandao, Triple J Excavation 575-527-1763								
<u>Alfredo Holguin</u>									
99015					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:33 AM					
Sanchez, Raul	Monthly - Gadsden HS - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99270					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:22 AM					
Sanchez, Raul	Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99267					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:21 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96148					12/2/2012		94		\$0.00
Medium	Work In Progress			12/2/2012 12:23:27 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95150					11/4/2012		122		\$0.00
Medium	Work In Progress			11/4/2012 12:20:01 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

3/6/2013 4:22:57 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
96877					1/6/2013		59		\$0.00
Medium	Work In Progress			1/6/2013 12:24:32 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98126					2/3/2013		31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:55 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98127					2/3/2013		31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:55 AM					
Sanchez, Raul	Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98803					2/25/2013		9		\$0.00
Medium	Work In Progress			2/25/2013 8:27:10 AM					
Herrera, Joel	Requested by Ms. Miller Rm. 344 Academic Building-Door doesn't stay open (magnet)								
<u>Velia Alarcon</u>									
99181					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:42 AM					
Herrera, Joel	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99178					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:41 AM					
Herrera, Joel	Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99179					3/3/2013	4/3/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:41 AM					
Herrera, Joel	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90166					7/25/2012		224		\$0.00
Medium	Work In Progress			7/25/2012 9:33:19 AM					
Estrada, Jesus	Requested by Mr. Pokluda for Rm. 300 in Academic Building-Replace or repair broken floor tiles at entry to classroom.								
<u>Velia Alarcon</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
96722					1/6/2013		59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:16 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99163					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:34 AM					
Hernandez, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98876					2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 10:50:16 AM					
Hernandez, Guillermo	Requested by Mr. Pokluda for Ms. Anderson's Classroom Move-Additional people are needed to help move Ms. Anderson from current classroom (rm. 233-North Building) into New Classroom in New Trades Building.								
<u>Velia Alarcon</u>									
98877					2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 10:52:05 AM					
Hernandez, Guillermo	Requested by Mr. Pokluda for Ms. Hamilton's Classroom Move-Additional people are needed to help move Ms. Hamilton from current classroom (rm. 504A-New Trades Building) into New Classroom (rm. # 516) in New Trades Building.								
<u>Velia Alarcon</u>									
98798					2/25/2013		9		\$0.00
Medium	Work In Progress			2/25/2013 8:24:28 AM					
Hernandez, Guillermo	Requested by Ms. Miller Rm. 344 Academic Building- Three lights are burnt out in classroom and need to be replaced.								
<u>Velia Alarcon</u>									
93612					9/30/2012		157		\$0.00
Medium	Work In Progress			9/30/2012 12:31:20 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
89302					7/1/2012		248		\$0.00
Medium	Work In Progress			7/1/2012 12:30:01 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
96720					1/6/2013		59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:15 AM					
Holguin, Alfredo	Monthly - Gadsden HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96804					1/6/2013	1/14/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:54 AM					
Hernandez, Guillermo	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98814					2/25/2013		9		\$0.00
Medium	Work In Progress			2/25/2013 12:24:04 PM					
Flores, Pete	PETE I HAVE PROBLEMS ON MY POLARIS BATTERY								
<u>Joel Herrera</u>									
99385		Portables			3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 4:09:32 PM					
Munoz, Joe	please relocate furniture in the 1st portable where pac used to be and re-locate to another portable and then clean and vacuum. the native indians will be using this portable during the pow/wow.thank you								
<u>Michael Munoz</u>									
97207					1/13/2013	1/29/2013	52		\$0.00
Medium	Work In Progress			1/13/2013 12:16:04 AM					
Munoz, Joe	Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91592					8/20/2012		198		\$0.00
Medium	Work In Progress			8/20/2012 3:55:01 PM					
Gonzalez, Salvador	Requested by Coach L. Chavez for Softball Field- Replace roofs on both dugouts.								
<u>Velia Alarcon</u>									
99382		Athletic Field			3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 4:03:53 PM					
Ontiveros, Guadalupe	please trench for new electrical for score boards. thank you								
<u>Michael Munoz</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

91453					8/16/2012		202		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/16/2012 4:19:55 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe Requested by Coach Yanez for Baseball Field-Set up brackets for a batting cage to be placed behind "visitors" dugout on mini-base infield. Dimensions asking for L 55' x H 12'.

Velia Alarcon

98758					2/22/2013		12		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/22/2013 1:32:43 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Munoz, Michael please deliver john deere TE 4x2 electric gator UV-GHS -0905.joey please read manual and view cd as well as your staff and return work order when complete. thank you

Michael Munoz

98824					2/25/2013		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			2/25/2013 3:22:14 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph Requested by Ms. Anderson/Mr. Pokluda for New Trades Building (New Panther Hut)-Re-key kitchen area six keys are needed Off Master; sales area. SEE MS. ANDERSON FOR FURTHER INSTRUCTION.

Velia Alarcon

98825					2/25/2013		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			2/25/2013 3:23:46 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph Requested by Mr. Pokluda for Rm. 514 in New Trades Building-Off Master keys are needed for storage cages.

Velia Alarcon

93980					10/10/2012		147		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress			10/10/2012 8:31:32 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lara, Ralph Need to replace cores in two storage's room for maintenance to have access for plumbing... (Academic and Annex building)

Guillermo Hernandez

96599					12/13/2012		83		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress			12/13/2012 2:58:12 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lara, Ralph Need to replace broken keys. for Maintenance 6 and 7 pin..

Guillermo Hernandez

97547					1/22/2013		43		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/22/2013 2:18:07 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph Requested by Ms. M. Sanchez Rm. 122 Main Building- Southern door handle is loose, it needs to be tighten so that door can be locked.

Velia Alarcon

3/6/2013 4:22:57 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: Gadsden HS										
95618					11/16/2012		110		\$0.00	
Medium	Work In Progress			11/16/2012 9:02:24 AM						
Lara, Ralph	Requested by Coach Lawrence Rm 341 Academic Building-Lock on door does not lock. Please repair as soon as possible, since Coach Lawrence has his Sp. Ed. lab top out and is afraid it might get stolen.		11/26 - Need status on work order asp email.							
<u>Velia Alarcon</u>										
99083					3/1/2013		5		\$0.00	
Medium	Work In Progress			3/1/2013 12:57:45 PM						
Ontiveros, Guadalupe	Requested by Coach Walker For Track Field-Please put up safety net for Shot Put/Discuss ring. SEE COACH WALKER FOR FURTHER INSTRUCTIONS.									
<u>Velia Alarcon</u>										
97772		Athletic Field			1/28/2013		37		\$0.00	
Medium	Work In Progress			1/28/2013 1:49:34 PM						
Ontiveros, Guadalupe	need blade spade for three point hitch. J.D 4440									
<u>Guadalupe Ontiveros</u>										
94661		Athletic Field			10/26/2012		131		\$0.00	
Medium	Work In Progress			10/26/2012 3:01:38 PM						
Holguin, Ramiro	sprinklers at softball and baseball need to be replace to be able for over seeding.									
<u>Guadalupe Ontiveros</u>										
99403		Athletic Field			3/6/2013		0		\$0.00	
High	Work In Progress			3/6/2013 11:13:47 AM						
Holguin, Ramiro	4" mainline on soccer field needs to be fix.									
<u>Guadalupe Ontiveros</u>										
99042		Athletic Field			2/28/2013		6		\$0.00	
Medium	Work In Progress			2/28/2013 3:24:38 PM						
Holguin, Ramiro	sprinklers need to be replaced on softball and soccer fields.									
<u>Guadalupe Ontiveros</u>										
Count: 114 Work Orders		Avg. Age of WO's 67		Total for Gadsden HS			0	\$0.00		

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
94655		Athletic Field			10/26/2012		131		\$0.00
Medium	Work In Progress			10/26/2012 2:51:10 PM					
Vasquez, Jose	need to replace solenoids on electric valves. sprinklers are not working.								
<u>Guadalupe Ontiveros</u>									
98662					2/20/2013		14		\$0.00
High	Work In Progress			2/20/2013 10:54:47 AM					
Ontiveros, Guadalupe	bases need to be replaced.								
<u>Guadalupe Ontiveros</u>									
95451					11/13/2012		113		\$0.00
Medium	Work In Progress			11/13/2012 11:21:58					
Ontiveros, Guadalupe	Please move guard shed to the back of the school. Set it up on the 6X6 concrete slab. Please see Mr. Calleros for details.								
<u>Nancy Tinajero</u>									
98440					2/13/2013		21		\$0.00
High	Work In Progress			2/13/2013 9:06:45 AM					
Diaz, Sebastian	please order signs and install on gates. signs are to read. gates to be closed and locked at all times. see mike for details								
<u>Alfredo Holguin</u>									
98958					2/27/2013		7		\$0.00
Medium	Work In Progress			2/27/2013 3:39:17 PM					
Diaz, Sebastian	Need to fix emergency lights AB wing								
<u>Sebastian Diaz</u>									
99280					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:26 AM					
Diaz, Sebastian	Monthly - Gadsden MS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99276					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:25 AM					
Diaz, Sebastian	Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99277					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:25 AM					
Diaz, Sebastian	Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
99360		Office			3/5/2013		1		\$0.00
Medium	Work In Progress	Front Office		3/5/2013 12:04:24 PM					
Sotelo, Enrique		Change front office outlet to a 120V for xerox machine.							
Nancy Tinajero									
96902		Football Field			1/7/2013		58		\$0.00
Medium	Work In Progress			1/7/2013 8:18:11 AM					
Sotelo, Enrique		Enrique can you help disconnecting power on scoreboard please so we can work on it, thank you.							
Salvador Gonzalez									
99281					3/3/2013	3/6/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:27 AM					
Diaz, Sebastian		Monthly - Gadsden MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
96765					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:38 AM					
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
99020					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:35 AM					
Diaz, Sebastian		Yearly - Gadsden MS C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
99110					3/3/2013	3/19/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:10 AM					
Villalobos, Margret		Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details.				E-mailed Honeywell 3/5			
Margret Villalobos									
99282					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:27 AM					
Diaz, Sebastian		Yearly - Gadsden MS A-10 HP Rooftop Yearly - Refer to PM schedule details.							
Margret Villalobos									
98007					2/1/2013		33		\$0.00
Medium	Work In Progress			2/1/2013 3:43:43 PM					
Solis, Lorenzo		Need to replace A/C on locker rooms thank you							
Sebastian Diaz									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
98956					2/27/2013		7		\$0.00
Medium	Work In Progress				2/27/2013 3:37:57 PM				
Solis, Lorenzo	Need to replace water fountain on old annex 2 thank you								
<u>Sebastian Diaz</u>									
98566					2/15/2013		19		\$0.00
Medium	Work In Progress				2/15/2013 12:43:04 PM				
Solis, Lorenzo	Need to check pump on boiler westside is leak thank you								
<u>Sebastian Diaz</u>									
93735					10/1/2012		156		\$0.00
Medium	Work In Progress				10/1/2012 3:44:34 PM				
Solis, Lorenzo	Need to check boiler in west side thank you								
<u>Sebastian Diaz</u>									
98858					2/26/2013		8		\$0.00
Medium	Work In Progress	Parking Lot -			2/26/2013 8:56:03 AM				
Lozoya, Manny	Lock opens with a slight pull. It doesn't lock properly. Please replace.								
<u>Nancy Tinajero</u>									
95623	Cafeteria	Custodial			11/16/2012		110		\$0.00
Medium	Work In Progress				11/16/2012 10:32:52				
Carbajal, Jimmy	THE DRIVABLE BURNISHERS BATTERY CABLE IS MELTED PLEASE CHECK FOR A SHORTAGE								
<u>Juan Acosta</u>									
98661	Main Building				2/20/2013		14		\$0.00
Medium	Work In Progress				2/20/2013 10:34:21 AM				
Lozoya, Manny	A.B WING ALL EXIT DOORS CORES NEED TO BE CLEAN CAN UNLOCK WITH KEY								
<u>Juan Acosta</u>									
94874	Main Building				11/1/2012		125		\$0.00
Medium	Work In Progress				11/1/2012 7:48:39 AM				
Lozoya, Manny	B.WING EXIT DOOR NEXT TO ROOM 113 CANNOT UNLOCK WHTH KEY								
<u>Juan Acosta</u>									
94878	Annex	Hallway/Corridor			11/1/2012		125		\$0.00
Medium	Work In Progress				11/1/2012 8:00:53 AM				
Lozoya, Manny	ANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOOR								
<u>Juan Acosta</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
94880	Gymnasium	Hallway/Corridor			11/1/2012		125		\$0.00
Medium	Work In Progress				11/1/2012 8:14:11 AM				
Lozoya, Manny	LOBBY EXIT DOOR GOING IN GYM FLOOR NEXT TO BLEACHERS THE MULLION IS LOOSE								
<u>Juan Acosta</u>									
97292	East Mechanical	Mechanical			1/15/2013		50		\$0.00
Medium	Work In Progress				1/15/2013 7:52:09 AM				
Appelzoller, Fred	need to replace return line on boiler system.								
<u>Fred Appelzoller</u>									
93405	C-Wing				9/28/2012		159		\$0.00
Medium	Work In Progress				9/28/2012 2:33:04 PM				
Castillo, Carlos	Check Transformer by Support Services/Athletic Portable.								
<u>Michael Munoz</u>									
95951	Gym				11/29/2012		97		\$0.00
Medium	Work In Progress	Gym Storage			11/29/2012 3:23:49 PM				
Gonzalez, Salvador	Please build new loft in storage room in gymnasium. See Mr. Calleros for more details.								
<u>Nancy Tinajero</u>									
98099					2/3/2013		31		\$0.00
Medium	Work In Progress				2/3/2013 12:22:44 AM				
Apodaca, Mario	Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97907					1/31/2013		34		\$0.00
Medium	Work In Progress				1/31/2013 12:25:28 AM				
Apodaca, Mario	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99207					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:54 AM				
Apodaca, Mario	Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99208					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:54 AM				
Apodaca, Mario	Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
99229					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:04 AM					
Munoz, Michael	Yearly - Gadsden MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
99279					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:26 AM					
Diaz, Sebastian	Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
89884					7/17/2012		232		\$0.00
Medium	Work In Progress			7/17/2012 7:12:12 AM					
Lozoya, Manny	ALL CORES TO EXIT DOORS OUTSIDE NEEDS CLEANING								
Juan Acosta									
Count: 35 Work Orders		Avg. Age of WO's 50		Total for Gadsden MS			0	\$0.00	

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
93326					9/27/2012		160		\$0.00
Medium	Work In Progress			9/27/2012 9:57:08 AM					
Lara, Ralph	DOOR BY WATER HEATER NEEDS TO BE SHAVED - CARPET WAS REPLACED IN BARRACK CHILD CARE CLASS (WORK ORDER #92350), .								
<u>Jesus Estrada</u>									
98954		Classroom			2/27/2013		7		\$0.00
Medium	Work In Progress			2/27/2013 3:35:15 PM					
Carbajal, Jimmy	VACUUM #0130 WHEEL CAME OFF								
<u>Jimmy Carbajal</u>									
98955		Classroom			2/27/2013		7		\$0.00
Medium	Work In Progress			2/27/2013 3:36:45 PM					
Carbajal, Jimmy	VACUUM # 5373 NEEDS SOME P.M.								
<u>Jimmy Carbajal</u>									
99220					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:00 AM					
Munoz, Michael	Yearly - La Union ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99247					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:12 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99009					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:30 AM					
Aguilar, Patricio	Yearly - La Union ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98430					2/13/2013		21		\$0.00
Medium	Work In Progress			2/13/2013 7:52:24 AM					
Aguilar, Patricio	wo to myself - need to install basepard molding office old wing								
<u>Patricio Aguilar</u>									
94907					11/1/2012		125		\$0.00
Medium	Work In Progress			11/1/2012 2:43:15 PM					
Aguilar, Patricio	wo to my self - paint class rooms - hall way old wing								
<u>Patricio Aguilar</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
99010					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:31 AM					
Aguilar, Patricio	Monthly - La Union ES A-16 Fan Exhaust Semimonthly - Refer to PM schedule details.								
Margret Villalobos									
96768					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:39 AM					
Villalobos, David	Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
94429					10/22/2012		135		\$0.00
Medium	Work In Progress			10/22/2012 11:31:40					
Villalobos, David	need wax donut - floor bracket for toilet r207								
Patricio Aguilar									
94427					10/22/2012		135		\$0.00
Medium	Work In Progress			10/22/2012 11:28:37					
Aguilar, Patricio	need p trap for urinal restroom b build								
Patricio Aguilar									
98650					2/20/2013		14		\$0.00
Medium	Work In Progress			2/20/2013 8:13:02 AM					
Castillo, Carlos	need transformer for florecent emeg light in hall way by gym								
Patricio Aguilar									
98861					2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 9:14:46 AM					
Aguilar, Patricio	wo to myself - need to replace round florecect light bulb r203 store room								
Patricio Aguilar									
99245					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:11 AM					
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
99249					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:13 AM					
Aguilar, Patricio	Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
99246					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:12 AM					
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
98862					2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 9:21:41 AM					
Flores, Pete	need oil - filter change - mower blades for jd125								
Patricio Aguilar									
97224					1/13/2013	1/29/2013	52		\$0.00
Medium	Work In Progress			1/13/2013 12:16:12 AM					
Ramos, Rudy	Monthly - QRTLY BLDG INSP REPORT (LU) - Refer to PM schedule details.								
Margret Villalobos									
99014					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:32 AM					
Sanchez, Raul	Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details.								
Margret Villalobos									
Count: 20 Work Orders			Avg. Age of WO's	38	Total for La Union ES			0	\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
97214					1/13/2013	1/29/2013	52		\$0.00
Medium	Work In Progress			1/13/2013 12:16:07 AM					
Solis, Luis	Monthly - QRTL BLDG INSP REPORT (LL) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99261					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:18 AM					
Arreola, Rudy	Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99258					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:17 AM					
Arreola, Rudy	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99257					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:16 AM					
Arreola, Rudy	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98454		Portables			2/13/2013		21		\$0.00
Medium	Work In Progress	7/8th Grade		2/13/2013 12:26:29 PM					
Arreola, Rudy	On each side of the portable there are 3 banks of lights that dont work. The tubes need replacing in each room.								
<u>Angie Flores</u>									
91008					8/8/2012		210		\$0.00
Medium	Work In Progress			8/8/2012 2:00:00 PM					
Sotelo, Enrique	Emerg lights (8) in Boys & Girls Restrooms not working asp PM 90795.								
<u>Rudy Arreola</u>									
96766					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:38 AM					
Villalobos, David	Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97624		Restroom (Boys)			1/24/2013		41		\$0.00
Medium	Work In Progress			1/24/2013 7:51:32 AM					
Appelzoller, Fred	please replace all granite wash basins in restrooms with stainless steal basins. the existing ones are in poor conditions. thankyou								
<u>Michael Munoz</u>									

3/6/2013 4:22:58 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
99013					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:32 AM					
Arreola, Rudy	Yearly - Loma Linda ES C11(Evap.Condnsr)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99260					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:18 AM					
Arreola, Rudy	Yearly - Loma Linda ES A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99259					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:17 AM					
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99221					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:00 AM					
Munoz, Michael	Yearly - Loma Linda ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97647					1/24/2013		41		\$0.00
Medium	Work In Progress			1/24/2013 2:04:25 PM					
Orozco, Daniel	WASHING MACHINE MAKING A LOUD NOISE. SNP MANAGER FRANCES B. 882.4707								
<u>Maritza Gonzalez</u>									
97061					1/9/2013		56		\$0.00
Medium	Work In Progress			1/9/2013 12:34:57 PM					
Orozco, Daniel	HAND SINK NEXT TO 3 COMPARTMENT SINK IS LEAKING. SNP MANAGER FRANCES B. 882.4707								
<u>Maritza Gonzalez</u>									
96789					1/6/2013	1/27/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:47 AM					
Orozco, Daniel	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98362	Main Building	Athletic Field			2/11/2013		23		\$0.00
Medium	Work In Progress			2/11/2013 3:01:31 PM					
Appelzoller, Fred	SUPPLY WATER LINE FOR WATER FOUNTAIN THAT WAS JUST INSTALLED OUTSIDE WAS BROKEN NEEDS TO BE REPLACED.								
Rudy Arreola									

3/6/2013 4:22:58 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Loma Linda ES

96483 Main Building Classroom 12/11/2012 85 \$0.00

Medium Work In Progress 112 12/11/2012 3:07:37 PM

Appelzoller, Fred Two weeiks ago "snake" was used to declog toilet. It has been 2 years of the toilet not flushing properly. I dont believe it is an issue of two much toilet paper. I dont know if the whole toilet bowl needs to be replaced. On a daily baisis I have to pause Instruction to hold the lever down so that it flushes. There are water stains on floor from water leaking.

Angie Flores

95663 Main Building Hallway/Corridor 11/19/2012 107 \$0.00

Medium Work In Progress 11/19/2012 9:43:03 AM

Sotelo, Enrique THE SECURITY LIGHT OUTSIDE ENTRANCE AND EXIT DOORS NORTH EAST SIDE IS OFF, WE NEED IT ON FOR THE SECURITY CAMARAS., THANKS.

Luis Solis

99315 Main Building Restroom (Boys) 3/4/2013 2 \$0.00

Medium Work In Progress Both Boys/Girls 3/4/2013 3:27:08 PM

Arreola, Rudy All Bathrooms (Walls and Stalls) need to be repainted, DARK BLUE, as per principal to control graffiti problems, needs to be painted AS SOON AS POSSIBLE

Angie Flores

96001 Main Building Parking Lot 11/30/2012 96 \$0.00

Medium Work In Progress 11/30/2012 11:37:03

Arreola, Rudy As per Mr. Lawler please repaint the fire lanes.

Angie Flores

98672 Main Building Portables 2/20/2013 14 \$0.00

Medium Work In Progress 2/20/2013 2:48:18 PM

Solis, Lorenzo COMPRESSOR WENT OUT ON UNIT PORTABLE THAT WAS JUST MOVED HERE FROM SAN MIGUEL

Rudy Arreola

96008 Main Building Athletic Field 11/30/2012 96 \$0.00

Medium Work In Progress 11/30/2012 2:49:28 PM

Ontiveros, Guadalupe ANOTHER VALVE IS STUCK SPRINKLERS KEEP RUNNING. BY PLAYGROUND AREA.

Rudy Arreola

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
97008	Main Building	Classroom			1/8/2013		57		\$0.00
Medium	Work In Progress			1/8/2013 10:10:55 AM					
Lozoya, Manny	As per our principal we need 6 keys to open the back door to the main building. Keys are for Morris, Martinez, Quintero, Gonzalez, Luna and Steinert. Keys will be able to only open one of the back main doors. Not a master key!								
<u>Angie Flores</u>									
97625	Main Building				1/24/2013		41		\$0.00
Medium	Work In Progress			1/24/2013 8:11:06 AM					
Arreola, Rudy	AS PER MY CONVERSATION WITH MIKE MUNOZ NEED TO CHANGE OUT FILTERS AT GES CAMPUS.								
<u>Rudy Arreola</u>									
95770	Main Building	Hallway/Corridor			11/26/2012		100		\$0.00
Medium	Work In Progress			11/26/2012 12:45:44					
Arreola, Rudy	Water fountain needed to be turned off water kept running solenoid needs to be replaced.								
<u>Rudy Arreola</u>									
95660	Main Building	Office			11/19/2012		107		\$0.00
Medium	Work In Progress			11/19/2012 9:27:33 AM					
Arreola, Rudy	PRINCIPAL OFFICE HAS SOME LIGHTS OFF. THANKS				11/20/12 - Asp Mike, route to Rudy.				
<u>Luis Solis</u>									
99316	Main Building	Classroom			3/4/2013		2		\$0.00
Medium	Work In Progress	102		3/4/2013 3:28:30 PM					
Arreola, Rudy	I have blinking lights in my room. Is ther a chance that you can change it before testing								
<u>Angie Flores</u>									
Count: 27 Work Orders		Avg. Age of WO's 48		Total for Loma Linda ES			0	\$0.00	

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
89435					7/1/2012	8/1/2012	248		\$0.00
Medium	Work In Progress			7/1/2012 12:30:58 AM					
Ramirez, Joe	Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
89436					7/1/2012	8/1/2012	248		\$0.00
Medium	Work In Progress			7/1/2012 12:30:58 AM					
Ramirez, Joe	Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90983		Portables			8/8/2012		210		\$0.00
Medium	Work In Progress			8/8/2012 9:32:51 AM					
Estrada, Jesus	Mr. Estrada,								
	On portables #801 and #802 the carpet is torn out and both rooms need new carpet. If you have a chance, could you please stop by and see it.								
	Thank you								
<u>Luis Saucedo</u>									
91491					8/17/2012		201		\$0.00
Medium	Work In Progress			8/17/2012 12:42:10 PM					
Estrada, Jesus	ATTEN. ALFREDO, RMS.201,202,203,204,205. CARPET NEEDS TO BE REPLACED WITH FLOOR TILE.								
<u>Joe Ramirez</u>									
94625		Custodial			10/26/2012		131		\$0.00
Medium	Work In Progress			10/26/2012 6:55:00 AM					
Estrada, Jesus	Mr. Estrada, On portables #602 the carpet is torn out and need new carpet. If you have a chance, could you please stop by and see it. Thank you								
<u>Luis Saucedo</u>									
97920		Custodial			1/31/2013		34		\$0.00
Medium	Work In Progress			1/31/2013 8:13:17 AM					
Carbajal, Jimmy	please #1166 vaccum no power at all thank you								
<u>Luis Saucedo</u>									
99206					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:53 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
96318					12/6/2012		90		\$0.00
Medium	Work In Progress			12/6/2012 1:02:43 PM					
Briones, Enrique	please Warehouse ATT: LARRY MARTINES we have broken computer desk, old furniture, student desk broken, etc. thank you								
<u>Luis Saucedo</u>									
97808					1/29/2013		36		\$0.00
Medium	Work In Progress			1/29/2013 8:06:10 AM					
Lozoya, Manny	bathroom partitions north and south ,boys' and girls' bathrooms need to be replaced								
<u>Joe Ramirez</u>									
99337					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 12:19:58 AM					
Apodaca, Mario	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99222					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:01 AM					
Munoz, Michael	Yearly - Mesquite ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97634		Custodial			1/24/2013		41		\$0.00
Medium	Work In Progress			1/24/2013 9:12:26 AM					
Carbajal, Jimmy	please vaccum #1168 the motor is not working making a lot of noise thank you								
<u>Luis Saucedo</u>									
95365					11/9/2012		117		\$0.00
Medium	Work In Progress			11/9/2012 1:09:02 PM					
Lozoya, Manny	sothside boys and girls bathroom stalls need to be replaced the floor securing brackets are either broken or rusted through and also most of the stalls are very rusted								
<u>Joe Ramirez</u>									
97385					1/16/2013		49		\$0.00
Medium	Work In Progress			1/16/2013 8:51:53 AM					
Lozoya, Manny	door handle rm.229 not working properly neds to be replaced								
<u>Joe Ramirez</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
97874		Parking Lot			1/30/2013		35		\$0.00
High	Work In Progress			1/30/2013 1:59:05 PM					
Ramirez, Joe	as per conversation, all ada parking spaces need to be re-painted as well as fire lanes and parking stripes. not all paking spaces are used nor the ada parking so this project can be done during hours of operation.								
<u>Michael Munoz</u>									
98997					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:25 AM					
Ramirez, Joe	Yearly - Mesquite ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98511					2/14/2013		20		\$0.00
Medium	Work In Progress			2/14/2013 9:17:23 AM					
Lozoya, Manny	AS PER MR. BAKER, HIS MASTER KEY TO KITCHEN (BACKDOOR) DID NOT WORK AT MESQUITE ELEM. HIS UNDERSTANDING WAS THAT HIS MASTER SHOULD BE ABLE TO OPEN ALL KITCHENS. PLEASE ADVISE.								
<u>Maritza Gonzalez</u>									
97630					1/24/2013		41		\$0.00
Medium	Work In Progress			1/24/2013 8:50:56 AM					
Lozoya, Manny	i need 4 padlocks for the new gates that are being installed								
<u>Joe Ramirez</u>									
95919					11/29/2012		97		\$0.00
Medium	Work In Progress			11/29/2012 8:12:40 AM					
Solis, Lorenzo	heater coil unit rm. 402 not working								
<u>Joe Ramirez</u>									
99203					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:52 AM					
Ramirez, Joe	Yearly - Mesquite ES A-10 HP Rooftop Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98407					2/12/2013		22		\$0.00
Medium	Work In Progress			2/12/2013 3:01:55 PM					
Ontiveros, Joe	toilet in boys' bathroom continues to clog up even after numerous augering								
Joe Ramirez									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Mesquite ES

96769					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:39 AM					
Villalobos, David	Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.								

Margret Villalobos

98927					2/27/2013		7		\$0.00
Medium	Work In Progress			2/27/2013 7:32:25 AM					
Villalobos, David	attent. david v. the backflow preventer is not working properly i believe there is something stuck needs to be repaired or replaced. need to water the grounds.								

Joe Ramirez

99201					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:51 AM					
Ramirez, Joe	Monthly - Mesquite ES - Barrack Drainage (Monthly) - Refer to PM schedule details.								

Margret Villalobos

99286					3/4/2013		2		\$0.00
Medium	Work In Progress			3/4/2013 8:54:28 AM					
Sotelo, Enrique	electrical outlets on westside wall in rm.601 continue to go off and on please check it out								

Joe Ramirez

97882					1/30/2013		35		\$0.00
Medium	Work In Progress			1/30/2013 2:25:48 PM					
Ramirez, Joe	interior doors need to be painted. please order paint. 55200 thank you								

Michael Munoz

97179					1/11/2013		54		\$0.00
Medium	Work In Progress			1/11/2013 3:47:35 PM					
Ramirez, Joe	please paint doors to portable 611 & 612. thank you								

Selma Nevarez

95182		Athletic Field			11/5/2012		121		\$0.00
Medium	Work In Progress			11/5/2012 3:27:39 PM					
Ramirez, Joe	As per mr. Mike need to in stall irrigation system on playing fields.								

Guadalupe Ontiveros

99268					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:21 AM					
Sanchez, Raul	Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.								

Margret Villalobos

3/6/2013 4:22:58 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
98128					2/3/2013		31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:56 AM					
Sanchez, Raul	Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91551					8/20/2012		198		\$0.00
Medium	Work In Progress			8/20/2012 12:50:51 PM					
Ramirez, Joe	need to install frp panel in rms. 801,802.								
<u>Joe Ramirez</u>									
99204					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:52 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97869					1/30/2013		35		\$0.00
High	Work In Progress			1/30/2013 1:23:23 PM					
Ramirez, Joe	need to clean in back and around morgan building, (ie commodes, pipes, pipe nedles. the pbraches need to be trimmed this is a fire hazard.								
<u>Michael Munoz</u>									
97877					1/30/2013		35		\$0.00
Medium	Work In Progress			1/30/2013 2:02:30 PM					
Ramirez, Joe	please clean along fence and between community baseball park and playground.								
<u>Michael Munoz</u>									
97878					1/30/2013		35		\$0.00
Medium	Work In Progress			1/30/2013 2:05:19 PM					
Ramirez, Joe	please make wells to trees on the south play structures next to community baseball park. the grass is up against the trunk therefore choking th tree. also check all irrigation and bubblers to all trees and playing fields.								
<u>Michael Munoz</u>									
99202					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:52 AM					
Ramirez, Joe	Monthly - Mesquite ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99205					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:53 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
3/6/2013 4:22:58 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

Count: 37 Work Orders Avg. Age of WO's 61 Total for Mesquite ES 0 \$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: North Valley ES									
96724					1/6/2013		59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:17 AM					
Holguin, Alfredo	Monthly - North Valley ES-Fire Pump Engine-Quartly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99147					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:27 AM					
Vega, Danny	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99148					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:27 AM					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93977					10/10/2012		147		\$0.00
Medium	Work In Progress			10/10/2012 7:41:20 AM					
Flores, Pete	truck #76 needs brakes checked-also it stulls on the road it just dies and leaks water thru water pump.plz ck anti freeze.my tool box is loose and will not close .plz remove								
<u>Danny Vega</u>									
94004					10/10/2012		147		\$0.00
Medium	Work In Progress			10/10/2012 3:11:28 PM					
Sotelo, Enrique	mechanical rms by rms 301-304-303-309-300-203208-210-102and by lounge lites are out bad emergency ballast								
<u>Danny Vega</u>									
97394					1/16/2013		49		\$0.00
Medium	Work In Progress			1/16/2013 12:18:39 PM					
Sotelo, Enrique	emergency lamp ballast burnt out boys restrms/rio grande wing								
<u>Danny Vega</u>									
97989					2/1/2013		33		\$0.00
Medium	Work In Progress			2/1/2013 12:50:37 PM					
Sotelo, Enrique	emergency lamp ballast in burnt out rio grande wing by rms 301-304. please replace								
<u>Danny Vega</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
96754					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:33 AM				
Villalobos, David	Yearly - North Valley ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99297					3/4/2013		2		\$0.00
Medium	Work In Progress				3/4/2013 11:44:56 AM				
Lozoya, Manny	need a chain for a walking gate that stays open.								
<u>Javier Parra</u>									
99146					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:27 AM				
Vega, Danny	Yearly - North Valley ES A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97366					1/15/2013		50		\$0.00
Medium	Work In Progress				1/15/2013 3:53:46 PM				
Lozoya, Manny	need help to secure front entrance door/divider bar core jammed /will not lock plz help								
<u>Danny Vega</u>									
91740		Classroom			8/23/2012		195		\$0.00
Medium	Work In Progress	various			8/23/2012 10:11:46 AM				
Lozoya, Manny	Need to obtain additional cabinet keys for certain classrooms.								
<u>Priscilla Martinez</u>									
89953					7/18/2012		231		\$0.00
Medium	Work In Progress				7/18/2012 10:38:49 AM				
Lozoya, Manny	need exterior security door handle plates installed in rm 107-108-211-212-309-310 doors to keep vandals from prying doors open as per MR. T								
<u>Danny Vega</u>									
94886					11/1/2012		125		\$0.00
Medium	Work In Progress				11/1/2012 10:47:05 AM				
Lozoya, Manny	door in between techers lounge and hallway wont close.								
<u>Javier Parra</u>									
99296					3/4/2013		2		\$0.00
Medium	Work In Progress				3/4/2013 11:44:04 AM				
Carbajal, Jimmy	handle on vacuum wont stay up and vacuum keeps turning on and off by itself also wont pick up good.								
<u>Javier Parra</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: North Valley ES									
99223					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:26:01 AM				
Munoz, Michael	Yearly - North Valley ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99363		Office			3/5/2013		1		\$0.00
Medium	Work In Progress				3/5/2013 2:03:13 PM				
Briones, Enrique	Please pick up Math Adoption samples boxes								
<u>Larry Martinez</u>									
98291					2/7/2013		27		\$0.00
Medium	Work In Progress				2/7/2013 1:51:55 PM				
Villalobos, Margret	need interior and exterior sprayed for spiders.they are all over campus					Waiting on price quote			
<u>Danny Vega</u>									
99151					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:29 AM				
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96782					1/6/2013		59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:44 AM				
Orozco, Daniel	Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99006					2/28/2013		6		\$0.00
Medium	Work In Progress				2/28/2013 12:28:29 AM				
Munoz, Michael	Yearly - North Valley ES - Fire Pump Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 21 Work Orders			Avg. Age of WO's	57	Total for North Valley ES		0		\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
99152					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:29 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99084	Main Building				3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 1:53:12 PM					
Sotelo, Enrique	(SENSOR) LIGHTS IN LOUNGE WILL NOT TURN OFF, OVERRIDE SWITCH IS NOT WORKING. (LIGHTS AND SWITCHES WERE REPLACED DURING THE SUMMER.)								
<u>Adam Montoya</u>									
98525	Main Building	Classroom			2/14/2013		20		\$0.00
Medium	Work In Progress			2/14/2013 3:16:00 PM					
Ontiveros, Joe	WATER HEATER IN DAYCARE ROOM 114 IS LEAKING WATER. NEED FIXED OR REPLACED AS SOON AS POSSIBLE. 3.85 GALLON.								
<u>Adam Montoya</u>									
99336					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 12:19:57 AM					
Apodaca, Mario	Monthly - Northern Pre-K- Domestic Water Filters - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99238					3/3/2013	3/14/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:08 AM					
Munoz, Michael	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98988					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:21 AM					
Vega, Danny	Yearly - Northern Pre-K C-11 (Evap.Cooler)Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96767					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:38 AM					
Villalobos, David	Yearly - Northern Pre-K Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
99149					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:28 AM					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99150					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:28 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 9 Work Orders			Avg. Age of WO's	11	Total for Northern On-Track Pre-K (LM)			0	\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
99111					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:10 AM					
Ruiz, Maria	Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98832					2/25/2013		9		\$0.00
Medium	Work In Progress			2/25/2013 3:38:41 PM					
Ronquillo, Ruben	Need signs made 12 by 18 Inches That will read Well Number 1 through 15 . Need 1 of each number .Thanks								
<u>Mario Apodaca</u>									
93067					9/20/2012		167		\$0.00
Medium	Work In Progress			9/20/2012 10:51:22 AM					
Ronquillo, Ruben	as per meeting held, please dispose of any unused material and clean and organize barracks. thank you.		Continuing from 68685						
<u>Michael Munoz</u>									
98242					2/6/2013		28		\$0.00
High	Work In Progress			2/6/2013 8:40:45 AM					
Flores, Pete	truck #137 needs to be service oil change. breaks need to be change.								
<u>Guadalupe Ontiveros</u>									
96035					11/30/2012		96		\$0.00
Medium	Work In Progress			11/30/2012 3:53:59 PM					
Flores, Pete	vehicle 99 is leaking oil and shocks sounds like if it is loose. please check. thank you								
<u>Michael Munoz</u>									
99085					3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 2:17:56 PM					
Flores, Pete	Work Truck #193: Need to change oil to work truck.								
<u>Joe Ontiveros</u>									
99307					3/4/2013		2		\$0.00
Medium	Work In Progress			3/4/2013 1:01:31 PM					
Ontiveros, Guadalupe	Need to move some of the dirt stockpiles by the barracks by friday March 8. Check with Alfredo on what piles to move and where to.								
<u>Alfredo Holguin</u>									
97897		Athletic Field			1/30/2013		35		\$0.00
Medium	Work In Progress			1/30/2013 3:48:20 PM					
Ontiveros, Guadalupe	warehouse personal need storage 8'x 40'								
Guadalupe Ontiveros									

3/6/2013 4:22:58 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
95523		Parking Lot			11/14/2012		112		\$0.00
Medium	Work In Progress			11/14/2012 2:39:27 PM					
Ontiveros, Guadalupe	Parking Area on south side of fence between warehouse and GMS Annex - Install parking stops along fence and around fire hydrant to provide enough clearance around hydrant and next to fence.								
Alfredo Holguin									
97770					1/28/2013		37		\$0.00
Medium	Work In Progress			1/28/2013 12:50:38 PM					
Flores, Pete	Vehicle 99 - Battery light has turned on.								
Michael Munoz									
96770					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:40 AM					
Villalobos, David	Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
97438					1/17/2013		48		\$0.00
High	Work In Progress			1/17/2013 6:56:41 AM					
Sotelo, Enrique	please cekck lighting on all buildings at ppd, there are alot of lights that are out. also please install another light on the pole int the auto shop parking lot thank you								
Michael Munoz									
99213					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:57 AM					
Munoz, Michael	Monthly - Physical Plant - Grease Trap (Custodial) - Refer to PM schedule details.								
Margret Villalobos									
92274					9/2/2012		185		\$0.00
Medium	Work In Progress			9/2/2012 12:21:47 AM					
Munoz, Michael	Monthly - Physical Plant - Grease Trap (Custodial) - Refer to PM schedule details.								
Margret Villalobos									
99283					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:28 AM					
Diaz, Sebastian	Monthly - Physical Plant - Lint Trap (Quarterly) - Refer to PM schedule details.								
Margret Villalobos									
99237					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:08 AM					
Munoz, Michael	Yearly - Physical Plant Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
3/6/2013 4:22:58 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
95647					11/16/2012		110		\$0.00
High	Work In Progress			11/16/2012 3:52:03 PM					
Munoz, Michael	this is to provide service or replace fire extinguisher (out-dated codes) at the following sites gac,ae,br,che,chs,cms,dp,dt,dv,ge,ghs,gms,northern pre-k,lu,ll,mq,nv,ppd,re,ste,sth,sp,sr,vado.								
Michael Munoz									
99278					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:25 AM					
Diaz, Sebastian	Monthly - Physical Plant FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
98667					2/20/2013		14		\$0.00
Medium	Work In Progress			2/20/2013 1:50:08 PM					
Lozoya, Manny	Custodial Warehouse Roll Up Door - Very Noisy needs to be cleaned and lubricated?								
Alfredo Holguin									
95524					11/14/2012		112		\$0.00
Medium	Work In Progress			11/14/2012 2:45:56 PM					
Apodaca, Mario	PPD Sewage treatment plant The expansion joints At the aeration basin are expanding and contracting due to cold weather loosing some product need to be repaired. As soon as possible								
Mario Apodaca									
93023					9/19/2012		168		\$0.00
Medium	Work In Progress			9/19/2012 3:17:08 PM					
Apodaca, Mario	need to place order for domestic water filters for several school sites								
Mario Apodaca									
93179		Lift Station			9/24/2012		163		\$0.00
Medium	Work In Progress			9/24/2012 2:41:20 PM					
Gonzalez, Salvador	Meet to manufacture A base for the domestic tablet container for the waste water treatment plant								
Mario Apodaca									
97854					1/30/2013		35		\$0.00
Medium	Work In Progress			1/30/2013 8:20:56 AM					
Gonzalez, Salvador	Need gas welder machine to replace small one installed on truck.								
Salvador Gonzalez									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Physical Plant Complex

98757	Food Services				2/22/2013		12		\$0.00
Medium	Work In Progress			2/22/2013 1:04:15 PM					
Lozoya, Manny	please make and assign the following keys 6/7 grand masters to gabriel provencio, robert duran, felipe nevarez and johhny lechuga. 2 per.thank you								

99288	Food Services				3/4/2013		2		\$0.00
Medium	Work In Progress			3/4/2013 9:41:56 AM					
Orozco, Daniel	FREEZER # 2 IS AT 38 DEGREES.								

Maritza Gonzalez

98752	Motor Vehicle				2/22/2013		12		\$0.00
Medium	Work In Progress	vehicle#111		2/22/2013 11:01:54 AM					
Flores, Pete	difficulty starting vehicle at times- cranks but will not start								

Pete Flores

98753	Motor Vehicle				2/22/2013		12		\$0.00
Medium	Work In Progress	vehicle#93		2/22/2013 11:04:27 AM					
Flores, Pete	please check electrical system-batteries are weak and truck is hard to start								

Pete Flores

98754	Motor Vehicle				2/22/2013		12		\$0.00
Medium	Work In Progress	vehicle#23		2/22/2013 11:07:59 AM					
Flores, Pete	brakes worn beyond limits and losing excessive amounts of engine coolant. please check and advise,also left rear tire losing air.								

Pete Flores

98755	Motor Vehicle				2/22/2013		12		\$0.00
Medium	Work In Progress	vehicle#51		2/22/2013 11:10:36 AM					
Flores, Pete	please check braking system,hissing sound heard when brakes are applied and brake pedal travels to the floor								

Pete Flores

94420	Motor Vehicle				10/22/2012		135		\$0.00
Medium	Work In Progress	vehicle#101		10/22/2012 11:16:35					
Flores, Pete	truck has difficulty achieving highway speed,possibly a fuel concern. check and advise.								

Pete Flores

94426	Motor Vehicle				10/22/2012		135		\$0.00
Medium	Work In Progress	vehicle#126		10/22/2012 11:27:16					
Flores, Pete	water pump losing coolant and runs very rough intermittently.please check								

Pete Flores

3/6/2013 4:22:58 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
97623	Motor Vehicle				1/24/2013		41		\$0.00
Medium	Work In Progress	vehicle#114		1/24/2013 7:51:18 AM					
Flores, Pete	please repair sun damage to rear speaker deck and torn headliner.								
Pete Flores									
96596	Motor Vehicle				12/13/2012		83		\$0.00
Medium	Work In Progress	vehicle#143		12/13/2012 2:36:26 PM					
Flores, Pete	check for leaks at fuel injection pump.								
Pete Flores									
99082	Motor Vehicle				3/1/2013		5		\$0.00
Medium	Work In Progress	vehicle#143		3/1/2013 12:54:10 PM					
Flores, Pete	batteries weak and in need of replacement.								
Pete Flores									
97157	Motor Vehicle				1/11/2013		54		\$0.00
Medium	Work In Progress	vehicle#153		1/11/2013 9:00:45 AM					
Flores, Pete	bench seat torn and metal is exposed.								
Pete Flores									
97158	Motor Vehicle				1/11/2013		54		\$0.00
Medium	Work In Progress	vehicles 147,187		1/11/2013 9:11:54 AM					
Flores, Pete	please repair windshields on vehicles as needed								
Pete Flores									
97243	Motor Vehicle				1/14/2013		51		\$0.00
Medium	Work In Progress	vehicle#18		1/14/2013 9:43:00 AM					
Flores, Pete	shocks worn and need replacement,also alternator charging excessively causing electrical concerns.engine leaking oil.								
Pete Flores									
95928	Motor Vehicle				11/29/2012		97		\$0.00
Medium	Work In Progress	vehicle#86		11/29/2012 9:53:45 AM					
Flores, Pete	van is running rough and engine is misfiring during normal operation.								
Pete Flores									
96593	Motor Vehicle				12/13/2012		83		\$0.00
Medium	Work In Progress	vehicles-		12/13/2012 2:27:15 PM					
Perez, Raul	please refuel,clean & wash as required by daily trip schedule.								
Pete Flores									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
96594	Motor Vehicle				12/13/2012		83		\$0.00
Medium	Work In Progress	vehicles-		12/13/2012 2:31:49 PM					
Perez, Raul	please check and prepare listed vehicles for daily trip schedules.								
Pete Flores									
96595	Motor Vehicle				12/13/2012		83		\$0.00
Medium	Work In Progress	vehicles-		12/13/2012 2:34:33 PM					
Perez, Raul	please clean, wash, and prepare for daily trip schedule.								
Pete Flores									
94667	Motor Vehicle				10/26/2012		131		\$0.00
Medium	Work In Progress	vehicles 188,161		10/26/2012 3:24:12 PM					
Perez, Raul	please wash, clean, & re-fuel as required by daily trip schedule.								
Pete Flores									
91931	Motor Vehicle				8/28/2012		190		\$0.00
Medium	Work In Progress			8/28/2012 7:52:34 AM					
Flores, Pete	driver seat is tearing on unit 170, request seat covers for it and a step to get on the truck to avoid any more damage to seats and steering wheel while getting into the truck. even a dash mat for the dashboard to avoid sun damage to it . thank u !!								
Fred Appelzoller									
98932	Motor Vehicle				2/27/2013		7		\$0.00
Medium	Work In Progress			2/27/2013 9:06:33 AM					
Lozoya, Manny	Install locks on gas pumps								
Pete Flores									
98555	Motor Vehicle				2/15/2013		19		\$0.00
Medium	Work In Progress	heaters		2/15/2013 8:23:34 AM					
Solis, Lorenzo	please check shop heaters, inoperative at times and very noisy								
Pete Flores									
99070	Purchasing				3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 8:30:37 AM					
Lozoya, Manny	Issue 6 and 7 pin Master Keys to David Ruiz, Mail Clerk								
Alfredo Holguin									
99088	Purchasing	Office			3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 3:12:12 PM					
Diaz, Sebastian	Please replace Lights in IM Office & Warehouse.								
Larry Martinez									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
95859	Purchasing	Office			11/27/2012		99		\$0.00
Medium	Work In Progress				11/27/2012 4:14:46 PM				
Lozoya, Manny		Please make a key for IM office 2. For larry							
<u>Larry Martinez</u>									
94890	Purchasing				11/1/2012		125		\$0.00
Medium	Work In Progress				11/1/2012 11:12:31 AM				
Lozoya, Manny		Main Entry Lock to PPD-Construction Offices - core is sticking and hard to unlock							
<u>Alfredo Holguin</u>									
97246	Maintenance				1/14/2013		51		\$0.00
Medium	Work In Progress				1/14/2013 9:53:38 AM				
Lozoya, Manny		NEED THREE DC1 LOCKS FOR NEW FENCED AREA AT BARRACKS THANK YOU							
<u>Ruben Ronquillo</u>									
97103	Maintenance				1/10/2013		55		\$0.00
Medium	Work In Progress				1/10/2013 9:58:53 AM				
Ronquillo, Ruben		PURCHASE NEW TIRES FOR JLG1935 SCISSOR LIFT, AND INSTALL							
<u>Ruben Ronquillo</u>									
91801	Maintenance				8/24/2012		194		\$0.00
Medium	Work In Progress				8/24/2012 7:25:21 AM				
Munoz, Michael		please clean-out lint tank for custodial washing machine. the offices and warehouse smell like sewer.							
<u>Alfredo Holguin</u>									
98304					2/7/2013		27		\$0.00
Medium	Work In Progress				2/7/2013 3:42:10 PM				
Carrasco, Danny		REQUESTING COVERS FOR ALL (3) SCISSOR LIFTS							
<u>Danny Carrasco</u>									
Count: 53 Work Orders		Avg. Age of WO's 62		Total for Physical Plant Complex				0	\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
93203					9/25/2012		162		\$0.00
Medium	Work In Progress			9/25/2012 7:35:15 AM					
Munoz, Michael	need to install new fence w/ gates where mobil home occupant used to be. security for tractors and morgan.								
<u>Alfredo Holguin</u>									
90107					7/24/2012		225		\$0.00
Medium	Work In Progress			7/24/2012 11:06:46 AM					
Estrada, Jesus	NEED TO REPLACE CARPET TO VCT IN BACK STORAGE OFFICE AREA. SEE RAUL ROMOER (HC).								
<u>Jesus Estrada</u>									
99158					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:32 AM					
Moncayo, Fernando	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98062					2/3/2013	2/9/2013	31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:29 AM					
Moncayo, Fernando	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97774		Athletic Field			1/28/2013		37		\$0.00
Medium	Work In Progress			1/28/2013 1:53:46 PM					
Ontiveros, Guadalupe	need wide trailer for transportation of z-track 997 mowers.								
<u>Guadalupe Ontiveros</u>									
97838					1/29/2013		36		\$0.00
Medium	Work In Progress			1/29/2013 3:33:37 PM					
Gonzalez, Salvador	need to build frame of metal for outside water fountain								
<u>Carlos Hernandez</u>									
93082					9/20/2012		167		\$0.00
Medium	Work In Progress			9/20/2012 3:22:08 PM					
Gonzalez, Salvador	need to make a metal box (plumbing protection) for outside drinking fountains, plywood won't stop vandals								
<u>Fernando Moncayo</u>									
98705					2/21/2013		13		\$0.00
Medium	Work In Progress			2/21/2013 8:07:53 AM					
Orozco, Daniel	OVENS ARE ACTING UP AGAIN, TAKING A LONG TIME TO HEAT. SNP MANAGER EMILIA C. 589.2550								
<u>Maritza Gonzalez</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
97057					1/9/2013		56		\$0.00
Medium	Work In Progress			1/9/2013 12:26:08 PM					
Orozco, Daniel	LIGHT ON DISHWASHER IS OUT. SNP MANAGER EMILIA C. 589.2550								
Maritza Gonzalez									
97058					1/9/2013		56		\$0.00
Medium	Work In Progress			1/9/2013 12:27:17 PM					
Orozco, Daniel	OVEN ON STOVE IS NOT HEATING. SNP MANAGER EMILIA C. 589.2550								
Maritza Gonzalez									
99351					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 10:52:19 AM					
Orozco, Daniel	Both serving lines do not drain properly clogging and overflowing at times. SNP Manager Emilia C. 589.2550								
Maritza Gonzalez									
99352					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 10:53:59 AM					
Orozco, Daniel	Grill does not work at all. SNP Manager Emilia C. 589.2550								
Maritza Gonzalez									
99353					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 10:54:23 AM					
Orozco, Daniel	Two burners on stove top do not light up. SNP Manager Emilia C. 589.2550								
Maritza Gonzalez									
99355					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 10:55:09 AM					
Orozco, Daniel	Oven timers do not function. Bottom oven either over or under heats at times making cooking inconsistent. SNP Manager Emilia C. 589.2550								
Maritza Gonzalez									
99224					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:02 AM					
Munoz, Michael	Yearly - Riverside ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
97947	Main Building	Classroom			1/31/2013		34		\$0.00
Medium	Work In Progress	Room#39			1/31/2013 3:04:51 PM				
Ambriz, Juan	Need to Install white board								
Juan Ambriz									

3/6/2013 4:22:58 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
92671	Main Building	Parking Lot			9/11/2012		176		\$0.00
Medium	Work In Progress			9/11/2012 11:07:54 AM					
Moncayo, Fernando	Paint back parking lot with the assigned titles for Administration office/cafeteria, handicapped parkings, ect.								
<u>Olga Arias</u>									
97653	Main Building	Restroom (Girls)			1/24/2013		41		\$0.00
Medium	Work In Progress	front of office		1/24/2013 2:59:49 PM					
Villalobos, David	Girls restroom last stable missing missing toilet seat								
<u>Juan Ambriz</u>									
98258	Main Building				2/6/2013		28		\$0.00
Medium	Work In Progress			2/6/2013 12:06:58 PM					
Villalobos, David	Problems in the girl restroom with toilet leaking as per custodian								
<u>Olga Arias</u>									
99026	Main Building	Portables			2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 8:56:04 AM					
Gonzalez, Salvador	Need to weld ramp to platform in portable								
<u>Juan Ambriz</u>									
91078	New Wing 1/02				8/9/2012		209		\$0.00
Medium	Work In Progress			8/9/2012 3:29:12 PM					
Villalobos, David	need to replace toilet room 117 broken								
<u>Carlos Hernandez</u>									
97407	New Wing 1/02	Classroom			1/16/2013		49		\$0.00
Medium	Work In Progress			1/16/2013 3:07:49 PM					
Villalobos, David	need new toilet room 144								
<u>Carlos Hernandez</u>									
97406					1/16/2013		49		\$0.00
Medium	Work In Progress			1/16/2013 3:05:38 PM					
Villalobos, David	need new toilet room 148								
<u>Carlos Hernandez</u>									
96757					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:34 AM					
Villalobos, David	Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
89794					7/3/2012		246		\$0.00
Medium	Work In Progress			7/12/2012 10:22:48 AM					
Villalobos, David	Outside water fountain vandalized.								
Carlos Hernandez									
90202					7/25/2012		224		\$0.00
Medium	Work In Progress			7/25/2012 3:44:33 PM					
Villalobos, David	need new toilet in outside teacher bathroom upper wing								
Carlos Hernandez									
97539		Restroom (Boys)			1/22/2013		43		\$0.00
High	Work In Progress			1/22/2013 11:40:53 AM					
Villalobos, David	please unclog drains in rest rooms and remove temporary drain line. thank you								
Michael Munoz									
94470					10/23/2012		134		\$0.00
Medium	Work In Progress			10/23/2012 8:38:46 AM					
Villalobos, David	need round toilet seats for "kohler" one piece small toilet								
Fernando Moncayo									
98990					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:22 AM					
Moncayo, Fernando	Monthly - Riverside ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
Margret Villalobos									
98987					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:20 AM					
Hernandez, Carlos	Yearly - Riverside ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									
99136					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:22 AM					
Hernandez, Carlos	Yearly - Riverside ES A-10 HP Rooftop Yearly - Refer to PM schedule details.								
Margret Villalobos									
99303					3/4/2013		2		\$0.00
Medium	Work In Progress			3/4/2013 12:10:19 PM					
Ambriz, Jose	circulating pump for boiler (north boiler) leaking water								
Carlos Hernandez									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
97477					1/18/2013		47		\$0.00
Medium	Work In Progress			1/18/2013 9:05:34 AM					
Ambriz, Jose	need to replace pressure relief valve on both boilers leaking								
Carlos Hernandez									
98348					2/11/2013		23		\$0.00
Medium	Work In Progress			2/11/2013 11:44:04 AM					
Flores, Pete	NEED GASOLINE AND 2 CYCLE OIL								
Jesus Estrada									
99350					3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 10:51:26 AM					
Lara, Ralph	Back screen doors are broken, difficult to open and close. SNP Manager Emilia C. 589.2550								
Maritza Gonzalez									
97111					1/10/2013		55		\$0.00
Medium	Work In Progress			1/10/2013 11:50:47 AM					
Ambriz, Juan	Asp walk-thru on 1/7/13 West Electrical Room is being used as storage blocking panels - code violation.								
Carlos Castillo									
95579					11/15/2012		111		\$0.00
Scheduled	Work In Progress			11/15/2012 10:48:21					
Moncayo, Fernando	Ms. Sherri with CLEARResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You								
99160					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:33 AM					
Moncayo, Fernando	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
98066					2/3/2013	2/11/2013	31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:31 AM					
Moncayo, Fernando	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
98065					2/3/2013	2/11/2013	31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:30 AM					
Moncayo, Fernando	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
3/6/2013 4:22:58 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
99069					3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 8:10:31 AM					
Hernandez, Carlos	Exposed PVC pipe in playground area								
Vicente Sanchez									
96409					12/9/2012	12/25/2012	87		\$0.00
Medium	Work In Progress			12/9/2012 12:16:24 AM					
Moncayo, Fernando	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
98326					2/10/2013	2/26/2013	24		\$0.00
Medium	Work In Progress			2/10/2013 12:20:34 AM					
Moncayo, Fernando	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
99162					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:34 AM					
Moncayo, Fernando	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
93729					10/1/2012		156		\$0.00
Medium	Work In Progress			10/1/2012 3:14:30 PM					
Moncayo, Fernando	cleaned and serviced heating equipment								
Fernando Moncayo									
Count: 45 Work Orders		Avg. Age of WO's 60		Total for Riverside ES			0	\$0.00	

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: RTC - Alliance									
98857		Portables			2/26/2013		8		\$0.00
Medium	Work In Progress				2/26/2013 8:11:16 AM				
Prospero, Manuel		our sidewalks are full of sand and it is hard for students and staff to walk							
Gloria Delgado									
98856					2/26/2013		8		\$0.00
Medium	Work In Progress				2/26/2013 8:09:19 AM				
Lara, Ralph		we are having trouble opening the office door with the keys and attachments are loose							
Gloria Delgado									
98719					2/21/2013		13		\$0.00
Medium	Work In Progress				2/21/2013 2:11:17 PM				
Castillo, Carlos		Need to check electrical outlets in the three portables. Have electrical cords running on floor to connect computers.							
Cora Ramirez									
Count: 3 Work Orders		Avg. Age of WO's		10	Total for RTC - Alliance			0	\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		San Miguel ES							
96761					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:36 AM					
Villalobos, David	Yearly - San Miguel ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
98125					2/3/2013		31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:55 AM					
Sanchez, Raul	Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
99269					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:21 AM					
Sanchez, Raul	Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
98540	Cafeteria				2/14/2013		20		\$0.00
Medium	Work In Progress			2/14/2013 3:57:51 PM					
Estrada, Jesus	Replace all VCT damaged by water leak				2/25 - Routed to J. Estrada asp Mike				
Alfredo Holguin									
Count: 4 Work Orders			Avg. Age of WO's	28	Total for San Miguel ES		0		\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa ES

98568	Main Building	Classroom			2/15/2013		19		\$0.00
Medium	Work In Progress	Room #209			2/15/2013 1:43:51 PM				
Villalobos, Margret		Problem communicating through Tracer Summit							

Juan Ambriz

97635	Main Building	Stairway			1/24/2013		41		\$0.00
Medium	Work In Progress	Art portable			1/24/2013 9:12:56 AM				
Gonzalez, Salvador		A ramp is needed at the entrance of the Art portable. Thank you.							

Rita Mendez

97536	Main Building	Athletic Field			1/22/2013		43		\$0.00
Medium	Work In Progress	OUTSIDE CASA			1/22/2013 10:24:14 AM				
Villalobos, David		WATER FOUNTAIN IS LEAKING. PLEASE CHECK. THANKS.							

Rita Mendez

98214	Main Building	Cafeteria			2/5/2013		29		\$0.00
Medium	Work In Progress	Kitchen			2/5/2013 3:18:42 PM				
Villalobos, David		Need to replace faucets in kitchen							

Juan Ambriz

97399	Main Building	Cafeteria			1/16/2013		49		\$0.00
Medium	Work In Progress	cafeteria			1/16/2013 1:25:53 PM				
Castillo, Carlos		PLEASE CHECK THE LIGHTS IN THE CAFETERIA. THERE ARE 3 LIGHTS THAT DO NOT WORK. PLEASE CHECK FOR MISSING LIGHTS ALSO, (WERE SUPPOSED TO BE REPLACED LAST SCHOOL YEAR). SECOND REQUEST. THANKS							

Rita Mendez

96473	Main Building	Cafeteria			12/11/2012		85		\$0.00
Medium	Work In Progress	CAFETERIA			12/11/2012 11:24:42				
Castillo, Carlos		A NEW LIGHT FIXTURE IS NEEDED IN THE CAFETERIA. THE OTHER WAS BROKEN AND HAD TO BE REMOVED. THANKS.							

Rita Mendez

96474	Main Building	Cafeteria			12/11/2012		85		\$0.00
Medium	Work In Progress	CAFETERIA			12/11/2012 11:27:48				
Castillo, Carlos		THE LIGHTS IN THE CAFETERIA NEED TO BE CHECKED. NOT ALL OF THEM ARE WORKING. THANKS.							

Rita Mendez

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
96581	Main Building	Portables			12/13/2012		83		\$0.00
Medium	Work In Progress	Portable B			12/13/2012 10:57:58				
Castillo, Carlos		Please replace 2 ceiling lights that are out in Portable B.							
Melynda Menchaca									
98556	Main Building	Classroom			2/15/2013		19		\$0.00
Medium	Work In Progress	Room #209			2/15/2013 8:33:15 AM				
Ambriz, Juan		Need to replace leaking sink faucet							
Juan Ambriz									
98666	Main Building	Classroom			2/20/2013		14		\$0.00
Medium	Work In Progress	Room #204			2/20/2013 12:41:15 PM				
Ambriz, Juan		Need to assemble new shelves for room #204							
Juan Ambriz									
98709	Main Building	Parking Lot			2/21/2013		13		\$0.00
Medium	Work In Progress	Student drop-			2/21/2013 8:36:49 AM				
Ambriz, Juan		As per Mr. Duran need to replace barricades in front of school and student drop-off							
Juan Ambriz									
91681	Main Building	Portables			8/22/2012		196		\$0.00
Medium	Work In Progress	BILINGUAL			8/22/2012 10:10:45 AM				
Ambriz, Juan		WE NEED MINI BLINDS IN BILINGUAL PORTABLE. ALSO IN MS. BARRAZA'S (VICE PRINCIPAL) OFFICE. PLEASE SEE RITA ON THIS. THANKS.							
Rita Mendez									
92408	Main Building	Portables			9/5/2012		182		\$0.00
Medium	Work In Progress	FIRST			9/5/2012 9:52:41 AM				
Ambriz, Juan		PLEASE SET UP HOOKS FOR COATS AND BACKPACKS IN BILINGUAL PORTABLE. THANKS.							
Rita Mendez									
94161	Main Building	Portables			10/15/2012		142		\$0.00
Medium	Work In Progress	PORTABLE A.			10/15/2012 2:43:09 PM				
Ambriz, Juan		WE NEED MINI BLINDS IN PORTABLE A (CASTANEDAS PORTABLE). THANKS.							
Rita Mendez									
97636	Main Building	Portables			1/24/2013		41		\$0.00
Medium	Work In Progress	FRONT AREA			1/24/2013 9:28:16 AM				
Munoz, Michael		PLEASE SET UP MORGAN BUILDING ACROSS THE ART PORTABLE. THIS BUILDING WILL BE USED AS STORAGE FOR ART SUPPLIES. ALSO, PLEASE INSTALL ELECTRICITY IN THE BLDG. THANK YOU.							
Rita Mendez									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
98665	Main Building	Library			2/20/2013		14		\$0.00
Medium	Work In Progress				2/20/2013 12:40:01 PM				
Ambriz, Juan	Need to replace lights in library								
<u>Juan Ambriz</u>									
99225					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:26:02 AM				
Munoz, Michael	Yearly - Santa Teresa ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97255					1/14/2013		51		\$0.00
Medium	Work In Progress				1/14/2013 12:59:56 PM				
Orozco, Daniel	AS PER INSPECTION PIPES ON DISHWASHER AND STAND NEEDS TO BE FIXED.SNP MANAGER MARINA R. 589.3439								
<u>Maritza Gonzalez</u>									
99290					3/4/2013		2		\$0.00
Medium	Work In Progress				3/4/2013 9:43:58 AM				
Orozco, Daniel	WALK IN FREEZER IS 17 DEGREES.								
<u>Maritza Gonzalez</u>									
98088					2/3/2013	2/9/2013	31		\$0.00
Medium	Work In Progress				2/3/2013 12:22:40 AM				
Ambriz, Juan	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99191					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:47 AM				
Ambriz, Juan	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93012		Portables			9/19/2012		168		\$0.00
Medium	Work In Progress	portable B			9/19/2012 2:33:09 PM				
Estrada, Jesus	Floor Tile in portable B is coming off needs to be replaced with tile or carpet. Tripping hazard for students and staff								
<u>Juan Ambriz</u>									
98329					2/10/2013	2/26/2013	24		\$0.00
Medium	Work In Progress				2/10/2013 12:20:35 AM				
Ambriz, Juan	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

3/6/2013 4:22:58 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
99187					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:45 AM					
Ambriz, Juan	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99189					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:46 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99190					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:46 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98086					2/3/2013	2/11/2013	31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:39 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98087					2/3/2013	2/11/2013	31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:39 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
94165		Athletic Field			10/15/2012		142		\$0.00
Medium	Work In Progress	BACK FIELD		10/15/2012 3:28:57 PM					
Ontiveros, Guadalupe	PLEASE FILL OUT ALL HOLES WITH DIRT IN THE BACK FIELDS. THANKS.								
<u>Rita Mendez</u>									
93845					10/7/2012	10/23/2012	150		\$0.00
Medium	Work In Progress			10/7/2012 12:16:24 AM					
Diaz, Pablo	Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97216					1/13/2013	1/29/2013	30		\$0.00
Medium	Work In Progress			1/13/2013 12:16:08 AM		2/12/2013			
Diaz, Pablo	Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.		inspections completed						
<u>Jesus Estrada</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
95724		Restroom (Boys)			11/20/2012		106		\$0.00
Medium	Work In Progress	CASA AZUL			11/20/2012 3:14:15 PM				
Marquez, Gerardo	OUR NEW HAND DRYER IS NOT WORKING PROPERLY. IT WAS TURNING ON AND STAYING ON BY ITSELF. IT WAS TURNED OFF COMPLETELY. PLEASE CHECK. THANKS.								
<u>Rita Mendez</u>									
96776					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:42 AM				
Villalobos, David	Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99166					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:36 AM				
Ambriz, Juan	Yearly - Santa Teresa ES A-10 HEAT PUMPS (ANNUAL) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96101					12/2/2012		94		\$0.00
Medium	Work In Progress				12/2/2012 12:23:08 AM				
Ambriz, Juan	Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99186					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:44 AM				
Ambriz, Juan	Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 36 Work Orders			Avg. Age of WO's	55		Total for Santa Teresa ES	0		\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

99109 3/3/2013 3/19/2013 3 \$0.00
 Medium Work In Progress 3/3/2013 12:25:09 AM

Villalobos, Margret Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer E-mailed Honeywell 3/5 to PM schedule details.

Margret Villalobos

99241 3/3/2013 4/3/2013 3 \$0.00
 Medium Work In Progress 3/3/2013 12:26:09 AM

Prospero, Manuel Yearly - Santa Teresa HS A-10 HP Yearly - Refer to PM schedule details.

Margret Villalobos

97485 1/18/2013 47 \$0.00
 Medium Work In Progress 1/18/2013 11:24:53 AM

Ambriz, Jose Room 210. Both fan coil units are not working on the heating mode. Need to replace the 3 way valves and the actuator valves.

Jaime Mijarez

93008 9/19/2012 168 \$0.00
 High Work In Progress 9/19/2012 1:23:35 PM

Mijarez, Jaime gnats are back, please check above ceiling tiles, ducting in ms. panthers classroom and surrounding classrooms for any signs of population. thank you

Michael Munoz

98284 2/6/2013 28 \$0.00
 Medium Work In Progress 2/6/2013 7:23:09 PM

Ambriz, Jose Library air-handler. Need to replace hot water side belimo valve. The stayed stuck in the open position.

Jaime Mijarez

90222 7/26/2012 223 \$0.00
 Medium Work In Progress 7/26/2012 7:54:01 AM

Ambriz, Jose Room 513 with Mrs. Hope. Classroom airconditioner is old and has corrosion on one of the corners of the water pan. A/C will need to be changed out. Check with Jaime or Art.

Jaime Mijarez

96169 12/3/2012 93 \$0.00
 Medium Work In Progress 12/3/2012 9:26:07 AM

Ambriz, Jose Mr. Ukestad wood shop teacher would like electrical wood machinery connected to saw dust exhaust collector. Joe will have to order and install the exhaust vent piping and other parts needed.

Jaime Mijarez

3/6/2013 4:22:58 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
98831					2/25/2013		9		\$0.00
Medium	Work In Progress				2/25/2013 3:37:23 PM				
Ambriz, Jose	Chiller has two failures low refrigerant temp, and high oil temp. Monitor water pressure and report to Honeywell.		Called Honeywell						
Jaime Mijarez									
98986					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress				2/28/2013 12:28:20 AM				
Marquez, Gerardo	Yearly - Santa Teresa HS C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									
99339		Mechanical			3/5/2013		1		\$0.00
Medium	Work In Progress				3/5/2013 7:46:43 AM				
Ambriz, Jose	Chiller System - Isolate hot and chilled water loops, eliminate cross connection after PRV and install water meters								
Alfredo Holguin									
98590					2/15/2013		19		\$0.00
Medium	Work In Progress				2/15/2013 4:03:43 PM				
Holguin, Alfredo	Chiller - Need to check water leak.		2/19/13 - Emailed to Honeywell						
Alfredo Holguin									
96774					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:41 AM				
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
98495					2/13/2013		21		\$0.00
Medium	Work In Progress				2/13/2013 4:00:53 PM				
Villalobos, David	Football concession stand. There was no water shutoff valve or drain line installed for selling area a/c. Had to find a way to close the water. Will need to install a shutoff valve and drain line.								
Jaime Mijarez									
97572					1/22/2013		43		\$0.00
Medium	Work In Progress				1/22/2013 3:52:53 PM				
Villalobos, David	Old gym a/c water supply. Locate water supply line to install a new shutoff valve. The existing valve is old and won't shutoff completely.								
Jaime Mijarez									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
99035					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 11:29:03 AM					
Villalobos, David	Boys urinal in the main hallway is still leaking water need to replace asap.								
<u>Jorge Perez</u>									
93984					10/10/2012		147		\$0.00
Medium	Work In Progress			10/10/2012 9:16:18 AM					
Villalobos, David	URINAL IN BOYS RRM. CONTINUES TO LEAK UNDERNEATH @ WALL. NEEDS TO BE CHECKED OUT BY PLUMBER. THANKS.								
<u>Gerardo Marquez</u>									
93789					10/3/2012		154		\$0.00
Medium	Work In Progress			10/3/2012 12:40:25 PM					
Villalobos, David	boys and girls restroom in the 300 hallway need new toilet seats as well as the girls restrooms in the main hallway.								
<u>Jorge Perez</u>									
93711					10/1/2012		156		\$0.00
Medium	Work In Progress			10/1/2012 12:03:32 PM					
Villalobos, David	Restrooms in the main hallway Boy and girls need to adjust or replace toilet seats as well as the restroom in the 300 hallway those need to be replaced.								
<u>Jorge Perez</u>									
92523					9/7/2012		180		\$0.00
Medium	Work In Progress			9/7/2012 11:28:42 AM					
Villalobos, David	Coach Dotson and Coach Bennet gym area showers have no water. Please check with Gerry.								
<u>Jaime Mijarez</u>									
98594					2/19/2013		15		\$0.00
Medium	Work In Progress			2/19/2013 8:03:14 AM					
Villalobos, David	3/4" backflow preventer to chiller makeup water is leaking needs to be replaced.								
<u>Jaime Mijarez</u>									
99168					3/3/2013	3/6/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:37 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
Margret Villalobos									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
92205					9/2/2012	9/5/2012	185		\$0.00
Medium	Work In Progress				9/2/2012 12:21:20 AM				
Marquez, Gerardo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98743					2/22/2013		12		\$0.00
Medium	Work In Progress				2/22/2013 8:28:41 AM				
Castillo, Carlos	need power in on The morgon/storage for custodial. Doesnt have any electrical box or anything. Power will be used to charge The electrical Gator.								
<u>Jorge Perez</u>									
98385					2/11/2013		23		\$0.00
Medium	Work In Progress				2/11/2013 6:28:00 PM				
Castillo, Carlos	New gym. One of the side basketball courts is not working please repair.								
<u>Jaime Mijarez</u>									
99398					3/6/2013		0		\$0.00
Medium	Work In Progress				3/6/2013 10:34:45 AM				
Castillo, Carlos	SECURITY GAURDS ARE REQUESTING THAT ALL BURNT OUT LIGHT BULBS BE CHANGED OUT @ FRONT PARKING LOT. THANKS.								
<u>Gerardo Marquez</u>									
98883		Athletic Field			2/26/2013		8		\$0.00
Medium	Work In Progress				2/26/2013 12:43:31 PM				
Mijarez, Jaime	Coach Bailon wanted some paint to freshen up his dugout. He would like to get 5 gallons of paint. Also the ceiling of the dugout is coming apart it needs to hammered down.								
<u>William Dickson</u>									
98346		Parking Lot			2/11/2013		23		\$0.00
Medium	Work In Progress				2/11/2013 11:07:12 AM				
Marquez, Gerardo	Need to get some white paint to mark off a no parking area.								
<u>William Dickson</u>									
92161		Parking Lot			8/31/2012		187		\$0.00
Medium	Work In Progress	MR.			8/31/2012 1:15:00 PM				
Marquez, Gerardo	PAINT THE 45, 35, 25 YARD LINE ON THE PARKING LOT. BAND NEEDS IT FOR AFTER SCHOOL REHEARSAL. ANYWAY IF IT COULD BE DONE ASAP.								
<u>Marylou Jimenez</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
93291		Football Field			9/26/2012		161		\$0.00
Medium	Work In Progress			9/26/2012 3:02:39 PM					
Castillo, Carlos	Need permanent electrical set-up or better and safer temporary for half-time music.								
<u>Carlos Castillo</u>									
96017		Athletic Field			11/30/2012		96		\$0.00
Medium	Work In Progress			11/30/2012 3:25:22 PM					
Castillo, Carlos	power will be needed for new scoreboards, baseball/softball please contact lynco for quote. thank you								
<u>Michael Munoz</u>									
99305					3/4/2013		2		\$0.00
Medium	Work In Progress			3/4/2013 12:34:42 PM					
Mijarez, Jaime	New Gym. Replace all ceiling light bulbs on fixtures. Mr. Dodson reported that it is to dark.								
<u>Jaime Mijarez</u>									
99212					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:56 AM					
Munoz, Michael	Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92273					9/2/2012		185		\$0.00
Medium	Work In Progress			9/2/2012 12:21:46 AM					
Munoz, Michael	Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97816					1/29/2013		36		\$0.00
Medium	Work In Progress			1/29/2013 10:09:05 AM					
Castillo, Carlos	1/28/13 NEED TO INSTALL AN ELECTRICAL OUTLET IN DUGS OUTS @ GIRLS SOFTBALL FIELD. CURRENTLY AN EXTENSION CORD FED THROUGH A HOLE MADE IN THE CINDERBLOCK IS BEING USED AND ISNT SAFE. THANKS.								
<u>Gerardo Marquez</u>									
93586					9/30/2012	10/8/2012	157		\$0.00
Medium	Work In Progress			9/30/2012 12:31:09 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

3/6/2013 4:22:58 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
93587					9/30/2012	10/8/2012	157		\$0.00
Medium	Work In Progress			9/30/2012 12:31:09 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93588					9/30/2012	10/31/2012	157		\$0.00
Medium	Work In Progress			9/30/2012 12:31:09 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92249					9/2/2012	9/10/2012	185		\$0.00
Medium	Work In Progress			9/2/2012 12:21:37 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90764					8/5/2012	8/13/2012	213		\$0.00
Medium	Work In Progress			8/5/2012 12:17:59 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90782					8/5/2012	9/5/2012	213		\$0.00
Medium	Work In Progress			8/5/2012 12:18:06 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90765					8/5/2012	8/13/2012	213		\$0.00
Medium	Work In Progress			8/5/2012 12:18:00 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91802					8/24/2012		194		\$0.00
Medium	Work In Progress			8/24/2012 7:27:50 AM					
Mijarez, Jaime	Water fountain located at the end of the 300 hallways is not working. And the water fountain in the back hall way that connects to the 300 is just stays running when power cord is connected.								
<u>Jorge Perez</u>									
90185					7/25/2012		224		\$0.00
Medium	Work In Progress			7/25/2012 1:25:35 PM					
Mijarez, Jaime	need to install vent motor to laser machine when it comes in. thank you								
<u>Michael Munoz</u>									

3/6/2013 4:22:58 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
93404		Choral			9/28/2012		159		\$0.00
Medium	Work In Progress			9/28/2012 2:31:45 PM					
Flores, Pete	We are wanting to remodel the band truck but we need help inpreparing it to be remodeled. the paint is popping off the truck and it may need engine work. Will or can you help us.								
<u>William Dickson</u>									
97814					1/29/2013		36		\$0.00
Medium	Work In Progress			1/29/2013 10:04:07 AM					
Marquez, Gerardo	NEED TO REPLACE LIGHT FIXTURE IN STORAGE RM. @ GIRLS SOFTBALLFIELD DUGOUT. THANKS.								
<u>Gerardo Marquez</u>									
99165					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:35 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92657					9/11/2012		176		\$0.00
Medium	Work In Progress			9/11/2012 8:11:10 AM					
Marquez, Gerardo	need to replace 2 ceiling tiles in the main lobby. as well in room 403. No ceiling tiles are in place due to the rain over the weekend.								
<u>Jorge Perez</u>									
92204					9/2/2012		185		\$0.00
Medium	Work In Progress			9/2/2012 12:21:19 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91609					8/21/2012		197		\$0.00
Medium	Work In Progress			8/21/2012 9:55:17 AM					
Marquez, Gerardo	NEED TO REPLACE WINDOW BLINDS IN 300 WING.								
<u>Gerardo Marquez</u>									
91619					8/21/2012		197		\$0.00
Medium	Work In Progress	MARY		8/21/2012 12:09:36 PM					
Marquez, Gerardo	NEED TO HAVE 2 SECURITY MIRRORS HUNG IN BACK OF LIBRARY.								
<u>Marylou Jimenez</u>									
92398					9/5/2012		182		\$0.00
Medium	Work In Progress			9/5/2012 7:39:21 AM					
Marquez, Gerardo	3 urinals in the outside concession stand are leaking water when flushed.								
<u>Jorge Perez</u>									
3/6/2013 4:22:58 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
93178		Classroom			9/24/2012		163		\$0.00
Medium	Work In Progress	VARIETY OF		9/24/2012 2:38:32 PM					
Marquez, Gerardo	SEVERAL ROOM NEED BRACKETS TO BE MOUNTED ON WALL FOR CLASSROOM FLAGS: MR. RINCON ROOM #801 2 BRACKETS MR. FELIX ROOM #505 2 BRACKETS MR. STOUT ROOM #509 2 BRACKETS RECEPTIONIST AREA NEEDS 2 BRACKETS MR. BAILEY ROOM #406 NEEDS 2 BRACKETS MR. CHAMPAGNE WELDING PORTABLE NEEDS 2 BRACKETS ROOM #301 NEEDS 2 BRACKETS								
<u>Marylou Jimenez</u>									
93068					9/20/2012		167		\$0.00
Medium	Work In Progress	BAND TRUCK		9/20/2012 11:19:31 AM					
Flores, Pete	BAND TRUCK NEEDS MAINTENANCE-CHECK FOR ANY MECHANICAL PROBLEMS ETC.								
<u>Marylou Jimenez</u>									
96808					1/6/2013	1/14/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:56 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98765					2/22/2013		11		\$0.00
Medium	Work In Progress			2/22/2013 2:34:01 PM		3/5/2013			
Perez, Jorge	please deliver Te 4x2 electric john deere gator UV-STHS-0906. jorge please read manual and view cd as well as your staff. once done please complete work order and turn in.thank you								
<u>Michael Munoz</u>									
99044		Athletic Field			2/28/2013		6		\$0.00
High	Work In Progress			2/28/2013 3:27:36 PM					
Garcia, Jose	compressor needs to be replaced.								
<u>Guadalupe Ontiveros</u>									
99066		Portables			2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 4:20:48 PM					
Lara, Ralph	We have some cabinets in the Nurse's office that need to be locked because it carries medication. Need to Rafa here to secure the medicine cabinets.								
<u>William Dickson</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
96311					12/6/2012		90		\$0.00
Medium	Work In Progress				12/6/2012 8:46:00 AM				
Mijarez, Jaime	Need to install power vent to Laser Machine.								
<u>Michael Munoz</u>									
97486					1/18/2013		47		\$0.00
Medium	Work In Progress				1/18/2013 11:29:17 AM				
Mijarez, Jaime	Weight Room. Heating unit fan motor gave out, please order fan motor with housing if possible. I will take care of installing the new one.								
<u>Jaime Mijarez</u>									
98084					2/3/2013	3/6/2013	31		\$0.00
Medium	Work In Progress				2/3/2013 12:22:38 AM				
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98082					2/3/2013	2/11/2013	31		\$0.00
Medium	Work In Progress				2/3/2013 12:22:37 AM				
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98083					2/3/2013	2/11/2013	31		\$0.00
Medium	Work In Progress				2/3/2013 12:22:38 AM				
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98283					2/6/2013		28		\$0.00
Medium	Work In Progress				2/6/2013 7:15:43 PM				
Mijarez, Jaime	200 wing photo cell needs to be replaced. lights are staying on too long.								
<u>Jaime Mijarez</u>									
99182					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:43 AM				
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99183					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:43 AM				
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
99184					3/3/2013	4/3/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:44 AM				
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99308					3/4/2013		2		\$0.00
Medium	Work In Progress				3/4/2013 1:25:40 PM				
Orozco, Daniel	NO WATER COMING OUT ON SINK IN RESTROOM (KITCHEN AREA) SNP MANAGER OLGA B. 589.5332								
<u>Maritza Gonzalez</u>									
96225					12/4/2012		92		\$0.00
Medium	Work In Progress				12/4/2012 9:24:33 AM				
Marquez, Gerardo	NEED TO REPLACE BURNT OUT LIGHT BULBS IN CUSTODIAL CLOSET 300 WING.								
<u>Gerardo Marquez</u>									
95746					11/21/2012		105		\$0.00
Medium	Work In Progress				11/21/2012 9:09:49 PM				
Estrada, Jesus	The carpet in the weight room needs repairing. It is coming and posing a unsafe setting.								
<u>William Dickson</u>									
97866					1/30/2013		35		\$0.00
Medium	Work In Progress				1/30/2013 1:06:53 PM				
Munoz, Michael	WHILE DOING FIRE SPRINKLER SYSTEM INSP. WITH DIMAR REPS. FOUND THAT ENTIRE FIRE SPRINKLER SYSTEM TO VOCATIONAL BLDG. HAS NOT BEEN OPERATIONAL SINCE 2011, DUE TO BUSTED WATER LINES. NEEDS TO BE CHECKED OUT. THANKS. CHECKED OUT. THANKS.								
<u>Gerardo Marquez</u>									
96790					1/6/2013	1/27/2013	59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:48 AM				
Orozco, Daniel	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99167					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:36 AM				
Marquez, Gerardo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
93667					9/30/2012	10/6/2012	157		\$0.00
Medium	Work In Progress			9/30/2012 12:31:44 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97918					1/31/2013		34		\$0.00
Medium	Work In Progress			1/31/2013 8:07:27 AM					
Marquez, Gerardo	NEED TO REPLACE 13 BROKEN/MISSING PLASTIC COVERS @ FIRE EXTINGUISHER STATIONS. ALSO NEED TO REPLACE TAGS. 36 TOTAL. THANKS								
<u>Gerardo Marquez</u>									
94657		Athletic Field			10/26/2012		131		\$0.00
High	Work In Progress			10/26/2012 2:57:54 PM					
Garcia, Jose	JD Tractor is leaking from front axle.								
<u>Guadalupe Ontiveros</u>									
94897					11/1/2012		125		\$0.00
Medium	Work In Progress			11/1/2012 11:54:26 AM					
Munoz, Michael	GATES & FENCE @ VOCATIONAL BLDG. ARE VERY RAGGED LOOOKING. POSTS HAVE BEEN BENT. MESH HAS BEEN RUN INTO IN VARIOUS PLACES. PROBABLY NEEDS TO BE REPLACED.								
<u>Gerardo Marquez</u>									
98502					2/13/2013		21		\$0.00
Medium	Work In Progress			2/13/2013 10:13:02 PM					
Munoz, Michael	Annex electrical and boiler room. 11'6"x 5'3" was never filled with concrete when new construction was done. Section of dirt is causing a problem to these two rooms and culinary entrance.				2/14 - route to R. Gallegos asp Mike				
<u>Jaime Mijarez</u>									
98501					2/13/2013		21		\$0.00
Medium	Work In Progress			2/13/2013 9:47:13 PM					
Mijarez, Jaime	Outside walkway between nurse portable and Morgan storages. Reported by Mr.Dickson a 28'x 4' section of concrete has cracks and a piece missing. Mr.Dickson wants it repaired before some one gets hurt.								
<u>Jaime Mijarez</u>									
94656		Athletic Field			10/26/2012		131		\$0.00
Medium	Work In Progress			10/26/2012 2:55:46 PM					
Ontiveros, Guadalupe	JD 997 Mower will not start.								
<u>Guadalupe Ontiveros</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
99072					3/1/2013		5		\$0.00
Medium	Work In Progress			3/1/2013 9:45:37 AM					
Orozco, Daniel	the drainer in the old favorite stand is broken and need some welding work. SNP Manager Olga B. 589.5332.								
Maritza Gonzalez									
93073					9/20/2012		167		\$0.00
Medium	Work In Progress			9/20/2012 12:56:13 PM					
Orozco, Daniel	SANIZER ON DISHWASHER NOT WORKING, AS PER ECO LAB IT HAS TO DO WITH THE WATER PRESSURE. SNP MANAGER OLGA B. 589.5332								
Maritza Gonzalez									
97001					1/8/2013		57		\$0.00
Medium	Work In Progress			1/8/2013 9:18:30 AM					
Gonzalez, Salvador	Railling to exterior stairway going from athletic dressing rooms to concession stand was damaged. We had to remove it, might need to fabricate a new one or repair if possible.								
Jaime Mijarez									
92782					9/13/2012		174		\$0.00
Medium	Work In Progress			9/13/2012 8:41:58 AM					
Gonzalez, Salvador	We need to have a chain welded or hooks welded to extend a chain that will keep people from driving onto side walk along tree line. Rafa Lara will be providing the chain and locks. Mr. Dickson would like to have this done before the game on Friday. Please check with me.								
Jaime Mijarez									
96027		Athletic Field			11/30/2012		96		\$0.00
Medium	Work In Progress			11/30/2012 3:41:07 PM					
Gonzalez, Salvador	pleaase order material for new scoreboards. baseball / softball. thank you								
Michael Munoz									
99235					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:07 AM					
Munoz, Michael	Yearly - Santa Teresa HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
98875		Athletic Field			2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 10:39:16 AM					
Marquez, Gerardo	Last year the concession stand door was broken into and coach would like to replace it with a metal door for safety. Need to be installed soon. Thanks!				2/28 - Route to Gerry asp Mike				
William Dickson									
3/6/2013 4:22:58 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
94151					10/15/2012		142		\$0.00
Medium	Work In Progress				10/15/2012 11:32:27				
Lara, Ralph	The electeic stops that hold the doors open in the gym area needs extensive repair before some gets hurt. The holders are falling off the wall.								
William Dickson									
98746		Athletic Field			2/22/2013		12		\$0.00
Medium	Work In Progress				2/22/2013 9:03:42 AM				
Mijarez, Jaime	The external restrooms have flipped over and the liquid has spilled out because of the high winds the other day. Can we get someone out here to take care of them.								
William Dickson									
94523					10/24/2012		133		\$0.00
Medium	Work In Progress				10/24/2012 9:52:53 AM				
Carbajal, Jimmy	vacuum cleaner #4088 doesn't turn on.				ASP JIMMY, SCHEDULED TO PICK AND AND SERVICE ON 9/29/12				
Jorge Perez									
99354					3/5/2013		1		\$0.00
Medium	Work In Progress				3/5/2013 10:55:01 AM				
Carbajal, Jimmy	Burnisher #0052 shuts of after the first 15 min and then every 1 min or so after that. Tried the reset button and it works but just for a very small period then it shuts up								
Jorge Perez									
99358					3/5/2013		1		\$0.00
Medium	Work In Progress				3/5/2013 11:16:37 AM				
Carbajal, Jimmy	Need to order a vacuum brush ansd belt for Vacuum #0045								
Jorge Perez									
97488	Main Building	Office			1/18/2013		47		\$0.00
Medium	Work In Progress				1/18/2013 11:39:50 AM				
Marquez, Gerardo	Need to get the Social Workers office painted								
William Dickson									
97550	Main Building	Hallway/Corridor			1/22/2013		43		\$0.00
Medium	Work In Progress				1/22/2013 2:34:13 PM				
Lara, Ralph	The double doors leading out of the 600 hallway need to be repaced. they do not lock well and with a pull can be opened.								
William Dickson									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

93402	Main Building	Classroom			9/28/2012		159		\$0.00
Medium	Work In Progress				9/28/2012 2:23:27 PM				

Marquez, Gerardo
 There was an announcement made by Mr. Gallegos in reference to some tables and chairs. We would like to get a few of them. We would like to get 4 rectangular and 4 round tables.

William Dickson

98884	Main Building	Classroom			2/26/2013		8		\$0.00
Medium	Work In Progress				2/26/2013 12:48:46 PM				

Miranda, Danny
 Mr. Lawrence was contacted by Joel B. Santamaria from Vado Elementary that he had some material for art this he could have. Will you be able to send a truck to vado and have the material transported to Santa Teresa High School.
 Thanks!

William Dickson

99348	Vocational				3/5/2013		1		\$0.00
Medium	Work In Progress				3/5/2013 9:49:02 AM				

Mijarez, Jaime
 Need to remove broken desks, chairs, Tables from the vocational Building.

Jorge Perez

94756	Vocational	Football Field			10/30/2012		127		\$0.00
Medium	Work In Progress				10/30/2012 8:52:33 AM				

Ontiveros, Guadalupe
 We need a new fence for the softball field to be set up before the season starts.

William Dickson

95225	Library	Classroom			11/6/2012		120		\$0.00
Medium	Work In Progress				11/6/2012 9:54:33 AM				

Estrada, Jesus
 The library has carpet that has been there for about 12 years. It has stains, gum, and other ugly looking marks on it. Even after shampooing the carpet it doesn't change the look. We need to exchange that carpet for a new one since we have dignitaries come in quite often.

William Dickson

95226	Library	Hallway/Corridor			11/6/2012		120		\$0.00
Medium	Work In Progress				11/6/2012 10:12:45 AM				

Lara, Ralph
 There is a open space in the Library that needs a drop down locking metal screen to keep equipment safe. There are two sections in the Library that are about 11 feet long. This was suppose to enclosed years ago but the job was never completed.

William Dickson

3/6/2013 4:22:59 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
97544	Library	Library			1/22/2013		43		\$0.00
Medium	Work In Progress				1/22/2013 1:20:44 PM				
Lara, Ralph	Replace the library door so it can be locked everyday. Does not lock and it has been worked on several times.								
<u>William Dickson</u>									
95227	Library				11/6/2012		120		\$0.00
Medium	Work In Progress				11/6/2012 10:17:04 AM				
Lara, Ralph	The front door of the Library can not be locked properly. It may need to be replaced. They have tried to fix it on several occasions but no luck. Can we please replace so the Library will be secure.								
<u>William Dickson</u>									
97545	Main Building	Athletic Field			1/22/2013		43		\$0.00
Medium	Work In Progress				1/22/2013 1:30:09 PM				
Lara, Ralph	Need to replace the outside door leading to ther football field. It does not lock.								
<u>William Dickson</u>									
98549	Main Building				2/14/2013		20		\$0.00
Medium	Work In Progress				2/14/2013 5:26:36 PM				
Mijarez, Jaime	The fan unit on the roof sounds like it is about to explode. Can we have someone look at it Thanks!								
<u>William Dickson</u>									
94785	Locker Room				10/30/2012		127		\$0.00
Medium	Work In Progress				10/30/2012 3:14:53 PM				
Marquez, Gerardo	Need paint for the dugouts for both the boys and the girls. The players will paint both dugouts.								
<u>William Dickson</u>									
97972	Cafeteria (2005)	Cafeteria			2/1/2013		33		\$0.00
Medium	Work In Progress				2/1/2013 8:13:50 AM				
Castillo, Carlos	The electrical plugs in the kitchen does not have any power. Need fixed ASAP. Thanks!								
<u>William Dickson</u>									
99309	GYM (2009)				3/4/2013		2		\$0.00
Medium	Work In Progress				3/4/2013 1:37:33 PM				
Castillo, Carlos	plenty of lights are not working in gym. state basketball game will be this weekend. please replace. thank you								
<u>Michael Munoz</u>									
Count: 106 Work Orders		Avg. Age of WO's 81			Total for Santa Teresa HS			0	\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
98104					2/3/2013	2/9/2013	31		\$0.00
Medium	Work In Progress			2/3/2013 12:22:46 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96126					12/2/2012	12/8/2012	94		\$0.00
Medium	Work In Progress			12/2/2012 12:23:18 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99230					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:04 AM					
Munoz, Michael	Yearly - Santa Teresa MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99242					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:10 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90174					7/25/2012		224		\$0.00
Medium	Work In Progress			7/25/2012 11:23:39 AM					
Prospero, Manuel	WE NEED SOME GASOLINE POR CUSTODIAN TRUAK AN POLARIS.								
<u>Manuel Prospero</u>									
97445	North Building	Classroom			1/17/2013		48		\$0.00
Medium	Work In Progress	BAND ROOM		1/17/2013 8:41:54 AM					
Gonzalez, Salvador	REQUESTING ROD IRON GATE OUTSIDE BAND ROOM. SAFETY ISSUE.								
<u>Laura Parra</u>									
92934	North Building	Gym			9/18/2012		169		\$0.00
Medium	Work In Progress			9/18/2012 1:07:55 PM					
Lara, Ralph	As per Mr.Montano Principal the door to the concession stand needs to be replace with a ventilated door it gets super hot inside the concession stand and trips the ice makerand fridge Mr.Lara is aware of this work order thanks..								
<u>Ismael Rodriguez</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
90913	North Building	Restroom (Girls)			8/7/2012		211		\$0.00
Medium	Work In Progress			8/7/2012 8:41:12 AM					
Castillo, Carlos	Need a electrical outlet in private restroom in north office see Mr.Rodriguez.								
<u>Ismael Rodriguez</u>									
90641	North Building	Office			8/3/2012		215		\$0.00
Medium	Work In Progress	REGISTAR		8/3/2012 8:33:52 AM					
Castillo, Carlos	NEED ELECTRICAL OUTLET IN RESTROOM-- AS PER MS LOVELACE'S REQUEST								
<u>Laura Parra</u>									
93976	North Building	Hallway/Corridor			10/10/2012		147		\$0.00
Medium	Work In Progress			10/10/2012 7:29:44 AM					
Castillo, Carlos	Replace electrical outlet where the water fountains connect in the north upper level wires expose thanks..								
<u>Ismael Rodriguez</u>									
91364	North Building	Office			8/15/2012		203		\$0.00
Medium	Work In Progress	RECEPTIONIST		8/15/2012 11:34:06 AM					
Prospero, Manuel	1. REMOVE BLIND ATTACHEMENTS 2. PAINT WINDOW FRAMES BLACK 3. PAINT OFFICE								
<u>Laura Parra</u>									
90600	North Building	Cafeteria			8/2/2012		216		\$0.00
Medium	Work In Progress			8/2/2012 1:41:31 PM					
Prospero, Manuel	KITCHEN A/C UNID NEED TO CHANGED CIRCULATION PUMP. IS NOT WORKING.								
<u>Manuel Prospero</u>									
98338	North Building	Hallway/Corridor			2/11/2013		23		\$0.00
Medium	Work In Progress			2/11/2013 8:19:42 AM					
Ambriz, Jose	Replace by-level water fountains in upper and lower level north building hallway.								
<u>Ismael Rodriguez</u>									
98749	North Building	Classroom			2/22/2013		12		\$0.00
Medium	Work In Progress	ROOM 3		2/22/2013 9:55:23 AM					
Prospero, Manuel	RESTROOM CLOGGED								
<u>Laura Parra</u>									
95495	North Building	Gym			11/14/2012		112		\$0.00
Medium	Work In Progress			11/14/2012 7:54:10 AM					
Villalobos, David	5 Gallons of cherry mat for drains in the gym and 5 for north and south building thanks..								
<u>Ismael Rodriguez</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
98441	North Building	Restroom (Boys)			2/13/2013		21		\$0.00
Medium	Work In Progress			2/13/2013 9:07:02 AM					
Villalobos, David	Five gallons of cherry mat for drains.								
<u>Ismael Rodriguez</u>									
98597	North Building	Hallway/Corridor			2/19/2013		15		\$0.00
Medium	Work In Progress			2/19/2013 8:53:06 AM					
Prospero, Manuel	Hang picture frames in north lobby.								
<u>Ismael Rodriguez</u>									
98710	North Building	Classroom			2/21/2013		13		\$0.00
Medium	Work In Progress	ROOM 2-A		2/21/2013 9:29:54 AM					
Prospero, Manuel	REPLACE AIR FILTER IN HVAC AIR HANDLING UNIT								
<u>Laura Parra</u>									
97153	North Building	Parking Lot			1/11/2013		54		\$0.00
Medium	Work In Progress			1/11/2013 7:42:26 AM					
Ontiveros, Guadalupe	Remove dirt with tracter dirt build up by portable ramps and also in North main entrance patio.								
<u>Ismael Rodriguez</u>									
98813	North Building	Custodial			2/25/2013		9		\$0.00
Medium	Work In Progress			2/25/2013 11:21:59 AM					
Ontiveros, Guadalupe	Need to remove the sand from north and south entrances custodians will help can you provide the Jhon Deer Gater.								
<u>Ismael Rodriguez</u>									
99404	North Building	Portables			3/6/2013		0		\$0.00
Medium	Work In Progress			3/6/2013 12:49:28 PM					
Lara, Ralph	Rafa clean the cores to portable 2 teacher having trouble opening it.								
<u>Ismael Rodriguez</u>									
99367	North Building	Office			3/5/2013		1		\$0.00
Medium	Work In Progress	NURSE'S		3/5/2013 3:21:35 PM					
Lara, Ralph	BACK DOOR LOCKS DIFFICULT TO LOCK AND OPEN								
<u>Laura Parra</u>									
91685	South Building	Restroom (Boys)			8/22/2012		196		\$0.00
Medium	Work In Progress			8/22/2012 10:58:29 AM					
Prospero, Manuel	Broken water valve to flushvalve needs to be replaced								
Manuel Prospero									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
99287	South Building	Restroom (Boys)			3/4/2013		2		\$0.00
Medium	Work In Progress				3/4/2013 8:57:28 AM				
Prospero, Manuel	Theres a sink thats leaking water in boys rest room south upper level.								
<u>Ismael Rodriguez</u>									
97984	South Building	Library			2/1/2013		33		\$0.00
Medium	Work In Progress				2/1/2013 10:06:33 AM				
Castillo, Carlos	NEED TO REPLACE 4 LIGHTS ON LIBRARY. 250 W. METAL HALIDE.								
<u>Manuel Prospero</u>									
95704	South Building	Stairway			11/20/2012		106		\$0.00
Medium	Work In Progress				11/20/2012 12:34:22				
Castillo, Carlos	The stairway in the South Building going up to the second floor the light is not working as per Manny theres a electrical problem we need the light for safety reasons.								
<u>Ismael Rodriguez</u>									
98950	Gym (1997)	Dressing Room			2/27/2013		7		\$0.00
Medium	Work In Progress	GIRLS			2/27/2013 3:23:44 PM				
Castillo, Carlos	LIGHTS BURNED OUDT IN THE GIRLS LOCKER ROOM CAGE AREA								
<u>Laura Parra</u>									
97716	Gym (1997)	Gym			1/25/2013		40		\$0.00
Medium	Work In Progress	CONCESSION			1/25/2013 3:21:30 PM				
Castillo, Carlos	CARLOS CASTILLO-- NEW ELECTRICAL LINE FOR ICE MAKER. AS PER MR. JACOBO								
<u>Laura Parra</u>									
97526	Gym (1997)				1/22/2013		43		\$0.00
Medium	Work In Progress				1/22/2013 7:56:32 AM				
Prospero, Manuel	please replace missing hvac louvers and clean the remaining ones. will need to replace the small rectangular and clean the larger 24 x 24. thank you								
<u>Michael Munoz</u>									
97437	Gym (1997)				1/17/2013		48		\$0.00
High	Work In Progress				1/17/2013 6:40:48 AM				
Soria, Mike	please remove sand along curb in the parking lot and remove weeds and sand that are around light poles in the the parking lot as well, also please remove sand on side walk that leads from the parking lot to the gym and clean debre ie soda cans, weeds, rocks etc along this areas well and cleand sidewalk to entrance to gym and surrounding areas. thank you								
<u>Michael Munoz</u>									
3/6/2013 4:22:59 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
98947	Gym (1997)	Athletic Field			2/27/2013		7		\$0.00
Medium	Work In Progress				2/27/2013 2:27:05 PM				
Ontiveros, Guadalupe	CENTER CIRCLE FOR TRACK AND FIELD PRACTICE								
<u>Laura Parra</u>									
93323	Gym (1997)	Gym			9/27/2012		160		\$0.00
Medium	Work In Progress				9/27/2012 9:15:33 AM				
Lara, Ralph	Rafa the exit door behind the boys dressing room gym area is not handicapp accessabel for the student thats riding a wheel chair, he had a hard time opening the door is there any way you can install a push button door as per administration.								
<u>Ismael Rodriguez</u>									
99239					3/3/2013	4/3/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:26:08 AM				
Prospero, Manuel	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99244					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:26:11 AM				
Prospero, Manuel	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91549		Classroom			8/20/2012		198		\$0.00
Medium	Work In Progress	ROOM 1			8/20/2012 12:21:59 PM				
Prospero, Manuel	1. PAPER TOWEL DISPENSER ABOVE SINKS 2. PLACE TILES ON BARE CONCRETE FLOOR.								
<u>Laura Parra</u>									
96852					1/6/2013	1/14/2013	59		\$0.00
Medium	Work In Progress				1/6/2013 12:24:18 AM				
Prospero, Manuel	Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93542					9/30/2012	10/8/2012	157		\$0.00
Medium	Work In Progress				9/30/2012 12:30:48 AM				
Prospero, Manuel	Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96128					12/2/2012	12/10/2012	94		\$0.00
Medium	Work In Progress				12/2/2012 12:23:19 AM				
Prospero, Manuel	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
3/6/2013 4:22:59 PM									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
96127					12/2/2012	12/10/2012	94		\$0.00
Medium	Work In Progress			12/2/2012 12:23:18 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95127					11/4/2012	11/12/2012	122		\$0.00
Medium	Work In Progress			11/4/2012 12:19:53 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99243					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:10 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99240					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:09 AM					
Prospero, Manuel	Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98143					2/4/2013		30		\$0.00
Medium	Work In Progress			2/4/2013 8:18:34 AM					
Castillo, Carlos	Need to replace light fixture lenses -8ea.								
<u>Carlos Castillo</u>									
96775					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:42 AM					
Villalobos, David	Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90766					8/5/2012	9/5/2012	213		\$0.00
Medium	Work In Progress			8/5/2012 12:18:00 AM					
Prospero, Manuel	Yearly - Santa Teresa MS C-11(Evap.Down)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99185					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:44 AM					
Mijarez, Jaime	Yearly - Santa Teresa MS A10 (Heat Pump)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
96672					12/31/2012		65		\$0.00
Medium	Work In Progress				12/31/2012 12:27:05				
Mijarez, Jaime	Yearly - Santa Teresa MS H6(Roof Furnace)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
98194					2/5/2013		29		\$0.00
Medium	Work In Progress				2/5/2013 12:08:49 PM				
Ambriz, Jose	Thermostat broken								
Laura Parra									
Count: 48 Work Orders		Avg. Age of WO's 75		Total for Santa Teresa MS			0	\$0.00	

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
97039					1/8/2013		57		\$0.00
Medium	Work In Progress			1/8/2013 3:40:58 PM					
Ambriz, Jose	need new a/c unit 43 areo cool contractors replaced roof and unit was no good								
Carlos Hernandez									
96589		Parking Lot			12/13/2012		83		\$0.00
Medium	Work In Progress			12/13/2012 1:31:50 PM					
Lara, Ralph	Need gate key for Sunland Park Elementary. There will be work there over the break. Need to check the key out to Justin Armendariz with C. D. General (575-635-7988). For more information contact Ralph Gallegos at 882-6921. Need key by December 14, 2012. Thanks.								
Rafael Gallegos									
99155					3/3/2013	3/19/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:31 AM					
Moncayo, Fernando	Monthly - Sunland Park ES A-1 Wall Ref Semiannual - Refer to PM schedule details.								
Margret Villalobos									
99156					3/3/2013	3/24/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:31 AM					
Moncayo, Fernando	Monthly - Sunland Park ES C-12 Chem. Feeder (SA) - Refer to PM schedule details.								
Margret Villalobos									
99153					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:30 AM					
Hernandez, Carlos	Yearly - Sunland Park ES A-10 HP Rooftop Yearly - Refer to PM schedule details.								
Margret Villalobos									
98991					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:22 AM					
Hernandez, Carlos	Monthly - Sunland Park ES A-16 Fan Exh Semiannual - Refer to PM schedule details.								
Margret Villalobos									
98989					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:21 AM					
Hernandez, Carlos	Yearly - Sunland Park ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
96773					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:41 AM					
Villalobos, David	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
96590					12/13/2012		83		\$0.00
Medium	Work In Progress	CLASSROOM		12/13/2012 1:40:56 PM					
Villalobos, David	AS PER MS. HERRERA - TOILET LEAKING FROM FLUSHING KNOW AND EVERYTIME ONE FLUSHES EVERYTHING COMES BACK AND IT OVERFLOWS. PLEASE CHECK. THANK YOU.								
David Avila									
98751					2/22/2013		12		\$0.00
Medium	Work In Progress			2/22/2013 10:52:03 AM					
Castillo, Carlos	need outlet in iep room for projector screen								
Carlos Hernandez									
94495					10/23/2012		134		\$0.00
Medium	Work In Progress			10/23/2012 3:40:31 PM					
Flores, Pete	need new tires for 970 john deere tractor								
Carlos Hernandez									
98474					2/13/2013		21		\$0.00
Medium	Work In Progress			2/13/2013 3:09:52 PM					
Ontiveros, Guadalupe	need fertlizer spredder								
Carlos Hernandez									
99406					3/6/2013		0		\$0.00
Medium	Work In Progress	MAIN OFFICE -		3/6/2013 1:17:11 PM					
Lara, Ralph	MR. VAN NOSDALE IS REQUESTING THAT 12 KEYS BE MADE OF CYLINDER # TT1. THESE KEYS ARE NEEDED FOR STAFF MEMBERS THAT ARE LOCATED IN PORTABLES. IF YOU HAVE ANY QUESTIONS PLEASE FEEL FREE TO ASK DAVID AVILA. THANK YOU.								
David Avila									
99078					3/1/2013		5		\$0.00
Medium	Work In Progress	CLASSROOM		3/1/2013 11:34:19 AM					
Lara, Ralph	AS PER MS. GARDEA- HER KEY DOES NOT OPEN HER CLOSET DOOR. SOMETHING SEEMS TO BE STUCK IN KNOB. PLEASE CHECK. THANK YOU.								
David Avila									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
98255					2/6/2013		28		\$0.00
Medium	Work In Progress	MS.		2/6/2013 10:40:51 AM					
Hernandez, Carlos	CARLOS, CAN YOU PLEASE MOVE THE TELEVISION THAT IS IN MS. GUTIERREZ'S ROOM (20A) AND PLEASE RELOCATE IT TO MS. KENNONS ROOM (11). IF YOU HAVE ANY QUESTIONS, PLEASE LET ME KNOW. THANK YOU, DAVID AVILA								
<u>David Avila</u>									
97892					1/30/2013		35		\$0.00
Medium	Work In Progress			1/30/2013 3:34:23 PM					
Hernandez, Carlos	need new dewalt hammer drill and battiers also need new acceline touch								
<u>Carlos Hernandez</u>									
99075					3/1/2013		5		\$0.00
Medium	Work In Progress	CLASSROOM		3/1/2013 11:29:56 AM					
Hernandez, Carlos	AS PER MS. GOMEZ - SHE NEEDS LIGHT BULBS REPLACED. PLEASE SEE HER FOR MORE INSTURCTIONS. THANK YOU.								
<u>David Avila</u>									
99076					3/1/2013		5		\$0.00
Medium	Work In Progress	CLASSROOM		3/1/2013 11:30:34 AM					
Hernandez, Carlos	AS PER MRS. PHILLIPS - SHE NEEDS LIGHT BULBS REPLACED. PLEASE SEE HER FOR MORE INSTURCTIONS. THANK YOU.								
<u>David Avila</u>									
99077					3/1/2013		5		\$0.00
Medium	Work In Progress	CLASSROOM		3/1/2013 11:32:24 AM					
Hernandez, Carlos	AS PER MS. BRIONES - SHE NEEDS LIGHT BULBS REPLACED. PLEASE SEE HER FOR MORE INSTURCTIONS. THANK YOU.								
<u>David Avila</u>									
98819					2/25/2013		9		\$0.00
Medium	Work In Progress	CLASSROOM#1		2/25/2013 1:46:57 PM					
Hernandez, Carlos	AS PER MS. RUBIO - PLEASE FIX A LEG FROM ONE OF THE BROWN ROUND TABLES IN THE MY CLASSROOM. THANK YOU.								
<u>David Avila</u>									
99134					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:21 AM					
Hernandez, Carlos	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

3/6/2013 4:22:59 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
99135					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:22 AM				
Hernandez, Carlos	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99133					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:21 AM				
Hernandez, Carlos	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99226					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:26:02 AM				
Munoz, Michael	Yearly - Sunland Park ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98171					2/4/2013		30		\$0.00
Medium	Work In Progress				2/4/2013 4:17:09 PM				
Orozco, Daniel	PLEASE CHECK STAND PIECE OF METAL IS MISSING.SNP MANAGER IGNACIA C. 589.2545								
<u>Maritza Gonzalez</u>									
98172					2/4/2013		30		\$0.00
Medium	Work In Progress				2/4/2013 4:17:37 PM				
Orozco, Daniel	OVENS NEED TO BE CHECKED, NOT HOLDING TEMPERATURE.SNP MANAGER IGNACIA C. 589.2545								
<u>Maritza Gonzalez</u>									
96426					12/10/2012		86		\$0.00
Medium	Work In Progress				12/10/2012 10:09:35				
Orozco, Daniel	VEGETABLE SINK IS LEAKING. SNP MANAGER IGNACIA C. 589.2545								
<u>Maritza Gonzalez</u>									
99364	Main Building	Office			3/5/2013		1		\$0.00
Medium	Work In Progress				3/5/2013 2:04:17 PM				
Briones, Enrique	Please pick up Math adoption Samples boxes								
<u>Larry Martinez</u>									
Count: 28 Work Orders		Avg. Age of WO's 26		Total for Sunland Park ES			0	\$0.00	

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
98101					2/3/2013		31		\$0.00
Medium	Work In Progress				2/3/2013 12:22:45 AM				
Apodaca, Mario	Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
99210					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:55 AM				
Apodaca, Mario	Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
99227					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:26:03 AM				
Munoz, Michael	Yearly - Sunrise ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
99192					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:47 AM				
Vargas, Juan	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
98187					2/5/2013		29		\$0.00
Medium	Work In Progress				2/5/2013 10:00:57 AM				
Vargas, Juan	trees in the bus turn a round need to be trimmed and area needs to be raked. also please trim and rake other areas as needed. thank you								
Michael Munoz									
95584					11/15/2012		111		\$0.00
Scheduled	Work In Progress				11/15/2012 10:53:04				
Vargas, Juan	Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You								
99193					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:48 AM				
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
99194					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:48 AM					
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99195					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:48 AM					
Vargas, Juan	Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93999					10/10/2012		147		\$0.00
Medium	Work In Progress			10/10/2012 2:36:23 PM					
Vargas, Juan	need 10 gls oil paint to painting entry and portables doors								
<u>Juan Vargas</u>									
97496					1/18/2013		47		\$0.00
Medium	Work In Progress			1/18/2013 3:11:50 PM					
Sotelo, Enrique	need fix lights out side round the school								
<u>Juan Vargas</u>									
98995					2/28/2013		6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:24 AM					
Vargas, Juan	Monthly - Sunrise ES A-1 Semiannual MCS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98996					2/28/2013	3/31/2013	6		\$0.00
Medium	Work In Progress			2/28/2013 12:28:25 AM					
Vargas, Juan	Yearly - Sunrise ES C-11 (Evap.Cooler)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99200					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:51 AM					
Vargas, Juan	Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99198					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:50 AM					
Vargas, Juan	Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Sunrise ES							
99199					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:50 AM				
Vargas, Juan	Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details.								
Margret Villalobos									
99196					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:49 AM				
Vargas, Juan	Yearly - Sunrise ES A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
99197					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:49 AM				
Vargas, Juan	Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM schedule details.								
Margret Villalobos									
Count: 18 Work Orders		Avg. Age of WO's 23			Total for Sunrise ES			0	\$0.00

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
99144					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:26 AM					
Miranda, Danny	Yearly - Vado ES A-10 Heat Pump Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99145					3/3/2013	4/3/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:26 AM					
Miranda, Danny	Yearly - Vado ES R-3 Ref. Unit Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93491					9/30/2012	10/21/2012	157		\$0.00
Medium	Work In Progress			9/30/2012 12:30:26 AM					
Orozco, Daniel	Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98445					2/13/2013		21		\$0.00
Medium	Work In Progress			2/13/2013 9:51:46 AM					
Solis, Lorenzo	NEED TO REPAIR UNIT IN ROOM 105 UNIT NEEDS TO BE RESET EVERY MORNING AND DURING THE DAY								
<u>Danny Miranda</u>									
97079		Office			1/9/2013		56		\$0.00
Medium	Work In Progress			1/9/2013 4:02:57 PM					
Lozoya, Manny	need doors from main lobby to corridors and cafeteria to have locks installed that can be operated from office area. Check with Alfredo Holguin if you have questions								
<u>Alfredo Holguin</u>									
97761					1/28/2013		37		\$0.00
Medium	Work In Progress			1/28/2013 10:37:09 AM					
Lozoya, Manny	NEED A KEY MADE FOR ROOM 205 AND 207								
<u>Debra Facio</u>									
97344					1/15/2013		50		\$0.00
Medium	Work In Progress			1/15/2013 2:54:22 PM					
Lozoya, Manny	NEED NEW KEYS FOR FRONT DOORS AND OUTSIDE DOORS								
<u>Danny Miranda</u>									
98859					2/26/2013		8		\$0.00
Medium	Work In Progress			2/26/2013 9:02:49 AM					
Lozoya, Manny	need to replace hinge to back door in cafeteria (continuance hinge)								
<u>Danny Miranda</u>									

3/6/2013 4:22:59 PM

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
99344					3/5/2013		1		\$0.00
Medium	Work In Progress				3/5/2013 9:18:27 AM				
Lozoya, Manny		need to rekey room in office for student files							
Danny Miranda									
96755					1/6/2013	2/6/2013	59		\$0.00
Medium	Work In Progress				1/6/2013 12:23:33 AM				
Villalobos, David		Yearly - Vado ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
99141					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:24 AM				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
97306					1/15/2013		50		\$0.00
Medium	Work In Progress				1/15/2013 9:14:04 AM				
Miranda, Danny		need saw horses for front parking lot							
Danny Miranda									
93941					10/9/2012		148		\$0.00
Medium	Work In Progress				10/9/2012 2:31:56 PM				
Miranda, Danny		please install new soccer goals when purchased. thank you							
Michael Munoz									
99142					3/3/2013	3/11/2013	3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:25 AM				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
99143					3/3/2013		3		\$0.00
Medium	Work In Progress				3/3/2013 12:25:25 AM				
Miranda, Danny		Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
97925					1/31/2013		34		\$0.00
Medium	Work In Progress				1/31/2013 9:47:23 AM				
Flores, Pete		NEED TO SERVICE MOWER SHARPEN BLADES AND CHANGE OIL							
Danny Miranda									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
93866					10/8/2012		149		\$0.00
Medium	Work In Progress			10/8/2012 8:46:35 AM					
Flores, Pete	TRUCK # NEED TO CK FRONT RIGHT SIDE NOISE, DRIVERS SIDE DOOR' TRANSMISION LEVER' WINDSHEALD, CATALYTIC CONVERTER								
<u>Danny Miranda</u>									
99140					3/3/2013	3/9/2013	3		\$0.00
Medium	Work In Progress			3/3/2013 12:25:24 AM					
Miranda, Danny	Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96783					1/6/2013		59		\$0.00
Medium	Work In Progress			1/6/2013 12:23:45 AM					
Orozco, Daniel	Monthly - Vado ES - Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99228					3/3/2013		3		\$0.00
Medium	Work In Progress			3/3/2013 12:26:04 AM					
Munoz, Michael	Yearly - Vado ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99291					3/4/2013		2		\$0.00
Medium	Work In Progress			3/4/2013 9:44:43 AM					
Orozco, Daniel	MILK COOLER IS TRIPPIN BREAKER. SNP MANAGER EVA M. 233.2945								
<u>Maritza Gonzalez</u>									
94699					10/29/2012		128		\$0.00
Medium	Work In Progress			10/29/2012 9:58:15 AM					
Orozco, Daniel	EXHAUST FAN OVER OVENS IS NOT WORKING.SNP MANAGER EVA M. 233.2945								
<u>Maritza Gonzalez</u>									
98664					2/20/2013		14		\$0.00
Medium	Work In Progress			2/20/2013 12:20:37 PM					
Lozoya, Manny	NEED TO CHANGE COMBINATION TO VAULT IN FRONT OFFICE								
<u>Danny Miranda</u>									
99365	Main Building	Office			3/5/2013		1		\$0.00
Medium	Work In Progress			3/5/2013 2:05:15 PM					
Briones, Enrique	Please pick up boxes of Math Adoption samples								
Larry Martinez									

1017 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
98251	Main Building	Custodial			2/6/2013		28		\$0.00
Medium	Work In Progress				2/6/2013 10:04:16 AM				
Carbajal, Jimmy		Need vacuum cleaner switch replace serial # 1174 Thank u !							
Armando Diaz									
97527	Main Building	Office			1/22/2013		43		\$0.00
Medium	Work In Progress				1/22/2013 8:30:35 AM				
Lozoya, Manny		NEED 3 F1 KEYS AND 1 STORAGE DOOR KEY							
Debra Facio									
Count: 26 Work Orders		Avg. Age of WO's		41	Total for Vado ES			0	\$0.00
Count: 1017 Work Orders		Avg. Age of WO's		55	Grand Total			0	\$0.00