

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location:		Alma Del Valle Daycare							
98506					2/14/2013		88		\$0.00
Medium	Work In Progress				2/14/2013 7:04:32 AM				
Ontiveros, Guadalupe	NEED SAND FOR DAYCARE SANDBOX. (FRONT OF BUILDING). 5 1/2 FT X 5 1/2 FT WIDE, 1 FT DEEP.								
Adam Montoya									
Count: 1 Work Orders		Avg. Age of WO's	88		Total for Alma Del Valle Daycare		0		\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
99574					3/12/2013		62		\$0.00
Medium	Work In Progress			3/12/2013 7:40:37 AM					
Ontiveros, Guadalupe	Remove dirt buildup in areas south of S. Bldg. and in between pine trees (clear sidewalk). Also areas in between sidewalks in front of portables.								
Alfredo Holguin									
99576					3/12/2013		62		\$0.00
Medium	Work In Progress			3/12/2013 7:46:54 AM					
Ontiveros, Guadalupe	build raised planters								
Alfredo Holguin									
99949					3/20/2013		54		\$0.00
Medium	Work In Progress			3/20/2013 3:46:38 PM					
Solis, Lorenzo	Need some assistance on a.c. on pre k workroom not working.								
Arturo Nunez									
95797					11/26/2012		168		\$0.00
Medium	Work In Progress			11/26/2012 3:48:45 PM					
Nunez, Arturo	CANOPY AT PRE K PLAY AREA NEEDS TO BE REPAIRED OR REPLACED, HAS A PRETTY GOOD SIZE TEAR ON TOP.								
Arturo Nunez									
99575					3/12/2013		62		\$0.00
Medium	Work In Progress			3/12/2013 7:43:08 AM					
Munoz, Michael	Install Pedestrian Gates and Fence from parent drop off to Anthony Pre-K.								
Alfredo Holguin									
100051					3/25/2013		49		\$0.00
Medium	Work In Progress			3/25/2013 9:13:24 AM					
Munoz, Michael	Install sidewalk from parent drop off to Anthony Pre-K.								
Alfredo Holguin									
Count: 6 Work Orders			Avg. Age of WO's 76		Total for Anthony - On Track Pre-K (Village)		0		\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
101781					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:45 AM				
Nunez, Arturo	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99215					3/3/2013		71		\$0.00
Medium	Work In Progress				3/3/2013 12:25:57 AM				
Munoz, Michael	Yearly - Anthony ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92466					9/6/2012		249		\$0.00
Medium	Work In Progress				9/6/2012 1:00:10 PM				
Orozco, Daniel	DISHWASHER WASH IN WASH MODE AND STOPPED WORKING. SNP MANAGER BECKY S. 882.3507								
<u>Maritza Gonzalez</u>									
100719					4/9/2013		34		\$0.00
Medium	Work In Progress				4/9/2013 9:10:55 AM				
Orozco, Daniel	THE ELECT. CORD TO THE CASH REGISTER TABLE DOES NOT WORK. SNP MANAGER BECKY. S. 882.3507								
<u>Maritza Gonzalez</u>									
100360					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress				3/31/2013 12:33:20 AM				
Orozco, Daniel	Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101011					4/17/2013		26		\$0.00
Medium	Work In Progress	SPED			4/17/2013 7:37:36 AM				
Lozoya, Manny	NEED FRONT DOOR PRESSURE GAUGE REPAIRED (DOOR SLAMS SHUT)								
<u>Margaret Villalobos</u>									
101997					5/9/2013		4		\$0.00
Medium	Work In Progress				5/9/2013 4:08:58 PM				
Lara, Ralph	MR. NUNEZ EXIT DOORS ARE NOT CLOSING PROPERLY PLEASE CHECK								
<u>Jessica Lopez</u>									
100538					4/4/2013		39		\$0.00
High	Work In Progress				4/4/2013 1:33:14 PM				
Munoz, Michael	on the southside of the upper primary the sidewalk is cracked and needs to be replaced. parents use it daily.								
<u>Alfredo Holguin</u>									
5/13/2013 12:30:57 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
101786					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:47 AM					
Orozco, Daniel	Monthly - Anthony ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99796	Main Building	Office			3/18/2013		56		\$0.00
Medium	Work In Progress			3/18/2013 7:45:26 AM					
Briones, Enrique	Please pick up obsolete equipment.								
<u>Larry Martinez</u>									
99902	Main Building	Office			3/20/2013		54		\$0.00
Medium	Work In Progress			3/20/2013 8:41:34 AM					
Briones, Enrique	Please pick up obsolete equipment .								
<u>Larry Martinez</u>									
98852	Main Building				2/26/2013		76		\$0.00
Medium	Work In Progress			2/26/2013 5:05:41 AM					
Lozoya, Manny	change core in morgan storage to k or h master so that custodians can have access to gator								
<u>David Vega</u>									
101141	Main Building				4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 9:02:27 AM					
Carbajal, Jimmy	vacuum cleaner serial #05387 needs repair, ext cord is shorting out also needs bottom plate								
<u>David Vega</u>									
101541	Original Main				5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 8:33:51 AM					
Lozoya, Manny	key cylinder in main entrance is getting stuck								
<u>David Vega</u>									
101649	Drug Free Bldg.				5/3/2013		10		\$0.00
High	Work In Progress			5/3/2013 1:26:11 PM					
Villalobos, David	water is running on commode. please replace ballcock. thank you								
<u>Michael Munoz</u>									
91739	Pump House				8/23/2012		263		\$0.00
Medium	Work In Progress			8/23/2012 9:52:41 AM					
Gonzalez, Salvador	upper primary pump house tank is leaking								
<u>Hector Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
95549					11/14/2012		180		\$0.00
Medium	Work In Progress			11/14/2012 3:48:20 PM					
Apodaca, Mario		AS PER MS. PEREZ , REQUESTING FOR WTAER FILTER BE INSTALLED FOR DOMESTIC WATER LINE.							
Arturo Nunez									
94354					10/19/2012		206		\$0.00
Medium	Work In Progress	SPED OFFICE		10/19/2012 9:00:43 AM					
Nunez, Arturo		MOVE OFFICE DESK FROM J. HERNANDEZ OFFICE TO DIAGNOSTICIANS OFFICE/MOVE DESK FROM DIAGNOSTICIAN OFFICE TO JULIE HERNANDEZ OFFICE (SEE JULIE HERNANDEZ OR MARGARET)							
Margaret Villalobos									
98807					2/25/2013		77		\$0.00
Medium	Work In Progress	SPED OFFICE		2/25/2013 10:34:38 AM					
Nunez, Arturo		REMOVE CHALKBOARD IN DIAGNOSTICIANS ROOM ON THE FAR LEFT SIDE WALL							
Margaret Villalobos									
98808					2/25/2013		77		\$0.00
Medium	Work In Progress	SPED OFFICE		2/25/2013 10:35:26 AM					
Nunez, Arturo		MOVE BLANCA ROLLE'S DESK IN DIAGNOSTIANS OFFICE TO THE RIGHT CORNER BY THE DOOR							
Margaret Villalobos									
98809					2/25/2013		77		\$0.00
Medium	Work In Progress	SPED OFFICE		2/25/2013 10:36:15 AM					
Nunez, Arturo		REMOVE STORAGE CABINETS IN A. SANCHEZ OFFICE AND MOVE TO DIAGNOSTICIAN OFFICE							
Margaret Villalobos									
98810					2/25/2013		77		\$0.00
Medium	Work In Progress	SPED OFFICE		2/25/2013 10:39:37 AM					
Nunez, Arturo		REMOVE CABINETS FROM STORAGE ROOM AND INSTALL IN DIAGNOSTICIANS ROOM							
Margaret Villalobos									
98593					2/19/2013		83		\$0.00
Medium	Work In Progress			2/19/2013 7:57:13 AM					
Nunez, Arturo		A.C.U'S NEED TO BE SERVICED FOR CHANGE OVER FROM HTGING. TO COOLING FOR SEASON.				3/1 - Reroute to BM			
Arturo Nunez									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
98611					2/19/2013		83		\$0.00
Medium	Work In Progress				2/19/2013 2:52:10 PM				
Nunez, Arturo	WATER SUPPLY LINES TO A.C. UNITS IN OLD CAF. BUILDING NEED TO BE REPLACED.								
<u>Arturo Nunez</u>									
98210					2/5/2013		97		\$0.00
Medium	Work In Progress	SPED OFFICE			2/5/2013 3:02:42 PM				
Nunez, Arturo	MOVE FURNITURE IN DIAGNOSTICIAN OFFICE AS INSTRUCTED BY JULIE HERNANDEZ (DR. BLANCA ROLLE)								
<u>Margaret Villalobos</u>									
98211					2/5/2013		97		\$0.00
Medium	Work In Progress	SPED OFFICE			2/5/2013 3:03:21 PM				
Nunez, Arturo	MOVE FILE CABINETS INTO DIAGNOSTICIAN ROOM (SEE JULIE HERNANDEZ)								
<u>Margaret Villalobos</u>									
98213					2/5/2013		97		\$0.00
Medium	Work In Progress	SPED OFFICE			2/5/2013 3:04:01 PM				
Nunez, Arturo	REMOVE OLD SHELVES FROM DIAGNOSTICIAN OFFICE (SEE JULIE HERNANDEZ)								
<u>Margaret Villalobos</u>									
98302					2/7/2013		95		\$0.00
Medium	Work In Progress				2/7/2013 3:40:46 PM				
Nunez, Arturo	NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING.								
<u>Arturo Nunez</u>									
96999					1/8/2013		125		\$0.00
Medium	Work In Progress	SPED OFFICE			1/8/2013 8:58:52 AM				
Nunez, Arturo	PLEASE HAVE MAINTENANCE FINISH ROOM 120 REMOVE ALL CHALKBOARDS FROM THE HALL AND DISPOSE OF, PAINTING STILL NEEDS TO COMPLETED IN ORDER TO SET UP OFFICE SPACE FOR DIAGNOSTICIAN								
<u>Margaret Villalobos</u>									
96328					12/6/2012		158		\$0.00
Medium	Work In Progress	SPED OFFICE			12/6/2012 3:22:16 PM				
Nunez, Arturo	FINISH REMOVING CHALK BOARDS IN ROOM 120 (DISPOSE OF CHALKBOARDS) AND PAINT ROOM 120								
<u>Margaret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
100307					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:00 AM					
Holguin, Alfredo	Monthly - Anthony ES - Fire Pump Engine - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101744					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:29 AM					
Nunez, Arturo	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101707					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:14 AM					
Nunez, Arturo	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100313					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:02 AM					
Nunez, Arturo	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101396					4/29/2013		14		\$0.00
Medium	Work In Progress			4/29/2013 8:18:01 AM					
Ontiveros, Guadalupe	Need some assistance on zone # 6 in new sod area, valve is getting stuck, with other zones.								
<u>Arturo Nunez</u>									
101398					4/29/2013		14		\$0.00
Medium	Work In Progress			4/29/2013 8:24:58 AM					
Ontiveros, Guadalupe	Need some assistance on sprinkler main water line, in Alamo parking lot, line is broken, and is leaking.								
<u>Arturo Nunez</u>									
99036					2/28/2013		74		\$0.00
Medium	Work In Progress	SPED OFFICE		2/28/2013 1:36:14 PM					
Solis, Lorenzo	HEATER UNIT IN DATA CLERKS OFFICE IS LEAKING PLEASE CHECK AS SOON AS POSSIBLE.								
<u>Margaret Villalobos</u>									
101976					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 3:32:13 PM					
Solis, Lorenzo	Can we please have have a.c switches installed in Alamo a.c unit, so that they can turn on a.c's individually, instead of turning all at once.								
<u>Arturo Nunez</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
99527					3/11/2013		63		\$0.00
Medium	Work In Progress				3/11/2013 8:05:17 AM				
Gallegos, Rafael	re adjust lights in new bldg and main bldg to turn on to new daylight savings time								
David Vega									
101199					4/23/2013		20		\$0.00
Medium	Work In Progress				4/23/2013 8:21:55 AM				
Sotelo, Enrique	Need some assistance with water fountain in Aggie hallway, g.f.c.i. keeps tripping frequently.								
Arturo Nunez									
94680					10/26/2012		199		\$0.00
Medium	Work In Progress				10/26/2012 3:48:12 PM				
Sotelo, Enrique	NEED SOME ASSISTANCE ON TROUBLE SHOOTING LIGHT FIXTURES ON PRE K. WORK ROOM, HALF OF THE IN ROOM ARE TURNED OFF								
Arturo Nunez									
102036					5/10/2013		3		\$0.00
Medium	Work In Progress				5/10/2013 3:38:51 PM				
Lara, Ralph	Need some assistance on adjusting door closers on all entrance doors.								
Arturo Nunez									
102037					5/10/2013		3		\$0.00
Medium	Work In Progress				5/10/2013 3:40:27 PM				
Lara, Ralph	Main entrance door lock needs to be repaired, door does not lock, security purpose.								
Arturo Nunez									
100968					4/16/2013		27		\$0.00
Medium	Work In Progress				4/16/2013 8:12:27 AM				
Lozoya, Manny	Need to have lock in mobile home tenant checked key is getting stuck, they are having trouble opening lock.								
Arturo Nunez									
93782					10/3/2012		222		\$0.00
Medium	Work In Progress	SPED OFFICE			10/3/2012 9:31:24 AM				
Lozoya, Manny	NEED TWO (2) KEYS FOR ROOM 120 (CANNOT READ NUMBER ON DOORKNOB)								
Margaret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
99024					2/28/2013		74		\$0.00
Medium	Work In Progress			2/28/2013 8:18:36 AM					
Lozoya, Manny	Here is a list of names for the Social Workers whom will be needing a gate key. If you have any questions please feel free to contact our office. Thank you, Luz Garcia 575-882-6788								
	ARAGON, CRYSTAL MARIE BACA, MARIBEL HOLGUIN, DEBORAH ANN JACQUEZ-GUILLEN, ERNESTINA MARQUEZ, ANAHI LORENA MARTINEZ, WILMA PORRAS, GEORGINA ELIZABETH RANGEL, VERONICA ROBERTS, RICARDO								
<u>Margret Villalobos</u>									
99980					3/21/2013		53		\$0.00
Medium	Work In Progress			3/21/2013 10:37:46 AM					
Villalobos, Margret	Monthly - Anthony ES - Trane PM Quarterly - Refer to PM schedule details. E-mailed Trane 3/21/13								
<u>Margret Villalobos</u>									
99170					3/3/2013	4/3/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:37 AM					
Villalobos, Hector	Yearly - Anthony ES R3 (Ref. Unit)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100192					3/31/2013	5/1/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:15 AM					
Villalobos, Hector	Yearly - Anthony ES A8(Rooftop Unit)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100190					3/31/2013	5/1/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:14 AM					
Villalobos, Hector	Yearly - Anthony ES A13 (AC Wall Mount)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100191					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:14 AM					
Villalobos, Hector	Yearly - Anthony ES A6 (Rooftop Unit)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
101864					5/7/2013		6		\$0.00
Medium	Work In Progress	SPED OFFICE		5/7/2013 12:53:53 PM					
Solis, Lorenzo		NEED FAN TO HELP CIRCULATE AIR IN THE DATA CLERKS OFFICE (OFFICE GETS REALLY HOT/STUFFY)							
<hr/>									
Margret Villalobos									
98993					2/28/2013	3/31/2013	74		\$0.00
Medium	Work In Progress			2/28/2013 12:28:23 AM					
Nunez, Arturo		Yearly - Anthony ES C-11 (Evap.Down)(Yearly) - Refer to PM schedule details.							
<hr/>									
Margret Villalobos									
100622					4/7/2013	4/23/2013	36		\$0.00
Medium	Work In Progress			4/7/2013 12:18:48 AM					
Nunez, Arturo		Monthly - Anthony ES A4 (Rooftop Unit)(S.Annual) - Refer to PM schedule details.							
<hr/>									
Margret Villalobos									
100204					3/31/2013	4/16/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:20 AM					
Nunez, Arturo		Monthly - Anthony ES A3(Rooftop Unit)(S.Annual) - Refer to PM schedule details.							
<hr/>									
Margret Villalobos									
Count: 55 Work Orders			Avg. Age of WO's	68		Total for Anthony ES	0		\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
99794					3/17/2013		57		\$0.00
Medium	Work In Progress			3/17/2013 12:19:59 AM					
Villalobos, Margret		Monthly - Berino ES - PC Automated Quarterly - Refer to PM schedule details.				Emailed to Melanie on 3/18/13			
<u>Margret Villalobos</u>									
94300		Office			10/18/2012		207		\$0.00
Medium	Work In Progress	OFFICE		10/18/2012 9:41:51 AM					
Lozoya, Manny		OFFICE- FOR MANNY LOZOYA- I NEED A NEW NAME PLATE MARIBEL GAMBOA. THANK YOU							
<u>Maribel Chavez</u>									
95628					11/16/2012		178		\$0.00
Medium	Work In Progress			11/16/2012 2:06:10 PM					
Lozoya, Manny		NEED A LOCK AND KEY FOR THE GATE DRAINAGE POND AREA.							
<u>Maribel Chavez</u>									
95215					11/6/2012		188		\$0.00
Medium	Work In Progress			11/6/2012 8:20:10 AM					
Lozoya, Manny		MANNY LOZOYA PER MR VALTIERRA MANNY NEED TO INSTALL A DEAD-BOLT MAIN ENTRANCE TO LIBRARY FOR BETTER SECURITY THANK YOU SIR AND GOD BLESS							
<u>Adan Duran</u>									
99748					3/15/2013		59		\$0.00
Medium	Work In Progress			3/15/2013 9:20:11 AM					
Lozoya, Manny		NEED TO HAVE SOME KEYS REKEYED TO THE OUTSIDE DOOR.							
<u>Maribel Chavez</u>									
96217					12/4/2012		160		\$0.00
Medium	Work In Progress			12/4/2012 8:19:14 AM					
Ontiveros, Guadalupe		MR LUPE ONTIVEROS SIR NEED TO CLEAN AND DRESS UP PONDING AREA EAST SIDE BOTTOM FULL OF DIRT THANK YOU SIR AND GOD BLESS							
<u>Adan Duran</u>									
101873					5/7/2013		6		\$0.00
Medium	Work In Progress			5/7/2013 3:22:13 PM					
Sotelo, Enrique		MR ENRIQUE SOTELO SIR THE GFI WATER FOUNTAINS MIDDLE WING NORTH SIDE NEED REPLACING THANK YOU SIR AND GOD BLESS							
<u>Adan Duran</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
96600					12/13/2012		151		\$0.00
Medium	Work In Progress			12/13/2012 3:03:45 PM					
Villalobos, David	MR FRED APPELLOZER SIR THE WATER HEATER PORTABLE 155&156 SMALL WATER HEATER IS TO HOT NEED TO ADJUST HOT WATER HEADSTART KIDS THANK YOU SIR AND GOD BLESS		Route to David asp reassignment 4/2/13						
Adan Duran									
96760					1/6/2013	2/6/2013	127		\$0.00
Medium	Work In Progress			1/6/2013 12:23:36 AM					
Villalobos, David	Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
98891					2/26/2013		76		\$0.00
Medium	Work In Progress			2/26/2013 2:46:15 PM					
Villalobos, David	MR FRED APPELZOLLAR SIR THE LITTLE WATER HEATER IN PORTABLE 155&156 IS NOT WORKING NEED TO BE REPLACE ALSO THE WATER FACET IS LEAKING NEED REPLACING		Route to David asp reassignment 4/2/13						
Adan Duran									
99979					3/21/2013		53		\$0.00
Medium	Work In Progress			3/21/2013 10:00:32 AM					
Villalobos, David	MR DAVID VILLALOBOS SIR THE WATER HEATER IN PORTABLE 155&156 HEADSTART IS NOT HEATING RIGHT PLEASE CHECK THANK YOU AND GOD BLESS								
Adan Duran									
100932					4/15/2013		28		\$0.00
Medium	Work In Progress			4/15/2013 1:29:51 PM					
Duran, Adan	MR DURAN AS PER MR VALTIERRA NEED TO ORDER 5 GAL OF PAINT TO MATCH CLASS ROOM OFF WHITE FOR TOUCH UPS								
Adan Duran									
99918					3/20/2013		54		\$0.00
Medium	Work In Progress			3/20/2013 10:09:17 AM					
Flores, Pete	MR PETE FLORES SIR WOULD LIKE THE USE OF THE BOBCAT THURSDAY AND FRIDAY IF ITS IN THE YARD THANK YOU SIR AND GOD BLESS								
Adan Duran									
99763					3/15/2013		59		\$0.00
Medium	Work In Progress			3/15/2013 1:40:40 PM					
Duran, Adan	MR DURAN NEED GO ORDER TWO 3/4 KEY SPRINKLER VALVES FOR NORTH PLAYGROUND WITH HOSE BIB								
Adan Duran									
5/13/2013 12:30:57 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
100843					4/11/2013		32		\$0.00
Medium	Work In Progress			4/11/2013 3:02:41 PM					
Duran, Adan	MR DURAN PER MR VALTIERRA SIR THE FACUETS IN RESTROOM ARE COMMING LOSE NEED TO TIGHTEN NEED BASS NUTS								
Adan Duran									
102050					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:25 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
100326					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:07 AM					
Sanchez, Raul	Monthly - Berino ES - Monthly Meter Readings - Refer to PM schedule details.								
Margret Villalobos									
99409					3/6/2013		68		\$0.00
Medium	Work In Progress			3/6/2013 2:55:21 PM					
Sanchez, Raul	MR RAUL SANCHEZ SIR NEED TO REPLACE WATER FILTERS ALSO THE WATER GAGE IS LEAKING NEED TO REPLACE THANK YOU SIR AND GOD BLESS								
Adan Duran									
101787					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:47 AM					
Orozco, Daniel	Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
101087					4/18/2013		25		\$0.00
Medium	Work In Progress			4/18/2013 3:41:57 PM					
Flores, Pete	MR PETE FLORES SIR NEED THE USE OF A LITTLE TRACTOR TO PULL THE DRAG ACROSS FIELD								
Adan Duran									
94887					11/1/2012		193		\$0.00
Medium	Work In Progress			11/1/2012 10:52:35 AM					
Lozoya, Manny	put 2 key cores on muntin in the 2 lobbys								
Jimmy Cortez									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Berino ES								
97927					1/31/2013		102		\$0.00	
Medium	Work In Progress			1/31/2013 10:17:48 AM						
Lozoya, Manny	MR MANNY LOZOYA SIR NEED THE KEY CORE INSTALL DOOR ROOM 138 IT IS MISSING THANK YOU SIR AND GOD BLESS									
Adan Duran										
100361					3/31/2013	4/21/2013	43		\$0.00	
Medium	Work In Progress			3/31/2013 12:33:21 AM						
Orozco, Daniel	Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details.									
Margret Villalobos										
101708					5/5/2013	5/13/2013	8		\$0.00	
Medium	Work In Progress			5/5/2013 12:24:15 AM						
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
Margret Villalobos										
101710					5/5/2013		8		\$0.00	
Medium	Work In Progress			5/5/2013 12:24:16 AM						
Duran, Adan	Monthly - Berino ES - Clothes Dryer (Monthly) - Refer to PM schedule details.									
Margret Villalobos										
101711					5/5/2013	5/13/2013	8		\$0.00	
Medium	Work In Progress			5/5/2013 12:24:16 AM						
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.									
Margret Villalobos										
101213					4/23/2013		20		\$0.00	
Medium	Work In Progress			4/23/2013 1:28:22 PM						
Orozco, Daniel	TILT SKILLET GOES OFF ALL OF A SUDDEN AND WONT TURN ON. SNP MANAGER ELSA C. 882.2417									
Maritza Gonzalez										
101779					5/5/2013	5/11/2013	8		\$0.00	
Medium	Work In Progress			5/5/2013 12:24:44 AM						
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.									
Margret Villalobos										
99216					3/3/2013		71		\$0.00	
Medium	Work In Progress			3/3/2013 12:25:58 AM						
Munoz, Michael	Yearly - Berino ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.									
Margret Villalobos										
Count: 29 Work Orders	Avg. Age of WO's 70		Total for Berino ES				0	\$0.00		

5/13/2013 12:30:57 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
99217					3/3/2013		71		\$0.00
Medium	Work In Progress				3/3/2013 12:25:58 AM				
Munoz, Michael	Yearly - Chaparral ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100342					3/31/2013	4/6/2013	43		\$0.00
Medium	Work In Progress				3/31/2013 12:33:13 AM				
Quinones, Paul	Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101765					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:38 AM				
Quinones, Paul	Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97957					1/31/2013		102		\$0.00
Medium	Work In Progress				1/31/2013 3:50:28 PM				
Gonzalez, Salvador	NEED METAL FRAME TO REPLACE THE WOOD FRAME, AND A 1/16 DIAMOND PLATE TO COVER THE WATER SUPPLY AND PLUMBING TO THE WATER FOUNTAIN FOR PROTECTION.								
<u>Paul Quinones</u>									
100362					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress				3/31/2013 12:33:21 AM				
Orozco, Daniel	Monthly - Chapparal ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98886					2/26/2013		76		\$0.00
Medium	Work In Progress				2/26/2013 1:46:18 PM				
Lozoya, Manny	DOUBLE DOORS, DOOR FRAME BEND AND DOOR IS RIPPED ON THE UPPER LEFT SIDE OF THE DOOR LOCATED NEXT TO THE CAFETERIA.								
<u>Paul Quinones</u>									
99759					3/15/2013		59		\$0.00
Medium	Work In Progress				3/15/2013 12:14:06 PM				
Lozoya, Manny	please replace broken door handle in rm. 220								
<u>Paul Quinones</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
98472					2/13/2013		89		\$0.00
Medium	Work In Progress				2/13/2013 2:23:16 PM				
Lozoya, Manny	REQUESTING DOOR AND DOOR FRAME TO SECURE SCHOOL SUPPLIES AND FOR STORAGE USE.								
Paul Quinones									
101299					4/24/2013		19		\$0.00
Medium	Work In Progress				4/24/2013 4:04:47 PM				
Lozoya, Manny	DOOR HANDLE IN ACTIVITY RM.BROKEN FROM THE INSIDE NEEDS TO BE REPLACED THANKS								
Paul Quinones									
100696					4/8/2013		35		\$0.00
Medium	Work In Progress				4/8/2013 3:50:15 PM				
Lozoya, Manny	DOOR IN CLASS RM.302 DOOR IS DRAGGING ON FLOOR								
Paul Quinones									
102072					5/13/2013		0		\$0.00
Medium	Work In Progress				5/13/2013 8:33:18 AM				
Lara, Ralph	DOUBLE DOORS 300WING N.END DOOR RIPPED FROM HINGE,AND DOUBLE DOORS FRONT ENTRANCE NEXT TO THE CAFETERIA ARE RIPPED FROM THE HINGE AS WAELL								
Paul Quinones									
101273		Custodial			4/24/2013		19		\$0.00
Medium	Work In Progress				4/24/2013 1:38:53 PM				
Carbajal, Jimmy	need,to,fix,vaccum,electrical, cord.bottom,cut,								
Daniel Ramirez									
101164		Custodial			4/22/2013		21		\$0.00
Medium	Work In Progress				4/22/2013 1:07:28 PM				
Carbajal, Jimmy	need,to,fix,vaccum,back,wheel,fell,off,i,0,6,c,00000,3								
Daniel Ramirez									
101165		Custodial			4/22/2013		21		\$0.00
Medium	Work In Progress				4/22/2013 1:10:00 PM				
Carbajal, Jimmy	need,to,fix,vaccum,handle,,d,5,a,0000,5,3,7,1								
Daniel Ramirez									
101807					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:57 AM				
Quinones, Paul	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
5/13/2013 12:30:58 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
100395					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:35 AM					
Quinones, Paul	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101369					4/26/2013		17		\$0.00
Medium	Work In Progress			4/26/2013 10:37:38 AM					
Estrada, Jesus	RM.501 CARPET NEEDS REPAIR,CARPET IS COMING APART INBETWEEN CLASS RM.TRANSITION STRIP WILL NOT COVER THE CARPET.								
<u>Paul Quinones</u>									
99850	Main Building	Office			3/19/2013		55		\$0.00
Medium	Work In Progress	school		3/19/2013 8:22:20 AM					
Lozoya, Manny	need 4 more keys to open doors from outside. See Jennifer								
<u>Jennifer Corral</u>									
96945	Main Building	Classroom			1/7/2013		126		\$0.00
Medium	Work In Progress	gym		1/7/2013 2:33:45 PM					
Lozoya, Manny	need keys for coaches N69 please see Nava and Flores								
<u>Jennifer Corral</u>									
97031	Main Building	Hallway/Corridor			1/8/2013		125		\$0.00
Medium	Work In Progress	whole school		1/8/2013 2:14:58 PM					
Lozoya, Manny	main doors going to protables need to be rekeyed so teachers may open with their keys. See Administration								
<u>Jennifer Corral</u>									
101788					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:48 AM					
Orozco, Daniel	Monthly - Chaparral ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100651					4/7/2013	4/23/2013	36		\$0.00
Medium	Work In Progress			4/7/2013 12:19:05 AM					
Quinones, Paul	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
102051					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:26 AM					
Quinones, Paul	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
5/13/2013 12:30:58 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
98332					2/10/2013	2/26/2013	92		\$0.00
Medium	Work In Progress			2/10/2013 12:20:37 AM					
Quinones, Paul	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99521					3/10/2013	3/26/2013	64		\$0.00
Medium	Work In Progress			3/10/2013 12:19:11 AM					
Quinones, Paul	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100508					4/3/2013		40		\$0.00
Medium	Work In Progress			4/3/2013 3:39:02 PM					
Estrada, Jesus	REQUESTING NEW FLOORING TILE IN THE CAFETERIA DURING THE SUMMER								
<u>Paul Quinones</u>									
100235					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:32 AM					
Quinones, Paul	Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99468					3/7/2013		67		\$0.00
Medium	Work In Progress			3/7/2013 3:48:50 PM					
Flores, Pete	please check front suspension to work truck #123								
<u>Paul Quinones</u>									
94038					10/11/2012		214		\$0.00
High	Work In Progress			10/11/2012 7:27:40 AM					
Quinones, Paul	new furniture came in and needs to be assembled. thank you								
<u>Michael Munoz</u>									
95567					11/15/2012		179		\$0.00
Scheduled	Work In Progress			11/15/2012 10:34:17					
Quinones, Paul	Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You								
Dominique Esparza									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
99666					3/13/2013		61		\$0.00
Medium	Work In Progress			3/13/2013 3:48:58 PM					
Quinones, Paul	need 100' of water hose 5/8"for general use and to water grass and trees								
Paul Quinones									
99890					3/19/2013		55		\$0.00
Medium	Work In Progress			3/19/2013 4:03:08 PM					
Quinones, Paul	NEED A TOTAL OF 18 ROOF JACKS FOR THE A/C'S IN THE 200 WING								
Paul Quinones									
101166		Custodial			4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 1:13:14 PM					
Carbajal, Jimmy	need,another,tilted,cart,to,pick,up,trash.								
Daniel Ramirez									
95651					11/16/2012		178		\$0.00
Medium	Work In Progress			11/16/2012 4:32:03 PM					
Martinez, Larry	relocate furniture from che to san miguel for storage.								
Paul Quinones									
101517					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 3:52:00 PM					
Quinones, Paul	need 1 1/2"X 1 1/2" 10' ANGLE FOR NEW A/C INSTALL IN THE ACTIVITY RM.								
Paul Quinones									
101370					4/26/2013		17		\$0.00
Medium	Work In Progress			4/26/2013 10:42:56 AM					
Quinones, Paul	REQUESTING 6800 AREO COOL SIDE DRAFT EVAP.COOLER FOR NEW INSTALLATION IN THE ACTIVITY RM.AND 6 ANGLE IRON FOR FRAME.								
Paul Quinones									
101443					4/29/2013		14		\$0.00
Medium	Work In Progress			4/29/2013 4:15:01 PM					
Quinones, Paul	REQUESTING REMINGTON FRAMING GUN TO ANCHOR OUTSIDE WALL TO FOUADATION ATTN. RUBEN RONQUILLO								
Paul Quinones									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
101685					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:06 AM					
Quinones, Paul	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101686					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:06 AM					
Quinones, Paul	Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
102065					5/13/2013		0		\$0.00
Medium	Work In Progress			5/13/2013 8:11:54 AM					
Quinones, Paul	NEED TO REPLACE BROKEN SPRINKLERS REORDER AND RESTOCK								
<u>Paul Quinones</u>									
100929					4/15/2013		28		\$0.00
Medium	Work In Progress			4/15/2013 12:24:51 PM					
Quinones, Paul	NEED TO REPLACE BROKEN SPRINKLERS IN THE FRONT OF SCHOOL.								
<u>Paul Quinones</u>									
100250					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:38 AM					
Quinones, Paul	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100251					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:38 AM					
Quinones, Paul	Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101847					5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 3:57:15 PM					
Vallejo, Albert	NEW OUTER WALL ENCLOSURE,AND NEW DOOR ENTRY IN FRONT OF THE CONCESSION STAND,REQUESTING A 3-WAY SWITCH CIRCUIT,2 LAMPS,AND 1 LAMP OUTSIDE DOOR								
<u>Paul Quinones</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
102075					5/13/2013		0		\$0.00
Medium	Work In Progress	LINE LOCATE		5/13/2013 8:55:06 AM					
Vallejo, Albert	LINE LOCATE IN BETWEEN 400 WING AND THE ACTIVITY RM.								
Paul Quinones									
101204					4/23/2013		20		\$0.00
Medium	Work In Progress			4/23/2013 8:36:20 AM					
Vallejo, Albert	requesting relocate electrical for new air conditioner install in the activity rm. 2-speed control wiring								
Paul Quinones									
99737					3/14/2013		60		\$0.00
Medium	Work In Progress			3/14/2013 3:55:16 PM					
Quinones, Paul	REPAINT 200 WING FOR THE SUMMER BREAK								
Paul Quinones									
100698					4/8/2013		35		\$0.00
Medium	Work In Progress			4/8/2013 3:52:48 PM					
Appelzoller, Fred	WATER FAUCETS LEAKING IN GIRLS REST RM.FRONT ENTRANCE,REQUESTING NEW FAUCETS.								
Paul Quinones									
101818					5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 9:47:38 AM					
Appelzoller, Fred	requesting new water faucet in rm.213 rest rm. handle is worn out.								
Paul Quinones									
98706					2/21/2013		81		\$0.00
Medium	Work In Progress			2/21/2013 8:09:12 AM					
Ontiveros, Guadalupe	please airate soccer field,and fertilize as well thank you								
Paul Quinones									
98708					2/21/2013		81		\$0.00
Medium	Work In Progress			2/21/2013 8:11:03 AM					
Ontiveros, Guadalupe	irrigation booster pump motor burned shorted out								
Paul Quinones									
101301					4/24/2013		19		\$0.00
Medium	Work In Progress			4/24/2013 4:09:14 PM					
Lozoya, Manny	NEED TO SECURE GATE NEXT TO NEW WING REQUESTING LOCK TO SECURE GATE THANKS								
Paul Quinones									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral ES									
101471					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 9:20:19 AM					
Lozoya, Manny	RM.501 KEY WILL NOT GO INTO KEY CYLINDER, DOOR DOESNT OPEN FROM THE OUTSIDE W/KEY								
Paul Quinones									
92134					8/31/2012		255		\$0.00
Medium	Work In Progress			8/31/2012 12:24:24 AM					
Quinones, Paul	Monthly - Chaparral ES A-16 Exh Fan (Semi Annual) - Refer to PM schedule details.								
Margret Villalobos									
100182					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:11 AM					
Quinones, Paul	Yearly - Chaparral ES A-13 A/C Wall Mount Yearly - Refer to PM schedule details.								
Margret Villalobos									
Count: 55 Work Orders		Avg. Age of WO's 52		Total for Chaparral ES			0	\$0.00	

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral HS								
96629		Classroom			12/14/2012		150		\$0.00	
Medium	Work In Progress			12/14/2012 10:02:17						
Lozoya, Manny		We need a new master key for our custodian. He is having trouble opening some doors. The key might be worn out or bent. Please replace. (Mireya Meza)								
<u>Mireya Meza</u>										
100887					4/12/2013		31		\$0.00	
Medium	Work In Progress			4/12/2013 3:35:57 PM						
Lozoya, Manny		Need to replace locks on all outside electrical panels students can still open them and turn off power.								
<u>Alfredo Ortiz</u>										
90843					8/6/2012		280		\$0.00	
Medium	Work In Progress			8/6/2012 11:26:25 AM						
Lozoya, Manny		We need the following keys made for CHS. Room A-108, #86 (6), light keys (10), key to staff room in library, key for trophy case in cafeteria and overhead in Q building.								
<u>Mireya Meza</u>										
98981					2/27/2013		75		\$0.00	
Medium	Work In Progress			2/27/2013 4:44:17 PM						
Appelzoller, Fred		Install utility sink in athletic training room in gym so that we are compliant with health department. (Mr. Beets)				Route to Fred asp reassignment 4/2/13				
<u>Mireya Meza</u>										
101670					5/5/2013	5/8/2013	8		\$0.00	
Medium	Work In Progress			5/5/2013 12:23:59 AM						
Ortiz, Alfredo		Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
101872		Roof			5/7/2013		6		\$0.00	
Medium	Work In Progress			5/7/2013 3:21:51 PM						
Solis, Lorenzo		Need to fabricate sheet metal caps for gutters to keep sand out of A/C units.								
<u>Alfredo Ortiz</u>										
100796		Cafeteria			4/10/2013		33		\$0.00	
Medium	Work In Progress			4/10/2013 3:23:47 PM						
Solis, Lorenzo		Having trouble with A/C unit in kitchen too hot.								
<u>Alfredo Ortiz</u>										
99025					2/28/2013		74		\$0.00	
Medium	Work In Progress			2/28/2013 8:39:02 AM						
Vallejo, Albert		I need 3 GFI outlets installed in athletic training room in gym. (Mr. Beets)				Route to Albert asp reassignment 4/2/13				
<u>Mireya Meza</u>										
5/13/2013 12:30:58 PM										

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
101057		Athletic Field			4/18/2013		25		\$0.00
Medium	Work In Progress			4/18/2013 7:41:05 AM					
Ontiveros, Guadalupe		buster pump needs to be replaced for more water pressure.							
<u>Guadalupe Ontiveros</u>									
99795					3/17/2013		57		\$0.00
Medium	Work In Progress			3/17/2013 12:19:59 AM					
Valdez, Pedro		Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
96668					12/16/2012		148		\$0.00
Medium	Work In Progress			12/16/2012 12:16:10					
Valdez, Pedro		Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
98589					2/15/2013		87		\$0.00
Medium	Work In Progress			2/15/2013 3:59:52 PM					
Valdez, Pedro		Sofia Payan is requesting dead plants be removed and plant differant plants infront of health Building.							
<u>Alfredo Ortiz</u>									
101751					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:32 AM					
Apodaca, Mario		Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
101325					4/25/2013		18		\$0.00
Medium	Work In Progress			4/25/2013 3:22:12 PM					
Ortiz, Alfredo		Need to pull weeds, pick up trsh and remove sand from sidewalks.							
<u>Alfredo Ortiz</u>									
100305					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:59 AM					
Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump Engine - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
101857		Hallway/Corridor			5/7/2013		6		\$0.00
Medium	Work In Progress			5/7/2013 8:45:46 AM					
Ortiz, Alfredo		Need to replace filters on A/C units in hallways.							
Alfredo Ortiz									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
96586		Parking Lot			12/13/2012		151		\$0.00
Medium	Work In Progress			12/13/2012 11:43:18					
Ortiz, Alfredo	We need several signs to be placed at different locations of the school. Please see Lupe Quinones for signs.								
<u>Mireya Meza</u>									
101592					5/2/2013		11		\$0.00
Medium	Work In Progress			5/2/2013 9:00:16 AM					
Ortiz, Alfredo	Need to replace missing screws and tighten all loose screws on picnic tables out side cafeteria.								
<u>Alfredo Ortiz</u>									
101716					5/5/2013	6/5/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:18 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101717					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:19 AM					
Ortiz, Alfredo	Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101706					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:14 AM					
Ortiz, Alfredo	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101806					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:57 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96443	Pre-K				12/10/2012		154		\$0.00
Medium	Work In Progress			12/10/2012 3:07:05 PM					
Gonzalez, Salvador	Need to repaid gate door, lach broken.								
<u>Alfredo Ortiz</u>									
101001	Pre-K	Classroom			4/16/2013		27		\$0.00
Medium	Work In Progress			4/16/2013 3:49:42 PM					
Solis, Lorenzo	Having trouble with A/C unit in room 103								
Alfredo Ortiz									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
97305	A-Wing	Classroom			1/15/2013		118		\$0.00
Medium	Work In Progress			1/15/2013 8:54:25 AM					
Lozoya, Manny	Mrs. Vega's door is hard to open with key. She is located in the counselors area in front office.								
<u>Mireya Meza</u>									
98979	A-Wing	Classroom			2/27/2013		75		\$0.00
Medium	Work In Progress			2/27/2013 4:40:56 PM					
Lozoya, Manny	Replace metal shelves with cabinets like in athletic training room in field house with locks. (Mr. Beets)								
<u>Mireya Meza</u>									
101491	A-Wing	Hallway/Corridor			4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 2:25:58 PM					
Ortiz, Alfredo	Need to replace ballast and light bulbs around the school outside walls.								
<u>Alfredo Ortiz</u>									
101596	A-Wing	Hallway/Corridor			5/2/2013		11		\$0.00
Medium	Work In Progress			5/2/2013 11:23:08 AM					
Lozoya, Manny	Need to replace door sweep around school campus.								
<u>Alfredo Ortiz</u>									
99919	A-Wing	Athletic Field			3/20/2013		54		\$0.00
Medium	Work In Progress			3/20/2013 10:30:59 AM					
Ontiveros, Guadalupe	When bleachers were moved from soccer fields to softball fields they were damaged. Could we replaced the damaged benches as this is a potential danger to students and public. (Sofia Payen)								
<u>Mireya Meza</u>									
100599	A-Wing				4/5/2013		38		\$0.00
Medium	Work In Progress			4/5/2013 3:32:35 PM					
Ortiz, Alfredo	Need to remove sand from roof-top.								
<u>Alfredo Ortiz</u>									
98147	A-Wing	Athletic Field			2/4/2013		98		\$0.00
Medium	Work In Progress			2/4/2013 10:26:26 AM					
Valdez, Pedro	The softball outfield fence on the left side needs to be fixed. It is lifted and balls go right under it. (Coach E. Guerrero)								
<u>Mireya Meza</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
98943	A-Wing	Hallway/Corridor			2/27/2013		75		\$0.00
Medium	Work In Progress			2/27/2013 1:37:32 PM					
Lozoya, Manny	Need to replace door exit device, Won't open with key. Exit door A-wing between A105 and A106. Also one in Cafeteria.								
<u>Alfredo Ortiz</u>									
101157	A-Wing	Classroom			4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 10:27:46 AM					
Ortiz, Alfredo	Need to replace blower motor on roof A/C unit. Room A-105.								
<u>Alfredo Ortiz</u>									
96529	A-Wing	Hallway/Corridor			12/12/2012		152		\$0.00
Medium	Work In Progress			12/12/2012 8:57:47 AM					
Lozoya, Manny	Outer door lock will not open with key. Door is 3rd outer door from nurse's office, between CAP class and ISS class. (Ms. Lopez)								
<u>Mireya Meza</u>									
99866	A-Wing	Classroom			3/19/2013		55		\$0.00
Medium	Work In Progress			3/19/2013 2:39:49 PM					
Lozoya, Manny	Need a replacement CH key for Jose Fernandez. Please pick up broken key and deliver new one to Mireya Meza.								
<u>Mireya Meza</u>									
99400	A-Wing	Library			3/6/2013		68		\$0.00
Medium	Work In Progress			3/6/2013 10:59:01 AM					
Lozoya, Manny	Need key for the security bar in main library door. (Ms. Mays)								
<u>Mireya Meza</u>									
101093	A-Wing	Hallway/Corridor			4/18/2013		25		\$0.00
Medium	Work In Progress			4/18/2013 3:56:25 PM					
Lozoya, Manny	Out-side door cylinder broken next to ISS classroom. Can,t open door with key.								
<u>Alfredo Ortiz</u>									
96907	A-Wing	Cafeteria			1/7/2013		126		\$0.00
Medium	Work In Progress			1/7/2013 8:42:27 AM					
Lozoya, Manny	Cafeteria doors lach don't work 3 doors.								
<u>Alfredo Ortiz</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
100972	A-Wing	Office			4/16/2013		27		\$0.00
Medium	Work In Progress			4/16/2013 11:05:51 AM					
Lozoya, Manny	The front door that leads into the main office (reception area) does not close correctly and we are unable to lock it. We are having students come into the office after working hours and so we need this fixed as soon as possible. (security)								
<u>Mireya Meza</u>									
97472	A-Wing	Office			1/17/2013		116		\$0.00
Medium	Work In Progress			1/17/2013 3:52:19 PM					
Lozoya, Manny	We need a CHS key for our permanent security guard. (Mireya Meza)		1/23/13 - ASP CHUY, CHECK STATUS ON KEY. ASP JESSIE/CHUY, NEED 2 KEYS, ASP MIREYA - MANNY ISSUED 2 KEYS TO HER.						
<u>Mireya Meza</u>									
101590	A-Wing	Office			5/2/2013		11		\$0.00
Medium	Work In Progress			5/2/2013 8:38:27 AM					
Lozoya, Manny	The fence doors on the west side closest to DACC branch need a longer chain. (Johnny Valdez)								
<u>Mireya Meza</u>									
101553	A-Wing	Hallway/Corridor			5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 10:23:02 AM					
Appelzoller, Fred	Need to raise the vent pipes on roof-top. The drain pipe is to close to A/C units.								
<u>Alfredo Ortiz</u>									
99692	A-Wing	Cafeteria			3/14/2013		60		\$0.00
Medium	Work In Progress			3/14/2013 8:45:49 AM					
Ortiz, Alfredo	Need to paint all metal doors, window seals and iron gates.								
<u>Alfredo Ortiz</u>									
99986	B-Wing	Classroom			3/21/2013		53		\$0.00
Medium	Work In Progress			3/21/2013 2:06:14 PM					
Lozoya, Manny	Need to make key for cabinets in store room in Science room B-3.								
<u>Alfredo Ortiz</u>									
99765	C-Wing	Classroom			3/15/2013		59		\$0.00
Medium	Work In Progress			3/15/2013 1:47:17 PM					
Solis, Lorenzo	Need to repair GEO thermal water leak in C-6 A/C unit.								
<u>Alfredo Ortiz</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
99766	D-Wing	Classroom			3/15/2013		59		\$0.00
Medium	Work In Progress			3/15/2013 1:50:04 PM					
Solis, Lorenzo	Need to repair GEO Thermal water leak in D-Sped heating unit.								
<u>Alfredo Ortiz</u>									
101578	F-Wing	Restroom (Boys)			5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 3:46:05 PM					
Ortiz, Alfredo	Need to paint over graffiti in restrooms.								
<u>Alfredo Ortiz</u>									
102067	F-Wing	Custodial			5/13/2013		0		\$0.00
Medium	Work In Progress			5/13/2013 8:22:07 AM					
Appelzoller, Fred	Need to replace Hot water circulating pump in F-wing leaking water.								
<u>Alfredo Ortiz</u>									
100674	G-Wing	Classroom			4/8/2013		35		\$0.00
Medium	Work In Progress			4/8/2013 12:11:31 PM					
Solis, Lorenzo	Room G5 has been very hot for the past few days. Please lower temperature. (Mr. C. Sanchez)								
<u>Mireya Meza</u>									
99764	G-Wing	Classroom			3/15/2013		59		\$0.00
Medium	Work In Progress			3/15/2013 1:44:20 PM					
Solis, Lorenzo	Need to replace two Terminator Balancing Valves for G-5 A/C unit.								
<u>Alfredo Ortiz</u>									
99405	Q-Wing	Classroom			3/6/2013		68		\$0.00
Medium	Work In Progress			3/6/2013 1:09:40 PM					
Ortiz, Alfredo	Need to paint and seal Q-4 welding shop Floor. Coaches use that room. to much dust.								
<u>Alfredo Ortiz</u>									
98453	Q-Wing	Classroom			2/13/2013		89		\$0.00
Medium	Work In Progress			2/13/2013 12:09:49 PM					
Vallejo, Albert	Need to install new air compresor for mechanic shop. Need new electrical set up.				Route to Albert asp reassignment 4/2/13				
<u>Alfredo Ortiz</u>									
100944	Q-Wing	Hallway/Corridor			4/15/2013		28		\$0.00
Medium	Work In Progress			4/15/2013 3:43:20 PM					
Ortiz, Alfredo	Need to secure locker with screw and nuts.								
<u>Alfredo Ortiz</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
101944	R-Wing				5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 3:52:59 PM					
Gonzalez, Salvador	please cable up lockers between boys and girls restroom on main corridor. thank you								
<u>Michael Munoz</u>									
94898	R-Wing	Classroom			11/1/2012		193		\$0.00
Medium	Work In Progress			11/1/2012 11:59:27 AM					
Lozoya, Manny	Door handle to storeroom in R1 has broken. Needs to be replaced. (Mr. Gabaldon)								
<u>Mireya Meza</u>									
101109	Field House	Athletic Field			4/19/2013		24		\$0.00
Medium	Work In Progress			4/19/2013 10:26:46 AM					
Ontiveros, Guadalupe	Would like to have a canopy set up for entrance of softball and baseball games. Area to be used for ticket sales and concessions. Maybe some cement to be poured or/and permanent canopy. (Ms. Ulibarri)								
<u>Mireya Meza</u>									
99584	Field House	Athletic Field			3/12/2013		62		\$0.00
Medium	Work In Progress	Lupe Ontiveros		3/12/2013 10:15:18 AM					
Ontiveros, Guadalupe	Please pickup the field windscreens from the Warehouse for:								
	CHS Softball - (install windscreens for softball field)								
	CHS Baseball - (install windscreens for baseball field)								
	To be installed on a school to school basis.								
<u>Terry Alvarado</u>									
89726	Field House	Athletic Field			7/10/2012		307		\$0.00
Medium	Work In Progress			7/10/2012 4:23:59 PM					
Valdez, Pedro	We need 8 sets of tires attached to the soccer goals to make them mobile.								
<u>Mireya Meza</u>									
99936	Field House	Dressing Room			3/20/2013		54		\$0.00
Medium	Work In Progress			3/20/2013 2:31:13 PM					
Lozoya, Manny	The outside door to girls locker room in the field house is very loose. Please adjust. (Coach Fernie Mendoza)								
<u>Mireya Meza</u>									
101901	Field House	Dressing Room			5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 8:02:12 AM					
Lozoya, Manny	The key hole on the girls dressing room in the field house is falling (outside door). Please repair ASAP. (Mr. Orozco)								
<u>Mireya Meza</u>									
5/13/2013 12:30:58 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral HS									
93777	Field House	Athletic Field			10/3/2012		222		\$0.00
Medium	Work In Progress				10/3/2012 7:29:03 AM				
Gonzalez, Salvador	Please put permanent shade in soccer fields. (Arnold Orozco)								
<u>Mireya Meza</u>									
101593	Field House	Dressing Room			5/2/2013		11		\$0.00
Medium	Work In Progress				5/2/2013 9:11:11 AM				
Vallejo, Albert	Need to run new electrical wires to install new thermostat at field house for all the A/C units.								
<u>Alfredo Ortiz</u>									
100837	Field House	Parking Lot			4/11/2013		32		\$0.00
Medium	Work In Progress				4/11/2013 12:30:59 PM				
Lozoya, Manny	Please replace the lock that is on the east side gate going into the football parking lot to open with key CH 86. The lock is very hard to open and close. (Mr. Aguilar)								
<u>Mireya Meza</u>									
101922	Field House	Dressing Room			5/8/2013		5		\$0.00
Medium	Work In Progress				5/8/2013 2:33:07 PM				
Lozoya, Manny	Need to repair door lock, trouble opning with key.								
<u>Alfredo Ortiz</u>									
98978	Field House	Athletic Field			2/27/2013		75		\$0.00
Medium	Work In Progress				2/27/2013 4:36:22 PM				
Flores, Pete	Need 2 batteries for the athletic training gator. Might need 8 now since other 6 do not charge at all. (Mr. Beets)								
<u>Mireya Meza</u>									
100795	H-Wing	Dressing Room			4/10/2013		33		\$0.00
Medium	Work In Progress				4/10/2013 3:21:36 PM				
Appelzoller, Fred	Need to repair water faucet wash bin in boys locker room won't stop running.								
<u>Alfredo Ortiz</u>									
101969	H-Wing	Auditorium			5/9/2013		4		\$0.00
Medium	Work In Progress				5/9/2013 1:43:49 PM				
Ortiz, Alfredo	Please replace rim on main basket on the main gym floor. All baskets will be in use for the basketball camp to be held June 4-7. (Coach Hernandez)								
<u>Mireya Meza</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral HS									
101924	H-Wing	Gym			5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 2:48:15 PM					
Ortiz, Alfredo	Need to replace two A/C motors one in girls dressing room and one for consetion stan in GYM.								
<u>Alfredo Ortiz</u>									
99856	H-Wing	Gym			3/19/2013		55		\$0.00
Medium	Work In Progress			3/19/2013 10:54:39 AM					
Ortiz, Alfredo	Need to replace Isolater Vibration on both Air Handlers, Evaporative Coolers for GYM.								
<u>Alfredo Ortiz</u>									
101186	H-Wing	Gym			4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 3:59:28 PM					
Ortiz, Alfredo	Need to replace submersible pumps on airhandlers A/C units								
<u>Alfredo Ortiz</u>									
98980	H-Wing	Classroom			2/27/2013		75		\$0.00
Medium	Work In Progress			2/27/2013 4:42:47 PM					
Munoz, Michael	Expand athletic training room in gym by knocking down north wall and building larger athletic training room. Unable to do complete therapies on injured athletes. (Mr. Beets)								
<u>Mireya Meza</u>									
101784					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:46 AM					
Orozco, Daniel	Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100387					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:32 AM					
Munoz, Michael	Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101105		Pump House			4/19/2013		24		\$0.00
Medium	Work In Progress			4/19/2013 8:55:45 AM					
Ortiz, Alfredo	The Controller panal screen in the fire pump room is blank and will not respond replaced panal battery and reset still blank.								
<u>Alfredo Ortiz</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
99917					3/20/2013		-239		\$0.00
Medium	Work In Progress			3/20/2013 9:51:13 AM		7/24/2012			
Estrada, Jesus	NEED GYM FLOOR TO BE RE-FINISHED (APPROX. L - 106' X W - 101')								
Jesus Estrada									
99080					3/1/2013		73		\$0.00
Medium	Work In Progress			3/1/2013 12:24:47 PM					
Carbajal, Jimmy	Advance terra 3700b auto sweeper batteries do not take charge.								
Jesus Urquidi									
99912					3/20/2013		54		\$0.00
Medium	Work In Progress			3/20/2013 9:39:11 AM					
Carbajal, Jimmy	roto sr 100a00304 needs plug								
Jesus Urquidi									
101559					5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 1:03:58 PM					
Carrasco, Danny	Please bring large scissor-lift to complete work order #98453. Deliver to Auto shop.								
Albert Vallejo									
101548					5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 9:29:56 AM					
Carbajal, Jimmy	adfinity 20d auto scrubber pad holder broke.sr 3510122902068								
Jesus Urquidi									
90833					8/6/2012		280		\$0.00
Medium	Work In Progress			8/6/2012 10:03:59 AM					
Gonzalez, Salvador	Need to weld Soccer Goals								
Guadalupe Ontiveros									
96587		Parking Lot			12/13/2012		151		\$0.00
Medium	Work In Progress			12/13/2012 11:46:18					
Gonzalez, Salvador	I also need a metal stop bar that comes from the end of the fence that also includes a seperate pole so that driving access can be denied because the students and parents are cutting off the busses as they are driving off. Please see Lupe Quinones for location.								
Mireya Meza									
101923		Parking Lot			5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 2:41:33 PM					
Gonzalez, Salvador	Need to fix gate. Gate door hard to open dragging the floor. Can't adjust gate welded to poll.								
Alfredo Ortiz									
5/13/2013 12:30:58 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: Chaparral HS										
102024					5/10/2013		3		\$0.00	
Medium	Work In Progress			5/10/2013 2:20:04 PM						
Orozco, Daniel	DISHES GETTING STUCK WHEN RUNNING THROUGH DISHWASHER. SNP MANAGER JUANITA M. 824.4461									
<hr/>										
Maritza Gonzalez		Classroom			3/12/2013		62		\$0.00	
99580	Medium	Work In Progress		3/12/2013 8:54:07 AM						
Gallegos, Rafael	Attention to Mr. Gallegos the heaters are turning on to late because of the time change. Teachers are complaining the classrooms are to cold.									
<hr/>										
Alfredo Ortiz					3/31/2013	4/21/2013	43		\$0.00	
100379	Medium	Work In Progress		3/31/2013 12:33:29 AM						
Orozco, Daniel	Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details.									
<hr/>										
Margret Villalobos					3/3/2013		71		\$0.00	
99232	Medium	Work In Progress		3/3/2013 12:26:05 AM						
Munoz, Michael	Yearly - Chaparral HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.									
<hr/>										
Margret Villalobos		Office			4/30/2013		13		\$0.00	
101465	Medium	Work In Progress		4/30/2013 8:09:57 AM						
Briones, Enrique	Please deliver 1 box for PO # 121306363.									
<hr/>										
Larry Martinez					5/5/2013		8		\$0.00	
101782	Medium	Work In Progress		5/5/2013 12:24:45 AM						
Ortiz, Alfredo	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.									
<hr/>										
Margret Villalobos			Avg. Age of WO's		55		Total for Chaparral HS		0	\$0.00
Count: 88 Work Orders										

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
101780					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:44 AM					
Vallejo, Albert	Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
99231					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:05 AM					
Munoz, Michael	Yearly - Chaparral MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
101504					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 3:38:26 PM					
Orozco, Daniel	SKILLET STAYS WARM OR HOT WHEN IN THE OFF POSITION.								
Maritza Gonzalez									
95176					11/5/2012		189		\$0.00
Medium	Work In Progress			11/5/2012 2:14:02 PM					
Gonzalez, Salvador	Please fabricate ice machine stand in Athletics locker room.								
Albert Vallejo									
102077		Hallway/Corridor			5/13/2013		0		\$0.00
Medium	Work In Progress			5/13/2013 9:53:28 AM					
Lara, Ralph	puertas del#400 hallway estan caidas nose pueden serrar son las que estan parair cuarto devanda GRACIAS								
M. Carmen Perez									
100728					4/9/2013		34		\$0.00
Medium	Work In Progress			4/9/2013 11:18:52 AM					
Munoz, Michael	need new scorboard for soccer and football. old one does not work.								
Carl Sullivan									
100363					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:22 AM					
Orozco, Daniel	Monthly - Chapparal MS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
100892					4/12/2013		31		\$0.00
Medium	Work In Progress			4/12/2013 3:46:14 PM					
Estrada, Jesus	NEED SEAMS REPAIRED ON CARPET IN BAND ROOM								
Jesus Estrada									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
99091					3/1/2013		73		\$0.00
Medium	Work In Progress				3/1/2013 3:18:36 PM				
Estrada, Jesus	NEED TO INSTALL COVE BASE IN CAFETERIA								
<u>Jesus Estrada</u>									
101822	Main Building	Pool			5/6/2013		7		\$0.00
Medium	Work In Progress				5/6/2013 11:52:31 AM				
Valdez, Pedro	Please clean around the pond area. Trees, bushes, and debris. Can we get this done by May 9th?		Pedro is working on it today.						
<u>Carl Sullivan</u>									
101168	Main Building	Classroom			4/22/2013		21		\$0.00
Medium	Work In Progress	407			4/22/2013 2:52:27 PM				
Lozoya, Manny	Door slams. Handle does not work								
<u>Gidget Mora</u>									
93237	Main Building	Classroom			9/25/2012		230		\$0.00
Medium	Work In Progress	308			9/25/2012 3:11:29 PM				
Lozoya, Manny	Teacher would like locks put on cabinets								
<u>Gidget Mora</u>									
101217	Main Building	Classroom			4/23/2013		20		\$0.00
Medium	Work In Progress	308			4/23/2013 1:56:34 PM				
Lozoya, Manny	Classroom door is extremely difficult to lock								
<u>Gidget Mora</u>									
99028	Main Building				2/28/2013		74		\$0.00
Medium	Work In Progress				2/28/2013 10:03:07 AM				
Lozoya, Manny	please make key for 405B								
<u>Gidget Mora</u>									
99030	Main Building				2/28/2013		74		\$0.00
Medium	Work In Progress	Security			2/28/2013 10:04:31 AM				
Lozoya, Manny	Please fix lock on security door								
<u>Gidget Mora</u>									
101903	Main Building	Restroom (Boys)			5/8/2013		5		\$0.00
Medium	Work In Progress	100-200 Hallway			5/8/2013 8:06:54 AM				
Appelzoller, Fred	Remove and replace fixtures in two restrooms for remodeling. (includes two urinals and two commodes per restroom)								
Albert Vallejo									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

101170 Main Building 4/22/2013 21 \$0.00

Medium Work In Progress Foyer 4/22/2013 3:00:12 PM

Vallejo, Albert Please paint 6inch blue strip on the wall above the knights of excellence bulletin board (in foyer) and place the new letters on the wall. Check with Mr. Sullivan or Ms. Muela if you have any questions

Gidget Mora

100714 Main Building Classroom 4/9/2013 34 \$0.00

Medium Work In Progress p-14 4/9/2013 8:41:41 AM

Estrada, Jesus Floor tile detached. please repair

Gidget Mora

101551 Main Building Classroom 5/1/2013 12 \$0.00

Medium Work In Progress 5/1/2013 9:45:44 AM

Lozoya, Manny puerta de banda esta caida 400/HALLWAY senesecita arreglar GRACIAS

M. Carmen Perez

101173 Main Building Gym 4/22/2013 21 \$0.00

Medium Work In Progress girls locker room 4/22/2013 3:21:24 PM

Lozoya, Manny The doors on the restroom on the restroom stalls are broken or non existent. Please repair and replace

Gidget Mora

101415 Main Building Classroom 4/29/2013 14 \$0.00

Medium Work In Progress 407 4/29/2013 2:37:02 PM

Lozoya, Manny Door slams really hard. Please repair

Gidget Mora

101902 Main Building Restroom (Boys) 5/8/2013 5 \$0.00

Medium Work In Progress 100-200 Hall 5/8/2013 8:03:56 AM

Vallejo, Albert (Summer Project) Remove partitions, tile and drywall. Install plywood and FRP panel, replace fixtures and install new partitions.

Albert Vallejo

101472 Main Building Classroom 4/30/2013 13 \$0.00

Medium Work In Progress 303 4/30/2013 9:46:45 AM

Vallejo, Albert A/C switch is broken

Gidget Mora

101555 Main Building Classroom 5/1/2013 12 \$0.00

Medium Work In Progress 103 5/1/2013 10:27:53 AM

Vallejo, Albert Air conditioner does not work. Does not cool

Gidget Mora

5/13/2013 12:30:58 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
101859	Main Building	Gym			5/7/2013		6		\$0.00
Medium	Work In Progress				5/7/2013 8:59:24 AM				
Vallejo, Albert	Pull up bar frame needs to be re-attached to the wall. frame bar is located in the storage in the gym.								
<u>Gidget Mora</u>									
101861	Main Building	Gym			5/7/2013		6		\$0.00
Medium	Work In Progress				5/7/2013 9:00:50 AM				
Vallejo, Albert	Southeast backboard padding needs to be replaced. Padding is located in storage inside the gym.								
<u>Gidget Mora</u>									
99916					3/20/2013		-245		\$0.00
Medium	Work In Progress				3/20/2013 9:49:59 AM	7/18/2012			
Estrada, Jesus	NEED GYM FLOORS TO BE RE-FINISHED (APPROX. L - 100' X W - 90') TO BE								
<u>Jesus Estrada</u>									
101789					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:48 AM				
Orozco, Daniel	Monthly - Chaparral MS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101858					5/7/2013		6		\$0.00
Medium	Work In Progress				5/7/2013 8:52:34 AM				
Quinones, Paul	ORDER A/C MOTOR BELTS FOR RESTOCK								
<u>Paul Quinones</u>									
100533					4/4/2013		39		\$0.00
Medium	Work In Progress				4/4/2013 11:46:31 AM				
Vallejo, Albert	Need to replace excavating tools that have broken over time.								
<u>Albert Vallejo</u>									
101482					4/30/2013		13		\$0.00
Medium	Work In Progress				4/30/2013 10:50:28 AM				
Vallejo, Albert	Install hose bib in planter area of front entrance.								
<u>Albert Vallejo</u>									
101712					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:17 AM				
Vallejo, Albert	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
101713					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:17 AM					
Vallejo, Albert	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101714					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:17 AM					
Vallejo, Albert	Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101715					5/5/2013	6/5/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:18 AM					
Vallejo, Albert	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92678					9/11/2012		244		\$0.00
Medium	Work In Progress			9/11/2012 11:27:08 AM					
Apodaca, Mario	I would like to have Mario come out to help me work on the irrigation booster pump.								
<u>Albert Vallejo</u>									
99760					3/15/2013		59		\$0.00
Medium	Work In Progress			3/15/2013 12:14:45 PM					
Ontiveros, Guadalupe	Need to repair vandalized sprinklers in front lawn area.								
<u>Albert Vallejo</u>									
101018		Custodial			4/17/2013		26		\$0.00
Medium	Work In Progress			4/17/2013 9:30:15 AM					
Carbajal, Jimmy	i need a wide area vacuum for band room and library THANK YOU								
<u>M. Carmen Perez</u>									
101536					5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 8:01:58 AM					
Ontiveros, Guadalupe	Install bubblers for new trees in entrance area.								
<u>Albert Vallejo</u>									
99679		Athletic Field			3/13/2013		61		\$0.00
Medium	Work In Progress			3/13/2013 4:15:00 PM					
Ontiveros, Guadalupe	please connect and add sprinklers to east and west side of football field. thank you								
<u>Michael Munoz</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
101677					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:02 AM					
Vallejo, Albert	Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
102076		Classroom			5/13/2013		0		\$0.00
Medium	Work In Progress			5/13/2013 9:46:44 AM					
Vallejo, Albert	en el cuarto #303 senesecita areglar el apagador del aire acondicionado estan alambres de fuera GRACIAS								
<u>M. Carmen Perez</u>									
99393					3/6/2013		68		\$0.00
Medium	Work In Progress			3/6/2013 8:14:58 AM					
Vallejo, Albert	Replace HID fixtures for parking lot.								
<u>Albert Vallejo</u>									
99538					3/11/2013		63		\$0.00
Medium	Work In Progress			3/11/2013 10:12:04 AM					
Solis, Lorenzo	Circulation pump for boiler system has a substantial leak.					Route to Fred asp reassignment 4/2/13 4/18/13 - Route to L. Solis asp Fred			
<u>Albert Vallejo</u>									
101900		Computer Lab			5/8/2013		5		\$0.00
Medium	Work In Progress	207-208		5/8/2013 8:00:04 AM					
Vallejo, Albert	(Summer Project) Paint computer labs.								
<u>Albert Vallejo</u>									
101669					5/5/2013	5/8/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:23:58 AM					
Vallejo, Albert	Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
102079		Restroom (Boys)			5/13/2013		0		\$0.00
Medium	Work In Progress			5/13/2013 10:00:29 AM					
Appelzoller, Fred	restroom boys del#100 hallway los orinales estan tapados ya selesiso lalucha de destaparlos GRACIAS								
<u>M. Carmen Perez</u>									
102080		Restroom (Boys)			5/13/2013		0		\$0.00
Medium	Work In Progress			5/13/2013 10:06:42 AM					
Appelzoller, Fred	restroom boys #200 hallway los orinales estan tapados yaselesiso lalucha de destaparlos inosedestapoGRACIAS								
<u>M. Carmen Perez</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
102081		Restroom (Boys)			5/13/2013		0		\$0.00
Medium	Work In Progress			5/13/2013 10:10:55 AM					
Appelzoller, Fred	restroom boys #300 hallway orinales estan tapados GRACIAS								
M. Carmen Perez									
100582		Restroom (Girls)			4/5/2013		38		\$0.00
Medium	Work In Progress			4/5/2013 9:28:06 AM					
Appelzoller, Fred	senecesita areglar lavado de manos esta suelto del lobby restroom (girls) GRACIAS								
M. Carmen Perez									
101313		Restroom (Boys)			4/25/2013		18		\$0.00
Medium	Work In Progress			4/25/2013 11:59:56 AM					
Appelzoller, Fred	banos delos hombres del 300 Hallway el labado delas manos abienta el agua acia fuera icease mucha agua en el piso GRACIAS								
M. Carmen Perez									
96486					12/11/2012		153		\$0.00
Medium	Work In Progress			12/11/2012 3:21:43 PM					
Lozoya, Manny	Key to room 106 is not working properly								
Albert Vallejo									
99392					3/6/2013		68		\$0.00
Medium	Work In Progress			3/6/2013 8:03:40 AM					
Ontiveros, Guadalupe	Please install bubblers for two new trees in front of school.								
Albert Vallejo									
100206					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:21 AM					
Vallejo, Albert	Monthly - Chaparral MS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
Count: 54 Work Orders		Avg. Age of WO's 33		Total for Chaparral MS			0	\$0.00	

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
99647		Classroom			3/13/2013		61		\$0.00
Medium	Work In Progress	ROOM 1		3/13/2013 12:58:56 PM					
Ambriz, Jose	HEATING & COOLING UNIT NOT WORKING PROPERLY								
David Acosta									
99648		Classroom			3/13/2013		61		\$0.00
Medium	Work In Progress	ART ROOM		3/13/2013 1:04:38 PM					
Ambriz, Jose	JUST A REMINDER FOR A/C TO BE INSTALL SOME TIME SOON FOR PORTABLE.								
David Acosta									
100178					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:09 AM					
Aguilar, Patricio	Monthly - Desert Pride HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
100179					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:09 AM					
Aguilar, Patricio	Monthly - Desert Pride HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
93272		Portables			9/26/2012		229		\$0.00
Medium	Work In Progress			9/26/2012 9:14:50 AM					
Ontiveros, Guadalupe	please assit with the trenching for a new electrical line to the portable this friday 9-28-12.thank you								
Michael Munoz									
100233					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:31 AM					
Aguilar, Patricio	Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
101155		Parking Lot			4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 10:23:17 AM					
Ontiveros, Guadalupe	NEED TO REMOVE TWO DEAD TREES AND HAUL AWAY.								
David Acosta									
97760		Portables			1/28/2013		105		\$0.00
Medium	Work In Progress	1,2,3,4,6.		1/28/2013 10:35:12 AM					
Gonzalez, Salvador	THE STEPS & RAMPS TOO PORTABLES (ROOM 1,2,3,4,6) NEEDS TO BE SAND BLASTED OR SOME METHOD OF REMOVING RUST AND OLD CHIPPING PAINT BEFORE REPAINTING								
David Acosta									

5/13/2013 12:30:58 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
101407		Portables			4/29/2013		14		\$0.00
Medium	Work In Progress	Boxing Area		4/29/2013 11:52:05 AM					
Munoz, Michael	Mr. J.C. Fernandez has requested for a storage unit to store boxing equipment. If there is an extra unit within the district.								
<u>Yvette Cortez</u>									
101753					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:33 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100909					4/14/2013		29		\$0.00
Medium	Work In Progress			4/14/2013 12:19:48 AM					
Sanchez, Raul	Monthly - Desert Pride - Water Filters - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100331					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:09 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100332					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:09 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101718					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:19 AM					
Acosta, David	Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101719					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:19 AM					
Acosta, David	Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101400		Classroom			4/29/2013		14		\$0.00
Medium	Work In Progress	16		4/29/2013 8:35:02 AM					
Ronquillo, Ruben	ALL WINDOWS IN ROOM 16 NEED TO BE REPLACED DUE TO BREAK-IN/								
<u>Yvette Cortez</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Desert Pride							
98505					2/14/2013		88		\$0.00
Medium	Work In Progress				2/14/2013 12:21:41 AM				
Sanchez, Raul		Monthly - Desert Pride - Water Filters - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
99234					3/3/2013		71		\$0.00
Medium	Work In Progress				3/3/2013 12:26:06 AM				
Munoz, Michael		Yearly - Desert Pride HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
101772					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:41 AM				
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
Count: 19 Work Orders		Avg. Age of WO's 49			Total for Desert Pride			0	\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
101761					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:36 AM					
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101489					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 1:27:10 PM					
Lozoya, Manny	Need to replace broken screws to door closure to white doors in front main entrance.								
<u>Johnny Acuna</u>									
100536		Pool			4/4/2013		39		\$0.00
High	Work In Progress			4/4/2013 1:06:10 PM					
Munoz, Michael	please install new fence with gates by portables to prevent parents from entering campus without going thru front office								
<u>Johnny Acuna</u>									
99218					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:59 AM					
Munoz, Michael	Yearly - Desert Trail ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101272					4/24/2013		19		\$0.00
Medium	Work In Progress			4/24/2013 1:22:24 PM					
Orozco, Daniel	DRYER IS MAKING A LOUD NOISE WHEN IN USE. SNP MANAGER PAT C. 824.3822								
<u>Maritza Gonzalez</u>									
92723					9/12/2012		243		\$0.00
Medium	Work In Progress			9/12/2012 8:26:47 AM					
Orozco, Daniel	Threshold to walk-in cooler came loose again. Also, please replace thermocouple to stove's oven. (Pilot keeps turning off) thank you. SNP Manager Pat C. 824.3822								
<u>Maritza Gonzalez</u>									
101645					5/3/2013		10		\$0.00
Medium	Work In Progress			5/3/2013 9:35:39 AM					
Ronquillo, Ruben	Need to install tint to all windows in the bus lobby. Windows in frames and Door windows.								
<u>Johnny Acuna</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
101790					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:49 AM					
Orozco, Daniel	Monthly - Desert Trail Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100364					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:22 AM					
Orozco, Daniel	Monthly - Desert Trail Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101177					4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 3:47:20 PM					
Appelzoller, Fred	Room 105 - Above Teacher's desk Fire sprinkler nipple is all rusted out, needs to be replaced before it burst.								
<u>Johnny Acuna</u>									
102052					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:26 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100270					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:45 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101729					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:24 AM					
Acuna, Johnny	Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101730					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:24 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101731					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:24 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
99784					3/15/2013		59		\$0.00
Medium	Work In Progress			3/15/2013 3:53:45 PM					
Ontiveros, Guadalupe	Need assistance in removing small swell (canal) along the sidewalk next to the (playground) main building and broken cement around playground area trees with Backhoe. Will be needing primary screening to fill in area.								
<u>Johnny Acuna</u>									
100229					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:30 AM					
Acuna, Johnny	Monthly - Desert Trail Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101070					4/18/2013		25		\$0.00
Medium	Work In Progress			4/18/2013 11:07:23 AM					
Flores, Pete	need to check work truck #192. Possibly needing turne up. Truck shakes a little when driven.								
<u>Johnny Acuna</u>									
101477					4/30/2013		13		\$0.00
Medium	Work In Progress	LINE LOCATE		4/30/2013 10:38:01 AM					
Appelzoller, Fred	CHAINLINK FENCE >>SOUTHWEST SIDE OF SCHOOL / AT PORTABLES SPOT>>IN FRONT OF PORTABLES (FOR ACADEMY FENCE - SEE JOHNNY ACUNA IF YOU HAVE ANY QUESTIONS)								
<u>Michael Munoz</u>									
94098					10/12/2012		213		\$0.00
Medium	Work In Progress			10/12/2012 10:11:07					
Appelzoller, Fred	Need to replace all student restroom wash basins (Sinks) (Qty. 6)		Route to Fred asp reassignment 4/2/13						
<u>Johnny Acuna</u>									
99479					3/8/2013		66		\$0.00
Medium	Work In Progress			3/8/2013 7:43:46 AM					
Solis, Lorenzo	Need (3) Mastercool Commercial A/c units replaced at Desert Trail. Mastercool, Sidedraft, No Model # Available								
<u>Johnny Acuna</u>									
101476					4/30/2013		13		\$0.00
Medium	Work In Progress	LINE LOCATE		4/30/2013 10:36:57 AM					
Vallejo, Albert	CHAINLINK FENCE >>SOUTHWEST SIDE OF SCHOOL / AT PORTABLES SPOT>>IN FRONT OF PORTABLES (FOR ACADEMY FENCE - SEE JOHNNY ACUNA IF YOU HAVE ANY QUESTIONS)								
<u>Michael Munoz</u>									
5/13/2013 12:30:59 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Trail Intermediate

99897 3/20/2013 54 \$0.00

Medium Work In Progress 3/20/2013 7:53:14 AM

Solis, Lorenzo
Need a whole replacement of a Rooftop Exhaust fan for the NW hall Boy's and Girl's Restroom. (Bottom Base size of the old Exhaust Fan is: 22" All Around) Duct Size Approx. 21" 1/2 All Around. (Can you order a Direct Drive Exhaust Fan?)

Johnny Acuna

100193 3/31/2013 43 \$0.00

Medium Work In Progress 3/31/2013 12:32:15 AM

Acuna, Johnny
Monthly - Desert Trail ES A16(Exhst Fan)(S.Annual) - Refer to PM schedule details.

Margret Villalobos

101152 4/22/2013 21 \$0.00

Medium Work In Progress 105 4/22/2013 10:04:36 AM

Lozoya, Manny
Mr. Casares in room 105 is having trouble with file cabinets. one will not lock and the oter one will not open.

Elizabeth Hernandez

94274 10/17/2012 208 \$0.00

Medium Work In Progress 10/17/2012 3:41:51 PM

Ontiveros, Guadalupe
Coaches requesting to move baseball backstop to another location in same playground area. It is in the way. (Currently Located inside of the soccer playing area)

Johnny Acuna

96990 1/8/2013 125 \$0.00

Medium Work In Progress 1/8/2013 8:19:24 AM

Ontiveros, Guadalupe
Need Top Soil to fill in holes in playground grass area. (Safety Issue)

Johnny Acuna

101823 5/6/2013 7 \$0.00

Medium Work In Progress 5/6/2013 12:34:20 PM

Lara, Ralph
Portable #409: Teacher needs keys made for filing cabinet.

Johnny Acuna

99499 3/8/2013 66 \$0.00

Medium Work In Progress 3/8/2013 3:40:17 PM

Lara, Ralph
As per Administrator: Need to re-key doorknob core in portable #417 as the same as portable #416.

Johnny Acuna

5/13/2013 12:30:59 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
98455					2/13/2013		89		\$0.00
Medium	Work In Progress			2/13/2013 12:30:26 PM					
Ontiveros, Guadalupe	Coaches requesting to re-locate Baseball Backstop to a different location of the field.								
Johnny Acuna									
101486					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 12:37:19 PM					
Lozoya, Manny	Need to check lock to outdoor storage shed. Having trouble opening lock.								
Johnny Acuna									
101408					4/29/2013		14		\$0.00
Medium	Work In Progress			4/29/2013 11:54:59 AM					
Lozoya, Manny	Buenos dias manuel por favor de revisar las puertas el cilindro esta quebrado se nesesito remplasar gracias								
Laura Sandoval									
101545					5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 9:11:15 AM					
Lozoya, Manny	Will be needing (2) locks for gates to be installed in portables area.								
Johnny Acuna									
101546					5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 9:17:36 AM					
Lozoya, Manny	Need to fix lock to main door in the bus lobby. Having trouble opening door. Core is loose.								
Johnny Acuna									
98806					2/25/2013		77		\$0.00
Medium	Work In Progress			2/25/2013 9:33:17 AM					
Lozoya, Manny	Need to change cylinder core to principal's office to secure Testing Material.								
Johnny Acuna									
Count: 35 Work Orders			Avg. Age of WO's	49	Total for Desert Trail Intermediate			0	\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
100729		Office			4/9/2013		34		\$0.00
Medium	Work In Progress	Nurse's Office		4/9/2013 11:49:22 AM					
Lara, Ralph	Lock needs to be replaced in fireproof filing cabinet. (Althouse)								
<u>Guadalupe Gonzalez</u>									
101899		Hallway/Corridor			5/8/2013		5		\$0.00
Medium	Work In Progress	East side door to		5/8/2013 7:58:12 AM					
Lara, Ralph	Teacher's keys don't open door on the East side of Lower Grade Level. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
99018					2/28/2013	3/31/2013	74		\$0.00
Medium	Work In Progress			2/28/2013 12:28:34 AM					
Ortiz, Ruben	Yearly - Desert View ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100918		Office			4/15/2013		28		\$0.00
Medium	Work In Progress	Front Entrance		4/15/2013 9:38:13 AM					
Castillo, Carlos	I meant to say the Doorbell isn't working again. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
100669					4/8/2013		35		\$0.00
Medium	Work In Progress	Outside in the		4/8/2013 8:47:08 AM					
Castillo, Carlos	Set up Electricity for the Spring Carnival by May 21st. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
101830		Restroom (Boys)			5/6/2013		7		\$0.00
Medium	Work In Progress	Lower Grade		5/6/2013 1:36:43 PM					
Ontiveros, Joe	The drainage to the Lower Grade Boys Bathroom is not working properly. It keeps getting clogged. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
96317		Classroom			12/6/2012		158		\$0.00
Medium	Work In Progress	Portable #8		12/6/2012 11:51:11 AM					
Ontiveros, Joe	Install sink in the classroom. (Gonzalez)				Route to Joe asp reassignment 4/2/13				
<u>Guadalupe Gonzalez</u>									
96939		Restroom (Girls)			1/7/2013		126		\$0.00
Medium	Work In Progress	Lower Grade		1/7/2013 2:12:25 PM					
Ontiveros, Joe	Broken toilet needs replacement. (Gonzalez)				Route to Joe asp reassignment 4/2/13				
<u>Guadalupe Gonzalez</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
101024					4/17/2013		26		\$0.00
Medium	Work In Progress			4/17/2013 11:22:48 AM					
Ontiveros, Joe	East side playground water fountain is broken need to have a new one installed. West side playground water fountain is broken need to have a new one installed.								
Ruben Ortiz									
100238					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:34 AM					
Ortiz, Ruben	Monthly - Desert View ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
101209					4/23/2013		20		\$0.00
Medium	Work In Progress			4/23/2013 10:21:42 AM					
Ontiveros, Guadalupe	In the new soccer field sprinklers valve 3 is defaulting								
Ruben Ortiz									
101210					4/23/2013		20		\$0.00
Medium	Work In Progress			4/23/2013 10:22:39 AM					
Ontiveros, Guadalupe	On the circle southwest sprinkler is not working								
Ruben Ortiz									
101211					4/23/2013		20		\$0.00
Medium	Work In Progress			4/23/2013 10:23:28 AM					
Ontiveros, Guadalupe	There is a water leak in the valves on the circle on the Westside middle								
Ruben Ortiz									
101397					4/29/2013		14		\$0.00
Medium	Work In Progress			4/29/2013 8:20:57 AM					
Ortiz, Ruben	Deliver Art Display to Chaparral Middle School on April 25, 2013 and pick up Art Display on April 29, 2013. (Ruben Ortiz)								
Guadalupe Gonzalez									
99689		Office			3/14/2013		60		\$0.00
Medium	Work In Progress	Office		3/14/2013 8:31:37 AM					
Ortiz, Ruben	Replace the lightbulbs in the office. (Gonzalez)								
Guadalupe Gonzalez									
99549					3/11/2013		63		\$0.00
Medium	Work In Progress			3/11/2013 1:56:36 PM					
Ortiz, Ruben	Picking up Bike Donation from Walmart. (R. Ortiz)								
Guadalupe Gonzalez									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
101681					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:04 AM					
Ortiz, Ruben	Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101679					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:03 AM					
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101680					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:03 AM					
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
102053					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:27 AM					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101266	Main Building	Office			4/24/2013		19		\$0.00
Medium	Work In Progress			4/24/2013 11:18:03 AM					
Lara, Ralph	File cabinet in Nurses office needs a lock on it. Thank you!								
<u>Colleen Runyan</u>									
101855	Main Building	Restroom			5/7/2013		6		\$0.00
Medium	Work In Progress			5/7/2013 8:09:59 AM					
Lara, Ralph	Because of the lack of privacy and high volume area in the Nurses office, we would appreciate an assessment of whether or not a door could be put in between the Asst. Principals office and the bathroom. Thank you, Colleen Runyan RN								
<u>Colleen Runyan</u>									
101820	Main Building	Custodial			5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 10:50:51 AM					
Carbajal, Jimmy	Hi Jimmy: That big wet dry vac scrubber machine that was brought, is not scrubbing any more. I was using it in the cafeteria and it just stopped spinning the pad and smelled like burned. If you could check it out. Thank you Jimmy								
<u>Israel Ortega</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
100365					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:23 AM					
Orozco, Daniel	Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101419					4/29/2013		14		\$0.00
Medium	Work In Progress			4/29/2013 3:09:47 PM					
Carrasco, Danny	Need 5 gals of gas for 61 truck and 8 gals of gas for 402 Mower 2 gals for 2 Stroke(Blowers, Weadearters) Thank you Ruben								
<u>Ruben Ortiz</u>									
99690		Classroom			3/14/2013		60		\$0.00
Medium	Work In Progress	Portable 4		3/14/2013 8:33:29 AM					
Gonzalez, Salvador	Repair the staircase outside of the portable. There is a gap and is dangerous. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
101791					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:49 AM					
Orozco, Daniel	Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97861		Cafeteria			1/30/2013		103		\$0.00
High	Work In Progress			1/30/2013 10:42:11 AM					
Orozco, Daniel	need to relace small stainless steal sink. chemical was used to unclog drain and as per health inspector it needs to be cleaned or relaced.								
<u>Demetrious Giovas</u>									
99219					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:59 AM					
Munoz, Michael	Yearly - Desert View ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101758					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:35 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 30 Work Orders			Avg. Age of WO's	37		Total for Desert View ES	0		\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
100378					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:28 AM					
Orozco, Daniel	Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99157					3/3/2013	3/9/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:32 AM					
Moncayo, Fernando	Monthly - GAC Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101773					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:41 AM					
Moncayo, Fernando	Monthly - GAC Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101811		Office			5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 8:03:26 AM					
Briones, Enrique	Please pick up broken equipment from GAC at Bil. Dept.								
<u>Larry Martinez</u>									
99236					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:07 AM					
Munoz, Michael	Yearly - GAC Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101792					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:50 AM					
Orozco, Daniel	Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99460					3/7/2013		67		\$0.00
Medium	Work In Progress			3/7/2013 3:26:05 PM					
Holguin, Alfredo	Becky A. - Build shelves in storage areas in finance offices (2)								
<u>Alfredo Holguin</u>									
102001					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 9:06:39 AM					
Carrasco, Danny	need to borrow the chain saw w/ a quart of bar oil								
Fernando Moncayo									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
102054					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:27 AM					
Moncayo, Fernando	Monthly - GAC Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101740					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:28 AM					
Moncayo, Fernando	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101741					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:28 AM					
Moncayo, Fernando	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101214					4/23/2013		20		\$0.00
Medium	Work In Progress			4/23/2013 1:29:32 PM					
Moncayo, Fernando	EXHAUST FAN IN DISHWASHER ROOM NOT WORKING PROPERLY.								
<u>Maritza Gonzalez</u>									
92964					9/18/2012		237		\$0.00
Medium	Work In Progress	Lucia Almeraz		9/18/2012 3:45:13 PM					
Moncayo, Fernando	ATTN: JUAN AMBRIZ PLEASE INSTALL A REGISTER IN OFFICE					2/26 -Routed to Fernando			
<u>Lucia Almeraz</u>									
94698					10/29/2012		196		\$0.00
Medium	Work In Progress			10/29/2012 9:26:05 AM					
Rodriguez, Arturo	TOILET IN RR IN FRONT OF RECEPTIONIST AREA WILL NOT FLUSH.								
<u>Maritza Gonzalez</u>									
99161					3/3/2013	3/11/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:33 AM					
Moncayo, Fernando	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99159					3/3/2013	3/11/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:32 AM					
Moncayo, Fernando	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
96829					1/6/2013	1/14/2013	127		\$0.00
Medium	Work In Progress			1/6/2013 12:24:07 AM					
Moncayo, Fernando	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101416					4/29/2013		14		\$0.00
Medium	Work In Progress	Federal		4/29/2013 2:49:41 PM					
Moncayo, Fernando	Please cover vent in office								
<u>Lucia Almeraz</u>									
101910					5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 9:25:54 AM					
Moncayo, Fernando	REPLACE BROKEN TILES IN FRONT OF MS. BROWDER AND LUCY GARCIA OFFICE.								
<u>Maritza Gonzalez</u>									
102010					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 10:22:25 AM					
Moncayo, Fernando	AC IN ROSA AND MARY TELLES OFFICE IS NOT COOLING. ALSO NEED HELP HANGING UP A BOARD.								
<u>Maritza Gonzalez</u>									
100310					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:01 AM					
Holguin, Alfredo	Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99743					3/15/2013		59		\$0.00
Medium	Work In Progress			3/15/2013 8:06:07 AM					
Munoz, Michael	need morgan for plumber and electrician for storage.								
<u>Michael Munoz</u>									
101064					4/18/2013		25		\$0.00
Medium	Work In Progress	Car#161		4/18/2013 8:52:02 AM					
Flores, Pete	Please check car#161 check engine light on								
<u>Lucia Almeraz</u>									
92932					9/18/2012		237		\$0.00
Medium	Work In Progress			9/18/2012 12:44:19 PM					
Ontiveros, Joe	MAIN WATER LINE LEAKING IN C-WING.		Route to Joe asp reassignment 4/2/13						
<u>Maritza Gonzalez</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
101322					4/25/2013		18		\$0.00
Medium	Work In Progress			4/25/2013 3:16:22 PM					
Castillo, Carlos	ARTURO REQUESTING LIGHT BULBS FOR MAIN ENTRANCE.								
<u>Maritza Gonzalez</u>									
101258					4/24/2013		19		\$0.00
Medium	Work In Progress			4/24/2013 8:21:20 AM					
Castillo, Carlos	As per Calixto, if possible extend emergency power to his office so he can keep operating during power outage.								
<u>Calixto Arzaga</u>									
101906		Electrical Room			5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 8:39:12 AM					
Castillo, Carlos	Need to order fuses for main electrical room to have in stock .								
<u>Carlos Castillo</u>									
101616		Electrical Room			5/2/2013		11		\$0.00
Medium	Work In Progress			5/2/2013 3:44:44 PM					
Castillo, Carlos	Need to order shelving and storage bins for morgan that will be placed at the Gac for maintenance dept.								
<u>Carlos Castillo</u>									
100186					3/31/2013	4/16/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:12 AM					
Ambriz, Juan	Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
102012					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 11:08:47 AM					
Ambriz, Jose	WALL UNIT IN ROSA APODACA AND MARY TELLES OFFICE IS NOT COOLING. AS PER FERNANDO IT NEEDS TO BE REPLACED.								
<u>Maritza Gonzalez</u>									
102014					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 11:47:14 AM					
Ambriz, Jose	Sally Sepulveda's office the unit is making alot of noise.								
<u>Richard Chavez</u>									
99188					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:45 AM					
Moncayo, Fernando	Yearly - GAC A-10 Heat Pump Cooling Only Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

5/13/2013 12:30:59 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
95653					11/19/2012		175		\$0.00
High	Work In Progress			11/19/2012 7:30:10 AM					
Ambriz, Jose	need to rewire liebert cooling system in tech room to have only 2 compressors functioning, install 4 contactors, new switches, intelligent board, programming etc . this system is to oversized for room and is causing problems as designed.								
<u>Michael Munoz</u>									
101194					4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 4:22:11 PM					
Ambriz, Jose	NEED TO CHECK THREE A/C UNITS IN TECHNOLOGY OFFICE. NOT WORKING CORRECTLY								
<u>Cora Ramirez</u>									
100908					4/14/2013		29		\$0.00
Medium	Work In Progress			4/14/2013 12:19:47 AM					
Ambriz, Jose	Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96987					1/8/2013		125		\$0.00
Medium	Work In Progress			1/8/2013 8:12:56 AM					
Ambriz, Jose	Server Room - Unit is down								
<u>Michael Munoz</u>									
99683					3/14/2013		60		\$0.00
Medium	Work In Progress			3/14/2013 12:19:34 AM					
Ambriz, Jose	Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 37 Work Orders			Avg. Age of WO's	54		Total for GAC	0		\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: GAC - Pre-K									
98516					2/14/2013		88		\$0.00
Medium	Work In Progress			2/14/2013 11:34:39 AM					
Ontiveros, Guadalupe	As per our conversation, please meet with Ms. Belegama for location and types of shade trees that are in need. Thank you								
Michael Munoz									
101488					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 1:04:14 PM					
Moncayo, Fernando	ROOM 202-CABINETS DOORS ARE NOT CLOSING RIGHT. BACK DOOR-LOCK GETTING STUCK STOVE (TOY)-NEEDS SCREWS ON DOOR.								
Maritza Gonzalez									
101492					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 2:35:52 PM					
Moncayo, Fernando	CAFETERIA WORK ROOM- LIGHT BULBS NEED TO BE REPLACED ON 2 OF THE CEILING LIGHTS.								
Maritza Gonzalez									
Count: 3 Work Orders			Avg. Age of WO's	38		Total for GAC - Pre-K	0		\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden ES									
100654					4/7/2013	4/23/2013	36		\$0.00
Medium	Work In Progress			4/7/2013 12:19:07 AM					
Medina, Eric	Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.		Routed to Eric asp reassignment 4/22/13						
<u>Margret Villalobos</u>									
102064					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:32 AM					
Medina, Eric	Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101678					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:02 AM					
Medina, Eric	Monthly - Gadsden ES - Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100643					4/7/2013	4/23/2013	36		\$0.00
Medium	Work In Progress			4/7/2013 12:19:00 AM					
Pinon, Jose	Monthly - QRTL BLDG INSP REPORT (GES) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101640					5/3/2013		10		\$0.00
Medium	Work In Progress			5/3/2013 8:56:49 AM					
Ontiveros, Guadalupe	Need to spruce up area for Teacher of the Year on Monday (see Mike for details)								
<u>Michael Munoz</u>									
101687					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:06 AM					
Medina, Eric	Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101704					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:13 AM					
Medina, Eric	Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101705					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:13 AM					
Medina, Eric	Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden ES

99907		Pump House			3/20/2013		54		\$0.00
Medium	Work In Progress			3/20/2013 9:30:55 AM					
Lozoya, Manny	At Gadsden Elem, a core change is needed in the pump house. Also 3 locks are needed for 3 designated areas. Please contact Jose Pinon for location of area. Should you have any questions please contact Mr. Rafael "Ralph" Gallegos at (575) 882-6921.								
<u>Dominique Esparza</u>									
101600		Custodial			5/2/2013		11		\$0.00
Medium	Work In Progress			5/2/2013 11:54:37 AM					
Lozoya, Manny	BOY RESTROOM DOOR IS BROKEN BY KITCHEN								
<u>Jose Pinion</u>									
101601		Office			5/2/2013		11		\$0.00
Medium	Work In Progress	front doors		5/2/2013 12:48:12 PM					
Lozoya, Manny	need immidiate assistance with front doors... they seem to be getting stuck and not locking properly... greatly appreciate your assitance in this matter...								
<u>Loraine Gandara</u>									
100715		Office			4/9/2013		34		\$0.00
Medium	Work In Progress	Front office main		4/9/2013 8:50:27 AM					
Lozoya, Manny	need immdiate assistance with doors... locks in the principal doors to entrance do not close properly... the key cyclinder turns instead of locking... please assist..								
<u>Loraine Gandara</u>									
97402					1/16/2013		117		\$0.00
Medium	Work In Progress	Morgan Building		1/16/2013 1:57:34 PM					
Lozoya, Manny	Asp Mike, need to key new Morgan Building the same as school site is keyed for admin to have access to it.								
<u>Michael Munoz</u>									
95947					11/29/2012		165		\$0.00
Medium	Work In Progress			11/29/2012 2:23:14 PM					
Lozoya, Manny	Need 2 gate keys. Need to check the keys out to either Hector Torres or Hector Gutierrez For more information contact Ralph Gallegos at 882-6921. Thank You.								
<u>Dominique Esparza</u>									
99967					3/21/2013		53		\$0.00
Medium	Work In Progress			3/21/2013 12:17:03 AM					
Villalobos, Margret	Monthly - Gadsden ES - Trane PM Quarterly - Refer to PM schedule details.					E-mailed Trane 3/21/13			
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden ES									
101136					4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 8:19:08 AM					
Solis, Lorenzo	SERVER ROOM TOO HOT. PLEASE CHECK A/C UNIT								
Cora Ramirez									
101399		Classroom			4/29/2013		14		\$0.00
Medium	Work In Progress	Mr. Burciaga		4/29/2013 8:27:53 AM					
Solis, Lorenzo	need assistance with air conditioner... the heater keeps turning on... thank you greatly appreciate your assistance in this matter....								
Loraine Gandara									
94633					10/26/2012		199		\$0.00
Medium	Work In Progress	outside area		10/26/2012 10:31:19					
Villalobos, David	need immediate assistance... outside where you hook up the water hoses... there seems to be alot of water drainage... water seems to be coming out even if the faucets are closed... please would greatly appreciate your assistance in this matter...		Route to David asp reassignment 4/2/13						
Loraine Gandara									
101599		Restroom (Boys)			5/2/2013		11		\$0.00
Medium	Work In Progress			5/2/2013 11:47:51 AM					
Nunez, Arturo	ROOM 106 SINK KEEPS ON RUNNING INSIDE RESTROOM								
Jose Pinion									
101912		Restroom			5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 11:21:32 AM					
Villalobos, David	room 102 the restroom sink is running all the time								
Jose Pinion									
99989		Mechanical			3/21/2013		53		\$0.00
Medium	Work In Progress			3/21/2013 3:03:12 PM					
Villalobos, David	At gadaden Elementary I need to install a new water filter housing Ford domestic water								
Mario Apodaca									
101104		Athletic Field			4/19/2013		24		\$0.00
High	Work In Progress			4/19/2013 8:20:19 AM					
Lozoya, Manny	need door to open with 7 pin.								
Guadalupe Ontiveros									
101913		Custodial			5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 11:24:39 AM					
Carbajal, Jimmy	vacumm is not working								
Jose Pinion									
5/13/2013 12:30:59 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Gadsden ES								
101783					5/5/2013	5/26/2013	8		\$0.00	
Medium	Work In Progress			5/5/2013 12:24:45 AM						
Orozco, Daniel	Monthly - Gadsden ES - Range Hood Cleaning - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
101785					5/5/2013	5/26/2013	8		\$0.00	
Medium	Work In Progress			5/5/2013 12:24:46 AM						
Orozco, Daniel	Monthly - Gadsden ES - Fire Suppression Insp - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
100916		Classroom			4/15/2013		28		\$0.00	
Medium	Work In Progress	101		4/15/2013 9:00:50 AM						
Estrada, Jesus	tile floor from bathroom wall is falling off.... need assistance with this matter thank you....									
<u>Loraine Gandara</u>										
101760					5/5/2013	5/16/2013	8		\$0.00	
Medium	Work In Progress			5/5/2013 12:24:36 AM						
Medina, Eric	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
99214					3/3/2013		71		\$0.00	
Medium	Work In Progress			3/3/2013 12:25:57 AM						
Munoz, Michael	Yearly - Gadsden ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
100922					4/15/2013		28		\$0.00	
Medium	Work In Progress			4/15/2013 10:31:02 AM						
Orozco, Daniel	SERVING LINE IS STILL LEAKING.. SNP MANAGER CUCA P. 882.3410									
<u>Maritza Gonzalez</u>										
101667					5/3/2013		10		\$0.00	
High	Work In Progress			5/3/2013 4:14:15 PM						
Gonzalez, Salvador	need to install bollards and cabling with do not enter signs in parking lot (3) please see mike for details. thank you									
<u>Michael Munoz</u>										
101862		Athletic Field			5/7/2013		6		\$0.00	
Medium	Work In Progress			5/7/2013 9:08:08 AM						
Gonzalez, Salvador	need 2 sturdy poles for volleyball nets. thank you									
<u>Michael Munoz</u>										
Count: 31 Work Orders			Avg. Age of WO's	34				Total for Gadsden ES	0	\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
102025					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 2:55:45 PM					
Briones, Enrique	Requested by Mr. Grubaugh New Library-Transfer Xerox coping machine to warehouse, copier is malfunctioning.								
Velia Alarcon									
100723					4/9/2013		34		\$0.00
Medium	Work In Progress			4/9/2013 10:55:38 AM					
Briones, Enrique	Requested by Mr. Pokluda & Mr. Grubaugh-Several items need to be removed from the Old Library and placed in storage at the District's Warehouse. Items need to be removed before the next phase of construction at Gadsden High School. The "Equipment & Furniture Transfer/Turn In Form" has already been sent to Mr. Manuel Leyva thru Inter-Department mail. SEE MR. POKLUDA FOR FURTHER INSTRUCTIONS.								
Velia Alarcon									
93175					9/24/2012		231		\$0.00
Medium	Work In Progress			9/24/2012 2:18:30 PM					
Gonzalez, Salvador	Requested by Coach Letz for Tennis Court-Please repair two of the benches on the Tennis Courts.								
Velia Alarcon									
101281		Choral			4/24/2013	6/7/2013	19		\$0.00
Medium	Work In Progress			4/24/2013 3:03:53 PM					
Gonzalez, Salvador	Need to re plumb altitude sensor into storage tank, Schedule this work for the summer and coordinate this work with Raul Sanchez and Mario Apodaca								
96148									
Medium	Work In Progress			12/2/2012 12:23:27 AM			162		\$0.00
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
97916					1/31/2013		102		\$0.00
Medium	Work In Progress			1/31/2013 12:25:34 AM					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
98126					2/3/2013		99		\$0.00
Medium	Work In Progress			2/3/2013 12:22:55 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
5/13/2013 12:30:59 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
97883					1/30/2013		103		\$0.00
Medium	Work In Progress			1/30/2013 3:07:52 PM					
Sanchez, Raul	Asp Alfredo, install 2 pump and install valves to isolate pumps.								
Alfredo Holguin									
98931					2/27/2013		75		\$0.00
Medium	Work In Progress			2/27/2013 8:38:09 AM					
Sanchez, Raul	Need to have Anthony Pump & Drilling check irrigation pump #1. Pumping gpm has gone done quite alot, casing screen may be clogged								
Raul Sanchez									
99698					3/14/2013		60		\$0.00
Medium	Work In Progress			3/14/2013 9:23:00 AM					
Sanchez, Raul	03/14/13 Need to order wastewater chemicals to control the foam in wwtp & the grease in the campus lift stations Thanks, Raul								
Raul Sanchez									
93642					9/30/2012		225		\$0.00
Medium	Work In Progress			9/30/2012 12:31:33 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
95150					11/4/2012		190		\$0.00
Medium	Work In Progress			11/4/2012 12:20:01 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
96877					1/6/2013		127		\$0.00
Medium	Work In Progress			1/6/2013 12:24:32 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
94821					10/31/2012		194		\$0.00
Medium	Work In Progress			10/31/2012 12:26:40					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
92301					9/2/2012		253		\$0.00
Medium	Work In Progress			9/2/2012 12:21:58 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
101959					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 11:12:37 AM					
Sanchez, Raul	check are prepare clean-out drain for rv dump stations (pow wow)								
Michael Munoz									
99233					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:06 AM					
Munoz, Michael	Yearly - Gadsden HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
101134		Athletic Field			4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 7:44:46 AM					
Munoz, Michael	nne to remove part of existing fence and and install gates where ada ramp and side walk poured on soccer field.								
Alfredo Holguin									
101775					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:42 AM					
Herrera, Joel	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
101793					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:50 AM					
Orozco, Daniel	Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
99439					3/7/2013		67		\$0.00
Medium	Work In Progress			3/7/2013 8:34:45 AM					
Estrada, Jesus	Requested by Mr. Martinez for Cafeteria-Need to install missing transicion on floor VCT to ceramic tiles, all around on the floor.								
Velia Alarcon									
99480					3/8/2013		66		\$0.00
Medium	Work In Progress			3/8/2013 7:58:12 AM					
Estrada, Jesus	NEED TO MEASURE AND REPLACE CERAMIC TILE TO VCT IN CAFETERIA								
Jesus Estrada									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
98513	Boys Gym	Custodial			2/14/2013		88		\$0.00
Medium	Work In Progress			2/14/2013 10:52:05 AM					
Lara, Ralph	At the boys gym at the girls locker room, the door for the custodial closet has been damaged and the latch has also been ripped off.								
<u>Joe Munoz</u>									
101921	Cafeteria (1998)	Kitchen			5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 1:42:55 PM					
Orozco, Daniel	FLOORING TO WALK IN REFRIGERATOR IS LIFTING. SNP MANAGER LYDIA M. 882.5522								
<u>Maritza Gonzalez</u>									
97699	Varsity Gym				1/25/2013		108		\$0.00
Medium	Work In Progress			1/25/2013 10:47:58 AM					
Sotelo, Enrique	Please check score boards in the V. Gym, scoreboard is turning off and on. Previously W/O #96524, did not had a location...					Route to Enrique asp reassignment 4/2/13			
<u>Guillermo Hernandez</u>									
100366					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:23 AM					
Orozco, Daniel	Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101405					4/29/2013		14		\$0.00
Medium	Work In Progress			4/29/2013 9:15:10 AM					
Lara, Ralph	Requested by Mr. Mora Rm. 403 Boy's Gym-Athletic Training Room-Allen lock on inside of door has been stripped, needs to be repaired so that I can lock the door.								
<u>Velia Alarcon</u>									
102002					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 9:34:44 AM					
Lara, Ralph	Requested by Mr. Grubaugh Rm. 728 New Library-The battery on the emergency door alarm may be dead. The alarm is not functioning.								
<u>Velia Alarcon</u>									
102003					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 9:35:52 AM					
Lara, Ralph	Requested by Ms. Howard Rm. 215 North Building-The screws are stripped on door stop.								
<u>Velia Alarcon</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

101148					4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 9:28:40 AM					

Lara, Ralph Requested by Mrs. Munoz Rm. 514 in New Trades Building-Requesting a lock guard on door.

Velia Alarcon

100481					4/3/2013		40		\$0.00
Medium	Work In Progress			4/3/2013 10:26:21 AM					

Lara, Ralph Requested by Mr. Mora Rm. 403 Boy's Gym-Athletic Training Room-Panic bar on Athletic Training Room door has a stripped allen key hole. Needs to be repaired in order to lock this door.

Velia Alarcon

100483					4/3/2013		40		\$0.00
Medium	Work In Progress			4/3/2013 10:40:39 AM					

Lara, Ralph Requested by Mr. Pokluda for Girl's Gym-Repair/replace door closure on double doors that lead from Girl's Gym to hallway in Old English Building.

Velia Alarcon

101914					5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 11:28:53 AM					

Carrasco, Danny Danny, we are going to need the fork lift and jack pallet to move equipment from the old panther hut to the new location. on 5/8/13

Guillermo Hernandez

99914					3/20/2013		-272		\$0.00
Medium	Work In Progress			3/20/2013 9:44:49 AM		6/21/2012			

Estrada, Jesus NEED 3 GYM FLOORS TO BE RE-FINISHED (BOYS - 100' X 74'; GIRLS - 91' X 50'; VARSITY - 129' X 92')

Jesus Estrada

100493	Business				4/3/2013		40		\$0.00
Medium	Work In Progress			4/3/2013 1:36:51 PM					

, please assist with the removal and installations of the sewing tables and machines in room 610, beginning 4-09-13. thank you

Michael Munoz

101626	Old English Bldg				5/2/2013		11		\$0.00
Medium	Work In Progress			5/2/2013 3:59:04 PM					

Ronquillo, Ruben Need to replace broken glass on window at Old English #137. double pane (42 1/4 X 38 3/4).

Guillermo Hernandez

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
95625	Old English Bldg				11/16/2012		178		\$0.00
High	Work In Progress				11/16/2012 10:46:22				
Lozoya, Manny	Need to replace door in Old English #141, door is hanging it is being hold by the door closer, secured door from falling down, but room needs to be secured..								
Guillermo Hernandez									
101065	North Building	Classroom			4/18/2013		25		\$0.00
Medium	Work In Progress				4/18/2013 8:53:38 AM				
Munoz, Joe	North Building – this is the current Home Ec room and the classrooms in that hallway as well as the corridor and the west end of the main corridor. In the North Building, GISD personnel will need to empty the Home Ec room, two classrooms, storage room and the copy machine room on May 24 and 28, 2013. If you have any questions please call Ralph Gallegos at 575-882-6921. Thanks.								
Rafael Gallegos									
101066	North Building	Classroom			4/18/2013		25		\$0.00
Medium	Work In Progress				4/18/2013 8:55:15 AM				
Hernandez, Guillermo	North Building – this is the current Home Ec room and the classrooms in that hallway as well as the corridor and the west end of the main corridor. In the North Building, GISD personnel will need to empty the Home Ec room, two classrooms, storage room and the copy machine room on May 24 and 28, 2013. If you have any questions please call Ralph Gallegos at 575-882-6921. Thanks.								
Rafael Gallegos									
97713	Pool Pump				1/25/2013		108		\$0.00
Medium	Work In Progress				1/25/2013 3:00:31 PM				
Lara, Ralph	Replace roll-up door with new motorized unit								
Alfredo Holguin									
99585	Grounds Shop	Athletic Field			3/12/2013		62		\$0.00
Medium	Work In Progress	Lupe Ontiveros			3/12/2013 10:20:32 AM				
Ontiveros, Guadalupe	Please pickup the windscreens for the following:								
	Softball - (install windscreens) GHS Softball								
	Baseball - (install windscreens) GHS Baseball								
	Installation will be on a school to school basis.								
Terry Alvarado									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
101597					5/2/2013		11		\$0.00
High	Work In Progress			5/2/2013 11:28:20 AM					
Villalobos, David	Need to replace angle stop for the water fountain on the second floor of the Old English. Water on the floor.								
<u>Guillermo Hernandez</u>									
101991					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 3:48:44 PM					
Villalobos, David	Need to clean sewer line for restroom #125, (Main building).								
<u>Guillermo Hernandez</u>									
102023					5/10/2013		3		\$0.00
High	Work In Progress			5/10/2013 2:06:05 PM					
Villalobos, David	Please check relief valve out side of the Administration building, there is gas odor.								
<u>Guillermo Hernandez</u>									
99640		Portables			3/13/2013		61		\$0.00
High	Work In Progress			3/13/2013 11:41:33 AM					
Villalobos, David	please check all commodes and lavatories for proper operation and secure them as well if need be. if caulking is old , remove and caulk with new one. these are the portables that were moved next to boys gum thankyou								
<u>Michael Munoz</u>									
97659					1/24/2013		109		\$0.00
Medium	Work In Progress			1/24/2013 3:24:56 PM					
Villalobos, David	Please check for gas smell outside of the boiler room for the cafeteria..		Route to David asp reassignment 4/2/13						
<u>Guillermo Hernandez</u>									
101671					5/5/2013	5/8/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:23:59 AM					
Herrera, Joel	Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92272					9/2/2012		253		\$0.00
Medium	Work In Progress			9/2/2012 12:21:46 AM					
Munoz, Michael	Monthly - Gadsden HS - Grease Trap (Culinary/Auto) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99211					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:56 AM					
Munoz, Michael	Monthly - Gadsden HS - Grease Trap (Culinary/Auto) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
5/13/2013 12:30:59 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
96524					12/12/2012		152		\$0.00
Medium	Work In Progress			12/12/2012 7:57:38 AM					
Sotelo, Enrique	Please check score board, having problems with the lights...		Route to Enrique asp reassignment 4/2/13						
Guillermo Hernandez									
100779					4/10/2013		33		\$0.00
Medium	Work In Progress			4/10/2013 10:31:09 AM					
Sotelo, Enrique	Please check lighting around Bus Turnaround, Parking Lot, and South Side of N. Bldg.								
Michael Munoz									
102017					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 12:08:03 PM					
Sotelo, Enrique	Please, as per Mike install electrical power to portable by the bus turn around, check lights and outlets. (pow-wow festivities)								
Guillermo Hernandez									
101960					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 11:14:13 AM					
Sanchez, Raul	please check bathrooms by soccer field for proper operations.(l. flush valves commodes) thank you								
Michael Munoz									
101480					4/30/2013		13		\$0.00
Medium	Work In Progress	LINE LOCATE		4/30/2013 10:45:06 AM					
Sotelo, Enrique	Academy Fence: Joe Coca (575)523-0779 NORTH SIDE OF SCHOOL AT BUS DROP OFF, 2ND ENTRANCE, GO TO WEST SIDE TO SMALL 4FT CHAINLINK FENCE/ *ADDING GATE SPOT>>>11FT RADIUS OF OPENING OF THE FENCE								
Alfredo Holguin									
99970					3/21/2013		53		\$0.00
Medium	Work In Progress			3/21/2013 8:20:59 AM					
Sotelo, Enrique	Need to replace broken light fixtures (reflectors) on the marquee on front of the school.		Route to Enrique asp reassignment 4/2/13						
Guillermo Hernandez									
99971					3/21/2013		53		\$0.00
Medium	Work In Progress			3/21/2013 8:24:25 AM					
Sotelo, Enrique	Need to install 2 missing or broken light fixtures (T8's) in the girls locker room at the Boys gym. After ceiling gets repaired.		Route to Enrique asp reassignment 4/2/13						
Guillermo Hernandez									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
99301					3/4/2013		70		\$0.00
Medium	Work In Progress			3/4/2013 12:08:06 PM					
Sotelo, Enrique		Need assistance to replace ballast in hallway of the North building.				Route to Enrique asp reassignment 4/2/13			
<u>Guillermo Hernandez</u>									
101965					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 11:36:33 AM					
Hernandez, Guillermo		Requested by Administration Team-Paint panther in front of school black. This can be done over the summer.							
<u>Velia Alarcon</u>									
95667					11/19/2012		175		\$0.00
High	Work In Progress			11/19/2012 10:06:13					
Hernandez, Guillermo		please paint all ADA logos, ramps and curbs etc to meet code requirements.thankyou				4/23/13 - Work is still in progress			
<u>Joe Munoz</u>									
97769					1/28/2013		105		\$0.00
Medium	Work In Progress			1/28/2013 12:45:56 PM					
Sotelo, Enrique		Requested by Velia for Faculty Parking Lot-The light closest to the Bus Turnaround is burned out. Please replace as soon as possible.				Route to Enrique asp reassignment 4/2/13			
<u>Velia Alarcon</u>									
99042		Athletic Field			2/28/2013		74		\$0.00
Medium	Work In Progress			2/28/2013 3:24:38 PM					
Holguin, Ramiro		sprinklers need to be replaced on softball and soccer fields.							
<u>Guadalupe Ontiveros</u>									
94661		Athletic Field			10/26/2012		199		\$0.00
Medium	Work In Progress			10/26/2012 3:01:38 PM					
Holguin, Ramiro		sprinklers at softball and baseball need to be replace to be able for over seeding.							
<u>Guadalupe Ontiveros</u>									
101026					4/17/2013		26		\$0.00
Medium	Work In Progress			4/17/2013 1:48:26 PM					
Lara, Ralph		Requested by Coach J. Vasquez Rm. 400 Boy's Gym-Coach's Office door does not lock. SEE COACH VASQUEZ FOR MORE INFORMATION & LOCATION							
<u>Velia Alarcon</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
101651					5/3/2013		10		\$0.00
Medium	Work In Progress			5/3/2013 2:15:44 PM					
Lara, Ralph	Please replace old kind of door knobs to the restroom doors in the new portables with the new type of door knob.								
<u>Guillermo Hernandez</u>									
101957					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 10:19:21 AM					
Lara, Ralph	Requested by Mr. Myers Rm. 504 New Voc. Building-A copy of of the counter cabinet key needs to be made. The key number is C413A. Mrs. Munoz has the key that needs to be copied.								
<u>Velia Alarcon</u>									
91453					8/16/2012		270		\$0.00
Medium	Work In Progress			8/16/2012 4:19:55 PM					
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Set up brackets for a batting cage to be placed behind "visitors" dugout on mini-base infield. Dimensions asking for L 55' x H 12'.								
<u>Velia Alarcon</u>									
96339					12/6/2012		158		\$0.00
Medium	Work In Progress			12/6/2012 3:48:09 PM					
Ambriz, Jose	Need to replace gasket to pump in the boiler room for the Old English....								
<u>Guillermo Hernandez</u>									
93992					10/10/2012		215		\$0.00
Medium	Work In Progress			10/10/2012 11:27:53					
Ambriz, Jose	Need assistance to remove old furnace from the Boys Gym...								
<u>Guillermo Hernandez</u>									
94019					10/10/2012		215		\$0.00
Medium	Work In Progress			10/10/2012 3:43:56 PM					
Ambriz, Jose	Need to replace broken contactor to A/C #6. cafeteria roof.								
<u>Guillermo Hernandez</u>									
94829					10/31/2012		194		\$0.00
Medium	Work In Progress			10/31/2012 9:33:08 AM					
Ambriz, Jose	HEATER UNIT IN BAND ROOM IT DOESNT WORKING AT ANNEX BUILDING								
Joel Herrera									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
94185					10/15/2012		210		\$0.00
Medium	Work In Progress			10/15/2012 3:54:24 PM					
Ambriz, Jose	Need to replace 6 A/C commercial units for the cafeteria....								
<u>Guillermo Hernandez</u>									
95309					11/8/2012		186		\$0.00
Medium	Work In Progress			11/8/2012 7:37:54 AM					
Ambriz, Jose	Need to replace T-stat and check leaks on gaskets on boiler for heating system on the Old English...								
<u>Guillermo Hernandez</u>									
99516					3/10/2013		64		\$0.00
Medium	Work In Progress			3/10/2013 12:19:08 AM					
Hernandez, Guillermo	Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100196					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:17 AM					
Hernandez, Guillermo	Yearly - Gadsden HS A13 (Ceil/Wall Unit)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100197					3/31/2013	5/1/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:17 AM					
Hernandez, Guillermo	Yearly - Gadsden HS A8 (Window Unit)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100195					3/31/2013	4/16/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:16 AM					
Hernandez, Guillermo	Monthly - Gadsden HS A1 (Air Dryer)(S.Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101563					5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 2:17:24 PM					
Ambriz, Jose	Need assistance to trouble shoot H/C unit for classrooms #230 & #231 at the North Building.								
<u>Guillermo Hernandez</u>									
101979					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 3:40:15 PM					
Ambriz, Jose	H/C unit on portable #2, may be low on refrigerant. Unit no cooling.								
<u>Guillermo Hernandez</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
99793					3/17/2013		57		\$0.00
Medium	Work In Progress			3/17/2013 12:19:58 AM					
Villalobos, Margret	Monthly - Gadsden HS - PC Automated Quarterly - Refer to PM schedule details.		Emailed to Melanie on 3/18/13						
<u>Margret Villalobos</u>									
98803					2/25/2013		77		\$0.00
Medium	Work In Progress			2/25/2013 8:27:10 AM					
Herrera, Joel	Requested by Ms. Miller Rm. 344 Academic Building-Door doesn't stay open (magnet)								
<u>Velia Alarcon</u>									
100734					4/9/2013		34		\$0.00
Medium	Work In Progress			4/9/2013 1:45:04 PM					
Herrera, Joel	Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced.								
<u>Velia Alarcon</u>									
101150					4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 9:34:04 AM					
Herrera, Joel	Requested by Ms. Aguilar Rm. 231 North Building-Move Smart Board from west wall to south wall. *Will help keep students focused and prevent them from turning towards door and being distracted by what is going on or who is in the hall.								
<u>Velia Alarcon</u>									
101404					4/29/2013		14		\$0.00
Medium	Work In Progress			4/29/2013 9:12:44 AM					
Herrera, Joel	Requested by Ray Calderon-Move cork board from the Old English Building (2nd Floor) to Main Building next to room # 110.								
<u>Velia Alarcon</u>									
101734					5/5/2013	6/5/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:26 AM					
Herrera, Joel	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101735					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:26 AM					
Herrera, Joel	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
101733					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:25 AM					
Herrera, Joel	Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101961		Portables			5/9/2013		4		\$0.00
Low	Work In Progress			5/9/2013 11:16:10 AM					
Munoz, Joe	please clean rest rooms and portable to be used in the pow wow. thank you								
<u>Michael Munoz</u>									
100474		Athletic Field			4/3/2013		40		\$0.00
Medium	Work In Progress			4/3/2013 9:35:12 AM					
Ontiveros, Guadalupe	Requested by Coach Lawrence for Soccer Fields-Airaid, fertalize, and patch main soccer field by both goals.								
<u>Velia Alarcon</u>									
100480					4/3/2013		40		\$0.00
Medium	Work In Progress			4/3/2013 9:57:03 AM					
Ontiveros, Guadalupe	Requested by Coach Lawrence for Soccer Fields-Paint fields and set up all nets.								
<u>Velia Alarcon</u>									
97772		Athletic Field			1/28/2013		105		\$0.00
Medium	Work In Progress			1/28/2013 1:49:34 PM					
Ontiveros, Guadalupe	need blade spade for three point hitch. J.D 4440								
<u>Guadalupe Ontiveros</u>									
100226					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:29 AM					
Hernandez, Guillermo	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91592					8/20/2012		266		\$0.00
Medium	Work In Progress			8/20/2012 3:55:01 PM					
Gonzalez, Salvador	Requested by Coach L. Chavez for Softball Field- Replace roofs on both dugouts.								
<u>Velia Alarcon</u>									
101915					5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 11:30:45 AM					
Flores, Pete	Need to replace worn tire on truck #155.								
Guillermo Hernandez									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
101990					5/9/2013		4		\$0.00
High	Work In Progress			5/9/2013 3:47:47 PM					
Sanchez, Raul	Need to empty septic tank by the Old library for classroom #125.								
<u>Guillermo Hernandez</u>									
100333					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:09 AM					
Sanchez, Raul	Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100328					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:08 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101754					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:33 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99267					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:21 AM					
Sanchez, Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101756					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:34 AM					
Sanchez, Raul	Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101457					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 12:29:56 AM					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100330					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:08 AM					
Sanchez, Raul	Monthly - Gadsden HS - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
100478		Cafeteria			4/3/2013		40		\$0.00
Medium	Work In Progress			4/3/2013 9:53:40 AM					
Miranda, Danny	KITCHEN-WALLS NEED TO BE REPLACED OR FIXED IN STORAGE AND CHEMICAL ROOMS. PIECES ARE FALLING. SNP MANAGER LYDIA M. 882.5522								
<u>Maritza Gonzalez</u>									
101917					5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 11:31:55 AM					
Hernandez, Guillermo	Need to replace wet section to A/C for the Boys locker room at Boys Gym.								
<u>Guillermo Hernandez</u>									
99892					3/19/2013		55		\$0.00
Medium	Work In Progress			3/19/2013 4:26:10 PM					
Ronquillo, Ruben	BROKEN WINDOWS PT. 1 26X18-1, PT. 3 26X18-3, PT. 4 26X36-1 ALL SINGLE GLASS								
<u>Ruben Ronquillo</u>									
100309					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:00 AM					
Holguin, Alfredo	Monthly - Gadsden HS - Fire Pump Engine - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100304					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:58 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99643		Portables			3/13/2013		61		\$0.00
High	Work In Progress			3/13/2013 11:47:53 AM					
Hernandez, Guillermo	please replace missing , broken or stained ceiling tiles to all portables that were re-located next to boys gym.thank you								
<u>Michael Munoz</u>									
98876					2/26/2013		76		\$0.00
Medium	Work In Progress			2/26/2013 10:50:16 AM					
Hernandez, Guillermo	Requested by Mr. Pokluda for Ms. Anderson's Classroom Move-Additional people are needed to help move Ms. Anderson from current classroom (rm. 233-North Building) into New Classroom in New Trades Building.								
<u>Velia Alarcon</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
100283					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:50 AM					
Hernandez, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101747					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:31 AM					
Hernandez, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 110 Work Orders			Avg. Age of WO's	65		Total for Gadsden HS	0	0	\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
97907					1/31/2013		102		\$0.00
Medium	Work In Progress			1/31/2013 12:25:28 AM					
Apodaca, Mario	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
102007					5/10/2013		3		\$0.00
Medium	Work In Progress	LINE LOCATE		5/10/2013 10:10:20 AM					
Sanchez, Raul	TRIPLE J EXCAVATION								
	Contact Name: ANNETTE GRANADO		Contact						
	Phone: (575)527-1763								
	Location of Work: W1305091638250 FROM N. MAIN ST & WASHINGTON ST IN ANTHONY, GO W ON WASHINGTON ST FOR 1.70 MI TO LEVEE RD. LOCATE ENTIRE LENGTH & WIDTH OF BRIDGE ON WASHINGTON ST TO INCLUDE ALL OF THE AREA UNDERNEATH THE BRIDGE AS WELL								
<u>Alfredo Holguin</u>									
101446					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 12:29:52 AM					
Apodaca, Mario	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101749					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:31 AM					
Apodaca, Mario	Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101750					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:32 AM					
Apodaca, Mario	Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99751		Office			3/15/2013		59		\$0.00
Medium	Work In Progress	front office		3/15/2013 11:31:03 AM					
Diaz, Sebastian	Need wall panel built up for security monitor installation and electrical for monitor hook up. See Mrs. Quinonez or Mr. Calleros for any questions.								
Nancy Tinajero									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
101824					5/6/2013		7		\$0.00
Medium	Work In Progress	117- Aldaz		5/6/2013 12:44:56 PM					
Diaz, Sebastian		Install white board next to other white board on the same wall.							
Nancy Tinajero									
101827					5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 1:17:23 PM					
Diaz, Sebastian		AS PER WORK ORDER #101815, VOCATIONAL BUILDING HAS ASBESTOS AND THEY WILL BE ABATING THE FIRST WEEK IN JUNE. NEED ALL SCIENCE DESK REMOVED.							
Alfredo Holguin									
101682					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:04 AM					
Diaz, Sebastian		Monthly - Gadsden MS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
101683					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:05 AM					
Diaz, Sebastian		Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
101684					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:05 AM					
Diaz, Sebastian		Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
99110					3/3/2013	3/19/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:10 AM					
Villalobos, Margret		Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details.				E-mailed Honeywell 3/5			
Margret Villalobos									
101676					5/5/2013	5/21/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:02 AM					
Villalobos, Margret		Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details.							
Margret Villalobos									
98858					2/26/2013		76		\$0.00
Medium	Work In Progress	Parking Lot -		2/26/2013 8:56:03 AM					
Lozoya, Manny		Lock opens with a slight pull. It does't lock properly. Please replace.							
Nancy Tinajero									
5/13/2013 12:31:00 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
95451					11/13/2012		181		\$0.00
Medium	Work In Progress				11/13/2012 11:21:58				
Ontiveros, Guadalupe	Please move guard shed to the back of the school. Set it up on the 6X6 concrete slab. Please see Mr. Calleros for details.								
<u>Nancy Tinajero</u>									
94655		Athletic Field			10/26/2012		199		\$0.00
Medium	Work In Progress				10/26/2012 2:51:10 PM				
Vasquez, Jose	need to replace solenoids on electric valves. sprinklers are not working.								
<u>Guadalupe Ontiveros</u>									
96902		Football Field			1/7/2013		126		\$0.00
Medium	Work In Progress				1/7/2013 8:18:11 AM				
Sotelo, Enrique	Enrique can you help disconnecting power on scoreboard please so we can work on it, thank you.								
<u>Salvador Gonzalez</u>									
100505					4/3/2013		40		\$0.00
Medium	Work In Progress				4/3/2013 3:34:37 PM				
Solis, Lorenzo	Need to fix pump on boiler westside thank you								
<u>Sebastian Diaz</u>									
100512					4/3/2013		40		\$0.00
Medium	Work In Progress				4/3/2013 3:43:03 PM				
Solis, Lorenzo	Need to check A/C on annex thank you								
<u>Sebastian Diaz</u>									
100211					3/31/2013	4/16/2013	43		\$0.00
Medium	Work In Progress				3/31/2013 12:32:23 AM				
Villalobos, Margret	Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details.		Emailed Art, Honeywell 4/2						
<u>Margret Villalobos</u>									
101674					5/5/2013	5/8/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:01 AM				
Diaz, Sebastian	Monthly - Gadsden MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101828					5/6/2013		7		\$0.00
Medium	Work In Progress				5/6/2013 1:17:56 PM				
Villalobos, David	AS PER WORK ORDER #101815, VOCATIONAL BUILDING HAS ASBESTOS AND THEY WILL BE ABATING THE FIRST WEEK IN JUNE. NEED ALL STOVES REMOVED.								
<u>Alfredo Holguin</u>									

5/13/2013 12:31:00 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
100747					4/9/2013		34		\$0.00
Medium	Work In Progress			4/9/2013 3:29:25 PM					
Villalobos, David	Need to relocate water lines for install water fountain on old annex thank you								
Sebastian Diaz									
99915					3/20/2013		-268		\$0.00
Medium	Work In Progress			3/20/2013 9:47:57 AM		6/25/2012			
Estrada, Jesus	FLOOR NEEDS TO BE RE-FINISHED (APPROX. L - 113' X W - 89')								
Jesus Estrada									
98661	Main Building				2/20/2013		82		\$0.00
Medium	Work In Progress			2/20/2013 10:34:21 AM					
Lozoya, Manny	A.B WING ALL EXIT DOORS CORES NEED TO BE CLEAN CAN UNLOCK WITH KEY								
Juan Acosta									
100829	Main Building	Hallway/Corridor			4/11/2013		32		\$0.00
Medium	Work In Progress			4/11/2013 8:55:47 AM					
Lozoya, Manny	A.WING DOOR GOING OUTSIDE TO PARK LOT .THE DOOR LEVER HANDLE IS GETING STUCK								
Juan Acosta									
94874	Main Building				11/1/2012		193		\$0.00
Medium	Work In Progress			11/1/2012 7:48:39 AM					
Lozoya, Manny	B.WING EXIT DOOR NEXT TO ROOM 113 CANNOT UNLOCK WHTH KEY								
Juan Acosta									
94878	Annex	Hallway/Corridor			11/1/2012		193		\$0.00
Medium	Work In Progress			11/1/2012 8:00:53 AM					
Lozoya, Manny	ANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOOR								
Juan Acosta									
101816	Vocational				5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 9:23:23 AM					
Holguin, Alfredo	abate asbestos floor tile in all classrooms(300-305) on south side and Lobby and classroom 308 .								
Alfredo Holguin									
101815	Vocational				5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 9:21:50 AM					
Estrada, Jesus	All classrooms(300-305) on south side and Lobby and classroom 308 . Needs to be re-tiled after abatement tentatively scheduled for the first week in June.								
Alfredo Holguin									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
94880	Gymnasium	Hallway/Corridor			11/1/2012		193		\$0.00
Medium	Work In Progress				11/1/2012 8:14:11 AM				
Lozoya, Manny	LOBBY EXIT DOOR GOING IN GYM FLOOR NEXT TO BLEACHERS THE MULLION IS LOOSE								
Juan Acosta									
97292	East Mechanical	Mechanical			1/15/2013		118		\$0.00
Medium	Work In Progress				1/15/2013 7:52:09 AM				
Villalobos, David	need to replace return line on boiler system.		Route to David asp reassignment 4/2/13						
Fred Appelzoller									
89884					7/17/2012		300		\$0.00
Medium	Work In Progress				7/17/2012 7:12:12 AM				
Lozoya, Manny	ALL CORES TO EXIT DOORS OUTSIDE NEEDS CLEANING								
Juan Acosta									
100367					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress				3/31/2013 12:33:24 AM				
Orozco, Daniel	Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
101867	C-Wing				5/7/2013		6		\$0.00
Medium	Work In Progress	CHARTER			5/7/2013 2:58:27 PM				
Solis, Lorenzo	Charter School - Need to replace control on wall unit will not shut off.								
Maggie Gonzalez									
101865	C-Wing				5/7/2013		6		\$0.00
Medium	Work In Progress	CHARTER			5/7/2013 12:57:15 PM				
Diaz, Sebastian	Charter School - We need some light replaced in the hallway. Also one of the wall units can't turn off.								
Maggie Gonzalez									
102016	C-Wing	Portables			5/10/2013		3		\$0.00
Safety	Work In Progress	MEDICAID			5/10/2013 11:57:26 AM				
Diaz, Sebastian	AS PER MR. CHAVEZ-NEED TO FIX A DRAIN CUTTER IN THE MEDICAID PORTABLE THAT IS HANGING AND MIGHT HURT SOMEONE DUE TO WINDS.		NEED TO BE TAKEN CARE OF ASAP AS PER MR. CHAVEZ						
Mary Garcia									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
101220	C-Wing	Office			4/23/2013		20		\$0.00
Medium	Work In Progress			4/23/2013 2:16:35 PM					
Ontiveros, Guadalupe	We would love to have a shade tree planted in the court yard, outside our office, to replace the 2 palm trees that died last yr. Thank you sooo much...Colleen Nursing Dept								
<u>Colleen Runyan</u>									
101218	C-Wing				4/23/2013		20		\$0.00
Medium	Work In Progress	Charter School		4/23/2013 2:01:17 PM					
Diaz, Sebastian	Please remove broken table in back of the Charter School.								
<u>Maggie Gonzalez</u>									
95951	Gym				11/29/2012		165		\$0.00
Medium	Work In Progress	Gym Storage		11/29/2012 3:23:49 PM					
Gonzalez, Salvador	Please build new loft in storage room in gymnasium. See Mr. Calleros for more details.								
<u>Nancy Tinajero</u>									
101163	Gym	Dressing Room			4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 11:59:25 AM					
Lozoya, Manny	GYM OUTSIDE BOYS LOCKER ROOM DOOR LEVER HANDLE IS GETING STUCK								
<u>Juan Acosta</u>									
100825	Gym	Gym			4/11/2013		32		\$0.00
Medium	Work In Progress			4/11/2013 8:18:37 AM					
Lozoya, Manny	WILL BE RE-FINISHING GYM FLOOR 6-3- TO 6-14 NEED TO CHANCE CORES TO EXIT DOORS AND LOCKER ROOM EXIT DOORS TO GYM								
<u>Juan Acosta</u>									
101794					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:50 AM					
Orozco, Daniel	Monthly - Gadsden MS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99229					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:04 AM					
Munoz, Michael	Yearly - Gadsden MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
101759					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:35 AM					
Diaz, Sebastian	Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100928					4/15/2013		28		\$0.00
Medium	Work In Progress			4/15/2013 12:20:19 PM					
Orozco, Daniel	FAUCET LEAKING . SNP MANAGER TERRY P. 882.2824								
<u>Maritza Gonzalez</u>									
101323					4/25/2013		18		\$0.00
Medium	Work In Progress			4/25/2013 3:20:03 PM					
Orozco, Daniel	CLOGGED DRAIN ON HADN WASHING SINK. SNP MANAGER TERRY P. 882.2824								
<u>Maritza Gonzalez</u>									
101324					4/25/2013		18		\$0.00
Medium	Work In Progress			4/25/2013 3:20:21 PM					
Orozco, Daniel	MILK COOLER IS DOWN. SNP MANAGER TERRY P. 882.2824								
<u>Maritza Gonzalez</u>									
101634		Athletic Field			5/3/2013		10		\$0.00
Medium	Work In Progress			5/3/2013 7:26:47 AM					
Gonzalez, Salvador	scoreboard to football field was damaged due to high winds. please re-install. thank you								
<u>Michael Munoz</u>									
101413					4/29/2013		14		\$0.00
Medium	Work In Progress			4/29/2013 2:13:50 PM					
Gonzalez, Salvador	Need to weld hinge on exterior door on the southwest of Academic building.								
<u>Guillermo Hernandez</u>									
Count: 50 Work Orders			Avg. Age of WO's	48		Total for Gadsden MS	0		\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
100716					4/9/2013		34		\$0.00
Medium	Work In Progress			4/9/2013 9:01:03 AM					
Orozco, Daniel	DRAIN PIPE ON DISHWASHER KEEPS FALLING OFF. SNP MANAGER LINDA Y. 589.2040								
<u>Maritza Gonzalez</u>									
101360					4/26/2013		17		\$0.00
Medium	Work In Progress	EARLY		4/26/2013 8:04:14 AM					
Briones, Enrique	DELIVER PO 121305389 DENVER DEVELOPMENT MAT'LS 1 BOX LORENO FIERRA/EARLY CHILDHOOD FAMILY EDUCATOR/LU								
<u>Margaret Villalobos</u>									
99220					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:00 AM					
Munoz, Michael	Yearly - La Union ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100341					3/31/2013	4/6/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:13 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101764					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:37 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101795					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:51 AM					
Orozco, Daniel	Monthly - La Union ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100368					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:24 AM					
Orozco, Daniel	Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
98430					2/13/2013		89		\$0.00
Medium	Work In Progress			2/13/2013 7:52:24 AM					
Aguilar, Patricio	wo to myself - need to install baseboard molding office old wing								
Patricio Aguilar									
101203					4/23/2013		20		\$0.00
Medium	Work In Progress			4/23/2013 8:31:44 AM					
Castillo, Carlos	need new installation on emerg light hall way - need help on ck of emerg light hall way								
Patricio Aguilar									
101833					5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 3:02:10 PM					
Aguilar, Patricio	wo to myself - need to replace toilet set boys rest room								
Patricio Aguilar									
101561					5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 1:29:19 PM					
Ambriz, Jose	need help with 4 water fountains the plastic connections leak								
Patricio Aguilar									
100180					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:10 AM					
Aguilar, Patricio	Monthly - La Union ES H-11 Unit Elec Ht Semiannual - Refer to PM schedule details.								
Margret Villalobos									
100181					3/31/2013	5/1/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:10 AM					
Aguilar, Patricio	Yearly - La Union ES A-8 Air Cooled Unit Yearly - Refer to PM schedule details.								
Margret Villalobos									
98862					2/26/2013		76		\$0.00
Medium	Work In Progress			2/26/2013 9:21:41 AM					
Flores, Pete	need oil - filter change - mower blades for jd125								
Patricio Aguilar									
100678					4/8/2013		35		\$0.00
Medium	Work In Progress			4/8/2013 12:55:07 PM					
Aguilar, Patricio	wo to myself - need to repair 2" pvc water line to the back to water yard								
Patricio Aguilar									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
101703					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:13 AM					
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Refer to PM schedule details.		Monthly -						
Margret Villalobos									
101701					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:12 AM					
Aguilar, Patricio	Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.		Monthly -						
Margret Villalobos									
101702					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:12 AM					
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.		Monthly -						
Margret Villalobos									
100260					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:42 AM					
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Refer to PM schedule details.		Monthly -						
Margret Villalobos									
100261					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:42 AM					
Aguilar, Patricio	Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.		Monthly -						
Margret Villalobos									
100259					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:41 AM					
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.		Monthly -						
Margret Villalobos									
100234					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:32 AM					
Aguilar, Patricio	Monthly - La Union ES Roof Inpsection - Refer to PM schedule details.		Monthly -						
Margret Villalobos									
100329					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:08 AM					
Sanchez, Raul	Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details.		Monthly -						
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		La Union ES							
102055					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress				5/12/2013 12:21:28 AM				
Aguilar, Patricio	Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
100648					4/7/2013	4/23/2013	36		\$0.00
Medium	Work In Progress				4/7/2013 12:19:04 AM				
Aguilar, Patricio	Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
Count: 25 Work Orders		Avg. Age of WO's		33	Total for La Union ES			0	\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
100653					4/7/2013	4/23/2013	36		\$0.00
Medium	Work In Progress			4/7/2013 12:19:06 AM					
Medina, Eric		Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.				Routed to Eric asp reassignment 4/22/13			
<u>Margret Villalobos</u>									
102056					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:28 AM					
Medina, Eric		Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
100977		Athletic Field			4/16/2013		27		\$0.00
Medium	Work In Progress			4/16/2013 2:47:22 PM					
Medina, Eric		Need to order and replace 13 I 25 sprinklers on soccer and play ground							
<u>Eric Medina</u>									
100237					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:33 AM					
Medina, Eric		Monthly - Loma Linda ES Roof Inpsection - Refer to PM schedule details.				Routed to Eric asp reassignment 4/22/13			
<u>Margret Villalobos</u>									
101315					4/25/2013		18		\$0.00
Medium	Work In Progress			4/25/2013 12:40:44 PM					
Ontiveros, Guadalupe		need to request backhoe due to the breaking of a playground spring toy and need to remove cement bulb							
<u>Eric Medina</u>									
101962					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 11:17:52 AM					
Ontiveros, Guadalupe		when possible please level and scrape with tractor around campus to include pine trees. thank you							
<u>Michael Munoz</u>									
101963					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 11:19:30 AM					
Medina, Eric		please clean around morgan buildings and dispose of debri. (ie sand bags, tables, metal etc).							
<u>Michael Munoz</u>									
101964					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 11:20:32 AM					
Medina, Eric		please clean area where mobile home used to be. thank you							
<u>Michael Munoz</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Loma Linda ES

100830					4/11/2013		26		\$0.00
Medium	Work In Progress			4/11/2013 9:02:02 AM		5/7/2013			
Medina, Eric	4/11 need to order 1 set of ratching open ended wrenches 1 set of sockets 1 backpack sprayer 1 hammer 1 drill bit set 1 basin wrench 1 small oilless compressor								
Eric Medina									
101316					4/25/2013		18		\$0.00
Medium	Work In Progress			4/25/2013 12:48:33 PM					
Medina, Eric	4/25 as per mr lawler need to assemble new furniture for front office								
Eric Medina									
101138					4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 8:52:16 AM					
Medina, Eric	need to weed and feed fields and need to order 20 bags of weed and feed								
Eric Medina									
101688					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:07 AM					
Medina, Eric	Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
101689					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:07 AM					
Medina, Eric	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
101690					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:07 AM					
Medina, Eric	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
101835		Athletic Field			5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 3:08:35 PM					
Ontiveros, Guadalupe	Lupe would like to request small tractor and two loads of top soil for soccer field								
Eric Medina									

5/13/2013 12:31:00 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
100184					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:11 AM					
Medina, Eric		Monthly - Loma Linda ES A16(Fan Exh.)(S.Annual) - Refer to PM schedule details.				Routed to Eric asp reassignment 4/22/13			
<u>Margret Villalobos</u>									
100731					4/9/2013		34		\$0.00
Medium	Work In Progress			4/9/2013 12:02:20 PM					
Lozoya, Manny		eric medina will be assigned to loma-linda effective 4-10-13, please turn over rudys keys and assign to eric. also please have eric turn in keys for sunland park thank you							
<u>Michael Munoz</u>									
97624		Restroom (Boys)			1/24/2013		109		\$0.00
Medium	Work In Progress			1/24/2013 7:51:32 AM					
Villalobos, David		please replace all granite wash basins in restrooms with stainless steal basins. the existing ones are in poor conditions. thankyou				Route to David asp reassignment 4/2/13			
<u>Michael Munoz</u>									
100369					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:25 AM					
Orozco, Daniel		Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
101796					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:51 AM					
Orozco, Daniel		Monthly - Loma Linda ES Fire Suppression Insp. - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
101525					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 4:15:47 PM					
Solis, Lorenzo		Asp PM Inspection by Dimar - need to check gauges.							
<u>Michael Munoz</u>									
101526					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 4:16:54 PM					
Villalobos, David		Asp PM Inspection by Dimar - main drain has a crack in pipe.							
<u>Michael Munoz</u>									
101766					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:38 AM					
Medina, Eric		Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
5/13/2013 12:31:00 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
99221					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:00 AM					
Munoz, Michael	Yearly - Loma Linda ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101544					5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 8:56:13 AM					
Orozco, Daniel	WALK IN NOT WORKING PROPERLY. SNP MANAGER FRANCES B. 882.4707								
<u>Maritza Gonzalez</u>									
101503					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 3:37:35 PM					
Orozco, Daniel	DEVICE ON DOORS FOR FLIES IS NOT WORKING. SNP MANAGER FRANCES B. 882.4707								
<u>Maritza Gonzalez</u>									
97008	Main Building	Classroom			1/8/2013		125		\$0.00
Medium	Work In Progress			1/8/2013 10:10:55 AM					
Lozoya, Manny	As per our principal we need 6 keys to open the back door to the main building. Keys are for Morris, Martinez, Quintero, Gonzalez, Luna and Steinert. Keys will be able to only open one of the back main doors. Not a master key!								
<u>Angie Flores</u>									
96001	Main Building	Parking Lot			11/30/2012		164		\$0.00
Medium	Work In Progress			11/30/2012 11:37:03					
Medina, Eric	As per Mr. Lawler please repaint the fire lanes.		4/22/13 Asp reassignment - routed to Eric						
<u>Angie Flores</u>									
100711	Main Building	Athletic Field			4/9/2013		34		\$0.00
Medium	Work In Progress			4/9/2013 7:57:54 AM					
Villalobos, David	WATER FOUNTAIN THAT WAS JUST INSTALLED ON THE EAST SIDE OF PORTABLE WATER LINE IS BROKEN NEEDS TO BE REPLACED.								
<u>Rudy Arreola</u>									
101111	Main Building	Portables			4/19/2013		24		\$0.00
Medium	Work In Progress	Martinez		4/19/2013 12:34:08 PM					
Sotelo, Enrique	No power to bottom plug of outlet located underneath front whiteboard. Top plug of outlet by front door wont hold plug.								
<u>Angie Flores</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
96008	Main Building	Athletic Field			11/30/2012		164		\$0.00
Medium	Work In Progress			11/30/2012 2:49:28 PM					
Ontiveros, Guadalupe ANOTHER VALVE IS STUCK SPRINKLERS KEEP RUNNING. BY PLAYGROUND AREA.									
Rudy Arreola									
101409	Main Building	Classroom			4/29/2013		14		\$0.00
Medium	Work In Progress	217		4/29/2013 11:57:56 AM					
Medina, Eric Blinds are broken and will not close, please help, too bright!									
Angie Flores									
101426	Main Building	Classroom			4/29/2013		14		\$0.00
Medium	Work In Progress	201		4/29/2013 3:29:50 PM					
Medina, Eric Air conditioner went out today, blowing hot air only									
Angie Flores									
101414	Main Building	Office			4/29/2013		14		\$0.00
Medium	Work In Progress	Office		4/29/2013 2:27:45 PM					
Medina, Eric Build two office desks and two file cabinets									
Angie Flores									
101920	Main Building	Restroom (Girls)			5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 12:59:16 PM					
Medina, Eric The middle water dispenser shoots water at you, in the girls restroom in front of the teachers lounge.									
Angie Flores									
99903	Main Building	Hallway/Corridor			3/20/2013		54		\$0.00
Medium	Work In Progress			3/20/2013 9:07:02 AM					
Estrada, Jesus SPOKE TO CHUY CARPET ON STAGE WAS INSTALLED ABOUT A 2 YEARS AGO IT STARTED TO RIP.									
Rudy Arreola									
99904	Main Building	Hallway/Corridor			3/20/2013		54		\$0.00
Medium	Work In Progress			3/20/2013 9:08:40 AM					
Estrada, Jesus SPOKE TO CHUY BASEBOARDS WERE REPLACED ON HALF OF SCHOOL WOULD LIKE TO DO THE OTHER HALF OF SCHOOL. THEY ARE IN REALLY BAD SHAPE COMING UNGLUED AND RIPPING									
Rudy Arreola									
Count: 37 Work Orders		Avg. Age of WO's 34			Total for Loma Linda ES			0	\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
101814	Main Building				5/6/2013		7		\$0.00
Medium	Work In Progress				5/6/2013 9:17:59 AM				
Estrada, Jesus	Book Room 107 . Needs to be re-tiled after tentatively scheduled for the first week in June.								
<u>Alfredo Holguin</u>									
89436					7/1/2012	8/1/2012	316		\$0.00
Medium	Work In Progress				7/1/2012 12:30:58 AM				
Ramirez, Joe	Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101212					4/23/2013		20		\$0.00
Medium	Work In Progress				4/23/2013 1:27:41 PM				
Orozco, Daniel	WALK IN FREEZER TEMP IS GOING UP.								
<u>Maritza Gonzalez</u>									
96318					12/6/2012		158		\$0.00
Medium	Work In Progress				12/6/2012 1:02:43 PM				
Briones, Enrique	please Warehouse ATT: LARRY MARTINES we have broken computer desk, old furniture, student desk broken, etc. thank you								
<u>Luis Saucedo</u>									
102009					5/10/2013		3		\$0.00
Medium	Work In Progress				5/10/2013 10:18:13 AM				
Orozco, Daniel	SLICER IS LOOSING DRIVE SHIFT.SNP MANAGER VIRGINIA P. 233.2341								
<u>Maritza Gonzalez</u>									
99222					3/3/2013		71		\$0.00
Medium	Work In Progress				3/3/2013 12:26:01 AM				
Munoz, Michael	Yearly - Mesquite ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101763					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:37 AM				
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101797					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:52 AM				
Orozco, Daniel	Monthly - Mesquite ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
100370					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:25 AM					
Orozco, Daniel	Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
95365					11/9/2012		185		\$0.00
Medium	Work In Progress			11/9/2012 1:09:02 PM					
Lozoya, Manny	sothside boys and girls bathroom stalls need to be replaced the floor securing brackets are either broken or rusted through and also most of the stalls are very rusted								
<u>Joe Ramirez</u>									
97808					1/29/2013		104		\$0.00
Medium	Work In Progress			1/29/2013 8:06:10 AM					
Lozoya, Manny	bathroom partitions north and south ,boys' and girls' bathrooms need to be replaced								
<u>Joe Ramirez</u>									
97385					1/16/2013		117		\$0.00
Medium	Work In Progress			1/16/2013 8:51:53 AM					
Lozoya, Manny	door handle rm.229 not working properly neds to be replaced								
<u>Joe Ramirez</u>									
101887					5/7/2013		6		\$0.00
Medium	Work In Progress			5/7/2013 3:46:41 PM					
Villalobos, David	o-ring on new toilet flush valve needs to be replaced.								
<u>Joe Ramirez</u>									
101672					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:00 AM					
Ramirez, Joe	Monthly - Mesquite ES - Barrack Drainage (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97179					1/11/2013		122		\$0.00
Medium	Work In Progress			1/11/2013 3:47:35 PM					
Ramirez, Joe	please paint doors to portable 611 & 612. thank you								
<u>Selma Nevarez</u>									
100174					3/31/2013	4/16/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:07 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

5/13/2013 12:31:00 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
100175					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:08 AM					
Ramirez, Joe	Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99530					3/11/2013		63		\$0.00
Medium	Work In Progress			3/11/2013 8:38:39 AM					
Lozoya, Manny	door knob in rm. 112 will not lock needs to be replaced (lock down) and door wouldn,t lock.								
<u>Joe Ramirez</u>									
98511					2/14/2013		88		\$0.00
Medium	Work In Progress			2/14/2013 9:17:23 AM					
Lozoya, Manny	AS PER MR. BAKER, HIS MASTER KEY TO KITCHEN (BACKDOOR) DID NOT WORK AT MESQUITE ELEM. HIS UNDERSTANDING WAS THAT HIS MASTER SHOULD BE ABLE TO OPEN ALL KITCHENS. PLEASE ADVISE.								
<u>Maritza Gonzalez</u>									
97630					1/24/2013		109		\$0.00
Medium	Work In Progress			1/24/2013 8:50:56 AM					
Lozoya, Manny	i need 4 padlocks for the new gates that are being installed								
<u>Joe Ramirez</u>									
95182		Athletic Field			11/5/2012		189		\$0.00
Medium	Work In Progress			11/5/2012 3:27:39 PM					
Ramirez, Joe	As per mr. Mike need to in stall irrigation system on playing fields.								
<u>Guadalupe Ontiveros</u>									
99448					3/7/2013		67		\$0.00
Medium	Work In Progress			3/7/2013 12:29:21 PM					
Lozoya, Manny	principals are requesting door viewers installed on doors (portables)approx 10								
<u>Joe Ramirez</u>									
91551					8/20/2012		266		\$0.00
Medium	Work In Progress			8/20/2012 12:50:51 PM					
Ramirez, Joe	need to install frp panel in rms. 801,802.								
<u>Joe Ramirez</u>									
101694					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:09 AM					
Ramirez, Joe	Monthly - Mesquite ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
5/13/2013 12:31:00 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
101695					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:09 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101696					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:10 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99968					3/21/2013		53		\$0.00
Medium	Work In Progress			3/21/2013 6:27:23 AM					
Holguin, Alfredo	ATTN alfredo h. bookroom (rm. 107) needs to be abated								
<u>Joe Ramirez</u>									
101755					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:34 AM					
Sanchez, Raul	Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99268					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:21 AM					
Sanchez, Raul	Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101812					5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 8:44:11 AM					
Ronquillo, Ruben	rm. 608 broken window need to replace 28"x28" double pane								
<u>Joe Ramirez</u>									
Count: 30 Work Orders			Avg. Age of WO's	74		Total for Mesquite ES	0		\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
102063					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:32 AM					
Vega, Danny	Monthly - North Valley ES Playground Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100306					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:59 AM					
Holguin, Alfredo	Monthly - North Valley ES - Fire Pump Engine - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101977					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 3:37:09 PM					
Vega, Danny	5-9-13 1-ck heat pumps at nve 1-ck ice maker at nve kitchen/clean filter 1-wk od#101769 1-wk od#101770 1-wk od#101736 1-wk od#101737 1-wk od#101738 1-wk od#101739								
<u>Danny Vega</u>									
101738					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:27 AM					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101736					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:26 AM					
Vega, Danny	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101971					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 2:23:27 PM					
Ontiveros, Guadalupe	need three shade tree /need to replant dried out trees at plygrd area.when available								
<u>Danny Vega</u>									
101154					4/22/2013		21		\$0.00
Medium	Work In Progress	Playground		4/22/2013 10:21:35 AM					
Ontiveros, Guadalupe	need plygrd sand at nve (2)loads.plz								
<u>Danny Vega</u>									

5/13/2013 12:31:00 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
101253		Classroom			4/23/2013		20		\$0.00
Medium	Work In Progress	206		4/23/2013 4:04:00 PM					
Lozoya, Manny		Replacement keys and lock on classroom doors, exterior and interior.							
Priscilla Martinez									
97366					1/15/2013		118		\$0.00
Medium	Work In Progress			1/15/2013 3:53:46 PM					
Lozoya, Manny		need help to secure front entrance door/divider bar core jammed /will not lock plz help							
Danny Vega									
89953					7/18/2012		299		\$0.00
Medium	Work In Progress			7/18/2012 10:38:49 AM					
Lozoya, Manny		need exterior security door handle plates installed in rm 107-108-211-212-309-310 doors to keep vandals from prying doors open as per MR. T							
Danny Vega									
99297					3/4/2013		70		\$0.00
Medium	Work In Progress			3/4/2013 11:44:56 AM					
Lozoya, Manny		need a chain for a walking gate that stays open.							
Javier Parra									
91740		Classroom			8/23/2012		263		\$0.00
Medium	Work In Progress	various		8/23/2012 10:11:46 AM					
Lozoya, Manny		Need to obtain additional cabinet keys for certain classrooms.							
Priscilla Martinez									
94886					11/1/2012		193		\$0.00
Medium	Work In Progress			11/1/2012 10:47:05 AM					
Lozoya, Manny		door in between techers lounge and hallway wont close.							
Javier Parra									
102004		Electrical Room			5/10/2013		3		\$0.00
Medium	Work In Progress	cafeteria		5/10/2013 9:36:14 AM					
Sotelo, Enrique		Please send someone to check an electrical outlet in our cafeteria for our microphone.							
Priscilla Martinez									
101208					4/23/2013		20		\$0.00
Medium	Work In Progress			4/23/2013 9:18:55 AM					
Carbajal, Jimmy		wet n dry machine not picking up water.							
Javier Parra									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: North Valley ES										
101799					5/5/2013	5/26/2013	8		\$0.00	
Medium	Work In Progress			5/5/2013 12:24:53 AM						
Orozco, Daniel	Monthly - North Valley ES Fire Suppression Insp. - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
101769					5/5/2013	5/11/2013	8		\$0.00	
Medium	Work In Progress			5/5/2013 12:24:40 AM						
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
99223					3/3/2013		71		\$0.00	
Medium	Work In Progress			3/3/2013 12:26:01 AM						
Munoz, Michael	Yearly - North Valley ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
100380					3/31/2013		43		\$0.00	
Medium	Work In Progress			3/31/2013 12:33:29 AM						
Orozco, Daniel	Monthly - North Valley ES - Range Hood Cleaning - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
102008					5/10/2013		3		\$0.00	
Medium	Work In Progress			5/10/2013 10:17:24 AM						
Orozco, Daniel	ICE MACHINE IS NOT WORKING. SNP MANAGER LAURA B. 233.3658									
<u>Maritza Gonzalez</u>										
100670					4/8/2013		35		\$0.00	
High	Work In Progress			4/8/2013 10:18:56 AM						
Munoz, Michael	fire pump alarm is on. low battieries. need to repair. thankyou									
<u>Yolie Jacquez</u>										
Count: 21 Work Orders	Avg. Age of WO's 59		Total for North Valley ES				0	\$0.00		

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
101466	Main Building				4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 8:13:54 AM					
Solis, Lorenzo	SMALL LEAK FROM PIPES RUNNING ALONG CEILING IN DAYCARE CLASSROOM 114.								
Adam Montoya									
101770					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:40 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
99238					3/3/2013	3/14/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:08 AM					
Munoz, Michael	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
100833					4/11/2013		32		\$0.00
Medium	Work In Progress			4/11/2013 10:54:47 AM					
Lara, Ralph	rm 108 restroom door will not close (off-alignment)at top hinge-door is split and screws on hinge will not hold .plz check .this is used as a infant changing rm								
Danny Vega									
100835					4/11/2013		32		\$0.00
Medium	Work In Progress			4/11/2013 11:34:08 AM					
Solis, Lorenzo	boiler pump is leaking water (new pumps installation)4-10-13								
Danny Vega									
100012					3/22/2013		52		\$0.00
Medium	Work In Progress			3/22/2013 7:46:06 AM					
Villalobos, David	need help in installing irrigation line shut-off valve to soccer field spklrs 1 1/2 inch line.please bring trencher to dig				Route to David asp reassignment 4/2/13				
Danny Vega									
100497					4/3/2013		40		\$0.00
Medium	Work In Progress			4/3/2013 2:32:54 PM					
Ontiveros, Guadalupe	NEED LANDSCAPING PROJECT IN FRONT OF BUILDING COMPLETED THAT WAS STARTED AT THE BEGINNING OF THE SCHOOL YEAR.								
Adam Montoya									
100472					4/3/2013		40		\$0.00
Medium	Work In Progress			4/3/2013 8:47:44 AM					
Ontiveros, Guadalupe	NEED TILLER. PRE-K IS PLANTING A GARDEN.								
Adam Montoya									
5/13/2013 12:31:00 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Northern On-Track Pre-K (LM)									
99547					3/11/2013		63		\$0.00
Medium	Work In Progress				3/11/2013 1:42:51 PM				
Flores, Pete		LAWN MOWER. (LA125) MOWING DECK NEEDS SERVICE.							
Adam Montoya									
101737					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:27 AM				
Vega, Danny		Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
101739					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:28 AM				
Vega, Danny		Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
102057					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress				5/12/2013 12:21:29 AM				
Vega, Danny		Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
Count: 12 Work Orders			Avg. Age of WO's	31	Total for Northern On-Track Pre-K (LM)			0	\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
100770					4/10/2013		33		\$0.00
Medium	Work In Progress			4/10/2013 7:28:50 AM					
Apodaca, Mario	Calibration of flow meters for waste water treatment plant At gadaden high school and gadsden middle school								
Mario Apodaca									
102019					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 1:06:54 PM					
Diaz, Sebastian	desk drawer has fallen, need to repair.								
Juliet Parra									
102020					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 1:12:27 PM					
Diaz, Sebastian	several lights in Alfredo's office are out and need to be replaced.								
Juliet Parra									
100528					4/4/2013		39		\$0.00
Medium	Work In Progress			4/4/2013 8:57:31 AM					
Ronquillo, Ruben	1/2" NYLON ROPE FOR BUCKET TRUCK								
Ruben Ronquillo									
93067					9/20/2012		235		\$0.00
Medium	Work In Progress			9/20/2012 10:51:22 AM					
Ronquillo, Ruben	as per meeting held, please dispose of any unused material and clean and organize barracks. thank you.		Continuing from 68685						
Michael Munoz									
100957					4/15/2013		28		\$0.00
Medium	Work In Progress			4/15/2013 3:57:18 PM					
Ronquillo, Ruben	TELLSTAR PC FOR GRASS INFESTATION OF WORMS AT PPD PARK								
Ruben Ronquillo									
101808					5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 12:24:54 AM					
Villalobos, Margret	Monthly - PPD - Quarterly Meeting - Refer to PM schedule details.								
Margret Villalobos									
99830					3/18/2013		56		\$0.00
Medium	Work In Progress			3/18/2013 3:32:37 PM					
Flores, Pete	Need to replace windsheild on 108 - Accident Report was filed by M. Lozoya								
Maria Ruiz									

5/13/2013 12:31:00 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
99749					3/15/2013		59		\$0.00
High	Work In Progress			3/15/2013 9:56:30 AM					
Munoz, Michael	need to repair the following roofs. PPD maintenance office, auto shop, snp warehouse and san miguel barrack. wind damage								
Alfredo Holguin									
101188					4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 4:10:33 PM					
Ontiveros, Guadalupe	please relocate material (i.e, gravel, sand, top dressing etc) by warehouse barracks for new snp barrack to be built. see mike for details. thank you								
Michael Munoz									
101189					4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 4:13:06 PM					
Ontiveros, Guadalupe	please relocate material (i.e sand, gravel top dressing) by warehouse barracks for new snp barrack to be built. please see mike for details. thank you								
Michael Munoz									
101648					5/3/2013		10		\$0.00
High	Work In Progress			5/3/2013 11:05:38 AM					
Ontiveros, Guadalupe	dump truck is down for repairs. need to rent one for 3 weeks for grounds department district wide.								
Michael Munoz									
101420					4/29/2013		14		\$0.00
Medium	Work In Progress			4/29/2013 3:16:58 PM					
Sotelo, Enrique	please check outlet to water fountain. the gfi trips when fountain wants to start. thank you								
Michael Munoz									
92274					9/2/2012		253		\$0.00
Medium	Work In Progress			9/2/2012 12:21:47 AM					
Munoz, Michael	Monthly - Physical Plant - Grease Trap (Custodial) - Refer to PM schedule details.								
Margret Villalobos									
99213					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:57 AM					
Munoz, Michael	Monthly - Physical Plant - Grease Trap (Custodial) - Refer to PM schedule details.								
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
97438					1/17/2013		116		\$0.00
High	Work In Progress			1/17/2013 6:56:41 AM					
Sotelo, Enrique	please cehck lighting on all buildings at ppd, there are alot of lights that are out. also please install another light on the pole int the auto shop parking lot thank you								
Michael Munoz									
95523		Parking Lot			11/14/2012		180		\$0.00
Medium	Work In Progress			11/14/2012 2:39:27 PM					
Ontiveros, Guadalupe	Parking Area on south side of fence between warehouse and GMS Annex - Install parking stops along fence and around fire hydrant to provide enough clearance around hydrant and next to fence.								
Alfredo Holguin									
99678					3/13/2013		61		\$0.00
Medium	Work In Progress			3/13/2013 4:13:34 PM					
Ontiveros, Guadalupe	please install sprinkler system in ppd park(conserve water) thank you								
Michael Munoz									
99797					3/18/2013		56		\$0.00
Medium	Work In Progress			3/18/2013 7:59:04 AM					
Ontiveros, Guadalupe	Build elevated planters including potting soil- Check with Elodia on location								
Alfredo Holguin									
101532					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 4:32:11 PM					
Lozoya, Manny	Please see Alfredo Holguin about (rekeying).								
Alfredo Holguin									
98667					2/20/2013		82		\$0.00
Medium	Work In Progress			2/20/2013 1:50:08 PM					
Lozoya, Manny	Custodial Warehouse Roll Up Door - Very Noisy needs to be cleaned and lubricated?								
Alfredo Holguin									
99237					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:08 AM					
Munoz, Michael	Yearly - Physical Plant Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
95647					11/16/2012		178		\$0.00
High	Work In Progress			11/16/2012 3:52:03 PM					
Munoz, Michael	this is to provide service or replace fire extinguisher (out-dated codes) at the following sites gac,ae,br,che,chs,cms,dp,dt,dv,ge,ghs,gms,northern pre-k,lu,ll,mq,nv,ppd,re,ste,sth,sp,sr,vado.								
Michael Munoz									
101767					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:39 AM					
Diaz, Sebastian	Monthly - Physical Plant FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
100824					4/11/2013		32		\$0.00
Medium	Work In Progress			4/11/2013 7:58:10 AM					
Gonzalez, Salvador	4-11-13 Need cover for welding machine.								
Salvador Gonzalez									
100750					4/9/2013		34		\$0.00
Medium	Work In Progress			4/9/2013 3:33:46 PM					
Gonzalez, Salvador	as per our meeting, please cover east side to back barrack with metal panels. thank you								
Michael Munoz									
101709					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:15 AM					
Ruiz, Maria	Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.								
Margret Villalobos									
93179		Lift Station			9/24/2012		231		\$0.00
Medium	Work In Progress			9/24/2012 2:41:20 PM					
Gonzalez, Salvador	Meet to manufacture A base for the domestic tablet container for the waste water treatment plant								
Mario Apodaca									
101863					5/7/2013		6		\$0.00
Medium	Work In Progress			5/7/2013 9:15:33 AM					
Munoz, Michael	need to remove from site all the debre (ie wood piles, wood poles, branches, tires etc.) and dispose of for new warehouse.								
Alfredo Holguin									
100572					4/5/2013		38		\$0.00
Medium	Work In Progress			4/5/2013 7:58:45 AM					
Gonzalez, Salvador	Need metal door and screen for shop and be installed.								
Salvador Gonzalez									
5/13/2013 12:31:00 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
101560	Food Services	Custodial			5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 1:05:02 PM					
Lozoya, Manny	NEED A CORE ON CUSTODIAL DOOR IN JOHNNYS OFFICE THE DOOR LOCKS AND THEN CUSTODIAN CANT OPEN IT WITHOUT A SCREWDRIVER IF POSSIBLE A DC 2 CORE SINCE THE CUSTODIAN ALREADY HAS THAT KEY								
<u>Jimmy Carbajal</u>									
101542	Food Services				5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 8:34:21 AM					
Aldaz, Bobby	SNP loading dock-add more crusher fine to ramp going into dock area. (Any ?'s see Alfredo)								
<u>Alfredo Holguin</u>									
98757	Food Services				2/22/2013		80		\$0.00
Medium	Work In Progress			2/22/2013 1:04:15 PM					
Lozoya, Manny	please make and assign the following keys 6/7 grand masters to gabriel provencio, robert duran, felipe nevarez and johhny lechuga. 2 per.thank you								
<u>Michael Munoz</u>									
98932	Motor Vehicle				2/27/2013		75		\$0.00
Medium	Work In Progress			2/27/2013 9:06:33 AM					
Lozoya, Manny	Install locks on gas pumps								
<u>Pete Flores</u>									
94420	Motor Vehicle				10/22/2012		203		\$0.00
Medium	Work In Progress	vehicle#101		10/22/2012 11:16:35					
Flores, Pete	truck has difficulty achieving highway speed,possibly a fuel concern. check and advise.								
<u>Pete Flores</u>									
101046	Motor Vehicle				4/17/2013		26		\$0.00
Medium	Work In Progress	vehicle#91		4/17/2013 3:51:49 PM					
Flores, Pete	please check cause of window falling on driver's door,also check for any other scheduled maintenance.								
<u>Pete Flores</u>									
100971	Motor Vehicle				4/16/2013		27		\$0.00
Medium	Work In Progress	l110-mowers		4/16/2013 10:33:13 AM					
Flores, Pete	repair flat tires and service mowers as required-- equipment#'s---0521,0429,0423,sme.								
Pete Flores									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
100976	Motor Vehicle				4/16/2013		27		\$0.00
Medium	Work In Progress	vehicle#166			4/16/2013 2:23:24 PM				
Flores, Pete	vehicle stalls at times please check and advise.								
Pete Flores									
91931	Motor Vehicle				8/28/2012		258		\$0.00
Medium	Work In Progress				8/28/2012 7:52:34 AM				
Flores, Pete	driver seat is tearing on unit 170, request seat covers for it and a step to get on the truck to avoid any more damage to seats and steering wheel while getting into the truck. even a dash mat for the dashboard to avoid sun damage to it . thank u !!								
Fred Appelzoller									
101975	Motor Vehicle				5/9/2013		4		\$0.00
Medium	Work In Progress	vehicle#52			5/9/2013 3:20:03 PM				
Flores, Pete	please service snp freightliner as needed								
Pete Flores									
102011	Motor Vehicle				5/10/2013		3		\$0.00
Medium	Work In Progress	vehicle 02			5/10/2013 11:04:58 AM				
Flores, Pete	windshield damaged and needs replacement,also check for any scheduled maintenance.								
Pete Flores									
97158	Motor Vehicle				1/11/2013		122		\$0.00
Medium	Work In Progress	vehicles 147,187			1/11/2013 9:11:54 AM				
Flores, Pete	please repair windshields on vehicles as needed								
Pete Flores									
97243	Motor Vehicle				1/14/2013		119		\$0.00
Medium	Work In Progress	vehicle#18			1/14/2013 9:43:00 AM				
Flores, Pete	shocks worn and need replacement,also alternator charging excessively causing electrical concerns.engine leaking oil.								
Pete Flores									
95928	Motor Vehicle				11/29/2012		165		\$0.00
Medium	Work In Progress	vehicle#86			11/29/2012 9:53:45 AM				
Flores, Pete	van is running rough and engine is misfiring during normal operation.								
Pete Flores									
101378	Motor Vehicle				4/26/2013		17		\$0.00
Medium	Work In Progress	vehicles-			4/26/2013 3:26:02 PM				
Perez, Raul	please clean,wash,and refuel as required by daily trip schedule.								
Pete Flores									
5/13/2013 12:31:00 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
100604	Motor Vehicle				4/5/2013		38		\$0.00
Medium	Work In Progress	vehicle#11			4/5/2013 3:39:15 PM				
Flores, Pete	difficulty starting vehicle. cranks but won't start at times								
Pete Flores									
100159	Motor Vehicle				3/28/2013		46		\$0.00
Medium	Work In Progress	vehicle#176			3/28/2013 3:54:53 PM				
Flores, Pete	brake lights operating intermittently, and a/c not working properly.								
Pete Flores									
100953	Motor Vehicle				4/15/2013		28		\$0.00
Medium	Work In Progress	vehicles, 104 &			4/15/2013 3:50:29 PM				
Flores, Pete	replace windshields as needed								
Pete Flores									
101825	Motor Vehicle				5/6/2013		7		\$0.00
Medium	Work In Progress	vehicle#151			5/6/2013 1:00:03 PM				
Flores, Pete	please check brakes, very noisy.								
Pete Flores									
101826	Motor Vehicle				5/6/2013		7		\$0.00
Medium	Work In Progress	vehicles-01,12			5/6/2013 1:01:37 PM				
Flores, Pete	please clean wash and prepare for daily trips								
Pete Flores									
101836	Motor Vehicle				5/6/2013		7		\$0.00
Medium	Work In Progress	vehicle#98			5/6/2013 3:17:41 PM				
Flores, Pete	please check electrical system for proper charging.								
Pete Flores									
101636	Motor Vehicle				5/3/2013		10		\$0.00
Medium	Work In Progress	ppd golf cart			5/3/2013 8:24:35 AM				
Flores, Pete	please repair golf cart for use at physical plant.								
Pete Flores									
101647	Motor Vehicle				5/3/2013		10		\$0.00
Medium	Work In Progress	vehicle#143			5/3/2013 10:28:43 AM				
Flores, Pete	vehicle may have sustained internal engine damage, will need to be repaired at border int.								
Pete Flores									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
101609	Motor Vehicle				5/2/2013		11		\$0.00
Medium	Work In Progress	vehicles-		5/2/2013 3:15:03 PM					
Flores, Pete	please refuel clean, wash, and prepare for daily trip schedule.								
<u>Pete Flores</u>									
101612	Motor Vehicle				5/2/2013		11		\$0.00
Medium	Work In Progress	vehicle # 191		5/2/2013 3:24:48 PM					
Flores, Pete	install trailer hook-up as needed to meet any towing requirement.								
<u>Pete Flores</u>									
101552	Motor Vehicle				5/1/2013		12		\$0.00
Medium	Work In Progress	vehicle#25		5/1/2013 10:10:38 AM					
Flores, Pete	vehicle runs sluggish after being driven for a while.								
<u>Pete Flores</u>									
101494	Motor Vehicle				4/30/2013		13		\$0.00
Medium	Work In Progress	vehicle#111		4/30/2013 3:09:34 PM					
Flores, Pete	vehicle difficult to start after driving for a while.								
<u>Pete Flores</u>									
101875	Motor Vehicle				5/7/2013		6		\$0.00
Medium	Work In Progress	vehicle#01		5/7/2013 3:31:13 PM					
Flores, Pete	door lock actuators not working as designed. please check.								
<u>Pete Flores</u>									
101642	Purchasing				5/3/2013		10		\$0.00
Medium	Work In Progress			5/3/2013 9:22:42 AM					
Lozoya, Manny	Issue J-3 and DC - 18 keys to Camilo Gonzales, Also collect any keys Larry Martinez may have to this offices or cabinets and reissue to Camilo								
<u>Alfredo Holguin</u>									
95859	Purchasing	Office			11/27/2012		167		\$0.00
Medium	Work In Progress			11/27/2012 4:14:46 PM					
Lozoya, Manny	Please make a key for IM office 2. For larry								
<u>Larry Martinez</u>									
99070	Purchasing				3/1/2013		73		\$0.00
Medium	Work In Progress			3/1/2013 8:30:37 AM					
Lozoya, Manny	Issue 6 and 7 pin Master Keys to David Ruiz, Mail Clerk								
<u>Alfredo Holguin</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
94890	Purchasing				11/1/2012		193		\$0.00
Medium	Work In Progress				11/1/2012 11:12:31 AM				
Lozoya, Manny	Main Entry Lock to PPD-Construction Offices - core is sticking and hard to unlock								
<u>Alfredo Holguin</u>									
99729	Purchasing	Custodial			3/14/2013		60		\$0.00
Medium	Work In Progress				3/14/2013 3:44:20 PM				
Sotelo, Enrique	A BALLAST IS FALLING DOWN IN CUSTODIAL WHSE IT IS A SAFETY HAZARD.								
<u>Jimmy Carbajal</u>									
101952	Maintenance	Electrical Room			5/9/2013		4		\$0.00
Medium	Work In Progress				5/9/2013 7:48:53 AM				
Castillo, Carlos	Need to replace wornout drill bits-replace light level meter-order 12vdc spotlight for night time power outage,order tool retrieving magnet.								
<u>Carlos Castillo</u>									
91801	Maintenance				8/24/2012		262		\$0.00
Medium	Work In Progress				8/24/2012 7:25:21 AM				
Munoz, Michael	please clean-out lint tank for custodail washing machine. the offices and warehouse smell like sewer.								
<u>Alfredo Holguin</u>									
101133	Maintenance				4/22/2013		21		\$0.00
Medium	Work In Progress				4/22/2013 7:35:04 AM				
Villalobos, David	Need replacement and worn out tools.								
<u>David Villalobos</u>									
97246	Maintenance				1/14/2013		119		\$0.00
Medium	Work In Progress				1/14/2013 9:53:38 AM				
Lozoya, Manny	NEED THREE DC1 LOCKS FOR NEW FENCED AREA AT BARRACKS THANK YOU								
<u>Ruben Ronquillo</u>									
101919	Maintenance				5/8/2013		5		\$0.00
Medium	Work In Progress				5/8/2013 12:17:08 PM				
Solis, Lorenzo	Order tools								
<u>Lorenzo Solis</u>									
99762	Maintenance				3/15/2013		59		\$0.00
Medium	Work In Progress				3/15/2013 1:15:33 PM				
Diaz, Sebastian	washbay drain at auto shop broken, replacement required.								
<u>Pete Flores</u>									
Count: 69 Work Orders			Avg. Age of WO's 62	Total for Physical Plant Complex				0	\$0.00

5/13/2013 12:31:01 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
99026	Main Building	Portables			2/28/2013		74		\$0.00
Medium	Work In Progress			2/28/2013 8:56:04 AM					
Gonzalez, Salvador		Need to weld ramp to platform in portable							
Juan Ambriz									
101644	Main Building	Classroom			5/3/2013		10		\$0.00
Medium	Work In Progress	Room #11		5/3/2013 9:32:35 AM					
Ronquillo, Ruben		Need to replace broken window in room #11							
Juan Ambriz									
101646	Main Building	Hallway/Corridor			5/3/2013		10		\$0.00
Medium	Work In Progress	6th grade		5/3/2013 9:35:49 AM					
Ronquillo, Ruben		Need to replace broken window on east exit door in the 6th grade hallway							
Juan Ambriz									
101981	Main Building	Classroom			5/9/2013		4		\$0.00
Medium	Work In Progress	Room #23		5/9/2013 3:41:16 PM					
Ambriz, Juan		Need to replace a/c motor in room #23							
Juan Ambriz									
101594	Main Building	Football Field			5/2/2013		11		\$0.00
Medium	Work In Progress			5/2/2013 11:02:03 AM					
Castillo, Carlos		We need electrical outlet for School carnival to be held on May 17, 2013 from noon to 6:15 p.m. After that time outlets maybe removed . Thank you.							
Olga Arias									
97653	Main Building	Restroom (Girls)			1/24/2013		109		\$0.00
Medium	Work In Progress	front of office		1/24/2013 2:59:49 PM					
Ontiveros, Joe		Girls restroom last stable missing missing toilet seat			Route to Joe asp reassignment 4/2/13				
Juan Ambriz									
100868	Main Building				4/11/2013		32		\$0.00
Medium	Work In Progress			4/11/2013 4:00:27 PM					
Ontiveros, Joe		WATER LEAK IN STORAGE ROOM IN RESTROOM AREA IN FRONT OF OFFICE.							
Olga Arias									
98258	Main Building				2/6/2013		96		\$0.00
Medium	Work In Progress			2/6/2013 12:06:58 PM					
Ontiveros, Joe		Problems in the girl restroom with toilet leaking as per custodian			Route to Joe asp reassignment 4/2/13				
Olga Arias									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
101606	New Wing 1/02	Classroom			5/2/2013		11		\$0.00
Medium	Work In Progress	classroom #144			5/2/2013 2:48:46 PM				
Ambriz, Juan		Need to replace lights in room							
Juan Ambriz									
101929					5/8/2013		5		\$0.00
Medium	Work In Progress				5/8/2013 3:29:47 PM				
Gonzalez, Salvador		need to repair fram and door to outside water fountains							
Carlos Hernandez									
99351					3/5/2013		69		\$0.00
Medium	Work In Progress				3/5/2013 10:52:19 AM				
Orozco, Daniel		Both serving lines do not drain properly clogging and overflowing at times. SNP Manager Emilia C. 589.2550							
Maritza Gonzalez									
99352					3/5/2013		69		\$0.00
Medium	Work In Progress				3/5/2013 10:53:59 AM				
Orozco, Daniel		Grill does not work at all. SNP Manager Emilia C. 589.2550							
Maritza Gonzalez									
99353					3/5/2013		69		\$0.00
Medium	Work In Progress				3/5/2013 10:54:23 AM				
Orozco, Daniel		Two burners on stove top do not light up. SNP Manager Emilia C. 589.2550							
Maritza Gonzalez									
98705					2/21/2013		81		\$0.00
Medium	Work In Progress				2/21/2013 8:07:53 AM				
Orozco, Daniel		OVENS ARE ACTING UP AGAIN, TAKING A LONG TIME TO HEAT. SNP MANAGER EMILIA C. 589.2550							
Maritza Gonzalez									
93203					9/25/2012		230		\$0.00
Medium	Work In Progress				9/25/2012 7:35:15 AM				
Munoz, Michael		need to install new fence w/ gates where mobil home occupant used to be. security for tractors and morgan.							
Alfredo Holguin									
99224					3/3/2013		71		\$0.00
Medium	Work In Progress				3/3/2013 12:26:02 AM				
Munoz, Michael		Yearly - Riverside ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
101774					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:42 AM					
Moncayo, Fernando	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99158					3/3/2013	3/9/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:32 AM					
Moncayo, Fernando	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100353					3/31/2013	4/6/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:18 AM					
Moncayo, Fernando	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100371					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:26 AM					
Orozco, Daniel	Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101798					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:52 AM					
Orozco, Daniel	Monthly - Riverside ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100215					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:24 AM					
Hernandez, Carlos	Yearly - Riverside ES A-13 A/C Wall Mount Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99136					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:22 AM					
Hernandez, Carlos	Yearly - Riverside ES A-10 HP Rooftop Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98990					2/28/2013		74		\$0.00
Medium	Work In Progress			2/28/2013 12:28:22 AM					
Moncayo, Fernando	Monthly - Riverside ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
99350					3/5/2013		69		\$0.00
Medium	Work In Progress			3/5/2013 10:51:26 AM					
Lara, Ralph	Back screen doors are broken, difficult to open and close. SNP Manager Emilia C. 589.2550								
<u>Maritza Gonzalez</u>									
100999					4/16/2013		27		\$0.00
Medium	Work In Progress			4/16/2013 3:46:41 PM					
Ontiveros, Joe	need to repair outside water fountain broken heads								
<u>Carlos Hernandez</u>									
101467					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 8:18:29 AM					
Castillo, Carlos	need to replace switches to lights in hallway to new wing theres only one key								
<u>Carlos Hernandez</u>									
101928					5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 3:28:38 PM					
Castillo, Carlos	need to reconnect power to maaint morgan								
<u>Carlos Hernandez</u>									
101918					5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 11:46:13 AM					
Ambriz, Juan	Handicap Logo needs to be painted.(Especially the one on the northside of the campus where parent parking lot a/s/a/p) and any others throughout site.								
<u>Richard Chavez</u>									
101898		Parking Lot			5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 7:48:52 AM					
Villalobos, David	Horizon Mechanical needs to repair failed main 3" domestic backflow preventer, did not pass annual test and extensive work needs to be addressed								
<u>David Villalobos</u>									
97539		Restroom (Boys)			1/22/2013		111		\$0.00
High	Work In Progress			1/22/2013 11:40:53 AM					
Ontiveros, Joe	please unclog drains in rest rooms and remove temporary drain line. thank you					Route to Joe asp reassignment 4/2/13			
<u>Michael Munoz</u>									
90202					7/25/2012		292		\$0.00
Medium	Work In Progress			7/25/2012 3:44:33 PM					
Ontiveros, Joe	need new toilet in outside teacher bathroom upper wing					Route to Joe asp reassignment 4/2/13			
<u>Carlos Hernandez</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
101567					5/1/2013		12		\$0.00
Medium	Work In Progress			5/1/2013 3:07:13 PM					
Ontiveros, Guadalupe	in enclosed fencing area need base to compact dirt loose								
<u>Carlos Hernandez</u>									
99909					3/20/2013		54		\$0.00
Medium	Work In Progress			3/20/2013 9:32:37 AM					
Romero, Raul	NEED TO CLEAN UP ALL TRASH ALONG FENCE LINE								
<u>Jesus Estrada</u>									
99910					3/20/2013		54		\$0.00
Medium	Work In Progress			3/20/2013 9:34:01 AM					
Romero, Raul	NEED TO CLEAN UP ALL BATHROOM WALLS								
<u>Jesus Estrada</u>									
100655					4/7/2013	4/23/2013	36		\$0.00
Medium	Work In Progress			4/7/2013 12:19:08 AM					
Romero, Raul	Monthly - QRTLY BLDG INSP REPORT (RS) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100227					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:29 AM					
Moncayo, Fernando	Monthly - Riverside ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99162					3/3/2013	3/11/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:34 AM					
Moncayo, Fernando	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99160					3/3/2013	3/11/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:33 AM					
Moncayo, Fernando	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101742					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:29 AM					
Moncayo, Fernando	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
101743					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:29 AM					
Moncayo, Fernando	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
100292					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:54 AM					
Moncayo, Fernando	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
100294					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:55 AM					
Moncayo, Fernando	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
102058					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:29 AM					
Moncayo, Fernando	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
99514					3/10/2013	3/26/2013	64		\$0.00
Medium	Work In Progress			3/10/2013 12:19:07 AM					
Moncayo, Fernando	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
100633					4/7/2013	4/23/2013	36		\$0.00
Medium	Work In Progress			4/7/2013 12:18:55 AM					
Moncayo, Fernando	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
Count: 46 Work Orders			Avg. Age of WO's	52	Total for Riverside ES			0	\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		RTC - Alliance								
100905					4/12/2013		31		\$0.00	
Medium	Work In Progress			4/12/2013 4:59:39 PM						
Moncayo, Fernando	we need our sidewalks and front area of portables cleaned unable to walk on the sidewalk due to sand accumulation placed a work order 2/26/13 #98857									
<u>Gloria Delgado</u>										
100567		Classroom			4/4/2013		39		\$0.00	
Medium	Work In Progress			4/4/2013 4:56:50 PM						
Moncayo, Fernando	we need a smartboard and enfocus transfered from Mr. Hawkins to Mrs. Kim Hirsch									
<u>Gloria Delgado</u>										
100906		Classroom			4/12/2013		31		\$0.00	
Medium	Work In Progress			4/12/2013 5:04:03 PM						
Moncayo, Fernando	need a smartboard/ enfocus transfered from Mr. Hawkins to Ms. Hirsch you can come at any time to do the transfer.Placed work order 4/4/13 #100567									
<u>Gloria Delgado</u>										
100907					4/12/2013		31		\$0.00	
Medium	Work In Progress			4/12/2013 5:07:27 PM						
Castillo, Carlos	need MS. Hirsch wired for the enfocus to be mounted on the ceiling									
<u>Gloria Delgado</u>										
101434		Classroom			4/29/2013		14		\$0.00	
Medium	Work In Progress			4/29/2013 3:45:35 PM						
Castillo, Carlos	Fernando already took off the smartboard from Mr. Hawkins for Mrs. Hirsch it is ready for the electrician to connect and place a ceiling plug									
<u>Gloria Delgado</u>										
98719					2/21/2013		81		\$0.00	
Medium	Work In Progress			2/21/2013 2:11:17 PM						
Castillo, Carlos	Need to check electrical outlets in the three portables. Have electrical cords running on floor to connect computers.									
<u>Cora Ramirez</u>										
Count: 6 Work Orders		Avg. Age of WO's 38		Total for RTC - Alliance			0	\$0.00		

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		San Miguel ES								
99269					3/3/2013		71		\$0.00	
Medium	Work In Progress			3/3/2013 12:26:21 AM						
Sanchez, Raul	Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
101757					5/5/2013		8		\$0.00	
Medium	Work In Progress			5/5/2013 12:24:35 AM						
Sanchez, Raul	Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
101311	Cafeteria				4/25/2013		18		\$0.00	
Medium	Work In Progress			4/25/2013 10:57:32 AM						
Lozoya, Manny	All doors between kitchen and dinning area need to lock. one door needs adjustment because it is not locking.									
<u>Alfredo Holguin</u>										
Count: 3 Work Orders		Avg. Age of WO's 32		Total for San Miguel ES			0	\$0.00		

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa ES

97635	Main Building	Stairway			1/24/2013		109		\$0.00
Medium	Work In Progress	Art portable			1/24/2013 9:12:56 AM				
Gonzalez, Salvador	A ramp is needed at the entrance of the Art portable. Thank you.								

Rita Mendez

101160	Main Building	Classroom			4/22/2013		21		\$0.00
Medium	Work In Progress	Room 308			4/22/2013 11:15:54 AM				
Prospero, Manuel	please mount maps on wall in classroom.								

Melynda Menchaca

101042	Main Building	Office			4/17/2013		26		\$0.00
Medium	Work In Progress	ART			4/17/2013 3:41:34 PM				
Prospero, Manuel	MS. JOHNSON NEEDS FOR ART BOARDS TO BE TAKEN TO CHAPARRAL MIDDLE SCHOOL (FOR ART FAIR) ON 4/25 AND HAVE THEM SET UP. ALSO, TAKEN DOWN ON 4/29/13.								

Rita Mendez

97636	Main Building	Portables			1/24/2013		109		\$0.00
Medium	Work In Progress	FRONT AREA			1/24/2013 9:28:16 AM				
Munoz, Michael	PLEASE SET UP MORGAN BUILDING ACROSS THE ART PORTABLE. THIS BUILDING WILL BE USED AS STORAGE FOR ART SUPPLIES. ALSO, PLEASE INSTALL ELECTRICITY IN THE BLDG. THANK YOU.								

Rita Mendez

100682	Main Building	Cafeteria			4/8/2013		35		\$0.00
Medium	Work In Progress	swamp cooler			4/8/2013 2:39:42 PM				
Ambriz, Juan	Need to repair leaky valves for swamp coolers								

Juan Ambriz

101607	Main Building	Hallway/Corridor			5/2/2013		11		\$0.00
Medium	Work In Progress				5/2/2013 2:54:35 PM				
Ambriz, Juan	Need to check exhaust fan in hallway								

Juan Ambriz

100442	Main Building				4/2/2013		41		\$0.00
Medium	Work In Progress	maint. storage			4/2/2013 2:55:32 PM				
Ambriz, Juan	Need to Install shelves in maint. storage morgan								

Juan Ambriz

98214	Main Building	Cafeteria			2/5/2013		97		\$0.00
Medium	Work In Progress	Kitchen			2/5/2013 3:18:42 PM				
Ontiveros, Joe	Need to replace faucets in kitchen				Route to Joe asp reassignment 4/2/13				
Juan Ambriz									

5/13/2013 12:31:01 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa ES

97536	Main Building	Athletic Field			1/22/2013		111		\$0.00
Medium	Work In Progress	OUTSIDE CASA		1/22/2013 10:24:14 AM					
Ontiveros, Joe		WATER FOUNTAIN IS LEAKING. PLEASE CHECK.				Route to Joe asp reassignment 4/2/13			
		THANKS.							

Rita Mendez

99828	Main Building	Parking Lot			3/18/2013		56		\$0.00
Medium	Work In Progress			3/18/2013 3:32:01 PM					
Ambriz, Juan		Need to repaint parking lines							

Juan Ambriz

97399	Main Building	Cafeteria			1/16/2013		117		\$0.00
Medium	Work In Progress	cafeteria		1/16/2013 1:25:53 PM					
Castillo, Carlos		PLEASE CHECK THE LIGHTS IN THE CAFETERIA. THERE ARE 3 LIGHTS THAT DO NOT WORK. PLEASE CHECK FOR MISSING LIGHTS ALSO, (WERE SUPPOSED TO BE REPLACED LAST SCHOOL YEAR). SECOND REQUEST. THANKS							

Rita Mendez

96473	Main Building	Cafeteria			12/11/2012		153		\$0.00
Medium	Work In Progress	CAFETERIA		12/11/2012 11:24:42					
Castillo, Carlos		A NEW LIGHT FIXTURE IS NEEDED IN THE CAFETERIA. THE OTHER WAS BROKEN AND HAD TO BE REMOVED. THANKS.							

Rita Mendez

96474	Main Building	Cafeteria			12/11/2012		153		\$0.00
Medium	Work In Progress	CAFETERIA		12/11/2012 11:27:48					
Castillo, Carlos		THE LIGHTS IN THE CAFETERIA NEED TO BE CHECKED. NOT ALL OF THEM ARE WORKING. THANKS.							

Rita Mendez

101655	Main Building	Exterior			5/3/2013		10		\$0.00
Medium	Work In Progress			5/3/2013 3:31:34 PM					
Castillo, Carlos		Need to check electrical outside breakers keep tripping							

Juan Ambriz

101800					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:53 AM					
Orozco, Daniel		Monthly - Santa Teresa ES Fire Suppression Insp. - Refer to PM schedule details.							

Margret Villalobos

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
100372					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:26 AM					
Orozco, Daniel	Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101776					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:43 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99225					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:02 AM					
Munoz, Michael	Yearly - Santa Teresa ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97255					1/14/2013		119		\$0.00
Medium	Work In Progress			1/14/2013 12:59:56 PM					
Orozco, Daniel	AS PER INSPECTION PIPES ON DISHWASHER AND STAND NEEDS TO BE FIXED.SNP MANAGER MARINA R. 589.3439								
<u>Maritza Gonzalez</u>									
101850					5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 4:19:49 PM					
Orozco, Daniel	HAND SINK NEAR VEGETABLE SINK- NO COLD WATER, IT WAS SHUT OFF DUE TO A LEAK. SNP MANAGER MARINA R. 589.3439								
<u>Maritza Gonzalez</u>									
101851					5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 4:21:17 PM					
Orozco, Daniel	DISHWASHER HAS 2 LEAKS ONPIPIPES. SNP MANAGER MARINA R. 589.3439								
<u>Maritza Gonzalez</u>									
102068					5/13/2013		0		\$0.00
High	Work In Progress			5/13/2013 8:24:20 AM					
Carrasco, Danny	no water to site. need tank and dispensers.								
Alfredo Holguin									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
95724		Restroom (Boys)			11/20/2012		174		\$0.00
Medium	Work In Progress	CASA AZUL		11/20/2012 3:14:15 PM					
Marquez, Gerardo	OUR NEW HAND DRYER IS NOT WORKING PROPERLY. IT WAS TURNING ON AND STAYING ON BY ITSELF. IT WAS TURNED OFF COMPLETELY. PLEASE CHECK. THANKS.								
Rita Mendez									
102059					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:30 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
100644					4/7/2013	4/23/2013	36		\$0.00
Medium	Work In Progress			4/7/2013 12:19:01 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
99687		Parking Lot			3/14/2013		60		\$0.00
Medium	Work In Progress	Vehicle #141		3/14/2013 8:18:38 AM					
Flores, Pete	Vehicle #141 needs service overheating								
Juan Ambriz									
100649					4/7/2013	4/23/2013	36		\$0.00
Medium	Work In Progress			4/7/2013 12:19:04 AM					
Diaz, Pablo	Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.								
Margret Villalobos									
94165		Athletic Field			10/15/2012		210		\$0.00
Medium	Work In Progress	BACK FIELD		10/15/2012 3:28:57 PM					
Ontiveros, Guadalupe	PLEASE FILL OUT ALL HOLES WITH DIRT IN THE BACK FIELDS. THANKS.								
Rita Mendez									
101727					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:23 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
101728					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:23 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

5/13/2013 12:31:01 PM

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: Santa Teresa ES										
101726					5/5/2013		8		\$0.00	
Medium	Work In Progress			5/5/2013 12:24:22 AM						
Ambriz, Juan	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
100279					3/31/2013	4/8/2013	43		\$0.00	
Medium	Work In Progress			3/31/2013 12:32:49 AM						
Ambriz, Juan	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
99166					3/3/2013		71		\$0.00	
Medium	Work In Progress			3/3/2013 12:25:36 AM						
Ambriz, Juan	Yearly - Santa Teresa ES A-10 HEAT PUMPS (ANNUAL) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
100189					3/31/2013		43		\$0.00	
Medium	Work In Progress			3/31/2013 12:32:14 AM						
Ambriz, Juan	Monthly - Santa Teresa ES-A-16 Fan Exhaust (SemiA) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
Count: 34 Work Orders		Avg. Age of WO's 59		Total for Santa Teresa ES			0	\$0.00		

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
100210					3/31/2013	4/16/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:22 AM					
Villalobos, Margret	Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.		Emailed Art, Honeywell 4/2						
Margret Villalobos									
93008					9/19/2012		236		\$0.00
High	Work In Progress			9/19/2012 1:23:35 PM					
Mijarez, Jaime	gnats are back, please check above ceiling tiles, ducting in ms. panthers classroom and surrounding classrooms for any signs of population. thank you								
Michael Munoz									
98883		Athletic Field			2/26/2013		76		\$0.00
Medium	Work In Progress			2/26/2013 12:43:31 PM					
Mijarez, Jaime	Coach Bailon wanted some paint to freshen up his dugout. He would like to get 5 gallons of paint. Also the ceiling of the dugout is coming apart it needs to be hammered down.								
William Dickson									
99398					3/6/2013		68		\$0.00
Medium	Work In Progress			3/6/2013 10:34:45 AM					
Castillo, Carlos	SECURITY GUARDS ARE REQUESTING THAT ALL BURNT OUT LIGHT BULBS BE CHANGED OUT @ FRONT PARKING LOT. THANKS.								
Gerardo Marquez									
97816					1/29/2013		104		\$0.00
Medium	Work In Progress			1/29/2013 10:09:05 AM					
Castillo, Carlos	1/28/13 NEED TO INSTALL AN ELECTRICAL OUTLET IN DUGS OUTS @ GIRLS SOFTBALL FIELD. CURRENTLY AN EXTENSION CORD FED THROUGH A HOLE MADE IN THE CINDERBLOCK IS BEING USED AND ISNT SAFE. THANKS.								
Gerardo Marquez									
101638					5/3/2013		10		\$0.00
Medium	Work In Progress			5/3/2013 8:37:16 AM					
Ontiveros, Joe	5/3/13 TOILETS IN GIRLS RRM. IN 300 WING ARE BACKED UP. TRIED PLUNGER, AND CLOSET AUGER. STILL HAVING PROBLEM. NEED PLUMBER TO ASSIST. THANKS.								
Gerardo Marquez									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
93291		Football Field			9/26/2012		229		\$0.00
Medium	Work In Progress			9/26/2012 3:02:39 PM					
Castillo, Carlos		Need permanent electrical set-up or better and safer temporary for half-time music.							
Carlos Castillo									
98346		Parking Lot			2/11/2013		91		\$0.00
Medium	Work In Progress			2/11/2013 11:07:12 AM					
Marquez, Gerardo		Need to get some white paint to mark off a no parking area.							
William Dickson									
100663		Parking Lot			4/7/2013		36		\$0.00
Medium	Work In Progress			4/7/2013 4:38:59 PM					
Marquez, Gerardo		Need to paint white arrows in the parking lot for cars to enter one way and leave one way. Safety issue. Will ease congestion in the mornings and afternoons. Need white paint.							
William Dickson									
92161		Parking Lot			8/31/2012		255		\$0.00
Medium	Work In Progress	MR.		8/31/2012 1:15:00 PM					
Marquez, Gerardo		PAINT THE 45, 35, 25 YARD LINE ON THE PARKING LOT. BAND NEEDS IT FOR AFTER SCHOOL REHEARSAL. ANYWAY IF IT COULD BE DONE ASAP.							
Marylou Jimenez									
92523					9/7/2012		248		\$0.00
Medium	Work In Progress			9/7/2012 11:28:42 AM					
Ontiveros, Joe		Coach Dotson and Coach Bennet gym area showers have no water. Please check with Gerry.				Route to Joe asp reassignment 4/2/13			
Jaime Mijarez									
101673					5/5/2013	5/8/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:00 AM					
Marquez, Gerardo		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.							
Margret Villalobos									
100165					3/31/2013	4/3/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:03 AM					
Marquez, Gerardo		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.							
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
99168					3/3/2013	3/6/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:37 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92205					9/2/2012	9/5/2012	253		\$0.00
Medium	Work In Progress			9/2/2012 12:21:20 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99212					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:56 AM					
Munoz, Michael	Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
92273					9/2/2012		253		\$0.00
Medium	Work In Progress			9/2/2012 12:21:46 AM					
Munoz, Michael	Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97572					1/22/2013		111		\$0.00
Medium	Work In Progress			1/22/2013 3:52:53 PM					
Ontiveros, Joe	Old gym a/c water supply. Locate water supply line to install a new shutoff valve. The existing valve is old and won't shutoff completely.		Route to Joe asp reassignment 4/2/13						
<u>Jaime Mijarez</u>									
93789					10/3/2012		222		\$0.00
Medium	Work In Progress			10/3/2012 12:40:25 PM					
Ontiveros, Joe	boys and girls restroom in the 300 hallway need new toilet seats as well as the girls restrooms in the main hallway.		Route to Joe asp reassignment 4/2/13						
<u>Jorge Perez</u>									
93711					10/1/2012		224		\$0.00
Medium	Work In Progress			10/1/2012 12:03:32 PM					
Ontiveros, Joe	Restrooms in the main hallway Boy and girls need to adjust or replace toilet seats as well as the restroom in the 300 hallway those need to be replaced.		Route to Joe asp reassignment 4/2/13						
<u>Jorge Perez</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
98495					2/13/2013		89		\$0.00
Medium	Work In Progress			2/13/2013 4:00:53 PM					
Ontiveros, Joe	Football concession stand. There was no water shutoff valve or drain line installed for selling area a/c. Had to find a way to close the water. Will need to install a shutoff valve and drain line.		Route to Joe asp reassignment 4/2/13						
<u>Jaime Mijarez</u>									
101927		Athletic Field			5/8/2013		5		\$0.00
High	Work In Progress			5/8/2013 3:25:50 PM					
Vasquez, Jose	need repair kit to fix football areas that where not seal correct. for S.T.H.S and G.H.S.								
<u>Guadalupe Ontiveros</u>									
99449					3/7/2013		67		\$0.00
Medium	Work In Progress			3/7/2013 12:56:15 PM					
Ontiveros, Guadalupe	Need to paint the sign over the bleachers on the softball field. Colors would be black and turquoise. We also need the softball fence changed so the poles are on the outside. The way it is now is a safety hazard.								
<u>William Dickson</u>									
100635					4/7/2013	4/23/2013	36		\$0.00
Medium	Work In Progress			4/7/2013 12:18:56 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100199					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:18 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS C-12 Chm Feeder Semimntly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100200					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:18 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100201					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:18 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
98986					2/28/2013	3/31/2013	74		\$0.00
Medium	Work In Progress			2/28/2013 12:28:20 AM					
Marquez, Gerardo	Yearly - Santa Teresa HS C-11 Evap Coolers Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100773					4/10/2013		33		\$0.00
Medium	Work In Progress			4/10/2013 8:22:26 AM					
Ambriz, Jose	NEED TO REPLACE AC UNITS IN FOLLOWING LOCATIONS. ATHLETICS OFFICE AT AUXILLARY GYM. ADMINISTRATION LOBBY RM. 515. (UNIT ALREADY HERE) 600 HALLWAY.								
<u>Gerardo Marquez</u>									
101854					5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 9:07:50 PM					
Ambriz, Jose	Warrior room need digital t-stat replacement existing one is not working anymore.								
<u>Jaime Mijarez</u>									
99109					3/3/2013	3/19/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:09 AM					
Villalobos, Margret	Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.		E-mailed Honeywell 3/5						
<u>Margret Villalobos</u>									
101675					5/5/2013	5/21/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:01 AM					
Villalobos, Margret	Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99241					3/3/2013	4/3/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:09 AM					
Prospero, Manuel	Yearly - Santa Teresa HS A-10 HP Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98831					2/25/2013		77		\$0.00
Medium	Work In Progress			2/25/2013 3:37:23 PM					
Ambriz, Jose	Chiller has two failures low refrigerant temp, and high oil temp. Monitor water pressure and report to Honeywell.		Called Honeywell						
<u>Jaime Mijarez</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
97485					1/18/2013		115		\$0.00
Medium	Work In Progress			1/18/2013 11:24:53 AM					
Ambriz, Jose	Room 210. Both fan coil units are not working on the heating mode. Need to replace the 3 way valves and the actuator valves.								
<u>Jaime Mijarez</u>									
98284					2/6/2013		96		\$0.00
Medium	Work In Progress			2/6/2013 7:23:09 PM					
Ambriz, Jose	Library air-handler. Need to replace hot water side belimo valve. The stayed stuck in the open position.								
<u>Jaime Mijarez</u>									
93586					9/30/2012	10/8/2012	225		\$0.00
Medium	Work In Progress			9/30/2012 12:31:09 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93587					9/30/2012	10/8/2012	225		\$0.00
Medium	Work In Progress			9/30/2012 12:31:09 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93588					9/30/2012	10/31/2012	225		\$0.00
Medium	Work In Progress			9/30/2012 12:31:09 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99182					3/3/2013	3/11/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:43 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99183					3/3/2013	3/11/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:43 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
99809					3/18/2013		56		\$0.00
Medium	Work In Progress			3/18/2013 10:50:15 AM					
Mijarez, Jaime	We need about 11 curb stops for our parking lot. These will be used to keep cars or trucks from parking on the sidewalk, stopping wheelchairs using it. It prevents them from using sidewalk.								
<u>William Dickson</u>									
97486					1/18/2013		115		\$0.00
Medium	Work In Progress			1/18/2013 11:29:17 AM					
Mijarez, Jaime	Weight Room. Heating unit fan motor gave out, please order fan motor with housing if possible. I will take care of installing the new one.								
<u>Jaime Mijarez</u>									
98084					2/3/2013	3/6/2013	99		\$0.00
Medium	Work In Progress			2/3/2013 12:22:38 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98082					2/3/2013	2/11/2013	99		\$0.00
Medium	Work In Progress			2/3/2013 12:22:37 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98083					2/3/2013	2/11/2013	99		\$0.00
Medium	Work In Progress			2/3/2013 12:22:38 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90782					8/5/2012	9/5/2012	281		\$0.00
Medium	Work In Progress			8/5/2012 12:18:06 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90765					8/5/2012	8/13/2012	281		\$0.00
Medium	Work In Progress			8/5/2012 12:18:00 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
90764					8/5/2012	8/13/2012	281		\$0.00
Medium	Work In Progress			8/5/2012 12:17:59 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101725					5/5/2013	6/5/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:22 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101723					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:21 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101724					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:22 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100832					4/11/2013		32		\$0.00
Medium	Work In Progress			4/11/2013 10:03:26 AM					
Mijarez, Jaime	Boys football room. A piece of sheet metal on the side of the locker is coming off								
<u>Jorge Perez</u>									
100276					3/31/2013	5/1/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:48 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100277					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:48 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100278					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:48 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
99184					3/3/2013	4/3/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:44 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91802					8/24/2012		262		\$0.00
Medium	Work In Progress			8/24/2012 7:27:50 AM					
Mijarez, Jaime	Water fountain located at the end of the 300 hallways is not working. And the water fountain in the back hall way that connects to the 300 is just stays running when power cord is connected.								
<u>Jorge Perez</u>									
92249					9/2/2012	9/10/2012	253		\$0.00
Medium	Work In Progress			9/2/2012 12:21:37 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101945		Athletic Field			5/8/2013		5		\$0.00
High	Work In Progress			5/8/2013 3:53:15 PM					
Ontiveros, Guadalupe	We need a fieldsweeper with groomer to be able to maintain fields.								
<u>Guadalupe Ontiveros</u>									
100225					3/31/2013	4/8/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:28 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
96808					1/6/2013	1/14/2013	127		\$0.00
Medium	Work In Progress			1/6/2013 12:23:56 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99598					3/12/2013		62		\$0.00
Medium	Work In Progress			3/12/2013 2:53:51 PM					
Marquez, Gerardo	Room 807 is used to fire up ceramic bowls and they use clay. The teacher needs a 200 ft water hose to water down the room and remove the clay. He would be using the custodian closet to hook up the hose.								
<u>William Dickson</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
101748					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:31 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99165					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:35 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
93178		Classroom			9/24/2012		231		\$0.00
Medium	Work In Progress	VARIETY OF		9/24/2012 2:38:32 PM					
Marquez, Gerardo	SEVERAL ROOM NEED BRACKETS TO BE MOUNTED ON WALL FOR CLASSROOM FLAGS: MR. RINCON ROOM #801 2 BRACKETS MR. FELIX ROOM #505 2 BRACKETS MR. STOUT ROOM #509 2 BRACKETS RECEPTIONIST AREA NEEDS 2 BRACKETS MR. BAILEY ROOM #406 NEEDS 2 BRACKETS MR. CHAMPAGNE WELDING PORTABLE NEEDS 2 BRACKETS ROOM #301 NEEDS 2 BRACKETS								
<u>Marylou Jimenez</u>									
96225					12/4/2012		160		\$0.00
Medium	Work In Progress			12/4/2012 9:24:33 AM					
Marquez, Gerardo	NEED TO REPLACE BURNT OUT LIGHT BULBS IN CUSTODIAL CLOSET 300 WING.								
<u>Gerardo Marquez</u>									
97814					1/29/2013		104		\$0.00
Medium	Work In Progress			1/29/2013 10:04:07 AM					
Marquez, Gerardo	NEED TO REPLACE LIGHT FIXTURE IN STORAGE RM. @ GIRLS SOFTBALLFIELD DUGOUT. THANKS.								
<u>Gerardo Marquez</u>									
92398					9/5/2012		250		\$0.00
Medium	Work In Progress			9/5/2012 7:39:21 AM					
Marquez, Gerardo	3 urinals in the outside concession stand are leaking water when flushed.								
<u>Jorge Perez</u>									
92657					9/11/2012		244		\$0.00
Medium	Work In Progress			9/11/2012 8:11:10 AM					
Marquez, Gerardo	need to replace 2 ceiling tiles in the main lobby. as well in room 403. No ceiling tiles are in place due to the rain over the weekend.								
<u>Jorge Perez</u>									
5/13/2013 12:31:02 PM									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
92204					9/2/2012		253		\$0.00
Medium	Work In Progress			9/2/2012 12:21:19 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
91609					8/21/2012		265		\$0.00
Medium	Work In Progress			8/21/2012 9:55:17 AM					
Marquez, Gerardo	NEED TO REPLACE WINDOW BLINDS IN 300 WING.								
<u>Gerardo Marquez</u>									
91619					8/21/2012		265		\$0.00
Medium	Work In Progress	MARY		8/21/2012 12:09:36 PM					
Marquez, Gerardo	NEED TO HAVE 2 SECURITY MIRRORS HUNG IN BACK OF LIBRARY.								
<u>Marylou Jimenez</u>									
100879					4/12/2013		31		\$0.00
Medium	Work In Progress			4/12/2013 9:00:24 AM					
Marquez, Gerardo	NEED TO SERVICE AC'S FOR COOLING SEASON.								
<u>Gerardo Marquez</u>									
100284					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:51 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97001					1/8/2013		125		\$0.00
Medium	Work In Progress			1/8/2013 9:18:30 AM					
Gonzalez, Salvador	Railling to exterior stairway going from athletic dressing rooms to concession stand was damaged. We had to remove it, might need to fabricate a new one or repair if possible.								
<u>Jaime Mijarez</u>									
99808					3/18/2013		56		\$0.00
Medium	Work In Progress			3/18/2013 10:44:37 AM					
Briones, Enrique	We need a big truck here at ST to haul off some unwanted chairs,sofas, and desk located in the vocational area. Would like to get this done over the spring break.								
William Dickson									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
100680					4/8/2013		35		\$0.00
Medium	Work In Progress			4/8/2013 1:16:13 PM					
Gonzalez, Salvador	(Guard shack) Mr. Dickson wants two post with chain welded on one post and hook on the other post. Chain will run across both post to stop visitors at exit side and collect visitor badges.								
<u>Jaime Mijarez</u>									
93073					9/20/2012		235		\$0.00
Medium	Work In Progress			9/20/2012 12:56:13 PM					
Orozco, Daniel	SANIZER ON DISHWASHER NOT WORKING, AS PER ECO LAB IT HAS TO DO WITH THE WATER PRESSURE. SNP MANAGER OLGA B. 589.5332								
<u>Maritza Gonzalez</u>									
98875		Athletic Field			2/26/2013		76		\$0.00
Medium	Work In Progress			2/26/2013 10:39:16 AM					
Marquez, Gerardo	Last year the concession stand door was broken into and coach would like to replace it with a metal door for safety. Need to be installed soon. Thanks!				2/28 - Route to Gerry asp	Mike			
<u>William Dickson</u>									
97918					1/31/2013		102		\$0.00
Medium	Work In Progress			1/31/2013 8:07:27 AM					
Marquez, Gerardo	NEED TO REPLACE 13 BROKEN/MISSING PLASTIC COVERS @ FIRE EXTINGUISHER STATIONS. ALSO NEED TO REPLACE TAGS. 36 TOTAL. THANKS								
<u>Gerardo Marquez</u>									
93667					9/30/2012	10/6/2012	225		\$0.00
Medium	Work In Progress			9/30/2012 12:31:44 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101768					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:39 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100354					3/31/2013	4/6/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:18 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
99167					3/3/2013	3/9/2013	71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:36 AM					
Marquez, Gerardo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99235					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:07 AM					
Munoz, Michael	Yearly - Santa Teresa HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100373					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:27 AM					
Orozco, Daniel	Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100664					4/8/2013		35		\$0.00
Medium	Work In Progress			4/8/2013 7:44:42 AM					
Carbajal, Jimmy	Extractor #9909 Is not working properly Has weak suction and sprayer doesnt spray.								
<u>Jorge Perez</u>									
100666					4/8/2013		35		\$0.00
Medium	Work In Progress			4/8/2013 7:47:20 AM					
Carbajal, Jimmy	Extractor # 2261 is not working properly, has weak suction and the sprayer isnz't spraying								
<u>Jorge Perez</u>									
94657		Athletic Field			10/26/2012		199		\$0.00
High	Work In Progress			10/26/2012 2:57:54 PM					
Garcia, Jose	JD Tractor is leaking from front axle.								
<u>Guadalupe Ontiveros</u>									
94656		Athletic Field			10/26/2012		199		\$0.00
Medium	Work In Progress			10/26/2012 2:55:46 PM					
Ontiveros, Guadalupe	JD 997 Mower will not start.								
<u>Guadalupe Ontiveros</u>									
102013					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 11:17:59 AM					
Carrasco, Danny	I need fuel for the polariz. (Maintenance Vehicle).								
<u>Jaime Mijarez</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
102018					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 12:26:25 PM					
Carrasco, Danny	NEED FUEL FOR TRUCK 107, AND BLOWERS. THANKS.								
Gerardo Marquez									
99572		Gym			3/12/2013		62		\$0.00
High	Work In Progress			3/12/2013 7:31:19 AM					
Lara, Ralph	magnetic doors by the old gym are not working and affecting the fire alarm. please check and repair. once completed let sylver in technology know. thank you								
Michael Munoz									
94151					10/15/2012		210		\$0.00
Medium	Work In Progress			10/15/2012 11:32:27					
Lara, Ralph	The electeic stops that hold the doors open in the gym area needs extensive repair before some gets hurt. The holders are falling off the wall.								
William Dickson									
101911					5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 9:27:29 AM					
Lara, Ralph	5/8/13. THE CYLINDER TO THE ONE OF THE FILING CABINETS IN THE STORAGE RM. BETWEEN RMS. 511 & 512 FELL OUT. MRS. STEVENS INFORMED US THAT SHE NEEDS TO HAVE A SECURE SPACE FOR STORING HER SCIENCE EQUIP. NEEDS TO BE PUT BACK ASAP. THANKS.								
Gerardo Marquez									
100136					3/28/2013		46		\$0.00
Medium	Work In Progress			3/28/2013 8:09:52 AM					
Carbajal, Jimmy	Shower Scrubber #6983 Doesn't power on when plugged in the wall.								
Jorge Perez									
100054					3/25/2013		49		\$0.00
Medium	Work In Progress			3/25/2013 1:51:22 PM					
Carbajal, Jimmy	Extractor #9909 and 2261 need service. they both have low suction and spayer doesnt spray					reminded Jorge that each machine needs an individual work order.			
Jorge Perez									
100062					3/25/2013		49		\$0.00
Medium	Work In Progress			3/25/2013 3:15:17 PM					
Carbajal, Jimmy	Wet and Dry #2595 doesn't turn on.								
Jorge Perez									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
100063					3/25/2013		49		\$0.00
Medium	Work In Progress			3/25/2013 3:16:40 PM					
Carbajal, Jimmy	wet and dry #2275 Needs service. doeasn't pick water up.								
Jorge Perez									
97866					1/30/2013		103		\$0.00
Medium	Work In Progress			1/30/2013 1:06:53 PM					
Munoz, Michael	WHILE DOING FIRE SPRINKLER SYSTEM INSP. WITH DIMAR REPS. FOUND THAT ENTIRE FIRE SPRINKLER SYSTEM TO VOCATIONAL BLDG. HAS NOT BEEN OPERATIONAL SINCE 2011, DUE TO BUSTED WATER LINES. NEEDS TO BE CHECKED OUT. THANKS. CHECKED OUT. THANKS.								
Gerardo Marquez									
97488	Main Building	Office			1/18/2013		115		\$0.00
Medium	Work In Progress			1/18/2013 11:39:50 AM					
Marquez, Gerardo	Need to get the Social Workers office painted								
William Dickson									
102049	Main Building	Classroom			5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 7:29:17 PM					
Lara, Ralph	Need a couple of keys MC12 and 512 so one of our teacher can enter the room. Thanks!								
William Dickson									
101462	Main Building	Library			4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 8:07:15 AM					
Briones, Enrique	Please pick up out dated equipment								
Larry Martinez									
93402	Main Building	Classroom			9/28/2012		227		\$0.00
Medium	Work In Progress			9/28/2012 2:23:27 PM					
Marquez, Gerardo	There was an announcement made by Mr. Gallegos in reference to some tables and chairs. We would like to get a few of them. We would like to get 4 rectangular and 4 round tables.								
William Dickson									
100662	Gymnasium	Gym			4/7/2013		36		\$0.00
Medium	Work In Progress			4/7/2013 4:34:14 PM					
Marquez, Gerardo	The roof that wholes the air conditioner over the old gym needs repair. Need new plywood and a facia board. It has decayed and looks ugly.								
William Dickson									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
101821	Dressing Rooms				5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 11:20:33 AM					
Ontiveros, Guadalupe	We will need another set of bleachers for the game on Friday. It has been mentioned that GHS has a 5 stack of bleachers we can borrow. We play Friday evening at 4:00.		5/6/13 - Waiting on response to e-mail from Mr. Dickson - mkv						
<u>William Dickson</u>									
98549	Main Building				2/14/2013		88		\$0.00
Medium	Work In Progress			2/14/2013 5:26:36 PM					
Mijarez, Jaime	The fan unit on the roof sounds like it is about to explode. Can we have someone look at it Thanks!								
<u>William Dickson</u>									
94785	Locker Room				10/30/2012		195		\$0.00
Medium	Work In Progress			10/30/2012 3:14:53 PM					
Marquez, Gerardo	Need paint for the dugouts for both the boys and the girls. The players will paint both dugouts.								
<u>William Dickson</u>									
100429	Cafeteria (2005)	Electrical Room			4/2/2013		41		\$0.00
Medium	Work In Progress			4/2/2013 11:20:50 AM					
Solis, Lorenzo	Cafeteria electrical room -300KVA Transformer is in bad need for cooling.Unit keeps shutting down.With hot weather approaching ,electrical room needs to be cooled down ASAP.								
<u>Carlos Castillo</u>									
99586	GYM (2009)	Athletic Field			3/12/2013		62		\$0.00
Medium	Work In Progress	Lupe Ontiveros			3/12/2013 10:23:01 AM				
Ontiveros, Guadalupe	Please pickup the fence top from the Warehouse for: Baseball - (install the fence top at) STHS Baseball								
<u>Terry Alvarado</u>									
99913					3/20/2013		54		\$0.00
Medium	Work In Progress			3/20/2013 9:43:26 AM					
Estrada, Jesus	NEED (2) GYM FLOORS TO BE RE-FINISHED (NEW - APPROX. L. - 135' X 116' -W; AUXILIARY - L -93' X 80' W)								
<u>Jesus Estrada</u>									
101801					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:54 AM					
Orozco, Daniel	Monthly - Santa Teresa HS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 113 Work Orders		Avg. Age of WO's 102		Total for Santa Teresa HS			0	\$0.00	

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
99911					3/20/2013		54		\$0.00
Medium	Work In Progress				3/20/2013 9:38:18 AM				
Estrada, Jesus	NEED GYM FLOOR TO BE RE-FINISHED (APPROX. L. - 105' X 85' -W)								
<u>Jesus Estrada</u>									
101802					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:55 AM				
Orozco, Daniel	Monthly - Santa Teresa MS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
90600	North Building	Cafeteria			8/2/2012		284		\$0.00
Medium	Work In Progress				8/2/2012 1:41:31 PM				
Prospero, Manuel	KITCHEN A/C UNID NEED TO CHANGED CIRCULATION PUMP. IS NOT WORKING.								
<u>Manuel Prospero</u>									
99450	North Building				3/7/2013		67		\$0.00
Medium	Work In Progress				3/7/2013 1:33:45 PM				
Ontiveros, Joe	As per Principal she wants new water fountains on play grounds north and south there are two old ones that need to be either fix or replace thank you..							Route to Joe asp reassignment 4/2/13	
<u>Ismael Rodriguez</u>									
98441	North Building	Restroom (Boys)			2/13/2013		89		\$0.00
Medium	Work In Progress				2/13/2013 9:07:02 AM				
Ontiveros, Joe	Five gallons of cherry mat for drains.							Route to Joe asp reassignment 4/2/13	
<u>Ismael Rodriguez</u>									
100418	North Building	Classroom			4/2/2013		41		\$0.00
Medium	Work In Progress	ROOM 1			4/2/2013 9:23:19 AM				
Prospero, Manuel	ART ROOM NEEDS TOUCH UP								
<u>Laura Parra</u>									
90913	North Building	Restroom (Girls)			8/7/2012		279		\$0.00
Medium	Work In Progress				8/7/2012 8:41:12 AM				
Castillo, Carlos	Need a electrical outlet in private restroom in north office see Mr.Rodriguez.								
<u>Ismael Rodriguez</u>									
90641	North Building	Office			8/3/2012		283		\$0.00
Medium	Work In Progress	REGISTAR			8/3/2012 8:33:52 AM				
Castillo, Carlos	NEED ELECTRICAL OUTLET IN RESTROOM-- AS PER MS LOVELACE'S REQUEST								
<u>Laura Parra</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
93976	North Building	Hallway/Corridor			10/10/2012		215		\$0.00
Medium	Work In Progress			10/10/2012 7:29:44 AM					
Castillo, Carlos	Replace electrical outlet where the water fountains connect in the north upper level wires expose thanks..								
<u>Ismael Rodriguez</u>									
101905	North Building	Stairway			5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 8:19:54 AM					
Soria, Mike	Remove sand from exterior stairways on play grounds custodians will help.								
<u>Ismael Rodriguez</u>									
97153	North Building	Parking Lot			1/11/2013		122		\$0.00
Medium	Work In Progress			1/11/2013 7:42:26 AM					
Ontiveros, Guadalupe	Remove dirt with tracter dirt build up by portable ramps and also in North main entrance patio.								
<u>Ismael Rodriguez</u>									
101549	North Building	Restroom (Girls)			5/1/2013		12		\$0.00
Medium	Work In Progress	NORTH		5/1/2013 9:30:19 AM					
Prospero, Manuel	TISSUE DISPENSER NEED TO BE REPLACED.								
<u>Laura Parra</u>									
100414	North Building	Classroom			4/2/2013		41		\$0.00
Medium	Work In Progress	ROOM 1		4/2/2013 9:13:51 AM					
Estrada, Jesus	TILE FOR BARE AREA								
<u>Laura Parra</u>									
101930	North Building	Classroom			5/8/2013		5		\$0.00
Medium	Work In Progress	ROOM 12		5/8/2013 3:30:22 PM					
Prospero, Manuel	SMART BOARD STORED IN 48A NEEDS TO BE PLACED IN ROOM 12--CRAVENS. -- RACK TO HOLD IT IS IN OLD BOOK ROOM SOUTH BLDG TOP FLOOR.								
<u>Laura Parra</u>									
102073	North Building	Classroom			5/13/2013		0		\$0.00
Medium	Work In Progress			5/13/2013 8:43:09 AM					
Carrasco, Danny	NEED 100PC S-HOOKS FOR ART TEACHER								
<u>Manuel Prospero</u>									
100484	North Building	Gym			4/3/2013		40		\$0.00
Medium	Work In Progress			4/3/2013 11:59:20 AM					
Prospero, Manuel	Manny, the a.c in gym lobby area not working.								
<u>Ismael Rodriguez</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
100421	North Building	Classroom			4/2/2013		41		\$0.00
Medium	Work In Progress	ROOM 1			4/2/2013 9:25:50 AM				
Prospero, Manuel		SET UP NEW TEACHER'S DESK							
Laura Parra									
97445	North Building	Classroom			1/17/2013		116		\$0.00
Medium	Work In Progress	BAND ROOM			1/17/2013 8:41:54 AM				
Gonzalez, Salvador		REQUESTING ROD IRON GATE OUTSIDE BAND ROOM. SAFETY ISSUE.							
Laura Parra									
102021	North Building	Classroom			5/10/2013		3		\$0.00
Medium	Work In Progress	ROOM 8			5/10/2013 1:41:32 PM				
Lara, Ralph		BACK EXIT DOOR DIFFICULT TO UNLOCK AND OPEN DOOR							
Laura Parra									
102022	North Building	Classroom			5/10/2013		3		\$0.00
Medium	Work In Progress	ROOM 8			5/10/2013 1:46:00 PM				
Lara, Ralph		BATHROOM DOOR HINGE IS BROKEN.							
Laura Parra									
101137	North Building	Custodial			4/22/2013		21		\$0.00
Medium	Work In Progress				4/22/2013 8:19:53 AM				
Carrasco, Danny		Fuel for truck #88.							
Ismael Rodriguez									
101403	North Building	Custodial			4/29/2013		14		\$0.00
Medium	Work In Progress				4/29/2013 8:51:33 AM				
Carbajal, Jimmy		Jimmy I need a pouch for cell phone.							
Ismael Rodriguez									
91685	South Building	Restroom (Boys)			8/22/2012		264		\$0.00
Medium	Work In Progress				8/22/2012 10:58:29 AM				
Prospero, Manuel		Broken water valve to flushvalve needs to be replaced							
Manuel Prospero									
102074	South Building	Classroom			5/13/2013		0		\$0.00
Medium	Work In Progress				5/13/2013 8:45:26 AM				
Lara, Ralph		NEED EXTRA KEY FOR MYSELF DC21.							
Manuel Prospero									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
101495	South Building	Parking Lot			4/30/2013		13		\$0.00
Medium	Work In Progress	FRANK			4/30/2013 3:16:51 PM				
Lara, Ralph	1. Remove padlock from entrance gate. 2. Lubricate for fix all padlocks in the school. Having trouble unlocking. 3. If possible would like to keep lubrication spray for future use.								
<u>Laura Parra</u>									
102015	South Building	Restroom (Girls)			5/10/2013		3		\$0.00
Medium	Work In Progress				5/10/2013 11:54:02 AM				
Ontiveros, Joe	FLASH VALVE ON GRILS BATROOMS TOILET IS BED								
<u>Manuel Prospero</u>									
101027	South Building	Classroom			4/17/2013		26		\$0.00
Medium	Work In Progress				4/17/2013 2:37:44 PM				
Ambriz, Jose	WE LOOSE COMUNICATION SOUTH BUILDING UNIDS.								
<u>Manuel Prospero</u>									
97526	Gym (1997)				1/22/2013		111		\$0.00
Medium	Work In Progress				1/22/2013 7:56:32 AM				
Prospero, Manuel	please replace missing hvac louvers and clean the remaining ones. will need to replace the small rectangular and clean the larger 24 x 24. thank you								
<u>Michael Munoz</u>									
101966	Gym (1997)	Gym			5/9/2013		4		\$0.00
Medium	Work In Progress				5/9/2013 12:20:25 PM				
Ambriz, Jose	HAVIN PROBLEM WIHT ICE MACHINE CONSSETION STAND (GYM AREA).								
<u>Manuel Prospero</u>									
101953	Gym (1997)	Gym			5/9/2013		4		\$0.00
Medium	Work In Progress				5/9/2013 7:51:27 AM				
Castillo, Carlos	WE HAVE A ELECTRIC PROBLEM WIHT BIG A/C ON GYM .								
<u>Manuel Prospero</u>									
98950	Gym (1997)	Dressing Room			2/27/2013		75		\$0.00
Medium	Work In Progress	GIRLS			2/27/2013 3:23:44 PM				
Castillo, Carlos	LIGHTS BURNED OUDT IN THE GIRLS LOCKER ROOM CAGE AREA								
<u>Laura Parra</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
97437	Gym (1997)				1/17/2013		116		\$0.00
High	Work In Progress				1/17/2013 6:40:48 AM				
Soria, Mike	please remove sand along curb in the parking lot and remove weeds and sand that are around light poles in the the parking lot as well, also please remove sand on side walk that leads from the parking lot to the gym and clean debre ie soda cans, weeds, rocks etc along this areas well and cleand sidewalk to entrance to gym and surrounding areas. thank you								
<u>Michael Munoz</u>									
98947	Gym (1997)	Athletic Field			2/27/2013		75		\$0.00
Medium	Work In Progress				2/27/2013 2:27:05 PM				
Ontiveros, Guadalupe	CENTER CIRCLE FOR TRACK AND FIELD PRACTICE								
<u>Laura Parra</u>									
101762					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:37 AM				
Prospero, Manuel	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99230					3/3/2013		71		\$0.00
Medium	Work In Progress				3/3/2013 12:26:04 AM				
Munoz, Michael	Yearly - Santa Teresa MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100374					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress				3/31/2013 12:33:27 AM				
Orozco, Daniel	Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101083					4/18/2013		25		\$0.00
Medium	Work In Progress				4/18/2013 3:38:13 PM				
Flores, Pete	POLARIS IS NOT WORKING. NEED SERVICE.								
<u>Manuel Prospero</u>									
100052					3/25/2013		49		\$0.00
Medium	Work In Progress				3/25/2013 12:25:01 PM				
Prospero, Manuel	I NEED MANIFULD GAUGES FOR READING PRESSURES IN A/C UNITS LORENZO SOLIS..								
Manuel Prospero									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
101697					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:10 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
101698					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:11 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
101699					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:11 AM					
Prospero, Manuel	Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
101700					5/5/2013	6/5/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:11 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
91549		Classroom			8/20/2012		266		\$0.00
Medium	Work In Progress	ROOM 1		8/20/2012 12:21:59 PM					
Prospero, Manuel	1. PAPER TOWEL DISPENSER ABOVE SINKS 2. PLACE TILES ON BARE CONCRETE FLOOR.								
Laura Parra									
99745					3/15/2013		59		\$0.00
Medium	Work In Progress			3/15/2013 8:26:09 AM					
Ambriz, Jose	I NEED SOME CIRCULATING PUMP. PL-36 IRON BODY PUMP.								
Manuel Prospero									
99746					3/15/2013		59		\$0.00
Medium	Work In Progress			3/15/2013 8:28:59 AM					
Ambriz, Jose	I NEED SOME CONDENSATE PUMPS LITTLE GIANT FOR HP.								
Manuel Prospero									
100176					3/31/2013	4/16/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:08 AM					
Prospero, Manuel	Monthly - Santa Teresa MS A1(Wall Refr.E/H)(Semi) - Refer to PM schedule details.								
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
100177					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:08 AM					
Prospero, Manuel		Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.							
Margret Villalobos									
98143					2/4/2013		98		\$0.00
Medium	Work In Progress			2/4/2013 8:18:34 AM					
Castillo, Carlos		Need to replace light fixture lenses -8ea.							
Carlos Castillo									
99185					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:25:44 AM					
Mijarez, Jaime		Yearly - Santa Teresa MS A10 (Heat Pump)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
Count: 49 Work Orders		Avg. Age of WO's 67		Total for Santa Teresa MS			0	\$0.00	

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
100065					3/25/2013		49		\$0.00
Medium	Work In Progress			3/25/2013 3:19:35 PM					
Solis, Lorenzo		need to replace a/c unit room 33 (43)							
Carlos Hernandez									
100550					4/4/2013		39		\$0.00
Medium	Work In Progress			4/4/2013 3:33:44 PM					
Castillo, Carlos		need ballest replaced room 28							
Carlos Hernandez									
100551					4/4/2013		39		\$0.00
Medium	Work In Progress			4/4/2013 3:34:45 PM					
Castillo, Carlos		need balest replaced room 16							
Carlos Hernandez									
100687					4/8/2013		35		\$0.00
Medium	Work In Progress			4/8/2013 3:22:29 PM					
Castillo, Carlos		need to replace several ballest in art portable							
Carlos Hernandez									
101605		Classroom			5/2/2013		11		\$0.00
Medium	Work In Progress			5/2/2013 2:08:55 PM					
Castillo, Carlos		contractors are replacing existing damaged roof. 2 light fixtures were damaged due to leaks. please check site for appropriate light fixtures. if in stock please hand over to contractor for installation. if not please order and install once received. thank you							
Michael Munoz									
101284					4/24/2013		19		\$0.00
Medium	Work In Progress			4/24/2013 3:33:32 PM					
Ontiveros, Joe		need to unclog water fountian north side							
Carlos Hernandez									
101037					4/17/2013		26		\$0.00
Medium	Work In Progress	MS. FLORES -		4/17/2013 3:29:36 PM					
Ontiveros, Joe		AS PER MS. FLORES - THERE IS A WATER LEAK ON TOP OF THE CABINET. NOT SURE WHERE IT IS COMING FROM. THANK YOU.							
David Avila									
100998					4/16/2013		27		\$0.00
Medium	Work In Progress			4/16/2013 3:45:32 PM					
Ontiveros, Joe		need to repair outside water fountain							
Carlos Hernandez									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
102078					5/13/2013		0		\$0.00
Medium	Work In Progress	MS. RUBIO -		5/13/2013 9:53:40 AM					
Ambriz, Jose	AS PER MS. RUBIO - LOW COOL SETTING ON AIR CONDITIONER IS NOT WORKING ONLY THE HIGH SCHOOL, PLEASE CHECK. THANK YOU.								
David Avila									
101810		Cafeteria			5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 7:57:38 AM					
Lara, Ralph	BUENOS DIAS MR LARA TENEMOS UN CANDADO K NO ABRE SI NOS PUEDE HACER EL FAVOR D REVISARLO GRACIAS								
Valeria Castillo									
94495					10/23/2012		202		\$0.00
Medium	Work In Progress			10/23/2012 3:40:31 PM					
Flores, Pete	need new tires for 970 john deere tractor								
Carlos Hernandez									
101475					4/30/2013		13		\$0.00
Medium	Work In Progress	GIRLS		4/30/2013 9:54:15 AM					
Hernandez, Carlos	CARLOS PLEASE CHECK FAUCET IN GIRLS RESTROOM IT IS LEAKING ALOT. THANK YOU.								
David Avila									
101745					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:30 AM					
Hernandez, Carlos	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
101746					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:30 AM					
Hernandez, Carlos	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
101215					4/23/2013		20		\$0.00
Medium	Work In Progress	CLASSROOM		4/23/2013 1:43:27 PM					
Ronquillo, Ruben	AS PER MS. KENNON - THE BOTTOM WINDOW BY THE CLASSROOM DOOR IS BROKEN. IT LOOKS LIKE IT WAS KICKED OR DAMAMGED IN SOME WAY. IT NEEDS TO BE PREPARED FOR SAFETY/WEATHER ISSUES. THANK YOU.								
David Avila									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
102060					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:30 AM					
Hernandez, Carlos	Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100375					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:27 AM					
Orozco, Daniel	Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
99226					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:02 AM					
Munoz, Michael	Yearly - Sunland Park ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101771					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:40 AM					
Hernandez, Carlos	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
98171					2/4/2013		98		\$0.00
Medium	Work In Progress			2/4/2013 4:17:09 PM					
Orozco, Daniel	PLEASE CHECK STAND PIECE OF METAL IS MISSING.SNP MANAGER IGNACIA C. 589.2545								
<u>Maritza Gonzalez</u>									
98172					2/4/2013		98		\$0.00
Medium	Work In Progress			2/4/2013 4:17:37 PM					
Orozco, Daniel	OVENS NEED TO BE CHECKED, NOT HOLDING TEMPERATURE.SNP MANAGER IGNACIA C. 589.2545								
<u>Maritza Gonzalez</u>									
96426					12/10/2012		154		\$0.00
Medium	Work In Progress			12/10/2012 10:09:35					
Orozco, Daniel	VEGETABLE SINK IS LEAKING. SNP MANAGER IGNACIA C. 589.2545								
<u>Maritza Gonzalez</u>									
100451					4/2/2013		41		\$0.00
Medium	Work In Progress			4/2/2013 3:40:33 PM					
Gonzalez, Salvador	need window gaurds on art and music portable								
Carlos Hernandez									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
101224					4/23/2013		20		\$0.00
Medium	Work In Progress				4/23/2013 3:16:58 PM				
Gonzalez, Salvador	need two new iron gates in north and south entrance								
Carlos Hernandez									
101803					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:56 AM				
Orozco, Daniel	Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
101809		Custodial			5/6/2013		7		\$0.00
Medium	Work In Progress				5/6/2013 7:50:46 AM				
Carbajal, Jimmy	BUENOS DIAS JIMMY TENEMOS UNA ASPIRADORA K NO SIRVE PARECE K SE KEMO SI PUEDE REVISARLA POR FAVOR GRACIAS EL NUM ES H06C000006								
Valeria Castillo									
101879					5/7/2013		6		\$0.00
Medium	Work In Progress				5/7/2013 3:41:09 PM				
Carrasco, Danny	need 10 gal desil tractor								
Carlos Hernandez									
99526					3/11/2013		63		\$0.00
Medium	Work In Progress				3/11/2013 7:46:48 AM				
Gallegos, Rafael	roof in cafe that was just repaired is leaking								
Carlos Hernandez									
101569					5/1/2013		12		\$0.00
Medium	Work In Progress				5/1/2013 3:10:34 PM				
Carrasco, Danny	need 10 gal lawn mower								
Carlos Hernandez									
101968					5/9/2013		4		\$0.00
Medium	Work In Progress				5/9/2013 12:52:14 PM				
Lara, Ralph	need to replace door handle to exit doors north side or repair								
Carlos Hernandez									
101999	Main Building	Mechanical			5/10/2013		3		\$0.00
Medium	Work In Progress				5/10/2013 8:00:49 AM				
Villalobos, David	Need to replace failed backflow preventer that is corroded								
David Villalobos									
Count: 31 Work Orders			Avg. Age of WO's	37	Total for Sunland Park ES		0	\$0.00	

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
99589	Main Building	Classroom			3/12/2013		62		\$0.00
Medium	Work In Progress	203			3/12/2013 11:16:33 AM				
Lozoya, Manny		PATY VILLA, 203, NEEDS KEY REPLACEMENT 1C31							
Joanne Munoz									
100720	Main Building	Custodial			4/9/2013		34		\$0.00
Medium	Work In Progress				4/9/2013 9:22:39 AM				
Carbajal, Jimmy		Upright royal vacumme cleaner needs electrical cord and plug replaced. Will need a back up vac							
Felipe Gallegos									
101897	Main Building	Custodial			5/8/2013		5		\$0.00
Medium	Work In Progress				5/8/2013 6:55:06 AM				
Carbajal, Jimmy		Need to have electrical cord and plug replaced on Royal upright vacumme cleaner. I will need a back up in the mean time. Thank you.							
Felipe Gallegos									
101804					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:56 AM				
Orozco, Daniel		Monthly - Sunrise ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
99990					3/21/2013		53		\$0.00
Medium	Work In Progress				3/21/2013 3:10:41 PM				
Estrada, Jesus		need replace floor tile in 100 hallway							
Juan Vargas									
99227					3/3/2013		71		\$0.00
Medium	Work In Progress				3/3/2013 12:26:03 AM				
Munoz, Michael		Yearly - Sunrise ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
101777					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress				5/5/2013 12:24:43 AM				
Vargas, Juan		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
100376					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress				3/31/2013 12:33:28 AM				
Orozco, Daniel		Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
101752					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:33 AM					
Apodaca, Mario	Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
102061					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:31 AM					
Vargas, Juan	Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101144					4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 9:21:02 AM					
Ontiveros, Guadalupe	nesesita picar el sacate y poner fertilisante								
<u>Juan Vargas</u>									
101967					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 12:47:40 PM					
Ronquillo, Ruben	need aluminium blinds for cafeteria windows almon color 9- 96-w 48-L and 8- 40-w 100-L								
<u>Juan Vargas</u>									
102006					5/10/2013		3		\$0.00
Medium	Work In Progress			5/10/2013 10:10:10 AM					
Vargas, Juan	need replace 10 doors stopers in kitchen doors								
<u>Juan Vargas</u>									
101151					4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 9:36:04 AM					
Vargas, Juan	need fix irigation trees poly pipe 100 ft. hose and 20 coplin fittings 5 te 1/2 in.								
<u>Juan Vargas</u>									
101693					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:09 AM					
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101691					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:08 AM					
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
101692					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:08 AM					
Vargas, Juan	Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101020					4/17/2013		26		\$0.00
Medium	Work In Progress			4/17/2013 10:50:09 AM					
Lozoya, Manny	confers roon need change door core lock								
<u>Juan Vargas</u>									
101021					4/17/2013		26		\$0.00
Medium	Work In Progress			4/17/2013 10:51:41 AM					
Lozoya, Manny	need replace marqui locks not closed								
<u>Juan Vargas</u>									
100979					4/16/2013		27		\$0.00
Medium	Work In Progress			4/16/2013 3:06:11 PM					
Lozoya, Manny	JOANNE MUNOZ, LUNA HALLWAY COMMUNICATION ROOM, LOCK IS BROKEN NEEDS TO BE REPLACED								
<u>Joanne Munoz</u>									
101143					4/22/2013		21		\$0.00
Medium	Work In Progress			4/22/2013 9:18:53 AM					
Lozoya, Manny	luna hall comonnications closed door need fix								
<u>Juan Vargas</u>									
101496					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 3:20:52 PM					
Lozoya, Manny	portable 3 need replace lock door								
<u>Juan Vargas</u>									
101327					4/25/2013		18		\$0.00
Medium	Work In Progress			4/25/2013 3:29:18 PM					
Appelzoller, Fred	300 wing boys r.rooms need replace fouset is broke								
<u>Juan Vargas</u>									
101022					4/17/2013		26		\$0.00
Medium	Work In Progress			4/17/2013 10:54:37 AM					
Appelzoller, Fred	r.rooms next to cafeteria need replace sinks								
<u>Juan Vargas</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Sunrise ES							
100506					4/3/2013		40		\$0.00
Medium	Work In Progress				4/3/2013 3:35:24 PM				
Vallejo, Albert		need fix out side portables	lights						
Juan Vargas									
101869					5/7/2013		6		\$0.00
Medium	Work In Progress				5/7/2013 3:16:04 PM				
Vallejo, Albert		need help to fix emergency lights in 100 hall							
Juan Vargas									
102071					5/13/2013		0		\$0.00
Medium	Work In Progress				5/13/2013 8:28:30 AM				
Vargas, Juan		need repint	art room						
Juan Vargas									
Count: 27 Work Orders		Avg. Age of WO's		21	Total for Sunrise ES			0	\$0.00

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
100217					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:32:25 AM					
Orozco, Daniel	Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
97344					1/15/2013		118		\$0.00
Medium	Work In Progress			1/15/2013 2:54:22 PM					
Lozoya, Manny	NEED NEW KEYS FOR FRONT DOORS AND OUTSIDE DOORS								
<u>Danny Miranda</u>									
97761					1/28/2013		105		\$0.00
Medium	Work In Progress			1/28/2013 10:37:09 AM					
Lozoya, Manny	NEED A KEY MADE FOR ROOM 205 AND 207								
<u>Debra Facio</u>									
101591					5/2/2013		11		\$0.00
Medium	Work In Progress			5/2/2013 8:51:27 AM					
Lozoya, Manny	need to ck. key in room #102 key will not open door								
<u>Danny Miranda</u>									
97079		Office			1/9/2013		124		\$0.00
Medium	Work In Progress			1/9/2013 4:02:57 PM					
Lozoya, Manny	need doors from main lobby to corridors and cafeteria to have locks installed that can be operated from office area. Check with Alfredo Holguin if you have questions								
<u>Alfredo Holguin</u>									
101958					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 10:51:05 AM					
Ontiveros, Guadalupe	need fertilizer to spread on grass								
<u>Danny Miranda</u>									
100937					4/15/2013		28		\$0.00
Medium	Work In Progress			4/15/2013 3:07:45 PM					
Flores, Pete	NEED BOBCAT FOR 4/17/13 TO WORK COMPOSE FOR RAISED GARDENS								
<u>Danny Miranda</u>									
101909					5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 9:09:17 AM					
Flores, Pete	need blower replaced old one is at auto shop can not be repaired								
Danny Miranda									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
102062					5/12/2013	5/28/2013	1		\$0.00
Medium	Work In Progress			5/12/2013 12:21:31 AM					
Miranda, Danny	Monthly - Vado ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101722					5/5/2013		8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:21 AM					
Miranda, Danny	Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101720					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:20 AM					
Miranda, Danny	Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101721					5/5/2013	5/13/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:20 AM					
Miranda, Danny	Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101817					5/6/2013		7		\$0.00
Medium	Work In Progress			5/6/2013 9:32:27 AM					
Miranda, Danny	need to replace sprinkler to zone six								
<u>Danny Miranda</u>									
101970					5/9/2013		4		\$0.00
Medium	Work In Progress			5/9/2013 1:44:01 PM					
Miranda, Danny	need to ck room 203 and replace sleeve to heat pump								
<u>Danny Miranda</u>									
101458					4/30/2013		13		\$0.00
Medium	Work In Progress			4/30/2013 7:35:11 AM					
Miranda, Danny	need to repair gate at bus turn around								
<u>Danny Miranda</u>									
100377					3/31/2013	4/21/2013	43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:28 AM					
Orozco, Daniel	Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

1129 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
99228					3/3/2013		71		\$0.00
Medium	Work In Progress			3/3/2013 12:26:04 AM					
Munoz, Michael	Yearly - Vado ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101778					5/5/2013	5/11/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:43 AM					
Miranda, Danny	Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101805					5/5/2013	5/26/2013	8		\$0.00
Medium	Work In Progress			5/5/2013 12:24:57 AM					
Orozco, Daniel	Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
100386					3/31/2013		43		\$0.00
Medium	Work In Progress			3/31/2013 12:33:32 AM					
Munoz, Michael	Monthly - Vado ES - Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
101908					5/8/2013		5		\$0.00
Medium	Work In Progress			5/8/2013 9:06:14 AM					
,	burned vacuum motor #1176								
<u>Danny Miranda</u>									
99644	Main Building	Gym			3/13/2013		61		\$0.00
Medium	Work In Progress			3/13/2013 12:36:20 PM					
Estrada, Jesus	As per the conversation with Richard Chavez and Ms. Navarro, we will be needing to put a wood floor on the stage.					3/18/13 - Asp Mike assign to Chuy.			
<u>Debra Facio</u>									
97527	Main Building	Office			1/22/2013		111		\$0.00
Medium	Work In Progress			1/22/2013 8:30:35 AM					
Lozoya, Manny	NEED 3 F1 KEYS AND 1 STORAGE DOOR KEY								
<u>Debra Facio</u>									
Count: 23 Work Orders		Avg. Age of WO's 36		Total for Vado ES			0	\$0.00	
Count: 1129 Work Orders		Avg. Age of WO's 57		Grand Total			0	\$0.00	