	ate Range for Request Building	Dates:7/1/2012 - 6	U	•	,	omp Date Day	ys Labor	Tota Costs
Priority	Status	Area Number	Reason	Cre	ated Date/Time Actual C	omp Date Age	ed Hours	
Assigned	То	Description			Acti	on Taken		
Requester	r Name							
Location:	Alma Del	Valle Daycare						
98506					2/14/2013	11()	\$0.00
Medium	Work In Progress			2/14/	2013 7:04:32 AM			
Ontiveros,	Guadalupe	BUILDING).	OR DAYCARE SANI 2 FT WIDE, 1 FT DE	,	ONT OF			
Adam Mor Count: 1 V	ntoya Nork Orders		vg. Age of WO's 11		Total for Alma De	el Valle Daycare	0	\$0.00

	te Range for Request Building		•	•		et Comp Date Days	Labor	Tota Costs
Priority	Status	Area Number	•		eated Date/Time Actu		Hours	
Assigned	То	Description				Action Taken		
Requester	Name							
Location:	Anthony -	On Track Pre-	K (Village)					
99576					3/12/2013	84		\$0.00
Medium	Work In Progress			3/12	/2013 7:46:54 AM			
Ontiveros,	Guadalupe	build raised pla	nters					
Alfredo Ho	Iguin							
95797					11/26/2012	190		\$0.00
Medium	Work In Progress			11/26	/2012 3:48:45 PM			
Nunez, Art	uro		RE K PLAY AREA REPLACED, HAS N TOP.					
Arturo Nun	ez							
Count: 2 V	Vork Orders	A	vg. Age of WO's	137 Tot	al for Anthony - On T	ack Pre-K (Village)	0	\$0.00

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By Reason	Until Request Date T Created Date/Time /	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Anthony	ES						
102785				5/31/2013		4		\$0.00
Medium	Work In Progress			5/31/2013 12:28:51 AM				
Apodaca, I	Mario	Monthly - Antho to PM schedule		Meter Readings - Refer				
Margret Vil 95549	lalobos			11/14/2012		202		\$0.00
Medium	Work In Progress			11/14/2012 3:48:20 PM				<i>Q</i> 0100
Apodaca, I	C C			TING FOR WTAER DMESTIC WATER				
Arturo Nun 102889	ez			6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:28:59 AM	0/10/2013	2		ψ0.00
Nunez, Art	-	Monthly - Antho to PM schedule		at Test: Monthly - Refer				
Margret Vil	lalobos		details.					
102890				6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:00 AM				
Nunez, Art		Monthly - Antho PM schedule d		nsp: Monthly - Refer to				
Margret Vil 100307	lalobos			3/31/2013		65		\$0.00
Medium	Work In Progress			3/31/2013 12:33:00 AM				
Holguin, Al	C C	Monthly - Antho schedule detail		p Engine - Refer to PM				
Margret Vil	lalobos			4/00/0040				* 0.00
101396				4/29/2013		36		\$0.00
Medium	Work In Progress			4/29/2013 8:18:01 AM				
Ontiveros,	Guadalupe		sitance on zone # etting stuck, with	6 in new new sod other zones.				
Arturo Nun 98807	ez			2/25/2013		99		\$0.00
Medium	Work In Progress	SPED OFFICE		2/25/2013 10:34:38 AM				<i>Q</i> 0100
Nunez, Art	-	REMOVE CHA		GNOSTICIANS ROOM				
Margaret V	íillalobos							
98808				2/25/2013		99		\$0.00
Medium	Work In Progress	SPED OFFICE		2/25/2013 10:35:26 AM				
Nunez, Art	uro			IN DIAGNOSTIANS R BY THE DOOR				

Medium Work In Progress SPED OFFICE 2/25/2013 10:3 Nunez, Arturo REMOVE STORAGE CABINETS IN A. SANCHEZ OFFICE AND MOVE TO DIAGNOSTICIAN OFFICE Margaret Villalobos 2/ 98810 2/ Medium Work In Progress SPED OFFICE 2/25/2013 10:3 Nunez, Arturo REMOVE CABINETS FROM STORAGE ROOM AND INSTALL IN DIAGNOSTICIANS ROOM 2/ Margaret Villalobos 2/ 98611 2/ Medium Work In Progress 2/19/2013 2:5 Nunez, Arturo WATER SUPPLY LINES TO A.C. UNITS IN OLD CAF. BUILDING NEED TO BE REPLACED. Arturo Nunez 2/ 98302 2 Medium Work In Progress 2/7/2013 3:4 Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez NEED TO CHECK OUTSIDE LIGHTING ON MAIN	/25/2013 39:37 AM /19/2013	99 99 99	
Medium Work In Progress SPED OFFICE 2/25/2013 10:3 Nunez, Arturo REMOVE STORAGE CABINETS IN A. SANCHEZ OFFICE AND MOVE TO DIAGNOSTICIAN OFFICE Margaret Villalobos 2/ 98810 2/ Medium Work In Progress SPED OFFICE 2/25/2013 10:3 Nunez, Arturo REMOVE CABINETS FROM STORAGE ROOM AND INSTALL IN DIAGNOSTICIANS ROOM Margaret Villalobos 2/ 98611 2/ Medium Work In Progress 2/19/2013 2:5 Nunez, Arturo WATER SUPPLY LINES TO A.C. UNITS IN OLD CAF. BUILDING NEED TO BE REPLACED. Arturo Nunez 2 98302 2 Medium Work In Progress 2/7/2013 3:4 Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez NEED TO CHECK OUTSIDE LIGHTING ON MAIN	36:15 AM /25/2013 39:37 AM /19/2013	99	\$0.00 \$0.00
Nunez, Arturo REMOVE STORAGE CABINETS IN A. SANCHEZ OFFICE AND MOVE TO DIAGNOSTICIAN OFFICE Margaret Villalobos 2/ 98810 2/ Medium Work In Progress SPED OFFICE 2/25/2013 10:3 Nunez, Arturo REMOVE CABINETS FROM STORAGE ROOM AND INSTALL IN DIAGNOSTICIANS ROOM Margaret Villalobos 2/ 98611 2/ Medium Work In Progress 2/19/2013 2:5 Nunez, Arturo WATER SUPPLY LINES TO A.C. UNITS IN OLD CAF. BUILDING NEED TO BE REPLACED. Arturo Nunez 2/ 98302 2/7/2013 3:4 Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez NEED TO CHECK OUTSIDE LIGHTING ON MAIN	/25/2013 39:37 AM /19/2013		\$0.00
OFFICE AND MOVE TO DIAGNOSTICIAN OFFICE Margaret Villalobos 2/ 98810 2/ Medium Work In Progress SPED OFFICE 2/25/2013 10:3 Nunez, Arturo REMOVE CABINETS FROM STORAGE ROOM AND INSTALL IN DIAGNOSTICIANS ROOM 10:3 Margaret Villalobos 98611 2/ 98611 2/ Medium Work In Progress 2/19/2013 2:5 Nunez, Arturo WATER SUPPLY LINES TO A.C. UNITS IN OLD CAF. BUILDING NEED TO BE REPLACED. Arturo Nunez 2 Medium Work In Progress 2/7/2013 3:4 Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING.	39:37 AM (19/2013		\$0.00
98810 2/ Medium Work In Progress SPED OFFICE 2/25/2013 10:3 Nunez, Arturo REMOVE CABINETS FROM STORAGE ROOM AND INSTALL IN DIAGNOSTICIANS ROOM Margaret Villalobos 98611 2/ Medium Work In Progress 2/19/2013 2:5 Nunez, Arturo WATER SUPPLY LINES TO A.C. UNITS IN OLD CAF. BUILDING NEED TO BE REPLACED. Arturo Nunez 2 Medium Work In Progress 2/7/2013 3:4 Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez	39:37 AM (19/2013		\$0.00
Medium Work In Progress SPED OFFICE 2/25/2013 10:3 Nunez, Arturo REMOVE CABINETS FROM STORAGE ROOM AND INSTALL IN DIAGNOSTICIANS ROOM Margaret Villalobos 2/ 98611 2/ Medium Work In Progress 2/19/2013 2:5 Nunez, Arturo WATER SUPPLY LINES TO A.C. UNITS IN OLD CAF. BUILDING NEED TO BE REPLACED. Arturo Nunez 2 Medium Work In Progress 2/2013 2 Medium Work In Progress 2/19/2013 2 Medium Work In Progress 2/10/2013 2 Medium Work In Progress 2/7/2013 3:4 Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez Arturo Nunez	39:37 AM (19/2013		
Nunez, Arturo REMOVE CABINETS FROM STORAGE ROOM AND INSTALL IN DIAGNOSTICIANS ROOM Margaret Villalobos 2/ 98611 2/ Medium Work In Progress 2/19/2013 2:5 Nunez, Arturo WATER SUPPLY LINES TO A.C. UNITS IN OLD CAF. BUILDING NEED TO BE REPLACED. Arturo Nunez 2 98302 2 Medium Work In Progress 2/7/2013 3:4 Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez 1000000000000000000000000000000000000	/19/2013	105	
98611 2/ Medium Work In Progress 2/19/2013 2:5 Nunez, Arturo WATER SUPPLY LINES TO A.C. UNITS IN OLD CAF. BUILDING NEED TO BE REPLACED. Arturo Nunez 2 98302 2 Medium Work In Progress 2/7/2013 3:4 Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez 2		105	
Medium Work In Progress 2/19/2013 2:5 Nunez, Arturo WATER SUPPLY LINES TO A.C. UNITS IN OLD CAF. BUILDING NEED TO BE REPLACED. Arturo Nunez 2 98302 2 Medium Work In Progress 2/7/2013 3:4 Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez 2		105	\$0.00
Nunez, Arturo WATER SUPPLY LINES TO A.C. UNITS IN OLD CAF. BUILDING NEED TO BE REPLACED. Arturo Nunez 2 98302 2 Medium Work In Progress 2/7/2013 3:4 Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez 2	2.10110		ψ0.00
98302 22 Medium Work In Progress 2/7/2013 3:4 Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez			
Medium Work In Progress 2/7/2013 3:4 Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez 2/1000000000000000000000000000000000000	/= /		
Nunez, Arturo NEED TO CHECK OUTSIDE LIGHTING ON MAIN BUILDING. Arturo Nunez	2/7/2013	117	\$0.00
BUILDING. Arturo Nunez	10:46 PM		
	2/5/2013	119	 \$0.00
Medium Work In Progress SPED OFFICE 2/5/2013 3:0)2:42 PM		
Nunez, Arturo MOVE FURNITURE IN DIAGNOSTICIAN OFFICE AS INSTRUCTED BY JULIE HERNANDEZ (DR. BLANCA ROLLE)			
Margaret Villalobos 98211 2	2/5/2013	119	 \$0.00
Medium Work In Progress SPED OFFICE 2/5/2013 3:0		113	ψ0.00
Nunez, Arturo MOVE FILE CABINETS INTO DIAGNOSTICIAN ROOM			
(SEE JULIE HERNANDEZ)	I		
Margaret Villalobos 98213 2	2/5/2013	119	 \$0.00
Medium Work In Progress SPED OFFICE 2/5/2013 3:0		110	ψ0.00
Nunez, Arturo REMOVE OLD SHELVES FROM DIAGNOSTICIAN			
OFFICE (SEE JULIE HERNANDEZ) Margaret Villalobos			

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013AreaDeferredArea NumberReasonDescription	ed By	Until F	-	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	ES							
96999					1/8/2013		147		\$0.00
Medium	Work In Progress	SPED OFFICE		1/8/201	3 8:58:52 AM				
Nunez, Ari	turo	PLEASE HAVE MAINTI REMOVE ALL CHALKE DISPOSE OF, PAINTIN COMPLETED IN ORDE FOR DIAGNOSTICIAN	BOARDS FRO	OM THE HALL	AND				
Margaret \ 96328	Villalobos				12/6/2012		180		\$0.00
Medium	Work In Progress	SPED OFFICE		12/6/201	2 3:22:16 PM		100		ψ0.00
Nunez, Ari	Ū	FINISH REMOVING CH (DISPOSE OF CHALKE 120		S IN ROOM 1	20				
<u>Margaret \</u> 101199	Villalobos				4/23/2013		42		\$0.00
Medium	Work In Progress			4/22/201	3 8:21:55 AM		42		ψ0.00
Sotelo, En	Ū	Need some assitance v hallway, g.f.c.i. keeps ti		ntain in Aggie					
Arturo Nur	nez		-		0/11/0010				* 0.00
99527				- / / /	3/11/2013		85		\$0.00
Medium	Work In Progress				3 8:05:17 AM				
Gallegos,		re adjust lights in new b new daylight savings tin		bldg to turn o	n to				
<u>David Veg</u> 94680	a				10/26/2012		221		\$0.00
Medium	Work In Progress			10/26/201	2 3:48:12 PM				
Sotelo, En	rique	NEED SOME ASSITAN LIGHT FIXTURES ON F THE IN ROOM ARE TU	PRE K. WORF						
<u>Arturo Nur</u> 99170	nez				3/3/2013	4/3/2013	93		\$0.00
Medium	Work In Brogross			2/2/2013	3 12:25:37 AM	-10/2010	30		ψ0.00
Villalobos,	Work In Progress Hector	Yearly - Anthony ES R3 PM schedule details.	8 (Ref. Unit)(Ye						
Margret Vi	illalobos				0/04/2215				A C C C
100192					3/31/2013	5/1/2013	65		\$0.00
Medium	Work In Progress			3/31/2013	3 12:32:15 AM				
Villalobos,	Hector	Yearly - Anthony ES A8 PM schedule details.	(Rooftop Unit))(Yearly) - Re	fer to				
Margret Vi	illalobos								

WOID Priority Assigned 1	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Local Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	Anthony	ES					
	Anthony	=	2/21/2012	E/1/2012	CE.		¢0.00
100190			3/31/2013	5/1/2013	65		\$0.00
Medium	Work In Progress		3/31/2013 12:32:14 AM				
Villalobos,		Yearly - Anthony ES A13 (AC Wall Mc Refer to PM schedule details.	unt)(Yearly) -				
Margret Vil 100191	lalobos		3/31/2013		65		\$0.00
Medium	Work In Progress		3/31/2013 12:32:14 AM		00		Q 0.00
	C C						
Villalobos,		Yearly - Anthony ES A6 (Rooftop Unit PM schedule details.)(Yearly) - Refer to				
Margret Vil 102868	lalobos		6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:49 AM				
Nunez, Arti	-	Yearly - Anthony ES - B2 Boiler (Yearl schedule details.					
Margret Vil	lalobos						
102869			6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:50 AM				
Nunez, Arti	uro	Yearly - Anthony ES B2(Boiler H.Wate to PM schedule details.	er)(Yearly) - Refer				
Margret Vil	lalobos						<u> </u>
100204			3/31/2013	4/16/2013	65		\$0.00
Medium	Work In Progress		3/31/2013 12:32:20 AM				
Nunez, Arte	uro	Monthly - Anthony ES A3(Rooftop Uni Refer to PM schedule details.	t)(S.Annual) -				
Margret Vil 100622	lalobos		4/7/2013	4/23/2013	58		\$0.00
					50		ψ0.00
Medium	Work In Progress		4/7/2013 12:18:48 AM				
Nunez, Art		Monthly - Anthony ES A4 (Rooftop Un Refer to PM schedule details.	it)(S.Annual) -				
Margret Vil 102768	lalobos		5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:43 AM				<i>Q</i> O O O O
Nunez, Arti	0	Yearly - Anthony ES A2 (Split System) PM schedule details.)(Yearly) - Refer to				
Margret Vil	lalobos						
98993			2/28/2013	3/31/2013	96		\$0.00
Medium	Work In Progress		2/28/2013 12:28:23 AM				
Nunez, Arti	uro	Yearly - Anthony ES C-11 (Evap.Down to PM schedule details.	n)(Yearly) - Refer				
Margret Vil	lalobos						

Selected Da WOID Priority Assigned ⁻ Requester	Building Status To	Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	ES						
103016				6/3/2013		1		\$0.00
Medium	Work In Progress	SPED OFFICE		6/3/2013 2:52:47 PM				
Solis, Lore	nzo	CHECK AIR CO OFFICE /BLOV	ONDITIONER IN F VING HOT AIR	ROOM 120 SPED				
Margaret V 102866	lilalobos			6/2/2013		2		\$0.00
Medium	Work In Progress			6/2/2013 12:28:48 AM		-		\$0.00
Villalobos,	•	Monthly - Antho PM schedule d		I Quarterly - Refer to	6/3 - emailed G. Herr	nandez		
Margret Vil	lalobos			= (0, (0, 0, 1, 0)				<u> </u>
101976				5/9/2013		26		\$0.00
Medium	Work In Progress	- ·		5/9/2013 3:32:13 PM				
Solis, Lore	nzo	Alamo a.c unit,	have have a.c swi so that they can to taed of turning all	urn on a.c's				
Arturo Nun 93782	ez			10/3/2012		244		\$0.00
Medium	Work In Progress	SPED OFFICE		10/3/2012 9:31:24 AM				<i>Q</i> O O O O
Lozoya, Ma	•	NEED TWO (2) KEYS FOR ROO R ON DOORKNO					
Margaret V	íilalobos			0/00/0040				\$0.00
99024 Medium	Work In Progress			2/28/2013 2/28/2013 8:18:36 AM		96		φ0.00
Lozoya, Ma	Work In Progress anny	be needing a g	names for the Sod ate key. If you hav to contact our off	cial Workers whom will ve any questions				
		MARQUEZ, AN MARTINEZ, W	EL BORAH ANN LLEN, ERNESTIN IAHI LORENA ILMA DRGINA ELIZABE ⁻ ONICA					
Margret Vil 100968	lalobos			4/16/2013		49		\$0.00
Medium	Work In Progress			4/16/2013 8:12:27 AM	l	-		
Lozoya, Ma	Ū			e tennant checked key rouble opening lock.				

6/4/2013 9:16:04 AM

WOID Priority Assigned Requester		Area De Area Number Re Description	eferred By eason	Until Request Date Ta Created Date/Time Ac	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Anthony	ES						
102648				5/28/2013		7		\$0.00
Medium	Work In Progress			5/28/2013 3:53:24 PM				
Ontiveros,	Guadalupe	Need some fertilize	er, to fertilize pla	aygrounds.				
Arturo Nur	nez							
102406				5/20/2013		15		\$0.00
Medium	Work In Progress			5/20/2013 3:43:46 PM				
	Guadalupe	Palm tree in front removed, tree is al		building needs to be				
<u>Arturo Nur</u> 102410	nez			5/20/2013		15		\$0.00
Medium	Work In Progress			5/20/2013 3:45:59 PM				
Ontiveros,	Guadalupe	Canopy frames in 2(ea.)	alamo building	need to be removed.				
Arturo Nur	nez	. ,						
102414				5/20/2013		15		\$0.00
Medium	Work In Progress			5/20/2013 3:47:32 PM				
	Guadalupe	Need to borrow mo main building.	ower to cut gras	s in new sod area				
Arturo Nur 92466	nez			9/6/2012		271		\$0.00
Medium	Work In Progress			9/6/2012 1:00:10 PM		211		φ0.00
Orozco, D	Ū	DISHWASHER W STOPPED WORK 882.3507		MODE AND				
Maritza Go	onzalez							
100313				3/31/2013	4/8/2013	65		\$0.00
Medium	Work In Progress			3/31/2013 12:33:02 AM				
Nunez, Ar	turo	Monthly - Anthony to PM schedule de		: Test: Monthly - Refer				
Margret Vi 94354	illalobos			10/19/2012		228		\$0.00
Medium	Work In Progress	SPED OFFICE		10/19/2012 9:00:43 AM		220		ψ0.00
Nunez, Ar	-	MOVE OFFICE DE	ANS OFFICE/M OFFICE TO JU	IERNANDEZ OFFICE IOVE DESK FROM LIE HERNANDEZ				

Location: Anthony ES 102528 5/23/2013 Medium Work In Progress GISD 5/23/2013 2:51:36 PM Briones, Enrique PO# 121304836 PLEASE DELIVER 400 BOOK BOXES TO ANTHONY ELEM. ATTN: INSTRUCTIONAL COACH	12	\$0.00
Medium Work In Progress GISD 5/23/2013 2:51:36 PM Briones, Enrique PO# 121304836 PLEASE DELIVER 400 BOOK BOXES TO ANTHONY ELEM. PLEASE DELIVER 400 BOOK BOXES TO ANTHONY	12	\$0.00
Briones, Enrique PO# 121304836 PLEASE DELIVER 400 BOOK BOXES TO ANTHONY ELEM.		
PLEASE DELIVER 400 BOOK BOXES TO ANTHONY ELEM.		
ATTN. INSTRUCTIONAL COACH		
Lucia Almeraz 102248 5/15/2013	20	\$0.00
Medium Work In Progress 5/15/2013 3:54:34 PM		·
Briones, Enrique CONCHA (DATA CLERK) IS REQUESTING 10 BOXES TO SEND CUMULATIVE FOLDERS BACK TO THE WAREHOUSE		
<u>Jessica Lopez</u> 101011 4/17/2013	48	 \$0.00
Medium Work In Progress SPED 4/17/2013 7:37:36 AM		
Lozoya, Manny NEED FRONT DOOR PRESSURE GAUGE REPAIRED (DOOR SLAMS SHUT)		
Margaret Villalobos 3/3/2013	93	 \$0.00
Medium Work In Progress 3/3/2013 12:25:57 AM	00	\$0.00
Munoz, Michael Yearly - Anthony ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.		
Margret Villalobos 6/2/2013 6/8/2013	3 2	\$0.00
102985 6/2/2013 6/8/201 Medium Work In Progress 6/2/2013 12:29:43 AM	5 2	Φ 0.00
Nunez, Arturo Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.		
Margret Villalobos		
102645 5/28/2013	7	\$0.00
MediumWork In Progress5/28/2013 3:50:30 PM		
Ontiveros, Guadalupe Need to borrow eqipment to aerate play grounds to soften the soil , ground to hard.		
Arturo Nunez 100360 3/31/2013 4/21/201	3 65	 \$0.00
Medium Work In Progress 3/31/2013 12:33:20 AM		
Orozco, Daniel Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.		
Margret Villalobos		

WOID	te Range for Request Building	Area	Deferred By	Until		arget Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Cre	ated Date/Time A	ctual Comp Date	Aged	Hours	
Assigned [·]	То	Description				Action Taken			
Requester	Name								
Location:	Anthony	ES							
98852	Main Building				2/26/2013		98		\$0.00
Medium	Work In Progress			2/26/2	2013 5:05:41 AM				
Lozoya, Ma	anny		morgan storage to have access to gat		so that				
David Vega					5/1/0010				
101541	Original Main				5/1/2013		34		\$0.00
Medium	Work In Progress			5/1/2	2013 8:33:51 AM				
Lozoya, Ma	anny	key cylinder in	main entrance is ge	tting stuck					
David Vega									
91739	Pump House				8/23/2012		285		\$0.00
Medium	Work In Progress			8/23/2	2012 9:52:41 AM				
Gonzalez,	Salvador	upper primary	oump house tank is	leaking					
Hector Villa	alobos								
Count: 53	Work Orders	A	vg. Age of WO's 7	79		Total for Anthon	y ES	0	\$0.00

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino E	S				
103031		6/3/2013	i	1		\$0.00
Medium	Work In Progress	6/3/2013 4:11:31 PM	1			
Munoz, Mic	hael	WE NEED DIMAR SYSTEMS TO CHECK OUT THE FIRE PUMP. THANK YOU				
Ruben Ron 100361	quillo	3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress	3/31/2013 12:33:21 AN		00		ψ0.00
Orozco, Da	Ū	Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details.				
Margret Vill 99216	alobos	3/3/2013		93		\$0.00
Medium	Work In Progress	3/3/2013 12:25:58 AN		00		ψ0.00
Munoz, Mic	Ū	Yearly - Berino ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.				
Margret Vill	alobos	0/0/00 / 0	0/0/0040			<u> </u>
102980		6/2/2013		2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:41 AN	1			
Duran, Ada		Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.				
Margret Vill 97927	alodos	1/31/2013	,	124		\$0.00
Medium	Work In Progress	1/31/2013 10:17:48 AM	1			
Lozoya, Ma	anny	MR MANNY LOZOYA SIR NEED THE KEY CORE INSTALL DOOR ROOM 138 IT IS MISSING THANK YOU SIR AND GOD BLESS				
Adan Durai 94887	1	11/1/2012		215		\$0.00
Medium	Work In Progress	11/1/2012 10:52:35 AN		210		φ0.00
Lozoya, Ma	Ŭ	put 2 key cores on muntin in the 2 lobbys	•			
-	-					
Jimmy Cort 101213	.ez	4/23/2013	· · · · · · · · · · · · · · · · · · ·	42		\$0.00
Medium	Work In Progress	4/23/2013 1:28:22 PM	1			
Orozco, Da	niel	TILT SKILLET GOES OFF ALL OF A SUDDEN AND WONT TURN ON. SNP MANAGER ELSA C. 882.2417				
Maritza Go	nzalez	3/31/2013		65		\$0.00
100326 Medium	Work In Prograss	3/31/2013 12:33:07 AN		00		φ0.00
	Work In Progress		1			
Sanchez, R		Monthly - Berino ES - Monthly Meter Readings - Refer to PM schedule details.				
Margret Vill	alobos					

6/4/2013 9:16:04 AM

WOID Priority Assigned Requester		Area Deferred By Un Area Number Reason Description	til Request Date T Created Date/Time A	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino E	S					
102780			5/31/2013		4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:49 AM				
Sanchez,	Raul	Monthly - Berino ES - Monthly Meter Rea PM schedule details.	adings - Refer to				
Margret Vi 99409	illalobos		3/6/2013		90		\$0.00
Medium	Work In Progress		3/6/2013 2:55:21 PM		00		φ0.00
Sanchez,	-	MR RAUL SANCHEZ SIR NEED TO RE FILTERS ALSO THE WATER GAGE IS NEED TO REPLACE THANK YOU SIR A BLESS	PLACE WATER LEAKING				
Adan Dura 95215	an		11/6/2012		210		\$0.00
Medium	Work In Progress		11/6/2012 8:20:10 AM		2.0		<i>Q</i> U U U
Lozoya, M		MANNY LOZOYA PER MR VALTIERRA NEED TO INSTALL A DEAD-BOLT MAII TO LIBRARY FOR BETTER SECURITY SIR AND GOD BLESS	N ENTRANCE				
Adan Dura 99748	an		3/15/2013		81		\$0.00
Medium	Work In Progress		3/15/2013 9:20:11 AM				
Lozoya, M	anny	NEED TO HAVE SOME KEYS REKEYE OUTSIDE DOOR.	D TO THE				
Maribel Ch 94300	navez	Office	10/18/2012		229		\$0.00
Medium	Work In Progress		10/18/2012 9:41:51 AM				Q UICC
Lozoya, M	Ŭ	OFFICE- FOR MANNY LOZOYA- I NEEI NAME PLATE MARIBEL GAMBOA. THA	D A NEW				
Maribel Cl	navez		11/10/0010				<u> </u>
95628			11/16/2012		200		\$0.00
Medium Lozoya, M	Work In Progress anny	NEED A LOCK AND KEY FOR THE GA ⁻ POND AREA.	11/16/2012 2:06:10 PM FE DRAINAGE				
Maribel Cl	navez						
99794			3/17/2013		79		\$0.00
Medium	Work In Progress		3/17/2013 12:19:59 AM				
Villalobos,	Margret	Monthly - Berino ES - PC Automated Qua to PM schedule details.	arterly - Refer E	Emailed to Melanie	on 3/18/ [,]	13	
Margret Vi	illalobos						

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino E	3					
102876			6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:53 AM	l			
Duran, Ada	an	Yearly - Berino ES B2(Boiler H.Wat PM schedule details.	er)(Yearly) - Refer to				
Margret Vil 102757	lalobos		5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:38 AM		•		φ0.00
Duran, Ada	•	Yearly - Berino ES A2 (Split System PM schedule details.					
Margret Vil	lalobos		5/7/2013		28		\$0.00
101873 Medium	Work In Progress		5/7/2013 3:22:13 PM		20		φ0.00
Sotelo, Enr	rique	MR ENRIQUE SOTELO SIR THE G FOUNTAINS MIDDLE WING NOR REPLACING THANK YOU SIR AND	FI WATER TH SIDE NEED				
Adan Dura 99979	n		3/21/2013		75		\$0.00
Medium	Work In Progress		3/21/2013 10:00:32 AM	I			
Villalobos,		MR DAVID VILLALOBOS SIR THE PORTABLE 155&156 HEADSTART RIGHT PLEASE CHECK THANK YO BLESS	IS NOT HEATING				
Adan Dura 98891	n		2/26/2013		98		\$0.00
Medium	Work In Progress		2/26/2013 2:46:15 PM				<i>Q</i> 0100
Villalobos,	-	MR FRED APPELZOLLAR SIR THE HEATER IN PORTABLE 155&156 I NEED TO BE REPLACE ALSO THE LEAKING NEED REPLACING	E LITTLE WATER S NOT WORKING	Route to David asp	reassign	ment 4/2/1	3
Adan Dura 96600	n		12/13/2012		173		\$0.00
Medium	Work In Progress		12/13/2012 3:03:45 PM				<i>Q</i> 0100
Villalobos,	-	MR FRED APPELL0ZER SIR THE PORTABLE 155&156 SMALL WAT HOT NEED TO ADJUST HOT WAT KIDS THANK YOU SIR AND GOD I	WATER HEATER ER HEATER IS TO ER HEADSTART	Route to David asp	reassign	ment 4/2/1	3
Adan Dura 96760	n		1/6/2013	2/6/2013	149		\$0.00
Medium	Work In Progress		1/6/2013 12:23:36 AM				<i></i>
Villalobos,	•	Yearly - Berino ES Backflow Inspec schedule details.					
Margret Vil	lalobos						

WOID Priority Assigned Requester	Name	Area E Area Number F Description	Deferred By	ocation, Status Until Crea	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino E	5							
99918					3/20/2013		76		\$0.00
Medium	Work In Progress			3/20/20	13 10:09:17 AM				
Flores, Pet	te	THE BOBCAT TI	ES SIR WOULD L HURSDAY AND F NK YOU SIR AND	RIDAY IF ITS	-				
Adan Dura 102896	in				6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/20	13 12:29:03 AM				
Duran, Ada		Monthly - Berino PM schedule det	ES Emer. Light Te ails.						
Margret Vi 102894	llalobos				6/2/2013		2		\$0.00
Medium	Work In Progress			6/2/20	0/2/2013 13 12:29:02 AM		2		ψ0.00
Duran, Ada	C C	Monthly - Berino PM schedule det	ES - Clothes Drye ails.						
Margret Vi	llalobos				6/2/2012	6/10/2012			¢0.00
102895					6/2/2013	6/10/2013	2		\$0.00
Medium Duran, Ada	Work In Progress an	Monthly - Berino PM schedule det	ES Exit Sign Insp:		13 12:29:02 AM fer to				
Margret Vi	llalobos		ano.						
100843					4/11/2013		54		\$0.00
Medium	Work In Progress			4/11/2	013 3:02:41 PM				
Duran, Ada	an	-	MR VALTIERRA ARE COMMING LO BASS NUTS	-					
Adan Dura	n Work Orders		. Age of WO's 8			Total for Berin		0	\$0.00

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Loca Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Labor Aged Hours	Costs
Location:	Chaparra	I ES				
99521			3/10/2013	3/26/2013	86	\$0.00
Medium	Work In Progress		3/10/2013 12:19:11 AM			
Quinones,	Paul	Monthly - Chaparral ES Playground In schedule details.	nsp - Refer to PM			
Margret Vi	llalobos		2/10/2013	2/26/2013	114	\$0.00
98332 Madium					114	φ0.00
Medium	Work In Progress		2/10/2013 12:20:37 AM			
Quinones,		Monthly - Chaparral ES Playground I schedule details.	nsp - Refer to PM			
Margret Vi 102519	llalobos		5/23/2013		12	\$0.00
Medium	Work In Progress		5/23/2013 11:44:49 AM			
Quinones,		PLAYGROUND BETWEEN 300WING SLIDE WAS REMOVED FOR SAFETY PUR WHEN ?.TALKED TO PRINCIPLE TO EITHER BOARD UP SLIDE IN PLACE.SLIDE IS NOT ON SCHOOL	POSES OR TO PLACE	5/30 - Asp Mike, ass		
Paul Quine 102051	ones		5/12/2013	5/28/2013	23	\$0.00
Medium	Work In Progress		5/12/2013 12:21:26 AM		-	
Quinones,	-	Monthly - Chaparral ES Playground I				
Margret Vi	llalobos		4/7/2012	4/22/2012	F Q	¢0.00
100651			4/7/2013	4/23/2013	58	\$0.00
Medium Quinones,	Work In Progress Paul	Monthly - Chaparral ES Playground I	4/7/2013 12:19:05 AM nsp - Refer to PM			
Margret Vi	llalobos					^
99468			3/7/2013		89	\$0.00
Medium	Work In Progress		3/7/2013 3:48:50 PM			
Flores, Pe	te	please check front suspension to wor	k truck #123			
Paul Quino 100508	ones		4/3/2013		62	\$0.00
Medium	Work In Prograss				02	φ0.00
	Work In Progress		4/3/2013 3:39:02 PM			
Estrada, Jo	esus	REQUESTING NEW FLOORING TIL CAFETERIA DURING THE SUMMER				
Paul Quine	ones					

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Location, St Area Deferred By Until Area Number Reason 0 Description 0	Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	IES					
102065			5/13/2013		22		\$0.00
Medium	Work In Progress	5/	13/2013 8:11:54 AN	1			
Quinones,	, Paul	NEED TO REPLACE BROKEN SPRINKLER REORDER AND RESTOCK	S				
Paul Quin 102947	ones		6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress	6/	2/2013 12:29:26 AN		Z		ψ0.00
Quinones,	C C	Monthly - Chaparral ES Exit Sign Insp: Mont to PM schedule details.		I			
Margret V	illalobos						
101370			4/26/2013		39		\$0.00
Medium	Work In Progress	4/2	6/2013 10:42:56 AN	1			
Quinones,	, Paul	REQUESTING 6800 AREO COOL SIDE DR EVAP.COOLER FOR NEW INSTALLATION ACTIVITY RM.AND 6 ANGLE IRON FOR FRAME.					
Paul Quin 101517	ones		4/30/2013		35		\$0.00
Medium	Work In Progress	۵/	30/2013 3:52:00 PM		00		ψ0.00
Quinones,	C C	need 1 1/2"X 1 1/2" 10' ANGLE FOR NEW / INSTALL IN THE ACTIVITY RM.					
Paul Quin	ones						
101685			5/5/2013		30		\$0.00
Medium	Work In Progress	5/	5/2013 12:24:06 AN	1			
Quinones,		Monthly - Chaparral ES Exit Sign Insp: Mont to PM schedule details.	hly - Refer				
Margret V 101686	illalobos		5/5/2013		30		\$0.00
Medium	Work In Progress	5/	5/2013 12:24:06 AN				·
Quinones,	-	Monthly - Chaparral ES - Clothes Dryer (Mon Refer to PM schedule details.					
Margret V	illalobos						
98706			2/21/2013		103		\$0.00
Medium	Work In Progress	2/.	21/2013 8:09:12 AN	1			
Ontiveros,	, Guadalupe	please airate soccer field, and fertilize as wel	l thank you				
Paul Quin	ones		2/21/2012		102		¢0.00
98708 Madium			2/21/2013		103		\$0.00
Medium	Work In Progress		21/2013 8:11:03 AN	I			
	, Guadalupe	irrigation booster pump motor burned shorter	d out				
Paul Quin	ones						
6/4/2013	9:16:05 AM					Page 2	16 of 160

6/4/2013 9:16:05 AM

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	IES				
99890		3/19/2013		77		\$0.00
Medium	Work In Progress	3/19/2013 4:03:08 PM	l			
Quinones,	Paul	NEED A TOTAL OF 18 ROOF JACKS FOR THE A/C'S IN THE 200 WING				
<u>Paul Quino</u> 95567	nes	11/15/2012		201		\$0.00
	Work In Progress	11/15/2012 10:34:17		201		\$0.00
Quinones,	Paul	Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You				
Dominique 102951	Esparza	6/2/2013		2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:28 AM		-		<i>Q</i> 0.00
Quinones,	•	Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.				
<u>Margret Vil</u> 94038	lalobos	10/11/2012		236		\$0.00
High	Work In Progress	10/11/2012 7:27:40 AM		200		φ0.00
Quinones,	-	new furniture came in and needs to be assembled. thank you				
<u>Michael Mu</u> 99666	Inoz	3/13/2013		83		\$0.00
	Work In Progress	3/13/2013 3:48:58 PM		00		ψ0.00
Quinones,		need 100' of water hose 5/8"for general use and to water grass and trees				
Paul Quino	ones	-				
100698		4/8/2013		57		\$0.00
Medium	Work In Progress	4/8/2013 3:52:48 PM				
Appelzoller	r, ⊢red	WATER FAUCETS LEAKING IN GIRLS REST RM.FRONT ENTRANCE,REQUESTING NEW FAUCETS.				
<u>Paul Quino</u> 101818	nes	5/6/2013		29		\$0.00
Medium	Work In Progress	5/6/2013 9:47:38 AM				\$0.00
Appelzoller	•	requesting new water faucet in rm.213 rest rm. handle is worn out.				
Paul Quino	ones					

WOID Priority Assigned ⁻ Requester		Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Chaparra	IES				
101847		5/6/2013		29		\$0.00
Medium	Work In Progress	5/6/2013 3:57:15 PM				
Vallejo, Alt	C C	NEW OUTER WALL ENCLOSURE,AND NEW DOOR ENTRY IN FRONT OF THE CONCESSION STAND,REQUESTING A 3-WAY SWITCH CIRCUIT,2 LAMPS,AND 1 LAMP OUTSIDE DOOR				
Paul Quinc 92134	ones	8/31/2012		277		\$0.00
Medium	Work In Progress	8/31/2012 12:24:24 AM		211		ψ0.00
Quinones,	Ū	Monthly - Chaparral ES A-16 Exh Fan (Semi Annual) - Refer to PM schedule details.				
Margret Vil	llalobos					
102857		6/2/2013		2		\$0.00
Medium	Work In Progress	6/2/2013 12:28:44 AM				
Quinones,	Paul	Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.				
Margret Vil	llalobos	3/14/2013		82		\$0.00
99737				02		φ0.00
Medium	Work In Progress	3/14/2013 3:55:16 PM				
Quinones,	Paul	REPAINT 200 WING FOR THE SUMMER BREAK				
Paul Quinc	ones	4/04/0040		4.4		<u> </u>
101301		4/24/2013		41		\$0.00
Medium	Work In Progress	4/24/2013 4:09:14 PM				
Lozoya, Ma	anny	NEED TO SECURE GATE NEXT TO NEW WING REQUESTING LOCK TO SECURE GATE THANKS				
Paul Quinc	ones	1/00/0040				<u> </u>
101471		4/30/2013		35		\$0.00
Medium	Work In Progress	4/30/2013 9:20:19 AM				
Lozoya, Ma	anny	RM.501 KEY WILL NOT GO INTO KEY CYLINDER,DOOR DOESNT OPEN FROM THE OUTSIDE W/KEY				
Paul Quinc	ones					
97957		1/31/2013		124		\$0.00
Medium	Work In Progress	1/31/2013 3:50:28 PM				
Gonzalez,	Salvador	NEED METAL FRAME TO REPLACE THE WOOD FRAME,AND A 1/16 DIAMOND PLATE TO COVER THE WATER SUPPLY AND PLUMBING TO THE WATER FOUNTAIN FOR PROTECTION.				

please replace broken door handle in rm. 22 SS 22 DOOR IN CLASS RM.302 DOOR IS DRAGO FLOOR SS GISD 5/	4/8/2013 4/8/2013 3:50:15 PM GING ON 5/23/2013		81 57		·
please replace broken door handle in rm. 22 s DOOR IN CLASS RM.302 DOOR IS DRAGO FLOOR s GISD 5/	5/2013 12:14:06 PM 0 4/8/2013 4/8/2013 3:50:15 PM GING ON 5/23/2013		-		\$0.00 \$0.00
please replace broken door handle in rm. 22 s DOOR IN CLASS RM.302 DOOR IS DRAGO FLOOR s GISD 5/	0 4/8/2013 4/8/2013 3:50:15 PM GING ON 5/23/2013		57		\$0.00
S DOOR IN CLASS RM.302 DOOR IS DRAGO FLOOR S GISD 5/	4/8/2013 4/8/2013 3:50:15 PM GING ON 5/23/2013		57		\$0.00
DOOR IN CLASS RM.302 DOOR IS DRAGO FLOOR IS GISD 5/	4/8/2013 3:50:15 PM GING ON 5/23/2013		57		\$0.00
DOOR IN CLASS RM.302 DOOR IS DRAGO FLOOR IS GISD 5/	4/8/2013 3:50:15 PM GING ON 5/23/2013		57		\$0.00
DOOR IN CLASS RM.302 DOOR IS DRAGO FLOOR IS GISD 5/	GING ON 5/23/2013				
FLOOR s GISD 5/	5/23/2013				
			12		\$0.00
	23/2013 2:56:41 PM				
PO# 121304836 PLEASE DELIVER 400 BOOK BOXES TO CHAPARRAL ELEM. ATTN: INSTRUCTIONAL COACH					
	5/13/2013		22		\$0.00
5			22		ψ0.00
DOUBLE DOORS 300WING N.END DOOR FROM HINGE,AND DOUBLE DOORS FRO	RIPPED NT				
	2/26/2013		98		\$0.00
s 2/					<i>Q</i>
DOUBLE DOORS, DOOR FRAME BEND AN	ID DOOR IS				
	2/12/2012		111		\$0.00
-			111		φ0.00
SECURE SCHOOL SUPPLIES AND FOR STORAGE USE.	10				
	0/0/0040	0/0/0040			
		6/8/2013	2		\$0.00
Monthly - Chaparral ES Monthly FE Inpsection PM schedule details.	on - Refer to				
	PLEASE DELIVER 400 BOOK BOXES TO CHAPARRAL ELEM. ATTN: INSTRUCTIONAL COACH SS 5/ DOUBLE DOORS 300WING N.END DOOR FROM HINGE, AND DOUBLE DOORS FRO ENTRANCE NEXT TO THE CAFETERIA AF FRON THE HINGE AS WAELL SS 2/ DOUBLE DOORS, DOOR FRAME BEND AN RIPPED ON THE UPPER LEFT SIDE OF TO LOCATED NEXT TO THE CAFETERIA. SS 2/ REQUESTING DOOR AND DOOR FRAME SECURE SCHOOL SUPPLIES AND FOR STORAGE USE. SS 6/ Monthly - Chaparral ES Monthly FE Inpsecti	PLEASE DELIVER 400 BOOK BOXES TO CHAPARRAL ELEM. ATTN: INSTRUCTIONAL COACH 5/13/2013 55 5/13/2013 8:33:18 AM DOUBLE DOORS 300WING N.END DOOR RIPPED FROM HINGE, AND DOUBLE DOORS FRONT ENTRANCE NEXT TO THE CAFETERIA ARE RIPPED FRON THE HINGE AS WAELL 2/26/2013 55 2/26/2013 1:46:18 PM DOUBLE DOORS, DOOR FRAME BEND AND DOOR IS RIPPED ON THE UPPER LEFT SIDE OF THE DOOR LOCATED NEXT TO THE CAFETERIA. 2/13/2013 55 2/13/2013 2:23:16 PM REQUESTING DOOR AND DOOR FRAME TO SECURE SCHOOL SUPPLIES AND FOR STORAGE USE. 6/2/2013 12:29:35 AM Monthly - Chaparral ES Monthly FE Inpsection - Refer to	PLEASE DELIVER 400 BOOK BOXES TO CHAPARRAL ELEM. ATTN: INSTRUCTIONAL COACH 5/13/2013 55 5/13/2013 8:33:18 AM DOUBLE DOORS 300WING N.END DOOR RIPPED FROM HINGE, AND DOUBLE DOORS FRONT ENTRANCE NEXT TO THE CAFETERIA ARE RIPPED FRON THE HINGE AS WAELL 2/26/2013 55 2/26/2013 1:46:18 PM DOUBLE DOORS, DOOR FRAME BEND AND DOOR IS RIPPED ON THE UPPER LEFT SIDE OF THE DOOR LOCATED NEXT TO THE CAFETERIA. 2/13/2013 55 2/13/2013 2:23:16 PM REQUESTING DOOR AND DOOR FRAME TO SECURE SCHOOL SUPPLIES AND FOR STORAGE USE. 6/2/2013 12:29:35 AM Monthly - Chaparral ES Monthly FE Inpsection - Refer to	PLEASE DELIVER 400 BOOK BOXES TO CHAPARRAL ELEM. ATTN: INSTRUCTIONAL COACH 5/13/2013 22 35 5/13/2013 8:33:18 AM DOUBLE DOORS 300WING N.END DOOR RIPPED FROM HINGE, AND DOUBLE DOORS FRONT ENTRANCE NEXT TO THE CAFETERIA ARE RIPPED FRON THE HINGE AS WAELL 2/26/2013 1:46:18 PM DOUBLE DOORS, DOOR FRAME BEND AND DOOR IS RIPPED ON THE UPPER LEFT SIDE OF THE DOOR LOCATED NEXT TO THE CAFETERIA. 2/13/2013 2:23:16 PM REQUESTING DOOR AND DOOR FRAME TO SECURE SCHOOL SUPPLIES AND FOR STORAGE USE. 6/2/2013 12:29:35 AM Monthly - Chaparral ES Monthly FE Inpsection - Refer to	PLEASE DELIVER 400 BOOK BOXES TO CHAPARRAL ELEM. ATTN: INSTRUCTIONAL COACH 5/13/2013 8:33:18 AM DOUBLE DOORS 300WING N.END DOOR RIPPED FROM HINGE, AND DOUBLE DOORS FRONT ENTRANCE NEXT TO THE CAFETERIA ARE RIPPED FRON THE HINGE AS WAELL 2/26/2013 98 SS 2/26/2013 1:46:18 PM DOUBLE DOORS, DOOR FRAME BEND AND DOOR IS RIPPED ON THE UPPER LEFT SIDE OF THE DOOR LOCATED NEXT TO THE CAFETERIA. 2/13/2013 111 SS 2/13/2013 2:23:16 PM REQUESTING DOOR AND DOOR FRAME TO SECURE SCHOOL SUPPLIES AND FOR STORAGE USE. 6/2/2013 12:29:35 AM Monthly - Chaparral ES Monthly FE Inpsection - Refer to

WOID Priority Assigned 1 Requester		Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description	arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	I ES				
101765		5/5/2013	5/11/2013	30		\$0.00
Medium	Work In Progress	5/5/2013 12:24:38 AM				
Quinones,	Paul	Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.				
Margret Vill 101299	lalobos	4/24/2013		41		\$0.00
Medium	Work In Progress	4/24/2013 4:04:47 PM				φ0.00
Lozoya, Ma	anny	DOOR HANDLE IN ACTIVITY RM.BROKEN FROM THE INSIDE NEEDS TO BE REPLACED THANKS				
Paul Quino 99217	nes	3/3/2013		93		\$0.00
Medium	Work In Progress	3/3/2013 12:25:58 AM				
Munoz, Mic	chael	Yearly - Chaparral ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.				
Margret Vill	lalobos	2/24/2042	4/04/0040	05		¢0.00
100362		3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress	3/31/2013 12:33:21 AM				
Orozco, Da		Monthly - Chapparal ES Range Hood Cleaning - Refer to PM schedule details.				
Margret Vill 101369	lalobos	4/26/2013		39		\$0.00
Medium	Work In Progress	4/26/2013 10:37:38 AM				
Estrada, Je		RM.501 CARPET NEEDS REPAIR,CARPET IS COMING APART INBETWEEN CLASS RM.TRANSITION STRIP WILL NOT COVER THE CARPET.				
Paul Quino 101807	nes	5/5/2013	5/13/2013	30		\$0.00
Medium	Work In Progress	5/5/2013 12:24:57 AM				
Quinones,	Ŭ	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vill	lalobos	0/0/0010	0/40/0040			¢0 00
102987		6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:44 AM				
Quinones,	Paul	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.				
	lalobos					

				•	,				Total
WOID	te Range for Request Building	Area	Deferred By	Until		Farget Comp Date	Days	Labor	Costs
Priority	Status	Area Number	-	Cr	-	Actual Comp Date	Aged	Hours	
Assigned '	То	Description				Action Taken			
Requester	Name								
Location:	Chaparra	IES							
97031	Main Building	Hallway/Corrid	or		1/8/2013		147		\$0.00
Medium	Work In Progress	whole school		1/8	/2013 2:14:58 PM				
Lozoya, Ma	anny		ng to protables nee open with their keys						
Jennifer Co									
96945	Main Building	Classroom			1/7/2013		148		\$0.00
Medium	Work In Progress	gym		1/7	/2013 2:33:45 PM				
Lozoya, Ma	anny	need keys for a	coaches N69 please	e see Nava a	nd Flores				
Jennifer Co	orral								
99850	Main Building	Office			3/19/2013		77		\$0.00
Medium	Work In Progress	school		3/19	/2013 8:22:20 AM				
Lozoya, Ma	anny	need 4 more k Jennifer	eys to open doors fi	rom outside.	See				
Jennifer Co						Transformer	. 50	•	
Count: 46	Work Orders	A	vg. Age of WO's	68		Total for Chaparra	al ES	0	\$0.00

WOID Priority Assigned Requeste		Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ac		Days Aged	Labor Hours	
Location:	Chaparra	II HS					
99917			3/20/2013		-239		\$0.00
Medium	Work In Progress		3/20/2013 9:51:13 AM	7/24/2012			
Estrada, J	esus	NEED GYM FLOOR TO BE RE-F - 106' X W - 101')	INISHED (APPROX. L				
<u>Jesus Est</u> 102820	rada A-Wing	Office	5/31/2013		4		\$0.00
	C	Onice			4		ψ0.00
Medium	Work In Progress		5/31/2013 11:03:10 AM				
Gonzales,	, Camilo	Please pick up box of attendance back to warehouse. Forms are no (Diana Salazar)					
Mireya Me		Classroom	2/27/2013		97		¢0.00
98979	A-Wing	Classroom			97		\$0.00
Medium	Work In Progress		2/27/2013 4:40:56 PM				
Lozoya, N	-	Replace metal shelves with cabine training room in field house with lo					
Mireya Me 97305	eza A-Wing	Classroom	1/15/2013		140		\$0.00
Medium	Work In Progress		1/15/2013 8:54:25 AM				
Lozoya, N	c	Mrs. Vega's door is hard to open v located in the counselors area in f					
<u>Mireya Me</u> 100599	za A-Wing		4/5/2013		60		\$0.00
Medium	C		4/5/2013 3:32:35 PM		00		ψ0.00
	Work In Progress						
Ortiz, Alfre	edo	Need to remove sand from roof-to	pp.				
Alfredo Or 101093		Hallway/Corridor	4/18/2013		47		\$0.00
	A-Wing	Hallway/Corridor			47		φ0.00
Medium	Work In Progress		4/18/2013 3:56:25 PM				
Lozoya, N	-	Out-side door cylinder broken nex Can,t open door with key.	t to ISS classroom.				
Alfredo Or 96529	rtiz A-Wing	Hallway/Corridor	12/12/2012		174		\$0.00
Medium	Work In Progress	hainay, contact	12/12/2012 8:57:47 AM				φ0.00
	-						
Lozoya, N	lanny	Outer door lock will not open with door from nurse's office, between class. (Ms. Lopez)					
Mireya Me		Hollwoy/Corridor	0/07/0040		07		<u> </u>
98943	A-Wing	Hallway/Corridor	2/27/2013		97		\$0.00
Medium	Work In Progress		2/27/2013 1:37:32 PM				
Lozoya, N	lanny	Need to replace door exit device, Exit door A-wing between A105 an Cafeteria.					
Alfredo Oi	rtiz						
6/4/2013	9:16:05 AM					Page	22 of 160

Medium Montiveros, G Mireya Meza 100972	a A-Wing Work In Progress	HS Athletic Field When bleachers were moved from so softball fields they were damaged. O the damaged benches as this is a po students and public. (Sofia Payen) Office The front door that leads into the ma	Could we replaced	1	76		\$0.00
Medium Montiveros, G Mireya Meza 100972 Medium	Work In Progress Guadalupe a A-Wing Work In Progress	When bleachers were moved from so softball fields they were damaged. Of the damaged benches as this is a po students and public. (Sofia Payen) Office	3/20/2013 10:30:59 AM occer fields to Could we replaced tential danger to 4/16/2013	1			\$0.00
Ontiveros, G <u>Mireya Meza</u> 100972 Medium	Guadalupe a A-Wing Work In Progress	softball fields they were damaged. C the damaged benches as this is a po students and public. (Sofia Payen) Office	occer fields to Could we replaced tential danger to 4/16/2013		49		
<u>Mireya Meza</u> 100972 - Medium - ^N	a A-Wing Work In Progress	softball fields they were damaged. C the damaged benches as this is a po students and public. (Sofia Payen) Office	Could we replaced tential danger to 4/16/2013		49		
100972 Medium	A-Wing Work In Progress				49		
Medium	Work In Progress				-10		\$0.00
		The front door that leads into the ma	4/16/2013 11:05:51 AIV				ψ0.00
		area) does not close correctly and w it. We are having students come into working hours and so we need this fi possible. (security)	in office (reception e are unable to lock o the office after				
Mireya Meza	a						
	A-Wing	Office	5/2/2013		33		\$0.00
Medium	Work In Progress		5/2/2013 8:38:27 AM	1			
Lozoya, Mar	-	The fence doors on the west side clo branch need a longer chain. (Johnn					
Mireya Meza 99866	a A-Wing	Classroom	3/19/2013		77		\$0.00
Medium	Work In Progress		3/19/2013 2:39:49 PM	1			
Lozoya, Mar	-	Need a replacement CH key for Jose Please pick up broken key and delive Mireya Meza.					
Mireya Meza							
97472	A-Wing	Office	1/17/2013		138		\$0.00
Medium	Work In Progress		1/17/2013 3:52:19 PM	1			
Lozoya, Mar Mireya Meza	-	We need a CHS key for our permane (Mireya Meza)	ent security guard.	1/23/13 - ASP CHU ON KEY. ASP JES KEYS, ASP MIREY/	SIE/CHU	Y, NEED 2	2
99692	A-Wing	Cafeteria	3/14/2013	KEYS TO HER.	82		\$0.00
	Work In Progress		3/14/2013 8:45:49 AM		-		
Ortiz, Alfredo	-	Need to paint all metal doors, window gates.					
Alfredo Ortiz	<u>z</u> A-Wing	Cafeteria	1/7/2013		148		\$0.00
	-	Caletena			140		φ 0. 00
	Work In Progress		1/7/2013 8:42:27 AM	I			
Lozoya, Mar	nny	Cafeteria doors lach don't work 3 do	ors.				

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Or Area Deferred Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	IHS					
101157	A-Wing	Classroom	4/22/2013		43		\$0.00
Medium	Work In Progress		4/22/2013 10:27:46 AM				
Ortiz, Alfred	do	Need to replace blower mo 105.	tor on roof A/C unit. Room A-				
Alfredo Orti 99400	z A-Wing	Library	3/6/2013		90		\$0.00
Medium	Work In Progress		3/6/2013 10:59:01 AM		00		φ0.00
Lozoya, Ma	anny	Need key for the security b Mays)	ar in main library door. (Ms.				
Mireya Mez 101553	<u>a</u> A-Wing	Hallway/Corridor	5/1/2013		34		\$0.00
Medium	Work In Progress		5/1/2013 10:23:02 AM				
Appelzoller	, Fred	Need to raise the vent pipe is to close to A/C units.	s on roof-top. The drain pipe				
Alfredo Orti 99986	iz B-Wing	Classroom	3/21/2013		75		\$0.00
Medium	Work In Progress		3/21/2013 2:06:14 PM				<i>Q</i> O O O O
Lozoya, Ma	U U	Need to make key for cabir room B-3.	nets in store room in Science				
Alfredo Orti		Destroom (Deve)	F/00/0040		40		<u>¢0.00</u>
102498	C-Wing	Restroom (Boys)	5/22/2013		13		\$0.00
Medium	Work In Progress		5/22/2013 3:43:09 PM				
Appelzoller		Need to replace broken toil	ets in boys restrooms				
Alfredo Orti 99765	z C-Wing	Classroom	3/15/2013		81		\$0.00
Medium	Work In Progress		3/15/2013 1:47:17 PM				
Solis, Lorer	nzo	Need to repair GEO therma	al water leak in C-6 A/C unit.				
Alfredo Orti		·					
99766	D-Wing	Classroom	3/15/2013		81		\$0.00
Medium	Work In Progress		3/15/2013 1:50:04 PM				
Solis, Lorer	120	Need to repair GEO Therm heating unit.	al water leak in D-Sped				
Alfredo Orti 102834	z D-Wing		5/31/2013		4		\$0.00
Medium	Work In Progress		5/31/2013 3:30:20 PM				
Appelzoller Alfredo Orti	, Fred	Need to replace two circula One in C-wing and one in	ating pumps for water heaters,				

WOID Priority Assigned 7 Requester			eferred By		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	IHS						
100674	G-Wing	Classroom		4/8/2013		57		\$0.00
Medium	Work In Progress			4/8/2013 12:11:31 PM				
Solis, Lorei	nzo	Room G5 has be Please lower tem						
Mireya Mez 99764	za G-Wing	Classroom		3/15/2013		81		\$0.00
Medium	Work In Progress	Classicolli		3/15/2013 1:44:20 PM		01		φ0.00
Solis, Lorei	•	Need to replace t 5 A/C unit.	wo Terminator B	alancing Valves for G-				
Alfredo Ort 102172	iz G-Wing	Restroom (Boys)		5/14/2013		21		\$0.00
Medium	Work In Progress			5/14/2013 3:26:48 PM				<i>Q</i> 0100
Ortiz, Alfree	-	Need to replace f and toilets.	lush valve handle	es on several urinals				
Alfredo Ort 100944	iz Q-Wing	Hallway/Corridor		4/15/2013		50		\$0.00
Medium	Work In Progress	rialiway, corriadi		4/15/2013 3:43:20 PM		00		φ0.00
Ortiz, Alfred	•	Need to secure lo	ocker with screw					
Alfredo Ort		Need to secure it	oker with screw					
99405	Q-Wing	Classroom		3/6/2013		90		\$0.00
Medium	Work In Progress			3/6/2013 1:09:40 PM				
Ortiz, Alfree	do	Need to paint and Coaches use that						
Alfredo Ort 102378	iz Q-Wing	Classroom		5/20/2013		15		\$0.00
Medium	Work In Progress			5/20/2013 11:18:27 AM				
Lara, Ralph	•	Install better lock for better security		on back room cabinets				
Mireya Mez		Exterior		E/21/2012		4		<u> </u>
102838	Q-Wing	Exterior		5/31/2013		4		\$0.00
Medium	Work In Progress		· · · · ·	5/31/2013 3:38:50 PM				
Munoz, Mic		Need to install a t compressor inbac						
Alfredo Ort 94898	R-Wing	Classroom		11/1/2012		215		\$0.00
Medium	Work In Progress			11/1/2012 11:59:27 AM				
Lozoya, Ma	anny	Door handle to st be replaced. (Mr.		as broken. Needs to				

Location: Chaparral HS 101944 R-Wing 5/8/2013 27 Medium Work In Progress 5/8/2013 3:52:59 PM Gonzalez, Salvador please cable up lockers between boys and girls restroom on main corridor, thank you Michael Munoz 93777 Field House Athletic Field 10/3/2012 244 Medium Work In Progress 10/3/2012 7:29:03 AM 9 Gonzalez, Salvador Please put permanent shade in socccor fields. (Arnold Orozoo) 76 Mireya Meza 9 3/20/2013 2:31:13 PM 76 Medium Work In Progress 3/20/2013 2:31:13 PM 76 Lozoya, Manny The outside door to girls locker room in the field house is very loose. Please adjust. (Coach Fernie Mendoza) 710/2012 Mireya Meza The key hole on the girls dressing room in the field house is 5/8/2013 8:02:12 AM 72 Lozoya, Manny The key hole on the girls dressing room in the field house is 7/10/2012 4:23:59 PM 74 Medium Work In Progress 7/10/2012 4:23:59 PM 74 Valdez, Pedro We need 8 sets of tires attached to the soccer goals to make them mobile. 710/2012 4:23:59 PM Valdez, Pedro We neeed 8 sets of tires	Costs
Medium Work In Progress 5/8/2013 3:52:59 PM Gonzalez, Salvador please cable up lockers between boys and girls restroom on main corridor. thank you Michael Munoz 10/3/2012 244 93777 Field House Athletic Field 10/3/2012 244 Midum Work In Progress 10/3/2012 7:29:03 AM 244 Gonzalez, Salvador Please put permanent shade in socccer fields. (Arnold Orozo) 10/3/2013 76 Mireya Meza 0 10/3/2013 2:31:13 PM 76 Medium Work In Progress 3/20/2013 2:31:13 PM 76 Mireya Meza 0 10/3/2013 2:31:13 PM 76 Modium Work In Progress Please adjust. (Coach Fernie Mendoza) 76 Mireya Meza 0 10/3/2013 2:31:13 PM 76 Modium Work In Progress Please adjust. (Coach Fernie Mendoza) 76 Mireya Meza 0 10/3/2013 0:212 AM 27 Modium Work In Progress 5/8/2013 0:02:12 AM 27 Modium Work In Progress Athletic Field 7/10/2012 329 Medium Work In Progress Athletic Field	
Gonzalez, Salvador please cable up lockers between boys and girls restroom on main corridor. thank you Michael Munoz 33777 Field House Athletic Field 10/3/2012 244 Medium Work In Progress 10/3/2012 7.29.03 AM Gonzalez, Salvador Please put permanent shade in socccer fields. (Arnold Orozco) Mireya Meza 99936 Field House Dressing Room 3/20/2013 76 Medium Work In Progress 3/20/2013 231:13 PM 10 Lozoya, Many The outside door to girls locker room in the field house is very loose. Please adjust. (Coach Fernie Mendoza) 101 10 Mireya Meza 10 5/8/2013 27 5/8/2013 27 Medium Work In Progress 5/8/2013 802:12 AM 10 10/3/2012 329 Medium Work In Progress The key hole on the girls dressing room in the field house is very loose. Please field door). Please repair ASAP. (Mr. Orozco) 10 10/2/2012 329 Medium Work In Progress Athletic Field 3/12/2013 84 Medium Work In Progress Lupe Ontiveros 3/12/2013 84 Medium Work In Progress Lu	\$0.00
Michael Munoz Sayr77 Field House Athletic Field 10/3/2012 244 Medium Work In Progress 10/3/2012 7:29:03 AM Gonzalez, Salvador Please put permanent shade in socceer fields. (Arnold Orozoo) Mireya Meza 99395 Field House Dressing Room 3/20/2013 76 Medium Work In Progress 3/20/2013 2:31:13 PM Lozoya, Manny The outside door to girls locker room in the field house is very locse. Please adjust. (Coach Fernie Mendoza) Mireya Meza U10901 Field House Dressing Room 5/8/2013 27 Medium Work In Progress 5/8/2013 8:02:12 AM Lozoya, Manny The key hole on the girls dressing room in the field house is falling (outside door). Please repair ASAP. (Mr. Orozoo) Mireya Meza Lozoya, Manny Work In Progress 7/10/2012 329 Medium Work In Progress 7/10/2012 4:23:59 PM Valdez, Petro We need 8 sets of tires attached to the soccer goals to make them mobile. Mireya Meza Sy554 Field House Athletic Field 3/12/2013 084 Medium Work In Progress Lupe Ontiveros 3/12/2013 10:15:18 AM Ontiveros, Guadalupe Please pickup the field windscreens from the Warehouse for: CHS Softball - (install windscreens for softball field) CHS Baseball - (install windscreens for softball field) CHS Baseball - (install windscreens for baseball field) Medium Work In Progress 4/19/2013 10:26:46 AM	
33777 Field House Athletic Field 10/3/2012 244 Medium Work In Progress 10/3/2012 7:29:03 AM 244 Gonzalez, Salvador Please put permanent shade in socccer fields. (Arnold Orozoo) 224 Wedium Work In Progress 3/20/2013 76 39936 Field House Dressing Room 3/20/2013 2:31:13 PM Lozoya, Manny The outside door to girls locker room in the field house is very loose. Please adjust. (Coach Fernie Mendoza) 27 Mireya Meza Dressing Room 5/8/2013 27 Medium Work In Progress 7/10/2012 329 Valdez, Pedro We need 8 sets of tires attached to the soccer goals to make them mobile. 3/12/2013 84 Wedium Work In Progress 3/12/2013 1/12/2013 84 Ontiveros, Guadalupe Please pickup the field windscreens fror the Warehouse for: CHS Sortball - (i	
Medium Work In Progress 10/3/2012 7:29:03 AM Gonzalez, Salvador Please put permanent shade in socccer fields. (Arnold Orozco) Mireya Meza 99936 99936 Field House Dressing Room 3/20/2013 2:31:13 PM Lozoya, Manny The outside door to girls locker room in the field house is very loose. Please adjust. (Coach Fernie Mendoza) Mireya Meza The outside door to girls locker room in the field house is very loose. Please adjust. (Coach Fernie Mendoza) Mireya Meza The souside door. Please girls dressing room in the field house is very loose. Please adjust. (Coach Fernie Mendoza) Mireya Meza The key hole on the girls dressing room in the field house is talling (outside door). Please repair ASAP. (Mr. Orozco) Mireya Meza The key hole on the girls dressing room in the field house is talling (outside door). Please repair ASAP. (Mr. Orozco) Wireya Meza Work In Progress S7/26 Field House Athetic Field 3/12/2012 329 Medium Work In Progress 7/10/2012 4:23:59 PM 4 Valdez, Pedro We need 8 sets of tires attached to the soccer goals to make them mobile. 3/12/2013 10:15:18 AM Medium Work In Progress Lupe Ontiveros 3/12/2013 10:15:18 AM 4 O	\$0.00
Gonzalez, Salvador Please put permanent shade in socccer fields. (Arnold Orozoo) Mireya Meza 76 99306 Field House Dressing Room 3/20/2013 2:31:13 PM Medium Work In Progress 3/20/2013 2:31:13 PM 76 Lozoya, Manny The outside door to girls locker room in the field house is very loose. Please adjust. (Coach Fernie Mendoza) 77 Mireya Meza The outside door to girls locker room in the field house is svery loose. Please adjust. (Coach Fernie Mendoza) 27 Mireya Meza The key hole on the girls dressing room in the field house is falling (outside door). Please repair ASAP. (Mr. Orozoo) 70 Mireya Meza 89726 Field House Athletic Field 7/10/2012 329 Medium Work In Progress 7/10/2012 4:23:59 PM 2329 Valdez, Pedro We need 8 sets of tires attached to the soccer goals to make them mobile. 3/12/2013 10:15:18 AM Wedium Work In Progress Lupe Ontiveros 3/12/2013 10:15:18 AM 70 Ontiveros, Guadalupe Please pickup the field windscreens for baseball field) CHS Softball - (install windscreens for baseball field) CHS Softball - (install windscreens for baseball field) To be installed on a school basis. Terry Alvarado 10110<	
99936 Field House Dressing Room 3/20/2013 76 Medium Work In Progress 3/20/2013 2:31:13 PM Lozoya, Manny The outside door to girls locker room in the field house is very loose. Please adjust. (Coach Fernie Mendoza) 27 Mireya Meza 5/8/2013 27 Medium Work In Progress 5/8/2013 8:02:12 AM Lozoya, Manny The key hole on the girls dressing room in the field house repair ASAP. (Mr. Orozo) 710/2012 329 Mireya Meza House 710/2012 329 Mireya Meza We need 8 sets of tires attached to the soccer goals to make them mobile. 710/2012 329 Wedium Work In Progress Upe Ontiveros 3/12/2013 84 Valdez, Pedro We need 8 sets of tires attached to the soccer goals to make them mobile. 99544 Field House Lupe Ontiveros 3/12/2013 84 Ontiveros, Guadalupe Please pickup the field windscreens from the Warehouse for: CHS Softball - (install windscreens for softball field) CHS Softball - (install windscreens for baseball field) CHS Softball - (install windscreens for baseball field) CHS Baseball - (install windscreens for baseball field) To be installed on a school to school basis. CHS Softball -	
Medium Work In Progress 3/20/2013 2:31:13 PM Lozoya, Manny The outside door to girls locker room in the field house is very loose. Please adjust. (Coach Fernie Mendoza) Mireya Meza 7 101901 Field House Dressing Room 5/8/2013 8:02:12 AM Lozoya, Manny The key hole on the girls dressing room in the field house is falling (outside door). Please repair ASAP. (Mr. Orozo) 7/10/2012 329 Medium Work In Progress Athletic Field 7/10/2012 329 Medium Work In Progress 7/10/2012 4:23:59 PM 3/22/2013 84 Valdez, Pedro We need 8 sets of tires attached to the soccer goals to make them mobile. 3/12/2013 84 Medium Work In Progress Lupe Ontiveros 3/12/2013 10:15:18 AM 44 Ontiveros, Guadalupe Please pickup the field windscreens from the Warehouse tor: CHS Softball - (install windscreens for softball field) CHS Softball - (install windscreens for baseball field) CHS Softball - (install windscreens for baseball field) 46 Medium Work In Progress Athletic Field 4/19/2013 46	\$0.00
Lozoya, Manny The outside door to girls locker room in the field house is very loose. Please adjust. (Coach Fernie Mendoza) Mireya Meza 101901 Field House Dressing Room 5/8/2013 8:02:12 AM Lozoya, Manny The key hole on the girls dressing room in the field house is falling (outside door). Please repair ASAP. (Mr. Orozoo) Mireya Meza 89726 Field House Athletic Field 7/10/2012 4:23:59 PM Valdez, Pedro We need 8 sets of tires attached to the soccer goals to make them mobile. Mireya Meza 99584 Field House Athletic Field 3/12/2013 84 Medium Work In Progress Lupe Ontiveros 3/12/2013 10:15:18 AM Ontiveros, Guadalupe Please pickup the field windscreens for softball field) Ontiveros, Guadalupe Please pickup the field windscreens for baseball field) CHS Borball - (install windscreens for baseball field) CHS Baseball - (install windscreens for baseball field) CHS Maretouse for: To be installed on a school to school basis. Terry Alvarado 10109 Field House Athletic Field 4/19/2013 46 Medium Work In Progress Curle Athletic Field 4/19/2013 10:26:46 AM	φ0.00
101901 Field House Dressing Room 5/8/2013 27 Medium Work In Progress 5/8/2013 8:02:12 AM 27 Lozoya, Manny The key hole on the girls dressing room in the field house is falling (outside door). Please repair ASAP. (Mr. Orozoo) 7/10/2012 329 Medium Work In Progress Athletic Field 7/10/2012 329 Medium Work In Progress 7/10/2012 4:23:59 PM 3/12/2013 84 Valdez, Pedro We need 8 sets of tires attached to the soccer goals to make them mobile. 3/12/2013 10:15:18 AM 84 Medium Work In Progress Lupe Ontiveros 3/12/2013 10:15:18 AM 84 Ontiveros, Guadalupe Please pickup the field windscreens for softball field) CHS Softball - (install windscreens for baseball field) To be installed on a school to school basis. Terry Alvarado To be installed on a school to school basis. 4/19/2013 10:26:46 AM 4/19/2013 46	
Medium Work In Progress 5/8/2013 8:02:12 AM Lozoya, Manny The key hole on the girls dressing room in the field house is falling (outside door). Please repair ASAP. (Mr. Orozoo) Mireya Meza 89726 B9726 Field House Athletic Field 7/10/2012 4:23:59 PM Valdez, Petro We need 8 sets of tires attached to the soccer goals to make them mobile. Mireya Meza 99584 99584 Field House Athletic Field 3/12/2013 99584 Field House Athletic Field 3/12/2013 10:15:18 AM Ontiveros, Guadalupe Please pickup the field windscreens from the Warehouse for: CHS Softball - (install windscreens for baseball field) CHS Softball - (install windscreens for baseball field) CHS Baseball - (install windscreens for baseball field) To be installed on a school to school basis. Terry Alvarado To be installed on a school to school basis. Terry Alvarado 4/19/2013 10:26:46 AM	\$0.00
Lozoya, Manny The key hole on the girls dressing room in the field house is falling (outside door). Please repair ASAP. (Mr. Orozoo) <u>Mireya Meza</u> <u>39726</u> Field House Athletic Field 7/10/2012 329 Medium Work In Progress Veneed 8 sets of tires attached to the soccer goals to make them mobile. <u>Mireya Meza</u> <u>399584</u> Field House Athletic Field 3/12/2013 84 Medium Work In Progress Lupe Ontiveros 3/12/2013 10:15:18 AM Ontiveros, Guadalupe Please pickup the field windscreens from the Warehouse for: CHS Softball - (install windscreens for baseball field) CHS Baseball - (install windscreens for baseball field) To be installed on a school to school basis. <u>Terry Alvarado</u> Medium Work In Progress Athletic Field 4/19/2013 10:26:46 AM	ψ0.00
89726 Field House Athletic Field 7/10/2012 329 Medium Work In Progress 7/10/2012 4:23:59 PM Xeldez, Pedro We need 8 sets of tires attached to the soccer goals to make them mobile. Mireya Meza 99584 Field House Athletic Field 3/12/2013 84 Medium Work In Progress Lupe Ontiveros 3/12/2013 10:15:18 AM 84 Ontiveros, Guadalupe Please pickup the field windscreens from the Warehouse for: CHS Softball - (install windscreens for softball field) CHS Softball - (install windscreens for baseball field) To be installed on a school to school basis. To be installed on a school to school basis. 4/19/2013 46 Medium Work In Progress 4/19/2013 10:26:46 AM 4/19/2013 46	
Medium Work In Progress 7/10/2012 4:23:59 PM Valdez, Pedro We need 8 sets of tires attached to the soccer goals to make them mobile. Mireya Meza 99584 Field House Athletic Field 3/12/2013 84 Medium Work In Progress Lupe Ontiveros 3/12/2013 10:15:18 AM 84 Ontiveros, Guadalupe Please pickup the field windscreens from the Warehouse for: CHS Softball - (install windscreens for softball field) 1 CHS Softball - (install windscreens for baseball field) CHS Baseball - (install windscreens for baseball field) 1 1 Terry Alvarado To be installed on a school to school basis. 4/19/2013 46 Medium Work In Progress Athletic Field 4/19/2013 10:26:46 AM	\$0.00
Mireya Meza 99584 Field House Athletic Field 3/12/2013 84 Medium Work In Progress Lupe Ontiveros 3/12/2013 10:15:18 AM 84 Ontiveros, Guadalupe Please pickup the field windscreens from the Warehouse for: CHS Softball - (install windscreens for softball field) 101105 CHS Baseball - (install windscreens for baseball field) 101109 Field House Athletic Field 4/19/2013 46 Medium Work In Progress Athletic Field 4/19/2013 10:26:46 AM 4/19/2013 46	
99584 Field House Athletic Field 3/12/2013 84 Medium Work In Progress Lupe Ontiveros 3/12/2013 10:15:18 AM Ontiveros, Guadalupe Please pickup the field windscreens from the Warehouse for: Please pickup the field windscreens for softball field) CHS Softball - (install windscreens for baseball field) CHS Baseball - (install windscreens for baseball field) To be installed on a school to school basis. To be installed on a school to school basis. Terry Alvarado 4/19/2013 46 Medium Work In Progress 4/19/2013 10:26:46 AM	
Medium Work In Progress Lupe Ontiveros 3/12/2013 10:15:18 AM Ontiveros, Guadalupe Please pickup the field windscreens from the Warehouse for: CHS Softball - (install windscreens for softball field) CHS Softball - (install windscreens for baseball field) CHS Baseball - (install windscreens for baseball field) Terry Alvarado To be installed on a school to school basis. Terry Alvarado 4/19/2013 Medium Work In Progress	\$0.00
Ontiveros, Guadalupe Please pickup the field windscreens from the Warehouse for: CHS Softball - (install windscreens for softball field) CHS Baseball - (install windscreens for baseball field) To be installed on a school to school basis. <u>Terry Alvarado</u> 101109 Field House Athletic Field 4/19/2013 46 Medium Work In Progress 4/19/2013 10:26:46 AM	
CHS Baseball - (install windscreens for baseball field) To be installed on a school to school basis. Terry Alvarado 101109 Field House Athletic Field 4/19/2013 46 Medium Work In Progress 4/19/2013 10:26:46 AM	
CHS Baseball - (install windscreens for baseball field) To be installed on a school to school basis. Terry Alvarado 101109 Field House Athletic Field 4/19/2013 46 Medium Work In Progress 4/19/2013 10:26:46 AM	
To be installed on a school to school basis. Terry Alvarado 101109 Field House Athletic Field 4/19/2013 46 Medium Work In Progress 4/19/2013 10:26:46 AM 4/19/2013 46	
Terry Alvarado 101109 Field House Athletic Field 4/19/2013 46 Medium Work In Progress 4/19/2013 10:26:46 AM 4/19/2013 46	
101109 Field House Athletic Field 4/19/2013 46 Medium Work In Progress 4/19/2013 10:26:46 AM 4/19/2013 46	
ŭ	\$0.00
Ontiveros, Guadalupe Would like to have a canopy set up for entrance of	
softball and baseball games. Area to be used for ticket sales and concessions. Maybe some cement to be poured or/and permanent canopy. (Ms. Ulibarri)	
Mireya Meza 6/4/2013 9:16:05 AM Pag	

WOID Priority Assigned Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	II HS						
102162	Field House	Mechanical		5/14/2013		21		\$0.00
Medium	Work In Progress			5/14/2013 10:45:39 AM				
Appelzolle	r, Fred	Need to replace house.	e gas valve on wate	er heater. At field				
		Need to replace	e gas valve on wate	er heater no hot water.				
<u>Alfredo Or</u> 101593	tiz Field House	Dressing Room)	5/2/2013		33		\$0.00
Medium	Work In Progress			5/2/2013 9:11:11 AM				<i>Q</i> 0.00
Vallejo, All	-		w electrical wires to eld house for all the	o install new				
Alfredo Or 102662	tiz Field House	Athletic Field		5/29/2013		6		\$0.00
Medium	Work In Progress			5/29/2013 9:04:04 AM				
Munoz, Mi			nt canopies to be p ntrance, to help wit	laced at softball & h athletic entrances.				
Mireya Me				5/00/0010				<u> </u>
102663	Field House	Athletic Field		5/29/2013		6		\$0.00
Medium Munoz, Mi	Work In Progress	concession sta	anopy is needed to nd by the soccer fie soccer games. (Ma	eld. To be used for				
<u>Mireya Me</u> 101922	za Field House	Dressing Room)	5/8/2013		27		\$0.00
Medium	Work In Progress	Diessing Roon	•	5/8/2013 2:33:07 PM		21		ψ0.00
Lozoya, M	· ·	Need to repair	door lock, trouble c					
•	•	Need to repair		pring with key.				
<u>Alfredo Or</u> 100837	Field House	Parking Lot		4/11/2013		54		\$0.00
Medium	Work In Progress			4/11/2013 12:30:59 PM				
Lozoya, M		going into the f	the lock that is on potball parking lot t very hard to open	o open with key CH				
Mireya Me	za							

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Area Deferred By Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	I HS					
102085	Field House	Athletic Field	5/13/2013		22		\$0.00
Medium	Work In Progress		5/13/2013 10:57:40 AM				
Ontiveros,	Guadalupe	Soccer goals need to be replaced to being damanged from high wir Hernandez)	d on practice field due nds. (coach				
Mireya Mez							
102084	Field House	Athletic Field	5/13/2013		22		\$0.00
Medium	Work In Progress		5/13/2013 10:53:23 AM				
Valdez, Pe	dro	Practice and game fields for soco dressed, re-seeded and watered					
Mireya Mez	za Field House	Athletic Field	5/20/2013		15		\$0.00
102383		Athletic Field			15		φ0.00
Medium	Work In Progress		5/20/2013 11:25:29 AM				
Valdez, Pe		Per Coach Mendoza both practic fields have not been watered and dead and their are a lot of bare s is dry and hard due to lack of wat be top dressed, seeded and water	l maintained. Grass is pots on fields. Ground ering. Fields need to				
Mireya Mez		<u>Cum</u>	5/8/2013		27		\$0.00
101924	H-Wing	Gym			21		Ф 0.00
Medium	Work In Progress		5/8/2013 2:48:15 PM				
Ortiz, Alfred		Need to replace two A/C motors of room and one for consetion stan					
Alfredo Ort 99856	IZ H-Wing	Gym	3/19/2013		77		\$0.00
Medium	Work In Progress		3/19/2013 10:54:39 AM				
Ortiz, Alfred	ob	Need to replace Isolater Vibratior Evaporative Coolers for GYM.					
Alfredo Ort 100795	iz H-Wing	Dressing Room	4/10/2013		55		\$0.00
Medium	Work In Progress	Brooking Koonn	4/10/2013 3:21:36 PM		00		φ0.00
	Ŭ						
Appelzoller		Need to repair water faucet wash roomwon't stop running.	bin in boys locker				
Alfredo Ort 98980	iz H-Wing	Classroom	2/27/2013		97		\$0.00
Medium	Work In Progress		2/27/2013 4:42:47 PM				
Munoz, Mic	-	Expand athletic training room in g north wall and building larger athl Unable to do complete therapies (Mr. Beets)	etic training room.				

WOID Priority Assigned 1 Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	I HS						
101105		Pump House		4/19/2013		46		\$0.00
Medium	Work In Progress			4/19/2013 8:55:45 AM				
Ortiz, Alfred	do		ot respond replace	e fire pump room is ed panal battery and				
Alfredo Orti 96443	z Pre-K			12/10/2012		176		\$0.00
Medium	Work In Progress			12/10/2012 3:07:05 PM		110		ψ0.00
Gonzalez, S	-	Need to repaid	gate door, lach bro					
Alfredo Orti			gato door, idon bri					
102983	2			6/2/2013		2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:42 AM				
Ortiz, Alfred	do	Monthly - Chap PM schedule de		E Inspection - Refer to				
Margret Vill 99232	alobos			3/3/2013		93		\$0.00
Medium	Work In Progress			3/3/2013 12:26:05 AM				·
Munoz, Mic	chael	Yearly - Chapa PM schedule de		sp. (Yearly) - Refer to				
Margret Vill 99080	alobos			3/1/2013		95		\$0.00
Medium	Work In Progress			3/1/2013 12:24:47 PM		30		ψ0.00
Carbajal, Ji	· ·	Advance terra 3 charge.	3700b auto sweep	er batteries do not take				
Jesus Urqu	iidi							
99912				3/20/2013		76		\$0.00
Medium	Work In Progress			3/20/2013 9:39:11 AM				
Carbajal, Ji	mmy	roto sr 100a003	304 needs plug					
<u>Jesus Urqu</u> 101548	lidi			5/1/2013		34		\$0.00
Medium	Work In Progress			5/1/2013 9:29:56 AM		-		,
Carbajal, Ji	-	adfinity 20d aut 351012290206	o scrubber pad ho 8					
Jesus Urqu	idi			E 100 100 10				<u> </u>
102716				5/30/2013		5		\$0.00
Medium	Work In Progress			5/30/2013 7:47:34 AM				
Carbajal, Ji Jesus Urqu	-	vaccum sr h060 motor smells lik	c00000119 sparks ke burnt.	are coming out of				

WOID Priority Assigned 1 Requester		Area Area Number Description	Deferred By		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparral	HS						
99580		Classroom		3/12/2013		84		\$0.00
Medium	Work In Progress			3/12/2013 8:54:07 AM				
Gallegos, F	Rafael	late becauce of	Gallegos the heat the time change. T classrooms are to					
Alfredo Ort 100379	iz			3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress			3/31/2013 12:33:29 AM	1/21/2010	00		φ0.00
Orozco, Da	0	Monthly - Chap PM schedule d		od Cleaning - Refer to				
Margret Vil	lalobos							
102986				6/2/2013		2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:44 AM				
Ortiz, Alfree		Monthly - Chap Refer to PM sc	arral HS Emer. Lig hedule details.	ht Test: Monthly -				
Margret Vil 96587	lalobos	Parking Lot		12/13/2012		173		\$0.00
Medium	Work In Progress	U U		12/13/2012 11:46:18				·
Gonzalez, a	C	the fence that a driving access parents are cut	also includes a sepe can be denied beca	omes from the end of erate pole so that ause the students and as they are driving off.				
Mireya Mez	za	Darking Lat		E/21/2012		1		¢0.00
102794		Parking Lot		5/31/2013		4		\$0.00
Medium	Work In Progress			5/31/2013 7:54:06 AM				
Gonzalez,	Salvador	Need to install	gate stoppers on bo	oth Main entrances.				
Alfredo Ort	iz			8/6/2012		302		\$0.00
90833						302		Φ 0.00
Medium	Work In Progress			8/6/2012 10:03:59 AM				
Gonzalez,	Salvador	Need to weld S	occer Goals					
Guadalupe 100887	Ontiveros			4/12/2013		53		\$0.00
	Work In Brogross					55		ψ0.00
Medium	Work In Progress			4/12/2013 3:35:57 PM				
Lozoya, Ma	anny		e locks on all outsid ill open them and to					
Alfredo Ort	iz							

WOID Priority Assigned Requester		Area Area Number Description	Deferred By Reason	-	te Target Comp Date le Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparral	HS						
96629		Classroom		12/14/20	12	172		\$0.00
Medium	Work In Progress			12/14/2012 10:02:	17			
Lozoya, M	anny	having trouble of		r custodian. He is rs. The key might be (Mireya Meza)				
<u>Mireya Me</u> 102808	za	Athletic Field		5/31/20	13	4		\$0.00
High	Work In Progress			5/31/2013 8:31:39				φ0.00
Lara, Ralp	C C			ouse and key to open he key to open is A-34				
Guadalupe 90843	e Ontiveros			8/6/20	12	302		\$0.00
Medium	Work In Progress			8/6/2012 11:26:25		002		<i>Q</i> 0 · 0
Lozoya, M	-	Room A-108, #8						
Mireya Me 102775	za			5/31/20	13 7/1/2013	4		\$0.00
Medium	Work In Progress			5/31/2013 12:28:47		·		φ0.00
Ortiz, Alfre	Ū	Yearly - Chapar PM schedule de		nit)(Yearly) - Refer to				
Margret Vi	llalobos							
101872		Roof		5/7/20	13	28		\$0.00
Medium	Work In Progress			5/7/2013 3:21:51 I	PM			
Solis, Lore		Need to fabricat sand out of A/C		s for gutters to keep				
Alfredo Ori 100796	tiz	Cafeteria		4/10/20	13	55		\$0.00
Medium	Work In Progress			4/10/2013 3:23:47 I	PM			
Solis, Lore	enzo	Having trouble v	with A/C unit in kite	chen too hot.				
Alfredo Or	tiz							
102797		Restroom		5/31/20	13	4		\$0.00
Medium	Work In Progress			5/31/2013 7:59:14	λM			
Appelzolle	r, Fred		the bottom. At ma	nd seal toilets, water ain build. and Field				
	tiz							

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Loca Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	IHS					
102849			6/2/2013	6/5/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:40 AM				
Ortiz, Alfre	do	Monthly - Chaparral HS - Emer. Eye Refer to PM schedule details.	wash (Monthly) -				
Margret Vi	llalobos		E/00/0040		40		<u> </u>
102565			5/23/2013		12		\$0.00
Medium	Work In Progress	LINE LOCATE	5/23/2013 4:04:44 PM				
Appelzolle	r, Fred	Company: WARREN CONSTRUCTIO Contact Name: ROD KRAUSKOPF Phone: (575)644-0616					
		INSTALL NEW TENNIS COURTS == EXISTING BASKETBALL COURT F FENCE TO THE PONDING AREA - / MARKED IN WHITE - NO HAZARDS	ROM CHAIN LINK AREA WILL BE				
Alfredo Ho	lguin		4/40/0040		47		
101057		Athletic Field	4/18/2013		47		\$0.00
Medium	Work In Progress		4/18/2013 7:41:05 AM				
	Guadalupe	buster pump needs to be replaced fo presure.	r more water				
101751	e Ontiveros		5/5/2013		30		\$0.00
Medium	Work In Progress		5/5/2013 12:24:32 AM				
Apodaca, I	Mario	Monthly - Chaparral HS - Lift Station to PM schedule details.	Inspection - Refer				
Margret Vi	llalobos		0/0/0040				<u> </u>
102959			6/2/2013		2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:32 AM				
Apodaca, I		Monthly - Chaparral HS - Lift Station to PM schedule details.	Inspection - Refer				
Margret Vil 100305	llalobos		3/31/2013		65		\$0.00
Medium	Work In Progress		3/31/2013 12:32:59 AM				
Holguin, A	-	Monthly - Chaparral HS - Fire Pump I PM schedule details.					
Margret Vi	llalobos						
102900			6/2/2013		2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:04 AM				
Ortiz, Alfre	do	Monthly - Chaparral HS - Clothes Dry Refer to PM schedule details.	ver (Monthly) -				
Margret Vi	llalobos						

WOID Priority	Building Status	Dates:7/1/2012 - 6/30/2013 Order By Area Deferred By Area Number Reason		Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned		Description		Action Taken			
Requester	Name						
Location:	Chaparra	I HS					
102887			6/2/2013		2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:58 AM				
Ortiz, Alfre	do	Monthly - Chaprral HS Exit Sign PM schedule details.	Insp: Monthly - Refer to				
Margret Vi 102888	llalobos		6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:59 AM	1/3/2013	2		ψ0.00
	0						
Ortiz, Alfre	00	Monthly - Chaparral HS Bleacher PM schedule details.	r inspection - Refer to				
Margret Vi	llalobos						
101857		Hallway/Corridor	5/7/2013		28		\$0.00
Medium	Work In Progress		5/7/2013 8:45:46 AM				
Ortiz, Alfre	do	Need to replace filters on A/C un	its in hallways.				
Alfredo Or	tiz						
102114		Exterior	5/13/2013		22		\$0.00
Medium	Work In Progress		5/13/2013 3:41:00 PM				
Ortiz, Alfre	do	Need to pick up trash around sch	iool.				
Alfredo Or	tiz						
96586		Parking Lot	12/13/2012		173		\$0.00
Medium	Work In Progress		12/13/2012 11:43:18				
Ortiz, Alfre	do	We need several signs to be place of the school. Please see Lupe C					
Mireya Me							
Count: 85	Work Orders	Avg. Age of WO's	64	Total for Chaparra	al HS	0	\$0.00

WOID Priority Assigned Requester	Building Status To	•	st Date Target Comp Date re/Time Actual Comp Date Action Taken	Days Lab Aged Hou	
Location:	Chaparra	IMS			
101482		4/	30/2013	35	\$0.00
Medium	Work In Progress	4/30/2013 10:5	0:28 AM		
Vallejo, Alt	pert	Install hose bib in planter area of front entrance.			
Albert Vall 92678	ejo	9/	11/2012	266	\$0.00
Medium	Work In Progress	9/11/2012 11:2	7:08 AM		
Apodaca, I	Mario	I would like to have Mario come out to help me work on the irrigation booster pump.			
Albert Valle 99392	ejo		9/6/2013	90	\$0.00
99392 Medium	Work In Progress	3/6/2013 8:0		90	ψ0.00
	Guadalupe	Please install bubblers for two new trees in front of school.	0.+0 / Wi		
Albert Valle	ejo				
99760		3/	15/2013	81	\$0.00
Medium	Work In Progress	3/15/2013 12:1	4:45 PM		
Ontiveros,	Guadalupe	Need to repair vandalized sprinklers in front lawn area.			
Albert Valle 101536	ejo	E	5/1/2013	34	\$0.00
Medium	Work In Progress	5/1/2013 8:0		54	ψ0.00
	· ·		1.30 AM		
	Guadalupe	Install bubblers for new trees in entrance area.			
Albert Valle 101858	ejo	5	5/7/2013	28	\$0.00
Medium	Work In Progress	5/7/2013 8:5	2:34 AM		
Quinones,	Paul	ORDER A/C MOTOR BELTS FOR RESTOCK			
Paul Quino 101677	ones	5	5/5/2013 5/13/2013	30	\$0.00
Medium	Work In Progress	5/5/2013 12:2			
Vallejo, Alt	· ·	Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.			
Margret Vi	llalobos		17/0010	40	#0.00
102294			17/2013	18	\$0.00
Medium	Work In Progress	5/17/2013 12:4	4:39 PM		
Appelzolle	r, Fred	#100 hallway restroom da boys ls escusados estan tapados GRACIAS			
M. Carmer	n Perez				

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time A	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Chaparra	II MS					
102848			6/2/2013	6/5/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:39 AM				
Vallejo, Al	bert	Monthly - Chaparral MS - Emerg. E Refer to PM schedule details.	Eyewash (Monthly) -				
Margret Vi 102256	illalobos		5/16/2013		19		\$0.00
Medium	Work In Progress		5/16/2013 9:23:54 AM		10		ψ0.00
	-	Clean and replace P-trap for lobby					
Appelzolle							
Albert Vall 100582	ејо	Restroom (Girls)	4/5/2013		60		\$0.00
Medium	Work In Progress		4/5/2013 9:28:06 AM				
Appelzolle	er, Fred	senecesita areglar lavado de mano lobby restroom (girls) GRACIAS	os esta suelto del				
<u>M. Carmer</u> 102758	n Perez		5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:39 AM				
Vallejo, Al	bert	Yearly - Chaparral MS A2 (H/C Un PM schedule details.	it)(Yearly) - Refer to				
Margret Vi 102877	illalobos		6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Brogroop		6/2/2013 12:28:54 AM	1/3/2013	2		φ0.00
	Work In Progress						
Vallejo, Al	bert	Yearly - Chaparral MS B2 (Boiler)(schedule details.	Yearly) - Refer to PM				
Margret Vi	illalobos		E/20/2012		45		\$0.00
102371			5/20/2013		15		\$0.00
Medium	Work In Progress		5/20/2013 10:44:41 AM				
Vallejo, Al		Paint over existing murals in open	courtyard.				
Albert Vall 101900	ejo	Computer Lab	5/8/2013		27		\$0.00
Medium	Work In Progress	207-208	5/8/2013 8:00:04 AM				<i>Q</i> 0.00
Vallejo, Al	C	(Summer Project) Paint computer I					
•							
Albert Vall 96486	σjU		12/11/2012		175		\$0.00
Medium	Work In Progress		12/11/2012 3:21:43 PM				
Lozoya, M	anny	Key to room 106 is not working pro	perly				
Albert Vall	-						
Albert Vall	ejo						

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	IMS						
99679		Athletic Field		3/13/2013		83		\$0.00
Medium	Work In Progress			3/13/2013 4:15:00 PM				
Ontiveros,	Guadalupe	please connect of football field.		s to east and west side				
Michael Mu 95176	unoz			11/5/2012		211		\$0.00
Medium	Work In Program			11/5/2012 2:14:02 PM		211		ψ0.00
	Work In Progress							
Gonzalez,		Please fabricat room.	e ice machine star	id in Athletics locker				
Albert Valle 102897	ejo			6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:03 AM				
Vallejo, Alb	-	Monthly - Chap to PM schedule		Insp: Monthly - Refer				
Margret Vil	lalobos			6/2/2013	7/3/2013	2		\$0.00
102886						Z		Φ 0.00
Medium Vallejo, Alb	Work In Progress			6/2/2013 12:28:58 AM Inspection - Refer to				
Margret Vil	lalohos	PM schedule d	etalis.					
102898				6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:04 AM				
Vallejo, Alb	pert	Monthly - Chap Refer to PM sc		ght Test: Monthly -				
Margret Vil	lalobos			6/2/2013		2		\$0.00
102899 Medium	Work In Progress			6/2/2013 12:29:04 AM		2		ψ0.00
Vallejo, Alb	•	Monthly - Chap Refer to PM sc	arral MS - Clothes					
Margret Vil	lalobos							
102077		Hallway/Corrid	or	5/13/2013		22		\$0.00
Medium	Work In Progress			5/13/2013 9:53:28 AM				
Lara, Ralpl	h		0 hallway estan ca jue estan parair cu					
M. Carmen 100728	Perez			4/9/2013		56		\$0.00
Medium	Work In Progress			4/9/2013 11:18:52 AM		00		ψ0.00
Munoz, Mie	•		board for soccer ar	nd football. old one				
	an	does not work.						

6/4/2013 9:16:05 AM

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Log Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	al MS					
99231			3/3/2013		93		\$0.00
Medium	Work In Progress		3/3/2013 12:26:05 AM				
Munoz, Mi	chael	Yearly - Chaparral MS Fire Ext. Ins PM schedule details.	sp. (Yearly) - Refer to				
Margret Vi 102981	llalobos		6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:41 AM	0/0/2010	2		ψ0.00
Vallejo, Alt	pert	Monthly - Chaparral MS Monthly Fl to PM schedule details.					
Margret Vi 99916	llalobos		3/20/2013		-245		\$0.00
Medium	Work In Progress		3/20/2013 9:49:59 AM	7/18/2012			·
Estrada, Je	-	NEED GYM FLOORS TO BE RE-F L - 100' X W - 90') TO BE	FINISHED (APPROX.				
<u>Jesus Estr</u> 100714	ada Main Building	Classroom	4/9/2013		56		\$0.00
Medium	Work In Progress	p-14	4/9/2013 8:41:41 AM		00		ψ0.00
Estrada, Je	Ū	Floor tile detached. please repair	-73/2010 01117 (W				
		r loor the detached. please repair					
Gidget Mo 101173	Main Building	Gym	4/22/2013		43		\$0.00
Medium	Work In Progress	girls locker room	4/22/2013 3:21:24 PM				
Lozoya, M	anny	The doors on the restroom on the r broken or non existent. Please repart					
<u>Gidget Mo</u> 102156	ra Main Building	Classroom	5/14/2013		21		\$0.00
Medium	Work In Progress	407	5/14/2013 9:01:32 AM		21		ψ0.00
Lara, Ralp	Ū	Door Slams, needs adjustment 4th					
-		Door Stains, needs adjustment 4th	nouce				
Gidget Mo 101415	ra Main Building	Classroom	4/29/2013		36		\$0.00
Medium	Work In Progress	407	4/29/2013 2:37:02 PM				
Lozoya, M	anny	Door slams really hard. Please rep	air				
Gidget Mo	ra						
101551	Main Building	Classroom	5/1/2013		34		\$0.00
Medium	Work In Progress		5/1/2013 9:45:44 AM				
Lozoya, M	anny	puerta de banda esta caida 400/HA areglar GRACIAS	ALLWAY senesecita				
M. Carmer	n Perez						

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By Reason	Until Request Date Ta Created Date/Time Ac	 Days Aged	Labor Hours	Costs
Location:	Chaparra	IMS					
101861	Main Building	Gym		5/7/2013	28		\$0.00
Medium	Work In Progress			5/7/2013 9:00:50 AM			
Vallejo, Alb	pert		board padding ne ted in storage insi	eds to be replaced. de the gym.			
Gidget Mor		-			4.0		\$ 0.00
102292	Main Building	Library		5/17/2013	18		\$0.00
Medium	Work In Progress			5/17/2013 11:28:57 AM			
Vallejo, Alb	pert	Please Assemb	le laminating mac	hine			
<u>Gidget Mo</u> 102293	ra Main Building	Library		5/17/2013	18		\$0.00
Medium	Work In Progress			5/17/2013 11:30:28 AM			<i>Q</i> 0 · 0
Vallejo, Alt	C C	balt presentatio	n cart needs to be				
Gidget Mor		ban procentatio					
101168	Main Building	Classroom		4/22/2013	43		\$0.00
Medium	Work In Progress	407		4/22/2013 2:52:27 PM			
Lozoya, Ma	anny	Door slams. Ha	ndle does not wor	k			
Gidget Mor							
101217	Main Building	Classroom		4/23/2013	42		\$0.00
Medium	Work In Progress	308		4/23/2013 1:56:34 PM			
Lozoya, Ma	anny	Classroom doo	r is extremely diffic	cult to lock			
Gidget Mor 99028	ra Main Building			2/28/2013	96		\$0.00
Medium	Work In Progress			2/28/2013 10:03:07 AM			
Lozoya, Ma	C C	please make ke	ev for 405B				
Gidget Mor	-	prodoo mano na					
99030	Main Building			2/28/2013	96		\$0.00
Medium	Work In Progress	Security		2/28/2013 10:04:31 AM			
Lozoya, Ma	anny	Please fix lock	on security door				
<u>Gidget Mor</u> 93237	ra Main Building	Classroom		9/25/2012	252		\$0.00
Medium	Work In Progress	308		9/25/2012 3:11:29 PM			<i>40.00</i>
Lozoya, Ma	-		like locks put on c				
Gidget Mor	-						

Priority Status Area Number Reason Created Date/Time Actual Comp Date Aged Action Taken Hou Assigned To Description Action Taken Action Taken Action Taken Action Taken Hou Requester Name Location: Chaparral MS Status 27 Status Status 27 Medium Work In Progress 100-200 Hall 5/8/2013 8:03:56 AM 27 Status Status Status Status Status Status 27 Status Status<	Costs	Labor	Days	Farget Comp Date		6/30/2013 Order By Loo Deferred By	Area	Building	WOID
Requester Name Location: Chaparral MS 101902 Main Building Restroom (Boys) 5/8/2013 27 Medium Work In Progress 100-200 Hall 5/8/2013 8:03:56 AM 27 Vallejo, Albert (Summer Project) Remove partitions, tile and drywall. Install plywood and FRP panel, replace fixtures and install new partitions. 27 Albert Vallejo 101903 Main Building Restroom (Boys) 5/8/2013 27 Medium Work In Progress 100-200 Hallway 5/8/2013 8:06:54 AM 7 Albert Vallejo 101903 Remove and replace fixtures in two restrooms for remodeling. (includes two urinals and two commodes per restroom) 27 Albert Vallejo 100892 4/12/2013 53 Medium Work In Progress 4/12/2013 3:4 Medium Work In Progress 3/1/2013 95 Medium Work In Progress 3/1/2013 95 Medium Work In Progress 3/1/2013 4/21/2013 Suss Estrada 99091 3/1/2013 95 Medium Work In Progress 3/31/2013 4/21/2013 Suss Stra	1	Hours	Aged			•	Area Number	Status	Priority
Location: Chaparral MS 101902 Main Building Restroom (Boys) 5/8/2013 27 Medium Work In Progress 100-200 Hall 5/8/2013 8:03:56 AM 7 Vallejo, Albert (Summer Project) Remove partitions, tile and drywall. Install plywood and FRP panel, replace fixtures and install new partitions. 7 Albert Vallejo 100-200 Hallway 5/8/2013 27 Medium Work In Progress 100-200 Hallway 5/8/2013 27 Albert Vallejo 100-200 Hallway 5/8/2013 8:06:54 AM 4 Appelzoller, Fred Remove and replace fixtures in two restrooms for remodeling. (includes two urinals and two commodes per restroom) 53 Albert Vallejo 100592 4/12/2013 53 Medium Work In Progress 3/1/2013 3:16:16 PM				Action Taken			Description	Го	Assigned 1
101902 Main Building Restroom (Boys) 5/8/2013 27 Medium Work In Progress 100-200 Hall 5/8/2013 8:03:56 AM 7 Vallejo, Albert (Summer Project) Remove partitions, tile and drywall. Install plywood and FRP panel, replace fixtures and install new partitions. 7 Albert Vallejo								Name	Requester
Medium Work In Progress 100-200 Hall 5/8/2013 8:03:56 AM Vallejo, Albert (Summer Project) Remove partitions, tile and drywall. Install plywood and FRP panel, replace fixtures and install new partitions. 27 Albert Vallejo							IMS	Chaparra	Location:
Vallejo, Albert Vallejo Albert Vallejo Albert Vallejo 101903 Main Building Restroom (Boys) 5/8/2013 27 Medium Work In Progress 100-200 Hallway 5/8/2013 8:06:54 AM Appelzoller, Fred Remove and replace fixtures in two restrooms for remodeling, (includes two urinals and two commodes per restroom) Albert Vallejo 100892 4/12/2013 3:46:14 PM Estrada, Jesus NEED SEAMS REPAIRED ON CARPET IN BAND ROOM Jesus Estrada 99091 3/1/2013 3:18:36 PM Estrada, Jesus NEED TO INSTALL COVE BASE IN CAFETERIA Jesus Estrada 100363 3/31/2013 4/21/2013 65 Medium Work In Progress 3/31/2013 12:33:22 AM Orozco, Daniel Monthly - Chapparal MS Range Hood Cleaning - Refer	\$0.00		27		5/8/2013	rs)	Restroom (Boy	Main Building	101902
Install plywood and FRP panel, replace fixtures and install new partitions. Albert Vallejo 7 101903 Main Building Restroom (Boys) 5/8/2013 27 Medium Work In Progress 100-200 Hallway 5/8/2013 8:06:54 AM 7 Appelzoller, Fred Remove and replace fixtures in two restrooms for remodeling. (includes two urinals and two commodes per restroom) 7 7 Albert Vallejo 4/12/2013 53 7 100892 4/12/2013 3:46:14 PM 7 Estrada, Jesus NEED SEAMS REPAIRED ON CARPET IN BAND ROOM 7 7 Jesus Estrada 3/1/2013 95 7 Medium Work In Progress 3/1/2013 95 Strada, Jesus NEED TO INSTALL COVE BASE IN CAFETERIA 9003 3/31/2013 4/21/2013 65 Medium Work In Progress 3/31/2013 12:33:22 AM 65 65 Medium Work In Pro					5/8/2013 8:03:56 AM		100-200 Hall	Work In Progress	Medium
101903 Main Building Restroom (Boys) 5/8/2013 27 Medium Work In Progress 100-200 Hallway 5/8/2013 8:06:54 AM 4 Appelzoller, Fred Remove and replace fixtures in two restrooms for remodeling. (includes two urinals and two commodes per restroom) 53 Albert Vallejo 4/12/2013 53 100892 4/12/2013 3:46:14 PM 53 Medium Work In Progress 4/12/2013 3:46:14 PM 53 Estrada, Jesus NEED SEAMS REPAIRED ON CARPET IN BAND ROOM 53 Medium Work In Progress 3/1/2013 3:18:36 PM 53 Medium Work In Progress 3/1/2013 3:18:36 PM 53 Strada, Jesus NEED TO INSTALL COVE BASE IN CAFETERIA 53 Jesus Estrada 3/31/2013 12:33:22 AM 65 Medium Work In Progress 3/31/2013 12:33:22 AM 65 Medium Work In Progress 3/31/2013 12:33:22 AM 65						and FRP panel, repla	Install plywood	pert	Vallejo, Alb
Medium Work In Progress 100-200 Hallway 5/8/2013 8:06:54 AM Appelzoller, Fred Remove and replace fixtures in two restrooms for remodeling. (includes two urinals and two commodes per restroom)	\$0.00		27		5/8/2013	rs)	Restroom (Boy		
Appelzoller, Fred Remove and replace fixtures in two restrooms for remodeling. (includes two urinals and two commodes per restroom) Albert Vallejo 4/12/2013 100892 4/12/2013 Medium Work In Progress Estrada, Jesus NEED SEAMS REPAIRED ON CARPET IN BAND ROOM Jesus Estrada 3/1/2013 99091 3/1/2013 Medium Work In Progress Strada, Jesus NEED SEAMS REPAIRED ON CARPET IN BAND ROOM Jesus Estrada 3/1/2013 99091 3/1/2013 Strada, Jesus NEED TO INSTALL COVE BASE IN CAFETERIA Jesus Estrada 3/31/2013 100363 3/31/2013 Medium Work In Progress 3/31/2013 3/31/2013 Medium Work In Progress 3/31/2013 3/31/2013 4/21/2013 65 Medium Work In Progress 3/31/2013 12:33:22 AM Orozco, Daniel Monthly - Chapparal MS Range Hood Cleaning - Refer	<i>Q</i> O I O O							C C	
1008924/12/201353MediumWork In Progress4/12/2013 3:46:14 PMEstrada, JesusNEED SEAMS REPAIRED ON CARPET IN BAND ROOM90091Jesus Estrada3/1/2013990913/1/2013MediumWork In ProgressStrada, JesusNEED TO INSTALL COVE BASE IN CAFETERIAJesus Estrada3/31/20131003633/31/2013MediumWork In ProgressJosof S3/31/2013MediumWork In ProgressJosof S3/31/2013MediumWork In ProgressJosof S3/31/2013MediumWork In ProgressJosof S3/31/2013MediumWork In ProgressJorozco, DanielMonthly - Chapparal MS Range Hood Cleaning - Refer						eplace fixtures in two	Remove and re remodeling. (in	5	Appelzoller
Medium Work In Progress 4/12/2013 3:46:14 PM Estrada, Jesus NEED SEAMS REPAIRED ON CARPET IN BAND ROOM 900 Jesus Estrada 3/1/2013 95 Medium Work In Progress 3/1/2013 3:18:36 PM Estrada, Jesus NEED TO INSTALL COVE BASE IN CAFETERIA 100363 Jesus Estrada 3/31/2013 4/21/2013 65 Medium Work In Progress 3/31/2013 12:33:22 AM 65 Medium Work In Progress 3/31/2013 12:33:22 AM 65			50		4/40/0040			ejo	
Estrada, Jesus NEED SEAMS REPAIRED ON CARPET IN BAND <u>AOOM</u> <u>Jesus Estrada</u> <u>99091</u> 3/1/2013 3:18:36 PM Estrada, Jesus NEED TO INSTALL COVE BASE IN CAFETERIA <u>Jesus Estrada</u> <u>100363</u> 3/31/2013 4/21/2013 65 Medium Work In Progress 3/31/2013 12:33:22 AM Orozco, Daniel Monthly - Chapparal MS Range Hood Cleaning - Refer	\$0.00		53						
Jesus Estrada 3/1/2013 95 99091 3/1/2013 3/1/2013 Medium Work In Progress 3/1/2013 3/1/2013 Estrada, Jesus NEED TO INSTALL COVE BASE IN CAFETERIA					4/12/2013 3:46:14 PM			Work In Progress	Medium
990913/1/201395MediumWork In Progress3/1/2013 3:18:36 PMEstrada, JesusNEED TO INSTALL COVE BASE IN CAFETERIAJesus Estrada3/31/20131003633/31/20134/21/201365MediumWork In Progress3/31/2013 12:33:22 AMOrozco, DanielMonthly - Chapparal MS Range Hood Cleaning - Refer					ET IN BAND	REPAIRED ON CAR		esus	Estrada, Je
Medium Work In Progress 3/1/2013 3:18:36 PM Estrada, Jesus NEED TO INSTALL COVE BASE IN CAFETERIA Jesus Estrada 3/31/2013 4/21/2013 65 Medium Work In Progress 3/31/2013 12:33:22 AM 65 Orozco, Daniel Monthly - Chapparal MS Range Hood Cleaning - Refer 5	\$0.00		05		2/1/2012			ada	
Estrada, Jesus NEED TO INSTALL COVE BASE IN CAFETERIA <u>Jesus Estrada</u> 100363 3/31/2013 4/21/2013 65 Medium Work In Progress 3/31/2013 12:33:22 AM Orozco, Daniel Monthly - Chapparal MS Range Hood Cleaning - Refer	φ0.00		90						
Jesus Estrada 100363 3/31/2013 4/21/2013 65 Medium Work In Progress 3/31/2013 12:33:22 AM 65 Orozco, Daniel Monthly - Chapparal MS Range Hood Cleaning - Refer 65					3/1/2013 3:18:36 PM			Work In Progress	Medium
100363 3/31/2013 4/21/2013 65 Medium Work In Progress 3/31/2013 12:33:22 AM 65 Orozco, Daniel Monthly - Chapparal MS Range Hood Cleaning - Refer 65					CAFETERIA	TALL COVE BASE IN	NEED TO INS	esus	Estrada, Je
Medium Work In Progress 3/31/2013 12:33:22 AM Orozco, Daniel Monthly - Chapparal MS Range Hood Cleaning - Refer	\$0.00		65	4/21/2013	3/31/2013			ada	
Orozco, Daniel Monthly - Chapparal MS Range Hood Cleaning - Refer	φ0.00		00	4/21/2013					
					3/31/2013 12:33:22 AM			work In Progress	Medium
					Cleaning - Refer			aniel	Orozco, Da
Margret Villalobos Total for Chaparral MS 0 Count: 45 Work Orders Avg. Age of WO's 48 Total for Chaparral MS 0	\$0.00								

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Location Area Deferred By Unit Area Number Reason Description		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert P	ride					
101772			5/5/2013	5/11/2013	30		\$0.00
Medium	Work In Progress		5/5/2013 12:24:41 AM				
Acosta, Da	avid	Monthly - Desert Pride Monthly FE Inspect PM schedule details.	tion - Refer to				
<u>Margret Vi</u> 102984	illalobos		6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:43 AM		_		
Acosta, Da	-	Monthly - Desert Pride Monthly FE Inspect PM schedule details.					
<u>Margret Vi</u> 99234	illalobos		3/3/2013		93		\$0.00
Medium	Work In Progress		3/3/2013 12:26:06 AM		90		ψ0.00
Munoz, Mi	-	Yearly - Desert Pride HS Fire Ext. Insp. (` to PM schedule details.					
Margret Vi	illalobos						
102996		Office	6/3/2013		1		\$0.00
Medium	Work In Progress		6/3/2013 9:42:53 AM				
Gonzales,	Camilo	Please deliver 3 boxes for PO 121307447					
Larry Mart 101718	inez		5/5/2013	5/13/2013	30		\$0.00
Medium	Work In Progress		5/5/2013 12:24:19 AM	0/10/2010	00		ψ0.00
Acosta, Da	-	Monthly - Desert Pride Emer. Light Test: I to PM schedule details.					
Margret Vi	illalobos		5/5/0040	5/10/0010			<u> </u>
101719			5/5/2013	5/13/2013	30		\$0.00
Medium	Work In Progress		5/5/2013 12:24:19 AM				
Acosta, Da		Monthly - Desert Pride Exit Sign Insp: Mo PM schedule details.	nthly - Refer to				
Margret Vi 102142	illalobos		5/14/2013		21		\$0.00
Medium	Work In Progress		5/14/2013 12:22:32 AM				·
Sanchez, I	-	Monthly - Desert Pride - Water Filters - Reschedule details.	efer to PM				
Margret Vi	illalobos		= /2 / /22 · 2				.
102783			5/31/2013		4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:50 AM				
Sanchez, I		Monthly - Desert Pride - Monthly Meter Retor Northly Schedule details.	eadings - Refer				
Margret Vi	illalobos						

WOID Priority Assigned	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By I Area Deferred By Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester							
Location:	Desert P	ride					
98505			2/14/2013		110		\$0.00
Medium	Work In Progress		2/14/2013 12:21:41 AM				
Sanchez, F	Raul	Monthly - Desert Pride - Water Fill schedule details.	ters - Refer to PM				
Margret Vil 100909	llalobos		4/14/2013		51		\$0.00
Medium	Work In Progress		4/14/2013 12:19:48 AM		01		<i>Q</i> 0100
Sanchez, F	· ·	Monthly - Desert Pride - Water Filt					
Margret Vil	llalobos						
99647		Classroom	3/13/2013		83		\$0.00
Medium	Work In Progress	ROOM 1	3/13/2013 12:58:56 PM				
Ambriz, Jo		HEATING & COOLING UNIT NOT PROPERLY	T WORKING				
David Acos 99648	sta	Classroom	3/13/2013		83		\$0.00
Medium	Work In Progress	ART ROOM	3/13/2013 1:04:38 PM				·
Ambriz, Jo	-	JUST A REMINDER FOR A/C TO TIME SOON FOR PORTABLE.					
David Acos	sta		3/31/2013		65		\$0.00
100178					00		Ф 0.00
Medium	Work In Progress		3/31/2013 12:32:09 AM				
Aguilar, Pa		Monthly - Desert Pride HS A16 (Fa Refer to PM schedule details.	an Exh.)(S.Annual) -				
Margret Vil 100179	lialopos		3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress		3/31/2013 12:32:09 AM				
Aguilar, Pa	atricio	Monthly - Desert Pride HS H11 (E Refer to PM schedule details.	.Heater)(S.Annual) -				
Margret Vil	llalobos		E /04 /004 0	7/4/0040	4		<u> </u>
102773			5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:46 AM				
Aguilar, Pa		Yearly - Desert Pride HS A2 (H/C to PM schedule details.	Unit)(Yearly) - Refer				
Margret Vil 101155	llalobos	Parking Lot	4/22/2013		43		\$0.00
Medium	Work In Progress	-	4/22/2013 10:23:17 AM				
	Guadalupe	NEED TO REMOVE TWO DEAD AWAY.					
David Acos	sta						

WOID	ate Range for Request Building	Area	Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Created Date/Time		Aged	Hours	
Assigned	То	Description			Action Taken			
Requester	Name	•						
Location:	Desert Pr	ide						
101407		Portables		4/29/2013		36		\$0.00
Medium	Work In Progress	Boxing Area		4/29/2013 11:52:05 AM	l			
Munoz, Mi	chael		ndez has requested fo quipment. If there is a					
Yvette Cor	rtez							
97760		Portables		1/28/2013		127		\$0.00
Medium	Work In Progress	1,2,3,4,6.		1/28/2013 10:35:12 AM	l			
Gonzalez,	Salvador	1,2,3,4,6) NEE METHOD OF F	RAMPS TOO PORT. DS TO BE SAND BL REMOVING RUST AN E REPAINTING	ASTED OR SOME				
David Aco	sta							
102955				6/2/2013		2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:30 AM	l			
Sanchez, I	Raul	Monthly - Dese to PM schedule	ert Pride - Monthly Wa e details.	ter Samples - Refer				
Margret Vi 102909	llalobos			6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:09 AM		2		ψ0.00
Acosta, Da	C		ert Pride Exit Sign Ins					
Morarot \/;	llalahaa	PM schedule d	etalis.					
Margret Vi 102908				6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:08 AM	l			·
Acosta, Da	avid	Monthly - Dese to PM schedule	ert Pride Emer. Light 7 e details.	est: Monthly - Refer				
Margret Vi	llalobos							
Count: 21	Work Orders	A	vg. Age of WO's 42	2	Total for Desert I	Pride	0	\$0.00

WOID Priority Assigned	Building Status	Dates:7/1/2012 - 6/30/2013 Order By Location, Status Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time Addition Description Comparison Comparison	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	Name					
Location:	Desert Ti	ail Intermediate				
102052		5/12/2013	5/28/2013	23		\$0.00
Medium	Work In Progress	5/12/2013 12:21:26 AM				
Acuna, Joh	nny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.				
Margret Vil	llalobos	5/5/2013	5/13/2013	30		\$0.00
101730			5/15/2013	30		Ф 0.00
Medium	Work In Progress	5/5/2013 12:24:24 AM				
Acuna, Joh	2	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.				
Margret Vil 101731	llalobos	5/5/2013	5/13/2013	30		\$0.00
Medium	Work In Progress	5/5/2013 12:24:24 AM				
Acuna, Joh	C C	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vil	llalobos					
102918		6/2/2013		2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:13 AM				
Acuna, Joh	nny	Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret Vil 102919	llalobos	6/2/2013	6/10/2013	2		\$0.00
		6/2/2013 12:29:14 AM	0/10/2013	2		ψ0.00
Medium	Work In Progress					
Acuna, Joh	-	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.				
Margret Vil 102920	llalobos	6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:14 AM				
Acuna, Joł	nny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vil	llalobos					
94274		10/17/2012		230		\$0.00
Medium	Work In Progress	10/17/2012 3:41:51 PM				
Ontiveros,	Guadalupe	Coaches requesting to move baseball backstop to another location in same playground area. It is in the way. (Currently Located inside of the soccer playing area)				
	una					

WOID Priority Assigned ⁻ Requester		Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Ti	ail Intermediate					
99784			3/15/2013		81		\$0.00
Medium	Work In Progress		3/15/2013 3:53:45 PN	l			
Ontiveros,	Guadalupe	Need assistance in removing sma the sidewalk next to the (playgroun broken cement around playground Backhoe. Will be needing primary area.	nd) main building and I area trees with				
Johnny Act 98455	una		2/13/2013		111		\$0.00
Medium	Work In Progress		2/13/2013 12:30:26 PM				·
Ontiveros,	Guadalupe	Coaches requesting to re-locate B different location of the field.	aseball Backstop to a				
Johnny Act 96990	una		1/8/2013		147		\$0.00
Medium	Work In Progress		1/8/2013 8:19:24 AN		147		ψ0.00
	Guadalupe	Need Top Soil to fill in holes in pla (Safety Issue)					
Johnny Ac	una		4/40/0040		47		<u> </u>
101070			4/18/2013		47		\$0.00
Medium	Work In Progress		4/18/2013 11:07:23 AM				
Flores, Pet	e	need to check work truck #192. Po up. Truck shakes a little when driven.	ossibly needing turne				
Johnny Act 99479	una		3/8/2013		88		\$0.00
Medium	Work In Progress		3/8/2013 7:43:46 AN		00		\$0.00
Solis, Lore	C C	Need (3) Mastercool Commercial Desert Trail. Mastercool, Sidedra Available	A/c units replaced at				
Johnny Act 99897	una		3/20/2013		76		\$0.00
Medium	Work In Progress		3/20/2013 7:53:14 AN	l			
Solis, Lore	C C	Need a whole replacement of a Ro the NW hall Boy's and Girl's Restri- size of the old Exhaust Fan is: 22" Size Approx. 21" 1/2 All Around. Direct Drive Exhaust Fan?)	ooftop Exhaust fan for oom.(Bottom Base All Around) Duct				
Johnny Ac	una				20		<u> </u>
101823 Modium	Work In Drograss		5/6/2013		29		\$0.00
Medium	Work In Progress	Destable #400. Track survey 1	5/6/2013 12:34:20 PM				
Lara, Ralph		Portable #409: Teacher needs key cabinet.	ys made for filing				
Johnny Ac	una						

Lozoya, Manr <u>Elizabeth Her</u> 101545	/ork In Progress ny nandez /ork In Progress	ail Intermediate 105 Mr. Casares in room 105 is having tro cabinets. one will not lock and the of open. Will be needing (2) locks for gates to portables area.	ter one will not 5/1/2013 5/1/2013 9:11:15 AM		43	
Medium W Lozoya, Manr <u>Elizabeth Her</u> 101545 Medium W	ny nandez /ork In Progress	Mr. Casares in room 105 is having tro cabinets. one will not lock and the of open. Will be needing (2) locks for gates to	4/22/2013 10:04:36 AM puble with file ter one will not 5/1/2013 5/1/2013 9:11:15 AM			\$0.00
Lozoya, Manr <u>Elizabeth Her</u> 101545 Medium W	ny nandez /ork In Progress	Mr. Casares in room 105 is having tro cabinets. one will not lock and the of open. Will be needing (2) locks for gates to	5/1/2013 9:11:15 AM		34	
<u>Elizabeth Her</u> 101545 Medium W	nandez /ork In Progress iy	cabinets. one will not lock and the of open. Will be needing (2) locks for gates to	ter one will not 5/1/2013 5/1/2013 9:11:15 AM		34	
101545 Medium W	/ork In Progress		5/1/2013 9:11:15 AM		34	
Medium W	у		5/1/2013 9:11:15 AM		01	\$0.00
	у					φ0.00
Lozoya, Manr	-		be installed in			
	à	-				
Johnny Acuna			5/4/0040		- 04	<u> </u>
101546			5/1/2013		34	\$0.00
Medium W	ork In Progress		5/1/2013 9:17:36 AM			
Lozoya, Manr	-	Need to fix lock to main door in the b trouble opening door. Core is loose.	us lobby. Having			
Johnny Acuna 99499	3		3/8/2013		88	 \$0.00
Medium W	/ork In Progress		3/8/2013 3:40:17 PM			
Lara, Ralph	Ū.	As per Administrator: Need to re-key portable #417 as the same as portab				
Johnny Acuna	3		0/05/0010			
98806			2/25/2013		99	\$0.00
Medium W	ork In Progress		2/25/2013 9:33:17 AM			
Lozoya, Manr	-	Need to change cylinder core to princ secure Testing Material.	cipal's office to			
Johnny Acuna 102769	a		5/31/2013	7/1/2013	4	 \$0.00
	ork In Progress		5/31/2013 12:28:44 AM			
Acuna, Johnn	-	Yearly - Desert Trail ES A2 (H&C Un PM schedule details.				
Margret Villalo	obos					
102870			6/2/2013	7/3/2013	2	\$0.00
Medium W	ork In Progress		6/2/2013 12:28:50 AM			
Acuna, Johnn	У	Yearly - Desert Trail ES B2 (Boiler)(Y PM schedule details.	/early) - Refer to			
Margret Villalo 102658	obos	Portables	5/29/2013		6	\$0.00
	lork In Drograat				U	ψ0.00
-	ork In Progress		5/29/2013 7:26:40 AM			
Vallejo, Albert		DT will be receiving a new double po be placed on south end,1st row of ex please provide power. thank you				
Michael Munc	Z					

WOID Priority Assigned 1 Requester		Area Area Number Description	Deferred By	Until Request D	Date Target Comp Date ime Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Tr	ail Intermediate	•					
102657				5/29/2	013	6		\$0.00
High	Work In Progress			5/29/2013 7:23:31	AM			
Appelzoller	, Fred	be placed on th	ne south end, 1st r	able. The portable will ow of the existing r and gas. thank you				
Michael Mu 102469	noz			5/22/2	013	13		\$0.00
Medium	Work In Progress			5/22/2013 10:14:57		10		φ0.00
	5							
Holguin, Alf		Portable # 39 L	OM from San Migue	el la				
Richard Ch 102523	avez			5/23/2	.013	12		\$0.00
Medium	Work In Progress			5/23/2013 1:06:55				
Appelzoller	, Fred	Restrooms.	e 3 wash basin (sir Girl's restrooms. S' room NW Hall					
Johnny Acu	ina			6/3/2	012	1		\$0.00
102997 Medium	Work In Progress			6/3/2013 10:14:29		I		ψ0.00
Orozco, Da		ICE MACHINE PAT C. 824.38		ICE. SNP MANAGER				
Maritza Go	nzalez			E 104 /0	04.0			<u> </u>
102816				5/31/2		4		\$0.00
Medium	Work In Progress			5/31/2013 10:46:59	J AM			
Gonzalez, S			new fence that wa delivered. thank yo	is installed for new u				
Michael Mu 92723	INOZ			9/12/2	012	265		\$0.00
Medium	Work In Progress			9/12/2012 8:26:47	7 AM			
Orozco, Da	niel	please replace		loose again. Also, tove's oven. (Pilot 9 Manager Pat C.				
Maritza Go	nzalez			5/23/2	012	11		\$0.00
102536 Modium	Mork In Dreamer					11		φ 0. 00
Medium Briones, Er	Work In Progress	-		5/23/2013 3:11:44 DXES TO DESERT ONAL COACH	4 PM 6/3/2013			

WOID Priority	Building Status	Area Area Number	5/30/2013 Order By Deferred By Reason	Until	-	arget Comp Date ctual Comp Date	Days Aged	Labor Hours	Costs
Assigned	То	Description				Action Taken			
Requester	Name								
Location:	Desert Tr	ail Intermediate							
99218					3/3/2013		93		\$0.00
Medium	Work In Progress			3/3/20	13 12:25:59 AM				
Munoz, Mi	chael	Yearly - Desert to PM schedule	Trail ES Fire Ext. details.	Insp. (Yearly) -	Refer				
Margret Vi 102971	llalobos				6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress			6/2/20	13 12:29:37 AM				
Acuna, Joł	nnny	Monthly - Dese PM schedule de	rt Trail Monthly FE etails.	Inpsection - R	efer to				
Margret Vi	llalobos				0/04/0040	1/21/2212			
100364					3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress			3/31/20	13 12:33:22 AM				
Orozco, Da	aniel	Monthly - Dese PM schedule de	rt Trail Range Hoc etails.	od Cleaning - R	efer to				
Margret Vi	llalobos				5/22/2013		13		\$0.00
102465							13		\$0.00
Medium	Work In Progress			5/22/2	013 9:37:31 AM				
Carrasco,	Danny	Need fuel for w	ork truck.						
Johnny Ac	una								
101177					4/22/2013		43		\$0.00
Medium	Work In Progress			4/22/2	013 3:47:20 PM				
Appelzolle	r, Fred		ove Teacher's des , needs to be repla						
Johnny Ac	una								

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By L Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ac		Days Aged	Labor Hours	Costs
Location:	Desert Vi	ew ES					
102826	Main Building	Office	5/31/2013		4		\$0.00
Medium	Work In Progress		5/31/2013 1:53:43 PM				
Ambriz, Jos		The office and library are hot and working. If you could help us out v					
Israel Orte 101820	ga Main Building	Custodial	5/6/2013		29		\$0.00
Medium	Work In Progress		5/6/2013 10:50:51 AM				
Carbajal, J	immy	Hi Jimmy: That big wet dry vac sc was brought, is not scrubbing any in the cafeteria and it just stopped smelled like burned. If you could c you Jimmy	more. I was using it spinning the pad and				
Israel Orte 100365	ga		3/31/2013	4/21/2013	65		\$0.00
	Work In Prograss			4/21/2013	05		ψ0.00
Medium	Work In Progress		3/31/2013 12:33:23 AM				
Orozco, Da	aniel	Monthly - Desert View ES Range I to PM schedule details.	Hood Cleaning - Refer				
Margret Vil	lalobos		3/3/2013		93		\$0.00
99219					93		φ0.00
Medium	Work In Progress		3/3/2013 12:25:59 AM				
Munoz, Mio	chael	Yearly - Desert View ES Fire Ext. to PM schedule details.	Insp. (Yearly) - Refer				
Margret Vil 102549	lalobos		5/23/2013		12		\$0.00
		0.05			12		φ0.00
Medium	Work In Progress	GISD	5/23/2013 3:29:04 PM				
Briones, Er	nrique	PO# 121304836 PLEASE DELIVER 400 BOOK BO VIEW ELEM. ATTN: INSTRUCTIO					
Lucia Alme	eraz		0/0/004.0	0/0/0040			<u> </u>
102967			6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:35 AM				
Ortiz, Rube	en	Monthly - Desert View ES Monthly to PM schedule details.	FE Inpsection - Refer				
Margret Vil	lalobos		. /				
97861		Cafeteria	1/30/2013		125		\$0.00
High	Work In Progress		1/30/2013 10:42:11 AM				
Orozco, Da	aniel	need to relace small stainless stea used to unclog drain and as per he needs to be cleaned or relaced.					

WOID Priority Assigned 1 Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Vi	ew ES						
101024				4/17/2013		48		\$0.00
Medium	Work In Progress			4/17/2013 11:22:48 AM				
Ontiveros,		have a new one	e installed. ground water founta	in is broken need to ain is broken need to				
Ruben Ortiz 100669	Ζ			4/8/2013		57		\$0.00
Medium	Work In Progress	Outside in the		4/8/2013 8:47:08 AM				
Castillo, Ca	-	Set up Electrici (Gonzalez)	ty for the Spring Ca	rnival by May 21st.				
Guadalupe 100918	Gonzalez	Office		4/15/2013		50		\$0.00
Medium	Work In Progress	Front Entrance		4/15/2013 9:38:13 AM				
Castillo, Ca	Ū.		he Doorbell isn't w					
Guadalupe 102126	Gonzalez			5/13/2013		22		\$0.00
Medium	Work In Progress			5/13/2013 3:55:51 PM				Q 0.00
Ortiz, Rube	Ū	Entrance doors	painted white/mare					
Ruben Ortiz	Z							
99018				2/28/2013	3/31/2013	96		\$0.00
Medium	Work In Progress			2/28/2013 12:28:34 AM				
Ortiz, Rube		Yearly - Desert Refer to PM scl	View ES C-11 Eva nedule details.	p Coolers Yearly -				
Margret Vill 102859	alobos			6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:28:45 AM				
Ortiz, Rube	-	Yearly - Desert schedule detail		r Yearly - Refer to PM				
Margret Vill	alobos							
102687		Portables		5/29/2013		6		\$0.00
Medium	Work In Progress	Portable #6		5/29/2013 1:53:05 PM				
Ortiz, Rube	n	Air conditioner (cooling). (R. La		ise and isn't working				
Guadalupe 102777	Gonzalez			5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress			5/31/2013 12:28:48 AM	.,	·		<i>40.00</i>
Ortiz, Rube	Ū.	Yearly - Desert PM schedule de		SS Yearly - Refer to				
Margret Vill	alobos							

WOID Priority Assigned		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester								
Location:	Desert V	iew ES						
100238				3/31/2013	4/8/2013	65		\$0.00
Medium	Work In Progress			3/31/2013 12:32:34 AM				
Ortiz, Rube	en	Monthly - Dese schedule detail		psection - Refer to PM				
<u>Margret Vi</u> 101209	llalobos			4/23/2013		42		\$0.00
Medium	Work In Progress			4/23/2013 10:21:42 AM				<i>Q</i> 0100
	Guadalupe	In the new see	or field oprinklare	valve 3 is defaulting				
	·	In the new soci		valve 5 is deladiting				
<u>Ruben Ort</u> 101210	12			4/23/2013		42		\$0.00
Medium	Work In Progress			4/23/2013 10:22:39 AM				
Ontiveros.	Guadalupe	On the circle s	outhwest sprinkler i	s not working				
Ruben Ort				4/23/2013		42		\$0.00
101211						42		Ф 0.00
Medium Ontiveros,	Work In Progress Guadalupe			4/23/2013 10:23:28 AM s on the circle on the				
Ruben Ort	iz	Westside midd	le					
102946				6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:26 AM				
Ortiz, Rube	en	Monthly - Dese Refer to PM sc		ight Test: Monthly -				
Margret Vi	llalobos			0/0/0040				<u> </u>
102944				6/2/2013		2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:25 AM				
Ortiz, Rube		Monthly - Dese Refer to PM sc		es Dryer (Monthly) -				
Margret Vi 102945	llalobos			6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:25 AM				
Ortiz, Rube	Ū		ert View ES Exit Sig					
Margret Vi	llalohos	Refer to PM sc	nequie details.					
101397	liaiobos			4/29/2013		36		\$0.00
Medium	Work In Progress			4/29/2013 8:20:57 AM				
Ortiz, Rube	en		blay to Chaparral N ick up Art Display o	liddle School on April on April 29, 2013.				
Guadalupe	e Gonzalez	•	ick up Art Display o	on April 29, 2013.				

WOID Priority Assigned T Requester		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert V	iew ES					
102133			5/13/2013		22		\$0.00
Medium	Work In Progress		5/13/2013 4:00:10 PM				
Ortiz, Rube	n	Fertilize the grass inside the rock	wall				
<u>Ruben Ortiz</u> 102134	2		5/13/2013		22		\$0.00
Medium	Work In Progress		5/13/2013 4:23:23 PM				
Ortiz, Rube	n	Need to replace sprinklers					
Ruben Ortiz 102135	2		5/13/2013		22		\$0.00
Medium	Work In Progress		5/13/2013 4:24:22 PM		22		ψ0.00
Ortiz, Rube	-	Paint fire lane curves red	5/15/2013 4.24.22 1 10				
Ruben Ortiz	2						
102136			5/13/2013		22		\$0.00
Medium	Work In Progress		5/13/2013 4:49:53 PM				
Ortiz, Rube	n	Paint the handicap parking space	S				
Ruben Ortiz 102137	2		5/13/2013		22		\$0.00
Medium	Work In Progress		5/13/2013 4:50:58 PM				
Ortiz, Rube	-	Paint the yellow direction arrows	in parking lot				
Ruben Ortiz		,	1 0				
102138			5/13/2013		22		\$0.00
Medium	Work In Progress		5/13/2013 4:51:43 PM				
Ortiz, Rube	n	Paint the stage					
Ruben Ortiz 102139	2		5/13/2013		22		\$0.00
Medium	Work In Progress		5/13/2013 4:52:32 PM		22		ψ0.00
Ortiz, Rube	-	Paint the bathroom floor	0, 10, 2010 1.02.02 T W				
Ruben Ortiz							
99689		Office	3/14/2013		82		\$0.00
Medium	Work In Progress	Office	3/14/2013 8:31:37 AM				
Ortiz, Rube	n	Replace the lightbulbs in the offic	e. (Gonzalez)				
Guadalupe 102053	Gonzalez		5/12/2013	5/28/2013	23		\$0.00
Medium	Work In Progress		5/12/2013 12:21:27 AM	0,20,2010	_0		<i>45.00</i>
Ortiz, Rube	-	Monthly - Desert View ES Playgro					
Margret Vill	alobos	PM schedule details.					
6/4/2013 9						Derel	51 of 160

Selected Da	ate Range for Request	Dates:7/1/2012 -	6/30/2013 Order By Lo	Cation, Statu	IS				Total Costs
WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	بمللا لمقتمك		00313
Priority	Status	Area Number	Reason	Cre	eated Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requester	r Name								
Location:	Desert Vi	iew ES							
99549					3/11/2013		85		\$0.00
Medium	Work In Progress			3/11/	/2013 1:56:36 PM	1			
Ortiz, Rub	en	Picking up Bike	e Donation from Wal	mart. (R. Or	tiz)				
	e Gonzalez								
Count: 33	Work Orders	A	vg. Age of WO's 3	6		Total for Desert View	w ES	0	\$0.00

Location:GAC1003103/31/2013MediumWork In ProgressAll of the progress3/31/2013 12:33:01 AMHolguin, AlfredoMonthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details.Margret Villalobos5/29/20131026745/29/2013MediumWork In Progress5/29/201311:08:56 AMMoncayo, FernandoGAC-MAIN ENTRANCE.HANDICAP DOOR CLOSURE IS NOT WORKING.Maritza Gonzalez5/30/20131027435/30/2013MediumWork In ProgressMediumWork In ProgressSynta Conzalez5/30/20131027435/30/2013MediumWork In ProgressMoncayo, FernandoREQUESTING FURNITURE TO BE MOVED TO C- WING, FOR THE FOLLOWING. MRS. CASILLAS TO RM 211, SALLY TO RM 207, JOSIE TO RM 208, IOD COMERTING FURNITURE TO RE MOVED TO C- WING, FOR THE FOLLOWING. MRS. CASILLAS TO RM 211, SALLY TO RM 207, JOSIE TO RM 208, IOD COMERTING FURNITURE TO RE DAME.	65	\$0.00
Medium Work In Progress 3/31/2013 12:33:01 AM Holguin, Alfredo Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details. Margret Villalobos 5/29/2013 102674 5/29/2013 Medium Work In Progress Moncayo, Fernando GAC-MAIN ENTRANCE.HANDICAP DOOR CLOSURE IS NOT WORKING. Maritza Gonzalez 5/30/2013 102743 5/30/2013 Medium Work In Progress Maritza Gonzalez 5/30/2013 102743 5/30/2013 Medium Work In Progress Medium Work In Progress Medium Work In Progress Medium Work In Progress Mancayo, Fernando REQUESTING FURNITURE TO BE MOVED TO C- WING, FOR THE FOLLOWING. MRS. CASILLAS TO RM 211, SALLY TO RM 207, JOSIE TO RM 208,		\$0.00
Holguin, Alfredo Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details. Margret Villalobos 5/29/2013 102674 5/29/2013 Medium Work In Progress Moncayo, Fernando GAC-MAIN ENTRANCE.HANDICAP DOOR CLOSURE IS NOT WORKING. Maritza Gonzalez 5/30/2013 102743 5/30/2013 Medium Work In Progress Medium Work In Progress Maritza Gonzalez 5/30/2013 102743 5/30/2013 Medium Work In Progress Moncayo, Fernando REQUESTING FURNITURE TO BE MOVED TO C- WING, FOR THE FOLLOWING. MRS. CASILLAS TO RM 211, SALLY TO RM 207, JOSIE TO RM 208,	6	
Margret Villalobos 5/29/2013 102674 5/29/2013 Medium Work In Progress Moncayo, Fernando GAC-MAIN ENTRANCE.HANDICAP DOOR CLOSURE IS NOT WORKING. Maritza Gonzalez 5/30/2013 102743 5/30/2013 Medium Work In Progress S/30/2013 5/30/2013 Medium Work In Progress S/30/2013 5/30/2013 Medium Work In Progress S/30/2013 5/30/2013 Mencayo, Fernando REQUESTING FURNITURE TO BE MOVED TO C- WING, FOR THE FOLLOWING. MRS. CASILLAS TO RM 211, SALLY TO RM 207, JOSIE TO RM 208,	6	
102674 5/29/2013 Medium Work In Progress 5/29/2013 11:08:56 AM Moncayo, Fernando GAC-MAIN ENTRANCE.HANDICAP DOOR CLOSURE IS NOT WORKING. Maritza Gonzalez 102743 102743 5/30/2013 Medium Work In Progress Moncayo, Fernando REQUESTING FURNITURE TO BE MOVED TO C- WING, FOR THE FOLLOWING. MRS. CASILLAS TO RM 211, SALLY TO RM 207, JOSIE TO RM 208,	6	
Medium Work In Progress 5/29/2013 11:08:56 AM Moncayo, Fernando GAC-MAIN ENTRANCE.HANDICAP DOOR CLOSURE IS NOT WORKING. Maritza Gonzalez 5/30/2013 102743 5/30/2013 Medium Work In Progress Moncayo, Fernando REQUESTING FURNITURE TO BE MOVED TO C- WING, FOR THE FOLLOWING. MRS. CASILLAS TO RM 211, SALLY TO RM 207, JOSIE TO RM 208,	0	\$0.00
Moncayo, Fernando GAC-MAIN ENTRANCE.HANDICAP DOOR CLOSURE IS NOT WORKING. Maritza Gonzalez 5/30/2013 102743 5/30/2013 Medium Work In Progress Moncayo, Fernando REQUESTING FURNITURE TO BE MOVED TO C- WING, FOR THE FOLLOWING. MRS. CASILLAS TO RM 211, SALLY TO RM 207, JOSIE TO RM 208,		φ0.00
IS NOT WORKING. <u>Maritza Gonzalez</u> 102743 Medium Work In Progress Moncayo, Fernando REQUESTING FURNITURE TO BE MOVED TO C- WING, FOR THE FOLLOWING. MRS. CASILLAS TO RM 211, SALLY TO RM 207, JOSIE TO RM 208,		
102743 5/30/2013 Medium Work In Progress 5/30/2013 3:36:37 PM Moncayo, Fernando REQUESTING FURNITURE TO BE MOVED TO C- WING, FOR THE FOLLOWING. MRS. CASILLAS TO RM 211, SALLY TO RM 207, JOSIE TO RM 208,		
Moncayo, Fernando REQUESTING FURNITURE TO BE MOVED TO C- WING, FOR THE FOLLOWING. MRS. CASILLAS TO RM 211, SALLY TO RM 207, JOSIE TO RM 208,	5	\$0.00
Moncayo, Fernando REQUESTING FURNITURE TO BE MOVED TO C- WING, FOR THE FOLLOWING. MRS. CASILLAS TO RM 211, SALLY TO RM 207, JOSIE TO RM 208,		
JORGE/CYNTHIA TO RM 209, ROSA TO RM 210. RM 205 WILL BE USED FOR STORAGE. PLEASE INFORM EMPLOYEES WHEN ROOMS ARE READY FOR MOVE. THANK YOU		
Maritza Gonzalez 102155 5/14/2013	21	\$0.00
	21	φ0.00
Medium Work In Progress 5/14/2013 8:35:56 AM Moncayo, Fernando NEED TO REPLACE HINGE ON STALL DOOR IN DOUBLE RESTROOM ON A -WING.		
Maritza Gonzalez		
102994 6/3/2013	1	\$0.00
Medium Work In Progress 6/3/2013 8:09:48 AM		
Moncayo, Fernando C-WING - FOLLOWING ROOMS NEED TO BE PAINTED RM. 207,208 AND 211.		
Maritza Gonzalez 6/2/2013 6/10/2013	2	\$0.00
Medium Work In Progress 6/2/2013 12:29:12 AM	2	φ0.00
Moncayo, Fernando Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.		
Margret Villalobos		
102913 6/2/2013 6/10/2013	2	 \$0.00
Medium Work In Progress 6/2/2013 12:29:11 AM		
Moncayo, Fernando Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.		
Margret Villalobos		

Priority Assigned Requester		Area Area Number Description	Deferred By Reason	Until Request Date T Created Date/Time A	arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	GAC							
101214				4/23/2013		42		\$0.00
Medium	Work In Progress			4/23/2013 1:29:32 PM				
Moncayo,	Fernando	EXHAUST FAN WORKING PR	N IN DISHWASHEF OPERLY.	R ROOM NOT				
<u>Maritza Go</u> 101910	onzalez			5/8/2013		27		\$0.00
Medium	Work In Progress			5/8/2013 9:25:54 AM		21		φ0.00
Moncayo,	C C		OKEN TILES IN FR	ONT OF MS.				
Maritza Go	onzalez			3/3/2013	3/11/2013	93		\$0.00
99159 Modium				3/3/2013 12:25:32 AM	3/11/2013	93		φ0.00
Medium Moncayo,	Work In Progress Fernando	Monthly - GAC schedule detail	Exit Sign Insp: Mo					
Margret Vi	llalobos	Schedule detail	5.					
92964				9/18/2012		259		\$0.00
Medium	Work In Progress	Lucia Almeraz		9/18/2012 3:45:13 PM				
Moncayo,	Fernando	ATTN: JUAN A PLEASE INST	MBRIZ ALL A REGISTER I		2/26 -Routed to Ferr	nando		
Lucia Alme 101740	eraz			5/5/2013	5/13/2013	30		\$0.00
Medium	Work In Progress			5/5/2013 12:24:28 AM	0, 10, 2010			<i>QO</i> . <i>OO</i>
Moncayo,	C C	Monthly - GAC schedule detail		Monthly - Refer to PM				
Margret Vi	llalobos							
99161				3/3/2013	3/11/2013	93		\$0.00
Medium	Work In Progress			3/3/2013 12:25:33 AM				
Moncayo,		Monthly - GAC schedule detail		Monthly - Refer to PM				
Margret Vi 102054	llalobos			5/12/2013	5/28/2013	23		\$0.00
Medium	Work In Progress			5/12/2013 12:21:27 AM		-		
Moncayo,	-	Monthly - GAC details.	Playground Insp -	Refer to PM schedule				
Margret Vi	llalobos							
101064				4/18/2013		47		\$0.00
Medium	Work In Progress	Car#161		4/18/2013 8:52:02 AM				
Flores, Pet	te	Please check c	ar#161 check engi	ne light on				
Lucia Alme	eraz							

WOID Priority Assigned 1 Requester		Area Deferred By Until Request Date Area Number Reason Created Date/Time A Description	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
_ocation:	GAC					
99743		3/15/2013		81		\$0.00
Medium	Work In Progress	3/15/2013 8:06:07 AM				
Munoz, Mic	chael	need morgan for plumber and electrican for storage.				
Michael Mu	inoz					
100186		3/31/2013	4/16/2013	65		\$0.00
Medium	Work In Progress	3/31/2013 12:32:12 AM				
Ambriz, Jua		Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.				
<u>Margret Vil</u> 102751	lalobos	5/30/2013		5		\$0.00
Medium	Work In Progress	5/30/2013 3:51:01 PM				
Lara, Ralph	Ũ	C-WING CYLINDER/CORE TO ROOM 109 NEEDS TO BE SWITCHED TO ROOM 205.				
Maritza Go	nzalez	3/3/2013		93		¢0.00
99188				93		\$0.00
Medium	Work In Progress	3/3/2013 12:25:45 AM				
Moncayo, F		Yearly - GAC A-10 Heat Pump Cooling Only Yearly - Refer to PM schedule details.				
Margret Vil 102770	lalobos	5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress	5/31/2013 12:28:44 AM				
Moncayo, F	Fernando	Yearly - GAC A-2 Package Unit Gas Yearly - Refer to PM schedule details.				
Margret Vil	lalobos					
102739		5/30/2013		5		\$0.00
Medium	Work In Progress	5/30/2013 3:26:52 PM				
Ambriz, Jos	se	PLEAS CHECK WALL UNITS IN THE CRRUA OFFICES(FRONT OFFICES). STATING THAT IT IS TOO NOISY AND NOT COOLING ENOUGH.				
Maritza Go	nzalez	E/20/2012		6		¢0.00
102681 Medium	Work In Progress	5/29/2013 5/29/2013 1:17:20 PM		6		\$0.00
	-					
Ambriz, Jos	Se	WALL UNITS TO ROOMS 205, 207, 208, 209, 210 and 211 IN C WING NEED TO BE CHECKED OUT TO MAKE SURE THEY ARE WORKING PROPERLY.				
Maritza Go	nzalez	5/29/2013		6		\$0.00
102689 Madium				U		φ0.00
Medium	Work In Progress	5/29/2013 2:23:01 PM				
Ambriz, Jos	se	please check hvac units to the following rooms for proper operation. 205,207,208,209,210,211.thankyou				

6/4/2013 9:16:06 AM

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Location, Status Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description Description	arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	GAC					
96987		1/8/2013		147		\$0.00
Medium	Work In Progress	1/8/2013 8:12:56 AM				
Ambriz, Jo	se	Server Room - Unit is down				
Michael M	unoz	5/10/2010		05		\$ 0.00
102014		5/10/2013		25		\$0.00
Medium	Work In Progress	5/10/2013 11:47:14 AM				
Ambriz, Jo	se	Sally Sepulveda's office the unit is making alot of noise.				
<u>Richard Cl</u> 102141	havez	5/14/2013		21		\$0.00
Medium	Work In Progress	5/14/2013 12:22:31 AM		21		ψ0.00
Ambriz, Jo	-	Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details.				
Margret Vi	llalobos					
95653		11/19/2012		197		\$0.00
High	Work In Progress	11/19/2012 7:30:10 AM				
Ambriz, Jo	se	need to rewire liebert cooling system in tech room to have only 2 compressors functioing, install4 contactors, new swithces, intelligent board, programming etc. this system is to overiszed for room and is causing problems as desighned.				
<u>Michael M</u> 101194	unoz	4/22/2013		43		\$0.00
Medium	Work In Brogroop	4/22/2013 4/22/2013 4:22:11 PM		40		ψ0.00
Ambriz, Jo	Work In Progress	NEED TO CHECK THREE A/C UNITS IN TECHNOLOGY OFFICE. NOT WORKING CORRECTLY				
Cora Ram	irez	0/44/0040		0.0		<u> </u>
99683		3/14/2013		82		\$0.00
Medium Ambriz, Jo	Work In Progress	3/14/2013 12:19:34 AM Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details.				
Margret Vi	llalobos					
100908		4/14/2013		51		\$0.00
Medium	Work In Progress	4/14/2013 12:19:47 AM				
Ambriz, Jo	se	Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details.				
Margret Vi	llalobos					

WOID Priority Assigned	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	GAC						
102569		Electrical Room	5/24/2013		11		\$0.00
Medium	Work In Progress		5/24/2013 8:06:02 AN	1			
Castillo, Ca	arlos	Walk-thru electrical rooms at Gac a VISUALL INSPECTION OF ELECT AND COMPONENTS.					
Carlos Cas 101906	stillo	Electrical Room	5/8/2013		27		\$0.00
					21		φ0.00
Medium	Work In Progress		5/8/2013 8:39:12 AN	1			
Castillo, Ca		Need to order fuses for main electri stock .	cal room to have in				
Carlos Cas 101616	stillo	Electrical Room	5/2/2013		33		\$0.00
Medium	Work In Progress		5/2/2013 3:44:44 PM		00		ψ0.00
	Work In Progress			1			
Castillo, Ca		Need to order shelving and storage will be placed at the Gac for mainta					
Carlos Cas 102145	Stillo	Parking Lot	5/14/2013		21		\$0.00
Medium	Work In Progress	-	5/14/2013 8:01:34 AM	1			
Castillo, Ca	C C	Irrigation service needs to be rebuil hanging down from conduit.	d.Panel box is				
Carlos Cas	stillo		E /04 /004 0		4		<u> </u>
102798			5/31/2013		4		\$0.00
Medium	Work In Progress		5/31/2013 8:07:49 AN	1			
Castillo, Ca		As per head custodiun, A. Rodriguez cord to floor buffer.	z,need to replace				
Carlos Cas 101322	stillo		4/25/2013		40		\$0.00
	Work In Progress				40		ψ0.00
Medium	0		4/25/2013 3:16:22 PN	1			
Castillo, Ca		ARTURO REQUESTING LIGHT BU ENTRANCE.	JLBS FOR MAIN				
Maritza Go 101258	onzalez		4/24/2013		41		\$0.00
Medium	Work In Progress		4/24/2013 8:21:20 AM				Q 0.00
Castillo, Ca	C C	As per Calixto, if possible extend er his office so he can keep operating outage.	nergency power to				
Calixto Arz	aga		- / /-				A
92932			9/18/2012		259		\$0.00
Medium	Work In Progress		9/18/2012 12:44:19 PN	1			
Ontiveros,	Joe	MAIN WATER LINE LEAKING IN C	-WING.	Route to Joe asp rea	assignme	nt 4/2/13	
Maritza Go	nzalez						

6/4/2013 9:16:06 AM

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Loca Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	GAC						
102488			5/22/2013		13		\$0.00
Medium	Work In Progress		5/22/2013 3:17:56 PM				
Moncayo, I	Fernando	PLEASE CHECK AND SERVICE A/C AREA. UNIT IN ANA OFFICE DOESN TIMES BLOWS OUT ROOM TEMP C THE CASHIER AREA DOES NOT GC AND DOESNT NOT VENT ENOUGH	NT COOL, OFTEN DR HOT AIR. IN D ABOVE LOW				
Maritza Go 94698	onzalez		10/29/2012		218		\$0.00
Medium	Work In Progress		10/29/2012 9:26:05 AM		-		
Rodriguez,	C C	TOILET IN RR IN FRONT OF RECEF WILL NOT FLUSH.	PTIONIST AREA				
Maritza Go 101811	onzalez	Office	5/6/2013		29		\$0.00
Medium	Work In Progress	Onice	5/6/2013 8:03:26 AM		29		φ0.00
	0						
Briones, Er		Please pick up broken equipment fror	n GAC at Bil. Dept.				
Larry Marti 102481	INEZ		5/22/2013		13		\$0.00
Medium	Work In Progress		5/22/2013 1:36:51 PM				
,		BI-LINGUAL ED DEPT-2 DESK AND SHELF OF NO USE NEEDS TO BE F DISPOSED. SEE CUSTIODIAN.					
Maritza Go 102741	onzalez		5/30/2013		5		\$0.00
Medium	Work In Progress		5/30/2013 3:29:35 PM		U		\$0.00
Gonzales,	C C	BROKEN FURNITURE (2 DESK AND NEED TO BE PICKED UP AND DISP BILINGUAL DEPT.	BOOKSHELVES)				
Maritza Go	onzalez		0/0/0040		00		#0.00
99236			3/3/2013		93		\$0.00
Medium	Work In Progress		3/3/2013 12:26:07 AM				
Munoz, Mic		Yearly - GAC Fire Ext. Insp. (Yearly) - schedule details.	- Refer to PM				
Margret Vil 102974	11010000		6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:38 AM				
Moncayo, I	Fernando	Monthly - GAC Monthly FE Inpsection schedule details.	n - Refer to PM				
Margret Vil	llalahas						

Selected Da	ate Range for Request Building	Dates:7/1/2012 - Area	6/30/2013 Order By Lo Deferred By	Until Request Date	e Target Comp Date	Days	Labor	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description			Action Taken			
Requester	Name							
Location:	GAC							
99157				3/3/2013	3/9/2013	93		\$0.00
Medium	Work In Progress			3/3/2013 12:25:32 AM	Л			
Moncayo,	Fernando	Monthly - GAC schedule detail	Monthly FE Inpsecti ls.	on - Refer to PM				
Margret Vi	llalobos							
102083		Custodial		5/13/2013	3	22		\$0.00
Medium	Work In Progress			5/13/2013 10:25:37 AM	Л			
Carbajal, J	limmy	• •	adora Num 0214 se l a revisar gracias	e cayo la llantita por				
Laura San	doval							
100378				3/31/2013	3 4/21/2013	65		\$0.00
Medium	Work In Progress			3/31/2013 12:33:28 AM	Л			
Orozco, Da	aniel	Monthly - GAC schedule detail	Range Hood Cleani ls.	ng - Refer to PM				
Margret Vi								
Count: 48	Work Orders	A	vg. Age of WO's 5	3	Total for	GAC	0	\$0.00

WOID	ate Range for Request Building	Area	Deferred By	Until R	equest Date T	arget Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created	Date/Time A	ctual Comp Date	Aged	Hours	
Assigned	То	Description			Action Taken				
Requester	[·] Name								
Location:	GAC - Pro	ə-K							
102153					5/14/2013		21		\$0.00
Medium	Work In Progress			5/14/201	3 8:20:57 AM				
Ambriz, Jo	se	please install w in MR.Yturalde	viring and control for	or remote a/c cont	rol,				
Fernando	Moncayo								
98516					2/14/2013		110		\$0.00
Medium	Work In Progress			2/14/2013	11:34:39 AM				
Ontiveros,	Guadalupe		versation, please m ocation and types o you		are				
Michael M	unoz								
102998					6/3/2013		1		\$0.00
Medium	Work In Progress			6/3/2013	10:35:12 AM				
Moncayo,	Fernando	big boxes in the	tle lofts in room 103 e hallway - please p box and all pieces t u!	place all pieces to	loft				
Maritza Go									
Count: 3 V	Vork Orders	A	vg. Age of WO's	44		Total for GAC - F	Pre-K	0	\$0.00

WOID Priority Assigned Requeste	Building Status To	•	e Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		ES				
102907		6/2/2013	3	2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:07 AM	Л			
Medina, E	ric	Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret V 102911	illalobos	6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Prograss	6/2/2013 12:29:10 A		۷		ψ0.00
	Work In Progress		VI			
Medina, E		Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.				
Margret V 102688	IIIAIODOS	Office 5/29/2013	3	6		\$0.00
Medium	Work In Progress	5/29/2013 2:11:39 Pt	N			
Miranda, I	Danny	need for a TV to be installed in front office would greatly appreciate your assistance in this matter thank you	5/29/13 - asp mike r Miranda	outed to D	anny	
Loraine G	andara	0/0/004	0/40/0040			* ••••
102910		6/2/2013		2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:09 AN	И			
Medina, E		Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.				
Margret V 102788	illalobos	5/31/2013	3	4		\$0.00
Medium	Work In Progress	5/31/2013 12:28:52 AM	И			
Apodaca,	Mario	Monthly - Gadsden ES - Monthly Meter Readings - Refer to PM schedule details.				
Margret V	illalobos		4/00/0040	50		<u> </u>
100643		4/7/2013		58		\$0.00
Medium	Work In Progress	4/7/2013 12:19:00 AM	И			
Pinon, Jos		Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PM schedule details.				
Margret V 97402	illalobos	1/16/2013	3	139		\$0.00
Medium	Work In Progress	Morgan Building 1/16/2013 1:57:34 PI				
Lozoya, N	-	Asp Mike, need to key new Morgan Building the same as school site is keyed for admin to have access to it.				
Michael N	lunoz	-				
95947		11/29/2012		187		\$0.00
Medium	Work In Progress	11/29/2012 2:23:14 PM	Λ			
Lozoya, N	lanny	Need 2 gate keys. Need to check the keys out to either Hector Torres or Hector Gutierrez For more information contact Ralph Gallegos at 882-6921. Thank You.				
Dominique	e Esparza					
6/4/2013	9:16:06 AM				Page 6	61 of 160

6/4/2013 9:16:06 AM

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Li Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ad		Days Aged	Labor Hours	Costs
Location:	Gadsden	ES					
101600		Custodial	5/2/2013		33		\$0.00
Medium	Work In Progress		5/2/2013 11:54:37 AM				
Lozoya, Ma	anny	BOY RESTROOM DOOR IS BROK	KEN BY KITCHEN				
Jose Pinio	n						
100715		Office	4/9/2013		56		\$0.00
Medium	Work In Progress	Front office main	4/9/2013 8:50:27 AM				
Lozoya, Ma	·	need immdiate assistance with doo principal doors to entrance do not o key cyclinder turns instead of locking	close properly the				
Loraine Ga 101601	andara	Office	5/2/2013		33		\$0.00
Medium	Work In Progress	front doors	5/2/2013 12:48:12 PM				
Lozoya, Ma	anny	need immidiate assistance with fro to be getting stuck and not locking appreciate your assitance in this m	properly greatly				
Loraine Ga 99907	andara	Pump House	3/20/2013		76		\$0.00
Medium	Work In Progress		3/20/2013 9:30:55 AM				Q
Lozoya, Ma	C C	At Gadsden Elem, a core change i house. Also 3 locks are needed for Please contact Jose Pinon for loca Should you have any questions ple Rafael "Ralph" Gallegos at (575) 88	s needed in the pump 3 designated areas. tion of area. ease contact Mr.				
Dominique	Esparza		5/5/2013	5/26/2013	30		\$0.00
101783				5/20/2013	30		φ0.00
Medium	Work In Progress		5/5/2013 12:24:45 AM				
Orozco, Da	aniel	Monthly - Gadsden ES - Range Ho to PM schedule details.	ood Cleaning - Refer				
Margret Vil	llalobos						
101104		Athletic Field	4/19/2013		46		\$0.00
High	Work In Progress		4/19/2013 8:20:19 AM				
Lozoya, Ma	anny	need door to open with 7 pin.					
Guadalupe	Ontiveros		0/0/0010	0/40/0040			<u> </u>
102976			6/2/2013	6/13/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:39 AM				
Medina, Er	ic	Monthly - Gadsden ES - FE Inspector to PM schedule details.	tion - Monthly - Refer				

WOID Priority	Building Status	Area I Area Number I	Deferred By Reason	Until Request Date T Created Date/Time A	-	Days Aged	Labor Hours	Costs
Assigned		Description			Action Taken			
Requester	Name							
Location:	Gadsden	ES						
101862		Athletic Field		5/7/2013		28		\$0.00
Medium	Work In Progress			5/7/2013 9:08:08 AM				
Gonzalez,	Salvador	need 2 sturdy po	les for volleyball r	nets. thank you				
Michael M	unoz							
101667				5/3/2013		32		\$0.00
High	Work In Progress			5/3/2013 4:14:15 PM				
Gonzalez,	Salvador			g with do not enter mike for details. thank				
Michael M	unoz			0/0/0040				^
99214				3/3/2013		93		\$0.00
Medium	Work In Progress			3/3/2013 12:25:57 AM				
Munoz, Mi	chael	Yearly - Gadsde PM schedule det		p. (Yearly) - Refer to				
Margret Vi	llalobos			5/30/2013		5		\$0.00
102720						5		φ0.00
High	Work In Progress			5/30/2013 8:46:16 AM				
Gonzalez,	Salvador	need to install 3 rooms to preven	window guards or break -ins.	n end counseling				
Michael M 100922	unoz			4/15/2013		50		\$0.00
						50		ψ0.00
Medium	Work In Progress			4/15/2013 10:31:02 AM				
Orozco, Da	aniel	SERVING LINE CUCA P. 882.34		G SNP MANAGER				
Maritza Go	onzalez			1/1 = /0.0 1.0				
100916		Classroom		4/15/2013		50		\$0.00
Medium	Work In Progress	101		4/15/2013 9:00:50 AM				
Estrada, Jo	esus		hroom wall is falli his matter thank y					
Loraine Ga	andara							

WOID Priority Assigned [•] Requester		Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time Ac Description		Days Aged	Labor Hours	
Location:	Gadsden	HS				
99439		3/7/2013		89		\$0.00
Medium	Work In Progress	3/7/2013 8:34:45 AM				
Estrada, Je	esus	Requested by Mr. Martinez for Cafeteria-Need to install missing transcition on floor VCT to ceramic tiles, all around on the floor.				
Velia Alarc 99480	on	3/8/2013		88		\$0.00
Medium	Work In Progress	3/8/2013 7:58:12 AM		00		φ0.00
	C C					
Estrada, Je	esus	NEED TO MEASURE AND REPLACE CERAMIC TILE TO VCT IN CAFETERIA				
Jesus Estr	ada	3/20/2013		-272		\$0.00
99914			0/04/0040	-212		φ 0. 00
Medium	Work In Progress	3/20/2013 9:44:49 AM	6/21/2012			
Estrada, Je		NEED 3 GYM FLOORS TO BE RE-FINISHED (BOYS - 100' X 74'; GIRLS - 91' X 50'; VARSITY - 129' X 92')				
Jesus Estr 100366	ada	3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress	3/31/2013 12:33:23 AM				
Orozco, Da	aniel	Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.				
Margret Vi	llalobos Business	4/3/2013		62		\$0.00
100493				02		φ 0. 00
Medium ,	Work In Progress	4/3/2013 1:36:51 PM please assist with the removal and installations of the sewing tables and machines in room 610, beginning 4- 09-13. thank you				
Michael M		·				
95625	Old English Bldg	11/16/2012		200		\$0.00
High	Work In Progress	11/16/2012 10:46:22				
Lozoya, M	anny	Need to replace door in Old English #141, door is hanging it is being hold by the door closer, secured door from falling down, but room needs to be secured				
Guillermo 101065	Hernandez North Building	Classroom 4/18/2013		47		\$0.00
Medium	Work In Progress	4/18/2013 8:53:38 AM				·
Munoz, Jo	-	North Building – this is the current Home Ec room and the classrooms in that hallway as well as the corridor and the west end of the main corridor. In the North Building, GISD personnel will need to empty the Home Ec room, two classrooms, storage room and the copy machine room on May 24 and 28, 2013. If you have any questions please call Ralph Gallegos at 575-882-6921.				
		Thanks.				

WOID Priority Assigned ⁻ Requester		Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ac	rget Comp Date tual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	HS					
99585	Grounds Shop	Athletic Field	3/12/2013		84		\$0.00
Medium	Work In Progress	Lupe Ontiveros	3/12/2013 10:20:32 AM				
Ontiveros,	Guadalupe	Please pickup the windscreens for the	e following:				
		Softball - (install windscreens) GHS S	Softball				
		Baseball - (install windscreens) GHS	Baseball				
		Installation will be on a school to scho	ool basis.				
Terry Alvar 93642	rado		9/30/2012		247		\$0.00
Medium	Work In Progress		9/30/2012 12:31:33 AM				
Sanchez, I	Raul	Monthly - Gadsden HS - Lift Station In to PM schedule details.	nspection - Refer				
Margret Vi 94821	llalobos		10/31/2012		216		\$0.00
Medium	Work In Progress		10/31/2012 12:26:40		210		ψ0.00
Sanchez, I	C C	Monthly - Gadsden HS-WWTP Chem (Monthly) - Refer to PM schedule deta	nical Order				
Margret Vi	llalobos		0/2/2012		275		¢0.00
92301 Medium			9/2/2012		275		\$0.00
Sanchez, I	Work In Progress Raul	Monthly - Gadsden HS - Lift Station In to PM schedule details.	9/2/2012 12:21:58 AM nspection - Refer				
Margret Vil 100328	llalobos		3/31/2013		65		\$0.00
Medium	Work In Progress				05		φ0.00
Sanchez, I	-	Monthly - Gadsden HS - Lift Station I to PM schedule details.	3/31/2013 12:33:08 AM nspection - Refer				
Margret Vi	llalobos						
97916			1/31/2013		124		\$0.00
Medium	Work In Progress		1/31/2013 12:25:34 AM				
Sanchez, I		Monthly - Gadsden HS-WWTP Chem (Monthly) - Refer to PM schedule deta					
Margret Vil 98126	llalobos		2/3/2013		121		\$0.00
Medium	Work In Progress		2/3/2013 12:22:55 AM				
Sanchez, I	Raul	Monthly - Gadsden HS - Lift Station In to PM schedule details.	nspection - Refer				

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Location, Status Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time A Description Description	•	Days Labor Aged Hours	Costs
Location:	Gadsden	HS			
97883		1/30/2013		125	\$0.00
Medium	Work In Progress	1/30/2013 3:07:52 PM			
Sanchez, I	Raul	Asp Alfredo, install 2 pump and install valves to isolate pumps.			
<u>Alfredo Ho</u> 98931	lguin	2/27/2013		97	\$0.00
Medium	Work In Progress	2/27/2013 8:38:09 AM		01	φ0.00
Sanchez, I	Raul	Need to have Anthony Pump & Drilling check irrigation pump #1. Pumping gpm has gone done quite alot, casing screen may be clogged			
Raul Sanc 95150	hez	11/4/2012		212	\$0.00
Medium	Work In Progress	11/4/2012 12:20:01 AM			·
Sanchez, I	Ŭ	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.			
Margret Vi	llalobos	40/0/0040		404	<u> </u>
96148 Madium		12/2/2012		184	\$0.00
Medium Sanchez, I	Work In Progress Raul	12/2/2012 12:23:27 AM Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.			
Margret Vi	llalobos				
96877		1/6/2013		149	\$0.00
Medium	Work In Progress	1/6/2013 12:24:32 AM			
Sanchez, I		Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.			
Margret Vil 99267	liaiodos	3/3/2013		93	\$0.00
Medium	Work In Progress	3/3/2013 12:26:21 AM			
Sanchez, I	Raul	Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.			
Margret Vi	llalobos	0/4.4/004.0		00	<u> </u>
99698 Medium	Work In Progress	3/14/2013 3/14/2013 9:23:00 AM		82	\$0.00
	0				
Sanchez, I	kaul	03/14/13 Need to order wastewater chemicals to control the foam in wwtp & the grease in the campus lift stations Thanks, Raul			

WOID Priority Assigned ⁻ Requester	Building Status Fo	Dates:7/1/2012 - 6/30/2013 Order By Location, Status Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time Ac Description Description	•	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS				
93175		9/24/2012		253		\$0.00
Medium	Work In Progress	9/24/2012 2:18:30 PM				
Gonzalez,	Salvador	Requested by Coach Letz for Tennis Court-Please repair two of the benches on the Tennis Courts.				
Velia Alarc 101281	on	Choral 4/24/2013	6/7/2013	41		\$0.00
Medium	Work In Progress	4/24/2013 3:03:53 PM				
Gonzalez,	0	Need to re plumb altitude sensor into storage tank, Schedule this work for the summer and coordinate this work with Raul Sanchez and Mario Apodaca				
101148		4/22/2013		43		\$0.00
Medium	Work In Progress	4/22/2013 9:28:40 AM				
Lara, Ralpł	ı	Requested by Mrs. Munoz Rm. 514 in New Trades Building-Requesting a lock guard on door.				
Velia Alarc 100481	on	4/3/2013		62		\$0.00
Medium	Work In Progress	4/3/2013 10:26:21 AM		02		ψ0.00
Lara, Ralph	Ū	Requested by Mr. Mora Rm. 403 Boy's Gym-Athletic Training Room-Panic bar on Athletic Training Room door has a stripped allen key hole. Needs to be repaired in order to lock this door.				
Velia Alarc 100483	on	4/3/2013		62		\$0.00
Medium	Work In Progress	4/3/2013 10:40:39 AM		02		ψ0.00
Lara, Ralph	•	Requested by Mr. Pokluda for Girl's Gym-Repair/replace door closure on double doors that lead from Girl's Gym to hallway in Old English Building.				
Velia Alarc	on					
102002		5/10/2013		25		\$0.00
Medium	Work In Progress	5/10/2013 9:34:44 AM				
Lara, Ralph	1	Requested by Mr. Grubaugh Rm. 728 New Library-The battery on the emergency door alarm may be dead. The alarm is not functioning.				
Velia Alarc	on	5/10/2013		25		\$0.00
102003 Medium	Work In Progress	5/10/2013 5/10/2013 5/10/2013		20		φ0.00
Lara, Ralph	-	Requested by Ms. Howard Rm. 215 North Building-The screws are stripped on door stop.				

WOID Priority Assigned Requester		Area Deferred Area Number Reason Description	,	-	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	HS						
102201				5/15/2013		20		\$0.00
Medium	Work In Progress		5/15/20	13 7:50:57 AM				
Gonzalez,	Salvador	Need to weld reinforceme band room.	ent for base of new H/C u	init on				
Guillermo I 100723	Hernandez			4/9/2013		56		\$0.00
Medium	Work In Progress		4/9/201	3 10:55:38 AM		00		ψ0.00
Briones, Er	nrique	Requested by Mr. Pokluc items need to be remove placed in storage at the D need to be removed befor construction at Gadsden & Furniture Transfer/Turr sent to Mr. Manuel Leyva SEE MR. POKLUDA FOR	d from the Old Library an District's Warehouse. Iten ore the next phase of High School. The "Equip In Form" has already be a thru Inter-Department m	d ns ment een aail.				
Velia Alarc 99233	on			3/3/2013		93		\$0.00
Medium	Work In Progress		3/3/201	3 12:26:06 AM				<i>Q</i> 0100
Munoz, Mi	C C	Yearly - Gadsden HS Fire PM schedule details.						
Margret Vil	llalobos			0 10 10 0 1 0	0/0/0010			* ••••
102970				6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress			3 12:29:37 AM				
Herrera, Jo		Monthly - Gadsden HS N PM schedule details.	Ionthly FE Inspection - Re	efer to				
Margret Vil 101921	llalobos Cafeteria (1998)	Kitchen		5/8/2013		27		\$0.00
Medium	Work In Progress		5/8/20	13 1:42:55 PM				
Orozco, Da	aniel	FLOORING TO WALK IN LIFTING. SNP MANAGE						
Maritza Go	onzalez Varsity Gym			1/25/2013		130		\$0.00
97699 Modium			1/25/201			130		Ф 0.00
Medium Sotelo, Eni	Work In Progress rique	Please check score board turning off and on. Previo a location	ds in the V. Gym, scorebo		Route to Enrique as	p reassi	gnment 4/2	2/13
	Hernandez	Athlatic Field		1/20/2012		107		\$0.00
97772	Morte In Dragge	Athletic Field	4/00/00	1/28/2013		127		Φ0.00
Medium	Work In Progress			13 1:49:34 PM				
	Guadalupe	need blade spade for three	an paint hitch $ID 1/1/0$					

WOID Priority Assigned	Building Status To	•		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
101026		4	1/17/2013		48		\$0.00
Medium	Work In Progress	4/17/2013 1:	48:26 PM				
Lara, Ralpl	h	Requested by Coach J. Vasquez Rm. 400 Boy's Gym- Coach's Office door does not lock. SEE COACH VASQUEZ FOR MORE INFORMATION & LOCATION					
Velia Alarc 102734	on	5	5/30/2013		5		\$0.00
Medium	Work In Progress	5/30/2013 3:			Ũ		ψ0.00
Lara, Ralpl	0	Requested by Coach Walker for Portable #2-Please provide keyed locks for two storage closets in portable #2.					
Velia Alarc 95309	on	1	1/8/2012		208		\$0.00
Medium	Work In Progress	' 11/8/2012 7:			200		ψ0.00
Ambriz, Jo	C C	Need to replace T-stat and check leaks on gaskets on boiler for heating system on the Old English					
Guillermo I	Hernandez		E 10 10 0 4 0				\$ 0.00
101965			5/9/2013		26		\$0.00
Medium	Work In Progress	5/9/2013 11:	36:33 AM				
Hernandez	z, Guillermo	Requested by Administration Team-Paint panther in front of school black. This can be done over the summer.					
Velia Alarc 102988	on		6/3/2013		1		\$0.00
Medium	Work In Progress	6/3/2013 6:			I		φ0.00
	, Guillermo	Paint (touch up) scratches on walls in Administration	.39.30 AIVI				
Tiernandez	, Guilenno	building.					
Guillermo I 95667	Hernandez	11	/19/2012		197		\$0.00
High	Work In Progress	11/19/2012			197		φ0.00
-	, Guillermo	please paint all ADA logos, ramps and curbs etc to me code requirements.thankyou		4/23/13 - Work is sti	ll in progr	ess	
Joe Munoz	<u>-</u>						
99793		3	3/17/2013		79		\$0.00
Medium	Work In Progress	3/17/2013 12:	19:58 AM				
Villalobos,	Margret	Monthly - Gadsden HS - PC Automated Quarterly - Refer to PM schedule details.	I	Emailed to Melanie	on 3/18/1	3	
Margret Vil	llalobos						

WOID Priority Assigned ⁻ Requester		Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	HS				
101957		5/9/2013		26		\$0.00
Medium	Work In Progress	5/9/2013 10:19:21 AM				
Lara, Ralpl	ı	Requested by Mr. Myers Rm. 504 New Voc. Building-A copy of of the counter cabinet key needs to be made. The key number is C413A. Mrs. Munoz has the key that needs to be copied.				
<u>Velia Alarc</u> 102093	on	5/13/2013		22		\$0.00
Medium	Work In Progress	5/13/2013 2:06:00 PM				φ0.00
Lara, Ralpl	-	Please check panic bar on the exterior door of North building H wing.				
<u>Guillermo I</u> 102427	Hernandez	5/21/2013		14		\$0.00
Medium	Work In Progress	5/21/2013 7:50:18 AM		17		ψ0.00
Lara, Ralpl	-	Teacher's key getting stock on the door and some times is hard to unlock door. Academic #404 and #408.				
<u>Guillermo I</u>	Hernandez	0/0/0040				
103008		6/3/2013		1		\$0.00
Medium	Work In Progress	6/3/2013 12:43:06 PM				
Lara, Ralpl	1	Please reinstall regular cores on doors for the Gyms after contractor is done.				
Guillermo I	Hernandez	6/3/2013		1		\$0.00
102990 Medium	Work In Drogroop	6/3/2013 6:46:30 AM		I		φ0.00
Ambriz, Jo	Work In Progress se	Please check the BCU on the main building, receiving alarm on loosing comm for units.				
Guillermo I	Hernandez	°				
102767		5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress	5/31/2013 12:28:43 AM				
	, Guillermo	Yearly - Gadsden HS A2 (H/C Unit)(Yearly) - Refer to PM schedule details.				
Margret Vil 102867	lalobos	6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress	6/2/2013 12:28:49 AM				
Hernandez	, Guillermo	Yearly - Gadsden HS B2 (Boiler)(Yearly) - Refer to PM schedule details.				
Margret Vil	lalobos	3/10/2013		86		\$0.00
99516 Modium	Mark In Dreaman			00		ψ0.00
Medium Hernandez	Work In Progress , Guillermo	3/10/2013 12:19:08 AM Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.				

Priority Assigned ⁻ Requester		Area Deferred By Area Number Reason Description	ation, Status Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
99970			3/21/2013		75		\$0.00
Medium	Work In Progress		3/21/2013 8:20:59 AN	1			
Sotelo, En	rique	Need to replace broken light fixtures marquee on front of the school.	(reflectors) on the	Route to Enrique as	o reassig	Inment 4/2	2/13
Guillermo 99971	Hernandez		3/21/2013		75		\$0.00
Medium	Work In Progress		3/21/2013 8:24:25 AN		-		
Sotelo, En	Ū	Need to install 2 missing or broken lig the girls locker room at the Boys gym repaired.	ght fixtures (T8's) in	Route to Enrique as	o reassig	nment 4/2	/13
Guillermo 99301	Hernandez		3/4/2013		92		\$0.00
Medium	Work In Progress		3/4/2013 12:08:06 PM		02		\$0.00
Sotelo, En	C C	Need assistance to replace ballast in North building.		Route to Enrique as	o reassig	Inment 4/2	2/13
	Hernandez		10/10/0010		474		
96524			12/12/2012		174		\$0.00
Medium	Work In Progress	D i i i i i i i i	12/12/2012 7:57:38 AM				
SOTOLO LO							
Sotelo, En	nque	Please check score board, having pro lights	oblems with the	Route to Enrique as	o reassig	inment 4/2	/13
Guillermo	Hernandez			Route to Enrique as		inment 4/2	
Guillermo 94185	Hernandez		10/15/2012		232	Inment 4/2	\$0.00
Guillermo	Hernandez Work In Progress		10/15/2012 10/15/2012 3:54:24 PM			Inment 4/2	
Guillermo 94185 Medium Ambriz, Jo Guillermo	Hernandez Work In Progress	lights Need to replace 6 A/C commercial ur	10/15/2012 10/15/2012 3:54:24 PM hits for the		232	nment 4/2	\$0.00
<u>Guillermo </u> 94185 Medium Ambriz, Jo <u>Guillermo </u> 93992	Hernandez Work In Progress se Hernandez	lights Need to replace 6 A/C commercial ur	10/15/2012 10/15/2012 3:54:24 PM hits for the 10/10/2012	 		nment 4/2	
Guillermo 94185 Medium Ambriz, Jo Guillermo 93992 Medium	Hernandez Work In Progress se Hernandez Work In Progress	lights Need to replace 6 A/C commercial ur	10/15/2012 10/15/2012 3:54:24 PM hits for the	 	232	nment 4/2	\$0.00
<u>Guillermo </u> 94185 Medium Ambriz, Jo <u>Guillermo </u> 93992 Medium Ambriz, Jo	Hernandez Work In Progress se Hernandez Work In Progress se	lights Need to replace 6 A/C commercial ur	10/15/2012 10/15/2012 3:54:24 PM hits for the 10/10/2012 10/10/2012 11:27:53	 	232	nment 4/2	\$0.00
<u>Guillermo </u> 94185 Medium Ambriz, Jo <u>Guillermo </u> 93992 Medium Ambriz, Jo	Hernandez Work In Progress se Hernandez Work In Progress	lights Need to replace 6 A/C commercial un cafeteria Need assistance to remove old furna	10/15/2012 10/15/2012 3:54:24 PM hits for the 10/10/2012 10/10/2012 11:27:53		232	nment 4/2	\$0.00
Guillermo 94185 Medium Ambriz, Jo <u>Guillermo </u> 93992 Medium Ambriz, Jo Guillermo	Hernandez Work In Progress se Hernandez Work In Progress se	lights Need to replace 6 A/C commercial un cafeteria Need assistance to remove old furna	10/15/2012 10/15/2012 3:54:24 PM nits for the 10/10/2012 10/10/2012 11:27:53 ce from the Boys	· · ·	232	nment 4/2	\$0.00
Guillermo 94185 Medium Ambriz, Jo Guillermo 93992 Medium Ambriz, Jo <u>Guillermo </u> 94019	Hernandez Work In Progress se Hernandez Work In Progress se Hernandez Work In Progress	lights Need to replace 6 A/C commercial un cafeteria Need assistance to remove old furna	10/15/2012 10/15/2012 3:54:24 PM hits for the 10/10/2012 10/10/2012 11:27:53 ce from the Boys 10/10/2012 10/10/2012 3:43:56 PM	· · ·	232	nment 4/2	\$0.00
Guillermo 94185 Medium Ambriz, Jo <u>Guillermo </u> 93992 Medium Ambriz, Jo <u>Guillermo </u> 94019 Medium Ambriz, Jo Guillermo	Hernandez Work In Progress se Hernandez Work In Progress se Hernandez Work In Progress	lights Need to replace 6 A/C commercial un cafeteria Need assistance to remove old furna Gym	10/15/2012 10/15/2012 3:54:24 PM hits for the 10/10/2012 10/10/2012 11:27:53 ce from the Boys 10/10/2012 10/10/2012 3:43:56 PM A/C #6. cafeteria		232 237 237	nment 4/2	\$0.00
Guillermo 94185 Medium Ambriz, Jo Guillermo 93992 Medium Ambriz, Jo Guillermo 94019 Medium Ambriz, Jo Guillermo 94829	Hernandez Work In Progress se Hernandez Work In Progress se Hernandez Work In Progress se Hernandez	lights Need to replace 6 A/C commercial un cafeteria Need assistance to remove old furna Gym	10/15/2012 10/15/2012 3:54:24 PM hits for the 10/10/2012 10/10/2012 11:27:53 ce from the Boys 10/10/2012 10/10/2012 3:43:56 PM A/C #6. cafeteria 10/31/2012		232	nment 4/2	\$0.00
Guillermo 94185 Medium Ambriz, Jo <u>Guillermo </u> 93992 Medium Ambriz, Jo <u>Guillermo </u> 94019 Medium Ambriz, Jo Guillermo	Hernandez Work In Progress se Hernandez Work In Progress se Hernandez Work In Progress se Hernandez Work In Progress	lights Need to replace 6 A/C commercial un cafeteria Need assistance to remove old furna Gym	10/15/2012 10/15/2012 3:54:24 PM hits for the 10/10/2012 10/10/2012 11:27:53 ce from the Boys 10/10/2012 3:43:56 PM A/C #6. cafeteria 10/31/2012 10/31/2012 9:33:08 AM		232 237 237	nment 4/2	\$0.00

WOID Priority Assigned T Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By I Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
96339			12/6/2012		180		\$0.00
Medium	Work In Progress		12/6/2012 3:48:09 PM				
Ambriz, Jos	se	Need to replace gasket to pump in the Old English	n the boiler room for				
<u>Guillermo I</u> 92272	Hernandez		9/2/2012		275		\$0.00
Medium			9/2/2012 12:21:46 AM		215		ψ0.00
Munoz, Mic	Work In Progress	Monthly - Gadsden HS - Grease T					
Margret Vil	lalohos	Refer to PM schedule details.					
99640		Portables	3/13/2013		83		\$0.00
High	Work In Progress		3/13/2013 11:41:33 AM				
Villalobos,	David	please check all commodes and la operation and secure them as we is old , remove and caulk with new portables that were moved next to	ll if need be. if caulking v one. these are the				
Michael Mu 103007	unoz		6/3/2013		1		\$0.00
	/ Work In Progress		6/3/2013 12:39:42 PM		•		φ0.00
Villalobos,	C	Please check gas regulator on the Academic building for gas leak.					
Guillermo I	Hernandez						
103010			6/3/2013		1		\$0.00
Medium	Work In Progress	LINE LOCATE	6/3/2013 1:59:43 PM				
Villalobos,		In our meeting on Wednesday the have locates done this morning. I locater flags this morning and will tomorrow morning. Will you still be men out to the site today to locate marked?	received most of the have the rest here e able to have your				
Michael Mu 102732	unoz		5/30/2013		5		\$0.00
Medium	Work In Progress		5/30/2013 3:00:44 PM				
Villalobos,	-	Requested by Ms. Vandergeest R Sink next to door does not have ru switches.	m. 226 North Building-				
Velia Alarc	on						.
102733			5/30/2013		5		\$0.00
Medium	Work In Progress		5/30/2013 3:02:39 PM				
Villalobos,		Requested by Ms. Vandergeest R Sink at teacher's desk still release sulfurous, it has been this way for	s water that smells				
Velia Alarc							

6/4/2013 9:16:07 AM

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Lo Area Deferred By Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
99211			3/3/2013		93		\$0.00
Medium	Work In Progress		3/3/2013 12:25:56 AM				
Munoz, Mi	ichael	Monthly - Gadsden HS - Grease Tra Refer to PM schedule details.	ap (Culinary/Auto) -				
Margret Vi	illalobos		5/9/2013		26		\$0.00
101960					20		Ф 0.00
Medium	Work In Progress		5/9/2013 11:14:13 AM				
Sanchez,		please check bathrooms by soccer operations.(I. flush valves commod					
Michael M 102851	unoz		6/2/2013	6/5/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:41 AM				
Herrera, J	oel	Monthly - Gadsden HS - Emerg. Ey Refer to PM schedule details.	vewash (Monthly) -				
Margret V	illalobos		5/0/0010				
101597			5/2/2013		33		\$0.00
High	Work In Progress		5/2/2013 11:28:20 AM				
Villalobos,	David	Need to replace angle stop for the second floor of the Old English. Wa					
Guillermo 101991	Hernandez		5/9/2013		26		\$0.00
Medium	Work In Progress		5/9/2013 3:48:44 PM		20		\$0.00
	-						
Villalobos,		Need to clean sewer line for restroc building).	om #125, (Main				
102199	Hernandez		5/15/2013		20		\$0.00
Medium	Work In Progress		5/15/2013 7:40:09 AM				
Sotelo, En	-	New refrigeration unit is going to ins the band room, please check to sup					
	Hernandez						<u> </u>
103011			6/3/2013		1		\$0.00
Medium	Work In Progress	LINE LOCATE	6/3/2013 2:00:37 PM				
Sotelo, En	rique	In our meeting on Wednesday the of have locates done this morning. I re locater flags this morning and will h tomorrow morning. Will you still be men out to the site today to locate I marked?	eceived most of the ave the rest here able to have your				
Michael M	unoz						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Locati Area Deferred By L Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
101961		Portables	5/9/2013		26		\$0.00
Low	Work In Progress		5/9/2013 11:16:10 AM				
Munoz, Jo	e	please clean rest rooms and portable to pow wow. thank you	o be used in the				
Michael M 99042	unoz	Athletic Field	2/28/2013		96		\$0.00
Medium	Work In Progress		2/28/2013 3:24:38 PM		00		φ0.00
Holguin, R	amiro	sprinklers need to be replaced on softb fields.					
<u>Guadalupe</u> 100480	e Ontiveros		4/3/2013		62		\$0.00
Medium	Work In Progress		4/3/2013 9:57:03 AM				
Ontiveros,	Guadalupe	Requested by Coach Lawrence for Soc fields and set up all nets.	ccer Fields-Paint				
Velia Alaro	con		3/31/2013	4/8/2013	65		\$0.00
Medium	Work In Progress		3/31/2013 12:32:29 AM	4/0/2013	00		ψ0.00
	z, Guillermo	Monthly - Gadsden HS Roof Inspection schedule details.					
Margret Vi	llalobos		E/0/2012		27		\$0.00
101915			5/8/2013		21		Ф 0.00
Medium	Work In Progress		5/8/2013 11:30:45 AM				
Flores, Pet		Need to replace worn tire on truck #155	5.				
Guillermo 102729	Hernandez		5/30/2013		5		\$0.00
Medium	Work In Progress		5/30/2013 2:24:08 PM		-		
Herrera, Jo	Ū	Requested by Coach Gerela for Footba Room-Close vents on top side of buildin airway stops on bottom of doors, this m dust out.	all Office Auxillary ng and rubber				
Velia Alaro 102731	on		5/30/2013		5		\$0.00
Medium	Work In Progress		5/30/2013 2:30:18 PM		5		ψ0.00
Herrera, Jo	-	Requested by Mr. Greenberg Portable teacher is really sorry about you taking up the "starboard" in his classroom. Ite someone else. Mr. Greenberg would lik projector screen placed back.	#7-Memo, the time to hang m will be given to				
Velia Alarc	con						

WOID Priority Assigned T Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Location, Area Deferred By Unt Area Number Reason Description		ate Aged	Labor Hours	Costs
Location:	Gadsden	HS				
102736			5/30/2013	5		\$0.00
Medium	Work In Progress		5/30/2013 3:11:03 PM			
Herrera, Jo	pel	Requested by Cathy for Waiting Room in A Building-Hang up a picture. PLEASE SEE PICTURE.				
Velia Alarc 102954	on		6/2/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:29 AM	2		ψ0.00
Sanchez, F	C C	Monthly - Gadsden HS - Lift Station Inspe				
Sanchez, r	Naui	to PM schedule details.				
Margret Vil 102782	lalobos		5/31/2013	4		\$0.00
Medium	Work In Progress	F	5/31/2013 12:28:50 AM	-		ψ0.00
Sanchez, F	-	Monthly - Gadsden HS - Monthly Meter Ro Refer to PM schedule details.				
Margret Vil	lalobos					
101457			4/30/2013	35		\$0.00
Medium	Work In Progress	4	I/30/2013 12:29:56 AM			
Sanchez, F	Raul	Monthly - Gadsden HS-WWTP Chemical (Monthly) - Refer to PM schedule details.	Order			
Margret Vil 101959	lalobos		5/9/2013	26		\$0.00
Medium	Work In Progress		5/9/2013 11:12:37 AM	20		ψ0.00
	C					
Sanchez, F	Raul	check are prepare clean-out drain for rv du (pow wow)	ump stations			
Michael Mu	unoz	~ · ·				<u> </u>
101754			5/5/2013	30		\$0.00
Medium	Work In Progress		5/5/2013 12:24:33 AM			
Sanchez, F		Monthly - Gadsden HS - Lift Station Inspe to PM schedule details.	ction - Refer			
Margret Vil 103012	lalobos		6/3/2013	1		\$0.00
Medium	Work In Progress		6/3/2013 2:02:29 PM	·		Q
Sanchez, F	-	Cuco Garcia from Enoch Mechanical wou				
	vaui	down the fire line and fire pump tomorrow in the line. Can you have Raul/Mario shut pump tomorrow for a few hours?	to make taps			
Michael Mu	unoz					

Location: Gadsden HS 102631 5/28/2013 102631 5/28/2013 Medium Work In Progress LINE LOCATE Sanchez, Raul Company: TRIPLE J EXCAVATION Contact Name: ANNETTE GRANADO Contact Name: ANNETTE GRANADO Contact Phone: (575)527-1763 Location of Work: FROM N. MAIN ST & WASHINGTON ST FOR 1.70 MI TO LEVEE RD. LOCATE ENTIRE LENGTH & WIDTH OF BRIDGE ON WASHINGTON ST TO INCLUDE ALL OF THE AREA UNDERNEATH THE BRIDGE AS WELL. Alfredo Holguin 6/2/2013 102252 6/2/2013 Medium Work In Progress Sanchez, Raul Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details. Margret Villalobos 102725 Office 5/30/2013 102725 Office Sologe Samonez, Raul Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details. Margret Villalobos 102725 Office 5/30/2013 Tozzes Z 5/30/2013 Medium Work In Progress Hermandez, Guillermo Memo - to drive hand truck to Sam's to pick up drinks for pow wow 150 cases of water and coke. Thank you! Cathy Ramos 2/25/2013 Gorda Laroon 100734		Labor Hours
Medium Work In Progress LINE LOCATE 5/28/2013 1:57:07 PM Sanchez, Raul Company: TRIPLE J EXCAVATION Contact Name: ANNETTE GRANADO Contact Name: ANNETTE GRANADO Contact Name: ANNETTE GRANADO ST IN ANTHOINY. GO W ON WASHINGTON ST FOR 1.70 MI TO LEVEE RD. LOCATE ENTIRE LENGTH & WIDTH OF BRIDGE ON WASHINGTON ST TO INCLUDE ALL OF THE AREA UNDERNEATH THE BRIDGE ON WASHINGTON ST TO INCLUDE ALL OF THE AREA UNDERNEATH THE BRIDGE ON WORK IN Progress 6/2/2013 1:2:29:28 AM Sanchez, Raul Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details. Margret Villalobos 102725 Office 5/30/2013 Medium Work In Progress 5/30/2013 1:52:18 PM Hernandez, Guillermo Memo - to drive band truck to Sam's to pick up drinks for pow wow 150 cases of water and coke. Thank you! Cathy Ramos 98803 2/25/2013 Medium Work In Progress 2/25/2013 8:27:10 AM Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building- Door doesn't stay open (magnet) Valia Alarcon 100734 4/9/2013 Medium Work In Progress 4/9/2013 Medium Work In Progress 5/24/2013 1:45:04 PM Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light buib needs to be replaced. Valia Alarcon 10252 5/24/2013 1:30:03 PM Herrera, Joel S-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24/2013 Medium Work In Progress 5/24/2013 1:30:03 PM Herrera JOE 6-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 FURNITURE Joel Herrera 101404 4/29/2013		
Sanchez, Raul Company: TRIPLE J EXCAVATION Contact Name: ANNETTE GRANADO Contact Phone: (675)527-1763 Location of Work: FROM N. MAIN ST & WASHINGTON ST IN ANTHONY, GO W ON WASHINGTON ST FOR 1.70 MI TO LEVEE RD. LOCATE ENTIRE LENGTH & WIDTH OF BRIDGE ON WASHINGTON ST TO INCLUDE ALL OF THE AREA UNDERNEATH THE BRIDGE AS WELL. Alfredo Holguin 102952 6/2/2013 12:29:28 AM Sanchez, Raul Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details. Margret Villalobos 102725 Office 5/30/2013 152:18 PM Hernandez, Guillermo Memo - to drive band truck to Sam's to pick up drinks for pow wow 150 cases of water and coke. Thank you! Cathy Ramos 98803 2/25/2013 8:27:10 AM Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building- Door doesn't stay open (magnet) Velia Alarcon 100734 4/9/2013 1:45:04 PM Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 102582 5/24/2013 1:30:03 PM Herrera, Joel S-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 FUNNITURE Joel Herrera 101404 4/29/2013	7	\$0.00
Contact Phone: (575)527-1763 Location of Work: FROM N. MAIN ST & WASHINGTON ST IN ANTHONY, GO W ON WASHINGTON ST FOR 1.70 MI TO LEVEE RD. LOCATE ENTIRE LENGTH & WIDTH OF BRIDGE ON WASHINGTON ST TO INCLUDE ALL OF THE AREA UNDERNEATH THE BRIDGE AS WELL Alfredo Holguin 6/2/2013 102952 6/2/2013 Medium Work In Progress 6/2/2013 12:29:28 AM Sanchez, Raul Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details. Margret Villalobos 0/162 102725 Office Memo - to drive band truck to Sam's to pick up drinks for pow wow 150 cases of water and coke. Thank you! Cathy Ramos 2/25/2013 Medium Work In Progress 100734 4/9/2013 Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building- Door doesn't stay open (magnet) Velia Alarcon 4/9/2013 100734 4/9/2013 Medium Work In Progress 4/24/2013 5/24/2013 Medium Work In Progress 4/9/2013 5/24/2013 Medium YolzUS Velia Alarcon 5/24/2013 100734 5/24/2013 Medium <t< td=""><td></td><td></td></t<>		
ST IN ANTHONY, GO WO NWASHINGTON ST FOR NTO IN TO LEVEE RD. LOCATE ENTIRE LENGTH & WIDTH OF BRIDGE ON WASHINGTON ST TOR INCLUDE ALL OF THE AREA UNDERNEATH THE BRIDGE AS WELL. Alfredo Holguin 6/2/2013 102952 6/2/2013 Medium Work In Progress 6/2/2013 12:29:28 AM Sanchez, Raul Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details. 6/30/2013 Margret Villalobos 102725 Office 5/30/2013 Medium Work In Progress 5/30/2013 1:52:18 PM Hernandez, Guillermo Memo - to drive band truck to Sam's to pick up drinks for pow wow 150 cases of water and coke. Thank you! Cathy Ramos 2/25/2013 98803 2/25/2013 8:27:10 AM Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building- Door doesn't stay open (magnet) Velia Alarcon 4/9/2013 Medium Work In Progress 4/9/2013 Kequested by Mr. Alan Andersen Rm. 220 North Building-Light builb needs to be replaced. Velia Alarcon 5/24/2013 102582 5/24/2013 Velia Alarcon 5/24/2013 102582 5/24/2013 Velia Alarcon 5/24/2013 Herrera, Joel		
102952 6/2/2013 Medium Work In Progress 6/2/2013 12:29:28 AM Sanchez, Raul Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details. Margret Villalobos 102725 102725 Office Medium Work In Progress Hernandez, Guillermo Memo - to drive band truck to Sam's to pick up drinks for pow wow 150 cases of water and coke. Thank you! Cathy Ramos 2/25/2013 98803 2/25/2013 Medium Work In Progress Perrera, Joel Requested by Ms. Miller Rm. 344 Academic Building-Door doesn't stay open (magnet) Velia Alarcon 4/9/2013 100734 4/9/2013 Medium Work In Progress 4/9/2013 1:45:04 PM Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 5/24/2013 1:30:03 PM Herrera, Joel S/24/2013 1:30:03 PM Herrera, Joel 5-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 FURNITURE Joel Herrera 4/29/2013		
Medium Work In Progress 6/2/2013 12:29:28 AM Sanchez, Raul Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details. Margret Villalobos 102725 102725 Office 5/30/2013 1:52:18 PM Hernandez, Guillermo Memo - to drive band truck to Sam's to pick up drinks for pow wow 150 cases of water and coke. Thank you! Cathy Ramos 2/25/2013 98803 2/25/2013 8:27:10 AM Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building-Door doesn't stay open (magnet) Velia Alarcon 4/9/2013 100734 4/9/2013 Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 5/24/2013 1:30:03 PM Herrera, Joel S/24/2013 1:30:03 PM Herrera S/24/2013 1:30:03 PM <	2	\$0.00
Sanchez, Raul Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details. Margret Villalobos 102725 Office 5/30/2013 Medium Work In Progress 5/30/2013 1:52:18 PM Hernandez, Guillermo Memo - to drive band truck to Sam's to pick up drinks for pow wow 150 cases of water and coke. Thank you! Cathy Ramos 98803 2/25/2013 8:27:10 AM Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building- Door doesn't stay open (magnet) Velia Alarcon 100734 4/9/2013 Medium Work In Progress 4/9/2013 1:45:04 PM Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 102582 5/24/2013 Medium Work In Progress 5/24/2013 1:30:03 PM Herrera, Joel S-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 FURNITURE Joel Herrera 101404 4/29/2013		
Margret Villalobos 102725 Office 5/30/2013 Medium Work In Progress 5/30/2013 1:52:18 PM Hernandez, Guillermo Memo - to drive band truck to Sam's to pick up drinks for pow wow 150 cases of water and coke. Thank you! Cathy Ramos 2/25/2013 98803 2/25/2013 Medium Work In Progress 2/25/2013 8:27:10 AM Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building-Door doesn't stay open (magnet) Velia Alarcon 4/9/2013 100734 4/9/2013 Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 5/24/2013 102582 5/24/2013 Medium Work In Progress Figure Building-Light bulb needs to be replaced. 5/24/2013 Medium Work In Progress 5/24/2013 1:30:03 PM Herrera, Joel 5-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 Joel Herrera 4/29/2013		
Medium Work In Progress 5/30/2013 1:52:18 PM Hernandez, Guillermo Memo - to drive band truck to Sam's to pick up drinks for pow wow 150 cases of water and coke. Thank you! Cathy Ramos 2/25/2013 98803 2/25/2013 8:27:10 AM Medium Work In Progress 2/25/2013 8:27:10 AM Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building-Door doesn't stay open (magnet) Velia Alarcon 4/9/2013 100734 4/9/2013 Medium Work In Progress 4/9/2013 1:45:04 PM Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 5/24/2013 1:30:03 PM Herrera, Joel S-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 FURNITURE 5/24/2013 5/24-6 Joel Herrera 4/29/2013 5/24-6		
Hernandez, Guillermo Memo - to drive band truck to Sam's to pick up drinks for pow wow 150 cases of water and coke. Thank you! Cathy Ramos 2/25/2013 98803 2/25/2013 8:27:10 AM Medium Work In Progress 2/25/2013 8:27:10 AM Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building-Door doesn't stay open (magnet) Velia Alarcon 4/9/2013 100734 4/9/2013 1:45:04 PM Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 5/24/2013 102582 5/24/2013 Medium Work In Progress Herrera, Joel S-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24/6 Joel Herrera 5/24/2013 5/24/2013 10404 4/29/2013 5/24/2013	5	\$0.00
pow wow 150 cases of water and coke. Thank you! Cathy Ramos 98803 2/25/2013 Medium Work In Progress 2/25/2013 8:27:10 AM Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building- Door doesn't stay open (magnet) Velia Alarcon 4/9/2013 100734 4/9/2013 Medium Work In Progress 4/9/2013 1:45:04 PM Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 5/24/2013 1:30:03 PM Herrera, Joel 5-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 Joel Herrera 4/29/2013 101404 4/29/2013		
98803 2/25/2013 Medium Work In Progress 2/25/2013 8:27:10 AM Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building- Door doesn't stay open (magnet) Velia Alarcon 4/9/2013 100734 4/9/2013 Medium Work In Progress Alarcon 4/9/2013 1:45:04 PM Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 5/24/2013 102582 5/24/2013 Medium Work In Progress Medium Work In Progress 5/24/2013 5/24/2013 Medium Work In Progress 5/24/2013 1:30:03 PM Herrera, Joel 5-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 Joel Herrera 4/29/2013		
Medium Work In Progress 2/25/2013 8:27:10 AM Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building- Door doesn't stay open (magnet) Velia Alarcon 4/9/2013 100734 4/9/2013 Medium Work In Progress 4/9/2013 1:45:04 PM Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 5/24/2013 102582 5/24/2013 Medium Work In Progress Herrera, Joel 5/24/2013 Medium Work In Progress 5/24/2013 5/24/2013 Herrera, Joel 5-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 Joel Herrera 4/29/2013 1/29/2013	99	\$0.00
Herrera, Joel Requested by Ms. Miller Rm. 344 Academic Building- Door doesn't stay open (magnet) Velia Alarcon 4/9/2013 100734 4/9/2013 Medium Work In Progress 4/9/2013 1:45:04 PM Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 5/24/2013 102582 5/24/2013 Medium Work In Progress Medium Work In Progress 5/24/2013 1:30:03 PM Herrera, Joel 5-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 5/24-6 Joel Herrera 4/29/2013		\$ 0100
1007344/9/2013MediumWork In Progress4/9/2013 1:45:04 PMHerrera, JoelRequested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced.Velia Alarcon5/24/20131025825/24/2013MediumWork In Progress5/24/2013 1:30:03 PMHerrera, Joel5-24-13 8.0 CHECKED A/CS AND RE-MOVEDJoel Herrera1014044/29/2013		
Medium Work In Progress 4/9/2013 1:45:04 PM Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 5/24/2013 102582 5/24/2013 1:30:03 PM Medium Work In Progress 5/24/2013 1:30:03 PM Herrera, Joel 5-24-13 8.0 CHECKED A/CS AND RE-MOVED Joel Herrera 4/29/2013		
Herrera, Joel Requested by Mr. Alan Andersen Rm. 220 North Building-Light bulb needs to be replaced. Velia Alarcon 5/24/2013 102582 5/24/2013 1:30:03 PM Medium Work In Progress 5-24-13 8.0 CHECKED A/CS AND RE-MOVED Joel Herrera 5/24-6 101404 4/29/2013	56	\$0.00
Building-Light bulb needs to be replaced. Velia Alarcon 5/24/2013 102582 5/24/2013 Medium Work In Progress 5-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 FURNITURE 5/24/2013 Joel Herrera 4/29/2013		
102582 5/24/2013 Medium Work In Progress 5/24/2013 1:30:03 PM Herrera, Joel 5-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 Joel Herrera 5/24/2013 101404 4/29/2013		
Medium Work In Progress 5/24/2013 1:30:03 PM Herrera, Joel 5-24-13 8.0 CHECKED A/CS AND RE-MOVED 5/24-6 Joel Herrera 101404 4/29/2013 5/24-9	11	\$0.00
FURNITURE Joel Herrera 101404 4/29/2013		
101404 4/29/2013		
	00	
Medium Work In Progress 4/29/2013 9:12:44 AM	36	\$0.00
Herrera, Joel Requested by Ray Calderon-Move cork board from the Old English Building (2nd Floor) to Main Building next to room # 110.		
Velia Alarcon		

6/4/2013 9:16:07 AM

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date T Created Date/Time A	arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	HS					
101150			4/22/2013		43		\$0.00
Medium	Work In Progress		4/22/2013 9:34:04 AM				
Herrera, Jo		Requested by Ms. Aguilar Rm. 231 I Smart Board from west wall to south keep students focused and prevent to towards door and being distracted b who is in the hall.	wall. *Will help them from turning				
Velia Alaro 102921	con		6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:15 AM				
Herrera, Jo	bel	Monthly - Gadsden HS Bleacher Ins PM schedule details.	pection - Refer to				
Margret Vi 102923	llalobos		6/2/2013		2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:16 AM		2		ψ0.00
Herrera, Jo	C C	Monthly - Gadsden HS-Clothes Drye to PM schedule details.					
Margret Vi	llalobos						
102937			6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:22 AM				
Herrera, Jo		Monthly - Gadsden HS Emer. Light Refer to PM schedule details.	Test: Monthly -				
Margret Vi 99892	llalobos		3/19/2013		77		\$0.00
Medium	Work In Progress		3/19/2013 4:26:10 PM				
Ronquillo,	Ū	BROKEN WINDOWS PT. 1 26X18- PT. 4 26X36-1 ALL SINGLE GLASS					
Ruben Ro	nquillo	Cafeteria	4/3/2013		62		\$0.00
100478		Caleteria			02		φ0.00
Medium	Work In Progress		4/3/2013 9:53:40 AM				
Miranda, E	Danny	KITCHEN-WALLS NEED TO BE RE FIXED IN STORAGE AND CHEMIC PIECES ARE FALLING. SNP MANA 882.5522	AL ROOMS.				
Maritza Go	onzalez		2/21/2012		CE.		¢0.00
100309 Medium	Work In Progress		3/31/2013 3/31/2013 12:33:00 AM		65		\$0.00
	Ū						
Holguin, A	IIIEGO	Monthly - Gadsden HS - Fire Pump PM schedule details.	Engine - Refer to				
Margret Vi	llalobos						

WOID Priority	ate Range for Request Building Status	Area Number	Deferred By	Until	-	Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned [•]	То	Description				Action Taken			
Requester	Name								
Location:	Gadsden	HS							
102989					6/3/2013		1		\$0.00
Medium	Work In Progress			6/3/2	013 6:43:15 AM				
Hernandez	z, Guillermo	Please check a replace.	all buildings for burn	out lamps and					
	Hernandez				5/5/2013	5/13/2013	30		\$0.00
101747						5/15/2015	30		φ0.00
Medium	Work In Progress			5/5/20	13 12:24:31 AM				
Hernandez	z, Guillermo	Monthly - Gade PM schedule d	den HS Exit Sign Ir etails.	nsp: Monthly -	Refer to				
Margret Vil	llalobos				0/0/0040	0/40/0040	0		<u> </u>
102917					6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/20	13 12:29:13 AM				
Hernandez	z, Guillermo	Monthly - Gads PM schedule d	den HS Exit Sign Ir etails.	nsp: Monthly -	Refer to				
Margret Vil 100304	llalobos				3/31/2013		65		\$0.00
							05		φ0.00
Medium	Work In Progress			3/31/20	13 12:32:58 AM				
Holguin, Al	lfredo	Monthly - Gads to PM schedule	den HS Generator	PM (Quarterly)	- Refer				
Margret Vil									
Count: 104	4 Work Orders	Α	vg. Age of WO's	68		Total for Gadsde	n HS	0	\$0.00

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By Reason	Until Request Date T Created Date/Time A	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	MS						
97907				1/31/2013		124		\$0.00
Medium	Work In Progress			1/31/2013 12:25:28 AM				
Apodaca, N	Mario		den MS-WWTP C er to PM schedule					
Margret Vil	lalobos			5/31/2013		4		\$0.00
102784						4		Ф 0.00
Medium	Work In Progress			5/31/2013 12:28:51 AM				
Apodaca, N		Monthly - Gads Refer to PM sch		Meter Readings -				
Margret Vil 101446	lalobos			4/30/2013		35		\$0.00
Medium	Work In Progress			4/30/2013 12:29:52 AM				
Apodaca, N	-		den MS-WWTP C er to PM schedule	Chemical Order				
Margret Vil	lalobos							•
101750				5/5/2013		30		\$0.00
Medium	Work In Progress			5/5/2013 12:24:32 AM				
Apodaca, N		Monthly - Gadse to PM schedule		ion Inspection - Refer				
Margret Vil 102957	lalobos			6/2/2013		2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:31 AM				
Apodaca, N	Ū.	Monthly - Gadso to PM schedule		Water Samples - Refer				
Margret Vil	lalobos							
102958				6/2/2013		2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:31 AM				
Apodaca, N		Monthly - Gadso to PM schedule		ion Inspection - Refer				
Margret Vil 103050	lalobos			6/4/2013		0		\$0.00
Medium	Work In Progress			6/4/2013 12:21:46 AM				
Apodaca, N	Ū.	Monthly - Gadso to PM schedule		ic Water Filters - Refer				
Margret Vil	lalobos							•
102214		Classroom		5/15/2013		20		\$0.00
Medium	Work In Progress	Gym room 600		5/15/2013 10:42:23 AM				
Diaz, Seba	stian	Remove small b	poard from wall ar	nd send to Rm 146.				

WOID Priority Assigned			Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
	Cuusuch	Gym		5/23/2013		12		\$0.00
102514		•				12		φ 0. 00
Medium	Work In Progress	Gym		5/23/2013 9:09:43 AM	l			
Diaz, Seba	istian	Can you please inserts.	remove the wax fi	om volleyball poles				
Nancy Tina	ajero	Office		2/15/2012		01		¢0.00
99751		Office		3/15/2013		81		\$0.00
Medium	Work In Progress	front office		3/15/2013 11:31:03 AM				
Diaz, Seba	istian	and electrical fo		ty monitor installation See Mrs. Quinonez				
Nancy Tina 102948	ajero			6/2/2013	6/10/2013	2		\$0.00
						2		φ0.00
Medium	Work In Progress			6/2/2013 12:29:26 AM				
Diaz, Seba		Monthly - Gadso Refer to PM sch	len MS Emer. Ligl edule details.	nt Test: Monthly -				
Margret Vil 102949	llalobos			6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:27 AM				
Diaz, Seba	C C	Monthly - Gadso to PM schedule		nsp: Monthly - Refer				
Margret Vil	llalobos							
102950				6/2/2013		2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:27 AM	l			
Diaz, Seba	istian	Monthly - Gadso to PM schedule		Dryer (Monthly) - Refer				
Margret Vil	llalobos			- 10/00/0				<u> </u>
101827				5/6/2013		29		\$0.00
Medium	Work In Progress			5/6/2013 1:17:23 PM	l			
Diaz, Seba	istian	BUILDING HAS						
Alfredo Ho	Iguin				_ /_ /			•
102853				6/2/2013	6/5/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:28:42 AM	l			
Diaz, Seba	istian	Monthly - Gadso Refer to PM sch		Eyewash (Monthly) -				
	llalobos							

NOID Priority Assigned 1 Requester		Area Deferred By U Area Number Reason Description	Intil Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
ocation:	Gadsden	MS					
101828			5/6/2013		29		\$0.00
Medium	Work In Progress		5/6/2013 1:17:56 PM				
√illalobos,		AS PER WORK ORDER #101815, VO BUILDING HAS ASBESTOS AND THE ABATING THE FIRST WEEK IN JUNE STOVES REMOVED.	Y WILL BE				
Alfredo Hol 96902	guin	Football Field	1/7/2013		148		\$0.00
Medium	Work In Progress		1/7/2013 8:18:11 AM				ψυιυυ
Sotelo, Enr	-	Enrique can you help disconnecting po scoreboard please so we can work on i	wer on				
<u>Salvador G</u> 102879	onzalez		6/2/2013	6/18/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:55 AM		-		φ0.00
villalobos,		Monthly - Gadsden MS Monthly Chiller PM schedule details.					
Margret Vil	lalobos						
101676			5/5/2013	5/21/2013	30		\$0.00
Medium	Work In Progress		5/5/2013 12:24:02 AM				
√illalobos,	-	Monthly - Gadsden MS Monthly Chiller PM schedule details.	Insp Refer to				
<u>Margret Vil</u> 102855	lalobos		6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:43 AM				
Diaz, Seba	Ū	Yearly - Gadsden MS B-2 Boiler Yearly schedule details.	- Refer to PM				
Margret Vil	lalobos		- / /	-///			
102778			5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:48 AM				
Diaz, Seba		Yearly - Gadsden MS A-2 Split System to PM schedule details.	s Yearly - Refer				
<u>Margret Vil</u> 102779	lalobos		5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:48 AM				
Diaz, Seba	-	Yearly - Gadsden MS A-9 Air Cooled C Refer to PM schedule details.					
Margret Vil	lalobos						
102513		Classroom	5/23/2013		12		\$0.00
Medium	Work In Progress	A wing	5/23/2013 8:57:55 AM	l			
Diaz, Seba	stian	please paint classroom 163					
Nancy Tina	ijero						

6/4/2013 9:16:07 AM

WOID Priority Assigned	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Area Deferred By Area Number Reason Description	Until Request Date Tar Created Date/Time Act	A	Costs
Requester					
Location:	Gadsden	MS			
102600		Classroom	5/28/2013	7	\$0.00
Medium	Work In Progress	Vocational	5/28/2013 9:34:45 AM		
Diaz, Seba	astian	Please paint the room.			
<u>Nancy Tina</u> 102722	ajero		5/30/2013	5	 \$0.00
Medium	Work In Progress		5/30/2013 9:01:01 AM		
Lara, Ralpl	h	AS PER LORENA WITH EL PAS DOES NOT HAVE A GATE KEY OUT TO THEM A.S.A.P.			
Jesus Estr 100505	ada		4/3/2013	62	\$0.00
Medium	Work In Progress		4/3/2013 3:34:37 PM	02	φ0.00
	C C				
Solis, Lore		Need to fix pump on boiler wests	ade thank you		
Sebastian 98858	Diaz		2/26/2013	98	 \$0.00
Medium	Work In Progress	Parking Lot -	2/26/2013 8:56:03 AM		
Lozoya, M		Lock opens with a slight pull. It of Please replace.	does't lock properly.		
Nancy Tina 101867	ajero C-Wing		5/7/2013	28	\$0.00
Medium	Work In Progress	CHARTER	5/7/2013 2:58:27 PM	-	
Solis, Lore	0	Charter School - Need to replace not shut off.			
Maggie Go 103040	onzalez C-Wing		6/3/2013	1	 \$0.00
Medium	Work In Progress		6/3/2013 4:26:43 PM	·	ψ0.00
	0	Number and the set into the Ob			
Lara, Ralpl		Nurses - need to get into the Ch	laner School		
Alfredo Ho 101220	lguin C-Wing	Office	4/23/2013	42	\$0.00
Medium	Work In Progress		4/23/2013 2:16:35 PM		·
Ontiveros,	Guadalupe	We would love to have a shade to yard, outside our office, to replace died last yr.	ce the 2 palm trees that		
	101/02	Thank you sooo muchColleen	Nursing Dept		
<u>Colleen Ru</u> 101163	<u>unyan</u> Gym	Dressing Room	4/22/2013	43	\$0.00
Medium	Work In Progress		4/22/2013 11:59:25 AM		
Lozoya, Ma	-	GYM OUTSIDE BOYS LOCKER HANDLE IS GETING STUCK	ROOM DOOR LEVER		
Juan Acos	ta				

WOID Priority Assigned	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Location Area Deferred By U Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requeste		MS					
100825		Gym	4/11/2013		54		\$0.00
	Gym	Gym			54		φ0.00
Medium	Work In Progress		4/11/2013 8:18:37 AM				
Lozoya, N		WILL BE RE-FINISHING GYM FLOOR NEED TO CHANCE CORES TO EXIT LOCKER ROOM EXIT DOORS TO GY	DOORS AND				
<u>Juan Acos</u> 95951	sta Gym		11/29/2012		187		\$0.00
Medium	Work In Progress	Gym Storage	11/29/2012 3:23:49 PM				
Gonzalez,	-	Please build new loft in storage room ir See Mr. Calleros for more details.					
Nancy Tin	ajero						
100367			3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress		3/31/2013 12:33:24 AM				
Orozco, D	aniel	Monthly - Gadsden MS Range Hood Cl PM schedule details.	eaning - Refer to				
Margret V 99229	illalobos		3/3/2013		93		\$0.00
Medium	Work In Drograad		3/3/2013 12:26:04 AM		00		ψ0.00
	Work In Progress						
Munoz, M		Yearly - Gadsden MS Fire Ext. Insp. (Y PM schedule details.	early) - Refer to				
<u>Margret V</u> 102515	IIIalobos	Classroom	5/23/2013		12		\$0.00
Medium	Work In Progress	Room 180-Mr.	5/23/2013 9:57:47 AM				
Briones, E	Enrique	Please surplus items: #0034979667, 00 0034106728, MU170860077168. They the door that are not covered.					
Nancy Tin	ajero		7/47/0040		000		<u> </u>
89884			7/17/2012		322		\$0.00
Medium	Work In Progress		7/17/2012 7:12:12 AM				
Lozoya, N	-	ALL CORES TO EXIT DOORS OUTSIL CLEANING	DE NEEDS				
Juan Acos 102968	sta		6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:36 AM	0/0/2010	2		ψ0.00
	Ũ						
Diaz, Seb		Monthly - Gadsden MS Monthly FE Insp PM schedule details.	pection - Refer to				
<u>Margret V</u> 101634	IIIdIUDUS	Athletic Field	5/3/2013		32		\$0.00
Medium	Work In Progress		5/3/2013 7:26:47 AM				
Gonzalez,	-	scoreboard to football field was damage					
GUNZAIEZ,		winds. please re-install. thank you					
Michael M	lunoz						
\$/4/2013	9:16:07 AM					Dere	83 of 160

6/4/2013 9:16:07 AM

WOID Priority Assigned 7 Requester		Area Area Number Description	Deferred By		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
101323				4/25/2013		40		\$0.00
Medium	Work In Progress			4/25/2013 3:20:03 PM				
Orozco, Da	aniel		AIN ON HADNWA RRY P. 882.2824	SHING SINK. SNP				
Maritza Go 101324	nzalez			4/25/2013		40		\$0.00
Medium	Work In Progress			4/25/2013 3:20:21 PM				<i>Q</i> 0.00
Orozco, Da	•	MILK COOLER 882.2824	IS DOWN. SNP N	JANAGER TERRY P.				
Maritza Go	nzalez			5/40/0040				* 0.00
102007				5/10/2013		25		\$0.00
Medium Sanchez, F	Work In Progress Raul	LINE LOCATE TRIPLE J EXC Contact Name: Phone: (575)5	ANNETTE GR/	5/10/2013 10:10:20 AM				
		& WASHINGTON WASHINGTON LOCATE ENTI ON WASHING	rk: W1305091638 DN ST IN ANTHOI I ST FOR 1.70 MI RE LENGTH & WI TON ST TO INCLI NEATH THE BRID	TO LEVEE RD. DTH OF BRIDGE JDE ALL OF THE				
Alfredo Hol 100928	lguin			4/15/2013		50		\$0.00
Medium	Work In Progress			4/15/2013 12:20:19 PM				
Orozco, Da	aniel	FAUCET LEAK 882.2824	(ING . SNP MANA	GER TERRY P.				
Maritza Go 102605	nzalez Cafeteria	Cafeteria		5/28/2013		7		\$0.00
Medium	Work In Progress	Cafeteria		5/28/2013 10:09:00 AM		,		ψ0.00
Diaz, Seba	•		p in cafeteria. See					
Nancy Tina	ajero							
99915				3/20/2013		-268		\$0.00
Medium	Work In Progress			3/20/2013 9:47:57 AM	6/25/2012			
Estrada, Je		FLOOR NEED 113' X W - 89')	S TO BE RE-FINIS	SHED (APPROX. L -				
Jesus Estra 102628	ada Main Building	Office		5/28/2013		7		\$0.00
Medium	Work In Progress	Room 177		5/28/2013 11:45:50 AM				
Diaz, Seba	-	Please paint ro	om					
, 5050								

	To [.] Name	Area Number Reason Description	Created Date/Time Ac	ctual Comp Date Action Taken	Aged	Hours	
Location:	Gadsden	MS					
102626	Main Building	Office	5/28/2013		7		\$0.00
Medium	Work In Progress	Office Area	5/28/2013 11:42:39 AM				
Diaz, Seba	astian	Paint office area/					
Nancy Tina		Classroom	E/29/2012		7		\$0.00
102625	Main Building		5/28/2013		/		Ф 0.00
Medium	Work In Progress	Room 180	5/28/2013 11:40:13 AM				
Diaz, Seba		Paint classroom					
<u>Nancy Tina</u> 102627	ajero Main Building	Classroom	5/28/2013		7		\$0.00
Medium	Work In Progress	Room 160	5/28/2013 11:44:27 AM				
Diaz, Seba	astian	Please paint room					
Nancy Tina	ajero						
102630	Main Building	Classroom	5/28/2013		7		\$0.00
Medium	Work In Progress	Room 157	5/28/2013 11:49:41 AM				
Diaz, Seba	astian	Please remove the projector scree top of the chalk board and place it Moreno.					
Nancy Tina 102606	ajero Main Building	Classroom	5/28/2013		7		\$0.00
Medium	Work In Progress	Room 164	5/28/2013 10:15:42 AM				
Diaz, Seba	C C	Windows need to be sealed becau	se dirt is coming in.				
Nancy Tina							
102607	Main Building	Classroom	5/28/2013		7		\$0.00
Medium	Work In Progress	Room 157	5/28/2013 10:34:28 AM				
Diaz, Seba		Remove small white board next to behind it because it is pink. Paint r light switch. Paint door.					
<u>Nancy Tina</u> 102608	ajero Main Building	Classroom	5/28/2013		7		\$0.00
Medium	Work In Progress	Room 157	5/28/2013 10:36:30 AM				
Diaz, Seba	C C	Install 2 tag board strips on wall wh removed. (Strips with screws are I smart board)					
<u>Nancy Tina</u> 100829	ajero Main Building	Hallway/Corridor	4/11/2013		54		\$0.00
Medium	Work In Progress		4/11/2013 8:55:47 AM				
_ozoya, M	-	A.WING DOOR GOING OUTSIDE DOOR LEVER HANDLE IS GETIN	TO PARK LOT .THE				

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Area Deferred By Area Number Reason Description	Until Request Date Target Comp Date Created Date/Time Actual Comp Date Action Taken	· · ·	Labor Hours	Costs
Location:	Gadsden	MS				
98661	Main Building		2/20/2013	104		\$0.00
Medium	Work In Progress		2/20/2013 10:34:21 AM			
Lozoya, M	anny	A.B WING ALL EXIT DOORS CO CLEAN CAN UNLOCK WITH KE				
<u>Juan Acos</u> 102668	ta Main Building	Office	5/29/2013	6		\$0.00
Medium	Work In Progress	Onice	5/29/2013 9:57:21 AM	0		ψ0.00
	Ū.					
Briones, E	•	Please deliver 42 boxes for PO 1	21307199.			
<u>Larry Marti</u> 102624	inez Main Building	Classroom	5/28/2013	7		\$0.00
Medium	Work In Progress	Room 148	5/28/2013 11:38:54 AM			
_ara, Ralp	h	Door does not close properly				
Nancy Tina						
94874	Main Building		11/1/2012	215		\$0.00
Aedium	Work In Progress		11/1/2012 7:48:39 AM			
₋ozoya, M	anny	B.WING EXIT DOOR NEXT TO F UNLOCK WHTH KEY	ROOM 113 CANNOT			
<u>Juan Acos</u> 102620	ta Band Room	Classroom	5/28/2013	7		\$0.00
Vedium	Work In Progress	Room 100-	5/28/2013 11:33:27 AM	,		ψ0.00
	-					
_ara, Ralp		Finish rod locks for guitar cabinet	s in storage room			
<u>Nancy Tina</u> 102613	ajero Band Room	Classroom	5/28/2013	7		\$0.00
Medium	Work In Progress	Room 100	5/28/2013 10:55:14 AM			
Diaz, Seba	Ū.	Paint counter shelves brown.				
Nancy Tina						
102619	Band Room	Classroom	5/28/2013	7		\$0.00
Aedium	Work In Progress	Room 100-	5/28/2013 11:30:46 AM			
Diaz, Seba	astian	Paint outside entrace doors front	and back.			
Nancy Tina						•
02618	Band Room	Classroom	5/28/2013	7		\$0.00
/ledium	Work In Progress	Room 100 Band	5/28/2013 11:13:13 AM			
Sotelo, En	rique	Install wall electrical outlets; north	n end. See Mr. Chacon.			
Nancy Tina 02612	ajero Band Room	Cafeteria	5/28/2013	7		\$0.00
/Jedium	Work In Progress	Room 100	5/28/2013 10:50:30 AM	1		ψ0.00
	-					
Diaz, Seba		Finish painting instrument bins gr	ey.			
Nancy Tina	ajero 9·16·07 AM					86 of 160

6/4/2013 9:16:07 AM

Requester Name Location: Gadsden MS 102611 Band Room Classroom 5/28/2013 10.48.35 AM Estrada, Jesus Repair snags on carpet, office, and inner rooms. Name 7 Name Timilero 7 7 102622 Band Room 5/28/2013 10.48.35 AM Bestrada, Jesus Repair snags on carpet, office, and inner rooms. 7 102622 Band Room 5/28/2013 11.36.47 AM Ontiveros, Guadalupe Fill in gravel area sink holes. 7 Nancy Timilero 7 7 102621 Band Room Classroom 5/28/2013 11.35.48 AM Diaz, Sebastian Clear weeds from front entrance before June 5 for summer band camp. 7 Nancy Timilero 7 7 7 102621 Band Room Clear weeds from front entrance. 7 Nancy Timilero 7 7 7 102623 Band Room Clear weeds from front entrance. 7 Nancy Timalero 7 7	Costs
Medium Work In Progress Room 100-Band 5/28/2013 10:48:35 AM Estrada, Jesu Repair snags on carpet, office, and inner rooms. 102822 Nancy Tinajero 5/28/2013 7 102822 Band Room 5/28/2013 11:36:47 AM 7 Medium Work In Progress room 100- Band 5/28/2013 11:36:47 AM 7 Ontiveros, Guadalupe Fill in gravel area sink holes. 5/28/2013 11:36:47 AM 7 Nancy Tinajero 102827 Band Room Classroom 5/28/2013 11:36:48 AM Diaz, Sebastian Clear weeds from front entrance before June 5 for summer band camp. 7 Nancy Tinajero 102823 Band Room 5/28/2013 11:37:32 AM Diaz, Sebastian Repair holes in the stucco front entrance. 7 Nancy Tinajero 102616 Band Room Classroom 5/28/2013 11:00:29 AM Diaz, Sebastian Replace floor tiles in front entrace due to floor leak, east wall. 7 Nancy Tinajero 11/1/2012 215 Hadium Work In Progress Room 100- 5/28/2013 11:00:29 AM Diaz, Sebastian <th></th>	
Estrada, Jesus Repair snags on carpet, office, and inner rooms. Nancy Tinalero 5/28/2013 102822 Band Room Nancy Tinalero 5/28/2013 Ontiveros, Guadalupe Fill in gravel area sink holes. Nancy Tinalero 5/28/2013 102821 Band Room Ontiveros, Guadalupe Fill in gravel area sink holes. Nancy Tinalero 5/28/2013 102821 Band Room Classroom 5/28/2013 Nedium Work In Progress Band Room Clear weeds from front entrance before June 5 for summer band camp. Nancy Tinalero 5/28/2013 102823 Band Room Nancy Tinalero 5/28/2013 Nancy Tinalero 5/28/2013 Nancy Tinalero 7 102816 Band Room Classroom 5/28/2013 Nancy Tinalero 7 102816 Band Room Classroom 5/28/2013 Nancy Tinalero 7 94878 Annex Hallway/Corridor 11/1/2012 94878 Annex Hallway/Corridor 11/1/2012 94878 Annex Hallway/Corridor 11/1/2012 102601 Vo	\$0.00
Nancy Tinaljero 5/28/2013 7 1026222 Band Room 5/28/2013 7 Medium Work In Progress room 100- Band 5/28/2013 11:36:47 AM Ontiveros, Guadalupe Fill in gravel area sink holes. 7 Nancy Tinaljero 7 TO2621 Band Room 5/28/2013 11:35:48 AM Diaz, Sebastian Clear weeds from front entrance before June 5 for summer band camp. Nancy Tinajero 7 102621 Band Room 5/28/2013 11:37:32 AM Diaz, Sebastian Repair holes in the stucco front entrance. Nancy Tinajero 7 1026263 Band Room 5/28/2013 11:37:32 AM Diaz, Sebastian Repair holes in the stucco front entrance. Nancy Tinajero 7 102616 Band Room Classroom Vocational Classroom 5/28/2013 11:00:29 AM Diaz, Sebastian Replace floor tiles in front entrace due to floor leak, east wall. Nancy Tinajero 11/1/2012 215 Medium Work In Progress 11/1/1/2012 215 Medium Work In Progress 11/1/1/2012 215 Medium Work In Progress 11/1/1/2012 215 Juan Acosta 11/1/2012 7 11/1/2	
102622 Band Room 5/28/2013 7 Medium Work In Progress room 100- Band 5/28/2013 11:36:47 AM Ontiveros, Guadalupe Fill in gravel area sink holes. 7 Nancy Tinajero 7 102621 Band Room Classroom 5/28/2013 11:35:48 AM Diaz, Sebastian Clear weeds from front entrance before June 5 for summer band camp. 7 Nancy Tinajero 5/28/2013 11:37:32 AM 7 Medium Work In Progress room 100- Band 5/28/2013 11:37:32 AM Diaz, Sebastian Repair holes in the stucco front entrance. 7 Nancy Tinajero 7 7 Medium Work In Progress room 100- Band 5/28/2013 11:37:32 AM Diaz, Sebastian Repair holes in the stucco front entrance. 7 Nancy Tinajero 7 7 Medium Work In Progress Room 100- 5/28/2013 11:00:29 AM Diaz, Sebastian Replace floor tiles in front entrace due to floor leak, east wall. vall. Nancy Tinajero 11/1/2012 8:00:53 AM 215 Medium	
MediumWork In Progressroom 100- Band5/28/2013 11:36:47 AMOntiveros, GuadalupeFill in gravel area sink holes.Nancy Tinajero102621Band RoomClassroom5/28/2013 11:35:48 AMDiaz, SebastianClear weeds from front entrance before June 5 for summer band camp.7Nancy Tinajero10:0- Band5/28/2013 11:37:32 AMDiaz, Sebastianroom 100- Band5/28/2013 11:37:32 AMDiaz, Sebastianroom 100- Band5/28/2013 11:37:32 AMDiaz, Sebastianroom 100- Band5/28/2013 11:37:32 AMDiaz, SebastianRepair holes in the stucco front entrance.Nancy Tinajeroroom 100- Band5/28/2013 11:00:29 AMDiaz, SebastianReplace floor tiles in front entrace due to floor leak, east wall.Nancy Tinajeroroom 100-5/28/2013 11:00:29 AMDiaz, SebastianReplace floor tiles in front entrace due to floor leak, east wall.Nancy Tinajeroroom 100-11/1/2012 2.0153 AMDiaz, SebastianReplace floor tiles in front entrace due to floor leak, east wall.Nancy Tinajeroroom 11/1/2012 8:00:53 AMLozoya, MannyANNEX EXIT DOOR NEXT TO ROOM 407 WE UJUCCK AND CAN NOT OPEN DOORJuan Acostaright corner of classroom is rotted. Room 300- Possible Damage.Diaz, SebastianFar right corner of classroom is rotted. Room 300- Possible Damage.Nancy Tinajeroright corner of classroom is rotted. Room 300- Possible Damage.Nancy Tinajeroright corner of classroom is rotted. Room 300- Possible Damage. <tr< td=""><td></td></tr<>	
Ontiveros, Guadalupe Fill in gravel area sink holes. Nancy Tinajero 5/28/2013 102621 Band Room Classroom 5/28/2013 Medium Work In Progress Band Room S/28/2013 Diaz, Sebastian Clear weeds from front entrance before June 5 for summer band camp. Nancy Tinajero 5/28/2013 102623 Band Room Vork In Progress room 100- Band 5/28/2013 7 Medium Work In Progress Repair holes in the stucco front entrance. Nancy Tinajero 102616 Band Room Classroom 5/28/2013 Nancy Tinajero 102616 Band Room Classroom 5/28/2013 Nancy Tinajero 94776 Annex Hallway/Corridor 11/1/2012 9478 Annex Hallway/Corridor 11/1/2012 102601 Vocational Classroom 5/28/2013 102601 Vocational Classroom 5/28/2013 10270 Classroom 102807 Vocational Classroom 5/28/2013 102807 Classroom 102801 Som 301- V	\$0.00
Nancy Tinajero 5/28/2013 7 102621 Band Room Classroom 5/28/2013 11:35:48 AM Diaz, Sebastian Clear weeds from front entrance before June 5 for summer band camp. 5/28/2013 17 Nancy Tinajero	
102821Band RoomClassroom5/28/20137MediumWork In ProgressBand Room5/28/2013 11:35:48 AMDiaz, SebastianClear weeds from front entrance before June 5 for summer band camp.5/28/20137Nancy Tinajero	
Medium Work In Progress Band Room 5/28/2013 11:35:48 AM Diaz, Sebastian Clear weeds from front entrance before June 5 for summer band camp. Nancy Tinajero 102623 Band Room 5/28/2013 11:37:32 AM Medium Work In Progress room 100- Band 5/28/2013 11:37:32 AM Diaz, Sebastian Repair holes in the stucco front entrance. 7 Nancy Tinajero 102616 Band Room Classroom 5/28/2013 11:00:29 AM Diaz, Sebastian Replace floor tiles in front entrace due to floor leak, east wall. 7 Medium Work In Progress Room 100- 5/28/2013 11:00:29 AM Diaz, Sebastian Replace floor tiles in front entrace due to floor leak, east wall. 7 Nancy Tinajero 94878 Annex Hallway/Corridor 11/1/2012 8:00:53 AM Lozoya, Mamy ANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOOR 1 7 Juan Acosta 102610 Vocational Classroom 10- Voc 5/28/2013 9:48:37 AM Diaz, Sebastian Room 301- Voc 5/28/2013 9:48:37 AM 7 Diaz, Sebastian Far right corner of classroom is rotted. Room 300- Possible Damage.	\$0.00
Nancy Tinajero 5/28/2013 7 102623 Band Room 5/28/2013 1:37:32 AM Medium Work In Progress room 100- Band 5/28/2013 11:37:32 AM Diaz, Sebastian Repair holes in the stucco front entrance. Nancy Tinajero 102616 Band Room Classroom 5/28/2013 11:00:29 AM Diaz, Sebastian Replace floor tiles in front entrace due to floor leak, east wall. Nancy Tinajero 94878 Annex Hallway/Corridor 11/1/2012 215 Medium Work In Progress 11/1/2012 8:00:53 AM Lozoya, Manny ANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOOR Juan Acosta J02601 Vocational Classroom 5/28/2013 9:48:37 AM <td></td>	
102623 Band Room 5/28/2013 7 Medium Work In Progress room 100- Band 5/28/2013 11:37:32 AM Diaz, Sebastian Repair holes in the stucco front entrance. Nancy Tinajero	
Medium Work In Progress room 100- Band 5/28/2013 11:37:32 AM Diaz, Sebastian Repair holes in the stucco front entrance. Nancy Tinajero	\$0.00
Diaz, Sebastian Repair holes in the stucco front entrance. Nancy Tinajero 102616 Band Room Classroom 5/28/2013 7 Medium Work In Progress Room 100- 5/28/2013 11:00:29 AM 7 Diaz, Sebastian Replace floor tiles in front entrace due to floor leak, east wall. 7 Nancy Tinajero 94878 Annex Hallway/Corridor 11/1/2012 215 Medium Work In Progress 11/1/2012 8:00:53 AM 215 Lozoya, Manny ANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOOR 7 Juan Acosta 102601 Vocational Classroom 5/28/2013 7 Medium Work In Progress Room 301- Voc 5/28/2013 7 Medium Work In Progress Room 301- Voc 5/28/2013 7 Medium Work In Progress Room 301- Voc 5/28/2013 7 Diaz, Sebastian Far right corner of classroom is rotted. Room 300- Possible Damage. 7 Nancy Tinajero 102807 Vocational 5/31/2013 4 Medium Work In Progress 5/31/2013 8:31:00 AM 4	ψ0.00
Nancy Tinajero102616Band RoomClassroom5/28/20137MediumWork In ProgressRoom 100-5/28/2013 11:00:29 AMDiaz, SebastianReplace floor tiles in front entrace due to floor leak, east wall.11/1/2012215Nancy Tinajero94878AnnexHallway/Corridor11/1/2012215MediumWork In Progress11/1/2012 8:00:53 AM11/1/2012 8:00:53 AM11/1/2012 8:00:53 AMLozoya, MannyANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOOR11/1/2013 8:00:53 AM11/1/2012 8:00:53 AMJuan Acosta102601VocationalClassroom5/28/2013 9:48:37 AM11/1/2010 100000000000000000000000000000	
102616Band RoomClassroom5/28/20137MediumWork In ProgressRoom 100-5/28/2013 11:00:29 AMDiaz, SebastianReplace floor tiles in front entrace due to floor leak, east wall.1000 1000 1000 1000 1000 1000 1000 100	
Diaz, Sebastian Replace floor tiles in front entrace due to floor leak, east wall. Nancy Tinajero 11/1/2012 215 Medium Work In Progress 11/1/2012 8:00:53 AM Lozoya, Manny ANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOOR 11/1/2012 8:00:53 AM Juan Acosta 102601 Vocational Classroom 5/28/2013 7 Medium Work In Progress Room 301- Voc 5/28/2013 9:48:37 AM 102807 Vocational Far right corner of classroom is rotted. Room 300-Possible Damage. 5/31/2013 9:48:37 AM 102807 4 Macy Tinajero 5/31/2013 8:31:00 AM 5/31/2013 8:31:00 AM 102807 <td>\$0.00</td>	\$0.00
Nancy Tinajero 94878 Annex Hallway/Corridor 11/1/2012 215 Medium Work In Progress 11/1/2012 8:00:53 AM 215 Lozoya, Manny ANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOOR 11/1/2012 8:00:53 AM Juan Acosta UNLOCK AND CAN NOT OPEN DOOR 11/1/2012 8:00:53 AM Juan Acosta Classroom 5/28/2013 7 Medium Work In Progress Room 301- Voc 5/28/2013 9:48:37 AM 11/1/2012 Diaz, Sebastian Far right corner of classroom is rotted. Room 300-Possible Damage. 102807 Vocational 4 Medium Work In Progress 5/31/2013 8:31:00 AM 4	
94878AnnexHallway/Corridor11/1/2012215MediumWork In Progress11/1/2012 8:00:53 AMLozoya, MannyANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOORJuan Acosta	
Medium Work In Progress 11/1/2012 8:00:53 AM Lozoya, Many ANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOOR Juan Acosta 102601 Vocational Classroom Medium Work In Progress Room 301- Voc 5/28/2013 9:48:37 AM Diaz, Sebastian Far right corner of classroom is rotted. Room 300- Possible Damage. Nancy Tinajero 5/31/2013 8:31:00 AM	\$0.00
Lozoya, MannyANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOORJuan AcostaJuan Acosta102601VocationalOracionalClassroomMediumWork In ProgressRoom 301- Voc5/28/2013 9:48:37 AMDiaz, SebastianFar right corner of classroom is rotted. Room 300- Possible Damage.Nancy Tinajero102807VocationalWork In Progress5/31/2013 8:31:00 AM	φ0.00
102601VocationalClassroom5/28/20137MediumWork In ProgressRoom 301- Voc5/28/2013 9:48:37 AM7Diaz, SebastianFar right corner of classroom is rotted. Possible Damage.Room 300- Possible Damage.7Nancy Tinajero 102807Vocational5/31/20134MediumWork In Progress5/31/2013 8:31:00 AM5/31/2013 8:31:00 AM	
Medium Work In Progress Room 301- Voc 5/28/2013 9:48:37 AM Diaz, Sebastian Far right corner of classroom is rotted. Room 300- Possible Damage. Room 300- Possible Damage. Nancy Tinajero 102807 Vocational 4 Medium Work In Progress 5/31/2013 8:31:00 AM 4	\$0.00
Diaz, Sebastian Far right corner of classroom is rotted. Room 300- Possible Damage. <u>Nancy Tinajero</u> 102807 Vocational 5/31/2013 4 Medium Work In Progress 5/31/2013 8:31:00 AM	φ0.00
Possible Damage. Nancy Tinajero 5/31/2013 4 102807 Vocational 5/31/2013 4 Medium Work In Progress 5/31/2013 8:31:00 AM	
102807 Vocational 5/31/2013 4 Medium Work In Progress 5/31/2013 8:31:00 AM 4	
Medium Work In Progress 5/31/2013 8:31:00 AM	\$0.00
Cut sewer, water and electrical lines below floor grade and cap so that tile will be placed. thank you Michael Munoz	

WOID	ate Range for Request Building	Area	Deferred By	Until	-	Target Comp Date	Days Aged	Labor Hours	Costs
Priority	Status	Area Number	Reason	Creat	ed Date/Time	Actual Comp Date	Ageu	Hours	
Assigned		Description				Action Taken			
Requester	Name								
Location:	Gadsden	MS							
102602	Vocational	Kitchen			5/28/2013		7		\$0.00
Medium	Work In Progress	Room 301- Fo	bc	5/28/20)13 9:50:35 AM				
Diaz, Seba	astian		classroom to the left, the need to be replaced.	first station, th	ne sink				
Nancy Tina					= 10,100,100				<u> </u>
101815	Vocational				5/6/2013		29		\$0.00
Medium	Work In Progress			5/6/20)13 9:21:50 AM				
Estrada, Je	esus	classroom 308	(300-305) on south sid . Needs to be re-tiled eduled for the first wee	after abaten					
Alfredo Ho									
102629	Vocational	Classroom			5/28/2013		7		\$0.00
Medium	Work In Progress	Room 413		5/28/201	3 11:47:37 AM				
Diaz, Seba	astian	Please repaint	room.						
Nancy Tina									
101816	Vocational				5/6/2013		29		\$0.00
Medium	Work In Progress			5/6/20	013 9:23:23 AM				
Holguin, A	lfredo		floor tile in all classro Lobby and classroom		5) on				
Alfredo Ho	<u> </u>	Hallway/Carrid	o.r.		11/1/2012		215		\$0.00
94880	Gymnasium	Hallway/Corrid	01		11/1/2012		215		Ф 0.00
Medium	Work In Progress			11/1/20)12 8:14:11 AM				
Lozoya, M	anny	-	DOOR GOING IN GYN THE MULLION IS LOO		ХТ ТО				
	ta								

WOID Priority Assigned 7 Requester	Building Status Fo	Dates:7/1/2012 - 6/30/2013 Order By Loca Area Deferred By Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	La Union	ES					
100716			4/9/2013		56		\$0.00
Medium	Work In Progress		4/9/2013 9:01:03 AM				
Orozco, Da	aniel	DRAIN PIPE ON DISHWASHER KEI OFF. SNP MANAGER LINDA Y. 589					
Maritza Go 102781	nzalez		5/31/2013		4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:49 AM		·		<i>QOOOO</i>
Sanchez, F	•	Monthly - La Union ES - Monthly Met to PM schedule details.					
Margret Vil 102962	lalobos		6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:33 AM	0/0/2013	2		ψ0.00
Aguilar, Pa	-	Monthly - La Union ES Monthly FE In PM schedule details.					
Margret Vil	lalobos		E/22/2042		40		<u> </u>
102546		0105	5/23/2013		12		\$0.00
Medium Briones, Er	Work In Progress	GISD PO# 121304836 PLEASE DELIVER 400 BOOK BOXE ELEM. ATTN: INSTRUCTIONAL CO					
Lucia Alme 99220	eraz		3/3/2013		93		\$0.00
Medium	Work In Progress		3/3/2013 12:26:00 AM		93		φ0.00
Munoz, Mic	•	Yearly - La Union ES Fire Ext. Insp. (PM schedule details.					
Margret Vil	lalobos		0/04/0040	4/04/0040			.
100368			3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress		3/31/2013 12:33:24 AM				
Orozco, Da	aniel	Monthly - La Union ES Range Hood (PM schedule details.	Cleaning - Refer to				
Margret Vill 102774	lalobos		5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:46 AM	1/11/2010			φ0.00
Aguilar, Pa	•	Yearly - La Union ES A-2 Package U Refer to PM schedule details.	nit Elec Yearly -				
Margret Vil	lalobos			_ /2 / 2 2 / 2			<u> </u>
102856			6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:44 AM				
Aguilar, Pa	tricio	Yearly - La Union ES B-2 Boiler Year schedule details.	ly - Refer to PM				

WOID Priority Assigned		Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	La Union	ES						
101561				5/1/2013		34		\$0.00
Medium	Work In Progress			5/1/2013 1:29:19 PM	1			
Ambriz, Jo	se	need help with leak	4 water fountains t	he plastic connections				
Patricio Ag 101703	uilar			5/5/2013	5/13/2013	30		\$0.00
Medium	Work In Progress			5/5/2013 12:24:13 AM		50		ψ0.00
Aguilar, Pa	C C	Monthly - La Ui Refer to PM sc	nion ES Emer. Ligl hedule details.					
Margret Vil	lalobos							
98862				2/26/2013		98		\$0.00
Medium	Work In Progress			2/26/2013 9:21:41 AM	1			
Flores, Pet	e	need oil - filter	change - mower bl	ades for jd125				
Patricio Ag 102817	uilar			5/31/2013		4		\$0.00
Medium	Work In Progress			5/31/2013 10:55:36 AM				ψ0.00
Aguilar, Pa	-	wo to myself - r class rooms	remove choke bore	s - repair walls - paint				
Patricio Ag	uilar							
102818				5/31/2013		4		\$0.00
Medium	Work In Progress			5/31/2013 10:58:03 AM	1			
Aguilar, Pa		wo to myself - t ground	ake apart slide on	the big toy on play				
Patricio Ag 102819	Juilar			5/31/2013		4		\$0.00
Medium	Work In Progress			5/31/2013 11:00:16 AM	1			
Aguilar, Pa	-	wo to myself - r	move student drop	of area				
Patricio Ag		, , , , , , , , , , , , , , , , , , ,						
102924				6/2/2013		2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:16 AM	1			
Aguilar, Pa	tricio	Monthly - La Ui to PM schedule		Dryer (Monthly) - Refer				
Margret Vil 102930	lalobos			6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Prograss					2		φ0.00
	Work In Progress			6/2/2013 12:29:19 AM	1			
Aguilar, Pa	ITTICIO	Monthly - La Ui PM schedule d		nsp: Monthly - Refer to				
Margret Vil	lalobos							

	ate Range for Request Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Area Deferred By Area Number Reason Description	Location, Status	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Total Costs
Location:	La Union	ES					
102931			6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:19 AM				
Aguilar, Pa	atricio	Monthly - La Union ES Emer. Lig Refer to PM schedule details.	ht Test: Monthly -				
Margret Vi	llalobos						
102435			5/21/2013		14		\$0.00
Medium	Work In Progress		5/21/2013 12:53:41 PM				
Aguilar, Pa	atricio	wo to myself -need to trim trees f up - cut down dead tree in the ba chainsaw					
Patricio Ag	guilar						
102055			5/12/2013	5/28/2013	23		\$0.00
Medium	Work In Progress		5/12/2013 12:21:28 AM				
Aguilar, Pa	atricio	Monthly - La Union ES Playgrour schedule details.	nd Insp - Refer to PM				
Margret Vi							
Count: 19	Work Orders	Avg. Age of WO's	24	Total for La Unio	n ES	0	\$0.00

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Loma Lir	nda ES					
100653			4/7/2013	4/23/2013	58		\$0.00
Medium	Work In Progress		4/7/2013 12:19:06 AM	I			
Medina, Ei	ric	Monthly - Loma Linda ES Playgrou schedule details.	ind Insp - Refer to PM	Routed to Eric asp r	eassignm	ent 4/22/1	13
Margret Vi 103051	llalobos		6/4/2013		0		\$0.00
Medium	Work In Progress		6/4/2013 12:21:46 AM		Ũ		ψ0.00
		Monthly, Long Linds FO, Donne					
Apodaca, I Margret Vi		Monthly - Loma Linda ES - Domes Refer to PM schedule details.	tic Water Filters -				
102730	lialopos	Library	5/30/2013		5		\$0.00
Medium	Work In Progress	Library	5/30/2013 2:25:51 PM	I			
Medina, Ei		Lights in my office need to be repla in storage room need to be replace cover thats falling down in back on library near the windows.	ed. I have a light				
Angie Flore 100977	es	Athletic Field	4/16/2013		49		\$0.00
Medium	Work In Progress		4/16/2013 2:47:22 PM		-		
Medina, Ei	Ū.	Need to order and replace 13 I 25 and play ground					
Eric Medin	a		5/0/0040				<u> </u>
101963			5/9/2013		26		\$0.00
Medium Medina, Ei	Work In Progress ric	please clean around morgan buildi debri. (ie sand bags, tables, metal					
Michael M	unoz						
101964			5/9/2013		26		\$0.00
Medium	Work In Progress		5/9/2013 11:20:32 AM	l			
Medina, Ei	ric	please clean area where mobile ho you	ome used to be. thank				
Michael Mi 101138	unoz		4/22/2013		43		\$0.00
Medium	Work In Progress		4/22/2013 8:52:16 AM				<i>Q</i> 0 1 0 0
Medina, Ei	Ū.	need to weed and feed fields and r of weed and feed					
Eric Medin	a						A
102904			6/2/2013		2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:06 AM	l			
Medina, Ei		Monthly - Loma Linda ES Emer. Li Refer to PM schedule details.	ght Test: Monthly -				
Margret Vi							
6/4/2013 9	9:16:08 AM					Page 9	92 of 160

WOID Priority Assigned 7 Requester		Area Deferred By Area Number Reason Description	Until Request Date T Created Date/Time A	arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Loma Lir	ida ES					
102905			6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:07 AM				
Medina, Er	ic	Monthly - Loma Linda ES Exit S to PM schedule details.	Sign Insp: Monthly - Refer				
Margret Vil 102906	lalobos		6/2/2013		2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:07 AM		-		φ0.00
Medina, Er	C C	Monthly - Loma Linda ES - Clot Refer to PM schedule details.					
Margret Vil 101962	lalobos		5/9/2013		26		\$0.00
Medium	Work In Progress		5/9/2013 11:17:52 AM				• • • •
Ontiveros,	C C	when possible please level and around campus to include pine	scrape with tractor				
Michael Mu	lnoz		6/2/2012		- 1		¢0.00
103022			6/3/2013		1		\$0.00
Medium	Work In Progress		6/3/2013 3:56:48 PM				
Miranda, D	anny	need to replace sink counter to	o in rm 101				
Eric Medina 103023	а		6/3/2013		1		\$0.00
Medium	Work In Progress		6/3/2013 3:57:42 PM				
Miranda, D	-	need to replace sink counter to					
	-	need to replace sink counter to	5 11 111 202				
Eric Medina 103024	a		6/3/2013		1		\$0.00
Medium	Work In Progress		6/3/2013 3:58:30 PM				
Miranda, D	anny	need to replace sink counter to	o in rm 203				
Eric Medina	a						
103026			6/3/2013		1		\$0.00
Medium	Work In Progress		6/3/2013 3:59:19 PM				
Miranda, D	anny	need to replace sink counter to	o in rm 204				
Eric Medina	a						
103027			6/3/2013		1		\$0.00
Medium	Work In Progress		6/3/2013 4:00:07 PM				
Miranda, D	anny	need to replace sink counter to	o in rm 115				
Eric Medina	а						

WOID Priority Assigned T Requester		AreaDeferred ByUntilRequest DateArea NumberReasonCreated Date/TimeDescription	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Loma Lir	ida ES				
103028		6/3/2013		1		\$0.00
Medium	Work In Progress	6/3/2013 4:00:54 PM	l			
Miranda, Da	anny	need to replace sink counter top in rm 217				
Eric Medina	l		-///			
102776		5/31/2013		4		\$0.00
Medium	Work In Progress	5/31/2013 12:28:47 AM				
Medina, Eri		Yearly - Loma Linda ES A2 (Split System)(Yearly) - Refer to PM schedule details.				
<u>Margret Vill</u> 102858	alobos	6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress	6/2/2013 12:28:45 AM				·
Medina, Eri	Ū.	Yearly - Loma Linda ES B2 (Boiler)(Yearly) - Refer to PM schedule details.				
Margret Vill	alobos	Restroom (Boys) 1/24/2013		131		\$0.00
97624 Medium	Work In Progress	Restroom (Boys) 1/24/2013 1/24/2013 7:51:32 AM		131		Ф 0.00
Villalobos, [David	please replace all granite wash basins in restrooms with stainless steal basins. the existing ones are in poor conditions. thankyou	Route to David asp	reassigni	ment 4/2/1	3
<u>Michael Mu</u> 102164	noz	5/14/2013		21		\$0.00
Medium	Work In Progress	5/14/2013 12:38:05 PM		21		ψ0.00
	-					
Solis, Loren		Lorenzo need for you to install new a/c in portable 3				
<u>Eric Medina</u> 101835	l	Athletic Field 5/6/2013		29		\$0.00
Medium	Work In Progress	5/6/2013 3:08:35 PM	I			
Ontiveros, (Guadalupe	Lupe would like to request small tractor and two loads of top soil for soccer field				
Eric Medina	L					
100731		4/9/2013		56		\$0.00
Medium	Work In Progress	4/9/2013 12:02:20 PM				
Lozoya, Ma	nny	eric medina will be assigned to loma-linda effetive 4-10- 13, please turn over rudys keys and assign to eric. also please have eric turn in keys for sunland park thank you				
Michael Mu	noz	2/04/0040	4/04/0040	65		¢0.00
100369 Madium		3/31/2013 2/21/2012 12:22:25 AM		65		\$0.00
Medium	Work In Progress	3/31/2013 12:33:25 AM	I			
Orozco, Da		Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.				
Margret Vill						
5/4/2013 9	16:08 AM				Page 9	94 of 160

Munoz, Michael Margret Villalobo 102979 Medium Wor Medina, Eric <u>Margret Villalobo</u> 102529	rk In Progress	da ES Yearly - Loma Linda ES Fire Ext. Insp to PM schedule details. Monthly - Loma Linda ES Monthly FE	3/3/2013 3/3/2013 12:26:00 AM b. (Yearly) - Refer 6/2/2013		93		\$0.00
Medium Wor Munoz, Michael <u>Margret Villalobo</u> 102979 Medium Wor Medina, Eric <u>Margret Villalobo</u> 102529 Medium Wor Briones, Enrique	rk In Progress	to PM schedule details.	3/3/2013 12:26:00 AM b. (Yearly) - Refer		93		\$0.00
Munoz, Michael <u>Margret Villalobo</u> 102979 Medium Wor Medina, Eric <u>Margret Villalobo</u> 102529 Medium Wor Briones, Enrique <u>Lucia Almeraz</u>	rk In Progress	to PM schedule details.	o. (Yearly) - Refer				
Margret Villalobo 102979 Medium Wor Medina, Eric Margret Villalobo 102529 Medium Wor Briones, Enrique	rk In Progress	to PM schedule details.					
102979 Medium Wor Medina, Eric <u>Margret Villalobo</u> 102529 Medium Wor Briones, Enrique Lucia Almeraz	rk In Progress	Monthly - Loma Linda ES Monthly FF	6/2/2013				
Medium Wor Medina, Eric <u>Margret Villalobo</u> 102529 Medium Wor Briones, Enrique Lucia Almeraz		Monthly - Loma Linda ES Monthly FF		6/8/2013	2		\$0.00
Medina, Eric <u>Margret Villalobo</u> 102529 Medium Wor Briones, Enrique Lucia Almeraz		Monthly - Loma Linda ES Monthly FF	6/2/2013 12:29:40 AM		_		
102529 Medium Wor Briones, Enrique Lucia Almeraz	00S	to PM schedule details.					
Medium Wor Briones, Enrique Lucia Almeraz			E/00/0040				
Briones, Enrique			5/23/2013		12		\$0.00
	rk In Progress e	GISD PO# 121304836 PLEASE DELIVER 400 BOOK BOXE LINDA ELEM. ATTN: INSTRUCTIONAL COACH	5/23/2013 2:53:14 PM S TO LOMA				
102101			5/30/2013		5		\$0.00
Medium Wor	rk In Progress		5/30/2013 3:11:59 PM		-		
Carrasco, Danny	C C	Danny need to request traile to dispose and metal around morgan building that	se of broken tables				
Eric Medina			4/30/2013		35		\$0.00
	rk In Progress		4/30/2013 3:37:35 PM		55		ψ0.00
Orozco, Daniel	ik in rogress	DEVICE ON DOORS FOR FLIES IS SNP MANAGER FRANCES B. 882.4	NOT WORKING.				
Maritza Gonzale	ez						
101544			5/1/2013		34		\$0.00
Medium Wor	rk In Progress		5/1/2013 8:56:13 AM				
Orozco, Daniel		WALK IN NOT WORKING PROPERI MANAGER FRANCES B. 882.4707	Y. SNP				
Maritza Gonzale 96001 Mair	ez in Building	Parking Lot	11/30/2012		186		\$0.00
	rk In Progress		11/30/2012 11:37:03				
Medina, Eric		As per Mr. Lawler please repaint the t		4/22/13 Asp reassig	nement -	- routed to	Eric
Angie Flores							
	in Building	Portables	5/29/2013		6		\$0.00
Medium Wor	rk In Progress	Portable	5/29/2013 2:38:58 PM				
Lozoya, Manny		Door Closer was loose, needs to be a	idiusted				

6/4/2013 9:16:08 AM

Assigned To Requester M Location: 97008	Name Loma Lin Main Building Work In Progress	Area Number Reason Description da ES Classroom As per our principal we need 6 ke door to the main building. Keys Quintero, Gonzalez, Luna and S able to only open one of the bac	1/8/2013 1/8/2013 10:10:55 AM eys to open the back are for Morris, Martinez, teinert. Keys will be	Comp Date Days Comp Date Aged Fon Taken	Hours	\$0.00
Assigned To Requester N Location: 97008 Medium	Name Loma Lin Main Building Work In Progress	da ES Classroom As per our principal we need 6 k door to the main building. Keys Quintero, Gonzalez, Luna and S	1/8/2013 1/8/2013 10:10:55 AM eys to open the back are for Morris, Martinez, teinert. Keys will be			\$0.00
Location: 97008 Medium	Loma Lin Main Building Work In Progress	Classroom As per our principal we need 6 k door to the main building. Keys Quintero, Gonzalez, Luna and S	1/8/2013 10:10:55 AM eys to open the back are for Morris, Martinez, teinert. Keys will be	147		\$0.00
97008 Medium	Main Building Work In Progress	Classroom As per our principal we need 6 k door to the main building. Keys Quintero, Gonzalez, Luna and S	1/8/2013 10:10:55 AM eys to open the back are for Morris, Martinez, teinert. Keys will be	147	Ś	\$0.00
Medium	Work In Progress	As per our principal we need 6 k door to the main building. Keys Quintero, Gonzalez, Luna and S	1/8/2013 10:10:55 AM eys to open the back are for Morris, Martinez, teinert. Keys will be	147	Ş	\$0.00
	Ũ	door to the main building. Keys Quintero, Gonzalez, Luna and S	eys to open the back are for Morris, Martinez, teinert. Keys will be			
Lozoya, Mai	nny	door to the main building. Keys Quintero, Gonzalez, Luna and S	are for Morris, Martinez, teinert. Keys will be			
		master key!	k main doors. Not a			
Angie Flores	S					
101414	Main Building	Office	4/29/2013	36	ç	\$0.00
Medium	Work In Progress	Office	4/29/2013 2:27:45 PM			
Medina, Eric	c	Build two office desks and two fil	e cabinets			
Angie Flores						
99903	Main Building	Hallway/Corridor	3/20/2013	76	ç	\$0.00
Medium	Work In Progress		3/20/2013 9:07:02 AM			
Estrada, Jes	sus	SPOKE TO CHUY CARPET ON INSTALLED ABOUT A 2 YEARS RIP.				
Rudy Arreol		Hollwoy/Corridor	3/20/2013	76		\$0.00
	Main Building	Hallway/Corridor		76		Ф 0.00
Medium	Work In Progress		3/20/2013 9:08:40 AM			
Estrada, Jes	sus	SPOKE TO CHUY BASEBOARD ON HALF OF SCHOOL WOULD OTHER HALF OF SCHOOL. TH BAD SHAPE COMING UNGLUE	LIKE TO DO THE EY ARE IN REALLY			
Rudy Arreol	а		1/00/0040			<u></u>
101526			4/30/2013	35	2	\$0.00
Medium	Work In Progress		4/30/2013 4:16:54 PM			
Villalobos, D	David	Asp PM Inspection by Dimar - m pipe.	ain drain has a crack in			
Michael Mur	noz Vork Orders	Avg. Age of WO's		Loma Linda ES	0 9	\$0.00

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Location, Status Area Deferred By Until Request Date Tail Area Number Reason Created Date/Time A Description Created Date/Time A	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Mesquite	ES				
101814	Main Building	5/6/2013		29		\$0.00
Medium	Work In Progress	5/6/2013 9:17:59 AM				
Estrada, Je	esus	Book Room 107 . Needs to be re-tiled after tentatively scheduled for the first week in June.				
<u>Alfredo Ho</u> 89436	lguin	7/1/2012	8/1/2012	338		\$0.00
Medium	Work In Progress	7/1/2012 12:30:58 AM				
Ramirez, J	C C	Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.				
Margret Vi 101212	llalobos	4/23/2013		42		\$0.00
Medium	Work In Progress	4/23/2013 1:27:41 PM		12		ψ0.00
Orozco, Da	· ·	WALK IN FREEZER TEMP IS GOING UP.				
Maritza Go	onzalez					
102009		5/10/2013		25		\$0.00
Medium	Work In Progress	5/10/2013 10:18:13 AM				
Orozco, Da		SLICER IS LOOSING DRIVE SHIFT.SNP MANAGER VIRGINIA P. 233.2341				
Maritza Go 101755	onzalez	5/5/2013		30		\$0.00
Medium	Work In Progress	5/5/2013 12:24:34 AM				
Sanchez, I	C C	Monthly - Mesquite ES - Lift Station Inspection - Refer				
Margret Vi	llalobos					
99268		3/3/2013		93		\$0.00
Medium	Work In Progress	3/3/2013 12:26:21 AM				
Sanchez, I		Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.				
Margret Vi 102829	llalobos	5/31/2013		4		\$0.00
Medium	Work In Progress	5/31/2013 3:09:29 PM				
Lara, Ralp	h	need to have lobby partition moved back 14'				
Joe Ramir	ez					
102963		6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:33 AM				
Ramirez, J	loe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.				
Margret Vi	llalohos					

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Location, Status Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time Ar Description Description	•	Days Labor Aged Hours	Costs
Location:	Mesquite	ES			
97808		1/29/2013		126	\$0.00
Medium	Work In Progress	1/29/2013 8:06:10 AM			
Lozoya, M	lanny	bathroom partitions north and south ,boys' and girls' bathrooms need to be replaced			
Joe Ramir	ez	4/40/0040		100	¢0.00
97385		1/16/2013		139	\$0.00
Medium	Work In Progress	1/16/2013 8:51:53 AM			
Lozoya, M	lanny	door handle rm.229 not working properly nneds to be replaced			
Joe Ramir 95365	ez	11/9/2012		207	\$0.00
				201	ψ0.00
Medium	Work In Progress	11/9/2012 1:09:02 PM			
Lozoya, M	lanny	sothside boys and girls bathroom stalls need to be replaced the floor securing brackets are either broken or rusted through and also most of the stalls are very rusted			
Joe Ramir	ez				.
96318		12/6/2012		180	\$0.00
Medium	Work In Progress	12/6/2012 1:02:43 PM			
Briones, E	nrique	please Warehouse ATT: LARRY MARTINES we have broken computer desk, old furniture, student desk broken, etc. thank you			
Luis Sauce	edo	3/3/2013		93	\$0.00
				93	Ф 0.00
Medium	Work In Progress	3/3/2013 12:26:01 AM			
Munoz, Mi		Yearly - Mesquite ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.			
Margret Vi 100370	illalobos	3/31/2013	4/21/2013	65	\$0.00
Medium	Work In Progress	3/31/2013 12:33:25 AM			+0.00
Orozco, Da	Ū	Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.			
Margret Vi	illalobos				
99530		3/11/2013		85	\$0.00
Medium	Work In Progress	3/11/2013 8:38:39 AM			
Lozoya, M	lanny	door knob in rm. 112 will not lock needs to be replaced (lock down) and door wouldn,t lock.			

WOID Priority Assigned ⁻ Requester		Area Deferred By U Area Number Reason Description	ion, Status Jntil Request Date Ta Created Date/Time A	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Mesquite	ES					
98511			2/14/2013		110		\$0.00
Medium	Work In Progress		2/14/2013 9:17:23 AM				
Lozoya, Ma		AS PER MR. BAKER, HIS MASTER K (BACKDOOR) DID NOT WORK AT MI HIS UNDERSTANDING WAS THAT H SHOULD BE ABLE TO OPEN ALL KIT PLEASE ADVISE.	ESQUITE ELEM. IS MASTER				
Maritza Go 97630	nzalez		1/24/2013		131		\$0.00
Medium	Work In Progress		1/24/2013 8:50:56 AM				
Lozoya, Ma		i need 4 padlocks for the new gates the installed					
Joe Ramire 102864	ez		6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:47 AM	1/0/2010	-		\$0.00
Ramirez, J	-	Yearly - Mesquite ES B-2 Boiler Yearly schedule details.					
Margret Vil 102772	lalobos		5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:45 AM	1/1/2013	-		ψ0.00
Ramirez, J	-	Yearly - Mesquite ES A-2 Electric Heat PM schedule details.					
Margret Vil 102827	lalobos		5/31/2013		4		\$0.00
Medium	Work In Progress		5/31/2013 2:55:53 PM		-		ψ0.00
Lara, Ralph	-	we need over head latches for cafeteri					
<i>,</i> ,		we need over nead latenes for caleten	a uoors.				
<u>Joe Ramire</u> 103015	32		6/3/2013		1		\$0.00
Medium	Work In Progress		6/3/2013 2:33:01 PM				
Lara, Ralpł	1	REPLACE KEY FOR KITCHEN, BENT SNP SUMMER SITE SUPERVISOR M FONG.					
Maritza Go	nzalez		5/15/2013		20		\$0.00
102208 Medium	Work In Progress		5/15/2013 9:39:04 AM		20		ψ0.00
		need to very sint was 044.040 (
Ramirez, J	oe	need to repaint rms.611,612 (vanilla b	ean)				

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date T Created Date/Time A	arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Mesquite	ES					
102209			5/15/2013		20		\$0.00
Medium	Work In Progress		5/15/2013 9:40:58 AM				·
Ramirez, .	Ū	need to touch west wall in rm.204 (int cl2262w)	o the mystic				
Joe Ramir	ez		4/44/0040				\$ 0.00
97179			1/11/2013		144		\$0.00
Medium	Work In Progress		1/11/2013 3:47:35 PM				
Ramirez, .	Joe	please paint doors to portable 611 &	612. thank you				
Selma Nev 102852	varez		6/2/2013		2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:42 AM		-		Q
	0	Monthly Manguita ES Parroak Drai					
Ramirez, .	JOE	Monthly - Mesquite ES - Barrack Drai Refer to PM schedule details.	nage (Monuniy) -				
Margret Vi 103003	illalobos		6/3/2013		1		\$0.00
					I		ψ0.00
Medium	Work In Progress		6/3/2013 12:03:51 PM				
Villalobos,	, David	angle stop on water fountain 100 wing replaced.	g needs to be				
Joe Ramir 103004	ez		6/3/2013		1		\$0.00
					I		ψ0.00
Medium	Work In Progress		6/3/2013 12:05:48 PM				
Sotelo, En		we need an electric outlet installed in the ceiling for the smartboards	rms.611.,612 from				
Joe Ramir 102941	ez		6/2/2013		2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:23 AM				•
Ramirez,	-	Monthly - Mesquite ES - Clothes Drye					
Morgrot \/	illalahaa	to PM schedule details.					
Margret Vi 102942	IIIaiodos		6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:24 AM				
Ramirez,	Joe	Monthly - Mesquite ES Exit Sign Insp PM schedule details.	: Monthly - Refer to				
Margret Vi	illalobos			0/40/0040			<u> </u>
102943			6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:24 AM				
Ramirez,	Joe	Monthly - Mesquite ES Emer. Light To to PM schedule details.	est: Monthly - Refer				

WOID Priority	Building Status	Area Deferred By Until Request Date Area Number Reason Created Date/Time	Target Comp Date	Days Aged	Labor Hours	
Assigned		Description	Action Taken			
Requester						
Location:	Mesquite	ES				
95182		Athletic Field 11/5/2012		211		\$0.00
Medium	Work In Progress	11/5/2012 3:27:39 PM				
Ramirez, J	loe	As per mr. Mike need to in stall irrigation system on playing fields.				
	e Ontiveros	0/20/2012		288		¢0.00
91551		8/20/2012		200		\$0.00
Medium	Work In Progress	8/20/2012 12:50:51 PM				
Ramirez, J	loe	need to install frp panel in rms. 801,802.				
<u>Joe Ramir</u> 99968	ez	3/21/2013		75		\$0.00
Medium	Work In Progress	3/21/2013 6:27:23 AM				
Holguin, A	lfredo	ATTN alfredo h. bookroom (rm. 107) needs to be abated				
Joe Ramir	ez	0/4/0040		0		#0.00
103049		6/4/2013		0		\$0.00
Medium	Work In Progress	6/4/2013 12:21:45 AM				
Apodaca, I	Mario	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.				
<u>Margret Vi</u> 102787	llalobos	5/31/2013		4		\$0.00
				-		ψ0.00
Medium	Work In Progress	5/31/2013 12:28:52 AM				
Apodaca, I		Monthly - Mesquite ES - Monthly Meter Readings - Refer to PM schedule details.				
<u>Margret Vi</u> 102956	llalobos	6/2/2013		2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:30 AM		£		ψ0.00
Sanchez, I	Ū	Monthly - Mesquite ES - Lift Station Inspection - Refer				
Mana () (U-l-h	to PM schedule details.				
Margret Vi	llalobos Work Orders	Avg. Age of WO's 69	Total for Mesquit	e FS	0	\$0.00

WOID Priority Assigned	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Locat Area Deferred By Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	North Va	lley ES					
101977			5/9/2013		26		\$0.00
Medium	Work In Progress		5/9/2013 3:37:09 PM				
Vega, Dan	ny	5-9-13 1-ck heat pumps at nve 1-ck ice maker at nve kitchen/clean filt 1-wk od#101769 1-wk od#101770 1-wk od#101736 1-wk od#101737 1-wk od#101738 1-wk od#101739	er				
Danny Veg 102885	ja		6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:58 AM	0,10,2010	-		\$0.00
Vega, Dan	-	Monthly - North Valley ES Exit Sign In Refer to PM schedule details.					
Margret Vil 102902	lalobos		6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:05 AM	0, 10, 2010	-		<i>Q</i>
Vega, Dan	C C	Monthly - North Valley ES Emer Light Refer to PM schedule details.	Test: Monthly -				
Margret Vil 100306	lalobos		3/31/2013		65		\$0.00
Medium	Work In Progress		3/31/2013 12:32:59 AM		00		ψ0.00
Holguin, Al	-	Monthly - North Valley ES - Fire Pump PM schedule details.					
Margret Vil 103014	lalobos		6/3/2013		1		\$0.00
High	Work In Progress		6/3/2013 2:26:26 PM				ψ0.00
Munoz, Mic	-	parapet cap was blown off due to high as a warranty and as per r.gallegos it i warranty. danny vega fastened it back be replaced and new one needs to go	winds. submitted is not under , but cap needs to				
Michael Mu 101154	unoz		4/22/2013		43		\$0.00
Medium	Work In Progress	Playground	4/22/2013 10:21:35 AM				÷ 0.00
	Guadalupe	need plygrd sand at nve (2)loads.plz					
Danny Veg	-						
101971			5/9/2013		26		\$0.00
Medium	Work In Progress		5/9/2013 2:23:27 PM				
	Guadalupe	need three shade tree /need to replant plygrd area.when available	t dried out trees at				
Danny Veg	Ja						

6/4/2013 9:16:08 AM

Selected Da WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2012 - 6/30/2013 Order By Loc Area Deferred By Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	North Va	lley ES					
102723		Office	5/30/2013		5		\$0.00
Medium	Work In Progress	400	5/30/2013 9:29:03 AM				
Sotelo, Enr	ique	Please send Electrician to install 2 o security monitor for the cameras.	utlets for the				
Priscilla Ma 102764	artinez		5/31/2013		4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:42 AM				·
Vega, Danı	ny	Monthly - North Valley ES A16 (Fan Refer to PM schedule details.	Exhst)(S.Ann.) -				
Margret Vil 102765	lalobos		5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:42 AM				·
Vega, Danı	-	Yearly - North Valley ES A2 (H/C Ur PM schedule details.	it)(Yearly) - Refer to				
Margret Vil 102320	lalobos		5/20/2013		15		\$0.00
Medium	Work In Progress		5/20/2013 8:47:53 AM		10		ψ0.00
Vega, Dani	-	need to paint rms at nve/order paint	0,20,2010 0.11.00 / 44				
Danny Veg	-						
102875	ŭ		6/2/2013	6/23/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:53 AM				
Vega, Danı	ny	Monthly - North Valley ES H11(E.He Refer to PM schedule details.	at)(S.Annual) -				
Margret Vil 99297	lalobos		3/4/2013		92		\$0.00
Medium	Work In Progress		3/4/2013 11:44:56 AM		-		
Lozoya, Ma	-	need a chain for a walking gate that					
Javier Parr	-	nood a chair for a training gate that					
94886	u		11/1/2012		215		\$0.00
Medium	Work In Progress		11/1/2012 10:47:05 AM				
Lozoya, Ma	anny	door in between techers lounge and	hallway wont close.				
Javier Parr	а		4/45/0040				<u> </u>
97366			1/15/2013		140		\$0.00
Medium	Work In Progress		1/15/2013 3:53:46 PM				
Lozoya, Ma Danny Veg	-	need help to secure front entance do jammed /will not lock plz help	oor/divider bar core				

WOID Priority Assigned 1 Requester	Building Status Fo	-	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	North Va	ley ES					
89953			7/18/2012		321		\$0.00
Medium	Work In Progress	7/18/201	2 10:38:49 AM	l			
Lozoya, Ma	anny	need exterior security door handle plates installed 107-108-211-212-309-310 doors to keep vandals prying doors open as per MR. T					
Danny Veg 101253	a	Classroom	4/23/2013		42		\$0.00
Medium	Work In Progress)13 4:04:00 PN				\$0.00
	Ū		713 4.04.00 1 10	I			
Lozoya, Ma	anny	Replacement keys and lock on classroom doors, exterior and interior.					
Priscilla Ma	artinez	<u>.</u>	- / / /				
91740		Classroom	8/23/2012		285		\$0.00
Medium	Work In Progress	various 8/23/201	12 10:11:46 AM				
Lozoya, Ma	-	Need to obtain additional cabinet keys for certain classrooms.					
Priscilla Ma 100380	artinez		3/31/2013		65		\$0.00
Medium	Work In Progress	3/31/201	3 12:33:29 AM	I			·
Orozco, Da	•	Monthly - North Valley ES - Range Hood Cleaning Refer to PM schedule details.	g -				
Margret Vill	lalobos		0 10 10 0 1 0				* •••••
99223			3/3/2013		93		\$0.00
Medium	Work In Progress	3/3/201	13 12:26:01 AM				
Munoz, Mic		Yearly - North Valley ES Fire Ext. Insp. (Yearly) - to PM schedule details.	Refer				
Margret Vill 102977	lalobos		6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress	6/2/201	I3 12:29:40 AM				·
Vega, Danr	•	Monthly - North Valley ES Monthly FE Inpsection to PM schedule details.					
Margret Vill	lalobos						
102008			5/10/2013		25		\$0.00
Medium	Work In Progress	5/10/201	13 10:17:24 AM				
Orozco, Da		ICE MACHINE IS NOT WORKING. SNP MANAG LAURA B. 233.3658	ER				
Maritza Go 100670	nzalez		4/8/2013		57		\$0.00
High	Work In Progress	4/8/201	13 10:18:56 AM				÷ 0.00
Munoz, Mic	-	fire pump alarm is on. low battieries. need to repa thankyou					
Yolie Jacqu				Total far bland Mart			<u> </u>
Count: 23	Work Orders	Avg. Age of WO's 67		Total for North Valle	y ES	0	\$0.00

WOID Priority Assigned	ate Range for Request Building Status To	Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time /	Target Comp DateActual Comp DateAction Taken	Days Aged	Labor Hours	Costs
Requester	Name							
Location:	Northern	On-Track Pre-K	(LM)					
102718	Main Building	Mechanical		5/30/2013		5		\$0.00
Medium	Work In Progress			5/30/2013 8:04:16 AM				
Gonzalez,	Salvador	please re-pipe l circulating pum	hydronic water sys ps.	tem, for boiler				
<u>Lorenzo S</u> 101466	olis Main Building			4/30/2013		35		\$0.00
Medium	Work In Progress			4/30/2013 8:13:54 AM		00		ψ0.00
Solis, Lore	· ·		ROM PIPES RUN	NING ALONG				
<u>Adam Mor</u> 100833	ntoya			4/11/2013		54		\$0.00
Medium				4/11/2013 10:54:47 AM		54		φ0.00
Lara, Ralp	Work In Progress	hinge-door is s		e (off-alignment)at top hinge will not hold .plz				
Danny Veo 102978	ga			6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:40 AM				
Vega, Dan	iny	Monthly - La Me PM schedule de		Inpsection - Refer to				
Margret Vi 99238	llalobos			3/3/2013	3/14/2013	93		\$0.00
Medium				3/3/2013 12:26:08 AM	3/14/2013	93		φ0.00
Munoz, Mi	Work In Progress chael	Yearly - Northe to PM schedule		Insp. (Yearly) - Refer				
Margret Vi	llalobos							
102872				6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:28:51 AM				
Vega, Dan	-	Yearly - Northe PM schedule de		r)(Yearly) - Refer to				
Margret Vi 102319	llalobos			5/20/2013		15		\$0.00
Medium	Work In Progress			5/20/2013 8:46:51 AM				
Vega, Dan	Ũ	need to paint m	ns at Im pre-k /ord					
Danny Veg	•							
103039	ya			6/3/2013		1		\$0.00
Medium	Work In Progress			6/3/2013 4:25:20 PM				
Solis, Luis		need to replace	to circulating pur	p to boiler. thank you				
Michael M	1007							

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Northern	On-Track Pre-K (LM)					
102457			5/22/2013		13		\$0.00
Medium	Work In Progress		5/22/2013 7:04:53 AM				
Lara, Ralp	h	NEED A LOCK FOR NW GATE BE	HIND BUILDING.				
Adam Mor	ntoya		5/4.4/00.40				* •••••
102167			5/14/2013		21		\$0.00
Medium	Work In Progress		5/14/2013 2:31:42 PM				
Lara, Ralp		NEED TO RE-ISSUE A NEW KEY DISPOSAL HAS NOT BEEN SERV THIS SIT, KEY IS NOT WORKING	ICING TRASH AT				
Jesus Estr 102762	rada		5/31/2013		4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:41 AM				·
Vega, Dar	Ŭ	Monthly - Northern Pre-K A16(Fan Refer to PM schedule details.					
Margret Vi 102763	llalobos		5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress		5/31/2013 12:28:42 AM				ψ0.00
Vega, Dan	Ū	Yearly - Northern Pre-K A2 (H/C U PM schedule details.					
Margret Vi	llalobos		6/2/2013	6/23/2013	2		\$0.00
102873 Medium	Work In Progress		6/2/2013 12:28:52 AM		Z		φ0.00
	-						
Vega, Dan	iny	Monthly - Northern Pre-K C12-Che Refer to PM schedule details.	m.Feeder(S.Annual) -				
Margret Vi	llalobos		6/2/2013	6/23/2013	2		\$0.00
102874 Medium			6/2/2013 12:28:52 AM		2		φ0.00
Vega, Dar	Work In Progress	Monthly - Northern Prek H11(E.Heat to PM schedule details.					
Margret Vi	llalobos		- / / /				* • • • •
100012			3/22/2013		74		\$0.00
Medium	Work In Progress		3/22/2013 7:46:06 AM				
Villalobos,	David	need help in installing irrigation line soccer field spklrs 1 1/2 inch line.p to dig		Route to David asp	reassignn	nent 4/2/1	3
Danny Veg 100497	ga		4/3/2013		62		\$0.00
Medium	Work In Progress		4/3/2013 2:32:54 PM		52		ψ0.00
	Guadalupe	NEED LANDSCAPING PROJECT BUILDING COMPLETED THAT W. THE BEGINNING OF THE SCHOO	IN FRONT OF AS STARTED AT				
Adam Mor	ntoya 9:16:08 AM						
04/2013	9. 10.00 AIVI					Page 1	06 of 160

WOID	Building Status	Area Area Number	Deferred By	Until	-	Farget Comp Date	Days Aged	Labor Hours	
Priority Assigned	Status To	Description	Reason	Crea	ted Date/Time P	Actual Comp Date Action Taken	, gee	neuro	
Requester		Description				ACTION TAKEN			
•			<pre>// ha></pre>						
Location:	Northern	On-Track Pre-M	(LM)						
102903					6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/20	13 12:29:06 AM				
Vega, Dan	ny	Monthly - La M to PM schedule	esa ES Emer. Ligh e details.	t Test: Monthly	- Refer				
Margret Vi 102901	llalobos				6/2/2013	6/10/2013	2		\$0.00
				- (- (0/10/2013	2		φ0.00
Medium	Work In Progress			6/2/20	13 12:29:05 AM				
Vega, Dan	ny	Monthly - La M PM schedule d	esa ES Exit Sign In etails.	isp: Monthly - F	Refer to				
Margret Vi 102429	llalobos				5/21/2013		14		\$0.00
Medium	Work In Progress			5/21/2	013 7:57:57 AM				φ0.00
	C C			5/21/2	0137.37.37 AW				
Ontiveros,	Guadalupe	NEED WIND S (350 FT).	CREEN REPLACE	D BEHIND BU	ILDING				
Adam Mor 103048	ntoya				6/4/2013		0		\$0.00
							0		φ0.00
Medium	Work In Progress			6/4/20	13 12:21:45 AM				
Apodaca,	Mario	Monthly - North Refer to PM sc	ern Pre-K- Domest hedule details.	ic Water Filters	3 -				
Margret Vi	llalobos				5/31/2013		4		\$0.00
102786							4		Ф 0.00
Medium	Work In Progress			5/31/20	13 12:28:51 AM				
Apodaca,	Mario	Monthly - North Refer to PM sc	nern Pre-K - Monthl hedule details.	y Meter Readir	ngs -				
Margret Vi									
Count: 21	Work Orders	A	vg. Age of WO's	20 -	Total for Northe	rn On-Track Pre-K	(LM)	0	\$0.00

WOID Priority Assigned ⁻ Requester		•	•	Days Labor Aged Hours	
Location:	Physical	Plant Complex			
102922		6/2/201	3	2	\$0.00
Medium	Work In Progress	6/2/2013 12:29:15 A	Μ		
Carbajal, J	limmy	Monthly - Physical Plant - Clothes Dryer (Monthly) - Refer to PM schedule details.			
Margret Vil	llalobos	E/20/204	2	F	¢0.00
102712		5/30/201		5	\$0.00
Medium	Work In Progress	5/30/2013 12:22:48 A	M		
Holguin, Al		Yearly - PPD - Maintenance Plan - Refer to PM schedule details.			
Margret Vil 102893	llalobos	6/2/201	3	2	\$0.00
Medium	Work In Progress	6/2/2013 12:29:01 A	M		
Ruiz, Maria	-	Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.			
Margret Vil	llalobos	0/20/201	0	057	\$0.00
93067		9/20/201		257	\$0.00
Medium	Work In Progress	9/20/2012 10:51:22 A			
Ronquillo,	Ruben	as per meeting held, please dispose of any unused material and clean and organize barracks. thank you.	Continuing from 6868	5	
Michael Mu 101648	unoz	5/3/201	3	32	\$0.00
		5/3/2013 11:05:38 A		52	ψ0.00
High	Work In Progress		IVI		
	Guadalupe	dump truck is down for repairs. need to rent one for 3 weeks for grounds department district wide.			
Michael Mu 99678	unoz	3/13/201	3	83	\$0.00
Medium	Work In Progress	3/13/2013 4:13:34 P	M		
Ontiveros,	Guadalupe	please install sprinkler system in ppd park(conserve water) thank you			
Michael Mu	unoz		_		
95523		Parking Lot 11/14/201	2 2	202	\$0.00
Medium	Work In Progress	11/14/2012 2:39:27 P	M		
Ontiveros,	Guadalupe	Parking Area on south side of fence between warehouse and GMS Annex - Install parking stops along fence and around fire hydrant to provide enough clearance around hydrant and next to fence.			
	Iguin				

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex					
101188			4/22/2013		43		\$0.00
Medium	Work In Progress		4/22/2013 4:10:33 PM	l			
Ontiveros,	Guadalupe	please relocte material (i.e, gravel, s etc) by warehouse barracks for new built. see mike for details. thank you	snp barrack to be				
<u>Michael M</u> 101189	unoz		4/22/2013		43		\$0.00
Medium	Work In Progress		4/22/2013 4:13:06 PM				
Ontiveros,	Guadalupe	please relocate material (i.e sand, g by warehouse barracks for new snp please see mike for details. thank y	barrack to be built.				
Michael M 99797	unoz		3/18/2013		78		\$0.00
Medium	Work In Progress		3/18/2013 7:59:04 AM		10		ψ0.00
	Guadalupe	Build elevated planters including po Elodia on location					
Alfredo Ho	lguin		2/45/2042		81		¢0.00
99749 High	Work In Progress		3/15/2013 3/15/2013 9:56:30 AM		01		\$0.00
High Munoz, Mi	Ū	need to repair the following roofs. P office, auto shop, snp warehouse ar barrack. wind damage	PD maintenance				
Alfredo Ho	lguin		E/04/0040				<u> </u>
102805			5/31/2013		4		\$0.00
Medium	Work In Progress		5/31/2013 8:27:22 AM				
Flores, Pe		electrical problem on truck 100 drain	ning battery				
<u>Mario Apo</u> 102169	daca		5/14/2013		21		\$0.00
Medium	Work In Progress		5/14/2013 3:12:59 PM	l			
Flores, Pe	te	truck 100 stop lights need to be wor	rked on				
Mario Apo	daca						
101420			4/29/2013		36		\$0.00
Medium	Work In Progress		4/29/2013 3:16:58 PM				
Sotelo, En		please check outlet to water fountai fountain wants to start. thank you	n. the gfi trips when				
<u>Michael M</u> 92274	UNOZ		9/2/2012		275		\$0.00
Medium	Work In Progress		9/2/2012 12:21:47 AM				
Munoz, Mi	chael	Monthly - Physical Plant - Grease T Refer to PM schedule details.	rap (Custodial) -				
Margret Vi	llalobos						
6/4/2013	9:16:08 AM					Page 10	19 of 160

WOID Priority Assigned 1 Requester		Area Deferred By Until Area Number Reason Cre Description	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Physical	Plant Complex					
102854			6/2/2013		2		\$0.00
Medium	Work In Progress	6/2/2	013 12:28:43 AM	1			
Diaz, Seba	stian	Monthly - Physical Plant - Lint Trap (Quarterly) · PM schedule details.	Refer to				
Margret Vil 99213	lalobos		3/3/2013		93		\$0.00
Medium	Work In Progress	3/3/2	013 12:25:57 AN				
Munoz, Mic	-	Monthly - Physical Plant - Grease Trap (Custod Refer to PM schedule details.					
Margret Vil	lalobos		4/47/0040		400		<u> </u>
97438		4/47/	1/17/2013		138		\$0.00
High Sotelo, Enr	Work In Progress rique	please cehck lighting on all buildings at ppd, the alot of lights that are out. also please install ano on the pole int the auto shop parking lot thank y	ther light	I			
Michael Mu	inoz		E/00/0040		10		¢0.00
102482 Medium	Work In Progress	5/22/	5/22/2013 2013 1:55:52 PM		13		\$0.00
Lara, Ralph	C C	need 3 sets of keys for the new bill jax lift, pleas mike for details. thank you		ı			
Michael Mu	inoz	-	E/21/2012		4		¢0.00
102806 Medium	Work In Progress	5/21/	5/31/2013 2013 8:28:17 AM		4		\$0.00
Lara, Ralph	C C	please make j-3 keys for gms custodial staff. ap by r.cahvez. thank you		I			
Michael Mu 101532	lnoz		4/30/2013		35		\$0.00
Medium	Work In Progress	4/30/	2013 4:32:11 PM		00		\$0.00
Lozoya, Ma	C C	Please see Alfredo Holguin about (rekeying).		-			
Alfredo Hol	•	· · · · · · · · · · · · · · · · · · ·					
98757	Food Services		2/22/2013		102		\$0.00
Medium	Work In Progress	2/22/	2013 1:04:15 PM	1			
Lozoya, Ma	anny	please make and assign the following keys 6/7 masters to gabriel provencio, robert duran, felip nevarez and johhny lechuga. 2 per.thank you					
Michael Mu	unoz Food Services		5/1/2013		34		\$0.00
101542 Medium	Work In Progress	5/1/	5/1/2013 2013 8:34:21 AM		34		φυ.υυ
Aldaz, Bob	-	SNP loading dock-add more crusher fine to ram into dock area. (Any ?'s see Alfredo)		1			
Alfredo Hol	Iguin	into uour alea. (Ally : 5 see Alleuu)					

WOID Priority	Building Status	Area Area Number	Deferred By Reason	Until Request Date Created Date/Time	•	Days Aged	Labor Hours	
Assigned 1		Description			Action Taken			
Requester	Name							
Location:	Physical	Plant Complex						
101560	Food Services	Custodial		5/1/2013		34		\$0.00
Medium	Work In Progress			5/1/2013 1:05:02 PM				
Lozoya, Ma	anny	OFFICE THE D	OOR LOCKS AN WITHOUT A SC OC 2 CORE SINCI	DOOR IN JOHNNYS D THEN CUSTODIAN REWDRIVER IF E THE CUSTODIAN				
Jimmy Carl 102995	bajal Food Services			6/3/2013		1		\$0.00
Medium	Work In Progress			6/3/2013 8:54:31 AM				φ0.00
Miranda, D	-			be checked, don't meone to Check it out.				
<u>Maritza Go</u> 98932	nzalez Motor Vehicle			2/27/2013		97		\$0.00
Medium				2/27/2013 9:06:33 AM		51		ψ0.00
	Work In Progress	Install Issue on		2/21/2013 9.00.33 AW				
Lozoya, Ma	-	Install locks on	gas pumps					
Pete Flores 101836	Motor Vehicle			5/6/2013		29		\$0.00
Medium	Work In Progress	vehicle#98		5/6/2013 3:17:41 PM				
Flores, Pet	9	please check e	lectrical system for	r proper charging.				
Pete Flores			-					
101636	Motor Vehicle			5/3/2013		32		\$0.00
Medium	Work In Progress	ppd golf cart		5/3/2013 8:24:35 AM				
Flores, Pet	e	please repair g	olf cart for use at p	physical plant.				
Pete Flores								
101647	Motor Vehicle			5/3/2013		32		\$0.00
Medium	Work In Progress	vehicle#143		5/3/2013 10:28:43 AM				
Flores, Pet			ve sustained inter aired at border int.	nal engine damage,will				
Pete Flores 101494	Motor Vehicle			4/30/2013		35		\$0.00
Medium	Work In Progress	vehicle#111		4/30/2013 3:09:34 PM	I			
Flores, Pet	-	vehicle difficult	to start after drivir	ng for a while.				
Pete Flores								
101552	Motor Vehicle			5/1/2013		34		\$0.00
Medium	Work In Progress	vehicle#25		5/1/2013 10:10:38 AM				
Flores, Pet	0	vehicle runs slu	ungish after being	driven for a while.				

Selected Da WOID Priority Assigned ⁻ Requester	Building Status To	Area Area Number Description	Deferred By		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex						
101875	Motor Vehicle			5/7/2013		28		\$0.00
Medium	Work In Progress	vehicle#01		5/7/2013 3:31:13 PM				
Flores, Pet	e	door lock actua check.	ators not working as	s designed. please				
Pete Flore: 100971	s Motor Vehicle			4/16/2013		49		\$0.00
Medium	Work In Progress	l110-mowers		4/16/2013 10:33:13 AM				
Flores, Pet	0	repair flat tires	and service mowe -0521,0429,0423,s	rs as required				
Pete Flores	s Motor Vehicle			4/16/2013		49		\$0.00
Medium	Work In Progress	vehicle#166		4/16/2013 2:23:24 PM		43		ψ0.00
Flores, Pet	0		t times please cheo					
Pete Flore		vernole stans a	t limes please chec					
101046	Motor Vehicle			4/17/2013		48		\$0.00
Medium	Work In Progress	vehicle#91		4/17/2013 3:51:49 PM				
Flores, Pet	e		ause of window fal k for any other sch	ling on driver's eduled maintenance.				
Pete Flore: 100604	s Motor Vehicle			4/5/2013		60		\$0.00
Medium	Work In Progress	vehicle#11		4/5/2013 3:39:15 PM				
Flores, Pet	-		a vehicle, cranks b	ut won't start at times				
Pete Flore		announcy startin	g vollicioi oranico z					
91931	Motor Vehicle			8/28/2012		280		\$0.00
Medium	Work In Progress			8/28/2012 7:52:34 AM				
Flores, Pet		it and a step to damage to sea	get on the truck to ts and steering wh a dash mat for the	request seat covers for avoid any more eel while getting into dashboard to avoid				
Fred Appe 94420	Izoller Motor Vehicle			10/22/2012		225		\$0.00
Medium	Work In Progress	vehicle#101		10/22/2012 11:16:35		220		\$0.00
Flores, Pet	-	truck has diffic	ulty achieving high heck and advise.	way speed,possibly a				
Pete Flore				- / /				A = = =
102531	Motor Vehicle			5/23/2013		12		\$0.00
Medium	Work In Progress	vehicle#183		5/23/2013 2:56:43 PM				
Flores, Pet	0	please service	as needed					

Selected Da WOID Priority Assigned Requester		Dates:7/1/2012 - 6 Area Area Number Description	Deferred By		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex						
102603	Motor Vehicle			5/28/2013		7		\$0.00
Medium	Work In Progress	vehicle#43		5/28/2013 10:03:10 AM				
Flores, Pe	te	please service	snp freightliner as r	needed				
Pete Flore				E/20/2042		7		<u> </u>
102604	Motor Vehicle			5/28/2013		7		\$0.00
Medium	Work In Progress	vehicle#176		5/28/2013 10:06:08 AM				
Flores, Pe	te	check vehicle for	or any required serv	vice.				
Pete Flore 95928	Motor Vehicle			11/29/2012		187		\$0.00
Medium	Work In Progress	vehicle#86		11/29/2012 9:53:45 AM				
Flores, Pe	-	van is running r normal operatio	ough and engine is m.	misfiring during				
Pete Flore	s Motor Vehicle			1/14/2013		141		\$0.00
97243 Medium		vehicle#18		1/14/2013 9:43:00 AM		141		Ф 0.00
	Work In Progress							
Flores, Pe	te		id need replacemei sively causing elec	trical concerns.engine				
Pete Flore	s Motor Vehicle			5/31/2013		4		\$0.00
Medium	Work In Progress	vehicles-		5/31/2013 11:37:20 AM				<i>Q0.00</i>
Flores, Pe	-		ash and-refuel as r	equired by daily trip				
1 10100, 1 0		schedule.						
Pete Flore 102822	S Motor Vehicle			5/31/2013		4		\$0.00
Medium	Work In Progress	vehicle-92		5/31/2013 11:40:00 AM				
Flores, Pe	Ŭ		or any required main					
Pete Flore								
102823	Motor Vehicle			5/31/2013		4		\$0.00
Medium	Work In Progress	vehicles34,54		5/31/2013 11:41:49 AM				
Flores, Pe	te	please check fo	or any needed main	tenance				
Pete Flore				- 1- 1				
102999	Motor Vehicle			6/3/2013		1		\$0.00
Medium	Work In Progress	vehicle#93		6/3/2013 10:50:56 AM				
Flores, Pe	te	difficulty starting	g vehicle-needs sta	rter				
Pete Flore	S							

Location:Physical F103000Motor VehicleMediumWork In ProgressFlores, PetePete Flores103001Motor VehicleMediumWork In ProgressFlores, PetePete Flores103002Motor VehicleMediumWork In Progress	please check for overheating. vehicle#97 6/3 electrical system not charging properly, and cany other required maintenance. vehicle#157 6/3	6/3/2013 3/2013 10:58:47 AM 6/3/2013 3/2013 11:01:27 AM check for 6/3/2013 3/2013 11:03:45 AM	1	
Medium Work In Progress Flores, Pete Pete Flores 103001 Motor Vehicle Medium Work In Progress Flores, Pete Pete Flores 103002 Motor Vehicle	please check for overheating. vehicle#97 6/3 electrical system not charging properly, and cany other required maintenance. vehicle#157 6/3	3/2013 10:58:47 AM 6/3/2013 3/2013 11:01:27 AM check for 6/3/2013	1	\$0.00
Flores, Pete Pete Flores 103001 Motor Vehicle Medium Work In Progress Flores, Pete Pete Flores 103002 Motor Vehicle	please check for overheating. vehicle#97 6/3 electrical system not charging properly, and cany other required maintenance. vehicle#157 6/3	6/3/2013 3/2013 11:01:27 AM check for 6/3/2013		\$0.00
Pete Flores103001Motor VehicleMediumWork In ProgressFlores, PetePete Flores103002Motor Vehicle	vehicle#97 6/3 electrical system not charging properly, and c any other required maintenance. vehicle#157 6/3	3/2013 11:01:27 AM check for 6/3/2013		 \$0.00
103001Motor VehicleMediumWork In ProgressFlores, PetePete Flores103002Motor Vehicle	electrical system not charging properly, and c any other required maintenance. vehicle#157 6/3	3/2013 11:01:27 AM check for 6/3/2013		\$0.00
Medium Work In Progress Flores, Pete Pete Flores 103002 Motor Vehicle	electrical system not charging properly, and c any other required maintenance. vehicle#157 6/3	3/2013 11:01:27 AM check for 6/3/2013		\$0.00
Flores, Pete Pete Flores 103002 Motor Vehicle	electrical system not charging properly, and c any other required maintenance. vehicle#157 6/3	check for 6/3/2013	1	
Pete Flores 103002 Motor Vehicle	any other required maintenance. vehicle#157 6/3	6/3/2013	1	
103002 Motor Vehicle			1	
Medium Work In Progress		3/2013 11:03:45 AM		\$0.00
-	, , ,, , ,, , , , , , ,			
Flores, Pete	a/c not working as should, also brake pedal tra floor.	avels to		
Pete Flores 103017 Motor Vehicle		6/3/2013	1	\$0.00
Medium Work In Progress	vehicle#14 6/	/3/2013 3:06:43 PM		ψ0.00
0		/3/2013 3.00. 4 3 F M		
Flores, Pete	please perform any scheduled maintenance.			
Pete Flores 102664 Motor Vehicle		5/29/2013	6	\$0.00
Medium Work In Progress	5/2	29/2013 9:06:35 AM		
Diaz, Sebastian	Lights in bathroom flickering			
Maria Ruiz	Custodial	2/11/2012	00	¢0.00
99729 Purchasing	Custodial	3/14/2013	82	\$0.00
Medium Work In Progress Sotelo, Enrique	A BALLAST IS FALLING DOWN IN CUSTOD IT IS A SAFETY HAZARD.	14/2013 3:44:20 PM DIAL WHSE		
Jimmy Carbajal				<u> </u>
94890 Purchasing		11/1/2012	215	\$0.00
Medium Work In Progress	11/1	/2012 11:12:31 AM		
Lozoya, Manny	Main Entry Lock to PPD-Construction Offices sticking and hard to unlock	s - core is		
Alfredo Holguin 95859 Purchasing	Office	11/27/2012	189	\$0.00
Medium Work In Progress		27/2012 4:14:46 PM		<i>4</i> 0.00
-		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Lozoya, Manny Larry Martinez	Please make a key for IM office 2. For larry			

Larry Martinez

WOID Priority Assigned 1		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		Diant Complex						
Location:		Plant Complex		0/1/0010				<u> </u>
99070	Purchasing			3/1/2013		95		\$0.00
Medium	Work In Progress			3/1/2013 8:30:37 AM				
Lozoya, Ma	anny	Issue 6 and 7 p	in Master Keys to	David Ruiz, Mail Clerk				
Alfredo Hol 101642	lguin Purchasing			5/3/2013		32		\$0.00
Medium	Work In Progress			5/3/2013 9:22:42 AM		02		ψ0.00
	-							
Lozoya, Ma	anny	collect any key		nilo Gonzales, Also ay have to this offices				
Alfredo Hol 102791	lguin Purchasing	Office		5/31/2013		4		\$0.00
Medium	Work In Progress	0		5/31/2013 7:50:49 AM		·		<i>Q</i> 0100
Diaz, Seba	0	Plaasa rapair A	C unit in Mr. Leyva					
		Flease lepail P		a onice				
Larry Marti 97246	nez Maintenance			1/14/2013		141		\$0.00
Medium	Work In Progress			1/14/2013 9:53:38 AM				
Lozoya, Ma	anny	NEED THREE AT BARRACKS THANK YOU		NEW FENCED AREA				
Ruben Ror 99762	nquillo Maintenance			3/15/2013		81		\$0.00
Medium	Work In Progress			3/15/2013 1:15:33 PM		01		ψ0.00
	-		-4					
Diaz, Seba		required.	at auto shop broke	n,replacement				
101919	Maintenance			5/8/2013		27		\$0.00
Medium	Work In Progress			5/8/2013 12:17:08 PM				
Solis, Lore	nzo	Order tools						
Lorenzo So								
91801	Maintenance			8/24/2012		284		\$0.00
Medium	Work In Progress			8/24/2012 7:25:21 AM				
Munoz, Mic			ut lint tank for custo warehouse smell l	odail washing machine. ke sewer.				
Alfredo Hol 99237	Iguin			3/3/2013		93		\$0.00
Medium	Work In Progress			3/3/2013 12:26:08 AM				
Munoz, Mic	•	Yearly - Physic PM schedule d		isp. (Yearly) - Refer to				
Margret Vil	lalobos							

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex					
102969			6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:36 AM				
Diaz, Seba	stian	Monthly - Physical Plant FE Inspec schedule details.	tion - Refer to PM				
<u>Margret Vill</u> 98667	lalobos		2/20/2013		104		\$0.00
Medium	Work In Brogroop		2/20/2013 1:50:08 PM		104		ψ0.00
Lozoya, Ma	Work In Progress anny	Custodial Warehouse Roll Up Door to be cleaned and lubricated?					
Alfredo Hol	guin						
100750			4/9/2013		56		\$0.00
Medium	Work In Progress		4/9/2013 3:33:46 PM				
Gonzalez, S	Salvador	as per our meeting, please cover e barrack with metal panels. thank yo					
<u>Michael Mu</u> 101863	INOZ		5/7/2013		28		\$0.00
Medium	Work In Progress		5/7/2013 9:15:33 AM		20		φ0.00
Munoz, Mic	•	need to remove from site all the de wood poles, branches, tires etc.) ar warehouse.	bre (ie wood piles,				
<u>Alfredo Hol</u> 100572	guin		4/5/2013		60		\$0.00
	Work In Dragrada				00		φ0.00
Medium	Work In Progress		4/5/2013 7:58:45 AM				
Gonzalez, S	Salvador	Need metal door and screen for she	op and be installed.				
<u>Salvador G</u> 100824	onzalez		4/11/2013		54		\$0.00
Medium	Work In Progress		4/11/2013 7:58:10 AM		04		ψ0.00
Gonzalez, S	Work In Progress Salvador	4-11-13 Need cover for welding machine.	4/11/2013 7.36.10 AM				
Salvador G	onzalez	-					
93179		Lift Station	9/24/2012		253		\$0.00
Medium	Work In Progress		9/24/2012 2:41:20 PM				
Gonzalez, S	Salvador	Meet to manufacture A base for the container for the waste water treatr					
Mario Apod	laca		6/3/2013		1		\$0.00
103034 Madium	Mork In Dreamer				I		ψ0.00
Medium Gonzalez, S	Work In Progress Salvador	NEED TO REPAIR BIL-JAX LIFT E THANK YOU	6/3/2013 4:19:09 PM SUCKET FLOOR!				
Ruben Ron Count: 71 V	quillo Work Orders	Avg. Age of WO's 6	8 Total for	Physical Plant Com	plex	0	\$0.00

WOID Priority Assigned 1 Requester		Area Deferred Area Number Reason Description	•	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Riverside	ES					
98705			2/21/2013		103		\$0.00
Medium	Work In Progress		2/21/2013 8:07:53 AM	l			
Orozco, Da	niel		P AGAIN, TAKING A LONG ANAGER EMILIA C. 589.2550				
Maritza Go 99351	nzalez		3/5/2013		91		\$0.00
Medium	Work In Progress		3/5/2013 10:52:19 AM		•		
Orozco, Da	-		drain properly clogging and ^D Manager Emilia C. 589.2550				
<u>Maritza Go</u> 99352	nzalez		3/5/2013		91		\$0.00
Medium	Work In Progress		3/5/2013 10:53:59 AM		51		ψ0.00
Orozco, Da	-	Grill does not work at all. 589.2550					
Maritza Go	nzalez		0/5/0040		0.1		\$0.00
99353			3/5/2013		91		\$0.00
Medium Orozco, Da	Work In Progress niel	Two burners on stove top Emilia C. 589.2550	3/5/2013 10:54:23 AM o do not light up. SNP Manager				
Maritza Gor 101929	nzalez		5/8/2013		27		\$0.00
Medium	Work In Progress		5/8/2013 3:29:47 PM		21		ψ0.00
	Ū						
Gonzalez, S		need to repair fram and c	door to outside water fountains				
Carlos Herr 102548	nandez		5/23/2013		12		\$0.00
Medium	Work In Progress	GISD	5/23/2013 3:27:24 PM	l			
Briones, En	rique	PO# 121304836 PLEASE DELIVER 400 E ELEM. ATTN: INSTRUC	BOOK BOXES TO RIVERSIDE TIONAL COACH				
Lucia Alme 99224	raz		3/3/2013		93		\$0.00
Medium	Work In Progress		3/3/2013 12:26:02 AM				
Munoz, Mic		Yearly - Riverside ES Fire PM schedule details.	e Ext. Insp. (Yearly) - Refer to				
Margret Vill	alobos		6/0/0040	6/0/2012	2		¢0.00
102973 Modium	Work In Drograss		6/2/2013		2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:38 AM				
Ambriz, Jua	an alobos	Monthly - Riverside ES M PM schedule details.	Ionthly FE Inpsection - Refer to				

Orozco, Daniel <u>Margret Villalob</u> 100353 Medium Wo Moncayo, Ferna <u>Margret Villalob</u> 101774 Medium Wo Moncayo, Ferna <u>Margret Villalob</u> 99026 Mai Medium Wo Gonzalez, Salva Juan Ambriz	rk In Progress	ES Monthly - Riverside ES Range Hood PM schedule details.	3/31/2013 3/31/2013 12:33:26 AM Cleaning - Refer to	4/21/2013	65	\$0.00
Medium Wo Orozco, Daniel <u>Margret Villalob</u> 100353 Medium Wo Moncayo, Ferna <u>Margret Villalob</u> 101774 Medium Wo Moncayo, Ferna <u>Margret Villalob</u> 99026 Mai Medium Wo Gonzalez, Salva	rk In Progress		3/31/2013 12:33:26 AM		65	\$0.00
Orozco, Daniel <u>Margret Villalob</u> 100353 Medium Wo Moncayo, Ferna <u>Margret Villalob</u> 101774 Medium Wo Moncayo, Ferna <u>Margret Villalob</u> 99026 Mai Medium Wo Gonzalez, Salva Juan Ambriz	rk In Progress					
Margret Villalob 100353 Medium Wo Moncayo, Ferna Margret Villalob 101774 Medium Wo Moncayo, Ferna Margret Villalob 99026 Mai Medium Wo Gonzalez, Salva Juan Ambriz	rk In Progress		Cleaning - Refer to			
100353 Medium Wo Moncayo, Ferna <u>Margret Villalob</u> 101774 Medium Wo Moncayo, Ferna <u>Margret Villalob</u> 99026 Mai Medium Wo Gonzalez, Salva Juan Ambriz	rk In Progress					
Medium Wo Moncayo, Ferna <u>Margret Villalob</u> 101774 Medium Wo Moncayo, Ferna <u>Margret Villalob</u> 99026 Mai Medium Wo Gonzalez, Salva Juan Ambriz	C C		3/31/2013	4/6/2013	65	\$0.00
Moncayo, Ferna Margret Villalob 101774 Medium Wo Moncayo, Ferna Margret Villalob 99026 Mai Medium Wo Gonzalez, Salva Juan Ambriz	C C		3/31/2013 12:33:18 AM			<i>QO</i> . <i>OO</i>
101774 Medium Wo Moncayo, Ferna <u>Margret Villalob</u> 99026 Mai Medium Wo Gonzalez, Salva Juan Ambriz		Monthly - Riverside ES Monthly FE Ir PM schedule details.				
Medium Wo Moncayo, Ferna <u>Margret Villalob</u> 99026 Mai Medium Wo Gonzalez, Salva Juan Ambriz	OS		5/5/2013	5/11/2013	30	\$0.00
Moncayo, Ferna <u>Margret Villalob</u> 99026 Mai Medium Wo Gonzalez, Salva Juan Ambriz	rk In Progress		5/5/2013 12:24:42 AM			
99026 Mai Medium Wo Gonzalez, Salva Juan Ambriz	C C	Monthly - Riverside ES Monthly FE Ir PM schedule details.				
Medium Wo Gonzalez, Salva Juan Ambriz		Dortoblas	2/28/2013		96	\$0.00
Gonzalez, Salva Juan Ambriz		Portables			90	Φ 0.00
Juan Ambriz	rk In Progress	No od to coold no no to platfama in a set	2/28/2013 8:56:04 AM			
	ador	Need to weld ramp to platform in por	adie			
	in Building		4/11/2013		54	\$0.00
Medium Wo	rk In Progress		4/11/2013 4:00:27 PM			
Ontiveros, Joe		WATER LEAK IN STORAGE ROOM AREA IN FRONT OF OFFICE.	IN RESTROOM			
Olga Arias	in Building	Postroom (Cirlo)	1/24/2013		131	\$0.00
	•	Restroom (Girls)			131	Φ 0.00
	rk In Progress	front of office	1/24/2013 2:59:49 PM			
Ontiveros, Joe		Girls restroom last stable missing mis	ssing toilet seat	Route to Joe asp rea	assignment 4/2/13	
Juan Ambriz 98258 Mai	in Building		2/6/2013		118	\$0.00
	rk In Progress		2/6/2013 12:06:58 PM			
Ontiveros, Joe	-	Problems in the girl restroom with toi custodian	let leaking as per	Route to Joe asp rea	assignment 4/2/13	
Olga Arias 101606 Nev	w Wing 1/02	Classroom	5/2/2013		33	\$0.00
	rk In Progress	classroom #144	5/2/2013 2:48:46 PM		00	ψ0.00
	IN III FIOYIESS		0/2/2013 2.40.40 PW			
Ambriz, Juan Juan Ambriz		Need to replace lights in room				

WOID Priority Assigned 1 Requester		Area Deferred By Until Area Number Reason Description	Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Riverside	ES					
101918			5/8/2013		27		\$0.00
Medium	Work In Progress	Ę	5/8/2013 11:46:13 AN	l			
Ambriz, Jua		Handicap Logo needs to be painted.(Espec on the northside of the campus where pare a/s/a/p) and any others throughout site.					
Richard Ch 102678	avez		5/29/2013		6		\$0.00
Medium	Work In Progress	5/	29/2013 11:31:19 AN		-		
Hernandez	-	a/c unit in teachers lounge not working pro					
		are unit in teachers lounge not working pro-	peny				
Carlos Heri 102881	nandez		6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress	6	6/2/2013 12:28:56 AN	l			
Ambriz, Jua	an	Yearly - Riverside ES B-2 Boiler Hot Water Refer to PM schedule details.	Yearly -				
Margret Vill	lalobos		E/21/2012	7/1/2013	4		¢0.00
102760		<i>с</i> /	5/31/2013		4		\$0.00
Medium	Work In Progress		31/2013 12:28:40 AN				
Ambriz, Jua		Yearly - Riverside ES A-2 Gas/Elec Unit Ye to PM schedule details.	early - Refer				
Margret Vill 102101	1210005		5/13/2013		22		\$0.00
Medium	Work In Progress	5	5/13/2013 3:32:09 PM	I			
Ortiz, Rube	n	Summer Project at Riverside Paint front circle turquoise					
Ruben Ortiz 102105	Z		5/13/2013		22		\$0.00
Medium	Work In Progress	F	5/13/2013 3:33:55 PM	1			\$0.00
Ortiz, Rube	0	Summer Project at Riverside	, 10,2010 0.00.001 1	•			
Oniz, Rube	; I I	Paint ramps to portables turquoise					
Ruben Ortiz	Z		E/12/2012				¢0.00
102108 Medium			5/13/2013 5/13/2013 3:35:10 PM		22		\$0.00
	Work In Progress		0/13/2013 3.35.10 PW	I			
Ortiz, Rube	n	Summer Project at Riverside Paint fire lane curves red					
Ruben Ortiz	Z		0/00/0040				<u> </u>
98990			2/28/2013		96		\$0.00
Medium	Work In Progress		28/2013 12:28:22 AN	I			
Moncayo, F	Fernando	Monthly - Riverside ES A-16 Fan Exhaust S Refer to PM schedule details.	Semiannual -				

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	FS						
	Riverside	Parking Lot		5/8/2013		27		\$0.00
101898		Farking Lot				21		φ0.00
Medium Villalobos,	Work In Progress David	domestic back	nical needs to rep low preventer, did work needs to be a	not pass annual test				
David Villa	lobos	Destream (De)		4/00/0040		400		<u> </u>
97539		Restroom (Boy	'S)	1/22/2013		133		\$0.00
High	Work In Progress			1/22/2013 11:40:53 AM				
Ontiveros,			drains in rest room n line. thank you	s and remove	Route to Joe asp rea	assignm	ent 4/2/13	
Michael Mu 90202	JNOZ			7/25/2012		314		\$0.00
Medium	Work In Progress			7/25/2012 3:44:33 PM	l			
Ontiveros,		need new toilet wing	in outside teache	r bathrooom upper	Route to Joe asp rea	assignm	ent 4/2/13	
Carlos Her	nandez	·····g						
101467				4/30/2013		35		\$0.00
Medium	Work In Progress			4/30/2013 8:18:29 AM	l			
Castillo, Ca	arlos	need to replace theres only one		in hallway to new wing				
Carlos Her 99909	nandez			3/20/2013		76		\$0.00
						70		ψ0.00
Medium Romero, R	Work In Progress aul		AN UP ALL TRAS	3/20/2013 9:32:37 AM H ALONG FENCE				
Jesus Estr	ada	LINE						
99910				3/20/2013		76		\$0.00
Medium	Work In Progress			3/20/2013 9:34:01 AM	I			
Romero, R	aul	NEED TO CLE	AN UP ALL BATH	ROOM WALLS				
Jesus Estra 102914	ada			6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:11 AM		2		ψ0.00
Ambriz, Ju	-	Monthly - River		Insp: Monthly - Refer to				
Margret Vil	lalobos							
102912				6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:10 AM				
Ambriz, Ju	an	Monthly - River Refer to PM sc	side ES Emer. Lig hedule details.	ht Test: Monthly -				

Location:	r Name	Description	Actual Comp Date Action Taken	Aged	Hours	
101742	Riverside	ES				
1017 12		5/5/2013	5/13/2013	30		\$0.00
Medium	Work In Progress	5/5/2013 12:24:29 AM				
Moncayo,	Fernando	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vi 101743	illalobos	5/5/2013	5/13/2013	30		\$0.00
Medium	Work In Progress	5/5/2013 12:24:29 AM	0,10,2010	00		φ0.00
Moncayo,	Ŭ	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vi	illalobos	0/04/0040	4/0/2042	05		<u> </u>
100292		3/31/2013	4/8/2013	65		\$0.00
Medium	Work In Progress	3/31/2013 12:32:54 AM				
Moncayo,		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vi 100294	IIIalodos	3/31/2013	4/8/2013	65		\$0.00
Medium	Work In Progress	3/31/2013 12:32:55 AM				
Moncayo,	Fernando	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vi 99162	illalobos	3/3/2013	3/11/2013	93		\$0.00
Medium	Work In Progress	3/3/2013 12:25:34 AM	0,11,2010	00		φ0.00
Moncayo,	Ŭ	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vi	illalobos	5/29/2013		6		\$0.00
102675 Madium				0		φ0.00
Medium Ronquillo,	Work In Progress Ruben	5/29/2013 11:26:26 AM need window replaced room 123 new wing broken due to vandlism				
Carlos Hei	rnandez					
102058		5/12/2013	5/28/2013	23		\$0.00
Medium	Work In Progress	5/12/2013 12:21:29 AM				
Moncayo,	Fernando	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.				
Margret Vi 100633	illalobos	4/7/2013	4/23/2013	58		\$0.00
Medium	Work In Progress	4/7/2013 12:18:55 AM	1,20,2010	00		ψ0.00
Moncayo,	Ū	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.				
Margret Vi	illalobos Work Orders	Avg. Age of WO's 58	Total for Riversid			\$0.00

-				•	/			Total
Selected Da WOID	ate Range for Request Building	Dates:7/1/2012 - 6 Area	6/30/2013 Order By L Deferred By	ocation, Statu Until	Request Date Target Comp Date Target Com	ate Days	Labor	Costs
Priority	Status	Area Number	Reason	Cre	eated Date/Time Actual Comp Da	te Aged	Hours	
Assigned	То	Description			Action Take	en		
Requeste	r Name							
Location:	RTC - All	iance						
98719					2/21/2013	103		\$0.00
Medium	Work In Progress			2/21	/2013 2:11:17 PM			
Castillo, C	carlos		electrial outlets in th cords running on flo					
Cora Ram	nirez							
	Nork Orders	Av	vg. Age of WO's 1	103	Total for RTC -	Alliance	0	\$0.00

WOID Priority Assigned Requester		Area Deferred Area Number Reason Description	By Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	San Migu	el ES					
102683			5/29/2013		6		\$0.00
Medium	Work In Progress		5/29/2013 1:26:48 PM	I			
Villalobos,		NEED TO DISCONNECT PORTABLE #37 FOR RE TRAIL.	WATER AND GAS FROM LOCATION TO DESERT				
Michael M 102682	unoz		5/29/2013		6		\$0.00
Medium	Work In Progress		5/29/2013 1:25:36 PM	l			·
Ontiveros,	Guadalupe	NEED TO REMOVE RAM PORTABLE #37 FOR RE TRAIL.					
<u>Michael M</u> 102953	unoz		6/2/2013		2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:29 AM		۷		ψ0.00
Sanchez, I	Ū	Monthly - San Miguel ES to PM schedule details.	- Lift Station Inspection - Refer				
Margret Vi	llalobos						
101757			5/5/2013		30		\$0.00
Medium	Work In Progress		5/5/2013 12:24:35 AM				
Sanchez, I	Raul	Monthly - San Miguel ES to PM schedule details.	- Lift Station Inspection - Refer				
Margret Vi 102260	llalobos		5/16/2013		19		\$0.00
Medium	Work In Progress		5/16/2013 2:08:29 PM	I			<i>Q</i>
Vega, Dan	Ū	need to replaced pine tree line /order spklrs and repl 20s					
Danny Veg 101311	<u>ga</u> Cafeteria		4/25/2013		40		\$0.00
Medium	Work In Progress		4/25/2013 10:57:32 AM		10		\$0.00
Lozoya, M	-		and dinning area need to lock. nt because it is not locking.				
Alfredo Ho	lguin	,	2				
99269			3/3/2013		93		\$0.00
Medium	Work In Progress		3/3/2013 12:26:21 AM				
Sanchez, I		Monthly - San Miguel ES to PM schedule details.	- Lift Station Inspection - Refer				
Margret Vi	llalobos Vork Orders	Avg. Age of	WOI- 28	Total for San Migue		0	\$0.00

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa ES					
97255			1/14/2013		141		\$0.00
Medium	Work In Progress		1/14/2013 12:59:56 PM				
Orozco, D	aniel	AS PER INSPECTION PIPES ON STAND NEEDS TO BE FIXED.SN MARINA R. 589.3439					
<u>Maritza Go</u> 102544	onzalez		5/23/2013		12		\$0.00
Medium	Work In Progress	GISD	5/23/2013 3:22:15 PM		12		φ0.00
	Ŭ		5/23/2013 3.22.15 PW				
Briones, E	nrique	PO# 121304836 PLEASE DELIVER 400 BOOK BO TERESA ELEM. ATTN: INSTRUC					
Lucia Almo 102512	eraz	Auditorium	5/23/2013		12		\$0.00
Medium	Work In Progress		5/23/2013 7:47:44 AM				\$0.00
Ronquillo,	Ŭ	Need scissor lift delivered to Sta.T auditorium.					
Carlos Ca	stillo						
100372			3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress		3/31/2013 12:33:26 AM				
Orozco, D		Monthly - Santa Teresa ES Range Refer to PM schedule details.	Hood Cleaning -				
Margret Vi 102964	llalobos		6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:34 AM				
Ambriz, Ju	Ū	Monthly - Santa Teresa ES Month Refer to PM schedule details.	ly FE Inspection -				
Margret Vi	illalobos						
99225			3/3/2013		93		\$0.00
Medium	Work In Progress		3/3/2013 12:26:02 AM				
Munoz, Mi		Yearly - Santa Teresa ES Fire Ext to PM schedule details.	t. Insp. (Yearly) - Refer				
Margret Vi 103045	illalobos Main Building	Office	6/3/2013		1		\$0.00
Medium	Work In Progress		6/3/2013 5:20:51 PM				
Gonzales,	Ū	Please deliver 1 Gaylord & pallet					
Larry Mart		, , , , , , , , , , , , , , , , , , , ,					
97635	Main Building	Stairway	1/24/2013		131		\$0.00
Medium	Work In Progress	Art portable	1/24/2013 9:12:56 AM				
Gonzalez,	Salvador	A ramp is needed at the entrance Thank you.	of the Art portable.				
Rita Mend	ez						

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa ES						
101607	Main Building	Hallway/Corrido	or	5/2/2013		33		\$0.00
Medium	Work In Progress			5/2/2013 2:54:35 PM				
Ambriz, Ju	an	Need to check	exhaust fan in hall	way				
Juan Ambr				5/11/00/10				<u> </u>
102151	Main Building	Classroom		5/14/2013		21		\$0.00
Medium	Work In Progress	308		5/14/2013 8:20:20 AM				
Ambriz, Ju	an		pencil sharpener. ust eats up the per	It does not sharpen ncils.				
Melynda M	lenchaca Main Building	Portables		1/24/2013		131		\$0.00
97636 Medium	Work In Progress	FRONT AREA		1/24/2013 9:28:16 AM		131		Ф 0.00
Munoz, Mi	•	PLEASE SET U ART PORTABL STORAGE FO	.E. THIS BUILDIN R ART SUPPLIES	LDING ACROSS THE IG WILL BE USED AS . ALSO, PLEASE BLDG. THANK YOU.				
Rita Mende 100682	ez Main Building	Cafeteria		4/8/2013		57		\$0.00
Medium	Work In Progress	swamp cooler		4/8/2013 2:39:42 PM		57		ψ0.00
Ambriz, Ju	Ŭ	•	leacky valves for s					
Juan Ambr		·	-					
100442	Main Building			4/2/2013		63		\$0.00
Medium	Work In Progress	maint. storage		4/2/2013 2:55:32 PM				
Ambriz, Ju	an	Need to Install	shelves in maint. s	torage morgan				
<u>Juan Ambr</u> 102437	r <u>iz</u> Main Building	Classroom		5/21/2013		14		\$0.00
Medium	Work In Progress	room 304		5/21/2013 1:45:31 PM				<i>Q</i> 0 1 0 0
Ambriz, Ju	•		is leaking. Please					
Rita Mende	ez							
102438	Main Building	Classroom		5/21/2013		14		\$0.00
Medium	Work In Progress	room 209		5/21/2013 1:46:52 PM				
Ambriz, Ju	an	Classroom sink	is leaking. Please	e check. Thanks.				
Rita Mende 97536	ez Main Building	Athletic Field		1/22/2013		133		\$0.00
Medium	Work In Progress	OUTSIDE CAS	A	1/22/2013 10:24:14 AM				<i>,</i>
	•			. PLEASE CHECK.	Route to Joe asp rea	assianmi	ont 1/2/13	
Ontiveros,	Joe	THANKS.		. TEENSE SHESK.		Josigini	5111 4 /2/10	

WOID Priority Assigned 7 Requester		Area Area Number Description	Deferred By Reason	Until Request Date Ta Created Date/Time A	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa ES						
97399	Main Building	Cafeteria		1/16/2013		139		\$0.00
Medium	Work In Progress	cafeteria		1/16/2013 1:25:53 PM				
Castillo, Ca	arlos	THERE ARE 3 L PLEASE CHECK (WERE SUPPO	IGHTS THAT DO FOR MISSING SED TO BE REP	LIGHTS ALSO,				
Rita Mende 96473	ez Main Building	Cafeteria		12/11/2012		175		\$0.00
Medium	Work In Progress	CAFETERIA		12/11/2012 11:24:42				
Castillo, Ca	0	A NEW LIGHT F						
Rita Mende 96474	ez Main Building	Cafeteria		12/11/2012		175		\$0.00
Medium	Work In Progress	CAFETERIA		12/11/2012 11:27:48		170		ψ0.00
Castillo, Ca	•	THE LIGHTS IN	THE CAFERERI ALL OF THEM					
Rita Mende		5 ())		0/0/00 40				.
103019	Main Building	Portables		6/3/2013		1		\$0.00
Medium	Work In Progress	all portables		6/3/2013 3:47:52 PM				
Ambriz, Jua	an	Need to paint all	doors and ramp	s to all portables				
Juan Ambr 99828	iz Main Building	Parking Lot		3/18/2013		78		\$0.00
Medium	Work In Progress			3/18/2013 3:32:01 PM				φ0.00
	0	Need to repaint	orking lines	3/10/2013 3.32.011 W				
Ambriz, Jua		Need to repaint	Jarking lines					
Juan Ambr 102059	12			5/12/2013	5/28/2013	23		\$0.00
Medium	Work In Progress			5/12/2013 12:21:30 AM				
Ambriz, Jua	an	Monthly - Santa PM schedule de		round Insp - Refer to				
Margret Vil	lalobos	Destream (Devis	<u>\</u>	11/00/0010		100		¢0.00
95724 Madium		Restroom (Boys)	11/20/2012		196		\$0.00
Medium	Work In Progress	CASA AZUL		11/20/2012 3:14:15 PM				
Marquez, C	Gerardo	PROPERLY. IT	IT WAS TURNE	T WORKING ON AND STAYING D OFF COMPLETELY.				
		FLEASE CHECK	A. THANKS.					

Santa Ter Work In Progress Nork In Progress Nork In Progress Nork In Progress	esa ES Monthly - Santa Teresa ES Exit Sign Ins Refer to PM schedule details. Monthly - Santa Teresa ES Emer Light T Refer to PM schedule details.	6/2/2013 6/2/2013 12:29:21 AM	6/10/2013	2		
lobos Nork In Progress Nork In Progress	Refer to PM schedule details. Monthly - Santa Teresa ES Emer Light 1	6/2/2013 12:29:21 AM sp: Monthly - 6/2/2013 6/2/2013 12:29:21 AM Fest: Monthly -				\$0.00 \$0.00
lobos Nork In Progress Nork In Progress	Refer to PM schedule details. Monthly - Santa Teresa ES Emer Light 1	5p: Monthly - 6/2/2013 6/2/2013 12:29:21 AM Fest: Monthly -	6/10/2013	2		\$0.00
lobos Work In Progress Nork In Progress	Refer to PM schedule details. Monthly - Santa Teresa ES Emer Light 1	6/2/2013 6/2/2013 12:29:21 AM Fest: Monthly -	6/10/2013	2		\$0.00
Work In Progress 1 Iobos Work In Progress		6/2/2013 12:29:21 AM Fest: Monthly -	6/10/2013	2		\$0.00
lobos Nork In Progress		6/2/2013 12:29:21 AM Fest: Monthly -	6/10/2013	Z		Φ0.00
lobos Nork In Progress		Fest: Monthly -				
lobos Work In Progress						
Nork In Progress		6/2/2013				
-				2		\$0.00
-				-		<i>Q</i> 0100
	Monthly - Santa Teresa ES -Clothes Dry Refer to PM schedule details.					
lobos		5/5/0040				<u> </u>
				30		\$0.00
Nork In Progress		5/5/2013 12:24:22 AM				
1	Monthly - Santa Teresa ES -Clothes Dry Refer to PM schedule details.	ver (Monthly) -				
lobos		5/5/2013	5/13/2013	30		\$0.00
Nork In Progress			0,10,2010	00		\$0.00
n n n n n n n n n n n n n n n n n n n	Monthly - Santa Teresa ES Emer Light T Refer to PM schedule details.					
lobos		5/5/0040	5/40/0040			
			5/13/2013	30		\$0.00
-		5/5/2013 12:24:23 AM				
1	Monthly - Santa Teresa ES Exit Sign Ins Refer to PM schedule details.	sp: Monthly -				
lobos		4/7/2013	4/23/2013	58		\$0.00
Nork In Progress		4/7/2013 12:19:04 AM				
0	Monthly - QRTLY BLDG INSP REPORT to PM schedule details.	(STE) - Refer				
lobos						
		10/15/2012		232		\$0.00
Nork In Progress	BACK FIELD	10/15/2012 3:28:57 PM				
uadalupe	PLEASE FILL OUT ALL HOLES WITH D BACK FIELDS. THANKS.	DIRT IN THE				
<u> </u> /n/ <u> </u> /n/ <u> </u> //	lobos Vork In Progress Iobos Vork In Progress Iobos Vork In Progress Iobos Vork In Progress Iobos	Monthly - Santa Teresa ES -Clothes Dry Refer to PM schedule details. Nork In Progress Monthly - Santa Teresa ES -Clothes Dry Refer to PM schedule details. Nork In Progress Monthly - Santa Teresa ES Emer Light T Refer to PM schedule details. Nork In Progress Monthly - Santa Teresa ES Exit Sign Ins Refer to PM schedule details. Nork In Progress Monthly - Santa Teresa ES Exit Sign Ins Refer to PM schedule details. Nork In Progress Monthly - QRTLY BLDG INSP REPORT to PM schedule details. Nork In Progress Monthly - QRTLY BLDG INSP REPORT to PM schedule details. Nork In Progress Monthly - QRTLY BLDG INSP REPORT to PM schedule details. Nork In Progress Athletic Field Nork In Progress BACK FIELD uadalupe PLEASE FILL OUT ALL HOLES WITH I	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details. bobos 5/5/2013 12:24:22 AM Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details. bobos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. bobos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. bobos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. bobos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details. bobos 4/7/2013 12:24:23 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. bobos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. bobos 4/7/2012 3:28:57 PM uadalupe PLEASE FILL OUT ALL HOLES WITH DIRT IN THE	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details. bobos 5/5/2013 Vork In Progress 5/5/2013 12:24:22 AM Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details. bobos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. bobos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. bobos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details. bobos 4/7/2013 12:24:23 AM Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details. bobos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. bobos 4/7/2012 Vork In Progress BACK FIELD 10/15/2012 Vork In Progress BACK FIELD 10/15/2012 3:28:57 PM uadalupe PLEASE FILL OUT ALL HOLES WITH DIRT IN THE	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details. 10bos 5/5/2013 12:24:22 AM Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details. 10bos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. 10bos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. 10bos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. 10bos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details. 10bos 4/7/2013 12:24:23 AM Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details. 10bos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. 10bos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. 10bos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. 10bos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. 10bos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. 10bos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. 10bos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. 10bos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. 10bos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. 10bos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. 10bos 4/7/2013 12:19:04 AM MONTH IN THE	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details. bobos 5/5/2013 12:24:22 AM Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details. bobos 5/5/2013 5/13/2013 30 Vork In Progress 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. bobos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. bobos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. bobos 5/5/2013 12:24:23 AM Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details. bobos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. bobos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. bobos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. bobos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. bobos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. bobos 4/7/2013 12:19:04 AM Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. bobos 4/7/2013 12:23:28:57 PM uadalupe PLEASE FILL OUT ALL HOLES WITH DIRT IN THE

WOID	ate Range for Request Building	Area	Deferred By	Until	Request Date Target Co	ام م م	Labor Hours	Costs
Priority	Status	Area Number	Reason	Crea	ted Date/Time Actual Co	•	Hours	
Assigned	То	Description			Actic	on Taken		
Requeste	r Name							
Location:	Santa Ter	resa ES						
99687		Parking Lot			3/14/2013	82		\$0.00
Medium	Work In Progress	Vehicle #141		3/14/2	013 8:18:38 AM			
Flores, Pe	te	Vehicle #141 n	eeds service overhe	ating				
Juan Amb	riz							
102865					6/2/2013	2		\$0.00
Medium	Work In Progress			6/2/20	13 12:28:48 AM			
Ambriz, Ju	Jan	Monthly - Santa to PM schedule	a Teresa ES C-4 Qu e details.	arterly MSS -	Refer			
Margret Vi	illalobos							<u> </u>
102436		Cafeteria			5/21/2013	14		\$0.00
Medium	Work In Progress			5/21/2	013 1:11:55 PM			
Ambriz, Jo	ose	A/C THROWIN	IG AIR TO HOT					
Pablo Dia	Z							
Count: 34	Work Orders	A	vg. Age of WO's 6	5	Total for Sa	anta Teresa ES	0	\$0.00

WOID Priority Assigned ⁻ Requester		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa HS					
97485			1/18/2013	· · · · · · · · · · · · · · · · · · ·	137		\$0.00
Medium	Work In Progress		1/18/2013 11:24:53 AN	1			
Ambriz, Jo	se	Room 210. Both fan coil units are n heating mode. Need to replace the actuator valves.					
<u>Jaime Mija</u> 98831	rez		2/25/2013		99		\$0.00
Medium	Work In Progress		2/25/2013 3:37:23 PM				
Ambriz, Jo	•	Chiller has two failures low refrigera temp. Monitor water pressure and r	ant temp, and high oil	Called Honeywell			
<u>Jaime Mija</u> 98284	rez		2/6/2013		118		\$0.00
Medium	Work In Progress		2/6/2013 7:23:09 PM		110		ψ0.00
Ambriz, Jo	Ū	Library air-handler. Need to replace belimo valve. The stayed stuck in the	hot water side				
Jaime Mija	rez	-	0/04/0040	4/04/0040	05		<u> </u>
100199			3/31/2013		65		\$0.00
Medium	Work In Progress		3/31/2013 12:32:18 AN	1			
Marquez, (Monthly - Santa Teresa HS C-12 C - Refer to PM schedule details.	hm Feeder Semimtly				
Margret Vil 100200	llalobos		3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress		3/31/2013 12:32:18 AN	1			·
Marquez, 0	Ū	Monthly - Santa Teresa HS H-11 U	nit Elec Semimly -				
Margret Vil	llalobos		0/04/0040				.
100201			3/31/2013		65		\$0.00
Medium	Work In Progress		3/31/2013 12:32:18 AN	1			
Marquez, (Gerardo	Monthly - Santa Teresa HS A-16 Ro Refer to PM schedule details.	oof/Exh Semiannual -				
Margret Vil	llalobos	Darking Lat	0/11/0010		110		¢0.00
98346	Morte In Dragger	Parking Lot	2/11/2013		113		\$0.00
Medium	Work In Progress	.	2/11/2013 11:07:12 AN	1			
Marquez, (Gerardo	Need to get some white paint to ma area.	irk off a no parking				
	ckson						

Priority Assigned Requester		Area Deferred By Area Number Reason Description		Actual Comp Date Actual Comp Date Action Taken	Days Labor Aged Hours	
Location:	Santa Te	resa HS				
92161		Parking Lot	8/31/2012	2	277	\$0.00
Medium	Work In Progress	MR.	8/31/2012 1:15:00 PM	N		
Marquez, (Gerardo	PAINT THE 45, 35, 25 YARD L LOT. BAND NEEDS IT FOR A REHEARSAL. ANYWAY IF IT ASAP.	AFTER SCHOOL			
Marylou Ji	menez	Parking Lot	4/7/2013)	58	\$0.00
100663		Faiking Lot			50	Ф 0.00
Medium	Work In Progress		4/7/2013 4:38:59 PM	М		
Marquez, (Gerardo	Need to paint white arrows in the enter one way and leave one we ease congestion in the morning white paint.	vay. Safety issue. Will			
William Di	ckson		0/00/00/2	0/04/0040	00	¢0.00
98986			2/28/2013	3/31/2013	96	\$0.00
Medium	Work In Progress		2/28/2013 12:28:20 AN	Ν		
Marquez,	Gerardo	Yearly - Santa Teresa HS C-11 Refer to PM schedule details.	1 Evap Coolers Yearly -			
Margret Vi	llalobos			4/00/0040		
100635			4/7/2013	3 4/23/2013	58	\$0.00
Medium	Work In Progress		4/7/2013 12:18:56 AN	Ν		
Marquez, (Gerardo	Monthly - Santa Teresa HS A-4 Refer to PM schedule details.	4 Comp Air Semiannual -			
Margret Vi	llalobos		0/40/0046			*• • • •
98495			2/13/2013	3	111	\$0.00
Medium	Work In Progress		2/13/2013 4:00:53 PM	N		
Ontiveros,	Joe	Football concession stand. The valve or drain line installed for find a way to close the water. V shutoff valve and drain line.	selling area a/c. Had to	Route to Joe asp rea	assignment 4/2/13	
Jaime Mija	arez		1/22/2013)	133	\$0.00
97572					155	φ0.00
Medium	Work In Progress		1/22/2013 3:52:53 PM	N		
Ontiveros,	Joe	Old gym a/c water supply. Loca install a new shutoff valve. The won't shutoff completely.		Route to Joe asp rea	assignment 4/2/13	
Jaime Mija	arez			-		A <i>c</i> -
93789			10/3/2012	2	244	\$0.00
Medium	Work In Progress		10/3/2012 12:40:25 PM	Л		
Ontiveros,	Joe	boys and girls restroom in the toilet seats as well as the girls hallway.		Route to Joe asp rea	assignment 4/2/13	
Jorge Pere	ez					

WOID Priority Assigned ⁻ Requester	Building Status To	•	e Target Comp Date Days Labor Actual Comp Date Aged Hours Action Taken	Costs
Location:	Santa Te	resa HS		
93711		10/1/2012	2 246	\$0.00
Medium	Work In Progress	10/1/2012 12:03:32 PM	Ν	
Ontiveros,		Restrooms in the main hallway Boy and girls need to adjust or replace toilet seats as well as the restroom in the 300 hallway those need to be replaced.	Route to Joe asp reassignment 4/2/13	
Jorge Pere 99212	Z	3/3/2013	3 93	\$0.00
Medium	Work In Progress	3/3/2013 12:25:56 AN		·
Munoz, Mi	-	Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PM schedule details.		
Margret Vil	llalobos	3/6/2013	3 90	\$0.00
99398 Medium		3/6/2013 10:34:45 AN		φ0.00
Castillo, Ca	Work In Progress arlos	SECURITY GAURDS ARE REQUESTING THAT ALL BURNT OUT LIGHT BULBS BE CHANGED OUT @ FRONT PARKING LOT. THANKS.	vi	
Gerardo M	arquez			
93291		Football Field 9/26/2012	-	\$0.00
Medium	Work In Progress	9/26/2012 3:02:39 PM	М	
Castillo, Ca		Need permanent electrical set-up or better and safer temporary for half-time music.		
Carlos Cas 102850	stillo	6/2/2013	3 6/5/2013 2	\$0.00
Medium	Work In Progress	6/2/2013 12:28:40 A		
Marquez, (C	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.		
Margret Vil	llalobos			
102759		5/31/2013		\$0.00
Medium	Work In Progress	5/31/2013 12:28:40 AN	Л	
Mijarez, Ja		Yearly - Santa Teresa HS A-2 H/C Units Yearly - Refer to PM schedule details.		
Margret Vil 102880	llalobos	6/2/2013	3 7/3/2013 2	\$0.00
Medium	Work In Progress	6/2/2013 12:28:55 A		+ 2.00
	-			
Mijarez, Ja	lime	Yearly - Santa Teresa HS B-2 Boiler Yearly - Refer to PM schedule details.		

WOID Priority Assigned	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Loc Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ad		Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS					
98883		Athletic Field	2/26/2013		98		\$0.00
Medium	Work In Progress		2/26/2013 12:43:31 PM				
Mijarez, Ja		Coach Bailon wanted some paint to dugout. He would like to get 5 gallon ceiling of the dugout is coming apart hammered down.	s of paint. Also the				
William Die 102690	ckson		5/29/2013		6		\$0.00
Medium	Work In Progress		5/29/2013 2:33:08 PM				
Lara, Ralpl	-	need to change cores for July 15th - finishing on the gym floors.	19th due to the re				
Jorge Pere 102878	Z		6/2/2013	6/18/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:28:54 AM	0/10/2010	2		ψ0.00
Villalobos,	C C	Monthly - Santa Teresa HS Monthly to PM schedule details.					
Margret Vil	llalobos						
101675			5/5/2013	5/21/2013	30		\$0.00
Medium	Work In Progress		5/5/2013 12:24:01 AM				
Villalobos,	-	Monthly - Santa Teresa HS Monthly to PM schedule details.	Chiller Insp Refer				
Margret Vil 101945	llalobos	Athletic Field	5/8/2013		27		\$0.00
High	Work In Progress		5/8/2013 3:53:15 PM				
-	Guadalupe	We need a fieldsweaper with groom maintain fields.	er to be able to				
Guadalupe	e Ontiveros						
102659			5/29/2013		6		\$0.00
Medium	Work In Progress		5/29/2013 8:02:48 AM				
Ontiveros,	Guadalupe	W/O 99809 Need 11 curb stops for or be used to keep vehicles of the side clearance for the use of wheelchairs. Dickson.	walk and leave				
Jaime Mija	irez		0/0/0010	4/0/0040			<u> </u>
99241			3/3/2013	4/3/2013	93		\$0.00
Medium	Work In Progress		3/3/2013 12:26:09 AM				
Prospero,	Manuel	Yearly - Santa Teresa HS A-10 HP N schedule details.	early - Refer to PM				
	llalobos						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS					
96808			1/6/2013	1/14/2013	149		\$0.00
Medium	Work In Progress		1/6/2013 12:23:56 AM				
Marquez, (Gerardo	Monthly - Santa Teresa HS Roof PM schedule details.	Inspection - Refer to				
Margret Vi	illalobos		0/04/0040	4/0/2042	05		<u> </u>
100225			3/31/2013	4/8/2013	65		\$0.00
Medium	Work In Progress		3/31/2013 12:32:28 AM				
Marquez, (Monthly - Santa Teresa HS Roof PM schedule details.	Inspection - Refer to				
<u>Margret Vi</u> 101927	llalobos	Athletic Field	5/8/2013		27		\$0.00
High	Work In Progress		5/8/2013 3:25:50 PM				
Vasquez, .	· ·	need repair kit to fix football areas					
<u>Guadalupe</u> 99449	e Ontiveros	correct. for S.T.H.S and G.H.S.	3/7/2013		89		\$0.00
99449 Medium	Work In Progress		3/7/2013 12:56:15 PM		09		φ0.00
Ontiveros,	Guadalupe	Need to paint the sign over the bl field. Colors would be black and to We also need the softball fence c are on the outside. The way it is n	urquoise. hanged so the poles				
William Di	ckson		E/E/2042	6/5/2013	30		¢0.00
101725			5/5/2013	0/5/2013	30		\$0.00
Medium	Work In Progress		5/5/2013 12:24:22 AM				
Mijarez, Ja		Monthly - Santa Teresa HS Bleac to PM schedule details.	her Inspection - Refer				
<u>Margret Vi</u> 101723	illalobos		5/5/2013	5/13/2013	30		\$0.00
Medium	Work In Progress		5/5/2013 12:24:21 AM				
Mijarez, Ja	Ū.	Monthly - Santa Teresa HS Exit S Refer to PM schedule details.					
Margret Vi	illalobos						
101724			5/5/2013	5/13/2013	30		\$0.00
Medium	Work In Progress		5/5/2013 12:24:22 AM				
Mijarez, Ja	aime	Monthly - Santa Teresa HS Emer Refer to PM schedule details.	Light Test: Monthly -				
<u>Margret Vi</u> 102223	illalobos		5/15/2013		20		\$0.00
	Mork In Dramas -				20		ψ0.00
Medium	Work In Progress		5/15/2013 1:37:55 PM				
Mijarez, Ja		Order and Install four 12"x18" sign and visitors parking.	ns at administration				
Jaime Mija							
3/4/2013	9:16:09 AM					Page 1	33 of 160

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Location, Status Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description Created Date/Time A	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS				
100832		4/11/2013		54		\$0.00
Medium	Work In Progress	4/11/2013 10:03:26 AM				
Mijarez, Ja	aime	Boys football room. A piece of sheet metal on the side of the locker is coming off				
Jorge Pere 100277	ez	3/31/2013	4/8/2013	65		\$0.00
Medium	Work In Progress	3/31/2013 12:32:48 AM				
Mijarez, Ja	aime	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.				
Margret Vi 99809	llalobos	3/18/2013		78		\$0.00
Medium	Work In Progress	3/18/2013 10:50:15 AM		-		,
Mijarez, Ja	aime	We need about 11 curb stops for our parking lot. These will be used to keep cars or trucks from parking on the sidewalk, stopping wheelchairs using it. It prevents them from using sidewalk.				
William Die 99182	ckson	3/3/2013	3/11/2013	93		\$0.00
Medium	Work In Progress	3/3/2013 12:25:43 AM				·
Mijarez, Ja	C C	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.				
Margret Vi	llalobos	4/40/0040		407		<u> </u>
97486		1/18/2013		137		\$0.00
Medium Mijarez, Ja	Work In Progress	1/18/2013 11:29:17 AM Weight Room. Heating unit fan motor gave out, please order fan motor with housing if possible. I will take care of installing the new one.				
Jaime Mija 98084	arez	2/3/2013	3/6/2013	121		\$0.00
Medium	Work In Progress	2/3/2013 12:22:38 AM	5, 5, 2010			<i>40.00</i>
Mijarez, Ja	-	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.				
Margret Vi	llalobos	0/0/0040	0/44/0040	404		<u> </u>
98082 Modium	Mork In Dramos	2/3/2013 2/2/2012 12:22:27 AM	2/11/2013	121		\$0.00
Medium	Work In Progress	2/3/2013 12:22:37 AM				
Mijarez, Ja	aime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.				
	llalobos					

	Des	a Number Reason cription	Created Date/Time	Actual Comp Date Action Taken	Aged	Hours	
ocation: S	anta Teresa	HS					
98083			2/3/2013	2/11/2013	121		\$0.00
Medium Work In P	rogress		2/3/2013 12:22:38 AM				
Mijarez, Jaime		nthly - Santa Teresa HS Emer er to PM schedule details.	Light Test: Monthly -				
<u>Margret Villalobos</u> 102938			6/2/2013	6/10/2013	2		\$0.00
Vedium Work In P	roaress		6/2/2013 12:29:22 AM	0, 10, 2010	-		<i>Q</i> 0100
Mijarez, Jaime	Mor	thly - Santa Teresa HS Emer er to PM schedule details.					
Margret Villalobos							
102939			6/2/2013	6/10/2013	2		\$0.00
Medium Work In P	rogress		6/2/2013 12:29:23 AM				
Mijarez, Jaime		hthly - Santa Teresa HS Exit S er to PM schedule details.	ign Insp: Monthly -				
<u>Margret Villalobos</u> 102940			6/2/2013	7/3/2013	2		\$0.00
Medium Work In P	roaress		6/2/2013 12:29:23 AM				·
Mijarez, Jaime	Mor	nthly - Santa Teresa HS Bleac M schedule details.	her Inspection - Refer				
Margret Villalobos			8/24/2012		284		\$0.00
91802 Vledium Work In P	rogrooo		8/24/2012 7:27:50 AM		204		Ф 0.00
Medium Work In P Mijarez, Jaime	Wat not that	er fountain located at the end working. And the water founta connects to the 300 is just sta er cord is connected.	of the 300 hallways is in in the back hall way				
Jorge Perez			9/30/2012	10/8/2012	247		\$0.00
93586				10/0/2012	247		Ф 0.00
Medium Work In P Mijarez, Jaime	Mor	nthly - Santa Teresa HS Exit S	9/30/2012 12:31:09 AM Sign Insp: Monthly -				
Margret Villalobos	Rei	er to PM schedule details.					
93587			9/30/2012	10/8/2012	247		\$0.00
Medium Work In P	rogress		9/30/2012 12:31:09 AM				
Mijarez, Jaime		nthly - Santa Teresa HS Emer er to PM schedule details.	Light Test: Monthly -				
<u>Margret Villalobos</u> 93588			9/30/2012	10/31/2012	247		\$0.00
Vedium Work In P	roaress		9/30/2012 12:31:09 AM	10/01/2012	<u>-</u> 71		ψ0.00
Mijarez, Jaime	Mor	nthly - Santa Teresa HS Bleac M schedule details.					
Margret Villalobos	10 P						
6/4/2013 9:16:09 AM						Page 1	35 of 160

WOID Priority Assigned Requester		AreaDeferred ByUntilRequest Date TArea NumberReasonCreated Date/Time ADescription	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS				
92249		9/2/2012	9/10/2012	275		\$0.00
Medium	Work In Progress	9/2/2012 12:21:37 AM				
Mijarez, Ja	aime	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vi	llalobos					
103046		Classroom 6/3/2013		1		\$0.00
Medium	Work In Progress	6/3/2013 9:20:18 PM				
Ronquillo,	Ruben	Drama classroom exterior entrance door glass is broken due to vandalism. sizes are 6 3/4" x 40 3/4"				
		Drama Classroom exterior entrance door glass is broken due to vandalism Size is 6 3/4"x 40 3/4".				
<u>Jaime Mija</u> 102915	arez	6/2/2013		2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:12 AM		2		φ0.00
Marquez,		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret Vi	llalobos					
100284		3/31/2013		65		\$0.00
Medium	Work In Progress	3/31/2013 12:32:51 AM				
Marquez,		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret Vi 99598	llalobos	3/12/2013		84		\$0.00
Medium	Work In Progress	3/12/2013 2:53:51 PM				<i>40.00</i>
	C C					
Marquez,	Gerardo	Room 807 is used to fire up ceramic bowls and they use clay. The teacher needs a 200 ft water hose to water down the room and remove the clay. He would be using the custodian closet to hook up the hose.				
William Di	ckson	8/21/2012		287		\$0.00
91609				201		φ0.00
Medium	Work In Progress	8/21/2012 9:55:17 AM				
Marquez,	Gerardo	NEED TO REPLACE WINDOW BLINDS IN 300 WING.				
Gerardo M	larquez					

WOID Priority Assigned Requester			Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS						
91619				8/21/2012		287		\$0.00
Medium	Work In Progress	MARY		8/21/2012 12:09:36 PM				
Marquez, C	Gerardo	NEED TO HAVE BACK OF LIBR		RRORS HUNG IN				
Marylou Jir 96225	menez			12/4/2012		182		\$0.00
Medium	Work In Progress			12/4/2012 9:24:33 AM				ψυισσ
Marquez, C	•		ACE BURNT OU OSET 300 WING	T LIGHT BULBS IN				
Gerardo M	arquez			1/20/2012		100		¢0.00
97814				1/29/2013		126		\$0.00
Medium	Work In Progress			1/29/2013 10:04:07 AM				
Marquez, C	Gerardo			URE IN STORAGE DUGOUT. THANKS.				
<u>Gerardo M</u> 100879	arquez			4/12/2013		53		\$0.00
Medium	Work In Progress			4/12/2013 9:00:24 AM				
Marquez, C	•	NEED TO SER	/ICE AC'S FOR C	OOLING SEASON.				
Gerardo M								
93178		Classroom		9/24/2012		253		\$0.00
Medium	Work In Progress	VARIETY OF		9/24/2012 2:38:32 PM				
Marquez, C		MOUNTED ON MR. RINCON R MR. FELIX ROO MR. STOUT RO RECEPTIONIST MR. BAILEY RO MR. CHAMPAG BRACKETS	OOM #801 2 BRA OM #505 2 BRACI OM #509 2 BRAC T AREA NEEDS 2 OOM #406 NEEDS	SSROOM FLAGS: ACKETS KETS CKETS BRACKETS S 2 BRACKETS DRTABLE NEEDS 2				
Marylou Jir 99165	nenez			3/3/2013		93		\$0.00
Medium	Work In Progress			3/3/2013 12:25:35 AM				
Marquez, C	Gerardo	Monthly - Santa Refer to PM sch		nes Dryer (Monthly) -				
Margret Vil	lalobos			0/5/0040		272		¢0.00
92398 Madium				9/5/2012 0/5/2012 7:20:21 AM		272		\$0.00
Medium	Work In Progress			9/5/2012 7:39:21 AM				
Marquez, C	erardo	3 urinals in the c water when flus		n stand are leaking				

WOID Priority Assigned Requester		Area Deferred By U Area Number Reason Description	ntil Request Date Ta Created Date/Time A	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa HS					
92657			9/11/2012		266		\$0.00
Medium	Work In Progress		9/11/2012 8:11:10 AM				
Marquez,	Gerardo	need to replace 2 ceiling tiles in the mai in room 403. No ceiling tiles are in place over the weekend.					
Jorge Pere 99913	ez		3/20/2013		76		\$0.00
Medium	Work In Progress		3/20/2013 9:43:26 AM				• • • •
Estrada, J	Ū	NEED (2) GYM FLOORS TO BE RE-FI APPROX. L 135' X 116' -W; AUXILIA W)					
Jesus Est		04:	E/20/2042				¢0.00
102713	Main Building	Office	5/30/2013		5		\$0.00
Medium	Work In Progress		5/30/2013 7:41:10 AM				
Gonzales,	Camilo	Please deliver 5 boxes for Po 12130728 pack.	38. Pulse 360 32				
Larry Mart 102717	inez Main Building	Office	5/30/2013		5		\$0.00
Medium	Work In Progress	Onice	5/30/2013 7:53:32 AM		5		ψ0.00
Gonzales,	Ū	Please deliver 12 boxes of Science Equ 121307022					
Larry Mart			E/21/2012		11		¢0.00
102440	Main Building		5/21/2013		14		\$0.00
Medium	Work In Progress		5/21/2013 2:29:58 PM				
Marquez,	Gerardo	Ms. Pope, teacher in the science hall ha that were disected. She needs for them her classroom safely.					
William Di		Classroom	9/28/2012		249		\$0.00
93402 Medium	Main Building	Classroom			249		φ0.00
	Work In Progress		9/28/2012 2:23:27 PM				
Marquez,	Gerardo	There was an announcement made by reference to some tables and chairs. We get a few of them. We would like to get and 4 round tables.	e would like to				
William Di 97488	ckson Main Building	Office	1/18/2013		137		\$0.00
Medium	Work In Progress		1/18/2013 11:39:50 AM		-		,
Marquez,	Ŭ	Need to get the Social Workers office pa					
-							
William Di	UKSUH						

Location: Santa Teresa HS 100662 Gymnasium Gym 4/7/2013 58 100662 Gymnasium Gym 4/7/2013 4:34:14 PM Marquez, Gerardo The roof that wholes the al conditioner over the old gym needs repair. Need new plywood and a facia board. It has decayed and looks ugly. 1 William Dickson 102598 Gymnasium Auditorium 5/28/2013 7 Medium Work In Progress 5/28/2013 7 1 William Dickson 102598 Gymnasium Auditorium 5/28/2013 8:18:58 AM Carrasco, Danny We would like to put up some banners and pictures in the gym and cafeteria. Will we be able to get the lift second week in July. Thank you! 19 William Dickson 5/16/2013 19 102254 Vocational 5/16/2013 19 High Work In Progress 5/16/2013 19 Bistall new one and test when complete. 100254 10 10 Munoz, Michael while repairing the sprinkler system dimar brought it to my attention that the backflow preventer was leaking and not working properity. recommendation is to remove, install new one and test when complete. 10 Mildam Dickson	Da Ag	arget Comp Date ctual Comp Date Action Taken	Cos ays Labor jed Hours
Medium Work In Progress 4/7/2013 4:34:14 PM Marquez, Gerardo The roof that wholes the air conditioner over the old gym needs repair. Need new plywood and a facia board. It has decayed and looks ugly. William Dickson			
Marquez, Gerardo The root that wholes the air conditioner over the old gym needs repair. Need new plywood and a facia board. It has decayed and looks ugly. William Dickson 6/28/2013 102598 Cymnasium Medium Work In Progress Carrasco, Damy We would like to put up some banners and pictures in the gym and cafeteria. Will we be able to get the lift second week in July. Thank you! William Dickson 5/16/2013 8:18:58 AM 102254 Vocational High Work In Progress S/16/2013 5/16/2013 8:08:44 AM Munoz, Michael while repairing the sprinkler system dimar brought it to my attention that the backflow preventer was leaking and not working properly, recommendation is to remove, install new one and test when complete. Michael Munoz Bergan unit on the roof sounds like it is about to explode. Can we have soneone look at it Thanks! William Dickson 10/30/2012 94785 Locker Room Medium Work In Progress 102207 GYM (2009) S/16/2013 9.26.22 AM Medium Work In Progress 102207 GYM (2009) S/16/2013 2.0 William Dickson 10/30/2012 William Dickson 10/30/2012 William Dickson 10/30/2012 William Dickson 10/30/2013	5		58 \$0.0
william Dickson 5/28/2013 7 102598 Gymnasium Auditorium 5/28/2013 8:18:58 AM Carrasco, Danny We would like to put up some banners and pictures in the gym and cafeteria. Will we be able to get the lift second week in July. Thank you! 19 William Dickson 5/16/2013 8:08:44 AM Munoz, Michael while repairing the sprinkler system dimar brought it to my attention that the backflow preventer was leaking and not working property, recommendation is to remove, install new one and test when complete. 110 Michael Work In Progress 2/14/2013 110 Medium Work In Progress 2/14/2013 110 Medium Work In Progress 2/14/2013 120 Michael while repairing the sprinkler system dimar brought it to my attention that the backflow preventer was leaking and not working property, recommendation is to remove, install new one and test when complete. 110 Michael Work In Progress 2/14/2013 120 Migarez, Jaire The fan unit on the roof sounds like it is about to explode. Can we have soneone look at it Thanks! 10/30/2012 217 William Dickson Interplay the dugouts for both the boys and the girls. The players will paint both dugouts. 20 5/15/2013 20 William Dickson Interplay the gym. 5/15/2013 20 21 William Dic			
102598 Gymnasium Auditorium 5/28/2013 7 Medium Work In Progress 5/28/2013 8:18:58 AM Carrasco, Danny We would like to put up some banners and pictures in the gym and carteria. Will we be able to get the lift second week in July. Thank you! 19 William Dickson 5/16/2013 19 High Work In Progress 5/16/2013 19 Munoz, Michael while repairing the sprinkler system dimar brought it to my attention that the backflow preventer was leaking and not working property. recommendation is to remove, install new one and test when complete. 110 Michael Munoz 98549 Main Building 2/14/2013 110 Medium Work In Progress 2/14/2013 110 Medium Work In Progress 10/30/2012 217 Medium Work In Progress 10/30/2012 217 Medium Work In Progress 10/30/2012 217 Medium Work In Progress 5/15/2013 20 Marquez, Gerardo Need paint for the dugouts for both the boys and the girts. The players will paint both dugouts. 21 William Dickson 10/2070 5/15/2013 20 Medium			
Carrasco, Danny We would like to put up some banners and pictures in the gym and cafeteria. Will we be able to get the lift second week in July. Thank you! William Dickson 5/16/2013 19 102254 Vocational 5/16/2013 808.44 AM Munoz, Michael while repairing the sprinkler system dimar brought it to my attention that the backflow preventer was leaking and not working properly. recommendation is to remove, install new one and test when complete. Michael Work In Progress 2/14/2013 110 Medium Work In Progress 2/14/2013 5:26:36 PM 10 Mijarez, Jaime The fan unit on the roof sounds like it is about to explode. Can we have soneone look at it Thanks! 10/30/2012 217 William Dickson 10/30/2012 3:14:53 PM 10 20 94785 Looker Room 10/30/2012 217 Medium Work In Progress 5/15/2013 20 William Dickson 10/2007 5/15/2013 20 William Dickson server of the dugouts for both the boys and the girls. The players will paint both dugouts. 20 William Dickson 10/2007 5/15/2013 20 Medium Work In Progress 5/15/2013 9:25:22 AM 20 Munoz,			7 \$0.0
William Dickson 5/16/2013 19 High Work In Progress 5/16/2013 8:08:44 AM Munoz, Michael while repairing the sprinkler system dimar brought it to my attention that the backflow preventer was leaking and not working properly. recommendation is to remove, install new one and test when complete. 100 Michael Munoz 98549 Main Building 2/14/2013 110 Medium Work In Progress 2/14/2013 5:26:36 PM 110 Mijarez, Jaime The fan unit on the roof sounds like it is about to explode. Can we have soneone look at it Thanks! 10/30/2012 217 William Dickson 94785 Locker Room 10/30/2012 217 Medium Work In Progress 5/15/2013 20 Munoz, Joe need to repair the porch on the north and west side of the gym. 10 Munoz, Joe need to repair the porch on the north and west side of the gym. 21 <			
102254Vocational5/16/201319HighWork In Progress5/16/2013 8.08:44 AMMunoz, Michaelwhile repairing the sprinkler system dimar brought it to my attention that the backflow preventer was leaking and not working properly. recommendation is to remove, install new one and test when complete.MichaelWork In ProgressMichael2/14/2013MediumWork In ProgressVolta100MediumWork In ProgressMijarez, JairThe fan unit on the roof sounds like it is about to explode. Can we have soneone look at it Thanks!William Dickson10/30/201294785Locker RoomMarquez, GerardoNeed paint for the dugouts for both the boys and the girls. The players will paint both dugouts.William Dickson10/30/2012 3:14:53 PMMunoz, Jueneed to repair the porch on the north and west side of the gym.Alfredo HolguinGYM (2009)5/15/2013 9:25:22 AMMunoz, Jueneed to repair the porch on the north and west side of the gym.Alfredo HolguinGYM (2009)Munoz, JueS/14/2013 7:58:34 AMCastillo, CarlosS/14/2013 7:58:34 AMCastillo, CarlosAs per security dept, front of gym very dark.Most light fixtures are out.			
High Work In Progress 5/16/2013 8:08:44 AM Munoz, Michael while repairing the sprinkler system dimar brought it to my attention that the backflow preventer was leaking and not working properly. recommendation is to remove, install new one and test when complete. Michael Munoz	1		9 \$0.0
Munoz, Michael while repairing the sprinkler system dimar brought it to my attention that the backflow preventer was leaking and not working properly. recommendation is to remove, install new one and test when complete. Michael Munoz 98549 Main Building 2/14/2013 110 Medium Work In Progress 2/14/2013 5:26:36 PM 100 Mijarez, Jaime The fan unit on the roof sounds like it is about to explode. Can we have soneone look at it Thanks! 10/30/2012 217 William Dickson 94785 Locker Room 10/30/2012 217 Medium Work In Progress 10/30/2012 3:14:53 PM 10 Marquez, Gerardo Need paint for the dugouts for both the boys and the girls. The players will paint both dugouts. 20 William Dickson 10/2007 5/15/2013 20 Wedium Work In Progress 5/15/2013 9:25:22 AM 20 Munoz, Joe need to repair the porch on the north and west side of the gym. 10 21 Alfredo Holguin 102144 GYM (2009) 5/14/2013 7:58:34 AM 21 Medium Work In Progress 5/14/2013 7:58:34 AM 21 Medium Work In Progress 5/14/2013 7:58:34 AM 21 <td>•</td> <td></td> <td>φο.</td>	•		φο.
98549 Main Building 2/14/2013 110 Medium Work In Progress 2/14/2013 5:26:36 PM 110 Mijarez, Jaime The fan unit on the roof sounds like it is about to explode. Can we have soneone look at it Thanks! 110 William Dickson 94785 Locker Room 10/30/2012 217 Medium Work In Progress 10/30/2012 3:14:53 PM 214/2013 217 Medium Work In Progress 10/30/2012 3:14:53 PM 20 Marquez, Gerardo Need paint for the dugouts for both the boys and the girls. The players will paint both dugouts. 20 William Dickson 5/15/2013 20 102207 GYM (2009) 5/15/2013 9:25:22 AM Munoz, Joe need to repair the porch on the north and west side of the gym. Alfredo Holguin 102144 GYM (2009) 5/14/2013 7:58:34 AM Castillo, Carlos As per security dept.,front of gym very dark.Most light fixtures are out. 5/14/2013 7:58:34 AM			
Medium Work In Progress 2/14/2013 5:26:36 PM Mijarez, Jaine The fan unit on the roof sounds like it is about to explode. Can we have soneone look at it Thanks! William Dickson 94785 94785 Locker Room 94785 Locker Room Morguez, Gerardo Need paint for the dugouts for both the boys and the girls. The players will paint both dugouts. William Dickson 10/2007 102207 GYM (2009) Medium Work In Progress 5/15/2013 20 Medium Work In Progress 102207 GYM (2009) 5/15/2013 20 Medium Work In Progress 5/15/2013 9:25:22 AM Munoz, Joe need to repair the porch on the north and west side of the gym. Alfredo Holguin 102144 GYM (2009) 5/14/2013 21 Medium Work In Progress 5/14/2013 21 Medium Work In Progress 5/14/2013 21 Alfredo Holguin As per security dept., front of gym very dark.Most light 21 Medium Work In Progress 5/14/2013 7:58:34 AM 21	44		0
Mijarez, JaimeThe fan unit on the roof sounds like it is about to explode. Can we have soneone look at it Thanks!William Dickson94785Locker Room10/30/2012217MediumWork In Progress10/30/2012 3:14:53 PM217Marquez, GerardoNeed paint for the dugouts for both the boys and the girls. The players will paint both dugouts.10William Dickson10/20075/15/201320MediumWork In Progress5/15/2013 9:25:22 AM20MediumWork In Progress5/15/2013 9:25:22 AM10Munoz, Joeneed to repair the porch on the north and west side of the gym.5/14/2013 9:25:22 AM21Alfredo Holguin102144GYM (2009)5/14/2013 2121MediumWork In Progress5/14/2013 7:58:34 AM21MediumWork In ProgressS/14/2013 7:58:34 AM21Castillo, CarlosAs per security dept.,front of gym very dark.Most light fixtures are out.As per security dept.,front of gym very dark.Most light fixtures are out.10	11		0 \$0.0
94785Locker Room10/30/2012217MediumWork In Progress10/30/2012 3:14:53 PMMarquez, GerardoNeed paint for the dugouts for both the boys and the girls. The players will paint both dugouts.William Dickson5/15/2013102207GYM (2009)MediumWork In ProgressMunoz, Joeneed to repair the porch on the north and west side of the gym.Alfredo Holguin5/14/2013102144GYM (2009)MediumWork In ProgressAlfredo Holguin5/14/2013Castillo, CarlosAs per security dept., front of gym very dark. Most light fixtures are out.			
MediumWork In Progress10/30/2012 3:14:53 PMMarquez, GerardoNeed paint for the dugouts for both the boys and the girls. The players will paint both dugouts.William Dickson	04		7 00
Marquez, GerardoNeed paint for the dugouts for both the boys and the girls. The players will paint both dugouts.William Dickson5/15/2013102207GYM (2009)MediumWork In ProgressMunoz, Joeneed to repair the porch on the north and west side of the gym.Alfredo Holguin102144102144GYM (2009)MediumWork In ProgressAudiumWork In ProgressAlfredo Holguin5/14/2013102144GYM (2009)Statillo, CarlosAs per security dept., front of gym very dark. Most light fixtures are out.	21		7 \$0.0
William Dickson 5/15/2013 20 102207 GYM (2009) 5/15/2013 9:25:22 AM Medium Work In Progress 5/15/2013 9:25:22 AM Munoz, Joe need to repair the porch on the north and west side of the gym. Alfredo Holguin 102144 GYM (2009) 102144 GYM (2009) 5/14/2013 Medium Work In Progress 5/14/2013 7:58:34 AM Castillo, Carlos As per security dept., front of gym very dark. Most light fixtures are out.			
102207GYM (2009)5/15/201320MediumWork In Progress5/15/2013 9:25:22 AMMunoz, Joeneed to repair the porch on the north and west side of the gym.102144Alfredo Holguin5/14/201321102144GYM (2009)5/14/2013 7:58:34 AMMediumWork In Progress5/14/2013 7:58:34 AMCastillo, CarlosAs per security dept., front of gym very dark. Most light fixtures are out.			
Medium Work In Progress 5/15/2013 9:25:22 AM Munoz, Joe need to repair the porch on the north and west side of the gym. Alfredo Holguin 7/14/2013 102144 GYM (2009) Medium Work In Progress S/14/2013 7:58:34 AM Castillo, Carlos As per security dept., front of gym very dark. Most light fixtures are out.			0.000
Munoz, Joe need to repair the porch on the north and west side of the gym. Alfredo Holguin 102144 GYM (2009) 5/14/2013 Medium Work In Progress Castillo, Carlos As per security dept.,front of gym very dark.Most light fixtures are out.	2		20 \$0.0
102144 GYM (2009) 5/14/2013 21 Medium Work In Progress 5/14/2013 7:58:34 AM Castillo, Carlos As per security dept.,front of gym very dark.Most light fixtures are out. 4			
Medium Work In Progress 5/14/2013 7:58:34 AM Castillo, Carlos As per security dept., front of gym very dark. Most light fixtures are out.	<u></u>		21 \$0.0
Castillo, Carlos As per security dept.,front of gym very dark.Most light fixtures are out.	2		. 1 \$0.0
fixtures are out.			
Carlos Castillo			

Assigned 1 Requester		Area Number Reason Description	Created Date/Time	Actual Comp Date Action Taken	Aged	Hours	
Location:	Santa Ter	resa HS					
99235			3/3/2013		93		\$0.00
Medium	Work In Progress		3/3/2013 12:26:07 AM				
Munoz, Mic	shael	Yearly - Santa Teresa HS Fire Ex to PM schedule details.	t. Insp. (Yearly) - Refer				
Margret Vill 100373	lalobos		3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress		3/31/2013 12:33:27 AM				
Orozco, Da	C C	Monthly - Santa Teresa HS Range Refer to PM schedule details.					
Margret Vil	lalobos		6/2/2013	6/8/2013	2		\$0.00
102972 Medium	Work In Progress		6/2/2013 12:29:38 AM		2		φ0.00
Marquez, G	c	Monthly - Santa Teresa HS Month Refer to PM schedule details.					
Margret Vil	lalobos		0/04/0040	4/0/004.0	05		<u> </u>
100354			3/31/2013	4/6/2013	65		\$0.00
Medium Marquez, G	Work In Progress Gerardo	Monthly - Santa Teresa HS Month Refer to PM schedule details.	3/31/2013 12:33:18 AM hly FE Inspection -				
Margret Vil	lalobos		4/04/0040		404		
97918 Madium			1/31/2013		124		\$0.00
Medium Marquez, G	Work In Progress Gerardo	NEED TO REPLACE 13 BROKEN COVERS @ FIRE EXTINGUISHE NEED TO REPLACE TAGS. 36 T	ER STATIONS. ALSO				
Gerardo Ma	arquez		3/3/2013	2/0/2012	02		\$0.00
99167 Maalii waa				3/9/2013	93		\$ 0.00
Medium Marquez, G	Work In Progress Gerardo	Monthly - Santa Teresa HS Month Refer to PM schedule details.	3/3/2013 12:25:36 AM hly FE Inspection -				
Margret Vil	lalobos						
100054			3/25/2013		71		\$0.00
Medium	Work In Progress		3/25/2013 1:51:22 PM				
Carbajal, Ji	-	Extractor #9909 and 2261 need so low suction and spayer doesnt sp		reminded Jorge that an individual work o		achine nee	∋ds
Jorge Pere 100666	Ζ		4/8/2013		57		\$0.00
Medium	Work In Progress		4/8/2013 7:47:20 AM				
Carbajal, Ji	-	Extractor # 2261 is not working pr suction and the sprayer isnz't spra	operly, has weak				

WOID Priority Assigned 1 Requester		Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken		Cos abor ours
Location:	Santa Te	resa HS				
94151			10/15/2012		232	\$0.0
Medium	Work In Progress		10/15/2012 11:32:27			
Lara, Ralph	1	The electeic stops that hold the door area needs extensive repair before s holders are falling off the wall.				
William Dic 99572	kson	Gym	3/12/2013		84	\$0.0
High	Work In Progress	-)	3/12/2013 7:31:19 AM			••••
Lara, Ralph	•	magnetic doors by the old gym are r affecting the fire alarm.please check completed let sylver in technology kr	not working and and repair.once			
Michael Mu 99808	INOZ		3/18/2013		78	\$0.0
Medium	Work In Progress		3/18/2013 10:44:37 AM		10	ψoιι
Briones, Er	nrique	We need a big truck here at ST to ha unwanted chairs,sofas, and desk loc vocational area. Would like to get thi spring break.	ated in the			
William Dic 97001	kson		1/8/2013		147	\$0.0
Medium	Work In Progress		1/8/2013 9:18:30 AM			ψ0.
Gonzalez, S	•	Railling to exterior stairway going fro rooms to concession stand was dam remove it, might need to fabricate a possible.	m athletic dressing aged. We had to			
Jaime Mija	rez		0/00/0010			
98875		Athletic Field	2/26/2013		98	\$0.0
Medium	Work In Progress		2/26/2013 10:39:16 AM			
Marquez, G	Gerardo	Last year the concession stand door and coach would like to replace it wi safety. Need to be installed soon. Thanks!		2/28 - Route to Gerr	y asp Mike	
William Dic	kson		4/0/0040			
100680			4/8/2013		57	\$0.0
Medium	Work In Progress		4/8/2013 1:16:13 PM			
Gonzalez, S	Salvador	(Guard shack) Mr. Dickson wants tw welded on one post and hook on the will run across both post to stop visit collect visitor badges.	other post. Chain			
Jaime Mija	rez					

	Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status							Total
WOID	Building		Deferred By	Until	Request Date Target Co	np Date Days	Labor	Costs
Priority	Status	Area Number	Reason	Cre	ated Date/Time Actual Con	np Date Aged	Hours	
Assigned	То	Description	Action Taken		n Taken			
Requeste	r Name							
Location:	Santa Te	resa HS						
93073					9/20/2012	257		\$0.00
Medium	Work In Progress			9/20/2	2012 12:56:13 PM			
Orozco, D	Daniel	ECO LAB IT H	DISHWASHER NO AS TO DO WITH T NP MANAGER OL	HE WATER	, -			
Maritza G Count: 93	onzalez Work Orders	A	vg. Age of WO's	103	Total for Sar	nta Teresa HS	0	\$0.00

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By Reason	Until Request Date Ta Created Date/Time A	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa MS						
102961				6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:32 AM				
Prospero,	Manuel	Monthly - Santa Refer to PM sch		thly FE Inspection -				
Margret Vil 100374	lalobos			3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress			3/31/2013 12:33:27 AM	4/21/2013	00		ψ0.00
Orozco, Da	C C	Monthly - Santa Refer to PM sch		ge Hood Cleaning -				
Margret Vil 99230	lalobos			3/3/2013		93		\$0.00
Medium	Work In Progress			3/3/2013 12:26:04 AM		00		ψ0.00
Munoz, Mi	C C	Yearly - Santa T to PM schedule		xt. Insp. (Yearly) - Refer				
Margret Vil								
97445	North Building	Classroom		1/17/2013		138		\$0.00
Medium	Work In Progress	BAND ROOM		1/17/2013 8:41:54 AM				
Gonzalez,		REQUESTING I		E OUTSIDE BAND				
Laura Parr 102792	a North Building	Office		5/31/2013		4		\$0.00
Medium	Work In Progress			5/31/2013 7:52:11 AM				
Gonzales,	Camilo	Please deliver 3 121306950.	3 boxes of TI Ca	culators for PO				
Larry Marti 102809	nez North Building	Kitchen		5/31/2013		1		\$0.00
	-	Richen				4		ψ0.00
Medium Orozco, Da	Work In Progress aniel	also all the freez the where the ward classrooms in th	ers, carts etc. the alk in refrigerator	Let me know if you				
Rafael Gal				-				A
102810	North Building	Kitchen		5/31/2013		4		\$0.00
Medium	Work In Progress			5/31/2013 8:46:40 AM				
Orozco, Da	aniel	also all the freez the where the ward classrooms in th	ers, carts etc. the alk in refrigerator	Let me know if you				
		2 I						

VOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ac	· · · · ·	Labor Hours	Costs
Location:	Santa Te	resa MS				
101403	North Building	Custodial	4/29/2013	36		\$0.00
Medium	Work In Progress		4/29/2013 8:51:33 AM			
Carbajal,	limmy	Jimmy I need a pouch for cell pho	one.			
<u>Ismael Ro</u> 102485	driguez North Building	Classroom	5/22/2013	13		\$0.00
Medium	Work In Progress	P 2A	5/22/2013 2:37:29 PM			
Estrada, J	esus	CARPET IS TORN AND WORN POSSIBLE	OUT REPLACE IF			
Laura Pari 101905	ra North Building	Stairway	5/8/2013	27		\$0.00
Medium	Work In Progress	,	5/8/2013 8:19:54 AM			
Soria, Mike	0	Remove sand from exterior stairv custodians will help.	vays on play grounds			
Ismael Ro						
100414	North Building	Classroom	4/2/2013	63		\$0.00
Medium	Work In Progress	ROOM 1	4/2/2013 9:13:51 AM			
Estrada, J	esus	TILE FOR BARE AREA				
Laura Pari 102579	ra North Building	Classroom	5/24/2013	11		\$0.00
Medium	-	ROOM 2	5/24/2013 12:07:02 PM			ψ0.00
Prospero,	Work In Progress Manuel	1. MOUNT SMART BOARD WHE 2. MOUNT BLACKBOARD NEXT	ERE BLACKBOARD IS.			
Laura Pari 102813	ra North Building	Restroom (Girls)	5/31/2013	4		\$0.00
Medium	Work In Progress	CAFETERIA	5/31/2013 9:20:03 AM	т. Т		ψ0.00
	0					
Prospero,		PARTITIONS NEED TO BE REP	LAGED			
Laura Pari 102812	ra North Building	Restroom (Boys)	5/31/2013	4		\$0.00
Medium	Work In Progress	CAFETERIA	5/31/2013 9:18:49 AM			
Prospero,	Manuel	PARTITIONS NEED TO BE REP	LACED			
Laura Pari	a					
102581	North Building	Classroom	5/24/2013	11		\$0.00
Medium	Work In Progress	ROOM1	5/24/2013 1:24:11 PM			
Prospero,	Manuel	COMPLETE TILE WORK IN THE	CLASSROOM			
Laura Pari	a					

WOID Priority Assigned ⁻		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	, .	Labor Hours	Costs
Requester	Name							
Location:	Santa Te	resa MS						
101930	North Building	Classroom		5/8/2013		27		\$0.00
Medium	Work In Progress	ROOM 12		5/8/2013 3:30:22 PM				
Prospero,		PLACED IN RO	D STORED IN 484 DOM 12CRAVEN OOK ROOM SOU	S RACK TO HOLD				
Laura Parr 100421	a North Building	Classroom		4/2/2013		63		\$0.00
Medium	Work In Progress	ROOM 1		4/2/2013 9:25:50 AM				
	0							
Prospero,		SET UP NEW	TEACHER'S DESI	X				
Laura Parr 90600	a North Building	Cafeteria		8/2/2012		306		\$0.00
Medium	Work In Progress			8/2/2012 1:41:31 PM				
Prospero, I	C C		UNID NEED TO C PUMP. IS NOT W	CHANGED				
Manuel Pro								
103005	North Building	Custodial		6/3/2013		1		\$0.00
Medium	Work In Progress			6/3/2013 12:19:55 PM				
Lara, Ralpl	h	Off Master Ban	d Room as per pri	ncipal.				
Ismael Roo	driguez							
103006	North Building	Custodial		6/3/2013		1		\$0.00
Medium	Work In Progress			6/3/2013 12:22:10 PM				
Lara, Ralpl	h	Rey key trophy	cabnit.					
Ismael Roo	driguez			40/40/0040		007		<u> </u>
93976	North Building	Hallway/Corrid	or	10/10/2012		237		\$0.00
Medium	Work In Progress			10/10/2012 7:29:44 AM				
Castillo, Ca			ical outlet where the north upper level w	ne water fountains vires expose thanks				
Ismael Roo 99450	North Building			3/7/2013		89		\$0.00
Medium	Work In Progress			3/7/2013 1:33:45 PM				
Ontiveros,	-	grounds north	and south there are	rater fountains on play e two old ones that	Route to Joe asp rea	assignment	: 4/2/13	
Ismael Roo	driquez	need to be eith	er fix or replace the	alin yuu				
102460	South Building	Classroom		5/22/2013		13		\$0.00
Medium	Work In Progress	ROOM 35		5/22/2013 8:32:29 AM	l			
Lara, Ralpl			EY FOR ROOM 3 RAPY- (915) 479-	5- SUSAN GRISWOLD 1199				
Laura Parr	а							

6/4/2013 9:16:10 AM

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Loca Area Deferred By Area Number Reason Description	Until Request Date Target Comp Date Created Date/Time Actual Comp Date Action Taken		Labor Hours	Costs
Location:	Santa Te	resa MS				
102461	South Building	Classroom	5/22/2013	13		\$0.00
Medium	Work In Progress	ROOM 35	5/22/2013 8:33:46 AM			
Lara, Ralp	h	TALL TWO DOOR LOCKER DOES N PLEASE REPAIR NEED TO LOCK				
Laura Pari 102811	ra South Building	Classroom	5/31/2013	4		\$0.00
Medium	Work In Progress	ROOM 35	5/31/2013 8:47:04 AM			•
Lara, Ralp	h	KAREN GRISWOLD- FOUND KEY F DO NOT DUPLICATE *** DO NOT CHARGE FOR LOST KE	OR ROOM 35			
Laura Pari 101027	South Building	Classroom	4/17/2013	48		\$0.00
Medium	Work In Progress		4/17/2013 2:37:44 PM			
Ambriz, Jo	ose	WE LOOSE COMUNICATION SOUT UNIDS.	TH BUILDING			
Manuel Pr 91685	ospero South Building	Restroom (Boys)	8/22/2012	286		\$0.00
Medium	Work In Progress		8/22/2012 10:58:29 AM			·
Prospero,	Ū	Broken water valve to flushvalve need				
Manuel Pr						
102814	South Building	Library	5/31/2013	4		\$0.00
Medium	Work In Progress	LIBRARY	5/31/2013 9:23:03 AM			
Rodriguez		UPHOLSTERY ON CHAIRS, SOFAS CHAIRS NEED TO BE STEEMED CI				
Laura Pari 98947	ra Gym (1997)	Athletic Field	2/27/2013	97		\$0.00
Medium	Work In Progress		2/27/2013 2:27:05 PM			
Ontiveros.	Guadalupe	CENTER CIRCLE FOR TRACK AND				
Laura Pari	·					
102574	Gym (1997)	Gym	5/24/2013	11		\$0.00
Medium	Work In Progress	BOYS LOCKER	5/24/2013 10:36:46 AM			
Prospero,	Manuel	 REMOVE LOCKERS 395-502 AND LOCATED IN SOUTH BUILDING. REMOVE LOCKERS FROM BOYS AS WELL AS THE CAGE STORAGE REPLACE LOCKERS WITH LOCKED FROM SOUTH BLDG. 	S LOCKER ROOM S IN THE CAGE.			
	ra					

Priority Assigned	Building Status To	Area Area Number Description	Deferred By Reason	Until Request Date T Created Date/Time A	arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester	Name							
Location:	Santa Te	resa MS						
102580	Gym (1997)	Gym		5/24/2013		11		\$0.00
Medium	Work In Progress			5/24/2013 12:08:01 PM				
Prospero,	Manuel		OP HALF ALL ON UP ON BLACK	IE COLOR (VANILLA				
Laura Parr 97526	r <u>a</u> Gym (1997)			1/22/2013		133		\$0.00
Medium	Work In Progress			1/22/2013 7:56:32 AM		100		ψ0.00
Prospero,	C	remaining ones	missing hvac louv . will need to repla l clean the larger 2	ers and clean the				
Michael Mi 99911	unoz			3/20/2013		76		\$0.00
						70		φ0.00
Medium	Work In Progress			3/20/2013 9:38:18 AM				
Estrada, Je		NEED GYM FL L 105' X 85' -'		FINISHED (APPROX.				
Jesus Estr 102815	Library	Library		5/31/2013		4		\$0.00
Medium	Work In Progress	LIBRARY		5/31/2013 10:07:54 AM				
Lara, Ralp	h	PIECE ON ENE 2. TOP HINGE LOOSENS 3. OFFICE CLC	ON ENTRY DOOR D KEEPS FALLING ON LEFT SIDE E DSET DOOR IS LO SCREWS TO TI	NTRY DOOR DOSE AND MAY				
Laura Parr	a	Classroom		8/20/2012		200		¢0.00
91549		Classroom		8/20/2012		288		\$0.00
	Work In Progress	ROOM 1		8/20/2012 12:21:59 PM				
Prospero,			/EL DISPENSER S ON BARE CON					
Laura Parr 100052	a			3/25/2013		71		\$0.00
Medium	Work In Progress			3/25/2013 12:25:01 PM				
Prospero,	-	I NEED MANIF PRESSURES I	ULD GAUGES FC N A/C UNITS					
		LORENZO SO	LIS					
Manuel Pro	ospero							
102932				6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:20 AM				
Prospero,	Manuel	Monthly - Santa to PM schedule		cher Inspection - Refer				

Priority Status Assigned To Requester Name	g Area Area Numb Description	Deferred By er Reason	Until Crea	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Teresa MS							
102933				6/2/2013		2		\$0.00
Medium Work In	Progress		6/2/20)13 12:29:20 AM	I			
Prospero, Manuel		anta Teresa MS -Clot schedule details.	hes Dryer (Mor	nthly) -				
Margret Villalobos 102928				6/2/2013	6/10/2013	2		\$0.00
	Progress		6/2/20)13 12:29:18 AM		-		<i>Q</i> 0.00
Prospero, Manuel	Monthly - Sa	anta Teresa MS Eme schedule details.						
Margret Villalobos 102929				6/2/2013	6/10/2013	2		\$0.00
	Progress		6/2/20)13 12:29:18 AM		2		φ0.00
Prospero, Manuel	Monthly - Sa	anta Teresa MS Exit : schedule details.						
Margret Villalobos				E /00 /00 40				
102486				5/22/2013		13		\$0.00
Medium Work In	Progress		5/22/2	2013 2:38:36 PM	I			
Prospero, Manuel	TO BE REIN	S NEED TO BE REF IFORCED. CE TEACHER'S DE						
Laura Parra				- / / /				
102535				5/23/2013		12		\$0.00
Medium Work In	Progress		5/23/2	2013 3:09:30 PM	I			
Prospero, Manuel		RS CHENGED AIR F MAIN OFFICE AND			5/23-8			
Manuel Prospero 99185				3/3/2013		93		\$0.00
	Progress		3/3/20)13 12:25:44 AM		00		\$0.00
			0,0/20					

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time A	arget Comp Date ctual Comp Date Action Taken		₋abor lours	
Location:	Santa Te	resa MS					
102800			5/31/2013		4		\$0.00
Medium	Work In Progress	LINE LOCATE	5/31/2013 8:21:40 AM				
Castillo, Ca	arlos	AND REMODEL FOR CAFETERIA SPOT>>>THE S.W CORNER OF BUILDING' AND SPOT THE NORT NORTH BUILDING 2 AREAS MAR *FOLLOW THE ARROWS*	THE 'NORTH TH SIDE OF THE				
		Company: ESA CONSTRUCTI Contact Name: ROGELIO ESPINO Contact Phone: (505)362-2506					
Alfredo Ho	lguin		2/4/2012		100		<u>م</u>
98143			2/4/2013		120		\$0.00
Medium	Work In Progress		2/4/2013 8:18:34 AM				
Castillo, Ca	arlos	Need to replace light fixture lenses	-8ea.				
Carlos Cas	stillo		5/31/2013		4		\$0.00
102799					4		Φ 0.00
Medium	Work In Progress	LINE LOCATE	5/31/2013 8:18:04 AM				
Ontiveros,	Joe	AND REMODEL FOR CAFETERIA SPOT>>>THE S.W CORNER OF BUILDING' AND SPOT THE NORT NORTH BUILDING 2 AREAS MAR *FOLLOW THE ARROWS*	THE 'NORTH TH SIDE OF THE				
		Company: ESA CONSTRUCTI Contact Name: ROGELIO ESPINO Contact Phone: (505)362-2506					
Alfredo Ho	lguin		2/45/2042		01		<u> </u>
99745			3/15/2013		81		\$0.00
Medium	Work In Progress		3/15/2013 8:26:09 AM				
Ambriz, Jo	se	I NEED SOME CIRCULATING PUI BODY PUMP.	MP. PL-36 IRON				
Manuel Pr	ospero		0/45/0040		0.1		
99746			3/15/2013		81		\$0.00
Medium	Work In Progress		3/15/2013 8:28:59 AM				
Ambriz, Jo	se	I NEED SOME CONDENSATE PU FOR HP.	MPS LITTLE GIANT				
Manuel Pr	ospero Work Orders	Avg. Age of WO's 5	-	al for Santa Teresa		0	\$0.00

WOID Priority Assigned 1 Requester		Area Area Number Description	Deferred By Reason	Until Request Date T Created Date/Time A	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Sunland	Park ES						
102871				6/2/2013	7/3/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:28:51 AM				
Medina, Er	C C	Yearly - Sunlan PM schedule de		iler Yearly - Refer to				
Margret Vil	lalobos							
102766				5/31/2013	7/1/2013	4		\$0.00
Medium	Work In Progress			5/31/2013 12:28:43 AM				
Hernandez	, Carlos	Yearly - Sunlan Refer to PM scl		lit System Yearly -				
Margret Vil 101037	lalobos			4/17/2013		48		\$0.00
						40		φ0.00
Medium	Work In Progress	MS. FLORES -		4/17/2013 3:29:36 PM				
Ontiveros,	Joe	TOP OF THE C		S A WATER LEAK ON JRE WHERE IT IS				
David Avila	1			4/04/0040		4.4		<u> </u>
101284				4/24/2013		41		\$0.00
Medium	Work In Progress			4/24/2013 3:33:32 PM				
Ontiveros,	Joe	need to unclog	water fountian nor	th side				
Carlos Her	nandez	01		E/0/0040				<u> </u>
101605		Classroom		5/2/2013		33		\$0.00
Medium	Work In Progress			5/2/2013 2:08:55 PM				
Castillo, Ca	arlos	fixtures were da for appropriate to contractor fo	amaged due to lea	damaged roof. 2 light ks. please check site stock please hand over please order and				
Michael Mu	unoz			5/44/0040				.
102159				5/14/2013		21		\$0.00
Medium	Work In Progress	FRONT		5/14/2013 9:40:54 AM				
Hernandez	, Carlos	SUPERINTENI MAIN POSTS A ENTRANCE. F	PER THE REQUE DENT YTURRALD AT THE INDOOR (PLEASE SEE MS. S. THANK YOU.	E, PLEASE PAIN 4 DF FRONT				
David Avila	1			0.000.000				AC CC
100065				3/25/2013		71		\$0.00
Medium	Work In Progress			3/25/2013 3:19:35 PM				
Solis, Lorei	nzo	need to replace	a/c unit room 33	(43)				
Carlos Her	nondoz							

WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES					
102790			5/31/2013		4		\$0.00
Medium	Work In Progress		5/31/2013 7:49:47 AM				
Ontiveros,	, Guadalupe	need base course next to morgan bu	ilding to sandy				
Carlos He	rnandez						
102891			6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:00 AM				
Hernande		Monthly - Sunland Park ES Emer Lig Refer to PM schedule details.	ht Test: Monthly -				
Margret V 102892	illalobos		6/2/2013	6/10/2013	2		\$0.00
Medium	Work In Progress		6/2/2013 12:29:01 AM				
Hernande	c	Monthly - Sunland Park ES Exit Sign Refer to PM schedule details.					
Margret V	illalobos						
101215			4/23/2013		42		\$0.00
Aedium	Work In Progress	CLASSROOM	4/23/2013 1:43:27 PM				
Ronquillo,	Ruben	AS PER MS. KENNON - THE BOTTO THE CLASSROOM DOOR IS BROK LIKE IT WAS KICKED OR DAMAMG WAY. IT NEEDS TO BE PREPARE SAFETY/WEATHER ISSUES. THAT	EN. IT LOOKS ED IN SOME D FOR				
<u>David Avil</u> 99526	а		3/11/2013		85		\$0.00
Medium	Work In Progress		3/11/2013 7:46:48 AM				
Gallegos,	Ū	roof in cafe that was just repaired is I					
Carlos He			caking				
101999	Main Building	Mechanical	5/10/2013		25		\$0.00
Medium	Work In Progress		5/10/2013 8:00:49 AM				
/illalobos	, David	Need to replace failed backflow preve corroded	enter that is				
David Villa			5/04/0040				* •••••
102795	Main Building	Office	5/31/2013		4		\$0.00
Medium Gonzales,	Work In Progress Camilo	Please deliver 3 boxes Of Digital can	5/31/2013 7:54:22 AM neras for PO				
orm · 14 - ·	linoz	121306720.					
<u>_arry Mart</u> 99226			3/3/2013		93		\$0.00
Medium	Work In Progress		3/3/2013 12:26:02 AM				
/lunoz, M	ichael	Yearly - Sunland Park ES Fire Ext. Ir to PM schedule details.	sp. (Yearly) - Refer				
Margret V	illalobos						
///2013	9:16:10 AM					Page 14	51 of 160

6/4/2013 9:16:10 AM

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2012 - 6/30/2013 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES				
102982		6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:42 AM	1			
Hernande	z, Carlos	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.				
Margret Vi 100375	illalobos	3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress	3/31/2013 12:33:27 AM		00		ψ0.00
Orozco, D	C C	Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.	I			
Margret Vi	illalobos					
101809		Custodial 5/6/2013		29		\$0.00
Medium	Work In Progress	5/6/2013 7:50:46 AN	1			
Carbajal,		BUENOS DIAS JIMMY TENEMOS UNA ASPIRADORA K NO SIRVE PARECE K SE KEMO SI PUEDE REVISARLA POR FAVOR GRACIAS EL NUM ES H06C000006				
Valeria Ca 100451	astillo	4/2/2013		63		\$0.00
Medium	Work In Progress	4/2/2013 3:40:33 PM		00		φ0.00
Gonzalez,	C C	need window gaurds on art and music portable				
Carlos He	rnandez					
101224		4/23/2013		42		\$0.00
Medium	Work In Progress	4/23/2013 3:16:58 PM	1			
Gonzalez,	Salvador	need two new iron gates in north and south entrance				
Carlos He	rnandez	5/23/2013		12		\$0.00
102552				12		Φ 0.00
Medium Briones, E	Work In Progress	GISD 5/23/2013 3:30:06 PN PO# 121304836 PLEASE DELIVER 400 BOOK BOXES TO SUNLAND PARK ELEM. ATTN: INSTRUCTIONAL COACH	I			
Lucia Alm	eraz	10/40/0040		470		<u> </u>
96426		12/10/2012		176		\$0.00
Medium Orozco, D	Work In Progress aniel	12/10/2012 10:09:35 VEGETABLE SINK IS LEAKING. SNP MANAGER)			
Maritza Go	onzalez	IGNACIA C. 589.2545				
98171		2/4/2013		120		\$0.00
Medium	Work In Progress	2/4/2013 4:17:09 PM	1			
Orozco, D	aniel	PLEASE CHECK STAND PIECE OF METAL IS MISSING.SNP MANAGER IGNACIA C. 589.2545				
Maritza Go	onzalez					
\$/4/2013	9:16:10 AM				Page 1	52 of 160

6/4/2013 9:16:10 AM

		ders mit rogres	5 (i i50ai i	carj			Total
Selected Da WOID	te Range for Request Building	Dates:7/1/2012 - 6/30/2013 Order B Area Deferred By	· ·	est Date Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Da	ate/Time Actual Comp Date	Aged	Hours	
Assigned	То	Description		Action Taken			
Requester	Name						
Location:	Sunland	Park ES					
98172				2/4/2013	120		\$0.00
Medium	Work In Progress		2/4/2013 4:	17:37 PM			
Orozco, Da	aniel	OVENS NEED TO BE CHECKE TEMPERATURE.SNP MANAGE 589.2545	,				
Maritza Go	onzalez						
102677			5	5/29/2013	6		\$0.00
Medium	Work In Progress		5/29/2013 11:	30:12 AM			
Gonzalez,	Salvador	as per principal need guards on music portable due to vandlism portable					
Carlos Her	nandez						
Count: 25	Work Orders	Avg. Age of WO's	44	Total for Sunland Par	k ES	0	\$0.00

WOID Priority Assigned 1 Requester			Deferred By		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunrise I	ES						
102537				5/23/2013		12		\$0.00
Medium	Work In Progress	GISD		5/23/2013 3:13:19 PM				
Briones, Er	nrique			DXES TO SUNRISE COACH				
<u>Lucia Alme</u> 100376	raz			3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress			3/31/2013 12:33:28 AM	4/21/2010	00		ψ0.00
Orozco, Da	-	Monthly - Sunris PM schedule de		d Cleaning - Refer to				
<u>Margret Vill</u> 102965	lalobos			6/2/2013	6/8/2013	2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:34 AM	0/0/2013	2		ψ0.00
Vargas, Jua	0	Monthly Supris	o ES Monthly EE	Inspection - Refer to				
vargas, Jua	an	PM schedule de						
<u>Margret Vill</u> 99227	lalobos			3/3/2013		93		\$0.00
Medium	Work In Progress			3/3/2013 12:26:03 AM		00		ψ0.00
Munoz, Mic	•	Yearly - Sunrise PM schedule de		. (Yearly) - Refer to				
Margret Vill 99589	lalobos Main Building	Classroom		3/12/2013		84		\$0.00
Medium	Work In Progress	203		3/12/2013 11:16:33 AM		04		ψ0.00
Lozoya, Ma	Ū			REPLACEMENT 1C31				
	-	TATT VIELA, 20	S, NEEDS RET R	LI LACEMENT 1031				
<u>Joanne Mu</u> 99990	1102			3/21/2013		75		\$0.00
Medium	Work In Progress			3/21/2013 3:10:41 PM				
Estrada, Je	sus	need replace flo	or tile in 100 hallw	/ay				
Juan Varga	is							
101752				5/5/2013		30		\$0.00
Medium	Work In Progress			5/5/2013 12:24:33 AM				
Apodaca, N Margret Vill		Monthly - Sunris PM schedule de		Inspection - Refer to				
102960	1010005			6/2/2013		2		\$0.00
Medium	Work In Progress			6/2/2013 12:29:32 AM				
Apodaca, N Margret Vill		Monthly - Sunris PM schedule de		Inspection - Refer to				

WOID Priority Assigned ⊺ Requester		•	ate Target Comp Date ne Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunrise I	ËS				
102925		6/2/20	6/10/2013	2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:17	AM			
Vargas, Ju	an	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.				
<u>Margret Vil</u> 102926	lalobos	6/2/20	6/10/2013	2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:17	AM			
Vargas, Ju		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vil 102927	lalobos	6/2/20	13	2		\$0.00
Medium	Work In Progress	6/2/2013 12:29:17	AM			
Vargas, Ju	an	Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.				
Margret Vil 102634	lalobos	5/28/20	13	7		\$0.00
Medium	Work In Progress	5/28/2013 3:10:26				\$0.00
Vargas, Ju	•	need paint all outside frames and doors				
Juan Varga						
102635		5/28/20	13	7		\$0.00
Medium	Work In Progress	5/28/2013 3:12:04	PM			
Vargas, Ju	an	need instaled smart boards in clasrooms walls				
<u>Juan Varga</u> 101967	as	5/9/20	13	26		\$0.00
Medium	Work In Progress	5/9/2013 12:47:40		20		\$0.00
Ronquillo, I	-	need aluminium blinds for cafeteria windows almon color 9- 96-w 48-L and 8- 40-w 100-L				
Juan Varga	as	100/00	10			.
101496		4/30/20		35		\$0.00
Medium	Work In Progress	4/30/2013 3:20:52	PM			
Lozoya, Ma	-	portable 3 need replace lock door				
Juan Varga 101143	as	4/22/20	13	43		\$0.00
Medium	Work In Progress	4/22/2013 9:18:53				
Lozoya, Ma	-	luna hall comonnications closed door need fix				
Juan Varga	-					

Location: Sunrise ES 101020 4/17/2013 48 Medium Work In Progress 4/17/2013 10:50:09 AM Lozoya, Manny confers roon need change door core lock Juan Vargas 101021 4/17/2013 48 Medium Work In Progress 4/17/2013 10:51:41 AM 48 Lozoya, Manny need replace marqui locks not closed Juan Vargas 100979 4/16/2013 49 Juan Vargas 100979 4/16/2013 3:06:11 PM 100979 4/16/2013 49 Medium Work In Progress 4/16/2013 3:06:11 PM 100271 5/31/2013 7/1/2013 4 Lozoya, Manny JOANNE MUNOZ, LUNA HALLWAY COMMUNICATION ROOM, LOCK IS BROKEN NEEDS TO BE REPLACED 5/31/2013 7/1/2013 4 Medium Work In Progress 5/31/2013 7/1/2013 4 Vargas, Juan Yearly - Sunrise ES A2 (H/C Unit)(Yearly) - Refer to PM schedule details. 5/28/2013 7 Medium Work In Progress 5/28/2013 7 Medium Work In Progress 5/28/2013 7 Medium Work In Progress<	\$0.00
Medium Work In Progress 4/17/2013 10:50:09 AM Lozoya, Manny confers roon need change door core lock Juan Vargas 4/17/2013 101021 4/17/2013 Medium Work In Progress 4/17/2013 10:51:41 AM 48 Lozoya, Manny need replace marqui locks not closed Juan Vargas 4/16/2013 3:06:11 PM Lozoya, Manny Nedium Work In Progress 4/16/2013 3:06:11 PM Lozoya, Manny JOANNE MUNOZ, LUNA HALLWAY COMMUNICATION ROOM, LOCK IS BROKEN NEEDS TO BE REPLACED Joanne Munoz 5/31/2013 7/1/2013 102771 5/31/2013 7/1/2013 Medium Work In Progress 5/28/2013 7 Margret Villalobos 5/28/2013 7 Medium Work In Progress 5/28/2013 7	\$0.00
Lozoya, Mannyconfers roon need change door core lockJuan Vargas4/17/20131010214/17/2013 10:51:41 AMMediumWork In ProgressLozoya, Mannyneed replace marqui locks not closedJuan Vargas1009791009794/16/2013 3:06:11 PMLozoya, MannyJOANNE MUNOZ, LUNA HALLWAY COMMUNICATION ROOM, LOCK IS BROKEN NEEDS TO BE REPLACEDJoanne Munoz5/31/20131027715/31/20131027715/31/2013Vargas, JuanYearly - Sunrise ES A2 (H/C Unit)(Yearly) - Refer to PM schedule details.Margret Villalobos5/28/20131026335/28/2013MediumWork In Progress5/28/20135/28/2013	
Juan Vargas1010214/17/201348MediumWork In Progress4/17/2013 10:51:41 AMLozoya, Mannyneed replace marqui locks not closed	
101021 4/17/2013 48 Medium Work In Progress 4/17/2013 10:51:41 AM 48 Lozoya, Manny need replace marqui locks not closed 4/17/2013 10:51:41 AM 49 Juan Vargas 4/16/2013 10:51:41 AM 49 Medium Work In Progress 4/16/2013 3:06:11 PM 49 Lozoya, Manny JOANNE MUNOZ, LUNA HALLWAY COMMUNICATION ROOM, LOCK IS BROKEN NEEDS TO BE REPLACED 5/31/2013 7/1/2013 4 Joanne Munoz 5/31/2013 12:28:45 AM 4 Vargas, Juan Yearly - Sunrise ES A2 (H/C Unit)(Yearly) - Refer to PM schedule details. 5/28/2013 3:08:56 PM Medium Work In Progress 5/28/2013 3:08:56 PM 7	
Medium Work In Progress 4/17/2013 10:51:41 AM Lozoya, Manny need replace marqui locks not closed Juan Vargas 4/16/2013 100979 4/16/2013 3:06:11 PM Medium Work In Progress 4/16/2013 3:06:11 PM Lozoya, Manny JOANNE MUNOZ, LUNA HALLWAY COMMUNICATION ROOM, LOCK IS BROKEN NEEDS TO BE REPLACED	
Lozoya, Manny need replace marqui locks not closed Juan Vargas 4/16/2013 49 Medium Work In Progress 4/16/2013 3:06:11 PM Lozoya, Manny JOANNE MUNOZ, LUNA HALLWAY COMMUNICATION ROOM, LOCK IS BROKEN NEEDS TO BE REPLACED Joanne Munoz 5/31/2013 12:28:45 AM Medium Work In Progress 5/31/2013 12:28:45 AM Vargas, Juan Yearly - Sunrise ES A2 (H/C Unit)(Yearly) - Refer to PM schedule details. Margret Villalobos 5/28/2013 3:08:56 PM	A 0.00
Juan Vargas 4/16/2013 49 100979 4/16/2013 3:06:11 PM 49 Medium Work In Progress 4/16/2013 3:06:11 PM Lozoya, Manny JOANNE MUNOZ, LUNA HALLWAY COMMUNICATION ROOM, LOCK IS BROKEN NEEDS TO BE REPLACED	Aa aa
1009794/16/20134/9MediumWork In Progress4/16/2013 3:06:11 PMLozoya, MannyJOANNE MUNOZ, LUNA HALLWAY COMMUNICATION ROOM, LOCK IS BROKEN NEEDS TO BE REPLACED	* ~ ~~
Medium Work In Progress 4/16/2013 3:06:11 PM Lozoya, Manny JOANNE MUNOZ, LUNA HALLWAY COMMUNICATION ROOM, LOCK IS BROKEN NEEDS TO BE REPLACED	\$0.00
Lozoya, Manny JOANNE MUNOZ, LUNA HALLWAY COMMUNICATION ROOM, LOCK IS BROKEN NEEDS TO BE REPLACED Joanne Munoz 102771 5/31/2013 7/1/2013 4 Medium Work In Progress 5/31/2013 12:28:45 AM Vargas, Juan Yearly - Sunrise ES A2 (H/C Unit)(Yearly) - Refer to PM schedule details. <u>Margret Villalobos</u> 102633 5/28/2013 3:08:56 PM	•
102771 5/31/2013 7/1/2013 4 Medium Work In Progress 5/31/2013 12:28:45 AM 4 Vargas, Juan Yearly - Sunrise ES A2 (H/C Unit)(Yearly) - Refer to PM schedule details. 5/28/2013 7 Margret Villalobos 5/28/2013 5/28/2013 7 Medium Work In Progress 5/28/2013 3:08:56 PM	
Medium Work In Progress 5/31/2013 12:28:45 AM Vargas, Juan Yearly - Sunrise ES A2 (H/C Unit)(Yearly) - Refer to PM schedule details. Margret Villalobos 5/28/2013 102633 5/28/2013 3:08:56 PM	\$0.00
Vargas, Juan Yearly - Sunrise ES A2 (H/C Unit)(Yearly) - Refer to PM schedule details. Margret Villalobos 5/28/2013 102633 5/28/2013 Work In Progress 5/28/2013 State 5/28/2013	\$0.00
102633 5/28/2013 7 Medium Work In Progress 5/28/2013 3:08:56 PM 7	
Medium Work In Progress 5/28/2013 3:08:56 PM	\$0.00
	φ0.00
Valuas, Juan need check a/c unite 100m 512	
-	
Juan Vargas 5/31/2013 4	\$0.00
Medium Work In Progress 5/31/2013 3:37:25 PM	
Vargas, Juan need paint rooms 310 303 305 307 309	
Juan Vargas	
102071 5/13/2013 22	\$0.00
MediumWork In Progress5/13/2013 8:28:30 AM	
Vargas, Juan need repint art room	
Juan Vargas 6/2/2013 2	\$0.00
Medium Work In Progress 6/2/2013 12:28:47 AM	÷2.00
Vargas, Juan Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details.	
Margret Villalobos	

WOID Priority	Building Status	Dates:7/1/2012 - 6/30/2013 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time	U 1	ays Labor jed Hours	Costs
Assigned		Description	Action Taken		
Requester		•			
Location:	Sunrise I	ES			
102861		6/2/2013		2	\$0.00
Medium	Work In Progress	6/2/2013 12:28:46 AM			
Vargas, Ju	ian	Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.			
Margret Vi 102862	llalobos	6/2/2013		2	\$0.00
				2	φ0.00
Medium	Work In Progress	6/2/2013 12:28:46 AM			
Vargas, Ju	lan	Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM schedule details.			
<u>Margret Vi</u> 102860	llalobos	6/2/2013		2	\$0.00
Medium	Work In Progress	6/2/2013 12:28:46 AM		2	φ0.00
Vargas, Ju	0	Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM schedule details.			
Margret Vi	llalobos	10/0010		20	<u> </u>
100506		4/3/2013	t	62	\$0.00
Medium	Work In Progress	4/3/2013 3:35:24 PM			
Vallejo, All	bert	need fix out side portables lights			
Juan Varg	as	4/05/0040		10	<u></u>
101327		4/25/2013	2	40	\$0.00
Medium	Work In Progress	4/25/2013 3:29:18 PM			
Appelzolle	r, Fred	300 wing boys r.rooms need replace fouset is broke			
Juan Varg	as	4/17/2013		18	\$0.00
101022			2	+0	Ф 0.00
Medium	Work In Progress	4/17/2013 10:54:37 AM			
Appelzolle	r, Fred	r.rooms next to cafeteria need replace sinks			
Juan Varg	as Work Orders	Avg. Age of WO's 28	Total for Sunrise E	S 0	\$0.00

WOID Priority Assigned Requester	Building Status To		te Target Comp Date ne Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Vado ES					
102761		5/31/20	13 7/1/2013	4		\$0.00
Medium	Work In Progress	5/31/2013 12:28:41	AM			
Miranda, I	Danny	Yearly - Vado ES A-2 Package Unit Elec Yearly - Refer to PM schedule details.				
Margret Vi 100217	illalobos	3/31/20	13 4/21/2013	65		\$0.00
Medium				05		φ0.00
	Work In Progress	3/31/2013 12:32:25				
Orozco, D		Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.				
Margret Vi 102824	illalobos	5/31/20	13	4		\$0.00
Medium	Work In Progress	5/31/2013 1:29:11				·
Miranda, E	-	need to paint classrooms as needed				
Danny Mir	-					
97344		1/15/20	13	140		\$0.00
Medium	Work In Progress	1/15/2013 2:54:22	PM			
Lozoya, M	anny	NEED NEW KEYS FOR FRONT DOORS AND OUTSIDE DOORS				
Danny Mir	anda	4/00/00	10	407		<u> </u>
97761		1/28/20		127		\$0.00
Medium	Work In Progress	1/28/2013 10:37:09	AM			
Lozoya, M	anny	NEED A KEY MADE FOR ROOM 205 AND 207				
<u>Debra Fac</u> 97079	cio	Office 1/9/20	13	146		\$0.00
				140		ψ0.00
Medium Work In Progress Lozoya, Manny		1/9/2013 4:02:57 need doors from main lobby to corridors and cafeteria to have locks installed that can be operated from office area. Check with Alfredo Holguin if you have questions				
Alfredo Ho	blauin					
101591		5/2/20	13	33		\$0.00
Medium	Work In Progress	5/2/2013 8:51:27	λM			
Lozoya, Manny		need to ck. key in room #102 key will not open door				
Danny Mir	anda					A = -
102473		5/22/20	-	13		\$0.00
Medium	Work In Progress	5/22/2013 10:18:19	AM			
Miranda, D	Danny	on having the Dual Board and projector mounted to wall and ceiling for room 201				
Cora Ram	irez					

WOID Priority Assigned		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken		Labor Hours		
Requester	Vado ES								
	Vado ES			5/9/2013				<u> </u>	
101958						26		\$0.00	
Medium	Work In Progress		_	5/9/2013 10:51:05 AM					
Ontiveros,	Guadalupe	need fertilizer t	to spread on grass						
Danny Mira 102882	anda			6/2/2013	6/10/2013	2		\$0.00	
Medium	Work In Progress			6/2/2013 12:28:56 AM		-		\$0.00	
Miranda, D	Ū.	Monthly - Vado schedule detail		: Monthly - Refer to PM					
Margret Vil	lalobos			0/0/0010	0/40/0040			<u> </u>	
102883				6/2/2013	6/10/2013	2		\$0.00	
Medium	Work In Progress			6/2/2013 12:28:57 AM					
Miranda, D	-	Monthly - Vado PM schedule de		est: Monthly - Refer to					
Margret Vil 102884	Iaiodos			6/2/2013		2		\$0.00	
Medium	Work In Progress			6/2/2013 12:28:57 AM					
Miranda, Danny		Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Vil 97527	lalobos Main Building	Office		1/22/2013		133		\$0.00	
Medium	Work In Progress	Childo		1/22/2013 8:30:35 AM		100		ψ0.00	
	-								
Lozoya, Ma	-	NEEDSFIKE	YS AND 1 STORA	GE DOOR KET					
Debra Fac 99644	io Main Building	Gym		3/13/2013		83		\$0.00	
Medium	Work In Progress			3/13/2013 12:36:20 PM					
Estrada, Jesus				ard Chavez and Ms. t a wood floor on the	3/18/13 - Asp Mike a	assign to C	huy.		
Debra Fac 99228	0			3/3/2013		93		\$0.00	
Medium	Work In Progress			3/3/2013 12:26:04 AM					
Munoz, Michael		Yearly - Vado E schedule detail		Yearly) - Refer to PM					
Margret Vil	lalobos			0/0/00000	0/0/00/0			.	
102975				6/2/2013	6/8/2013	2		\$0.00	
Medium	Work In Progress			6/2/2013 12:29:39 AM					
Miranda, Danny Margret Villalobos		Monthly - Vado schedule detail		spection - Refer to PM					

	ate Range for Request Building Status		Deferred By	cation, State	JS	arget Comp Date ctual Comp Date	A		
Assigned To		Description		Action Taken					
Requester	Name								
Location:	Vado ES								
100377					3/31/2013	4/21/2013	65		\$0.00
Medium	Work In Progress			3/31/	2013 12:33:28 AM				
Orozco, Da	aniel	Monthly - Vado schedule detail	ES Range Hood Cles.	eaning - Re	fer to PM				
Margret Vi	llalobos								
102202					5/15/2013		20		\$0.00
Medium	Work In Progress			5/15	/2013 8:38:55 AM				
Orozco, Daniel		PASS THRU R MANAGER EV	EFRIGERATOR IS I A M. 233.2945	NOT COOL	ING. SNP				
Maritza Go	onzalez								
Count: 18	Work Orders	Α	vg. Age of WO's 5	3		Total for Vad	o ES	0	\$0.00
Count: 11	02 Work Orders	Α	vg. Age of WO's 5	9		Grand Total		0	\$0.00