WOID Priority Assigned	Building Status	Area Area Number Description	/30/2016 Order By Loca Deferred By Reason	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		Description				ACTION TAKEN			
Location:		Early College H	19						
					44/0/2045		05		<u> </u>
143189					11/6/2015		25		\$0.00
Medium	Work In Progress	Teacher's		11/6/20)15 10:17:42 AN	1			
Villalobos	, David	INSTALLING A EATING AREA	STIGATE THE POSSIE SMALL BAR SINK IN FOR THE PURPOSE LEANING MAINTENA	THE TEAC OF WASHI					
Yvette Cor									
140069	Curriculum and	Classroom			9/16/2015		76		\$0.00
Medium	Work In Progress	203 - MAIN		9/16/20)15 11:52:52 AM	1			
Castillo, C		NEED NEW OFFIC	UTLET AND 1 GANG I E.	BOX IN THE	E				
Yvette Cor	tez Curriculum and	0#:			0/47/0045		4.00		<u> </u>
138185		Office			8/17/2015		106		\$0.00
Medium	Work In Progress	Main Office			2015 5:15:22 PM	1			
Castillo, C	arlos	NEEDS TO BE	THE FRONT OFFICE I ADJUSTED OR REP Y IT BREAKS LOOSE	LACED. M					
Yvette Cor	tez								
143934		Classroom			11/20/2015		11		\$0.00
Medium	Work In Progress	504		11/20/2	2015 3:24:22 PM				
Ambriz, Jo	se	-	/M DOES NOT WORK D IS VERY COLD TO E						
Yvette Cor	tez								
143935		Classroom			11/20/2015		11		\$0.00
Medium	Work In Progress	501		11/20/2	2015 3:25:16 PM				
Ambriz, Jo		-	ASSROOM DOES NO CK FOR NECESSARY	-					
Yvette Cor	tez Curriculum and	Classroom			9/16/2015		76		\$0.00
140093				0/4.0/			70		φ 0. 00
Medium	Work In Progress	202			2015 3:42:45 PM	1			
Lara, Ralp	h	ROOM 202 FR ONLY. CYLINI ON BOTH SID	NGE DOOR CYLINE OM 203 FROM X33 T DER NEEDS TO HAV ES. FOR FURTHER [I, PLEASE CONTACT 382-6400.	O MASTER E KEY ACC DETAILS AN	KEY ESS ID				
Yvette Cor	tez		-						

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date Targe Created Date/Time Actu		Labor Hours	Costs
Location:	Alta Vista	Early College HS				
143208			11/6/2015	25	\$	\$0.00
Medium	Work In Progress		11/6/2015 11:55:58 AM			
Vallejo, Alt	pert	Roof Leak in the Library. It is right table where computers are. Also re #6. Leak is right next to teachers	oof leak in portable			
David Sori	ano					
136834		Office	7/31/2015	123	\$	\$0.00
Medium	Work In Progress	FRONT OFFICE	7/31/2015 10:03:35 AM			
Marquez, C	Gerardo	PLEASE INSTALL NEW COUNTE AREA AT ANNEX BUILDING. FOR DETAILS OR INFORMATION, PLE YVETTE AT 882-6400.	FURTHER			
Yvette Cor	tez					
139910		Library	9/14/2015	78	\$	\$0.00
Medium	Work In Progress		9/14/2015 2:11:00 PM			
Soriano, D	avid	25 Pack assorted wire connectors [Please include the green ones for				
David Sori	ano					
140462			9/23/2015	69	\$	\$0.00
Medium	Work In Progress		9/23/2015 8:58:29 AM			
Soriano, D	avid	10-2x4x8 Studs to hang up windov	<i>v</i> blinds			
David Sori	ano					
142013			10/20/2015	42	\$	\$0.00
Medium	Work In Progress		10/20/2015 2:25:50 PM			
Soriano, D	avid	4- White Heavy Duty Shelf and Ro 3- Concrete Mix Sacks	d Support			
David Sori	ano					
139734			9/10/2015	82	\$	\$0.00
Medium	Work In Progress		9/10/2015 2:27:06 PM			
Soriano, D	avid	4 - 9 in. Roller Covers 4- 2 in. Roller Covers 1- 2 in. Roller 1- 10 oz Caulking Gun 1- 4-in Metal Twist Nozzle (for Gau	den Hose)			

Selected Date Range WOID Buildin Priority Status Assigned To Requester Name		Dates:7/1/2015 - 6, Area Area Number Description	Deferred By	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Tota Costs
Location:	Alta Vista	a Early College H	IS						
139349					9/4/2015		88		\$0.00
Medium Work In	Progress			9/4/20	15 10:38:51 AM	1			
Soriano, David		25ft - 3/8 Plastic 25ft - 1/2 Plastic							
		5- (3/8 - 7/8) Ho	se Repair Clamp						
David Soriano									
139907					9/14/2015		78		\$0.00
Medium Work In	Progress			9/14/2	015 2:04:54 PN	1			
Soriano, David		10 - Ballaster 4	lamp 110 v						
David Soriano									
139356					9/4/2015		88		\$0.00
Medium Work In	Progress			9/4/20	15 11:07:10 AM	1			
Soriano, David		1/2 in. length)	ith washer and nut						
		washers and n	ts 3/8 in width x 2 1 uts	/2 length) with	1				
David Soriano 143206		Parking Lot			11/6/2015		25		\$0.00
	Progress			11/6/20	15 11:43:48 AM	1	20		ψ0.00
Soriano, David	rriogiess	4 - Flat Bar 17 : 8 - Carriage Bo	x 1 x 1/8 blts with nuts(1 1/2		13 11.43.46 Aw	I			
David Soriano									
142369					10/27/2015		35		\$0.00
Medium Work In	Progress			10/27/2	015 8:43:13 AN	1			
Soriano, David		3- 42x29 windo 2- 48x48 windo							
David Soriano									
142305					10/26/2015		36		\$0.00
Medium Work In	Progress			10/2	6/2015 11:40:36	5			
Soriano, David		2-Melnor Y Shu	ut-Off 2-Way Metal	Hose Connec	or				
David Soriano									

Location: 142306 Medium Wo Soriano, David	ork In Progress	Early College HS 2 Boxes - #6 x 2 in. Phillips Bugle-H Sharp Point Gold Screw (1 lbPa 2 Boxes - #8 3 in. Philips Bugle-He Wood Screws (1 lbPack) 2 Boxes - #6 x1-5/8 in. Philips Bug Thread Gold Screw Parking Lot	ck) ead Coarse Thread	36	\$0.00
Medium Wo		Sharp Point Gold Screw (1 lbPa 2 Boxes - #8 3 in. Philips Bugle-He Wood Screws (1 lbPack) 2 Boxes - #6 x1-5/8 in. Philips Bug Thread Gold Screw	10/26/2015 11:51:47 Head Coarse Thread ck) ead Coarse Thread gle-Head Coarse	36	\$0.00
		Sharp Point Gold Screw (1 lbPa 2 Boxes - #8 3 in. Philips Bugle-He Wood Screws (1 lbPack) 2 Boxes - #6 x1-5/8 in. Philips Bug Thread Gold Screw	Head Coarse Thread ck) ead Coarse Thread gle-Head Coarse		
Soriano, David		Sharp Point Gold Screw (1 lbPa 2 Boxes - #8 3 in. Philips Bugle-He Wood Screws (1 lbPack) 2 Boxes - #6 x1-5/8 in. Philips Bug Thread Gold Screw	ck) ead Coarse Thread gle-Head Coarse		
	ork In Progress	Wood Screws (1 lbPack) 2 Boxes - #6 x 1-5/8 in. Philips Bug Thread Gold Screw	Jle-Head Coarse		
	ork In Progress	Thread Gold Screw			
	ork In Progress	Parking Lot	11/6/2015		
David Soriano	ork In Progress	ParkingLot	11/6/2015		
143204	ork In Progress			25	\$0.00
		MAIN OFFICE	11/6/2015 11:37:36 AM		
Ronquillo, Rube	en	NEED PARKING LOT SIGNS (2)	THAT READS:		
		STAFF PARKING LOT			
Yvette Cortez					
143990			11/30/2015	1	\$0.00
Medium Wo	ork In Progress		11/30/2015 12:52:01		
Sanchez, Raul		Monthly - Desert Pride - Monthly N to PMschedule details.	<i>l</i> eter Readings - Refer		
Margret Villalob	bos		11/11/0015		
143600			11/14/2015	17	\$0.00
Medium Wo	ork In Progress		11/14/2015 12:27:49		
Sanchez, Raul		Monthly - Alta Vista ECHS- Water schedule details.	Filters - Refer to PM		
Margret Villalob 143993	DOS	Classroom	11/30/2015	1	 \$0.00
	ork In Progress	Clabologin	11/30/2015 7:30:49 AM		φ0.00
Gonzalez, Salva	-	Need rail to be welded	11/30/2013 1.30.43 AM		
David Soriano		Need fail to be welded			
	irriculum and		7/20/2015	134	\$0.00
	ork In Progress	ANNEX	7/20/2015 9:53:42 AM	10-	ψ0.00
Marquez, Gerar	Ū	REPLACE OLD DOORS WITH W GLASS DOORS AT ANNEX BUILI BE REPLACED HAVE BEEN LAB IDENTIFICATION. ANY QUESTIC CONTACT YVETTE OR GEMA AT	OOD FRAME AND DING. DOORS TO ELED FOR DNS, PLEASE		
Yvette Cortez					

			•	•	i cai j				Tota
WOID	ate Range for Request Building	Area	Deferred By	Until	-	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Cre	ated Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Alta Vista	a Early College H	IS						
136923					8/2/2015		121		\$0.00
Medium	Work In Progress			8/2/2	015 12:32:10 AN	I			
Vallejo, Al	lbert	Yearly - Desert to PMschedule	t Pride HS Fire Ext. e details.	Insp. (Yearly)	- Refer				
Margret V	illalobos								
135852					7/14/2015		140		\$0.00
Medium	Work In Progress			7/14/2	015 12:01:35 PM				
Vallejo, Al	lbert	Improve sidew	alks at front entran	ce.					
Albert Val	lejo								
Count: 26	Work Orders	Α	vg. Age of WO's	60	Total for Al	a Vista Early Colleg	e HS	0	\$0.00

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Days Actual Comp Date Aged Action Taken	Costs Labor Hours
Location:	Anthony	- On Track Pre-K (Village)			
136804			7/31/2015	123	\$0.00
Medium	Work In Progress		7/31/2015 12:30:53 AM		
Vallejo, Al	bert	Yearly - Anthony On Track Pre-K Refer to PMschedule details.	(Yearly) Fire Ext -		
Margret Vi	illalobos				
143619			11/16/2015	15	\$0.00
Medium	Work In Progress		11/16/2015 9:23:49 AM		
Ronquillo	, Ruben	Need to have window glass repla portable at pre k. 2ea.33 3/4 x 28 pane glass.			
Arturo Nur	nez				
144011			11/30/2015	1	\$0.00
Medium	Work In Progress		11/30/2015 11:14:00		
Ronquillo	, Ruben	Need to have glass on windows vandalism.6ea.141/2x155/8wi 323/4x28.,1ea.331/4x28.			
Arturo Nur	nez				
135840			7/14/2015	140	\$0.00
Medium	Work In Progress	FAMILY	7/14/2015 10:02:19 AM		
Nunez, Art	turo	INSTALL TOILET SEAT DISPENS IN BOTH RESTROOMS.	SER WITH COVERS	10/9/15 - waiting for parts	
Noemi Du	Iron		40/0/0045		
141264			10/8/2015	54	\$0.00
Medium	Work In Progress		10/8/2015 8:30:10 AM		
Nunez, Art		please clean garden planters bet them look clean and pretty any q			
Laura Vaz	quez	Colotaria	7/00/0045	404	¢0.00
136332		Cafeteria	7/23/2015	131	\$0.00
Medium	Work In Progress	882-1904	7/23/2015 12:06:53 PM		
Nunez, Art		doors from room 101 and 102 ne	ed a weather strip		
Laura Vaz	quez		0/0/0045	100	
137103			8/3/2015	120	\$0.00
Medium	Work In Progress		8/3/2015 2:08:08 PM		
Ontiveros,	, Guadalupe	Please trim trees that are in the f thank you.	front office		
Laura Vaz	quez				

WOID Priority Assigned	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason	Until Request D	Date Target Comp Date Time Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony -	On Track Pre-	(Village)					
142861				11/2/2	2015	29		\$0.00
Medium	Work In Progress			11/2/2015 9:20:5	2 AM			
Solis, Lore	enzo	Need some as on F.C.U. in roo	sistance on trouble s om # 107.	hooting water leak				
Arturo Nun	iez							
143774				11/18/2	2015	13		\$0.00
Medium	Work In Progress			11/18/2015 11:5	4.01			
Solis, Lore			sistance on H.W.R lin in room # 107, is ha					
Arturo Nun	iez			11/17/2	0015	14		¢0.00
143694		000 4004				14		\$0.00
Medium	Work In Progress	882-1904		11/17/2015 8:57:2	1 AM			
Solis, Lore		heater from lou working	nge room in the pre k	coffice is not				
Laura Vazo 143784	quez			11/18/2	015	13		\$0.00
Medium	Work In Progress	882-1904		11/18/2015 2:32:43		10		ψ0.00
	-							
Marquez, C		install chains it	ırnished and weld or	to gates please				
Laura Vazo 143973	quez			11/21/2	2015	10		\$0.00
	Mark In Drogrado					10		ψ0.00
Medium	Work In Progress			11/21/2015 9:35:39	9 AIVI			
Marquez, C		having trouble of	opening doors on pre	ek office both sides				
David Veg	а			44/00/0	045	4		<u> </u>
144016				11/30/2		1		\$0.00
Medium	Work In Progress			11/30/2015 11:2	26:27			
Nunez, Art		Need to paint p graffited	ortable, and outside	restrooms that were				
Arturo Nun	lez	01		0/04/0	045			<u> </u>
138597		Classroom		8/24/2		99		\$0.00
Medium	Work In Progress	ANTHONY		8/24/2015 3:12:3	2 PM			
Nunez, Art	uro	DRY ERASE B ANTHONY FAN JUANA ESPINO	AN INSIDE ONE W. OARD WAS REMOVI IILY LITERACY CEN DZA @ EXT.4420 OR FURTHER INFO.	ED AT THE TER. CONTACT				
Karla Que	aada							

Selected Da WOID Priority Assigned ⁻ Requester		Dates:7/1/2015 - 6/ Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Cost
Location:	Anthony	On Track Pre-K	(Village)					
138101				8/14/2015		109		\$0.00
Medium	Work In Progress	FAMILY		8/14/2015 4:38:22 PM				
Nunez, Art	uro	Paint behind th	ne T.V on the wall.					
Noemi Du	iron							
142145				10/22/2015		40		\$0.00
Medium	Work In Progress			10/22/2015 10:34:31				
Ontiveros,	Joe	Admin Portable	- water fountain (ex	terior) does not work.				
Albert Valle	ejo							
144025				11/30/2015		1		\$0.00
Medium	Work In Progress			11/30/2015 2:00:33 PM				
Chavez, Sa	antos	Install wall pack	ks around building.					
Albert Valle	ejo							
144009				11/30/2015		1		\$0.00
Medium	Work In Progress			11/30/2015 11:08:54				
Chavez, Sa	antos		sistance on trouble to classrooms. Circ netrations.					
Arturo Nur	iez							
Count: 18	Work Orders	A	vg. Age of WO's 5	Total for Anthony - 0	On Track Pre-K (Vill	age)	0	\$0.00

Location: Anthony ES 142485 10/28/2015 Medium Work In Progress 10/28/2015 3:28:10 PM Ontiveros, Joe Need some assistance on checking and , and draining hot water storage tanks. Arturo Nunez	WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Medium Work In Progress 10/28/2015 3:28:10 PM Ontiveros, Joe Need some assistance on checking and , and draining hot water storage tanks. Arturo Nunez 139294 Office 139294 Office 9/3/2015 Medium Work In Progress Room 109 9/3/2015 1:25:25 PM Chavez, Santos Please send a technician to install an electrical outlet for a new employees desk top and printer. Room 109 Susie Ramos Lara 11/19/2015 2:20:05 PM Vallejo, Albert Repair main domestic backflow preventer. Albert Vallejo 11/19/2015 2:20:05 PM Vallejo, Albert Repair main domestic backflow preventer. Albert Vallejo 11/1/2015 1:2:5:400 AM Nunez, Arturo Yearly - Anthony ES - Grease Trap - Refer to PM schedule details. Marguet Villalobos 11/16/2015 4:19:44 PM Marquez, Gerardo Please cut extra keys for Alamo Cafeteria. Albert Vallejo 10/4/2015 1:2:3:43 AM Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details. Marguez, Gerardo 10/4/2015 1:2:3:43 AM Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details. Marguet Villalobos 10/4/2015 1:2:3:43 AM	Location:	Anthony	ES					
Ontiveros, Joe Need some assistance on checking and , and draining hot water storage tanks. Arturo Nunez	142485			10/28/2015		34		\$0.00
Arturo Nunez 139294 Office 9/3/2015 139294 Office 9/3/2015 1:25:25 PM Medium Work In Progress Room 109 9/3/2015 1:25:25 PM Chavez, Santos Please send a technician to install an electrical outletfor a new employees desk top and printer. Room 109 Susie Ramos Lara 11/19/2015 143850 11/19/2015 2:20:05 PM Vallejo, Albert Repair main domestic backflow preventer. Albert Vallejo 11/1/2015 12:54:00 AM 142692 11/1/2015 12:54:00 AM Nunez, Arturo Yearly - Anthony ES - Grease Trap - Refer to PM schedule details. Margret Villalobos 11/16/2015 4:19:44 PM Marquez, Gerardo Please cut extra keys for Alamo Cafeteria. Albert Vallejo 10/4/2015 12:38:43 AM Villalobos, Margret Wonthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details. Marguet Villalobos 10/4/2015 12:38:43 AM Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details. Margret Villalobos 10/4/2015 12:38:43 AM Villalobos 10/4/2015 12:38:43 AM	Medium	Work In Progress		10/28/2015 3:28:10 PM				
139294Office9/3/2015MediumWork In ProgressRoom 1099/3/2015 1:25:25 PMChavez, SantosPlease send a technician to install an electrical outletfor a new employees desk top and printer. Room 109Susie Ramos Lara11/19/201514385011/19/2015 2:20:05 PMVallejo, AlbertRepair main domestic backflow preventer.Albert Vallejo11/1/201514269211/1/2015MediumWork In Progress11/1/201511/1/2015MediumWork In Progress11/1/201511/1/2015Margret Villalobos11/1/2015Marquez, GerardoPlease cut extra keys for Alamo Cafeteria.Albert Vallejo10/4/201514090910/4/2015Margret Villalobos, MargretMonthly- Anthony ES - Enviro Controls Quarterly- Refer to PM schedule details.Margret Villalobos10/4/201514090910/4/2015 <td< td=""><td>Ontiveros,</td><td>, Joe</td><td></td><td>ng and , and draining</td><td></td><td></td><td></td><td></td></td<>	Ontiveros,	, Joe		ng and , and draining				
MediumWork In ProgressRoom 1099/3/2015 1:25:25 PMChavez, SantosPlease send a technician to install an electrical outletfor a new employees desk top and printer. Room 109Susie Ramos Lara14385011/19/2015MediumWork In Progress11/19/2015 2:20:05 PMVallejo, AlbertRepair main domestic backflow preventer.Albert Vallejo11/1/2015 12:54:00 AMNunez, ArturoYearly - Anthony ES - Grease Trap - Refer to PM schedule details.Margret Villalobos11/16/2015MediumWork In Progress11/16/2015Margret Villalobos11/16/2015 4:19:44 PMMarquez, GerardoPlease cut extra keys for Alamo Cafeteria.Albert Vallejo10/4/201514090910/4/201510/4/201511/4/2015MediumWork In Progress10/4/201510/4/2015Margret Villalobos, MargretMonthily - Anthony ES - Enviro Controls Quarterly- Refer to PM schedule details.Margret Villalobos10/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/201511/16/201511/4/2015 </td <td>Arturo Nur</td> <td>nez</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Arturo Nur	nez						
Chavez, Santos Please send a technician to install an electrical outlet for a new employees desk top and printer. Room 109 Susie Ramos Lara 143850 11/19/2015 Medium Work In Progress 11/19/2015 2:20:05 PM Vallejo, Albert Repair main domestic backflow preventer. Albert Vallejo 142692 11/1/2015 12:54:00 AM Nunez, Arturo Yearly - Anthony ES - Grease Trap - Refer to PM schedule details. Margret Villalobos 143685 11/16/2015 Medium Work In Progress 10/4/2015 4:19:44 PM Marquez, Gerardo Please cut extra keys for Alamo Cafeteria. Albert Vallejo 140909 10/4/2015 Medium Work In Progress 10/4/2015 12:38:43 AM Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly- Refer to PM schedule details. Margret Villalobos	139294		Office	9/3/2015		89		\$0.00
a new employees desk top and printer. Room 109 Susie Ramos Lara 143850 11/19/2015 Medium Work In Progress 11/19/2015 2:20:05 PM Vallejo, Albert Repair main domestic backflow preventer. Albert Vallejo 142692 11/1/2015 142692 11/1/2015 Medium Work In Progress 11/1/2015 12:54:00 AM Nunez, Arturo Yearly - Anthony ES - Grease Trap - Refer to PM schedule details. Margret Villalobos 143685 11/16/2015 4:19:44 PM Marquez, Gerardo Please cut extra keys for Alamo Cafeteria. Albert Vallejo 140909 10/4/2015 Medium Work In Progress 10/4/2015 12:38:43 AM Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details. Margret Villalobos 11/04/2015 12:38:43 AM Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details. Margret Villalobos 110/4/2015 12:38:43 AM	Medium	Work In Progress	Room 109	9/3/2015 1:25:25 PM				
14385011/19/2015MediumWork In Progress11/19/2015 2:20:05 PMVallejo, AlbertRepair main domestic backflow preventer.Albert Vallejo11/1/2015 2:20:05 PM14269211/1/2015MediumWork In Progress11/1/2015MediumWork In Progress11/1/2015 12:54:00 AMNunez, ArturoYearly - Anthony ES - Grease Trap - Refer to PM schedule details.Margret Villalobos11/16/2015MediumWork In Progress11/16/2015 4:19:44 PMMarquez, GerardoPlease cut extra keys for Alamo Cafeteria.Albert Vallejo10/4/2015 12:38:43 AM14090910/4/2015MediumWork In Progress10/apos, MargretMonthly - Anthony ES - Enviro Controls Quarterly- Refer to PM schedule details.Marguet Villalobos11/4/201514083910/4/2015	Chavez, S	Santos						
MediumWork In Progress11/19/2015 2:20:05 PMVallejo, AlbertRepair main domestic backflow preventer.Albert Vallejo11/1201514269211/1/2015 12:54:00 AMNunez, ArturoYearly - Anthony ES - Grease Trap - Refer to PM schedule details.Margret Villalobos11/16/201514368511/16/2015MediumWork In Progress14368511/16/2015MediumWork In Progress14368511/16/2015MediumWork In Progress14368511/16/2015MediumWork In Progress11/16/201511/16/2015MediumWork In Progress11/19/201511/4/2015MediumWork In Progress10/4/201510/4/201511/19/201511/4/2015MediumWork In Progress10/4/201511/4/2015MediumWork In Progress10/4/201511/4/2015Margret Villalobos, MargretMonthly - Anthony ES - Enviro Controls Quarterly- Refer to PM schedule details.Margret Villalobos11/4/201514083910/4/201511/4201511/4/2015		mos Lara		44/40/0045		40		.
Vallejo, Albert Repair main domestic backflow preventer. Albert Vallejo 142692 11/1/2015 Medium Work In Progress 11/1/2015 12:54:00 AM Nunez, Arturo Yearly - Anthony ES - Grease Trap - Refer to PM schedule details. Margret VIIIalobos 143685 11/16/2015 11/16/2015 4:19:44 PM Marquez, Gerardo Please cut extra keys for Alamo Cafeteria. Albert Vallejo 140909 10/4/2015 11/4/2015 10/4/2015 12:38:43 AM VIIlalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PMschedule details. Margret VIIIalobos 11/16/2015 11/4/2						12		\$0.00
Albert Vallejo 11/1/2015 142692 11/1/2015 Medium Work In Progress 11/1/2015 Nunez, Arturo Yearly - Anthony ES - Grease Trap - Refer to PM schedule details. Margret Villalobos 11/16/2015 143685 11/16/2015 Medium Work In Progress 143685 11/16/2015 Medium Work In Progress 11/16/2015 11/16/2015 Medium Work In Progress 140909 10/4/2015 Medium Work In Progress 10/4/2015 12:38:43 AM Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details. Margret Villalobos 10/4/2015 140839 10/4/2015 11/4/2015	Medium	Work In Progress		11/19/2015 2:20:05 PM				
142692 11/1/2015 Medium Work In Progress 11/1/2015 12:54:00 AM Nunez, Arturo Yearly - Anthony ES - Grease Trap - Refer to PM schedule details. Margret Villalobos 11/16/2015 143685 11/16/2015 Medium Work In Progress 143685 11/16/2015 4:19:44 PM Marquez, Gerardo Please cut extra keys for Alamo Cafeteria. Albert Vallejo 10/4/2015 140909 10/4/2015 Medium Work In Progress 10/4/2015 11/16/2015 Medium Work In Progress 10/4/2015 11/16/2015 Margret Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly- Refer to PM schedule details. Margret Villalobos 11/4/2015 140839 10/4/2015 11/4/2015	Vallejo, All	bert	Repair main domestic backflow pr	reventer.				
MediumWork In Progress11/1/2015 12:54:00 AMNunez, ArturoYearly - Anthony ES - Grease Trap - Refer to PM schedule details.Margret Villalobos11/16/201514368511/16/2015 4:19:44 PMMarquez, GerardoPlease cut extra keys for Alamo Cafeteria.Albert Vallejo10/4/201514090910/4/2015MediumWork In Progress10/4/201510/4/2015MediumWork In Progress10/4/201510/4/2015MediumWork In Progress10/4/201510/4/2015MediumWork In Progress10/4/201511/4/2015Margret VillalobosMonthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details.Margret Villalobos10/4/201511/4/201511/4/2015		lejo						
Nunez, ArturoYearly - Anthony ES - Grease Trap - Refer to PM schedule details.Margret Villalobos11/16/201514368511/16/2015 4:19:44 PMMarquez, GerardoPlease cut extra keys for Alamo Cafeteria.Albert Vallejo10/4/2015 1:2:38:43 AM14090910/4/2015 12:38:43 AMVillalobos, MargretMonthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details.Margret Villalobos10/4/2015 11/4/20151403910/4/2015 11/4/2015	142692			11/1/2015		30		\$0.00
Margret VIIIalobos 11/16/2015 143685 11/16/2015 4:19:44 PM Marquez, Gerardo Please cut extra keys for Alamo Cafeteria. Albert Vallejo 10/4/2015 12:38:43 AM 140909 10/4/2015 12:38:43 AM Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PMschedule details. Margret Villalobos 10/4/2015 140839 10/4/2015	Medium	Work In Progress		11/1/2015 12:54:00 AM				
14368511/16/2015MediumWork In Progress11/16/2015 4:19:44 PMMarquez, GerardoPlease cut extra keys for Alamo Cafeteria.Albert Vallejo10/4/201514090910/4/2015MediumWork In Progress10/4/201512:38:43 AMVillalobos, MargretMonthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details.Margret Villalobos10/4/201514083910/4/201511/4/201511/4/2015	Nunez, Art	turo		o - Refer to PM				
Medium Work In Progress 11/16/2015 4:19:44 PM Marquez, Gerardo Please cut extra keys for Alamo Cafeteria. Albert Vallejo 10/4/2015 140909 10/4/2015 Medium Work In Progress Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details. Margret Villalobos 10/4/2015 140839 10/4/2015		illalobos						
Marquez, Gerardo Please cut extra keys for Alamo Cafeteria. Albert Vallejo 10/4/2015 140909 10/4/2015 Medium Work In Progress 10/4/2015 12:38:43 AM Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PMschedule details. Margret Villalobos 10/4/2015 140839 10/4/2015				11/16/2015		15		\$0.00
Albert Vallejo 140909 10/4/2015 Medium Work In Progress 10/4/2015 12:38:43 AM Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PMschedule details. Margret Villalobos 140839 10/4/2015 11/4/2015	Medium	Work In Progress		11/16/2015 4:19:44 PM				
140909 10/4/2015 Medium Work In Progress 10/4/2015 12:38:43 AM Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PM schedule details. Margret Villalobos 10/4/2015 140839 10/4/2015	Marquez, 0	Gerardo	Please cut extra keys for Alamo C	afeteria.				
Medium Work In Progress 10/4/2015 12:38:43 AM Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PMschedule details. Margret Villalobos 10/4/2015 140839 10/4/2015	Albert Vall	lejo						
Villalobos, Margret Monthly - Anthony ES - Enviro Controls Quarterly - Refer to PMschedule details. Margret Villalobos 10/4/2015 11/4/2015	140909			10/4/2015		58		\$0.00
Refer to PMschedule details. Margret Villalobos 140839 10/4/2015 11/4/2015	Medium	Work In Progress		10/4/2015 12:38:43 AM				
140839 10/4/2015 11/4/2015	Villalobos	, Margret		trols Quarterly-				
	Margret Vi	illalobos						
Medium Work In Progress 10/4/2015 12:37:56 AM	140839			10/4/2015	11/4/2015	58		\$0.00
	Medium	Work In Progress		10/4/2015 12:37:56 AM				
Nunez, Arturo Yearly - Anthony ES H6 (Furnace Gas)(Yearly) - Refer to PMschedule details. Margret Villalobos				Gas)(Yearly) - Refer				

WOID Priority Assigned T		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester	Anthony	FS					
142313	Antiony		10/26/2015		36		\$0.00
Medium	Work In Progress		10/26/2015 1:32:44 PM		50		ψ0.00
Vega, Davi	-	SOAP DISPENSER THAT IS LOCA RESTROOM IS LEAKING. SNP MA B. 882.3507	TED IN KITCHEN				
Maritza Go	nzalez						
141174	AnnexBuilding	Office	10/6/2015		56		\$0.00
Medium	Work In Progress		10/6/2015 4:15:23 PM	1			
Nunez, Artı	uro	Please set up: 2 New employees no set up in the room that is close to the and cabinets to be moved in to tha 2 person office. We also need for so cabinets, desks etc to be moved ou set up in the hallways. For additiona stop by to see Susie or Mary. Than	e office. Need desk t room to set up as a ome storage t of those offices and al information please				
Susie Ran	nos Lara						
140303	Office	Office	9/21/2015		71		\$0.00
Medium	Work In Progress		9/21/2015 2:35:09 PM	1			
Nunez, Artı	uro	Need to move one brown desk and 109. The desk and file cabinet are office area. This office needs to be staff member.	located in the front				
Susie Ran	nos Lara						
140304	Office	Office	9/21/2015		71		\$0.00
Medium	Work In Progress		9/21/2015 2:36:19 PM	1			
Nunez, Artı	uro	Need to move one file cabinet to roc is located near the front office. If yo please ask Mary Bonet.					
Susie Ran	nos Lara						
140305	Office	Office	9/21/2015		71		\$0.00
Medium	Work In Progress		9/21/2015 2:37:36 PM	1			
Nunez, Arti	uro	Need to move two storage cabinets cabinets are located near the front information please ask Mary Bonet.	office. If you need				
Susie Ran							
140307	Office	Office	9/21/2015		71		\$0.00
Medium	Work In Progress		9/21/2015 2:40:07 PM	1			
Nunez, Arti	uro	Need to set up new office furniture the sped office. Please check in w					

WOID Priority Assigned ⁻	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester							
Location:	Anthony	ES					
139297		Office	9/3/2015		89		\$0.00
Medium	Work In Progress		9/3/2015 1:41:36 PM	1			
Nunez, Arti	uro	Need to have someone come in an conditioner grills in the SPED ADM					
Susie Ran	nos Lara						
143297			11/9/2015		22		\$0.00
Medium	Work In Progress		11/9/2015 9:41:42 AN	l			
Nunez, Art	uro	Need the following tools : C.O.2 test thermometer, laser thermometer.	er, digital pocket				
Arturo Nun	ez						
142974			11/3/2015		28		\$0.00
Medium	Work In Progress		11/3/2015 3:34:29 PM	1			
Nunez, Art	uro	Circulating hot water pumps need to pumps are bad.	be replaced both				
Arturo Nun	ez						
144014			11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 11:22:19				
Ronquillo,	Ruben	Need the following glasses replace 1/8.,371/2 x16 1/4 safety tempered 1/4double glass tinted module., 1ea double glass tinted module., 3 ea. 1 double glass tinted module.	glass.,37 1/2 x 16 a. 15 1/4 x 29 3/4				
Arturo Nun	ez						
143983			11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 12:51:55				
Apodaca, I	Mario	Monthly - Anthony ES - Monthly Meters to PM schedule details.	r Readings - Refer				
Margret Vil	lalobos						
136827			7/31/2015		123		\$0.00
Medium	Work In Progress	107	7/31/2015 9:04:38 AN	I			
Nunez, Arti	uro	Mr. Nunez, Please move white board to a differe Please see Ms. GibsonRoom #107	ntlocation				
Jessica Lo	opez						
136904			8/2/2015		121		\$0.00
Medium	Work In Progress		8/2/2015 12:31:58 AN	l			
Vallejo, Alt	pert	Yearly - Anthony ES Fire Ext. Insp. (PMschedule details.	rearly) - Refer to				
Margret Vil	lalobos						

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Locat Area Deferred By Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	ES					
144067			11/30/2015		1		\$0.00
Medium	Work In Progress	Library	11/30/2015 3:55:47 PM				
Marquez, (Gerardo	Metal door on north side of library need replacement Library Ms. Marquez	ds tightening or				
Jessica Lo	opez						
143309			11/9/2015		22		\$0.00
Medium	Work In Progress		11/9/2015 1:24:29 PM				
Orozco, Da	aniel	WASHER MACHINE IS NOT WORKIN BUT DOES NOT FILL UP WITH WATE WASH.SNP MANAGER LORENA B. 8	ER TO				
Maritza Go	onzalez						
143631			11/16/2015		15		\$0.00
Medium	Work In Progress		11/16/2015 11:47:14				
Orozco, Da	aniel	GARBAGE DISPOSAL IS NOT GRINE MANAGER LORENA B. 882.3507 (W. SUBMITTED, SHOWING AS DUPLICA	O. 142397				
Maritza Go	onzalez						
142697			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:03 AM				
Orozco, Da	aniel	Monthly - Anthony ES Range Hood Cl PMschedule details.	eaning - Refer to				
Margret Vi							
141175	AnnexBuilding	Stairway	10/6/2015		56		\$0.00
Medium	Work In Progress		10/6/2015 4:20:41 PM				
Vallejo, All	bert	We have cracks in the sidewalk that co building. We had an employee that trip and almost fell today. Also employees training materials in and out of the con having difficulty with their carts becaus Please send someone to assess the special ed department.	oped on the crack are trying to bring nplex and are se of these cracks.				
Susie Rar	nos Lara						
142718			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:17 AM				
Orozco, Da	aniel	Monthly - Anthony ES Fire Suppression PMschedule details.	on Insp Refer to				
Margret Vi	llalobos						

WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	ES					
140897			10/4/2015		58		\$0.00
Medium	Work In Progress		10/4/2015 12:38:35 AM				
Vallejo, Al	bert	Monthly - Anthony ES - Fire Sprinkl PMschedule details.	er Insp Refer to				
Margret Vi	illalobos						
136796			7/30/2015		71		\$0.00
Medium	Work In Progress		7/30/2015 3:53:27 PM	10/9/2015			
Holguin, A	Nfredo	Need to have a fire sprinkler connector room # 107. leaking prettybad.	ction repaired in	will fax to dimar for o	quote as	per alfred	0
Arturo Nu	nez						
135294			7/5/2015		149		\$0.00
Medium	Work In Progress		7/5/2015 12:30:37 AM				
Vallejo, Al	bert	Monthly - Anthony ES - Fire Pump I schedule details.	Engine - Refer to PM				
Margret Vi	illalobos						
140872			10/4/2015		58		\$0.00
Medium	Work In Progress		10/4/2015 12:38:19 AM				
Vallejo, Al	bert	Monthly - Anthony ES - Fire Pump I schedule details.	Engine - Refer to PM				
Margret Vi	illalobos						
143974			11/24/2015		7		\$0.00
Medium	Work In Progress		11/24/2015 12:34:40				
Nunez, Ar	turo	Daily - Anthony ES - Fire Pump (Bir schedule details.	weekly) - Refer to PM				
Margret Vi	illalobos						
Count: 31	Work Orders	Avg. Age of WO's 5	60	Total for Anthor	IY ES	0	\$0.00

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Tage Area Number Reason Created Date/Time A Description	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino Es	8				
140873		10/4/2015		58		\$0.00
Medium	Work In Progress	10/4/2015 12:38:19 AM				
Vallejo, Alb	pert	Monthly - Berino ES - Fire Pump Engine - Refer to PM schedule details.				
Margret Vil	lalobos					
135295		7/5/2015		149		\$0.00
Medium	Work In Progress	7/5/2015 12:30:37 AM				
Vallejo, Alb		Monthly - Berino ES - Fire Pump Engine - Refer to PM schedule details.				
Margret Vil	lalobos		/			<u> </u>
142719		11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress	11/1/2015 12:54:18 AM				
Orozco, Da		Monthly - Berino ES Fire Suppression Insp Refer to PMschedule details.				
Margret Vil	lalobos	10/1/00/5	4.0.10.5.10.0.4.5	=0		<u> </u>
140891		10/4/2015	10/25/2015	58		\$0.00
Medium	Work In Progress	10/4/2015 12:38:31 AM				
Vallejo, Alb		Monthly - Berino ES Fire Sprinkler Insp Refer to PM schedule details.				
Margret Vil	lalobos		4.4.100.100.4.5			<u> </u>
142698		11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress	11/1/2015 12:54:04 AM				
Orozco, Da		Monthly - Berino ES Range Hood Cleaning - Refer to PMschedule details.				
Margret Vil	lalobos	10/22/2015		40		\$0.00
142163				40		Ф 0.00
Medium Orozco, Da	Work In Progress	10/22/2015 2:27:38 PM WASHING MACHINE IS MAKING LOUD NOISE AND SHAKING TOO MUCH. SNP MANAGER MERCEDES				
Moritar O	2202	F.882.2417				
Maritza Go 141199	nzalez	10/7/2015		55		\$0.00
	Work In Brograss			00		ψ0.00
Medium Orozco, Da	Work In Progress	10/7/2015 12:53:27 PM SPRAYER HOSE ON DISHWASHER- SPRAYS WATER ALL OVER THE PLACE. SNP MANAGER MERCEDES F. 882.2417.				
Maritza Go	nzalez					

WOID Priority Assigned⊺ Requester	Building Status Fo	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description	arget Comp Date Day Actual Comp Date ^{Age} Action Taken		Costs
Location:	Berino ES	i			
141139		10/6/2015	56	6	\$0.00
Medium	Work In Progress	10/6/2015 3:19:29 PM			
Gonzalez,	Salvador	Need to install metal ramp on portable 18 thank you			
Sebastian	Diaz				
136905		8/2/2015	12'	1	\$0.00
Medium	Work In Progress	8/2/2015 12:31:59 AM			
Vallejo, Alb	pert	Yearly - Berino ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.			
Margret Vil	lalobos				
143984		11/30/2015		1	\$0.00
Medium	Work In Progress	11/30/2015 12:51:56			
Apodaca, I	Vlario	Monthly - Berino ES - Monthly Meter Readings - Refer to PMschedule details.			
Margret Vil	lalobos				
143294		11/9/2015	22	2	\$0.00
Medium	Work In Progress	11/9/2015 8:32:11 AM			
Ontiveros,	Joe	HANDLES TO 3 COMPARTMENT SINK AND HAND WASHING SINK ARE LEAKING. SNP MANAGER MERCEDES F. 882.2417			
Maritza Go	nzalez				
140913		10/4/2015	58	3	\$0.00
Medium	Work In Progress	10/4/2015 12:38:46 AM			
Villalobos,	Margret	Monthly - Berino ES - Enviro Controls Quarterly - Refer to PMschedule details.			
Margret Vil	lalobos				
139809		9/11/2015	8	1	\$0.00
Medium	Work In Progress	9/11/2015 12:58:12 PM			
Solis, Lore	nzo	Need to fix water fountain on room 121 thank you			
Sebastian	Diaz				
138589		8/24/2015	99	9	\$0.00
Medium	Work In Progress	8/24/2015 1:53:26 PM			
Diaz, Seba	stian	Need paint for walls on cafeteria TAN PLAN THANK YOU 5GL			
Sebastian	Diaz				
143636		11/16/2015	15	5	\$0.00
Medium	Work In Progress	11/16/2015 1:40:12 PM			
Ontiveros,	Joe	Need unclog sink on room 101 thank you			

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time Ac Description		Labor Hours	Total Costs
Location:	Berino ES	3			
143637		11/16/2015	15		\$0.00
Medium	Work In Progress	11/16/2015 1:41:51 PM			
Ontiveros,	, Joe	Need check leak water on boiler pipes thank you			
Sebastian	Diaz				
144024		11/30/2015	1		\$0.00
High	Work In Progress	11/30/2015 1:51:23 PM			
Appelzolle	er, Fred	BERINO KITCHEN DRAINS BACKING UP.SNP MANAGER MERCEDES F.882.2417			
Maritza Go	onzalez				
140256		9/18/2015	74		\$0.00
Medium	Work In Progress	9/18/2015 3:36:56 PM			
Chavez, S	antos	need to fix light on room 10 thank you			
Sebastian	n Diaz				
142687		11/1/2015	30		\$0.00
Medium	Work In Progress	11/1/2015 12:53:57 AM			
Diaz, Seba	astian	Yearly - Berino ES - Grease Trap - Refer to PM schedule details.			
Margret Vi	llalobos				
139814		9/11/2015	81		\$0.00
Medium	Work In Progress	9/11/2015 2:31:31 PM			
Chavez, S	antos	Need to install power for smart board on room 101 thank you			
Sebastian	n Diaz				
143635		11/16/2015	15		\$0.00
Medium	Work In Progress	11/16/2015 1:38:26 PM			
Chavez, S	antos	Need to check hand dryer on boy's restroom thank you			
Sebastian	Diaz				
Count: 21	Work Orders	Avg. Age of WO's 52	Total for Berino ES	0	\$0.00

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Target Created Date/Time Actual Ac		Labor Hours
Location:	Chaparra	II ES			
142688			11/1/2015	30	\$0.0
Medium	Work In Progress		11/1/2015 12:53:57 AM		
Quinones	, Paul	Yearly - Chaparral ES - Grease T schedule details.	rap - Refer to PM		
Margret Vi	llalobos				
143628			11/16/2015	15	\$0.0
Medium	Work In Progress		11/16/2015 11:13:26		
Chavez, S	antos	need outdoor lamps the 70 watt ty up.thanks	pe120voltset		
Paul Quin	ones				
139975			9/15/2015	77	\$0.0
Medium	Work In Progress		9/15/2015 11:35:50 AM		
Chavez, S		please chk exterior lighting new w portables as well.thanks	ing lights are out,and		
Paul Quin	ones		10/12/2015	50	<u>ቀ</u> ር ር
141567				50	\$0.0
Medium	Work In Progress		10/12/2015 3:58:09 PM		
Chavez, S		chk outside lighting new wing 200) wing thanks		
Paul Quin			0/4/00/15		
139378	E.Building	Classroom	9/4/2015	88	\$0.0
Medium	Work In Progress	404	9/4/2015 1:53:11 PM		
Chavez, S	antos	needs electrical for the computers already submitted by Paul mainte Paul or Mr. M. Villalobos			
Jennifer C	Corral				
137181		Classroom	8/4/2015	119	\$0.0
Medium	Work In Progress	220	8/4/2015 9:13:37 AM		
Chavez, S	antos	Need electrical outlet for projector Pargas	s as per Arnold/Mrs.		
Jennifer C	Corral				
137182		Classroom	8/4/2015	119	\$0.0
Medium	Work In Progress	217	8/4/2015 9:14:33 AM		
Chavez, S	antos	Need electrical outlet for projector Pargas	s as per Arnold/Mrs.		
Jennifer C	Corral				

Selected Dat WOID Priority Assigned 1 Requester		Dates:7/1/2015 - 6 Area Area Number Description	Deferred By	Until	•	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	I ES							
143176					11/6/2015		25		\$0.00
Medium	Work In Progress			11/6/2	2015 8:16:47 AM	1			
Solis, Lore	nzo		ed or surface typ elec equesting 1 208/240						
Paul Quind	ones								
143180					11/6/2015		25		\$0.00
Medium	Work In Progress			11/6/2	2015 8:29:44 AN	1			
Solis, Lore	nzo	needing filter m 1/2".thank you.	aterial for heaters h	ogs hair 1 rl.					
Paul Quind	ones						- 10		
143570					11/13/2015		18		\$0.00
Medium	Work In Progress			11/13/2	2015 3:40:38 PM	1			
Quinones,	Paul	no heating in po relays	ortable #6 problem v	vith the heat s	trip				
Paul Quind	ones								
142468		Custodial			10/28/2015		34		\$0.00
Medium	Work In Progress			10/2	8/2015 10:25:44	ļ			
Carbajal, J	limmy	need,four,vacc	um,belts.						
Daniel Rai									
142567	Main Building	Classroom			10/29/2015		33		\$0.00
Medium	Work In Progress	206		10/29/2	2015 3:24:43 PN	1			
Quinones,	Paul	Ceiling is leaki	ng.seeMs.Barraza						
Jennifer C	orral								
136906					8/2/2015		121		\$0.00
Medium	Work In Progress			8/2/20)15 12:32:00 AN	1			
Vallejo, Alb	pert	Yearly - Chapa PMschedule d	rral ES Fire Ext. Ins _f etails.	o. (Yearly) - R	efer to				
Margret Vil	lalobos								
142112		Athletic Field			10/21/2015		41		\$0.00
Medium	Work In Progress			10/21/2	2015 3:49:46 PN	1			
Ontiveros,	Guadalupe	Ms. Nougues is	s requesting a basel	ball field.					
Guadalung	e Ontiveros								

Selected Dat WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loca Area Deferred By Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	I ES					
142956			11/3/2015		28		\$0.00
Medium	Work In Progress		11/3/2015 11:02:44 AM				
Orozco, Da	niel	AS PER ENVIRONMENTAL HEALTH 10/23/15. INSUFFICIENT BACKDO OUTER AIR, NEED DOOR SWEEPS ESTHER C. 824.0048	OR SEAL TO				
Maritza Go	nzalez						
144018			11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 12:47:38				
Marquez, G	Gerardo	requesting handicap door closer do cafeteria principle requesting door c student					
Paul Quind	ones						
143693	Main Building	Classroom	11/17/2015		14		\$0.00
Medium	Work In Progress	308	11/17/2015 8:35:33 AM				
Gonzales,	Camilo	pick up monitors, All in One's, and Cl room 308. As per Ms. El-kurdi these looked at and cleaned out by tech. S further information	items have been				
Jennifer Co	orral						
142699			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:05 AM				
Orozco, Da	niel	Monthly-Chapparal ES Range Hood to PMschedule details.	d Cleaning - Refer				
Margret Vil	lalobos						
142720			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:19 AM				
Orozco, Da		Monthly-Chaparral ES Fire Suppres to PMs chedule details.	ssion Insp Refer				
Margret Vil	lalobos		0/05/0045		67		<u> </u>
140630			9/25/2015		67		\$0.00
Medium	Work In Progress		9/25/2015 10:42:30 AM				
Carbajal, J	-	requesting new tile in staffs rest rms going into rest rms.	, and floor entrance				
Paul Quino 139719	EastCentral	Classroom	9/10/2015		82		\$0.00
		0103310011			02		ψ0.00
Medium	Work In Progress	.	9/10/2015 9:51:47 AM				
Estrada, Je		Aseam is coming apart in classroor	n #505.				
Jesus Estr		Ave. Ame - (1410)		Total for Obarra			¢0.00
Count: 21 V	Work Orders	Avg. Age of WO's 50	1	Total for Chaparra	ai E9	0	\$0.00

002 -			1091633 (F13Ca	i i cai j				Tota
Selected Da WOID Priority	ate Range for Request Building Status	Dates:7/1/2015 - 6 Area Area Number	/30/2016 Order By Loca Deferred By Poason	Until	Request Date	Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned		Description	Reason			Action Taken	C		
Requeste									
Location:	Chaparra	al High - Pre-K							
142465					10/28/2015	i	34		\$0.00
Medium	Work In Progress	FEDERAL		10/28	3/2015 9:45:21 AN	Л			
Flores, Pe	ete		TARTED BUT ALL L AND OFF AND WAS						
Noemi Du	uron								
142378		Exterior			10/27/2015		35		\$0.00
Medium	Work In Progress			10/27	7/2015 9:20:11 AN	Л			
Appelzolle	er, Fred	Check for wate next to water o	r leak, to much cond utlet outside.	lensate on v	vindow				
Alfredo Or	rtiz								
Count: 2 V	Vork Orders	A	vg. Age of WO's	35	Total fo	or Chaparral High - F	Pre-K	0	\$0.00
		A	vg. Age of WO's	35	Total fo	or Chaparral High - F	Pre-K		0

862 - Work Orders In Progress (Fiscal Year)

WOID Priority Assigned	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date Tar Created Date/Time Act		Labor Hours	Costs
Location:	Chaparra	al HS				
144088	E-Wing	Restroom	12/1/2015	0		\$0.00
Medium	Work In Progress		12/1/2015 10:38:24 AM			
Appelzolle	r, Fred	Need to replace handicap toilet bro	ken E-wing boys			
Alfredo Ort	tiz					
137495	R-Wing	Pump House	8/7/2015	116		\$0.00
Medium	Work In Progress		8/7/2015 11:26:04 AM			
Appelzolle	r, Fred	One Circulating pump is leaking w won't start, In R-Buil. Pump room.	ater. The other pump			
Alfredo Ort	tiz					
142691			11/1/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:53:59 AM			
Ortiz, Alfred	do	Yearly - Chaparral HS - Grease Tr schedule details.	ap - Refer to PM			
Margret Vil	llalobos					
141757			10/15/2015	47		\$0.00
Medium	Work In Progress		10/15/2015 9:02:41 AM			
Appelzolle	r, Fred	need a water hose for outside by co hose is all torn.	ompactor the other			
Jesus Urq	luidi					
142147			10/22/2015	40		\$0.00
Medium	Work In Progress		10/22/2015 10:36:40			
Appelzolle	r, Fred	Need hot water in Home Economic	cs.			
Albert Valle	ejo					
137857	Field House	Athletic Field	8/12/2015	111		\$0.00
Medium	Work In Progress	Softball field	8/12/2015 3:36:25 PM			
Chavez, Sa	antos	Need electricityfor new softball/ba (Mireya Meza)	seball batting cage.			
Mireya Mez						
137624	C-Wing	Classroom	8/10/2015	113		\$0.00
Medium	Work In Progress		8/10/2015 9:37:57 AM			
Chavez, Sa	antos	In C-6 Green-house need to rewire exhaust fan and A/C. Thank you.	electicity for heater,			
Alfredo Ort						
137427	B-Wing	Classroom	8/6/2015	117		\$0.00
Medium	Work In Progress	B2	8/6/2015 2:49:56 PM			
Chavez, Sa	antos	Need a wall plug socket in room.	(Ms. Perez, B2)			
Mireya Mez	za					
	4:03:40 PM				Daga	21 of 137

12/1/2015 4:03:40 PM

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	al HS					
141762	Pre-K	Roof	10/15/2015		47		\$0.00
Medium	Work In Progress		10/15/2015 10:17:47				
Solis, Lore	-	Need to replace condenser fan m	otor.				
Alfredo Or	tiz	·					
144012	H-Wing	Gym	11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 11:18:38	6			
Solis, Lore	enzo	Having problem with heater for G	βΥM				
Alfredo Or	tiz						
143787	Q-Wing	Mechanical	11/18/2015		13		\$0.00
Medium	Work In Progress		11/18/2015 3:16:38 PM	I			
Solis, Lore	enzo	Need to Replace seals on Geo the water.	ermal pumps leaking				
Alfredo Or							
143875	Field House	Exterior	11/19/2015		12		\$0.00
Medium	Work In Progress		11/19/2015 3:47:55 PN	l			
Marquez,	Gerardo	Need to fix door cylinders at weig	ht room hard to open.				
Alfredo Or	tiz						
143319			11/9/2015		22		\$0.00
Medium	Work In Progress		11/9/2015 3:10:52 PM	1			
Marquez,		need fixtwo closure door pomp o cafeteria and gym to	ne in eastside				
Juan Varg		2	44/40/0045		40		.
143474		Classroom	11/12/2015		19		\$0.00
Medium Marquez, (Work In Progress Gerardo	Need to install a door lock in Q-6 b and welding shop. Auto parts missing.	11/12/2015 10:31:03 between auto shop				
Alfredo Or	tiz						
140543			9/24/2015	_	68		\$0.00
Medium	Work In Progress		9/24/2015 8:34:17 AN	1			
Marquez,	Gerardo	PLEASE WELD PADLOCKS AND	CHAINS ON GATES.				
Gerardo N	-						
143767	Q-Wing	Classroom	11/18/2015		13		\$0.00
Medium	Work In Progress	Q7 / Autoshop	11/18/2015 9:11:23 AM	1			
Marquez,		The lock for the gate to go tot the locking properly. (Mr. Rodriguez, a					
Mireya Me	za						
10/1/0045	1.03.40 PM					D	22 of 127

12/1/2015 4:03:40 PM

Cacation: Chaparral HS 138388 Q-Wing Classroom 8/20/2015 103 \$0 Medium Work In Progress Q6 8/20/2015 1012:00 AM \$0 Marquez, Gerardo Please make copy of Matco key 172. This key opens tool box in Autoshop. We also need copies made for all the other tool box keys. Please see Mireya. (Mireya Meza \$139947 Field House Mechanical 9/14/2015 78 \$0 Medium Work In Progress 9/14/2015 3:58:21 PM \$2 \$2 Medium Work In Progress Buster pump for irrigation has to be reset every day, needs to checked electrical power. \$17/2015 75 \$0 Medium Work In Progress 9/17/2015 75 \$0 Medium Work In Progress 9/17/2015 75 \$0 Medium Work In Progress 8/27/2015 96 \$0 Medium Work In Progress 8/27/2015 13.13 PM \$13826 \$12320 has huge ball on side of time plase replaced. Guadalupe Ontiveros, Guadalupe Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas) \$124262 \$127/2015 34 \$0	WOID Priority Assigned Requester		Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
138388 Q-Wing Classroom 8/20/2015 103 SC Medium Work In Progress Q6 8/20/2015 10:12:00 AM Marquez, Gerardo Please make copy of Matox key 172. This key opens tool boxin Atuboshop. We also need copies made for all the other tool box keys. Please see Mireya. (Mireya Meza) Mireya Mireya Meza	Location:		al HS						
Medium Work in Progress 0.6 8/20/2015 10:12:00 AM Marquez, Gerardo Please make copy of Matox key 172. This key opens too'l boxin. Autoshop. We also need copies made for all we other too'l box keys. Please see Mireya (Mireya Mireya Mi	138398	-			8/20/2015		103		\$0.00
Marquez, Gerardo Please make copy of Matco key 172. This key opens tool boxin Autoshop. We also need copies made for all the other tool box keys. Please see Mireya. (Mireya Meza) Mireya Meza 139347 Field House Mechanical 9/14/2015 78 \$C Medium Work In Progress 9/14/2015 3.58:21 PM \$C \$C Chavez, Santos Buster pump for irrigation has to be reset every day, needs to checked electrical power. 9/17/2015 75 \$C Alfredo Ortiz 9/17/2015 75 \$C \$C <td></td> <td>C</td> <td>Q6</td> <td></td> <td>8/20/2015 10:12:00 AM</td> <td>1</td> <td></td> <td></td> <td></td>		C	Q6		8/20/2015 10:12:00 AM	1			
139947 Field House Mechanical 9/14/2015 78 \$C Medium Work in Progress 9/14/2015 3:58:21 PM C Chavez, Santos Buster pump for irrigation has to be reset every day, needs to checked electrical power. 9/17/2015 75 \$C Alfredo Ortiz 9/17/2015 75 \$C \$C Ortiz, Alfredo Athletic Data Clerk - Paint office area 9/17/2015 96 \$C Medium Work in Progress 9/17/2015 96 \$C Medium Work in Progress 8/27/2015 96 \$C Medium Work in Progress 8/27/2015 113:19 PM Flores, Pete Jd 3320 has huge ball on side of tire plase replaced. Guadalupe Ontiveros 124242 Field House Athletic Field 10/28/2015 34 \$C Medium Work in Progress Baseball Field 10/28/2015 34 \$C Medium Work in Progress Baseball Field 10/28/2015 38 \$C Medium Work in Progress Sudalupe Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas) \$V <td>Marquez, (</td> <td>C C</td> <td>tool boxin Auto the other tool b</td> <td>shop. We also need</td> <td>copies made for all</td> <td></td> <td></td> <td></td> <td></td>	Marquez, (C C	tool boxin Auto the other tool b	shop. We also need	copies made for all				
Medium Work In Progress Buster pump for irrigation has to be reset every day, needs to checked electrical power. Affredo Ortiz 9/17/2015 75 \$0 140132 9/17/2015 75 \$0 Medium Work In Progress 9/17/2015 75 \$0 Ortiz, Alfredo Athletic Data Clerk - Paint office area 9/17/2015 10 \$0 Abert Vallejo Athletic Data Clerk - Paint office area 8/27/2015 13 \$0 Redium Work In Progress 8/27/2015 113:19 PM \$0 Flores, Petro Jd 3320 has huge ball on side of tire plase replaced. \$0 \$0 Guadalupe Ontiveros Baseball Field 10/28/2015 34 \$0 Medium Work In Progress Baseball Field 10/28/2015 34 \$0 Medium Work In Progress Baseball Field 10/28/2015 34 \$0 Medium Work In Progress Baseball Field 10/28/2015 34 \$0 Medium Work In Progress Baseball Field 10/28/2015 38 \$0 Medium Work In Progress Baseball Field 10/28/2015 38 \$0 Mireya Mezz Integreas remove shrubberyin planters nearesthe parking lotby the a			<u></u>						
Chavez, Santos Buster pump for irrigation has to be reset every day, needs to checked electrical power. Alfredo Ortiz 140132 9/17/2015 75 \$0 Nedium Work In Progress 9/17/2015 75 \$0 Ortiz, Alfredo Athletic Data Clerk - Paint office area Abert Vallejo Athletic Data Clerk - Paint office area 8/27/2015 96 \$0 I 38858 8/27/2015 96 \$0	139947	Field House	Mechanical		9/14/2015		78		\$0.00
Alfredo Ortiz Alfredo Ortiz Hedo Ortiz Hedo Ortiz Hordo Ortiz Hedo Ortiz Hedo Ortiz Hedo Ortiz Hedo Nork In Progress Philot Data Clerk - Paint office area Abert Vallejo Hedium Work In Progress Ba/27/2015 10:35:25 AM Ortiz, Alfredo Athletic Data Clerk - Paint office area Abert Vallejo U U U U U U U U U U U U U U U U U U U	Medium	Work In Progress			9/14/2015 3:58:21 PM	1			
140132 9/17/2015 75 \$C Medium Work In Progress 9/17/2015 10:35:25 AM Ortiz, Alfredo Athletic Data Clerk - Paint office area Albert Vallejo 138858 8/27/2015 96 \$C Medium Work In Progress 8/27/2015 11:3:19 PM PM Flores, Pete Jd 3320 has huge ball on side of tire plase replaced. Guadalupe Ontiveros 14/2462 Field House Athletic Field 10/28/2015 34 \$C Medium Work In Progress Baseball Field 10/28/2015 34 \$C Medium Work In Progress Baseball Field 10/28/2015 34 \$C Medium Work In Progress Baseball Field 10/28/2015 34 \$C Mireya Meza 139387 9/4/2015 88 \$C Medium Work In Progress 9/4/2015 88 <td< td=""><td>Chavez, S</td><td>antos</td><td>needs to check</td><td>ed</td><td>be reset every day,</td><td></td><td></td><td></td><td></td></td<>	Chavez, S	antos	needs to check	ed	be reset every day,				
Medium Work In Progress 9/17/2015 10:35:25 AM Ortiz, Alfredo Athletic Data Clerk - Paint office area Abert Vallejo 138858 & 8/27/2015 96 \$00 Medium Work In Progress 8/27/2015 1:13:19 PM 96 \$00 Flores, Pete Jd 3320 has huge ball on side of tire plase replaced. 96 \$00 Guadalupe Ontiveros 10/28/2015 1:13:19 PM 96 \$00 Hedium Work In Progress 8aseball Field 10/28/2015 9:32:29 AM \$00 Medium Work In Progress Baseball Field 10/28/2015 9:32:29 AM \$00 Ontiveros, Guadalupe Install dug outmade of cinder block. In visitor and home dug outs. (Coach Rojas) \$01 Mreya Meza 133387 \$9/4/2015 3:16:11 PM \$00 Ontiveros, Guadalupe Please remove shrubberyin planters nearest the parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) \$02 Abert Vallejo 140161 Field House Athletic Field \$017/2015 2:20:24 PM Abert vallejo To have green wind screens placed around the entire \$017/2015 2:20:24 PM		tiz			- /				
Oriz, Alfredo Athletic Data Clerk - Paint office area Albert Vallejo 96 13868 8/27/2015 96 \$0 Medium Work In Progress 8/27/2015 1:13:19 PM Flores, Pete Jd 3320 has huge ball on side of tire plase replaced. 4/2422 Field House Athletic Field 10/28/2015 34 \$0 Medium Work In Progress Baseball Field 10/28/2015 9:32:29 AM 10/28/2015 34 \$0 Medium Work In Progress Baseball Field 10/28/2015 9:32:29 AM 10/28/2015 34 \$0 Ontiveros, Guadalupe Install dug outmade of cinder block. In visitor and home dug outs. (Coach Rojas) 10/28/2015 316:11 11 Mreya Meza 139387 9/4/2015 316:11 PM Ontiveros, Guadalupe Please remove shrubbery in planters nearest the parking lotby the amphitheater and replace with low maintenance lands caping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) Albert Vallejo 75 \$0 Abort Vallejo 140161 Field House Athletic Field 9/17/2015 75 \$0 Medium	140132				9/17/2015		75		\$0.00
Abert Vallejo 13858 8/27/2015 1:13:19 PM Flores, Pete Jd 3320 has huge ball on side of tire plase replaced. Guadalupe Ontiveros 142462 Field House Athletic Field 10/28/2015 9:32:29 AM Ontiveros, Guadalupe Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas) Mireya Meza 139387 9/4/2015 3:16:11 PM Nedium Work In Progress 9/4/2015 3:16:11 PM Please remove shrubbery in planters nearest the parking lot by the amphitheater and replace with low maintenance lands caping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) Abert Vallejo To have green wind screens placed around the entire To have green wind screens placed around the entire	Medium	Work In Progress			9/17/2015 10:35:25 AM	1			
138858 8/27/2015 96 \$C Medium Work In Progress 8/27/2015 1:13:19 PM Flores, Pete Jd 3320 has huge ball on side of tire plase replaced. Guadalupe Ontiveros Guadalupe Ontiveros 10/28/2015 9:32:29 AM SC Medium Work In Progress Baseball Field 10/28/2015 9:32:29 AM SC Ontiveros, Guadalupe Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas) 9/4/2015 3:16:11 PM SC Mireya Meza 9/4/2015 3:16:11 PM 9/4/2015 3:16:11 PM SC Ontiveros, Guadalupe Please remove shrubbery in planters nearest the parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) SC Abert Vallejo 140161 Field House Athletic Field 9/17/2015 75 \$C Medium Work In Progress Football & 9/17/2015 2:20:24 PM SC Ontiveros, Guadalupe To have green wind screens placed around the entire SC SC	Ortiz, Alfre	do	Athletic Data C	lerk - Paint office a	rea				
Medium Work In Progress 8/27/2015 1:13:19 PM Flores, Pete Jd 3320 has huge ball on side of tire plase replaced. Guadalupe Ontiveros 10/28/2015 34 \$C 142462 Field House Athletic Field 10/28/2015 34 \$C Medium Work In Progress Baseball Field 10/28/2015 9:32:29 AM Total dug out made of cinder block. In visitor and home dug outs. (Coach Rojas) Total dug outs. (Coach Rojas) Total dug outs. (Coach Rojas) Total dug outs. (Coach Rojas) 88 \$C Medium Work In Progress Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas) 9/4/2015 88 \$C Medium Work In Progress 9/4/2015 3:16:11 PM Total dug out made of cinder place with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) St \$C Albert Vallejo Totave green wind screens placed around the entire 9/17/2015 75 \$C Medium Work In Progress Football & 9/17/2015 9/17/2015 \$C \$C Ontiveros, Guadalupe To have green wind screens placed around the entire 9/17/2015 \$C \$C	Albert Vall	ejo							
Flores, Pete Jd 3320 has huge ball on side of tire plase replaced. Guadalupe Ontiveros 10/28/2015 34 \$0 142462 Field House Athletic Field 10/28/2015 9:32:29 AM 10	138858				8/27/2015		96		\$0.00
Guadalupe Ontiveros 142462 Field House Athletic Field 10/28/2015 34 \$C Medium Work In Progress Baseball Field 10/28/2015 9:32:29 AM Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas) Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas) Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas) 9/4/2015 88 \$C Mireya Meza 9/4/2015 88 \$C 139387 9/4/2015 3:16:11 PM 88 \$C Medium Work In Progress 9/4/2015 3:16:11 PM \$C Ontiveros, Guadalupe Please remove shrubberyin planters nearest the parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) Albert Vallejo Albert Vallejo 140161 Field House Athletic Field 9/17/2015 75 \$C Medium Work In Progress Football & 9/17/2015 9/17/2015 75 \$C Medium Work In Progress Football & 9/17/2015 2:0:24 PM \$C Ontiveros, Guadalupe To have green wind screens placed around the entire To have green wind screens placed aro	Medium	Work In Progress			8/27/2015 1:13:19 PM	1			
142462 Field House Athletic Field 10/28/2015 34 \$C Medium Work In Progress Baseball Field 10/28/2015 9:32:29 AM 10/28/2015 9:32:29 AM 10/28/2015 9:32:29 AM Ontiveros, Guadalupe Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas) 13/28/2015 9:32:29 AM 10/28/2015 9:32:29 AM Mireya Meza 13/28/2015 9/4/2015 88 \$C 139387 9/4/2015 88 \$C Medium Work In Progress 9/4/2015 3:16:11 PM 88 \$C Ontiveros, Guadalupe Please remove shrubbery in planters nearest the parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) Albert Vallejo Albert Vallejo 140161 Field House Athletic Field 9/17/2015 75 \$C Medium Work In Progress Football & 9/17/2015 2:20:24 PM 9/17/2015 2:20:24 PM Ontiveros, Guadalupe To have green wind screens placed around the entire	Flores, Pe	te	Jd 3320 has hu	ige ball on side of ti	re plase replaced.				
142462 Field House Athletic Field 10/28/2015 34 \$C Medium Work In Progress Baseball Field 10/28/2015 9:32:29 AM 10/28/2015 9:32:29 AM 10/28/2015 9:32:29 AM Ontiveros, Guadalupe Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas) 13/28/2015 9:32:29 AM 10/28/2015 9:32:29 AM Mireya Meza 13/28/2015 9/4/2015 88 \$C 139387 9/4/2015 88 \$C Medium Work In Progress 9/4/2015 3:16:11 PM 88 \$C Ontiveros, Guadalupe Please remove shrubbery in planters nearest the parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) Albert Vallejo Albert Vallejo 140161 Field House Athletic Field 9/17/2015 75 \$C Medium Work In Progress Football & 9/17/2015 2:20:24 PM 9/17/2015 2:20:24 PM Ontiveros, Guadalupe To have green wind screens placed around the entire	Guadalup	e Ontiveros							
Ontiveros, Guadalupe Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas) Mireya Meza 139387 139387 9/4/2015 Medium Work In Progress Ontiveros, Guadalupe Please remove shrubberyin planters nearest the parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) Albert Vallejo 140161 Field House Athletic Field Modium Work In Progress Football & 9/17/2015 2:20:24 PM Ontiveros, Guadalupe To have green wind screens placed around the entire	142462	Field House	Athletic Field		10/28/2015		34		\$0.00
Mireya Meza 9/4/2015 88 \$0 139387 9/4/2015 88 \$0 Medium Work In Progress 9/4/2015 3:16:11 PM \$0 Ontiveros, Guadalupe Please remove shrubbery in planters nearest the parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) \$140161 Field House Athletic Field 9/17/2015 75 \$0 Medium Work In Progress Football & 9/17/2015 2:20:24 PM \$0 Ontiveros, Guadalupe To have green wind screens placed around the entire \$17/2015 2:20:24 PM \$17/2015 \$12:20:24 PM \$12:20:2	Medium	Work In Progress	Baseball Field		10/28/2015 9:32:29 AN	1			
139387 9/4/2015 88 \$0 Medium Work In Progress 9/4/2015 3:16:11 PM \$1 Ontiveros, Guadalupe Please remove shrubbery in planters nearest the parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) See Ms. Payen or Albert for location if in question) Albert Vallejo 140161 Field House Athletic Field 9/17/2015 75 \$0 Medium Work In Progress Football & 9/17/2015 2:20:24 PM \$1 To have green wind screens placed around the entire	Ontiveros,	Guadalupe			k. In visitor and home				
Medium Work In Progress 9/4/2015 3:16:11 PM Ontiveros, Guadalupe Please remove shrubberyin planters nearest the parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) Albert Vallejo 140161 Field House Athletic Field 9/17/2015 75 \$C Medium Work In Progress Football & 9/17/2015 2:20:24 PM 9/17/2015 2:20:24 PM \$C	Mireya Me	za							
Ontiveros, Guadalupe Please remove shrubbery in planters nearest the parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question) Albert Vallejo 140161 Field House Athletic Field 9/17/2015 Medium Work In Progress Football & 9/17/2015 2:20:24 PM Ontiveros, Guadalupe To have green wind screens placed around the entire	139387				9/4/2015		88		\$0.00
parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question)Albert Vallejo140161Field HouseAthletic Field9/17/201575\$0MediumWork In ProgressFootball &9/17/2015 2:20:24 PM9/17/2015 2:20:24 PMOntiveros, GuadalupeTo have green wind screens placed around the entire	Medium	Work In Progress			9/4/2015 3:16:11 PM	1			
140161Field HouseAthletic Field9/17/201575\$0MediumWork In ProgressFootball &9/17/2015 2:20:24 PMOntiveros, GuadalupeTo have green wind screens placed around the entire	Ontiveros,	Guadalupe	parking lot by th maintenance la and some indig	e amphitheater and andscaping. (Prima genous flora) See M	replace with low ryscreening, boulders				
MediumWork In ProgressFootball &9/17/2015 2:20:24 PMOntiveros, GuadalupeTo have green wind screens placed around the entire		-							
Ontiveros, Guadalupe To have green wind screens placed around the entire	140161	Field House	Athletic Field		9/17/2015		75		\$0.00
	Medium	Work In Progress	Football &		9/17/2015 2:20:24 PN	1			
	Ontiveros,	Guadalupe							
Mireya Meza	Mireya Me	za							

WOID Priority Assigned	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date Target Created Date/Time Actual	· · · · ·	Costs Labor Hours
Location:	Chaparra	II HS			
143601			11/15/2015	16	\$0.00
Medium	Work In Progress		11/15/2015 12:27:52		
Flores, Pe	te	Yearly - Chaparral HS M-0405 (Z- Refer to PMschedule details.	Track) Grounds -		
Margret Vil	llalobos				
136928			8/2/2015	121	\$0.00
Medium	Work In Progress		8/2/2015 12:32:13 AM		
Flores, Pe	te	Monthly - CHS-UV-0513 PM Servic schedule details.	e - Refer to PM		
Margret Vil	llalobos				
142130			10/21/2015	41	\$0.00
Medium	Work In Progress		10/21/2015 4:19:14 PM		
Ortiz, Alfred		We need letters to identify hall way inside and outside of every wing.			
Mireya Mez	za		44/40/2045	45	¢
143638			11/16/2015	15	\$0.00
Medium	Work In Progress		11/16/2015 2:37:24 PM		
Apodaca, I	Mario	Need to install a water meter in the see if there is a water leak undergrowater line.			
Alfredo Ort	tiz				
141677			10/14/2015	48	\$0.00
Medium	Work In Progress		10/14/2015 10:52:34		
Vallejo, Alt	bert	Repair leaks in geo-thermal system	m throughout building.		
Albert Valle	ejo				
142230	Field House	Mechanical	10/23/2015	39	\$0.00
Medium	Work In Progress		10/23/2015 11:59:03		
Ortiz, Alfred	do	Need to reroute water and drain pip field house.	bes leak in ceiling. At		
Alfredo Ort	tiz				
142129	I-Wing	Classroom	10/21/2015	41	\$0.00
Medium	Work In Progress	Band room	10/21/2015 4:10:18 PM		
Estrada, Je	esus	Please replace carpet in band roor band roor	n with tile. (Mr. Rios,		
Mireya Mez					

Selected Dat WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	al HS					
140408	Field House	Storage	9/22/2015		70		\$0.00
Medium	Work In Progress		9/22/2015 3:10:01 PM				
Vallejo, Alb	pert	Trouble in fire sprinkler system					
Alfredo Orti	iz						
142695			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:02 AM				
Orozco, Da	niel	Monthly-Chaparral HS Range Ho PMschedule details.	od Cleaning - Refer to				
Margret Vill							
141351	Field House	Athletic Field	10/9/2015		53		\$0.00
Safety	Work In Progress	Visitors seating	10/9/2015 9:12:28 AM				
Vallejo, Alb	pert	We had an issue at one of our foot visitors seating area. There was a that wanted to sit on the visitors s wheelchair due to going through th to be sidewalks going to the visitor Ulibarri)	ladyon a wheelchair ide, but fell out of her ne dirt. There needs				
Mireya Mez	ra						
135292			7/5/2015		149		\$0.00
Medium	Work In Progress		7/5/2015 12:30:35 AM				
Vallejo, Alb		Monthly - Chaparral HS - Fire Pun PMschedule details.	np Engine - Refer to				
Margret Vill	lalobos		40/4/0045		50		<u> </u>
140870			10/4/2015		58		\$0.00
Medium	Work In Progress		10/4/2015 12:38:17 AM				
Vallejo, Alb		Monthly - Chaparral HS - Fire Pun PMschedule details.	np Engine - Refer to				
Margret Vill	lalobos		11/01/0015		7		\$0.00
143976			11/24/2015		7		\$0.00
Medium	Work In Progress		11/24/2015 12:34:41				
Ortiz, Alfrec		Daily - Chaparral HS - Fire Pump PMschedule details.	(Biweekly) - Refer to				
Margret Vill	lalobos						* •••••
142738			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:31 AM				
Orozco, Da Margret Vill		Monthly-Chaparral HS Fire Suppr to PMschedule details.	ession Insp Refer				

WOID Priority Assigned	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By I Area Deferred By Area Number Reason Description		•	Days Labo Aged Hour	
Location:	Chaparra	al HS				
140901			10/4/2015		58	\$0.00
Medium	Work In Progress		10/4/2015 12:38:38 AM			
Vallejo, Alt	pert	Monthly - Chaparral HS Pre-K- F Refer to PMschedule details.	ire Sprinkler Insp -			
Margret Vil	lalobos					
140898			10/4/2015		58	\$0.00
Medium	Work In Progress		10/4/2015 12:38:36 AM			
Vallejo, Alt	pert	Monthly - Chaparral HS - Fire Sp PMschedule details.	rinkler Insp Refer to			
Margret Vil	lalobos					
142396			10/27/2015		35	\$0.00
Medium	Work In Progress		10/27/2015 12:59:35			
Orozco, Da	aniel	NEON LIGHTS FOR FOLLOWIN WORKING RED & GREEN, FRESH FROM ⁻ ON A BUN. SNP MANAGER JUA	THE GARDEN AND			
Maritza Go						
143521	R-Wing	Classroom	11/12/2015		19	\$0.00
Medium	Work In Progress		11/12/2015 4:00:54 PM			
Orozco, Da	aniel	One of the stove ovens not worki replace gas valve. In Home Economics classroom.	ing need to fix or			
Alfredo Ort						
142460	Field House	Athletic Field	10/28/2015		34	\$0.00
Medium	Work In Progress	Baseball Field	10/28/2015 9:28:03 AM			
Gonzalez,	Salvador	Please install 4 mini batting cage (Coach Rojas)	es for baseball field.			
Mireya Mez						
142461	Field House	Athletic Field	10/28/2015		34	\$0.00
Medium	Work In Progress	Baseball Field	10/28/2015 9:30:35 AM			
Gonzalez,	Salvador	Please install bull pen in visitors Rojas)	dugoutarea. (Coach			
Mireya Mez						
142463	Field House	Athletic Field	10/28/2015		34	\$0.00
Medium	Work In Progress	baseball field	10/28/2015 9:33:25 AM			
Gonzalez,	Salvador	Please install back stop extensio backstop. (Coach Rojas)	on on baseball field			
Mireya Mez	za					

002 -			IUGIE33	(1 150a	i i eai j				Total
Selected Da WOID	ate Range for Request Building	Dates:7/1/2015 - 6 Area	/30/2016 Order By Lo Deferred By	ocation, Status Until		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Cre	eated Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Chaparra	II HS							
136921					8/2/2015		121		\$0.00
Medium	Work In Progress			8/2/2	2015 12:32:08 AM	1			
Vallejo, Al	bert	Yearly - Chapa PMschedule d	rral HS Fire Ext. Ins etails.	sp. (Yearly) -	Refer to				
Margret Vi	illalobos								
141268	Q-Wing	Classroom			10/8/2015		54		\$0.00
Medium	Work In Progress	Q2		10/8	/2015 8:53:30 AN	1			
Marquez,	Gerardo	•	ge door is a second se all the way. Lets . Waters, Q2)		•				
Mireya Me	za								
Count: 46	Work Orders	A	vg. Age of WO's	54		Total for Chaparra	al HS	0	\$0.00

WOID Priority Assigned 1 Requester		•		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Chaparra	IMS					
143314		1	1/9/2015		22		\$0.00
Medium	Work In Progress	11/9/2015 2	:22:11 PN	1			
Vallejo, Alb	pert	Create pad for dumpsters in bus turnaround.					
Albert Valle	ejo						
138787	-	3	3/26/2015		97		\$0.00
Medium	Work In Progress	8/26/2015 3	:04:42 PN	1			
Gonzalez, 3	Salvador	Need to make and install 4 sets of ladders to different sections of Chaparral Middle School rooftop.					
Johnny Acu	una						
144003		Office 11	1/30/2015		1		\$0.00
Medium	Work In Progress	11/30/2015 9	:29:12 AN	1			
Gonzales,	Camilo	Pick up 25 boxes of textbooks and deliver to IM/PPD. See Gidget Mora for location of boxes. Thank you.					
Theresa R	amirez						
144031		Office 11	1/30/2015		1		\$0.00
Medium	Work In Progress	11/30/2015 2	:47:33 PN	l			
Gonzales,		Deliver 1 box of instructional materials. Attn: Rosa Mariscal. Thank you.					
Theresa R	amirez		10010045				
142473)/28/2015		34		\$0.00
Medium	Work In Progress	10/28/2015	5 11:59:26	5			
Holguin, Al	fredo	need to install second service for fire pump					
Alfredo Ho	Iguin						
136920			8/2/2015		121		\$0.00
Medium	Work In Progress	8/2/2015 12	:32:08 AN	1			
Vallejo, Alb	pert	Yearly - Chaparral MS Fire Ext. Insp. (Yearly) - Refer to PMschedule details.					
Margret Vil	lalobos						
142700		1	1/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress	11/1/2015 12	:54:05 AN	1			
Orozco, Da	niel	Monthly-Chapparal MS Range Hood Cleaning - Refer to PM schedule details.					
Margret Vil	lalobos						
140892			10/4/2015	10/25/2015	58		\$0.00
Medium	Work In Progress	10/4/2015 12	:38:32 AN	1			
Vallejo, Alb		Monthly - Chaparral MS Fire Sprinkler Insp Refer to PMschedule details.					
Margret Vil	lalobos						

WOID Priority Assigned 7 Requester		Area Area Number Description	Deferred By		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	al MS						
142721				11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress			11/1/2015 12:54:19 AM				
Orozco, Da	niel	Monthly - Chap to PMschedule		ression Insp Refer				
Margret Vil								
139646	Main Building	Kitchen		9/9/2015		83		\$0.00
Medium	Work In Progress			9/9/2015 11:47:14 AM				
Estrada, Je	esus		oming up under the after the kitchen flo					
Jesus Est	rada			10/0/0015				
141125		Classroom		10/6/2015		56		\$0.00
Medium	Work In Progress	P-6		10/6/2015 2:12:49 PM				
Acuna, Joh	nny	Ms. Stogden ne	eds dividers screw	ed in so theywont fall				
Gidget Mor	ra							
141130	Main Building	Classroom		10/6/2015		56		\$0.00
Medium	Work In Progress	107		10/6/2015 2:25:27 PM				
Acuna, Joh	nny	Outlet in restro	om needs to be rem	ounted				
Gidget Mor	ra							
143100	Main Building	Cafeteria		11/5/2015		26		\$0.00
Medium	Work In Progress			11/5/2015 8:51:22 AM				
Acuna, Joh	nny	Please hang ba TV	anner in the cafeteri	a to the right of the				
Gidget Mor	ra							
138149	Main Building	Classroom		8/17/2015		106		\$0.00
Medium	Work In Progress	205		8/17/2015 3:11:44 PM				
Acuna, Joh	nny	Door guard for	front and back door	please				
Gidget Mor	ra							
139031		Classroom		8/31/2015		92		\$0.00
Medium	Work In Progress	305		8/31/2015 10:34:06 AM				
Acuna, Joł	nny	Please anchor	smartboard to wall					
Gidget Mor	-							
137492	Main Building	Classroom		8/7/2015		116		\$0.00
Medium	Work In Progress	103		8/7/2015 11:09:44 AM				
Acuna, Joh	-	Lightswitches	are reversed					
, Suna, 501	y	Lights witches						

WOID Priority Assigned	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ac		Days Labor Aged Hours	Costs
Location:	Chaparra	al MS				
136119	Main Building	Classroom	7/20/2015		134	\$0.00
Medium	Work In Progress	p-14	7/20/2015 1:24:35 PM			
Acuna, Joł	nny	please fill holes in wall				
Gidget Mo	ra					
136120	Main Building	Classroom	7/20/2015	,	134	\$0.00
Medium	Work In Progress	101	7/20/2015 1:25:55 PM			
Acuna, Joł	nny	Please mount SMART Board on th	e wall			
Gidget Mo	ra					
136761	Main Building	Gym	7/30/2015		124	\$0.00
Medium	Work In Progress		7/30/2015 3:18:19 PM			
Acuna, Joł	nny	Please reinforce chin up bar in gyr	n			
Gidget Mo	ra					
139414			9/6/2015		86	\$0.00
Medium	Work In Progress		9/6/2015 12:34:05 AM			
Flores, Pe		Monthly - CHM-UV-0514 PM Servi schedule details.	ce - Refer to PM			
Margret Vil						<u> </u>
142483	Main Building	Classroom	10/28/2015		34	\$0.00
Medium	Work In Progress	355	10/28/2015 3:20:44 PM			
Quinones,	, Paul	Please repair holes in wall				
Gidget Mo	ra					
142865		Athletic Field	11/2/2015		29	\$0.00
Medium	Work In Progress		11/2/2015 10:09:27 AM			
	Guadalupe	softball field needs benches for ne post for offical games.	ew dugout and foul line			
	e Ontiveros					
143449	Main Building	Portables	11/12/2015		19	\$0.00
Medium	Work In Progress	p-5	11/12/2015 8:43:17 AM			
Quinones,	, Paul	Nurse would like medicine cabine	et mounted on the wall			
Gidget Mo	ra					
136489		Portables	7/27/2015		0	\$0.00
Medium	Work In Progress		7/27/2015 9:26:41 AM	7/27/2015		
Quinones, M. Carmer		senesecita replace broken tiles a GRACIAS	nd portables # 5 7-2	27-15		

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	al MS					
139807		Hallway/Corridor	9/11/2015		81		\$0.00
Medium	Work In Progress		9/11/2015 12:42:35 PM				
Quinones	, Paul	senesecita remplasar focos que GRACIAS	no prenden en el lobby				
M. Carmer	n Perez						
139808		Hallway/Corridor	9/11/2015		81		\$0.00
Medium	Work In Progress		9/11/2015 12:47:37 PM				
Quinones	, Paul	senesecita poner lampara que no switch del hallway del lobby GRA					
M. Carmer							
143770	Main Building	Classroom	11/18/2015		13		\$0.00
Medium	Work In Progress	P-4	11/18/2015 10:18:26				
Acuna, Jol	nny	Wooden bench next to south footb needing to be painted due to taggi for tagging removal but was unsue black paint	ing. Attempt was made				
Gidget Mo	ra						
143622		Restroom (Girls)	11/16/2015		15		\$0.00
Medium	Work In Progress		11/16/2015 10:06:40				
Chavez, Sa	antos	senesecita remplasar hand airblo de las girls del lobby GRACIAS	ower dryer del bathroom				
M. Carmer	n Perez						
143621		Restroom	11/16/2015		15		\$0.00
Medium	Work In Progress		11/16/2015 10:00:59				
Chavez, Sa	antos	senesecita remplasar hand air bl delos boys del lobby GRACIAS	owerdryer en bathroom				
M. Carmer			/ /				
143652	Main Building	Office	11/16/2015		15		\$0.00
Medium	Work In Progress		11/16/2015 3:36:58 PM				
Chavez, Sa	antos	Please install electrical outlet nea office	r mounted tvin the				
Gidget Mo	ra						A
143210			11/6/2015		25		\$0.00
Medium	Work In Progress		11/6/2015 12:33:32 PM				
Solis, Lore		Need to install Temperature Ther boiler heating unit in the mechanic					
Johnny Ac	una						

WOID Priority Assigned Requester		Area Area Number Description	Deferred By	Until Requ		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	I MS							
143669	Main Building	Classroom		11	/16/2015		15		\$0.00
Medium	Work In Progress	404		11/16/2015 3:	49:48 PM				
Chavez, S	antos	Please install e Projector for po		eiling in order to plug i	in				
Gidget Mo	ora								
143711	Main Building	Classroom		11	/17/2015		14		\$0.00
Medium	Work In Progress	202		11/17/20152:	57:55 PM				
Chavez, S	antos		rical outlet in room ected to surge prot	ASAP. Sparks coming	g				
Gidget Mo	ora								
142660				10)/31/2015		31		\$0.00
Medium	Work In Progress			10/31/2015	512:34:35				
Acuna, Jol	hnny	Yearly - Chapa schedule detail		Frap - Refer to PM					
Margret Vi	llalobos								
140059		Restroom (Girk	5)	ç	9/16/2015		76		\$0.00
Medium	Work In Progress			9/16/2015 10:	:41:43 AM				
Appelzolle	er, Fred	esta tirando ag		s yatiene tiempo que s la segunda ho terser IAS	a				
M. Carme	n Perez								
139553		Restroom (Girk	6)		9/8/2015		84		\$0.00
Medium	Work In Progress			9/8/2015 9:	:44:08 AM				
Appelzolle	er, Fred	senesecita arg para de tirar ag		los locker de las girls r	о				
M. Carme	n Perez								
136253		Restroom (Girk	6)		7/22/2015		132		\$0.00
Medium	Work In Progress			7/22/2015 8:	:37:10 AM				
Appelzolle	er, Fred	girls locker roor GRACIAS	n hand washhhin	gsinkesleaking					
M. Carme	n Perez								
Count: 37	Work Orders	Α	vg. Age of WO's	56		Total for Chaparra	al MS	0	\$0.00

WOID Priority Assigned 1 Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loca Deferred By Reason	Until F		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert P	ride HS							
142464		Office			10/28/2015		34		\$0.00
Medium	Work In Progress			10/28/20	15 9:42:40 AN	1			
Ontiveros,	Joe	There's No hot	water in the Administ	tration bldg.					
David Acos	sta								
143998					11/30/2015		1		\$0.00
Medium	Work In Progress			11/30/20	15 8:41:00 AN	1			
Ontiveros,	Joe	Email: blanca Location of Wo 10, R ON O'HA 1.5MI, L (W) ON APPR 0.5MI TC ELEMENTARY LOCATED ON HAZARDS, OP	act: BLANCA CRUZ caliperconstcom rk: FROM LAS CRUC RA RD, R ON ANTHO N SHRODE RD GO N SIDE OF ROAD A SPOT WITHIN WHIT THE N SIDE OF THE	Contact Ph EES GO SE Of DNY DR GO A T DESERT PF E MARKS SCHOOL, NO	I I- PPR RIDE				
Dominique	Esparza	Remains. REL	OCATE.EQUIPMENT	DOWN					
143915					11/20/2015		11		\$0.00
Medium	Work In Progress			11/20/20	15 9:36:25 AM	1			
Ontiveros,	Joe	Company: Contact Name: (575)382-8474 Email: cdmech	CD MECHANICAL DEAN POGUE anical@comcastnet	Contact Pr	one:				
		VADO EXIT WE TRN L ON SHF L :: SPOT ARE/	rk: FRM LAS CRUCE ST ON VADO DR TR RODE RD TO THE AD A MARKED IN WHT B THE NEW GYM APP	N L/S ON NM DRESS ON T ETWEEN THI	478 HE				
Dominique	e Esparza	Remarks: OPE	N ACCESS / NO HAZ	ZARDS					

Location: Desert Pride HS 143778 11/18/2015 13 Medium Work In Progress 11/18/2015 12:52:50 Ontiveros, Joe Company: CARVER ELECTRIC Contact Name: BOBBY CARVER Contact Phone: (575)527-2127 Alternate Contact: DANEIL CARVER Alternate Phone: (575)649-9142 Best Time to Call: Fax No: (575) S27-2128 Cell Phone: (575)644-4313 Pager No: Email: carver@carverelectric.com Location of Work: LOCATE PER THE WORK PLAN Dominique Esparza 11/19/2015 7:53:19 AM 12 Medium Work In Progress 11/19/2015 7:53:19 AM 12 Ontiveros, Joe Please line locate area for CD Mechanical (see email) from Albert. Albert Vallejo	
Medium Work In Progress 11/18/2015 12:52:50 Ontiveros, Joe Company: CARVER ELECTRIC Contact Name: BOBBY CARVER Contact Phone: (575)527-2127 Atternate Dome: (575)649-9142 Best Time to Call: Fax No: (575) Atternate Phone: (575)649-9142 Best Time to Call: Fax No: (575) S27-2128 Cell Phone: (575)644-4313 Pager No: Email: carver@ carver@ectric.com Location of Work: LOCATE PER THE WORK PLAN Dominique Esparza 11/19/2015 12 143833 11/19/2015 12 12 Medium Work In Progress 11/19/2015 7:53:19 AM Ontiveros, Joe Please line locate area for CD Mechanical (see email) from Albert. Heat Halbert Albert Vallejo Location of CD Mechanical (see email) Location Albert.	
Ontiveros, JoeCompany: Contact Name: BOBBY CARVER Contact Name: BOBBY CARVER BOBBY CARVER Atternate 	\$0.00
Contact Name:BOBBY CARVERContact Phone:(575)527-2127Alternate Contact: DANEIL CARVERAlternatePhone:(575)649-9142Best Time to Call:Fax No:Best Time to Call:Fax No:(575)527-2128Cell Phone:(575)644-4313Cell Phone:(575)644-4313Pager No:Email: carver@carverelectric.comLocation of Work: LOCATE PER THE WORK PLANDominique Esparza11/19/20151214383311/19/201512MediumWork In Progress11/19/20157:53:19 AMOntiveros, JoePlease line locate area for CD Mechanical (see email) from Albert.Ferminication of CD Mechanical (see email)Albert VallejoContact AlbertContact Albert	
Dominique Esparza 143833 11/19/2015 Medium Work In Progress 11/19/2015 Ontiveros, Joe Please line locate area for CD Mechanical (see email) from Albert. Albert Vallejo Vertice	
Dominique Esparza 143833 11/19/2015 Medium Work In Progress Ontiveros, Joe Please line locate area for CD Mechanical (see email) from Albert. Albert Vallejo Vertice	
Medium Work In Progress 11/19/2015 7:53:19 AM Ontiveros, Joe Please line locate area for CD Mechanical (see email) from Albert. Albert Vallejo 11/19/2015 7:53:19 AM	
Ontiveros, Joe Please line locate area for CD Mechanical (see email) from Albert. Albert Vallejo	\$0.00
from Albert. Albert Vallejo	
40/07/0045	
142402 10/27/2015 35	\$0.00
Medium Work In Progress Main building 10/27/2015 3:02:24 PM	
Ontiveros, Joe Need to check for hot water.	
Maria Carbajal	
142970 11/3/2015 28	\$0.00
Medium Work In Progress 11/3/2015 3:16:52 PM	
Ontiveros, Joe Need to check mechanic room water leak on gym thank you	
Sebastian Diaz	
143546 11/13/2015 18	\$0.00
Medium Work In Progress 11/13/2015 11:54:59	
Ontiveros, Joe Company: CARVER ELECTRIC Contact Name: BOBBY CARVER Contact Phone: (575)527-2127 Alternate Contact: DANEIL CARVER Alternate Phone: (575)649-9142 Fax No: (575)527-2128 Cell Phone: (575)644-4313 Email: carver@carverelectric.com	
Location of Work: 11/18/15 9:00AM AT THE JOB LOCATION Remarks: NO HAZARDS - OPEN ACCESS	
Dominique Esparza	

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Locat Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert P	ride HS					
143549			11/13/2015		18		\$0.00
Medium	Work In Progress		11/13/2015 12:05:49	I			
Ontiveros,	Joe	Company: CARVER ELECTRIC Contact Name: BOBBY CARVER (575)527-2127 Alternate Contact: DANEIL CARVER Phone: (575)649-9142 Fax No: (575)527-2128 Cell Phone: (575)644-4313	; Contact Phone: Alternate				
		Email: carver@carverelectric.com Location of Work: FROM HWY 478 S SHRODE RD FOR 0.5MI TURN INTC CONSTRUCTION SITE AND ADDITIC PRIDE ACADEMY- SPOT AREA WITH IN CO SITE ON THE NW SIDE OF SCHOOL) DN DESERT				
		Remarks: NO HAZARDS - OPEN AC	CESS				
Dominique	e Esparza						
143835			11/19/2015		12		\$0.00
Medium	Work In Progress		11/19/2015 7:54:45 AN	1			
Chavez, Sa		Please line locate area for CD Mechar from Albert.	nical (see email)				
Albert Valle	ejo		11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 8:40:38 AM	1	I		ψ0.00
Chavez, Sa	Ū	Company: CALIPER CONSTRU Contact Name: FERNIE REYES (575)635-8919 Alternate Contact: BLANCA CRUZ Email: blanca@caliperconstcom					
		Location of Work: FROM LAS CRUCE 10, R ON O'HARA RD, R ON ANTHOI 1.5MI, L (W) ON SHRODE RD GO APPR 0.5MI TO N SIDE OF ROAD AT ELEMENTARY: SPOT WITHIN WHITE LOCATED ON THE N SIDE OF THE S HAZARDS, OPEN ACCESS	NY DR GO APPR DESERT PRIDE MARKS				
		Remarks: RELOCATE:EQUIPMENT I	DOWN				
.	e Esparza						

WOID Priority Assigned T Requester	Building Status o	Dates: 7/1/2015 - 6 Area Area Number Description	/30/2016 Order By Loca Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert P	ride HS						
143914				11/20/2015		11		\$0.00
Medium	Work In Progress			11/20/2015 9:35:58 AN	1			
Chavez, Sa	intos	Company: Contact Name: (575)382-8474 Email: cdmech		Contact Phone:				
		VADO EXIT WE TRN L ON SHF L :: SPOT ARE/	rk: FRM LAS CRUCE ST ON VADO DR TR RODE RD TO THE AL A MARKED IN WHT B THE NEW GYM APP	N L/S ON NM478 DRESS ON THE ETWEEN THE				
		Remarks: OPE	N ACCESS / NO HAZ	ZARDS				
Dominique	Esparza			11/10/0015		10		.
143777				11/18/2015		13		\$0.00
Medium	Work In Progress			11/18/2015 12:52:34				
Chavez, Sa	intos	Phone: (575)64 Best Time to C 527-2128 Cell Phone:	act: DANEIL CARVER 19-9142	Contact Phone:				
			rk: LOCATE PER THI	E WORK PLAN				
Dominique	Esparza							
140490	-			9/23/2015		69		\$0.00
Medium	Work In Progress			9/23/2015 3:04:41 PM	1			
Ontiveros,	Joe	Outside Water	Fountain keeps runni	ng				
Marin Herre	era							
138187		Portables		8/18/2015		105		\$0.00
Medium	Work In Progress	room #19		8/18/2015 5:32:16 AN	1			
Solis, Lore	nzo	a/c not cooling	need to be serviced as	sap.				
David Acos		·						
137898		Portables		8/13/2015		110		\$0.00
Medium	Work In Progress	room #19		8/13/2015 5:24:27 AN	1			
Ambriz, Jos	-	a/cunitnotcool	ling (asap)					
David Acos			3 (

WOID Priority Assigned T Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert P	ride HS					
137900		Portables	8/13/2015		110		\$0.00
Medium	Work In Progress	room #18	8/13/2015 5:26:58 AM				
Ambriz, Jos	se	a/c unit not cooling (asap).					
David Acos	sta						
143359		Office	11/10/2015		21		\$0.00
Medium	Work In Progress	boys restroom in	11/10/2015 5:29:00 AM				
Marquez, G	Gerardo	Having trouble unlocking door.					
David Acos	sta						
144074		Office	12/1/2015		0		\$0.00
Medium	Work In Progress	middleschool	12/1/2015 5:32:17 AM				
Marquez, G	Gerardo	need to check door handle for prop	er locking.				
David Acos	sta						
143996		Office	11/30/2015		1		\$0.00
Medium	Work In Progress	patio	11/30/2015 8:37:10 AM				
Marquez, G		The lock on the gate can be pulled lock position.	open while on the				
David Acos	sta	Portables	11/10/2015		21		\$0.00
143360 Medium			11/10/2015 5:33:29 AM		21		φ0.00
	Work In Progress	room #20					
Marquez, G		Having trouble with cylinder unlock	ing and locking.				
David Acos	sta	Portables	11/5/2015		26		\$0.00
143101					20		φ0.00
Medium	Work In Progress	room 5	11/5/2015 9:04:12 AM				
Chavez, Sa		Night light does not turn on.					
David Acos	sta	Portables	11/5/2015		26		\$0.00
143102					20		Φ 0.00
Medium	Work In Progress	room #18	11/5/2015 9:05:38 AM				
Chavez, Sa		Night light does not turn on.					
David Acos	sta	Destables	0/00/0045		05		<u> </u>
138929		Portables	8/28/2015		95		\$0.00
Medium	Work In Progress	portables	8/28/2015 10:22:55 AM				
Chavez, Sa Maria Carb		Electrician needed to wire for dual several portables. (portables 1,4,7 19.)					

WOID	ate Range for Request I Building	Dates:7/1/2015 - 6 Area Area Number	Deferred By	Until Re	•	Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Priority Assigned	Status To	Description	Reason	Greated	Date/ Time	Action Taken			
Requester		Decemption							
Location:	Desert Pi	ide HS							
139620		Portables			9/9/2015		83		\$0.00
Medium	Work In Progress	room #18		9/9/201	5 5:20:08 AN	I			
Chavez, S	antos	Two light fixture the other does	es that need to be c not turn on.	heck. one flicking	and				
David Aco	sta								
142399		Office			10/27/2015		35		\$0.00
Medium	Work In Progress			10/27/201	5 1:39:56 PM				
Chavez, S	antos		are staying on and r front side and both s		ation				
David Aco	sta								
144085		Office			12/1/2015		0		\$0.00
Medium	Work In Progress	in front of main		12/1/2015	10:03:57 AN	l			
Diaz, Seba	astian	One palm tree	looks like it,s startir	ng to dry out.					
David Aco	sta								
140807					10/4/2015	10/25/2015	58		\$0.00
Medium	Work In Progress			10/4/2015	12:37:33 AN	l			
Vallejo, Al	bert	Monthly - Dese schedule detail	rt Pride Fire Sprinkl s.	ler Insp Refer to	PM				
Margret Vi	llalobos								
Count: 28	Work Orders	A	vg. Age of WO's 3	35		otal for Desert Prid	e HS	0	\$0.00

WOID Priority Assigned T Requester	Building Status o	Dates:7/1/2015 - 6/30/2016 Order By Location, S Area Deferred By Unt Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert T	ail ES					
140893			10/4/2015	10/25/2015	58		\$0.00
Medium	Work In Progress	1	0/4/2015 12:38:33 AM	I			
Vallejo, Alb	ert	Monthly - Desert Trail ES - Fire Sprinkler I PMschedule details.	nsp Refer to				
Margret Vill	alobos						
142722			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress	1	1/1/2015 12:54:20 AN	l			
Orozco, Da	niel	Monthly - Desert Trail ES - Fire Suppress Refer to PMschedule details.	ion Insp				
Margret Vill	alobos						
135927			7/15/2015		139		\$0.00
Medium	Work In Progress	7	/15/2015 11:48:40 AN	I			
Estrada, Je		Need to replace VCT tile in the bus lobby in front of main doors. Also, need to fill in holes on this section where the tile will be Size of Area: 7' L X 11' W	and level out				
Laura Sano	doval		- /2 / /2 2 / 2				
136190		Custodial	7/21/2015		133		\$0.00
Medium	Work In Progress	7	/21/2015 11:06:40 AN	l			
Estrada, Je	esus	Buenos dias Chuy, el piso de los Banos d necesita remplasar. Num de clases 201, 205, 206, 207, 208, y el bano de la cocin necesita remplasar gracias	202, 203, 204,				
Laura Sano	doval						
138489		Custodial	8/21/2015		102		\$0.00
Medium	Work In Progress		8/21/2015 9:37:38 AN	l			
Estrada, Je	esus	Buenos dias .Chuyse necesita remplazar la libreria gracias	la alfombra de				
Laura Sano	doval						
142701			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress	1	1/1/2015 12:54:06 AM	l			
Orozco, Da	niel	Monthly - Desert Trail ES - Range Hood C Refer to PMschedule details.	Cleaning -				
Margret Vill	alobos						
139805			9/11/2015		81		\$0.00
Medium	Work In Progress	g	/11/2015 12:01:57 PM				
Carrasco, I	Danny	Need unleaded fuel for worktruck #192					
Johnny Acu	ina						

WOID	Building	Area	/30/2016 Order By Loca Deferred By	Until	-	Target Comp Date	Days Aged	Labor Hours	Costs
Priority	Status	Area Number	Reason	Cre	ated Date/Time	Actual Comp Date	Ayeu	nour 5	
Assigned Requeste		Description				Action Taken			
Location:	Desert Ti	ail FS							
	Desert II				44/4/2045		07		<u> </u>
143078					11/4/2015		27		\$0.00
Medium	Work In Progress				2015 3:55:48 PN	//			
Orozco, D	aniel	FAUCET TO SA MANAGER PAT	ALAD SINK IS LEAKIN F C.8243822	NG. SNP					
Maritza Go	onzalez								
136907					8/2/2015		121		\$0.00
Medium	Work In Progress			8/2/2	015 12:32:00 AM	1			
Vallejo, Al	bert	Yearly - Desert to PMschedule	Trail ES Fire Ext. Ins details.	p. (Yearly) -	Refer				
Margret Vi	illalobos								
142559					10/29/2015		33		\$0.00
Medium	Work In Progress			10/29/	2015 1:56:57 PM	1			
Acuna, Jo	hnny	Need Heating	season filters for Des	ert Trail					
Johnny Ad	cuna								
143211					11/6/2015		25		\$0.00
Medium	Work In Progress			11/6/2	015 12:34:36 PM	1			
Acuna, Jo	hnny	Need a replace	ementair-compressor						
Johnny Ac	cuna								
138576					8/24/2015		99		\$0.00
Medium	Work In Progress			8/24/2	015 11:02:21 AM	1			
Acuna, Jo	hnny	Need 2 4500 m and 419	aster cool media pac	ls for portab	le#418				
Johnny Ac	cuna								
138686					8/25/2015		98		\$0.00
Medium	Work In Progress			8/25/	2015 2:08:42 PN	1			
Acuna, Jo	hnny		0 Pvc line and 1" Pvc vater line install in fror						
Johnny Ac	cuna								
139381	Main Building	Classroom			9/4/2015		88		\$0.00
Medium	Work In Progress	405		9/4/	2015 2:34:29 PN	1			
Acuna, Jo	hnny	Ms.Garcia in po won't fall.	ortable #405 needs b	ookshelfbc	Ited so it				
Elizabeth	Hernandez								

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2015 - 6/30/2016 Order By Location Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert T	rail ES					
144095			12/1/2015		0		\$0.00
Medium	Work In Progress		12/1/2015 12:31:14 PM				
Herrera, Ja	aime	Need 1 load of top soil. Also, please re (removed) cement slabs from school Trail.					
Johnny Acu	una						
139225			9/2/2015		90		\$0.00
Medium	Work In Progress		9/2/2015 3:22:30 PM	1			
Acuna, Joh	nny	Water Seal new portable ramps with w	ood boards.				
Johnny Acu	una						
135165			7/1/2015		153		\$0.00
Medium	Work In Progress		7/1/2015 7:43:14 AN	1			
Solis, Lore	nzo	Need Refrigeration unit for new compu RM. 304	iter class room.				
Johnny Acu	una						
143704		Custodial	11/17/2015		14		\$0.00
Medium	Work In Progress		11/17/2015 11:43:50	1			
Marquez, G	Gerardo	Buenos Dias .Gerardo la puerta del po cerrando bien el candado se atora ,po revisarlo gracias					
Laura San	doval						
143376		Custodial	11/10/2015		21		\$0.00
Medium	Work In Progress		11/10/2015 10:07:44				
Marquez, G	Gerardo	Buenos dias .Gerardo puede canbiarr del east side gate estan viejos y dificile poner unos nuevos se lo agradeceria	es de abrir, puede				
Laura San	doval						
142104			10/21/2015		41		\$0.00
Medium	Work In Progress		10/21/2015 3:44:50 PN				
Chavez, Sa	antos	Need assistance with light fixture in en in front of the teacher's lounge. Fixture noise.					
Johnny Acu	una						
143757			11/18/2015		13		\$0.00
Medium	Work In Progress		11/18/2015 7:38:17 AM	1			
Chavez, Sa	antos ozco	Need outlet electrical box repaired					

12/1/2015 4:03:41 PM

Count: 22	Work Orders	A	vg. Age of WO's 65	5		Total for Desert Tra	ail ES	0	\$0.00
Margret Vi	llalobos								
Acuna, Jol	hnny	Yearly - Desert schedule detaik	Trail ES - Grease Tr s.	ap - Refer to	PM				
Medium	Work In Progress			11/1/20	15 12:53:58 AN	Л			
142689					11/1/2015		30		\$0.00
Location:	Desert Ti	ail ES							
Requester	^r Name								
Assigned	То	Description				Action Taken			
Priority	Status	Area Number	Reason	Crea	ted Date/Time	Actual Comp Date		Hours	
Selected Da WOID	te Range for Request Building	Dates:7/1/2015 - 6/ Area	/30/2016 Order By Loca Deferred By	ation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
002 -			1091655 (1	iscai	i eai j				Total

Selected Da WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date	Target Comp Date Day Actual Comp Date Age Action Taken	•	Total Costs
Location:	Desert V	iew ES				
142682			11/1/2015	5 30)	\$0.00
Medium	Work In Progress		11/1/2015 12:53:53 A	M		
Ortiz, Rub	en	Yearly - Desert View ES - Grease schedule details.	Trap - Refer to PM			
Margret Vi	llalobos					
143293		Classroom	11/9/2015	5 22	2	\$0.00
Medium	Work In Progress	Rm.#210	11/9/2015 8:28:54 A	N		
Castillo, C		Install an outlet in the classroom to (Amaya)	o connect Duel Board.			
· · · ·	e Gonzalez		1.1/0.0/0.01			* • • • •
143930	Main Building		11/20/2015			\$0.00
Medium	Work In Progress		11/20/2015 2:22:05 PM	Λ		
Castillo, C	Carlos	Install dedicated circuits for new co	omputer lab set-up.			
Carlos Ca	astillo					
143183			11/6/2015	5 25	5	\$0.00
Medium	Work In Progress		11/6/2015 9:06:26 A	Л		
Castillo, C	Carlos	The nurse is asking for outlet prote	ector's room 205			
Ruben Or	tiz					
143184			11/6/2015	5 25	5	\$0.00
Medium	Work In Progress		11/6/2015 9:07:23 A	Ν		
Castillo, C	Carlos	The principal is asking for outlet pr hallways	rotector's through the			
Ruben Or	tiz		10/00/0045			.
142525			10/28/2015		ł	\$0.00
Medium	Work In Progress		10/28/2015 4:14:04 PM	Λ		
Castillo, C	Carlos	provide additional lighting to south	n side of mobile home	10/30/15 Asp Albert, rout	e to Cali	
Alfredo Ho	olguin					
142405			10/27/2015		5	\$0.00
Medium	Work In Progress		10/27/2015 3:33:29 PM	Λ		
Castillo, C	Carlos	As per A.Vallejo,check area for ligh at mobil home area.	nt poles to be installed			
Carlos Ca	astillo					.
143709			11/17/2015		ł	\$0.00
Medium	Work In Progress		11/17/2015 2:36:41 PM	Л		
	, Guadalupe	Principal Araujo, is requesting for spaint the basketball lines on the basketb				
Ruben Or	uΖ					
12/1/2015	5 4·03·41 PM				D	12 of 127

12/1/2015 4:03:41 PM

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert V	iew ES						
144093		Classroom		12/1/2015		0		\$0.00
Medium	Work In Progress	Rm.#116		12/1/2015 11:46:50 AM				
Lara, Ralp	h	Install a differer (Gonzalez)	nt lock for the class r	room. (See Lupe G.)				
Guadalup	e Gonzalez							
144089				12/1/2015		0		\$0.00
Medium	Work In Progress	Rm.#115 (Data	а	12/1/2015 10:56:08 AM				
Lara, Ralp	h	Need a key for	the Data Room. (G	ionzalez)				
Guadalup	e Gonzalez							
144008				11/30/2015		1		\$0.00
Medium	Work In Progress			11/30/2015 10:53:55				
Lara, Ralp	h	Room 115 nee	ds cylinder replaced	ł				
Ruben Ort	tiz							
143278				11/8/2015	11/24/2015	23		\$0.00
Medium	Work In Progress			11/8/2015 12:30:05 AM				
Ortiz, Rube	en	Monthly - Dese PMschedule de	rt View ES Playgrou etails.	und Insp - Refer to				
Margret Vi	llalobos							
136908				8/2/2015		121		\$0.00
Medium	Work In Progress			8/2/2015 12:32:01 AM				
Vallejo, All	bert	Yearly - Desert to PMschedule		nsp. (Yearly) - Refer				
Margret Vi	llalobos			/ . /	/= /=			
142744				11/1/2015	11/7/2015	30		\$0.00
Medium	Work In Progress			11/1/2015 12:54:35 AM				
Ortiz, Rube	en	Monthly - Dese to PMschedule		FE Inpsection - Refer				
Margret Vi	llalobos							
143705		Custodial		11/17/2015		14		\$0.00
Medium	Work In Progress			11/17/2015 1:40:31 PM				
Carbajal,	-			enter lock clamp pad #1238102. Thank you				
Israel Orte	ega							

002 -			iogress (riscai	i ear j				Tota
Selected Da WOID Priority Assigned Requester		Dates:7/1/2015 - 6 Area Area Number Description	Deferred By	Until	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Vi	iew ES							
143706		Custodial			11/17/2015		14		\$0.00
Medium	Work In Progress			11/17/2	2015 1:42:36 PM	1			
Carbajal,	Jimmy	clamp pad reta	re going to need ano iner for a Nobles bur 1048. Thank you		ck				
Israel Orte	ega								
142702					11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress			11/1/20	015 12:54:07 AN	1			
Orozco, Da	aniel	Monthly - Dese to PMschedule	ert View ES Range H e details.	ood Cleanin	g - Refer				
Margret Vi	llalobos								
142723					11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress			11/1/20	015 12:54:21 AN	1			
Orozco, Da	aniel	Monthly - Dese to PMschedule	ert View ES Fire Supp e details.	pression Ins	p Refer				
Margret Vi	llalobos								
Count: 18	Work Orders	4	Avg. Age of WO's 2	6		Total for Desert Vie	w ES	0	\$0.00

Assigned To Requester N		Area Deferred By Until Request Date T Area Number Reason Created Date/Time A Description		Days Aged	Labor Hours	
Location:	GAC					
142724		11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress	11/1/2015 12:54:21 AM				
Orozco, Dan	iel	Monthly - GAC Fire Suppression Insp Refer to PM schedule details.				
Margret Villa	alobos					
140894		10/4/2015	10/25/2015	58		\$0.00
Medium	Work In Progress	10/4/2015 12:38:33 AM				
Vallejo, Albe	ert	Monthly - GAC Fire Sprinkler Insp Refer to PM schedule details.				
Margret Villa	alobos					
142715		11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress	11/1/2015 12:54:15 AM				
Orozco, Dan	niel	Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.				
Margret Villa	alobos					
140875		10/4/2015		58		\$0.00
Medium	Work In Progress	10/4/2015 12:38:21 AM				
Vallejo, Albe	ert	Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PMschedule details.				
Margret Villa	alobos					
135297		7/5/2015		149		\$0.00
Medium	Work In Progress	7/5/2015 12:30:38 AM				
Vallejo, Albe		Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PMschedule details.				
Margret Villa	alobos	40/4/0045				* •••••
144102		12/1/2015		0		\$0.00
Medium	Work In Progress	12/1/2015 1:04:07 PM				
Lara, Ralph		The door stopper in Mr. Suggs office needs to be repaired. It is the door leading to my office(Anne de los Santos). Thanks				
Esteban Ro	sas					
142287		10/26/2015		36		\$0.00
Medium	Work In Progress	10/26/2015 8:35:06 AM				
Carbajal, Jir	nmy	need to replace batteries (2) in the scrubber machine serial #1721044				
	guez					

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2015 - 6/30/2016 Order By Locati Area Deferred By Area Number Rea <i>s</i> on Description		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	GAC						
136925			8/2/2015		121		\$0.00
Medium	Work In Progress		8/2/2015 12:32:11 AM				
Vallejo, Alb	pert	Yearly - GAC Fire Ext. Insp. (Yearly) - F schedule details.	Refer to PM				
Margret Vil	lalobos						
143271			11/8/2015	11/24/2015	23		\$0.00
Medium	Work In Progress		11/8/2015 12:30:00 AM				
Moncayo, F	Fernando	Monthly - GAC Playground Insp - Refe	er to PM schedule				
Margret Vil	lalobos						
144021			11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 1:36:48 PM				
Moncayo, F	Fernando	NEW TEA MACHINE NEEDS TO BE II MANAGER IRMA V. 882.6784	NSTALLED. SNP				
Maritza Go	nzalez						
144022			11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 1:37:33 PM				
Moncayo, F	Fernando	REACH IN- SERVING LINE IS NOT C MANAGER IRMA V. 882.6784	OOLING. SNP				
Maritza Go	nzalez						
143185			11/6/2015		25		\$0.00
Medium	Work In Progress	FEDERAL	11/6/2015 9:47:31 AM				
Moncayo, F	Fernando	HEATER VENT IS DIRECTLY DOWN. CHANGED TO DISTRIBUTE HEAT TO					
Noemi Du	ron						
142546			10/29/2015		33		\$0.00
Medium	Work In Progress		10/29/2015 11:26:28				
Moncayo, F	Fernando	AS PER LUCY GARCIA - One of Perso Cabinet in Vanessa Garcia's office (we employee personnel files) is stuck. It to open the filing cabinet. Please help access to those files as soon as poss	hich stores does not allow us us, we need				
Maritza Go	nzalez						
142383			10/27/2015		35		\$0.00
Medium	Work In Progress	FEDERAL	10/27/2015 10:03:01				
Moncayo, F	Fernando	SHUT DOWN AIR CONDITIONER IN PROGRAMS OFFICE.	FEDERAL				

Selected Dat WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2015 - 6/30/2016 Order By Loca Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	GAC						
143510			11/12/2015		19		\$0.00
Medium	Work In Progress	Federal	11/12/2015 3:51:37 PN	I			
Moncayo, F	Fernando	Move furniture in office for District P Consultant/Specialist	re-k				
Noemi Du	ron						
142753			11/1/2015	11/9/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:40 AM	1			
Moncayo, F	Fernando	Monthly - GAC Emer. Light Test: Mo schedule details.	nthly - Refer to PM				
Margret Vil	lalobos						
142754			11/1/2015	11/9/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:41 AM	1			
Moncayo, F		Monthly - GAC Exit Sign Insp: Month schedule details.	ly - Refer to PM				
Margret Vil	lalobos		44/47/0045		4.4		<u> </u>
143696			11/17/2015	_	14		\$0.00
Medium	Work In Progress	FEDERAL	11/17/2015 9:31:30 AN	1			
Moncayo, F	Fernando	HANG PICTURE FRAME IN OFFICE					
Noemi Du	ron						
143559			11/13/2015		18		\$0.00
Medium	Work In Progress		11/13/2015 3:17:06 PN	l			
Ontiveros,	Guadalupe	I need a drag matplease					
Fernando I	Moncayo						
140411			9/22/2015		70		\$0.00
Medium	Work In Progress		9/22/2015 3:15:51 PM	1			
Vallejo, Alb	pert	pool area pump house/storage need leaking and mold is growing in dryw					
Fernando I	Moncayo						
135227			7/2/2015		152		\$0.00
Medium	Work In Progress		7/2/2015 2:31:29 PM	1			
Moncayo, F	Fernando	SNP Vehicle # 177 needs to be clear organized.	ned out and				
Maritza Go	nzalez						
140371			9/22/2015		70		\$0.00
Medium	Work In Progress		9/22/2015 9:38:12 AM	1			
Flores, Pet	e	vehicle 111 (Rocio Herrera) doesn't	start				
Maria Ruiz							

12/1/2015 4:03:41 PM

WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Area Deferred By Un Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	GAC						
142171			10/22/2015		40		\$0.00
Medium	Work In Progress		10/22/2015 3:34:48 PM				
Ambriz, Jo	ose	Please repair damage to A/C units from h	ailstorm.				
Albert Val	lejo						
139283			9/3/2015		89		\$0.00
Medium	Work In Progress		9/3/2015 10:21:09 AM				
Ambriz, Jo	ose	Server room at GAC is warm					
		please check ASAP					
Cora Ran	nirez						
141701			10/14/2015		48		\$0.00
Medium	Work In Progress		10/14/2015 3:17:10 PM				
Ambriz, Jo	ose	backup units to server room very noisy a	nd old				
Fernando	Moncayo						
141292			10/8/2015		54		\$0.00
Medium	Work In Progress		10/8/2015 2:04:18 PM				
Ambriz, Jo	ose	ductless in Richard Acosta's office needs cover and condenser grille cover	a line set				
Fernando	Moncayo						
142680			11/1/2015		30		\$0.00
Medium	Work In Progress		11/1/2015 12:53:52 AM				
Moncayo,	Fernando	Yearly - GAC - Grease Trap - Refer to PM details.	<i>I</i> schedule				
Margret V							
Count: 27	Work Orders	Avg. Age of WO's 47		Total for	GAC	0	\$0.00

WOID	te Range for Request Building	Area	Deferred By	Until Request Date 1	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time	=	Aged	Hours	
Assigned 1		Description			Action Taken			
Requester	Name							
Location:	GAC - Pre	e-K						
136470		Classroom		7/24/2015		130		\$0.00
Medium	Work In Progress	all		7/24/2015 4:49:52 PM				
Rodriguez	, Arturo	shampooedbe	classrooms need to fore kids start scho ecific carpets that ne	ol. Please see				
Leticia Tar	ngonan							
136187		Cafeteria		7/21/2015		133		\$0.00
Medium	Work In Progress	lounge		7/21/2015 9:47:47 AM				
Rodriguez	, Arturo	please clean fl	oors in our lounge-(r	mop)				
Leticia Tar	ngonan							
142955		Office		11/3/2015		28		\$0.00
Medium	Work In Progress			11/3/2015 11:00:01 AM				
Moncayo, F	Fernando	please replace	our blinds in our off	ice and lobby area.				
Leticia Tar	ngonan							
142524		Office		10/28/2015		34		\$0.00
Medium	Work In Progress			10/28/2015 4:13:40 PM				
Moncayo, F	Fernando		o request 2 door stop or and the work roo	opers to be installed m door.				
Leticia Tar	ngonan							
140226		Kitchen		9/18/2015		74		\$0.00
Medium	Work In Progress			9/18/2015 1:46:43 PM				
Miranda, D	Danny	GAC Pre-K kitc and dining roor		separate the kitchen				
Albert Valle	ejo							
139652				9/9/2015		83		\$0.00
Medium	Work In Progress			9/9/2015 12:40:15 PM				
Moncayo, F	Fernando	NO ELECTRIC	ITY IN PRE-K.					
Maritza Go	nzalez							
Count: 6 W	ork Orders	4	vg. Age of WO's 8	30	Total for GAC - F	Pre-K	0	\$0.00

Location:	Name	Description	eason	Created Date/Time	Actual Comp Date Action Taken	Aged	Hours	
	Gadsden	ES						
143981				11/30/2015		1		\$0.00
Medium	Work In Progress			11/30/2015 12:51:54				
Apodaca, N	Vlario	Monthly - Gadsde Refer to PMscheo		eter Readings -				
Margret Vill	lalobos							
136579				7/28/2015		126		\$0.00
Medium	Work In Progress	Playground		7/28/2015 10:29:22 AM				
Ontiveros,	Guadalupe	please provide us	with four trees in	front of the school				
		Arborvitae Blue C Size: 20' tall x 12 ' space 6-10 feet a	wide Exposure F	Full sun part shade,				
Loraine Ga	andara							
139709				9/10/2015		82		\$0.00
Medium	Work In Progress			9/10/2015 7:25:13 AM				
Ontiveros, (Guadalupe	Please remove tre Texas Ash. Please remove th the trees have gor	e dead ones ASA	P, and replant once				
Albert Valle	ejo							
136580				7/28/2015		126		\$0.00
Medium	Work In Progress			7/28/2015 10:30:21 AM				
Herrera, Ja	aime	Please provide us playgroundsgre matter		e two bur assistance in this				
Loraine Ga	andara							
141446				10/11/2015	10/27/2015	51		\$0.00
Medium	Work In Progress			10/11/2015 12:28:53				
Pinon, Jose	е	Monthly - QRTLY to PMschedule de		ORT (GES) - Refer				
Margret Vill	lalobos							
142949				11/3/2015		28		\$0.00
Medium	Work In Progress	Conference		11/3/2015 9:26:50 AM				
Gallegos, F	Rafael	need immediate a coming in greatly						
Loraine Ga	andara							
142862		Restroom		11/2/2015		29		\$0.00
Medium	Work In Progress			11/2/2015 9:32:58 AM				
Ontiveros,	Joe	need to replace al	l staff toilets					
Joe Ontive	ros							

12/1/2015 4:03:41 PM

Selected Dat WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2015 - 6/30/2016 Order By Loo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	ES					
142678			11/1/2015		30		\$0.00
Medium	Work In Progress		11/1/2015 12:53:51 AM				
Ontiveros,	Joe	Yearly - Gadsden ES - Grease Tra schedule details.	p - Refer to PM				
Margret Vil	lalobos						
140066		Office	9/16/2015		76		\$0.00
Medium	Work In Progress	Ms. Word	9/16/2015 11:25:15 AM				
Chavez, Sa	antos	need immediate assistance with lig officewould greatly appreciate you matter					
Loraine Ga	andara						
140910			10/4/2015		58		\$0.00
Medium	Work In Progress		10/4/2015 12:38:44 AM				
Villalobos,	Margret	Monthly - Gadsden ES - Enviro Con Refer to PMschedule details.	ntrols Quarterly -				
Margret Vil	lalobos						
137401		Classroom	8/6/2015		117		\$0.00
Medium	Work In Progress	305	8/6/2015 10:51:39 AM				
Chavez, Sa	antos	need to do a walk thruwill be purch create class room into a labwill ne for computersgreatly appreciate y matter	ed additional outlets				
Loraine Ga	andara						
136480		Cafeteria	7/27/2015		127		\$0.00
Medium	Work In Progress		7/27/2015 7:46:34 AM				
Chavez, Sa	antos	need assistancellight bulbs in ca outwhen they do soa lot of smc smell comes outgreatlyappreciat	ke and a aweful burn				
Loraine Ga	andara						
136903			8/2/2015		121		\$0.00
Medium	Work In Progress		8/2/2015 12:31:58 AM				
Vallejo, Alb	pert	Yearly - Gadsden ES Fire Ext. Insp PMschedule details.	. (Yearly) - Refer to				
Margret Vil	lalobos						
142717			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:17 AM				
Orozco, Da	niel	Monthly-Gadsden ES - Fire Suppre to PM schedule details.	ession Insp - Refer				
Margret Vil	lalobos						

Count: 15	Work Orders	А	vg. Age of WO's 6	9		Total for Gadsde	en ES	0	\$0.00
Margret Vi	llalobos								
Orozco, Da	aniel	Monthly-Gads to PMschedule	den ES - Range Hoo details.	d Cleaning -	Refer				
Medium	Work In Progress			11/1/20	15 12:54:16 AN	1			
142716					11/1/2015	11/22/2015	30		\$0.00
Location:	Gadsden	ES							
Requeste	r Name								
Assigned	То	Area Number F Description	Reason		Created Date/Time	Action Taken			
Priority	Status			Crea		Actual Comp Date	Aged	Hours	
Selected Da WOID	ate Range for Request Building	Dates:7/1/2015 - 6 Area	3/30/2016 Order By Loca Deferred By	cation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
002 -			1091633 (i iscai	i cai j				Total

WOID Priority Assigned ⁻ Requester		Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ac		Days Aged	Labor Hours	
Location:	Gadsden	HS					
138687		Athletic Field	8/25/2015		98		\$0.00
Medium	Work In Progress	Baseball Field	8/25/2015 2:32:18 PM				
Vallejo, Alt	bert	Requested by Coach Yanezfor B Baseball Field-Pour cement in ba baseball field.					
Velia Alarc	con						
143861			11/19/2015		12		\$0.00
Medium	Work In Progress		11/19/2015 3:34:59 PM				
Carrasco,	Danny	Need fuel for truck #154, GHS.					
Guillermo	Hernandez						
143829			11/18/2015		13		\$0.00
Medium	Work In Progress		11/18/2015 6:19:12 PM				
Carrasco,	Danny	need fuel for utv 0515					
Eric Medin	ia						
142703			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:07 AM				
Orozco, Da	aniel	Monthly-Gadsden HS Range Ho PMschedule details.	ood Cleaning - Refer to				
Margret Vil	llalobos						
142725			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:22 AM				
Orozco, Da	aniel	Monthly-Gadsden HS Fire Supp PMschedule details.	ression Insp Refer to				
Margret Vil	llalobos						
135291			7/5/2015		149		\$0.00
Medium	Work In Progress		7/5/2015 12:30:35 AM				
Vallejo, Alt	bert	Monthly - Gadsden HS Generato to PMschedule details.	or PM (Quarterly) - Refer				
Margret Vil	llalobos						
143977			11/24/2015		7		\$0.00
Medium	Work In Progress		11/24/2015 12:34:42				
Medina, Er	ric	Daily - Gadsden HS - Fire Pump PMschedule details.	(Biweekly) - Refer to				
Margret Vil	llalobos						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time A Description	•	Days Labor Aged Hours	
Location:	Gadsden	HS			
140899		10/4/2015		58	\$0.00
Medium	Work In Progress	10/4/2015 12:38:37 AM			
Vallejo, Alt	pert	Monthly - Gadsden HS - Fire Sprinkler Insp Refer to PMschedule details.			
Margret Vil	lalobos				
140869		10/4/2015		58	\$0.00
Medium	Work In Progress	10/4/2015 12:38:17 AM			
Vallejo, Alt	pert	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PMschedule details.			
Margret Vil	lalobos				
135296		7/5/2015		149	\$0.00
Medium	Work In Progress	7/5/2015 12:30:38 AM			
Vallejo, Alb	pert	Monthly - Gadsden HS - Fire Pump Engine - Refer to PMschedule details.			
Margret Vil	lalobos				
140874		10/4/2015		58	\$0.00
Medium	Work In Progress	10/4/2015 12:38:20 AM			
Vallejo, Alb	pert	Monthly - Gadsden HS - Fire Pump Engine - Refer to PMschedule details.			
Margret Vil	lalobos				
142834		11/1/2015	11/7/2015	30	\$0.00
Medium	Work In Progress	11/1/2015 12:55:34 AM			
Hernandez	z, Guillermo	Monthly - Gadsden HS Monthly FE Inspection - Refer to PMschedule details.			
Margret Vil	lalobos				* • • • •
143400		11/10/2015		21	\$0.00
Medium	Work In Progress	11/10/2015 3:45:02 PM			
Carrasco,	Danny	Need to check scissor lift. Batteries are not holding the charge. The scissor lift needs to be moved awayfrom the wall in order to check the rest of the batteries.			
Guillermo	Hernandez				
136922		8/2/2015		121	\$0.00
Medium	Work In Progress	8/2/2015 12:32:09 AM			
Vallejo, Alb	pert	Yearly - Gadsden HS Fire Ext. Insp. (Yearly) - Refer to PMschedule details.			
Margret Vil	lalobos				

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
142869			11/2/2015		29		\$0.00
Medium	Work In Progress		11/2/2015 10:38:48 AN	1			
Vallejo, All	bert	Requested by Mr. D. Martinez for Portables-ATTENTION ALBERT fence to be extended in area nex	VALLEJO-Request for				
Velia Alaro	con						
139037	Academic Bldg	Classroom	8/31/2015		92		\$0.00
Medium	Work In Progress		8/31/2015 11:20:31 AN	1			
Lara, Ralp	h	Requested by Mr. Gallardo Rm. 3 Door handle is not working prope very hard to open.					
Velia Alaro	con						
141291			10/8/2015		54		\$0.00
Medium	Work In Progress	WeightRoom	10/8/2015 1:43:56 PM	1			
Lara, Ralp	h	Requested by Mr. Giron for Weigh entrance doors into the Weight Re lock properly. Students pull on the open. There is a chain and pad I secures the building. However, ir emergency, this will become a sa students or staff try to exit the bui ensure the security of the equipm locking mechanism need to be re soon as possible.	oom do not close or e doors and theyeasily ock that currently a case of an afetyissue when ilding. For safety and to ent the doors or				
Velia Alaro	con						
143910			11/20/2015		11		\$0.00
High	Work In Progress		11/20/2015 8:13:58 AN	1			
Orozco, Da	aniel	MILK BOX IN OLD FAVORITES S WORKING AT ALL. SNP MANAG 882.5522					
Maritza Go	onzalez						
139199			9/2/2015		90		\$0.00
Medium	Work In Progress		9/2/2015 8:13:39 AN	1			
Orozco, Da	aniel	4 OVENS DOWN. SNP MANAGE 882.5522	R FRANCES B.				
Maritza Go	onzalez	• ///					A
143927		Office	11/20/2015		11		\$0.00
Medium	Work In Progress		11/20/2015 12:23:58	•			
Gonzales,	, Camilo	Deliver 2 boxes. PO# 15160285	0. Thank you.				
Theresa F	Ramirez						

WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loo Area Deferred By Area Number Reason Description	Until Request Date Targ Created Date/Time Actu		Cos Labor Hours
Location:	Gadsden	HS			
143929		Office	11/20/2015	11	\$0.
Medium	Work In Progress		11/20/2015 2:11:43 PM		
Gonzales	, Camilo	Deliver 1 cow and 4 boxes. PO# 1 you.	51602849. Thank		
Theresa F	Ramirez				
143192			11/6/2015	25	\$0.
Medium	Work In Progress		11/6/2015 10:49:59 AM		
Gonzalez,	, Salvador	Requested by Coach Vasquezfor F in the Boy's Gym-Extension to existi room.			
Velia Alar			0/15/0015		
139963	Pool Pump	Pump House	9/15/2015	77	\$0.
Medium	Work In Progress		9/15/2015 7:55:51 AM		
Gonzalez,	, Salvador	fabricate square tubing post to sup shade	portpool canopy		
Mario Apo	odaca	o.#			^
143922		Office	11/20/2015	11	\$0.
Medium	Work In Progress		11/20/2015 11:03:50		
Gonzales	, Camilo	Deliver 1 box. PO# 151602375. T	hank you.		
Theresa F	Ramirez				
143924		Office	11/20/2015	11	\$0.
Medium	Work In Progress		11/20/2015 11:19:26		
Gonzales	, Camilo	Deliver 1 box. PO# 151602042. A Thank you.	ttn: S. Schapekahm.		
Theresa I	Ramirez				
138008			8/14/2015	109	\$0.
Medium	Work In Progress		8/14/2015 7:21:53 AM		
Castillo, C	Carlos	Need to replace two burn out lamps parking lot and around the CTE buil			
	Hernandez				
142895			11/2/2015	29	\$0.
Medium	Work In Progress		11/2/2015 3:42:33 PM		
Ambriz, Jo	ose	Joe need to order contactor for tran gym	ne heater unit west v.		
Eric Medi	na				

Building Status To Name	Area Deferred By U Area Number Reason Description	Jntil Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
	HS					
		11/6/2015		25		\$0.00
Work In Progress						
se	Joe need to replace add water valve on hydronic system please	academic				
а						
		11/30/2015		1		\$0.00
Work In Progress		11/30/2015 3:52:06 PM				
se	Need to replace fan coil motor to unit in at the Old English.	classroom #150				
Hernandez						
		11/10/2015		21		\$0.00
Work In Progress		11/10/2015 3:42:00 PM				
se	Need to check H/C unit for North buildin and #221.	ng #219, #220				
Hernandez						
	Athletic Field	9/3/2015		89		\$0.00
Work In Progress		9/3/2015 7:55:28 AM				
arlos	need to wire tanks at ghs and also com	pressor.				
e Ontiveros						
		11/6/2015		25		\$0.00
Work In Progress		11/6/2015 10:47:08 AM				
arlos						
on						
	Football Field	8/24/2015		99		\$0.00
Work In Progress		8/24/2015 2:46:32 PN	l			
arlos	that was run last year for the Band Boos down with the intention to rerun anothe bleachers. The work was not complete that the current electrician was no longe district. We are asking for the work to be	sters was taken r one under the d due to the word er with the e finished				
	Name Gadsden I Work In Progress a Work In Progress se Hernandez Work In Progress arlos e Ontiveros Work In Progress arlos anos	Name Gadsden HS Work In Progress se Joe need to replace add water valve on hydronic system please a Work In Progress se Need to replace fan coil motor to unit in at the Old English. Hernandez Work In Progress se Need to check H/C unit for North buildir and #221. Hernandez Work In Progress se Need to wire tanks at ghs and also come on the onthe on the set of	Name Cadsden HS 11/6/2015 7:58:53 AM Work In Progress A 11/6/2015 7:58:53 AM See Joe need to replace add water valve on academic hydronic system please a 11/30/2015 3:52:06 PM See Need to replace fan coil motor to unit in classroom #150 atthe Old English. Hernandez 11/10/2015 3:42:00 PM See Need to replace fan coil motor to unit in classroom #150 atthe Old English. Hernandez 11/10/2015 3:42:00 PM See Need to check H/C unit for North building #219, #220 and #221. Hernandez Athletic Field 9/3/2015 Work In Progress 9/3/2015 7:55:28 AM and seed to wire tanks at ghs and also compressor. Ontiveros Ontiveros Athletic Field 9/3/2015 Work In Progress Requested by Coach Vasquez for Football Locker Room in Boy's Gym-Install a light switch	Name 11/6/2015 Cadsden HS 11/6/2015 7:58:53 AM See Joe need to replace add water valve on academic hydronic system please a 11/30/2015 Work In Progress Need to replace fan coil motor to unit in class room #150 atthe Old English. Hernandez 11/10/2015 3:42:00 PM Work In Progress Need to check H/C unit for North building #219, #220 and #221. Hernandez 11/10/2015 3:42:00 PM See Need to check H/C unit for North building #219, #220 and #221. Hernandez 11/10/2015 3:42:00 PM See Need to check H/C unit for North building #219, #220 and #221. Hernandez 11/6/2015 3:42:00 PM Work In Progress 0 Athletic Field 9/3/2015 7:55:28 AM ados need to wire tanks at ghs and also compressor. a Onti	Name Number of Cadsden HS Gadsden HS 11/6/2015 7:58:53 AM See Joe need to replace add water valve on academic hydronic system please a 11/6/2015 7:58:53 AM See Need to replace add water valve on academic hydronic system please a 11/30/2015 3:52:06 PM Work In Progress Need to replace fan coil motor to unitin class room #150 at the Old English. Hermandez 11/10/2015 3:42:00 PM Work In Progress Need to check H/C unit for North building #219, #220 and #221. Hermandez 11/6/2015 7:55:28 AM adots need to wire tanks at ghs and also compressor. a Ontwores 11/6/2015 10:47:08 AM adots Requested by Coach Vasquez/or Football Locker Room in Boy's Gym-Install a light switch for Football Botoball Field 8/24/2015 99 Work In Progress 8/2/2/2015 2:46:32 PM	

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description	Until Request Date Target Co Created Date/Time Actual Co		Cos Labor Hours
Location:	Gadsden	HS			
137323		Football Field	8/5/2015	118	\$0.
Medium	Work In Progress		8/5/2015 2:51:56 PM		
Castillo, C	arlos	the new irrigation well by the footb switch regulator needs to be wired panel of the well			
Mario Apo	daca				
144098		Classroom	12/1/2015	0	\$0.
Medium	Work In Progress	Portable # 12	12/1/2015 12:49:25 PM		
Medina, Ei		Requested by Coach J. Vasquez would like have the front door of th maroon.			
Velia Alarc	on		40/4/0045	0	¢ 0.
144099			12/1/2015	0	\$0.
Medium	Work In Progress		12/1/2015 12:54:31 PM		
Medina, Ei	ric	Requested by Coach J. Vasquezf Room-He would like to have the o football locker room painted marc	utside doors to the		
Velia Alarc	on				
140912			10/4/2015	58	\$0.
Medium	Work In Progress		10/4/2015 12:38:45 AM		
Villalobos,	, Margret	Monthly - Gadsden HS - Enviro C Refer to PM schedule details.	ontrols Quarterly -		
Margret Vil					
138667	AcademicBldg	Classroom	8/25/2015	98	\$0.
Medium	Work In Progress	332	8/25/2015 10:16:59 AM		
Lara, Ralp	h	Requested by Ms. Roth Rm. 332 A Only secure closet, locked died to closet re-keyed as soon as possi closet to secure personal items.	oday. Need to have		
Velia Alarc	on				
137919		Office	8/13/2015	110	\$0.
Medium	Work In Progress		8/13/2015 9:11:06 AM		
Lara, Ralp	h	Requested by Ms. Valles Rm. 718 drawer is jammed and cannot be unlocked.			
	on				

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By	Until	•	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS							
140354					9/21/2015		71		\$0.00
Medium	Work In Progress			9/21/2	015 3:52:51 PM	1			
Ambriz, Jos	se		de cooling system a and ice machine.	tbreak room t	o hot				
Guadalupe	e Ontiveros								
141924					10/19/2015		43		\$0.00
Medium	Work In Progress			10/1	9/2015 12:15:24				
Ambriz, Jos	se	Need to replac rooms at the B	e two roof top exhau oys Gym.	ist fans for th	e locker				
Guillermo	Hernandez								
144090	North Building	Classroom			12/1/2015		0		\$0.00
Medium	Work In Progress	210		12/1/20	15 11:37:02 AN	1			
Ambriz, Jos	se	Check heating-	Ars. Munoz Rm. 210 warm at beginning o d stays very cold.						
Velia Alarc	on								
140227					9/18/2015		74		\$0.00
Medium	Work In Progress			9/18/2	015 1:53:22 PM	1			
Chavez, Sa	antos		rewire outside light nd pulled out wires	near panther	paw				
Eric Medin	а				- / / / / -				
139352					9/4/2015		88		\$0.00
Medium	Work In Progress			9/4/20	15 10:53:29 AN	1			
Chavez, Sa	antos	Irrigation Well -	Need to wire control	ls					
Albert Valle	ejo								
141916		Classroom			10/19/2015		43		\$0.00
Medium	Work In Progress	Portable #7		10/1	9/2015 10:51:52				
Villalobos,	David	small sink and	<i>I</i> ls . Hartmann Portal broken faucet with a an equipment (one r	laundrysink					
Velia Alarc	on								
142747					11/1/2015	11/4/2015	30		\$0.00
Medium	Work In Progress			11/1/20	15 12:54:37 AN	1			
Medina, Er	ic	Monthly - Gads Refer to PMsch	den HS - Emerg. Ey Jedule details.	/ewash (Mon	hly) -				
	lalobos								

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Area Number Description Created Date/Time Created Date/Time	Target Comp Date Days Labor Actual Comp Date Aged Hours Action Taken	Costs
Location:	Gadsden	HS		
142675		11/1/2015	30	\$0.00
Medium	Work In Progress	11/1/2015 12:53:49 AM		
Medina, E	ric	Yearly - Gadsden HS - Grease Trap - Refer to PM schedule details.		
Margret Vi	llalobos			
143088		11/5/2015	26	\$0.00
Medium	Work In Progress	11/5/2015 7:01:35 AM		
Villalobos	, David	please on the weigth room girls restrooms the sink is clogged and over flows i tried to uncloged but no luck thank you		
Luis Sauc				
136037	Boys Gym	7/16/2015	138	\$0.00
Medium	Work In Progress	7/16/2015 4:00:37 PM		
Villalobos	, David	As per Mr. Giron he would like to have all the showers working. Location is locker rooms in the Boys Gym.		
	Hernandez			
140867		10/4/2015	58	\$0.00
Medium	Work In Progress	10/4/2015 12:38:15 AM		
Flores, Pe		Monthly - GHS-UV-0515 PM Service - Refer to PM schedule details.		
Margret Vi	llalobos			
142871		11/2/2015	29	\$0.00
Medium	Work In Progress	11/2/2015 10:56:01 AM		
Flores, Pe		please the john deere gator uv-ghs-0905 flat tire from the back of passenger side not good thank you		
Luis Sauc	edo	10/07/0015	05	* •••••
142432		10/27/2015	35	\$0.00
Medium	Work In Progress	10/27/2015 3:49:15 PM		
Flores, Pe	te	Truck GHS #155. Gearshift broke and due for services.		
Guillermo	Hernandez			
141042		Custodial 10/5/2015	57	\$0.00
Medium	Work In Progress	10/5/2015 9:14:41 AM		
Flores, Pe		please the john deere gator uv-ghs-0905 the headligths not working please thank you		
Luis Sauc	edo			

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By	Until Request Da	ate Target Comp Date ne Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS						
143455		Athletic Field		11/12/20)15	19		\$0.00
Medium	Work In Progress			11/12/2015 9:04:06	AM			
	Guadalupe			e hook up with relay with irrigation control.				
	e Ontiveros							
141254		Custodial		10/8/20		54		\$0.00
Medium	Work In Progress			10/8/2015 7:39:18	AM			
Estrada, Je	esus		possible to have a to clean around th	a wheelbarrow and two ne edges of sides				
		thank you						
Luis Sauc	edo							
140885				10/4/20	015 10/12/2015	58		\$0.00
Medium	Work In Progress			10/4/2015 12:38:27	AM			
Hernande	z, Guillermo	Monthly - Gads schedule detail		ection - Refer to PM				
Margret Vil	llalobos							
143610				11/16/20)15	15		\$0.00
Medium	Work In Progress			11/16/2015 7:44:32	AM			
Flores, Pe	te	Need to replace	e bad tire for truck	#154 at GHS.				
Guillermo	Hernandez							
138924				8/28/20)15	95		\$0.00
Medium	Work In Progress			8/28/2015 9:27:48	AM			
Lara, Ralp	h			5 Science Building- ot go into door cylinder				
Velia Alarc	con							
138952				8/28/20)15	95		\$0.00
Medium	Work In Progress			8/28/2015 2:15:09	PM			
Lara, Ralp	h		e the panic bars to n stopped working	back doors of the g and theyare losing				
Guillermo	Hernandez							

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
141301		Athletic Field	10/8/2015		54		\$0.00
Medium	Work In Progress	Track Field	10/8/2015 3:36:12 PN	1			
Ontiveros,	Guadalupe	Requested by Coach Walker for T track, track has bubbled at the 14 worn patches (x3-5). Needs to be remarked.	4 yd marker and has				
Velia Alarc	on		10/10/00/5		- 10		<u> </u>
141599			10/13/2015		49		\$0.00
Medium	Work In Progress		10/13/2015 11:37:31				
	Guadalupe	Trash Dumpsters along south ac regular trash dumpster from the b across from Tech/Ag building to t across from the nurse/girls gym. the move is completed	block enclosed area he block enclosed area				
Alfredo Ho	•						
144005	AcademicBldg		11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 10:33:13	5			
Lara, Ralpl	h	Requested by Rita Correa for Rm Building Sp.Ed. Office-Cabinet#3 open. They really need the file ca are stored in cabinet.	3 does not want to				
Velia Alarc	con						
143766			11/18/2015		13		\$0.00
Medium	Work In Progress		11/18/2015 9:11:09 AM	1			
Lara, Ralpl	h	please need to adjust doors on th	ne varisty gym				
		thank you					
Luis Sauc	edo						
140029	Varsity Gym	Gym	9/15/2015		77		\$0.00
Medium	Work In Progress		9/15/2015 4:08:53 PN	1			
Lara, Ralpl	h	Requested by Mr. Giron for the V new pad lock under the stage ar Master and four (4) keys are need to store folding tables and tables	nd it needs to be Off led. This area is used				
Velia Alarc	on						
141117		Classroom	10/6/2015		56		\$0.00
Medium	Work In Progress	Portable #6	10/6/2015 1:23:40 PN	1			
Lara, Ralpl	h	Requested by Ms. Arredondo for lock door knob between portable of equipment and when teacher is afraid equipment can be stolen.	s. Portable # 5 has a lot				
Velia Alarc	on						

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
143112		Classroom	11/5/2015		26		\$0.00
Medium	Work In Progress	605	11/5/2015 10:58:52 AM	I			
Lara, Ralpl	h	Requested by Ms. Emery Rm. 605 file cabinet was locked by a stude able to find the keyto cabinet. Teac cabinet as soon as possible. Cabin keyed and three keys are needed.	nt. We have not been her needs access to				
Velia Alarc	on						
139129		Classroom	9/1/2015		91		\$0.00
Medium	Work In Progress	Portable # 150	9/1/2015 9:55:53 AM	l			
Lara, Ralpl	h	Requested by Coach Yanez for Po Intervention Portable)-Put a lock or storage room door which is located towards the back of the room.	deadbolt on the				
Velia Alarc	on						
143906			11/20/2015		11		\$0.00
High	Work In Progress		11/20/2015 7:57:31 AM				
Villalobos,	, Margret	MICE PROBLEMS. SNP MANAGEF 882.5522	R FRANCES B.	EMBennie 11/20/15			
Maritza Go	nzalez						
143989			11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 12:52:00				
Sanchez, F	Raul	Monthly - Gadsden HS - Monthly M Refer to PMschedule details.	eter Readings -				
Margret Vil	lalobos		44/4/0045				.
142823			11/1/2015		30		\$0.00
Medium	Work In Progress		11/1/2015 12:55:27 AM				
Sanchez, F	Raul	Monthly - Gadsden HS - Lift Station to PMschedule details.	n Inspection - Refer				
Margret Vil	lalobos						
143599			11/14/2015		17		\$0.00
Medium	Work In Progress		11/14/2015 12:27:49				
Sanchez, F	Raul	Monthly - Gadsden HS- Filters (Pu Refer to PMschedule details.	mp Rm) Quarterly -				
Morarat \/il	lalobos						

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
140674	Main Building	PumpHouse	9/25/2015		67		\$0.00
Medium	Work In Progress		9/25/2015 4:01:26 PN				
Sanchez, R	Raul	9/25/15 Requesting a work order for the inst chlorination equiptment for the supp well in case of emergency use					
		Thanks, Raul					
Raul Sanc	hez		40/04/0045		- 24		<u> </u>
142662			10/31/2015		31		\$0.00
Medium	Work In Progress		10/31/2015 12:34:37				
Sanchez, R		Monthly - Gadsden HS-WWTP Che (Monthly) - Refer to PM schedule de					
Margret Vill 143536			11/13/2015		18		\$0.00
Medium	Work In Progress		11/13/2015 8:15:55 AM				ψυιου
Carrasco, I	-	please as per office we need a 5 fly					
Curracio, i	Danny						
Luis Sauce	odo	thank you					
143602	euo		11/15/2015		16		\$0.00
Medium	Work In Progress		11/15/2015 12:27:53				+
Flores, Pet	-	Yearly-Gadsden HS-Mow (0408/04 Refer to PMschedule details.					
Margret Vil	lalobos						
142786			11/1/2015	11/9/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:55:03 AM				
Medina, Er	ic	Monthly - Gadsden HS Emer. Light Refer to PMschedule details.	Test: Monthly-				
Margret Vil	lalobos						
143860			11/19/2015		12		\$0.00
Medium	Work In Progress		11/19/2015 3:34:01 PM				
Medina, Er	ic	replaced tile in custodial closet in ol	dmain				
Eric Medina	а						
142238			10/23/2015		39		\$0.00
Medium	Work In Progress		10/23/2015 2:00:32 PM				
Medina, Er	ic	need to replace weather strip in v. g	<u>jym</u>				
Eric Medina	а						

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
142888			11/2/2015		29		\$0.00
Medium	Work In Progress		11/2/2015 3:34:56 PM				
Medina, Er	ic	need replace contactor on trane ur	nitwest				
Eric Medin	а						
143194			11/6/2015		25		\$0.00
Medium	Work In Progress		11/6/2015 10:58:39 AM				
Medina, Er	ic	Requested byCoach Vasquezfor in Boy's Gym-Remove a rod from c					
Velia Alarc	on	0	0/04/0045				.
140548		Classroom	9/24/2015		68		\$0.00
Medium	Work In Progress	Portable # 7	9/24/2015 9:17:10 AM				
Medina, Er		Requested byMs. Hartmann Porta replace broken blinds.	able#7-Please				
Velia Alarc 144096	on		12/1/2015		0		\$0.00
Medium	Work In Progress		12/1/2015 12:38:44 PM		Ū		φ0.00
	z, Guillermo	Requested byMs. Schapekahm R -Check heater.					
Velia Alarc	on						
144041			11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 3:43:55 PM				
Hernandez	z, Guillermo	Need to replace flush lever to toile	tPortable #15.				
Guillermo	Hernandez						
144046			11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 3:46:31 PM				
Hernandez	z, Guillermo	Please check entrance door to the	Nurse station.				
Guillermo	Hernandez						
143634			11/16/2015		15		\$0.00
Medium	Work In Progress		11/16/2015 12:14:05				
Hernandez	z, Guille <i>r</i> mo	Need to order paint for the weight r	oom.				
Guillermo	Hernandez						
143859			11/19/2015		12		\$0.00
Medium	Work In Progress		11/19/2015 3:33:21 PM				
Hernandez	z, Guillermo	Please check water leak in class re	oom.#123.				
Guillermo	Hernandez						

	WORK OID				i cai j				Tota
Selected Da WOID	ate Range for Request Building	Dates:7/1/2015 - 6 Area	/30/2016 Order By Loo Deferred By	cation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Crea	ated Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Gadsden	HS							
142809					11/1/2015	11/9/2015	30		\$0.00
Medium	Work In Progress			11/1/20)15 12:55:18 AN	1			
Hernande	ez, Guille m o	Monthly - Gads PMschedule d	den HS Exit Sign In: etails.	sp:Monthly-	Refer to				
Margret Vi	illalobos								
141917		Classroom			10/19/2015		43		\$0.00
Medium	Work In Progress	Portable #7		10/1	9/2015 10:54:48				
Medina, E	ric		. Hartmann Portable rooms near sink for						
Velia Alaro	con								
142973	Academic Bldg	Storage			11/3/2015		28		\$0.00
Medium	Work In Progress			11/3/2	2015 3:32:45 PM	1			
Medina, E	ric	Bookroom in A bookshelves ir	Mr. Martinez for Rm. cademic Building-Pl the old math bookro bookshelves in case	ease remove oom in the Ac	the ademic				
Velia Alaro	con								
Count: 89	Work Orders	A	vg. Age of WO's 4	5		Total for Gadsde	n HS	0	\$0.00

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loo Area Deferred By Area Number Reason Description	Until Request Dat	e Target Comp Date e Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS					
138518	C-Wing	Office	8/21/201	5	102		\$0.00
Medium	Work In Progress	AVECHS -	8/21/2015 2:37:51 F	PM			
Marquez, (Gerardo	PLEASE BUILT IN COUNTERS FO ROOM.	OR STUDENT UNION				
Yvette Cor	tez						
138519	C-Wing	Office	8/21/201	5	102		\$0.00
Medium	Work In Progress	AVECHS -	8/21/2015 2:40:17 F	M			
Marquez, (Gerardo	NEED OPEN SHELVING FOR KITC PLEASE CONTACT MRS. HOOD C FOR FURTHER DETAILS AT 882-6	OR MRS QUEZADA				
Yvette Cor	tez						
143782	Gym	Gym	11/18/201	5	13		\$0.00
Medium	Work In Progress	Gym Lobby	11/18/2015 2:12:02 F	М			
Marquez, (Gerardo	In gym lobby, hallway between 602 the way into the key hole. For more contact Martin Soria					
Hilda Adle	er						
141772			10/15/201	5	47		\$0.00
Medium	Work In Progress		10/15/2015 12:14:	52			
Herrera, N	lario	Need to order list of Filters that wa	s giving to Danny C.				
Mario Her	rera						
142661			10/31/201	5	31		\$0.00
Medium	Work In Progress		10/31/2015 12:34:	36			
Apodaca,	Mario	Monthly - Gadsden MS-WWTP Che (Monthly) - Refer to PM schedule d					
Margret Vi	llalobos						
144075			12/1/201	5	0		\$0.00
Medium	Work In Progress		12/1/2015 7:15:22 A	M			
Villalobos	, Margret	MICE IN WASH ROOM.SNP MANA 882.2824	GER TERRY P.	EM Bennie 12/1/15			
Maritza Go	onzalez						
143982			11/30/201	5	1		\$0.00
Medium	Work In Progress		11/30/2015 12:51:	55			
Apodaca,	Mario	Monthly - Gadsden MS - Monthly M Refer to PM schedule details.	eter Readings -				
Margret Vi	llalobos						

Selected Da WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS					
142015		Classroom	10/20/2015		42		\$0.00
Medium	Work In Progress	B-Wing Rm#117	10/20/2015 3:02:16 PN	1			
Soria, Mai	rtin	Please clean light fixtures.					
Hilda Adle		Ŭ					
142290		Storage	10/26/2015		36		\$0.00
Medium	Work In Progress	Old Main	10/26/2015 8:48:07 AN	1			
Soria, Mai	rtin	Please clean and mop room to ge Will be used for Panther Closet. If see Terry Urbina or Carol Hernand	anyquestions please				
Hilda Adle	er						
142226	C-Wing	Foyer	10/23/2015		39		\$0.00
Medium	Work In Progress	AVECHS -	10/23/2015 10:34:51				
Carbajal,	Jimmy	we needs floor mats in front entrait wet AVECHS - ANNEX	nce. slipperywhen				
Rosa Que	ezada	2					.
143259		Classroom	11/6/2015		25		\$0.00
Medium	Work In Progress	A-Wing Rm#160	11/6/2015 4:20:30 PN	Λ			
Herrera, N	<i>l</i> ario	Door stop rubber fell off. Door do	bes not stay open.				
Hilda Adle	er						
143907			11/20/2015		11		\$0.00
Medium	Work In Progress		11/20/2015 7:57:48 AN	1			
Herrera, N	<i>l</i> ario	Requesting new levels					
Mario Her	rera						
144006			11/30/2015		1		\$0.00
Medium	Work In Progress	Rm#112	11/30/2015 10:35:25	5			
Herrera, N	<i>l</i> ario	I need 2 White boards put on the w	valls.				
Hilda Adle	er						
142880	C-Wing		11/2/2015		29		\$0.00
Medium	Work In Progress		11/2/2015 1:57:07 PM	1			
Flores, Pe	ete	The brakes on vehicle 169 need to noise and need to press brake pe to make vehicle stop.					
Terry Alva	rado						
143810			11/18/2015		13		\$0.00
Medium	Work In Progress		11/18/2015 3:50:29 PN	1			
Ontiveros	, Joe	Gym locker rooms are clogged					
Mario Her							
	5 4:03:42 PM						69 of 137

12/1/2015 4:03:42 PM

WOID Priority Assigned 1 Requester			Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
140230	Annex	Restroom		9/18/2015		74		\$0.00
Medium	Work In Progress			9/18/2015 2:27:59 PM	I			
Ontiveros,	Joe	please replace i leaving them on		with new ones kids are				
Martin Sori	a							
143387		Classroom		11/10/2015		21		\$0.00
Medium	Work In Progress	A-Wing Rm#169)	11/10/2015 2:49:53 PM				
Ontiveros,	Joe	Washing Machiı Please fix ASAP		to drain the water.				
Hilda Adle								
140237	C-Wing			9/18/2015		74		\$0.00
Medium	Work In Progress	Main Annex		9/18/2015 3:00:33 PM	l			
Chavez, Sa		-	POWER OURTAG	GE IN THE BUILDING. ASAP.				
Yvette Cort	Annex			9/14/2015		78		\$0.00
139952		Anney Electrical				10		Ф 0.00
Medium	Work In Progress	Annex Electrica		9/14/2015 4:04:27 PN	I			
Chavez, Sa		Annexelectrical	boxis notworking	g or jumping as well.				
Hilda Adle	r			0/14/2015		70		¢0.00
139909				9/14/2015		78		\$0.00
Medium	Work In Progress			9/14/2015 2:07:22 PN				
Chavez, Sa		PleaseseeMar Signs	o, Building Mech	anic regarding Exit				
Mario Herr 139974	Main Building	Office		9/15/2015		77		\$0.00
	-	Ollice						φ0.00
Medium	Work In Progress			9/15/2015 10:40:35 AN				
Chavez, Sa		Nopowerinnur	ses office and sp	ed. Check outlets				
Santos Ch		Classroom		40/40/0045		50		<u> </u>
141522	Band Room	Classroom		10/12/2015		50		\$0.00
Medium	Work In Progress	Rm#100 Band /		10/12/2015 3:10:56 PM				
Chavez, Sa	antos	Install wall elect	rical outlet under	sink.				
Hilda Adle				10/00/0015				.
142281	Cafeteria	Exterior		10/26/2015		36		\$0.00
Medium	Work In Progress			10/26/2015 7:29:31 AN				
Chavez, Sa	antos	light next to SNP	entrance needs	a new Ballast				

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date T Created Date/Time A	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS					
140218		Office	9/18/2015		74		\$0.00
Medium	Work In Progress	A-Wing Sped	9/18/2015 11:19:14 AM				
Chavez, S	antos	Electrical outlet on wall connection working.	to printer is not				
Hilda Adle	r						
143779			11/18/2015		13		\$0.00
Medium	Work In Progress		11/18/2015 1:03:44 PM				
Chavez, S		Silver is checking on the scoreboa are having issues. He thinks it is e					
Cora Ram	irez		0/05/0045				<u> </u>
138659			8/25/2015		98		\$0.00
Safety	Work In Progress		8/25/2015 9:23:01 AM				
Ontiveros,		Eye Wash - All 3 missing string for a valve is broken asp PM136938	shower and 002-				
Mario Heri 142674	rera		11/1/2015		30		\$0.00
Medium	Work In Prograam		11/1/2015 12:53:48 AM		50		ψ0.00
Herrera, N	Work In Progress Iario	Yearly - Gadsden MS - Grease Tra schedule details.					
Margret Vi	llalobos						
140809			10/4/2015	11/4/2015	58		\$0.00
Medium	Work In Progress		10/4/2015 12:37:35 AM				
Herrera, N	lario	Yearly - Gadsden MS I-4 Fan Coil PMschedule details.	Unit Yearly - Refer to				
Margret Vi	llalobos						
140810			10/4/2015	11/4/2015	58		\$0.00
Medium	Work In Progress		10/4/2015 12:37:36 AM				
Herrera, N	lario	Yearly - Gadsden MS U-2 Unit HT Refer to PM schedule details.	Gas/Water Yearly -				
Margret Vi	llalobos						
140796			9/30/2015		62		\$0.00
Medium	Work In Progress		9/30/2015 12:43:19 AM				
Herrera, N	lario	Monthly - Gadsden MS A-16 Fan E Refer to PMschedule details.	xhaust Semiannual -				
Margret Vi	llalobos						

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2015 - 6/30/2016 Order By Area Deferred By Area Number Reason Description	Until Request Date Target C Created Date/Time Actual C		Labor Hours
Location:	Gadsden	MS			
140575	Annex	Hallway/Corridor	9/24/2015	68	\$0.00
Medium	Work In Progress		9/24/2015 3:17:11 PM		
Solis, Lore	nzo	water fountain in annexis leakin	g		
		Please contact Mario Herrera			
Mario Herr	era				
141771	Cafeteria	Cafeteria	10/15/2015	47	\$0.00
Medium	Work In Progress		10/15/2015 11:58:35		
Solis, Lore	nzo	Requesting new AC units (mast	ercools)9 of them		
Mario Herr	era				
137816	C-Wing		8/12/2015	111	\$0.00
Medium	Work In Progress	AVECHS -	8/12/2015 9:06:55 AM		
Marquez, C	Serardo	Need keys issued for Custodiar Counselor Evelyn Chisari.) Jeremy Apodaca and		
Margret Vil	lalobos				
143775			11/18/2015	13	\$0.00
Medium	Work In Progress		11/18/2015 12:13:09		
Marquez, G	Serardo	SNP OFFICES, NEED 4 CD1 K	EYS FOR STORAGE.		
Maritza Go	nzalez				
143488			11/12/2015	19	\$0.00
Medium	Work In Progress		11/12/2015 3:31:25 PM		
Marquez, C		Need to supply chain and padloo enclosure, so EPEC can double			
Albert Valle	ејо		0/47/0045	100	
138142			8/17/2015	106	\$0.00
Medium	Work In Progress		8/17/2015 2:41:41 PM		
Solis, Lore	NZO	Please assist building mechani inline filter to remove debris from about this.			
Albert Valle	ejo				
143769		Office	11/18/2015	13	\$0.00
Medium	Work In Progress	Sped Conf Rm -	11/18/2015 9:18:59 AM		
Chavez, Sa	antos	2 electrical outlets in the SPED r	oom are not working		

WOID Priority Assigned		Dates: 7/1/2015 - 6/ Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
139948		Football Field		9/14/2015		78		\$0.00
Medium	Work In Progress	Electrical/Field	-	9/14/2015 3:58:31 PM	1			
Chavez, Sa	antos	Electrical grour football clock is		all field to connect the				
Hilda Adle	r							
144019				11/30/2015		1		\$0.00
High	Work In Progress			11/30/2015 1:07:22 PM				
Orozco, Da	aniel		ZER FAN IS NOT \ RY P. 882.2824	WORKING. SNP				
Maritza Go	onzalez			44/00/0045				.
144020				11/30/2015		1		\$0.00
High	Work In Progress			11/30/2015 1:08:23 PM				
Orozco, Da		-	RIGERATOR # 3 I ANAGER TERRY F					
Maritza Go 143913	onzalez			11/20/2015		11		\$0.00
Medium	Work In Prograam			11/20/2015 9:35:13 AM		11		φ0.00
	Work In Progress	N I I <i>N</i>						
Carbajal, J	-	Need propane	or the gas burnish	er				
Martin Sor	ia			8/2/2015		121		\$0.00
136918 Madium						121		φ0.00
Medium Vallejo, Alt	Work In Progress bert	Yearly - Gadsdo PMschedule de		8/2/2015 12:32:07 AM p. (Yearly) - Refer to				
Margret Vil	llalobos							
142726				11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress			11/1/2015 12:54:22 AM	l			
Orozco, Da	aniel	Monthly - Gads PMschedule de		ression Insp Refer to				
Margret Vil								
141514	Band Room	Classroom		10/12/2015		50		\$0.00
Medium	Work In Progress	Rm#100 Band	/	10/12/2015 2:58:44 PM				
Estrada, Je	esus	Repair snags o	n carpet, office and	linner rooms.				
Hilda Adle	r							
142704				11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress			11/1/2015 12:54:08 AM	I			
Orozco, Da	aniel	Monthly - Gads PMschedule de		od Cleaning - Refer to				
Margret Vil	llalobos							
12/1/2015	4:03:42 PM						Page 7	73 of 137

		est Dates:7/1/2015 - 6	U	•					Total Costs
WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requester	r Name								
Location:	Gadso	den MS							
Count: 45	Work Orders	Δ	vg. Age of WO's	46		Total for Gadsde	n MS	0	\$0.00

Selected Da WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, StatusAreaDeferred ByUntilRequest DateArea NumberReasonCreated Date/TimeDescription	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Total Costs
Location:	La Union	ES				
142705		11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress	11/1/2015 12:54:09 AN	1			
Orozco, Da	aniel	Monthly - La Union ES Range Hood Cleaning - Refer to PMschedule details.				
Margret Vil	llalobos		1.1.100.100.15			<u> </u>
142727		11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress	11/1/2015 12:54:23 AV	1			
Orozco, Da		Monthly - La Union ES Fire Suppression Insp Refer to PMschedule details.				
Margret Vil	llalobos	0/20/2015		64		\$0.00
140718		9/28/2015 0/20/2015 2:52:17 PM	a	64		Ф 0.00
Medium	Work In Progress	9/28/2015 3:52:17 PM	1			
Vallejo, Alt		Remove sand and plastic borders and replace with woodchips and concrete at south playground.				
Albert Valle	ејо	8/2/2015		121		\$0.00
Medium	Work In Progress	8/2/2015 12:32:01 AM	1	121		ψ0.00
Vallejo, Alt	-	Yearly - La Union ES Fire Ext. Insp. (Yearly) - Refer to PMschedule details.				
Margret Vil	llalobos					
140398		9/22/2015		70		\$0.00
Medium	Work In Progress	9/22/2015 2:38:01 PM	1			
Gonzalez,	Salvador	need to extend 1' 6" metal pipe for the legs on bench weld metal poll a on parking sign				
Patricio Ag	guilar					
143854		11/19/2015		12		\$0.00
Medium	Work In Progress	11/19/2015 2:49:02 PM				
Castillo, C	arlos	emergency light fixer needing ballast r310				
Patricio Ag	guilar					
142676		11/1/2015		30		\$0.00
Medium	Work In Progress	11/1/2015 12:53:49 AM	1			
Aguilar, Pa	atricio	Yearly - La Union ES - Grease Trap - Refer to PM schedule details.				
Margret Vil	llalobos					
143295		11/9/2015		22		\$0.00
Medium	Work In Progress	11/9/2015 9:01:15 AN	1			
Vallejo, Alt	pert	Replace water heaters.				
Albert Valle	ejo					
12/1/2015	4:03:42 PM				Page 7	75 of 137

WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2015 - 6/30/20 Area Defe Area Number Reas Description	rred By	Until	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	La Union	ES							
139032					8/31/2015		92		\$0.00
Medium	Work In Progress			8/31/20	15 10:35:07 AN	Λ			
Villalobos	s, David	old wing girls rest roc replaced on 5 toilets. brake off if tighten.							
Patricio A	guilar								
143443					11/12/2015		19		\$0.00
Medium	Work In Progress			11/12/2	015 7:52:17 AN	Λ			
Aguilar, Pa	atricio	wo to myself - ck on	gas odor r208	- 209 -110					
Patricio A	guilar								
143853					11/19/2015		12		\$0.00
Medium	Work In Progress			11/19/2	015 2:38:36 PM	1			
Aguilar, Pa	atricio	wo to myself - ck and	cover water line	es insulation					
Patricio A	guilar								
137072					8/3/2015		120		\$0.00
Medium	Work In Progress			8/3/20	15 10:29:17 AN	Λ			
Holguin, A	Alfredo	wo as per Alfredo Hol leaks. 100-110-106-104-10 same side. 201-203-204-207-20 replaced. 208-209-110 metal re installed	3-101-lounge 8 old roof as th	old wing all or e one being		please see Alfredo	on this w	ork order	
Patricio A	guilar								
143988					11/30/2015		1		\$0.00
Medium	Work In Progress			11/3	0/2015 12:51:59	9			
Sanchez,	Raul	Monthly - La Union E to PMschedule detai		ter Readings	- Refer				
Margret Vi									
Count: 13	Work Orders	Avg. Ag	je of WO's 48	3		Total for La Unio	on ES	0	\$0.00

Selected Da WOID Priority Assigned	Building Status	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		_					
Location:	Loma Lin	ida ES					
141183	Main Building	Classroom	10/7/2015		55		\$0.00
Medium	Work In Progress		10/7/2015 7:49:11 AN	1			·
Carrasco,		In need of replacing 89 Window s 31 1/4 L please asap. I have a wo window screens #139344	screens size 28 1/4 W x				
Hector Pa	checo						
141937			10/19/2015		43		\$0.00
Medium	Work In Progress		10/19/2015 2:56:26 PM	l			
Pacheco, I	Hector	CORNER BIT FALLING OUT OF I PANEL.SNP MANAGER DOLORE					
Maritza Go	onzalez						
143209			11/6/2015		25		\$0.00
Medium	Work In Progress		11/6/2015 12:27:51 PM	l			
Pacheco, I	Hector	l need a work order number to as compressor,50ft extension cord,1 changer,small shop vac 2.5 gallor	l 1 ft light bulb				
Hector Pa	checo						
142942			11/3/2015		28		\$0.00
Medium	Work In Progress		11/3/2015 7:45:14 AN	1			
Pacheco, I	Hector	Insulate and weatherize all expos change.	ed piping do to climate				
Hector Pa	checo						
142209		Custodial	10/23/2015		39		\$0.00
Medium	Work In Progress		10/23/2015 8:09:26 AN	1			
Carbajal,	Jimmy	I'm requesting a metal long cart f	or my site thank you.				
Alfredo Am	nbriz						
142212		Custodial	10/23/2015		39		\$0.00
Medium	Work In Progress		10/23/2015 8:52:04 AN	1			
Carbajal,	Jimmy	I'm requesting a tool box set, a se hammer, needle nose players se cutters players set, a small metal wrenches, screw drivers set, drilli short and long extension drill bit	et, measuring tape, wire saw, a set of ng & driving bit set, the				
Alfredo Am	nbriz						
142912		Athletic Field	11/2/2015		29		\$0.00
Medium	Work In Progress		11/2/2015 3:50:39 PM	1			
Vasquez, .	Jose	Need assistance trouble shooting	g sprinklers.				
Hector Pa			ч				

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Loma Lin	ida ES					
143627	Main Building	Athletic Field	11/16/2015		15		\$0.00
Medium	Work In Progress		11/16/2015 11:08:33				
Ontiveros	, Guadalupe	For request from Coach Ontiveros hoops and back boards.Also 2 sho kids.I would appreciate your assis	orter hoops for smaller				
Hector Pa	checo						
143453		Athletic Field	11/12/2015		19		\$0.00
Medium	Work In Progress		11/12/2015 8:57:15 AM				
Ontiveros	, Guadalupe	Booster pump is not working.					
Guadalup	e Ontiveros						
142924	Main Building	Classroom	11/2/2015		29		\$0.00
Medium	Work In Progress		11/2/2015 3:55:16 PM				
Pacheco,	Hector	Need to replace exhaust fan moto	r room #105,108,110.				
Hector Pa	checo						
142127	Main Building	Restroom	10/21/2015		41		\$0.00
Medium	Work In Progress		10/21/2015 4:02:58 PM				
Appelzolle	er, Fred	Need to replace commode not wo 109 Ms Carley room.	rking properly in room				
Hector Pa	checo						
143644	Main Building	Classroom	11/16/2015		15		\$0.00
Medium	Work In Progress		11/16/2015 3:27:53 PM				
Ontiveros	, Joe	Stuffed sink in class room #218 re could not unclog.	moved P-Trap but				
Hector Pa							
143941	Main Building	Restroom	11/20/2015		11		\$0.00
Medium	Work In Progress		11/20/2015 3:35:02 PM				
Ontiveros	,Joe	Need assistance Unclogging lava 5th grade wing.	toryladys restroom				
Hector Pa							
140150	Main Building	Restroom (Girls)	9/17/2015		75		\$0.00
Medium	Work In Progress		9/17/2015 11:52:44 AM				
Ontiveros	, Joe	Can you please come and fix the d restroom from the front of the teach clogged up thank you.					
	nbriz						

WOID Priority Assigned	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date Tai Created Date/Time Ac	- · · · ·	Labor Hours	Costs
Location:	Loma Lin	da ES				
143844	Main Building	Restroom	11/19/2015	12		\$0.00
Medium	Work In Progress		11/19/2015 1:18:23 PM			
Ontiveros,	Joe	Need assistance to unclog 2 urina 5th 6th grade wing tried using toilet success.				
Hector Pac	checo					
143776		Portables	11/18/2015	13		\$0.00
Medium	Work In Progress		11/18/2015 12:47:53			
Ontiveros,	Joe	Electric tankless water heater in LS working I tried trouble shooting no asap per Mr Smith.				
Hector Pac	checo					
141779		Portables	10/15/2015	47		\$0.00
Medium	Work In Progress		10/15/2015 1:25:59 PM			
Ontiveros,	Joe	Spec Ed Port, - Complete installation dryer. will need hose set	on of new washer and			
Alfredo Ho	-					
143944	Main Building	Restroom	11/20/2015	11		\$0.00
Medium	Work In Progress		11/20/2015 3:37:51 PM			
Ontiveros,	Joe	Need assistance replacing flush v across teachers lounge.	alve in boys restroom			
Hector Pac	checo					
142673			11/1/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:53:47 AM			
Pacheco, H	Hector	Yearly - Loma Linda ES - Grease schedule details.	Trap - Refer to PM			
Margret Vil						
143659	Main Building	Classroom	11/16/2015	15		\$0.00
Medium	Work In Progress		11/16/2015 3:42:27 PM			
Chavez, Sa	antos	Need to replace ballast room #102	poor lighting in room.			
Hector Pag	checo					
143656	Main Building	Office	11/16/2015	15		\$0.00
Medium	Work In Progress		11/16/2015 3:40:40 PM			
Chavez, Sa	antos	Need to replace a few ballast in ma	in office.			
- ,						

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Loma Lin	ida ES					
143647	Main Building	Office	11/16/2015		15		\$0.00
Medium	Work In Progress		11/16/2015 3:32:22 PM				
Chavez, Sa	antos	Need to replace emergencyballast office.	in Principal Lawlor				
Hector Pac	checo						
143653	Main Building	Office	11/16/2015		15		\$0.00
Medium	Work In Progress		11/16/2015 3:38:13 PM				
Chavez, Sa	antos	Need to replace few ballast in assis Smith office.	tant principal Mr				
Hector Pac	checo						
139345			9/4/2015		88		\$0.00
Medium	Work In Progress	All around the	9/4/2015 9:31:04 AM				
Pacheco, H	Hector	Repaint door frames in all entrance doors.	doors and office				
Angie Flore	es						
143126	Main Building	Roof	11/5/2015		26		\$0.00
Medium	Work In Progress		11/5/2015 1:00:49 PM				
Solis, Lore	nzo	Need assistance replacing motor o #RTF-LL-001.	n Reznor Roof heater				
Hector Pac	checo						
143195			11/6/2015		25		\$0.00
Medium	Work In Progress		11/6/2015 11:22:11 AM				
Orozco, Da	niel	ICE MACHINE IS NOT MAKING ICE					
Maritza Go	nzalez						
141376			10/9/2015		53		\$0.00
Medium	Work In Progress	Kitchen	10/9/2015 2:43:55 PM				
Orozco, Da	niel	Replace drain grill in front of tilt skille inspection the drain grill should be appropriate style. Please call Cynth questions 882-6949.	replaced with an				
Cynthia Ma	aes						
136910			8/2/2015		121		\$0.00
Medium	Work In Progress		8/2/2015 12:32:02 AM				
Vallejo, Alb	pert	Yearly - Loma Linda ES Fire Ext. In to PMschedule details.	sp. (Yearly) - Refer				
Margret Vil	lalobos						

Medium Work Carrasco, Danny <u>Hector Pacheco</u> 141373 Medium Work Vallejo, Albert Albert Vallejo 143932 Medium Work Estrada, Jesus Angie Flores 142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895	Loma Lin Building In Progress	Cafeteria 10 In need of a scissor lift. Need to reach 20 f to service heating units in cafeteria. 1 Install new VCT flooring in 7 Classrooms. Classroom	10/26/2015 0/26/2015 2:01:06 PM eet or higher 10/9/2015 0/9/2015 2:16:17 PM 11/20/2015 1/20/2015 2:26:44 PM		36	
Medium Work Carrasco, Danny <u>Hector Pacheco</u> 141373 Medium Work Vallejo, Albert Albert Vallejo 143932 Medium Work Estrada, Jesus Angie Flores 142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895	In Progress	10 In need of a scissor lift. Need to reach 20 ft to service heating units in cafeteria. 1 Install new VCT flooring in 7 Classrooms. Classroom Music Portable	0/26/2015 2:01:06 PM eet or higher 10/9/2015 10/9/2015 2:16:17 PM 11/20/2015		53	\$0.00 \$0.00
Carrasco, Danny Hector Pacheco 141373 Medium Work Vallejo, Albert Albert Vallejo 143932 Medium Work Estrada, Jesus Angie Flores 142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895	< In Progress	In need of a scissor lift. Need to reach 20 ft to service heating units in cafeteria.	eet or higher 10/9/2015 10/9/2015 2:16:17 PM 11/20/2015			 \$0.00
Hector Pacheco 141373 Medium Work Vallejo, Albert Albert Vallejo 143932 Medium Work Estrada, Jesus Angie Flores 142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895	(In Progress	to service heating units in cafeteria.	10/9/2015 0/9/2015 2:16:17 PM 11/20/2015			 \$0.00
141373 Medium Work Vallejo, Albert Albert Vallejo 143932 Medium Work Estrada, Jesus Angie Flores 142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895		Install new VCT flooring in 7 Classrooms. Classroom Music Portable 11	0/9/2015 2:16:17 PM 11/20/2015			 \$0.00
Medium Work Vallejo, Albert Albert Vallejo 143932 Medium Work Estrada, Jesus Angie Flores 142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895		Install new VCT flooring in 7 Classrooms. Classroom Music Portable 11	0/9/2015 2:16:17 PM 11/20/2015			\$0.00
Vallejo, Albert Albert Vallejo 143932 Medium Work Estrada, Jesus Angie Flores 142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895		Install new VCT flooring in 7 Classrooms. Classroom Music Portable 11	11/20/2015			
Albert Vallejo 143932 Medium Work Estrada, Jesus Angie Flores 142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895	(In Progress	Classroom Music Portable 11				
143932 Medium Work Estrada, Jesus Angie Flores 142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895	In Progress	Music Portable 11				
Medium Work Estrada, Jesus Angie Flores 142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895	n Progress	Music Portable 11				
Estrada, Jesus Angie Flores 142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895	(In Progress		/20/2015 2:26:44 PM		11	\$0.00
Angie Flores 142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895		CARPET IS TORN CREATING A HAZARD				
142728 Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895		CHILDREN	FOR			
Medium Work Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895						
Orozco, Daniel Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895			11/1/2015	11/22/2015	30	\$0.00
Margret Villalobos 138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895	In Progress	11	/1/2015 12:54:24 AM			
138748 Main E Medium Work Estrada, Jesus Alfredo Ambriz 140895		Monthly-Loma Linda ES Fire Suppression to PM schedule details.	Insp Refer			
Medium Work Estrada, Jesus Alfredo Ambriz 140895			0/00/00/5			
Estrada, Jesus Alfredo Ambriz 140895	-	Classroom	8/26/2015		97	\$0.00
Alfredo Ambriz 140895	In Progress		3/26/2015 7:46:19 AM			
140895		In class room 222 the plastic the edge of the of it came of its needs to be replaced.	ecarpetpart			
			10/4/2015	10/25/2015	58	\$0.00
Medium Work	(In Progress	10)/4/2015 12:38:34 AM	10/20/2010	00	φ0.00
Vallejo, Albert	Cirri Togress	Monthly - Loma Linda ES Fire Sprinkler Ins PMschedule details.				
Margret Villalobos	S					
142706			11/1/2015	11/22/2015	30	\$0.00
Medium Work	In Progress	11	/1/2015 12:54:09 AM			
Orozco, Daniel		Monthly - Loma Linda ES Range Hood Clea to PMschedule details.	ning - Refer			
Margret Villalobos						

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time A	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Mesquite	ES					
142707			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:10 AM				
Orozco, Da	aniel	Monthly - Mesquite ES Range Ho PMschedule details.	od Cleaning - Refer to				
Margret Vi	llalobos						
142729			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:25 AM				
Orozco, Da	aniel	Monthly - Mesquite ES Fire Suppr PMschedule details.	ession Insp Refer to				
Margret Vi							
142965	Main Building		11/3/2015		28		\$0.00
Medium	Work In Progress	Main Office	11/3/2015 1:55:34 PM				
Estrada, J		Main Office need carpet repair 2 se you, Sandy	eam repair. Thank				
Sandra Mo	ora		9/2/2045		101		¢0.00
136911			8/2/2015		121		\$0.00
Medium Vallejo, All	Work In Progress bert	Yearly - Mesquite ES Fire Ext. Insp PMschedule details.	8/2/2015 12:32:03 AM b. (Yearly) - Refer to				
Margret Vi	llalobos						
143451	Main Building	Office	11/12/2015		19		\$0.00
Medium	Work In Progress	Main Office	11/12/2015 8:53:54 AM				
Marquez, (Gerardo	Need plaque to read for front doo Principal Lisa White, and also for f					
Sandra Mo	ora						
143467	Main Building		11/12/2015		19		\$0.00
Medium	Work In Progress	Portable #611	11/12/2015 9:33:56 AM				
Marquez, (Gerardo	Need a plaque for the following sta Andrews for door.	affmember only R.				
Sandra Mo							
143462	Main Building		11/12/2015		19		\$0.00
Medium	Work In Progress	Room # 612	11/12/2015 9:22:32 AM				
Marquez, (Gerardo	Need plaque for the following staff Sanchez, for door.	member only W.				
Sandra Mo	ora						

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description	Until Request Date Target Co Created Date/Time Actual Co		Labor Hours	osts
Location:	Mesquite	ES				
143463	Main Building		11/12/2015	19	\$(0.00
Medium	Work In Progress	Room # 404	11/12/2015 9:26:33 AM			
Marquez,	Gerardo	Need a plaque for the following s door.	taff only B. Herrera, for			
Sandra M	ora					
143472	Main Building		11/12/2015	19	\$0	0.00
Medium	Work In Progress	Room # 204	11/12/2015 9:54:57 AM			
Marquez,		Need a plaque for the following sta Nevarez for door.	affmember onlyG.			
Sandra M						
144001	Main Building	Office	11/30/2015	1	\$0	0.00
Medium	Work In Progress	Main Office	11/30/2015 9:05:10 AM			
Gonzales	,Camilo	As per Margarita Terrazas/Purcha needs to pick up RizoGraph copyr to warehouse.				
Sandra M						
143457	Main Building		11/12/2015	19	\$0	0.00
Medium	Work In Progress	Room # 302	11/12/2015 9:09:48 AM			
Marquez,		Need name plaque onlyfor the fol for door C, Zuloaga.	lowing staff member			
Sandra M		Classroom	11/12/2015	10	<u></u>	0.00
143465	Main Building	Classroom	11/12/2015	19	Φſ	0.00
Medium	Work In Progress	Room # 401	11/12/2015 9:29:58 AM			
Marquez,		Need a plaque for the following sta Baldauf for door.	affmemberonlyL.			
Sandra M			44/40/0045			0.00
143469	Main Building	Classroom	11/12/2015	19	\$0	0.00
Medium	Work In Progress	Room # 609	11/12/2015 9:47:02 AM			
Marquez,		Need a plaque for the following s door.	taff only S. Lerma for			
Sandra M					-	
143470	ArmyBuilding	Classroom	11/12/2015	19	\$0	0.00
Medium	Work In Progress	Portable # 608	11/12/2015 9:48:51 AM			
Marquez,	Gerardo	Need a plaque for a staff membe door.	er only K. Munoz for			
Sandra M	ora					

Selected Da WOID Priority Assigned	Building Status	Dates:7/1/2015 - 6/30/2016 Order By Area Deferred By Area Number Reason Description	Location, Status Until Request Date Targ Created Date/Time Act		Cost Labor Hours
Requeste	r Name				
Location:	Mesquite	ES			
143471	2003 Classroom	Classroom	11/12/2015	19	\$0.0
Medium	Work In Progress	Portable # 505	11/12/2015 9:53:32 AM		
Marquez,	Gerardo	Need a Plaque for the following Lawerence for door.	staff member only M.		
Sandra M					
143456	Main Building	Classroom	11/12/2015	19	\$0.0
Medium	Work In Progress	Room # 303	11/12/2015 9:07:15 AM		
Marquez,		Need a plaque made for the follo Gonzalez for door.	wing staff member J.		
Sandra M		2	11/10/2015		
143454	Main Building	Classroom	11/12/2015	19	\$0.0
Medium	Work In Progress	Room # 113	11/12/2015 9:01:36 AM		
Marquez,		Linda Al-Hanna/Art teacher need #113.	l onlyplaque with room		
Sandra M		2	11/10/2015	10	* ••••
143460	Main Building	Classroom	11/12/2015	19	\$0.0
Medium	Work In Progress	Room # 305	11/12/2015 9:13:43 AM		
Marquez,		Need a plaque onlyfor the follow Garcia for door.	ing staff member A.		
Sandra M		2	11/10/2015		
143461	Main Building	Classroom	11/12/2015	19	\$0.0
Medium	Work In Progress	Room # 301	11/12/2015 9:18:17 AM		
Marquez,		Need a plaque for the following s Munoz for door.	taffmember only V.		
Sandra M	ora		11/10/2015	40	
143838			11/19/2015	12	\$0.0
Medium	Work In Progress		11/19/2015 8:27:44 AM		
Solis, Lore	enzo	portable 608 heating unit is not w	vorking at all.		
Joe Rami	rez				
138289	Main Building	Cafeteria	8/18/2015	105	\$0.0
Medium	Work In Progress	Cafeteria	8/18/2015 4:08:23 PM		
Chavez, S	antos	Requesting, suggest power surg	ge protector ASAP.		
Sandra M	ora				
140233	Pump House	Pump House	9/18/2015	74	\$0.0
Medium	Work In Progress		9/18/2015 2:52:32 PM		
Chavez, S	antos	irrigation control boxneed to ide wires to the control system to we			
Mario Apo	daca	-			
12/1/2015	5 4:03:42 PM				Page 84 of 13

WOID Priority Assigned	Building Status	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description	Until Request Date Target Com Created Date/Time Actual Com Action	p Date Aged	Labor Hours	Costs
Requester	Name					
Location:	Mesquite	ES				
141899			10/19/2015	43		\$0.00
Medium	Work In Progress		10/19/2015 6:33:12 AM			
Chavez, Sa	antos	we have 5 parking lot/ security lig replaced.	hts out need to be			
Joe Ramir	ez					
139560			9/8/2015	84		\$0.00
Medium	Work In Progress		9/8/2015 10:14:50 AM			
Chavez, Sa	antos	we have 4 parking/security lights	that are not working			
Joe Ramir	ez					
138478	Main Building		8/21/2015	102		\$0.0
Medium	Work In Progress	Cafeteria	8/21/2015 7:53:48 AM			
Chavez, Sa	antos	outlet is loose in cafeteria.				
Sandra Mo	ora					
137278			8/5/2015	118		\$0.0
Medium	Work In Progress		8/5/2015 8:23:26 AM			
Chavez, Sa		Environmental Park - Check if it is electrical power to this area- cost				
Alfredo Ho	lguin		444/0045			<u> </u>
142685			11/1/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:53:55 AM			
Ramirez, J		Yearly - Mesquite ES - Grease Tr schedule details.	ap - Refer to PM			
Margret Vil 142969	lalobos		11/3/2015	28		\$0.00
	Mark In Drograda			20		φ0.00
Medium	Work In Progress		11/3/2015 3:16:43 PM			
Appelzolle	r, Fred	need to install small elec. water h rm. 505.	eater in early childhood			
Joe Ramir	ez					
136170	2003 Classroom	Hallway/Corridor	7/20/2015	134		\$0.00
Medium	Work In Progress	E Wing	7/20/2015 3:59:34 PM			
Marquez, (Gerardo	Need staff name plaque's for the f Munoz, L. Baldauf, C. Zuloaga, G M. Martinez. Thank you, Sandy				
Sandra Mo	ora					
142284			10/26/2015	36		\$0.00
Medium	Work In Progress		10/26/2015 8:11:31 AM			
Ramirez, J	loe	need to replace u shaped lightbul	bs in the e and f wing			
Joe Ramir			-			
	4:03:42 PM				Page	35 of 13

002 -			1091633 (1	1304	i cai j				Total
Selected Da WOID Priority Assigned	ate Range for Request Building Status To	Dates:7/1/2015 - 6 Area Area Number Description	Deferred By	Until	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requeste	r Name								
Location:	Mesquite	ES							
143986					11/30/2015		1		\$0.00
Medium	Work In Progress			11/30)/2015 12:51:58	3			
Apodaca,	Mario	Monthly - Mesq Refer to PMsch	uite ES - Monthly Me nedule details.	ter Readings	-				
Margret Vi	llalobos								
Count: 31	Work Orders	A	vg. Age of WO's 40	0		Total for Mesqui	te ES	0	\$0.00

WOID Priority Assigned 7 Requester			Deferred By	Until	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	North Val	ley ES							
143781					11/18/2015		13		\$0.00
Medium	Work In Progress			11/18/20)15 1:37:54 PM				
Vega, Dan	ny	assistin raised danny v)	garden projectat n	ve(dannym joe	r				
Danny Veg	ja								
143643					11/16/2015		15		\$0.00
Medium	Work In Progress			11/16/20	15 3:25:43 PM				
Carrasco,	Danny	need 3 bx ceiling	tiles (attention Da	nny)					
Danny Veg	ja								
142953		Athletic Field			11/3/2015		28		\$0.00
Medium	Work In Progress			11/3/201	5 10:31:01 AM	I			
Ontiveros,	Guadalupe	Need Soccer G	oal Nets-(2)-20ft L	x 8ft H x 6ft D					
Gloria Rey	/es								
136000		Cafeteria			7/16/2015		138		\$0.00
High	Work In Progress			7/16/20	015 1:32:41 PM	1			
Solis, Lore	enzo	Wash all window	vs inside and out (cafeteria)					
Jesus Esti	rada								
142684					11/1/2015		30		\$0.00
Medium	Work In Progress			11/1/201	5 12:53:55 AM	I			
Vega, Dan	ny	Yearly - North Va schedule details	alley ES - Grease ⁻	Trap - Refer to	PM				
Margret Vil	lalobos								
143541		Office			11/13/2015		18		\$0.00
Medium	Work In Progress			11/13	/2015 10:03:55	1			
Appelzolle	r, Fred	unless it is left ru wasteful and ke Please can a sn	ce at NVE does no unning for 5 minute eps student from g nall hot water heate olleen Runyan, RN	s. This is very oing back to cla br be put in unde	ISS.				
Colleen R	unyan								
143843					11/19/2015		12		\$0.00
Medium	Work In Progress			11/19	/2015 11:49:18				
Appelzolle	r, Fred	water leak on 4 ck out/ ne fence	inch shut off valve line	by back flows/p	blease				
Danny Veg	a								

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	North Va	lley ES				
143556		11/13/2015		18		\$0.00
Medium	Work In Progress	11/13/2015 1:44:13 PM				
Appelzolle	r, Fred	rm 104 restroom toilet object stuck -need small snake (used auger on it)please help-wont flush				
Danny Veg	ja					
142541		10/29/2015		33		\$0.00
Medium	Work In Progress	10/29/2015 10:30:21				
Appelzolle	r, Fred	nurses office/hot water takes to long to deliver/need to run faucet open for a long time.Need small 3 gal water heater for nurses to have hot water at all times				
Danny Veg	ja					
141189		10/7/2015		55		\$0.00
Medium	Work In Progress	10/7/2015 8:35:13 AV	l			
Chavez, Sa	antos	exterior bldg. lighting have 14 (dome type)lamps that are out thru out bdlg please ck to order bulbs if not in stock				
Danny Veg	ja					
141341		10/9/2015		53		\$0.00
Medium	Work In Progress	10/9/2015 7:25:07 AV	l			
Chavez, Sa	antos	emergency ballast out in hallway(pecan valley) by rm 201-205-211-rio grand wing by rm 305 -402-				
Danny Veg	ja					
143845		Hallway/Corridor 11/19/2015		12		\$0.00
Medium	Work In Progress	11/19/2015 1:28:39 PM				
Chavez, Sa	antos	We need 3 more electrical outlets installed for our copiers by our office area. Per the service tech need to make sure there is enough amperage per outlet to support copier. Min. of 25 amps.				
Gloria Rey	es					
143980		11/30/2015		1		\$0.00
Medium	Work In Progress	11/30/2015 12:51:53				
Vega, Dan	ny	Monthly - North Valley ES A16 (Fan Exhst)(S.Ann.) - Refer to PMschedule details.				
Margret Vil	lalobos					
140342		9/21/2015		71		\$0.00
Medium	Work In Progress	9/21/2015 3:48:33 PM	1			
Orozco, Da	niel	AS PER HEALTH INSPECTION REPORT 9/10/15, WALK IN FLOOR PANEL COMING UP , REPLACE RUBBER BOTTOM SPACES AS THEY START TO CRUBMLE.				
Maritza Go	nzalez					

WOID Priority Assigned	Building Status	Dates:7/1/2015 - 6/30/2016 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		·					
Location:	North Va	lley ES					
143994		Custodial	11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 7:40:49 AM	1			
Carbajal,	Jimmy	MR. JIMMY, CAN YOU PLEASE GE PROPONE GAS FOR THE BUFFEF THANK YOU.					
Luis Solis							
143925		Custodial	11/20/2015		11		\$0.00
Medium	Work In Progress		11/20/2015 11:43:58	6			
Carbajal,	Jimmy	WE NEED SERVICE FOR (3) VACU CLEANERS .,1:20002250,.2:DOS 3:P5800000242., NO POWER IN T ONE THE TUBE IS BROKEN., THA	A00005379 AND WO AND THE LAST				
Luis Solis							
136912			8/2/2015		121		\$0.00
Medium	Work In Progress		8/2/2015 12:32:03 AN	1			
Vallejo, All	bert	Yearly - North Valley ES Fire Ext. Insto PMschedule details.	sp. (Yearly) - Refer				
Margret Vi	llalobos		/ / /				
142696			11/1/2015		30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:03 AM	1			
Orozco, Da	aniel	Monthly - North Valley ES - Range H Refer to PMschedule details.	Hood Cleaning -				
Margret Vi	llalobos						
135293			7/5/2015		149		\$0.00
Medium	Work In Progress		7/5/2015 12:30:36 AM	1			
Vallejo, All	bert	Monthly - North Valley ES - Fire Pur PMschedule details.	np Engine - Refer to				
Margret Vi	llalobos						
140871			10/4/2015		58		\$0.00
Medium	Work In Progress		10/4/2015 12:38:18 AM	1			
Vallejo, All	bert	Monthly - North Valley ES - Fire Pur PMschedule details.	np Engine - Refer to				
Margret Vi	llalobos						
140900			10/4/2015		58		\$0.00
Medium	Work In Progress		10/4/2015 12:38:37 AM	1			
Vallejo, All	bert	Monthly - North Valley ES - Fire Spr to PMschedule details.	inkler Insp Refer				
Margret Vi	llalobos						

002 -			Togress	(1 150a)	i eai j				Total
WOID Priority Assigned		Dates:7/1/2015 - 6 Area Area Number Description	Deferred By	Until	Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	r Name North Val	lley ES							
142731		-			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress			11/1/2	015 12:54:26 AN	1			
Orozco, Da	aniel	Monthly - North to PMschedule	n Valley ES Fire Suj e details.	opression Ins	p Refer				
Margret Vi	llalobos								
143975					11/24/2015		7		\$0.00
Medium	Work In Progress			11/	24/2015 12:34:40)			
Vega, Dar	ny	Daily - North Va PMschedule d	alley ES - Fire Pum etails.	p (Biweekly)	- Refer to				
Margret Vi	llalobos								
Count: 23	Work Orders	Δ	vg. Age of WO's	42		Total for North Valle	ey ES	0	\$0.00

Selected Da WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Labor Aged Hours	Costs
Location:		On-Track Pre-K (LM)				
136927			8/2/2015	8/13/2015	121	\$0.00
Medium	Work In Progress		8/2/2015 12:32:12 AM	1		
Vallejo, Alt	-	Yearly - Northern Pre-K Fire Ext. I to PMschedule details.	nsp. (Yearly) - Refer			
Margret Vil	llalobos					
144002		Office	11/30/2015		1	\$0.00
Medium	Work In Progress		11/30/2015 9:18:48 AM	1		
Gonzales,	Camilo	Pick up obsolete items and deliv disposal. Thank you.	er to IM/PPD for			
Theresa R	Ramirez					
143979			11/30/2015		1	\$0.00
Medium	Work In Progress		11/30/2015 12:51:52	2		
Vega, Dan	iny	Monthly - Northern Pre-K A16(Far Refer to PMschedule details.	n Exhst)(S. Annual) -			
Margret Vil	llalobos					
142549			10/29/2015		33	\$0.00
Medium	Work In Progress		10/29/2015 11:57:13	\$		
Marquez, (Gerardo	having trouble locking and unlock you could please take a look at it				
Brian Pach	neco					
143433			11/10/2015		21	\$0.00
Medium	Work In Progress		11/10/2015 4:16:24 PN	I		
Marquez, C	Gerardo	need room 108 switched to maste	er (F) key			
Brian Pach	neco					
140486	Main Building	Athletic Field	9/23/2015		69	\$0.00
Medium	Work In Progress	outside	9/23/2015 1:57:54 PN	1		
Ontiveros,	Guadalupe	There is a new canopy in our cafe set up where our sandboxis for th not have appropriate shade to be located and they are digging holes	e students. Theydo where the sand is	9/29/15 - Asp Albert	, route to Grounds	
Concepcio	on Montalvo					
139406	Main Building	Storage	9/4/2015		88	\$0.00
Medium	Work In Progress		9/4/2015 4:14:10 PM	1		
Herrera, Ja	aime	We need for the storage shed that playground moved to the staff parl a slab of cement. We need it mov accessibility.	king lot where there is			
Concepcio	on Montalvo					

002 -			iogiess (riscai	rear)				Tota
Selected Da WOID Priority Assigned Requester			Deferred By	Until	-	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Northern	On-Track Pre-K	(LM)						
140484	Main Building	Athletic Field			9/23/2015		69		\$0.00
Medium	Work In Progress	outside		9/23/2	2015 1:53:08 PM				
Herrera, J	aime		og playhouse on the uld like moved close						
Concepcie	on Montalvo								
142800					11/1/2015	11/9/2015	30		\$0.00
Medium	Work In Progress			11/1/20	015 12:55:12 AM				
Vega, Dar	nny	Monthly - La Me PMschedule de	esa ES Exit Sign Ins etails.	p: Monthly - F	Refer to				
Margret Vi	illalobos								
143985					11/30/2015		1		\$0.00
Medium	Work In Progress			11/3	0/2015 12:51:57				
Apodaca,	Mario	Monthly - North Refer to PMsch	ern Pre-K - Monthly edule details.	Meter Readi	ngs -				
Margret Vi	illalobos								
Count: 10	Work Orders	A	vg. Age of WO's 4	3	Total for Northe	rn On-Track Pre-K	(LM)	0	\$0.00

		Area Number Reason Created Date/Time Actual Com Description Action	-	Hours	
Location:	Physical	Plant Complex			
143987		11/30/2015	1		\$0.00
Medium Work In P	rogress	11/30/2015 12:51:58			
Apodaca, Mario		Monthly - PPD/GHS - WW Monthly Sampling - Refer to PMschedule details.			
Margret Villalobos					
138657		8/25/2015	98		\$0.00
Medium Work In P	rogress	8/25/2015 8:53:15 AM			
Apodaca, Mario		stainless steel fittings for the new UV system at the wastewater plant at ppd also to be installed			
Mario Apodaca					
141679		10/14/2015	48		\$0.00
Medium Work In P	rogress	10/14/2015 11:21:22			
Carrasco, Danny		Move maintenance distribution from old warehouse to new.			
Albert Vallejo					
142780		11/1/2015	30		\$0.00
Medium Work In P	rogress	11/1/2015 12:54:59 AM			
Carrasco, Danny		Monthly - PPD - Fueling Station Monthly Inspection - Refer to PMschedule details.			
Margret Villalobos					
142964		11/3/2015	28		\$0.00
Medium Work In P	rogress	11/3/2015 1:42:59 PM			
Ronquillo, Ruben		ORDER WIRE DECKING AND 96" ORANGE BEAMS FOR NEW WHS. THANK YOU			
Ruben Ronquillo					
143626		11/16/2015	15		\$0.00
Medium Work In P	rogress	11/16/2015 11:00:58			
Ronquillo, Ruben		NEED TWO SIGNS FOR CUSTODIAL WHSE BACK DOOR:			
		EXIT ONLY ALL VISITORS MUST ENTER THROUGH FRONT ENTRANCE (TO BE PLACED ON OUTSIDE OF DOOR)			
		DOOR MUST REMAIN CLOSED AT ALL TIMES (TO BE PLACED ON INSIDE OF DOOR)			
Alfredo Holguin					

WOID Priority Assigned 7 Requester	Building Status Fo	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Physical	Plant Complex					
143558			11/13/2015		18		\$0.00
Medium	Work In Progress		11/13/2015 2:59:11 PN	l			
Carrasco,	Danny	need 3 plastic wheel barrels for ghat teatment plant to dispose of all ba					
Mario Apoc	daca						
144104	Purchasing		12/1/2015		0		\$0.00
Medium	Work In Progress		12/1/2015 1:24:50 PM	1			
Herrera, Ma		Need to repair broken water line, le box.	aking onto electrical				
Theresa R	amirez		44/5/0045				*• • • •
143127			11/5/2015	_	26		\$0.00
Medium	Work In Progress		11/5/2015 1:08:36 PN	1			
Duran, Fer		NEED 2 NEW FRONT OFFICES C BOTTOM	CLEANED TOP TO				
Alfredo Ho	-	0#	40/00/0045				<u> </u>
142587	Main Warehouse	Office	10/29/2015		33		\$0.00
High	Work In Progress		10/29/2015 3:49:34 PN				
Duran, Fer	nanda	Clean all the light fixtures in the old	mail room.				
Jesus Estr							
142595	Main Warehouse	Office	10/29/2015		33		\$0.00
High	Work In Progress		10/29/2015 3:54:21 PN	l			
Duran, Fer	nanda	Shower scrub floors in the old mail hallwaybehind Mary's new office.W room and small hallwaybehind Ma are new floors and will require 7 co	/axfloors in old mail Iry's new office. These				
Jesus Estr	rada						
142641			10/30/2015		32		\$0.00
Medium	Work In Progress		10/30/2015 3:50:04 PN	I			
Vallejo, Alb	pert	Repair roof leak above records offic	ce.				
Albert Valle	ejo						
142376	Purchasing		10/27/2015		35		\$0.00
Medium	Work In Progress		10/27/2015 9:18:09 AM	1			
Carbajal, J Alfredo Ho	-	Custodial Wash room - Dryer need Noisy	ls maintenance ,	10/30/15 - Asp Albe	rt, route to	Jimmy	

WOID Priority Assigned 7 Requester	Building Status Fo	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex						
143712	Motor Vehicle			11/17/2015		14		\$0.00
Medium	Work In Progress			11/17/2015 3:09:06 PM				
Flores, Pet	e	the service ligh changed on tru	t indicator at the moto ck 38	or oil needs to be				
Mario Apoc	daca							
144084	Motor Vehicle			12/1/2015		0		\$0.00
Medium	Work In Progress	equip#0908		12/1/2015 9:55:39 AM				
Flores, Pet	e	please replace	gator's broken tailga	atestraps				
Pete Flores	S							
143373		Athletic Field		11/10/2015		21		\$0.00
Medium	Work In Progress			11/10/2015 8:55:19 AM				
Flores, Pet	e	goose neck tria	ler need tire replace	d.				
Guadalupe	e Ontiveros							
143557	Motor Vehicle			11/13/2015		18		\$0.00
Medium	Work In Progress	vehicle#181		11/13/2015 1:49:17 PM				
Flores, Pet	e	check engine li	ght illuminated, plea	se check and advise				
Pete Flores	S							
143608				11/16/2015		15		\$0.00
Medium	Work In Progress			11/16/2015 7:39:41 AM				
Flores, Pet	e		lease check out engi ears in the instrumer					
David Villa								
142875	Motor Vehicle			11/2/2015		29		\$0.00
Medium	Work In Progress			11/2/2015 1:08:58 PM	l			
Ruiz, Maria	a	vehicle 172 nee	eds clear coat on hoc	od.				
Maria Ruiz								
142876	Motor Vehicle			11/2/2015		29		\$0.00
Medium	Work In Progress			11/2/2015 1:11:08 PM	I			
Ruiz, Maria	3	veh 120 needs bumper and tai	a handle on tail gate I gate.	and paint front				
Maria Ruiz								<u> </u>
143413	Motor Vehicle			11/10/2015		21		\$0.00
Medium	Work In Progress			11/10/2015 3:52:24 PM				
Ruiz, Maria	a	vehicle 58 nee	ds a new windshield					
Salvador G	Gonzalez							

WOID Priority Assigned ⁻ Requester		Area Deferred By Area Number Reason Description	Until Request Date Targ Created Date/Time Act		Labor Hours	Costs
Location:		Plant Complex				
144013	Motor Vehicle		11/30/2015	1		\$0.00
Medium	Work In Progress		11/30/2015 11:21:00			
Ruiz, Maria	-	vehicle 41 was damaged during t Bailey)	he weekend driver(Ken			
Maria Ruiz	2					
143096			11/5/2015	26		\$0.00
Medium	Work In Progress		11/5/2015 8:13:45 AM			
Herrera, M	ario	Window in the construction office off its track on the right side of the Dominique for information				
Dominique	e Esparza					
143920			11/20/2015	11		\$0.00
Medium	Work In Progress		11/20/2015 10:56:11			
Herrera, M	ario	Maria S. Office - Install blinds				
Alfredo Ho	lguin					
143174	Motor Vehicle		11/6/2015	25		\$0.00
Medium	Work In Progress	vehicle#135	11/6/2015 8:08:25 AM			
Flores, Pe	te	please check exhaust system da service	mage, and any required			
Pete Flore	S					
143131			11/5/2015	26		\$0.00
Medium	Work In Progress	FEDERAL	11/5/2015 3:03:16 PM			
Flores, Pe		Car shakes when driving long dis speed is high.	tances, when the			
Noemi Du	ron Maintenanœ		11/6/2015	25		¢0.00
143226				25		\$0.00
Medium	Work In Progress		11/6/2015 2:34:46 PM			
Flores, Pe		vehicle 15 needs a drivers rear le	ns			
Maria Ruiz						
143202	Motor Vehicle		11/6/2015	25		\$0.00
Medium	Work In Progress	vehicle#54	11/6/2015 11:33:49 AM			
Flores, Pe	te	please check for any required ma	intenance			
Pete Flore						A -
142146	Motor Vehicle		10/22/2015	40		\$0.00
Medium	Work In Progress	EQUIP.#0408	10/22/2015 10:35:13			
Flores, Pe		PLEASE CHECK CHS 735 MOW STARTING CONDITION. CHECK				
Pete Flore	S					

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2015 - 6/30/2016 Order By Loo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex					
142200			10/22/2015		40		\$0.00
Medium	Work In Progress	FEDERAL	10/22/2015 3:59:11 PM				
Flores, Pet	e	BREAK PADS GIVING OUT.					
Noemi Du	ron						
142293			10/26/2015		36		\$0.00
Medium	Work In Progress	FEDERAL	10/26/2015 10:08:09				
Flores, Pet	e	CHECK TRANSMITION LIGHT ON					
Noemi Du	ron						
142372	Motor Vehicle		10/27/2015		35		\$0.00
Medium	Work In Progress		10/27/2015 9:10:35 AM				
Flores, Pet	e	vehicle 47 driver's window wouldn't door doesn't open from inside.	goup;passenger				
Maria Ruiz			10/07/00/5				* •••••
142374	Motor Vehicle		10/27/2015		35		\$0.00
Medium	Work In Progress		10/27/2015 9:12:26 AM				
Flores, Pet		vehicle 148 right quarter light is ou	t in front				
Maria Ruiz			8/14/2015		109		\$0.00
138057					109		\$0.00
Medium	Work In Progress	Federal Vehicle	8/14/2015 1:48:15 PM	I			
Flores, Pet		NEEDS OIL CHANGE					
Noemi Du	ron Motor Vehicle		8/14/2015		109		\$0.00
138059					109		Ф 0.00
Medium	Work In Progress	FEDERAL	8/14/2015 2:03:43 PM	I			
Flores, Pet		VEHICLE HAS A STRONG GASOL	INE ODOR.				
Noemi Du 141738	ron		10/14/2015		48		\$0.00
Medium	Work In Progress		10/14/2015 3:50:55 PM		40		ψ0.00
	-		10/14/2015 5.50.55 PW				
Flores, Pet		THE A/C IS NOT FUNCTIONING					
Santos Ch 141741	avez		10/14/2015		48		\$0.00
					40		ψ0.00
Medium	Work In Progress		10/14/2015 3:52:13 PM				
Flores, Pet	e	NEED STEP TO GET INTO THE TR	RUCK				

WOID Priority Assigned		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	Name							
Location:	Physical	Plant Complex						
141992	Motor Vehicle			10/20/2015		42		\$0.00
Medium	Work In Progress	vehicle #128		10/20/2015 10:26:37				
Flores, Pe	te	charging syster advise	n not working to sp	ecs, please check and				
Pete Flore								
142005	Motor Vehicle			10/20/2015		42		\$0.00
Medium	Work In Progress	vehicle#111		10/20/2015 1:10:20 PM	l			
Flores, Pe	te	worn battery, pl	ease replace					
Pete Flore	S							
141379	Motor Vehicle			10/9/2015		53		\$0.00
Medium	Work In Progress			10/9/2015 3:12:59 PM	1			
Flores, Pe	te	vehicle 120 Ag. cylinder	truck (Shane Sm)	the) broken ignition				
Pete Flore	s			- / - / - / - / - / - / - / - / - / - /				
140137				9/17/2015		75		\$0.00
Medium	Work In Progress			9/17/2015 11:09:20 AN	1			
Flores, Pe	te	vehicle #21 nee	d spare key					
Pete Flore								
140148	Motor Vehicle			9/17/2015		75		\$0.00
Medium	Work In Progress			9/17/2015 11:31:24 AN	1			
Flores, Pe	te	Tune and repai	r District Warehous	se van #11				
Enrique Bi	riones							
139799				9/11/2015		81		\$0.00
Medium	Work In Progress			9/11/2015 10:51:19 AN	1			
Flores, Pe	te	Check electric b	orakes on unit 075	1				
Guadalup	e Ontiveros							
138345	Motor Vehicle			8/19/2015		104		\$0.00
Medium	Work In Progress			8/19/2015 3:24:08 PM	1			
Flores, Pe	te	veh 29change	e ignition key cylind	der				
Pete Flore	S							
138392	Motor Vehicle			8/20/2015		103		\$0.00
Medium	Work In Progress			8/20/2015 8:39:05 AN	1			
Flores, Pe	-	accompressor	doesn'twork; mak	es a lot of noise				
Pete Flore								

Decision: Physical Plant Complex 136734 Motor Vehicle 7/30/2015 124 136734 Motor Vehicle 7/30/2015 124 Medium Work In Progress 7/30/2015 10:17:35 AM Flores, Pete vehicle 186 needs brakes and right/river's side window doesn't roll down reported by Joe Vasquez Maria Maria Ruiz 10/19/2015 43 141935 10/19/2015 2:49:46 PM Marquez, Gerardo AS PER MR, CHAVEZ, ALL NORTHERN KITCHENS Marquez, Gerardo AS PER MR, CHAVEZ, ALL NORTHERN KITCHENS Marquez, Gerardo AS PER MR, CHAVEZ, ALL NORTHERN KITCHENS Marquez, Gerardo AS PER MR, CHAVEZ, ALL NORTHERN KITCHENS Marquez, Gerardo AS PER MR, CHAVEZ, ALL NORTHERN KITCHENS Marquez, Gerardo AS PER MR, CHAVEZ, ALL NORTHERN KITCHENS Marquez, Gerardo AS PER MR, CHAVEZ, ALL NORTHERN KITCHENS Marquez, Gerardo AS PER MR, CHAVEZ, ALL NORTHERN KITCHENS Marquez 11/13/2015 18 Solis, Lorenzo The heaters in the Instructional Materials Warehouse need to be service. The one in the north side is not working. Thank you. Solis, Lorenzo	WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By I Area Deferred By Area Number Reason Description	Until Request Date Tar Created Date/Time Act	· · · · ·	Labor Hours	Costs
Medium Work In Progress 7/30/2015 10:17:35 AM Flores, Pete wehide 186 needs brakes and right driver's side window doesn'troil down reported by Joe Vasquez Maria Ruiz 10/19/2015 141335 0/19/2015 2:49:46 PM Marquez, Gerardo AS PER MR, CHAVEZ, ALL NORTHERN KITCHENS NEED TO BE REKEYED. Maritza Gonzalez 0/fice 143359 Office 11/13/2015 18 Medium Work In Progress The heaters in the Instructional Materials Warehouse need to be service. The one in the north side is not working. Thank you. Theresa Ramirez 11/10/2015 143352 Need heating turned on. Cynthia Maes 11/10/2015 Cynthia Maes 10/30/2015 4:28:07 PM Solis, Lorenzo Need heating turned on. Cynthia Maes 10/30/2015 4:28:07 PM Solis, Lorenzo Need heating turned on. Cynthia Maes 10/30/2015 4:28:07 PM Solis, Lorenzo NEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS Gerardo Marquez 11/16/2015 1:30:44 PM Kedium Work In Progress 7/24/2015 7:52:42 AM Gastillo, Carlos Material Istforstock. Carlos Castillo 11/16/2015 1:30:44 PM Herring I, Maring A, POSSIBLE 11/16/2	Location:	Physical	Plant Complex				
Flores, Pete wehicle 186 needs brakes and right driver's side window deesn'troll down reported by Joe Vasquez Maria Ruiz 10/19/2015 141935 10/19/2015 2:49.46 PM Mariquez, Gerardo AS PER MR. CHAVEZ, ALL NORTHERN KITCHENS NEED TO BE REKEYED. Maritza Gonzalez AS PER MR. CHAVEZ, ALL NORTHERN KITCHENS NEED TO BE REKEYED. Maritza Gonzalez Office 11/13/2015 18 Madium Work In Progress Solis, Lorenzo The heaters in the Instructional Materials Warehouse need to be senice. The one in the north side is not working. Thank you. Theresa Ramirez 11/10/2015 4:10:47 PM Vedium Work In Progress Receiving Need heating turned on. 10/30/2015 4:28:07 PM Solis, Lorenzo NEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS. Gerardo Marquez Electrical Room 7/24/2015 7:52:42 AM Castillo, Carlos Make material listfor stock. Castillo, Carlos Make material listfor stock. Castillo, Carlos Make material listfor stock. Castillo 11/6/2015 1:30:44 PM Herrar, Mario NEED TO FINISH PANTING JULIES NEW OFFICE AS SOON AS POSSIBLE	136734	Motor Vehicle		7/30/2015	124		\$0.00
Maria Ruiz	Medium	Work In Progress		7/30/2015 10:17:35 AM			
141935 10/19/2015 43 Medium Work In Progress 10/19/2015 2:49:46 PM Marquez, Gerardo AS PER MR. CHAVEZ, ALL NORTHERN KITCHENS NEED TO BE REKEYED. Maritza Gonzalez 11/13/2015 143539 Office 11/13/2015 9:58:46 AM Solis, Lorenzo The heaters in the Instructional Materials Warehouse need to be service. The one in the north side is not working. Thank you. Theresa Ramirez 11/13/2015 21 Medium Work In Progress Receiving 11/10/2015 21 Need heating turned on. Cynthia Maes 10/30/2015 11/2666 10/30/2015 Solis, Lorenzo NEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS. Gerardo Marquez 136406 Maintenance Electrical Room 7/24/2015 136405 11/6/2015 7:52:42 AM Casillo, Caitos Make material listfor stock. Carlos Castillo 11/6/2015 1:30:44 PM Herrera, Mario NEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	Flores, Pe	te					
Medium Work In Progress 10/19/2015 2:49.46 PM Marquez, Gerardo AS PER MR. CHAVEZ, ALL NORTHERN KITCHENS NEED TO BE REKEYED. Maritza Gonzalez	Maria Ruiz	2					
Marquez, Gerardo AS PER MR. CHAVEZ, ALL NORTHERN KITCHENS NEED TO BE REKEYED. Maritza Gonzalez 11/13/2015 143539 Office 11/13/2015 9:58:46 AM Medium Work In Progress The heaters in the Instructional Materials Warehouse need to be service. The one in the north side is not working. Thank you. The resaters in the Instructional Materials Warehouse need to be service. The one in the north side is not working. Thank you. Theresa Ramirez 11/10/2015 21 Solis, Lorenzo Need heating turned on. 21 Cynthia Maes 10/30/2015 32 142656 10/30/2015 32 Medium Work In Progress 10/30/2015 4:28:07 PM Solis, Lorenzo NEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS. Gerardo Marquez 11/6/2015 7:52:42 AM 2136405 Maintenance Electrical Room 7/24/2015 7:52:42 AM Castillo, Carlos Make material list for stock. Carlos Castillo 11/6/2015 1:30:44 PM Herrera, Mario NEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	141935			10/19/2015	43		\$0.00
MARIZZ GONZAIEZ Haritza Gonzalez 143539 Office 11/13/2015 18 Medium Work In Progress 11/13/2015 5.82.46 AM 11/13/2015 18 Solis, Lorenzo The heaters in the Instructional Materials Warehouse need to be service. The one in the north side is not working. Thank you. The heaters in the Instructional Materials Warehouse need to be service. The one in the north side is not working. Thank you. 11/10/2015 21 Hedium Work In Progress Receiving 11/10/2015 21 Medium Work In Progress Receiving 11/10/2015 21 Solis, Lorenzo Need heating turned on. 2 2 Cynthia Maes 10/30/2015 32 32 Medium Work In Progress NEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS. 32 Gerardo Marquez 130 33 33 Gerardo Maintenance Electrical Room 7/24/2015 130 Medium Work In Progress Make material list for stock. 25 Carlos Castillo 11/6/2015 130<	Medium	Work In Progress		10/19/2015 2:49:46 PM			
143539Office11/13/201518MediumWork In Progress11/13/2015 9:58:46 AM18Solis, LorenzoThe heaters in the Instructional Materials Warehouse need to be service. The one in the north side is not working. Thank you.11/10/2015Theresa Ramirez11/10/201521143432Purchasing11/10/2015 4:10:47 PMSolis, LorenzoNeed heating turned on.Cynthia Maes10/30/20153214265610/30/2015 4:28:07 PMSolis, LorenzoNEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS.Gerardo Marquez130136405MaintenanceElectrical Room7/24/2015 7:52:42 AM130Castillo, CarlosMake material listfor stock.Carlos Castillo11/6/2015 1:30:44 PMHerrera, MarioNEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	Marquez, (Gerardo		THERN KITCHENS			
Medium Work In Progress 11/13/2015 9:58:46 AM Solis, Lorenzo The heaters in the Instructional Materials Warehouse need to be service. The one in the north side is not working. Thank you. Theresa Ramirez 11/10/2015 143432 Purchasing 11/10/2015 4:10:47 PM Solis, Lorenzo Need heating turned on. 21 Cynthia Maes 10/30/2015 4:28:07 PM 32 Medium Work In Progress NEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS. 32 Gerardo Marquez 136405 Maintenance 130 Medium Work In Progress Flectrical Room 7/24/2015 7:52:42 AM Castillo, Carlos Make material list for stock. 11/6/2015 1:30:44 PM Herrera, Wario NEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE SOON AS POSSIBLE		onzalez					
Solis, Lorenzo The heaters in the Instructional Materials Warehouse need to be service. The one in the north side is not working. Thank you. Thereas Ramirez 143432 Purchasing 11/10/2015 21 Medium Work In Progress Receiving 11/10/2015 4:10:47 PM 21 Solis, Lorenzo Need heating turned on. Need heating turned on. 21 Cynthia Maes 10/30/2015 4:28:07 PM 32 Medium Work In Progress 10/30/2015 4:28:07 PM 32 Solis, Lorenzo NEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS. Service	143539		Office	11/13/2015	18		\$0.00
need to be service. The one in the north side is not working. Thank you. Theresa Ramirez Theresa Ramirez 11/10/2015 21 143432 Purchasing 11/10/2015 4:10:47 PM 21 Medium Work In Progress Receiving 11/10/2015 4:10:47 PM 21 Solis, Lorrazo Need heating turned on. 10/30/2015 4:28:07 PM 32 Medium Work In Progress 10/30/2015 4:28:07 PM 32 Solis, Lorrazo NEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS. Secretardon and the secretary of t	Medium	Work In Progress		11/13/2015 9:58:46 AM			
143432Purchasing11/10/201521MediumWork In ProgressReceiving11/10/2015 4:10:47 PMSolis, LorenzoNeed heating turned on.Cynthia Maes14265610/30/201532MediumWork In Progress10/30/2015 4:28:07 PMSolis, LorenzoNEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS.Gerardo Marquez136405MaintenanceElectrical Room7/24/2015130MediumWork In Progress7/24/2015 7:52:42 AMCastillo, CarlosMake material list for stock.Carlos Castillo11/6/201525MediumWork In Progress11/6/2015Hazit711/6/20151:30:44 PMHerrera, MarioNEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLENEED TO SINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	Solis, Lore	enzo	need to be service. The one in t				
MediumWork In ProgressReceiving11/10/2015 4:10:47 PMSolis, LorenzoNeed heating turned on.Cynthia Maes14265610/30/201514265610/30/2015 4:28:07 PMSolis, LorenzoNEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS.Gerardo Marquez136405MaintenanceElectrical Room7/24/2015 7:52:42 AMCastillo, CarlosMake material list for stock.Carlos Castillo11/6/2015 1:30:44 PMHerrera, MarioNEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	Theresa R						
Solis, Lorenzo Need heating turned on. Cynthia Maes 142656 10/30/2015 32 Medium Work In Progress 10/30/2015 4:28:07 PM Solis, Lorenzo NEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS. Gerardo Marquez 136405 Maintenance Electrical Room 7/24/2015 130 Medium Work In Progress 7/24/2015 7:52:42 AM Castillo, Carlos Make material list for stock. Carlos Castillo 143217 11/6/2015 1:30:44 PM Herrera, Mario NEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	143432	Purchasing		11/10/2015	21		\$0.00
Cynthia Maes 10/30/2015 32 142656 10/30/2015 4:28:07 PM 32 Medium Work In Progress 10/30/2015 4:28:07 PM Solis, Lorenzo NEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS. Image: Construct of the second of	Medium	Work In Progress	Receiving	11/10/2015 4:10:47 PM			
14265610/30/201532MediumWork In Progress10/30/2015 4:28:07 PMSolis, LorenzoNEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS.Gerardo Marquez136405MaintenanœElectrical Room7/24/2015130MediumWork In ProgressMake material list for stock.Carlos Castillo14321711/6/2015123MediumWork In Progress11/6/20151:30:44 PMHerrera, MarioNEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	Solis, Lore	enzo	Need heating turned on.				
Medium Work In Progress 10/30/2015 4:28:07 PM Solis, Lorenzo NEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS. Gerardo Marquez 136405 136405 Maintenanœ Electrical Room 7/24/2015 Medium Work In Progress Additional de material list for stock. 130 Castillo, Carlos Castillo Make material list for stock. 143217 11/6/2015 25 Medium Work In Progress 11/6/2015 130 Medium Work In Progress 25 Medium Work In Progress 11/6/2015 25 Medium Work In Progress 11/6/2015 25 Medium Work In Progress 11/6/2015 25	Cynthia Ma	aes					
Solis, Lorenzo NEED HEATING AND COOLING DUCT AND REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS. Gerardo Marquez 136405 136405 Maintenance Electrical Room 7/24/2015 7:52:42 AM Castillo, Carlos Make material list for stock. Carlos Castillo 11/6/2015 143217 11/6/2015 Medium Work In Progress Medium Work In Progress 143217 11/6/2015 Medium Work In Progress Medium NEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	142656			10/30/2015	32		\$0.00
REGISTERS INSTALLED IN LOCKSMITH AND WASTEWATER OFFICES. THANKS. Gerardo Marquez 136405 Maintenance Electrical Room 7/24/2015 130 Medium Work In Progress 7/24/2015 7:52:42 AM 130 Castillo, Carlos Make material list for stock. 143217 Make material list for stock. 143217 Vork In Progress 11/6/2015 25 Medium Work In Progress 11/6/2015 1:30:44 PM Herrera, Mario NEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE Lectrical Room of the stock of the	Medium	Work In Progress		10/30/2015 4:28:07 PM			
136405MaintenanceElectrical Room7/24/2015130MediumWork In Progress7/24/2015 7:52:42 AM130Castillo, CarlosMake material list for stock.110Carlos Castillo11/6/20152514321711/6/2015 1:30:44 PMMediumWork In Progress11/6/2015 1:30:44 PMHerrera, MarioNEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLENEW OFFICE AS SOON AS POSSIBLE	Solis, Lore	enzo	REGISTERS INSTALLED IN LOO	CKSMITH AND			
MediumWork In Progress7/24/2015 7:52:42 AMCastillo, CarlosMake material list for stock.Carlos Castillo11/6/201514321711/6/2015MediumWork In ProgressMediumWork In Progress11/6/2015 1:30:44 PMHerrera, MarioNEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	Gerardo N	larquez					
Castillo, Carlos Make material list for stock. Carlos Castillo 11/6/2015 143217 11/6/2015 Medium Work In Progress 11/6/2015 1:30:44 PM Herrera, Mario NEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	136405	Maintenanœ	Electrical Room	7/24/2015	130		\$0.00
Carlos Castillo 11/6/2015 25 143217 11/6/2015 1:30:44 PM Medium Work In Progress 11/6/2015 1:30:44 PM Herrera, Mario NEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE Let al	Medium	Work In Progress		7/24/2015 7:52:42 AM			
143217 11/6/2015 25 Medium Work In Progress 11/6/2015 1:30:44 PM Herrera, Mario NEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	Castillo, C	arlos	Make material list for stock.				
Medium Work In Progress 11/6/2015 1:30:44 PM Herrera, Mario NEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	Carlos Ca	stillo					
Herrera, Mario NEED TO FINISH PAINTING JULIES NEW OFFICE AS SOON AS POSSIBLE	143217			11/6/2015	25		\$0.00
SOON AS POSSIBLE	Medium	Work In Progress		11/6/2015 1:30:44 PM			
	Herrera, M	lario		LIES NEW OFFICE AS			
Alledo Holgun	Alfredo Ho	olguin					

WOID Priority Assigned	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason	Until	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex							
143918					11/20/2015		11		\$0.00
Medium	Work In Progress			11/20	0/2015 10:51:37				
Herrera, M	lario	Julies Old Offic	e - paintholes in wall	l and finish pa	ainting				
Alfredo Ho			•		0				
143919					11/20/2015		11		\$0.00
Medium	Work In Progress			11/20	0/2015 10:53:35	i			
Herrera, M	-	Maria S. Office	- remove door and v	arnish					
Alfredo Ho									
142608	ngum				10/30/2015		32		\$0.00
Medium	Work In Progress			10/30	0/2015 10:48:14	L			
Chavez, Sa	-		ddle of parking lot wa on pole close to stree t from Jose R.	s not on this					
Maria Ruiz	2								
142138	Motor Vehicle				10/22/2015		40		\$0.00
Medium	Work In Progress			10/22/2	015 8:49:29 AN	1			
Chavez, Sa	antos	Install outlets a (Please see Sa	s needed in the new I and Jimmy)	welding shop	D.				
Albert Valle	•								
143459	Main Warehouse				11/12/2015		19		\$0.00
Medium	Work In Progress			11/12/2	015 9:13:41 AN	1			
Chavez, Sa		Requesting over warehouse.	erhead light fixture for	r counter at ne	ew				
Danny Car	rrasco				11/10/2015		10		¢0.00
143840				4.4.4.0.10	11/19/2015		12		\$0.00
Medium	Work In Progress				015 9:06:35 AN	1			
Chavez, Sa		NEED OUTLET	FOR 120V WATER	HEATER					
Ruben Ro	nquillo								
143870					11/19/2015		12		\$0.00
Medium	Work In Progress			11/19/2	015 3:45:46 PN	l			
Chavez, Sa	antos	PPD Directors System	Office - install electric	cal outlet for C	amera				
Alfredo Ho	lauin								

WOID Priority Assigned T Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex					
142124			10/21/2015		41		\$0.00
Medium	Work In Progress		10/21/2015 3:56:52 PM	1			
Ontiveros,	Joe	10-21-15 17046.6 17060.9 .5 Enter Log LLES 7-133840-p .5 Enter Log 1 Total HR		10/21/15			
Joe Ontive	ros						
141133			10/6/2015		56		\$0.00
Medium	Work In Progress		10/6/2015 2:56:10 PN	1			
Villalobos,	David	need to order detectable tape alon utilities	g with tracer wire for				
David Villal	lobos						
143285			11/9/2015		22		\$0.00
Medium	Work In Progress		11/9/2015 8:02:05 AN	1			
Gonzalez, S	Salvador	need to replace broken masonryd	rill bits				
Salvador G	Gonzalez						
143609			11/16/2015		15		\$0.00
Medium	Work In Progress		11/16/2015 7:43:51 AN	1			
Gonzalez, S	Salvador	Sal can you please construct a pip the Morgan building at the GAC. T	e rack with a shade at hanks				
David Villal	lobos						
143513			11/12/2015		19		\$0.00
Medium	Work In Progress		11/12/2015 3:53:13 PM	1			
Gonzalez, S	Salvador	Need to frame for installation of ins	sulation of back shop.				
Salvador G	Gonzalez						
135167	Motor Vehicle		7/1/2015		153		\$0.00
Medium	Work In Progress		7/1/2015 9:19:42 AM	1			
Marquez, G	Gerardo	NEED TO INSTALL DOOR AT ME WESTSIDE OF AUTOSHOP. THIS SMALL DR. NEXT TO ROLL UP D	S WILL BE THE				
Gerardo Ma	arquez						
143448			11/12/2015		19		\$0.00
Medium	Work In Progress		11/12/2015 8:29:14 AM	1			
Marquez, G	Gerardo	NEED DOOR CLOSURE INSTALL THAT IS IN FRONT OF COPY MAD					
Alfredo Hol	lguin						

WOID Priority Assigned 1 Requester		AreaDeferred ByUntilRequest Date Target Comp DateArea NumberReasonCreated Date/TimeActual Comp DateDescriptionAction Taken						Labor Hours	Costs
Location:	Physical	Plant Complex							
139632		Office			9/9/2015		83		\$0.00
Medium	Work In Progress			9/9/	2015 9:35:50 AN	1			
Marquez, C	Gerardo	Please install doors a APCO.	nd windows, w	hen theyar	rive from				
Danny Mira	anda								
140460					9/23/2015		69		\$0.00
Medium	Work In Progress			9/23/	2015 8:36:42 AN	1			
Marquez, G	Gerardo	DOOR FRAMES RUS MAINT. WHS. AND LC YOU							
Ruben Ro	nquillo								
138019					8/14/2015		109		\$0.00
Medium	Work In Progress			8/14/	2015 8:57:46 AM	1			
Marquez, G	Gerardo	PLEASE MEET WITH QUOTE.	DR. VENDOR	FOR PRIC	E				
Gerardo M	arquez								
141695					10/14/2015		48		\$0.00
Medium	Work In Progress			10/14/	2015 2:47:58 PN	1			
Marquez, G	Gerardo	Install a peephole at e exit door. Please start evaluation.			kitchen				
Cynthia Ma	ies								
137531		Lift Station			8/7/2015		116		\$0.00
Medium	Work In Progress			8/7/	2015 3:13:14 PN	1			
Gonzalez,	Salvador	the uvsystem shaded metal to cover the uvs		put more s	neet				
Mario Apoc	laca								
144080					12/1/2015		0		\$0.00
Medium	Work In Progress			12/1/	2015 8:33:54 AN	1			
Gonzalez,	Salvador	dump truck need exhu	astclamps we	ld					
Guadalupe	e Ontiveros								
144059					11/30/2015		1		\$0.00
Medium	Work In Progress			11/30/	2015 3:52:45 PN	1			
Gonzalez,	Salvador	need to clean shop							
Salvadar (Sonzalez								

WOID Priority Assigned ⁻	Building Status To	Area Number Description	/30/2016 Order By Loc Deferred By Reason	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		Diant Complex							
	_	Plant Complex			44/40/0045		- 10		.
143841	Maintenance				11/19/2015		12		\$0.00
Medium	Work In Progress			11/19	9/2015 11:26:45	5			
Gonzalez,		Modifyplumbin outside new wa	ig racks for plumbing arehouse.	supplies to ii	nstall				
Danny Car	rrasco				10/10/0015		=0		.
141575					10/12/2015		50		\$0.00
Medium	Work In Progress			10/12/2	015 4:26:40 PN	1			
Gonzalez,	Salvador	TUBING	L SHELVING FOR PV OORS ONE ON EACH						
Ruben Ro	nquillo								
141672					10/14/2015		48		\$0.00
Medium	Work In Progress			10/14/2	015 8:35:25 AN	1			
Orozco, Da	aniel	PLEASE SCHE	EDULE 1ST GREASE		PING.				
Maritza Go	nzalez								
136926					8/2/2015		121		\$0.0
Medium	Work In Progress			8/2/20	15 12:32:11 AN	1			
Vallejo, Alt	pert	Yearly - Physic PMschedule d	al Plant Fire Ext. Insp etails.	. (Yearly) - R	efer to				
Margret Vil	lalobos								
143690					11/17/2015		14		\$0.00
Medium	Work In Progress			11/17/2	015 7:40:21 AN	1			
Flores, Pet	te	Jd needs new	batttery.						
•	e Ontiveros								
137702					8/11/2015		112		\$0.00
Medium	Work In Progress			8/11/2	015 8:06:59 AN	1			
Flores, Pet	te	trailer #0751 ne	eeds tires replaced.						
	e Ontiveros								
142036		Custodial			10/20/2015		42		\$0.0
Medium	Work In Progress			10/20/2	015 3:43:06 PN	1			
Carbajal, J	limmy	roto #3591 has	a burnt motor						
Jimmy Ca	rbajal								

002 - WOIK OIDEIS III I IOGIESS (I ISCAI TEAI)									Tota
Selected Da WOID	ate Range for Request Building	Dates:7/1/2015 - 6 Area	/30/2016 Order By Loc Deferred By	ation, Status Until		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Cre	eated Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Physical	Plant Complex							
141694					10/14/2015		48		\$0.00
Medium	Work In Progress			10/14	/2015 2:45:35 PN	1			
Lara, Ralp	bh		ole at each South Dis se start with STMS p						
Cynthia M	aes								
144078	Motor Vehicle				12/1/2015		0		\$0.00
Medium	Work In Progress			12/1	/2015 8:03:29 AN	1			
Ontiveros	, Guadalupe	Need diesel for diesel to the tru	r truck 134,Lupe Onti uck. Thank you	veros grour	nds add				
Jose Amb	oriz								
Count: 82	Work Orders	Α	vg. Age of WO's 4	3	Total for	Physical Plant Com	xela	0	\$0.00

WOID Priority Assigned T Requester	Building Status o		0/2016 Order By L Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	ES						
144082				12/1/2015		0		\$0.00
Medium	Work In Progress			12/1/2015 8:51:13 AM	I			
Carrasco, I	Danny	Need fuel for truc	ck #76.					
Mario Marti	nez							
142708				11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress			11/1/2015 12:54:11 AM	I			
Orozco, Da	niel	Monthly - Riversio PMschedule deta		ood Cleaning - Refer to				
Margret Vill	alobos							
142730				11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress			11/1/2015 12:54:25 AM	l			
Orozco, Da	niel	Monthly - Riversion PMschedule detail		pression Insp Refer to				
Margret Vill								
143832	Main Building	Custodial		11/19/2015		12		\$0.00
Medium	Work In Progress			11/19/2015 7:53:15 AM	l			
Carbajal, J	-	Jimmy si por favo cuatro cepillos pa		er cuatro bandas y Muchas gracias				
Miguel Son 144017	iora	Hallway/Carridar		11/30/2015		1		\$0.00
		Hallway/Corridor				I		Ф 0.00
Medium	Work In Progress	Main entrance		11/30/2015 11:26:56	1			
Lara, Ralph		Main entrance no	ot closing prope	rly. (Mrs. Martinez)				
Norma Mai	rtinez			/				
144015		Office		11/30/2015		1		\$0.00
Medium	Work In Progress			11/30/2015 11:25:07				
Lara, Ralph		Readjustmainol (Mrs.Martinez)	ffice door. Door s	lams when closing.				
Norma Mai	rtinez							
136913				8/2/2015		121		\$0.00
Medium	Work In Progress			8/2/2015 12:32:04 AM	l			
Vallejo, Alb	ert	Yearly - Riverside PMschedule det		sp. (Yearly) - Refer to				
Margret Vill	alobos							
143289				11/9/2015		22		\$0.00
Medium	Work In Progress			11/9/2015 8:15:00 AM	I			
Moncayo, F	ernando	ICE IS BUILDING		ER ONCE AGAIN. 9.2550.				

VOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Locatio Area Deferred By L Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	ES					
142531			10/29/2015		33		\$0.00
Medium	Work In Progress		10/29/2015 8:00:00 AM				
Gonzalez,	Salvador	Need Sal to fabricate new ramps and s science portable.	tairs for new				
Mario Mar	tinez						
143287			11/9/2015		22		\$0.00
Medium	Work In Progress		11/9/2015 8:03:52 AM				
Gonzalez,	Salvador	Need welder Sal to cut and reverse met that they face in opposite direction.	al benches so				
Mario Mar	tinez						
142681			11/1/2015		30		\$0.00
Medium	Work In Progress		11/1/2015 12:53:53 AM				
Martinez, I	Mario	Yearly - Riverside ES - Grease Trap - F schedule details.	Refer to PM				
Margret Vi	llalobos						
144097			12/1/2015		0		\$0.00
Medium	Work In Progress		12/1/2015 12:49:20 PM				
Ambriz, Jo	ose	Need Jose A. to work on boiler at north stay on in order to heat water.	n wing. It will not				
Mario Mar	tinez		- / /				
140231			9/18/2015		74		\$0.00
Medium	Work In Progress		9/18/2015 2:33:41 PM				
Ambriz, Jo	ose	Need Jose A. to check Library A/C unit freeezing over.	which is still				
Mario Mar	tinez						
136101		Athletic Field	7/20/2015		134		\$0.00
Medium	Work In Progress		7/20/2015 7:40:36 AM				
Castillo, C	Carlos	need to run power for booster pump 24 amps.	0-single face-30				
	e Ontiveros						
143611			11/16/2015		15		\$0.00
Medium	Work In Progress		11/16/2015 7:57:34 AM				
Castillo, C	Carlos	Need Carlos C. toremove and install ne north wing boys and girls restrooms.	ew light fixtures at				
Mario Mar	tinez						

WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loca Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	ES					
138122			8/17/2015		106		\$0.00
Medium	Work In Progress		8/17/2015 11:37:03 AM	1			
Castillo, C	Carlos	Need door bell installed at cafeteria f	or deliveries.	Asp Albert, route to 0	Cali.		
Mario Mar	tinez						
141608			10/13/2015		49		\$0.00
Medium	Work In Progress		10/13/2015 2:22:23 PM	I			
Castillo, C	Carlos	Need Carlos C. to work on parking lot	lights.				
Mario Mar	tinez						
141609			10/13/2015		49		\$0.00
Medium	Work In Progress		10/13/2015 2:24:23 PM	I			
Castillo, C	Carlos	Need Carlos C. to work on bad light p entrance along palm trees.	oles at main				
Mario Mar	tinez						
142944			11/3/2015		28		\$0.00
Medium	Work In Progress		11/3/2015 8:06:35 AM	1			
Martinez, I	Mario	Need to remove banners from gym ce clean metal sidings for up coming No presentation.					
Mario Mar	tinez						
142237			10/23/2015		39		\$0.00
Medium	Work In Progress		10/23/2015 1:59:05 PN	l			
Martinez, I	Mario	Need to replace stained ceiling titles	through out school.				
Mario Mar	tinez						
142239			10/23/2015		39		\$0.00
Medium	Work In Progress		10/23/2015 2:01:28 PM	l			
Martinez, I	Mario	Need to replace bad T-8 light bulbs in	several rooms.				
Mario Mar	tinez						
142151			10/22/2015		40		\$0.00
Medium	Work In Progress		10/22/2015 11:02:29)			
Lara, Ralp	bh	Need Rafa L. to re key locks for wate gates. And to have two padlocks.	er cabinet and				
Mario Mar	tinez						
144081			12/1/2015		0		\$0.00
Medium	Work In Progress		12/1/2015 8:38:26 AM	1			
Ronquillo		Vandalism W.O. for damage caused 6 fire extingushers stolen and one do					
Mario Mar	tinez						
2/1/2016	5 4:03:43 PM					Page 10	7 - 6 4 0

12/1/2015 4:03:43 PM

Count: 23	Count: 23 Work Orders A		vg. Age of WO's	38		Total for Riversid	le ES	0	\$0.00
Location:	Riversi	ide ES							
Requester	r Name								
Assigned	То	Description				Action Taken			
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	
Selected Da	ate Range for Reque Building	st Dates:7/1/2015 - 6 Area	Deferred By L	Until		Target Comp Date	Days	Labor	Costs

WOID Priority Assigned Requester		Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	RTC - Alli	ance						
143605				11/16/2015		15		\$0.00
Medium	Work In Progress			11/16/2015 7:02:31 AM				
Vallejo, All	bert	Remove VCT fl	oors to replace with	linoleum.				
Albert Vall	ejo							
141681		Classroom		10/14/2015		48		\$0.00
Medium	Work In Progress	Ms.Hirsch		10/14/2015 11:27:51				
Moncayo,	Fernando	tried to reset a been 30 min. a	nd turn back but ha nd has not turned or	nas given out. She has s not worked. It has n. Please send re complaining Thank				
Gloria Del	lgado							
140563		Classroom		9/24/2015		68		\$0.00
Medium	Work In Progress			9/24/2015 11:44:03 AM				
Moncayo,	Fernando		s not working throw to cancel afternoon					
Gloria Del	lgado							
143458		Classroom		11/12/2015		19		\$0.00
Medium	Work In Progress			11/12/2015 9:13:35 AM				
Moncayo,	Fernando	Some are flicke	e light bulbs in Ms. H ering and some are We need to unlock					
Gloria Del	lgado							
141364		Portables		10/9/2015		53		\$0.00
Medium	Work In Progress			10/9/2015 1:39:23 PM	l			
Gonzalez,	Salvador		donated by the Pea ace in the back by t	ak and iron grill and he office portable				
Gloria Del								
Count: 5 W	Vork Orders	A	vg. Age of WO's	41	Total for RTC - Allia	ance	0	\$0.00

WOID Priority Assigned ⁻ Requester		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa ES					
136192			7/21/2015		133		\$0.00
Medium	Work In Progress		7/21/2015 11:28:26 AM	I			
Gonzalez,	Salvador	Attach ramps to portables.					
Albert Valle	ejo						
141504			10/12/2015		50		\$0.00
Medium	Work In Progress		10/12/2015 2:01:47 PN				
Orozco, Da	aniel	AS PER ADELE'S MONITORING RE FLOOR IN WALK IN IS LIFTING. SN MARINA R. 589.3439					
Maritza Go	nzalez						
136914			8/2/2015		121		\$0.00
Medium	Work In Progress		8/2/2015 12:32:04 AM	l			
Vallejo, All	pert	Yearly - Santa Teresa ES Fire Ext. Ir to PMschedule details.	nsp. (Yearly) - Refer				
Margret Vi		2					
143995	Main Building	Custodial	11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 8:26:23 AN	l			
Carbajal,	-	JimmyBuenos dias, se quebro un v por favor si me lo puede reemplazar					
Ivan Rodri	guez		44/4/0045	44/00/0045			<u> </u>
142709			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:11 AM				
Orozco, Da		Monthly-Santa Teresa ES Range He Refer to PM schedule details.	ood Cleaning -				
Margret Vil			11/18/2015		13		\$0.00
143790	Main Building				15		Ф 0.00
Medium	Work In Progress		11/18/2015 3:30:38 PM				
Carrasco,	-	Need fuel for vehicle #140, weed eat	er, and blowers				
Juan Amb	riz		44/4/0045	11/00/0015			*• • • •
142732			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:27 AN	I			
Orozco, Da		Monthly-Santa Teresa ES Fire Supp Refer to PMschedule details.	pression Insp				
Margret Vil			0/16/00/5		77		
140025	Main Building		9/15/2015	_	77		\$0.00
Medium	Work In Progress	Playgrounds	9/15/2015 3:59:23 PN	1			
Vallejo, All	pert	Need new floor padding on both play	/grounds				

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa ES					
143916			11/20/2015		11		\$0.00
Medium	Work In Progress		11/20/2015 10:43:47				
Moncayo, I	Fernando	SKILLET WILL NOT TURN ON. S MARINA R. 589.3439	SNP MANAGER				
Maritza Go	nzalez						
140238	Main Building	Classroom	9/18/2015		74		\$0.00
Medium	Work In Progress	Room 101	9/18/2015 3:01:26 PM				
Lara, Ralpl	h	Please make 2 keys for room 10 and the other one is a backup ke					
Rita Mende		Estaviar	44/40/0045		18		<u> </u>
143584	Main Building	Exterior	11/13/2015		10		\$0.00
Medium	Work In Progress		11/13/2015 3:52:39 PM				
	Guadalupe	Need to line locate for sprinklers	nearplayground				
Juan Amb	riz		40/00/0045		40		* •••••
142139			10/22/2015		40		\$0.00
Medium	Work In Progress		10/22/2015 8:53:23 AM				
Ambriz, Ju	an	Need to replace wheels on trash	cart				
Juan Amb	riz						
144079			12/1/2015		0		\$0.00
Medium	Work In Progress		12/1/2015 8:13:13 AM				
Ambriz, Ju		Need to replace batterypack for fi hallway	re alarm panel in 300				
Juan Amb	nz Main Building	Custodial	11/13/2015		18		\$0.00
143538 Madium	-	custodial closet			10		φ0.00
Medium	Work In Progress		11/13/2015 9:08:12 AM				
Ambriz, Ju		Need to replace leakyfaucet in cu	istodial closet				
Juan Amb		Restroom (Girls)	11/2/2015		29		\$0.00
142857	Main Building				29		Ф 0.00
Medium	Work In Progress	300 hallway	11/2/2015 7:44:34 AM				
Ambriz, Ju		Need to replace hand dryers. Not	working.				
Juan Amb		Cofotorio	0/40/0045		111		¢0.00
137878	Main Building	Cafeteria	8/12/2015		111		\$0.00
Medium	Work In Progress		8/12/2015 3:49:58 PM				
Ambriz, Ju	an	Need to order 2-6X4 banners		Denied			

WOID Priority Assigned	Building Status	Dates:7/1/2015 - 6/30/2016 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		Description		Action Taken			
Location:	Santa Te	resa ES					
142530	Main Building	Restroom	10/29/2015		33		\$0.00
Medium	Work In Progress	adult 200	10/29/2015 7:59:04 AM	I			
Ambriz, Ju	ian	Need to replace toilet					
Juan Amb	oriz						
141685	Main Building	Classroom	10/14/2015		48		\$0.00
Medium	Work In Progress	whole building	10/14/2015 1:10:55 PM				
Ambriz, Ju	ian	Need to replace filters in all cool	ing units				
Juan Amb	oriz						
143848	Main Building	Classroom	11/19/2015		12		\$0.00
Medium	Work In Progress	Room #211	11/19/2015 1:45:32 PM				
Ambriz, Ju	lan	As per Ms. Navarrete need to re wall	elocate smart board on				
Juan Amb	oriz						
140070	Main Building	Parking Lot	9/16/2015		76		\$0.00
Medium	Work In Progress	Exteriorlighting	9/16/2015 12:03:20 PM				
Castillo, C	Carlos	Need to replace some exterior li	ghting				
Juan Amb	oriz						
136178	Main Building	Library	7/21/2015		133		\$0.00
Medium	Work In Progress		7/21/2015 8:02:28 AM	I			
Ambriz, Jo	se	Need to repair cooling unit librar	ynot working properly				
Juan Amb	oriz						
142677			11/1/2015		30		\$0.00
Medium	Work In Progress		11/1/2015 12:53:50 AM	I			
Ambriz, Ju	lan	Yearly - Santa Teresa ES - Grea schedule details.	ase Trap - Refer to PM				
Margret Vi							
Count: 22	Work Orders	Avg. Age of WO's	49 To	otal for Santa Teres	a ES	0	\$0.00

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Total Costs
Location:	Santa Te	resa HS					
142006			10/20/2015		42		\$0.00
Medium	Work In Progress		10/20/2015 1:23:44 PM	l			
Villalobos	C	wood shop is in need of a wash bas and not working properly anymore.	in existing one is old				
Jaime Mija	arez						
142007			10/20/2015		42		\$0.00
Medium	Work In Progress		10/20/2015 1:27:58 PM	l			
Villalobos	, David	Boys soccer locker room urinal nee	ds to be replaced.				
Jaime Mija	arez						
141730			10/14/2015		48		\$0.00
Medium	Work In Progress		10/14/2015 3:45:49 PM	l			
Villalobos	, David	Nurses restroom toilet is leaking wa	ater from Tank.				
Jaime Mija	arez						
141736			10/14/2015		48		\$0.00
Medium	Work In Progress		10/14/2015 3:49:13 PM	l			
Villalobos	, David	Varsityfootball showers are clogge	d.				
Jaime Mija	arez						
141581			10/13/2015		49		\$0.00
Medium	Work In Progress		10/13/2015 7:49:59 AN	1			
Villalobos	, David	need to replace missing shower ha boys lockerooms	ndles at girls and				
David Villa	alobos	-					
142679			11/1/2015		30		\$0.00
Medium	Work In Progress		11/1/2015 12:53:51 AN	1			
Hernande	z, Carlos	Yearly - Santa Teresa HS - Grease schedule details.	Trap - Refer to PM				
Margret Vi	llalobos						
143655	Main Building	Gym	11/16/2015		15		\$0.00
Medium	Work In Progress	lockerrooms	11/16/2015 3:40:06 PM	l			
Villalobos	, David	shower head and handles need to b lockerrooms	be replaced within the				
	Dominguez						
140842			10/4/2015	11/4/2015	58		\$0.00
Medium	Work In Progress		10/4/2015 12:37:58 AN	1			
Diaz, Davi		Yearly - Santa Teresa HS U-2 Unit Refer to PMschedule details.	Ht Gas Yearly-				
Margret Vi	llalobos						

12/1/2015 4:03:44 PM

WOID Priority Assigned ⊺	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester							
Location:	Santa Te	resa HS					
140843			10/4/2015	11/4/2015	58		\$0.00
Medium	Work In Progress		10/4/2015 12:37:59 AN	1			
Diaz, David		Yearly - Santa Teresa HS H-6 Rf to PMschedule details.	top Furn Yearly - Refer				
Margret Vil							
143379	Main Building	Classroom	11/10/2015		21		\$0.00
Medium	Work In Progress	215	11/10/2015 10:55:05				
Lara, Ralph	h	Door needs to be moved to room Soriano	215, please see Mrs.				
Lorraine D	ominguez		44/40/0045		40		.
143827			11/18/2015		13		\$0.00
Medium	Work In Progress		11/18/2015 4:39:07 PM				
Castillo, Ca	arlos	need keys for new switches					
Carlos He	rnandez						
144026			11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 2:01:53 PM				
Castillo, Ca	arlos	Nurses Portable - relocate electri	cal for water heater.				
Albert Valle	ejo						
141409	Main Building	Classroom	10/9/2015		53		\$0.00
Medium	Work In Progress	407, 500, 503	10/9/2015 3:56:03 PM	1			
Castillo, Ca	arlos	Need outlets in these classroom: were installed in classrooms.	s as new smart boards				
Lorraine D	-						
136350	Main Building	Classroom	7/23/2015		131		\$0.00
Medium	Work In Progress	209	7/23/2015 2:34:10 PM	1			
Diaz, David	b	Please paint where tvstand was i	removed.				
Lorraine D	ominguez						
136351	Main Building	Restroom	7/23/2015		131		\$0.00
Medium	Work In Progress	bylibrary	7/23/2015 2:35:07 PM	1			
Diaz, David	t	Ceiling needs painting					
Lorraine D							
140232		Football Field	9/18/2015		74		\$0.00
Medium	Work In Progress		9/18/2015 2:44:34 PM	1			
Castillo, Ca	Ū	As per J.Mijarez one footbalfield					
Casulo, Ca	a1103						

WOID Priority Assigned ⁻	Building Status Fo	Dates:7/1/2015 - 6/30/2016 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	Santa Te	resa HS					
142566			10/29/2015		33		\$0.00
					55		ψ0.00
Medium Ambriz, Jos	Work In Progress se	Trainers ice thickness sensor for ic needs to be replaced. Trainer wants on the ice maker water filters.					
Jaime Mija	arez						
142694			11/1/2015		30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:01 AN	1			
Flores, Pet	te	Monthly - STH-UV-0517 PM Service schedule details.	e - Refer to PM				
Margret Vil	lalobos						
136482			7/27/2015		127		\$0.00
Medium	Work In Progress		7/27/2015 7:56:16 AN	1			
Flores, Pet	le	7/27/14 Can you please see if you can do an company truck (141). Was checking pretty bad, also if you can check th don't work. Truck 141 is located at	oil and it looks e turn signals they				
David Diaz	2						
141103			10/6/2015		56		\$0.00
Medium	Work In Progress		10/6/2015 10:18:03 AN	1			
Flores, Pet	te	997 mower needs new battery will n	not start.				
Guadalupe	e Ontiveros						
139558		Custodial	9/8/2015		84		\$0.00
Medium	Work In Progress		9/8/2015 9:59:57 AN	1			
Flores, Pet	te	need headlights on the gator the yw months ago and theyburnout again					
Arnold Luc	ero						
143494	GYM (2009)		11/12/2015		0		\$0.00
Medium	Work In Progress		11/12/2015 3:44:07 PM	11/12/2015			
Lara, Ralpl	h	DOORS NEED TO BE AJUSTED A LACHES ON ALL DOORS AT GYM					
Ralph Lara	a						
141435			10/11/2015	10/27/2015	51		\$0.00
Medium	Work In Progress		10/11/2015 12:28:46	i			
Lucero, Arr	nold	Monthly - QRTLY BLDG INSP REPO to PMschedule details.	ORT (STH) - Refer				
Jesus Est	rada						

Requester	Го	Area Number Reason Description	Created Date/Time	Actual Comp Date Action Taken	Days Aged	Hours	
Location:	Name Santa Te	resa HS					
143604			11/15/2015		16		\$0.00
Medium	Work In Progress		11/15/2015 12:27:55				<i>Q</i> 0100
Flores, Pet		Yearly - Santa Teresa HS - Mower Refer to PMschedule details.					
Margret Vil	lalobos						
136365	Main Building	Classroom	7/23/2015		131		\$0.00
Medium	Work In Progress	410	7/23/2015 2:57:12 PN	1			
Diaz, Davio	t	Take down board and replace with see Ms. Soriano	bulletin board please				
Lorraine D	-						
136366	Main Building	Classroom	7/23/2015		25		\$0.00
Medium	Work In Progress	500	7/23/2015 2:57:44 PN	8/17/2015			
Diaz, Davio	t	Baseboard behind teacher desk n	leeds replacing				
Lorraine D	ominguez						
141562	Vocational	Classroom	10/12/2015		50		\$0.00
Medium	Work In Progress	805	10/12/2015 3:53:51 PM				
Diaz, Davio	b	In need of changing light bulbs					
Lorraine D	ominguez						
136764	Main Building	Classroom	7/30/2015		124		\$0.00
Medium	Work In Progress	C-4	7/30/2015 3:27:13 PN	1			
Diaz, Davio	t	Install whiteboard in C-4 along wa entering classroom also needed i					
Lorraine D	ominguez						
141057		Classroom	10/5/2015		57		\$0.00
Medium	Work In Progress	MR.	10/5/2015 1:03:46 PN	1			
Diaz, Davio	k	LAB C-4 NEEDS BOARD MOUNT	ED.				
Marylou Jir	menez						
143846			11/19/2015		12		\$0.00
Medium	Work In Progress	Nurses Office	11/19/2015 1:31:03 PM				
Miranda, D	Danny	Please fur out wall in Nurses Offic plumbing and water heater (see D specifics)					
Albert Valle	ejo						
139966			9/15/2015		77		\$0.00
Medium	Work In Progress		9/15/2015 8:40:48 AM				
Vallejo, Alb	pert	Install new marquee.					
Albert Valle							

12/1/2015 4:03:44 PM

WOID Priority Assigned 1 Requester	Building Status Fo	Dates:7/1/2015 - 6/30/2016 Order By Locatio Area Deferred By L Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS					
143593			11/13/2015		18		\$0.00
Medium	Work In Progress		11/13/2015 3:59:23 PM				
Carrasco,	Danny	11/13/15 Requesting to order a pancake compre	essorforac's.				
David Diaz	2						
139126			9/1/2015		91		\$0.00
Medium	Work In Progress		9/1/2015 9:42:05 AM				
Diaz, Davio	2	ASP PM 136985 - Exit Signs not workin Choir Room Bandroom Cafeteria 500 Wing - Hallway Hallwayleading to Football Field.	ng:	11/19/15 -As per Ca	ıli, BM's a	re servici	ng
David Diaz	<u>.</u>						
139128			9/1/2015		91		\$0.00
Medium	Work In Progress		9/1/2015 9:47:44 AM				
Diaz, David	3	ASP PM 136986 - Emergency Lights n Portables V. Gym Entrance and hallway on top of Coach Dotson Office and storage room coaches offices Boys Locker Room - lead outside both i	Forever s infront of	11/19/15 -As per Ca	ıli, BM's a	re servici	ng
David Diaz	<u>.</u>						
144027			11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 2:03:16 PM				
Diaz, Davio	Ł	Nurses Portable - glue back rf panel, so install sink.	Plumber can				
Albert Valle	ejo						
140732			9/29/2015		63		\$0.00
Medium	Work In Progress		9/29/2015 8:06:24 AM				
Diaz, David	ł	9/29/15 Request to order tools to substitute old	ones.				
David Diaz	1		0//0/201-		4.40		^
137914			8/13/2015		110		\$0.00
Medium	Work In Progress		8/13/2015 8:28:56 AM				
Diaz, Davio		8/13/15 Requesting to order some tools.					
David Diaz	2						

Selected Da WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	eresa HS					
142733			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:27 AM	1			
Orozco, D	aniel	Monthly-Santa Teresa HS Fire So Refer to PMschedule details.	uppression Insp				
Margret V	illalobos						
143590			11/13/2015		18		\$0.00
Medium	Work In Progress		11/13/2015 3:55:53 PM				
Carrasco	· •	11/13/15 Requesting fuel for Polaris.					
David Dia	Z		44/4/0045	44/00/0045			<u> </u>
142710			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:12 AM	1			
Orozco, D		Monthly-Santa Teresa HS Range Refer to PMschedule details.	Hood Cleaning -				
Margret V	illalobos		10/4/2015	10/25/2015	50		¢0.00
140896			10/4/2015	10/25/2015	58		\$0.0
Medium	Work In Progress		10/4/2015 12:38:35 AM	1			
Vallejo, Al		Monthly - Santa Teresa HS Fire S to PMschedule details.	Sprinkler Insp Refer				
Margret V 140744	Applied Science		9/29/2015		63		\$0.00
Medium	Work In Progress		9/29/2015 11:48:16 AM	1	00		ψ0.0
	-	Depless tils in slag at (auline music		1			
Estrada, J		Replace tile in closet (culinary cla	ssroom)				
Jesus Es 141034	trada		10/5/2015		57		\$0.00
Medium			10/5/2015 8:05:08 AM		57		ψ0.00
	Work In Progress			I			
Estrada, J Albert Val		Please Install tile where it was rer work. (South hall by Locker rooms					
143437	GYM (2009)	Classroom	11/10/2015		21		\$0.00
Medium	Work In Progress	Training Room	11/10/2015 5:57:00 PM				
Estrada, J	· ·	Please replace tile that was torn u to plumbing upgrades in Oct. 201	ıp in training room due				
Nicholas	Wohlgemuth						
135788	Gymnasium	Classroom	7/13/2015		141		\$0.00
Medium	Work In Progress	weightroom	7/13/2015 2:34:55 PN	1			
Estrada, J	Jesus	floor in weight room is lifting					
	Dominguez	· · · ·					
	5 4:03:44 PM					Page 1	18 of 137
						i ago i	

Priority Assigned ⁻ Requester		Area Number Reason Description	y Until Request Date Ta Created Date/Time A	arget Comp Date Days ctual Comp Date Aged Action Taken	
Location:	Santa Te	resa HS			
136357	Main Building	Restroom	7/23/2015	131	 \$0.00
Medium	Work In Progress	300 hallway	7/23/2015 2:41:30 PM		
Lara, Ralpl	h	Bathroom stalls need replac of them and theyare in bad s			
Lorraine D	ominguez				
144028	Storage (Tennis)	Storage	11/30/2015	1	\$0.00
Medium	Work In Progress		11/30/2015 2:06:33 PM		
Lara, Ralpl	h	The walk through door to sto secured, and needs the dea padlocks are needed for the and gate.	dbolt replaced. Plus, two		
Rick Llane	Z				
143753	Main Building	Hallway/Corridor	11/17/2015	14	\$0.00
Medium	Work In Progress		11/17/2015 4:44:53 PM		
Lara, Ralpl	h	Replace Exterior doors by Co Replace and upgrade to fire that now separate the 400 ha	doors the old exterior doors		
Nicholas V	Nohlgemuth				
135501	Library	Hallway/Corridor	7/6/2015	148	\$0.00
Medium	Work In Progress	200 Hall Student	7/6/2015 10:50:05 PM		
Lara, Ralp		Please replace all existing s partitions due to heavy graffi			
	Nohlgemuth	1 ih na ma	0/4/0045	140	<u> </u>
137214	Library	Library	8/4/2015	119	\$0.00
Medium	Work In Progress	library	8/4/2015 2:28:04 PM		
Lara, Ralpl	h	Emergencydoors not function	pning		
Lorraine D	-				
141349	Locker Room	Hallway/Corridor	10/9/2015	53	\$0.00
Medium	Work In Progress		10/9/2015 8:50:43 AM		
Lara, Ralpl	h	Fire Door Magnetic Door Hol lose it and looks damaged. I necessaryand re-attached to	t needs to be replaced if		
Alfredo Ho	lguin				
136924			8/2/2015	121	\$0.00
Medium	Work In Progress		8/2/2015 12:32:10 AM		
Vallejo, Alt	pert	Yearly - Santa Teresa HS Fi to PMschedule details.	re Ext. Insp. (Yearly) - Refer		

WOID Priority Assigned	Building Status	Dates:7/1/2015 - 6/30/2016 Order By Area Deferred By Area Number Reason Description	Until Request Date Target Com Created Date/Time Actual Com Action	p Date Aged	Labor Hours	Costs
Requeste	r Name					
Location:	Santa Te	resa HS				
143991			11/30/2015	1		\$0.00
Medium	Work In Progress		11/30/2015 7:10:31 AM			
Vallejo, A	lbert	Create concrete pad for new ble	eachers.			
Albert Val	lejo					
141374			10/9/2015	53		\$0.00
Medium	Work In Progress		10/9/2015 2:17:00 PM			
Orozco, D	aniel	WALK IN FLOOR PANELS ARE HAZARD. SNP MANAGER OLG				
Maritza G	onzalez					
141390			10/9/2015	53		\$0.00
Medium	Work In Progress		10/9/2015 3:42:03 PM			
Orozco, D	aniel	washer leaking water				
Daniel Or	ozco					
142154			10/22/2015	40		\$0.00
Medium	Work In Progress		10/22/2015 11:20:31			
Orozco, D	aniel	need to add lighting to walk in re	efrigerator			
Daniel Or	OZCO					
141547	GYM (2009)	Athletic Field	10/12/2015	50		\$0.00
Medium	Work In Progress	Baseball	10/12/2015 3:46:32 PM			
Gonzalez	, Salvador	Need for batting caged to be rer pitching mounds. Requesting t batting cages.				
Lorraine I	Dominguez					
Count: 57	Work Orders	Avg. Age of WO's	s 57 Total for Sant	a Teresa HS	0	\$0.00

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Area Deferred By Area Number Reason Description	Until Request Date Targ Created Date/Time Actu			otal
Location:	Santa Te	resa MS				
139197			9/2/2015	90	\$0	0.00
Medium	Work In Progress		9/2/2015 8:03:32 AM			
Gonzalez,	Salvador	A LEVER NEEDS TO BE WELD WE CAN CHECK THE FLUID LE ENGINE				
Laura Par	ra					
141506			10/12/2015	50	\$0	0.00
Medium	Work In Progress		10/12/2015 2:28:22 PM			
Orozco, Da	aniel	HANDLE FOR HOT WATER ON IS BROKEN. SNP MANAGER GE				
Maritza Go	onzalez					
136401		Office	7/23/2015	131	\$0	0.00
Medium	Work In Progress		7/23/2015 4:17:14 PM			
Marquez, (Gerardo	PLEASE GET A PRICE QUOTE MAILBOX AND BASE CABINETS				
Gerardo M	Marquez					
141421			10/9/2015	53	\$0	0.00
Medium	Work In Progress	Outside Exit of	10/9/2015 4:17:37 PM			
Vallejo, All	bert	Repair pavement from kitchen de ergonomic inspections paveme made to provide a smooth transi the concrete.	ntrepairs should be			
Cynthia Ma	aes					
136919			8/2/2015	121	\$0	0.00
Medium	Work In Progress		8/2/2015 12:32:07 AM			
Vallejo, All	bert	Yearly - Santa Teresa MS Fire E to PMschedule details.	xt. Insp. (Yearly) - Refer			
Margret Vi	llalobos					
139307	North Building	Office	9/3/2015	89	\$0	0.00
Medium	Work In Progress	ASST	9/3/2015 3:22:50 PM			
Lara, Ralp	h	OUTSIDE DOOR IN ASST PRIN DOES NOT WORK PROPERLY. CLOSE				
Laura Par	ra					
139066	Gym (1997)	Foyer	8/31/2015	92	\$0	0.00
Medium	Work In Progress	MAIN GYM	8/31/2015 3:24:41 PM			
Lara, Ralp	h	1- EXTERIOR DOORS NEED LA DOOR OPEN 2- FOYER DOORS DO NOT SEC				
Laura Par	ra					
40/4/0045						

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loca Deferred By Reason	Until	•	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS							
141507					10/12/2015		50		\$0.00
Medium	Work In Progress			10/12/	2015 2:30:14 PN	I			
Lara, Ralp	h	(PREVIOUS W	OUTSIDE DOORS S ORK ORDER SUBMI PLETE). SNP MANAG	TTED 1275	44				
Maritza Go	onzalez								
140121					9/17/2015		75		\$0.00
Medium	Work In Progress			9/17/	2015 8:07:29 AM	1			
Lara, Ralp	h	Please install v (new Morgan)	vrought iron screen d	oor on athle	etics shed				
Albert Vall	ejo								
141419					10/9/2015		53		\$0.00
Medium	Work In Progress	Kitchen		10/9/	2015 4:05:33 PN	1			
Lara, Ralp	h	Need to fixprob inspector has a return to check	ash enter through un lem, please inspect a lreadybeen there an if the problem has be yquestions 882-694	and repair. d is expecte en repaired	Food ed to				
Cynthia Ma	aes								
141420					10/9/2015		53		\$0.00
Medium	Work In Progress	Kitchen		10/9/	2015 4:13:39 PN	1			
Lara, Ralp	h	pad locks. Insp need to be used access route to	ors are being secure ect and repair so that d. As per ergonomic i this clear space mus se call Cynthia with ar	pad locks on spections to be mainted by the mainted	don't an iined at				
Cynthia Ma									
143366	North Building	Custodial			11/10/2015		21		\$0.00
Medium	Work In Progress			11/10/	2015 8:06:58 AM	1			
Carbajal,	Jimmy	lhave2burnish #110.	ers that are not worki	ng serial #	050 and				
Ismael Ro	-								
143442	North Building	Custodial			11/12/2015		19		\$0.00
Medium	Work In Progress			11/12/	2015 7:41:27 AN	1			
Carbajal,	Jimmy	Floorburnishe	#110 doesn't work n	eedservice					
Ismael Ro	odriguez								

WOID Priority Assigned	Building Status To	Area Area Number Description	/30/2016 Order By Loc: Deferred By Reason	Until	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	Name								
Location:	Santa Te	resa MS							
139979					9/15/2015		77		\$0.00
Medium	Work In Progress			9/15/20	015 12:50:46 PM	l			
Lara, Ralp	h	Administration	n security office hallw the office needs to so urity officer for details	ecure confis	cated				
Albert Vall	ejo								
142711					11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress			11/1/20)15 12:54:13 AN	1			
Orozco, Da	aniel	Monthly - Santa Refer to PMsch	i Teresa MS Range I iedule details.	Hood Clean	ing -				
Margret Vil									
144101	North Building	Office			12/1/2015		0		\$0.00
Medium	Work In Progress	ADMIN		12/1/2	2015 1:01:30 PM	1			
Carrasco,	Danny	DELIVER FUE	FOR ADMIN GATO	RS					
Laura Par	ra								
137056					8/3/2015		120		\$0.00
Medium	Work In Progress			8/3/2	2015 9:09:16 AM	1			
Vallejo, All	pert	Repair gas me	ter enclos ure.						
Albert Vall	ejo								
142734					11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress			11/1/20	015 12:54:28 AM	1			
Orozco, Da	aniel	Monthly - Santa Refer to PMsch	i Teresa MS Fire Sup iedule details.	pression In	sp				
Margret Vil									
141985	South Building				10/20/2015		42		\$0.00
Medium	Work In Progress			10/20/2	2015 8:06:34 AM	1			
Miranda, D	Danny		- cover two pocket do e- tape texture and p		vay				
Alfredo Ho	-								
138255	Gym (1997)				8/18/2015		105		\$0.00
Medium	Work In Progress			8/18/2	2015 3:34:23 PM	1			
Vallejo, All	pert	The scorers tal or replaced	ole on the bleachers	need to be re	epaired				
Alfredo Ho	lauin								

VOID Priority Assigned Requeste	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date Ta Created Date/Time Ac		Costs Labor Hours
Location:	Santa Te	resa MS			
143603			11/15/2015	16	\$0.00
Medium	Work In Progress		11/15/2015 12:27:54		
Flores, Pe	ete	Yearly - Santa Teresa MS - Mower Refer to PM schedule details.	0416 - Grounds -		
Margret Vi	illalobos				
143198			11/6/2015	25	\$0.00
Medium	Work In Progress		11/6/2015 11:27:44 AM		
Moncayo,	Fernando	ON/OFF SWIETCH FROM EXHAU STORAGE AND WALK IN AREA A MANAGER GESSICA M. 589.9836	RE BROKEN. SNP		
Maritza Go	onzalez				^
144091			12/1/2015	0	\$0.00
Medium	Work In Progress		12/1/2015 11:45:10 AM		
Moncayo,	Fernando	2 OVENS - DIALS ARE NOT WOR SNP MANAGER GESSICA M. 589			
Maritza Go	onzalez		10/1/00/15		.
144092			12/1/2015	0	\$0.00
Medium	Work In Progress		12/1/2015 11:46:19 AM		
Rodrigue	z, Ismael	2 SOAP DISPENSERS LEAKING. GESSICA M. 589.9836	SNP MANAGER		
Maritza Go	onzalez		0/04/0045		.
138502		Restroom	8/21/2015	102	\$0.00
Medium	Work In Progress		8/21/2015 1:34:48 PM		
Lara, Ralp		Please acquire quote for urinal parestrooms.	rtitions 18' for boys		
Albert Vall	-		/		
143947	North Building	Classroom	11/20/2015	11	\$0.00
Medium	Work In Progress	#3- DE LA	11/20/2015 3:39:32 PM		
Lara, Ralp	bh	NEED BATHROOM KEY AND LOU	JNGE KEY.		
Laura Par					
143641	South Building	Classroom	11/16/2015	15	\$0.00
Medium	Work In Progress	53- DE LA	11/16/2015 3:13:29 PM		
Lara, Ralp	bh	KEY TO FILING CABINET BROKE NEW KEY.	. PLEASE ISSUE		
Laura Par	rra				

WOID Priority Assigned ⁻		Dates:7/1/2015 - 6 Area Area Number Description	Deferred By	Until R	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	Name Santa Te	roco MS							
					/ /				
142535	North Building	Classroom			10/29/2015		33		\$0.00
Medium	Work In Progress			10/29/201	5 9:59:44 AM				
Prospero,	Manuel	AFTER SERVIC	CING DRYER, CON S. NO HEAT	TINUES NOT TO)				
Laura Pari									
137285	North Building	Classroom			8/5/2015		118		\$0.00
Medium	Work In Progress	22 PRADO		8/5/201	5 9:17:19 AM				
Prospero,	Manuel		HAD WATER LEAK WHITE BOARD WA						
Laura Parr									
140642	South Building	Office			9/25/2015		67		\$0.00
Medium	Work In Progress	SEE MR.		9/25/201	5 2:51:51 PN	l			
Prospero,	Manuel	-	S/SHEETROCK IN D DOWN STAIRS.	BOYS RESTRO	DMS				
Laura Parr	ra								
137649		Restroom			8/10/2015		113		\$0.00
Medium	Work In Progress			8/10/201	5 2:55:21 PN	I			
Prospero,	Manuel	FRAMES ON 3	REPAIR PARTITION BOYS AND GIRLS ESTROOMS DOOR	RESTROOMS.		8/21/15 - Asp Albert complete	, route to	Manuel to	
Manuel Pro	ospero								
141508					10/12/2015		50		\$0.00
Medium	Work In Progress			10/12/201	5 2:32:47 PM				
Prospero,	Manuel		S ON STORAGE AR LEAK. SNP MANAG	-					
Maritza Go	nzalez								
141509					10/12/2015		50		\$0.00
Medium	Work In Progress			10/12/201	5 2:34:34 PM				
Prospero,	Manuel		S MONITORING RE AND BATHROOM		N				
Maritza Go	nzalez								
144033					11/30/2015		1		\$0.00
Medium	Work In Progress			11/30/201	5 3:12:55 PM				
Prospero,	Manuel	1 1/2 X 1 1/4 W FLASH VALVES	RAPS 1.5 FLANGE ASHERS ANS NUT S FOR COMMODES SPUDS. 1 1/2 SPU	S. PIPE DOPE. AND URINALS					
Manuel Pro	ospero								

Selected Dat WOID Priority Assigned 1 Requester		Dates:7/1/2015 - 6/ Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS						
136584	Gym (1997)	Gym		7/28/2015		126		\$0.00
Medium	Work In Progress	GYM FLOOR		7/28/2015 11:54:01 AN	I			
Prospero, I	Manuel		LACE FLOOR SLE NET STANDARDS	EVES FOR				
Laura Parr	a							
144094				12/1/2015		0		\$0.00
Medium	Work In Progress			12/1/2015 11:48:18 AN	l			
Prospero, I	Manuel		.ING TILES NEED REA. SNP MANAG	TO BE REPLACED ER GESSICA M.				
Maritza Go	nzalez							
142804				11/1/2015		30		\$0.00
Medium	Work In Progress			11/1/2015 12:55:15 AN	I			
Prospero, I	Manuel	Monthly - Santa Refer to PMsch		es Dryer (Monthly) -				
Margret Vil	lalobos							
142805				11/1/2015	11/9/2015	30		\$0.00
Medium	Work In Progress			11/1/2015 12:55:15 AN	I			
Prospero, I	Manuel	Monthly - Santa Refer to PMsch		ign Insp: Monthly-				
Margret Vil	lalobos							
142806				11/1/2015	11/9/2015	30		\$0.00
Medium	Work In Progress			11/1/2015 12:55:16 AN	l			
Prospero, I	Manuel	Monthly - Santa Refer to PMsch		Light Test: Monthly -				
Margret Vil	lalobos							
143567				11/13/2015		18		\$0.00
Medium	Work In Progress			11/13/2015 3:39:42 PM				
Prospero, I	Manuel	11/13/15. .5HR CHECK E 4HRS WO 1409 3HRS WO 1428 .5HR ENTER L	902. 352.		11/13/15			
Manuel Pro								
141855	North Building	Office		10/16/2015		46		\$0.00
Medium	Work In Progress	NORTH/SOUT	н	10/16/2015 2:19:12 PM				
Prospero, I	Manuel		REPLACE ALL THE ND WEATHER STE ORS.					
Laura Parr	a							
	4:03:44 PM							26 of 137

VOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description	Cation, Status Until Request Date Ta Created Date/Time Ac	· · · · ·	Labor Hours	Costs
Location:	Santa Te	resa MS				
143316	South Building	Office	11/9/2015	22		\$0.00
Medium	Work In Progress	SOUTH OFFICE	11/9/2015 2:24:01 PM			
Prospero,	Manuel	PAINT ALL TRIM INSIDE AND OU AND RESTROOMS-BLACK PAINT				
Laura Par	ra					
140159	South Building	Office	9/17/2015	75		\$0.00
Medium	Work In Progress	SECURITY-MR	9/17/2015 1:10:33 PM			
Prospero,	Manuel	1-RE PAINT NO PARKING FIRE L 2- NEED SIGNS "NO PARKING AT SOUTH GATE ENTRANCE				
Laura Par						
141494	South Building	Office	10/12/2015	50		\$0.00
Medium	Work In Progress	SEE MR.	10/12/2015 12:11:26			
Castillo, C	Carlos	NEED LIGHTS AND OUTLES INS STORAGE BUILDING. SEE MR. R	_			
Laura Par						
138771	North Building	Parking Lot	8/26/2015	97		\$0.00
Medium	Work In Progress	PARKING LOT	8/26/2015 11:12:25 AM			
Castillo, C	Carlos	SOME LIGHTS IN THE PARKING I ON- BULBS MAY BE WORN OUT	LOT DO NOT TURN			
Laura Par		-				^
139063	Gym (1997)	Gym	8/31/2015	92		\$0.00
Medium	Work In Progress	GYMBACK	8/31/2015 3:20:53 PM			
Castillo, C	Carlos	NO EXTERIOR LIGHTING. REPLA PREVIOUSLY POSITIONED BEHI GYMNASIUM.				
Laura Par	ra					
140749	North Building	Parking Lot	9/29/2015	63		\$0.00
Medium	Work In Progress		9/29/2015 1:57:53 PM			
Castillo, C	Carlos	9/29/15. EXPOSED WIRES BY PA	RKING LOT.			
Manuel Pr	rospero					
140751	-	Parking Lot	9/29/2015	63		\$0.00
Medium	Work In Progress		9/29/2015 2:29:11 PM			
Castillo, C	Carlos	ldentify and secure and repair brok parking lot light circuit.	en underground			
Carlos Ca	astillo					

Selected Da WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location Area Deferred By U Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS					
140855			10/4/2015	10/20/2015	58		\$0.00
Medium	Work In Progress		10/4/2015 12:38:07 AN	1			
Prospero	, Manuel	Monthly - Santa Teresa MS A1 (Wall Ref Refer to PMschedule details.	r.E/H)(Semi) -				
Margret V	illalobos						
140794			9/30/2015		62		\$0.00
Medium	Work In Progress		9/30/2015 12:43:18 AM	1			
Prospero	, Manuel	Monthly - Santa Teresa MS A16 (Fan Ex Refer to PMschedule details.	h.)(Monthly) -				
Margret V	illalobos						
142476	South Building	Office	10/28/2015		34		\$0.00
Medium	Work In Progress		10/28/2015 1:17:50 PM	1			
Ambriz, Jo	ose	WE NEED TO CHANGE BLOWER MOT OFFICE LOBBY. GE MOD NUMB. SKC 1/2. 460 VOLTS. RPM. 1075 1HP K773 X70671117010.	P38PG HP				
Manuel P	rospero						
141491	South Building	Library	10/12/2015		50		\$0.00
Medium	Work In Progress	CUSTODIAL	10/12/2015 12:01:39)			
Villalobos	s, David	FIX OR SHUT OFF WATER LEAK IN CU CLOSEST BEHIND LIBRARY	ISTODIAL				
Laura Par	rra						
142693			11/1/2015		30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:01 AM	1			
Prospero	, Manuel	Yearly - Santa Teresa MS - Grease Traț schedule details.	o - Refer to PM				
Margret V							
139067	North Building	Classroom	8/31/2015		92	1	\$25.00
Medium	Work In Progress	9 CORDOVA	8/31/2015 3:25:43 PM	Λ			
Prospero	, Manuel	LEAK IN CEILING AGAINST THE WALL		9/1/15 - Manuel plea			ber
Laura Pai	rra			David V. Teacher sa	ays it's fro	om rain	
Count: 54	Work Orders	Avg. Age of WO's 55	Т	otal for Santa Teres	a MS	1	\$25.00

Requester	To Name	Area Number Reason Description	Created Date/Time Actual C Acti	Comp Date Days Comp Date Aged Con Taken	Labor Hours
Location:	Sunland	Park ES			
142683			11/1/2015	30	\$0.00
Medium	Work In Progress		11/1/2015 12:53:54 AM		
Mijarez, Ja	ime	Yearly - Sunland Park ES - Grease schedule details.	e Trap - Refer to PM		
Margret Vil	lalobos				
142166			10/22/2015	40	\$0.00
Medium	Work In Progress		10/22/2015 3:20:00 PM		
Villalobos	David	Girls Restroom ADA stall - remove there is only one water closet in the			
Alfredo Ho	-				
141659	Main Building	Restroom	10/14/2015	48	\$0.00
Medium	Work In Progress		10/14/2015 7:27:02 AM		
Villalobos		second to last toilet needs work it g to 3 times per daythanks.	ets clugged at least 2		
Jesus Luc 143764	ero	Classroom	11/18/2015	13	\$0.00
Medium	Work In Progress	36	11/18/2015 8:29:34 AM	10	φ0.00
Ambriz, Jo		RM#36- HANTZOPULOS- FIX THE IN THE CLASSROOM SO THAT S DRINK WATER DURING THE DAY	WATER FOUNTAIN TUDENT MAY		
Maribel Ga	amboa				
144087	Main Building	Classroom	12/1/2015	0	\$0.00
Medium	Work In Progress		12/1/2015 10:34:46 AM		
Ambriz, Jo	se	there are some complains on roon are cold if you could please help us	,		
Jesus Luc	ero				
142382			10/27/2015	35	\$0.00
Medium	Work In Progress		10/27/2015 9:53:27 AM		
Castillo, C	arlos	OFFICE - MORALES- SHE NEEDS INSTALLED IN HER OFFICE	S A OUTLET TO BE		
Maribel Ga	amboa				
143762		Library	11/18/2015	13	\$0.00
Medium	Work In Progress	LIBRARY	11/18/2015 8:22:59 AM		
Mijarez, Ja	ime	LIBRARY- MORENO- NEED DOOI SEE MRS. MORENO	RS PAINTED BLUE		
Maribel Ga	amboa				

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason	Until Request		rrget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES							
143763		Library		11/18	/2015		13		\$0.00
Medium	Work In Progress	LIBRARY		11/18/2015 8:25:	55 AM				
Mijarez, Ja	aime	FINISHED IN L	RENO- NEED TO HA IBRARY WALLS. LIG GON COMPLETELY	-					
Maribel G	amboa								
138311				8/19	/2015		104		\$0.00
Medium	Work In Progress	25		8/19/2015 10:16:	35 AM				
Mijarez, Ja	aime		GUIN- PLEASE PAIN DOM-2ND NOTICE	IT THE DOES IN	R	oute to Jaime on 1	1/16/15		
Maribel G	amboa								
142787				11/1	/2015	11/9/2015	30		\$0.00
Medium	Work In Progress			11/1/2015 12:55:	03 AM				
Mijarez, Ja	aime	Monthly - Sunla Refer to PMsch	and Park ES Exit Sigr nedule details.	n Insp: Monthly-					
Margret Vi	llalobos								
142788				11/1	/2015	11/9/2015	30		\$0.00
Medium	Work In Progress			11/1/2015 12:55:	04 AM				
Mijarez, Ja	aime	Monthly - Sunla Refer to PMsch	and Park ES Emer Li nedule details.	ght Test: Monthly -					
Margret Vi									
141920	Main Building	Parking Lot		10/19	/2015		43		\$0.00
Medium	Work In Progress			10/19/2015 11	:06:16				
Mijarez, Ja	aime	South Side of B weeds.	uilding/BackEntries	- cut and remove	R	oute to Jaime on 1	1/16/15		
Alfredo Ho	olguin								
137110		Classroom		8/3	/2015		120		\$0.00
Medium	Work In Progress	25		8/3/2015 3:04:	41 PM				
Mijarez, Ja	aime	RM#25- GARC DOORS	IA- PLEASE PAINT C	LASSROOM	R	oute to Jaime on 1	1/16/15		
Maribel G	amboa								
143765		Library		11/18	/2015		13		\$0.00
Medium	Work In Progress	LIBRARY		11/18/2015 8:36:	45 AM				
Mijarez, Ja	aime		RENO- NEEDS TO H STALLED SEE MRS.						
Maribel G	amboa								

141871	unland Park ES			Action Taken		
			10/16/2015		46	 \$0.00
Medium Work In Pr	ogress		10/16/2015 3:39:05 PM			
Flores, Pete	tractor 970 4x get repaired)	4 dont work(worked	d before they took it to			
Carlos Hernandez						
137975			8/13/2015		110	\$0.00
Medium Work In Pr	ogress Nurse office		8/13/2015 3:41:17 PN	l		
Lara, Ralph	MAKE A HANI TALL FILE CA	CE- PLEASE HAVE DLE FOR THE 2ND BINET IN THE NUR S NO HANDLE				
Maribel Gamboa						
141417 Main Build	ling		10/9/2015		53	\$0.00
Medium Work In Pr	ogress		10/9/2015 4:04:12 PN			
Ontiveros, Guadalupe	Front Entranc tree.	e - Purchase and rep	place 1 missing palm			
Alfredo Holguin						
141634			10/13/2015		49	\$0.00
High Work In Pr	ogress		10/13/2015 3:46:14 PM			
Moncayo, Fernando	ESTABLISHM ACCUMILATIO FROM SMALL	RONMENT DEPT. F ENT INSPECTION 1 DN OF BUILDUP UN LEAK - LEAK NOT PECTION. CORREC	10/13/15- IDER ICE MACHINE OBSERVED AT			
Maritza Gonzalez						
143264			11/8/2015	11/24/2015	23	\$0.00
Medium Work In Pr	ogress		11/8/2015 12:29:55 AM			
Mijarez, Jaime	Monthly-Sun PMschedule		round Insp - Refer to			
Margret Villalobos						
141950			10/19/2015		43	\$0.00
Medium Work In Pr	ogress		10/19/2015 3:36:43 PM			
Ronquillo, Ruben		blatform and one cra inqullio was going to red up)				
Carlos Hernandez						

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order I Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES					
136740			7/30/2015		124		\$0.00
Medium	Work In Progress		7/30/2015 11:23:17 AN	I			
Ronquillo,	Ruben	need platforms for bridge brol	ken(hazard)				
Carlos Hei	rnandez						
142735			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:29 AN	I			
Orozco, Da	niel	Monthly-Sunland Park ES Fire Refer to PMschedule details.	e Suppression Insp				
Margret Vil	lalobos						
142712			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:13 AN	l			
Orozco, Da		Monthly-Sunland Park ES Ra Refer to PMschedule details.	nge Hood Cleaning -				
Margret Vill 141381	lalobos		10/9/2015		53		\$0.00
Medium	Work In Progress		10/9/2015 3:31:47 PM	1	55		ψ0.00
	-	floor tile in both room pood to b		I			
Estrada, Je		floor tile in bathroom need to b	e replaced in room 38				
Carlos Hei 141382	rnandez		10/9/2015		53		\$0.00
Medium	Work In Progress		10/9/2015 3:32:56 PM	1	00		φ0.00
	U U	tile in main office bethroom no		ı			
Estrada, Je		tile in main office bathroom ne	eus lo be replaced				
Carlos Hei 141361	mandez		10/9/2015		53		\$0.00
Medium	Work In Progress		10/9/2015 1:05:26 PM	1			ψυιου
Estrada, Je	-	need tile replaced in bathroon					
Carlos Hei		need the replaced in bathloon					
144032	manuez		11/30/2015		1		\$0.00
Medium	Work In Progress		11/30/2015 3:01:58 PM				·
Estrada, Je	-	portable-D will need to have care replaced.					
Jaime Mija	arez						
143216	Main Building	Custodial	11/6/2015		25		\$0.00
Medium	Work In Progress		11/6/2015 1:15:41 PM	1			
Carbajal, J	limmy	requesting special dolly to mo	ove fire proff cabinets				
Jesus Luc	ero						

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status WOID Building Area Deferred By Until Request Date Target Comp Date Days Labor							Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	e Actual Comp Date	Aged	Hours	
Assigned To		Description			Action Taken			
Requester	Name							
Location:	Sunland	Park ES						
143107	Main Building	Custodial		11/5/2015	5	26		\$0.00
Medium	Work In Progress			11/5/2015 10:18:09 AI	M			
Carbajal,	limmy		w automatic scrubbe ould not be fixed thank					
Jesus Luc	ero							
142839				11/1/2015	5 11/7/2015	30		\$0.00
Medium	Work In Progress			11/1/2015 12:55:38 A	M			
Mijarez, Ja	ime	Monthly - Sunla Refer to PMsch	and Park ES Monthly nedule details.	FE Inspection -				
Margret Vil	llalobos							
136915				8/2/2015	5	121		\$0.00
Medium	Work In Progress			8/2/2015 12:32:05 A	M			
Vallejo, All	pert	Yearly - Sunlar to PMschedule	nd Park ES Fire Ext. Ir e details.	nsp. (Yearly) - Refer				
Margret Vil	llalobos							
Count: 31	Work Orders	Α	vg. Age of WO's 45	5	Total for Sunland Pa	rk ES	0	\$0.00

Priority Assigned		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester	Name Sunrise I						
136916			8/2/2015		121		\$0.00
Medium	Work In Progress		8/2/2015 12:32:06 AN	I			\$0.00
Vallejo, Alt	-	Yearly - Sunrise ES Fire Ext. Insp. (Y PMschedule details.					
Margret Vil	lalobos						
137924			8/13/2015		110		\$0.00
Medium	Work In Progress		8/13/2015 10:00:04 AN	l			
Orozco, Da		BASEBOARDS IN LAUNDRY ROOM OFF. SNP MANAGER GLENDA G. 82					
Maritza Go	nzalez			/			
142713			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:14 AN	1			
Orozco, Da		Monthly-Sunrise ES Range Hood Cl PMschedule details.	eaning - Refer to				
Margret Vil	lalobos		11/10/0015		10		.
143785			11/18/2015		13		\$0.00
Medium	Work In Progress		11/18/2015 3:03:29 PM				
Carrasco,	Danny	need gas for truck and two blowers					
Juan Varga	as						
142736			11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress		11/1/2015 12:54:29 AN	l			
Orozco, Da		Monthly-Sunrise ES Fire Suppression PM schedule details.	on Insp Refer to				
Margret Vil	lalobos		11/17/2015		14		\$0.00
143714					14		ֆ 0.00
Medium	Work In Progress		11/17/2015 3:17:58 PM				
Vargas, Ju		need replace a/c unite circulator wat 211	er pomp in room				
Juan Varga	as		44/40/0045		04		<u> </u>
143389			11/10/2015		21		\$0.00
Medium	Work In Progress		11/10/2015 2:53:26 PM				
Marquez, C		nick, el custodian need replace mate problems to open classrooms	erkeyhave				
Juan Varga	as		11/9/2015		22		¢0.00
143329					22		\$0.00
Medium	Work In Progress		11/9/2015 3:43:06 PM	1			
Appelzolle		stafflonge room need replace sick	foucet				
Juan Varga	as						

WOID	Building	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By	Until Request Date T	arget Comp Date		Labor Hours	Costs
Priority	Status	Area Number Reason	Created Date/Time	lotaal oomp Date	Ageu r	1001 5	
Assigned Requester		Description		Action Taken			
Location:	Sunrise I						
	50111361						
142690			11/1/2015		30		\$0.00
Medium	Work In Progress		11/1/2015 12:53:59 AM				
Vargas, Ju	Jan	Yearly - Sunrise ES - Grease Trap schedule details.	> - Refer to PM				
Margret Vi	llalobos						
139884			9/14/2015		78		\$0.00
Medium	Work In Progress		9/14/2015 10:06:24 AM				
Chavez, S	antos	need replace 4 hand dryer in300 to cafeteria grls.r.room	boys r.room and next				
Juan Varg	jas						
141530			10/12/2015		50		\$0.00
Medium	Work In Progress		10/12/2015 3:27:44 PM				
Chavez, S	antos	need replace outlet in kitchen cas	hermachine				
Juan Varg	jas						
141533			10/12/2015		50		\$0.00
Medium	Work In Progress		10/12/2015 3:30:38 PM				
Chavez, S	antos	need fixoutside lights in front park	king				
Juan Varg	las						
138842	·		8/27/2015		96		\$0.00
Medium	Work In Progress		8/27/2015 7:45:20 AM				
Chavez, S	antos	need fixout side lights in front park	king				
Juan Varg			-				
	Work Orders	Avg. Age of WO's	51	Total for Sunrise	ES	0	\$0.00

Priority Assigned	Status To	Area Area Number Description	Deferred By Reason	Until Crea	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester									
Location:	Vado ES								
138946					8/28/2015		95		\$0.00
Medium	Work In Progress			8/28/2	2015 1:47:51 PN	1			
Chavez, S	antos	need 3 shatterl walk in and free	ess safetylight bulbs zers	s 75 watts for	kitcen				
Danny Mir	anda								
143363					11/10/2015		21		\$0.00
Medium	Work In Progress			11/10/2	2015 7:56:40 AM	1			
Appelzolle	r, Fred	need to replace	booster pump in 10	0-wing boile	r room				
Danny Mir	anda								
142686					11/1/2015		30		\$0.00
Medium	Work In Progress			11/1/20	015 12:53:56 AM	1			
Miranda, D	Danny	Yearly - Vado E details.	S - Grease Trap - R	tefer to PM s	chedule				
Margret Vi	lalobos								
140859					10/4/2015	10/25/2015	58		\$0.00
Medium	Work In Progress			10/4/20	015 12:38:10 AM	1			
Orozco, Da	aniel	Monthly - Vado Refer to PMsch	ES F-39 Kitchen Ext nedule details.	n Unit Semia	innual -				
Margret Vi									
144038	Main Building	Computer Lab			11/30/2015		1		\$0.00
Medium	Work In Progress	300		11/30/2	2015 3:40:15 PM	l			
Solis, Lore		Our new comp lower the temp	uter lab is very hot.	We are unat	le to				
Reyes Val	tierra								
143177					11/6/2015		25		\$0.00
Medium	Work In Progress			11/6/2	2015 8:21:21 AN	1			
Solis, Lore	ozn	need to ck. unit cold all the time	t in library north side e	will not turn	off on				
Danny Mir	anda								
142737					11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress			11/1/20	015 12:54:30 AN	1			
Orozco, Daniel		Monthly - Vado schedule detail	ES Fire Suppressio s.	n Insp Ref	er to PM				
Margret Vi	lalobos								

OOZ - WOIK OIGETS III PIOGRESS (FISCAL TEAL) Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status WOID Building Area Deferred By Until Request Date Target Comp Date Days Labo						Labor	Total Costs	
Priority	Status	Area Number	•	Created Date/Time	•	Aged	Hours	
Assigned		Description	ite de com		Action Taken			
Requeste								
Location:	Vado ES							
142714				11/1/2015	11/22/2015	30		\$0.00
Medium	Work In Progress			11/1/2015 12:54:15 AN	Λ			
Orozco, Da	aniel	Monthly - Vado schedule detai		Cleaning - Refer to PM				
Margret Vi	illalobos							
144077				12/1/2015		0		\$0.00
Medium	Work In Progress			12/1/2015 7:44:42 AN	Λ			
Orozco, Da	aniel		OT HEATING PRO ZABETH M. 233.29	-				
Maritza Go	onzalez							
136917				8/2/2015		121		\$0.00
Medium	Work In Progress			8/2/2015 12:32:06 AN	Λ			
Vallejo, Al	bert	Yearly - Vado E schedule detai		∕early) - Refer to PM				
Margret Vi								
142950	Main Building	Custodial		11/3/2015		28		\$0.00
Medium	Work In Progress			11/3/2015 9:28:28 AN	Л			
Carbajal,	Jimmy	Propane burnis	sherwon'tstart!					
Armando	Diaz							
Count: 11	Work Orders	Α	vg. Age of WO's	40	Total for Vac	lo ES	0	\$0.00
Count: 80	62 Work Orders	A	/g. Age of WO's	48	Grand Total		1	\$25.00