**Total** Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Priority Status Assigned To Description Action Taken** Requester Name Location: **Location Not Assigned** 145496 1/4/2016 15 \$0.00 Medium Work In Progress 1/4/2016 12:38:42 AM Monthly - District Tractors - Full Service PM - Refer to Flores, Pete PMschedule details. Margret Villalobos Count: 1 Work Orders Avg. Age of WO's 15 Total for <Blank> 0 \$0.00

1/19/2016 11:45:12 AM Page 1 of 153

David Soriano

WOID Priority Assigned	Building Status To	Area Deferred By Area Number Reason Description	Until Request Date 1 Created Date/Time /	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester	Name						
Location:	Alta Vista	Early College HS					
145920			1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress		1/10/2016 12:27:45 AM				
Soriano, D	Pavid	Monthly - QRTLY BLDG INSP RE PMschedule details.	PORT (DP) - Refer to				
Margret Vi	llalobos						
143208			11/6/2015		74		\$0.00
Medium	Work In Progress		11/6/2015 11:55:58 AM				
Vallejo, All	bert	Roof Leak in the Library. It is right table where computers are. Also #6. Leak is right next to teachers	roof leak in portable				
David Sori							
140093	Curriculum and	Classroom	9/16/2015		125		\$0.00
Medium	Work In Progress	202	9/16/2015 3:42:45 PM				
Lara, Ralp	h	NEED TO CHANGE DOOR CYLII ROOM 202 FROM 203 FROM X3 ONLY. CYLINDER NEEDS TO H ON BOTH SIDES. FOR FURTHE INFORMATION, PLEASE CONTA SALCEDO AT 882-6400.	3 TO MASTER KEY AVE KEY ACCESS ER DETAILS AND				
Yvette Cor	tez						
145378			1/3/2016		16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:19 AM				
Ronquillo	Ruben	Monthly - Alta Vista ECHS - (Qtrly) to PMschedule details.	) Fitness Equip - Refer				
Margret Vi	llalobos						
142369			10/27/2015		84		\$0.00
Medium	Work In Progress		10/27/2015 8:43:13 AM				
Soriano, D	avid	3-42x29 window blinds 2-48x48 window blinds					
David Sori	ano						
142305			10/26/2015		85		\$0.00
Medium	Work In Progress		10/26/2015 11:40:36				
Soriano, D	avid	2- Melnor Y Shut-Off 2-Way Metal	Hose Connector				

1/19/2016 11:45:12 AM Page 2 of 153

WOID	Building	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Da	te Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason Created Date/Tim	e Actual Comp Date	Aged	Hours	
Assigned		Description	Action Taken			
Requester	r Name					
Location:	Alta Vista	a Early College HS				
142306		10/26/20	15	85		\$0.00
Medium	Work In Progress	10/26/2015 11:51	47			
Soriano, D	Pavid	2 Boxes-#6 x2 in. Phillips Bugle-Head Coarse Thread Sharp Point Gold Screw (1 lbPack)				
		2 Boxes-#8 3 in. Philips Bugle-Head Coarse Thread Wood Screws (1 lbPack)				
		2 Boxes - #6 x1-5/8 in. Philips Bugle-Head Coarse Thread Gold Screw				
David Sori	iano	40/00/00	15	04		<u></u>
142013		10/20/20		91		\$0.00
Medium	Work In Progress	10/20/2015 2:25:50 F	PM			
Soriano, D		<ul><li>4- White Heavy Duty Shelf and Rod Support</li><li>3- Concrete Mix Sacks</li></ul>				
David Sori	iano	0/00/00		440		<b>#</b> 0.00
140462		9/23/20		118		\$0.00
Medium	Work In Progress	9/23/2015 8:58:29	AM			
Soriano, D	David	10-2x4x8 Studs to hang up window blinds				
David Sori	iano					
139734		9/10/20	15	131		\$0.00
Medium	Work In Progress	9/10/2015 2:27:06	PM			
Soriano, D	David	<ul> <li>4 - 9 in. Roller Covers</li> <li>4 - 2 in. Roller Covers</li> <li>1 - 2 in. Roller</li> <li>1 - 10 oz Caulking Gun</li> <li>1 - 4-in Metal Twist Nozzle (for Garden Hose)</li> </ul>				
David Sori	iano					
139907		9/14/20	15	127		\$0.00
Medium	Work In Progress	9/14/2015 2:04:54	PM			
Soriano, D	David	10 - Ballaster 4 lamp 110 v				
David Sori	iano					
139349		9/4/20	15	137		\$0.00
Medium	Work In Progress	9/4/2015 10:38:51	AM			
Soriano, D	David	25ft - 3/8 Plastic hose 25ft - 1/2 Plastic Hose				
		5- (3/8 - 7/8) Hose Repair Clamp				

1/19/2016 11:45:12 AM Page 3 of 153

**David Soriano** 

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loc Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		Early College HS					
139356			9/4/2015		137		\$0.00
Medium	Work In Progress		9/4/2015 11:07:10 AM	1			
Soriano, D	avid	24 Hex Bolts with washer and nuts 1/2 in. length)	(size - 1/4 in width x				
		2 Carriage bolts 3/8 in width x 2 1/2 washers and nuts	2 length) with				
David Sor	ano						
144961			12/14/2015		36		\$0.00
Medium	Work In Progress		12/14/2015 12:39:25	i			
Soriano, D		<ul><li>10- Electronic Ballast for 4 ft. 4-Lar</li><li>6- Electronic Ballast for 4 ft. 2-Lan</li></ul>					
David Sor	ano		0/4.4/0045		4.07		Φο οσ
139910		Library	9/14/2015		127		\$0.00
Medium	Work In Progress		9/14/2015 2:11:00 PM	1			
Soriano, D	avid	25 Pack assorted wire connectors ( [Please include the green ones for the content of the content					
David Sor	ano						
146209			1/14/2016		5		\$0.00
Medium	Work In Progress		1/14/2016 9:51:31 AM	1			
Soriano, D	avid	PVC cement and primer to fix ruptu	red water pipe				
David Sor	ano						
143206		Parking Lot	11/6/2015		74		\$0.00
Medium	Work In Progress		11/6/2015 11:43:48 AM	1			
Soriano, D	avid	4 - Flat Bar 17 x 1 x 1/8 8 - Carriage Bolts with nuts ( 1 1/2 i	n x 3/8)				
David Sor	ano						
143189			11/6/2015		74		\$0.00
Medium	Work In Progress	Teacher's	11/6/2015 10:17:42 AM	1			
Villalobos	, David	PLEASE INVESTIGATE THE POSSI INSTALLING A SMALL BAR SINK IN EATING AREA FOR THE PURPOSE HANDS AND CLEANING MAINTEN	I THE TEACHER'S E OF WASHING				
Yvette Cor	tez						
145500		Parking Lot	1/4/2016		15		\$0.00
Medium	Work In Progress		1/4/2016 6:33:17 AM	1			
Villalobos		Need plumber to repair pvc pipe that holidays.	truptured during the				
David Sor	ano						
1/19/2016	11:45:12 AM					Dogo	4 of 153

1/19/2016 11:45:12 AM Page 4 of 153

WOID Priority	e Range for Request Building Status	Area Area Number	Deferred By			Days Aged	Labor Hours	Costs
Assigned 1 Requester		Description			Action Taken			
Location:		a Early College HS	•					
145871	Storage B-	Gym		1/8/2016		11		\$0.00
Medium	Work In Progress			1/8/2016 11:36:00 AM	1			
Chavez, Sa	ntos	Alta Vista (hwy 2 portable	8) Need 60A breal	ker panel for P.E.				
Santos Ch	avez							
146127				1/13/2016		6		\$0.00
Medium	Work In Progress			1/13/2016 7:58:43 AV	1			
Vallejo, Alb	ert	Upgrade electric	al service for porta	bles.				
Albert Valle	ejo							
146211	Storage B-	Hallway/Corrido	r	1/14/2016		5		\$0.00
Medium	Work In Progress			1/14/2016 10:16:12 AV	1			
Ambriz, Jos	se	Heater is not wo	rking properly					
David Soria	ano							
136834		Office		7/31/2015		172		\$0.00
Medium	Work In Progress	FRONT OFFICE		7/31/2015 10:03:35 AM	1			
Marquez, G	Serardo	AREA AT ANNE	KBUILDING. FOR FORMATION, PLEA					
Yvette Cort	ez							
146193				1/14/2016		5		\$0.00
Medium	Work In Progress			1/14/2016 12:30:52 AM	1			
Sanchez, F	aul	Monthly - Alta Vi schedule details		Filters - Refer to PM				
Margret Vil	alobos							
143993		Classroom		11/30/2015		50		\$0.00
Medium	Work In Progress			11/30/2015 7:30:49 AM	1			
Gonzalez,	Salvador	Need rail to be w	elded					
David Soria	ano							
146067		Parking Lot		1/12/2016		7		\$0.00
Medium	Work In Progress			1/12/2016 2:26:28 PM	1			
Soriano, D	avid	18ft uni-strut to	nang up sings in pa	arking lot.				
David Soria	ano							

1/19/2016 11:45:12 AM Page 5 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Deferred By Request Date Target Comp Date** Area Until **Days** Labor Hours Aged Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: Alta Vista Early College HS 146141 1/13/2016 6 \$0.00 Medium Work In Progress 1/13/2016 11:02:07 AM Soriano, David 10 ft- 3/4 sch. 40 pvc pipe 1 - 3/4 sch. 40 pvc coupling 1 - 3/4 sch. 40 pvc male adapter 1-3/4 in. x 6 ft. Polyethylene Pipe Wrap Insulation **David Soriano** 136112 Curriculum and 7/20/2015 183 \$0.00 **ANNEX** Medium Work In Progress 7/20/2015 9:53:42 AM Marquez, Gerardo REPLACE OLD DOORS WITH WOOD FRAME AND GLASS DOORS AT ANNEX BUILDING. DOORS TO BE REPLACED HAVE BEEN LABELED FOR IDENTIFICATION. ANY QUESTIONS, PLEASE CONTACT YVETTE OR GEMA AT AVECHS 882-6400. Yvette Cortez 7/14/2015 189 \$0.00 135852 Medium Work In Progress 7/14/2015 12:01:35 PM Improve sidewalks at front entrance. Vallejo, Albert Albert Vallejo Count: 29 Work Orders Total for Alta Vista Early College HS \$0.00 Avg. Age of WO's 75

1/19/2016 11:45:12 AM Page 6 of 153

WOID	Building	Area Deferred By		Target Comp Date	Days Aged	Labor Hours	
Priority	Status	Area Number Reason	Created Date/Time	•	Ageu	nours	
Assigned Requeste		Description		Action Taken			
Location:	Anthony	- On Track Pre-K (Village)					
146343		Classroom	1/19/2016		0		\$0.00
Medium	Work In Progress	882-1904	1/19/2016 8:47:32 AN	1			
Nunez, Ar	turo	please check for mice in room	110				
Laura Vaz	zquez						
145789			1/7/2016		12		\$0.00
Medium	Work In Progress	882-1904	1/7/2016 11:35:19 AN	1			
Nunez, Ar	turo	bolt down big red tube that in questions ask Ms. Sandy	the pre-k playground any				
Laura Vaz	zquez						
138101			8/14/2015		158		\$0.00
Medium	Work In Progress	FAMILY	8/14/2015 4:38:22 PM	1			
Nunez, Ar	turo	Paint behind the T.V on the w	all.				
Noemi Du	ıron						
138597		Classroom	8/24/2015		148		\$0.00
Medium	Work In Progress	ANTHONY	8/24/2015 3:12:32 PM	1			
Nunez, Ar	turo	PLEASE PAINT AN INSIDE OF DRY ERASE BOARD WAS RE ANTHONY FAMILY LITERACY JUANA ESPINOZA @ EXT.442 EXT.6799 FOR FURTHER INF	MOVED AT THE CENTER. CONTACT 20 OR RAY LARA @				
Karla Que	esada						
143774			11/18/2015		62		\$0.00
Medium	Work In Progress		11/18/2015 11:54:01				
Solis, Lore	en <i>z</i> o	Need some assistance on H.\ heating system in room #107,	•				
Arturo Nu	nez						
142861			11/2/2015		78		\$0.00
Medium	Work In Progress		11/2/2015 9:20:52 AV	1			
Solis, Lore	en <i>z</i> o	Need some assistance on troon F.C.U. in room # 107.	uble shooting water leak				
Arturo Nu	nez						
143784			11/18/2015		62		\$0.00
Medium	Work In Progress	882-1904	11/18/2015 2:32:43 PM	I			
Marquez,	Gerardo	Install chains furnished and w	eld on to gates please				
Laura Vaz	70UE7						

1/19/2016 11:45:12 AM Page 7 of 153

WOID Priority Assigned Requester		Dates://1/2015 - 6 Area Area Number Description	Deferred By	Until Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		On Track Pre-l	(Village)					
144025				11/30/2015		50		\$0.00
Medium	Work In Progress			11/30/2015 2:00:33 PN				*****
Chavez, S	-	Install wall nac	ks around building.					
Albert Valle		inotan wan pao	no around banding.					
142145	6,0			10/22/2015		89		\$0.00
Medium	Work In Progress			10/22/2015 10:34:3 <sup>-</sup>				
Ontiveros,	-	Admin Portable	- water fountain (ex	terior) does not work.				
Albert Valle		/ dillilli oldbic	water louritain (ex	ichor) does not work.				
135840	ејо			7/14/2015		189		\$0.00
Medium	Work In Progress	FAMILY		7/14/2015 10:02:19 AN				
Nunez, Art	_	INSTALL TOILI	ET SEAT DISPENSE FROOMS.		10/9/15 - waiting for p	parts		
Noemi Du	ron							
136332		Cafeteria		7/23/2015		180		\$0.00
Medium	Work In Progress	882-1904		7/23/2015 12:06:53 PN	1			
Nunez, Art	uro	doors from roo	m 101 and 102 need	l a weather strip				
Laura Vaz	quez							
146056				1/12/2016	i	7		\$0.00
Medium	Work In Progress	882-1904		1/12/2016 12:11:15 PN	1			
Nunez, Art	uro		the water fountains	ront of room 111 and thank you any				
Laura Vaz	quez							
144270				12/3/2015		47		\$0.00
Medium	Work In Progress			12/3/2015 10:35:43 AN	Л			
Nunez, Art	uro	the pre k class r teachers and l	rooms room 111,11	e on the other side of 0, 109 and 108 the e in that side so they				
Laura Vaz	quez							
137103				8/3/2015		169		\$0.00
Medium	Work In Progress			8/3/2015 2:08:08 PM	М			
Ontiveros,	Guadalupe	Please trim tre thank you.	es that are in the fro	ont office				

1/19/2016 11:45:12 AM Page 8 of 153

Laura Vazquez

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Status Priority Assigned To Description Action Taken** Requester Name Location: Anthony - On Track Pre-K (Village) 145873 1/8/2016 \$0.00 Medium Work In Progress 882-1904 1/8/2016 1:39:36 PM shampoo carpetin room 108 a child had an accident on Vega, David it... will be the one in blocks center any question ask teacher Ms. Liz or Ms. Arely Laura Vazquez **Count: 15 Work Orders** 0 \$0.00 Avg. Age of WO's 84 Total for Anthony - On Track Pre-K (Village)

1/19/2016 11:45:12 AM Page 9 of 153

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2 Area De: Area Number Re: Description	ferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	ES						
145927				1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/2016 12:27:50 AM				
Vega, Dav	id	Monthly - QRTLY BI PMschedule details		PRT (AE) - Refer to				
Margret Vi	lalobos							
145345				1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:43:49 AM				
Nunez, Art	uro	Monthly - Anthony E schedule details.	S Roof Inspection	on - Refer to PM				
Margret Vi	lalobos							
144635				12/8/2015		42		\$0.00
Medium	Work In Progress			12/8/2015 8:04:05 AM				
Flores, Pe	te	The speedometer a properlyin district a issues because the speed and the odor traveled.	ssigned car#13 espeedometer is	These are safety not monitoring				
Susie Rar	nos Lara							
142974				11/3/2015		77		\$0.00
Medium	Work In Progress			11/3/2015 3:34:29 PM				
Nunez, Art	uro	Circulating hot water pumps are bad.	er pumps need to	be replaced both				
Arturo Nur	iez							
145404				1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:44:43 AM				
Nunez, Art	uro	Monthly - Anthony E to PMschedule deta		est: Monthly - Refer				
Margret Vi	lalobos							
145405				1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:44:44 AM				
Nunez, Art	uro	Monthly - Anthony E PMschedule details		Monthly - Refer to				
Margret Vi	lalobos							
146128				1/13/2016		6		\$0.00
Medium	Work In Progress			1/13/2016 8:14:42 AM				
Nunez, Art	uro	Need 6 ea. Trane building # x137908 you.						
Arturo Nur	107							

1/19/2016 11:45:12 AM Page 10 of 153

Total

#### 952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Davs** Labor Area **Deferred By** Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Assigned To** Description **Action Taken** Requester Name Location: Anthony ES 141174 **Annex Building** Office 10/6/2015 105 \$0.00 10/6/2015 4:15:23 PM Medium Work In Progress Nunez, Arturo Please set up: 2 New employees need a work area to be set up in the room that is close to the office. Need desk and cabinets to be moved in to that room to set up as a 2 person office. We also need for some storage cabinets, desks etc to be moved out of those offices and set up in the hallways. For additional information please stop by to see Susie or Mary. Thank you. Susie Ramos Lara Office Office 9/21/2015 120 \$0.00 140303 Medium Work In Progress 9/21/2015 2:35:09 PM Nunez, Arturo Need to move one brown desk and file cabinet to room 109. The desk and file cabinet are located in the front office area. This office needs to be set up for our new staff member. Susie Ramos Lara 140304 Office Office 9/21/2015 120 \$0.00 9/21/2015 2:36:19 PM Medium Work In Progress Nunez, Arturo Need to move one file cabinet to room 118. This cabinet is located near the front office. If you need information please ask Mary Bonet. Susie Ramos Lara 140305 Office Office 9/21/2015 120 \$0.00 9/21/2015 2:37:36 PM Medium Work In Progress Nunez. Arturo Need to move two storage cabinets to room 110. These cabinets are located near the front office. If you need information please ask Mary Bonet. Susie Ramos Lara 140307 Office Office 9/21/2015 120 \$0.00 Medium Work In Progress 9/21/2015 2:40:07 PM Nunez, Arturo Need to set up new office furniture in the little cottage in the sped office. Please check in with Mary Bonet for information on the set up. Susie Ramos Lara Office 139297 9/3/2015 138 \$0.00 Medium Work In Progress 9/3/2015 1:41:36 PM Need to have someone come in an replace all the air Nunez, Arturo conditioner grills in the SPED ADMIN OFFICES. Susie Ramos Lara

1/19/2016 11:45:12 AM Page 11 of 153

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	ES .				
142485		10/28/2015		83		\$0.00
Medium	Work In Progress	10/28/2015 3:28:10 PM	1			
Ontiveros,	_	Need some assistance on checking and, and draining hot water storage tanks.				
Arturo Nur	nez					
146288		1/15/2016		4		\$0.00
Medium	Work In Progress	1/15/2016 11:56:15 AN	1			
Ontiveros,	,Joe	Need assistance on checking for problem with no water in lavatories in boys restrooms.				
Arturo Nur	nez					
145309		1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress	1/3/2016 12:43:19 AN	1			
Nunez, Art	turo	Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.				
Margret Vi	llalobos					
143850		11/19/2015		61		\$0.00
Medium	Work In Progress	11/19/2015 2:20:05 PM	l			
Vallejo, All	bert	Repair main domestic backflow preventer.				
Albert Vall	ejo					
144956		12/14/2015		36		\$0.00
Medium	Work In Progress	261 12/14/2015 11:39:15	;			
Chavez, S		Please replace light bulb in room #261 V. Ramos				
Jessica Lo	opez	40/4/2045	44/4/2045	407		<u>Фо оо</u>
140839		10/4/2015	11/4/2015	107		\$0.00
Medium	Work In Progress	10/4/2015 12:37:56 AV				
Nunez, Art		Yearly - Anthony ES H6 (Furnace Gas)(Yearly) - Refer to PMschedule details.				
Margret Vi	llalobos	4/40/0040				<u>Фо оо</u>
146134		1/13/2016	_	6		\$0.00
Medium	Work In Progress	1/13/2016 9:17:47 AV				
Nunez, Art	turo	As per Ms. Perez please check unit AHU-3 lower grade wing, room numbers 262 and 259 are very cold or hot thank you				
Jessica L	opez					
143685		11/16/2015		64		\$0.00
Medium	Work In Progress	11/16/2015 4:19:44 PM	l			
Marquez, 0	Gerardo	Please cut extra keys for Alamo Cafeteria.				
Albert Vall	ejo					
	5 11:45:12 AM				Page 1	12 of 153

1/19/2016 11:45:12 AM Page 12 of 153

WOID	Building	Dates:7/1/2015 - 6/30/2016 Order By Loca Area Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned <sup>*</sup>	Го	Description		<b>Action Taken</b>			
Requester	Name						
Location:	Anthony	ES					
144923			12/13/2015	12/29/2015	37		\$0.00
Medium	Work In Progress		12/13/2015 12:30:15				
Nunez, Art	uro	Monthly - Anthony ES Monthly Playg to PMschedule details.	round Insp Refer				
Margret Vil	lalobos						
145946			1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress		1/10/2016 12:28:04 AM	I			
Nunez, Art	uro	Monthly - Anthony ES Monthly Playg to PMschedule details.	round Insp Refer				
Margret Vil	lalobos						
145966		Classroom	1/11/2016		8		\$0.00
Medium	Work In Progress		1/11/2016 8:19:31 AM	I			
Ronquillo,	Ruben	Need to replace the blinds in room 1 room is used as a training/work roor department throughout the district					
Susie Ran	nos Lara						
145986			1/11/2016		8		\$0.00
Medium	Work In Progress		1/11/2016 11:33:09 AM	I			
Ronquillo,	Ruben	Need to replace the blinds in the follo Office 101, 119, 111, 109, 110 and					
Susie Ran	nos Lara						
146138			1/13/2016		6		\$0.00
Medium	Work In Progress		1/13/2016 10:23:03 AM	I			
Orozco, Da	niel	Could you put a work order for the dis vacuum breaker and the rinse jets no SNP Manager Lorena B. 882.3507					
Maritza Go	nzalez						
136796			7/30/2015		71		\$0.00
Medium	Work In Progress		7/30/2015 3:53:27 PM	1 10/9/2015			
Holguin, A	fredo	Need to have a fire sprinkler connectroom # 107. leaking prettybad.	tion repaired in	will fax to dimar for o	quote as	per alfred	lo
Arturo Nun	ez						
136827			7/31/2015		172		\$0.00
Medium	Work In Progress	107	7/31/2015 9:04:38 AM	I			
Nunez, Art	uro	Mr. Nunez, Please move white board to a differe Please see Ms. GibsonRoom #107	ent location				

1/19/2016 11:45:12 AM Page 13 of 153

WOID Priority Assigned <sup>-</sup> Requester		Area I Area Number I Description	Deferred By Reason	Until Request Da Created Date/Tir	ne Actu	et Comp Date lal Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Anthony	ES							
145480				1/3/20	16	1/9/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:45:57	AM				
Nunez, Artı	uro	Monthly - Anthon PMschedule det		Inspection - Refer to					
Margret Vil	lalobos								
142697				11/1/20	)15	11/22/2015	79		\$0.00
Medium	Work In Progress			11/1/2015 12:54:03	AM				
Orozco, Da	nniel	Monthly - Anthon PMschedule det		d Cleaning - Refer to					
Margret Vil	lalobos								
146227				1/14/20	)16		5		\$0.00
Medium	Work In Progress	Portable		1/14/2016 3:00:47	PM				
Gonzales,	Camilo			ay at the Alamor need Cazares room which					
Susie Ran	nos Lara								
146040		Office		1/12/20	)16		7		\$0.00
Medium	Work In Progress	sped office		1/12/2016 8:33:55	AM				
Gonzales,	Camilo	therapy) storage room 101. Pleas	room that needs se call the main of ne pick up day so	special ed (physical s to be taken to Vado ffice at 575-882-6221 that we can have age. Thank you.					
Susie Ran	nos Lara								
145364				1/3/20	16		16		\$0.00
Medium	Work In Progress			1/3/2016 12:44:06	AM				
Vallejo, Alb	pert	Monthly - Anthon PMschedule det		kler Insp Refer to					
Margret Vil	lalobos			4.4.4.10		4.4.10.0.10.0.4.5			
142718				11/1/20		11/22/2015	79		\$0.00
Medium	Work In Progress			11/1/2015 12:54:17	AM				
Orozco, Da	nniel	Monthly - Anthon PMschedule det		ssion Insp Refer to					
Margret Vil	lalobos								<b>*</b>
145846				1/8/20			11		\$0.00
Medium	Work In Progress			1/8/2016 12:28:49	AM				
Nunez, Art	uro	Daily - Anthony E schedule details		Biweekly) - Refer to PM					

1/19/2016 11:45:12 AM Page 14 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged **Created Date/Time Actual Comp Date** Status Area Number Reason **Priority Assigned To Description Action Taken** Requester Name Location: **Anthony ES** 144709 12/9/2015 41 \$0.00 12/9/2015 12:29:43 AM Medium Work In Progress Nunez, Arturo Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details. Margret Villalobos 12/24/2015 26 \$0.00 145286 Medium Work In Progress 12/24/2015 12:29:31 Nunez. Arturo Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details. Margret Villalobos 11/24/2015 56 \$0.00 143974 Medium Work In Progress 11/24/2015 12:34:40 Nunez, Arturo Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details. Margret Villalobos **Count: 38 Work Orders** 0 \$0.00 Avg. Age of WO's 51 **Total for Anthony ES** 

1/19/2016 11:45:12 AM Page 15 of 153

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino ES					
142719		11/1/2015	11/22/2015	79		\$0.00
	Work In Drogram			13		ψ0.00
Medium	Work In Progress	11/1/2015 12:54:18 AM				
Orozco, Da		Monthly - Berino ES Fire Suppression Insp Refer to PMschedule details.				
Margret Vill	lalobos	4/0/0040	4/0.4/0.040	40		Φο οο
145358		1/3/2016	1/24/2016	16		\$0.00
Medium	Work In Progress	1/3/2016 12:44:01 AM				
Vallejo, Alb	ert	Monthly - Berino ES Fire Sprinkler Insp Refer to PM schedule details.				
Margret Vill	lalobos					
145973	Main Building	Custodial 1/11/2016		8		\$0.00
Medium	Work In Progress	1/11/2016 9:12:09 AM				
Carbajal, J	immy	vaccum cleanersmoking#do5aoooo5374				
Francisco I	Marin					
142698		11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress	11/1/2015 12:54:04 AM				
Orozco, Da	niel	Monthly - Berino ES Range Hood Cleaning - Refer to PMschedule details.				
Margret Vill	lalobos					
141139		10/6/2015		105		\$0.00
Medium	Work In Progress	10/6/2015 3:19:29 PM				
Gonzalez, S	Salvador	Need to install metal ramp on portable 18 thank you				
Sebastian	Diaz					
146103		1/12/2016		7		\$0.00
Medium	Work In Progress	1/12/2016 3:52:17 PM				
Marquez, G	· ·	Need to fix cylinder by main entrance thank you				
Sebastian		11000 to involunted by main ormanice thank you				
139809	Diaz	9/11/2015		130		\$0.00
Medium	Work In Progress	9/11/2015 12:58:12 PM				,
	_					
Solis, Lore		Need to fix water fountain on room 121 thank you				
Sebastian	Diaz	1/15/2016		1		\$0.00
146314	Martin D			4		φυ.υ0
Medium	Work In Progress	1/15/2016 3:43:34 PM				
Chavez, Sa	antos	Need to check lights on portable not power thank you				
Sebastian	Diaz					

1/19/2016 11:45:12 AM Page 16 of 153

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time A Description	arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino Es	6				
145310		1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress	1/3/2016 12:43:20 AM				
Diaz, Seba	astian	Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.				
Margret Vi	llalobos					
143635		11/16/2015		64		\$0.00
Medium	Work In Progress	11/16/2015 1:38:26 PM				
Chavez, S	antos	Need to check hand dryer on boy's restroom thank you				
Sebastian	Diaz					
139814		9/11/2015		130		\$0.00
Medium	Work In Progress	9/11/2015 2:31:31 PM				
Chavez, S	antos	Need to install power for smart board on room 101 thank you				
Sebastian	Diaz					
140256		9/18/2015		123		\$0.00
Medium	Work In Progress	9/18/2015 3:36:56 PM				
Chavez, S	antos	need to fix light on room 10 thank you				
Sebastian	Diaz					
143637		11/16/2015		64		\$0.00
Medium	Work In Progress	11/16/2015 1:41:51 PM				
Ontiveros,	Joe	Need check leak water on boiler pipes thank you				
Sebastian	Diaz					
144663		12/8/2015		42		\$0.00
Medium	Work In Progress	12/8/2015 3:04:59 PM				
Ontiveros,	Joe	Need to check boiler domestic water not turn on thank you				
Sebastian	Diaz					
145938		1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress	1/10/2016 12:27:58 AM				
Marin, Fra	ncisco	Monthly - QRTLY BLDG INSP REPORTS (BE) - Refer to PMschedule details.				
Margret Vi	llalobos					
Count: 15	Work Orders	Avg. Age of WO's 58	Total for Berin	o ES	0	\$0.00

1/19/2016 11:45:13 AM Page 17 of 153

Location: 142468 Medium Carbajal, Ji Daniel Ran	<b>Chaparra</b> Work In Progress immy	I ES Custodial					
Medium Carbajal, Ji	· ·	Custodial					
Carbajal, Ji	· ·			10/28/2015		83	\$0.00
-	immy			10/28/2015 10:25:44			
Daniel Ran		need,four,vacc	um,belts.				
	nirez						
145926				1/10/2016	1/26/2016	9	\$0.00
Medium	Work In Progress			1/10/2016 12:27:49 AM			
Ramirez, D	aniel	Monthly - QRTL PMschedule d		PORT (CE) - Refer to			
Margret Vill	alobos						
146341	East Central	Classroom		1/19/2016		0	\$0.00
High	Work In Progress	402		1/19/2016 8:26:54 AM			
Vallejo, Alb	ert	•	ible mold in the clas as soon as possible				
Jennifer Co	orral						
145069	Main Building	Hallway/Corrid	lor	12/15/2015		35	\$0.00
Medium	Work In Progress	school hallway	S	12/15/2015 3:11:54 PM			
Quinones,	Paul		ut up pennants throi on as possible. See	ughoutschool e Mrs. Pargas or Ms.			
Jennifer Co	orral						
146199				1/14/2016		5	\$0.00
Medium	Work In Progress			1/14/2016 8:21:35 AM			
Quinones,	Paul	reordering plur rings clost bolts	mbing materials tan	k levers, fill valves ,wax			
Paul Quino	nes						
145792				1/7/2016		12	\$0.00
Medium	Work In Progress			1/7/2016 12:33:17 PM	1		
Quinones,	Paul	requesting hea replace broken	ating onlythermosta ones.	ts 24 volt type,to			
Paul Quino							
146277	E.Building	Restroom		1/15/2016		4	\$0.00
High	Work In Progress	Ewing		1/15/2016 8:09:44 AM			
Quinones,	Paul	The restroom h	nas a leakage. Need Administration	l fixed as soon as			

1/19/2016 11:45:13 AM Page 18 of 153

Selected Dat WOID Priority Assigned 1 Requester	Building Status o	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	II ES					
146251			1/14/2016		5		\$0.00
Medium	Work In Progress		1/14/2016 3:47:59 PM				
Appelzoller	, Fred	custodial closet in front lobby,wate	r faucet leaking water.				
Paul Quinc	nes						
145308			1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:43:18 AM				
Quinones,	Paul	Yearly - Chaparral ES Backflow In schedule details.	spection - Refer to PM				
Margret Vill	alobos						
143176			11/6/2015		74		\$0.00
Medium	Work In Progress		11/6/2015 8:16:47 AM				
Solis, Lore	nzo	need a recessed or surface typ ele 200/400 watt,requesting 1 208/240					
Paul Quinc	nes						
143180			11/6/2015		74		\$0.00
Medium	Work In Progress		11/6/2015 8:29:44 AM				
Solis, Lore		needing filter material for heaters h 1/2".thank you.	nogs hair 1 rl.				
Paul Quino		Classican	1/14/2016				ФО OO
146204	Main Building	Classroom			5		\$0.00
Medium	Work In Progress	108	1/14/2016 8:33:37 AM				
Solis, Lore		heater does not stop, it just heats u	ıp. See Ms. Jimenez				
Jennifer Co							
146205	Main Building	Classroom	1/14/2016		5		\$0.00
High	Work In Progress	106	1/14/2016 8:34:45 AM				
Solis, Lore		heater not working, sub reported th See Ms. Foskets class	e heater not working.				
Jennifer Co			4/44/0040				<b>A</b> 0 00
146201	Main Building	Classroom	1/14/2016		5		\$0.00
High	Work In Progress	220,302,309,30	1/14/2016 8:29:26 AM				
Solis, Lore		Heater's not working in the above of see Ms. Nevarez, Mr. Ramirez, OT					
Jennifer Co		Dootroom	4/45/0040				<u>Фо оо</u>
146286	East Central	Restroom	1/15/2016		4		\$0.00
Medium	Work In Progress	boys/girls	1/15/2016 11:02:03 AM				
Marquez, G Jennifer Co		doors do not lock with key. See Dar	nnyCustodian				

1/19/2016 11:45:13 AM Page 19 of 153

WOID Priority Assigned	Building Status	Area Area Number Description	/30/2016 Order By Loc <b>Deferred By</b> <b>Reason</b>	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	Name								
Location:	Chaparra	I ES							
146215	Main Building	Hallway/Corrid	or		1/14/2016		5		\$0.00
Medium	Work In Progress	doors		1/14/2	016 10:52:46 AM	1			
Marquez, (	Gerardo		keys for Teachers wh Coach Nava, Coach						
Jennifer C	orral								
145855	Main Building	Classroom			1/8/2016		11		\$0.00
Medium	Work In Progress	414		1/8/	2016 8:15:14 AM	1			
Marquez, (		before we wen	ready but does not o on break this keyop er opens. Need new	ened the do	orand				
Jennifer C	orral				44/4/0045	44/00/0045	70		<b>ФО 00</b>
142699					11/1/2015		79		\$0.00
Medium	Work In Progress			11/1/2	015 12:54:05 AM	1			
Orozco, Da		Monthly-Chap to PMschedule	paral ES Range Hoo details.	d Cleaning ·	Refer				
Margret Vil					0/40/0045		101		Φο οο
139719	East Central	Classroom			9/10/2015		131		\$0.00
Medium	Work In Progress			9/10/	2015 9:51:47 AN	1			
Estrada, Jo	esus	Aseam is com	ing apart in class roo	m #505.					
Jesus Est	rada								
140630					9/25/2015		116		\$0.00
Medium	Work In Progress			9/25/2	015 10:42:30 AM	1			
Carbajal,	limmy	requesting new going into rest	v tile in staffs rest rms rms.	s,and floor e	ntrance				
Paul Quin	ones								
142112		Athletic Field			10/21/2015		90		\$0.00
Medium	Work In Progress			10/21/	2015 3:49:46 PM	1			
Ontiveros,	Guadalupe	Ms. Nougues is	s requesting a baseb	all field.					
Guadalup	e Ontiveros								
145523					1/4/2016		15		\$0.00
Medium	Work In Progress			1/4/	2016 9:50:23 AM	1			
Carrasco,	Danny	fuel for work tru	ıck # 7.thanks						
Paul Quine	nes								

1/19/2016 11:45:13 AM Page 20 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason **Created Date/Time Actual Comp Date Status Priority Assigned To Description Action Taken** Requester Name Location: Chaparral ES 144018 11/30/2015 50 \$0.00 11/30/2015 12:47:38 Medium Work In Progress Marquez, Gerardo requesting handicap door closer double doors next to cafeteria principle requesting door closer for handi cap student Paul Quinones Office Main Building 1/13/2016 6 \$0.00 146149 Data Clerk 1/13/2016 2:20:21 PM Medium Work In Progress Gonzales, Camilo Please pick up cume folders from data clerk office Jennifer Corral **Count: 24 Work Orders** 0 \$0.00 Avg. Age of WO's 35 **Total for Chaparral ES** 

1/19/2016 11:45:13 AM Page 21 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Status Priority Assigned To Description Action Taken** Requester Name Location: Chaparral High - Pre-K 142465 10/28/2015 83 \$0.00 Medium Work In Progress **FEDERAL** 10/28/2015 9:45:21 AM SUBURBAN STARTED BUT ALL LIGHTS WERE Flores, Pete TURNING ON AND OFF AND WAS DRIVING VERY SLOW. Noemi Duron Count: 1 Work Orders **Total for Chaparral High - Pre-K** 0 \$0.00 Avg. Age of WO's 83

1/19/2016 11:45:13 AM Page 22 of 153

Total

## 952 - Work Orders In Progress (Fiscal Year)

Priority Assigned	Status				Request Date		Days	Labor	
•	0.00.00	Area Number	Reason	Crea	=	Actual Comp Date	Aged	Hours	
	То	Description				<b>Action Taken</b>			
Requester	Name								
Location:	Chaparra	I HS							
136928					8/2/2015		170		\$0.00
Medium	Work In Progress			8/2/20	15 12:32:13 AN	1			
Flores, Pet	te	Monthly - CHS- schedule detai	-UV-0513 PM Servic ls.	ce - Refer to Pl	М				
Margret Vil	lalobos								
145941					1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/20	16 12:28:00 AN	1			
Urquidi, Je	esus	Monthly - QRTI PMschedule d	_Y BLDG INSP REP etails.	PORT (CH) - R	efer to				
Margret Vil	lalobos								
145343					1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/20	16 12:43:47 AN	1			
Ortiz, Alfred	do	Monthly - Chap schedule detai	oarral HS Roof Insp ls.	ection - Refer	to PM				
Margret Vil	lalobos								
139387					9/4/2015		137		\$0.00
Medium	Work In Progress			9/4/2	015 3:16:11 PN	Л			
Ontiveros,	Guadalupe	parking lot by th maintenance la	e shrubberyin plant ne amphitheater and andscaping. (Prima genous flora) See M estion)	d replace with I ryscreening, b	ow oulders				
Albert Valle	ejo								
146279		Athletic Field			1/15/2016		4		\$0.00
Medium	Work In Progress			1/15/2	016 8:17:54 AN	1			
Ontiveros,	Guadalupe	Need to replace condition.	e 8 long jump boar	ds ASAP. In b	ad				
Alfredo Ort	tiz								
145838	Field House	Athletic Field			1/7/2016		12		\$0.00
Medium	Work In Progress	softball field		1/7/2	016 4:02:57 PN	Л			
Ontiveros,	Guadalupe		e the softball dug ou an protect the girls fr ston, softball)						
Mireya Mez	za		·						
140161	Field House	Athletic Field			9/17/2015		124		\$0.00
Medium	Work In Progress	Football &		9/17/2	015 2:20:24 PN	Л			
Ontiveros,	Guadalupe		wind screens place ccer field areas. (Ms		ntire				
Mireya Mez	za		,	•					

1/19/2016 11:45:13 AM Page 23 of 153

WOID Priority Assigned <sup>-</sup>	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester								
Location:	Chaparra							
142462	Field House	Athletic Field		10/28/2015		83		\$0.00
Medium	Work In Progress	Baseball Field		10/28/2015 9:32:29 AM	1			
Ontiveros,	Guadalupe	Install dug out i dug outs. (Coa	nade of cinder block. ch Rojas)	In visitor and home				
Mireya Mez	za							
143601				11/15/2015		65		\$0.00
Medium	Work In Progress			11/15/2015 12:27:52	2			
Flores, Per	e	Yearly - Chapa Refer to PMsch	rral HS M-0405 (Z-T nedule details.	rack) Grounds -				
Margret Vil	lalobos							
145431				1/3/2016		16		\$0.00
Medium	Work In Progress			1/3/2016 12:45:09 AM	1			
Ortiz, Alfred	do	Monthly - Chap PMschedule d	rral HS Exit Sign Ins <sub>l</sub> etails.	p: Monthly - Refer to				
Margret Vil	lalobos							
144846				12/10/2015		40		\$0.00
Medium	Work In Progress			12/10/2015 3:55:18 PM	1			
Ortiz, Alfred	do	Need to order a outside lights.	ınd replace ballastar	nd light bulbs for				
Alfredo Ort	iz							
145600				1/5/2016		14		\$0.00
Medium	Work In Progress			1/5/2016 7:03:16 AM	1			
Vallejo, Alb	pert	Repairbroken	bleacher modules.					
Albert Valle	ejo							
145843	Q-Wing	Classroom		1/7/2016		12		\$0.00
Medium	Work In Progress	Q5		1/7/2016 4:10:52 PM	1			
Ortiz, Alfred	do		ne whiteboard on the ne west of the window					
Mireya Mez	za							
146271	E-Wing	Classroom		1/14/2016		5		\$0.00
Medium	Work In Progress	E5		1/14/2016 4:02:06 PM	1			
Ortiz, Alfred	do	Please install r work. (Ms. Pav	netal strip to hold and lis, E5)	ddisplaystudents				
Mireya Mez	za	`	•					

1/19/2016 11:45:13 AM Page 24 of 153

WOID	Building	Area Deferred By		Target Comp Date	A		
Priority	Status	Area Number Reason	Created Date/Time	·-	Agea	Hours	
Assigned 1		Description		Action Taken			
Requester	Name						
Location:	Chaparra	al HS					
145970	E-Wing	Hallway/Corridor	1/11/2016		8		\$0.00
Medium	Work In Progress		1/11/2016 8:38:16 AM				
Ortiz, Alfred	do	Need to remove and clean smoke panel on alarm.	e detectors, alarm				
Alfredo Ort	iz						
146272	A-Wing	Restroom (Girls)	1/14/2016		5		\$0.00
Medium	Work In Progress	Front office	1/14/2016 4:04:02 PM	1			
Ortiz, Alfred	do	Please clean and check exhaust restroom in front office. It's not to the switch. (Mireya Meza)					
Mireya Mez	za						
146285	Q-Wing	Restroom	1/15/2016		4		\$0.00
Medium	Work In Progress	Q boys restroom	1/15/2016 10:14:57 AM				
Ortiz, Alfred	do	Alfredo please fix sink in boys rebottom of the sink was broken and (Mireya Meza)					
Mireya Mez	a						
140543			9/24/2015		117		\$0.00
Medium	Work In Progress		9/24/2015 8:34:17 AM				
Marquez, C	Serardo	PLEASE WELD PADLOCKS AND	CHAINS ON GATES.				
Gerardo M	arquez						
144249	·	Cafeteria	12/3/2015		47		\$0.00
Medium	Work In Progress		12/3/2015 8:24:02 AM				
Marquez, C	_	The exterior doors entering the c					
Alfredo Ort	iz						
143474	Q-Wing	Classroom	11/12/2015		68		\$0.00
Medium	Work In Progress		11/12/2015 10:31:03				
Marquez, C	Gerardo	Need to install a door lock in Q-6 b and welding shop. Auto parts missing.	oetween auto shop				
Alfredo Ort	iz	-					
138398	Q-Wing	Classroom	8/20/2015		152		\$0.00
Medium	Work In Progress	Q6	8/20/2015 10:12:00 AM				
Marquez, (	Gerardo	Please make copy of Matco key tool boxin Autoshop. We also nee the other tool box keys. Please s Meza)	ed copies made for all				

1/19/2016 11:45:13 AM Page 25 of 153

WOID	Building	Area	3/30/2016 Order By Loca <b>Deferred By</b>	Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Crea	ted Date/Time	<b>Actual Comp Date</b>	Aged	Hours	
Assigned 1		Description				<b>Action Taken</b>			
Requester	Name								
Location:	Chaparra	II HS							
143875	Field House	Exterior			11/19/2015		61		\$0.00
Medium	Work In Progress			11/19/2	.015 3:47:55 PM	1			
Marquez, C	Serardo	Need to fix doc	or cylinders at weight	room hard	to open.				
Alfredo Ort	iz								
144318					12/3/2015		47		\$0.00
Medium	Work In Progress			12/3/2	.015 3:57:28 PN	1			
Marquez, C	Serardo	Weight room d	oors hard to open and	lock.					
Alfredo Ort	iz								
141762	Pre-K	Roof			10/15/2015		96		\$0.00
Medium	Work In Progress			10/1	5/2015 10:17:47	•			
Solis, Lore	nzo	Need to replac	e condenser fan moto	r.					
Alfredo Ort	iz								
144860	Q-Wing	Hallway/Corric	lor		12/11/2015		39		\$0.00
Medium	Work In Progress			12/11/2	.015 9:41:19 AM	1			
Chavez, Sa	antos	Need to replac side light	e burned out timer and	d contactor f	orout				
Alfredo Ort									
137857	Field House	Athletic Field			8/12/2015		160		\$0.00
Medium	Work In Progress	Softball field		8/12/2	.015 3:36:25 PN	1			
Chavez, Sa	antos	Need electricity (Mireya Meza)	yfor new softball/base	ball batting	cage.				
Mireya Mez									
144639	H-Wing	Gym			12/8/2015		42		\$0.00
Medium	Work In Progress	Gym Training		12/8/20	)15 10:00:34 AM	1			
Chavez, Sa	antos		ght bulbs are burned o (Mrs. Walsh, gym trair		n				
Mireya Mez									
139947	Field House	Mechanical			9/14/2015		127		\$0.00
Medium	Work In Progress			9/14/2	:015 3:58:21 PN	1			
Chavez, Sa	antos	Buster pump for needs to check electrical power		reset every	day,				
Alfredo Ort									

1/19/2016 11:45:13 AM Page 26 of 153

WOID Priority Assigned Requester		Area Area Number Description	Deferred By Until Request			Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	al HS							
145122	•				12/16/2015		34		\$0.00
Medium	Work In Progress			12/16/2	:015 8:40:49 AN		0.		Ψ0.00
Chavez, Sa	_	storage and ar need for maint	roundskeeper, need i inside light at least c enance.equipment th edo Olguin or to whor	one outlet ple nank you					
Pedro Valo	dez								
137624	C-Wing	Classroom			8/10/2015		162		\$0.00
Medium	Work In Progress			8/10/2	:015 9:37:57 AN	1			
Chavez, Sa			ouse need to rewire of A/C. Thank you.	electicity for h	eater,				
Alfredo Ori		Classroom			8/6/2015		166		\$0.00
137427	B-Wing			0.10.10			100		φυ.υυ
Medium	Work In Progress	B2			015 2:49:56 PN	/1			
Chavez, Sa		Need a wall pl	ug socket in room. (	Ms. Perez, B	2)				
Mireya Me									
145780	B-Wing	Classroom			1/7/2016		12		\$0.00
Medium	Work In Progress			1/7/2	:016 9:40:49 AN	1			
Appelzolle	r, Fred	Need to replac	e kitchen faucets in B	-2 class roon	١.				
Alfredo Or	iz								
145386					1/3/2016	1/6/2016	16		\$0.00
Medium	Work In Progress			1/3/20	16 12:44:25 AM	1			
Ortiz, Alfre	do	Monthly - Chap Refer to PM sch	oarral HS - Emer. Ey nedule details.	ewash (Mon	hly) -				
Margret Vil	lalobos								
145329					1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress			1/3/20	16 12:43:35 AN	1			
Ortiz, Alfre	do	Yearly - Chapa PMschedule d	rral HS Backflow Ins etails.	pection - Re	fer to				
Margret Vil	lalobos								
145840	Field House	Athletic Field		<u> </u>	1/7/2016		12		\$0.00
Medium	Work In Progress	Softball		1/7/2	:016 4:06:58 PN	1			
Appelzolle	r, Fred		a water fountain/fauce ater. (coach Heddles						
Mireya Me:	za								

1/19/2016 11:45:13 AM Page 27 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Davs** Labor Area **Deferred By** Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Action Taken Assigned To** Description Requester Name Chaparral HS Location: 146301 A-Wing Office 1/15/2016 4 \$0.00 Medium MARK 1/15/2016 2:49:26 PM Work In Progress Gonzales, Camilo PLEASE DELIVER THE FOLLOWING ITEMS TO: MARK RUPCICH OR DIANA SALAZAR PO #151601869 - 6 BOXES/2 CYLINDERS (TRACK SUPPLIES AND JAVALINS) - CHS TRACK Terry Alvarado A-Wing Office 1/15/2016 4 \$0.00 146302 Medium Work In Progress MARK 1/15/2016 2:50:48 PM PLEASE DELIVER THE FOLLOWING ITEMS TO: Gonzales, Camilo MARK OR DIANA SALAZAR NO PURCHASE ORDER - 2SETS OF CATCHERS GEAR (1SET FOR SOFTBALL AND 1SET FOR BASEBALL) Terry Alvarado 145969 Q-Wing Exterior 1/11/2016 R \$0.00 Medium Work In Progress 1/11/2016 8:32:11 AM Marquez, Gerardo Warranty work order or vandalism? On the new closer automatic doors, The elbow was broken off. Alfredo Ortiz 141268 Q-Wing Classroom 10/8/2015 103 \$0.00 Medium Work In Progress 10/8/2015 8:53:30 AM East side garage door is a secondary emergency exit Marquez, Gerardo and doesn't close all the way. Lets bugs in daily. Please fix. (Mr. Waters, Q2) Mireya Meza 1/12/2016 \$0.00 A-Wing Library 146116 Medium Work In Progress Library 1/12/2016 4:19:55 PM Gonzales, Camilo We need warehouse to pick up several items from Library. Either broken or no longer compatible with our systems. (Lamination Machine GISD #1000000010033), (Poster Maker GISD #FA00000001877), (Gateway Scanner GISD #00002298), (Scanner GISD #000673), (HP Scanner #CN6C6A60SB) & (3 TV's) Mireya Meza 11/1/2015 11/22/2015 \$0.00 142695 Work In Progress 11/1/2015 12:54:02 AM Medium Orozco, Daniel Monthly-Chaparral HS Range Hood Cleaning - Refer to PMschedule details. Margret Villalobos

1/19/2016 11:45:13 AM Page 28 of 153

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2 Area De Area Number Re Description	ferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	II HS						
142129	I-Wing	Classroom		10/21/2015		90		\$0.00
Medium	Work In Progress	Band room		10/21/2015 4:10:18 PM				
Estrada, Je		Please replace car band room)	oet in band roor	n with tile. (Mr. Rios,				
146148	H-Wing	Gym		1/13/2016		6		\$0.00
Medium	Work In Progress	•		1/13/2016 2:18:45 PM				
	Guadalupe	Attention to wareho volleyball poles on handle broke off. T	he gym floor ne	ed to be replaced the				
Alfredo Ort								
142463	Field House	Athletic Field		10/28/2015		83		\$0.00
Medium	Work In Progress	baseball field		10/28/2015 9:33:25 AM				
Gonzalez,		Please install back backstop. (Coach F		on baseball field				
Mireya Mez	za Field House	Athletic Field		10/28/2015		83		\$0.00
Medium	Work In Progress	Baseball Field		10/28/2015 9:28:03 AM		00		Ψ0.00
Gonzalez,	•	Please install 4 mir (Coach Rojas)	ni batting cages					
Mireya Mez	za	. ,						
142461	Field House	Athletic Field		10/28/2015		83		\$0.00
Medium	Work In Progress	Baseball Field		10/28/2015 9:30:35 AM				
Gonzalez,	Salvador	Please install bull p Rojas)	en in visitors d	ugoutarea. (Coach				
Mireya Mez								
143521	R-Wing	Classroom		11/12/2015		68		\$0.00
Medium	Work In Progress			11/12/2015 4:00:54 PM				
Orozco, Da	niel	One of the stove ov replace gas valve. In Home Economic		g need to fix or				
Alfredo Ort	iz							
143638				11/16/2015		64		\$0.00
Medium	Work In Progress			11/16/2015 2:37:24 PM				
Apodaca, I	Mario			mechanical room to ound on Geo thermal				

1/19/2016 11:45:13 AM Page 29 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building Area Until **Request Date Target Comp Date Days** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Chaparral HS Location: 145467 1/3/2016 16 \$0.00 Medium Work In Progress 1/3/2016 12:45:44 AM Monthly - Chaparral HS - Lift Station Inspection - Refer Apodaca, Mario to PMschedule details. Margret Villalobos 10/27/2015 84 \$0.00 142396 Medium Work In Progress 10/27/2015 12:59:35 Orozco, Daniel NEON LIGHTS FOR FOLLOWING LINES NOT WORKING RED & GREEN, FRESH FROM THE GARDEN AND ON A BUN. SNP MANAGER JUANITA M. 824.4461 Maritza Gonzalez 1/3/2016 16 \$0.00 145365 Medium Work In Progress 1/3/2016 12:44:07 AM Vallejo, Albert Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PMschedule details. Margret Villalobos 1/3/2016 16 \$0.00 145368 Medium Work In Progress 1/3/2016 12:44:10 AM Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp -Vallejo, Albert Refer to PMschedule details. Margret Villalobos 9/22/2015 119 140408 Field House Storage \$0.00 9/22/2015 3:10:01 PM Medium Work In Progress Vallejo, Albert Trouble in fire sprinkler system Alfredo Ortiz Count: 53 Work Orders \$0.00 Avg. Age of WO's 57 **Total for Chaparral HS** 

1/19/2016 11:45:13 AM Page 30 of 153

Assigned Requester		Area Number Reason Description	Created Date/Time	Action Taken	Aged	Hours	
Location:	Chaparra	II MS					
142473	<u> </u>		10/28/2015		83		\$0.00
Medium	Work In Progress		10/28/2015 11:59:26	i			
Holguin, A	Ifredo	need to install second service for fire	pump				
Alfredo Ho							
145359			1/3/2016	1/24/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:02 AM	1			
Vallejo, All	pert	Monthly - Chaparral MS Fire Sprinkle PMschedule details.	er Insp Refer to				
Margret Vi	llalobos						
138787			8/26/2015		146		\$0.00
Medium	Work In Progress		8/26/2015 3:04:42 PM	1			
Gonzalez,	Salvador	Need to make and install 4 sets of lac sections of Chaparral Middle School					
Johnny Ac	una						
139031		Classroom	8/31/2015		141		\$0.00
Medium	Work In Progress	305	8/31/2015 10:34:06 AM	1			
Acuna, Jol	nnny	Please anchor smartboard to wall					
Gidget Mo							
136761	Main Building	Gym	7/30/2015		173		\$0.00
Medium	Work In Progress		7/30/2015 3:18:19 PM	1			
Acuna, Jol	nnny	Please reinforce chin up bar in gym					
Gidget Mo	ra						
143100	Main Building	Cafeteria	11/5/2015		75		\$0.00
Medium	Work In Progress		11/5/2015 8:51:22 AM	1			
Acuna, Jol	nnny	Please hang banner in the cafeteria to TV	o the right of the				
Gidget Mo			-/				
136119	Main Building	Classroom	7/20/2015		183		\$0.00
Medium	Work In Progress	p-14	7/20/2015 1:24:35 PM	1			
Acuna, Jol	nnny	please fill holes in wall					
Gidget Mo							
136120	Main Building	Classroom	7/20/2015		183		\$0.00
Medium	Work In Progress	101	7/20/2015 1:25:55 PM	1			
Acuna, Jol	nnny	Please mount SMART Board on the w	/all				

1/19/2016 11:45:13 AM Page 31 of 153

WOID Priority Assigned Requester	Building Status To	•	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Chaparra	al MS				
144474		12/6/2015	12/14/2015	44		\$0.00
Medium	Work In Progress	12/6/2015 12:39:57 AN	Л			
Acuna, Jol	hnny	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.				
Margret Vi	llalobos					
146062		1/12/2016	i	7		\$0.00
Medium	Work In Progress	1/12/2016 1:59:23 PM	М			
Acuna, Jol	hnny	Need 10 exit signs only for CMS				
Johnny Ac	cuna					
144180	Main Building	Classroom 12/2/2015		48		\$0.00
Medium	Work In Progress	408 12/2/2015 10:20:14 AN	Л			
Acuna, Jol	hnny	Exhaust not working, vent not working				
Gidget Mo	ra					
145416		1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress	1/3/2016 12:44:54 AN	Л			
Acuna, Jol	hnny	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PMschedule details.				
Margret Vi	llalobos					
145418		1/3/2016		16		\$0.00
Medium	Work In Progress	1/3/2016 12:44:56 AN	Л			
Acuna, Jol	•	Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PMschedule details.				
Margret Vi	llalobos	4/0/0040	0/0/0040			Φο οο
145419		1/3/2016		16		\$0.00
Medium	Work In Progress	1/3/2016 12:44:57 AN	Л			
Acuna, Jol	•	Monthly - Chaparral MS Bleacher Inspection - Refer to PMschedule details.				
Margret Vi	llalobos	1/3/2016	1/9/2016	16		\$0.00
145483	W 11 B			10		<b>Ф</b> 0.00
Medium	Work In Progress	1/3/2016 12:46:00 AN	Л			
Quinones		Monthly - Chaparral MS Monthly FE Inpsection - Refer to PMschedule details.				
Margret Vi	llalobos	44 (4 (0045	44/00/0045	70		<b>ФО 00</b>
142700		11/1/2015		79		\$0.00
Medium	Work In Progress	11/1/2015 12:54:05 AN	Л			
Orozco, Da		Monthly-Chapparal MS Range Hood Cleaning - Refer to PMschedule details.				
Margret Vi	llalobos					
1/19/2016	11:45:13 AM				Page 3	32 of 153

1/19/2016 11:45:13 AM Page 32 of 153

Total

## 952 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request <b>Building</b>	Dates:7/1/2015 - 6 <b>Area</b>	6/30/2016 Order By Loc <b>Deferred By</b>	ation, Status <b>Until</b>	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned <sup>·</sup>		Description				Action Taken			
Requester	Name	-							
Location:	Chaparra	al MS							
145621	Main Building	Classroom			1/5/2016		14		\$0.00
Medium	Work In Progress	P-5		1/5/20	16 12:02:58 PN	1			
Carbajal,	limmy	Tiles in Nurse' Please repair	s office breaking and	lifting from flo	or.				
Gidget Mo	ra								
139646	Main Building	Kitchen			9/9/2015		132		\$0.00
Medium	Work In Progress			9/9/20	15 11:47:14 AM	1			
Estrada, J	esus		coming up under the s d after the kitchen floo		ers.				
Jesus Est	rada								
143314					11/9/2015		71		\$0.00
Medium	Work In Progress			11/9/2	015 2:22:11 PN	1			
Vallejo, All	pert	Create pad for	dumpsters in bus tur	naround.					
Albert Valle	ejo								
146104					1/12/2016		7		\$0.00
Medium	Work In Progress			1/12/2	016 3:52:22 PN	1			
Marquez, 0	Gerardo		e cracked solid wood sroom Room #205 at		or				
Johnny Ac	una								
146207		Restroom (Gir	ls)		1/14/2016		5		\$0.00
Medium	Work In Progress			1/14/2	016 9:26:23 AM	1			
Marquez, 0	Gerardo	senesecita po del lobby GRA	ner puerta en unos de CIAS	los banos de	e las girls				
M. Carmer	n Perez								
146303	Main Building	Office			1/15/2016		4		\$0.00
Medium	Work In Progress	Charlene		1/15/2	016 2:53:10 PN	1			
Gonzales,	Camilo	PLEASE DELI' CHARLENE B	VER THE FOLLOWIN ONHAM	G ITEMS TO	:				
		PO#1516020	28 - 1BOX (UNIFORI	MS) - CMS SO	OCCER				
Terry Alvar	ado								
145972	Main Building	Classroom			1/11/2016		8		\$0.00
Medium	Work In Progress	205		1/11/2	016 9:02:25 AM	1			
Marquez, 0	Gerardo	please fixdoor	, slams loudlywhen c	losed.					
Gidget Mo			, , , , , , , , , , , , , , , , , , , ,						
Jiuget IVIO	ıu								

1/19/2016 11:45:13 AM Page 33 of 153

WOID Priority	Building Status	Area Number	i/30/2016 Order By Loca <b>Deferred By</b> <b>Reason</b>		Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned To		Description			Action Taken			
Requester	Name							
Location:	Chaparra	al MS						
145311				1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:43:21 AN	1			
Acuna, Johnny		Yearly - Chapa PMschedule d	rral MS Backflow Insp etails.	pection - Refer to				
Margret Vil	lalobos							
145859		Restroom		1/8/2016		11		\$0.00
Medium	Work In Progress			1/8/2016 9:17:48 AM	1			
Appelzoller, Fred		senesecita are lobby GRACIAS	eglar es cusado de res S	troom de las girls del				
M. Carmer	n Perez							
139553		Restroom (Girl	s)	9/8/2015		133		\$0.00
Medium	Work In Progress			9/8/2015 9:44:08 AM	1			
Appelzoller, Fred		senesecita arg para de tirar ag	llar lavamanos de los gua GRACIAS	locker de las girls no				
M. Carmer	n Perez							
136253		Restroom (Girl	s)	7/22/2015		181		\$0.00
Medium	Work In Progress			7/22/2015 8:37:10 AM	И			
Appelzoller, Fred		girls locker roo GRACIAS	m hand washhhing si	nk es leaking				
M. Carmer								
145615	Main Building	Restroom (Girl	s)	1/5/2016		14		\$0.00
Medium	Work In Progress	300		1/5/2016 10:14:26 AN	Л			
Appelzoller, Fred		Sink is leaking	in girls 300 hallwayre	stroom				
Gidget Mo	ra							
143622		Restroom (Girl	s)	11/16/2015		64		\$0.00
Medium	Work In Progress			11/16/2015 10:06:40	)			
Chavez, Santos		senesecita remplasar hand airblower dryer del bathroom de las girls del lobby GRACIAS						
M. Carmen Perez								
143669	Main Building	Classroom		11/16/2015		64		\$0.00
Medium	Work In Progress	404		11/16/2015 3:49:48 PM	1			
Chavez, Sa	antos	Please install e Projector for po	electrical outlet in ceili ower	ng in order to plug in				
Gidget Mo	ra							

1/19/2016 11:45:13 AM Page 34 of 153

Total

## 952 - Work Orders In Progress (Fiscal Year)

Priority S Assigned To		Area Number	Deferred By Reason		te Target Comp Date ne Actual Comp Date	Days	Labor	
Assigned To	•			Created Date/11n	ie actual comp date	Aged	Hours	
_		Description			Action Taken			
Requester N		-						
Location:	Chaparra	IMS						
144795				12/10/20	15	40		\$0.00
Medium V	Work In Progress			12/10/2015 9:20:24	AM			
Chavez, Santos		need to run cor heating system	duit for temperature	sensor to boiler				
Johnny Acun	na							
143621		Restroom		11/16/20	15	64		\$0.00
Medium V	Nork In Progress			11/16/2015 10:00	:59			
Chavez, Santos			nplasarhand air blov Iobby GRACIAS	verdryer en bathroom				
M. Carmen F	Perez							
144644		Office		12/8/20	15	42		\$0.00
Medium V	Work In Progress			12/8/2015 11:19:35	AM			
Chavez, San	tos	senesecita ren administration	nplasar lus de laentr GRACIAS	ada de la office de				
M. Carmen F	Perez							
146109				1/12/20	16	7		\$0.00
Medium V	Work In Progress			1/12/2016 3:54:22	PM			
Chavez, Santos		Need to relocat	te electrical outlet to r	estroom in SPED				
Johnny Acun	na							
143770 N	Main Building	Classroom		11/18/20	15	62		\$0.00
Medium V	Work In Progress	P-4		11/18/2015 10:18	26			
Acuna, Johnny		needing to be p	next to south footbal vainted due to taggin oval but was unsucc	g. Attempt was made				
Gidget Mora								
144334				12/4/20	15	46		\$0.00
Medium V	Work In Progress			12/4/2015 8:15:32	AM			
Solis, Lorenzo			aquastat outdoor the n at Chaparral Middle					
Johnny Acun	na							
145862		Classroom		1/8/20	16	11		\$0.00
Medium V	Work In Progress			1/8/2016 9:23:28	AM			
Marquez, Gerardo			glar candado de la p nallway GRACIAS	uerta de ladase				
M. Carmen F	Perez							

1/19/2016 11:45:13 AM Page 35 of 153

WOID	Building		<del>-</del>	Target Comp Date	Days Aged	Labor Hours	
Priority	Status	Area Number Reason Description	Created Date/Time	Actual Comp Date Action Taken	rigou	riouro	
Assigned To Requester Name		Description	Action Taken	Action Taken			
Location:	Chaparra	u MS					
145865	Onaparre	Parking Lot	1/8/2016		11		\$0.00
	Mark In Drawna a	r arking Lot			!!		ψ0.00
Medium	Work In Progress		1/8/2016 9:29:15 AN	1			
Marquez, Gerardo		senesecita lubricar los candados de la pordonde entran los camiones escolar candados GRACIAS	•				
M. Carmei	n Perez						
139414			9/6/2015		135		\$0.00
Medium	Work In Progress		9/6/2015 12:34:05 AM	1			
Flores, Pete		Monthly - CHM-UV-0514 PM Service - Fschedule details.	Refer to PM				
Margret Vi							
145971	Main Building	Classroom	1/11/2016		8		\$0.00
Medium	Work In Progress	103	1/11/2016 9:00:49 AM	1			
Quinones	, Paul	Please replace fire extinguisher hook.					
Gidget Mo	ra						
145618	Main Building	Portables	1/5/2016		14		\$0.00
Medium	Work In Progress	P-5	1/5/2016 11:52:55 AM	1			
Quinones	, Paul	Wall paper in bathroom torn and comin	g off the wall				
Gidget Mo	ra						
136489		Portables	7/27/2015		0		\$0.00
Medium	Work In Progress		7/27/2015 9:26:41 AM	7/27/2015			
Quinones	, Paul	senesecita replace broken tiles and po GRACIAS	ortables #5	7-27-15			
M. Carmei	n Perez						
145647			1/5/2016		14		\$0.00
Medium	Work In Progress		1/5/2016 3:41:17 PM	1			
Quinones	, Paul	need 1 basketball rim for the basketbal chm,requesting 2 rims.thanks	lgym @				
Paul Quin	ones						
139807		Hallway/Corridor	9/11/2015		130		\$0.00
Medium	Work In Progress		9/11/2015 12:42:35 PM	I			
Quinones	, Paul	senesecita remplasar focos que no pre GRACIAS	enden en el lobby				
M. Carmei	n Perez						

1/19/2016 11:45:13 AM Page 36 of 153

Total

### 952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Created Date/Time Actual Comp Date Status Area Number Reason **Priority Description Action Taken Assigned To** Requester Name Location: Chaparral MS 139808 Hallway/Corridor 9/11/2015 130 \$0.00 9/11/2015 12:47:37 PM Medium Work In Progress Quinones, Paul senesecita poner lampara que no prende y areglar switch del hallway del lobby GRACIAS M. Carmen Perez Athletic Field 1/4/2016 15 \$0.00 145512 Medium Work In Progress 1/4/2016 9:05:39 AM Ontiveros, Guadalupe Softball field needs concrete slap for dug outs home and visitor sides and to anker benches. Guadalupe Ontiveros 1/10/2016 1/26/2016 9 \$0.00 145937 1/10/2016 12:27:57 AM Medium Work In Progress Perez, M. Carmen Monthly - QRTLY BLDG INSP REPORTS (CM) - Refer to PMschedule details. Margret Villalobos **Count: 47 Work Orders** Avg. Age of WO's 58 0 \$0.00 **Total for Chaparral MS** 

1/19/2016 11:45:13 AM Page 37 of 153

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6 Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Pi	ride HS						
145919				1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/2016 12:27:44 AM				
Acosta, Da	vid	Monthly - QRTL PMschedule de		ORT (DP) - Refer to				
Margret Vil	lalobos							
146136		Gym		1/13/2016		6		\$0.00
Medium	Work In Progress	inside		1/13/2016 10:09:56 AM				
Ronquillo,	Ruben	Need to reinsta loose from gym	ll stationarypunchir floor.	ng bags that came				
David Acos	sta			4/40/0040				Ф0.00
146139		Gym		1/13/2016		6		\$0.00
Medium	Work In Progress	Boxing ring		1/13/2016 10:37:04 AM				
Ronquillo,		There is still a trip hazard and		ng platform that still a				
David Acos	sta			4 /0 /00 40		40		Φο οο
145373				1/3/2016		16		\$0.00
Medium	Work In Progress			1/3/2016 12:44:14 AM				
Ronquillo,		Monthly - Dese Refer to PMsch	rt Pride - (Qtrly) Fitn edule details.	ess Equipment -				
Margret Vil	lalobos	Office		1/13/2016		6		<u>ФО ОО</u>
146135	W 11 B					O		\$0.00
Medium	Work In Progress	nurse's office		1/13/2016 9:55:17 AM				
Diaz, Seba		Need to mount office.	a medicine cabinet	on wall at nurse's				
Maria Carb 143359	pajai	Office		11/10/2015		70		\$0.00
Medium	Work In Brogross		in	11/10/2015 5:29:00 AM		70		ψ0.00
	Work In Progress	boys restroom		1 1/10/2013 3.29.00 AW				
Marquez, G		Having trouble	unlocking door.					
David Acos	sta	0#:		4 /0/2040		40		<u>ФО 00</u>
145704	W 11 B	Office		1/6/2016		13		\$0.00
Medium	Work In Progress	Middle school		1/6/2016 12:19:23 PM				
Marquez, G		Entrance door turning up and	on the right, handle down to far.	as to much play				
David Acos	sta	Dortobles		44/40/0045		70		<u></u>
143360	W 11.5	Portables		11/10/2015		70		\$0.00
Medium	Work In Progress	room #20		11/10/2015 5:33:29 AM				
Marquez, G	Gerardo	Having trouble	with cylinder unlocki	ng and locking.				

WOID Briority	Building Status	Area Number	Deferred By	Until Request Date  Created Date/Time	Target Comp Date	Days Aged	Labor Hours	
Priority Assigned 1		Description	NEG SUII	Greated Date/Time	Action Taken	J		
Requester		Description			Action raken			
Location:	Desert P	ride HS						
138187		Portables		8/18/2015		154		\$0.00
Medium	Work In Progress	room #19		8/18/2015 5:32:16 AM	I			
Solis, Lore	nzo	a/c not cooling	need to be service	dasap.				
David Acos	sta							
137898		Portables		8/13/2015		159		\$0.00
Medium	Work In Progress	room #19		8/13/2015 5:24:27 AN	I			
Ambriz, Jos	se	a/c unit not cool	ing (asap).					
David Acos	sta							
137900		Portables		8/13/2015		159		\$0.00
Medium	Work In Progress	room #18		8/13/2015 5:26:58 AN	I			
Ambriz, Jos	se	a/c unit not cool	ing (asap).					
David Acos	sta							
142399		Office		10/27/2015		84		\$0.00
Medium	Work In Progress			10/27/2015 1:39:56 PM				
Chavez, Sa	antos			I not turning off at a side to Administration				
David Acos	sta							
144191				12/2/2015		48		\$0.00
Medium	Work In Progress			12/2/2015 12:23:53 PM				
Chavez, Sa	antos	Need to check on nurse entrance		n mechanic room by				
Sebastian	Diaz							
139620		Portables		9/9/2015		132		\$0.00
Medium	Work In Progress	room #18		9/9/2015 5:20:08 AN	I			
Chavez, Sa	antos	Two light fixture the other does		check. one flicking and				
David Acos	sta							
138929		Portables		8/28/2015		144		\$0.00
Medium	Work In Progress	portables		8/28/2015 10:22:55 AM	I			
Chavez, Sa	antos			l boards installed in ,7,8,9,12,15,16,18 &				

1/19/2016 11:45:13 AM Page 39 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date Status **Priority Assigned To Action Taken** Description Requester Name Location: Desert Pride HS 143101 **Portables** 11/5/2015 75 \$0.00 11/5/2015 9:04:12 AM Medium Work In Progress room 5 Chavez, Santos Night light does not turn on. David Acosta 143102 **Portables** 11/5/2015 75 \$0.00 Medium Work In Progress room #18 11/5/2015 9:05:38 AM Chavez, Santos Night light does not turn on. David Acosta 146217 Restroom 1/14/2016 5 \$0.00 restrooms #17 1/14/2016 11:03:23 AM Medium Work In Progress Need to connect electrical wires to water heater in Chavez, Santos restroom. Thank you (asap). David Acosta **Portables** 12/16/2015 34 \$0.00 145126 Medium Work In Progress room #10 12/16/2015 8:54:40 AM Appelzoller, Fred Need to replace crack toilet (water leaking thru crack). David Acosta 1/24/2016 1/3/2016 \$0.00 145334 16 Medium Work In Progress 1/3/2016 12:43:40 AM Monthly - Desert Pride Fire Sprinkler Insp. - Refer to PM Vallejo, Albert schedule details. Margret Villalobos Count: 20 Work Orders Total for Desert Pride HS Avg. Age of WO's 64 0 \$0.00

1/19/2016 11:45:14 AM Page 40 of 153

WOID Priority Assigned Requester			Deferred By	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert Ti	rail ES							
145360					1/3/2016	1/24/2016	16		\$0.00
Medium	Work In Progress			1/3/20	16 12:44:03 AM	1			
Vallejo, All	bert	Monthly - Deser PMschedule de	t Trail ES - Fire Sp tails.	rinkler Insp I	Refer to				
Margret Vi	llalobos								
142722					11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress			11/1/20	15 12:54:20 AM	1			
Orozco, Da	aniel	Monthly - Deser Refer to PMsch	t Trail ES - Fire Su edule details.	ppression Ins	0				
Margret Vi	llalobos								
146046					1/12/2016		7		\$0.00
Medium	Work In Progress			1/12/2	016 9:07:39 AM	1			
Marquez, (	Gerardo	Need to replace towards the por	door clos ure to ma tables.	ain Left door go	ing out				
Johnny Ac	cuna								
146063					1/12/2016		7		\$0.00
Medium	Work In Progress			1/12/2	016 2:06:06 PN	1			
Carrasco,	Danny	Need unleaded	gasoline for Work	Truck#192					
Johnny Ac	euna								
139805					9/11/2015		130		\$0.00
Medium	Work In Progress			9/11/20	15 12:01:57 PM	I			
Carrasco,	Danny	Need unleaded	fuel for worktruck #	<sup>‡</sup> 192					
Johnny Ac	cuna								
136190		Custodial			7/21/2015		182		\$0.00
Medium	Work In Progress			7/21/20	15 11:06:40 AM	1			
Estrada, J	esus	necesita rempla	nuy, el piso de los E asar . Num de clas 208, y el bano de l asar gracias	es 201,202,20	03, 204,				
Laura Sar	ndoval								
138489		Custodial			8/21/2015		151		\$0.00
Medium	Work In Progress			8/21/2	015 9:37:38 AM	1			
Estrada, J	esus	Buenos dias .C la libreria gracia	huyse necesita rei s	mplazar la alfoi	mbra de				
Laura Sar	ndoval								

1/19/2016 11:45:14 AM Page 41 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Days** Labor Area **Deferred By** Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Action Taken Assigned To** Description Requester Name **Desert Trail ES** Location: 135927 7/15/2015 188 \$0.00 Medium Work In Progress 7/15/2015 11:48:40 AM Need to replace VCT tile in the bus lobby entrance right Estrada, Jesus in front of main doors. Also, need to fill in and level out holes on this section where the tile will be replaced. Size of Area: 7' L X 11' W Laura Sandoval 11/1/2015 11/22/2015 \$0.00 142701 79 Work In Progress Medium 11/1/2015 12:54:06 AM Monthly - Desert Trail ES - Range Hood Cleaning -Orozco, Daniel Refer to PMschedule details. Margret Villalobos 1/3/2016 1/9/2016 \$0.00 145488 16 1/3/2016 12:46:05 AM Medium Work In Progress Monthly - Desert Trail ES - Monthly FE Inpsection -Acuna, Johnny Refer to PMschedule details. Margret Villalobos 1/12/2016 \$0.00 146060 Medium Work In Progress 1/12/2016 1:56:11 PM Acuna, Johnny Need (15) 4L-210 Notched fan belts and (15) 4L-220 Notched fan belts for CMS and Desert Trail Exhaust fan units. Johnny Acuna 1/12/2016 7 \$0.00 146061 1/12/2016 1:57:52 PM Medium Work In Progress Need Lamp covers for light fixtures at Desert Trail. Acuna, Johnny (Sent lamp cover samples to PPD) Johnny Acuna 1/3/2016 1/11/2016 16 \$0.00 145395 Work In Progress 1/3/2016 12:44:34 AM Medium Monthly - Desert Trail ES- Emer Light Insp:Monthly -Acuna, Johnny Refer to PMschedule details. Margret Villalobos 145396 1/3/2016 1/11/2016 16 \$0.00 1/3/2016 12:44:35 AM Work In Progress Medium Monthly - Desert Trail ES - Exit Sign Insp:Monthly -Acuna, Johnny Refer to PMschedule details. Margret Villalobos

1/19/2016 11:45:14 AM Page 42 of 153

WOID	Building	Dates:7/1/2015 - 6/30/2016 Order By Locat <b>Area Deferred By</b>	Until Request Date	<b>Target Comp Date</b>	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time	•	Aged	Hours	
Assigned <sup>-</sup>		Description		Action Taken			
Requester	r Name						
Location:	Desert Ti	ail ES					
145397			1/3/2016		16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:36 AM	I			
Acuna, Joh	hnny	Monthly - Desert Trail ES -Clothes Dr Refer to PMschedule details.	yer (Monthly) -				
Margret Vil	llalobos						
142559			10/29/2015		82		\$0.00
Medium	Work In Progress		10/29/2015 1:56:57 PM				
Acuna, Joh	hnny	Need Heating season filters for Dese	rtTrail				
Johnny Ac	una						
139381	Main Building	Classroom	9/4/2015		137		\$0.00
Medium	Work In Progress	405	9/4/2015 2:34:29 PM	1			
Acuna, Joh	hnny	Ms. Garcia in portable #405 needs bo won't fall.	okshelf bolted so it				
Elizabeth I	Hernandez						
138576			8/24/2015		148		\$0.00
Medium	Work In Progress		8/24/2015 11:02:21 AM	I			
Acuna, Joh	hnny	Need 2 4500 master cool media pads and 419	s for portable #418				
Johnny Ac	una						
138686			8/25/2015		147		\$0.00
Medium	Work In Progress		8/25/2015 2:08:42 PM	1			
Acuna, Joh	hnny	Need 1" Sch. 40 Pvc line and 1" Pvc with irrigation water line install in front Desert Trail.					
Johnny Ac	una						
145716			1/6/2016		13		\$0.00
Medium	Work In Progress		1/6/2016 2:49:35 PM	1			
Acuna, Joh	hnny	Need window blinds for portable clas #406, #424, and #425 (98" Wide X 39" Long) Qty. 4 (34" Wide X 63" Long) Qty. 4	srooms #405,				
Johnny Ac	una						
145717			1/6/2016		13		\$0.00
Medium	Work In Progress		1/6/2016 2:52:18 PM	1			
Acuna, Joh	hnny	Need Aluminum window blinds for po #423 (94" Wide X 34" Long) Qty. 1 (46" Wide X 33" Long) Qty. 1	rtable #422 and				
Johnny Ac	una	3, ,					

1/19/2016 11:45:14 AM Page 43 of 153

WOID Priority Assigned Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Ti	ail ES						
144656				12/8/2015		42		\$0.00
Medium	Work In Progress			12/8/2015 2:07:59 PM	1			
Ronquillo,	Ruben		outer lab needs large ents unable to see w					
Elizabeth I	Hernandez							
145953				1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/2016 12:28:10 AM	1			
Acuna, Joh	nnny	Monthly - Dese PMschedule d	rt Trail ES - Playgro etails.	und Insp - Refer to				
Margret Vil	lalobos							
145771				1/7/2016		12		\$0.00
Medium	Work In Progress			1/7/2016 8:52:18 AM	1			
Orozco, Da		SKILLET IS NO MANAGER PAT	T WORKING PROP C. 824.3822	ERLY. SNP				
Maritza Go	nzalez			44/4/0045		70		<u>ФО 00</u>
143078				11/4/2015		76		\$0.00
Medium	Work In Progress			11/4/2015 3:55:48 PN	1			
Orozco, Da		FAUCET TO SA MANAGER PAT	ALAD SINK IS LEAK C.8243822	ING. SNP				
Maritza Go	nzalez			4/0/0040	2/2/2016	40		<u>ФО 00</u>
145312				1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:43:22 AN	1			
Acuna, Joh		Yearly - Desert PMschedule d		Inspection - Refer to				
Margret Vil	lalobos			40/4/0045		40		<b>ФО 00</b>
144332				12/4/2015		46		\$0.00
Medium	Work In Progress			12/4/2015 8:12:26 AM	1			
Appelzolle	r, Fred	Please replace	single entryfaucets	on 200 wing. (12)				
Johnny Ac	una							
146047				1/12/2016		7		\$0.00
Medium	Work In Progress			1/12/2016 9:11:50 AM	1			
Chavez, Sa	antos	#423.		ng to portable #422 - eady turned off Main				

1/19/2016 11:45:14 AM Page 44 of 153

WOID Priority Assigned Requester		Area Area Number Description	Deferred By Reason		-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert Ti	rail ES							
144870					12/11/2015		39		\$0.00
Medium	Work In Progress			12/11/20	015 11:39:29	)			
Chavez, Sa	antos		- ELECTRICAL OUT CED SNP MANAGER						
Maritza Go	nzalez								
142104					10/21/2015		90		\$0.00
Medium	Work In Progress			10/21/2015	3:44:50 PM	I			
Chavez, Sa	antos		ce with light fixture in acher's lounge. Fix						
Johnny Ac	una								
145755					1/6/2016		13		\$0.00
Medium	Work In Progress			1/6/2016	6 4:01:51 PM	1			
Chavez, Sa	antos	playground equand remove se	ease: (Security light iipment) Need to dis curity light pole. Pole the pole. (Safety Ha	s connect electrica e has massive rus					
Johnny Ac	una								
139225					9/2/2015		139		\$0.00
Medium	Work In Progress			9/2/2015	3:22:30 PN	1			
Acuna, Joh	nnny	Water Seal new	portable ramps wit	th wood boards.					
Johnny Ac	una								
135165					7/1/2015		202		\$0.00
Medium	Work In Progress			7/1/2015	7:43:14 AM	1			
Solis, Lore	n <i>z</i> o	Need Refrigera RM. 304	tion unit for new con	mputer class room					
Johnny Ac	una								
144651					12/8/2015		42		\$0.00
Medium	Work In Progress			12/8/2015	11:59:16 AM	1			
Marquez, 0	Serardo	Mrs. Medina in ı	oom #398 needs ke	eyfor metal cabin	et.				
Elizabeth I	Hernandez								
145934					1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/2016	12:27:55 AM	1			
Sandoval,	Laura	Monthly - QRTL	YBLDG INSP REP	ORTS (DT) - Refe	er				

1/19/2016 11:45:14 AM Page 45 of 153

**Total** Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Created Date/Time Actual Comp Date **Priority Status** Area Number Reason **Assigned To Description Action Taken** Requester Name Location: **Desert Trail ES** 145353 1/3/2016 1/11/2016 16 \$0.00 Medium Work In Progress 1/3/2016 12:43:57 AM Monthly - Desert Trail ES - Roof Inpsection - Refer to Acuna, Johnny PMschedule details. Margret Villalobos Count: 36 Work Orders **Total for Desert Trail ES** Avg. Age of WO's 62 0 \$0.00

1/19/2016 11:45:14 AM Page 46 of 153

WOID	Building	Area	3/30/2016 Order By Loca Deferred By	Until Request Date	Target Comp Date	Days Aged	Labor Hours	Costs
Priority	Status	Area Number	Reason	Created Date/Time	•	Ageu	i ioui s	
Assigned <sup>-</sup>		Description			Action Taken			
Requester								
Location:	Desert Vi	ew ES						
145929				1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/2016 12:27:51 AM	1			
Ortega, Isr	ael	Monthly - QRTI PMschedule d	_Y BLDG INSP REPO etails.	RT (DV) - Refer to				
Margret Vil	lalobos							
143709				11/17/2015		63		\$0.00
Medium	Work In Progress			11/17/2015 2:36:41 PM				
Ontiveros,	Guadalupe		o, is requesting for so etball lines on the basl					
Ruben Ort	iz							
146280	Main Building	Classroom		1/15/2016		4		\$0.00
Medium	Work In Progress			1/15/2016 8:44:18 AM	1			
Lara, Ralpi	n	the contractor. one and now a be removed ar	e old door knob was re A new door knob rep cylinder from the used and placed in the new on get in and out of her c	laced the old used I door knob need to loor knob. So that				
Israel Orte	<del>-</del>							
145854	Main Building	Hallway/Corrid	lor	1/8/2016		11		\$0.00
Medium	Work In Progress			1/8/2016 8:05:04 AM	1			
Lara, Ralpi	h	doors that are f would like to g	e having problems wi acing the lower grade et it fix today since we ng up. Thank you	playground. We				
Israel Orte	ga							
145794		Library		1/7/2016		12		\$0.00
Medium	Work In Progress	Rm.122		1/7/2016 1:06:14 PM	1			
Ortiz, Rube	en	Install two bulle	etin boards in library. (	Segura)				
Guadalupe	e Gonzalez							
145991		Classroom		1/11/2016		8		\$0.00
Medium	Work In Progress	Rm.328		1/11/2016 1:27:51 PM	1			
Ortiz, Rube	en	Elementary-S	cabinets back to Sun peech Therapy Room utside of Rm. 328 and wold)	-Julie Moran. Filing				
Cuadalun	e Gonzalez		,					

1/19/2016 11:45:14 AM Page 47 of 153

WOID Priority Assigned	Building Status	Dates:7/1/2015 - 6/30/2016 Order By Location Area Deferred By United Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Labor Aged Hours	Costs
Requester	Name					
Location:	Desert Vi	ew ES				
145858			1/8/2016		11	\$0.00
Medium	Work In Progress		1/8/2016 9:16:38 AM	1		
Ortiz, Rube	en	Mr. Araujo signs on the door to let visito in the front office	rs know to sign			
Ruben Ort	iz					
145381			1/3/2016		16	\$0.00
Medium	Work In Progress		1/3/2016 12:44:21 AM	1		
Ortiz, Rube	en	Monthly - Desert View ES - Clothes Dry Refer to PMschedule details.	er (Monthly) -			
Margret Vil	lalobos					
145383			1/3/2016	1/11/2016	16	\$0.00
Medium	Work In Progress		1/3/2016 12:44:23 AV	1		
Ortiz, Rube	en	Monthly - Desert View ES Exit Sign Insp Refer to PMschedule details.	: Monthly -			
Margret Vil	lalobos					
142525			10/28/2015		83	\$0.00
Medium	Work In Progress		10/28/2015 4:14:04 PM	1		
Castillo, C	arlos	provide additional lighting to south side	of mobile home	10/30/15 Asp Albert	t, route to Cali	
Alfredo Ho	lguin					
145313			1/3/2016	2/3/2016	16	\$0.00
Medium	Work In Progress		1/3/2016 12:43:22 AM	1		
Ortiz, Rube	en	Yearly - Desert View ES Backflow Insper PMschedule details.	ection - Refer to			
Margret Vil	lalobos					
145861			1/8/2016		11	\$0.00
Medium	Work In Progress		1/8/2016 9:19:46 AM	1		
Gonzalez,	Salvador	Need stoppers for the swing gates on th the school; to stop them from swing	e southwest of			
Ruben Ort	iz					
145959			1/10/2016	1/26/2016	9	\$0.00
Medium	Work In Progress		1/10/2016 12:28:15 AM	1		
Ortiz, Rube	en	Monthly - Desert View ES Playground Ir PMschedule details.	sp - Refer to			
Margret Vil	lalobos					

1/19/2016 11:45:14 AM Page 48 of 153

Selected Da WOID	ite Range for Request <b>Building</b>	Dates:7/1/2015 - 6/ <b>Area</b>	/30/2016 Order By Loca <b>Deferred By</b>	ation, Status <b>Until</b>	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned		Description				Action Taken			
Requeste	r Name								
Location:	Desert V	iew ES							
145384					1/3/2016	1/9/2016	16		\$0.00
Medium	Work In Progress			1/3/20	16 12:44:24 AN	1			
Ortiz, Rub	en	Monthly - Dese to PMschedule	rt View ES Monthly Fl details.	E Inpsection	- Refer				
Margret Vi	llalobos								
142702					11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress			11/1/20	15 12:54:07 AM	1			
Orozco, Da	aniel	Monthly - Dese to PMschedule	rt View ES Range Ho details.	ood Cleaning	ı - Refer				
Margret Vi	llalobos								
146176					1/13/2016		6		\$0.00
Medium	Work In Progress			1/13/2	016 3:51:58 PM	1			
Gonzales,	Camilo	Pickup furniture (Gonzalez)	e for the Nurse's Offic	ce from San	Miguel.				
Guadalup	e Gonzalez								
143705		Custodial			11/17/2015		63		\$0.00
Medium	Work In Progress			11/17/2	015 1:40:31 PM				
Carbajal,	Jimmy		e going to need a cer Advance burnisher#1						
Israel Orte	ega								
143706		Custodial			11/17/2015		63		\$0.00
Medium	Work In Progress			11/17/2	015 1:42:36 PM				
Carbajal,	Jimmy	clamp pad retai	e going to need anotl iner for a Nobles burr 048. Thank you		k				
Israel Orte	ega								
142723					11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress			11/1/20	15 12:54:21 AM	1			
Orozco, Da	aniel	Monthly - Dese to PMschedule	rt View ES Fire Supp details.	ression Insp	Refer				
Margret Vi	llalobos								
Count: 19	Work Orders	Α	vg. Age of WO's 30	)		Total for Desert Vie	w ES	0	\$0.00

1/19/2016 11:45:14 AM Page 49 of 153

WOID	Building	Dates:7/1/2015 - 6/30/2016 Order By Location, Status  Area Deferred By Until Request Deferred By	ate Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason Created Date/Til	me Actual Comp Date	Aged	Hours	
Assigned	То	Description	Action Taken			
Requester	r Name					
Location:	GAC					
142724		11/1/20	015 11/22/2015	79		\$0.00
Medium	Work In Progress	11/1/2015 12:54:21	AM			
Orozco, Da	aniel	Monthly - GAC Fire Suppression Insp Refer to PM schedule details.				
Margret Vi	Ilalobos					
145361		1/3/20	1/24/2016	16		\$0.00
Medium	Work In Progress	1/3/2016 12:44:04	AM			
Vallejo, Al	bert	Monthly - GAC Fire Sprinkler Insp Refer to PM schedule details.				
Margret Vi	llalobos					
142715		11/1/20	015 11/22/2015	79		\$0.00
Medium	Work In Progress	11/1/2015 12:54:15	AM			
Orozco, Da	aniel	Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.				
Margret Vi	Ilalobos					
145475		1/3/20	016 1/9/2016	16		\$0.00
Medium	Work In Progress	1/3/2016 12:45:52	AM			
Moncayo,	Fernando	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.				
Margret Vi	Ilalobos					
145952		1/10/20	016 1/26/2016	9		\$0.00
Medium	Work In Progress	1/10/2016 12:28:09	AM			
Moncayo,	Fernando	Monthly - GAC Playground Insp - Refer to PM schedule details.				
Margret Vi	Ilalobos					
146232		1/14/20	016	5		\$0.00
Medium	Work In Progress	1/14/2016 3:24:42	PM			
Moncayo,	Fernando	need to have computer technology office sprayed. HAVE MOUSE DROPPINGS.				
		THANK YOU				
Cora Ram	nirez					
145250		12/18/20	015	32		\$0.00
Medium	Work In Progress	12/18/2015 8:19:00	AM			
Orozco, Da	aniel	STEAM LINE IS LEAKING. SNP MANAGER IRMA S. 882.6784				
	onzalez					

1/19/2016 11:45:14 AM Page 50 of 153

WOID Priority Assigned Requester		Area Number Description	Deferred By	Until Reques		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	GAC								
145314				1/:	3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:43		2/0/2010	10		ψ0.00
	_	V 1 040 B			).23 AIVI				
Moncayo,	Fernando	schedule details	ackflow Inspection s.	- Refer to PIVI					
Margret Vil	llalobos								
145521				1/-	4/2016		15		\$0.00
Medium	Work In Progress			1/4/2016 9:47	7:52 AM				
Castillo, C	arlos		ier from Calixto Offi ectrical outlet in ne	ce into computer tech					
Cora Ram	irez								
141292				10/	8/2015		103		\$0.00
Medium	Work In Progress			10/8/2015 2:04	4:18 PM				
Ambriz, Jo	se		nard Acosta's office enser grille cover	needs a line set					
Fernando	Moncayo								
141701				10/1	4/2015		97		\$0.00
Medium	Work In Progress			10/14/2015 3:17	7:10 PM				
Ambriz, Jo	se	backup units to	server room very	noisy and old					
Fernando	Moncayo								
139283				9/5	3/2015		138		\$0.00
Medium	Work In Progress			9/3/2015 10:21	1:09 AM				
Ambriz, Jo	se	Server room at	GAC is warm						
		please check A	SAP						
Cora Ram	irez	•							
142171				10/2	2/2015		89		\$0.00
Medium	Work In Progress			10/22/2015 3:34	1:48 PM				
Ambriz, Jo	se	Please repair d	amage to A/C units	from hailstorm.					
Albert Valle	ejo		-						
145519	•			1/-	4/2016		15		\$0.00
Medium	Work In Progress			1/4/2016 9:46	6:40 AM				
Lara, Ralp	-			es (Michael Vega and e moved from offices.					
		see cora about	this						
Cora Ram	iroz	200 0014 45041							

1/19/2016 11:45:14 AM Page 51 of 153

Selected Da	ate Range for Request <b>Building</b>	Area	Deferred By	Ocation, Status	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	-	Cre	=	Actual Comp Date	Aged	Hours	
Assigned	То	Description				<b>Action Taken</b>			
Requeste	r Name								
Location:	GAC								
145626					1/5/2016		14		\$0.00
Medium	Work In Progress			1/5/2	2016 1:37:19 PN	Л			
Lara, Ralp	oh		ve key from Mr. Ra cobar[she will be m						
Esteban F	Rosas								
145613					1/5/2016		14		\$0.00
Medium	Work In Progress			1/5/20	016 10:07:13 AN	1			
Lara, Ralp	oh		ace office key#AC lla Escobar's office		Dept.				
Esteban F	Rosas								
143696					11/17/2015		63		\$0.00
Medium	Work In Progress	FEDERAL		11/17/2	2015 9:31:30 AN	1			
Moncayo,	Fernando	HANG PICTUR	RE FRAME IN OFFI	CE.					
Noemi Du	uron								
145393					1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/20	)16 12:44:32 AN	1			
Moncayo,	Fernando	Monthly - GAC schedule detail	Emer. Light Test:    s.	Monthly - Refe	to PM				
Margret V	illalobos								
145394					1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/20	016 12:44:33 AN	1			
Moncayo,	Fernando	Monthly - GAC schedule detail	Exit Sign Insp: Mo ls.	nthly - Refer to	PM				
Margret V	illalobos								
145924					1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/20	)16 12:27:48 AN	1			
Rodrigue	z, Arturo	Monthly - QRTL to PMschedule	LY BLDG INSP RE details.	PORT (GAC) -	Refer				
Margret V	illalobos								
145351					1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/20	016 12:43:55 AN	1			
Moncayo,	Fernando	Monthly - GAC details.	Roof Inspection -	Refer to PMsc	hedule				
Margret V	illalobos								

1/19/2016 11:45:14 AM Page 52 of 153

**Total** Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Days Labor Area **Deferred By** Until Hours Aged Created Date/Time Actual Comp Date **Priority Status** Area Number Reason **Assigned To Description Action Taken** Requester Name Location: **GAC** 135227 7/2/2015 201 \$0.00 Medium Work In Progress 7/2/2015 2:31:29 PM SNP Vehicle # 177 needs to be cleaned out and Moncayo, Fernando organized. Maritza Gonzalez Count: 22 Work Orders Total for GAC 0 \$0.00 Avg. Age of WO's 48

1/19/2016 11:45:14 AM Page 53 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID Area Until **Request Date Target Comp Date Davs** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name GAC - Pre-K Location: 136187 Cafeteria 7/21/2015 182 \$0.00 7/21/2015 9:47:47 AM Medium Work In Progress lounge please clean floors in our lounge-(mop) Rodriguez, Arturo Leticia Tangonan Classroom 7/24/2015 179 \$0.00 136470 Medium Work In Progress 7/24/2015 4:49:52 PM Rodriguez, Arturo Carpets in all 6 class rooms need to be vacuumed and shampooed before kids start school. Please see teachers for specific carpets that need cleaning. Leticia Tangonan 145795 Classroom 1/7/2016 12 \$0.00 Work In Progress Medium 1/7/2016 2:18:45 PM please remove door stops that are bolted to the floor in Moncayo, Fernando room 201 Leticia Tangonan 132 9/9/2015 \$0.00 139652 9/9/2015 12:40:15 PM Medium Work In Progress Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez Kitchen 9/18/2015 123 \$0.00 140226 9/18/2015 1:46:43 PM Medium Work In Progress Miranda, Danny GAC Pre-K kitchen -build a wall to separate the kitchen and dining room. Albert Vallejo Classroom 1/12/2016 \$0.00 146053 Medium Work In Progress 201 1/12/2016 11:09:17 AM Moncayo, Fernando could you please cut one of the hook racks and move it down lower to accommodate one of our sped students in room 201-see Ms. viola Leticia Tangonan Count: 6 Work Orders Avg. Age of WO's Total for GAC - Pre-K \$0.00

1/19/2016 11:45:14 AM Page 54 of 153

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	ES					
144558			12/7/2015		43		\$0.00
Medium	Work In Progress	SCHOOL AREA	12/7/2015 8:00:10 AM				
Villalobos,	Margret	good morningneed immediate a get Pest Control for rodentsgreat assistance in this matter					
Loraine Ga	andara						
145951			1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress		1/10/2016 12:28:08 AM				
Ontiveros,	Joe	Monthly - Gadsden ES - Playgrour schedule details.	nd Insp - Refer to PM				
Margret Vil	lalobos						
146130		Cafeteria	1/13/2016		6		\$0.00
Medium	Work In Progress		1/13/2016 8:22:54 AM				
Gonzalez,	Maritza	Garbage Disposal not working sm noise when trying to start. SNP Mar H.882.3410					
Dino Facio	)						
145875		Cafeteria	1/8/2016		11		\$0.00
Medium	Work In Progress		1/8/2016 1:50:37 PM				
Orozco, Da	nniel	As per manager the tilt skillet shoo it's start up for use	ts flames out when				
Dino Facio	)						
146129		Cafeteria	1/13/2016		6		\$0.00
Medium	Work In Progress		1/13/2016 8:21:09 AM				
Orozco, Da		Garbage Disposal not working sm noise when trying to start. SNP Mar H.882.3410					
Dino Facio	)		4 /0 /00 40	4/4 4/0040	40		Φο οο
145473			1/3/2016	1/14/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:45:50 AM				
Ontiveros,		Monthly - Gadsden ES - FE Inspecto PMschedule details.	ction - Monthly - Refer				
Margret Vil	lalobos		44/4/0045	44/00/0045	70		<u></u>
142716			11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress		11/1/2015 12:54:16 AM				
Orozco, Da	niel	Monthly-Gadsden ES-Range Hoot to PMschedule details.	od Cleaning - Refer				
Margret Vil	lalobos						

1/19/2016 11:45:14 AM Page 55 of 153

Total

#### 952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID Until **Request Date Target Comp Date Days** Labor Area **Deferred By** Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Gadsden ES Location: 145028 Classroom 12/15/2015 35 \$0.00 Medium Work In Progress Ms. Marquez 12/15/2015 8:54:47 AM need assistance from DIMAR...need to replace sprinkler Vallejo, Albert in Ms. Marquez office... would greatly appreciate your assistance in this matter.... Loraine Gandara 11/22/2015 11/1/2015 79 \$0.00 142717 Medium Work In Progress 11/1/2015 12:54:17 AM Orozco, Daniel Monthly-Gadsden ES-Fire Suppression Insp-Refer to PMschedule details. Margret Villalobos 1/3/2016 1/11/2016 16 \$0.00 145407 1/3/2016 12:44:45 AM Medium Work In Progress Ontiveros, Joe Monthly - Gadsden ES - Emer Light Test - Monthly -Refer to PMschedule details. Margret Villalobos 10/27/2015 10/11/2015 100 \$0.00 141446 Medium Work In Progress 10/11/2015 12:28:53 Pinon, Jose Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PMschedule details. Margret Villalobos 1/10/2016 1/26/2016 9 \$0.00 145933 1/10/2016 12:27:54 AM Medium Work In Progress Pinon, Jose Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PMschedule details. Margret Villalobos 7/28/2015 175 \$0.00 136579 Medium Work In Progress Playground 7/28/2015 10:29:22 AM please provide us with four trees in front of the school.... Ontiveros, Guadalupe Arborvitae Blue Cone Plant Type: Evergreen, Mature Size: 20' tall x 12' wide Exposure Full sun part shade, space 6-10 feet apart. Water-moderate. Loraine Gandara

1/19/2016 11:45:14 AM Page 56 of 153

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/ Area De Area Number Re Description	eferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	ES						
139709				9/10/2015		131		\$0.00
Medium	Work In Progress			9/10/2015 7:25:13 AM	1			
Ontiveros,	Guadalupe	Please remove tre Texas Ash. Please remove the the trees have gon	e dead ones ASA	AP, and replant once				
Albert Valle	ejo							
136580				7/28/2015		175		\$0.00
Medium	Work In Progress			7/28/2015 10:30:21 AM	1			
Herrera, Ja	aime	Please provide us playgroundsgre matter		ne two our assistance in this				
Loraine Ga	andara							
142949				11/3/2015		77		\$0.00
Medium	Work In Progress	Conference		11/3/2015 9:26:50 AM	1			
Gallegos,		need immediate a coming in greatly a						
Loraine Ga	andara			4.4/0/0045				<b></b>
142862		Restroom		11/2/2015		78		\$0.00
Medium	Work In Progress			11/2/2015 9:32:58 AN	1			
Ontiveros,	Joe	need to replace all	staff toilets					
Joe Ontive	ros							
145778		Cafeteria		1/7/2016		12		\$0.00
Medium	Work In Progress			1/7/2016 9:39:54 AM	1			
Ontiveros,	Joe	cafeteria bustedt	here is a leakv	oe on the roof in the vould greatly matterthank you				
Loraine Ga	andara							
145332				1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:43:38 AN	1			
Ontiveros,	Joe	Yearly - Gadsden schedule details.	ES Backflow Ins	pection - Refer to PM				
Margret Vil	lalobos							
137401		Classroom		8/6/2015		166		\$0.00
Medium	Work In Progress	305		8/6/2015 10:51:39 AM	1			
Chavez, Sa	antos	create class room	nto a labwill no	chasing computers to eed additional outlets your assistance in this				
Loraine Ga	andara							

1/19/2016 11:45:14 AM Page 57 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged **Status** Area Number Reason **Created Date/Time Actual Comp Date Priority Description Action Taken Assigned To** Requester Name Location: Gadsden ES 140066 Office 9/16/2015 125 \$0.00 Ms. Word 9/16/2015 11:25:15 AM Medium Work In Progress Chavez, Santos need immediate assistance with light bulbs in Ms. Word office...would greatly appreciate your assistance in this matter.... Loraine Gandara 176 Cafeteria 7/27/2015 \$0.00 136480 Medium Work In Progress 7/27/2015 7:46:34 AM Chavez, Santos need assistance....llight bulbs in cafeteria gave out...when they do so ... a lot of smoke and a aweful burn smell comes out...greatly appreciate Loraine Gandara Count: 22 Work Orders **Total for Gadsden ES** 0 Avg. Age of WO's 70 \$0.00

1/19/2016 11:45:14 AM Page 58 of 153

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loc <b>Deferred By</b> <b>Reason</b>		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS						
139352				9/4/2015		137		\$0.00
Medium	Work In Progress			9/4/2015 10:53:29 AM				
Chavez, Sa	antos	Irrigation Well -	Need to wire control	S				
Albert Valle		J						
140227	,,,,			9/18/2015		123		\$0.00
Medium	Work In Progress			9/18/2015 1:53:22 PM				
Chavez, Sa	•		rewire outside light nd pulled out wires					
Eric Medin	a							
145315				1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:43:24 AM				
Hernande	z, Guillermo	Yearly - Gadsd schedule detai		pection - Refer to PM				
Margret Vil	lalobos							
141916		Classroom		10/19/2015		92		\$0.00
Medium	Work In Progress	Portable #7		10/19/2015 10:51:52				
Villalobos,	David	small sink and	Ms. Hartmann Portab broken faucet with a an equipment (one re	laundrysink/faucet				
Velia Alarc	on							
144198		Classroom		12/2/2015		48		\$0.00
Medium	Work In Progress	Portable # 7 &	8	12/2/2015 2:45:56 PM				
Villalobos,	David		Vls. Hartmann for Por ter heater in restroor					
Velia Alarc	on							
145387				1/3/2016	1/6/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:44:26 AM				
Medina, Er	ic	Monthly - Gads Refer to PMsch	den HS - Emerg. Ey nedule details.	ewash (Monthly) -				
Margret Vil	lalobos							
143088				11/5/2015		75		\$0.00
Medium	Work In Progress			11/5/2015 7:01:35 AM				
Villalobos,	David		veigth room girls res er flows i tried to unc					

1/19/2016 11:45:14 AM Page 59 of 153

Requester	Status Fo Name	Area Number Reason C Description	reated Date/Time Actual Comp Date Action Taken	Aged	Hours	
Location:	Gadsden	HS				
145118			12/16/2015	34		\$0.00
Medium	Work In Progress	12/1	6/2015 7:49:13 AM			
Villalobos,	David	Need to replace missing knob on sink fauceti restroom of the North building.	n the boys			
Guillermo	Hernandez					
136037	Boys Gym		7/16/2015	187		\$0.00
Medium	Work In Progress	7/1	6/2015 4:00:37 PM			
Villalobos,	David	As per Mr. Giron he would like to have all the working. Location is locker rooms in the Boys				
Guillermo	Hernandez					
144141			12/1/2015	49		\$0.00
Medium	Work In Progress	12/	1/2015 3:50:17 PM			
Villalobos,	David	Install a small WH in portable 8				
Albert Valle	ejo					
145910			1/8/2016	11		\$0.00
Medium	Work In Progress	1/	8/2016 3:58:42 PM			
Lara, Ralp	h	Requested by Claudia Rodriguez for Rm. 134 English Building-Action PAC will be utilizing ro nurse's building is being remodeled. Need for be re-keyed and four keys will be needed.	om since			
Velia Alarc	on					
138952			8/28/2015	144		\$0.00
Medium	Work In Progress	8/2	8/2015 2:15:09 PM			
Lara, Ralp	h	Need to replace the panic bars to back doors of library, the alarm stopped working and they are books.				
Guillermo	Hernandez					
145117			12/16/2015	34		\$0.00
Medium	Work In Progress	12/1	6/2015 7:47:34 AM			
Ambriz, Jo	se	Need to replace one of the gas valve on boile Old English.	er for the			
Guillermo	Hernandez					
145560			1/4/2016	15		\$0.00
Medium	Work In Progress	1/	4/2016 3:44:46 PM			
Hernande	z, Guillermo	Need to check heaters in the Cafeteria.				

1/19/2016 11:45:14 AM Page 60 of 153

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Locat Area Deferred By Area Number Reason Description		arget Comp Date actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
140354			9/21/2015		120		\$0.00
Medium	Work In Progress		9/21/2015 3:52:51 PM				
Ambriz, Jos	se	need to up-grade cooling system at br for computers and ice machine.	reak room to hot				
Guadalupe	e Ontiveros						
141924			10/19/2015		92		\$0.00
Medium	Work In Progress		10/19/2015 12:15:24				
Ambriz, Jos	se	Need to replace two roof top exhaust rooms at the Boys Gym.	fans for the locker				
	Hernandez						
143191			11/6/2015		74		\$0.00
Medium	Work In Progress		11/6/2015 10:47:08 AM				
Castillo, C	arlos	Requested by Coach Vasquez for Foo in Boy's Gym-Install a light switch for F Equipment room.					
Velia Alarc	on						
138008			8/14/2015		158		\$0.00
Medium	Work In Progress		8/14/2015 7:21:53 AM				
Castillo, C	arlos	Need to replace two burn out lamps of parking lot and around the CTE building					
Guillermo	Hernandez						
145999	Varsity Gym	Gym	1/11/2016		8		\$0.00
Medium	Work In Progress		1/11/2016 3:41:32 PM				
Castillo, Ca	arlos	Requested by Ms. L. Chavez for Vars basketball score board keeps flicking problem will need to be resolved as so since District Playwill begin on Tuesd 2016/	on and off. This oon as possible				
Velia Alarc	on						
145928			1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress		1/10/2016 12:27:51 AM				
Saucedo, l	_uis	Monthly - QRTLY BLDG INSP REPOR PMschedule details.	RT (GH) - Refer to				
Margret Vil	lalobos						
145352			1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:43:56 AM				
Hernandez	z, Guillemo	Monthly - Gadsden HS Roof Inspection schedule details.	on - Refer to PM				

1/19/2016 11:45:14 AM Page 61 of 153

WOID Priority Assigned Requester		Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS						
146278				1/15/2016		4		\$0.00
Medium	Work In Progress			1/15/2016 8:17:01 AM				
Flores, Pe	te	Pete need to re	place front tires on	utv 0515 thank you				
Eric Medin	a							
142432				10/27/2015		84		\$0.00
Medium	Work In Progress			10/27/2015 3:49:15 PM				
Flores, Pe	te	Truck GHS #15	5. Gearshift broke	and due for services.				
Guillermo	Hernandez							
142871				11/2/2015		78		\$0.00
Medium	Work In Progress			11/2/2015 10:56:01 AM				
Flores, Pe	te		deere gator uv-ghs senger side not goo					
Luis Sauc	edo							
140867				10/4/2015		107		\$0.00
Medium	Work In Progress			10/4/2015 12:38:15 AM				
Flores, Pe	te	Monthly - GHS- schedule detail	UV-0515 PM Servic s.	e - Refer to PM				
Margret Vi	lalobos							
144164				12/2/2015		48		\$0.00
Medium	Work In Progress			12/2/2015 6:47:00 AM				
Flores, Pe	te		deere gator uv-ghs driving can yuo ples	-0905 is making a lot e see it thank you				
Luis Sauc	edo			10/10/0015				<b>A</b> 2 2 2 2
141599				10/13/2015		98		\$0.00
Medium	Work In Progress			10/13/2015 11:37:31				
Ontiveros,	Guadalupe	regular trash du across from Te	nurse/girls gym.C					
Alfredo Ho	lguin							
141301		Athletic Field		10/8/2015		103		\$0.00
Medium	Work In Progress	Track Field		10/8/2015 3:36:12 PM				
Ontiveros,	Guadalupe	track, track has	Coach Walker for Tra bubbled at the 14 y (3-5). Needs to be re	d marker and has				

1/19/2016 11:45:14 AM Page 62 of 153

Total Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Days** Labor Area **Deferred By** Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Action Taken Assigned To** Description Requester Name Gadsden HS Location: 139129 Classroom 9/1/2015 140 \$0.00 Medium Work In Progress Portable #150 9/1/2015 9:55:53 AM Requested by Coach Yanez for Portable # 150 (Old Lara, Ralph Intervention Portable)-Put a lock or deadbolt on the storage room door which is located inside portable # 150 towards the back of the room. Velia Alarcon Custodial 10/8/2015 103 \$0.00 141254 Medium Work In Progress 10/8/2015 7:39:18 AM Estrada. Jesus mr. estrada is it possible to have a wheelbarrow and two square shovels to clean around the edges of sides walks. thank you Luis Saucedo 1/4/2016 145511 Custodial 15 \$0.00 1/4/2016 9:04:40 AM Medium Work In Progress please i need (2) a 50ft of extention core. Asp Cali, need to request thru Custodial. Carbajal, Jimmy 1/12/16 thank you Luis Saucedo 1/8/2016 11 \$0.00 145885 Medium Work In Progress 1/8/2016 3:42:53 PM Please check sink in the SPED classroom at the Annex Hernandez, Guillermo building for hot water. Guillermo Hernandez 145905 1/8/2016 11 \$0.00 Medium Work In Progress 1/8/2016 3:54:59 PM Hernandez, Guillermo Requested by Mrs. Scott Rm. 515 CTE Building-Window keeps leaking at bottom right side. PLEASE SEE MRS. SCOTT FOR WINDOW LOCATIONS. Velia Alarcon 1/11/2016 8 \$0.00 146031 Medium Work In Progress 1/11/2016 4:15:58 PM Need to check boys restroom at the Annex building, Hernandez, Guillermo urinal is flushing constantly. Guillermo Hernandez

1/19/2016 11:45:15 AM Page 63 of 153

WOID Priority Assigned <sup>1</sup> Requester		Area Number Description	Deferred By Reason		=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	HS							
145665					1/5/2016		14		\$0.00
Medium	Work In Progress			1/5/20	16 3:51:19 PM	1			
Hernande	z, Guillemo	Remove Graffit boys gym.	i from walls in boys I	ocker room at	he				
Guillermo	Hernandez								
145517					1/4/2016		15		\$0.00
Medium	Work In Progress			1/4/20	16 9:19:39 AM				
Hernande	z, Guillermo	Need to check	urnace in the Weigh	nt room.					
Guillermo	Hernandez								
145430					1/3/2016		16		\$0.00
Medium	Work In Progress			1/3/201	6 12:45:08 AM				
Medina, Eı	ic	Monthly - Gads to PMschedule	den HS-Clothes Dr details.	yer (Monthly) -	Refer				
Margret Vil	lalobos								
145426					1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/201	6 12:45:05 AM				
Medina, Eı	ic	Monthly - Gads Refer to PMsch	den HS Emer. Ligh nedule details.	t Test: Monthly	-				
Margret Vil	lalobos								
145449					1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/201	6 12:45:26 AM				
Medina, Eı	ic	Monthly - Gads PMschedule d	den HS Exit Sign In etails.	sp: Monthly - R	efer to				
Margret Vil	lalobos								
146197					1/14/2016		5		\$0.00
Medium	Work In Progress			1/14/20	16 7:55:21 AM				
Medina, Eı	ic	need to organiz	ze basement						
Eric Medin	a								
141917		Classroom			10/19/2015		92		\$0.00
Medium	Work In Progress	Portable #7		10/19	/2015 10:54:48				
Medina, Eı	ic		. Hartmann Portable rooms near sink for						

1/19/2016 11:45:15 AM Page 64 of 153

Total

### 952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Davs** Labor Area **Deferred By** Until Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Assigned To** Description **Action Taken** Requester Name Gadsden HS Location: 144648 Classroom 12/8/2015 42 \$0.00 Work In Progress 12/8/2015 11:45:56 AM Medium Requested by Cathy Cano for Rm. 214 North Building-Medina, Eric Both the U.S. and N.M. flags need to be mounted on wall in class room. Velia Alarcon 11/3/2015 77 \$0.00 142973 Academic Bldg Storage Medium Work In Progress 11/3/2015 3:32:45 PM Medina, Eric Requested by Mr. Martinez for Rm. 342A Old Math Bookroom in Academic Building-Please remove the books helves in the old math bookroom in the Academic Building. Store bookshelves in case they're needed at a later time. Velia Alarcon 146291 North Building Classroom 1/15/2016 \$0.00 Medium Work In Progress 1/15/2016 1:30:40 PM Medina, Eric Requested by Mrs. N. Torres Rm. 211 North Building-Teacher has ordered two dry erase boards that need to be mounted to south wall in class room. The boards are in her storage room (211S1). If possible, let her know if furniture needs to be moved before boards are mounted. Velia Alarcon 143602 11/15/2015 65 \$0.00 Medium Work In Progress 11/15/2015 12:27:53 Yearly-Gadsden HS-Mow (0408/0419/0428) Grounds -Flores. Pete Refer to PMschedule details. Margret Villalobos 1/8/2016 11 \$0.00 145849 Work In Progress 1/8/2016 12:28:52 AM Medium Medina, Eric Daily - Gadsden HS - Fire Pump (Biweekly) - Refer to PMschedule details. Margret Villalobos 1/3/2016 16 \$0.00 145366 Medium Work In Progress 1/3/2016 12:44:08 AM Vallejo, Albert Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PMschedule details.

1/19/2016 11:45:15 AM Page 65 of 153

Margret Villalobos

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
142725			11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress		11/1/2015 12:54:22 AM				
Orozco, Da	niel	Monthly-Gadsden HS Fire Suppre PMschedule details.	ssion Insp Refer to				
Margret Vil	lalobos						
146125			1/13/2016		6		\$0.00
Medium	Work In Progress		1/13/2016 7:47:54 AM				
Carrasco,	Danny	Need fuel for Truck #154 GHS.					
Guillermo	Hernandez						
146126			1/13/2016		6		\$0.00
Medium	Work In Progress		1/13/2016 7:55:02 AM				
Carrasco,	Danny	need fuel for utv 0515 please					
Eric Medin	a						
138687		Athletic Field	8/25/2015		147		\$0.00
Medium	Work In Progress	Baseball Field	8/25/2015 2:32:18 PM	I			
Vallejo, Alt	pert	Requested by Coach Yanez for Bas Baseball Field-Pour cement in bat baseball field.					
Velia Alarc	on						
142703			11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress		11/1/2015 12:54:07 AM				
Orozco, Da	niel	Monthly-Gadsden HS Range Hoo PMschedule details.	d Cleaning - Refer to				
Margret Vil	lalobos						
146050			1/12/2016		7		\$0.00
Medium	Work In Progress		1/12/2016 9:46:07 AM				
Carbajal, J	immy	please i have one dolly with flat tir	es.				
		thank you					
Luis Sauc	edo						
145510		Athletic Field	1/4/2016		15		\$0.00
Medium	Work In Progress		1/4/2016 9:01:56 AM				
Ontiveros,	Guadalupe	997 mower needs drive cluctch rep by warranty not labor.	placed. clutch is cover				
Guadalupe	Ontiveros						

1/19/2016 11:45:15 AM Page 66 of 153

Total

Costs

#### 952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

Building WOID Area Until **Request Date Target Comp Date Davs** Labor **Deferred By** Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Action Taken Assigned To** Description Requester Name Gadsden HS Location: 141291 10/8/2015 103 \$0.00 Medium Work In Progress Weight Room 10/8/2015 1:43:56 PM Lara, Ralph Requested by Mr. Giron for Weight Room-The west end entrance doors into the Weight Room do not close or lock properly. Students pull on the doors and they easily open. There is a chain and pad lock that currently secures the building. However, in case of an emergency, this will become a safety issue when students or staff try to exit the building. For safety and to ensure the security of the equipment the doors or locking mechanism need to be repaired or replaced as soon as possible. Velia Alarcon 146208 **Nursing Center** Office 1/14/2016 5 \$0.00 1/14/2016 9:42:00 AM Medium Work In Progress Gonzales, Camilo Please coordinate w/Memo We need the Sleep Pod in the GHS Nursing Office taken apart and moved to the School Based Health Center on the GMS campus. (The building next to the athletic dept.) This is a very heavy machine and will take several people to move it. Thank you very much! Colleen Runyan RN Colleen Runyan 11/6/2015 74 \$0.00 143192 Medium Work In Progress 11/6/2015 10:49:59 AM Gonzalez, Salvador Requested by Coach Vasquezfor Football Locker Room in the Boy's Gym-Extension to existing wall in equipment room. Velia Alarcon 146296 New Admin Bldg Office 1/15/2016 \$0.00 WILLIAM Medium Work In Progress 1/15/2016 2:40:06 PM PLEASE DELIVER THE FOLLOWING ITEMS TO: Gonzales, Camilo WILLIAM DICKSON 'PO# 151603951 - 1 BOX (UNIFORMS) - GHS SOFTBALL Terry Alvarado

1/19/2016 11:45:15 AM Page 67 of 153

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loca <b>Deferred By</b> <b>Reason</b>	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS							
146297	New Admin Bldg	Office			1/15/2016		4		\$0.00
Medium	Work In Progress	WILLIAM		1/15/2	016 2:41:45 PN	1			
Gonzales,	Camilo	PLEASE DELIV	VER THE FOLLOWIN SON	G ITEMS TO	:				
			E ORDER - 2SETS C OR SOFTBALL AND		RS				
Terry Alvar		D Have a			0/05/0045		440		ФО ОО
140674	Main Building	Pump House		- / /-	9/25/2015	_	116		\$0.00
Medium	Work In Progress			9/25/2	015 4:01:26 PM	1			
Sanchez, F	Raul	chlorination eq	vork order for the insta uiptment for the supp emergencyuse		mestic				
		Thanks, Raul							
Raul Sand	hez								
145543					1/4/2016		15		\$0.00
Medium	Work In Progress			1/4/20	16 11:31:52 AM	1			
Gonzalez,	Salvador	Need to weld fr	ame on North door of	the Weight ro	oom.				
Guillermo	Hernandez								
145765					1/7/2016		12		\$0.00
Medium	Work In Progress			1/7/2	016 7:49:36 AM	1			
Gonzalez,	Salvador	Need adjust No replace missin	orth gate by the North I ig wheel.	ouilding and					
	Hernandez								
139963	Pool Pump	Pump House			9/15/2015		126		\$0.00
Medium	Work In Progress			9/15/2	015 7:55:51 AM	1			
Gonzalez,	Salvador	fabricate squar shade	re tubing post to supp	ort pool cand	рру				
Mario Apo	daca								
142662					10/31/2015		80		\$0.00
Medium	Work In Progress			10/3	1/2015 12:34:37	,			
Sanchez, F	Raul		den HS-WWTP Cher er to PM schedule de						
Margret Vil	lalobos								

1/19/2016 11:45:15 AM Page 68 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Area Until **Days** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: Gadsden HS 144521 12/6/2015 44 \$0.00 Medium Work In Progress 12/6/2015 12:40:32 AM Sanchez, Raul Monthly - Gadsden HS - Lift Station Inspection - Refer to PMschedule details. Margret Villalobos 11/14/2015 66 \$0.00 143599 Medium Work In Progress 11/14/2015 12:27:49 Sanchez, Raul Monthly - Gadsden HS- Filters (Pump Rm) Quarterly -Refer to PMschedule details. Margret Villalobos 1/3/2016 16 \$0.00 145463 1/3/2016 12:45:40 AM Medium Work In Progress Sanchez, Raul Monthly - Gadsden HS - Lift Station Inspection - Refer to PMschedule details. Margret Villalobos 12/18/2015 32 \$0.00 145272 Medium Work In Progress 12/18/2015 11:54:03 DRYER BURNT APRONS MIT ETC. DRYING. SNP Orozco, Daniel MANAGER FRANCES B. 882.5522 Maritza Gonzalez 144378 Pool Pump Pump House 12/4/2015 46 \$0.00 12/4/2015 1:55:47 PM Medium Work In Progress GHS NEED TO REORDER POOL WATER FILTERS Apodaca, Mario Mario Apodaca Count: 69 Work Orders Total for Gadsden HS \$0.00 Avg. Age of WO's 54

1/19/2016 11:45:15 AM Page 69 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID Until **Request Date Target Comp Date Davs** Labor Area **Deferred By** Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Gadsden MS Location: 138518 C-Wing Office 8/21/2015 151 \$0.00 AVECHS -8/21/2015 2:37:51 PM Medium Work In Progress PLEASE BUILT IN COUNTERS FOR STUDENT UNION Marquez, Gerardo ROOM. Yvette Cortez Office 151 \$0.00 138519 C-Wing 8/21/2015 Medium Work In Progress AVECHS -8/21/2015 2:40:17 PM Marquez, Gerardo NEED OPEN SHELVING FOR KITCHEN AREA. PLEASE CONTACT MRS. HOOD OR MRS QUEZADA FOR FURTHER DETAILS AT 882-6770. Yvette Cortez 7 146119 Classroom 1/12/2016 \$0.00 Medium Work In Progress A-Wing Rm#157 1/12/2016 5:17:34 PM Herrera, Mario Please replace pencil sharpener. Thank you Hilda Adler Office 6 \$0.00 1/13/2016 146190 Front Office Medium Work In Progress 1/13/2016 4:24:34 PM Herrera, Mario Please replace 2 lights in the supply room in the back of the front office and 1 in Hilda's office located on the back. thank you. Hilda Adler 145142 Gym Gym 12/16/2015 34 \$0.00 Medium Work In Progress 12/16/2015 1:57:47 PM Need new hoist controls for basketball courts Herrera, Mario Mario Herrera 1/3/2016 16 \$0.00 145465 Medium Work In Progress 1/3/2016 12:45:42 AM Apodaca, Mario Monthly - Gadsden MS - Lift Station Inspection - Refer to PMschedule details. Margret Villalobos 10/31/2015 \$0.00 142661 Medium Work In Progress 10/31/2015 12:34:36 Monthly - Gadsden MS-WWTP Chemical Order Apodaca, Mario (Monthly) - Refer to PM schedule details. Margret Villalobos

1/19/2016 11:45:15 AM Page 70 of 153

Priority Assigned <sup>:</sup> Requester		Area Number Reason Description	Created Date/Time	Actual Comp Date Action Taken	Aged	Hours	
Location:	Gadsden	MS					
146223			1/14/2016		5		\$0.00
Medium	Work In Progress		1/14/2016 12:49:18 PM				
Orozco, Da	aniel	AS PER ENVIRONMENT FOOD E INSPECTION 1.14.16- ICE BUILD FREEZER. SNP MANAGER TERR	UP INSIDE WALK IN				
Maritza Go	nzalez						
145051			12/15/2015		35		\$0.00
Medium	Work In Progress		12/15/2015 10:37:46				
Orozco, Da		MILK COOLER - SIDE PANEL DO SAFETY HAZARD. SNP MANAGER 882.2824					
Maritza Go							
145782	C-Wing	Portables	1/7/2016		12		\$0.00
Medium	Work In Progress		1/7/2016 10:13:41 AM	1			
Gonzales,	Camilo	Would like small refrigerator from moved to Gadsden Elementary Nu					
Lisa Alarc	on						
146273		Classroom	1/14/2016		5		\$0.00
Medium	Work In Progress	B-Wing RM#132	1/14/2016 4:35:44 PM	1			
Gonzales,	Camilo	Hello! Mrs. Foster does not have a books asked Enrique at the warehouse if her from San Miguel. Camilo calle would bring one, however he need you create one please? Thank you, Nicole Ortiz Special Education Reading Special Office 575-882-6253	he can bring one for d me and said he ls a work order. Can				
Hilda Adle			40/4/0045		40		<b>#</b> 0.00
144336	East Mechanical		12/4/2015		46		\$0.00
Medium	Work In Progress		12/4/2015 8:27:19 AM	1			
Marquez, 0	Gerardo	Requesting new doors to boiler room	om				
Mario Herr	era						
144337			12/4/2015		46		\$0.00
Medium	Work In Progress		12/4/2015 8:28:05 AM	1			
Marquez, 0	Gerardo	Requesting new doors to mechan cafeteria	ical room behind				

1/19/2016 11:45:15 AM Page 71 of 153

WOID Priority Assigned Requester	Building Status To	Area Number Description	/30/2016 Order By Loc <b>Deferred By</b> <b>Reason</b>		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
142704				11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress			11/1/2015 12:54:08 AM	I			
Orozco, Da	-	Monthly - Gads PMschedule d		d Cleaning - Refer to				
Margret Vil	lalobos							
141514	Band Room	Classroom		10/12/2015		99		\$0.00
Medium	Work In Progress	Rm#100 Band	/	10/12/2015 2:58:44 PM				
Estrada, Je	esus	Repairsnags	on carpet, office and i	nnerrooms.				
Hilda Adle	r							
142726				11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress			11/1/2015 12:54:22 AM	I			
Orozco, Da	niel	Monthly - Gads PMschedule d		ssion Insp Refer to				
Margret Vil	lalobos							
145149				12/16/2015		34		\$0.00
Medium	Work In Progress			12/16/2015 3:14:39 PM				
Herrera, M	ario	trouble shootin	g exterior lighting an	d interior				
Mario Herr	era							
141772				10/15/2015		96		\$0.00
Medium	Work In Progress			10/15/2015 12:14:52				
Herrera, M	ario	Need to order I	ist of Filters that was	s giving to Danny C.				
Mario Herr	era							
144995				12/14/2015		36		\$0.00
Medium	Work In Progress			12/14/2015 3:48:35 PM				
Estrada, Je	esus	need to replace	e VCT and Carpt (o	n stage) in back				
Jesus Esti	ada							
145936				1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/2016 12:27:56 AM	I			
Soria, Mart	in	Monthly - QRTL PMschedule d	YBLDG INSP REPo	ORT (GM) - Refer to				
Margret Vil	lalobos							
142015		Classroom		10/20/2015		91		\$0.00
Medium	Work In Progress	B-Wing Rm#11	7	10/20/2015 3:02:16 PM				
Soria, Mart	in	Please clean li	ght fixtures.					
Hilda Adle	r							

1/19/2016 11:45:15 AM Page 72 of 153

Total

#### 952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID Until **Request Date Target Comp Date Days** Labor **Deferred By** Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Gadsden MS Location: 142290 Storage 10/26/2015 85 \$0.00 10/26/2015 8:48:07 AM Medium Work In Progress Old Main Soria, Martin Please clean and mop room to get it ready for storage. Will be used for Panther Closet. If any questions please see Terry Urbina or Carol Hernandez. Hilda Adler Foyer 10/23/2015 88 \$0.00 142226 C-Wing Work In Progress Medium AVECHS -10/23/2015 10:34:51 Carbajal, Jimmy we needs floor mats in front entrance. slipperywhen wet.. AVECHS - ANNEX Rosa Quezada Athletic Field 1/4/2016 15 \$0.00 145515 1/4/2016 9:10:40 AM Medium Work In Progress Vasquez, Jose P.V.B needs to be replaced leaking over winter break Guadalupe Ontiveros 1/5/2016 \$0.00 C-Wing **Portables** 14 145631 1/5/2016 2:44:05 PM Medium Work In Progress Herrera, Mario Roof in Nursing Dept portable leaking. Lisa Alarcon 1/3/2016 1/11/2016 16 \$0.00 145375 1/3/2016 12:44:16 AM Medium Work In Progress Herrera, Mario Monthly - Gadsden MS Roof Inspection - Refer to PM schedule details. Margret Villalobos Classroom 1/14/2016 5 \$0.00 146233 Medium Work In Progress A-Wing SPED 1/14/2016 3:30:17 PM Chavez, Santos Electrician: Need electrical wiring for new in-focus, in Sped Conference room. Need in-focus for IEP Meetings. Hilda Adler 145391 1/3/2016 1/19/2016 16 \$0.00 1/3/2016 12:44:30 AM Medium Work In Progress Monthly - Gadsden MS Monthly Chiller Insp. - Refer to EM 1/5/16 Villalobos, Margret PMschedule details. Margret Villalobos

1/19/2016 11:45:15 AM Page 73 of 153

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until  Area Number Reason Cre  Description	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS					
140796			9/30/2015		111		\$0.00
Medium	Work In Progress	9/30/2	015 12:43:19 AN	1			
Herrera, M	/ario	Monthly - Gadsden MS A-16 Fan Exhaust Semi Refer to PMschedule details.	annual -				
Margret Vi	llalobos						
140809			10/4/2015	11/4/2015	107		\$0.00
Medium	Work In Progress	10/4/2	015 12:37:35 AN	1			
Herrera, M	<i>l</i> lario	Yearly - Gadsden MS I-4 Fan Coil Unit Yearly - PMschedule details.	Refer to				
Margret Vi							
141771	Cafeteria	Cafeteria	10/15/2015		96		\$0.00
Medium	Work In Progress	10/	15/2015 11:58:35	5			
Solis, Lore	enzo	Requesting new AC units (master cools) 9 of the	em				
Mario Her	rera						
145038	C-Wing	Portables	12/15/2015		35		\$0.00
Medium	Work In Progress	12/15/	2015 9:24:13 AN	1			
Marquez,	Gerardo	Would like to change lock on Nursing Dept. doo	r.				
Lisa Alarc	on						
145201	C-Wing	Portables	12/17/2015		33		\$0.00
Medium	Work In Progress	12/	17/2015 11:09:29	)			
Marquez,	Gerardo	Would like outside doors of portable re keyed P. Dept.	Nursing				
Lisa Alarc	on						
145125		Cafeteria	12/16/2015		34		\$0.00
Medium	Work In Progress	12/16/	2015 8:52:29 AN	1			
Marquez,	Gerardo	PLEASE GET A PRICE QUOTE TO REFURBIS REPLACE CAFETERIA ROLL UP DELIVERY D					
Gerardo N	Marquez						
146219			1/14/2016		5		\$0.00
Medium	Work In Progress	1/14/2	016 11:44:57 AN	1			
Marquez,	Gerardo	Need assistance opening door for lights on top	of roof				
Mario Her	rera						
146289			1/15/2016		4		\$0.00
Medium	Work In Progress	Front Office-Gulf 1/15/2	016 12:05:14 PM	1			
Marquez,	Gerardo	Need 6 keys for New Gulf Cart. Approved per N Quinonez. Should you need additional informati please contact Connie Avalos. Thank you					
Hilda Adle	er						
1/19/2016	6 11:45:15 AM					Page 7	74 of 153

1/19/2016 11:45:15 AM Page 74 of 153

WOID Priority	Building Status	Area Area Number	6/30/2016 Order By Loc Deferred By Reason	Until Requ		Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned -		Description				Action Taken			
Requeste	r Name								
Location:	Gadsden	MS							
145683		Classroom			1/5/2016		14		\$0.00
Medium	Work In Progress	B-Wing Rm#1	15	1/5/2016 4	:26:42 PN	1			
Marquez,	Gerardo	Door doesn't d	close or lock, please	fix. thank you.					
Hilda Adle	er								
143488				1	1/12/2015		68		\$0.00
Medium	Work In Progress			11/12/2015 3	:31:25 PM	I			
Marquez,	Gerardo		/chain and padlock fo EPEC can double loc						
Albert Vall	ejo								
143775				1	1/18/2015		62		\$0.00
Medium	Work In Progress			11/18/201	5 12:13:09	)			
Marquez,	Gerardo	SNP OFFICES	, NEED 4 CD1 KEYS	FOR STORAGE.					
Maritza Go	onzalez								
146137					1/13/2016		6		\$0.00
Medium	Work In Progress			1/13/2016 10	):15:48 AM	1			
Marquez,	Gerardo		N DOOR IS NOT SH TCH. SNP MANAGE		Υ,				
Maritza Go	onzalez								
145979					1/11/2016		8		\$0.00
Medium	Work In Progress	See Mr.Mora		1/11/2016 9	):54:29 AM	1			
Marquez,	Gerardo	storage with (1	n expanded metal sto I) expanded door & ( c. Mora for details. Th	1) loft key.					
Hilda Adle	er								
137816	C-Wing			;	8/12/2015		160		\$0.00
Medium	Work In Progress	AVECHS -		8/12/2015 9	0:06:55 AM	1			
Marquez,	Gerardo	Need keys issu Counselor Eve	ued for Custodian Je elyn Chisari.	remy Apodaca and					
Margret Vi	llalobos								
146342					1/19/2016		0		\$0.00
Medium	Work In Progress			1/19/2016 8	3:28:55 AM	1			
Vallejo, Al	bert	Order 3" strain	ersets for west chille	er/boiler.					

1/19/2016 11:45:15 AM Page 75 of 153

Albert Vallejo

Total

# 952 - Work Orders In Progress (Fiscal Year)

Selected Da <b>WOID</b>	te Range for Request <b>Building</b>	Dates:7/1/2015 - 6 <b>Area</b>	5/30/2016 Order By Loc Deferred By	cation, Status <b>Until</b>	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Crea	ted Date/Time	<b>Actual Comp Date</b>	Aged	Hours	
Assigned <sup>*</sup>		Description				Action Taken			
Requester	Name								
Location:	Gadsden	MS							
140575	Annex	Hallway/Corrid	lor		9/24/2015		117		\$0.00
Medium	Work In Progress			9/24/2	015 3:17:11 PN	1			
Solis, Lore	nzo	water fountain i	in annexis leaking						
		Please contact	Mario Herrera						
Mario Herr	era								
146231		Classroom			1/14/2016		5		\$0.00
Medium	Work In Progress	A-Wing Rm#15	56	1/14/2	016 3:22:29 PN	1			
Solis, Lore	nzo		varm air for a while the se check, thank you.		come				
Hilda Adle	r								
144581					12/7/2015		43		\$0.00
Medium	Work In Progress			12/7/2	015 2:01:49 PN	1			
Solis, Lore	nzo	Requesting ne	w heaters for Boys a	nd girls locke	r-rooms				
Mario Herr	era								
145791	Gymnasium				1/7/2016		12		\$0.00
Medium	Work In Progress			1/7/20	16 12:21:50 PN	1			
Solis, Lore	en <b>z</b> o	RTU in Gym Io to work for abou	bby heating is not w ut 30mins	orking have t	o reset				
Mario Herr	era								
143387		Classroom			11/10/2015		70		\$0.00
Medium	Work In Progress	A-Wing Rm#16	69	11/10/2	015 2:49:53 PM	I			
Ontiveros,	Joe	Washing Mach Please fix ASA	ine is not spinning to P.	drain the wa	ter.				
Hilda Adle	r								
145316					1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress			1/3/20	16 12:43:25 AM	1			
Herrera, M	ario	Yearly - Gadsd schedule detail	len MS Backflow Ins ls.	pection - Ref	er to PM				
Margret Vil	lalobos								
140230	Annex	Restroom			9/18/2015		123		\$0.00
Medium	Work In Progress			9/18/2	015 2:27:59 PN	1			
Ontiveros,	Joe	please replace leaving them or	e new sink faucets wi n.	th new ones I	rids are				
Martin Sor	a								

1/19/2016 11:45:15 AM Page 76 of 153

Selected Da WOID Priority Assigned	Building Status	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requeste		Description		Action runch			
Location:	Gadsden	MS					
146039	Gym	Mechanical	1/12/2016		7		\$0.00
Medium	Work In Progress		1/12/2016 8:00:16 AM	1			
Ontiveros	, Joe	Domestic water heater in Mechar relief valve is leaking	nical room pressure				
Mario Her	rera						
138659			8/25/2015		147		\$0.00
Safety	Work In Progress		8/25/2015 9:23:01 AM	1			
Ontiveros	, Joe	Eye Wash - All 3 missing string for valve is broken asp PM136938	shower and 002-				
Mario Her	rera						
139909			9/14/2015		127		\$0.00
Medium	Work In Progress		9/14/2015 2:07:22 PN	И			
Chavez, S	Santos	Please see Mario, Building Mecha Signs	anic regarding Exit				
Mario Her							
139952	Annex		9/14/2015		127		\$0.00
Medium	Work In Progress	Annex Electrical	9/14/2015 4:04:27 PN	Л			
Chavez, S	Santos	Annex electrical box is not working	orjumping as well.				
Hilda Adle	er						
140237	C-Wing		9/18/2015		123		\$0.00
Medium	Work In Progress	Main Annex	9/18/2015 3:00:33 PN	Л			
Chavez, S	Santos	THERE WAS A POWER OURTAG PLEASE EVALUATE SITUATION :					
Yvette Co							
145141	Main Building		12/16/2015		34		\$0.00
Medium	Work In Progress		12/16/2015 1:54:48 PM	1			
Chavez, S	Santos	Need to rewire projector in SPED	conference room				
Mario Her	rera						
145853			1/8/2016		11		\$0.00
Medium	Work In Progress		1/8/2016 7:45:19 AM	1			
Chavez, S	Santos	Please supply electricity of prope unit to be placed at SNP offices.	r voltage for new HVAC				
Albert Vall	lejo						
143779			11/18/2015		62		\$0.00
Medium	Work In Progress		11/18/2015 1:03:44 PM	1			
Chavez, S	Santos	Silver is checking on the scoreboare having issues. He thinks it is					
Cora Ram	nirez						
1/19/2016	3 11:45:15 AM					Page 7	7 of 153

1/19/2016 11:45:15 AM Page 77 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Area Until **Days** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Gadsden MS Location: 145060 C-Wing Foyer 12/15/2015 35 \$0.00 Work In Progress **AVECHS-**12/15/2015 12:59:53 Medium WE NEED A DOORBELL INSTALLED IN THE FRONT Chavez, Santos **ENTRANCE** Rosa Quezada Office C-Wing 12/15/2015 35 \$0.00 145061 Medium Work In Progress **AVECHS-**12/15/2015 1:02:11 PM Chavez, Santos THE LIGHT SWITCH IN THE WORKROOM NEEDS TO BE MOVED TO THE FRONT OF THE ROOM ENTRANCE INSTEAD OF BY THE EXIT DOOR. (QUEZADA) Rosa Quezada Band Room Classroom 141522 10/12/2015 99 \$0.00 Medium Work In Progress Rm#100 Band/ 10/12/2015 3:10:56 PM Chavez, Santos Install wall electrical outlet under sink. Hilda Adler Football Field 127 9/14/2015 \$0.00 139948 Work In Progress Medium Electrical/Field -9/14/2015 3:58:31 PM Chavez, Santos Electrical ground box by the football field to connect the football clock is not working. Hilda Adler Total for Gadsden MS Count: 62 Work Orders Avg. Age of WO's 55 0 \$0.00

1/19/2016 11:45:15 AM Page 78 of 153

WOID Priority Assigned 1 Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loc <b>Deferred By</b> <b>Reason</b>	Until Re	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	La Union	ES							
145319					1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress			1/3/2016	12:43:27 AM	I			
Aguilar, Pa	tricio	Yearly - La Uni schedule detail	on ES Backflow Insp s.	ection - Refer to	PM				
Margret Vil	lalobos								
142676					11/1/2015		79		\$0.00
Medium	Work In Progress			11/1/2015	12:53:49 AM	I			
Aguilar, Pa	tricio	Yearly - La Uni schedule detail	on ES - Grease Trap s.	- Refer to PM					
Margret Vil	lalobos								
146153					1/13/2016		6		\$0.00
Medium	Work In Progress			1/13/201	6 2:56:39 PM	1			
Aguilar, Pa	tricio	wo to myself - I tiles rest room	need to replace toile kitchen	t wax gasket - fl	oor				
Patricio Ag	uilar								
143854					11/19/2015		61		\$0.00
Medium	Work In Progress			11/19/201	5 2:49:02 PM				
Castillo, Ca	arlos	emergencyligh	nt fixer needing ballas	str310					
Patricio Ag	uilar								
145985					1/11/2016		8		\$0.00
Medium	Work In Progress			1/11/2016	11:23:35 AM	I			
Castillo, Ca	arlos	Also please ch 302 and 304 a	#35 panel L2-A, circueck for leaks in the 30 and in room 308. Sho se call Mr. Ralph Gal	00 hallwaybyRo ould you have an	om y				
Dominique	e Esparza								
145370					1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/2016	12:44:12 AN	I			
Aguilar, Pa	tricio	Monthly - La Ur schedule detail	nion ES Roof Inpsec s.	tion - Refer to P	M				
Margret Vil	lalobos								
145942					1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/2016	12:28:01 AM	I			
Ramos, Ru	udy	Monthly - QRTL PMschedule de	Y BLDG INSP REPO	ORT (LU) - Refe	r to				

1/19/2016 11:45:15 AM Page 79 of 153

Total

#### 952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID Until **Request Date Target Comp Date Davs** Labor Area **Deferred By** Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name La Union ES Location: 137072 8/3/2015 169 \$0.00 Medium Work In Progress 8/3/2015 10:29:17 AM please see Alfredo on this work order Holguin, Alfredo wo as per Alfredo Holguin room # of rooms that have leaks. 100-110-106-104-103-101-lounge old wing all on the same side. 201-203-204-207-208 old roof as the one being replaced. 208-209-110 metal roof leaks after new ac were installed Patricio Aguilar 1/3/2016 1/11/2016 16 \$0.00 145447 Medium Work In Progress 1/3/2016 12:45:24 AM Monthly - La Union ES Exit Sign Insp: Monthly - Refer to Aguilar, Patricio PMschedule details. Margret Villalobos 1/3/2016 1/11/2016 16 \$0.00 145448 1/3/2016 12:45:25 AM Medium Work In Progress Monthly - La Union ES Emer. Light Test: Monthly -Aguilar, Patricio Refer to PMschedule details. Margret Villalobos 11/1/2015 11/22/2015 79 \$0.00 142727 Medium Work In Progress 11/1/2015 12:54:23 AM Orozco, Daniel Monthly - La Union ES Fire Suppression Insp. - Refer to PMschedule details. Margret Villalobos 140718 9/28/2015 113 \$0.00 Medium Work In Progress 9/28/2015 3:52:17 PM Remove sand and plastic borders and replace with Vallejo, Albert woodchips and concrete at south playground. Albert Vallejo 11/1/2015 11/22/2015 79 \$0.00 142705 Medium Work In Progress 11/1/2015 12:54:09 AM Orozco, Daniel Monthly - La Union ES Range Hood Cleaning - Refer to PMschedule details.

1/19/2016 11:45:15 AM Page 80 of 153

Margret Villalobos

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Deferred By Request Date Target Comp Date** Labor Area Until **Days** Hours Aged Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: La Union ES 145491 1/3/2016 1/9/2016 16 \$0.00 Medium Work In Progress 1/3/2016 12:46:08 AM Aguilar, Patricio Monthly - La Union ES Monthly FE Inpsection - Refer to PMschedule details. Margret Villalobos 7 Office 1/12/2016 \$0.00 146044 Main Building Medium Work In Progress Diagnostician's 1/12/2016 8:51:14 AM Gonzales, Camilo Please pick up an interactive white board that is in the diagnostician's office and deliver to the special ed department in Anthony. If possible please have technician notifythe special ed office as to when this will be done. They can call the office at 575-882-6221. Thank you. Susie Ramos Lara 145957 1/10/2016 1/26/2016 9 \$0.00 1/10/2016 12:28:13 AM Medium Work In Progress Monthly - La Union ES Playground Insp - Refer to PM Aguilar, Patricio schedule details. Margret Villalobos Count: 16 Work Orders Avg. Age of WO's 44 **Total for La Union ES** 0 \$0.00

1/19/2016 11:45:15 AM Page 81 of 153

WOID Priority	Building Status	Dates:7/1/2015 - 6/30/2016 Order By Area Deferred By Area Number Reason		-	Days Aged	Labor Hours	Costs
Assigned Requeste		Description		Action Taken			
Location:	Loma Lin	nda ES					
145950			1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress		1/10/2016 12:28:07 AM		3		Ψ0.00
	Work In Progress						
Pacheco,	Hector	Monthly - Loma Linda ES Playg schedule details.	round Insp - Refer to PM				
Margret V	illalobos						
145400			1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:39 AM				
Pacheco,	Hector	Monthly - Loma Linda ES Emer Refer to PMs chedule details.	r. Light Test: Monthly -				
Margret V	illalobos						
145401			1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:40 AM				
Pacheco,	Hector	Monthly - Loma Linda ES Exit S to PMschedule details.	ign Insp: Monthly - Refer				
Margret V	illalobos						
145402			1/3/2016		16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:41 AM				
Pacheco,	Hector	Monthly - Loma Linda ES - Clot Refer to PMschedule details.	thes Dryer (Monthly) -				
Margret V							
144250	Main Building	Athletic Field	12/3/2015		47		\$0.00
Medium	Work In Progress		12/3/2015 8:37:43 AM				
Pacheco,	Hector	Need to extend sprinkler valve b	oxes 6 inches higher.				
Hector Pa	icheco						
145978	Main Building	Classroom	1/11/2016		8		\$0.00
Medium	Work In Progress	107	1/11/2016 9:46:41 AM				
Pacheco,	Hector	Mr. Pacheco please go to San Student Corral and place it in roc Richhart, as per IEP we need S	om 107 with Ms.				
Angie Flo	res						
144197	Main Building	Exterior	12/2/2015		48		\$0.00
Medium	Work In Progress		12/2/2015 2:22:51 PM				
Pacheco,	Hector	In need of 580 feet of Fence Wi on east side fence.	nd Screen to be installed				
Hector Pa	icheco						

1/19/2016 11:45:15 AM Page 82 of 153

141378	WOID Priority Assigned Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loc <b>Deferred By</b> <b>Reason</b>		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Medium         Work In Progress         Kitchen         10/9/2015 2:43:55 PM           Orozzoo, Dariel         Replace drain grill in front of tilts killet. Per ergonomic inspection the drain grill should be replaced with any appropriate style. Please call Cynthia with any questions 882-6949.         Section 11/6/2015         74         \$           Cynthia         Tax 195         11/6/2015 11:22:11 AM         74         \$           Medium         Work In Progress         11/6/2015 11:22:11 AM         74         \$           Orozzo, Dariel         ICE MACHINE IS NOT MAKING ICE.         Work In Progress         10/26/2015 2:01:06 PM         85         \$           Medium         Work In Progress         10/26/2015 2:01:06 PM         85         \$         \$           Carrasco, Danny         In need of a scissor lift. Need to reach 20 feet or higher to service heating units in cafeteria.         11/1/2015 12:54:09 AM         79         \$           Hector Patrice         Work In Progress         11/1/2015 12:54:09 AM         11/22/2015 79         \$           Medium         Work In Progress         11/3/2016 12:45:55 AM         1/9/2016 16         \$           Medium         Work In Progress         1/3/2016 12:45:55 AM         1/9/2016 16         \$           Pacheco, Hector         Monthly - Loma Linda ES Monthly FE Inpsection - Refer         1/9/2016 16	Location:	Loma Lin	nda ES						
Orozzoo, Dahlel         Replace drain grill in front of tilt skillet. Per ergonomic inspection the drain grill should be replaced with any questions 882-6949.           Cynthia Maes           14/3195         11/6/2015         74         \$           Medium         Work in Progress         11/6/2015 11:22:11 AM         **         **           Orozzoo, Daniel         IN CE MACHINE IS NOT MAKING ICE.         **	141376				10/9/2015		102		\$0.00
Page	Medium	Work In Progress	Kitchen		10/9/2015 2:43:55 PM	M			
143195         11/6/2015         74         \$           Medium         Work In Progress         11/6/2015 11:22:11 AM         74         \$           Orozzo, Daniel         ICE MACHINE IS NOT MAKING ICE.         Wartze Gonzalez         10/26/2015 11:22:11 AM         85         \$           Medium         Work In Progress         10/26/2015 2:01:06 PM         85         \$           Carrasco, Danny         In need of a scissor lift. Need to reach 20 feet or higher to service heating units in cafeteria.         11/1/2015 11:22:50 79         \$           Hector Pacheco         142706         11/1/2015 12:54:09 AM         11/22/2015 79         \$           Medium         Work In Progress         11/1/2015 12:54:09 AM         11/22/2015 79         \$           Margret Villalobos         1/3/2016 12:45:55 AM         \$         \$           Medium         Work In Progress         1/3/2016 12:45:55 AM         \$         \$           Pacheco, Hector         Monthly- Loma Linda ES Monthly FE Inpsection - Refer to PMschedule details.         \$         \$           Margret Villalobos         138748         Main Building         Classroom         8/26/2015 7:46:19 AM         \$           Estrada, Jesus         In classroom 222 the plastic the edge of the carpet part of it came of its needs to be replaced.         \$         \$	Orozco, Da	aniel	inspection the appropriate sty	drain grill should be i le. Please call Cynth	replaced with an				
Medium         Work In Progress         11/6/2015 11:22:11 AM           Orozco, Daniel         ICE MACHINE IS NOT MAKING ICE.           Maritza Gonzalez         142315 Main Building Cafeteria 10/26/2015 85 \$	Cynthia M	aes							
Orazzo, Daniel         ICE MACHINE IS NOT MAKING ICE.           Maritza Gorzalez           142315         Main Building         Cafeteria         10/26/2015 2:01:06 PM         85         \$           Medium         Work In Progress         10/26/2015 2:01:06 PM         ***         ***           Carrasco, Danny         In need of a scissor lift. Need to reach 20 feet or higher to service heating units in cafeteria.         *** </td <td>143195</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>74</td> <td></td> <td>\$0.00</td>	143195						74		\$0.00
Maritza Suzer           142315         Main Building         Cafeteria         10/26/2015 2:01:06 PM         \$	Medium	Work In Progress			11/6/2015 11:22:11 AN	Л			
142315       Main Building       Cafeteria       10/26/2015       85       \$         Medium       Work In Progress       10/26/2015 2:01:06 PM	Orozco, Da	aniel	ICE MACHINE	IS NOT MAKING ICE	<u>.</u>				
Medium         Work In Progress         10/26/2015 2:01:06 PM           Carrasco, Danny         In need of a scissor lift. Need to reach 20 feet or higher to service heating units in cafeteria.           Hector Pacheco           142706         11/1/2015         11/22/2015         79         \$           Medium         Work In Progress         11/1/2015 12:54:09 AM         11/1/2015 12:54:09 AM           Orozco, Daniel         Monthly-Loma Linda ES Range Hood Cleaning - Refer to PMschedule details.         145478         1/3/2016 12:45:55 AM           Medium         Work In Progress         1/3/2016 12:45:55 AM         1/9/2016 16         \$           Pacheco, Hector         Monthly-Loma Linda ES Monthly FE Inpsection - Refer to PMschedule details.         1/3/2016 12:45:55 AM         1/9/2016 16         \$           Margret Villalobos         138748         Main Building         Classroom         8/26/2015 7:46:19 AM         \$           Estrada, Jesus         In classroom 222 the plastic the edge of the carpet part of it came of its needs to be replaced.         4         \$           Alfredo Ambriz         Classroom         11/20/2015 2:26:44 PM         \$           Estrada, Jesus         Classroom         11/20/2015 2:26:44 PM         \$           Estrada, Jesus         CARPET IS TORN CREATING A HAZARD FOR CHILDREN         CARPET IS TORN CREATING	Maritza Go	onzalez							
In need of a scissor lift. Need to reach 20 feet or higher to service heating units in cafeteria.	142315	Main Building	Cafeteria		10/26/2015		85		\$0.00
Hector Pacheco  142706	Medium	Work In Progress			10/26/2015 2:01:06 PM	1			
142706         11/1/2015         11/22/2015         79         \$           Medium         Work In Progress         11/1/2015 12:54:09 AM         ***         ***         ***         ***         ***         ***         ***         ***         ***         ***         ***         ***         ***         ***         ***         **         *** </td <td>Carrasco,</td> <td>Danny</td> <td></td> <td></td> <td>ach 20 feet or higher</td> <td></td> <td></td> <td></td> <td></td>	Carrasco,	Danny			ach 20 feet or higher				
Medium         Work In Progress         11/1/2015 12:54:09 AM           Orozco, Daniel         Monthly-Loma Linda ES Range Hood Cleaning - Refer to PMschedule details.           Margret Villalobos         1/3/2016         1/9/2016         16         \$           Medium         Work In Progress         1/3/2016 12:45:55 AM         1/9/2016         16         \$           Pacheco, Hector         Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PMschedule details.         ***         ***         ***           Margret Villalobos         ***         8/26/2015         146         \$           138748         Main Building         Classroom         8/26/2015 7:46:19 AM         ***           Estrada, Jesus         In classroom 222 the plastic the edge of the carpet part of it came of its needs to be replaced.         ***         ***           Alfredo Ambriz         ***         ***         ***         ***           143932         Classroom         11/20/2015         60         ***           Medium         Work In Progress         Music Portable         11/20/2015 2:26:44 PM           Estrada, Jesus         CARPET IS TORN CREATING A HAZARD FOR CHILDREN	Hector Pa	checo							
Orozco, Daniel Monthly-Loma Linda ES Range Hood Cleaning - Refer to PMschedule details.  Margret Villalobos  145478	142706				11/1/2015	11/22/2015	79		\$0.00
Margret Villalobos	Medium	Work In Progress			11/1/2015 12:54:09 AN	Л			
145478       1/3/2016       1/9/2016       16       \$         Medium       Work In Progress       1/3/2016 12:45:55 AM         Pacheco, Hector       Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PMschedule details.         Margret Villalobos         138748       Main Building       Classroom       8/26/2015       146       \$         Medium       Work In Progress       8/26/2015 7:46:19 AM         Estrada, Jesus       In classroom 222 the plastic the edge of the carpet part of it came of its needs to be replaced.         Alfredo Ambriz         143932       Classroom       11/20/2015       60       \$         Medium       Work In Progress       Music Portable       11/20/2015 2:26:44 PM         Estrada, Jesus       CARPET IS TORN CREATING A HAZARD FOR CHILDREN	Orozco, Da	aniel			od Cleaning - Refer				
Medium Work In Progress 1/3/2016 12:45:55 AM  Pacheco, Hector Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PMschedule details.  Margret Villalobos  138748 Main Building Classroom 8/26/2015 146 \$  Medium Work In Progress 8/26/2015 7:46:19 AM  Estrada, Jesus In classroom 222 the plastic the edge of the carpet part of it came of its needs to be replaced.  Alfredo Ambriz  143932 Classroom 11/20/2015 60 \$  Medium Work In Progress Music Portable 11/20/2015 2:26:44 PM  Estrada, Jesus CARPET IS TORN CREATING A HAZARD FOR CHILDREN		llalobos							
Pacheco, Hector  Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PMschedule details.  Margret Villalobos  138748 Main Building Classroom 8/26/2015 146 \$  Medium Work In Progress  8/26/2015 7:46:19 AM  Estrada, Jesus In classroom 222 the plastic the edge of the carpet part of it came of its needs to be replaced.  Alfredo Ambriz  143932 Classroom 11/20/2015 60 \$  Medium Work In Progress Music Portable 11/20/2015 2:26:44 PM  Estrada, Jesus CARPET IS TORN CREATING A HAZARD FOR CHILDREN	145478				1/3/2016	1/9/2016	16		\$0.00
Margret Villalobos  138748 Main Building Classroom 8/26/2015 146 \$  Medium Work In Progress 8/26/2015 7:46:19 AM  Estrada, Jesus In classroom 222 the plastic the edge of the carpet part of it came of its needs to be replaced.  Alfredo Ambriz  143932 Classroom 11/20/2015 60 \$  Medium Work In Progress Music Portable 11/20/2015 2:26:44 PM  Estrada, Jesus CARPET IS TORN CREATING A HAZARD FOR CHILDREN	Medium	Work In Progress			1/3/2016 12:45:55 AN	Л			
138748 Main Building Classroom 8/26/2015 146 \$  Medium Work In Progress 8/26/2015 7:46:19 AM  Estrada, Jesus In classroom 222 the plastic the edge of the carpet part of it came of its needs to be replaced.  Alfredo Ambriz  143932 Classroom 11/20/2015 60 \$  Medium Work In Progress Music Portable 11/20/2015 2:26:44 PM  Estrada, Jesus CARPET IS TORN CREATING A HAZARD FOR CHILDREN	Pacheco,	Hector			E Inpsection - Refer				
Medium Work In Progress 8/26/2015 7:46:19 AM  Estrada, Jesus In class room 222 the plastic the edge of the carpet part of it came of its needs to be replaced.  Alfredo Ambriz  143932 Classroom 11/20/2015 60 \$  Medium Work In Progress Music Portable 11/20/2015 2:26:44 PM  Estrada, Jesus CARPET IS TORN CREATING A HAZARD FOR CHILDREN									
Estrada, Jesus In class room 222 the plastic the edge of the carpet part of it came of its needs to be replaced.  Alfredo Ambriz  143932 Classroom 11/20/2015 60 \$  Medium Work In Progress Music Portable 11/20/2015 2:26:44 PM  Estrada, Jesus CARPET IS TORN CREATING A HAZARD FOR CHILDREN		•	Classroom				146		\$0.00
of it came of its needs to be replaced.  Alfredo Ambriz  143932 Classroom 11/20/2015 60 \$  Medium Work In Progress Music Portable 11/20/2015 2:26:44 PM  Estrada, Jesus CARPET IS TORN CREATING A HAZARD FOR CHILDREN	Medium	Work In Progress			8/26/2015 7:46:19 AN	Л			
143932 Classroom 11/20/2015 60 \$  Medium Work In Progress Music Portable 11/20/2015 2:26:44 PM  Estrada, Jesus CARPET IS TORN CREATING A HAZARD FOR CHILDREN	Estrada, J	esus							
Medium Work In Progress Music Portable 11/20/2015 2:26:44 PM  Estrada, Jesus CARPET IS TORN CREATING A HAZARD FOR CHILDREN		nbriz							
Estrada, Jesus CARPET IS TORN CREATING A HAZARD FOR CHILDREN	143932		Classroom		11/20/2015		60		\$0.00
CHILDREN	Medium	Work In Progress	Music Portable		11/20/2015 2:26:44 PM	1			
Angie Flores	Estrada, J	esus		RN CREATING A H	AZARD FOR				
	Angie Flor	res							

1/19/2016 11:45:15 AM Page 83 of 153

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time Area Description	-	Days Aged	Labor Hours	Costs
Location:	Loma Lin	ida FS				
142728	Loma Lin	11/1/2015	11/22/2015	79		\$0.00
_	Mork In Drogram		11/22/2013	13		ψ0.00
Medium	Work In Progress	11/1/2015 12:54:24 AM				
Orozco, Da		Monthly-Loma Linda ES Fire Suppression Insp Refer to PMschedule details.				
Margret Vil	lalobos	1/0/00/0	1/0.1/0.10			<b>A</b> 0 00
145362		1/3/2016	1/24/2016	16		\$0.00
Medium	Work In Progress	1/3/2016 12:44:04 AM				
Vallejo, Alb	pert	Monthly - Loma Linda ES Fire Sprinkler Insp Refer to PMschedule details.				
Margret Vil	lalobos					
145350		1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress	1/3/2016 12:43:54 AM				
Pacheco, I	Hector	Monthly - Loma Linda ES Roof Inpsection - Refer to PM schedule details.				
Margret Vil	lalobos					
145935		1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress	1/10/2016 12:27:56 AM				
Ambriz, Alf	redo	Monthly - QRTLY BLDG INSP REPORT (LL) - Refer to PMschedule details.				
Margret Vil	lalobos					
146079		Mechanical 1/12/2016		7		\$0.00
Medium	Work In Progress	1/12/2016 3:40:57 PM				
Solis, Lore	enzo	Need help with boiler not working properly.				
Hector Pag	checo					
139345		9/4/2015		137		\$0.00
Medium	Work In Progress	All around the 9/4/2015 9:31:04 AM				
Pacheco, I	Hector	Repaint door frames in all entrance doors and office doors.				
Angie Flore	es					
143659	Main Building	Classroom 11/16/2015		64		\$0.00
Medium	Work In Progress	11/16/2015 3:42:27 PM				
Chavez, Sa	antos	Need to replace ballast room #102 poor lighting in room.				
Hector Pag						
143656	Main Building	Office 11/16/2015		64		\$0.00
Medium	Work In Progress	11/16/2015 3:40:40 PM				
Chavez, Sa	-	Need to replace a few ballast in main office.				
Jilavez, Se	anios	record to replace a few ballastiff finality lines.				

1/19/2016 11:45:15 AM Page 84 of 153

Total

#### 952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID Until **Request Date Target Comp Date Days** Labor Area **Deferred By** Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Loma Linda ES Location: 143647 Main Building Office 11/16/2015 64 \$0.00 11/16/2015 3:32:22 PM Medium Work In Progress Chavez, Santos Need to replace emergency ballast in Principal Lawlor office. **Hector Pacheco** Restroom 60 \$0.00 143944 Main Building 11/20/2015 11/20/2015 3:37:51 PM Medium Work In Progress Ontiveros. Joe Need assistance replacing flush valve in boys restroom across teachers lounge. **Hector Pacheco** 124 \$0.00 Main Building Restroom (Girls) 9/17/2015 140150 Medium Work In Progress 9/17/2015 11:52:44 AM Ontiveros, Joe Can you please come and fix the drainer from the girl restroom from the front of the teachers lunch room its clogged up thank you. Alfredo Ambriz Main Building Restroom 12/2/2015 48 \$0.00 144165 Medium Work In Progress 12/2/2015 7:42:04 AM Ontiveros, Joe Need to replace gaskets on flush valve teachers rest room across teachers lounge. **Hector Pacheco** Main Building Restroom 10/21/2015 \$0.00 142127 10/21/2015 4:02:58 PM Medium Work In Progress Ontiveros, Joe Need to replace commode not working properly in room 109 Ms Carleyroom. **Hector Pacheco** 1/3/2016 2/3/2016 16 \$0.00 145317 Medium Work In Progress 1/3/2016 12:43:25 AM Yearly - Loma Linda ES Backflow Inspection - Refer to Pacheco, Hector PMschedule details. Margret Villalobos Count: 28 Work Orders Avg. Age of WO's 54 Total for Loma Linda ES 0 \$0.00

1/19/2016 11:45:15 AM Page 85 of 153

WOID Priority Assigned Requester		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Mesquite	ES						
145772	Main Building			1/7/2016		12		\$0.00
Medium	Work In Progress	Main Office		1/7/2016 8:53:17 AM	1			
Appelzolle	r, Fred		umber to install water storage located in m					
Sandra Mo	ora							
142969				11/3/2015		77		\$0.00
Medium	Work In Progress			11/3/2015 3:16:43 PM	1			
Appelzolle	r, Fred	need to install a	small elec. water hea	ter in early childhood				
Joe Ramir	ez							
145320				1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:43:28 AM	1			
Ramirez, J	loe	Yearly - Mesqu schedule detai	-	ection - Refer to PM				
Margret Vil								
138289	Main Building	Cafeteria		8/18/2015		154		\$0.00
Medium	Work In Progress	Cafeteria		8/18/2015 4:08:23 PM	1			
Chavez, Sa	antos	Requesting, su	uggest power surge p	protector ASAP.				
Sandra Mo	ora							
145770	Main Building	Storage		1/7/2016		12		\$0.00
Medium	Work In Progress	Main Office		1/7/2016 8:49:28 AM	1			
Chavez, Sa	antos	power to powe	nirez/Bldg. Mech. we r a new refrigerator m talled. Thank you					
Sandra Mo	ora							
144199	Pump House	Pump House		12/2/2015		48		\$0.00
Medium	Work In Progress			12/2/2015 2:47:12 PM	1			
Chavez, Sa	antos	the well pump	room need new lighti	ng fixtures				
Mario Apo	daca							
140233	Pump House	Pump House		9/18/2015		123		\$0.00
Medium	Work In Progress			9/18/2015 2:52:32 PM	1			
Chavez, Sa	antos		ol boxneed to identify ntrol system to well a					
Mario Apo	daca							

1/19/2016 11:45:15 AM Page 86 of 153

Selected Dat WOID Priority Assigned I Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Mesquite	ES					
141899			10/19/2015		92		\$0.00
Medium	Work In Progress		10/19/2015 6:33:12 AN	1			
Chavez, Sa	antos	we have 5 parking lot/ security lig replaced.	hts out need to be				
Joe Ramir	ez						
139560			9/8/2015		133		\$0.00
Medium	Work In Progress		9/8/2015 10:14:50 AM	1			
Chavez, Sa	antos	we have 4 parking/security lights	that are not working				
Joe Ramir	ez						
138478	Main Building		8/21/2015		151		\$0.00
Medium	Work In Progress	Cafeteria	8/21/2015 7:53:48 AM	1			
Chavez, Sa	antos	outlet is loose in cafeteria.					
Sandra Mo	ora						
137278			8/5/2015		167		\$0.00
Medium	Work In Progress		8/5/2015 8:23:26 AM	1			
Chavez, Sa		Environmental Park - Check if it is electrical power to this area- cost					
Alfredo Ho							
146206	Main Building		1/14/2016		5		\$0.00
Medium	Work In Progress	Room # 402	1/14/2016 9:03:58 AM	1			
Solis, Lore	nzo	Gracie Moreno/Kinder, room was	to cold. Thank you				
Sandra Mo	ora						
136170	2003 Classroom	Hallway/Corridor	7/20/2015		183		\$0.00
Medium	Work In Progress	E Wing	7/20/2015 3:59:34 PM	1			
Marquez, G	Gerardo	Need staff name plaque's for the f Munoz, L. Baldauf, C. Zuloaga, G M. Martinez. Thank you, Sandy					
Sandra Mo	ora						
145943			1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress		1/10/2016 12:28:02 AM	1			
Valles, Mar	rio	Monthly - QRTLY BLDG INSP RE PMschedule details.	PORT (MQ) - Refer to				
Margret Vil	lalobos						
145530			1/4/2016		15		\$0.00
Medium	Work In Progress		1/4/2016 10:33:36 AM	1			
Valles, Mar		SOAP DISPENSER IS LEAKING. EMILIA C. 233.2341	SNP MANAGER				
Maritza Go	nzalez						

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area Until **Days Deferred By** Hours Aged Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: **Mesquite ES** 142729 11/1/2015 11/22/2015 79 \$0.00 Medium Work In Progress 11/1/2015 12:54:25 AM Orozco, Daniel Monthly - Mesquite ES Fire Suppression Insp. - Refer to PMschedule details. Margret Villalobos 11/3/2015 77 \$0.00 142965 Main Building Medium Work In Progress Main Office 11/3/2015 1:55:34 PM Estrada. Jesus Main Office need carpet repair 2 seam repair. Thank you, Sandy Sandra Mora 11/1/2015 11/22/2015 79 \$0.00 142707 Work In Progress 11/1/2015 12:54:10 AM Medium Orozco, Daniel Monthly - Mesquite ES Range Hood Cleaning - Refer to PMschedule details. Margret Villalobos 1/3/2016 16 \$0.00 145469 Medium Work In Progress 1/3/2016 12:45:46 AM Monthly - Mesquite ES - Lift Station Inspection - Refer Apodaca, Mario to PMschedule details. Margret Villalobos Count: 19 Work Orders Avg. Age of WO's 76 **Total for Mesquite ES** 0 \$0.00

1/19/2016 11:45:15 AM Page 88 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Davs** Labor Area **Deferred By** Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Action Taken Assigned To** Description Requester Name Location: North Valley ES 140342 9/21/2015 120 \$0.00 9/21/2015 3:48:33 PM Medium Work In Progress Orozco, Daniel AS PER HEALTH INSPECTION REPORT 9/10/15, WALK IN FLOOR PANEL COMING UP, REPLACE RUBBER BOTTOM SPACES AS THEY START TO CRUBMLE. Maritza Gonzalez 12/4/2015 \$0.00 144369 46 Medium Work In Progress 12/4/2015 11:40:22 AM Gonzalez, Salvador soccer goal bottom bar needs welded/plus need some metal spikes to anchor down goals Danny Vega 1/26/2016 1/10/2016 9 \$0.00 145948 1/10/2016 12:28:06 AM Medium Work In Progress Monthly - North Valley ES Playground Inspection - Refer Vega, Danny to PMschedule details. Margret Villalobos 1/3/2016 1/9/2016 16 \$0.00 145477 Medium Work In Progress 1/3/2016 12:45:54 AM Monthly - North Valley ES Monthly FE Inpsection - Refer Vega, Danny to PMschedule details. Margret Villalobos 11/1/2015 142696 79 \$0.00 11/1/2015 12:54:03 AM Medium Work In Progress Orozco, Daniel Monthly - North Valley ES - Range Hood Cleaning -Refer to PMschedule details. Margret Villalobos 1/3/2016 16 \$0.00 145367 Medium Work In Progress 1/3/2016 12:44:09 AM Vallejo, Albert Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PMschedule details. Margret Villalobos 1/3/2016 16 \$0.00 145338 Work In Progress 1/3/2016 12:43:43 AM Medium Monthly - North Valley ES - Fire Pump Engine - Refer to Vallejo, Albert PMschedule details. Margret Villalobos

1/19/2016 11:45:16 AM Page 89 of 153

WOID Priority Assigned Requester	Building Status To	•	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	North Va	lley ES				
145287		12/24/2015	5	26		\$0.00
Medium	Work In Progress	12/24/2015 12:29:3	2			
Vega, Dan	_	Daily - North Valley ES - Fire Pump (Biweekly) - Refer to PMschedule details.				
Margret Vil	llalobos					
142731		11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress	11/1/2015 12:54:26 Al	M			
Orozco, Da	aniel	Monthly - North Valley ES Fire Suppression Insp Refer to PMschedule details.				
Margret Vil	llalobos					
136000		Cafeteria 7/16/2015	5	187		\$0.00
High	Work In Progress	7/16/2015 1:32:41 Pl	М			
Solis, Lore	enzo	Wash all windows inside and out (cafeteria)				
Jesus Est	rada					
145925		1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress	1/10/2016 12:27:48 Al	М			
Solis, Luis		Monthly - QRTLY BLDG INSP REPORT (NV) - Refer to PMschedule details.				
Margret Vil	llalobos					
142953		Athletic Field 11/3/2015	5	77		\$0.00
Medium	Work In Progress	11/3/2015 10:31:01 Al	М			
Ontiveros,	Guadalupe	Need Soccer Goal Nets-(2)-20ft L x 8ft H x 6ft D				
Gloria Rey	/es					
145348		1/3/2016	5 1/11/2016	16		\$0.00
Medium	Work In Progress	1/3/2016 12:43:52 Al	M			
Vega, Dan	nny	Monthly - North Valley ES Roof Inspection - Refer to PM schedule details.				
Margret Vil	llalobos					
145439		1/3/2016	5 1/11/2016	16		\$0.00
Medium	Work In Progress	1/3/2016 12:45:17 A	M			
Vega, Dan	nny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PMschedule details.				
Margret Vil	llalobos					<b>^ ^ ^ - -</b>
145442		1/3/2016		16		\$0.00
Medium	Work In Progress	1/3/2016 12:45:20 Al	М			
Vega, Dan	-	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.				
Margret Vil	llalobos					

WOID	Building		Deferred By	Until Request Date	-	Days	Hours	
Priority	Status	Area Number	Reason	Created Date/Time	·-	Aged	Hours	
Assigned 1		Description			Action Taken			
Requester	Name							
Location:	North Val	lley ES						
143845		Hallway/Corrido	or	11/19/2015		61		\$0.00
Medium	Work In Progress			11/19/2015 1:28:39 PM				
Chavez, Sa	antos	copiers by our o	e electrical outlets office area. Per the e is enough ampe Min. of 25 amps.	e service tech need to				
Gloria Rey	es							
141189				10/7/2015		104		\$0.00
Medium	Work In Progress			10/7/2015 8:35:13 AM	I			
Chavez, Sa	antos			me type)lamps that are der bulbs if not in stock				
Danny Veg	a							
141341				10/9/2015		102		\$0.00
Medium	Work In Progress			10/9/2015 7:25:07 AM	I			
Chavez, Sa	antos		astoutin hallway( o grand wing byrn	(pecan valley) by rm n 305 -402-				
Danny Veg	а							
146282				1/15/2016		4		\$0.00
Medium	Work In Progress			1/15/2016 9:52:33 AM	I			
Chavez, Sa	antos	Need to replace hallway,302,30	emergencylights 3,304, and 305	s in 300-wing				
Danny Mira	anda							
146283				1/15/2016		4		\$0.00
Medium	Work In Progress			1/15/2016 9:53:31 AM	I			
Chavez, Sa	antos	need to replace hallway,302,30	emer. lights in 30 3,304, and305	0-wing				
Danny Mira	anda							
146284				1/15/2016		4		\$0.00
Medium	Work In Progress			1/15/2016 9:56:42 AM	I			
Chavez, Sa	antos	need to replace 206,207,208, a		wing hallway204,				
Danny Mira	anda							
146058		Hallway/Corrido	or	1/12/2016		7		\$0.00
Medium	Work In Progress	200 WING		1/12/2016 12:58:03 PM				
Chavez, Sa	entos	Need to replace	light fixture due to	burned out lamp				

1/19/2016 11:45:16 AM Page 91 of 153

Selected Dat	e Range for Request <b>Building</b>	Dates:7/1/2015 - 6	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned 1	Го	Description				Action Taken			
Requester	Name								
Location:	North Va	lley ES							
143843					11/19/2015		61		\$0.00
Medium	Work In Progress			11/1	9/2015 11:49:18				
Appelzollei	r, Fred	water leak on ck out/ ne fenc	4inch shut off valve b	y back flows	/please				
Danny Veg	а								
143556					11/13/2015		67		\$0.00
Medium	Work In Progress			11/13/2	015 1:44:13 PM				
Appelzollei	r, Fred		m toilet object stuck - n it)please help-wont		snake				
Danny Veg	a								
142541					10/29/2015		82		\$0.00
Medium	Work In Progress			10/2	9/2015 10:30:21				
Appelzollei	r, Fred	run faucet oper	ot water takes to long n for a long time.Need es to have hot water a	small 3 gal					
Danny Veg	а								
146195					1/14/2016		5		\$0.00
Medium	Work In Progress			1/14/2	016 7:38:01 AM	I			
Appelzollei	r, Fred		e 1 inch elbow from th Valley. Call Memo for		e fire				
Guillermo	Hernandez								
145330					1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress			1/3/20	16 12:43:36 AM	I			
Vega, Dan	ny	Yearly - North \ PMschedule d	/alley ES Backflow In: etails.	spection - R	efer to				
Margret Vil	lalobos								
143541		Office			11/13/2015		67		\$0.00
Medium	Work In Progress			11/1	3/2015 10:03:55				
Appelzollei	r, Fred	unless it is left wasteful and ke Please can a s	ffice at NVE does not running for 5 minutes eeps student from goi mall hot water heater Colleen Runyan, RN	. This is very ng back to c	ass.				
Colleen Ru	unyan								

1/19/2016 11:45:16 AM Page 92 of 153

Location: 145609	Northern			Action Taken	Aged	Hours	
		On-Track Pre-K (LM)					
Madium			1/5/2016		14		\$0.00
Medium	Work In Progress		1/5/2016 9:45:15 AM				
Ramirez, Jo	De	need 5 old bulletin boards in storage mrs. angelics request	e rooms moved to				
Brian Pach	eco						
145349			1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:43:53 AM				
Vega, Danr	ny	Monthly - La Mesa ES Roof Inpsecti schedule details.	on - Refer to PM				
Margret Vill	alobos						
144371			12/4/2015		46		\$0.00
Medium	Work In Progress		12/4/2015 11:52:32 AM				
Vallejo, Alb		class room at old cafeteria rms need roofing/plus clothing bank used bys new shingles.(currently used as sto VALLEJO	ocial workers need				
Danny Veg			2/22/22/2				
140486	Main Building	Athletic Field	9/23/2015		118		\$0.00
Medium	Work In Progress	outside	9/23/2015 1:57:54 PM				
Ontiveros, 0	Guadalupe	There is a new canopy in our cafete set up where our sandbox is for the sonot have appropriate shade to be who located and they are digging holes not set to be whose the set of	tudents. Theydo ere the sand is	9/29/15 - Asp Albert	, route to (	Grounds	
Concepcio	n Montalvo						
145921			1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress		1/10/2016 12:27:45 AM				
Pacheco, B	rian	Monthly - QRTLY BLDG INSP REPORT Refer to PMschedule details.	PRT (LMPRE-K) -				
Margret Vill	alobos						
145949			1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress		1/10/2016 12:28:06 AM				
Vega, Danr	ny	Monthly - Northern Pre-K Playgroun schedule details.	d Insp - Refer to PM				
Margret Vill							
146070	Main Building	Lift Station	1/12/2016		7		\$0.00
Medium	Work In Progress		1/12/2016 3:02:09 PM				
Apodaca, N	Mario	need to order a spare wastewater li	ftpump				

1/19/2016 11:45:16 AM Page 93 of 153

**Total** Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Priority Status Assigned To Description Action Taken** Requester Name Location: Northern On-Track Pre-K (LM) 145464 1/3/2016 16 \$0.00 Medium Work In Progress 1/3/2016 12:45:41 AM Monthly - Northern Pre-K -Lift Station Inspection - Refer Apodaca, Mario to PMschedule details. Margret Villalobos Count: 8 Work Orders Avg. Age of WO's 29 0 \$0.00 Total for Northern On-Track Pre-K (LM)

1/19/2016 11:45:16 AM Page 94 of 153

Total

# 952 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request <b>Building</b>	Dates:7/1/2015 - 6 <b>Area</b>	6/30/2016 Order By Loc <b>Deferred By</b>	cation, Status <b>Until</b>	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned		Description				Action Taken			
Requeste		-							
Location:	Physical	Plant Complex							
138657					8/25/2015		147		\$0.00
Medium	Work In Progress			8/25/2	015 8:53:15 AN	1			
Apodaca,	Mario		l fittings for the new L ant at ppd also to be i		ne				
Mario Apo	odaca								
145303					12/31/2015		19		\$0.00
Medium	Work In Progress			12/3	1/2015 12:49:09	)			
Apodaca,	Mario	Monthly - PPD/ PMschedule d	/GHS - WW Monthly letails.	Sampling - R	efer to				
Margret Vi	illalobos								
143987					11/30/2015		50		\$0.00
Medium	Work In Progress			11/3	0/2015 12:51:58	3			
Apodaca,	Mario	Monthly - PPD/ PMscheduled	/GHS - WW Monthly letails.	Sampling - R	efer to				
Margret Vi	illalobos								
137531		Lift Station			8/7/2015		165		\$0.00
Medium	Work In Progress			8/7/2	015 3:13:14 PN	1			
Gonzalez,	, Salvador	the uv system s metal to cover	shaded area need to the uv system	o put more sh	eet				
Mario Apo	odaca								
144247					12/3/2015		47		\$0.00
Medium	Work In Progress			12/3/2	015 7:42:04 AN	1			
Ronquillo	, Ruben	need blinds fo	r front office @ PPD						
144666		Pump House			12/8/2015		42		\$0.00
Medium	Work In Progress			12/8/2	015 3:17:39 PN	1			
Apodaca,	Mario	need to put a n box for the blo	ew selector switches wer motor	s at the contro	l panel				
Mario Apo	odaca								
144738	Maintenance	Pump House			12/9/2015		41		\$0.00
Medium	Work In Progress			12/9/2	015 2:43:24 PN	1			
Apodaca,	Mario		et toxicity testing need b at sage environme						
Mario Apo	odaca								

1/19/2016 11:45:16 AM Page 95 of 153

WOID Priority Assigned T	Building Status o	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Area Number Reason Created Date/Time Description	Target Comp Date Days Actual Comp Date Aged Action Taken	
Location:		Plant Complex		
145632		1/5/2016	14	\$0.
Medium	Work In Progress	1/5/2016 2:49:25 PM		***
Vallejo, Alb	-	Make repairs to fire sprinklers to to correct deficiencies found at annual inspection.		
Albert Valle	ejo	·		
143690		11/17/2015	63	\$0.
Medium	Work In Progress	11/17/2015 7:40:21 AM		
Flores, Pet	е	Jd needs new batttery.		
Guadalupe	Ontiveros			
145608		1/5/2016	14	\$0.
Medium	Work In Progress	1/5/2016 9:40:07 AM		
Ronquillo,	Ruben	NEED TO ORDER 3 NEW CHAINSAWS.		
Ruben Ror	nquillo			
146147	•	1/13/2016	6	\$0.
Medium	Work In Progress	1/13/2016 2:17:38 PM		
Apodaca, N	Mario	ghs wastewater plant need a water hose of 100'		
Mario Apod	laca			
135167	Motor Vehicle	7/1/2015	202	\$0.
Medium	Work In Progress	7/1/2015 9:19:42 AM		
Marquez, G	Gerardo	NEED TO INSTALL DOOR AT METAL BLDG. ON WESTSIDE OF AUTOSHOP. THIS WILL BE THE SMALL DR. NEXT TO ROLL UP DR.		
Gerardo Ma	arquez			
143513		11/12/2015	68	\$0.
Medium	Work In Progress	11/12/2015 3:53:13 PM		
Gonzalez, S	Salvador	Need to frame for installation of insulation of back shop.		
Salvador G	onzalez			
143609		11/16/2015	64	\$0.
Medium	Work In Progress	11/16/2015 7:43:51 AM		
Gonzalez, S	Salvador	Sal can you please construct a pipe rack with a shade at the Morgan building at the GAC. Thanks		
David Villal	obos			
143285		11/9/2015	71	\$0.
Medium	Work In Progress	11/9/2015 8:02:05 AM		
Gonzalez, S	Salvador	need to replace broken masonry drill bits		
Salvador G	onzalez			

1/19/2016 11:45:16 AM Page 96 of 153

WOID Priority Assigned		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex						
138019				8/14/2015		158		\$0.00
Medium	Work In Progress			8/14/2015 8:57:46 AM				
Marquez, C	Gerardo	PLEASE MEET QUOTE.	WITH DR. VENDOR	R FOR PRICE				
Gerardo M	arquez							
140460				9/23/2015		118		\$0.00
Medium	Work In Progress			9/23/2015 8:36:42 AM				
Marquez, C			S RUSTED. PLEASI ND LOCKSMITH EI	E REPLACE AT NTRANCE. THANK				
Ruben Ro	nquillo	000		0 10 10 0 4 5		100		<b>A</b> 0 00
139632		Office		9/9/2015		132		\$0.00
Medium	Work In Progress			9/9/2015 9:35:50 AM				
Marquez, C	Gerardo	Please install d APCO.	oors and windows,	when they arrive from				
Danny Mira	anda							
141695				10/14/2015		97		\$0.00
Medium	Work In Progress			10/14/2015 2:47:58 PM				
Marquez, C	Gerardo		ole at each North Dis e start with LLE per					
Cynthia Ma	ies							
143448				11/12/2015		68		\$0.00
Medium	Work In Progress			11/12/2015 8:29:14 AM				
Marquez, C	Gerardo		CLOSURE INSTALL ONT OF COPY MAC	ED ON NEW DOOR HINE.				
Alfredo Ho	lguin							
141694				10/14/2015		97		\$0.00
Medium	Work In Progress			10/14/2015 2:45:35 PM				
Lara, Ralpl	1		ole at each South Disse start with STMS	strict school kitchen per ergonomic				
Cynthia Ma	ies							
145977				1/11/2016		8		\$0.00
Scheduled	Work In Progress			1/11/2016 9:36:50 AM				
Ontiveros,	Guadalupe	we need extra l replaced.	keys for kubota tract	or and seat has to be				
Guadalupe	Ontiveros	-						

1/19/2016 11:45:16 AM Page 97 of 153

WOID Priority Assigned 1 Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex						
145135	Motor Vehicle			12/16/2015		34		\$0.00
Medium	Work In Progress	VEHICLE#164		12/16/2015 11:26:36				
Flores, Pet	e	PLEASE CHEC	CK FOR ANY SCHE	DULED				
Pete Flores								
145872	Motor Vehicle			1/8/2016		11		\$0.00
Medium	Work In Progress	vehicle#129		1/8/2016 12:41:34 PM				
Flores, Pet	te	please replace	windshield washer	reservoir				
Pete Flores	S							
145860	Motor Vehicle			1/8/2016		11		\$0.00
Medium	Work In Progress	vehicle#36		1/8/2016 9:17:50 AM				
Flores, Pet	e	please check fo	or any scheduled ma	intenance				
Pete Flores	S							
145976	Motor Vehicle			1/11/2016		8		\$0.00
Medium	Work In Progress	vehicle#162		1/11/2016 9:35:36 AM				
Flores, Pet	e	please check c	ause of low tire pres	sure				
Pete Flores	S							
146087	Motor Vehicle			1/12/2016		7		\$0.00
Medium	Work In Progress	vehicle#08		1/12/2016 3:45:01 PM				
Flores, Pet	e	please check fo	or any scheduled ma	intenance				
Pete Flores	s							
146150	Main Warehouse			1/13/2016		6		\$0.00
Medium	Work In Progress	vehicle#12		1/13/2016 2:53:41 PM				
Flores, Pet	te	please check fo	or any scheduled ma	intenance				
Pete Flores	S							
146198	Motor Vehicle			1/14/2016		5		\$0.00
Medium	Work In Progress	vehicle#183		1/14/2016 8:08:20 AM				
Flores, Pet	e	gear selector h please check a	as difficultydisenga nd advise.	ging from park.				
Pete Flores								
145698	Motor Vehicle			1/6/2016		13		\$0.00
Medium	Work In Progress			1/6/2016 10:00:47 AM				
Flores, Pet Maria Ruiz		vehicle 47 heat on	er blows constantly;	check engine light in				

1/19/2016 11:45:16 AM Page 98 of 153

WOID	Building		eferred By	<u>-</u>	Target Comp Date	Days Aged	Labor Hours	
Priority Assigned <sup>-</sup>	Status	Area Number Ro	eason	Created Date/Time	Action Taken	7.900	110410	
Requester		Description			Action Taken			
Location:		Plant Complex						
		Tiant Complex		4 /4 4 /0040				<u>ФО 00</u>
146224	Motor Vehicle			1/14/2016	_	5		\$0.00
Medium	Work In Progress			1/14/2016 2:35:50 PM				
Perez, Rau	ıl	put logos and vehi	cle #6 on new o	dump truck				
Maria Ruiz								
146214	Motor Vehicle			1/14/2016		5		\$0.00
Medium	Work In Progress	vehicle#169		1/14/2016 10:50:51 AM	l			
Flores, Pe	te	please check cond	dition of battery					
Pete Flore	S							
146216	Motor Vehicle			1/14/2016		5		\$0.00
Medium	Work In Progress	equip.#0512-		1/14/2016 10:52:55 AM	l			
Flores, Per	te	fork lift not starting	please check a	and advise				
Pete Flore	S	J						
146218	Motor Vehicle			1/14/2016		5		\$0.00
Medium	Work In Progress	equip.#0400		1/14/2016 11:27:06 AM				
Flores, Per	te	mower will not sta	rt . please chec	k and advise				
Pete Flore								
145374	<u> </u>			1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:44:15 AV				·
Herrera, M	-	Monthly - Physical schedule details.	Plant Roof Ins	pection - Refer to PM				
Margret Vil	lalobos							
146281	Motor Vehicle			1/15/2016		4		\$0.00
Medium	Work In Progress	vehicle#15		1/15/2016 8:48:08 AM	l			
Flores, Per	te	please check for a	nyscheduled r	naintenance				
Pete Flore	S							
145025	Motor Vehicle			12/15/2015		35		\$0.00
Medium	Work In Progress			12/15/2015 8:27:51 AM				
Flores, Per	-	Brakes are grindir	na leakina antif	reeze Thank vou				
Jose Amb		Brakes are grinair	ig,ioaitiig airtii	10020. Marik you				
143202	Motor Vehicle			11/6/2015		74		\$0.00
Medium	Work In Progress	vehicle#54		11/6/2015 11:33:49 AV	l			Ψ0.00
	-				ı			
Flores, Pe	ie	please check for a	ny required ma	untenance				

1/19/2016 11:45:16 AM Page 99 of 153

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 O Area Deferre Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		Plant Complex					
143226	Maintenance		11/6/2015		74		\$0.00
Medium	Work In Progress		11/6/2015 2:34:46 PM	I			
Flores, Pet	te	vehicle 15 needs a driver	s rear lens				
Maria Ruiz	:						
143608			11/16/2015		64		\$0.00
Medium	Work In Progress		11/16/2015 7:39:41 AM				
Flores, Pet	te	Pete, can you please che constantly appears in the	ck out engine light icon that instrument panel.				
David Villa							
144084	Motor Vehicle		12/1/2015		49		\$0.00
Medium	Work In Progress	equip#0908	12/1/2015 9:55:39 AM				
Flores, Pet	te	please replace gator's br	oken tailgate straps				
Pete Flore	S						
143131			11/5/2015		75		\$0.00
Medium	Work In Progress	FEDERAL	11/5/2015 3:03:16 PM	I			
Flores, Per		Car shakes when driving speed is high.	long distances, when the				
143174	Motor Vehicle		11/6/2015		74		\$0.00
Medium	Work In Progress	vehicle#135	11/6/2015 8:08:25 AM				,
Flores, Pet	_		stem damage, and any required				
Pete Flore							
142372	Motor Vehicle		10/27/2015		84		\$0.00
Medium	Work In Progress		10/27/2015 9:10:35 AM				
Flores, Per		vehicle 47 driver's window door doesn't open from in	v wouldn't go up; passenger side.				
Maria Ruiz 144185			12/2/2015		48		\$0.00
Medium	Work In Progress	FEDERAL	12/2/2015 11:01:49 AM		-10		ψ0.00
Flores, Pet	-	The engine light comes of					
Noemi Du		The origine light confes o	11				
144718	Motor Vehicle		12/9/2015		41		\$0.00
Medium	Work In Progress	vehicle#131	12/9/2015 8:20:19 AM				,
Flores, Pet	-	please check cause of gr compartment					
Pete Flore	S	-					
1/10/2016	11·45·16 AM					Dogo 10	20 ( 1 =

1/19/2016 11:45:16 AM Page 100 of 153

WOID Priority Assigned 7 Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex						
144725	Motor Vehicle			12/9/2015		41		\$0.00
Medium	Work In Progress	vehicle#158		12/9/2015 9:17:19 AM				
Flores, Pet	te	please check co		starting. also check				
Pete Flore								
144374	Motor Vehicle			12/4/2015		46		\$0.00
Medium	Work In Progress	tilt trailer-0784		12/4/2015 12:38:19 PM				
Flores, Pet	te	please check c	ause of inoperative	tail lamps.				
Pete Flore	s							
144565	Motor Vehicle			12/7/2015		43		\$0.00
Medium	Work In Progress			12/7/2015 10:28:39 AM				
Flores, Pet	te	vehicle 163 (che Richard Yanez		ned on) reported by				
Maria Ruiz				40/7/0045		40		Φο οο
144568	Motor Vehicle			12/7/2015		43		\$0.00
Medium	Work In Progress			12/7/2015 10:30:14 AM				
Flores, Pet		vehicle 187; che reported by Cha	eck brakes and tire arlene Bonham	pressure sensor				
Maria Ruiz	!			40/44/0045		07		ФО 00
141738				10/14/2015		97		\$0.00
Medium	Work In Progress			10/14/2015 3:50:55 PM				
Flores, Pet	te	THE A/C IS NO	T FUNCTIONING					
Santos Ch	avez							
141741				10/14/2015		97		\$0.00
Medium	Work In Progress			10/14/2015 3:52:13 PM				
Flores, Pet	te	NEED STEP TO	O GET INTO THE T	RUCK				
Santos Ch								
140148	Motor Vehicle			9/17/2015		124		\$0.00
Medium	Work In Progress			9/17/2015 11:31:24 AM				
Flores, Pet	te	Tune and repai	r District Warehous	se van #11				
Enrique Br	riones							
138345	Motor Vehicle			8/19/2015		153		\$0.00
Medium	Work In Progress			8/19/2015 3:24:08 PM				
Flores, Pet	te	veh 29change	e ignition key cylind	der				
Pete Flore		3	, , ,					

1/19/2016 11:45:16 AM Page 101 of 153

Location:	Го Name	Area Number Reason Description	Created Date/Time Ad	ctual Comp Date Action Taken	Aged	Hours	
	Physical	Plant Complex					
138392	Motor Vehicle		8/20/2015		152		\$0.00
Medium	Work In Progress		8/20/2015 8:39:05 AM				
Flores, Pet	e	ac compressor doesn't work; make	s a lot of noise				
Pete Flores	S						
138059	Motor Vehicle		8/14/2015		158		\$0.00
Medium	Work In Progress	FEDERAL	8/14/2015 2:03:43 PM				
Flores, Pet	e	VEHICLE HAS A STRONG GASOLI	NE ODOR.				
Noemi Dui	ron						
145497			1/4/2016		15		\$0.00
Medium	Work In Progress		1/4/2016 12:38:42 AM				
Flores, Pet	e	Monthly - District Backhoe 0520 - F Refer to PMschedule details.	ull Service PM -				
Margret Vil	lalobos						
145498			1/4/2016		15		\$0.00
Medium	Work In Progress		1/4/2016 12:38:43 AM				
Flores, Pet	e	Monthly - PPD - UV-0516 PM Service schedule details.	e - Refer to PM				
Margret Vil							
143413	Motor Vehicle		11/10/2015		70		\$0.00
Medium	Work In Progress		11/10/2015 3:52:24 PM				
Ruiz, Maria	ı	vehicle 58 needs a new windshield					
Salvador G	Gonzalez						
145333			1/3/2016		16		\$0.00
Medium	Work In Progress		1/3/2016 12:43:39 AM				
Flores, Pet	e	Monthly - PPD-T-0525 PM (Excavate to PMs chedule details.	or) - by SWP - Refer				
Margret Vil	lalobos						
143920			11/20/2015		60		\$0.00
Medium	Work In Progress		11/20/2015 10:56:11				
Herrera, Ma	ario	Maria S. Office - Install blinds					
Alfredo Ho	lguin						
144354			12/4/2015		46		\$0.00
Medium	Work In Progress		12/4/2015 11:06:13 AM				
Miranda, D	anny	Patch walls in Julie's old office.					

1/19/2016 11:45:16 AM Page 102 of 153

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		Plant Complex					
146304	Main Warehouse	•	1/15/2016		4		\$0.00
Medium	Work In Progress		1/15/2016 3:06:34 PN	1			·
Carrasco,	_	Requesting storage bins for pluml new warehouse.	bing material to store in				
Danny Ca	ırrasco						
145420			1/3/2016		16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:58 AM	1			
Carrasco,	, Danny	Monthly - PPD - Fueling Station Me Refer to PMschedule details.	onthly Inspection -				
Margret Vi	illalobos						
146123			1/13/2016		6		\$0.00
Medium	Work In Progress		1/13/2016 7:20:42 AN	1			
Ronquillo	, Ruben	need to post at main entrance : Thi Surveillance	s Site is Under Video				
Richard C	Chavez						
146094			1/12/2016		7		\$0.00
Medium	Work In Progress		1/12/2016 3:48:33 PM	1			
Appelzolle	er, Fred	12JAN2016: 38831 - 38874: .5 check email: 6 - CMS 139553 WP: 1 - CHS 145780 WP: .5 - enter log					
Fred Appe	elzoller						
142124			10/21/2015		90		\$0.00
Medium	Work In Progress		10/21/2015 3:56:52 PM	I			
Ontiveros		10-21-15 17046.6 17060.9 .5 Enter Log LLES 7-133840-p .5 Enter Log 1 Total HR		10/21/15			
Joe Ontive	eros		40/40/0045		40		<b>ФО 00</b>
144789	We dele D		12/10/2015		40		\$0.00
Medium	Work In Progress		12/10/2015 7:46:12 AM	1			
Ontiveros	, Joe	Welding Shop - supply gas for two	heater units				
Albert Vall							<b>^</b> -
142138	Motor Vehicle		10/22/2015		89		\$0.00
Medium	Work In Progress		10/22/2015 8:49:29 AM	1			
Chavez, S		Install outlets as needed in the new (Please see Sal and Jimmy)	w welding shop.				
Albert Vall	lejo						
1/19/2016	6 11:45:16 AM					Page 10	03 of 153

WOID Priority Assigned	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requeste		<b>D</b>					
Location:	Physical	Plant Complex					
145321			1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:43:29 AM	l			
Herrera, N	<i>M</i> ario	Yearly - Physical Plant Backflow In PMschedule details.	nspection - Refer to				
Margret Vi	llalobos						
142608			10/30/2015		81		\$0.00
Medium	Work In Progress		10/30/2015 10:48:14				
Chavez, S		light pole in middle of parking lot we morning; light on pole close to stre morning. report from Jose R.					
Maria Rui			7/04/0045		470		
136405	Maintenance	Electrical Room	7/24/2015		179		\$0.00
Medium	Work In Progress		7/24/2015 7:52:42 AM				
Castillo, C	Carlos	Make material list for stock.					
Carlos Ca	astillo						
141935			10/19/2015		92		\$0.00
Medium	Work In Progress		10/19/2015 2:49:46 PM				
Marquez,	Gerardo	AS PER MR. CHAVEZ, ALL NORTI NEED TO BE REKEYED.	HERN KITCHENS				
Maritza Go	onzalez						
144787			12/10/2015		40		\$0.00
Medium	Work In Progress		12/10/2015 7:44:29 AM				
Solis, Lore	enzo	Welding Shop - Install two heaters					
Albert Vall	ejo						
144788			12/10/2015		40		\$0.00
Medium	Work In Progress		12/10/2015 7:45:06 AM	I			
Solis, Lore	enzo	Welding Shop - Install exhaust fan					
Albert Vall	ejo						
146121			1/12/2016		7		\$0.00
Medium	Work In Progress		1/12/2016 11:18:09 PM				
Marquez,	_	1/12/16 3167-3217 .5-CHECK E-MAIL/PREP MATRL.4 2-CH. H.S. 145697 C. 1-CH. H. S. 145969 WP. .5-LOG OUT.					

1/19/2016 11:45:16 AM Page 104 of 153

Gerardo Marquez

**Total** Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Deferred By Request Date Target Comp Date** Days Labor Area Until Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Priority Status Assigned To Description Action Taken** Requester Name Location: **Physical Plant Complex** 146144 Motor Vehicle 1/13/2016 6 \$0.00 Medium Work In Progress 1/13/2016 1:06:47 PM Shop and Gate key for Leonel Vega, Marquez, Gerardo Avg. Age of WO's 56 Count: 77 Work Orders **Total for Physical Plant Complex** 0 \$0.00

1/19/2016 11:45:16 AM Page 105 of 153

WOID Priority Assigned 1 Requester	Building Status o	Dates:7/1/2015 - 6/30/2016 Order By Location, 3 Area Deferred By Unit Area Number Reason Description	il Request Date Targ Created Date/Time Actu		Labor Hours		
Location:	Riverside	ES					
145604			1/5/2016	14		\$0.00	
Medium	Work In Progress		1/5/2016 7:40:23 AM				
Lara, Ralph	1	Need cylinders changed at North double of	door entrance.				
Mario Marti	nez						
145997			1/11/2016	8		\$0.00	
Medium	Work In Progress	Gym	1/11/2016 3:37:06 PM				
Lara, Ralph		Readjust clock to allow coaches to lock/unlock double doors in the gym next to coaches office. (Mr. Flavian)					
Norma Ma	rtinez		0/40/0045	100		<b>A</b> 0 0 0	
140231			9/18/2015	123		\$0.00	
Medium	Work In Progress		9/18/2015 2:33:41 PM				
Ambriz, Jose		Need Jose A. to check Library A/C unit where the state of	nich is still				
Mario Marti	nez		1/14/2016	5		\$0.00	
Medium	Work In Progress		1/14/2016 8:30:00 AM	3		ψ0.00	
	· ·	Need less A to travelle about foulty DTU					
Ambriz, Jos		Need Jose A. to trouble shoot faulty RTU	at gym.				
Mario Marti	nez		1/14/2016	5		\$0.00	
Medium	Work In Progress		1/14/2016 8:31:29 AM	3		ψ0.00	
	· ·	No ad Jacob A to to also also set facility DTI La					
Ambriz, Jos		Need Jose A. to to check out faulty RTU a	at serving area.				
Mario Marti 144582	nez		12/7/2015	43		\$0.00	
Medium	Work In Progress		12/7/2015 2:41:11 PM	-10		ψ0.00	
	-	No ed loco A to verile co evented monifold					
Ambriz, Jose		Need Jose A. to replace cracked manifold north wing.	ior boller at				
Mario Marti	nez						
141608			10/13/2015	98		\$0.00	
Medium	Work In Progress	•	10/13/2015 2:22:23 PM				
Castillo, Ca	arlos	Need Carlos C. to work on parking lot light	ts.				
Mario Marti	nez						
141609			10/13/2015	98		\$0.00	
Medium	Work In Progress		10/13/2015 2:24:23 PM				
Castillo, Carlos		Need Carlos C. to work on bad light poles at main entrance along palm trees.					
Mario Marti	nez						

1/19/2016 11:45:16 AM Page 106 of 153

Total

#### 952 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID Area Until **Request Date Target Comp Date Davs** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: Riverside ES 138122 8/17/2015 155 \$0.00 Medium Work In Progress 8/17/2015 11:37:03 AM Castillo, Carlos Need door bell installed at cafeteria for deliveries. Asp Albert, route to Cali. Mario Martinez 136101 Athletic Field 7/20/2015 183 \$0.00 Medium Work In Progress 7/20/2015 7:40:36 AM Castillo, Carlos need to run power for booster pump 240-single face-30 amps. Guadalupe Ontiveros 1/19/2016 0 \$0.00 146344 Medium 1/19/2016 9:02:24 AM Work In Progress Castillo, Carlos Need Carlos C. to replace bad lights in book room. Mario Martinez 1/3/2016 2/3/2016 \$0.00 145322 16 Medium Work In Progress 1/3/2016 12:43:29 AM Yearly - Riverside ES Backflow Inspection - Refer to PM Martinez, Mario schedule details. Margret Villalobos 12/15/2015 35 \$0.00 145031 Medium Work In Progress 12/15/2015 9:14:00 AM Villalobos, David 12/15/2015 Need David V. to assist with faulty kitchen hot water heater. Mario Martinez 145357 1/3/2016 1/11/2016 16 \$0.00 Medium Work In Progress 1/3/2016 12:44:00 AM Monthly - Riverside ES Roof Inpsection - Refer to PM Martinez, Mario schedule details. Margret Villalobos 1/10/2016 1/26/2016 \$0.00 145939 Medium Work In Progress 1/10/2016 12:27:59 AM Monthly - QRTLY BLDG INSP REPORT (RS) - Refer to Sonora, Miguel PMschedule details. Margret Villalobos

1/19/2016 11:45:16 AM Page 107 of 153

WOID Priority Assigned <sup>-</sup> Requester		Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Riverside	ES						
146152				1/13/2016		6		\$0.00
Medium	Work In Progress	Computer Labs	<b>;</b>	1/13/2016 2:53:58 PM	1			
Marquez, Gerardo			ler to be able to open eys. (Mrs. Navarro)	computer lab doors				
Norma Ma	rtinez		, , ,					
142151				10/22/2015		89		\$0.00
Medium	Work In Progress			10/22/2015 11:02:29	)			
Lara, Ralph		Need Rafa L. to re key locks for water cabinet and gates. And to have two padlocks.						
Mario Mart	inez							
146295				1/15/2016		4		\$0.00
Medium	Work In Progress	Mr. Flavian		1/15/2016 2:27:49 PM	1			
Lara, Ralph		Re-key both doors in Mr. Flavian's office for testing purposes. (Mr. Flavian)						
Norma Ma	rtinez							
145998				1/11/2016		8		\$0.00
Medium	Work In Progress	Gym		1/11/2016 3:39:45 PM	1			
Lara, Ralpl	h	locking doors w	r and lock are incom vith a chain and a loc ches office. (Mr. Flavi	k. Doors are located				
Norma Ma	rtinez							
146005				1/11/2016		8		\$0.00
Medium	Work In Progress	Gym		1/11/2016 3:44:51 PM	1			
Lara, Ralph		Double doors to through the ins	o the gym: panic bar r ide. (Mr. Flavian)	needs to be installed				
Norma Ma	rtinez							
145993				1/11/2016		8		\$0.00
Medium	Work In Progress			1/11/2016 2:37:31 PM	1			
Lara, Ralph			oor - Right door need door. (Mr. Flavian)	s new cylinder;				
Norma Ma	rtinez							
143287				11/9/2015		71		\$0.00
Medium	Work In Progress			11/9/2015 8:03:52 AM	1			
Gonzalez, Salvador			al to cut and reverse r opposite direction.	metal benches so				
Mario Mart	inez							

1/19/2016 11:45:16 AM Page 108 of 153

WOID	Building	•	Target Comp Date	Days	Labor Hours	Costs
Priority	Status	Area Number Reason Created Date/Time	•	Aged	nours	
Assigned		Description	Action Taken			
Requeste						
Location:	Riverside	ES				
145487		1/3/2016	1/9/2016	16		\$0.00
Medium	Work In Progress	1/3/2016 12:46:04 AM	1			
Martinez, I	Vlario	Monthly - Riverside ES Monthly FE Inpsection - Refer to PMschedule details.				
Margret Vi	llalobos					
142708		11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress	11/1/2015 12:54:11 AM	1			
Orozco, Da	aniel	Monthly - Riverside ES Range Hood Cleaning - Refer to PMschedule details.				
Margret Vi	llalobos					
145956		1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress	1/10/2016 12:28:12 AM	1			
Martinez, I	Mario	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.				
Margret Vi	llalobos					
144933		12/13/2015	12/29/2015	37		\$0.00
Medium	Work In Progress	12/13/2015 12:30:22				
Martinez, N	Vlario	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.				
Margret Vi	llalobos					
142944		11/3/2015		77		\$0.00
Medium	Work In Progress	11/3/2015 8:06:35 AM	1			
Martinez, I	Mario	Need to remove banners from gym ceiling and need to clean metal sidings for up coming November TV presentation.				
Mario Mar	tinez					
145857		1/8/2016		11		\$0.00
Medium	Work In Progress	Office 1/8/2016 9:05:54 AM	1			
Martinez, I	Vlario	Replace light bulbs in secretary office and office hall. (Mrs. Martinez)				
Norma Ma	artinez					
145640		1/5/2016		14		\$0.00
Medium	Work In Progress	1/5/2016 3:29:46 PM	1			
Martinez, I	Vlario	Need to begin phase 2 of restroom renovations at North wing.				
Mario Mar	tinez					

1/19/2016 11:45:16 AM Page 109 of 153

WOID Priority Assigned 7 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Stat Area Deferred By Until Area Number Reason C Description	Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	ES					
145452			1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress	1/3	3/2016 12:45:29 AM	1			
Martinez, M	<i>M</i> ario	Monthly - Riverside ES Emer. Light Test: Mor Refer to PMschedule details.	nthly -				
Margret Vil	lalobos						
145453			1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress	1/3	3/2016 12:45:30 AM	1			
Martinez, N	<i>M</i> ario	Monthly - Riverside ES Exit Sign Insp: Month PMschedule details.	ly - Refer to				
Margret Vil	lalobos						
145503			1/4/2016		15		\$0.00
Medium	Work In Progress	1	/4/2016 8:04:15 AM	1			
Gonzalez,	Salvador	Need to repair damaged canopy poles at Kine playground.	derwing				
Mario Mart	inez						
142531			10/29/2015		82		\$0.00
Medium	Work In Progress	10/2	29/2015 8:00:00 AM	1			
Gonzalez,	Salvador	Need Sal to fabricate new ramps and stairs for science portable.	ornew				
Mario Mart	inez						
145798			1/7/2016		12		\$0.00
Medium	Work In Progress	1	/7/2016 3:23:12 PN	Л			
Moncayo, F	Fernando	AS PER ADELES MONITORING REPORT 1. DISHWASHER IS NOT WORKING. SNP MAN SANTA N.589.2550.					
Maritza Go	nzalez						
145799			1/7/2016		12		\$0.00
Medium	Work In Progress	1	/7/2016 3:24:58 PN	Л			
Moncayo, F	Fernando	AS PER ADELES MONITORING REPORT 1. WALK IN STILL ACCUMILATING ICE. SNP M SANTA N.589.2550.	-				
Maritza Go	nzalez						
145800			1/7/2016		12		\$0.00
Medium	Work In Progress	1	/7/2016 3:26:56 PN	Л			
Moncayo, F	Fernando	AS PER ADELES MONITORING REPORT 1. PANEL CAME OFF CAFETERIA WALL. SNP MANAGER SANTA N.589.2550.	7.16-				
Maritza Go	nzalez						

1/19/2016 11:45:16 AM Page 110 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Created Date/Time Actual Comp Date Status Area Number Reason **Priority Description Action Taken Assigned To** Requester Name Location: Riverside ES 145801 1/7/2016 12 \$0.00 Work In Progress Medium 1/7/2016 3:27:40 PM AS PER ADELES MONITORING REPORT 1.7.16-Moncayo, Fernando BLACK STRIP OFF WALK IN FLOOR CAME OFF. SNP MANAGER SANTA N.589.2550. Maritza Gonzalez 71 11/9/2015 \$0.00 143289 Medium Work In Progress 11/9/2015 8:15:00 AM Moncayo, Fernando ICE IS BUILDING UP IN FREEZER ONCE AGAIN. SNP MANAGER SANTA NAVA 589.2550. Maritza Gonzalez 11/22/2015 142730 11/1/2015 79 \$0.00 Medium Work In Progress 11/1/2015 12:54:25 AM Orozco, Daniel Monthly - Riverside ES Fire Suppression Insp. - Refer to PMschedule details. Margret Villalobos Count: 39 Work Orders Avg. Age of WO's 40 Total for Riverside ES 0 \$0.00

1/19/2016 11:45:16 AM Page 111 of 153

Total

## 952 - Work Orders In Progress (Fiscal Year)

			3/30/2016 Order By Loc				_		Costs
WOID	Building	Area	Deferred By	Until		Target Comp Date	Days Aged	Labor Hours	
Priority	Status	Area Number	Reason	Crea	ted Date/Time	Actual Comp Date	Ageu	i loui 3	
Assigned <sup>·</sup> Requester		Description				Action Taken			
•									
Location:	RTC - Alli	ance							
141364		Portables			10/9/2015		102		\$0.00
Medium	Work In Progress			10/9/2	015 1:39:23 PN	1			
Gonzalez,	Salvador		donated by the Peak lace in the back by th						
Gloria Del	gado								
144375		Portables			12/4/2015		46		\$0.00
Medium	Work In Progress			12/4/2	015 1:03:29 PN	1			
Moncayo,	Fernando	secure nails in	e an paint plank on off place 2-6450 prior coming.'						
Gloria Del	gado								
143458		Classroom			11/12/2015		68		\$0.00
Medium	Work In Progress			11/12/2	015 9:13:35 AM	1			
Moncayo,	Fernando	Some are flicke	e light bulbs in Ms. HI ering and some are o . We need to unlock th	ut. Please ca	II				
Gloria Del	gado								
140563		Classroom			9/24/2015		117		\$0.00
Medium	Work In Progress			9/24/20	15 11:44:03 AM	1			
Moncayo,	Fernando		is not working throwir to cancel afternoon c		ase				
Gloria Del	gado								
141681		Classroom			10/14/2015		97		\$0.00
Medium	Work In Progress	Ms. Hirsch		10/1	4/2015 11:27:51				
Moncayo,	Fernando	tried to reset a been 30 min. a	ass air conditioner ha nd turn back but has nd has not turned on. P Student in class are	not worked. Please send	lt has d				
Gloria Del	gado								
143605					11/16/2015		64		\$0.00
Medium	Work In Progress			11/16/2	015 7:02:31 AM	1			
Vallejo, All	pert	Remove VCTfl	oors to replace with li	noleum.					
Albert Valle	ejo								
Count: 6 W	ork Orders	A	vg. Age of WO's 82	2		Total for RTC - Alli	ance	0	\$0.00

1/19/2016 11:45:16 AM Page 112 of 153

0

\$0.00

**Total for San Miguel ES** 

#### 952 - Work Orders In Progress (Fiscal Year)

**Total** Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Created Date/Time Actual Comp Date **Priority Status** Area Number Reason **Assigned To Description Action Taken** Requester Name Location: San Miguel ES 145324 1/3/2016 2/3/2016 16 \$0.00 Medium Work In Progress 1/3/2016 12:43:31 AM Yearly - San Miguel ES Backflow Inspection - Refer to Ramirez, Joe PMschedule details. Margret Villalobos Count: 1 Work Orders

Avg. Age of WO's 16

1/19/2016 11:45:16 AM Page 113 of 153

WOID Priority Assigned 1 Requester		Area Number Description	Deferred By		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa ES						
145328				1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:43:34 AM	2/6/2010	.0		ψ0.00
Ambriz, Jua	_	Yearly - Santa <sup>-</sup> PMschedule de		w Inspection - Refer to				
Margret Vil	lalobos							
140070	Main Building	Parking Lot		9/16/2015		125		\$0.00
Medium	Work In Progress	Exterior lighting	I	9/16/2015 12:03:20 PM				
Castillo, Ca	arlos	Need to replace	e some exterior ligh	nting				
Juan Ambr	iz							
146196	Main Building	Office		1/14/2016		5		\$0.00
Medium	Work In Progress			1/14/2016 7:49:58 AM				
Ambriz, Jos	se	Need to check to working.	neating unit in adm	inistration office not				
Juan Ambr	iz							
146042	Main Building	Exterior		1/12/2016		7		\$0.00
Medium	Work In Progress	outside wall of		1/12/2016 8:43:11 AM				
Castillo, Ca	arlos	Need to replace	elights					
Juan Ambr	iz							
146210	Main Building	Office		1/14/2016		5		\$0.00
Medium	Work In Progress			1/14/2016 10:15:03 AM				
Lara, Ralph	า	Masterkeynee you.	ded for custodian s	ubstitutes. Thank				
Rita Mende								
145653	Main Building	Classroom		1/5/2016		14		\$0.00
Medium	Work In Progress	room 305		1/5/2016 3:45:00 PM				
Marquez, G	Gerardo	We need anoth Thank you.	er key for IA for roo	om 305. Key#1S17.				
Rita Mende	ez			40/00/0045				
142139				10/22/2015		89		\$0.00
Medium	Work In Progress			10/22/2015 8:53:23 AM				
Ambriz, Ju	an	Need to replace	wheels on trash o	eart				
Juan Ambr	iz							
144079				12/1/2015		49		\$0.00
Medium	Work In Progress			12/1/2015 8:13:13 AM				
Ambriz, Jua	an	Need to replace hallway	e batterypack for fir	e alarm panel in 300				

1/19/2016 11:45:17 AM Page 114 of 153

WOID Priority Assigned	Building Status To	Area Area Number Description	Deferred By Reason		=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester		-							
Location:	Santa Te	resa ES							
145863					1/8/2016		11		\$0.00
Medium	Work In Progress			1/8/20	016 9:24:42 AN	1			
Ambriz, Ju	an	Need to replace	e tools						
Juan Amb	riz								
137878	Main Building	Cafeteria			8/12/2015		160		\$0.00
Medium	Work In Progress			8/12/20	015 3:49:58 PN	Л			
Ambriz, Ju	an	Need to order 2	2-6X4 banners			Denied			
Juan Amb	riz								
145984	Main Building	Restroom			1/11/2016		8		\$0.00
Medium	Work In Progress	Kitchen		1/11/20	16 11:03:38 AN	1			
Ambriz, Ju	an	Need to replace	e toilet bowl handle						
Juan Amb	riz								
141685	Main Building	Classroom			10/14/2015		97		\$0.00
Medium	Work In Progress	whole building		10/14/20	015 1:10:55 PM	1			
Ambriz, Ju	an	Need to replace	e filters in all cooling	units					
Juan Amb	riz								
140238	Main Building	Classroom			9/18/2015		123		\$0.00
Medium	Work In Progress	Room 101		9/18/20	015 3:01:26 PN	Л			
Lara, Ralp	h		keys for room 101. one is a backup key						
Rita Mend	ez								
145931					1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/20	16 12:27:53 AN	Л			
Rodriguez	z, Ivan	Monthly - QRTL to PMschedule	Y BLDG INSP REP details.	ORT (STE) - R	efer				
Margret Vil	llalobos								
142709					11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress			11/1/20	15 12:54:11 AN	1			
Orozco, Da	aniel	Monthly-Santa Refer to PMsch	Teresa ES Range H nedule details.	Hood Cleaning	j -				
Margret Vil	llalobos								

1/19/2016 11:45:17 AM Page 115 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Davs** Labor Area **Deferred By** Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Action Taken Assigned To** Description Requester Name Santa Teresa ES Location: 146043 Classroom 1/12/2016 \$0.00 Medium Work In Progress azul hall 1/12/2016 8:43:32 AM Gonzales, Camilo There is a Rifton Chair and standing tray at STE in the work room in the Azul hall that needs to be taken to the physical therapy storage room in Anthony (the Alamo). Please have technician call the office at 575-882-6221 when they are going to deliver so that we can have someone open the storage room. Thank you. Susie Ramos Lara 145157 Classroom 12/16/2015 34 \$0.00 Main Building Medium Work In Progress Room #103 12/16/2015 3:40:01 PM Gonzales, Camilo Need a Kidneytable for room #103 Juan Ambriz Custodial 1/14/2016 5 \$0.00 146220 Main Building Medium Work In Progress 1/14/2016 11:48:20 AM WE NEED PROPANE GAS FOR THE BUFFER Carbajal, Jimmy MACHINE., THANKS. Luis Solis 146221 Custodial Main Building 1/14/2016 \$0.00 Medium Work In Progress 1/14/2016 11:52:33 AM WE NEED (3) ROYAL BELTS, (2) ROYAL BRUSH Carbajal, Jimmy Luis Solis 10/12/2015 141504 \$0.00 Medium Work In Progress 10/12/2015 2:01:47 PM AS PER ADELE'S MONITORING REPORT 10.12.15 Orozco, Daniel FLOOR IN WALK IN IS LIFTING. SNP MANAGER MARINA R. 589.3439 Maritza Gonzalez 7/21/2015 182 \$0.00 136192 7/21/2015 11:28:26 AM Medium Work In Progress Gonzalez, Salvador Attach ramps to portables. Albert Vallejo 1/14/2016 \$0.00 146225 Medium Work In Progress 1/14/2016 2:40:30 PM AS PER ENVIRONMENT FOOD ESTABLISHMENT Moncayo, Fernando INSPECTION ON 1.14.16, CALCIFICATION BUILDUP ON HAND SINK FAUCETS. SNP MANAGER MARINA R.589.3439 Maritza Gonzalez

1/19/2016 11:45:17 AM Page 116 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Area Until **Days** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: Santa Teresa ES 146226 1/14/2016 5 \$0.00 Medium Work In Progress 1/14/2016 2:42:32 PM AS PER ENVIRONMENT FOOD ESTABLISHMENT Moncayo, Fernando INSPECTION ON 1.14.16, NO EQUIPMENT THERMOMETERS OBSERVABLE IN STANDING WARMERS AND COOLER, ONE IN COOLER IS MISREADING. SNP MANAGER MARINA R. 589.3439 Maritza Gonzalez 145864 Main Building Exterior 1/8/2016 11 \$0.00 Medium Work In Progress Playgrounds 1/8/2016 9:26:59 AM Ambriz, Juan Need to replace swings Juan Ambriz 1/26/2016 145954 1/10/2016 9 \$0.00 Medium Work In Progress 1/10/2016 12:28:10 AM Monthly - Santa Teresa ES Playground Insp - Refer to Ambriz, Juan PMschedule details. Margret Villalobos 11/1/2015 11/22/2015 \$0.00 142732 Medium Work In Progress 11/1/2015 12:54:27 AM Orozco, Daniel Monthly-Santa Teresa ES Fire Suppression Insp. -Refer to PMschedule details. Margret Villalobos Total for Santa Teresa ES Count: 26 Work Orders Avg. Age of WO's 48 \$0.00

1/19/2016 11:45:17 AM Page 117 of 153

WOID	Building	Area	Deferred By	<del>-</del>	Target Comp Date	Days	Labor	
Priority	Status -	Area Number	Reason	Created Date/Time	-	Aged	Hours	
Assigned <sup>*</sup>		Description			Action Taken			
Requester								
Location:	Santa Te	resa HS						
142733				11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress			11/1/2015 12:54:27 AV	1			
Orozco, Da	niel	Monthly-Santa Refer to PMsch		uppression Insp				
Margret Vil	lalobos							
145363				1/3/2016	1/24/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:44:05 AM	1			
Vallejo, Alb	pert	Monthly - Santa to PMschedule		Sprinkler Insp Refer				
Margret Vil	lalobos							
145714				1/6/2016		13		\$0.00
Medium	Work In Progress	300		1/6/2016 2:16:17 PM	1			
Marquez, (	Serardo		ct to install work sta ill be removed. See	ations at film lab area e Albert for further				
Albert Valle	ejo							
145877				1/8/2016		11		\$0.00
Medium	Work In Progress			1/8/2016 3:10:36 PM	1			
Ronquillo,	Ruben	1/8/16 Requesting to i	install two new wir	ndows for room 309.				
David Diaz	2							
142154				10/22/2015		89		\$0.00
Medium	Work In Progress			10/22/2015 11:20:31				
Orozco, Da	niel	need to add ligl	hting to walk in refr	igerator				
Daniel Ord	OZCO							
145830				1/7/2016		12		\$0.00
Medium	Work In Progress			1/7/2016 3:55:49 PM	1			
Gonzalez,	Salvador	Install window	guards on 700-702	2				
Albert Valle			-					
146310	- 1 -	Athletic Field		1/15/2016		4		\$0.00
	Work In Progress			1/15/2016 3:40:10 PM	1			
Medium								
Medium Gonzalez,	Salvador	One old batting		third base dugout				

1/19/2016 11:45:17 AM Page 118 of 153

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS						
141547	GYM (2009)	Athletic Field		10/12/2015		99		\$0.00
Medium	Work In Progress	Baseball		10/12/2015 3:46:32 PM	1			
Gonzalez,	Salvador		g caged to be remove ds. Requesting two fr					
Lorraine D	ominguez							
141374				10/9/2015		102		\$0.00
Medium	Work In Progress			10/9/2015 2:17:00 PM	Л			
Orozco, Da	niel		R PANELS ARE RIS MANAGER OLGA B.					
Maritza Go				2//22/-				
137214	Library	Library		8/4/2015		168		\$0.00
Medium	Work In Progress	library		8/4/2015 2:28:04 PM	Л			
Lara, Ralp	า	Emergencydo	ors not functioning					
Lorraine D	ominguez							
136357	Main Building	Restroom		7/23/2015		180		\$0.00
Medium	Work In Progress	300 hallway		7/23/2015 2:41:30 PM	Л			
Lara, Ralp	n		s need replacing, doo yare in bad shape	or is missing on one				
Lorraine D	ominguez							
141349	Locker Room	Hallway/Corrid	or	10/9/2015		102		\$0.00
Medium	Work In Progress			10/9/2015 8:50:43 AN	1			
Lara, Ralp	า	lose it and look	etic Door Holder mo s damaged. It needs re-attached to the wa	to be replaced if				
Alfredo Ho								
135501	Library	Hallway/Corrid	or	7/6/2015		197		\$0.00
Medium	Work In Progress	200 Hall Stude	nt	7/6/2015 10:50:05 PM	Л			
Lara, Ralp	า	Please replace partitions due		itions with new black				
Nicholas V	Vohlgemuth							
145711				1/6/2016		13		\$0.00
Medium	Work In Progress			1/6/2016 2:06:46 PM	Л			
Marquez, Gerardo		Door should be	6' door between roo situated at the south urther instruction.	ms 700 and 702. n end of dividing wall.				

1/19/2016 11:45:17 AM Page 119 of 153

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	i/30/2016 Order By Loca <b>Deferred By</b> <b>Reason</b>	Until	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa HS							
146298	Main Building	Office			1/15/2016		4		\$0.00
Medium	Work In Progress	MARYLOU		1/15/2	016 2:43:16 PM	1			
Gonzales,	Camilo	PLEASE DELI'	VER THE FOLLOWIN	G ITEMS TO	:				
		PO #15160282	26 - 1BOX (UNIFORM	(S) - STHS C	HEER				
Terry Alvar	ado								
146299	Main Building	Office			1/15/2016		4		\$0.00
Medium	Work In Progress	MARYLOU		1/15/2	016 2:44:20 PM	1			
Gonzales,	Camilo	PLEASE DELI	VER THE FOLLOWIN	G ITEMS TO	:				
		PO#1516004	92 - 1 BOX (BAT) - ST	THS SOFTBA	<b>ALL</b>				
Terry Alvar	ado								
146300	Main Building	Office			1/15/2016		4		\$0.00
Medium	Work In Progress	MARYLOU		1/15/2	016 2:45:57 PN	1			
Gonzales,	Camilo	PLEASE DELI MARYLOU	VER THE FOLLOWIN	G ITEMS TO	:				
			E ORDER - 2 SETS ( OR SOFTBALL AND		RS				
Terry Alvar	ado								
142710					11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress			11/1/20	15 12:54:12 AM	1			
Orozco, Da		Monthly-Santa Refer to PMscl	a Teresa HS Range H nedule details.	ood Cleanin	g -				
Margret Vi	llalobos				4 /0 /0040	4/0/0040	40		<u>Фо</u> 00
145489				. /2 /2 2	1/3/2016		16		\$0.00
Medium	Work In Progress				16 12:46:06 AM	1			
Hernande		Monthly - Santa Refer to PMscl	a Teresa HS Monthly nedule details.	FE Inspection	on -				
Margret Vi		Classes			7/40/0045		100		фо oo
135788	Gymnasium	Classroom		= // = /-	7/13/2015		190		\$0.00
Medium	Work In Progress	weightroom		7/13/2	015 2:34:55 PN	1			
Estrada, J	esus	floor in weight i	oom is lifting						
Lorraine D	Oominguez								
	•								

1/19/2016 11:45:17 AM Page 120 of 153

Selected Dar WOID Priority Assigned I Requester		Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS						
144361	Main Building	Classroom		12/4/2015		46		\$0.00
Medium	Work In Progress	nurses office		12/4/2015 11:13:17 AM	I			
Lucero, Arr	nold	Waxand clean	floors					
Lorraine D	ominguez							
144363	Cafeteria (2005)	Cafeteria		12/4/2015		46		\$0.00
Medium	Work In Progress	Cafeteria		12/4/2015 11:15:15 AM	I			
Lucero, Arr	nold	Clean buff, and	d wax floor in cafete	ria				
Lorraine D	ominguez							
141435				10/11/2015	10/27/2015	100		\$0.00
Medium	Work In Progress			10/11/2015 12:28:46				
Lucero, Arr	nold	Monthly - QRTL to PMschedule	Y BLDG INSP REF details.	ORT (STH) - Refer				
Jesus Estr	ada							
145922				1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/2016 12:27:46 AM	l			
Lucero, Arr		Monthly - QRTL to PMschedule		PORT (STH) - Refer				
Margret Vil	lalobos			1/6/2016		12		\$0.00
145710	Madala Das susses					13		\$0.00
Medium	Work In Progress			1/6/2016 2:01:27 PM	I			
Ontiveros,	Guadalupe		sh xeris caping and valk between portab					
Albert Valle	<u>•</u>							
144172	Main Building	Classroom		12/2/2015		48		\$0.00
Medium	Work In Progress	215		12/2/2015 9:16:30 AM				
Lara, Ralpł		keyfor room 21 see Mrs. Valde		was created. Please				
Lorraine D								
144362	Main Building	Classroom		12/4/2015		46		\$0.00
Medium	Work In Progress	nurses office		12/4/2015 11:14:14 AM				
Lara, Ralph	า	change door kr	nob on door					
	ominguez							
143379	Main Building	Classroom		11/10/2015		70		\$0.00
Medium	Work In Progress	215		11/10/2015 10:55:05				
Lara, Ralph		Door needs to l Soriano	pe moved to room 2	15, please see Mrs.				
Lorraine D	ominguez							

WOID Priority Assigned <sup>-</sup> Requester		Area Number Description	Deferred By		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS						
145689	Main Building	Classroom		1/6/2016		13		\$0.00
Medium	Work In Progress	707		1/6/2016 8:19:46 AM				
Lara, Ralpl	h		s rekeyed and no ex extra keys need to b	tra keys were created e done for school				
Lorraine D	ominguez							
146229				1/14/2016		5		\$0.00
Medium	Work In Progress			1/14/2016 3:10:44 PM				
Lara, Ralpl	h	1/14/16 Need to make ( check that they	4) keys to the Culina open.	aryroom.Please				
David Diaz								
145914	Cafeteria (2005)	Mechanical		1/8/2016		11		\$0.00
Medium	Work In Progress	sound room		1/8/2016 4:04:53 PM				
Lara, Ralpl		lock in sliding v to be taken out		uck in the core needs				
Lorraine D	Gymnasium	Storage		12/1/2015		49		\$0.00
Medium	•	basketball and		12/1/2015 3:31:46 PM		49		φυ.υυ
	Work In Progress							
Lara, Ralpl		Keys are neede	ed for basketball and	tennis storage				
Lorraine D	GYM (2009)			11/12/2015		0		\$0.00
143494	, ,				44/40/0045	U		φυ.υυ
Medium	Work In Progress			11/12/2015 3:44:07 PM	11/12/2015			
Lara, Ralpl			TO BE AJUSTED A LL DOORS AT GYM					
Ralph Lara	<u>a</u>	Athletic Field		12/11/2015		39		\$0.00
144910	Mork In Drogram	Auneuc Field		12/11/2015 3:54:51 PM		39		φυ.υυ
Medium Ontiveros,	Work In Progress Guadalupe	need fence put	up around third bas	e softball dugout				
		To be done by	ecycled chain link a Grounds Dept.	na poies.				
Rick Llane	zZ	,						
145347				1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:43:51 AM				
Diaz, David	d	Monthly - Santa	a Teresa HS Roof In	spection - Refer to				

1/19/2016 11:45:17 AM Page 122 of 153

WOID Priority Assigned T Requester		Area Deferr Area Number Reaso Description	ed By Until Request I	Date Target Comp Date ime Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS					
136482			7/27/2	2015	176		\$0.00
Medium	Work In Progress		7/27/2015 7:56:1	6 AM			
Flores, Pet	Э	companytruck (141). We pretty bad, also if you do	ou can do an oil change on fas checking oil and it looks can check the turn signals they s located at STHS Thanks				
David Diaz							
143846			11/19/2	2015	61		\$0.00
Medium	Work In Progress	Nurses Office	11/19/2015 1:31:0	3 PM			
Miranda, D	·		lurses Office at STHS to cover ater (see David Villalobos for				
Albert Valle	<u>-                                      </u>	Draga in a Dagas	40/0/	2045	40		<u>ФО 00</u>
144169	Locker Room	Dressing Room	12/2/2		48		\$0.00
Medium	Work In Progress		12/2/2015 8:19:3	5 AM			
Miranda, D	-	The wall directly behind needs to be replaced.	the urinal is rotted out and				
David Villal							•
144359	Main Building	Classroom	12/4/2		46		\$0.00
Medium	Work In Progress	nurses office	12/4/2015 11:11:1	2 AM			
Miranda, D	anny	Cover tubing in restroom connected and sink.	m. New toilet needs to be				
Lorraine Do	ominguez		106	20.40			Φο οο
145399			1/3/2		16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:3	8 AM			
Hernandez		Monthly - Santa Teresa Refer to PMschedule d	HS -Clothes Dryer (Monthly) - etails.				
Margret Vill			10/11	2015			Φο οο
144126	Main Building	Storage	12/1/2		49		\$0.00
Medium	Work In Progress	Equipment	12/1/2015 3:40:2	2 PM			
Hernandez	, Carlos		ures in storage areas soccer, oom all connected areas.				
Lorraine D	ominguez						
144356		Cafeteria	12/4/2		46		\$0.00
Medium	Work In Progress	CAFETERIA	12/4/2015 11:08:1	6 AM			
Hernandez	, Carlos		TS OF FLAGS IN CAFETERIA S HANGING IN VARSITY GYM.				

1/19/2016 11:45:17 AM Page 123 of 153

WOID	te Range for Request Building Status	Dates:7/1/2015 - 6 Area Area Number	Deferred By	Until R	=	Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Priority Assigned <sup>1</sup>		Description	Reason	Create	d Date/Time	Actual Comp Date  Action Taken	7.900		
Requester		Description				Action Taken			
Location:	Santa Te	resa HS							
144862	Main Building	Classroom			12/11/2015		39		\$0.00
Medium	Work In Progress	307		12/11/201	5 9:58:57 AM	1			
Hernandez	z, Carlos	If we can move	maps to a differer	nt location in the ro	om				
Lorraine D	ominguez								
144864	Main Building	Classroom			12/11/2015		39		\$0.00
Medium	Work In Progress	501		12/11/2	2015 10:00:39	1			
Hernandez	z, Carlos	Hole in wall nee	eds to be fixed						
Lorraine D	ominguez								
144734					12/9/2015		41		\$0.00
Medium	Work In Progress			12/9/2015	12:08:15 PM	I			
Diaz, David	t	Requesting to	order some tools						
		6VEE3 Dewa	ılt 18v Battery PK2 \$99 1						
		10J319 Scre	w Driver set 1	\$51.40					
		24WY33 cord	less screwdriver	\$126.25 1					
David Diaz	<u>!</u>								
139966					9/15/2015		126		\$0.00
Medium	Work In Progress			9/15/201	5 8:40:48 AM	1			
Vallejo, Alb	pert	Install new mai	rquee.						
Albert Valle	ejo								
145785					1/7/2016		12		\$0.00
Medium	Work In Progress			1/7/2016	5 11:20:44 AM	1			
Vallejo, Alb	pert	below the marc	quee between the	arquee to be placed poles. One sign w er "Tribe of 2015"					
Alfredo Ho	lguin								

1/19/2016 11:45:17 AM Page 124 of 153

WOID Priority Assigned <sup>1</sup> Requester		Area Number Reason Description	ler By Location By	Jntil Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS						
144733				12/9/2015		41		\$0.00
Medium	Work In Progress			12/9/2015 12:04:40 PM				
Hernande	z, Carlos	Requiting these tools:						
		muliti-screw driver granger	r 32477 ea\$24.00	-1				
		dewalt battery pack 6vee3	ea \$99.00 -1					
		utility cart fg452088bla -1	ea \$293.2	6				
		extension cord 100 ft 1ed5	7 ea \$127.50	0				
Carlos He	rnandez							
141057		Classroom		10/5/2015		106		\$0.00
Medium	Work In Progress	MR.		10/5/2015 1:03:46 PM	I			
Diaz, David	d	LAB C-4 NEEDS BOARD N	MOUNTED.					
Marylou Jii	menez							
145634	Main Building	Classroom		1/5/2016		14		\$0.00
Medium	Work In Progress	300		1/5/2016 3:02:42 PM	I			
Diaz, David	d	Please install white board under clock	in classroor	n on back wall				
	ominguez							
136365	Main Building	Classroom		7/23/2015		180		\$0.00
Medium	Work In Progress	410		7/23/2015 2:57:12 PM				
Diaz, David		Take down board and repla see Ms. Soriano	ace with bull	etin board please				
	ominguez  Main Building	Classroom		7/23/2015		25		\$0.00
136366	_				0/47/0045	20		φυ.υυ
Medium	Work In Progress	500		7/23/2015 2:57:44 PM	8/17/2015			
Diaz, David		Baseboard behind teacher	rdeskneed	s replacing				
	ominguez	01		40/40/00:=				<b>A A A A B</b>
141562	Vocational	Classroom		10/12/2015		99		\$0.00
Medium	Work In Progress	805		10/12/2015 3:53:51 PM				
Diaz, David	4	In need of changing light bu	ulbs					

1/19/2016 11:45:17 AM Page 125 of 153

WOID Priority Assigned Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS						
146068		Office		1/12/2016		7		\$0.00
Medium	Work In Progress	OFFICE		1/12/2016 2:55:00 PM	1			
Prospero,	Manuel	PLEASE ASSE STORAGE OF		DOLLY'S IN FRONT				
Marylou Ji	menez							
143604				11/15/2015		65		\$0.00
Medium	Work In Progress			11/15/2015 12:27:55				
Flores, Pe	te	Yearly - Santa <sup>-</sup> Refer to PMsch	Teresa HS - Mower nedule details.	0425 - Grounds -				
Margret Vil	llalobos							
146151				1/13/2016		6		\$0.00
Medium	Work In Progress			1/13/2016 2:53:44 PM	1			
Marquez, (		1/13/16 Requesting a k	sey lock door knob f	or J T P portable.				
David Diaz	<u>Z</u>			1/11/2016		8		\$0.00
Medium	Work In Progress			1/11/2016 10:33:06 AM	•	O		ψ0.00
Lara, Ralp	Work In Progress h	-	GER NEEDS KEYN LIAN LINE. SNP MA	IADE TO OPEN	l			
Maritza Go	nzalez							
140843				10/4/2015	11/4/2015	107		\$0.00
Medium	Work In Progress			10/4/2015 12:37:59 AM	1			
Diaz, Davi	d	Yearly - Santa to PMschedule		p Furn Yearly - Refer				
Margret Vil								
146003	Cafeteria (2005)	Exterior		1/11/2016		8		\$0.00
Medium	Work In Progress			1/11/2016 3:43:48 PM	1			
Castillo, C		Safetyissue as problem at nigh	per custodial dept nt.	lights went out ,dog				
Carlos Ca	stillo	_ ,		2/12/5		4.00		00.00
140232		Football Field		9/18/2015		123		\$0.00
Medium	Work In Progress			9/18/2015 2:44:34 PM	1			
Castillo, C	arlos	As per J.Mijare	z one footbalfield gf	ci is not working.				
Carlos Ca	stillo							

1/19/2016 11:45:17 AM Page 126 of 153

WOID	Building	Dates:7/1/2015 - 6/30/2016 Order By Location, State Area Deferred By Until	Request Date	<b>Target Comp Date</b>	Days	Labor	
Priority	Status		reated Date/Time	<b>Actual Comp Date</b>	Aged	Hours	
Assigned <sup>*</sup>		Description		Action Taken			
Requester	Name						
Location:	Santa Te	resa HS					
142566			10/29/2015		82		\$0.00
Medium	Work In Progress	10/2	9/2015 3:21:14 PM	1			
Ambriz, Jo	se	Trainers ice thickness sensor for ice maker is needs to be replaced. Trainer wants to know ton the ice maker water filters.					
Jaime Mija	arez						
144604			12/7/2015		43		\$0.00
Medium	Work In Progress	12/	/7/2015 3:47:52 PM	Л			
Ambriz, Jo	se	need to order parts to heaters in trainers room locker room	n and girls				
Carlos He	rnandez						
145185			12/16/2015		34		\$0.00
Medium	Work In Progress	12/1	6/2015 4:01:31 PM	1			
Ambriz, Jo	se	in the science wing room 512 is where our contech is located, the heater is not working. PLe check. It is really cold.					
		THANK YOU					
Cora Ram	irez						
144876			12/11/2015		39		\$0.00
Medium	Work In Progress	12/1	1/2015 1:35:49 PM	1			
Ambriz, Jo	se	12/11/15 Need to replace module to furnace in room 80	05				
David Diaz	<u>z</u>						
144950			12/14/2015		36		\$0.00
Medium	Work In Progress	1	2/14/2015 11:02:57	7			
Ambriz, Jo		12/14/15 Boiler 1 need to replace low pressure switch.					
David Diaz	<u>Z</u>		10/1/10045				
144951			12/14/2015		36		\$0.00
Medium	Work In Progress	1	2/14/2015 11:04:42	2			
Ambriz, Jo		12/14/15 Boiler 2 need to replace gas valve.					
David Diaz	Z		40/44/004		00		Φο οο
144952			12/14/2015		36		\$0.00
Medium	Work In Progress	1	2/14/2015 11:06:26	6			
Ambriz, Jo	se	12/14/15 B D F Boiler 1 no signal.					
David Diaz	7						

1/19/2016 11:45:17 AM Page 127 of 153

WOID Priority Assigned Requester		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa HS						
136351	Main Building	Restroom		7/23/2015		180		\$0.00
Medium	Work In Progress	by library		7/23/2015 2:35:07 PM	I			
Diaz, David	d	Ceiling needs	painting					
Lorraine D	ominguez							
136350	Main Building	Classroom		7/23/2015		180		\$0.00
Medium	Work In Progress	209		7/23/2015 2:34:10 PM	I			
Diaz, David	d	Please paint w	here tvstand was ren	noved.				
Lorraine D	ominguez							
144110	Main Building	Hallway/Corric	lor	12/1/2015		49		\$0.00
Medium	Work In Progress	outside locker		12/1/2015 3:09:51 PM	I			
Diaz, David	d	leading out to fo this. Also we p	d paint a stripe turquo potball field please so probably need to orde p the wall after work v n area.	ee Mrs. Soriano for er the vanilla bean				
	ominguez							
145712				1/6/2016		13		\$0.00
Medium	Work In Progress			1/6/2016 2:11:24 PM	I			
Castillo, C	arlos		sh circuits for new co ext to pump room)	mputer lab at room				
Albert Valle	ejo			. / 2 / 2				
145721				1/6/2016		13		\$0.00
Medium	Work In Progress			1/6/2016 3:30:29 PM	I			
Castillo, C	arlos	Please remove LED lay in fixtu	e dark room lights and res.	d replace with 2'x4'				
Albert Valle	·			40/0/0045		400		
141409	Main Building	Classroom		10/9/2015		102		\$0.00
Medium	Work In Progress	407, 500, 503		10/9/2015 3:56:03 PM				
Castillo, C		Need outlets in were installed	these classrooms a in classrooms.	s new smart boards				
	ominguez			4/40/0010				ФО ОО
146054				1/12/2016		7		\$0.00
Medium	Work In Progress			1/12/2016 12:06:39 PM				
Castillo, C	arlos	Run 20 amp-1	20v circuit for new ma	rquee.				
Carlos Ca	stillo							

1/19/2016 11:45:17 AM Page 128 of 153

WOID	Building Status	Area Deferred By Area Number Reason	Until Request Date  Created Date/Time	Target Comp Date	Days Aged	Labor Hours	
Priority Assigned T		Description	Created Date/Time	Action Taken	, .go u		
Requester		Description		Action Taken			
Location:	Santa Te	resa HS					
143655	Main Building	Gym	11/16/2015		64		\$0.00
Medium	Work In Progress	locker rooms	11/16/2015 3:40:06 PM				,
Villalobos,	-	shower head and handles need to lockerrooms					
Lorraine D	ominguez						
142007			10/20/2015		91		\$0.00
Medium	Work In Progress		10/20/2015 1:27:58 PM				
Villalobos,	David	Boys soccer locker room urinal nee	eds to be replaced.				
Jaime Mija	rez						
141730			10/14/2015		97		\$0.00
Medium	Work In Progress		10/14/2015 3:45:49 PM				
Villalobos,	David	Nurses restroom toilet is leaking w	ater from Tank.				
Jaime Mija	rez						
141581			10/13/2015		98		\$0.00
Medium	Work In Progress		10/13/2015 7:49:59 AM				
Villalobos,	David	need to replace missing shower had boys lockerooms	andles at girls and				
David Villal	obos						
145988			1/11/2016		8		\$0.00
Medium	Work In Progress		1/11/2016 12:22:05 PM				
Villalobos,	David	trouble resetting water heater in me	echanical room				
Carlos Her	nandez						
145713			1/6/2016		13		\$0.00
Medium	Work In Progress	300	1/6/2016 2:13:52 PM	1			
Villalobos,	David	Please remove film lab stainless swater and sewer connections.	teel sinks and cap				
Albert Valle	jo						
145389			1/3/2016	1/6/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:28 AM				
Hernandez	, Carlos	Monthly - Santa Teresa HS - Emer Refer to PMschedule details.	g. Eyewash (Mthly) -				
Margret Vill	alobos						
145326			1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:43:33 AM	l			
Hernandez	, Carlos	Yearly - Santa Teresa HS Backflow PMschedule details.	/ Inspection - Refer to				

1/19/2016 11:45:17 AM Page 129 of 153

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

**Total** Costs

Building WOID Area **Deferred By** Until **Request Date Target Comp Date** 

Days Labor Hours Aged Area Number Reason Created Date/Time Actual Comp Date

**Assigned To Description Action Taken** 

Requester Name

**Priority** 

Location: Santa Teresa HS

**Status** 

**Total for Santa Teresa HS** Count: 82 Work Orders Avg. Age of WO's 57 0 \$0.00

1/19/2016 11:45:17 AM Page 130 of 153

Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6 Area Area Number Description	/30/2016 Order By Loc <b>Deferred By</b> <b>Reason</b>		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS						
145529	South Building	Restroom		1/4/2016		15		\$0.00
Medium	Work In Progress			1/4/2016 10:31:49 AM				
Villalobos	, David	Flush valve in a doesn't work fir		om south upper level				
Ismael Ro	odriguez							
145696	North Building	Classroom		1/6/2016		13		\$0.00
Medium	Work In Progress	3 PORTILLO		1/6/2016 9:49:46 AM				
Villalobos	, David	KITCHEN SINK	( CLOGGED					
Laura Par	ra							
145327				1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress			1/3/2016 12:43:34 AM				
Prospero,	Manuel	Yearly - Santa PMschedule d		Inspection - Refer to				
Margret Vi	llalobos							
139067	North Building	Classroom		8/31/2015		141	1	\$25.00
Medium	Work In Progress	9 CORDOVA		8/31/2015 3:25:43 PM				
Prospero, Laura Par		LEAK IN CEILII	NG AGAINST THE W		9/1/15 - Manuel plea David V. Teacher sa			per
138771	North Building	Parking Lot		8/26/2015		146		\$0.00
Medium	Work In Progress	PARKING LOT		8/26/2015 11:12:25 AM				
	ŭ							
Castillo, C	arlos		IN THE PARKING L AY BE WORN OUT	OT DO NOT TURN				
Castillo, C				OT DO NOT TURN				
				OT DO NOT TURN 9/29/2015		112		\$0.00
Laura Par	ra	ON- BULBS MA				112		\$0.00
Laura Par 140749	ra North Building Work In Progress	ON- BULBS MA		9/29/2015 9/29/2015 1:57:53 PM		112		\$0.00
Laura Par 140749 Medium Castillo, C	na  North Building  Work In Progress  arlos	ON- BULBS MA	AY BE WORN OUT	9/29/2015 9/29/2015 1:57:53 PM		112		\$0.00
Laura Par 140749 Medium	na  North Building  Work In Progress  arlos	ON- BULBS MA	AY BE WORN OUT	9/29/2015 9/29/2015 1:57:53 PM		112		
Laura Par 140749 Medium Castillo, C Manuel Pr	na  North Building  Work In Progress  arlos	ON- BULBS M/ Parking Lot  9/29/15. EXPO	AY BE WORN OUT	9/29/2015 9/29/2015 1:57:53 PM RKING LOT.				
Laura Par 140749 Medium Castillo, C Manuel Pr 140751	North Building Work In Progress earlos cospero Work In Progress	Parking Lot  9/29/15. EXPO	SED WIRES BY PAR	9/29/2015 9/29/2015 1:57:53 PM RKING LOT. 9/29/2015 9/29/2015 2:29:11 PM				
Laura Par 140749 Medium Castillo, C Manuel Pr 140751 Medium	North Building Work In Progress carlos cospero Work In Progress carlos	Parking Lot  9/29/15. EXPO	SED WIRES BY PAR	9/29/2015 9/29/2015 1:57:53 PM RKING LOT. 9/29/2015 9/29/2015 2:29:11 PM				
Laura Par 140749 Medium Castillo, C Manuel Pr 140751 Medium Castillo, C	North Building Work In Progress carlos cospero Work In Progress carlos	Parking Lot  9/29/15. EXPO	SED WIRES BY PAR	9/29/2015 9/29/2015 1:57:53 PM RKING LOT. 9/29/2015 9/29/2015 2:29:11 PM				\$0.00
Laura Par 140749 Medium Castillo, C Manuel Pr 140751 Medium Castillo, C Carlos Ca	North Building Work In Progress carlos cospero Work In Progress carlos	Parking Lot  9/29/15. EXPO	SED WIRES BY PAR	9/29/2015 9/29/2015 1:57:53 PM RKING LOT. 9/29/2015 9/29/2015 2:29:11 PM en underground		112		\$0.00 \$0.00
Laura Par 140749 Medium Castillo, C Manuel Pr 140751 Medium Castillo, C Carlos Ca 141494	North Building Work In Progress Earlos Work In Progress Earlos Ea	Parking Lot  9/29/15. EXPO  Parking Lot  Identify and sec parking lot light  Office  SEE MR.  NEED LIGHTS	SED WIRES BY PAR	9/29/2015 9/29/2015 1:57:53 PM RKING LOT.  9/29/2015 9/29/2015 2:29:11 PM en underground  10/12/2015 10/12/2015 12:11:26 IDE ATHLETIC		112		\$0.00

1/19/2016 11:45:17 AM Page 131 of 153

Total

## 952 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request <b>Building</b>	Dates:7/1/2015 - 6 <b>Area</b>	6/30/2016 Order By Loca <b>Deferred By</b>	ation, Status <b>Until</b>	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		<del>-</del>	Actual Comp Date	Aged	Hours	
Assigned <sup>1</sup>		Description				Action Taken			
Requester	Name	-							
Location:	Santa Te	resa MS							
139063	Gym (1997)	Gym			8/31/2015		141		\$0.00
Medium	Work In Progress	GYM BACK		8/31/2	:015 3:20:53 PN	Л			
Castillo, C	arlos	-	R LIGHTING. REPLAC POSITIONED BEHIN		DLES				
Laura Parı									
146140	North Building	Portables			1/13/2016		6		\$0.00
Medium	Work In Progress			1/13/20	16 10:57:25 AN	1			
Castillo, C	arlos	Change the ba don't work Port	llast, replace with nev able #1.	vlightbulbs	still				
Ismael Ro	driguez								
145876	North Building	Office			1/8/2016		11		\$0.00
Medium	Work In Progress	COPY WORK		1/8/2	016 2:27:20 PN	Л			
Castillo, C	arlos	NEED ADDITIONS. PARRA	ONAL OUTLET IN CC	PY ROOM. S	SEE				
Laura Parı	ra e								
143316	South Building	Office			11/9/2015		71		\$0.00
Medium	Work In Progress	SOUTH OFFIC	E	11/9/2	:015 2:24:01 PN	Л			
Prospero,	Manuel		IM INSIDE AND OUTS OMS-BLACK PAINT	SIDE OF OFF	FICES				
Laura Pari	a								
140159	South Building	Office			9/17/2015		124		\$0.00
Medium	Work In Progress	SECURITY-MF	?	9/17/2	:015 1:10:33 PN	Л			
Prospero,	Manuel		O PARKING FIRE LAI IS "NO PARKING AT A ENTRANCE		N				
Laura Parı	a								
145296					12/31/2015		19		\$0.00
Medium	Work In Progress			12/3	1/2015 12:49:04	ļ			
Prospero,	Manuel	Yearly - Santa Refer to PMscl	Teresa MS H6(Roof I nedule details.	Furnace)(Ye	arly) -				
Margret Vil	lalobos								
140794					9/30/2015		111		\$0.00
Medium	Work In Progress			9/30/20	15 12:43:18 AN	1			
Prospero,	Manuel	Monthly - Santa Refer to PMscl	a Teresa MS A16 (Fa nedule details.	n Exh.)(Mont	hly) -				
Margret Vil	lalobos								

1/19/2016 11:45:17 AM Page 132 of 153

Priority   Status   Area Number   Reason   Created Date/Time   Actival Comp Date   Action Taken   Action Tak	Selected Da	ate Range for Request <b>Building</b>	Dates:7/1/2015 - 6/30/2016 Order <b>Area Deferred By</b>		Target Comp Date	Days	Labor	Total Costs
Passign   To   Pass   Passign   P			•	<del>,</del>	-	-	Hours	
	-	То			-			
10/4/2015   10/20/2015   107   \$0.	_		·					
Madium   Work in Progress   10/4/2015 12:38:07 AM	Location:	Santa Te	resa MS					
Monthly - Santa Teresa MS A1 (Wall Refr.E/H) (Semi) - Refer to PMschedule details.	140855			10/4/2015	10/20/2015	107		\$0.00
Refer to PMschedule details.   Refer to PMschedule details.	Medium	Work In Progress		10/4/2015 12:38:07 AV	1			
146077   South Building   Classroom   1/12/2016   7   \$0.	Prospero,	Manuel						
Medium         Work in Progress         1/12/2016 3:35:17 PM           Prospero, Manuel         1/12/16. HAWING PROBLEMS HEATER ROOM 31.           Manuel Prospero           138502         Restroom         8/21/2015 1:34:48 PM           Medium         Work in Progress         8/21/2015 1:34:48 PM           Lara, Ralph         Please acquire quote for urinal partitions 18' for boys restrooms.           Albert Vallejo         Vallejo           141508         10/12/2015 2:32:47 PM           Prospero, Manuel         CEILING TILES ON STORAGE AREA ARE STAINED FROM WATER LEAK. SNP MANAGER GESSICA M. 589.9836.           Maritza Gonzalez         10/12/2015 2:34:34 PM           Prospero, Manuel         AS PER ADEL'S MONITORING REPORT. DENTS ON WALK IN HALL AND BATHROOM WALLS.           Maritza Gonzalez         11/13/2015 3:39:42 PM           Prospero, Manuel         11/13/15 5:HR CHECK EMAIL. 4HRS WO 14/9902. 3HRS WO 14/2852. 5HR CHECK EMAIL. 4HRS WO 14/2852. 5HR ENTER LOG.           Manuel Prospero         Manuel Prospero         12/6/2015 12:40:18 AM         4         \$0.           Medium         Work in Progress         12/6/2015 12:40:18 AM         \$0.           Medium         Work in Progress         Monthly- Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMISchedule details.	Margret Vi	llalobos						
Prospero	146077	South Building	Classroom	1/12/2016		7		\$0.00
Manuel Prospero   Manuel Prospero   Restroom   8/21/2015   151   \$0.	Medium	Work In Progress		1/12/2016 3:35:17 PM	1			
138502   Restroom   8/21/2015   151   \$0.	Prospero,	Manuel		R ROOM31.				
Medium         Work In Progress         8/21/2015 1:34:48 PM           Lara, Ralph         Please acquire quote for urinal partitions 18 for boys restrooms.           Albert Vallejo         10/12/2015 :39:32:47 PM           141508         10/12/2015 2:32:47 PM           Prospero, Manuel         CEILING TILES ON STORAGE AREA ARE STAINED FROM WATER LEAK. SNP MANAGER GESSICA M. 589.9836.           Maritza Gonzalez         10/12/2015 2:34:34 PM           Prospero, Manuel         AS PER ADEL'S MONITORING REPORT. DENTS ON WALK IN HALL AND BATHROOM WALLS.           Maritza Gonzalez         11/13/2015 3:39:42 PM           Prospero, Manuel         4S PER ADEL'S MONITORING REPORT. DENTS ON WALK IN HALL AND BATHROOM WALLS.           Medium         Work In Progress         11/13/2015 3:39:42 PM           Prospero, Manuel         11/13/15. 5HR CHECK EMAIL. 4HRS WO 14/9902. 3HRS WO 14/9902. 3HRS WO 14/9902. 3HRS WO 14/9902. 3HRS WO 14/9902. 5HR ENTER LOG.         11/13/15 44           Medium         Work In Progress         12/6/2015 12:40:18 AM           Prospero, Manuel         Monthly - Santa Teresa MS - Clothes Dryer (Monthly) - Refer to PMschedule details.	Manuel Pr	rospero						
Please acquire quote for urinal partitions 18' for boys restrooms.	138502		Restroom	8/21/2015		151		\$0.00
Restrooms	Medium	Work In Progress		8/21/2015 1:34:48 PM	1			
10/12/2015   99   \$0.	Lara, Ralp	bh		al partitions 18' for boys				
Medium         Work In Progress         10/12/2015 2:32:47 PM           Prospero, Manuel         CEILING TILES ON STORAGE AREA ARE STAINED FROM WATER LEAK. SNP MANAGER GESSICA M. 589.9836.           Maritza Gonzalez           141509         10/12/2015 99 \$0.           Medium         Work In Progress           Prospero, Manuel         AS PER ADEL'S MONITORING REPORT. DENTS ON WALK IN HALL AND BATHROOM WALLS.           Maritza Gonzalez         11/13/2015 67 67 \$0.           Medium         Work In Progress         11/13/2015 3:39:42 PM           Prospero, Manuel         11/13/15. 5HR CHECK EMAIL. 4HRS WO 140902. 3HRS WO 142852. 5HR ENTER LOG.         11/13/15 3HR ENTER LOG.           Manuel Prospero         14/4502         12/6/2015 12:40:18 AM           Prospero, Manuel         Monthly - Santa Teresa MS - Clothes Dryer (Monthly) - Refer to PM schedule details.	Albert Vall	ejo						
Prospero, Manuel CEILING TILES ON STORAGE AREA ARE STAINED FROM WATER LEAK. SNP MANAGER GESSICA M. 589.9836.  Maritza Gonzalez  141509 10/12/2015 99 \$0.  Medium Work In Progress 10/12/2015 2:34:34 PM  Prospero, Manuel AS PER ADEL'S MONITORING REPORT. DENTS ON WALK IN HALL AND BATHROOM WALLS.  Maritza Gonzalez  143567 11/13/2015 67 \$0.  Medium Work In Progress 11/13/2015 3:39:42 PM  Prospero, Manuel 11/13/15.	141508			10/12/2015		99		\$0.00
### FROM WATER LEAK. SNP MANAGER GESSICA M. 589.9836.    Maritza Gonzalez	Medium	Work In Progress		10/12/2015 2:32:47 PM				
10/12/2015   99   \$0.	Prospero,	Manuel	FROM WATER LEAK. SNP M	_				
Medium         Work In Progress         10/12/2015 2:34:34 PM           Prospero, Manuel         AS PER ADEL'S MONITORING REPORT. DENTS ON WALK IN HALL AND BATHROOM WALLS.           Maritza Gonzalez         143567         11/13/2015         67         \$0.           Medium         Work In Progress         11/13/15 3:39:42 PM           Prospero, Manuel         11/13/15. 5HR CHECK EMAIL. 4HRS WO 140902. 3HRS WO 140902. 3HRS WO 142852. 5HR ENTER LOG.         11/13/15 44           Manuel Prospero         144502         12/6/2015         44         \$0.           Medium         Work In Progress         12/6/2015 12:40:18 AM           Prospero, Manuel         Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMschedule details.	Maritza Go	onzalez						
Prospero, Manuel AS PER ADEL'S MONITORING REPORT. DENTS ON WALK IN HALL AND BATHROOM WALLS.  Maritza Gonzalez  143567 11/13/2015 67 \$0.  Medium Work In Progress 11/13/15. 11/13/15. 5HR CHECK EMAIL. 4HRS WO 140902. 3HRS WO 142852. 5HR ENTER LOG.  Manuel Prospero  144502 12/6/2015 12:40:18 AM  Prospero, Manuel Monthly - Santa Teresa MS - Clothes Dryer (Monthly) - Refer to PMschedule details.	141509			10/12/2015		99		\$0.00
WALK IN HALL AND BATHROOM WALLS.         Maritza Gonzalez         143567       11/13/2015       67       \$0.         Medium       Work In Progress       11/13/2015 3:39:42 PM         Prospero, Manuel       11/13/15.       11/13/15         .5HR CHECK EMAIL.       4HRS WO 140902.         3HRS WO 142852.       .5HR ENTER LOG.         Manuel Prospero       12/6/2015       44       \$0.         Medium       Work In Progress       12/6/2015 12:40:18 AM         Prospero, Manuel       Monthly - Santa Teresa MS - Clothes Dryer (Monthly) - Refer to PMschedule details.	Medium	Work In Progress		10/12/2015 2:34:34 PM	I			
143567	Prospero,	Manuel						
Medium       Work In Progress       11/13/2015 3:39:42 PM         Prospero, Manuel       11/13/15	Maritza Go	onzalez						
Prospero, Manuel 11/13/15	143567			11/13/2015		67		\$0.00
.5HR CHECK EMAIL. 4HRS W0 140902. 3HRS W0 1428525HR ENTER LOG.  Manuel Prospero  144502	Medium	Work In Progress		11/13/2015 3:39:42 PM	I			
Medium Work In Progress 12/6/2015 12:40:18 AM  Prospero, Manuel Monthly - Santa Teresa MS -Clothes Dryer (Monthly) -	Prospero,	Manuel	.5HR CHECK EMAIL. 4HRS WO 140902. 3HRS WO 142852.		11/13/15			
Medium Work In Progress 12/6/2015 12:40:18 AM  Prospero, Manuel Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMschedule details.	Manuel Pr	rospero						
Prospero, Manuel Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMschedule details.	144502			12/6/2015		44		\$0.00
Refer to PMs chedule details.	Medium	Work In Progress		12/6/2015 12:40:18 AV	1			
Margret Villalobos	Prospero,	Manuel						
	Margret Vi	llalobos						

1/19/2016 11:45:17 AM Page 133 of 153

WOID Priority Assigned Requester	Building Status Fo	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS							
144503					12/6/2015	12/14/2015	44		\$0.00
Medium	Work In Progress			12/6/201	5 12:40:18 AM	1			
Prospero,	Manuel	Monthly - Santa Refer to PMsch	a Teresa MS Exit Sign nedule details.	n Insp: Month	y -				
Margret Vil	lalobos								
144504					12/6/2015	12/14/2015	44		\$0.00
Medium	Work In Progress			12/6/201	5 12:40:19 AM	1			
Prospero,	Manuel	Monthly - Santa Refer to PMsch	a Teresa MS Emer Li nedule details.	ight Test: Mon	thly -				
Margret Vil									
140642	South Building	Office			9/25/2015		116		\$0.00
Medium	Work In Progress	SEE MR.		9/25/20	)15 2:51:51 PN	Л			
Prospero,		-	S/SHEETROCK IN B D DOWN STAIRS.	OYS RESTRO	OOMS				
Laura Pari	a				4 /0 /0040	2/2/2016	40		<u>ФО 00</u>
145443					1/3/2016		16		\$0.00
Medium	Work In Progress			1/3/201	6 12:45:21 AM	1			
Prospero,		Monthly - Santa to PMschedule	a Teresa MS Bleache details.	er Inspection -	Refer				
Margret Vil	lalobos				4 /0 /0040		40		<b>ФО ОО</b>
145444					1/3/2016		16		\$0.00
Medium	Work In Progress			1/3/201	6 12:45:22 AM	1			
Prospero,		Monthly - Santa Refer to PMsch	a Teresa MS -Clothes nedule details.	s Dryer (Montl	nly) -				
Margret Vil	lalobos				1 10 10 0 10	4/44/0040			
145445					1/3/2016		16		\$0.00
Medium	Work In Progress			1/3/201	6 12:45:22 AM	1			
Prospero,	Manuel	Monthly - Santa Refer to PMsch	a Teresa MS Exit Sigr nedule details.	n Insp: Month	y -				
Margret Vil	lalobos								
145446					1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/201	6 12:45:23 AM	1			
Prospero,	Manuel	Monthly - Santa Refer to PMsch	a Teresa MS Emer Li nedule details.	ight Test: Mon	thly -				
Margret Vil	lalohos								

1/19/2016 11:45:17 AM Page 134 of 153

Laura Parra

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building Area Until **Request Date Target Comp Date Davs** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Santa Teresa MS Location: 146083 1/12/2016 7 \$0.00 1/12/2016 3:41:57 PM Medium Work In Progress Prospero, Manuel 1/12/16. .5HR CHECK E MAIL. 2HRS CHEKING HEATERS CAFETERIA. 2HRS TROUBLE SOOTER HEATERS PORTABLE 2 AND NURCES OFFICE. 3HRS WO 146077. .5HR ENTER LOG. Manuel Prospero Restroom 8/10/2015 162 \$0.00 137649 Medium Work In Progress 8/10/2015 2:55:21 PM WE NEED TO REPAIR PARTITION, AND HEAVY 8/21/15 - Asp Albert, route to Manuel to Prospero, Manuel FRAMES ON 3 BOYS AND GIRLS RESTROOMS. complete CAFETERIA RESTROOMS DOORS NEED TO LOCK Manuel Prospero Classroom 8/5/2015 167 137285 North Building \$0.00 Work In Progress 22 PRADO 8/5/2015 9:17:19 AM Medium CEILING HAS HAD WATER LEAK FOR 2 YEARS-Prospero, Manuel LEAK IS NEAR WHITE BOARD WALL Laura Parra 142535 North Building Classroom 10/29/2015 82 \$0.00 Medium Work In Progress 10/29/2015 9:59:44 AM AFTER SERVICING DRYER, CONTINUES NOT TO Prospero, Manuel DRY CLOTHES, NO HEAT Laura Parra 136584 Gym (1997) Gym 7/28/2015 175 \$0.00 Medium Work In Progress **GYM FLOOR** 7/28/2015 11:54:01 AM NEED TO REPLACE FLOOR SLEEVES FOR Prospero, Manuel VOLLEYBALL NET STANDARDS Laura Parra 1/6/2016 13 \$0.00 145695 Gym (1997) Dressing Room Medium Work In Progress GIRLS-1/6/2016 9:49:10 AM Prospero, Manuel HEATER IS NOT WORKING- HEATER WORKS IN GYM AND BOYS LOCKER ROOM

1/19/2016 11:45:17 AM Page 135 of 153

WOID Priority Assigned	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requeste							
Location:	Santa Te	resa MS					
143603			11/15/2015		65		\$0.00
Medium	Work In Progress		11/15/2015 12:27:54				
Flores, Pe	ete	Yearly - Santa Teresa MS - Mowe Refer to PMschedule details.	r 0416 - Grounds -				
Margret Vi							
138255	Gym (1997)		8/18/2015		154		\$0.00
Medium	Work In Progress		8/18/2015 3:34:23 PM	I			
Vallejo, Al	bert	The scorers table on the bleache or replaced	rs need to be repaired				
Alfredo Ho							
141985	South Building		10/20/2015		91		\$0.00
Medium	Work In Progress		10/20/2015 8:06:34 AM				
Miranda, [	Danny	Security Office - cover two pocket leading to office- tape texture and					
Alfredo Ho							
145200	South Building		12/17/2015		33		\$0.00
Medium	Work In Progress		12/17/2015 10:20:58				
Mijarez, Ja	aime	Room 31 - please check unit, una	ble to reset in Tracer.				
Albert Vall	ejo						
144431			12/6/2015		44		\$0.00
Medium	Work In Progress		12/6/2015 12:39:24 AM				
Flores, Pe	ete	Monthly - STM-UV-0518 PM Servi schedule details.	ce - Refer to PM				
Margret Vi	Ilalobos						
146142	North Building	Custodial	1/13/2016		6		\$0.00
Medium	Work In Progress		1/13/2016 11:06:43 AM				
Flores, Pe	ete	Pressure washer doesn't work ne	eed to be fix				
Ismael Ro	odriguez						
145369			1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:11 AM				
Prospero,	, Manuel	Monthly - Santa Teresa MS Roof PMschedule details.	Inspection - Refer to				
Margret Vi	Ilalobos						
146064	South Building	Exterior	1/12/2016		7		\$0.00
Medium	Work In Progress	STORAGE	1/12/2016 2:14:42 PM	I			
Lara, Ralp	<b>bh</b>	NEED DEADBOLT LOCK TO LOC SHED	CK UP STORAGE				
Laura Par	ra						
1/19/2016	6 11:45:17 AM					Page 13	6 of 153

1/19/2016 11:45:17 AM Page 136 of 153

Location: Santa Teresa MS  145694 North Building Classroom 1/6/2016 9:48:23 AM  Medium Work in Progress 9-CORDOVA 1/6/2016 9:48:23 AM  Lara, Ralph METAL FILING CABINET NEEDS TO BE RE-KEYED. CABINET IS LOCKED  Laura Parra  145138 North Building Classroom 12/16/2015  Medium Work in Progress ANITA DE LA 12/16/2015 12:05:00  Lara, Ralph NEED KEY 109 TO ENTER BUILDING DOOR BY RAMP  Laura Parra  145701 South Building Classroom 1/6/2016  Medium Work in Progress 1/6/2016 11:23:58 AM  Lara, Ralph South Building Classroom 1/6/2016  Medium Work in Progress 1/6/2016 11:23:58 AM  Lara, Ralph South Building Idower level teachers key got stuck class room #34 need the locksmith a.s.a.p. as per building mech.  Ismael Rodriguez  145930 1/10/2016 12:27:52 AM  Medium Work in Progress 1/10/2016 12:27:52 AM  Morthly - QRTLY BLDG INSP REPORT (STM) - Refer to PMschedule details.  Margret Villalobos  141421 10/9/2015  Cynthia Maes  14592 1/3/2016 1/9/2  Medium Work in Progress Outside Exit of 10/9/2015 4:17:37 PM  Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalito the concrete.  Cynthia Maes  14592 1/3/2016 1/9/2  Medium Work in Progress 1/3/2016 1/9/2	Date Days Date Aged ken	
Medium   Work In Progress   9-CORDOVA   1/6/2016 9:48:23 AM		
Lara, Ralph	13	\$0.00
CABINET IS LOCKED  Laura Parra  145138 North Building Classroom 12/16/2015  Medium Work In Progress ANITA DE LA 12/16/2015 12:05:00  Lara, Ralph NEED KEY 109 TO ENTER BUILDING DOOR BY RAMP  Laura Parra  145701 South Building Classroom 1/6/2016 11:23:58 AM  Lara, Ralph South Building Classroom 1/6/2016 11:23:58 AM  Lara, Ralph South Building Iower level teachers key got stuck class room #34 need the locksmith a.s.a.p. as per building mech.  Ismael Rodriguez  145930 1/10/2016 12:27:52 AM  Modium Work In Progress 1/10/2016 12:27:52 AM  Rodriguez, Ismael Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PM schedule details.  Margret Villalobos  141421 10/9/2015  Medium Work In Progress Outside Exit of 10/9/2015 4:17:37 PM  Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  1/45492 1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.  Margret Villalobos  142711 11/1/2015 11/22/5		
145138         North Building         Classroom         12/16/2015           Medium         Work In Progress         ANITA DE LA         12/16/2015 12:05:00           Lara, Ralph         NEED KEY 109 TO ENTER BUILDING DOOR BY RAMP           Laura Parra         145701         South Building         Classroom         1/6/2016 11:23:58 AM           Lara, Ralph         south building lower level teachers key got stuck class room #34 need the locksmith a.s.a.p. as per building mech.           Ismael Rodriguez         1/10/2016 12:27:52 AM           Medium         Work In Progress         1/10/2016 12:27:52 AM           Rodriguez, Ismael         Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PMschedule details.           Margret Villalobos         141421         10/9/2015           Medium         Work In Progress         Outside Exit of 10/9/2015 4:17:37 PM           Vallejo, Albert         Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.           Cynthia Maes         1/3/2016 12:46:08 AM           Prospero, Manuel         Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PMschedule details.           Margret Villalobos         11/1/2015 11/22/5		
Medium         Work In Progress         ANITA DE LA         12/16/2015 12:05:00           Lara, Ralph         NEED KEY 109 TO ENTER BUILDING DOOR BY RAMP           Laura Parra         145701         South Building         Classroom         1/6/2016           Medium         Work In Progress         1/6/2016 11:23:58 AM           Lara, Ralph         south building lower level teachers key got stuck class room #34 need the locksmith a.s.a.p. as per building mech.           Ismael Rodriguez         1/10/2016 12:27:52 AM           Medium         Work In Progress         1/10/2016 12:27:52 AM           Rodriguez, Ismael         Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PM schedule details.           Margret Villalobos         10/9/2015 4:17:37 PM           Vallejo, Albert         Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.           Cynthia Maes         1/3/2016 12:46:08 AM           145492         1/3/2016 12:46:08 AM           Medium         Work In Progress         1/3/2016 12:46:08 AM           Prospero, Manuel         Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.           Margret Villalobos         11/1/2015 11/22/5	0.4	Ф0.06
Lara, Ralph NEED KEY 109 TO ENTER BUILDING DOOR BY RAMP  Laura Parra  145701 South Building Classroom 1/6/2016  Medium Work In Progress 1/6/2016 11:23:58 AM  Lara, Ralph south building lower level teachers key got stuck class room #34 need the locksmith a.s.a.p. as per building mech.  Ismael Rodriguez  145930 1/10/2016 12:27:52 AM  Medium Work In Progress 1/10/2016 12:27:52 AM  Rodriguez, Ismael Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PM schedule details.  Margret Villalobos  141421 10/9/2015 4:17:37 PM  Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.  Margret Villalobos  11/1/2015 11/22/2	34	\$0.00
145701 South Building Classroom 1/6/2016  Medium Work In Progress 1/6/2016 11:23:58 AM  Lara, Ralph South building lower level teachers keygot stuck class room #34 need the locksmith a.s.a.p. as per building mech.  Ismael Rodriguez  145930 1/10/2016 12:27:52 AM  Medium Work In Progress 1/10/2016 12:27:52 AM  Rodriguez, Ismael Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PM schedule details.  Margret Villalobos  141421 10/9/2015 10/9/2015  Medium Work In Progress Outside Exit of 10/9/2015 4:17:37 PM  Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  145492 1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.  Margret Villalobos  141/2711 11/1/2015 11/22/2		
Medium Work In Progress 1/6/2016 11:23:58 AM  Lara, Ralph south building lower level teachers keygot stuck class room #34 need the locksmith a.s.a.p. as per building mech.  Ismael Rodriguez  145930 1/10/2016 12:27:52 AM  Rodriguez, Ismael Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PM schedule details.  Margret Villalobos  141421 10/9/2015 4:17:37 PM  Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.  Margret Villalobos  11/1/2015 11/22/2		
Lara, Ralph south building lower level teachers keygot stuck class room #34 need the locksmith a.s.a.p. as per building mech.  Ismael Rodriguez  145930 1/10/2016 12:27:52 AM  Medium Work In Progress 1/10/2016 12:27:52 AM  Rodriguez, Ismael Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PM schedule details.  Margret Villalobos  141421 10/9/2015  Medium Work In Progress Outside Exit of 10/9/2015 4:17:37 PM  Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  145492 1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.  Margret Villalobos  142711 11/1/2015 11/22/2	13	\$0.00
Ismael Rodriguez  145930 1/10/2016 1/26/2  Medium Work In Progress 1/10/2016 12:27:52 AM  Rodriguez, Ismael Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PM schedule details.  Margret Villalobos  141421 10/9/2015  Medium Work In Progress Outside Exit of 10/9/2015 4:17:37 PM  Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  145492 1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.  Margret Villalobos  142711 11/1/2015 11/22/2		
Medium Work In Progress 1/10/2016 12:27:52 AM  Rodriguez, Ismael Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PMschedule details.  Margret Villalobos  10/9/2015  Medium Work In Progress Outside Exit of 10/9/2015 4:17:37 PM  Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  1/3/2016 1/9/2  Medium Work In Progress 1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PMschedule details.  Margret Villalobos  142711 11/2015 11/22/2		
Medium Work In Progress  Rodriguez, Ismael  Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PMschedule details.  Margret Villalobos  141421  Medium Work In Progress  Outside Exit of  Vallejo, Albert  Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  1/3/2016  1/3/2016  1/3/2016  1/9/2  Medium Work In Progress  1/3/2016 12:46:08 AM  Prospero, Manuel  Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PMschedule details.  Margret Villalobos  1/1/2015  1/1/2015  1/1/2015		
Rodriguez, Ismael Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PMschedule details.  Margret Villalobos  141421 10/9/2015  Medium Work In Progress Outside Exit of 10/9/2015 4:17:37 PM  Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  1/3/2016 1/9/2  Medium Work In Progress 1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PMschedule details.  Margret Villalobos  1/1/2015 11/22/2	2016 9	\$0.00
to PMschedule details.  Margret Villalobos  141421		
141421 10/9/2015  Medium Work In Progress Outside Exit of 10/9/2015 4:17:37 PM  Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  145492 1/3/2016 1/9/2  Medium Work In Progress 1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.  Margret Villalobos  142711 11/1/2015 11/22/2		
Medium Work In Progress Outside Exit of 10/9/2015 4:17:37 PM  Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  145492 1/3/2016 1/9/2  Medium Work In Progress 1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.  Margret Villalobos  142711 11/1/2015 11/22/2		
Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  1/3/2016 1/9/2  Medium Work In Progress 1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.  Margret Villalobos  1/1/2015 11/22/2	102	\$0.00
ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.  Cynthia Maes  145492  1/3/2016  Medium Work In Progress  1/3/2016 12:46:08 AM  Prospero, Manuel  Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.  Margret Villalobos  142711  11/1/2015  11/22/2		
1/3/2016 1/9/2  Medium Work In Progress 1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.  Margret Villalobos 11/1/2015 11/22/2		
Medium Work In Progress 1/3/2016 12:46:08 AM  Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PMschedule details.  Margret Villalobos 11/1/2015 11/22/2		
Prospero, Manuel Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PMschedule details.  Margret Villalobos  11/1/2015 11/22/2	016 16	\$0.00
Refer to PMschedule details.  Margret Villalobos  142711 11/2015 11/22/2		
142711 11/2015 11/22/2		
Modium Work in Drogress	2015 79	\$0.00
Medium Work In Progress 11/1/2015 12:54:13 AM		
Orozco, Daniel Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PMschedule details.		

1/19/2016 11:45:17 AM Page 137 of 153

Maritza Gonzalez

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Days** Labor Area **Deferred By** Until Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Santa Teresa MS Location: 136401 Office 7/23/2015 180 \$0.00 Medium Work In Progress 7/23/2015 4:17:14 PM PLEASE GET A PRICE QUOTE FOR NEW STAFF Marquez, Gerardo MAILBOX AND BASE CABINETS FOR WORKRM. Gerardo Marquez Office 9/3/2015 138 \$0.00 139307 North Building Medium **ASST** 9/3/2015 3:22:50 PM Work In Progress Lara, Ralph OUTSIDE DOOR IN ASST PRINCIPALS OFFICE DOES NOT WORK PROPERLY, HARD TO OPEN AND CLOSE Laura Parra 7 146065 South Building Exterior 1/12/2016 \$0.00 **STORAGE** Medium Work In Progress 1/12/2016 2:16:43 PM Lara, Ralph NEED STRONGER DOORS PLACED IN STORAGE SHED. DOORS ARE NOT SECURE ENOUGH. Laura Parra 9/15/2015 126 \$0.00 139979 Medium Work In Progress 9/15/2015 12:50:46 PM Lara, Ralph Install a door in security office hallway. As per Administration, the office needs to secure confiscated items. See security officer for details. Albert Vallejo 9/17/2015 124 140121 \$0.00 9/17/2015 8:07:29 AM Medium Work In Progress Please install wrought iron screen door on athletics shed Lara, Ralph (new Morgan) Albert Vallejo 10/12/2015 99 \$0.00 141507 Medium Work In Progress 10/12/2015 2:30:14 PM GAP ON MAIN OUTSIDE DOORS STILL HAVE GAP Lara, Ralph (PREVIOUS WORK ORDER SUBMITTED 127544 SHOWS COMPLETE). SNP MANAGER GESSICA M. 589.9836

1/19/2016 11:45:18 AM Page 138 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Davs** Labor Area **Deferred By** Until Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Assigned To** Description **Action Taken** Requester Name Santa Teresa MS Location: 141419 10/9/2015 102 \$0.00 Medium Work In Progress Kitchen 10/9/2015 4:05:33 PM Lara, Ralph Bugs, dirt and trash enter through unsealed doors. Need to fixproblem, please inspect and repair. Food inspector has already been there and is expected to return to check if the problem has been repaired. Call Cynthia with any questions 882-6949. Cynthia Maes 141420 10/9/2015 102 \$0.00 Medium Work In Progress Kitchen 10/9/2015 4:13:39 PM Lara, Ralph Dining room doors are being secured with chains and pad locks. Inspect and repair so that pad locks don't need to be used. As per ergonomic inspections an access route to this clear space must be maintained at all times. Please call Cynthia with any questions 882-6949 Cynthia Maes 145796 1/7/2016 12 \$0.00 Medium Work In Progress 1/7/2016 3:00:35 PM Orozco, Daniel As per Jackie-Please ask Dannyifhe can install the portable pass thru warmer to help out with production. Maritza Gonzalez 141506 10/12/2015 99 \$0.00 Medium Work In Progress 10/12/2015 2:28:22 PM HANDLE FOR HOT WATER ON DISHWASHER AREA Orozco, Daniel IS BROKEN. SNP MANAGER GESSICA M. 589.9836 Maritza Gonzalez 9/2/2015 139 \$0.00 139197 Work In Progress 9/2/2015 8:03:32 AM Medium Gonzalez, Salvador A LEVER NEEDS TO BE WELDED ON A GATOR SO WE CAN CHECK THE FLUID LEVELS ON THE **ENGINE** Laura Parra 144091 12/1/2015 49 \$0.00 Medium Work In Progress 12/1/2015 11:45:10 AM 2 OVENS - DIALS ARE NOT WORKING CORRECTLY. Moncayo, Fernando SNP MANAGER GESSICA M. 589.9836

1/19/2016 11:45:18 AM Page 139 of 153

Maritza Gonzalez

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Area Until **Days** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: Santa Teresa MS 145706 1/6/2016 13 \$0.00 1/6/2016 1:39:20 PM Medium Work In Progress Will you please submit a work order for my two old Moncayo, Fernando school ovens, sometimes the units heat up and sometimes they don't. the problem seems to be getting worse. Maritza Gonzalez 11/6/2015 74 \$0.00 143198 Medium Work In Progress 11/6/2015 11:27:44 AM ON/OFF SWIETCH FROM EXHAUST FAN IN Moncayo, Fernando STORAGE AND WALK IN AREA ARE BROKEN. SNP MANAGER GESSICA M. 589.9836 Maritza Gonzalez Cafeteria 1/8/2016 11 \$0.00 145867 North Building Medium SEE CAF 1/8/2016 10:37:18 AM Work In Progress Villalobos, Margret MICE PROBLEM Laura Parra 11/1/2015 11/22/2015 79 \$0.00 142734 Work In Progress 11/1/2015 12:54:28 AM Medium Orozco, Daniel Monthly - Santa Teresa MS Fire Suppression Insp. -Refer to PMs chedule details. Margret Villalobos Total for Santa Teresa MS Count: 66 Work Orders \$25.00 Avg. Age of WO's 70

1/19/2016 11:45:18 AM Page 140 of 153

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order B Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES					
142735			11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress		11/1/2015 12:54:29 AM				
Orozco, Da	aniel	Monthly-Sunland Park ES Fire Refer to PMschedule details.	Suppression Insp				
Margret Vi	llalobos						
136740			7/30/2015		173		\$0.00
Medium	Work In Progress		7/30/2015 11:23:17 AM				
Ronquillo,	, Ruben	need platforms for bridge broke	en(hazard)				
Carlos He	ernandez						
141950			10/19/2015		92		\$0.00
Medium	Work In Progress		10/19/2015 3:36:43 PM				
Ronquillo,	, Ruben	missing one platform and one talked to mr ronqullio was goir one has showed up)					
Carlos He	ernandez						
144922			12/13/2015	12/29/2015	37		\$0.00
Medium	Work In Progress		12/13/2015 12:30:14				
Mijarez, Ja	iime	Monthly - Sunland Park ES Pla PMschedule details.	ayground Insp - Refer to				
Margret Vi	llalobos						
145945			1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress		1/10/2016 12:28:03 AM				
Mijarez, Ja	iime	Monthly - Sunland Park ES Pla PMschedule details.	ayground Insp - Refer to				
Margret Vi							
145614	Main Building		1/5/2016		14		\$0.00
Medium	Work In Progress		1/5/2016 10:11:45 AM				
Mijarez, Ja	ime	Jaime, EC playground is full of so that it can be ready when s Front of building is full of sand a against the front chain link fend	tudents can go out to play. and paper that is stuck				
Rosa Kah	oe						
144284			12/3/2015		47		\$0.00
Medium	Work In Progress		12/3/2015 1:50:44 PM				
Moncayo,	Fernando	SERVING LINE IS NOT COOL IGNACIA C. 589.2545	ING. SNP MANAGER				
Maritza Go	onzalez						

1/19/2016 11:45:18 AM Page 141 of 153

WOID Building Priority Status Assigned To Requester Name		Dates:7/1/2015 - 6/30/2016 Order I Area Deferred By Area Number Reason Description	Days Aged	Labor Hours	Costs		
Location:	Sunland	Park ES					
144786		Cafeteria	12/10/2015		40		\$0.00
Medium	Work In Progress		12/10/2015 7:36:06 AM				
Moncayo,	Fernando	NO HOT WATER IN KITCHEN 589-2545	N - SNP MGR IGNACIA				
Jacquelin	e Aguilar						
144765			12/9/2015		41		\$0.00
Medium	Work In Progress		12/9/2015 3:53:31 PM				
Gonzalez,	Salvador	metal gate on rock wall keeps Gate is heavy and can hurt a I have already repaired it, but of the hinges. Contact Jaime.	kid if it falls off completely.				
Jaime Mija							
145499	Main Building	Custodial	1/4/2016		15		\$0.00
Medium	Work In Progress		1/4/2016 5:21:12 AM				
Carbajal,	Jimmy	burnisher wont turn on. if you thanks	can please check it out				
Jesus Luc							
143107	Main Building	Custodial	11/5/2015		75		\$0.00
Medium	Work In Progress		11/5/2015 10:18:09 AM				
Carbajal,	Jimmy	Requesting new automatic so working and could not be fixed					
Jesus Luc	cero						• • • • •
142712			11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress		11/1/2015 12:54:13 AM				
Orozco, Da		Monthly-Sunland Park ES Ra Refer to PMschedule details.	nge Hood Cleaning -				
Margret Vi	llalobos		44/4/0045	44/7/2045	70		ФО OO
142839			11/1/2015	11/7/2015	79		\$0.00
Medium	Work In Progress		11/1/2015 12:55:38 AM				
Mijarez, Ja		Monthly - Sunland Park ES Monthly - Sunland Park ES Monthly - Refer to PMschedule details.	onthly FE Inspection -				
Margret Vi	llalobos		4/0/0040	4 10 10 0 4 2	40		<b></b>
145479			1/3/2016	1/9/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:45:56 AM				
Mijarez, Ja	iime	Monthly - Sunland Park ES Mo Refer to PMschedule details.	onthly FE Inspection -				
Margret Vi	llalobos						

1/19/2016 11:45:18 AM Page 142 of 153

WOID Priority Assigned Requester		Area Area Number Description	Deferred By	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Sunland	Park ES							
144537					12/6/2015	12/12/2015	44		\$0.00
Medium	Work In Progress			12/6/20	15 12:40:43 AM	1			
Mijarez, Ja	ime	Monthly - Sunla Refer to PMsch	and Park ES Monthly nedule details.	y FE Inspectio	n -				
Margret Vil	lalobos								
141381					10/9/2015		102		\$0.00
Medium	Work In Progress			10/9/2	015 3:31:47 PN	Л			
Estrada, Je	esus	floor tile in bath	room need to be rep	olaced in room	38				
Carlos He	rnandez								
145932					1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/20	16 12:27:54 AM	1			
Lucero, Jesus		Monthly - QRTL PMschedule de	Y BDLG INSP REP	PORT (SP) - R	efer to				
Margret Vil	lalobos								
141417	Main Building				10/9/2015		102		\$0.00
Medium	Work In Progress			10/9/2	015 4:04:12 PN	1			
Ontiveros,	Guadalupe	Front Entrance tree.	- Purchase and repl	lace 1 missin	palm				
Alfredo Ho	lguin								
145344					1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress			1/3/20	16 12:43:48 AM	1			
Mijarez, Ja	ime	Monthly - Sunla PMschedule d	and Park ES Roof In etails.	spection - Re	fer to				
Margret Vil	lalobos								
141871					10/16/2015		95		\$0.00
Medium	Work In Progress			10/16/2	015 3:39:05 PM	1			
Flores, Pet	te	tractor 970 4x4 get repaired)	dont work( worked	before they to	ok it to				
Carlos He	rnandez								
145136					12/16/2015		34		\$0.00
Medium	Work In Progress	library		12/1	6/2015 11:43:36	5			
Mijarez, Ja	ime		ED TO HAVE COOLI L ROOM CHECK AT FAIR						
	ımboa								

1/19/2016 11:45:18 AM Page 143 of 153

Total

## 952 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request <b>Building</b>	Dates:7/1/2015 - 6			Poguest Date	Target Comp Date	Dove	Labor	Costs
Priority	Status	Area Number	Deferred By	Until	-	Target Comp Date Actual Comp Date	Days Aged	Hours	
Assigned		Description	Neason	Oi Co	ned Bate, Time	Action Taken	•		
Requeste		2000. ip.i.o.i				nonon ranon			
Location:	Sunland	Park ES							
145137					12/16/2015		34		\$0.00
Medium	Work In Progress	36		12/1	6/2015 11:45:03				,
Mijarez, Ja	· ·	RM#36- HANT FOUNTAN IN	Z- PLEASE FIX THI THE CLASSROOM. COMING OUT OF T	E SINK & WATI THERE IS A V	≣R				
Maribel G	amboa								
143765		Library			11/18/2015		62		\$0.00
Medium	Work In Progress	LIBRARY		11/18/2	015 8:36:45 AM	1			
Mijarez, Ja	aime	_	RENO- NEEDS TO STALLED SEE MRS		ILE				
Maribel G	amboa								
137110		Classroom			8/3/2015		169		\$0.00
Medium	Work In Progress	25		8/3/2	015 3:04:41 PN	Л			
Mijarez, Jaime		RM#25- GARC DOORS	IA- PLEASE PAINT	CLASSROOM		Route to Jaime on 11	1/16/15		
Maribel G	amboa								
144112		Classroom			12/1/2015		49		\$0.00
Medium	Work In Progress	24		12/1/2	015 3:15:00 PN	Л			
Mijarez, Ja	aime	ONTHE PILAS	UFO- CAN YOU PL TERS IN THE HAL MED ARTWORK P ' ROOM	LWAYS IN ORI	DER				
Maribel G	amboa								
141920	Main Building	Parking Lot			10/19/2015		92		\$0.00
Medium	Work In Progress			10/1	9/2015 11:06:16	6			
Mijarez, Ja	aime	South Side of E weeds.	Building/Back Entri	es - cut and ren	nove	Route to Jaime on 11	1/16/15		
Alfredo Ho	olguin								
145703		Classroom			1/6/2016		13		\$0.00
Medium	Work In Progress	21		1/6/20	16 11:46:56 AM	1			
Mijarez, Ja	aime	OF WASHER A BOARD 3) NAI	DIA PEREZ- 1) UTI AND DRY. 2) PAINT LS ON WALL FOR BLE FOR COMPUT	AROUND HIT BULLETIN BO	ACHI ARD				
Maribel G	amboa								

1/19/2016 11:45:18 AM Page 144 of 153

WOID Priority Assigned <sup>-</sup> Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES					
144631			12/8/2015		42		\$0.00
Medium	Work In Progress	OFFICE	12/8/2015 7:40:23 AV	1			
Mijarez, Ja	ime	OFFICE- KAHOE- HER DOOR STO WORKING	OP IS NOT				
Maribel Ga	ımboa						
145708			1/6/2016		13		\$0.00
Medium	Work In Progress	40	1/6/2016 1:56:51 PM	1			
Mijarez, Ja	ime	RM#40- GAMBOA- THE ROOM IS	STILL COLD				
Maribel Ga	ımboa						
145709			1/6/2016		13		\$0.00
Medium	Work In Progress	29	1/6/2016 1:57:52 PM	1			
Mijarez, Ja	ime	RM#29- RESENDIZ- THE ROOM I	S COLD				
Maribel Ga							
142788			11/1/2015	11/9/2015	79		\$0.00
Medium	Work In Progress		11/1/2015 12:55:04 AM	1			
Mijarez, Ja	•	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PMschedule details.					
Margret Vil	lalobos						
145427			1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:45:06 AM	1			
Mijarez, Ja	ime	Monthly - Sunland Park ES Exit Sig Refer to PMschedule details.	ın Insp: Monthly-				
Margret Vil	lalobos						
145428			1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:45:07 AM	1			
Mijarez, Ja	ime	Monthly - Sunland Park ES Emer L Refer to PMschedule details.	ight Test: Monthly-				
Margret Vil	lalobos						
144115			12/1/2015		49		\$0.00
Medium	Work In Progress	19	12/1/2015 3:25:30 PM	1			
Mijarez, Ja	ime	RM#19 - CANO - REMOVE MY PROFROM PORTABLE B TO RM#19	OGRAM BOARDS				
Maribel Ga	ımboa						
144485			12/6/2015	12/14/2015	44		\$0.00
Medium	Work In Progress		12/6/2015 12:40:05 AM	1			
Mijarez, Ja	ime	Monthly - Sunland Park ES Exit Sig Refer to PMschedule details.	ın Insp: Monthly-				
Margret Vil	lalobos						

WOID	Building	Area Deferred By		Target Comp Date	Days Aged	Labor Hours	
Priority	Status	Area Number Reason	Created Date/Time	-	Ageu	i ioui s	
Assigned <sup>-</sup> Requester		Description		Action Taken			
		D. J. 50					
Location:	Sunland	Park ES					
144486			12/6/2015	12/14/2015	44		\$0.00
Medium	Work In Progress		12/6/2015 12:40:06 AN	1			
Mijarez, Ja	ime	Monthly - Sunland Park ES Em Refer to PMschedule details.	er Light Test: Monthly -				
Margret Vil	lalobos						
145195			12/17/2015		33		\$0.00
Medium	Work In Progress	21	12/17/2015 8:46:35 AN	1			
Mijarez, Ja	ime	RM#21- PEREZ - WANTS TO F WALL AND WANT 6 MORE CH CLASSROOM					
Maribel Ga	amboa						
137975			8/13/2015		159		\$0.00
Medium	Work In Progress	Nurse office	8/13/2015 3:41:17 PM	Л			
Lara, Ralph		OFFICE OFFICE- PLEASE HAV MAKE A HANDLE FOR THE 2N TALL FILE CABINET IN THE NI DRAWER HAS NO HANDLE	ID DRAWER OF THE				
Maribel Ga	amboa						
145160			12/16/2015		34		\$0.00
Medium	Work In Progress		12/16/2015 3:43:28 PM	1			
Lara, Ralpl	h	OFFICE - NEED TO HAVE A SM FOR COMBINATION	ALL SAFE LOOK AT				
Maribel Ga	amboa						
138311			8/19/2015		153		\$0.00
Medium	Work In Progress	25	8/19/2015 10:16:35 AN	1			
Mijarez, Ja	ime	RM#25 M.HOLGUIN- PLEASE THE CLASSROOM-2ND NOTIC		Route to Jaime on 11	/16/15		
Maribel Ga	amboa						
144739			12/9/2015		41		\$0.00
Medium	Work In Progress		12/9/2015 3:19:12 PN	Л			
Mijarez, Ja	ime	Paint portable interior walls with need 5 gallons.	n Vanilla Bean paint. I				
Jaime Mija	arez						
143762		Library	11/18/2015		62		\$0.00
Medium	Work In Progress	LIBRARY	11/18/2015 8:22:59 AN	1			
Mijarez, Jaime		LIBRARY- MORENO- NEED DO SEE MRS. MORENO	OORS PAINTED BLUE				

1/19/2016 11:45:18 AM Page 146 of 153

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason **Created Date/Time Actual Comp Date Status Priority Assigned To Description Action Taken** Requester Name Location: Sunland Park ES 143763 Library 11/18/2015 62 \$0.00 Medium Work In Progress LIBRARY 11/18/2015 8:25:55 AM LIBRARY- MORENO- NEED TO HAVE PAINTING Mijarez, Jaime FINISHED IN LIBRARY WALLS. LIGHT ARE STILL NOT TURNING ON COMPLETELY Maribel Gamboa 2/3/2016 145325 1/3/2016 16 \$0.00 1/3/2016 12:43:32 AM Medium Work In Progress Mijarez, Jaime Yearly - Sunland Park ES Backflow Inspection - Refer to PMschedule details. Margret Villalobos Count: 44 Work Orders **Total for Sunland Park ES** 0 Avg. Age of WO's 57 \$0.00

1/19/2016 11:45:18 AM Page 147 of 153

WOID Priority Assigned 1 Requester	Building Status o	Dates:7/1/2015 - 6/30/2016 Order By Loca Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunrise I	ES					
145323			1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:43:30 AM	1			
Vargas, Ju	an	Yearly - Sunrise ES Backflow Inspectschedule details.	ction - Refer to PM				
Margret Vill	alobos						
144564			12/7/2015		43		\$0.00
Medium	Work In Progress		12/7/2015 10:14:26 AM	1			
Chavez, Sa	intos	need fix 7 lights in cafeteria					
Juan Varga	as						
146072			1/12/2016		7		\$0.00
Medium	Work In Progress		1/12/2016 3:13:36 PN	1			
Chavez, Sa	intos	computer room need run 120 volts o	able for a/c unite				
Juan Varga	as						
139884			9/14/2015		127		\$0.00
Medium	Work In Progress		9/14/2015 10:06:24 AM	1			
Chavez, Sa	intos	need replace 4 hand dryer in 300 boto cafeteria grls. r.room	bys r.room and next				
Juan Varga	as						
145412			1/3/2016		16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:50 AM	1			
Vargas, Ju	an	Monthly - Sunrise ES - Clothes Drye to PMschedule details.	r (Monthly) - Refer				
Margret Vill	alobos						
145413			1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:51 AM	1			
Vargas, Ju	an	Monthly - Sunrise ES Emer. Light Te to PM schedule details.	est: Monthly - Refer				
Margret Vill	alobos						
145414			1/3/2016	1/11/2016	16		\$0.00
Medium	Work In Progress		1/3/2016 12:44:52 AM	1			
Vargas, Ju	an	Monthly - Sunrise ES Exit Sign Insp: PMschedule details.	Monthly - Refer to				
Margret Vill	alobos						
146073			1/12/2016		7		\$0.00
Medium	Work In Progress		1/12/2016 3:16:05 PN	1			
Vargas, Ju	an	a/c unite in computer room need rep circulator water pomp	ace motor and				
Juan Varga	as						

WOID Priority Assigned Requester	Building Status To	Area Number Description	i/30/2016 Order By Loc Deferred By Reason	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunrise I								
	- Juliuse I				1/12/2016		7		\$0.00
146071	W 11 B			4 /4 0 /6			1		φυ.υυ
Medium	Work In Progress				2016 3:11:39 PM	Л			
Appelzolle	r, Fred	100 wing custo	odian closed need ch	eck map sinl	c foucet				
Juan Varg	as								
145940					1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/20	16 12:27:59 AM	1			
Gallegos,	Felipe	Monthly - QRTI PMschedule d	_Y BLDG INSP REP( etails.	ORT (SR) - R	efer to				
Margret Vi	lalobos								
145470					1/3/2016	1/9/2016	16		\$0.00
Medium	Work In Progress			1/3/20	16 12:45:47 AM	1			
Vargas, Juan		Monthly - Sunri PMschedule d	ise ES Monthly FE In etails.	spection - R	efer to				
Margret Vi	lalobos								
142713					11/1/2015	11/22/2015	79		\$0.00
Medium	Work In Progress			11/1/20	15 12:54:14 AM	1			
Orozco, Da	aniel	Monthly-Sunri PMscheduled	se ES Range Hood ( etails.	Cleaning - Re	fer to				
Margret Vi	lalobos								
146276					1/15/2016		4		\$0.00
Medium	Work In Progress			1/15/2	2016 7:19:23 AM	1			
Orozco, Da	aniel	TOP LEFT OVE GLENDA G. 82	EN IS NOT HEATING 24.3194	SNP MANA	SER				
Maritza Go	nzalez								
145468					1/3/2016		16		\$0.00
Medium	Work In Progress			1/3/20	16 12:45:45 AM	1			
Apodaca,	Mario	Monthly - Sunri PMschedule d	se ES - Lift Station I etails.	nspection - I	Refer to				
Margret Vi	lalobos								
145955				<u> </u>	1/10/2016	1/26/2016	9		\$0.00
Medium	Work In Progress			1/10/20	16 12:28:11 AM	1			
Vargas, Ju	an	Monthly - Sunri schedule detai	se ES Playground Ir ls.	nsp - Refer to	PM				
Margret Vi	lalobos								

1/19/2016 11:45:18 AM Page 149 of 153

**Total** Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Priority Status Assigned To Description Action Taken** Requester Name Location: Sunrise ES 142736 11/1/2015 11/22/2015 79 \$0.00 Medium Work In Progress 11/1/2015 12:54:29 AM Monthly-Sunrise ES Fire Suppression Insp. - Refer to Orozco, Daniel PMschedule details. Margret Villalobos Count: 16 Work Orders Total for Sunrise ES Avg. Age of WO's 29 0 \$0.00

1/19/2016 11:45:18 AM Page 150 of 153

Location:         Vado ES           142737         11/1/2015 12:54:30 AM         79           Medium         Work In Progress         11/1/2015 12:54:30 AM         79           Orozco, Daniel         Monthly - Vado ES Fire Suppression Insp Refer to PM schedule details.         1/10/2016 12:28:05 AM         1/26/2016 9           Medium         Work In Progress         1/10/2016 12:28:05 AM         1/26/2016 9         9           Merry Medium         Work In Progress         1/21/2015 12:28:05 AM         49         1/26/2016 12:28:05 AM         49           Medium         Work In Progress         1/21/2015 7:44:42 AM         7         12/1/2015 12:42 AM         7         14/4077         49         40 </th <th>Labor Hours</th> <th></th> <th>Cos</th>	Labor Hours		Cos
Medium         Work In Progress         11/1/2015 12:54:30 AM           Orozco, Daniel         Monthly - Vado ES Fire Suppression Insp Refer to PM schedule details.           Margret Villalobos         1/10/2016 12:28:05 AM           Medium         Work In Progress         1/10/2016 12:28:05 AM           Margret Villalobos         1/10/2015 7:44:42 AM           Margret Villalobos         12/1/2015 7:44:42 AM           Medium         Work In Progress         12/1/2015 7:44:42 AM           Orozco, Daniel         SKILLET IS NOT HEATING PROPERLY, SNP MANAGER ELIZABETH M. 233.2945           Medium         Work In Progress         11/1/2015 12:54:15 AM           Orozco, Daniel         Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.           Margret Villalobos         11/1/2016 12:54:15 AM           Margret Villalobos         1/1/2/2016 8:38:18 AM           Medium         Work In Progress         1/1/2/2016 8:38:18 AM           Gonzales, Camilo         There is a chair that is at Vado Elementary School that will need to be moved to the physical therapy storage room in the Anthony office (the Ajamo). If you have any questions pertaining to this request please call the office at 575-882-6221. Thank you.           Susie Ramos         12/15/2015 1:44:27 PM           Hodium         Work In Progress         12/15/2015 1:44:27 PM           Flores, Pete         AUTO			
Monthly - Vado ES Fire Suppression Insp Refer to PM schedule details.	Ş		\$0
Margret Villa  obos			
145947         1/10/2016         1/26/2016         9           Medium         Work In Progress         1/10/2016 12:28:05 AM         1/26/2016 12:28:05 AM           Miranda, Danny         Monthly - Vado ES Playground Insp - Refer to PM schedule details.         49           Margret Villalobos         12/1/2015 7:44:42 AM         49           Medium         Work In Progress         12/1/2015 7:44:42 AM         49           Orozzo, Daniel         SKILLET IS NOT HEATING PROPERLY. SNP MANAGER ELIZABETH M. 233.2945         11/1/2015 12:54:15 AM         11/22/2015 79           Medium         Work In Progress         11/1/2015 12:54:15 AM         11/22/2015 79           Orozzo, Daniel         Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.         7           Margret Villalobos         1/12/2016 8:38:18 AM         7           Medium         Work In Progress         1/12/2016 8:38:18 AM         7           Gonzales, Camilo         There is a chair that is at Vado Elementary School that will need to be moved to the physical therapystorage room in the Anthony office (the Alamo). If you have any questions pertaining to this requestplease call the office at 575-882-6221. Thank you.         35           Susie Ramos Lara         1/15/2015 1:44:27 PM         35           Medium         Work In Progress         1/2/15/2015 1:44:27 PM         35           Flore			
Medium         Work In Progress         1/10/2016 12:28:05 AM           Miranda, Danny         Monthly - Vado ES Playground Insp - Refer to PM schedule details.           Margret Villalobos         12/1/2015         49           Medium         Work In Progress         12/1/2015 7:44:42 AM         49           Orozco, Daniel         SKILLET IS NOT HEATING PROPERLY. SNP MANAGER ELIZABETH M. 233.2945         5         11/1/2015 12:54:15 AM           Maritza Gonzalez         Maritza Gonzalez         11/1/2015 12:54:15 AM         79         11/1/2015 12:54:15 AM           Orozco, Daniel         Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.         7			
Miranda, Danny         Monthly - Vado ES Playground Insp - Refer to PM schedule details.           Margret Villalobos         12/1/2015         49           Medium         Work In Progress         12/1/2015 7:44:42 AM         49           Orozco, Daniel         SKILLET IS NOT HEATING PROPERLY. SNP MANAGER ELIZABETH M. 233.2945         11/1/2015         11/1/2015         79           Medium         Work In Progress         11/1/2015 12:54:15 AM         79         11/1/2015         79           Medium         Work In Progress         1/1/2/2016 12:54:15 AM         7         11/1/2/2016         7           Medium         Work In Progress         1/1/2/2016 8:38:18 AM         7         1/1/2/2016 3:38:18 AM         7           Gonzales, Camilo         There is a chair that is at Vado Elementary School that will need to be moved to the physical therapy storage room in the Anthony office (the Alamo). If you have any questions pertaining to this request please call the office at 575-882-6221. Thank you.         35           Susie Ramos Lara         145064         12/15/2015 1:44:27 PM         35           Medium         Work In Progress         12/15/2015 1:44:27 PM         35           Flores, Pete         AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG         9           Danny Miranda         Work In Progress	Ş		\$0
Schedule details.   Margret Villalobos			
144077			
Medium         Work In Progress         12/1/2015 7:44:42 AM           Orozco, Daniel         SKILLET IS NOT HEATING PROPERLY. SNP MANAGER ELIZABETH M. 233.2945           Maritza Gonzalez         11/1/2015 12:54:15 AM           Medium         Work In Progress         11/1/2015 12:54:15 AM           Orozco, Daniel         Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.           Margret Villalobos         1/12/2016 12:54:15 AM           Medium         Work In Progress         1/12/2016 8:38:18 AM           Gonzales, Camilo         There is a chair that is at Vado Elementary School that will need to be moved to the physical therapy storage room in the Anthony office (the Alamo). If you have any questions pertaining to this request please call the office at 575-882-6221. Thank you.           Susie Ramos Lara         145064         12/15/2015 1:44:27 PM           Flores, Pete         AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG           Danny Miranda         1/10/2016 12:27:47 AM			•
SKILLET IS NOT HEATING PROPERLY. SNP   MANAGER ELIZABETH M. 233.2945	(		\$0
MANAGER ELIZABETH M. 233.2945         Maritza Gonzalez         142714       11/1/2015       11/22/2015       79         Medium       Work In Progress       11/1/2015 12:54:15 AM       7         Orozco, Daniel       Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.       5         Margret Villalobos       1/12/2016       7         Medium       Work In Progress       1/12/2016 8:38:18 AM         Gonzales , Camilo       There is a chair that is at Vado Elementary School that will need to be moved to the physical therapy storage room in the Anthony office (the Alamo). If you have any questions pertaining to this request please call the office at 575-882-6221. Thank you.         Susie Ramos Lara       12/15/2015 1:44:27 PM         Hedium       Work In Progress       12/15/2015 1:44:27 PM         Flores , Peter       AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG         Danny Miranda       1/10/2016       1/26/2016       9         Medium       Work In Progress       1/10/2016 12:27:47 AM       9			
142714         11/1/2015         11/22/2015         79           Medium         Work In Progress         11/1/2015 12:54:15 AM         11/22/2015         79           Orozco, Daniel         Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.         2         2         2         2         2         3         3         4         4         4         4         4         4         4         4         4         4         4         4         4         4         4         4         4         4         2         4         4         4         4         2         1         4			
Medium Work In Progress 11/1/2015 12:54:15 AM  Orozco, Daniel Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.  Margret Villalobos  146041 1/12/2016 7  Medium Work In Progress 1/12/2016 8:38:18 AM  Gonzales, Camilo There is a chair that is at Vado Elementary School that will need to be moved to the physical therapy storage room in the Anthony office (the Alamo). If you have any questions pertaining to this request please call the office at 575-882-6221. Thank you.  Susie Ramos Lara  145064 12/15/2015 35  Medium Work In Progress 12/15/2015 1:44:27 PM  Flores, Pete AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG  Danny Miranda  1/10/2016 12:27:47 AM  Medium Work In Progress 1/10/2016 12:27:47 AM			Φ0
Orozco, Daniel Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.  Margret Villalobos  146041	``		\$0
Susie Ramos Lara  Susie Ramos Lara  AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG  Danny Miranda  Margret Villalobos  1/12/2016 8:38:18 AM  1/12/2016 8:38:18 AM  There is a chair that is at Vado Elementary School that will need to be moved to the physical therapy storage room in the Anthony office (the Alamo). If you have any questions pertaining to this request please call the office at 575-882-6221. Thank you.  Susie Ramos Lara  145064  AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG  Danny Miranda  145923  Medium Work In Progress  1/10/2016 12:27:47 AM			
146041         1/12/2016         7           Medium         Work In Progress         1/12/2016 8:38:18 AM           Gonzales, Camilo         There is a chair that is at Vado Elementary School that will need to be moved to the physical therapy storage room in the Anthony office (the Alamo). If you have any questions pertaining to this request please call the office at 575-882-6221. Thank you.           Susie Ramos Lara         12/15/2015         35           Medium         Work In Progress         12/15/2015 1:44:27 PM           Flores, Pete         AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG         Danny Miranda           Danny Miranda         1/10/2016         1/26/2016         9           Medium         Work In Progress         1/10/2016 12:27:47 AM         9			
Medium Work In Progress  1/12/2016 8:38:18 AM  Gonzales, Camilo  There is a chair that is at Vado Elementary School that will need to be moved to the physical therapy storage room in the Anthony office (the Alamo). If you have any questions pertaining to this request please call the office at 575-882-6221. Thank you.  Susie Ramos Lara  145064  12/15/2015  35  Medium Work In Progress  12/15/2015 1:44:27 PM  Flores, Pete  AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG  Danny Miranda  145923  1/10/2016 12:27:47 AM			•
Gonzales, Camilo  There is a chair that is at Vado Elementary School that will need to be moved to the physical therapystorage room in the Anthony office (the Alamo). If you have any questions pertaining to this request please call the office at 575-882-6221. Thank you.  Susie Ramos Lara  145064  12/15/2015  35  Medium Work In Progress  AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG  Danny Miranda  145923  1/10/2016  1/26/2016  9  Medium Work In Progress  1/10/2016 12:27:47 AM	,		\$0
will need to be moved to the physical therapy storage room in the Anthony office (the Alamo). If you have any questions pertaining to this request please call the office at 575-882-6221. Thank you.  Susie Ramos Lara  145064  12/15/2015  35  Medium Work In Progress  12/15/2015 1:44:27 PM  Flores, Pete  AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG  Danny Miranda  145923  1/10/2016 12:27:47 AM			
145064       12/15/2015       35         Medium       Work In Progress       12/15/2015 1:44:27 PM         Flores, Pete       AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG         Danny Miranda       1/10/2016       1/26/2016       9         Medium       Work In Progress       1/10/2016 12:27:47 AM			
Medium Work In Progress  12/15/2015 1:44:27 PM  Flores, Pete  AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG  Danny Miranda  145923  1/10/2016 12:27:47 AM			
Flores, Pete AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG  Danny Miranda  1/10/2016 1/26/2016 9  Medium Work In Progress  AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG  1/10/2016 12:27:47 AM	Ç		\$0
CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVELOF CUTTUNG  Danny Miranda  145923			
145923 1/10/2016 1/26/2016 9 Medium Work In Progress 1/10/2016 12:27:47 AM			
Medium Work In Progress 1/10/2016 12:27:47 AM			
•	Ş		\$0
Diaz, Armando Monthly - QRTLY BLDG INSP REPORT (VE) - Refer to PMs chedule details.  Margret Villalobos			

1/19/2016 11:45:18 AM Page 151 of 153

WOID Priority Assigned 1 Requester	Building Status o	•	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Vado ES						
145611			1/5/2016		14		\$0.00
Medium	Work In Progress	1/5/2016	9:56:51 AM	1			
Miranda, D	anny	need to repair outside electrical covers					
Danny Mira	ında						
145620			1/5/2016		14		\$0.00
Medium	Work In Progress	1/5/2016 1	1:54:30 AV	1			
Miranda, D	anny	need to replace wheels to front gates					
Danny Mira	ında						
138946			8/28/2015		144		\$0.00
Medium	Work In Progress	8/28/2015	1:47:51 PM	1			
Chavez, Sa	intos	need 3 shatterless safety light bulbs 75 watts for kitce walk in and freezers	en				
Danny Mira	ında						
144866			12/11/2015		39		\$0.00
Medium	Work In Progress	12/11/20	15 10:31:24				
Chavez, Santos		need to replace emer. ballast in rooms 103,107,208, and teachers lounge	303,				
Danny Mira	ında		11/10/2015		70		\$0.00
Medium	Work In Progress	11/10/2015		•	70		φυ.υυ
	· ·			I			
Appelzoller		need to replace booster pump in 100-wing boiler room	m				
Danny Mira 145331	ında		1/3/2016	2/3/2016	16		\$0.00
Medium	Work In Progress	1/3/2016 1	2:43:37 AV		10		ψ0.00
Miranda, D	_	Yearly - Vado ES Backflow Inspection - Refer to PM schedule details.	2.43.31 AIV	'			
Margret Vill	alobos	scriedule details.					
144038	Main Building	Computer Lab	11/30/2015		50		\$0.00
Medium	Work In Progress	300 11/30/2015	3:40:15 PM	l			
Solis, Lore	nzo	Our new computer lab is very hot. We are unable to lower the temp.					
Reyes Valt	ierra						
140859			10/4/2015	10/25/2015	107		\$0.00
Medium	Work In Progress	10/4/2015 1	2:38:10 AM	1			
Orozco, Da	niel	Monthly - Vado ES F-39 Kitchen Exh Unit Semiannua Refer to PMschedule details.	al -				

1/19/2016 11:45:18 AM Page 152 of 153

							Total		
Selected Da WOID Priority	ate Range for Request Building Status	Dates:7/1/2015 - 6 Area Area Number	Deferred By U	Until	•	Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned		Description	Neason	Greated Date/Time F		Action Taken			
Requester									
Location:	Vado ES								
143177					11/6/2015		74		\$0.00
Medium	Work In Progress			11/6/2	2015 8:21:21 AM	I			
Solis, Lore	enzo	need to ck. uni	t in library north side v	vill not turn	off on				
Danny Mir	anda								
144256		Classroom			12/3/2015		47		\$0.00
Medium	Work In Progress	Room 300		12/3/2	2015 9:33:48 AM	l			
Solis, Lore	enzo	There is a burn	smell an a classroom	, please ch	neck				
Sylvia Car	у								
Count: 17	Work Orders	Δ	vg. Age of WO's 50			Total for Vad	o ES	0	\$0.00
Count: 95	2 Work Orders	A	g. Age of WO's 56			Grand Total		1	\$25.00

1/19/2016 11:45:18 AM Page 153 of 153