

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Location Not Assigned							
145496					1/4/2016		45		\$0.00
Medium	Work In Progress				1/4/2016 12:38:42 AM				
Flores, Pete	Monthly - District Tractors - Full Service PM - Refer to PM schedule details.								
Margret Villalobos									
Count: 1 Work Orders		Avg. Age of WO's	45	Total for <Blank>				0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Alta Vista Early College HS									
143208					11/6/2015		104		\$0.00
Medium	Work In Progress				11/6/2015 11:55:58 AM				
Vallejo, Albert		Roof Leak in the Library. It is right on top of the first table where computers are. Also roof leak in portable #6. Leak is right next to teachers desk.							
David Soriano									
143206		Parking Lot			11/6/2015		104		\$0.00
Medium	Work In Progress				11/6/2015 11:43:48 AM				
Soriano, David		4 - Flat Bar 17 x 1 x 1/8 8 - Carriage Bolts with nuts (1 1/2 in x 3/8)							
David Soriano									
146209					1/14/2016		35		\$0.00
Medium	Work In Progress				1/14/2016 9:51:31 AM				
Soriano, David		PVC cement and primer to fix ruptured water pipe							
David Soriano									
143993		Classroom			11/30/2015		80		\$0.00
Medium	Work In Progress				11/30/2015 7:30:49 AM				
Gonzalez, Salvador		Need rail to be welded							
David Soriano									
145871	Storage B-	Gym			1/8/2016		41		\$0.00
Medium	Work In Progress				1/8/2016 11:36:00 AM				
Chavez, Santos		Alta Vista (hwy 28) Need 60A breaker panel for P.E. portable							
Santos Chavez									
147907					2/14/2016		4		\$0.00
Medium	Work In Progress				2/14/2016 12:31:15 AM				
Sanchez, Raul		Monthly - Alta Vista ECHS- Water Filters - Refer to PM schedule details.							
Margret Villalobos									
143189					11/6/2015		104		\$0.00
Medium	Work In Progress	Teachers			11/6/2015 10:17:42 AM				
Villalobos, David		PLEASE INVESTIGATE THE POSSIBILITY OF INSTALLING A SMALL BAR SINK IN THE TEACHER'S EATING AREA FOR THE PURPOSE OF WASHING HANDS AND CLEANING MAINTENANCE.							
Yvette Cortez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Alta Vista Early College HS									
139910		Library			9/14/2015		157		\$0.00
Medium	Work In Progress				9/14/2015 2:11:00 PM				
Soriano, David		25 Pack assorted wire connectors (14 gauge wire) [Please include the green ones for the ground]							
David Soriano									
144961					12/14/2015		66		\$0.00
Medium	Work In Progress				12/14/2015 12:39:25				
Soriano, David		10- Electronic Ballast for 4 ft. 4-Lamp Fixture 6- Electronic Ballast for 4 ft. 2-Lamp Fixture							
David Soriano									
142013					10/20/2015		121		\$0.00
Medium	Work In Progress				10/20/2015 2:25:50 PM				
Soriano, David		4- White Heavy Duty Shelf and Rod Support 3- Concrete Mix Sacks							
David Soriano									
142305					10/26/2015		115		\$0.00
Medium	Work In Progress				10/26/2015 11:40:36				
Soriano, David		2- Melnor Y Shut-Off 2-Way Metal Hose Connector							
David Soriano									
142306					10/26/2015		115		\$0.00
Medium	Work In Progress				10/26/2015 11:51:47				
Soriano, David		2 Boxes - #6 x2 in. Phillips Bugle-Head Coarse Thread Sharp Point Gold Screw (1 lb.-Pack)							
		2 Boxes - #8 3 in. Philips Bugle-Head Coarse Thread Wood Screws (1 lb.-Pack)							
		2 Boxes - #6 x1-5/8 in. Philips Bugle-Head Coarse Thread Gold Screw							
David Soriano									
142369					10/27/2015		114		\$0.00
Medium	Work In Progress				10/27/2015 8:43:13 AM				
Soriano, David		3- 42x29 window blinds 2- 48x48 window blinds							
David Soriano									
140462					9/23/2015		148		\$0.00
Medium	Work In Progress				9/23/2015 8:58:29 AM				
Soriano, David		10- 2x4x8 Studs to hang up window blinds							
David Soriano									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Alta Vista Early College HS									
139907					9/14/2015		157		\$0.00
Medium	Work In Progress				9/14/2015 2:04:54 PM				
Soriano, David		10 - Ballaster 4 lamp 110 v							
David Soriano									
139734					9/10/2015		161		\$0.00
Medium	Work In Progress				9/10/2015 2:27:06 PM				
Soriano, David		4 - 9 in. Roller Covers 4- 2 in. Roller Covers 1- 2 in. Roller 1- 10 oz Caulking Gun 1- 4-in Metal Twist Nozzle (for Garden Hose)							
David Soriano									
139349					9/4/2015		167		\$0.00
Medium	Work In Progress				9/4/2015 10:38:51 AM				
Soriano, David		25ft - 3/8 Plastic hose 25ft - 1/2 Plastic Hose 5- (3/8 - 7/8) Hose Repair Clamp							
David Soriano									
139356					9/4/2015		167		\$0.00
Medium	Work In Progress				9/4/2015 11:07:10 AM				
Soriano, David		24 Hex Bolts with washer and nuts (size - 1/4 in width x 1/2 in. length) 2 Carriage bolts 3/8 in width x 2 1/2 length) with washers and nuts							
David Soriano									
146141					1/13/2016		36		\$0.00
Medium	Work In Progress				1/13/2016 11:02:07 AM				
Soriano, David		10 ft- 3/4 sch. 40 pvc pipe 1 - 3/4 sch. 40 pvc coupling 1 - 3/4 sch. 40 pvc male adapter 1- 3/4 in. x 6 ft. Polyethylene Pipe Wrap Insulation							
David Soriano									
146067		Parking Lot			1/12/2016		37		\$0.00
Medium	Work In Progress				1/12/2016 2:26:28 PM				
Soriano, David		1 8 ft uni-strut to hang up sings in parking lot.							
David Soriano									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Alta Vista Early College HS									
147971					2/18/2016		0		\$0.00
Medium	Work In Progress				2/18/2016 8:56:12 AM				
Vallejo, Albert		Move (3) Double Portables from DT to AVEC.							
Alfredo Holguin									
136834		Office			7/31/2015		202		\$0.00
Medium	Work In Progress	FRONT OFFICE			7/31/2015 10:03:35 AM				
Marquez, Gerardo		PLEASE INSTALL NEW COUNTER IN FRONT OFFICE AREA AT ANNEX BUILDING. FOR FURTHER DETAILS OR INFORMATION, PLEASE CONTACT YVETTE AT 882-6400.							
Yvette Cortez									
146752					1/26/2016		23		\$0.00
Medium	Work In Progress				1/26/2016 10:08:35 AM				
Carbajal, Jimmy		Needed 1 Shop Vac. for cleaning window sills							
David Soriano									
136112	Curriculum and				7/20/2015		213		\$0.00
Medium	Work In Progress	ANNEX			7/20/2015 9:53:42 AM				
Marquez, Gerardo		REPLACE OLD DOORS WITH WOOD FRAME AND GLASS DOORS AT ANNEX BUILDING. DOORS TO BE REPLACED HAVE BEEN LABELED FOR IDENTIFICATION. ANY QUESTIONS, PLEASE CONTACT YVETTE OR GEMA AT AVECHS 882-6400.							
Yvette Cortez									
145378					1/3/2016		46		\$0.00
Medium	Work In Progress				1/3/2016 12:44:19 AM				
Ronquillo, Ruben		Monthly - Alta Vista ECHS - (Qtrly) Fitness Equip - Refer to PMs schedule details.							
Margret Villalobos									
135852					7/14/2015		219		\$0.00
Medium	Work In Progress				7/14/2015 12:01:35 PM				
Vallejo, Albert		Improve sidewalks at front entrance.							
Albert Vallejo									
146127					1/13/2016		36		\$0.00
Medium	Work In Progress				1/13/2016 7:58:43 AM				
Vallejo, Albert		Upgrade electrical service for portables.							
Albert Vallejo									
Count: 27 Work Orders			Avg. Age of WO's 103			Total for Alta Vista Early College HS	0		\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
142861					11/2/2015		108		\$0.00
Medium	Work In Progress				11/2/2015 9:20:52 AM				
Solis, Lorenzo		Need some assistance on trouble shooting water leak on F.C.U. in room # 107.							
Arturo Nunez									
143774					11/18/2015		92		\$0.00
Medium	Work In Progress				11/18/2015 11:54:01				
Solis, Lorenzo		Need some assistance on H.W.R line on hydronic heating system in room # 107, is has leak.							
Arturo Nunez									
146739					1/26/2016		23		\$0.00
Medium	Work In Progress				1/26/2016 7:30:40 AM				
Vallejo, Albert		Remove plastic borders and sand to replace with concrete and woodchips at playgrounds.							
Albert Vallejo									
142145					10/22/2015		119		\$0.00
Medium	Work In Progress				10/22/2015 10:34:31				
Ontiveros, Joe		Admin Portable - water fountain (exterior) does not work.							
Albert Vallejo									
136332		Cafeteria			7/23/2015		210		\$0.00
Medium	Work In Progress	882-1904			7/23/2015 12:06:53 PM				
Nunez, Arturo		doors from room 101 and 102 need a weather strip..							
Laura Vazquez									
147400					2/4/2016		14		\$0.00
Medium	Work In Progress	882-1904			2/4/2016 9:33:08 AM				
Nunez, Arturo		move desk that is in the corner of the office and screw it in the corner of the lunchroom any question please ask Laura or Sandy Thank you.							
Laura Vazquez									
135840					7/14/2015		219		\$0.00
Medium	Work In Progress	FAMILY			7/14/2015 10:02:19 AM				
Nunez, Arturo		INSTALL TOILET SEAT DISPENSER WITH COVERS IN BOTH RESTROOMS.				10/9/15 - waiting for parts			
Noemi Duron									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
144270					12/3/2015		77		\$0.00
Medium	Work In Progress				12/3/2015 10:35:43 AM				
Nunez, Arturo		please provide us with a water hose on the other side of the pre k classrooms room 111, 110, 109 and 108 the teachers and IA's need to have one in that side so they can wash their water tables etc.							
Laura Vazquez									
145789					1/7/2016		42		\$0.00
Medium	Work In Progress	882-1904			1/7/2016 11:35:19 AM				
Nunez, Arturo		bolt down big red tube that in the pre-k playground... any questions ask Ms. Sandy							
Laura Vazquez									
138101					8/14/2015		188		\$0.00
Medium	Work In Progress	FAMILY			8/14/2015 4:38:22 PM				
Nunez, Arturo		Paint behind the T.V on the wall.							
Noemi Duron									
138597		Classroom			8/24/2015		178		\$0.00
Medium	Work In Progress	ANTHONY			8/24/2015 3:12:32 PM				
Nunez, Arturo		PLEASE PAINT AN INSIDE ONE WALL WHERE THE DRY ERASE BOARD WAS REMOVED AT THE ANTHONY FAMILY LITERACY CENTER. CONTACT JUANA ESPINOZA @ EXT.4420 OR RAY LARA @ EXT.6799 FOR FURTHER INFO.							
Karla Quesada									
147803					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 1:46:27 PM				
Nunez, Arturo		...as per Ray L. For the POA center in the portable at the Anthony Pre-K. To re-paint stairs/ramp leading to center entrance. Thank you.							
Esteban Rosas									
144025					11/30/2015		80		\$0.00
Medium	Work In Progress				11/30/2015 2:00:33 PM				
Chavez, Santos		Install wall packs around building.							
Albert Vallejo									
143784					11/18/2015		92		\$0.00
Medium	Work In Progress	882-1904			11/18/2015 2:32:43 PM				
Marquez, Gerardo		Install chains furnished and weld on to gates please							
Laura Vazquez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
137103					8/3/2015		199		\$0.00
Medium	Work In Progress				8/3/2015 2:08:08 PM				
Ontiveros, Guadalupe		Please trim trees that are in the front office thank you.							
Laura Vazquez									
Count: 15 Work Orders		Avg. Age of WO's	110	Total for Anthony - On Track Pre-K (Village)				0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
144923					12/13/2015	12/29/2015	67		\$0.00
Medium	Work In Progress				12/13/2015 12:30:15				
Nunez, Arturo		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									
147073					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:18 AM				
Nunez, Arturo		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
147074					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:18 AM				
Nunez, Arturo		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
142697					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:03 AM				
Orozco, Daniel		Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
145364					1/3/2016		46		\$0.00
Medium	Work In Progress				1/3/2016 12:44:06 AM				
Vallejo, Albert		Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
145309					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:19 AM				
Nunez, Arturo		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
147409					2/4/2016		14		\$0.00
Medium	Work In Progress				2/4/2016 12:01:51 PM				
Nunez, Arturo		Prune and clean area around tree/bushes on ponding area on student drop off							
Arturo Nunez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Anthony ES										
144956					12/14/2015		66		\$0.00	
Medium	Work In Progress	261			12/14/2015 11:39:15					
Chavez, Santos		Please replace light bulb in room #261 V. Ramos								
Jessica Lopez										
144635					12/8/2015		72		\$0.00	
Medium	Work In Progress				12/8/2015 8:04:05 AM					
Flores, Pete		The speedometer and odometer are not working properly in district assigned car #13. These are safety issues because the speedometer is not monitoring speed and the odometer is not monitoring miles traveled.								
Susie Ramos Lara										
146128					1/13/2016		36		\$0.00	
Medium	Work In Progress				1/13/2016 8:14:42 AM					
Nunez, Arturo		Need 6 ea. Trane Zone sensors for A.H.U'S in Main building # x13790842-01 Rev. A (SEN1518). Thank you.								
Arturo Nunez										
145966		Classroom			1/11/2016		38		\$0.00	
Medium	Work In Progress				1/11/2016 8:19:31 AM					
Ronquillo, Ruben		Need to replace the blinds in room 102 please. This room is used as a training/work room for special ed department throughout the district								
Susie Ramos Lara										
145986					1/11/2016		38		\$0.00	
Medium	Work In Progress				1/11/2016 11:33:09 AM					
Ronquillo, Ruben		Need to replace the blinds in the following offices: Office 101, 119, 111, 109, 110 and the main office.								
Susie Ramos Lara										
136827					7/31/2015		202		\$0.00	
Medium	Work In Progress	107			7/31/2015 9:04:38 AM					
Nunez, Arturo		Mr. Nunez, Please move white board to a different location Please see Ms. Gibson Room #107								
Jessica Lopez										
136796					7/30/2015		71		\$0.00	
Medium	Work In Progress				7/30/2015 3:53:27 PM	10/9/2015				
Holguin, Alfredo		Need to have a fire sprinkler connection repaired in room # 107. leaking pretty bad.				will fax to dimar for quote as per alfredo				
Arturo Nunez										
2/18/2016 11:23:45 AM										

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
143685					11/16/2015		94		\$0.00
Medium	Work In Progress				11/16/2015 4:19:44 PM				
Marquez, Gerardo		Please cut extra keys for Alamo Cafeteria.							
Albert Vallejo									
147772					2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 4:06:08 PM				
Ontiveros, Joe		Please replace safety valve on boiler NM320136 so that valve will have manufacturer information nameplate.							
Albert Vallejo									
146839					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 11:56:17 AM				
Nunez, Arturo		Need 5 surveillance signs the ones we have are old.							
Arturo Nunez									
139297		Office			9/3/2015		168		\$0.00
Medium	Work In Progress				9/3/2015 1:41:36 PM				
Nunez, Arturo		Need to have someone come in an replace all the air conditioner grills in the SPED ADMIN OFFICES.							
Susie Ramos Lara									
147915					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 8:58:01 AM				
Orozco, Daniel		Could you please put a work order for the salad chopper, it doesn't close and it can't be turn on. SNP Manager Lorena B.882.3507							
Maritza Gonzalez									
146748					1/26/2016		23		\$0.00
Medium	Work In Progress				1/26/2016 9:08:05 AM				
Orozco, Daniel		OVEN DIALS ON ALL 4 OVENS ARE NOT WORKING.SNP LORENA B. 882.3507							
Maritza Gonzalez									
147799					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 12:29:55 PM				
Vega, Danny		Please install 4 toilet seat dispensers in the ladies restrooms. And provide the toilet seat covers for the dispensers. Thank you.							
Susie Ramos Lara									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
147779					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 7:38:06 AM				
Solis, Lorenzo		Need some assistance on trouble shooting mini split unit in room # 108 at pre k.							
Arturo Nunez									
146824					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 8:36:11 AM				
Carbajal, Jimmy		vacuum cleaner serial#02747 having trouble with electrical cord also replace brush							
David Vega									
146816					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 7:30:36 AM				
Vallejo, Albert		Construct hand rails and guard rails for ADA ramps in front of Alamo.							
Albert Vallejo									
146419					1/20/2016		29		\$0.00
Medium	Work In Progress				1/20/2016 8:13:09 AM				
Solis, Lorenzo		Need some assistance on clearing all alarms for A.H.U'S , on main campus, and pre k units.							
Arturo Nunez									
145946					1/10/2016	1/26/2016	39		\$0.00
Medium	Work In Progress				1/10/2016 12:28:04 AM				
Nunez, Arturo		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									
147531					2/7/2016	2/23/2016	11		\$0.00
Medium	Work In Progress				2/7/2016 12:31:54 AM				
Nunez, Arturo		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									
145846					1/8/2016		41		\$0.00
Medium	Work In Progress				1/8/2016 12:28:49 AM				
Nunez, Arturo		Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details.							
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
147545					2/7/2016		11		\$0.00
Medium	Work In Progress				2/7/2016 12:32:04 AM				
Nunez, Arturo		Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details.							
Margret Villalobos									
146638					1/23/2016		26		\$0.00
Medium	Work In Progress				1/23/2016 12:27:19 AM				
Nunez, Arturo		Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details.							
Margret Villalobos									
Count: 30 Work Orders			Avg. Age of WO's	46		Total for Anthony ES	0		\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Berino ES							
147182					2/1/2016		17		\$0.00
Medium	Work In Progress				2/1/2016 10:57:56 AM				
Diaz, Sebastian		Need to replace filters on DP thank you							
Sebastian Diaz									
139809					9/11/2015		160		\$0.00
Medium	Work In Progress				9/11/2015 12:58:12 PM				
Solis, Lorenzo		Need to fix water fountain on room 121 thank you							
Sebastian Diaz									
147395					2/4/2016		14		\$0.00
Medium	Work In Progress				2/4/2016 9:07:08 AM				
Ontiveros, Joe		Need to check water heater on portable 156 not hot water thank you							
Sebastian Diaz									
145973	Main Building	Custodial			1/11/2016		38		\$0.00
Medium	Work In Progress				1/11/2016 9:12:09 AM				
Carbajal, Jimmy		vaccum cleaner smoking #do5aoooo5374							
Francisco Marin									
146429	Main Building	Custodial			1/20/2016		29		\$0.00
Medium	Work In Progress				1/20/2016 12:08:52 PM				
Carbajal, Jimmy		blower is smoking it starts and then turns of smells alot of gas							
Francisco Marin									
146430	Main Building	Custodial			1/20/2016		29		\$0.00
Medium	Work In Progress				1/20/2016 12:12:15 PM				
Carbajal, Jimmy		vacuum is sparking #do5aoooo							
Francisco Marin									
147588					2/8/2016		10		\$0.00
Medium	Work In Progress				2/8/2016 3:33:36 PM				
Orozco, Daniel		SINK FAUCETS LEAKING. SNP MANAGER MERCEDES F. 882.2417							
Maritza Gonzalez									
141139					10/6/2015		135		\$0.00
Medium	Work In Progress				10/6/2015 3:19:29 PM				
Gonzalez, Salvador		Need to install metal ramp on portable 18 thank you							
Sebastian Diaz									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Berino ES									
140256					9/18/2015		153		\$0.00
Medium	Work In Progress				9/18/2015 3:36:56 PM				
Chavez, Santos		need to fix light on room 10 thank you							
Sebastian Diaz									
139814					9/11/2015		160		\$0.00
Medium	Work In Progress				9/11/2015 2:31:31 PM				
Chavez, Santos		Need to install power for smart board on room 101 thank you							
Sebastian Diaz									
147735					2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 3:29:09 PM				
Apodaca, Mario		Need to check water filters thank you							
Sebastian Diaz									
147793					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 11:01:00 AM				
Apodaca, Mario		Need check water tank for sprinkler is clog for sand thank you							
Sebastian Diaz									
146827					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 8:47:43 AM				
Diaz, Sebastian		Need 7 signs Video Surveillance thank you							
Sebastian Diaz									
147250					2/2/2016		16		\$0.00
Medium	Work In Progress				2/2/2016 8:36:35 AM				
Carrasco, Danny		Need exhaust fan motor for Electrical room thank you							
Sebastian Diaz									
147583					2/8/2016		10		\$0.00
Medium	Work In Progress				2/8/2016 3:31:12 PM				
Gonzalez, Salvador		need to secure new heater on portable 18 DP thank you							
Sebastian Diaz									
143635					11/16/2015		94		\$0.00
Medium	Work In Progress				11/16/2015 1:38:26 PM				
Chavez, Santos		Need to check hand dryer on boy's restroom thank you							
Sebastian Diaz									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Berino ES									
146611					1/22/2016		27		\$0.00
Medium	Work In Progress				1/22/2016 3:41:30 PM				
Chavez, Santos		Need to fix emergency lights on hall thank you							
Sebastian Diaz									
147587					2/8/2016		10		\$0.00
Medium	Work In Progress				2/8/2016 3:33:30 PM				
Ontiveros, Guadalupe		need assist for sprinkler in front school thank you							
Sebastian Diaz									
144663					12/8/2015		72		\$0.00
Medium	Work In Progress				12/8/2015 3:04:59 PM				
Ontiveros, Joe		Need to check boiler domestic water not turn on thank you							
Sebastian Diaz									
143637					11/16/2015		94		\$0.00
Medium	Work In Progress				11/16/2015 1:41:51 PM				
Ontiveros, Joe		Need check leak water on boiler pipes thank you							
Sebastian Diaz									
147262					2/2/2016		16		\$0.00
Medium	Work In Progress				2/2/2016 12:35:01 PM				
Ontiveros, Joe		Need to replace lounge 8" center faucet thank you							
Sebastian Diaz									
145310					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:20 AM				
Diaz, Sebastian		Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
147331					2/3/2016		15		\$0.00
Medium	Work In Progress				2/3/2016 12:36:14 PM				
Ontiveros, Guadalupe		Need small tractor to remove sand DP and Berino thank you							
Sebastian Diaz									
146507					1/21/2016		28		\$0.00
Medium	Work In Progress				1/21/2016 11:11:08 AM				
Ontiveros, Guadalupe		Need Aerator for fields thank you							
Sebastian Diaz									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
Location: Berino ES									
145358					1/3/2016	1/24/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:44:01 AM				
Vallejo, Albert	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
142698					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:04 AM				
Orozco, Daniel	Monthly - Berino ES Range Hood Cleaning - Refer to PMs schedule details.								
Margret Villalobos									
Count: 26 Work Orders			Avg. Age of WO's	53		Total for Berino ES	0	0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
142699					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:05 AM				
Orozco, Daniel		Monthly - Chapparal ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
147543					2/7/2016	2/23/2016	11		\$0.00
Medium	Work In Progress				2/7/2016 12:32:02 AM				
Quinones, Paul		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
145308					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:18 AM				
Quinones, Paul		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
142112		Athletic Field			10/21/2015		120		\$0.00
Medium	Work In Progress				10/21/2015 3:49:46 PM				
Ontiveros, Guadalupe		Ms. Nougues is requesting a baseball field.							
Guadalupe Ontiveros									
146831					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 10:28:26 AM				
Quinones, Paul		Need 3 surveillance signs.							
Paul Quinones									
144018					11/30/2015		80		\$0.00
Medium	Work In Progress				11/30/2015 12:47:38				
Marquez, Gerardo		requesting handicap door closer double doors next to cafeteria principle requesting door closer for handi cap student							
Paul Quinones									
145792					1/7/2016		42		\$0.00
Medium	Work In Progress				1/7/2016 12:33:17 PM				
Quinones, Paul		requesting heating only thermostats 24 volt type, to replace broken ones.							
Paul Quinones									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
146524					1/21/2016		28		\$0.00
Medium	Work In Progress				1/21/2016 3:28:15 PM				
Quinones, Paul		need to remove broken and water stained cieling tiles in all hall ways at chm.requesting 7 boxes of cieling tiles							
Paul Quinones									
146526					1/21/2016		28		\$0.00
Medium	Work In Progress				1/21/2016 3:32:39 PM				
Quinones, Paul		need to replace metal bath rm. metal partitions,rusted and broken door hinges reorder hardware as well. @ chm							
Paul Quinones									
145069	Main Building	Hallway/Corridor			12/15/2015		65		\$0.00
Medium	Work In Progress	school hallways			12/15/2015 3:11:54 PM				
Quinones, Paul		Need Paul to put up pennants throughout school hallways as soon as possible. See Mrs. Pargas or Ms. Barraza							
Jennifer Corral									
143180					11/6/2015		104		\$0.00
Medium	Work In Progress				11/6/2015 8:29:44 AM				
Solis, Lorenzø		needing filter material for heaters hogs hair 1 rl. 1/2".thank you.							
Paul Quinones									
146569		Custodial			1/22/2016		27		\$0.00
Medium	Work In Progress				1/22/2016 7:31:35 AM				
Carbajal, Jimmy		fix,handle,vaccum,machine,120002054							
Daniel Ramirez									
146570		Custodial			1/22/2016		27		\$0.00
Medium	Work In Progress				1/22/2016 7:35:00 AM				
Carbajal, Jimmy		fix,vaccum,machine,electrical,cord,switch.I06c00000111							
Daniel Ramirez									
142468		Custodial			10/28/2015		113		\$0.00
Medium	Work In Progress				10/28/2015 10:25:44				
Carbajal, Jimmy		need,four,vaccum,belts.							
Daniel Ramirez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Chaparral ES							
147864		Office			2/12/2016		6		\$0.00
Medium	Work In Progress				2/12/2016 1:38:24 PM				
Gonzales, Camilo		Deliver 40 boxes. PO# 151604953. Thank you.							
Theresa Ramirez									
Count: 15 Work Orders		Avg. Age of WO's		55	Total for Chaparral ES			0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Chaparral High - Pre-K										
147631		Classroom			2/9/2016		9		\$0.00	
Medium	Work In Progress				2/9/2016 10:23:16 AM					
Solis, Lorenzo		Having problem with Heating and cooling unit in room 101.								
Alfredo Ortiz										
142465					10/28/2015		113		\$0.00	
Medium	Work In Progress	FEDERAL			10/28/2015 9:45:21 AM					
Flores, Pete		SUBURBAN STARTED BUT ALL LIGHTS WERE TURNING ON AND OFF AND WAS DRIVING VERY SLOW.								
Noemi Duron										
Count: 2 Work Orders			Avg. Age of WO's	61	Total for Chaparral High - Pre-K			0	\$0.00	

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
147678	R-Wing				2/9/2016		9		\$0.00
Medium	Work In Progress				2/9/2016 3:54:48 PM				
Appelzoller, Fred		need new Mixing valve at building R Mixing valve isn't adjusting temp.							
Fred Appelzoller									
145329					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:35 AM				
Ortiz, Alfredo		Yearly - Chaparral HS Backflow Inspection - Refer to PMs schedule details.							
Margret Villalobos									
139387					9/4/2015		167		\$0.00
Medium	Work In Progress				9/4/2015 3:16:11 PM				
Ontiveros, Guadalupe		Please remove shrubbery in planters nearest the parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question)							
Albert Vallejo									
146844		Athletic Field			1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 2:15:45 PM				
Holguin, Alfredo		Football field Artificial Turf - Perform SportChamp deep cleaning service							
Alfredo Holguin									
145368					1/3/2016		46		\$0.00
Medium	Work In Progress				1/3/2016 12:44:10 AM				
Vallejo, Albert		Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PMs schedule details.							
Margret Villalobos									
145365					1/3/2016		46		\$0.00
Medium	Work In Progress				1/3/2016 12:44:07 AM				
Vallejo, Albert		Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PMs schedule details.							
Margret Villalobos									
147709		Auditorium			2/10/2016		8		\$0.00
Safety	Work In Progress	Gym floor			2/10/2016 10:22:58 AM				
Prospero, Manuel		Please have black floor/wall board fixed. It is at the entrance of the gym by boys locker room area. The board is coming off and we had a person on trip and almost fall last time we had a basketball game. I will send picture to Margaret.							
Mireya Meza									
2/18/2016 11:23:46 AM									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
146148	H-Wing	Gym			1/13/2016		36		\$0.00
Medium	Work In Progress				1/13/2016 2:18:45 PM				
Ontiveros, Guadalupe		Attention to warehouse. The brass covers for the volleyball poles on the gym floor need to be replaced the handle broke off. They are tape on to the floor							
Alfredo Ortiz									
146503		Hallway/Corridor			1/21/2016		28		\$0.00
Medium	Work In Progress				1/21/2016 8:45:15 AM				
Ortiz, Alfredo		Need materials for school stock.							
Alfredo Ortiz									
147184		Gym			2/1/2016		17		\$0.00
Medium	Work In Progress				2/1/2016 12:46:11 PM				
Ortiz, Alfredo		Need to replace Ballast in GYM. and Light bulbs							
Alfredo Ortiz									
147320	Q-Wing	Classroom			2/3/2016		15		\$0.00
Medium	Work In Progress				2/3/2016 8:43:35 AM				
Ortiz, Alfredo		Need to re-place all 250 W light bulbs to 400 W bulbs in auto shop teacher said it's room to dark in the shop.							
Alfredo Ortiz									
146271	E-Wing	Classroom			1/14/2016		35		\$0.00
Medium	Work In Progress	E5			1/14/2016 4:02:06 PM				
Ortiz, Alfredo		Please install metal strip to hold and displays students work. (Ms. Pavlis, E5)							
Mireya Meza									
147180		Hallway/Corridor			2/1/2016		17		\$0.00
Medium	Work In Progress				2/1/2016 10:54:17 AM				
Ortiz, Alfredo		Need to order and replace Exhaust fan motors in Restrooms.							
Alfredo Ortiz									
147632	F-Wing	Classroom			2/9/2016		9		\$0.00
Medium	Work In Progress				2/9/2016 10:25:23 AM				
Marquez, Gerardo		Need to fix or replace cabinet door cylinders don't lock. In room F-4.							
Alfredo Ortiz									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
147476	Q-Wing	Classroom			2/5/2016		13		\$0.00
Medium	Work In Progress				2/5/2016 1:07:29 PM				
Marquez, Gerardo		Please inspect garage doors and fix any problems as needed.							
Alfredo Ortiz									
147408	Q-Wing	Classroom			2/4/2016		14		\$0.00
Medium	Work In Progress	Welding Room			2/4/2016 11:42:46 AM				
Marquez, Gerardo		Teacher is unable to lock the back door to the welding room. It seems to be the tumbler. (Mr. Lawler, welding room)							
Mireya Meza									
147474	Field House	Athletic Field			2/5/2016		13		\$0.00
Medium	Work In Progress	Softball			2/5/2016 11:40:21 AM				
Marquez, Gerardo		Jerry, need to order 2 86 key locks to secure softball storage room. (Lupe Quinones, security)							
Mireya Meza									
144639	H-Wing	Gym			12/8/2015		72		\$0.00
Medium	Work In Progress	Gym Training			12/8/2015 10:00:34 AM				
Chavez, Santos		2 fluorescent light bulbs are burned out in the gym training room. (Mrs. Walsh, gym training room)							
Mireya Meza									
145122					12/16/2015		64		\$0.00
Medium	Work In Progress				12/16/2015 8:40:49 AM				
Chavez, Santos		Pedro Valdez groundskeeper, need electrical outlet at storage and an inside light at least one outlet please need for maintenance equipment thank you supervisor. Alfredo Olguin or to whom concern.							
Pedro Valdez									
144860	Q-Wing	Hallway/Corridor			12/11/2015		69		\$0.00
Medium	Work In Progress				12/11/2015 9:41:19 AM				
Chavez, Santos		Need to replace burned out timer and contactor for outside light							
Alfredo Ortiz									
147256	Q-Wing	Classroom			2/2/2016		16		\$0.00
Medium	Work In Progress	Q4			2/2/2016 11:00:06 AM				
Chavez, Santos		I need two 220 female wall plugs hooked up. (Mr. Lawler, Q4)							
Mireya Meza									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

146652 H-Wing Auditorium 1/25/2016 24 \$0.00

Medium Work In Progress gym 1/25/2016 8:51:25 AM

Chavez, Santos There are 5 lights that are burned out in the gym. Bulbs need replacing. (Ms. Lopez, gym)

Mireya Meza

146650 Q-Wing Classroom 1/25/2016 24 \$0.00

Medium Work In Progress 1/25/2016 8:32:32 AM

Chavez, Santos The hoist in the welding shop won't move up or down. No power to contact.

Alfredo Ortiz

143638 11/16/2015 94 \$0.00

Medium Work In Progress 11/16/2015 2:37:24 PM

Apodaca, Mario Need to install a water meter in the mechanical room to see if there is a water leak underground on Geo thermal water line.

Alfredo Ortiz

138398 Q-Wing Classroom 8/20/2015 182 \$0.00

Medium Work In Progress Q6 8/20/2015 10:12:00 AM

Marquez, Gerardo Please make copy of Matco key 172. This key opens tool box in Autoshop. We also need copies made for all the other tool box keys. Please see Mireya. (Mireya Meza)

Mireya Meza

142462 Field House Athletic Field 10/28/2015 113 \$0.00

Medium Work In Progress Baseball Field 10/28/2015 9:32:29 AM

Ontiveros, Guadalupe Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas)

Mireya Meza

140543 9/24/2015 147 \$0.00

Medium Work In Progress 9/24/2015 8:34:17 AM

Marquez, Gerardo PLEASE WELD PADLOCKS AND CHAINS ON GATES.

Gerardo Marquez

139947 Field House Mechanical 9/14/2015 157 \$0.00

Medium Work In Progress 9/14/2015 3:58:21 PM

Chavez, Santos Buster pump for irrigation has to be reset every day, needs to checked electrical power.

Alfredo Ortiz

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
147909					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 7:22:24 AM				
Orozco, Daniel		REACH IN IS AS 62 DEGREES. SNP MANAGER JUANITA M. 824.4461							
Maritza Gonzalez									
146744					1/26/2016		23		\$0.00
Medium	Work In Progress				1/26/2016 8:33:20 AM				
Orozco, Daniel		OVEN IS NOT TURNING ON. SNP MANAGER JUANITA M.824.4461							
Maritza Gonzalez									
142396					10/27/2015		114		\$0.00
Medium	Work In Progress				10/27/2015 12:59:35				
Orozco, Daniel		NEON LIGHTS FOR FOLLOWING LINES NOT WORKING RED & GREEN, FRESH FROM THE GARDEN AND ON A BUN. SNP MANAGER JUANITA M. 824.4461							
Maritza Gonzalez									
143521	R-Wing	Classroom			11/12/2015		98		\$0.00
Medium	Work In Progress				11/12/2015 4:00:54 PM				
Orozco, Daniel		One of the stove ovens not working need to fix or replace gas valve. In Home Economics classroom.							
Alfredo Ortiz									
146826					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 8:39:12 AM				
Ortiz, Alfredo		Need two surveillance signs.							
Alfredo Ortiz									
142460	Field House	Athletic Field			10/28/2015		113		\$0.00
Medium	Work In Progress	Baseball Field			10/28/2015 9:28:03 AM				
Gonzalez, Salvador		Please install 4 mini batting cages for baseball field. (Coach Rojas)							
Mireya Meza									
142461	Field House	Athletic Field			10/28/2015		113		\$0.00
Medium	Work In Progress	Baseball Field			10/28/2015 9:30:35 AM				
Gonzalez, Salvador		Please install bull pen in visitors dugout area. (Coach Rojas)							
Mireya Meza									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
142463	Field House	Athletic Field			10/28/2015		113		\$0.00
Medium	Work In Progress	baseball field			10/28/2015 9:33:25 AM				
Gonzalez, Salvador									
Please install back stop extension on baseball field backstop. (Coach Rojas)									
Mireya Meza									
137624	C-Wing	Classroom			8/10/2015		192		\$0.00
Medium	Work In Progress				8/10/2015 9:37:57 AM				
Chavez, Santos									
In C-6 Green-house need to rewire electricity for heater, exhaust fan and A/C. Thank you.									
Alfredo Ortiz									
137857	Field House	Athletic Field			8/12/2015		190		\$0.00
Medium	Work In Progress	Softball field			8/12/2015 3:36:25 PM				
Chavez, Santos									
Need electricity for new softball/baseball batting cage. (Mireya Meza)									
Mireya Meza									
146508					1/21/2016		28		\$0.00
Medium	Work In Progress				1/21/2016 11:11:20 AM				
Ortiz, Alfredo									
Need to replace broken tools and order new tools augers, hammer drill and crimper, DeWalt battery.									
Alfredo Ortiz									
145840	Field House	Athletic Field			1/7/2016		42		\$0.00
Medium	Work In Progress	Softball			1/7/2016 4:06:58 PM				
Appelzoller, Fred									
Please install a water fountain/faucet at the field so we always have water. (coach Heddleston, softball)									
Mireya Meza									
140161	Field House	Athletic Field			9/17/2015		154		\$0.00
Medium	Work In Progress	Football &			9/17/2015 2:20:24 PM				
Ontiveros, Guadalupe									
To have green wind screens placed around the entire football and soccer field areas. (Ms. Ulibarri)									
Mireya Meza									
145838	Field House	Athletic Field			1/7/2016		42		\$0.00
Medium	Work In Progress	softball field			1/7/2016 4:02:57 PM				
Ontiveros, Guadalupe									
Please enclose the softball dug outs with windscreens or anything that can protect the girls from the elements. (coach Heddleston, softball)									
Mireya Meza									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS									
146651		Hallway/Corridor			1/25/2016		24		\$0.00
Medium	Work In Progress				1/25/2016 8:48:04 AM				
Ortiz, Alfredo		Need to replace filters in all Computer rooms and cyber cafe.							
Alfredo Ortiz									
146864	H-Wing				1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 3:44:13 PM				
Carbajal, Jimmy		Attention to Jimmy Custodial Supervisor Need to replace tile in Gym. Also on the Hallway tile baseboard.							
Alfredo Ortiz									
142695					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:02 AM				
Orozco, Daniel		Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
147136					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:52:05 AM				
Apodaca, Mario		Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
143601					11/15/2015		95		\$0.00
Medium	Work In Progress				11/15/2015 12:27:52				
Flores, Pete		Yearly - Chaparral HS M-0405 (Z-Track) Grounds - Refer to PM schedule details.							
Margret Villalobos									
141762	Pre-K	Roof			10/15/2015		126		\$0.00
Medium	Work In Progress				10/15/2015 10:17:47				
Solis, Lorenz		Need to replace condenser fan motor.							
Alfredo Ortiz									
147630					2/9/2016		9		\$0.00
Medium	Work In Progress				2/9/2016 10:21:08 AM				
Solis, Lorenz		Need to replace burn out GEO thermal pump in Q-Building.							
Alfredo Ortiz									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
147467		Athletic Field			2/5/2016		13		\$0.00
Medium	Work In Progress				2/5/2016 8:50:18 AM				
Ontiveros, Guadalupe		Need to install a new gate on softball field to keep students from damaging batting cages nets. with locks.							
Alfredo Ortiz									
145600					1/5/2016		44		\$0.00
Medium	Work In Progress				1/5/2016 7:03:16 AM				
Vallejo, Albert		Repair broken bleacher modules.							
Albert Vallejo									
Count: 51 Work Orders		Avg. Age of WO's 63			Total for Chaparral HS			0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral MS							
143314					11/9/2015		101		\$0.00
Medium	Work In Progress				11/9/2015 2:22:11 PM				
Vallejo, Albert		Create pad for dumpsters in bus turnaround.							
Albert Vallejo									
146836					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 10:57:42 AM				
Vallejo, Albert		Construct wall to surround dumpsters in bus turnaround.							
Albert Vallejo									
139646	Main Building	Kitchen			9/9/2015		162		\$0.00
Medium	Work In Progress				9/9/2015 11:47:14 AM				
Estrada, Jesus		Anti slip tile is coming up under the sink and mixers. This happened after the kitchen flooded.							
Jesus Estrada									
145621	Main Building	Classroom			1/5/2016		44		\$0.00
Medium	Work In Progress	P-5			1/5/2016 12:02:58 PM				
Carbajal, Jimmy		Tiles in Nurse's office breaking and lifting from floor. Please repair							
Gidget Mora									
139414					9/6/2015		165		\$0.00
Medium	Work In Progress				9/6/2015 12:34:05 AM				
Flores, Pete		Monthly - CHM-UV-0514 PM Service - Refer to PM schedule details.							
Margret Villalobos									
147254		Custodial			2/2/2016		16		\$0.00
Medium	Work In Progress				2/2/2016 10:28:33 AM				
Carbajal, Jimmy		senesecita che car aspiradora salio umo del motor y siesposible cambiar el cordon electric #f07c000007 GRACIAS							
M. Carmen Perez									
147260					2/2/2016		16		\$0.00
Medium	Work In Progress				2/2/2016 11:48:01 AM				
Ontiveros, Joe		Small (Blue) motor pump hooked up to the Fire Sprinkler System in the Mechanical Room is Leaking Water.							
Johnny Acuna									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
144644		Office			12/8/2015		72		\$0.00
Medium	Work In Progress				12/8/2015 11:19:35 AM				
Chavez, Santos		senesecita remplasar lus de la entrada de la office de administration GRACIAS							
M. Carmen Perez									
145618	Main Building	Portables			1/5/2016		44		\$0.00
Medium	Work In Progress	P-5			1/5/2016 11:52:55 AM				
Quinones, Paul		Wall paper in bathroom torn and coming off the wall							
Gidget Mora									
147918					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 9:57:54 AM				
Quinones, Paul		Requesting flatbed to transport items from track meet back to CMS on Tuesday							
Gidget Mora									
147178	Main Building	Classroom			2/1/2016		17		\$0.00
Medium	Work In Progress	306			2/1/2016 10:19:18 AM				
Quinones, Paul		Please replace ceiling tile							
Gidget Mora									
139807		Hallway/Corridor			9/11/2015		160		\$0.00
Medium	Work In Progress				9/11/2015 12:42:35 PM				
Quinones, Paul		senesecita remplasar focos que no prenden en el lobby GRACIAS							
M. Carmen Perez									
139808		Hallway/Corridor			9/11/2015		160		\$0.00
Medium	Work In Progress				9/11/2015 12:47:37 PM				
Quinones, Paul		senesecita poner lampara que no prende y arreglar switch del hallway del lobby GRACIAS							
M. Carmen Perez									
136489		Portables			7/27/2015		0		\$0.00
Medium	Work In Progress				7/27/2015 9:26:41 AM	7/27/2015			
Quinones, Paul		senesecita replace broken tiles and portables # 5 GRACIAS				7-27-15			
M. Carmen Perez									
138787					8/26/2015		176		\$0.00
Medium	Work In Progress				8/26/2015 3:04:42 PM				
Gonzalez, Salvador		Need to make and install 4 sets of ladders to different sections of Chaparral Middle School rooftop.							
Johnny Acuna									
2/18/2016 11:23:46 AM									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral MS							
139031		Classroom			8/31/2015		171		\$0.00
Medium	Work In Progress	305			8/31/2015 10:34:06 AM				
Acuna, Johnny		Please anchor smartboard to wall							
Gidget Mora									
136119	Main Building	Classroom			7/20/2015		213		\$0.00
Medium	Work In Progress	p-14			7/20/2015 1:24:35 PM				
Acuna, Johnny		please fill holes in wall							
Gidget Mora									
136120	Main Building	Classroom			7/20/2015		213		\$0.00
Medium	Work In Progress	101			7/20/2015 1:25:55 PM				
Acuna, Johnny		Please mount SMART Board on the wall							
Gidget Mora									
143100	Main Building	Cafeteria			11/5/2015		105		\$0.00
Medium	Work In Progress				11/5/2015 8:51:22 AM				
Acuna, Johnny		Please hang banner in the cafeteria to the right of the TV							
Gidget Mora									
146369					1/19/2016		30		\$0.00
Medium	Work In Progress				1/19/2016 3:12:14 PM				
Appelzoller, Fred		Need to repair 4" or 6" backflow preventer. Leaking water.							
Johnny Acuna									
146990					1/29/2016		20		\$0.00
Medium	Work In Progress				1/29/2016 12:31:45 PM				
Chavez, Santos		Need to install new hand dryer to Girls locker room at CMS							
Johnny Acuna									
147054					1/31/2016	2/3/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:03 AM				
Quinones, Paul		Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
145359					1/3/2016	1/24/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:44:02 AM				
Vallejo, Albert		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PMschedule details.							
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
147085					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:27 AM				
Acuna, Johnny		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
147087					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:29 AM				
Acuna, Johnny		Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
147088					1/31/2016	3/2/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:30 AM				
Acuna, Johnny		Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
142700					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:05 AM				
Orozco, Daniel		Monthly - Chapparal MS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
147084					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:27 AM				
Quinones, Paul		Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
145311					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:21 AM				
Acuna, Johnny		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
147152					1/31/2016	2/6/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:52:17 AM				
Quinones, Paul		Monthly - Chaparral MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
147733	Main Building				2/10/2016		8		\$0.00
Medium	Work In Progress	office			2/10/2016 3:20:03 PM				
Marquez, Gerardo please re-keygroundsmans new office and 2 extras for keybox and custodial									
Gidget Mora									
146109					1/12/2016		37		\$0.00
Medium	Work In Progress				1/12/2016 3:54:22 PM				
Chavez, Santos Need to relocate electrical outlet to restroom in SPED classroom at CMS.									
Johnny Acuna									
143669	Main Building	Classroom			11/16/2015		94		\$0.00
Medium	Work In Progress	404			11/16/2015 3:49:48 PM				
Chavez, Santos Please install electrical outlet in ceiling in order to plug in Projector for power									
Gidget Mora									
147258					2/2/2016		16		\$0.00
Medium	Work In Progress				2/2/2016 11:31:18 AM				
Acuna, Johnny Need 1 video surveillance sign for CMS									
Johnny Acuna									
144180	Main Building	Classroom			12/2/2015		78		\$0.00
Medium	Work In Progress	408			12/2/2015 10:20:14 AM				
Acuna, Johnny Exhaust not working, vent not working									
Gidget Mora									
147562	Main Building	Classroom			2/8/2016		10		\$0.00
Medium	Work In Progress	205			2/8/2016 11:35:27 AM				
Acuna, Johnny Please replace the light bulbs in classroom									
Gidget Mora									
146062					1/12/2016		37		\$0.00
Medium	Work In Progress				1/12/2016 1:59:23 PM				
Acuna, Johnny Need 10 exit signs only for CMS									
Johnny Acuna									
Count: 37 Work Orders			Avg. Age of WO's 68		Total for Chaparral MS			0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Pride HS

145373 1/3/2016 46 \$0.00

Medium Work In Progress 1/3/2016 12:44:14 AM

Ronquillo, Ruben Monthly - Desert Pride - (Qtrly) Fitness Equipment - Refer to PM schedule details.

Margret Villalobos

138187 Portables 8/18/2015 184 \$0.00

Medium Work In Progress room #19 8/18/2015 5:32:16 AM

Solis, Lorenzo a/c not cooling need to be serviced asap.

David Acosta

137898 Portables 8/13/2015 189 \$0.00

Medium Work In Progress room #19 8/13/2015 5:24:27 AM

Ambriz, Jose a/c unit not cooling (asap).

David Acosta

147342 2/3/2016 15 \$0.00

Medium Work In Progress 2/3/2016 2:19:19 PM

Ontiveros, Joe
 Company: CARVER ELECTRIC
 Main Contact Phone: (575) 527-2127
 Address: PO BOX 1469
 Secondary Phone: (575)-644-4313
 MESILLA PARK, NM 88047
 Main Contact Email: carver@carverelectric.com
 Company Phone: (575) 527-2127
 Alternate Contact: DANEIL CARVER
 Alternate Contact Phone: (575)-649-9142
 Main Contact: BOBBY CARVER

LOCATE PER THE WORK PLAN

Dominique Esparza

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

Location:	Desert Pride HS								
147922					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 10:54:27 AM				
Chavez, Santos	Company: CARVER ELECTRIC Main Contact Phone: (575) 644-4313 Address: PO BOX 1469 City, St, Zip: MESILLA PARK, NM 88047 Main Contact Email: carver@carverelectric.com CompanyPhone: (575) 527-2127 Alternate Contact: DANEIL CARVER Alternate Contact Phone: (575)-649-9142 Main Contact: BOBBY CARVER								
	Spotting Instructions LOCATE PER THE WORK PLAN Remarks REAFFIRM - TICKET #16FE020123								

Dominique Esparza									
147921					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 10:25:02 AM				
Ontiveros, Joe	Company: Caliper Construction Main Contact Phone: (575) 635-8919 Address: 2000 S Valley Dr City, St, Zip: Las Cruces, NM88005 Main Contact Email: blanca@caliperconstoom CompanyPhone: (575) 635-8919 Alternate Contact: Blanca Cruz Company Fax: (575) 647-5197 Alternate Contact Phone: (575) 635-8919 Main Contact: Fernie Reyes								
	SPOT WITHIN WHITE MARKS LOCATED ON THE N SIDE OF SCHOOL								

Dominique Esparza

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location:	Desert Pride HS								
147923					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 10:54:38 AM				
Ontiveros, Joe	Company: CARVER ELECTRIC								
	Main Contact Phone: (575) 644-4313								
	Address: PO BOX 1469								
	City, St, Zip: MESILLA PARK, NM 88047								
	Main Contact Email: carver@carverelectric.com								
	CompanyPhone: (575) 527-2127								
	Alternate Contact: DANEIL CARVER								
	Alternate Contact Phone: (575)-649-9142								
	Main Contact: BOBBY CARVER								
	Spotting Instructions								
	LOCATE PER THE WORK PLAN								
	Remarks								
	REAFFIRM - TICKET #16FE020123								

Dominique Esparza									
147919					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 10:22:17 AM				
Chavez, Santos	Company: Caliper Construction								
	Main Contact Phone: (575) 635-8919								
	Address: 2000 S Valley Dr								
	City, St, Zip: Las Cruces, NM88005								
	Main Contact Email: blanca@caliperconstoom								
	CompanyPhone: (575) 635-8919								
	Alternate Contact: Blanca Cruz								
	Company Fax: (575) 647-5197								
	Alternate Contact Phone: (575) 635-8919								
	Main Contact: Fernie Reyes								
	SPOT WITHIN WHITE MARKS LOCATED ON THE N SIDE OF SCHOOL								

Dominique Esparza									
147920					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 10:23:24 AM				
Chavez, Santos	Company: Caliper Construction								
	Main Contact Phone: (575) 635-8919								
	Address: 2000 S Valley Dr								
	City, St, Zip: Las Cruces, NM88005								
	Main Contact Email: blanca@caliperconstoom								
	CompanyPhone: (575) 635-8919								
	Alternate Contact: Blanca Cruz								
	Company Fax: (575) 647-5197								
	Alternate Contact Phone: (575) 635-8919								
	Main Contact: Fernie Reyes								
	SPOT WITHIN WHITE MARKS LOCATED ON THE N SIDE OF SCHOOL								

Dominique Esparza									
2/18/2016 11:23:46 AM									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Pride HS							
146136		Gym			1/13/2016		36		\$0.00
Medium	Work In Progress	inside			1/13/2016 10:09:56 AM				
Ronquillo, Ruben		Need to reinstall stationary punching bags that came loose from gym floor.							
David Acosta									
146139		Gym			1/13/2016		36		\$0.00
Medium	Work In Progress	Boxing ring			1/13/2016 10:37:04 AM				
Ronquillo, Ruben		There is still a gap on the boxing ring platform that still a trip hazard and a safety issue.							
David Acosta									
146375					1/19/2016		30		\$0.00
Medium	Work In Progress				1/19/2016 3:38:48 PM				
Ontiveros, Joe		Need to check restroom on DP thank you							
Sebastian Diaz									
143101		Portables			11/5/2015		105		\$0.00
Medium	Work In Progress	room 5			11/5/2015 9:04:12 AM				
Chavez, Santos		Night light does not turn on.							
David Acosta									
143102		Portables			11/5/2015		105		\$0.00
Medium	Work In Progress	room #18			11/5/2015 9:05:38 AM				
Chavez, Santos		Night light does not turn on.							
David Acosta									
138929		Portables			8/28/2015		174		\$0.00
Medium	Work In Progress	portables			8/28/2015 10:22:55 AM				
Chavez, Santos		Electrician needed to wire for dual boards installed in several portables. (portables 1,4,7,8,9,12,15,16,18 & 19.)							
Maria Carbajal									
139620		Portables			9/9/2015		162		\$0.00
Medium	Work In Progress	room #18			9/9/2015 5:20:08 AM				
Chavez, Santos		Two light fixtures that need to be check. one flicking and the other does not turn on.							
David Acosta									
147555		Office			2/8/2016		10		\$0.00
Medium	Work In Progress	patio door			2/8/2016 9:56:29 AM				
Marquez, Gerardo		Having trouble with cylinder unlocking door.							
David Acosta									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Desert Pride HS							
147693		Portables			2/10/2016		8		\$0.00
Medium	Work In Progress	room 1			2/10/2016 5:21:32 AM				
Solis, Lorenzo		Need to replace thermostat							
David Acosta									
145334					1/3/2016	1/24/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:40 AM				
Vallejo, Albert		Monthly - Desert Pride Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
Count: 19 Work Orders		Avg. Age of WO's		61	Total for Desert Pride HS			0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail ES							
136190		Custodial			7/21/2015		212		\$0.00
Medium	Work In Progress				7/21/2015 11:06:40 AM				
Estrada, Jesus		Buenos dias Chuy, el piso de los Banos de kinder se necesita remplasar . Num de clases 201, 202, 203, 204, 205, 206, 207, 208, y el bano de la cocina tambien se necesita remplasar gracias							
Laura Sandoval									
138576					8/24/2015		178		\$0.00
Medium	Work In Progress				8/24/2015 11:02:21 AM				
Acuna, Johnny		Need 2 4500 master cool media pads for portable #418 and 419							
Johnny Acuna									
142559					10/29/2015		112		\$0.00
Medium	Work In Progress				10/29/2015 1:56:57 PM				
Acuna, Johnny		Need Heating season filters for Desert Trail....							
Johnny Acuna									
135927					7/15/2015		218		\$0.00
Medium	Work In Progress				7/15/2015 11:48:40 AM				
Estrada, Jesus		Need to replace VCT tile in the bus lobby entrance right in front of main doors. Also, need to fill in and level out holes on this section where the tile will be replaced. Size of Area: 7' L X 11' W							
Laura Sandoval									
147538					2/7/2016	2/23/2016	11		\$0.00
Medium	Work In Progress				2/7/2016 12:31:59 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
147702		Custodial			2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 8:57:13 AM				
Carbajal, Jimmy		Buenos Dias . la Aspiradora num .0214 la extencion esta fallando se apaga de repente la puede revisar por favor .Gracias							
Laura Sandoval									
147696		Custodial			2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 7:44:16 AM				
Carbajal, Jimmy		Buenos Dias . La aspiradora num .0056 el jendel no se detiene yno apira bien por favor de revisarla gracias							
Laura Sandoval									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail ES							
147694		Custodial			2/10/2016		8		\$0.00
Medium	Work In Progress			2/10/2016 7:31:05 AM					
Carbajal, Jimmy	Buenos Dias . la aspiradora num. 1162 se le callo la llanta y tira la basura por el motor por favor puede revisarla .Gracias								
Laura Sandoval									
144656					12/8/2015		72		\$0.00
Medium	Work In Progress			12/8/2015 2:07:59 PM					
Ronquillo, Ruben	5th grade computer lab needs large blinds for the windows, students unable to see with so much light coming in.								
Elizabeth Hernandez									
139805					9/11/2015		160		\$0.00
Medium	Work In Progress			9/11/2015 12:01:57 PM					
Carrasco, Danny	Need unleaded fuel for worktruck #192								
Johnny Acuna									
144870					12/11/2015		69		\$0.00
Medium	Work In Progress			12/11/2015 11:39:29					
Chavez, Santos	SERVING LINE- ELECTRICAL OUTLET BOX NEEDS TO BE REPLACED SNP MANAGER PAT C. 824.3822								
Maritza Gonzalez									
139225					9/2/2015		169		\$0.00
Medium	Work In Progress			9/2/2015 3:22:30 PM					
Acuna, Johnny	Water Seal new portable ramps with wood boards.								
Johnny Acuna									
135165					7/1/2015		232		\$0.00
Medium	Work In Progress			7/1/2015 7:43:14 AM					
Solis, Lorenzø	Need Refrigeration unit for new computer classroom. RM. 304								
Johnny Acuna									
147257					2/2/2016		16		\$0.00
Medium	Work In Progress			2/2/2016 11:30:44 AM					
Acuna, Johnny	Need 1 video surveliance sign for Desert Trail.								
Johnny Acuna									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Desert Trail ES									
138686					8/25/2015		177		\$0.00
Medium	Work In Progress				8/25/2015 2:08:42 PM				
Acuna, Johnny	Need 1" Sch. 40 Pvc line and 1" Pvc parts to continue with irrigation water line install in front of main building at Desert Trail.								
Johnny Acuna									
143078					11/4/2015		106		\$0.00
Medium	Work In Progress				11/4/2015 3:55:48 PM				
Orozco, Daniel	FAUCET TO SALAD SINK IS LEAKING. SNP MANAGER PAT C.8243822								
Maritza Gonzalez									
145771					1/7/2016		42		\$0.00
Medium	Work In Progress				1/7/2016 8:52:18 AM				
Orozco, Daniel	SKILLET IS NOT WORKING PROPERLY. SNP MANAGER PAT C. 824.3822								
Maritza Gonzalez									
147715					2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 12:20:58 PM				
Orozco, Daniel	OVEN NOT WORKING PROPERLY.ARLENE M. 824.3822								
Maritza Gonzalez									
147957					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 3:52:18 PM				
Appelzoller, Fred	Need to replace faucets in the north 100 hallway.								
Johnny Acuna									
145312					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:22 AM				
Acuna, Johnny	Yearly - Desert Trail ES - Backflow Inspection - Refer to PMschedule details.								
Margret Villalobos									
142701					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:06 AM				
Orozco, Daniel	Monthly - Desert Trail ES - Range Hood Cleaning - Refer to PMschedule details.								
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail ES

147064 1/31/2016 2/8/2016 18 \$0.00

Medium Work In Progress 1/31/2016 12:51:11 AM

Acuna, Johnny Monthly - Desert Trail ES- Emer Light Insp:Monthly - Refer to PM schedule details.

Margret Villalobos

147065 1/31/2016 2/8/2016 18 \$0.00

Medium Work In Progress 1/31/2016 12:51:12 AM

Acuna, Johnny Monthly - Desert Trail ES - Exit Sign Insp:Monthly - Refer to PM schedule details.

Margret Villalobos

147066 1/31/2016 18 \$0.00

Medium Work In Progress 1/31/2016 12:51:12 AM

Acuna, Johnny Monthly - Desert Trail ES - Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

145360 1/3/2016 1/24/2016 46 \$0.00

Medium Work In Progress 1/3/2016 12:44:03 AM

Vallejo, Albert Monthly - Desert Trail ES - Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

147157 1/31/2016 2/6/2016 18 \$0.00

Medium Work In Progress 1/31/2016 12:52:21 AM

Acuna, Johnny Monthly - Desert Trail ES - Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

146977 1/29/2016 20 \$0.00

Medium Work In Progress 1/29/2016 9:24:02 AM

Chavez, Santos Need 10 replacement hand dryers for Desert Trail Elementary Restrooms. Make: World Dryer, Model: WA 126, Serial: 90332, 120 volts, 17A

Johnny Acuna

145755 1/6/2016 43 \$0.00

Medium Work In Progress 1/6/2016 4:01:51 PM

Chavez, Santos First Priority Please: (Security light Pole next to kinder playground equipment) Need to disconnect electrical and remove security light pole. Pole has massive rust eating through the pole. (Safety Hazard)

Johnny Acuna

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail ES

147783 2/11/2016 7 \$0.00

Medium Work In Progress 2/11/2016 8:29:55 AM

Marquez, Gerardo Please clean out or re-do cylinder lock to Kitchen main door going outdoors (Green Door). Manager having a hard time trying to lock and unlock door cylinder. (Cylinder gets stuck when unlocking). Tried lubricating cylinder, but still having trouble. Contact: Johnny Acuña for Info.

Johnny Acuna

146912 1/28/2016 21 \$0.00

Medium Work In Progress 1/28/2016 12:01:16 PM

Solis, Lorenzø Need to order and replace (2) SIDEDRAFT 4500 Evap. Coolers for Portable #418 and Portable #419

Johnny Acuna

146911 1/28/2016 21 \$0.00

Medium Work In Progress 1/28/2016 11:53:34 AM

Gonzalez, Salvador Please fabricate stand for new refrigeration unit (roof install) to room #304 (computer room)

Johnny Acuna

146910 1/28/2016 21 \$0.00

Medium Work In Progress 1/28/2016 11:51:13 AM

Flores, Pete walk-behind trencher. Need to replace busted pull cord from machine.

Johnny Acuna

145716 1/6/2016 43 \$0.00

Medium Work In Progress 1/6/2016 2:49:35 PM

Acuna, Johnny Need window blinds for portable classrooms #405, #406, #424, and #425 (98" Wide X 39" Long) Qty. 4 (34" Wide X 63" Long) Qty. 4

Johnny Acuna

145717 1/6/2016 43 \$0.00

Medium Work In Progress 1/6/2016 2:52:18 PM

Acuna, Johnny Need Aluminum window blinds for portable #422 and #423 (94" Wide X 34" Long) Qty. 1 (46" Wide X 33" Long) Qty. 1

Johnny Acuna

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To	Description		Action Taken							
Requester Name										
Location:		Desert Trail ES								
146060					1/12/2016		37		\$0.00	
Medium	Work In Progress				1/12/2016 1:56:11 PM					
Acuna, Johnny	Need (15) 4L-210 Notched fan belts and (15) 4L-220 Notched fan belts for CMS and Desert Trail Exhaust fan units.									
Johnny Acuna										
146061					1/12/2016		37		\$0.00	
Medium	Work In Progress				1/12/2016 1:57:52 PM					
Acuna, Johnny	Need Lamp covers for light fixtures at Desert Trail. (Sent lamp cover samples to PPD)									
Johnny Acuna										
Count: 36 Work Orders		Avg. Age of WO's	66	Total for Desert Trail ES			0	\$0.00		

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
143709					11/17/2015		93		\$0.00
Medium	Work In Progress				11/17/2015 2:36:41 PM				
Ontiveros, Guadalupe		Principal Araujo, is requesting for someone to come and paint the basketball lines on the basketball courts							
Ruben Ortiz									
145861					1/8/2016		41		\$0.00
Medium	Work In Progress				1/8/2016 9:19:46 AM				
Gonzalez, Salvador		Need stoppers for the swing gates on the southwest of the school; to stop them from swing							
Ruben Ortiz									
147781		Office			2/11/2016		7		\$0.00
Medium	Work In Progress	Front Office			2/11/2016 8:16:27 AM				
Lara, Ralph		Need keys made for desks in the office. (Gonzalez)							
Guadalupe Gonzalez									
147050					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:00 AM				
Ortiz, Ruben		Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
147051					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:01 AM				
Ortiz, Ruben		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
147052					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:02 AM				
Ortiz, Ruben		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
147053					1/31/2016	2/6/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:02 AM				
Ortiz, Ruben		Monthly - Desert View ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
147544					2/7/2016	2/23/2016	11		\$0.00
Medium	Work In Progress				2/7/2016 12:32:03 AM				
Ortiz, Ruben		Monthly - Desert View ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
142702					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:07 AM				
Orozco, Daniel		Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
142525					10/28/2015		113		\$0.00
Medium	Work In Progress				10/28/2015 4:14:04 PM				
Castillo, Carlos		provide additional lighting to south side of mobile home				10/30/15 Asp Albert, route to Cali			
Alfredo Holguin									
145858					1/8/2016		41		\$0.00
Medium	Work In Progress				1/8/2016 9:16:38 AM				
Ortiz, Ruben		Mr. Araujo signs on the door to let visitors know to sign in the front office							
Ruben Ortiz									
147329		Classroom			2/3/2016		15		\$0.00
Medium	Work In Progress	Rm. 131			2/3/2016 12:07:04 PM				
Ortiz, Ruben		Assemble a pocket chart stand. (Perez)							
Guadalupe Gonzalez									
147927					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 3:15:09 PM				
Carrasco, Danny		Need 15 gals of gas for #61 Truck and 5 gals for 402 Mower Thank you Ruben							
Ruben Ortiz									
147787		Custodial			2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 9:17:48 AM				
Carrasco, Danny		We are in need of a wheelbarrow the one that we had broke. In the upcoming months it will get windy and the sidewalks get filled with a lot of sand.							
Israel Ortega									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Desert View ES							
146751		Custodial			1/26/2016		23		\$0.00
Medium	Work In Progress				1/26/2016 10:08:08 AM				
Carbajal, Jimmy		Vacuum cleaner #20002017 is not working and needs to be repaired. Thank you							
Israel Ortega									
Count: 15 Work Orders		Avg. Age of WO's	36			Total for Desert View ES	0		\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
147801					2/11/2016		7		\$0.00
Medium	Work In Progress			2/11/2016 1:42:29 PM					
Vega, David	...as per Ray L. For the POA center in the portable at the Anthony Pre-K: To add: Paper towel dispenser in the women's restroom and Paper towel dispenser in the sink area. Thank you.								
Esteban Rosas									
145952					1/10/2016	1/26/2016	39		\$0.00
Medium	Work In Progress			1/10/2016 12:28:09 AM					
Moncayo, Fernando	Monthly - GAC Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
147537					2/7/2016	2/23/2016	11		\$0.00
Medium	Work In Progress			2/7/2016 12:31:58 AM					
Moncayo, Fernando	Monthly - GAC Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
142715					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress			11/1/2015 12:54:15 AM					
Orozco, Daniel	Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
142724					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress			11/1/2015 12:54:21 AM					
Vallejo, Albert	Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
145361					1/3/2016	1/24/2016	46		\$0.00
Medium	Work In Progress			1/3/2016 12:44:04 AM					
Vallejo, Albert	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
147144					1/31/2016	2/6/2016	18		\$0.00
Medium	Work In Progress			1/31/2016 12:52:11 AM					
Moncayo, Fernando	Monthly - GAC Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		GAC							
143696					11/17/2015		93		\$0.00
Medium	Work In Progress	FEDERAL			11/17/2015 9:31:30 AM				
Moncayo, Fernando		HANG PICTURE FRAME IN OFFICE.							
Noemi Duron									
146661					1/25/2016		24		\$0.00
Medium	Work In Progress	FEDRAL			1/25/2016 11:11:04 AM				
Moncayo, Fernando		LIGHT BULB IN OFFICE-A IS FLICKERING.							
Noemi Duron									
147931		Office			2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 3:29:00 PM				
Gonzales, Camilo		Deliver 100 boxes. PO# 151604288. Attn: Cora Ramirez, Technology Department. Thank you.							
Theresa Ramirez									
141701					10/14/2015		127		\$0.00
Medium	Work In Progress				10/14/2015 3:17:10 PM				
Ambriz, Jose		backup units to server room very noisy and old							
Fernando Moncayo									
142171					10/22/2015		119		\$0.00
Medium	Work In Progress				10/22/2015 3:34:48 PM				
Holguin, Alfredo		Please repair damage to (8) A/C units from hailstorm.							
Albert Vallejo									
147473					2/5/2016		13		\$0.00
Medium	Work In Progress				2/5/2016 11:31:15 AM				
Lara, Ralph		Wanting to place an Auto-Door closer on the door in the Reception area[B-wing](HR section).							
Esteban Rosas									
139283					9/3/2015		168		\$0.00
Medium	Work In Progress				9/3/2015 10:21:09 AM				
Ambriz, Jose		Server room at GAC is warm							
		please check ASAP							
Cora Ramirez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
147804					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 1:48:54 PM				
Marquez, Gerardo		...as per Ray L. For the POA center in the portable at the Anthony Pre-K. To re-key two large black cabinets. Thank you.							
Esteban Rosas									
146684		Electrical Room			1/25/2016		24		\$0.00
Medium	Work In Progress				1/25/2016 3:35:14 PM				
Castillo, Carlos		CLEAN, ORGANIZE AND INVENTORY ELECTRICAL STORAGE SHED							
Carlos Castillo									
146680					1/25/2016		24		\$0.00
Medium	Work In Progress				1/25/2016 3:20:50 PM				
Castillo, Carlos		Can we get a work order for lights in the hallway by the Superintendents file room (C-wing). More details with Elisa Saenz.							
Esteban Rosas									
145521					1/4/2016		45		\$0.00
Medium	Work In Progress				1/4/2016 9:47:52 AM				
Castillo, Carlos		moving the copier from Calixto Office into computer tech office. Need electrical outlet in new office							
Cora Ramirez									
146363					1/19/2016		30		\$0.00
Medium	Work In Progress				1/19/2016 1:08:15 PM				
Moncayo, Fernando		...to check 'All loose tiles' in B-wing (Finance and HR) and C-wing. ...as per Mr. Efren Yturalde. Thank you.							
Esteban Rosas									
135227					7/2/2015		231		\$0.00
Medium	Work In Progress				7/2/2015 2:31:29 PM				
Moncayo, Fernando		SNP Vehicle # 177 needs to be cleaned out and organized.							
Maritza Gonzalez									
147248		Kitchen			2/2/2016		16		\$0.00
Medium	Work In Progress				2/2/2016 7:51:33 AM				
Moncayo, Fernando		Top Oven was making a clicking noise than completely stopped working							
Dino Facio									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
145250					12/18/2015		62		\$0.00
Medium	Work In Progress				12/18/2015 8:19:00 AM				
Orozco, Daniel		STEAM LINE IS LEAKING. SNP MANAGER IRMA S. 882.6784							
Maritza Gonzalez									
145314					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:23 AM				
Moncayo, Fernando		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
147062					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:09 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
147063					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:10 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
Count: 25 Work Orders			Avg. Age of WO's	56		Total for GAC	0		\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC - Pre-K									
145795		Classroom			1/7/2016		42		\$0.00
Medium	Work In Progress	201			1/7/2016 2:18:45 PM				
Moncayo, Fernando		please remove door stops that are bolted to the floor in room 201							
Leticia Tangonan									
146053		Classroom			1/12/2016		37		\$0.00
Medium	Work In Progress	201			1/12/2016 11:09:17 AM				
Moncayo, Fernando		could you please cut one of the hook racks and move it down lower to accommodate one of our sped students in room 201-see Ms. viola							
Leticia Tangonan									
146438		Classroom			1/20/2016		29		\$0.00
Medium	Work In Progress	103			1/20/2016 1:42:00 PM				
Moncayo, Fernando		please replace light bulb in classroom bathroom in room 103							
Leticia Tangonan									
146577		Classroom			1/22/2016		27		\$0.00
Medium	Work In Progress	203			1/22/2016 8:36:05 AM				
Moncayo, Fernando		cabinet door in room 203 is hanging off hinge							
Leticia Tangonan									
147177		Foyer			2/1/2016		17		\$0.00
Medium	Work In Progress				2/1/2016 9:36:57 AM				
Moncayo, Fernando		Could you please add light bulbs to our front entrance hallway by the office.							
Leticia Tangonan									
146753		Office			1/26/2016		23		\$0.00
Medium	Work In Progress	computer room			1/26/2016 10:25:30 AM				
Moncayo, Fernando		please move shelves in office computer room to the other side of the wall. See Letty or Amanda in office for further instructions							
Leticia Tangonan									
139652					9/9/2015		162		\$0.00
Medium	Work In Progress				9/9/2015 12:40:15 PM				
Moncayo, Fernando		NO ELECTRICITY IN PRE-K.							
Maritza Gonzalez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC - Pre-K									
136470		Classroom			7/24/2015		209		\$0.00
Medium	Work In Progress	all			7/24/2015 4:49:52 PM				
Rodriguez, Arturo		Carpets in all 6 classrooms need to be vacuumed and shampooed before kids start school. Please see teachers for specific carpets that need cleaning.							
Leticia Tangonan									
136187		Cafeteria			7/21/2015		212		\$0.00
Medium	Work In Progress	lounge			7/21/2015 9:47:47 AM				
Rodriguez, Arturo		please clean floors in our lounge-(mop)							
Leticia Tangonan									
140226		Kitchen			9/18/2015		153		\$0.00
Medium	Work In Progress				9/18/2015 1:46:43 PM				
Miranda, Danny		GAC Pre-K kitchen -build a wall to separate the kitchen and dining room.							
Albert Vallejo									
Count: 10 Work Orders		Avg. Age of WO's 91			Total for GAC - Pre-K			0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden ES							
146979		Storage			1/29/2016		20		\$0.00
Medium	Work In Progress				1/29/2016 9:39:44 AM				
Gonzales, Camilo		Need to transfer tables from GES to Alta Vista Annex....Per Ms. Marquez greatly appreciate your assistance in this matter...thank you...							
Loraine Gandara									
142716					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:16 AM				
Orozco, Daniel		Monthly- Gadsden ES - Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
147170					2/1/2016		17		\$0.00
Medium	Work In Progress				2/1/2016 9:09:38 AM				
Ontiveros, Joe		Mid Wing Mechanical Room - Backflow is leaking.							
Joe Ontiveros									
142949					11/3/2015		107		\$0.00
Medium	Work In Progress	Conference			11/3/2015 9:26:50 AM				
Gallegos, Rafael		need immediate assistance for leak in roof...water coming in greatly appreciate assistance...							
Loraine Gandara									
147866		Mechanical			2/12/2016		6		\$0.00
Medium	Work In Progress				2/12/2016 2:26:45 PM				
Villalobos, David		Install front cover to water heater boiler as p the boiler inspector							
David Villalobos									
136579					7/28/2015		205		\$0.00
Medium	Work In Progress	Playground			7/28/2015 10:29:22 AM				
Ontiveros, Guadalupe		please provide us with four trees in front of the school....							
		Arborvitae Blue Cone Plant Type: Evergreen, Mature Size: 20' tall x 12 ' wide Exposure Full sun part shade, space 6-10 feet apart. Water- moderate .							
Loraine Gandara									
147708		Mechanical			2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 10:01:24 AM				
Ontiveros, Joe		Need to replace a 3/4 inch leaking back Flow preventer in Jefferson Mechanical RM.							
Joe Ontiveros									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden ES									
146931					1/28/2016		21		\$0.00
Medium	Work In Progress				1/28/2016 3:30:00 PM				
Ontiveros, Joe		Please repair water supply for washing machine in room 101 to include installing a water filter on the supply lines.							
Albert Vallejo									
147317					2/3/2016		15		\$0.00
Medium	Work In Progress	staff lounge			2/3/2016 8:17:00 AM				
Ontiveros, Joe		need assistance with our faucet in the teachers lounge....leaking quite a bit and loose...greatly appreciate your assistance in this matter....							
Loraine Gandara									
145933					1/10/2016	1/26/2016	39		\$0.00
Medium	Work In Progress				1/10/2016 12:27:54 AM				
Pinon, Jose		Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PM schedule details.							
Margret Villalobos									
139709					9/10/2015		161		\$0.00
Medium	Work In Progress				9/10/2015 7:25:13 AM				
Ontiveros, Guadalupe		Please remove trees that have died and replace with Texas Ash. Please remove the dead ones ASAP, and replant once the trees have gone dormant this fall.							
Albert Vallejo									
147536					2/7/2016	2/23/2016	11		\$0.00
Medium	Work In Progress				2/7/2016 12:31:57 AM				
Ontiveros, Joe		Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
145332					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:38 AM				
Ontiveros, Joe		Yearly - Gadsden ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
141446					10/11/2015	10/27/2015	130		\$0.00
Medium	Work In Progress				10/11/2015 12:28:53				
Pinon, Jose		Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PM schedule details.							
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden ES									
147075					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:19 AM				
Ontiveros, Joe		Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.							
Margret Villalobos									
147076					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:20 AM				
Ontiveros, Joe		Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.							
Margret Villalobos									
147072					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:17 AM				
Ontiveros, Joe		Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
146658		Classroom			1/25/2016		24		\$0.00
Medium	Work In Progress				1/25/2016 9:31:12 AM				
Chavez, Santos		need assistance with electrical work for new computer lab in room 302 greatly appreciate your assistance							
Loraine Gandara									
146983		Classroom			1/29/2016		20		\$0.00
Medium	Work In Progress	302			1/29/2016 10:29:58 AM				
Chavez, Santos		need immediate assistance for electrical work done in room 302...just converted to computer labs...greatly appreciate your assistance in this matter...							
Loraine Gandara									
147718					2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 12:52:43 PM				
Ontiveros, Joe		Nee (2) surveillance signs.							
Joe Ontiveros									
140066		Office			9/16/2015		155		\$0.00
Medium	Work In Progress	Ms. Word			9/16/2015 11:25:15 AM				
Chavez, Santos		need immediate assistance with light bulbs in Ms. Word office...would greatly appreciate your assistance in this matter....							
Loraine Gandara									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden ES									
142862		Restroom			11/2/2015		108		\$0.00
Medium	Work In Progress				11/2/2015 9:32:58 AM				
Ontiveros, Joe		need to replace all staff toilets							
Joe Ontiveros									
136580					7/28/2015		196		\$0.00
Medium	Work In Progress				7/28/2015 10:30:21 AM	2/9/2016			
Herrera, Jaime		Please provide us with mulch for the two playgrounds....greatly appreciate your assistance in this matter....							
Loraine Gandara									
Count: 23 Work Orders				Avg. Age of WO's	63		Total for Gadsden ES	0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
140867					10/4/2015		137		\$0.00
Medium	Work In Progress				10/4/2015 12:38:15 AM				
Flores, Pete		Monthly - GHS-UV-0515 PM Service - Refer to PM schedule details.							
Margret Villalobos									
147548					2/7/2016		11		\$0.00
Medium	Work In Progress				2/7/2016 12:32:06 AM				
Medina, Eric		Daily - Gadsden HS - Fire Pump (Biweekly) - Refer to PM schedule details.							
Margret Villalobos									
143602					11/15/2015		95		\$0.00
Medium	Work In Progress				11/15/2015 12:27:53				
Flores, Pete		Yearly - Gadsden HS- Mow (0408/0419/0428) Grounds - Refer to PM schedule details.							
Margret Villalobos									
142662					10/31/2015		110		\$0.00
Medium	Work In Progress				10/31/2015 12:34:37				
Sanchez, Raul		Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
144521					12/6/2015		74		\$0.00
Medium	Work In Progress				12/6/2015 12:40:32 AM				
Sanchez, Raul		Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
147037					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:50:51 AM				
Sanchez, Raul		Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
147132					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:52:03 AM				
Sanchez, Raul		Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
147906					2/14/2016		4		\$0.00
Medium	Work In Progress				2/14/2016 12:31:14 AM				
Sanchez, Raul		Monthly - Gadsden HS- Filters (Pump Rm) Quarterly - Refer to PM schedule details.							
Margret Villalobos									
143599					11/14/2015		96		\$0.00
Medium	Work In Progress				11/14/2015 12:27:49				
Sanchez, Raul		Monthly - Gadsden HS- Filters (Pump Rm) Quarterly - Refer to PM schedule details.							
Margret Villalobos									
147719	Academic Bldg				2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 12:57:47 PM				
Hernandez, Guillermo		need to remove all furniture and equipment that is in good and store at SM. Furniture and equipment that is no longer in usable condition can be left behind for demo contractor.							
Alfredo Holguin									
146821					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 8:12:15 AM				
Vallejo, Albert		Albert, the concrete slab that needs repair by the flag poles is approximately 20 ft by 15.							
Guillermo Hernandez									
147641					2/9/2016		9		\$0.00
Medium	Work In Progress				2/9/2016 1:11:58 PM				
Vallejo, Albert		Re-tile showers in boys gym locker room.							
Albert Vallejo									
146908		Athletic Field			1/28/2016		21		\$0.00
Medium	Work In Progress				1/28/2016 11:02:35 AM				
Ontiveros, Guadalupe		Requested by Coach Walker for Discus/Shot Put Cage- Check/repair and install net for track discus/shot put cage on soccer field.							
Velia Alarcon									
138687		Athletic Field			8/25/2015		177		\$0.00
Medium	Work In Progress	Baseball Field			8/25/2015 2:32:18 PM				
Vallejo, Albert		Requested by Coach Yanez for Baseball Cages on Baseball Field-Pour cement in batting cages at the baseball field.							
Velia Alarcon									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

146050					1/12/2016		37		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/12/2016 9:46:07 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Carbajal, Jimmy please i have one dolly with flat tires.

thank you

Luis Saucedo

141254		Custodial			10/8/2015		133		\$0.00
--------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/8/2015 7:39:18 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Estrada, Jesus mr. estrada is it possible to have a wheelbarrow and two square shovels to clean around the edges of sides walks.

thank you

Luis Saucedo

145511		Custodial			1/4/2016		45		\$0.00
--------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/4/2016 9:04:40 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Carbajal, Jimmy please i need (2) a 50ft of extention core. Asp Cali, need to request thru Custodial.
1/12/16

thank you

Luis Saucedo

142871					11/2/2015		108		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/2/2015 10:56:01 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Flores, Pete please the john deere gator uv-ghs-0905 flat tire from the back of passenger side not good thank you

Luis Saucedo

142432					10/27/2015		114		\$0.00
--------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/27/2015 3:49:15 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Flores, Pete Truck GHS #155. Gearshift broke and due for services.

Guillermo Hernandez

146823					1/27/2016		22		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/27/2016 8:20:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Medina, Eric Need to order (2) surveillance signs.

Eric Medina

141917		Classroom			10/19/2015		122		\$0.00
--------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	Portable # 7			10/19/2015 10:54:48				
--------	------------------	--------------	--	--	---------------------	--	--	--	--

Medina, Eric Requested Ms. Hartmann Portable # 7-Please place two shelves in bathrooms near sink for cleaning painting cups.

Velia Alarcon

2/18/2016 11:23:47 AM

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

143192 11/6/2015 104 \$0.00

Medium Work In Progress 11/6/2015 10:49:59 AM

Gonzalez, Salvador Requested by Coach Vasquez for Football Locker Room in the Boy's Gym-Extension to existing wall in equipment room.

Velia Alarcon

146662 Boys Gym 1/25/2016 24 \$0.00

Medium Work In Progress 1/25/2016 11:18:30 AM

Villalobos, David Install gang sinks in boys gym. (See Albert)

Albert Vallejo

146663 Boys Gym 1/25/2016 24 \$0.00

Medium Work In Progress 1/25/2016 11:19:21 AM

Villalobos, David Install floor drains in showers in boys gym. (See Albert)

Albert Vallejo

143088 11/5/2015 105 \$0.00

Medium Work In Progress 11/5/2015 7:01:35 AM

Villalobos, David please on the weigh room girls restrooms the sink is clogged and over flows i tried to uncloged but no luck thank you

Luis Saucedo

136037 Boys Gym 7/16/2015 217 \$0.00

Medium Work In Progress 7/16/2015 4:00:37 PM

Villalobos, David As per Mr. Giron he would like to have all the showers working. Location is locker rooms in the Boys Gym.

Guillermo Hernandez

141916 Classroom 10/19/2015 122 \$0.00

Medium Work In Progress Portable # 7 10/19/2015 10:51:52

Villalobos, David Requested by Ms. Hartmann Portable # 7-Replace very small sink and broken faucet with a laundry sink/faucet to maintain clean equipment (one restroom).

Velia Alarcon

144141 12/1/2015 79 \$0.00

Medium Work In Progress 12/1/2015 3:50:17 PM

Villalobos, David Install a small WH in portable 8

Albert Vallejo

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

140227					9/18/2015		153		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/18/2015 1:53:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Chavez, Santos Santos need to rewire outside light near panther paw light dropped and pulled out wires

Eric Medina

138008					8/14/2015		188		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/14/2015 7:21:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos Need to replace two burn out lamps on the south parking lot and around the CTE building.

Guillermo Hernandez

138952					8/28/2015		174		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/28/2015 2:15:09 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Need to replace the panic bars to back doors of the library, the alarm stopped working and they are losing books.

Guillermo Hernandez

139129		Classroom			9/1/2015		170		\$0.00
--------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	Portable # 150			9/1/2015 9:55:53 AM				
--------	------------------	----------------	--	--	---------------------	--	--	--	--

Lara, Ralph Requested by Coach Yanez for Portable # 150 (Old Intervention Portable)-Put a lock or deadbolt on the storage room door which is located inside portable # 150 towards the back of the room.

Velia Alarcon

141301		Athletic Field			10/8/2015		133		\$0.00
--------	--	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Track Field			10/8/2015 3:36:12 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Coach Walker for Track Field-Inspect track, track has bubbled at the 14 yd marker and has worn patches (x3-5). Needs to be repaired and remarked.

Velia Alarcon

139963	Pool Pump	Pump House			9/15/2015		156		\$0.00
--------	-----------	------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/15/2015 7:55:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador fabricate square tubing post to support pool canopy shade

Mario Apodaca

146501		Athletic Field			1/21/2016		28		\$0.00
--------	--	----------------	--	--	-----------	--	----	--	--------

Low	Work In Progress				1/21/2016 8:39:26 AM				
-----	------------------	--	--	--	----------------------	--	--	--	--

Carrasco, Danny we need 18 volts dewalt charger to charge battery at work sites.

Guadalupe Ontiveros

2/18/2016 11:23:47 AM

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
147348	Grounds Shop	Mechanical			2/3/2016		15		\$0.00
Medium	Work In Progress				2/3/2016 3:27:08 PM				
Apodaca, Mario wastewater treatment plant flow meter service									
Mario Apodaca									
144378	Pool Pump	Pump House			12/4/2015		76		\$0.00
Medium	Work In Progress				12/4/2015 1:55:47 PM				
Apodaca, Mario GHS NEED TO REORDER POOL WATER FILTERS									
Mario Apodaca									
140674	Main Building	Pump House			9/25/2015		146		\$0.00
Medium	Work In Progress				9/25/2015 4:01:26 PM				
Sanchez, Raul 9/25/15 Requesting a work order for the installation of chlorination equipment for the supplemental domestic well in case of emergency use									
Thanks, Raul									
Raul Sanchez									
147722					2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 1:59:33 PM				
Vallejo, Albert Requested by Coach Walker for Under Stadium Storage Rooms for Track-Create/build concrete entrance sidewalks for under stadium storage rooms (track and football).									
Velia Alarcon									
147862					2/12/2016		6		\$0.00
Medium	Work In Progress				2/12/2016 12:01:48 PM				
Gonzalez, Salvador Need to weld chain and padlock to student drop off area by the North Parking area.									
Guillermo Hernandez									
147595					2/8/2016		10		\$0.00
Medium	Work In Progress				2/8/2016 3:40:49 PM				
Gonzalez, Salvador Need to install window guard to new doors installed at the Weight room.									
Guillermo Hernandez									
145272					12/18/2015		62		\$0.00
Medium	Work In Progress				12/18/2015 11:54:03				
Orozco, Daniel DRYER BURNT APRONS MIT ETC. DRYING. SNP MANAGER FRANCES B. 882.5522									
Maritza Gonzalez									
2/18/2016 11:23:47 AM									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
147816					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 3:35:18 PM				
Escobar, David		02/11/2016. repair 2 sinks in room 207. water leaks at traps and valve connections.							
David Escobar									
147796	North Building				2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 12:02:10 PM				
Medina, Eric		need to replace broken ceiling tiles in hall way							
Eric Medina									
147795	Academic Bldg	Restroom (Girls)			2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 12:01:04 PM				
Medina, Eric		need to replace faucet in girls gang rr							
Eric Medina									
146197					1/14/2016		35		\$0.00
Medium	Work In Progress				1/14/2016 7:55:21 AM				
Medina, Eric		need to organize basement							
Eric Medina									
146997	Cafeteria (1998)				1/29/2016		20		\$0.00
Medium	Work In Progress				1/29/2016 2:10:52 PM				
Medina, Eric		Requested by Mrs. Hamilton for Cafeteria-Neet promotion posters for CTE hung in the cafeteria as per Mr. Giron. Mrs. Hamilton will collect posters from each program. Please see her for them.							
Velia Alarcon									
146655					1/25/2016		24		\$0.00
Medium	Work In Progress				1/25/2016 9:11:19 AM				
Hernandez, Guillermo		Requested by Ms. Hartmann Portable # 7-Please transport Art Boards (displays) and table to Gadsden Middle School on Feb 9th @ 8:30 a.m. and return to G.H.S. 2:30 p.m.							
Velia Alarcon									
147695					2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 7:36:59 AM				
Hernandez, Guillermo		Need to replace P-trap and unclog sink in boys restroom at the cafeteria.							
Guillermo Hernandez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
147886					2/12/2016		6		\$0.00
Medium	Work In Progress				2/12/2016 3:45:18 PM				
Hernandez, Guillermo		Need to unclog main sewer line for Administration building.							
Guillermo Hernandez									
147730	North Building	Classroom			2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 3:12:23 PM				
Hernandez, Guillermo		Requested by Ms. Schapekahn Rm. 209 North Building -Please turn down cooling class is a little cold.							
Velia Alarcon									
147417	Pool Pump	Pump House			2/4/2016		14		\$0.00
Medium	Work In Progress				2/4/2016 3:14:36 PM				
Apodaca, Mario		need 2 baby changing station for the dressing room for the new regulation							
Mario Apodaca									
144164					12/2/2015		78		\$0.00
Medium	Work In Progress				12/2/2015 6:47:00 AM				
Flores, Pete		please the john deere gator uv-ghs-0905 is making a lot of noise when driving can yuo plese see it thank you							
Luis Saucedo									
146628					1/22/2016		27		\$0.00
Medium	Work In Progress				1/22/2016 3:52:32 PM				
Flores, Pete		please the john deere gator uv-ghs-0905 is making a lot of noise when driving can yuo plese see as we needed to move furniture it thank you							
Luis Saucedo									
146829		Athletic Field			1/27/2016		22		\$0.00
Medium	Work In Progress	Track			1/27/2016 10:12:18 AM				
Ontiveros, Guadalupe		Requested by Coach Walker for Track-Repair/resurface GHS Track 4-6 spots on track are extremely cracked, worn or have holes on track surface. If/when possible track needs to be resurfaced.							
Velia Alarcon									
146493					1/21/2016		28		\$0.00
Medium	Work In Progress				1/21/2016 7:49:11 AM				
Ontiveros, Guadalupe		Need to fill the rain run-outs around campus.							
Guillermo Hernandez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

147723 New Admin Bldg 2/10/2016 8 \$0.00

Medium Work In Progress 2/10/2016 2:03:15 PM

Lara, Ralph Requested by Pam Holguin Rm. 701 Attendance Office in the Admin. Building-Lock on middle drawer fell off and right side drawer does not lock, both of these drawers are on the counter cabinet.

Velia Alarcon

145999 Varsity Gym Gym 1/11/2016 38 \$0.00

Medium Work In Progress 1/11/2016 3:41:32 PM

Castillo, Carlos Requested by Ms. L. Chavez for Varsity Gym-North side basketball score board keeps flicking on and off. This problem will need to be resolved as soon as possible since District Play will begin on Tuesday, January 19, 2016/

Velia Alarcon

147908 2/16/2016 2 \$0.00

Medium Work In Progress 2/16/2016 6:27:31 AM

Castillo, Carlos please this morning around the academic building is to dark is hard to see (safety) thank you

Luis Saucedo

144198 Classroom 12/2/2015 78 \$0.00

Medium Work In Progress Portable # 7 & 8 12/2/2015 2:45:56 PM

Villalobos, David Requested by Ms. Hartmann for Portable # 7 & 8-Please reinstall hot water heater in restroom area.

Velia Alarcon

146942 1/28/2016 21 \$0.00

Medium Work In Progress 1/28/2016 3:45:15 PM

Villalobos, David taco circulating pumps for main building need replacing

Eric Medina

147394 Athletic Field 2/4/2016 14 \$0.00

Medium Work In Progress 2/4/2016 8:16:31 AM

Gonzalez, Salvador need to weld I hook for back drop on batting cages as per coach Llenez.

Guadalupe Ontiveros

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
141599					10/13/2015		128		\$0.00
Medium	Work In Progress				10/13/2015 11:37:31				
Ontiveros, Guadalupe		Trash Dumpsters along south access road- Move one regular trash dumpster from the block enclosed area across from Tech/Ag building to the block enclosed area across from the nurse/girls gym. Call Alfredo as soon as the move is completed							
Alfredo Holguin									
146847		Athletic Field			1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 2:27:04 PM				
Holguin, Alfredo		Football field Artificial Turf - Perform SportChamp deep cleaning service, Seam Repairs and add infill Rubber							
Alfredo Holguin									
147056					1/31/2016	2/3/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:05 AM				
Medina, Eric		Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PMSchedule details.							
Margret Villalobos									
145315					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:24 AM				
Hernandez, Guillermo		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
145366					1/3/2016		46		\$0.00
Medium	Work In Progress				1/3/2016 12:44:08 AM				
Vallejo, Albert		Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PMSchedule details.							
Margret Villalobos									
147095					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:35 AM				
Medina, Eric		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
147118					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:52 AM				
Medina, Eric		Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PMSchedule details.							
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Gadsden HS							
142703					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:07 AM				
Orozco, Daniel	Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
Count: 70 Work Orders		Avg. Age of WO's	61	Total for Gadsden HS				0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Gadsden MS									
145316					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:25 AM				
Herrera, Mario	Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
140796					9/30/2015		141		\$0.00
Medium	Work In Progress				9/30/2015 12:43:19 AM				
Herrera, Mario	Monthly - Gadsden MS A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
Margret Villalobos									
140809					10/4/2015	11/4/2015	137		\$0.00
Medium	Work In Progress				10/4/2015 12:37:35 AM				
Herrera, Mario	Yearly - Gadsden MS I-4 Fan Coil Unit Yearly - Refer to PM schedule details.								
Margret Villalobos									
142704					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:08 AM				
Orozco, Daniel	Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
147036					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:50:50 AM				
Apodaca, Mario	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
145936					1/10/2016	1/26/2016	39		\$0.00
Medium	Work In Progress				1/10/2016 12:27:56 AM				
Soria, Martin	Monthly - QRTLY BLDG INSP REPORT (GM) - Refer to PM schedule details.								
Margret Villalobos									
146039	Gym	Mechanical			1/12/2016		37		\$0.00
Medium	Work In Progress				1/12/2016 8:00:16 AM				
Ontiveros, Joe	Domestic water heater in Mechanical room pressure relief valve is leaking								
Mario Herrera									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

145979 1/11/2016 38 \$0.00

Medium Work In Progress See Mr.Mora 1/11/2016 9:54:29 AM

Marquez, Gerardo Requesting an expanded metal storage with -in a storage with (1) expanded door & (1) loft key. Please see Mr. Mora for details. Thank you

Hilda Adler

147398 2/4/2016 14 \$0.00

Medium Work In Progress 2/4/2016 9:23:18 AM

Marquez, Gerardo portable where computers tech are in (Frank and Richard) lock is broken.

Cora Ramirez

145125 Cafeteria 12/16/2015 64 \$0.00

Medium Work In Progress 12/16/2015 8:52:29 AM

Marquez, Gerardo PLEASE GET A PRICE QUOTE TO REFURBISH OR REPLACE CAFETERIA ROLL UP DELIVERY DOOR.

Gerardo Marquez

145201 C-Wing Portables 12/17/2015 63 \$0.00

Medium Work In Progress 12/17/2015 11:09:29

Marquez, Gerardo Would like outside doors of portable re keyed. -Nursing Dept.

Lisa Alarcon

145038 C-Wing Portables 12/15/2015 65 \$0.00

Medium Work In Progress 12/15/2015 9:24:13 AM

Marquez, Gerardo Would like to change lock on Nursing Dept. door.

Lisa Alarcon

147647 Classroom 2/9/2016 9 \$0.00

Medium Work In Progress B-Wing Rm#121 2/9/2016 2:42:58 PM

Marquez, Gerardo The door to classroom does not lock.

Hilda Adler

146587 1/22/2016 27 \$0.00

Medium Work In Progress 1/22/2016 10:50:50 AM

Chavez, Santos Replace perimeter lights to improve lighting conditions in parking lot.

Albert Vallejo

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
143779					11/18/2015		92		\$0.00
Medium	Work In Progress				11/18/2015 1:03:44 PM				
Chavez, Santos		Silver is checking on the scoreboard in the gym. They are having issues. He thinks it is electrical.							
Cora Ramirez									
147819					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 3:38:09 PM				
Herrera, Mario		need 30 in rake and adjustable wrenches. and ratchet wrenches							
Mario Herrera									
146965					1/28/2016		21		\$0.00
Medium	Work In Progress				1/28/2016 3:59:37 PM				
Ontiveros, Guadalupe		need parking blocks removed by marquee please see Mario for details							
Mario Herrera									
147261					2/2/2016		16		\$0.00
Medium	Work In Progress				2/2/2016 11:57:32 AM				
Herrera, Mario		requesting two 5 gallons of Beget paint to paint exterior doors							
Mario Herrera									
146518					1/21/2016		28		\$0.00
Medium	Work In Progress				1/21/2016 2:53:01 PM				
Herrera, Mario		Requesting new ballast for exterior lighting and new bulbs 25 each							
Mario Herrera									
146767					1/26/2016		23		\$0.00
Medium	Work In Progress				1/26/2016 3:11:59 PM				
Herrera, Mario		Need supplies and replacement components for AC units (Master Cools)							
Mario Herrera									
147786		Classroom			2/11/2016		7		\$0.00
Medium	Work In Progress	A-Wing Rm#160			2/11/2016 8:54:49 AM				
Herrera, Mario		Door is not closing. I have to push it, its falling down. Thank you.							
Hilda Adler									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
147648		Classroom			2/9/2016		9		\$0.00
Medium	Work In Progress	A-Wing Rm#163			2/9/2016 2:44:01 PM				
Herrera, Mario		Light in classroom is out							
Hilda Adler									
147790					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 10:24:51 AM				
Ontiveros, Joe		Need new Faucets and Faucet plates and 3/8x1/2x12 w/supply lines							
Mario Herrera									
147728					2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 3:07:35 PM				
Ontiveros, Joe		Backflow is leaking							
Joe Ontiveros									
140230	Annex	Restroom			9/18/2015		153		\$0.00
Medium	Work In Progress				9/18/2015 2:27:59 PM				
Ontiveros, Joe		please replace new sink faucets with new ones kids are leaving them on.							
Martin Soria									
138659					8/25/2015		177		\$0.00
Safety	Work In Progress				8/25/2015 9:23:01 AM				
Ontiveros, Joe		Eye Wash - All 3 missing string for shower and 002-valve is broken asp PM136938							
Mario Herrera									
139948		Football Field			9/14/2015		157		\$0.00
Medium	Work In Progress	Electrical/Field -			9/14/2015 3:58:31 PM				
Chavez, Santos		Electrical ground box by the football field to connect the football clock is not working.							
Hilda Adler									
141522	Band Room	Classroom			10/12/2015		129		\$0.00
Medium	Work In Progress	Rm#100 Band/			10/12/2015 3:10:56 PM				
Chavez, Santos		Install wall electrical outlet under sink.							
Hilda Adler									
138518	C-Wing	Office			8/21/2015		181		\$0.00
Medium	Work In Progress	AVECHS -			8/21/2015 2:37:51 PM				
Marquez, Gerardo		PLEASE BUILT IN COUNTERS FOR STUDENT UNION ROOM.							
Yvette Cortez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
138519	C-Wing	Office			8/21/2015		181		\$0.00
Medium	Work In Progress	AVECHS -			8/21/2015 2:40:17 PM				
Marquez, Gerardo NEED OPEN SHELVING FOR KITCHEN AREA. PLEASE CONTACT MRS. HOOD OR MRS QUEZADA FOR FURTHER DETAILS AT 882-6770.									
Yvette Cortez									
145631	C-Wing	Portables			1/5/2016		44		\$0.00
Medium	Work In Progress				1/5/2016 2:44:05 PM				
Vallejo, Albert Roof in Nursing Dept portable leaking.									
Lisa Alarcon									
147237					2/1/2016		17		\$0.00
Medium	Work In Progress				2/1/2016 4:04:33 PM				
Orozco, Daniel DISHWASHER LEAKS ALOT FROM THE BOTTOM. SNP MANAGER TERRY P.882.2824									
Jacqueline Aguilar									
145051					12/15/2015		65		\$0.00
Medium	Work In Progress				12/15/2015 10:37:46				
Orozco, Daniel MILK COOLER - SIDE PANEL DOORS FALLS - SAFETY HAZARD. SNP MANAGER TERRY P. 882.2824									
Maritza Gonzalez									
146289					1/15/2016		34		\$0.00
Medium	Work In Progress	Front Office-Gulf			1/15/2016 12:05:14 PM				
Flores, Pete Need 6 keys for New Gulf Cart. Approved per Mrs. Quinonez. Should you need additional information please contact Connie Avalos. Thank you									
Hilda Adler									
139909					9/14/2015		157		\$0.00
Medium	Work In Progress				9/14/2015 2:07:22 PM				
Chavez, Santos Please see Mario, Building Mechanic regarding Exit Signs									
Mario Herrera									
139952	Annex				9/14/2015		157		\$0.00
Medium	Work In Progress	Annex Electrical			9/14/2015 4:04:27 PM				
Chavez, Santos Annex electrical boxis not working or jumping as well.									
Hilda Adler									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
140237	C-Wing				9/18/2015		153		\$0.00
Medium	Work In Progress	Main Annex			9/18/2015 3:00:33 PM				
Chavez, Santos		THERE WAS A POWER OURTAGE IN THE BUILDING. PLEASE EVALUATE SITUATION ASAP.							
Yvette Cortez									
145853					1/8/2016		41		\$0.00
Medium	Work In Progress				1/8/2016 7:45:19 AM				
Chavez, Santos		Please supply electricity of proper voltage for new HVAC unit to be placed at SNP offices.							
Albert Vallejo									
137816	C-Wing				8/12/2015		190		\$0.00
Medium	Work In Progress	AVECHS -			8/12/2015 9:06:55 AM				
Marquez, Gerardo		Need keys issued for Custodian Jeremy Apodaca and Counselor Evelyn Chisari.							
Margret Villalobos									
143488					11/12/2015		98		\$0.00
Medium	Work In Progress				11/12/2015 3:31:25 PM				
Marquez, Gerardo		Need to supply chain and padlock for electrical meter enclosure, so EPEC can double lock.							
Albert Vallejo									
143775					11/18/2015		92		\$0.00
Medium	Work In Progress				11/18/2015 12:13:09				
Marquez, Gerardo		SNP OFFICES, NEED 4 CD1 KEYS FOR STORAGE.							
Maritza Gonzalez									
144336	East Mechanical				12/4/2015		76		\$0.00
Medium	Work In Progress				12/4/2015 8:27:19 AM				
Marquez, Gerardo		Requesting new doors to boiler room							
Mario Herrera									
144337					12/4/2015		76		\$0.00
Medium	Work In Progress				12/4/2015 8:28:05 AM				
Marquez, Gerardo		Requesting new doors to mechanical room behind cafeteria							
Mario Herrera									
141771	Cafeteria	Cafeteria			10/15/2015		126		\$0.00
Medium	Work In Progress				10/15/2015 11:58:35				
Solis, Lorenz		Requesting new AC units (master cools) 9 of them							
Mario Herrera									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
140575	Annex	Hallway/Corridor			9/24/2015		147		\$0.00
Medium	Work In Progress				9/24/2015 3:17:11 PM				
Solis, Lorenzø									
water fountain in annexis leaking									
Please contact Mario Herrera									
Mario Herrera									
141514	Band Room	Classroom			10/12/2015		129		\$0.00
Medium	Work In Progress	Rm#100 Band/			10/12/2015 2:58:44 PM				
Estrada, Jesus									
Repair snags on carpet, office and inner rooms.									
Hilda Adler									
144995					12/14/2015		66		\$0.00
Medium	Work In Progress				12/14/2015 3:48:35 PM				
Estrada, Jesus									
need to replace VCT and Carpt (on stage) in back room									
Jesus Estrada									
144581					12/7/2015		73		\$0.00
Medium	Work In Progress				12/7/2015 2:01:49 PM				
Solis, Lorenzø									
Requesting new heaters for Boys and girls locker-rooms									
Mario Herrera									
145061	C-Wing	Office			12/15/2015		65		\$0.00
Medium	Work In Progress	AVECHS-			12/15/2015 1:02:11 PM				
Chavez, Santos									
THE LIGHT SWITCH IN THE WORKROOM NEEDS TO BE MOVED TO THE FRONT OF THE ROOM ENTRANCE INSTEAD OF BY THE EXIT DOOR. (QUEZADA)									
Rosa Quezada									
146986	C-Wing				1/29/2016		20		\$0.00
Medium	Work In Progress	AVECHS-			1/29/2016 10:52:15 AM				
Chavez, Santos									
need to install an outlet in the student union.									
Rosa Quezada									
146342					1/19/2016		30		\$0.00
Medium	Work In Progress				1/19/2016 8:28:55 AM				
Vallejo, Albert									
Order 3" strainer sets for west chiller/boiler.									
Albert Vallejo									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
147134					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:52:04 AM				
Apodaca, Mario Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.									
Margret Villalobos									
142226	C-Wing	Foyer			10/23/2015		118		\$0.00
Medium	Work In Progress	AVECHS -			10/23/2015 10:34:51				
Carbajal, Jimmy we needs floor mats in front entrance. slippery when wet.. AVECHS - ANNEX									
Rosa Quezada									
142290		Storage			10/26/2015		115		\$0.00
Medium	Work In Progress	Old Main			10/26/2015 8:48:07 AM				
Soria, Martin Please clean and mop room to get it ready for storage. Will be used for Panther Closet. If any questions please see Terry Urbina or Carol Hernandez.									
Hilda Adler									
142015		Classroom			10/20/2015		121		\$0.00
Medium	Work In Progress	B-Wing Rm#117			10/20/2015 3:02:16 PM				
Soria, Martin Please clean light fixtures.									
Hilda Adler									
146345		Custodial			1/19/2016		30		\$0.00
Medium	Work In Progress				1/19/2016 9:37:37 AM				
Carbajal, Jimmy Propane burnisher won't start									
Martin Soria									
Count: 56 Work Orders			Avg. Age of WO's 76		Total for Gadsden MS			0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
145319					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:27 AM				
Aguilar, Patricio		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
146153					1/13/2016		36		\$0.00
Medium	Work In Progress				1/13/2016 2:56:39 PM				
Aguilar, Patricio		wo to myself - need to replace toilet wax gasket - floor tiles rest room kitchen							
Patricio Aguilar									
142705					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:09 AM				
Orozco, Daniel		Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
146901					1/28/2016		21		\$0.00
Medium	Work In Progress				1/28/2016 8:56:44 AM				
Aguilar, Patricio		wo to myself - need to in stall video surveillance signs at entrances							
Patricio Aguilar									
147318					2/3/2016		15		\$0.00
Medium	Work In Progress				2/3/2016 8:20:23 AM				
Aguilar, Patricio		wo to myself - need to replace glass filler on water fountain by gym							
Patricio Aguilar									
143854					11/19/2015		91		\$0.00
Medium	Work In Progress				11/19/2015 2:49:02 PM				
Castillo, Carlos		emergency light fixer needing ballast r310							
Patricio Aguilar									
147401					2/4/2016		14		\$0.00
Medium	Work In Progress				2/4/2016 9:49:13 AM				
Ambriz, Jose		need a push lever 8-1/2" high gooseneck glass filler for a halsey taylor water fountain - located by gum entrance - thank you for your help							
Patricio Aguilar									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
147814					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 3:30:52 PM				
Ambriz, Jose		the control vale is not closing - room getting hot - closed vales r308 - thank you for your help							
Patricio Aguilar									
147916					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 9:37:57 AM				
Ambriz, Jose		a heater line pressure valve opened and dumped water in to the room 305 - I closed heater valves lines , thank you for the help							
Patricio Aguilar									
140718					9/28/2015		143		\$0.00
Medium	Work In Progress				9/28/2015 3:52:17 PM				
Vallejo, Albert		Remove sand and plastic borders and replace with woodchips and concrete at south playground.							
Albert Vallejo									
147565		Custodial			2/8/2016		10		\$0.00
Medium	Work In Progress				2/8/2016 12:42:45 PM				
Carbajal, Jimmy		I HAVE 2 ROYAL VACUUM BAGS THAT NEED REPLACING. THEY HAVE HOLES IN THEM							
Rudy Ramos									
Count: 11 Work Orders			Avg. Age of WO's	45		Total for La Union ES	0		\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
138748	Main Building	Classroom			8/26/2015		176		\$0.00
Medium	Work In Progress			8/26/2015 7:46:19 AM					
Estrada, Jesus	In classroom 222 the plastic the edge of the carpet part of it came of its needs to be replaced.								
Alfredo Ambriz									
147703					2/10/2016		8		\$0.00
Medium	Work In Progress			2/10/2016 9:22:22 AM					
Gonzales, Camilo	Please pick up File Cabinet from Anthony Pre K for Ms. Lucy from SPED and bring it and place it in the IEP portable at LLE, thank you!								
Angie Flores									
145978	Main Building	Classroom			1/11/2016		38		\$0.00
Medium	Work In Progress	107		1/11/2016 9:46:41 AM					
Pacheco, Hector	Mr. Pacheco please go to San Miguel Elem to pick up a Student Corral and place it in room 107 with Ms. Richhart, as per IEP we need Student Corral ASAP								
Angie Flores									
142728					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress			11/1/2015 12:54:24 AM					
Vallejo, Albert	Monthly - Loma Linda ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
147535					2/7/2016	2/23/2016	11		\$0.00
Medium	Work In Progress			2/7/2016 12:31:56 AM					
Pacheco, Hector	Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
146589		Roof			1/22/2016		27		\$0.00
Medium	Work In Progress			1/22/2016 11:04:24 AM					
Solis, Lorenzo	In need of 4 - 4800 evaporate A/C and 13 - 6800 evaporate A/C.								
Hector Pacheco									
147197		Classroom			2/1/2016		17		\$0.00
Medium	Work In Progress			2/1/2016 3:15:07 PM					
Chavez, Santos	Need assistance on replacing a few ballast in room #203.								
Hector Pacheco									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

143656 Main Building Office 11/16/2015 94 \$0.00

Medium Work In Progress 11/16/2015 3:40:40 PM

Chavez, Santos Need to replace a few ballast in main office.

Hector Pacheco

147622 Exterior 2/9/2016 9 \$0.00

Medium Work In Progress 2/9/2016 7:52:36 AM

Ontiveros, Guadalupe In need of some rock at middle of bus turn around at water run off. And maybe some at east side fence line if possible. Thanks

Hector Pacheco

144250 Main Building Athletic Field 12/3/2015 77 \$0.00

Medium Work In Progress 12/3/2015 8:37:43 AM

Pacheco, Hector Need to extend sprinkler valve boxes 6 inches higher.

Hector Pacheco

147332 Main Building Restroom 2/3/2016 15 \$0.00

Medium Work In Progress 2/3/2016 12:38:53 PM

Pacheco, Hector Need to change out motor on exhaust fan.

Hector Pacheco

147333 Main Building Roof 2/3/2016 15 \$0.00

Medium Work In Progress 2/3/2016 12:43:56 PM

Pacheco, Hector Need to order A/C sheet metal covers to be replace.

Hector Pacheco

147462 Main Building 2/5/2016 13 \$0.00

Medium Work In Progress 2/5/2016 7:32:11 AM

Pacheco, Hector Need to install Video Surveillance signs.

Hector Pacheco

142706 11/1/2015 11/22/2015 109 \$0.00

Medium Work In Progress 11/1/2015 12:54:09 AM

Orozco, Daniel Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

145317 1/3/2016 2/3/2016 46 \$0.00

Medium Work In Progress 1/3/2016 12:43:25 AM

Pacheco, Hector Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Loma Linda ES							
145362					1/3/2016	1/24/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:44:04 AM				
Vallejo, Albert		Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
144165	Main Building	Restroom			12/2/2015		78		\$0.00
Medium	Work In Progress				12/2/2015 7:42:04 AM				
Ontiveros, Joe		Need to replace gaskets on flush valve teachers rest room across teachers lounge.							
Hector Pacheco									
147412	Main Building	Restroom			2/4/2016		14		\$0.00
Medium	Work In Progress				2/4/2016 12:46:51 PM				
Ontiveros, Joe		Need assistance to repair toilet flush valve wont stop flushing and leaks on all joints. Man teacher restroom 3rd and 4th grade wing.							
Hector Pacheco									
147198	Main Building	Auditorium			2/1/2016		17		\$0.00
Medium	Work In Progress				2/1/2016 3:21:13 PM				
Ontiveros, Joe		In need to remove and replace water fountain in cafeteria. I found a new fountain in a morgen to get installed.							
Hector Pacheco									
147822		Restroom (Girls)			2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 3:44:32 PM				
Ontiveros, Joe		toilet needs to be anchored to floor. 1 flush valve not working other leaking.tried trouble shooting.							
Hector Pacheco									
147839		Restroom			2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 3:49:00 PM				
Ontiveros, Joe		5th 6th grade wing boy restroom 2 leaking flush valves.							
Hector Pacheco									
147625	Main Building	Restroom			2/9/2016		9		\$0.00
Medium	Work In Progress				2/9/2016 8:08:29 AM				
Ontiveros, Joe		I have 2 leaking flash valves on 2 urinals I tried Teflon tape but no success.Also 1 toilet not secured to floor no toilet bolts .Across teachers lounge.							
Hector Pacheco									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

147874	Main Building	Restroom			2/12/2016		6		\$0.00
Medium	Work In Progress				2/12/2016 3:34:35 PM				
Ontiveros, Joe		3rd and 4th grade wing 2 urinal flush valve leaking, toilet not anchored to floor flush valve leaking.							
Hector Pacheco									

143944	Main Building	Restroom			11/20/2015		90		\$0.00
Medium	Work In Progress				11/20/2015 3:37:51 PM				
Ontiveros, Joe		Need assistance replacing flush valve in boys rest room across teachers lounge.							
Hector Pacheco									

147624	Main Building	Restroom (Girls)			2/9/2016		9		\$0.00
Medium	Work In Progress				2/9/2016 7:58:33 AM				
Ontiveros, Joe		Toilet not fastened to floor, leaking flush valve at joints. Tried Teflon tape no success.							
Hector Pacheco									

143647	Main Building	Office			11/16/2015		94		\$0.00
Medium	Work In Progress				11/16/2015 3:32:22 PM				
Chavez, Santos		Need to replace emergency ballast in Principal Lawlor office.							
Hector Pacheco									

140150	Main Building	Restroom (Girls)			9/17/2015		154		\$0.00
Medium	Work In Progress				9/17/2015 11:52:44 AM				
Ontiveros, Joe		Can you please come and fix the drainer from the girl restroom from the front of the teachers lunch room its clogged up thank you.							
Alfredo Ambriz									

141376					10/9/2015		132		\$0.00
Medium	Work In Progress	Kitchen			10/9/2015 2:43:55 PM				
Orozco, Daniel		Replace drain grill in front of tilt skillet. Per ergonomic inspection the drain grill should be replaced with an appropriate style. Please call Cynthia with any questions 882-6949.							
Cynthia Maes									

143932		Classroom			11/20/2015		90		\$0.00
Medium	Work In Progress	Music Portable			11/20/2015 2:26:44 PM				
Estrada, Jesus		CARPET IS TORN CREATING A HAZARD FOR CHILDREN							
Angie Flores									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Loma Linda ES							
139345					9/4/2015		167		\$0.00
Medium	Work In Progress	All around the			9/4/2015 9:31:04 AM				
Pacheco, Hector		Repaint door frames in all entrance doors and office doors.							
Angie Flores									
Count: 30 Work Orders		Avg. Age of WO's	56			Total for Loma Linda ES	0		\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
139560					9/8/2015		163		\$0.00
Medium	Work In Progress				9/8/2015 10:14:50 AM				
Chavez, Santos		we have 4 parking/security lights that are not working							
Joe Ramirez									
138478	Main Building				8/21/2015		181		\$0.00
Medium	Work In Progress	Cafeteria			8/21/2015 7:53:48 AM				
Chavez, Santos		outlet is loose in cafeteria.							
Sandra Mora									
146830					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 10:23:37 AM				
Ramirez, Joe		Need to install 4 under surveillance signs at entrances.							
Joe Ramirez									
140233	Pump House	Pump House			9/18/2015		153		\$0.00
Medium	Work In Progress				9/18/2015 2:52:32 PM				
Chavez, Santos		irrigation control box need to identify and number all wires to the control system to well and air compressor							
Mario Apodaca									
138289	Main Building	Cafeteria			8/18/2015		184		\$0.00
Medium	Work In Progress	Cafeteria			8/18/2015 4:08:23 PM				
Chavez, Santos		Requesting, suggest power surge protector ASAP.							
Sandra Mora									
145320					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:28 AM				
Ramirez, Joe		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
142707					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:10 AM				
Orozco, Daniel		Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
145770	Main Building	Storage			1/7/2016		42		\$0.00
Medium	Work In Progress	Main Office			1/7/2016 8:49:28 AM				
Chavez, Santos		As per Joe Ramirez/Bldg. Mech. we are needing electric power to power a new refrigerator may need a electric power drop installed. Thank you							
Sandra Mora									
2/18/2016 11:23:48 AM									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
146579					1/22/2016		27		\$0.00
Medium	Work In Progress				1/22/2016 9:16:51 AM				
Chavez, Santos		elect. wall heater in the teachers bathroom (north end) is not working.							
Joe Ramirez									
147138					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:52:07 AM				
Apodaca, Mario		Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
136170	2003 Classroom	Hallway/Corridor			7/20/2015		213		\$0.00
Medium	Work In Progress	E Wing			7/20/2015 3:59:34 PM				
Marquez, Gerardo		Need staff name plaque's for the following staff V. Munoz, L. Baldauf, C. Zuloaga, G. Moreno, A. Alvarado, M. Martinez. Thank you, Sandy							
Sandra Mora									
142729					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:25 AM				
Vallejo, Albert		Monthly - Mesquite ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
142965	Main Building				11/3/2015		107		\$0.00
Medium	Work In Progress	Main Office			11/3/2015 1:55:34 PM				
Estrada, Jesus		Main Office need carpet repair 2 seam repair. Thank you, Sandy							
Sandra Mora									
147637	Main Building				2/9/2016		9		\$0.00
Medium	Work In Progress				2/9/2016 12:13:13 PM				
Gonzales, Camilo		NEED A REFILL ON PROPANE TANK FOR BURNISHER							
Mario Valles									
137278					8/5/2015		197		\$0.00
Medium	Work In Progress				8/5/2015 8:23:26 AM				
Chavez, Santos		Environmental Park - Check if it is possible to get electrical power to this area- cost estimate							
Alfredo Holguin									
Count: 15 Work Orders			Avg. Age of WO's 105		Total for Mesquite ES			0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
147969					2/18/2016		0		\$0.00
Medium	Work In Progress				2/18/2016 8:18:53 AM				
Marquez, Gerardo		Need to get paint from Danny Vega's storage building.							
Salvador Gonzalez									
141341					10/9/2015		132		\$0.00
Medium	Work In Progress				10/9/2015 7:25:07 AM				
Chavez, Santos		emergency ballast out in hallway(pecan valley) by rm 201-205-211-rio grand wing by rm 305 -402-							
Danny Vega									
141189					10/7/2015		134		\$0.00
Medium	Work In Progress				10/7/2015 8:35:13 AM				
Chavez, Santos		exterior bldg. lighting have 14 (dome type) lamps that are out thru out bldg please ck to order bulbs if not in stock							
Danny Vega									
147315					2/3/2016		15		\$0.00
Medium	Work In Progress				2/3/2016 7:46:59 AM				
Ontiveros, Joe		Backflow is leaking							
Danny Miranda									
142541					10/29/2015		112		\$0.00
Medium	Work In Progress				10/29/2015 10:30:21				
Appelzoller, Fred		nurses office/hot water takes to long to deliver/need to run faucet open for a long time.Need small 3 gal water heater for nurses to have hot water at all times							
Danny Vega									
140342					9/21/2015		150		\$0.00
Medium	Work In Progress				9/21/2015 3:48:33 PM				
Orozco, Daniel		AS PER HEALTH INSPECTION REPORT 9/10/15, WALK IN FLOOR PANEL COMING UP , REPLACE RUBBER BOTTOM SPACES AS THEY START TO CRUBMLE.							
Maritza Gonzalez									
147913					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 8:00:46 AM				
Orozco, Daniel		DISHWASHER STOPPED WORKING. SNP MANAGER LAURA B. 233.3658							
Maritza Gonzalez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
146284					1/15/2016		34		\$0.00
Medium	Work In Progress				1/15/2016 9:56:42 AM				
Chavez, Santos		need to replace exit signs in 200- wing hallway204, 206,207,208, and 209							
Danny Miranda									
144369					12/4/2015		76		\$0.00
Medium	Work In Progress				12/4/2015 11:40:22 AM				
Gonzalez, Salvador		soccer goal bottom bar needs welded/plus need some metal spikes to anchor down goals							
Danny Vega									
145367					1/3/2016		46		\$0.00
Medium	Work In Progress				1/3/2016 12:44:09 AM				
Vallejo, Albert		Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PMschedule details.							
Margret Villalobos									
145330					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:36 AM				
Vega, Danny		Yearly - North Valley ES Backflow Inspection - Refer to PMschedule details.							
Margret Villalobos									
143843					11/19/2015		91		\$0.00
Medium	Work In Progress				11/19/2015 11:49:18				
Appelzoller, Fred		water leak on 4inch shut off valve by back flows/please ck out/ ne fence line							
Danny Vega									
147639					2/9/2016		9		\$0.00
Medium	Work In Progress				2/9/2016 12:57:30 PM				
Vallejo, Albert		Construct curb to complete perimeter of playground.							
Albert Vallejo									
143845		Hallway/Corridor			11/19/2015		91		\$0.00
Medium	Work In Progress				11/19/2015 1:28:39 PM				
Chavez, Santos		We need 3 more electrical outlets installed for our copiers by our office area. Per the service tech need to make sure there is enough amperage per outlet to support copier. Min. of 25 amps.							
Gloria Reyes									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: North Valley ES									
143541		Office			11/13/2015		97		\$0.00
Medium	Work In Progress				11/13/2015 10:03:55				
Appelzoller, Fred	The Nursing office at NVE does not have HOT water unless it is left running for 5 minutes. This is very wasteful and keeps student from going back to class. Please can a small hot water heater be put in under the sink? Thanks, Colleen Runyan, RN								
Colleen Runyan									
145338					1/3/2016		46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:43 AM				
Vallejo, Albert	Monthly - North Valley ES - Fire Pump Engine - Refer to PM schedule details.								
Margret Villalobos									
142696					11/1/2015		109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:03 AM				
Orozco, Daniel	Monthly - North Valley ES - Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
136000		Cafeteria			7/16/2015		217		\$0.00
High	Work In Progress				7/16/2015 1:32:41 PM				
Solis, Lorenzo	Wash all windows inside and out (cafeteria)								
Jesus Estrada									
147911		Restroom (Girls)			2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 7:41:53 AM				
Appelzoller, Fred	Boys, girls, and adult restrooms in kinder hallway are all clogged.								
Ivan Rodriguez									
147707		Custodial			2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 10:00:44 AM				
Gonzales, Camilo	As per the principal Ms. Hernandez, the school needs 10 6 grade student chairs. Thank you.								
Ivan Rodriguez									
147335		Custodial			2/3/2016		15		\$0.00
Medium	Work In Progress				2/3/2016 1:07:11 PM				
Carbajal, Jimmy	Jimmy buenas tardes, tengo una aspiradora que se le cae el handle y tambien necesita la bolsa, por favor si me la puede arreglar.. Gracias.								
Ivan Rodriguez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		North Valley ES							
142953		Athletic Field			11/3/2015		107		\$0.00
Medium	Work In Progress				11/3/2015 10:31:01 AM				
Ontiveros, Guadalupe		Need Soccer Goal Nets-(2)-20ft L x 8ft H x 6ft D							
Gloria Reyes									
Count: 22 Work Orders		Avg. Age of WO's		70	Total for North Valley ES			0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Northern On-Track Pre-K (LM)									
147133					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:52:03 AM				
Apodaca, Mario	Monthly - Northern Pre-K -Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
144371					12/4/2015		76		\$0.00
Medium	Work In Progress				12/4/2015 11:52:32 AM				
Vallejo, Albert	class room at old cafeteria rms need new tpo poly roofing/plus clothing bank used by social workers need new shingles.(currently used as storage)attention MR VALLEJO								
Danny Vega									
146681					1/25/2016		24		\$0.00
Medium	Work In Progress				1/25/2016 3:28:40 PM				
Appelzoller, Fred	hot water not working in rm 104, please fix								
Brian Pacheco									
140486	Main Building	Athletic Field			9/23/2015		148		\$0.00
Medium	Work In Progress	outside			9/23/2015 1:57:54 PM				
Ontiveros, Guadalupe	There is a new canopy in our cafeteria that needs to be set up where our sandbox is for the students. They do not have appropriate shade to be where the sand is located and they are digging holes next to the building.				9/29/15 - Asp Albert, route to Grounds				
Concepcion Montalvo									
Count: 4 Work Orders		Avg. Age of WO's		67	Total for Northern On-Track Pre-K (LM)			0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
139632		Office			9/9/2015		162		\$0.00
Medium	Work In Progress				9/9/2015 9:35:50 AM				
Marquez, Gerardo		Please install doors and windows, when they arrive from APCO.							
Danny Miranda									
147926					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 3:10:19 PM				
Carrasco, Danny		ATT: DANNY CARRASCO, PLEASE ORDER NEW LADDERS. THNX!							
Lorenzo Solis									
147807					2/11/2016		7		\$0.00
Low	Work In Progress				2/11/2016 2:43:32 PM				
Ronquillo, Ruben		NEED TO ORED TOOL POUCH, PLIER SET							
146224	Motor Vehicle				1/14/2016		35		\$0.00
Medium	Work In Progress				1/14/2016 2:35:50 PM				
Perez, Raul		put logos and vehicle #6 on new dump truck							
Maria Ruiz									
147973	Motor Vehicle				2/18/2016		0		\$0.00
Medium	Work In Progress	vehicle#134			2/18/2016 9:03:08 AM				
Flores, Pete		please prepare vehicle for use by grounds dept.							
Pete Flores									
145698	Motor Vehicle				1/6/2016		43		\$0.00
Medium	Work In Progress				1/6/2016 10:00:47 AM				
Flores, Pete		vehicle 47 heater blows constantly; check engine light in on							
Maria Ruiz									
138392	Motor Vehicle				8/20/2015		182		\$0.00
Medium	Work In Progress				8/20/2015 8:39:05 AM				
Flores, Pete		ac compressor doesn't work; makes a lot of noise							
Pete Flores									
144565	Motor Vehicle				12/7/2015		73		\$0.00
Medium	Work In Progress				12/7/2015 10:28:39 AM				
Flores, Pete		vehicle 163 (check engine light turned on) reported by Richard Yanez							
Maria Ruiz									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
144568	Motor Vehicle				12/7/2015		73		\$0.00
Medium	Work In Progress				12/7/2015 10:30:14 AM				
Flores, Pete	vehicle 187; check brakes and tire pressure sensor reported by Charlene Bonham								
Maria Ruiz									
142372	Motor Vehicle				10/27/2015		114		\$0.00
Medium	Work In Progress				10/27/2015 9:10:35 AM				
Flores, Pete	vehicle 47 driver's window wouldn't go up; passenger door doesn't open from inside.								
Maria Ruiz									
142124					10/21/2015		120		\$0.00
Medium	Work In Progress				10/21/2015 3:56:52 PM				
Ontiveros, Joe		10-21-15 17046.6 17060.9				10/21/15			
		.5 Enter Log							
		LLES 7-133840-p							
		.5 Enter Log							
		1 Total HR							
Joe Ontiveros									
147550					2/8/2016		10		\$0.00
Medium	Work In Progress				2/8/2016 7:39:23 AM				
Gonzalez, Salvador	2-8-16 I Need fabricate racks for shop								
Salvador Gonzalez									
146834	Maintenance				1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 10:33:31 AM				
Miranda, Danny	NEED TO BUILD WALLS IN MAINT. WHS. TO ENCLOSE EQUIP. THANK YOU								
Ruben Ronquillo									
138019					8/14/2015		188		\$0.00
Medium	Work In Progress				8/14/2015 8:57:46 AM				
Marquez, Gerardo	PLEASE MEET WITH DR. VENDOR FOR PRICE QUOTE.								
Gerardo Marquez									
145632					1/5/2016		44		\$0.00
Medium	Work In Progress				1/5/2016 2:49:25 PM				
Vallejo, Albert	District Wide - Make repairs to fire sprinklers to correct deficiencies found at annual inspection.								
Albert Vallejo									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
144787					12/10/2015		70		\$0.00
Medium	Work In Progress				12/10/2015 7:44:29 AM				
Solis, Lorenzo		Welding Shop - Install two heaters							
Albert Vallejo									
144788					12/10/2015		70		\$0.00
Medium	Work In Progress				12/10/2015 7:45:06 AM				
Solis, Lorenzo		Welding Shop - Install exhaust fan							
Albert Vallejo									
147035					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:50:49 AM				
Flores, Pete		Monthly - PPD-T-0529 PM (Trencher) - by SWP - Refer to PM schedule details.							
Margret Villalobos									
147268					2/2/2016		16		\$0.00
Medium	Work In Progress	FEDERAL			2/2/2016 3:00:19 PM				
Flores, Pete		ENGINE LIGHT TURNED ON. NEEDED TO JUMP START BATTERY.							
Noemi Duron									
138059	Motor Vehicle				8/14/2015		188		\$0.00
Medium	Work In Progress	FEDERAL			8/14/2015 2:03:43 PM				
Flores, Pete		VEHICLE HAS A STRONG GASOLINE ODOR.							
Noemi Duron									
143131					11/5/2015		105		\$0.00
Medium	Work In Progress	FEDERAL			11/5/2015 3:03:16 PM				
Flores, Pete		Car shakes when driving long distances, when the speed is high.							
Noemi Duron									
142608					10/30/2015		111		\$0.00
Medium	Work In Progress				10/30/2015 10:48:14				
Chavez, Santos		light pole in middle of parking lot was not on this morning; light on pole close to street was not on this morning. report from Jose R.							
Maria Ruiz									
140148	Motor Vehicle				9/17/2015		154		\$0.00
Medium	Work In Progress				9/17/2015 11:31:24 AM				
Flores, Pete		Tune and repair District Warehouse van #11							
Enrique Briones									
2/18/2016 11:23:48 AM									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
143987					11/30/2015		80		\$0.00
Medium	Work In Progress				11/30/2015 12:51:58				
Apodaca, Mario	Monthly - PPD/GHS - WW Monthly Sampling - Refer to PM schedule details.								
Margret Villalobos									
147046					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:50:57 AM				
Apodaca, Mario	Monthly - PPD/GHS - WW Monthly Sampling - Refer to PM schedule details.								
Margret Villalobos									
145333					1/3/2016		46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:39 AM				
Flores, Pete	Monthly - PPD-T-0525 PM (Excavator) - by SWP - Refer to PM schedule details.								
Margret Villalobos									
147089					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:31 AM				
Carrasco, Danny	Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.								
Margret Villalobos									
147034					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:50:48 AM				
Flores, Pete	Monthly - PPD-MP-0143 DT PM Service - by SWP - Refer to PM schedule details.								
Margret Villalobos									
145497					1/4/2016		45		\$0.00
Medium	Work In Progress				1/4/2016 12:38:42 AM				
Flores, Pete	Monthly - District Backhoe 0520 - Full Service PM - Refer to PM schedule details.								
Margret Villalobos									
145498					1/4/2016		45		\$0.00
Medium	Work In Progress				1/4/2016 12:38:43 AM				
Flores, Pete	Monthly - PPD - UV-0516 PM Service - Refer to PM schedule details.								
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

147905 2/14/2016 4 \$0.00

Medium Work In Progress 2/14/2016 12:31:13 AM

Flores, Pete Yearly - PPD-T-0524 Bobcat PM Service - Refer to PM schedule details.

Margret Villalobos

145321 1/3/2016 2/3/2016 46 \$0.00

Medium Work In Progress 1/3/2016 12:43:29 AM

Herrera, Mario Yearly - Physical Plant Backflow Inspection - Refer to PMs schedule details.

Margret Villalobos

145374 1/3/2016 1/11/2016 46 \$0.00

Medium Work In Progress 1/3/2016 12:44:15 AM

Herrera, Mario Monthly - Physical Plant Roof Inspection - Refer to PM schedule details.

Margret Villalobos

145977 1/11/2016 38 \$0.00

Scheduled Work In Progress 1/11/2016 9:36:50 AM

Ontiveros, Guadalupe we need extra keys for kubota tractor and seat has to be replaced.

Guadalupe Ontiveros

144789 12/10/2015 70 \$0.00

Medium Work In Progress 12/10/2015 7:46:12 AM

Ontiveros, Joe Welding Shop - supply gas for two heater units

Albert Vallejo

143609 11/16/2015 94 \$0.00

Medium Work In Progress 11/16/2015 7:43:51 AM

Gonzalez, Salvador Sal can you please construct a pipe rack with a shade at the Morgan building at the GAC. Thanks

David Villalobos

146216 Motor Vehicle 1/14/2016 35 \$0.00

Medium Work In Progress equip.#0512- 1/14/2016 10:52:55 AM

Flores, Pete fork lift not starting please check and advise

Pete Flores

146218 Motor Vehicle 1/14/2016 35 \$0.00

Medium Work In Progress equip.#0400 1/14/2016 11:27:06 AM

Flores, Pete mower will not start . please check and advise

Pete Flores

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

147972	Motor Vehicle				2/18/2016		0		\$0.00
--------	---------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	vehicle#152			2/18/2016 9:01:12 AM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Flores, Pete
please check electrical system . have to jump start at times.

Pete Flores

147968	Motor Vehicle				2/16/2016		2		\$0.00
--------	---------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	vehicle#153			2/16/2016 4:07:10 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Flores, Pete
please repair flat tire

Pete Flores

147857	Motor Vehicle				2/12/2016		6		\$0.00
--------	---------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	vehicle#153			2/12/2016 9:40:20 AM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Flores, Pete
please repair rear flat tire

Pete Flores

146427	Motor Vehicle				1/20/2016		29		\$0.00
--------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	vehicle#163			1/20/2016 9:35:52 AM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Flores, Pete
please check for any scheduled maintenance

Pete Flores

146512	Motor Vehicle				1/21/2016		28		\$0.00
--------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	vehicle#120			1/21/2016 12:20:57 PM				
--------	------------------	-------------	--	--	-----------------------	--	--	--	--

Flores, Pete
losing diesel fuel through fuel filter canister. please check and advise.

Pete Flores

147859	Motor Vehicle				2/12/2016		6		\$0.00
--------	---------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	vehicle#185			2/12/2016 11:20:24 AM				
--------	------------------	-------------	--	--	-----------------------	--	--	--	--

Flores, Pete
please replace broken window

Pete Flores

147860	Motor Vehicle				2/12/2016		6		\$0.00
--------	---------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	vehicle#178			2/12/2016 11:22:03 AM				
--------	------------------	-------------	--	--	-----------------------	--	--	--	--

Flores, Pete
please replace broken windshield

Pete Flores

147917					2/16/2016		2		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				2/16/2016 9:47:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Mario
Please assemble and set up 1 stand and 4 flat file cabinets in construction office storage room. see Dominique in the construction off should you have questions. Thank You

Dominique Esparza

2/18/2016 11:23:49 AM

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
147871					2/12/2016		6		\$0.00
Medium	Work In Progress				2/12/2016 3:32:02 PM				
Herrera, Mario		Please assemble new shelves. Box in Construction office storage room. Also please bring 2 shelves from SW corner of custodial barrack and install them in the Construction storage room with the flat files. Please see Jimmy or Marin for key to get into custodial barrack to pick up shelves. If you have any questions please see Dominique in the construction office.							
Dominique Esparza									
147851	Maintenance				2/11/2016		7		\$0.00
Medium	Work In Progress	Maint Office			2/11/2016 4:00:52 PM				
Herrera, Mario		Mens Restroom - Need to replace trap on urinal.							
Margret Villalobos									
146281	Motor Vehicle				1/15/2016		34		\$0.00
Medium	Work In Progress	vehicle#15			1/15/2016 8:48:08 AM				
Flores, Pete		please check for any scheduled maintenance							
Pete Flores									
146670	Motor Vehicle				1/25/2016		24		\$0.00
Medium	Work In Progress	vehicle#111			1/25/2016 1:49:28 PM				
Flores, Pete		driver's door window will not roll up or down. please check and advise							
Pete Flores									
146672	Motor Vehicle				1/25/2016		24		\$0.00
Medium	Work In Progress	vehicle#171			1/25/2016 2:09:38 PM				
Flores, Pete		please service							
Pete Flores									
146676	Motor Vehicle				1/25/2016		24		\$0.00
Medium	Work In Progress	equip#0906			1/25/2016 3:08:27 PM				
Flores, Pete		sth's electric gator will not travel fore or aft. please check and advise							
Pete Flores									
144718	Motor Vehicle				12/9/2015		71		\$0.00
Medium	Work In Progress	vehicle#131			12/9/2015 8:20:19 AM				
Flores, Pete		please check cause of grinding noise in engine compartment							
Pete Flores									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
144725	Motor Vehicle				12/9/2015		71		\$0.00
Medium	Work In Progress	vehicle#158			12/9/2015 9:17:19 AM				
Flores, Pete		please check cause of vehicle not starting. also check for any required maintenance							
Pete Flores									
141738					10/14/2015		127		\$0.00
Medium	Work In Progress				10/14/2015 3:50:55 PM				
Flores, Pete		THE A/C IS NOT FUNCTIONING							
Santos Chavez									
141741					10/14/2015		127		\$0.00
Medium	Work In Progress				10/14/2015 3:52:13 PM				
Flores, Pete		NEED STEP TO GET INTO THE TRUCK							
Santos Chavez									
146817					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 7:31:41 AM				
Chavez, Santos		tool replacement and issue							
Santos Chavez									
146818					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 7:33:35 AM				
Chavez, Santos		materials for stock for electrical dept.							
Santos Chavez									
146584					1/22/2016		27		\$0.00
Medium	Work In Progress				1/22/2016 10:44:56 AM				
Chavez, Santos		Install exterior shop lighting.							
Albert Vallejo									
146586					1/22/2016		27		\$0.00
Medium	Work In Progress				1/22/2016 10:48:05 AM				
Chavez, Santos		Install interior shop lights.							
Albert Vallejo									
147415					2/4/2016		14		\$0.00
Medium	Work In Progress				2/4/2016 1:59:44 PM				
Chavez, Santos		Need to replace ladders the fiberglass is deteriorated due to sun exposure.							
Santos Chavez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
142138	Motor Vehicle				10/22/2015		119		\$0.00
Medium	Work In Progress			10/22/2015 8:49:29 AM					
Chavez, Santos	Install outlets as needed in the new welding shop. (Please see Sal and Jimmy)								
Albert Vallejo									
147811	Motor Vehicle				2/11/2016		7		\$0.00
Medium	Work In Progress			2/11/2016 3:17:28 PM					
Chavez, Santos	lights on pole in the middle of vehicles in front of Auto Shop are not working reported by (R. Tapia)								
Maria Ruiz									
136405	Maintenance	Electrical Room			7/24/2015		209		\$0.00
Medium	Work In Progress			7/24/2015 7:52:42 AM					
Castillo, Carlos	Make material list for stock.								
Carlos Castillo									
141935					10/19/2015		122		\$0.00
Medium	Work In Progress			10/19/2015 2:49:46 PM					
Marquez, Gerardo	AS PER MR. CHAVEZ, ALL NORTHERN KITCHENS NEED TO BE REKEYED.								
Maritza Gonzalez									
147249					2/2/2016		16		\$0.00
Medium	Work In Progress			2/2/2016 8:14:17 AM					
Marquez, Gerardo	NEED TO PREP CORE LIST FOR YUCCA HEIGHTS ELEM.								
Gerardo Marquez									
146121					1/12/2016		37		\$0.00
Medium	Work In Progress			1/12/2016 11:18:09 PM					
Marquez, Gerardo	1/12/16 3167-3217 .5-CHECK E-MAIL/PREP MATRL.4-GMS. 145085 C. 2-CH. H.S. 145697 C. 1-CH. H. S. 145969 WP. .5-LOG OUT.								
Gerardo Marquez									
147701					2/10/2016		8		\$0.00
Medium	Work In Progress			2/10/2016 8:35:23 AM					
Marquez, Gerardo	as per Jimmy & Lisa, the back door is still hard to open. please check again.								
Alfredo Holguin									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
137531		Lift Station			8/7/2015		195		\$0.00
Medium	Work In Progress				8/7/2015 3:13:14 PM				
Gonzalez, Salvador		the uv system shaded area need too put more sheet metal to cover the uv system							
Mario Apodaca									
140460					9/23/2015		148		\$0.00
Medium	Work In Progress				9/23/2015 8:36:42 AM				
Marquez, Gerardo		DOOR FRAMES RUSTED. PLEASE REPLACE AT MAINT. WHS. AND LOCKSMITH ENTRANCE. THANK YOU							
Ruben Ronquillo									
135167	Motor Vehicle				7/1/2015		232		\$0.00
Medium	Work In Progress				7/1/2015 9:19:42 AM				
Marquez, Gerardo		NEED TO INSTALL DOOR AT METAL BLDG. ON WESTSIDE OF AUTOSHOP. THIS WILL BE THE SMALL DR. NEXT TO ROLL UP DR.							
Gerardo Marquez									
138657					8/25/2015		177		\$0.00
Medium	Work In Progress				8/25/2015 8:53:15 AM				
Apodaca, Mario		stainless steel fittings for the new UV system at the wastewater plant at ppd also to be installed							
Mario Apodaca									
144738	Maintenance	Pump House			12/9/2015		71		\$0.00
Medium	Work In Progress				12/9/2015 2:43:24 PM				
Apodaca, Mario		wastewater wet toxicity testing need to grab and sent out to water lab at sage environment Oklahoma city							
Mario Apodaca									
144354					12/4/2015		76		\$0.00
Medium	Work In Progress				12/4/2015 11:06:13 AM				
Miranda, Danny		Patch walls in Julie's old office.							
Albert Vallejo									
141694					10/14/2015		127		\$0.00
Medium	Work In Progress				10/14/2015 2:45:35 PM				
Lara, Ralph		Install a peephole at each South District school kitchen exit door. Please start with STMS per ergonomic evaluation.							
Cynthia Maes									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
141695					10/14/2015		127		\$0.00
Medium	Work In Progress				10/14/2015 2:47:58 PM				
Marquez, Gerardo	Install a peephole at each North District school kitchen exit door. Please start with LLE per ergonomic evaluation.								
Cynthia Maes									
146927	Main Warehouse				1/28/2016		21		\$0.00
Medium	Work In Progress				1/28/2016 2:56:14 PM				
Carrasco, Danny	Requesting cordless telephone for new maintenance warehouse.								
Danny Carrasco									
Count: 77 Work Orders		Avg. Age of WO's 63		Total for Physical Plant Complex				0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

147576 2/8/2016 10 \$0.00

Medium Work In Progress 2/8/2016 3:25:38 PM

Carrasco, Danny Need fuel for truck #76 and for gas operated tools, also need diesel fuel for 970 john deere tractor.

Mario Martinez

146666 1/25/2016 24 \$0.00

Medium Work In Progress 1/25/2016 12:03:11 PM

Lara, Ralph Need to replace portable door at science lab.

Mario Martinez

142151 10/22/2015 119 \$0.00

Medium Work In Progress 10/22/2015 11:02:29

Lara, Ralph Need Rafa L. to re key locks for water cabinet and gates. And to have two padlocks.

Mario Martinez

141608 10/13/2015 128 \$0.00

Medium Work In Progress 10/13/2015 2:22:23 PM

Castillo, Carlos Need Carlos C. to work on parking lot lights.

Mario Martinez

141609 10/13/2015 128 \$0.00

Medium Work In Progress 10/13/2015 2:24:23 PM

Castillo, Carlos Need Carlos C. to work on bad light poles at main entrance along palm trees.

Mario Martinez

146889 1/27/2016 22 \$0.00

Medium Work In Progress 1/27/2016 4:19:17 PM

Castillo, Carlos Please upgrade lighting in 6th grade restrooms.

Albert Vallejo

147698 2/10/2016 8 \$0.00

Medium Work In Progress 2/10/2016 7:50:14 AM

Orozco, Daniel as per email need to check warmers for missing parts

Daniel Orozco

143287 11/9/2015 101 \$0.00

Medium Work In Progress 11/9/2015 8:03:52 AM

Gonzalez, Salvador Need welder Sal to cut and reverse metal benches so that they face in opposite direction.

Mario Martinez

2/18/2016 11:23:49 AM

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
145798					1/7/2016		42		\$0.00
Medium	Work In Progress				1/7/2016 3:23:12 PM				
Moncayo, Fernando		AS PER ADELES MONITORING REPORT 1.7.16- DISHWASHER IS NOT WORKING. SNP MANAGER SANTA N.589.2550.							
Maritza Gonzalez									
145799					1/7/2016		42		\$0.00
Medium	Work In Progress				1/7/2016 3:24:58 PM				
Moncayo, Fernando		AS PER ADELES MONITORING REPORT 1.7.16- WALK IN STILL ACCUMILATING ICE. SNP MANAGER SANTA N.589.2550.							
Maritza Gonzalez									
143289					11/9/2015		101		\$0.00
Medium	Work In Progress				11/9/2015 8:15:00 AM				
Moncayo, Fernando		ICE IS BUILDING UP IN FREEZER ONCE AGAIN. SNP MANAGER SANTA NAVA 589.2550.							
Maritza Gonzalez									
145322					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:29 AM				
Martinez, Mario		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
145031					12/15/2015		65		\$0.00
Medium	Work In Progress				12/15/2015 9:14:00 AM				
Villalobos, David		12/15/2015 Need David V. to assist with faulty kitchen hot water heater.							
Mario Martinez									
147581					2/8/2016		10		\$0.00
Medium	Work In Progress				2/8/2016 3:30:49 PM				
Martinez, Mario		2/8/2016 Vandalism work order for break in on 2/7/2016.							
Mario Martinez									
147551					2/8/2016		10		\$0.00
Medium	Work In Progress				2/8/2016 8:39:27 AM				
Martinez, Mario		Need to replace four stolen fire extinguishers.							
Mario Martinez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
147156					1/31/2016	2/6/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:52:20 AM				
Martinez, Mario		Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
142708					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:11 AM				
Orozco, Daniel		Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
147541					2/7/2016	2/23/2016	11		\$0.00
Medium	Work In Progress				2/7/2016 12:32:01 AM				
Martinez, Mario		Monthly - Riverside ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
147808					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 2:49:12 PM				
Ontiveros, Guadalupe		Requesting fill soil for soccer field leveling.							
Mario Martinez									
147809					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 2:51:25 PM				
Ontiveros, Guadalupe		Requesting assistance with sprinkler valves and control boxes.							
Mario Martinez									
147933					2/16/2016		2		\$0.00
Medium	Work In Progress	Custodian Room			2/16/2016 3:35:27 PM				
Lara, Ralph		Need a spare key for the custodian room located on the 3rd grade hall - Mrs. Valenzuela. (Mrs. Martinez)							
Norma Martinez									
145640					1/5/2016		44		\$0.00
Medium	Work In Progress				1/5/2016 3:29:46 PM				
Martinez, Mario		Need to begin phase 2 of restroom renovations at North wing.							
Mario Martinez									
147791					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 10:27:33 AM				
Martinez, Mario		Need to replace two broken drain lines at Kinder wing.							
Mario Martinez									
2/18/2016 11:23:49 AM									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
146768					1/26/2016		23		\$0.00
Medium	Work In Progress				1/26/2016 3:16:58 PM				
Martinez, Mario		need to install 4 video surv. signs.							
Mario Martinez									
145503					1/4/2016		45		\$0.00
Medium	Work In Progress				1/4/2016 8:04:15 AM				
Gonzalez, Salvador		Need to repair damaged canopy poles at Kinder wing playground.							
Mario Martinez									
146770					1/26/2016		23		\$0.00
Medium	Work In Progress				1/26/2016 3:26:24 PM				
Martinez, Mario		1/26/2016 Need to replace all heating unit air filters.							
Mario Martinez									
140231					9/18/2015		153		\$0.00
Medium	Work In Progress				9/18/2015 2:33:41 PM				
Ambriz, Jose		Need Jose A. to check Library A/C unit which is still freeezing over.							
Mario Martinez									
144582					12/7/2015		73		\$0.00
Medium	Work In Progress				12/7/2015 2:41:11 PM				
Ambriz, Jose		Need Jose A. to replace cracked manifold for boiler at north wing.							
Mario Martinez									
146202					1/14/2016		35		\$0.00
Medium	Work In Progress				1/14/2016 8:30:00 AM				
Ambriz, Jose		Need Jose A. to trouble shoot faulty RTU at gym.							
Mario Martinez									
147858	Main Building	Custodial			2/12/2016		6		\$0.00
Medium	Work In Progress				2/12/2016 10:16:33 AM				
Carbajal, Jimmy		Could you fix me the wheelbarrow it has a flat tire. Thank you							
Miguel Sonora									
136101		Athletic Field			7/20/2015		213		\$0.00
Medium	Work In Progress				7/20/2015 7:40:36 AM				
Castillo, Carlos		need to run power for booster pump 240-single face-30 amps.							
Guadalupe Ontiveros									
2/18/2016 11:23:49 AM									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Riverside ES							
142531					10/29/2015		112		\$0.00
Medium	Work In Progress				10/29/2015 8:00:00 AM				
Gonzalez, Salvador		Need Sal to fabricate new ramps and stairs for new science portable.							
Mario Martinez									
Count: 32 Work Orders		Avg. Age of WO's	55			Total for Riverside ES	0		\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: RTC - Alliance									
143605					11/16/2015		94		\$0.00
Medium	Work In Progress				11/16/2015 7:02:31 AM				
Vallejo, Albert		Remove VCT floors to replace with linoleum.							
Albert Vallejo									
140563		Classroom			9/24/2015		147		\$0.00
Medium	Work In Progress				9/24/2015 11:44:03 AM				
Moncayo, Fernando		air conditioner is not working throwing hot air please send tech if not to cancel afternoon classes							
Gloria Delgado									
141681		Classroom			10/14/2015		127		\$0.00
Medium	Work In Progress	Ms. Hirsch			10/14/2015 11:27:51				
Moncayo, Fernando		Ms. Hirsch's class air conditioner has given out. She has tried to reset and turn back but has not worked. It has been 30 min. and has not turned on. Please send someone ASAP Student in class are complaining Thank you							
Gloria Delgado									
141364		Portables			10/9/2015		132		\$0.00
Medium	Work In Progress				10/9/2015 1:39:23 PM				
Gonzalez, Salvador		We have been donated by the Peak and iron grill and would like to place in the back by the office portable Thank you							
Gloria Delgado									
144375		Portables			12/4/2015		76		\$0.00
Medium	Work In Progress				12/4/2015 1:03:29 PM				
Moncayo, Fernando		need to replace an paint plank on office ramp area and secure nails in place Please call 882-6450 prior coming. We are gated now. Thank you							
Gloria Delgado									
Count: 5 Work Orders		Avg. Age of WO's 115		Total for RTC - Alliance		0		\$0.00	

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: San Miguel ES									
147135					1/31/2016		18		\$0.00
Medium	Work In Progress				1/31/2016 12:52:05 AM				
Apodaca, Mario	Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
146894	Classrooms				1/28/2016		21		\$0.00
Medium	Work In Progress				1/28/2016 7:30:18 AM				
Chavez, Santos	Alta De Las Flores Water Assoc. Portable and make sure lighting is working and adequate in area between portable and main building								
Alfredo Holguin									
145324					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:31 AM				
Ramirez, Joe	Yearly - San Miguel ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 3 Work Orders			Avg. Age of WO's	28		Total for San Miguel ES	0		\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

147970	Main Building				2/18/2016		0		\$0.00
Medium	Work In Progress	Main entrance			2/18/2016 8:31:06 AM				
Castillo, Carlos		Need to replace front door buzzard not working							
Juan Ambriz									

147539					2/7/2016	2/23/2016	11		\$0.00
Medium	Work In Progress				2/7/2016 12:31:59 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									

140070	Main Building	Parking Lot			9/16/2015		155		\$0.00
Medium	Work In Progress	Exterior lighting			9/16/2015 12:03:20 PM				
Castillo, Carlos		Need to replace some exterior lighting							
Juan Ambriz									

145864	Main Building	Exterior			1/8/2016		41		\$0.00
Medium	Work In Progress	Playgrounds			1/8/2016 9:26:59 AM				
Ambriz, Juan		Need to replace swings							
Juan Ambriz									

140238	Main Building	Classroom			9/18/2015		153		\$0.00
Medium	Work In Progress	Room 101			9/18/2015 3:01:26 PM				
Lara, Ralph		Please make 2 keys for room 101. One if for Ms. Linck and the other one is a backup key for school. Key							
Rita Mendez									

146825					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 8:37:07 AM				
Ambriz, Juan		Need one surveillance sign.							
Juan Ambriz									

146521					1/21/2016		28		\$0.00
Medium	Work In Progress				1/21/2016 3:22:23 PM				
Moncayo, Fernando		3 COMPARTMENT SINK FACUETS LEAKING. SNP MANAGER MARINA R. 589.3439							
Maritza Gonzalez									

141504					10/12/2015		129		\$0.00
Medium	Work In Progress				10/12/2015 2:01:47 PM				
Orozco, Daniel		AS PER ADELE'S MONITORING REPORT 10.12.15 FLOOR IN WALK IN IS LIFTING. SNP MANAGER MARINA R. 589.3439							
Maritza Gonzalez									

2/18/2016 11:23:49 AM									
-----------------------	--	--	--	--	--	--	--	--	--

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
136192					7/21/2015		212		\$0.00
Medium	Work In Progress				7/21/2015 11:28:26 AM				
Gonzalez, Salvador		Attach ramps to portables.							
Albert Vallejo									
145863					1/8/2016		41		\$0.00
Medium	Work In Progress				1/8/2016 9:24:42 AM				
Ambriz, Juan		Need to replace tools							
Juan Ambriz									
147711	Main Building	Exterior			2/10/2016		8		\$0.00
Medium	Work In Progress	Front main			2/10/2016 10:52:18 AM				
Ambriz, Juan		Need to Install NO PARKING signs all across main street due to congestion at the end of the day due to new houses							
Juan Ambriz									
146893					1/28/2016		21		\$0.00
High	Work In Progress				1/28/2016 7:19:23 AM				
Moncayo, Fernando		WALK IN FREEZER IS AT 44 DEGREES.SNP MANAGER MARINA R. 589.3439							
Maritza Gonzalez									
146042	Main Building	Exterior			1/12/2016		37		\$0.00
Medium	Work In Progress	outside wall of			1/12/2016 8:43:11 AM				
Castillo, Carlos		Need to replace lights							
Juan Ambriz									
145328					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:34 AM				
Ambriz, Juan		Yearly - Santa Teresa ES Backflow Inspection - Refer to PMs schedule details.							
Margret Villalobos									
142709					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:11 AM				
Orozco, Daniel		Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PMs schedule details.							
Margret Villalobos									
Count: 15 Work Orders			Avg. Age of WO's	68		Total for Santa Teresa ES	0		\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

144359	Main Building	Classroom			12/4/2015		76		\$0.00
Medium	Work In Progress	nurses office			12/4/2015 11:11:12 AM				
Miranda, Danny		Cover tubing in restroom. New toilet needs to be connected and sink.							
Lorraine Dominguez									

143846					11/19/2015		91		\$0.00
Medium	Work In Progress	Nurses Office			11/19/2015 1:31:03 PM				
Miranda, Danny		Please fur out wall in Nurses Office at STHS to cover plumbing and water heater (see David Villalobos for specifics)							
Albert Vallejo									

144910		Athletic Field			12/11/2015		69		\$0.00
Medium	Work In Progress				12/11/2015 3:54:51 PM				
Ontiveros, Guadalupe		need fence put up around third base softball dugout using existing/recycled chain link and poles.							
		To be done by Grounds Dept.							
Rick Llanez									

141349	Locker Room	Hallway/Corridor			10/9/2015		132		\$0.00
Medium	Work In Progress				10/9/2015 8:50:43 AM				
Lara, Ralph		Fire Door Magnetic Door Holder mounted on the wall is lose it and looks damaged. It needs to be replaced if necessary and re-attached to the wall							
Alfredo Holguin									

141547	GYM (2009)	Athletic Field			10/12/2015		129		\$0.00
Medium	Work In Progress	Baseball			10/12/2015 3:46:32 PM				
Gonzalez, Salvador		Need for batting caged to be removed to replace with pitching mounds. Requesting two frames for two more batting cages.							
Lorraine Dominguez									

146916					1/28/2016		21		\$0.00
Medium	Work In Progress				1/28/2016 12:47:20 PM				
Hernandez, Carlos		need these tools tool pouch 11 pocket polyester black item# 5LF11 \$49.50 cordless screwdriver kit 12- 1/2in item# 24WY33 \$130.05 step drill bit set cobalt item#2CJR9 \$97.00 double face sledge hammer 1.b head weight 1-1/2 item 21YT89 \$64.60 Maglite hand held black item 8EX25 \$26.55							
Carlos Hernandez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
144363	Cafeteria (2005)	Cafeteria			12/4/2015		76		\$0.00
Medium	Work In Progress	Cafeteria			12/4/2015 11:15:15 AM				
Lucero, Arnold		Clean buff, and wax floor in cafeteria							
Lorraine Dominguez									
144361	Main Building	Classroom			12/4/2015		76		\$0.00
Medium	Work In Progress	nurses office			12/4/2015 11:13:17 AM				
Lucero, Arnold		Waxand clean floors							
Lorraine Dominguez									
145714					1/6/2016		43		\$0.00
Medium	Work In Progress	300			1/6/2016 2:16:17 PM				
Marquez, Gerardo		Please contract to install work stations at film lab area where sinks will be removed. See Albert for further instruction.							
Albert Vallejo									
145785					1/7/2016		42		\$0.00
Medium	Work In Progress				1/7/2016 11:20:44 AM				
Vallejo, Albert		Need Aluminum sign for new marquee to be placed below the marquee between the poles. One sign will read "Tribe of 2014" and the other "Tribe of 2015"							
Alfredo Holguin									
147784					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 8:38:04 AM				
Ronquillo, Ruben		2/11/2016 Need to replace broken window in the reception area. 36" 1/4 x 42". Single window light black tint.							
David Diaz									
145877					1/8/2016		41		\$0.00
Medium	Work In Progress				1/8/2016 3:10:36 PM				
Ronquillo, Ruben		1/8/16 Requesting to install two new windows for room 309.							
David Diaz									
135788	Gymnasium	Classroom			7/13/2015		220		\$0.00
Medium	Work In Progress	weightroom			7/13/2015 2:34:55 PM				
Estrada, Jesus		floor in weight room is lifting							
Lorraine Dominguez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

146671	Main Building	Cafeteria			1/25/2016		24		\$0.00
Medium	Work In Progress	Stage area			1/25/2016 2:06:33 PM				
Carbajal, Jimmy		Theater curtain is torn and needs mending.			As per Albert, assign to Jimmy C.				
Lorraine Dominguez									

147956	GYM (2009)	Athletic Field			2/16/2016		2		\$0.00
Medium	Work In Progress	FRANK MUNOZ			2/16/2016 3:51:32 PM				
Carrasco, Danny		CAN YOU PLEASE DELIVER 3 GALLONS OF GASOLINE TO STHS - TRAINER FRANK MUNOZ FOR THE GATOR?							
		THANKS, TERRY							
Terry Alvarado									

143655	Main Building	Gym			11/16/2015		94		\$0.00
Medium	Work In Progress	locker rooms			11/16/2015 3:40:06 PM				
Villalobos, David		shower head and handles need to be replaced within the lockerrooms							
Lorraine Dominguez									

147925	Main Building	Parking Lot			2/16/2016		2		\$0.00
Medium	Work In Progress	Guard shack			2/16/2016 3:01:44 PM				
Vallejo, Albert		Guard shack is in dire need of repair. Please see David for further direction							
Lorraine Dominguez									

147399		Office			2/4/2016		14		\$0.00
Medium	Work In Progress				2/4/2016 9:23:55 AM				
Gonzales, Camilo		Deliver 2 cows, PO# 151604292. Thank you.							
Theresa Ramirez									

147404	GYM (2009)				2/4/2016		14		\$0.00
Medium	Work In Progress				2/4/2016 10:49:31 AM				
Ontiveros, Guadalupe		LUPE, CAN YOU PLEASE PICKUP 40 HURDLES FROM SANTA TERESA HS AND THE HIGH JUMP PIT WITH THE CROSS BAR AND STANDARDS FROM THE TRACK COACH. MS. NOUGUES WILL INFORM MRS. SORIANO AND COACH SOLIS ABOUT US BORROWING THE ITEMS.							
		THANKS, TERRY							
Terry Alvarado									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
143379	Main Building	Classroom			11/10/2015		100		\$0.00
Medium	Work In Progress	215			11/10/2015 10:55:05				
Lara, Ralph		Door needs to be moved to room 215, please see Mrs. Soriano							
Lorraine Dominguez									
144362	Main Building	Classroom			12/4/2015		76		\$0.00
Medium	Work In Progress	nurses office			12/4/2015 11:14:14 AM				
Lara, Ralph		change door knob on door							
Lorraine Dominguez									
143604					11/15/2015		95		\$0.00
Medium	Work In Progress				11/15/2015 12:27:55				
Flores, Pete		Yearly - Santa Teresa HS - Mower 0425 - Grounds - Refer to PM schedule details.							
Margret Villalobos									
146425	GYM (2009)	Gym			1/20/2016		29		\$0.00
Medium	Work In Progress	Varsity Gym			1/20/2016 9:29:19 AM				
Gonzales, Camilo		We need three mats from GHS that will be labeled to be brought to Santa Teresa High School for GISD Spirit Event which will take place on Feb. 27, 2016. We would like to have mats here early Friday to set up for event.							
Lorraine Dominguez									
146667	Main Building	Gym			1/25/2016		24		\$0.00
Medium	Work In Progress	varsity gym			1/25/2016 12:24:19 PM				
Gonzales, Camilo		Transport mats from athletic warehouse to Santa Teresa High School on 02/26/2016 for event on 02/27/2016 there should be nine mats and another three from Gadsden High School. Please see Karen for storage of mats at warehouse.							
Lorraine Dominguez									
142733					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:27 AM				
Vallejo, Albert		Monthly - Santa Teresa HS Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
142710					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:12 AM				
Orozco, Daniel		Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

137214	Library	Library			8/4/2015		198		\$0.00
--------	---------	---------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	library			8/4/2015 2:28:04 PM				
--------	------------------	---------	--	--	---------------------	--	--	--	--

Lara, Ralph Emergencydoors not functioning

Lorraine Dominguez

135501	Library	Hallway/Corridor			7/6/2015		227		\$0.00
--------	---------	------------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	200 Hall Student			7/6/2015 10:50:05 PM				
--------	------------------	------------------	--	--	----------------------	--	--	--	--

Lara, Ralph Please replace all existing stall partitions with new black partitions due to heavy graffiti

Nicholas Wohlgemuth

141057		Classroom			10/5/2015		136		\$0.00
--------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	MR.			10/5/2015 1:03:46 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Diaz, David LAB C-4 NEEDS BOARD MOUNTED.

Marylou Jimenez

136365	Main Building	Classroom			7/23/2015		210		\$0.00
--------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	410			7/23/2015 2:57:12 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Diaz, David Take down board and replace with bulletin board please see Ms. Soriano

Lorraine Dominguez

136366	Main Building	Classroom			7/23/2015		25		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	500			7/23/2015 2:57:44 PM	8/17/2015			
--------	------------------	-----	--	--	----------------------	-----------	--	--	--

Diaz, David Baseboard behind teacher desk needs replacing

Lorraine Dominguez

141562	Vocational	Classroom			10/12/2015		129		\$0.00
--------	------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	805			10/12/2015 3:53:51 PM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Diaz, David In need of changing light bulbs

Lorraine Dominguez

145711					1/6/2016		43		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/6/2016 2:06:46 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo Please install a 6' door between rooms 700 and 702.
Door should be situated at the south end of dividing wall.
See admin for further instruction.

Albert Vallejo

144169	Locker Room	Dressing Room			12/2/2015		78		\$0.00
--------	-------------	---------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/2/2015 8:19:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Miranda, Danny The wall directly behind the urinal is rotted out and needs to be replaced.

David Villalobos

2/18/2016 11:23:49 AM

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
144126	Main Building	Storage			12/1/2015		79		\$0.00
Medium	Work In Progress	Equipment			12/1/2015 3:40:22 PM				
Hernandez, Carlos		Please replace light fixtures in storage areas soccer, track/football storage room all connected areas.							
Lorraine Dominguez									
147479					2/5/2016		13		\$0.00
Medium	Work In Progress				2/5/2016 1:39:26 PM				
Hernandez, Carlos		need air filters for units in café area							
Carlos Hernandez									
147805					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 1:53:49 PM				
Hernandez, Carlos		water hose 50ft item #20L429 5/8 \$39.15 nee qty 3 to clean Hvac units and closet auger 6ft, 1/2in cable w/bulb item #4cx11 \$77.90 qty 2							
Carlos Hernandez									
147928					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 3:18:18 PM				
Hernandez, Carlos		as per albert need to remove main gate latches and touch up paint							
Carlos Hernandez									
143494	GYM (2009)				11/12/2015		0		\$0.00
Medium	Work In Progress				11/12/2015 3:44:07 PM	11/12/2015			
Lara, Ralph		DOORS NEED TO BE AJUSTED AND REPALED LACHES ON ALL DOORS AT GYM EXIT DOORS.							
Ralph Lara									
136357	Main Building	Restroom			7/23/2015		210		\$0.00
Medium	Work In Progress	300 hallway			7/23/2015 2:41:30 PM				
Lara, Ralph		Bathroom stalls need replacing, door is missing on one of them and theyare in bad shape							
Lorraine Dominguez									
136350	Main Building	Classroom			7/23/2015		210		\$0.00
Medium	Work In Progress	209			7/23/2015 2:34:10 PM				
Diaz, David		Please paint where tv stand was removed.							
Lorraine Dominguez									
136351	Main Building	Restroom			7/23/2015		210		\$0.00
Medium	Work In Progress	by library			7/23/2015 2:35:07 PM				
Diaz, David		Ceiling needs painting							
Lorraine Dominguez									
2/18/2016 11:23:49 AM									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
146054					1/12/2016		37		\$0.00
Medium	Work In Progress			1/12/2016 12:06:39 PM					
Castillo, Carlos	Run 20 amp-120v circuit for new marquee.								
Carlos Castillo									
146519					1/21/2016		28		\$0.00
Medium	Work In Progress			1/21/2016 2:54:04 PM					
Moncayo, Fernando	MILK COOLER COVER IS COMING OFF. SNP MANAGER OLGA B.589.5332								
Maritza Gonzalez									
142154					10/22/2015		119		\$0.00
Medium	Work In Progress			10/22/2015 11:20:31					
Orozco, Daniel	need to add lighting to walk in refrigerator								
Daniel Orozco									
141374					10/9/2015		132		\$0.00
Medium	Work In Progress			10/9/2015 2:17:00 PM					
Orozco, Daniel	WALK IN FLOOR PANELS ARE RISING, SAFETY HAZARD. SNP MANAGER OLGA B. 589.5332								
Maritza Gonzalez									
136482					7/27/2015		206		\$0.00
Medium	Work In Progress			7/27/2015 7:56:16 AM					
Flores, Pete	7/27/14 Can you please see if you can do an oil change on company truck (141). Was checking oil and it looks pretty bad, also if you can check the turn signals they don't work. Truck 141 is located at STHS Thanks								
David Diaz									
145713					1/6/2016		43		\$0.00
Medium	Work In Progress	300		1/6/2016 2:13:52 PM					
Villalobos, David	Please remove film lab stainless steel sinks and cap water and sewer connections.								
Albert Vallejo									
142007					10/20/2015		121		\$0.00
Medium	Work In Progress			10/20/2015 1:27:58 PM					
Villalobos, David	Boys soccer locker room urinal needs to be replaced.								
Jaime Mijarez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
141730					10/14/2015		127		\$0.00
Medium	Work In Progress				10/14/2015 3:45:49 PM				
Villalobos, David		Nurses restroom toilet is leaking water from Tank.							
Jaime Mijarez									
141581					10/13/2015		128		\$0.00
Medium	Work In Progress				10/13/2015 7:49:59 AM				
Villalobos, David		need to replace missing shower handles at girls and boys lockerooms							
David Villalobos									
147482		Kitchen			2/5/2016		13		\$0.00
Medium	Work In Progress				2/5/2016 1:58:16 PM				
Moncayo, Fernando		Dishwasher machine leaking water							
Dino Facio									
146980					1/29/2016		20		\$0.00
Medium	Work In Progress				1/29/2016 9:51:33 AM				
Carrasco, Danny		NEED BUBBLE COVER FOR FIRE EXTINGUISHERS							
Carlos Hernandez									
145830					1/7/2016		42		\$0.00
Medium	Work In Progress				1/7/2016 3:55:49 PM				
Gonzalez, Salvador		Install window guards on 700-702							
Albert Vallejo									
147239					2/1/2016		17		\$0.00
Medium	Work In Progress				2/1/2016 4:13:12 PM				
Marquez, Gerardo		NEED TO GET A PRICE QUOTE FOR INSATALLATION OF A 6-0X7-0 DR TO NEW ENGINERING RM.							
Gerardo Marquez									
146984					1/29/2016		20		\$0.00
Medium	Work In Progress				1/29/2016 10:36:18 AM				
Lara, Ralph		1/29/16 Need to replace Complete steel doors and frames from the ROTC building. Doors are falling from hinges.							
David Diaz									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS									
147716					2/10/2016		8		\$0.00
Medium	Work In Progress				2/10/2016 12:36:10 PM				
Ambriz, Jose		2/10/16							
		Ice maker in Trainers office evap. nickel worn out and ice is not releasing. Need to be replaced							
David Diaz									
144110	Main Building	Hallway/Corridor			12/1/2015		79		\$0.00
Medium	Work In Progress	outside locker			12/1/2015 3:09:51 PM				
Diaz, David		Order paint and paint a stripe turquoise color in hallway leading out to football field please see Mrs. Soriano for this. Also we probably need to order the vanilla bean color to touch up the wall after work was done in hallway and locker room area.							
Lorraine Dominguez									
147186					2/1/2016		17		\$0.00
Medium	Work In Progress				2/1/2016 12:59:15 PM				
Castillo, Carlos		need to replace light fixtures in equipment room							
Carlos Hernandez									
145712					1/6/2016		43		\$0.00
Medium	Work In Progress				1/6/2016 2:11:24 PM				
Castillo, Carlos		Please establish circuits for new computer lab at room 700 (directly next to pump room)							
Albert Vallejo									
145721					1/6/2016		43		\$0.00
Medium	Work In Progress				1/6/2016 3:30:29 PM				
Castillo, Carlos		Please remove dark room lights and replace with 2'x4' LED lay in fixtures.							
Albert Vallejo									
145347					1/3/2016	1/11/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:51 AM				
Diaz, David		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
145326					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:33 AM				
Hernandez, Carlos		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
145710					1/6/2016		43		\$0.00
Medium	Work In Progress				1/6/2016 2:01:27 PM				
Ontiveros, Guadalupe		Please establish xeriscaping and raised planters at entrance sidewalk between portables and barracks buildings							
Albert Vallejo									
147782					2/11/2016		7		\$0.00
Medium	Work In Progress				2/11/2016 8:26:41 AM				
Holguin, Alfredo		Running Track - Repair cracks in rubberized surface							
Alfredo Holguin									
146848		Athletic Field			1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 2:33:21 PM				
Holguin, Alfredo		Football field Artificial Turf - Perform SportChamp deep cleaning service, Seam Repairs and add infill Rubber							
Alfredo Holguin									
147668		Athletic Field			2/9/2016		9		\$0.00
Medium	Work In Progress				2/9/2016 3:51:16 PM				
Ontiveros, Guadalupe		The old goal post needs to be removed along with the small makeshift backstop. Both of these are in the grass area east of the softball field. I will need some help in removing them.							
Rick Llanez									
145988					1/11/2016		38		\$0.00
Medium	Work In Progress				1/11/2016 12:22:05 PM				
Villalobos, David		trouble resetting water heater in mechanical room							
Carlos Hernandez									
147105					1/31/2016	3/2/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:43 AM				
Diaz, David		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
147106					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:43 AM				
Diaz, David		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
147107					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:44 AM				
Diaz, David		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
145363					1/3/2016	1/24/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:44:05 AM				
Vallejo, Albert		Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
141435					10/11/2015	10/27/2015	130		\$0.00
Medium	Work In Progress				10/11/2015 12:28:46				
Lucero, Arnold		Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.							
Jesus Estrada									
Count: 73 Work Orders			Avg. Age of WO's	71	Total for Santa Teresa HS		0	0	\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
140794					9/30/2015		141		\$0.00
Medium	Work In Progress				9/30/2015 12:43:18 AM				
Prospero, Manuel		Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.							
Margret Villalobos									
142711					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:13 AM				
Orozco, Daniel		Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
147325	South Building	Restroom			2/3/2016		15		\$0.00
Medium	Work In Progress	WOMENS			2/3/2016 10:35:51 AM				
Villalobos, David		PLEASE FIX HANDLE ON THE WOMENS BATHROOM TOILET IN THE SOUTH OFFICE. IT RUNS CONTINUOUSLY AND WILL NOT FLUSH PROPERLY							
Laura Parra									
147910	North Building	Cafeteria			2/16/2016		2		\$0.00
Medium	Work In Progress	MS GESSICA			2/16/2016 7:32:19 AM				
Villalobos, David		UNCLOG THE REGULAR SINK DRAIN. WATER OVERFLOWS							
Laura Parra									
145327					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:34 AM				
Prospero, Manuel		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
143316	South Building	Office			11/9/2015		101		\$0.00
Medium	Work In Progress	SOUTH OFFICE			11/9/2015 2:24:01 PM				
Prospero, Manuel		PAINTE ALL TRIM INSIDE AND OUTSIDE OF OFFICES AND RESTROOMS-BLACK PAINT							
Laura Parra									
145694	North Building	Classroom			1/6/2016		43		\$0.00
Medium	Work In Progress	9-CORDOVA			1/6/2016 9:48:23 AM				
Lara, Ralph		METAL FILING CABINET NEEDS TO BE RE-KEYED. CABINET IS LOCKED							
Laura Parra									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
146414	North Building	Cafeteria			1/20/2016		29		\$0.00
Medium	Work In Progress				1/20/2016 7:31:19 AM				
Lara, Ralph		NEED TO REPLACED OLD DOORS AT CAFETERIA BACK EXIT ENTERANCE.							
Ralph Lara									
146083					1/12/2016		37		\$0.00
Medium	Work In Progress				1/12/2016 3:41:57 PM				
Prospero, Manuel		1/12/16. .5HR CHECK E MAIL. 2HRS CHEKING HEATERS CAFETERIA. 2HRS TROUBLE SOOTER HEATERS PORTABLE 2 AND NURCES OFFICE. 3HRS WO 146077. .5HR ENTER LOG.							
Manuel Prospero									
146142	North Building	Custodial			1/13/2016		36		\$0.00
Medium	Work In Progress				1/13/2016 11:06:43 AM				
Flores, Pete		Pressure washer doesn't work need to be fix..							
Ismael Rodriguez									
145706					1/6/2016		43		\$0.00
Medium	Work In Progress				1/6/2016 1:39:20 PM				
Moncayo, Fernando		Will you please submit a work order for my two old school ovens, sometimes the units heat up and sometimes they don't. the problem seems to be getting worse.							
Maritza Gonzalez									
143198					11/6/2015		104		\$0.00
Medium	Work In Progress				11/6/2015 11:27:44 AM				
Moncayo, Fernando		ON/OFF SWIETCH FROM EXHAUST FAN IN STORAGE AND WALK IN AREA ARE BROKEN. SNP MANAGER GESSICA M. 589.9836							
Maritza Gonzalez									
144091					12/1/2015		79		\$0.00
Medium	Work In Progress				12/1/2015 11:45:10 AM				
Moncayo, Fernando		2 OVENS - DIALS ARE NOT WORKING CORRECTLY. SNP MANAGER GESSICA M. 589.9836							
Maritza Gonzalez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
139197					9/2/2015		169		\$0.00
Medium	Work In Progress				9/2/2015 8:03:32 AM				
Gonzalez, Salvador		A LEVER NEEDS TO BE WELDED ON A GATOR SO WE CAN CHECK THE FLUID LEVELS ON THE ENGINE							
Laura Parra									
139067	North Building	Classroom			8/31/2015		171	1	\$25.00
Medium	Work In Progress	9 CORDOVA			8/31/2015 3:25:43 PM				
Prospero, Manuel		LEAK IN CEILING AGAINST THE WALL				9/1/15 - Manuel please check roof, as per David V. Teacher says it's from rain			
Laura Parra									
145796					1/7/2016		42		\$0.00
Medium	Work In Progress				1/7/2016 3:00:35 PM				
Orozco, Daniel		As per Jackie- Please ask Danny if he can install the portable pass thru warmer to help out with production.							
Maritza Gonzalez									
141506					10/12/2015		129		\$0.00
Medium	Work In Progress				10/12/2015 2:28:22 PM				
Orozco, Daniel		HANDLE FOR HOT WATER ON DISHWASHER AREA IS BROKEN. SNP MANAGER GESSICA M. 589.9836							
Maritza Gonzalez									
140642	South Building	Office			9/25/2015		146		\$0.00
Medium	Work In Progress	SEE MR.			9/25/2015 2:51:51 PM				
Prospero, Manuel		BROKEN TILES/SHEETROCK IN BOYS RESTROOMS UP STAIRS AND DOWN STAIRS.							
Laura Parra									
142535	North Building	Classroom			10/29/2015		112		\$0.00
Medium	Work In Progress				10/29/2015 9:59:44 AM				
Prospero, Manuel		AFTER SERVICING DRYER, CONTINUES NOT TO DRY CLOTHES. NO HEAT							
Laura Parra									
138771	North Building	Parking Lot			8/26/2015		176		\$0.00
Medium	Work In Progress	PARKING LOT			8/26/2015 11:12:25 AM				
Castillo, Carlos		SOME LIGHTS IN THE PARKING LOT DO NOT TURN ON- BULBS MAY BE WORN OUT							
Laura Parra									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa MS							
138502		Restroom			8/21/2015		181		\$0.00
Medium	Work In Progress				8/21/2015 1:34:48 PM				
Lara, Ralph		Please acquire quote for urinal partitions 18' for boys restrooms.							
Albert Vallejo									
140159	South Building	Office			9/17/2015		154		\$0.00
Medium	Work In Progress	SECURITY-MR			9/17/2015 1:10:33 PM				
Prospero, Manuel		1-RE PAINT NO PARKING FIRE LANE 2- NEED SIGNS "NO PARKING AT ANY TIME" ON SOUTH GATE ENTRANCE							
Laura Parra									
141421					10/9/2015		132		\$0.00
Medium	Work In Progress	Outside Exit of			10/9/2015 4:17:37 PM				
Vallejo, Albert		Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.							
Cynthia Maes									
141508					10/12/2015		129		\$0.00
Medium	Work In Progress				10/12/2015 2:32:47 PM				
Prospero, Manuel		CEILING TILES ON STORAGE AREA ARE STAINED FROM WATER LEAK. SNP MANAGER GESSICA M. 589.9836.							
Maritza Gonzalez									
141509					10/12/2015		129		\$0.00
Medium	Work In Progress				10/12/2015 2:34:34 PM				
Prospero, Manuel		AS PER ADEL'S MONITORING REPORT. DENTS ON WALK IN HALL AND BATHROOM WALLS.							
Maritza Gonzalez									
139307	North Building	Office			9/3/2015		168		\$0.00
Medium	Work In Progress	ASST			9/3/2015 3:22:50 PM				
Lara, Ralph		OUTSIDE DOOR IN ASST PRINCIPALS OFFICE DOES NOT WORK PROPERLY. HARD TO OPEN AND CLOSE							
Laura Parra									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
141507					10/12/2015		129		\$0.00
Medium	Work In Progress				10/12/2015 2:30:14 PM				
Lara, Ralph		GAP ON MAIN OUTSIDE DOORS STILL HAVE GAP (PREVIOUS WORK ORDER SUBMITTED 127544 SHOWS COMPLETE). SNP MANAGER GESSICA M. 589.9836							
Maritza Gonzalez									
139979					9/15/2015		156		\$0.00
Medium	Work In Progress				9/15/2015 12:50:46 PM				
Lara, Ralph		Install a door in security office hallway. As per Administration, the office needs to secure confiscated items. See security officer for details.							
Albert Vallejo									
141419					10/9/2015		132		\$0.00
Medium	Work In Progress	Kitchen			10/9/2015 4:05:33 PM				
Lara, Ralph		Bugs, dirt and trash enter through unsealed doors. Need to fix problem, please inspect and repair. Food inspector has already been there and is expected to return to check if the problem has been repaired. Call Cynthia with any questions 882-6949.							
Cynthia Maes									
141420					10/9/2015		132		\$0.00
Medium	Work In Progress	Kitchen			10/9/2015 4:13:39 PM				
Lara, Ralph		Dining room doors are being secured with chains and pad locks. Inspect and repair so that pad locks don't need to be used. As per ergonomic inspections an access route to this clear space must be maintained at all times. Please call Cynthia with any questions 882-6949							
Cynthia Maes									
142734					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:28 AM				
Vallejo, Albert		Monthly - Santa Teresa MS Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
147650	Gym (1997)	Dressing Room			2/9/2016		9		\$0.00
Medium	Work In Progress				2/9/2016 3:22:17 PM				
Lara, Ralph		WE NEED FIX BROKEN DOOR HANDLE							
Manuel Prospero									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
143603					11/15/2015		95		\$0.00
Medium	Work In Progress				11/15/2015 12:27:54				
Flores, Pete		Yearly - Santa Teresa MS - Mower 0416 - Grounds - Refer to PM schedule details.							
Margret Villalobos									
146077	South Building	Classroom			1/12/2016		37		\$0.00
Medium	Work In Progress				1/12/2016 3:35:17 PM				
Prospero, Manuel		1/12/16. HAVING PROBLEMS HEATER ROOM 31.							
Manuel Prospero									
145200	South Building				12/17/2015		63		\$0.00
Medium	Work In Progress				12/17/2015 10:20:58				
Mijarez, Jaime		Room 31 - please check unit, unable to reset in Tracer.							
Albert Vallejo									
138255	Gym (1997)				8/18/2015		184		\$0.00
Medium	Work In Progress				8/18/2015 3:34:23 PM				
Vallejo, Albert		The scorers table on the bleachers need to be repaired or replaced							
Alfredo Holguin									
136401		Office			7/23/2015		210		\$0.00
Medium	Work In Progress				7/23/2015 4:17:14 PM				
Marquez, Gerardo		PLEASE GET A PRICE QUOTE FOR NEW STAFF MAILBOX AND BASE CABINETS FOR WORKRM.							
Gerardo Marquez									
147955					2/16/2016		2		\$0.00
Medium	Work In Progress				2/16/2016 3:51:15 PM				
Gonzalez, Salvador		Construct batting cages (see Albert for drawings)							
Albert Vallejo									
143567					11/13/2015		97		\$0.00
Medium	Work In Progress				11/13/2015 3:39:42 PM				
Prospero, Manuel		11/13/15. .5HR CHECK EMAIL. 4HRS WO 140902. 3HRS WO 142852. .5HR ENTER LOG.							
Manuel Prospero									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Santa Teresa MS							
141985	South Building				10/20/2015		121		\$0.00
Medium	Work In Progress				10/20/2015 8:06:34 AM				
Miranda, Danny	Security Office - cover two pocket doors in hallway leading to office- tape texture and paint								
Alfredo Holguin									
Count: 40 Work Orders		Avg. Age of WO's	102	Total for Santa Teresa MS				1	\$25.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location:		Sunland Park ES							
142788					11/1/2015	11/9/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:55:04 AM				
Mijarez, Jaime	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
147148					1/31/2016	2/6/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:52:14 AM				
Mijarez, Jaime	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
147530					2/7/2016	2/23/2016	11		\$0.00
Medium	Work In Progress				2/7/2016 12:31:53 AM				
Mijarez, Jaime	Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
142712					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:13 AM				
Orozco, Daniel	Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
141920	Main Building	Parking Lot			10/19/2015		122		\$0.00
Medium	Work In Progress				10/19/2015 11:06:16				
Mijarez, Jaime	South Side of Building/Back Entries - cut and remove weeds.		Route to Jaime on 11/16/15						
Alfredo Holguin									
141417	Main Building				10/9/2015		132		\$0.00
Medium	Work In Progress				10/9/2015 4:04:12 PM				
Ontiveros, Guadalupe	Front Entrance - Purchase and replace 1 missing palm tree.								
Alfredo Holguin									
145325					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:32 AM				
Mijarez, Jaime	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

146649					1/25/2016		24		\$0.00
Medium	Work In Progress				1/25/2016 8:26:39 AM				
Castillo, Carlos		Main office printer relocation. Please relocate electrical connection for big printer.							
Jaime Mijarez									

143762		Library			11/18/2015		92		\$0.00
Medium	Work In Progress	LIBRARY			11/18/2015 8:22:59 AM				
Mijarez, Jaime		LIBRARY- MORENO- NEED DOORS PAINTED BLUE SEE MRS. MORENO							
Maribel Gamboa									

143763		Library			11/18/2015		92		\$0.00
Medium	Work In Progress	LIBRARY			11/18/2015 8:25:55 AM				
Mijarez, Jaime		LIBRARY- MORENO- NEED TO HAVE PAINTING FINISHED IN LIBRARY WALLS. LIGHT ARE STILL NOT TURNING ON COMPLETELY							
Maribel Gamboa									

144739					12/9/2015		71		\$0.00
Medium	Work In Progress				12/9/2015 3:19:12 PM				
Mijarez, Jaime		Paint portable interior walls with Vanilla Bean paint. I need 5 gallons.							
Jaime Mijarez									

147643					2/9/2016		9		\$0.00
Medium	Work In Progress				2/9/2016 1:17:02 PM				
Lara, Ralph		Main Administrative Office. Need to replace old hydraulic door closer with a new one. I tried to adjust but no luck.							
Jaime Mijarez									

145160					12/16/2015		64		\$0.00
Medium	Work In Progress				12/16/2015 3:43:28 PM				
Lara, Ralph		OFFICE - NEED TO HAVE A SMALL SAFE LOOK AT FOR COMBINATION							
Maribel Gamboa									

144765					12/9/2015		71		\$0.00
Medium	Work In Progress				12/9/2015 3:53:31 PM				
Gonzalez, Salvador		metal gate on rock wall keeps falling off from the hinge. Gate is heavy and can hurt a kid if it falls off completely. I have already repaired it, but keeps coming off from one of the hinges. Contact Jaime.							
Jaime Mijarez									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
146362		Classroom			1/19/2016		30		\$0.00
Medium	Work In Progress	21			1/19/2016 12:53:31 PM				
Mijarez, Jaime		RM#21 - PEREZ- EXTENTION CORD FOR COMPUTER. PAINT AROUND WHITEBOARD. NAILS TO HANG WHITEBOARD. SHELVES IN LANDRY ROOM FOR STORAGE.							
Maribel Gamboa									
145703		Classroom			1/6/2016		43		\$0.00
Medium	Work In Progress	21			1/6/2016 11:46:56 AM				
Mijarez, Jaime		RM#21- CLAUDIA PEREZ- 1) UTILITY SHLVE ON TOP OF WASHER AND DRY. 2) PAINT AROUND HITACHI BOARD 3) NAILS ON WALL FOR BULLETIN BOARD 4) 1 LONG TABLE FOR COMPUTERS 5) TEACHER DESK							
Maribel Gamboa									
146581					1/22/2016		27		\$0.00
Medium	Work In Progress	21			1/22/2016 9:43:54 AM				
Mijarez, Jaime		RM#21- PEREZ- NEED A TEACHERS DESK PLEASE							
Maribel Gamboa									
146907					1/28/2016		21		\$0.00
Medium	Work In Progress				1/28/2016 10:50:25 AM				
Mijarez, Jaime		RM#18- MARQUEZ- CLASSROOM IS EXTREMELY HOT							
Maribel Gamboa									
146909					1/28/2016		21		\$0.00
Medium	Work In Progress				1/28/2016 11:39:21 AM				
Mijarez, Jaime		LIBRARY- MORENO- NEED TO HAVE LIBRARY TABLES LEGS TIGHTEN. Table have become very woobly.							
Maribel Gamboa									
145195					12/17/2015		63		\$0.00
Medium	Work In Progress	21			12/17/2015 8:46:35 AM				
Mijarez, Jaime		RM#21- PEREZ - WANTS TO PUT NAILS ON THE WALL AND WANT 6 MORE CHAIRS FOR THE CLASSROOM							
Maribel Gamboa									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
144112		Classroom			12/1/2015		79		\$0.00
Medium	Work In Progress	24			12/1/2015 3:15:00 PM				
Mijarez, Jaime		RM#24-MARRUFO- CAN YOU PLEASE PUT NAILS ON THE PILASTERS IN THE HALLWAYS IN ORDER TO HANG FARMED ARTWORK PLEASE COME AND SEE ME AT MY ROOM							
Maribel Gamboa									
143765		Library			11/18/2015		92		\$0.00
Medium	Work In Progress	LIBRARY			11/18/2015 8:36:45 AM				
Mijarez, Jaime		LIBRARY- MORENO- NEEDS TO HAVE WALL FILE HOLDERS INSTALLED SEE MRS. MORENO							
Maribel Gamboa									
146905		Library			1/28/2016		21		\$0.00
Medium	Work In Progress				1/28/2016 10:40:04 AM				
Mijarez, Jaime		LIBRARY- CLAUDIA- NEED TO HAVE CEILING LIGHT FROM NEW CONSTRUCTION CHECKED. I BEGAN WITH ONLY LIGHT							
Maribel Gamboa									
137110		Classroom			8/3/2015		199		\$0.00
Medium	Work In Progress	25			8/3/2015 3:04:41 PM				
Mijarez, Jaime		RM#25- GARCIA- PLEASE PAINT CLASSROOM DOORS				Route to Jaime on 11/16/15			
Maribel Gamboa									
144284					12/3/2015		77		\$0.00
Medium	Work In Progress				12/3/2015 1:50:44 PM				
Moncayo, Fernando		SERVING LINE IS NOT COOLING. SNP MANAGER IGNACIA C. 589.2545							
Maritza Gonzalez									
144786		Cafeteria			12/10/2015		70		\$0.00
Medium	Work In Progress				12/10/2015 7:36:06 AM				
Moncayo, Fernando		NO HOT WATER IN KITCHEN - SNP MGR IGNACIA 589-2545							
Jacqueline Aguilar									
147480		Kitchen			2/5/2016		13		\$0.00
Medium	Work In Progress				2/5/2016 1:42:40 PM				
Moncayo, Fernando		There is water on the Walk In Freezer floor							
Dino Facio									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Sunland Park ES									
141871					10/16/2015		125		\$0.00
Medium	Work In Progress				10/16/2015 3:39:05 PM				
Flores, Pete	tractor 970 4x4 dont work(worked before they took it to get repaired)								
Carlos Hernandez									
144631					12/8/2015		72		\$0.00
Medium	Work In Progress	OFFICE			12/8/2015 7:40:23 AM				
Mijarez, Jaime	OFFICE- KAHOE- HER DOOR STOP IS NOT WORKING								
Maribel Gamboa									
138311					8/19/2015		183		\$0.00
Medium	Work In Progress	25			8/19/2015 10:16:35 AM				
Mijarez, Jaime	RM#25 M.HOLGUIN- PLEASE PAINT THE DOES IN THE CLASSROOM-2ND NOTICE		Route to Jaime on 11/16/15						
Maribel Gamboa									
145614	Main Building				1/5/2016		44		\$0.00
Medium	Work In Progress				1/5/2016 10:11:45 AM				
Mijarez, Jaime	Jaime, EC playground is full of stickers please remove so that it can be ready when students can go out to play. Front of building is full of sand and paper that is stuck against the front chain link fence.								
Rosa Kahoe									
141950					10/19/2015		122		\$0.00
Medium	Work In Progress				10/19/2015 3:36:43 PM				
Ronquillo, Ruben	missing one platform and one cracked.(hazard had talked to mr ronquillio was going to send someone no one has showed up)								
Carlos Hernandez									
136740					7/30/2015		203		\$0.00
Medium	Work In Progress				7/30/2015 11:23:17 AM				
Ronquillo, Ruben	need platforms for bridge broken(hazard)								
Carlos Hernandez									
147096					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:36 AM				
Mijarez, Jaime	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PMschedule details.								
Margret Villalobos									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Sunland Park ES									
147097					1/31/2016	2/8/2016	18		\$0.00
Medium	Work In Progress				1/31/2016 12:51:37 AM				
Mijarez, Jaime	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
142735					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:29 AM				
Vallejo, Albert	Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
142839					11/1/2015	11/7/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:55:38 AM				
Mijarez, Jaime	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
146758	Main Building	Custodial			1/26/2016		23		\$0.00
Medium	Work In Progress				1/26/2016 1:19:05 PM				
Briones, Enrique	requesting dolly to move fire profiling cabinets thanks.								
Jesus Lucero									
141381					10/9/2015		132	0.5	\$12.50
Medium	Work In Progress				10/9/2015 3:31:47 PM				
Mijarez, Jaime	floor tile in bathroom need to be replaced in room 38					1/25/15 - route to building mechanic as per Jimmy, the tile is still there just a couple came unglued			
Carlos Hernandez									
146926					1/28/2016		21		\$0.00
Medium	Work In Progress				1/28/2016 2:55:42 PM				
Ambriz, Jose	Install covers on O/A temp sensors that control on and off to both boilers booster pumps for heating.								
Jaime Mijarez									
147444					2/4/2016		14		\$0.00
Medium	Work In Progress				2/4/2016 3:50:08 PM				
Ambriz, Jose	Rm 26 and Rm 27 are complaining of rooms being too cold.								
Jaime Mijarez									
Count: 41 Work Orders			Avg. Age of WO's	71	Total for Sunland Park ES		0.5	\$12.50	

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Sunrise ES									
142713					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress			11/1/2015 12:54:14 AM					
Orozco, Daniel	Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
147271					2/2/2016		16		\$0.00
Medium	Work In Progress			2/2/2016 3:22:09 PM					
Chavez, Santos	need replace 10 emergency lights and 20 exit lights								
Juan Vargas									
147323	Main Building	Library			2/3/2016		15		\$0.00
Medium	Work In Progress			2/3/2016 10:12:50 AM					
Chavez, Santos	Need to replace lenses on several 4 x2 light fixtures								
Santos Chavez									
147172					2/1/2016		0		\$0.00
Medium	Work In Progress			2/1/2016 9:17:20 AM	2/1/2016				
Orozco, Daniel	WASHING MACHINE STOPPED WORKING AGAIN, WATER WILL NOT DRAIN. SNP MANAGER GLENDA G.824.3194								
Maritza Gonzalez									
147577					2/8/2016		10		\$0.00
Medium	Work In Progress			2/8/2016 3:25:56 PM					
Carrasco, Danny	need gas for truck # 155 and two blower								
Juan Vargas									
147137					1/31/2016		18		\$0.00
Medium	Work In Progress			1/31/2016 12:52:06 AM					
Apodaca, Mario	Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
146535					1/21/2016		28		\$0.00
Medium	Work In Progress			1/21/2016 3:44:31 PM					
Vallejo, Albert	Remove sand and plastic barriers to replace with concrete barriers and wood chips at playgrounds.								
Albert Vallejo									
Count: 7 Work Orders			Avg. Age of WO's	28		Total for Sunrise ES	0		\$0.00

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
142737					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:30 AM				
Orozco, Daniel		Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
147855	Main Building	Custodial			2/12/2016		6		\$0.00
Medium	Work In Progress				2/12/2016 7:46:42 AM				
Carbajal, Jimmy		Good morning Jimmy just sending work order for MR. Trevino safety boots thank you !							
Armando Diaz									
146516					1/21/2016		28		\$0.00
Medium	Work In Progress				1/21/2016 2:00:06 PM				
Miranda, Danny		need to replace outside electrical covers							
Danny Miranda									
146833					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 10:31:39 AM				
Miranda, Danny		Need 6 surveillance signs the ones we have are old.							
Danny Miranda									
144866					12/11/2015		69		\$0.00
Medium	Work In Progress				12/11/2015 10:31:24				
Chavez, Santos		need to replace emer. ballast in rooms 103,107,208,303, and teachers lounge							
Danny Miranda									
146973					1/29/2016		20		\$0.00
Medium	Work In Progress				1/29/2016 8:25:37 AM				
Chavez, Santos		need a 115 outlet in room 105 to be able to plug in smart board on south side wall							
Danny Miranda									
147556					2/8/2016		10		\$0.00
Medium	Work In Progress				2/8/2016 10:25:50 AM				
Solis, Lorenzo		unit in room 305 will not start up on auto every morning							
Danny Miranda									
147557					2/8/2016		10		\$0.00
Medium	Work In Progress				2/8/2016 10:27:15 AM				
Solis, Lorenzo		need to ck. unit in room 106 will not start up in the mornings							
Danny Miranda									

846 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
146837					1/27/2016		22		\$0.00
Medium	Work In Progress				1/27/2016 11:42:20 AM				
Solis, Lorenzo		NEED TO CK. UNIT IN ROOM 309 LOUD NOISE COMING FROM CONTROL BOX							
Danny Miranda									
145064					12/15/2015		65		\$0.00
Medium	Work In Progress				12/15/2015 1:44:27 PM				
Flores, Pete		AUTO SHOP NEEDS TO SERVICE MOWER 431 V.E. CHANGE BLADES CHANGE OIL LEFT BUTTON WILL NOT PICK UP BLADE TO CHANGE HIGHT LEVEL OF CUTTUNG							
Danny Miranda									
142714					11/1/2015	11/22/2015	109		\$0.00
Medium	Work In Progress				11/1/2015 12:54:15 AM				
Orozco, Daniel		Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
145331					1/3/2016	2/3/2016	46		\$0.00
Medium	Work In Progress				1/3/2016 12:43:37 AM				
Miranda, Danny		Yearly - Vado ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
143363					11/10/2015		100		\$0.00
Medium	Work In Progress				11/10/2015 7:56:40 AM				
Appelzoller, Fred		need to replace booster pump in 100-wing boiler room							
Danny Miranda									
Count: 13 Work Orders		Avg. Age of WO's 47		Total for Vado ES		0		\$0.00	
Count: 846 Work Orders		Avg. Age of WO's 67		Grand Total		1.5		\$37.50	