

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Alta Vista Early College HS									
147971					2/18/2016		61		\$0.00
Medium	Work In Progress			2/18/2016 8:56:12 AM					
Vallejo, Albert	Move (3) Double Portables from DT to AVEC.								
Alfredo Holguin									
136112	Curriculum and				7/20/2015		274		\$0.00
Medium	Work In Progress	ANNEX		7/20/2015 9:53:42 AM					
Marquez, Gerardo	REPLACE OLD DOORS WITH WOOD FRAME AND GLASS DOORS AT ANNEX BUILDING. DOORS TO BE REPLACED HAVE BEEN LABELED FOR IDENTIFICATION. ANY QUESTIONS, PLEASE CONTACT YVETTE OR GEMA AT AVECHS 882-6400.								
Yvette Cortez									
149395					3/10/2016		40		\$0.00
Medium	Work In Progress			3/10/2016 12:08:44 PM					
Villalobos, Jose	I'm requesting a wet and dry machine for my site thank you.								
Alfredo Ambriz									
135852					7/14/2015		280		\$0.00
Medium	Work In Progress			7/14/2015 12:01:35 PM					
Vallejo, Albert	Improve sidewalks at front entrance.								
Albert Vallejo									
146127					1/13/2016		97		\$0.00
Medium	Work In Progress			1/13/2016 7:58:43 AM					
Vallejo, Albert	Upgrade electrical service for portables.								
Albert Vallejo									
151353					4/14/2016		5		\$0.00
Medium	Work In Progress			4/14/2016 12:34:31 AM					
Martinez, Salvador	Monthly - Alta Vista ECHS- Water Filters - Refer to PM schedule details.								
Margret Villalobos									
150625					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress			4/3/2016 12:44:46 AM					
Soriano, David	Monthly - Alta Vista ECHS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Alta Vista Early College HS							
150253					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:46:09 AM				
Aguilar, Patricio		Monthly - Desert Pride HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
150464					4/3/2016	4/24/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:48 AM				
Aguilar, Patricio		Monthly - Alta Vista ECHS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
150515					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:26 AM				
Aguilar, Patricio		Monthly - Alta Vista ECHS - Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
151039					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:06 AM				
Ambriz, Alfredo		Monthly - QRTLY BLDG INSP REPORT (AVECS) - Refer to PM schedule details.							
Margret Villalobos									
150522					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:32 AM				
Ronquillo, Ruben		Monthly - Alta Vista ECHS - (Qtrly) Fitness Equip - Refer to PM schedule details.							
Margret Villalobos									
143208					11/6/2015		165		\$0.00
Medium	Work In Progress				11/6/2015 11:55:58 AM				
Vallejo, Albert		Roof Leak in the Library. It is right on top of the first table where computers are. Also roof leak in portable #6. Leak is right next to teachers desk.							
David Soriano									
150306					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 11:14:06 AM				
Lara, Ralph		Rafa please come and fix the door from the p.e. portable is falling.							
Alfredo Ambriz									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Alta Vista Early College HS

150060 Parking Lot 3/23/2016 27 \$0.00

Medium Work In Progress Front Parking 3/23/2016 3:11:22 PM

Lara, Ralph GLASS DOOR TO MARQUEE DOES NOT LOCK AND MOVES WITH THE WIND. NEEDS A PAD LOCK FOR SECURITY

Yvette Cortez

151363 Portables 4/14/2016 5 \$0.00

Medium Work In Progress 4/14/2016 9:20:59 AM

Lara, Ralph Rafa we having some problems with some few doors to be ajust and change door nubs thank you.

Alfredo Ambriz

143189 11/6/2015 165 \$0.00

Medium Work In Progress Teacher's 11/6/2015 10:17:42 AM

Villalobos, David PLEASE INVESTIGATE THE POSSIBILITY OF INSTALLING A SMALL BAR SINK IN THE TEACHER'S EATING AREA FOR THE PURPOSE OF WASHING HANDS AND CLEANING MAINTENANCE.

Yvette Cortez

151517 4/18/2016 1 \$0.00

Medium Work In Progress 4/18/2016 11:22:36 AM

Castillo, Carlos can you please come and check the outlets in the server room there's no power in three outlets they need it to connect a sever box if you can come as soon as possible thank you.

Alfredo Ambriz

151568 4/18/2016 1 \$0.00

Medium Work In Progress 4/18/2016 3:57:27 PM

Castillo, Carlos Server Room - please check electrical outlets.

Albert Vallejo

148846 Classroom 3/3/2016 47 \$0.00

Medium Work In Progress 3/3/2016 10:27:16 AM

Ronquillo, Ruben Can you please change the windows from the science lab there sealed with silicone and they need to be open for science experience thank you.

Alfredo Ambriz

146067 Parking Lot 1/12/2016 98 \$0.00

Medium Work In Progress 1/12/2016 2:26:28 PM

Soriano, David 1 8 ft uni-strut to hang up sings in parking lot.

David Soriano

4/19/2016 12:10:23 PM

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Alta Vista Early College HS									
146141					1/13/2016		97		\$0.00
Medium	Work In Progress				1/13/2016 11:02:07 AM				
Soriano, David		10 ft- 3/4 sch. 40 pvc pipe 1 - 3/4 sch. 40 pvc coupling 1 - 3/4 sch. 40 pvc male adapter 1 - 3/4 in. x 6 ft. Polyethylene Pipe Wrap Insulation							
David Soriano									
150312					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 11:31:32 AM				
Miranda, Danny		Please permanently seal door to principles office and insulate to minimize sound penetration. See Ms. Saucedo for details.							
Albert Vallejo									
146209					1/14/2016		96		\$0.00
Medium	Work In Progress				1/14/2016 9:51:31 AM				
Soriano, David		PVC cement and primer to fix ruptured water pipe							
David Soriano									
144961					12/14/2015		127		\$0.00
Medium	Work In Progress				12/14/2015 12:39:25				
Soriano, David		10- Electronic Ballast for 4 ft. 4-Lamp Fixture 6- Electronic Ballast for 4 ft. 2-Lamp Fixture							
David Soriano									
142013					10/20/2015		182		\$0.00
Medium	Work In Progress				10/20/2015 2:25:50 PM				
Soriano, David		4- White Heavy Duty Shelf and Rod Support 3- Concrete Mix Sacks							
David Soriano									
140462					9/23/2015		209		\$0.00
Medium	Work In Progress				9/23/2015 8:58:29 AM				
Soriano, David		10- 2x4x8 Studs to hang up window blinds							
David Soriano									
139907					9/14/2015		218		\$0.00
Medium	Work In Progress				9/14/2015 2:04:54 PM				
Soriano, David		10 - Ballaster 4 lamp 110 v							
David Soriano									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Alta Vista Early College HS

139734					9/10/2015		222		\$0.00
Medium	Work In Progress				9/10/2015 2:27:06 PM				
Soriano, David		4 - 9 in. Roller Covers 4- 2 in. Roller Covers 1- 2 in. Roller 1- 10 oz Caulking Gun 1- 4-in Metal Twist Nozzle (for Garden Hose)							
David Soriano									

142305					10/26/2015		176		\$0.00
Medium	Work In Progress				10/26/2015 11:40:36				
Soriano, David		2- Melnor Y Shut-Off 2-Way Metal Hose Connector							
David Soriano									

142306					10/26/2015		176		\$0.00
Medium	Work In Progress				10/26/2015 11:51:47				
Soriano, David		2 Boxes - #6 x2 in. Phillips Bugle-Head Coarse Thread Sharp Point Gold Screw (1 lb.-Pack) 2 Boxes - #8 3 in. Philips Bugle-Head Coarse Thread Wood Screws (1 lb.-Pack) 2 Boxes - #6 x1-5/8 in. Philips Bugle-Head Coarse Thread Gold Screw							
David Soriano									

142369					10/27/2015		175		\$0.00
Medium	Work In Progress				10/27/2015 8:43:13 AM				
Soriano, David		3- 42x29 window blinds 2- 48x48 window blinds							
David Soriano									

139349					9/4/2015		228		\$0.00
Medium	Work In Progress				9/4/2015 10:38:51 AM				
Soriano, David		25ft - 3/8 Plastic hose 25ft - 1/2 Plastic Hose 5- (3/8 - 7/8) Hose Repair Clamp							
David Soriano									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Alta Vista Early College HS									
139356					9/4/2015		228		\$0.00
Medium	Work In Progress				9/4/2015 11:07:10 AM				
Soriano, David	24 Hex Bolts with washer and nuts (size - 1/4 in width x 1/2 in. length)								
	2 Carriage bolts 3/8 in width x 2 1/2 length) with washers and nuts								
David Soriano									
139910		Library			9/14/2015		218		\$0.00
Medium	Work In Progress				9/14/2015 2:11:00 PM				
Soriano, David	25 Pack assorted wire connectors (14 gauge wire) [Please include the green ones for the ground]								
David Soriano									
143206		Parking Lot			11/6/2015		165		\$0.00
Medium	Work In Progress				11/6/2015 11:43:48 AM				
Soriano, David	4 - Flat Bar 17 x 1 x 1/8 8 - Carriage Bolts with nuts (1 1/2 in x 3/8)								
David Soriano									
Count: 36 Work Orders		Avg. Age of WO's 109		Total for Alta Vista Early College HS				0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
150839					4/6/2016		13		\$0.00
Medium	Work In Progress				4/6/2016 2:53:00 PM				
Nunez, Arturo		please assemble new furniture							
Laura Vazquez									
150855					4/6/2016		13		\$0.00
Medium	Work In Progress				4/6/2016 3:42:18 PM				
Nunez, Arturo		Check light fixture in restroom room # 108							
Arturo Nunez									
136332		Cafeteria			7/23/2015		271		\$0.00
Medium	Work In Progress	882-1904			7/23/2015 12:06:53 PM				
Nunez, Arturo		doors from room 101 and 102 need a weather strip..							
Laura Vazquez									
150758					4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 1:11:16 PM				
Nunez, Arturo		mice activity in room 109 please check							
Laura Vazquez									
148514		Classroom			2/26/2016		53		\$0.00
Medium	Work In Progress	882-1904			2/26/2016 11:29:36 AM				
Marquez, Gerardo		requesting cabinets install in four teacher classrooms. any questions please ask Sandy Silvas							
Laura Vazquez									
150744					4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 9:30:04 AM				
Ronquillo, Ruben		Need to have a window glass replaced in room # 110 at pre k. measurements are 14 1/4 x 19 1/2. single pane.							
Arturo Nunez									
143784					11/18/2015		153		\$0.00
Medium	Work In Progress	882-1904			11/18/2015 2:32:43 PM				
Marquez, Gerardo		Install chains furnished and weld on to gates please							
Laura Vazquez									
142145					10/22/2015		180		\$0.00
Medium	Work In Progress				10/22/2015 10:34:31				
Ontiveros, Joe		Admin Portable - water fountain (exterior) does not work.							
Albert Vallejo									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
137103					8/3/2015		260		\$0.00
Medium	Work In Progress				8/3/2015 2:08:08 PM				
Ontiveros, Guadalupe		Please trim trees that are in the front office thank you.							
Laura Vazquez									
144025					11/30/2015		141		\$0.00
Medium	Work In Progress				11/30/2015 2:00:33 PM				
Chavez, Santos		Install wall packs around building.							
Albert Vallejo									
150651					4/4/2016		15		\$0.00
Medium	Work In Progress				4/4/2016 8:31:29 AM				
Nunez, Arturo		please repaint the yellow arrows that are on the walk side the one that the children's use to ride the bikes							
Laura Vazquez									
150652					4/4/2016		15		\$0.00
Medium	Work In Progress				4/4/2016 8:32:35 AM				
Nunez, Arturo		please paint a caterpillar on the side walk more info or details ask Sandy							
		Thank you							
Laura Vazquez									
147803					2/11/2016		68		\$0.00
Medium	Work In Progress				2/11/2016 1:46:27 PM				
Nunez, Arturo		...as per Ray L. For the POA center in the portable at the Anthony Pre-K. To re-paint stairs/ramp leading to center entrance. Thank you.							
Esteban Rosas									
138597		Classroom			8/24/2015		239		\$0.00
Medium	Work In Progress	ANTHONY			8/24/2015 3:12:32 PM				
Nunez, Arturo		PLEASE PAINT AN INSIDE ONE WALL WHERE THE DRY ERASE BOARD WAS REMOVED AT THE ANTHONY FAMILY LITERACY CENTER. CONTACT JUANA ESPINOZA @ EXT.4420 OR RAY LARA @ EXT.6799 FOR FURTHER INFO.							
Karla Quesada									
150757					4/5/2016		14		\$0.00
Medium	Work In Progress	882-1904			4/5/2016 1:10:36 PM				
Carbajal, Jimmy		removed carpet from room 111 and install tile							
Laura Vazquez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
143774					11/18/2015		153		\$0.00
Medium	Work In Progress				11/18/2015 11:54:01				
Solis, Lorenzo		Need some assistance on H.W.R line on hydronic heating system in room # 107, is has leak.							
Arturo Nunez									
142861					11/2/2015		169		\$0.00
Medium	Work In Progress				11/2/2015 9:20:52 AM				
Solis, Lorenzo		Need some assistance on trouble shooting water leak on F.C.U. in room # 107.							
Arturo Nunez									
Count: 17 Work Orders		Avg. Age of WO's	105	Total for Anthony - On Track Pre-K (Village)				0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES									
151534					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 3:09:23 PM				
Carrasco, Danny		need weedeater string							
David Vega									
151091					4/11/2016		8		\$0.00
Medium	Work In Progress				4/11/2016 9:28:06 AM				
Villalobos, Jose		supersuction colt wet and dry does not pick up water squeegee is shot							
David Vega									
151093					4/11/2016		8		\$0.00
Medium	Work In Progress				4/11/2016 9:30:44 AM				
Villalobos, Jose		weed eater stihl no serial number needs repair wont start sometimes							
David Vega									
150920					4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 11:28:28 AM				
Villalobos, Jose		need new vacuum cleaner as per jimmy							
David Vega									
151206					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 1:09:25 PM				
Villalobos, Jose		pick up old rotoar machine serial#1000405							
David Vega									
151207					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 1:11:34 PM				
Villalobos, Jose		pick up old rotar machine serial#1000327							
David Vega									
147779					2/11/2016		68		\$0.00
Medium	Work In Progress				2/11/2016 7:38:06 AM				
Solis, Lorenzø		Need some assistance on trouble shooting mini split unit in room # 108 at pre k.							
Arturo Nunez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
150764					4/5/2016		14		\$0.00
Medium	Work In Progress	105		4/5/2016 2:09:43 PM					
Nunez, Arturo	Mr. Nunez, As per Ms. Chaparro please set up mesh panels and 2 tables at chaparral middle school on May5, 2016 for district art show. Please see Ms.Chaparro for more info.								
Jessica Lopez									
151065					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress			4/10/2016 12:32:26 AM					
Nunez, Arturo	Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
150548					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress			4/3/2016 12:43:51 AM					
Nunez, Arturo	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
150549					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress			4/3/2016 12:43:52 AM					
Nunez, Arturo	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
148575					2/29/2016		50		\$0.00
Medium	Work In Progress			2/29/2016 12:58:23 AM					
Vallejo, Albert	Yearly - Anthony ES - Fire Pump Inspection - Refer to PM schedule details.								
Margret Villalobos									
150889					4/7/2016		12		\$0.00
Medium	Work In Progress			4/7/2016 12:32:12 AM					
Nunez, Arturo	Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details.								
Margret Villalobos									
150035					3/23/2016		27		\$0.00
Medium	Work In Progress			3/23/2016 12:31:35 AM					
Nunez, Arturo	Daily - Anthony ES - Fire Pump (Biweekly) - Refer to PM schedule details.								
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Anthony ES							
150508					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:21 AM				
Vallejo, Albert		Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to PMschedule details.							
Margret Villalobos									
150520					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:30 AM				
Villalobos, Margret		Monthly - Anthony ES - Enviro Controls Quarterly -				em 4/5/16			
Margret Villalobos		Refer to PMschedule details.							
150623					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:45 AM				
Nunez, Arturo		Monthly - Anthony ES Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
150489					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:07 AM				
Nunez, Arturo		Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
150238					3/31/2016	5/1/2016	19		\$0.00
Medium	Work In Progress				3/31/2016 12:45:57 AM				
Nunez, Arturo		Yearly - Anthony ES A8(Rooftop Unit)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
150239					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:45:58 AM				
Nunez, Arturo		Yearly - Anthony ES A6 (Rooftop Unit)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
150461					4/3/2016	5/4/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:46 AM				
Nunez, Arturo		Yearly - Anthony ES A13 (AC Wall Mount)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
150474					4/3/2016	5/4/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:56 AM				
Nunez, Arturo		Monthly - Anthony ES A16 (Fan Exhst.)(Semi. Ann.) - Refer to PMschedule details.							
Margret Villalobos									
148986					3/6/2016		44		\$0.00
Medium	Work In Progress				3/6/2016 12:40:41 AM				
Nunez, Arturo		Yearly - Anthony ES A10(Heat Pumps)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
148987					3/6/2016	4/6/2016	44		\$0.00
Medium	Work In Progress				3/6/2016 12:40:42 AM				
Nunez, Arturo		Yearly - Anthony ES R3 (Ref. Unit)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
148562					2/29/2016	3/31/2016	50		\$0.00
Medium	Work In Progress				2/29/2016 12:58:13 AM				
Nunez, Arturo		Yearly - Anthony ES C-11 (Evap.Down)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
151046					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:12 AM				
Vega, David		Monthly - QRTLY BLDG INSP REPORT (AE) - Refer to PMschedule details.							
Margret Villalobos									
147409					2/4/2016		75		\$0.00
Medium	Work In Progress				2/4/2016 12:01:51 PM				
Nunez, Arturo		Prune and clean area around tree/bushes on ponding area on student drop off							
Arturo Nunez									
149422					3/10/2016		40		\$0.00
Medium	Work In Progress				3/10/2016 3:44:33 PM				
Nunez, Arturo		Need to check sprinkler system on patio at pre k.							
Arturo Nunez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
150316					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 11:40:53 AM				
Chavez, Santos		Please verify that electrical pole and meter enclosure are secure. Supply power to Morgan shed from mobile home site in a permanent manner.							
Albert Vallejo									
151085					4/11/2016		8		\$0.00
Medium	Work In Progress				4/11/2016 7:50:52 AM				
Vallejo, Albert		Need to have fence by parking lot repaired, some vehicle and swiped it. and damaged it.							
Arturo Nunez									
151538					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 3:28:12 PM				
Nunez, Arturo		Check playgrounds for vandalism, and clean graffiti.							
Arturo Nunez									
148198					2/23/2016		56		\$0.00
Medium	Work In Progress				2/23/2016 8:05:39 AM				
Chavez, Santos		Need to have electricity connected to wall heaters on Alamo restrooms.							
Arturo Nunez									
144956					12/14/2015		127		\$0.00
Medium	Work In Progress	261			12/14/2015 11:39:15				
Chavez, Santos		Please replace light bulb in room #261 V. Ramos							
Jessica Lopez									
148883					3/3/2016		47		\$0.00
Medium	Work In Progress				3/3/2016 3:47:23 PM				
Ontiveros, Guadalupe		Need to borrow boom sprayer for gator, to spray large areas.							
Arturo Nunez									
150313					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 11:33:07 AM				
Ontiveros, Joe		Please remove natural gas stub outs and cap below grade at mobile home site.							
Albert Vallejo									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
150314					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 11:37:04 AM				
Ontiveros, Joe		Please cap off water supplies below grade at mobile home site to avoid damage or freezing.							
Albert Vallejo									
151238					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 3:48:48 PM				
Ontiveros, Joe		Need some assistance on trouble shooting Hi. Delta water heater, making loud popping sound.							
Arturo Nunez									
147772					2/10/2016		69		\$0.00
Medium	Work In Progress				2/10/2016 4:06:08 PM				
Ontiveros, Joe		Please replace safety valve on boiler NM320136 so that valve will have manufacturer information nameplate.							
Albert Vallejo									
151205					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 1:05:05 PM				
Marquez, Gerardo		teach and afternoon custodian having trouble locking door in pre k room 109(PURPLE DOOR WEST DOOR)							
David Vega									
143685					11/16/2015		155		\$0.00
Medium	Work In Progress				11/16/2015 4:19:44 PM				
Marquez, Gerardo		Please cut extra keys for Alamo Cafeteria.							
Albert Vallejo									
149442					3/10/2016		40		\$0.00
Medium	Work In Progress				3/10/2016 3:54:05 PM				
Flores, Pete		Vehicle 55 needs to be serviced. Thank you.							
Susie Ramos Lara									
148197					2/23/2016		56		\$0.00
Medium	Work In Progress				2/23/2016 8:03:20 AM				
Ronquillo, Ruben		Need six (6) picture frames for boiler certificates certifications.							
Arturo Nunez									
136796					7/30/2015		71		\$0.00
Medium	Work In Progress				7/30/2015 3:53:27 PM	10/9/2015			
Holguin, Alfredo		Need to have a fire sprinkler connection repaired in room # 107. leaking pretty bad.							
Arturo Nunez									
4/19/2016 12:10:23 PM									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES									
136827					7/31/2015		263		\$0.00
Medium	Work In Progress	107			7/31/2015 9:04:38 AM				
Nunez, Arturo		Mr. Nunez, Please move white board to a different location Please see Ms. Gibson Room #107							
Jessica Lopez									
148158	Cafeteria	Kitchen			2/22/2016		57		\$0.00
Medium	Work In Progress				2/22/2016 3:23:45 PM				
Orozco, Daniel		Remove stainless steel work table with shelves from storeroom. SNP Manager Lorena Baquera 575-882-3507							
Dino Facio									
147915					2/16/2016		63		\$0.00
Medium	Work In Progress				2/16/2016 8:58:01 AM				
Orozco, Daniel		Could you please put a work order for the salad chopper, it doesn't close and it can't be turn on. SNP Manager Lorena B.882.3507							
Maritza Gonzalez									
151535					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 3:20:08 PM				
Nunez, Arturo		Install signs on rotary parking lot safety issue							
Arturo Nunez									
146128					1/13/2016		97		\$0.00
Medium	Work In Progress				1/13/2016 8:14:42 AM				
Nunez, Arturo		Need 6 ea. Trane Zone sensors for A.H.U'S in Main building # x13790842-01 Rev. A (SEN1518). Thank you.							
Arturo Nunez									
146839					1/27/2016		83		\$0.00
Medium	Work In Progress				1/27/2016 11:56:17 AM				
Nunez, Arturo		Need 5 surveillance signs the ones we have are old.							
Arturo Nunez									
150006					3/22/2016		28		\$0.00
Medium	Work In Progress				3/22/2016 3:34:01 PM				
Nunez, Arturo		Need to check light fixtures in class rooms on main building, there is a lot of bulbs out, some need balasts.							
Arturo Nunez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
151255					4/12/2016		7		\$0.00
Medium	Work In Progress	Room 120 Sped			4/12/2016 4:13:19 PM				
Nunez, Arturo		Please send a technician to secure 4 files on the wall in room 120 in the Sped Department building.							
Susie Ramos Lara									
139297		Office			9/3/2015		229		\$0.00
Medium	Work In Progress				9/3/2015 1:41:36 PM				
Nunez, Arturo		Need to have someone come in an replace all the air conditioner grills in the SPED ADMIN OFFICES.							
Susie Ramos Lara									
Count: 52 Work Orders			Avg. Age of WO's 42		Total for Anthony ES			0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Berino ES							
147588					2/8/2016		71		\$0.00
Medium	Work In Progress				2/8/2016 3:33:36 PM				
Orozco, Daniel		SINK FAUCETS LEAKING. SNP MANAGER MERCEDES F. 882.2417							
Maritza Gonzalez									
148528		Kitchen			2/26/2016		53		\$0.00
High	Work In Progress				2/26/2016 3:24:38 PM				
Orozco, Daniel		MIXER DOWN NOT ABLE TO USE MISSING PARTS. SNP MANAGER SUSANA HERRERA (575) 882-2417							
Dino Facio									
147583					2/8/2016		71		\$0.00
Medium	Work In Progress				2/8/2016 3:31:12 PM				
Gonzalez, Salvador		need to secure new heater on portable 18 DP thank you							
Sebastian Diaz									
141139					10/6/2015		196		\$0.00
Medium	Work In Progress				10/6/2015 3:19:29 PM				
Gonzalez, Salvador		Need to install metal ramp on portable 18 thank you							
Sebastian Diaz									
148076					2/19/2016		60		\$0.00
Medium	Work In Progress				2/19/2016 3:42:43 PM				
Gonzalez, Salvador		Need frame A/C on portable 18 DP thank you							
Sebastian Diaz									
150749					4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 10:17:02 AM				
Orozco, Daniel		SINGLE DOOR REACH THRU REFRIGERATOR NEEDS REPAIR REGISTERING AT 56 DEGREES. SNP MANAGER SUSANA H.882.2417							
Maritza Gonzalez									
150750					4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 10:19:05 AM				
Orozco, Daniel		RACKS FOR DOUBLED DOOR REACH IN REFRIGERATOR 5 EA (21' X 26')SNP MANAGER SUSANA H.882.2417							
Maritza Gonzalez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Berino ES							
144663					12/8/2015		133		\$0.00
Medium	Work In Progress				12/8/2015 3:04:59 PM				
Ontiveros, Joe		Need to check boiler domestic water not turn on thank you							
Sebastian Diaz									
143637					11/16/2015		155		\$0.00
Medium	Work In Progress				11/16/2015 1:41:51 PM				
Ontiveros, Joe		Need check leak water on boiler pipes thank you							
Sebastian Diaz									
147262					2/2/2016		77		\$0.00
Medium	Work In Progress				2/2/2016 12:35:01 PM				
Ontiveros, Joe		Need to replace lounge 8" center faucet thank you							
Sebastian Diaz									
147395					2/4/2016		75		\$0.00
Medium	Work In Progress				2/4/2016 9:07:08 AM				
Ontiveros, Joe		Need to check water heater on portable 156 not hot water thank you							
Sebastian Diaz									
151372					4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 11:42:29 AM				
Ontiveros, Joe		Need to check noise under sink portable thank you							
Sebastian Diaz									
151373					4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 11:44:25 AM				
Ontiveros, Joe		Need to check odor gas on room 104 thank you							
Sebastian Diaz									
151502					4/18/2016		1		\$0.00
Safety	Work In Progress				4/18/2016 8:15:22 AM				
Ontiveros, Joe		Need to ck on gas odor.							
Albert Vallejo									
149302					3/9/2016		41		\$0.00
Medium	Work In Progress				3/9/2016 9:05:30 AM				
Ontiveros, Joe		Need to check washer on room 113 thank you							
Sebastian Diaz									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Berino ES									
148529					2/26/2016		53		\$0.00
Medium	Work In Progress				2/26/2016 3:29:14 PM				
Chavez, Santos		Need to fix outlet on room 107 thank you							
Sebastian Diaz									
148073					2/19/2016		60		\$0.00
Medium	Work In Progress				2/19/2016 3:40:47 PM				
Chavez, Santos		Need to connect A/C on portable 18 DP thank you							
Sebastian Diaz									
140256					9/18/2015		214		\$0.00
Medium	Work In Progress				9/18/2015 3:36:56 PM				
Chavez, Santos		need to fix light on room 10 thank you							
Sebastian Diaz									
146611					1/22/2016		88		\$0.00
Medium	Work In Progress				1/22/2016 3:41:30 PM				
Chavez, Santos		Need to fix emergency lights on hall thank you							
Sebastian Diaz									
139814					9/11/2015		221		\$0.00
Medium	Work In Progress				9/11/2015 2:31:31 PM				
Chavez, Santos		Need to install power for smart board on room 101 thank you							
Sebastian Diaz									
147331					2/3/2016		76		\$0.00
Medium	Work In Progress				2/3/2016 12:36:14 PM				
Ontiveros, Guadalupe		Need small tractor to remove sand DP and Berino thank you							
Sebastian Diaz									
151057					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:20 AM				
Marin, Francisco		Monthly - QRTLY BLDG INSP REPORTS (BE) - Refer to PM schedule details.							
Margret Villalobos									
150479					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:00 AM				
Diaz, Sebastian		Monthly - Berino ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Berino ES									
150502					4/3/2016	4/24/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:17 AM				
Vallejo, Albert		Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
150524					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:33 AM				
Villalobos, Margret		Monthly - Berino ES - Enviro Controls Quarterly - Refer to PM schedule details.				em 4/5/16			
Margret Villalobos									
150240					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:45:59 AM				
Diaz, Sebastian		Monthly - Berino ES A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
148576					2/29/2016		50		\$0.00
Medium	Work In Progress				2/29/2016 12:58:23 AM				
Vallejo, Albert		Yearly - Berino ES - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
151063					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:24 AM				
Diaz, Sebastian		Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									
139809					9/11/2015		221		\$0.00
Medium	Work In Progress				9/11/2015 12:58:12 PM				
Solis, Lorenz		Need to fix water fountain on room 121 thank you							
Sebastian Diaz									
149394	Main Building	Custodial			3/10/2016		40		\$0.00
Medium	Work In Progress				3/10/2016 11:52:48 AM				
Ronquillo, Ruben		need to order new letters for markie requested by principal							
Francisco Marin									
151522		Custodial			4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 12:54:59 PM				
Marquez, Gerardo		need too replace a key							
Francisco Marin									
4/19/2016 12:10:23 PM									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Berino ES									
151306	Main Building	Pump House			4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 2:37:28 PM				
Chavez, Santos		the new water solenoid valve for the irrigation system need to be wired up .							
Mario Apodaca									
145973	Main Building	Custodial			1/11/2016		99		\$0.00
Medium	Work In Progress				1/11/2016 9:12:09 AM				
Carbajal, Jimmy		vaccum cleaner smoking #do5aoooo5374							
Francisco Marin									
Count: 33 Work Orders			Avg. Age of WO's	66		Total for Berino ES	0		\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

151589					4/19/2016		0		\$0.00
Medium	Work In Progress				4/19/2016 8:34:33 AM				
Appelzoller, Fred		Company:		Caliper Construction		Main Contact Phone:			
				(575) 635-8919					
		Address:		PO Box 1719		SecondaryPhone:			
				(575) 635-8919					
		City, St, Zip:		Las Cruces, NM88004					
				Main					
		Contact Email:		blanca@caliperconstoom					
		CompanyPhone:		(575) 524-3924					
		Main Contact:		Fernie Reyes					
		Spotting Instructions							
		Locate Per the work Plan							

Dominique Esparza

151588					4/19/2016		0		\$0.00
Medium	Work In Progress				4/19/2016 8:34:08 AM				
Chavez, Santos		Company:		Caliper Construction		Main Contact Phone:			
				(575) 635-8919					
		Address:		PO Box 1719		SecondaryPhone:			
				(575) 635-8919					
		City, St, Zip:		Las Cruces, NM88004					
				Main					
		Contact Email:		blanca@caliperconstoom					
		CompanyPhone:		(575) 524-3924					
		Main Contact:		Fernie Reyes					
		Spotting Instructions							
		Locate Per the work Plan							

Dominique Esparza

151161					4/11/2016		8		\$0.00
Medium	Work In Progress				4/11/2016 4:11:26 PM				
Quinones, Paul		4-11-16							
		.5,chk e-mail/get materials							
		2.0,chk server no cooling locate problem send							
		w/O. @chm							
		2.0,150559-c							
		1.0,150529-c							
		1.0,150456-c							
		1.0,150475-c							
		.5,meeting with contractors							
		total hrs.3.0							

Paul Quinones

4/19/2016 12:10:23 PM

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral ES							
150174		Custodial			3/30/2016		20		\$0.00
Medium	Work In Progress				3/30/2016 9:30:20 AM				
Villalobos, Jose		fix,advance,scrubbing,machine,brush,does,not,fit,off,balance.							
Daniel Ramirez									
151095		Custodial			4/11/2016		8		\$0.00
Medium	Work In Progress				4/11/2016 9:51:22 AM				
Villalobos, Jose		need,to,fix,vaccum,wheel,broked.							
Daniel Ramirez									
149393					3/10/2016		40		\$0.00
Medium	Work In Progress				3/10/2016 11:45:20 AM				
Quinones, Paul		replace media pads mastercool evap.coolers,requesting new pads							
Paul Quinones									
151575					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 4:06:46 PM				
Ronquillo, Ruben		broken glass window in portable #2 @ chm.clear glass single payne glass 28"x35".							
Paul Quinones									
151077					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:35 AM				
Quinones, Paul		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
148978					3/6/2016		44		\$0.00
Medium	Work In Progress				3/6/2016 12:40:35 AM				
Quinones, Paul		Yearly - Chaparral ES A-10 HP Rooftop Yearly - Refer to PM schedule details.							
Margret Villalobos									
149004					3/6/2016		44		\$0.00
Medium	Work In Progress				3/6/2016 12:40:55 AM				
Quinones, Paul		Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
145308					1/3/2016	2/3/2016	107		\$0.00
Medium	Work In Progress				1/3/2016 12:43:18 AM				
Quinones, Paul		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
151045					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:11 AM				
Ramirez, Daniel		Monthly - QRTLY BLDG INSP REPORT (CE) - Refer to PMs schedule details.							
Margret Villalobos									
150516					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:27 AM				
Quinones, Paul		Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
142112		Athletic Field			10/21/2015		181		\$0.00
Medium	Work In Progress				10/21/2015 3:49:46 PM				
Ontiveros, Guadalupe		Ms. Nougues is requesting a baseball field.							
Guadalupe Ontiveros									
151111					4/11/2016		8		\$0.00
Medium	Work In Progress				4/11/2016 1:39:29 PM				
Ontiveros, Guadalupe		as per ernesto concha he needs the tractor to clean all open areas and fence lines @ che, and dte for weed control. also needs school dude connected to his computer.							
Paul Quinones									
148444					2/25/2016		54		\$0.00
Medium	Work In Progress				2/25/2016 3:38:05 PM				
Chavez, Santos		power source for wall heater rm .501							
Paul Quinones									
151510					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 8:56:27 AM				
Chavez, Santos		electrical service sagging too much need to raise cable students are reching for cable. e-wing area next to drinking water fountain							
Paul Quinones									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
151035					4/8/2016		11		\$0.00
Medium	Work In Progress				4/8/2016 4:15:37 PM				
Solis, Lorenzo		need a halsleytaylor drinking fountain the hi/lo type.need the one with the compressor.							
Paul Quinones									
151036					4/8/2016		11		\$0.00
Medium	Work In Progress				4/8/2016 4:20:02 PM				
Solis, Lorenzo		exhaust fan in girls rest rm.requesting a new curb and motor set up mushroom type thanks 300 wing							
Paul Quinones									
144018					11/30/2015		141		\$0.00
Medium	Work In Progress				11/30/2015 12:47:38				
Marquez, Gerardo		requesting handicap door closer double doors next to cafeteria principle requesting door closer for handi cap student							
Paul Quinones									
145069	Main Building	Hallway/Corridor			12/15/2015		126		\$0.00
Medium	Work In Progress	school hallways			12/15/2015 3:11:54 PM				
Quinones, Paul		Need Paul to put up pennants throughout school hallways as soon as possible. See Mrs. Pargas or Ms. Barraza							
Jennifer Corral									
146831					1/27/2016		83		\$0.00
Medium	Work In Progress				1/27/2016 10:28:26 AM				
Quinones, Paul		Need 3 surveillance signs.							
Paul Quinones									
146526					1/21/2016		89		\$0.00
Medium	Work In Progress				1/21/2016 3:32:39 PM				
Quinones, Paul		need to replace metal bath rm. metal partitions,rusted and broken door hinges reorder hardware as well. @ chm							
Paul Quinones									
148786					3/2/2016		48		\$0.00
Medium	Work In Progress				3/2/2016 3:09:59 PM				
Ronquillo, Ruben		REPLACE AIR CHARGER COMPRESSOR ON BOOSTER SYSTEM AND							

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
148787					3/2/2016		48		\$0.00
Medium	Work In Progress				3/2/2016 3:11:19 PM				
Ronquillo, Ruben		REPAIR JOCKEY FIRE PUMP							
151273					4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 8:11:13 AM				
Ronquillo, Ruben		broken glass window in rm.rm.504,need new glass window asap thank you							
Paul Quinones									
Count: 26 Work Orders				Avg. Age of WO's	43		Total for Chaparral ES	0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Chaparral High - Pre-K										
147631		Classroom			2/9/2016		70		\$0.00	
Medium	Work In Progress				2/9/2016 10:23:16 AM					
Solis, Lorenzo		Having problem with Heating and cooling unit in room 101.								
Alfredo Ortiz										
151515					4/18/2016		1		\$0.00	
Medium	Work In Progress				4/18/2016 9:30:19 AM					
Marquez, Gerardo		NEED TO ISSUE A GATE KEY TO EL PASO DISPOSAL FOR GATE ACCESS TO DUMPSTER @ CH PE-K. APPROVED AS PER ALFREDO								
Mary Sitters										
151006		Classroom			4/8/2016		11		\$0.00	
Medium	Work In Progress				4/8/2016 3:27:54 PM					
Ortiz, Alfredo		Need to assemble four CommunityLofts at Pre-K. Also some furniture.								
Alfredo Ortiz										
Count: 3 Work Orders			Avg. Age of WO's	27	Total for Chaparral High - Pre-K			0	\$0.00	

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
149795	A-Wing	Foyer			3/17/2016		33		\$0.00
Medium	Work In Progress	Amphitheater			3/17/2016 8:48:27 AM				
Valdez, Pedro		Please replace all landscaping on the west side of amphetheater, near nurse's office, with new bushes. The ones there are all dried up (dead) and are not producing new foliage. (Sofia Payen)				Reroute to Grounds 3/21/16			
Mireya Meza									
139387					9/4/2015		228		\$0.00
Medium	Work In Progress				9/4/2015 3:16:11 PM				
Ontiveros, Guadalupe		Please remove shrubbery in planters nearest the parking lot by the amphitheater and replace with low maintenance landscaping. (Primary screening, boulders and some indigenous flora) See Ms. Payen or Albert for location if in question)							
Albert Vallejo									
150242					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:46:00 AM				
Ortiz, Alfredo		Monthly - Chaparral HS A16 (Fan Exhst.)(S. Annual) - Refer to PM schedule details.							
Margret Villalobos									
150476					4/3/2016	4/24/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:58 AM				
Ortiz, Alfredo		Monthly - Chaparral HS H11 (E.Heater)(S. Annual) - Refer to PM schedule details.							
Margret Villalobos									
150487					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:06 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
151060					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:22 AM				
Urquidi, Jesus		Monthly - QRTLY BLDG INSP REPORT (CH) - Refer to PM schedule details.							
Margret Villalobos									
145329					1/3/2016	2/3/2016	107		\$0.00
Medium	Work In Progress				1/3/2016 12:43:35 AM				
Ortiz, Alfredo		Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
150512					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:24 AM				
Vallejo, Albert		Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PM schedule details.							
Margret Villalobos									
150509					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:22 AM				
Vallejo, Albert		Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
150638					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:56 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
148577					2/29/2016		50		\$0.00
Medium	Work In Progress				2/29/2016 12:58:24 AM				
Vallejo, Albert		Yearly - Chaparral HS - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
150636					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:54 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
150575					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:10 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
150576					4/3/2016	5/4/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:11 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

150610 4/3/2016 16 \$0.00

Medium Work In Progress 4/3/2016 12:44:35 AM

Apodaca, Mario Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.

Margret Villalobos

146864 H-Wing 1/27/2016 83 \$0.00

Medium Work In Progress 1/27/2016 3:44:13 PM

Carbajal, Jimmy Attention to Jimmy Custodial Supervisor Need to replace tile in Gym. Also on the Hallway tile baseboard.

Alfredo Ortiz

149984 3/22/2016 28 \$0.00

Medium Work In Progress 3/22/2016 8:39:08 AM

Flores, Pete Gator will not start. Also needs to be service.

Guadalupe Ontiveros

145600 1/5/2016 105 \$0.00

Medium Work In Progress 1/5/2016 7:03:16 AM

Vallejo, Albert Repair broken bleacher modules.

Albert Vallejo

147467 Athletic Field 2/5/2016 74 \$0.00

Medium Work In Progress 2/5/2016 8:50:18 AM

Ontiveros, Guadalupe Need to install a new gate on softball field to keep students from damaging batting cages nets. with locks.

Alfredo Ortiz

151266 Gym 4/13/2016 6 \$0.00

Medium Work In Progress 4/13/2016 7:49:19 AM

Carbajal, Jimmy need gym floors re varnished , Dates 5-23-16 to 6-3-16.

Jesus Urquidi

150916 4/7/2016 12 \$0.00

Medium Work In Progress 4/7/2016 10:55:52 AM

Villalobos, Jose Auto scrubber is not keeping the charge.

Jesus Urquidi

145838 Field House Athletic Field 1/7/2016 103 \$0.00

Medium Work In Progress softball field 1/7/2016 4:02:57 PM

Ontiveros, Guadalupe Please enclose the softball dug outs with windscreens or anything that can protect the girls from the elements. (coach Heddleston, softball)

Mireya Meza

4/19/2016 12:10:23 PM

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

150308 Field House 3/31/2016 19 \$0.00

Medium Work In Progress 3/31/2016 11:19:35 AM

Solis, Lorenzo In the trainers room/office at the Field house, the copy machine and the filling cabinet papers are getting ruined because of the moisture and humidity also she gets mosquitoes. Need to install a Refrigerated unit.

Alfredo Ortiz

145840 Field House Athletic Field 1/7/2016 103 \$0.00

Medium Work In Progress Softball 1/7/2016 4:06:58 PM

Appelzoller, Fred Please install a water fountain/faucet at the field so we always have water. (coach Heddleston, softball)

Mireya Meza

140161 Field House Athletic Field 9/17/2015 215 \$0.00

Medium Work In Progress Football & 9/17/2015 2:20:24 PM

Ontiveros, Guadalupe To have green wind screens placed around the entire football and soccer field areas. (Ms. Ulibarri)

Mireya Meza

146844 Athletic Field 1/27/2016 83 \$0.00

Medium Work In Progress 1/27/2016 2:15:45 PM

Holguin, Alfredo Football field Artificial Turf - Perform SportChamp deep cleaning service

Alfredo Holguin

145122 12/16/2015 125 \$0.00

Medium Work In Progress 12/16/2015 8:40:49 AM

Chavez, Santos Pedro Valdez groundskeeper, need electrical outlet at storage and an inside light at least one outlet please need for maintenance.equipment thank you supervisor.Alfredo Olguin or to whom concern.

Pedro Valdez

147256 Q-Wing Classroom 2/2/2016 77 \$0.00

Medium Work In Progress Q4 2/2/2016 11:00:06 AM

Chavez, Santos I need two 220 female wall plugs hooked up. (Mr. Lawler, Q4)

Mireya Meza

139947 Field House Mechanical 9/14/2015 218 \$0.00

Medium Work In Progress 9/14/2015 3:58:21 PM

Chavez, Santos Buster pump for irrigation has to be reset every day, needs to checked electrical power.

Alfredo Ortiz

4/19/2016 12:10:23 PM

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
144860	Q-Wing	Hallway/Corridor			12/11/2015		130		\$0.00
Medium	Work In Progress				12/11/2015 9:41:19 AM				
Chavez, Santos		Need to replace burned out timer and contactor for out side light							
Alfredo Ortiz									
151593	Q-Wing				4/19/2016		0		\$0.00
Medium	Work In Progress	Q2			4/19/2016 9:32:00 AM				
Chavez, Santos		Move and connect laser engraver to pneumatic system. (Ms. Cordova, Q2)							
Mireya Meza									
137624	C-Wing	Classroom			8/10/2015		253		\$0.00
Medium	Work In Progress				8/10/2015 9:37:57 AM				
Chavez, Santos		In C-6 Green-house need to rewire electricity for heater, exhaust fan and A/C. Thank you.							
Alfredo Ortiz									
144639	H-Wing	Gym			12/8/2015		133		\$0.00
Medium	Work In Progress	Gym Training			12/8/2015 10:00:34 AM				
Chavez, Santos		2 fluorescent light bulbs are burned out in the gym training room. (Mrs. Walsh, gym training room)							
Mireya Meza									
148500	H-Wing	Gym			2/26/2016		53		\$0.00
Medium	Work In Progress				2/26/2016 8:54:24 AM				
Chavez, Santos		Need to replace switches for the basket ball back court that moves them up and down several broken. ASAP Thanks.							
Alfredo Ortiz									
137857	Field House	Athletic Field			8/12/2015		251		\$0.00
Medium	Work In Progress	Softball field			8/12/2015 3:36:25 PM				
Chavez, Santos		Need electricity for new softball/baseball batting cage. (Mireya Meza)							
Mireya Meza									
146650	Q-Wing	Classroom			1/25/2016		85		\$0.00
Medium	Work In Progress				1/25/2016 8:32:32 AM				
Chavez, Santos		The hoist in the welding shop won't move up or down. No power to contact.							
Alfredo Ortiz									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
149741	A-Wing	Classroom			3/16/2016		34		\$0.00
Medium	Work In Progress	office			3/16/2016 3:20:02 PM				
Marquez, Gerardo									
Please make 3 keycopies of baseball & softball new sheds. key #BT13 & #BT14. (Mireya Meza)									
Mireya Meza									
142462	Field House	Athletic Field			10/28/2015		174		\$0.00
Medium	Work In Progress	Baseball Field			10/28/2015 9:32:29 AM				
Ontiveros, Guadalupe									
Install dug out made of cinder block. In visitor and home dug outs. (Coach Rojas)									
Mireya Meza									
148692		Kitchen			3/1/2016		49		\$0.00
Medium	Work In Progress				3/1/2016 9:57:13 AM				
Ortiz, Alfredo									
Need to replace faucet and cartridges on other faucets leaking. In kitchen.									
Alfredo Ortiz									
148691	A-Wing	Hallway/Corridor			3/1/2016		49		\$0.00
Medium	Work In Progress				3/1/2016 9:53:11 AM				
Ortiz, Alfredo									
Need to replace Light bulbs and plastic cover some are broken.									
Alfredo Ortiz									
150732	Field House	Roof			4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 8:09:26 AM				
Ortiz, Alfredo									
Need to fix water lines and drain lines for A/C units in Field house and Gym.									
Alfredo Ortiz									
147992	H-Wing	Gym			2/18/2016		61		\$0.00
Medium	Work In Progress				2/18/2016 3:10:05 PM				
Ortiz, Alfredo									
Need to order and replace lamp covers broken for Gym lights.									
Alfredo Ortiz									
143521	R-Wing	Classroom			11/12/2015		159		\$0.00
Medium	Work In Progress				11/12/2015 4:00:54 PM				
Orozco, Daniel									
One of the stove ovens not working need to fix or replace gas valve. In Home Economics classroom.									
Alfredo Ortiz									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
150690	D-Wing	Classroom			4/4/2016		15		\$0.00
Medium	Work In Progress				4/4/2016 3:44:12 PM				
Vallejo, Albert In D-Sped. classroom. A fire sprinkler head leaking water, need to be fixed ASAP. Thank you									
Alfredo Ortiz									
148121		Mechanical			2/22/2016		57		\$0.00
Medium	Work In Progress				2/22/2016 9:40:02 AM				
Ronquillo, Ruben Need to order 5 Frames for Boiler Certificates									
Alfredo Ortiz									
142460	Field House	Athletic Field			10/28/2015		174		\$0.00
Medium	Work In Progress	Baseball Field			10/28/2015 9:28:03 AM				
Gonzalez, Salvador Please install 4 mini batting cages for baseball field. (Coach Rojas)									
Mireya Meza									
151299	A-Wing	Classroom			4/13/2016		6		\$0.00
Medium	Work In Progress	Storage			4/13/2016 1:00:53 PM				
Gonzales, Camilo Please pick up 2 gaylords from CHS book room. (Victoria Lopez)									
Mireya Meza									
149793	Field House	Athletic Field			3/17/2016		33		\$0.00
Medium	Work In Progress	Soccer field			3/17/2016 8:25:45 AM				
Ontiveros, Guadalupe Please replace the green screen around the soccer field. Looking very torn up in different areas. (Mark Rupcich)									
Mireya Meza									
Count: 48 Work Orders		Avg. Age of WO's 74			Total for Chaparral HS			0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
148933	Main Building	Athletic Field			3/4/2016		46		\$0.00
Medium	Work In Progress	OUTSIDE			3/4/2016 2:25:55 PM				
Ontiveros, Guadalupe									
GROUNDS, PLEASE LINE OUTSIDE BASKETBALL COURTS FOR BASKETBALL AND TENNIS, PLEASE SEE COACH CASTILLO FOR SPECS.									
THANKS, TERRY									
Terry Alvarado									
149378					3/10/2016		40		\$0.00
Medium	Work In Progress				3/10/2016 8:22:36 AM				
Orozco, Daniel									
ONE OF THE TOP OVENS IS NOT HEATING PROPERLY. SNP MANAGER SANDRA D. 824.4376									
Maritza Gonzalez									
136119	Main Building	Classroom			7/20/2015		274		\$0.00
Medium	Work In Progress	p-14			7/20/2015 1:24:35 PM				
Acuna, Johnny									
please fill holes in wall									
Gidget Mora									
136120	Main Building	Classroom			7/20/2015		274		\$0.00
Medium	Work In Progress	101			7/20/2015 1:25:55 PM				
Acuna, Johnny									
Please mount SMART Board on the wall									
Gidget Mora									
139031		Classroom			8/31/2015		232		\$0.00
Medium	Work In Progress	305			8/31/2015 10:34:06 AM				
Acuna, Johnny									
Please anchor smartboard to wall									
Gidget Mora									
143100	Main Building	Cafeteria			11/5/2015		166		\$0.00
Medium	Work In Progress				11/5/2015 8:51:22 AM				
Acuna, Johnny									
Please hang banner in the cafeteria to the right of the TV									
Gidget Mora									
151447		Classroom			4/15/2016		4		\$0.00
Medium	Work In Progress	309			4/15/2016 11:25:17 AM				
Quinones, Paul									
Tighten metal clamps that hold the shelves up in the cubbies for back packs. Paul Quinones has repaired them in the past									
Gidget Mora									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral MS									
148494		Restroom			2/26/2016		53		\$0.00
Medium	Work In Progress			2/26/2016 7:53:57 AM					
Quinones, Paul	senesecita arreglar puerta de particion de los banos de los boys main hallway GRACIAS								
M. Carmen Perez									
151096	Main Building	Restroom (Girls)			4/11/2016		8		\$0.00
Medium	Work In Progress	200		4/11/2016 10:05:10 AM					
Quinones, Paul	metal border in restroom stall has become detached								
Gidget Mora									
136489		Portables			7/27/2015		0		\$0.00
Medium	Work In Progress			7/27/2015 9:26:41 AM	7/27/2015				
Quinones, Paul	senesecita replace broken tiles and portables # 5 GRACIAS								
M. Carmen Perez									
139807		Hallway/Corridor			9/11/2015		221		\$0.00
Medium	Work In Progress			9/11/2015 12:42:35 PM					
Quinones, Paul	senesecita remplasar focos que no prenden en el lobby GRACIAS								
M. Carmen Perez									
139808		Hallway/Corridor			9/11/2015		221		\$0.00
Medium	Work In Progress			9/11/2015 12:47:37 PM					
Quinones, Paul	senesecita poner lampara que no prende y arreglar switch del hallway del lobby GRACIAS								
M. Carmen Perez									
149225	Main Building	Classroom			3/8/2016		42		\$0.00
Medium	Work In Progress			3/8/2016 9:37:58 AM					
Quinones, Paul	Please mount white boards in Ms. Alden and Ms. Poitevints room								
Gidget Mora									
150132	Main Building	Classroom			3/29/2016		21		\$0.00
Medium	Work In Progress	300		3/29/2016 3:44:16 PM					
Quinones, Paul	one of the windows needs a screen								
Gidget Mora									
149558		Classroom			3/14/2016		36		\$0.00
Medium	Work In Progress			3/14/2016 9:43:10 AM					
Gonzalez, Salvador	senesecita arreglar urgente las windowbars del#408/GRACIAS								
M. Carmen Perez									
4/19/2016 12:10:23 PM									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
149559		Classroom			3/14/2016		36		\$0.00
Medium	Work In Progress			3/14/2016 9:48:00 AM					
Gonzalez, Salvador	senesecita areglar urgente window bars esta suelta del chassroom#304								
M. Carmen Perez									
149561		Classroom			3/14/2016		36		\$0.00
Medium	Work In Progress			3/14/2016 9:53:19 AM					
Gonzalez, Salvador	senesecita areglar urgente windowbars nociera del chassroom#302 GRACIAS								
M. Carmen Perez									
138787					8/26/2015		237		\$0.00
Medium	Work In Progress			8/26/2015 3:04:42 PM					
Gonzalez, Salvador	Need to make and install 4 sets of ladders to different sections of Chaparral Middle School rooftop.								
Johnny Acuna									
149866					3/18/2016		32		\$0.00
Medium	Work In Progress			3/18/2016 8:35:53 AM					
Quinones, Paul	Portable 2 - Once all furniture is removed, please paint walls.								
Albert Vallejo									
148498					2/26/2016		53		\$0.00
Medium	Work In Progress			2/26/2016 8:41:38 AM					
Acuna, Johnny	Need (12) GreenHeck SP-108 D170 (Small) Exhaust fan motors W/assemblyhousing, (6) GreenHeck SP-125 (Medium) motors W/assemblyhousing, (6) V-300 motors W/assemblyhousing (Big) Black Housing								
Johnny Acuna									
144644		Office			12/8/2015		133		\$0.00
Medium	Work In Progress			12/8/2015 11:19:35 AM					
Chavez, Santos	senesecita remplasar lus de laentrada de la office de administration GRACIAS								
M. Carmen Perez									
148220					2/23/2016		56		\$0.00
Medium	Work In Progress			2/23/2016 2:22:42 PM					
Chavez, Santos	lamp upgrade in rest rms.wing 300,200,and 400.								
Paul Quinones									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
146109					1/12/2016		98		\$0.00
Medium	Work In Progress				1/12/2016 3:54:22 PM				
Chavez, Santos		Need to relocate electrical outlet to restroom in SPED classroom at CMS.							
Johnny Acuna									
146990					1/29/2016		81		\$0.00
Medium	Work In Progress				1/29/2016 12:31:45 PM				
Chavez, Santos		Need to install new hand dryer to Girls locker room at CMS							
Johnny Acuna									
151289	Main Building	Classroom			4/13/2016		6		\$0.00
Medium	Work In Progress	303			4/13/2016 9:15:28 AM				
Appelzoller, Fred		Please repair sink in art room							
Gidget Mora									
147260					2/2/2016		77		\$0.00
Medium	Work In Progress				2/2/2016 11:48:01 AM				
Ontiveros, Joe		Small (Blue) motor pump hooked up to the Fire Sprinkler System in the Mechanical Room is Leaking Water.							
Johnny Acuna									
145311					1/3/2016	2/3/2016	107		\$0.00
Medium	Work In Progress				1/3/2016 12:43:21 AM				
Acuna, Johnny		Yearly - Chaparral MS Backflow Inspection - Refer to PMschedule details.							
Margret Villalobos									
148988					3/6/2016		44		\$0.00
Medium	Work In Progress				3/6/2016 12:40:43 AM				
Acuna, Johnny		Yearly - Chaparral MS A10 (Heat Pumps)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
150462					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:47 AM				
Quinones, Paul		Yearly - Chaparral MS A13(AC Wall)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
151056					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:19 AM				
Perez, M. Carmen		Monthly - QRTL BLDG INSP REPORTS (CM) - Refer to PM schedule details.							
Margret Villalobos									
150503					4/3/2016	4/24/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:18 AM				
Vallejo, Albert		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
150626					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:47 AM				
Quinones, Paul		Monthly - Chaparral MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
148580					2/29/2016		50		\$0.00
Medium	Work In Progress				2/29/2016 12:58:26 AM				
Vallejo, Albert		Yearly - Chaparral MS - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
149045					3/6/2016	3/14/2016	44		\$0.00
Medium	Work In Progress				3/6/2016 12:41:25 AM				
Acuna, Johnny		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
149047					3/6/2016		44		\$0.00
Medium	Work In Progress				3/6/2016 12:41:26 AM				
Acuna, Johnny		Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
149048					3/6/2016	4/6/2016	44		\$0.00
Medium	Work In Progress				3/6/2016 12:41:27 AM				
Acuna, Johnny		Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral MS							
150560					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:00 AM				
Acuna, Johnny		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
150562					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:01 AM				
Acuna, Johnny		Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
150563					4/3/2016	5/4/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:02 AM				
Acuna, Johnny		Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
151303					4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 1:46:57 PM				
Vallejo, Albert		Make repairs to roof at CMS and DTE as marked by building mechanic.							
Albert Vallejo									
145621	Main Building	Classroom			1/5/2016		105		\$0.00
Medium	Work In Progress	P-5			1/5/2016 12:02:58 PM				
Carbajal, Jimmy		Tiles in Nurse's office breaking and lifting from floor. Please repair							
Gidget Mora									
139646	Main Building	Kitchen			9/9/2015		223		\$0.00
Medium	Work In Progress				9/9/2015 11:47:14 AM				
Estrada, Jesus		Anti slip tile is coming up under the sink and mixers. This happened after the kitchen flooded.							
Jesus Estrada									
151265		Gym			4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 7:41:05 AM				
Carbajal, Jimmy		para aser el piso del GYM/6/de june---al----17/de june/2016 GRACIAS							
M. Carmen Perez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
151098	Main Building				4/11/2016		8		\$0.00
Medium	Work In Progress				4/11/2016 10:22:44 AM				
Quinones, Paul		Server room is down. Too hot. Please check							
Gidget Mora									
151181					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 9:58:12 AM				
Ontiveros, Guadalupe		Grounds Personel: Need to fix or replace tire to Polaris Vehicle							
Johnny Acuna									
Count: 45 Work Orders		Avg. Age of WO's 73			Total for Chaparral MS			0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Desert Pride HS								
151513		Hallway/Corridor			4/18/2016		1		\$0.00
Medium	Work In Progress	door into			4/18/2016 9:03:22 AM				
Lara, Ralph		Need lock to be compatible with teachers keys to come in to the administration offices.							
Maria Carbajal									
143101		Portables			11/5/2015		166		\$0.00
Medium	Work In Progress	room 5			11/5/2015 9:04:12 AM				
Chavez, Santos		Night light does not turn on.							
David Acosta									
143102		Portables			11/5/2015		166		\$0.00
Medium	Work In Progress	room #18			11/5/2015 9:05:38 AM				
Chavez, Santos		Night light does not turn on.							
David Acosta									
139620		Portables			9/9/2015		223		\$0.00
Medium	Work In Progress	room #18			9/9/2015 5:20:08 AM				
Chavez, Santos		Two light fixtures that need to be check. one flicking and the other does not turn on.							
David Acosta									
148930		Office			3/4/2016		46		\$0.00
Medium	Work In Progress	conference			3/4/2016 1:36:49 PM				
Solis, Lorenzo		ice maker is leaking water (waterline).							
David Acosta									
151366					4/14/2016		5		\$0.00
Medium	Work In Progress	conference			4/14/2016 9:26:15 AM				
Solis, Lorenzo		Ice maker in need of water filter.							
Maria Carbajal									
149873		Portables			3/18/2016		32		\$0.00
Medium	Work In Progress	room #1&2,13.			3/18/2016 11:21:59 AM				
Gallegos, Rafael		Crack floor tiles in restrooms (rooms 1&2 & 13) and entrance to room 1&2							
David Acosta									
137898		Portables			8/13/2015		250		\$0.00
Medium	Work In Progress	room #19			8/13/2015 5:24:27 AM				
Ambriz, Jose		a/c unit not cooling (asap).							
David Acosta									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride HS							
150104		Custodial			3/29/2016		21		\$0.00
Medium	Work In Progress				3/29/2016 10:39:26 AM				
Villalobos, Jose	Burnisher (10521334) as a grinding sound, please check.								
David Acosta									
150761		Custodial			4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 1:39:31 PM				
Villalobos, Jose	Need to replace handle on vacuum cleaner (008C00000157).								
David Acosta									
150478					4/3/2016	4/24/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:59 AM				
Vallejo, Albert	Monthly - Desert Pride Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
150517					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:28 AM				
Ronquillo, Ruben	Monthly - Desert Pride - (Qtrly) Fitness Equipment - Refer to PM schedule details.								
Margret Villalobos									
151038					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:05 AM				
Acosta, David	Monthly - QRTLY BLDG INSP REPORT (DP) - Refer to PM schedule details.								
Margret Villalobos									
Count: 13 Work Orders			Avg. Age of WO's	74	Total for Desert Pride HS		0	\$0.00	

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

Location:		Desert Trail ES							
151365					4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 9:22:44 AM				
Orozco, Daniel	MILK COOLER MAKING A LOUD NOISE. SNP MANAGER PAT C. 824.3822								
Maritza Gonzalez									
145716					1/6/2016		104		\$0.00
Medium	Work In Progress				1/6/2016 2:49:35 PM				
Acuna, Johnny	Need window blinds for portable classrooms #405, #406, #424, and #425 (98" Wide X 39" Long) Qty. 4 (34" Wide X 63" Long) Qty. 4								
Johnny Acuna									
145717					1/6/2016		104		\$0.00
Medium	Work In Progress				1/6/2016 2:52:18 PM				
Acuna, Johnny	Need Aluminum window blinds for portable #422 and #423 (94" Wide X 34" Long) Qty. 1 (46" Wide X 33" Long) Qty. 1								
Johnny Acuna									
146061					1/12/2016		98		\$0.00
Medium	Work In Progress				1/12/2016 1:57:52 PM				
Acuna, Johnny	Need Lamp covers for light fixtures at Desert Trail. (Sent lamp cover samples to PPD)								
Johnny Acuna									
139805					9/11/2015		221		\$0.00
Medium	Work In Progress				9/11/2015 12:01:57 PM				
Carrasco, Danny	Need unleaded fuel for worktruck #192								
Johnny Acuna									
146911					1/28/2016		82		\$0.00
Medium	Work In Progress				1/28/2016 11:53:34 AM				
Gonzalez, Salvador	Please fabricate stand for new refrigeration unit (roof install) to room #304 (computer room)								
Johnny Acuna									
139225					9/2/2015		230		\$0.00
Medium	Work In Progress				9/2/2015 3:22:30 PM				
Acuna, Johnny	Water Seal new portable ramps with wood boards.								
Johnny Acuna									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail ES									
135165					7/1/2015		293		\$0.00
Medium	Work In Progress				7/1/2015 7:43:14 AM				
Solis, Lorenzo		Need Refrigeration unit for new computer classroom. RM. 304							
Johnny Acuna									
145755					1/6/2016		104		\$0.00
Medium	Work In Progress				1/6/2016 4:01:51 PM				
Chavez, Santos		First Priority Please: (Security light Pole next to kinder playground equipment) Need to disconnect electrical and remove security light pole. Pole has massive rust eating through the pole. (Safety Hazard)							
Johnny Acuna									
144870					12/11/2015		130		\$0.00
Medium	Work In Progress				12/11/2015 11:39:29				
Chavez, Santos		SERVING LINE- ELECTRICAL OUTLET BOX NEEDS TO BE REPLACED SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
150318	Main Building	Office			3/31/2016		19		\$0.00
Medium	Work In Progress	front office			3/31/2016 11:47:15 AM				
Marquez, Gerardo		Mr. Nunez needs key extra keys made for his desk and cabinet. ASAP							
Elizabeth Hernandez									
149488					3/11/2016		39		\$0.00
Medium	Work In Progress				3/11/2016 3:29:44 PM				
Concha, Ernesto		Requesting 5 Football fields and 1 soccer field painted in playground grass area at Desert Trail							
Johnny Acuna									
147957					2/16/2016		63		\$0.00
Medium	Work In Progress				2/16/2016 3:52:18 PM				
Appelzoller, Fred		Need to replace faucets in the north 100 hallway.							
Johnny Acuna									
151364					4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 9:21:40 AM				
Appelzoller, Fred		KITCHEN TOILET CLOGGED SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail ES									
138686					8/25/2015		238		\$0.00
Medium	Work In Progress				8/25/2015 2:08:42 PM				
Concha, Ernesto		Need 1" Sch. 40 Pvc line and 1" Pvc parts to continue with irrigation water line install in front of main building at Desert Trail.							
Johnny Acuna									
151053					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:17 AM				
Sandoval, Laura		Monthly - QRTLY BLDG INSP REPORTS (DT) - Refer to PM schedule details.							
Margret Villalobos									
150497					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:13 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
148995					3/6/2016		44		\$0.00
Medium	Work In Progress				3/6/2016 12:40:48 AM				
Acuna, Johnny		Yearly - Desert Trail ES A10 (Heat Pump)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
150247					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:46:04 AM				
Acuna, Johnny		Monthly - Desert Trail ES A16(Exhst Fan)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
145312					1/3/2016	2/3/2016	107		\$0.00
Medium	Work In Progress				1/3/2016 12:43:22 AM				
Acuna, Johnny		Yearly - Desert Trail ES - Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
150504					4/3/2016	4/24/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:18 AM				
Vallejo, Albert		Monthly - Desert Trail ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail ES									
149117					3/6/2016	3/12/2016	44		\$0.00
Medium	Work In Progress				3/6/2016 12:42:16 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
150631					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:51 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
150539					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:45 AM				
Acuna, Johnny		Monthly - Desert Trail ES- Emer Light Insp:Monthly - Refer to PMschedule details.							
Margret Villalobos									
150540					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:46 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Exit Sign Insp:Monthly - Refer to PMschedule details.							
Margret Villalobos									
150541					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:46 AM				
Acuna, Johnny		Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
151072					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:31 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Playground Insp - Refer to PMschedule details.							
Margret Villalobos									
149540					3/13/2016	3/29/2016	37		\$0.00
Medium	Work In Progress				3/13/2016 12:32:13 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Playground Insp - Refer to PMschedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail ES							
149024					3/6/2016	3/14/2016	44		\$0.00
Medium	Work In Progress				3/6/2016 12:41:10 AM				
Acuna, Johnny		Monthly - Desert Trail ES- Emer Light Insp:Monthly - Refer to PMschedule details.							
Margret Villalobos									
149025					3/6/2016	3/14/2016	44		\$0.00
Medium	Work In Progress				3/6/2016 12:41:11 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Exit Sign Insp:Monthly - Refer to PMschedule details.							
Margret Villalobos									
149026					3/6/2016		44		\$0.00
Medium	Work In Progress				3/6/2016 12:41:12 AM				
Acuna, Johnny		Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
148046		Custodial			2/19/2016		60		\$0.00
Medium	Work In Progress				2/19/2016 12:15:54 PM				
Carbajal, Jimmy		Buenas tardes . Jimmyla alfombra del portable 407 se necesita reparar por favor gracias							
Laura Sandoval									
135927					7/15/2015		279		\$0.00
Medium	Work In Progress				7/15/2015 11:48:40 AM				
Estrada, Jesus		Need to replace VCT tile in the bus lobby entrance right in front of main doors. Also, need to fill in and level out holes on this section where the tile will be replaced. Size of Area: 7' L X 11' W							
Laura Sandoval									
136190		Custodial			7/21/2015		273		\$0.00
Medium	Work In Progress				7/21/2015 11:06:40 AM				
Estrada, Jesus		Buenos dias Chuy, el piso de los Banos de kinder se necesita remplasar . Num de clases 201, 202, 203, 204, 205, 206, 207, 208, y el bano de la cocina tambien se necesita remplasar gracias							
Laura Sandoval									
151290		Custodial			4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 10:17:42 AM				
Villalobos, Jose		Buenos dias . la aspiradora Num. 0048 el jendel no se detiene se cae por favor de revisarla gracias							
Laura Sandoval									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Desert Trail ES							
151304					4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 1:54:00 PM				
Acuna, Johnny	Need an Electric Hammer Drill								
Johnny Acuna									
Count: 36 Work Orders		Avg. Age of WO's 79			Total for Desert Trail ES			0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
150406					4/1/2016		18		\$0.00
Medium	Work In Progress				4/1/2016 2:26:16 PM				
Castillo, Carlos		ACADEMY FENCE (575) 523-0779 JOE COCA							
		Spotting Instructions LOCATE N SIDE OF NEW SCHOOL BUILDING Remarks MARKED IN MAROON - CHECK IN THE FRONT OFFICE NO HAZARDS							
Alfredo Holguin									
151367		Custodial			4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 9:40:47 AM				
Villalobos, Jose		Vacuum cleaner #C08C00000151 is not working it needs to be repaired. Thank you							
Israel Ortega									
151370		Custodial			4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 10:56:20 AM				
Herrera, Marin		We are going to need a propane refill for propane burnisher #FS48IV-ES10-M. Thank you							
Israel Ortega									
151078					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:36 AM				
Ortiz, Ruben		Monthly - Desert View ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
151381		Classroom			4/14/2016		5		\$0.00
Medium	Work In Progress	Rm. 312			4/14/2016 1:56:50 PM				
Ortiz, Ruben		Deliver Art items on May 5, 2016 to Chaparral Middle. (Lee)							
Guadalupe Gonzalez									
151382		Classroom			4/14/2016		5		\$0.00
Medium	Work In Progress	Rm. 312			4/14/2016 1:58:30 PM				
Ortiz, Ruben		For Ruben Ortiz pick up Art items from Chaparral Middle on May 9, 2016. (Lee)							
Guadalupe Gonzalez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
150528					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:36 AM				
Ortiz, Ruben		Monthly - Desert View ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
150455					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:41 AM				
Vallejo, Albert		Monthly - DesertView ES - Storm Sewer Drain Inlets - Refer to PMschedule details.							
Margret Villalobos									
151048					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:13 AM				
Ortega, Israel		Monthly - QRTLY BLDG INSP REPORT (DV) - Refer to PMschedule details.							
Margret Villalobos									
148036					2/19/2016		60		\$0.00
Medium	Work In Progress				2/19/2016 7:56:22 AM				
Vallejo, Albert		Chiller and Electrical Transformer areas need to be fenced In.							
Alfredo Holguin									
148449					2/25/2016		54		\$0.00
Medium	Work In Progress	Outside			2/25/2016 3:43:39 PM				
Ortiz, Ruben		Put up Soccer Nets into both soccer goals (with net clips)							
Guadalupe Gonzalez									
150526					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:34 AM				
Ortiz, Ruben		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
151358		Exterior			4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 8:45:07 AM				
Villalobos, David		One of our water fountains in the exterior facing the lower grade playground is constantly leaking water. Our building mechanic couldn't find a shut off valve. It needs to get repaired. Thank you							
Israel Ortega									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
151359		Exterior			4/14/2016		5		\$0.00
Medium	Work In Progress			4/14/2016 8:45:29 AM					
Villalobos, David	One of our water fountains in the exterior facing the lower grade playground is constantly leaking water. Our building mechanic couldn't find a shut off valve. It needs to get repaired. Thank you								
Israel Ortega									
151186					4/12/2016		7		\$0.00
Medium	Work In Progress			4/12/2016 10:29:12 AM					
Villalobos, David	Broken faucet need to be replaced in the Zuni boys bathroom. Thank you, Ruben								
Ruben Ortiz									
143709					11/17/2015		154		\$0.00
Medium	Work In Progress			11/17/2015 2:36:41 PM					
Ontiveros, Guadalupe	Principal Araujo, is requesting for someone to come and paint the basketball lines on the basketball courts								
Ruben Ortiz									
151443		Exterior			4/15/2016		4		\$0.00
Medium	Work In Progress			4/15/2016 10:35:03 AM					
Lara, Ralph	We are going to need some extra locks now that the pump room, electrical boxes, and water tank have been gated. Thank you								
Israel Ortega									
145861					1/8/2016		102		\$0.00
Medium	Work In Progress			1/8/2016 9:19:46 AM					
Gonzalez, Salvador	Need stoppers for the swing gates on the southwest of the school; to stop them from swing								
Ruben Ortiz									
151379		Classroom			4/14/2016		5		\$0.00
Medium	Work In Progress	Rm. 224		4/14/2016 1:45:20 PM					
Lara, Ralph	Door doesn't close properly. Ask Ms. Dominguez which door. (Gonzalez)								
Guadalupe Gonzalez									
151380		Classroom			4/14/2016		5		\$0.00
Medium	Work In Progress	Rm. 325		4/14/2016 1:46:17 PM					
Lara, Ralph	The door doesn't close properly. (Gonzalez)								
Guadalupe Gonzalez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

151536 4/18/2016 1 \$0.00

Medium Work In Progress 4/18/2016 3:23:31 PM

Herrera, Marin Need 10 gals of gas for #61 Polaris and 5 gals for #402 Mower Thank you Ruben

Ruben Ortiz

151590 Classroom 4/19/2016 0 \$0.00

Medium Work In Progress Rm. 139 4/19/2016 9:17:15 AM

Ortiz, Ruben Install a dry/erase board in the classroom. (Nava)

Guadalupe Gonzalez

151279 Classroom 4/13/2016 6 \$0.00

Medium Work In Progress Rm. 321 4/13/2016 8:28:54 AM

Ortiz, Ruben Check the air conditioner it's very hot. (Serna)

Guadalupe Gonzalez

151280 Classroom 4/13/2016 6 \$0.00

Medium Work In Progress Rm. 322 4/13/2016 8:30:36 AM

Ortiz, Ruben Check air conditioner it's very hot. (Arguelles)

Guadalupe Gonzalez

151300 4/13/2016 6 \$0.00

Medium Work In Progress Outside Campus 4/13/2016 1:30:08 PM

Ortiz, Ruben Move the Mailbox down to the parking lot. (Gonzalez)

Guadalupe Gonzalez

148446 Gym 2/25/2016 54 \$0.00

Medium Work In Progress Outside 2/25/2016 3:42:40 PM

Ortiz, Ruben Paint Basketball and Volleyball lines on the court (including additional spots and marks for games and activities.

Guadalupe Gonzalez

148771 Gym 3/2/2016 48 \$0.00

Medium Work In Progress Gym 3/2/2016 9:38:22 AM

Ortiz, Ruben Hang up two banners.

Guadalupe Gonzalez

151119 Library 4/11/2016 8 \$0.00

Medium Work In Progress Library 4/11/2016 3:12:50 PM

Ortiz, Ruben Hang 12 picture frames in the library. (Sanchez-Segura)

Guadalupe Gonzalez

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Desert View ES									
148466					2/25/2016		54		\$0.00
Medium	Work In Progress	Outside			2/25/2016 3:49:41 PM				
Ortiz, Ruben	Paint swing set in upper playground.								
Guadalupe Gonzalez									
150403					4/1/2016		18		\$0.00
Medium	Work In Progress	Bike Racks			4/1/2016 2:16:50 PM				
Ortiz, Ruben	Paint Bicycle Racks.								
Guadalupe Gonzalez									
150396					4/1/2016		18		\$0.00
Medium	Work In Progress	Teacher's			4/1/2016 9:24:31 AM				
Ortiz, Ruben	Paint the cart in the Teacher's Lounge.								
Guadalupe Gonzalez									
Count: 31 Work Orders		Avg. Age of WO's 23			Total for Desert View ES			0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
135227					7/2/2015		292		\$0.00
Medium	Work In Progress				7/2/2015 2:31:29 PM				
Moncayo, Fernando		SNP Vehicle # 177 needs to be cleaned out and organized.							
Maritza Gonzalez									
149932					3/21/2016		29		\$0.00
Medium	Work In Progress				3/21/2016 1:49:41 PM				
Lara, Ralph		conversation between Alfredo and Calixto about the door inside the server room being some form of screen door as long as it has lock.							
		please talk to Alfredo or Calixto							
Cora Ramirez									
147473					2/5/2016		74		\$0.00
Medium	Work In Progress				2/5/2016 11:31:15 AM				
Lara, Ralph		Wanting to place an Auto-Door closer on the door in the Reception area[B-wing](HR section).							
Esteban Rosas									
145250					12/18/2015		123		\$0.00
Medium	Work In Progress				12/18/2015 8:19:00 AM				
Orozco, Daniel		STEAM LINE IS LEAKING. SNP MANAGER IRMA S. 882.6784							
Maritza Gonzalez									
149581		Restroom			3/14/2016		36		\$0.00
Medium	Work In Progress				3/14/2016 3:14:41 PM				
Moncayo, Fernando		Restroom overflowing in one of the stalls.							
Esteban Rosas									
150917					4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 11:05:40 AM				
Moncayo, Fernando		The light bulbs need to be replaced in the C wing hallway.							
Elisa Santillano									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
149749		Office			3/16/2016		34		\$0.00
Medium	Work In Progress	C-WING GLASS			3/16/2016 3:42:31 PM				
Moncayo, Fernando		AS PER MRS. YTURRALDE, PLEASE HAVE THE SKY LIGHT IN THE CUBICLE GLASS OFFICE IN C-WING CLEANED FROM THE INSIDE AND OUTSIDE FOR BETTER LIGHT AND VISIBILITY. THANK YOU. ANY QUESTIONS PLEASE CONTACT CATHIE WILLIAMS @ EXT. 6743				3/31/16 - as per Jimmy, route to Fernando Moncayo			
Karla Quesada									
151386					4/14/2016		5		\$0.00
Medium	Work In Progress	C-WING VAULT			4/14/2016 3:04:15 PM				
Moncayo, Fernando		AS PER MRS. YTURRALDE, SHE IS REQUESTING A SHELF TOP FOR ONE OF OUR SHELVES IN THE VAULT ROOM. THANK YOU!!!							
Karla Quesada									
139283					9/3/2015		229		\$0.00
Medium	Work In Progress				9/3/2015 10:21:09 AM				
Ambriz, Jose		Server room at GAC is warm please check ASAP							
Cora Ramirez									
150121					3/29/2016		21		\$0.00
Medium	Work In Progress				3/29/2016 3:25:53 PM				
Moncayo, Fernando		broken irrigation sprinklers							
Fernando Moncayo									
146680					1/25/2016		85		\$0.00
Medium	Work In Progress				1/25/2016 3:20:50 PM				
Castillo, Carlos		Can we get a work order for lights in the hallway by the Superintendents file room(C-wing). More details with Elisa Saenz.							
Esteban Rosas									
145521					1/4/2016		106		\$0.00
Medium	Work In Progress				1/4/2016 9:47:52 AM				
Castillo, Carlos		moving the copier from Calixto Office into computer tech office. Need electrical outlet in new office							
Cora Ramirez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
149022					3/6/2016	3/14/2016	44		\$0.00
Medium	Work In Progress				3/6/2016 12:41:09 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
149023					3/6/2016	3/14/2016	44		\$0.00
Medium	Work In Progress				3/6/2016 12:41:09 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
150537					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:43 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
150538					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:44 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
151043					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:09 AM				
Rodriguez, Arturo		Monthly - QRTLY BLDG INSP REPORT (GAC) - Refer to PM schedule details.							
Margret Villalobos									
150495					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:12 AM				
Moncayo, Fernando		Monthly - GAC Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
150246					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:46:03 AM				
Moncayo, Fernando		Monthly - GAC A-16 Fan Exh Roof Semimonthly - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
150470					4/3/2016	4/19/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:53 AM				
Moncayo, Fernando		Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.							
Margret Villalobos									
150471					4/3/2016	4/24/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:54 AM				
Moncayo, Fernando		Monthly - GAC F-39 Kitch Exh Makeup Ut Semimonthly - Refer to PM schedule details.							
Margret Villalobos									
150505					4/3/2016	4/24/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:19 AM				
Vallejo, Albert		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
150618					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:41 AM				
Moncayo, Fernando		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
142724					11/1/2015	11/22/2015	170		\$0.00
Medium	Work In Progress				11/1/2015 12:54:21 AM				
Vallejo, Albert		Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
149539					3/13/2016	3/29/2016	37		\$0.00
Medium	Work In Progress				3/13/2016 12:32:12 AM				
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
151071					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:31 AM				
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
150726					4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 7:29:25 AM				
Ambriz, Jose		Need to replace the back up unit #2 for the server room at GAC.							
Guillermo Hernandez									
150754					4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 11:59:24 AM				
Ambriz, Jose		technologymain server room need to replace backup a/c unit #2							
Fernando Moncayo									
143696					11/17/2015		154		\$0.00
Medium	Work In Progress	FEDERAL			11/17/2015 9:31:30 AM				
Moncayo, Fernando		HANG PICTURE FRAME IN OFFICE.							
Noemi Duron									
151532		Office			4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 3:05:02 PM				
Gonzales, Camilo		DELIVER 38 EMPTY BOXES TO FINANCE AT GAC FROM STUDENT RECORDS				DELIVER 38 EMPTY BOXES TO FINANCE AT GAC FROM STUDENT RECORDS			
Tracey Swinford									
150380		Hallway/Corridor			3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 4:25:10 PM				
Carbajal, Jimmy		NEED TO REPLACE OR REPAIR TILE IN HALLWAYS THE TILE IS BECOMEING A TRIP HAZZARD.							
Jimmy Carbajal									
Count: 31 Work Orders		Avg. Age of WO's 55			Total for GAC			0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC - Pre-K									
150327		Classroom			3/31/2016		19		\$0.00
Medium	Work In Progress	203			3/31/2016 1:33:31 PM				
Moncayo, Fernando Air conditioner is not turning on									
Amanda Flores									
139652					9/9/2015		223		\$0.00
Medium	Work In Progress				9/9/2015 12:40:15 PM				
Moncayo, Fernando NO ELECTRICITY IN PRE-K.									
Maritza Gonzalez									
150330		Cafeteria			3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 1:47:37 PM				
Moncayo, Fernando Please put together large water tub for playground. Equipment in boxes in Cafeteria.									
Amanda Flores									
146577		Classroom			1/22/2016		88		\$0.00
Medium	Work In Progress	203			1/22/2016 8:36:05 AM				
Moncayo, Fernando cabinet door in room 203 is hanging off hinge									
Leticia Tangonan									
150919		Classroom			4/7/2016		12		\$0.00
Medium	Work In Progress	103			4/7/2016 11:22:54 AM				
Moncayo, Fernando please assemble fumiture									
Leticia Tangonan									
150658		Classroom			4/4/2016		15		\$0.00
Medium	Work In Progress	202			4/4/2016 10:36:14 AM				
Moncayo, Fernando Please transfer loft from room 202 to 103.									
Amanda Flores									
150659		Classroom			4/4/2016		15		\$0.00
Medium	Work In Progress	202			4/4/2016 10:37:51 AM				
Moncayo, Fernando Please assemble new loft in room 202.									
Amanda Flores									
Count: 7 Work Orders		Avg. Age of WO's 56			Total for GAC - Pre-K			0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden ES									
148775		Hallway/Corridor			3/2/2016		48		\$0.00
Medium	Work In Progress				3/2/2016 10:34:44 AM				
Marquez, Gerardo		Bottom hinge broken on mechanical room near to room 308...thank you....							
Loraine Gandara									
151124					4/11/2016		8		\$0.00
Medium	Work In Progress				4/11/2016 3:23:39 PM				
Ontiveros, Joe		need assistance with assembling some easels for GES....greatly appreciate your assistance in this matter....							
Loraine Gandara									
151384		Pump House			4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 2:30:34 PM				
Apodaca, Mario		Gadsden elem irrigation well need to be pull out and inspected repair and put back in service by Anthony pump and drill							
Mario Apodaca									
151362					4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 9:20:21 AM				
Orozco, Daniel		EXHAUST FAN IN DISH ROOM IS NOT WORKING.SNP MANAGER LAURA H. 882.3410							
Maritza Gonzalez									
149985					3/22/2016		28		\$0.00
Medium	Work In Progress				3/22/2016 8:43:10 AM				
Ontiveros, Joe		La Semilla project personal are requesting for the A.V.B for flower bed to be replaced, leaking all the time.							
Guadalupe Ontiveros									
148627					2/29/2016		50		\$0.00
Medium	Work In Progress				2/29/2016 2:03:13 PM				
Marquez, Gerardo		Communications Room (west wing) - install louvers on both doors m, top and bottom.							
Alfredo Holguin									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden ES									
150333					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 1:59:00 PM				
Ontiveros, Joe		Per Mr. Ontiveros and Ms. Marquez meeting with our Garden Corordinator what was discussed in the meeting was done properly...can someone please come see what needs to be done...greatly appreciate your assistance in this matter...our Garden Cor. comes in on Wed mornings...thank you once again...							
Loraine Gandara									
146931					1/28/2016		82		\$0.00
Medium	Work In Progress				1/28/2016 3:30:00 PM				
Ontiveros, Joe		Please repair water supply for washing machine in room 101 to include installing a water filter on the supply lines.							
Albert Vallejo									
146658		Classroom			1/25/2016		85		\$0.00
Medium	Work In Progress				1/25/2016 9:31:12 AM				
Chavez, Santos		need assistance with electrical work for new computer lab in room 302 greatly appreciate your assistance							
Loraine Gandara									
151503		Classroom			4/18/2016		1		\$0.00
Medium	Work In Progress	304			4/18/2016 8:16:59 AM				
Chavez, Santos		Would you please submit a work order for a light bulb that needs to be replaced in my room, it's the one nearest to the door.							
		Thank you, Melissa							
Loraine Gandara									
146983		Classroom			1/29/2016		81		\$0.00
Medium	Work In Progress	302			1/29/2016 10:29:58 AM				
Chavez, Santos		need immediate assistance for electrical work done in room 302...just converted to computer labs...greatly appreciate your assistance in this matter...							
Loraine Gandara									
151052					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:16 AM				
Pinon, Jose		Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden ES

139709 9/10/2015 222 \$0.00

Medium Work In Progress 9/10/2015 7:25:13 AM

Ontiveros, Guadalupe Please remove trees that have died and replace with Texas Ash. Please remove the dead ones ASAP, and replant once the trees have gone dormant this fall.

Albert Vallejo

150840 4/6/2016 13 \$0.00

Medium Work In Progress 4/6/2016 2:54:42 PM

Ontiveros, Guadalupe Replace several dead trees throughout campus with new ones

Alfredo Holguin

150841 4/6/2016 13 \$0.00

Medium Work In Progress 4/6/2016 3:00:22 PM

Ontiveros, Guadalupe Replace dead bushes (pink ladies) in row on west side of building and north of the parking lot

Alfredo Holguin

136579 7/28/2015 266 \$0.00

Medium Work In Progress Playground 7/28/2015 10:29:22 AM

Ontiveros, Guadalupe please provide us with four trees in front of the school....
Arborvitae Blue Cone Plant Type: Evergreen, Mature
Size: 20' tall x 12' wide Exposure Full sun part shade,
space 6-10 feet apart. Water- moderate .

Loraine Gandara

150656 Football Field 4/4/2016 15 \$0.00

Medium Work In Progress 4/4/2016 9:30:33 AM

Ontiveros, Guadalupe Please submit this work order to Mr. Guadalupe Ontiveros.

1. Aeration and fertilizing of the field.
2. Planting of new trees.

Thank you,

Grace Marquez
Principal

Loraine Gandara

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden ES							
150521					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:31 AM				
Villalobos, Margret		Monthly - Gadsden ES - Enviro Controls Quarterly - Refer to PM schedule details.				em 4/5/16			
Margret Villalobos									
150616					4/3/2016	4/14/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:39 AM				
Ontiveros, Joe		Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.							
Margret Villalobos									
150547					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:51 AM				
Ontiveros, Joe		Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
150550					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:53 AM				
Ontiveros, Joe		Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.							
Margret Villalobos									
150551					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:53 AM				
Ontiveros, Joe		Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.							
Margret Villalobos									
148503		Hallway/Corridor			2/26/2016		53		\$0.00
Medium	Work In Progress	Mechanical			2/26/2016 9:27:38 AM				
Ontiveros, Joe		There is a loud rattling noise next to the mechanical room next to the Nurses Station...greatly appreciate your assistance in this matter...							
Loraine Gandara									
142949					11/3/2015		168		\$0.00
Medium	Work In Progress	Conference			11/3/2015 9:26:50 AM				
Gallegos, Rafael		need immediate assistance for leak in roof...water coming in greatly appreciate assistance...							
Loraine Gandara									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden ES									
149481					3/11/2016		39		\$0.00
Medium	Work In Progress				3/11/2016 2:31:13 PM				
Gonzalez, Salvador		Anchor soccer goals in field.							
Albert Vallejo									
Count: 25 Work Orders			Avg. Age of WO's	52		Total for Gadsden ES	0		\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
151473					4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 3:43:21 PM				
Medina, Eric		At GHS for Building Mechanic to please fix the open pipe east of the counselors office. Pipe is broken so cap does not stay on. This poses a safety hazard. Please refer to e-mail for pictures of pipe. Should you have any questions please contact Mr. Gallegos in the construction office at 575-882-6921. Thank You							
Dominique Esparza									
150994					4/8/2016		11		\$0.00
Medium	Work In Progress				4/8/2016 1:22:43 PM				
Medina, Eric		unclog toilets in café kitchen							
Eric Medina									
151167					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 7:02:15 AM				
Medina, Eric		please on the weigh room to the girls bathroom stall in the weight room is broken. thank you							
Luis Saucedo									
151529					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 2:58:47 PM				
Medina, Eric		need to remove chalk board and install new white board in Ms Hartman's portable							
Eric Medina									
151530	North Building				4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 3:00:47 PM				
Medina, Eric		need to repair partition in boy gang north building							
Eric Medina									
150980		Classroom			4/8/2016		11		\$0.00
Medium	Work In Progress				4/8/2016 9:16:23 AM				
Medina, Eric		Requested by Mr. Palmer Rm. 612 Science Building- Check air conditioner, not working.							
Velia Alarcon									
151010					4/8/2016		11		\$0.00
Medium	Work In Progress				4/8/2016 3:30:33 PM				
Escobar, David		04/08/2016. unclog urinal at admin men's restroom.							
David Escobar									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

151292 Academic Bldg Restroom 4/13/2016 6 \$0.00

Medium Work In Progress 4/13/2016 10:42:49 AM

Medina, Eric please on the boys restroom on the academic building
the urinal is clogged i tried to unpluged but no luck.

thank you

Luis Saucedo

150265 3/31/2016 19 \$0.00

Medium Work In Progress 3/31/2016 6:57:06 AM

Medina, Eric please on the annexbuilding on the girls bathroom
there are 2 toilet seats when flush there leaking from
the back wall put i a bag over. thank you

Luis Saucedo

148778 3/2/2016 48 \$0.00

Medium Work In Progress 3/2/2016 10:54:14 AM

Medina, Eric order and install coat hooks in cabinet for weight room

Eric Medina

149297 Academic Bldg 3/9/2016 41 \$0.00

Medium Work In Progress 3/9/2016 8:14:05 AM

Escobar, David please the ligths in front of the varisty gym burn out is to
dark in the morning.

thank you

Luis Saucedo

149467 3/11/2016 39 \$0.00

Medium Work In Progress 3/11/2016 10:51:45 AM

Escobar, David Requested by Ms. Leahy Rm. 343 Academic Building-
Light bulbs in Faculty Restroom need to be replaced.

Velia Alarcon

149495 3/11/2016 39 \$0.00

Medium Work In Progress 3/11/2016 3:38:33 PM

Escobar, David trouble shoot electrical circuit to lights in boys baseball
locker room.

David Escobar

150993 4/8/2016 11 \$0.00

Medium Work In Progress 4/8/2016 1:16:55 PM

Escobar, David 04/08/2016.
repair door closer at storage room 212 in main building.

David Escobar

4/19/2016 12:10:24 PM

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden HS

150998 New Admin Bldg 4/8/2016 11 \$0.00

Medium Work In Progress 4/8/2016 3:00:36 PM

Escobar, David Requested by Debbie Costalez for Women's Faculty Restroom in Admin. Building-The original toilet paper dispensers need to be removed from stalls. Dispensers are not used at all. One of the dispensers has a missing piece and are in the way of the big dispensers.

Velia Alarcon

151000 New Admin Bldg 4/8/2016 11 \$0.00

Medium Work In Progress 4/8/2016 3:09:18 PM

Escobar, David Requested by Debbie Costalez for Rm. 725 Parent Work Room in Admin. Building-The original paper towel dispenser needs to be removed from wall and the back wall over the sink needs to be painted as well.

Velia Alarcon

151468 4/15/2016 0 \$0.00

Medium Work In Progress 4/15/2016 3:33:14 PM 4/15/2016

Escobar, David 04/15/2016. unclog mop sink at janitor closet at cafeteria .

David Escobar

151442 4/15/2016 4 \$0.00

Medium Work In Progress 4/15/2016 10:11:53 AM

Escobar, David Requested by Mr. J. Mora Rm. 227 North Building-Two whiteboards need to be installed on the walls of the athletic training room office and main area. SEE MR. MORA FOR WHITEBOARDS AND LOCATION HE NEEDS BOARDS PLACED.

Velia Alarcon

150394 4/1/2016 18 \$0.00

Medium Work In Progress 4/1/2016 9:11:34 AM

Medina, Eric Requested by Chief Escudero for Ropes on the two Flag Poles by the Bus Turn Around-Please replace all four ropes on the two flag poles. One of the ropes on the U.S. flag pole ripped yesterday and the second one also has a tear and might rip soon.

Velia Alarcon

151394 Grounds Shop 4/14/2016 5 \$0.00

Medium Work In Progress 4/14/2016 3:36:58 PM

Herrera, Jaime Need two top side bed mount tool boxes to store more tools, chains, booms and straps. Also easier access to get items from tool boxes to tie down equipment. Thank you

Jaime Herrera

4/19/2016 12:10:24 PM

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

150384	Grounds Shop	Mechanical			4/1/2016		18		\$0.00
--------	--------------	------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/1/2016 7:38:08 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Apodaca, Mario
need spare blower motor for waste water treatment plant

Salvador Martinez

149349					3/9/2016		41		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/9/2016 3:47:32 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Apodaca, Mario
Need to have grease traps pumped out at panther hut

Eric Medina

149351					3/9/2016		41		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/9/2016 3:48:30 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Apodaca, Mario
Mario need chemical for floor drains thank you

Eric Medina

140674	Main Building	Pump House			9/25/2015		207		\$0.00
--------	---------------	------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/25/2015 4:01:26 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sanchez, Raul
9/25/15
Requesting a work order for the installation of chlorination equipment for the supplemental domestic well in case of emergency use

Thanks, Raul

Raul Sanchez

150752	Cafeteria (1998)	Kitchen			4/5/2016		14		\$0.00
--------	------------------	---------	--	--	----------	--	----	--	--------

High	Work In Progress				4/5/2016 10:26:32 AM				
------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Daniel
Need knobs on the Southbend Stove/Oven Combo to operate. Broken need replacing. SNP Manager Frances Black 575-882-5522

Dino Facio

139963	Pool Pump	Pump House			9/15/2015		217		\$0.00
--------	-----------	------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/15/2015 7:55:51 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador
fabricate square tubing post to support pool canopy shade

Mario Apodaca

150787					4/5/2016		14		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/5/2016 3:47:09 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Gonzalez, Salvador
Chava need to replace holding pole for fence in parent drop off please

Eric Medina

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

143192 11/6/2015 165 \$0.00

Medium Work In Progress 11/6/2015 10:49:59 AM

Gonzalez, Salvador Requested by Coach Vasquez for Football Locker Room in the Boy's Gym-Extension to existing wall in equipment room.

Velia Alarcon

147595 2/8/2016 71 \$0.00

Medium Work In Progress 2/8/2016 3:40:49 PM

Gonzalez, Salvador Need to install window guard to new doors installed at the Weight room.

Guillermo Hernandez

148065 2/19/2016 60 \$0.00

Medium Work In Progress 2/19/2016 3:24:59 PM

Gonzalez, Salvador Need to replace gate wheels and hinges to the south gate (automatic gate).

Guillermo Hernandez

150844 4/6/2016 13 \$0.00

Medium Work In Progress 4/6/2016 3:21:08 PM

Gonzales, Camilo requesting scissor lift for WO#149297.

David Escobar

149784 3/17/2016 33 \$0.00

Medium Work In Progress 3/17/2016 7:36:36 AM

Herrera, Jaime Danny or Ruben if you could please order me these items please: Socket wrench set, Metric combination wrenches, SAE combination wrenches, Socket bit set, Cordless grease gun and a 35ft tape measure. Thank you

Jaime Herrera

147722 2/10/2016 69 \$0.00

Medium Work In Progress 2/10/2016 1:59:33 PM

Vallejo, Albert Requested by Coach Walker for Under Stadium Storage Rooms for Track-Create/build concrete entrance sidewalks for under stadium storage rooms (track and football).

Velia Alarcon

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
146628					1/22/2016		88		\$0.00
Medium	Work In Progress				1/22/2016 3:52:32 PM				
Flores, Pete		please the john deere gator uv-ghs-0905 is making a lot of noise when driving can yuo plese see as we needed to move furniture it thank you							
Luis Saucedo									
151472					4/15/2016		4		\$0.00
Medium	Work In Progress	Vehicle #154			4/15/2016 3:43:17 PM				
Flores, Pete		Pete truck-154 - is leaking water from engine from Gadsden high school							
Eric Medina									
142871					11/2/2015		169		\$0.00
Medium	Work In Progress				11/2/2015 10:56:01 AM				
Flores, Pete		please the john deere gator uv-ghs-0905 flat tire from the back of passenger side not good thank you							
Luis Saucedo									
144164					12/2/2015		139		\$0.00
Medium	Work In Progress				12/2/2015 6:47:00 AM				
Flores, Pete		please the john deere gator uv-ghs-0905 is making a lot of noise when driving can yuo plese see it thank you							
Luis Saucedo									
149175	Pool Pump	Pool			3/7/2016		43		\$0.00
Medium	Work In Progress				3/7/2016 3:42:37 PM				
Apodaca, Mario		GHS- pool start-up need to get ready for up coming season.							
Mario Apodaca									
147417	Pool Pump	Pump House			2/4/2016		75		\$0.00
Medium	Work In Progress				2/4/2016 3:14:36 PM				
Apodaca, Mario		need 2 babychanging station for the dressing room for the new regulation							
Mario Apodaca									
151377					4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 12:38:07 PM				
Lara, Ralph		please joe having problems with his keydc20 for the swimming pool.							
		thank you							
Luis Saucedo									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
151581					4/19/2016		0		\$0.00
Medium	Work In Progress				4/19/2016 7:45:47 AM				
Lara, Ralph		Rafa need new key for panther hut storage teacher lost hers							
Eric Medina									
150303					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 11:11:12 AM				
Lara, Ralph		Requested by Ms. Miller for Theater Building-Please check lobby doors and back door (facing North Building) for key issues on metal bar. Requires a drill and removal of entire piece to take key out; it gets stuck when trying to release the bar.							
Velia Alarcon									
138952					8/28/2015		235		\$0.00
Medium	Work In Progress				8/28/2015 2:15:09 PM				
Lara, Ralph		Need to replace the panic bars to back doors of the library, the alarm stopped working and they are losing books.							
Guillermo Hernandez									
150922		Classroom			4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 1:03:30 PM				
Lara, Ralph		Requested by Mrs. Scott Rm. 515 CTE Building-Needs to have a file cabinet re-keyed.							
Velia Alarcon									
146829		Athletic Field			1/27/2016		83		\$0.00
Medium	Work In Progress	Track			1/27/2016 10:12:18 AM				
Ontiveros, Guadalupe		Requested by Coach Walker for Track-Repair/resurface GHS Track 4-6 spots on track are extremely cracked, worn or have holes on track surface. If/when possible track needs to be resurfaced.							
Velia Alarcon									
141301		Athletic Field			10/8/2015		194		\$0.00
Medium	Work In Progress	Track Field			10/8/2015 3:36:12 PM				
Ontiveros, Guadalupe		Requested by Coach Walker for Track Field-Inspect track, track has bubbled at the 14 yd marker and has worn patches (x3-5). Needs to be repaired and remarked.							
Velia Alarcon									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
146493					1/21/2016		89		\$0.00
Medium	Work In Progress				1/21/2016 7:49:11 AM				
Ontiveros, Guadalupe		Need to fill the rain run-outs around campus.							
Guillermo Hernandez									
148287					2/24/2016		55		\$0.00
Medium	Work In Progress				2/24/2016 8:43:23 AM				
Ontiveros, Guadalupe		Requested by Coach Yanez for Baseball Field-Install maroon windscreen slats on the baseball outfield fence, similar to S.T.H.S. fence. SEE COACH YANEZ FOR MORE INFORMATION.							
Velia Alarcon									
151388					4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 3:29:32 PM				
Villalobos, David		David need to replace supply water valve in mechanical room boys football locker room							
Eric Medina									
149708	Pool Dressing	Pool			3/16/2016		34		\$0.00
Medium	Work In Progress				3/16/2016 7:42:52 AM				
Villalobos, David		The shower faucets, shower heads, sink faucets & toilets need to be checked and replaced if needed. This needs to be done due to pool inspection coming up.							
Terry Alvarado									
148634	Pool Pump	Pump House			2/29/2016		50		\$0.00
Medium	Work In Progress				2/29/2016 2:57:20 PM				
Villalobos, David		2 inch copper water line need to install a water strainer at the ghs pool pump room							
Mario Apodaca									
143088					11/5/2015		166		\$0.00
Medium	Work In Progress				11/5/2015 7:01:35 AM				
Villalobos, David		please on the weight room girls restrooms the sink is clogged and over flows i tried to uncloged but no luck thank you							
Luis Saucedo									
136037	Boys Gym				7/16/2015		278		\$0.00
Medium	Work In Progress				7/16/2015 4:00:37 PM				
Villalobos, David		As per Mr. Giron he would like to have all the showers working. Location is locker rooms in the Boys Gym.							
Guillermo Hernandez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

150730 4/5/2016 14 \$0.00

Medium Work In Progress 4/5/2016 8:00:28 AM

Villalobos, David 04/05/2016.
piping in wall of girls restroom in weight room will not clear out.

David Escobar

146662 Boys Gym 1/25/2016 85 \$0.00

Medium Work In Progress 1/25/2016 11:18:30 AM

Villalobos, David Install gang sinks in boys gym.
(See Albert)

Albert Vallejo

146942 1/28/2016 82 \$0.00

Medium Work In Progress 1/28/2016 3:45:15 PM

Villalobos, David taco circulating pumps for main building need replacing

Eric Medina

140227 9/18/2015 214 \$0.00

Medium Work In Progress 9/18/2015 1:53:22 PM

Chavez, Santos Santos need to rewire outside light near panther paw light dropped and pulled out wires

Eric Medina

150797 Library Library 4/5/2016 14 \$0.00

Medium Work In Progress 4/5/2016 3:54:09 PM

Castillo, Carlos Requested by Matt Grubaugh for Library-Has two new alarms/locks that he needs installed on the Library's emergency exits. The ones there are now are battery operated and unreliable. The alarms he wants installed are hard wired in the Library's wiring. They go off for 15 seconds before opening the door.

Velia Alarcon

148428 2/25/2016 54 \$0.00

Medium Work In Progress 2/25/2016 12:31:14 PM

Castillo, Carlos Need to install outlets on commercial a/c's on vocational building

Eric Medina

149566 3/14/2016 36 \$0.00

Medium Work In Progress 3/14/2016 10:54:21 AM

Castillo, Carlos Need to cancel out emergency ballast in faculty restroom in academic building

Eric Medina

4/19/2016 12:10:24 PM

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
149709	Pool Dressing	Pool			3/16/2016		34		\$0.00
Medium	Work In Progress				3/16/2016 7:47:20 AM				
Escobar, David	The walls in the pool dressing rooms and office area need to be touched up and repaired where needed and all re-painted. This needs to be done due to pool inspection coming up.								
Terry Alvarado									
149710	Pool Dressing	Pool			3/16/2016		34		\$0.00
Medium	Work In Progress				3/16/2016 7:52:34 AM				
Castillo, Carlos	Lighting in dressing rooms and outside of the pool deck need to be checked and repaired if needed. This needs to be done due to pool inspection coming up.								
Terry Alvarado									
146847		Athletic Field			1/27/2016		83		\$0.00
Medium	Work In Progress				1/27/2016 2:27:04 PM				
Holguin, Alfredo	Football field Artificial Turf - Perform SportChamp deep cleaning service, Seam Repairs and add infill Rubber								
Alfredo Holguin									
141599					10/13/2015		189		\$0.00
Medium	Work In Progress				10/13/2015 11:37:31				
Ontiveros, Guadalupe	Trash Dumpsters along south access road- Move one regular trash dumpster from the block enclosed area across from Tech/Ag building to the block enclosed area across from the nurse/girls gym. Call Alfredo as soon as the move is completed								
Alfredo Holguin									
150740		Athletic Field			4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 8:44:03 AM				
Ronquillo, Ruben	need 15 gallon sprayer								
Guadalupe Ontiveros									
150477					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:58 AM				
Flores, Pete	Monthly - GHS-UV-0515 PM Service - Refer to PM schedule details.								
Margret Villalobos									
150496					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:13 AM				
Escobar, David	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
151047					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:12 AM				
Saucedo, Luis		Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.							
Margret Villalobos									
150472					4/3/2016	4/24/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:54 AM				
Escobar, David		Monthly - Gadsden HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
150460					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:45 AM				
Escobar, David		Yearly - Gadsden HS A13 (Ceil/Wall Unit)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
149530					3/13/2016		37		\$0.00
Medium	Work In Progress				3/13/2016 12:32:06 AM				
Escobar, David		Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
148564					2/29/2016	3/31/2016	50		\$0.00
Medium	Work In Progress				2/29/2016 12:58:14 AM				
Escobar, David		Yearly - Gadsden HS C-11 (Evap.Condnser)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
150523					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:32 AM				
Villalobos, Margret		Monthly - Gadsden HS - Enviro Controls Quarterly - Refer to PM schedule details.				em 4/5/16			
Margret Villalobos									
150617					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:40 AM				
Escobar, David		Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
143602					11/15/2015		145	4.5	\$208.43
Medium	Work In Progress				11/15/2015 12:27:53	4/8/2016			
Villalobos, Jose		Yearly - Gadsden HS - Mow (0408/0419/0428) Grounds - Refer to PM schedule details.				Pending 0419/0428 completed work on 0408 on 3/31/2016 replaced air, oil, fuel filters & blades, reverse pedal			
Margret Villalobos									
150510					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:23 AM				
Vallejo, Albert		Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
148578					2/29/2016		50		\$0.00
Medium	Work In Progress				2/29/2016 12:58:25 AM				
Vallejo, Albert		Yearly - Gadsden HS - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
150569					4/3/2016	5/4/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:06 AM				
Medina, Eric		Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
150570					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:07 AM				
Medina, Eric		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
150574					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:10 AM				
Medina, Eric		Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
150593					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:23 AM				
Medina, Eric		Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
150892					4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 12:32:14 AM				
Medina, Eric		Daily - Gadsden HS - Fire Pump (Biweekly) - Refer to PM schedule details.							
Margret Villalobos									
150606					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:32 AM				
Martinez, Salvador		Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
150324		Office			3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 1:22:21 PM				
Gonzales, Camilo		Deliver 2 large boxes. PO# 15165314. Attn: Athletic Department/Volleyball. Thank you.							
Theresa Ramirez									
151283					4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 8:43:54 AM				
Vallejo, Albert		Repair door frame in gym.							
Albert Vallejo									
151275					4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 8:16:49 AM				
Carbajal, Jimmy		il am requesting for the varnishing of the 3 gym. floors, varsity gym, boys, and the girls gym., to begin on june the 27th until they are completed. thank you							
Luis Saucedo									
151460		Classroom			4/15/2016		4		\$0.00
Medium	Work In Progress	341			4/15/2016 2:34:08 PM				
Medina, Eric		Requested by Ms. Morales Rm. 341 Academic Building- A/C is only blowing out hot air. Maybe the water pump needs replacing.							
Velia Alarcon									
149565					3/14/2016		36		\$0.00
Medium	Work In Progress				3/14/2016 10:40:52 AM				
Medina, Eric		reinstall blower housing in portable 1							
Eric Medina									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
149818					3/17/2016		33		\$0.00
Medium	Work In Progress				3/17/2016 3:28:05 PM				
Medina, Eric		need to replace pully wheel for make up air unit in science building							
Eric Medina									
146908		Athletic Field			1/28/2016		82		\$0.00
Medium	Work In Progress				1/28/2016 11:02:35 AM				
Ontiveros, Guadalupe		Requested by Coach Walker for Discus/Shot Put Cage- Check/repair and install net for track discus/shot put cage on soccer field.							
Velia Alarcon									
151369					4/14/2016		5		\$0.00
Medium	Work In Progress	UV GHS 0905			4/14/2016 10:46:29 AM				
Flores, Pete		UV GHS 0905 The steering is out of the alignment on the left front when turning to left rubs against the fender as per statement send to Mr. Carbajal today.							
Luis Saucedo									
151504	Pool Dressing	Pool			4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 8:30:31 AM				
Saucedo, Luis		Walls & floors need to be scrubbed in dressing rooms, showers and office area. This needs to be done before the inspection on May 10th.							
Terry Alvarado									
146050					1/12/2016		98		\$0.00
Medium	Work In Progress				1/12/2016 9:46:07 AM				
Carbajal, Jimmy		please i have one dolly with flat tires. thank you							
Luis Saucedo									
151462					4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 3:07:15 PM				
Villalobos, David		David need to demo east football locker room							
Eric Medina									
Count: 94 Work Orders			Avg. Age of WO's	49		Total for Gadsden HS	4.5	\$208.43	

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden MS							
151516		Office			4/18/2016		1		\$0.00
Medium	Work In Progress	B-Wing Office			4/18/2016 9:52:24 AM				
Carbajal, Jimmy		Carpet needs to be removed, its very old. Rita Dominguez Office #133							
Hilda Adler									
151440		Office			4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 9:47:57 AM				
Gonzales, Camilo		Pick up obsolete items and deliver to Instructional Materials for disposal. Thank you.							
Theresa Ramirez									
151193		Office			4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 10:43:39 AM				
Gonzales, Camilo		Deliver 1 box. PO# 151606441. Attn: SNP. Thank you.							
Theresa Ramirez									
151117					4/11/2016		8		\$0.00
Medium	Work In Progress	Choir Room			4/11/2016 2:53:32 PM				
Carbajal, Jimmy		Room 306 - need to carpet new stage.							
Danny Miranda									
140575	Annex	Hallway/Corridor			9/24/2015		208		\$0.00
Medium	Work In Progress				9/24/2015 3:17:11 PM				
Solis, Lorenzø		water fountain in annexis leaking							
		Please contact Mario Herrera							
Mario Herrera									
150901	Cafeteria	Office			4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 8:43:55 AM				
Solis, Lorenzø		need to replace duct work SNP office							
Mario Herrera									
150829		Classroom			4/6/2016		13		\$0.00
Medium	Work In Progress	A-Wing Rm#			4/6/2016 9:54:07 AM				
Soria, Martin		There's dead roaches in lighting fixtures. Please clean							
Hilda Adler									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
151580	Gym	Gym			4/19/2016		0		\$0.00
Medium	Work In Progress				4/19/2016 7:44:45 AM				
Carbajal, Jimmy Please have them come varnish the gym floor anytime after June they can come anytime in July due to YMCA games									
Martin Soria									
148921		Custodial			3/4/2016		46		\$0.00
Medium	Work In Progress				3/4/2016 10:44:40 AM				
Flores, Pete Front tire of the Gator has a flat.									
Martin Soria									
151519					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 11:45:25 AM				
Herrera, Mario Requesting small and large copper tube cutter									
Mario Herrera									
150608					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:34 AM				
Apodaca, Mario Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.									
Margret Villalobos									
146986	C-Wing				1/29/2016		81		\$0.00
Medium	Work In Progress	AVECHS-			1/29/2016 10:52:15 AM				
Chavez, Santos need to install an outlet in the student union.									
Rosa Quezada									
151216					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 3:30:21 PM				
Ontiveros, Joe GIRLS BATHROOM LEAKS ON BOTTOM. WET FLOOR. SAFETY ISSUE..(QUEZADA)									
Rosa Quezada									
148847	C-Wing	Office			3/3/2016		47		\$0.00
Medium	Work In Progress	AVECHS-			3/3/2016 10:44:24 AM				
Chavez, Santos Need an electrical outlet installed in ceiling for the projector in the conference room. (hood)									
Rosa Quezada									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden MS							
145061	C-Wing	Office			12/15/2015		126		\$0.00
Medium	Work In Progress	AVECHS-			12/15/2015 1:02:11 PM				
Chavez, Santos		THE LIGHT SWITCH IN THE WORKROOM NEEDS TO BE MOVED TO THE FRONT OF THE ROOM ENTRANCE INSTEAD OF BY THE EXIT DOOR. (QUEZADA)							
Rosa Quezada									
150535					4/3/2016	4/19/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:42 AM				
Villalobos, Margret		Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details. em 4/5/16							
Margret Villalobos									
150254					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:46:09 AM				
Herrera, Mario		Monthly - Gadsden MS A-16 Fan Exhaust Semiannual - Refer to PM schedule details.							
Margret Villalobos									
150459					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:44 AM				
Herrera, Mario		Yearly - Gadsden MS A-13 A/C Wall Mount Yearly - Refer to PM schedule details.							
Margret Villalobos									
150463					4/3/2016	4/19/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:47 AM				
Herrera, Mario		Monthly - Gadsden MS A-1 Wall Ref Elec Semiannual - Refer to PM schedule details.							
Margret Villalobos									
148574					2/29/2016	3/31/2016	50		\$0.00
Medium	Work In Progress				2/29/2016 12:58:22 AM				
Herrera, Mario		Yearly - Gadsden MS C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
151055					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:18 AM				
Soria, Martin		Monthly - QRTLY BLDG INSP REPORT (GM) - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
150519					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:29 AM				
Herrera, Mario		Monthly - Gadsden MS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
150602					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:29 AM				
Herrera, Mario		Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
150603					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:30 AM				
Herrera, Mario		Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
151356	C-Wing				4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 7:43:15 AM				
Ontiveros, Guadalupe		would like 10 bags for fertilizer							
		Thank you							
Mario Herrera									
151269	C-Wing				4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 7:59:26 AM				
Herrera, Mario		Front of C-Wing, please cut weeds and cut grass.							
Margret Villalobos									
151102					4/11/2016		8		\$0.00
Medium	Work In Progress	Choir Room			4/11/2016 10:44:47 AM				
Chavez, Santos		Room 306 - prewire for outlets on new stage.							
Danny Miranda									
151463					4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 3:11:49 PM				
Castillo, Carlos		A-Wing - No power							
Mario Herrera									
143779					11/18/2015		153		\$0.00
Medium	Work In Progress				11/18/2015 1:03:44 PM				
Chavez, Santos		Silver is checking on the scoreboard in the gym. They are having issues. He thinks it is electrical.							
Cora Ramirez									
4/19/2016 12:10:24 PM									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
140237	C-Wing				9/18/2015		214		\$0.00
Medium	Work In Progress	Main Annex			9/18/2015 3:00:33 PM				
Chavez, Santos		THERE WAS A POWER OURTAGE IN THE BUILDING. PLEASE EVALUATE SITUATION ASAP.							
Yvette Cortez									
139909					9/14/2015		218		\$0.00
Medium	Work In Progress				9/14/2015 2:07:22 PM				
Chavez, Santos		Please see Mario, Building Mechanic regarding Exit Signs							
Mario Herrera									
139952	Annex				9/14/2015		218		\$0.00
Medium	Work In Progress	Annex Electrical			9/14/2015 4:04:27 PM				
Chavez, Santos		Annex electrical boxis not working or jumping as well.							
Hilda Adler									
149740		Athletic Field			3/16/2016		34		\$0.00
Medium	Work In Progress	Baseball batting			3/16/2016 3:17:38 PM				
Chavez, Santos		I am requesting an electrical outlet on or by the batting cages at GMS. Should you have anyquestions please contact M. Mora. Thank you							
Hilda Adler									
141522	Band Room	Classroom			10/12/2015		190		\$0.00
Medium	Work In Progress	Rm#100 Band /			10/12/2015 3:10:56 PM				
Chavez, Santos		Install wall electrical outlet under sink.							
Hilda Adler									
139948		Football Field			9/14/2015		218		\$0.00
Medium	Work In Progress	Electrical/Field -			9/14/2015 3:58:31 PM				
Chavez, Santos		Electrical ground box by the football field to connect the football clock is not working.							
Hilda Adler									
146587					1/22/2016		88		\$0.00
Medium	Work In Progress				1/22/2016 10:50:50 AM				
Chavez, Santos		Replace perimeter lights to improve lighting conditions in parking lot.							
Albert Vallejo									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
148765		Kitchen			3/2/2016		48		\$0.00
High	Work In Progress				3/2/2016 8:44:03 AM				
Chavez, Santos		Need two electrical plugs installed outside the kitchen office area. SNP Manager Teresa Portillo (575) 882-2824							
Dino Facio									
143488					11/12/2015		159		\$0.00
Medium	Work In Progress				11/12/2015 3:31:25 PM				
Marquez, Gerardo		Need to supply chain and padlock for electrical meter enclosure, so EPEC can double lock.							
Albert Vallejo									
151293		Storage			4/13/2016		6		\$0.00
Medium	Work In Progress	room next to			4/13/2016 11:35:24 AM				
Marquez, Gerardo		Change lock (Off Master) re-key, per Mrs. Quinonez. Contact Connie for instructions.							
Hilda Adler									
150454	Gymnasium	Restroom			4/1/2016		18		\$0.00
Medium	Work In Progress	Boys & Girls			4/1/2016 4:33:34 PM				
Lara, Ralph		The locks on the stalls in the boys and girls restrooms by the gym lobby are not working. Please fix, thank you.							
Hilda Adler									
147819					2/11/2016		68		\$0.00
Medium	Work In Progress				2/11/2016 3:38:09 PM				
Herrera, Mario		need 30 in rake and adjustable wrenches . and ratchet wrenches							
Mario Herrera									
146767					1/26/2016		84		\$0.00
Medium	Work In Progress				1/26/2016 3:11:59 PM				
Herrera, Mario		Need supplies and replacement components for AC units (Master Cools)							
Mario Herrera									
149643	Cafeteria	Cafeteria			3/15/2016		35	0.5	\$12.50
Medium	Work In Progress	Cafeteria-			3/15/2016 10:42:04 AM				
Herrera, Mario		There are several floor tiles in the kitchen that need repair. They are lifting and a hazard to the employees. Please repair or replace ASAP. Thank you.				3/29/16 - as per Jimmy, there are only like 6 to 8 tiles that need to be re-glued reassign to bldg. mech. (no asbestos in kitchen).			
Hilda Adler						4/6/16 - asp Mario, there are several pieces broken and need to be replaced. faxed to rodriguez for quote.			

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

151454	C-Wing	Office			4/15/2016		4		\$0.00
--------	--------	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/15/2016 1:19:30 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Mario relocated keyboard and side hand drawer

Mario Herrera

149315	Vocational	Classroom			3/9/2016		41		\$0.00
--------	------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Room #302			3/9/2016 11:00:10 AM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Herrera, Mario Please check and seals/repair windows and doors. Too much dirt is coming in to the classroom.

Hilda Adler

151511					4/18/2016		1		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/18/2016 8:58:06 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Herrera, Mario requesting 25 emergencylights and 25 exit signs

Mario Herrera

143775					11/18/2015		153		\$0.00
--------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/18/2015 12:13:09				
--------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo SNP OFFICES, NEED 4 CD1 KEYS FOR STORAGE.

Maritza Gonzalez

145979					1/11/2016		99		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	See Mr.Mora			1/11/2016 9:54:29 AM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Marquez, Gerardo Requesting an expanded metal storage with -in a storage with (1) expanded door & (1) loft key. Please see Mr. Mora for details. Thank you

Hilda Adler

137816	C-Wing				8/12/2015		251		\$0.00
--------	--------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	AVECHS -			8/12/2015 9:06:55 AM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Marquez, Gerardo Need keys issued for Custodian Jeremy Apodaca and Counselor Evelyn Chisari.

Margret Villalobos

145125		Cafeteria			12/16/2015		125		\$0.00
--------	--	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/16/2015 8:52:29 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo PLEASE GET A PRICE QUOTE TO REFURBISH OR REPLACE CAFETERIA ROLL UP DELIVERY DOOR.

Gerardo Marquez

145631	C-Wing	Portables			1/5/2016		105		\$0.00
--------	--------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				1/5/2016 2:44:05 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Vallejo, Albert Roof in Nursing Dept portable leaking.

Lisa Alarcon

4/19/2016 12:10:25 PM

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
147790					2/11/2016		68		\$0.00
Medium	Work In Progress				2/11/2016 10:24:51 AM				
Ontiveros, Joe		Need new Faucets and Faucet plates and 3/8x1/2x12 w/supply lines							
Mario Herrera									
147728					2/10/2016		69		\$0.00
Medium	Work In Progress				2/10/2016 3:07:35 PM				
Ontiveros, Joe		Backflow is leaking							
Joe Ontiveros									
146039	Gym	Mechanical			1/12/2016		98		\$0.00
Medium	Work In Progress				1/12/2016 8:00:16 AM				
Ontiveros, Joe		Domestic water heater in Mechanical room pressure relief valve is leaking							
Mario Herrera									
138659					8/25/2015		238		\$0.00
Safety	Work In Progress				8/25/2015 9:23:01 AM				
Ontiveros, Joe		Eye Wash - All 3 missing string for shower and 002-valve is broken asp PM 136938							
Mario Herrera									
140230	Annex	Restroom			9/18/2015		214		\$0.00
Medium	Work In Progress				9/18/2015 2:27:59 PM				
Ontiveros, Joe		please replace new sink faucets with new ones kids are leaving them on.							
Martin Soria									
138519	C-Wing	Office			8/21/2015		242		\$0.00
Medium	Work In Progress	AVECHS -			8/21/2015 2:40:17 PM				
Marquez, Gerardo		NEED OPEN SHELVING FOR KITCHEN AREA. PLEASE CONTACT MRS. HOOD OR MRS QUEZADA FOR FURTHER DETAILS AT 882-6770.							
Yvette Cortez									
149479					3/11/2016		39		\$0.00
Medium	Work In Progress				3/11/2016 2:28:18 PM				
Miranda, Danny		Build a raised platform in room 306. See Rick Martinez/Albert Vallejo for details.							
Albert Vallejo									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
151301	Cafeteria				4/13/2016		6		\$0.00
High	Work In Progress				4/13/2016 1:32:45 PM				
Orozco, Daniel		Milk Cooler not cooling. SNP Manager Terry Portillo (575) 882-2824							
Dino Facio									
149729					3/16/2016		34		\$0.00
Medium	Work In Progress				3/16/2016 11:57:21 AM				
Orozco, Daniel		REACH IN FREEZER IS DOWN . SNP MANAGER TERRY P. 882.2824							
Maritza Gonzalez									
149214					3/8/2016		42		\$0.00
Medium	Work In Progress				3/8/2016 8:03:00 AM				
Carrasco, Danny		SNP OFFICES - REQUESTING SIGN INDICATING STUDENT NUTRITION PROGRAM ADMINISTRATION OFFICES. HORIZONTAL (SEE ATTACHED)							
Maritza Gonzalez									
150092		Parking Lot			3/29/2016		21		\$0.00
Medium	Work In Progress				3/29/2016 8:09:34 AM				
Gonzalez, Salvador		Need adapters for pole lights for new LED lighting							
Santos Chavez									
144336	East Mechanical				12/4/2015		137		\$0.00
Medium	Work In Progress				12/4/2015 8:27:19 AM				
Marquez, Gerardo		Requesting new doors to boiler room							
Mario Herrera									
144337					12/4/2015		137		\$0.00
Medium	Work In Progress				12/4/2015 8:28:05 AM				
Marquez, Gerardo		Requesting new doors to mechanical room behind cafeteria							
Mario Herrera									
150885	Cafeteria	Cafeteria			4/6/2016		13		\$0.00
Medium	Work In Progress	Cafeteria door			4/6/2016 4:34:40 PM				
Marquez, Gerardo		The hinge on top of the Cafeteria door broke off. Please repair. thank you.							
Hilda Adler									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Gadsden MS										
151438	C-Wing	Portables			4/15/2016		4		\$0.00	
Medium	Work In Progress				4/15/2016 8:13:11 AM					
Gonzalez, Salvador		Due to incident, Need to have wood on ramps and stairs replaced from Portables. Wood is splintering and falling apart.								
Lisa Alarcon										
146289					1/15/2016		95		\$0.00	
Medium	Work In Progress	Front Office-Gulf			1/15/2016 12:05:14 PM					
Flores, Pete		Need 6 keys for New Gulf Cart. Approved per Mrs. Quinonez. Should you need additional information please contact Connie Avalos. Thank you								
Hilda Adler										
Count: 67 Work Orders		Avg. Age of WO's 71			Total for Gadsden MS			0.5	\$12.50	

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
149723					3/16/2016		34		\$0.00
Medium	Work In Progress				3/16/2016 9:42:03 AM				
Vallejo, Albert		Order new marquee for La Union Elementary							
Vicente Sanchez									
150201					3/30/2016		20		\$0.00
Medium	Work In Progress				3/30/2016 3:25:46 PM				
Villalobos, Jose		need repair - john deer mower la 106 loud noise drive belt pulley and blades need sharpening							
Patricio Aguilar									
151076					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:34 AM				
Aguilar, Patricio		Monthly - La Union ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
150634					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:53 AM				
Aguilar, Patricio		Monthly - La Union ES Monthly FE Inpsection - Refer to PMs schedule details.							
Margret Villalobos									
150514					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:26 AM				
Aguilar, Patricio		Monthly - La Union ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
145319					1/3/2016	2/3/2016	107		\$0.00
Medium	Work In Progress				1/3/2016 12:43:27 AM				
Aguilar, Patricio		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
151061					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:23 AM				
Ramos, Rudy		Monthly - QRTL BLDG INSP REPORT (LU) - Refer to PMs schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
150591					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:21 AM				
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
150592					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:22 AM				
Aguilar, Patricio		Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
148357					2/24/2016		55		\$0.00
Medium	Work In Progress				2/24/2016 3:17:13 PM				
Aguilar, Patricio		wo to myself - replace light bulbs new wing hall way.							
Patricio Aguilar									
151285					4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 8:54:24 AM				
Villalobos, David		gas smell in mechanical room by the kitchen. gas line having leaks - thanks for the help							
Patricio Aguilar									
151458					4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 2:23:55 PM				
Villalobos, David		the drain line for r 207 and 209 rest room is clogged will be needing the snake - thank you for the help							
Patricio Aguilar									
151459					4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 2:30:04 PM				
Villalobos, David		need to replace restroom sink faucets for r207 and 209 - replace class room sink faucets r207 and 209 - thank you for all the help							
Patricio Aguilar									
150927					4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 2:53:17 PM				
Ontiveros, Guadalupe		need to remove a tree stump and some cemented poles for the new marquee will need the backhoe, - thank you you for the help							
Patricio Aguilar									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
146153					1/13/2016		97		\$0.00
Medium	Work In Progress				1/13/2016 2:56:39 PM				
Aguilar, Patricio		wo to myself - need to replace toilet wax gasket - floor tiles rest room kitchen							
Patricio Aguilar									
143854					11/19/2015		152		\$0.00
Medium	Work In Progress				11/19/2015 2:49:02 PM				
Castillo, Carlos		emergency light fixer needing ballast r310							
Patricio Aguilar									
149396					3/10/2016		40		\$0.00
Medium	Work In Progress				3/10/2016 12:23:09 PM				
Castillo, Carlos		can a fluorescent emergency light fixture be made into just a fluorescent light fixture? new wing hall way 2 fixtures							
Patricio Aguilar									
151376	Annex Building				4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 12:25:42 PM				
Ambriz, Jose		Need to check room 209 trane split system not cooling as per Alfredo Holguin.							
Jose Ambriz									
Count: 18 Work Orders			Avg. Age of WO's	34		Total for La Union ES	0		\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

150111 3/29/2016 21 \$0.00

Medium Work In Progress 3/29/2016 1:15:25 PM

Pacheco, Hector Need 8 Window Blinds. Sizes are 35 x 48

Hector Pacheco

151361 Main Building Office 4/14/2016 5 \$0.00

Medium Work In Progress 4/14/2016 9:19:33 AM

Solis, Lorenzo A/C not working in main office.

Hector Pacheco

139345 9/4/2015 228 \$0.00

Medium Work In Progress All around the 9/4/2015 9:31:04 AM

Pacheco, Hector Repaint door frames in all entrance doors and office doors.

Angie Flores

151309 Main Building Office 4/13/2016 6 \$0.00

Medium Work In Progress 4/13/2016 3:20:01 PM

Chavez, Santos Need assistance with the electrical on a A/C no power to switch breakers ok.

Hector Pacheco

148153 Main Building Roof 2/22/2016 57 \$0.00

Medium Work In Progress 2/22/2016 2:55:29 PM

Chavez, Santos need to check the contactor for the a/c on east side of cafeteria

Hector Pacheco

148155 Roof 2/22/2016 57 \$0.00

Medium Work In Progress 2/22/2016 2:57:32 PM

Chavez, Santos need to check the contactor on the west of cafeteria

Hector Pacheco

150271 Main Building Exterior 3/31/2016 19 \$0.00

Medium Work In Progress 3/31/2016 7:56:24 AM

Chavez, Santos Need assistance to replace ballast under porch at main entrance.

Hector Pacheco

148922 Cafeteria 3/4/2016 46 \$0.00

Medium Work In Progress 3/4/2016 10:46:12 AM

Chavez, Santos door bell ringer not loud enough to hear 3/4/16 - route to electrician asp Alfredo

please see manager

Cora Ramirez

4/19/2016 12:10:25 PM

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

151291	Main Building	Library			4/13/2016		6		\$0.00
--------	---------------	---------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/13/2016 10:19:00 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Chavez, Santos
Need assistance to change out ballast in Library area do to poor lighting.

Hector Pacheco

150445		Classroom			4/1/2016		18		\$0.00
--------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/1/2016 3:56:19 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Chavez, Santos
Need assistance to change out ballast .

Hector Pacheco

150448		Classroom			4/1/2016		18		\$0.00
--------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/1/2016 3:58:46 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Chavez, Santos
Need assistance to change out ballast room #210

Hector Pacheco

148506	Main Building	Exterior			2/26/2016		53		\$0.00
--------	---------------	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/26/2016 9:45:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo
In need to replace door lock on exterior door main west side entrance.

Hector Pacheco

151505					4/18/2016		1		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/18/2016 8:33:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo
The lock at the gate will not open since Friday in the afternoon.

David Soriano

151506					4/18/2016		1		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/18/2016 8:34:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo
Faculty restroom (Men's Room) will not open.

David Soriano

148002		Cafeteria			2/18/2016		61		\$0.00
--------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/18/2016 3:44:35 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe
3rd and 4th grade wing girls bathroom I have 4 leaking flush valves and 4 toilets not anchored to the floor.

Hector Pacheco

148203	Main Building	Mechanical			2/23/2016		56		\$0.00
--------	---------------	------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/23/2016 8:49:14 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe
Boiler room 3/4 back flow preventer is dripping from diaphragm.

Hector Pacheco

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
148767	Main Building	Athletic Field				3/2/2016	48		\$0.00
Medium	Work In Progress				3/2/2016 8:50:43 AM				
Ontiveros, Joe		Need assistance to repair out side water fountains per request by assistant principal Mr Smith.							
Hector Pacheco									
147198	Main Building	Auditorium				2/1/2016	78		\$0.00
Medium	Work In Progress				2/1/2016 3:21:13 PM				
Ontiveros, Joe		In need to remove and replace water fountain in cafeteria. I found a new fountain in a morgan to get installed.							
Hector Pacheco									
143944	Main Building	Restroom				11/20/2015	151		\$0.00
Medium	Work In Progress				11/20/2015 3:37:51 PM				
Ontiveros, Joe		Need assistance replacing flush valve in boys rest room across teachers lounge.							
Hector Pacheco									
147839		Restroom				2/11/2016	68		\$0.00
Medium	Work In Progress				2/11/2016 3:49:00 PM				
Ontiveros, Joe		5th 6th grade wing boy restroom 2 leaking flush valves.							
Hector Pacheco									
147874	Main Building	Restroom				2/12/2016	67		\$0.00
Medium	Work In Progress				2/12/2016 3:34:35 PM				
Ontiveros, Joe		3rd and 4th grade wing 2 urinal flush valve leaking, toilet not anchored to floor flush valve leaking.							
Hector Pacheco									
140150	Main Building	Restroom (Girls)				9/17/2015	215		\$0.00
Medium	Work In Progress				9/17/2015 11:52:44 AM				
Ontiveros, Joe		Can you please come and fix the drainer from the girl restroom from the front of the teachers lunch room its clogged up thank you.							
Alfredo Ambriz									
147624	Main Building	Restroom (Girls)				2/9/2016	70		\$0.00
Medium	Work In Progress				2/9/2016 7:58:33 AM				
Ontiveros, Joe		Toilet not fastened to floor, leaking flush valve at joints. Tried Teflon tape no success.							
Hector Pacheco									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
147822		Restroom (Girls)			2/11/2016		68		\$0.00
Medium	Work In Progress				2/11/2016 3:44:32 PM				
Ontiveros, Joe	toilet needs to be anchored to floor. 1 flush valve not working other leaking.tried trouble shooting.								
Hector Pacheco									
147412	Main Building	Restroom			2/4/2016		75		\$0.00
Medium	Work In Progress				2/4/2016 12:46:51 PM				
Ontiveros, Joe	Need assistance to repair toilet flush valve wont stop flushing and leaks on all joints. Man teacher restroom 3rd and 4th grade wing.								
Hector Pacheco									
144165	Main Building	Restroom			12/2/2015		139		\$0.00
Medium	Work In Progress				12/2/2015 7:42:04 AM				
Ontiveros, Joe	Need to replace gaskets on flush valve teachers rest room across teachers lounge.								
Hector Pacheco									
150272					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 8:00:47 AM				
Flores, Pete	Need assistance to repair flat tire on ride on lawn mower rite side.								
Hector Pacheco									
143932		Classroom			11/20/2015		151		\$0.00
Medium	Work In Progress	Music Portable			11/20/2015 2:26:44 PM				
Estrada, Jesus	CARPET IS TORN CREATING A HAZARD FOR CHILDREN								
Angie Flores									
141376					10/9/2015		193		\$0.00
Medium	Work In Progress	Kitchen			10/9/2015 2:43:55 PM				
Orozco, Daniel	Replace drain grill in front of tilt skillet. Per ergonomic inspection the drain grill should be replaced with an appropriate style. Please call Cynthia with any questions 882-6949.								
Cynthia Maes									
151375		Classroom			4/14/2016		5		\$0.00
Medium	Work In Progress	204			4/14/2016 12:14:17 PM				
Pacheco, Hector	Please remove TV and TV Stand from classroom.								
Angie Flores									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
150119		Portables			3/29/2016		21		\$0.00
Medium	Work In Progress	IEP Portable			3/29/2016 3:23:14 PM				
Pacheco, Hector									
Secure security bars on IEP Room , replace window blinds in IEP Room									
Angie Flores									
144250	Main Building	Athletic Field			12/3/2015		138		\$0.00
Medium	Work In Progress				12/3/2015 8:37:43 AM				
Pacheco, Hector									
Need to extend sprinkler valve boxes 6 inches higher.									
Hector Pacheco									
147462	Main Building				2/5/2016		74		\$0.00
Medium	Work In Progress				2/5/2016 7:32:11 AM				
Pacheco, Hector									
Need to install Video Surveillance signs.									
Hector Pacheco									
151054					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:18 AM				
Soriano, David									
Monthly - QRTLY BLDG INSP REPORT (LL) - Refer to PMs schedule details.									
Jimmy Carbajal									
151587	Main Building	Athletic Field			4/19/2016		0		\$0.00
Medium	Work In Progress				4/19/2016 8:31:24 AM				
Ontiveros, Guadalupe									
Need assistance to remove and replace diaphragm on 6 of the sprinkler valves do to not working properly grass is still dry.									
Hector Pacheco									
150702		Athletic Field			4/4/2016		15		\$0.00
Medium	Work In Progress				4/4/2016 3:50:02 PM				
Pacheco, Hector									
Need to remove and replace sprinklers trouble shoot timer.									
Hector Pacheco									
150457					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:43 AM				
Pacheco, Hector									
Yearly - Loma Linda ES A13(AC Wall Mount)(Yearly) - Refer to PMs schedule details.									
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
150494					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:11 AM				
Pacheco, Hector		Monthly - Loma Linda ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
150506					4/3/2016	4/24/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:20 AM				
Vallejo, Albert		Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PMs schedule details.							
Margret Villalobos									
150621					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:43 AM				
Pacheco, Hector		Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PMs schedule details.							
Margret Villalobos									
148979					3/6/2016		44		\$0.00
Medium	Work In Progress				3/6/2016 12:40:36 AM				
Pacheco, Hector		Yearly - Loma Linda ES A10 (Heat Pumps)(Yearly) - Refer to PMs schedule details.							
Margret Villalobos									
150244					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:46:02 AM				
Pacheco, Hector		Monthly - Loma Linda ES A16(Fan Exh.)(S. Annual) - Refer to PMs schedule details.							
Margret Villalobos									
150544					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:48 AM				
Pacheco, Hector		Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PMs schedule details.							
Margret Villalobos									
150545					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:49 AM				
Pacheco, Hector		Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PMs schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Loma Linda ES										
150546					4/3/2016		16		\$0.00	
Medium	Work In Progress				4/3/2016 12:43:50 AM					
Pacheco, Hector		Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos										
151069					4/10/2016	4/26/2016	9		\$0.00	
Medium	Work In Progress				4/10/2016 12:32:29 AM					
Pacheco, Hector		Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos										
145978	Main Building	Classroom			1/11/2016		99		\$0.00	
Medium	Work In Progress	107			1/11/2016 9:46:41 AM					
Pacheco, Hector		Mr. Pacheco please go to San Miguel Elem to pick up a Student Corral and place it in room 107 with Ms. Richhart, as per IEP we need Student Corral ASAP								
Angie Flores										
138748	Main Building	Classroom			8/26/2015		237		\$0.00	
Medium	Work In Progress				8/26/2015 7:46:19 AM					
Estrada, Jesus		In classroom 222 the plastic the edge of the carpet part of it came of its needs to be replaced.								
Alfredo Ambriz										
151360					4/14/2016		5		\$0.00	
Medium	Work In Progress				4/14/2016 8:55:31 AM					
Villalobos, Jose		wet-n-dry#4419 doesn't pick up water								
Jimmy Carbajal										
Count: 49 Work Orders		Avg. Age of WO's 57		Total for Loma Linda ES			0	\$0.00		

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
151198					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 12:13:02 PM				
Villalobos, Jose	VACUUM #1100001168, BACK WHEELS DAMAGED, AND BOTTOM CORD HOLDER MISSING.								
Mario Valles									
151197					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 12:11:03 PM				
Herrera, Marin	BURNISHER #12049, PROPANE TANK NEEDS TO BE REFILLED.								
Mario Valles									
142965	Main Building				11/3/2015		168		\$0.00
Medium	Work In Progress	Main Office			11/3/2015 1:55:34 PM				
Estrada, Jesus	Main Office need carpet repair 2 seam repair. Thank you, Sandy								
Sandra Mora									
151453					4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 12:54:30 PM				
Villalobos, Jose	VACUUM #008000000089. VACUUM WILL NOT POWER ON, AND HAS DAMAGE TO CORD. ALSO NEEDS BELT AND BEATER BAR.								
Mario Valles									
136170	2003 Classroom	Hallway/Corridor			7/20/2015		274		\$0.00
Medium	Work In Progress	E Wing			7/20/2015 3:59:34 PM				
Marquez, Gerardo	Need staff name plaque's for the following staff V. Munoz, L. Baldauf, C. Zuloaga, G. Moreno, A. Alvarado, M. Martinez. Thank you, Sandy								
Sandra Mora									
150612					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:36 AM				
Apodaca, Mario	Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
151062					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:24 AM				
Valles, Mario	Monthly - QRTLY BLDG INSP REPORT (MQ) - Refer to PM schedule details.								
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
145320					1/3/2016	2/3/2016	107		\$0.00
Medium	Work In Progress				1/3/2016 12:43:28 AM				
Ramirez, Joe		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
150251					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:46:07 AM				
Ramirez, Joe		Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.							
Margret Villalobos									
148568					2/29/2016	3/31/2016	50		\$0.00
Medium	Work In Progress				2/29/2016 12:58:17 AM				
Ramirez, Joe		Yearly - Mesquite ES C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
151586					4/19/2016		0		\$0.00
Medium	Work In Progress				4/19/2016 8:29:34 AM				
Appelzoller, Fred		floor drains in the bathrooms are backing up need fred to come unclog the drains							
Joe Ramirez									
148434					2/25/2016		54		\$0.00
Medium	Work In Progress				2/25/2016 2:37:18 PM				
Ramirez, Joe		need to replace several hunter sprinklers.							
Joe Ramirez									
145770	Main Building	Storage			1/7/2016		103		\$0.00
Medium	Work In Progress	Main Office			1/7/2016 8:49:28 AM				
Chavez, Santos		As per Joe Ramirez/Bldg. Mech. we are needing electric power to power a new refrigerator may need a electric power drop installed. Thank you							
Sandra Mora									
138289	Main Building	Cafeteria			8/18/2015		245		\$0.00
Medium	Work In Progress	Cafeteria			8/18/2015 4:08:23 PM				
Chavez, Santos		Requesting, suggest power surge protector ASAP.							
Sandra Mora									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
140233	Pump House	Pump House			9/18/2015		214		\$0.00
Medium	Work In Progress				9/18/2015 2:52:32 PM				
Chavez, Santos		irrigation control box need to identify and number all wires to the control system to well and air compressor							
Mario Apodaca									
149719	Main Building				3/16/2016		34		\$0.00
Medium	Work In Progress	Main hallway			3/16/2016 8:51:17 AM				
Chavez, Santos		As per Ms. Angela Silvaggio/Principal, she is requesting that our copy machine be moved to hallway, we need 2 electrical drops one for each copy machine, asap. Thank you, Sandy							
Sandra Mora									
139560					9/8/2015		224		\$0.00
Medium	Work In Progress				9/8/2015 10:14:50 AM				
Chavez, Santos		we have 4 parking/security lights that are not working							
Joe Ramirez									
138478	Main Building				8/21/2015		242		\$0.00
Medium	Work In Progress	Cafeteria			8/21/2015 7:53:48 AM				
Chavez, Santos		outlet is loose in cafeteria.							
Sandra Mora									
146579					1/22/2016		88		\$0.00
Medium	Work In Progress				1/22/2016 9:16:51 AM				
Chavez, Santos		elect. wall heater in the teachers bathroom (north end) is not working.							
Joe Ramirez									
Count: 19 Work Orders		Avg. Age of WO's 98		Total for Mesquite ES		0		\$0.00	

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		North Valley ES							
151436					4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 7:46:51 AM				
Solis, Lorenzo		erv unit(rooftop) for organ trail is not running -will not stay on -starts and cuts out in less than 10 seconds.plz							
Danny Vega									
148927					3/4/2016		46		\$0.00
Medium	Work In Progress				3/4/2016 11:24:39 AM				
Chavez, Santos		emergency ballast out rm 307-212-302							
Danny Vega									
142953		Athletic Field			11/3/2015		168		\$0.00
Medium	Work In Progress				11/3/2015 10:31:01 AM				
Ontiveros, Guadalupe		Need Soccer Goal Nets-(2)-20ft L x 8ft H x 6ft D							
Gloria Reyes									
143845		Hallway/Corridor			11/19/2015		152		\$0.00
Medium	Work In Progress				11/19/2015 1:28:39 PM				
Chavez, Santos		We need 3 more electrical outlets installed for our copiers by our office area. Per the service tech need to make sure there is enough amperage per outlet to support copier. Min. of 25 amps.							
Gloria Reyes									
151067					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:28 AM				
Vega, Danny		Monthly - North Valley ES Playground Inspection - Refer to PM schedule details.							
Margret Villalobos									
150620					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:42 AM				
Vega, Danny		Monthly - North Valley ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
148579					2/29/2016		50		\$0.00
Medium	Work In Progress				2/29/2016 12:58:26 AM				
Vallejo, Albert		Yearly - North Valley ES - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
150511					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:23 AM				
Vallejo, Albert		Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
150890					4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 12:32:12 AM				
Vega, Danny		Daily - North Valley ES - Fire Pump (Biweekly) - Refer to PM schedule details.							
Margret Villalobos									
151044					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:10 AM				
Rodriguez, Ivan		Monthly - QRTLY BLDG INSP REPORT (NV) - Refer to PM schedule details.							
Margret Villalobos									
150850					4/6/2016		13		\$0.00
Medium	Work In Progress				4/6/2016 3:36:12 PM				
Solis, Lorenzo		RM 102 COMPUTER RM /AC UNIT HAS TO BE RE-SET MANUALLY DAILY.PLEASE CK							
Danny Vega									
141341					10/9/2015		193		\$0.00
Medium	Work In Progress				10/9/2015 7:25:07 AM				
Chavez, Santos		emergency ballast out in hallway(pecan valley) by rm 201-205-211-rio grand wing by rm 305 -402-							
Danny Vega									
141189					10/7/2015		195		\$0.00
Medium	Work In Progress				10/7/2015 8:35:13 AM				
Chavez, Santos		exterior bldg. lighting have 14 (dome type) lamps that are out thru out bldg please ck to order bulbs if not in stock							
Danny Vega									
146284					1/15/2016		95		\$0.00
Medium	Work In Progress				1/15/2016 9:56:42 AM				
Chavez, Santos		need to replace exit signs in 200- wing hallway 204, 206, 207, 208, and 209							
Danny Miranda									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
150048					3/23/2016		27		\$0.00
Medium	Work In Progress				3/23/2016 12:14:54 PM				
Chavez, Santos		emergency lamp ballast are out in rm 306-310-302							
Danny Vega									
150103					3/29/2016		21		\$0.00
Medium	Work In Progress				3/29/2016 10:37:20 AM				
Chavez, Santos		BAD BALLAST IN MECHANNICAL RMS BY CLASSRMS -101-203-206-207-301-							
Danny Vega									
149411					3/10/2016		40		\$0.00
Medium	Work In Progress				3/10/2016 3:28:06 PM				
Ontiveros, Guadalupe		need kabota and small boxscaper to level off court yards at nve and lm pre-k							
Danny Vega									
150050					3/23/2016		27		\$0.00
Medium	Work In Progress				3/23/2016 12:22:41 PM				
Ontiveros, Guadalupe		need kabota tractor to clean -up ponding areas and build borders up							
Danny Vega									
150047					3/23/2016		27		\$0.00
Medium	Work In Progress				3/23/2016 12:13:08 PM				
Gonzalez, Salvador		soccer goal top rail needs to be welded							
Danny Vega									
151526					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 2:32:23 PM				
Herrera, Marin		diesel fuel mower#422 and 2 stroke#616 weed eater and blowers							
Danny Vega									
Count: 20 Work Orders			Avg. Age of WO's 56			Total for North Valley ES	0		\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

151525 4/18/2016 1 \$0.00

Medium Work In Progress 4/18/2016 2:29:23 PM

Herrera, Marin need gas fuel mower#418-#612 and 2 stroke (blower,weedeater)

Danny Vega

150926 Main Building Classroom 4/7/2016 12 \$0.00

Medium Work In Progress 103 4/7/2016 2:50:11 PM

Vega, Danny The teacher in Room 103 is requesting to move the cabinets in her room.

Concepcion Montalvo

140486 Main Building Athletic Field 9/23/2015 209 \$0.00

Medium Work In Progress outside 9/23/2015 1:57:54 PM

Ontiveros, Guadalupe There is a new canopy in our cafeteria that needs to be set up where our sandbox is for the students. They do not have appropriate shade to be where the sand is located and they are digging holes next to the building. 9/29/15 - Asp Albert, route to Grounds

Concepcion Montalvo

150657 4/4/2016 15 \$0.00

Medium Work In Progress 4/4/2016 10:10:39 AM

Ontiveros, Guadalupe need for somebody to operate a cherry picker to cut down some branches from a tree, the branches are brittle and are a safety hazard as per our principal Angelic Ramos's request

Brian Pacheco

151040 4/10/2016 4/26/2016 9 \$0.00

Medium Work In Progress 4/10/2016 12:32:07 AM

Pacheco, Brian Monthly - QRTLTY BLDG INSP REPORT (LM/PRE-K) - Refer to PM schedule details.

Margret Villalobos

150493 4/3/2016 4/11/2016 16 \$0.00

Medium Work In Progress 4/3/2016 12:43:10 AM

Vega, Danny Monthly - La Mesa ES Roof Inspection - Refer to PM schedule details.

Margret Villalobos

151068 4/10/2016 4/26/2016 9 \$0.00

Medium Work In Progress 4/10/2016 12:32:28 AM

Vega, Danny Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.

Margret Villalobos

4/19/2016 12:10:25 PM

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Northern On-Track Pre-K (LM)									
150607					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:33 AM				
Apodaca, Mario	Monthly - Northern Pre-K -Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
150878					4/6/2016		13		\$0.00
Medium	Work In Progress				4/6/2016 3:58:37 PM				
Ontiveros, Joe	4-6-16 18350.8 18367.2 .5 ck E-Mail-Material LLES 2-147624-p GES 2-150245-p GES 2-Water grass Trees BES 1-147262-p .5- Enter Log 1 Total HR								
Joe Ontiveros									
Count: 9 Work Orders		Avg. Age of WO's 33			Total for Northern On-Track Pre-K (LM)			0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
146584					1/22/2016		88		\$0.00
Medium	Work In Progress				1/22/2016 10:44:56 AM				
Chavez, Santos		Install exterior shop lighting.							
Albert Vallejo									
146586					1/22/2016		88		\$0.00
Medium	Work In Progress				1/22/2016 10:48:05 AM				
Chavez, Santos		Install interior shop lights.							
Albert Vallejo									
149213					3/8/2016		42		\$0.00
Medium	Work In Progress				3/8/2016 7:51:49 AM				
Chavez, Santos		Need to order 1/2" EMT to replenish stock							
Santos Chavez									
147811	Motor Vehicle				2/11/2016		68		\$0.00
Medium	Work In Progress				2/11/2016 3:17:28 PM				
Chavez, Santos		lights on pole in the middle of vehicles in front of Auto Shop are not working reported by (R. Tapia)							
Maria Ruiz									
142138	Motor Vehicle				10/22/2015		180		\$0.00
Medium	Work In Progress				10/22/2015 8:49:29 AM				
Chavez, Santos		Install outlets as needed in the new welding shop. (Please see Sal and Jimmy)							
Albert Vallejo									
151560	Motor Vehicle				4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 3:54:04 PM				
Chavez, Santos		Auto Shop - Demo and roughin at new construction area.							
Albert Vallejo									
149323					3/9/2016		41		\$0.00
Medium	Work In Progress				3/9/2016 11:35:33 AM				
Castillo, Carlos		Need to order drill bits and replacement tool pouch.							
Carlos Castillo									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
149707					3/16/2016		34		\$0.00
Medium	Work In Progress				3/16/2016 7:39:03 AM				
Herrera, Mario	Door stopper on Construction office door needs to be fixed. Rubber part is coming off and not allowing the door to be held open as needed. For questions please see Dominique in the Construction office								
Dominique Esparza									
148508	Main Warehouse				2/26/2016		53		\$0.00
Medium	Work In Progress				2/26/2016 10:29:43 AM				
Marquez, Gerardo	please switch lock to a cls room lock. Still having issues with lock.								
Lisa Sanchez									
141935					10/19/2015		183		\$0.00
Medium	Work In Progress				10/19/2015 2:49:46 PM				
Marquez, Gerardo	AS PER MR. CHAVEZ, ALL NORTHERN KITCHENS NEED TO BE REKEYED.								
Maritza Gonzalez									
146121					1/12/2016		98		\$0.00
Medium	Work In Progress				1/12/2016 11:18:09 PM				
Marquez, Gerardo	1/12/16 3167-3217 .5-CHECK E-MAIL/PREP MATRL.4-GMS. 145085 C. 2-CH. H.S. 145697 C. 1-CH. H. S. 145969 WP. .5-LOG OUT.								
Gerardo Marquez									
151284					4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 8:53:16 AM				
Lara, Ralph	NEED ORDER PEN LUBE AEROSOL SPRAY CANS FOR DIS WIDE								
Ralph Lara									
151288					4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 8:59:55 AM				
Lara, Ralph	NEED TO ORDER EXIT DEVICES, FOR R.S.E.								
Ralph Lara									
151282					4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 8:41:31 AM				
Lara, Ralph	NEED TO ORDER CLASS RM LOCKSETS FOR DIST WIDE								
Ralph Lara									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
151565	Motor Vehicle				4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 3:55:56 PM				
Ontiveros, Joe		Auto Shop - Demo and roughin at new construction area.							
Albert Vallejo									
144789					12/10/2015		131		\$0.00
Medium	Work In Progress				12/10/2015 7:46:12 AM				
Ontiveros, Joe		Welding Shop - supplygas for two heater units							
Albert Vallejo									
149721					3/16/2016		34		\$0.00
Medium	Work In Progress				3/16/2016 9:04:45 AM				
Miranda, Danny		NEED TO HAVE DRYWALL REPAIRED. TAPED, TEXTURED AND PAINTED. LOCKSMITH OFFICE CURRENTLY HAS MANY GAPS AND HOLES IN WALLS AND AREAS AROUND THE WINDOW ARE MISSING DRYWALL ENTIRELY.							
Gerardo Marquez									
144738	Maintenance	Pump House			12/9/2015		132		\$0.00
Medium	Work In Progress				12/9/2015 2:43:24 PM				
Apodaca, Mario		wastewater wet toxicity testing need to grab and sent out to water lab at sage environment Oklahoma city							
Mario Apodaca									
148635					2/29/2016		50		\$0.00
Medium	Work In Progress				2/29/2016 3:00:10 PM				
Apodaca, Mario		need too order air compressor for the irrigation water system pressure tanks							
Mario Apodaca									
138657					8/25/2015		238		\$0.00
Medium	Work In Progress				8/25/2015 8:53:15 AM				
Apodaca, Mario		stainless steel fittings for the new UV system at the wastewater plant at ppd also to be installed							
Mario Apodaca									
150328					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 1:35:50 PM				
Apodaca, Mario		need to order spare parts for the UV UNIT							
Mario Apodaca									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
150765					4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 2:53:18 PM				
Apodaca, Mario		domestic water filters for district-wide use reorder							
Mario Apodaca									
137531		Lift Station			8/7/2015		256		\$0.00
Medium	Work In Progress				8/7/2015 3:13:14 PM				
Gonzalez, Salvador		the uv system shaded area need too put more sheet metal to cover the uv system							
Mario Apodaca									
147550					2/8/2016		71		\$0.00
Medium	Work In Progress				2/8/2016 7:39:23 AM				
Gonzalez, Salvador		2-8-16 I Need fabricate racks for shop							
Salvador Gonzalez									
149802					3/17/2016		33		\$0.00
Medium	Work In Progress				3/17/2016 10:33:07 AM				
Gonzalez, Salvador		3-17-16 Need to cover shop wall with sheet metal							
Salvador Gonzalez									
143609					11/16/2015		155		\$0.00
Medium	Work In Progress				11/16/2015 7:43:51 AM				
Gonzalez, Salvador		Sal can you please construct a pipe rack with a shade at the Morgan building at the GAC. Thanks							
David Villalobos									
141694					10/14/2015		188		\$0.00
Medium	Work In Progress				10/14/2015 2:45:35 PM				
Lara, Ralph		Install a peephole at each South District school kitchen exit door. Please start with STMS per ergonomic evaluation.							
Cynthia Maes									
135167	Motor Vehicle				7/1/2015		293		\$0.00
Medium	Work In Progress				7/1/2015 9:19:42 AM				
Marquez, Gerardo		NEED TO INSTALL DOOR AT METAL BLDG. ON WESTSIDE OF AUTOSHOP. THIS WILL BE THE SMALL DR. NEXT TO ROLL UP DR.							
Gerardo Marquez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
140460					9/23/2015		209		\$0.00
Medium	Work In Progress				9/23/2015 8:36:42 AM				
Marquez, Gerardo		DOOR FRAMES RUSTED. PLEASE REPLACE AT MAINT. WHS. AND LOCKSMITH ENTRANCE. THANK YOU							
Ruben Ronquillo									
141695					10/14/2015		188		\$0.00
Medium	Work In Progress				10/14/2015 2:47:58 PM				
Marquez, Gerardo		Install a peephole at each North District school kitchen exit door. Please start with LLE per ergonomic evaluation.							
Cynthia Maes									
148835					3/3/2016		47		\$0.00
Medium	Work In Progress				3/3/2016 8:12:27 AM				
Marquez, Gerardo		NEED TO HAVE FRONT DRIVERS SIDE TIRE FIXED. (FLAT)							
Gerardo Marquez									
150393	Motor Vehicle				4/1/2016		18		\$0.00
Medium	Work In Progress	1050 tractor			4/1/2016 9:10:07 AM				
Flores, Pete		exhaust manifold leaking fumes, and fuel filter housing leaking diesel fuel. please check and advise.							
Pete Flores									
151268	Motor Vehicle				4/13/2016		6		\$0.00
Medium	Work In Progress	vehicle#119			4/13/2016 7:56:39 AM				
Flores, Pete		transmission slipping severely please check and advise.							
Pete Flores									
151298	Motor Vehicle				4/13/2016		6		\$0.00
Medium	Work In Progress	vehicle #06			4/13/2016 12:45:03 PM				
Flores, Pete		check engine light on & cooling fan not working properly							
Pete Flores									
150179	Motor Vehicle				3/30/2016		20		\$0.00
Medium	Work In Progress	equip#0507-			3/30/2016 11:05:12 AM				
Flores, Pete		please check cause of hydraulic oil leak							
Pete Flores									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
150188	Motor Vehicle				3/30/2016		20		\$0.00
Medium	Work In Progress	VEHICLE#158			3/30/2016 2:05:12 PM				
Flores, Pete		passenger side window regulator needs replacing. Please check and advise							
Pete Flores									
150647	Motor Vehicle				4/4/2016		15		\$0.00
Medium	Work In Progress	Truck 170			4/4/2016 8:06:16 AM				
Flores, Pete		Need transmission module for truck 170 and install two new tires.							
Fred Appelzoller									
146427	Motor Vehicle				1/20/2016		90		\$0.00
Medium	Work In Progress	vehicle#163			1/20/2016 9:35:52 AM				
Flores, Pete		please check for any scheduled maintenance							
Pete Flores									
149717	Motor Vehicle				3/16/2016		34		\$0.00
Medium	Work In Progress	vehicle #136			3/16/2016 8:42:23 AM				
Flores, Pete		vehicle overheating, please check cause and advise on repairs needed							
Pete Flores									
149718	Motor Vehicle				3/16/2016		34		\$0.00
Medium	Work In Progress	vehicle#185			3/16/2016 8:44:33 AM				
Flores, Pete		please replace front and rear brake pads. pads have exceeded wear limits							
Pete Flores									
149794	Motor Vehicle				3/17/2016		33		\$0.00
Medium	Work In Progress				3/17/2016 8:30:04 AM				
Ronquillo, Ruben		ORDER 2EA. GENERAL WIRE MINI-ROOTER POWER FEED. THANK YOU!							
Ruben Ronquillo									
150904	Motor Vehicle				4/7/2016		12		\$0.00
Medium	Work In Progress	vehicle#147			4/7/2016 8:57:25 AM				
Flores, Pete		vehicle lost power and stalled. please check cause and advise.							
Pete Flores									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
150894					4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 7:50:44 AM				
Flores, Pete		Need to have Services truck ck. Ck engine light is on, oil change is needed, Clean exhaust Filter, ck low tire. THANK YOU.							
Joe Ontiveros									
150518					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:29 AM				
Herrera, Mario		Monthly - Physical Plant Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
147905					2/14/2016		65		\$0.00
Medium	Work In Progress				2/14/2016 12:31:13 AM				
Flores, Pete		Yearly - PPD-T-0524 Bobcat PM Service - Refer to PM schedule details.							
Margret Villalobos									
150564					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:03 AM				
Flores, Pete		Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.							
Margret Villalobos									
150261					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:46:14 AM				
Apodaca, Mario		Monthly - PPD/GHS - WW Monthly Sampling - Refer to PM schedule details.							
Margret Villalobos									
149049					3/6/2016		44		\$0.00
Medium	Work In Progress				3/6/2016 12:41:27 AM				
Carrasco, Danny		Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.							
Margret Villalobos									
151305					4/13/2016		6		\$0.00
Medium	Work In Progress	FEDERAL			4/13/2016 2:12:36 PM				
Flores, Pete		PASSENGER SIDE TAILLIGHT IS OUT							
Noemi Duron									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
151112					4/11/2016		8		\$0.00
Medium	Work In Progress	FEDERAL			4/11/2016 1:39:44 PM				
Flores, Pete		LIGHT FOR MOTOR TURNED ON							
Noemi Duron									
151429					4/14/2016		5		\$0.00
Medium	Work In Progress	FEDERAL			4/14/2016 4:12:33 PM				
Flores, Pete		MAKING A STRANGE NOISE-MIGHT BE AC.							
Noemi Duron									
140148	Motor Vehicle				9/17/2015		215		\$0.00
Medium	Work In Progress				9/17/2015 11:31:24 AM				
Flores, Pete		Tune and repair District Warehouse van #11							
Enrique Briones									
148920					3/4/2016		46		\$0.00
Medium	Work In Progress	FEDERAL			3/4/2016 10:37:51 AM				
Flores, Pete		Radio knobs are missing, center arm rest came apart and has ignition problems.							
Noemi Duron									
149822					3/17/2016		33		\$0.00
Medium	Work In Progress	Federal Vehicle			3/17/2016 3:35:55 PM				
Flores, Pete		VEHICLE SHUTS OFF WHILE DRIVING.							
Noemi Duron									
150678					4/4/2016		15		\$0.00
Medium	Work In Progress	Federal Vehicle			4/4/2016 3:36:14 PM				
Flores, Pete		Battery light blinking.							
Noemi Duron									
142608					10/30/2015		172		\$0.00
Medium	Work In Progress				10/30/2015 10:48:14				
Chavez, Santos		light pole in middle of parking lot was not on this morning; light on pole close to street was not on this morning. report from Jose R.							
Maria Ruiz									
147989	Motor Vehicle				2/18/2016		61		\$0.00
Medium	Work In Progress				2/18/2016 2:59:43 PM				
Flores, Pete		vehicle 01 has a cracked windshield reported by D. Brown							
Maria Ruiz									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
147973	Motor Vehicle				2/18/2016		61		\$0.00
Medium	Work In Progress	vehicle#134			2/18/2016 9:03:08 AM				
Flores, Pete		please prepare vehicle for use by grounds dept.							
Pete Flores									
149734	Motor Vehicle				3/16/2016		34		\$0.00
Medium	Work In Progress	vehicle 47 & 48			3/16/2016 2:10:44 PM				
Flores, Pete		have water in front bottom lens							
Maria Ruiz									
138392	Motor Vehicle				8/20/2015		243		\$0.00
Medium	Work In Progress				8/20/2015 8:39:05 AM				
Flores, Pete		ac compressor doesn't work; makes a lot of noise							
Pete Flores									
150991	Motor Vehicle				4/8/2016		11		\$0.00
Medium	Work In Progress				4/8/2016 12:17:17 PM				
Flores, Pete		Replace Cabin Air Filter on SNP Truck#176							
Dino Facio									
151175	Motor Vehicle				4/12/2016		7		\$0.00
Medium	Work In Progress	vehicle 48			4/12/2016 8:52:20 AM				
Flores, Pete		vehicle 48 doesn't start correctly reported by LGuerrero							
Maria Ruiz									
142372	Motor Vehicle				10/27/2015		175		\$0.00
Medium	Work In Progress				10/27/2015 9:10:35 AM				
Flores, Pete		vehicle 47 driver's window wouldn't go up; passenger door doesn't open from inside.							
Maria Ruiz									
151518	Motor Vehicle				4/18/2016		1		\$0.00
Medium	Work In Progress	vehicle 137			4/18/2016 11:33:58 AM				
Flores, Pete		truck needs to be serviced & Lupe is experiencing problems with transmission.							
Guadalupe Ontiveros									
151531	Motor Vehicle				4/18/2016		1		\$0.00
Medium	Work In Progress	vehicle 128			4/18/2016 3:01:30 PM				
Perez, Raul		needs to be serviced for trip to San Antonio, TX							
Maria Ruiz									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
148615	Motor Vehicle				2/29/2016		50		\$0.00
Medium	Work In Progress				2/29/2016 10:10:36 AM				
Ruiz, Maria		vehicle 183 driver side back door was damaged (Ivonne Perez)							
Maria Ruiz									
148837	Motor Vehicle				3/3/2016		47		\$0.00
Medium	Work In Progress				3/3/2016 8:33:04 AM				
,		vehicle 64 has a recall on seat belts, needs to be taken to dealer for service.							
Maria Ruiz									
150837	Work In Progress				4/6/2016		13		\$0.00
Medium	Work In Progress				4/6/2016 1:13:07 PM				
Flores, Pete		SNP VEHICLE 172- DRIVER SIDE WINDOW WILL NOT GO UP.							
Maritza Gonzalez									
150838	Work In Progress				4/6/2016		13		\$0.00
Medium	Work In Progress				4/6/2016 1:18:50 PM				
Flores, Pete		SNP Vehicle#131 has front driver side flat tire and dead battery.							
Dino Facio									
150654	Work In Progress				4/4/2016		15		\$0.00
Medium	Work In Progress	vehicle 163 &			4/4/2016 8:59:13 AM				
Flores, Pete		vehicles 163 & 164 have tire monitor lights on vehicle 164 needs new washer fluid tank							
Maria Ruiz									
151003	Work In Progress	Vehicle #10			4/8/2016		11		\$0.00
Medium	Work In Progress	Vehicle #10			4/8/2016 3:21:25 PM				
Flores, Pete		Vehicle #10 - Need Oil change and check fluids on mail truck also air pressure gauge light is on (will need a vehicle for mail run)							
Enrique Briones									
144568	Motor Vehicle				12/7/2015		134		\$0.00
Medium	Work In Progress				12/7/2015 10:30:14 AM				
Flores, Pete		vehicle 187; check brakes and tire pressure sensor reported by Charlene Bonham							
Maria Ruiz									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
150907	Motor Vehicle				4/7/2016		12		\$0.00
Medium	Work In Progress	auto shop			4/7/2016 9:40:53 AM				
Tobias, Victor please supply hand tools for Victor Tobias -auto shop technician.									
Pete Flores									
148870					3/3/2016		47		\$0.00
Medium	Work In Progress				3/3/2016 3:38:41 PM				
Hernandez, Guillermo Need HVAC equipment: Vacuum pump, manifold gage & charging hoses, CO-2 detector, leak detector, pocket thermometer, refrigeration hole saw kit, high speed drill set, service valve wrench, no loss fitting, extra-long shaft nut driver, knee pads, locking pliers, tubing cutter, Acetylene torch kit, aviator snip left, aviator snip right, 6 ft. fiber glass step ladder, 8 ft. fiber glass step ladder and 24 ft. fiber glass extension ladder.									
Guillermo Hernandez									
150167	Motor Vehicle				3/30/2016		20		\$0.00
Medium	Work In Progress				3/30/2016 8:56:16 AM				
Villalobos, Jose requesting supplies for small engine repair shop									
Jose Villalobos									
150169	Motor Vehicle				3/30/2016		20		\$0.00
Medium	Work In Progress				3/30/2016 9:04:55 AM				
Villalobos, Jose requesting toolbox and tools for small engine repair shop									
Jose Villalobos									
150170	Motor Vehicle				3/30/2016		20		\$0.00
Medium	Work In Progress				3/30/2016 9:06:56 AM				
Villalobos, Jose requesting equipment lift for repairing grounds equipment									
Jose Villalobos									
139632		Office			9/9/2015		223		\$0.00
Medium	Work In Progress				9/9/2015 9:35:50 AM				
Marquez, Gerardo Please install doors and windows, when they arrive from APCO.									
Danny Miranda									
149322		Electrical Room			3/9/2016		41		\$0.00
Medium	Work In Progress				3/9/2016 11:34:10 AM				
Castillo, Carlos Need to order drill bits and replacement tool pouch.									
Carlos Castillo									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
150813	Maintenance	Electrical Room			4/6/2016		13		\$0.00
Medium	Work In Progress				4/6/2016 7:29:14 AM				
Castillo, Carlos		Need to order extra came along for scissor lift transport tie up.							
Carlos Castillo									
150984	Motor Vehicle				4/8/2016		11		\$0.00
Medium	Work In Progress				4/8/2016 10:22:06 AM				
Carrasco, Danny		2 signs for fuel station							
Maria Ruiz									
149861					3/18/2016		32		\$0.00
Medium	Work In Progress				3/18/2016 7:47:43 AM				
Vallejo, Albert		Create pad for lift south of auto shop.							
Albert Vallejo									
145632					1/5/2016		105		\$0.00
Medium	Work In Progress				1/5/2016 2:49:25 PM				
Vallejo, Albert		District Wide - Make repairs to fire sprinklers to correct deficiencies found at annual inspection.							
Albert Vallejo									
149883					3/18/2016		32		\$0.00
Medium	Work In Progress				3/18/2016 3:29:50 PM				
Vallejo, Albert		Create office / lounge area in shop with storage mezzanine above.							
Albert Vallejo									
151448					4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 11:31:11 AM				
Briones, Enrique		move/organize equipment/salvage items into fenced area to prepare for auction - contact Alfredo for details							
Alfredo Holguin									
138019					8/14/2015		249		\$0.00
Medium	Work In Progress				8/14/2015 8:57:46 AM				
Marquez, Gerardo		PLEASE MEET WITH DR. VENDOR FOR PRICE QUOTE.							
Gerardo Marquez									
150748	Main Warehouse				4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 10:16:01 AM				
Herrera, Mario		Please turn off heaters and turn on swamp coolers.							
Enrique Briones									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
144787					12/10/2015		131		\$0.00
Medium	Work In Progress				12/10/2015 7:44:29 AM				
Solis, Lorenzo		Welding Shop - Install two heaters							
Albert Vallejo									
144788					12/10/2015		131		\$0.00
Medium	Work In Progress				12/10/2015 7:45:06 AM				
Solis, Lorenzo		Welding Shop - Install exhaust fan							
Albert Vallejo									
150701					4/4/2016		15		\$0.00
Medium	Work In Progress				4/4/2016 3:50:01 PM				
Lara, Ralph		4/4/16-68533-68582-MILEAGE .5 3.-R.V.S.E.-WO-150095-P 2.-D.V.E.-WO-150672-P 2.-S.T.H.S.-WO-150671-P .5							
Ralph Lara									
151425					4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 3:58:52 PM				
Gonzalez, Salvador		Need to build cages to store tools for Small engine repair and welding shop.							
Salvador Gonzalez									
150766					4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 3:18:13 PM				
Villalobos, Jose		the custodial gator here at the ppd needs lights							
Jimmy Carbajal									
151395					4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 3:37:14 PM				
Villalobos, Jose		advance all purpose matador #1713591 no power							
Jimmy Carbajal									
151444					4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 10:53:38 AM				
Castillo, Carlos		Please transport lift from the South Side to PPD Warehouse for Plan B.							
Albert Vallejo									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Physical Plant Complex										
151437					4/15/2016		4		\$0.00	
Medium	Work In Progress				4/15/2016 8:01:11 AM					
Castillo, Carlos		Clean, and organize veh.#152								
Carlos Castillo										
150270					3/31/2016		19		\$0.00	
Medium	Work In Progress				3/31/2016 7:53:44 AM					
Solis, Lorenzo		Lorenzo, we need 2 air conditioning (side draft) to be installed on new shop please. Thanks								
Salvador Gonzalez										
150968					4/7/2016		12		\$0.00	
Medium	Work In Progress				4/7/2016 4:17:32 PM					
Carrasco, Danny		scissor lift needed for Plan B to run cable for phone in warehouse. please let me know when available for them to use								
Cora Ramirez										
150152	Motor Vehicle				3/29/2016		21		\$0.00	
Medium	Work In Progress				3/29/2016 3:58:12 PM					
Solis, Lorenzo		Please install exhaust fan in Small Engine Repair Shop.								
Jose Villalobos										
Count: 98 Work Orders			Avg. Age of WO's	61	Total for Physical Plant Complex			0	\$0.00	

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
140231					9/18/2015		214		\$0.00
Medium	Work In Progress			9/18/2015 2:33:41 PM					
Ambriz, Jose	Need Jose A. to check Library A/C unit which is still freeezing over.								
Mario Martinez									
150689					4/4/2016		15		\$0.00
Medium	Work In Progress			4/4/2016 3:43:40 PM					
Martinez, Mario	4/4/2016 .5 hr open up gates, pick up trash, walk through campus and check e-mail.7 hrs work on soccer field leveling top soil. .5 hr pick up, clean up, log in work day and check e-mail.								
Mario Martinez									
151528					4/18/2016		1		\$0.00
Medium	Work In Progress			4/18/2016 2:55:11 PM					
Martinez, Mario	Need to renovate middle wing boys and girls restrooms.								
Mario Martinez									
151182					4/12/2016		7		\$0.00
Medium	Work In Progress			4/12/2016 10:08:56 AM					
Martinez, Mario	Summer project!!! need to install 1800 feet of vinyl baseboard through out entire interior of hallways.								
Mario Martinez									
142531					10/29/2015		173		\$0.00
Medium	Work In Progress			10/29/2015 8:00:00 AM					
Gonzalez, Salvador	Need Sal to fabricate new ramps and stairs for new science portable.								
Mario Martinez									
151075					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress			4/10/2016 12:32:34 AM					
Martinez, Mario	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
150458					4/3/2016		16		\$0.00
Medium	Work In Progress			4/3/2016 12:42:43 AM					
Martinez, Mario	Yearly - Riverside ES A-13 A/C Wall Mount Yearly - Refer to PMs schedule details.								
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
150630					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:50 AM				
Martinez, Mario		Monthly - Riverside ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
150724					4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 7:26:55 AM				
Martinez, Mario		Need to cut tree branches around playground and at morgan building.							
Mario Martinez									
150596					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:25 AM				
Martinez, Mario		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
150597					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:26 AM				
Martinez, Mario		Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
151058					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:21 AM				
Sonora, Miguel		Monthly - QRTLY BLDG INSP REPORT (RS) - Refer to PMschedule details.							
Margret Villalobos									
150501					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:16 AM				
Martinez, Mario		Monthly - Riverside ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
148384					2/24/2016		55		\$0.00
Medium	Work In Progress				2/24/2016 3:45:22 PM				
Martinez, Mario		2/24/2016. Summer project. Need to replace all 6 inch X6 inch broken tiles at all side walks.							
Mario Martinez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
148788					3/2/2016		48		\$0.00
Medium	Work In Progress			3/2/2016 3:12:50 PM					
Ronquillo, Ruben	REPAIR WATER SYSTEM CHECK VALVE								
149989					3/22/2016		28		\$0.00
Medium	Work In Progress			3/22/2016 9:32:37 AM					
Vallejo, Albert	Would like to renovate second and third grade wing boys and girls restrooms. I will take care of plumbing and sub contract the partitions.								
Mario Martinez									
150336					3/31/2016		19		\$0.00
Medium	Work In Progress	North Entrance		3/31/2016 3:01:08 PM					
Lara, Ralph	**2nd Request** North side entrance door needs a new cylinder. (Mr. Flavian)								
Norma Martinez									
150343					3/31/2016		19		\$0.00
Medium	Work In Progress	2nd Grade		3/31/2016 3:41:31 PM					
Lara, Ralph	Double doors in 2nd grade hallway needs a new cylinder. (Mr. Flavian)								
Norma Martinez									
150345					3/31/2016		19		\$0.00
Medium	Work In Progress	Gym		3/31/2016 3:42:41 PM					
Lara, Ralph	**2nd Request** Double doors at the gym need a push bar. (Mr. Flavian)								
Norma Martinez									
146666					1/25/2016		85		\$0.00
Medium	Work In Progress			1/25/2016 12:03:11 PM					
Lara, Ralph	Need to replace portable door at science lab.								
Mario Martinez									
145503					1/4/2016		106		\$0.00
Medium	Work In Progress			1/4/2016 8:04:15 AM					
Gonzalez, Salvador	Need to repair damaged canopy poles at Kinder wing playground.								
Mario Martinez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Riverside ES							
143287					11/9/2015		162		\$0.00
Medium	Work In Progress				11/9/2015 8:03:52 AM				
Gonzalez, Salvador		Need welder Sal to cut and reverse metal benches so that they face in opposite direction.							
Mario Martinez									
149470					3/11/2016		39		\$0.00
Medium	Work In Progress				3/11/2016 10:53:48 AM				
Moncayo, Fernando		OVEN DOWN.SNP MANAGER SANTA N.589.2550							
Maritza Gonzalez									
150397					4/1/2016		18		\$0.00
Medium	Work In Progress				4/1/2016 10:40:15 AM				
Moncayo, Fernando		FREEZER-ICE BUILD AROUND DOOR. SNP MANAGER SANTA N. 589.2550							
Maritza Gonzalez									
143289					11/9/2015		162		\$0.00
Medium	Work In Progress				11/9/2015 8:15:00 AM				
Moncayo, Fernando		ICE IS BUILDING UP IN FREEZER ONCE AGAIN. SNP MANAGER SANTA NAVA 589.2550.							
Maritza Gonzalez									
145799					1/7/2016		103		\$0.00
Medium	Work In Progress				1/7/2016 3:24:58 PM				
Moncayo, Fernando		AS PER ADELES MONITORING REPORT 1.7.16- WALK IN STILL ACCUMILATING ICE. SNP MANAGER SANTA N.589.2550.							
Maritza Gonzalez									
151081					4/11/2016		8		\$0.00
Medium	Work In Progress				4/11/2016 7:37:28 AM				
Moncayo, Fernando		AS PER ONSITE MONITORING REPORT 4.5.16 , FREEZER STILL DROPS DOWN TO -20 DEGREES NEEDS TO BE ADJUSTED. SNP MANAGER SANTA N. 589.2550							
Maritza Gonzalez									
150095	Main Building	Hallway/Corridor			3/29/2016		21		\$0.00
Medium	Work In Progress				3/29/2016 8:33:26 AM				
Lara, Ralph		Rafa la puerta de salida del pasillo que va a el lado de donde esta el portable de pto no esta cerrando la chapa. Gracias.							
Miguel Sonora									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
142151					10/22/2015		180		\$0.00
Medium	Work In Progress				10/22/2015 11:02:29				
Lara, Ralph		Need Rafa L. to re key locks for water cabinet and gates. And to have two padlocks.							
Mario Martinez									
149987					3/22/2016		28	0.5	\$12.50
Medium	Work In Progress				3/22/2016 9:25:06 AM				
Martinez, Mario		Requesting new tile flooring in rooms #39 and #41.				4/15/16 - as per Jimmy, there are only a few tiles that need glue, re-route work order to building mechanic.			
Mario Martinez									
141608					10/13/2015		189		\$0.00
Medium	Work In Progress				10/13/2015 2:22:23 PM				
Castillo, Carlos		Need Carlos C. to work on parking lot lights.							
Mario Martinez									
149980					3/22/2016		28		\$0.00
Medium	Work In Progress				3/22/2016 8:19:58 AM				
Martinez, Mario		Need to paint and install braces for one piece lavatories at north wing boys and girls restrooms.							
Mario Martinez									
151277					4/13/2016		6		\$0.00
Medium	Work In Progress	Room 026			4/13/2016 8:19:06 AM				
Ambriz, Jose		Room is very hot, need to adjust AC temperature. (Mrs.Oblack)							
Norma Martinez									
151524					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 1:25:14 PM				
Ambriz, Jose		Need Jose A. to check on faulty A/C unit at room #26. Alarm showing 2 low coil temperture detect.							
Mario Martinez									
151508					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 8:43:11 AM				
Ronquillo, Ruben		Need 10 small windows replaced at NE double door entrance.							
Mario Martinez									
Count: 35 Work Orders			Avg. Age of WO's 53			Total for Riverside ES	0.5	\$12.50	

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: RTC - Alliance									
144375		Portables			12/4/2015		137		\$0.00
Medium	Work In Progress				12/4/2015 1:03:29 PM				
Moncayo, Fernando		need to replace an paint plank on office ramp area and secure nails in place Please call 882-6450 prior coming. We are gated now. Thank you							
Gloria Delgado									
141681		Classroom			10/14/2015		188		\$0.00
Medium	Work In Progress	Ms. Hirsch			10/14/2015 11:27:51				
Moncayo, Fernando		Ms. Hirsch's class air conditioner has given out. She has tried to reset and turn back but has not worked. It has been 30 min. and has not turned on. Please send someone ASAP Student in class are complaining Thank you							
Gloria Delgado									
148426					2/25/2016		54		\$0.00
Medium	Work In Progress				2/25/2016 10:49:10 AM				
Gonzalez, Salvador		need an old rim and metal post build to store our water hose for our Science class							
Gloria Delgado									
141364		Portables			10/9/2015		193		\$0.00
Medium	Work In Progress				10/9/2015 1:39:23 PM				
Gonzalez, Salvador		We have been donated by the Peak and iron grill and would like to place in the back by the office portable Thank you							
Gloria Delgado									
Count: 4 Work Orders		Avg. Age of WO's 143			Total for RTC - Alliance			0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		San Miguel ES							
150913		Athletic Field			4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 10:10:39 AM				
Ontiveros, Guadalupe		need to cut weeds with flail mower							
Alfredo Holguin									
Count: 1 Work Orders		Avg. Age of WO's		12	Total for San Miguel ES			0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa ES							
146825					1/27/2016		83		\$0.00
Medium	Work In Progress				1/27/2016 8:37:07 AM				
Ambriz, Juan		Need one surveillance sign.							
Juan Ambriz									
145863					1/8/2016		102		\$0.00
Medium	Work In Progress				1/8/2016 9:24:42 AM				
Ambriz, Juan		Need to replace tools							
Juan Ambriz									
148713	Main Building	Classroom			3/1/2016		49		\$0.00
Medium	Work In Progress	Room #108			3/1/2016 3:11:02 PM				
Ambriz, Juan		Need to replace sink faucet							
Juan Ambriz									
150722	Main Building	Exterior			4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 7:18:56 AM				
Ambriz, Juan		need to Install water hose and hangers between hallways							
Juan Ambriz									
147711	Main Building	Exterior			2/10/2016		69		\$0.00
Medium	Work In Progress	Front main			2/10/2016 10:52:18 AM				
Ambriz, Juan		Need to Install NO PARKING signs all across main street due to congestion at the end of the day due to new houses							
Juan Ambriz									
149659	Main Building	Exterior			3/15/2016		35		\$0.00
Medium	Work In Progress	rolling gates			3/15/2016 3:13:18 PM				
Ambriz, Juan		Need to replace bottom gate wheels							
Juan Ambriz									
151591	Main Building	Classroom			4/19/2016		0		\$0.00
Medium	Work In Progress				4/19/2016 9:29:22 AM				
Ambriz, Juan		Need to replace window blind in room 208							
Juan Ambriz									
151592	Main Building	Classroom			4/19/2016		0		\$0.00
Medium	Work In Progress	Room #305			4/19/2016 9:30:40 AM				
Ambriz, Juan		Need to replace window blinds in room #305							
Juan Ambriz									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa ES									
136192					7/21/2015		273		\$0.00
Medium	Work In Progress			7/21/2015 11:28:26 AM					
Gonzalez, Salvador	Attach ramps to portables.								
Albert Vallejo									
146521					1/21/2016		89		\$0.00
Medium	Work In Progress			1/21/2016 3:22:23 PM					
Moncayo, Fernando	3 COMPARTMENT SINK FACUETS LEAKING. SNP MANAGER MARINA R. 589.3439								
Maritza Gonzalez									
140238	Main Building	Classroom			9/18/2015		214		\$0.00
Medium	Work In Progress	Room 101		9/18/2015 3:01:26 PM					
Lara, Ralph	Please make 2 keys for room 101. One if for Ms. Linck and the other one is a backup key for school. Key								
Rita Mendez									
146042	Main Building	Exterior			1/12/2016		98		\$0.00
Medium	Work In Progress	outside wall of		1/12/2016 8:43:11 AM					
Castillo, Carlos	Need to replace lights								
Juan Ambriz									
148834					3/3/2016		47		\$0.00
Medium	Work In Progress			3/3/2016 8:01:52 AM					
Ambriz, Juan	Need to order tools								
Juan Ambriz									
151573		Classroom			4/18/2016		1		\$0.00
Medium	Work In Progress	Room # 106		4/18/2016 4:00:18 PM					
Ambriz, Jose	Need to repair water leak in room #106 from main 3" line								
Juan Ambriz									
151073					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress			4/10/2016 12:32:32 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
149567	Main Building	Kitchen			3/14/2016		36		\$0.00
Medium	Work In Progress			3/14/2016 12:31:23 PM					
Villalobos, David	Having problems with hot water								
Juan Ambriz									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

149663 Main Building Computer Lab 3/15/2016 35 \$0.00

Medium Work In Progress 2 computer labs 3/15/2016 3:24:28 PM

Lara, Ralph Need to Install cylinder locks to lock from inside

Juan Ambriz

148686 Main Building Portables 3/1/2016 49 \$0.00

Medium Work In Progress all portables 3/1/2016 8:43:40 AM

Lara, Ralph Need to Install peep holes on all portable doors

Juan Ambriz

151441 4/15/2016 4 \$0.00

Medium Work In Progress 4/15/2016 10:03:10 AM

Lara, Ralph Having problems with some locks on gates

Juan Ambriz

149569 Main Building Parking Lot 3/14/2016 36 \$0.00

Medium Work In Progress 3/14/2016 12:45:44 PM

Gonzalez, Salvador As per Ms. Tarin need to Install posts with chain in front of school

Juan Ambriz

148854 Main Building Computer Lab 3/3/2016 47 \$0.00

Medium Work In Progress 2 Computer labs 3/3/2016 12:40:20 PM

Marquez, Gerardo Need to Install locking door nobs for a safe lockdown

Juan Ambriz

140070 Main Building Parking Lot 9/16/2015 216 \$0.00

Medium Work In Progress Exterior lighting 9/16/2015 12:03:20 PM

Castillo, Carlos Need to replace some exterior lighting

Juan Ambriz

150249 3/31/2016 19 \$0.00

Medium Work In Progress 3/31/2016 12:46:06 AM

Ambriz, Juan Monthly - Santa Teresa ES-A-16 Fan Exhaust (SemiA) - Refer to PM schedule details.

Margret Villalobos

148983 3/6/2016 44 \$0.00

Medium Work In Progress 3/6/2016 12:40:39 AM

Ambriz, Juan Yearly - Santa Teresa ES A-10 HEAT PUMPS (ANNUAL) - Refer to PM schedule details.

Margret Villalobos

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
151050					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:15 AM				
Solis, Luis		Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.							
Margret Villalobos									
149572	Main Building	Exterior			3/14/2016		36		\$0.00
Medium	Work In Progress	back field			3/14/2016 1:28:24 PM				
Ambriz, Juan		Need to fertilize back field							
Juan Ambriz									
Count: 26 Work Orders			Avg. Age of WO's	62		Total for Santa Teresa ES	0		\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
147239					2/1/2016		78		\$0.00
Medium	Work In Progress				2/1/2016 4:13:12 PM				
Marquez, Gerardo		NEED TO GET A PRICE QUOTE FOR INSATALLATION OF A 6-0X7-0 DR TO NEW ENGINEERING RM.							
Gerardo Marquez									
145711					1/6/2016		104		\$0.00
Medium	Work In Progress				1/6/2016 2:06:46 PM				
Marquez, Gerardo		Please install a 6' door between rooms 700 and 702. Door should be situated at the south end of dividing wall. See admin for further instruction.							
Albert Vallejo									
148362	Main Building	Classroom			2/24/2016		55		\$0.00
Medium	Work In Progress	305			2/24/2016 3:22:00 PM				
Lara, Ralph		door hinge is broken							
Lorraine Dominguez									
137214	Library	Library			8/4/2015		259		\$0.00
Medium	Work In Progress	library			8/4/2015 2:28:04 PM				
Lara, Ralph		Emergencydoors not functioning							
Lorraine Dominguez									
136357	Main Building	Restroom			7/23/2015		271		\$0.00
Medium	Work In Progress	300 hallway			7/23/2015 2:41:30 PM				
Lara, Ralph		Bathroom stalls need replacing, door is missing on one of them and they are in bad shape							
Lorraine Dominguez									
135501	Library	Hallway/Corridor			7/6/2015		288		\$0.00
Medium	Work In Progress	200 Hall Student			7/6/2015 10:50:05 PM				
Lara, Ralph		Please replace all existing stall partitions with new black partitions due to heavy graffiti							
Nicholas Wohlgemuth									
145830					1/7/2016		103		\$0.00
Medium	Work In Progress				1/7/2016 3:55:49 PM				
Gonzalez, Salvador		Install window guards on 700-702							
Albert Vallejo									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
147482		Kitchen			2/5/2016		74		\$0.00
Medium	Work In Progress				2/5/2016 1:58:16 PM				
Moncayo, Fernando	Dishwasher machine leaking water								
Dino Facio									
148285					2/24/2016		55		\$0.00
Medium	Work In Progress				2/24/2016 8:35:22 AM				
Moncayo, Fernando	WASHING MACHINE IS LEAKING WATER WHILE MACHINE IS WORKING (URGNT TO AVOID AND ACCIDENT.)SNP MANAGER OLGA B.589.5332								
Maritza Gonzalez									
149301					3/9/2016		41		\$0.00
Medium	Work In Progress				3/9/2016 8:40:15 AM				
Moncayo, Fernando	The Environmental Health Division, was here yesterday 03/08/2016 and he found some violations and we need to fixed it as soon as possible. He need response by 3/29/2016 The works orders are the following; 3) The hose that we used to wash the dishwasher machine is not the appropriate for food service, we need to replace it. SNP Manager Olga B. 589.5332								
Maritza Gonzalez									
151005	Main Building	Classroom			4/8/2016		11		\$0.00
Medium	Work In Progress	various			4/8/2016 3:25:57 PM				
Hernandez, Carlos	Doors sweeps on exterior doors to include 801,803,807,805 All 700 classrooms. Exterior doors football hallway, 500 and 600 hallway.								
Lorraine Dominguez									
149553	Main Building	Classroom			3/14/2016		36		\$0.00
Medium	Work In Progress	401			3/14/2016 8:43:42 AM				
Hernandez, Carlos	Mr. Solis has some banners he would like for them to be hung up, please see him for further direction								
Lorraine Dominguez									
150983	Main Building	Classroom			4/8/2016		11		\$0.00
Medium	Work In Progress	Classroom and			4/8/2016 9:43:09 AM				
Hernandez, Carlos	Put up signs and banners in various areas around campus please see Mr. W for further direction								
Lorraine Dominguez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
151464	Main Building	Classroom			4/15/2016		4		\$0.00
Medium	Work In Progress	nurses station			4/15/2016 3:29:15 PM				
Hernandez, Carlos		need to replace light bulbs							
Lorraine Dominguez									
151407	Main Building	Classroom			4/14/2016		5		\$0.00
Medium	Work In Progress	601			4/14/2016 3:48:25 PM				
Hernandez, Carlos		Light bulbs need replacing							
Lorraine Dominguez									
150237		Office			3/30/2016		20		\$0.00
Medium	Work In Progress	OFFICE			3/30/2016 5:13:47 PM				
Hernandez, Carlos		ASSEMBLE 5 OFFICE CHAIRS AND MOUNT 2 DISPLAY CABINETS IN FRONT RECEPTIONIST OFFICE.							
Marylou Jimenez									
144126	Main Building	Storage			12/1/2015		140		\$0.00
Medium	Work In Progress	Equipment			12/1/2015 3:40:22 PM				
Hernandez, Carlos		Please replace light fixtures in storage areas soccer, track/football storage room all connected areas.							
Lorraine Dominguez									
149554	GYM (2009)	Gym			3/14/2016		36		\$0.00
Medium	Work In Progress	office			3/14/2016 8:44:46 AM				
Hernandez, Carlos		I have a banner that needs to be hung in the gym for soccer							
Lorraine Dominguez									
148340	Main Building	Classroom			2/24/2016		55		\$0.00
Medium	Work In Progress	603			2/24/2016 2:41:09 PM				
Hernandez, Carlos		Mount displayboards for art classrooms if possible							
Lorraine Dominguez									
148780	Main Building	Library			3/2/2016		48		\$0.00
Medium	Work In Progress	lobby area			3/2/2016 12:29:48 PM				
Hernandez, Carlos		lobby area ceiling needs to be repaired, as well as entry doors are in need of scraping and painting							
Lorraine Dominguez									
151457					4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 1:43:59 PM				
Hernandez, Carlos		need to replace light bulbs in kitchen							
Carlos Hernandez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

147479 2/5/2016 74 \$0.00

Medium Work In Progress 2/5/2016 1:39:26 PM

Hernandez, Carlos need air filters for units in café area

Carlos Hernandez

144169 Locker Room Dressing Room 12/2/2015 139 \$0.00

Medium Work In Progress 12/2/2015 8:19:35 AM

Miranda, Danny The wall directly behind the urinal is rotted out and needs to be replaced.

David Villalobos

148373 Vocational Classroom 2/24/2016 55 \$0.00

Medium Work In Progress 805 2/24/2016 3:35:26 PM

Diaz, David Light bulbs need replacing

Lorraine Dominguez

148702 Computer Lab 3/1/2016 49 \$0.00

Medium Work In Progress MRS. 3/1/2016 11:51:00 AM

Diaz, David MOUNT 4 X 6 BOARD IN COMPUTER LAB C-1.

Marylou Jimenez

148841 3/3/2016 47 \$0.00

Medium Work In Progress 3/3/2016 9:00:59 AM

Diaz, David Requesting to order tools:
Demolition Bar Item#2UV13 \$13.26
Westward 12ft. ladder Item#44YY30 \$290.00
Magliner Folding nose dolly Item#9CHW2 \$108.30

David Diaz

149160 GYM (2009) Gym 3/7/2016 43 \$0.00

Medium Work In Progress varsity gym 3/7/2016 3:18:50 PM

Diaz, David Hang sign in gym

Lorraine Dominguez

141562 Vocational Classroom 10/12/2015 190 \$0.00

Medium Work In Progress 805 10/12/2015 3:53:51 PM

Diaz, David In need of changing light bulbs

Lorraine Dominguez

141057 Classroom 10/5/2015 197 \$0.00

Medium Work In Progress MR. 10/5/2015 1:03:46 PM

Diaz, David LAB C-4 NEEDS BOARD MOUNTED.

Marylou Jimenez

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS									
136365	Main Building	Classroom			7/23/2015		271		\$0.00
Medium	Work In Progress	410			7/23/2015 2:57:12 PM				
Diaz, David Take down board and replace with bulletin board please see Ms. Soriano									
Lorraine Dominguez									
136366	Main Building	Classroom			7/23/2015		25		\$0.00
Medium	Work In Progress	500			7/23/2015 2:57:44 PM	8/17/2015			
Diaz, David Baseboard behind teacher desk needs replacing									
Lorraine Dominguez									
151183	Main Building	Restroom			4/12/2016		7		\$0.00
Medium	Work In Progress	400 Hallway			4/12/2016 10:21:50 AM				
Lara, Ralph Re-Keylock cylinder in 400 hallway restrooms so all staff can access using their classroom or office key.									
Nicholas Wohlgemuth									
150305	Main Building	Classroom			3/31/2016		19		\$0.00
Medium	Work In Progress	508/511 storage			3/31/2016 11:13:26 AM				
Lara, Ralph Need locking cabinets along one wall and built in shelving down middle of both storage rooms for proper and safe storage of chemicals and science equipment									
Rosalinda Rodriguez									
146984					1/29/2016		81		\$0.00
Medium	Work In Progress				1/29/2016 10:36:18 AM				
Lara, Ralph 1/29/16 Need to replace Complete steel doors and frames from the ROTC building. Doors are falling from hinges.									
David Diaz									
143494	GYM (2009)				11/12/2015		0		\$0.00
Medium	Work In Progress				11/12/2015 3:44:07 PM	11/12/2015			
Lara, Ralph DOORS NEED TO BE AJUSTED AND REPALED LACHES ON ALL DOORS AT GYM EXIT DOORS.									
Ralph Lara									
151174					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 8:31:39 AM				
Lara, Ralph door handle to concession stand broken needs to be replaced									
Carlos Hernandez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
151385					4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 2:55:13 PM				
Lara, Ralph		4/14/16							
		Need to make keys to electrical boxes in vocational rooms.							
David Diaz									
148146					2/22/2016		57		\$0.00
Medium	Work In Progress				2/22/2016 1:52:22 PM				
Villalobos, David		2/22/16							
		Need to replace union in water heater at custodial room in main hallway. Is leaking a lot of water shut down main water line leading into tank.							
David Diaz									
145988					1/11/2016		99		\$0.00
Medium	Work In Progress				1/11/2016 12:22:05 PM				
Villalobos, David									
		trouble resetting water heater in mechanical room							
Carlos Hernandez									
148364	Main Building	Classroom			2/24/2016		55		\$0.00
Medium	Work In Progress	610			2/24/2016 3:22:53 PM				
Villalobos, David									
		Dishwasher is leaking							
Lorraine Dominguez									
151455					4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 1:41:01 PM				
Villalobos, David									
		need to replace copper drain to sink in kitchen							
Carlos Hernandez									
142007					10/20/2015		182		\$0.00
Medium	Work In Progress				10/20/2015 1:27:58 PM				
Villalobos, David									
		Boys soccer locker room urinal needs to be replaced.							
Jaime Mijarez									
150655					4/4/2016		15		\$0.00
Medium	Work In Progress				4/4/2016 9:03:25 AM				
Castillo, Carlos									
		need to replace lights in varsity gym							
Carlos Hernandez									
136350	Main Building	Classroom			7/23/2015		271		\$0.00
Medium	Work In Progress	209			7/23/2015 2:34:10 PM				
Diaz, David									
		Please paint where tvstand was removed.							
Lorraine Dominguez									
4/19/2016 12:10:26 PM									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
136351	Main Building	Restroom			7/23/2015		271		\$0.00
Medium	Work In Progress	by library			7/23/2015 2:35:07 PM				
Diaz, David		Ceiling needs painting							
Lorraine Dominguez									
147186					2/1/2016		78		\$0.00
Medium	Work In Progress				2/1/2016 12:59:15 PM				
Castillo, Carlos		need to replace light fixtures in equipment room							
Carlos Hernandez									
149332	Main Building	Classroom			3/9/2016		41		\$0.00
Medium	Work In Progress	c-4,			3/9/2016 3:01:24 PM				
Castillo, Carlos		All classrooms have been installed a smart board and they need to get power to them for functioning purposes							
Lorraine Dominguez									
145712					1/6/2016		104		\$0.00
Medium	Work In Progress				1/6/2016 2:11:24 PM				
Castillo, Carlos		Please establish circuits for new computer lab at room 700 (directly next to pump room)							
Albert Vallejo									
149679					3/15/2016		35		\$0.00
Medium	Work In Progress				3/15/2016 3:47:23 PM				
Castillo, Carlos		need scissor lift to hang flags in gym							
Carlos Hernandez									
150988	Storage (Tennis)	Classroom			4/8/2016		11		\$0.00
Medium	Work In Progress	300			4/8/2016 11:36:12 AM				
Castillo, Carlos		Second request as per carpenter who will be here on 04/16/2016 three electrical outlets need to be lowered and one switch needs to be removed							
Lorraine Dominguez									
146848		Athletic Field			1/27/2016		83		\$0.00
Medium	Work In Progress				1/27/2016 2:33:21 PM				
Holguin, Alfredo		Football field Artificial Turf - Perform SportChamp deep cleaning service, Seam Repairs and add infill Rubber							
Alfredo Holguin									
151523					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 12:57:32 PM				
Carbajal, Jimmy		NEED GYM FLOORS TO BE REFINISHED (MAIN & AUX)							
Jimmy Carbajal									
4/19/2016 12:10:26 PM									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
151002	Main Building	Athletic Field			4/8/2016		11		\$0.00
Medium	Work In Progress	football stadium			4/8/2016 3:20:00 PM				
Vallejo, Albert Need sidewalk behind the football that was removed as well as a sidewalk to go from track to visitor bleacher area									
Lorraine Dominguez									
151004	Cafeteria (2005)	Cafeteria			4/8/2016		11		\$0.00
Medium	Work In Progress	sidewalk in			4/8/2016 3:23:37 PM				
Vallejo, Albert Sidewalk needs to be replaced in area where there was work done between 700 and cafeteria									
Lorraine Dominguez									
135788	Gymnasium	Classroom			7/13/2015		281		\$0.00
Medium	Work In Progress	weightroom			7/13/2015 2:34:55 PM				
Estrada, Jesus floor in weight room is lifting									
Lorraine Dominguez									
150978	Main Building	Athletic Field			4/8/2016		11		\$0.00
Medium	Work In Progress	football field			4/8/2016 8:58:56 AM				
Lara, Ralph Entry gate was driven through and is completely off hinges, doors are bent and need to be fixed.									
Lorraine Dominguez									
150743					4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 9:09:12 AM				
Holguin, Alfredo Remove and dispose outdated chemicals from Chemistry Class storage Rm. 511 - Contact; Ms. Alicia Stevens									
Alfredo Holguin									
145714					1/6/2016		104		\$0.00
Medium	Work In Progress	300			1/6/2016 2:16:17 PM				
Marquez, Gerardo Please contract to install work stations at film lab area where sinks will be removed. See Albert for further instruction.									
Albert Vallejo									
146671	Main Building	Cafeteria			1/25/2016		85		\$0.00
Medium	Work In Progress	Stage area			1/25/2016 2:06:33 PM				
Carbajal, Jimmy Theater curtain is torn and needs mending. As per Albert, assign to Jimmy C.									
Lorraine Dominguez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
144910		Athletic Field			12/11/2015		130		\$0.00
Medium	Work In Progress				12/11/2015 3:54:51 PM				
Ontiveros, Guadalupe		need fence put up around third base softball dugout using existing/recycled chain link and poles.							
Rick Llenez		To be done by Grounds Dept.							
141349	Locker Room	Hallway/Corridor			10/9/2015		193		\$0.00
Medium	Work In Progress				10/9/2015 8:50:43 AM				
Lara, Ralph		Fire Door Magnetic Door Holder mounted on the wall is lose it and looks damaged. It needs to be replaced if necessary and re-attached to the wall							
Alfredo Holguin									
150062					3/23/2016		27		\$0.00
Medium	Work In Progress				3/23/2016 3:27:53 PM				
Ambriz, Jose		a/c unit to lobby in varsity gym needs to be reconnected							
Carlos Hernandez									
141547	GYM (2009)	Athletic Field			10/12/2015		190		\$0.00
Medium	Work In Progress	Baseball			10/12/2015 3:46:32 PM				
Gonzalez, Salvador		Need for batting caged to be removed to replace with pitching mounds. Requesting two frames for two more batting cages.							
Lorraine Dominguez									
151527	GYM (2009)				4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 2:52:42 PM				
Carbajal, Jimmy		Gym floors will be available to get re-finished from july 18 to august 5							
Jimmy Carbajal									
149990					3/22/2016		28		\$0.00
Medium	Work In Progress				3/22/2016 9:42:57 AM				
,		I need to place a work order to the custodians to clean on the kitchen Week of March 21-23 2016. SNP Manager Olga B. 589-5332							
Maritza Gonzalez									
151199					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 12:44:42 PM				
Villalobos, Jose		wet n dry vac. #835 needs white rollers on squeegee and trouble with on off switch							
Jimmy Carbajal									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
151200					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 12:46:42 PM				
Villalobos, Jose		wet n dry vac. #2815 having problems with on off switch and needs hoses and hose clamp as well as hose cap							
Jimmy Carbajal									
151201					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 12:47:46 PM				
Villalobos, Jose		wet and dry vac. #279 needs new hoses and hose clamp							
Jimmy Carbajal									
151202					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 12:49:51 PM				
Villalobos, Jose		floor scrubbing mach. #1343 needs new wheels and handle adjustment							
Jimmy Carbajal									
151203					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 12:50:40 PM				
Villalobos, Jose		vacuum #045 need maintenance							
Jimmy Carbajal									
151204					4/12/2016		7		\$0.00
Medium	Work In Progress				4/12/2016 12:51:17 PM				
Villalobos, Jose		vacuum #005 needs maintenance							
Jimmy Carbajal									
151512		Parking Lot			4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 9:01:47 AM				
Castillo, Carlos		need to line locate. we will install irrigation drip line and new trees and flower beds in front main entrance. we will mark area. Any questions for exact area.							
Guadalupe Ontiveros									
151507					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 8:36:08 AM				
Gonzales, Camilo		Custodians at sth need 3 pair of size 9 rubber boots please							
Jimmy Carbajal									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
151347					4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 4:11:23 PM				
Villalobos, Jose		please issue 1 roto (floor scrubber) to sth with a 2gallon tank on handle							
Jimmy Carbajal									
151355					4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 7:39:34 AM				
Villalobos, Jose		adfinity auto scrubber #111634900 not scrubbing correct maybe not enough pressure on pad							
Jimmy Carbajal									
150536					4/3/2016	4/19/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:43 AM				
Villalobos, Margret		Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.				em 4/5/16			
Margret Villalobos									
150507					4/3/2016	4/24/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:21 AM				
Vallejo, Albert		Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
150580					4/3/2016	5/4/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:14 AM				
Diaz, David		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
148919	Main Building	Classroom			3/4/2016		46		\$0.00
Medium	Work In Progress	403			3/4/2016 10:31:09 AM				
Castillo, Carlos		Projector needs power for use of smart board							
Lorraine Dominguez									
150378	Main Building	Classroom			3/31/2016		19		\$0.00
Medium	Work In Progress	300			3/31/2016 4:10:00 PM				
Castillo, Carlos		Need electrical work to be done in computer lab within the 300 classroom due to remodeling of the area							
Lorraine Dominguez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
149728	Vocational	Classroom			3/16/2016		34		\$0.00
Medium	Work In Progress	801			3/16/2016 11:23:13 AM				
Castillo, Carlos		Outlets in classroom are loose and missing covers. There will also be a need for more outlets due to number of students increasing.							
Lorraine Dominguez									
151466	Vocational	Classroom			4/15/2016		4		\$0.00
Medium	Work In Progress	welding shop			4/15/2016 3:30:07 PM				
Castillo, Carlos		new machinery needs to have wiring installed							
Lorraine Dominguez									
148369	Vocational	Classroom			2/24/2016		55		\$0.00
Medium	Work In Progress	805			2/24/2016 3:26:54 PM				
Ontiveros, Guadalupe		Machines need to be moved from second level to first level. Will require machinery any questions, please contact David for further instruction.							
Lorraine Dominguez									
148202	Vocational	Classroom			2/23/2016		56		\$0.00
Medium	Work In Progress	805			2/23/2016 8:41:51 AM				
Lara, Ralph		Need keys for electric panel for student safety							
Lorraine Dominguez									
144362	Main Building	Classroom			12/4/2015		137		\$0.00
Medium	Work In Progress	nurses office			12/4/2015 11:14:14 AM				
Lara, Ralph		change door knob on door							
Lorraine Dominguez									
148367	Vocational	Classroom			2/24/2016		55		\$0.00
Medium	Work In Progress	805			2/24/2016 3:25:18 PM				
Lara, Ralph		Flammable cabinets need to be rekeyed to keep locked for safety							
Lorraine Dominguez									
151041					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:08 AM				
Lucero, Arnold		Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
150491					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:09 AM				
Diaz, David		Monthly - Santa Teresa HS Roof Inspection - Refer to PMschedule details.							
Margret Villalobos									
148565					2/29/2016	3/31/2016	50		\$0.00
Medium	Work In Progress				2/29/2016 12:58:15 AM				
Hernandez, Carlos		Yearly - Santa Teresa HS C-11 Evap Coolers Yearly - Refer to PMschedule details.							
Margret Villalobos									
150248					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:46:05 AM				
Hernandez, Carlos		Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PMschedule details.							
Margret Villalobos									
151037					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:05 AM				
Hernandez, Carlos		Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PMschedule details.							
Margret Villalobos									
143604					11/15/2015		156		\$0.00
Medium	Work In Progress				11/15/2015 12:27:55				
Flores, Pete		Yearly - Santa Teresa HS - Mower 0425 - Grounds - Refer to PMschedule details.							
Margret Villalobos									
151412	Main Building	Classroom			4/14/2016		5		\$0.00
Medium	Work In Progress	215			4/14/2016 3:50:09 PM				
Llanez, Rick		If a can crusher can be installed in patio on one of the pillar.							
Lorraine Dominguez									
150172	Main Building	Athletic Field			3/30/2016		20		\$0.00
Medium	Work In Progress	baseball			3/30/2016 9:15:58 AM				
Llanez, Rick		Dirt needs to be placed in back of baseball field							
Lorraine Dominguez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Santa Teresa HS									
145710					1/6/2016		104		\$0.00
Medium	Work In Progress				1/6/2016 2:01:27 PM				
Ontiveros, Guadalupe	Please establish xeriscaping and raised planters at entrance sidewalk between portables and barracks buildings								
Albert Vallejo									
147782					2/11/2016		68		\$0.00
Medium	Work In Progress				2/11/2016 8:26:41 AM				
Holguin, Alfredo	Running Track - Repair cracks in rubberized surface								
Alfredo Holguin									
Count: 96 Work Orders		Avg. Age of WO's 65		Total for Santa Teresa HS			0	\$0.00	

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa MS							
143603					11/15/2015		156		\$0.00
Medium	Work In Progress				11/15/2015 12:27:54				
Flores, Pete		Yearly - Santa Teresa MS - Mower 0416 - Grounds - Refer to PMschedule details.							
Margret Villalobos									
150587					4/3/2016	5/4/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:19 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
150588					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:19 AM				
Prospero, Manuel		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
150589					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:20 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
150590					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:21 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
150513					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:25 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Roof Inspection - Refer to PMschedule details.							
Margret Villalobos									
151049					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:14 AM				
Rodriguez, Ismael		Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PMschedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
145327					1/3/2016	2/3/2016	107		\$0.00
Medium	Work In Progress				1/3/2016 12:43:34 AM				
Prospero, Manuel		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
150635					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:54 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
150252					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:46:08 AM				
Prospero, Manuel		Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.							
Margret Villalobos									
148982					3/6/2016		44		\$0.00
Medium	Work In Progress				3/6/2016 12:40:38 AM				
Prospero, Manuel		Yearly - Santa Teresa MS A10 (Heat Pump)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
150465					4/3/2016	4/19/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:42:49 AM				
Prospero, Manuel		Monthly - Santa Teresa MS A1 (Wall Refr.E/H)(Semi) - Refer to PM schedule details.							
Margret Villalobos									
136401		Office			7/23/2015		271		\$0.00
Medium	Work In Progress				7/23/2015 4:17:14 PM				
Marquez, Gerardo		PLEASE GET A PRICE QUOTE FOR NEW STAFF MAILBOX AND BASE CABINETS FOR WORKRM.							
Gerardo Marquez									
141985	South Building				10/20/2015		182		\$0.00
Medium	Work In Progress				10/20/2015 8:06:34 AM				
Miranda, Danny		Security Office - cover two pocket doors in hallway leading to office- tape texture and paint							
Alfredo Holguin									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa MS							
146142	North Building	Custodial			1/13/2016		97		\$0.00
Medium	Work In Progress				1/13/2016 11:06:43 AM				
Flores, Pete		Pressure washer doesn't work need to be fix...							
Ismael Rodriguez									
150667	North Building	Custodial			4/4/2016		15		\$0.00
Medium	Work In Progress				4/4/2016 12:02:17 PM				
Villalobos, Jose		Gator not working need to be check .							
Ismael Rodriguez									
147955					2/16/2016		63		\$0.00
Medium	Work In Progress				2/16/2016 3:51:15 PM				
Gonzalez, Salvador		Construct batting cages (see Albert for drawings)							
Albert Vallejo									
151108	Gym (1997)	Roof			4/11/2016		8		\$0.00
Medium	Work In Progress				4/11/2016 1:10:09 PM				
Ambriz, Jose		4/11/16. WE NEED CHANGED BIG A/C 1500 ON GYM.. A/S NUM 1.							
Manuel Prospero									
151109	Gym (1997)	Roof			4/11/2016		8		\$0.00
Medium	Work In Progress				4/11/2016 1:13:05 PM				
Ambriz, Jose		WE NEED REPLACE BIG A/C 1500 ON GYM BAD CONDITION. A/C NUM2.							
Manuel Prospero									
151110	Gym (1997)	Roof			4/11/2016		8		\$0.00
Medium	Work In Progress				4/11/2016 1:14:39 PM				
Ambriz, Jose		NEED TO REPLACE A/C 1500 GYM AREA A/C NUM3.							
Manuel Prospero									
150986					4/8/2016		11		\$0.00
Medium	Work In Progress				4/8/2016 11:13:11 AM				
Ambriz, Jose		4/8/16. NO COMUNICATION ON BAND ROOM UNID PH 37.							
Manuel Prospero									
146077	South Building	Classroom			1/12/2016		98		\$0.00
Medium	Work In Progress				1/12/2016 3:35:17 PM				
Prospero, Manuel		1/12/16. HAVING PROBLEMS HEATER ROOM 31.							
Manuel Prospero									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
151449	North Building	Classroom			4/15/2016		4		\$0.00
Medium	Work In Progress	ADMIN		4/15/2016 11:31:59 AM					
Prospero, Manuel	EXHAUST FANS FOR BOTH WOMEN AND MEN RESTROOMS IN ADMIN AREA NEED TO BE REPAIRED OR REPLACED.								
Laura Parra									
151451	North Building	Classroom			4/15/2016		4		\$0.00
Medium	Work In Progress	ADMIN		4/15/2016 11:33:17 AM					
Prospero, Manuel	EXHAUST FANS FOR BOTH WOMEN AND MEN RESTROOMS IN THE ADMIN AREA NEED TO BE REPAIRED AND OR REPLACED.								
Laura Parra									
145200	South Building				12/17/2015		124		\$0.00
Medium	Work In Progress			12/17/2015 10:20:58					
Mijarez, Jaime	Room 31 - please check unit, unable to reset in Tracer.								
Albert Vallejo									
138255	Gym (1997)				8/18/2015		245		\$0.00
Medium	Work In Progress			8/18/2015 3:34:23 PM					
Vallejo, Albert	The scorers table on the bleachers need to be repaired or replaced								
Alfredo Holguin									
151287	Gym (1997)	Gym			4/13/2016		6		\$0.00
Medium	Work In Progress			4/13/2016 8:57:03 AM					
Carbajal, Jimmy	Resurface the gym floor on this date 7-18-16 thru 7-22-16..								
Ismael Rodriguez									
148333	North Building	Storage			2/24/2016		55		\$0.00
Medium	Work In Progress	UTVS		2/24/2016 2:12:50 PM					
Castillo, Carlos	1- NEED LIGHTS INSIDE THE STORAGE BLDG FOR THE UTVS WHEN WORKING AT NIGHT. 2- NEED OUTSIDE LIGHTS FOR THE 3 STORAGE BLDG FACING EASTSIDE OF THE STORAGE BUILDINGS. THE LIGHT IN PARKING LOT IS NOT SUFFICIENT.								
Laura Parra									
143316	South Building	Office			11/9/2015		162		\$0.00
Medium	Work In Progress	SOUTH OFFICE		11/9/2015 2:24:01 PM					
Prospero, Manuel	PAINT ALL TRIM INSIDE AND OUTSIDE OF OFFICES AND RESTROOMS-BLACK PAINT								
Laura Parra									
4/19/2016 12:10:26 PM									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
148712					3/1/2016		49		\$0.00
Medium	Work In Progress				3/1/2016 3:10:27 PM				
Castillo, Carlos		KITCHEN-DUE TO NEW DOOR INSTALLATION. TRIGGER SWITCH NEEDS TO BE REINSTALLED. SNP MANAGER GESSICA M. 589.9836							
Maritza Gonzalez									
147980	Gym (1997)	Gym			2/18/2016		61		\$0.00
Medium	Work In Progress	BEHIND GYM			2/18/2016 11:31:28 AM				
Castillo, Carlos		INSTALL TWO LARGE FLOOD LIGHTS TO LIGHT UP THE BACK OF WHAT IS AN EXTREMELY DARK AREA BEHIND THE GYM AND ATHLETIC FIELDS. INSTALL ON TWO CORNERS OF THE GYM FACING THE ATHLETIC FIELDS.							
Laura Parra									
150921	South Building	Parking Lot			4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 12:06:19 PM				
Castillo, Carlos		south bldg.Light pole not turning on.							
Carlos Castillo									
147979		Storage			2/18/2016		61		\$0.00
Medium	Work In Progress	SEE MR			2/18/2016 11:27:43 AM				
Castillo, Carlos		NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITCHING MACHINES NEXT TO THE TUFF SHED.							
Laura Parra									
148332	North Building	Office			2/24/2016		55		\$0.00
Medium	Work In Progress	MR			2/24/2016 2:08:50 PM				
Prospero, Manuel		ASSEMBLE 8 ADMINISTRATIVE CHAIRS							
Laura Parra									
151371	South Building	Custodial			4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 11:41:14 AM				
Lara, Ralph		The south back ramp door is not closing need to be check...							
Ismael Rodriguez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

145694 North Building Classroom 1/6/2016 104 \$0.00

Medium Work In Progress 9-CORDOVA 1/6/2016 9:48:23 AM

Lara, Ralph METAL FILING CABINET NEEDS TO BE RE-KEYED.
CABINET IS LOCKED

Laura Parra

138502 Restroom 8/21/2015 242 \$0.00

Medium Work In Progress 8/21/2015 1:34:48 PM

Lara, Ralph Please acquire quote for urinal partitions 18' for boys
restrooms.

Albert Vallejo

141506 10/12/2015 190 \$0.00

Medium Work In Progress 10/12/2015 2:28:22 PM

Orozco, Daniel HANDLE FOR HOT WATER ON DISHWASHER AREA
IS BROKEN. SNP MANAGER GESSICA M. 589.9836

Maritza Gonzalez

139307 North Building Office 9/3/2015 229 \$0.00

Medium Work In Progress ASST 9/3/2015 3:22:50 PM

Lara, Ralph OUTSIDE DOOR IN ASST PRINCIPALS OFFICE
DOES NOT WORK PROPERLY. HARD TO OPEN AND
CLOSE

Laura Parra

151520 Foyer 4/18/2016 1 \$0.00

Medium Work In Progress LOBBY- MR 4/18/2016 11:59:17 AM

Lara, Ralph HANDICAP BUTTON DOES NOT WORK. STUDENTS
WITH CRUTHCES HAVE DIFFICULTY ENTERING
THE BLDG.

Laura Parra

139979 9/15/2015 217 \$0.00

Medium Work In Progress 9/15/2015 12:50:46 PM

Lara, Ralph Install a door in security office hallway. As per
Administration, the office needs to secure confiscated
items. See security officer for details.

Albert Vallejo

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

141420 10/9/2015 193 \$0.00

Medium Work In Progress Kitchen 10/9/2015 4:13:39 PM

Lara, Ralph Dining room doors are being secured with chains and pad locks. Inspect and repair so that pad locks don't need to be used. As per ergonomic inspections an access route to this clear space must be maintained at all times. Please call Cynthia with any questions 882-6949

Cynthia Maes

141421 10/9/2015 193 \$0.00

Medium Work In Progress Outside Exit of 10/9/2015 4:17:37 PM

Vallejo, Albert Repair pavement from kitchen door to dumpsters. Per ergonomic inspections pavement repairs should be made to provide a smooth transition from the asphalt to the concrete.

Cynthia Maes

147978 South Building Storage 2/18/2016 61 \$0.00

Medium Work In Progress SEE MR 2/18/2016 11:23:47 AM

Vallejo, Albert AT THE SAME LOCATION WHERE TUFF SHED HAS BEEN PLACED, FENCE NEEDS TO BE CUT AND GATE INSTALLED. TUFF SHED IS PLACED ON THE FLUSH NEXT TO THE FENCE AND ON THE BASE SCREENING. INSTALL A 5' FOOT FENCE ALL AROUND TUFF SHED WITH FRONT GATE TO GAIN ACCESS.

Laura Parra

146083 1/12/2016 98 \$0.00

Medium Work In Progress 1/12/2016 3:41:57 PM

Prospero, Manuel 1/12/16.
.5HR CHECK E MAIL.
2HRS CHEKING HEATERS CAFETERIA.
2HRS TROUBLE SOOTER HEATERS PORTABLE 2 AND NURCES OFFICE.
3HRS WO 146077.
.5HR ENTER LOG.

Manuel Prospero

141509 10/12/2015 190 \$0.00

Medium Work In Progress 10/12/2015 2:34:34 PM

Prospero, Manuel AS PER ADEL'S MONITORING REPORT. DENTS ON WALK IN HALL AND BATHROOM WALLS.

Maritza Gonzalez

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
150898	South Building	Restroom			4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 8:26:10 AM				
Prospero, Manuel		Replace foam soap dispenser in south office boys restroom thanks..							
Ismael Rodriguez									
150912	South Building	Restroom			4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 10:04:07 AM				
Prospero, Manuel		Need a new paper towel dispenser in south office boys restroom check with frank..							
Ismael Rodriguez									
Count: 48 Work Orders			Avg. Age of WO's 79		Total for Santa Teresa MS			0	\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunland Park ES							
141417	Main Building				10/9/2015		193		\$0.00
Medium	Work In Progress				10/9/2015 4:04:12 PM				
Ontiveros, Guadalupe		Front Entrance - Purchase and replace 1 missing palm tree.							
Alfredo Holguin									
150819					4/6/2016		13		\$0.00
Medium	Work In Progress				4/6/2016 8:27:44 AM				
Ontiveros, Guadalupe		Attn: Lupe Ontiveros I have several sprinklers at soccer field that are not working or are broken. Can you please help me replace them so that I can learn and also show me the ropes on scheduling the cutting of grasses and watering.							
Jaime Mijarez									
151509					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 8:52:11 AM				
Vasquez, Jose		Timer #2/Zone #14 water line is broken. Joe has uncovered line and is getting materials to repair.							
Jaime Mijarez									
150488					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:07 AM				
Mijarez, Jaime		Monthly - Sunland Park ES Roof Inspection - Refer to PMschedule details.							
Margret Villalobos									
151051					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:15 AM				
Lucero, Jesus		Monthly - QRTLTY BDLG INSP REPORT (SP) - Refer to PMschedule details.							
Margret Villalobos									
145325					1/3/2016	2/3/2016	107		\$0.00
Medium	Work In Progress				1/3/2016 12:43:32 AM				
Mijarez, Jaime		Yearly - Sunland Park ES Backflow Inspection - Refer to PMschedule details.							
Margret Villalobos									
148997					3/6/2016	3/22/2016	44		\$0.00
Medium	Work In Progress				3/6/2016 12:40:50 AM				
Mijarez, Jaime		Monthly - Sunland Park ES A-1 Wall Ref Semiannual - Refer to PMschedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunland Park ES							
148984					3/6/2016		44		\$0.00
Medium	Work In Progress				3/6/2016 12:40:40 AM				
Mijarez, Jaime		Yearly - Sunland Park ES A-10 HP Rooftop Yearly - Refer to PM schedule details.							
Margret Villalobos									
148563					2/29/2016	3/31/2016	50		\$0.00
Medium	Work In Progress				2/29/2016 12:58:13 AM				
Mijarez, Jaime		Yearly - Sunland Park ES C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
148585					2/29/2016		50		\$0.00
Medium	Work In Progress				2/29/2016 12:58:30 AM				
Mijarez, Jaime		Monthly - Sunland Park ES A-16 Fan Exh Semiannual - Refer to PM schedule details.							
Margret Villalobos									
151064					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:25 AM				
Mijarez, Jaime		Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
149532					3/13/2016	3/29/2016	37		\$0.00
Medium	Work In Progress				3/13/2016 12:32:07 AM				
Mijarez, Jaime		Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
150622					4/3/2016	4/9/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:44 AM				
Mijarez, Jaime		Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
149108					3/6/2016	3/12/2016	44		\$0.00
Medium	Work In Progress				3/6/2016 12:42:09 AM				
Mijarez, Jaime		Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Sunland Park ES									
150571					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress			4/3/2016 12:44:08 AM					
Mijarez, Jaime	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
150572					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress			4/3/2016 12:44:08 AM					
Mijarez, Jaime	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
148039	Main Building	Custodial			2/19/2016		60		\$0.00
Medium	Work In Progress			2/19/2016 10:28:35 AM					
Carbajal, Jimmy	burnisher after returning from being fixed is not functioning like it was prior to it breaking down. if we can please check it out thanks								
Jesus Lucero									
150826					4/6/2016		13		\$0.00
Medium	Work In Progress			4/6/2016 9:38:08 AM					
Flores, Pete	Maintenance truck. I would like to have the truck replaced permanently with a better running truck and with out any tool boxes. This truck is lacking horse power and I don't need the tool boxes, they limit the space when i have to carry big items. I am having to drag a piece of half pipe around the campus to cut weeds since the tractor is not always available. 4x4 would be great.								
Jaime Mijarez									
149556					3/14/2016		36		\$0.00
Medium	Work In Progress			3/14/2016 8:51:12 AM					
Mijarez, Jaime	Attn: Danny and Ruben I will be painting the hallways in the summer. Please order 50 gallons of Q37-36p vanilla bean paint								
Jaime Mijarez									
146926					1/28/2016		82		\$0.00
Medium	Work In Progress			1/28/2016 2:55:42 PM					
Ambriz, Jose	Install covers on O/A temp sensors that control on and off to both boilers booster pumps for heating.								
Jaime Mijarez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunland Park ES							
148041					2/19/2016		60		\$0.00
Medium	Work In Progress				2/19/2016 10:52:26 AM				
Vallejo, Albert		Create new opening for entry to office							
Albert Vallejo									
141920	Main Building	Parking Lot			10/19/2015		183		\$0.00
Medium	Work In Progress				10/19/2015 11:06:16				
Mijarez, Jaime		South Side of Building/ Back Entries - cut and remove weeds.				Route to Jaime on 11/16/15			
Alfredo Holguin									
151177					4/12/2016		7		\$0.00
Medium	Work In Progress	41			4/12/2016 9:16:58 AM				
Ambriz, Jose		RM#41- CASTANEDA- AIR NOT WORKING ROOM GETS REALLY HOT							
Maribel Gamboa									
151179					4/12/2016		7		\$0.00
Medium	Work In Progress	29			4/12/2016 9:21:24 AM				
Ambriz, Jose		RM#29-RESENDIZ- ROOM IS HOT							
Maribel Gamboa									
150985					4/8/2016		11		\$0.00
Medium	Work In Progress	LIBRARY			4/8/2016 11:02:40 AM				
Castillo, Carlos		LIBRARY- CARLOS ITS ABOUT THE LIGHTS IN THE LIBRARY IF YOU CAN COME AND CHECK ON IT I WOULD GREATLY APPRECIATE IT. THANK YOU				4/12/16 - Asp Gallegos, not under warranty			
Maribel Gamboa									
148783					3/2/2016		48		\$0.00
Medium	Work In Progress	LIBRARY			3/2/2016 2:57:31 PM				
Mijarez, Jaime		LIBRARY- MORENO- NEED TO HAVE ELECTRICIAN COME AND TAKE A LOOK AT THE NEW CEILING LIGHTS THEY ARE NO LONGER TURNING ON WHEN SWITCH IS FIRST USED. THIS IS THE THIRD NOTICE FOR THIS INCIDENCE. THANK YOU							
Maribel Gamboa									
143762		Library			11/18/2015		153		\$0.00
Medium	Work In Progress	LIBRARY			11/18/2015 8:22:59 AM				
Mijarez, Jaime		LIBRARY- MORENO- NEED DOORS PAINTED BLUE SEE MRS. MORENO							
Maribel Gamboa									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
143763		Library			11/18/2015		153		\$0.00
Medium	Work In Progress	LIBRARY			11/18/2015 8:25:55 AM				
Mijarez, Jaime		LIBRARY- MORENO- NEED TO HAVE PAINTING FINISHED IN LIBRARY WALLS. LIGHT ARE STILL NOT TURNING ON COMPLETELY							
Maribel Gamboa									
138311					8/19/2015		244		\$0.00
Medium	Work In Progress	25			8/19/2015 10:16:35 AM				
Mijarez, Jaime		RM#25 M.HOLGUIN- PLEASE PAINT THE DOES IN THE CLASSROOM-2ND NOTICE				Route to Jaime on 11/16/15			
Maribel Gamboa									
144739					12/9/2015		132		\$0.00
Medium	Work In Progress				12/9/2015 3:19:12 PM				
Mijarez, Jaime		Paint portable interior walls with Vanilla Bean paint. I need 5 gallons.							
Jaime Mijarez									
151215					4/12/2016		7		\$0.00
Medium	Work In Progress	bathroom in the			4/12/2016 3:30:01 PM				
Villalobos, David		ADULT BATHROOM IN THE HALLWAY- THE WATER KNOB DO NOT FLOW WORK PROPERLY YOU MUST HOLD WITH ONE HAD TO GET THE WATER RUNNING							
Maribel Gamboa									
150746					4/5/2016		14		\$0.00
Medium	Work In Progress				4/5/2016 9:39:03 AM				
Ontiveros, Guadalupe		Attn: Lupe Ontiveros. I have a broken water line leak on timer #2 section. Carlos Hernandez had turned off water at back flow. I opened the water backup to locate leak and shut it back up.							
Jaime Mijarez									
148911					3/4/2016		46		\$0.00
Medium	Work In Progress				3/4/2016 12:07:21 AM				
Marquez, Gerardo		PLEASE CHECK IF ITS POSSIBLE TO MOVE COUNTER IN MAIN OFFICE.							
Gerardo Marquez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
151579	Main Building	Custodial			4/19/2016		0		\$0.00
Medium	Work In Progress				4/19/2016 7:35:11 AM				
Lara, Ralph		The door to the office is not opening this would be to custodial office if you could please help us out with that thanks.							
Jesus Lucero									
141950					10/19/2015		183		\$0.00
Medium	Work In Progress				10/19/2015 3:36:43 PM				
Ronquillo, Ruben		missing one platform and one cracked.(hazard had talked to mr ronquillo was going to send someone no one has showed up)							
Carlos Hernandez									
136740					7/30/2015		264		\$0.00
Medium	Work In Progress				7/30/2015 11:23:17 AM				
Ronquillo, Ruben		need platforms for bridge broken(hazard)							
Carlos Hernandez									
143765		Library			11/18/2015		153		\$0.00
Medium	Work In Progress	LIBRARY			11/18/2015 8:36:45 AM				
Mijarez, Jaime		LIBRARY- MORENO- NEEDS TO HAVE WALL FILE HOLDERS INSTALLED SEE MRS. MORENO							
Maribel Gamboa									
145703		Classroom			1/6/2016		104		\$0.00
Medium	Work In Progress	21			1/6/2016 11:46:56 AM				
Mijarez, Jaime		RM#21- CLAUDIA PEREZ- 1) UTILITY SHLVE ON TOP OF WASHER AND DRY. 2) PAINT AROUND HITACHI BOARD 3) NAILS ON WALL FOR BULLETIN BOARD 4) 1 LONG TABLE FOR COMPUTERS 5) TEACHER DESK							
Maribel Gamboa									
148784					3/2/2016		48		\$0.00
Medium	Work In Progress	LIBRARY			3/2/2016 3:01:00 PM				
Mijarez, Jaime		LIBRARY- MORENO - NEED TO HAVE LIBRARY TABLES TIGHTENED. THE LEGS ON THE TALBLES HAVE BECOME VERY LOOSE AND ARE STARTING TO BECOME A HAZARD. SECOND NOTICE							
Maribel Gamboa									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
149405					3/10/2016		40		\$0.00
Medium	Work In Progress	39			3/10/2016 2:52:57 PM				
Mijarez, Jaime		RM#39- ARMENDARIZ- PENCIL SHARPNER DOES NOT WORK							
Maribel Gamboa									
150914		Office			4/7/2016		12		\$0.00
Medium	Work In Progress				4/7/2016 10:16:57 AM				
Mijarez, Jaime		OFFICE - NEW FURNITURE WILL NEED TO BE PUT TOGETHER AND PUT IN PRINCIPAL OFFICE AND HER OLD FURNITURE NEEDS TO GO INTO IN MRS. DUQUES OFFICE.							
Maribel Gamboa									
146362		Classroom			1/19/2016		91		\$0.00
Medium	Work In Progress	21			1/19/2016 12:53:31 PM				
Mijarez, Jaime		RM#21 - PEREZ- EXTENTION CORD FOR COMPUTER. PAINT AROUND WHITEBOARD. NAILS TO HANG WHITEBOARD. SHELVES IN LANDRY ROOM FOR STORAGE.							
Maribel Gamboa									
144112		Classroom			12/1/2015		140		\$0.00
Medium	Work In Progress	24			12/1/2015 3:15:00 PM				
Mijarez, Jaime		RM#24-MARRUFO- CAN YOU PLEASE PUT NAILS ONTHE PILASTERS IN THE HALLWAYS IN ORDER TO HANG FARMED ARTWORK PLEASE COME AND SEE ME AT MY ROOM							
Maribel Gamboa									
137110		Classroom			8/3/2015		260		\$0.00
Medium	Work In Progress	25			8/3/2015 3:04:41 PM				
Mijarez, Jaime		RM#25- GARCIA- PLEASE PAINT CLASSROOM DOORS				Route to Jaime on 11/16/15			
Maribel Gamboa									
151180		Library			4/12/2016		7		\$0.00
Medium	Work In Progress	LIBRARY			4/12/2016 9:39:37 AM				
Mijarez, Jaime		LIBRARY - MORENO- NEED TO HAVE LIBRARY TABLE TIGHTENED THEY HAVE BECOME COMPLETELY LOOSE EVEN THE NUTS AND BOLTS ARE COMING OUT. THIRD NOTICE							
Maribel Gamboa									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
145195					12/17/2015		124		\$0.00
Medium	Work In Progress	21			12/17/2015 8:46:35 AM				
Mijarez, Jaime		RM#21 - PEREZ - WANTS TO PUT NAILS ON THE WALL AND WANT 6 MORE CHAIRS FOR THE CLASSROOM							
Maribel Gamboa									
141381					10/9/2015		193	0.5	\$12.50
Medium	Work In Progress				10/9/2015 3:31:47 PM				
Mijarez, Jaime		floor tile in bathroom need to be replaced in room 38				1/25/15 - route to building mechanic as per Jimmy, the tile is still there just a couple came unglued			
Jimmy Carbajal									
146909					1/28/2016		82		\$0.00
Medium	Work In Progress				1/28/2016 11:39:21 AM				
Mijarez, Jaime		LIBRARY- MORENO- NEED TO HAVE LIBRARY TABLES LEGS TIGHTEN. Table have become very woobly.							
Maribel Gamboa									
146581					1/22/2016		88		\$0.00
Medium	Work In Progress	21			1/22/2016 9:43:54 AM				
Mijarez, Jaime		RM#21 - PEREZ- NEED A TEACHERS DESK PLEASE							
Maribel Gamboa									
144786		Cafeteria			12/10/2015		131		\$0.00
Medium	Work In Progress				12/10/2015 7:36:06 AM				
Moncayo, Fernando		NO HOT WATER IN KITCHEN - SNP MGR IGNACIA 589-2545							
Jacqueline Aguilar									
145614	Main Building				1/5/2016		105		\$0.00
Medium	Work In Progress				1/5/2016 10:11:45 AM				
Mijarez, Jaime		Jaime, EC playground is full of stickers please remove so that it can be ready when students can go out to play. Front of building is full of sand and paper that is stuck against the front chain link fence.							
Rosa Kahoe									
151439					4/15/2016		4		\$0.00
Medium	Work In Progress				4/15/2016 8:14:07 AM				
Castillo, Carlos		We need the scissor lift to repair cable on one of the flag poles.							
Jaime Mijarez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Sunland Park ES									
148226					2/23/2016		56		\$0.00
Medium	Work In Progress				2/23/2016 2:43:24 PM				
Ontiveros, Guadalupe	I am going to need the Bobcat with the brush so I can sweep the walkways around the school.								
Jaime Mijarez									
150974					4/8/2016		11		\$0.00
Medium	Work In Progress				4/8/2016 8:15:10 AM				
Gonzales, Camilo	Pick up unused furniture and pick up earlychildhood furniture to relocate to other school campuses.								
Jaime Mijarez									
141871					10/16/2015		186		\$0.00
Medium	Work In Progress				10/16/2015 3:39:05 PM				
Flores, Pete	tractor 970 4x4 dont work(worked before they took it to get repaired)								
Carlos Hernandez									
151533	Main Building	Exterior			4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 3:05:28 PM				
Herrera, Marin	Would like 5 gallons for pressure washer and one gallon for blower mix along with one container of 2cycle for blower mix								
Jesus Lucero									
Count: 56 Work Orders		Avg. Age of WO's 75			Total for Sunland Park ES			0.5	\$12.50

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location:		Sunrise ES							
150556					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:57 AM				
Vargas, Juan	Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
150557					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:58 AM				
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
150558					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:58 AM				
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
150499					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:43:15 AM				
Vargas, Juan	Monthly - Sunrise ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
150250					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 12:46:06 AM				
Vargas, Juan	Monthly - Sunrise ES A16 (Fan Exh.)(S. Annual) - Refer to PM schedule details.								
Margret Villalobos									
151059					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:22 AM				
Gallegos, Felipe	Monthly - QRTLY BLDG INSP REPORT (SR) - Refer to PM schedule details.								
Margret Villalobos									
151074					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:33 AM				
Vargas, Juan	Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
150611					4/3/2016		16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:36 AM				
Apodaca, Mario Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.									
Margret Villalobos									
151276	Main Building				4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 8:17:15 AM				
Villalobos, Jose Royal upright vacuum cleaner SER# 20002145. Handle fork release pedal broke off. Need new bag. Electrical plug has a short, will not start unless you wiggle it.									
Felipe Gallegos									
151274	Main Building				4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 8:15:51 AM				
Villalobos, Jose Handle fork release pedal broke off. Need new bag. Electrical plug has a short, will not start unless you wiggle it.									
Felipe Gallegos									
149992					3/22/2016		28		\$0.00
Medium	Work In Progress				3/22/2016 10:19:08 AM				
Vargas, Juan replace all a/c unites filters									
Juan Vargas									
151311					4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 3:22:14 PM				
Solis, Lorenz NEED CHECK A/C UNITE A . IN LIBRATY									
Juan Vargas									
151539					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 3:29:20 PM				
Solis, Lorenz NEED HELP TO FIX CAFETERIA A/C MAKE UPER									
Juan Vargas									
148363					2/24/2016		55		\$0.00
Medium	Work In Progress				2/24/2016 3:22:26 PM				
Solis, Lorenz a/c unite in kitchen area need replace cooler section									
Juan Vargas									
147323	Main Building	Library			2/3/2016		76		\$0.00
Medium	Work In Progress				2/3/2016 10:12:50 AM				
Chavez, Santos Need to replace lenses on several 4 x2 light fixtures									
Santos Chavez									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
150392					4/1/2016		18		\$0.00
Medium	Work In Progress				4/1/2016 8:48:12 AM				
Vargas, Juan		need put buses sing in north side gate							
Juan Vargas									
150843					4/6/2016		13		\$0.00
Medium	Work In Progress				4/6/2016 3:12:07 PM				
Appelzoller, Fred		toilet grls rest room in 300 wing need fix							
Juan Vargas									
151302					4/13/2016		6		\$0.00
Medium	Work In Progress				4/13/2016 1:40:48 PM				
Gonzalez, Salvador		NEED WELDING IN NORTH SIDE PLAY GROUND DINOSAURIOS							
Juan Vargas									
Count: 18 Work Orders			Avg. Age of WO's	18		Total for Sunrise ES	0		\$0.00

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Vado ES							
148833					3/3/2016		47		\$0.00
Medium	Work In Progress				3/3/2016 7:59:28 AM				
Flores, Pete		need bobcat to clean all ponds							
Danny Miranda									
150823					4/6/2016		13		\$0.00
Medium	Work In Progress				4/6/2016 9:07:30 AM				
Flores, Pete		need to ck truck #153 belt tension pulley damaged							
Danny Miranda									
150301					3/31/2016		19		\$0.00
Medium	Work In Progress				3/31/2016 10:40:49 AM				
Miranda, Danny		need 1/2" wood screws philips head total 200							
Danny Miranda									
151521					4/18/2016		1		\$0.00
Medium	Work In Progress				4/18/2016 12:39:20 PM				
Miranda, Danny		need to replace air filters to a/c units							
Danny Miranda									
150825					4/6/2016		13		\$0.00
Medium	Work In Progress				4/6/2016 9:22:14 AM				
Appelzoller, Fred		need to replace lav's in 200-wing boys r.r. and one in boys r.r. going out to bus area							
Danny Miranda									
150045					3/23/2016		27		\$0.00
Medium	Work In Progress				3/23/2016 8:40:54 AM				
Appelzoller, Fred		NEED TO REPLACE FAUCET IN ROOM 304							
Danny Miranda									
143363					11/10/2015		161		\$0.00
Medium	Work In Progress				11/10/2015 7:56:40 AM				
Appelzoller, Fred		need to replace booster pump in 100-wing boiler room							
Danny Miranda									
146973					1/29/2016		81		\$0.00
Medium	Work In Progress				1/29/2016 8:25:37 AM				
Chavez, Santos		need a 115 outlet in room 105 to be able to plug in smart board on south side wall							
Danny Miranda									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
150673					4/4/2016		15		\$0.00
Medium	Work In Progress				4/4/2016 3:13:14 PM				
Ontiveros, Guadalupe		need help with grass alfalfa is taking over need something to kill alfalfa and something to help grass grow							
Danny Miranda									
149245					3/8/2016		42		\$0.00
Medium	Work In Progress				3/8/2016 2:22:33 PM				
Marquez, Gerardo		need to re key double doors by office to open with all teachers keys							
Danny Miranda									
144866					12/11/2015		130		\$0.00
Medium	Work In Progress				12/11/2015 10:31:24				
Chavez, Santos		need to replace emer. ballast in rooms 103,107,208,303, and teachers lounge							
Danny Miranda									
148053					2/19/2016		60		\$0.00
Medium	Work In Progress				2/19/2016 1:37:55 PM				
Chavez, Santos		principal is requesting a new outlet or heavy duty extension cord for projector in comp. rm. #2							
Danny Miranda									
150411					4/1/2016		18		\$0.00
Medium	Work In Progress				4/1/2016 2:56:18 PM				
Solis, Lorenzo		need to ck. unit in room (#300/parent room)parent room is fresh but room 300 is very hot they will start testing on Monday							
Danny Miranda									
150299	Main Building	Parking Lot			3/31/2016		19		\$0.00
Medium	Work In Progress	Front of the			3/31/2016 10:29:01 AM				
Vallejo, Albert		Paint all lines in parking lot, drop off/pick up area. Paint the front. Paint the front doors of the lobby and cafeteria. Paint the blue poles that are located in the front of the school							
Sylvia Cary									
149482					3/11/2016		39		\$0.00
Medium	Work In Progress				3/11/2016 2:32:25 PM				
Vallejo, Albert		Create drainage for playground area.							
Albert Vallejo									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Vado ES							
151368					4/14/2016		5		\$0.00
Medium	Work In Progress				4/14/2016 9:56:04 AM				
Vallejo, Albert		Build enclosed area for trash dumpsters							
Alfredo Holguin									
150106	Main Building	Custodial			3/29/2016		21		\$0.00
Medium	Work In Progress				3/29/2016 10:49:09 AM				
Carbajal, Jimmy		Need to replace 3 old vacuum cleaner's with 3 new one's the one's are date 8-5-11 are not working . Thank u !							
Armando Diaz									
148681		Custodial			3/1/2016		49		\$0.00
Medium	Work In Progress				3/1/2016 7:55:18 AM				
Carbajal, Jimmy		Requesting to trade old extractor for a new one . Thank you !							
Armando Diaz									
151066					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:27 AM				
Miranda, Danny		Monthly - Vado ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
150577					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:12 AM				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
150578					4/3/2016	4/11/2016	16		\$0.00
Medium	Work In Progress				4/3/2016 12:44:12 AM				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
151042					4/10/2016	4/26/2016	9		\$0.00
Medium	Work In Progress				4/10/2016 12:32:09 AM				
Diaz, Armando		Monthly - QRTLTY BLDG INSP REPORT (VE) - Refer to PM schedule details.							
Margret Villalobos									

1085 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2015 - 6/30/2016 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Vado ES							
148992					3/6/2016	4/6/2016	44		\$0.00
Medium	Work In Progress				3/6/2016 12:40:46 AM				
Miranda, Danny		Yearly - Vado ES R-3 Ref. Unit Yearly - Refer to PM schedule details.							
Margret Villalobos									

148414					2/25/2016		54		\$0.00
Medium	Work In Progress				2/25/2016 7:46:10 AM				
Ontiveros, Guadalupe		need 30 bags of weed and feed for vado elem.							
Danny Miranda									

Count: 24 Work Orders		Avg. Age of WO's	38			Total for Vado ES	0	\$0.00	
Count: 1085 Work Orders		Avg. Age of WO's	62			Grand Total	6	\$245.93	